



Form 125-22  
Supercedes  
Form 125-21

# 2022

## TRUCKS & BUSES





# FAST FACTS


## YOUR SINGLE SOURCE FOR QUALITY FILTRATION BROADEST COVERAGE IN THE INDUSTRY

As leaders in the industry, Baldwin has a reputation for protecting heavy-duty engines in a wide range of markets and applications. From the big city to the remote countryside and everywhere in between, Baldwin provides protection you can rely on no matter where you're headed.


### FILTRATION EXPERTISE

**FOUNDED 1936** Baldwin's longevity has resulted in a sophisticated level of understanding across a broad range of industries.


### TOUGH HEAVY-DUTY

-  **ON-HIGHWAY**  
Class 4-8 Trucks


---

-  **CONSTRUCTION**  
Backhoes, Loaders, Excavators


---

-  **OIL & GAS**  
Generators, Industrial Engines, Trucks


---


-  **MINING**  
Earth Movers, Excavators, Haul Trucks

---

-  **AGRICULTURE**  
Tractors, Loaders, Combines


---

-  **MARINE**  
Tug Boats, Generators




**NORTH AMERICAN CLASS 4-8 MARKET SHARE**


### PREMIUM LIGHT-DUTY

-  **DIESEL PICKUPS**


---

-  **GAS PICKUPS**


---


-  **SUVS**

---

-  **LAW ENFORCEMENT VEHICLES**

---

-  **COMMERCIAL VEHICLES**



**80+ YEARS**

### UNSURPASSED PERFORMANCE

- Products designed to fully meet or exceed application requirements
- Efficiency to protect the most advanced modern engines
- Capacity to meet OE recommended service intervals
- Products tested over and beyond industry standards

### KNOWLEDGEABLE SERVICE

Largest, most experienced field and inside technical support team



### RELIABLE QUALITY

- Vertical integration for world-class quality exceeding 6 Sigma
- Application specific filter design and unique, proprietary media development
- Complete process control, vertical integration from media development through component production and final assembly
- Cutting edge innovation center and on-site test labs to validate high performance

**45000+**  
CASES SHIPPED PER DAY

**7500+**  
OE QUALITY PARTS

**150+**  
BRAND PARTNERSHIPS

### MORE COVERAGE

BALDWIN VS. COMPETITOR A

**68%**

**46%**

BALDWIN VS. COMPETITOR B

**77%**

**54%**

BALDWIN VS. COMPETITOR C


**84%**

**68%**

BALDWIN VS. COMPETITOR D

**82%**

**46%**



**95%** TOP 200 SALES  
MADE IN THE USA

**AIR | FUEL | LUBE | HYDRAULIC | COOLANT | TRANSMISSION | EMISSIONS**

[baldwinfilters.com](http://baldwinfilters.com)

Table of Contents .....	1
Form 123-22, Form 124-22, Form 560-22, Form 561-21 and Form 562-22 List of Contents .....	2
Baldwin New Products .....	3-4
Baldwin Obsolete Products.....	5-14
Abbreviations Used Anywhere in Our Catalogs .....	15-23
Preixes and Su ixes.....	24-32
Notes .....	33

# TABLE OF CONTENTS

## Trucks & Buses Applications

<b>TRUCKS AND BUSES APPLICATIONS .....</b>	<b>34-1041</b>
How Truck Applications are Arranged.....	34-42
Trucks and Buses Applications .....	43-1041
Notes .....	1042
Date Coding .....	1043-1048
Baldwin Warranty .....	1049-1052
Product Investigation .....	1053
Field Report Form .....	1054
Filter Survey.....	1055-1056

# Form 123-22, Form 124-22, Form 560-22, Form 561-21 & Form 562-22 List of Contents

## **FORM 123-22 AUTOMOTIVE APPLICATIONS**

Refer to the following list of contents for information contained in the Baldwin Automotive Filter Applications Catalog, Form 123-22.

- *Automotive and Light-Duty Truck Applications 1985-on (Includes Imports)*
- *Automotive and Light-Duty Truck Applications Pre-1985 (Includes Imports)*

## **FORM 124-22 OFF-HIGHWAY APPLICATIONS**

Refer to the following list of contents for information contained in the Baldwin Off-Highway Filter Applications Catalog, Form 124-22.

- *Off-Highway Applications*

## **FORM 560-22 MANUFACTURERS' CROSS-REFERENCE**

Refer to the following list of contents for information contained in the Baldwin Manufacturers' Cross-Reference Catalog, Form 560-22.

- *Manufacturers' Cross-Reference*

## **FORM 561-21 NUMBER-FINDER CROSS-REFERENCE**

Refer to the following list of contents for information contained in the Baldwin Number-Finder Cross-Reference Catalog, Form 561-21.

- *Cross-Reference Information Arranged in Number-Finder Format*
- *Manufacturers' Codes*

## **FORM 562-22 PRODUCT GUIDE**

Refer to the following list of contents for information contained in the Baldwin Product Guide Catalog, Form 562-22.

- *Filter Bases*
- *Vacuum/Pressure Gauges*
- *Farr Tube-Type Air Filters*
- *Air Filter Adapters*
- *Coolant Filters/Products*
- *Truck Service Kits*
- *Hydraulic Pall-Type Replacement Elements (9000)*
- *Automatic Transmission Filters*
- *Oil/Air Separators*
- *Stanadyne Fuel Additives*
- *Gaskets*
- *Caterpillar Gaskets*
  
- *Size Charts*
  - *O-Ring Uniform Dash Numbers*
  - *Round Gaskets Arranged by O.D.*
  - *Spin-on Filters by Tap Size*
  - *Liquid Elements by Length*
  - *Round Air Filters by Length*
  - *Panel Air Filters*
  - *Oval, Oblong and Miscellaneous Air Filters*
  - *Box-Style and Can-Type Fuel Filters*
  - *Oil/Air Separator Elements*
  - *Oil/Air Separator Spin-ons*
  - *In-Line Fuel Filters by Inlet Size*
- *Also Included*
  - *DAHL Fuel Filter/Water Separators*
  - *Radial Seal Air Element Adapters*
  - *Industrial Air Cartridges*
  - *Filter Wrenches*
  - *PKG Items*
  - *UPC Codes*
  - *Baldwin Weights and Volumes*

## BALDWIN NEW PRODUCTS

BALDWIN NUMBER	DESCRIPTION	REPLACES	APPLICATIONS
PA4387	Panel Air Element	Hyundai 28113-26350	2003-06 Hyundai Santa Fe
PA10107	Panel Air Element	Toyota 178010P090	2017-22 Lexus RX450h, 2018-22 RX450hL; 2017-19 Toyota Highlander
PA10406	Panel Air Element	Nissan 165461LA0A	2017-22 Nissan Armada; 2011-13 Infiniti QX56, 2014-22 QX80
PA10419	Panel Air Element	Subaru 16546AA16A	2019-22 Subaru Ascent, Forester, 2018-22 Crosstrek, 2017-22 Impreza, 2020-22 Legacy, Outback
PA10420	Panel Air Element	Volkswagen 5QM129620B	2019-21 Volkswagen Golf, Jetta, 2022 Taos
PA10421	Panel Air Element with Foam Pad	Volvo 31370089	Volvo Automotive, Light-Duty Trucks
PA10423	Panel Air Element with Foam Pad	AC Delco A3228C; GM General Motors 84065602	2018-20 Chevrolet Express Van 2500, Express Van 3500; GMC Savana 2500, Savana 3500, all with 4.3L Engine
PA10424	Panel Air Element with Foam Pad	Nissan 165465RB1A	2018-22 Nissan Kicks, 2020-22 Versa
PA10431	Cabin Air Element	Ford Motor KB3Z19N619A; Motorcraft FP88	2019-22 Ford Ranger
PA10433	Panel Air Element	Honda 1722-06A-0A00	2018-22 Honda Accord
PA10435	Panel Air Element with Foam Pad	Chrysler 68320315AB	2019-22 Jeep Cherokee
PA10436	Panel Air Element	Ford Motor JX6Z9601A; Motorcraft FA1939	2019-22 Ford Transit Connect, 2020-22 Escape, 2021-22 Bronco Sport; 2020-22 Lincoln Corsair
PA10437	Panel Air Element	Ford Motor KV61-9601-AA, 2207430; Motorcraft FA1938	2019-22 Ford Transit Connect
PA10438	Panel Air Element	Chrysler 68386779AA; 68441763AA	2019-22 RAM 1500, 1500 Classic
PA10439	Cabin Air Element	Nissan 272776CA0A, 272776CA1A	2022 Infinity WX50, QX55, QX60; 2019-22 Nissan Altima, 2022 Pathfinder
PA10440	Cabin Air Element	Ford Motor JX6Z19N619BA; Motorcraft FP89	2021-23 Ford Bronco Sport, Mustang 2021-22 Mach-E, 2020-22 Escape, Explorer, 2020-22 Police Interceptor Utility; 2020-22 Lincoln Aviator, Corsair
PA10441	Panel Air Element	Ford Motor L1MZ9601A; Motorcraft FA1947	2020-22 Ford Explorer, 2020-22 Police Interceptor Utility
CV15015	Crankcase Breather	Caterpillar 2747913; Racor CCV5527410; Donaldson P636077	Caterpillar Marine Engines
20071	Transmission Filter	Toyota 3533033050, 3533048020	Lexus, Toyota Automotive
20072	Transmission Filter	Motorcraft FT202; FT215; Ford Motor HL3Z7A098A, L1MZ7A098A	2019-22 Ford Expedition, Ranger, 2021-22 Bronco, 2022 Explorer, 2017-2021, 2023 F-150, 2020-22 Mustang, 2020, 2022 Police Interceptor Utility; 2019-23 Lincoln Navigator
PT23627-MPG	Maximum Performance Glass Hydraulic Element	Komatsu 2076071183	Komatsu Dozers, Dump Trucks, Excavators, Loaders
CA30203	Channel Flow Air Element	Caterpillar 2804180; Donaldson P643217	Caterpillar Generators
PA30284	Air Element	Cummins 1404157; Fleetguard AF26044	Cummins X3.3 Generator Engine
RS30295	Radial Seal Outer Air Element	Tata Cummins 571909130130; Fleetguard AF26676	Tata LPK3138, Prima 3138K Trucks
RS30296	Radial Seal Inner Air Element	Tata Cummins 571909130131; Fleetguard AF26339	Tata LPK3138, Prima 3138K Trucks
RS30336	Radial Seal Air Element	Briggs & Stratton 796031; John Deere MIU13038, MIU14395	John Deere Lawn & Garden Equipment
B40057	Lube Spin-on	Quincy 2023400100, 2023400101	Quincy Reciprocating Air Compressors
B40146	Lube Spin-on	Cummins 3647559; Fleetguard LF9540	Cummins Engines
BC40148	Centrifugal Lube Element	Paccar 1922496, 1922496PE	Kenworth, Peterbilt Trucks with Paccar MX-13 Engines
B40153	Lube Spin-on	Mack 23155587; Volvo 23151592	2021 Volvo North America Trucks w/D13 Engine
B40154	Lube Spin-on	Cummins 5375337; Fleetguard LF14005NN	Cummins Engines, Generator Engines, Marine Engines; Hitachi Dump Trucks, Excavators; Komatsu Dump Trucks, Loaders
P40156	Lube Element	Ford Motor JX6Z6731B; Motorcraft FL2082	2019-20 Ford Transit Connect
BF46061	Fuel Spin-on	Donaldson DBB8666	
BF46148	Fuel Spin-on	Nissan 1640501T70, 1640501T0A	Nissan UD MK130, MK150 Trucks
PF46174 KIT	Fuel Filter Kit	Ford Motor HC3Z-9N184-B, HC3Z-9N184-C; Motorcraft FD4624, FD4625, FD4625AA	2017-22 Ford F-250 Super Duty, F-350 Super Duty, F-450 Super Duty, F550 Super Duty
BF46242	In-Line Fuel Filter	Cummins 149234101; Onan 1492341	Onan RV Generators

---

## BALDWIN NEW PRODUCTS

---

<b>BALDWIN NUMBER</b>	<b>DESCRIPTION</b>	<b>REPLACES</b>	<b>APPLICATIONS</b>
BF46245	Fuel Spin-on	Donaldson DBB0248, P570248	Custom applications needing a water absorbing fuel filter
BF46256	Fuel Spin-on	Cummins 3644985; Fleetguard FF256	Cummins QSK23, QSK38, QSK50, QSK60 Off-Highway Engines
PF46259	Fuel Element	ACDelco TP2016; GM General Motors, 84428486, 84428487, 84186990	2021-22 Chevrolet Express 2500, Express 3500; 2021-22 GMC Savana 2500, Savana 3500

---

### NOTES

---

## BALDWIN OBSOLETE PRODUCTS

OBSOLETE NUMBER	REPLACED BY	OBSOLETE NUMBER	REPLACED BY	OBSOLETE NUMBER	REPLACED BY	OBSOLETE NUMBER	REPLACED BY	OBSOLETE NUMBER	REPLACED BY
B-1/2		PT-55	T55-M*	PT123-5		P-244		VSD-407	SD407*
B-1/2-S		T55-M		B-127		B245		VDF-408	DF408
B-1	B2	T-56-M	V835-M*	C130-C		PT-245		T-409-PE	
BO-1A		T57-M		C-132-C Series		PT-246		T-410-PE	
V-1-F	V2-F*	T58-M		C-134-EL		V-247-M		TA410-CPE5	
DL2	B2	C59-C		BT136		B-249	B2 or V2-F*	TC411-CPE5	
V-2-A	B9	P-59	C59-C*	PT-139		P250		TC411-OPE5	
V2-F	B2	C-60-C	P60	B-140		PD-250		T-411-PE	
B-3	B9	PT-61	PT61-HD	C-141-F		P-252		TB411-CPE25	
V-3-A	B9	T-62-P	PT62	B-142		B-254	B50	TC411-CPE2	
C-5-K	C-50-MH*	T-63-P	PT63-1	B-145	B243	P254		TC411-OPE2	
E-5		C64-P	P64*	PT147		PT-255		TC411-CPE10	
ME-6-F		P64		P149		V-261-A		TB412-CPE25	
V-6-A	B6	BT65		T-153-M		PT-262		T-412-PE	
D-7		C-65-P	T77-P*	V-156-M		P-263		PT412-5	
B-8	B27	P-65	T77-P*	PT-157	P80 or P80-HD	BT-266	B2 or V2-F*	TB412-OPE25	
V-9-A	B9	PT-66	PT66-HD	PT158(2)		P270		P412-5A	
B-10	B10-AL	C-67-P	P67	PT-159	PT385	BT272	B7082	P412-25	
B-10 Bowl	B10-AL Bowl	C-68-P	P68	PT-159-E	PT385-E	P-272		TA412-CPE5	
B-10-HD	B10-AL	C-69-P	P69*	PT-160		P276 KIT		PA4125	
B-10-HD Bowl	B10-AL Bowl	P69		B-161	B161-S	B-278		PT412-25A	
B-13	B10-AL	T70-P	PT70	P165		B-280	B39	TC412-CPE5	
B-13 Bowl	B10-AL Bowl	T71-P	PT71	P-168		BT-281	B975	TC412-CPE25	
P-13		T72-P	PT72	P169		BT282	BT8449	TC412-OPE5A	
P-14		C-73-P	P73	B-173	B173-S	BT282-10	BT8449-10	TC412-CPE2	
EO-16-A		PT-73	P73	P-173		PT-286		TC412-OPE5	
S-16	S16-1	C-73-PS	P73	B175	B1422	PT-288	PT288-HD	TC412-CPE50	
P17		T-73-P	P73	P-175		B-290		TA412-CPE10A	
C18-A	P18 or P18-HD	C-74-P		P-178		B291		TA412-CPE10	
C-19-A	P19	T-75-P		P-179	P177	PT-291		TS412-CPE50	
P-20	P20-HD	B76-B	B76	P180		PT293		TC412-CPE10	
P-20-E	P20-HDE*	B76-HPG	B76-SS	PT-182 Kit		PT-294		TC412-CPE25A	
P20-HDE	P20-HD	PT-77	T77-P*	C184-P	P184	B297	B2	TC412-OPE10	
C21-A		T77-P		P188		B-298	BT223	TB413-CPE25	
P-21	C21-A*	C78-P		T192-P		VT-299	V842-O*	T-413-PE	
C22-A		C80-P	P80	PT-195	P15	T-301-M	T300-M	TS413-CPE50	
P-22	C22-A*	C81-P	P81	B196-MPG		T-302-M	T303-M	TA413-CPE10S	
C23-A		C-84-P1	C84-P2*	P-196		T304-M	PT304	TA413-CPE10	
C24-A		P-84-1	P84-2	B-197	B243	T-305-M	T304-M*	TS413-CPE75	
V24-A2		C84-P2	P84-2	P-197		T-306-M		TC413-CPE10AS	
C25-A	P25	T-85-P	PT85	C200-K		T-307-M		TC413-CPE10	
C-26-A	P26	PT-86	PT86-HD	P-200	C200-K*	P315		F-414-B	
V-27-A	B27	PT-87	PT87-S	T-200-K	C200-K*	PT317	PT317-MPG	PF-414-10	
C-28-A		PT-87-HD	PT87-S	B-201	B201-S	PT318	PT318-MPG	PF-414-15	
C-30-B		PT88	PT88-HD	C-201-K	P42	PT319	PT319-MPG	PF-414-25	
C-31-B		PT-90	PT90-10	P-202	PT154	PT320	PT320-MPG	P-415-2A	P415-5A
C-32-B		PT92		P-202-S		BD321	BD325	PF-415	P415-5
PT32-H		PT94		P-205		BD322	BD232	S-416	PT416
C-33-B		B95-B	B95	PT-208-10		BD323	BD232	S417	
P-33	C-33-B*	B95-HPG	B95-SS	P-209		C327-O		S-418	
C-34-M		C-95-IL		PT-211		B328	BT8417	S419	
P-34		B-96 Kit	BK6311*	PT-212	PT212-5	BF335		PT-420	
B-35	B35-S	B96-B	B96	PT-215	P41	BT-344	BT344-S	S-421	PT435
C-35-M		B96-HPG	B96-SS	PT-216	P198	BT-352	BT486	S422	
C36-M		C-96-IL		P-217		BT-356	BT292	S-424	
P-36	C36-M*	B97-B	B97	C-218-A		BF362	BF7629	PT-425	
C-37-M		C-97-G		P219		BF363	BF984	S-426	
P-37	C-37-M*	B99-HPG	B99-SS	V-220-R		BT371-5		S-427	
B38		C-100-C		V-221-R		PT384		BT428	BT372-MPG
V-39-A	B39	C-101-W	T101-W* w/G115-A	F-222-P		PT390	PT390-MPG	V-428-B	
C-40-F	P40	PT-101	T101-W*	P-223		PT391	PT391-MPG	V-428-FF	
C-41-F	P41	T101-W		F225-F	PF225	PT-394	P194-HD	V-429-BP	V429-B
C-42-F	P42	C-102-W		F226-F	PF226	PT394-5		PF-430	
B43	B43-S	T-103-W	P42 w/G143	PT-227		PT399	P7003	PT-430-B	
PT-43	PT29	P-105		P-228	P190	WG-400		PT432	
T44-M		P107		C-229-A		PT401	PT401-MPG	S-433	
PT-45		P-109		P-230		WG-401		PT-436-WO	PT436
T-45-F	PT-45*	P-110		B-232	B233	WG-402		S-438	
PT46		P-113		B233-HPG		WG-403		PT-439-HD20	
T-46-F	PT46*	V-117-F	PT117	V-233-F	B233	WG-404		PT-439-HD40	PT-439-HD20*
C-47-P	P47	V-118-MN		B-234	B296	JC-405-B	JC405	S-440	
C-49-F		PT-119-5DL	(2) PT119-5	PT-236		CU-406-B	CU406	S-441	
C-50-MH		PT-119-5TR	(3) PT119-5	P-237		CU-406-I	CU406	PT442	PT442-MPG
PT-51	T51-M*	PT119-HD5DL		P-238		CU-406-WO	CU406	S-442	
T51-M		PT-119-TR	(3) PT119	PF-239		P-406	CU406	S-443	
C-52-MS	P52	PF-120		P-241	PT29	VCU-406	CU406	S444	
C-53-MJ	P53	B-121	B50	PT-242		VCU-406-HD	CU406	PT445	PT445-MPG
C-54-M	P54	B-122		PT-243	PT82-HD	SD407		S-445	S423

\* These Part Numbers are also Obsolete.

**BALDWIN OBSOLETE PRODUCTS**

OBSOLETE NUMBER	REPLACED BY	OBSOLETE NUMBER	REPLACED BY	OBSOLETE NUMBER	REPLACED BY	OBSOLETE NUMBER	REPLACED BY	OBSOLETE NUMBER	REPLACED BY
S-447	S444*	P540-S	P540	PA664-1 FOAM		BT758	BT8850-MPG	PF-855	
S448		PT542		PA-665		C759		PF-856	PF859
PT449		PT544		PA-667		PT-760	PT760-10 or PT760-25	PF-858	
PT-452		PT-544-10		PA-668		PT762		F-861-C	
BT453	BT260-10	PT-547		PA-672		PT769	PT8395 or PT8396	F-862-C	F924-C*
PT-453		PT552		PA-673		BT770	BT8861	F-863-C	
PT-454		BF553		PA-674		BT771	BT8863	PF-865	
P457		PT-553-10		PA-676		PT773	PT773-MPG	BF867	BF7713
PT457	PT457-MPG	BT-556		PA-679		PT776	PT776-MPG	F-867-M	
S458		PT557-10		PT679	PT23490-MPG	V-780-S		PF-867	
TB460-CPE25		PT559		PA-681		BF785-MPG		PF-868	
T-460-PE		PT562		PT681	PT23489-MPG	BF787	BF1280	PF870	PF7521*
BT464	BT8860	PT569-10		PA-682		BF793		F871-F	
P-464		P-570		PA-682(2)		BF796	BF7546	F-872-A	
PT465		PT570-10		PA-683		BF799-D	BF7639-D	PF-873	
P-466		PT572-10		PA-684		F800-A		BF875	
P-467		PT574-10		PT684	PT8400-MPG	F801-P		BF876-B	BF876
PT467	PT467-MPG	PT575		PA-685		F802-A		BF877-B	BF877
PT468	PT468-MPG	B-576 Kit		PT685	PT685-MPG	F-803-A		F878-F	
T-468-R		BF580	BF5800	PA-686		PF803		BF880	BF880-FP
P-470		BF580-B	BF5800-B*	PT686		F-804-A	PF804	PF-880	
PT-472 Kit		BF581	BF5810	PA-687		F-805-A		PF-881	
S-473		BF581-B	BF5810-B*	PT687		F-806-C		PF-885	
PT-474		PF589	PF7789*	PA-689		F808-A		BF887	
PT478	PT478-MPG*	PF589-10	PF7789-10*	PA-690		F-808-P	PF828	BF889	
PT478-MPG		PF589-30	PF7789-30*	PA-692		F-809-P	PF809	PF-889	
S-478		PF589-30E		PA-694	PA642	F-811-A		PF-893-GR	PF893
S479		PF589-E		PA695		PF-812	PF906	PF-894-GR	PF894
PT-481	P446	PF590	PF7790*	PA-698		F813-F		BF895	
PT482	PT482-MPG*	PF590-10	PF7790-10*	C701-L		PF-813	F813-F*	PF-895	
PT482-MPG	PT725-MPG	PF590-30	PF7790-30*	C702-L		B-815-O		SF-898-GR	SF898
S-482		PF590-30E		C703-L		BF815	BF7713	F901-C	
S-483		PF590-E		C-704-L Poly	C704-L	F-815-A		F902-C1	
PT484		C-59-C3	C59-C*	C-704-LS	C704-L	F817-F		F-902-S	PF902-S
P-486		PF599-30		F-704-L	P7040*	F-818-A	F800-A*	F-903-C	PF-903*
PT487 KIT	PT487	PF599-30		C705-L		PF819-HD		PF-902-3	
P-488		PA-601	PA602	PV706-M	P706-M	F-820-P	PF820-S	PF-903	
S489		PF601		PV-706-M Poly	PV706-M*	F-820-S		F-904-C	PF904*
PT491(2)	(2) PT491	PA-603		PT-707	PT707-HD	PF-821	PF821-S	PF904	
BK495-A		PA-605		PT-707-10	PT707-HD10	F-823-P	PF823	F905-C	
BK495-B		BT606	BT606-MPG	VT-708		PF823(2)	(2) PF823-E	F-905-W	
P-495		PA-606		C-709-L		w/5H-5601		F906-C	
PT-499	PT499-5	B608	B227	VT-710		PF823(3)	(3) PF823-E	PF-906-S	PF906
T500-MD		PA-608		V-711		w/8M-7830		F-910-C	PF910
T502-AMD		PA-609		V-712		PF823(4)	(4) PF823-E	F911-C	PF926
T-503-MD		BT610	BT610-MPG	V-713		w/7M-8286*		F911-DL	PF952
V504-MD		PA-610		PT714		PF823(6)	(6) PF823-E	F-911-W	
P505		BT611	BT611-MPG	P718		w/G219, (2) 4L-8212-R		PF-911	F911-C* (Depth); PF926 (Paper)
P-506		PA-611		V-718-FF	P718*	PF824(2)	(2) PF824	V-911-C	F911-C*
PT508	PT508-MPG	PA-614	PA650	P-719		F828-F		F-912-W	
P-509		PA-619		P-720		BF830		PF-914	
PT509 Kit	PT509-MPG Kit	PA-620		PT-727	PT727-HD	BF832	BF7713	R915	BF915
T-509-E		PA-622		PT-727-10	PT727-HD10	PF-832		F917-C	
F-510-S		PA-623	PA602	PT-727-HD5		F-833-P		BF918	BF918-K
V-510-S		SA-624		PT728	PT728-MPG	F-835-M		PT-918	
P-511		PA-626		V-728-O		W835-M		F-919-C3	(3) F919-C w/5B-1581, 7B-8037
P-511-HD		PA-627		PT730	PT8361	F-836-F		F-919-C4	(4) F919-C w/(2) 7B-7635
F-515-O		PA-628	PA634	BT731 Kit	BT8308-MPG Kit	PF-837		F-919-C5	(5) F919-C w/3H-5671*, 3H5673*
EL-518		PA-629		BT734	BT8851-MPG	BF-840-K2	BF833-K2	F-919-A6	(6) F919-C w/(2) 7B-7635
F-518-O		PA-630		V736-O		BF-840-K3	BF836-K3	F-919-C6	(6) F919-C w/(2) 7B-7999*
V-518-O		PA-635	PA-603*	PT-737-5		BF-840-K4	BF836-K4	F-919-A9	(9) F919-C w/2F-9341*, 2F-9342*
B519	B1400	PA-636		BT742	BT8870-MPG	BF-841		F-919-B9	(9) F919-C w/1H-4511*, 1H4514-R*
P-519		PA-637		V-743-O		BT841		F-919-C9	(9) F919-C w/(2) 7B-7664
PT520-10		PA-640-HD		V743-T		V842-O	VT842-O	F-919-C10	(10) F919-C w/8F-7715*, 8F-7716*
BT523	BT8803-MPG	PA-646	PA2007	BT744	BT8862	F848-A		F-919-C12	(12) F919-C w/6B-2955*, 7B-8017
PT-523	PT561	PA647		BT745	BT8844	PF-849	PT849	F-919-A17	(17) F919-C w/9F-1805*, 9F-1806*
BT-524	B2	PA656 FOAM		BT746	BT8845	BF850			
P524	P294	PA659		BT747	BT8846	BF850-K			
EL-527		BF660	BF1179	BT748	BT8840-MPG	BF851	BF833		
B530	B1402	PA-660		BT749	BT8852-MPG	PF-851			
PT-530	PT390* or PT391*	T-660-P		C-750-EP		PF-852			
S-530		BF661		C-750-L Poly	C750-L	PF-853			
PT531		PA-661		C-750-LS	C750-L	PF-854			
S-531		PA-663	PA675	F-750-L	P7500	V-854-O	V854-T*		
PT-532-10	PT482*	PA-664	PA664-1*	PT754		V854-T			
S-532		PA664 Foam		PT755					
PT533	PT8331-MPG	PA664-1 Foam*		PT756					
S-533		PA664-1		PT-757-5					

\* These Part Numbers are also Obsolete.



## BALDWIN OBSOLETE PRODUCTS

OBSOLETE NUMBER	REPLACED BY	OBSOLETE NUMBER	REPLACED BY	OBSOLETE NUMBER	REPLACED BY	OBSOLETE NUMBER	REPLACED BY	OBSOLETE NUMBER	REPLACED BY
F-919-C17	(17) F919-C w/2F-9228*, 2F-9231*	BF1006		BF1203	BF1236*	V-1510-R	P1510	PA-1703 Ele.	
P-920		B-1007-N		BF1212-HP	BF1212	V-1515-R		PA1703 FOAM	
F921-C		BF1007		BF1212-W		V-1530-FF		PA-1703 Scr.	
F922-C		B-1008-N		BF1229	BF1230*	V1530-R		PA1706XP	
F923-C		V1009-W		BF1230	BF1222 or	F-1540-C		PA-1708-FN	PA2657-FN
F924-C	PF924	BF1010		BF1222-SP		P1562		PA-1711	
BF925		P-1010-L		BF1234	BF1205 or	P1564		PA1713	
F-925-C		PV-1010-L	P-1010-L*	BF1205-SP		P1566		PA-1714 Ele.	
F927-C		F-1030-C		BF1235	BF1257	P1569		PA-1714 Foam	
PF-928		V-1030-C		BF1236	BF7673*	P1570		PA-1714 Scr.	
PF-929		B1031		BF1237	BF7674*	P1571		PA-1715	
F-930-C		B-1032		BF1238	BF7672*	P1572		PA-1716	
PF-930		F-1033-O		F-1240-C		P1573		PA-1716-FN	
T931-3T		V-1033-O		V1240-O		P1574		PA-1717	
V931-W(8)		F-1035-C		V-1240-O1		P1575		PA-1720	
V-931-W(57)	V931-W(8)*	V-1035-C		BF1241	BF7679*	P1576		PA-1722	
F-932-C		T-1036-B		F-1241-C		P1578		PA-1723	
F-933-C		V-1037-A		V-1241-C		P1579		PA-1724	
BF934		V-1038-T		V-1250-O		PF1580		PA-1725	
F-934-C		F-1040-O		V-1251-O		PF1581		PA-1727	
P-937-C8		V1040-C		BF1254	BF7681*	PF1582		PA-1728	
F-941-C		F-1050-O		BF1255	BF7677*	PF1583		PA-1728-1	
BF944		BF1051		BF1259-W		PF1586		PA1729	
PF-944	PF947	BF1054		BF1260	BF1283	PF1587		PA-1730	
BF948-B	BF948	V-1055-O		BF1260-SP	BF1283-SP	PF1588		PA-1731	
BF948-D		BF1058		BF1263-SP	BF1272-SP*	PF1589		PA-1732	
BF-948-D Kit	BF948-D*	BF1059		BF1264-SP	BF1274-SP	PF1590		PA-1733	
F-949-F	PF949	V-1060-O			or BF1274-SPS	PA-1601		PA-1734	
F950F-WO	F950-F	V-1074-O		BF1272-SP	BF1272-SPS	PA-1604		PA-1736	
P-951	PT951	BF1103			(Oval Sensor)	PA-1605		PA-1737	
BF-953		BF1106	BF1100		or BF1293-SPS	PA-1611		PA-1738	
F-954-F		BF1107	BF1155*		(Rectangular Sensor)	PA-1612		PA-1738(3)	
PF-956		BF1108	BF1179	F-1280-C		PA-1612-1A	PA1754	PA1739	
BF957-B	BF957	BF1109	BF1108*	BF1284-SP	BF1399-SP	PA1616		PA-1740	
BF-957-D Kit	BF957-D	BF1111		BF1290-O		PA-1617		PA-1741	
B-958	BT839-10	BF1112		BF1295-O		PA-1620-2S	PA1620-S	PA-1741 Foam	
BT-958	BT839-10	BF1116	BF1120*	CK1300	FB1301, FB1302, OB1303	PA1621-S		PA-1741-WPC	
F-959-C		BF1117		FK1304		PA1622		PA-1742	
PF-960	P960	BF1118		BF1321	BF1212	PA-1623-S		PA-1743	
F961-C		BF1120		BF1322	BF5813	PA-1624		PA-1744	
BF964		BF1121	BF1123	BF1322	BF5813	PA-1628		PA-1744-FN	
F-964-C		BF1126		BF1323	BF1214	PA1632 FOAM		PA-1744-K	
BF965		BF1127		BF1324	BF1220	PA-1636-2		PA-1745	
PF-965		BF1128		BK1327	B7577, OB1308	PA-1636-2K		PA-1746	
PF-966		BF1129		BK1328	B95, OB1303	PA-1638		PA-1747	
F-969-M		BF1130		BF1329-O	BF46083-O	PA-1640	PA2007	PA-1751	
BF972		BF1131		BF1341	BF1212	V1650-O		PA-1752	
BF-973	BF970	BF1133		BF1342	BF5813	PA-1651(2)		PA-1753	
PF-973		BF1135	BF1100	BF1343	BF1214	PA-1652		PA-1756	
PF-973 Kit	PF-973*	BF1136	BF1100	BF1344	BF1220	PA-1654		PA-1759	
BF976-B	BF976	V-1136-O		BF1351-SP	BF9811-SP	PA-1655		PA-1760	
F-976-W		BF1137	BF1100	BF1352-SP	BF1352-SPS	PA-1656	PA2140 (Cars)	PA-1761	
B-977 Kit	BK6710	BF1138		BF1354-SP	BF1354-SPS	PA2139 (Comp.)		PA-1762	
BF-977		BF1139	BF1105	BF1366	BF1366-O	V-1657-O		PA-1764	
PF-980		BF1144	BF1100	OB1369		PA1658		PA-1766	
BF-981		BF1145		BF1383	BF1383-O	PA-1659		PA-1767	
BF982		BF1149	BF1191	B1401	B1400	PA-1660		PA1770	
BF-983	BF970	BF1152	BF1100	B1403	BD1403	PA-1660 Special	PA2698	PA-1785	
BF-985	BF991	BF1153	BF1100	B1404	B245*	PA-1662		PA-1791	
PF-988		BF1155		B1408		PA-1665		PA-1792	
BF-989 Kit		V-1155-C		B1412	B33	PA-1668		PA-1793	
BF990		BF1156		B1415		PA-1671		PA-1796	PA1815
BF-993	BF988	BF1157	BF1100	B1420	B173-S	PA-1672		PA-1796-K	PA1815
PF994		BF1158	BF1100	B1423	B113	PA-1676	PA1863	PA-1799	PA1848
P-997		BF1162		B1424		PA-1677		PA1800 FOAM	
P999	P999-HD	BF1165		B1427	B421	PA-1678(2)		PA-1801	
P-999 Kit		BF1167	BF1057	HC-1430		PA-1685		PA-1803	
P-999-B Kit		BF1168	BF1057	P1439	P1445	PA-1690		PA1804	
B1000-CD	P996	BF1169		B1442	B1429	PA-1691		PA1807	
B1001-N		BF1175		P1445	P7442	PA-1693		PA-1808	
B-1002-CD	B1000-CD*	BF1183		V1500-R		PA-1694		SA-1809	
F1002-C		BF1186		V1506-FF		PA-1695		PA1810-WPC	
B-1003-N		BF1188		V1506-R		PA-1700 Ele.		PA-1811	
BF1003		BF1190		V-1507-R		PA1700 FOAM		PA-1812	
BF1004		BF1192		V1509-R		PA-1700 Scr.		PA-1813-FN	
B-1004-N		BF1194		F-1510-R	P1510	PA-1701 Scr.		PA-1820	
B1005-N		BF1196		PF-1510	P1510	PA1702 Ele.		PA-1822	
		BF1202	BF1237*	PF-1510-7		PA-1702 Scr.		PA-1829	

\* These Part Numbers are also Obsolete.

**BALDWIN OBSOLETE PRODUCTS**

OBSOLETE NUMBER	REPLACED BY	OBSOLETE NUMBER	REPLACED BY	OBSOLETE NUMBER	REPLACED BY	OBSOLETE NUMBER	REPLACED BY	OBSOLETE NUMBER	REPLACED BY
PA-1833		LL1980-FN		PA2129		PA2373		PA2802	PA3499
PA-1835		PA1983		PA2130		LL2382	PA2382	PA2804 KIT	PA2804
PA-1837		PA-1986 Kit	PA1986-K	PA2131		LL2389-FN	PA2389-FN	PA2808	
PA-1838		PA-1987 Kit	PA-1987-K*	PA2132		PA2398		PA2809	
PA-1838-K		PA-1987-K		PA2133		C2400-A		PA2810	
PA1839-FN		PA-1990		PA2137		V-2400-A	C2400-A*	PA2811	
PA-1842		PA-1991-FN		PA2141		PA2406		PA2841	
PA-1843		LL1992-FN		PA2142		PA2416	PA2845	PA2850	
PA-1844		PA1992	LL1992	PA2143		LL2438	PA2438	PA2859	PA2859-FN
LL1847-FN		PA-1993	PA2546	SA2144		PA2441		PA2862 FOAM	
PA-1847		PA-1994	PA2547	PA2145		PA2449-K		PA2863	RS2863
PA-1850		PA-1999		PA2146		LL2461	PA2461	PA2868-FN	PA2778-FN
PA-1853		PA-2000		PA2151		PA2463		PA2873	
PA1853-FN		PA-2003		PA2155		LL2465	PA2465	PA2879-FN	
PA-1853-K		PA2004		PA2157		PA-2470	PA2667	PA2882	
PA-1854		PA2008 FOAM		V-2160-O		PA-2471	PA2668	PA2883	
PA1855		PA-2011		PA2161		PA2480		PA2887-FN	
PA-1856	PA-2000*	PA-2012		PA2165		PA2481		PA2889	
PA-1862	PA1885	PA-2013	PA1802	PA2166		PA2492		PA2890	
LL1864-FN		PA2014		PA2170		LL2494	PA2494	PA2893	PA3477
PA-1869		PA2015		PA2172		PA2501	PA3951	PA2894-FN	
PA-1870		PA-2016		PA2173		PA-2505		PA2898	
PA-1871		PA-2017		PA2174		PA2506		PA2899	
PA-1872		PA-2018		PA2175		LL2515		PA2901	
PA-1874	PA1884	PA-2019		PA2176		LL2516	PA2516	PA2907	
PA-1876		PA-2020		PA2177		LL2520	PA2520	PA2910	
PA-1878		PA-2021		PA2179		LL2531	PA2531	PA2911	
PA-1879		PA-2022		PA2180		LL2532	PA2532	PA2916-FN	PA3664-FN
PA-1883		PA2025		PA2184		LL2533	PA2533	PA2919	
PA1887		PA-2026		PA2185		PA-2537		PA2920	
PA-1890		PA-2028		PA2187		PA2543		PA2926-FN	
PA-1902		PA-2029		PA2188		PA2549		PA2927-FN	
PA-1903		PA-2030		PA2190		PA2553		PA2929	
PA-1908		PA-2032		PA2192		LL2555	PA2555	PA2929-FN	
PA-1910		PA-2033		PA2195		LL2556	PA2556	PA2933	
PA-1914		PA2034		PA2197		LL2558	PA2558	PA2934	PA3445*
PA-1917		SA2035		PA2198		PA2560		PA2935	
PA-1918		SA-2038	SA2045 (Pad Only)	PA2199		PA2561		PA2937	PA2698
PA-1918-K	PA1667-FN			PA2201		PA2565		PA2939	PA2855
LL1922-FN	PA1922-FN	SA2040		PA2202		PA2584		PA2940	
PA-1923		PA-2043		PA2203		PA2590		PA2941	
PA-1924		SA2045		PA2205		PA2594		PA2965	
PA1925		SA2046		PA2206		LL2596	PA2596	PA2966	
LL1926	PA1926	PA-2047		PA2207		PA2597		PA2969	PA2689
PA-1927		SA-2048	PA648	PA2209		PA2600		PA2972-FN	
PA-1927-FN		SA2048		PA2210		PA2603		PA2974	
PA-1928	PA1848	PA-2049		PA2211		PA-2627 Ele.		PA2975	
PA-1929		PA2054		PA2213		PA2639		PA2981	
PA-1930-FN		PA2055		PA2217		LL2641		PA2983	
PA-1931(2)		PA-2056		PA2219		LL2656	PA2656	PA2985	
PA-1933		PA2057		PA2220		LL2659	PA2659	PA2986	
PA-1935		PA-2058		PA2227		LL2663-FN	PA2663-FN	PA2987	
PA-1938		PA2059		PA2228		PA2671		AD2990	
PA-1939		PA-2060		PA2229		LL2675	PA2675	AK2990	
PA-1939-FN		PA2062		PA2235		LL2679	PA2679	AD2991	
PA-1939-K		PA2066		PA2236		PA2681		AK2991...AD2991* & PA2735	
PA1942		PA2078		PA2238		PA2682-FN		AD2992	
PA1943		PA-2080		PA2239		PA2683		AK2992...AD2992* & PA2737	
PA-1944		PA2082		PA2242		PA2685	LL2685	AD2993	
PA-1947		SA2086		PA2245	PA2243	PA2686		AK2993...AD2993* & PA2625	
PA-1948		SA2087		PA2246		PA2695		AD2994	
F-1950-O		PA2088		PA2259		PA2696		AK2994...AD2994* & PA2738	
PA-1950		PA2089		PA2309		PA2697		AD2995	
V1950-O		PA2090		PA-2311-FN		PA2698-K		AK2995	
PA1954		PA-2098		LL2316	PA2316	PA2717		AD2997	
PA-1955		PA-2101	PA2101A	PA-2324	PA-2324-1*	PA2720		AK2997...AD2997* & PA2739	
PA-1958		PA2105		PA-2324-1		LL2734	PA2734	AD2998	
PA-1959		PA2108		PA-2324-K	PA-2324-1*	PA2741	PA3467	AK2998	
PA-1962		PA2111		PA2325		LL2749	PA2749	AD2999	
PA-1964		PA2112		PA-2326-WO	PA2326	PA2759		AK2999	
PA-1965		PA2115 FOAM		PA2327		PA2760		AD3000	
PA-1966		PA2118		PA-2334		PA2763		AK3000	
PA-1968-FN		PA2119		PA-2336		PA2770		HSG3000	
PA-1968-K		LL2120		PA2348-FN		LL2780	LL2503	AD3001	
PA-1970		PA2122		PA-2355		PA2780	PA2503	AK3001	
PA1971		PA2123		LL2357	PA2357	LL2783		HSG3001	
PA1974		PA2126		PA-2365	PA2546	PA2795		AD3002	
LL1979-FN	PA1979-FN	PA2128		PA-2366	PA2547	PA2800-FN		AK3002	

\* These Part Numbers are also Obsolete.

## BALDWIN OBSOLETE PRODUCTS

OBSOLETE NUMBER	REPLACED BY	OBSOLETE NUMBER	REPLACED BY	OBSOLETE NUMBER	REPLACED BY	OBSOLETE NUMBER	REPLACED BY	OBSOLETE NUMBER	REPLACED BY
HSG3002		AE3201		AB3279		PA3412		PA3858	
HSG3003		AE3202		AB3280.....AB3312*		PA3413		PA3866.....PA2489	
HSG3004		AE3203		AB3281.....AB3314*		PA3418		PA3876	
HSG3005		AE3204		AB3282		PA3423-FN		PA3947	
HSG3006		AE3205		AB3283		PA3424-FN		PA3961	
HSG3007		AE3206		AB3284		PA3425		PA3962	
HSG3008		AE3207		AB3285		PA3441		BF-4000	
HSG3009		AE3208		AC3286		PA3445		PF4001	
HSG3010		AE3209		AC3287		PA3449		WF4002-M	
HSG3011		AE3210		AC3288		PA3450		WF4003-M	
HSG3012		AE3211		AC3289		PA3451		PA4004	
HSG3013		AE3212		AC3290		PA3454		BF-4010	
HSG3014		AE3213		AC3291		PA3459		PF4011	
HSG3015		AE3214		AC3292		PA3462		WF4012-A	
HSG3016		AE3215		AC3293		PA3465		WF4013-A	
HSG3017		AE3216		AC3294		PA3468		PA4014	
HSG3018		AE3217		AC3295		PA3497		PA4019	
HSG3019		AE3218		AC3296		AD3522		PA4020	
HSG3020		AE3219		AC3297		AD3523		PA4026	
HSG3021		AE3220		AC3298		AD3524		PA4031	
HSG3022		AE3221		AC3299		AD3525		WG-4033	
HSG3023		AE3222		AC3300		AD3526		PA4034	
HSG3024		AE3223		AC3301		AD3527		PA4036	
HSG3025		AE3224		AH3302		RS3546.....RS3954		PA4038	
HSG3026		AE3225		AH3303		PA3552		PA4039	
HSG3027		AE3226		AH3304		PA3559		PA4040	
HSG3028		AE3227		AS3305		PA3561		PA4047	
HSG3029		AE3228		AS3306		PA3564.....PA3606		PA4051	
HSG3030		AE3229		AB3307		PA3567		PA4052	
HSG3031		AE3230		AB3308		PA3570.....PA3691		PA4053	
HSG3032		AE3231		AB3309		PA3571		PA4054	
HSG3033		AE3232		AB3310		PA3574		PA4058	
HSG3034		AE3233		AB3311.....AB3278*		PA3577		PA4061	
HSG3035		AE3234		AB3312		PA3580		PA4064	
HSG3036		AE3235		AB3313		PA3582-FN.....PA3671-FN		PA4067	
HSG3037		AE3236		AB3314		PA3583.....PA3672		PA4068	
HSG3038		AE3237		AB3315		PA3586		PA4074.....PA3763	
HSG3039		AE3238		AV3316		PA3589		PA4076	
HSG3040		AH3239		AV3317		PA3590		PA4082	
HSG3041.....HSG3069*		AH3240		AV3318		PA3591		PA4083.....PA4081	
HSG3042		AH3241		AV3319		PA3592		PA4086.....PA4416 KIT	
HSG3043		AH3242		AC3320		PA3593		PA4087	
HSG3044		AH3243		AC3321		PA3594		PA4090	
HSG3045		AH3244		AC3322		PA3599		PA4094	
HSG3046		AH3245		AR3323		PA3603		PA4095	
HSG3047		AH3246		AR3324		PA3610		PA4096	
HSG3048		AH3247		AR3325		PA3634		PA4097	
HSG3049		AH3248		AR3326		PA3639		PA4098	
HSG3050		AH3249		AR3327		PA3646-FN		PA4101	
HSG3051		AH3250		AR3328		PA3647		PA4115.....PA4154	
HSG3052		AH3251		AR3329		PA3648		PA4116	
HSG3053		AH3252		AR3330		PA3659		PA4117	
HSG3054		AH3253		AW3332		PA3662		PA4122.....PA4163	
HSG3055		AH3254		AW3333		PA3663		PA4124	
HSG3056		AH3255		AW3334		PA3665		PA4135	
HSG3057.....HSG3070*		AH3256		AW3335		PA3666-FN		PA4136.....PA4155 KIT	
HSG3058		AH3257		AW3336		PA3673		SA4137	
HSG3059		AH3258		AW3337		PA3677		SA4139	
HSG3060		AH3259		AW3338		RS3702.....RS3988		PA4140	
HSG3061		AH3260		AW3339		PA3751-FN		SA4142	
HSG3062		AH3261		AW3340		PA3752		SA4143	
HSG3063		AS3262		AW3341		PA3753		PA4155 KIT	
HSG3064		AS3263		AS3343		PA3759		PA4186	
HSG3065.....HSG3064*		AS3264		AS3344		PA3762		OAS4200	
HSG3066.....HSG3059*		AS3265		AD3345		PA3766		OAS4201	
HSG3067.....HSG3068*		AS3266		AS3346		PA3769		OAS4202	
HSG3068		AS3267		AD3347		PA3770		OAS4203	
HSG3069		AS3268		AS3348		PA3771		OAS4204	
HSG3070		AS3269		PA3400		PA3772		OAS4205	
HSG3072		AS3270.....AS3269*		PA3401		PA3776		OAS4206	
HSG3073		AS3271		PA3402		PA3776		OAS4207	
HSG3074		AS3272		PA3403		PA3784		OAS4208	
HSG3075		AS3273		PA3405		PA3793		OAS4209	
HSG3076		AS3274		PA3407		PA3821		OAS4210	
HSG3079		AS3275		PA3408		PA3837		OAS4211	
HSG3080		AB3276		PA3409		PA3842		OAS4212	
AE3200		AB3277		PA3410.....PA3410-FN*		PA3845		OAS4213	
AS3200		AB3278		PA3410-FN		PA3856		OAS4214	
						PA3857			

\* These Part Numbers are also Obsolete.

## BALDWIN OBSOLETE PRODUCTS

OBSOLETE NUMBER	REPLACED BY	OBSOLETE NUMBER	REPLACED BY	OBSOLETE NUMBER	REPLACED BY	OBSOLETE NUMBER	REPLACED BY	OBSOLETE NUMBER	REPLACED BY
OAS4215		OAS4293		PA4742		PA4856		CTK5026	CTK5029
OAS4216		OAS4294		PA4743		PA4865-FN		CTK5027	CTK5029
OAS4217		OAS4295		PA4744		PA4866		CS5055	
OAS4218		OAS4296		PA4745		PA4867		OTK5062	
OAS4219		OAS4297		PA4746		PA4868-FN		LB-5100 Kit	
OAS4220		OAS4298		PA4747		PA4869		WF5100	
OAS4221		OAS4299		PA4748		PA4873		WF5101	
OAS4222		OAS4300		PA4748 FOAM		PA4874		BW-5120	
OAS4223		OAS4301		PA4749		PA4875		BWC-5120	
OAS4224		OAS4302		PA4751		PA4879		BW-5121	
OAS4225		PA4319		PA4752		PA4880		BWC-5121	
OAS4226		PA4353		PA4756		PA4882		C5130-P	
OAS4227		PA4354		PA4757		PA4884		CW5130-P	
OAS4228		PA4357		PA4759		PA4888		CW-5130-PWP ..CW5130-P*	
OAS4229		PA4369		PA4761		PA4892		& WF4002-M*	
OAS4230		PA4375		PA4762 FOAM		PA4893		CWC-5130-P	
OAS4231		PA4380		PA4765 FOAM		PA4894		CWC-5130-PWP	
OAS4232		PA4382		PA4767		PA4898		CW5131-P	
OAS4233		PA4387		PA4768		PA4901		CWC-5131-P	
OAS4234		PA4389		PA4770		PA4904		CW-5132-P ... (2) CW5131-P*	
OAS4235		PA4392		PA4771	PA4689	PA4906		CW5132-PWP(2) CW5131-P*	
OAS4236		PA4395		PA4772		PA4907		& WF4003-M*	
OAS4237		PA4396		PA4774		PA4909		CWC-5132-P	
OAS4238		PA4403		PA4776		PA4910		CWC-5132-PWP	
OAS4239		PA4406 KIT		PA4777		PA4913		BW-5133	BW5139
OAS4240		PA4407		PA4779		PA4914		BW-5133-A	BW-5133*
OAS4241		PA4408		PA4780		PA4915		BW-5133-Z	BW-5133*
OAS4242		PA4414		PA4780 FOAM		PA4916		BWC-5133	
OAS4243		PA4415		PA4782		PA4917		BWC-5133-Z	
OAS4244		PA4420		PA4783		PA4920		BW-5134	BW5137
OAS4245		PA4424		PA4784		PA4921		BW-5134-Z	BW-5134*
OAS4246		PA4427		PA4785		PA4922		BWC-5134	
OAS4247		PA4467		PA4786		PA4923		BWC-5134-A	
OAS4248		PA4556		PA4787		PA4924		BWC-5134-Z	
OAS4249		RS4584	RS4634	PA4788	PA4389	PA4925		BW-5135	BW5136
OAS4250		PA4607		PA4789		PA4926		CW5150-L	
OAS4251		PA4612		PA4790		PA4927		BW5170	BW5070
OAS4252		PA4615		PA4791		PA4928		BW5171	BW5071
OAS4253		PA4621		PA4792		PA4933		BW5173	BW5073
OAS4254		PA4626		PA4796		PA4935		BW5174	BW5074
OAS4255		PA4640	PA4640-FN	PA4797		PA4936		BW-5176	BW5178
OAS4256		PA4645-FN		PA4798		PA4937		BW-5177	BW5179
OAS4257		PA4658		PA4799		PA4940		BW5180	
OAS4258		PA4668		PA4800		PA4941		BW5181	
OAS4259		PA4669		PA4801		PA4943		PA5286 KIT	
OAS4260		PA4670		PA4805		PA4944		RS5295	RS30191
OAS4261		PA4684		RS4807		PA4946	PA4938	RS5296	RS30192
OAS4262		PA4685		PA4808		PA4947		PA5307	
OAS4263		RS4686	RS4678	PA4810		PA4948		PA5324-FN	
OAS4264		RS4687	RS4679	PA4811		PA4949		PA5330	
OAS4265		PA4688		PA4812	PA3672	PA4950		RS5347	
OAS4266		PA4688 FOAM		PA4814		PA4951	PA4947	RS5348	
OAS4267		PA4689		PA4815		PA4952		RS5362	RS30065,
OAS4268		PA4689 FOAM		PA4816		PA4953			RS30065 KIT (w/Lid)
OAS4269		PA4690		PA4817		PA4954		BA5372	
OAS4270		PA4691		PA4818		PA4957		PA5394	
OAS4271		PA4696 FOAM		PA4821		PA4958		PA5402	
OAS4272		PA4699		PA4822		PA4964-FN		PA5406-FN	
OAS4273		PA4710		PA4826		PA4965		PA5407	
OAS4274		PA4712		PA4828		PA4974		RS5438	
OAS4275		PA4714		PA4832		PA4975		PA5444-FN	
OAS4276		PA4717		PA4835		PA4976	PA3872	PA5469	
OAS4277		PA4718		PA4836		PA4978		PA5473	
OAS4278		PA4719		PA4837		PA4980		PA5474	
OAS4279		PA4721		PA4838		PA4981		PA5476	
OAS4280		PA4722-FN		PA4839		PA4982		PA5480	
OAS4281		PA4723		PA4840		PA4998	PA4820	PA5481	
OAS4282		PA4724-FN		PA4841		CS-5001		PA5487	
OAS4283		PA4725		PA4842		CS-5002	CS5008	RS5488	
OAS4284		PA4726		PA4843		CS-5003	CS5009	PA5501	RS5782
OAS4285		PA4727		PA4844		CS-5004	CS5011	PA5502	RS5783
OAS4286		PA4728		PA4845		CS-5005	CS5010	PA5518	
OAS4287		PA4729		PA4846		CK5006B		PA5519	
OAS4288		PA4731		PA4847		CT5006A		PA5521	
OAS4289		PA4735		PA4849		CTK5006	CTK5029	PA5522	
OAS4290		PA4738		PA4850		CSC5014		PA5523	
OAS4291		PA4739		PA4851		CT5026A		PA5524	
OAS4292		PA4741		PA4854 FOAM		CT5026B		PA5525	

\* These Part Numbers are also Obsolete.

## BALDWIN OBSOLETE PRODUCTS

OBSOLETE NUMBER	REPLACED BY	OBSOLETE NUMBER	REPLACED BY	OBSOLETE NUMBER	REPLACED BY	OBSOLETE NUMBER	REPLACED BY	OBSOLETE NUMBER	REPLACED BY
PA5526		PA5724 FOAM		BK6299		BK6556.....BK6575*		BK6950	
PA5527		PA5726		BK6300		BK6557		BK6951	
PA5530		PA5732		BK6301		BK6558		BK6952	
PA5531		PA5737 KIT		BK6302		BK6565		BK6981	
PA5532		PA5740		BK6303		BK6573		BK6988	
PA5533		RS5760 KIT		BK6310		BK6575		BK6993	
RS5542..RS30142, RS30142		PA5769 KIT		BK6311		BK6580		BK6996	
KIT		PA5775		BK6312		BK6582		B7006	
PA5545		PA5777		BK6313		BK6584		B7008-D.....B7019	
RS5550		PA5778		BK6314		BK6585		B7026.....B7026-MPG	
PA5551		PA5779		BK6316		BK6588		B7027.....B7085*	
PA5552		PA5785		BK6317		BK6589		B7032.....B7130	
PA5553		PA5786		BK6318		BK6590		B7040.....B7040-A*	
PA5554		PA5787		BK6321		BK6592		B7040-A	
PA5555		PA5798		BK6327		BK6593		B7040-CH.....B7040-A*	
PA5560		PA5799		BK6342		BK6594		B7040-PR.....B7040-A*	
PA5561		BF5800-B.....BF5800		BK6348		BK6596		BF7040	
PA5562		BF5810-B.....BF5810		BK6350.....BK6371*		BK6602		BH7040.....B7040-A*	
PA5564		6010		BK6351		BK6603		BH7040-CH.....B7040-A*	
PA5565		6011		BK6352		BK6604		BH7040-PR.....B7040-A*	
PA5567		6012		BK6355		BK6605		F7040	
PA5568		6013		BK6370		BK6606		P7040.....C704-L	
PA5569		6014		BK6371		BK6609		P7040 POLY.....P7040*	
PA5570		6015		BK6374		BK6611		BD7041.....BD7166	
PA5571		6016		BK6381		BK6612		B7043	
PA5572		6018		BK6384		BK6614		B7046	
PA5573		6019		BK6385		PA-664-1 Ele.		P7055	
PA5574		BK6034		BK6386		PA-664-1 Scr.		PT-707-HD5	
PA5575		BK6041		BK6388		BK6649		B7079	
PA5576		BK6043		BK6389		BK6660		B7085.....B7144	
PA5577		BK6044		BK6395		BK6669		P7087	
PA5578		BK6046		BK6398		BK6671		P7088	
PA5579		BK6047		BK6400		BK6674		BD7100	
PA5582.....PA30026		BK6048		BK6401		BK6685		B7108.....B7004	
PA5585		BK6052		BK6404		BK6691		B7109.....B7585	
PA5590 KIT		BK6063		BK6411		BK6701		B7118.....B7144	
RS5591.....RS5591XP		BK6066		BK6413		BK6708		BD7120	
BA5592.....BA5374		BK6072		BK6416		BK6709		BC7140.....BC7194	
RS5593.....RS5593XP		BK6074		BK6418		BK6712		B7149	
PA5594		BK6077		BK6419		BK6718		B7150.....B7180	
PA5596		BK6078		BK6420		BK6722		P7198.....P1443	
PA5598		BK6079		BK6421		BK6742		BT7237-MPG.....BT7237	
PA5599		BK6181		BK6423		BK6788		BD7244.....BD7105	
PA5600 KIT		BK6186		BK6430		BK6792		C7253	
PA5601 KIT		BK6189		BK6431		BK6793		P7254	
PA5603 KIT		BK6200		BK6432		BK6800		P7257	
PA5608 KIT		BK6203		BK6433		BK6802		P7258	
PA5609 KIT		BK6206		BK6435		BK6804		P7261	
PA5612 KIT		BK6209		BK6439		BK6806		P7262	
PA5613 KIT		BK6210		BK6444		BK6807		P7265	
PA5614 KIT		BK6211		BK6452		BK6808		P7266	
PA5615 KIT		BK6212		BK6456		BK6810		B7272.....B7402	
PA5616 KIT		BK6217		BK6463		BK6811		B7278	
PA5634		BK6220		BK6471		BK6818		B7279	
PA5635		BK6221		BK6475		BK6826		B7282	
RS5639 KIT		BK6223		BK6479		BK6829		B7283	
PA5643		BK6226		BK6481		BK6830		B7284	
PA5644		BK6227		BK6485		BK6831		B7288.....B7217	
PA5645		BK6229		BK6496		BK6832		B7296	
PA5646		BK6230		BK6498		BK6834		P7300.....P1562	
PA5647		BK6231		BK6500		BK6838		P7301	
PA5648		BK6233		BK6504		BK6839		P7302	
PA5659		BK6236		BK6509		BK6900		C7304	
PA5660		BK6237		BK6510		BK6901		BT7339.....BT7349	
RS5671		BK6238		BK6511		BK6902		BD7353.....BD40027	
RS5677 KIT		BK6239		BK6514		BK6906		P7354.....P40019	
PA5687		BK6240		BK6516		BK6907		BD7355.....BD40139	
PA5688		BK6243		BK6520		BK6908		B7369	
PA5701		BK6247		BK6523		BK6939		P7371	
PA5702		BK6254		BK6526		BK6940		P7381	
PA5704		BK6259		BK6530		BK6941		B7389	
PA5705		BK6260		BK6531		BK6943		B7392	
PA5714		BK6261		BK6534		BK6944		P7405.....P7505	
PA5715		BK6266		BK6537		BK6945		B7429	
PA5717		BK6269		BK6540		BK6946		B7457	
PA5718 KIT		BK6271		BK6547		BK6947		B7459	
PA5721		BK6284		BK6553		BK6948		B7460	
PA5724		BK6289		BK6555		BK6949		B7462	

\* These Part Numbers are also Obsolete.

**BALDWIN OBSOLETE PRODUCTS**

OBSOLETE NUMBER	REPLACED BY	OBSOLETE NUMBER	REPLACED BY	OBSOLETE NUMBER	REPLACED BY	OBSOLETE NUMBER	REPLACED BY	OBSOLETE NUMBER	REPLACED BY
B7464	B7370	BF7674	BF7674-D	H8039	H9039	H8117		BT8923	
B7465		BF7675	BF7675-D	H8040	H9040	H8118		BT8924	
B7466		BF7677	BF7677-D	H8041	H9041	H8119		BT8925	
B7470		BF7679	BF7679-D	H8042	H9042	H8120		BT8929	
B7472		BF7681	BF7681-D	H8043	H9043	H8121		BT8932	
B7473		BF7682	BF7682-D	H8044	H9044	H8122		BT8933	
B7474		PF7688	PF7698	H8045	H9045	H8123	H9123	BT8934	
B7475		BF7689	BF788	H8046	H9046	BT8300	BT8871-MPG*	BT8936	
B7476		BF7710	BF7765	H8047	H9047	BT8303	BT8304	BT8938-MPG	
B7478		BF7723		H8048	H9048	BT8311	BT8873	PT8938-MPG	
B7481		BF7724		H8049	H9049	BT8313	BT8874-MPG	PT8941-MPG	
B7482		BF7727	BF7827*	H8050	H9050	BT8315	BT8512	PT8942-MPG	
P7484		BF7739	BF7801	H8051	H9051	PT8321	PT8378-MPG	PT8944-MPG	
B-7500	B7500A*	PF7789	PF7889	H8052		BT8324		PT8949-MPG	
B-7500 Kit		PF7789-10	PF7889-10	H8053	H9053*	BT8325		PT8953-MPG	
B7500A		PF7789-30	PF7889-30	H8054	H9054	BT8327	BT8856-MPG	PT8961-MPG...PT9337-MPG	
B7500A-CH		PF7790	PF7890	H8055	H9055	PT8336		PT8963-MPG	
B-7500-CH	B7500A-CH*	PF7790-10	PF7890-10	H8056	H9056	PT8337		PT8964-MPG...PT9403-MPG	
B-7500-PR	B7500A*	PF7790-30	PF7890-30	H8057	H9057	BT8340-MPG..	BT8876-MPG	PT8965-MPG	
BF7500	BF7500-A*	BF7807		H8058	H9058	C8342		PT8966-MPG	
BF7500-A		BF7821		H8059		PT8343		PT8968-MPG	
BH-7500	B7500A*	BF7827	BF9882*, BF46062	H8060	H9060	PT8358		PT8973-MPG...PT8458-MPG	
BH-7500-CH	B7500A-CH*	PF7829		H8061		BT8360	BT8871-MPG	PT8976-MPG	
BH-7500-PR	B7500A*	PF7831		H8062	H9062	PT8362		PT8977-MPG	
C-7500-M	P7500	PF7834		H8063		PT8364	PT8370-MPG	PT8979-MPG	
P7500 POLY	P7500	PF7835		H8064		PT8374-MPG		PT8983-MPG	
P7500 SINGLE	P7500	BF7846		H8065		BT8377-MPG..	BT8853-MPG	PT8986-MPG	
P7514		BF7856		H8066		BT8379	BT8437	PT8988-MPG	
EL7518		BF7858	BF7693	H8067		BT8380	PT8380	PT8993-MPG	
PF7520	PF7799	BF7859		H8068		PT8389	PT23282-MPG	PT8999-MPG	
PF7521	PF7655	BF7861		H8069	H9069	BT8398-MPG		PT9000-MPG	
BF7523		BF7867		H8070	H9070	BT8399	BT8444	H9006	
BF7524	BF788	BF7868		H8071	H9071	PT8402-MPG		H9010	
BF7525	BF970	BF7870		H8072	H9072	PT8405-MPG KIT		H9015	
BF7526	B605	BF7871		H8073	H9073	PT8515-MPG KIT*		H9018	
BF7530-MPG	BF7632	PF7902	FD7926 & BF7925	H8074	H9074	PT8406-MPG KIT		H9024	
BF7533	BF7535	BF7918	BF7972	H8075	H9075	PT8516-MPG KIT*		H9029	
BF7539	BF7644	BF7933 KIT	BF9918 KIT	H8076	H9076	BT8424-MPG		H9037	
BF7542		BF7953-D	BF7951-D	H8077	H9077	BT8434	B114	H9039	
BF7543		H8000		H8078	H9078	BT8454	BT9422	H9040	
PF7547		H8001	H9001	H8079	H9079	BT8466-MPG		H9042-V	
PF7548	PF7620*	H8002		H8080	H9080	PT8467		H9053	
	(Cat, Cummins)	H8003		H8081	H9081	PT8469-MPG		H9057	
	PF7621* (Detroit)	H8004		H8082	H9082	PT8515-MPG KIT		H9095	
K-7550 Kit	BK6355*	H8005		H8083	H9083	PT9415-MPG KIT		H9097	
BF7557-B	BF7557	H8006	H9006*	H8084	H9084	PT8516-MPG KIT		PT9124-MPG	
B7575	B7577	H8007	H9007	H8085	H9085	PT9416-MPG KIT		PT9125	
B7577-B	B7577	H8008		H8086	H9086	OV8700		PT9125-MPG	
K-7577 Kit	BK6401	H8009		H8087		OV8701		PT9126	
PF7578	PF7678	H8010	H9010*	H8088		OS8702		PT9127	
BF7581	BF7646*	H8011		H8089		OS8703		PT9128	
BF7582	BF7647*	H8012		H8090		OS8704		PT9130	
PF7583		H8013	H9013	H8091		OS8705		PT9133	
K-7596 Kit	BK6350*	H8014	H9014	H8092	H9092	OS8706		PT9138	
P7599		H8015		H8093	H9093	OS8707		PT9141	
BF7601	BF954	H8016		H8094		OS8717		PT9146	
BF7609		H8017		H8095	H9095*	OS8718		PT9147	
PF7610	PF7651*	H8018	H9018	H8096	H9096	OB8720		PT9151	
PF7611		H8019		H8097	H9097	OB8724		PT9154	
PF7620	PF7680	H8020	H9020	H8098		OB8726		PT9155	
PF7621	PF7680	H8021	H9021	H8099		OV8728		PT9156	
BF7626		H8022		H8100		OB8732		PT9159	
B7637		H8023		H8101		OB8740		PT9160	
BF7641		H8024	H9024	H8102		OB8741		PT9163	
P7642		H8025		H8103	H9103	OB8744		PT9165	
BF7643	BF7682*	H8026		H8104		OB8745		PT9166	
BF7646	BF7674*	H8027		H8105		OB8746		PT9171	
BF7647	BF7681*	H8028		H8106		OB8771		PT9173	
BF7649	BF7672*	H8029	H9029*	H8107	H9107	OB8772		PT9177	
BF7650	BF7679*	H8030		H8108	H9108	OB8781		PT9178	
PF7651	PF7751	H8031		H8109		OB8783		PT9182	
BF7652	BF7674-D	H8032		H8110	H9110	BT8806-MPG		PT9184	
PF7654	PF7777	H8033		H8111	H9111	BT8807-MPG..	BT8800-MPG	PT9190	
BF7660	BF1163	H8034		H8112	H9112	BT8860	BT8861	PT9192	
BF7662		H8035		H8113	H9113	BT8871-MPG..	BT8876-MPG	PT9194	
BF7665	BF7675*	H8036	H9036	H8114	H9114	BT8914		PT9198	
BF7672	BF7672-D	H8037	H9037	H8115		BT8916		PT9200	
BF7673	BF7673-D	H8038		H8116		BT8921		PT9201	

\* These Part Numbers are also Obsolete.

## BALDWIN OBSOLETE PRODUCTS

OBSOLETE NUMBER	REPLACED BY	OBSOLETE NUMBER	REPLACED BY	OBSOLETE NUMBER	REPLACED BY	OBSOLETE NUMBER	REPLACED BY	OBSOLETE NUMBER	REPLACED BY
PT9202		PT9514		18286		PT23109-MPG		PT23308	
PT9204		PT9531		18287		PT23113-MPG		PT23309	
PT9205		PF9806 KIT	PF9924 KIT	18288	18024	PT23115-MPG		PT23310	
PT9206		BF9813		18289		PT23116-MPG		PT23311	
PT9207		BF9819		18290		PT23118-MPG		PT23312	
PT9209		BF9824		18291		PT23119-MPG		PT23313	
BT9211	BT8474	PF9824		19551		PT23130-MPG	PT23396-MPG	PT23314	
PT9213		PF9825		19569		PT23134-MPG		PT23315	
PT9216		BF9832		19577		PT23144		PT23316	
PT9218		PF9838		19585		PT23146		PT23317	
PT9219		BF9840		19593		PT23147		PT23318	
PT9220		BF9843		19607	18112	PT23150		PT23319	
PT9221		PF9845		19615	19739	PT23151		PT23320	
PT9226		BF9849		19623		PT23153		PT23321	
PT9228		BF9853		19631		PT23158		PT23322	
H9229		BF9854		19658		PT23159		PT23323	
H9230		CA9872		19666		PT23161		PT23325	
H9232		BF9882	BF46062	19674		PT23162		PT23326	
H9233	PT320-MPG	PF9896 KIT		19682		PT23164		PT23327	
H9234		PF9900		19691		PT23165		PT23328	
PT9235-MPG	PT9350-MPG	PF9902		19801		PT23170		PT23329	
PT9236-MPG		PF9909		19852		PT23171		PT23330	
PT9241		BF9926-O		19861		PT23173		PT23331	
PT9243		PA10013		19879		PT23175		PT23332	
PT9246		18000		19887		PT23177		PT23333	
PT9249		18001		19895		PT23180		PT23334	
PT9252		18003		19909		PT23183		PT23335	
PT9253-MPG		18005		19917		PT23188		PT23336	
PT9257		18006	18033	19925		PT23191		PT23337	
PT9259		18008	18022	19933		PT23192		PT23338-MPG	
PT9262-MPG		18011		19941		PT23194-MPG		PT23339-MPG	
PT9263		18012		19950	18032	PT23195-MPG		PT23340-MPG	
PT9265		18014		19968	18032	PT23196-MPG		PT23341-MPG	
PT9269		18015		19976		PT23198-MPG		PT23342-MPG	
PT9270		18016		19984		PT23199-MPG		PT23343-MPG	
PT9271		18017		19993		PT23204-MPG		PT23344-MPG	
PT9273		18018		19994		PT23205-MPG		PT23346-MPG	
PT9274		18019		19995		PT23208-MPG		PT23347-MPG	
PT9275		18020		19997		PT23210-MPG		PT23348-MPG	
PT9276		18021		19998	18010	PT23212-MPG		PT23349-MPG	
PT9280		18023		20001		PT23214-MPG		PT23350-MPG	
PT9281		18026		20009		PT23218-MPG		PT23351-MPG	
PT9284-MPG		18028		20041		PT23221-MPG		PT23352-MPG	
PT9285-MPG		18030		PT23004		PT23222-MPG		PT23353-MPG	
PT9292-MPG		18031		PT23008		PT23225-MPG		PT23354-MPG	
PT9294-MPG		18040		PT23012		PT23226-MPG		PT23355-MPG	
PT9295-MPG		18058		PT23013		PT23228-MPG		PT23359-MPG	
PT9298-MPG		18066	18155	PT23014		PT23230-MPG		PT23360-MPG	
PT9299-MPG		18074		PT23015		PT23233-MPG		PT23361-MPG	
PT9301-MPG	PT9359-MPG	18082		PT23019		PT23235-MPG		PT23362-MPG	
PT9302-MPG		18091		PT23021		PT23236-MPG		PT23364-MPG	
H9305		18112		PT23022		PT23238-MPG		PT23367-MPG	
PT9312-MPG		18121		PT23023		PT23243-MPG		PT23369-MPG	
PT9314-MPG		18147		PT23025		PT23249-MPG		PT23370-MPG	
PT9317-MPG	PT8975-MPG	18163		PT23027		PT23252-MPG		PT23372-MPG	
BT9319-MPG		18180	18025	PT23031-MPG		PT23255-MPG		PT23373-MPG	
BT9322		18201		PT23050-MPG		PT23256-MPG		PT23377-MPG	
BT9323		18210		PT23053-MPG		PT23257-MPG		PT23378-MPG	
BT9325		18228		PT23054-MPG		PT23258-MPG		PT23379-MPG	
PT9332		18253		PT23055-MPG		PT23259-MPG		PT23381-MPG	
PT9333		18254	18264	PT23056-MPG		PT23261-MPG		PT23382-MPG	
PT9334-MPG		18255	18265	PT23057-MPG		PT23262-MPG		PT23384-MPG	
PT9335-MPG		18256		PT23058-MPG		PT23263-MPG		PT23385-MPG	
PT9336		18257		PT23065-MPG		PT23265-MPG		PT23387-MPG	
PT9412-MPG		18258		PT23068-MPG		PT23268-MPG	H9001	PT23388-MPG	
PT9415		18261		PT23071-MPG		PT23269-MPG		PT23390-MPG	
BT9437		18262		PT23072-MPG		PT23270-MPG		PT23391-MPG	
PT9453-MPG		18266		PT23073-MPG		PT23271-MPG		PT23392-MPG	
PT9463		18269		PT23074-MPG		PT23274-MPG		PT23393-MPG	
PT9473		18270		PT23075-MPG		PT23275-MPG		PT23397-MPG	
PT9474		18273		PT23094-MPG		PT23276-MPG		PT23399-MPG	
PT9480-MPG		18274		PT23096-MPG		PT23278-MPG		PT23400-MPG	
PT9485-MPG		18275		PT23099-MPG		PT23280-MPG		PT23401-MPG	
PT9497-MPG		18277		PT23100-MPG		PT23283-MPG		PT23402-MPG	
PT9498-MPG		18278		PT23102-MPG		PT23284-MPG		PT23403-MPG	
PT9500-MPG		18281		PT23104-MPG		PT23288-MPG		PT23404-MPG	
PT9506		18283		PT23105-MPG		PT23289-MPG		PT23405-MPG	
PT9512		18284		PT23106-MPG		PT23293-MPG		PT23406-MPG	

\* These Part Numbers are also Obsolete.

## BALDWIN OBSOLETE PRODUCTS

OBSOLETE NUMBER	REPLACED BY	OBSOLETE NUMBER	REPLACED BY	OBSOLETE NUMBER	REPLACED BY	OBSOLETE NUMBER	REPLACED BY	OBSOLETE NUMBER	REPLACED BY
PT23408-MPG		OAS98008		<b>DAHL PRODUCTS</b>		200-20		1010-10x8DTA	
PT23409-MPG		OAS98011		65-W30		200-21AL		1010-10x8DTB	
PT23410-MPG		OAS98013		85-P		200-22		1010-10x8DTC	
PT23411-MPG		OAS98014		85-VK6x6		200-23		1010-10x8DTD	
PT23412-MPG		OAS98018		85-VK10x8		200-24		1010-10x10	
PT23413-MPG		OAS98021		85-VK10x10		200-25,26,27		1010-10x10DTB	
PT23415-MPG		OAS98025		85-VK12x10		200-30T		1010-12x10	
PT23417-MPG		OAS98026		85-VK12x12		200-32		1010-12x10DTB	
PT23418-MPG		OAS98027		100		200-33		1010-12x12	
PT23419-MPG		OAS98030		100-10		200-34		1010-12x12DTB	
PT23420-MPG		OAS98034		100-11		200-AL		1015-DDT	
PT23421-MPG		OAS98035		100-13		200-BP		1015-F	
PT23422-MPG		OAS98036		100-14		200-CUT		1020-6x4	
PT23423-MPG		OAS98037		100-15		200-DEPR KIT		1020-6x6	
PT23424-MPG		OAS98039		100-16		200-DGK		1020-10x8	
PT23425-MPG		OAS98040		100-17		200-HBP		1020-10x10	
PT23426-MPG		OAS98041		100-19		200-HN		1020-12x10	
PT23427-MPG		OAS98043		100-20		200-M		1020-12x12	
PT23428-MPG		OAS98044		100-21BP		200-M30		1028-F	
PT23429-MPG		OAS98046		100-21H		200-MBP		1030-4x4	
PT23430-MPG		OAS98047		100-21HBP		200-MMV30		1030-6x6	
PT23431-MPG		OAS98048		100-22		200-MPC		1030-8x8	
PT23432-MPG		OAS98049		100-23		200-SR		1030-10x10	
PT23433-MPG		OAS98051..... OAS98057		100-24		200-W		1030-12x12	
PT23434-MPG		OAS98052		100-25,26,27		300-14		1040-6x4	
PT23435-MPG		OAS98054		100-33		300-16		1040-6x4B	
PT23436-MPG		OAS98055..... OAS98010		100-35		300-35		1040-6x6	
PT23437-MPG		OAS98057		100-36		300-AL		1040-10x6	
PT23438-MPG		OAS99000		100-AL		300-BP		1040-10x8	
PT23439-MPG		OAS99002		100-BMK		300-DB		1040-10x12	
PT23440-MPG		OAS99003		100-BMKBP		300-DB W/O		1040-12x8	
PT23443-MPG		OAS99004		100-BMKH		300-DB5		1040-12x12	
PT23446-MPG		OAS99005		100-CUT		300-DB5 W/O		1063-BK1	
PT23448-MPG		OAS99007		100-DGK		300-DB5220		1063-BK2	
PT23452		OAS99009		100-H		300-DBA		1063-BK3	
PT23453		OAS99010		100-HBP		300-DBA5		1063-D	
PT23457		OAS99011		100-HBP		300-DBA220		1063-F	
PT23459		OAS99012		100-M		300-DHRAP5		1072-B	
PT23460		OAS99013		100-M30		300-DR		DEMO-100 MINI	
PT23462		OAS99015		100-MMV30		300-DR W/O		EA-002	
PT23465		OAS99016		100-MMVBP		300-DR5		EC-005	
PT23466..... PA4876		OAS99019		100-MPC		300-DR5 W/O		EC-112	
PT23469		OAS99021		100-W/O		300-DR220		EM-03D11	
PT23474		OAS99022		100-W/OBP		300-DR5220		EM-05D11	
PT23479		OAS99023		101-A		300-DRA		HH4	
PT23480		OAS99024		140 KIT		300-M		HH6	
PT23481		OAS99026		140-10		300-MBP		HH8	
PT23483-MPG		OAS99027		140-12		300-MF		HH10	
PT23484-MPG		OAS99030		140-25 KIT		300-MF3		HH12	
PT23485-MPG		OAS99031		143-6L KIT		300-MFV			
PT23486-MPG		OAS99032		143-6L9 KIT		300-MFV3			
PT23487-MPG		OAS99033		150-10		300-MM			
PT23488-MPG		OAS99036		150-14		300-MM30			
PT23497-MPG		OAS99037		150-15		300-MMV			
PT23498-MPG		OAS99039		150-16		300-MMV3			
PT23503-MPG		OAS99040		150-17		300-MMV3-30			
PT23504-MPG		OAS99041		150-22		300-MMV3BP			
PT23506-MPG		OAS99042		150-24		300-MMV30			
PT23511-MPG		OAS99043		150-32		300-MPC			
PT23512-MPG		OAS99044		150-35		300-SB			
PT23522-MPG		OAS99045		150-AL		300-SB5			
PT23524-MPG		OAS99046		150-BP		300-SB12V			
PT23527				150-HBP		300-SB22			
PT23528-MPG				150-MFV		300-SBBP			
PT23534				150-W		300-SR			
PA30097				186-11		300-W			
RS30241 KIT				186-12		500-15			
RS30289..... RS30220				186-21		500-BK1			
P40052..... PF40052				186-22		500-BP			
B40122				200-10P		500-MFVBP			
BF46013				200-11		500-MFVBP22			
BF46034..... BF46233				200-12		500-SBBP W/O			
PF46086				200-13		1010-6x4			
BF46095-O				200-14		1010-6x4DTD			
BF46124-O				200-16		1010-6x6			
BF46197				200-17		1010-6x6DTC			
OAS98004				200-18		1010-6x6DTD			
OAS98007				200-19A		1010-10x8			

\* These Part Numbers are also Obsolete.



# ABBREVIATIONS USED ANYWHERE IN OUR CATALOGS

<b>2WD</b>	2-Wheel Drive	<b>Etc.</b>	Et cetera (and so forth)	<b>L.H.</b>	Left Hand	<b>rpm</b>	Revolutions per Minute
<b>4WD</b>	4-Wheel Drive	<b>EUI</b>	Electronic Unit Injector	<b>LoPres.</b>	Low Pressure	<b>R.R.</b>	Railroad
<b>A. Gskt.</b>	Attached Gasket(s)	<b>Exc.</b>	Except	<b>LPG</b>	Liquefied Petroleum Gas	<b>RWD</b>	Rear Wheel Drive
<b>ABS</b>	Anti-Lock Braking System	<b>ExHiPres.</b>	Extra High Pressure	<b>LPH</b>	Liters per Hour	<b>S. Eng.</b>	Starter Engine
<b>AD</b>	Anti-Drainback Valve	<b>ExpHsg.</b>	Exposed Housing	<b>Ltd.</b>	Limited	<b>S. Fuel</b>	Secondary Fuel
<b>ADP</b>	Anti-Drainback Pipe	<b>ExpTank</b>	Expansion Tank	<b>M-F</b>	Massey Ferguson	<b>S. Pan</b>	Shallow Pan
<b>AirCond.</b>	Air Conditioned or Air Conditioner	<b>Ext.</b>	Extended	<b>MBP</b>	Medium Pressure By-Pass Valve (11-17 PSID)	<b>SCA</b>	Supplemental Coolant Additive
<b>Alum.</b>	Aluminum	<b>F</b>	Fahrenheit	<b>Mfg.</b>	Manufacturing	<b>SCR</b>	Selective Catalytic Reduction
<b>AMC</b>	American Motors	<b>F. Drive</b>	Final Drive	<b>Mfr.</b>	Manufacturer	<b>Sec.</b>	Secondary
<b>Amp</b>	Ampere	<b>F. Fuel</b>	Final Fuel	<b>MichFIPow.</b>	Michigan Fluid Power	<b>Sgl.</b>	Single
<b>App.</b>	Approved	<b>F. Gskt.</b>	Furnished Gasket(s)	<b>Min.</b>	Minimum Order Quantity	<b>SHBP</b>	Super High Pressure By-Pass Valve (30-45 PSID)
<b>Approx.</b>	Approximately	<b>FECV</b>	Front-End Check Valve	<b>mm</b>	Millimeter	<b>SHO</b>	Super High Output
<b>Arr.</b>	Arrangement	<b>F-F</b>	Full-Flow	<b>M-M</b>	Minneapolis-Moline	<b>SintBronze</b>	Sintered Bronze
<b>A.T.</b>	Automatic Transmission	<b>FFV</b>	Flex Fuel Vehicle	<b>MO</b>	Metering Orifice	<b>S/N</b>	Serial Number(s)
<b>ATAAC</b>	Air-to-Air Aftercooling	<b>FI</b>	Fuel Injection	<b>M.T.</b>	Manual Transmission	<b>SOHC</b>	Single Overhead Cam
<b>Attach.</b>	Attachment	<b>FidC/O</b>	Field Change-Over	<b>Mtd.</b>	Mounted	<b>SP</b>	Sensor Port
<b>AutoTrans.</b>	Automatic Transmission	<b>FidInst.</b>	Field Installation	<b>Mtr.</b>	Motor	<b>Spd.</b>	Speed
<b>Aux.</b>	Auxiliary	<b>FP</b>	Fill Port	<b>NPSF</b>	National Pipe Straight Fine	<b>Spec(s).</b>	Specification(s)
<b>AWD</b>	All Wheel Drive	<b>FRM</b>	Flame Retardant Media	<b>NPT</b>	National Pipe Thread	<b>SPI</b>	Sequential Port Injection
<b>Bbl.</b>	Barrel	<b>Ft.</b>	Foot	<b>N/R</b>	Not Required	<b>Sr.</b>	Senior
<b>BP</b>	By-Pass Valve (8-10 PSID)	<b>FWD</b>	Front Wheel Drive	<b>NS</b>	Non-Serviceable	<b>SSS</b>	Synchro Shuttle Shift
<b>B-P</b>	By-Pass	<b>FWS</b>	Fuel/Water Separator	<b>O. Air</b>	Outer Air	<b>Std.</b>	Standard
<b>BPS</b>	By-Pass Screen	<b>[G]</b>	Gasket	<b>O. Gskt.</b>	Optional Gasket(s)	<b>Steer.</b>	Steering
<b>BSP</b>	British Standard Pipe Thread	<b>Gal.</b>	Gallon(s)	<b>OBS</b>	Obsolete	<b>Sub.</b>	Substitute
<b>BSP-PL</b>	British Standard Pipe Parallel Thread	<b>GM, GMC</b>	General Motors Corporation	<b>O.D.</b>	Outside Diameter	<b>SuctLine</b>	Suction Line
<b>BTA PLUS</b>	Balanced Treatment Additive Plus	<b>gph</b>	Gallons per Hour	<b>OE</b>	Original Equipment	<b>Sys.</b>	System
<b>BTE</b>	Balanced Treatment for Ethylene Glycol Antifreeze	<b>gpm</b>	Gallons per Minute	<b>OEM</b>	Original Equipment Manufacturer	<b>TBA</b>	To Be Announced
<b>BTU</b>	British Thermal Unit	<b>Gskt.</b>	Gasket(s)	<b>OES</b>	Open Emission System	<b>TBI</b>	Throttle Bodied Injection
<b>C</b>	Celsius, Centigrade	<b>GVW</b>	Gross Vehicle Weight	<b>Off-Hwy</b>	Off-Highway	<b>Temp.</b>	Temperature
<b>Calif.</b>	California	<b>[H]</b>	Base or Housing Number	<b>OHC</b>	Overhead Cam	<b>Thd.</b>	Thread
<b>Carb.</b>	Carburetor, Carbureted	<b>HBP</b>	High Pressure By-Pass Valve (18-25 PSID)	<b>OHV</b>	Overhead Valve	<b>THM</b>	Turbo-Hydrumatic
<b>Cat</b>	Caterpillar	<b>HEUI</b>	Hydraulic Electronic Unit Injector	<b>Olds</b>	Oldsmobile	<b>TorqConv.</b>	Torque Converter
<b>cc</b>	Cubic Centimeters	<b>Hgt.</b>	Height	<b>Opt.</b>	Optional	<b>Trans.</b>	Transmission
<b>CCLS</b>	Closed Center Load Sensing	<b>Hi</b>	High	<b>oz.</b>	Ounce(s)	<b>Turbo</b>	Turbocharger, Turbocharged
<b>CES</b>	Closed Emission System	<b>HiPerf.</b>	High Performance	<b>P. Cab</b>	Pressurized Cab	<b>UK</b>	United Kingdom
<b>CFM</b>	Cubic Feet per Minute	<b>HiPres.</b>	High Pressure	<b>P. Fuel</b>	Primary Fuel	<b>UL, U.L.</b>	Underwriters Lab Listed
<b>CID</b>	Cubic Inch Displacement	<b>HLT</b>	High-Low Transmission	<b>Perf.</b>	Performance	<b>UNF</b>	Universal National Fine
<b>CLN&amp;R</b>	Clean & Reuse Present Filter	<b>HO</b>	High Output	<b>PCV</b>	Positive Crankcase Ventilation	<b>U.S.</b>	United States
<b>CNG</b>	Compressed Natural Gas Company	<b>HP</b>	Horsepower	<b>PEEC</b>	Programmable Electronic Engine Control	<b>U.S.C.G.</b>	U.S. Coast Guard Accepted
<b>COE</b>	Cab Over Engine	<b>Hsg.</b>	Housing	<b>Pkg.</b>	Package	<b>V</b>	Volt
<b>Comp.</b>	Compressor	<b>HVAC</b>	Heating, Ventilation and Air Conditioning	<b>PltD.</b>	Pleated	<b>VapDiv.</b>	Vapor Diverter
<b>Cont'd.</b>	Continued	<b>HvyDty.</b>	Heavy-Duty	<b>PowBrakes</b>	Power Brakes	<b>Veh.</b>	Vehicle
<b>Corp.</b>	Corporation	<b>Hyd.</b>	Hydraulic	<b>PowDr.</b>	Power Drive	<b>Vers.</b>	Version
<b>CPI</b>	Center Port Injection	<b>Hz</b>	Hertz	<b>PowQuad</b>	Power Quad	<b>VIN</b>	Vehicle Identification Number
<b>CSC</b>	Coolant System Cleaner	<b>I. Air</b>	Inner Air	<b>PowShift</b>	Power Shift	<b>VW</b>	Volkswagen
<b>Cu.</b>	Cubic	<b>I. Gskt.</b>	Integral Gasket(s)	<b>PowSteer.</b>	Power Steering	<b>w/</b>	With
<b>CVT</b>	Continuously Variable Transmission	<b>I.D.</b>	Inside Diameter	<b>Pri.</b>	Primary	<b>w/o</b>	Without
<b>Cyl.</b>	Cylinder	<b>IH, IHC</b>	International Harvester, International Navistar Inch(es)	<b>PRWD</b>	Power Rear Wheel Drive	<b>W.B.</b>	Wheel Base
<b>D. Pan</b>	Deep Pan	<b>In.</b>	Incorporated	<b>PS</b>	Integral Post Seal Gasket	<b>XHBP</b>	Extra High Pressure By-Pass Valve (50+ PSID)
<b>Dbl.</b>	Double	<b>Incl.</b>	Included	<b>PSI</b>	Pounds per Square Inch	<b>XP</b>	Extreme Performance
<b>DC</b>	Direct Current	<b>Ind.</b>	Industrial	<b>PSID</b>	Pounds per Square Inch Displacement	<b>Yd.</b>	Yard(s)
<b>DDA</b>	Detroit Diesel Allison	<b>Info</b>	Information	<b>PSR</b>	Post Seal Required		
<b>DEF</b>	Diesel Exhaust Fluid	<b>Int.</b>	International	<b>Pt.</b>	Pint		
<b>DI</b>	Direct Injection	<b>Int.</b>	International	<b>PTO</b>	Power Take-Off		
<b>Div.</b>	Division	<b>ISO</b>	Inside-Out Flow Direction	<b>PZEV</b>	Partial Zero Emissions Vehicle		
<b>DOHC</b>	Dual Overhead Cam	<b>IVT</b>	Infinitely Variable Transmission	<b>QR/SR</b>	Quad Range or Syncro Range		
<b>Don.</b>	Donaldson	<b>J.C.W.</b>	John Cooper Works	<b>Qt.</b>	Quart		
<b>ea.</b>	Each	<b>JD</b>	John Deere	<b>Qty.</b>	Quantity		
<b>EFI</b>	Electronic Fuel Injection	<b>JIC</b>	Joint Industry Conference	<b>RC</b>	Reinforced Centertube		
<b>EGR</b>	Exhaust Gas Recirculation	<b>Jr.</b>	Junior	<b>Recirc.</b>	Recirculation		
<b>EHSS</b>	Electro-Hydraulic Shuttle Shift	<b>KHD</b>	Klockner-Humboldt-Deutz	<b>Rect.</b>	Rectangular		
<b>Ele.</b>	Element	<b>Kw</b>	Kilowatt	<b>Res.</b>	Reservoir		
<b>Elec.</b>	Electric	<b>L</b>	Liters	<b>RetLine</b>	Return Line		
<b>E.M.D.</b>	Electro-Motive Division	<b>LBP</b>	Low Pressure By-Pass Valve (2-7 PSID)	<b>R.H.</b>	Right Hand		
<b>Eng(s).</b>	Engine(s)	<b>Lb(s).</b>	Pound(s)	<b>ROPS</b>	Roll Over Protection System		
<b>Equip.</b>	Equipment	<b>LGP</b>	Low Ground Pressure	<b>Rpl.</b>	Replaced, Replacement		



## 本公司目录中出现的缩写词

2WD..... 二轮驱动	F..... 华氏	Power	SHBP..... 超高压旁通阀(30-45 PSI)
4WD..... 四轮驱动	F. Drive..... 主减速器	Min..... 最低订购量	SHO..... 超高输出
A. Gskt..... 附加垫圈	F. Fuel..... 最终燃油	mm..... 毫米	SintBronze..... 粉末青铜
ABS..... 防抱死制动系统	F. Gskt..... 提供的垫圈	M-M..... Minneapolis-Moline	S/N..... 系列号
AD..... 防回流阀	FECV..... F 前端出油阀	MO..... 量孔	SOHC..... 单顶置凸轮轴
ADP..... 防回流管	F-F..... 全流式	MPI..... 多点燃油喷射	SP..... 传感器端口
AirCond..... 空调	FFV..... 灵活燃油车辆	M.T..... 手动变速器	Spd..... 速度
Alum..... 铝	FI..... 燃油喷射	Mtd..... 安装的	Spec(s)..... 规格
AMC..... 美国汽车公司	FidC/O..... 现场转换	Mtr..... 马达	SPI..... 顺序端口喷射
Amp..... 安培	FidInst..... 现场安装	NPSF..... National Pipe Straight Fine	Sr..... 高级资深
App..... 批准	FP..... 加油孔	NPT..... 国家管材螺纹规范	SSS..... 同步移行换挡
Approx..... 大约	FRM..... 阻燃剂	N/R..... 不要求的	Std..... 标准
Arr..... 安排	Ft..... 呎	I/S..... 不可修复的	Steer..... 转向
A.T..... 自动变速器	FWD..... 前轮驱动	O. Air..... 外部空气	Sub..... 代替, 取代
ATAAC..... 增压中冷	FWS..... 燃油/水分离器	O. Gskt..... 可选垫圈	SuctLine..... 进(吸)气管道
Attach..... 附件	G..... 垫圈	OBS..... 过时	TBA..... 待宣布
AutoTrans..... 自动变速器	Gal..... 加仑	O.D..... 外径	TBI..... 节气体喷射
Aux..... 辅助的, 辅机	GM, GMC..... 通用汽车公司	OE..... 原始设备	Temp..... 温度
AWD..... 全轮驱动	gph..... 每小时加仑	OEM..... 原车设备生产厂	Thd..... 螺纹
Bbl..... 桶	gpm..... 每分钟加仑	OES..... 开放式排放系统	THM..... 涡轮增压和液压自动变速
BP..... 旁通阀(8-10 PSI)	Gskt..... 垫圈	Off-Hwy..... 越野	TorqConv..... 变矩器
B-P..... 旁通	GVW..... 车辆最大总质量, 总车重	OHC..... 顶置凸轮轴	TPI..... 顺序多点燃油喷射
BPS..... 旁通滤网	H..... 底盘或外壳编号	OHV..... 顶置式气门	Trans..... 变速器, 传动
BSP..... 英国标准管材螺纹	HBP..... 高压旁通阀(18-25 PSI)	Olds..... Oldsmobile	Turbo..... 涡轮增压器, 涡轮增压的
BSP-PL..... 英国标准管材平行螺纹	HEUI..... 液压电子控制泵-喷嘴	Opt..... 可选, 选项	UK..... 英国
BTA PLUS..... 增效平衡处理添加剂	Hi..... 高	oz..... 盎司	UL, U.L..... 安全检测实验室 (美国) 登记
BTE..... 乙二醇防冻剂平衡处理	HiPerf..... 高性能	P. Cab..... 密封驾驶室	UNF..... Universal National Fine
BTU..... 英国热量单位	HiPres..... 高压	P. Fuel..... 主要燃料	U.S..... 美国
C..... 摄氏, 摄氏度	HLT..... 双(高/低)传动	PCV..... 曲轴箱强制通风	U.S.C.G..... 美国海岸警卫队接受
Calif..... 加利福尼亚	HO..... 高输出	PEEC..... 编程电子引擎控制	V..... 伏, 伏特
Carb..... 化油器, 汽化的	HP..... 马力	PFI..... 程控燃油喷射	VapDiv..... 蒸汽分流器
Cat..... 卡特彼勒	Hsg..... 外壳	Pkg..... 包, 成套	VIN..... 车辆识别代号
cc..... 立方厘米	HvyDty..... 重型	Pld..... 边的	VV..... 可变喉管
CES..... 闭路排放系统	Hyd..... 液压	PowBrakes..... 助力制动, 动力刹车	VW..... 大众牌汽车
CFI..... 中央燃油喷射	I. Air..... 内部空气	PowDr..... 动力驱动	w/..... 带有...
CFM..... 每分钟立方呎	I. Gskt..... 整体式垫圈	PowQuad..... PowerQuad	w/o..... 不带有...
CID..... 立方吋排量	I.D..... 内径	PowShift..... 传动轴, 动力换挡	W.B..... 轴距
Cin&R..... 清洁后重新使用	IH, IHC..... International Harvester, International Navistar	PowSteer..... 动力转向	XHBP..... 超高压旁通阀(50+ PSI)
Co..... 公司	In..... 吋	Pri..... 主要的	Yd..... 码
COE..... 平头汽车驾驶室	Inc..... 公司	PRWD..... 动力后轮驱动	
Comp..... 压缩机	Incl..... 包括	PS..... 整体式端口密封垫圈	
Cont'd..... 续	Ind..... 工业	PSI..... 每平方吋磅	
Corp..... 公司	Info..... 信息, 资料	PSID..... 每平方英寸排量磅	
CPI..... 中央端口喷射	Int..... 国际	PSR..... 要求端口密封: 必须在端口安装 松弛O型环以求密封	
CSC..... 冷却系统清洁剂	ISO..... 内-外流方向	Pt..... 品脱	
Cu..... 立方	IVT..... 无限变速传动	PTO..... 取力器, 动力输出装置	
Cyl..... 汽缸	J.C.W..... John Cooper Works	PZEV..... 部分零排放车辆	
D. Pan..... 深油盘	JD..... John Deere	QR/SR..... Quad Range or Syncro Range	
Dbi..... 双	JIC..... 联合工业会议	Qt..... 夸特	
DC..... 直流电	Jr..... 之子	Qty..... 数量	
DDA..... Detroit Diesel Allison	KHD..... Klockner-Humboldt-Deutz	RC..... 强化中央脊梁管	
DI..... 直接喷射	Kw..... 千瓦	Recirc..... 再循环	
Div..... 部门	L..... 公升	Rect..... 矩形	
DOHC..... 双顶置凸轮轴	LBP..... 低压旁通阀(2-7 PSI)	Res..... 储罐	
Don..... 唐纳逊(人名)	Lb(s)..... 磅	RetLine..... 回流管路	
ea..... 每个	LGP..... 低对地压力	R.H..... 右手, 右方	
EFI..... 电子燃油喷射	L.H..... 左手, 左方	ROPS..... 滚翻防护系统	
EGR..... 废气再循环	LoPres..... 低压	Rpl..... 更换, 替换	
EHSS..... 电液移行变速器	LPG..... 液化石油气	rpm..... 每分钟转数	
Ele..... 构件, 元件	LPH..... 每小时公升	R.R..... 铁路	
Elec..... 电器, 电动	Ltd..... 有限	RWD..... 后轮驱动	
E.M.D..... 电动汽车部	M-F..... Massey Ferguson	S. Eng..... 起动机引擎	
Eng(s)..... 引擎	MBP..... 中压旁通阀(11-17 PSI)	S. Fuel..... 次要燃油	
Equip..... 设备	Mfg..... 制造	S. Pan..... 浅油盘	
Etc..... 等等	MFI..... 多点燃油喷射	Sec..... 选择性催化减少	
EUI..... 电子控制泵-喷嘴	Mfr..... 制造厂(商)	SCR..... 次要的, 二次的	
Exc..... 例外, 除了...	MichFIPow..... Michigan Fluid	SFI..... 顺序燃油喷射	
ExHiPres..... 超高压		Sgl..... 单	
ExpHsg..... 暴露外壳			
ExpTank..... 膨胀容箱			
Ext..... 扩展的, 伸长的			

**ABREVIATIONS UTILISEES DANS NOS CATALOGUES**

<b>2WD</b>	2 Roues motrices	<b>Don.</b>	Donaldson	<b>ISO</b>	Direction d'écoulement intérieur vers extérieur	<b>Pt.</b>	Pinte
<b>4WD</b>	4 Roues motrices	<b>ea.</b>	Chacun	<b>IVT</b>	Transmission à variation infinie	<b>PTO</b>	Prise de force
<b>A. Gskt.</b>	Joint(s) attaché(s)	<b>EFI</b>	Injection de carburant électronique	<b>J.C.W.</b>	John Cooper Works	<b>PZEV</b>	Véhicule à émissions quasi-nulles
<b>ABS</b>	système de freinage antibloquant	<b>EGR</b>	Recirculation des gaz d'échappement	<b>JD</b>	John Deere	<b>QR/SR</b>	Gamme quad ou gamme Syncro
<b>AD</b>	Clapet anti-retour	<b>EHSS</b>	Transmission électro-hydraulique automatique	<b>JIC</b>	Joint Industry Conference	<b>Qt.</b>	Quart
<b>ADP</b>	Conduit anti-retour	<b>Ele.</b>	Elément	<b>Jr.</b>	Junior	<b>Qty.</b>	Quantité
<b>AirCond.</b>	Avec air conditionné ou climatiseur	<b>Elec.</b>	Electrique	<b>KHD</b>	Klockner-Humboldt-Deutz	<b>RC</b>	Tube central renforcé
<b>Alum.</b>	Aluminium	<b>E.M.D.</b>	Electro-Motive Division	<b>Kw</b>	Kilowatt, kW	<b>Recirc.</b>	Recirculation
<b>AMC</b>	American Motors	<b>Eng(s).</b>	Moteur(s)	<b>L</b>	Litres	<b>Rect.</b>	De forme rectangulaire
<b>Amp</b>	Ampère	<b>Equip.</b>	Equipement	<b>LBP</b>	Vanne de dérivation basse pression (14 à 20 kPa)	<b>Res.</b>	Réservoir
<b>App.</b>	Approuvé	<b>Etc.</b>	Et cetera	<b>Lb(s).</b>	Livre(s)	<b>RetLine</b>	Conduite de retour
<b>Approx.</b>	Environ	<b>EUI</b>	Injecteur électronique excepté	<b>L.H.</b>	Pression au sol faible Gauche	<b>R.H.</b>	Droit(e)
<b>Arr.</b>	Arrangement	<b>Exc.</b>	Pression très élevée	<b>LoPres.</b>	Basse Pression	<b>ROPS</b>	Système de protection en cas de renversement
<b>A.T.</b>	Boîte de vitesses automatique	<b>ExHiPres.</b>	Carter exposé	<b>LPG</b>	Gaz de pétrole liquéfié	<b>Rpl.</b>	Remplacé, Remplacement
<b>ATAAC</b>	Refroidissement secondaire Air-Air	<b>ExpTank</b>	Vase d'expansion	<b>LPH</b>	Litres par heure	<b>rpm</b>	Tours par minute, tr/min
<b>Attach.</b>	Accessoire	<b>Ext.</b>	Prolongé	<b>Ltd.</b>	Limited, Limité	<b>R.R.</b>	Train, ferroviaire
<b>AutoTrans.</b>	Boîte de vitesses automatique	<b>F</b>	Fahrenheit	<b>M-F</b>	Massey Ferguson	<b>RWD</b>	Traction arrière
<b>Aux.</b>	Auxiliaire	<b>F Drive</b>	Entraînement final	<b>MBP</b>	Valve de dérivation moyenne pression (76 à 117 kPa)	<b>S. Eng.</b>	Moteur de démarrage
<b>AWD</b>	Toutes roues motrices	<b>F. Fuel</b>	Carburant final	<b>Mfg.</b>	Fabrication	<b>S. Fuel</b>	Carburant secondaire
<b>Bbl.</b>	Corps	<b>F. Gskt.</b>	Joint(s) fourni(s)	<b>Mfr.</b>	Fabricant	<b>S. Pan</b>	Bac peu profond
<b>BP</b>	Vanne de dérivation (55 à 69 kPa)	<b>FECV</b>	Clapet antiretour d'extrémité avant	<b>MichFIPow.</b>	Michigan Fluid Power	<b>SCA</b>	Additif supplémentaire
<b>B-P</b>	Dérivation	<b>F-F</b>	A plein débit	<b>Min.</b>	Quantité minimum de la commande	<b>SCR</b>	Réduction sélective catalytique
<b>BPS</b>	Crépine de dérivation	<b>FFV</b>	Véhicule polycarburant	<b>mm</b>	Millimètre	<b>Sec.</b>	Secondaire
<b>BSP</b>	Normes britanniques de tuyaux	<b>FI</b>	Injection de carburant	<b>M-M</b>	Minneapolis-Moline	<b>Sgl.</b>	Unique
<b>BSP-PL</b>	Filetage droit de tuyauterie aux normes britanniques	<b>FIdC/O</b>	Changement sur le chantier	<b>MO</b>	Orifice de mesure	<b>SHBP</b>	Vanne de dérivation super haute pression (207 à 276 kPa)
<b>BTA PLUS</b>	Additif de traitement équilibré Plus	<b>FIdInst.</b>	Montage sur le chantier	<b>M.T.</b>	Boîte de vitesse manuelle	<b>SHO</b>	Rendement super élevé
<b>BTE</b>	Traitement équilibré pour antigel éthylène glycol	<b>FRM</b>	Orifice de remplissage	<b>Mtd.</b>	Monté	<b>SintBronze</b>	Bronze fritté
<b>BTU</b>	British Thermal Unit	<b>Ft.</b>	Média ignifuge	<b>Mtr.</b>	Moteur	<b>S/N</b>	Numéro de série
<b>C</b>	Celsius	<b>FWD</b>	Traction avant	<b>NPSF</b>	Filetage tuyauterie NPT droit fin	<b>SOHC</b>	à cames en tête unique
<b>Calif.</b>	Californie	<b>FWS</b>	Séparateur carburant / eau	<b>NPT</b>	National Pipe Thread	<b>SP</b>	Orifice de capteur
<b>Carb.</b>	Carburateur, avec carburateur	<b>[G]</b>	Joint	<b>N/R</b>	Non requis	<b>Spd.</b>	Vitesse
<b>Cat</b>	Caterpillar	<b>Gal.</b>	Gallon	<b>NS</b>	Non remplaçable	<b>Spec(s).</b>	Spécification(s)
<b>cc</b>	Centimètres cubes	<b>GM, GMC</b>	General Motors Corporation	<b>O. Air</b>	Air extérieur	<b>SPI</b>	Injection séquentielle par orifice
<b>CCLS</b>	Détection de charge à fermeture centrale	<b>gph</b>	Gallons par heure	<b>O. Gskt.</b>	Joint(s) en option	<b>Sr.</b>	Senior
<b>CES</b>	Système fermé d'émissions	<b>gpm</b>	Gallons par minute	<b>OBS</b>	Plus en usage	<b>SSS</b>	Transmission synchro
<b>CFM</b>	Pied cube par minute	<b>Gskt.</b>	Joint(s)	<b>O.D.</b>	Diamètre extérieur	<b>Std.</b>	Standard
<b>CID</b>	Cylindrée, en pouces cubes	<b>GVW</b>	Poids Total Brut	<b>OE</b>	Equipement d'origine	<b>Steer.</b>	Direction
<b>CLN&amp;R</b>	Nettoyer et ré-utiliser le filtre existant	<b>[H]</b>	Numéro de boîtier (Notre remplacement n'est que le filtre)	<b>OEM</b>	Fabricant d'équipement d'origine	<b>Sub.</b>	Remplacement
<b>CNG</b>	Gaz naturel comprimé	<b>HBP</b>	Vanne de dérivation haute pression (124 à 138 kPa)	<b>OES</b>	Système ouvert d'émissions	<b>SuctLine</b>	Conduite d'aspiration
<b>Co.</b>	Compagnie	<b>HEUI</b>	Injecteur électronique unité hydraulique	<b>Off-Hwy</b>	Hors route, de chantier	<b>Sys.</b>	Système
<b>COE</b>	Cabine avancée	<b>Hgt.</b>	Height	<b>OHC</b>	Arbre à cames en tête	<b>TBA</b>	À déterminer
<b>Comp.</b>	Compresseur	<b>Hi</b>	Haut	<b>OHV</b>	Soupapes en tête	<b>TBI</b>	injection à étranglement
<b>Cont'd.</b>	A suivre, suite	<b>HiPerf.</b>	Haute performance	<b>Olds</b>	Oldsmobile	<b>Temp.</b>	Température
<b>Corp.</b>	Corporation	<b>HiPres.</b>	Pression élevée	<b>Opt.</b>	En option	<b>Thd.</b>	Pas de vis
<b>CPI</b>	Injection d'orifice centrale	<b>HLT</b>	Boîte de vitesses hautes-basses	<b>oz.</b>	Once	<b>THM</b>	Turbo-Hydratmatique
<b>CSC</b>	Produit de nettoyage de circuit de refroidissement	<b>HO</b>	Puissance élevée	<b>P. Cab</b>	Cabine pressurisée	<b>TorqConv.</b>	Convertisseur de couple
<b>Cu.</b>	cuve	<b>HP</b>	Puissance	<b>P. Fuel</b>	Carburant primaire	<b>Trans.</b>	Transmission, boîte de vitesses
<b>CVT</b>	Transmission à variation continue	<b>Hsg.</b>	Carter	<b>PCV</b>	Réaspiration des gaz du carter	<b>Turbo</b>	Turbo-compresseur
<b>Cyl.</b>	Cylindre	<b>HVAC</b>	Chauffage, ventilation et conditionnement d'air	<b>PEEC</b>	Contrôleur moteur électronique programmable	<b>UK</b>	Royaume-Uni
<b>D. Pan</b>	Cuvette profonde	<b>HvyDty.</b>	Service sévère	<b>Perf.</b>	Performance	<b>UL, U.L.</b>	Homologué Underwriters Lab
<b>DbI.</b>	Double	<b>Hyd.</b>	Hydraulique	<b>Pkg.</b>	Paquet	<b>UNF</b>	Universal National Fine
<b>DC</b>	Courant continu	<b>HZ</b>	Hertz	<b>Pitd.</b>	Plissé	<b>U.S.</b>	Etats-Unis
<b>DDA</b>	Detroit Diesel Allison	<b>I. Air</b>	Air interne (sécurité)	<b>PowBrakes</b>	Freins assistés	<b>U.S.C.G.</b>	Accepté par U.S. Coast Guard, Garde Côtière Américaine
<b>DEF</b>	Fluide d'échappement des diesels	<b>I. Gskt.</b>	Joint intégral	<b>PowDr.</b>	Motorisation	<b>V</b>	Volt
<b>DI</b>	Injection Directe	<b>I.D.</b>	Diamètre interne	<b>PowQuad</b>	Power Quad	<b>VapDiv.</b>	Dérivation de vapeur
<b>Div.</b>	Division	<b>IH, IHC</b>	International Harvester, International Navistar	<b>PowShift</b>	Servo commande des vitesses	<b>Veh.</b>	Véhicule
<b>DOHC</b>	Double arbre à cames en tête	<b>In.</b>	Pouce	<b>Pri.</b>	Direction assistée Primaire, principal	<b>Vers.</b>	Version
		<b>Inc.</b>	Incorporated, incorporé	<b>PRWD</b>	Roue motrice arrière	<b>VIN</b>	Numéro d'identification du véhicule
		<b>Incl.</b>	Inclus, compris	<b>PS</b>	Joint intégral de montant	<b>VW</b>	Volkswagen
		<b>Ind.</b>	Industriel	<b>PSID</b>	Livres par pouce carré	<b>w/</b>	Avec
		<b>Info</b>	Renseignements	<b>PSR</b>	Joint de montant nécessaire	<b>w/o</b>	Sans
		<b>Int.</b>	International			<b>W.B.</b>	Empatement
						<b>XHBP</b>	Vanne de dérivation extra haute pression (plus de 345 kPa)
						<b>XP</b>	Ultra-performant
						<b>Yd.</b>	Yard

## ABKÜRZUNGEN, DIE IN UNSEREM KATALOG VERWENDET WERDEN

2WD.....2-Rad-Antrieb	<b>Elec.</b> .....Elektrik	<b>L</b> .....Liter	<b>RetLine</b> .....Rückfuhrleitung
4WD.....4-Rad-Antrieb	<b>E.M.D.</b> .....Electro-Motive Division	<b>LBP</b> .....Niederdruck-Bypass-Ventil (2-7 PSID)	<b>R.H.</b> .....rechts
<b>A. Gskt.</b> .....beigefügte Dichtung(en)	<b>Eng.</b> .....Motor	<b>Lb(s)</b> .....Pound(s)	<b>ROPS</b> .....Überrollkäfig
<b>ABS</b> .....Antiblockiersystem	<b>Equip.</b> .....Ausrüstung	<b>LGP</b> .....geringer Bodendruck	<b>Rpl.</b> .....ersetzt, Austausch
<b>AD</b> .....Rücklaufsperrventil	<b>Etc.</b> .....usw.	<b>L.H.</b> .....links	<b>rpm</b> .....UPM
<b>ADP</b> .....Rücklaufsperrrohr	<b>EUI</b> .....elektronische Einspritzeinheit	<b>LoPres.</b> .....Niedrigdruck	<b>R.R.</b> .....Eisenbahn
<b>AirCond.</b> .....Klimaanlage	<b>Exc.</b> .....außer	<b>LPG</b> .....Flüssig-Petroleumgas	<b>RWD</b> .....Hinterradantrieb
<b>Alum.</b> .....Aluminium	<b>ExHiPres.</b> .....sehr hoher Druck	<b>LPH</b> .....Liter pro Std.	
<b>AMC</b> .....American Motors	<b>ExpHsg.</b> .....offenes Gehäuse	<b>Ltd.</b> .....begrenzt	
<b>Amp</b> .....Ampere	<b>ExpTank</b> .....Ausdehnungstank		<b>S. Eng.</b> .....Anlaßmotor
<b>App</b> .....zugelassen	<b>Ext.</b> .....erweitert		<b>S. Fuel</b> .....sekundäres Brennstoffsystem
<b>Approx.</b> .....ungefähr	<b>F</b> .....Fahrenheit	<b>M-F</b> .....Massey Ferguson	<b>S. Pan</b> .....Flache Wanne
<b>Arr.</b> .....Anordnung	<b>F. Drive</b> .....Endantrieb	<b>MBP</b> .....Bypass-Ventil für mittelhohen Druck (11-17 PSID)	<b>SCR</b> .....Selektive katalytische Reduktion
<b>A.T.</b> .....Automobilgetriebe	<b>F. Fuel</b> .....Endbrennstoff	<b>Mfg.</b> .....Herstellung	<b>Sec.</b> .....sekundär
<b>ATAAC</b> .....Luft-Luft-Nachkühlung	<b>F. Gskt.</b> .....mit Dichtung ausgestattet	<b>MFI</b> .....Saugrohreinnspritzung	<b>SFI</b> .....sequentielle Kraftstoffeinspritzung
<b>Attach.</b> .....Befestigung	<b>FECV</b> .....vorderes Rückschlagventil	<b>Mfr.</b> .....Hersteller	
<b>AutoTrans.</b> .....automatisches Getriebe	<b>F-F</b> .....Hauptstrom	<b>MichFIPOw.</b> .....Michigan Fluid Power	<b>Sgl.</b> .....einzel
<b>Aux</b> .....Zusatz	<b>FFV</b> .....Mehrkraftstoff-Fahrzeug	<b>Min.</b> .....Mindestbestellmenge	<b>SHBP</b> .....Extremdruck-Bypass-Ventil (30-45 PSID)
<b>AWD</b> .....Allradantrieb	<b>FI</b> .....Einspritzung	<b>mm</b> .....Millimeter	<b>SHO</b> .....Super hohe Leistung
	<b>FIdC/O</b> .....Feldwechsel	<b>M-M</b> .....Minneapolis-Moline	<b>SintBronze</b> .....Sinterbronze
	<b>FIdInst.</b> .....Feldeinbau	<b>MO</b> .....kalibrierte Bohrung	<b>S/N</b> .....Seriennummer(n)
	<b>FP</b> .....Füllanschluß	<b>MPI</b> .....Einlasskanaleinspritzung	<b>SOHC</b> .....eine obenliegende Nockenwelle
	<b>FRM</b> .....Schwer entflammbares Filtermedium	<b>M.T.</b> .....Schaltgetriebe	<b>SP</b> .....Fühleranschluß
	<b>Ft.</b> .....Fuß (Foot)	<b>Mtd.</b> .....befestigt	<b>Spd.</b> .....Geschwindigkeit
	<b>FWD</b> .....Vorderradantrieb	<b>Mtr.</b> .....Motor	<b>Spec(s)</b> .....Spezifikation
	<b>FWS</b> .....Kraftstoff-Wasserabscheider		<b>SPI</b> .....sequentielle Kraftstoffeinspritzung
		<b>NPSF</b> .....US-Rohrgewindenorm NPSF	<b>Sr.</b> .....Senior
	<b>G</b> .....Dichtung	<b>NPT</b> .....NPT-Gewinde	<b>SSS</b> .....Synchrongetriebe- Wendeschaltung
	<b>Gal.</b> .....Gallone	<b>N/R</b> .....Nicht benötigt	
	<b>GM, GMC</b> .....General Motors Corporation	<b>N/S</b> .....Nicht wartbar	
	<b>gph</b> .....Gallonen pro Std.	<b>O. Air</b> .....äußere Luft	
	<b>gpm</b> .....Gallonen pro Min.	<b>O. Gskt.</b> .....zusätzliche Dichtung(en)	
	<b>Gskt.</b> .....Dichtung(en)	<b>OBS</b> .....Veraltet	
	<b>GVW</b> .....Brutto Fahrzeug Gewicht	<b>O.D.</b> .....äußerer Durchmesser	
		<b>OE</b> .....Originalausstattung	
		<b>OEM</b> .....Erstausrüster	
		<b>OES</b> .....offenes Emissionssystem	
	<b>H</b> .....Gehäusenummer (unser Ersatz ist nur der Einsatz)	<b>Off-Hwy</b> .....Gelände	
	<b>HBP</b> .....Hochdruck-Bypass-Ventil (18-25 PSID)	<b>OHV</b> .....obenliegende Nockenwelle	
	<b>HEUI</b> .....hydraulisch-elektronische Einspritzeinheit	<b>OHV</b> .....hängende Ventile	
		<b>Olds</b> .....Oldsmobile	
	<b>Hi</b> .....Hoch	<b>Opt.</b> .....wahlweise	
	<b>HiPerf.</b> .....Hochleistung	<b>oz</b> .....Unze	
	<b>HiPres.</b> .....Hochdruck		<b>P. Cab</b> .....Fahrerhaus unter Druck
	<b>HLT</b> .....Getriebe mit zusätzlicher Geländeübersetzung		<b>P. Fuel</b> .....Primär-Brennstoffsystem
	<b>HO</b> .....hohe Leistung		<b>PCV</b> .....positive Kurbelgehäuseentlüftung
	<b>HP</b> .....PS		<b>PEEC</b> .....programmierbare elektronische Motorsteuerung
	<b>Hsg.</b> .....Gehäuse		<b>PFI</b> .....programmierte Kraftstoffeinspritzung
	<b>HvyDty.</b> .....hohe Beanspruchung		<b>Pkg.</b> .....Packung
	<b>Hyd.</b> .....Hydraulik		<b>Pitd.</b> .....gefaltet
	<b>Hz</b> .....Hertz		<b>PowBrakes</b> .....Bremskraftverstärker
			<b>PowDr.</b> .....Kraftantrieb
	<b>I. Air</b> .....innere (Sicherheits-) Luft		<b>PowShift</b> .....Lastschaltgetriebe
	<b>I. Gskt.</b> .....Integraldichtung(en)		<b>PowSteer.</b> .....Servolenkung
	<b>I.D.</b> .....innerer Durchmesser		<b>Pri.</b> .....primär
	<b>IH, IHC</b> .....International Harvester, International Navistar		<b>PRWD</b> .....Hinterrad-Kraftantrieb
	<b>In.</b> .....Inch (Zoll)		<b>PS</b> .....Dichtung mit integrierter Stütze
	<b>Inc.</b> .....eingebaut		<b>PSID</b> .....Pounds pro Quadratzoll
	<b>Incl.</b> .....beinhaltet		<b>PSR</b> .....Dichtung mit Stütze erforderlich
	<b>Ind.</b> .....industriell		<b>Pt</b> .....Pint
	<b>Info</b> .....Information		<b>PTO</b> .....Zapfwellenantrieb
	<b>Int.</b> .....international		<b>PZEV</b> .....Partial Zero Emissions Vehicle (US-Standard für abgasarme Fahrzeuge)
	<b>ISO</b> .....Strömungsrichtung von innen nach Außen		
	<b>IVT</b> .....Stufenloses Getriebe		<b>QR/SR</b> .....Allradbetrieb oder Synchromtrieb
			<b>Qt.</b> .....Viertel Gallone
	<b>J.C.W.</b> .....John Cooper Works		<b>Qty.</b> .....Anzahl
	<b>JD</b> .....John Deere		
	<b>JIC</b> .....Joint Industry Conference		
	<b>Jr.</b> .....Junior		
			<b>RC</b> .....Verstärktes Mittelrohr
	<b>KHD</b> .....Klöckner-Humboldt-Deutz		<b>Recirc.</b> .....Rezirkulation
	<b>Kw</b> .....Kilowatt		<b>Rect.</b> .....Rechteckig
			<b>Res.</b> .....Behälter

**ABBREVIAZIONI USATE NEL NOSTRO CATALOGO**

<b>2WD</b> ..... Trazione su 2 ruote	<b>E.M.D.</b> ..... Electro-Motive Division	<b>L.H.</b> ..... Sinistra	<b>Rect.</b> ..... Forma rettangolare
<b>4WD</b> ..... Trazione integrale	<b>Eng(s)</b> ..... Motore/i	<b>LoPres.</b> ..... Bassa pressione	<b>Res.</b> ..... Serbatoio
<b>A. Gskt.</b> ..... Guarnizioni incluse	<b>Equip.</b> ..... Attrezzatura	<b>LPG</b> ..... Gasolio liquido	<b>RetLine</b> ..... Ritorno
<b>ABS</b> ..... Sistema di frenata antibloccaggio (ABS)	<b>Etc.</b> ..... Eccetera	<b>LPH</b> ..... Litri all'ora	<b>R.H.</b> ..... Destra
<b>AD</b> ..... Valvola di non ritorno	<b>EUI</b> ..... Iniettore unità elettronica	<b>Ltd.</b> ..... Società a responsabilità limitata	<b>ROPS</b> ..... Roll Over Protection System
<b>ADP</b> ..... Tubatura di non ritorno	<b>Exc.</b> ..... Eccetto	<b>M-F</b> ..... Massey Ferguson	<b>Rpl.</b> ..... Sostituito, sostituzione
<b>AirCond.</b> ..... Ad aria condizionata oppure Condizionatore dell'aria	<b>ExHiPres.</b> ..... Pressione altissima	<b>MBP</b> ..... Valvola di by-pass a media pressione (11-17 PSID)	<b>rpm</b> ..... Giri al minuto
<b>Alum.</b> ..... Alluminio	<b>ExpHsg.</b> ..... Alloggiamento esposto	<b>Mfg</b> ..... Produzione	<b>R.R.</b> ..... Linea ferroviaria
<b>AMC</b> ..... American Motors	<b>Ext.</b> ..... Esteso	<b>MFI</b> ..... Iniezione carburante a più porte	<b>RWD</b> ..... Trazione su ruote posteriori
<b>Amp.</b> ..... Ampere	<b>F</b> ..... Fahrenheit	<b>Mfr.</b> ..... Produttore	<b>S. Eng.</b> ..... Motore avviatore
<b>App.</b> ..... Approvato	<b>F. Drive</b> ..... Coppia al ponte	<b>MichFlIPow.</b> ..... Michigan Fluid Power	<b>S. Fuel</b> ..... Carburante secondario
<b>Apprx.</b> ..... Circa	<b>F. Fuel</b> ..... Carburante finale	<b>Min.</b> ..... Ordine minimo	<b>S. Pan.</b> ..... Vaschetta poco profonda
<b>Attach.</b> ..... Disposizione	<b>F. Gskt.</b> ..... Guarnizioni fornite	<b>mm</b> ..... Millimetro	<b>SCR</b> ..... Riduzione catalitica selettiva
<b>A.T.</b> ..... Trasmissione automatica	<b>FECV</b> ..... Valvola di ritegno di testa	<b>M-M</b> ..... Minneapolis-Moline	<b>Sec.</b> ..... Secondario
<b>ATAAC</b> ..... Postrefrigerazione aria-aria	<b>F-F</b> ..... Flusso totale	<b>MO</b> ..... Orifizio dosatore	<b>SFI</b> ..... Iniezione sequenziale di carburante
<b>Attach.</b> ..... Accessorio	<b>FFV</b> ..... Flex Fuel Vehicle	<b>MPI</b> ..... Sistema ad iniezione multi-point	<b>Sgl.</b> ..... Singolo
<b>AutoTrans.</b> ..... Trasmissione automatica	<b>FI</b> ..... Iniezione del carburante	<b>M.T.</b> ..... Trasmissione manuale	<b>SHBP</b> ..... Valvola di by-pass a pressione molto alta (30-45 PSID)
<b>Aux.</b> ..... Ausiliario	<b>FidC/O</b> ..... Cambiamento di campo	<b>Mtd.</b> ..... Montato	<b>SHO</b> ..... Potenza molto elevata
<b>AWD</b> ..... Trazione integrale	<b>FidInst.</b> ..... Installazione campo	<b>Mtr.</b> ..... Motore	<b>SintBronze</b> ..... Bronzo sinterizzato
<b>Bbl.</b> ..... Cilindro	<b>FP</b> ..... Porta di riempimento	<b>NPSF</b> ..... Filettatura per tubi nazionale dritta fine	<b>S/N</b> ..... Numero di serie
<b>BP</b> ..... Valvola di bypass (8-10 PSID)	<b>FRM</b> ..... Mezzi antifiama	<b>NPT</b> ..... Filettatura passo gas nazionale	<b>SOHC</b> ..... Singolo albero a camma in testa
<b>B-P</b> ..... Schermo di bypass	<b>Ft.</b> ..... Piede	<b>NR</b> ..... Non richiesto	<b>SP</b> ..... Porta sensore
<b>BSP</b> ..... Filettatura passo gas	<b>FWD</b> ..... Trazione anteriore	<b>NS</b> ..... Non idoneo al servizio	<b>Spd.</b> ..... Velocità
<b>BSP-PL</b> ..... Filettatura passo gas parallela	<b>FWS</b> ..... Separatore carburante/acqua	<b>O. Air</b> ..... Aria esterna	<b>Spec.</b> ..... Specifica
<b>BTA PLUS</b> ..... Additivo per trattamento bilanciato PLUS	<b>G</b> ..... Guarnizione	<b>O. Gskt.</b> ..... Guarnizioni opzionali	<b>Spec(s)</b> ..... Specifiche
<b>BTE</b> ..... Trattamento bilanciato per anticongelante a base di glicole etilenico	<b>Gal.</b> ..... Gallone	<b>OBS</b> ..... Obsoleto	<b>SPI</b> ..... Iniezione porta sequenziale
<b>BTU</b> ..... British Thermal Unit	<b>GM, GMC</b> ..... General Motors Corporation	<b>O.D.</b> ..... Diametro esterno	<b>Sr.</b> ..... Senior
<b>C</b> ..... Celsius, Centigrado	<b>gph</b> ..... Galloni all'ora	<b>OE</b> ..... Attrezzatura originale	<b>SSS</b> ..... Cambio shuttle sincronizzato
<b>Calif.</b> ..... California	<b>gpm</b> ..... Galloni al minuto	<b>OEM</b> ..... Produttore di attrezzatura originale	<b>Std.</b> ..... Standard
<b>Carb.</b> ..... Carburatore, carburato	<b>Gskt.</b> ..... Guarnizioni	<b>OES</b> ..... Sistema di emissione aperto	<b>Steer.</b> ..... Sterzo
<b>Cat</b> ..... Caterpillar	<b>GVW</b> ..... Peso lordo del veicolo	<b>Off-Hwy</b> ..... Veicoli off-highway	<b>Sub.</b> ..... Sostituto
<b>cc</b> ..... Centimetri cubi	<b>H</b> ..... Codice base o alloggiamento	<b>OHC</b> ..... Albero a camme in testa	<b>SuctLine</b> ..... Linea d'aspirazione
<b>CCLS</b> ..... Sensore di carico a centro chiuso	<b>HBP</b> ..... Valvola di by-pass ad alta pressione (18-25 PSID)	<b>OHV</b> ..... Valvola in testa	<b>TBA</b> ..... Da comunicare
<b>CES</b> ..... Sistema di emissione chiuso	<b>HEUI</b> ..... Iniettore idraulico unità elettronica	<b>Olds</b> ..... Oldsmobile	<b>TBI</b> ..... Iniezione farfalla incorporata
<b>CFI</b> ..... Iniezione centralizzata del carburante	<b>Hi</b> ..... Alto	<b>Opt</b> ..... Opzionale	<b>Temp.</b> ..... Temperatura
<b>CFM</b> ..... Piedi cubi al minuto	<b>HiPerf.</b> ..... Alta prestazione	<b>oz.</b> ..... Oncia	<b>Thd.</b> ..... Filettatura
<b>CID</b> ..... Portata in pollici cubi	<b>HiPres.</b> ..... Alta pressione	<b>P. Cab</b> ..... Cabina pressurizzata	<b>THM</b> ..... Turbo-Hydratic
<b>CLN&amp;R</b> ..... Pulire e riutilizzare il filtro in uso	<b>HLT</b> ..... Trasmissione alto-basso	<b>P. Fuel</b> ..... Carburante primario	<b>TorqConv.</b> ..... Convertitore di coppia
<b>Co.</b> ..... Società	<b>HO</b> ..... Alta potenza	<b>PCV</b> ..... Ventilazione basamento positiva	<b>TPI</b> ..... Iniezione porta messa a punto
<b>COE</b> ..... Autoveicolo con cabina sopra al motore	<b>HP</b> ..... Cavallo vapore	<b>PEEC</b> ..... Controllo motore programmabile elettronico	<b>Trans.</b> ..... Trasmissione
<b>Comp.</b> ..... Compressore	<b>Hsg.</b> ..... Alloggiamento	<b>PFI</b> ..... Iniezione carburante programmata	<b>Turbo</b> ..... Turbocompressore a gas di scarico, sovralimentato con turbocompressore a gas di scarico
<b>Cont'd.</b> ..... Continuo	<b>HvyDty.</b> ..... Servizio pesante	<b>Pkg</b> ..... Imballaggio	<b>UK</b> ..... Regno Unito
<b>Corp.</b> ..... Società per azioni	<b>Hyd.</b> ..... Idraulico	<b>Pitd.</b> ..... Pieghettato	<b>UL, U.L.</b> ..... Riportato in Underwriters Lab
<b>CPI</b> ..... Iniezione porta centrale	<b>Hz</b> ..... Hertz	<b>PowBrakes</b> ..... Servofreni	<b>UNF</b> ..... Filettatura universale fine
<b>CSC</b> ..... Depuratore sistema refrigerante	<b>I. Air</b> ..... Aria interna	<b>PowDr.</b> ..... Power Drive	<b>U.S.</b> ..... Stati Uniti
<b>Cu.</b> ..... Cubico	<b>I. Gskt.</b> ..... Guarnizioni integrali	<b>PowQuad</b> ..... Power Quad	<b>U.S.C.G.</b> ..... Accettato da U.S. Coast Guard
<b>Cyl.</b> ..... Cilindro	<b>I.D.</b> ..... Diametro interno	<b>PowShift</b> ..... Power Shift	<b>V</b> ..... Volt
<b>D. Pan</b> ..... Vaschetta profonda	<b>IH, IHC</b> ..... International Harvester, International Navistar	<b>PowSteer.</b> ..... Servosterzo	<b>VapDiv.</b> ..... Divertore vapore
<b>Dbl.</b> ..... Doppio	<b>In.</b> ..... Pollice	<b>Pri.</b> ..... Primario	<b>VIN</b> ..... Numero di identificazione del veicolo
<b>DC</b> ..... Corrente continua	<b>Inc.</b> ..... Incorporato	<b>PRWD</b> ..... Trazione su ruote posteriori	<b>VV</b> ..... Venturi Variabile
<b>DDA</b> ..... Detroit Diesel Allison	<b>Incl.</b> ..... Incluso	<b>PS</b> ..... Guarnizione integrale supporto filtro	<b>VVT</b> ..... Variable Valve Timing
<b>DI</b> ..... Iniezione diretta	<b>Ind.</b> ..... Industriale	<b>PSI</b> ..... Libbre per pollice quadrato	<b>VW</b> ..... Volkswagen
<b>Div.</b> ..... Divisione	<b>Info</b> ..... Informazione	<b>PSID</b> ..... Libbre per pollice quadrato	<b>w/</b> ..... Con
<b>DOHC</b> ..... Doppio albero a camme in testa	<b>Int</b> ..... Internazionale	<b>PSR</b> ..... È necessario ermetizzare il supporto	<b>w/o</b> ..... Senza
<b>Don.</b> ..... Donaldson	<b>ISO</b> ..... Direzione flusso interno-esterno	<b>Pt.</b> ..... Pinta	<b>W.B.</b> ..... Interasse ruote
<b>ea.</b> ..... Ciascuno	<b>IVT</b> ..... Trasmissione a variazione infinita	<b>PTO</b> ..... Presa di forza	<b>XHBP</b> ..... Valvola di bypass a pressione altissima (50+ PSID)
<b>EFI</b> ..... Iniezione elettronica del carburante	<b>J.C.W.</b> ..... John Cooper Works	<b>PZEV</b> ..... Partial Zero Emissions Vehicle	<b>Yd.</b> ..... larda
<b>EGR</b> ..... Ricircolo gas esausti	<b>JD</b> ..... John Deere	<b>QR/SR</b> ..... Range quadrato o range sincronizzato	
<b>EHSS</b> ..... Cambio shuttle elettroidraulico	<b>JIC</b> ..... Joint Industry Conference	<b>Qt.</b> ..... Quart (Misura di capacità uguale a 1,1365 litri (ingl.) e 0,9463 (am.)	
<b>Ele</b> ..... Elemento	<b>Jr.</b> ..... Junior	<b>Qty.</b> ..... Quantità	
<b>Elec.</b> ..... Elettrico	<b>KHD</b> ..... Klockner-Humboldt-Deutz	<b>RC</b> ..... Tubo centrale rinforzato	
	<b>Kw</b> ..... Kilowatt	<b>Recirc.</b> ..... Ricircolo	
	<b>L</b> ..... Litri		
	<b>LBP</b> ..... Valvola di by-pass a bassa pressione (2-7 PSID)		
	<b>Lb(s)</b> ..... Libbre		
	<b>LGP</b> ..... Pressione litostatica bassa		

## ABREVIATURAS USADAS EN CUALQUIER PARTE DE NUESTROS CATALOGOS

2WD..... tração em duas rodas	Equip..... Equipamento	de Baixa Pressão (2-7 PSID)	RetLine ..... Linha de Retorno
4WD..... tração nas quatro rodas	Etc..... Etcetera	Lb(s)..... Libra(s)	R.H..... Direita
A. Gskt..... Acompanha Junta(s)	EUI..... Injetor de Unidade Eletrônica	LGP..... Baixa Pressão do solo	ROPS ..... Sistema de Proteção contra Capotagem
ABS ..... Sistema de Freio Antitravamento	Exc..... Exceto	L.H..... Esquerda	Rpl..... Substituído, Substituição
AD ..... Válvula anti-retorno	ExHiPres..... Alta Pressão Extra	LoPres..... Presao Barxa	rpm..... Rotações Por Minuto
ADP ..... Tubo anti-retorno	ExpHsg..... Carcaça exposta	LPG..... Gás Liquefeito de Petróleo	R.R..... Ferrovia
AirCond..... Ar Condicionado	ExpTank..... Tanque de expansão	LPH..... Litros por Hora	RWD..... Tração Traseira
Alum..... Alumínio	Ext..... Extensão	Ltd..... Limitado	S. Eng..... Motor de Partida
AMC..... American Motors	F..... Fahrenheit	M-F..... Massey Ferguson	S. Fuel..... Combustível Secundário
Amp..... Ampere	F. Drive..... Última marcha da transmissão	MBP..... Válvula de Contorno de Média Pressão (11-17 PSID)	S. Pan..... Carter Raso
App..... Aprovado	F. Fuel..... combustível, final	Mfg..... Produção	SCR..... Redução Catalítica Seletiva
Approx..... Aproximadamente	F. Gskt..... Junta(s) fornecidas	MFI..... Injeção Multiponto	Sec..... Secundário
Arr..... Arranjo	FECV..... Válvula de verificação frente e verso	Mfr..... Fabricante	SFI..... Injeção de Combustível Sequencial
A.T..... Transmissão automática	F-F..... Fluxo total	MichFlPow..... Michigan Fluid Power	Sgl..... Único, Individual
ATAAC..... Pós-resfriamento ar - ar	FFV... Veículo de Combustível Flexível	Min..... Quantidade mínima de pedido	SHBP..... Válvula de Contorno de Pressão Super Alta (30-45 PSID)
Attach..... Fixação	FI..... Injeção de combustível	mm..... Milímetros	SHO..... Alta Saída
AutoTrans..... transmissão automática	FidC/O..... Troca no campo	M-M..... Minneapolis-Moline	SintBronze..... Bronze Sinterizado
Aux..... Auxiliar	FidInst..... Instalação no campo	MO..... furo para medição	S/N..... Numero(s) de Série
AWD..... Tração em Todas as Rodas	FP..... Entrada para abastecimento	MPI..... Injeção de Combustível Multiponto	SOHC..... Comando de válvulas simples na cabeça
Bbl..... Barril	FRM..... Meio retardante do fogo	M.T..... Transmissão Manual	SP..... Suporte do Sensor
BP... Válvula de Contorno (8-10 PSID)	Ft..... Pé	Mtd..... Montado	Spd..... Velocidade
B-P..... Desvio	FWD..... Tração dianteira	Mtr..... Motor	Spec(s)..... Especificações
BPS..... Tela de contorno	FWS..... Separador Combustível/Água	NPSF..... Tubo Reto Fino Nacional	SPI..... Injeção sequencial
BSP..... Rosca norma Inglesa	G..... Junta	NPT... Rosca para tubos, padrão USA	Sr..... Senior
BSP-PL..... Rosca Paralela de Tubos da Norma Britânica	Gal..... Galão	N/R..... Não Requerido	SSS..... Transmissão Automática Continua Sincronizada
BTA PLUS..... Aditivo Plus para Tratamento Balanceado	GM, GMC..... General Motors Corporation	N/S..... Não Sujeito a Manutenção	Std..... Estandar
BTE..... Tratamento balanceado para anti-congelante Etileno Glicol	gph..... Galões por hora	O. Air..... Saída de Ar	Steer..... Direção
BTU..... Unidade Térmica Britânica	gpm..... Galões por minuto	O. Gskt..... Junta(s) Opcionais	Sub..... Substituto
C..... Celsius, Centígrado	Gskt..... Junta(s)	OBS..... Obsoleto	SubLine..... Linha de Sucção
Calif..... Califórnia	GVW..... Peso Bruto Vehicular	O.D..... Diâmetro Externo	TBA..... A Ser Anunciado
Carb..... Carburador, Carburado	H..... Numero da carcaça (somente troca do elemento)	OE..... Equipamento Original	TBI..... Injeção de ponto simples
Cat..... Caterpillar	HBP..... Válvula de Contorno de Alta Pressão (18-25 PSID)	OEM..... Fabricante de equipamento Original	Temp..... Temperatura
cc..... Centímetros Cúbicos	HEUI..... Injetor Hidráulico de Unidade Eletrônica	OES..... Sistema de Emissões Aberto	Thd..... Rosca
CCLS..... Sensor de Carga de Centro Fechado	Hi..... Alto	Off-Hwy..... Fora de estrada	THM..... Turbo Hidramático
CES... Sistema de Emissões Fechado	HiPerf..... Alto desempenho	OHC..... Comando de válvulas na Cabeça	TorqConv..... Conversor de Torque
CFI..... Injeção de Combustível Central	HiPres..... Alta pressão	OHV..... Válvulas na Cabeça	TPI..... Injeção ajustável
CFM..... Pés cúbicos por minuto	HLT..... Transmissão alta e baixa	Olds..... Oldsmobile	Trans..... Transmissão
CID..... Capacidade Cúbica em Polegadas	HO..... Alta capacidade	Opt..... Opcional	Turbo..... Turbocarregador
Cin&R..... Limpe e reuse o filtro	HP..... Cavalo Vapor	oz..... Onças	UK..... United Kingdom
Co..... Companhia	Hsg..... Carcaça	P. Cab..... Cabina Pressurizada	UL, U.L..... Registrado pelo laboratório Underwrites
COE..... Cabina acima do motor	HvyDty..... Serviço pesado	P. Fuel..... Combustível Primário	UNF... Rosca Fina Universal Americana
Comp..... Compressor	Hyd..... Hidráulico	PVC..... Ventilação Positiva do Câter	U.S..... Estados Unidos
Cont'd..... Continuação	Hz..... Hertz	PEEC..... Controle de Motor Eletrônico Programável	U.S.C.G..... Aceito pela Guarda Costeira Americana
Corp..... Corporação	I. Air..... Entrada de Ar	PFI..... Injeção de combustível programada	V..... Volt
CPI..... Corpo de injeção central	I. Gskt..... Junta inteira	Pkg..... Embalagem	VapDiv..... Derivação de Vapor
CSC..... Limpador do sistema de refrigeração	I.D..... Diâmetro Interno	Pitd..... Plissado	VIN..... Numero de Identificação do Veículo
Cu..... Cúbico	IH, IHC..... International Harvester, International Navistar	PowBrakes... Freios servo-assistidos	VV..... Venturi Variável
Cyl..... Cilindro	In..... Polegada	PowDr..... Unidade Propulsora	VVT..... Temporização Variável de Válvula
D. Pan..... Cuba profunda	Inc..... Incorporado	PowShift..... Transmissão Automática	VW..... Volkswagen
Dbi..... Duplo	Incl..... Incluso	PowSteer..... Direção Hidráulica	w/..... Com
DC..... Corrente Direta	Ind..... Industrial	Pri..... Primário	w/o..... Sem
DDA..... Detroit Diesel Allison	Info..... Informação	PRWD..... Tração traseira	W.B..... Distancia Entre Eixos
DI..... Inj. Direcctea	Int..... Internacional	PS..... Junta integral	XHBP..... Válvula de Contorno de Pressão Extra Alta (50+ PSID)
Div..... Divisão	ISO..... Sertido do fluxo de dentro para fora	PSID... Libras por Polegada Quadrada	Yd..... Jarra(s)
DOHC..... Came Dupla no Cabeçote	IVT..... Transmissão Infinitamente Variável	PSR..... Junta necessária	
Don..... Donaldson	J.C.W..... John Cooper Works	PT..... Pintas	
ea..... cada	JD..... John Deere	PTO..... Tomada de Força	
EFI..... Injeção eletrônica de combustível	JIC..... Joint Industry Conference	PZEV..... Veiculo de Emissão Zero Parcial	
EGR..... Recirculação de Gases de Descarga	Jr..... Júnior	QR/SR..... Transmissão com relações Quad, ou Sincronizada	
EHSS..... Transmissão Automática Continua Eletrodráulica	KHD..... Klockner-Humboldt-Deutz	Qt..... Um Quarto	
Ele..... Elemento	Kw..... Quilowatt	Qty..... Quantidade	
Elec..... Electrico	L..... Litros	RC..... Tubo central reforçado	
E.M.D..... Divisão eletro-motiva	LBP..... Válvula de Contorno	Recirc..... Recirculações	
Eng..... Motor		Rect..... Rectangular	
		Res..... Reservatório	

# СОКРАЩЕНИЯ, ИСПОЛЗУЕМЫЕ В НАШИХ КАТАЛОГАХ

<b>2WD</b> .....Привод на 2 колеса	<b>EHSS</b> .....Электрогидравлическая передача с сервоуправлением	<b>KHD</b> .....Компания "Klockner-Humboldt-Deutz"	<b>Qty.</b> .....Количество
<b>4WD</b> .....Привод на 4 колеса	<b>Ele</b> .....Элемент	<b>Kw</b> .....Киловатт	<b>RC</b> .....Ужесточенная центральная труба
<b>A. Gskt.</b> .....Устанавливаемая прокладка (прокладки)	<b>Elec.</b> .....Электрический	<b>L</b> .....Литры	<b>Recirc.</b> .....Повторное использование
<b>ABS</b> .....Антиблокировочная тормозная система	<b>E.M.D.</b> .....Отделение по работе с электрооборудованием	<b>LBP</b> .....Перепускной клапан низкого давления (2 - 7 фунт-сил на кв. дюйм)	<b>Res.</b> .....Емкость
<b>AD</b> .....Клапан, предотвращающий слив в бак	<b>Eng.</b> .....Двигатель	<b>Lb(s)</b> .....Фунт(ы)	<b>RetLine</b> .....Магистраль возврата
<b>ADP</b> .....Труба для предотвращения слива в бак	<b>Equip.</b> .....Оборудование	<b>LGP</b> .....Низкое давление на грунт	<b>R.H.</b> .....Правосторонний
<b>AirCond.</b> .....С кондиционированием воздуха или кондиционер	<b>Etc.</b> .....И т. д.	<b>L.H.</b> .....Левосторонний	<b>ROPS</b> .....Система защиты пассажиров при переворачивании автомобиля
<b>Alum.</b> .....Алюминий	<b>EUI</b> .....Электронная насос-форсунка	<b>LoPres</b> .....Низкое давление	<b>Rpl.</b> .....Заменяемый, замена
<b>AMC</b> .....Компания "American Motors"	<b>Exc.</b> .....За исключением	<b>LPG</b> .....Жидкий нефтяной газ	<b>rpm</b> .....Оборотов в минуту
<b>Amp</b> .....Ампер	<b>ExHiPres.</b> .....Сверхвысокое давление	<b>LPH</b> .....Литры в час	<b>R.R.</b> .....Железная дорога
<b>App</b> .....Утвержденный	<b>ExpHsg.</b> .....Открытый корпус	<b>Ltd.</b> .....Ограниченный или Лимитед (составляющая названий компаний)	<b>RWD</b> .....Привод на задние колеса
<b>Approx.</b> .....Приблизительно	<b>ExpTank</b> .....Расширительный бачок	<b>M-F</b> .....Компания "Massey Ferguson"	<b>S. Eng</b> .....Двигатель стартера
<b>Arr.</b> .....Компоновка, расположение	<b>Ext.</b> .....Расширенный	<b>MBP</b> .....Перепускной клапан среднего давления (11 - 17 фунт-сил на кв. дюйм)	<b>S. Fuel</b> .....Вторичное топливо
<b>A.T.</b> .....Автоматическая коробка передач	<b>F</b> .....Фаренгейт	<b>Mfg.</b> .....Производственный, производство	<b>S. Pan</b> .....Неглубокий поддон
<b>ATAAC</b> .....Воздушное последовательное охлаждение	<b>F. Drive</b> .....Главная передача	<b>MFI</b> .....Многооточный выриск топлива	<b>SCR</b> .....Селективное каталитическое восстановление
<b>Attach</b> .....Приложение, приспособление	<b>F. Fuel</b> .....Топливо после тонкой очистки	<b>Mfr.</b> .....Производитель	<b>Sec.</b> .....Вторичный, второстепенный
<b>AutoTrans.</b> .....Автоматическая коробка передач	<b>F. Gskt.</b> .....Поставляемая в комплекте прокладка (прокладки)	<b>MfchFIPow.</b> .....Компания "Michigan Fluid Power"	<b>Sgl.</b> .....Последовательный выриск топлива
<b>Aux.</b> .....Дополнительный, вспомогательный	<b>FECV</b> .....Передний запорный клапан	<b>Min.</b> .....Минимальный объем заказа	<b>SHBP</b> .....Перепускной клапан сверхвысокого давления (30 - 45 фунт-сил на кв. дюйм)
<b>AWD</b> .....Полный привод	<b>F-F</b> .....Транспортное средство, работающее на нескольких видах топлива	<b>mm</b> .....Миллиметр	<b>SHO</b> .....Со сверхвысокой производительностью
<b>Bbl.</b> .....Баррель	<b>FFV</b> .....Транспортное средство, работающее на нескольких видах топлива	<b>M-M</b> .....Компания "Minneapolis-Moline"	<b>SintBronze</b> .....Спеченная бронза
<b>BP</b> .....Перепускной клапан (8 - 10 фунт-сил на кв. дюйм)	<b>FI</b> .....Выриск топлива	<b>MO</b> .....Калиброванное отверстие	<b>S/N</b> .....Серийный номер (номера)
<b>B-P</b> .....Сетчатый фильтр перепускного канала	<b>FidC/O</b> .....Замена в полевых условиях	<b>MPI</b> .....Многооточный выриск топлива	<b>SOHC</b> .....Одinarsый верхний распределительный вал
<b>BSP</b> .....Британская стандартная трубная резьба	<b>FidInst.</b> .....Монтаж в полевых условиях	<b>M.T.</b> .....Ручная коробка передач	<b>SP</b> .....Отверсти датчика
<b>BSP-PL</b> .....Британская трубная цилиндрическая резьба	<b>FP</b> .....Заливное отверстие	<b>Mtd.</b> .....Установленный	<b>Spd.</b> .....Скорость
<b>BTA PLUS</b> .....Присадка Plus со сбалансированным составом	<b>FRM</b> .....Огнезащитные средства	<b>Mtr.</b> .....Двигатель	<b>Spec(s)</b> .....арактеристика (-ки)
<b>BTE</b> .....Добавка со сбалансированным составом для антифриза на основе этиленгликоля	<b>Ft.</b> .....Фут	<b>NPSF</b> .....Стандарт США для труб NPSF	<b>SPI</b> .....Последовательный выриск во впускные каналы
<b>BTU</b> .....Британская тепловая единица (BTE)	<b>FWD</b> .....Передний привод	<b>NPT</b> .....Нормальная трубная резьба	<b>Sr.</b> .....Старший
<b>C</b> .....Цельсий	<b>FWS</b> .....Топливный фильтр с водоотделителем	<b>N/R</b> .....Не требуется	<b>SSS</b> .....Передача с сервоуправлением и синхронизатором
<b>Calif.</b> .....Калифорния	<b>Gal.</b> .....Галлон	<b>N/S</b> .....Необслуживаемый	<b>Std.</b> .....Стандарт, стандартный
<b>Calif.</b> .....Калифорния	<b>GM, GMC</b> .....Компания "General Motors"	<b>O. Air</b> .....Воздух вне системы	<b>Steer.</b> .....Рулевое управление
<b>Carb.</b> .....Карбюратор, карбюрированный	<b>gph</b> .....Галлоны в час	<b>O. Gskt.</b> .....Дополнительная прокладка (прокладки)	<b>Sub.</b> .....Заменяющий, заменитель
<b>Cat</b> .....Гусеница, гусеничный ход	<b>gpm</b> .....Галлоны в минуту	<b>OBS</b> .....Устаревший	<b>SubLine</b> .....Линия всасывания
<b>cc</b> .....Кубически сантиметры	<b>gskt.</b> .....Прокладка (прокладки)	<b>O.D.</b> .....Внешний диаметр	<b>TBA</b> .....Должно быть сообщено
<b>CCLS</b> .....Распределитель с перекрытой золотником средней частью рабочего отверстия, работающий в зависимости от нагрузки	<b>GVW</b> .....Полная масса автомобиля	<b>OE</b> .....Комплектное оборудование	<b>TBI</b> .....Впрыск топлива в корпусе дроссельных заслонок
<b>CES</b> .....Замкнутая система выпуска отработавших газов	<b>HiPerf.</b> .....Высокие эксплуатационные характеристики	<b>OEM</b> .....Изготовитель комплектного оборудования	<b>Temp.</b> .....Температура
<b>CFI</b> .....Центральный выриск топлива	<b>HiPres.</b> .....Высокое давление	<b>OES</b> .....Открытая система выпуска отработавших газов	<b>Thd.</b> .....Резьба
<b>CFM</b> .....Кубически футы в минуту	<b>HLT</b> .....Коробка передач с демультипликатором	<b>Off-Hwy</b> .....Используемый вне автомобильных дорог	<b>THM</b> .....Фирменное название коробок передач "Turbo-Hydrumatic"
<b>CID</b> .....Объем двигателя в кубических дюймах	<b>HO</b> .....Высокопроизводительный	<b>ONC</b> .....Верхний распределительный вал	<b>TorqConv.</b> .....Гидротрансформатор
<b>CLN&amp;R</b> .....Очистить и повторно использовать имеющийся фильтр	<b>HP</b> .....Лошадиная сила	<b>OHV</b> .....Клапан верхнего расположения	<b>TRP</b> .....Регулируемый выриск топлива во впускные каналы
<b>Co.</b> .....Компания	<b>Hsg.</b> .....Корпус	<b>Olds</b> .....Марка автомобилей "Oldsmobile"	<b>Trans.</b> .....Коробка передач
<b>COE</b> .....Кабина над двигателем	<b>HvyDty.</b> .....Предназначенный для эксплуатации в тяжелом режиме	<b>Opt.</b> .....Дополнительный	<b>Turbo</b> .....Турбоагнетатель, оборудованный турбоагнетателем
<b>Comp.</b> .....Компрессор	<b>Hyd.</b> .....Гидравлический	<b>oz</b> .....Унция (унции)	<b>UK</b> .....Соединенное королевство (Великобритании и Северной Ирландии)
<b>Cont'd</b> .....Продолжающийся, продолжение	<b>HZ</b> .....Гц Hertz - герц	<b>P. Cab</b> .....Кабина с наддувом	<b>UL, U.L.</b> .....Включенный в перечень лабораторий "Underwriters Lab"
<b>Corp.</b> .....Корпорация	<b>I. Air</b> .....Воздух внутри системы	<b>P. Fuel</b> .....Первичное топливо	<b>UNF</b> .....Стандартная мелкая резьба (UNF)
<b>CPI</b> .....Впрыск в центральный канал	<b>I. Gskt.</b> .....Встроенная прокладка	<b>PEEC</b> .....Программируемая электронная система управления двигателем	<b>U.S.</b> .....Соединенный Штаты Америки
<b>CSC</b> .....Средство очистки системы охлаждения	<b>I.D.</b> .....Внутренний диаметр	<b>PFI</b> .....Программируемая система впрыска топлива	<b>U.S.C.G.</b> .....Принятый Службой береговой охраны США
<b>Cu.</b> .....Кубический	<b>IH, IHC</b> .....Компании "International Harvester" и "International Navistar"	<b>Pkg.</b> .....Комплект	<b>V</b> .....Вольт
<b>Cyl.</b> .....Цилиндр	<b>In.</b> .....Дюйм(ы)	<b>Pld.</b> .....Гофрированный, плисированный	<b>VapDiv.</b> .....Устройство отвода паров
<b>D. Pan</b> .....Глубокий поддон	<b>Inc.</b> .....Инкorpopейтид (составляющая названий корпораций)	<b>PowBrakes</b> .....Тормоза с усилителем	<b>VIN</b> .....Идентификационный номер автомобиля
<b>Dbi.</b> .....Двойной	<b>Incl.</b> .....Включенный в комплект	<b>PowDr.</b> .....Силовой привод	<b>VV</b> .....Смесительная камера с переменным давлением
<b>DC</b> .....Постоянный ток	<b>Ind.</b> .....Промышленный	<b>PowShift</b> .....Переключение (передач) при помощи усилителя	<b>VVT</b> .....Регулирование фаз газораспределения
<b>DDA</b> .....Компания "Detroit Diesel Allison"	<b>Info</b> .....Информация	<b>PowSteer.</b> .....Гидроусилитель рулевого управления	<b>VW</b> .....Компания "Volkswagen"
<b>DI</b> .....Непосредственный выриск	<b>Int.</b> .....Международный	<b>Pri</b> .....Основной	<b>w/</b> .....С (предлог)
<b>Div.</b> .....Отделение	<b>ISO</b> .....Направление потока "изнутри наружу"	<b>PRWD</b> .....Силовой привод на задние колеса	<b>w/o</b> .....Без
<b>DOHC</b> .....Двойной верхний распределительный вал	<b>IVT</b> .....Вариатор	<b>PS</b> .....Встроенная прокладка стойки	<b>W.B.</b> .....Колесная база
<b>Don.</b> .....Компания "Donaldson"	<b>J.C.W.</b> .....John Cooper Works	<b>PSID</b> .....Фунтов на квадратный дюйм	<b>XHBP</b> .....Перепускной клапан максимального сверхвысокого давления (50 и более фунт-сил на кв. дюйм)
<b>ea.</b> .....Каждый	<b>JD</b> .....Компания "John Deere"	<b>PSR</b> .....Требуется прокладка стойки	<b>Yd.</b> .....Ярд(ы)
<b>EFI</b> .....Электронный выриск топлива	<b>JIC</b> .....Общая конференция представителей промышленности	<b>PTO</b> .....Отбор мощности	
<b>EGR</b> .....Система повторного сжигания отработанных газов	<b>Jr.</b> .....Младший	<b>PZEV</b> .....Автомобиль с частично нулевыми выбросами	
		<b>QR/SR</b> .....Диапазон четырехскоростной передачи или синхронизатора	
		<b>Qt.</b> .....Кварта	



## ABREVIATURAS USADAS EN CUALQUIER PARTE DE NUESTROS CATALOGOS

<b>2WD</b>	Tracción sencilla a 2 ruedas	<b>EFI</b>	Inyección electrónica de combustible	<b>J.C.W.</b>	John Cooper Works	<b>Qt.</b>	Un cuarto
<b>4WD</b>	Tracción doble a 4 ruedas	<b>EGR</b>	Recirculación de gas de escape	<b>JD</b>	John Deere	<b>Qty.</b>	La cantidad
<b>A. Gskt.</b>	Empaque(s) adjunto(s)	<b>EHSS</b>	Cambio de sentido de desplazamiento electrohidráulico	<b>JIC</b>	Joint Industrial Conference	<b>RC</b>	Tubo central reforzado
<b>ABS</b>	Sistema de frenos antibloqueo	<b>Ele.</b>	Cartucho de repuesto eléctrico	<b>Jr.</b>	Junior	<b>Recirc.</b>	Recirculación
<b>AD</b>	Válvula anti-retorno	<b>Elec.</b>	Eléctrico	<b>KHD</b>	Klockner-Humboldt-Deutz	<b>Rect.</b>	Rectangular
<b>ADP</b>	Tubo anti-retorno	<b>E.M.D.</b>	División electromotriz	<b>Kw</b>	Kilovatios	<b>Res.</b>	Depósito
<b>AirCond.</b>	Climatizado o acondicionador de aire	<b>Eng(s).</b>	Motor(es)	<b>L</b>	Litros	<b>RetLine</b>	Línea de retorno
<b>Alum.</b>	Aluminio	<b>Equip.</b>	Equipo	<b>LBP</b>	Válvula de desviación de baja presión (2-7 PSID)	<b>R.H.</b>	Lado derecho
<b>AMC</b>	American Motors	<b>Etc.</b>	Etcétera	<b>Lb(s).</b>	Libra(s)	<b>ROPS</b>	Sistema de protección contra vuelcos
<b>Amp</b>	Amperio	<b>EUI</b>	Inyector de unidad electrónica	<b>LGP</b>	Presión baja del terreno	<b>Rpl.</b>	Reemplazado, reemplazo
<b>App.</b>	Aprobado	<b>Exc.</b>	Excepto	<b>L.H.</b>	Lado izquierdo	<b>rpm</b>	Revoluciones por minuto
<b>Approx.</b>	Aproximadamente	<b>ExHiPres.</b>	Muy alta presión	<b>LoPres.</b>	Presión Baja	<b>R.R.</b>	Ferrocarril
<b>Arr.</b>	Arreglo, disposición	<b>ExpHsg.</b>	Cárter abierto	<b>LPG</b>	Gas de petróleo licuado	<b>RWD</b>	Tracción trasera
<b>A.T.</b>	Transmisión Automotriz	<b>ExpTank</b>	Tanque de expansión	<b>LPH</b>	Litros por hora	<b>S. Eng.</b>	Motor de arranque
<b>ATAAC</b>	Postrefrigeración de aire a aire	<b>Ext.</b>	Extendido	<b>Ltd.</b>	Limitado	<b>S. Fuel</b>	Combustible secundario
<b>Attach.</b>	Accesorio	<b>F</b>	Fahrenheit	<b>M-F</b>	Massey Ferguson	<b>S. Pan</b>	Un carter llano
<b>AutoTrans.</b>	Transmisión automática	<b>F. Drive</b>	Tracción de transmisión final	<b>MBP</b>	Válvula de desviación de presión intermedia (11-17 PSID)	<b>SCR</b>	Reducción catalítica selectiva
<b>Aux.</b>	Auxiliar	<b>F. Fuel</b>	Filtro final (último)	<b>Mfg.</b>	Producción	<b>SCA</b>	Aditivo de refrigerante
<b>AWD</b>	Tracción de cuatro ruedas	<b>F. Gskt.</b>	Empaque(s) surtido(s)	<b>Mfr.</b>	Fabricante	<b>Sec.</b>	Secundario
<b>Bbl.</b>	Barril, tambor	<b>FECV</b>	Válvula de no retorno al frente	<b>MichFlIPow.</b>	Michigan Fluid Power	<b>Sgl.</b>	Sencillo
<b>BP</b>	Válvula de desviación (8-10 PSID)	<b>F-F</b>	Flujo de combustible	<b>Min.</b>	Cantidad mínima a pedir	<b>SHBP</b>	Válvula de desviación de super alta presión (30-45 PSID)
<b>B-P</b>	Desviación	<b>FFV</b>	Vehículo de combustible flexible	<b>mm</b>	Milímetro	<b>SHO</b>	Rendimiento superalto
<b>BPS</b>	Tamiz de desvío	<b>Fi</b>	Inyección de combustible	<b>M-M</b>	Minneapolis-Moline	<b>SintBronze</b>	Bronce sinterizado
<b>BSP</b>	Rosca de tubería británica estándar	<b>FidC/O</b>	Conversión en el campo	<b>MO</b>	Orificio de medición	<b>S/N</b>	Número(s) de serie
<b>BSP-PL</b>	Rosca paralela de tubería británica estándar	<b>FIdInst.</b>	Instalación en el campo	<b>M.T.</b>	Transmisión automática	<b>SOHC</b>	Árbol de levas único sobre la culata
<b>BTA PLUS</b>	Aditivo de tratamiento equilibrado Plus	<b>FP</b>	Puerto de llenado	<b>Mtd.</b>	Montado	<b>SP</b>	Puerto del sensor
<b>BTE</b>	Tratamiento balanceado para anticongelante de etileno glicol	<b>FRM</b>	Medio ignífugo	<b>Mtr.</b>	Motor	<b>Spd.</b>	La velocidad
<b>BTU</b>	Unidad térmica británica	<b>Ft.</b>	Pie	<b>NPSF</b>	Tubería nacional recta angosta	<b>Spec(s).</b>	Especificación(es)
<b>C</b>	Celsius, centígrado	<b>FWD</b>	Tracción delantera	<b>NPT</b>	National Pipe Thread (Rosca nacional para tubería EE.UU.)	<b>SPI</b>	Inyección Secuencial por Puertos
<b>Calif.</b>	California	<b>FWS</b>	Separador de combustible/ agua	<b>N/R</b>	No se requiere	<b>Sr.</b>	Senior
<b>Carb.</b>	Carburador, carburado	<b>[G]</b>	Empaque	<b>N/S</b>	No se puede reparar	<b>SSS</b>	Cambio de sentido de desplazamiento sincronizado
<b>Cat</b>	Caterpillar	<b>Gal.</b>	Galón	<b>O. Air</b>	Aire exterior	<b>Std.</b>	Estándar
<b>cc</b>	Centímetros cúbicos	<b>GM, GMC</b>	General Motors Corporation	<b>O. Gskt.</b>	Empaque(s) opcional(es)	<b>Steer.</b>	Dirección
<b>CCLS</b>	Detección de carga en posición de cierre	<b>gph</b>	Galones por hora	<b>OBS</b>	Obsoleto	<b>Sub</b>	Sustituto
<b>CES</b>	Sistema de escape cerrado	<b>gpm</b>	Galones por minuto	<b>O.D.</b>	Diámetro exterior	<b>SuctLine</b>	Línea de succión
<b>CFM</b>	Pie cúbico por minuto	<b>Gskt.</b>	Empaque(s)	<b>OE</b>	Equipo original	<b>Sys.</b>	Sistema
<b>CID</b>	Cilindrada en pulgada cuadradas	<b>GVW</b>	Peso Bruto Vehicular	<b>OEM</b>	Fabricante de equipo original	<b>TBA</b>	A anunciarse
<b>CLN&amp;R</b>	Limpie y reutilice el filtro instalado	<b>[H]</b>	Número de cárter (Nuestro repuesto es sólo el cartucho)	<b>OES</b>	Sistema de escape abierto	<b>TBI</b>	Inyección por el Cuerpo del Estrangulador
<b>CNG</b>	Gas natural comprimido	<b>HBP</b>	Válvula de desviación de alta presión (18-25 PSID)	<b>Off-Hwy</b>	Todo terreno	<b>Temp.</b>	Temperatura
<b>Co.</b>	Compañía	<b>HEUI</b>	Inyector de unidad hidráulica-electrónica	<b>OHC</b>	Árbol de levas a la cabeza	<b>Thd.</b>	Rosca
<b>COE</b>	Cabina montada arriba del motor	<b>Hgt.</b>	Height	<b>OHV</b>	Válvulas a la cabeza	<b>THM</b>	Turbo-hydrámatic
<b>Comp.</b>	Compresor	<b>Hi</b>	Alto	<b>Olds</b>	Oldsmobile	<b>TorqConv.</b>	Convertidor de torsión
<b>Cont'd.</b>	Continua	<b>HiPerf.</b>	Alto rendimiento	<b>Opt.</b>	Opcional	<b>Trans.</b>	Transmisión
<b>Corp.</b>	S.A.	<b>HiPres.</b>	Alta presión	<b>oz.</b>	Onza	<b>Turbo</b>	Turboalimentado
<b>CPI</b>	Inyección por Puerto Central	<b>HLT</b>	Transmisión alta-baja	<b>P. Cab</b>	Cabina a presión	<b>UK</b>	Reino Unido
<b>CSC</b>	Limpiador del sistema de refrigeración	<b>HO</b>	Alta capacidad	<b>P. Fuel</b>	Combustible primario	<b>UL, U.L.</b>	Registrado por Underwriters Laboratories
<b>Cu.</b>	Cúbico	<b>HP</b>	Caballaje	<b>PCV</b>	Ventilación positiva de cárter del cigüeñal	<b>UNF</b>	Universal National Fine (Rosca fina nacional universal-EE.UU.)
<b>CVT</b>	Transmisión variable continua	<b>Hsg.</b>	Cárter del cigüeñal	<b>PEEC</b>	Control de motor electrónico programable	<b>U.S.</b>	Estados Unidos
<b>Cyl.</b>	Cilindro	<b>HVAC</b>	Calefacción, ventilación y aire acondicionado	<b>Perf.</b>	Rendimiento	<b>U.S.C.G.</b>	Aceptado por los Guardacostas de los EE.UU.
<b>D. Pan</b>	Colector profundo	<b>HvyDty.</b>	Servicio pesado	<b>Pkg.</b>	Paquete promocional	<b>V</b>	Voltio
<b>Dbl.</b>	Doble	<b>Hyd.</b>	Hidráulico	<b>Pltid.</b>	Plegado	<b>VapDiv.</b>	Desviador de vapores
<b>DC</b>	Corriente directa	<b>Hz</b>	Hertzio	<b>PowBrakes</b>	Frenos de potencia	<b>Veh.</b>	Vehículo
<b>DDA</b>	Detroit Diesel Allison	<b>I. Air</b>	Aire interior (forma tapón de seguridad)	<b>PowDr.</b>	Unidad impulsora	<b>Vers.</b>	Versión
<b>DEF</b>	Fluido para el flujo de escape de vehículos diesel	<b>I. Gskt.</b>	Empaque(s) integral(es)	<b>PowrQuad</b>	Power Quad	<b>VIN</b>	Número de identificación de vehículo
<b>DI</b>	Inj. Directa	<b>I.D.</b>	Diámetro interior	<b>PowShift</b>	Velocidades hidráulicas	<b>VW</b>	Volkswagen
<b>Div.</b>	División	<b>IH, IHC</b>	International Harvester, International Navistar	<b>PowSteer.</b>	Dirección hidráulica	<b>w/</b>	Con
<b>DOHC</b>	Árbol de levas doble en la culata	<b>In.</b>	Pulgada	<b>Pri.</b>	Primario	<b>w/o</b>	Sin
<b>Don.</b>	Donaldson	<b>Incl.</b>	Incorporado	<b>PRWD</b>	Tracción Trasera de Potencia	<b>W.B.</b>	La distancia entre ejes
<b>ea.</b>	Cada uno	<b>Ind.</b>	Incluido	<b>PS</b>	Empaque integral de sello de poste	<b>XHBP</b>	Válvula de desviación de extra alta presión (50+ PSID)
		<b>Info</b>	Información	<b>PSD</b>	Libras por pulgada cuadrada	<b>XP</b>	Rendimiento extremo
		<b>Int.</b>	Internacional	<b>Pt.</b>	Se requiere sello de poste	<b>Yd.</b>	Yarda(s)
		<b>ISO</b>	Dirección de flujo de adentro hacia afuera	<b>PTO</b>	Toma de fuerza		
		<b>IVT</b>	Transmisión variable sin fin	<b>PZEV</b>	Vehículo de cero emisiones parciales		
				<b>QR/SR</b>	Transmisión Quad Range o Synchro Range		

## PREFIXES AND SUFFIXES

### PREFIXES

<b>AB</b>	Air Housing Mounting Band
<b>AC</b>	Air Housing Accessory - Air Inlet Hoods or Clamps
<b>AD</b>	Air Housing Dust Bowl, Air Filter Adapter
<b>AE</b>	Air Housing Elbow
<b>AFG</b>	Air Filter Restriction Gauge
<b>AH</b>	Air Housing Hump Hose
<b>AR</b>	Air Housing O-Ring
<b>AS</b>	Air Housing Sleeve, Stack Cap
<b>AV</b>	Air Housing Dust Ejector Valve
<b>AW</b>	Air Housing Wing or Metric Nut
<b>B</b>	Spin-on or Bag-Type Filter *
<b>BA</b>	Bag Air or Air Dryer
<b>BC</b>	Centrifugal Element
<b>BD</b>	Dual-Flow Lube Spin-on
<b>BF</b>	Spin-on, Can-Type or In-Line Fuel Filter
<b>BK</b>	Baldwin Kit
<b>BT</b>	Spin-on Lube or Hydraulic/Transmission Filter
<b>BW</b>	Coolant Spin-on with Chemicals
<b>C</b>	Cotton Lube Element
<b>CA</b>	Channel Flow® Air Filter
<b>CFB</b>	Coolant Filter Base
<b>CS</b>	Chemical Supplement
<b>CSC</b>	Coolant System Cleaner
<b>CTK</b>	Coolant Test Kit
<b>CV</b>	Crankcase Ventilation Breather
<b>CW</b>	Coolant Sock-Type Element with Chemicals
<b>ES</b>	End Seal
<b>F</b>	Cotton Fuel Element
<b>FB</b>	Fuel Filter Base
<b>FD</b>	Fuel Filter Adapter
<b>G</b>	Gasket

<b>H</b>	Pall-Type Hydraulic Element
<b>HH</b>	Hose
<b>HSG</b>	Air Filter Housing
<b>LL</b>	Long Life Air Filter Element
<b>OAS</b>	Oil/Air Separator
<b>OB</b>	Lube or Hydraulic Filter Base
<b>OP</b>	Plug
<b>OS</b>	Electrical Indicator
<b>OTK</b>	Oil Test Kit
<b>OV</b>	Visual Indicator
<b>P</b>	Paper Lube or Hydraulic Element
<b>PA</b>	Paper Air Element
<b>PE</b>	Urea Diesel Exhaust Fluid Filter
<b>PF</b>	Paper Fuel Element
<b>PG</b>	Pressure Gauge
<b>PKG</b>	Package, Premium Item
<b>PT</b>	Paper Lube or Hydraulic Element
<b>PV</b>	Paper and Vac-Cel Element *
<b>RS</b>	Radial Seal Air Filter
<b>S, SA, SF</b>	Special Material *
<b>T</b>	Cotton Lube Element *
<b>TA</b>	Acrylic and Other Synthetic Fibers for Most Fluids; Medium Flow; 5 or 10 Micron Retention (Peco Prefix AF)
<b>TB</b>	Blend of Cotton and Sisal for Non-Acid Fluids; Medium to High Flow; 25 to 40 Micron Retention (Peco Prefix FTE)
<b>TC</b>	All Cotton for Non-Acid Fluids; Low Flow Rates; 2, 5, or 10 Micron Retention (Peco Prefix FT)
<b>V</b>	Vac-Cel (Cotton) Lube Element *
<b>VG</b>	Vacuum Gauge
<b>VT</b>	Vac-Cel (Cotton) Lube Element *

### SUFFIXES

Multiple letter suffixes may need to be read as single letters. Suffixes often indicate the maker of the filter housing in which the element fits. When the suffix is not used for this purpose, it most often indicates the following:

<b>-1</b>	Specification Change	<b>-H</b>	Hydraulic Element
<b>-2</b>	Double Length or Air Element with 2 Inch Pleats	<b>-HD</b>	Heavy-Duty or Hydraulic
<b>(2), (3), (4)</b>	Number of Elements in a Kit	<b>-HPG</b>	High Performance Glass Media
<b>-3, -5, -10,</b>	Nominal Micron Retention	<b>-K</b>	Kit, Includes Reusable Parts, Fittings *
<b>-25, -30</b>		<b>-M</b>	Magnesium, Mason Jar Screw Neck *
<b>-A</b>	Closed End, Conversion Kit, Aluminum, Version # *	<b>-MPG</b>	Maximum Performance Glass Media
<b>-AF</b>	Normally on Air Filters	<b>-O</b>	Open End *
<b>-AL</b>	Can be Used with Fluids Containing Alcohol	<b>-OPE</b>	Orlon Sock for Use with Most Fluids; Particularly Recommended for High Heat or Acid-Content Fluids
<b>-B</b>	By-Pass Lube, Boxed, Version # *	<b>-OW</b>	Orlon Wrap
<b>-BSP</b>	British Standard Pipe	<b>-RV</b>	Roll-Over Valve
<b>-CPE</b>	Cotton Sock for Use with Non-Acid Fluids Flowing at Moderate Temperatures	<b>-S</b>	Specification Change on Liquid Filters; Smaller, Solid Lid on Air Filters *
<b>-CS</b>	Water Absorbent Media	<b>-SP</b>	With Sensor Port
<b>-D</b>	Drain, Direct Mount *	<b>-SPS</b>	With Reusable Sensor Port
<b>-DL</b>	Double Length	<b>-SS</b>	Filter for Severe Service
<b>-DM</b>	Drain - Marine Applications	<b>-T</b>	Sisal Sock for High Flow Applications *
<b>-E</b>	Economy or Fleet Pack *	<b>-V</b>	Viton O-Ring
<b>-F</b>	Wound Cotton or Felt Media	<b>-W</b>	With Wrap, Winter - Cold Weather Applications *
<b>-FF</b>	Full-Flow Lube Element	<b>-WO</b>	Without - See Specifications
<b>-FN</b>	Air Filter with Fins	<b>-WPC</b>	With Pre-Cleaner
<b>-FP</b>	Contains Fill Port	<b>XP</b>	Extreme Performance

\* See Specific Number in Product Guide for Details and Exceptions.

## الحروف البادئة واللاحقة

الحروف البادئة	
<b>AB</b>	طوق تحميل مبيّت الهواء
<b>AC</b>	مستلزمات مبيّت الهواء - أغطية أو قامطات مدخل الهواء
<b>AD</b>	مهاين مرشح الهواء
<b>AE</b>	كوع مبيّت الهواء
<b>AFG</b>	مقياس تقييم مرشح الهواء
<b>AH</b>	خرطوم بحدبة لمبيّت الهواء
<b>AR</b>	حلقة سد مستديرة لمبيّت الهواء
<b>AS</b>	أغطية علوية وسفلية لجلبة مبيّت الهواء
<b>AV</b>	صمام طرد التراب لمبيّت الهواء
<b>AW</b>	صامولة مجنحة أو مترية لمبيّت الهواء
<b>B</b>	مرشح لف أو مرشح جرابي *
<b>BA</b>	جراب الهواء
<b>BC</b>	جزء الطرد المركزي
<b>BD</b>	وسيلة التزيت بالسرطان الثنائي والتركيّب بالف
<b>BF</b>	مرشح الزيت بتركيّب اللف، من نوع العلبه أو نوع التحاذي
<b>BK</b>	عُدّة بولدوين Baldwin Kit
<b>BT</b>	فلتر بتركيّب اللف لنظام الترشيح أو لمجموعة النقل الهيدرولي
<b>BW</b>	وسيلة تبريد بتركيّب اللف مع المواد الكيماوية
<b>C</b>	عنصر ترزيق قطن
<b>CA</b>	مرشح هواء Channel Flow®
<b>CFB</b>	قاعدة مرشح التبريد
<b>CS</b>	مضافات كيماوية
<b>CSC</b>	منظف نظام التبريد
<b>CTK</b>	عده اختبار التبريد
<b>CV</b>	فتحة التهوية الخاصة بعلبة المرافق
<b>CW</b>	عنصر مرشح التبريد من نوع الجورب مع المواد الكيماوية
<b>ES</b>	مانع للتسرب عند الطرف
<b>F</b>	عنصر من القطن ترشيح الوقود
<b>FB</b>	قاعدة مرشح الوقود
<b>FD</b>	مهاين مرشح الوقود
<b>G</b>	حشوة (لمنع التسرب)
<b>H</b>	عنصر هيدرولي من نوع Paul-Type
<b>HH</b>	خرطوم
<b>HSG</b>	مبيّت مرشح الهواء
<b>LL</b>	عنصر مرشح هواء طويل العمر
<b>OAS</b>	عازل الزيت/الهواء
<b>OB</b>	قاعدة مرشح الزيت أو مرشح النظام الهيدرولي
<b>OP</b>	توصيل
<b>OS</b>	المؤشرات الكهربائية
<b>OTK</b>	عده اختبار الزيت
<b>OV</b>	المؤشرات المرئية
<b>P</b>	عنصر ورقي لمرشح نظام الترزيق أو النظام الهيدرولي
<b>PA</b>	عنصر ورقي لترشيح الهواء
<b>PF</b>	عنصر ورقي لترشيح الوقود
<b>PG</b>	مقياس الضغط
<b>PKG</b>	عبوة، منتج ممتاز
<b>PT</b>	عنصر ورقي لمرشح نظام الترزيق أو النظام الهيدرولي
<b>PV</b>	عنصر من الورق والخلايا المفرغة *
<b>RS</b>	مرشح هواء ذو منع تسرب قطري
<b>S, SA, SF</b>	مواد خاصة *
<b>T</b>	عنصر ترزيق قطن *
<b>TA</b>	أكريليك وألياف اصطناعية أخرى لأكثر أنواع السوائل، تدفق متوسط، مقياس الاحتفاظ ٥ أو ١٩ ميكرون (بادئ بيكو AF)
<b>TB</b>	خليط من القطن والسيرال للسوائل غير الحامضية، تدفق متوسط إلى عالي، مقياس الاحتفاظ ٢٥ إلى ٤٠ ميكرون (بادئ بيكو FTE)
<b>TC</b>	قطن خالص للسوائل غير الحامضية، تدفق منخفض، مقياس الاحتفاظ ٢ أو ٥ أو ١٠ ميكرون (بادئ بيكو FT)
<b>V</b>	عنصر ترزيق بخلايا مفرغة (قطن) *
<b>VG</b>	مقياس التفريغ
<b>VT</b>	عنصر ترزيق بخلايا مفرغة (قطن) *

## اللواحق

<b>-FP</b>	يحتوي على مدخل التعبئة
<b>-H</b>	عنصر هيدرولي
<b>-HD</b>	تحميل ثقيل أو هيدرولي
<b>-HPG</b>	وسيط زجاجي ذو أداء عالي
<b>-K</b>	عُدّة، تشمل أجزاء قابلة لإعادة الاستخدام، توصيلات *
<b>-M</b>	مغنسيوم، مرطبان جيسون بالرقيبة الملولة *
<b>-MPG</b>	وسيط زجاجي ذو أداء عالي
<b>-O</b>	نهاية مفتوحة *
<b>-OPE</b>	جورب من الأورلون للاستخدام مع أكثر السوائل، يفضل خاصة في حالة السخونة العالية أو السوائل التي تحتوي على حامض.
<b>-OW</b>	لفيف من الأورلون
<b>-RV</b>	صمام انقلاب
<b>-S</b>	تغيير مواصفات مرشحات السوائل، أصغر، غطاء مصممت لمرشحات الهواء *
<b>-SP</b>	مع المدخل الاستشعاري
<b>-SPS</b>	مع مدخل استشعاري قابل لإعادة الاستخدام
<b>-SS</b>	مرشح للخدمة الشاقة
<b>-T</b>	جورب من السيرال لاستخدامات التدفق العالي *
<b>-V</b>	حلقة سد مستديرة من نوع قيتون.
<b>-W</b>	مع الغلاف، استخدامات الشتاء و الطقس البارد *
<b>-WO</b>	بدون - أنظر المواصفات
<b>-WPC</b>	مع مادة التنظيف الأولي
<b>XP</b>	الأداء الأمثل
<b>-A</b>	طرف مغلق أو عده تحويل أو ألومنيوم أو نسخة رقم *
<b>-AF</b>	يظهر عادة على مرشحات الهواء
<b>-AL</b>	يمكن استخدامه مع سوائل تحتوي على الكحول
<b>-B</b>	تجاوزي لنظام الترزيق، في إطار، نسخة رقم *
<b>-BSP</b>	الأنابيب القياسية البريطانية
<b>-CPE</b>	جورب قطن (عنصر ترشيح) للاستخدام مع السوائل غير الحامضية المتدفقة في درجات حرارة متوسطة
<b>-CS</b>	وسائط ماصة للماء
<b>-D</b>	تصفية، تحميل مباشر *
<b>-DL</b>	طول مزدوج
<b>-DM</b>	تطبيقات الصرف - التطبيقات البحرية
<b>-E</b>	عبوة اقتصادية أو عبوة أسطول *
<b>-F</b>	وسط من قطن ملفوف أو اللباد
<b>-FF</b>	عنصر لنظام التزيت كالم التدفق
<b>-FN</b>	مرشح هواء بزعاغف

\* انظر الرقم المعين في دليل المنتجات للحصول على التفاصيل والاستثناءات

## 前缀和后缀

### 前缀

<b>AB</b>	空气滤清器外壳安装环	<b>FB</b>	燃油滤清器底座
<b>AC</b>	空气滤清器外壳附件-空气进口罩或夹具	<b>G</b>	垫圈
<b>AD</b>	空气滤清器接头	<b>H</b>	罩式液压滤芯
<b>AE</b>	空气滤清器外壳弯管	<b>HH</b>	软管
<b>AFG</b>	空气滤清器限流表	<b>HSG</b>	空气滤清器外壳
<b>AH</b>	空气滤清器外壳驼峰软管	<b>LL</b>	长寿命空气滤清器滤芯
<b>AK</b>	含空气滤清器接头和内空气滤芯的工具包	<b>OB</b>	润滑油或液压滤清器底座
<b>AR</b>	空气滤清器 O 型环	<b>OTK</b>	油测试包
<b>AS</b>	空气滤清器外壳护套, 叠盖	<b>P</b>	纸质润滑油或液压滤芯
<b>AV</b>	空气滤清器外壳 去尘器阀e	<b>PA</b>	纸质空气滤芯
<b>AW</b>	空气滤清器外壳翼形螺母或公制螺母	<b>PF</b>	纸质燃油滤芯
<b>B</b>	旋装式或袋式滤清器*	<b>PG</b>	压力表
<b>BA</b>	袋式空气滤清器	<b>PKG</b>	套装, 优质品
<b>BC</b>	离心滤芯	<b>PT</b>	纸质润滑油或液压滤芯
<b>BD</b>	双向流润滑油旋装式	<b>PV</b>	纸质及 Vac-Cel 滤芯*
<b>BF</b>	旋装式, 罐式或直列式燃油滤清器	<b>RS</b>	径向密封空气滤清器
<b>BK</b>	Baldwin 工具包	<b>S, SA, SF</b>	特殊材料 *
<b>BT</b>	旋装式润滑油或液压/变速滤清器	<b>T</b>	棉织润滑油滤芯*
<b>BW</b>	冷却剂旋装式滤清器 (带化学品)	<b>TA</b>	用于大多数丙烯酸及其它合成纤维; 5 或 10微米积垢 (Peco Prefix AF)
<b>C</b>	棉质润滑油滤芯	<b>TB</b>	用于非酸性液体的棉与剑麻混合物; 25或40 微米积垢 (Peco Prefix FTE)
<b>CA</b>	Channel Flow® 空气滤清器	<b>TC</b>	用于非酸性液体的全棉, 低流量; 2, 5, 或10微米积垢(Peco Prefix FT)
<b>CFB</b>	冷却剂过滤器底座	<b>V</b>	Vac-Cel (棉质) 润滑油滤芯 *
<b>CS</b>	化学补充剂	<b>VG</b>	真空表
<b>CSC</b>	冷却剂系统清洁剂	<b>VT</b>	Vac-Cel (棉质) 润滑油滤芯 *
<b>CTK</b>	冷却剂测试包		
<b>CW</b>	冷却剂袜式滤芯 (带化学品)		
<b>ES</b>	端密封		
<b>F</b>	棉质燃油滤芯		

### 后缀

多字母组成的后缀可能需要读为单一字母。后缀往往表示滤清器外壳的制造厂商。如果不是这种情况, 则大多数表示以下意义:

<b>-1</b>	规格改变	<b>-H</b>	液压滤芯
<b>-2</b>	双倍长度或有2吋摺边的滤芯	<b>-HD</b>	重型或液压
<b>(2), (3), (4)</b>	工具包中的滤芯数	<b>-HPG</b>	高性能玻璃介质
<b>-3, -5, -10, -25, -30</b>	标定微米积垢	<b>-K</b>	工具包, 包括可重新使用的零配件和紧固件 *
<b>-A</b>	封口, 转换包, 铝质, 型号*	<b>-M</b>	镁, Mason Jar 螺旋颈 *
<b>-AF</b>	一般用于空气滤清器	<b>-MPG</b>	最高性能玻璃介质
<b>-AL</b>	可用于含酒精的液体	<b>-O</b>	开口 *
<b>-B</b>	旁通润滑油, 盒装, 型号*	<b>-OPE</b>	用于大多数液体的奥纶袜式滤芯; 尤其推荐用于搞热或含酸的液体
<b>-CPE</b>	用于中等温度下流动非酸性液体的棉质袜式滤芯	<b>-OW</b>	奥纶匝环
<b>-CS</b>	吸水介质	<b>-RV</b>	翻车安全阀
<b>-D</b>	排放, 直接安装*	<b>-S</b>	液体滤清器规格变化; 空气滤清器上较小的实心盖子*
<b>-DL</b>	双倍长度	<b>-SP</b>	带传感器出口
<b>-E</b>	经济型或车队包装	<b>-SS</b>	严酷服务条件下使用的滤清器
<b>-F</b>	织棉或毛毡介质	<b>-SPS</b>	带可重新使用的传感器端口
<b>-FF</b>	全流式润滑油滤芯	<b>-T</b>	高流量应用的剑麻袜式滤芯 *
<b>-FN</b>	带肋片的空气滤清器	<b>-V</b>	Viton O型环
<b>-FP</b>	带加油端口	<b>-W</b>	带匝环, 冬季 - 寒冷天气应用 *
		<b>-WO</b>	不带 - 参见规格
		<b>-WPC</b>	带预清洁剂
		<b>XP</b>	超级性能

\* 详情及例外情况请参阅产品指导中的特别编号。

## PREFIXES ET SUFFIXES

### PREFIXES

<b>AB</b>	Bande de montage de boîtier d'air	<b>H</b>	Cartouche hydraulique
<b>AC</b>	Accessoire de boîtier d'air - capots ou colliers d'entrée d'air	<b>HH</b>	Flexible
<b>AD</b>	Adaptateur de filtre à air	<b>HSG</b>	Boîtier de filtre à air
<b>AE</b>	Coude de boîtier d'air	<b>LL</b>	Cartouche de filtre à air longue durée
<b>AFG</b>	Indicateur de colmatage de filtre à air	<b>OAS</b>	Séparateur huile / air
<b>AH</b>	Flexible de bosse de boîtier d'air	<b>OB</b>	Base de filtre à huile de lubrification ou hydraulique
<b>AR</b>	Joint torique de boîtier d'air	<b>OP</b>	Obturbateur
<b>AS</b>	Manchon de boîtier d'air, capuchon cheminée	<b>OS</b>	Indicateur électrique
<b>AV</b>	Valve d'éjection de poussière du boîtier d'air	<b>OTK</b>	Nécessaire de contrôle d'huile
<b>AW</b>	Ecrou papillon ou métrique du boîtier d'air	<b>OV</b>	Indicateur visuel
<b>B</b>	Filtre de type vissable ou en ligne *	<b>P</b>	Cartouche en papier pour filtre à huile de lubrification ou hydraulique
<b>BA</b>	Élément sac ou sécheur d'air	<b>PA</b>	Cartouche en papier pour filtre à air
<b>BC</b>	Cartouche centrifuge	<b>PE</b>	Filtre à fluide d'échappement (diesel-urée)
<b>BD</b>	Lubrification, flux double, vissable	<b>PF</b>	Cartouche en papier pour filtre à carburant
<b>BF</b>	Filtre à carburant vissable, type bidon ou sur conduite	<b>PG</b>	Manomètre
<b>BK</b>	Jeu Baldwin	<b>PKG</b>	Paquet, article de qualité supérieure
<b>BT</b>	Filtre à huile de lubrification ou hydraulique/de transmission vissable	<b>PT</b>	Cartouche en papier pour filtre à huile de lubrification ou hydraulique
<b>BW</b>	Liquide de refroidissement avec produits chimiques, vissable	<b>PV</b>	Cartouche Papier et Vac-Cel *
<b>C</b>	Cartouche coton pour lubrification	<b>RS</b>	Filtre à air à joint radial
<b>CA</b>	Filtre à air Channel Flow®	<b>S, SA, SF</b>	Matériau spécial *
<b>CFB</b>	Base de filtre à liquide de refroidissement	<b>T</b>	Cartouche coton pour lubrification *
<b>CS</b>	Supplément chimique	<b>TA</b>	Fibres acryliques et autres fibres synthétiques pour la plupart des fluides; flux moyen; rétention 5 ou 10 microns (Préfixe peco AT)
<b>CSC</b>	Produit de nettoyage de circuit de refroidissement	<b>TB</b>	Mélange de coton et sisal pour fluides non acides; flux moyen à élevé; rétention 25 à 40 microns (Préfixe peco FTE)
<b>CTK</b>	Jeu de test de liquide de refroidissement	<b>TC</b>	Tout coton pour fluides non acides; débits faibles; rétention 2, 5 ou 10 microns (Préfixe peco TT)
<b>CV</b>	Reniflard de carter	<b>V</b>	Cartouche pour lubrification Vac-Cel (coton) *
<b>CW</b>	Élément de type chaussette pour liquide de refroidissement avec produits chimiques	<b>VG</b>	Déprimomètre
<b>ES</b>	Joint d'extrémité	<b>VT</b>	Cartouche pour lubrification Vac-Cel (coton) *
<b>F</b>	Cartouche en coton pour carburant		
<b>FB</b>	Base de filtre à carburant		
<b>FD</b>	Adaptateur pour filtre à carburant		
<b>G</b>	Joint		

### SUFFIXES

Les suffixes à lettres multiples doivent parfois être lus comme lettres individuelles. Les suffixes indiquent souvent le fabricant du boîtier du filtre dans lequel s'ajuste la cartouche. Lorsque le suffixe n'est pas utilisé dans ce but, il indique le plus souvent ce qui suit:

<b>-1</b>	Changement de spécification	<b>-FN</b>	Filtre à air avec ailettes
<b>-2</b>	Double longueur ou cartouche air avec plis de 2 pouces (5 cm)	<b>-FP</b>	Contient orifice de remplissage
<b>(2), (3), (4)</b>	Nombre d'éléments dans un nécessaire	<b>-H</b>	Cartouche hydraulique
<b>-3, -5, -10,</b>	Rétention nominale en microns	<b>-HD</b>	Usage intensif ou hydraulique
<b>-25, -30</b>		<b>-HPG</b>	En verre haute performance
<b>-A</b>	Version extrémité fermée, nécessaire de conversion, aluminium *	<b>-K</b>	Nécessaire, comprend pièces réutilisables, garnitures *
<b>-AF</b>	Normalement sur filtres à air	<b>-M</b>	Tubulure fileté, magnésium, récipient maçon *
<b>-AL</b>	Peut être utilisé avec des fluides contenant de l'alcool	<b>-MPG</b>	En verre performance maximum
<b>-B</b>	Version en boîte, dérivation, lubrification *	<b>-O</b>	Extrémité ouverte *
<b>-BSP</b>	British Standard Pipe	<b>-OPE</b>	Chaussette Orlon pour utiliser avec la plupart des fluides; particulièrement recommandée pour la chaleur élevée ou les fluides acides
<b>-CPE</b>	Chaussette coton pour utiliser avec les fluides non acides s'écoulant à températures modérées	<b>-OW</b>	Enveloppe Orlon
<b>-CS</b>	Milieu avide d'eau	<b>-RV</b>	Vanne de reuversement
<b>-D</b>	Montage direct, vidange *	<b>-S</b>	Changement de spécification sur filtres à liquide; Couverture plein, plus petit sur filtres à air *
<b>-DL</b>	Double longueur	<b>-SP</b>	Avec orifice de capteur
<b>-DM</b>	Scarico - Applicazioni marine	<b>-SPS</b>	Avec orifice de capteur réutilisable
<b>-E</b>	Paquet économie ou flotte *	<b>-SS</b>	Filtre SS pour les utilisations intensives
<b>-F</b>	En coton enroulé ou feutre	<b>-T</b>	Chaussette sisal pour applications de bit élevé *
<b>-FF</b>	Cartouche pour lubrification à passage intégral	<b>-V</b>	Joint torique en Viton
		<b>-W</b>	Avec enveloppe, Hiver - Applications pour temps froid *
		<b>-WO</b>	Sans - Voir les spécifications
		<b>-WPC</b>	Avec préfiltre
		<b>XP</b>	Performances extrêmes

\* Voir le numéro spécifique dans le Guide des Produits pour les détails et exceptions.

## PRÄFIXE UND SUFFIXE

### PRÄFIXE (VORSILBEN)

<b>AB</b>	Luftgehäuse Halteklammer
<b>AC</b>	Luftgehäuse Zubehör - Ansaugkappe oder Klammern
<b>AD</b>	Luftfilteradapter
<b>AE</b>	Luftgehäuse Kniestück
<b>AFG</b>	Luftfilter Drosselungsanzeige
<b>AH</b>	Luftgehäuse Buckelverbindungsstück
<b>AR</b>	Luftgehäuse Dichtungsring
<b>AS</b>	Luftgehäuse Verbindungsstück, Kappe
<b>AV</b>	Luftgehäuse Staubausstoßventil
<b>AW</b>	Luftgehäuse Flügelmutter
<b>B</b>	Dreh- oder Beutel-Filter *
<b>BA</b>	Taschenluftfilter oder Lufttrockner
<b>BC</b>	Zentrifugen Einsatz
<b>BD</b>	Öl doppelter Durchfluß Drehfilter
<b>BF</b>	Brennstoff Dreh-, Topf-, oder Durchfluß-Filter
<b>BK</b>	Baldwin Satz
<b>BT</b>	Drehfilter für Öl oder Hydraulik/Getriebe
<b>BW</b>	Kühlung, Dreh mit Chemikalien
<b>C</b>	Öl Baumwolle Einsatz
<b>CA</b>	Channel Flow <sup>®</sup> -Luftfilter
<b>CFB</b>	Kühlungsfiltergehäuse
<b>CS</b>	Chemikalien Ergänzungssatz
<b>CSC</b>	Kühlungssystemreiniger
<b>CTK</b>	Kühlungsprüfungssatz
<b>CV</b>	Kurbelgehäuseentlüftung
<b>CW</b>	Kühlungs Einsatz, Sockeu-typ, mit Chemikalien
<b>ES</b>	Abschlußdichtung
<b>F</b>	Treibstoff Baumwolle Einsatz
<b>FB</b>	Ölfiltergehäuse
<b>FD</b>	Kraftstofffilter-Adapter
<b>G</b>	Dichtung
<b>H</b>	Hydraulik Pall-typ Einsatz

<b>HH</b>	Schlauch
<b>HSG</b>	Luftfiltergehäuse
<b>LL</b>	Langlebiger Luftfilter Einsatz
<b>OAS</b>	Öl-Luft-Abscheider
<b>OB</b>	Öl- oder Hydraulikfiltergehäuse
<b>OP</b>	Verschlussstopfen
<b>OS</b>	Elektrische Anzeige
<b>OTK</b>	Öltestsatz
<b>OV</b>	Visuelle Anzeige
<b>P</b>	Öl- oder Hydraulik Papier Einsatz
<b>PA</b>	Luftfilter Papier Einsatz
<b>PF</b>	Brennstoff Papier Einsatz
<b>PG</b>	Druckanzeigergerät
<b>PKG</b>	Packung, gehobenes Modell
<b>PT</b>	Öl- oder Hydraulik Papier Einsatz
<b>PV</b>	Papier und Vac-Cel *
<b>RS</b>	Kreisartige Dichtung Luftfilter
<b>S, SA, SF</b>	Sondermaterial *
<b>T</b>	Öl Baumwolle Einsatz *
<b>TA</b>	Acrylik und andere synthetischen Faserstoffe für die meisten Flüssigkeiten; mittlerer Durchfluß 5 oder 10 Mikron Auffang (Peco Vorsatz AF)
<b>TB</b>	Mischung von Baumwolle und Sisal for nicht-sauere Flüssigkeiten; mittlerer bis hoher Durchfluß; 25 bis 40 Mikron Auffang (Peco Vorsatz FTE)
<b>TC</b>	Reine Baumwolle für nicht-sauere Flüssigkeiten; kleine Durchflußgeschwindigkeiten; 2, 5 oder 10 Mikron Auffang (Peco Vorsatz FT)
<b>V</b>	Öl Vac Cel (Baumwolle) Einsatz *
<b>VG</b>	Manometer
<b>VT</b>	Öl Vac Cel (Baumwolle) Einsatz *

### SUFFIXE (NACHSILBEN)

Suffixe mit mehreren Buchstaben dürfen unter Umständen nur als ein einzelner Buchstabe gelesen werden. Suffixe geben oft den Hersteller des Filtergehäuses an in welches das Filter paßt. Falls der Zusatz nicht zu diesem Zweck gebraucht ist, dann bedeutet er meist wie folgt:

<b>-1</b>	Änderung der Spezifikationen
<b>-2</b>	Doppelte Länge oder Luft Einsatz mit 2-inch Falten
<b>(2), (3), (4)</b>	Anzahl der Einsätze in einem Satz
<b>-3, -5, -10, -25, -30</b>	Nominaler Auffang in Mikron
<b>-A</b>	Abschließendes Ende, Konversionssatz, Aluminium, Ausführung *
<b>-AF</b>	Normalerweise bei Luftfiltern
<b>-AL</b>	Kann mit alkoholischen Flüssigkeiten verwendet werden
<b>-B</b>	Öl By-Pass, Schachtel, Ausführung *
<b>-BSP</b>	British Standard Pipe (Gewindetyp)
<b>-CPE</b>	Baumwolle Socken-typ zum Gebrauch für nicht-sauere Flüssigkeiten bei mittleren Temperaturen
<b>-CS</b>	Wasseraufnahmefähiger Inhalt
<b>-D</b>	Abfluß, direkter Anbau *
<b>-DL</b>	Doppelte Länge
<b>-DM</b>	Abläss – Wasserfahrzeuge
<b>-E</b>	Spar-oder Mengenpackung *
<b>-F</b>	Gespulte Baumwolle oder Filzmaterial
<b>-FF</b>	Öl Hoher Durchfluß Einsatz
<b>-FN</b>	Luftfilter mit Finnen
<b>-FP</b>	Einschließlich Einfüllstutzen
<b>-H</b>	Hydraulik Einsatz
<b>-HD</b>	Schwere Belastung oder Hydraulik
<b>-HPG</b>	Glasinhalt für hohe Ansprüche
<b>-K</b>	Satz, einschließlich wiederverwendbarer Teile, Verbindungsstücke *
<b>-M</b>	Magnesium, Mason-Jar Schraubgewinde *
<b>-MPG</b>	Glasinhalt für höchste Ansprüche
<b>-O</b>	Offenes Ende *
<b>-OPE</b>	Orlon Socken-typ für die meisten Flüssigkeiten; besonders empfohlen bei hoher Hitze oder sauren Flüssigkeiten
<b>-OW</b>	Orlon Wickel
<b>-RV</b>	Roll-over Ventil
<b>-S</b>	Änderung der Spezifikationen für Filter für Flüssigkeiten; kleinerer harter Deckel für Luftfilter *
<b>-SP</b>	mit Sensoröffnung
<b>-SPS</b>	Mit wiederverwendbarer Sensoröffnung
<b>-SS</b>	SS-Filter für Schwerstbetrieb
<b>-T</b>	Sisalsocken für Anwendungen mit hohem Durchfluß *
<b>-V</b>	Viton Dichtungsring
<b>-W</b>	Mit Umschlag, Winter Anwendungen bei niedrigen Temperaturen *
<b>-WO</b>	Ohne, bitte Spezifikationen beachten
<b>-WPC</b>	Mit Vorreiniger
<b>XP</b>	Höchstleistungsfilter

\* Beachten Sie die Einzelheiten und Ausnahmen in der, Produktaufzeichnung.

## PREFISSI E SUFFISSI

### PREFISSI

<b>AB</b>	Fascetta di montaggio alloggiamento aria
<b>AC</b>	Accessorio alloggiamento aria – Cappucci o morsetti entrata aria
<b>AD</b>	Adattatore filtro aria
<b>AE</b>	Gomito alloggiamento aria
<b>AFG</b>	Indicatore di restrizione filtro aria
<b>AH</b>	Tubo flessibile alloggiamento aria
<b>AR</b>	O-Ring alloggiamento aria
<b>AS</b>	Manicotto alloggiamento aria, cappuccio pila
<b>AV</b>	Valvola estrattore polvere alloggiamento aria
<b>AW</b>	Ala alloggiamento aria oppure dado metrico
<b>B</b>	Filtro spin-on oppure filtro a sacco *
<b>BA</b>	Sacco aria
<b>BC</b>	Elemento centrifugo
<b>BD</b>	Filtro spin-on lubrificante a doppio flusso
<b>BF</b>	Filtro spin-on, filtro carburante a barattolo o in linea
<b>BK</b>	Kit Baldwin
<b>BT</b>	Filtro spin-on lubrificante oppure filtro idraulico/di trasmissione
<b>BW</b>	Filtro spin-on refrigerante con sostanze chimiche
<b>C</b>	Elemento di cotone lubrificante
<b>CA</b>	Filtro dell'aria Channel Flow®
<b>CFB</b>	Base filtro refrigerante
<b>CS</b>	Supplemento chimico
<b>CSC</b>	Depuratore sistema refrigerante
<b>CTK</b>	Kit di prova refrigerante
<b>CV</b>	Crankcase Ventilation Breather
<b>CW</b>	Elemento a sacco refrigerante con sostanze chimiche
<b>ES</b>	Guarnizione finale
<b>F</b>	Elemento di cotone carburante
<b>FB</b>	Base filtro carburante
<b>FD</b>	Fuel Filter Adapter

<b>G</b>	Guarnizione
<b>H</b>	Elemento idraulico di tipo Pall
<b>HH</b>	Tubo flessibile
<b>HSG</b>	Alloggiamento filtro aria
<b>LL</b>	Elemento filtro aria a lunga durata
<b>OAS</b>	Oil/Air Separator
<b>OB</b>	Base filtro idraulico o lubrificante
<b>OP</b>	Plug
<b>OS</b>	Electrical Indicator
<b>OTK</b>	Kit di prova olio
<b>OV</b>	Visual Indicator
<b>P</b>	Elemento di carta lubrificante o idraulico
<b>PA</b>	Elemento di carta aria
<b>PF</b>	Elemento di carta carburante
<b>PG</b>	Manometro
<b>PKG</b>	Confezione, articolo di qualità superiore
<b>PT</b>	Elemento di carta lubrificante o idraulico
<b>PV</b>	Elemento di carta e Vac-cel *
<b>RS</b>	Filtro aria guarnizione radiale
<b>S, SA, SF</b>	Materiale speciale *
<b>T</b>	Elemento di cotone lubrificante *
<b>TA</b>	Acrilico e altre fibre sintetiche per grand parte dei fluidi; flusso medio; ritenzione 5 o 10 micron (Prefisso Peco AF)
<b>TB</b>	Miscela di cotone e sisal per fluidi non acidi; flusso medio-alta; ritenzione da 25 a 40 micron (Prefisso Peco FTE)
<b>TC</b>	Puro cotone per fluidi non acidi; flusso basso; ritenzione da 2, 5, o 10 micron (Prefisso Peco FT)
<b>V</b>	Elemento in Vac-cel (cotone) lubrificante *
<b>VG</b>	Vacuometro
<b>VT</b>	Elemento in Vac-cel (cotone) lubrificante *

### SUFFISSI

Può essere necessario leggere i suffissi con più lettere come lettere singole. Spesso i suffissi indicano il produttore dell'alloggiamento del filtro in cui risiede l'elemento. Quando il suffisso non è utilizzato per questo scopo, esso spesso indica quanto segue:

<b>-1</b>	Modifica della specifica tecnica
<b>-2</b>	Lunghezza doppia oppure elemento aria con pieghettature da 2 pollici
<b>(2), (3), (4)</b>	Numero di elementi in un kit
<b>-3, -5, -10, -25, -30</b>	Ritenzione nominale in micron
<b>-A</b>	Estremità chiusa, kit di conversione, alluminio, versione # *
<b>-AF</b>	Normalmente su filtri aria
<b>-AL</b>	Può essere utilizzato con fluidi contenenti alcol
<b>-B</b>	Bypass lubrificante, incassato, versione # *
<b>-BSP</b>	British Standard Pipe
<b>-CPE</b>	Sacco in cotone per uso con fluidi non acidi a temperature moderate
<b>-CS</b>	Mezzi assorbenti acqua
<b>-D</b>	Scarico, montaggio diretto *
<b>-DL</b>	Lunghezza doppia
<b>-DM</b>	Drain - Marine Applications
<b>-E</b>	Economia oppure fleet pack *
<b>-F</b>	Cotone avvolto oppure mezzo di feltro
<b>-FF</b>	Elemento lubrificante per flusso totale
<b>-FN</b>	Filtro aria con alette

<b>-FP</b>	Contiene porta di riempimento
<b>-H</b>	Elemento idraulico
<b>-HD</b>	Servizio pesante oppure idraulico
<b>-HPG</b>	Mezzi di vetro per alte prestazioni
<b>-K</b>	Kit, include parti riutilizzabili, accessori *
<b>-M</b>	Magnesio, vite Mason Jar *
<b>-MPG</b>	Mezzi di vetro per prestazioni massime
<b>-O</b>	Estremità aperta *
<b>-OPE</b>	Sacco di orlon per uso con gran parte dei fluidi; particolarmente consigliata per fluidi altamente riscaldati o acidi
<b>-OW</b>	Copertura di orlon
<b>-RV</b>	Valvola "roll-over"
<b>-S</b>	Modifica della specifica tecnica per filtri di liquidi; più piccolo; coperchio solido su filtri aria *
<b>-SP</b>	Con porta sensore
<b>-SPS</b>	Con porta sensore riutilizzabile
<b>-SS</b>	Filtro per servizio pesante
<b>-T</b>	Sacco in sisal per applicazioni con flusso elevato *
<b>-V</b>	O-Ring in Viton
<b>-W</b>	Con copertura, applicazioni inverno-tempo freddo *
<b>-WO</b>	Senza – Vedere specifiche tecniche
<b>-WPC</b>	Con pre-depuratore
<b>XP</b>	Prestazioni estreme

\* Per dettagli ed eccezioni, vedere il numero specifico nella guida prodotto.

## PREFIXOS E SUFIXOS

### PREFIXOS

<b>AB</b>	Tira de montagem para carcaça de filtro de ar
<b>AC</b>	Acessórios da carcaças dos filtros de ar - Chapéu ou abraçadeiras
<b>AD</b>	Adaptador do filtro de ar
<b>AE</b>	Cotovelo da carcaça do filtro de ar
<b>AFG</b>	Mostrador de restrição do filtro de ar
<b>AH</b>	Mangueira curva da caixa de ar
<b>AR</b>	Anel "O" da caixa de ar
<b>AS</b>	Bucha e tampa da chaminé
<b>AV</b>	Válvula para retirar excesso de poeira da caixa de ar
<b>AW</b>	Porca métrica ou tipo borboleta da caixa de ar
<b>B</b>	Filtro selado ou tipo bolsa *
<b>BA</b>	Ar do Saco ou Secador de Ar
<b>BC</b>	Elemento de centrifugação
<b>BD</b>	Filtro selado de dois fluxos
<b>BF</b>	Filtro selado, tipo caneca, ou filtro de linha
<b>BK</b>	Kit Baldwin
<b>BT</b>	Filtro selado para lubrificante ou transmissão hidráulica
<b>BW</b>	Filtro selado para sistema de refrigeração com substancias químicas
<b>C</b>	Elemento de algodão
<b>CA</b>	Filtro de Ar Channel Flow®
<b>CFB</b>	Base do filtro para sistemas de refrigeração
<b>CS</b>	Suplemento de substancias químicas
<b>CSC</b>	Limpador do sistema de refrigeração
<b>CTK</b>	Kit do teste do liquido refrigerante
<b>CV</b>	Suspiro de Ventilação do Câter
<b>CW</b>	Elemento de filtro tipo meia para sistemas de refrigeração, com substancias químicas
<b>ES</b>	Selo
<b>F</b>	Elemento de filtro de algodão
<b>FB</b>	Base do filtro de combustível
<b>FD</b>	Adaptador do Filtro de Combustível

<b>G</b>	Junta
<b>H</b>	Elemento de filtro hidráulico
<b>HH</b>	mangueira
<b>HSG</b>	Carcaça de filtro de ar
<b>LL</b>	Elemento de filtro de ar de longa vida
<b>OAS</b>	Separador de Óleo e Água
<b>OB</b>	Base de filtro lubrificante ou hidráulico
<b>OP</b>	Bujão
<b>OS</b>	Indicador Elétrico
<b>OTK</b>	Kit de teste de óleo
<b>OV</b>	Indicador Visual
<b>P</b>	Elemento de papel para lubrificante ou hidráulico
<b>PA</b>	Elemento de papel para ar
<b>PF</b>	Elemento de papel para combustível
<b>PG</b>	Indicador de pressão
<b>PKG</b>	Embalagem, artigo "premium"
<b>PT</b>	Elemento de papel para lubrificante ou hidráulico
<b>PV</b>	Elemento de papel e Vac-Cel *
<b>RS</b>	Elemento de filtro de ar tipo Selo radial
<b>S, SA, SF</b>	Material especial *
<b>T</b>	Elemento de algodão para lubrificante
<b>TA</b>	Acrílico ou outras fibras sintéticas para a maioria dos fluidos; Vazão média; retenção de 5 a 10 microns (Prefixo Peco AF)
<b>TB</b>	Mistura de algodão e sisal para fluidos não ácidos; Vazão de média para alta; Retenção de 25 a 40 microns (Prefixo Peco FTE)
<b>TC</b>	Totalmente algodão para fluidos não ácidos; Baixas relações de vazão; retenção de 2, 5, ou 10 microns (Prefixo Peco FT)
<b>V</b>	Elemento lubrificante de Vac-Cel (algodão) *
<b>VG</b>	Indicados de vácuo - Vacuômetro
<b>VT</b>	Elemento lubrificante de Vac-Cel (algodão) *

### SUFIXOS

Sufixos com muitas letras devem ser lidos como se fossem letras simples. Normalmente o sufixo indica o fabricante da carcaça do filtro, na qual o elemento se encaixa. Quando o sufixo não se utiliza para este propósito, na maioria das vezes indica o seguinte:

<b>-1</b>	Mudança de especificações
<b>-2</b>	Comprimento duplo, ou elemento de filtro de ar com plissado de duas polegadas
<b>(2), (3), (4)</b>	Número de elemento no Kit
<b>-3, -5, -10, -25, -30</b>	Retenção nominal em microns
<b>-A</b>	Fechamento externo, Kit de conversão, Alumínio, Versão # *
<b>-AF</b>	Normalmente em filtros de ar
<b>-AL</b>	Poderá ser utilizado em fluidos que contém álcool
<b>-B</b>	Lubrificante tipo derivação, fechado, versão # *
<b>-BSP</b>	British Standard Pipe
<b>-CPE</b>	Tipo meia de algodão para utilização em fluidos não ácidos e temperaturas moderadas
<b>-CS</b>	Meio filtrante absorvente de água
<b>-D</b>	Drenagem, Montagem direta *
<b>-DL</b>	Comprimento duplo
<b>-DM</b>	Dreno DM - Aplicações Marítimas
<b>-E</b>	Embalagem econômica ou para transporte
<b>-F</b>	Meio filtrante em algodão ou feltro
<b>-FF</b>	Elemento de fluxo total

<b>-FN</b>	Filtro de ar com aletas
<b>-FP</b>	Contém orifício de entrada
<b>-H</b>	Elemento hidráulico
<b>-HD</b>	Elemento hidráulico ou serviço pesado
<b>-HPG</b>	Meio filtrante de alto desempenho de fibra de vidro
<b>-K</b>	Kit, Inclui peças reutilizáveis, acessórios
<b>-M</b>	Magnésio, Jarra hermética com rosca
<b>-MPG</b>	Meio filtrante de máximo desempenho de fibra de vidro
<b>-O</b>	Final aberto
<b>-OPE</b>	Meia de orlón para ser utilizado na maioria dos fluidos; particularmente recomendado para altas temperaturas ou fluidos que contem ácidos
<b>-OW</b>	Revestimento de orlón
<b>-RV</b>	Válvula de rotação
<b>-S</b>	Modificação das especificações dos filtros para líquidos, Menores, Tampa sólida nos filtros de ar
<b>-SP</b>	Com tomada para sensor
<b>-SPS</b>	Com tomada de sensor reutilizável
<b>-SS</b>	Filtros para seriços severos
<b>-T</b>	Meia de sisal para aplicações de altas vazões *
<b>-V</b>	Anel "O" de viton
<b>-W</b>	Com revestimento, Inverno - para aplicações em baixas temperaturas
<b>-WO</b>	Sem - Verifique as especificações
<b>-WPC</b>	Com o Pré-limpador
<b>XP</b>	Desempenho Extremo

\* Veja o Numero Especifico No Catalogo Produtos, com Relação aos Detalhes.



# ПРИСТАВКИ И СУФФИКСЫ

## ПРИСТАВКИ

<b>AB</b>	Лента крепления воздухозаборной коробки
<b>AC</b>	Принадлежности воздухозаборной коробки: предохранительный колпак на впуске воздуха или хомуты
<b>AD</b>	Переходник воздушного фильтра
<b>AE</b>	Колено воздухозаборной коробки
<b>AFG</b>	Указатель сопротивления воздушного фильтра
<b>AH</b>	Сортировочный шланг воздухозаборной коробки
<b>AR</b>	Уплотнительное кольцо воздухозаборной коробки
<b>AS</b>	Рукав воздухозаборной коробки, крышка выводного патрубка
<b>AV</b>	Клапан пылеэжектора воздухозаборной коробки
<b>AW</b>	Крыльчатая барашковая или метрическая гайка воздухозаборной коробки
<b>B</b>	Навинчиваемый или рукавный фильтр *
<b>BA</b>	Баллон с воздухом или осушитель воздуха
<b>BC</b>	Элемент центробежного фильтра
<b>BD</b>	—вухпоточный навинчиваемый масляный фильтр
<b>BF</b>	Навинчиваемый, стаканый или встраиваемый топливный фильтр
<b>BK</b>	Комплект принадлежностей фирмы “Болдуин”
<b>BT</b>	Навинчиваемый масляный фильтр или фильтр гидравлической системы или коробки передач
<b>BW</b>	Навинчиваемый фильтр охлаждающей жидкости с присадками
<b>C</b>	Хлопчатобумажный элемент масляного фильтра
<b>CA</b>	Воздушный фильтр с разделенными каналами (Channel Flow®)
<b>CFB</b>	Корпус фильтра охлаждающей жидкости
<b>CS</b>	Химическая добавка
<b>CSC</b>	Фильтр системы охлаждения
<b>CTK</b>	Набор принадлежностей для контроля качества охлаждающей жидкости
<b>CV</b>	Сапун вентиляции картера
<b>CW</b>	Рукавный элемент фильтра охлаждающей жидкости с присадками
<b>ES</b>	Торцевое уплотнение
<b>F</b>	Хлопчатобумажный элемент топливного фильтра
<b>FB</b>	Корпус топливного фильтра
<b>FD</b>	Переходной патрубок топливного фильтра
<b>G</b>	Уплотнительная прокладка
<b>H</b>	Элемент Полла для фильтра гидравлической системы

<b>HH</b>	Шланг
<b>HSG</b>	Корпус воздушного фильтра
<b>LL</b>	Элемент воздушного фильтра с длительным сроком службы
<b>OAS</b>	Устройство для центробежной очистки моторного масла
<b>OB</b>	Корпус масляного фильтра или фильтра гидравлической системы
<b>OP</b>	Заглушка
<b>OS</b>	Электрический индикатор
<b>OTK</b>	Набор принадлежностей для контроля качества масла
<b>OV</b>	Индикатор визуального контроля
<b>P</b>	Бумажный элемент масляного фильтра или фильтра гидравлической системы
<b>PA</b>	Бумажный элемент воздушного фильтра
<b>PF</b>	Бумажный элемент топливного фильтра
<b>PG</b>	Манометр
<b>PKG</b>	Комплектное изделие высшего сорта
<b>PT</b>	Бумажный элемент масляного фильтра или фильтра гидравлической системы
<b>PV</b>	Бумажный фильтрующий элемент со структурой Vac-Cel *
<b>RS</b>	Воздушный фильтр с радиальным уплотнением
<b>S, SA, SF</b>	Специальный материал *
<b>T</b>	Хлопчатобумажный элемент масляного фильтра *
<b>TA</b>	Акриловое или иное синтетическое волокно для большинства рабочих сред; для средних значений расхода; степень фильтрации 5 или 10 мкм (для серии Peco - приставка AF)
<b>TB</b>	Материал из смеси хлопка с сизалем для неагрессивных рабочих сред; для средних и высоких значений расхода; степень фильтрации 25 - 40 мкм (для серии Peco - приставка FTE)
<b>TC</b>	Чисто хлопчатобумажный материал; для низких значений расхода; степень фильтрации 2, 5 или 10 мкм (для серии Peco - приставка FT)
<b>V</b>	Элемент со структурой Vac-Cel (хлопчатобумажный) для масляного фильтра
<b>VG</b>	Вакуумметр
<b>VT</b>	Элемент со структурой Vac-Cel (хлопчатобумажный) для масляного фильтра

## СУФФИКСЫ

Некоторые суффиксы из нескольких букв могут потребовать их чтения как суффиксов, состоящих из единственной буквы. Во многих случаях суффиксом обозначается предприятие-изготовитель корпуса фильтра, в который может быть установлен данный фильтрующий элемент. Если суффикс используется с иной целью, то им часто обозначаются следующие характеристики:

<b>-1</b>	Изменение технических данных
<b>-2</b>	Элемент воздушного фильтра, имеющий двойную длину или 2-доймовый гофр
<b>(2), (3), (4)</b>	Число фильтрующих элементов в комплекте
<b>-3, -5, -10, -25, -30</b>	Номинальная удерживающая способность фильтра в микрометрах
<b>-A</b>	С закрытым торцом, комплектом для переоборудования, алюминиевое исполнение, модификация № *
<b>-AF</b>	Стандартно устанавливаемый на воздушных фильтрах
<b>-AL</b>	Может применяться с жидкостями, содержащими спирт
<b>-B</b>	Обводная линия смазки, коробчатое исполнение, модификация № *
<b>-BSP</b>	британская стандартная трубная [резьба]
<b>-CPE</b>	Хлопчатобумажный, в рукавном исполнении для применения с неагрессивными текучими средами при умеренных температурах
<b>-CS</b>	Материал, впитывающий воду *
<b>-D</b>	Выпуск, непосредственный монтаж
<b>-DL</b>	—войная длина
<b>-DM</b>	Слив - для использования на судах
<b>-E</b>	Экономичный вариант или для автохозяйств *
<b>-F</b>	Навитой хлопчатобумажный или фетровый материал
<b>-FF</b>	Полнопоточный элемент смазочного фильтра
<b>-FN</b>	Воздушный фильтр с ребрами
<b>-FP</b>	Содержит заправочную горловину

<b>-H</b>	Элемент для гидравлических систем
<b>-HD</b>	—тяжелых машин или гидравлических систем
<b>-HPG</b>	Высокоэффективный материал на основе стекла
<b>-K</b>	Комплект, содержащий детали повторного использования, элементы арматуры *
<b>-M</b>	Магний, керамическая резьбовая горловина *
<b>-MPG</b>	Предельно эффективный материал на основе стекла
<b>-O</b>	Открытый торец *
<b>-OPE</b>	Рукавное исполнение из полиакрилонитрильного волокна “орлон”, для использования с большинством текучих сред; особенно рекомендуется для сильно нагретых или содержащих кислоты жидкостей
<b>-OW</b>	Витая оболочка из полиакрилонитрильного волокна “орлон”
<b>-RV</b>	Клапан, срабатывающий при переворачивании
<b>-S</b>	Изменение технических характеристик жидкостных фильтров; уменьшенная сплошная крышка на воздушных фильтрах *
<b>-SP</b>	С каналом для датчика
<b>-SPS</b>	С каналом для повторно используемого датчика
<b>-SS</b>	Фильтр для особо тяжелых условий эксплуатации
<b>-T</b>	Рукавное исполнение из сизала для применения в устройствах с высоким расходом
<b>-V</b>	Кольцевое уплотнение из сополимера прфторпропилена с винилиденфторидом “вайтон”
<b>-W</b>	С витой оболочкой, для применения в условиях низких температур
<b>-WO</b>	Без - см. технические данные
<b>-WPC</b>	С предварительным очистителем
<b>XP</b>	Высокая производительность

\* См. подробные сведения и исключения в разделе “Справочника по продукции”, посвященном индивидуальным номерам.

## PREFIJOS Y SUFIJOS

### PREFIJOS

<b>AB</b>	Banda de montaje para la caja de aire	<b>HH</b>	Manguera
<b>AC</b>	Accesorio de caja de aire - Capucha o abrazador de la toma de aire	<b>HSG</b>	Caja de filtro de aire
<b>AD</b>	Adaptador del filtro de aire	<b>LL</b>	Elemento de filtro de aire de larga duración
<b>AE</b>	Codo de la caja de aire	<b>OAS</b>	Separador de aceite/aire
<b>AFG</b>	Indicador de restricción del filtro de aire	<b>OB</b>	Base del filtro hidráulico o del lubricante
<b>AH</b>	Manguera encorvada de la caja de aire	<b>OP</b>	Tapón
<b>AR</b>	Anillo "O" de la caja de aire	<b>OS</b>	Indicador eléctrico
<b>AS</b>	Manga de unidad de aire, tapón de escape	<b>OTK</b>	Kit de comprobación del aceite
<b>AV</b>	Válvula eyectora de polvo de la caja de aire	<b>OV</b>	Indicador visual
<b>AW</b>	Tuerca métrica o tuerca de orejetas de la caja de aire	<b>P</b>	Elemento de papel para lubricantes o hidráulicos
<b>B</b>	Filtro de rosca o tipo-bolsa *	<b>PA</b>	Elemento de papel para aire
<b>BA</b>	Aire en bolsa o secadora de aire	<b>PE</b>	Filtro de fluidos de escape de urea-diesel
<b>BC</b>	Elemento de centrifugación	<b>PF</b>	Elemento de papel para combustible
<b>BD</b>	Filtro de lubricante de rosca de corriente dual	<b>PG</b>	Indicador de presión
<b>BF</b>	Filtro de combustible de rosca, tipo-lata o de línea	<b>PKG</b>	Paquete, artículo de primera
<b>BK</b>	Kit de Baldwin	<b>PT</b>	Elemento de papel para lubricantes o hidráulicos
<b>BT</b>	Filtro de lubricante de rosca o de sistema de transmisión hidráulica	<b>PV</b>	Papel y Vac-Cel *
<b>BW</b>	Filtro de refrigerante de rosca con químicos	<b>RS</b>	Filtro de aire de sellado radial
<b>C</b>	Elemento de algodón para lubricación	<b>S, SA, SF</b>	Material especial *
<b>CA</b>	Filtro de aire Channel Flow®	<b>T</b>	Elemento de algodón para lubricante *
<b>CFB</b>	Base del filtro de refrigerante	<b>TA</b>	Acrílicos y otras fibras sintéticas para la mayoría de los fluidos; caudal medio; 5 ó 10 micrometros de retención (Prefijo Peco AF)
<b>CS</b>	Suplemento químico	<b>TB</b>	Derivados de algodón y fibra de para fluidos sin contenido de acidos; caudal medio a alto; de 25 a 40 micrometros de retención (Prefijo Peco FTE)
<b>CSC</b>	Limpiador del sistema de refrigeración	<b>TC</b>	Puro algodón para fluidos sin contenido de acidos; Porcentajes de caudal bajo; 2, 5, ó 10 micrometros de retención (Prefijo Peco FT)
<b>CTK</b>	Kit de comprobación del refrigerante	<b>V</b>	Elemento de lubricación de Vac-Cel (algodón) *
<b>CV</b>	Respiradero de ventilación del cárter	<b>VG</b>	Vaciómetro
<b>CW</b>	Elemento de refrigeración tipo calcetín con químicos	<b>VT</b>	Elemento de lubricación de Vac-Cel (algodón) *
<b>ES</b>	Sello de extremo		
<b>F</b>	Elemento de algodón para combustible		
<b>FB</b>	Base del filtro para combustible		
<b>FD</b>	Adaptador para filtro de combustible		
<b>G</b>	Empaque		
<b>H</b>	Elemento hidráulico		

### SUFIJOS

Puede que los sufijos de múltiples letras necesiten leerse como letras simples. Los sufijos a menudo indican el fabricante de la caja de filtro en la que el elemento encaja. Cuando el sufijo no se utiliza para este propósito, la mayoría de las veces indica lo siguiente:

<b>-1</b>	Cambio de especificación	<b>-H</b>	Elemento hidráulico
<b>-2</b>	Doble longitud o elemento de aire con 2 pulgadas de pliegues	<b>-HD</b>	Trabajos pesados o hidráulicos
<b>(2), (3), (4)</b>	Número de elementos en un kit	<b>-HPG</b>	Medio de cristal de alto rendimiento
<b>-3, -5, -10,</b>	Retención nominal de micrometros	<b>-K</b>	Kit, incluye piezas reutilizables, accesorios *
<b>-25, -30</b>		<b>-M</b>	Magnesio, bote hermético con cuello de rosca *
<b>-A</b>	Versión de extremo cerrado, de kit de conversión, Aluminio *	<b>-MPG</b>	Medio de cristal de máximo rendimiento
<b>-AF</b>	Normalmente en filtros de aire	<b>-O</b>	Extremo abierto *
<b>-AL</b>	Puede usarse junto con fluidos que contengan alcohol	<b>-OPE</b>	Calcetín de Orlón a utilizar con la mayoría de los fluidos; Recomendado particularmente en fluidos de temperaturas elevadas o en fluidos conteniendo acidos
<b>-B</b>	Versión de lubricación por derivación en caja	<b>-OW</b>	Envoltura de Orlón
<b>-BSP</b>	Tubería estándar británica	<b>-RV</b>	Válvula de rotación
<b>-CPE</b>	Calcetín de algodón para el uso en fluidos sin contenido de ácidos corriendo a temperaturas moderadas	<b>-S</b>	Cambio de especificación en los filtros de líquidos; más pequeños, tapadera sólida en filtros de aire *
<b>-CS</b>	Medio de fécula de maíz	<b>-SP</b>	Con lumbrera sensora
<b>-D</b>	Desagüe, montaje directo *	<b>-SPS</b>	Con lumbrera sensora reutilizable
<b>-DL</b>	Doble longitud	<b>-SS</b>	Filtro SS para servicio severo
<b>-DM</b>	Drenaje – Aplicaciones marinas	<b>-T</b>	Calcetín de fibra de para aplicaciones de alta corriente *
<b>-E</b>	Paquete económico o de carga	<b>-V</b>	Anillo-O de Vitón
<b>-F</b>	Medio de algodón en ovillo o fieltro	<b>-W</b>	Con envoltura, aplicaciones de temperaturas frías - Invierno
<b>-FF</b>	Elemento de lubricación de flujo pleno	<b>-WO</b>	Sin - Véase las especificaciones
<b>-FN</b>	Filtro de aire con aletas	<b>-WPC</b>	Con Pre-limpiador
<b>-FP</b>	Contiene orificio de entrada	<b>XP</b>	Rendimiento extremo

\* Véase el número específico en la Guía de Productos para observar los detalles y excepciones.

---

**NOTES**

---

# TRUCK APPLICATIONS

Trucks, Buses, Vans, Motor Homes,  
Truck Engines, Related Equipment

## **Alphabetically by Make**

All trucks (medium to heavy-duty), buses, vans, motor homes, truck engines and related equipment are listed in this section alphabetically by make. (Light-duty trucks are listed in the Automotive Section of this catalog in year sequence.)

Names starting with initials are listed under the last name, while names which are initials only are listed as if the initials spelled a word. Therefore, G.H. Tennant is listed under "T". Wherever the possibility of confusion may exist, a reference to the correct listing will be found in this section.

## **Alphabetically by Model Name**

Within each make, all models are arranged alphabetically.

## **By Engine Make**

Under each model, the engines are listed according to make and then size, from the smallest to the largest engines. If you don't know the model of the equipment, refer to the engine listing in this section.

## **Optional Filters**

Optional filters often appear at the beginning of the list ahead of the first model listing. Refer to the Baldwin Cross-Reference Catalogs (Form 560, Form 561) or the Baldwin Electronic Catalog on the internet at [www.baldwinfilter.com](http://www.baldwinfilter.com) if you have an Original Equipment (OE) or competitive part number.

## **Engine Listing**

Not all air filters are listed under the engine listing. Refer to the Baldwin Cross-Reference Catalogs (Form 560, Form 561) or the Baldwin Electronic Catalog on the internet at [www.baldwinfilter.com](http://www.baldwinfilter.com) if you have an Original Equipment (OE) or competitive part number.

## **NUMBERS IN BRACKETS OR PARENTHESES**

The number in square brackets in front of our bold face part number shows the quantity for a single change per piece of equipment. If the number is in parentheses at the close of our part number, that is the quantity included in the package and sold as a unit.

A number in parentheses ahead of our part number is the Original Equipment number for that filter. Verify that the OE number is the same on your piece of equipment before use. If the OE number is different on your equipment, refer to the Baldwin Cross-Reference Catalogs (Form 560, Form 561) or the Baldwin Electronic Catalog on the internet at [www.baldwinfilter.com](http://www.baldwinfilter.com) for the proper replacement filter. Help us make a better catalog by letting the Baldwin Catalog Department know of any exceptions.

## **MEANING OF SYMBOLS USED IN THIS SECTION**

When there are variations of a Baldwin product, a plus sign (+) (BF957+) indicates you can find these variations in the Baldwin Product Guide Catalog (Form 562) or the Baldwin Electronic Catalog on the internet at [www.baldwinfilter.com](http://www.baldwinfilter.com).

Numbers representing screens or other permanent filters (not replaced by Baldwin) are marked CLN&R (Clean and Reuse) if they have been reported as capable of being cleaned and reused. Baldwin cannot be responsible for such reuse.

## **IMPORTANT NOTICE**

All product applications and specifications in Baldwin catalogs are based upon the most authoritative information available at the time of publication. However, there are many filter options offered by equipment manufacturers during a given model year making it impossible to be absolutely certain that all equipment of the same make, model and year will use the same filter. For this reason, we cannot be responsible for misapplications.

Original equipment manufacturer's tradenames or trademarks are for identification purposes only. There is no affiliation, sponsorship or connection with the original equipment parts or manufacturer.

## استخدامات عربات النقل

عربات النقل والحافلات وعربات النقل الخفيف المغطاة و المنازل النقالة ومحركات مركبات النقل والمعدات المتعلقة بذلك.

الأعداد التي بين الأقواس المربعة أو الأقواس الهلالية يبين العدد الذي بين القوسين المرعيين [ ] أمام أحد أرقام أصنافنا الواردة بالبُنت الثقل القيمة لكل تعديل في قطعة من المعدات. أما إذا كان العدد بين القوسين الهلاليين "()" ويتبع رقم صنفنا، فإنه يدل على الكمية الموجودة في العبوة والمباعة كوحدة واحدة.

والعدد إذا كان بين القوسين الهلاليين "()" ويسبق رقم صنفنا، فهو رقم المعدات الأصلية لهذا المرشح. تحقق من مطابقة رقم المعدات الأصلية (OE) للرقم الذي على ألتك قبل الاستخدام. فإذا كان رقم المعدات الأصلية (OE) الذي على ألتك مختلفاً، يمكنك النظر في كتالوج بولدوين للإسناد المفهرس Baldwin Cross-Reference Catalogs (نموذج رقم 561/560) أو كتالوج بولدوين الإلكتروني Baldwin Electronic Catalog على شبكة الإنترنت على الموقع [www.baldwinfilter.com](http://www.baldwinfilter.com) للعثور على المرشح البديل المناسب. نرجو أن تساعدنا على تحسين الكتالوجات بأن تخبر قسم الكتالوجات Baldwin Catalog Department بأي أخطاء تجدها.

### معاني الرموز المستخدمة في هذا الجزء

عند وجود منتج لبولدوين Baldwin متوفر في صور مختلفة، سوف تدل علامة الجمع (+) (BF957+) على وجود هذه الصور المختلفة في كتالوج دليل المنتجات Guide Catalog Product (نموذج رقم 562) أو في كتالوج بولدوين الإلكتروني Baldwin Electronic Catalog على شبكة الإنترنت على الموقع [www.baldwinfilter.com](http://www.baldwinfilter.com).

وتدل علامة النجمة (\*) على توافر نوع من المنتج بعمر أطول. يشار إلى أرقام المصافي أو غيرها من المرشحات الدائمة (لا تستبدل ببولدوين Baldwin) بعلامة CLN&R إذا ورد أنها قابلة للتنظيف وإعادة الاستخدام. لا يمكن لشركة بولدوين Baldwin تحمل إعادة الاستخدام هذه.

### تنبيه هام

تدرج جميع استخدامات المنتجات ومواصفاتها في كتالوجات بولدوين (Baldwin) بناءً على أحدث معلومات موثوق بها متوفرة في وقت النشر. ومع ذلك فهناك العديد من الاختيارات الخاصة بالمرشحات التي يمنحها منتج المعدات خلال العام الذي ينتج فيه طراز معين، مما يستحيل معه التيقن التام من أن جميع المعدات من نفس النوع والطراز والسنة ستستخدم نفس المرشح. ولهذا فإننا لا نستطيع تحمل مسؤولية حالات الاستخدامات الخاطئة.

الأسماء التجارية والعلامات التجارية الخاصة بمنتجي المعدات الأصلية واردة للتعريف فقط. لا يوجد ارتباط أو انتساب أو علاقة مع منتجي قطع الغيار الأصلية أو الشركة المصنعة الأصلية.

### الترتيب الهجائي حسب النوع

جميع الشاحنات (من النقل المتوسط إلى النقل الثقيل) والحافلات والبيوت النقالة ومحركات الشاحنات والمعدات المتعلقة بها مدرجة في هذا الجزء بالترتيب الهجائي حسب النوع. (عربات النقل الخفيف مدرجة في الجزء الخاص بالمركبات في هذا الكتالوج حسب ترتيب السنة)

تدرج الأسماء التي تبدأ بالأحرف الأولى حسب اسمها الأخير. أما الأسماء التي تتكون فقط من أحرف متقطعة، فهي تدرج كما لو كانت هذه الأحرف تكون كلمة. وبناءً على ذلك يدرج اسم G H Tennant تحت حرف "T" (حسب الاسم الأخير Tennant) وفي حالة الالتباس المحتمل يمكن العثور على البيانات الصحيحة في هذا الجزء.

### بالترتيب الهجائي حسب اسم الطراز

داخل قائمة كل نوع يتم الترتيب هجائياً حسب اسم الطراز. فإذا احتوى اسم الطراز على أرقام تمثل اسم الطراز أو جزءاً منه، يكون ترتيبه رقمياً بعد أسماء الطراز المرتبة هجائياً.

### حسب نوع المحرك

وتحت كل طراز تدرج المحركات بترتيب أنواعها ثم سعتها من الأصغر فالأكبر إلى أكبرها سعة. فإن لم تكن تعرف اسم طراز الآلة، فعليك مراجعة بيانات المحرك في هذا الجزء.

### المرشحات الإضافية

كثيراً ما تظهر المرشحات الإضافية (الاختيارية) في بداية القائمة قبل أول طراز مسرد. أنظر كتالوج بولدوين للإسناد المفهرس Baldwin Cross-Reference Catalogs (نموذج رقم 561/560) أو كتالوج بولدوين الإلكتروني Baldwin Electronic Catalog على شبكة الإنترنت على الموقع [www.baldwinfilter.com](http://www.baldwinfilter.com) إذا كان لديك رقم صنف لمعدات أصلية (OE) أو مضاهية.

### مسرد المحركات

لا يحتوي مسرد المحركات على جميع المرشحات. أنظر كتالوج بولدوين للإسناد المفهرس Reference Catalogs - Baldwin Cross (نموذج رقم 561/560) أو كتالوج بولدوين الإلكتروني Baldwin Electronic Catalog على شبكة الإنترنت على الموقع [www.baldwinfilter.com](http://www.baldwinfilter.com) إذا كان لديك رقم صنف لمعدات أصلية (OE) أو مضاهية.

# 卡车应用

卡车、大轿车、箱型车、旅行车、  
卡车引擎、有关设备

## /按厂牌字母列出

所有卡车、大轿车、箱型车、旅行车、卡车引擎及有关设备在本节中按厂牌字母列出。以缩写开头的名称列在姓的下面，而如果名字只是缩写，则将缩写当作一个词来处理。

因此，G. H. Tennant列在“T”下面。M & W列在M末尾的“MW”下面。如有混淆不清之处，在本节中有正确排列的参考资料。

## 按型号名称字母列出

在每种厂牌内，所有型号均按字母排列。

## 按引擎厂牌列出

在每种型号下面，引擎按厂牌然后按规格从最小引擎到最大引擎列出。如果您不知道设备型号，请参考本节中的引擎名单。

## 可选滤清器

可选滤清器往往出现在名单开始时，在第一批型号清单之前。如果您有原厂设备(OE)或竞争者零件编号的话，参考 Baldwin 互查目录(表格560-13, 表格561-13) 或互联网www.baldwinfilter.com 上的Baldwin 电子目录。

## 引擎名单

并非所有空气滤清器都列在引擎名单中。如果您有原厂设备(OE)或竞争者零件编号的话，参考 Baldwin 互查目录(表格560-13, 表格561-13) 或互联网www.baldwinfilter.com 上的Baldwin 电子目录。

## 方括号或圆括号中的数字

我们粗体字零件号前面方括号中的数字表示每台设备一次更换的数量。如果数字在我们零件号后面的括号中，该数字表示一套的数量，只供成套销售。

我们零件号前面括号中的数字是该滤清器的原厂设备号。使用前请核对确认该OE号码和您设备上的号码时一致的。如果OE号码跟您设备上的号码不同，请参阅 Baldwin 互查目录(表格560-13, 表格561-13) 或互联网www.baldwinfilter.com 上的Baldwin 电子目录，以找到适当的替换滤清器。如果有任何例外情况，请通知 Baldwin 目录部，以便修改，把目录编得更完善。

## 本节中所用符号的意义

如果一种Baldwin产品有几种变型，则示以加号(+), 如(BF957+), 表示您可以在Baldwin产品指导目录(表格562-13) 或互联网www.baldwinfilter.com 上的Baldwin 电子目录中找到这些变型。

如果滤网或其它永久性滤清器据(不由Baldwin产品更换) 报告可以清洁后再用，代表它们的数字上标有CLN&R(清洁和重新使用) 字样。Baldwin不能对这种重新使用的情况负责。

## 重要通知

Baldwin目录中的所有产品应用及规格均根据出版时能够搜集到的最权威资料。然而，在给定型号年份中设备制造厂商提供许多滤清器选项，无法绝对肯定所有同一厂牌、型号和年份的设备都使用同一滤清器。因此，本公司不能对误用负责。

原设备生产厂的商品名或商标仅用于识别之目的，与原始设备零件或厂商并无附属、资助或其它关系。

# APPLICATIONS POUR CAMIONS

Camions, Bus, Fourgons, Motor-Homes, Moteurs de camions, Équipement apparenté

## Par ordre alphabétique par marque

Tous les camions (de poids moyen à gros tonnage), bus, fourgons, motor-homes, moteurs de camion et l'équipement apparenté sont classés dans cette section par ordre alphabétique et par marque. (Les camions légers sont indiqués dans la section Automobile par année de ce catalogue.)

Les noms commençant par des initiales sont classés sous le nom principal tandis que les noms qui ne sont composés que d'initiales sont classés comme si les initiales formaient un nom. Donc, G.H. Tennant est donné sous "T". Quand il y a possibilité de confusion, cette section donne une référence pour le nom correct.

## Par ordre alphabétique par nom de modèle

Pour chaque marque, tous les modèles sont classés par ordre alphabétique.

## Par marque de moteur

Pour chaque modèle, les moteurs sont classés par marque puis par cylindrée, du plus petit au plus gros. Si vous ne connaissez pas le modèle de l'équipement, veuillez consulter la liste des moteurs de cette section.

## Filtres en option

Les filtres en option apparaissent souvent au début de la liste, avant le premier modèle. Consultez la section Numéros de renvoi du catalogues Baldwin (Form 560, Form 561) ou le Catalogue électronique Baldwin disponible sur le web à [www.baldwinfilter.com](http://www.baldwinfilter.com) si vous avez le numéro de pièce d'un concurrent ou du fabricant d'origine (OE).

## Liste des moteurs

Tous les filtres ne sont pas indiqués dans la liste des moteurs. Consultez la section Numéros de renvoi du catalogues Baldwin (Form 560, Form 561) ou le Catalogue électronique Baldwin disponible sur le web à [www.baldwinfilter.com](http://www.baldwinfilter.com) si vous avez le numéro de pièce d'un concurrent ou du fabricant d'origine (OE).

## NUMÉROS ENTRE CROCHETS OU PARENTHÈSES

Le numéro entre crochets devant notre numéro de pièce en caractères gras indique la quantité pour un remplacement unique par pièce d'équipement. Tout nombre entre parenthèses à la fin du numéro de pièce indique la quantité incluse dans le paquet et vendue comme unité.

Un nombre entre parenthèses devant notre numéro de pièce correspond au numéro d'équipement d'origine pour ce filtre. Si le numéro d'équipement d'origine est différent sur votre engin, consultez la section Numéros de renvoi du catalogues Baldwin (Form 560, Form 561) ou le Catalogue électronique Baldwin disponible sur le web à [www.baldwinfilter.com](http://www.baldwinfilter.com) pour obtenir le filtre de rechange correct. Aidez-nous à créer un meilleur catalogue en indiquant ces exceptions au Service Catalogues de Baldwin.

## SIGNIFICATION DES SYMBOLES UTILISÉS DANS CETTE SECTION

Quand il existe des variations pour un produit Baldwin, un signe plus (+) (BF957+) indique que vous pouvez trouver ces variations dans la section Guide des produits du catalogue Baldwin (Form 562) ou le Catalogue électronique Baldwin disponible sur le web à [www.baldwinfilter.com](http://www.baldwinfilter.com).

Les numéros représentant les crépines et autres filtres permanents (pas remplacés par Baldwin) sont identifiés par CLN&R s'il a été déterminé qu'ils peuvent être nettoyés et réutilisés. Baldwin ne saurait être tenu responsable de leur réutilisation.

## AVIS IMPORTANT

Tous les renvois de ce catalogue sont basés sur les informations les plus récentes disponibles à la mise sous presse. Cependant, les fabricants d'équipement changent fréquemment de fournisseurs de composants sans préavis, tout en continuant à utiliser le même numéro de filtre. Ce changement peut changer une dimension non-critique en dimension critique. D'autres fabricants de filtres peuvent utiliser un filtre pour remplacer deux des nôtres. Par conséquent, à partir d'un numéro de filtre de fabricant autre que le fabricant d'origine, un problème peut apparaître. Si un filtre n'est pas étanche après installation, il ne doit pas être utilisé. Nous ne pouvons pas être tenus responsables des mauvaises applications.

Les marques et noms de fabricant d'équipement d'origine ne sont utilisés que pour des raisons d'identification. Il n'existe aucune affiliation, parrainage ou connexion avec le fabricant d'équipement d'origine ou ses pièces.

# LASTKRAFTWAGEN- PRODUKTE

Lkw, Busse, Kleinbusse, Wohnmobile,  
Lkw-Motoren, ähnliche Aggregate

## **Alphabetisch nach Marke**

Alle Lkw (mittelschwer bis schwer), Busse, Kleinbusse, Wohnmobile, Lkw-Motoren und ähnliche Aggregate sind in diesem Abschnitt alphabetisch nach Markennamen aufgeführt. (Kleinlastkraftwagen sind im Pkw-Abschnitt dieses Katalogs nach Modelljahr aufgelistet.)

Marken, die mit Buchstaben beginnen, werden unter dem letzten Namen (bzw. Nachnamen) aufgeführt, während reine Abkürzungen nach dem ersten Buchstaben eingeordnet sind. Beispiele: G.H. Tennant ist unter "T" aufgeführt. Wo Verwechslungsgefahr besteht, verweist eine entsprechende Anmerkung auf den richtigen Eintrag in diesem Abschnitt.

## **Alphabetisch nach Modellnamen**

Zu jeder Marke sind die Modelle in alphabetischer Reihenfolge aufgeführt.

## **Nach Motorhersteller**

Zu jedem Modell sind die Motoren nach Hersteller und Größe aufgelistet, vom kleinsten bis zum größten Motor. Falls Sie das Modell der Ausführung nicht kennen, sehen Sie unter der Motoraufistung in diesem Abschnitt nach.

## **Optionale Filter**

Optionale Filter stehen oft am Anfang der Liste vor dem ersten Modell. In der Baldwin-Referenz (Form 560, Form 561), im elektronischen Baldwin-Katalog oder im Internet unter [www.baldwinfilter.com](http://www.baldwinfilter.com) können Sie Teilenummern von Originalteilen oder Konkurrenzprodukten nachschlagen.

## **Motorenliste**

Unter den Motoren sind nicht alle Luftfilter aufgelistet. In der Baldwin-Referenz (Form 560, Form 561), im elektronischen Baldwin-Katalog oder im Internet unter [www.baldwinfilter.com](http://www.baldwinfilter.com) können Sie Teilenummern von Originalteilen oder Konkurrenzprodukten nachschlagen.

## **ZAHLEN IN RECHTECKIGEN ODER RUNDEN KLAMMERN**

Die Zahl in der rechteckigen Klammer vor der fett gedruckten Teilenummer gibt die benötigte Stückzahl für einen Austausch pro Fahrzeugteil an. Eine Zahl am Ende unserer Teilenummer in runden Klammern gibt die Stückzahl pro Verpackungseinheit wieder.

Eine Zahl in runden Klammern vor unserer Ersatzteilnummer ist die Originalteilnummer (OE-Nummer) für den Filter. Vor Gebrauch prüfen, ob die OE-Nummer an Ihrem Fahrzeugteil mit dieser Nummer identisch ist. Ist dies nicht der Fall, suchen Sie den richtigen Ersatzfilter bitte in der Referenz (Form 560,

Form 561). Sie würden uns helfen, den Katalog laufend zu verbessern, wenn Sie die Baldwin Katalogabteilung von solchen Abweichungen unterrichten.

## **BEDEUTUNG DER IN DIESEM ABSCHNITT VERWENDETEN SYMBOLE**

Wenn es verschiedene Varianten eines Baldwin-Produkts gibt, zeigt ein Pluszeichen (+) (z. B. BF957+) an, dass Sie diese Varianten in der Produktübersicht des Baldwin-Katalogs (Form 562), im Baldwin-Elektronikkatalog oder im Internet unter [www.baldwinfilter.com](http://www.baldwinfilter.com) finden können.

Nummern für Siebe oder sonstige Permanentfilter (für die Baldwin keine Ersatzteile liefert) sind mit dem Kürzel CLN&R markiert ("Clean and reuse", reinigen und wieder einbauen). Zwar wird dieser Kürzel nur verwendet, wenn diese Teile nach dem Kenntnisstand von Baldwin gereinigt und wiederverwendet werden können, jedoch übernimmt Baldwin hierfür keinerlei Haftung.

## **WICHTIGER HINWEIS**

Alle Querverweise in diesem Katalog basieren auf den neuesten zum Zeitpunkt des Drucks erhältlichen Informationen. Die Fahrzeughersteller wechseln jedoch oftmals Teilezulieferer ohne Ankündigung und benutzen trotzdem weiterhin die gleiche Filternummer. Durch diese Änderung kann eine scheinbar unwichtige Abmessung auf einmal bedeutsam werden. Andere Filterhersteller könnten z.B. einen Filter verwenden, der zwei unserer Filter ersetzt. Suchen Sie daher nach der Filternummer eines nicht originalen Filters, kann dies oftmals zu einem Problem führen. Schließt ein Filter nicht dicht ab, wenn er eingesetzt wird, so sollte er nicht verwendet werden. Wir haften nicht für falsche Verwendung.

Die Handelsnamen oder Handelsmarken der Originalteilehersteller werden nur zu Identifikationszwecken angegeben. Es besteht keine Angliederung, Förderung oder Verbindung mit dem Originalteil oder dem Hersteller.



# APPLICAZIONI RELATIVE AGLI AUTOCARRI

Autocarri, autobus, furgoni, motor home,  
motori per autocarri, apparecchiature correlate

## **In ordine alfabetico per marca**

In questa sezione, tutti gli autocarri (da mediopesanti a pesanti), gli autobus, i furgoni, i motor home, i motori di autocarri e le relative apparecchiature sono elencati in ordine alfabetico per marca. (Gli autocarri leggeri sono elencati per anno nella sezione "Autoveicoli" del catalogo.)

I nomi che cominciano con iniziali sono elencati in base all'ultimo nome, mentre i nomi costituiti soltanto da iniziali sono elencati considerando che le iniziali formano una parola. Pertanto, G.H. Tennant è riportato in "T". In caso di possibilità di confusione, nella sezione è riportato un riferimento all'elencazione corretta.

## **In ordine alfabetico per nome di modello**

Nell'ambito di ciascuna marca, tutti i modelli sono disposti in ordine alfabetico.

## **Per marca di motore**

Nell'ambito di ciascun modello, i motori sono elencati in base alla marca e alla cilindrata, dai più piccoli ai più grandi. Se non si conosce il modello dell'apparecchiatura, fare riferimento all'elenco dei motori in questa sezione.

## **Filtri facoltativi**

Spesso i filtri facoltativi sono riportati all'inizio dell'elenco, davanti al primo modello. Consultare il Baldwin Cross-Reference Catalogs (Catalogos riferimenti incrociati di Baldwin) (Form 560, Form 561) oppure il Baldwin Electronic Catalog (Catalogo elettronico Baldwin) sul sito Internet [www.baldwinfilter.com](http://www.baldwinfilter.com) se si dispone di un'apparecchiatura originale (OE, Original Equipment) o di un numero pezzo concorrente.

## **Elenco motori**

Non tutti i filtri dell'aria sono presenti nell'elenco motori. Consultare il Baldwin Cross-Reference Catalogs (Catalogos riferimenti incrociati di Baldwin) (Form 560, Form 561) oppure il Baldwin Electronic Catalog (Catalogo elettronico Baldwin) sul sito Internet [www.baldwinfilter.com](http://www.baldwinfilter.com) se si dispone di un'apparecchiatura originale, (OE, Original Equipment) o di un numero pezzo concorrente.

## **NUMERI IN PARENTESI**

Il numero in parentesi quadre che precede il nostro numero pezzo in grassetto indica la quantità necessaria per una singola sostituzione dell'apparecchiatura. Se il numero è in parentesi al termine del nostro numero pezzo, esso rappresenta la quantità inclusa nella confezione e venduta come unità.

Un numero in parentesi davanti al nostro numero pezzo rappresenta il numero apparecchiatura originale per quel filtro.

Prima dell'uso, verificare che il numero apparecchiatura originale corrisponda a quello sull'apparecchiatura. In caso contrario, consultare il Baldwin Cross-Reference Catalogs (Catalogos riferimenti incrociati di Baldwin) (Form 560, Form 561) oppure il Baldwin Electronic Catalog (Catalogo elettronico Baldwin) sul sito Internet [www.baldwinfilter.com](http://www.baldwinfilter.com) per cercare il filtro sostitutivo corretto. Aiutateci a migliorare il catalogo comunicando eventuali eccezioni all'Ufficio Catalogo di Baldwin.

## **SIGNIFICATO DEI SIMBOLI UTILIZZATI IN QUESTA SEZIONE**

Se ci sono variazioni a un prodotto Baldwin, il segno più (+) (BF957+) indica che tali variazioni sono riportate nel Baldwin Product Guide Catalog (Catalogo Guida Prodotto di Baldwin) (Form 562) oppure nel Baldwin Electronic Catalog (Catalogo elettronico di Baldwin) sul sito internet [www.baldwinfilter.com](http://www.baldwinfilter.com).

I numeri che rappresentano schermi o altri filtri permanenti (non sostituiti da Baldwin) sono contrassegnati con CLN&R (Clean and Reuse, Pulire e riutilizzare) se sono stati indicati come idonei a essere puliti e riutilizzati. Baldwin non è responsabile di tale riutilizzo.

## **AVVISO IMPORTANTE**

Tutti i riferimenti incrociati presenti in questo catalogo si basano sulle informazioni più autorevoli disponibili al momento di andare in stampa. Tuttavia, i produttori di apparecchiature spesso cambiano i fornitori dei componenti senza preavviso, pur continuando a usare lo stesso numero filtro. Ne potrebbe quindi derivare che una dimensione non critica diventi critica. Altri produttori di filtri possono utilizzare un filtro per sostituire due nostri filtri. Pertanto, quando si effettua il riferimento incrociato da un numero filtro di apparecchiatura non originale, potrebbero verificarsi dei problemi. Non usare filtri che non chiudono a tenuta dopo l'installazione. Non siamo responsabili di usi impropri.

I nomi o i marchi di fabbrica del produttore di apparecchiature originali si intendono unicamente per scopi di identificazione. Non esistono affiliazioni, sponsorizzazioni né connessioni con i produttori né con i componenti di apparecchiature originali.

# APLICAÇÕES PARA CAMINHÕES

Caminhões, Ônibus, Peruas, Motor Homes, Motores de Caminhões, Equipamentos Relacionados

## **Ordem alfabética, por marca**

Todos os caminhões (para serviço médio a pesado), ônibus, peruas, motor homes, motores de caminhões e equipamentos relacionados estão listados nesta seção em ordem alfabética, por marca. (Os caminhões leves estão listados na Seção Automotiva deste catálogo em seqüência, por ano).

Os nomes que começam por iniciais estão listados pelos últimos nomes, enquanto os nomes que são apenas iniciais estão listados como se estas constituíssem uma palavra. Assim, G.H. Tennant, está listado como "T". Sempre que houver possibilidade de confusão, será encontrada nesta seção uma referência para a listagem correta.

## **Ordem alfabética, por nome do modelo**

Dentro de cada marca, todos os modelos estão classificados alfabeticamente.

## **Por marca de motor**

Para cada modelo, os motores estão listados de acordo com a marca e em seguida o tamanho, do menor para o maior. Se você não conhece o modelo do equipamento, poderá recorrer à listagem de motores desta seção.

## **Filtros opcionais**

Freqüentemente, aparecem filtros opcionais no início da lista, à frente da listagem do primeiro modelo. Consulte o Catálogos de Referência Cruzada Baldwin (Form 560, Form 561) ou o Catálogo Eletrônico Baldwin na Internet, no endereço [www.baldwinfilter.com](http://www.baldwinfilter.com) se você tiver um número de peça de Fabricante Original (OE) ou da concorrência.

## **Alistamento de motor**

Nem todos os filtros estão listados sob a listagem de motores. Consulte o Catálogo de Referência Cruzada Baldwin (Form 560, Form 561) ou o Catálogo Eletrônico Baldwin na Internet, no endereço [www.baldwinfilter.com](http://www.baldwinfilter.com) se você tiver um número de peça de Fabricante Original (OE) ou da concorrência.

## **NÚMEROS ENTRE COLCHETES OU PARÊNTESES**

O número entre colchetes à frente do nosso número de peça em negrito significa a quantidade necessária para uma única troca de filtros por equipamento. Se o número estiver entre parênteses, em seguida ao nosso número de peça, indica que esta é a quantidade incluída na embalagem e vendida como uma unidade.

Um número entre parênteses à frente do nosso número de peça é o número do equipamento original para este filtro. Verifique se o número OE é o mesmo do seu equipamento

antes da utilização. Se o número OE for diferente no seu equipamento, consulte o Catálogos de Referência Cruzada Baldwin (Form 560, Form 561) ou o Catálogo Eletrônico Baldwin na Internet, no endereço [www.baldwinfilter.com](http://www.baldwinfilter.com), para obter o filtro de reposição correto. Ajude-nos a fazer uma catálogo melhor informando o Departamento de Catálogos da Baldwin sobre quaisquer exceções.

## **SIGNIFICADO DOS SÍMBOLOS UTILIZADOS NESTA SEÇÃO**

Quando houver variações num produto Baldwin, um sinal de (+) (BF957+) indica que você poderá encontrá-las no Catálogo de Guia de Produtos Baldwin (Form 562) ou no Catálogo Eletrônico Baldwin na Internet, no endereço [www.baldwinfilter.com](http://www.baldwinfilter.com).

Os números que representam telas ou outros filtros permanentes (não substituídos pela Baldwin) estão marcados com CLN&R (Limpar e Reutilizar) se puderem ser limpos e reutilizados. A Baldwin não se responsabiliza por este tipo de reutilização.

## **AVISO IMPORTANTE**

Todas as referências cruzadas presentes neste catálogo têm por base as últimas informações disponíveis no momento da publicação. Contudo, os fabricantes de equipamentos freqüentemente modificam os seus fornecedores de componentes sem prévio aviso e continuam se utilizando do mesmo número de filtro. Esta modificação poderia resultar em tornar uma dimensão não crítica em crítica. Outros fabricantes de filtros podem usar um filtro para substituir dois dos nossos. Portanto, quando se está procurando uma referência cruzada a partir de um número de filtro de equipamento não original, poderá surgir algum problema. Se um filtro não vedar corretamente quando instalado, não deverá ser utilizado. Não podemos nos responsabilizar por aplicações incorretas.

Os nomes ou marcas comerciais dos fabricantes de equipamentos são apenas para fins de identificação. Não há relacionamento, patrocínio ou conexão com as peças dos equipamentos originais ou com o fabricante.

# ПРОДУКЦИЯ — ДЛЯ ГРУЗОВОГО АВТОТРАНСПОРТА

Грузовые автомашины, автобусы, микроавтобусы, жилые автофургоны, двигатели для грузового автотранспорта, вспомогательное оборудование

## В алфавитном порядке по наименованию предприятия-изготовителя

Все грузовые автомобили (включая средне- и большегрузные), автобусы, микроавтобусы, жилые автофургоны, двигатели для грузового автотранспорта и изделия вспомогательного оборудования указываются в данном разделе в алфавитном порядке по наименованию предприятия-изготовителя. (—анные по легким грузовым автомобилям приведены в разделе автомобильной техники настоящего каталога в последовательности годов выпуска.)

Наименования, начинающиеся с инициалов, располагаются в порядке алфавита по первой букве фамилии, в то время как наименования, состоящие из одних инициалов, располагаются в алфавитном порядке так, как если бы инициалы составляли слово. Поэтому полное наименование "G.H. Tennant" указывается в перечне под буквой "Т". В тех случаях, когда существует некоторая вероятность перепутывания, в этом разделе можно найти ссылку на верный источник информации.

## В алфавитном порядке по наименованию марки изделия

В пределах перечня продукции одного изготовителя все марки изделий приводятся в алфавитном порядке.

## В алфавитном порядке по наименованию марки двигателя

В перечне для каждой марки двигателя указаны в порядке следования наименований предприятий-изготовителей с дополнительной разбивкой по типоразмерам: от самого маломощного к самому мощному двигателю. Если марка оборудования неизвестна, следует найти указательный перечень двигателей, приведенный в этом разделе.

## Вариантные исполнения фильтров

Вариантные исполнения фильтров часто указываются в начале перечня - перед сведениями о первой марке. Если известен каталожный номер комплектного оборудования или конкурирующего изделия, следует обратиться к Каталогу перекрестных ссылок фирмы "Болдуин" (форма - Form 560, Form 561) или к электронному каталогу, который размещен этой фирмой в глобальной сети "Интернет" и может быть найден по указателю [www.baldwinfilter.com](http://www.baldwinfilter.com).

## Перечень двигателей

В перечень двигателей включены не все воздушные фильтры. Если известен каталожный номер комплектного оборудования или конкурирующего изделия, следует обратиться к Каталогу перекрестных ссылок фирмы "Болдуин" (форма - Form 560, Form 561) или к электронному каталогу, который размещен этой фирмой в глобальной сети "Интернет" и может быть найден по указателю [www.baldwinfilter.com](http://www.baldwinfilter.com).

## ЧИСЛА, УКАЗАННЫЕ В КВАДРАТНЫХ ИЛИ КРУГЛЫХ СКОБКАХ

Числа, приведенные в квадратных скобках перед выделенным жирным шрифтом каталожным номером изделия фирмы "Болдуин", указывают количественный состав одного сменного комплекта на каждое изделие оборудования. Если число приведено в круглых скобках в конце каталожного номера изделия фирмы "Болдуин", оно соответствует количеству, входящему в комплектное оборудование и продаваемое как одно изделие.

Число, приведенное в круглых скобках перед каталожным номером

изделия фирмы "Болдуин", - это номер комплектного оборудования, в состав которого входит данный фильтр. Прежде чем использовать фильтр, следует убедиться в совпадении указанного номера комплектного оборудования с номером на приобретенном изделии. Если на приобретенном изделии указан иной номер комплектного оборудования, номер нужного сменного фильтра следует искать в Каталоге перекрестных ссылок фирмы "Болдуин" (форма - Form 560, Form 561) или в электронном каталоге, который размещен этой фирмой в глобальной сети "Интернет" и может быть найден по указателю [www.baldwinfilter.com](http://www.baldwinfilter.com). Получение отделом, выпускающим каталоги фирмы "Болдуин", сведений о любых случаях исключения поможет исправить недостатки каталога.

## СМЫСЛ СИМВОЛОВ, ИСПОЛЬЗУЕМЫХ В —АННОМ РАЗ—ЕЛЕ

При наличии вариантных исполнений какого-либо изделия фирмы "Болдуин" добавленный знак "плюс" (+), например BF957+, указывает на то, что сведения об этих модификациях следует искать в Справочнике по продукции фирмы "Болдуин" (форма - Form 562) или в электронном каталоге, который размещен этой фирмой в глобальной сети "Интернет" и может быть найден по указателю [www.baldwinfilter.com](http://www.baldwinfilter.com).

Номера, присвоенные сетчатым или иным несменным фильтрам (не подлежащим замене фирмой "Болдуин"), снабжаются дополнительным обозначением CLN&R (от "очистить и использовать повторно"), если они зарегистрированы как допускающие очистку и пригодные к повторному использованию. Фирма "Болдуин" не может взять на себя ответственность за подобное повторное использование.

## ВАЖНОЕ ПРИМЕЧАНИЕ

Все изделия, применяемые на автомобильном транспорте, а также спецификации, включенные в каталоги компании "Болдуин", приводятся с учетом наиболее авторитетных источников информации, существующих на дату публикации. Следует отметить, что для каждого модельного года изготовители оборудования предлагают множество типов фильтров, в связи с чем не представляется возможным гарантировать, что на всем оборудовании одной и той же марки, модели и года выпуска используется один и тот же фильтр. По этой причине мы не несем ответственности за неправильное применение фильтров.

Торговые арки и товарные знаки изготовителей комплектного оборудования приводятся исключительно в целях обозначения продукции. Отсутствует какая-либо принадлежность, поручительство или связь с элементами или изготовителями комплектного оборудования.

# APLICACIONES CAMIONERAS

Camiones, Autobuses, Vagones, Casas rodantes,  
Motores para camiones, Equipos conexos

## **Alfabeticamente por marca**

Todos los camiones (de servicio intermedio a pesado), vagones, autobuses, casas rodantes (móviles), motores de camiones y equipo asociado están ordenados alfabéticamente por marca en esta sección. (Las camionetas están listadas en la Sección Automotriz de este catálogo en secuencia de año.)

Los nombres que empiezan con iniciales están anotados por último nombre (equivalente a un apellido), mientras que los nombres compuestos únicamente de iniciales (acrónimos, siglas, etc.) están sorteados como vocablos normales. Cuando existe la posibilidad de una confusión, se hace una referencia en esta sección que facilita encontrar la partida.

## **Alfabeticamente por nombre del modelo**

Dentro de cada marca, todos los modelos están ordenados alfabéticamente.

## **De acuerdo al motor**

Para cada modelo, los motores están anotados de acuerdo a sus cilindradas, del más chico al más grande. Si se desconoce el número de modelo del equipo, véase el alistamiento del motor en esta sección.

## **Filtros opcionales**

Los filtros opcionales frecuentemente aparecen al comienzo de la lista delante del primer listado de modelos. Consulte el Catálogos de referencia cruzada de Baldwin (Form 560, Form 561) o el Catálogo Electrónico de Baldwin en la Internet en [www.baldwinfilter.com](http://www.baldwinfilter.com) si usted tiene el número de pieza del equipo original (OE) o de la competencia.

## **Lista de cilindrada**

No todos los filtros de aire aparecen en la lista bajo cilindrada. Consulte el Catálogos de referencia cruzada de Baldwin (Form 560, Form 561) o el Catálogo Electrónico de Baldwin en la Internet en [www.baldwinfilter.com](http://www.baldwinfilter.com) si usted tiene el número de pieza del equipo original (OE) o de la competencia.

## **NÚMEROS ENTRE CORCHETES O PARENTESIS**

El número entre corchetes antes de nuestro número de parte indica la cantidad requerida para un solo cambio para un equipo. Si el número está entre paréntesis después de nuestro número de pieza, entonces indica éste la cantidad de piezas incluidas dentro del paquete que se vende como unidad.

Un número entre paréntesis delante de nuestro número de pieza

corresponde al número del Equipo Original (OE) para ese filtro. Antes de instalarlo, verifique que el número OE sea igual al que aparece en su pieza de equipo. Si el número OE es diferente en su equipo, consulte el Catálogos de Referencia Cruzada de Baldwin (Form 560, Form 561) o el Catálogo Electrónico de Baldwin para el filtro de repuesto correspondiente. Ayúdenos a mejorar nuestro catálogo, informando al Departamento de Catálogos de Baldwin sobre cualquiera de estas excepciones.

## **SIGNIFICADO DE LOS SÍMBOLOS USADOS EN ESTA SECCIÓN**

Cuando existen variaciones de un producto Baldwin, un signo más (+) (BF957+) indica que usted puede encontrarlas en el Catálogo de la Guía de Productos de Baldwin (Form 562) o en el Catálogo Electrónico de Baldwin en la Internet en [www.baldwinfilter.com](http://www.baldwinfilter.com).

Los números que representan tamices u otros filtros permanentes (no reemplazados por Baldwin) están marcados CLN&R (Limpiar y Reutilizar) si se informa que pueden limpiarse y reutilizarse; Baldwin no puede aceptar responsabilidad por dicha reutilización.

## **NOTA IMPORTANTE**

Todas las referencias cruzadas en este catálogo están basadas en la información más reciente disponible en el momento de la publicación. Sin embargo, los fabricantes de equipos a menudo cambian de proveedores de componentes sin previo aviso y continúan usando el mismo número de filtro. Esto cambio podría dar por resultado la conversión de una dimensión no crítica en una crítica. Otros fabricantes de filtros a veces usan un filtro para sustituir a dos de los nuestros. Por lo tanto, cuando se estén haciendo averiguaciones a partir de un número de filtro de equipo no original, podrían surgir problemas. Si un filtro no cierra después de instalado, no deberá usarse. No podemos responsabilizarnos por aplicaciones incorrectas.

Los nombres comerciales o marcas registradas de los fabricantes de equipos se dan solamente para propósito de identificación. No existe ninguna afiliación, patrocinio o conexión con el fabricante o pieza de equipo original.

<p style="text-align: center;"><b>A.E.C. Trucks</b></p> <p>Models w/C.A.V. Bowl-less Filter <b>Can-Type Fuel</b>..... <b>BF825<sup>+</sup></b></p> <hr/> <p>Models w/7.7L Diesel Eng. <b>Lube</b>..... <b>P198</b> <b>Fuel Ele.</b>..... <b>PF838</b></p> <hr/> <p>AVT.1100/148 Dump Truck HDK, 4LA <b>Lube</b>..... <b>P176</b> <b>Fuel Ele.</b>..... <b>PF838</b></p> <hr/> <p>Models w/312, 410, 470, 590, 690 Eng. <b>Lube</b>..... <b>P198</b> <b>Fuel Ele.</b>..... <b>PF838</b></p> <hr/> <p>Mercury, Monarch, Monmouth <b>Lube</b>..... <b>P174</b></p> <hr/> <p style="text-align: center;"><b>ACF-BRILL Buses</b></p> <p>Models w/Cummins Eng. <b>F-F Lube Bag</b>..... <b>P996</b> <b>F-F Lube Ele.</b>..... <b>P999-HD</b> <b>F-F Lube Spin-on</b>..... <b>B196<sup>+</sup></b> <b>B-P Lube Ele.</b>..... <b>C750-E<sup>+</sup></b> <b>Fuel/Water Separator</b>..... <b>BF1212<sup>+</sup></b> <b>4 3/8 In. Fuel Spin-on</b>..... <b>BF948<sup>+</sup></b> <b>5 3/4 In. Fuel Spin-on</b>..... <b>BF957<sup>+</sup></b> <b>11 7/32 In. Fuel Spin-on</b>..... <b>BF596<sup>+</sup></b> <b>Breather Ele. (w/Turbo) (255963)</b> <b>PA643</b> <b>Breather Ele. (w/o Turbo)</b> <b>(256837)</b>..... <b>PA1627</b> <b>Turbocharger</b>..... <b>BT112</b></p> <hr/> <p>C27, C31, SU37 w/IHC Eng. <b>B-P Lube Sock</b>..... <b>CU406<sup>90</sup></b></p> <hr/> <p>C36, C40, 1C41, 1C41A, C44, C48, C51 w/Hall-Scott 180, 190, 477 Eng. <b>B-P Lube</b>..... <b>P52</b></p> <hr/> <p style="text-align: center;"><b>AERO-COACH Buses</b></p> <p>Early Models w/IHC 6 Cyl. RD450 Eng. <b>B-P Lube Sock</b>..... <b>CU406<sup>90</sup></b></p> <hr/> <p>D, DE, E, EFI, EFS, EFT, PB <b>Lube (Michiana SA12800)</b>..... <b>P52</b></p> <hr/> <p>DE, P29 Early Models w/IHC UD9, UD16 Eng. <b>Lube (376376-R91)</b>..... <b>PT72</b></p> <hr/> <p>P29, P41, P46 <b>Lube (Michiana SA12800)</b>..... <b>P52</b></p> <hr/> <p>P361, T361, T371, P411, T451 <b>B-P Lube Sock (Deluxe CU)</b>..... <b>CU406<sup>90</sup></b> <b>Lube (Michiana SA12800)</b>..... <b>P52</b> <b>Lube (Michiana SA15117)</b>..... <b>P54</b></p> <hr/> <p>P371, P372, P373 w/Continental U501 Eng. <b>Lube</b>..... <b>P42</b></p> <hr/> <p style="text-align: center;"><b>ALLIANCE Auxiliary Power Units (APU)</b></p> <p>Deluxe N83 UD500 w/Kubota Eng. <b>Fuel Ele. (ABPN83328802)</b>..... <b>PF872</b></p>	<p style="text-align: center;"><b>ALLIANCE Auxiliary Power Units (APU) (cont'd)</b></p> <p>Premium N83 UP600 w/Kubota Eng. <b>Lube (Alliance ABP/N10G-LF692)</b>..... <b>B7</b></p> <hr/> <p style="text-align: center;"><b>ALLIANZ Sweepers</b></p> <p>770 w/John Deere 4045T Eng. <b>Lube (T19044)</b>..... <b>BT259</b> <b>Fuel/Water Separator (RE62418)</b>..... <b>BF7673-D</b></p> <hr/> <p>3000 w/John Deere 4045T Eng. <b>Lube (T19044)</b>..... <b>BT259</b> <b>Fuel/Water Separator (RE62418)</b>..... <b>BF7673-D</b></p> <hr/> <p>4000 w/Cummins ISB Eng. <b>Lube (3937736)</b>..... <b>B7177</b></p> <hr/> <p>MS350 w/Cat C7 Eng. <b>Lube (1R1807)</b>..... <b>B7700<sup>+</sup></b> <b>Fuel (1R0751)</b>..... <b>BF7632</b> <b>Air Dryer (Bendix 107796)</b>..... <b>BA5377</b></p> <hr/> <p>MS350 w/Two Cat C7 Eng. <b>Lube (1R1807)</b>..... <b>[2] B7700<sup>+</sup></b> <b>Fuel (1R0751)</b>..... <b>[2] BF7632</b> <b>Air Dryer (Bendix 107796)</b>..... <b>BA5377</b></p> <hr/> <p>MS350 w/Cat 3126B Eng. <b>Lube (1R1807)</b>..... <b>B7700<sup>+</sup></b> <b>Fuel (1R0751)</b>..... <b>BF7632</b> <b>Air Dryer (Bendix 107796)</b>..... <b>BA5377</b> <b>Trans. (2 In. Kit) (Allison 29540493)</b>..... <b>PT9416-MPG KIT</b> <b>Trans. (4 In. Kit) (Allison 29540494)</b>..... <b>PT9415-MPG KIT</b></p> <hr/> <p>MS350 w/Two JD 5030T Eng. <b>Lube (RE519626)</b>..... <b>[2] B7306</b> <b>Fuel/Water Separator (RE508202)</b>..... <b>[2] BF7904-D</b> <b>Air Dryer (Bendix 107796)</b>..... <b>BA5377</b> <b>Trans. (2 In. Kit) (Allison 29540493)</b>..... <b>PT9416-MPG KIT</b> <b>Trans. (4 In. Kit) (Allison 29540494)</b>..... <b>PT9415-MPG KIT</b></p> <hr/> <p>MT350 w/Cat C7 Eng. <b>Lube (1R1807)</b>..... <b>B7700<sup>+</sup></b> <b>Fuel (1R0751)</b>..... <b>BF7632</b> <b>Air Dryer (Bendix 107796)</b>..... <b>BA5377</b></p> <hr/> <p>MT350 w/Two Cat C7 Eng. <b>Lube (1R1807)</b>..... <b>[2] B7700<sup>+</sup></b> <b>Fuel (1R0751)</b>..... <b>[2] BF7632</b> <b>Air Dryer (Bendix 107796)</b>..... <b>BA5377</b></p> <hr/> <p>MT350 w/Cat 3126B Eng. <b>Lube (1R1807)</b>..... <b>B7700<sup>+</sup></b> <b>Fuel (1R0751)</b>..... <b>BF7632</b> <b>Air Dryer (Bendix 107796)</b>..... <b>BA5377</b> <b>Trans. (2 In. Kit) (Allison 29540493)</b>..... <b>PT9416-MPG KIT</b> <b>Trans. (4 In. Kit) (Allison 29540494)</b>..... <b>PT9415-MPG KIT</b></p>	<p style="text-align: center;"><b>ALLIANZ Sweepers (cont'd)</b></p> <p>MT350 w/Two JD 5030T Eng. <b>Lube (RE519626)</b>..... <b>[2] B7306</b> <b>Fuel/Water Separator (RE508202)</b>..... <b>[2] BF7904-D</b> <b>Air Dryer (Bendix 107796)</b>..... <b>BA5377</b> <b>Trans. (2 In. Kit) (Allison 29540493)</b>..... <b>PT9416-MPG KIT</b> <b>Trans. (4 In. Kit) (Allison 29540494)</b>..... <b>PT9415-MPG KIT</b></p> <hr/> <p>MX450 w/John Deere 4045T Eng. <b>Lube (T19044)</b>..... <b>BT259</b> <b>Fuel/Water Separator (RE62418)</b>..... <b>BF7673-D</b></p> <hr/> <p>RT655 w/John Deere 4045T Eng. <b>Lube (T19044)</b>..... <b>BT259</b> <b>Fuel/Water Separator (RE62418)</b>..... <b>BF7673-D</b></p> <hr/> <p>VT650 w/John Deere 4045T Eng. <b>Lube (T19044)</b>..... <b>BT259</b> <b>Fuel/Water Separator (RE62418)</b>..... <b>BF7673-D</b></p> <hr/> <p>VT800 w/John Deere 4045T Eng. <b>Lube (T19044)</b>..... <b>BT259</b> <b>Fuel/Water Separator (RE62418)</b>..... <b>BF7673-D</b></p> <hr/> <p style="text-align: center;"><b>ALLIS CHALMERS Truck Engines</b></p> <p>3500, 3500 Mk II <b>Lube (4513411-1)</b>..... <b>[2] BT267</b> <b>Lube (4037047)</b>..... <b>[2] BT440</b> <b>Fuel</b>..... <b>BF962</b> <b>Turbocharger</b>..... <b>BT112</b></p> <hr/> <p>21000, 25000 <b>F-F Lube</b>..... <b>[2] P20-HD<sup>+</sup></b> <b>B-P Lube Ele. (500 Size)</b>..... <b>C704-L<sup>+</sup></b> <b>B-P Lube Ele. (750 Size)</b>..... <b>C750-E<sup>+</sup></b> <b>S. Fuel Ele. (4052172)</b>..... <b>PF910</b> <b>S. Fuel Ele. (4056633)</b>..... <b>PF906</b> <b>Fuel Spin-on</b>..... <b>[2] BF962</b> <b>Coolant Spin-on</b>..... <b>BW5139</b> <b>Turbocharger</b>..... <b>P80-HD</b></p> <hr/> <p style="text-align: center;"><b>ALLISON Transmissions</b></p> <p>Models w/Cooler Circuit Filters <b>Trans. Ele. (ACDelco PF132)</b>..... <b>P20-HD<sup>+</sup></b> <b>Trans. Ele. (ACDelco PF141)</b>..... <b>P18-HD</b> <b>Trans. Spin-on (ACDelco HD222)</b>..... <b>B252</b> <b>Trans. Spin-on (ACDelco PF897)</b>..... <b>BT230</b> <b>Trans. Spin-on (ACDelco PF911)</b>..... <b>B95<sup>+</sup></b></p> <hr/> <p>22 <b>Trans. (ACDelco P203)</b>..... <b>P40</b></p>
---	--	---

<sup>+</sup> See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.

Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

ALLISON Transmissions (cont'd)	ALLISON Transmissions (cont'd)	ALLISON Transmissions (cont'd)
103, 104 Trans. (ACDelco P209)..... P41	CRT5631, CLBT5660, CLBT5860, CLBT5960, CLBT6060 Trans. (ACDelco PF951)..... PT385 +	V730 Trans. Ele. (Glass Media) (23040988)..... PT8330-MPG Remote Mtd. Trans. Spin-on (25010643)..... BT359 Trans. Spin-on (Cooler Circuit) (25010495)..... B95 +
1000 & 2000 Series Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004 Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016 Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003 Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017 Trans. Spin-on (29539579)..... BT8460	Ev 40/50 Trans. Ele. (29545785)..... PT23127-MPG Trans. Spin-on (Control Main) (29539579)..... BT8460	VT730 Remote Mtd. Trans. Spin-on (690348)..... [2] B252
3000 Series Trans. (2 In. Kit) (29558117)..... PT9416-MPG KIT Trans. (4 In. Kit) (29558118)..... PT9415-MPG KIT	HT Series Trans. Ele. (Auxiliary) (29510918)..... PT8330-MPG	World Transmissions Trans. (2 In. Kit) (29526899)..... PT9416-MPG KIT Trans. (4 In. Kit) (29526898)..... PT9415-MPG KIT
4000 Series Trans. (2 In. Kit) (29540493)..... PT9416-MPG KIT Trans. (4 In. Kit) (29540494)..... PT9415-MPG KIT	HT70 Remote Mtd. Trans. Ele. (ACDelco PF132)..... P20-HD +	<b>AM GENERAL Buses</b> Models w/GMC 6V-71, 8V-71 Engs. F-F Lube Ele..... P20-HD + B-P Lube Ele..... P52 P. Fuel Spin-on..... BF5800 + S. Fuel Spin-on..... BF5810
5000, 6000, 8000, 9000 Series Trans. (Clean-up) (23018850)..... PT317-MPG Trans. (Clean-up) (23018853)..... PT320-MPG Trans. (Maintenance) (23018851)..... PT318-MPG Trans. (Maintenance) (23018852)..... PT319-MPG	HT700 5 21/32 In. Trans. Ele. (ACDelco PF141)..... P18-HD 9 1/16 In. Trans. Ele. (ACDelco PF132)..... P20-HD + Trans. Ele. (Glass Media) (23040988)..... PT8330-MPG Main Circuit Trans. Spin-on (25013612)..... BT359 Trans. Spin-on (690348)..... B252	<b>AMERICAN LAFRANCE Trucks</b> Models w/American LaFrance 020-900008 Hsg. Air..... PA2399
AT Series Trans. (3.8 In. Pan) (Allison 29540976)..... 19992 + Trans. (5.3 In. Pan) (29538489)..... 19739 +	HT740 Trans. (25010643)..... BT359	Models w/Donaldson P119297 Air..... PA2399
AT540, AT543 Trans. Pan-Type (6438326)..... 19992 + Trans. Ele. (Cooler Circuit) (5574540)..... P18-HD Trans. Spin-on (Cooler Circuit) (25011122)..... BT230	HT750 Trans. (25010643)..... BT359	Models w/Fram FBM1110PL Hsg. Fuel..... PF945
AT545 Trans. (3.8 In. Pan) (6438326)..... 19992 + Trans. (5.3 In. Pan) (25010355)..... 19739 + Trans. Ele. (Cooler Circuit) (5574540)..... P18-HD	MT Series Trans. Ele. (ACDelco PF133-1).... S16-1 Trans. Pan-Type (3.8 In. Pan) (6438326)..... 19992 + Trans. Pan-Type (5.3 In. Pan) (29538489)..... 19739 + Trans. Spin-on (Auxiliary) (29510922)..... BT8316-MPG	Models w/Power Steering Filters Steering (1956-on)..... P80-HD
CLBT750 Trans. Ele. (Glass Media) (23040988)..... PT8330-MPG Trans. Ele. (Paper Media) (ACDelco PF951)..... PT385 +	MT643, MT644, MT650, MT653, MT654 (MT600 Series) Trans. Ele. (Fiber Media) (25010355)..... 19739 + Trans. Ele. (Glass Media) (23040988)..... PT8330-MPG Trans. Ele. (Paper Media) (25012522)..... PT374 Trans. Spin-on (25010543)..... B252	800 Series Lube (1956-on)..... P52
CLT3440-7, CLT3460-7, CRT3531, CLBT4460 Trans. Ele. (Glass Media) (23040988)..... PT8330-MPG Remote Mtd. Trans. Ele. (ACDelco PF132)..... P20-HD +	Torqmatic Series Trans. (2 In. Kit) (29540493)..... PT9416-MPG KIT Trans. (4 In. Kit) (29540494)..... PT9415-MPG KIT	B Lube (1947-61)..... P42
CRT3321-1, CRT3321-3, CRT3331-1, CRT3340-7, CLT3360-7 Trans. Ele. (Glass Media) (23040988)..... PT8330-MPG Remote Mtd. Trans. Ele. (ACDelco PF132)..... P20-HD +	TT, TRT-1-2-4000 Trans. Ele. (Glass Media) (23040988)..... PT8330-MPG Trans. Ele. (Paper Media) (ACDelco PF951)..... PT385 +	C Lube (1957-66)..... P52 Air (1955-on)..... PA652
	TT2000 Remote Mtd. Trans. Ele. (ACDelco PF132)..... P20-HD +	Condor Radial Seal Air (Racor 500247-012)..... RS30313

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>AMERICAN LAFRANCE Trucks (cont'd)</b>	<b>AUTOCAR Trucks (cont'd)</b>	<b>AUTOCAR Trucks (cont'd)</b>
Fire Truck w/GMC 6V-53 Eng. (Cont'd) Air (1967)..... <b>PA1641</b>	A42B, A42F, S42B, S42F, A64B, A64F, S64B, S64F w/Cummins NH230 Eng. F-F Lube Ele..... <b>P999-HD</b> F-F Lube Spin-on..... <b>B196 +</b> Fuel Spin-on..... <b>BF957 +</b> Coolant..... <b>BW5071</b>	ACL w/Cat 3306 (10.5L) Eng. (Cont'd) Fuel Ele. (9M2341)..... <b>PF935</b> Fuel Spin-on (1R1740)..... <b>BF970 +</b> <b>3.05 In. O.D. Fuel Spin-on</b> (1R0750)..... <b>BF7637</b> <b>3.69 In. O.D. Fuel Spin-on</b> (1R0750)..... <b>BF7633 +</b>
<b>J</b> Lube (1947-66)..... <b>P42</b> Air (1955-61)..... <b>PA652</b> Air (1962-66)..... <b>PA653</b>	A42TB, A42TF, S42TB, S42TF, A64TB, A64TF, S64TB, S64TF w/Cummins NTC300 Eng. F-F Lube Spin-on..... <b>B196 +</b> B-P Lube Ele..... <b>C750-E +</b> Fuel Spin-on..... <b>BF957 +</b> Coolant..... <b>BW5071</b>	ACL w/Cat 3406 (14.6L) Eng. Lube (1R0716)..... <b>B99 +</b> Fuel (1R0749)..... <b>BF7587 +</b> Air..... <b>LL2685</b>
<b>K, L, M</b> Lube (To 1957) (303E1500)..... <b>P116</b> Lube (1957-66) (291E1758)..... <b>P42</b> Lube (1962-66) (801E1266)..... <b>P52</b> Air (1957-66)..... <b>PA653</b>	A42TB, A42TF, S42TB, S42TF, A64TB, A64TF, S64TB, S64TF w/Cummins KT450 Eng. F-F Lube Spin-on..... <b>[2] B196 +</b> B-P Lube Ele..... <b>C750-E +</b> Fuel Spin-on..... <b>BF957-D +</b> Coolant..... <b>BW5073</b>	ACL w/Cummins ISM Eng. Dual-Flow Lube (Std. Vers.) (Fleetguard LF9001)..... <b>BD7154 +</b> Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> Fuel/Water Separator (Fleetguard FS1000)..... <b>BF1259</b> Radial Seal O. Air (Standard) (Fleetguard AF25139M)..... <b>RS3518</b> Radial Seal XP O. Air (Upgrade) (DBA5069)..... <b>RS3518XP</b> Opt. Radial Seal I. Air (Fleetguard AF25345)..... <b>RS3519</b> Breather (3683918)..... <b>CV15000</b> Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
LAF w/Cummins M11 Eng. Dual-Flow Lube..... <b>BD103 +</b> Fuel/Water Separator..... <b>BF1259</b>	A42TB, A42TF, S42TB, S42TF, A64TB, A64TF, S64TB, S64TF w/Cummins M11 Eng. F-F Lube Spin-on..... <b>[2] B196 +</b> B-P Lube Ele..... <b>C750-E +</b> Fuel Spin-on..... <b>BF957-D +</b> Coolant..... <b>BW5073</b>	ACL w/Cummins L10 (10.0L) Eng. Dual-Flow Lube (3318853)..... <b>BD103 +</b> F-F Lube (Standard) (Fleetguard LF670SC)..... <b>B196 +</b> F-F Lube (Extended Life) (Fleetguard LF670SC)..... <b>B96 +</b> B-P Lube Spin-on (3304232)..... <b>B7577</b> Opt. Fuel/Water Separator (3308638)..... <b>BF1212 +</b> Fuel (154789)..... <b>BF957-D +</b> Coolant (w/4 Units BTA+) (3315116)..... <b>BW5071</b> Coolant (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b>
<b>N</b> Lube (1962-66) (801E1266)..... <b>P52</b> Air (1955-on)..... <b>PA652</b>	A64TB, A64TF, S64B, S64F, S64TB, S64TF w/Detroit Diesel 6-71, 6V-92, 8V-71, 8V-92 Series Eng. F-F Lube Ele..... <b>P20-HD +</b> F-F Lube Spin-on..... <b>B95 +</b> P. Fuel Spin-on..... <b>BF5800 +</b> S. Fuel Spin-on..... <b>BF5810</b>	ACL w/Cummins L14 (14.0L) Eng. Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309 +</b> Fuel/Water Separator (Fleetguard FS1000)..... <b>BF1259</b> Axial Seal Air (22005-5039)..... <b>LL2685</b> Radial Seal O. Air (Standard) (Fleetguard AF25139M)..... <b>RS3518</b> Radial Seal XP O. Air (Upgrade) (DBA5069)..... <b>RS3518XP</b> Opt. Radial Seal I. Air (Fleetguard AF25345)..... <b>RS3519</b> Coolant (w/23 Units BTA+) (Fleetguard WF2076)..... <b>BW5076</b> Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>V</b> Lube (1947-66)..... <b>P42</b> Air (1957-66)..... <b>PA653</b>	ACL w/Cat 3176 Eng. Lube (1R0716)..... <b>B99 +</b> Lube (1R0713)..... <b>BT230 +</b> Lube (1R0714)..... <b>[2] B75</b> Fuel Ele. (9M2342)..... <b>[2] PF935</b> Fuel Spin-on (1R1740)..... <b>BF970 +</b>	
<b>ASTRA Trucks</b>	ACL w/Cat 3208 (10.4L) Eng. Lube (1R0713)..... <b>[2] BT230 +</b> Lube (1R0714)..... <b>[2] B75</b> Lube (9L9200)..... <b>[2] BT364</b> Fuel/Water Separator (8N9803)..... <b>BF912</b> Fuel Ele. (9M2341)..... <b>PF935</b> Fuel Spin-on (1R0740)..... <b>BF970 +</b> <b>3.05 In. O.D. Fuel Spin-on</b> (1R0750)..... <b>BF7637</b> <b>3.69 In. O.D. Fuel Spin-on</b> (1R0750)..... <b>BF7633 +</b>	
HD9 w/Iveco Cursor 13 (Euro 4) Eng. Lube (2992544)..... <b>B7174-MPG</b> Fuel/Water Separator (2992662)..... <b>BF1365</b> Radial Seal O. Air (Don. P777871)..... <b>RS3826</b> Radial Seal I. Air (Don. P777875)..... <b>RS3827</b> Air Dryer (2992261)..... <b>BA5374 +</b>	ACL w/Cat 3306 (10.5L) Eng. Lube (w/Metal Wrapper) (5S0484)..... <b>PT7332</b> Lube (w/Paper Wrapper) (5S0484)..... <b>PT670</b> Lube (1R0716)..... <b>B99 +</b> Lube (Standard Vers.) (1R0739)..... <b>B76 +</b> Lube (Severe Service) (1R0739)..... <b>B76-SS +</b> Fuel/Water Separator Ele. (8N0205)..... <b>PF316</b> Fuel/Water Separator Box-Style (6N7617)..... <b>BF912</b> Fuel/Water Separator Spin-on (256-8753)..... <b>BF1259</b> Fuel (7W8910)..... <b>CLN&amp;R</b>	
<b>AUTOCAR Trucks</b>		
Models w/Fram Air Filter Hsg. Air (FA230PL)..... <b>PA617 +</b> Heavy Duty Air (FA230PLHD)..... <b>PA1700<sup>90</sup></b> Air (FA240PL)..... <b>PA616 +</b>		
Models w/White 6 Cyl. 185A Gas Eng. F-F Lube (To Late 1963)..... <b>P82 +</b> B-P Lube (To Late 1963)..... <b>P53</b>		
65T w/White 490 Eng. B-P Lube Ele. (1958-62)..... <b>C750-E +</b> Fuel Spin-on (Fleetguard FF104)..... <b>BF948 +</b> Air (1958-62)..... <b>PA617 +</b> Heavy Duty Air..... <b>PA1700<sup>90</sup></b>		
A42B, A42F, S42B, S42F, A64B, A64F, S64B, S64F w/Cat 1674 Eng. Lube..... <b>PT670</b> P. Fuel Ele..... <b>[2] PF935</b> Fuel Spin-on..... <b>BF970 +</b>		
A42B, A42F, S42B, S42F, A64B, A64F, S64B, S64F w/Cat 1693 Eng. Lube Spin-on..... <b>B99 +</b> Fuel Spin-on..... <b>[2] BF970 +</b>		

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.

Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

AUTOCAR Trucks (cont'd)	AUTOCAR Trucks (cont'd)	AUTOCAR Trucks (cont'd)
ACL w/Cummins N14 (14.0L) Eng. (Cont'd) Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	ACTT Xspotter w/Cummins B6.7 (6.7L) Eng. (2018) Lube (3937736)..... <b>B7177</b> <b>Fuel/Water Separator</b> (Fleetguard FS20081)..... <b>PF46171</b> Fuel (Fleetguard FF63009)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636)..... <b>CV15010</b> Trans. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	ACX Xpeditor w/Cummins ISM Eng. (Cont'd) <b>Radial Seal XP O. Air</b> (Upgrade) (DBA5069)..... <b>RS3518XP</b> <b>Opt. Radial Seal I. Air</b> (Fleetguard AF25345)..... <b>RS3519</b> <b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b> <b>Breather</b> (3683918)..... <b>CV15000</b> Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (38708-5002)..... <b>P528</b>
ACL w/Detroit Diesel Series 60 Eng. Lube (23530573)..... <b>[2] B495</b> P. Fuel (23530706)..... <b>BF5800 +</b> S. Fuel (23530707)..... <b>BF5810</b>	ACTT Xspotter w/Cummins B6.7 (6.7L) Eng. (2019) Lube (3937736)..... <b>B7177</b> Fuel (5303743)..... <b>BF63000</b> <b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b> <b>Crankcase Breather</b> (4936636)..... <b>CV15010</b> Trans. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	ACX w/Cummins ISX Eng. <b>Dual-Flow Lube</b> (Std. Vers.) (2882674)..... <b>BD7154 +</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> Fuel (2893612)..... <b>BF9885 +</b> Coolant (3680434)..... <b>B5087</b> <b>Diesel Exhaust Fluid</b> (5303604)..... <b>PE17000</b>
ACL w/Detroit Diesel 6V-92N (9.0L) Eng. Lube (23530407)..... <b>B95 +</b> Lube (23530408)..... <b>B95-MPG +</b> P. Fuel (23530706)..... <b>BF5800 +</b> S. Fuel (23530707)..... <b>BF5810</b> S. Fuel (23530645)..... <b>BF5815</b>	ACTT Xspotter w/Cummins ISB 6.7 (6.7L) Eng. (2019) Lube (3937736)..... <b>B7177</b> Fuel (5303743)..... <b>BF63000</b> <b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b> <b>Crankcase Breather</b> (4936636)..... <b>CV15010</b> Trans. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	ACX w/Cummins L9 (9.0L) Eng. (2019) Lube (3401544)..... <b>B40142</b> Fuel (5303743)..... <b>BF63000</b>
ACL w/Detroit Diesel 8V-71 (9.3L) Eng. Lube (23530407)..... <b>B95 +</b> Lube (23530408)..... <b>B95-MPG +</b> B-P Lube Ele. (23519155)..... <b>P52</b> 5 3/4 In. P. Fuel Sock (5574961)..... <b>F916-C</b> 8 5/16 In. P. Fuel Ele. (5575032)..... <b>PF845</b> 9 In. P. Fuel Sock (5574980)..... <b>F844-A</b> P. Fuel Spin-on (23530706)..... <b>BF5800 +</b> 5 5/8 In. S. Fuel Ele. (5574961)..... <b>PF916</b> 7 13/16 In. S. Fuel Ele. (5574508)..... <b>PF902</b> 8 1/4 In. S. Fuel Ele. (6436719)..... <b>PF846</b> S. Fuel Spin-on (23530707)..... <b>BF5810</b> S. Fuel Spin-on (23530645)..... <b>BF5815</b>	ACTT Xspotter w/Cummins QSB 6.7 (6.7L) Eng. (2019) <b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b> Trans. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	ACX 64 w/Cummins ISL Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> Fuel (4940647)..... <b>BF7924</b> <b>Air Dryer</b> (Bendix 65624)..... <b>BA5373</b> Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Diesel Exhaust Fluid</b> (2888182)..... <b>PE17000</b>
ACL w/Detroit Diesel 8V-92 (12.1L) Eng. Lube Ele. (23518666)..... <b>P20-HD +</b> Lube Spin-on (23530407)..... <b>B95 +</b> Lube Spin-on (23530408)..... <b>B95-MPG +</b> P. Fuel Ele. (9717391)..... <b>PF845</b> P. Fuel Spin-on (23530706)..... <b>BF5800 +</b> S. Fuel Ele. (23519152)..... <b>PF902</b> S. Fuel Spin-on (23530707)..... <b>BF5810</b> S. Fuel Spin-on (23530645)..... <b>BF5815</b>	ACX Xpeditor w/Cummins ISM Eng. <b>Dual-Flow Lube</b> (Std. Vers.) (Fleetguard LF9001)..... <b>BD7154 +</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (Fleetguard FS1000)..... <b>BF1259</b> <b>Axial Seal Air</b> (Fleetguard AF888M)..... <b>LL2326 +</b> <b>Radial Seal O. Air</b> (Standard) (Fleetguard AF25139M)..... <b>RS3518</b>	ACX 64 w/Cummins ISX Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> Fuel (Fleetguard FF63009)..... <b>BF63000</b> Trans. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Diesel Exhaust Fluid</b> (2888182)..... <b>PE17000</b>
ACL w/Volvo D12 (12.1L) Eng. <b>Fuel/Water Separator</b> (Alliance ABPN122R50551)..... <b>BF46016-O</b>	ACTT Xspotter w/Cummins QSB 6.7 (6.7L) Eng. (2019) <b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b> Trans. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	AP19, AP25, AP30 w/Cat 1673 Eng. Lube (5S0485)..... <b>PT88-HD</b> Fuel Ele. (9H4729)..... <b>PF824 +</b>
ACL w/Volvo TD122 (12.0L) Eng. Lube (466634)..... <b>B76 +</b> <b>Severe Service F-F Lube</b> (466634)..... <b>B76-SS +</b> <b>Fuel/Water Separator</b> (Fleetguard FS20095)..... <b>BF46016-O</b> Fuel (466987)..... <b>BF988 +</b>	ACX 64 w/Cummins ISX Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> Fuel (Fleetguard FF63009)..... <b>BF63000</b> Trans. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Diesel Exhaust Fluid</b> (2888182)..... <b>PE17000</b>	AP19, AP25, AP30 w/GMC 6-110 Eng. Lube..... <b>[2] P20-HD +</b> B-P Lube..... <b>[2] P52</b> P. Fuel Sock..... <b>F916-C</b> S. Fuel Ele..... <b>PF902</b>
ACL64FF w/Volvo VED12 Eng. F-F Lube..... <b>[2] B76 +</b> B-P Lube (477556)..... <b>B7685</b> Fuel (8193841)..... <b>BF7653</b>	AT w/Cat 3306 (10.5L) Eng. Lube Ele. (w/Metal Wrapper) (5S0484)..... <b>PT7332</b> Lube Ele. (w/Paper Wrapper) (5S0484)..... <b>PT670</b> Lube Spin-on (1R0716)..... <b>B99 +</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



AUTOCAR Trucks (cont'd)	AUTOCAR Trucks (cont'd)	AUTOCAR Trucks (cont'd)
AT w/Cat 3306 (10.5L) Eng. (Cont'd)	C65, C65D, C65T, C85D, C85T, C87, C87D, C90 w/White 390A, 490A, 531AA, C186A, 6-200A Engs.	C/DC w/Cummins N14 (14.0L) Eng.
Lube Spin-on (Standard Vers.) (1R0739).....	Lube (Late 1958-Late 1963).....	F-F Lube (Extended Life) (Fleetguard LF670SC).....
B76 +	P82 +	B96 +
Lube Spin-on (Severe Service) (1R0739).....	C75T, C95T w/Continental Eng.	F-F Lube (Standard) (Fleetguard LF670SC).....
B76-SS +	Lube.....	B196 +
Fuel/Water Separator Ele. (8N0205).....	P52	BD103 +
PF316	C4466, C5564 w/White 6 Cyl. 185A Eng.	B7577
Fuel/Water Separator Box-Style (6N7617).....	F-F Lube (To Late 1963).....	B-P Lube (3304232).....
BF912	P82 +	BF1212 +
Fuel/Water Separator Spin-on (256-8753).....	B-P Lube (To Late 1963).....	BF957-D +
BF1259	P53	Fuel/Water Separator (To 12/1995) (3308638).....
Fuel (7W8910).....	PA602	BF1212 +
CLN&R	C6564, C6564T, C6764, C9564, C9764, C103643 w/White 390A, 490A, 531AA, C186A, 6-200A Engs.	Fuel (154789).....
P. Fuel Ele. (9M2341).....	F-F Lube (Late 1958-Late 1963)..	BF957-D +
PF935	P82 +	C/DC w/Detroit Diesel 6-71 (7.0L) Eng.
Fuel Spin-on (1R1740).....	C/DC w/Cat 3208 (10.4L) Eng.	Lube (23530407).....
BF970 +	Lube (1R0713).....	B95 +
3.05 In. O.D. Fuel Spin-on (1R0750).....	Lube (1R0714).....	B95-MPG +
BF7637	Lube (9L9200).....	BF5800 +
3.69 In. O.D. Fuel Spin-on (1R0750).....	Fuel/Water Separator (8N9803)..	BF5810
BF7633 +	[2] BT230 +	BF5815
AT w/Cat 3406 (14.6L) Eng.	[2] B75	C/DC w/Detroit Diesel 6V-92N (9.0L) Eng.
Lube (1R0716).....	[2] BT364	Lube (23530407).....
B99 +	Fuel/Water Separator (8N9803)..	B95 +
Lube (High Efficiency) (1R1808)..	P. Fuel Ele. (9M2341).....	B95-MPG +
B7299 +	Fuel Spin-on (1R0740).....	BF5800 +
Fuel/Water Separator (256-8753).....	BF970 +	BF5810
BF1259	3.05 In. O.D. Fuel Spin-on (1R0750).....	BF5815
P. Fuel Ele. (9M2342).....	BF7637	C/DC w/Detroit Diesel 8V-71 (9.3L) Eng.
[2] PF935	3.69 In. O.D. Fuel Spin-on (1R0750).....	F-F Lube (23530407).....
Fuel Spin-on (High Efficiency) (1R0749).....	BF7633 +	B95 +
BF7587 +	C/DC w/Cat 3306 (10.5L) Eng.	B95-MPG +
BF614 +	Lube Ele. (Metal Wrapper) (5S0484).....	P52
AT w/Cat 3408 (18.0L) Eng.	Lube Ele. (Paper Wrapper) (5S0484).....	5 3/4 In. P. Fuel Sock (5574961).....
Lube (1R0716).....	Lube Spin-on (1R0716).....	F916-C
[2] B99 +	Lube Spin-on (Standard Vers.) (1R0739).....	PF845
P. Fuel Ele. (9M2342).....	B76 +	F844-A
[2] PF935	Lube Spin-on (Severe Service) (1R0739).....	BF5800 +
Fuel Spin-on (4N5823).....	B76-SS +	PF916
BF614 +	Fuel/Water Separator Ele. (8N0205).....	PF902
Fuel Spin-on (High Efficiency) (1R0749).....	PF316	PF846
BF7587 +	Fuel/Water Separator Box-Style (6N7617).....	BF5810
BF614 +	BF912	BF5815
AT w/Cummins N14 (14.0L) Eng.	Fuel/Water Separator Spin-on (256-8753).....	C/DC w/Detroit Diesel 8V-92 (12.1L) Eng.
F-F Lube (Extended Life) (Fleetguard LF670SC).....	Fuel (7W8910).....	Lube Ele. (23518666).....
B96 +	P. Fuel Ele. (9M2341).....	P20-HD +
F-F Lube (Std. Vers.) (Fleetguard LF670SC).....	PF935	B95 +
B196 +	Fuel Spin-on (1R1740).....	B95-MPG +
B-P Lube (3304232).....	BF970 +	PF845
B7577	3.05 In. O.D. Fuel Spin-on (1R0750).....	PF902
Dual-Flow Lube (3318853).....	BF7637	BF5810
BD103 +	3.69 In. O.D. Fuel Spin-on (1R0750).....	BF5815
Fuel/Water Separator (3308638).....	BF7633 +	C/DC w/Cat 3406 (14.6L) Eng.
BF1212 +	C/DC w/Cat 3406 (14.6L) Eng.	Lube (1R0716).....
Fuel (154789).....	Lube (High Efficiency) (1R1808)..	B99 +
BF957-D +	Fuel/Water Separator (256-8753).....	B7299 +
Coolant (w/4 Units BTA+) (3315116).....	BF1259	Lube (To S/N 570).....
BW5071	P. Fuel Ele. (9M2342).....	PT66-HD
AT w/Detroit Diesel 8V-92 (12.1L) Eng.	[2] PF935	Lube (S/N 570-up).....
Lube Ele. (23518666).....	Fuel Spin-on (High Efficiency) (1R0749).....	PT670
P20-HD +	BF7587 +	C/DC w/Detroit Diesel 8V-92 (12.1L) Eng.
Lube Spin-on (23530407).....	Fuel Spin-on (1R1712).....	Lube (To S/N 570).....
B95 +	BF614 +	PT66-HD
Lube Spin-on (23530408).....		PT670
B95-MPG +		CL65, CL65D, CL65T, CL84T, CL85, CL85T w/LeRoi TH540 Eng.
P. Fuel Ele. (9717391).....		Lube (To S/N 570).....
PF845		PT66-HD
P. Fuel Spin-on (23530706).....		Lube (S/N 570-up).....
BF5800 +		PT670
S. Fuel Ele. (23519152).....		CL6564, CL6564T, CL8464, CL10364S w/LeRoi TH540 Eng.
PF902		Lube (To S/N 570).....
S. Fuel Spin-on (23530707).....		PT66-HD
BF5810		Lube (S/N 570-up).....
S. Fuel Spin-on (23530645).....		PT670
BF5815		
AT w/Volvo TD102 (9.6L) Eng.		
Lube (466634).....		
B76 +		
Severe Service F-F Lube (466634).....		
B76-SS +		
Fuel (466987).....		
BF988 +		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>AUTOCAR Trucks (cont'd)</b>	<b>AUTOCAR Trucks (cont'd)</b>	<b>AUTOCAR Trucks (cont'd)</b>
<b>Construcktor w/Cat 3208 (10.4L) Eng.</b> <b>Lube (1R0713)..... [2] BT230 +</b> <b>Lube (1R0714)..... [2] B75</b> <b>Lube (9L9200)..... [2] BT364</b> <b>Fuel/Water Separator (8N9803).. BF912</b> <b>P. Fuel Ele. (9M2341)..... PF935</b> <b>Fuel Spin-on (1R0740)..... BF970 +</b> <b>3.05 In. O.D. Fuel Spin-on (1R0750)..... BF7637</b> <b>3.69 In. O.D. Fuel Spin-on (1R0750)..... BF7633 +</b>	<b>DK w/Cat 3406 (14.6L) Eng.</b> <b>Lube (1R0716)..... B99 +</b> <b>Lube (High Efficiency) (1R1808).. B7299 +</b> <b>Fuel/Water Separator (256-8753)..... BF1259</b> <b>P. Fuel Ele. (9M2341)..... [2] PF935</b> <b>Fuel Spin-on (High Efficiency) (1R0749)..... BF7587 +</b> <b>Fuel Spin-on (1R1712)..... BF614 +</b>	<b>DK w/Detroit Diesel 8V-92 (12.1L) Eng. (Cont'd)</b> <b>S. Fuel Spin-on (23530707)..... BF5810</b> <b>S. Fuel Spin-on (Upgrade) (23530645)..... BF5815</b>
<b>DC-64 w/Cummins X12 (11.9L) Eng. (2020)</b> <b>Dual-Flow Lube (4367100)..... BD50000</b> <b>Fuel (5365988)..... BF46129</b>	<b>DK w/Cat 3408 (18.0L) Eng.</b> <b>Lube (1R0716)..... [2] B99 +</b> <b>P. Fuel Ele. (9M2342)..... [2] PF935</b> <b>Fuel Spin-on (4N5823)..... BF614 +</b> <b>Fuel Spin-on (High Efficiency) (1R0749)..... BF7587 +</b>	<b>DS w/Cat 3208 (10.4L) Eng.</b> <b>Lube (1R0713)..... [2] BT230 +</b> <b>Lube (1R0714)..... [2] B75</b> <b>Lube (9L9200)..... [2] BT364</b> <b>Fuel/Water Separator (8N9803).. BF912</b> <b>P. Fuel Ele. (9M2341)..... PF935</b> <b>Fuel Spin-on (1R0740)..... BF970 +</b> <b>3.05 In. O.D. Fuel Spin-on (1R0750)..... BF7637</b> <b>3.69 In. O.D. Fuel Spin-on (1R0750)..... BF7633 +</b>
<b>DC-64 w/Cummins X12 (11.9L) Eng. (2021)</b> <b>Dual-Flow Lube (4367100)..... BD50000</b> <b>Fuel (5365988)..... BF46129</b>	<b>DK w/Cummins L10 (10.0L) Eng.</b> <b>Dual-Flow Lube (3318853)..... BD103 +</b> <b>F-F Lube (Extended Life) (Fleetguard LF670SC)..... B96 +</b> <b>F-F Lube (Standard) (Fleetguard LF670SC)..... B196 +</b> <b>B-P Lube (3304232)..... B7577</b> <b>Opt. Fuel/Water Separator (3308638)..... BF1212 +</b> <b>Fuel (154789)..... BF957-D +</b> <b>Coolant (w/4 Units BTA+) (3315116)..... BW5071</b> <b>Coolant (w/15 Units BTA+) (Fleetguard WF2075)..... BW5075</b>	<b>DS w/Cat 3306 (10.5L) Eng.</b> <b>Lube Ele. (w/Metal Wrapper) (5S0484)..... PT7332</b> <b>Lube Ele. (w/Paper Wrapper) (5S0484)..... PT670</b> <b>Lube Spin-on (1R0716)..... B99 +</b> <b>Lube Spin-on (Standard Vers.) (1R0739)..... B76 +</b> <b>Lube Spin-on (Severe Service) (1R0739)..... B76-SS +</b> <b>Fuel/Water Separator Ele. (8N0205)..... PF316</b> <b>Fuel/Water Separator Box-Style (6N7617)..... BF912</b> <b>Fuel/Water Separator Spin-on (256-8753)..... BF1259</b> <b>Fuel (7W8910)..... CLN&amp;R</b> <b>P. Fuel Ele. (9M2341)..... PF935</b> <b>Fuel Spin-on (1R1740)..... BF970 +</b> <b>3.05 In. O.D. Fuel Spin-on (1R0750)..... BF7637</b> <b>3.69 In. O.D. Fuel Spin-on (1R0750)..... BF7633 +</b>
<b>DC-64 w/Cummins X12 (11.9L) Eng. (2022)</b> <b>Lube (5575298)..... B40145</b> <b>Fuel (5365988)..... BF46129</b>	<b>DK w/Cummins N14 (14.0L) Eng.</b> <b>F-F Lube (Extended Life) (Fleetguard LF670SC)..... B96 +</b> <b>F-F Lube (Standard) (Fleetguard LF670SC)..... B196 +</b> <b>Dual-Flow Lube (3318853)..... BD103 +</b> <b>B-P Lube (3304232)..... B7577</b> <b>Fuel/Water Separator (3308638)..... BF1212 +</b> <b>Fuel (154789)..... BF957-D +</b>	<b>DK w/Cat 3406 (14.6L) Eng.</b> <b>Lube (1R0716)..... B99 +</b> <b>Lube (High Efficiency) (1R1808).. B7299 +</b> <b>Fuel/Water Separator (256-8753)..... BF1259</b> <b>P. Fuel Ele. (9M2342)..... [2] PF935</b> <b>Fuel Spin-on (High Efficiency) (1R0749)..... BF7587 +</b> <b>Fuel Spin-on (1R1712)..... BF614 +</b>
<b>DK w/Cat 3208 (10.4L) Eng.</b> <b>Lube (1R0713)..... [2] BT230 +</b> <b>Lube (1R0714)..... [2] B75</b> <b>Lube (9L9200)..... [2] BT364</b> <b>Fuel/Water Separator (8N9803).. BF912</b> <b>P. Fuel Ele. (9M2341)..... PF935</b> <b>Fuel Spin-on (1R0740)..... BF970 +</b> <b>3.05 In. O.D. Fuel Spin-on (1R0750)..... BF7637</b> <b>3.69 In. O.D. Fuel Spin-on (1R0750)..... BF7633 +</b>	<b>DK w/Cummins L10 (10.0L) Eng.</b> <b>Lube (23530407)..... B95 +</b> <b>Lube (Upgrade) (23530408)..... B95-MPG +</b> <b>P. Fuel (23530706)..... BF5800 +</b> <b>S. Fuel (23530707)..... BF5810</b> <b>S. Fuel (Upgrade) (23530645)..... BF5815</b>	<b>DS w/Cat 3406 (14.6L) Eng.</b> <b>Lube (1R0716)..... B99 +</b> <b>Lube (High Efficiency) (1R1808).. B7299 +</b> <b>Fuel/Water Separator (256-8753)..... BF1259</b> <b>P. Fuel Ele. (9M2342)..... [2] PF935</b> <b>Fuel Spin-on (High Efficiency) (1R0749)..... BF7587 +</b> <b>Fuel Spin-on (1R1712)..... BF614 +</b>
<b>DK w/Cat 3306 (10.5L) Eng.</b> <b>Lube Ele. (w/Metal Wrapper) (5S0484)..... PT7332</b> <b>Lube Ele. (w/Paper Wrapper) (5S0484)..... PT670</b> <b>Lube Spin-on (1R0716)..... B99 +</b> <b>Lube Spin-on (Standard Vers.) (1R0739)..... B76 +</b> <b>Lube Spin-on (Severe Service) (1R0739)..... B76-SS +</b> <b>Fuel/Water Separator Ele. (8N0205)..... PF316</b> <b>Fuel/Water Separator Box-Style (6N7617)..... BF912</b> <b>Fuel/Water Separator Spin-on (256-8753)..... BF1259</b> <b>Fuel (7W8910)..... CLN&amp;R</b> <b>P. Fuel Ele. (9M2341)..... PF935</b> <b>Fuel Spin-on (1R1740)..... BF970 +</b> <b>3.05 In. O.D. Fuel Spin-on (1R0750)..... BF7637</b> <b>3.69 In. O.D. Fuel Spin-on (1R0750)..... BF7633 +</b>	<b>DK w/Detroit Diesel 6-71 (7.0L) Eng.</b> <b>Lube (23530407)..... B95 +</b> <b>Lube (Upgrade) (23530408)..... B95-MPG +</b> <b>P. Fuel (23530706)..... BF5800 +</b> <b>S. Fuel (23530707)..... BF5810</b> <b>S. Fuel (Upgrade) (23530645)..... BF5815</b>	<b>DS w/Cummins L10 (10.0L) Eng.</b> <b>Dual-Flow Lube (3318853)..... BD103 +</b> <b>F-F Lube (Extended Life) (Fleetguard LF670SC)..... B96 +</b> <b>F-F Lube (Standard) (Fleetguard LF670SC)..... B196 +</b> <b>B-P Lube (3304232)..... B7577</b> <b>Opt. Fuel/Water Separator (3308638)..... BF1212 +</b> <b>Fuel Spin-on (154789)..... BF957-D +</b> <b>Coolant (w/4 Units BTA+) (3315116)..... BW5071</b>
<b>DK w/Cat 3306 (10.5L) Eng.</b> <b>Lube Ele. (w/Metal Wrapper) (5S0484)..... PT7332</b> <b>Lube Ele. (w/Paper Wrapper) (5S0484)..... PT670</b> <b>Lube Spin-on (1R0716)..... B99 +</b> <b>Lube Spin-on (Standard Vers.) (1R0739)..... B76 +</b> <b>Lube Spin-on (Severe Service) (1R0739)..... B76-SS +</b> <b>Fuel/Water Separator Ele. (8N0205)..... PF316</b> <b>Fuel/Water Separator Box-Style (6N7617)..... BF912</b> <b>Fuel/Water Separator Spin-on (256-8753)..... BF1259</b> <b>Fuel (7W8910)..... CLN&amp;R</b> <b>P. Fuel Ele. (9M2341)..... PF935</b> <b>Fuel Spin-on (1R1740)..... BF970 +</b> <b>3.05 In. O.D. Fuel Spin-on (1R0750)..... BF7637</b> <b>3.69 In. O.D. Fuel Spin-on (1R0750)..... BF7633 +</b>	<b>DK w/Detroit Diesel 6V-92N (9.0L) Eng.</b> <b>Lube (23530407)..... B95 +</b> <b>Lube (Upgrade) (23530408)..... B95-MPG +</b> <b>P. Fuel (23530706)..... BF5800 +</b> <b>S. Fuel (23530707)..... BF5810</b> <b>S. Fuel (Upgrade) (23530645)..... BF5815</b>	<b>DK w/Detroit Diesel 8V-92 (12.1L) Eng.</b> <b>Lube Ele. (23518666)..... P20-HD +</b> <b>Lube Spin-on (23530407)..... B95 +</b> <b>Lube Spin-on (Upgrade) (23530408)..... B95-MPG +</b> <b>P. Fuel Ele. (9717391)..... PF845</b> <b>P. Fuel Spin-on (23530706)..... BF5800 +</b> <b>S. Fuel Ele. (23519152)..... PF902</b>

+ See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

AUTOCAR Trucks (cont'd)	AUTOCAR Trucks (cont'd)	AUTOCAR Trucks (cont'd)
DS w/Cummins L10 (10.0L) Eng. (Cont'd) <b>Coolant</b> (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b>	Xpeditor w/Cummins ISC 8.3 (8.3L) Eng. (Cont'd) <b>Fuel</b> (Fleetguard FF5636)..... <b>BF7924</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b> <b>Coolant</b> (w/23 Units BTA+) (Fleetguard WF2076)..... <b>BW5076</b> <b>Coolant</b> (Controlled Release) (Fleetguard WF2121)..... <b>BW5250</b>	Xpeditor w/Cummins ISL 8.9 (8.9L) Eng. (2018) (Cont'd) <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Opt. Rear Axle</b> (Mertitor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (2888182).. <b>PE17000</b>
DS w/Cummins N14 (14.0L) Eng. <b>F-F Lube</b> (Extended Life) (Fleetguard LF670SC)..... <b>B96 +</b> <b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Fuel/Water Separator</b> (3308638). <b>BF1212 +</b> <b>Fuel</b> (154789)..... <b>BF957-D +</b> <b>Coolant</b> (w/4 Units BTA+) (3315116)..... <b>BW5071</b>	Xpeditor w/Cummins ISL 8.9 (8.9L) Eng. (2010-17) <b>Dual-Flow Lube</b> (High Velocity) (Fleetguard LF9009)..... <b>BD7309</b> <b>Dual-Flow Lube</b> (Fleetguard LF9548)..... <b>BD324 +</b> <b>Opt. Dual-Flow Lube</b> (Std. Vers.) (Fleetguard LF3000)..... <b>BD103 +</b> <b>Fuel/Water Separator</b> (w/Rect. Sensor) (Fleetguard FS1022)..... <b>BF1293-SPS</b> <b>Fuel/Water Separator</b> (w/Oval Sensor) (Fleetguard FS1022)..... <b>BF1272-SPS</b> <b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b> <b>Fuel</b> (Fleetguard FF5488)..... <b>BF7815</b> <b>Fuel</b> (Fleetguard FF5636)..... <b>BF7924</b> <b>Fuel</b> (2014 Emissions, Hex Drive Base) (Fleetguard FF63009)..... <b>BF63000</b> <b>Axial Seal Air</b> (Fleetguard AF888M)..... <b>LL2326 +</b> <b>Radial Seal O. Air</b> (Standard) (Fleetguard AF25139M)..... <b>RS3518</b> <b>Radial Seal XP O. Air</b> (Upgrade) (DBA5069)..... <b>RS3518XP</b> <b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (Controlled Release) (Fleetguard WF2121)..... <b>BW5250</b> <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (38708-5002)..... <b>P528</b>	Xpeditor w/Cummins ISL 8.9 (8.9L) Eng. (2019) <b>Lube</b> (3401544)..... <b>B40142</b> <b>Fuel</b> (5303743)..... <b>BF63000</b>
DS w/Detroit Diesel 6-71 (7.0L) Eng. <b>Lube</b> (23530407)..... <b>B95 +</b> <b>Lube</b> (Upgrade) (23530408)..... <b>B95-MPG +</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b> <b>S. Fuel</b> (Upgrade) (23530645)..... <b>BF5815</b>	Xpeditor w/Cummins ISL 8.9 (8.9L) Eng. (2020) <b>Lube</b> (5444774)..... <b>B40142</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Xpeditor w/Cummins ISL 8.9 (8.9L) Eng. (2021) <b>Lube</b> (5444774)..... <b>B40142</b>
S w/Cat 3406 (14.6L) Eng. <b>Lube</b> (1R0716)..... <b>B99 +</b> <b>Lube</b> (High Efficiency) (1R1808).. <b>B7299 +</b> <b>Fuel/Water Separator</b> (256-8753)..... <b>BF1259</b> <b>P. Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (High Efficiency) (1R0749)..... <b>BF7587 +</b> <b>Fuel Spin-on</b> (1R1712)..... <b>BF614 +</b>	Xpeditor w/Cummins ISL 8.9 (8.9L) Eng. (2022) <b>Lube</b> (5444774)..... <b>B40142</b> <b>Fuel</b> (5660774)..... <b>BF63000</b>	Xpeditor w/Cummins ISL-G (8.9L) Eng. (2008-17) <b>Dual-Flow Lube</b> (Std. Vers.) (Fleetguard LF3000)..... <b>BD103 +</b> <b>Dual-Flow Lube</b> (High Velocity) (Fleetguard LF9009)..... <b>BD7309</b> <b>Fuel</b> (Fleetguard NG5900)..... <b>BF7695</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b>
S w/Cummins N14 (14.0L) Eng. <b>F-F Lube</b> (Extended Life) (Fleetguard LF670SC)..... <b>B96 +</b> <b>F-F Lube</b> (Standard) (Fleetguard LF670SC)..... <b>B196 +</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Fuel/Water Separator</b> (3308638). <b>BF1212 +</b> <b>Fuel</b> (154789)..... <b>BF957-D +</b>	Xpeditor w/Cummins ISL-G (8.9L) Eng. (2018) <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel/Water Separator</b> (Fleetguard NG5900)..... <b>BF7695</b> <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	Xpeditor w/Cummins ISL-G (8.9L) Eng. (2019) <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309</b> <b>Fuel/Water Separator</b> (Fleetguard NG5900)..... <b>BF7695</b> <b>Air</b> (Don. P185057)..... <b>PA2326</b> <b>Long Life Air</b> (Don. P185057)..... <b>LL2326</b> <b>XP Air</b> (Don. EAF5057)..... <b>PA2326XP</b> <b>Radial Seal O. Air</b> (3520400C1).. <b>RS3518</b> <b>Radial Seal XP O. Air</b> (3520400C1)..... <b>RS3518XP</b> <b>Radial Seal I. Air</b> (3520401C1).... <b>RS3519</b> <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
S w/Detroit Diesel 6V-92N (9.0L) Eng. <b>Lube</b> (23530407)..... <b>B95 +</b> <b>Lube</b> (Upgrade) (23530408)..... <b>B95-MPG +</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b> <b>S. Fuel</b> (Upgrade) (23530645)..... <b>BF5815</b>	Xpeditor w/Cummins ISC 8.3 (8.3L) Eng. <b>Dual-Flow Lube</b> (High Velocity) (Fleetguard LF9009)..... <b>BD7309</b> <b>Dual-Flow Lube</b> (Fleetguard LF9548)..... <b>BD324 +</b> <b>Opt. Dual-Flow Lube</b> (Std. Vers.) (Fleetguard LF3000)..... <b>BD103 +</b> <b>Fuel/Water Separator</b> (w/Rect. Sensor) (3800394)..... <b>BF1293-SPS</b> <b>Fuel/Water Separator</b> (w/Oval Sensor) (3800394)..... <b>BF1272-SPS</b> <b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b> <b>Fuel/Water Separator</b> (3942533). <b>BF1271</b> <b>Fuel</b> (Fleetguard FF5488)..... <b>BF7815</b>	Xpeditor w/Cummins ISL-G (8.9L) Eng. (2018) <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309</b> <b>Fuel/Water Separator</b> (Fleetguard NG5900)..... <b>BF7695</b> <b>Air</b> (Don. P185057)..... <b>PA2326</b> <b>Long Life Air</b> (Don. P185057)..... <b>LL2326</b> <b>XP Air</b> (Don. EAF5057)..... <b>PA2326XP</b> <b>Radial Seal O. Air</b> (3520400C1).. <b>RS3518</b> <b>Radial Seal XP O. Air</b> (3520400C1)..... <b>RS3518XP</b> <b>Radial Seal I. Air</b> (3520401C1).... <b>RS3519</b>


+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>AUTOCAR Trucks (cont'd)</b>	<b>AUTOCAR Trucks (cont'd)</b>	<b>AUTOCAR Trucks (cont'd)</b>
Xpeditor w/Cummins ISL-G (8.9L) Eng. (2019) (Cont'd) <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b>	Xpeditor w/Cummins ISX 11.9G (11.9L) Eng. (2018) (Cont'd) <b>Trans.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	Xpeditor w/Cummins L9N (8.9L) Eng. (2021) <b>Lube</b> (Fleetguard LF14002NN)..... <b>B40142</b> <b>Fuel</b> (Fleetguard NG5900)..... <b>BF7695</b>
Xpeditor w/Cummins ISL-G (8.9L) Eng. (2020) <b>Lube</b> (Fleetguard LF9009)..... <b>B40142</b> <b>Fuel</b> (Fleetguard NG5900)..... <b>BF7695</b> <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Xpeditor w/Cummins ISX 11.9G (11.9L) Eng. (2020) <b>Dual-Flow Lube</b> (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel</b> (Fleetguard NG5900)..... <b>BF7695</b> <b>Trans.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	Xpeditor WX w/Cat 3126 (7.2L) Eng. (To 1/2004) <b>Lube</b> (Standard Vers.) (1R0739).. <b>B76 +</b> <b>Lube</b> (Severe Service) (1R0739).. <b>B76-SS +</b> <b>Fuel/Water Separator</b> (175-2949)..... <b>BF1268</b> <b>Fuel/Water Separator</b> (256-8753)..... <b>BF1259</b> <b>Fuel/Water Separator</b> (198-6378)..... <b>BF7798-SP</b> <b>P. Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (1R0751)..... <b>BF7632</b>
Xpeditor w/Cummins ISX 11.9 (11.9L) Eng. (2018) <b>Dual-Flow Lube</b> (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (Fleetguard FS19763)..... <b>PF7928</b> <b>Fuel</b> (Fleetguard FF5776)..... <b>BF9885 +</b> <b>Air</b> (Don. P185057)..... <b>PA2326</b> <b>Long Life Air</b> (Don. P185057)..... <b>LL2326</b> <b>XP Air</b> (Don. EAF5057)..... <b>PA2326XP</b> <b>Radial Seal O. Air</b> (3520400C1).. <b>RS3518</b> <b>Radial Seal XP O. Air</b> (3520400C1)..... <b>RS3518XP</b> <b>Radial Seal I. Air</b> (3520401C1).... <b>RS3519</b> <b>Trans.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	Xpeditor w/Cummins ISX 11.9G (11.9L) Eng. (2021) <b>Lube</b> (5575298)..... <b>B40145</b> <b>Fuel</b> (3607140)..... <b>BF7695</b> <b>Coolant</b> (3680434)..... <b>B5087</b>	Xpeditor WX w/Cat 3126 (7.2L) Eng. (1/2004-on) <b>Lube</b> (1R1807)..... <b>B7700 +</b> <b>Fuel/Water Separator</b> (175-2949)..... <b>BF1268</b> <b>Fuel/Water Separator</b> (256-8753)..... <b>BF1259</b> <b>Fuel/Water Separator</b> (198-6378)..... <b>BF7798-SP</b> <b>P. Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (1R0751)..... <b>BF7632</b>
Xpeditor w/Cummins ISX 11.9 (11.9L) Eng. (2019) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel</b> (2893612)..... <b>BF9885 +</b>	Xpeditor w/Cummins X12 (11.9L) Eng. (2020) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel</b> (5365988)..... <b>BF46129</b>	Xpeditor WX w/Cat C10 (10.3L) Eng. <b>F-F Lube</b> (1R0716)..... <b>B99 +</b> <b>F-F Lube</b> (High Efficiency) (1R1808)..... <b>B7299 +</b> <b>Attach. B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Attach. Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Attach. Fuel/Water Separator Spin-on</b> (Open End for Bowl) (133-5673)..... <b>BF1395-O</b> <b>Attach. Fuel/Water Separator Spin-on</b> (w/Drain) (133-5673)..... <b>BF1265</b> <b>Attach. Fuel/Water Separator Spin-on</b> (w/Sensor Port) (133-5673)..... <b>BF1395-SP</b> <b>Fuel/Water Separator Spin-on</b> (256-8753)..... <b>BF1259</b> <b>Attach. P. Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (High Efficiency) (1R0749)..... <b>BF7587 +</b> <b>Fuel Spin-on</b> (Std. Vers.) (1R1712)..... <b>BF614 +</b>
Xpeditor w/Cummins ISX 11.9 (11.9L) Eng. (2020) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel</b> (2893612)..... <b>BF9885</b> <b>Trans.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	Xpeditor w/Cummins X12 (11.9L) Eng. (2022) <b>Lube</b> (5575298)..... <b>B40145</b> <b>Fuel</b> (5365988)..... <b>BF46129</b>	<b>Attach. Fuel/Water Separator Spin-on</b> (w/Sensor Port) (133-5673)..... <b>BF1395-SP</b> <b>Fuel/Water Separator Spin-on</b> (256-8753)..... <b>BF1259</b> <b>Attach. P. Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (High Efficiency) (1R0749)..... <b>BF7587 +</b> <b>Fuel Spin-on</b> (Std. Vers.) (1R1712)..... <b>BF614 +</b>
Xpeditor w/Cummins ISX 11.9 (11.9L) Eng. (2019) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel</b> (2893612)..... <b>BF9885 +</b>	Xpeditor w/Cummins L9 (9.0L) Eng. (2018) <b>Lube</b> (3401544)..... <b>B40142</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> <b>Air</b> (Don. P185057)..... <b>PA2326</b> <b>Long Life Air</b> (Don. P185057)..... <b>LL2326</b> <b>XP Air</b> (Don. EAF5057)..... <b>PA2326XP</b> <b>Radial Seal O. Air</b> (3520400C1).. <b>RS3518</b> <b>Radial Seal XP O. Air</b> (3520400C1)..... <b>RS3518XP</b> <b>Radial Seal I. Air</b> (3520401C1).... <b>RS3519</b> <b>Crankcase Breather</b> (4936636).... <b>CV15010</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (Fleetguard UF101)..... <b>PE17000</b>	<b>Attach. Fuel/Water Separator Spin-on</b> (w/Sensor Port) (133-5673)..... <b>BF1395-SP</b> <b>Fuel/Water Separator Spin-on</b> (256-8753)..... <b>BF1259</b> <b>Attach. P. Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (High Efficiency) (1R0749)..... <b>BF7587 +</b> <b>Fuel Spin-on</b> (Std. Vers.) (1R1712)..... <b>BF614 +</b>
Xpeditor w/Cummins ISX 11.9 (11.9L) Eng. (2020) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel</b> (2893612)..... <b>BF9885</b> <b>Trans.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	Xpeditor w/Cummins L9 (9.0L) Eng. (2019) <b>Lube</b> (3401544)..... <b>B40142</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Trans.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	Xpeditor WX w/Cat C11 (11.1L) Eng. <b>Lube</b> ..... <b>B99 +</b> <b>Fuel</b> ..... <b>BF7587 +</b>
Xpeditor w/Cummins ISX 11.9G (11.9L) Eng. (2018) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Air</b> (Don. P185057)..... <b>PA2326</b> <b>Long Life Air</b> (Don. P185057)..... <b>LL2326</b> <b>XP Air</b> (Don. EAF5057)..... <b>PA2326XP</b> <b>Radial Seal O. Air</b> (3520400C1).. <b>RS3518</b> <b>Radial Seal XP O. Air</b> (3520400C1)..... <b>RS3518XP</b> <b>Radial Seal I. Air</b> (3520401C1).... <b>RS3519</b> <b>Coolant</b> (3680434)..... <b>B5087</b> <b>Trans.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	Xpeditor w/Cummins L9N (8.9L) Eng. (2020) <b>Lube</b> (3401544)..... <b>B40142</b> <b>Fuel</b> (3607140)..... <b>BF7695</b>	Xpeditor WX w/Cummins ISC 8.3 (8.3L) Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

AUTOCAR Trucks (cont'd)	AUTOCAR Trucks (cont'd)	AUTOCAR Trucks (cont'd)
Xpeditor WX w/Cummins ISC 8.3 (8.3L) Eng. (Cont'd) <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Xpeditor WXLL w/Cummins ISC 8.3 (8.3L) Eng. (Cont'd) <b>Coolant</b> (Controlled Release) (Fleetguard WF2121)..... <b>BW5250</b>	Xpeditor WXLL w/Cummins ISM 10.8 (10.8L) Eng. (Cont'd) <b>Coolant</b> (Controlled Release) (Fleetguard WF2121)..... <b>BW5250</b>
Xpeditor WX w/Cummins ISL 8.9 (8.9L) Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Xpeditor WXLL w/Cummins ISL 8.9 (8.9L) Eng. <b>Dual-Flow Lube</b> (High Velocity) (Fleetguard LF9009)..... <b>BD7309</b> <b>Opt. Dual-Flow Lube</b> (Std. Vers.) (Fleetguard LF3000)..... <b>BD103 +</b> <b>Dual-Flow Lube</b> (Fleetguard LF9548)..... <b>BD324 +</b> <b>Fuel/Water Separator</b> (w/Rect. Sensor) (Fleetguard FS1022)..... <b>BF1293-SPS</b> <b>Fuel/Water Separator</b> (w/Oval Sensor) (Fleetguard FS1022)..... <b>BF1272-SPS</b> <b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b> <b>Fuel</b> (Fleetguard FF5488)..... <b>BF7815</b> <b>Fuel</b> (Fleetguard FF5636)..... <b>BF7924</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (Controlled Release) (Fleetguard WF2121)..... <b>BW5250</b>	Xpeditor WXR w/Cat 3126 (7.2L) Eng. (To 1/04) <b>Lube</b> (Standard Vers.) (1R0739).. <b>B76 +</b> <b>Lube</b> (Severe Service) (1R0739).. <b>B76-SS +</b> <b>Fuel/Water Separator</b> (175-2949)..... <b>BF1268</b> <b>Fuel/Water Separator</b> (256-8753)..... <b>BF1259</b> <b>Fuel/Water Separator</b> (198-6378)..... <b>BF7798-SP</b> <b>P. Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (1R0751)..... <b>BF7632</b>
Xpeditor WX w/Cummins ISL-G (8.9L) Eng. <b>Dual-Flow Lube</b> (Std. Vers.) (Fleetguard LF3000)..... <b>BD103 +</b> <b>Dual-Flow Lube</b> (High Velocity) (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel</b> (Fleetguard NG5900)..... <b>BF7695</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b>	Xpeditor WXLL w/Cummins ISL-G (8.9L) Eng. <b>Dual-Flow Lube</b> (Std. Vers.) (Fleetguard LF3000)..... <b>BD103 +</b> <b>Dual-Flow Lube</b> (High Velocity) (Fleetguard LF9009)..... <b>BD7309</b> <b>Fuel</b> (Fleetguard NG5900)..... <b>BF7695</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b>	Xpeditor WXR w/Cat 3126 (7.2L) Eng. (1/04-on) <b>Lube</b> (1R1807)..... <b>B7700 +</b> <b>Fuel/Water Separator</b> (175-2949)..... <b>BF1268</b> <b>Fuel/Water Separator</b> (256-8753)..... <b>BF1259</b> <b>Fuel/Water Separator</b> (198-6378)..... <b>BF7798-SP</b> <b>P. Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (1R0751)..... <b>BF7632</b>
Xpeditor WX w/Cummins ISM 10.8 (10.8L) Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154 +</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Breather</b> (3683918)..... <b>CV15000</b> <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Xpeditor WXLL w/Cummins ISM 10.8 (10.8L) Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154 +</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF9001)..... <b>BD50000</b> <b>Dual-Flow Lube</b> (Fleetguard LF9031)..... <b>BD7509 +</b> <b>Dual-Flow Lube</b> (Fleetguard LF9000)..... <b>BD7153 +</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1000)..... <b>BF1259</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1282)..... <b>BF1282 +</b> <b>Fuel/Water Separator Spin-on</b> (3406889)..... <b>BF1293-SPS</b> <b>Crankcase Breather</b> (3683918)..... <b>CV15000</b> <b>Coolant</b> (w/o Chemicals) (Fleetguard WF2127)..... <b>B5087</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b>	Xpeditor WXR w/Cummins ISC 8.3 (8.3L) Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Air</b> (Fleetguard AF888M)..... <b>LL2326 +</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
Xpeditor WXLL w/Cummins ISC 8.3 (8.3L) Eng. <b>Dual-Flow Lube</b> (High Velocity) (Fleetguard LF9009)..... <b>BD7309</b> <b>Opt. Dual-Flow Lube</b> (Std. Vers.) (Fleetguard LF3000)..... <b>BD103 +</b> <b>Dual-Flow Lube</b> (Fleetguard LF9548)..... <b>BD324 +</b> <b>Fuel/Water Separator</b> (w/Rect. Sensor) (3800394)..... <b>BF1293-SPS</b> <b>Fuel/Water Separator</b> (w/Oval Sensor) (3800394)..... <b>BF1272-SPS</b> <b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b> <b>Fuel/Water Separator</b> (3942533)..... <b>BF1271</b> <b>Fuel</b> (High Efficiency) (Fleetguard FF5488)..... <b>BF7815</b> <b>Fuel</b> (Fleetguard FF5636)..... <b>BF7924</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b> <b>Coolant</b> (w/23 Units BTA+) (Fleetguard WF2076)..... <b>BW5076</b>	Xpeditor WXLL w/Cummins ISM 10.8 (10.8L) Eng. <b>Dual-Flow Lube</b> (High Velocity) (Fleetguard LF9009)..... <b>BD7309</b> <b>Opt. Dual-Flow Lube</b> (Std. Vers.) (Fleetguard LF3000)..... <b>BD103 +</b> <b>Dual-Flow Lube</b> (Fleetguard LF9548)..... <b>BD324 +</b> <b>Fuel/Water Separator</b> (w/Rect. Sensor) (Fleetguard FS1022)..... <b>BF1293-SPS</b> <b>Fuel/Water Separator</b> (w/Oval Sensor) (Fleetguard FS1022)..... <b>BF1272-SPS</b> <b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b> <b>Fuel</b> (High Efficiency) (Fleetguard FF5488)..... <b>BF7815</b> <b>Fuel</b> (Fleetguard FF5636)..... <b>BF7924</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (Controlled Release) (Fleetguard WF2121)..... <b>BW5250</b>	Xpeditor WXR w/Cummins ISL 8.9 (8.9L) Eng. <b>Dual-Flow Lube</b> (High Velocity) (Fleetguard LF9009)..... <b>BD7309</b> <b>Opt. Dual-Flow Lube</b> (Std. Vers.) (Fleetguard LF3000)..... <b>BD103 +</b> <b>Dual-Flow Lube</b> (Fleetguard LF9548)..... <b>BD324 +</b> <b>Fuel/Water Separator</b> (w/Rect. Sensor) (Fleetguard FS1022)..... <b>BF1293-SPS</b> <b>Fuel/Water Separator</b> (w/Oval Sensor) (Fleetguard FS1022)..... <b>BF1272-SPS</b> <b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b> <b>Fuel</b> (High Efficiency) (Fleetguard FF5488)..... <b>BF7815</b> <b>Fuel</b> (Fleetguard FF5636)..... <b>BF7924</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (Controlled Release) (Fleetguard WF2121)..... <b>BW5250</b>


\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>AUTOCAR Trucks (cont'd)</b>	<b>AUTOCAR Trucks (cont'd)</b>	<b>AUTOCAR Trucks (cont'd)</b>
Xpedito WXR w/Cummins ISL-G (8.9L) Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel</b> (Fleetguard NG5900)..... <b>BF7695</b> <b>Air</b> (Fleetguard AF888M)..... <b>LL2326 +</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Xpert w/Cummins ISB 6.7 (6.7L) Eng. (2020) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b> Xpert w/Cummins ISB 6.7 (6.7L) Eng. (2021) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b> Xpert w/Cummins ISB 6.7 (6.7L) Eng. (2022) <b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b> Xpert w/Cummins ISL 8.9 (8.9L) Eng. (2018) <b>Lube</b> (Fleetguard LF9009)..... <b>B40142</b> <b>Fuel</b> (FF63009)..... <b>BF63000</b> Xpert w/Cummins ISL 8.9 (8.9L) Eng. (2019) <b>Lube</b> (3401544)..... <b>B40142</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> Xpert w/Cummins ISL 8.9 (8.9L) Eng. (2020) <b>Lube</b> (5444774)..... <b>B40142</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Xpert w/Cummins ISL 8.9 (8.9L) Eng. (2021) <b>Lube</b> (5444774)..... <b>B40142</b> Xpert w/Cummins ISL-G (8.9L) Eng. (2014-16) <b>Dual-Flow Lube</b> (Std. Vers.) (Fleetguard LF3000)..... <b>BD103 +</b> <b>Dual-Flow Lube</b> (High Velocity) (Fleetguard LF9009)..... <b>BD7309</b> <b>Fuel</b> (Fleetguard NG5900)..... <b>BF7695</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b> Xpert w/Cummins ISL-G (8.9L) Eng. (2018) <b>Lube</b> (Fleetguard LF9009)..... <b>B40142</b> <b>Fuel/Water Separator</b> (Fleetguard NG5900)..... <b>BF7695</b> Xpert w/Cummins ISL-G (8.9L) Eng. (2019) <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309</b> <b>Fuel/Water Separator</b> (Fleetguard NG5900)..... <b>BF7695</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b> Xpert w/Cummins ISM 10.8 (10.8L) Eng. <b>Dual-Flow Lube</b> (Std. Vers.) (Fleetguard LF9001)..... <b>BD7154 +</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF9001)..... <b>BD50000</b> <b>Dual-Flow Lube</b> (Fleetguard LF9031)..... <b>BD7509</b> <b>Dual-Flow Lube</b> (Fleetguard LF9000)..... <b>BD7153 +</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> (3406889)..... <b>BF1293-SPS</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1000)..... <b>BF1259</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1282)..... <b>BF1282 +</b> <b>Crankcase Breather</b> (3683918)... <b>CV15000</b> <b>Coolant</b> (w/o Chemicals) (Fleetguard WF2127)..... <b>B5087</b> <b>Coolant</b> (Controlled Release) (Fleetguard WF2121)..... <b>BW5250</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b>	Xpert w/Cummins ISM 10.8 (10.8L) Eng. (Cont'd) <b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> (3406889)..... <b>BF1293-SPS</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1000)..... <b>BF1259</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1282)..... <b>BF1282 +</b> <b>Crankcase Breather</b> (3683918)... <b>CV15000</b> <b>Coolant</b> (w/o Chemicals) (Fleetguard WF2127)..... <b>B5087</b> <b>Coolant</b> (Controlled Release) (Fleetguard WF2121)..... <b>BW5250</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b> Xpert w/Cummins L9N (8.9L) Eng. (2020) <b>Lube</b> (3401544)..... <b>B40142</b> <b>Fuel</b> (3607140)..... <b>BF7695</b> <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Xpert w/Cummins L9N (8.9L) Eng. (2021) <b>Lube</b> (Fleetguard LF14002NN).... <b>B40142</b> <b>Fuel</b> (Fleetguard NF5900)..... <b>BF7695</b> Xpert w/Cummins X12 (11.9L) Eng. (2022) <b>Lube</b> (5575298)..... <b>B40145</b> <b>Fuel</b> (5365988)..... <b>BF46129</b> XSpotter Off Road w/Cummins ISB 6.7 (6.7L) Eng. <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b> <b>Fuel</b> (Fleetguard FF5421)..... <b>BF7966</b> <b>Fuel</b> (Fleetguard FF5632)..... <b>BF7940</b> <b>Crankcase Breather</b> (Fleetguard CV52001)..... <b>CV15010</b> XSpotter Off Road w/Cummins QSB 6.7 (6.7L) Eng. (2010-17) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (4989106)..... <b>BF7922</b> XSpotter Off Road w/Cummins QSB 6.7 (6.7L) Eng. (2020) <b>Lube</b> (5444774)..... <b>B40142</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> Xspotter On Road w/Cummins ISL-G (8.9L) Eng. (2018) <b>Lube</b> (Fleetguard LF9009)..... <b>B40142</b> <b>Fuel/Water Separator</b> (Fleetguard NG5900)..... <b>BF7695</b> <b>Radial Seal Air</b> (Don. P527484)... <b>RS2863</b> <b>Radial Seal XP Air</b> (Don. P527484)..... <b>RS2863XP</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

AUTOCAR Trucks (cont'd)	AUTOCAR Trucks (cont'd)	AVAILABLE Trucks (cont'd)
XSpotter On Road w/Cummins ISL-G (8.9L) Eng. (2018) (Cont'd) Trans. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	XSpotter On Road w/Cummins ISL-G (8.9L) Eng. (2014-17) (Cont'd) <b>Dual-Flow Lube</b> (High Velocity) (Fleetguard LF9009)..... <b>BD7309</b> <b>Fuel</b> (Fleetguard NG5900)..... <b>BF7695</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b>	620, 630 w/Cummins Eng. <b>F-F Lube Bag</b> ..... <b>P996</b> <b>F-F Lube Ele.</b> ..... <b>P999-HD</b> <b>F-F Lube Spin-on</b> ..... <b>B196 +</b> <b>B-P Lube Ele.</b> ..... <b>C750-E +</b> <b>Fuel/Water Separator</b> ..... <b>BF1212 +</b> <b>4 3/8 In. Fuel Spin-on</b> ..... <b>BF948 +</b> <b>5 3/4 In. Fuel Spin-on</b> ..... <b>BF957 +</b> <b>11 7/32 In. Fuel Spin-on</b> ..... <b>BF596 +</b> <b>Breather Ele.</b> (w/Turbo) (255963) <b>PA643</b> <b>Breather Ele.</b> (w/o Turbo) (256837)..... <b>PA1627</b> <b>Turbocharger</b> ..... <b>BT112</b>
XSpotter On Road w/Cummins ISB 6.7 (6.7L) Eng. (2011-17) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel/Water Separator</b> (Fleetguard FS20081)..... <b>PF46171</b> <b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b> <b>Fuel</b> (Fleetguard FF5421)..... <b>BF7966</b> <b>Fuel</b> (Fleetguard FF5632)..... <b>BF7940</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> <b>Crankcase Breather</b> (Fleetguard CV52001)..... <b>CV15010</b> <b>Diesel Exhaust Fluid</b> (Fleetguard UF106)..... <b>PE17002 KIT</b>	XSpotter On Road w/Cummins ISL-G (8.9L) Eng. (2019) <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309</b> <b>Fuel/Water Separator</b> (Fleetguard NG5900)..... <b>BF7695</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b>	<b>BEAVER Buses</b>
XSpotter On Road w/Cummins ISB 6.7 (6.7L) Eng. (2018) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> <b>Radial Seal Air</b> (Don. P527484)... <b>RS2863</b> <b>Radial Seal XP Air</b> (Don. P527484)..... <b>RS2863XP</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b> <b>Trans.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	XSpotter On Road w/Cummins ISM 10.8 (10.8L) Eng. <b>Dual-Flow Lube</b> (Std. Vers.) (Fleetguard LF9001)..... <b>BD7154 +</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF9001)..... <b>BD50000</b> <b>Dual-Flow Lube</b> (Fleetguard LF9031)..... <b>BD7509</b> <b>Dual-Flow Lube</b> (Fleetguard LF9000)..... <b>BD7153 +</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> (3406889)..... <b>BF1293-SPS</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1000)..... <b>BF1259</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1282)..... <b>BF1282 +</b> <b>Crankcase Breather</b> (3683918)... <b>CV15000</b> <b>Coolant</b> (w/o Chemicals) (Fleetguard WF2127)..... <b>B5087</b> <b>Coolant</b> (Controlled Release) (Fleetguard WF2121)..... <b>BW5250</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b>	Models w/Deluxe CU <b>B-P Lube Sock</b> ..... <b>CU406<sup>90</sup></b>
XSpotter On Road w/Cummins ISB 6.7 (6.7L) Eng. (2019) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	<b>AVAILABLE Trucks</b>	Models w/Michiana SA15117 <b>Lube Ele.</b> ..... <b>P54</b>
XSpotter On Road w/Cummins ISB 6.7 (6.7L) Eng. (2020) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b> <b>Trans.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	200 <b>Lube</b> ..... <b>P42</b>	<b>BEAVER Motor Homes</b>
XSpotter On Road w/Cummins ISB 6.7 (6.7L) Eng. (2022) <b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b> <b>Trans.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	500 <b>Lube</b> ..... <b>P41</b>	Santiam <b>Dual-Flow Lube</b> (To unit number 142797) (Fleetguard LF3000)..... <b>BD103 +</b> <b>Dual-Flow Lube</b> (From unit number 142797) (Fleetguard LF9009)..... <b>BD7309 +</b> <b>P. Fuel/Water Separator</b> (w/Drain) (Fleetguard FS1242)..... <b>BF1249</b> <b>P. Fuel/Water Separator</b> (Open End for Bowl) (Fleetguard FS1242)..... <b>BF1249-O</b> <b>P. Fuel/Water Separator</b> (w/Drain & Sensor Port) (Fleetguard FS1242)..... <b>BF1249-SP</b> <b>P. Fuel/Water Separator</b> (w/Drain & Sensor Port, High Efficiency Version) (Fleetguard FS1242)..... <b>BF1393-SP</b> <b>P. Fuel/Water Separator</b> (From unit number 142797) (Fleetguard FS1003)..... <b>BF1293-SPS</b> <b>S. Fuel/Water Separator</b> (To unit number 142797) (Fleetguard FS1022)..... <b>BF1272-SPS</b> <b>S. Fuel</b> (From unit number 142797) (Fleetguard FF5488)..... <b>BF7815</b> <b>Radial Seal Air</b> (Don. P533930)... <b>RS3548</b> <b>Radial Seal XP Air</b> (Don. P533930)..... <b>RS3548XP</b> <b>Steering</b> (Nelson 83213D)..... <b>PT951</b>
XSpotter On Road w/Cummins ISL-G (8.9L) Eng. (2014-17) <b>Dual-Flow Lube</b> (Std. Version) (Fleetguard LF3000)..... <b>BD103 +</b>	550, 550X <b>Lube</b> (1955-on)..... <b>P80</b> <b>Lube</b> (1955-on)..... <b>P80-HD</b>	<b>BEDFORD Buses</b>
		BLP w/Bedford 500 CID Eng. <b>Lube Ele.</b> ..... <b>P356</b> <b>Can-Type Fuel</b> ..... <b>BF884</b>

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>BEDFORD</b> Buses (cont'd)	<b>BENDIX</b> Air Dryers (cont'd)	<b>BLACKROCK</b> Auxiliary Power Units (APU) (cont'd)
BRP w/Bedford 466 CID Eng. Lube Ele. .... PT12 Can-Type Fuel..... BF825 +	AD-9si Air Dryer (5008414)..... BA5374 +	Blackrock w/Kubota Z482 Eng. Lube (70000-15241)..... B179 Fuel (15231-43560)..... PF872 Radial Seal Air (Enginaire 2S-E1)..... RS3715
VAL, VAM Coaches w/Bedford Eng. Lube Ele. .... PT12 Can-Type Fuel..... BF825 + Air (To 1970)..... PA2958	AD-IP Air Dryer (65624)..... BA5373	Blackrock w/Kubota D722 Eng. Lube (70000-15241)..... B179 Fuel (15231-43560)..... PF872 Radial Seal Air (Enginaire 2S-E1)..... RS3715
YLQ, YMT w/Bedford 500 CID Eng. Lube Ele. .... P356 Can-Type Fuel..... BF884 8 In. Air..... PA2958	AD-IS Air Dryer (5008414)..... BA5374 +	
YRQ, YRT Coaches Lube Ele. .... PT12 Can-Type Fuel..... BF825 +	AD-SP Air Dryer (5008414)..... BA5374 +	
<b>BEDFORD</b> Trucks	<b>BENDIX-WESTINGHOUSE</b> Compressors	<b>BLUE BIRD</b> Buses
10-12 CWT Lube..... P40	Models w/Bendix-Westinghouse Breathers Air Breather (100783)..... PA1909	450 LXi w/Cat C13 Eng. Lube (To 1/2004) (1R0716)..... B99 + Lube (1/2004-on) (1R1808)..... B7299 + Fuel (High Efficiency) (1R0749).... BF7587 + Fuel (1R1712)..... BF614 + Trans. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT
200, 300 CID Gas Eng. Lube..... PT12	Truck Air Compressors Foam Breather (239292)..... PA1600 Breather Ele. (243009)..... PA1704	All-American w/Cat C7 Eng. (1/2004-on) Lube (1R1807)..... B7700 + Lube (1R1808)..... B7299 + Fuel/Water Separator (Racor S3230)..... BF1252 Fuel/Water Separator (Open End for Bowl) (Racor R90P)..... BF46083-O Fuel/Water Separator (w/Bowl) (Racor R90P)..... BF46072 Fuel/Water Separator (w/Drain) (Racor R90P)..... BF1329 Fuel/Water Separator (Sensor Port Thd. 9/16-18) (Racor R90P).. BF1329-SP Fuel/Water Separator (Sensor Port Thd. 1/2-20) (Racor R90P).... BF1339-SP + Fuel/Water Separator (Racor R90T)..... BF1390-O Fuel/Water Separator (w/SP) (Racor R90S)..... BF1360-SP Fuel/Water Separator (Open End for Bowl) (Racor R90S)..... BF1360-O Fuel/Water Separator (w/o SP) (Racor S3225P)..... BF1348 Fuel/Water Separator (w/SP) (Racor S3225P)..... BF1348-SP Fuel/Water Separator (Open End for Bowl) (Racor S3225P)..... BF1348-O Fuel/Water Separator (4934879) BF1378-SPS Fuel (1R0751)..... BF7632 Fuel (60586)..... BF7634 Air (6 In. Outlet) (1967744)..... PA3987 Air (7 In. Outlet) (126394)..... PA4653 Air Dryer (AD-9 System) (Bendix 107796)..... BA5377 Air Dryer (AD-IS, AD-SP System) (Bendix 5008414)..... BA5374 + Coolant (w/o Chemical) (9Y4528) B5134 +
KD, KDS, KE, KF, KG w/Bedford 300, 330 Diesel Eng. Lube..... PT12 Fuel Ele. (To 1963)..... PF838 Can-Type Fuel (1963-on)..... BF825 + Fuel Ele. (1963-on)..... PF816-S Air..... PA2958	Tru Flow 400, 500, 600, 1000 Air Compressors Air Breather..... PA1704	
TK Series w/Bedford 330 Diesel Eng. Lube..... PT12 Can-Type Fuel..... BF825 + Air (7964609)..... PA2958	<b>BERING</b> Trucks	
TK Series w/Bedford 500 CID Diesel Eng. Lube Ele. (1975-83)..... P356 Can-Type Fuel..... BF884 Air (7964609)..... PA2958	HDMX, HDSS, HDTT w/Cat C12 Eng. F-F Lube..... B99 + B-P Lube..... B7577 Fuel Spin-on..... BF7587 +	
TL Series w/Bedford 500 CID Diesel Eng. Lube Ele. (1980-83)..... P356 Can-Type Fuel..... BF884 8 In. Air (7964609)..... PA2958	HDSS, HDTT w/Cummins ISM Eng. Dual-Flow Lube..... BD7153 + Fuel/Water Separator..... BF1272-SPS	
TM Series w/Bedford 500 CID Diesel Eng. Lube Ele. (1975-83)..... P356 Can-Type Fuel..... BF884 19 1/2 In. Air..... PA2751	HDST w/Cat C10 Eng. F-F Lube..... B99 + B-P Lube..... B7577 Fuel Spin-on..... BF7587 +	
J4, J5, J6 w/Bedford 300, 330 Diesel Eng. Lube..... PT12 Fuel Ele. (To 1963)..... PF838 Can-Type Fuel (1963-on)..... BF825 + Fuel Ele. (1963-on)..... PF816-S Air..... PA2958	LD15A w/Detroit Diesel 638 (3.8L) Eng. Lube (41150066A)..... BT237 +	
<b>BENDIX</b> Air Dryers	MD23A, MD23M, MD26A, MD26M w/Cummins ISB 5.9L Eng. Lube..... B7177 Fuel/Water Separator Spin-on.... BF1271 Fuel Ele..... PF7777	
AD-9 Air Dryer (107794)..... BA5377	<b>BIEDERMAN</b> Trucks	
	Models w/Hercules JXD Eng. Lube..... P41	
	<b>BLACKROCK</b> Auxiliary Power Units (APU)	
	Blackrock w/Yanmar 2TNV70 Eng. Lube (119305-35150)..... B1400 Fuel (119810-55650)..... PF981 Radial Seal Air (Enginaire 2S-E1)..... RS3715	
	Blackrock w/Yanmar 3TNV70 Eng. Lube (119305-35150)..... B1400 Fuel (119810-55650)..... PF981 Radial Seal Air (Enginaire 2S-E1)..... RS3715	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



<b>BLUE BIRD Buses (cont'd)</b>	<b>BLUE BIRD Buses (cont'd)</b>	<b>BLUE BIRD Buses (cont'd)</b>
All-American w/Cat C7 Eng. (1/2004-on) (Cont'd)	All-American w/Cat C7 Eng. (To 1/2004) (Cont'd)	All-American w/Cat 3126 Eng. (To 1/2004) (Cont'd)
<b>Trans. Pan-Type</b> (AT Series, 3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b>	<b>Air</b> (7 In. Outlet) (126394)..... <b>PA4653</b>	<b>Fuel/Water Separator</b> (w/Bowl) (Racor R90P)..... <b>BF46072</b>
<b>Trans. Pan-Type</b> (AT & MT Series, 5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Fuel/Water Separator</b> (w/Drain) (Racor R90P)..... <b>BF1329</b>
<b>Trans. Spin-on</b> (AT & MT Series) (Allison 29510922)..... <b>BT8316-MPG</b>	<b>Air Dryer</b> (AD-IS, AD-SP System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Fuel/Water Separator</b> (Sensor Port Thd. 9/16-18) (Racor R90P).. <b>BF1329-SP</b>
<b>Trans. Pan-Type</b> (2000 Series, S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Coolant</b> (w/o Chemical) (9Y4528)..... <b>B5134 +</b>	<b>Fuel/Water Separator</b> (Sensor Port Thd. 1/2-20) (Racor R90P).... <b>BF1339-SP +</b>
<b>Trans. Pan-Type</b> (2000 Series, S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Trans. Pan-Type</b> (AT Series, 3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b>	<b>Fuel/Water Separator</b> (w/Drain) (Racor S3225P)..... <b>BF1348</b>
<b>Trans. Pan-Type</b> (2000 Series, D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Trans. Pan-Type</b> (AT & MT Series, 5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>	<b>Fuel/Water Separator</b> (w/Sensor Port) (Racor S3225P)..... <b>BF1348-SP</b>
<b>Trans. Pan-Type</b> (2000 Series, D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Trans. Spin-on</b> (AT & MT Series) (Allison 29510922)..... <b>BT8316-MPG</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor S3225P)..... <b>BF1348-O</b>
<b>Trans. Ele.</b> (3000 & 4000 Series, 2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Trans. Pan-Type</b> (2000 Series, S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Fuel/Water Separator</b> (w/Sensor Port) (23514654)..... <b>BF1330-SP</b>
<b>Trans. Ele.</b> (3000 & 4000 Series, 4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Trans. Pan-Type</b> (2000 Series, S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Fuel</b> (1R0751)..... <b>BF7632</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Trans. Pan-Type</b> (2000 Series, D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Fuel</b> (60586)..... <b>BF7634</b>
All-American w/Cat C7 Eng. (To 1/2004)	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Air</b> (1967744)..... <b>PA3987</b>
<b>Lube</b> (Standard Vers.) (1R0739).. <b>B76 +</b>	<b>Trans. Ele.</b> (3000 & 4000 Series, 2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
<b>Lube</b> (1R1808)..... <b>B7299 +</b>	<b>Trans. Ele.</b> (3000 & 4000 Series, 4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Air Dryer</b> (AD-IS, AD-SP System) (Bendix 5008414)..... <b>BA5374 +</b>
<b>Lube</b> (Severe Service) (1R0739).. <b>B76-SS +</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Coolant</b> (w/o Chemical) (9Y4528)..... <b>B5134 +</b>
<b>Fuel/Water Separator</b> (Racor S3230)..... <b>BF1252</b>	All-American w/Cat 3116 (6.6L) Eng.	<b>Trans. Pan-Type</b> (AT Series, 3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R90P)..... <b>BF46083-O</b>	<b>Lube</b> (Standard Vers.) (1R0739).. <b>B76 +</b>	<b>Trans. Pan-Type</b> (AT & MT Series, 5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>
<b>Fuel/Water Separator</b> (w/Bowl) (Racor R90P)..... <b>BF46072</b>	<b>Lube</b> (Severe Service) (1R0739).. <b>B76-SS +</b>	<b>Trans. Spin-on</b> (AT & MT Series) (Allison 29510922)..... <b>BT8316-MPG</b>
<b>Fuel/Water Separator</b> (w/Drain) (Racor R90P)..... <b>BF1329</b>	<b>Fuel/Water Separator Box-Style</b> (8N9803)..... <b>BF912</b>	<b>Trans. Pan-Type</b> (2000 Series, S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Fuel/Water Separator</b> (Sensor Port Thd. 9/16-18) (Racor R90P).. <b>BF1329-SP</b>	<b>Fuel/Water Coalescer Ele. w/Drain</b> (1174089)..... <b>BF7679-D</b>	<b>Trans. Pan-Type</b> (2000 Series, S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Fuel/Water Separator</b> (Sensor Port Thd. 1/2-20) (Racor R90P).... <b>BF1339-SP +</b>	<b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (1466695)..... <b>BF1350-SP</b>	<b>Trans. Pan-Type</b> (2000 Series, D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Fuel/Water Separator</b> (Racor R90T)..... <b>BF1390-O</b>	<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (1466695).... <b>BF46030-O</b>	<b>Trans. Pan-Type</b> (2000 Series, D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
<b>Fuel/Water Separator</b> (w/SP) (Racor R90S)..... <b>BF1360-SP</b>	<b>Fuel</b> (1R0751)..... <b>BF7632</b>	<b>Trans. Ele.</b> (3000 & 4000 Series, 2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R90S)..... <b>BF1360-O</b>	<b>Fuel</b> (1R0740)..... <b>BF970 +</b>	<b>Trans. Ele.</b> (3000 & 4000 Series, 4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Fuel/Water Separator</b> (w/o SP) (Racor S3225P)..... <b>BF1348</b>	<b>Fuel</b> (1R0750)..... <b>BF7633 +</b>	All-American w/Cat 3126 Eng. (To 1/2004)
<b>Fuel/Water Separator</b> (w/SP) (Racor S3225P)..... <b>BF1348-SP</b>	<b>Air Compressor Breather</b> (9L2169)..... <b>PA1704</b>	<b>Lube</b> (Standard Vers.) (1R0739).. <b>B76</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor S3225P)..... <b>BF1348-O</b>	All-American w/Cat 3126 Eng. (To 1/2004)	<b>Fuel/Water Separator</b> (w/Sensor Port) (Racor R90S)..... <b>BF1360-SP</b>
<b>Fuel/Water Separator</b> (4934879). <b>BF1378-SPS</b>	<b>Lube</b> (Standard Vers.) (1R0739).. <b>B76</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R90S)..... <b>BF1360-O</b>
<b>Fuel</b> (1R0751)..... <b>BF7632</b>	<b>Fuel/Water Separator</b> (w/Sensor Port) (Racor R90S)..... <b>BF1360-SP</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R90S)..... <b>BF1360-O</b>
<b>Fuel</b> (60586)..... <b>BF7634</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R90S)..... <b>BF1360-O</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R90T)..... <b>BF1390-O</b>
<b>Air</b> (6 In. Outlet) (1967744)..... <b>PA3987</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R90T)..... <b>BF1390-O</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R90P)..... <b>BF46083-O</b>
	<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R90P)..... <b>BF46083-O</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

BLUE BIRD Buses (cont'd)	BLUE BIRD Buses (cont'd)	BLUE BIRD Buses (cont'd)
All-American w/Cat 3126 Eng. (1/2004-on) (Cont'd)	All-American w/Cummins ISB (5.9L) Eng.	All-American w/Cummins ISB (5.9L) Eng. (Cont'd)
<b>Fuel/Water Separator</b> (w/Bowl) (Racor R90P)..... <b>BF46072</b>	<b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b>	<b>Trans. Pan-Type</b> (2000 Series, S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Fuel/Water Separator</b> (w/Drain) (Racor R90P)..... <b>BF1329</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19800)..... <b>PF7977</b>	<b>Trans. Pan-Type</b> (2000 Series, D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Fuel/Water Separator</b> (Sensor Port Thd. 9/16-18) (Racor R90P).. <b>BF1329-SP</b>	<b>Fuel/Water Separator Spin-on</b> (1966993)..... <b>BF1390-O</b>	<b>Trans. Spin-on</b> (2000 Series) (Allison 29539579)..... <b>BT8460</b>
<b>Fuel/Water Separator</b> (Sensor Port Thd. 1/2-20) (Racor R90P).... <b>BF1339-SP +</b>	<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Racor R90-BB-02)..... <b>BF46083-O</b>	<b>Trans. Ele.</b> (3000 & 4000 Series, 2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Fuel/Water Separator</b> (w/Drain) (Racor S3225P)..... <b>BF1348</b>	<b>Fuel/Water Separator Spin-on</b> (w/9/16-18 SP Thd.) (Racor R90-BB-02)..... <b>BF1329-SP</b>	<b>Trans. Ele.</b> (3000 & 4000 Series, 4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Fuel/Water Separator</b> (w/Sensor Port) (Racor S3225P)..... <b>BF1348-SP</b>	<b>Fuel/Water Separator Spin-on</b> (w/1/2-20 SP Thd.) (Racor R90-BB-02)..... <b>BF1339-SP +</b>	
<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor S3225P)..... <b>BF1348-O</b>	<b>Fuel/Water Separator Spin-on</b> (w/Bowl) (Racor R90-BB-02)..... <b>BF46072</b>	
<b>Fuel/Water Separator</b> (w/Sensor Port) (23514654)..... <b>BF1330-SP</b>	<b>Fuel/Water Separator Spin-on</b> (w/Drain) (Racor R90-BB-02)..... <b>BF1329</b>	
<b>Fuel</b> (1R0751)..... <b>BF7632</b>	<b>Fuel/Water Separator Spin-on</b> (w/Drain) (Racor S3230)..... <b>BF1252</b>	
<b>Fuel</b> (60586)..... <b>BF7634</b>	<b>Fuel/Water Separator Spin-on</b> (w/o SP) (4299582)..... <b>BF1348</b>	
<b>Air</b> (1967744)..... <b>PA3987</b>	<b>Fuel/Water Separator Spin-on</b> (w/SP) (4299582)..... <b>BF1348-SP</b>	
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (4299582)..... <b>BF1348-O</b>	
<b>Air Dryer</b> (AD-IS, AD-SP System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Fuel/Water Separator</b> (w/SP) (Racor R90S)..... <b>BF1360-SP</b>	
<b>Coolant</b> (w/o Chemical) (9Y4528) <b>Trans. Pan-Type</b> (AT Series, 3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R90S)..... <b>BF1360-O</b>	
<b>Trans. Pan-Type</b> (AT & MT Series, 5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>	<b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1022)..... <b>BF1272-SPS</b>	
<b>Trans. Spin-on</b> (AT & MT Series) (Allison 29510922)..... <b>BT8316-MPG</b>	<b>Fuel</b> (4934845)..... <b>BF7940</b>	
<b>Trans. Pan-Type</b> (2000 Series, S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Disposable Air Hsg.</b> (6 In. Outlet) (1967744)..... <b>PA3987</b>	
<b>Trans. Pan-Type</b> (2000 Series, S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Disposable Air Hsg.</b> (7 In. Outlet) (126394)..... <b>PA4653</b>	
<b>Trans. Pan-Type</b> (2000 Series, D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Radial Seal O. Air</b> (10004113)..... <b>RS5756</b>	
<b>Trans. Pan-Type</b> (2000 Series, D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Radial Seal I. Air</b> (10004114)..... <b>RS30237</b>	
<b>Trans. Ele.</b> (3000 & 4000 Series, 2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	
<b>Trans. Ele.</b> (3000 & 4000 Series, 4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Air Dryer</b> (AD-IS, AD-SP System) (Bendix 5008414)..... <b>BA5374 +</b>	
All-American w/Cat 3208 Eng.	<b>Crankcase Breather</b> (Fleetguard CV52001)..... <b>CV15010</b>	
<b>Lube</b> (1R0713)..... <b>[2] BT230 +</b>	<b>Coolant</b> (w/o Chemical) (64641).. <b>B5134 +</b>	
<b>Lube</b> (1R0714)..... <b>[2] B75</b>	<b>Coolant</b> (w/2 Units BTA +) (Fleetguard WF2070)..... <b>BW5070</b>	
<b>Lube</b> (9L9200)..... <b>[2] BT364</b>	<b>Trans. Pan-Type</b> (AT Series, 3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b>	
<b>Fuel/Water Separator</b> (8N9803).. <b>BF912</b>	<b>Trans. Pan-Type</b> (AT & MT Series, 5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>	
<b>P. Fuel Ele.</b> (9M2341)..... <b>PF935</b>	<b>Trans. Spin-on</b> (AT & MT Series, Auxiliary) (Allison 29510922)..... <b>BT8316-MPG</b>	
<b>Fuel Spin-on</b> (1R0740)..... <b>BF970 +</b>	<b>Trans. Pan-Type</b> (2000 Series, S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	
<b>Fuel Spin-on</b> (1R0750)..... <b>BF7633 +</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>BLUE BIRD Buses (cont'd)</b>	<b>BLUE BIRD Buses (cont'd)</b>	<b>BLUE BIRD Buses (cont'd)</b>
All-American w/Cummins ISB (6.7L) Eng. (Cont'd)	All-American w/Cummins ISC Eng. (Cont'd)	All-American w/Cummins ISL-G Eng. (Cont'd)
<b>Trans. Ele.</b> (3000 Series, 2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	<b>Trans. Spin-on</b> (AT & MT Series, Auxiliary) (Allison 29510922)..... <b>BT8316-MPG</b>	<b>Trans.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>
<b>Trans. Ele.</b> (3000 Series, 4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	<b>Trans. Pan-Type</b> (2000 Series, S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	All-American w/Cummins M11 (10.8L) Eng.
All-American w/Cummins ISC Eng.	<b>Trans. Pan-Type</b> (2000 Series, S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b>
<b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b>	<b>Trans. Pan-Type</b> (2000 Series, D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b>
<b>Fuel/Water Separator</b> (w/o SP) (Racor R90-BB-02)..... <b>BF1329</b>	<b>Trans. Pan-Type</b> (2000 Series, D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Fuel/Water Separator Spin-on</b> (2568753)..... <b>BF1259</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R90-BB-02)..... <b>BF46083-O</b>	<b>Trans. Spin-on</b> (2000 Series) (Allison 29539579)..... <b>BT8460</b>	All-American w/Cummins 6BT5.9 (5.9L) Eng.
<b>Fuel/Water Separator</b> (w/9/16-18 SP Thd.) (Racor R90-BB-02)..... <b>BF1329-SP</b>	<b>Trans. Ele.</b> (3000 & 4000 Series, 2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Lube</b> (Fleetguard LF3972)..... <b>BT7349</b>
<b>Fuel/Water Separator</b> (w/Bowl) (Racor R90-BB-02)..... <b>BF46072</b>	<b>Trans. Ele.</b> (3000 & 4000 Series, 4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1251)..... <b>BF1226</b>
<b>Fuel/Water Separator</b> (w/1/2-20 SP Thd.) (Racor R90-BB-02)..... <b>BF1339-SP +</b>	<b>Diesel Exhaust Fluid</b> (5303604)..... <b>PE17000</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1280)..... <b>BF1280 +</b>
<b>Fuel/Water Separator</b> (Racor S3230)..... <b>BF1252</b>	All-American w/Cummins ISL 8.9 (8.9L) Eng.	<b>Fuel</b> (Fleetguard FF5052)..... <b>BF788</b>
<b>Fuel/Water Separator</b> (Racor R90T)..... <b>BF1390-O</b>	<b>Dual-Flow Lube</b> (Standard Vers.) (3318853)..... <b>BD103 +</b>	<b>Trans. Pan-Type</b> (AT Series, 3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b>
<b>Fuel/Water Separator</b> (w/o SP) (4299582)..... <b>BF1348</b>	<b>Dual-Flow Lube</b> (High Velocity) (3401544)..... <b>BD7309 +</b>	<b>Trans. Pan-Type</b> (AT Series, 5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>
<b>Fuel/Water Separator</b> (w/SP) (4299582)..... <b>BF1348-SP</b>	<b>Lube</b> (Upgrade) (3401544)..... <b>B40142 +</b>	<b>Trans. Spin-on</b> (AT Series) (Allison 29510922)..... <b>BT8316-MPG</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (4299582)..... <b>BF1348-O</b>	<b>Fuel/Water Separator</b> (3800394)..... <b>BF1272-SPS</b>	All-American w/Cummins 6CT8.3 (8.3L) Eng.
<b>Fuel/Water Separator</b> (w/SP) (Racor R90S)..... <b>BF1360-SP</b>	<b>Fuel/Water Separator</b> (4934879)..... <b>BF1378-SPS</b>	<b>F-F Lube</b> (3313281)..... <b>B205 +</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R90S)..... <b>BF1360-O</b>	<b>Fuel/Water Separator</b> (3406889)..... <b>BF1293-SPS</b>	<b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b>
<b>Fuel/Water Separator</b> (Fleetguard FS1003)..... <b>BF1293-SPS</b>	<b>Fuel</b> (3959612)..... <b>BF7815</b>	<b>Fuel/Water Separator</b> (3925274)..... <b>BF1280 +</b>
<b>Fuel</b> (Fleetguard FF5488)..... <b>BF7815</b>	<b>Fuel</b> (4940647)..... <b>BF7924</b>	<b>Opt. Fuel/Water Separator</b> (3903202)..... <b>BF1226</b>
<b>Fuel</b> (Fleetguard FF5636)..... <b>BF7924</b>	<b>Coolant</b> (w/4 Units BTA+) (3315116)..... <b>BW5071</b>	<b>Fuel</b> (3903640)..... <b>BF788</b>
<b>Disposable Air Hsg.</b> (1967744)..... <b>PA3987</b>	<b>Coolant</b> (Controlled Release BTA+) (Fleetguard WF2121)..... <b>BW5250</b>	All-American w/Detroit Diesel 8.2L Eng.
<b>Single Radial Seal Air</b> (10004112)..... <b>RS30313</b>	<b>Trans. Ele. (2 In. Kit)</b> (Allison 29545776)..... <b>PT9416-MPG KIT</b>	<b>Lube</b> (23518668)..... <b>B6-HPG +</b>
<b>O. Air</b> (10013632)..... <b>RS30133</b>	<b>Trans. Ele. (4 In. Kit)</b> (Allison 29548988)..... <b>PT9415-MPG KIT</b>	<b>Fuel/Water Separator</b> (12542374)..... <b>BF1266</b>
<b>I. Air</b> (10013633)..... <b>RS30134</b>	All-American w/Cummins ISL-G Eng.	<b>P. Fuel</b> (23518527)..... <b>BF592 +</b>
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Dual-Flow Lube</b> (Fleetguard LF3000)..... <b>BD103 +</b>	<b>S. Fuel</b> (23518526)..... <b>BF593</b>
<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b>	All-American w/John Deere 6068 (6.8L) CNG Eng.
<b>Air Dryer</b> (AD-IS, AD-SP System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Fuel</b> (Fleetguard NG5900)..... <b>BF7695</b>	<b>Lube</b> (T19044)..... <b>BT259</b>
<b>Coolant</b> (w/o Chemical) (64641)..... <b>B5134 +</b>	<b>Air</b> (1967744)..... <b>PA3987</b>	<b>Air</b> (1967744)..... <b>PA3987</b>
<b>Coolant</b> (w/2 Units BTA+) (Fleetguard WF2070)..... <b>BW5070</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
<b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>	<b>Air Dryer</b> (AD-SP System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Air Dryer</b> (AD-IS, AD-SP System) (Bendix 5008414)..... <b>BA5374 +</b>
<b>Trans. Pan-Type</b> (AT Series, 3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b>	<b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>	<b>Trans. Pan-Type</b> (AT Series, 3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b>
<b>Trans. Pan-Type</b> (AT & MT Series, 5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>	<b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b>	<b>Trans. Pan-Type</b> (AT & MT Series, 5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>
	<b>Trans. (2 In. Kit)</b> (Allison 29548987)..... <b>PT9416-MPG KIT</b>	<b>Trans. Spin-on</b> (AT & MT Series) (Allison 29510922)..... <b>BT8316-MPG</b>
		<b>Trans. Pan-Type</b> (2000 Series, S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
		<b>Trans. Pan-Type</b> (2000 Series, S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

BLUE BIRD Buses (cont'd)	BLUE BIRD Buses (cont'd)	BLUE BIRD Buses (cont'd)
All-American w/John Deere 6068 (6.8L) CNG Eng. (Cont'd)	All American FE w/Cummins B6.7 (6.7L) Eng. (2019)	All American FE w/Cummins ISB 6.7 (6.7L) Eng. (2017) (Cont'd)
<b>Trans. Pan-Type</b> (2000 Series, D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Lube</b> (3937736)..... <b>B7177</b>	<b>Fuel/Water Separator</b> (4934879)..... <b>BF1378-SPS</b>
<b>Trans. Pan-Type</b> (2000 Series, D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Fuel/Water Separator</b> (R34000BB01)..... <b>BF46169-O</b>	<b>Fuel</b> (4934845)..... <b>BF7940</b>
<b>Trans. Spin-on</b> (2000 Series) (Allison 29539579)..... <b>BT8460</b>	<b>Fuel</b> (5303743)..... <b>BF63000</b>	<b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b>
<b>Trans. Ele.</b> (3000 & 4000 Series, 2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Disposable Housing Air</b> (1967744)..... <b>PA3987</b>
<b>Trans. Ele.</b> (3000 & 4000 Series, 4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Crankcase Breather</b> (Fleetguard CV52001)..... <b>CV15010</b>
All-American w/John Deere 6081 (8.1L) CNG Eng.	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Trans.</b> (2 In. Kit) (Allison 29558328)..... <b>PT9416-MPG KIT</b>
<b>Lube Ele.</b> (RE509672)..... <b>P7233</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Trans.</b> (4 In. Kit) (Allison 29558329)..... <b>PT9415-MPG KIT</b>
<b>Lube Spin-on</b> (RE57394)..... <b>BT486</b>	<b>Crackcase Breather</b> (4936636)..... <b>CV15010</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Air</b> (1967744)..... <b>PA3987</b>	All American FE w/Cummins B6.7 (6.7L) Eng. (2020)	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Lube</b> (3937736)..... <b>B7177</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Air Dryer</b> (AD-IS, AD-SP System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Fuel/Water Separator</b> (1966993)..... <b>BF1390-O</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
<b>Coolant</b> (64641)..... <b>B5134 +</b>	<b>Fuel/Water Separator</b> (R34000BB01)..... <b>BF46169-O</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>Trans. Pan-Type</b> (AT Series, 3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b>	<b>Fuel</b> (5303743)..... <b>BF63000</b>	<b>Diesel Exhaust Fluid</b> (Fleetguard UF106)..... <b>PE17002 KIT</b>
<b>Trans. Pan-Type</b> (AT & MT Series, 5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>	<b>Cab Air</b> ..... <b>CLN&amp;R</b>	All American FE w/Cummins ISB 6.7 (6.7L) Eng. (2018)
<b>Trans. Spin-on</b> (AT & MT Series) (Allison 29510922)..... <b>BT8316-MPG</b>	<b>Crankcase Breather</b> (4936636)..... <b>CV15010</b>	<b>Lube</b> (3637736)..... <b>B7177</b>
<b>Trans. Pan-Type</b> (2000 Series, S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Coolant</b> (64641)..... <b>B5134 +</b>	<b>Fuel/Water Separator</b> (R34000BB01)..... <b>BF46169-O</b>
<b>Trans. Pan-Type</b> (2000 Series, S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Trans. Spin-on</b> (33381)..... <b>BT8460</b>	<b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b>
<b>Trans. Pan-Type</b> (2000 Series, D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	All American FE w/Cummins B6.7 (6.7L) Eng. (2021)	<b>Air</b> (Farr 119861003)..... <b>PA3987</b>
<b>Trans. Pan-Type</b> (2000 Series, D. Pan w/Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Lube</b> (3937736)..... <b>B7177</b>	<b>Crankcase Breather</b> (4936636)..... <b>CV15010</b>
<b>Trans. Pan-Type</b> (2000 Series, D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Fuel</b> (5303743)..... <b>BF63000</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Trans. Spin-on</b> (2000 Series) (Allison 29539579)..... <b>BT8460</b>	<b>Crackcase Breather</b> (4936636)..... <b>CV15010</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Trans. Ele.</b> (3000 & 4000 Series, 2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Trans. Ele.</b> (3000 & 4000 Series, 4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
All American FE w/Cummins B6.7 (6.7L) Eng. (2018)	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
<b>Lube</b> (3937736)..... <b>B7177</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>Fuel/Water Separator</b> (Fleetguard FS20081)..... <b>PF46171</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Crankcase Breather</b> (4936636)..... <b>CV15010</b>	All American FE w/Cummins B6.7 (6.7L) Eng. (2022)	<b>Crackcase Breather</b> (4936636)..... <b>CV15010</b>
<b>Diesel Exhaust Fluid</b> (4388378)..... <b>PE17002 KIT</b>	<b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b>	All American FE w/Cummins L9 (9.0L) Eng. (2020)
All American FE w/Cummins B6.7 (6.7L) Eng. (2018)	All American FE w/Cummins B6.7 (6.7L) Eng. (2023)	<b>Lube</b> (5444774)..... <b>B40142</b>
<b>Lube</b> (3937736)..... <b>B7177</b>	<b>Lube</b> (3937736)..... <b>B7177</b>	<b>Fuel/Water Separator</b> (R34000BB01)..... <b>BF46169-O</b>
<b>Fuel/Water Separator</b> (Fleetguard FS20081)..... <b>PF46171</b>	All American FE w/Cummins ISB 6.7 (6.7L) Eng. (2017)	<b>Fuel</b> (5303743)..... <b>BF63000</b>
<b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b>	<b>Lube</b> (3937736)..... <b>B7177</b>	<b>Cab Air</b> ..... <b>CLN&amp;R</b>
<b>Crankcase Breather</b> (4936636)..... <b>CV15010</b>	<b>Fuel/Water Separator</b> (FS20081)..... <b>PF46171</b>	<b>Trans. Spin-on</b> (33381)..... <b>BT8460</b>
<b>Diesel Exhaust Fluid</b> (4388378)..... <b>PE17002 KIT</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

BLUE BIRD Buses (cont'd)	BLUE BIRD Buses (cont'd)	BLUE BIRD Buses (cont'd)
All American RE w/Cummins B6.7 (6.7L) Eng. (2018)	All American RE w/Cummins B6.7 (6.7L) Eng. (2022)	All American RE w/Cummins ISB 6.7 (6.7L) Eng. (2018) (Cont'd)
Lube (3937736)..... B7177	Lube (Fleetguard LF3970)..... B7177	Trans. Spin-on (Allison 29539579)..... BT8460
<b>Fuel/Water Separator</b> (Fleetguard FS20081)..... PF46171	All American RE w/Cummins B6.7 (6.7L) Eng. (2023)	Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT
Fuel (Fleetguard FF63009)..... BF63000	Lube (3937736)..... B7177	Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT
Crankcase Breather (4936636)... CV15010	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004	All American RE w/Cummins ISL 8.9 (8.9L) Eng. (2018)
Diesel Exhaust Fluid (4388378).. PE17002 KIT	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016	Dual-Flow Lube (Fleetguard LF9009)..... BD7309 +
All American RE w/Cummins B6.7 (6.7L) Eng. (2019)	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003	<b>Fuel/Water Separator</b> (R34000BB01)..... BF46169-O
Lube (3937736)..... B7177	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017	Fuel (Fleetguard FF63009)..... BF63000
<b>Fuel/Water Separator</b> (R34000BB01)..... BF46169-O	Trans. Spin-on (Allison 29539579)..... BT8460	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004
Fuel (5303743)..... BF63000	All American RE w/Cummins ISB 6.7 (6.7L) Eng. (2017)	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016
Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004	Lube (3937736)..... B7177	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003
Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016	<b>Fuel/Water Separator</b> (4934879). BF1378-SPS	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20017
Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003	Fuel (4934845)..... BF7940	Trans. Spin-on (Allison 29539579)..... BT8460
Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017	Fuel (Fleetguard FF63009)..... BF63000	Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT
Trans. Spin-on (Allison 29539579)..... BT8460	<b>Disposable Housing Air</b> (1967744)..... PA3987	Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT
<b>Crankcase Breather</b> (4936636)... CV15010	<b>Crankcase Breather</b> (Fleetguard CV52001)..... CV15010	All American RE w/Cummins ISL 8.9 (8.9L) Eng. (2020)
All American RE w/Cummins B6.7 (6.7L) Eng. (2020)	Trans. (2 In. Kit) (Allison 29558328)..... PT9416-MPG KIT	Lube (5444774)..... B40142
Lube (3937736)..... B7177	Trans. (4 In. Kit) (Allison 29558329)..... PT9415-MPG KIT	Fuel (5303743)..... BF63000
<b>Fuel/Water Separator</b> (1966993). BF1390-O	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004	<b>Cab Air</b> ..... CLN&R
<b>Fuel/Water Separator</b> (R34000BB01)..... BF46169-O	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016	Trans. (33381)..... BT8460
Fuel (5303743)..... BF63000	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003	All American RE w/Cummins ISL-G (8.9L) Eng. (2018)
<b>Cab Air</b> ..... CLN&R	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017	Dual-Flow Lube (Fleetguard LF9009)..... BD7309 +
<b>Crankcase Breather</b> (4936636)... CV15010	Trans. Spin-on (Allison 29539579)..... BT8460	<b>Fuel/Water Separator</b> (Fleetguard NG5900)..... BF7695
<b>Coolant</b> (64641)..... B5134 +	<b>Diesel Exhaust Fluid</b> (Fleetguard UF106)..... PE17002 KIT	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004
Trans. Spin-on (33381)..... BT8460	All American RE w/Cummins ISB 6.7 (6.7L) Eng. (2018)	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016
All American RE w/Cummins B6.7 (6.7L) Eng. (2021)	Lube (3937736)..... B7177	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003
Lube (3937736)..... B7177	<b>Fuel/Water Separator</b> (R34000BB01)..... BF46169-O	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017
Fuel (5303743)..... BF63000	Fuel (Fleetguard FF63009)..... BF63000	Trans. Spin-on (Allison 29539579)..... BT8460
<b>Crankcase Breather</b> (4936636)... CV15010	<b>Air</b> (Farr 119861003)..... PA3987	Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT
Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004	<b>Crankcase Breather</b> (4936636)... CV15010	Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT
Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004	
Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016	
Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003	
Trans. Spin-on (Allison 29539579)..... BT8460	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017	
Trans. Ele. (2 In. Kit) (Allison 29558117)..... PT9416-MPG KIT		
Trans. Ele. (4 In. Kit) (Allison 29558118)..... PT9415-MPG KIT		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

BLUE BIRD Buses (cont'd)	BLUE BIRD Buses (cont'd)	BLUE BIRD Buses (cont'd)
All American RE w/Cummins ISL-G (8.9L) Eng. (2019) <b>Dual-Flow Lube</b> (Fleetguard LF3000)..... <b>BD103</b> <b>Fuel/Water Separator</b> (Fleetguard NG5900)..... <b>BF7695</b> <b>Disposable Housing Air</b> (1967744)..... <b>PA3987</b> <b>Radial Seal Air</b> (500454001)..... <b>RS5756</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	All American RE w/Cummins L9 (9.0L) Eng. (2021) (Cont'd) <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	Commercial Bus w/Cat 3116 (6.6L) Eng. (Cont'd) <b>Fuel</b> (1R0751)..... <b>BF7632</b> <b>Fuel</b> (1R0740)..... <b>BF970 +</b> <b>Fuel</b> (1R0750)..... <b>BF7633 +</b> <b>Air Compressor Breather</b> (9L2169)..... <b>PA1704</b>
All American RE w/Cummins L9 (9.0L) Eng. (2018) <b>Lube</b> (3401544)..... <b>B40142</b> <b>Fuel/Water Separator</b> (Fleetguard FS20081)..... <b>PF46171</b> <b>Fuel</b> (Fleetguard FF63008)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636)..... <b>CV15010</b> <b>Coolant</b> (Fleetguard WF2123)..... <b>B5090</b> <b>Diesel Exhaust Fluid</b> (Fleetguard UF106)..... <b>PE17002 KIT</b>	All American RE w/Cummins L9 (9.0L) Eng. (2022) <b>Lube</b> (5520789)..... <b>B40142</b>	Commercial Bus w/Cat 3126 (7.2L) Eng. <b>Lube</b> (1R1807)..... <b>B7700 +</b> <b>Fuel/Water Separator</b> (1752949)..... <b>BF1268</b> <b>Fuel/Water Separator</b> (2568753)..... <b>BF1259</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (1986378)..... <b>BF7798-SP</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (1986378)..... <b>BF7798-O</b> <b>Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (1R0751)..... <b>BF7632</b>
All American RE w/Cummins L9 (9.0L) Eng. (2019) <b>Lube</b> (3401544)..... <b>B40142</b> <b>Fuel/Water Separator</b> (Fleetguard FS20081)..... <b>PF46171</b> <b>Fuel/Water Separator</b> (R34000BB01)..... <b>BF46169-O</b> <b>Fuel</b> (5660774)..... <b>BF63000</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Diesel Exhaust Fluid</b> (Fleetguard UF106)..... <b>PE17002 KIT</b>	All American RE w/Cummins L9 (9.0L) Eng. (2023) <b>Lube</b> (5520789)..... <b>B40142</b>	Commercial Bus w/Cat C7 (7.2L) Eng. <b>F-F Lube</b> (1R1808)..... <b>B7299 +</b> <b>F-F Lube</b> (1R1807)..... <b>B7700 +</b> <b>Fuel/Water Separator</b> (2568753)..... <b>BF1259</b> <b>Fuel/Water Separator</b> (1752949)..... <b>BF1268</b> <b>Fuel</b> (1R0751)..... <b>BF7632</b>
All American RE w/Cummins L9 (9.0L) Eng. (2020) <b>Lube</b> (5444774)..... <b>B40142</b> <b>Fuel/Water Separator</b> (Fleetguard FS20081)..... <b>PF46171</b> <b>Fuel/Water Separator</b> (R34000BB01)..... <b>BF46169-O</b> <b>Fuel</b> (5660774)..... <b>BF63000</b> <b>Cab Air</b> ..... <b>CLN&amp;R</b> <b>Trans. Spin-on</b> (33381)..... <b>BT8460</b> <b>Diesel Exhaust Fluid</b> (Fleetguard UF106)..... <b>PE17002 KIT</b>	All American RE w/Cummins L9N (8.9L) Eng. (2019) <b>Lube</b> (3401544)..... <b>B40142</b>	Commercial Bus w/Cat C12 (12.0L) Eng. <b>Lube</b> (Standard Vers.) (1R0716).. <b>B99 +</b> <b>Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> <b>B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Racor R120T)..... <b>BF1395-O</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (Racor R120T)..... <b>BF1265</b> <b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (Racor R120T).... <b>BF1395-SP</b> <b>Fuel/Water Separator Spin-on</b> (2568753)..... <b>BF1259</b> <b>Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (Standard Vers.) (4N5823)..... <b>BF614 +</b> <b>Fuel Spin-on</b> (High Efficiency Vers.)..... <b>BF7587 +</b>
All American RE w/Cummins L9 (9.0L) Eng. (2021) <b>Lube</b> (5444774)..... <b>B40142</b> <b>Fuel/Water Separator</b> (Fleetguard FS20081)..... <b>PF46171</b> <b>Fuel</b> (5660774)..... <b>BF63000</b> <b>Cab Air</b> ..... <b>CLN&amp;R</b> <b>Trans. Spin-on</b> (33381)..... <b>BT8460</b> <b>Diesel Exhaust Fluid</b> (Fleetguard UF106)..... <b>PE17002 KIT</b>	All American RE w/Cummins L9N (8.9L) Eng. (2020) <b>Lube</b> (3401544)..... <b>B40142</b> <b>Fuel</b> (3607140)..... <b>BF7695</b>	Commercial Bus w/Cummins 6BT5.9 (5.9L) Eng. <b>Lube</b> (Fleetguard LF3972)..... <b>BT7349</b> <b>Fuel/Water Separator</b> (Fleetguard FS1251)..... <b>BF1226</b> <b>Fuel/Water Separator</b> (Fleetguard FS1280)..... <b>BF1280 +</b> <b>Fuel</b> (Fleetguard FF5052)..... <b>BF788</b>
All American RE w/Cummins L9 (9.0L) Eng. (2021) <b>Lube</b> (5444774)..... <b>B40142</b> <b>Fuel/Water Separator</b> (Fleetguard FS20081)..... <b>PF46171</b> <b>Fuel</b> (5660774)..... <b>BF63000</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	All American RE w/Cummins L9N (8.9L) Eng. (2021) <b>Lube</b> (Fleetguard LF14002NN).... <b>B40142</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	Commercial Bus w/Cummins 6CT8.3 (8.3L) Eng. <b>F-F Lube</b> (3313281)..... <b>B205 +</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Fuel/Water Separator</b> (3925274)..... <b>BF1280 +</b> <b>Fuel/Water Separator</b> (Fleetguard FS1251)..... <b>BF1226</b>
All American RE w/Electric Motor (2018) <b>Cab Air</b> ..... <b>CLN&amp;R</b>	Commercial Bus w/Cat 3116 (6.6L) Eng. <b>Lube</b> (Standard Vers.) (1R0739).. <b>B76 +</b> <b>Lube</b> (Severe Service) (1R0739).. <b>B76-SS +</b> <b>Fuel/Water Separator Box-Style</b> (8N9803)..... <b>BF912</b> <b>Fuel/Water Coalescer Ele. w/Drain</b> (1174089)..... <b>BF7679-D</b> <b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (1466695)..... <b>BF1350-SP</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (1466695).... <b>BF46030-O</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).


<b>BLUE BIRD Buses (cont'd)</b>	<b>BLUE BIRD Buses (cont'd)</b>	<b>BLUE BIRD Buses (cont'd)</b>
Commercial Bus w/Cummins 6CT8.3 (8.3L) Eng. (Cont'd) <b>Fuel</b> (3903640)..... <b>BF788</b>	Commercial Bus w/Detroit Diesel Series 50 (8.5L) Eng. <b>Lube</b> (23530573)..... [2] <b>B495</b>	Micro Bird w/Ford 6.0L Turbo Diesel Eng. <b>Lube</b> (w/o Screw on Cap) (Motorcraft FL2016)..... <b>P7235</b>
Commercial Bus w/Cummins ISB (5.9L) Eng. <b>Lube</b> (3937736)..... <b>B7177</b> <b>Lube</b> (4897898)..... <b>BT7237</b> <b>Fuel/Water Separator Ele.</b> (3942470)..... <b>PF7777</b> <b>Fuel/Water Separator Spin-on</b> (3942533)..... <b>BF1271</b> <b>Fuel/Water Separator Spin-on</b> (3406889)..... <b>BF1293-SPS</b> <b>Fuel/Water Separator Spin-on</b> (4934879)..... <b>BF1378-SPS</b> <b>Fuel</b> (Fleetguard FF5632)..... <b>BF7940</b>	<b>Fuel/Water Separator Spin-on</b> (23516189)..... <b>BF5812</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (23535985)..... <b>BF5813 +</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (23535985).. <b>BF5813-O +</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b>	<b>Lube</b> (w/Screw on Cap) (Wix 57313)..... <b>P7437</b> <b>Fuel</b> (Motorcraft FD4604)..... <b>PF7812 KIT</b> <b>Air</b> (Motorcraft FA1804)..... <b>PA4171</b> <b>Trans.</b> (AODE) (Motorcraft FT158)..... <b>18029</b> <b>Trans.</b> (5R110W, To 11/07) (Motorcraft FT144)..... <b>20005</b> <b>Trans.</b> (5R110W, 11/07-on) (Motorcraft FT180)..... <b>20021</b>
Commercial Bus w/Cummins ISC 8.3 (8.3L) Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Dual-Flow Lube</b> (Fleetguard LF9548)..... <b>BD324 +</b> <b>Fuel/Water Separator Spin-on</b> (3800394)..... <b>BF1272-SPS</b> <b>Fuel/Water Separator Spin-on</b> (3942533)..... <b>BF1271</b> <b>Fuel/Water Separator Spin-on</b> (4934879)..... <b>BF1378-SPS</b> <b>Fuel/Water Separator Spin-on</b> (3406889)..... <b>BF1293-SPS</b> <b>Fuel</b> (Fleetguard FF5488)..... <b>BF7815</b> <b>Fuel</b> (Fleetguard FF5636)..... <b>BF7924</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b> <b>Coolant</b> (w/23 Units BTA+) (Fleetguard WF2076)..... <b>BW5076</b> <b>Coolant</b> (w/Controlled Release) (Fleetguard WF2121)..... <b>BW5250</b>	Commercial Bus w/Detroit Diesel Series 60 (11.1L) Eng. <b>Lube</b> (23530573)..... [2] <b>B495</b> <b>Lube</b> (Don. DELF3998)..... [2] <b>B495-SS</b> <b>Fuel/Water Separator Spin-on</b> (23516189)..... <b>BF5812</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (23535985)..... <b>BF5813 +</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl, w/o ProDrive) (23535985)..... <b>BF5813-O +</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b> <b>S. Fuel</b> (23530645)..... <b>BF5815</b> <b>S. Fuel</b> (23533726)..... <b>BF5816</b>	Micro Bird w/Ford 6.8L Gas Eng. <b>Lube</b> (Motorcraft FL820S)..... <b>B329</b> <b>Fuel</b> (Motorcraft FG986B)..... <b>BF7668 +</b> <b>Air</b> (Motorcraft FA1632)..... <b>PA4075</b> <b>Trans.</b> (AODE) (Motorcraft FT158)..... <b>18029</b> <b>Trans.</b> (5R110W, To 11/07) (Motorcraft FT144)..... <b>20005</b> <b>Trans.</b> (5R110W, 11/07-on) (Motorcraft FT180)..... <b>20021</b>
Commercial Bus w/Cummins M11 (10.8L) Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> (2568753)..... <b>BF1259</b>	Commercial Bus w/Detroit Diesel Series 60 (12.7L) Eng. <b>F-F Lube</b> (23530573)..... [2] <b>B495</b> <b>F-F Lube</b> (Don. DELF3998)..... [2] <b>B495-SS</b> <b>B-P Lube</b> (9Y4468)..... <b>B7577</b> <b>Fuel/Water Separator Spin-on</b> (23516189)..... <b>BF5812</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (23535985)..... <b>BF5813 +</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (23535985).. <b>BF5813-O +</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b> <b>S. Fuel</b> (23530645)..... <b>BF5815</b> <b>S. Fuel</b> (23533726)..... <b>BF5816</b>	Micro Bird w/GMC 4.8L Gas Eng. <b>Dual-Flow Lube</b> (97148270)..... <b>BD7169</b> <b>Fuel</b> (25012015)..... <b>BF719</b> <b>Radial Seal Air</b> (ACDelco A2032C)..... <b>RS4859</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
Commercial Bus w/Detroit Diesel 8V-92 (12.1L) Eng. <b>Lube Ele.</b> (5573013)..... <b>P20-HD</b> <b>Lube Spin-on</b> (23530407)..... <b>B95 +</b> <b>Lube Spin-on</b> (23530408)..... <b>B95-MPG +</b> <b>P. Fuel Ele.</b> (9717391)..... <b>PF845</b> <b>P. Fuel Spin-on</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel Ele.</b> (5574508)..... <b>PF902</b> <b>S. Fuel Spin-on</b> (23530707)..... <b>BF5810</b> <b>S. Fuel Spin-on</b> (23530645)..... <b>BF5815</b>	Express 4000, Express 4500 w/Cat Eng. <b>Lube</b> (1R1808)..... <b>B7299 +</b> <b>Fuel</b> (1R0749)..... <b>BF7587 +</b> <b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b> <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Micro Bird w/GMC 6.0L Gas Eng. <b>Lube</b> (2003-06) (88984215)..... <b>B31</b> <b>Lube</b> (2007-on) (ACDelco PF48).. <b>B160</b> <b>Fuel</b> (Thd. Both Ends. 2003-05) (ACDelco GF481)..... <b>BF853</b> <b>Fuel</b> (Thd. One End. 2003-05) (ACDelco GF578)..... <b>BF1171</b> <b>Fuel</b> (2006-on) (N/S)..... <b>N/S</b> <b>Radial Seal Air</b> (ACDelco A2032C)..... <b>RS4859</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
	Express 4000, Express 4500 w/Detroit Series 60 Eng. <b>Lube</b> (1993-on) (23530573)..... [2] <b>B495</b> <b>P. Fuel</b> (25014274)..... <b>BF5800 +</b> <b>S. Fuel</b> (25014342)..... <b>BF5810</b> <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

BLUE BIRD Buses (cont'd)	BLUE BIRD Buses (cont'd)	BLUE BIRD Buses (cont'd)
Micro Bird w/GMC 6.6L Turbo Diesel Eng. <b>Lube</b> (ACDelco PF2232)..... <b>B1441</b> <b>Fuel/Water Separator</b> (Upgrade) (ACDelco TP3018)..... <b>BF46062</b> <sup>89</sup> <b>Radial Seal Air</b> (ACDelco A2032C)..... <b>RS4859</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	SHL Commercial w/Cummins ISC 8.3 (8.3L) Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309</b> + <b>Dual-Flow Lube</b> (Fleetguard LF9548)..... <b>BD324</b> + <b>Fuel/Water Separator Spin-on</b> (3800394)..... <b>BF1272-SPS</b> <b>Fuel/Water Separator Spin-on</b> (3942533)..... <b>BF1271</b> <b>Fuel/Water Separator Spin-on</b> (4934879)..... <b>BF1378-SPS</b> <b>Fuel/Water Separator Spin-on</b> (3406889)..... <b>BF1293-SPS</b> <b>Fuel</b> (Fleetguard FF5488)..... <b>BF7815</b> <b>Fuel</b> (Fleetguard FF5636)..... <b>BF7924</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b> <b>Coolant</b> (w/23 Units BTA+) (Fleetguard WF2076)..... <b>BW5076</b> <b>Coolant</b> (w/Controlled Release) (Fleetguard WF2121)..... <b>BW5250</b>	TC2000 w/Cat 3208 (10.4L) Eng. (Cont'd) <b>Box-Style Fuel/Water Separator</b> (8N9803)..... <b>BF912</b> <b>P. Fuel Ele.</b> (9M2341)..... <b>PF935</b> <b>P. Fuel Spin-on</b> (1R0740)..... <b>BF970</b> + <b>S. Fuel Spin-on</b> (1R0750)..... <b>BF7633</b> + <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2</b> + TC 2000 w/Cummins ISB Eng. <b>Lube</b> (3942365)..... <b>B7177</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19579)..... <b>PF7777</b> <b>Fuel/Water Separator Spin-on</b> (4309159)..... <b>BF1252</b> <b>Fuel/Water Separator Spin-on</b> (3800394)..... <b>BF1272-SPS</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b> <b>Fuel</b> (Fleetguard FF5632)..... <b>BF7940</b> <b>Air</b> (4298501)..... <b>PA3474</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992</b> + <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739</b> + <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b>
SHL All American w/Cummins B6.7 (6.7L) Eng. (2020) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b> <b>Coolant</b> (64641)..... <b>B5134</b>	SHL All American w/Cummins B6.7 (6.7L) Eng. (2021) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	TC 2000 w/Cummins 6BT5.9 Diesel Eng. <b>Lube</b> (3908615)..... <b>BT339</b> + <b>Fuel/Water Separator</b> (3903202). <b>BF1226</b> <b>Fuel/Water Separator</b> (3925274). <b>BF1280</b> + <b>Fuel</b> (3903640)..... <b>BF788</b> <b>Air</b> (4298501)..... <b>PA3474</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992</b> + <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739</b> + <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b>
SHL All American w/Cummins B6.7 (6.7L) Eng. (2022) <b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b>	TC 1000 w/Cummins 6BT5.9 (5.9L) Eng. <b>Lube</b> (Fleetguard LF3972)..... <b>BT7349</b> <b>Fuel/Water Separator</b> (Fleetguard FS1251)..... <b>BF1226</b> <b>Fuel/Water Separator</b> (Fleetguard FS1280)..... <b>BF1280</b> + <b>Fuel</b> (Fleetguard FF5052)..... <b>BF788</b>	TC 2000 w/Cummins 6BT5.9 Diesel Eng. <b>Lube</b> (3908615)..... <b>BT339</b> + <b>Fuel/Water Separator</b> (3903202). <b>BF1226</b> <b>Fuel/Water Separator</b> (3925274). <b>BF1280</b> + <b>Fuel</b> (3903640)..... <b>BF788</b> <b>Air</b> (4298501)..... <b>PA3474</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992</b> + <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739</b> + <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b>
SHL Commercial w/Cat C7 (7.2L) Eng. <b>F-F Lube</b> (1R1808)..... <b>B7299</b> + <b>F-F Lube</b> (1R1807)..... <b>B7700</b> + <b>Fuel/Water Separator</b> (2568753). <b>BF1259</b> <b>Fuel/Water Separator</b> (1752949). <b>BF1268</b> <b>Fuel</b> (1R0751)..... <b>BF7632</b>	TC 2000 w/Cat 3116 Eng. <b>Lube</b> (Standard Vers.) (1R0739).. <b>B76</b> <b>Fuel/Water Separator</b> (6N7617).. <b>BF912</b> <b>Fuel</b> (1R0750)..... <b>BF7633</b> + <b>Air</b> (4298501)..... <b>PA3474</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992</b> + <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739</b> + <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b>	TC 2000 w/Cummins M11 (10.8L) Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103</b> + <b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> (2568753)..... <b>BF1259</b>
SHL Commercial w/Cummins 6BT5.9 (5.9L) Eng. <b>Lube</b> (Fleetguard LF3972)..... <b>BT7349</b> <b>Fuel/Water Separator</b> (Fleetguard FS1251)..... <b>BF1226</b> <b>Fuel/Water Separator</b> (Fleetguard FS1280)..... <b>BF1280</b> + <b>Fuel</b> (Fleetguard FF5052)..... <b>BF788</b>	TC 2000 w/Cat 3126 (7.2L) Eng. <b>Lube</b> (Standard Vers.) (1R0739).. <b>B76</b> + <b>Lube</b> (Severe Service) (1R0739).. <b>B76-SS</b> + <b>Fuel/Water Separator</b> (1752949). <b>BF1268</b> <b>Fuel/Water Separator</b> (2568753). <b>BF1259</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (1986378)..... <b>BF7798-SP</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (1986378)..... <b>BF7798-O</b> <b>Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (1R0751)..... <b>BF7632</b>	Transit w/Cummins ISB Eng. <b>F-F Lube</b> (3937736)..... <b>B7177</b> <b>Dual-Flow Lube</b> (3401544)..... <b>BD7309</b> + <b>Lube</b> (Upgrade) (3401544)..... <b>B40142</b> + <b>Fuel/Water Separator</b> (4070801). <b>BF1293-SPS</b> <b>Fuel/Water Separator</b> (4934879). <b>BF1378-SPS</b> <b>Fuel</b> (M20 x 1.5 Thd.) (4934845).. <b>BF7940</b> <b>Fuel</b> (7/8-14 Thd.) (4940647)..... <b>BF7924</b>
SHL Commercial w/Cummins ISB (5.9L) Eng. <b>Lube</b> (3937736)..... <b>B7177</b> <b>Lube</b> (4897898)..... <b>BT7237</b> <b>Fuel/Water Separator Ele.</b> (3942470)..... <b>PF7777</b> <b>Fuel/Water Separator Spin-on</b> (3942533)..... <b>BF1271</b> <b>Fuel/Water Separator Spin-on</b> (3406889)..... <b>BF1293-SPS</b> <b>Fuel/Water Separator Spin-on</b> (4934879)..... <b>BF1378-SPS</b> <b>Fuel</b> (Fleetguard FF5632)..... <b>BF7940</b>	TC2000 w/Cat 3208 (10.4L) Eng. <b>Lube</b> (1R0713)..... <b>[2] BT230</b> + <b>Lube</b> (1R0714)..... <b>[2] B75</b> <b>Lube</b> (9L9200)..... <b>[2] BT364</b>	Ultra LF w/Cummins ISB Eng. <b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19579)..... <b>PF7777</b>

+ See Product Guide for Variations of This Number. <sup>89</sup> Inner Fender Liner Removal Recommended for Proper Installation.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



BLUE BIRD Buses (cont'd)	BLUE BIRD Buses (cont'd)	BLUE BIRD Buses (cont'd)
Vision w/Cat C7 Eng. (To 1/2004)	Vision w/Cat C7 Eng. (1/2004-on) (Cont'd)	Vision w/Cummins ISB (5.9L) Eng. (Cont'd)
<b>Lube</b> (Standard Vers.) (1R0739).. <b>B76 +</b>	<b>Fuel/Water Separator</b> (Racor R90T)..... <b>BF1390-O</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>
<b>Lube</b> (1R1808)..... <b>B7299 +</b>	<b>Fuel/Water Separator</b> (w/SP) (Racor R90S)..... <b>BF1360-SP</b>	<b>Crankcase Breather</b> (Fleetguard CV52001)..... <b>CV15010</b>
<b>Lube</b> (Severe Service) (1R0739).. <b>B76-SS +</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R90P)..... <b>BF46083-O</b>	<b>Coolant</b> (64641)..... <b>B5134 +</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R90P)..... <b>BF46083-O</b>	<b>Fuel/Water Separator</b> (w/Bowl) (Racor R90P)..... <b>BF46072</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Fuel/Water Separator</b> (w/Bowl) (Racor R90P)..... <b>BF46072</b>	<b>Fuel/Water Separator</b> (w/Drain) (Racor R90P)..... <b>BF1329</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Fuel/Water Separator</b> (Sensor Port Thd. 9/16-18) (Racor R90P).. <b>BF1329-SP</b>	<b>Fuel/Water Separator</b> (Sensor Port Thd. 1/2-20) (Racor R90P).... <b>BF1339-SP +</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Fuel/Water Separator</b> (Racor R90T)..... <b>BF1390-O</b>	<b>Fuel/Water Separator</b> (Racor R90S)..... <b>BF1360-SP</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
<b>Fuel/Water Separator</b> (w/SP) (Racor R90S)..... <b>BF1360-SP</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R90S)..... <b>BF1360-O</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R90S)..... <b>BF1360-O</b>	<b>Fuel</b> (1R0751)..... <b>BF7632</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Fuel</b> (1R0751)..... <b>BF7632</b>	<b>Fuel</b> (1R0759)..... <b>BF7634</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Fuel</b> (1R0759)..... <b>BF7634</b>	<b>Radial Seal Air</b> (To Chassis S/N F20200679) (61519)..... <b>RS5424</b>	Vision w/Cummins ISB 6.7 (6.7L) Eng. (2008-2016)
<b>Radial Seal Air</b> (To Chassis S/N F20200679) (61519)..... <b>RS5424</b>	<b>Radial Seal Air</b> (From Chassis S/N F20200680) (87782)..... <b>RS5458</b>	<b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b>
<b>Radial Seal Air</b> (From Chassis S/N F20200680) (87782)..... <b>RS5458</b>	<b>Cab Air</b> (90,000 BTU)..... <b>CLN&amp;R</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R90P)..... <b>BF46083-O</b>
<b>Cab Air</b> (90,000 BTU)..... <b>CLN&amp;R</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Fuel/Water Separator</b> (w/Bowl) (Racor R90P)..... <b>BF46072</b>
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Fuel/Water Separator</b> (w/Drain) (Racor R90P)..... <b>BF1329</b>
<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Coolant</b> (9Y4528)..... <b>B5134 +</b>	<b>Fuel/Water Separator</b> (Sensor Port Thd. 9/16-18) (Racor R90P).. <b>BF1329-SP</b>
<b>Coolant</b> (9Y4528)..... <b>B5134 +</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Fuel/Water Separator</b> (Sensor Port Thd. 1/2-20) (Racor R90P).... <b>BF1339-SP +</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Fuel/Water Separator</b> (Racor R90T)..... <b>BF1390-O</b>
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Fuel/Water Separator</b> (w/SP) (Racor R90S)..... <b>BF1360-SP</b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R90S)..... <b>BF1360-O</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Fuel</b> (Fleetguard FF5632)..... <b>BF7940</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Radial Seal Air</b> (61519)..... <b>RS5424</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Vision w/Cummins ISB (5.9L) Eng.	<b>Radial Seal Air</b> (87782)..... <b>RS5458</b>
Vision w/Cat C7 Eng. (1/2004-on)	<b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b>	<b>Cab Air</b> (90,000 BTU)..... <b>CLN&amp;R</b>
<b>Lube</b> (1R1807)..... <b>B7700 +</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R90P)..... <b>BF46083-O</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
<b>Lube</b> (1R1808)..... <b>B7299 +</b>	<b>Fuel/Water Separator</b> (w/Bowl) (Racor R90P)..... <b>BF46072</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R90P)..... <b>BF46083-O</b>	<b>Fuel/Water Separator</b> (w/Drain) (Racor R90P)..... <b>BF1329</b>	<b>Air Dryer</b> (AD-SP System) (Bendix 5008414)..... <b>BA5374 +</b>
<b>Fuel/Water Separator</b> (w/Bowl) (Racor R90P)..... <b>BF46072</b>	<b>Fuel/Water Separator</b> (Sensor Port Thd. 9/16-18) (Racor R90P).. <b>BF1329-SP</b>	<b>Crankcase Breather</b> (Fleetguard CV52001)..... <b>CV15010</b>
<b>Fuel/Water Separator</b> (w/Drain) (Racor R90P)..... <b>BF1329</b>	<b>Fuel/Water Separator</b> (Sensor Port Thd. 1/2-20) (Racor R90P).... <b>BF1339-SP +</b>	<b>Coolant</b> (64641)..... <b>B5134 +</b>
<b>Fuel/Water Separator</b> (Sensor Port Thd. 9/16-18) (Racor R90P).. <b>BF1329-SP</b>	<b>Fuel/Water Separator</b> (Racor R90T)..... <b>BF1390-O</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Fuel/Water Separator</b> (Sensor Port Thd. 1/2-20) (Racor R90P).... <b>BF1339-SP +</b>	<b>Fuel/Water Separator</b> (w/SP) (Racor R90S)..... <b>BF1360-SP</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R90S)..... <b>BF1360-O</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R90S)..... <b>BF1360-O</b>	
<b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b>	
<b>Fuel</b> (Fleetguard FF5632)..... <b>BF7940</b>	<b>Fuel</b> (Fleetguard FF5632)..... <b>BF7940</b>	
<b>Radial Seal Air</b> (61519)..... <b>RS5424</b>	<b>Radial Seal Air</b> (61519)..... <b>RS5424</b>	
<b>Radial Seal Air</b> (87782)..... <b>RS5458</b>	<b>Radial Seal Air</b> (87782)..... <b>RS5458</b>	
<b>Cab Air</b> (90,000 BTU)..... <b>CLN&amp;R</b>	<b>Cab Air</b> (90,000 BTU)..... <b>CLN&amp;R</b>	
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>BLUE BIRD Buses (cont'd)</b>	<b>BLUE BIRD Buses (cont'd)</b>	<b>BLUE BIRD Buses (cont'd)</b>
Vision w/Cummins ISB 6.7 (6.7L) Eng. (2008-2016) (Cont'd)	Vision w/GMC 8.1L Propane Eng. (Cont'd)	Vision School Bus w/Cat 3126 (7.2L) Eng. (Cont'd)
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Cab Air</b> (90,000 BTU)..... <b>CLN&amp;R</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	Vision School Bus w/Cummins B6.7 (6.7L) Eng. (2018)
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Lube</b> (3937736)..... <b>B7177</b>
Vision w/Cummins ISC Eng. Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309 +</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Fuel/Water Separator</b> (1966993)..... <b>BF1390-O</b>
<b>Fuel/Water Separator</b> (w/SP) (Racor R90S)..... <b>BF1360-SP</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Fuel/Water Separator</b> (R34000BB01)..... <b>BF46169-O</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R90S)..... <b>BF1360-O</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Fuel/Water Separator</b> (Fleetguard FS20081)..... <b>PF46171</b>
<b>Fuel/Water Separator</b> (Racor R90T)..... <b>BF1390-O</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Fuel</b> (Fleetguard FF63054NN)..... <b>BF63000</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R90P)..... <b>BF46083-O</b>	Vision School Bus w/Cat 3126 (7.2L) Eng.	<b>Radial Seal Air</b> (87782)..... <b>RS5458</b>
<b>Fuel/Water Separator</b> (w/Bowl) (Racor R90P)..... <b>BF46072</b>	<b>Lube</b> (To 1/2004 (Std. Version)) (1R0739)..... <b>B76 +</b>	<b>Cab Air</b> (CLN&R)..... <b>CLN&amp;R</b>
<b>Fuel/Water Separator</b> (w/Drain) (Racor R90P)..... <b>BF1329</b>	<b>Lube</b> (1/2004-on) (1R1807)..... <b>B7700 +</b>	<b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b>
<b>Fuel/Water Separator</b> (Sensor Port Thd. 9/16-18) (Racor R90P)..... <b>BF1329-SP</b>	<b>Lube</b> (To 1/2004 (Severe Service)) (1R0739)..... <b>B76-SS +</b>	<b>Opt. Coolant</b> (64641)..... <b>B5134</b>
<b>Fuel/Water Separator</b> (Sensor Port Thd. 1/2-20) (Racor R90P)..... <b>BF1339-SP +</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R90P)..... <b>BF46083-O</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Fuel</b> (Fleetguard FF5488)..... <b>BF7815</b>	<b>Fuel/Water Separator</b> (w/Bowl) (Racor R90P)..... <b>BF46072</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Radial Seal Air</b> (61519)..... <b>RS5424</b>	<b>Fuel/Water Separator</b> (w/Drain) (Racor R90P)..... <b>BF1329</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Radial Seal Air</b> (87782)..... <b>RS5458</b>	<b>Fuel/Water Separator</b> (Sensor Port Thd. 9/16-18) (Racor R90P)..... <b>BF1329-SP</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>Cab Air</b> (90,000 BTU)..... <b>CLN&amp;R</b>	<b>Fuel/Water Separator</b> (Sensor Port Thd. 1/2-20) (Racor R90P)..... <b>BF1339-SP +</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Fuel/Water Separator</b> (Racor R90T)..... <b>BF1390-O</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Coolant</b> (w/o Chemical) (64641)..... <b>B5134 +</b>	<b>Fuel/Water Separator</b> (w/SP) (Racor R90S)..... <b>BF1360-SP</b>	<b>Crankcase Breather</b> (4936636)..... <b>CV15010</b>
<b>Coolant</b> (w/2 Units BTA +) (Fleetguard WF2070)..... <b>BW5070</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R90S)..... <b>BF1360-O</b>	Vision School Bus w/Cummins B6.7 (6.7L) Eng. (2019)
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Fuel</b> (1R0751)..... <b>BF7632</b>	<b>Lube</b> (3937736)..... <b>B7177</b>
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Radial Seal Air</b> (61519)..... <b>RS5424</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS20081)..... <b>PF46171</b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Cab Air</b> (90,000 BTU)..... <b>CLN&amp;R</b>	<b>Fuel/Water Separator Spin-on</b> (1966993)..... <b>BF1390-O</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Fuel/Water Separator Spin-on</b> (R34000BB01)..... <b>BF46169-O</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Fuel</b> (5660774)..... <b>BF63000</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Coolant</b> (w/o Chemical) (9Y4528)..... <b>B5134 +</b>	<b>Radial Seal Air</b> (87782)..... <b>RS5458</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107794)..... <b>BA5377</b>
Vision w/GMC 8.1L Propane Eng.	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Coolant</b> (64641)..... <b>B5134</b>
<b>Lube Ele.</b> ..... <b>P7233</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Lube Spin-on</b> ..... <b>BT486</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Radial Seal Air</b> (61519)..... <b>RS5424</b>		<b>Crankcase Breather</b> (4936636)..... <b>CV15010</b>
<b>Radial Seal Air</b> (87782)..... <b>RS5458</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>BLUE BIRD Buses (cont'd)</b>	<b>BLUE BIRD Buses (cont'd)</b>	<b>BLUE BIRD Buses (cont'd)</b>
Vision School Bus w/Cummins B6.7 (6.7L) Eng. (2020)	Vision School Bus w/Cummins ISB 6.7 (6.7L) Eng. (2017) (Cont'd)	Vision School Bus w/Cummins ISV5.0 (5.0L) Eng. (2018) (Cont'd)
<b>Lube</b> (3937736)..... <b>B7177</b>	<b>Trans.</b> (4 In. Kit) (Allison 29558329)..... <b>PT9415-MPG KIT</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
<b>Fuel/Water Separator</b> (1966993). <b>BF1390-O</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>Fuel/Water Separator</b> (R34000BB01)..... <b>BF46169-O</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	Vision School Bus w/Cummins ISV5.0 (5.0L) Eng. (2019)
<b>Fuel</b> (5660774)..... <b>BF63000</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107794)..... <b>BA5377</b>
<b>Radial Seal Air</b> (87782)..... <b>RS5458</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	Vision School Bus w/Cummins ISV5.0 (5.0L) Eng. (2020)
<b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Fuel/Water Separator</b> (R34000BB01)..... <b>BF46169-O</b>
<b>Coolant</b> (64641)..... <b>B5134 +</b>	<b>Diesel Exhaust Fluid</b> (Fleetguard UF106)..... <b>PE17002 KIT</b>	<b>Trans. Spin-on</b> (33381)..... <b>BT8460</b>
<b>Trans. Spin-on</b> (33381)..... <b>BT8460</b>	Vision School Bus w/Cummins ISB 6.7 (6.7L) Eng. (2018)	Vision School Bus w/Ford V10-415 (6.8L) Eng. (2017)
Vision School Bus w/Cummins B6.7 (6.7L) Eng. (2021)	<b>Lube</b> (3937736)..... <b>B7177</b>	<b>Lube</b> (F1AZ6731BE)..... <b>B329</b>
<b>Lube</b> (3937736)..... <b>B7177</b>	<b>Fuel/Water Separator</b> (1966993). <b>BF1390-O</b>	<b>Cab Air</b> (CLN&R)..... <b>CLN&amp;R</b>
<b>Fuel</b> (5303743)..... <b>BF63000</b>	<b>Fuel/Water Separator</b> (R34000BB01)..... <b>BF46169-O</b>	<b>Trans.</b> (BC3P7G186BE)..... <b>20028</b>
<b>Air Dryer</b> (AD-9 System) (Bendix 107794)..... <b>BA5377</b>	<b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b>	Vision School Bus w/Ford V10-415 (6.8L) Eng. (2018)
<b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	<b>Radial Seal Air</b> (87782)..... <b>RS5458</b>	<b>Lube</b> (F1AZ6731A)..... <b>B329</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Cab Air</b> (CLN&R)..... <b>CLN&amp;R</b>	<b>Fuel</b> (F89Z9155A)..... <b>BF7668</b>
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b>	<b>Air</b> (F50Y9601A)..... <b>PA4075</b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	<b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Opt. Coolant</b> (64641)..... <b>B5134</b>	<b>Trans.</b> (4R75W) (F6AZ7A098A)... <b>18029</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Trans.</b> (5R100W) (8C3Z7A098D). <b>20021</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Trans.</b> (BC3P7G186BE)..... <b>20028</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	Vision School Bus w/Ford V10-415 (6.8L) Eng. (2019)
Vision School Bus w/Cummins B6.7 (6.7L) Eng. (2022)	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Lube</b> (F1AZ6731BE)..... <b>B329</b>
<b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Fuel</b> (N/S)..... <b>N/S</b>
Vision School Bus w/Cummins B6.7 (6.7L) Eng. (2023)	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Primary Air</b> (F50X9601BA)..... <b>PA4075</b>
<b>Lube</b> (3937736)..... <b>B7177</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Cab Air</b> (CLN&R)..... <b>CLN&amp;R</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	Vision School Bus w/Cummins ISV5.0 (5.0L) Eng. (2018)	<b>Trans.</b> (BC3P7G186BE)..... <b>20028</b>
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Lube</b> (4378318)..... <b>B7420</b>	Vision School Bus w/Ford V10-415 (6.8L) Eng. (2020)
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Lube</b> (4378319)..... <b>BT7349</b>	<b>Lube</b> (F1AZ6731BE)..... <b>B329</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Fuel/Water Separator</b> (1966993). <b>BF1390-O</b>	<b>Fuel</b> (N/S)..... <b>N/S</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Primary Air</b> (F50X9601BA)..... <b>PA4075</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Secondary Air</b> (CLN&R)..... <b>CLN&amp;R</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Air Dryer</b> (AD-SP System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Cab Air</b> (CLN&R)..... <b>CLN&amp;R</b>
Vision School Bus w/Cummins ISB 6.7 (6.7L) Eng. (2017)	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Trans.</b> (BC3P7G186BE)..... <b>20028</b>
<b>Lube</b> (3937736)..... <b>B7177</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	Vision School Bus w/Ford V10-415 (6.8L) Eng. (2021)
<b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107794)..... <b>BA5377</b>
<b>Radial Seal Air</b> (87782)..... <b>RS5458</b>		<b>Trans.</b> (BC3P7G186BE)..... <b>20028</b>
<b>Crankcase Breather</b> (Fleetguard CV52001)..... <b>CV15010</b>		Vision School Bus w/General Motors V8-496 (8.1L) Eng. (2018)
<b>Trans.</b> (2 In. Kit) (Allison 29558328)..... <b>PT9416-MPG KIT</b>		<b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

BLUE BIRD Buses (cont'd)	BLUE BIRD Buses (cont'd)	BLUE BIRD Buses (cont'd)
Wanderlodge w/Cat 3116 (6.6L) Eng. <b>Lube</b> (Standard Vers.) (1R0739).. <b>B76 +</b> <b>Lube</b> (Severe Service) (1R0739).. <b>B76-SS +</b> <b>Fuel/Water Separator Box-Style</b> (8N9803)..... <b>BF912</b> <b>Fuel/Water Coalescer Ele. w/Drain</b> (1174089)..... <b>BF7679-D</b> <b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (1466695)..... <b>BF1350-SP</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (1466695).... <b>BF46030-O</b> <b>Fuel</b> (1R0751)..... <b>BF7632</b> <b>Fuel</b> (1R0740)..... <b>BF970 +</b> <b>Fuel</b> (1R0750)..... <b>BF7633 +</b> <b>Air Compressor Breather</b> (9L2169)..... <b>PA1704</b>	Wanderlodge w/Cummins ISL Eng. (Cont'd) <b>10 1/32 In. Fuel/Water Separator</b> (Fleetguard FS1022)..... <b>BF1293-SPS</b> <b>Fuel</b> (Fleetguard FF5488)..... <b>BF7815</b> <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Wanderlodge w/Detroit Diesel Series 60 (11.1L) or (12.7L) Eng. (Cont'd) <b>Fuel/Water Separator Spin-on</b> (w/Bowl) (1967009)..... <b>BF46072</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (1967009)..... <b>BF1329</b> <b>Fuel/Water Separator Spin-on</b> (w/Sensor Port Thd. 9/16-18) (1967009)..... <b>BF1329-SP</b> <b>Fuel/Water Separator Spin-on</b> (w/Sensor Port Thd. 1/2-20) (1967009)..... <b>BF1339-SP +</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b> <b>Air</b> (Disposable Hsg.) (Farr 99842007)..... <b>PA30322</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (6082416)..... <b>BW5137</b> <b>Trans. Ele. (2 In. Kit)</b> (Allison 29545776)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele. (4 In. Kit)</b> (Allison 29548988)..... <b>PT9415-MPG KIT</b>
Wanderlodge w/Cat 3208 (10.4L) Eng. <b>Lube</b> (9N6007)..... <b>B75</b> <b>Lube</b> (Generator) (Kubota 1524132092)..... <b>B179</b> <b>Fuel/Water Separator Ele.</b> (Racor 2040SM)..... <b>PF7889</b> <b>Fuel</b> (2236677)..... <b>BF970 +</b> <b>Conical-Shaped Air</b> (Don. P129396)..... <b>PA3951</b>	Wanderlodge w/Cummins M11 (10.8L) Eng. <b>Dual-Flow Lube</b> (9424)..... <b>BD7309 +</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> (2568753)..... <b>BF1259</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Trans. Ele. (2 In. Kit)</b> (Allison 29545776)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele. (4 In. Kit)</b> (Allison 29548988)..... <b>PT9415-MPG KIT</b>	XCEL102 w/Cummins ISC Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel/Water Separator</b> (3800394)..... <b>BF1272-SPS</b> <b>Fuel</b> (3959612)..... <b>BF7815</b> <b>Air</b> (1967744)..... <b>PA3987</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
Wanderlodge w/Cat C13 (12.5L) Eng. <b>Lube</b> (1R1808)..... <b>B7299 +</b> <b>Lube</b> (2492347)..... <b>[2] B7402</b> <b>Fuel/Water Separator</b> (3329289)..... <b>BF1259</b> <b>Fuel</b> (Standard Vers.) (4N5823).... <b>BF614 +</b> <b>Fuel</b> (High Efficiency Vers.) (1R0749)..... <b>BF7587 +</b>	Wanderlodge w/Detroit Diesel 8V-92 (12.1L) Eng. <b>Lube Spin-on</b> (3734209)..... <b>B95 +</b> <b>Fuel/Water Separator</b> (3831310)..... <b>PF7890</b> <b>P. Fuel Ele.</b> (9717391)..... <b>PF845</b> <b>P. Fuel Spin-on</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel Spin-on</b> (23530707)..... <b>BF5810</b> <b>Conical-Shaped Air</b> (Don. P129396)..... <b>PA3951</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Trans. Ele. (2 In. Kit)</b> (Allison 29545776)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele. (4 In. Kit)</b> (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Trans.</b> (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b> <b>Steering</b> (2138246)..... <b>PT9344</b> <b>Hyd.</b> (2122026)..... <b>PT8498</b>	
Wanderlodge w/Cummins 6CT8.3 (8.3L) Eng. <b>F-F Lube</b> (3313281)..... <b>B205 +</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Fuel/Water Separator</b> (3925274)..... <b>BF1280 +</b> <b>Fuel/Water Separator</b> (Fleetguard FS1251)..... <b>BF1226</b> <b>Fuel</b> (3903640)..... <b>BF788</b> <b>Trans. Ele. (2 In. Kit)</b> (Allison 29545776)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele. (4 In. Kit)</b> (Allison 29548988)..... <b>PT9415-MPG KIT</b>	Wanderlodge w/Detroit Diesel Series 50 (8.5L) Eng. <b>Lube</b> (23530573)..... <b>[2] B495</b> <b>Fuel/Water Separator Spin-on</b> (23516189)..... <b>BF5812</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (23535985)..... <b>BF5813 +</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (23535985).. <b>BF5813-O +</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b>	<b>BROCKWAY Trucks &amp; Buses</b> Models w/Bendix-Westinghouse 400, 500 Air Compressors <b>Air Breather</b> ..... <b>PA1704</b>
Wanderlodge w/Cummins ISL Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel/Water Separator</b> (w/Drain) (Fleetguard FS1242)..... <b>BF1249</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (Fleetguard FS1242)..... <b>BF1249-O</b> <b>Fuel/Water Separator</b> (w/Drain & Sensor Port) (Fleetguard FS1242) <b>BF1249-SP</b> <b>Fuel/Water Separator</b> (w/Drain & Sensor Port, High Efficiency Version) (Fleetguard FS1242)..... <b>BF1393-SP</b> <b>9 15/32 In. Fuel/Water Separator</b> (Fleetguard FS1022)..... <b>BF1272-SPS</b>	Wanderlodge w/Detroit Diesel Series 60 (11.1L) or (12.7L) Eng. <b>F-F Lube</b> (23530573)..... <b>[2] B495</b> <b>F-F Lube</b> (Don. DELF3998)..... <b>[2] B495-SS</b> <b>Fuel/Water Separator Ele.</b> (Racor 2020SMOR)..... <b>PF7890</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (1967009).... <b>BF46083-O</b>	Models w/Brockway Air Filter <b>Air</b> (534564)..... <b>PA2317 +</b> Most Models w/Cummins Eng. <b>F-F Lube Bag</b> ..... <b>P996</b> <b>F-F Lube Ele.</b> ..... <b>P999-HD</b> <b>F-F Lube Spin-on</b> ..... <b>B196 +</b> <b>B-P Lube Ele.</b> ..... <b>C750-E +</b> <b>Fuel/Water Separator</b> ..... <b>BF1212 +</b> <b>4 3/8 In. Fuel Spin-on</b> ..... <b>BF948 +</b> <b>5 3/4 In. Fuel Spin-on</b> ..... <b>BF957 +</b> <b>11 7/32 In. Fuel Spin-on</b> ..... <b>BF596 +</b> <b>Breather Ele.</b> (w/Turbo) (255963) <b>PA643</b> <b>Breather Ele.</b> (w/o Turbo) (256837)..... <b>PA1627</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>BROCKWAY</b> Trucks & Buses (cont'd)	<b>BROWN</b> Trucks (cont'd)	<b>CAPACITY OF TEXAS</b> Trucks (cont'd)
Most Models w/Cummins Eng. (Cont'd) <b>Turbocharger</b> ..... BT112	Models w/Cummins Eng. (Cont'd) <b>Turbocharger</b> ..... BT112	TJ5000 w/Cummins ISB 6.7 (6.7L) Eng. (2018) <b>Lube</b> (3937736)..... B7177 <b>Fuel</b> (Fleetguard FF63009)..... BF63000 <b>Air Dryer</b> (Bendix 65624)..... BA5373 <b>Crankcase Breather</b> (4936636)... CV15010 <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... B233
Models w/Fram Filter Hsg. <b>Air</b> (FA230PL)..... PA617 <b>Heavy Duty Air</b> (FA230PLHD).... PA1700 <sup>90</sup> <b>Air</b> (FA240PL)..... PA616	<b>CAN-CAR</b> <b>Trucks</b> Models w/Leyland Diesel 600, 680 Eng. <b>Fuel Ele.</b> (1957-59)..... PF838	TJ5000 w/Cummins ISB 6.7 (6.7L) Eng. (2019) <b>Lube</b> (3937736)..... B7177 <b>Fuel</b> (5303743)..... BF63000 <b>Radial Seal O. Air</b> (Fleetguard AF25962)..... RS4992 <b>Radial Seal I. Air</b> (Fleetguard AF25963)..... RS5329 <b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... BA5373 <b>Crankcase Breather</b> (4936636)... CV15010 <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT
Models w/Mack 300 Series Eng. <b>Inter-Cooler Air</b> (57MD21)..... PA2438 <b>Eng. Air</b> (57MD31)..... PA2439	<b>CANADIAN EXTREME CLIMATE</b> <b>SYSTEMS</b> <b>Auxiliary Power Units (APU)</b> Patriot w/Yanmar 2TNV70 Eng. <b>Lube</b> (119305-35151)..... B1400 <b>Fuel</b> (119810-55650)..... PF981 <b>Air</b> ..... CLN&R	TJ5000 w/Cummins ISB 6.7 (6.7L) Eng. (2020) <b>Lube</b> (3937736)..... B7177 <b>Fuel</b> (5303743)..... BF63000 <b>Crankcase Breather</b> (4936636)... CV15010
Models w/PowShift <b>Trans.</b> (1959-on)..... PF906	<b>CAPACITY OF TEXAS</b> <b>Trucks</b> Sabre 5 w/Cummins ISB 6.7 (6.7L) Eng. (2018) <b>Lube</b> (3937736)..... B7177 <b>Fuel</b> (Fleetguard FF63009)..... BF63000 <b>Crankcase Breather</b> (4936636)... CV15010	TJ5000 w/Cummins ISB 6.7 (6.7L) Eng. (2020) <b>Lube</b> (3937736)..... B7177 <b>Fuel</b> (5303743)..... BF63000 <b>Crankcase Breather</b> (4936636)... CV15010
158L, 158LL, 158LQ, 158T w/44BD Eng. <b>Lube</b> ..... P20-HD + <b>Fuel</b> ..... PF827	Sabre 5 w/Cummins ISB 6.7 (6.7L) Eng. (2019) <b>Lube</b> (3937736)..... B7177 <b>Fuel</b> (5303743)..... BF63000 <b>Crankcase Breather</b> (4936636)... CV15010	TJ5000 w/Cummins ISB 6.7 (6.7L) Eng. (2021) <b>Lube</b> (3937736)..... B7177 <b>Fuel</b> (5303743)..... BF63000 <b>Crankcase Breather</b> (4936636)... CV15010
253, 254W, 255T, 258W, 260L, 260LD, 260LF, 260LQ, 260T w/46BD, 48BD Eng. <b>Lube</b> ..... P52	Sabre 5 w/Cummins ISB 6.7 (6.7L) Eng. (2020) <b>Lube</b> (3937736)..... B7177 <b>Fuel</b> (5303743)..... BF63000 <b>Crankcase Breather</b> (4936636)... CV15010	TJ5000 w/Cummins ISB 6.7 (6.7L) Eng. (2021) <b>Lube</b> (3937736)..... B7177 <b>Fuel</b> (5303743)..... BF63000 <b>Crankcase Breather</b> (4936636)... CV15010
360, 361 w/Cat 1674 Eng. <b>Lube</b> ..... PT670 <b>Fuel Spin-on</b> ..... BF970 + <b>Opt. Air Comp. Breather</b> ..... PA1704	Sabre 5 w/Cummins ISB 6.7 (6.7L) Eng. (2021) <b>Lube</b> (3937736)..... B7177 <b>Fuel</b> (5303743)..... BF63000 <b>Crankcase Breather</b> (4936636)... CV15010	TJ5000 w/Cummins ISB 6.7 (6.7L) Eng. (2022) <b>Lube</b> (Fleetguard LF3970)..... B7177
255W, 260WD, 260WLD, 260SF, 260SQ w/48BD Eng. <b>Lube</b> ..... P52	TJ5000 w/Cummins 6CT8.3 Eng. <b>Dual-Flow Lube</b> (3401544)..... BD7309 + <b>Lube</b> (Upgrade) (3401544)..... B40142 + <b>Fuel/Water Separator</b> (3930942)..... BF1280 + <b>Coolant</b> (4058964)..... BW5073	TJ5000 w/Cummins QSB 6.7 (6.7L) Eng. (2011-15) <b>Lube</b> (Fleetguard LF3970)..... B7177 <b>Fuel/Water Separator</b> (3973233)..... BF1385-SPS <b>Fuel/Water Separator</b> (3903410)..... BF1280 + <b>S. Fuel</b> (3903640)..... BF788 <b>Disposable Air Hsg.</b> (Mtd. Through Hood) (Fleetguard AH1197)..... PA3493 <b>Disposable Air Hsg.</b> (Mtd. Under Hood) (Fleetguard AH1193)..... PA3556 <b>Air Dryer</b> (Bendix 107796)..... BA5377 <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT
457 w/Cat 1674 Eng. <b>Lube</b> ..... PT670 <b>Fuel Spin-on</b> ..... BF970 + <b>Opt. Air Comp. Breather</b> ..... PA1704	TJ5000 w/Cummins ISB 6.7 (6.7L) Eng. (2011-15) <b>Lube</b> (Fleetguard LF3970)..... B7177 <b>Fuel/Water Separator</b> (Fleetguard FS1065)..... BF1378-SPS <b>Fuel/Water Separator</b> (3954904)..... BF1293-SPS <b>S. Fuel</b> (Fleetguard FF5632)..... BF7940 <b>Disposable Air Hsg.</b> (Mtd. Through Hood) (Fleetguard AH1197)..... PA3493 <b>Disposable Air Hsg.</b> (Mtd. Under Hood) (Fleetguard AH1193)..... PA3556 <b>Air Dryer</b> (Bendix 107796)..... BA5377 <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	TJ5000 w/Cummins QSB 6.7 (6.7L) Eng. (2019) <b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... BA5373 <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT
550 w/Cat 3306 Eng. <b>Lube Spin-on</b> (Standard Vers.) (1R0739)..... B76 <b>Fuel Spin-on</b> (1R0740)..... BF970 +		
H360 w/Cat 1693T, 1693TA Eng. <b>Lube Ele.</b> ..... [2] PT88-HD <b>Lube Spin-on</b> ..... B99 + <b>Fuel Spin-on</b> ..... [2] BF970 + <b>Opt. Air Comp. Breather</b> ..... PA1704		
M146A <b>B-P Lube Sock</b> (1946-52)..... CU406 <sup>90</sup>		
<b>BROWN</b> <b>Trucks</b>		
Models w/Buda Eng. <b>Lube</b> (1956-on)..... P20-HD + <b>Fuel</b> (1956-on)..... PF810		
Models w/Cummins Eng. <b>F-F Lube Bag</b> ..... P996 <b>F-F Lube Ele.</b> ..... P999-HD <b>F-F Lube Spin-on</b> ..... B196 + <b>B-P Lube Ele.</b> ..... C750-E + <b>Fuel/Water Separator</b> ..... BF1212 + <b>4 3/8 In. Fuel Spin-on</b> ..... BF948 + <b>5 3/4 In. Fuel Spin-on</b> ..... BF957 + <b>11 7/32 In. Fuel Spin-on</b> ..... BF596 + <b>Breather Ele.</b> (w/Turbo) (255963) PA643 <b>Breather Ele.</b> (w/o Turbo) (256837)..... PA1627		

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.

Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

CAPACITY OF TEXAS Trucks (cont'd)	CAPACITY OF TEXAS Trucks (cont'd)	CARRIER-TRANSICOLD Air Conditioners (cont'd)
TJ5000, YM5000 w/Cummins 6BT5.9 Eng. Lube (3934430)..... <b>BT339</b> + P. Fuel/Water Separator..... <b>BF1280</b> + Fuel/Water Separator (3991350). <b>BF1356</b> S. Fuel..... <b>BF788</b>	TJ7000 w/Cummins QSB 6.7 (6.7L) Eng. (Cont'd) Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	DM-1 w/Kubota Eng. Air (AC501-330)..... <b>LL1690-FN</b> +
TJ6500 w/Cummins ISB 6.7 (6.7L) Eng. (2011-14) Lube (Fleetguard LF3970)..... <b>B7177</b> Fuel/Water Separator (Fleetguard FS1065)..... <b>BF1378-SPS</b> S. Fuel (Fleetguard FF5632)..... <b>BF7940</b> Air (132647)..... <b>PA3493</b> Air Dryer (Bendix 107796)..... <b>BA5377</b>	TJ9000 w/Cummins ISB 6.7 (6.7L) Eng. (2018) Lube (3937736)..... <b>B7177</b> Fuel (Fleetguard FF63009)..... <b>BF63000</b> Crankcase Breather (4936636).... <b>CV15010</b>	DM-2 w/Cummins Diesel Eng. Air (AC501-330)..... <b>LL1690-FN</b> +
TJ6500 w/Cummins ISB 6.7 (6.7L) Eng. (2018) Lube (3937736)..... <b>B7177</b> Fuel/Water Separator Ele. (Fleetguard FS20081)..... <b>PF46171</b> Fuel (Fleetguard FF63009)..... <b>BF63000</b> Crankcase Breather (4936636).... <b>CV15010</b>	TJ9000 w/Cummins ISB 6.7 (6.7L) Eng. (2019) Lube (3937736)..... <b>B7177</b> Fuel (5303743)..... <b>BF63000</b> Crankcase Breather (4936636).... <b>CV15010</b>	DM-2 w/Kubota Eng. Air (AC501-330)..... <b>LL1690-FN</b> +
TJ6500 w/Cummins ISB 6.7 (6.7L) Eng. (2018) Lube (3937736)..... <b>B7177</b> Fuel/Water Separator Ele. (Fleetguard FS20081)..... <b>PF46171</b> Fuel (Fleetguard FF63009)..... <b>BF63000</b> Crankcase Breather (4936636).... <b>CV15010</b>	TJ9000 w/Cummins ISB 6.7 (6.7L) Eng. (2020) Lube (3937736)..... <b>B7177</b> Fuel (5303743)..... <b>BF63000</b> Crankcase Breather (4936636).... <b>CV15010</b>	GM-1 w/w/Gas Eng. Air (AC501-330)..... <b>LL1690-FN</b> +
TJ6500 w/Cummins ISB 6.7 (6.7L) Eng. (2019) Lube (3937736)..... <b>B7177</b> Fuel (5303743)..... <b>BF63000</b> Crankcase Breather (4936636).... <b>CV15010</b>	TJ9000 w/Cummins ISB 6.7 (6.7L) Eng. (2021) Lube (3937736)..... <b>B7177</b> Fuel (5303743)..... <b>BF63000</b> Crankcase Breather (4936636).... <b>CV15010</b>	<b>CARRIER-TRANSICOLD Auxiliary Power Units (APU)</b>
TJ6500 w/Cummins ISB 6.7 (6.7L) Eng. (2020) Lube (3937736)..... <b>B7177</b> Fuel (5303743)..... <b>BF63000</b> Crankcase Breather (4936636).... <b>CV15010</b>	TJ9000 w/Cummins ISL-G Eng. Dual-Flow Lube (Fleetguard LF3000)..... <b>BD103</b> + Fuel (Fleetguard NG5900)..... <b>BF7695</b> Air (132647)..... <b>PA3493</b> Air Dryer (Bendix 107796)..... <b>BA5377</b>	ComfortPro PC5009 w/Kubota Z482 Eng. Lube (9610123K)..... <b>B7139</b> Fuel (9610124K)..... <b>BF954</b> + Fuel (In-Line) (3018601K)..... <b>BF7725</b> Radial Seal Air (3072410K)..... <b>RS3715</b>
TJ6500 w/Cummins ISB 6.7 (6.7L) Eng. (2021) Lube (3937736)..... <b>B7177</b> Fuel (5303743)..... <b>BF63000</b> Crankcase Breather (4936636).... <b>CV15010</b>	Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	ComfortPro PC6000 w/13.9 HP 2 cyl. Kubota Eng. Lube (9610133K)..... <b>B7139</b> Fuel Spin-on (9610124K)..... <b>BF954</b> + Radial Seal Air (3072411K)..... <b>RS3715</b>
TJ6500, TJ7000 w/Cummins 6BT5.9 Eng. Lube..... <b>BT339</b> + Lube (Fleetguard LF3959)..... <b>BT7349</b> P. Fuel/Water Separator (Fleetguard FS1280)..... <b>BF1280</b> + Fuel/Water Separator (Fleetguard FS1251)..... <b>BF1226</b> S. Fuel (Fleetguard FF5052)..... <b>BF788</b>	TJ9000 w/Cummins QSBT3 6.7L Eng. Lube (Fleetguard LF3970)..... <b>B7177</b> Fuel/Water Separator (3973233). <b>BF1385-SPS</b> Fuel/Water Separator (3903410). <b>BF1280</b> + S. Fuel (3903640)..... <b>BF788</b> Air (132647)..... <b>PA3493</b>	ComfortPro PC6002 w/2 cyl. Kubota Eng Lube (9610133K)..... <b>B7139</b> Fuel Spin-on (9610124K)..... <b>BF954</b> + Radial Seal Air (3072411K)..... <b>RS3715</b>
TJ7000 w/Cummins ISB 6.7 (6.7L) Eng. Lube (3937736)..... <b>B7177</b> Fuel/Water Separator (Fleetguard FS1065)..... <b>BF1378-SPS</b>	Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	ComfortPro PC6003 w/2 cyl. Kubota Eng Lube (9610133K)..... <b>B7139</b> Fuel Spin-on (9610124K)..... <b>BF954</b> + Radial Seal Air (3072411K)..... <b>RS3715</b>
TJ7000 w/Cummins QSB 6.7 (6.7L) Eng. Lube (Fleetguard LF3970)..... <b>B7177</b> Fuel/Water Separator (3973233). <b>BF1385-SPS</b> Fuel/Water Separator (3903410). <b>BF1280</b> + S. Fuel (3903640)..... <b>BF788</b> Air (132647)..... <b>PA3493</b>	TJ9000 w/Cummins QSB 6.7 (6.7L) Eng. (2020) Lube (3937736)..... <b>B7177</b> Fuel (5303743)..... <b>BF63000</b> Primary EnduraPanel Air (Fleetguard AF55014)..... <b>PA31002</b> Secondary EnduraPanel Air (Fleetguard AF55308)..... <b>PA31003</b>	ComfortPro PC6006 w/2 cyl. Kubota Eng Lube (9610133K)..... <b>B7139</b> Fuel Spin-on (9610124K)..... <b>BF954</b> + Radial Seal Air (3072411K)..... <b>RS3715</b>
TJ7000 w/Cummins ISB 6.7 (6.7L) Eng. Lube (3937736)..... <b>B7177</b> Fuel/Water Separator (Fleetguard FS1065)..... <b>BF1378-SPS</b>	Radial Seal O. Air (Fleetguard AF25962)..... <b>RS4992</b> Radial Seal I. Air (Fleetguard AF25963)..... <b>RS5329</b> Crankcase Breather (4936636).... <b>CV15010</b> Diesel Exhaust Fluid (5303604).... <b>PE17000</b>	ComfortPro PC6012 w/Kubota Z482-B Eng Lube (9610133K)..... <b>B7139</b> Fuel Spin-on (9610124K)..... <b>BF954</b> + Radial Seal Air (3072411K)..... <b>RS3715</b>
TJ7000 w/Cummins ISB 6.7 (6.7L) Eng. Lube (3937736)..... <b>B7177</b> Fuel/Water Separator (Fleetguard FS1065)..... <b>BF1378-SPS</b>	CARRIER-TRANSICOLD Air Conditioners DM-1 w/Cummins Diesel Eng. Air (AC501-330)..... <b>LL1690-FN</b> +	ComfortPro PC6013 w/Kubota Z482-B Eng Lube (9610133K)..... <b>B7139</b> Fuel Spin-on (9610124K)..... <b>BF954</b> + Radial Seal Air (3072411K)..... <b>RS3715</b>
TJ7000 w/Cummins QSB 6.7 (6.7L) Eng. Lube (Fleetguard LF3970)..... <b>B7177</b> Fuel/Water Separator (3973233). <b>BF1385-SPS</b> Fuel/Water Separator (3903410). <b>BF1280</b> + S. Fuel (3903640)..... <b>BF788</b> Air (132647)..... <b>PA3493</b> Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>		ComfortPro PC6014 w/Kubota Z482-B Eng Lube (9610133K)..... <b>B7139</b> Fuel Spin-on (9610124K)..... <b>BF954</b> + Radial Seal Air (3072411K)..... <b>RS3715</b>
		ComfortPro PC6015 w/Kubota Z482-B Eng Lube (9610133K)..... <b>B7139</b> Fuel Spin-on (9610124K)..... <b>BF954</b> + Radial Seal Air (3072411K)..... <b>RS3715</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

CARRIER-TRANSICOLD Auxiliary Power Units (APU) (cont'd)	CARRIER-TRANSICOLD Engines (cont'd)	CARRIER-TRANSICOLD Engines (cont'd)
PC6011 w/Kubota Z482-B Eng Lube (9610133K)..... <b>B7139</b> Fuel Spin-on (9610124K)..... <b>BF954 +</b> Radial Seal Air (3072411K)..... <b>RS3715</b>	CT4-113-DI Lube (S/N XA0001-on) (30-00323-00)..... <b>BT217</b>	V1902-IDI F-F Lube (30-00323-00)..... <b>BT217</b> Dual-Flow Lube (If Converted to Ext. Maintenance) (30-00463-00). <b>BD7317</b>
PC6018 w/Kubota Z482-B Eng Lube (9610133K)..... <b>B7139</b> Fuel Spin-on (9610124K)..... <b>BF954 +</b> Radial Seal Air (3072411K)..... <b>RS3715</b>	CT4-114DI F-F Lube (S/N XA0001-on) (30-00323-00)..... <b>BT217</b> Dual-Flow Lube (If Converted to Ext. Maintenance) (30-00463-00). <b>BD7317</b> Fuel (30-00302-00)..... <b>BF970 +</b>	V1903-TV F-F Lube (30-00323-00)..... <b>BT217</b> Dual-Flow Lube (If Converted to Ext. Maintenance) (30-00463-00). <b>BD7317</b>
PC6019 w/Kubota Z482-B Eng Lube (9610133K)..... <b>B7139</b> Fuel Spin-on (9610124K)..... <b>BF954 +</b> Radial Seal Air (3072411K)..... <b>RS3715</b>	CT4-114IDI Lube (30-00304-00)..... <b>B164</b> Lube (S/N XA0001-on) (30-00323-00)..... <b>BT217</b> Fuel (30-00302-00)..... <b>BF970 +</b>	V2202-DI F-F Lube (30-00323-00)..... <b>BT217</b> Dual-Flow Lube (If Converted to Ext. Maintenance) (30-00463-00). <b>BD7317</b>
PC6021 w/Kubota Eng Lube (9610133K)..... <b>B7139</b> Fuel Spin-on (9610124K)..... <b>BF954 +</b> Radial Seal Air (3072411K)..... <b>RS3715</b>	CT4-114-IDI F-F Lube (S/N XA0001-on) (30-00323-00)..... <b>BT217</b> Dual-Flow Lube (If Converted to Ext. Maintenance) (30-00463-00). <b>BD7317</b>	V2203-DI F-F Lube (S/N XA0001-on) (30-00323-00)..... <b>BT217</b> Dual-Flow Lube (S/N 3Y0015-on) (30-00463-00)..... <b>BD7317</b>
PC6022 w/Kubota Eng Lube (9610133K)..... <b>B7139</b> Fuel Spin-on (9610124K)..... <b>BF954 +</b> Radial Seal Air (3072411K)..... <b>RS3715</b>	CT4-114TV Lube (30-00304-00)..... <b>B164</b> Lube (S/N XA0001-on) (30-00323-00)..... <b>BT217</b>	V2203-TV F-F Lube (30-00323-00)..... <b>BT217</b> Dual-Flow Lube (If Converted to Ext. Maintenance) (30-00463-00). <b>BD7317</b>
PC6023 w/Kubota Eng Lube (9610133K)..... <b>B7139</b> Fuel Spin-on (9610124K)..... <b>BF954 +</b> Radial Seal Air (3072411K)..... <b>RS3715</b>	CT4-133-DI F-F Lube (30-00323-00)..... <b>BT217</b> Dual-Flow Lube (If Converted to Ext. Maintenance) (30-00463-00). <b>BD7317</b>	<b>CARRIER-TRANSICOLD Generators</b>
PC6024 w/Kubota Eng Lube (9610133K)..... <b>B7139</b> Fuel Spin-on (9610124K)..... <b>BF954 +</b> Radial Seal Air (3072411K)..... <b>RS3715</b>	CT4-134DI F-F Lube (S/N XA0001 to 3Y0014) (30-00323-00)..... <b>BT217</b> B-P Lube (30-00304-00)..... <b>B164</b> Dual-Flow Lube (S/N 3Y0015-on) (30-00463-00)..... <b>BD7317</b>	69GC15-104/114/134/144/154/174/184 & 194 w/CT4-114, CT4-133-DI, CT4-134-DI Eng. Lube (30-00323-00)..... <b>BT217</b> P. Fuel (30-00301-00)..... <b>BF896</b> S. Fuel (30-00302-00)..... <b>BF970 +</b> Air (66U1-2155)..... <b>PA1690-FN +</b>
PC6028 w/Kubota Eng Lube (9610133K)..... <b>B7139</b> Fuel Spin-on (9610124K)..... <b>BF954 +</b> Radial Seal Air (3072411K)..... <b>RS3715</b>	CT4-134-DI Lube (To S/N 3A0001) (30-00323-00)..... <b>BT217</b> Dual-Flow Lube (S/N 3A0001-on; w/Ext. Maintenance) (30-00463-00)..... <b>BD7317</b> Lube (S/N XA0001-3Y0014) (30-00323-00)..... <b>BT217</b>	69GC15-164 w/CT4-134DI Eng. Lube (30-00323-00)..... <b>BT217</b> P. Fuel/Water Separator (w/o Drain or Sensor Port) (30-01079-00)..... <b>BF1224</b> P. Fuel/Water Separator (w/Drain) (30-01079-00)..... <b>BF1223</b> P. Fuel/Water Separator (w/Drain & Sensor Port) (30-01079-00)..... <b>BF1223-SP</b> P. Fuel/Water Separator (Open End for Bowl) (30-01079-00)..... <b>BF1223-O</b> P. Fuel (30-00-301-00)..... <b>BF896</b> S. Fuel (30-00302-00)..... <b>BF970 +</b> Air (66U1-2155)..... <b>PA1690-FN +</b>
<b>CARRIER-TRANSICOLD Engines</b>	CT4-134TVU Lube (30-00304-00)..... <b>B164</b>	69GL15-114, 69GL15-134 w/Deutz Eng. Single Fuel/Water Separator (w/o Drain or Sensor Port) (30-01079-00)..... <b>BF1224</b> Single Fuel/Water Separator (w/Drain) (30-01079-00)..... <b>BF1223</b> Single Fuel/Water Separator (w/Drain & Sensor Port) (30-01079-00)..... <b>BF1223-SP</b> Single Fuel/Water Separator (Open End for Bowl) (30-01079-00)..... <b>BF1223-O</b> P. Fuel (30-00301-00)..... <b>BF896</b> S. Fuel (30-00302-00)..... <b>BF970 +</b>
CT2-29TV F-F Lube (941172)..... <b>B7139</b> B-P Lube (30-00304-00)..... <b>B164</b>	CT4-134TV F-F Lube (30-00304-00)..... <b>B164</b>	
CT3-37 Lube (941172)..... <b>B7139</b>	CT4-134-TV F-F Lube (30-00323-00)..... <b>BT217</b> Dual-Flow Lube (If Converted to Ext. Maintenance) (30-00463-00). <b>BD7317</b>	
CT3-44TV Lube (941172)..... <b>B7139</b> Fuel (30-00302-00)..... <b>BF970 +</b>	CT4-134TVU Lube (30-00304-00)..... <b>B164</b>	
CT3-69TV Fuel (30-00302-00)..... <b>BF970 +</b>	V1902-DI Lube (30-00323-00)..... <b>BT217</b> Dual-Flow Lube (If Converted to Ext. Maintenance) (30-00463-00). <b>BD7317</b>	
CT4-91TV F-F Lube (945539)..... <b>B161-S</b> B-P Lube (30-00304-00)..... <b>B164</b> Fuel (30-00302-00)..... <b>BF970 +</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

CARRIER-TRANSICOLD Generators (cont'd)	CARRIER-TRANSICOLD Generators (cont'd)	CARRIER-TRANSICOLD Refrigeration Units (cont'd)
69GL15-124 w/Kubota Eng. Lube (30-00323-00)..... <b>BT217</b> Fuel/Water Separator (w/o Drain or Sensor Port) (30-01079-00)..... <b>BF1224</b> Fuel/Water Separator (w/Drain) (30-01079-00)..... <b>BF1223</b> Fuel/Water Separator (w/Drain & Sensor Port) (30-01079-00)..... <b>BF1223-SP</b> Fuel/Water Separator (Open End for Bowl) (30-01079-00)..... <b>BF1223-O</b>	69UG15 w/V2203-DI Eng. (PID UG1450-on) Fuel/Water Separator (30-01101-50)..... <b>PF7751</b> Radial Seal Air (30-00426-27)..... <b>RS5325</b>	Extra XT w/CT4-114TV Eng. (Cont'd) Radial Seal Air (To S/N LAA90946117) (30-00426-20)..... <b>RS3704</b> Air (S/N LAA90946117-on) (30-00471-20)..... <b>PA5584</b>
69GN15-114 w/CT4-114 Eng. Lube (30-00323-00)..... <b>BT217</b> P. Fuel (30-00301-00)..... <b>BF896</b> S. Fuel (30-00302-00)..... <b>BF970 +</b> Air (66U1-6435-P06)..... <b>PA1865-FN</b>	<b>CARRIER-TRANSICOLD Refrigeration Units</b> Models w/Perkins 4.99 Eng. Lube (32578)..... <b>P15</b> Can-Type Fuel (26560017)..... <b>BF825 +</b> Fuel Ele. (26560088)..... <b>PF882</b> Fuel Ele. (30232)..... <b>PF816-S</b> Fuel Ele. (31938)..... <b>PF838</b>	Genesis Multi-Temp (S/N HAD90547903 to NAY90594028) F-F Lube (30-00323-00)..... <b>BT217</b> B-P Lube (30-00304-00)..... <b>B164</b> Fuel/Water Separator (30-01090-05)..... <b>BF1224 +</b> Fuel (30-01079-01)..... <b>BF7628</b> Air (30-00430-23)..... <b>PA4802</b>
69GN15-124 w/CT4-114 Eng. Lube (30-00323-00)..... <b>BT217</b> P. Fuel (30-00301-00)..... <b>BF896</b> S. Fuel (30-00302-00)..... <b>BF970 +</b> Air (66U1-2155)..... <b>PA1690-FN +</b>	250CM w/Mercedes-Benz OM636 Eng. Lube..... <b>P106</b> Single-Stage Fuel..... <b>PF834</b>	Genesis R70 Lube (941172)..... <b>B7139</b> S. Fuel (30-00302-00)..... <b>BF970 +</b> Radial Seal Air (30-60049-20)..... <b>RS3715</b>
69RG15 w/CT4-134-DI Eng. (To PID RG1135) F-F Lube (30-00323-00)..... <b>BT217</b> F-F Lube (30-00450-00)..... <b>B7311-MPG</b> Dual-Flow Lube (Eng. S/N 2Y2853-on) (30-00463-00)..... <b>BD7317</b> Fuel/Water Separator (30-01101-50)..... <b>PF7751</b> Fuel (Prior to UG0679) (30-01079-01)..... <b>BF7628</b>	270 w/Hercules 1XB Eng. Deluxe Hsg. B-P Lube Sock (66595B)..... <b>JC405</b> Michiana Hsg. Lube (17249BS)..... <b>P54</b> Purolator Hsg. B-P Lube (47247BS)..... <b>P73</b>	Genesis R90 Lube (30-00323-00)..... <b>BT217</b> Fuel (30-00302-00)..... <b>BF970 +</b> Radial Seal Air (30-60049-20)..... <b>RS3715</b>
69RG15 w/CT4-134-DI Eng. (PID RG1135-on) F-F Lube (30-00323-00)..... <b>BT217</b> Dual-Flow Lube (30-00463-00)..... <b>BD7317</b> Fuel/Water Separator (30-01101-50)..... <b>PF7751</b> Radial Seal Air (30-00426-25)..... <b>RS3704</b>	620 Lube (111836)..... <b>B163</b> S. Fuel Ele..... <b>PF816-S</b>	Genesis R90 Multi-Temp w/CT3-69 Eng. Eng. Lube (30-00323-00)..... <b>BT217</b> Fuel (30-00302-00)..... <b>BF970 +</b> Fuel (30-01079-01)..... <b>BF7628</b>
69RG15 w/CT4-134-DI Eng. (PID RG1402-on) Fuel/Water Separator (30-01101-50)..... <b>PF7751</b> Radial Seal Air (30-00426-27)..... <b>RS5325</b>	640M w/Mercedes-Benz Eng. Lube..... <b>PT82-HD +</b> S. Fuel Ele..... <b>PF950</b>	Genesis TM1000 w/CT4-134DI, DT4-134TV Engs. F-F Lube (30-00323-00)..... <b>BT217</b> B-P Lube (30-00304-00)..... <b>B164</b> Fuel (30-01079-01)..... <b>BF7628</b> Air (30-01077-01)..... <b>PA2803</b>
69UG15 w/CT4-134-DI (To PID UG1032) F-F Lube (30-00323-00)..... <b>BT217</b> F-F Lube (30-00304-00)..... <b>B164</b> F-F Lube (30-00450-00)..... <b>B7311-MPG</b> Dual-Flow Lube (Eng. S/N 2Y2853-on) (30-00463-00)..... <b>BD7317</b> Fuel/Water Separator (30-01101-50)..... <b>PF7751</b> Fuel (To UG0678) (30-01079-01)..... <b>BF7628</b>	Advantage w/CT4-134DI, CT4-134TV, CT4-114 Engs. Eng. F-F Lube (30-00323-00)..... <b>BT217</b> Eng. B-P Lube (30-00304-00)..... <b>B164</b> P. Fuel (30-01079-01)..... <b>BF7628</b> S. Fuel (30-00302-00)..... <b>BF970 +</b> Air (66U12155)..... <b>PA1690-FN +</b> Air (300043023)..... <b>PA4802</b>	Genesis TM900 w/CT4-134DI, DT4-134TV Engs. F-F Lube (30-00323-00)..... <b>BT217</b> B-P Lube (30-00304-00)..... <b>B164</b> Fuel (30-01079-01)..... <b>BF7628</b> Air (30-01077-01)..... <b>PA2803</b>
69UG15 w/CT4-134-DI Eng. (PID UG1024 to UG1226) Dual-Flow Lube (30-00463-00)..... <b>BD7317</b> Fuel/Water Separator (30-01101-50)..... <b>PF7751</b> Radial Seal Air (30-00426-25)..... <b>RS3704</b>	Eagle w/CT4-134DI, CT4-134TV, CT4-114, CT4114DI Engs. Eng. F-F Lube (30-00323-00)..... <b>BT217</b> Eng. B-P Lube (30-00304-00)..... <b>B164</b> P. Fuel (30-01079-01)..... <b>BF7628</b> S. Fuel (30-00302-00)..... <b>BF970 +</b> Air (66U12155)..... <b>PA1690-FN +</b>	Genesis TR1000 F-F Lube (30-00323-00)..... <b>BT217</b> B-P Lube (30-00304-00)..... <b>B164</b> Air (30-00426-20)..... <b>RS3704</b>
	EuroPhoenix S. Fuel (30-00302-00)..... <b>BF970 +</b>	Gen Set 69UG F-F Lube (30-00323-00)..... <b>BT217</b> Dual-Flow Lube (30-00463-00)..... <b>BD7317</b> Fuel/Water Separator (30-01101-50)..... <b>PF7751</b> Fuel (30-01079-01)..... <b>BF7628</b> Radial Seal Air (30-00426-25)..... <b>RS3704</b>
	Extra w/CT4-114TV Eng. Eng. F-F Lube (30-00323-00)..... <b>BT217</b> Eng. B-P Lube (30-00304-00)..... <b>B164</b> Fuel/Water Separator (30-01090-05)..... <b>BF1224 +</b> Fuel (30-01079-01)..... <b>BF7628</b> Air (300043023)..... <b>PA4802</b> Air (30-01077-01)..... <b>PA2803</b>	King Bird TDS295N4 Lube (941172)..... <b>B7139</b>
	Extra XT w/CT4-114TV Eng. F-F Lube (30-00450-00)..... <b>B7311-MPG</b> B-P Lube (30-00304-00)..... <b>B164</b> Fuel/Water Separator (30-01090-05)..... <b>BF1224 +</b>	Maxima Eng. Lube (30-00323-00)..... <b>BT217</b> Eng. Lube (30-50327-00)..... <b>B161-S</b> Fuel (30-00302-00)..... <b>BF970 +</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



CARRIER-TRANSICOLD Refrigeration Units (cont'd)	CARRIER-TRANSICOLD Refrigeration Units (cont'd)	CARRIER-TRANSICOLD Refrigeration Units (cont'd)
Maxima Plus Lube (945539)..... <b>B161-S</b> Fuel (30-00302-00)..... <b>BF970 +</b>	Supra 622 w/Kubota D722 Eng. Fuel/Water Separator (w/o Drain or Sensor Port) (30-01090-00)..... <b>BF1224</b> Fuel/Water Separator (w/Drain) (30-01090-00)..... <b>BF1223</b> Fuel/Water Separator (w/Drain & Sensor Port) (30-01090-00)..... <b>BF1223-SP</b> Fuel/Water Separator (Open End for Bowl) (30-01090-00)..... <b>BF1223-O</b>	Supra 822 w/CT3-44TV Eng. F-F Lube (941172)..... <b>B7139</b> B-P Lube (30-00304-00)..... <b>B164</b> Fuel Spin-on (30-00302-00)..... <b>BF970 +</b> Air (941070)..... <b>PA1865-FN</b> Radial Seal Air (30-60049-20)..... <b>RS3715</b>
Optima w/CT4-911TV Eng. Eng. F-F Lube (30-50327-00)..... <b>B161-S</b> Eng. B-P Lube (30-00304-00)..... <b>B164</b> Fuel/Water Separator (w/o Drain or Sensor Port) (30-01090-00)..... <b>BF1224</b> Fuel/Water Separator (w/Drain) (30-01090-00)..... <b>BF1223</b> Fuel/Water Separator (w/Drain & Sensor Port) (30-01090-00)..... <b>BF1223-SP</b> Fuel/Water Separator (Open End for Bowl) (30-01090-00)..... <b>BF1223-O</b> Fuel (30-01079-01)..... <b>BF7628</b> Air (300043023)..... <b>PA4802</b> Air (30-01077-01)..... <b>PA2803</b>	Supra 622 w/CT3-44TV Eng. Eng. F-F Lube (30-00323-00)..... <b>BT217</b> Eng. F-F Lube (941172)..... <b>B7139</b> Eng. B-P Lube (30-00304-00)..... <b>B164</b> Fuel (30-00302-00)..... <b>BF970 +</b> Fuel (30-01079-01)..... <b>BF7628</b> Radial Seal Air (30-60049-20)..... <b>RS3715</b>	Supra 844 w/CT3-44TV Eng. F-F Lube (941172)..... <b>B7139</b> B-P Lube (30-00304-00)..... <b>B164</b> Fuel/Water Separator (30-01090-05)..... <b>BF1224 +</b> Fuel (30-01079-01)..... <b>BF7628</b> Fuel (30-00302-00)..... <b>BF970 +</b> Radial Seal Air (30-60049-20)..... <b>RS3715</b> Air (941070)..... <b>PA1865-FN</b>
Phoenix Ultra, Extra XL Lube (30-00304)..... <b>B164</b> Fuel/Water Separator (w/o Drain or Sensor Port) (30-01090-00)..... <b>BF1224</b> Fuel/Water Separator (w/Drain) (30-01090-00)..... <b>BF1223</b> Fuel/Water Separator (w/Drain & Sensor Port) (30-01090-00)..... <b>BF1223-SP</b> Fuel/Water Separator (Open End for Bowl) (30-01090-00)..... <b>BF1223-O</b>	Supra 644 w/CT3-44TV Eng. Eng. F-F Lube (30-00323-00)..... <b>BT217</b> Eng. F-F Lube (941172)..... <b>B7139</b> Eng. B-P Lube (30-00304-00)..... <b>B164</b> Fuel/Water Separator (30-01090-05)..... <b>BF1224 +</b> Fuel (30-00302-00)..... <b>BF970 +</b> Fuel (30-01079-01)..... <b>BF7628</b> Radial Seal Air (30-60049-20)..... <b>RS3715</b>	Supra 850 w/CT3-44 Eng. Lube (941172)..... <b>B7139</b> Fuel (30-00302-00)..... <b>BF970 +</b>
R70 w/CT3-44TV Eng. B-P Lube (30-00304-00)..... <b>B164</b> Fuel (30-00302-00)..... <b>BF970 +</b>	Supra 650 w/CT3-44 Eng. Lube (941172)..... <b>B7139</b> Fuel (30-00302-00)..... <b>BF970 +</b>	Supra 850U w/CT3-44TV Eng. Lube (941172)..... <b>B7139</b> Lube (30-00323-00)..... <b>BT217</b> Fuel (30-00302-00)..... <b>BF970 +</b> Radial Seal O. Air (30-00426-20)..... <b>RS3704</b>
R90 w/CT3-69TV Eng. Fuel (30-00302-00)..... <b>BF970 +</b> Radial Seal Air (30-60049-20)..... <b>RS3715</b>	Supra 722 w/Kubota D722 Eng. Fuel/Water Separator (w/o Drain or Sensor Port) (30-01090-00)..... <b>BF1224</b> Fuel/Water Separator (w/Drain) (30-01090-00)..... <b>BF1223</b> Fuel/Water Separator (w/Drain & Sensor Port) (30-01090-00)..... <b>BF1223-SP</b> Fuel/Water Separator (Open End for Bowl) (30-01090-00)..... <b>BF1223-O</b>	Supra 922 w/CT3-69TV Eng. Eng. Lube (30-00323-00)..... <b>BT217</b> Fuel/Water Separator (S/N EFY90375766-on) (30-01090-05)..... <b>BF1224 +</b> Fuel (30-00302-00)..... <b>BF970 +</b> Fuel (To S/N EFY90375766) (30-01079-01)..... <b>BF7628</b> Radial Seal Air (30-60049-20)..... <b>RS3715</b>
Solara w/CT2-29 Eng. Fuel (30-01079-01)..... <b>BF7628</b>	Supra 722 w/CT3-44TV Eng. Eng. F-F Lube (30-00323-00)..... <b>BT217</b> Eng. F-F Lube (941172)..... <b>B7139</b> Eng. B-P Lube (30-00304-00)..... <b>B164</b> Fuel (30-00302-00)..... <b>BF970 +</b> Fuel (30-01079-01)..... <b>BF7628</b> Radial Seal Air (30-60049-20)..... <b>RS3715</b>	Supra 944 w/CT3-69TV Eng. Eng. Lube (30-00323-00)..... <b>BT217</b> Fuel/Water Separator (S/N EFY90375766-on) (30-01090-05)..... <b>BF1224 +</b> Fuel (30-00302-00)..... <b>BF970 +</b> Fuel (To S/N EFY90375766) (30-01079-01)..... <b>BF7628</b> Radial Seal Air (30-60049-20)..... <b>RS3715</b>
Supra 322 w/CT2-29TV Eng. Eng. F-F Lube (941172)..... <b>B7139</b> Eng. B-P Lube (30-00304-00)..... <b>B164</b>	Supra 744 w/CT3-44TV Eng. Eng. F-F Lube (30-00323-00)..... <b>BT217</b> Eng. F-F Lube (941172)..... <b>B7139</b> Eng. B-P Lube (30-00304-00)..... <b>B164</b> Fuel/Water Separator (30-01090-05)..... <b>BF1224 +</b> Fuel (30-00302-00)..... <b>BF970 +</b> Fuel (30-01079-01)..... <b>BF7628</b> Radial Seal Air (30-60049-20)..... <b>RS3715</b>	Supra 950 w/CT3-69 Eng. Fuel (30-00302-00)..... <b>BF970 +</b>
Supra 422 w/CT2-29TV Eng. Eng. F-F Lube (941172)..... <b>B7139</b> Eng. B-P Lube (30-00304-00)..... <b>B164</b> Fuel/Water Separator (30-01090-05)..... <b>BF1224 +</b> Fuel (30-01079-01)..... <b>BF7628</b>	Supra 750 w/CT3-44 Eng. Lube (941172)..... <b>B7139</b> Fuel (30-00302-00)..... <b>BF970 +</b>	Thunderbird w/CT4-134DI, CT4-114 Engs. Eng. F-F Lube (30-00323-00)..... <b>BT217</b> Eng. B-P Lube (30-00304-00)..... <b>B164</b> S. Fuel (30-00302-00)..... <b>BF970 +</b> Air (66U12155)..... <b>PA1690-FN +</b>
Supra 522 Lube (941172)..... <b>B7139</b> Fuel Spin-on (30-00302-00)..... <b>BF970 +</b> Air (941070)..... <b>PA1865-FN</b>		Thunderbird NDJ w/4 Cyl. Kubota Diesel Eng. F-F Lube (30-00323)..... <b>BT217</b> B-P Lube (30-00304-00)..... <b>B164</b> P. Fuel Spin-on (30-00301)..... <b>BF896</b> S. Fuel Spin-on (30-00302)..... <b>BF970 +</b>
Supra 544 Lube (941172)..... <b>B7139</b> Fuel Spin-on (30-00302-00)..... <b>BF970 +</b> Air (941070)..... <b>PA1865-FN</b>		TM 900 Multi-Temp w/CT4-134DI Eng. Lube (30-00450-00)..... <b>B7311-MPG</b>
Supra 550 w/CT2-29 Eng. F-F Lube (941172)..... <b>B7139</b> B-P Lube (30-00304-00)..... <b>B164</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>CARRIER-TRANSICOLD</b> Refrigeration Units (cont'd)	<b>CARRIER-TRANSICOLD</b> Refrigeration Units (cont'd)	<b>CATERPILLAR</b> Diesel Truck Engines (cont'd)
TM 1000 Multi-Temp w/CT4-134DI Eng. Eng. Lube (30-00450-00)..... <b>B7311-MPG</b>	Ultra XTC w/CT4-134DI Eng. F-F Lube (30-00450-00)..... <b>B7311-MPG</b> Dual-Flow Lube (30-00463-00).... <b>BD7317</b> Fuel/Water Separator (30-01090-05)..... <b>BF1224 +</b> Radial Seal Air (30-00426-20).... <b>RS3704</b> Radial Seal Air (Extended Service Interval) (30-00426-27).... <b>RS5325</b> Air (S/N LAA90946117-on) (30-00471-20)..... <b>PA5584</b>	1673 (Cont'd) Air (2M7941)..... <b>PA645</b> Std. Air (4M9334)..... <b>PA1634 +</b> Air (Upgrade) (4M9334)..... <b>PA1634XP</b> Air (S/N 1L1-up)..... <b>PA618-S</b> Breather (1M3474)..... <b>CLN&amp;R</b>
Ultima w/CT4-134DI Eng. F-F Lube (30-00323-00)..... <b>BT217</b> B-P Lube (30-00304-00)..... <b>B164</b> Fuel/Water Separator (30-01090-05)..... <b>BF1224 +</b> Fuel (30-01079-01)..... <b>BF7628</b> Air (S/N FAR90427529-on) (300043023)..... <b>PA4802</b> Air (30-01077-01)..... <b>PA2803</b>	Ultra XTC Rail Edition w/CT4-134DI Eng. Eng. Lube (30-00450-00)..... <b>B7311-MPG</b>	1673B Lube (5S0485)..... <b>PT88-HD</b> Fuel Ele. (9H4729)..... <b>PF824</b> P. Fuel Ele. (9M2341)..... <b>PF935</b> Air (2S5648)..... <b>PA645</b> Std. Air (4M9334)..... <b>PA1634 +</b> Air (Upgrade) (4M9334)..... <b>PA1634XP</b>
Ultima 53 F-F Lube (30-00450-00)..... <b>B7311-MPG</b> B-P Lube (30-00304-00)..... <b>B164</b> Fuel/Water Separator (30-01090-05)..... <b>BF1224 +</b> Radial Seal Air (30-00426-20).... <b>RS3704</b>	Vector 1800 Multi-Temp w/CT4-134DI Eng. Eng. Lube (30-00450-00)..... <b>B7311-MPG</b>	1673C Lube (5S0484)..... <b>PT670</b> Box-Style Fuel/Water Separator (6N7617)..... <b>BF912</b> P. Fuel Ele. (9M2341)..... <b>PF935</b> Fuel Spin-on (1P2299)..... <b>BF970 +</b> Std. Air (4M9334)..... <b>PA1634 +</b> Air (Upgrade) (4M9334)..... <b>PA1634XP</b> Comp. Air (9L2169)..... <b>PA1704</b>
Ultima 53-Stealth w/Kubota Eng. Lube (30-00304)..... <b>B164</b> Fuel (30-01090-01)..... <b>BF7628</b>	Vector 6500 w/2.2L D.I. (Hybrid) Dual-Flow Lube (30-00463-00).... <b>BD7317</b> Fuel/Water Separator (w/o Drain or Sensor Port) (30-01090-04).... <b>BF1224</b> Fuel/Water Separator (w/Drain) (30-01090-04)..... <b>BF1223</b> Fuel/Water Separator (w/Drain & Sensor Port) (30-01090-04)..... <b>BF1223-SP</b> Fuel/Water Separator (Open End for Bowl) (30-01090-04)..... <b>BF1223-O</b>	1674 Lube Ele. (5S0484)..... <b>PT670</b> P. Fuel Ele. (9M2342)..... <b>[2] PF935</b> Fuel Spin-on (1R0740)..... <b>BF970 +</b> Opt. Air (4L9853)..... <b>PA1629-S</b> Comp. Air (9L2169)..... <b>PA1704</b>
Ultima XTC w/CT4-134DI Eng. F-F Lube (30-00450-00)..... <b>B7311-MPG</b> Dual-Flow Lube (30-00463-00).... <b>BD7317</b> Fuel/Water Separator (30-01090-05)..... <b>BF1224 +</b> Fuel (30-01079-01)..... <b>BF7628</b> Radial Seal Air (30-00426-20).... <b>RS3704</b> Radial Seal Air (Extended Service Interval) (30-00426-27).... <b>RS5325</b> Air (S/N LAA90946117-on) (30-00471-20)..... <b>PA5584</b>	X2 Special Edition Fuel/Water Separator (w/o Drain or Sensor Port) (30-01090-04).... <b>BF1224</b> Fuel/Water Separator (w/Drain) (30-01090-04)..... <b>BF1223</b> Fuel/Water Separator (w/Drain & Sensor Port) (30-01090-04)..... <b>BF1223-SP</b> Fuel/Water Separator (Open End for Bowl) (30-01090-04)..... <b>BF1223-O</b>	1676 Lube Ele. (5S0485)..... <b>[2] PT88-HD</b> P. Fuel Ele. (9M2342)..... <b>[2] PF935</b> Fuel Spin-on (6L7440)..... <b>[2] BF970 +</b> Opt. Air (4L9853)..... <b>PA1629-S</b> Comp. Air (9L2169)..... <b>PA1704</b>
Ultima XTC Rail Edition w/CT4-134DI Eng. Eng. Lube (30-00450-00)..... <b>B7311-MPG</b>	<b>CATERPILLAR</b> Diesel Truck Engines	1693 Lube Ele. (5S0485)..... <b>[2] PT88-HD</b> Lube Spin-on (2P4005)..... <b>B99 +</b> Fuel Ele. (6H5932)..... <b>PF823-E</b> P. Fuel Ele. (9M2342)..... <b>[2] PF935</b> Fuel Spin-on (1P2299)..... <b>[2] BF970 +</b> Air (4L9853)..... <b>PA1629-S</b> Air (9L3420)..... <b>PA1630-2</b> Comp. Air (9L2169)..... <b>PA1704</b>
Ultra w/CT4-134DI, CT4-134TV Eng. Eng. F-F Lube (30-00323-00)..... <b>BT217</b> Eng. B-P Lube (30-00304-00)..... <b>B164</b> Fuel/Water Separator (30-01090-05)..... <b>BF1224 +</b> Fuel (30-01079-01)..... <b>BF7628</b> Air (300043023)..... <b>PA4802</b> Air (30-01077-01)..... <b>PA2803</b>	Models w/Air Compressor Air Breather (9L2169)..... <b>PA1704</b>	3054 Lube (7W2326)..... <b>BT237</b> Can-Type Fuel (67-6987)..... <b>BF825 +</b>
Ultra XL Standby w/CT4-134DI Eng. F-F Lube (30-00323-00)..... <b>BT217</b> F-F Lube (30-00450-00)..... <b>B7311-MPG</b> B-P Lube (30-00304-00)..... <b>B164</b> Fuel (To S/N DAW90273677) (30-01079-01)..... <b>BF7628</b> Air (30-01077-01)..... <b>PA2803</b>	1140, 1145, 1150, 1160 Lube Spin-on (9L9200)..... <b>[2] BT364</b> Fuel Spin-on (9L9100)..... <b>BF583</b>	3114 Lube (To 1/2004 (Standard Vers.)) (1R0739)..... <b>B76</b> Lube (1/2004-on) (1R1807)..... <b>B7700 +</b> Fuel (1R0751)..... <b>BF7632</b>
Ultra XT w/CT4-134DI Eng. Eng. Lube (30-00450-00)..... <b>B7311-MPG</b> Fuel/Water Separator (30-01090-05)..... <b>BF1224 +</b> Radial Seal Air (To S/N LAA90946117) (30-00426-20).... <b>RS3704</b> Air (S/N LAA90946117-on) (30-00471-20)..... <b>PA5584</b>	1670 Lube Ele. (5S0485)..... <b>PT88-HD</b> P. Fuel Ele. (8H4681)..... <b>PF935</b> Fuel (9H4729)..... <b>PF824</b> Fuel (S/N 6A6000-6053) (4H8792)..... <b>PF823-E +</b> Std. Air (4M9334)..... <b>PA1634 +</b> Air (Upgrade) (4M9334)..... <b>PA1634XP</b>	3116 Lube Spin-on (To 1/2004 (Standard Vers.)) (1R0739)..... <b>B76</b> Lube Spin-on (1/2004-on) (1R1807)..... <b>B7700 +</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

CATERPILLAR Diesel Truck Engines (cont'd)	CATERPILLAR Diesel Truck Engines (cont'd)	CATERPILLAR Diesel Truck Engines (cont'd)
3116 (Cont'd)	3176B	3406B, 3406C (14.6L)
<b>Box-Style Fuel/Water Separator</b> (8N9803)..... <b>BF912</b>	<b>F-F Lube</b> (1R0716)..... <b>B99 +</b>	<b>F-F Lube</b> (1R0716)..... <b>B99 +</b>
<b>Fuel/Water Separator</b> (117-4089)..... <b>BF7679-D</b>	<b>F-F Lube</b> (High Efficiency) (1R1808)..... <b>B7299 +</b>	<b>F-F Lube</b> (High Efficiency) (1R1808)..... <b>B7299 +</b>
<b>Fuel/Water Separator</b> (w/Sensor Port) (146-6695)..... <b>BF1350-SP</b>	<b>B-P Lube</b> (1W8845)..... <b>B7577</b>	<b>Fuel/Water Separator</b> (256-8753)..... <b>BF1259</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (146-6695)..... <b>BF46030-O</b>	<b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b>	<b>P. Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b>
<b>Fuel Spin-on</b> (ATAAC Engine Only) (1R0740)..... <b>BF970 +</b>	<b>Fuel/Water Separator Spin-on</b> (256-8753)..... <b>BF1259</b>	<b>Fuel Spin-on</b> (1R0712)..... <b>BF614 +</b>
<b>Fuel Spin-on</b> (High Efficiency) (1R0750)..... <b>BF7633 +</b>	<b>P. Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b>	<b>Fuel Spin-on</b> (High Efficiency) (1R0749)..... <b>BF7587 +</b>
<b>Fuel Spin-on</b> (High Efficiency) (1R0751)..... <b>BF7632</b>	<b>Fuel Spin-on</b> (1R0749)..... <b>BF7587 +</b>	3406E (14.6L)
<b>Attach. Fuel Spin-on</b> (7E9763).... <b>BF984</b>	3208 (10.4L)	<b>F-F Lube</b> (1R0716)..... <b>B99 +</b>
<b>Attach. Radial Seal O. Air</b> (6I2499)..... <b>RS3502</b>	<b>Lube</b> (1R0713)..... <b>[2] BT230</b>	<b>F-F Lube</b> (High Efficiency) (1R1808)..... <b>B7299 +</b>
<b>Attach. Radial Seal I. Air</b> (6I2500)..... <b>RS3503</b>	<b>Lube</b> (1R0714)..... <b>[2] B75</b>	<b>Fuel/Water Separator</b> (256-8753)..... <b>BF1259</b>
<b>Comp. Air</b> (9L2169)..... <b>PA1704</b>	<b>Lube</b> (9L9200)..... <b>[2] BT364</b>	<b>P. Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b>
3126, 3126B, 3126E (7.2L)	<b>Box-Style Fuel/Water Separator</b> (8N9803)..... <b>BF912</b>	<b>Fuel Spin-on</b> (For use w/HvyDty. Priming Pump) (1R0712)..... <b>BF614 +</b>
<b>Lube</b> (To 1/2004 (Standard Vers.)) (1R0739)..... <b>B76</b>	<b>P. Fuel Ele.</b> (9M2341)..... <b>PF935</b>	<b>Fuel Spin-on</b> (High Efficiency) (1R0749)..... <b>BF7587 +</b>
<b>Lube</b> (1/2004-on) (1R1807)..... <b>B7700 +</b>	<b>Fuel Spin-on</b> (1R0740)..... <b>BF970 +</b>	<b>Fuel Spin-on</b> (High Efficiency) (1R0749)..... <b>BF7587 +</b>
<b>Fuel/Water Separator</b> (175-2949)..... <b>BF1268</b>	<b>Fuel Spin-on</b> (1R0750)..... <b>BF7633 +</b>	<b>Air</b> (5L1203)..... <b>PA1631-S</b>
<b>Fuel/Water Separator</b> (256-8753)..... <b>BF1259</b>	<b>Attach. Air</b> (7N1225)..... <b>PA2557</b>	C7 (7.2L)
<b>Fuel/Water Separator</b> (198-6378)..... <b>BF7798-SP</b>	3306, 3306B	<b>Lube</b> (To 1/2004 (Standard Vers.)) (1R0739)..... <b>B76</b>
<b>Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b>	<b>Lube Ele.</b> (5S0484)..... <b>PT670</b>	<b>Lube</b> (1/2004-on) (1R1807)..... <b>B7700 +</b>
<b>Fuel Spin-on</b> (High Efficiency) (1R0751)..... <b>BF7632</b>	<b>Lube Spin-on</b> (1R0716)..... <b>B99 +</b>	<b>Lube</b> (1/2004-on) (1R1807)..... <b>B7700 +</b>
3176	<b>Lube Spin-on</b> (To 1/2004 (Standard Vers.)) (1R0739)..... <b>B76</b>	<b>Lube</b> (1R1808)..... <b>B7299 +</b>
<b>F-F Lube</b> (1R0716)..... <b>B99 +</b>	<b>Lube Spin-on</b> (1/2004-on) (1R1807)..... <b>B7700 +</b>	<b>Some Fuel/Water Separator</b> <b>Spin-on</b> (256-8753)..... <b>BF1259</b>
<b>F-F Lube</b> (High Efficiency) (1R1808)..... <b>B7299 +</b>	<b>Fuel/Water Separator Box-Style</b> (6N7617)..... <b>BF912</b>	<b>Fuel/Water Separator Spin-on</b> (175-2949)..... <b>BF1268</b>
<b>F-F Lube</b> (1R0713)..... <b>[2] BT230</b>	<b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b>	<b>Fuel</b> (High Efficiency) (1R0751).... <b>BF7632</b>
<b>F-F Lube</b> (1R0714)..... <b>[2] B75</b>	<b>Fuel/Water Separator Spin-on</b> (256-8753)..... <b>BF1259</b>	C9 (8.8L)
<b>Opt. B-P Lube Spin-on</b> (1W8845)..... <b>B7577</b>	<b>P. Fuel Ele.</b> (7W8910)..... <b>CLN&amp;R</b>	<b>Lube</b> (To 1/2004) (1R0716)..... <b>B99 +</b>
<b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b>	<b>P. Fuel Ele.</b> (9M2341)..... <b>PF935</b>	<b>Lube</b> (1/2004-on) (1R1808)..... <b>B7299 +</b>
<b>Fuel/Water Separator Spin-on</b> (256-8753)..... <b>BF1259</b>	<b>P. Fuel Spin-on</b> (1R1740)..... <b>BF970 +</b>	<b>Lube</b> (1R1807)..... <b>B7700 +</b>
<b>P. Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b>	<b>S. Fuel Spin-on</b> (1R0750)..... <b>BF7633 +</b>	<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (133-5673).... <b>BF1395-O</b>
<b>Remote Mtd. Fuel Spin-on</b> (1R0712)..... <b>BF614 +</b>	<b>Attach. Lube</b> (1R0716)..... <b>B99 +</b>	<b>Fuel/Water Separator Spin-on</b> (w/Drain) (133-5673)..... <b>BF1265</b>
<b>FldInst. Fuel Spin-on</b> (High Efficiency) (1R0749)..... <b>BF7587 +</b>	<b>Lube</b> (To 1/2004 (Standard Vers.)) (1R0739)..... <b>B76</b>	<b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (133-5673)..... <b>BF1395-SP</b>
<b>P. Fuel Spin-on</b> (1R1740)..... <b>BF970 +</b>	<b>Lube</b> (1/2004-on) (1R1807)..... <b>B7700 +</b>	<b>Fuel/Water Separator Spin-on</b> (175-2949)..... <b>BF1268</b>
<b>S. Fuel Spin-on</b> (High Efficiency) (1R0750)..... <b>BF7633 +</b>	<b>P. Fuel Ele.</b> (9M2341)..... <b>PF935</b>	<b>Fuel/Water Separator Spin-on</b> (256-8753)..... <b>BF1259</b>
<b>Std. O. Air</b> (7W5317)..... <b>PA1634 +</b>	<b>Fuel Spin-on</b> (1R0740)..... <b>BF970 +</b>	<b>Fuel Spin-on</b> (High Efficiency) (1R0751)..... <b>BF7632</b>
<b>O. Air</b> (Upgrade) (7W5317)..... <b>PA1634XP</b>	<b>Fuel Spin-on</b> (1R0750)..... <b>BF7633 +</b>	C10 (10.3L)
<b>I. Air</b> (9S9972)..... <b>PA2310</b>	<b>Axial Seal Air</b> (7W5317)..... <b>PA1634 +</b>	<b>F-F Lube</b> (1R0716)..... <b>B99 +</b>
	<b>Radial Seal Air</b> (6I2501)..... <b>RS3504</b>	<b>F-F Lube</b> (High Efficiency) (1R1808)..... <b>B7299 +</b>
	3406	<b>Attach. B-P Lube</b> (1W8845)..... <b>B7577</b>
	<b>F-F Lube</b> (1R0716)..... <b>B99 +</b>	
	<b>F-F Lube</b> (High Efficiency) (1R1808)..... <b>B7299 +</b>	
	<b>Fuel/Water Separator</b> (256-8753)..... <b>BF1259</b>	
	<b>P. Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b>	
	<b>Fuel Spin-on</b> (4N5823)..... <b>BF614 +</b>	
	<b>Fuel</b> (High Efficiency) (1R0749).... <b>BF7587 +</b>	
	<b>Attach. Air</b> (4L9853)..... <b>PA1629-S</b>	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

CATERPILLAR Diesel Truck Engines (cont'd)	CATERPILLAR Diesel Truck Engines (cont'd)	CATERPILLAR Transmissions (cont'd)
<b>C10 (10.3L) (Cont'd)</b> <b>Attach. Fuel/Water Separator Ele.</b> (8N0205)..... PF316 <b>Attach. Fuel/Water Separator Spin-on</b> (Open End for Bowl) (133-5673)..... BF1395-O <b>Attach. Fuel/Water Separator Spin-on</b> (w/Drain) (133-5673)..... BF1265 <b>Attach. Fuel/Water Separator Spin-on</b> (w/Sensor Port) (133-5673)..... BF1395-SP <b>Fuel/Water Separator</b> (256-8753)..... BF1259 <b>Attach. P. Fuel Ele.</b> (9M2342)..... [2] PF935 <b>Fuel Spin-on</b> (High Efficiency) (1R0749)..... BF7587 + <b>Fuel Spin-on</b> (1R1712)..... BF614 +	<b>C15 (14.6L) &amp; (15.2L)</b> <b>Lube</b> (To 1/2004) (1R0716)..... B99 + <b>Lube</b> (1/2004-on) (1R1808)..... B7299 + <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (133-5673)... BF1395-O <b>Fuel/Water Separator Spin-on</b> (w/Drain) (133-5673)..... BF1265 <b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (133-5673)..... BF1395-SP <b>Fuel/Water Separator Spin-on</b> (256-8753)..... BF1259 <b>Attach. P. Fuel Ele.</b> (9M2342)..... [2] PF935 <b>Fuel Spin-on</b> (High Efficiency) (1R0749)..... BF7587 + <b>Fuel Spin-on</b> (1R1712)..... BF614 + <b>Breather</b> (3805840)..... CV15008	<b>CX-35</b> <b>Trans. Spin-on</b> (126-1817)..... BT8878-MPG <hr/> <b style="text-align: center;">CATERPILLAR</b> <b style="text-align: center;">Trucks</b> <b>CT660 w/CT11 (10.5L) Eng.</b> <b>Lube</b> (380-9364)..... P7494 <b>Fuel/Water Separator</b> (376-2578)..... PF7986 <b>Fuel/Water Separator</b> (370-0572)..... PF9814 <b>Air</b> (390-3433)..... PA30066 <b>Trans. Spin-on</b> (Fuller 4304827).. BT223 <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... B2 + <hr/> <b>CT660 w/CT13 (12.4L) Eng.</b> <b>Lube</b> (380-9364)..... P7494 <b>Air</b> (390-3433)..... PA30066 <b>Trans. Spin-on</b> (Fuller 4304827).. BT223 <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... B2 + <hr/> <b>CT660 w/CT15 (15.2L) Eng.</b> <b>Opt. Fuel/Water Separator Ele.</b> (Davco 102528)..... PF7930 <b>Air</b> (390-3433)..... PA30066 <b>Trans. Spin-on</b> (Fuller 4304827).. BT223 <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... B2 + <hr/> <b>CT680 w/CT13 (12.4L) Eng.</b> <b>Lube</b> (3809364)..... P7494 <b>Fuel/Water Separator</b> ..... PF7986 <b>Air</b> (3903433)..... PA30066 <b>Trans. Spin-on</b> (1261817)..... BT8878-MPG <b>Trans. Spin-on</b> (Fuller 4304827).. BT223 <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... B2 +
<b>C11 (11.1L)</b> <b>Lube</b> (To 1/2004) (1R0716)..... B99 + <b>Lube</b> (1/2004-on) (1R1808)..... B7299 + <b>Fuel/Water Separator</b> (256-8753)..... BF1259 <b>Fuel</b> (High Efficiency) (1R0749).... BF7587 + <b>Fuel</b> (1R0762)..... BF7753 <b>Fuel</b> (1R1712)..... BF614 +	<b>C16 (15.8L)</b> <b>Lube</b> (To 1/2004) (1R0716)..... B99 + <b>Lube</b> (1/2004-on) (1R1808)..... B7299 + <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (133-5673)... BF1395-O <b>Fuel/Water Separator Spin-on</b> (w/Drain) (133-5673)..... BF1265 <b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (133-5673)..... BF1395-SP <b>Fuel/Water Separator Spin-on</b> (256-8753)..... BF1259 <b>Attach. P. Fuel Ele.</b> (9M2342)..... [2] PF935 <b>Fuel Spin-on</b> (High Efficiency) (1R0749)..... BF7587 + <b>Fuel Spin-on</b> (1R1712)..... BF614 +	<hr/> <b style="text-align: center;">CCS</b> <b style="text-align: center;">Auxiliary Power Units (APU)</b> Flying J w/Kubota Z482 Eng. <b>Radial Seal Air</b> (Don. P822686)... RS3715 <hr/> <b style="text-align: center;">CENTRAMATIC</b> <b style="text-align: center;">Auxiliary Power Units (APU)</b> Centramatic w/Kubota 2 Cyl. Diesel Eng. <b>Lube</b> (Luberfiner PH299)..... BT237 <b>Air</b> ..... CLN&R
<b>C12 (12.0L)</b> <b>F-F Lube Spin-on</b> (1R0716)..... B99 + <b>F-F Lube Spin-on</b> (High Efficiency) (1R1808)..... B7299 + <b>Attach. B-P Lube Spin-on</b> (1W8845)..... B7577 <b>Attach. Fuel/Water Separator Ele.</b> (8N0205)..... PF316 <b>Attach. Fuel/Water Separator Spin-on</b> (Open End for Bowl) (133-5673)..... BF1395-O <b>Attach. Fuel/Water Separator Spin-on</b> (w/Drain) (133-5673)..... BF1265 <b>Attach. Fuel/Water Separator Spin-on</b> (w/Sensor Port) (133-5673)..... BF1395-SP <b>Fuel/Water Separator Spin-on</b> (256-8753)..... BF1259 <b>Attach. P. Fuel Ele.</b> (9M2342)..... [2] PF935 <b>Fuel Spin-on</b> (High Efficiency) (1R0749)..... BF7587 + <b>Fuel Spin-on</b> (1R1712)..... BF614 +	<b>C18 (18.1L)</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (133-5673)..... BF1395-O <b>Fuel/Water Separator</b> (w/Drain) (133-5673)..... BF1265 <b>Fuel/Water Separator</b> (w/Sensor Port) (133-5673)..... BF1395-SP <b>Coolant</b> (9N3718)..... BW5139	<hr/> <b style="text-align: center;">CHAMPION</b> <b style="text-align: center;">Buses</b> <b>CTS w/Cummins ISB (5.9L) Eng.</b> <b>Lube</b> (Fleetguard LF3970)..... B7177 <b>Fuel/Water Separator</b> (Fleetguard FS19596)..... BF1293-SPS <b>Disposable Air Hsg.</b> (Farr 114810007)..... PA3555 <b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... BA5373 <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... 20004
<b>C13 (12.5L)</b> <b>F-F Lube</b> (To 1/2004) (1R0716)... B99 + <b>F-F Lube</b> (1/2004-on) (1R1808)... B7299 + <b>F-F Lube</b> (249-2347)..... [2] B7402 <b>Fuel/Water Separator</b> (256-8753)..... BF1259 <b>Fuel</b> (High Efficiency) (1R0749).... BF7587 + <b>Fuel</b> (1R1712)..... BF614 + <b>Breather</b> (3805840)..... CV15008	<b>G3306</b> <b>Lube</b> (To 1/2004 (Standard Vers.)) (2P4004)..... B76 <b>Lube</b> (1/2004-on) (1R1807)..... B7700 + <hr/> <b style="text-align: center;">CATERPILLAR</b> <b style="text-align: center;">Transmissions</b> <b>CX28</b> <b>Trans. Spin-on</b> (w/o PTO) (126-1815)..... [2] BT8842-MPG <b>Trans. Spin-on</b> (w/PTO) (102-2828)..... BT8853-MPG <b>Trans. Spin-on</b> (Remote Mtd.) (126-1817)..... BT8878-MPG <hr/> <b>CX31</b> <b>Trans. Spin-on</b> (126-1817)..... BT8878-MPG <b>TorqConv.</b> (8S9129)..... CLN&R	

+ See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>CHAMPION Buses (cont'd)</b>	<b>CHEVROLET Gas Engines (cont'd)</b>	<b>CHEVROLET Gas Engines (cont'd)</b>
CTS w/Cummins ISB (5.9L) Eng. (Cont'd)	235 6 Cyl.	292 6 Cyl. (Cont'd)
Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016	B-P Lube (ACDelco S2)..... P52	In-Line Fuel..... BF836
Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003	B-P Lube (ACDelco SC353)..... P53	Fuel (SintBronze)..... SF898
Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017		Air (ACDelco A114C)..... PA648
Trans. Spin-on (Allison 29539579)..... BT8460	250 6 Cyl.	Air (ACDelco A178CW)..... PA1680
	Lube..... B27	Air (ACDelco A180C)..... PA621
	1 1/32 In. Fuel (Paper)..... PF893	Air (ACDelco A276C)..... PA1841
	2 1/32 In. Fuel (Paper)..... PF894-RV	
	3 15/32 In. Fuel Ele..... PF827	305 V6
	Air (ACDelco A114C)..... PA648	2 Qt. Lube Ele. (1963-66)..... P20-HD +
	Air (ACDelco A227C)..... PA658	4 3/8 In. Lube Spin-on..... B39
	Air (ACDelco A276C)..... PA1841	5 9/32 In. Lube Spin-on..... B9
	Air (ACDelco A333C)..... PA1680	1 1/32 In. Fuel Ele. (Carb.)..... PF893
	Air (ACDelco A736C)..... PA2077	3 15/32 In. Fuel Ele..... PF827
		In-Line Fuel..... BF840 +
	261 6 Cyl.	Air (2236986)..... PA1800 +
	F-F Lube Ele. (1959)..... P18	Air (702025)..... PA1922-FN
	B-P Lube (1950-58) (ACDelco S2)..... P52	
	B-P Lube (1950-58) (ACDelco SC353)..... P53	305 V8
		Lube (1988-on, (K Series))..... B35-S +
	262 V6	Other Lube Spin-on..... B6 +
	Lube..... B35-S +	Fuel (FI)..... BF853
	Fuel (4 Bbl.)..... PF894-RV	1 1/32 In. Fuel (Carb.)..... PF893
	Fuel (EFI)..... BF853	2 1/32 In. Fuel (Carb.)..... PF894-RV
	Air (Astro, S10)..... PA2106	Axial Seal Air (1976-79)..... PA2006
	Air (El Camino)..... PA2006	3 9/16 In. Air (1980-83)..... PA1680
	Air (Pickups, Vans)..... PA1680	3 15/32 In. Air (1984-on)..... PA2008
		5 7/16 In. Air (1981-on)..... PA2091
	265 V8	
	Lube (1956-57)..... P19	307 V8
	Lube (1958-59)..... P18	Opt. Lube Ele. (1968-69)..... P18
	Fuel..... PF857	Lube Spin-on..... B6 +
		Fuel (SintBronze)..... SF898
	267 V8	
	Lube..... B27	322 V8
	Fuel (To 1982)..... PF894-RV	Lube..... P25
	Fuel (1982)..... PF893	Fuel..... PF827
	Air (To 1981)..... PA1680	
	Air (1981-on)..... PA2106	327 V8
		Std. Lube Ele. (1962-68)..... P18
	283 V8	Opt. 2 Qt. Lube Ele. (1967, (Exc. 50-80 Series))..... P20-HD +
	Std. Lube Ele. (1956-57)..... P19	Lube Spin-on..... B6 +
	Std. Lube Ele. (1958-67)..... P18	Fuel..... PF827
	Opt. 2 Qt. Lube Ele. (1962-67)..... P20-HD +	1 1/32 In. Fuel (Paper) (Carb.)..... PF893
	Lube (Converted to Spin-on)..... B6 +	
	Fuel Ele. (1956-57)..... PF857	348 V8
	Fuel Ele. (1958-59)..... PF860	Std. Lube Ele..... P18
	Fuel (1959, (SintBronze) (Carb.))..... SF898	Opt. 2 Qt. Lube Ele. (1962-65)..... P20-HD +
	Fuel Ele. (1960-67)..... PF827	Fuel (1958-59)..... PF860
	Axial Seal Air (1964-67)..... PA625	Fuel (1960-65)..... SF827
	Air (w/Foam Wrap) 1964-67..... PA1800	Fuel (SintBronze) (Carb.)..... SF898
		Air (1964-65)..... PA625
	292 6 Cyl.	350 V8
	2 Qt. Lube Ele. (1967-75)..... P476	Std. Lube Ele. (1969)..... P18
	4 3/8 In. Lube Spin-on..... B27	Opt. 2 Qt. Lube Ele. (1969-72)..... P476
	5 5/16 In. Lube Spin-on..... B6 +	Lube Spin-on (1988-on, (K Series))..... B35-S +
	1 1/32 In. O.D. Fuel Ele. (1963-67)..... PF857	Opt. 1 Qt. Lube Spin-on..... B6 +
	3 In. O.D. Fuel Ele. (1963-67)..... PF860	Opt. 2 Qt. Lube Spin-on..... B7
	2 In. O.D. Fuel Ele. (1966-on)..... PF827	1 1/32 In. Fuel Ele. (Paper) (Carb.)..... PF893
	1 1/32 In. Fuel Ele. (1969-86)..... PF893	2 1/32 In. Fuel Ele. (Paper) (Carb.)..... PF894-RV
	2 1/32 In. Fuel Ele. (1988-on)..... PF894-RV	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>CHEVROLET</b> Gas Engines (cont'd)	<b>CHEVROLET</b> Gas Engines (cont'd)	<b>CHEVROLET</b> North America Trucks & Vans (cont'd)
350 V8 (Cont'd) 3 15/32 In. Fuel Ele..... PF827 In-Line Fuel (Carb.)..... BF836 In-Line Fuel (FI)..... BF853 Fuel (SintBronze) (Carb.)..... SF898	409 V8 Lube..... P20-HD + 3 15/32 In. Fuel (Paper)..... PF827 Fuel (SintBronze) (Carb.)..... SF898 Air..... PA625	14-190 w/Cat 3116 Eng. (Cont'd) Fuel/Water Separator (Sensor Port Thd. 1/2-20) (Mann WK1060/1)..... BF1339-SP +
366 V8 Std. Lube Ele. (1966)..... P18 Opt. 2 Qt. Lube Ele. (1966)..... P20-HD + 2 Qt. Lube Ele. (1967-72)..... P476 1 Qt. Lube Spin-on..... B6 + 2 Qt. Lube Spin-on..... B7 3 15/32 In. Fuel Ele. (Paper)..... PF827 Fuel (SintBronze) (Carb.)..... SF898 Fuel Spin-on..... BF782 Air (2236986)..... PA1800 + Air (6487958)..... PA2008 Air (699505)..... PA2316 Air (702025)..... PA1922-FN	427 V8 Std. Lube Ele. (1966)..... P18 Opt. 2 Qt. Lube Ele. (1966)..... P20-HD + Lube Ele. (1967-72)..... P476 Lube Spin-on..... B7 1 1/32 In. Fuel (Paper) (Carb.)..... PF893 3 15/32 In. Fuel (Paper)..... PF827 Air (2236986)..... PA1800 + Air (702025)..... PA1922-FN Air (699505)..... PA2316	15-190 w/Cat 3116 Eng. Fuel/Water Separator (Open End for Bowl) (Mann WK1060/1)..... BF46083-O Fuel/Water Separator (w/Bowl) (Mann WK1060/1)..... BF46072 Fuel/Water Separator (w/Drain) (Mann WK1060/1)..... BF1329 Fuel/Water Separator (Sensor Port Thd. 9/16-18) (Mann WK1060/1)..... BF1329-SP Fuel/Water Separator (Sensor Port Thd. 1/2-20) (Mann WK1060/1)..... BF1339-SP +
379 V6 Opt. Lube Ele..... P20-HD + 4 3/8 In. Lube Spin-on..... B39 5 9/32 In. Lube Spin-on..... B9 Fuel..... PF827 Air (2236986)..... PA1800 + Air (702025)..... PA1922-FN	432, 432M V6 Lube Ele..... P20-HD + In-Line Fuel (73103)..... BF836-K4 Air (2236986)..... PA1800 + Air (702025)..... PA1922-FN	16-220 w/Cat 3116 Eng. Fuel/Water Separator (Open End for Bowl) (Mann WK1060/1)..... BF46083-O Fuel/Water Separator (w/Bowl) (Mann WK1060/1)..... BF46072 Fuel/Water Separator (w/Drain) (Mann WK1060/1)..... BF1329 Fuel/Water Separator (Sensor Port Thd. 9/16-18) (Mann WK1060/1)..... BF1329-SP Fuel/Water Separator (Sensor Port Thd. 1/2-20) (Mann WK1060/1)..... BF1339-SP +
396 V8 Std. Lube Ele. (1966-67)..... P18 Opt. 2 Qt. Lube Ele. (1966)..... P20-HD + Opt. 2 Qt. Lube Ele. (1967-69)..... P476 Lube Spin-on..... B6 + 1 1/32 In. Fuel (Paper) (Carb.)..... PF893 3 15/32 In. Fuel (Paper)..... PF827 Fuel (SintBronze) (Carb.)..... SF898 Air (ACDelco A178CW)..... PA1680 Air (ACDelco A212CW)..... PA1758 Air (ACDelco A269CW)..... PA1798 + Air (ACDelco A329C)..... PA2006	454 V8 1 Qt. Lube..... B6 + 2 Qt. Lube..... B7 1 1/32 In. Fuel (Paper) (Carb.)..... PF893 2 1/32 In. Fuel (Paper) (Carb.)..... PF894-RV 3 15/32 In. Fuel (Paper)..... PF827 In-Line Fuel (Carb.)..... BF836 In-Line Fuel (FI)..... BF853 Fuel (SintBronze) (Carb.)..... SF898 Air (1972-75) (ACDelco A222C)..... PA1800 Air (1972) (ACDelco A329C)..... PA2006 Air (1973-on) (ACDelco A348C)..... PA2008 Air (1980-on) (ACDelco A753C)..... PA2091 Air (1988-on) (ACDelco A644C)..... PA2073	20, 30 Series w/Detroit Diesel 3-53 Eng. F-F Lube Ele..... PT11 P. Fuel Sock..... F916-C S. Fuel Ele..... PF906
400 V8 Opt. 2 Qt. Lube Ele..... P476 Lube Spin-on..... B6 + 1 1/32 In. Fuel (Paper) (Carb.)..... PF893 2 1/32 In. Fuel (Paper) (Carb.)..... PF894-RV Fuel (SintBronze) (Carb.)..... SF898 Air (1970)..... PA2006 Air (1971-on) (ACDelco A348C)..... PA2008 Air (1975-on, (Vans)) (ACDelco A178CW)..... PA1680	478, 478M V6 Lube Ele..... P20-HD + Fuel Ele..... PF827 In-Line Fuel..... BF840 + Air (w/Foam Wrap)..... PA1800 Air (w/o Foam Wrap)..... PA1798 +	40 Series w/V8-307 Eng. Lube Ele..... P18 Fuel (SintBronze)..... SF898 Air (6419892)..... PA1680
401, 401M V6 Lube Ele..... P20-HD + Fuel Ele..... PF827 In-Line Fuel..... BF840 + Air (1972-74)..... PA1800	637 V8 Lube..... P20-HD + Fuel Ele..... PF827 Air (2236986)..... PA1800 +	40 Series w/GMC 3-53, 3-53N Diesel Eng. Lube Ele. (1964-65)..... PT11 Lube Ele. (1966-on)..... P20-HD + P. Fuel Sock..... F916-C S. Fuel Ele..... PF906
402 V8 Opt. 2 Qt. Lube Ele..... P476 Lube Spin-on..... B6 + 1 1/32 In. Fuel (Paper) (Carb.)..... PF893 Air..... PA2006	<b>CHEVROLET</b> <b>North America Trucks &amp; Vans</b>	40, 50 Series w/6-230 Eng. Lube Spin-on..... B6 + Fuel (SintBronze)..... SF898 1 1/32 In. Fuel (Paper)..... PF893 Axial Seal Air..... PA658 Heavy Duty Air..... PA1680 Comp. Breather (9028042)..... PA1600
	14-190 w/Cat 3116 Eng. Fuel/Water Separator (Open End for Bowl) (Mann WK1060/1)..... BF46083-O Fuel/Water Separator (w/Bowl) (Mann WK1060/1)..... BF46072 Fuel/Water Separator (w/Drain) (Mann WK1060/1)..... BF1329 Fuel/Water Separator (Sensor Port Thd. 9/16-18) (Mann WK1060/1)..... BF1329-SP	40, 50 Series w/6-250 Eng. Std. Lube Ele. (6437562)..... P476 Opt. Lube Ele. (5573014)..... P20-HD + 4 3/8 In. Lube Spin-on..... B27 5 5/16 In. Lube Spin-on..... B6 + 1 1/32 In. Fuel (Paper)..... PF893 3 15/32 In. Fuel Ele..... PF827 Fuel (SintBronze)..... SF898 Air (1967-74) (6424027)..... PA1841

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

CHEVROLET North America Trucks & Vans (cont'd)	CHEVROLET North America Trucks & Vans (cont'd)	CHEVROLET North America Trucks & Vans (cont'd)
40, 50 Series w/6-250 Eng. (Cont'd)	50 Series w/V8-327 Eng.	60 Series w/V6-379 Eng.
Air (3979576)..... PA648	Lube..... P18	Lube Ele..... P20-HD +
Air (6419892)..... PA1680	Fuel Ele..... PF827	Lube Spin-on..... B39
Comp. Breather (8875051)..... PA1909	Air (1964-66) (6420690)..... PA625	Fuel Ele..... PF827
Comp. Breather (9028042)..... PA1600	Air (1966-68) (6423239)..... PA1798 +	5 9/16 In. Air (2236986)..... PA1800 +
40, 50 Series w/6-261 Eng.	50, 60 Series w/GMC 3-53, 3-53N Diesel Eng. (1962-on)	8 5/16 In. Air (702025)..... PA1922-FN
Lube Ele..... P18	Lube Ele. (Exc. 1964-65)..... P20-HD +	Comp. Breather (1 5/16 In. I.D.) (8875051)..... PA1909
Air..... PA621	Lube Ele. (1964-65)..... PT11	Comp. Breather (1 5/16 In. I.D.) (2467368)..... PA1704
40, 50 Series w/6-292 Eng.	P. Fuel Sock..... F916-C	60 Series w/V6-432 Eng.
Std. Lube Ele. (6437562)..... P476	S. Fuel Ele..... PF906	Lube Ele..... P20-HD +
Opt. Lube Ele. (5573014)..... P20-HD +	50, 60 Series w/GMC 4-53 Diesel Eng.	In-Line Fuel (73103)..... BF836-K4
4 3/8 In. Lube Spin-on..... B27	Lube Ele..... P20-HD +	Air..... PA1800 +
5 5/16 In. Lube Spin-on..... B6 +	P. Fuel Sock..... F916-C	60 Series w/V8 Gas Eng.
1 1/32 In. O.D. Fuel (1963-67)..... PF857	S. Fuel Ele..... PF906	Lube Ele. (1960-66) (5574540)..... P18-HD
3 In. O.D. Fuel (1963-67)..... PF860	Air (2009007)..... PA2465	Lube Ele. (1967-on) (6437562)..... P476
Fuel (1969-77, (Carb.))..... PF893	Air (2014573)..... PA2550	Opt. Lube Ele. (5573014)..... P20-HD +
2 In. O.D. Fuel (1973-78)..... PF827	Air (2031381)..... PA2540 +	1 Qt. Lube Spin-on..... B6 +
Fuel (SintBronze) (Carb.)..... SF898	50, 60 Series w/GMC 6V-53 Diesel Eng.	2 Qt. Lube Spin-on..... B7
Air (1965-66) (6419892)..... PA1680	Lube Ele..... P20-HD +	1 1/32 In. Fuel (Paper) (Carb.)..... PF893
Air (1966-72) (6424027)..... PA1841	P. Fuel Sock..... F916-C	2 1/32 In. Fuel (Paper) (Carb.)..... PF894-RV
Air (1973-78) (3979645)..... PA648	S. Fuel Ele..... PF902	3 15/32 In. Fuel..... PF827
40, 50 Series w/V8-283 Eng.	50, 60 Series w/GMC D351, D478 Diesel Eng.	Fuel (SintBronze) (Carb.)..... SF898
Lube Ele..... P18	F-F Lube Ele..... P20-HD +	Air (w/4WD, Governor) 1964-65 (6422880)..... PA625
Fuel Ele..... PF827	P. Fuel Sock..... F916-C	Heavy Duty Air (1964-65)..... PA1680
Air (1967) (6419892)..... PA1680	S. Fuel Ele..... PF902	Air (1966-on) (6422556)..... PA1800 +
Air (1967) (6420690)..... PA625	60 Series w/6-261 Eng.	Air (1966-on) (6423239)..... PA1798 +
Comp. Breather (9028042)..... PA1600	Lube Ele. (5574540)..... P18-HD	Air (8 5/16 In.) (702025)..... PA1922-FN
40, 50 Series w/V8-350 Eng.	Opt. Lube Ele. (8 7/16 In.) (6437562)..... P476	Comp. Breather Ele. (8875051)..... PA1909
Std. Lube Ele. (6437562)..... P476	Opt. Lube Ele. (9 1/16 In.) (5573014)..... P20-HD +	Comp. Breather Foam (9028042)..... PA1600
Opt. Lube Ele. (5573014)..... P20-HD +	Lube Spin-on (6437946)..... B6 +	60 Series w/GMC DH478 Diesel Eng. (7.8L)
Opt. Lube Ele. (5574540)..... P18-HD	Dry-Type Air..... PA621	F-F Lube Ele..... P20-HD +
Lube Spin-on..... B6 +	60 Series w/6-292 Eng.	5 3/4 In. P. Fuel Sock..... F916-C
1 1/32 In. Fuel..... PF893	Lube Spin-on..... B27	8 5/16 In. P. Fuel Ele..... PF845
2 1/32 In. Fuel..... PF894-RV	1 1/32 In. O.D. Fuel (1963-67)..... PF857	S. Fuel Ele..... PF902
3 15/32 In. Fuel Ele..... PF827	3 In. O.D. Fuel (1963-67)..... PF860	Comp. Breather Ele. (1 5/16 In. I.D.) (8875051)..... PA1909
Air (1969) (6423239)..... PA1798 +	2 In. O.D. Fuel Ele. (1966-78)..... PF827	Comp. Breather Ele. (1 5/8 In. I.D.) (2467368)..... PA1704
Axial Seal Air (1970) (6485108)..... PA2006	1 1/32 In. Fuel (Paper) (Carb.)..... PF893	Comp. Breather Foam (9028042)..... PA1600
Air (6422556)..... PA1800	Fuel (SintBronze) (Carb.)..... SF898	65 Series w/Cat 3208 Eng.
Air (702025)..... PA1922-FN	3 In. Air (3979645)..... PA648	Lube (9L9200)..... [2] BT364
Comp. Breather (8875051)..... PA1909	3 1/8 In. Air (6424027)..... PA1841	Box-Style Fuel/Water Separator..... BF912
Comp. Breather (9028042)..... PA1600	3 9/16 In. Air (6419892)..... PA1680	Fuel Spin-on..... BF970 +
40, 50 Series w/V8-366 Eng.	60 Series w/V6-305C Eng.	Air (2009007)..... PA2465
Std. Lube Ele. (6437562)..... P476	Lube Ele..... P20-HD +	65 Series w/6-379 Eng.
Opt. Lube Ele. (5573014)..... P20-HD +	Lube Spin-on..... B39	Lube Ele..... P20-HD +
Opt. Lube Ele. (5574540)..... P18-HD	In-Line Fuel..... BF840 +	4 3/8 In. Lube Spin-on..... B39
3 15/32 In. Fuel..... PF827	Fuel Ele..... PF827	5 9/32 In. Lube Spin-on..... B9
Fuel (SintBronze) (Carb.)..... SF898	5 9/16 In. Air (2236986)..... PA1800 +	Fuel..... PF827
Axial Seal Air (w/o Foam Wrap)..... PA1798 +	8 5/16 In. Air (702025)..... PA1922-FN	Air..... PA1800 +
Opt. Air (w/Foam Wrap)..... PA1800	Comp. Breather (1 5/16 In. I.D.) (8875051)..... PA1909	
40, 50 Series w/V8-427 Eng.	Comp. Breather (1 5/8 In. I.D.) (2467368)..... PA1704	
Std. Lube Ele. (6437562)..... P476		
Opt. Lube Ele. (5573014)..... P20-HD +		
Opt. Lube Ele. (5574540)..... P18-HD		
1 1/32 In. Fuel (Carb.)..... PF893		
3 15/32 In. Fuel..... PF827		
Axial Seal Air (w/o Foam Wrap)..... PA1798 +		
Opt. Air (w/Foam Wrap)..... PA1800		


+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

CHEVROLET North America Trucks & Vans (cont'd)	CHEVROLET North America Trucks & Vans (cont'd)	CHEVROLET North America Trucks & Vans (cont'd)
65 Series w/6-432 Eng. Lube Ele. .... P20-HD + In-Line Fuel (73103)..... BF836-K4 Air (2236986)..... PA1800 + Air (702025)..... PA1922-FN Comp. Breather (2467368)..... PA1704 Comp. Breather (8875051)..... PA1909	70 Series w/GMC DH478, D637, DH637 Diesel Eng. Lube Ele. .... P20-HD + P. Fuel Ele. .... PF902 Comp. Breather (2467368)..... PA1704 Comp. Breather (8875051)..... PA1909 Trans. Breather (Fuller RT510)... P187	80 Series w/V8-409 Eng. Lube Ele. (5573014)..... P20-HD + 3 15/32 In. Fuel..... PF827 Air..... PA625
65 Series w/V8-366, V-427 Eng. Lube Ele. .... P476 1 Qt. Lube Spin-on..... B6 + 2 Qt. Lube Spin-on..... B7 1 1/32 In. Fuel (Paper) (Carb.)..... PF893 2 1/32 In. Fuel (Paper) (Carb.)..... PF894-RV 3 15/32 In. Fuel Ele. .... PF827 Fuel (SintBronze) (Carb.)..... SF898 Air (2236986)..... PA1800 + Air (699505)..... PA2316 Air (702025)..... PA1922-FN Comp. Breather (8875051)..... PA1909	80 Series w/6 Cyl. Gas Eng. Lube Ele. (5573014)..... P20-HD + 1 1/32 In. Fuel (Paper) (Carb.)..... PF893 2 1/32 In. Fuel (Paper) (Carb.)..... PF894-RV 3 15/32 In. Fuel Ele. .... PF827 In-Line Fuel..... BF840 + Fuel (SintBronze) (Carb.)..... SF898 Air (United 250A28)..... PA1798 + Air (702025)..... PA1922-FN Comp. Breather (2467368)..... PA1704 Comp. Breather (8875051)..... PA1909 Trans. (Allison Powermatic)..... S16-1 Trans. (Allison AT540)..... 19992 +	80 Series w/V8-427 Eng. Lube..... B7 Fuel Ele..... PF827 Air (6422556)..... PA1800 Comp. Breather (8875051)..... PA1909
65 Series w/V8-366 TBI Eng. Lube (ACDelco PF932)..... B7 Fuel (ACDelco GF481)..... BF853 Air (ACDelco A348C)..... PA2008	80 Series w/V8-283 Eng. Lube Ele. (1956-57)..... P19 Lube Spin-on (1956-67)..... B6 + Std. Lube Ele. (1958-67)..... P18 2 Qt. Lube Ele. (1962-67)..... P20-HD + Fuel (1956-57)..... PF857 Fuel (1958-59)..... PF860 Fuel (1960-67)..... PF827 Air (1964-67)..... PA625	80 Series w/Detroit Diesel 6V-53 Eng. F-F Lube Ele. .... P20-HD + B-P Lube Ele. .... C750-E + 5 3/4 In. P. Fuel Sock..... F916-C 8 5/16 In. P. Fuel Ele. .... PF845 S. Fuel Ele. .... PF902 P. Fuel Spin-on..... BF5800 + S. Fuel Spin-on..... BF5810 Comp. Breather (2467368)..... PA1704 Comp. Breather (8875051)..... PA1909 Comp. Breather (9028042)..... PA1600 Coolant Spin-on (Maintenance).. BW5137 Coolant Spin-on (Pre-Charge).... BW5139
65 Series w/Detroit Diesel 4-53, 4-53T Eng. F-F Lube Ele. .... P20-HD + P. Fuel Sock..... F916-C S. Fuel Ele. .... PF902 Air (2009007)..... PA2465 Air (2014573)..... PA2550 Air (2031381)..... PA2540 +	80 Series w/V8-307 Eng. Lube Ele. .... P18 Lube Spin-on..... B6 + Fuel..... SF898 Axial Seal Air..... PA1680 11 13/16 In. O.D. Air..... PA2006	90 Series w/Cat 3406 Eng. F-F Lube Spin-on..... B99 + B-P Lube Ele. .... C750-E + Fuel Spin-on..... BF614 + Std. Air (700016)..... PA1846 + Air (Upgrade) (700016)..... PA1846XP
70 Series w/V6-401M, 478M Eng. Lube..... P20-HD + Fuel Ele..... PF827 In-Line Fuel..... BF840 + Air (2236986)..... PA1800 + Comp. Breather (1 5/16 In. I.D.) (8875051)..... PA1909 Comp. Breather (1 5/8 In. I.D.) (2467368)..... PA1704 Trans. (Allison Powermatic)..... S16-1 Trans. (Allison AT540)..... 19992 +	80 Series w/V8-327 Eng. Lube Ele. (1967)..... P476 Std. Lube Ele. (1962-66)..... P18 Opt. 2 Qt. Lube Ele. (1962-66).... P20-HD + Lube Spin-on..... B6 + Fuel (1962-67)..... PF827 Dry-Type Air (1964-65)..... PA625 Air (1966-67)..... PA1798 +	90 Series w/Cummins Eng. F-F Lube Bag..... P996 F-F Lube Ele. .... P999-HD F-F Lube Spin-on..... B196 + B-P Lube Ele. .... C750-E + Fuel/Water Separator..... BF1212 + 4 3/8 In. Fuel Spin-on..... BF948 + 5 3/4 In. Fuel Spin-on..... BF957 + 11 7/32 In. Fuel Spin-on..... BF596 + Std. O. Air (Don. P106632)..... PA1846 + O. Air (Upgrade) (Don. P106632). PA1846XP I. Air (Don. P106641)..... PA1880 Air (2017021)..... PA2503 Air (699505)..... PA2316 Air (706193)..... PA2468 <sup>90</sup> Single-Stage Air (Don. P111511)..... PA1892-FN <sup>90</sup> Breather (w/Turbo) (255963)..... PA643 Breather Ele. (w/o Turbo) (256837)..... PA1627 Trans. Breather Ele. (Fuller)..... P187 Coolant Spin-on..... BW5137 Turbocharger..... BT112
70 Series w/GMC 6V-53 Diesel Eng. F-F Lube Ele. .... P20-HD + B-P Lube Ele. .... C750-E + 5 3/4 In. P. Fuel Sock..... F916-C 8 5/16 In. P. Fuel Ele. .... PF845 7 13/16 In. S. Fuel Ele. .... PF902 P. Fuel Spin-on..... BF5800 + S. Fuel Spin-on..... BF5810 Comp. Breather Ele. (1 5/16 In. I.D.) (8875051)..... PA1909 Comp. Breather Ele. (1 5/8 In. I.D.) (2467368)..... PA1704 Comp. Breather Foam (9028042)..... PA1600 Coolant Spin-on (Maintenance).. BW5137 Coolant Spin-on (Pre-Charge).... BW5139 Trans. (Allison Powermatic)..... S16-1	80 Series w/V8-348 Eng. Std. Lube Ele. (1958-65)..... P18 Opt. 2 Qt. Lube Ele. (1962-65).... P20-HD + Fuel (1958-59)..... PF860 Fuel (1960-65)..... PF827 Air (1964-65)..... PA625	90 Series w/Detroit Diesel 6V-92, 8V-92 Series Eng. F-F Lube Ele. .... P20-HD + B-P Lube Ele. .... C750-E + P. Fuel Ele. .... PF845 S. Fuel Ele. .... PF902 P. Fuel Spin-on..... BF5800 +

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



CHEVROLET North America Trucks & Vans (cont'd)	CHEVROLET North America Trucks & Vans (cont'd)	CHEVROLET North America Trucks & Vans (cont'd)
90 Series w/Detroit Diesel 6V-92, 8V-92 Series Eng. (Cont'd) <b>S. Fuel Spin-on</b> ..... BF5810 <b>Air</b> (2010760)..... PA2500 + <b>Air</b> (2014558)..... PA3951 <b>Air</b> (2017021)..... PA2503 <b>Air</b> (2034764)..... PA2532 <b>Std. Air</b> (700016)..... PA1846 + <b>Air</b> (Upgrade) (700016)..... PA1846XP <b>Coolant Spin-on</b> (Maintenance).. BW5137 <b>Coolant Spin-on</b> (Pre-Charge).... BW5139	1000, 3000, 4000, 5000 Series w/6-216, 6-235 Eng. <b>Lube Ele.</b> (ACDelco P115)..... P53 <b>Lube Ele.</b> (ACDelco P117)..... P52 1000, 3000, 4000, 5000, 6000, 7000, 8000 Series w/V8-265 Eng. <b>Lube Ele.</b> (1955) (ACDelco S2).... P52 <b>Lube Ele.</b> (1955) (ACDelco S6).... P53 <b>Lube Ele.</b> (1956-57)..... P19 <b>Lube Spin-on</b> ..... B6 + <b>Fuel</b> (1956-57)..... PF857 1000, 3000, 4000, 5000, 6000, 7000, 8000, 9000, 10000 Series w/V8-283 Eng. <b>Lube Ele.</b> (1956-57)..... P19 <b>Std. Lube Ele.</b> (1958-59)..... P18 <b>Lube Spin-on</b> ..... B6 + <b>Fuel</b> (1956-57)..... PF857 <b>Fuel Ele.</b> (1958-59)..... PF860 <b>Fuel</b> (1959, (SintBronze) (Carb.)) ..... SF898 1500, 2500, 3500 Series w/V6-262 (4.3L) Eng. <b>Lube</b> ..... B35-S + <b>Fuel</b> ..... BF853 <b>Air</b> ..... PA1680 1500, 2500, 3500 Series w/V8-305 (5.0L) Eng. <b>Lube</b> (2WD)..... B6 + <b>Lube</b> (4WD)..... B35-S + <b>Fuel</b> ..... BF853 <b>Air</b> ..... PA2008 1500, 2500, 3500 Series w/V8-350 (5.7L) Eng. <b>Lube</b> (2WD)..... B6 + <b>Lube</b> (4WD)..... B35-S + <b>Fuel</b> ..... BF853 <b>Air</b> ..... PA2008 1500, 2500, 3500 Series w/V8-379 (6.2L) Diesel Eng. <b>Lube</b> (1986-on)..... B1428 + <b>Lube</b> (To 1986)..... B6 + <b>Box-Style Fuel</b> ..... BF856 <b>Air</b> ..... PA2073 1500, 2500, 3500 Series w/V8-454 (7.4L) Eng. <b>Lube</b> (To 1986)..... B6 + <b>Lube</b> (1986-on)..... B1428 + <b>Fuel</b> ..... BF853 <b>Air</b> ..... PA2008 6000 Series w/6-235 Eng. <b>Lube Ele.</b> (ACDelco P115)..... P53 <b>Lube Ele.</b> (ACDelco P117)..... P52 6000 Series w/6-261 Eng. <b>Lube</b> (1950-58) (ACDelco P115).. P53 <b>Lube</b> (1950-58) (ACDelco P117).. P52 <b>Lube</b> (1959)..... P18 7000 Series w/GMC D637, DH637 Diesel Eng. <b>Lube Ele.</b> ..... P20-HD + <b>Fuel Ele.</b> ..... PF902	7000, 8000 Series w/V6-401, V6-478 Eng. <b>Lube Ele.</b> ..... P20-HD + <b>3 15/32 In. Fuel</b> ..... PF827 8000, 9000, 10000 Series w/V8-348 Eng. <b>Std. Lube Ele.</b> (1958-65)..... P18 <b>Opt. 2 Qt. Lube Ele.</b> (1962-65).... P20-HD + <b>Fuel</b> (1958-59)..... PF860 <b>Std. Fuel</b> (1960-65)..... PF827 <b>Air</b> (1964-65)..... PA625 9000, 10000, 10800 Series w/V8-322 Eng. <b>Lube</b> ..... P25 <b>Fuel</b> ..... PF857 9005 Series w/Cummins NTC290, NTC350 Eng. <b>F-F Lube Ele.</b> ..... P999-HD <b>F-F Lube Spin-on</b> ..... B196 + <b>B-P Lube Ele.</b> ..... C750-E + <b>Fuel Spin-on</b> ..... PF857 <b>Fuel Spin-on</b> ..... BF957 + <b>Air</b> (Don. P124490)..... PA2515 <b>Air</b> (Don. P126442)..... PA2516 9005, 9006 Series w/Detroit Diesel 6-71, 6V-92, 8V-71, 8V-92 Series Eng. <b>F-F Lube Ele.</b> ..... P20-HD + <b>B-P Lube Ele.</b> ..... C750-E + <b>P. Fuel Ele.</b> ..... PF845 <b>S. Fuel Ele.</b> ..... PF902 <b>P. Fuel Spin-on</b> ..... BF5800 + <b>S. Fuel Spin-on</b> ..... BF5810 <b>Air</b> (Farr C45800)..... PA2350 <b>Air</b> (Don. P124490)..... PA2515 <b>Air</b> (Don. P126442)..... PA2516 <b>Coolant Spin-on</b> ..... BW5137 B7 w/Cat 3116 (6.6L) Eng. <b>F-F Lube</b> (8N9586)..... BT230 + <b>B-P Lube Ele.</b> (15525633)..... C750-E + <b>Fuel/Water Separator</b> (12542374)..... BF1266 <b>Fuel</b> (ACDelco TP936)..... BF592 + <b>Std. Air</b> (6487958)..... PA2008 <b>Radial Seal O. Air</b> (15619013).... RS2863 <b>Radial Seal O. XP Air</b> (15619013)..... RS2863XP <b>Radial Seal I. Air</b> (12544543)..... RS3501 <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... 20004 <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... 20016 <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... 20003 <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... 20017 <b>Trans. Spin-on</b> (Allison 29539579)..... BT8460 B7 w/Cat 3126 (7.2L) Eng. <b>Lube</b> (Standard Vers.) (1R0739).. B76 + <b>Lube</b> (Severe Service) (1R0739).. B76-S + <b>Fuel/Water Separator</b> (w/Drain) (Racor S3212)..... BF1266

+ See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

CHEVROLET North America Trucks & Vans (cont'd)	CHEVROLET North America Trucks & Vans (cont'd)	CHEVROLET North America Trucks & Vans (cont'd)
B7 w/Cat 3126 (7.2L) Eng. (Cont'd) Fuel/Water Separator (Open End for Bowl) (Racor S3212)..... <b>BF1278-O</b> Fuel (ACDelco TP936)..... <b>BF592 +</b> Radial Seal O. Air (15696245).... <b>RS2863</b> Radial Seal XP O. Air (15696245)..... <b>RS2863XP</b> Radial Seal I. Air (12544543)..... <b>RS3501</b> Trans. (ACDelco PF897)..... <b>BT230</b>	B60 w/V8-350 (5.7L) Eng. 1 Qt. Lube..... <b>B6 +</b> 2 Qt. Lube..... <b>B7</b> 1 1/32 In. Fuel Ele..... <b>PF893</b> 3 15/32 In. Fuel Ele..... <b>PF827</b> Air (6422556)..... <b>PA1800</b> Comp. Air..... <b>PA1909</b> Trans. (Allison AT540)..... <b>19992 +</b>	Bruin w/Detroit Diesel 6-71N, 6-71T Eng. (1980) F-F Lube Ele..... <b>P20-HD +</b> B-P Lube Ele..... <b>C750-E +</b> P. Fuel Spin-on..... <b>BF5800 +</b> S. Fuel Spin-on..... <b>BF5810</b> Air (2017021)..... <b>PA2503</b> Air (2052116)..... <b>PA2482</b> Comp. Air (Midland 100696A)..... <b>PA1909</b> Comp. Air (Bendix 239292)..... <b>PA1600</b> Coolant..... <b>BW5137</b>
B7 w/V8-366 (6.0L) Eng. F-F Lube (8N9586)..... <b>BT230 +</b> Fuel In-Line (25171792)..... <b>BF853</b> Std. Air (6487958)..... <b>PA2008</b> Trans. Pan-Type (AT Series, 3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> Trans. Pan-Type (AT Series, 5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> Trans. Spin-on (AT Series) (Allison 29510922)..... <b>BT8316-MPG</b>	B60 w/V8-427 (7.0L) Eng. Lube..... <b>B7</b> Fuel Ele..... <b>PF827</b> Comp. Air..... <b>PA1909</b> Trans. (Allison AT540)..... <b>19992 +</b>	Bruin w/Detroit Diesel 6-71N, 6-71T Eng. (1981) F-F Lube Ele..... <b>P20-HD +</b> B-P Lube Ele..... <b>C750-E +</b> P. Fuel Spin-on..... <b>BF5800 +</b> S. Fuel Spin-on..... <b>BF5810</b> Comp. Air (Midland 100696A)..... <b>PA1909</b> Comp. Air (Bendix 239292)..... <b>PA1600</b> Coolant..... <b>BW5137</b>
B7 w/V8-395 (6.5L) Turbo Diesel Eng. Lube (25013454)..... <b>B6-HPG +</b> Fuel/Water Separator (ACDelco TP1263)..... <b>BF7674-D</b> Std. Air (6487958)..... <b>PA2008</b> Radial Seal O. Air (15619013).... <b>RS2863</b> Radial Seal O. XP Air (15619013)..... <b>RS2863XP</b> Radial Seal I. Air (12544543)..... <b>RS3501</b>	B60 w/V8-366 (6.0L) Eng. Lube..... <b>B7</b> Fuel Ele..... <b>PF827</b> Comp. Air..... <b>PA1909</b> Trans. (Allison AT540)..... <b>19992 +</b>	Bruin w/Detroit Diesel 6V-92 Series, 8V-71N Eng. (1979) F-F Lube Ele..... <b>P20-HD +</b> B-P Lube Ele..... <b>C750-E +</b> P. Fuel Spin-on..... <b>BF5800 +</b> S. Fuel Spin-on..... <b>BF5810</b> Air (2034764)..... <b>PA2532</b> Comp. Air (Midland 100696A)..... <b>PA1909</b> Coolant..... <b>BW5137</b>
B7 w/V8-427 (7.0L) Eng. F-F Lube (ACDelco PF897F)..... <b>BT230 +</b> Fuel Ele. (5651879)..... <b>PF827</b> Std. Air (6487958)..... <b>PA2008</b> Trans. Pan-Type (AT Series, 3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> Trans. Pan-Type (AT Series, 5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> Trans. Spin-on (AT Series) (Allison 29510922)..... <b>BT8316-MPG</b>	B60 w/Cummins N14 (14.0L) Eng. F-F Lube (Fleetguard LF670SC).. <b>B196 +</b> Dual-Flow Lube (3318853)..... <b>BD103 +</b> B-P Lube (3304232)..... <b>BF577</b> Fuel/Water Separator (3308638). <b>BF1212 +</b> Fuel (154789)..... <b>BF957-D +</b> Coolant (3315116)..... <b>BW5071</b>	Bruin w/Detroit Diesel 6V-92 Series, 8V-71N Eng. (1980) F-F Lube Ele..... <b>P20-HD +</b> B-P Lube Ele..... <b>C750-E +</b> P. Fuel Spin-on..... <b>BF5800 +</b> S. Fuel Spin-on..... <b>BF5810</b> Conical Air (2014558)..... <b>PA3951</b> Air (2017021)..... <b>PA2503</b> Comp. Air (Midland 100696A)..... <b>PA1909</b> Coolant..... <b>BW5137</b>
B7 w/V8-454 (7.4L) Eng. 3 3/16 In. Lube (ACDelco PF454)..... <b>B1438</b> 5 11/32 In. Lube (ACDelco PF1218)..... <b>B1428 +</b> Fuel (ACDelco GF481)..... <b>BF853</b> Std. Air (6484235)..... <b>PA2008</b> Radial Seal Air (ACDelco A1301C)..... <b>RS3706</b> Trans. (ACDelco PF897)..... <b>BT230</b>	B60 w/Detroit Diesel 8.2L Eng. Lube..... <b>[2] B6 +</b> P. Fuel Spin-on..... <b>BF592 +</b> S. Fuel Spin-on..... <b>BF593</b> Comp. Air..... <b>PA1909</b> Trans. (Allison AT540)..... <b>19992 +</b>	Bruin w/Detroit Diesel 6V-92 Series, 8V-71N Eng. (1981) F-F Lube Ele..... <b>P20-HD +</b> B-P Lube Ele..... <b>C750-E +</b> P. Fuel Spin-on..... <b>BF5800 +</b> S. Fuel Spin-on..... <b>BF5810</b> Comp. Air (Midland 100696A)..... <b>PA1909</b> Coolant..... <b>BW5137</b>
B7 w/V8-496 (8.1L) Eng. 3 3/16 In. Lube (ACDelco PF454)..... <b>B1438</b> 5 11/32 In. Lube (ACDelco PF1218)..... <b>B1428 +</b> Fuel (ACDelco GF481)..... <b>BF853</b> Std. Air (6484235)..... <b>PA2008</b> Radial Seal Air (ACDelco A1301C)..... <b>RS3706 +</b> Trans. (ACDelco PF897)..... <b>BT230</b>	Bruin w/V8-427 Eng. Lube..... <b>B7</b> Fuel Ele..... <b>PF827</b> Air (6422556)..... <b>PA1800</b> Comp. Air (Midland 100696A)..... <b>PA1909</b>	Bruin w/Detroit Diesel 6V-92 Series, 8V-71N Eng. (1981) F-F Lube Ele..... <b>P20-HD +</b> B-P Lube Ele..... <b>C750-E +</b> P. Fuel Spin-on..... <b>BF5800 +</b> S. Fuel Spin-on..... <b>BF5810</b> Comp. Air (Midland 100696A)..... <b>PA1909</b> Coolant..... <b>BW5137</b>
	Bruin w/Cat 3208 Eng. F-F Lube (9L9200)..... <b>[2] BT364</b> F-F Lube (9N5570)..... <b>[2] BT230</b> B-P Lube Ele..... <b>C750-E +</b> Box-Style Fuel/Water Separator. <b>BF912</b> Fuel Spin-on..... <b>BF970 +</b> Air (2009007)..... <b>PA2465</b> Comp. Air..... <b>PA1909</b>	Bruin w/Detroit Diesel 6V-53 Series Eng. F-F Lube Ele..... <b>P20-HD +</b> P. Fuel Spin-on..... <b>BF5800 +</b> S. Fuel Spin-on..... <b>BF5810</b> Air (2052116)..... <b>PA2482</b> Comp. Air..... <b>PA1909</b>
	Bruin w/Detroit Diesel 6-71N, 6-71T Eng. (1979) F-F Lube Ele..... <b>P20-HD +</b> B-P Lube Ele..... <b>C750-E +</b> P. Fuel Spin-on..... <b>BF5800 +</b> S. Fuel Spin-on..... <b>BF5810</b> Air (2034763)..... <b>PA2531</b> Air (2034764)..... <b>PA2532</b> Comp. Air (Midland 100696A)..... <b>PA1909</b> Comp. Air (Bendix 239292)..... <b>PA1600</b> Coolant..... <b>BW5137</b>	Bruin w/Cummins NTC290, NTC350 Eng. (1979) F-F Lube Ele..... <b>P999-HD</b> F-F Lube Spin-on..... <b>B196 +</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

CHEVROLET North America Trucks & Vans (cont'd)	CHEVROLET North America Trucks & Vans (cont'd)	CHEVROLET North America Trucks & Vans (cont'd)
Bruin w/Cummins NTC290, NTC350 Engs. (1979) (Cont'd)	C60 w/6-292 (4.8L) Eng. (Cont'd)	C60 Kodiak w/V8-427 (7.0L) Eng.
B-P Lube Ele..... C750-E +	Fuel (SintBronze) (Carb.)..... SF898	Lube..... B7
Fuel Spin-on..... BF957 +	3 In. Air (3979645)..... PA648	Fuel Ele..... PF827
Air (2034764)..... PA2532	3 1/8 In. Air (6424027)..... PA1841	Comp. Air..... PA1909
Comp. Air..... PA1909	3 9/16 In. Air (6419892)..... PA1680	Air (Ele. w/Foam Wrap) (6422556)..... PA1800
Bruin w/Cummins NTC290, NTC350 Engs. (1980)	C60 w/V8-350 (5.7L) Eng.	Air (Ele. w/Fins) (702025)..... PA1922-FN
F-F Lube Ele..... P999-HD	1 Qt. Lube..... B6 +	C60 Kodiak w/V8-366 (6.0L) Eng.
F-F Lube Spin-on..... B196 +	2 Qt. Lube..... B7	Lube..... B7
B-P Lube Ele..... C750-E +	1 1/32 In. Fuel (Rochester Carb.)..... PF893	Fuel Ele..... PF827
Fuel Spin-on..... BF957 +	3 15/32 In. Fuel Ele..... PF827	Comp. Air..... PA1909
Air (2017021)..... PA2503	Air (6422556)..... PA1800	Air (Ele. w/Foam Wrap) (6422556)..... PA1800
Comp. Air..... PA1909	Comp. Air..... PA1909	Air (Ele. w/Fins) (702025)..... PA1922-FN
Bruin w/Cummins NTC290, NTC350 Engs. (1981)	Trans. (Allison AT540)..... 19992 +	C60 Kodiak w/Cat 3116 (6.6L) Eng.
F-F Lube Ele..... P999-HD	C60 w/V8-366 (6.0L) Eng.	Lube (Standard Vers.) (1R0739).. B76 +
F-F Lube Spin-on..... B196 +	Lube..... B7	Lube (Severe Service) (1R0739).. B76-SS +
B-P Lube Ele..... C750-E +	Fuel Ele..... PF827	Fuel Spin-on (1R0740)..... BF970 +
Fuel Spin-on..... BF957 +	Comp. Air..... PA1909	C-65 w/V8 5.9L Eng. Mexico (1987)
Comp. Air..... PA1909	Air (Ele. w/Foam Wrap) (6422556)..... PA1800	Air (ACDelco A348C)..... PA2008
Bruin w/Cummins NTC300 Eng.	Air (Ele. w/Fins) (702025)..... PA1922-FN	Turbocharger (ACDelco PF25).... B27
F-F Lube Spin-on..... B196 +	C60 w/V8-427 (7.0L) Eng.	C70 w/Cat 3208 (10.4L) Eng.
B-P Lube Ele..... C750-E +	Lube..... B7	Lube (9L9200)..... [2] BT364
Fuel Spin-on..... BF957 +	Fuel Ele..... PF827	Lube (9N5570)..... [2] BT230 +
Air (2017021)..... PA2503	Comp. Air..... PA1909	Box-Style Fuel/Water Separator..... BF912
Comp. Air..... PA1909	Air (Ele. w/Foam Wrap) (6422556)..... PA1800	Fuel Spin-on..... BF970 +
C50 w/6-292 (4.8L) Eng.	Air (Ele. w/Fins) (702025)..... PA1922-FN	C70 w/Cummins N14 (14.0L) Eng.
Lube..... B6 +	C60 w/Cat 3208 (10.4L) Eng.	F-F Lube (Fleetguard LF670SC).. B196 +
1 1/32 In. Fuel (Rochester Carb.)..... PF893	Lube (9L9200)..... [2] BT364	Dual-Flow Lube (3318853)..... BD103 +
3 15/32 In. Fuel Ele..... PF827	Lube (9N5570)..... [2] BT230 +	B-P Lube (3304232)..... B7577
Air (United 250A35WR)..... PA648	Box-Style Fuel/Water Separator..... BF912	Fuel/Water Separator (3308638)..... BF1212 +
C50 w/V8-350 (5.7L) Eng.	Fuel Spin-on..... BF970 +	Fuel (154789)..... BF957-D +
1 Qt. Lube..... B6 +	C60 w/Cummins N14 (14.0L) Eng.	Coolant (3315116)..... BW5071
2 Qt. Lube..... B7	F-F Lube (Fleetguard LF670SC).. B196 +	C70 w/Cummins VT225 (9.1L) Eng.
1 1/32 In. Fuel (Rochester Carb.)..... PF893	Dual-Flow Lube (3318853)..... BD103 +	F-F Lube (3313281)..... B205 +
3 15/32 In. Fuel Ele..... PF827	B-P Lube (3304232)..... B7577	B-P Lube (3304232)..... B7577
Air (6422556)..... PA1800	Fuel/Water Separator (3308638)..... BF1212 +	Fuel (158172)..... BF957 +
Comp. Air..... PA1909	Fuel (154789)..... BF957-D +	O. Air (ACDelco A863C)..... PA2520
Trans. (Allison AT540)..... 19992 +	Coolant (3315116)..... BW5071	I. Air (ACDelco A1009C)..... PA2586
C50 w/Detroit Diesel 8.2L Naturally Aspirated Eng.	C60 w/Detroit Diesel 8.2L Eng.	Coolant (3315116)..... BW5071
Lube..... [2] B6 +	Lube..... [2] B6 +	C70 w/Detroit Diesel 8.2L Eng.
P. Fuel..... BF592 +	P. Fuel Spin-on..... BF592 +	Lube..... [2] B6 +
S. Fuel..... BF593	S. Fuel Spin-on..... BF593	P. Fuel Spin-on..... BF592 +
Air (2062063)..... PA2596	Air (2062063)..... PA2596	S. Fuel Spin-on..... BF593
C50 w/Detroit Diesel 8.2L Turbocharged Eng.	Comp. Air..... PA1909	Air (6 23/32 In. I.D.) (2062062)..... PA2599
Lube..... [2] B6 +	Trans. (Allison AT540)..... 19992 +	Air (8 11/16 In. I.D.) (2062063)..... PA2596
P. Fuel..... BF592 +	C60 w/Deutz BF6L913 (6.1L) Eng.	Comp. Air..... PA1909
S. Fuel..... BF593	F-F Lube (1174420)..... B218	Trans. (Allison AT540)..... 19992 +
Air (2062062)..... PA2599	F-F Lube (1174418)..... BT292	C70 w/Deutz BF6L913 (6.1L) Eng.
C60 w/6-292 (4.8L) Eng.	Fuel Ele. (Wire Mesh Media) (1340114)..... BF7866	F-F Lube (1174420)..... B218
Lube Spin-on..... B27	P. Fuel Spin-on (11819117)..... BF988 +	F-F Lube (1174418)..... BT292
1 1/32 In. O.D. Fuel..... PF857	P. Fuel Spin-on (1174423)..... BF7931	Fuel Ele. (Wire Mesh Media) (1340114)..... BF7866
3 In. O.D. Fuel..... PF860	S. Fuel Spin-on (1174482)..... BF587-D +	P. Fuel Spin-on (11819117)..... BF988 +
2 In. O.D. Fuel Ele..... PF827		P. Fuel Spin-on (1174423)..... BF7931
1 1/32 In. Fuel (Paper) (Carb.)..... PF893		S. Fuel Spin-on (1174482)..... BF587-D +
		O. Air (ACDelco A863C)..... PA2520


+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

CHEVROLET North America Trucks & Vans (cont'd)	CHEVROLET North America Trucks & Vans (cont'd)	CHEVROLET North America Trucks & Vans (cont'd)
C70 w/Deutz BF6L913 (6.1L) Eng. (Cont'd) I. Air (ACDelco A1009C)..... <b>PA2586</b>	C3500HD w/V8-395 (6.5L) Turbo Diesel Eng. (VIN F) <b>Lube</b> (ACDelco PF1218)..... <b>B1428</b> + <b>Fuel/Water Separator</b> (ACDelco TP1256)..... <b>BF1201</b> <b>In-Line Fuel</b> (12339208)..... <b>BF46007</b> <b>Radial Seal Air</b> (Std. (1997-2002)) (ACDelco A1300C).. <b>RS3707</b> <b>Radial Seal Air</b> (w/Foam (1997-2002)) (ACDelco A1306C).. <b>RS3735</b> 90 <b>Panel Air</b> (1992-96) (ACDelco A1236C)..... <b>PA2232</b> <b>Trans.</b> (1997-2002) (24210956)... <b>18027</b> <b>Trans.</b> (1992-96) (8684221)..... <b>18007</b>	C4500 Kodiak w/6.6L Duramax Turbo Diesel Eng. <b>Lube</b> (ACDelco PF2232)..... <b>B1441</b> <b>Fuel/Water Separator</b> (Upgrade) (ACDelco TP3018)..... <b>BF46062</b> 89 <b>Fuel</b> (19256348)..... <b>BF9918 KIT</b> <b>Radial Seal Air</b> (88937527)..... <b>RS4859</b> <b>Panel Air</b> (ACDelco A3102C)..... <b>PA5428</b> <b>Channel Flow Air</b> (15102546)..... <b>CA5370</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Steering</b> (88892858)..... <b>P106-HD</b>
C70 w/V8-366 (6.0L) Eng. <b>Lube</b> ..... <b>B7</b> <b>Fuel Ele.</b> ..... <b>PF827</b> <b>Comp. Air</b> ..... <b>PA1909</b> <b>Air</b> (Ele. w/Foam Wrap) (6422556)..... <b>PA1800</b> <b>Air</b> (Ele. w/Fins) (702025)..... <b>PA1922-FN</b>	C3500HD w/V8-454 (7.4L) FI Eng. (VIN N) (1991-95) <b>Lube</b> (25160561)..... <b>B1428</b> + <b>In-Line Fuel</b> (25171792)..... <b>BF853</b> <b>Air</b> (6484235)..... <b>PA2008</b> <b>Trans.</b> (8684221)..... <b>18007</b>	C4500 Kodiak w/8.1L Eng. (2003-04) <b>Lube</b> (ACDelco PF454)..... <b>B1438</b> <b>Fuel</b> (ACDelco GF652)..... <b>BF853</b> <b>Air</b> (25313349)..... <b>PA4113</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Steering</b> (88892858)..... <b>P106-HD</b>
C70 w/V8-427 (7.0L) Eng. <b>Lube</b> ..... <b>B7</b> <b>Fuel Ele.</b> ..... <b>PF827</b> <b>In-Line Fuel</b> (25171792)..... <b>BF853</b> <b>Comp. Air</b> ..... <b>PA1909</b> <b>Air</b> (Ele. w/Foam Wrap) (6422556)..... <b>PA1800</b> <b>Air</b> (Ele. w/Fins) (702025)..... <b>PA1922-FN</b>	C3500HD w/V8-454 (7.4L) FI Eng. (VIN J) (1996) <b>Lube</b> (25160561)..... <b>B1428</b> + <b>In-Line Fuel</b> (25171792)..... <b>BF853</b> <b>Radial Seal Air</b> (Std.) (25168081) <b>RS3707</b> <b>Radial Seal Air</b> (w/Foam) (25173426)..... <b>RS3735</b> 90 <b>Radial Seal Air</b> (Heavy Duty) (25168082)..... <b>RS3706</b> <b>Trans.</b> (8684221)..... <b>18007</b>	C4500 Kodiak w/8.1L Eng. (2005) <b>Lube</b> (ACDelco PF454)..... <b>B1438</b> <b>Fuel</b> (ACDelco GF652)..... <b>BF853</b> <b>Radial Seal Air</b> (88937527)..... <b>RS4859</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Steering</b> (88892858)..... <b>P106-HD</b>
C70 w/V8-454 (7.4L) Eng. <b>Lube</b> ..... <b>B7</b> <b>Fuel Ele.</b> ..... <b>PF827</b> <b>Air</b> (702025)..... <b>PA1922-FN</b> <b>Comp. Air</b> ..... <b>PA1909</b>	C3500HD w/V8-454 (7.4L) FI Eng. (VIN J) (1997-5/10/1999) <b>Lube</b> (25160561)..... <b>B1428</b> + <b>In-Line Fuel</b> (25171792)..... <b>BF853</b> <b>Radial Seal Air</b> (Std.) (25168081) <b>RS3707</b> <b>Radial Seal Air</b> (w/Foam) (25173426)..... <b>RS3735</b> 90 <b>Radial Seal Air</b> (Heavy Duty) (25168082)..... <b>RS3706</b> <b>Trans.</b> (24208847)..... <b>18027</b>	C4500 Kodiak w/8.1L Eng. (2006-on) <b>Lube</b> (ACDelco PF454)..... <b>B1438</b> <b>Radial Seal Air</b> (88937527)..... <b>RS4859</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
C70 Kodiak w/V8-366 (6.0L) Eng. <b>Lube</b> ..... <b>B7</b> <b>Fuel Ele.</b> ..... <b>PF827</b> <b>Comp. Air</b> ..... <b>PA1909</b> <b>Air</b> (Ele. w/Foam Wrap) (6422556)..... <b>PA1800</b> <b>Air</b> (Ele. w/Fins) (702025)..... <b>PA1922-FN</b>	C3500HD w/V8-454 (7.4L) FI Eng. (VIN J) (5/10/99-2000) <b>Lube</b> (25324052)..... <b>B1438</b> <b>In-Line Fuel</b> (25171792)..... <b>BF853</b> <b>Radial Seal Air</b> (Std.) (25168081) <b>RS3707</b> <b>Radial Seal Air</b> (w/Foam) (25173426)..... <b>RS3735</b> 90 <b>Radial Seal Air</b> (Heavy Duty) (25168082)..... <b>RS3706</b> <b>Trans.</b> (24208847)..... <b>18027</b>	
C70 Kodiak w/V8-427 (7.0L) Eng. <b>Lube</b> ..... <b>B7</b> <b>Fuel Ele.</b> ..... <b>PF827</b> <b>Comp. Air</b> ..... <b>PA1909</b> <b>Air</b> (Ele. w/Foam Wrap) (6422556)..... <b>PA1800</b> <b>Air</b> (Ele. w/Fins) (702025)..... <b>PA1922-FN</b>	C3500HD w/V8-496 (8.1L) FI Eng. (VIN G) <b>Lube</b> (ACDelco PF454)..... <b>B1438</b> <b>In-Line Fuel</b> (ACDelco GF652).... <b>BF853</b> <b>Radial Seal Air</b> (Std.) (ACDelco A1300C)..... <b>RS3707</b> <b>Radial Seal Air</b> (w/Foam) (ACDelco A1306C)..... <b>RS3735</b> 90 <b>Trans.</b> (24210956)..... <b>18027</b>	
C70 Kodiak w/Cat 3116 (6.6L) Eng. <b>Lube</b> (Standard Vers.)..... <b>B76</b> <b>Lube</b> (High Efficiency Vers.) (1R-1807)..... <b>B7700</b> + <b>Box-Style Fuel/Water Separator.</b> <b>BF912</b> <b>Fuel Spin-on</b> (1P2299)..... <b>BF970</b> + <b>Fuel Spin-on</b> (1R-0750)..... <b>BF7633</b> + <b>Radial Seal O. Air</b> (15619013)..... <b>RS2863</b> <b>Radial Seal XP O. Air</b> (15619013)..... <b>RS2863XP</b> <b>Radial Seal I. Air</b> ..... <b>RS3501</b>		

+ See Product Guide for Variations of This Number. 89 Inner Fender Liner Removal Recommended for Proper Installation. 90 Obsolete Pending. Check Original Equipment Numbers In Parentheses.



CHEVROLET North America Trucks & Vans (cont'd)	CHEVROLET North America Trucks & Vans (cont'd)	CHEVROLET North America Trucks & Vans (cont'd)
C4500 Kodiak w/8.1L Eng. (2006-on) (Cont'd)	C6500 Kodiak w/Cat C7 (7.2L) Eng. (To 1/2004)	C6500 Kodiak w/Cat 3116 (6.6L) Eng. (Cont'd)
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Lube</b> (Standard Vers.) (1R0739).. <b>B76 +</b>	<b>Radial Seal O. XP Air</b> (15619013)..... <b>RS2863XP</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Lube</b> (Severe Service) (1R0739).. <b>B76-SS +</b>	<b>Radial Seal I. Air</b> (12544543)..... <b>RS3501</b>
<b>Steering</b> (88892858)..... <b>P106-HD</b>	<b>Fuel/Water Separator</b> (ACDelco TP1519)..... <b>BF7759</b>	<b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b>
C5500 Kodiak w/6.6L Turbo Diesel Eng.	<b>Fuel</b> (1-12 Thd.) (ACDelco TP915D)..... <b>BF5800 +</b>	C6500 Kodiak w/Cat 3126 (7.2L) Eng. (To 1/2004)
<b>Lube</b> (ACDelco PF2232)..... <b>B1441</b>	<b>Fuel</b> (7/8-14 Thd.) (1R0751)..... <b>BF7632</b>	<b>Lube</b> (Standard Vers.) (1R0739).. <b>B76 +</b>
<b>Fuel/Water Separator</b> (Upgrade) (ACDelco TP3018)..... <b>BF46062<sup>89</sup></b>	<b>Radial Seal O. Air</b> (88937525)..... <b>RS4672</b>	<b>Lube</b> (Severe Service) (1R0739).. <b>B76-SS +</b>
<b>Fuel</b> (ACDelco TP1247)..... <b>BF790</b>	<b>Radial Seal I. Air</b> ..... <b>RS4673</b>	<b>Fuel</b> (ACDelco TP915D)..... <b>BF5800 +</b>
<b>Radial Seal Air</b> (ACDelco A2032C)..... <b>RS4859</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Radial Seal O. Air</b> (88915422)..... <b>RS2863</b>
<b>Panel Air</b> (ACDelco A3102C)..... <b>PA5428</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Radial Seal XP O. Air</b> (88915422)..... <b>RS2863XP</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Radial Seal I. Air</b> (12544543)..... <b>RS3501</b>
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Trans.</b> (ACDelco TF338)..... <b>BT8316-MPG</b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	C6500 Kodiak w/Cat 3126 (7.2L) Eng. (1/2004-on)
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Lube</b> (1R1807)..... <b>B7700 +</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Fuel</b> (ACDelco TP915D)..... <b>BF5800 +</b>
<b>Steering</b> (88892858)..... <b>P106-HD</b>	<b>Steering</b> (88892858)..... <b>P106-HD</b>	<b>Radial Seal O. Air</b> (88915422)..... <b>RS2863</b>
C5500 Kodiak w/8.1L Eng. (2003-04)	C6500 Kodiak w/Cat C7 (7.2L) Eng. (1/2004-on)	<b>Radial Seal XP O. Air</b> (88915422)..... <b>RS2863XP</b>
<b>Lube</b> (ACDelco PF454)..... <b>B1438</b>	<b>Lube</b> (1R1807)..... <b>B7700 +</b>	<b>Radial Seal I. Air</b> (12544543)..... <b>RS3501</b>
<b>Fuel</b> (ACDelco GF652)..... <b>BF853</b>	<b>Fuel/Water Separator</b> (ACDelco TP1519)..... <b>BF7759</b>	<b>Trans.</b> (ACDelco TF338)..... <b>BT8316-MPG</b>
<b>Radial Seal Air</b> (ACDelco A2032C)..... <b>RS4859</b>	<b>Fuel</b> (1-12 Thd.) (ACDelco TP915D)..... <b>BF5800 +</b>	C6500 Kodiak w/Isuzu 6HK1-TC (7.8L) Eng. (2003-06)
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Fuel</b> (7/8-14 Thd.) (1R0751)..... <b>BF7632</b>	<b>Lube</b> (94037791)..... <b>B75</b>
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Radial Seal O. Air</b> (88937525)..... <b>RS4672</b>	<b>P. Fuel/Water Separator</b> (w/Drain) (15618921)..... <b>BF5813 +</b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Radial Seal I. Air</b> ..... <b>RS4673</b>	<b>P. Fuel/Water Separator</b> (Open End for Bowl) (15618921)..... <b>BF5813-O +</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Fuel/Water Separator Strainer</b> (ACDelco TP1519)..... <b>BF7759</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Fuel Ele.</b> (8980370110)..... <b>PF9919</b>
<b>Steering</b> (88892858)..... <b>P106-HD</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Fuel Spin-on</b> (94392474)..... <b>BF7602</b>
C5500 Kodiak w/8.1L Eng. (2005-on)	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Radial Seal O. Air</b> (88937525)..... <b>RS4672</b>
<b>Lube</b> (ACDelco PF454)..... <b>B1438</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Radial Seal I. Air</b> (ACDelco A2035C)..... <b>RS4673</b>
<b>Fuel</b> (ACDelco TP1247)..... <b>BF790</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>Radial Seal Air</b> (ACDelco A2032C)..... <b>RS4859</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Steering</b> (88892858)..... <b>P106-HD</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	C6500 Kodiak w/Cat 3116 (6.6L) Eng.	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>B-P Lube Ele.</b> (15525633)..... <b>C750-E +</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Fuel/Water Separator</b> (ACDelco TP1519)..... <b>BF7759</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Fuel/Water Separator</b> (12542374)..... <b>BF1266</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Steering</b> (88892858)..... <b>P106-HD</b>	<b>Fuel</b> (Short Version) (ACDelco TP936)..... <b>BF592 +</b>	<b>Steering</b> (88892858)..... <b>P106-HD</b>
	<b>Fuel</b> (Long Vers.) (25010793)..... <b>BF5800 +</b>	
	<b>Radial Seal O. Air</b> (15619013)..... <b>RS2863</b>	


\* See Product Guide for Variations of This Number. <sup>89</sup> Inner Fender Liner Removal Recommended for Proper Installation. Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

CHEVROLET North America Trucks & Vans (cont'd)	CHEVROLET North America Trucks & Vans (cont'd)	CHEVROLET North America Trucks & Vans (cont'd)
C6500 Kodiak w/Isuzu 6HK1-TC (7.8L) Eng. (2007-08)	C6500 Kodiak w/V8-366 (6.0L) Eng.	C6500 Kodiak w/V8-496 (8.1L) Eng. (2005-on)
Lube (94037791)..... B75	Lube (25160561)..... B1428 +	(Cont'd)
P. Fuel/Water Separator (w/Drain) (15618921)..... BF5813 +	Lube (ACDelco PF897F)..... BT230 +	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017
Fuel/Water Separator Strainer (ACDelco TP1519)..... BF7759	Fuel In-Line (25171792)..... BF853	Trans. Spin-on (Allison 29539579)..... BT8460
P. Fuel/Water Separator (Open End for Bowl) (15618921)..... BF5813-O +	C6500 Kodiak w/V8-427 (7.0L) Eng.	Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT
Fuel Ele. (8980370110)..... PF9919	F-F Lube (ACDelco PF897F)..... BT230 +	Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT
Fuel Spin-on (94392474)..... BF7602	Fuel Ele. (5651879)..... PF827	Steering (88892858)..... P106-HD
Radial Seal O. Air (88937525)..... RS4672	C6500 Kodiak w/V8-454 (7.4L) Eng.	C7500 Kodiak w/V8-366 (6.0L)
Radial Seal I. Air (ACDelco A2035C)..... RS4673	Lube (25160561)..... B1428 +	Lube..... B7
Single Radial Seal Air (ACDelco A3101C)..... RS5767	Lube (25324052)..... B1438	Fuel Ele..... PF827
Trans. Spin-on (Allison 29539579)..... BT8460	Lube (25013454)..... B6-HPG +	Comp. Air..... PA1909
Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004	Fuel In-Line (25171792)..... BF853	Air (Ele. w/Foam Wrap) (6422556)..... PA1800
Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016	Fuel In-Line (ACDelco GF681).... BF7713	Air (Ele. w/Fins) (702025)..... PA1922-FN
Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003	Fuel Spin-on (ACDelco TP1227)..... BF790	C7500 Kodiak w/V8-427 (7.0L) Eng.
Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017	Radial Seal Air (15986275)..... RS3706 +	Lube..... B7
Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	Trans. Pan-Type (AT & MT Series, 3.8 In. Pan) (Allison 29540976)..... 19992 +	Fuel Ele..... PF827
Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Trans. Pan-Type (AT & MT Series, 5.3 In. Pan) (Allison 29538489)..... 19739 +	Comp. Air..... PA1909
Steering (88892858)..... P106-HD	Trans. Spin-on (AT & MT Series, Auxiliary) (Allison 29510922)..... BT8316-MPG	Air (Ele. w/Foam Wrap) (6422556)..... PA1800
C6500 Kodiak w/Isuzu 6HK1-TC (7.8L) Eng. (2009-on)	C6500 Kodiak w/V8-496 (8.1L) Eng. (To 2004)	Air (Ele. w/Fins) (702025)..... PA1922-FN
Lube (94037791)..... B75	Lube (ACDelco PF454)..... B1438	C7500 Kodiak w/V8-454 (7.4L) Eng.
P. Fuel/Water Separator (w/Drain) (15618921)..... BF5813 +	Fuel (ACDelco GF652)..... BF853	Lube..... B7
P. Fuel/Water Separator (Open End for Bowl) (15618921)..... BF5813-O +	11 3/32 In. Radial Seal Air (ACDelco A1301C)..... RS3706	Fuel Ele..... PF827
Fuel/Water Separator Strainer (ACDelco TP1519)..... BF7759	18 1/2 In. Radial Seal Air (88937525)..... RS4672	Air (702025)..... PA1922-FN
Fuel Ele. (8980370110)..... PF9919	Comp. Air (ACDelco A507CF)..... PA1909	Comp. Air..... PA1909
Fuel Spin-on (94392474)..... BF7602	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004	C7500 Kodiak w/V8 8.1L Eng. (To 2004)
Radial Seal Air (ACDelco A3101C)..... RS5767	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016	Lube (ACDelco PF454)..... B1438
Trans. Spin-on (Allison 29539579)..... BT8460	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003	Fuel (ACDelco GF652)..... BF853
Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017	Radial Seal O. Air (ACDelco A2031C)..... RS4672
Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016	Trans. Spin-on (Allison 29539579)..... BT8460	Comp. Air (ACDelco A507CF)..... PA1909
Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003	Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT
Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017	Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT
Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	Steering (88892858)..... P106-HD	Opt. Trans. Spin-on (Fuller 17237)..... B2 +
Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	C6500 Kodiak w/V8-496 (8.1L) Eng. (2005-on)	Steering (88892858)..... P106-HD
Steering (88892858)..... P106-HD	Lube (ACDelco PF454)..... B1438	C7500 Kodiak w/V8 8.1L Eng. (2005-on)
	Fuel (ACDelco TP1247)..... BF790	Lube (ACDelco PF454)..... B1438
	Radial Seal O. Air (88937525)..... RS4672	Fuel (ACDelco TP1247)..... BF790
	Comp. Air (ACDelco A507CF)..... PA1909	Radial Seal O. Air (ACDelco A2031C)..... RS4672
	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004	Comp. Air (ACDelco A507CF)..... PA1909
	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016	Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT
	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003	Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT
		Opt. Trans. Spin-on (Fuller 17237)..... B2 +
		Steering (88892858)..... P106-HD

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

CHEVROLET North America Trucks & Vans (cont'd)	CHEVROLET North America Trucks & Vans (cont'd)	CHEVROLET North America Trucks & Vans (cont'd)
C7500 Kodiak w/Cat 3116 (6.6L) Eng. Lube (Standard Vers.)..... <b>B76</b> + Lube (High Efficiency Vers.) (1R-1807)..... <b>B7700</b> + Lube (Severe Service)..... <b>B76-SS</b> + Box-Style Fuel/Water Separator. <b>BF912</b> Fuel Spin-on..... <b>BF970</b> + Fuel Spin-on (1R-0750)..... <b>BF7633</b> + Radial Seal O. Air (15619013)..... <b>RS2863</b> Radial Seal XP O. Air (15619013)..... <b>RS2863XP</b> Radial Seal I. Air..... <b>RS3501</b>	C7500 Kodiak w/Isuzu 6HK1-TC (7.8L) Eng. (2003-06) (Cont'd) Fuel Ele. (8980370110)..... <b>PF9919</b> Fuel Spin-on (94392474)..... <b>BF7602</b> Radial Seal O. Air (88937525)..... <b>RS4672</b> Radial Seal I. Air (ACDelco A2035C)..... <b>RS4673</b> Air Dryer (89040662)..... <b>BA5374</b> + Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2</b> + Steering (88892858)..... <b>P106-HD</b>	C7500 Kodiak w/Isuzu 6HK1-TC (7.8L) Eng. (2009-on) (Cont'd) Steering (88892858)..... <b>P106-HD</b> C8500 w/Cat 3126 Eng. Radial Seal O. Air (88915422)..... <b>RS2863</b> Radial Seal XP O. Air (88915422)..... <b>RS2863XP</b> Radial Seal I. Air (12544543)..... <b>RS3501</b>
C7500 Kodiak w/Cat 3126 (7.2L) Eng. Radial Seal O. Air (88915422)..... <b>RS2863</b> Radial Seal XP O. Air (88915422)..... <b>RS2863XP</b> Radial Seal I. Air (12544543)..... <b>RS3501</b>	C7500 Kodiak w/Isuzu 6HK1-TC (7.8L) Eng. (2007-08) Lube (94037791)..... <b>B75</b> P. Fuel/Water Separator (w/Drain) (15618921)..... <b>BF5813</b> + P. Fuel/Water Separator (Open End for Bowl) (15618921)..... <b>BF5813-O</b> + Fuel/Water Separator Strainer (ACDelco TP1519)..... <b>BF7759</b> Fuel Ele. (8980370110)..... <b>PF9919</b> Fuel Spin-on (94392474)..... <b>BF7602</b> Radial Seal O. Air (88937525)..... <b>RS4672</b> Radial Seal I. Air (ACDelco A2035C)..... <b>RS4673</b> Single Radial Seal Air (ACDelco A3101C)..... <b>RS5767</b> Air Dryer (89040662)..... <b>BA5374</b> + Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2</b> + Steering (88892858)..... <b>P106-HD</b>	C8500 w/Cat C7 Eng. Lube (To 1/2004 (Standard Vers.)) (1R0739)..... <b>B76</b> Lube (1/2004-on) (1R1807)..... <b>B7700</b> + Fuel/Water Separator (ACDelco TP1519)..... <b>BF7759</b> Fuel (1-12 Thd.) (ACDelco TP915D)..... <b>BF5800</b> + Radial Seal O. Air (88937525)..... <b>RS4672</b> Radial Seal I. Air..... <b>RS4673</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2</b> + Steering (88892858)..... <b>P106-HD</b>
C7500 Kodiak w/Cat C7 (7.2L) Eng. (To 1/2004) Lube (Standard Vers.) (1R0739).. <b>B76</b> Fuel/Water Separator (ACDelco TP1519)..... <b>BF7759</b> Fuel (7/8-14 Thd.) (1R0751)..... <b>BF7632</b> Fuel (1-12 Thd.) (ACDelco TP915D)..... <b>BF5800</b> + Radial Seal O. Air (88937525)..... <b>RS4672</b> Radial Seal I. Air..... <b>RS4673</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2</b> + Steering (88892858)..... <b>P106-HD</b>	C7500 Kodiak w/Isuzu 6HK1-TC (7.8L) Eng. (2009-06) Lube (94037791)..... <b>B75</b> P. Fuel/Water Separator (w/Drain) (15618921)..... <b>BF5813</b> + P. Fuel/Water Separator (Open End for Bowl) (15618921)..... <b>BF5813-O</b> + Fuel/Water Separator Strainer (ACDelco TP1519)..... <b>BF7759</b> Fuel Ele. (8980370110)..... <b>PF9919</b> Fuel Spin-on (94392474)..... <b>BF7602</b> Radial Seal O. Air (ACDelco A2031C)..... <b>RS4672</b> Radial Seal I. Air (ACDelco A2035C)..... <b>RS4673</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2</b> + Steering (88892858)..... <b>P106-HD</b>	C8500 w/Isuzu 6HK1-TC (7.8L) Eng. (2003-06) Lube (94037791)..... <b>B75</b> P. Fuel/Water Separator (w/Drain) (15618921)..... <b>BF5813</b> + P. Fuel/Water Separator (Open End for Bowl) (15618921)..... <b>BF5813-O</b> + Fuel/Water Separator Strainer (ACDelco TP1519)..... <b>BF7759</b> Fuel Ele. (8980370110)..... <b>PF9919</b> Fuel Spin-on (94392474)..... <b>BF7602</b> Radial Seal O. Air (ACDelco A2031C)..... <b>RS4672</b> Radial Seal I. Air (ACDelco A2035C)..... <b>RS4673</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2</b> + Steering (88892858)..... <b>P106-HD</b>
C7500 Kodiak w/Cat C7 (7.2L) Eng. (1/2004-on) Lube (1R1807)..... <b>B7700</b> + Fuel/Water Separator (ACDelco TP1519)..... <b>BF7759</b> Fuel (7/8-14 Thd.) (1R0751)..... <b>BF7632</b> Fuel (1-12 Thd.) (ACDelco TP915D)..... <b>BF5800</b> + Radial Seal O. Air (88937525)..... <b>RS4672</b> Radial Seal I. Air..... <b>RS4673</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2</b> + Steering (88892858)..... <b>P106-HD</b>	C7500 Kodiak w/Isuzu 6HK1-TC (7.8L) Eng. (2009-on) Lube (94037791)..... <b>B75</b> P. Fuel/Water Separator (w/Drain) (15618921)..... <b>BF5813</b> + P. Fuel/Water Separator (Open End for Bowl) (15618921)..... <b>BF5813-O</b> + Fuel/Water Separator Strainer (ACDelco TP1519)..... <b>BF7759</b> Fuel Ele. (8980370110)..... <b>PF9919</b> Fuel Spin-on (94392474)..... <b>BF7602</b> Radial Seal Air (ACDelco A3101C)..... <b>RS5767</b> Air Dryer (89040662)..... <b>BA5374</b> + Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2</b> +	C8500 w/Isuzu 6HK1-TC (7.8L) Eng. (2007-08) Lube (94037791)..... <b>B75</b> P. Fuel/Water Separator (w/Drain) (15618921)..... <b>BF5813</b> + P. Fuel/Water Separator (Open End for Bowl) (15618921)..... <b>BF5813-O</b> + Fuel/Water Separator Strainer (ACDelco TP1519)..... <b>BF7759</b> Fuel Ele. (8980370110)..... <b>PF9919</b> Fuel Spin-on (94392474)..... <b>BF7602</b>
C7500 Kodiak w/Isuzu 6HK1-TC (7.8L) Eng. (2003-06) Lube (94037791)..... <b>B75</b> P. Fuel/Water Separator (w/Drain) (15618921)..... <b>BF5813</b> + P. Fuel/Water Separator (Open End for Bowl) (15618921)..... <b>BF5813-O</b> + Fuel/Water Separator Strainer (ACDelco TP1519)..... <b>BF7759</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

CHEVROLET North America Trucks & Vans (cont'd)	CHEVROLET North America Trucks & Vans (cont'd)	CHEVROLET North America Trucks & Vans (cont'd)
C8500 w/Isuzu 6HK1-TC (7.8L) Eng. (2007-08) (Cont'd)	C8500 w/V8-496 (8.1L) Eng. (2005-on) (Cont'd)	Express 4500 w/V8-403 (6.6L) Turbo Diesel Eng. (2012-16)
Radial Seal O. Air (ACDelco A2031C).....	Steering (88892858).....	Lube (ACDelco PF2232).....
RS4672	P106-HD	B1441
Radial Seal I. Air (ACDelco A2035C).....	Express 4500 w/V8-364 (6.0L) CNG Eng. (2012-16)	Fuel/Water Separator (Upgrade) (ACDelco TP3018).....
RS4673	Lube (ACDelco PF48).....	BF46062 <sup>89</sup>
Single Radial Seal Air (ACDelco A3101C).....	Radial Seal Air (ACDelco A3097C).....	Channel Flow Air (ACDelco A2959C).....
RS5767	RS4131	CA5370
Trans. Ele. (2 In. Kit) (Allison 29540493).....	Trans. (24236933).....	20022
PT9416-MPG KIT	Express 4500 w/V8-364 (6.0L) Flex Fuel or Gas Eng. (2009-16)	Kodiak w/V8 6.0L Eng. (Mexico) (1995-98)
Trans. Ele. (4 In. Kit) (Allison 29540494).....	Lube (ACDelco PF48).....	Lube (ACDelco PF1218).....
PT9415-MPG KIT	Fuel (N/S).....	B1428 +
Opt. Trans. Spin-on (Fuller 17237).....	Radial Seal Air (ACDelco A3097C).....	Air (ACDelco A348C).....
B2 +	RS4131	PA2008
Steering (88892858).....	Trans. (4L60-E) (24208576).....	Kodiak w/6 Cyl. 6.6L Turbo Eng. (Mexico) (1995-98)
P106-HD	18056	Lube (ACDelco PF1218).....
C8500 w/Isuzu 6HK1-TC (7.8L) Eng. (2009-on)	Trans. (4L80-E) (24210956).....	Fuel/Water Separator (w/Drain) (15618921).....
Lube (94037791).....	20022	BF5813 +
P. Fuel/Water Separator (w/Drain) (15618921).....	Express 4500 w/V8-364 (6.0L) Eng. (2017)	Fuel/Water Separator (Open End for Bowl) (15618921).....
BF5813 +	Lube (ACDelco PF48).....	BF5813-O +
P. Fuel/Water Separator (Open End for Bowl) (15618921).....	Fuel (N/S).....	RS3501
BF5813-O +	Radial Seal Air (84000015).....	Kodiak w/V8 7.0L Eng. (Mexico) (1995-98)
Fuel/Water Separator Strainer (ACDelco TP1519).....	Trans. (24236933).....	Lube (ACDelco PF1218).....
BF7759	20022	B1428 +
Fuel Ele. (8980370110).....	Express 4500 w/V8-364 (6.0L) Eng. (2018)	Air (ACDelco A348C).....
PF9919	Lube (ACDelco PF48).....	PA2008
Fuel Spin-on (94392474).....	Fuel (N/S).....	Kodiak w/6 Cyl. 7.2L Turbo Eng. (Mexico)
BF7602	N/S	Lube (ACDelco PF1218).....
Radial Seal Air (ACDelco A3101C).....	Radial Seal Air (84000015).....	Fuel/Water Separator (w/Drain) (15618921).....
RS5767	RS4131	BF5813 +
Trans. Ele. (2 In. Kit) (Allison 29540493).....	Trans. (24236933).....	Fuel/Water Separator (Open End for Bowl) (15618921).....
PT9416-MPG KIT	20022	BF5813-O +
Trans. Ele. (4 In. Kit) (Allison 29540494).....	Express 4500 w/V8-364 (6.0L) Eng. (2019)	RS2863
PT9415-MPG KIT	Lube (89017524).....	Radial Seal XP Air (88915422).....
Opt. Trans. Spin-on (Fuller 17237).....	Fuel (N/S).....	RS2863XP
B2 +	Radial Seal Air (22909882).....	Kodiak w/4 Cyl. 7.2L Turbo Eng. (Mexico) (2005-06)
Steering (88892858).....	Trans. (24236933).....	Lube (ACDelco PF25).....
P106-HD	20022	B27
C8500 w/V8-496 (8.1L) Eng. (To 2004)	Express 4500 w/V8-364 (6.0L) Eng. (2020)	Fuel/Water Separator (w/Drain) (15618921).....
Lube (ACDelco PF454).....	Lube (89017524).....	BF5813 +
B1438	B160	Fuel/Water Separator (Open End for Bowl) (15618921).....
Fuel (ACDelco GF652).....	Fuel (N/S).....	BF5813-O +
BF853	N/S	RS3501
Radial Seal O. Air (ACDelco A2031C).....	Radial Seal Air (84000015).....	Kodiak w/V8 7.4L Eng. (Mexico)
RS4672	RS4131	Lube (ACDelco PF1218).....
Comp. Air (ACDelco A507CF).....	Express 4500 w/V8-401 (6.6L) Gas Eng. (2021)	B1428 +
PA1909	Lube (12707246).....	Panel Air (1995-99) (ACDelco A348C).....
Trans. Ele. (2 In. Kit) (Allison 29540493).....	Fuel (N/S).....	PA2008
PT9416-MPG KIT	N/S	Radial Seal Air (2000-01) (ACDelco A1301C).....
Trans. Ele. (4 In. Kit) (Allison 29540494).....	Air (ACDelco A3228C).....	RS3706
PT9415-MPG KIT	PA10423	Kodiak w/V8 8.1L Eng. (Mexico) (1999-2006)
Opt. Trans. Spin-on (Fuller 17237).....	Trans. (24258269).....	Lube (ACDelco PF25).....
B2 +	N/S	B27
Steering (88892858).....	Express 4500 w/V8-403 (6.6L) Turbo Diesel Eng. (2009-11)	Radial Seal Air (12544543).....
P106-HD	Lube (ACDelco PF2232).....	RS3501
C8500 w/V8-496 (8.1L) Eng. (2005-on)	Fuel Kit (ACDelco TP1537).....	LCF 4500 w/V8 (6.0L) CNG Eng. (2016)
Lube (ACDelco PF454).....	BF9918 KIT <sup>76</sup>	Lube (89017524).....
B1438	Channel Flow Air (ACDelco A2959C).....	B160
Fuel (ACDelco TP1247).....	CA5370	Air (97062294).....
BF790	Trans. (4L60-E S. Pan) (24200796).....	RS5434
Radial Seal O. Air (ACDelco A2031C).....	18010	Cab Air.....
RS4672	Trans. (4L60-E D. Pan) (24208813).....	CLN&R
Comp. Air (ACDelco A507CF).....	18056	LCF 4500 w/V8 (6.0L) Flex Fuel Eng. (2016)
PA1909	Trans. (4L80-E, 4L85-E) (24210956).....	Lube (89017524).....
Trans. Ele. (2 In. Kit) (Allison 29540493).....	18027	B160
PT9416-MPG KIT	Trans. (6L90) (24236933).....	Fuel.....
Trans. Ele. (4 In. Kit) (Allison 29540494).....	20022	N/S
PT9415-MPG KIT	Express 4500 w/V8-403 (6.6L) Turbo Diesel Eng. (2009-11)	Air (97062294).....
Opt. Trans. Spin-on (Fuller 17237).....	Lube (ACDelco PF2232).....	RS5434
B2 +	B1441	CLN&R
Steering (88892858).....	BF9918 KIT <sup>76</sup>	20022
P106-HD	Channel Flow Air (ACDelco A2959C).....	

+ See Product Guide for Variations of This Number. <sup>76</sup> Contains Pri. and Sec. Fuel Elements. <sup>89</sup> Inner Fender Liner Removal Recommended for Proper Installation. Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).




CHEVROLET North America Trucks & Vans (cont'd)	CHEVROLET North America Trucks & Vans (cont'd)	CHEVROLET North America Trucks & Vans (cont'd)
LCF 4500 w/V8 (6.0L) Eng. (2017) Lube (19303975)..... <b>B160</b> Fuel (N/S)..... <b>N/S</b> Air (97780479)..... <b>RS5434</b> Trans. (24236933)..... <b>20022</b>	LCF 4500XD w/Isuzu 5.2L Turbo/Intercooled Diesel Eng. (2017) Lube (98298404)..... <b>B40137</b> Fuel/Water Separator (Chassis Side) (98037481)..... <b>BF7534</b> Fuel (Eng. Side) (98147525)..... <b>PF46059</b> Radial Seal Air (98177271)..... <b>RS5434</b> Cab Air..... <b>CLN&amp;R</b>	LCF 5500HD w/Isuzu 5.2L Turbo/Intercooled Diesel Eng. (2019) (Cont'd) Diesel Exhaust Fluid (8981694030)..... <b>PE17000</b>
LCF 4500 w/V8 (6.0L) Eng. (2018) Lube (19303975)..... <b>B160</b> Fuel (N/S)..... <b>N/S</b> Air (97780479)..... <b>RS5434</b> Trans. (24236933)..... <b>20022</b>	LCF 4500XD w/Isuzu 5.2L Turbo/Intercooled Diesel Eng. (2018) Lube (98298404)..... <b>B40137</b> Fuel/Water Separator (98037481)..... <b>BF7534</b> Fuel (98147525)..... <b>PF46059</b> Radial Seal Air (97780479)..... <b>RS5434</b>	LCF 5500HD w/Isuzu 5.2L Turbo/Intercooled Diesel Eng. (2020) Dual-Flow Lube (97148270)..... <b>BD7169</b> Fuel/Water Separator (98037481)..... <b>BF7534</b> Fuel (98147525)..... <b>PF46059</b> Radial Seal Air (97780479)..... <b>RS5434</b> Trans. (97182282)..... <b>B114</b> Diesel Exhaust Fluid (98169403) <b>PE17000</b>
LCF 4500 w/V8 (6.0L) Eng. (2019) Lube (89017524)..... <b>B160</b> Fuel (N/S)..... <b>N/S</b> Air (97062294)..... <b>RS5434</b> Cab Air..... <b>CLN&amp;R</b>	LCF 4500XD w/Isuzu 5.2L Turbo/Intercooled Diesel Eng. (2019) Lube (98298404)..... <b>B40137</b> Fuel/Water Separator (Chassis Side) (98037481)..... <b>BF7534</b> Fuel (Eng. Side) (98147525)..... <b>PF46059</b> Radial Seal Air (97780479)..... <b>RS5434</b> Cab Air..... <b>CLN&amp;R</b>	LCF 5500XD w/Isuzu 5.2L Turbo/Intercooled Diesel Eng. (2017) Lube (98298404)..... <b>B40137</b> Fuel/Water Separator (Chassis Side) (98037481)..... <b>BF7534</b> Fuel (Eng. Side) (98147525)..... <b>PF46059</b> Radial Seal Air (98177271)..... <b>RS5434</b> Cab Air..... <b>CLN&amp;R</b>
LCF 4500 w/V8 (6.0L) Eng. (2020) Lube (89017524)..... <b>B160</b> Fuel (N/S)..... <b>N/S</b>	LCF 4500XD w/Isuzu 5.2L Turbo/Intercooled Diesel Eng. (2020) Dual-Flow Lube (97148270)..... <b>BD7169</b> Fuel/Water Separator (98037481)..... <b>BF7534</b> Fuel (98147525)..... <b>PF46059</b> Radial Seal Air (97780479)..... <b>RS5434</b> Trans. (97182282)..... <b>B114</b>	LCF 5500XD w/Isuzu 5.2L Turbo/Intercooled Diesel Eng. (2018) Lube (98298404)..... <b>B40137</b> Fuel/Water Separator (98037481)..... <b>BF7534</b> Fuel (98147525)..... <b>PF46059</b> Radial Seal Air (97780479)..... <b>RS5434</b>
LCF 4500HD w/Isuzu 5.2L Turbo/Intercooled Diesel Eng. (2017) Lube (98298404)..... <b>B40137</b> Fuel/Water Separator (Chassis Side) (98037481)..... <b>BF7534</b> Fuel (Eng. Side) (98147525)..... <b>PF46059</b> Radial Seal Air (98177271)..... <b>RS5434</b> Cab Air..... <b>CLN&amp;R</b> Diesel Exhaust Fluid (98169403) <b>PE17000</b>	LCF 4500XD w/Isuzu 5.2L Turbo/Intercooled Diesel Eng. (2019) Lube (98298404)..... <b>B40137</b> Fuel/Water Separator (Chassis Side) (98037481)..... <b>BF7534</b> Fuel (98147525)..... <b>PF46059</b> Radial Seal Air (97780479)..... <b>RS5434</b> Trans. (97182282)..... <b>B114</b>	LCF 5500XD w/Isuzu 5.2L Turbo/Intercooled Diesel Eng. (2019) Lube (98298404)..... <b>B40137</b> Fuel/Water Separator (Chassis Side) (98037481)..... <b>BF7534</b> Fuel (Eng. Side) (98147525)..... <b>PF46059</b> Radial Seal Air (97780479)..... <b>RS5434</b> Cab Air..... <b>CLN&amp;R</b> Trans. (97182282)..... <b>B114</b>
LCF 4500HD w/Isuzu 5.2L Turbo/Intercooled Diesel Eng. (2018) Lube (98298404)..... <b>B40137</b> Fuel/Water Separator (98037481)..... <b>BF7534</b> Fuel (98147525)..... <b>PF46059</b> Radial Seal Air (97780479)..... <b>RS5434</b> Diesel Exhaust Fluid (98169403) <b>PE17000</b>	LCF 5500HD w/Isuzu 5.2L Turbo/Intercooled Diesel Eng. (2017) Lube (98298404)..... <b>B40137</b> Fuel/Water Separator (Chassis Side) (98037481)..... <b>BF7534</b> Fuel (Eng. Side) (98147525)..... <b>PF46059</b> Radial Seal Air (98177271)..... <b>RS5434</b> Cab Air..... <b>CLN&amp;R</b> Diesel Exhaust Fluid (98169403) <b>PE17000</b>	LCF 5500XD w/Isuzu 5.2L Turbo/Intercooled Diesel Eng. (2020) Dual-Flow Lube (97148270)..... <b>BD7169</b> Fuel/Water Separator (98037481)..... <b>BF7534</b> Fuel (98147525)..... <b>PF46059</b> Radial Seal Air (97780479)..... <b>RS5434</b> Trans. (97182282)..... <b>B114</b>
LCF 4500HD w/Isuzu 5.2L Turbo/Intercooled Diesel Eng. (2019) Lube (98298404)..... <b>B40137</b> Fuel/Water Separator (Chassis Side) (98037481)..... <b>BF7534</b> Fuel (Eng. Side) (98147525)..... <b>PF46059</b> Radial Seal Air (97780479)..... <b>RS5434</b> Cab Air..... <b>CLN&amp;R</b> Trans. (97182282)..... <b>B114</b> Diesel Exhaust Fluid (8981694030)..... <b>PE17000</b>	LCF 5500HD w/Isuzu 5.2L Turbo/Intercooled Diesel Eng. (2018) Lube (98298404)..... <b>B40137</b> Fuel/Water Separator (98037481)..... <b>BF7534</b> Fuel (98147525)..... <b>PF46059</b> Radial Seal Air (97780479)..... <b>RS5434</b>	LCF 6500XD w/Isuzu 5.2L Turbo/Intercooled Diesel Eng. (2018) Lube (98298404)..... <b>B40137</b> Fuel/Water Separator (98037481)..... <b>BF7534</b> Fuel (98147525)..... <b>PF46059</b> Air (2906469100)..... <b>PA2761</b> Trans. (97182282)..... <b>B114</b>
LCF 4500HD w/Isuzu 5.2L Turbo/Intercooled Diesel Eng. (2020) Lube (97148270)..... <b>BD7169</b> Fuel/Water Separator (98037481)..... <b>BF7534</b> Fuel (98147525)..... <b>PF46059</b> Radial Seal Air (97780479)..... <b>RS5434</b> Trans. (97182282)..... <b>B114</b> Diesel Exhaust Fluid (98169403) <b>PE17000</b>	LCF 5500HD w/Isuzu 5.2L Turbo/Intercooled Diesel Eng. (2019) Lube (98298404)..... <b>B40137</b> Fuel/Water Separator (Chassis Side) (98037481)..... <b>BF7534</b> Fuel (Eng. Side) (98147525)..... <b>PF46059</b> Radial Seal Air (97780479)..... <b>RS5434</b> Cab Air..... <b>CLN&amp;R</b> Trans. (97182282)..... <b>B114</b>	

Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

CHEVROLET North America Trucks & Vans (cont'd)	CHEVROLET North America Trucks & Vans (cont'd)	CHEVROLET North America Trucks & Vans (cont'd)
LCF 6500XD w/Isuzu 5.2L Turbo/Intercooled Diesel Eng. (2019) Lube (98298404)..... <b>B40137</b> Fuel/Water Separator (Chassis Side) (98037481)..... <b>BF7534</b> Fuel (Eng. Side) (98147525)..... <b>PF46059</b> Radial Seal Air (97780479)..... <b>RS5434</b> Cab Air..... <b>CLN&amp;R</b> Trans. (97182282)..... <b>B114</b>	Motorhomes w/V8-454 Eng. 1 Qt. Lube (To 1986)..... <b>B6 +</b> 1 Qt. Lube (1986-on)..... <b>B1428 +</b> 2 Qt. Lube..... <b>B7</b> 2 1/32 In. Fuel Ele. (Carb.)..... <b>PF894-RV</b> In-Line Fuel..... <b>BF836</b> Air..... <b>PA2008</b>	Silverado 4500 HD w/V8-403 (6.6L) Turbo Diesel Eng. (2020) (Cont'd) Trans. Pan-Type (D. Pan w/o Gskt.) (29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (29537966)..... <b>20017</b> Trans. Spin-on (29539579)..... <b>BT8460</b>
LCF 6500XD w/Isuzu 5.2L Turbo/Intercooled Diesel Eng. (2020) Dual-Flow Lube (97148270)..... <b>BD7169</b> Fuel/Water Separator (98037481)..... <b>BF7534</b> Fuel (98147525)..... <b>PF46059</b> Trans. (97182282)..... <b>B114</b>	P-30 w/V8 5.7L TBI (Mexico) Lube (ACDelco PF25)..... <b>B27</b> Air (ACDelco A348C)..... <b>PA2008</b>	Silverado 4500 HD w/V8-403 (6.6L) Turbo Diesel Eng. (2021) Lube (ACDelco PF26)..... <b>B40150</b> Fuel/Water Separator (19405644)..... <b>PF46250</b> Fuel (Hsg. Marked Mann Hummel) (13539108)..... <b>PF46126</b> Cab Air (ACDelco CF188)..... <b>PA4486</b>
LCF 6500XD w/Isuzu 5.2L Turbo/Intercooled Diesel Eng. (2021) Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>	P-30 w/V8 5.7L CPI (Mexico) Lube (ACDelco PF52)..... <b>B35-S +</b> Air (ACDelco A348C)..... <b>PA2008</b>	Silverado 5500 HD w/V8-403 (6.6L) Turbo Diesel Eng. (2019) Lube (12684038)..... <b>B40150</b> Fuel/Water Separator (19405644)..... <b>PF46250</b> Cab Air (23281440)..... <b>PA4486</b> Trans. Pan-Type (S. Pan w/o Gskt.) (29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (29537966)..... <b>20017</b> Trans. Spin-on (29539579)..... <b>BT8460</b>
MD Isuzu Truck Forward w/V8 6.0L Eng. Lube (To 2006) (ACDelco PF46)..... <b>B31</b> Lube (2007-on) (ACDelco PF48)..... <b>B160</b>	P30 Motorhomes w/V8-402 Eng. Opt. Lube Ele..... <b>P476</b> Lube Spin-on..... <b>B6 +</b> Fuel..... <b>PF893</b> Air..... <b>PA2006</b>	Silverado 5500 HD w/V8-403 (6.6L) Turbo Diesel Eng. (2020) Lube (ACDelco PF26)..... <b>B40150</b> Fuel/Water Separator (19405644)..... <b>PF46250</b> Cab Air (23281440)..... <b>PA4486</b> Trans. Pan-Type (S. Pan w/o Gskt.) (29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (29537966)..... <b>20017</b> Trans. Spin-on (29539579)..... <b>BT8460</b>
Mexico Med Conventional w/L6 7.2L Turbo Eng. Lube (To 1/2004 (Standard Vers.)) (1R0739)..... <b>B76</b> Lube (1/2004-on) (1R1807)..... <b>B7700 +</b> Fuel (1R0751)..... <b>BF7632</b> Radial Seal Air (ACDelco A1169C)..... <b>RS2863</b> Radial Seal XP Air (ACDelco A1169C)..... <b>RS2863XP</b>	P40 w/6-292 (4.8L) Eng. Lube..... <b>B6 +</b> 1 1/32 In. Fuel (Rochester Carb.)..... <b>PF893</b> 3 15/32 In. Fuel Ele..... <b>PF827</b>	Silverado 5500 HD w/V8-403 (6.6L) Turbo Diesel Eng. (2021) Lube (ACDelco PF26)..... <b>B40150</b> Fuel/Water Separator (19405644)..... <b>PF46250</b> Fuel (Hsg. Marked Mann Hummel) (13539108)..... <b>PF46126</b> Cab Air (ACDelco CF188)..... <b>PA4486</b>
Mexico Med Conventional w/V8 8.1L Eng. Lube (ACDelco PF454)..... <b>B1438</b> Fuel (ACDelco GF652)..... <b>BF853</b>	S7 w/Detroit Diesel V8-501 (8.2L) Eng. Lube (25013454)..... <b>B6-HPG +</b> Fuel/Water Separator (12542374)..... <b>BF1266</b> P. Fuel (ACDelco TP936)..... <b>BF592 +</b> S. Fuel (23518526)..... <b>BF593</b>	Silverado 6500 HD w/V8-403 (6.6L) Turbo Diesel Eng. (2019) Lube (12684038)..... <b>B40150</b>
Motorhomes w/V8-350 Eng. 1 Qt. Lube..... <b>B6 +</b> 2 Qt. Lube..... <b>B7</b> Fuel Ele. (Carb.)..... <b>PF893</b> In-Line Fuel..... <b>BF836</b> Air..... <b>PA1680</b>	Silverado 4500 HD w/V8-403 (6.6L) Turbo Diesel Eng. (2019) Lube (12684038)..... <b>B40150</b> Fuel/Water Separator (19405644)..... <b>PF46250</b> Cab Air (23281440)..... <b>PA4486</b> Trans. Pan-Type (S. Pan w/o Gskt.) (29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (29537965)..... <b>20016</b> Trans. Spin-on (29539579)..... <b>BT8460</b>	Silverado 6500 HD w/V8-403 (6.6L) Turbo Diesel Eng. (2019) Lube (12684038)..... <b>B40150</b>
Motorhomes w/V8-402 Eng. Opt. Lube Ele..... <b>P476</b> Lube Spin-on..... <b>B6 +</b> Fuel..... <b>PF893</b> Air..... <b>PA2006</b>	Silverado 4500 HD w/V8-403 (6.6L) Turbo Diesel Eng. (2020) Lube (ACDelco PF26)..... <b>B40150</b> Fuel/Water Separator (19405644)..... <b>PF46250</b> Cab Air (23281440)..... <b>PA4486</b> Trans. Pan-Type (S. Pan w/o Gskt.) (29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (29537965)..... <b>20016</b>	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>CHEVROLET</b> North America Trucks & Vans (cont'd)	<b>CHEVROLET</b> North America Trucks & Vans (cont'd)	<b>CHEVROLET</b> North America Trucks & Vans (cont'd)
Silverado 6500 HD w/V8-403 (6.6L) Turbo Diesel Eng. (2019) (Cont'd)	T6500 w/Cat 3116 (6.6L) Eng. (Cont'd)	T6500 w/V8-366 (6.0L) Eng.
<b>Fuel/Water Separator</b> (19405644)..... <b>PF46250</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2<sup>+</sup></b>	<b>Lube</b> (25160561)..... <b>B1428<sup>+</sup></b>
<b>Cab Air</b> (23281440)..... <b>PA4486</b>	T6500 w/Cat 3126 (7.2L) Eng.	<b>Lube</b> (25013454)..... <b>B6-HPG<sup>+</sup></b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (29537965)..... <b>20004</b>	<b>F-F Lube</b> (Standard Vers.) (1R0739)..... <b>B76<sup>+</sup></b>	<b>Lube</b> (ACDelco PF897F)..... <b>BT230<sup>+</sup></b>
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (29537965)..... <b>20016</b>	<b>B-P Lube</b> (15525633)..... <b>C750-E<sup>+</sup></b>	<b>Fuel In-Line</b> (25171792)..... <b>BF853</b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (29537966)..... <b>20003</b>	<b>F-F Lube</b> (Severe Service) (1R0739)..... <b>B76-SS<sup>+</sup></b>	<b>Air</b> (6487958)..... <b>PA2008</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (29537966)..... <b>20017</b>	<b>Fuel/Water Separator</b> (w/Drain) (19256911)..... <b>BF5813</b>	<b>Trans. Pan-Type</b> (AT Series, 3.8 In. Pan) (Allison 29540976)..... <b>19992<sup>+</sup></b>
<b>Trans. Spin-on</b> (29539579)..... <b>BT8460</b>	<b>P. Fuel/Water Separator</b> (15152281)..... <b>BF7759</b>	<b>Trans. Pan-Type</b> (AT Series, 5.3 In. Pan) (Allison 29538489)..... <b>19739<sup>+</sup></b>
Silverado 6500 HD w/V8-403 (6.6L) Turbo Diesel Eng. (2020)	<b>Fuel/Water Separator</b> (Open End for Bowl) (19256911)..... <b>BF5813-O<sup>+</sup></b>	<b>Trans. Spin-on</b> (AT Series) (Allison 29510922)..... <b>BT8316-MPG</b>
<b>Lube</b> (ACDelco PF26)..... <b>B40150</b>	<b>Fuel</b> (1-12 Thd.) (25014274)..... <b>BF5800<sup>+</sup></b>	T7500 w/Cat 3116 (6.6L) Eng.
<b>Fuel/Water Separator</b> (19405644)..... <b>PF46250</b>	<b>Fuel</b> (7/8-14 Thd.) (614783)..... <b>BF7632</b>	<b>Lube</b> (ACDelco PF897F)..... <b>BT230<sup>+</sup></b>
<b>Cab Air</b> (23281440)..... <b>PA4486</b>	<b>Std. Air</b> (Don. P134353)..... <b>PA2577</b>	<b>B-P Lube Ele.</b> (15525633)..... <b>C750-E<sup>+</sup></b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (29537965)..... <b>20004</b>	<b>Radial Seal O. Air</b> (ACDelco A2012C)..... <b>RS3548</b>	<b>Fuel/Water Separator</b> (ACDelco TP1519)..... <b>BF7759</b>
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (29537965)..... <b>20016</b>	<b>Radial Seal XP O. Air</b> (ACDelco A2012C)..... <b>RS3548XP</b>	<b>Fuel</b> (25010793)..... <b>BF5800<sup>+</sup></b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (29537966)..... <b>20003</b>	<b>Radial Seal I. Air</b> (Don. P538456)..... <b>RS3722</b>	<b>O. Air</b> (94048864)..... <b>PA2577</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (29537966)..... <b>20017</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	<b>I. Air</b> (25096436)..... <b>PA2578</b>
<b>Trans. Spin-on</b> (29539579)..... <b>BT8460</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	<b>Trans. Ele. (2 In. Kit)</b> (Allison 29545776)..... <b>PT9416-MPG KIT</b>
Silverado 6500 HD w/V8-403 (6.6L) Turbo Diesel Eng. (2021)	T6500 w/Isuzu 6HK1-TC (7.8L) Eng.	<b>Trans. Ele. (4 In. Kit)</b> (Allison 29548988)..... <b>PT9415-MPG KIT</b>
<b>Lube</b> (ACDelco PF26)..... <b>B40150</b>	<b>Lube</b> (94037791)..... <b>B75</b>	<b>Trans. Pan-Type</b> (AT Series, 3.8 In. Pan) (Allison 29540976)..... <b>19992<sup>+</sup></b>
<b>Fuel/Water Separator</b> (19405644)..... <b>PF46250</b>	<b>Fuel/Water Separator</b> (Upgrade) (ACDelco TP3018)..... <b>BF46062<sup>89</sup></b>	<b>Trans. Pan-Type</b> (AT Series, 5.3 In. Pan) (Allison 29538489)..... <b>19739<sup>+</sup></b>
<b>Fuel</b> (Hsg. Marked Mann Hummel) (13539108)..... <b>PF46126</b>	<b>Fuel/Water Separator</b> (w/Drain) (15618921)..... <b>BF5813<sup>+</sup></b>	<b>Trans. Spin-on</b> (AT Series) (Allison 29510922)..... <b>BT8316-MPG</b>
<b>Cab Air</b> (ACDelco CF188)..... <b>PA4486</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (15618921)..... <b>BF5813-O<sup>+</sup></b>	<b>Trans. Spin-on</b> (Fuller 4304827)..... <b>BT223</b>
Titan 90	<b>Fuel Ele.</b> (8980370110)..... <b>PF9919</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2<sup>+</sup></b>
<b>Trans. Breather</b> (1970-on)..... <b>P187</b>	<b>Fuel Spin-on</b> (94392474)..... <b>BF7602</b>	T7500 w/Cat 3126 (7.2L) Eng.
T6500 w/Cat 3116 (6.6L) Eng.	<b>Radial Seal Air</b> (ACDelco A2012C)..... <b>RS3548</b>	<b>F-F Lube</b> (Standard Vers.) (1R0739)..... <b>B76<sup>+</sup></b>
<b>Lube</b> (ACDelco PF897F)..... <b>BT230<sup>+</sup></b>	<b>Radial Seal XP Air</b> (ACDelco A2012C)..... <b>RS3548XP</b>	<b>B-P Lube</b> (15525633)..... <b>C750-E<sup>+</sup></b>
<b>B-P Lube Ele.</b> (15525633)..... <b>C750-E<sup>+</sup></b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>F-F Lube</b> (Severe Service) (1R0739)..... <b>B76-SS<sup>+</sup></b>
<b>Fuel/Water Separator</b> (ACDelco TP1519)..... <b>BF7759</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Fuel/Water Separator</b> (w/Drain) (19256911)..... <b>BF5813</b>
<b>Fuel</b> (25010793)..... <b>BF5800<sup>+</sup></b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (19256911)..... <b>BF5813-O<sup>+</sup></b>
<b>O. Air</b> (94048864)..... <b>PA2577</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Fuel</b> (1-12 Thd.) (25014274)..... <b>BF5800<sup>+</sup></b>
<b>I. Air</b> (25096436)..... <b>PA2578</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Fuel</b> (7/8-14 Thd.) (614783)..... <b>BF7632</b>
<b>Trans. Ele. (2 In. Kit)</b> (Allison 29545776)..... <b>PT9416-MPG KIT</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Std. Air</b> (Don. P134353)..... <b>PA2577</b>
<b>Trans. Ele. (4 In. Kit)</b> (Allison 29548988)..... <b>PT9415-MPG KIT</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Radial Seal O. Air</b> (ACDelco A2012C)..... <b>RS3548</b>
<b>Trans. Pan-Type</b> (AT Series, 3.8 In. Pan) (Allison 29540976)..... <b>19992<sup>+</sup></b>		<b>Radial Seal XP O. Air</b> (ACDelco A2012C)..... <b>RS3548XP</b>
<b>Trans. Pan-Type</b> (AT Series, 5.3 In. Pan) (Allison 29538489)..... <b>19739<sup>+</sup></b>		<b>Radial Seal I. Air</b> (Don. P538456)..... <b>RS3722</b>
<b>Trans. Spin-on</b> (AT Series) (Allison 29510922)..... <b>BT8316-MPG</b>		<b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>
<b>Trans. Spin-on</b> (Fuller 4304827)..... <b>BT223</b>		<b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>
		<b>Trans. Spin-on</b> (25011122)..... <b>BT230</b>


<sup>+</sup> See Product Guide for Variations of This Number. <sup>89</sup> Inner Fender Liner Removal Recommended for Proper Installation. Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

CHEVROLET North America Trucks & Vans (cont'd)	CHEVROLET North America Trucks & Vans (cont'd)	CHEVROLET North America Trucks & Vans (cont'd)
T7500 w/Isuzu 6HK1-TC (7.8L) Eng. Lube (94037791)..... <b>B75</b> Fuel/Water Separator (Upgrade) (ACDelco TP3018)..... <b>BF46062</b> <sup>89</sup> Fuel/Water Separator (w/Drain) (15618921)..... <b>BF5813</b> + Fuel/Water Separator (Open End for Bowl) (15618921)..... <b>BF5813-O</b> + Fuel Ele. (8980370110)..... <b>PF9919</b> Fuel Spin-on (94392474)..... <b>BF7602</b> Radial Seal Air (ACDelco A2012C)..... <b>RS3548</b> Radial Seal XP Air (ACDelco A2012C)..... <b>RS3548XP</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2</b> +	W3500 Tiltmaster w/V8-364 (6.0L) Eng. Lube (13/16-16 Thd.) (ACDelco PF46)..... <b>B31</b> Lube (M22 x 1.5 Thd.) (89017524)..... <b>B160</b> Fuel/Water Separator Spin-on (94369299)..... <b>BF7534</b> Fuel In-Line (25055129)..... <b>BF853</b> Std. Air w/Lid (94430250)..... <b>PA2761</b> Radial Seal Air (8970622940)..... <b>RS5434</b> Trans. (4L80-E) (24210956)..... <b>18027</b> W3500 Tiltmaster w/Isuzu 4BD2 (3.9L) Eng. Dual-Flow Lube (2906546000).... <b>BD7166</b> Fuel (5873103350)..... <b>BF7648</b> W3500 Tiltmaster w/Isuzu 4HE1 (4.8L) Eng. Dual-Flow Lube (97148270)..... <b>BD7169</b> Fuel (97714339)..... <b>BF7602</b> Air (94430250)..... <b>PA2761</b> W3500 Tiltmaster w/Isuzu 4HK1 (5.2L) Eng. Dual-Flow Lube (8-97148-270-0) <b>BD7169</b> Fuel/Water Separator (94369299)..... <b>BF7534</b> Fuel (1-13240-079-1)..... <b>BF7602</b> Air (8-94430250-0)..... <b>PA2761</b> W4500 Tiltmaster w/Isuzu 4BD2 (3.9L) Eng. F-F Lube (3 1/32 In. O.D.) (94463715)..... <b>B131</b> F-F Lube (3 11/16 In. O.D.) (94169778)..... <b>B244</b> B-P Lube (94169779)..... <b>B222</b> B-P Lube (94360419)..... <b>B494</b> Fuel Spin-on (94414796)..... <b>[2] BF954</b> + Air (10 1/2 In.) (94156052)..... <b>PA2712</b> Air (13 1/2 In.) (94430250)..... <b>PA2761</b> W4500 Tiltmaster w/Isuzu 4HE1 (4.8L) Eng. Dual-Flow Lube (97148270)..... <b>BD7169</b> Fuel (97714339)..... <b>BF7602</b> Air (94430250)..... <b>PA2761</b> W4500 Tiltmaster w/Isuzu 4HK1 (5.2L) Eng. Dual-Flow Lube (8-97148-270-0) <b>BD7169</b> Fuel/Water Separator (94369299)..... <b>BF7534</b> Fuel (1-13240-079-1)..... <b>BF7602</b> Air (8-94430250-0)..... <b>PA2761</b> W4500 Tiltmaster w/V8-364 (6.0L) Eng. Lube (13/16-16 Thd.) (ACDelco PF46)..... <b>B31</b> Lube (M22 x 1.5 Thd.) (89017524)..... <b>B160</b> Fuel/Water Separator (94369299)..... <b>BF7534</b> Fuel In-Line (25055129)..... <b>BF853</b> Std. Air w/Lid (94430250)..... <b>PA2761</b> Radial Seal Air (8970622940)..... <b>RS5434</b> Trans. (4L80-E) (24210956)..... <b>18027</b>	W5500 Tiltmaster w/Isuzu 4HE1 (4.8L) Eng. Dual-Flow Lube (97148270)..... <b>BD7169</b> Fuel (97714339)..... <b>BF7602</b> Air (94430250)..... <b>PA2761</b> W5500 Tiltmaster w/Isuzu 4HK1 (5.2L) Eng. Dual-Flow Lube (8-97148-270-0) <b>BD7169</b> Fuel/Water Separator (94369299)..... <b>BF7534</b> Fuel (1-13240-079-1)..... <b>BF7602</b> Air (8-94430250-0)..... <b>PA2761</b> W5500 Tiltmaster w/Isuzu 6BG1 (6.5L) Naturally Aspirated Diesel Eng. F-F Lube (1132401220)..... <b>B75</b> B-P Lube (156071860)..... <b>B7124</b> Fuel (1132400791)..... <b>BF7602</b> W5500 Tiltmaster w/Isuzu 6BG1 (6.5L) Turbo Diesel Eng. F-F Lube (1132401220)..... <b>B75</b> B-P Lube (156071860)..... <b>B7124</b> Fuel (1132400791)..... <b>BF7602</b> W5500 Tiltmaster w/Isuzu 6HE1 (7.1L) Eng. Trans. Pan-Type (AT Series, 3.8 In. Pan) (Allison 29540976)..... <b>19992</b> + Trans. Pan-Type (AT Series, 5.3 In. Pan) (Allison 29538489)..... <b>19739</b> + Trans. Spin-on (AT Series) (Allison 29510922)..... <b>BT8316-MPG</b> W5500 Tiltmaster w/Isuzu 6HK1-TC (7.8L) Eng. F-F Lube (1132401220)..... <b>B75</b> W5500HD Tiltmaster w/Isuzu 4HE1 (4.8L) Eng. Fuel..... <b>BF7602</b> W5500HD Tiltmaster w/Isuzu 4HK1 (5.2L) Eng. Dual-Flow Lube (8-97148-270-0) <b>BD7169</b> Fuel/Water Separator (94369299)..... <b>BF7534</b> Fuel (1132400791)..... <b>BF7602</b> Air (8-94430250-0)..... <b>PA2761</b> W6500 Tiltmaster w/Isuzu 6BD1 (5.8L) Eng. F-F Lube (94037791)..... <b>B75</b> B-P Lube Spin-on (94054123).... <b>B7124</b> Fuel (94051085)..... <b>BF7602</b> O. Air (94037810)..... <b>PA2504</b> I. Air (94037809)..... <b>PA2545</b> W7500 Tiltmaster w/Isuzu Eng. F-F Lube (94037791)..... <b>B75</b> B-P Lube Spin-on (94056207).... <b>B7577</b> Fuel (94051085)..... <b>BF7602</b> O. Air (94037810)..... <b>PA2504</b> I. Air (94037809)..... <b>PA2545</b> O. Air (94048865)..... <b>PA2577</b> I. Air (94047568)..... <b>PA2578</b>
T8500 w/Isuzu 6HK1-TC (7.8L) Eng. Lube (94037791)..... <b>B75</b> Fuel/Water Separator (Upgrade) (ACDelco TP3018)..... <b>BF46062</b> <sup>89</sup> Fuel/Water Separator (w/Drain) (15618921)..... <b>BF5813</b> + Fuel/Water Separator (Open End for Bowl) (15618921)..... <b>BF5813-O</b> + Fuel Ele. (8980370110)..... <b>PF9919</b> Fuel Spin-on (94392474)..... <b>BF7602</b> Radial Seal Air (ACDelco A2012C)..... <b>RS3548</b> Radial Seal XP Air (ACDelco A2012C)..... <b>RS3548XP</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2</b> +	W6NO42, W7NO42 w/V8-350 Eng. Lube..... <b>B7</b> 1 1/32 In. Fuel (Rochester Carb.)... <b>PF893</b> 3 15/32 In. Fuel Ele..... <b>PF827</b> Comp. Air..... <b>PA1909</b> W6NO42, W7NO42 w/V8-366, V8-427 Eng. Lube..... <b>B7</b> Fuel Ele..... <b>PF827</b> Air (6422556)..... <b>PA1800</b> + Comp. Air..... <b>PA1909</b> W3500 Tiltmaster w/V8 5.7L Gas Eng. Lube (25160561)..... <b>B1428</b> + Fuel In-Line (25055129)..... <b>BF853</b> 3 15/32 In. Air (6484235)..... <b>PA2008</b> 13 1/2 In. Air (94430250)..... <b>PA2761</b>	W7500 Tiltmaster w/Isuzu South America Trucks 14-190 w/Cat 3116 Eng. Fuel/Water Separator (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b>

+ See Product Guide for Variations of This Number. <sup>89</sup> Inner Fender Liner Removal Recommended for Proper Installation.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).


CHEVROLET South America Trucks (cont'd)	CITROEN European Light Duty Vehicles (cont'd)	CITROEN European Light Duty Vehicles (cont'd)
14-190 w/Cat 3116 Eng. (Cont'd)	Berlingo I 1.4 BiValent (M59) w/TU3JP 75 HP Eng. (04/03-03/10)	Jumper I 2.5 Diesel w/T9A (DJ5) Eng. (09/98-03/02)
Fuel/Water Separator (With Bowl) (Mann WK1060/1).....	Lube Spin-on (To 08/00) (1109N3).....	Lube (1109N3).....
<b>BF46072</b>	<b>B7167</b>	<b>B7167</b>
Fuel/Water Separator (With Drain) (Mann WK1060/1).....	Lube Ele. (1109CK).....	Fuel (190632).....
<b>BF1329</b>	<b>P7450</b>	<b>BF825 +</b>
Fuel/Water Separator (Sensor Port Thread 9/16-18) (Mann WK1060/1).....	Berlingo I 1.4 (M49, M59) w/KFX (TU3JP) Eng. (10/96-03/10)	Air (1444A1).....
<b>BF1329-SP</b>	Lube Spin-on (To 08/00) (1109N3).....	<b>PA3836</b>
Fuel/Water Separator (Sensor Port Thread 1/2-20) (Mann WK1060/1).....	Lube Ele. (1109CK).....	Jumper I 2.5 TurboDiesel w/T8A (DJ5T) Eng. (02/94-08/98)
<b>BF1339-SP +</b>	<b>P7450</b>	Lube (1109K7).....
15-190 w/Cat 3116 Eng.	Berlingo I 1.6 16V (M49, M59) w/NFU (TU5JP4) Eng. (10/00-03/10)	Fuel (190632).....
Fuel/Water Separator (Open End for Bowl) (Mann WK1060/1).....	Lube Spin-on (To 08/00) (1109N3).....	<b>B7042</b>
<b>BF46083-O</b>	Lube Ele. (1109CK).....	<b>BF825 +</b>
Fuel/Water Separator (With Bowl) (Mann WK1060/1).....	<b>B7167</b>	Jumper I 2.5 TurboDiesel w/THX-THZ (DJ5TED) Eng. (09/98-12/00)
<b>BF46072</b>	<b>P7450</b>	Lube (1109N3).....
Fuel/Water Separator (With Drain) (Mann WK1060/1).....	Berlingo II 1.6 (B9) w/TU5JP4 Eng. (04/08-on)	Fuel (Bosch System) (190661).....
<b>BF1329</b>	Lube (1109Z2).....	<b>BF587-D +</b>
Fuel/Water Separator (Sensor Port Thread 9/16-18) (Mann WK1060/1).....	Fuel (N/S).....	<b>BF825 +</b>
<b>BF1329-SP</b>	<b>N/S</b>	Jumper I 2.5 TurboDiesel w/THX-THZ (DJ5TED) Eng. (11/96-08/98)
Fuel/Water Separator (Sensor Port Thread 1/2-20) (Mann WK1060/1).....	Berlingo II 1.6 (B9) w/TU5JP4B Eng. (04/08-on)	Lube (1109K7).....
<b>BF1339-SP +</b>	Lube (1109Z2).....	<b>B7042</b>
16-220 w/Cat 3116 Eng.	Fuel (N/S).....	Fuel (Bosch System) (190661).....
Fuel/Water Separator (Open End for Bowl) (Mann WK1060/1).....	Berlingo II 1.6 Vti 95 (B9) w/EP6CDTR Eng. (08/10-on)	<b>BF587-D +</b>
<b>BF46083-O</b>	Lube (1109Z2).....	<b>BF825 +</b>
Fuel/Water Separator (With Bowl) (Mann WK1060/1).....	Air (1444XG).....	Fuel (CAV) (190632).....
<b>BF46072</b>	<b>P7450</b>	<b>BF825 +</b>
Fuel/Water Separator (With Drain) (Mann WK1060/1).....	<b>PA10336</b>	Jumper I 2.8 HDI w/DW12TED Eng. (09/00-03/02)
<b>BF1329</b>	Berlingo II 1.6 Vti 120 (B9) w/EP6 Eng. (11/09-on)	Dual-Flow Lube (1109J3).....
Fuel/Water Separator (Sensor Port Thread 9/16-18) (Mann WK1060/1).....	Lube (1109Z2).....	<b>BD232</b>
<b>BF1329-SP</b>	Air (1444XG).....	<b>BF7976</b>
Fuel/Water Separator (Sensor Port Thread 1/2-20) (Mann WK1060/1).....	<b>PA10336</b>	Jumper II 2.0 HDI w/DW10TD Eng. (02/02-12/04)
<b>BF1339-SP +</b>	Jumper I 1.9 Diesel w/D9B (XUD9) Eng. (07/99-03/02)	Lube (1109R1).....
	Lube (1109N3).....	<b>B7428</b>
	Fuel (Bosch System) (190661).....	<b>BF7976</b>
	Fuel (CAV) (190632).....	Jumper II 2.0 HDI w/DW10TD Eng. (12/04-on)
	Air (1444A1).....	Lube (1109R1).....
	<b>PA3836</b>	<b>B7428</b>
	Jumper I 1.9 TurboDiesel w/D8C (XUD9TF)-DHX Eng. (04/94-03/02)	Jumper II 2.0 i w/XU10J2 Eng. (02/02-on)
	Lube (1109N3).....	Lube (1109N3).....
	Fuel (190632).....	Fuel (156775).....
	<b>B7167</b>	<b>BF885</b>
	<b>BF825 +</b>	<b>BF1185</b>
	Jumper I 2.0 HDI w/DW10TD Eng. (08/01-03/02)	Jumper II 2.0 i Bipower w/XU10J2 Eng. (02/02-on)
	Lube (1109R1).....	Lube (1109N3).....
	Fuel (190666).....	Fuel (156775).....
	<b>B7428</b>	<b>BF885</b>
	<b>BF7976</b>	<b>BF1185</b>
	Jumper I 2.0 i (4x4) w/RFW (XU10J2U) Eng. (02/94-03/02)	Jumper II 2.2 HDI w/DW12TED Eng. (02/02-12/04)
	Lube (1109N3).....	Lube (1109R1).....
	Fuel (156775).....	Fuel (190666).....
	<b>B7167</b>	<b>B7428</b>
	<b>BF885</b>	<b>BF7976</b>
	Jumper I 2.5 Diesel w/T9A (DJ5) Eng. (02/94-08/98)	Jumper II 2.2 HDI w/DW12TED Eng. (12/04-on)
	Lube (1109K7).....	Lube (1109R1).....
	Fuel (190632).....	<b>B7428</b>
	Air (1444A1).....	<b>BF7976</b>
	<b>PA3836</b>	Jumper II 2.8 HDI w/DW12TED (8140.43S) Eng. (02/02-10/02)
	Berlingo I 1.1 (M49, M59) w/HDZ/HFX (TU1M, TU1JP) Eng. (10/96-03/10)	Dual-Flow Lube (1109J3).....
	Lube Spin-on (To 08/00) (1109N3).....	<b>BD232</b>
	Lube Ele. (1109CK).....	<b>BF7976</b>
	<b>B7167</b>	
	<b>P7450</b>	
	Berlingo I 1.4 BiValent (M59) w/TU3JP 65 HP Eng. (11/02-03/10)	
	Lube Spin-on (To 08/00) (1109N3).....	
	Lube Ele. (1109CK).....	
	<b>B7167</b>	
	<b>P7450</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

CITROEN European Light Duty Vehicles (cont'd)	CITROEN European Light Duty Vehicles (cont'd)	CITROEN European Light Duty Vehicles (cont'd)
Jumper II 2.8 HDI w/DW12TED (8140.43S) Eng. (11/02-10/04) Dual-Flow Lube (1109J3)..... <b>BD232</b>	Jumpl I 1.6 w/220A.2000 Eng. (04/96-01/07) Lube (1109K9)..... <b>B7430</b> Fuel (91535807)..... <b>BF1195</b>	Nemo 1.4 HDI w/DV4TED Eng. (02/08-on) Cab Air (6479E0)..... <b>PA10085</b>
Jumper II 2.8 HDI w/DW12TED (8140.43S) Eng. (11/04-12/04) Lube (1109Y6)..... <b>B7377</b>	Jumpl I 1.9 D w/DW8 (WJZ) / DW8B (WJY) Eng. (04/98-01/07) Lube (1109K9)..... <b>B7430</b>	Xsara 1.8 TD (1997-2005) Lube (W712/8)..... <b>B7167</b> Fuel (P716)..... <b>PF7817</b> Air (From 2/98) (1444.H1)..... <b>PA4388</b>
Jumper II 2.8 HDI w/DW12TED (8140.43S) Eng. (12/04-on) Lube (1109Y6)..... <b>B7377</b>	Jumpl I 1.9 TD w/D8B (XUD9TF) Eng. (04/96-01/07) Lube..... <b>B173-S</b> Lube..... <b>B7167</b> Lube..... <b>B195</b>	Xsara 1.9 D (1997-2005) Lube (W712/8)..... <b>B7167</b> Fuel (P716)..... <b>PF7817</b> Air (10/98-2005) (1444.H1)..... <b>PA4388</b>
Jumper II 2.8 HDI 146 w/DW12UTED Eng. (04/04-10/04) Dual-Flow Lube (1109J3)..... <b>BD232</b>	Jumpl I 1.9 TD w/DHX (XUD9TF) Eng. (04/96-01/07) Lube..... <b>B173-S</b> Lube..... <b>B7167</b> Lube..... <b>B195</b> Fuel (96098964)..... <b>PF7817</b>	Xsara 1.9 TD (1997-2005) Lube (W712/8)..... <b>B7167</b> Fuel (P716)..... <b>PF7817</b> Air (3/98-on) (1444.H1)..... <b>PA4388</b>
Jumper II 2.8 HDI 146 w/DW12UTED Eng. (11/04-12/04) Lube (1109Y6)..... <b>B7377</b>	Jumpl I 2.0 w/RFN (EW10J4) Eng. (04/00-01/07) Lube (1109R1)..... <b>B7428</b>	<b>CITROEN Trucks</b>
Jumper II 2.8 HDI 146 w/DW12UTED Eng. (12/04-on) Lube (1109Y6)..... <b>B7377</b>	Jumpl I 2.0 16V w/RFN (EW10J4) Eng. (03/00-01/07) Lube (1109R1)..... <b>B7428</b>	Models w/Perkins 4.99 Eng. Lube..... <b>P15</b>
Jumper III 2.2 HDI 100 w/4HV Eng. (05/06-on) Lube (1109X4)..... <b>P7450</b> Air (1444QV)..... <b>PA4472</b> Cab Air (6447YC)..... <b>PA5798</b> <sup>90</sup>	Jumpl I 2.0 HDI 95 w/DW10BTED (RHX) Eng. (03/00-01/07) Lube (1109R1)..... <b>B7428</b>	23 w/Perkins 4.192, 4.203 Engs. Lube..... <b>P174</b> Fuel Ele..... <b>PF838</b>
Jumper III 2.2 HDI 120 w/4HU Eng. (05/06-on) Lube (1109X4)..... <b>P7450</b> Air (1444QV)..... <b>PA4472</b> Cab Air (6447YC)..... <b>PA5798</b> <sup>90</sup>	Jumpl I 2.0 HDI 110 w/DW10A/CTED Eng. (03/00-01/07) Lube (1109R1)..... <b>B7428</b>	C25 1.8L, 2.0L Lube (To 1983)..... <b>B195</b> Lube (1983-on) (C2105)..... <b>B7167</b> In-Line Fuel (1983-on)..... <b>BF833</b>
Jumper III 2.2 HDI FAP 110 w/22 DT PUMA Euro 5 Eng. (07/11-on) Lube (1109Z2)..... <b>P7450</b> Air (1444QV)..... <b>PA4472</b> Cabin Air (6447YC)..... <b>PA5798</b> <sup>90</sup>	Jumpl II 2.0 HDI 120 w/DW10UTED4 Eng. (01/07-on) Lube (1109Z2)..... <b>P7450</b>	C25 1.9D, 2.5D Lube (1.9D) (C2105)..... <b>B7167</b> Lube (2.5D) 1983-on (L34480)..... <b>B7042</b> 2 13/16 In. Can-Type Fuel..... <b>BF825 +</b> 4 13/32 In. Can-Type Fuel..... <b>BF884</b> Fuel (1987-on)..... <b>PF7596</b> Air (1987-on)..... <b>PA3836</b>
Jumper III 2.2 HDI FAP 130 w/22 DT PUMA Euro 5 Eng. (07/11-on) Lube (1109Z2)..... <b>P7450</b> Air (1444QV)..... <b>PA4472</b> Cabin Air (6447YC)..... <b>PA5798</b> <sup>90</sup>	Jumpl II 2.0 w/EW10A Eng. (01/07-on) Lube (1109Z2)..... <b>P7450</b>	Jumper 1.9D, 1.9TD, 2.0 Lube (C2105)..... <b>B7167</b> Can-Type Fuel..... <b>BF825 +</b> Air (1.9D)..... <b>PA3836</b>
Jumper III 2.2 HDI FAP 150 w/22 DT PUMA Euro 5 Eng. (07/11-on) Lube (1109Z2)..... <b>P7450</b> Air (1444QV)..... <b>PA4472</b> Cabin Air (6447YC)..... <b>PA5798</b> <sup>90</sup>	Jumpl II 2.0 HDI 140 w/DW10BTED4 Eng. (01/07-on) Lube (1109Z2)..... <b>P7450</b>	Jumper 2.5D Lube (L34480)..... <b>B7042</b> Air..... <b>PA3836</b>
Jumper III 3.0 HDI 160 w/F1C Eng. (05/06-on) Lube (1606267580)..... <b>B7388</b> Air (1444QV)..... <b>PA4472</b> Cab Air (6447YC)..... <b>PA5798</b> <sup>90</sup>	Jumpl II HDI FAP 95 w/DW10CE D5 Eng. (07/01-on) Lube (1109Z2)..... <b>P7450</b>	T45, T55 Fuel Ele..... <b>PF231</b>
Jumper III 3.0 HDI FAP 160 w/F30 DT Euro 5 Eng. (07/11-on) Lube (1606267580)..... <b>B7388</b> Air (1444QV)..... <b>PA4472</b> Cab Air (6447YC)..... <b>PA5798</b> <sup>90</sup>	Jumpl II HDI FAP 125 w/DW10CE E5 Eng. (07/01-on) Lube (1109Z2)..... <b>P7450</b>	<b>COLEMAN Trucks</b>
Jumper III 3.0 HDI FAP F30 DT E5 w/F30 DT ES Eng. (01/10-on) Lube (1606267580)..... <b>B7388</b> Air (1444QV)..... <b>PA4472</b> Cab Air (6447YC)..... <b>PA5798</b> <sup>90</sup>	Nemo 1.3 HDI 75 w/F130DTE5 Eng. (09/10-on) Fuel (1606384980)..... <b>BF46051</b> Cab Air (6479E0)..... <b>PA10085</b>	CF55AF, F55AF, G55S Lube..... <b>P52</b>
	Nemo 1.4 w/TU3A Eng. (02/08-on) Cab Air (6479E0)..... <b>PA10085</b>	G53, G54, G55, G56, G57 w/LO525 Eng. Lube..... <b>P67</b>

\* See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

COLLINS Buses (cont'd)	COLLINS Buses (cont'd)	COLLINS Buses (cont'd)
<b>Bantam w/Ford 5.4L Gas Eng. (Cont'd)</b> <b>Trans.</b> (4R100 D. Pan) (Motorcraft FT114)..... <b>18265</b> <b>Trans.</b> (4R70W) (Motorcraft FT105)..... <b>18029</b> <b>Trans.</b> (5R110W, To 11/07) (Motorcraft FT144)..... <b>20005</b> <b>Trans.</b> (5R110W, 11/07-On) (Motorcraft FT180)..... <b>20021</b> <b>Trans. Ele.</b> (5R110W) (Motorcraft FT145)..... <b>P7247</b>	<b>Bantam w/GM 6.6L Diesel Eng. (Cont'd)</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Steering</b> (88892858)..... <b>P106-HD</b>	<b>Mid Bus w/GM 6.0L Gas Eng.</b> <b>Lube</b> (2003-06) (ACDelco PF46).. <b>B31</b> <b>Lube</b> (2007-on)..... <b>B160</b> <b>Fuel</b> (2003-05 (Thd. Both Ends)) (ACDelco GF652)..... <b>BF853</b> <b>Fuel</b> (2003-05 (Thd. One End)) (ACDelco GF578)..... <b>BF1171</b> <b>Fuel</b> (2006-on) (N/S)..... <b>N/S</b> <b>Radial Seal Air</b> (ACDelco A1621C)..... <b>RS4131</b> <b>Trans.</b> (4L60-E S. Pan) (24200796)..... <b>18010</b> <b>Trans.</b> (4L60-E D. Pan) (24208576)..... <b>18056</b> <b>Trans.</b> (4L80-E) (24210956)..... <b>18027</b>
<b>Bantam w/Ford 6.0L Diesel Eng.</b> <b>Lube</b> (w/o Screw on Cap) (Motorcraft FL2016)..... <b>P7235</b> <b>Lube</b> (w/Screw on Cap) (Wix 57312)..... <b>P7436</b> <b>Fuel</b> (Motorcraft FD4606)..... <b>PF7852 KIT</b> <b>Air</b> (Motorcraft FA1746)..... <b>CA4999</b> <b>Trans. Ele.</b> (Motorcraft FT145)..... <b>P7247</b> <b>Trans. Pan-Type</b> (5R110W, To 11/07) (Motorcraft FT144)..... <b>20005</b> <b>Trans.</b> (5R110W, 11/07-on) (Motorcraft FT180)..... <b>20021</b>	<b>Mid Bus w/Ford 5.4L Gas Eng.</b> <b>Lube</b> (Motorcraft FL820S)..... <b>B329</b> <b>Fuel</b> (Motorcraft FG986B)..... <b>BF7668 +</b> <b>Air</b> (Motorcraft FA1632)..... <b>PA4075</b> <b>Trans.</b> (4R100 S. Pan) (Motorcraft FT113)..... <b>18264</b> <b>Trans.</b> (4R100 D. Pan) (Motorcraft FT144)..... <b>20005</b> <b>Trans.</b> (4R70W) (Motorcraft FT105)..... <b>18029</b> <b>Trans.</b> (5R110W, To 11/07) (Motorcraft FT144)..... <b>20005</b> <b>Trans.</b> (5R110W, 11/07-on) (Motorcraft FT180)..... <b>20021</b> <b>Trans. Ele.</b> (5R110W) (Motorcraft FT145)..... <b>P7247</b>	<b>Mid Bus w/GM 6.6L Diesel Eng.</b> <b>Lube</b> (ACDelco PF2232)..... <b>B1441</b> <b>Fuel/Water Separator</b> (Upgrade) (ACDelco TP3018)..... <b>BF46062 <sup>89</sup></b> <b>Radial Seal Air</b> (ACDelco A2032C)..... <b>RS4859</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Steering</b> (88892858)..... <b>P106-HD</b>
<b>Bantam w/GM 4.8L Gas Eng.</b> <b>Lube</b> (2003-05) (ACDelco PF46).. <b>B31</b> <b>Lube</b> (2006-on)..... <b>B160</b> <b>Fuel</b> (2003-05 (Thd. Both Ends)) (ACDelco GF652)..... <b>BF853</b> <b>Fuel</b> (2003-05 (Thd. One End)) (ACDelco GF578)..... <b>BF1171</b> <b>Fuel</b> (2006-on) (N/S)..... <b>N/S</b> <b>Radial Seal Air</b> (ACDelco A1621C)..... <b>RS4131</b> <b>Trans.</b> (4L60-E S. Pan) (24200796)..... <b>18010</b> <b>Trans.</b> (4L60-E D. Pan) (24208576)..... <b>18056</b> <b>Trans.</b> (4L80-E) (24210956)..... <b>18027</b>	<b>Mid Bus w/Ford 6.0L Diesel Eng.</b> <b>Lube</b> (w/o Screw on Cap) (Motorcraft FL2016)..... <b>P7235</b> <b>Lube</b> (w/Screw on Cap) (Wix 57312)..... <b>P7436</b> <b>Fuel</b> (Motorcraft FD4606)..... <b>PF7852 KIT</b> <b>Channel Flow Air</b> (Motorcraft FA1746)..... <b>CA4999</b> <b>Trans. Ele.</b> (Motorcraft FT145)..... <b>P7247</b> <b>Trans. Pan-Type</b> (To 11/07) (Motorcraft FT144)..... <b>20005</b> <b>Trans. Pan-Type</b> (11/07-on) (Motorcraft FT180)..... <b>20021</b>	<b>COMFORT MASTER</b> <b>Auxiliary Power Units (APU)</b> Models w/Isuzu 3 Cyl. Diesel Eng. <b>Lube</b> (Defense DL7317)..... <b>B1400</b> <b>Lube</b> (Fram PH8A)..... <b>B2 +</b> <b>Lube</b> (Isuzu 13201-2)..... <b>B118</b> <b>Fuel</b> ..... <b>PF981</b> <b>Air</b> ..... <b>CLN&amp;R</b>
<b>Bantam w/GM 6.0L Gas Eng.</b> <b>Lube</b> (2003-06) (ACDelco PF46).. <b>B31</b> <b>Lube</b> (2007-on)..... <b>B160</b> <b>Fuel</b> (2003-05 (Thd. Both Ends)) (ACDelco GF652)..... <b>BF853</b> <b>Fuel</b> (2003-05 (Thd. One End)) (ACDelco GF578)..... <b>BF1171</b> <b>Fuel</b> (2006-on) (N/S)..... <b>N/S</b> <b>Radial Seal Air</b> (ACDelco A1621C)..... <b>RS4131</b> <b>Trans.</b> (4L60-E S. Pan) (24200796)..... <b>18010</b> <b>Trans.</b> (4L60-E D. Pan) (24208576)..... <b>18056</b> <b>Trans.</b> (4L80-E) (24210956)..... <b>18027</b>	<b>Mid Bus w/GM 4.8L Gas Eng.</b> <b>Lube</b> (2003-05) (ACDelco PF46).. <b>B31</b> <b>Lube</b> (2006-on)..... <b>B160</b> <b>Fuel</b> (2003-05 (Thd. Both Ends)) (ACDelco GF652)..... <b>BF853</b> <b>Fuel</b> (2003-05 (Thd. One End)) (ACDelco GF578)..... <b>BF1171</b> <b>Fuel</b> (2006-on) (N/S)..... <b>N/S</b> <b>Radial Seal Air</b> (ACDelco A1621C)..... <b>RS4131</b> <b>Trans.</b> (4L60-E S. Pan) (24200796)..... <b>18010</b> <b>Trans.</b> (4L60-E D. Pan) (24208576)..... <b>18056</b> <b>Trans.</b> (4L80-E) (24210956)..... <b>18027</b>	<b>COMMER</b> <b>Trucks</b> Models w/Dorman Eng. <b>Lube</b> ..... <b>P177</b> <b>Fuel Ele.</b> ..... <b>PF838</b>
<b>Bantam w/GM 6.6L Diesel Eng.</b> <b>Lube</b> (ACDelco PF2232)..... <b>B1441</b> <b>Fuel/Water Separator</b> (Upgrade) (ACDelco TP3018)..... <b>BF46062 <sup>89</sup></b> <b>Radial Seal Air</b> (ACDelco A2032C)..... <b>RS4859</b>	<b>1 1/2 Ton w/Rootes 2.6L Diesel Eng.</b> <b>Lube</b> ..... <b>P174</b> <b>Fuel Ele.</b> ..... <b>PF838</b>	<b>1 1/2, 3 Ton Walk-Thru w/6 Cyl. Gas Eng.</b> <b>Lube</b> ..... <b>P15</b>
	<b>3 Liter 6 Cyl. Gas</b> <b>Lube</b> (1964-on)..... <b>B2 +</b>	<b>3 Ton Walk-Thru w/Perkins 4.203 Diesel Eng.</b> <b>Lube</b> ..... <b>PT108</b> <b>Fuel Ele.</b> ..... <b>PF816-S</b>

+ See Product Guide for Variations of This Number. <sup>89</sup> Inner Fender Liner Removal Recommended for Proper Installation.  
 Check Original Equipment Numbers In Parentheses.


**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>COMMER</b> Trucks (cont'd)	<b>CORBEIL</b> Buses (cont'd)	<b>CORBITT</b> Trucks
3/4 Ton w/Hillman Minx Eng. Lube (1960-on)..... P174	Quantum w/Ford 6.0L Diesel Eng. (Cont'd) Fuel (Motorcraft FD4606)..... PF7852 KIT	Models w/Continental Gas Eng. Lube (1944-47)..... P52
3/4 Ton w/Perkins 4.99 Eng. Lube (1960-on)..... P15 Fuel Ele. (1960-on)..... PF838	Channel Flow Air (Motorcraft FA1746)..... CA4999 Trans. Ele. (Motorcraft FT145).... P7247 Trans. Pan-Type (To 11/07) (Motorcraft FT144)..... 20005 Trans. Pan-Type (11/07-on) (Motorcraft FT180)..... 20021	Models w/Cummins Eng. F-F Lube Bag..... P996 F-F Lube Ele..... P999-HD B-P Lube Ele..... C750-E + Fuel/Water Separator..... BF1212 + 4 3/8 In. Fuel Spin-on..... BF948 + 5 3/4 In. Fuel Spin-on..... BF957 + Breather..... PA643 Turbocharger..... BT112
4, 5, 6 Ton Forward Control w/Perkins C305 Diesel Eng. Lube (To S/N 340103)..... PT12 Lube (S/N 340103-up)..... P15 Fuel Ele..... PF838	Quantum w/GM 4.8L Gas Eng. Lube (2003-05) (ACDelco PF46).. B31 Lube (2006-on)..... B160 Fuel (2003-05 (Thd. Both Ends)) (ACDelco GF652)..... BF853 Fuel (2003-05 (Thd. One End)) (ACDelco GF578)..... BF1171 Fuel (2006-on) (N/S)..... N/S Radial Seal Air (ACDelco A1621C)..... RS4131 Trans. (4L60-E S. Pan) (24200796)..... 18010 Trans. (4L60-E D. Pan) (24208576)..... 18056 Trans. (4L80-E) (24210956)..... 18027	18BG, 18FG, 18TG, 18TQ Lube (1946-50)..... P42
8 CWT Express w/4 Cyl. OHV Eng. Lube..... P174	Quantum w/GM 6.0L Gas Eng. Lube (2003-06) (ACDelco PF46).. B31 Lube (2007-on)..... B160 Fuel (2003-05 (Thd. Both Ends)) (ACDelco GF652)..... BF853 Fuel (2003-05 (Thd. One End)) (ACDelco GF578)..... BF1171 Fuel (2006-on) (N/S)..... N/S Radial Seal Air (ACDelco A1621C)..... RS4131 Trans. (4L60-E S. Pan) (24200796)..... 18010 Trans. (4L60-E D. Pan) (24208576)..... 18056 Trans. (4L80-E) (24210956)..... 18027	22, 24, 28, 35, 40 w/Continental Eng. Lube (1946-52)..... P52
B Series 2-3, 3-4, 2 and 5 Ton; C Series 5-7 Ton; T Series 2-3, 3-4, 5 Ton w/TS3 Diesel Eng Fuel Ele. (To 1957)..... PF838	Quantum w/GM 6.6L Diesel Eng. Lube (ACDelco PF2232)..... B1441 Fuel/Water Separator (Upgrade) (ACDelco TP3018)..... BF46062 <sup>89</sup> Radial Seal Air (ACDelco A2032C)..... RS4859 Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004 Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016 Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003 Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017 Trans. Spin-on (Allison 29539579)..... BT8460 Steering (88892858)..... P106-HD	27TD Lube Sock (1945-50)..... DF408 <sup>90</sup>
COB Sedan Delivery Lube (1964)..... BT223		28TD B-P Lube Ele. (1946-50)..... C750-E +
Q4 Lube..... P15		C666 Lube (1951-56)..... P52
<b>COOK</b> Trucks		D801 Lube Sock (1951-53)..... DF408 <sup>90</sup>
Models w/Cummins Eng. F-F Lube Bag..... P996 F-F Lube Ele..... P999-HD F-F Lube Spin-on..... B196 + B-P Lube Ele..... C750-E + Fuel/Water Separator..... BF1212 + 4 3/8 In. Fuel Spin-on..... BF948 + 5 3/4 In. Fuel Spin-on..... BF957 + 11 7/32 In. Fuel Spin-on..... BF596 + Breather Ele. (w/Turbo) (255963) PA643 Breather Ele. (w/o Turbo) (256837)..... PA1627 Turbocharger..... BT112		G101 Lube (1950-55)..... P42
<b>CORBEIL</b> Buses		G40X46 Lube (1952-55)..... P53
Quantum w/Ford 5.4L Gas Eng. Lube (Motorcraft FL820S)..... B329 Fuel (Motorcraft FG986B)..... BF7668 + Air (Motorcraft FA1634)..... PA4075 Trans. (4R100 S. Pan) (Motorcraft FT113)..... 18264 Trans. (4R100 D. Pan) (Motorcraft FT114)..... 18265 Trans. (4R70W) (Motorcraft FT105)..... 18029 Trans. (5R110W, To 11/07) (Motorcraft FT144)..... 20005 Trans. (5R110W, 11/07-on) (Motorcraft FT180)..... 20021 Trans. Ele. (5R110W) (Motorcraft FT145)..... P7247		G301, G302, G601, G602, G603 Lube (1950-56)..... P52
Quantum w/Ford 6.0L Diesel Eng. Lube (w/o Screw on Cap) (Motorcraft FL2016)..... P7235 Lube (w/Screw on Cap) (Wix 57312)..... P7436		G402 Lube (1950-on)..... P52

**CRANE CARRIER COMPANY**  
Chassis & Trucks

Centurion w/Detroit Diesel Series 40 Eng. Lube (23529744)..... B7030 Conical Air (Don. P129472)..... PA2500 + Air Dryer (AD-9 System) (Bendix 107796)..... BA5377 Trans. Ele. (Allison 29538489).... 19739 + Trans. Spin-on (Allison 29510922)..... BT8316-MPG
Centurion w/John Deere 8.1L CNG Eng. Lube Ele. (RE509672)..... P7233 Lube Spin-on (RE57394)..... BT486 Trans. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT
CNG w/Cummins C8.3G Eng. Trans. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT

+ See Product Guide for Variations of This Number. <sup>89</sup> Inner Fender Liner Removal Recommended for Proper Installation. <sup>90</sup> Obsolete Pending. Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



CRANE CARRIER COMPANY Chassis & Trucks (cont'd)	CRANE CARRIER COMPANY Chassis & Trucks (cont'd)	CRANE CARRIER COMPANY Chassis & Trucks (cont'd)
CNG w/JD 8.1L CNG Eng. <b>Lube Ele.</b> (RE509672)..... <b>P7233</b> <b>Lube Spin-on</b> (RE57394)..... <b>BT486</b> <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Low Entry w/Cat C7 (7.2L) Eng. (1/2004-on) <b>Lube</b> (1R1807)..... <b>B7700 +</b> <b>Fuel</b> (1R0751)..... <b>BF7632</b> <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Low Entry w/Cummins ISB (5.9L) Eng. (Cont'd) <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b>
Drill Rig DR/IR w/Cat 3126 Eng. <b>Lube</b> (1R-1807)..... <b>B7700 +</b> <b>Fuel</b> (1R-0751)..... <b>BF7632</b> <b>Coolant</b> (4 Units BTW) (9N-3368) <b>BW5137</b> <b>Coolant</b> (8 Units BTE) (9N-3367) <b>BW5139</b> <b>Trans.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	Low Entry w/Cat C9 (8.8L) Eng. (To 1/2004) <b>Lube</b> (1R0716)..... <b>B99 +</b> <b>Fuel</b> (1R0751)..... <b>BF7632</b> <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Low Entry w/Cummins ISB 5.9 (5.9L) Eng. <b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b> <b>Air</b> (Don. P116918)..... <b>PA2317 +</b> <b>Opt. Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b>
Low Entry w/Cat 3126 (7.2L) Eng. (To 1/2004) <b>Lube</b> (Standard Vers.) (1R0739).. <b>B76 +</b> <b>Lube</b> (Severe Service) (1R0739).. <b>B76-SS +</b> <b>Fuel</b> (1R0751)..... <b>BF7632</b> <b>Air</b> (Don. P116918)..... <b>PA2317 +</b> <b>Conical Air</b> (Don. P140822)..... <b>PA2500 +</b> <b>Opt. Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b>	Low Entry w/Cat C9 (8.8L) Eng. (1/2004-on) <b>Lube</b> (1R1808)..... <b>B7299 +</b> <b>Fuel</b> (1R0751)..... <b>BF7632</b> <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Low Entry w/Cummins ISC 8.3 (8.3L) Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel</b> (Fleetguard FF5488)..... <b>BF7815</b> <b>Conical Air</b> (Don. P140822)..... <b>PA2500 +</b> <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
Low Entry w/Cat 3126 (7.2L) Eng. (1/2004-on) <b>Lube</b> (1R1807)..... <b>B7700 +</b> <b>Fuel</b> (1R0751)..... <b>BF7632</b> <b>Air</b> (Don. P116918)..... <b>PA2317 +</b> <b>Conical Air</b> (Don. P140822)..... <b>PA2500 +</b> <b>Opt. Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b>	Low Entry w/Cat C10 (10.3L) Eng. <b>Lube</b> (1R0716)..... <b>B99 +</b> <b>Lube</b> (High Efficiency) (1R1808).. <b>B7299 +</b> <b>Fuel</b> (1R1712)..... <b>BF614 +</b> <b>Fuel</b> (High Efficiency) (1R0749).... <b>BF7587 +</b> <b>Air</b> (Don. P116918)..... <b>PA2317 +</b> <b>Conical Air</b> (Don. P140822)..... <b>PA2500 +</b> <b>Opt. Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (Nelson 83804E)..... <b>P528</b>	Low Entry w/Cummins ISL 8.9 (8.9L) Eng. (2002-14) <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel</b> (Fleetguard FF5488)..... <b>BF7815</b> <b>Conical Air</b> (Don. P140822)..... <b>PA2500 +</b> <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (Nelson 83804E)..... <b>P528</b>
Low Entry w/Cat 3126 (7.2L) Eng. (1/2004-on) <b>Lube</b> (1R1807)..... <b>B7700 +</b> <b>Fuel</b> (1R0751)..... <b>BF7632</b> <b>Air</b> (Don. P116918)..... <b>PA2317 +</b> <b>Conical Air</b> (Don. P140822)..... <b>PA2500 +</b> <b>Opt. Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b>	Low Entry w/Cat C11 (11.1L) Eng. (To 1/2004) <b>Lube</b> (1R0716)..... <b>B99 +</b> <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Low Entry w/Cummins ISL 8.9 (8.9L) Eng. (2018) <b>Lube</b> (Fleetguard LF9009)..... <b>B40142</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b>
Low Entry w/Cat C7 (7.2L) Eng. (To 1/2004) <b>Lube</b> (Standard Vers.) (1R0739).. <b>B76 +</b> <b>Lube</b> (Severe Service) (1R0739).. <b>B76-SS +</b> <b>Fuel</b> (1R0751)..... <b>BF7632</b> <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Low Entry w/Cat C11 (11.1L) Eng. (1/2004-on) <b>Lube</b> (1R1808)..... <b>B7299 +</b> <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Low Entry w/Cummins ISL 8.9 (8.9L) Eng. (2019) <b>Lube</b> (3401544)..... <b>B40142</b> <b>Fuel</b> (5303743)..... <b>BF63000</b>
Low Entry w/Cat C7 (7.2L) Eng. (To 1/2004) <b>Lube</b> (Standard Vers.) (1R0739).. <b>B76 +</b> <b>Lube</b> (Severe Service) (1R0739).. <b>B76-SS +</b> <b>Fuel</b> (1R0751)..... <b>BF7632</b> <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Low Entry w/Cummins ISB (5.9L) Eng. <b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b> <b>Air</b> (Don. P116918)..... <b>PA2317 +</b> <b>Opt. Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b>	Low Entry w/Cummins ISL-G (8.9L) Eng. (2018) <b>Lube</b> (Fleetguard LF9009)..... <b>B40142</b> <b>Fuel/Water Separator</b> (Fleetguard NG5900)..... <b>BF7695</b>
		Low Entry w/Cummins ISL-G (8.9L) Eng. (2019) <b>Lube</b> (Fleetguard LF9009)..... <b>BD7309</b> <b>Fuel/Water Separator</b> (Fleetguard NG5900)..... <b>BF7695</b>


\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

CRANE CARRIER COMPANY Chassis & Trucks (cont'd)	CRANE CARRIER COMPANY Chassis & Trucks (cont'd)	CRANE CARRIER COMPANY Chassis & Trucks (cont'd)
Low Entry w/Cummins ISL-G (8.9L) Eng. (2019) (Cont'd) <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b>	Low Entry w/IHC DT466E Eng. <b>F-F Lube</b> (1819452-C1)..... <b>B7030</b> <b>Dual-Flow Lube</b> (1842655-C91).. <b>BD7252</b> <b>Fuel/Water Separator</b> (Racor 2020PM)..... <b>PF7890-30</b> <b>Conical Air</b> (Don. P140822)..... <b>PA2500</b> + <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (Nelson 83804E)..... <b>P528</b>	LDT2 w/Cat C11 Eng. (Cont'd) <b>Radial Seal O. Air</b> (w/Plastic Shield) (Don. P777868)..... <b>RS3870</b> + <b>Radial Seal XP O. Air</b> (w/Plastic Shield) (Don. P777868)..... <b>RS3870XP</b> + <b>Radial Seal O. Air</b> (w/o Plastic Shield) (Don. P777868)..... <b>RS4638</b> + <b>Radial Seal I. Air</b> (Don. P777869)..... <b>RS3871</b> + <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
Low Entry w/Cummins ISM 10.8 (10.8L) Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154</b> + <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Conical Air</b> (Don. P140822)..... <b>PA2500</b> + <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (Nelson 83804E)..... <b>P528</b>	Low Entry Drop Frame w/Cummins ISL 8.9 (8.9L) Eng. (2018) <b>Lube</b> (3401544)..... <b>B40142</b> <b>Fuel</b> (5303743)..... <b>BF63000</b>	LDT2 w/Cummins ISC Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309</b> + <b>Fuel</b> (Fleetguard FF5488)..... <b>BF7815</b> <b>Radial Seal O. Air</b> (w/Plastic Shield) (Don. P777868)..... <b>RS3870</b> + <b>Radial Seal XP O. Air</b> (w/Plastic Shield) (Don. P777868)..... <b>RS3870XP</b> + <b>Radial Seal O. Air</b> (w/o Plastic Shield) (Don. P777868)..... <b>RS4638</b> + <b>Radial Seal I. Air</b> (Don. P777869)..... <b>RS3871</b> + <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
Low Entry w/Cummins ISX 11.9 (11.9L) Eng. (2018) <b>Dual-Flow Lube</b> (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel</b> (Fleetguard FF5776)..... <b>BF9885</b>	Low Entry Drop Frame w/Cummins ISL 8.9 (8.9L) Eng. (2019) <b>Lube</b> (3401544)..... <b>B40142</b> <b>Fuel</b> (5303743)..... <b>BF63000</b>	LDT2 w/Cummins ISL Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309</b> + <b>Fuel</b> (Fleetguard FF5488)..... <b>BF7815</b> <b>Radial Seal O. Air</b> (w/Plastic Shield) (Don. P777868)..... <b>RS3870</b> + <b>Radial Seal XP O. Air</b> (w/Plastic Shield) (Don. P777868)..... <b>RS3870XP</b> + <b>Radial Seal O. Air</b> (w/o Plastic Shield) (Don. P777868)..... <b>RS4638</b> + <b>Radial Seal I. Air</b> (Don. P777869)..... <b>RS3871</b> + <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
Low Entry w/Cummins ISX 11.9 (11.9L) Eng. (2019) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel</b> (2893612)..... <b>BF9885</b>	LDT2 w/Cat C7 Eng. <b>Lube</b> (To 1/2004 (Std. Version)) (1R0739)..... <b>B76</b> + <b>Lube</b> (1/2004-on) (1R1807)..... <b>B7700</b> + <b>Lube</b> (To 1/2004 (Severe Service)) (1R0739)..... <b>B76-SS</b> + <b>Fuel</b> (1R0751)..... <b>BF7632</b> <b>Radial Seal O. Air</b> (w/Plastic Shield) (Don. P777868)..... <b>RS3870</b> + <b>Radial Seal XP O. Air</b> (w/Plastic Shield) (Don. P777868)..... <b>RS3870XP</b> + <b>Radial Seal O. Air</b> (w/o Plastic Shield) (Don. P777868)..... <b>RS4638</b> + <b>Radial Seal I. Air</b> (Don. P777869)..... <b>RS3871</b> + <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	LDT2 w/Cummins ISL Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309</b> + <b>Fuel</b> (Fleetguard FF5488)..... <b>BF7815</b> <b>Radial Seal O. Air</b> (w/Plastic Shield) (Don. P777868)..... <b>RS3870</b> + <b>Radial Seal XP O. Air</b> (w/Plastic Shield) (Don. P777868)..... <b>RS3870XP</b> + <b>Radial Seal O. Air</b> (w/o Plastic Shield) (Don. P777868)..... <b>RS4638</b> + <b>Radial Seal I. Air</b> (Don. P777869)..... <b>RS3871</b> + <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
Low Entry w/Cummins ISX 11.9G (11.9L) Eng. (2018) <b>Lube</b> (4367100)..... <b>BD50000</b> <b>Coolant</b> (3680434)..... <b>B5087</b>	LDT2 w/Cat C9 Eng. <b>Lube</b> (To 1/2004) (1R0716)..... <b>B99</b> + <b>Lube</b> (1/2004-on) (1R1808)..... <b>B7299</b> + <b>Fuel</b> (1R0751)..... <b>BF7632</b> <b>Radial Seal O. Air</b> (w/Plastic Shield) (Don. P777868)..... <b>RS3870</b> + <b>Radial Seal XP O. Air</b> (w/Plastic Shield) (Don. P777868)..... <b>RS3870XP</b> + <b>Radial Seal O. Air</b> (w/o Plastic Shield) (Don. P777868)..... <b>RS4638</b> + <b>Radial Seal I. Air</b> (Don. P777869)..... <b>RS3871</b> + <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	LDT2 w/Cummins ISM Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154</b> + <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Radial Seal O. Air</b> (w/Plastic Shield) (Don. P777868)..... <b>RS3870</b> + <b>Radial Seal O. Air</b> (w/o Plastic Shield) (Don. P777868)..... <b>RS4638</b> + <b>Radial Seal XP O. Air</b> (w/Plastic Shield) (Don. P777868)..... <b>RS3870XP</b> + <b>Radial Seal I. Air</b> (Don. P777869)..... <b>RS3871</b> +
Low Entry w/Cummins L9 (9.0L) Eng. (2020) <b>Lube</b> (5444774)..... <b>B40142</b> <b>Fuel</b> (5303743)..... <b>BF63000</b>	Low Entry w/Cummins L9 (9.0L) Eng. (2021) <b>Lube</b> (5444774)..... <b>B40142</b> <b>Fuel</b> (5303743)..... <b>BF63000</b>	
Low Entry w/Cummins L9 (9.0L) Eng. (2021) <b>Lube</b> (Fleetguard LF14002NN)..... <b>B40142</b> <b>Fuel</b> (Fleetguard NG5900)..... <b>BF7695</b>	Low Entry w/Cummins L9N (8.9L) Eng. (2021) <b>Lube</b> (Fleetguard LF14002NN)..... <b>B40142</b> <b>Fuel</b> (Fleetguard NG5900)..... <b>BF7695</b>	
Low Entry w/Cummins L10 (10.0L) Eng. <b>Conical Air</b> (Don. P140822)..... <b>PA2500</b> + <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (Nelson 83804E)..... <b>P528</b>	Low Entry w/Cummins L10 (10.0L) Eng. <b>Conical Air</b> (Don. P140822)..... <b>PA2500</b> + <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (Nelson 83804E)..... <b>P528</b>	
Low Entry w/Cummins X12 (11.9L) Eng. (2021) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel</b> (5365988)..... <b>BF46129</b>	Low Entry w/Detroit Diesel Series 50 (8.5L) Eng. <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	
	LDT2 w/Cat C11 Eng. <b>Lube</b> (To 1/2004) (1R0716)..... <b>B99</b> + <b>Lube</b> (1/2004-on) (1R1808)..... <b>B7299</b> +	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>CRANE CARRIER COMPANY</b> Chassis & Trucks (cont'd)	<b>CRANE CARRIER COMPANY</b> Chassis & Trucks (cont'd)	<b>CUB CADET</b> Buses
LDT2 w/Cummins ISM Eng. (Cont'd) Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	M2000 w/Cat 3176 Eng. Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Models w/Ford L-Head Eng. Lube..... <b>P41</b>
LWT w/Cat C10 Eng. Lube (1R0716)..... <b>B99 +</b> Lube (High Efficiency) (1R1808).. <b>B7299 +</b> Fuel (1R1712)..... <b>BF614 +</b> Fuel (High Efficiency) (1R0749).... <b>BF7587 +</b> Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	M2000 w/IHC DT466 Eng. F-F Lube (1819452-C1)..... <b>B7030</b> Dual-Flow Lube (1842655-C91).. <b>BD7252</b> Trans. Pan-Type (Allison 29538489)..... <b>19739 +</b> Trans. Spin-on (Allison 29510922)..... <b>BT8316-MPG</b>	<b>CUMMINS</b> <b>Auxiliary Power Units (APU)</b> Comfort Guard w/Kubota Z482 Eng. Lube (Fleetguard LF3490)..... <b>B7139</b> Fuel/Water Separator (Fleetguard FS19709)..... <b>BF1267</b> Pre-Fuel (Fleetguard FF149)..... <b>BF840-K1 +</b> Radial Seal Air (140-3071)..... <b>RS3715</b>
LWT w/Cat 3126E Eng. Lube (Std. Version) (1R0739)..... <b>B76 +</b> Lube (High Efficiency) (1R1807).. <b>B7700 +</b> Lube (Severe Service) (1R0739).. <b>B76-SS +</b> Fuel (1R0751)..... <b>BF7632</b> Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	M-4000T w/Cat 3126E Eng. Lube (To 1/2004 (Std. Version)) (1R0739)..... <b>B76 +</b> Lube (1/2004-on) (1R1807)..... <b>B7700 +</b> Lube (To 1/2004 (Severe Service)) (1R0739)..... <b>B76-SS +</b> Fuel (1R0751)..... <b>BF7632</b> Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>CUMMINS</b> <b>Engines</b> 4B3.9, 4BT3.9, 4BTA3.9 Lube (3903224)..... <b>BT427 +</b> Opt. Fuel/Water Separator (3903202)..... <b>BF1226</b> Fuel (3903640)..... <b>BF788</b> 6B5.9, 6BT5.9, 6BTA5.9 Lube (To 1998) (3914395)..... <b>BT339 +</b> P. Fuel/Water Separator (3925274)..... <b>BF1280 +</b> Opt. Fuel/Water Separator..... <b>BF1226</b> S. Fuel (3903640)..... <b>BF788</b>
LWT w/Cummins ISC Eng. Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309 +</b> Fuel (Fleetguard FF5488)..... <b>BF7815</b> Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>CROWN COACH</b> <b>Buses</b> Models w/GMC 6-71N, 6V-71, 8V-71 Eng. F-F Lube Ele..... <b>P20-HD +</b> Std. B-P Lube..... <b>P52</b> P. Fuel Sock (5574961)..... <b>F916-C</b> P. Fuel Ele. (5575032)..... <b>PF845</b> S. Fuel Ele. (5574508)..... <b>PF902</b>	6C8.3, 6CT8.3, 6CTA8.3 F-F Lube (3313281)..... <b>B205 +</b> Dual-Flow Lube (3318853)..... <b>BD103 +</b> Opt. Fuel/Water Separator (3903202)..... <b>BF1226</b> P. Fuel/Water Separator (3925274)..... <b>BF1280 +</b> S. Fuel (3903640)..... <b>BF788</b>
LWT w/Cummins ISL Eng. Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309 +</b> Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Models w/IHC RD450 Eng. B-P Lube Sock..... <b>CU406<sup>90</sup></b> A501-10, A501-11 B-P Lube Sock (1956-61)..... <b>CU406<sup>90</sup></b> A590-10, A590-11 Lube Sock (1956-66)..... <b>V1240-C</b> A779-11 Lube Sock (1956-61)..... <b>V1240-C</b>	V6-140 F-F Lube (1965-on)..... <b>P998</b> Axial Seal Air..... <b>PA1866</b>
LWT w/Cummins ISM Eng. Dual-Flow Lube (Fleetguard LF9001)..... <b>BD7154 +</b> Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	School Bus w/Detroit Diesel 6-71 (7.0L) Eng. F-F Lube Ele..... <b>P20-HD +</b> Std. B-P Lube..... <b>P52</b> P. Fuel Sock (5574961)..... <b>F916-C</b> P. Fuel Ele. (5575032)..... <b>PF845</b> S. Fuel Ele. (5574508)..... <b>PF902</b>	V6-150 F-F Lube Ele..... <b>P998</b> B-P Lube Ele..... <b>C704-L +</b> B-P Lube Spin-on..... <b>B7577</b> Fuel Spin-on..... <b>BF957 +</b> Coolant..... <b>BW5071</b>
M2000 w/Cat 3126E Eng. Lube (To 1/2004 (Std. Version)) (1R0739)..... <b>B76 +</b> Lube (1/2004-on) (1R1807)..... <b>B7700 +</b> Lube (To 1/2004 (Severe Service)) (1R0739)..... <b>B76-SS +</b> Fuel (1R0751)..... <b>BF7632</b> Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	AD743-11, AD743-T11 w/Cummins Eng. F-F Lube Bag..... <b>P996</b> F-F Lube Ele..... <b>P999-HD</b> B-P Lube Ele..... <b>C750-E +</b> Fuel/Water Separator..... <b>BF1212 +</b> 4 3/8 In. Fuel Spin-on..... <b>BF948 +</b> 5 3/4 In. Fuel Spin-on..... <b>BF957 +</b> Breather..... <b>PA643</b> Turbocharger..... <b>BT112 +</b>	VT155 F-F Lube Spin-on..... <b>B205 +</b> B-P Lube Ele..... <b>C704-L +</b> Fuel Spin-on..... <b>BF957 +</b> Coolant..... <b>BW5071</b>
		V8E 170 Axial Seal Air..... <b>PA1867</b>
		V8-185 F-F Lube (1965-on)..... <b>P998</b> Axial Seal Air..... <b>PA1867</b>
		V8-210 F-F Lube Ele..... <b>P998</b> B-P Lube Ele..... <b>C704-L +</b> B-P Lube Spin-on..... <b>B7577</b> Fuel Spin-on..... <b>BF957 +</b> Coolant..... <b>BW5071</b>

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.


Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

CUMMINS Engines (cont'd)	CUMMINS Engines (cont'd)	CUMMINS Engines (cont'd)
VT210 F-F Lube Spin-on..... B205 + B-P Lube Ele..... C704-L + Fuel Spin-on..... BF957 + Coolant..... BW5071	Formula 400 Big Cam IV F-F Lube Spin-on..... B196 + B-P Lube Spin-on..... B7577 Dual-Flow Lube..... BD103 + Opt. Fuel/Water Separator..... BF1212 + Fuel Spin-on..... BF957 +	ISB Series (6.7L) (Cont'd) Fuel/Water Separator (Dodge Ram) (Fleetguard FS43255)..... PF9870 Fuel (Fleetguard FF5421)..... BF7966 Fuel (Fleetguard FF5632)..... BF7940 Crankcase Breather (Fleetguard CV52001)..... CV15010
NH230 F-F Lube Ele..... P999-HD F-F Lube Spin-on..... B196 + B-P Lube Spin-on..... B7577 Fuel Spin-on..... BF957 + Breather (Fleetguard AF250)..... PA643 Coolant..... BW5071	Formula 525, KTA525 F-F Lube Spin-on..... [2] B196 + B-P Lube Ele..... C750-E + B-P Lube Spin-on..... B7577 Fuel Spin-on..... [2] BF957 + Coolant..... BW5073	ISB4 Lube (4897898)..... BT7237 Fuel (4897833)..... BF7813
Formula 230, NTC230, NTC230S F-F Lube Ele..... P999-HD B-P Lube Ele..... C750-E + Fuel Spin-on..... BF957 + Opt. Air (3001690)..... PA616 Coolant..... BW5071	B6.7 Lube (3937736)..... B7177 Fuel (Fleetguard FF63009)..... BF63000 Crankcase Breather (4936636)..... CV15010	ISBE Lube (4897898)..... BT7237 Fuel/Water Separator (Fleetguard FS19584)..... BF7941 Fuel/Water Separator (Fleetguard FS19689)..... BF7942 Fuel (4897833)..... BF7813
VT240 F-F Lube Spin-on..... B205 + Fuel Spin-on..... BF957 + Coolant..... BW5071	B Gas Plus Lube (Fleetguard LF3894)..... BT7349	ISC Series (8.3L) Dual-Flow Lube (Fleetguard LF9009)..... BD7309 + Lube (Upgrade) (3401544)..... B40142 Dual-Flow Lube (Fleetguard LF9548)..... BD324 + Opt. Dual-Flow Lube (Fleetguard LF3000)..... BD103 + Fuel/Water Separator (3800394)..... BF1272-SPS Fuel/Water Separator (Fleetguard FS1065)..... BF1378-SPS Fuel/Water Separator (3942533)..... BF1271 Fuel/Water Separator (Fleetguard FS1003)..... BF1293-SPS Fuel (Fleetguard FF5488)..... BF7815 Fuel (Fleetguard FF5636)..... BF7924 Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071 Coolant (w/12 Units BTA+) (Fleetguard WF2074)..... BW5074 Coolant (w/23 Units BTA+) (Fleetguard WF2076)..... BW5076 Coolant (Controlled Release) (Fleetguard WF2121)..... BW5250
Formula 240, NTC240, PT240 F-F Lube Spin-on..... B196 + B-P Lube Ele..... C750-E + B-P Lube Spin-on..... B7577 Fuel Spin-on..... BF957 + Coolant..... BW5071	C Gas Plus Dual-Flow Lube (Fleetguard LF9009)..... BD7309 + Coolant (Fleetguard WF2073)..... BW5073 Coolant (Fleetguard WF2071)..... BW5071	ISF 2.8 Lube (Fleetguard LF17356)..... B40051 Diesel Exhaust Fluid (5303604)..... PE17000
Formula 250, NHH250 F-F Lube Ele..... P999-HD B-P Lube Ele..... C750-E + Fuel Spin-on..... BF957 + Coolant..... BW5071	Fleet 270, Formula 270, NTC270CT, PT270 F-F Lube Ele..... P999-HD F-F Lube Spin-on..... B196 + B-P Lube Ele..... C750-E + B-P Lube Spin-on..... B7577 Fuel Spin-on..... BF957 + Opt. Air (3001690)..... PA616 Coolant..... BW5071	ISL Series (8.9L) Dual-Flow Lube (Fleetguard LF9009)..... BD7309 + Lube (Upgrade) (3401544)..... B40142 Dual-Flow Lube (Fleetguard LF9548)..... BD324 + Opt. Dual-Flow Lube (Fleetguard LF3000)..... BD103 + Fuel/Water Separator (Fleetguard FS1022)..... BF1272-SPS Fuel/Water Separator (Fleetguard FS1065)..... BF1378-SPS Fuel/Water Separator (Fleetguard FS1003)..... BF1293-SPS
Formula 290, NHHTC290, NHHTCC290, NTC290, NTCC290 F-F Lube Ele..... P999-HD F-F Lube Spin-on..... B196 + B-P Lube Ele..... C750-E + 4 3/8 In. Fuel Spin-on..... BF948 + 5 9/32 In. Fuel Spin-on..... BF957 + Coolant..... BW5071	ISB Series (3.9L) Lube (4897898)..... BT7237 Fuel (4897833)..... BF7813	
Power Torque 300D, NT310, Power Torque 330D F-F Lube Ele..... P999-HD F-F Lube Spin-on..... B196 + B-P Lube Ele..... C750-E + Fuel Spin-on..... BF957 + Opt. Air (3001690)..... PA616 Coolant..... BW5071	ISB Series (5.9L) Lube (3937736)..... B7177 Lube (4897898)..... BT7237 Fuel/Water Separator Ele. (Dodge 1997-99) (Fleetguard FS19528)..... PF7751 Fuel/Water Separator Ele..... PF7777 Fuel/Water Separator Spin-on (3942533)..... BF1271 Fuel/Water Separator Spin-on (Fleetguard FS19596)..... BF1293-SPS Fuel/Water Separator Spin-on (Fleetguard FS1065)..... BF1378-SPS Fuel (Fleetguard FF5632)..... BF7940 Crankcase Breather (1/07-on) (4936636)..... CV15010	
Power Torque 315 Dual-Flow Lube..... BD103 + Fuel Spin-on..... BF957-D +	ISB Series (6.7L) Lube (3937736)..... B7177 Lube (Dodge Ram) (Fleetguard LF3972)..... BT7349 Fuel/Water Separator (Fleetguard FS1065)..... BF1378-SPS	
Formula 365, NTC365 Dual-Flow Lube..... BD103 + Fuel Spin-on..... BF957-D +		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

CUMMINS Engines (cont'd)	CUMMINS Engines (cont'd)	CUMMINS Engines (cont'd)
ISL Series (8.9L) (Cont'd)	ISX Series (11.9L)	ISX Series (15.0L) (Cont'd)
<b>Fuel</b> (Fleetguard FF5488)..... <b>BF7815</b>	<b>Dual-Flow Lube</b> (2002 & 2014 Emissions) (Fleetguard LF9000)... <b>BD7153 +</b>	<b>Fuel</b> (Upgrade) (FF5825NN)..... <b>BF46129</b>
<b>Fuel</b> (Fleetguard FF5636)..... <b>BF7924</b>	<b>Dual-Flow Lube</b> (2007, 2010 & 2014 Emissions) (Fleetguard LF9001)..... <b>BD7154 +</b>	<b>Breather</b> (3683918)..... <b>CV15000</b>
<b>Fuel</b> (2014 Emissions) (Hex Drive Base) (Fleetguard FF63009) <b>BF63000</b>	<b>Dual-Flow Lube</b> (Upgrade, 2017-on) (Fleetguard LF14000NN) <b>BD50000</b>	<b>Coolant</b> (w/o Chemical) (Fleetguard WF2127)..... <b>B5087</b>
<b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>	<b>Dual-Flow Lube</b> (2014 Emissions) (Fleetguard LF9009)... <b>BD7309 +</b>	<b>Coolant</b> (w/11 1/2 Units BTA+) (Fleetguard WF2126)..... <b>BW5086</b>
<b>Coolant</b> (Controlled Release) (Fleetguard WF2121)..... <b>BW5250</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19729)..... <b>PF7755</b>	<b>Coolant</b> (Controlled Release) (Fleetguard WF2121)..... <b>BW5250</b>
<b>Diesel Exhaust Fluid</b> (2880298).. <b>PE17000</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19764)..... <b>PF9814</b>	ISX 11.9G (11.9L)
ISL9 (8.9L)	<b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1000)..... <b>BF1259</b>	<b>Lube</b> (3401544)..... <b>BD7309</b>
<b>Lube</b> (3401544)..... <b>BD7309</b>	<b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1007)..... <b>BF1274-SP</b>	<b>Lube</b> (Upgrade) (3401544)..... <b>B40142</b>
<b>Lube</b> (Upgrade) (3401544)..... <b>B40142</b>	<b>S. Fuel</b> (2010 & 2014 Emissions) (Fleetguard FF5776)..... <b>BF9885 +</b>	ISX 565, ISX 600
ISL-G Natural Gas (8.9L)	<b>Fuel</b> (Upgrade) (FF5825NN)..... <b>BF46129</b>	<b>Dual-Flow Lube</b> ..... <b>BD7153 +</b>
<b>Dual-Flow Lube</b> (Fleetguard LF3000)..... <b>BD103 +</b>	<b>Coolant</b> (w/11 1/2 Units BTA+) (Fleetguard WF2126)..... <b>BW5086</b>	<b>Fuel/Water Separator</b> ..... <b>BF1274-SP</b>
<b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b>	<b>Coolant</b> (w/o Chemical) (Fleetguard WF2127)..... <b>B5087</b>	ISX-G (11.9L)
<b>Lube</b> (Upgrade) (3401544)..... <b>B40142</b>	<b>Diesel Exhaust Fluid</b> (2888182).. <b>PE17000</b>	<b>Dual-Flow Lube</b> (Upgrade, 2017-on) (Fleetguard LF14000NN) <b>BD50000</b>
<b>Fuel</b> (Fleetguard NG5900)..... <b>BF7695</b>	ISX Series (15.0L)	<b>Dual-Flow Lube</b> (2882674)..... <b>BD7154 +</b>
<b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>	<b>Dual-Flow Lube</b> (2007 Emissions) (Fleetguard LF9001)... <b>BD7154 +</b>	<b>Fuel</b> (3607140)..... <b>BF7695</b>
<b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b>	<b>Dual-Flow Lube</b> (Upgrade, 2017-on) (Fleetguard LF14000NN) <b>BD50000</b>	ISX-G (15.0L)
ISM Series (10.8L)	<b>Dual-Flow Lube</b> (2007 Emissions) (Fleetguard LF9031)... <b>BD7509 +</b>	<b>Dual-Flow Lube</b> (Fleetguard LF9080)..... <b>BD7154 +</b>
<b>Dual-Flow 11 25/32 In. Lube</b> (Fleetguard LF9001)..... <b>BD7154 +</b>	<b>Dual-Flow Lube</b> (2007 Emissions) (Fleetguard LF9031)... <b>BD7509 +</b>	<b>Dual-Flow Lube</b> (Upgrade, 2017-on) (Fleetguard LF14000NN) <b>BD50000</b>
<b>Dual-Flow 11 25/32 In. Lube</b> (Fleetguard LF9031)..... <b>BD7509 +</b>	<b>Dual-Flow Lube</b> (2010 Emissions) (Fleetguard LF9080)... <b>BD7154 +</b>	<b>Fuel/Water Separator</b> (Fleetguard NG5900)..... <b>BF7695</b>
<b>Dual-Flow 14 7/32 In. Lube</b> (Fleetguard LF9000)..... <b>BD7153 +</b>	<b>Dual-Flow Lube</b> (2010 Emissions) (Fleetguard LF9080)... <b>BD7154 +</b>	<b>Fuel</b> (Fleetguard FF5686)..... <b>BF9860 +</b>
<b>Dual-Flow Lube</b> (Upgrade, 2017-on) (Fleetguard LF14000NN) <b>BD50000</b>	<b>Dual-Flow Lube</b> (Fleetguard LF9070)..... <b>BD7153 +</b>	<b>Coolant</b> (w/o Chemical) (Fleetguard WF2127)..... <b>B5087</b>
<b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b>	<b>Lube</b> (3401544)..... <b>BD7309</b>	<b>Coolant</b> (w/Chemical) (Fleetguard WF2126)..... <b>BW5086</b>
<b>Fuel/Water Separator Spin-on</b> (3406889)..... <b>BF1293-SPS</b>	<b>Lube</b> (Upgrade) (3401544)..... <b>B40142</b>	Formula 450, KT450, KTA450, KTC450
<b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1000)..... <b>BF1259</b>	<b>Fuel/Water Separator Ele.</b> (1998-2002) (Fleetguard FF5369W)..... <b>PF7744</b>	<b>F-F Lube Spin-on</b> ..... <b>[2] B196 +</b>
<b>Fuel/Water Separator Spin-on</b> (Closed End) (Fleetguard FS1282)..... <b>BF1282 +</b>	<b>Fuel/Water Separator Ele.</b> (To 1998) (Fleetguard FS19727)..... <b>PF7895</b>	<b>B-P Lube Ele.</b> ..... <b>C750-E +</b>
<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl)..... <b>BF1282-O +</b>	<b>Fuel/Water Separator Ele.</b> (1998-2002) (Fleetguard FS19728)..... <b>PF7782</b>	<b>B-P Lube Spin-on</b> ..... <b>B7577</b>
<b>Breather</b> (1/07-on) (3683918)..... <b>CV15000</b>	<b>Fuel/Water Separator Ele.</b> (2002-on) (Fleetguard FS19729).. <b>PF7755</b>	<b>Fuel Spin-on</b> ..... <b>BF957 +</b>
<b>Coolant</b> (w/o Chemical) (Fleetguard WF2127)..... <b>B5087</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19764)..... <b>PF9814</b>	<b>Opt. Air</b> (154012)..... <b>PA1649</b>
<b>Coolant</b> (Controlled Release) (Fleetguard WF2121)..... <b>BW5250</b>	<b>Fuel Spin-on</b> (Pre 2010 Emissions) (Fleetguard FF2200)... <b>BF7766</b>	<b>Coolant</b> ..... <b>BW5073</b>
<b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>	<b>Fuel Spin-on</b> (Pre 2010 Emissions) (Fleetguard FF2203)... <b>BF7760</b>	KT 1150
<b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b>	<b>Fuel Spin-on</b> (2010 Emissions) (Fleetguard FF5686)..... <b>BF9860 +</b>	<b>9 15/16 In. F-F Lube</b> (3313279)... <b>B196 +</b>
ISV	<b>Fuel Spin-on</b> (2014 Emissions) (Fleetguard FF5776)..... <b>BF9885 +</b>	<b>11 9/32 In. F-F Lube</b> (3313279)... <b>B96 +</b>
<b>Lube</b> (4378318)..... <b>B7420</b>		<b>B-P Lube Ele.</b> (256838)..... <b>C750-E +</b>
<b>Lube</b> (4378319)..... <b>BT7349</b>		<b>B-P Lube Spin-on</b> (3313283)..... <b>B7577</b>
		<b>Fuel/Water Separator</b> (3308638).. <b>BF1212 +</b>
		<b>Fuel</b> (156172)..... <b>BF957-D +</b>
		KTA600
		<b>F-F Lube Spin-on</b> ..... <b>[2] B196 +</b>
		<b>B-P Lube Ele.</b> ..... <b>C750-E +</b>
		<b>B-P Lube Spin-on</b> ..... <b>B7577</b>
		<b>Fuel Spin-on</b> ..... <b>[2] BF957 +</b>
		<b>Opt. Air</b> (154012)..... <b>PA1649</b>
		<b>Coolant</b> ..... <b>BW5073</b>
		L9
		<b>Lube</b> (3937736)..... <b>B7177</b>
		<b>Lube</b> (3401544)..... <b>BD7309</b>
		<b>Lube</b> (Upgrade) (3401544)..... <b>B40142</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

**Trucks & Buses Applications** **BALDWIN FILTERS**

<b>CUMMINS Engines (cont'd)</b>	<b>CUMMINS Engines (cont'd)</b>	<b>CUMMINS Engines (cont'd)</b>
L9 (Cont'd) Fuel (Fleetguard FF63008)..... <b>BF63000</b> Crankcase Breather (4936636).... <b>CV15010</b>	N14 Plus (Cont'd) Opt. Fuel/Water Separator (Fleetguard FS1003)..... <b>BF1293-SPS</b> Coolant (Fleetguard WF2071)..... <b>BW5071</b> Opt. Coolant (Controlled Release) (Fleetguard WF2121).... <b>BW5250</b>	NTA420 F-F Lube Ele..... <b>P999-HD</b> B-P Lube Ele..... <b>C750-E +</b> Fuel Spin-on..... <b>[2] BF957 +</b> Coolant..... <b>BW5073</b>
L9N (8.9L) Lube (3401544)..... <b>BD7309</b> Lube (Upgrade) (3401544)..... <b>B40142</b>	NH250, NHC250 F-F Lube Ele..... <b>P999-HD</b> F-F Lube Spin-on..... <b>B196 +</b> B-P Lube Spin-on..... <b>B7577</b> Fuel Spin-on..... <b>BF957 +</b> Breather (Fleetguard AF250)..... <b>PA643</b> Coolant..... <b>BW5071</b>	NTC F-F Lube Ele. (158139)..... <b>P999-HD</b> F-F Lube Spin-on (3313279)..... <b>B196 +</b> Dual-Flow Lube Spin-on (3318853)..... <b>BD103 +</b> B-P Lube Ele. (256838)..... <b>C750-E +</b> B-P Lube Spin-on (3313283)..... <b>B7577</b> Fuel/Water Separator (3308638). <b>BF1212 +</b> Fuel (154709)..... <b>BF957 +</b>
L10, LT10A Dual-Flow Lube (3318853)..... <b>BD103 +</b> F-F Lube Spin-on (Fleetguard LF670SC)..... <b>B196 +</b> B-P Lube Spin-on (3304232)..... <b>B7577</b> Opt. Fuel/Water Separator (3308638)..... <b>BF1212 +</b> Fuel Spin-on (154789)..... <b>BF957-D +</b> Coolant (w/4 Units BTA+) (3315116)..... <b>BW5071</b> Coolant (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b>	NHHTC335 F-F Lube Ele..... <b>P999-HD</b> B-P Lube Ele..... <b>C750-E +</b> Fuel Spin-on..... <b>BF957 +</b> Coolant..... <b>BW5071</b>	NTC250, NTC250S F-F Lube Ele..... <b>P999-HD</b> F-F Lube Spin-on..... <b>B196 +</b> B-P Lube Ele..... <b>C750-E +</b> B-P Lube Spin-on..... <b>B7577</b> Fuel Spin-on..... <b>BF957 +</b> Opt. Air (Fleetguard AF253)..... <b>PA616</b> Coolant..... <b>BW5071</b>
M11 (10.8L) Dual-Flow Lube (3318853)..... <b>BD103 +</b> Fuel/Water Separator Spin-on (To 12/1995) (3308638)..... <b>BF1212 +</b> Fuel/Water Separator Spin-on (12/1995-on) (3329289)..... <b>BF1259</b> Fuel/Water Separator Ele. (Fleetguard FS1029W)..... <b>PF7680</b>	NT280, NTC280 F-F Lube Ele..... <b>P999-HD</b> B-P Lube Ele..... <b>C750-E +</b> Fuel Spin-on..... <b>BF957 +</b> Opt. Air (3001690)..... <b>PA616</b>	Formula 300, NTC300, Formula 315 F-F Lube Spin-on..... <b>B196 +</b> Dual-Flow Lube..... <b>BD103 +</b> B-P Lube Ele..... <b>C750-E +</b> B-P Lube Spin-on..... <b>B7577</b> Fuel Spin-on..... <b>BF957 +</b> Coolant..... <b>BW5071</b>
M11 Plus Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309 +</b> Opt. Std. Dual-Flow Lube (Fleetguard LF3000)..... <b>BD103 +</b> Fuel/Water Separator (Fleetguard FS1000)..... <b>BF1259</b> Opt. Fuel/Water Separator (Fleetguard FS1003)..... <b>BF1293-SPS</b> Coolant (Fleetguard WF2071)..... <b>BW5071</b> Opt. Coolant (Controlled Release) (Fleetguard WF2121).... <b>BW5250</b>	NT335 F-F Lube Ele..... <b>P999-HD</b> B-P Lube Ele..... <b>C750-E +</b> Fuel Spin-on..... <b>BF957 +</b> Opt. Air (299253)..... <b>PA616</b>	NTC335, Formula 350, NTC350 F-F Lube Ele..... <b>P999-HD</b> F-F Lube Spin-on..... <b>B196 +</b> Dual-Flow Lube..... <b>BD103 +</b> B-P Lube Ele..... <b>C750-E +</b> B-P Lube Spin-on..... <b>B7577</b> Fuel Spin-on..... <b>BF957 +</b> Opt. Air (Fleetguard AF253)..... <b>PA616</b> Coolant..... <b>BW5071</b>
N14 F-F Lube Spin-on (Fleetguard LF670SC)..... <b>B196 +</b> B-P Lube Spin-on (3304232)..... <b>B7577</b> Dual-Flow Lube (3318853)..... <b>BD103 +</b> Lube (Upgrade) (3401544)..... <b>B40142</b> Opt. Fuel/Water Separator (To 12/1995) (3308638)..... <b>BF1212 +</b> Opt. Fuel/Water Separator (12/1995-on) (3329289)..... <b>BF1259</b> Fuel Spin-on (154789)..... <b>BF957-D +</b> Coolant (Maintenance)..... <b>BW5071</b>	NT380, NTA380 F-F Lube Ele..... <b>P999-HD</b> B-P Lube Ele..... <b>C750-E +</b> Fuel Spin-on..... <b>BF957 +</b> Opt. Air (3001690)..... <b>PA616</b>	NTC400 F-F Lube Ele..... <b>P999-HD</b> F-F Lube Spin-on..... <b>B196 +</b> Dual-Flow Lube..... <b>BD103 +</b> B-P Lube Ele..... <b>C750-E +</b> B-P Lube Spin-on..... <b>B7577</b> Fuel Spin-on..... <b>BF957 +</b> Coolant..... <b>BW5071</b>
N14 Plus Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309 +</b> Opt. Std. Dual-Flow Lube (Fleetguard LF3000)..... <b>BD103 +</b> Fuel/Water Separator (Fleetguard FS1000)..... <b>BF1259</b>	NT855 (14.0L) 9 15/16 In. F-F Lube (Fleetguard LF670)..... <b>B196 +</b> 11 9/32 In. F-F Lube (Fleetguard LF670)..... <b>B96 +</b> B-P Lube (Fleetguard LF777)..... <b>B7577</b> Dual-Flow Lube (Fleetguard LF3000)..... <b>BD103 +</b> Fuel (Fleetguard FF105)..... <b>BF957 +</b>	NTC444, 444XT F-F Lube..... <b>B196 +</b> Dual-Flow Lube..... <b>BD103 +</b> B-P Lube..... <b>B7577</b> Opt. Fuel/Water Separator..... <b>BF1212 +</b> Fuel Spin-on..... <b>BF957-D +</b>
	NTA370 F-F Lube Ele..... <b>P999-HD</b> B-P Lube Ele..... <b>C750-E +</b> Fuel Spin-on..... <b>[2] BF957 +</b> Coolant..... <b>BW5073</b>	NTCC350, NTE350 F-F Lube Spin-on..... <b>B196 +</b> B-P Lube Ele..... <b>C750-E +</b> Fuel Spin-on..... <b>BF957 +</b> Coolant..... <b>BW5071</b>
	NTA400 F-F Lube Ele..... <b>P999-HD</b> F-F Lube Spin-on..... <b>B196 +</b> B-P Lube Ele..... <b>C750-E +</b> Fuel Spin-on..... <b>BF957 +</b> Opt. Air (Fleetguard AF253)..... <b>PA616</b> Coolant..... <b>BW5071</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

CUMMINS Engines (cont'd)	CUMMINS Engines (cont'd)	CUMMINS Engines (cont'd)
<b>NTCC400</b> F-F Lube Spin-on..... B196 + B-P Lube Ele..... C750-E + Fuel Spin-on..... BF957 + Coolant..... BW5071	<b>Tector 4</b> Lube..... BT7237 Fuel..... BF7813 Breather..... P7336 KIT	<b>X15 (14.9L)</b> Dual-Flow Lube (4367100)..... BD50000 Lube (5575298)..... B40145 Lube (3401544)..... B40142 Fuel/Water Separator (Fleetguard FS19764)..... PF9814 Fuel (5365988)..... BF46129 Fuel (5575143)..... BF46248
<b>NTE290</b> F-F Lube Spin-on..... B196 + B-P Lube Ele..... C750-E + Fuel Spin-on..... BF957 + Coolant..... BW5073	<b>Tector 6</b> Lube..... BT7237 Fuel..... BF7813 Breather..... P7336 KIT	<b>DACIA</b> <b>European Light Duty Vehicles</b> Dokker 1.6 w/K7M 85 HP Eng. (2012-on) Lube (7700274177)..... B7276
<b>NTE370</b> F-F Lube Spin-on..... B196 + B-P Lube Ele..... C750-E + Fuel Spin-on..... BF957 + Coolant..... BW5071	<b>V378</b> F-F Lube Spin-on..... B205 + B-P Lube Ele..... C704-L + Fuel Spin-on..... BF957 + Opt. Air (Fleetguard AF252)..... PA617 Coolant..... BW5071	Duster 1.6 16V w/H4M 105 HP Eng. (2010-on) Lube (152085758R)..... B1400
<b>NTF250</b> F-F Lube Ele..... P999-HD B-P Lube Ele..... C750-E + Fuel Spin-on..... BF957 + Opt. Air (Fleetguard AF253)..... PA616 Coolant..... BW5071	<b>V504</b> F-F Lube Spin-on..... B205 + Fuel Spin-on..... BF957 + Coolant..... BW5071	Duster 1.6 16V w/K4M 105 HP Eng. (2010-on) Lube (7700274177)..... B7276
<b>NTF365</b> F-F Lube Ele..... P999-HD F-F Lube Spin-on..... B196 + B-P Lube Ele..... C750-E + Fuel Spin-on..... BF957 + Opt. Air (Fleetguard AF253)..... PA616 Coolant..... BW5071	<b>V555</b> F-F Lube Ele..... P999-HD F-F Lube Spin-on..... B205 + B-P Lube Spin-on..... B7577 Fuel Spin-on..... BF957 + Coolant..... BW5071	Duster 2.0 16V w/F4R 133 HP Eng. (2010-on) Lube (8200768913)..... B7276
<b>NTTC475</b> F-F Lube Ele..... P999-HD F-F Lube Spin-on..... B196 + B-P Lube Spin-on..... B7577 Fuel Spin-on..... BF957 + Coolant (Maintenance)..... BW5071	<b>VF 390M</b> Dual-Flow Lube..... BD103 + Fuel..... BF1259 Coolant..... BW5071	Lodgy 1.6 w/K7M 85 HP Eng. (2012-on) Lube (7700274177)..... B7276
<b>Signature 600</b> 14 7/32 In. Dual-Flow Lube (Fleetguard LF9000)..... BD7153 + Opt. 11 13/16 In. Dual-Flow Lube (Fleetguard LF9001)..... BD7154 + Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... BD50000 Fuel/Water Separator (3331096). BF1274-SP Fuel/Water Separator (4010651). BF1277-SPS Coolant (Fleetguard WF2126)..... BW5086	<b>VT225</b> F-F Lube Spin-on..... B205 + B-P Lube Spin-on..... B7577 Fuel Spin-on..... BF957 + Coolant..... BW5071	Logan 1.4 w/K7J 75HP Eng. (2007-2012) Lube (7700274177)..... B7276
<b>T300 (8.3L)</b> Dual-Flow Lube (Fleetguard LF3000)..... BD103 + Fuel (Fleetguard FF42000)..... [2] BF788 Radial Seal O. Air (Fleetguard AF4878)..... RS2863 Radial Seal XP O. Air (Fleetguard AF4878)..... RS2863XP Radial Seal I. Air (Fleetguard AF25215)..... RS3501	<b>VT350</b> F-F Lube Ele..... P999-HD F-F Lube Spin-on..... B196 + B-P Lube Ele..... C750-E + B-P Lube Spin-on..... B7577 Fuel Spin-on..... BF957 + Opt. Air (3001690)..... PA616 Coolant..... BW5071	Logan 1.5 dCi w/K9K 68/86 HP Eng. (2007-2012) Lube (8200768913)..... B7276
	<b>VT903</b> F-F Lube Ele. (158139)..... P999-HD F-F Lube Spin-on (3313279)..... B196 + B-P Lube Ele. (256838)..... C750-E + B-P Lube Spin-on (3313283)..... B7577 Fuel/Water Separator (3308638). BF1212 + Fuel (156172)..... BF957-D +	Logan 1.6 8V w/K7M 87 HP Eng. (2007-2012) Lube (7700274177)..... B7276
	<b>X12 (11.9L)</b> Dual-Flow Lube (4367100)..... BD50000 Dual-Flow Lube (5575298)..... B40145 Lube (3401544)..... BD7309 Lube (Upgrade) (3401544)..... B40142	Logan 1.6 16v w/K4M 105 HP Eng. (2007-2012) Lube (7700274177)..... B7276
		Logan II 1.6 8V w/K7M Eng. (2012-on) Lube (7700274177)..... B7276
		Logan II 1.6 16V w/K4M Eng. (2012-on) Lube (7700274177)..... B7276
		Sandero I 1.4 8V w/K7J 75 HP Eng. (2008-2012) Lube (7700274177)..... B7276
		Sandero I 1.5 dCi w/K9K 75/90 HP Eng. (2008-2012) Lube (8200768913)..... B7276
		Sandero I 1.6 8V w/K7M 85 HP Eng. (2008-2012) Lube (7700274177)..... B7276
		Sandero I 1.6 16V w/K4M 105/112 HP Eng. (2008-2012) Lube (7700274177)..... B7276
		Sandero II 1.6 8V w/K7M 85/95 HP Eng. (2012-on) Lube (7700274177)..... B7276
		Sandero II 1.6 16V w/K4M 105/112 Eng. (2012-on) Lube (7700274177)..... B7276

\* See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>DAF Buses</b>	<b>DAF Buses (cont'd)</b>	<b>DAF Engines (cont'd)</b>
B1100AD, B1100DA w/DA475 Eng. Lube..... P7017	MBG200, MPG200 w/DKCL1160, DKFL1160 Engs. Fuel (247138)..... BF980 Air (667078)..... PA2813	CD85 Lube (CBU1124)..... BT339 + Fuel/Water Separator (CBU1920)..... BF1226
B1300DD, B1600DD w/DD575 Eng. Lube..... P7017 Fuel (247139)..... BF900	SB200 Lube Ele. (248126)..... P235 Fuel (247138)..... BF980 381.0 mm Air (112294)..... PA2474 377.8 mm Air (667078)..... PA2813 Steering (229348)..... P106-HD	CE100 Series Lube..... BT7237 P. Fuel (1399760)..... BF7813
B1600DF, SB1600DF w/DF615 Eng. Lube (114786)..... B236 + Fuel (247139)..... BF900 Steering (229348)..... P106-HD	SB201, SB210 Lube Ele. (248126)..... P235 Fuel (247138)..... BF980 381.0 mm Air (112294)..... PA2474 377.8 mm Air (667078)..... PA2813 Steering (229348)..... P106-HD	CEC100 (Euro 3) Series F-F Lube (1397764)..... P7232 F-F Long Life Lube (1397765).... P7330 B-P Lube (1310891)..... BC7194 201.6 mm Fuel (1397766)..... PF7767 247.7 mm Fuel (1450184)..... PF7946
B1600DS, SB1600DS w/DS575 Eng. Lube (114786)..... B236 +	SB220 Series w/1160 Eng. Lube Spin-on (114786)..... B236 + Fuel (247138)..... BF980 O. Air (393561)..... PA3760 I. Air..... PA2836	CN95 Lube (CBU1124)..... BT339 + Fuel/Water Separator (CBU1920)..... BF1226
F2200DU Lube Spin-on..... B7031 Fuel Spin-on (247138)..... BF980 O. Air (112294)..... PA2474 I. Air..... PA2836	SB220 Series w/1160 Eng. Lube Spin-on (114786)..... B236 + Fuel (247138)..... BF980 O. Air (393561)..... PA3760 I. Air..... PA2836	CS100 Series Lube (CBU1124)..... BT339 + Fuel/Water Separator (CBU1920)..... BF1226
F2300EHD Lube Ele. (213342)..... P25 Fuel Spin-on..... BF980 O. Air (607179)..... PA2475 I. Air..... PA2814	SB1602DH, SB1602DU w/DH825, DU825 Eng. Lube Ele. (213342)..... P25 Fuel (247138)..... BF980 Air (265045)..... PA2405	CS134 Lube (CBU1124)..... BT339 +
TB160DF w/DF615 Eng. Lube (114786)..... B236 + Fuel (247139)..... BF900 Steering (229348)..... P106-HD	SB2000 Air (112294)..... PA2474	CS156 Lube (CBU1124)..... BT339 +
TB160DS w/DS575 Eng. Lube (114786)..... B236 +	SB2300, SBR2300, SB2305 Lube Ele..... P25 Fuel (247138)..... BF980 Air (667078)..... PA2813 Steering (229348)..... P106-HD	CT119/119G Lube (CBU1124)..... BT339 + Fuel/Water Separator (CBU1920)..... BF1226
TB163DF w/DF615 Eng. Lube (114786)..... B236 + Fuel (247139)..... BF900 Steering (229348)..... P106-HD	SB3000 Series w/DKSB1160 Eng. Lube..... B236 + Fuel (247138)..... BF980 O. Air (112294)..... PA2474 I. Air..... PA2836	DA475, DD475, DA575, DD575 Lube Ele..... P7017
TB163DS w/DS575 Eng. Lube (114786)..... B236 +	SP200 w/DKCL1160, DKFL1160 Series Eng. Fuel (247138)..... BF980 I. Air (667078)..... PA2813	DH825, DHS825, DHT825, DHTD825 Lube Ele. (213342)..... P25 Lube Spin-on (114786)..... B236 + Fuel (247138)..... BF980
TB1600DF w/DF615 Eng. Lube (114786)..... B236 + Fuel..... BF900 Steering (229348)..... P106-HD		DF615 Lube Ele..... P7017 Fuel (247139)..... BF900
TB2100 w/DH825, DHT825 Eng. Lube Spin-on (661049)..... B7031 Fuel (247138)..... BF980 O. Air (607179)..... PA2475 I. Air (691280)..... PA2814		DKS1160, DKT1160 Lube (114786)..... B236 + Fuel (247138)..... BF980
MB200, MB200DKTL Lube Ele. (248126)..... P235 Fuel (247138)..... BF980 381.0 mm Air (112294)..... PA2474 377.8 mm Air (667078)..... PA2813 Steering (229348)..... P106-HD	<b>DAF Engines</b>	DS575 Lube Spin-on (114786)..... B236 + Fuel Ele. (138364)..... PF838 Fuel Spin-on..... BF988 +
MB230 w/1160 Series Eng. Lube..... B236 + Fuel (247138)..... BF980 Air (667078)..... PA2813 Steering (229348)..... P106-HD	11.6L Lube (267714)..... B7187 + Fuel (1318695)..... BF7664	FR100 (Euro 4) Series Lube (Fleetguard LF16015)..... BT7237 Fuel (1399760)..... BF7813
	BE99 Series Lube..... BT7237 P. Fuel (1399760)..... BF7813	GR100 (Euro 4) Series Lube (Fleetguard LF16015)..... BT7237 Fuel (1399760)..... BF7813
	BE100 Series Lube..... BT7237 P. Fuel (1399760)..... BF7813	GR200 (Euro 4) Series Lube (Fleetguard LF16015)..... BT7237 Fuel (1399760)..... BF7813
	CB107 Lube (CBU1124)..... BT339 + Fuel/Water Separator (CBU1920)..... BF1226	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



DAF Engines (cont'd)	DAF Engines (cont'd)	DAF Engines (cont'd)
<b>MX265S (Euro 4-5)</b>	<b>PR250 S Series</b>	<b>XE300C (Euro3) Series</b>
F-F Lube (1643070)..... <b>P40019</b>	F-F Lube (1397764)..... <b>P7232</b>	F-F Lube (1397764)..... <b>P7232</b>
B-P Lube Spinner (1643072)..... <b>BC7326 +</b>	F-F Long Life Lube (1397765).... <b>P7330</b>	F-F Long Life Lube (1397765).... <b>P7330</b>
Fuel/Water Separator (1433649). <b>BF1383-O</b>	Fuel/Water Separator (1433649). <b>BF1383-O</b>	B-P Lube Spinner (1310891)..... <b>BC7194</b>
Fuel (1643080)..... <b>PF7947</b>		Fuel/Water Separator (1433649). <b>BF1383-O</b>
<b>MX300S Series</b>	<b>PR300S Series</b>	<b>201.6 mm Fuel (1397766)..... PF7767</b>
F-F Lube (1643070)..... <b>P40019</b>	F-F Lube (1397764)..... <b>P7232</b>	<b>247.7 mm Fuel (1450184)..... PF7946</b>
B-P Lube Spinner (1643072)..... <b>BC7326 +</b>	F-F Long Life Lube (1397765).... <b>P7330</b>	
Fuel/Water Separator (1433649). <b>BF1383-O</b>	Fuel/Water Separator (1433649). <b>BF1383-O</b>	
Fuel (1643080)..... <b>PF7947</b>		
<b>MX400S Series</b>	<b>RS100L Series</b>	
F-F Lube (1643070)..... <b>P40019</b>	Lube (1316123)..... <b>B7182 +</b>	
B-P Lube Spinner (1643072)..... <b>BC7326 +</b>	Fuel (247138)..... <b>BF980</b>	
Fuel/Water Separator (1433649). <b>BF1383-O</b>	Fuel (1318695)..... <b>BF7664</b>	
Fuel (1643080)..... <b>PF7947</b>		
<b>NS100L Series</b>	<b>RS200L Series</b>	
Lube (671490)..... <b>B236 +</b>	Lube (1316123)..... <b>B7182 +</b>	
Fuel (1318695)..... <b>BF7664</b>	Fuel (247138)..... <b>BF980</b>	
	Fuel (1318695)..... <b>BF7664</b>	
<b>NS100M (Euro2) Series</b>	<b>WS200 Series</b>	
Lube (1306549)..... <b>B7151</b>	Lube (267714)..... <b>B7187 +</b>	
Fuel (1318695)..... <b>BF7664</b>	Lube (1316123)..... <b>B7182 +</b>	
	Fuel (247138)..... <b>BF980</b>	
<b>PE100C (Euro 3) Series</b>	Fuel (1318695)..... <b>BF7664</b>	
F-F Lube (1397764)..... <b>P7232</b>	Fuel (1309511)..... <b>BF7696</b>	
F-F Long Life Lube (1397765).... <b>P7330</b>		
B-P Lube Spinner (1310891)..... <b>BC7194</b>	<b>XE200C Series</b>	
Fuel/Water Separator Spin-on (1433649)..... <b>BF1383-O</b>	F-F Lube (1310901)..... <b>B7162</b>	
Fuel (1450184)..... <b>PF7946</b>	F-F Lube (1397764)..... <b>P7232</b>	
Fuel (1397766)..... <b>PF7767</b>	B-P Lube Spinner (1310891)..... <b>BC7194</b>	
	Fuel/Water Separator Spin-on (1433649)..... <b>BF1383-O</b>	
<b>PE 183C</b>	Fuel (1345335)..... <b>BF7747</b>	
Lube (1397764)..... <b>P7232</b>	Fuel (1397766)..... <b>PF7767</b>	
P. Fuel (1397766)..... <b>PF7767</b>		
<b>PE 183M</b>	<b>XE200C (Euro3) Series</b>	
Fuel (1318695)..... <b>BF7664</b>	F-F Lube (1397764)..... <b>P7232</b>	
<b>PE200C (Euro3) Series</b>	F-F Long Life Lube (1397765).... <b>P7330</b>	
F-F Lube (1397764)..... <b>P7232</b>	B-P Lube Spinner (1310891)..... <b>BC7194</b>	
F-F Long Life Lube (1397765).... <b>P7330</b>	Fuel/Water Separator (1433649). <b>BF1383-O</b>	
B-P Lube Spinner (1310891)..... <b>BC7194</b>	201.6 mm Fuel (1397766)..... <b>PF7767</b>	
Fuel/Water Separator Spin-on (1433649)..... <b>BF1383-O</b>	247.7 mm Fuel (1450184)..... <b>PF7946</b>	
Fuel (1397766)..... <b>PF7767</b>		
Fuel (1450184)..... <b>PF7946</b>	<b>XE300C Series</b>	
<b>PF-M9.2L</b>	F-F Lube (1310901)..... <b>B7162</b>	
Fuel (1318695)..... <b>BF7664</b>	F-F Lube (1397764)..... <b>P7232</b>	
<b>PF100M (Euro2) Series</b>	B-P Lube Spinner (1310891)..... <b>BC7194</b>	
Lube (1345332)..... <b>B7161</b>	Fuel/Water Separator (1433649). <b>BF1383-O</b>	
Fuel/Water Separator (1433649). <b>BF1383-O</b>	Fuel (1345335)..... <b>BF7747</b>	
Fuel (1318695)..... <b>BF7664</b>	Fuel (1397766)..... <b>PF7767</b>	
<b>PF200M (Euro2) Series</b>	<b>XF300M Series</b>	
Lube (1345332)..... <b>B7161</b>	F-F Lube (1310901)..... <b>B7162</b>	
Fuel/Water Separator (1433649). <b>BF1383-O</b>	B-P Lube Spinner (1310891)..... <b>BC7194</b>	
Fuel (1318695)..... <b>BF7664</b>	Fuel/Water Separator (1433649). <b>BF1383-O</b>	
	Fuel..... <b>BF7664</b>	
	<b>XF200M Series</b>	
	F-F Lube (1310901)..... <b>B7162</b>	
	B-P Lube Spinner (1310891)..... <b>BC7194</b>	
	Fuel/Water Separator (1433649). <b>BF1383-O</b>	
	Fuel..... <b>BF7664</b>	
		<b>DAF Trucks</b>
		<b>45-Serie 45.120 w/CD85 Eng. (05/91-on)</b>
		Lube (CBU1124)..... <b>BT339 +</b>
		Fuel/Water Separator (CBU1920)..... <b>BF1226</b>
		<b>292.1 mm Air (MAK7603)..... PA2684-FN</b>
		<b>Air Dryer (Mann TB1374X)..... BA5374 +</b>
		<b>Steering (229348)..... P106-HD</b>
		<b>45-Serie 45.130 w/CN95 Eng. (05/91-on)</b>
		Lube (CBU1124)..... <b>BT339 +</b>
		Fuel/Water Separator (CBU1920)..... <b>BF1226</b>
		<b>292.1 mm Air (MAK7603)..... PA2684-FN</b>
		<b>341.3 mm Air..... PA2859-FN<sup>90</sup></b>
		<b>Air Dryer (Mann TB1374X)..... BA5374 +</b>
		<b>Steering (229348)..... P106-HD</b>
		<b>45-Serie 45.130 w/Cummins 6BT5.9 Eng.</b>
		Lube (490196)..... <b>BT339 +</b>
		Fuel/Water Separator (490160).... <b>BF1226</b>
		<b>Air (MAK1629)..... PA2859-FN<sup>90</sup></b>
		<b>Steering..... P106-HD</b>
		<b>45-Serie 45.150 Turbo w/Cummins 6BT5.9 Eng.</b>
		Lube (490196)..... <b>BT339 +</b>
		Fuel/Water Separator (490160).... <b>BF1226</b>
		<b>Steering..... P106-HD</b>
		<b>45-Serie 45.150 Turbo w/CB107 Eng. (05/91-on)</b>
		Lube (CBU1124)..... <b>BT339 +</b>
		Fuel/Water Separator (CBU1920)..... <b>BF1226</b>
		<b>Air (MAK1629)..... PA2859-FN<sup>90</sup></b>
		<b>Air Dryer (Mann TB1374X)..... BA5374 +</b>
		<b>Steering (229348)..... P106-HD</b>
		<b>45-Serie 45.160 Turbo w/CT119, CT119G Engs. (05/91-on)</b>
		Lube (CBU1124)..... <b>BT339 +</b>
		Fuel/Water Separator (CBU1920)..... <b>BF1226</b>
		<b>Air (MAK1629)..... PA2859-FN<sup>90</sup></b>
		<b>Air Dryer (Mann TB1374X)..... BA5374 +</b>
		<b>Steering (229348)..... P106-HD</b>
		<b>45-Serie 45.180 w/Cummins 6BT5.9 Eng.</b>
		Lube (490196)..... <b>BT339 +</b>
		Fuel/Water Separator (490160).... <b>BF1226</b>
		<b>Steering..... P106-HD</b>
		<b>45-Serie 45.180 Turbo w/CS134 Eng. (11/95-on)</b>
		Lube (CBU1124)..... <b>BT339 +</b>
		Fuel/Water Separator (CBU1920)..... <b>BF1226</b>
		<b>Air (MAK1629)..... PA2859-FN<sup>90</sup></b>

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.


Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

DAF Trucks (cont'd)	DAF Trucks (cont'd)	DAF Trucks (cont'd)
45-Serie 45.180 Turbo w/CS134 Eng. (11/95-on) (Cont'd) Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Steering (229348)..... <b>P106-HD</b>	LF 45LF.150 w/SBE Eng. (02/01-on) Lube..... <b>BT7237</b> Fuel (1399760)..... <b>BF7813</b> Air (1433690)..... <b>RS5431</b> Steering (229348)..... <b>P106-HD</b>	LF 45LF.190 w/CE136C Eng. (02/01-on) (Cont'd) Air (1433690)..... <b>RS5431</b> Air Dryer (1391510)..... <b>BA5376 +</b> Steering..... <b>P106-HD</b>
45-Serie 45.210 w/Cummins 6BT5.9 Eng. Lube (490196)..... <b>BT339 +</b> Fuel/Water Separator (490160)..... <b>BF1226</b> Steering..... <b>P106-HD</b>	LF 45LF.160 w/FR118 (Euro 4) Eng. (07/06-on) Lube (Fleetguard LF16015)..... <b>BT7237</b> Fuel/Water Separator (1618993)..... <b>BF7942</b> Fuel (1399760)..... <b>BF7813</b> Radial Seal Air (1679397)..... <b>RS5692</b> Air Dryer (1391510)..... <b>BA5376 +</b> Steering (229348)..... <b>P106-HD</b> Urea Oil/Air Separator (1686587)..... <b>OAS98000</b>	LF 45LF.210 w/FR152 E5/EEV Eng. (06/09-on) Lube (1399494)..... <b>BT7237</b> Fuel/Water Separator (1618993)..... <b>BF7942</b> Fuel (To 12/09) (1399760)..... <b>BF7813</b> Fuel (01/10-on) (1705122)..... <b>BF7922</b> Radial Seal O. Air (1679397)..... <b>RS5692</b> Air Dryer (1391510)..... <b>BA5376 +</b> Steering (229348)..... <b>P106-HD</b> Urea (1686587)..... <b>OAS98000</b>
45-Serie 45.210 Turbo w/CS156 Eng. (11/95-on) Lube (CBU1124)..... <b>BT339 +</b> Fuel/Water Separator (CBU1920)..... <b>BF1226</b> Air (MAK1629)..... <b>PA2859-FN<sup>90</sup></b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Steering (229348)..... <b>P106-HD</b>	LF 45LF.170 w/BE123C Eng. (02/01-on) Lube..... <b>BT7237</b> Fuel/Water Separator (M10 x 1.5 mm SP Thd.) (1437070)..... <b>BF7941</b> Fuel/Water Separator (w/M14 x 2.0 SP Thd.) (1618993)..... <b>BF7942</b> Fuel (1399760)..... <b>BF7813</b> Radial Seal Air (1668000)..... <b>RS5433</b> Air (1433690)..... <b>RS5431</b> Air Dryer (1391510)..... <b>BA5376 +</b> Steering (229348)..... <b>P106-HD</b>	LF 45LF.220 w/CE162C Eng. (02/01-on) Lube..... <b>BT7237</b> Fuel/Water Separator (M10 x 1.5 mm SP Thd.) (1437070)..... <b>BF7941</b> Fuel/Water Separator (w/M14 x 2.0 SP Thd.) (1618993)..... <b>BF7942</b> Fuel..... <b>BF7813</b> Radial Seal Air (1668000)..... <b>RS5433</b> Air (1433690)..... <b>RS5431</b> Air Dryer (1391510)..... <b>BA5376 +</b> Steering..... <b>P106-HD</b>
LF 45LF.130 w/BE99C Eng. (12/05-on) Lube (1399494)..... <b>BT7237</b> Fuel (1399760)..... <b>BF7813</b> Radial Seal Air (1672463)..... <b>RS5431</b> Air Dryer (1391510)..... <b>BA5376 +</b> Steering (229348)..... <b>P106-HD</b>	LF 45LF.170 w/SBE Eng. (02/01-on) Lube..... <b>BT7237</b> Fuel (1399760)..... <b>BF7813</b> Air (1433690)..... <b>RS5431</b> Steering (229348)..... <b>P106-HD</b>	LF 45LF.220 w/GR165 (Euro 4) Eng. (07/06-on) Lube (Fleetguard LF16015)..... <b>BT7237</b> Fuel/Water Separator (1618993)..... <b>BF7942</b> Fuel (1399760)..... <b>BF7813</b> Radial Seal Air (1679397)..... <b>RS5692</b> Air Dryer (1391510)..... <b>BA5376 +</b> Steering (229348)..... <b>P106-HD</b> Urea Oil/Air Separator (1686587)..... <b>OAS98000</b>
LF 45LF.140 w/BE99C Eng. (02/01-on) Lube..... <b>BT7237</b> Fuel/Water Separator (M10 x 1.5 mm SP Thd.) (1437070)..... <b>BF7941</b> Fuel/Water Separator (w/M14 x 2.0 SP Thd.) (1618993)..... <b>BF7942</b> Fuel (1399760)..... <b>BF7813</b> Radial Seal Air (1668000)..... <b>RS5433</b> Air (1433690)..... <b>RS5431</b> Air Dryer (1391510)..... <b>BA5376 +</b> Steering (229348)..... <b>P106-HD</b>	LF 45LF.180 w/CE136C Eng. (02/01-on) Lube..... <b>BT7237</b> Fuel/Water Separator (M10 x 1.5 mm SP Thd.) (1437070)..... <b>BF7941</b> Fuel/Water Separator (w/M14 x 2.0 SP Thd.) (1618993)..... <b>BF7942</b> Fuel..... <b>BF7813</b> Radial Seal Air (1668000)..... <b>RS5433</b> Air (1433690)..... <b>RS5431</b> Air Dryer (1391510)..... <b>BA5376 +</b> Steering..... <b>P106-HD</b>	LF 45LF.250 w/GR185 (Euro 4) Eng. (07/06-on) Lube (Fleetguard LF16015)..... <b>BT7237</b> Fuel/Water Separator (1618993)..... <b>BF7942</b> Fuel (1399760)..... <b>BF7813</b> Radial Seal Air (1679397)..... <b>RS5692</b> Air Dryer (1391510)..... <b>BA5376 +</b> Steering (229348)..... <b>P106-HD</b> Urea Oil/Air Separator (1686587)..... <b>OAS98000</b>
LF 45LF.140 w/SBE Eng. (02/01-on) Lube..... <b>BT7237</b> Fuel (1399760)..... <b>BF7813</b> Air (1433690)..... <b>RS5431</b> Steering (229348)..... <b>P106-HD</b>	LF 45LF.180 w/FR136 (Euro 4) Eng. (07/06-on) Lube (Fleetguard LF16015)..... <b>BT7237</b> Fuel/Water Separator (1618993)..... <b>BF7942</b> Fuel (1399760)..... <b>BF7813</b> Radial Seal Air (1679397)..... <b>RS5692</b> Air Dryer (1391510)..... <b>BA5376 +</b> Steering (229348)..... <b>P106-HD</b> Urea Oil/Air Separator (1686587)..... <b>OAS98000</b>	LF 45LF.300 w/GR225 E5/EEV Eng. (06/09-on) Lube (1399494)..... <b>BT7237</b> Fuel/Water Separator (1618993)..... <b>BF7942</b> Fuel (To 12/09) (1399760)..... <b>BF7813</b> Fuel (01/10-on) (1705122)..... <b>BF7922</b> Radial Seal O. Air (1679397)..... <b>RS5692</b> Oil/Air Separator (1686587)..... <b>OAS98000</b> Air Dryer (1391510)..... <b>BA5376 +</b> Steering (229348)..... <b>P106-HD</b> Urea (1815766)..... <b>PE5270</b>
LF 45LF.150 w/BE110C Eng. (02/01-on) Lube..... <b>BT7237</b> Fuel/Water Separator (M10 x 1.5 mm SP Thd.) (1437070)..... <b>BF7941</b> Fuel/Water Separator (w/M14 x 2.0 SP Thd.) (1618993)..... <b>BF7942</b> Fuel (1399760)..... <b>BF7813</b> Radial Seal Air (1668000)..... <b>RS5433</b> Air (1433690)..... <b>RS5431</b> Air Dryer (1391510)..... <b>BA5376 +</b> Steering (229348)..... <b>P106-HD</b>	LF 45LF.190 w/CE136C Eng. (02/01-on) Lube..... <b>BT7237</b> Fuel/Water Separator (M10 x 1.5 mm SP Thd.) (1437070)..... <b>BF7941</b> Fuel/Water Separator (w/M14 x 2.0 SP Thd.) (1618993)..... <b>BF7942</b> Fuel..... <b>BF7813</b> Radial Seal Air (1668000)..... <b>RS5433</b>	55-Serie 55.150 Ti w/CS107M Eng. (11/95-12/00) Lube..... <b>BT339 +</b> Fuel/Water Separator..... <b>BF1226</b> Radial Seal Air..... <b>RS4794</b>

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

DAF Trucks (cont'd)	DAF Trucks (cont'd)	DAF Trucks (cont'd)
55-Serie 55.150 Ti w/CS107M Eng. (11/95-12/00) (Cont'd) Steering..... P106-HD	LF 55LF.170 w/ISBE Eng. (02/01-on) Lube (Fleetguard LF16015)..... BT7237 Fuel..... BF7813 Radial Seal Air (1433697)..... RS4970 Steering..... P106-HD	LF 55LF.220 w/GR165 (Euro 4) Eng. (07/06-on) Lube (Fleetguard LF16015)..... BT7237 Fuel/Water Separator (1618993). BF7942 Fuel (1399760)..... BF7813 Radial Seal Air (1679397)..... RS5692 Air Dryer (1391510)..... BA5376 + Steering (229348)..... P106-HD Urea Oil/Air Separator (1686587)..... OAS98000
55-Serie 55.180 Ti w/Cummins 6BT5.9 Eng. (490196)..... BT339 + Fuel/Water Separator (490160)... BF1226 Steering..... P106-HD	LF 55LF.180 w/CE136C Eng. (02/01-on) Lube..... BT7237 Fuel/Water Separator (M10 x 1.5 mm SP Thd.) (1437070)..... BF7941 Fuel/Water Separator (w/M14 x 2.0 SP Thd.) (1618993)..... BF7942 Fuel (1399760)..... BF7813 Air (1433690)..... RS5431 Radial Seal Air (1433697)..... RS4970 Air Dryer (1391510)..... BA5376 + Steering..... P106-HD	LF 55LF.250 w/CE184C Eng. (02/01-on) Lube..... BT7237 Fuel/Water Separator (M10 x 1.5 mm SP Thd.) (1437070)..... BF7941 Fuel/Water Separator (w/M14 x 2.0 SP Thd.) (1618993)..... BF7942 Fuel (1399760)..... BF7813 Air (1433690)..... RS5431 Radial Seal Air (1433697)..... RS4970 Air Dryer (1391510)..... BA5376 + Steering..... P106-HD
55-Serie 55.210 Ti w/Cummins 6BT5.9 Eng. (490196)..... BT339 + Fuel/Water Separator (490160)... BF1226 Steering..... P106-HD	LF 55LF.180 w/FR136 E4/5/EEV Eng. (07/06-on) Lube (1399494)..... BT7237 Fuel/Water Separator (1618993). BF7942 Fuel (To 12/09) (1399760)..... BF7813 Fuel (01/10-on) (1705122)..... BF7922 Air Dryer (1391510)..... BA5376 + Steering (229348)..... P106-HD Urea (1686587)..... OAS98000	LF 55LF.250 w/GR185 (Euro 4) Eng. (07/06-on) Lube (Fleetguard LF16015)..... BT7237 Fuel/Water Separator (1618993). BF7942 Fuel (1399760)..... BF7813 Radial Seal Air (1679397)..... RS5692 Air Dryer (1391510)..... BA5376 + Steering (229348)..... P106-HD Urea Oil/Air Separator (1686587)..... OAS98000
55-Serie 55.210 Ti w/CS156 Eng. (11/95-on) (CUBU1920)..... BF1226 Radial Seal Air (ACHD040)..... RS4794 Air Dryer (Mann TB1374X)..... BA5374 + Steering (229348)..... P106-HD	LF 55LF.190 w/CE136C Eng. (02/01-on) Lube..... BT7237 Fuel/Water Separator (M10 x 1.5 mm SP Thd.) (1437070)..... BF7941 Fuel/Water Separator (w/M14 x 2.0 SP Thd.) (1618993)..... BF7942 Fuel (1399760)..... BF7813 Air (1433690)..... RS5431 Radial Seal Air (1433697)..... RS4970 Air Dryer (1391510)..... BA5376 + Steering..... P106-HD	LF 55LF.290 w/GR210 (Euro 4) Eng. (07/06-on) Lube (Fleetguard LF16015)..... BT7237 Fuel/Water Separator (1618993). BF7942 Fuel (1399760)..... BF7813 Radial Seal Air (1679397)..... RS5692 Air Dryer (1391510)..... BA5376 + Steering (229348)..... P106-HD Urea Oil/Air Separator (1686587)..... OAS98000
55-Serie 55.230 Ti w/Cummins 6BT5.9 Eng. (490196)..... BT339 + Fuel/Water Separator (490160)... BF1226 Steering..... P106-HD	55LF.210 w/ FR152 E4/5/EEV Eng. (06/09-on) Lube (1399494)..... BT7237 Fuel/Water Separator (1618993). BF7942 Fuel (To 12/09) (1399760)..... BF7813 Fuel (01/10-on) (1829166)..... BF7922 Air Dryer (1391510)..... BA5376 + Steering (229348)..... P106-HD Urea (1815766)..... PE5270	LF 55LF.300 w/GR220 E5/EEV Eng. (06/09-on) Lube (1399494)..... BT7237 Fuel/Water Separator (1618993). BF7942 Fuel (To 12/09) (1399760)..... BF7813 Fuel (01/10-on) (1705122)..... BF7922 Air Dryer (1391510)..... BA5376 + Steering (229348)..... P106-HD Urea (1686587)..... OAS98000
55-Serie 55.230 Ti w/CS174 Eng. (11/95-on) (CUBU1124)..... BT339 + Fuel/Water Separator (CUBU1920)..... BF1226 Radial Seal Air (ACHD040)..... RS4794 Air Dryer (Mann TB1374X)..... BA5374 + Steering (229348)..... P106-HD	LF 55LF.170 w/BE123C Eng. (02/01-on) Lube..... BT7237 Fuel/Water Separator (M10 x 1.5 mm SP Thd.) (1437070)..... BF7941 Fuel/Water Separator (w/M14 x 2.0 SP Thd.) (1618993)..... BF7942 Fuel (1399760)..... BF7813 Air (1433690)..... RS5431 Radial Seal Air (1433697)..... RS4970 Air Dryer (1391510)..... BA5376 + Steering (229348)..... P106-HD	65-Serie 65 (3/93-on) Lube (1306549)..... B7151 Fuel..... BF7664 Steering (1902137)..... P106-HD
LF 55LF.160 w/FR118 E4 Eng. (07/06-on) (1399494)..... BT7237 Fuel/Water Separator (1618993). BF7942 Fuel (To 12/09) (1399760)..... BF7813 Fuel (01/10-on) (1705122)..... BF7922 Air Dryer (1391510)..... BA5376 + Steering (229348)..... P106-HD Urea (1686587)..... OAS98000	LF 55LF.220 w/CE162C Eng. (02/01-on) Lube..... BT7237 Fuel/Water Separator (M10 x 1.5 mm SP Thd.) (1437070)..... BF7941 Fuel/Water Separator (w/M14 x 2.0 SP Thd.) (1618993)..... BF7942 Fuel (1399760)..... BF7813 Air (1433690)..... RS5431 Radial Seal Air (1433697)..... RS4970 Air Dryer (1391510)..... BA5376 + Steering..... P106-HD	65-Serie 65.180 ATi w/6 Cyl. 6.2L Eng. (03/93-05/98) Fuel..... BF900 Steering..... P106-HD
LF 55LF.170 w/BE123C Eng. (02/01-on) Lube..... BT7237 Fuel/Water Separator (M10 x 1.5 mm SP Thd.) (1437070)..... BF7941 Fuel/Water Separator (w/M14 x 2.0 SP Thd.) (1618993)..... BF7942 Fuel (1399760)..... BF7813 Air (1433690)..... RS5431 Radial Seal Air (1433697)..... RS4970 Air Dryer (1391510)..... BA5376 + Steering (229348)..... P106-HD		65-Serie 65.180 ATi w/NS133L Eng. (03/93-05/98) Lube (671490)..... B236 + Fuel (1318695)..... BF7664 Radial Seal Air (754718)..... RS4861


\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

**Trucks & Buses Applications** **BALDWIN FILTERS**

DAF Trucks (cont'd)	DAF Trucks (cont'd)	DAF Trucks (cont'd)
65-Serie 65.180 ATi w/NS133L Eng. (03/93-05/98) (Cont'd) Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Steering (229348)..... <b>P106-HD</b>	CF 65CF.210 w/NS156M (Euro2) Eng. (03/98-12/00) Lube (1306549)..... <b>B7151</b> Fuel (1318695)..... <b>BF7664</b> Radial Seal Air (1346885)..... <b>RS4562</b> Cab Air (1322259)..... <b>PA4928</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Steering (229348)..... <b>P106-HD</b>	CF 65CF.250 w/CEC184 (Euro3) Eng. (01/01-on) (Cont'd) Radial Seal Air (1657522)..... <b>RS5360</b> Cab Air (1322259)..... <b>PA4928</b> 134.9 mm Air Dryer (1391510).... <b>BA5376 +</b> 167.5 mm Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Steering (229348)..... <b>P106-HD</b>
65-Serie 65.210 ATi w/6 Cyl. 6.2L Eng. Fuel..... <b>BF900</b> Steering..... <b>P106-HD</b>	CF 65CF.220 w/CEC162 (Euro3) Eng. (01/01-on) F-F Lube (1397764)..... <b>P7232</b> F-F Lube (Long Life) (1397765)... <b>P7330</b> B-P Lube Spinner (1310891)..... <b>BC7194</b> Fuel/Water Separator (M10 x 1.5 mm SP Thd.) (1437070)..... <b>BF7941</b> Fuel/Water Separator (M14 x 2 mm SP Thd.) (1618993)..... <b>BF7942</b> 201.6 mm Fuel (1397766)..... <b>PF7767</b> 247.7 mm Fuel (Long Life) (1450184)..... <b>PF7946</b> Radial Seal Air (1657522)..... <b>RS5360</b> Cab Air (1322259)..... <b>PA4928</b> 134.9 mm Air Dryer (1391510).... <b>BA5376 +</b> 167.5 mm Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Steering (229348)..... <b>P106-HD</b>	CF 65CF.250 w/GR185 (Euro 4) Eng. (07/06-on) Lube (Fleetguard LF16015)..... <b>BT7237</b> Fuel/Water Separator (1618993). <b>BF7942</b> Fuel (1399760)..... <b>BF7813</b> 417.5 mm Radial Seal Air (1668000)..... <b>RS5433</b> 479.4 mm Radial Seal Air (1789291)..... <b>RS4959</b> Air Dryer (1391510)..... <b>BA5376 +</b> Steering (229348)..... <b>P106-HD</b> Urea Oil/Air Separator (1686587)..... <b>OAS98000</b>
65-Serie 65.240 w/6 Cyl. 6.2L Eng. Fuel..... <b>BF900</b> Steering..... <b>P106-HD</b>	CF 65CF.220 w/GR165 (Euro 4) Eng. (07/06-on) Lube (Fleetguard LF16015)..... <b>BT7237</b> Fuel/Water Separator (1618993). <b>BF7942</b> Fuel (1399760)..... <b>BF7813</b> 417.5 mm Radial Seal Air (1668000)..... <b>RS5433</b> 479.4 mm Radial Seal Air (1789291)..... <b>RS4959</b> Air Dryer (1391510)..... <b>BA5376 +</b> Steering (229348)..... <b>P106-HD</b> Urea Oil/Air Separator (1686587)..... <b>OAS98000</b>	CF 65CF.290 w/GR210 (Euro 4) Eng. (07/06-on) Lube (Fleetguard LF16015)..... <b>BT7237</b> Fuel/Water Separator (1618993). <b>BF7942</b> Fuel (1399760)..... <b>BF7813</b> 417.5 mm Radial Seal Air (1668000)..... <b>RS5433</b> 479.4 mm Radial Seal Air (1789291)..... <b>RS4959</b> Air Dryer (1391510)..... <b>BA5376 +</b> Steering (229348)..... <b>P106-HD</b> Urea Oil/Air Separator (1686587)..... <b>OAS98000</b>
65-Serie 65.240 ATi w/NS177L Eng. (05/96-05/98) Lube (671490)..... <b>B236 +</b> Fuel (1318695)..... <b>BF7664</b> Radial Seal Air (754718)..... <b>RS4861</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Steering (229348)..... <b>P106-HD</b>	CF 65CF.180 (3/98-on) Lube (1306549)..... <b>B7151</b> Fuel..... <b>BF7664</b> Radial Seal Air (1385791)..... <b>RS4562</b> Steering (1902137)..... <b>P106-HD</b>	75-Serie 75.240 ATi w/8.65L Eng. Lube (1316123)..... <b>B7182 +</b> Fuel (To 9/96) (247138)..... <b>BF980</b> Fuel (9/96-on) (1318695)..... <b>BF7664</b> Radial Seal Air (754718)..... <b>RS4861</b> Steering..... <b>P106-HD</b>
CF 65CF.180 w/NS133M (Euro2) Eng. (03/98-12/00) Lube (1306549)..... <b>B7151</b> Fuel (1318695)..... <b>BF7664</b> Radial Seal Air (1346885)..... <b>RS4562</b> Cab Air (1322259)..... <b>PA4928</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Steering (229348)..... <b>P106-HD</b>	CF 65CF.240 w/NS177M (Euro2) Eng. (03/98-12/00) Lube (1306549)..... <b>B7151</b> Fuel (1318695)..... <b>BF7664</b> Radial Seal Air (1346885)..... <b>RS4562</b> Cab Air (1322259)..... <b>PA4928</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Steering (229348)..... <b>P106-HD</b>	75-Serie 75.240 ATi w/RS180L Eng. (02/92-05/98) Lube (1316123)..... <b>B7182 +</b> Fuel (2/92-8/96) (247138)..... <b>BF980</b> Fuel (9/96-5/98) (1318695)..... <b>BF7664</b> Radial Seal Air (754718)..... <b>RS4861</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Trans. (5000807213)..... <b>PT8385</b> Steering (229348)..... <b>P106-HD</b>
CF 65CF.180 w/CEC136 (Euro3) Eng. (01/01-on) F-F Lube (1397764)..... <b>P7232</b> F-F Lube (Long Life) (1397765)... <b>P7330</b> B-P Lube Spinner (1310891)..... <b>BC7194</b> Fuel/Water Separator (M14 x 2 mm SP Thd.) (1618993)..... <b>BF7942</b> Fuel/Water Separator (M10 x 1.5 mm SP Thd.) (1437070)..... <b>BF7941</b> 201.6 mm Fuel (1397766)..... <b>PF7767</b> 247.7 mm Fuel (Long Life) (1450184)..... <b>PF7946</b> Radial Seal Air (1657522)..... <b>RS5360</b> Cab Air (1322259)..... <b>PA4928</b> 134.9 mm Air Dryer (1391510).... <b>BA5376 +</b> 167.5 mm Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Steering (229348)..... <b>P106-HD</b>	CF 65CF.250 w/CEC184 (Euro3) Eng. (01/01-on) F-F Lube (1397764)..... <b>P7232</b> F-F Lube (Long Life) (1397765)... <b>P7330</b> B-P Lube Spinner (1310891)..... <b>BC7194</b> Fuel/Water Separator (M10 x 1.5 mm SP Thd.) (1437070)..... <b>BF7941</b> Fuel/Water Separator (M14 x 2 mm SP Thd.) (1618993)..... <b>BF7942</b> 201.6 mm Fuel (1397766)..... <b>PF7767</b> 247.7 mm Fuel (Long Life) (1450184)..... <b>PF7946</b>	75-Serie 75.270 ATi w/8.65L Eng. Lube (1316123)..... <b>B7182 +</b> Fuel (To 9/96) (247138)..... <b>BF980</b> Fuel (9/96-on) (1318695)..... <b>BF7664</b> Radial Seal Air (754718)..... <b>RS4861</b> Steering..... <b>P106-HD</b>
		75-Serie 75.270 ATi w/RS200L Eng. (02/92-05/98) Lube (1316123)..... <b>B7182 +</b> Fuel (2/92-8/96) (247138)..... <b>BF980</b> Fuel (9/96-5/98) (1318695)..... <b>BF7664</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

DAF Trucks (cont'd)	DAF Trucks (cont'd)	DAF Trucks (cont'd)
75-Serie 75.270 ATi w/RS200L Eng. (02/92-05/98) (Cont'd)	CF 75CF.250 w/PF183M (Euro2) Eng. (03/98-12/00) (Cont'd)	CF 75CF.310 w/PE228C (Euro3) Eng. (01/01-on)
Radial Seal Air (754718)..... <b>RS4861</b>	Cab Air (1322259)..... <b>PA4928</b>	F-F Lube (1397764)..... <b>P7232</b>
Air Dryer (Mann TB1374X)..... <b>BA5374 +</b>	Air Dryer (Mann TB1374X)..... <b>BA5374 +</b>	F-F Lube (Long Life) (1397765)... <b>P7330</b>
Trans. (5000807213)..... <b>PT8385</b>	Steering (229348)..... <b>P106-HD</b>	B-P Lube Spinner (1310891)..... <b>BC7194</b>
Steering (229348)..... <b>P106-HD</b>	CF 75CF.250 w/PR250S (Euro4-5) Eng. (04/06-on)	Fuel/Water Separator (5/02-on) (1433649)..... <b>BF1383-O</b>
75-Serie 75.300 w/RS222 Eng.	F-F Lube (1397764)..... <b>P7232</b>	201.6 mm Fuel (1397766)..... <b>PF7767</b>
Lube (Mann W13120/2)..... <b>B7182 +</b>	Lube (Long Life) (1397765)..... <b>P7330</b>	247.7 mm Fuel (Long Life) (1450184)..... <b>PF7946</b>
Fuel (482247138)..... <b>BF980</b>	Fuel/Water Separator (1433649). <b>BF1383-O</b>	Radial Seal Air (Don. Air System) <b>RS3952</b>
Radial Seal Air (Mann C25860)... <b>RS4861</b>	Fuel (1643080)..... <b>PF7947</b>	Radial Seal Air (Mann & Hummel Air System) (1657522)..... <b>RS5360</b>
Steering (905480)..... <b>P106</b>	Radial Seal Air (1638026)..... <b>RS5360</b>	Cab Air (1322259)..... <b>PA4928</b>
75-Serie 75.300 ATi w/8.65L Eng.	Cab Air (1362124)..... <b>PA5341</b>	134.9 mm Air Dryer (1391510)... <b>BA5376 +</b>
Lube (1316123)..... <b>B7182 +</b>	Steering (229348)..... <b>P106-HD</b>	167.5 mm Air Dryer (Mann TB1374X)..... <b>BA5374 +</b>
Fuel (To 9/96) (247138)..... <b>BF980</b>	Urea Oil/Air Separator (1686587)..... <b>OAS98000</b>	Steering (229348)..... <b>P106-HD</b>
Fuel (9/96-on) (1318695)..... <b>BF7664</b>	CF 75CF.290 w/PF183M Eng. (09/98-on)	CF 75CF.310 w/PR310S (Euro4) Eng. (04/06-on)
Radial Seal Air (754718)..... <b>RS4861</b>	Lube (1345332)..... <b>B7161</b>	Lube (1397764)..... <b>P7232</b>
Steering..... <b>P106-HD</b>	Fuel..... <b>BF7664</b>	Lube (Long Life) (1397765)..... <b>P7330</b>
75-Serie 75.300 ATi w/RS222L Eng. (02/92-05/98)	442.9 mm Radial Seal Air (1385791)..... <b>RS4562</b>	Fuel/Water Separator (1433649). <b>BF1383-O</b>
Lube (1316123)..... <b>B7182 +</b>	479.4 mm Some Radial Seal Air (Mann C291290)..... <b>RS3888</b>	Fuel (1643080)..... <b>PF7947</b>
Fuel (2/92-8/96) (247138)..... <b>BF980</b>	Radial Seal Air (5/02-on) (1657522)..... <b>RS5360</b>	418.3 mm Radial Seal Air (1638026)..... <b>RS5360</b>
Fuel (9/96-5/98) (1318695)..... <b>BF7664</b>	Cab Air..... <b>PA4928</b>	479.4 mm Radial Seal Air (1638006)..... <b>RS4959</b>
Radial Seal Air (754718)..... <b>RS4861</b>	Steering (1902137)..... <b>P106-HD</b>	Cab Air (1362124)..... <b>PA5341</b>
Air Dryer (Mann TB1374X)..... <b>BA5374 +</b>	CF 75CF.290 w/PF212M (Euro2) Eng. (03/98-12/00)	Steering (229348)..... <b>P106-HD</b>
Trans. (5000807213)..... <b>PT8385</b>	Lube (1345332)..... <b>B7161</b>	Urea Oil/Air Separator (1686587)..... <b>OAS98000</b>
Steering (229348)..... <b>P106-HD</b>	Fuel/Water Separator (5/02-on) (1433649)..... <b>BF1383-O</b>	CF 75CF.320 w/PF183M Eng. (3/98-on)
75-Serie 75.320 w/WS235 Eng.	Fuel (1318695)..... <b>BF7664</b>	Lube (1345332)..... <b>B7161</b>
Metric Thd. Lube (1345332)..... <b>B7161</b>	442.9 mm Radial Seal Air (1346885)..... <b>RS4562</b>	Fuel..... <b>BF7664</b>
Std. Thd. Lube (1346986)..... <b>B7182 +</b>	479.4 mm Radial Seal Air (1317409)..... <b>RS3888</b>	442.9 mm Radial Seal Air (1385791)..... <b>RS4562</b>
CF 75CF.250 w/PE183C (Euro3) Eng. (01/01-on)	Cab Air (1322259)..... <b>PA4928</b>	479.4 mm Some Radial Seal Air (Mann C291290)..... <b>RS3888</b>
F-F Lube (1397764)..... <b>P7232</b>	Air Dryer (Mann TB1374X)..... <b>BA5374 +</b>	Radial Seal Air (5/02-on) (1657522)..... <b>RS5360</b>
F-F Lube (Long Life) (1397765)... <b>P7330</b>	Steering (229348)..... <b>P106-HD</b>	Cab Air..... <b>PA4928</b>
B-P Lube Spinner (1310891)..... <b>BC7194</b>	CF 75CF.310 w/PE183C Eng. (07/00-on)	Steering (1902137)..... <b>P106-HD</b>
Fuel/Water Separator (5/02-on) (1433649)..... <b>BF1383-O</b>	F-F Lube (1397764)..... <b>P7232</b>	CF 75CF.320 w/PF235M (Euro2) Eng. (03/98-12/00)
201.6 mm Fuel (1397766)..... <b>PF7767</b>	F-F Lube (Long Life) (1397765)... <b>P7330</b>	Lube (1345332)..... <b>B7161</b>
247.7 mm Fuel (Long Life) (1450184)..... <b>PF7946</b>	B-P Lube Spinner..... <b>BC7194</b>	Fuel/Water Separator (5/02-on) (1433649)..... <b>BF1383-O</b>
Radial Seal Air (Don. Air System) <b>RS3952</b>	Fuel/Water Separator (5/02-on) (1433649)..... <b>BF1383-O</b>	Fuel (1318695)..... <b>BF7664</b>
Radial Seal Air (Mann & Hummel Air System) (1657522)..... <b>RS5360</b>	201.6 mm Fuel (1397766)..... <b>PF7767</b>	442.9 mm Radial Seal Air (1346885)..... <b>RS4562</b>
Cab Air (1322259)..... <b>PA4928</b>	247.7 mm Fuel (Long Life) (1450184)..... <b>PF7946</b>	479.4 mm Radial Seal Air (1317409)..... <b>RS3888</b>
134.9 mm Air Dryer (1391510)... <b>BA5376 +</b>	Radial Seal Air (Don. Air System) <b>RS3952</b>	479.4 mm Radial Seal Air (1322259)..... <b>PA4928</b>
167.5 mm Air Dryer (Mann TB1374X)..... <b>BA5374 +</b>	Radial Seal Air (Mann & Hummel Air System) (1657522)..... <b>RS5360</b>	Air Dryer (Mann TB1374X)..... <b>BA5374 +</b>
Steering (229348)..... <b>P106-HD</b>	Cab Air..... <b>PA4928</b>	Steering (229348)..... <b>P106-HD</b>
CF 75CF.250 w/PF183M (Euro2) Eng. (03/98-12/00)	Steering (229348)..... <b>P106-HD</b>	
Lube (1345332)..... <b>B7161</b>		
Fuel/Water Separator (5/02-on) (1433649)..... <b>BF1383-O</b>		
Fuel (1318695)..... <b>BF7664</b>		
442.9 mm Radial Seal Air (1346885)..... <b>RS4562</b>		
479.4 mm Radial Seal Air (1317409)..... <b>RS3888</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

**Trucks & Buses Applications** **BALDWIN FILTERS**

DAF Trucks (cont'd)	DAF Trucks (cont'd)	DAF Trucks (cont'd)
CF 75CF.360 w/PE183C Eng. (7/00-on) F-F Lube (1397764)..... P7232 F-F Lube (Long Life) (1397765)... P7330 B-P Lube Spinner..... BC7194 Fuel/Water Separator (5/02-on) (1433649)..... BF1383-O 201.6 mm Fuel (1397766)..... PF7767 247.7 mm Fuel (Long Life) (1450184)..... PF7946 Radial Seal Air (Don. Air System) RS3952 Radial Seal Air (Mann & Hummel Air System) (1657522)..... RS5360 Cab Air..... PA4928 Steering (229348)..... P106-HD	85-Serie 85.300 ATi w/WS222L Eng. (02/92-05/98) Lube (1316123)..... B7182 + Fuel (3/95-8/96) (247138)..... BF980 Fuel (9/96-5/97) (1318695)..... BF7664 Fuel (1309511)..... BF7696 Radial Seal Air (754718)..... RS4861 Air Dryer (Mann TB1374X)..... BA5374 + Steering (229348)..... P106-HD	85-Serie 85.360 ATi w/WS268L Eng. (09/96-on) (Cont'd) Steering (229348)..... P106-HD
CF 75CF.360 w/PE265C (Euro3) Eng. (01/01-on) F-F Lube (1397764)..... P7232 F-F Lube (Long Life) (1397765)... P7330 B-P Lube Spinner (1310891)..... BC7194 Fuel/Water Separator (5/02-on) (1433649)..... BF1383-O 201.6 mm Fuel (1397766)..... PF7767 247.7 mm Fuel (Long Life) (1450184)..... PF7946 Radial Seal Air (Don. Air System) RS3952 Radial Seal Air (Mann & Hummel Air System) (1657522)..... RS5360 Cab Air (1322259)..... PA4928 134.9 mm Air Dryer (1391510).... BA5376 + 167.5 mm Air Dryer (Mann TB1374X)..... BA5374 + Steering (229348)..... P106-HD	85-Serie 85.330 ATi w/WS242L Eng. (07/92-08/96) Lube (267714)..... B7187 + Fuel (3/95-8/96) (247138)..... BF980 Fuel (9/96-5/97)..... BF7664 Fuel (1309511)..... BF7696 Radial Seal Air (754718)..... RS4861 Air Dryer (Mann TB1374X)..... BA5374 + Steering (229348)..... P106-HD	85-Serie 85.400 ATi w/WS295M Eng. (03/95-on) Lube (267714)..... B7187 + Fuel (3/95-8/96) (247138)..... BF980 Fuel (9/96-5/97) (1318695)..... BF7664 Fuel (1309511)..... BF7696 Air (667078)..... PA2813 Air Dryer (Mann TB1374X)..... BA5374 + Steering (229348)..... P106-HD
CF 75CF.360 w/PR360S (Euro 4-5) Eng. (04/06-on) Lube (1397764)..... P7232 Lube (Long Life) (1397765)..... P7330 Fuel/Water Separator (1433649) BF1383-O Fuel (1643080)..... PF7947 418.3 mm Radial Seal Air (1638026)..... RS5360 479.4 mm Radial Seal Air (1638006)..... RS4959 Cab Air (1362124)..... PA5341 Steering (229348)..... P106-HD Urea Oil/Air Separator (1686587)..... OAS98000	85-Serie 85.330 ATi w/WS242L Eng. (09/96-on) Lube (1316123)..... B7182 + Fuel (1318695)..... BF7664 Radial Seal Air (754718)..... RS4861 Air Dryer (Mann TB1374X)..... BA5374 + Steering (229348)..... P106-HD	CF 85CF.340 w/XE Series Eng. (7/00-on) F-F Lube (1397764)..... P7232 B-P Lube Spinner..... BC7194 Fuel/Water Separator (5/02-on) (1433649)..... BF1383-O Fuel Ele. (1397766)..... PF7767 473.9 mm Radial Seal Air (1363024)..... RS4959 505.6 mm Radial Seal Air (Don. Air System)..... RS3952 Cab Air (7/00-12/00)..... PA4928 Cab Air (1/01-on) (1362124)..... PA5341 Trans. (5000807213)..... PT8385 Steering (229348)..... P106-HD
85-Serie 85.300 ATi w/11.6L Eng. 225.4 mm Lube (1316123)..... B7182 + 314.3 mm Lube (267714)..... B7187 + Fuel (To 9/96) (247138)..... BF980 Fuel (9/96-on) (1318695)..... BF7664 418.3 mm Radial Seal Air (754718)..... RS4861 479.4 mm Radial Seal Air (1317409)..... RS3888 Coolant (1296929)..... B5134 + Steering..... P106-HD	85-Serie 85.360 ATi w/WS268L Eng. (07/92-08/96) Lube (267714)..... B7187 + Fuel (3/95-8/96) (247138)..... BF980 Fuel (9/96-5/97)..... BF7664 Fuel (1309511)..... BF7696 Radial Seal Air (754718)..... RS4861 Air Dryer (Mann TB1374X)..... BA5374 + Steering (229348)..... P106-HD	CF 85CF.340 w/XE250C (Euro3) Eng. (01/01-on) F-F Lube (1397764)..... P7232 F-F Lube (Long Life) (1397765)... P7330 B-P Lube Spinner (1310891)..... BC7194 Fuel/Water Separator (5/02-on) (1433649)..... BF1383-O 201.6 mm Fuel (1397766)..... PF7767 247.7 mm Fuel (Long Life) (1450184)..... PF7946 473.9 mm Radial Seal Air..... RS4959 505.6 mm Radial Seal Air (Don. Air System)..... RS3952 Cab Air (To 12/00) (1322259).... PA4928 Cab Air (1/01-on) (1362124)..... PA5341 134.9 mm Air Dryer (1391510).... BA5376 + 167.5 mm Air Dryer (Mann TB1374X)..... BA5374 + Trans. (5000807213)..... PT8385 Steering (229348)..... P106-HD
	85-Serie 85.360 ATi w/WS268L Eng. (09/96-on) Lube (1316123)..... B7182 + Fuel (1318695)..... BF7664 Radial Seal Air (754718)..... RS4861 Air Dryer (Mann TB1374X)..... BA5374 +	CF 85CF.340 w/XF250M (Euro2) Eng. (09/98-12/00) F-F Lube (1310901)..... B7162 B-P Lube Spinner (1310891)..... BC7194 Fuel/Water Separator (05/02-on) (1433649)..... BF1383-O Fuel (1318695)..... BF7664

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

DAF Trucks (cont'd)	DAF Trucks (cont'd)	DAF Trucks (cont'd)
CF 85CF.340 w/XF250M (Euro2) Eng. (09/98-12/00) (Cont'd)	CF 85CF.380 w/XE280C (Euro3) Eng. (01/01-on) (Cont'd)	CF 85CF.430 w/XE Series Engs. (7/00-on)
418.3 mm Radial Seal Air (754718)..... <b>RS4861</b>	247.7 mm Fuel (Long Life) (1450184)..... <b>PF7946</b>	F-F Lube (1397764)..... <b>P7232</b>
479.4 mm Radial Seal Air (1317409)..... <b>RS3888</b>	473.9 mm Radial Seal Air..... <b>RS4959</b>	B-P Lube Spinner..... <b>BC7194</b>
Cab Air (To 12/00) (1322259)..... <b>PA4928</b>	505.6 mm Radial Seal Air (Don. Air System) (1353115)..... <b>RS3952</b>	Fuel/Water Separator (5/02-on) (1433649)..... <b>BF1383-O</b>
Cab Air (1/01-on) (1362124)..... <b>PA5341</b>	Cab Air (To 12/00) (1322259)..... <b>PA4928</b>	Fuel Ele. (1397766)..... <b>PF7767</b>
Air Dryer (Mann TB1374X)..... <b>BA5374 +</b>	Cab Air (1/01-on) (1362124)..... <b>PA5341</b>	473.9 mm Radial Seal Air (1363024)..... <b>RS4959</b>
Steering (229348)..... <b>P106-HD</b>	134.9 mm Air Dryer (1391510)..... <b>BA5376 +</b>	505.6 mm Radial Seal Air (Don. Air System)..... <b>RS3952</b>
CF 85CF.340 w/DAF XF-M Eng.	167.5 mm Air Dryer (Mann TB1374X)..... <b>BA5374 +</b>	Cab Air (7/00-12/00)..... <b>PA4928</b>
F-F Lube (1310901)..... <b>B7162</b>	Trans. (5000807213)..... <b>PT8385</b>	Cab Air (1/01-on) (1362124)..... <b>PA5341</b>
B-P Lube Spinner..... <b>BC7194</b>	Steering (229348)..... <b>P106-HD</b>	Trans. (5000807213)..... <b>PT8385</b>
Fuel/Water Separator (1433649)..... <b>BF1383-O</b>	CF 85CF.380 w/XF280M (Euro2) Eng. (09/98-12/00)	Steering (229348)..... <b>P106-HD</b>
Fuel (1318695)..... <b>BF7664</b>	F-F Lube (1310901)..... <b>B7162</b>	CF 85CF.430 w/XE315C (Euro 3) Eng. (01/01-on)
418.3 mm Radial Seal Air (Mann C25860)..... <b>RS4861</b>	B-P Lube Spinner (1310891)..... <b>BC7194</b>	F-F Lube..... <b>P7232</b>
479.4 mm Some Radial Seal Air (1317409)..... <b>RS3888</b>	Fuel/Water Separator (5/02-on) (1433649)..... <b>BF1383-O</b>	F-F Lube (Long Life) (1397765)..... <b>P7330</b>
Cab Air (7/00-12/00)..... <b>PA4928</b>	Fuel (1318695)..... <b>BF7664</b>	B-P Lube Spinner..... <b>BC7194</b>
Cab Air (1/01-on) (1362124)..... <b>PA5341</b>	418.3 mm Radial Seal Air (754718)..... <b>RS4861</b>	Fuel/Water Separator (5/02-on) (1433649)..... <b>BF1383-O</b>
Air Dryer (Mann TB1374x)..... <b>BA5374 +</b>	479.4 mm Radial Seal Air (1317409)..... <b>RS3888</b>	201.6 mm P. Fuel..... <b>PF7767</b>
Trans. (5000807213)..... <b>PT8385</b>	Cab Air (To 12/00)..... <b>PA4928</b>	247.7 mm P. Fuel (Long Life) (1450184)..... <b>PF7946</b>
Steering (229348)..... <b>P106-HD</b>	Cab Air (1/01-on) (1362124)..... <b>PA5341</b>	473.9 mm Radial Seal Air..... <b>RS4959</b>
CF 85CF.360 w/MX265S (Euro 4-5) Eng. (05/06-on)	Air Dryer (Mann TB1374X)..... <b>BA5374 +</b>	505.6 mm Radial Seal Air (Don. Air System)..... <b>RS3952</b>
F-F Lube (1643070)..... <b>P40019</b>	Trans. (5000807213)..... <b>PT8385</b>	Cab Air (1362124)..... <b>PA5341</b>
B-P Lube Spinner (1643072)..... <b>BC7326 +</b>	Steering (229348)..... <b>P106-HD</b>	134.9 mm Air Dryer (1391510)..... <b>BA5376 +</b>
Fuel/Water Separator (1433649)..... <b>BF1383-O</b>	CF 85CF.380 w/DAF XF-M Series Engs. (3/98-on)	167.5 mm Air Dryer (Mann TB1374X)..... <b>BA5374 +</b>
Fuel (1643080)..... <b>PF7947</b>	F-F Lube (1310901)..... <b>B7162</b>	Trans. (5000807213)..... <b>PT8385</b>
Radial Seal Air (1638006)..... <b>RS4959</b>	B-P Lube Spinner..... <b>BC7194</b>	Steering (229348)..... <b>P106-HD</b>
Cab Air (1362124)..... <b>PA5341</b>	Fuel/Water Separator (1433649)..... <b>BF1383-O</b>	CF 85CF.430 w/XF315M (Euro 2) Eng. (03/98-12/00)
Air Dryer (1391510)..... <b>BA5376 +</b>	Fuel (1318695)..... <b>BF7664</b>	F-F Lube..... <b>B7162</b>
Steering (229348)..... <b>P106-HD</b>	418.3 mm Radial Seal Air (Mann C25860)..... <b>RS4861</b>	B-P Lube Spinner..... <b>BC7194</b>
Urea Oil/Air Separator (1686587)..... <b>OAS98000</b>	479.4 mm Some Radial Seal Air (1317409)..... <b>RS3888</b>	Fuel/Water Separator (5/02-on) (1433649)..... <b>BF1383-O</b>
CF 85CF.380 w/XE Series Engs. (7/00-on)	Cab Air (7/00-12/00)..... <b>PA4928</b>	Fuel..... <b>BF7664</b>
F-F Lube (1397764)..... <b>P7232</b>	Cab Air (1/01-on) (1362124)..... <b>PA5341</b>	418.3 mm Radial Seal Air..... <b>RS4861</b>
B-P Lube Spinner..... <b>BC7194</b>	Air Dryer (Mann TB1374x)..... <b>BA5374 +</b>	479.4 mm Radial Seal Air..... <b>RS3888</b>
Fuel/Water Separator (5/02-on) (1433649)..... <b>BF1383-O</b>	Trans. (5000807213)..... <b>PT8385</b>	Cab Air (To 12/00)..... <b>PA4928</b>
Fuel Ele. (1397766)..... <b>PF7767</b>	Steering (229348)..... <b>P106-HD</b>	Cab Air (1/01-on) (1362124)..... <b>PA5341</b>
473.9 mm Radial Seal Air (1363024)..... <b>RS4959</b>	CF 85CF.410 w/MX300S (Euro 4-5) Eng. (05/06-on)	Air Dryer (Mann TB1374X)..... <b>BA5374 +</b>
505.6 mm Radial Seal Air (Don. Air System)..... <b>RS3952</b>	F-F Lube (1643070)..... <b>P40019</b>	Trans. (5000807213)..... <b>PT8385</b>
Cab Air (7/00-12/00)..... <b>PA4928</b>	B-P Lube Spinner (1643072)..... <b>BC7326 +</b>	Steering (229348)..... <b>P106-HD</b>
Cab Air (1/01-on) (1362124)..... <b>PA5341</b>	Fuel/Water Separator (1433649)..... <b>BF1383-O</b>	CF 85CF.430 w/XF-M Series Eng. (3/98-on)
Trans. (5000807213)..... <b>PT8385</b>	Fuel (1643080)..... <b>PF7947</b>	F-F Lube (1310901)..... <b>B7162</b>
Steering (229348)..... <b>P106-HD</b>	Radial Seal Air (1638006)..... <b>RS4959</b>	B-P Lube Spinner..... <b>BC7194</b>
CF 85CF.380 w/XE280C (Euro3) Eng. (01/01-on)	Cab Air (1362124)..... <b>PA5341</b>	Fuel/Water Separator (1433649)..... <b>BF1383-O</b>
F-F Lube (1397764)..... <b>P7232</b>	Air Dryer (1391510)..... <b>BA5376 +</b>	Fuel (1318695)..... <b>BF7664</b>
F-F Lube (Long Life) (1397765)..... <b>P7330</b>	Steering (229348)..... <b>P106-HD</b>	418.3 mm Radial Seal Air (Mann C25860)..... <b>RS4861</b>
B-P Lube Spinner (1310891)..... <b>BC7194</b>	Urea Oil/Air Separator (1686587)..... <b>OAS98000</b>	479.4 mm Some Radial Seal Air (1317409)..... <b>RS3888</b>
Fuel/Water Separator (5/02-on) (1433649)..... <b>BF1383-O</b>		Cab Air (7/00-12/00)..... <b>PA4928</b>
201.6 mm Fuel (1397766)..... <b>PF7767</b>		Cab Air (1/01-on) (1362124)..... <b>PA5341</b>
		Air Dryer (Mann TB1374x)..... <b>BA5374 +</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

DAF Trucks (cont'd)	DAF Trucks (cont'd)	DAF Trucks (cont'd)
CF 85CF.430 w/XF-M Series Eng. (3/98-on) (Cont'd) Trans. (5000807213)..... PT8385 Steering (229348)..... P106-HD	95-Serie 95.300 ATi w/WS222G Eng. (03/95-05/97) Lube (267714)..... B7187 + Fuel (3/95-8/96) (247138)..... BF980 Fuel (9/96-5/97) (1318695)..... BF7664 Air (667078)..... PA2813 Air Dryer (Mann TB1374X)..... BA5374 + Steering (229348)..... P106-HD	95-Serie 95.360 w/WS268 Eng. Lube (267714)..... B7187 + Fuel (8/90-8/96) (Mann WK962/4)..... BF980 Fuel (9/96-on) (Mann WDK940/5)..... BF7664 374.7 mm Some Air (Mann C20325/2)..... PA2405 377.8 mm Air (667078)..... PA2813 Steering (229348)..... P106-HD
CF 85CF.460 w/MX340S Eng. (05/06-on) F-F Lube (1643070)..... P40019 B-P Lube Spinner (1643072)..... BC7326 + Fuel/Water Separator (1433649)..... BF1383-O Fuel (1643080)..... PF7947 Radial Seal Air (1638006)..... RS4959 Cab Air (1362124)..... PA5341 Air Dryer (1391510)..... BA5376 + Steering (229348)..... P106-HD Urea Oil/Air Separator (1686587)..... OAS98000	95.300 ATi w/ WS222G Eng. (03/95-05/97) Lube (267714)..... B7187 + Fuel (09/96-05/97) (1318695)..... BF7664 Fuel (03/95-08/96) (247138)..... BF980 Radial Seal Air (667078)..... PA2813 Air Dryer (699387)..... BA5374 + Steering (229348)..... P106-HD	95-Serie 95.360 ATi w/WS282 Eng. 225.4 mm Lube (1316123)..... B7182 + 314.3 mm Lube (267714)..... B7187 + Fuel (To 9/96) (247138)..... BF980 Fuel (9/96-on) (1318695)..... BF7664 374.7 mm Some Air (265045)..... PA2405 377.8 mm Air (667078)..... PA2813 Coolant (1296929)..... B5134 + Steering..... P106-HD
CF 85CF.480 w/XE Series Eng. (7/00-on) F-F Lube Ele. (1397764)..... P7232 B-P Lube Spinner..... BC7194 Fuel/Water Separator (5/02-on) (1433649)..... BF1383-O Fuel Ele. (1397766)..... PF7767 473.9 mm Radial Seal Air (1363024)..... RS4959 505.6 mm Radial Seal Air (Don. Air System)..... RS3952 Cab Air (7/00-12/00)..... PA4928 Cab Air (1/01-on) (1362124)..... PA5341 Trans. (5000807213)..... PT8385 Steering (229348)..... P106-HD	95-Serie 95.310 ATi w/WS282 Eng. 225.4 mm Lube (1316123)..... B7182 + 314.3 mm Lube (267714)..... B7187 + Fuel (To 9/96) (247138)..... BF980 Fuel (9/96-on) (1318695)..... BF7664 374.7 mm Some Air (265045)..... PA2405 377.8 mm Air (667078)..... PA2813 Coolant (1296929)..... B5134 + Steering..... P106-HD	95-Serie 95.360 ATi w/WS268 Eng. (03/95-05/97) Lube (267714)..... B7187 + Fuel (3/95-8/96) (247138)..... BF980 Fuel (9/96-5/97) (1318695)..... BF7664 Fuel (1309511)..... BF7696 Air (667078)..... PA2813 Air Dryer (Mann TB1374X)..... BA5374 + Steering (229348)..... P106-HD
CF 85CF.480 w/XE355C (Euro 3) Eng. (06/02-on) F-F Lube..... P7232 F-F Lube (Long Life) (1397765)..... P7330 B-P Lube..... BC7194 Fuel/Water Separator (1433649)..... BF1383-O 201.6 mm P. Fuel..... PF7767 247.7 mm P. Fuel (Long Life) (1450184)..... PF7946 Radial Seal Air..... RS3888 Cab Air (1362124)..... PA5341 134.9 mm Air Dryer (1391510)..... BA5376 + 167.5 mm Air Dryer (Mann TB1374X)..... BA5374 + Trans. (5000807213)..... PT8385 Steering (229348)..... P106-HD	95-Serie 95.310 ATi w/WS225 Eng. (03/95-05/97) Lube (267714)..... B7187 + Fuel (3/95-8/96) (247138)..... BF980 Fuel (9/96-5/97) (1318695)..... BF7664 Air (667078)..... PA2813 Air Dryer (Mann TB1374X)..... BA5374 + Steering (229348)..... P106-HD	95-Serie 95.380 ATi w/WS282 Eng. 225.4 mm Lube (1316123)..... B7182 + 314.3 mm Lube (267714)..... B7187 + Fuel (To 9/96) (247138)..... BF980 Fuel (9/96-on) (1318695)..... BF7664 374.7 mm Some Air (265045)..... PA2405 377.8 mm Air (667078)..... PA2813 Coolant (1296929)..... B5134 + Steering..... P106-HD
CF 85CF.510 w/MX375S Eng. (05/06-on) F-F Lube (1643070)..... P40019 B-P Lube Spinner (1643072)..... BC7326 + Fuel/Water Separator (1433649)..... BF1383-O Fuel (1643080)..... PF7947 Radial Seal Air (1638006)..... RS4959 Cab Air (1362124)..... PA5341 Air Dryer (1391510)..... BA5376 + Steering (229348)..... P106-HD Urea Oil/Air Separator (1686587)..... OAS98000	95-Serie 95.330 ATi w/WS282 Eng. 225.4 mm Lube (1316123)..... B7182 + 314.3 mm Lube (267714)..... B7187 + Fuel (To 9/96) (247138)..... BF980 Fuel (9/96-on) (1318695)..... BF7664 374.7 mm Some Air (265045)..... PA2405 377.8 mm Air (667078)..... PA2813 Coolant (1296929)..... B5134 + Steering..... P106-HD	XF 95.380XF w/XF280M, XF315M, XF355M, VF390M Eng. (3/97-on) F-F Lube (1310901)..... B7162 F-F Lube (1327672)..... B7224 B-P Lube Spinner (1310891)..... BC7194 Fuel (1309511)..... BF7696 Fuel (1318695)..... BF7664 Fuel/Water Separator (1319159)..... BF1269 505.6 mm Radial Seal Air (1353115)..... RS3952 522.3 mm Radial Seal Air (1295090)..... RS3744 Coolant (w/Chemical) (1289132)..... BW5071 Coolant (w/o Chemical) (1296929)..... B5134 + Steering (229348)..... P106-HD
	95-Serie 95.330 ATi w/WS242 Eng. (03/95-05/97) Lube (267714)..... B7187 + Fuel (3/95-8/96) (247138)..... BF980 Fuel (9/96-5/97) (1318695)..... BF7664 Air (667078)..... PA2813 Air Dryer (Mann TB1374X)..... BA5374 + Steering (229348)..... P106-HD	95-Serie 95.400 ATi Lube (267714)..... B7187 + Fuel (To 9/96) (247138)..... BF980 Fuel (9/96-on) (1318695)..... BF7664 374.7 mm O. Air (265045)..... PA2405
	95-Serie 95.350 ATi w/WS259 Eng. (03/95-05/97) Lube (267714)..... B7187 + Fuel (3/95-8/96) (247138)..... BF980 Fuel (9/96-5/97) (1318695)..... BF7664 Air (667078)..... PA2813 Air Dryer (Mann TB1374X)..... BA5374 + Steering (229348)..... P106-HD	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



DAF Trucks (cont'd)	
95-Serie 95.400 ATi (Cont'd)	
377.8 mm Some Air (667078).....	PA2813
Steering (1902137).....	P106-HD
95-Serie 95.430 ATi	
Lube (267714).....	B7187 +
Fuel (To 9/96) (247138).....	BF980
Fuel (9/96-on) (1318695).....	BF7664
374.7 mm O. Air (265045).....	PA2405
377.8 mm Some Air (667078).....	PA2813
Steering (1902137).....	P106-HD
XF 95.430XF w/XF280M, XF315M, XF355M, VF390M Eng. (3/97-on)	
F-F Lube (1310901).....	B7162
F-F Lube (1327672).....	B7224
B-P Lube Spinner (1310891).....	BC7194
Fuel (1309511).....	BF7696
Fuel (1318695).....	BF7664
Fuel/Water Separator (1319159).....	BF1269
505.6 mm Radial Seal Air (1353115).....	RS3952
522.3 mm Radial Seal Air (1295090).....	RS3744
Coolant (w/Chemical) (1289132).....	BW5071
Coolant (w/o Chemical) (1296929).....	B5134 +
Steering (229348).....	P106-HD
XF 95.480XF w/XF280M, XF315M, XF355M, VF390M Eng.	
F-F Lube (1310901).....	B7162
F-F Lube (1327672).....	B7224
B-P Lube Spinner (1310891).....	BC7194
Fuel (1309511).....	BF7696
Fuel (1318695).....	BF7664
Fuel/Water Separator (1319159).....	BF1269
505.6 mm Radial Seal Air (1353115).....	RS3952
522.3 mm Radial Seal Air (1295090).....	RS3744
Coolant (w/Chemical) (1289132).....	BW5071
Coolant (w/o Chemical) (1296929).....	B5134 +
Steering (229348).....	P106-HD
XF 95.530XF w/XF280M, XF315M, XF355M, VF390M Eng.	
F-F Lube (1310901).....	B7162
F-F Lube (1327672).....	B7224
B-P Lube Spinner (1310891).....	BC7194
Fuel (1309511).....	BF7696
Fuel (1318695).....	BF7664
Fuel/Water Separator (1319159).....	BF1269
505.6 mm Radial Seal Air (1353115).....	RS3952
522.3 mm Radial Seal Air (1295090).....	RS3744
Coolant (w/Chemical) (1289132).....	BW5071
Coolant (w/o Chemical) (1296929).....	B5134 +
Steering (229348).....	P106-HD

DAF Trucks (cont'd)	
2000	
Lube Ele.....	P25
Fuel Ele.....	PF838
Fuel Spin-on (247138).....	BF980
374.7 mm O. Air (265045).....	PA2405
371.5 mm I. Air (692380).....	PA2835
381.0 mm Some Air (112294).....	PA2474
2400	
198.4 mm Lube Ele. (248126).....	P235
235.7 mm Lube Ele. (110371).....	PT670
Fuel (247138).....	BF980
2600	
198.4 mm Lube Ele. (248126).....	P235
235.7 mm Lube Ele. (110371).....	PT670
Fuel (247138).....	BF980
2600 w/O680, P680 Eng.	
Lube Ele.....	P25
Fuel Ele.....	PF838
2900 w/KV212 Eng.	
225.4 mm Lube (1316123).....	B7182 +
314.3 mm Lube (267714).....	B7187 +
Fuel Spin-on (247138).....	BF980
Air (667078).....	PA2813
3200 w/KS238TI Eng.	
225.4 mm Lube (1316123).....	B7182 +
314.3 mm Lube (267714).....	B7187 +
Fuel Spin-on (247138).....	BF980
Air (667078).....	PA2813
AZ1900 w/DD575, DS575 Eng.	
Lube Ele. (236481).....	P7017
Lube Spin-on (114786).....	B236 +
Can-Type Fuel.....	BF825 +
290 w/ PACCAR MX 11 Euro 6 Eng. (2013-on)	
Lube (1928868).....	P40008
Lube (1928869).....	BC40009
Fuel/Water Separator (1433649).....	BF1383-O
Radial Seal Air (1921967).....	RS4959
Cab Air (1791192).....	PA5341
Air Dryer (1821580).....	BA5284 +
Steering (229348).....	P106-HD
Urea (1927474).....	PE17000
330 w/ MX 11 Euro 6 Eng. (2013-on)	
Lube (1928868).....	P40008
Lube (1928869).....	BC40009
Fuel/Water Separator (1433649).....	BF1383-O
Radial Seal Air (1921967).....	RS4959
Cab Air (1791192).....	PA5341
Air Dryer (1821580).....	BA5284 +
Steering (229348).....	P106-HD
Urea (1927474).....	PE17000
370 w/ MX 11 Euro 6 Eng., (2013-on)	
Lube (1928868).....	P40008
Lube (1928869).....	BC40009
Fuel/Water Separator (1433649).....	BF1383-O
Radial Seal Air (1921967).....	RS4959
Cab Air (1791192).....	PA5341
Air Dryer (1821580).....	BA5284 +

DAF Trucks (cont'd)	
370 w/ MX 11 Euro 6 Eng., (2013-on) (Cont'd)	
Steering (229348).....	P106-HD
Urea (1927474).....	PE17000
400 w/ PACCAR MX 11 Euro 6 Eng. (2013-on)	
Lube (1928868).....	P40008
Lube (1928869).....	BC40009
Fuel/Water Separator (1433649).....	BF1383-O
Radial Seal Air (1921967).....	RS4959
Cab Air (1791192).....	PA5341
Air Dryer (1821580).....	BA5284 +
Steering (229348).....	P106-HD
Urea (1927474).....	PE17000
410 w/ PACCAR MX 13 Euro 6 Eng. (04/13-on)	
Lube (1629393).....	P40019
Centrifugal Lube (1872106).....	BC7326 +
Fuel/Water Separator (1433649).....	BF1383-O
Radial Seal Air (1789291).....	RS4959
Cab Air (1791192).....	PA5341
Air Dryer (1821580).....	BA5284 +
Steering (229348).....	P106-HD
Urea (1927474).....	PE17000
440 w/ PACCAR MX 11 Euro 6 Eng. (2013-on)	
Lube (1928868).....	P40008
Fuel/Water Separator (1433649).....	BF1383-O
Radial Seal Air (1921967).....	RS4959
Cab Air (1791192).....	PA5341
Air Dryer (1821580).....	BA5284 +
Steering (229348).....	P106-HD
Urea (1927474).....	PE17000
460 w/ PACCAR MX 13 Euro 6 Eng. (04/13-on)	
Lube (1629393).....	P40019
Centrifugal Lube (1872106).....	BC7326 +
Fuel/Water Separator (1433649).....	BF1383-O
Radial Seal Air (1789291).....	RS4959
Cab Air (1791192).....	PA5341
Air Dryer (1821580).....	BA5284 +
Steering (229348).....	P106-HD
Urea (1927474).....	PE17000
510 w/ PACCAR MX 13 Euro 6 Eng. (04/13-on)	
Lube (1629393).....	P40019
Centrifugal Lube (1872106).....	BC7326 +
Fuel/Water Separator (1433649).....	BF1383-O
Radial Seal Air (1789291).....	RS4959
Cab Air (1791192).....	PA5341
Air Dryer (1821580).....	BA5284 +
Steering (229348).....	P106-HD
Urea (1927474).....	PE17000
CF CF75.360 w/PR360S (Euro4) Eng. (04/06-on)	
Lube (1397764).....	P7232
Lube (Long Life) (1397765).....	P7330
Fuel/Water Separator (1433649).....	BF1383-O
Radial Seal Air (1638006).....	RS4959
Cab Air (1322259).....	PA4928
Steering (229348).....	P106-HD

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

**Trucks & Buses Applications** **BALDWIN FILTERS**

DAF Trucks (cont'd)	DAF Trucks (cont'd)	DAF Trucks (cont'd)
E2000 Series w/DH825, DHT825, DU825 Engs. Lube (661049)..... <b>B7031</b> Fuel (247138)..... <b>BF980</b> Air (112294)..... <b>PA2474</b>	XF F95.430XF w/XE Series Engs. (Cont'd) 505.6 mm Radial Seal Air (Mann C291366/1)..... <b>RS3952</b> 522.3 mm Some Radial Seal Air (Mann C291410)..... <b>RS3744</b> Cab Air (Mann CU3132)..... <b>PA4612<sup>90</sup></b> Trans. (Mann H710/1n)..... <b>PT8385</b> Steering (Mann H601/4)..... <b>P106-HD</b>	XF F95.480XF w/XF355M Eng. (09/99-10/02) F-F Lube..... <b>B7162</b> B-P Lube Spinner (1310891)..... <b>BC7194</b> Fuel/Water Separator (5/02-10/02) (1433649)..... <b>BF1383-O</b> Fuel..... <b>BF7664</b> 505.6 mm Radial Seal Air (1353115)..... <b>RS3952</b> 522.3 mm Radial Seal Air..... <b>RS3744</b> Cab Air (1322255)..... <b>PA4612<sup>90</sup></b> Air Dryer (Mann TB1374X)..... <b>BA5374<sup>+</sup></b> Trans. (5000807213)..... <b>PT8385</b> Steering (229348)..... <b>P106-HD</b>
F65 Series Lube (1306549)..... <b>B7151</b>	XF F95.380XF w/XE Series Engs. Lube (Mann W13145/6)..... <b>B7162</b> Fuel (1345335)..... <b>BF7747</b> Fuel/Water Separator (Mann PL420x)..... <b>BF1383-O</b> 505.6 mm Radial Seal Air (Mann C291366/1)..... <b>RS3952</b> 522.3 mm Some Radial Seal Air (Mann C291410)..... <b>RS3744</b> Cab Air (Mann CU3132)..... <b>PA4612<sup>90</sup></b> Trans. (Mann H710/1n)..... <b>PT8385</b> Steering (Mann H601/4)..... <b>P106-HD</b>	XF F95.530XF w/Cummins VF 390M Eng. (03/97-10/99) Dual-Flow Lube..... <b>BD103<sup>+</sup></b> Fuel/Water Separator..... <b>BF1259</b> Radial Seal Air..... <b>RS3952</b> Cab Air (1322255)..... <b>PA4612<sup>90</sup></b> Air Dryer (Mann TB1374X)..... <b>BA5374<sup>+</sup></b> Coolant..... <b>BW5071</b> Trans. (5000807213)..... <b>PT8385</b> Steering (229348)..... <b>P106-HD</b>
XF F95.380XF w/XE280C Eng. (09/99-10/02) F-F Lube (1310901)..... <b>B7162</b> B-P Lube Spinner (1310891)..... <b>BC7194</b> Fuel/Water Separator (5/02-10/02) (1433649)..... <b>BF1383-O</b> Fuel (1345335)..... <b>BF7747</b> 505.6 mm Radial Seal Air (1353115)..... <b>RS3952</b> 522.3 mm Radial Seal Air (1295090)..... <b>RS3744</b> Cab Air (1322255)..... <b>PA4612<sup>90</sup></b> Air Dryer (Mann TB1374X)..... <b>BA5374<sup>+</sup></b> Trans. (5000807213)..... <b>PT8385</b> Steering (229348)..... <b>P106-HD</b>	XF F95.430XF w/XF315M Eng. (09/99-10/02) F-F Lube..... <b>B7162</b> B-P Lube Spinner..... <b>BC7194</b> Fuel/Water Separator (5/02-10/02) (1433649)..... <b>BF1383-O</b> Fuel..... <b>BF7664</b> 505.6 mm Radial Seal Air (1353115)..... <b>RS3952</b> 522.3 mm Radial Seal Air..... <b>RS3744</b> Cab Air (1322255)..... <b>PA4612<sup>90</sup></b> Air Dryer (Mann TB1374X)..... <b>BA5374<sup>+</sup></b> Trans. (5000807213)..... <b>PT8385</b> Steering (229348)..... <b>P106-HD</b>	XF F95.530XF w/XE390C Eng. (09/99-10/02) F-F Lube..... <b>B7162</b> B-P Lube Spinner (1310891)..... <b>BC7194</b> Fuel/Water Separator (5/02-10/02) (1433649)..... <b>BF1383-O</b> Fuel..... <b>BF7747</b> Radial Seal Air (1353115)..... <b>RS3952</b> Cab Air (1322255)..... <b>PA4612<sup>90</sup></b> Air Dryer (Mann TB1374X)..... <b>BA5374<sup>+</sup></b> Trans. (5000807213)..... <b>PT8385</b> Steering (229348)..... <b>P106-HD</b>
XF F95.380XF w/XE280C Eng. (10/02-on) F-F Lube..... <b>P7232</b> B-P Lube Spinner..... <b>BC7194</b> Fuel/Water Separator (1433649)..... <b>BF1383-O</b> Fuel..... <b>PF7767</b> Radial Seal Air..... <b>RS3952</b> Cab Air (1362124)..... <b>PA5341</b> Steering..... <b>P106-HD</b>	XF F95.480XF w/XE Series Engs. Lube (Mann W13145/6)..... <b>B7162</b> Fuel (1345335)..... <b>BF7747</b> Fuel/Water Separator (Mann PL420x)..... <b>BF1383-O</b> 505.6 mm Radial Seal Air (Mann C291366/1)..... <b>RS3952</b> 522.3 mm Some Radial Seal Air (Mann C291410)..... <b>RS3744</b> Cab Air (Mann CU3132)..... <b>PA4612<sup>90</sup></b> Trans. (Mann H710/1n)..... <b>PT8385</b> Steering (Mann H601/4)..... <b>P106-HD</b>	F600 w/Cummins 5.9L Eng. Lube..... <b>BT339<sup>+</sup></b> Opt. Fuel/Water Separator..... <b>BF1226</b> S. Fuel..... <b>BF788</b> Steering..... <b>P106-HD</b>
XF F95.380XF w/XF280M Eng. (03/97-10/02) F-F Lube..... <b>B7162</b> B-P Lube Spinner (1310891)..... <b>BC7194</b> Fuel/Water Separator (5/02-10/02) (1433649)..... <b>BF1383-O</b> Fuel..... <b>BF7664</b> 505.6 mm Radial Seal Air (1353115)..... <b>RS3952</b> 522.3 mm Radial Seal Air..... <b>RS3744</b> Cab Air (1322255)..... <b>PA4612<sup>90</sup></b> Air Dryer (Mann TB1374X)..... <b>BA5374<sup>+</sup></b> Trans. (5000807213)..... <b>PT8385</b> Steering (229348)..... <b>P106-HD</b>	XF F95.480XF w/XF355C Eng. (09/99-10/02) F-F Lube..... <b>B7162</b> B-P Lube Spinner (1310891)..... <b>BC7194</b> Fuel/Water Separator (5/02-10/02) (1433649)..... <b>BF1383-O</b> Fuel..... <b>BF7747</b> 505.6 mm Radial Seal Air (1353115)..... <b>RS3952</b> 522.3 mm Radial Seal Air..... <b>RS3744</b> Cab Air (1322255)..... <b>PA4612<sup>90</sup></b> Air Dryer (Mann TB1374X)..... <b>BA5374<sup>+</sup></b> Trans. (5000807213)..... <b>PT8385</b> Steering (229348)..... <b>P106-HD</b>	F700, F700DE w/DE385 Eng. Can-Type Fuel..... <b>BF825<sup>+</sup></b>
XF F95.430XF w/XE Series Engs. Lube (Mann W13145/6)..... <b>B7162</b> Fuel (1345335)..... <b>BF7747</b> Fuel/Water Separator (Mann PL420x)..... <b>BF1383-O</b>		F800 w/Cummins 5.9L Eng. Lube..... <b>BT339<sup>+</sup></b> Opt. Fuel/Water Separator..... <b>BF1226</b> S. Fuel..... <b>BF788</b> Steering (1902137)..... <b>P106-HD</b>
		F900 w/DD575, DF575 Engs. Lube Ele..... <b>P7017</b> Fuel (247139)..... <b>BF900</b> 100.8 mm Steering..... <b>P106-HD</b> 115.9 mm Some Steering (Clean ML480)..... <b>PT691</b>
		F900 w/DE385 Eng. Can-Type Fuel..... <b>BF825<sup>+</sup></b>

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

DAF Trucks (cont'd)	DAF Trucks (cont'd)	DAF Trucks (cont'd)
F1000 w/Cummins 6BT5.9 Eng. Lube (490196)..... <b>BT339 +</b> Fuel/Water Separator (490160)... <b>BF1226</b> Steering..... <b>P106-HD</b>	F2200 Lube Ele..... <b>P25</b> Fuel Ele..... <b>PF838</b> Fuel Spin-on (247138)..... <b>BF980</b> 374.7 mm O. Air (265045)..... <b>PA2405</b> 371.5 mm I. Air (692380)..... <b>PA2835</b> 381.0 mm Some Air (112294)..... <b>PA2474</b>	F2800DKSE, FT2800 Lube Spin-on (661049)..... <b>B7031</b> Fuel (247138)..... <b>BF980</b> O. Air (265045)..... <b>PA2405</b> I. Air (692380)..... <b>PA2835</b>
F1300DF, F1300DT Lube Spin-on (671490)..... <b>B236 +</b> 136.5 mm Fuel (247139)..... <b>BF900</b> 206.4 mm Fuel (247138)..... <b>BF980</b>	F2205 Lube Ele. (213342)..... <b>P25</b> Fuel (247138)..... <b>BF980</b> O. Air (607179)..... <b>PA2475</b> I. Air (691280)..... <b>PA2814</b>	F2805DKSE, FMD2825DKTD Lube Spin-on (661049)..... <b>B7031</b> Fuel (247138)..... <b>BF980</b> O. Air (265045)..... <b>PA2405</b> I. Air (692380)..... <b>PA2835</b>
F1400 w/DD615, DF615 Eng. Fuel (247139)..... <b>BF900</b>	F2300 Series w/DH825, DHT825, DHU825 Eng. 206.4 mm Lube (114786)..... <b>B236 +</b> 168.3 mm Lube (661049)..... <b>B7031</b> Fuel (247138)..... <b>BF980</b> 374.7 mm O. Air (265045)..... <b>PA2405</b> 371.5 mm I. Air (692380)..... <b>PA2835</b> 496.9 mm O. Air (607179)..... <b>PA2475</b> 381.0 mm Some Air (112294)..... <b>PA2474</b> 473.1 mm I. Air (691280)..... <b>PA2814</b> Steering (905480)..... <b>P106</b>	F3000 Series Lube Spin-on (661049)..... <b>B7031</b> Fuel (247138)..... <b>BF980</b> 374.7 mm O. Air (265045)..... <b>PA2405</b> 371.5 mm I. Air (692380)..... <b>PA2835</b> 492.1 mm Some Air (506337)..... <b>PA3477</b>
F1500 w/DF615, DTD615 Eng. Fuel (247139)..... <b>BF900</b>	F2500 w/DK825, DKA825, DKB825 Eng. 198.4 mm Lube Ele. (248126)..... <b>P235</b> 235.7 mm Lube Ele. (110371)..... <b>PT670</b> 136.5 mm Fuel (247139)..... <b>BF900</b> 206.4 mm Fuel (247138)..... <b>BF980</b> 381.0 mm Air (112294)..... <b>PA2474</b> 496.9 mm Air (607179)..... <b>PA2475</b> 492.1 mm Some Air (506337)..... <b>PA3477</b>	F3300 Series w/DKX1160 Eng. Lube Spin-on (661049)..... <b>B7031</b> Fuel (247138)..... <b>BF980</b> 374.7 mm O. Air (265045)..... <b>PA2405</b> 371.5 mm I. Air (692380)..... <b>PA2835</b> 492.1 mm Some Air (110376)..... <b>PA3477</b> Steering (905480)..... <b>P106</b>
F1600 w/DF615, DTD615 Eng. Lube Ele. (236481)..... <b>P7017</b> 136.5 mm Fuel (247139)..... <b>BF900</b> 206.4 mm Fuel (247138)..... <b>BF980</b>	F2500 Series w/DHS825 Eng. Lube (661049)..... <b>B7031</b> Fuel (247138)..... <b>BF980</b> 496.9 mm O. Air (607179)..... <b>PA2475</b> 473.1 mm I. Air (691280)..... <b>PA2814</b> 381.0 mm Some Air (112294)..... <b>PA2474</b>	F3600 ATi Lube Spin-on (661049)..... <b>B7031</b> Fuel (247138)..... <b>BF980</b> O. Air (265045)..... <b>PA2405</b> I. Air (692380)..... <b>PA2835</b>
F1700DH, F1700DT Lube (661049)..... <b>B7031</b> Fuel (247138)..... <b>BF980</b> Air (265045)..... <b>PA2405</b>	F2600 w/DK825, DKA825, DKB825 Eng. 198.4 mm Lube Ele. (248126)..... <b>P235</b> 235.7 mm Lube Ele. (110371)..... <b>PT670</b> 136.5 mm Fuel (247139)..... <b>BF900</b> 206.4 mm Fuel (247138)..... <b>BF980</b> 381.0 mm Air (112294)..... <b>PA2474</b> 496.9 mm Air (607179)..... <b>PA2475</b> 492.1 mm Some Air (506337)..... <b>PA3477</b>	FA1100 w/DD575 Eng. (1966-on) Can-Type Fuel..... <b>BF825 +</b>
F1800 Series w/DF615, DTD615 Eng. Lube Ele. (236481)..... <b>P7017</b> 136.5 mm Fuel (247139)..... <b>BF900</b> 206.4 mm Fuel (247138)..... <b>BF980</b>	F2700 w/HA200ATI Eng. Lube (114786)..... <b>B236 +</b> Fuel (247138)..... <b>BF980</b> O. Air (265045)..... <b>PA2405</b>	FA1200DF w/DD615, DF615 Eng. Fuel (247139)..... <b>BF900</b>
F1800 w/DS575 Eng. Lube (114786)..... <b>B236 +</b> Fuel Ele. (138364)..... <b>PF838</b>	F2800 Series w/DKS1160, DKSE1160, DKTD1160 Eng. Lube Spin-on (114786)..... <b>B236 +</b> Fuel (247138)..... <b>BF980</b> 374.7 mm O. Air (265045)..... <b>PA2405</b> 371.5 mm I. Air (692380)..... <b>PA2835</b> 492.1 mm Some Air (110376)..... <b>PA3477</b>	FA1300 w/DD615, DF615 Eng. Fuel (247139)..... <b>BF900</b>
F1900 w/DS575 Eng. Lube (114786)..... <b>B236 +</b> Fuel Ele. (138364)..... <b>PF838</b>		FA1900DNS, FA1900DNT Lube Spin-on (114786)..... <b>B236 +</b> Fuel (247138)..... <b>BF980</b> Air (265045)..... <b>PA2405</b>
F2000, FA2000DH, F2005 Lube Ele..... <b>P25</b> Fuel Ele..... <b>PF838</b> Fuel Spin-on (247138)..... <b>BF980</b> 374.7 mm O. Air (265045)..... <b>PA2405</b> 371.5 mm I. Air (692380)..... <b>PA2835</b> 381.0 mm Some Air (112294)..... <b>PA2474</b>		FA2105 w/DBH825, DH825, DU825 Eng. Lube Ele. (213342)..... <b>P25</b> Fuel (247138)..... <b>BF980</b> 381.0 mm O. Air..... <b>PA2474</b> 496.9 mm O. Air (607179)..... <b>PA2475</b> 473.1 mm I. Air (691280)..... <b>PA2814</b>
F2100 Series w/DH825, DHR825, DHT825, DHTD825, DU825 Eng. Lube Spin-on (661049)..... <b>B7031</b> Fuel (247138)..... <b>BF980</b> 374.7 mm O. Air (265045)..... <b>PA2405</b> 371.5 mm I. Air (692380)..... <b>PA2835</b> 496.9 mm O. Air (607179)..... <b>PA2475</b> 473.1 mm I. Air (691280)..... <b>PA2814</b> 349.3 mm Some Air (695633)..... <b>PA2845</b> 381.0 mm Some Air (112294)..... <b>PA2474</b>		FA3305, FA3325DKX, F3326DKX Lube Spin-on (661049)..... <b>B7031</b> Fuel (247138)..... <b>BF980</b> O. Air (265045)..... <b>PA2405</b> I. Air (692380)..... <b>PA2835</b>
F2100EHD Lube Ele. (213342)..... <b>P25</b> Fuel (247138)..... <b>BF980</b> O. Air (607179)..... <b>PA2475</b> I. Air (691280)..... <b>PA2814</b>		FA900DE Fuel (247139)..... <b>BF900</b>
		150 w/ PX-5 Euro 6 Eng. (01/14-on) Lube (1399494)..... <b>BT7237</b> Fuel/Water Separator (1814637). <b>BF1293-SPS</b> Air Dryer (1391510)..... <b>BA5376 +</b> Air Dryer (1821580)..... <b>BA5284 +</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

**Trucks & Buses Applications** **BALDWIN FILTERS**

DAF Trucks (cont'd)	DAF Trucks (cont'd)	DAF Trucks (cont'd)
150 w/ PX-5 Euro 6 Eng. (01/14-on) (Cont'd)	XF XF95.380 w/XE Series Eng. (Cont'd)	XF XF95.480 w/XE355C Eng. (10/02-on)
Steering (229348)..... P106-HD	247.7 mm (Long Life) Fuel	F-F Lube (1397764)..... P7232
Urea (1927474)..... PE17000	(Mann PU966x)..... PF7946	B-P Lube Spinner (1310891)..... BC7194
180 w/ PX-5 Euro 6 Eng. (01/14-on)	Fuel/Water Separator (Mann	Fuel/Water Separator (1433649)..... BF1383-O
Lube (1399494)..... BT7237	PL420x)..... BF1383-O	Fuel (1397766)..... PF7767
Fuel/Water Separator (1814637)..... BF1293-SPS	Radial Seal Air (Mann	Radial Seal Air (1353115)..... RS3952
Air Dryer (1391510)..... BA5376 +	C291366/1)..... RS3952	Cab Air (1362124)..... PA5341
Air Dryer (1821580)..... BA5284 +	Cab Air (Mann CU2534)..... PA5341	Air Dryer (1391510)..... BA5376 +
Steering (229348)..... P106-HD	Steering..... P106-HD	Steering (229348)..... P106-HD
Urea (1927474)..... PE17000	XF XF95.380 w/XE280C Eng. (10/02-on)	XF XF95.530 w/XE Series Eng.
210 w/ PX-5 Euro 6 Eng. (01/14-on)	F-F Lube (1397764)..... P7232	Lube (Mann HU1270x)..... P7232
Lube (1399494)..... BT7237	B-P Lube Spinner (1310891)..... BC7194	Lube (Long Life) (Mann
Fuel/Water Separator (1814637)..... BF1293-SPS	Fuel/Water Separator (1433649)..... BF1383-O	HU1297x)..... P7330
Air Dryer (1391510)..... BA5376 +	Fuel (1397766)..... PF7767	201.6 mm Fuel (Mann
Air Dryer (1821580)..... BA5284 +	Radial Seal Air (1353115)..... RS3952	PU999/2x)..... PF7767
Steering (229348)..... P106-HD	Cab Air (1362124)..... PA5341	247.7 mm (Long Life) Fuel
Urea (1927474)..... PE17000	Air Dryer (1391510)..... BA5376 +	(Mann PU966x)..... PF7946
220 w/ PX-7 Euro 6 Eng. (01/14-on)	Steering (229348)..... P106-HD	Fuel/Water Separator (Mann
Lube (1399494)..... BT7237	XF XF95.430 w/XE Series Eng.	PL420x)..... BF1383-O
Fuel/Water Separator (1814637)..... BF1293-SPS	Lube (Mann HU1270x)..... P7232	Radial Seal Air (Mann
Air Dryer (1391510)..... BA5376 +	Lube (Long Life) (Mann	C291366/1)..... RS3952
Air Dryer (1821580)..... BA5284 +	HU1297x)..... P7330	Cab Air (Mann CU2534)..... PA5341
Steering (229348)..... P106-HD	201.6 mm Fuel (Mann	Steering..... P106-HD
Urea (1927474)..... PE17000	PU999/2x)..... PF7767	XF XF95.530 w/XE390C Eng. (10/02-on)
250 w/ PX-7 Euro 6 Eng. (01/14-on)	247.7 mm (Long Life) Fuel	F-F Lube (1397764)..... P7232
Lube (1399494)..... BT7237	(Mann PU966x)..... PF7946	B-P Lube Spinner (1310891)..... BC7194
Fuel/Water Separator (1814637)..... BF1293-SPS	Fuel/Water Separator (Mann	Fuel/Water Separator (1433649)..... BF1383-O
Air Dryer (1391510)..... BA5376 +	PL420x)..... BF1383-O	Fuel (1397766)..... PF7767
Air Dryer (1821580)..... BA5284 +	Radial Seal Air (Mann	Radial Seal Air (1353115)..... RS3952
Steering (229348)..... P106-HD	C291366/1)..... RS3952	Cab Air (1362124)..... PA5341
Urea (1927474)..... PE17000	Cab Air (Mann CU2534)..... PA5341	Air Dryer (1391510)..... BA5376 +
280 w/ PX-7 Euro 6 Eng. (01/14-on)	Steering..... P106-HD	Steering (229348)..... P106-HD
Lube (1399494)..... BT7237	XF XF95.430 w/XE315C Eng. (10/02-on)	XF XF105.410 w/MX300S Eng. (01/06-on)
Fuel/Water Separator (1814637)..... BF1293-SPS	F-F Lube (1397764)..... P7232	F-F Lube (1643070)..... P40019
Air Dryer (1391510)..... BA5376 +	B-P Lube Spinner (1310891)..... BC7194	B-P Lube Spinner (1643072)..... BC7326 +
Air Dryer (1821580)..... BA5284 +	Fuel/Water Separator (1433649)..... BF1383-O	Fuel/Water Separator (1433649)..... BF1383-O
Steering (229348)..... P106-HD	Fuel (1397766)..... PF7767	Fuel (1643080)..... PF7947
Urea (1927474)..... PE17000	Radial Seal Air (1353115)..... RS3952	Radial Seal Air (1638054)..... RS5413
310 w/ PACCAR PX-7 Euro 6 Eng. (01/14-on)	Cab Air (1362124)..... PA5341	Cab Air (1322255)..... PA4612 <sup>90</sup>
Lube (1399494)..... BT7237	Air Dryer (1391510)..... BA5376 +	Air Dryer (1391510)..... BA5376 +
Fuel/Water Separator (1814637)..... BF1293-SPS	Steering (229348)..... P106-HD	Steering..... P106-HD
Air Dryer (1391510)..... BA5376 +	XF XF95.480 w/XE Series Eng.	XF XF105.460 w/MX340S Eng. (01/06-on)
Air Dryer (1821580)..... BA5284 +	Lube (Mann HU1270x)..... P7232	F-F Lube (1643070)..... P40019
Steering (229348)..... P106-HD	Lube (Long Life) (Mann	B-P Lube Spinner (1643072)..... BC7326 +
Urea (1927474)..... PE17000	HU1297x)..... P7330	Fuel/Water Separator (1433649)..... BF1383-O
NAT2800, NTT2800 w/DKA1160, DKS1160	201.6 mm Fuel (Mann	Fuel (1643080)..... PF7947
Eng.	PU999/2x)..... PF7767	Radial Seal Air (1638054)..... RS5413
Lube (114786)..... B236 +	247.7 mm (Long Life) Fuel	Cab Air..... PA4612 <sup>90</sup>
Fuel (247138)..... BF980	(Mann PU966x)..... PF7946	Air Dryer (1391510)..... BA5376 +
O. Air (265045)..... PA2405	Fuel/Water Separator (Mann	Steering..... P106-HD
I. Air (692380)..... PA2835	PL420x)..... BF1383-O	XF XF105.510 w/MX375S Eng. (01/06-on)
XF XF95.380 w/XE Series Eng.	Radial Seal Air (Mann	F-F Lube (1643070)..... P40019
Lube (Mann HU1270x)..... P7232	C291366/1)..... RS3952	B-P Lube Spinner (1643072)..... BC7326 +
Lube (Long Life) (Mann	Cab Air (Mann CU2534)..... PA5341	Fuel/Water Separator (1433649)..... BF1383-O
HU1297x)..... P7330	Steering..... P106-HD	Fuel (1643080)..... PF7947
201.6 mm Fuel (Mann		Radial Seal Air (1638054)..... RS5413
PU999/2x)..... PF7767		Cab Air (1322255)..... PA4612 <sup>90</sup>
		Air Dryer (1391510)..... BA5376 +

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

DAF Trucks (cont'd)	DANA Transmissions	DENNIS EAGLE Trucks (cont'd)
XF XF105.510 w/MX375S Eng. (01/06-on) (Cont'd)	Air Shift	ProView w/Cummins L9 (9.0L) Eng. (2020)
Steering..... P106-HD	Air Shift Breather..... P187	Lube (5444774)..... B40142
XF XF105.560 w/MX410S Eng. (01/06-on)	C58122	Fuel (5303743)..... BF63000
F-F Lube (1643070)..... P40019	Trans..... PT48	Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT
B-P Lube Spinner (1643072)..... BC7326 +	SK 12763	Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT
Fuel/Water Separator (1433649)..... BF1383-O	Trans..... P80-HD	
Fuel (1643080)..... PF7947	Spicer 8125 12 Spd.	<b>DETROIT DIESEL</b> Diesel Engines
Radial Seal Air (1638054)..... RS5413	Trans..... PT82-HD +	3-53 Series
Cab Air (1658991)..... PA4612 <sup>90</sup>	Spicer 8312 5 Spd.	Lube (23530409)..... B105 +
Air Dryer (1391510)..... BA5376 +	Trans..... PT82-HD +	P. Fuel Spin-on (23530641)..... BF7774
Steering (229348)..... P106-HD		S. Fuel Spin-on (23530640)..... BF593
400 w/ MX 11 Euro 6 Eng. (2013-on)	<b>DART</b> Trucks	3-71 Series
Lube (1928868)..... P40008	Models w/Cummins Eng.	Lube Spin-on (23530407)..... B95 +
B-P Lube Centrifugal (1928869)..... BC40009	F-F Lube Bag..... P996	Lube Spin-on (Upgrade) (23530408)..... B95-MPG +
Fuel/Water Separator (1433649)..... BF1383-O	F-F Lube Ele..... P999-HD	P. Fuel Spin-on (23530641)..... BF7774
Radial Seal Air (1854407)..... RS5754	F-F Lube Spin-on..... B196 +	S. Fuel Spin-on (23530640)..... BF593
Cab Air (1825427)..... PA4612 <sup>90</sup>	B-P Lube Ele..... C750-E +	
Air Dryer (1821580)..... BA5284 +	Fuel/Water Separator..... BF1212 +	4-53 Series
Steering (229348)..... P106-HD	4 3/8 In. Fuel Spin-on..... BF948 +	F-F Lube Spin-on (23530407)..... B95 +
Urea (1927474)..... PE17000	5 3/4 In. Fuel Spin-on..... BF957 +	F-F Lube Spin-on (Upgrade) (23530408)..... B95-MPG +
100 w/ MX 13 Euro 6 Eng. (04/13-on)	11 7/32 In. Fuel Spin-on..... BF596 +	P. Fuel Spin-on..... BF592 +
Lube (1629393)..... P40019	Breather Ele. (w/Turbo) (255963) PA643	P. Fuel Spin-on (Upgrade) (23530641)..... BF7774
Centrifugal Lube (1872106)..... BC7326 +	Breather Ele. (w/o Turbo) (256837)..... PA1627	S. Fuel Spin-on (23530640)..... BF593
Fuel/Water Separator (1433649)..... BF1383-O	Turbocharger..... BT112	
Radial Seal O. Air (1854407)..... RS5754	Models w/Sump-Type Hydraulic Steering	4-71 Series
Cab Air (1658991)..... PA4612 <sup>90</sup>	Steering..... PT475	F-F Lube Spin-on (23530407)..... B95 +
Air Dryer (1821580)..... BA5284 +	Models w/Waukesha 140GK, 145GK Eng.	F-F Lube Spin-on (Upgrade) (23530408)..... B95-MPG +
Steering (229348)..... P106-HD	Lube..... P41	P. Fuel Spin-on..... BF592 +
Urea (1927474)..... PE17000	10S Custom	P. Fuel Spin-on (Upgrade) (23530641)..... BF7774
440 w/ MX 11 Euro 6 (2013-on)	Lube..... P42	S. Fuel Spin-on (23530640)..... BF593
Lube (1928868)..... P40008	Fuel..... PF810	
B-P Lube Centrifugal (1928869)..... BC40009	20S, 30SL, 100UG, 185UGS, 200	6-71 Series
Fuel/Water Separator (1433649)..... BF1383-O	Lube..... P42	F-F Lube Spin-on (23530407)..... B95 +
Radial Seal Air (1854407)..... RS5754	Fuel..... PF902	F-F Lube Spin-on (Upgrade) (23530408)..... B95-MPG +
Cab Air (1825427)..... PA4612 <sup>90</sup>		P. Fuel Spin-on (23530706)..... BF5800 +
Air Dryer (1821580)..... BA5284 +	<b>DENNIS EAGLE</b> Trucks	S. Fuel Spin-on (23530707)..... BF5810
Steering (229348)..... P106-HD	ProView w/Cummins ISL 8.9 (8.9L) Eng. (2020)	S. Fuel Spin-on (Upgrade) (23530645)..... BF5815
Urea (1927474)..... PE17000	Lube (5444774)..... B40142	
XF 460 w/MX 13 Euro 6 Eng. (04/13-on)	Fuel (5303743)..... BF63000	6V-53 Series
Lube (1629393)..... P40019	Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	F-F Lube Spin-on (23530407)..... B95 +
Centrifugal Lube (1872106)..... BC7326 +	Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	F-F Lube Spin-on (Upgrade) (23530408)..... B95-MPG +
Fuel/Water Separator (1433649)..... BF1383-O		P. Fuel Spin-on (23530706)..... BF5800 +
Radial Seal O. Air (1854407)..... RS5754		S. Fuel Spin-on (23530707)..... BF5810
Cab Air (1658991)..... PA4612 <sup>90</sup>		S. Fuel Spin-on (Upgrade) (23530645)..... BF5815
Air Dryer (1821580)..... BA5284 +		
Steering (229348)..... P106-HD		6V-71 Series
Urea (1927474)..... PE17000		F-F Lube Spin-on (23530407)..... B95 +
510 w/ MX 13 Euro 6 Eng. (04/13-on)		F-F Lube Spin-on (Upgrade) (23530408)..... B95-MPG +
Lube (1629393)..... P40019		P. Fuel Spin-on (23530706)..... BF5800 +
Centrifugal Lube (1872106)..... BC7326 +		S. Fuel Spin-on (23530707)..... BF5810
Fuel/Water Separator (1433649)..... BF1383-O		S. Fuel Spin-on (Upgrade) (23530645)..... BF5815
Radial Seal O. Air (1854407)..... RS5754		
Cab Air (1658991)..... PA4612 <sup>90</sup>		
Air Dryer (1821580)..... BA5284 +		
Steering (229348)..... P106-HD		
Urea (1927474)..... PE17000		

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.

Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

DETROIT DIESEL Diesel Engines (cont'd)	DETROIT DIESEL Diesel Engines (cont'd)	DETROIT DIESEL Diesel Engines (cont'd)
6V-71 Series (Cont'd) S. Fuel Spin-on (Upgrade) (23530645)..... <b>BF5815</b>	12V-92 Series F-F Lube Spin-on (23530407)..... [2] B95 + Some F-F Lube Spin-on (23530407)..... [4] B95 + F-F Lube Spin-on (Upgrade) (23530408)..... [2] B95-MPG + Some F-F Lube Spin-on (Upgrade) (23530408)..... [4] B95-MPG + P. Fuel Spin-on (23530642)..... <b>BF784</b> S. Fuel Spin-on (23530643)..... <b>BF785</b> S. Fuel Spin-on (Upgrade) (23530644)..... <b>BF7697</b>	DD15 (14.8L) Lube (To Eng. S/N A472910S0690710) (A4731800409)..... <b>P7505</b> Fuel (2 Filter Kit) (A4720900651). <b>PF9908 KIT</b> Fuel (3 Filter Kit) (A0000904251). <b>PF9924 KIT</b> Coolant (A4722030255)..... <b>P5092</b>
6V-92 Series F-F Lube Spin-on (23530407)..... <b>B95 +</b> F-F Lube Spin-on (Upgrade) (23530408)..... <b>B95-MPG +</b> P. Fuel Spin-on (23530706)..... <b>BF5800 +</b> S. Fuel Spin-on (23530707)..... <b>BF5810</b> S. Fuel Spin-on (Upgrade) (23530645)..... <b>BF5815</b>	12V-149 Series F-F Lube Spin-on (23530408)..... [4] B95-MPG + Some F-F Lube Spin-on (23530408)..... [6] B95-MPG + P. Fuel Spin-on (23530642)..... [2] <b>BF784</b> S. Fuel Spin-on (23530644)..... [2] <b>BF7697</b>	DD16 (15.6L) Lube (To Eng. S/N A472910S0690710) (A4731800409)..... <b>P7505</b> Fuel Kit (A0000904251)..... <b>PF9924 KIT</b>
8.2L Lube (23518668)..... [2] <b>B6-HPG +</b> Fuel/Water Separator (12542374)..... <b>BF1266</b> P. Fuel Spin-on (23518527)..... <b>BF592 +</b> S. Fuel Spin-on (23518526)..... <b>BF593</b>	16V-71 Series F-F Lube Spin-on (23530407)..... [2] B95 + F-F Lube Spin-on (Upgrade) (23530408)..... [2] B95-MPG + P. Fuel Spin-on (23530642)..... [2] <b>BF784</b> S. Fuel Spin-on (23530643)..... <b>BF785</b> S. Fuel Spin-on (Upgrade) (23530644)..... <b>BF7697</b>	Series 40 (7.6L, 8.7L) Lube (23529744)..... <b>B7030</b> Fuel (Trucks)..... <b>BF7629 +</b> Fuel (Buses) (1820479-C1)..... <b>BF7531</b>
8V-71 Series F-F Lube Spin-on (23530407)..... <b>B95 +</b> F-F Lube Spin-on (Upgrade) (23530408)..... <b>B95-MPG +</b> B-P Lube Ele. (23519155)..... <b>P52</b> 5 3/4 In. P. Fuel Sock (5574961). <b>F916-C</b> 8 5/16 In. P. Fuel Ele. (5575032). <b>PF845</b> 9 In. P. Fuel Sock (5574980)..... <b>F844-A</b> P. Fuel Spin-on (23530706)..... <b>BF5800 +</b> 7 13/16 In. S. Fuel Ele. (5574508)..... <b>PF902</b> 8 1/4 In. S. Fuel Ele. (6436719)... <b>PF846</b> S. Fuel Spin-on (23530707)..... <b>BF5810</b> S. Fuel Spin-on (Upgrade) (23530645)..... <b>BF5815</b>	16V-92 Series F-F Lube Spin-on (23530407)..... [2] B95 + Some F-F Lube Spin-on (23530407)..... [4] B95 + F-F Lube Spin-on (Upgrade) (23530408)..... [2] B95-MPG + Some F-F Lube Spin-on (Upgrade) (23530408)..... [4] B95-MPG + P. Fuel Spin-on (23530642)..... <b>BF784</b> S. Fuel Spin-on (23530643)..... <b>BF785</b> S. Fuel Spin-on (Upgrade) (23530644)..... <b>BF7697</b>	Series 50 Lube (To 1993) (23530407)..... [2] B95 + Lube (1993-on) (23530573)..... [2] B495 Opt. Fuel/Water Separator (23516189)..... <b>BF5812</b> Fuel/Water Separator (w/Drain) (23535985)..... <b>BF5813 +</b> Fuel/Water Separator (Open End for Bowl) (23535985)..... <b>BF5813-O +</b> P. Fuel Spin-on (To 2004) (23530706)..... <b>BF5800 +</b> S. Fuel Spin-on (23530707)..... <b>BF5810</b>
8V-92 Series F-F Lube Ele. (23518666)..... <b>P20-HD +</b> F-F Lube Spin-on (23530407)..... <b>B95 +</b> F-F Lube Spin-on (Upgrade) (23530408)..... <b>B95-MPG +</b> P. Fuel Ele. (9717391)..... <b>PF845</b> P. Fuel Spin-on (23530706)..... <b>BF5800 +</b> S. Fuel Ele. (23519152)..... <b>PF902</b> S. Fuel Spin-on (23530707)..... <b>BF5810</b> S. Fuel Spin-on (Upgrade) (23530645)..... <b>BF5815</b>	16V-149 Series F-F Lube Spin-on (23530408)..... [4] B95-MPG + Some F-F Lube (23530408)..... [6] B95-MPG + P. Fuel Spin-on (23530642)..... [2] <b>BF784</b> S. Fuel Spin-on (23530644)..... [2] <b>BF7697</b>	Series 55 Lube (5241800310)..... <b>B7135</b> Fuel (23530707)..... <b>BF5810</b>
8V-149 Series F-F Lube Spin-on (23530408)..... [3] B95-MPG + P. Fuel Spin-on (23530642)..... [2] <b>BF784</b> S. Fuel Spin-on (23530643)..... <b>BF785</b> S. Fuel Spin-on (Upgrade) (23530644)..... <b>BF7697</b>	20V-149 Series Lube (23530408)..... [6] B95-MPG +	Series 60 (11.1L, 12.7L, 14.0L) F-F Lube Spin-on (To 1993) (23530407)..... [2] B95 + F-F Lube Spin-on (1993-on) (23530573)..... [2] B495 F-F Lube Spin-on (1993-on (Upgrade)) (Don. DELF3998)..... [2] B495-SS B-P Lube Spin-on (To 1993) (23530413)..... <b>B7577</b> Fuel/Water Separator Ele. (Davco) (23514049)..... <b>PF7680</b> Fuel/Water Separator Ele. (Fuel Pro 382) (23533816)..... <b>PF7748</b> Fuel/Water Separator Spin-on (w/Drain) (23535985)..... <b>BF5813 +</b> Fuel/Water Separator Spin-on (Open End for Bowl) (23535985).. <b>BF5813-O +</b> Opt. Fuel/Water Separator Spin-on (23516189)..... <b>BF5812</b> Opt. Fuel/Water Separator (Alliance ABPN122R50407)..... <b>BF1283-SP +</b> P. Fuel Spin-on (To 2004) (23530706)..... <b>BF5800 +</b> S. Fuel Spin-on (To 12/03) (23530707)..... <b>BF5810</b> S. Fuel Spin-on (12/03-on) (23533726)..... <b>BF5816</b>
12V-71 Series F-F Lube Spin-on (23530407)..... [2] B95 + F-F Lube Spin-on (Upgrade) (23530408)..... [2] B95-MPG + P. Fuel Spin-on (23530642)..... [2] <b>BF784</b> S. Fuel Spin-on (23530643)..... <b>BF785</b> S. Fuel Spin-on (Upgrade) (23530644)..... <b>BF7697</b>	DD5 (5.1L) Lube (A9341801410)..... <b>P40017</b> Diesel Exhaust Fluid (A0001421089)..... <b>PE17002 KIT</b>	
	DD13 (12.8L) Lube (To Eng. S/N A472910S0690710) (A4731800409)..... <b>P7505</b> Fuel Kit (A0000904251)..... <b>PF9924 KIT</b> Coolant (A4722030255)..... <b>P5092</b>	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

DETROIT DIESEL Diesel Engines (cont'd)	DIAMOND REO Trucks & Buses (cont'd)	DIAMOND REO Trucks & Buses (cont'd)
Series 60 (11.1L, 12.7L, 14.0L) (Cont'd)	378, 400, 401, 402, 403 Series w/Perkins 6.354 Eng.	540, 578 Series w/Reo OA110, OA130, OA142LPG, OA145, OH160LPG, OH170, OH185, OH186, OH200 Eng.
S. Fuel Spin-on (12/03-on) (23530645).....	Lube Ele.....	Lube Ele.....
BF5815	PT12	P82 +
Ext. Life S. Fuel Spin-on.....	378, 400, 401, 402, 403 Series w/Reo OA110, OA130, OA142LPG, OA145 Eng.	590SC Bus
BF7612	Lube Ele.....	Lube (1947-on).....
Coolant (23516489).....	P82 +	P42
BW5200	378, 400, 401, 402, 403 Series w/Reo OH160LPG, OH170, OH185, OH186, OH200 Eng.	600, 601, 602, 603 Series w/Reo OH192, OH195, OV202, OV220, OV225, OV235 Eng.
DDC 500 Series	Lube Ele.....	F-F Lube.....
Lube (23530412).....	P82 +	P82 +
S. Fuel (23530640).....	404SC Bus	B-P Lube.....
[2] B6 +	Lube (1947-on).....	P41 +
BF593	P42	Fuel (712H3).....
<b>DEUTZ</b> Buses	430, 432, 433, 436, 440, 442, 470, 475 Series w/Perkins 6.354 Eng.	PF945
120L80, 120R80	Lube Ele.....	603D Series w/GMC 6-71 Diesel Eng.
Air (2165049EZ0199-22).....	P82 +	F-F Lube Ele.....
PA2405	404SC Bus	P20-HD +
<b>DIAMOND POWER SYSTEMS</b> Auxiliary Power Units (APU)	Lube (1947-on).....	P52
DPS6500 w/JD 2 Cyl. Diesel Eng.	P42	P. Fuel Sock.....
Air (DPS6500-O-05-XD).....	430, 432, 433, 436, 440, 442, 470, 475 Series w/Reo OA110, OA130, OA142LPG, OA145 Eng.	F916-C
RS3715	Lube Ele.....	PF902
<b>DIAMOND REO</b> Trucks & Buses	430, 432, 433, 436, 440, 442, 470, 475 Series w/Reo OA110, OA130, OA142LPG, OA145 Eng.	607, 620, 623, 630, 632, 633 Series w/Reo OH192, OV195, OV202, OV220, OV225, OV23 Eng.
130, 145	Lube Ele.....	F-F Lube.....
Lube Ele.....	P82 +	P82 +
170, 186, 200, 201, 202, 203 Series w/Perkins 6.354 Eng.	430, 432, 433, 436, 440, 442, 470, 475 Series w/Reo OH160LPG, OH170, OH185, OH186, OH200 Eng.	B-P Lube.....
Lube Ele.....	Lube Ele.....	P41 +
PT12	P82 +	Fuel (712H3).....
170, 186, 200, 201, 202, 203 Series w/Reo OA110, OA130, OA142LPG, OA145 Eng.	478 Series w/Reo OA110, OA130, OA142LPG, OA145, OH160LPG, OH170, OH185, OH186, OH200 Eng.	PF945
Lube Ele.....	Lube Ele.....	632D, 633D Series w/GMC 6-71 Diesel Eng.
P82 +	P82 +	F-F Lube Ele.....
170, 186, 200, 201, 202, 203 Series w/Reo OH160LPG, OH170, OH185, OH186, OH200 Eng.	478 Series w/Reo OH192, OV195, OV202, OV220, OV225, OV235 Eng.	P20-HD +
Lube Ele.....	F-F Lube.....	P52
P82 +	P82 +	B-P Lube Ele.....
270, 300, 301, 302, 303 Series w/Perkins 6.354 Eng.	B-P Lube.....	F916-C
Lube Ele.....	P41 +	PF902
PT12	Fuel (712H3).....	634, 634C Series w/DT170 Eng.
270, 300, 301, 302, 303 Series w/Reo OA110, OA130, OA142LPG, OA145 Eng.	PF945	Lube.....
Lube Ele.....	500, 501, 502, 503 Series w/Perkins 6.354 Eng.	P82 +
P82 +	Lube Ele.....	PA602
270, 300, 301, 302, 303 Series w/Reo OH160LPG, OH170, OH185, OH186, OH200 Eng.	PT12	636, 678, 700 Series w/Reo OH192, OV195, OV202, OV220, OV225, OV235 Eng.
Lube Ele.....	500, 501, 502, 503 Series w/Reo OA110, OA130, OA142LPG, OA145 Eng.	F-F Lube.....
P82 +	Lube Ele.....	P82 +
322 w/IHC Eng.	500, 501, 502, 503 Series w/Reo OH160LPG, OH170, OH185, OH186, OH200 Eng.	B-P Lube.....
B-P Lube Sock (1956-on).....	Lube Ele.....	P41 +
CU406 <sup>90</sup>	P82 +	Fuel (712H3).....
330, 332, 333, 370, 375 Series w/Perkins 6.354 Eng.	510, 530, 532, 536 Series w/Perkins 6.354 Eng.	PF945
Lube Ele.....	Lube Ele.....	700D, 702D, 703D Series w/GMC 6-71 Eng.
PT12	PT12	F-F Lube Ele.....
330, 332, 333, 370, 375 Series w/Reo OA110, OA130, OA142LPG, OA145 Eng.	510, 530, 532, 536 Series w/Reo OA110, OA130, OA142LPG, OA145 Eng.	P20-HD +
Lube Ele.....	Lube Ele.....	P52
P82 +	P82 +	P. Fuel Sock.....
330, 332, 333, 370, 375 Series w/Reo OH160LPG, OH170, OH185, OH186, OH200 Eng.	540, 570 Series w/Perkins 6.354 Eng.	F916-C
Lube Ele.....	Lube Ele.....	PF902
P82 +	PT12	701, 702, 703, 720, 723 Series w/Reo OH192, OV195, OV202, OV220, OV225, OV235 Eng.
723C Tilt Cab w/Cummins Eng.	510, 530, 532, 536 Series w/Reo OH160LPG, OH170, OH185, OH186, OH200 Eng.	F-F Lube.....
F-F Lube Bag.....	Lube Ele.....	P82 +
P996	P82 +	B-P Lube.....
F-F Lube Ele.....	510, 530, 532, 536 Series w/Reo OH160LPG, OH170, OH185, OH186, OH200 Eng.	P41 +
P999-HD	Lube Ele.....	Fuel (712H3).....
F-F Lube Spin-on.....	P82 +	PF945
B196 +	540, 570 Series w/Perkins 6.354 Eng.	723C Tilt Cab w/Cummins Eng.
B-P Lube Ele.....	Lube Ele.....	F-F Lube Bag.....
C750-E +	PT12	P996
Fuel/Water Separator.....	540, 570 Series w/Perkins 6.354 Eng.	F-F Lube Ele.....
BF1212 +	Lube Ele.....	P999-HD
4 3/8 In. Fuel Spin-on.....	PT12	F-F Lube Spin-on.....
BF948 +	540, 570 Series w/Perkins 6.354 Eng.	B196 +
5 3/4 In. Fuel Spin-on.....	Lube Ele.....	B-P Lube Ele.....
BF957 +	PT12	C750-E +
11 7/32 In. Fuel Spin-on.....	540, 570 Series w/Perkins 6.354 Eng.	Fuel/Water Separator.....
BF596 +	Lube Ele.....	BF1212 +
Air (Purolator Hsg.).....	PT12	4 3/8 In. Fuel Spin-on.....
PA617 +	540, 570 Series w/Perkins 6.354 Eng.	BF948 +
Heavy Duty Air (Fram Hsg.).....	Lube Ele.....	5 3/4 In. Fuel Spin-on.....
PA1700 <sup>90</sup>	PT12	BF957 +
	540, 570 Series w/Perkins 6.354 Eng.	11 7/32 In. Fuel Spin-on.....
	Lube Ele.....	BF596 +
	PT12	Air (Purolator Hsg.).....
	540, 570 Series w/Perkins 6.354 Eng.	PA617 +
	Lube Ele.....	Heavy Duty Air (Fram Hsg.).....
	PT12	PA1700 <sup>90</sup>

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.


Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

DIAMOND REO Trucks & Buses (cont'd)	DIAMOND REO Trucks & Buses (cont'd)	DIAMOND REO Trucks & Buses (cont'd)
723C Tilt Cab w/Cummins Eng. (Cont'd) Breather Ele. (w/Turbo) (255963) <b>PA643</b> Breather Ele. (w/o Turbo) (256837) <b>PA1627</b> Turbocharger <b>BT112</b> *	1000 Series w/GMC 6V-53N Diesel Eng. F-F Lube Ele. <b>P20-HD</b> + B-P Lube <b>P52</b> P. Fuel Sock <b>F916-C</b> S. Fuel Ele. <b>PF906</b>	F206, F216, F226 Series w/Reo OA225, OA292, OA331 Eng. Lube (1391A6) <b>P52</b> Lube (1495A6) <b>P53</b>
730D, 732D, 733D, 830D Series w/GMC 6-71 Diesel Eng. F-F Lube Ele. <b>P20-HD</b> + B-P Lube Ele. <b>P52</b> P. Fuel Sock <b>F916-C</b> S. Fuel Ele. <b>PF902</b>	A375 Series w/Reo OA255, OA292, OA331 Eng. Lube (1391A6) <b>P52</b> Lube (1495A6) <b>P53</b>	F236 w/Continental 6427 Eng. Lube <b>P52</b>
732, 733, 800, 830 Series w/Reo OH192, OV195, OV202, OV220, OV225, OV235 Eng. F-F Lube <b>P82</b> + B-P Lube <b>P41</b> + Fuel (712H3) <b>PF945</b>	A475 Series w/Reo OA225, OA292, OA331 Eng. Lube (1391A6) <b>P52</b> Lube (1495A6) <b>P53</b>	F536 Series w/Reo OH160, OH170 Eng. Lube (1495A6) <b>P53</b>
831 Lube Sock <b>V1240-C</b>	AC403 Series w/Reo OA255, OA292, OA331 Eng. Lube (1391A6) <b>P52</b> Lube (1495A6) <b>P53</b>	Gold Comet Series Lube (1950-53) <b>P53</b>
838CG w/207, 235 Eng. F-F Lube <b>P82</b> + B-P Lube <b>P41</b> +	AC503, F506 Series w/Reo OH160, OH170 Eng. Lube (1495A6) <b>P53</b>	P2000D, DF3000, P3000D, DF4000, P4000D, DF5000 w/Perkins 6.354D Eng. Lube <b>PT12</b> Can-Type Fuel <b>BF825</b> +
921 w/GMC 6-71 Diesel Eng. F-F Lube Ele. (1963-on) <b>P20-HD</b> + P. Fuel Sock (1963-on) <b>F916-C</b> S. Fuel Ele. (1963-on) <b>PF902</b>	Apollo 101 Series w/Cat 1160 Eng. Lube <b>[2] BT364</b> Fuel <b>BF583</b>	P4300D, P4400D, P4560D, P5300D, P5400D, P6000D, P7000D w/GMC 6V-53N Diesel Eng. F-F Lube Ele. <b>P20-HD</b> + B-P Lube <b>P52</b> P. Fuel Sock <b>F916-C</b> S. Fuel Ele. <b>PF906</b>
921, 921C Tilt Cab w/Cummins Eng. F-F Lube Bag <b>P996</b> F-F Lube Ele. <b>P999-HD</b> F-F Lube Spin-on <b>B196</b> + B-P Lube Ele. <b>C750-E</b> + Fuel/Water Separator <b>BF1212</b> + 4 3/8 In. Fuel Spin-on <b>BF948</b> + 5 3/4 In. Fuel Spin-on <b>BF957</b> + 11 7/32 In. Fuel Spin-on <b>BF596</b> + Air (Purrolator Hsg.) <b>PA618</b> Heavy Duty Air (Fram Hsg.) <b>PA1701</b> + Breather Ele. (w/Turbo) (255963) <b>PA643</b> Breather Ele. (w/o Turbo) (256837) <b>PA1627</b> Turbocharger <b>BT112</b> +	C120 w/Cat 3406 (14.6L) Eng. Lube <b>B99</b> + P. Fuel Ele. <b>[2] PF935</b> Fuel Spin-on <b>BF614</b> +	P6300D, P7000D, P7300D w/GMC 6-71N Eng. F-F Lube Ele. <b>P20-HD</b> + B-P Lube Ele. <b>P52</b> P. Fuel Sock <b>F916-C</b> S. Fuel Ele. (5574508) <b>PF902</b> S. Fuel Ele. (6436719) <b>PF846</b>
921B w/GMC 6-71 Diesel Eng. F-F Lube Ele. (1963-on) <b>P20-HD</b> + B-P Lube Ele. (1963-on) <b>C750-E</b> + P. Fuel Sock (1963-on) <b>F916-C</b> S. Fuel Ele. (1963-on) <b>PF902</b> Air (1963-on) <b>PA618</b>	CF60 Rogue w/Cat 3208 Eng. Lube <b>[2] BT364</b> Fuel Spin-on <b>BF970</b> +	UV42 w/Cummins L10 Eng. F-F Lube <b>B196</b> + B-P Lube <b>B7577</b> Dual-Flow Lube <b>BD103</b> + Opt. Fuel/Water Separator <b>BF1212</b> + Fuel Spin-on <b>BF957-D</b> +
931C w/GMC Diesel Eng. F-F Lube Ele. (1963-on) <b>P20-HD</b> + B-P Lube (1963-on) <b>C750-E</b> + P. Fuel Sock (1963-on) <b>F916-C</b> S. Fuel Ele. (1963-on) <b>PF902</b>	CF60 Rogue w/Cat 3306 Eng. Lube (Standard Vers.) <b>B76</b> Fuel Spin-on <b>BF970</b> +	<b>DIETZ</b> <b>Compressors</b>
1000 Series w/Cat 1673 Eng. Lube <b>PT88-HD</b> Fuel <b>PF824</b> +	CF60 Rogue w/Cat 3406 Eng. Lube <b>B99</b> + Fuel Spin-on <b>BF614</b> +	Van Refrigerator Units Lube <b>P15</b>
	D6000, D6300, D7000, D7300 w/207, 235 Eng. F-F Lube <b>P82</b> B-P Lube <b>P41</b> +	<b>DIVCO</b> <b>Trucks</b>
	F14 Series w/IHC SD240 Eng. B-P Lube Sock <b>CU406</b> <sup>90</sup>	Models w/Continental Eng. Lube (1960-on) <b>P41</b> Fuel (To 1961) <b>BF840</b> +
	F20, F21, F22 Series w/Reo OA225, OA292, OA331 Eng. Lube (1391A6) <b>P52</b> Lube (1495A6) <b>P53</b>	Models w/Ford 240, 262, 300 Eng. Lube (1964-on) <b>B2</b> +
	F23 Series w/Continental 6427 Eng. Lube <b>P52</b>	Models w/Fram FA121PL Series Filter Hsgs. Air (1955-60) (6407) <b>PA652</b>
	F50, F53 Series w/Reo OH160, OH170 Eng. Lube (1495A6) <b>P53</b>	Models w/F4-162 Eng., 6298H 6 Cyl. OHV Eng., Hercules QXLD-3, 2QXLD-3 Eng. Lube (1965-on) (5600) <b>P41</b>
	F120, F122 Series w/Reo OA225, OA292 Eng. Lube (1391A6) <b>P52</b> Lube (1495A6) <b>P53</b>	Models w/FD6-266A Eng. Lube (1960-68) <b>P41</b>
		Models w/GF193 Eng. Lube (1960-68) <b>P41</b>

\* See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



<b>DIVCO</b> Trucks (cont'd)	<b>DODGE</b> Gas Engines (cont'd)	<b>DODGE</b> Gas Engines (cont'd)
Models w/Hercules QXLD3, G298, GO298H Engs.	225, 225-1, 225-2 6 Cyl. (Cont'd)	354 V8
F-F Lube..... P82	Air (1967-77) (2206376)..... PA650	Lube (1959)..... P82
B-P Lube (Fram F4 Hsg.)..... P41	Air (1977-on) (1739547)..... PA615	360 V8 (5.9 L)
B-P Lube (Military Jr. Hsg.)..... P53	Air (1977-on) (4041252)..... PA1735	Lube Ele. (2129023)..... P84-2
Models w/Purolator AF701 Air Filter Hsg.	Air (1979-on) (2453346)..... PA642	4 3/8 In. Lube Spin-on..... B233
Air (1959-60)..... PA669	230 6 Cyl.	5 9/32 In. Lube Spin-on
Dividend Series w/OHV Eng.	B-P Lube Sock (1955-61)..... JC405	(1971-on)..... B2+
Air (1955-on)..... PA634	Opt. Lube Ele. (1821552)..... P81	In-Line Fuel (1982-88)..... BF865
40B, 40C, 50C, 50D, 70B w/Continental FO6226 Eng.	Opt. Lube Ele. (1821552)..... P73	In-Line Fuel (1971-81, (Std.))..... BF840+
Lube..... P41	Bowl-Type Fuel (1138687)..... PF859	In-Line Fuel (1975-81, (Calif.))..... BF865
Air (1963-66)..... PA634	Fuel Ele. (2240546)..... PF827	Air (1972-79) (3614353)..... PA2052
40D, 40E, 50, 50F w/Ford 240, 262, 300 Eng.	In-Line Fuel (2525254)..... BF840+	Air (1979-on) (1739547)..... PA615
Lube..... B2+	238 V6	Air (1979-80) (2863349)..... PA2010
3 15/32 In. Fuel Ele. (1964-66)..... PF827	Lube..... BT223	361, 361-2, 361-3, 361-4 V8
40D, 40E, 50E, 50F, 70C, 70D, 200 w/Hercules G298H Eng.	251, 251-1, 251-2, 251-3 6 Cyl.	F-F Lube Ele. (2129109)..... P82
Lube (1959-on)..... P41	Lube Ele. (1610435)..... P60	B-P Lube Ele. (2128752)..... P41
Air (1962)..... PA634	Lube Ele. (1821552)..... P73	Fuel Ele. (2128752)..... PF827
200C w/Hercules G298 Eng.	Lube Ele. (1821552)..... P81	Air (2120933)..... PA671
Lube (1959-on)..... P41	Opt. Lube Ele. (1961-Early 1965) (2129023)..... P84-2	383 V8
Air (1963)..... PA634	Lube Spin-on (1961-69)..... B2+	4 3/8 In. Lube Spin-on..... B233
	1 7/8 In. Fuel Ele. (1957-60)..... PF859	5 9/32 In. Lube Spin-on..... B2+
	In-Line Fuel (1961-69) (2525254) BF840+	In-Line Fuel..... BF840+
	Fuel Ele. (1969) (2240546)..... PF827	Air (1966-69)..... PA693
	265 6 Cyl.	Air (1970-72)..... PA2010
	B-P Lube Sock (1955-61)..... JC405	400 V8
	Eng. Mtd. Lube Ele. (1821552).... P81	4 3/8 In. Lube Spin-on..... B233
	Remote Mtd. Lube Ele. (1821552)..... P73	5 9/32 In. Lube Spin-on
	Fuel Ele. (1955-61)..... PF859	(1972-on)..... B2+
	270 V8	In-Line Fuel (1972-78, (Std.))..... BF840+
	B-P Lube Sock (1946-56)..... JC405	In-Line Fuel (1975-78, (Calif.))..... BF865
	273A V8	Air (1972-on) (2863349)..... PA2010
	Opt. Lube Ele. (2129023)..... P84-2	Air (2402677)..... PA693
	Lube Spin-on (1964-69)..... B2+	Air (3614353)..... PA2052
	Fuel Ele. (1964-69)..... PF827	413 V8 (6.8L)
	In-Line Fuel Ele..... BF840+	F-F Lube Ele. (2129109)..... P82
	Air (1964-68)..... PA615	B-P Lube Ele. (2128752)..... P41
	314 V8	Lube Spin-on (1960-on)..... B2+
	B-P Lube Sock (1957-60)..... JC405	Fuel Ele. (1960-67)..... PF827
	Lube Ele. (1821552)..... P81	In-Line Fuel (1975-on, (Calif.))..... BF865
	318 V8	In-Line Fuel (Std.)..... BF840+
	B-P Lube Sock (1959)..... JC405	Air (1960-67)..... PA671-1
	Eng. Mtd. Lube Ele. (1821552).... P81	Air (1971-77)..... PA2010
	Remote Mtd. Lube Ele. (1821552)..... P73	Air (1978 (2 Bbl.)) (1739547)..... PA615
	Opt. 1 Qt. Lube Ele..... P84-2	Air (1978 (4 Bbl.)) (3614353)..... PA2052
	Opt. 2 Qt. Lube Ele. (1965-70).... P82	Air (1979-on)..... PA2010
	4 3/8 In. Lube Spin-on (1960-on) B233	440 V8 (7.2)
	5 9/32 In. Lube Spin-on..... B2+	Lube Spin-on (1973-on)..... B2+
	Fuel Ele. (1959-71)..... PF827	In-Line Fuel (1974-on, (Std.))..... BF840+
	In-Line Fuel (1968-81, (Std.))..... BF840+	In-Line Fuel (1975-on, (Calif.))..... BF865
	In-Line Fuel (1975-81, (Calif.))..... BF865	Fuel Ele..... PF827
	In-Line Fuel (1982-on)..... BF865	Air (2402677)..... PA693
	Air (1961-67) (2203311)..... PA607	Air (2863349)..... PA2010
	Air (1964-on) (1739547)..... PA615	Air (3614353)..... PA2052
	Air (1974-on) (3614353)..... PA2052	
		<b>DODGE</b> Trucks
		150, 250, 350 Series w/Cummins 6BT5.9 Eng.
		Lube (To 1998)..... BT339+
		Lube (1998-on)..... BT7349

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

**Trucks & Buses Applications** **BALDWIN FILTERS**

<b>DODGE Trucks (cont'd)</b>	<b>DODGE Trucks (cont'd)</b>	<b>DODGE Trucks (cont'd)</b>
150, 250, 350 Series w/Cummins 6BT5.9 Eng. (Cont'd) Air..... <b>PA2183</b>	400, 500, S550, 600 Series w/V8-318A Eng. (Cont'd) Air (1967-68) (2203311)..... <b>PA607</b> Air (1974) (1739547)..... <b>PA615</b> Air (1974-on) (3614353)..... <b>PA2052</b> Air (1978-on) (1739547)..... <b>PA615</b>	700, 800, C850, 900, 1000 Series w/V8-400 Eng. 4 3/8 In. Lube Spin-on..... <b>B233</b> 5 9/32 In. Lube Spin-on..... <b>B2+</b> In-Line Fuel..... <b>BF840+</b>
400, 500, S550, 600 Series w/6-170 Eng. Lube Spin-on..... <b>B2+</b> In-Line Fuel..... <b>BF840+</b> Air (1961, (D Series)) (2203311).. <b>PA607</b>	400, 500, S550, 600 Series w/V8-354 Eng. <b>F-F Lube Ele.</b> (2129109)..... <b>P82</b>	C800, CN800, CNT800, CT800 w/Cat 1100 Series Engs. Lube..... <b>[2] BT364</b> Fuel..... <b>BF583</b>
400, 500, S550, 600 Series w/6-198 Eng. Lube Spin-on..... <b>B2+</b> Fuel Ele..... <b>PF827</b> In-Line Fuel..... <b>BF840+</b> Air (2206376)..... <b>PA650</b>	400, 500, S550, 600 Series w/V8-360 Eng. 4 3/8 In. Lube Spin-on..... <b>B233</b> 5 9/32 In. Lube Spin-on..... <b>B2+</b> In-Line Fuel..... <b>BF840+</b> Air (3614353)..... <b>PA2052</b>	C800, CN900, CNT900 w/Cummins V8-210 Eng. F-F Lube..... <b>P998</b> B-P Lube..... <b>C704-L+</b> Fuel Spin-on..... <b>BF957+</b> Air (106837)..... <b>PA616</b> Tube-Type Air (Farr P24-38)..... <b>[2] PA1780</b> Breather..... <b>PA643</b> Coolant (Pre-Charge) (Add CS5008)..... <b>BW5071</b>
400, 500, S550, 600 Series w/6-225 Eng. Lube Ele. (2129023)..... <b>P84-2</b> 4 3/8 In. Lube Spin-on (3549957)..... <b>B233</b> 5 9/32 In. Lube Spin-on (1851658)..... <b>B2+</b> Bowl-Type Fuel (1138687)..... <b>PF859</b> Fuel Ele. (2240546)..... <b>PF827</b> In-Line Fuel (2525254)..... <b>BF840+</b> Axial Seal Air (1967-77) (2206376)..... <b>PA650</b> Axial Seal Air (2 Bbl.) 1977-on (1739547)..... <b>PA615</b> Air (2 Bbl.) 1977-on, (Vans) (4041252)..... <b>PA1735</b> Air (2203311)..... <b>PA607</b>	400, 500, S550, 600 Series w/V8-361 Eng. F-F Lube (2129109)..... <b>P82</b> B-P Lube (2128752)..... <b>P41</b> Fuel Ele..... <b>PF827</b> Air (1960-67 (361-3, 361-4)) (2120933)..... <b>PA671</b>	CN900, CNT900 w/Cummins NHC250 Eng. F-F Lube Ele..... <b>P999-HD</b>
400, 500, S550, 600 Series w/6-251 Eng. Std. Lube Ele. (1961-65) (2129023)..... <b>P84-2</b> Opt. Lube Ele. (1610435)..... <b>P60</b> Opt. Lube Ele. (1821552)..... <b>P81</b> Lube Spin-on (1961-69)..... <b>B2+</b> Bowl-Type Fuel (1138687)..... <b>PF859</b> Fuel Ele. (2240546)..... <b>PF827</b> In-Line Fuel (2525254)..... <b>BF840+</b>	400, 500, S550, 600 Series w/V8-400 Eng. 4 3/8 In. Lube Spin-on..... <b>B233</b> 5 9/32 In. Lube Spin-on..... <b>B2+</b> In-Line Fuel..... <b>BF840+</b>	CN900, CNT900 w/GMC 6-71N Eng. F-F Lube..... <b>P20-HD+</b> B-P Lube..... <b>P52</b> P. Fuel Sock..... <b>F916-C</b> S. Fuel Ele..... <b>PF902</b> P. Fuel Spin-on..... <b>BF5800+</b> S. Fuel Spin-on..... <b>BF5810</b> Tube-Type Air (Farr P24-38)..... <b>[2] PA1780</b> Tube-Type Air (Farr P32)..... <b>PA1781</b> Tube-Type Air (Farr P48)..... <b>PA1783</b>
400, 500, S550, 600 Series w/6-265 Eng. Shunt-Type Lube Ele. (1821552) <b>P81</b> Bowl-Type Fuel (1138687)..... <b>PF859</b>	700, 800, C850, 900, 1000 Series w/V8-273A Eng. Lube Ele. (2129023)..... <b>P84-2</b> Lube Spin-on (1851658)..... <b>B2+</b> Fuel Ele..... <b>PF827</b> In-Line Fuel..... <b>BF840+</b>	CNT800 w/Cummins VT225 Eng. F-F Lube..... <b>B205+</b> B-P Lube..... <b>B7577</b> Fuel..... <b>BF957+</b> Coolant..... <b>BW5071</b>
400, 500, S550, 600 Series w/V8-273A Eng. Lube Ele. (2129023)..... <b>P84-2</b> Lube Spin-on (1851658)..... <b>B2+</b> Fuel Ele. (2240546)..... <b>PF827</b> In-Line Fuel (2525254)..... <b>BF840+</b> Air (1964-68) (1739547)..... <b>PA615</b>	700, 800, C850, 900, 1000 Series w/V8-314 Eng. Shunt-Type Lube Ele. (1821552) <b>P81</b> B-P Lube Sock (676575)..... <b>JC405</b>	CNT900 w/Detroit 8V-71 Eng. F-F Lube (23530407)..... <b>B95+</b> B-P Lube..... <b>P52</b> 5 3/4 In. P. Fuel Sock (5574961). <b>F916-C</b> 8 5/16 In. P. Fuel Ele. (5575032). <b>PF845</b> 9 In. P. Fuel Sock (5574980)..... <b>F844-A</b> P. Fuel Spin-on (23530706)..... <b>BF5800+</b> 7 13/16 In. S. Fuel Ele. (5574508)..... <b>PF902</b> 8 1/4 In. S. Fuel Ele. (6436719)... <b>PF846</b> S. Fuel Spin-on (23530707)..... <b>BF5810</b> S. Fuel (Upgrade) (23530645)..... <b>BF5815</b>
400, 500, S550, 600 Series w/V8-314 Eng. Shunt-Type Lube Ele. (1821552) <b>P81</b> B-P Lube Sock (676575)..... <b>JC405</b>	700, 800, C850, 900, 1000 Series w/V8-354 Eng. F-F Lube Ele. (2129109)..... <b>P82</b>	CT900, C1000 w/V8-478, 549 Engs. Lube..... <b>P204</b> Bowl-Type Fuel (IHC 967640-R21)..... <b>PF859</b>
400, 500, S550, 600 Series w/V8-318A Eng. Shunt-Type Lube Ele. (1821552) <b>P81</b> Opt. F-F Lube Ele. (2129023)..... <b>P84-2</b> B-P Lube Sock (676575)..... <b>JC405</b> 4 3/8 In. Lube Spin-on..... <b>B233</b> 5 9/32 In. Lube Spin-on..... <b>B2+</b> Fuel Ele..... <b>PF827</b> In-Line Fuel..... <b>BF840+</b>	700, 800, C850, 900, 1000 Series w/V8-360 Eng. 4 3/8 In. Lube Spin-on..... <b>B233</b> 5 9/32 In. Lube Spin-on..... <b>B2+</b> In-Line Fuel..... <b>BF840+</b>	D400 w/V8-360 (5.9L) Eng. Lube..... <b>B233</b> In-Line Fuel (Exc. HiPerf. or Calif.)..... <b>BF840+</b> In-Line Fuel (Calif.)..... <b>BF865</b>
400, 500, S550, 600 Series w/V8-318A Eng. Shunt-Type Lube Ele. (1821552) <b>P81</b> Opt. F-F Lube Ele. (2129023)..... <b>P84-2</b> B-P Lube Sock (676575)..... <b>JC405</b> 4 3/8 In. Lube Spin-on..... <b>B233</b> 5 9/32 In. Lube Spin-on..... <b>B2+</b> Fuel Ele..... <b>PF827</b> In-Line Fuel..... <b>BF840+</b>	700, 800, C850, 900, 1000 Series w/V8-361 Eng. F-F Lube (2129109)..... <b>P82</b> B-P Lube (2128752)..... <b>P41</b> Fuel Ele..... <b>PF827</b> Air (2120933)..... <b>PA671</b>	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).


DODGE Trucks (cont'd)	DODGE Trucks (cont'd)	DUPLEX Trucks
D400 w/V8-360 (5.9L) Eng. (Cont'd)	M Series Motorhomes w/V8-318, V8-413, V8-440 Engs.	Models w/Continental HRG6, R6602 Engs.
Air (2 3/4 In.)..... PA615	Lube (1969-on)..... B2 +	Lube..... P52
Air (3 1/2 In.)..... PA2052	In-Line Fuel (Std.)..... BF840 +	GR6x4 w/Continental B6427 Eng.
Crankcase Breather..... SA4141	In-Line Fuel (Calif.) (4041540)..... BF865-K	Lube (1952-on)..... P52
Trans..... 18032	Fuel Ele..... PF827	GR6x4 w/GMC 4-71 Eng.
D400 w/V8-440 (7.2L) Eng.	Air (318) 1969-on..... PA615	Lube (1955-on)..... P52
Lube..... B233	Air (413, 440) 1969-on..... PA2010	P. Fuel Sock..... F916-C
In-Line Fuel (Exc. Calif.)..... BF840 +	M300, M400, MB400 w/Chrysler 5.9L Eng.	S. Fuel Ele..... PF916
Fuel (Opt. 3 15/32 In. Ele.)..... PF827	Lube Ele. (2129023)..... P84-2	GR6x4 w/IHC RD401 Eng.
Air..... PA2052	Lube Spin-on (1971-on)..... B2 +	B-P Lube Sock (1957-on)..... CU406 <sup>90</sup>
Crankcase Breather..... SA4141	Fuel (1971-81)..... BF840 +	HR6x4 w/Hercules RXLD Eng.
Trans..... 18032	Air (1972-79) (3614353)..... PA2052	Lube (1953-on)..... P52
D450 w/V8-360 (5.9L) Eng.	PC500, PD500, L600, PC600, PD600 w/Perkins 6.354 Diesel Eng.	HR6x6 w/Waukesha 148DKB Eng.
Lube..... B233	Lube (1963-on)..... PT12	Lube (1956-on)..... P52
In-Line Fuel (Exc. HiPerf. or Calif.)..... BF840 +	Fuel Ele. (1960-62)..... PF838	K501 w/IHC RD501 Eng.
In-Line Fuel (Calif.)..... BF865	Can-Type Fuel (1963-on)..... BF825 +	B-P Lube Sock (1955-on)..... CU406 <sup>90</sup>
Air (2 3/4 In.)..... PA615	Ram 4500 w/L6-408 (6.7L) Turbo Diesel Eng. (2008-09)	SH501, JH558
Air (3 1/2 In.)..... PA2052	Lube (5083285AA)..... BT7349	B-P Lube Sock (1946-58)..... CU406 <sup>90</sup>
Crankcase Breather..... SA4141	Fuel/Water Separator (Upgraded Hsg. w/Ele.) (5183410AA)..... BF1392-SPS KIT	WC244 w/Continental F6244 Eng.
Trans..... 18032	Fuel/Water Separator (Ele. for Upgraded Hsg.) (68061634AA)..... PF1392	Lube (1954-on)..... P40
D450 w/V8-440 (7.2L) Eng.	Air (53034051AB)..... PA4318	<b>E-Z ON POWER SYSTEMS</b>
Lube..... B233	Crankcase Breather (68002433AB)..... CV15010	<b>Auxiliary Power Units (APU)</b>
In-Line Fuel..... BF840 +	Trans. (6 Spd.) (68019688AA)..... 20025	Model I w/Cat 3011C Eng.
Fuel (Opt. 3 15/32 In. Ele.)..... PF827	Ram 4500 w/L6-408 (6.7L) Turbo Diesel Eng. (2010)	Lube (220-1523)..... B1405
Air..... PA2052	Lube (5083285AA)..... BT7349	Fuel (67-6987)..... BF825 +
Crankcase Breather..... SA4141	Fuel Ele. (68065608AA)..... PF9870	Model II w/Cat C.5 Eng.
Trans..... 18032	Air (53034051AB)..... PA4318	Lube (266-7143)..... B33
D800 w/Chrysler V8 413 6.8L Eng.	Crankcase Breather (68002433AB)..... CV15010	Model III w/Cat C.5 Eng.
F-F Lube Ele. (2129109)..... P82	Trans. (68019688AA)..... 20025	Lube (266-7143)..... B33
B-P Lube Ele. (2128752)..... P41	Ram 5500 w/L6-408 (6.7L) Turbo Diesel Eng. (2008-09)	<b>EAGLE TRANSIT</b>
Lube Spin-on..... B2 +	Lube (5083285AA)..... BT7349	<b>Bus</b>
Fuel In-Line..... BF840 +	Fuel Ele. (68065608AA)..... PF9870	Eagle 10 w/Detroit 6V-92 Eng.
Air (1971-77)..... PA2010	Air (53034051AB)..... PA4318	F-F Lube (23530407)..... B95 +
LS1000, LT1000 w/GMC 6-71N Eng.	Crankcase Breather (68002433AB)..... CV15010	F-F Lube (Upgrade) (23530408)..... B95-MPG +
F-F Lube..... P20-HD +	Trans. (68019688AA)..... 20025	P. Fuel (23530706)..... BF5800 +
B-P Lube..... P52	Ram 5500 w/L6-408 (6.7L) Turbo Diesel Eng. (2010)	S. Fuel (23530707)..... BF5810
P. Fuel Sock..... F916-C	Lube (5083285AA)..... BT7349	S. Fuel (Upgrade) (23530645)..... BF5815
S. Fuel Ele..... PF902	Fuel/Water Separator (Upgraded Hsg. w/Ele.) (5183410AA)..... BF1392-SPS KIT	<b>ECOWIND</b>
P. Fuel Spin-on..... BF5800 +	Fuel/Water Separator (Ele. for Upgraded Hsg.) (68061634AA)..... PF1392	<b>Auxiliary Power Units (APU)</b>
S. Fuel Spin-on..... BF5810	Air (53034051AB)..... PA4318	UT ECO 702 w/Lombardini LDW 702 Eng.
Tube-Type Air (Farr P24-38)..... [2] PA1780	Crankcase Breather (68002433AB)..... CV15010	Lube..... B7276
Tube-Type Air (Farr P32)..... PA1781	Trans. (68019688AA)..... 20025	Fuel..... BF988 +
Tube-Type Air (Farr P48)..... PA1783	Ram 5500 w/L6-408 (6.7L) Turbo Diesel Eng. (2010)	<b>EL DORADO</b>
LS1000, LT1000 w/GMC 8V-71N Eng.	Lube (5083285AA)..... BT7349	<b>Buses</b>
F-F Lube..... P20-HD +	Fuel Ele. (68065608AA)..... PF9870	30LF Low Flow Transit w/LNG Eng. (1999-2001)
B-P Lube..... P52	Air (53034051AB)..... PA4318	Lube..... [2] B495
P. Fuel Sock (5574961)..... F916-C	Crankcase Breather (68002433AB)..... CV15010	Fuel..... BF5800 +
S. Fuel Ele. (5575032)..... PF845	Trans. (68019688AA)..... 20025	S. Fuel..... BF5810
S. Fuel Ele..... PF902	Ram 5500 w/L6-408 (6.7L) Turbo Diesel Eng. (2010)	Air..... PA2721
P. Fuel Spin-on..... BF5800 +	Lube (5083285AA)..... BT7349	Coolant..... B5134 +
S. Fuel Spin-on..... BF5810	Fuel Ele. (68065608AA)..... PF9870	Axess w/Cummins ISL 8.9 (8.9L) Eng. (2018)
Tube-Type Air (Farr P24-38)..... [2] PA1780	Air (53034051AB)..... PA4318	Lube (Fleetguard LF9009)..... B40142
Tube-Type Air (Farr P32)..... PA1781	Crankcase Breather (68002433AB)..... CV15010	Fuel (FF63009)..... BF63000
Tube-Type Air (Farr P48)..... PA1783	Trans. (68019688AA)..... 20025	

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>EL DORADO Buses (cont'd)</b>	<b>EL DORADO Buses (cont'd)</b>	<b>EMERGENCY ONE, INC. Trucks (cont'd)</b>
Axess w/Cummins ISL-G (8.9L) Eng. (2018) <b>Lube</b> (Fleetguard LF9009)..... <b>B40142</b> <b>Fuel/Water Separator</b> (Fleetguard NG5900)..... <b>BF7695</b>	E-Z Rider II Max w/Cummins L9 (9.0L) Eng. (2018) <b>Lube</b> (3401544)..... <b>B40142</b> <b>Fuel</b> (Fleetguard FF63008)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	Jackal, Jackrabbit w/Ford 6.0L Turbo Diesel Eng. <b>Lube Ele.</b> (w/o Screw on Cap) (FL2016)..... <b>P7235</b> <b>Lube</b> (w/Screw on Cap) (Wix 57312)..... <b>P7436</b>
Axess w/Cummins ISL-G (8.9L) Eng. (2019) <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309</b> <b>Fuel/Water Separator</b> (Fleetguard NG5900)..... <b>BF7695</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b>	E-Z Rider II Max w/Cummins L9 (9.0L) Eng. (2019) <b>Lube</b> (3401544)..... <b>B40142</b> <b>Fuel</b> (5303743)..... <b>BF63000</b>	Lynx CC B123, Super Lynx B125, Super Lynx PR B127 w/Ford 6.0L Turbo Diesel Eng. <b>Lube Ele.</b> (w/o Screw on Cap) (FL2016)..... <b>P7235</b> <b>Lube</b> (w/Screw on Cap) (Wix 57312)..... <b>P7436</b>
Axess w/Cummins L9 (9.0L) Eng. (2019) <b>Lube</b> (3401544)..... <b>B40142</b> <b>Fuel</b> (5303743)..... <b>BF63000</b>	E-Z Rider II Max w/Cummins L9N (8.9L) Eng. (2021) <b>Lube</b> (Fleetguard LF14002NN).... <b>B40142</b> <b>Fuel</b> (Fleetguard NG5900)..... <b>BF7695</b>	Titan 4x4, Titan 6x6 w/Detroit Diesel 8V-92TA Eng. <b>Lube</b> ..... <b>B95+</b> <b>P. Fuel</b> ..... <b>BF5800+</b> <b>S. Fuel</b> ..... <b>BF5810</b>
Axess w/Cummins L9 (9.0L) Eng. (2020) <b>Lube</b> (5444774)..... <b>B40142</b> <b>Fuel</b> (5303743)..... <b>BF63000</b>	Transit w/CNG Eng. (2000) <b>Lube</b> ..... <b>BT339+</b> <b>Fuel Coalescer</b> ..... <b>BF7695</b> <b>Disposable Air Hsg.</b> (Farr 114500002)..... <b>PA3555</b>	Titan HPR 4x4, Titan HPR 6x6 w/Detroit Diesel Series 60 Eng. <b>Lube</b> ..... <b>[2] B495</b> <b>P. Fuel</b> ..... <b>BF5800+</b> <b>S. Fuel</b> ..... <b>BF5810</b>
Axess w/Cummins L9N (8.9L) Eng. (2020) <b>Lube</b> (3401544)..... <b>B40142</b> <b>Fuel</b> (3607140)..... <b>BF7695</b>	Transmark XHF w/Cummins L9N (8.9L) Eng. (2019) <b>Lube</b> (3401544)..... <b>B40142</b>	Titan HPR 8x8 w/Detroit Diesel 12V-2000 Eng. <b>Lube</b> ..... <b>[3] B7180</b> <b>Fuel</b> ..... <b>[2] BF7697</b>
Axess w/Cummins L9N (8.9L) Eng. (2021) <b>Lube</b> (Fleetguard LF14002NN).... <b>B40142</b> <b>Lube</b> (Fleetguard LF14002NN).... <b>B40142</b> <b>Fuel</b> (Fleetguard NG5900)..... <b>BF7695</b>	<b>EMERGENCY ONE, INC. Trucks</b>	<b>ENERGY &amp; ENGINE Auxiliary Power Units (APU)</b>
E-Z Rider II Max w/Cummins B6.7 (6.7L) Eng. (2019) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	AN10, AW12 w/Ford 7.3L Turbo Diesel Eng. <b>Lube</b> ..... <b>B7039</b>	AXP 1000 w/Lombardini 15LD 350 Eng. <b>Lube</b> (Napa 1347)..... <b>B161-S</b> <b>Fuel</b> (John Deere CH15553)..... <b>PF937</b>
E-Z Rider II Max w/Cummins B6.7 (6.7L) Eng. (2020) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	Bronto F100 RLP w/Cummins ISM Eng. <b>Dual-Flow Lube</b> ..... <b>BD7153+</b> <b>Fuel/Water Separator</b> ..... <b>BF1272-SPS</b>	<b>ERF Trucks</b>
E-Z Rider II Max w/Cummins B6.7 (6.7L) Eng. (2021) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	Hurricane, Cyclone II w/Detroit Diesel Series 60 Eng. <b>Lube</b> ..... <b>[2] B495</b> <b>P. Fuel</b> ..... <b>BF5800+</b> <b>S. Fuel</b> ..... <b>BF5810</b> <b>Air</b> (Don. P116918)..... <b>PA2317+</b> <b>Coolant</b> (Don. P554071)..... <b>BW5137</b>	EC Series 6.21 w/Perkins Phaser 210Ti Eng. (08/93-on) <b>Lube</b> (AHM2007)..... <b>BT237</b> <b>Fuel</b> (P26561117)..... <b>BF825+</b>
E-Z Rider II Max w/Cummins ISB (5.9L) Eng. (2018) <b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b>	Emergency One w/Cummins ISL 8.9 (8.9L) Eng. (2018) <b>Lube</b> (Fleetguard LF9009)..... <b>B40142</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b>	ECM 6.22 w/Cummins 5.9 Eng. (04/00-on) <b>F-F Lube</b> (3903264)..... <b>BT339+</b> <b>Fuel/Water Separator</b> (C3903202)..... <b>BF1226</b> <b>Air Dryer</b> (1368731)..... <b>BA5374+</b> <b>Steering</b> ..... <b>P106-HD</b>
E-Z Rider II Max w/Cummins ISL 8.9 (8.9L) Eng. (2018) <b>Lube</b> (Fleetguard LF9009)..... <b>B40142</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b>	Emergency One w/Cummins ISL 8.9 (8.9L) Eng. (2019) <b>Lube</b> (3401544)..... <b>B40142</b> <b>Fuel</b> (5303743)..... <b>BF63000</b>	ECM Series 7.22 w/Cummins 5.9 Eng. (04/00-on) <b>F-F Lube</b> (3903264)..... <b>BT339+</b> <b>Fuel/Water Separator</b> (C3903202)..... <b>BF1226</b> <b>Air Dryer</b> (1368731)..... <b>BA5374+</b> <b>Steering</b> ..... <b>P106-HD</b>
E-Z Rider II Max w/Cummins ISL 8.9 (8.9L) Eng. (2018) <b>Lube</b> (Fleetguard LF9009)..... <b>B40142</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b>	Emergency One w/Cummins ISL 8.9 (8.9L) Eng. (2020) <b>Lube</b> (5444774)..... <b>B40142</b> <b>Fuel</b> (5303743)..... <b>BF63000</b>	ECM Series 7.28 w/MAN D0836 Eng. (09/00-on) <b>F-F Lube</b> (51055017180)..... <b>B7116</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>Air Dryer</b> (1368731)..... <b>BA5374+</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>
E-Z Rider II Max w/Cummins ISL-G (8.9L) Eng. (2018) <b>Lube</b> (Fleetguard LF9009)..... <b>B40142</b> <b>Fuel/Water Separator</b> (Fleetguard NG5900)..... <b>BF7695</b>	Emergency One w/Cummins ISL 8.9 (8.9L) Eng. (2021) <b>Lube</b> (5444774)..... <b>B40142</b>	
	HP75 SideStacker w/Cummins ISM Eng. <b>Dual-Flow Lube</b> ..... <b>BD7153+</b> <b>Fuel/Water Separator</b> ..... <b>BF1272-SPS</b>	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

ERF Trucks (cont'd)	ERF Trucks (cont'd)	ERF Trucks (cont'd)
ECL Series 7.28 RD3 w/MAN D0836 Eng. (09/00-on) F-F Lube (51055017180)..... <b>B7116</b> Fuel/Water Separator (51125030040)..... <b>BF1372</b> Air Dryer (1368731)..... <b>BA5374 +</b> Steering (81473016005)..... <b>P106-HD</b>	EC Series 10.30 TP4 w/Cummins LTA10.300 Eng. (08/93-on) Dual-Flow Lube (1355360)..... <b>BD103 +</b> 252.4 mm F-F Lube (1356338).... <b>B196 +</b> 286.5 mm F-F Lube (1356338).... <b>B96 +</b> B-P Lube (1356344)..... <b>B7577</b> Fuel (C156172)..... <b>BF957 +</b> Air (990199)..... <b>PA3499</b>	ECS Series 11.34 w/Cummins ISM340 Eng. (05/00-on) Dual-Flow Lube (3406809)..... <b>BD7154 +</b> Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> Air Dryer (1368731)..... <b>BA5374 +</b>
EC Series 8.24 w/Cummins 6TAA Turbo Eng. (08/93-on) Dual-Flow Lube (1355360)..... <b>BD103 +</b> 252.4 mm F-F Lube (1356338).... <b>B196 +</b> 286.5 mm F-F Lube (1356338).... <b>B96 +</b> B-P Lube (1356344)..... <b>B7577</b> Fuel/Water Separator (C3903202)..... <b>BF1226</b> Air (990199)..... <b>PA3499</b>	EC Series 10.32 w/Cummins LTA10.325 Eng. (08/93-on) Dual-Flow Lube (1355360)..... <b>BD103 +</b> 252.4 mm F-F Lube (1356338).... <b>B196 +</b> 286.5 mm F-F Lube (1356338).... <b>B96 +</b> B-P Lube (1356344)..... <b>B7577</b> Fuel (C156172)..... <b>BF957 +</b> Air (990199)..... <b>PA3499</b>	ECS Series 11.39 w/Cummins ISM390 Eng. (05/00-on) Dual-Flow Lube (3406809)..... <b>BD7154 +</b> Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> Air Dryer (1368731)..... <b>BA5374 +</b>
EC Series 8.27 w/Cummins 6TAA Turbo Eng. (08/93-on) Dual-Flow Lube (1355360)..... <b>BD103 +</b> 252.4 mm F-F Lube (1356338).... <b>B196 +</b> 286.5 mm F-F Lube (1356338).... <b>B96 +</b> B-P Lube (1356344)..... <b>B7577</b> Fuel/Water Separator (C3903202)..... <b>BF1226</b> Air (990199)..... <b>PA3499</b>	EC Series 10.34 w/Cummins L300 Turbo Eng. (08/93-on) 252.4 mm F-F Lube (1356338).... <b>B196 +</b> 286.5 mm F-F Lube (1356338).... <b>B96 +</b> B-P Lube (1356344)..... <b>B7577</b> Fuel (C156172)..... <b>BF957 +</b> Air (990199)..... <b>PA3499</b>	ECT Series 11.39 w/Cummins ISME385 Eng. (05/02-on) Dual-Flow Lube (3406809)..... <b>BD7154 +</b> Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> Cab Air (w/o Carbon) (81619100018)..... <b>PA4955</b> Cab Air (w/Carbon) (81619100019)..... <b>PA5477</b> Air Dryer (1368731)..... <b>BA5374 +</b> Steering (81473016005)..... <b>P106-HD</b>
ECS Series 8.28 w/Cummins C280 Eng. (05/00-on) Air Dryer (1368731)..... <b>BA5374 +</b> Coolant (C3315789)..... <b>BW5071</b>	EC Series 10.35 w/Cummins LTA10.350 Eng. (08/93-on) Dual-Flow Lube (1355360)..... <b>BD103 +</b> 252.4 mm F-F Lube (1356338).... <b>B196 +</b> 286.5 mm F-F Lube (1356338).... <b>B96 +</b> B-P Lube (1356344)..... <b>B7577</b> Fuel (C156172)..... <b>BF957 +</b> Air (990199)..... <b>PA3499</b>	ECX Series 11.39 w/Cummins ISM390 Eng. (05/00-on) Dual-Flow Lube (3406809)..... <b>BD7154 +</b> Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> Air Dryer (1368731)..... <b>BA5374 +</b>
ECS Series 8.30 w/Cummins C300 Eng. (05/00-on) Air Dryer (1368731)..... <b>BA5374 +</b> Coolant (C3315789)..... <b>BW5071</b>	ECT Series 10.35 w/MAN D2066 Eng. (06/05-on) F-F Lube (51055040107)..... <b>P7329</b> P. Fuel (51125030061)..... <b>PF7935</b> Radial Seal O. Air (81084050021)..... <b>RS4971</b> Radial Seal I. Air (81084050017)..... <b>RS5361</b> Cab Air (w/o Carbon) (81619100018)..... <b>PA4955</b> Cab Air (w/Carbon) (81619100019)..... <b>PA5477</b> Air Dryer (1368731)..... <b>BA5374 +</b> Steering (81473016005)..... <b>P106-HD</b>	ECX Series 11.40 w/Cummins ISM405 Eng. (05/00-on) Dual-Flow Lube (3406809)..... <b>BD7154 +</b> Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> Air Dryer (1368731)..... <b>BA5374 +</b>
E Series: E10-26R, E12-26ST, E12-30ST, E12-30TT, E12-34DT, E12-34ST, E12-34TT w/265 Eng. Lube Ele..... <b>P104</b> Fuel Spin-on..... <b>BF1102</b> Air (99019-9)..... <b>PA3499</b>	ECT Series 10.43 w/MAN D2066 Eng. (06/05-on) F-F Lube (51055040107)..... <b>P7329</b> P. Fuel (51125030061)..... <b>PF7935</b> Radial Seal O. Air (81084050021)..... <b>RS4971</b> Radial Seal I. Air (81084050017)..... <b>RS5361</b> Cab Air (w/o Carbon) (81619100018)..... <b>PA4955</b> Cab Air (w/Carbon) (81619100019)..... <b>PA5477</b> Air Dryer (1368731)..... <b>BA5374 +</b> Steering (81473016005)..... <b>P106-HD</b>	ECS Series 11.41 w/Cummins ISM405 Eng. (05/00-on) Dual-Flow Lube (3406809)..... <b>BD7154 +</b> Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> Air Dryer (1368731)..... <b>BA5374 +</b>
EC Series 10.30 RD4 w/Cummins LTA10.300 Eng. (08/93-on) Dual-Flow Lube (1355360)..... <b>BD103 +</b> 252.4 mm F-F Lube (1356338).... <b>B196 +</b> 286.5 mm F-F Lube (1356338).... <b>B96 +</b> B-P Lube (1356344)..... <b>B7577</b> Fuel (C156172)..... <b>BF957 +</b> Air (990199)..... <b>PA3499</b>	EC Series 10.30 ST w/Cummins L300 Eng. (08/93-on) Dual-Flow Lube (1355360)..... <b>BD103 +</b> 252.4 mm F-F Lube (1356338).... <b>B196 +</b> 286.5 mm F-F Lube (1356338).... <b>B96 +</b> B-P Lube (1356344)..... <b>B7577</b> Fuel (C156172)..... <b>BF957 +</b> Air (990199)..... <b>PA3499</b>	ECT Series 11.42 w/Cummins ISME420 Eng. (05/02-on) Dual-Flow Lube (3406809)..... <b>BD7154 +</b> Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> Cab Air (w/o Carbon) (81619100018)..... <b>PA4955</b> Cab Air (w/Carbon) (81619100019)..... <b>PA5477</b> Air Dryer (1368731)..... <b>BA5374 +</b> Steering (81473016005)..... <b>P106-HD</b>
		ECS Series 11.44 w/Cummins ISM440 Eng. (05/00-on) Dual-Flow Lube (3406809)..... <b>BD7154 +</b> Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

ERF Trucks (cont'd)	ERF Trucks (cont'd)	ERF Trucks (cont'd)
ECS Series 11.44 w/Cummins ISM440 Eng. (05/00-on) (Cont'd) <b>Air Dryer</b> (1368731)..... <b>BA5374 +</b>	ECT Series 13.48 w/MAN D2876 Eng. (05/02-on) <b>Air Dryer</b> (1368731)..... <b>BA5374 +</b>	C Series: 25R3, 31C4 w/Cummins Eng. <b>F-F Lube Spin-on</b> ..... <b>B196 +</b> <b>B-P Lube Ele.</b> ..... <b>C750-E +</b> <b>B-P Lube Spin-on</b> ..... <b>B7577</b> <b>Fuel Spin-on</b> ..... <b>BF957-D +</b> <b>Air</b> (955180)..... <b>PA2751</b>
ECX Series 11.44 w/Cummins ISM440 Eng. (05/00-on) <b>Dual-Flow Lube</b> (3406809)..... <b>BD7154 +</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Air Dryer</b> (1368731)..... <b>BA5374 +</b>	EC Series 14.34 w/Cummins NTAA340 Eng. (08/93-on) <b>Dual-Flow Lube</b> (1355360)..... <b>BD103 +</b> <b>Fuel</b> (C156172)..... <b>BF957 +</b> <b>Air</b> (990199)..... <b>PA3499</b>	B Series: 32G4, 34G2, 36G2 w/Gardner 6LXC Eng. <b>Lube Ele.</b> ..... <b>P352</b> <b>Lube Spin-on</b> ..... <b>B76 +</b> <b>P. Fuel</b> ..... <b>PF831</b> <b>Air</b> (95518-0)..... <b>PA2751</b> <b>Air</b> (95709-8)..... <b>PA2750</b>
EC11 w/Cummins ISM Eng. <b>Dual-Flow Lube</b> ..... <b>BD7153 +</b> <b>Fuel/Water Separator</b> ..... <b>BF1272-SPS</b>	EC Series 14.38 w/Cummins NTAA380 Eng. (08/93-on) <b>Dual-Flow Lube</b> (1355360)..... <b>BD103 +</b> <b>Fuel</b> (C156172)..... <b>BF957 +</b> <b>Air</b> (990199)..... <b>PA3499</b>	B Series: 35G2, 38G2 w/Gardner 8LXB 240 Eng. <b>Lube Ele.</b> ..... <b>P352</b> <b>P. Fuel</b> ..... <b>PF831</b> <b>Air</b> ..... <b>[2] PA656</b> <b>Tube-Type Air</b> (Farr P24)..... <b>PA1779</b>
ECM Series 12.36 w/MAN D2866 Eng. (09/02-on) <b>F-F Lube</b> (51055040098)..... <b>P7190</b> <b>P. Fuel</b> (51125030042)..... <b>PF7878</b> <b>S. Fuel</b> (51125030043)..... <b>PF7974</b> <b>Radial Seal O. Air</b> (81084050021)..... <b>RS4971</b> <b>Radial Seal I. Air</b> (81084050017)..... <b>RS5361</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (1368731)..... <b>BA5374 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>	EC Series 14.41 w/Cummins NTAA400 Eng. (08/93-on) <b>Dual-Flow Lube</b> (1355360)..... <b>BD103 +</b> <b>Fuel</b> (C156172)..... <b>BF957 +</b> <b>Air</b> (990199)..... <b>PA3499</b>	C Series: 35R2 w/Rolls-Royce 220 Eng. <b>Lube Ele.</b> ..... <b>P104</b> <b>Fuel Spin-on</b> ..... <b>BF1102</b>
ECT Series 12.36 w/MAN D2866 Eng. (05/02-on) <b>F-F Lube</b> (51055040098)..... <b>P7190</b> <b>P. Fuel</b> (51125030042)..... <b>PF7878</b> <b>S. Fuel</b> (51125030043)..... <b>PF7974</b> <b>Radial Seal O. Air</b> (81084050021)..... <b>RS4971</b> <b>Radial Seal I. Air</b> (81084050017)..... <b>RS5361</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (1368731)..... <b>BA5374 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>	ECX Series 14.47 w/Cummins N475 Eng. (05/00-on) <b>Dual-Flow Lube</b> (1355360)..... <b>BD103 +</b> <b>Air Dryer</b> (1368731)..... <b>BA5374 +</b> <b>Coolant</b> (C3315789)..... <b>BW5071</b>	C Series: 35R2, 36R2, 38R4, 40R2 w/Rolls-Royce 265L, 290L Eng. <b>Lube Ele.</b> ..... <b>P104</b> <b>Fuel Spin-on</b> ..... <b>BF1102</b> <b>Air</b> (95518-0)..... <b>PA2751</b> <b>Air</b> (95709-8)..... <b>PA2750</b>
ECT Series 13.46 w/MAN D2876 Eng. (05/02-on) <b>F-F Lube</b> (51055040098)..... <b>P7190</b> <b>P. Fuel</b> (51125030042)..... <b>PF7878</b> <b>S. Fuel</b> (51125030043)..... <b>PF7974</b> <b>Radial Seal O. Air</b> (81084050021)..... <b>RS4971</b> <b>Radial Seal I. Air</b> (81084050017)..... <b>RS5361</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (1368731)..... <b>BA5374 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>	EC Series 14.50 w/Cummins N500E Eng. (08/93-on) <b>Dual-Flow Lube</b> (1355360)..... <b>BD103 +</b> <b>Fuel</b> (C156172)..... <b>BF957 +</b> <b>Air</b> (990199)..... <b>PA3499</b>	C Series: 36C2, 38C2, 40C2 w/Cummins Eng. <b>F-F Lube Spin-on</b> ..... <b>B196 +</b> <b>B-P Lube Ele.</b> ..... <b>C750-E +</b> <b>B-P Lube Spin-on</b> ..... <b>B7577</b> <b>Fuel Spin-on</b> ..... <b>BF957-D +</b> <b>Air</b> (93822-9)..... <b>PA1902-FN</b> <b>Air</b> (95518-0)..... <b>PA2751</b>
ECT Series 13.48 w/MAN D2876 Eng. (05/02-on) <b>F-F Lube</b> (51055040098)..... <b>P7190</b> <b>P. Fuel</b> (51125030042)..... <b>PF7878</b> <b>S. Fuel</b> (51125030043)..... <b>PF7974</b> <b>Radial Seal O. Air</b> (81084050021)..... <b>RS4971</b> <b>Radial Seal I. Air</b> (81084050017)..... <b>RS5361</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (1368731)..... <b>BA5374 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>	ECX Series 14.52 w/Cummins N525 Eng. (05/00-on) <b>Dual-Flow Lube</b> (1355360)..... <b>BD103 +</b> <b>Air Dryer</b> (1368731)..... <b>BA5374 +</b> <b>Coolant</b> (C3315789)..... <b>BW5071</b>	B Series: 36R2 w/Rolls-Royce Eagle 265 Eng. <b>Lube Ele.</b> ..... <b>P104</b> <b>Fuel Spin-on</b> ..... <b>BF1102</b> <b>Air</b> (95709-8)..... <b>PA2750</b>
ECT Series 13.48 w/MAN D2876 Eng. (05/02-on) <b>F-F Lube</b> (51055040098)..... <b>P7190</b> <b>P. Fuel</b> (51125030042)..... <b>PF7878</b> <b>S. Fuel</b> (51125030043)..... <b>PF7974</b> <b>Radial Seal O. Air</b> (81084050021)..... <b>RS4971</b> <b>Radial Seal I. Air</b> (81084050017)..... <b>RS5361</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (1368731)..... <b>BA5374 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>	B Series: 16G2, 25G3, 31G2, 31G4, 32G4 w/Gardner 6LX, 6LXB 180 Eng. <b>Lube Ele.</b> ..... <b>P352</b> <b>P. Fuel</b> ..... <b>PF831</b> <b>Air</b> ..... <b>[2] PA656</b>	B Series: 38R2 w/Rolls-Royce Eagle 220, 265 Eng. <b>Lube Ele.</b> ..... <b>P104</b> <b>Can-Type Fuel</b> ..... <b>BF825 +</b> <b>Fuel Spin-on</b> ..... <b>BF1102</b> <b>Air</b> (35389)..... <b>PA656</b>
ECT Series 13.46 w/MAN D2876 Eng. (05/02-on) <b>F-F Lube</b> (51055040098)..... <b>P7190</b> <b>P. Fuel</b> (51125030042)..... <b>PF7878</b> <b>S. Fuel</b> (51125030043)..... <b>PF7974</b> <b>Radial Seal O. Air</b> (81084050021)..... <b>RS4971</b> <b>Radial Seal I. Air</b> (81084050017)..... <b>RS5361</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (1368731)..... <b>BA5374 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>	M Series: M16G2 w/Gardner 6LXB 180 Eng. <b>Lube Ele.</b> ..... <b>P352</b> <b>P. Fuel</b> ..... <b>PF831</b> <b>Air</b> ..... <b>PA656</b>	B Series: 38R2 w/Rolls-Royce Eagle 290L Eng. <b>Lube Ele.</b> ..... <b>P104</b> <b>Fuel Spin-on</b> ..... <b>BF1102</b> <b>Air</b> (95518-0)..... <b>PA2751</b>
ECT Series 13.48 w/MAN D2876 Eng. (05/02-on) <b>F-F Lube</b> (51055040098)..... <b>P7190</b> <b>P. Fuel</b> (51125030042)..... <b>PF7878</b> <b>S. Fuel</b> (51125030043)..... <b>PF7974</b> <b>Radial Seal O. Air</b> (81084050021)..... <b>RS4971</b> <b>Radial Seal I. Air</b> (81084050017)..... <b>RS5361</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (1368731)..... <b>BA5374 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>	B Series: 25R3, 31R4 w/Rolls-Royce Eagle 220, 265 Eng. <b>Lube Ele.</b> ..... <b>P104</b> <b>Can-Type Fuel</b> ..... <b>BF825 +</b> <b>Fuel Spin-on</b> ..... <b>BF1102</b> <b>Air</b> (35389)..... <b>PA656</b>	C Series: C38G2 w/Gardner 8LXB, 8LXC Eng. <b>Lube Ele.</b> ..... <b>P352</b> <b>Lube Spin-on</b> ..... <b>B76 +</b> <b>P. Fuel</b> ..... <b>PF831</b> <b>Air</b> (39134)..... <b>PA1885 +</b> <b>Air</b> (Upgrade) (39134)..... <b>PA1885XP</b> <b>Air</b> (93822-9)..... <b>PA1902-FN</b> <b>Air</b> (95518-0)..... <b>PA2751</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>ERF</b> Trucks (cont'd)	
B Series: 40C2, 42C2 w/Cummins Eng.	
F-F Lube Spin-on.....	B196 +
B-P Lube Ele.....	C750-E +
B-P Lube Spin-on.....	B7577
Fuel Spin-on.....	BF957 +
Air (938229).....	PA1902-FN
Air (955180).....	PA2751
Coolant.....	BW5071
B Series: 40G2 w/Gardner 8LXC Eng.	
Lube Ele.....	P104
P. Fuel.....	PF831
Air (33664).....	PA1884 +
Air (Upgrade) (33664).....	PA1884XP
Air (35389).....	PA656
Air (39134).....	PA1885 +
Air (Upgrade) (39134).....	PA1885XP
Air (938229).....	PA1902-FN
B Series: 40R2 w/Rolls-Royce Eagle 265L, 290L Engs.	
Lube Ele.....	P104
Fuel Spin-on.....	BF1102
Air (95709-8).....	PA2750
EC127 w/Detroit Diesel Series 60 Eng.	
Lube.....	[2] B495

<b>ESCO</b> Trucks	
450T	
Lube (1950).....	P52

<b>EVOBUS</b> (MERCEDES-BENZ/SENTRA) Buses	
17 RHD (629) w/OM502LA (11/99-12/06)	
Lube (Mann HU12140x).....	P7192
Fuel/Water Separator (w/Parker-Racor System) (Mann WK1080/7x).....	BF1391-O
Fuel (Mann PU999/1x).....	PF7761
Fuel/Water Separator (w/Webasto Heating System) (Mann WDK725).....	BF1372
Radial Seal Air (09/02-on) (Mann C19416).....	[5] RS5422
Air (Mann C331840).....	PA3765
Breather (Eng. S/N to 265303) (Mann C716x).....	CV15001
Steering (Mann H601/4).....	P106-HD
O500M w/OM904LA Eng. (01/98-on)	
Fuel/Water Separator (w/Undetachable Bowl) (A3844777015).....	BF46071
Fuel/Water Separator (Open End for Bowl) (A3844777015).....	BF46109-O
O500M w/OM906LA Eng. (01/98-on)	
Fuel/Water Separator (w/Undetachable Bowl) (A3844777015).....	BF46071

<b>EVOBUS</b> (MERCEDES-BENZ/SENTRA) Buses (cont'd)	
O500M w/OM906LA Eng. (01/98-on) (Cont'd)	
Fuel/Water Separator (Open End for Bowl) (A3844777015).....	BF46109-O
O500M w/OM926LA Eng. (01/00-on)	
Fuel/Water Separator (w/Undetachable Bowl) (A3844777015).....	BF46071
Fuel/Water Separator (Open End for Bowl) (A3844777015).....	BF46109-O
O500R w/OM926LA Eng. (01/00-on)	
Fuel/Water Separator (w/Undetachable Bowl) (A3844777015).....	BF46071
Fuel/Water Separator (Open End for Bowl) (A3844777015).....	BF46109-O
O500U w/OM906LA Eng. (01/98-on)	
Fuel/Water Separator (w/Undetachable Bowl) (A3844777015).....	BF46071
Fuel/Water Separator (Open End for Bowl) (A3844777015).....	BF46109-O
S 315 GT-HD w/OM457LA (09/00-on)	
Lube (Mann HU12110x).....	P7230
Lube (Mann HU945/2x).....	[2] P7188
Fuel/Water Separator (Mann WK1080/7x).....	BF1391-O
Fuel (Mann PU999/1x).....	PF7761
Radial Seal Air (Mann C19416)...	[5] RS5422
Steering (Mann H601/4).....	P106-HD
S 319 GT-HD w/OM457LA (09/00-on)	
Lube (Mann HU12110x).....	P7230
Lube (Mann HU945/2x).....	[2] P7188
Fuel/Water Separator (Mann WK1080/7x).....	BF1391-O
Fuel (Mann PU999/1x).....	PF7761
Radial Seal Air (Mann C19416)...	[5] RS5422
Steering (Mann H601/4).....	P106-HD
Steering (Mann P919/7).....	PT691
S 415 HD/HDH w/OM502LA (09/01-12/07)	
Lube (Mann HU12140x).....	P7192
Fuel/Water Separator (w/Parker System) (Mann WK1080/7x).....	BF1391-O
Fuel (Mann PU999/1x).....	PF7761
Fuel/Water Separator (w/Webasto Heating System) (Mann WDK725).....	BF1372
Radial Seal Air (Mann C19416)...	[5] RS5422
Air Dryer (Mann TB1394/1x).....	BA5379 +
Breather (Eng. S/N to 265 303) (Mann C716x).....	CV15001
Steering (Mann H601/4).....	P106-HD
S 416 HDH w/OM502LA (10/03-12/07)	
Lube (Mann HU12140x).....	P7192
Fuel/Water Separator (w/Parker System) (Mann WK1080/7x).....	BF1391-O
Fuel (Mann PU999/1x).....	PF7761

<b>EVOBUS</b> (MERCEDES-BENZ/SENTRA) Buses (cont'd)	
S 416 HDH w/OM502LA (10/03-12/07) (Cont'd)	
Fuel/Water Separator (w/Webasto Heating System) (Mann WDK725).....	BF1372
Radial Seal Air (Mann C19416)...	[5] RS5422
Air Dryer (Mann TB1394/1x).....	BA5379 +
Breather (Eng. S/N to 265 303) (Mann C716x).....	CV15001
Steering (Mann H601/4).....	P106-HD
S 417 HDH w/OM502LA (03/01-12/07)	
Lube (Mann HU12140x).....	P7192
Fuel/Water Separator (w/Parker System) (Mann WK1080/7x).....	BF1391-O
Fuel (Mann PU999/1x).....	PF7761
Fuel/Water Separator (w/Webasto Heating System) (Mann WDK725).....	BF1372
Radial Seal Air (Mann C19416)...	[5] RS5422
Air Dryer (Mann TB1394/1x).....	BA5379 +
Breather (Eng. S/N to 265 303) (Mann C716x).....	CV15001
Steering (Mann H601/4).....	P106-HD
S 431 DT w/OM502LA (06/02-on)	
Lube (Mann HU12140x).....	P7192
Fuel/Water Separator (w/Parker System) (Mann WK1080/7x).....	BF1391-O
Fuel (Mann PU999/1x).....	PF7761
Fuel/Water Separator (w/Webasto Heating System) (Mann WDK725).....	BF1372
Radial Seal Air (Mann C19416)...	[5] RS5422
Air Dryer (Mann TB1394/1x).....	BA5379 +
Breather (Eng. S/N to 265 303) (Mann C716x).....	CV15001
Steering (Mann H601/4).....	P106-HD

<b>FAGEOL</b> Trucks & Buses	
Models w/44 Eng.	
Lube.....	P53


<b>FEDERAL</b> Trucks	
16M, 18M, 18M2	
Lube (1947-52).....	P81
25, 29	
Lube (1B1283).....	P41 +
Lube (1B6402).....	P42
25M, 25M2	
Lube (1947-52).....	P41 +
29M	
Lube (1949-52).....	P41 +
35, 45, 55, 65, 66	
Lube (1947-51).....	P52

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FEDERAL Trucks (cont'd)	FIAT European Light Duty Vehicles (cont'd)	FIAT European Light Duty Vehicles (cont'd)
45M, 55M Lube (1952-54)..... P52	Doblo I 1.9D (119/223) w/63 HP Eng. (11/00-on) Lube (71736158)..... B7445	Ducato 1.9 TDI w/230BNAB Eng. (10/98-03/02) Lube (9456000927)..... B173-S Fuel (1909142)..... BF587-D +
60M, 65M Lube (1952-54)..... P42	Doblo I 1.9D JTD (119/223) w/182.B4.000 Eng. (01/01-on) Lube (71736158)..... B7445 Fuel (77363804)..... BF46052 Fuel..... BF7976	Ducato 2.0 i.e. w/RWF Eng. (03/94-03/02) Lube (9456000927)..... B173-S Fuel (82434499)..... BF885
400R, 600R Lube (1955-on)..... P52	Doblo I 1.9D JTD 105 (119/223) w/102 HP Eng. (07/03-on) Lube (71736158)..... B7445 Fuel (77363804)..... BF46052	Ducato 2.0 JTD w/110 HP Eng. (09/00-03/02) Lube (9456183480)..... B7428 Fuel (46797378)..... BF7976
500R Lube (1955-on)..... P42	Doblo I 1.9D JTD 105 (119/223) w/120 HP Eng. (11/05-on) Fuel (77363657)..... BF46051	Ducato 2.0 JTD w/84 HP Eng. (10/01-03/02) Lube (9456183480)..... B7428 Fuel (46797378)..... BF7976
1500, 1800 Lube (1950-54)..... P81 Lube (1955-on)..... P41 +	Doblo II 1.3 MTJD w/90 HP Eng. (01/10-on) Lube (73500049)..... P9605 Fuel (77363657)..... BF46051 Cabin Air (77364561)..... PA10085	Ducato 2.3 D 150 Multijet w/F1AGL411A Eng. Lube Spin-on (71779555)..... B7496 Air (1349042080)..... PA4472 Cabin Air (77364063)..... PA5798 <sup>90</sup>
1600 Lube (1951-54)..... P81	Doblo II 1.4 16V w/843A1.000 Eng. (01/10-on) Lube (71736161)..... B7441 Cabin Air (77364561)..... PA10085	Ducato 2.3 D 180 Multijet w/F1AGL411B Eng. Lube Spin-on (71779555)..... B7496 Air (1349042080)..... PA4472 Cabin Air (77364063)..... PA5798 <sup>90</sup>
2500, 2900 Lube (1950, (2500))..... P81 Lube (1950, (2900))..... P41 + Lube (1951-on)..... P41 +	Doblo II 1.4 Natural Power (CNG) w/198A1.000 Eng. (05/10-on) Lube (71736161)..... B7441 Cabin Air (77364561)..... PA10085	Ducato 2.5 Diesel w/Sofim 8140.67 Eng. (03/94-03/02) Dual-Flow Lube (98472349)..... BD232 Fuel (1909142)..... BF587-D + Air (5980183)..... PA3836
3400 Lube (1947-on)..... P52	Doblo II 1.6 JTD w/198A1.000 Eng. (01/10-on) Fuel (77363657)..... BF46051 Cabin Air (77364561)..... PA10085	Ducato 2.5 TDI w/Sofim 8140.47/R Eng. (03/94-03/02) Dual-Flow Lube (98472349)..... BD232 Fuel (1909142)..... BF587-D +
4400 Lube (1952-on)..... P52	Doblo II 1.6 JTD w/263A3.000 Eng. (01/10-on) Fuel (77363657)..... BF46051 Cabin Air (77364561)..... PA10085	Ducato 2.8 Diesel w/Sofim 8140.47 Eng. (02/98-03/02) Dual-Flow Lube (98472349)..... BD232 Fuel (1909142)..... BF587-D +
4500, 5500 Lube (1952-54)..... P52	Doblo II 1.6 JTD w/263A4.000 Eng. (01/10-on) Fuel (77363657)..... BF46051 Cabin Air (77364561)..... PA10085	Ducato 2.8 idTD w/Sofim 8140.43 Eng. (04/98-03/02) Dual-Flow Lube (98472349)..... BD232 Fuel (1909142)..... BF587-D +
6000 Lube (1952-on)..... P42	Doblo II 2.0 JTD w/263A1.000 Eng. (01/10-on) Fuel (77363657)..... BF46051 Cabin Air (77364561)..... PA10085	Ducato 2.8 idTD w/Sofim 8140.47 Eng. (02/98-03/02) Dual-Flow Lube (98472349)..... BD232
6500 Lube (1952)..... P42 Lube (1953-54)..... P52	Ducato 1.9 Diesel w/230A2000 Eng. (03/94-03/02) Lube (46805831)..... B7433 Fuel (1909142)..... BF587-D + Air (5980183)..... PA3836	Ducato 2.8 JTD w/Sofim 8140.43S Eng. (10/00-03/02) Dual-Flow Lube (98472349)..... BD232 Fuel (46797378)..... BF7976
ML, MLA Lube (1947-52)..... P41 +	Doblo I 1.2 (119/223) w/223A5.000 Eng. (11/00-on) Lube (71736161)..... B7441 Fuel (N/S)..... N/S	Ducato 2.8 TDI w/Sofim 8140.43 Eng. (10/97-03/02) Dual-Flow Lube (98472349)..... BD232
<b>FIAT</b> <b>European Light Duty Vehicles</b>	Doblo I 1.3 JTD (119/223) w/70 HP Eng. (04/04-12/05) Lube (73500049)..... P9605	Ducato 2002 2.0 i. w/RFL Eng. (02/02-on) Lube (9456183480)..... B7428 Fuel (N/S)..... N/S
Doblo I 1.3 Multijet 16V JTD (119/223) w/75 HP, 85 HP Eng. (11/05-on) Lube (73500049)..... P9605 Lube (55197218)..... P40058	Doblo I 1.4 8V (119/223) w/77 HP Eng. (10/05-on) Lube (71736161)..... B7441 Fuel (N/S)..... N/S	Ducato 2002 2.0 JTD w/RHV (DW10) Eng. (01/05-on) Lube (9456183480)..... B7428
Doblo I 1.4 8V (119/223) w/77 HP Eng. (10/05-on) Lube (71736161)..... B7441 Fuel (N/S)..... N/S	Doblo I 1.6 16V (119/223) w/182.A4.000 Eng. (01/01-on) Lube (5973928)..... B7430 Fuel (N/S)..... N/S	
Doblo I 1.6 16V (119/223) w/182.A4.000 Eng. (01/01-on) Lube (5973928)..... B7430 Fuel (N/S)..... N/S	Ducato 1.9 TD w/230A3000 Eng. (02/94-03/02) Lube (46805831)..... B7433 Fuel (1909142)..... BF587-D +	
	Ducato 1.9 TD w/230A4000 Eng. (08/94-03/02) Lube (46805831)..... B7433 Fuel (1909142)..... BF587-D +	

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



FIAT European Light Duty Vehicles (cont'd)	FIAT European Light Duty Vehicles (cont'd)	FIAT European Light Duty Vehicles (cont'd)
Ducato 2002 2.0 JTD w/RHV (DW10) Eng. (02/02-10/02) <b>Lube</b> (9456183480)..... <b>B7428</b> <b>Fuel</b> (46797378)..... <b>BF7976</b>	Ducato 2007 2.0 115 Multijet w/115 HP Eng. (06/11-on) <b>Fuel</b> (82425329)..... <b>BF46195</b> <b>Air</b> (1349042080)..... <b>PA4472</b> <b>Cabin Air</b> (77364063)..... <b>PA5798</b> <sup>90</sup>	Fiorino 1.4 Natural Power 8V w/70 HP Eng. (09/10-on) <b>Lube</b> (71736161)..... <b>B7441</b> <b>Cabin Air</b> (77364561)..... <b>PA10085</b>
Ducato 2002 2.0 JTD w/RHV (DW10) Eng. (11/02-12/04) <b>Lube</b> (9456183480)..... <b>B7428</b>	Ducato 2007 2.3 110 Multijet w/F1AE3481G Eng. (06/11-on) <b>Lube</b> (8094872)..... <b>B7496</b> <b>Fuel</b> (82425329)..... <b>BF46195</b> <b>Air</b> (1349042080)..... <b>PA4472</b> <b>Cabin Air</b> (77364063)..... <b>PA5798</b> <sup>90</sup>	Qubo 1.3 Multijet 16V 75 w/75 HP Eng. (11/08-on) <b>Lube</b> (71765460)..... <b>P9605</b> <b>Fuel</b> (77363804)..... <b>BF46052</b> <b>Cabin Air</b> (77364561)..... <b>PA10085</b>
Ducato 2002 2.3 JTD w/F1AE0481C Eng. (01/05-on) <b>Lube</b> (8093784)..... <b>B7377</b> <b>Lube</b> (8094872)..... <b>B7496</b>	Ducato 2007 2.3 115 Multijet w/F1AE3481E Eng. (06/11-on) <b>Lube</b> (8094872)..... <b>B7496</b> <b>Fuel</b> (82425329)..... <b>BF46195</b> <b>Air</b> (1349042080)..... <b>PA4472</b> <b>Cabin Air</b> (77364063)..... <b>PA5798</b> <sup>90</sup>	Qubo 1.3 Multijet 16V 95 w/95 HP Eng. (08/10-on) <b>Lube</b> (71765460)..... <b>P9605</b> <b>Fuel</b> (77363657)..... <b>BF46051</b> <b>Cabin Air</b> (77364561)..... <b>PA10085</b>
Ducato 2002 2.3 JTD w/F1AE0481C Eng. (02/02-12/04) <b>Lube</b> (8093784)..... <b>B7377</b>	Ducato 2007 2.3 JTD, 2.3 JTD 130 Multijet w/F1AE0481N, F1AE3481D Eng. (07/06-on) <b>Lube</b> (8094872)..... <b>B7496</b> <b>Fuel In-Line</b> (82425329)..... <b>BF46195</b> <b>Air</b> (1349042080)..... <b>PA4472</b> <b>Cabin Air</b> (77364063)..... <b>PA5798</b> <sup>90</sup>	Qubo 1.4 Natural Power 8V w/70 HP Eng. (09/10-on) <b>Lube</b> (71736161)..... <b>B7441</b> <b>Cabin Air</b> (77364561)..... <b>PA10085</b>
Ducato 2002 2.8 JTD w/8140.43N Eng. (01/05-on) <b>Lube</b> (8093784)..... <b>B7377</b>	Ducato 2007 2.3 JTD w/146 HP Eng. (04/10-05/11) <b>Lube</b> (8094872)..... <b>B7496</b> <b>Air</b> (1349042080)..... <b>PA4472</b> <b>Cabin Air</b> (77364063)..... <b>PA5798</b> <sup>90</sup>	Qubo 1.4 w/73 HP Eng. (11/08-on) <b>Lube</b> (9662282580)..... <b>P7450</b> <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Cabin Air</b> (77364561)..... <b>PA10085</b>
Ducato 2002 2.8 JTD w/8140.43N Eng. (04/04-10/04) <b>Dual-Flow Lube</b> (98472349)..... <b>BD232</b>	Ducato 2007 3.0 JTD w/157 HP Eng. (07/06-05/11) <b>Lube</b> (8094872)..... <b>B7496</b> <b>Air</b> (1349042080)..... <b>PA4472</b> <b>Cabin Air</b> (77364063)..... <b>PA5798</b> <sup>90</sup>	Scudo 2.0 D Multijet w/120 HP DW10UTED4 Eng. (2007-2016) <b>Lube Ele.</b> (9467521180)..... <b>P7450</b>
Ducato 2002 2.8 JTD w/8140.43N Eng. (11/04-12/04) <b>Lube</b> (8093784)..... <b>B7377</b>	Ducato 2007 3.0 JTD w/146 HP Eng. (04/10-05/11) <b>Lube</b> (8094872)..... <b>B7496</b> <b>Air</b> (1349042080)..... <b>PA4472</b> <b>Cabin Air</b> (77364063)..... <b>PA5798</b> <sup>90</sup>	Scudo 2.0 Multijet w/140 HP DW10BTED4 Eng. (2007-2016) <b>Lube Ele.</b> (9467521180)..... <b>P7450</b>
Ducato 2002 2.8 JTD w/8140.43S Eng. (01/05-on) <b>Lube</b> (8093784)..... <b>B7377</b>	Ducato 2007 3.0 JTD w/177 HP Eng. (06/11-on) <b>Lube</b> (8094872)..... <b>B7496</b> <b>Air</b> (1349042080)..... <b>PA4472</b> <b>Cabin Air</b> (77364063)..... <b>PA5798</b> <sup>90</sup>	Scudo 2.0 D Multijet w/128 HP DW10TED4 Eng. (2011-2016) <b>Lube Ele.</b> (9467521180)..... <b>P7450</b>
Ducato 2002 2.8 JTD w/8140.43S Eng. (02/02-10/02) <b>Dual-Flow Lube</b> (98472349)..... <b>BD232</b> <b>Fuel</b> (46797378)..... <b>BF7976</b>	Ducato 2007 3.0 JTD 180 Multijet Power w/177 HP Eng. (06/11-on) <b>Lube</b> (8094872)..... <b>B7496</b> <b>Air</b> (1349042080)..... <b>PA4472</b> <b>Cabin Air</b> (77364063)..... <b>PA5798</b> <sup>90</sup>	Scudo 2.0 D Multijet w/165 HP DW10TED4 Eng. (2010-2016) <b>Lube Ele.</b> (9467521180)..... <b>P7450</b>
Ducato 2002 2.8 JTD w/8140.43S Eng. (11/04-12/04) <b>Lube</b> (8093784)..... <b>B7377</b>	Ducato 2007 3.0 Natural Power w/136 HP Eng. (09/09-on) <b>Lube</b> (8094872)..... <b>B7496</b> <b>Air</b> (1349042080)..... <b>PA4472</b> <b>Cabin Air</b> (77364063)..... <b>PA5798</b> <sup>90</sup>	Strada 1.3 JTD w/86 HP 223.A.9000 Eng. (2006-2011) <b>Lube Ele.</b> (Purflux system) (73500049)..... <b>P9605</b> <b>Lube Ele.</b> (UFI system) (55238304)..... <b>P40058</b>
Ducato 2006 2.2 JTD w/4HV Eng. (07/06-on) <b>Lube</b> (9456183480)..... <b>B7428</b> <b>Air</b> (1349042080)..... <b>PA4472</b> <b>Cab Air</b> (77364063)..... <b>PA5798</b> <sup>90</sup>	Fiorino 1.3 Multijet 16V w/75 HP Eng. (02/08-on) <b>Lube</b> (71765460)..... <b>P9605</b> <b>Fuel</b> (77363804)..... <b>BF46052</b> <b>Cabin Air</b> (77364561)..... <b>PA10085</b>	Strada 1.3 JTD Multijet 16V w/95 HP 199.B.1000 Eng. (2011-2014) <b>Fuel</b> (77363657)..... <b>BF46051</b>
Ducato 2006 2.3 JTD w/F1AE0481D Eng. (07/06-on) <b>Lube</b> (9456203580)..... <b>B7428</b> <b>Air</b> (1349042080)..... <b>PA4472</b> <b>Cab Air</b> (77364063)..... <b>PA5798</b> <sup>90</sup>	Fiorino 1.3 Multijet 16V w/95 HP Eng. (08/10-on) <b>Lube</b> (71765460)..... <b>P9605</b> <b>Fuel</b> (77363657)..... <b>BF46051</b> <b>Cabin Air</b> (77364561)..... <b>PA10085</b>	
Ducato 2006 3.0 JTD w/F1CE0481D Eng. (07/06-on) <b>Lube</b> (9456203580)..... <b>B7428</b> <b>Air</b> (1349042080)..... <b>PA4472</b> <b>Cab Air</b> (77364063)..... <b>PA5798</b> <sup>90</sup>	Fiorino 1.4 w/73 HP Eng. (02/08-on) <b>Lube</b> (9662282580)..... <b>P7450</b> <b>Cabin Air</b> (77364561)..... <b>PA10085</b>	<b>FIAT Trucks, Vans, Etc.</b>
		Ducato 1.9D (1995-on) <b>Fuel Spin-on</b> ..... <b>BF587-D +</b> <b>Air</b> (1902457)..... <b>PA3836</b>
		Ducato 1.9TD (1995-on) <b>Fuel Spin-on</b> ..... <b>BF587-D +</b>
		Ducato 2.5D (1995-on) <b>Dual-Flow Lube</b> ..... <b>BD232</b> <b>Fuel Spin-on</b> ..... <b>BF587-D +</b> <b>Air</b> ..... <b>PA3836</b>


\* See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>FIAT</b> Trucks, Vans, Etc. (cont'd)	<b>FLXIBLE TRANSIT</b> Buses (cont'd)	<b>FODEN</b> Trucks (cont'd)
Ducato 2.5TDI (1995-on) Dual-Flow Lube..... <b>BD232</b> Fuel Spin-on..... <b>BF587-D +</b>	218GM1 P. Fuel Sock..... <b>F916-C</b> S. Fuel Ele..... <b>PF902</b>	Rigid 08R030C2208 w/Cummins NHK220 Eng. F-F Lube Ele. (Y02120202)..... <b>P999-HD</b> B-P Lube Ele. (Y02160711)..... <b>C750-E +</b> Fuel Spin-on..... <b>BF957 +</b> Air (Y02520504)..... <b>PA1884 +</b> Coolant..... <b>BW5071</b>
Ducato 10 Diesel, Ducato 10 Turbo Diesel, Ducato 14 Diesel, Ducato 14 Turbo Diesel w/1.9L Eng. Fuel Spin-on..... <b>BF587</b> Air (1902457)..... <b>PA3836</b>	218JB1 Fuel Ele. (105211)..... <b>PF821-S</b> Fuel (S3062-1-A)..... <b>PF902</b>	Rigid 08R030G1808 w/Gardner 6LX, 6LXB Eng. Air (Y02520504)..... <b>PA1884 +</b>
Ducato 10 Diesel, Ducato 14 Diesel, Ducato 18 Maxi Diesel w/2.5L Eng. Dual-Flow Lube..... <b>BD232</b> Fuel Spin-on..... <b>BF587</b>	228JT1 Lube (S/N 10208-up)..... <b>C704-L +</b>	Rigid 08R030G2208 w/Rolls-Royce Eagle 220 MKII Eng. Lube (Y00586607)..... <b>P104</b> Can-Type Fuel (Y01336609)..... <b>BF825 +</b> Air (Y02520504)..... <b>PA1884 +</b>
Ducato 10 Diesel, Ducato 14 Diesel, Ducato 18 Maxi Diesel w/Peugeot 2.0L Eng. Lube (To 6/94)..... <b>B173-S</b> Fuel..... <b>BF885</b>	236DD1 Lube..... <b>P20-HD +</b>	Rigid 6X6/24, Rigid 6XB6/24 w/Gardner 6LX, 6LXB Eng. Air (Y02204404)..... <b>PA1621-2</b> Air (Y02264502)..... <b>PA645</b>
Ducato 10 Diesel, Ducato 14 Diesel Dual-Flow Lube..... <b>BD232</b> Fuel Spin-on..... <b>BF587</b> Air (1902457)..... <b>PA3836</b>	2362DD1 Intercity Bus w/GMC 6V-71 Eng. F-F Lube..... <b>P20-HD +</b> B-P Lube..... <b>P52</b> P. Fuel Sock..... <b>F916-C</b> S. Fuel Ele..... <b>PF902</b>	Rigid 8L6/24, Rigid 8L6/26 w/Leyland DAF 680 Eng. Can-Type Fuel (Y01336609)..... <b>BF825 +</b> Air (Y02264502)..... <b>PA645</b>
Ducato 18 Diesel w/2.5L Eng. Can-Type Fuel..... <b>BF825 +</b> Fuel Spin-on..... <b>BF587</b> Air (1902457)..... <b>PA3836</b>	2362DD1 Intercity Bus w/GMC 6174E Eng. Lube..... <b>P20-HD +</b> P. Fuel Sock..... <b>F916-C</b> S. Fuel Ele..... <b>PF902</b>	Rigid 8XB6/28, 8XB6/30 w/Gardner 6LX, 6LXB Eng. Air (Y02204404)..... <b>PA1621-2</b> Air (Y02264502)..... <b>PA645</b>
Ducato 18 Maxi Diesel, Ducato 18 Maxi Turbo Diesel, Ducato 18 Turbo Diesel w/2.5L Eng. Can-Type Fuel..... <b>BF825 +</b> Fuel Spin-on..... <b>BF587</b> Air (1902457)..... <b>PA3836</b>	F2D6V-401 w/GMC 6V-71 Eng. F-F Lube..... <b>P20-HD +</b> B-P Lube..... <b>P52</b> P. Fuel Sock..... <b>F916-C</b> S. Fuel Ele..... <b>PF902</b>	Rigid 8XB6/30FT w/Gardner 6LXB Eng. Air (Y02520504)..... <b>PA1884 +</b> Air..... <b>PA1646-FN</b>
Ducato Cargo Van w/2.3L Diesel (Mexico) Lube (9456203580)..... <b>B7428</b> Air (1349042080)..... <b>PA4472</b>	<b>FODEN</b> Trucks	Rigid 8XB6/30FT w/Leyland DAF 680T Eng. Can-Type Fuel (Y01336609)..... <b>BF825 +</b> Air (Y02120607)..... <b>PA1636-FN</b>
Ducato Cargo Van w/3.0L Diesel (Mexico) Lube (9456203580)..... <b>B7428</b> Air (1349042080)..... <b>PA4472</b>	Artic 04A032C2208, Artic 04A032C2508 w/Cummins NHC200, NHC220, NHC250, NHK250, NTC290, NTK335 Eng. F-F Lube Ele. (Y02120202)..... <b>P999-HD</b> B-P Lube Ele. (Y02160711)..... <b>C750-E +</b> Fuel Spin-on..... <b>BF957 +</b> Air (Y02520504)..... <b>PA1884 +</b> Coolant..... <b>BW5071</b>	30 Ton Tipper Universal w/Gardner 6LXB Eng. Air (Y02520504)..... <b>PA1884 +</b>
Talento w/1.9L Diesel Eng. Fuel Spin-on..... <b>BF587</b> Air (1902457)..... <b>PA3836</b>	Artic 04A032G2508 w/Gardner 8LXB Eng. Air (Y02520504)..... <b>PA1884 +</b>	2000 Series w/Cummins 6BTA5.9 Eng. Lube..... <b>BT339 +</b> Opt. Fuel/Water Separator..... <b>BF1226</b> P. Fuel/Water Separator..... <b>BF1280 +</b> S. Fuel..... <b>BF788</b>
<b>FITZJOHN</b> Buses	Artic 04A032R2808, Artic 04A045C2508, Artic 040A32R2208 w/Rolls-Royce Eagle 220, 280 Eng. Lube (Y00586607)..... <b>P104</b> Can-Type Fuel (Y01336609)..... <b>BF825 +</b> Air (Y02520504)..... <b>PA1884 +</b>	2000 Series w/Perkins Phaser 210TI Eng. Lube..... <b>BT251</b> Can-Type Fuel..... <b>BF825 +</b>
Models w/Perkins S6 Diesel Eng. Can-Type Fuel..... <b>BF825 +</b>	Artic 06A075C2708, Artic 06A100C3308 w/Cummins NHC200, NHC220, NHC250, NHK250, NTC290, NTK335 Eng. F-F Lube Ele. (Y02120202)..... <b>P999-HD</b> B-P Lube Ele. (Y02160711)..... <b>C750-E +</b> Fuel Spin-on..... <b>BF957 +</b> Air (Y02520504)..... <b>PA1884 +</b> Coolant..... <b>BW5071</b>	3000 Series w/Cat C10, C12 Eng. Lube..... <b>B99 +</b> Fuel Spin-on..... <b>BF7587 +</b> Radial Seal Air (1317409)..... <b>RS3888</b>
Falcon w/Waukesha 140SK Eng. Lube..... <b>P52</b>	Rigid 06R024G1503, Rigid 06R024G1803 w/Gardner 6LX, 6LXB Eng. Air (Y02520504)..... <b>PA1884 +</b>	3000 Series w/Cummins 6CT8.3 Eng. Lube..... <b>B205 +</b> Opt. Fuel/Water Separator..... <b>BF1226</b> P. Fuel/Water Separator..... <b>BF1280 +</b> S. Fuel..... <b>BF788</b>
<b>FLEXI-TRUC</b> Trucks		Conical-Shaped Air (Y05590000)..... <b>PA3499</b> Round Air (Y03547112)..... <b>PA1885 +</b> Coolant..... <b>BW5071</b>
Models w/Ford V8-361 Eng. Lube..... <b>P80</b> Lube..... <b>P80-HD</b> Fuel..... <b>PF827</b>		
<b>FLXIBLE TRANSIT</b> Buses		
Some Models w/Cummins JT Eng. Lube..... <b>C704-L +</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).


FODEN Trucks (cont'd)	FODEN Trucks (cont'd)	FODEN Trucks (cont'd)
4000 Series w/Cat 3306 Eng. Lube (Y05008003)..... <b>B76 +</b> Lube (1R0716)..... <b>B99 +</b> P. Fuel Ele. (Y05014002)..... <b>PF935</b> Fuel Spin-on (Y05008005)..... <b>BF970 +</b> Conical-Shaped Air (Y03582800)..... <b>PA2751</b> Round Air (Y03547112)..... <b>PA1885 +</b> Coolant (Y02729203)..... <b>BW5137</b>	A108/1 w/Cummins L10, LT10 Eng. F-F Lube (Y02942403)..... <b>B196 +</b> B-P Lube (Y03426604)..... <b>B7577</b> Opt. Fuel/Water Separator..... <b>BF1212 +</b> Fuel Spin-on..... <b>BF957 +</b> Coolant..... <b>BW5071</b>	Artic FF33, Artic FF40 w/Cummins NHC200, NHC220, NHC250, NHK250, NTC290, NTK335 Eng. (Cont'd) Fuel Spin-on..... <b>BF957-D +</b> Air (Y02520504)..... <b>PA1884 +</b> Coolant..... <b>BW5071</b>
4000 Series w/Cat 3406 Eng. Lube (1R0716)..... <b>B99 +</b> P. Fuel Ele. (Y05014002)..... <b>PF935</b> Fuel Spin-on (1R0712)..... <b>BF614 +</b> Conical-Shaped Air (Y05590000)..... <b>PA3499</b> Round Air (Y03583806)..... <b>PA1846 +</b> Coolant (Y02729203)..... <b>BW5137</b>	Fleetmaster AC20/33 w/Gardner 6LXC Series Eng. Air (Y02520504)..... <b>PA1884 +</b>	Haulmaster w/Cummins NTC 250 Eng. Lube Ele. (Y02120202)..... <b>P999-HD</b> Fuel Spin-on..... <b>BF957 +</b>
4000 Series w/Cummins NTE Series Eng. F-F Lube (Y02942403)..... <b>B196 +</b> B-P Lube (Y03426604)..... <b>B7577</b> Opt. Fuel/Water Separator..... <b>BF1212 +</b> Fuel Spin-on..... <b>BF957 +</b> Conical-Shaped Air (Y05590000)..... <b>PA3499</b> Round Air (Y03583806)..... <b>PA1846 +</b>	Universal Range AC25/38 w/Cummins NHC250, NTC290 Eng. F-F Lube Ele. (Y02120202)..... <b>P999-HD</b> F-F Lube Spin-on (Y02942403)..... <b>B196 +</b> B-P Lube Ele. (Y02160711)..... <b>C750-E +</b> B-P Lube Spin-on (Y03426604)..... <b>B7577</b> Opt. Fuel/Water Separator..... <b>BF1212 +</b> Fuel Spin-on..... <b>BF957 +</b> O. Air (Y02520504)..... <b>PA1884 +</b> I. Air..... <b>PA1911</b>	Haulmaster w/Gardner 6LXB-180, 8LXB-240 Eng. Air..... <b>PA1621-2</b> Air (Y02520504)..... <b>PA1884 +</b>
4000 Series w/Cummins L10 Series Eng. F-F Lube (Y02942403)..... <b>B196 +</b> B-P Lube (Y03426604)..... <b>B7577</b> Opt. Fuel/Water Separator..... <b>BF1212 +</b> Fuel Spin-on..... <b>BF957 +</b> Conical-Shaped Air (Y05590000)..... <b>PA3499</b> Round Air (Y03583806)..... <b>PA1846 +</b>	Fleetmaster AC29/38 w/Cummins NTE290 Eng. F-F Lube Spin-on (Y02942403)..... <b>B196 +</b> B-P Lube Ele. (Y02160711)..... <b>C750-E +</b> B-P Lube Spin-on..... <b>B7577</b> Fuel Spin-on..... <b>BF957 +</b> Conical-Shaped Air (955180)..... <b>PA2751</b> Round Air (Y02265005)..... <b>PA1630-2</b> Round Air (Y02520504)..... <b>PA1884 +</b> Round Air..... <b>PA1621-2</b> Coolant..... <b>BW5071</b>	Haulmaster RC21/25 w/Cummins 240 Turbo Eng. F-F Lube (Y02942403)..... <b>B196 +</b> B-P Lube (Y03426604)..... <b>B7577</b> Fuel Spin-on..... <b>BF957 +</b> Air (Y02520504)..... <b>PA1884 +</b> Coolant..... <b>BW5071</b>
4000 Series w/Cummins L10 Series Eng. F-F Lube (Y02942403)..... <b>B196 +</b> B-P Lube (Y03426604)..... <b>B7577</b> Opt. Fuel/Water Separator..... <b>BF1212 +</b> Fuel Spin-on..... <b>BF957 +</b> Conical-Shaped Air (Y03582800)..... <b>PA2751</b> Round Air (Y03547112)..... <b>PA1885 +</b>	Universal Range AC29/38 w/Cummins NHC250, NTC290 Eng. F-F Lube Ele. (Y02120202)..... <b>P999-HD</b> F-F Lube Spin-on (Y02942403)..... <b>B196 +</b> B-P Lube Ele. (Y02160711)..... <b>C750-E +</b> B-P Lube Spin-on (Y03426604)..... <b>B7577</b> Opt. Fuel/Water Separator..... <b>BF1212 +</b> Fuel Spin-on..... <b>BF957 +</b> O. Air (Y02520504)..... <b>PA1884 +</b> I. Air..... <b>PA1911</b>	Haulmaster RC21/25 w/Cummins VT504 Eng. F-F Lube..... <b>B205 +</b> B-P Lube..... <b>B7577</b> Fuel Spin-on..... <b>BF957 +</b> Air (Y03547112)..... <b>PA1885 +</b> Coolant..... <b>BW5071</b>
4000 Series w/Gardner 6LXDT, 6LYT Eng. Lube (Y03601712)..... <b>B76 +</b> Conical-Shaped Air (Y03582800)..... <b>PA2751</b> Conical-Shaped Air (Y05590000)..... <b>PA3499</b> Round Air (Y03547112)..... <b>PA1885 +</b> Round Air (Y03583806)..... <b>PA1846 +</b>	Super Haulmaster AC29/45, Super Haulmaster AC29/65, Super Haulmaster AC29/66 w/Cummins NCT290E Eng. B-P Lube Ele. (Y02160711)..... <b>C750-E +</b> B-P Lube Spin-on (Y03426604)..... <b>B7577</b> Fuel Spin-on..... <b>BF957 +</b>	Super Haulmaster RC29/38 w/Cummins NCT290E Eng. B-P Lube Ele. (Y02160711)..... <b>C750-E +</b> B-P Lube Spin-on (Y03426604)..... <b>B7577</b> Fuel Spin-on..... <b>BF957 +</b>
4000 Series w/Rolls-Royce LE265, LF265, LE300, LF300, LF325, LF350 Eng. Conical-Shaped Air (Y03582800)..... <b>PA2751</b> Conical-Shaped Air (Y05590000)..... <b>PA3499</b> Round Air (Y03583806)..... <b>PA1846 +</b> Round Air (Y03547112)..... <b>PA1885 +</b>	Fleetmaster AR27/38 w/Rolls-Royce Eagle 220 MKII Eng. Air (Y02520504)..... <b>PA1884 +</b>	Haulmaster RG20/25, Haulmaster RG20/27, Haulmaster RG20/30 w/Gardner 6LXC, 8LXC-201 Eng. Air (Y02520504)..... <b>PA1884 +</b>
A3-6T.T w/Cummins ISM Eng. Dual-Flow Lube..... <b>BD7153 +</b> Fuel/Water Separator..... <b>BF1272-SPS</b> Radial Seal Air (1317409)..... <b>RS3888</b>	Super Haulmaster RR27/30 w/Rolls-Royce Eagle MKIII, 265, 290 Eng. Air (Y02520504)..... <b>PA1884 +</b>	Haulmaster RR29/30 w/Rolls-Royce Eagle MKIII, 265, 290 Eng. Air (Y02520504)..... <b>PA1884 +</b>
A3-8R.T w/Cat C12 Eng. Lube..... <b>B99 +</b> Fuel Spin-on..... <b>BF7587 +</b> Radial Seal Air (1317409)..... <b>RS3888</b>	Fleetmaster AR29/38, Fleetmaster AR29/40 w/Rolls-Royce Eagle 220 MKII Eng. Air (Y02520504)..... <b>PA1884 +</b>	S104, S106, S108 w/Cat 3306B Eng. Lube (Y03601712)..... <b>B76 +</b> Lube (Upgrade)..... <b>B76-SS +</b> Fuel Spin-on (Y05008005)..... <b>BF970 +</b> Conical-Shaped Air (Y03582800)..... <b>PA2751</b> Round Air (Y03547112)..... <b>PA1885 +</b> Round Air (Y03583806)..... <b>PA1846 +</b>
	Artic FF33, Artic FF40 w/Cummins NHC200, NHC220, NHC250, NHK250, NTC290, NTK335 Eng. F-F Lube Ele. (Y02120202)..... <b>P999-HD</b> B-P Lube Ele. (Y02160711)..... <b>C750-E +</b>	S104, S106, S108 w/Cat 3406B Eng. Lube (Y03601712)..... <b>B76 +</b> Fuel Spin-on (Y05008005)..... <b>BF970 +</b> Round Air (Y03583806)..... <b>PA1846 +</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FODEN Trucks (cont'd)	FODEN Trucks (cont'd)	FORD EUROPE Trucks (cont'd)
S104, S106, S108 w/Cat 3408 Eng. Lube (Y03601712)..... <b>B76 +</b> Lube (Upgrade)..... <b>B76-SS +</b> Fuel Spin-on (Y05008005)..... <b>BF970 +</b> Conical-Shaped Air (Y03582800)..... <b>PA2751</b> Round Air (Y03583806)..... <b>PA1846 +</b>	S104, S106, S108 w/Gardner 6LXCT, 8LXCT Engs. Lube (Y03601712)..... <b>B76 +</b> Conical-Shaped Air..... <b>PA2751</b> Round Air (Y02520504)..... <b>PA1884 +</b> Round Air (Y03547112)..... <b>PA1885 +</b>	Cargo 0811 w/90 Dover Eng. Lube..... <b>B7097</b> Can-Type Fuel..... <b>BF825 +</b>
S104, S106, S108 w/Cat 3408B Eng. Lube (Y03601712)..... <b>B76 +</b> Fuel Spin-on (Y05008005)..... <b>BF970 +</b> Air (Y03547112)..... <b>PA1885 +</b> Air (Y03583806)..... <b>PA1846 +</b>	S104, S106, S108 w/Gardner 6LXDT Eng. Lube (Y03601712)..... <b>B76 +</b> Air (Y03547112)..... <b>PA1885 +</b>	Cargo 0813 w/130 Dover Eng. Lube Spin-on..... <b>B7097</b> Can-Type Fuel..... <b>BF825 +</b> Air (To 12/81)..... <b>PA2647</b> Air..... <b>PA1884 +</b> Air..... <b>PA2581</b> Air..... <b>PA2756</b>
S104, S106, S108 w/Cummins 6BTA5.9 Eng. Lube..... <b>BT339 +</b> Opt. Fuel/Water Separator..... <b>BF1226</b> P. Fuel/Water Separator..... <b>BF1280 +</b> S. Fuel..... <b>BF788</b>	S104, S106, S108 w/Perkins Phaser 210TI Eng. Lube..... <b>BT251</b> Can-Type Fuel..... <b>BF825 +</b>	Cargo 0911, 1011 w/90 Dover Eng. Lube..... <b>B7097</b> Can-Type Fuel..... <b>BF825 +</b>
S104, S106, S108 w/Cummins LT10-250 Eng. F-F Lube (Y02942403)..... <b>B196 +</b> B-P Lube Spin-on (Y03426604)..... <b>B7577</b> Opt. Fuel/Water Separator..... <b>BF1212 +</b> Fuel Spin-on..... <b>BF957 +</b> Air (Y02520504)..... <b>PA1884 +</b> Air (Y03547112)..... <b>PA1885 +</b> Air (Y03583806)..... <b>PA1846 +</b> Coolant..... <b>BW5071</b>	S104, S106, S108 w/Rolls-Royce 220, 265 Engs. Air (Y02520504)..... <b>PA1884 +</b> Air (Y03547112)..... <b>PA1885 +</b> Air (Y03583806)..... <b>PA1846 +</b>	Cargo 1013 w/130 Dover Eng. Lube Spin-on..... <b>B7097</b> Can-Type Fuel..... <b>BF825 +</b> Air (To 12/81)..... <b>PA2647</b> Air..... <b>PA1884 +</b> Air..... <b>PA2581</b> Air..... <b>PA2756</b>
S104, S106, S108 w/Cummins NT250, NTE290 Engs. F-F Lube (Y02942403)..... <b>B196 +</b> B-P Lube Spin-on (Y03426604)..... <b>B7577</b> Opt. Fuel/Water Separator..... <b>BF1212 +</b> Fuel Spin-on..... <b>BF957 +</b> O. Air (Y03583806)..... <b>PA1846 +</b> I. Air..... <b>PA1880</b> Air (Y02520504)..... <b>PA1884 +</b> Air (Y03547112)..... <b>PA1885 +</b> Coolant..... <b>BW5071</b>	S104, S106, S108 w/Rolls-Royce 265L Eng. Lube (Y00586607)..... <b>P104</b> Conical-Shaped Air..... <b>PA2751</b> Round Air (Y02520504)..... <b>PA1884 +</b>	Cargo 1111, 1113 w/90 Dover Eng. Lube..... <b>B7097</b> Can-Type Fuel..... <b>BF825 +</b>
S104, S106, S108 w/Cummins E320TD Eng. F-F Lube (Y02942403)..... <b>B196 +</b> B-P Lube (Y03426604)..... <b>B7577</b> Fuel Spin-on..... <b>BF957 +</b> Coolant..... <b>BW5071</b>	S104, S106, S108 w/Rolls-Royce 290, 305, 320L Engs. Air (Y02520504)..... <b>PA1884 +</b> Air (Y03547112)..... <b>PA1885 +</b> Air (Y03583806)..... <b>PA1846 +</b>	Cargo 1113 w/130 Dover Eng. Lube Spin-on..... <b>B7097</b> Can-Type Fuel..... <b>BF825 +</b> Air (To 12/81)..... <b>PA2647</b> Air..... <b>PA1884 +</b> Air..... <b>PA2581</b> Air..... <b>PA2756</b>
S104, S106, S108 w/Cummins 350 Eng. F-F Lube (Y02942403)..... <b>B196 +</b> B-P Lube Spin-on (Y03426604)..... <b>B7577</b> Fuel Spin-on..... <b>BF957 +</b> Air (Y02520504)..... <b>PA1884 +</b>	S104, S106, S108 w/Rolls-Royce 325LE, 350LE Engs. Air (Y02520504)..... <b>PA1884 +</b> Air (Y03547112)..... <b>PA1885 +</b> Air (Y03583806)..... <b>PA1846 +</b>	Cargo 1117 w/Cummins V8-504 Eng. Lube Spin-on..... <b>B205 +</b> Fuel/Water Separator..... <b>BF1212 +</b> Air..... <b>PA1884 +</b> Air..... <b>PA2581</b> Air..... <b>PA2756</b> Coolant..... <b>BW5071</b>
S104, S106, S108 w/Cummins NTE350, VT504, V555 Engs. F-F Lube (Y02942403)..... <b>B196 +</b> B-P Lube Ele. (Y02160711)..... <b>C750-E +</b> B-P Lube Spin-on (Y03426604)..... <b>B7577</b> Opt. Fuel/Water Separator..... <b>BF1212 +</b> Fuel Spin-on..... <b>BF957 +</b> Air (Y02520504)..... <b>PA1884 +</b> Air (Y03547112)..... <b>PA1885 +</b> Air (Y03583806)..... <b>PA1846 +</b>	Fleetmaster AC24/33 w/Cummins 240 Turbo Eng. F-F Lube (Y02942403)..... <b>B196 +</b> B-P Lube (Y03426604)..... <b>B7577</b> Fuel Spin-on..... <b>BF957 +</b> Air (Y02265005)..... <b>PA1630-2</b> Air (Y02520504)..... <b>PA1884 +</b> Air..... <b>PA1621-2</b> Coolant..... <b>BW5071</b>	Cargo 1117 w/Perkins V8-540 Eng. Lube Spin-on..... <b>B233</b> Fuel Spin-on (Bosch)..... <b>BF988 +</b> Can-Type Fuel (C.A.V.)..... <b>BF812</b> Air..... <b>PA1884 +</b> Air..... <b>PA2581</b> Air..... <b>PA2641</b> Air..... <b>PA2756</b>
	<b>FORD EUROPE Trucks</b>	Cargo 1213 w/130 Dover Eng. Lube Spin-on..... <b>B7097</b> Can-Type Fuel..... <b>BF825 +</b> Air (To 12/81)..... <b>PA2647</b> Air..... <b>PA1884 +</b> Air..... <b>PA2581</b> Air..... <b>PA2756</b>
	Cargo 0711 w/90 Dover Eng. Lube..... <b>B7097</b> Can-Type Fuel..... <b>BF825 +</b>	Cargo 1217 w/Cummins V8-504 Eng. Lube Spin-on..... <b>B205 +</b> Fuel/Water Separator..... <b>BF1212 +</b> Air..... <b>PA1884 +</b> Air..... <b>PA2581</b>
	Cargo 0713 w/130 Dover Eng. Lube Spin-on..... <b>B7097</b> Can-Type Fuel..... <b>BF825 +</b> Air (To 12/81)..... <b>PA2647</b> Air..... <b>PA1884 +</b> Air..... <b>PA2581</b> Air..... <b>PA2756</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FORD EUROPE Trucks (cont'd)	FORD EUROPE Trucks (cont'd)	FORD EUROPE Trucks (cont'd)
Cargo 1217 w/Cummins V8-504 Eng. (Cont'd)	Cargo 1517 w/Cummins V8-504 Eng. (Cont'd)	Cargo 1620 w/Deutz F6L413F2 Eng.
Air..... PA2756	Air..... PA2581	Lube..... B236 +
Coolant..... BW5071	Air..... PA2756	Fuel/Water Separator..... BF1221 +
Cargo 1313 w/130 Dover Eng.	Coolant..... BW5071	Fuel..... BF988 +
Lube Spin-on..... B7097	Cargo 1517 w/Deutz F6L413F2 Eng.	Air..... PA1884 +
Can-Type Fuel..... BF825 +	Lube..... B236 +	Air..... PA2581
Air (To 12/81)..... PA2647	Fuel/Water Separator..... BF1221 +	Air..... PA2756
Air..... PA1884 +	Fuel..... BF988 +	Cargo 1713, 1813 w/130 Dover Eng.
Air..... PA2581	Air..... PA1884 +	Lube..... B7097
Air..... PA2756	Air..... PA2581	Can-Type Fuel..... BF825 +
Cargo 1317 w/Cummins V8-504 Eng.	Air..... PA2756	Air (To 12/81)..... PA2647
Lube..... B205 +	Cargo 1517 w/Perkins V8-540 Eng.	Air..... PA1884 +
Fuel/Water Separator..... BF1212 +	Lube Spin-on..... B233	Air..... PA2581
Air..... PA1884 +	Can-Type Fuel (C.A.V.)..... BF812	Air..... PA2756
Air..... PA2581	Fuel Spin-on..... BF988 +	Cargo 2417, 2517 w/Cummins V8-504 Eng.
Air..... PA2756	Air..... PA1884 +	Lube..... B205 +
Coolant..... BW5071	Air..... PA2581	Fuel/Water Separator..... BF1212 +
Cargo 1317 w/Deutz F6L413F2 Eng.	Air..... PA2641	Air..... PA1884 +
Lube..... B236 +	Air..... PA2756	Air..... PA2581
Fuel/Water Separator..... BF1221 +	Cargo 1520 w/Deutz F6L413F2 Eng.	Air..... PA2756
Fuel..... BF988 +	Lube..... B236 +	Coolant..... BW5071
Air..... PA1884 +	Fuel/Water Separator..... BF1221 +	Cargo 2517 w/Perkins V8-540 Eng.
Air..... PA2581	Fuel..... BF988 +	Lube Spin-on..... B233
Air..... PA2756	Air..... PA1884 +	Can-Type Fuel (C.A.V.)..... BF812
Cargo 1317 w/Perkins V8-540 Eng.	Air..... PA2581	Fuel Spin-on (Bosch)..... BF988 +
Lube Spin-on..... B233	Air..... PA2756	Air..... PA1884 +
Fuel Spin-on (Bosch)..... BF988 +	Cargo 1613 w/130 Dover Eng.	Air..... PA2581
Can-Type Fuel (C.A.V.)..... BF812	Lube..... B7097	Air..... PA2641
Air..... PA1884 +	Can-Type Fuel..... BF825 +	Air..... PA2756
Air..... PA2581	Air (To 12/81)..... PA2647	Cargo 2817 w/Cummins V8-504 Eng.
Air..... PA2641	Air..... PA1884 +	Lube..... B205 +
Air..... PA2756	Air..... PA2581	Fuel/Water Separator..... BF1212 +
Cargo 1320 w/Deutz F6L413F2 Eng.	Air..... PA2756	Air..... PA1884 +
Lube..... B236 +	Cargo 1617 w/Cummins V8-504 Eng.	Air..... PA2581
Fuel/Water Separator..... BF1221 +	Lube..... B205 +	Air..... PA2756
Fuel..... BF988 +	Fuel/Water Separator..... BF1212 +	Coolant..... BW5071
Air..... PA1884 +	Air..... PA1884 +	Cargo 2817 w/Perkins V8-540 Eng.
Air..... PA2581	Air..... PA2581	Lube Spin-on..... B233
Air..... PA2756	Air..... PA2756	Fuel Spin-on (Bosch)..... BF988 +
Cargo 1417 w/Cummins V8-504 Eng.	Coolant..... BW5071	Can-Type Fuel (C.A.V.)..... BF812
Lube..... B205 +	Cargo 1617 w/Deutz F6L413F2 Eng.	Air..... PA1884 +
Fuel/Water Separator..... BF1212 +	Lube..... B236 +	Air..... PA2581
Air..... PA1884 +	Fuel/Water Separator..... BF1221 +	Air..... PA2641
Air..... PA2581	Fuel..... BF988 +	Air..... PA2756
Air..... PA2756	Air..... PA1884 +	Cargo 2820 w/Deutz F6L413F2 Eng.
Coolant..... BW5071	Air..... PA2581	Lube..... B236 +
Cargo 1513 w/130 Dover Eng.	Air..... PA2756	Fuel/Water Separator..... BF1221 +
Lube Spin-on..... B7097	Cargo 1617 w/Perkins V8-540 Eng.	Fuel Spin-on..... BF988 +
Can-Type Fuel..... BF825 +	Lube Spin-on..... B233	Air..... PA1884 +
Air (To 12/81)..... PA2647	Fuel..... BF988 +	Air..... PA2581
Air..... PA1884 +	Can-Type Fuel (C.A.V.)..... BF812	Air..... PA2756
Air..... PA2581	Air..... PA1884 +	Cargo 3024 w/Cummins L10 Eng.
Air..... PA2756	Air..... PA2581	F-F Lube..... B196 +
Cargo 1517 w/Cummins V8-504 Eng.	Air..... PA2641	B-P Lube..... B7577
Lube..... B205 +	Air..... PA2756	Fuel/Water Separator..... BF1212 +
Fuel/Water Separator..... BF1212 +	Cargo 1620 w/Deutz F6L413F2 Eng.	Fuel Spin-on..... BF957-D +
Air..... PA1884 +	Lube..... B236 +	Coolant..... BW5071


+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FORD EUROPE Trucks (cont'd)	FORD EUROPE Trucks (cont'd)	FORD Diesel Engines (cont'd)
Cargo 3220 w/Deutz F6L413F2 Eng. Lube..... B236 + Fuel/Water Separator..... BF1221 + Fuel..... BF988 + Air..... PA1884 + Air..... PA2581 Air..... PA2756	Torneo w/2.5L Diesel Eng. Lube..... B7001	363 V8 Turbo (Power Stroke) Lube (w/o Screw on Cap)..... P7235 Lube (w/Screw on Cap) (Wix 57312)..... P7436 Fuel (Pickups)..... PF7812 KIT <sup>76</sup> Fuel (Vans) (FD4606)..... PF7852 KIT
Courier w/4 Cyl. 2.0L Eng. Lube..... B233 Fuel..... BF840 + Air..... PA2075	Transit w/Essex V4 (2.0L) Eng. Lube Ele..... PT108 Can-Type Fuel..... BF825 +	401 (6.6L) Lube (1986)..... BT343 Lube (1987-on) (E7HZ-6731-A).... [2] B157 Lube (1987-on) (F0HZ-6731-A).... [2] BT355 B-P Lube Ele. (750 Size)..... C750-E + Fuel/Water Separator (To 1991) (Motorcraft FD3370)..... BF1205
Courier w/L4-122 (2.0L) Eng. Lube..... B161-S Fuel..... BF933	Transit w/2.360 Eng. Lube..... P15 Can-Type Fuel (C.A.V.)..... BF825 + Fuel Spin-on (Bosch)..... BF587-D +	Fuel/Water Separator (w/ Drain or Sensor Port) (Motorcraft FD3368)..... BF1224 Fuel/Water Separator (w/Drain) (Motorcraft FD3368)..... BF1223 Fuel/Water Separator (w/Drain & Sensor Port) (Motorcraft FD3368). BF1223-SP Fuel/Water Separator (Open End for Bowl) (Motorcraft FD3368)..... BF1223-O Fuel Spin-on..... [2] BF7608
Courier w/4 Cyl. 2.3L Eng. Fuel..... BF840 +	Transit w/Perkins 4.99, 4.108 Eng. Lube Ele..... P15 Fuel Ele..... PF816-S	444 V8 (7.3L) Turbo (Power Stroke) Lube..... B7039 Fuel Ele. (To 1999)..... PF7678 Fuel Ele. (1999-on)..... PF7698 Air (1993, 1994 VIN K (Trucks))... PA4073 Air (1994-12/97 (Exc. 1994 VIN K Trucks))..... PA2233 Air (1/98-12/7/98 (Trucks))..... PA4110 Air (12/7/98-2001 (Trucks))..... PA4120 Air (2002-on (Trucks))..... PA4148 Air (Vans)..... [2] PA2237
Courier w/L4-140 (2.3L) Eng. Lube..... B233 Fuel..... BF933	Transit w/Perkins 4.203 Eng. Lube Ele..... PT108 Can-Type Fuel..... BF825 +	446 V8 (7.3L) Lube..... B134 Fuel/Water Separator (w/Sensor Port)..... BF1222-SP + Fuel/Water Separator (w/o Sensor Port)..... BF1222 + Fuel/Water Separator (Open End for Bowl)..... BF1222-O + Air (6/91-1994 (Exc. Vans))..... PA2092 Air (6/91-1994 (Vans))..... PA4005
Transit FT80 w/2.5L Diesel Eng. Lube (w/Turbo)..... B7001 Lube (w/o Turbo)..... B179 Fuel..... BF7522 Air (1/86-9/88)..... PA2984	Transit w/Perkins 6 Cyl. Diesel Eng. Lube Ele..... PT12 Can-Type Fuel..... BF825 +	476 (7.8L) Lube (E7HZ-6731-A)..... [2] B157 Lube (F0HZ-6731-A)..... [2] BT355 B-P Lube Ele. (750 Size)..... C750-E + Fuel/Water Separator (To 1991) (Motorcraft FD3370)..... BF1205 Fuel/Water Separator (w/o Drain or Sensor Port) (Motorcraft FD3368)..... BF1224 Fuel/Water Separator (w/Drain) (Motorcraft FD3368)..... BF1223 Fuel/Water Separator (w/Drain & Sensor Port) (Motorcraft FD3368). BF1223-SP Fuel/Water Separator (Open End for Bowl) (Motorcraft FD3368)..... BF1223-O
Transit FT100 w/York 2.4L Diesel Eng. Lube..... P15 Can-Type Fuel (C.A.V.)..... BF825 + Fuel Spin-on (Bosch)..... BF587-D + Fuel Spin-on..... BF790	Transcontinental H Series w/Cummins Eng. F-F Lube Ele..... P999-HD F-F Lube Spin-on..... B196 + B-P Lube Ele..... C750-E + B-P Lube Spin-on..... B7577 Fuel/Water Separator Ele..... PF316 Fuel/Water Separator Spin-on..... BF1212 + Fuel Spin-on..... BF957-D + Some Air (749F-6A752-AAA)..... PA643 Some Tube-Type Air (74HB-9601-AA)..... PA1781 Coolant..... BW5071	
Transit FT130 w/2.5L Diesel Eng. Lube (w/Turbo)..... B7001 Fuel (FC5111)..... BF7522 Air (1/86-9/88) (A1920)..... PA2984	<b>FORD Diesel Engines</b>	
Transit FT130 w/York 2.4L Diesel Eng. Lube..... P15 Can-Type Fuel (C.A.V.)..... BF825 + Fuel Spin-on (Bosch)..... BF587-D + Fuel Spin-on..... BF790	220 Lube (528E-6731-A)..... P190 Lube (C2TZ-6708-A)..... P15 Lube (957E-6731)..... PT108 P. Fuel (To S/N 400001, 4/63)..... PF827 Can-Type P. Fuel (S/N 400001-up)..... BF838-F2 S. Fuel Ele..... PF816	
Transit FT160 w/2.5L Diesel Eng. Lube (w/Turbo)..... B7001 Fuel (FC5111)..... BF7522 Air (1/86-9/88) (A1920)..... PA2984	230 Lube (C2TZ-6708-A)..... P15	
Transit FT160 w/York 2.4L Diesel Eng. Lube..... P15 Can-Type Fuel (C.A.V.)..... BF825 + Fuel Spin-on (Bosch)..... BF587-D + Fuel Spin-on..... BF790	242 Lube (C2TZ-6708-A)..... P15 Can-Type P. Fuel..... BF838-F2 S. Fuel Ele. (To 1969)..... PF816 Can-Type S. Fuel (1969-on)..... BF825 +	
Transit FT190 w/2.5L Diesel Eng. Lube (w/Turbo)..... B7001 Fuel (FC5111)..... BF7522 Air (1/86-9/88) (A1920)..... PA2984	330 Lube..... P15 P. Fuel Sock..... F916-C S. Fuel Ele..... PF816	
Transit FT190 w/York 2.4L Diesel Eng. Lube..... P15 Can-Type Fuel (C.A.V.)..... BF825 + Fuel Spin-on (Bosch)..... BF587-D + Fuel Spin-on..... BF790	363 Lube (1967-70)..... PT12 Can-Type Fuel..... BF825 +	

+ See Product Guide for Variations of This Number. <sup>76</sup> Contains Pri. and Sec. Fuel Elements. Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FORD Diesel Engines (cont'd)	FORD European Light Duty Vehicles (cont'd)	FORD European Light Duty Vehicles (cont'd)
476 (7.8L) (Cont'd)	C-Max I 2.0 Duratorq w/C20DD0X 110-143 HP Eng. (2007-10)	Fiesta VI 1.5 DI TC w/15DS0X 95-115 HP Eng. (2012-on)
Fuel Spin-on..... [2] BF7608	Lube (1717510)..... P7450	Air (1803059)..... PA10003
Coolant..... BW5136	Radial Seal Air (1848220)..... RS4450	Fiesta VI 1.6 Duratorq w/C16DD0X 75-110 HP Eng. (2008-10)
FD1060 (5.9L)	C-Max II/ Grand C-Max 1.0 Duratec w/C10FD0X 65 HP Eng. (2010-on)	Cabin Air (8V5118D543AA)..... PA4475
Lube..... BT339 +	Lube (9W7E6714AA)..... BT223	Fiesta VI 1.6 Duratorq w/C16DS0X 75-115 HP Eng. (2010-on)
Fuel/Water Separator (F3HZ-9365-E)..... BF1226	Radial Seal Air (1848220)..... RS4450	Cabin Air (8V5118D543AA)..... PA4475
FD1460 (8.3L)	C-Max II/ Grand C-Max 1.0 Ecoboost w/C10FD0X 75-100 HP Eng. (2010-on)	Fiesta VI 1.6 Duratec Ti-VCT w/C16HDEZ 100-125 HP Eng. (2008-on)
Dual-Flow Lube..... BD103 +	Lube (9W7E6714AA)..... BT223	Cabin Air (8V5118D543AA)..... PA4475
Fuel/Water Separator (F3HZ-9365-E)..... BF1226	Radial Seal Air (1848220)..... RS4450	Focus MK2 1.4 Duratec w/C14HDEZ 80 HP Eng. (2004-10)
Radial Seal O. Air (F3HZ-9601-A)..... RS2863	C-Max II/ Grand C-Max 1.6 Duratec w/C16HDEZ 85-125 HP Eng. (2010-on)	Radial Seal Air (1848220)..... RS4450
Radial Seal O. Air (F3HZ-9601-A)..... RS2863XP	C-Max II/ Grand C-Max 1.6 Duratorq w/C16DS0X 75-115 Eng. (2010-on)	Focus MK2 1.6 TDCi w/C16DD0X 75-110 HP Eng. (2004-10)
Radial Seal I. Air (F3HZ-9R500-A)..... RS3501	Radial Seal Air (1848220)..... RS4450	Radial Seal Air (1848220)..... RS4450
Coolant (F3HZ-8A424-D)..... BW5073	C-Max II/ Grand C-Max 2.0 Duratorq w/C20DD0X 115-150 HP Eng. (2010-on)	Focus MK2 1.6 Ti-VCT Duratec w/C16HDEZ 115 HP Eng. (2004-10)
<b>FORD</b>	Lube (1717510)..... P7450	Radial Seal Air (1848220)..... RS4450
<b>European Light Duty Vehicles</b>	Radial Seal Air (1848220)..... RS4450	Focus MK2 1.8 16V Duratec w/C18HDEA 125 HP Eng. (2004-10)
B-Max 1.0 Ecoboost w/C10FD0X 101-120 HP Eng. (2012-on)	Fiesta V 1.3 w/C13LSEZ 60 HP Eng. (2002-08)	Lube (1595247)..... BT8409
Lube (9W7E6714AA)..... BT223	Lube (1119421)..... B243	Radial Seal Air (1848220)..... RS4450
Air (1803059)..... PA10003	Fiesta V 1.6 Duratec Ti-VCT w/C16HDEZ 85-125 HP Eng. (2002-08)	Focus MK2 1.8 Duratorq TDCi w/C18DC4X 115 HP Eng. (2004-10)
B-Max 1.4 Duratec w/C14HDEZ 90 HP Eng. (2012-on)	Lube (1119421)..... B243	Radial Seal Air (1848220)..... RS4450
Air (CN119601AD)..... PA10003	Fiesta V 2.0 16V Duratec-HE w/C20HDEA 145 HP Eng. (2005-08)	Focus MK2 2.0 16V Duratec HE w/C20HDEA 145 HP Eng. (2004-10)
B-Max 1.5 Duratorq w/C15DS0X 75 HP Eng. (2012-on)	Lube (1595247)..... BT8409	Lube (1595247)..... BT8409
Air (1803059)..... PA10003	Fiesta VI 1.0 Duratec w/10FD0X 65-80 HP Eng. (2012-on)	Radial Seal Air (1848220)..... RS4450
B-Max 1.6 Duratec w/C16HDEZ 105 HP Eng. (2012-on)	Lube (9W7E6714AA)..... BT223	Focus MK2 2.0 Duratorq TDCi w/C20DD0X 110-136 HP Eng. (2004-10)
Air (1803059)..... PA10003	Air (1803059)..... PA10003	Lube (1717510)..... P7450
B-Max 1.6 Duratorq w/C16DS0X 95 HP Eng. (2012-on)	Fiesta VI 1.0 Ecoboost w/10FD0X 100-125 HP Eng. (2012-on)	Radial Seal Air (1848220)..... RS4450
Air (1803059)..... PA10003	Lube (9W7E6714AA)..... BT223	Focus MK2 2.5 Duratec VCT Turbo w/C25KDTD 225-305
C-Max I 1.6 Duratec Ti-VCT w/C16HDEZ 85-120 HP Eng. (2007-10)	Air (CN119601AD)..... PA10003	Lube (1421704)..... P7417
Radial Seal Air (1848220)..... RS4450	Fiesta VI 1.0 GTDI w/10FD0X 100-140 HP Eng. (2012-on)	Air (1418712)..... PA10280
C-Max I 1.6 Duratorq w/C16DD0X 75-110 HP Eng. (2007-10)	Lube (9W7E6714AA)..... BT223	Focus MK3 1.0 Ecoboost w/C10FD0X 100-125 HP Eng. (2011-on)
Radial Seal Air (1848220)..... RS4450	Air (1803059)..... PA10003	Lube (9W7E6714AA)..... BT223
C-Max I 1.8 16V Duratec HE w/C18HDEA 120-125 Hp Eng. (2007-10)	Fiesta VI 1.25 Duratec w/C12HDEZ 60-80 HP Eng. (2008-on)	Radial Seal Air (1848220)..... RS4450
Lube (1595247)..... BT8409	Cabin Air (8V5118D543AA)..... PA4475	Focus MK3 1.0 GTDI w/C10FD0X 100-140 HP Eng. (2011-on)
Radial Seal Air (1848220)..... RS4450	Fiesta VI 1.4 16V Duratec w/C14HDEZ 90 HP Eng. (2008-on)	Lube (9W7E6714AA)..... BT223
C-Max I 1.8 Duratorq w/C18DC4X 75-125 HP Eng. (2007-10)	Cabin Air (8V5118D543AA)..... PA4475	Radial Seal Air (1848220)..... RS4450
Radial Seal Air (1848220)..... RS4450	Fiesta VI 1.4 Duratorq TDCi w/C14DS4X 68 HP Eng. (2008-on)	Focus MK3 1.5 DI TC w/C15DS0X 95-115 HP Eng. (2014-on)
C-Max I 2.0 16V Duratec w/C20HDEA 145 HP Eng. (2007-10)	Cabin Air (8V5118D543AA)..... PA4475	Radial Seal Air (1848220)..... RS4450
Lube (1595247)..... BT8409		
Radial Seal Air (1848220)..... RS4450		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FORD European Light Duty Vehicles (cont'd)	FORD European Light Duty Vehicles (cont'd)	FORD European Light Duty Vehicles (cont'd)
Focus MK3 1.5 Ecoboost 16V w/C15HDTX 150-180 HP Eng. (2014-on) Radial Seal Air (1848220)..... <b>RS4450</b>	Mondeo MKIII 2.2 Duratorq TDCI w/155 HP Eng. (2001-07) Lube (1088179)..... <b>P7255</b> Cabin Air (1119613)..... <b>PA4153</b> Cabin Air (1S7H16N619AC)..... <b>PA4153</b> Cabin Air (1119616)..... <b>PA4153</b>	Mondeo MKV 1.0 GTDI w/C10FD0X 100 HP Eng. (10/2014-on) Lube (9W7E6714AA)..... <b>BT223</b> Fuel (2M519155AA)..... <b>BF7668</b> + Air (5243186)..... <b>PA4471</b> Air (DS739601AC)..... <b>PA4471</b>
Focus MK3 1.6 Duratec Ti-VCT w/C16HDEZ 85-125 HP Eng. (2011-on) Radial Seal Air (1848220)..... <b>RS4450</b>	Mondeo MKIII 2.5 Duratec EFI w/170 HP Eng. (2001-07) Lube (5191626)..... <b>B329</b> Cabin Air (1119613)..... <b>PA4153</b> Cabin Air (1S7H16N619AC)..... <b>PA4153</b> Cabin Air (1119616)..... <b>PA4153</b>	Mondeo MKV 1.5 16V Ecoboost w/C15HDTX 150-180 HP Eng. (10/2014-on) Fuel (2M519155AA)..... <b>BF7668</b> + Air (5243186)..... <b>PA4471</b> Air (DS739601AC)..... <b>PA4471</b>
Focus MK3 1.6 Ecoboost SCTI w/C16HD0Z 150-182 HP Eng. (2011-on) Radial Seal Air (1848220)..... <b>RS4450</b>	Mondeo MKIII 3.0 Duratec EFI w/200-220 HP Eng. (2001-07) Lube (5191626)..... <b>B329</b> Cabin Air (1119613)..... <b>PA4153</b> Cabin Air (1S7H16N619AC)..... <b>PA4153</b> Cabin Air (1119616)..... <b>PA4153</b>	Mondeo MKV 1.6 Duratorq w/C16DS0X 95-115 HP Eng. (10/2014-on) Air (5243186)..... <b>PA4471</b> Air (DS739601AC)..... <b>PA4471</b>
Focus MK3 1.6 Ecoboost Ti-VCT w/C16HD0Z 150 HP Eng. (2011-on) Radial Seal Air (1848220)..... <b>RS4450</b>	Mondeo MKIV 2.0 16V Duratec HE w/C20HDEA 145-150 HP Eng. (2007-14) Lube (1595247)..... <b>BT8409</b>	Mondeo MKV 2.0 4V PFI Gas/Electric w/C20EDEF Eng. (10/2014-on) Lube (9W7E6714AA)..... <b>BT223</b>
Focus MK3 2.0 16V Duratec Ti-VCT w/C20HDEX 154-160 HP Eng. (2011-on) Lube (9W7E6714AA)..... <b>BT223</b> Radial Seal Air (1848220)..... <b>RS4450</b>	Mondeo MKIV 2.0 Duratorq DI w/C20DD0X 110-163 HP Eng. (2007-14) Lube (1717510)..... <b>P7450</b>	Mondeo MKV 2.0 Duratorq w/C20DD0X 150-230 Eng. (10/2014-on) Air (5243186)..... <b>PA4471</b> Air (DS739601AC)..... <b>PA4471</b>
Focus MK3 2.0 Duratorq w/C20DD0X 115-163 HP Eng. (2011-on) Lube (1717510)..... <b>P7450</b> Radial Seal Air (1848220)..... <b>RS4450</b>	Mondeo MKIV 2.0 Turbo Ecoboost w/C20HD0D 200-250 HP Eng. (2010-14) Lube (9W7E6714AA)..... <b>BT223</b> Fuel (2M519155AA)..... <b>BF7668</b> + Air (5243186)..... <b>PA4471</b> Air (DS739601AC)..... <b>PA4471</b>	Mondeo MKV 2.0 Turbo Ecoboost w/C20HD0D 200-250 HP Eng. (10/2014-on) Lube (9W7E6714AA)..... <b>BT223</b> Fuel (2M519155AA)..... <b>BF7668</b> + Air (5243186)..... <b>PA4471</b> Air (DS739601AC)..... <b>PA4471</b>
Focus MK3 2.0 Ecoboost w/C20HD0D 200-250 HP Eng. (2011-on) Lube (9W7E6714AA)..... <b>BT223</b> Radial Seal Air (1848220)..... <b>RS4450</b>	Mondeo MKIV 2.2 Duratorq w/C22DD0X 200 HP Eng. (2010-14) Lube (1427824)..... <b>P7450</b>	Mondeo MKV 2.5 Duratec w/C25HDEX 170 HP Eng. (10/2014-on) Lube (9W7E6714AA)..... <b>BT223</b> Fuel (2M519155AA)..... <b>BF7668</b> + Air (5243186)..... <b>PA4471</b> Air (DS739601AC)..... <b>PA4471</b>
Ka I 1.3 Zetec w/C13LSEZ Eng. (2002-08) Lube (1119421)..... <b>B243</b>	Mondeo MKIV 2.0 Turbo Ecoboost w/C20HD0D 200-250 HP Eng. (2010-14) Lube (9W7E6714AA)..... <b>BT223</b>	Ranger 2.5 TDCI 16V Duratorq w/WLC Eng. (2006-2011) Fuel Spin-on (9M349150AA)..... <b>BF7535</b> Air Panel (XM3J9601AA)..... <b>PA4144</b>
Ka I 1.6 Zetec w/C16LSEZ Eng. (2002-08) Lube (1119421)..... <b>B243</b>	Mondeo MKIV 2.3 16V Duratec HE w/C23HDEX 160 HP Eng. (2007-14) Lube Ele. (1343102)..... <b>P7313</b> Lube Spin-on (1595247)..... <b>BT8409</b>	Ranger 3.0 TDCI 16V Duratorq w/WEC Eng. (2006-2011) Fuel Spin-on (9M349150AA)..... <b>BF7535</b> Air Panel (XM3J9601AA)..... <b>PA4144</b>
Ka II 1.2 w/C12LSED 69 HP Eng. (2008-on) Lube (1699522)..... <b>B7441</b>	Mondeo MKIV 2.5 turbo Duratec w/C25KDTD 220-305 HP Lube (1421704)..... <b>P7417</b> Air (1418712)..... <b>PA10280</b>	Ranger 2.5 16V w/T25HDEX Eng. (2011-on) Lube Spin-on (9W7E6714AA)..... <b>BT223</b>
Ka II 1.3 TDCi w/C13DD0X 75 HP Eng. (2008-on) Lube (Purflex) (To 11/2010) (1565248)..... <b>P9605</b> Fuel (To 11/2010) (1578143)..... <b>BF46052</b> Fuel (11/2010-on) (1729042)..... <b>BF46051</b>	Mondeo MKV 1.0 Duratec w/C10FD0X 65-80 HP Eng. (10/2014-on) Lube (9W7E6714AA)..... <b>BT223</b> Fuel (2M519155AA)..... <b>BF7668</b> + Air (5243186)..... <b>PA4471</b> Air (DS739601AC)..... <b>PA4471</b>	S-Max 2.0 16V Duratec HE w/C20HDEA 145 HP Eng. (2006-on) Lube (1595247)..... <b>BT8409</b>
Mondeo II 2.0 Duratorq w/90-130 HP Eng. (2001-07) Lube (1088179)..... <b>P7255</b> Cabin Air (1119613)..... <b>PA4153</b> Cabin Air (1S7H16N619AC)..... <b>PA4153</b> Cabin Air (1119616)..... <b>PA4153</b>	Mondeo MKV 1.0 Ecoboost w/C10FD0X 100-140 HP Eng. (10/2014-on) Lube (9W7E6714AA)..... <b>BT223</b> Fuel (2M519155AA)..... <b>BF7668</b> + Air (5243186)..... <b>PA4471</b> Air (DS739601AC)..... <b>PA4471</b>	S-Max 2.0 Duratorq w/C20DD0X 130 HP Eng. (2006-on) Lube (1717510)..... <b>P7450</b>
Mondeo MKIII 1.8 Duratec HE SCI w/130 HP Eng. (2001-07) Lube Ele. (1343102)..... <b>P7313</b> Lube Spin-on (To 11/2002) (1595247)..... <b>BT8409</b> Cabin Air (1119613)..... <b>PA4153</b> Cabin Air (1S7H16N619AC)..... <b>PA4153</b> Cabin Air (1119616)..... <b>PA4153</b>		S-Max 2.0 Ecoboost w/C20HD0D 200-250 HP Eng. (2010-on) Lube (9W7E6714AA)..... <b>BT223</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



FORD European Light Duty Vehicles (cont'd)	FORD European Light Duty Vehicles (cont'd)	FORD European Light Duty Vehicles (cont'd)
S-Max 2.2 Duratorq w/C22DD0X 175 HP Eng. (2008-on) Lube (1427824)..... P7450	Transit 2.2 TDCI w/T22DD0P Eng. (01/14-on) Fuel (CC119176BB)..... PF46004 Air (RWD) (1741635)..... PA4793 Cab Air (BK2118D543AA)..... PA30000 Cab Air (BK2119G244AA)..... PA30000 Cab Air (1839688)..... PA30000	Transit 2.3 16V w/145 HP Eng. (07/06-on) Lube (1250507)..... BT8409 Air (1C159601AC)..... PA4793
S-Max 2.2 Duratorq w/C22DD0X 200 HP Eng. (2010-on) Lube (1717510)..... P7450	Transit 2.2 TDCI 110 (07-06-on) Lube (3M5Q6744AA)..... P7450 Fuel (Euro 3) (YC159176AA)..... BF7746-D Fuel (Euro 4) (6C119176AA)..... BF9809-D Air (1373667)..... PA4425 <sup>90</sup>	Transit 2.3 16V w/E5FA Eng. (03/00-on) Lube (E1FZ6731A)..... B243 Air (1496814)..... PA4793
S-Max 2.3 Duratec HE w/C23HDEX 160 HP Eng. (2007-on) Lube Ele. (1343102)..... P7313 Lube Spin-on (1595247)..... BT8409	Transit 2.2 TDCI 130 (07-06-on) Lube (3M5Q6744AA)..... P7450 Fuel (Euro 3) (YC159176AA)..... BF7746-D Fuel (Euro 4) (6C119176AA)..... BF9809-D Air (1373667)..... PA4425 <sup>90</sup>	Transit 2.3 16V CNG w/145 HP Eng. (10/06-on) Lube (1250507)..... BT8409 Air (1496814)..... PA4793
S-Max 2.5 Turbo RS Duratec w/C25KDTD 305 HP Eng. ( ) Lube (1421704)..... P7417 Air (1418712)..... PA10280	Transit 2.2 TDCI 135 w/USRA/USRB Eng. (09/11-on) Lube (6C1Q6744AA)..... P7450 Fuel (1764944)..... PF46004 Air (1496814)..... PA4793	Transit 2.4 DI TD w/75 HP Eng. (03/00-on) Lube (1088179)..... P7255 Fuel (To 10/04) (YC159176AA)..... BF7746-D Fuel (10/04-on) (4537951)..... BF9827-D Air (1496814)..... PA4793
S-Max 2.5 Turbo ST Duratec w/C25KDTD 220 HP Eng. ( ) Lube (1421704)..... P7417 Air (1418712)..... PA10280	Transit 2.2 TDCI 140 (10/07-on) Lube (3M5Q6744AA)..... P7450 Fuel (Euro 3) (YC159176AA)..... BF7746-D Fuel (Euro 4) (6C119176AA)..... BF9809-D Air (1373667)..... PA4425 <sup>90</sup>	Transit 2.4 DI TDE w/D2FA/FE 90 HP Eng. (03/00-on) Lube (1088179)..... P7255 Fuel (To 10/04) (YC159176AA)..... BF7746-D Fuel (11/04-on) (4537951)..... BF9827-D Air (1496814)..... PA4793
Transit 2.0 w/NSG Eng. (07/94-12/00) Lube (w/AirCond.) (5002230)..... B233	Transit 2.2 TDCI 155 w/2.2 Duratorq TDCI Eng. (09/ ) Lube (6C1Q6744AA)..... P7450 Fuel (1764944)..... PF46004 Air (1496814)..... PA4793	Transit 2.4 DI TDE w/D4FA 115 HP Eng. (03/04-11/04) Lube (1088179)..... P7255 Fuel (Euro 3) (YC159176AA)..... BF7746-D Fuel (Euro 4) (1370779)..... BF9809-D Air (1C159601AC)..... PA4793
Transit 2.0 DI TD w/D3FA Eng. (08/00-on) Lube (1088179)..... P7255 Fuel (To 10/04) (YC159176AA)..... BF7746-D Fuel (11/04-on) (4537951)..... BF9827-D Air (1C159601AC)..... PA4793	Transit 2.2 TDCI 85 (07-06-on) Lube (3M5Q6744AA)..... P7450 Fuel (Euro 3) (YC159176AA)..... BF7746-D Fuel (Euro 4) (6C119176AA)..... BF9809-D Air (1373667)..... PA4425 <sup>90</sup>	Transit 2.4 DI TDE w/D4FA 115 HP Eng. (11/04-on) Lube (1088179)..... P7255 Fuel (4032667)..... BF7746-D Air (1C159601AC)..... PA4793
Transit 2.0 DI TDE w/125 HP Eng. (07/02-11/04) Lube (1088179)..... P7255 Fuel (YC159176AA)..... BF7746-D Air (1C159601AC)..... PA4793	Transit 2.2 TDCI ECOnetic w/100 HP Eng. (09/11-on) Lube (6C1Q6744AA)..... P7450 Fuel (1764944)..... PF46004 Air (RWD) (1496814)..... PA4793	Transit 2.4 DI TDE w/D4FA 120 HP Eng. (03/00-on) Lube (1088179)..... P7255 Fuel (To 10/04) (YC159176AA)..... BF7746-D Fuel (11/04-on) (4537951)..... BF9827-D Air (1C159601AC)..... PA4793
Transit 2.0 DI TDE w/125 HP Eng. (11/04-on) Lube (1088179)..... P7255 Fuel (4669224)..... BF9810-D Air (1C159601AC)..... PA4793	Transit 2.2 TDCI ECOnetic w/115 HP Eng. (10/08-11/11) Lube (3M5Q6744AA)..... P7450 Fuel (Euro 3) (YC159176AA)..... BF7746-D Fuel (Euro 4) (6C119176AA)..... BF9809-D Air (1373667)..... PA4425 <sup>90</sup>	Transit 2.4 DI TDE w/D4FA 125 HP Eng. (11/01-on) Lube (1088179)..... P7255 Fuel (To 10/04) (YC159176AA)..... BF7746-D Fuel (11/04-on) (4537951)..... BF9827-D Air (1C159601AC)..... PA4793
Transit 2.0 DI TDE w/85 HP Eng. (08/00-on) Lube (1088179)..... P7255 Fuel (To 10/04) (YC159176AA)..... BF7746-D Fuel (11/04-on) (4537951)..... BF9827-D Air (1C159601AC)..... PA4793	Transit 2.2 TDCI ECOnetic w/125 HP Eng. (09/11-on) Lube (3M5Q6744AA)..... P7450 Fuel (1764944)..... PF46004 Air (RWD or AWD) (1496814)..... PA4793	Transit 2.4 DI TDE w/D4FA 137 HP Eng. (03/04-11/04) Lube (1088179)..... P7255 Fuel (To 10/04) (YC159176AA)..... BF7746-D Fuel (11/04-on) (4537951)..... BF9827-D Air (1C159601AC)..... PA4793
Transit 2.0 DI TDE w/ABFA Eng. (08/00-on) Lube (1088179)..... P7255 Fuel (To 10/04) (YC159176AA)..... BF7746-D Fuel (11/04-on) (4537951)..... BF9827-D Air (1C159601AC)..... PA4793		Transit 2.4 DI TDE w/D4FA 137 HP Eng. (11/04-on) Lube (1088179)..... P7255 Fuel (Euro 3) (YC159176AA)..... BF7746-D Fuel (Euro 4) (1370779)..... BF9809-D Air (1C159601AC)..... PA4793
Transit 2.0 TDCI 16V Eco Blue (03/16-on) Cabin Air (1812679)..... PA30000 Cab Air (1839688)..... PA30000		
Transit 2.2 TDCI w/100, 125, 140, 155 HP Eng. (09/12-on) Lube (6C1Q6744AA)..... P7450 Fuel (1837319)..... PF46004 Air (RWD or 4WD) (1741635)..... PA4793 Cabin Air (BK21-18D543-AA)..... PA30000		

<sup>90</sup> Obsolete Pending.


Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FORD European Light Duty Vehicles (cont'd)	FORD European Light Duty Vehicles (cont'd)	FORD European Light Duty Vehicles (cont'd)
Transit 2.4 TDCI 100 w/100 HP Eng. (07/06-on) Lube (3M5Q6744AA)..... <b>P7450</b> Fuel (Euro 3) (YC159176AA)..... <b>BF7746-D</b> Fuel (Euro 4) (6C119176AA)..... <b>BF9809-D</b> Air (1C159601AC)..... <b>PA4793</b>	Transit Connect 1.5 TDCI Duratorq (2015-on) <b>Radial Seal Air (1848220)..... RS4450</b>	Transit Custom 2.0 TDCi 16V Eco Blue w/YLFS Eng. (12/15-on) <b>Cabin Air (1812679)..... PA30000</b>
Transit 2.4 TDCI 115 w/115 HP Eng. (07/06-on) Lube (3M5Q6744AA)..... <b>P7450</b> Fuel (Euro 3) (YC159176AA)..... <b>BF7746-D</b> Fuel (Euro 4) (6C119176AA)..... <b>BF9809-D</b> Air (1C159601AC)..... <b>PA4793</b>	Transit Connect 1.6 Duratorq w/C16DSOX Eng. (2013-on) <b>Radial Seal Air (1848220)..... RS4450</b>	Transit Connect 1.5 TDCi EConectic w/XVGA, XVGB, XVGC Eng. (2015-on) <b>Radial Seal Air (1848220)..... RS4450</b>
Transit 2.4 TDCI 140 w/140 HP Eng. (07/06-on) Lube (3M5Q6744AA)..... <b>P7450</b> <b>Centrifugal Lube</b> (6C1Q6N602BA)..... <b>BC40007<sup>90</sup></b> Fuel (Euro 3) (YC159176AA)..... <b>BF7746-D</b> Fuel (Euro 4) (6C119176AA)..... <b>BF9809-D</b> Air (1C159601AC)..... <b>PA4793</b>	Transit Connect 1.6 Ecoboost w/C16HD0Z Eng. (2013-on) <b>Radial Seal Air (1848220)..... RS4450</b>	<b>FORD Gas Engines</b>
Transit 2.5 D w/4HB Eng. (07/94-09/97) Lube (6203126)..... <b>B7001</b> Fuel (6202100)..... <b>BF7522</b>	Transit Connect 1.8 Lynx w/T18DC4X Eng. (2013-on) Lube (2M5Q6714AC)..... <b>B7001</b> Cab Air (XS4H16N619AB)..... <b>PA10142</b> Cab Air (XS4H19G244AA)..... <b>PA10142</b> Cab Air (1121106)..... <b>PA10142</b>	144 6 Cyl. Lube Spin-on..... <b>B2<sup>+</sup></b> In-Line Fuel (1960)..... <b>BF843</b> In-Line Fuel (1961-62)..... <b>BF840<sup>+</sup></b> In-Line Fuel (1966-67, (Carb.)).... <b>BF879</b> Air (1960-62, (E100, P100))..... <b>PA642</b>
Transit 2.5 D w/4HB Eng. (10/97-12/00) Lube (6203126)..... <b>B7001</b> Fuel (1015734)..... <b>BF7821<sup>90</sup></b>	Transit Connect 1.8 D Zetec-E w/T18HDEZ Eng. (2013-on) Lube (978M6714B4A)..... <b>B243</b> Cab Air (XS4H16N619AB)..... <b>PA10142</b> Cab Air (XS4H19G244AA)..... <b>PA10142</b> Cab Air (1121106)..... <b>PA10142</b>	170 6 Cyl. Lube..... <b>B2<sup>+</sup></b> In-Line Fuel (1961-64)..... <b>BF840<sup>+</sup></b> Fuel Ele. (1963-65, 1967)..... <b>PF827</b> In-Line Fuel (1966-72, (Carb.)).... <b>BF879</b> Air (1961-66, (Ranchero))..... <b>PA642</b> Air (1965-67, (Bronco))..... <b>PA642</b> Air (1968-72, (Bronco))..... <b>PA2005</b> Air (1968-72, (E Series))..... <b>PA657</b>
Transit 2.5 DI w/4FA, 4FB, 4FC Eng. (04/97-09/97) Lube (6203126)..... <b>B7001</b> Fuel (6202100)..... <b>BF7522</b>	Transit Connect 2.5 w/C25HDEX Eng. (2013-on) Lube (9W7E6714AA)..... <b>BT223</b> Air (5182117)..... <b>PA4470</b>	200 6 Cyl. Lube..... <b>B2<sup>+</sup></b> Fuel Ele. (1963-65)..... <b>PF827</b> In-Line Fuel (1965-74, (Carb.)).... <b>BF879</b> Air (1968, (Ranchero))..... <b>PA642</b> Air (1968-74, (Bronco))..... <b>PA2005</b>
Transit 2.5 DI w/4FA, 4FB, 4FC Eng. (10/97-12/00) Lube (6203126)..... <b>B7001</b> Fuel (1015734)..... <b>BF7821<sup>90</sup></b>	Transit Courier 1.0 TI Ecoboost w/C10FD0X Eng. (2014-on) Lube Spin-on (9W7E6714AA).... <b>BT223</b> Air Panel (CN119601AD)..... <b>PA10003</b>	223 6 Cyl. Lube Ele. (1954-59)..... <b>P80</b> Lube Ele. (1960-63)..... <b>P184</b> Lube Ele. (1954-59)..... <b>P80-HD</b> Lube Spin-on..... <b>B2<sup>+</sup></b> Fuel (1954-64)..... <b>PF857</b> Air (1957-60, (F Series))..... <b>PA602</b> Air (1961-64, (Ranchero))..... <b>PA642</b>
Transit 2.5 DI-TDE w/4ED Eng. (05/99-03/00) Lube (6203126)..... <b>B7001</b> Fuel (1015734)..... <b>BF7821<sup>90</sup></b>	Transit Courier 1.5 TDCI w/C15DSOX 75HP Eng. (2014-on) Air Panel (CN119601AD)..... <b>PA10003</b>	226 6 Cyl. Lube..... <b>P42</b>
Transit 2.5 TDE w/4HA, 4HD Eng. (11/98-12/00) Lube (6203126)..... <b>B7001</b> Fuel (1015734)..... <b>BF7821<sup>90</sup></b>	Transit Courier 1.5 TDCI w/C15DSOX 95HP Eng. (2015-on) Air Panel (CN119601AD)..... <b>PA10003</b>	232 V6 Lube..... <b>B2<sup>+</sup></b> Screw-in Fuel (Exc. Calif.)..... <b>BF920</b>
Transit 2.5 TDI w/4EB, 4GC Eng. (08/95-09/97) Lube (6203126)..... <b>B7001</b> Fuel (6202100)..... <b>BF7522</b>	Transit Courier 1.6 TDCI w/C16DSOX Eng. (2014-on) Air Panel (CN119601AD)..... <b>PA10003</b>	239 V8 Lube (1948-53, (Exc. 1952-53 B500, B600, B700))..... <b>P42</b> Lube (1952-53, (B500, B600, B700))..... <b>P41</b> Lube (1954-55)..... <b>P80</b> Lube (1954-55)..... <b>P80-HD</b>
Transit 2.5 TDI w/4EB, 4GC Eng. (10/97-12/00) Lube (6203126)..... <b>B7001</b> Fuel (1015734)..... <b>BF7821<sup>90</sup></b>	Transit Custom 2.0 TDCI Duratorq (12/15-on) Cabin Air (1812679)..... <b>PA30000</b> Cab Air (1839688)..... <b>PA30000</b>	240 6 Cyl. Lube Ele. (1965-74) (C5RA-6744-C)..... <b>P184</b> Lube Spin-on..... <b>B2<sup>+</sup></b> Fuel Ele. (1965-72)..... <b>PF827</b> In-Line Fuel (1965-74, (Carb.)).... <b>BF879</b> Air (1968-74, (E Series))..... <b>PA657</b>
Transit 3.2 TDCI (10/07-on) Lube (3M5Q6744AA)..... <b>P7450</b> <b>Centrifugal Lube</b> (1372808)..... <b>BC40007<sup>90</sup></b> Fuel (Euro 3) (YC159176AA)..... <b>BF7746-D</b> Fuel (Euro 4) (1370779)..... <b>BF9809-D</b>	Transit Custom 2.2 Duratorq w/T22DD0P Eng. (2012-on) Lube (6C1Q6744BA)..... <b>P7450</b> Fuel (1837319)..... <b>PF46004</b> Cab Air (1812679)..... <b>PA30000</b> Cab Air (BK2119G244AA)..... <b>PA30000</b> Cab Air (1839688)..... <b>PA30000</b>	
Transit Connect 1.0 w/C10FD0X Eng. (2013-on) Lube (9W7E6714AA)..... <b>BT223</b> Radial Seal Air (1848220)..... <b>RS4450</b>	Transit Custom 2.0 TDCi 16V Eco Blue w/YNFS Eng. (12/15-on) Cabin Air (1812679)..... <b>PA30000</b>	
	Transit Custom 2.0 TDCi 16V Eco Blue w/YMFS Eng. (12/15-on) Cabin Air (1812679)..... <b>PA30000</b>	

\* See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).


FORD Gas Engines (cont'd)	FORD Gas Engines (cont'd)	FORD Gas Engines (cont'd)
240 6 Cyl. (Cont'd)	292 V8	317 V8
Air (1969-74, (F Series)) (C8TZ-9601-A)..... PA2005	Lube Ele. (1958-63)..... P80	Lube..... P80
250 6 Cyl.	Lube Ele. (1958-63)..... P80-HD	Lube..... P80-HD
Lube..... B2 +	Lube Ele. (1963-64)..... P184	Opt. Fuel (B6T-9365-A)..... PF827
In-Line Fuel (Carb.)..... BF879	Lube Spin-on..... B2 +	330 V8
Air (1970-74)..... PA1802	1 1/32 In. Fuel (1958-64, (2 Bbl.)) ..... PF857	Opt. F-F Lube Ele. (1964-74)..... P80
254 6 Cyl.	1 7/8 In. Fuel (1958-60, 1964)..... PF859	Opt. F-F Lube Ele. (1964-74)..... P80-HD
Lube..... P41	3 15/32 In. Fuel (1958-64, (4 Bbl.))..... PF827	B-P Lube Ele. (1964-76)..... C704-L +
255 V8	3 11/16 In. Air (1959-64)..... PA602	Lube Spin-on (U.S. Thread)..... B2 +
Lube..... B2 +	7 7/32 In. Air (1959)..... PA651	Lube Spin-on (1997-on)..... B329
Screw-in Fuel (1981)..... BF920	300 6 Cyl.	Fuel Ele..... PF827
Screw-in Fuel (1982 (Exc. Calif.)) ..... BF920	Lube..... B2 +	In-Line Fuel (To 2000 (Trucks))... BF1166
Air..... PA2051	Fuel Ele. (1966-72)..... PF827	In-Line Fuel (2000-on (Trucks))... BF7668 +
256 V6	In-Line Fuel (1966-77, (Carb.))... BF879	In-Line Fuel (To 2003 (Vans))... BF1166
Lube..... B243	Screw-in Fuel (1978-81, (Carb.))... BF995	In-Line Fuel (2003-on (Vans))... BF7668 +
Fuel (1999-on (Trucks))... BF7668 +	In-Line Fuel (1980-81)..... BF989	Air (1964-69, (700, 800 Series))... PA2412
Fuel (To 1999 (Trucks))... BF1166	Screw-in Fuel (1982-86, (Carb.))... BF920	Air (1970-76, (800 Series))... PA2379-K
Fuel (2000-on (Vans))... BF7668 +	Fuel (1987-on)..... BF966	Axial Seal Air (1976-on, (500 Series))... PA2472
Fuel (To 2000 (Vans))... BF1166	Air (1970-79, (F Series))... PA2005	Heavy Duty Air (1976-on, (500 Series))... PA2483
Air..... PA4075	Axial Seal Air (1973-86, (E Series))... PA657	Air (1997-on)..... PA4075
256 V8	Axial Seal Air (1980-81, (F Series))... PA657	330 V8 Natural Gas
Lube (1954-55)..... P80	Heavy Duty Air (1980-86, (E Series))... PA2107	Lube..... B329
Lube (1954-55)..... P80-HD	Heavy Duty Air (1980-81, (F Series))... PA2107	Air..... PA4075
260 V8	Axial Seal Air (1982-86, (F Series))... PA1802	332 V8
Lube..... B2 +	Air (1987-on)..... PA2164	Lube..... P80
Fuel..... PF827	302 V8 (Except FI)	Lube..... P80-HD
Air..... PA642	Lube Ele. (1956-64)..... P80	Opt. Fuel (1956-64) (B6T-9365-A)..... PF827
262 6 Cyl.	Lube Ele. (1956-64)..... P80-HD	Air (1957-58)..... PA651
Lube (1961-64)..... P80	Opt. Lube Ele. (1968-73)..... B2 +	Air (1961-63)..... PA2412
Lube (1961-64)..... P80-HD	Lube Spin-on..... B2 +	351 V8
Fuel Ele. (1961-63) (C2AZ-9155-A)..... PF827	Fuel Ele. (1956-64, 1968-72)..... PF827	Lube..... B2 +
272 V8	In-Line Fuel (1968-76, (Carb.))... BF879	In-Line Fuel (w/o Ram) 1969-76, (Carb.)..... BF879
Lube..... P80	Fuel (1977-79)..... BF995	Fuel (1977-78)..... BF995
Lube..... P80-HD	Fuel (1980)..... BF989	Fuel (1980)..... BF989
Fuel (500, 600, 700 Series)..... PF827	Screw-in Fuel (1981-on, (Exc. Calif.))..... BF920	Std. Screw-in Fuel (1981-87)..... BF920
Other Fuel..... PF857	Air (1968-79, (Bronco))..... PA657	Fuel (1988-on)..... BF966
Axial Seal Air..... PA602	Air (1968-73, (Econoline))..... PA657	Air (1969-71)..... PA2002
Opt. Air (B8Q-9601-A)..... PA651	Air (1970-71, (Ranchero))... PA2002	Air (w/Ram Air) 1972, (CJ 4 Bbl.)... PA1828
281 V8	Air (1970-73, (Other F Series))... PA2002	Air (w/o Ram Air) 1972, (CJ 4 Bbl.)..... PA2002
Lube..... B329	Air (1972-79, (Ranchero, F100 Ranger))... PA2051	Air (1972-76, (Ranchero 2 Bbl.))... PA2051
Fuel (To 2000 (Trucks))... BF1166	Air (1978-79, (Other F Series))... PA2005	Air (1973-76, (Ranchero 4 Bbl.))... PA2024
Fuel (2000-on (Trucks))... BF7668 +	Axial Seal Air (1980-on)..... PA2051	Air (1975-76, (E Series))... PA2051
Fuel (To 2003 (Vans))... BF1166	302 V8 FI	Air (Exc. HvyDty.) 1977-83... PA2051
Fuel (2003-on (Vans))... BF7668 +	Lube..... B2 +	Air (2 Bbl. Exc. HvyDty.) 1984-on... PA2051
Air..... PA4075	Fuel (1987-on)..... BF966	Air (4 Bbl.) 1984-87... PA2002
289 V8	Air (1985-86)..... PA2152	Air (FI) 1987 (GVW 8500 lbs. & up)..... PA2002
Lube..... B2 +	Air (1987-on)..... PA2164	Air (1988-on, (FI))..... PA2164
Fuel (1963-65)..... PF827		352 V8
In-Line Fuel (1966-68, (Carb.))... BF879		Lube Ele. (1965-67)..... P80
Air (Exc. Sedan Delivery) 1963-67..... PA657		Lube Ele. (1965-67)..... P80-HD
Air (Exc. Sedan Delivery) 1968... PA2002		Lube Spin-on..... B2 +
		Fuel (1965-67)..... PF827

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FORD Gas Engines (cont'd)	FORD Gas Engines (cont'd)	FORD Gas Engines (cont'd)
352 V8 (Cont'd) Air (1957-58, (Ranchero))..... PA602	400 V8 Lube..... B2 + In-Line Fuel (1972-77, (Carb.)).... BF879 In-Line Fuel (1977-80)..... BF989 Screw-in Fuel (1978-80, (Carb.)).. BF995 Screw-in Fuel (1981-82, (Carb.)).. BF920 Air (1972, (Ranchero))..... PA2002 Air (1973-74, (Ranchero))..... PA2024 Air (1975-76, (Ranchero))..... PA2051 Air (1977-on)..... PA2051	475 V8 (Cont'd) Opt. Air (1974-76) (D4HZ-9601-B)..... PA2483 Opt. Air (1974-78) (E1HZ-9601-A)..... PA2472
359 V8 Lube Ele. (1974)..... P80 Lube Ele. (1974)..... P80-HD Lube Spin-on..... BT251 In-Line Fuel (1974-76)..... BF840 + Air (1974-76)..... PA2379-K	401 V8 Lube Ele..... P47 Lube Spin-on..... B2 + Fuel Ele. (1958-77)..... PF821-S Fuel Spin-on (1973-77)..... BF585 Air (1958-60)..... PA654 Air (1961-69)..... PA2412 Air (1970-77) (D2HZ-9601-C)..... PA2379-K Air (1976) (D6HZ-9601-A)..... PA2585	477 V8 Lube Ele..... P47 Lube Spin-on..... B2 + Fuel Ele..... PF821-S Fuel Spin-on..... BF585 10 7/32 In. O.D. Air (1958-60)..... PA1619 12 1/4 In. O.D. Air (1958-60)..... PA654 Air (1961-69, (After Conversion)).. PA2412 Air (1970-75, (Exc. C900, CT900))..... PA2379-K Air (1972-77, (C900, CT900)) (D2HZ-9601-A)..... PA2412 Opt. Air (1976-77) (D6HZ-9601-A)..... PA2585 Air (E1HZ-9601-A)..... PA2472 Air (E1HZ-9601-B)..... PA2483 Oil Filler Tube Breather (1958-63)..... [2] PA633(2) <sup>90</sup>
360 V8 Opt. Lube Ele. (1969-74)..... P184 Lube Spin-on..... B2 + Fuel Ele. (1969-76)..... PF827 In-Line Fuel (1973-76, (Carb.)).... BF879 Air (1968-76)..... PA2002	415 V10 Lube..... B329 Fuel (Trucks)..... BF1166 Fuel (To 2003 (Vans))..... BF1166 Fuel (2003-on (Vans))..... BF7668 + Air..... PA4075	534 V8 Lube Ele..... P47 Lube Spin-on..... B2 + Fuel Ele..... PF821-S Fuel Spin-on..... BF585 10 7/32 In. O.D. Air (1958-60)..... PA1619 12 1/4 In. O.D. Air (1958-60)..... PA654 Air (1970-74, (Exc. C900, CT900))..... PA2379-K Air (1973-74, (C900, CT900))..... PA2412 Air (1978-on) (E1HZ-9601-B)..... PA2483 Air (E1HZ-9601-A)..... PA2472 Oil Filler Tube Breather (1958-63)..... [2] PA633(2) <sup>90</sup>
361 V8 (5.9L) F-F Lube Ele. (1964-74)..... P80 F-F Lube Ele. (1964-74)..... P80-HD B-P Lube Ele. (1970-76)..... C704-L + 7 1/8 In. Lube Spin-on..... BT251 Fuel (1964-76)..... PF827 Air (1964-69)..... PA2412 Air (1970-76)..... PA2379-K	428 V8 Cobra Jet Lube Spin-on..... B2 + Air..... PA1828	
370 V8 Lube..... BT251 Fuel Ele..... PF827 Fuel Spin-on (1986-87)..... BF790 Heavy Duty Air (1979-on) (D4HZ-9601-B)..... PA2483 Air (1980-82) (E1HZ-9601-A)..... PA2472 Air (1983-on) (E0HZ-9601-A)..... PA2596	429 V8 7.0L Lube (To 1973)..... B2 + Lube (1979-on)..... BT251 In-Line Fuel (1971-73, (Carb.)).... BF879 Fuel Ele. (1979-on)..... PF827 Fuel Spin-on (1986-87)..... BF790 2 1/4 In. Air (1971, (GPD Carb.)).. PA1828 2 1/2 In. Air (1971, (Ram Air))..... PA2024 2 3/4 In. Air (1971, (Rochester Carb.))..... PA2002 Heavy Duty Air (1979-on) (D4HZ-9601-B)..... PA2483 Air (1980-82) (E1HZ-9601-A)..... PA2472 Air (1983-on) (E0HZ-9601-A)..... PA2596	
389 V8 F-F Lube Ele. (1964-74)..... P80 F-F Lube Ele. (1964-74)..... P80-HD B-P Lube Ele. (1970-76)..... C704-L + 7 1/8 In. Lube Spin-on..... BT251 Fuel (1964-76)..... PF827 Air (1964-69)..... PA2412 Air (1970-76)..... PA2379-K	460 V8 Lube..... B2 + Fuel Ele. (1973-76)..... PF827 In-Line Fuel (1973-76, (Carb.)).... BF879 Fuel (1979-86)..... SF898 Fuel (1988-on)..... BF966 Air (1973-87, (F Series))..... PA2002 Air (1973-on, (Ranchero))..... PA2024 Air (1975-87, (Econoline))..... PA2002	
390 V8 Opt. Lube Ele. (1967-71)..... P184 Lube Spin-on..... B2 + Fuel Ele. (1967-71)..... PF827 In-Line Fuel (1967-76, (Carb.)).... BF879 Air (1967, (Ranchero))..... PA1735 Air (1969, (Ranchero))..... PA1828 Air (1973-76 (Exc. Ranchero))..... PA2002	475 V8 Lube Ele..... P47 Lube Spin-on..... B2 + Fuel Ele..... PF821-S Fuel Spin-on..... BF585 Opt. Air (1973-76) (D2HZ-9601-C)..... PA2379-K	
391 V8 6.4L F-F Lube Ele. (1964-74)..... P80 B-P Lube Ele. (1970-77)..... C704-L + F-F Lube Ele. (1964-74)..... P80-HD 5 9/32 In. Lube Spin-on (1964-72)..... B2 + 7 1/8 In. Lube Spin-on..... BT251 Fuel Ele. (1964-77)..... PF827 Air (1964-69)..... PA2412 Air (1970-77)..... PA2379-K		

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)
500, 550, 600, 700, 750, 800 Series w/V8-330 Eng. Lube Ele. (1964-74)..... P80 Lube Ele. (1964-74)..... P80-HD Lube Spin-on (1964-on)..... B2+ Fuel Ele..... PF827 Air (1964-69, (700, 800 Series))... PA2412 Air (1976-77, (500 Series))..... PA2472 Air (1970-76, (800 Series))..... PA2379-K Heavy Duty Air (1976-77, (500 Series))..... PA2483	700, 750, 800 Series w/V8-391 Eng. F-F Lube Ele. (1964-74)..... P80 F-F Lube Ele. (1964-74)..... P80-HD B-P Lube (1970-77)..... C704-L + 5 9/32 In. Lube Spin-on..... B2+ 7 1/8 In. Lube Spin-on..... BT251 Fuel (1964-77)..... PF827 Air (1964-69)..... PA2412 Air (1970-77)..... PA2379-K 700, 750, 800, 900 Series w/V8-332 Eng. Lube Ele. (1956-64)..... P80 Lube Ele. (1956-64)..... P80-HD Fuel (1963) (C2AZ-9155-A)..... PF827 7 7/32 In. Air (1957-58)..... PA651 10 7/16 In. Air (1961-63)..... PA2412 700, 800, 900 Series w/6 Cyl. (7.8L) Diesel Eng. Lube..... [2] B157 Fuel/Water Separator (E7HZ-9N184-A)..... BF1204 Fuel/Water Separator (w/o Drain or Sensor Port) (F1HZ9365A)..... BF1224 Fuel/Water Separator (w/Drain) (F1HZ9365A)..... BF1223 Fuel/Water Separator (w/Drain & Sensor Port) (F1HZ9365A)..... BF1223-SP Fuel/Water Separator (Open End for Bowl) (F1HZ9365A)..... BF1223-O Fuel Spin-on..... [2] BF7608 Air (16 1/2 In.) (E6HZ-9601-A)..... PA2523 Air (23 1/2 In.) (E7HZ-9601-A)..... PA2726	800, 900 Series w/V8-429 Eng. Lube (B7A6714A)..... B2+ Lube (D2NN6714C)..... BT251 In-Line Fuel..... BF879 Fuel Ele..... PF827 Air (8 1/16 In.) (D6HZ-9601-B)..... PA2548 Air (13 7/8 In.) (F1HZ-9601-C)..... PA3475 800, 900 Series w/V8-534 Eng. Lube Ele..... P47 Lube Spin-on..... B2+ Fuel Ele..... PF821-S Fuel Spin-on..... BF585 Air (1958-60) (C0TE-9601-A)..... PA654 Air (1978-on) (D4HZ-9601-B)..... PA2483 Opt. Air (5 1/2 In.) (E1HZ-9601-A)..... PA2472 Opt. Air (8 1/16 In.) (D6HZ-9601-B)..... PA2548 Opt. Air (9 7/16 In.) (D2HZ-9601-C)..... PA2379-K Opt. Air (10 7/16 In.) (D2HZ-9601-A)..... PA2412 Oil Filler Tube Breather..... PA633(2) <sup>90</sup> 850, 900, 950 Series w/V8-401 Eng. Lube Ele..... P47 Lube Spin-on..... B2+ Fuel Ele. (1958-77)..... PF821-S Fuel Spin-on (1973-77)..... BF585 Air (1958-60)..... PA654 Air (1961-69)..... PA2412 Air (1970-77) (D2HZ-9601-C)..... PA2379-K Opt. Air (1976) (D6HZ-9601-A)..... PA2585 6000, 7000 Series w/6-220 Diesel Eng. Lube..... P15 6000, 7000 Series w/6-242, 6-300 Diesel Eng. Lube (1963-on)..... P15 6000, 7000 Series w/6-363 Diesel Eng. Lube (1967-on)..... PT12 6000, 7000, 8000 Series w/GMC 8.2L Diesel Eng. Lube..... [2] B6+ P. Fuel Spin-on..... BF592+ S. Fuel Spin-on..... BF593 Air (E0HZ-9601-B)..... PA2599 Air (Don. P140558)..... PA2596 A9513 w/Cat 3176 (10.3L) Eng. F-F Lube (Std. Efficiency) (1R0716)..... B99+ F-F Eng. Lube (High Efficiency Vers.) (1R1808)..... B7299+ Opt. B-P Lube (1W8845)..... B7577 Fuel/Water Separator Ele. (8N0205)..... PF316 Fuel/Water Separator Spin-on (Fleetguard FS1000)..... BF1259 P. Fuel Ele. (9M2342)..... [2] PF935 P. Fuel Spin-on (1R0740)..... BF970+ P. Fuel Spin-on (1R0749)..... BF7587+
600, 700 Series w/6-401 (6.6L) Eng. Lube (D8NN6714DA)..... BT343 Lube (E7HZ6731A)..... [2] B157 Fuel/Water Separator (w/o Drain or Sensor Port) (F1HZ9365A)..... BF1224 Fuel/Water Separator (w/Drain) (F1HZ9365A)..... BF1223 Fuel/Water Separator (w/Drain & Sensor Port) (F1HZ9365A)..... BF1223-SP Fuel/Water Separator (Open End for Bowl) (F1HZ9365A)..... BF1223-O Fuel Spin-on..... [2] BF7608 Air (16 1/2 In.) (E6HZ-9601-A)..... PA2523 Air (23 1/2 In.) (E7HZ-9601-A)..... PA2726	Air (16 In.) (D5HZ-9601-D)..... PA2425+ Air (23 1/2 In.) (E7HZ-9601-A)..... PA2726 Coolant (E7HZ-8A424-B)..... BW5136 800, 880, 900 Series w/V8-475 Eng. Lube Ele..... P47 Lube Spin-on..... B2+ Fuel Ele..... PF821-S Fuel Spin-on..... BF585 Air (1974-78, (F880)) (E1HZ-9601-A)..... PA2472 Opt. Air (D2HZ-9601-C)..... PA2379-K Opt. Air (D4HZ-9601-B)..... PA2483 Opt. Air (D6HZ-9601-B)..... PA2548 800, 880, 900 Series w/V8-477 Eng. Lube Ele..... P47 Lube Spin-on..... B2+ Fuel Ele..... PF821-S Fuel Spin-on..... BF585 Air (1958-60) (C0TE-9601-A)..... PA654 Opt. Air (D2HZ-9601-A)..... PA2412 Opt. Air (D2HZ-9601-C)..... PA2379-K Opt. Air (D6HZ-9601-A)..... PA2585 Opt. Air (D6HZ-9601-B)..... PA2548 Opt. Air (E1HZ-9601-A)..... PA2472 Opt. Air (E1HZ-9601-B)..... PA2483 Oil Filler Tube Breather..... [2] PA633(2) <sup>90</sup>	600 Series, 700 Series, 800 Series w/Ford 6.1L Eng. Lube (Motorcraft FL1995)..... B7039 Fuel (Motorcraft FG789)..... PF827 600, 700, 800 Series w/Detroit Diesel 8.2L Eng. Lube..... [2] B6+ P. Fuel..... BF592+ S. Fuel..... BF593 Air (6 23/32 In. I.D.) (E0HZ-9601-B)..... PA2599 Air (8 9/32 In. I.D.) (E1HZ-9601-B)..... PA2483 Air (8 11/16 In. I.D.) (E0HZ-9601-A)..... PA2596 600, 700, 800 Series w/V8-429 (7.0L) Eng. Lube..... BT251 Fuel Ele..... PF827 Fuel Spin-on..... BF790 Air (E1HZ-9601-A)..... PA2472 Heavy Duty Air (D4HZ-9601-B)..... PA2483 Air (E0HZ-9601-A)..... PA2596 Air (F1HZ-9601-C)..... PA3475 Air (w/Air Restriction Gauge Fitting) (D6HZ-9601-B)..... PA2548

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.


Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)
A9513 w/Cat 3176 (10.3L) Eng. (Cont'd)	A9513 w/Cat 3406 (14.6L) Eng. (Cont'd)	A9513 w/Cat C12 (12.0L) Eng. (Cont'd)
S. Fuel Spin-on (1R0750)..... <b>BF7633 +</b>	Trans. Spin-on (Fuller 4304827).. <b>BT223</b>	Air Dryer (Bendix 5008414)..... <b>BA5374 +</b>
Air Dryer (Bendix 5008414)..... <b>BA5374 +</b>	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	Air Dryer (Wabco R950068)..... <b>BA5379 +</b>
Air Dryer (Wabco R950068)..... <b>BA5379 +</b>	A9513 w/Cat C10 (10.3L) Eng.	Coolant (w/4 Units BTE) (9N3368)..... <b>BW5137</b>
Coolant (w/8 Units BTE) (9N6123)..... <b>BW5139</b>	F-F Lube (Std. Version) (1R0716)..... <b>B99 +</b>	Coolant (w/8 Units BTE) (9N3366)..... <b>BW5139</b>
Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	F-F Lube (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b>	Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	B-P Lube (1W8845)..... <b>B7577</b>	Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
Trans. Spin-on (Fuller 4304827).. <b>BT223</b>	Fuel/Water Separator Ele. (8N0205)..... <b>PF316</b>	Trans. Spin-on (Fuller 4304827).. <b>BT223</b>
Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	Fuel/Water Separator Spin-on (Open End for Bowl) (Alliance ABPN122R50421)..... <b>BF1395-O</b>	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>
A9513 w/Cat 3306 (10.5L) Eng.	Fuel/Water Separator Spin-on (w/Sensor Port) (Alliance ABPN122R50421)..... <b>BF1395-SP</b>	A9513 w/Cummins M11 (10.8L) Eng.
Lube Ele. (w/Paper Wrapper) (1R0659)..... <b>PT670</b>	Fuel/Water Separator Spin-on (w/Drain) (Alliance ABPN122R50421)..... <b>BF1265</b>	Dual-Flow Lube (3318853)..... <b>BD103 +</b>
Lube Ele. (w/Metal Wrapper) (1R0659)..... <b>PT7332</b>	Fuel/Water Separator Spin-on (Fleetguard FS1000)..... <b>BF1259</b>	Fuel/Water Separator Ele. (Fleetguard FS1029W)..... <b>PF7680</b>
F-F Lube Spin-on (1R0716)..... <b>B99 +</b>	Fuel (Standard Vers.) (1R1712).. <b>BF614 +</b>	Fuel/Water Separator Spin-on (3329289)..... <b>BF1259</b>
F-F Lube Spin-on (Standard Vers.) (1R0739)..... <b>B76 +</b>	Fuel (High Efficiency Vers.) (1R0749)..... <b>BF7587 +</b>	Air Dryer (Bendix 5008414)..... <b>BA5374 +</b>
F-F Lube Spin-on (Severe Service) (1R0739)..... <b>B76-SS +</b>	Air Dryer (Bendix 5008414)..... <b>BA5374 +</b>	Air Dryer (Wabco R950068)..... <b>BA5379 +</b>
Fuel/Water Separator Ele. (8N0205)..... <b>PF316</b>	Air Dryer (Wabco R950068)..... <b>BA5379 +</b>	Coolant (w/4 Units BTA+) (3315116)..... <b>BW5071</b>
Box-Style Glass Fuel/Water Separator (6N7617)..... <b>BF912</b>	Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	Coolant (w/15 Units BTA+) (3318318)..... <b>BW5075</b>
Fuel/Water Separator Spin-on (Fleetguard FS1000)..... <b>BF1259</b>	Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
P. Fuel Ele. (9M2341)..... <b>PF935</b>	Trans. Spin-on (Fuller 4304827).. <b>BT223</b>	Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
P. Fuel Spin-on (1R0740)..... <b>BF970 +</b>	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	Trans. Spin-on (Fuller 4304827).. <b>BT223</b>
S. Fuel Spin-on (1R0750)..... <b>BF7633 +</b>	A9513 w/Cat C12 (12.0L) Eng.	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>
Air Dryer (Bendix 5008414)..... <b>BA5374 +</b>	F-F Lube (Std. Version) (1R0716)..... <b>B99 +</b>	A9513 w/Cummins N14 (14.0L) Eng.
Air Dryer (Wabco R950068)..... <b>BA5379 +</b>	F-F Lube (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b>	F-F Lube (Fleetguard LF670SC).. <b>B196 +</b>
Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	B-P Lube (1W8845)..... <b>B7577</b>	Dual-Flow Lube (3318853)..... <b>BD103 +</b>
Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Fuel/Water Separator Ele. (8N0205)..... <b>PF316</b>	B-P Lube (3304232)..... <b>B7577</b>
Trans. Spin-on (Fuller 4304827).. <b>BT223</b>	Fuel/Water Separator Spin-on (Open End for Bowl) (Alliance ABPN122R50421)..... <b>BF1395-O</b>	Fuel/Water Separator Spin-on (3329289)..... <b>BF1259</b>
Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	Fuel/Water Separator Spin-on (w/Sensor Port) (Alliance ABPN122R50421)..... <b>BF1395-SP</b>	Fuel/Water Separator Spin-on (3406889)..... <b>BF1293-SPS</b>
A9513 w/Cat 3406 (14.6L) Eng.	Fuel/Water Separator Spin-on (w/Drain) (Alliance ABPN122R50421)..... <b>BF1265</b>	Fuel (154789)..... <b>BF957-D +</b>
F-F Lube (Std. Efficiency) (1R0716)..... <b>B99 +</b>	Fuel/Water Separator Spin-on (Fleetguard FS1000)..... <b>BF1259</b>	Air Dryer (Bendix 5008414)..... <b>BA5374 +</b>
F-F Eng. Lube (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b>	P. Fuel Ele. (9M2342)..... <b>[2] PF935</b>	Air Dryer (Wabco R950068)..... <b>BA5379 +</b>
Fuel/Water Separator Spin-on (Fleetguard FS1000)..... <b>BF1259</b>	Fuel Spin-on (Standard Vers.) (1R1712)..... <b>BF614 +</b>	Coolant (3315116)..... <b>BW5071</b>
P. Fuel Spin-on (1R0749)..... <b>BF7587 +</b>	Fuel Spin-on (High Efficiency Vers.) (1R0749)..... <b>BF7587 +</b>	Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
Air Dryer (Bendix 5008414)..... <b>BA5374 +</b>		Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
Air Dryer (Wabco R950068)..... <b>BA5379 +</b>		Trans. Spin-on (Fuller 4304827).. <b>BT223</b>
Coolant (w/4 Units BTE) (9N3368)..... <b>BW5137</b>		Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>
Coolant (w/8 Units BTE) (9N3366)..... <b>BW5139</b>		A9513 w/Detroit Diesel Series 60 (11.1L) or (12.7L) Eng.
Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>		F-F Lube (23518480)..... <b>[2] B495</b>
Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>		Fuel/Water Separator (w/Drain) (23512317)..... <b>BF5813 +</b>
		Fuel/Water Separator (Open End for Bowl) (23512317)..... <b>BF5813-O +</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)
A9513 w/Detroit Diesel Series 60 (11.1L) or (12.7L) Eng. (Cont'd)	AT9513 w/Cat 3126 (7.2L) Eng. (Cont'd)	AT9513 w/Cat 3406 (14.6L) Eng. (Cont'd)
<b>Opt. Fuel/Water Separator</b> (23516189)..... <b>BF5812</b>	<b>Trans.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	<b>P. Fuel Spin-on</b> (1R0749)..... <b>BF7587 +</b>
<b>Opt. Fuel/Water Separator</b> (Alliance ABPN122R50407)..... <b>BF1283-SP +</b>	AT9513 w/Cat 3176 (10.3L) Eng.	<b>Coolant</b> (w/4 Units BTE) (9N3368)..... <b>BW5137</b>
<b>P. Fuel</b> (25014274)..... <b>BF5800 +</b>	<b>F-F Lube</b> (Std. Efficiency) (1R0716)..... <b>B99 +</b>	<b>Coolant</b> (w/8 Units BTE) (9N3366)..... <b>BW5139</b>
<b>S. Fuel</b> (23518482)..... <b>BF5810</b>	<b>F-F Eng. Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b>	<b>Opt. B-P Lube</b> (1W8845)..... <b>B7577</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Air Dryer</b> (Wabco R950068)..... <b>BA5379 +</b>	<b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1000)..... <b>BF1259</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>P. Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b>	AT9513 w/Cat C10 (10.3L) Eng.
<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>P. Fuel Spin-on</b> (1R0740)..... <b>BF970 +</b>	<b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99 +</b>
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>P. Fuel Spin-on</b> (1R0749)..... <b>BF7587 +</b>	<b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b>
A9522 w/Cat C10 (10.3L) Eng.	<b>S. Fuel Spin-on</b> (1R0750)..... <b>BF7633 +</b>	<b>B-P Lube</b> (1W8845)..... <b>B7577</b>
<b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99 +</b>	<b>Coolant</b> (w/8 Units BTA+) (9N6123)..... <b>BW5073</b>	<b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b>
<b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Alliance ABPN122R50421)..... <b>BF1395-O</b>
<b>B-P Lube</b> (1W8845)..... <b>B7577</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (Alliance ABPN122R50421)..... <b>BF1395-SP</b>
<b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>Fuel/Water Separator Spin-on</b> (w/Drain) (Alliance ABPN122R50421)..... <b>BF1265</b>
<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Alliance ABPN122R50421)..... <b>BF1395-O</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1000)..... <b>BF1259</b>
<b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (Alliance ABPN122R50421)..... <b>BF1395-SP</b>	AT9513 w/Cat 3306 (10.5L) Eng.	<b>Fuel/Water Separator Spin-on</b> (w/Drain) (Alliance ABPN122R50421)..... <b>BF1265</b>
<b>Fuel/Water Separator Spin-on</b> (w/Drain) (Alliance ABPN122R50421)..... <b>BF1265</b>	<b>Lube Ele.</b> (w/Paper Wrapper) (1R0659)..... <b>PT670</b>	<b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1000)..... <b>BF1259</b>
<b>Fuel/Water Separator Spin-on</b> (Alliance ABPN122R50421)..... <b>BF1395-SP</b>	<b>Lube Ele.</b> (w/Metal Wrapper) (1R0659)..... <b>PT7332</b>	<b>Fuel/Water Separator Spin-on</b> (w/Drain) (Alliance ABPN122R50421)..... <b>BF1265</b>
<b>Fuel/Water Separator Spin-on</b> (w/Drain) (Alliance ABPN122R50421)..... <b>BF1265</b>	<b>F-F Lube Spin-on</b> (1R0716)..... <b>B99 +</b>	<b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1000)..... <b>BF1259</b>
<b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1000)..... <b>BF1259</b>	<b>F-F Lube Spin-on</b> (Standard Vers.) (1R0739)..... <b>B76 +</b>	<b>Fuel/Water Separator Spin-on</b> (w/Drain) (Alliance ABPN122R50421)..... <b>BF1265</b>
<b>Fuel</b> (Standard Vers.) (1R1712).. <b>BF614 +</b>	<b>F-F Lube Spin-on</b> (Severe Service) (1R0739)..... <b>B76-SS +</b>	<b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1000)..... <b>BF1259</b>
<b>Fuel</b> (High Efficiency Vers.) (1R0749)..... <b>BF7587 +</b>	<b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b>	<b>P. Fuel Ele.</b> (9M2341)..... <b>PF935</b>
A9522 w/Detroit Diesel Series 60 (12.7L) Eng.	<b>Box-Style Glass Fuel/Water Separator</b> (6N7617)..... <b>BF912</b>	<b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1000)..... <b>BF1259</b>
<b>F-F Lube</b> (23518480)..... <b>[2] B495</b>	<b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1000)..... <b>BF1259</b>	<b>P. Fuel Spin-on</b> (1R0740)..... <b>BF970 +</b>
<b>Fuel/Water Separator</b> (w/Drain) (23512317)..... <b>BF5813 +</b>	<b>P. Fuel Spin-on</b> (1R0740)..... <b>BF970 +</b>	<b>S. Fuel Spin-on</b> (1R0750)..... <b>BF7633 +</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (23512317)..... <b>BF5813-O +</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Opt. Fuel/Water Separator</b> (23516189)..... <b>BF5812</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Opt. Fuel/Water Separator</b> (Alliance ABPN122R50407)..... <b>BF1283-SP +</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>
<b>P. Fuel</b> (25014274)..... <b>BF5800 +</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
<b>S. Fuel</b> (23518482)..... <b>BF5810</b>	AT9513 w/Cat 3126 (7.2L) Eng.	AT9513 w/Cat C12 (12.0L) Eng.
AT9513 w/Cat 3126 (7.2L) Eng.	<b>Lube</b> (1R-1807)..... <b>B7700 +</b>	<b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99 +</b>
<b>F-F Lube</b> (1R-0751)..... <b>BF7632</b>	<b>Fuel</b> (1R-0751)..... <b>BF7632</b>	<b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b>
<b>Radial Seal Air</b> (F6HZ9601AB).... <b>RS3548</b>	<b>Radial Seal Air</b> (F6HZ9601AB).... <b>RS3548</b>	<b>B-P Lube</b> (1W8845)..... <b>B7577</b>
<b>Radial Seal XP Air</b> (F6HZ9601AB)..... <b>RS3548XP</b>	<b>Trans.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	<b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b>
<b>Trans.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	AT9513 w/Cat 3406 (14.6L) Eng.	<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Alliance ABPN122R50421)..... <b>BF1395-O</b>
AT9513 w/Cat 3126 (7.2L) Eng.	<b>F-F Lube</b> (Std. Efficiency) (1R0716)..... <b>B99 +</b>	<b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (Alliance ABPN122R50421)..... <b>BF1395-SP</b>
<b>Lube</b> (1R-1807)..... <b>B7700 +</b>	<b>F-F Eng. Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b>	
<b>Fuel</b> (1R-0751)..... <b>BF7632</b>	<b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1000)..... <b>BF1259</b>	
<b>Radial Seal Air</b> (F6HZ9601AB).... <b>RS3548</b>		
<b>Radial Seal XP Air</b> (F6HZ9601AB)..... <b>RS3548XP</b>		
<b>Trans.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)
AT9513 w/Cat C12 (12.0L) Eng. (Cont'd)	AT9513 w/Detroit Diesel Series 60 (11.1L) or (12.7L) Eng.	AT9522 w/Cat C10 (10.3L) Eng. (Cont'd)
<b>Fuel/Water Separator Spin-on</b> (w/Drain) (Alliance ABPN122R50421).....	<b>F-F Lube</b> (23518480)..... [2] B495	<b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1000).....
BF1265	<b>Fuel/Water Separator</b> (w/Drain) (23512317).....	BF1259
<b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1000).....	BF5813 +	<b>Fuel</b> (Standard Vers.) (1R1712)...
BF1259	<b>Fuel/Water Separator</b> (Open End for Bowl) (23512317).....	BF614 +
<b>P. Fuel Ele.</b> (9M2342)..... [2] PF935	BF5813-O +	<b>Fuel</b> (High Efficiency Vers.) (1R0749).....
<b>Fuel Spin-on</b> (Standard Vers.) (1R1712).....	BF5812	BF7587 +
BF614 +	<b>Opt. Fuel/Water Separator</b> (Alliance ABPN122R50407).....	<b>Air Dryer</b> (Bendix 5008414).....
<b>Fuel Spin-on</b> (High Efficiency Vers.) (1R0749).....	BF1283-SP +	BA5374 +
BF7587 +	<b>P. Fuel</b> (25014274).....	BA5379 +
<b>Coolant</b> (w/4 Units BTE) (9N3368).....	BF5800 +	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493).....
BW5137	BF5810	PT9416-MPG KIT
<b>Coolant</b> (w/8 Units BTE) (9N3366).....	PT9416-MPG KIT	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494).....
BW5139	PT9415-MPG KIT	PT9415-MPG KIT
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493).....	BT223	<b>Trans. Spin-on</b> (Fuller 4304827)..
PT9416-MPG KIT	BT223	BT223
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494).....	<b>Opt. Trans. Spin-on</b> (Fuller 17237).....	<b>Opt. Trans. Spin-on</b> (Fuller 17237).....
PT9415-MPG KIT	B2 +	B2 +
<b>Trans. Spin-on</b> (Fuller 4304827)..	AT9522 w/Cat 3406 (14.6L) Eng.	AT9522 w/Cat C12 (12.0L) Eng.
BT223	<b>F-F Lube</b> (Std. Efficiency) (1R0716).....	<b>F-F Lube</b> (Std. Version) (1R0716).....
<b>Opt. Trans. Spin-on</b> (Fuller 17237).....	B99 +	B99 +
B2 +	<b>F-F Eng. Lube</b> (High Efficiency Vers.) (1R1808).....	<b>F-F Lube</b> (High Efficiency Vers.) (1R1808).....
AT9513 w/Cummins M11 (10.8L) Eng.	B7299 +	B7299 +
<b>Dual-Flow Lube</b> (3318853).....	<b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1000).....	<b>B-P Lube</b> (1W8845).....
BD103 +	BF1259	B7577
<b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W).....	<b>P. Fuel Spin-on</b> (1R0749).....	<b>Fuel/Water Separator Ele.</b> (8N0205).....
PF7680	BF7587 +	PF316
<b>Fuel/Water Separator Spin-on</b> (3329289).....	BA5374 +	<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Alliance ABPN122R50421).....
BF1259	BA5379 +	BF1395-O
<b>Coolant</b> (w/4 Units BTA+) (3315116).....	BW5137	<b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (Alliance ABPN122R50421).....
BW5071	BW5139	BF1395-SP
<b>Coolant</b> (w/15 Units BTA+) (3318318).....	PT9416-MPG KIT	<b>Fuel/Water Separator Spin-on</b> (w/Drain) (Alliance ABPN122R50421).....
BW5075	PT9415-MPG KIT	BF1265
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493).....	PT9416-MPG KIT	<b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1000).....
PT9416-MPG KIT	PT9415-MPG KIT	BF1259
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494).....	PT9415-MPG KIT	<b>P. Fuel Ele.</b> (9M2342).....
PT9415-MPG KIT	BT223	[2] PF935
<b>Trans. Spin-on</b> (Fuller 4304827)..	BT223	<b>Fuel Spin-on</b> (Standard Vers.) (1R1712).....
BT223	BT223	BF614 +
<b>Opt. Trans. Spin-on</b> (Fuller 17237).....	B2 +	<b>Fuel Spin-on</b> (High Efficiency Vers.) (1R0749).....
B2 +	AT9522 w/Cat C10 (10.3L) Eng.	BF7587 +
AT9513 w/Cummins N14 (14.0L) Eng.	<b>F-F Lube</b> (Std. Version) (1R0716).....	BA5374 +
<b>F-F Lube</b> (Fleetguard LF670SC)..	B99 +	BA5379 +
B196 +	<b>F-F Lube</b> (High Efficiency Vers.) (1R1808).....	<b>Coolant</b> (w/4 Units BTE) (9N3368).....
<b>Dual-Flow Lube</b> (3318853).....	B7299 +	BW5137
BD103 +	B7577	<b>Coolant</b> (w/8 Units BTE) (9N3366).....
<b>B-P Lube</b> (3304232).....	<b>B-P Lube</b> (1W8845).....	BW5139
B7577	PF316	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493).....
<b>Fuel/Water Separator Spin-on</b> (3329289).....	<b>Fuel/Water Separator Ele.</b> (8N0205).....	PT9416-MPG KIT
BF1259	PF316	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494).....
<b>Fuel/Water Separator Spin-on</b> (3406889).....	<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Alliance ABPN122R50421).....	PT9415-MPG KIT
BF1293-SPS	BF1395-O	PT9415-MPG KIT
<b>Fuel</b> (154789).....	<b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (Alliance ABPN122R50421).....	<b>Trans. Spin-on</b> (Fuller 4304827)..
BF957-D +	BF1395-SP	BT223
<b>Coolant</b> (3315116).....	<b>Fuel/Water Separator Spin-on</b> (w/Drain) (Alliance ABPN122R50421).....	<b>Opt. Trans. Spin-on</b> (Fuller 17237).....
BW5071	BF1265	B2 +
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493).....	AT9522 w/Cummins M11 (10.8L) Eng.	AT9522 w/Cummins M11 (10.8L) Eng.
PT9416-MPG KIT	<b>Dual-Flow Lube</b> (3318853).....	<b>Dual-Flow Lube</b> (3318853).....
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494).....	BD103 +	BD103 +
PT9415-MPG KIT	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W).....	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W).....
<b>Trans. Spin-on</b> (Fuller 4304827)..	PF7680	PF7680
BT223	<b>Fuel/Water Separator Spin-on</b> (3329289).....	BF1259
<b>Opt. Trans. Spin-on</b> (Fuller 17237).....	<b>Air Dryer</b> (Bendix 5008414).....	BA5374 +
B2 +	BA5374 +	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).




FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)
AT9522 w/Cummins M11 (10.8L) Eng. (Cont'd)	B600, F600, B700, F700 w/Cummins FD1060 (5.9L) Eng.	C8000 w/6-473 (7.8L) Turbo Diesel Eng. (To 1990)
Air Dryer (Wabco R950068)..... <b>BA5379 +</b>	Lube..... <b>BT339 +</b>	Lube..... [2] <b>B157</b>
Coolant (w/4 Units BTA+) (3315116)..... <b>BW5071</b>	Fuel/Water Separator..... <b>BF1226</b>	Fuel/Water Separator (E7HZ-9N184-A)..... <b>BF1204</b>
Coolant (w/15 Units BTA+) (3318318)..... <b>BW5075</b>	B700 w/Cummins 6BT5.9 (5.9L) Eng.	Fuel Spin-on..... [2] <b>BF7608</b>
Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	Lube (3914395)..... <b>BT339 +</b>	Air (16 In.) (D5HZ-9601-D)..... <b>PA2425 +</b>
Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Fuel/Water Separator (3903202)..... <b>BF1226</b>	Air (23 1/2 In.) (E7HZ-9601-A)..... <b>PA2726</b>
Trans. Spin-on (Fuller 4304827)..... <b>BT223</b>	Fuel/Water Separator (3925274)..... <b>BF1280 +</b>	Coolant (E7HZ-8A424-B)..... <b>BW5136</b>
Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	Fuel (3903640)..... <b>BF788</b>	Steering (F0HZ-3C602-A)..... <b>PT8407</b>
AT9522 w/Cummins N14 (14.0L) Eng.	B800 w/Cummins 5.9L Diesel Eng.	C8000 w/6-473 (7.8L) Turbo Diesel Eng. (1991-on)
F-F Lube (Fleetguard LF670SC).. <b>B196 +</b>	Lube (To 1998) (3914395)..... <b>BT339 +</b>	Lube..... [2] <b>B157</b>
Dual-Flow Lube (3318853)..... <b>BD103 +</b>	Fuel/Water Separator (3925274)..... <b>BF1280 +</b>	Fuel/Water Separator (w/o Drain or Sensor Port) (F1HZ9365A)..... <b>BF1224</b>
B-P Lube (3304232)..... <b>B7577</b>	Fuel (3903640)..... <b>BF788</b>	Fuel/Water Separator (w/Drain) (F1HZ9365A)..... <b>BF1223</b>
Fuel/Water Separator Spin-on (3329289)..... <b>BF1259</b>	B800F w/Cummins 6BT5.9 (5.9L) Eng.	Fuel/Water Separator (w/Drain & Sensor Port) (F1HZ9365A)..... <b>BF1223-SP</b>
Fuel/Water Separator Spin-on (3406889)..... <b>BF1293-SPS</b>	Lube (3914395)..... <b>BT339 +</b>	Fuel/Water Separator (Open End for Bowl) (F1HZ9365A)..... <b>BF1223-O</b>
Fuel (154789)..... <b>BF957-D +</b>	Fuel/Water Separator (3903202)..... <b>BF1226</b>	Fuel Spin-on..... [2] <b>BF7608</b>
Air Dryer (Bendix 5008414)..... <b>BA5374 +</b>	Fuel/Water Separator (3925274)..... <b>BF1280 +</b>	Air (16 In.) (D5HZ-9601-D)..... <b>PA2425 +</b>
Air Dryer (Wabco R950068)..... <b>BA5379 +</b>	Fuel (3903640)..... <b>BF788</b>	Air (23 1/2 In.) (E7HZ-9601-A)..... <b>PA2726</b>
Coolant (3315116)..... <b>BW5071</b>	B7000 w/Cat 3208 (10.4L) Eng.	Coolant (E7HZ-8A424-B)..... <b>BW5136</b>
Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	Lube (1R0713)..... [2] <b>BT230 +</b>	Steering (F0HZ-3C602-A)..... <b>PT8407</b>
Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Lube (1R0714)..... [2] <b>B75</b>	
Trans. Spin-on (Fuller 4304827)..... <b>BT223</b>	Lube (9L9200)..... [2] <b>BT364</b>	
Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	Box-Style Fuel/Water Separator (8N9803)..... <b>BF912</b>	
AT9522 w/Detroit Diesel Series 60 (11.1L) or (12.7L) Eng.	P. Fuel Ele. (9M2341)..... <b>PF935</b>	
F-F Lube (23518480)..... [2] <b>B495</b>	P. Fuel Spin-on (1R0740)..... <b>BF970 +</b>	
Fuel/Water Separator (w/Drain) (23512317)..... <b>BF5813 +</b>	S. Fuel Spin-on (1R0750)..... <b>BF7633 +</b>	
Fuel/Water Separator (Open End for Bowl) (23512317)..... <b>BF5813-O +</b>	Coolant (w/o Chemicals) (4355142)..... <b>B5089 +</b>	
Opt. Fuel/Water Separator (23516189)..... <b>BF5812</b>	Coolant (w/4 Units BTE) (9N3717)..... <b>BW5137</b>	
Opt. Fuel/Water Separator (Alliance ABPN122R50407)..... <b>BF1283-SP +</b>	Coolant (w/8 Units BTE) (9N3718)..... <b>BW5139</b>	
P. Fuel (25014274)..... <b>BF5800 +</b>	C, F, H, N, P, T Series w/220 Dagenham Diesel Eng.	
S. Fuel (23518482)..... <b>BF5810</b>	Lube..... <b>P190</b>	
Air Dryer (Bendix 5008414)..... <b>BA5374 +</b>	C600 w/V8 361 5.9L Eng.	
Air Dryer (Wabco R950068)..... <b>BA5379 +</b>	F-F Lube..... <b>BT251</b>	
Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	B-P Lube..... <b>C704-L</b>	
Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Fuel (1964-76)..... <b>PF827</b>	
Trans. Spin-on (Fuller 4304827)..... <b>BT223</b>	Air (1970-76)..... <b>PA2379-K</b>	
Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	C6000, F6000, LN6000, C7000, F7000, LN7000 w/Cat 1140, 1145, 1150, 1160 Engs.	
B600 w/Cummins 6BT5.9 (5.9L) Eng.	Lube Spin-on..... [2] <b>BT364</b>	
Lube (3914395)..... <b>BT339 +</b>	B-P Lube Ele..... <b>C750-E +</b>	
Fuel/Water Separator (3903202)..... <b>BF1226</b>	Fuel..... <b>BF583</b>	
Fuel/Water Separator (3925274)..... <b>BF1280 +</b>	Air (Don. P127919)..... <b>PA1922-FN</b>	
Fuel (3903640)..... <b>BF788</b>	C7000, CT7000, F7000, FT7000, LN7000 w/Cat 3208 Eng.	
	Lube (1-12 Thd.) (9L9200)..... [2] <b>BT364</b>	
	Lube (1 1/8-16 Thd.) (9N5570)..... [2] <b>BT230</b>	
	8 In. Air (6 23/32 In. I.D.) (EOHZ-9601-B)..... <b>PA2599</b>	
	8 In. Air (8 11/16 In. I.D.) (EOHZ-9601-A)..... <b>PA2596</b>	
	8 5/16 In. Air (C8HZ-9601-A)..... <b>PA1922-FN</b>	
	10 3/8 In. Air (DOHZ-9601-D)..... <b>PA1986-K</b>	
	C8000 w/Cummins C160, CF160, C180 Engs.	
	F-F Lube Bag..... <b>P996</b>	
	F-F Lube Ele..... <b>P999-HD</b>	
	B-P Lube Ele..... <b>C750-E +</b>	
	Fuel/Water Separator..... <b>BF1212 +</b>	
	4 3/8 In. Fuel Spin-on..... <b>BF948 +</b>	
	5 3/4 In. Fuel Spin-on..... <b>BF957 +</b>	
	Air (1964-69) (C7TZ-9601-D)..... <b>PA1845</b>	
	Air (1966-70) (C7TZ-9600-D)..... <b>PA1848</b>	
	Breather..... <b>PA643</b>	
	Turbocharger..... <b>BT112</b>	
	C8000, CT8000 w/Cat 1100 Series Eng.	
	F-F Lube..... [2] <b>BT364</b>	
	B-P Lube Ele..... [2] <b>C750-E +</b>	
	Fuel..... <b>BF583</b>	
	Air (Don. P127919)..... <b>PA1922-FN</b>	

\* See Product Guide for Variations of This Number. Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)
C8000, CT8000, L8000, LN8000, LNT8000, LT8000, LTS8000 w/Cummins V555 Eng. F-F Lube Ele. .... P999-HD F-F Lube Spin-on ..... B196 + Fuel Spin-on ..... BF957 + Coolant ..... BW5071	CF7000 w/6.6L Turbo Diesel Eng. (Cont'd) Coolant (w/Chemical) (E7HZ8A424B)..... BW5136	CFT8000 w/Cummins 6CT8.3 (8.3L) Eng. Dual-Flow Lube (3318853)..... BD103 + Fuel/Water Separator (3286503)..... BF1226 Fuel (3903640)..... BF788 Coolant (w/6 Units BTA+) (3318201)..... BW5072 Coolant (w/8 Units BTA+) (3315115)..... BW5073
CF6000 w/6.6L Turbo Diesel Eng. F-F Lube (E7HZ26731A)..... [2] B157 Opt. B-P Lube (Motorcraft FL750)..... C750-E + Fuel/Water Separator (3 11/16 In. O.D., (w/SP)) (E7HZ9N184A).. BF1204 Fuel/Water Separator (3 11/16 In. O.D., (w/o SP)) (E7HZ9N184A) BF1204-SP Fuel/Water Separator (w/Drain or Sensor Port) (F1HZ9365A)..... BF1224 Fuel/Water Separator (w/Drain) (F1HZ9365A)..... BF1223 Fuel/Water Separator (w/Drain & Sensor Port) (F1HZ9365A)..... BF1223-SP Fuel/Water Separator (Open End for Bowl) (F1HZ9365A)..... BF1223-O Fuel (E6HZ9365A)..... BF790 16 In. Air (D5HZ9601D)..... PA2425 + 16 1/2 In. Air (7 15/16 In. O.D.) (E6HZ9601A)..... PA2523 16 1/2 In. Air (10 3/8 In. O.D.) (E7HZ9601B)..... PA2538 23 1/2 In. Air (E7HZ9601A)..... PA2726 Coolant (w/o Chemical) (E7HZ8A424A)..... BW5073 Coolant (w/Chemical) (E7HZ8A424B)..... BW5136	CF7000, LN7000 w/Cummins FD1060 (5.9L) Eng. Lube..... BT339 + Fuel/Water Separator..... BF1226	CT8000 w/Cat 3208 Eng. F-F Lube (1R0714)..... [2] B75 B-P Lube (Luberfiner 750CT)..... C750-E + Fuel (1R0750)..... BF7633 + Air (E0HT-9600-B)..... PA2596
CF7000 w/6.6L Turbo Diesel Eng. F-F Lube (E7HZ26731A)..... [2] B157 Opt. B-P Lube (Motorcraft FL750)..... C750-E + Fuel/Water Separator (3 11/16 In. O.D., (w/o SP)) (E7HZ9N184A) BF1204 Fuel/Water Separator (3 11/16 In. O.D., (w/SP)) (E7HZ9N184A).. BF1204-SP Fuel/Water Separator (w/Drain or Sensor Port) (F1HZ9365A)..... BF1224 Fuel/Water Separator (w/Drain) (F1HZ9365A)..... BF1223 Fuel/Water Separator (w/Drain & Sensor Port) (F1HZ9365A)..... BF1223-SP Fuel/Water Separator (Open End for Bowl) (F1HZ9365A)..... BF1223-O Fuel (E6HZ9365A)..... BF790 16 In. Air (D5HZ9601D)..... PA2425 + 16 1/2 In. Air (7 15/16 In. O.D.) (E6HZ9601A)..... PA2523 16 1/2 In. Air (10 3/8 In. O.D.) (E7HZ9601B)..... PA2538 23 1/2 In. Air (E7HZ9601A)..... PA2726 Coolant (w/o Chemical) (E7HZ8A424A)..... BW5073 Coolant (w/Chemical) (E7HZ8A424B)..... BW5136	CF8000 w/6-473 (7.8L) Turbo Diesel Eng. (To 1990) Lube..... [2] B157 Fuel/Water Separator (E7HZ-9N184-A)..... BF1204 Fuel Spin-on..... [2] BF7608 Air (16 In.) (D5HZ-9601-D)..... PA2425 + Air (23 1/2 In.) (E7HZ-9601-A)..... PA2726 Coolant (E7HZ-8A424-B)..... BW5136 Steering (F0HZ-3C602-A)..... PT8407	CL9000 w/Cummins L10 Eng. F-F Lube (3313279)..... B196 + B-P Lube (3313283)..... B7577 Fuel/Water Separator (3308638)..... BF1212 + Fuel (154709)..... BF957 + Air (E2HZ9601B)..... PA2642 Coolant (w/4 Units BTA+) (3315116)..... BW5071 Coolant (w/8 Units BTA+) (3315115)..... BW5073
CF7000 w/6.6L Turbo Diesel Eng. F-F Lube (E7HZ26731A)..... [2] B157 Opt. B-P Lube (Motorcraft FL750)..... C750-E + Fuel/Water Separator (3 11/16 In. O.D., (w/o SP)) (E7HZ9N184A) BF1204 Fuel/Water Separator (3 11/16 In. O.D., (w/SP)) (E7HZ9N184A).. BF1204-SP Fuel/Water Separator (w/Drain or Sensor Port) (F1HZ9365A)..... BF1224 Fuel/Water Separator (w/Drain) (F1HZ9365A)..... BF1223 Fuel/Water Separator (w/Drain & Sensor Port) (F1HZ9365A)..... BF1223-SP Fuel/Water Separator (Open End for Bowl) (F1HZ9365A)..... BF1223-O Fuel (E6HZ9365A)..... BF790 16 In. Air (D5HZ9601D)..... PA2425 + 16 1/2 In. Air (7 15/16 In. O.D.) (E6HZ9601A)..... PA2523 16 1/2 In. Air (10 3/8 In. O.D.) (E7HZ9601B)..... PA2538 23 1/2 In. Air (E7HZ9601A)..... PA2726 Coolant (w/o Chemical) (E7HZ8A424A)..... BW5073 Coolant (w/Chemical) (E7HZ8A424B)..... BW5136	CF8000 w/6-473 (7.8L) Turbo Diesel Eng. (1991-on) Lube..... [2] B157 Fuel/Water Separator (w/o Drain or Sensor Port) (F1HZ9365A)..... BF1224 Fuel/Water Separator (w/Drain) (F1HZ9365A)..... BF1223 Fuel/Water Separator (w/Drain & Sensor Port) (F1HZ9365A)..... BF1223-SP Fuel/Water Separator (Open End for Bowl) (F1HZ9365A)..... BF1223-O Fuel Spin-on..... [2] BF7608 Air (16 In.) (D5HZ-9601-D)..... PA2425 + Air (23 1/2 In.) (E7HZ-9601-A)..... PA2726 Coolant (E7HZ-8A424-B)..... BW5136 Steering (F0HZ-3C602-A)..... PT8407	CL9000 w/Cummins N14 (14.0L) Eng. F-F Lube (Fleetguard LF670SC).. B196 + Dual-Flow Lube (3318853)..... BD103 + B-P Lube (3304232)..... B7577 Fuel/Water Separator Spin-on (3329289)..... BF1259 Fuel/Water Separator Spin-on (3406889)..... BF1293-SPS Fuel (154789)..... BF957-D + Coolant (3315116)..... BW5071
CF7000 w/6.6L Turbo Diesel Eng. F-F Lube (E7HZ26731A)..... [2] B157 Opt. B-P Lube (Motorcraft FL750)..... C750-E + Fuel/Water Separator (3 11/16 In. O.D., (w/o SP)) (E7HZ9N184A) BF1204 Fuel/Water Separator (3 11/16 In. O.D., (w/SP)) (E7HZ9N184A).. BF1204-SP Fuel/Water Separator (w/Drain or Sensor Port) (F1HZ9365A)..... BF1224 Fuel/Water Separator (w/Drain) (F1HZ9365A)..... BF1223 Fuel/Water Separator (w/Drain & Sensor Port) (F1HZ9365A)..... BF1223-SP Fuel/Water Separator (Open End for Bowl) (F1HZ9365A)..... BF1223-O Fuel (E6HZ9365A)..... BF790 16 In. Air (D5HZ9601D)..... PA2425 + 16 1/2 In. Air (7 15/16 In. O.D.) (E6HZ9601A)..... PA2523 16 1/2 In. Air (10 3/8 In. O.D.) (E7HZ9601B)..... PA2538 23 1/2 In. Air (E7HZ9601A)..... PA2726 Coolant (w/o Chemical) (E7HZ8A424A)..... BW5073	CF8000 w/Cummins 6BT5.9 (5.9L) Eng. Lube (3914395)..... BT339 + Fuel/Water Separator (3903202)..... BF1226 Fuel/Water Separator (3925274)..... BF1280 + Fuel (3903640)..... BF788 Trans. Pan-Type (3.8 In. Pan, AT Series Trans.) (Allison 29540976)..... 19992 + Trans. Pan-Type (5.3 In. Pan, A.T. Series Trans.) (Allison 29538489)..... 19739 + Trans. Spin-on (AT Series) (Allison 29510922)..... BT8316-MPG	CL9000 w/Detroit Diesel 6V-92, 8V-92 Series Engs. F-F Lube Ele..... P20-HD + B-P Lube Ele. (750 Size)..... C750-E + P. Fuel Spin-on..... BF5800 + S. Fuel Spin-on..... BF5810 O. Air (Motorcraft AFA93)..... PA2959-FN <sup>90</sup> I. Air (Motorcraft AFA94)..... PA2960 Std. Air (16 1/2 In.) (D5HZ-9601-A)..... PA2533 Conical Air (8 11/16 In. O.D.) (D8HZ-9601-A)..... PA2500 + Conical Air (10 13/32 In. O.D.) (D8HZ-9601-B)..... PA3951 DynaCell Panel Air (D8HZ-9601-E)..... PA2375 + Conical Air (12 3/4 In. O.D.) (E2HZ-9601-A)..... PA2632
CF7000 w/6.6L Turbo Diesel Eng. F-F Lube (E7HZ26731A)..... [2] B157 Opt. B-P Lube (Motorcraft FL750)..... C750-E + Fuel/Water Separator (3 11/16 In. O.D., (w/o SP)) (E7HZ9N184A) BF1204 Fuel/Water Separator (3 11/16 In. O.D., (w/SP)) (E7HZ9N184A).. BF1204-SP Fuel/Water Separator (w/Drain or Sensor Port) (F1HZ9365A)..... BF1224 Fuel/Water Separator (w/Drain) (F1HZ9365A)..... BF1223 Fuel/Water Separator (w/Drain & Sensor Port) (F1HZ9365A)..... BF1223-SP Fuel/Water Separator (Open End for Bowl) (F1HZ9365A)..... BF1223-O Fuel (E6HZ9365A)..... BF790 16 In. Air (D5HZ9601D)..... PA2425 + 16 1/2 In. Air (7 15/16 In. O.D.) (E6HZ9601A)..... PA2523 16 1/2 In. Air (10 3/8 In. O.D.) (E7HZ9601B)..... PA2538 23 1/2 In. Air (E7HZ9601A)..... PA2726 Coolant (w/o Chemical) (E7HZ8A424A)..... BW5073	CF/CFT8000, LA8000, L/LT8000, LN/LNT8000, LS/LTS8000 w/FD1460 (8.3L) Eng. Dual-Flow Lube..... BD103 + Fuel/Water Separator..... BF1226 Radial Seal O. Air (F3HZ-9601-A)..... RS2863 Radial Seal XP O. Air (F3HZ-9601-A)..... RS2863XP Radial Seal I. Air (F3HZ-9R500-A)..... RS3501	CL9000, CLT9000, L9000, LA9000, LL9000, LN9000 w/Cat 3406 Eng. Lube (1R0716)..... B99 + P. Fuel Ele..... PF935 P. Fuel Spin-on (E6HZ-9155-E).... BF5800 + Opt. Fuel Spin-on (1R-0749)..... BF7587 + O. Air (Motorcraft AFA93)..... PA2959-FN <sup>90</sup>

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)
CL9000, CLT9000, L9000, LA9000, LL9000, LN9000 w/Cat 3406 Eng. (Cont'd)	CL9000, CLT9000, L9000, LN9000, LNT9000, LT9000, LTS9000, W9000, WT9000 w/GMC 8V-71 Series Engs. (Cont'd)	CLT9000 w/Detroit Diesel 6V-92N, 8V-92 Series Engs. (Cont'd)
<b>I. Air</b> (Motorcraft AFA94)..... <b>PA2960</b>	<b>Std. Air</b> (18 1/2 In.) (Don. P117443)..... <b>PA1846 +</b>	<b>DynaCell Panel Air</b> (D8HZ-9601-E)..... <b>PA2375 +</b>
<b>Air</b> (15 3/4 In. O.D., w/Fins) (Don. P127918)..... <b>PA1980-FN</b>	<b>Std. Air</b> (Upgrade), 18 1/2 In. (Don. P117443)..... <b>PA1846XP</b>	<b>Conical Air</b> (12 3/4 In. O.D.) (E2HZ-9601-A)..... <b>PA2632</b>
<b>Conical Air</b> (8 11/16 In. O.D.) (Don. P129472)..... <b>PA2500 +</b>	<b>Std. Air</b> (18 9/16 In.) (Don. P126662)..... <b>PA2533</b>	CT900 w/Detroit Diesel 8.2L Eng.
<b>Air</b> (7 7/16 In. O.D.) (Don. P142367)..... <b>PA2642</b>	<b>Long Life Air</b> (16 3/8 In. Length, (12 1/32 In. O.D.)) (Don. P126719) <b>LL1992</b>	<b>Lube</b> ..... <b>[2] B6 +</b>
<b>Conical Air</b> (12 3/4 In. O.D.) (Don. P141228)..... <b>PA2632</b>	<b>O. Air</b> (16 3/8 In. Length, (13 3/4 In. O.D.)) (Don. P127917)..... <b>PA1979-FN</b>	<b>P. Fuel</b> ..... <b>BF592 +</b>
<b>Conical Air</b> (10 13/32 In. O.D.) (D8HZ-9601-B)..... <b>PA3951</b>	CLT9000 w/Cummins L10 (10.0L) Eng.	<b>S. Fuel</b> ..... <b>BF593</b>
<b>Radial Seal O. Air</b> (Standard) (F1HZ-9601-B)..... <b>RS3518</b>	<b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196 +</b>	<b>Air</b> (E0HZ-9601-A)..... <b>PA2596</b>
<b>Radial Seal XP O. Air</b> (Upgrade) (F1HZ9601B)..... <b>RS3518XP</b>	<b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b>	E-450 Econoline Super Duty w/V8-330 (5.4L) CNG Eng.
<b>Coolant</b> (w/4 Units BTA+)..... <b>BW5071</b>	<b>B-P Lube</b> (3304232)..... <b>B7577</b>	<b>Lube</b> (Motorcraft FL820S)..... <b>B329</b>
<b>Coolant</b> (w/8 Units BTE) (9N-6123)..... <b>BW5139</b>	<b>Fuel/Water Separator Spin-on</b> (3329289)..... <b>BF1259</b>	<b>Air</b> (Motorcraft FA1634)..... <b>PA4075</b>
LNT9000, LS9000, LTA9000, LTL9000, LTS9000 w/Cat 3406 Eng.	<b>Fuel/Water Separator Spin-on</b> (3406889)..... <b>BF1293-SPS</b>	<b>Trans.</b> (4R70W) (Motorcraft FT105)..... <b>18029</b>
<b>Lube</b> (1R0716)..... <b>B99 +</b>	<b>Fuel</b> (154789)..... <b>BF957-D +</b>	<b>Trans.</b> (4R100) (Motorcraft FT113)..... <b>18264</b>
<b>P. Fuel Ele.</b> ..... <b>PF935</b>	<b>Air</b> (E2HZ9601B)..... <b>PA2642</b>	E-450 Econoline Super Duty w/V8-330 (5.4L) Gas Eng.
<b>P. Fuel Spin-on</b> (E6HZ-9155-E)... <b>BF5800 +</b>	<b>Coolant</b> (3315116)..... <b>BW5071</b>	<b>Lube</b> (Motorcraft FL820)..... <b>B329</b>
<b>Opt. Fuel Spin-on</b> (1R-0749)..... <b>BF7587 +</b>	CLT9000 w/Cummins N14 (14.0L) Eng.	<b>In-Line Fuel</b> (To 2/12/2000) (Motorcraft FG872)..... <b>BF1166</b>
<b>O. Air</b> (Motorcraft AFA93)..... <b>PA2959-FN 90</b>	<b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196 +</b>	<b>In-Line Fuel</b> (2/12/2000-on) (F89Z9155A)..... <b>BF7668 +</b>
<b>I. Air</b> (Motorcraft AFA94)..... <b>PA2960</b>	<b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b>	<b>Air</b> (Motorcraft FA1634)..... <b>PA4075</b>
<b>Air</b> (15 3/4 In. O.D., w/Fins) (Don. P127918)..... <b>PA1980-FN</b>	<b>B-P Lube</b> (3304232)..... <b>B7577</b>	<b>Trans.</b> (4R70W) (Motorcraft FT105)..... <b>18029</b>
<b>Conical Air</b> (8 11/16 In. O.D.) (Don. P129472)..... <b>PA2500 +</b>	<b>Fuel/Water Separator Spin-on</b> (3329289)..... <b>BF1259</b>	<b>Trans.</b> (4R100) (Motorcraft FT113)..... <b>18264</b>
<b>Air</b> (7 7/16 In. O.D.) (Don. P142367)..... <b>PA2642</b>	<b>Fuel/Water Separator Spin-on</b> (3406889)..... <b>BF1293-SPS</b>	E-450 Econoline Super Duty w/V10-415 (6.8L) Eng.
<b>Conical Air</b> (12 3/4 In. O.D.) (Don. P141228)..... <b>PA2632</b>	<b>Fuel</b> (154789)..... <b>BF957-D +</b>	<b>Lube</b> (Motorcraft FL820S)..... <b>B329</b>
<b>Conical Air</b> (10 13/32 In. O.D.) (D8HZ-9601-B)..... <b>PA3951</b>	<b>Coolant</b> (3315116)..... <b>BW5071</b>	<b>In-Line Fuel</b> (To 2/12/2000) (Motorcraft FG872)..... <b>BF1166</b>
<b>Radial Seal O. Air</b> (Standard) (F1HZ-9601-B)..... <b>RS3518</b>	CLT9000 w/Cummins VT903 (14.8L) Eng.	<b>In-Line Fuel</b> (2/12/2000-on) (F89Z9155A)..... <b>BF7668 +</b>
<b>Radial Seal XP O. Air</b> (Upgrade) (F1HZ9601B)..... <b>RS3518XP</b>	<b>F-F Lube Ele.</b> (158139)..... <b>P999-HD</b>	<b>Air</b> (Motorcraft FA1634)..... <b>PA4075</b>
<b>Coolant</b> (w/4 Units BTA+)..... <b>BW5071</b>	<b>F-F Lube Spin-on</b> (3313279)..... <b>B96 +</b>	<b>Trans.</b> (4R70W) (Motorcraft FT105)..... <b>18029</b>
<b>Coolant</b> (w/8 Units BTE) (9N-6123)..... <b>BW5139</b>	<b>B-P Lube Ele.</b> (256838)..... <b>C750-E +</b>	<b>Trans.</b> (4R100) (Motorcraft FT113)..... <b>18264</b>
CL9000, CLT9000, L9000, LN9000, LNT9000, LT9000, LTS9000, W9000, WT9000 w/GMC 8V-71 Series Engs.	<b>B-P Lube Spin-on</b> (3313283)..... <b>B7577</b>	E-450 Econoline Super Duty w/V8-445 (7.3L) Turbo Diesel Eng.
<b>F-F Lube Ele.</b> ..... <b>P20-HD +</b>	<b>Fuel/Water Separator</b> (3308638). <b>BF1212 +</b>	<b>Lube</b> (Motorcraft FL1995)..... <b>B7039</b>
<b>B-P Lube Ele.</b> (750 Size)..... <b>C750-E +</b>	<b>Fuel</b> (156172)..... <b>BF957-D +</b>	<b>Fuel Ele.</b> (Motorcraft FD4596)..... <b>PF7698</b>
<b>P. Fuel Spin-on</b> ..... <b>BF5800 +</b>	<b>Conical-Shaped Air</b> (Don. P151097)..... <b>PA3951</b>	<b>Air</b> (Motorcraft FA1618)..... <b>[2] PA2237</b>
<b>S. Fuel Spin-on</b> ..... <b>BF5810</b>	<b>Coolant</b> (3315116)..... <b>BW5071</b>	<b>Trans.</b> (Motorcraft FT113)..... <b>18264</b>
<b>Air</b> (1975-on) (Don. P128960)..... <b>PA2430</b>	CLT9000 w/Detroit Diesel 6V-92N, 8V-92 Series Engs.	E-450 Super Duty w/V8-330 (5.4L) Eng. (To 5/20/2007)
<b>Conical Air</b> (8 11/16 In. O.D.) (D8HZ-9601-A)..... <b>PA2500 +</b>	<b>F-F Lube Ele.</b> ..... <b>P20-HD +</b>	<b>Lube</b> (Motorcraft FL820S)..... <b>B329</b>
<b>Conical Air</b> (10 13/32 In. O.D.) (D8HZ-9601-B)..... <b>PA3951</b>	<b>B-P Lube Ele.</b> (750 Size)..... <b>C750-E +</b>	<b>In-Line Fuel</b> (Motorcraft FG986B)..... <b>BF7668 +</b>
<b>DynaCell Panel Air</b> (19 In.) (D8HZ-9601-E)..... <b>PA2375 +</b>	<b>P. Fuel Spin-on</b> ..... <b>BF5800 +</b>	<b>Air</b> (Motorcraft FA1634)..... <b>PA4075</b>
	<b>S. Fuel Spin-on</b> ..... <b>BF5810</b>	<b>Trans. Pan-Type</b> (4R75W) (Motorcraft FT105)..... <b>18029</b>
	<b>O. Air</b> (Motorcraft AFA93)..... <b>PA2959-FN 90</b>	
	<b>I. Air</b> (Motorcraft AFA94)..... <b>PA2960</b>	
	<b>Std. Air</b> (16 1/2 In.) (D5HZ-9601-A)..... <b>PA2533</b>	
	<b>Conical Air</b> (8 11/16 In. O.D.) (D8HZ-9601-A)..... <b>PA2500 +</b>	
	<b>Conical Air</b> (10 13/32 In. O.D.) (D8HZ-9601-B)..... <b>PA3951</b>	

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.

Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)
E-450 Super Duty w/V8-330 (5.4L) Eng. (To 5/20/2007) (Cont'd)	E-450 Super Duty w/V10-415 (6.8L) Eng. (To 2016) (Cont'd)	E-550 Econoline Super Duty w/V8-445 (7.3L) Turbo Diesel Eng.
Trans. Pan-Type (4R100) (Motorcraft FT113)..... 18264	Trans. Pan-Type (4R75W) (Motorcraft FT105)..... 18029	Lube (Motorcraft FL1995)..... B7039
Trans. Ele. (5R100W) (Motorcraft FT145)..... P7247	Trans. Pan-Type (4R100) (Motorcraft FT113)..... 18264	Fuel Ele. (Motorcraft FD4596)..... PF7698
Trans. Pan-Type (5R110W) (Motorcraft FT144)..... 20005	Trans. Ele. (5R100W) (Motorcraft FT145)..... P7247	Air (Motorcraft FA1618)..... [2] PA2237
E-450 Super Duty w/V8-330 (5.4L) Eng. (5/21/2007-on)	Trans. Pan-Type (5R110W (To 11/07)) (Motorcraft FT144)..... 20005	Trans. Pan-Type (Motorcraft FT113)..... 18264
Lube (Motorcraft FL820S)..... B329	Trans. Pan-Type (5R110W (11/07-on)) (Motorcraft FT180)..... 20021	E-550 Super Duty w/V10-415 (6.8L) Eng.
In-Line Fuel (Motorcraft FG986B)..... BF7668 +	E-450 Super Duty w/V10-415 (6.8L) Eng. (2017)	Lube (Motorcraft FL820S)..... B329
Air (Motorcraft FA1634)..... PA4075	Lube (Motorcraft FL820S)..... B329	In-Line Fuel (Motorcraft FG986B)..... BF7668 +
Trans. Pan-Type (4R75W) (Motorcraft FT105)..... 18029	Fuel (N/S)..... N/S	Air (Motorcraft FA1634)..... PA4075
Trans. Pan-Type (4R100) (Motorcraft FT113)..... 18264	Air (Motorcraft FA1632)..... PA4075	Trans. Pan-Type (Motorcraft FT113)..... 18264
Trans. Ele. (5R100W) (Motorcraft FT145)..... P7247	Trans. (Motorcraft FT187)..... 20028	E-550 Super Duty w/V8-445 (7.3L) Turbo Diesel Eng.
Trans. Pan-Type (5R100W) (Motorcraft FT180)..... 20021	E-450 Super Duty w/V10-415 (6.8L) Eng. (2018)	Lube (Motorcraft FL1995)..... B7039
Trans. Pan-Type (TorqShift) (Motorcraft FT144)..... 20005	Lube (Motorcraft FL820S)..... B329	Fuel Ele. (Motorcraft FD4596)..... PF7698
E-450 Super Duty w/V8-363 (6.0L) FI Turbo Diesel Eng.	Fuel (N/S)..... N/S	Air (Motorcraft FA1618)..... [2] PA2237
Lube Ele. (w/o Screw-on Cap) (Motorcraft FL2016)..... P7235	Air (Motorcraft FA1632)..... PA4075	Trans. Pan-Type (Motorcraft FT113)..... 18264
Lube Ele. (w/Screw on Cap) (Wix 57313)..... P7437	Trans. (Motorcraft FT187)..... 20028	Econoline Super Duty w/V8-330 (5.4L) FI Eng.
Fuel Ele. (Motorcraft FD4606)..... PF7852 KIT <sup>76</sup>	E-450 Super Duty w/V10-415 (6.8L) Eng. (2019)	Lube..... B329
Air (Motorcraft FA1769)..... PA4171	Lube (Motorcraft FL820S)..... B329	In-Line Fuel..... BF1166
Trans. Pan-Type (4R75W) (Motorcraft FT105)..... 18029	Fuel (N/S)..... N/S	Air..... PA4075
Trans. Pan-Type (4R100) (Motorcraft FT114)..... 18265	Air (Motorcraft FA1632)..... PA4075	Trans. Pan-Type (4R70W) (Motorcraft FT105)..... 18029
Trans. Ele. (5R110W) (Motorcraft FT145)..... P7247	Trans. (Motorcraft FT187)..... 20028	Trans. Pan-Type (4R100) (Motorcraft FT113)..... 18264
Trans. Pan-Type (5R110W (To 11/07)) (Motorcraft FT144)..... 20005	E-450 Super Duty w/V8-445 (7.3L) Turbo Diesel Eng. (2003)	Econoline Super Duty w/V8-351 (5.8L) FI Eng.
Trans. Pan-Type (5R110W (11/07-on)) (Motorcraft FT180)..... 20021	Lube (Motorcraft FL1995)..... B7039	Lube..... B2 +
E-450 Super Duty w/V8-378 (6.2L) Eng. (2018)	Fuel Ele. (Motorcraft FD4596)..... PF7698	In-Line Fuel..... BF1166
Lube (Motorcraft FL820S)..... B329	Air (Motorcraft FA1618)..... [2] PA2237	Air..... PA2164
Fuel (N/S)..... N/S	Trans. Pan-Type (Motorcraft FT113)..... 18264	Crankcase Breather..... SA2047
Air (Motorcraft FA1632)..... PA4075	E-450 Super Duty w/V8-445 (7.3L) Eng. (2021)	Trans. Pan-Type (E4OD)..... 18264
Trans. (Motorcraft FT187)..... 20028	Lube (Motorcraft FL820S)..... B329	Econoline Super Duty w/V10-415 (6.8L) Eng.
E-450 Super Duty w/V8-378 (6.2L) Eng. (2019)	Fuel (N/S)..... N/S	Lube..... B329
Lube (Motorcraft FL820S)..... B329	Trans. (Motorcraft FT187)..... 20028	In-Line Fuel..... BF1166
Fuel (N/S)..... N/S	E-450 Super Duty w/V8-445 (7.3L) Eng. (2022)	Air..... PA4075
Air (Motorcraft FA1632)..... PA4075	Lube (Motorcraft FL820S)..... B329	Crankcase Breather..... SA2047
Trans. (Motorcraft FT187)..... 20028	Fuel (N/S)..... N/S	Trans. Pan-Type (Motorcraft FT113)..... 18264
E-450 Super Duty w/V8-378 (6.2L) Eng. (2019)	Trans. (Motorcraft TF187)..... 20028	Econoline Super Duty w/V8-445 (7.3L) FI Turbo Diesel Eng. (1996)
Lube (Motorcraft FL820S)..... B329	E-450 Super Duty w/V8-445 (7.3L) Eng. (2023)	Lube..... B7039
Fuel (N/S)..... N/S	Lube (Motorcraft FL820S)..... B329	Fuel Ele..... PF7678
Air (Motorcraft FA1632)..... PA4075	Fuel (N/S)..... N/S	Air..... [2] PA2237
Trans. (Motorcraft FT187)..... 20028	Trans. (Motorcraft FT187)..... 20028	Trans. Pan-Type (C6)..... 19828
E-450 Super Duty w/V10-415 (6.8L) Eng. (To 2016)	E-550 Econoline Super Duty w/V10-415 (6.8L) Eng.	Trans. Pan-Type (E4OD) (Motorcraft FT113)..... 18264
Lube (Motorcraft FL820S)..... B329	Lube (Motorcraft FL820S)..... B329	Econoline Super Duty w/V8-445 (7.3L) FI Turbo Diesel Eng. (1997)
In-Line Fuel (Motorcraft FG986B)..... BF7668 +	In-Line Fuel (F89Z9155A)..... BF7668 +	Lube..... B7039
Air (Motorcraft FA1634)..... PA4075	Air (Motorcraft FA1634)..... PA4075	Fuel Ele..... PF7678
Trans. (Motorcraft FT187)..... 20028	Trans. Pan-Type (Motorcraft FT113)..... 18264	Air..... [2] PA2237
E-450 Super Duty w/V10-415 (6.8L) Eng. (To 2016)	E-550 Econoline Super Duty w/V10-415 (6.8L) Eng.	Trans. Pan-Type (4R70W)..... 18029
Lube (Motorcraft FL820S)..... B329	Lube (Motorcraft FL820S)..... B329	
In-Line Fuel (Motorcraft FG986B)..... BF7668 +	In-Line Fuel (F89Z9155A)..... BF7668 +	
Air (Motorcraft FA1634)..... PA4075	Air (Motorcraft FA1634)..... PA4075	
Trans. (Motorcraft FT187)..... 20028	Trans. Pan-Type (Motorcraft FT113)..... 18264	

+ See Product Guide for Variations of This Number. <sup>76</sup> Contains Pri. and Sec. Fuel Elements. Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>FORD</b> <b>Trucks &amp; Buses (cont'd)</b>	<b>FORD</b> <b>Trucks &amp; Buses (cont'd)</b>	<b>FORD</b> <b>Trucks &amp; Buses (cont'd)</b>
Econoline Super Duty w/V8-445 (7.3L) FI Turbo Diesel Eng. (1997) (Cont'd) <b>Trans. Pan-Type</b> (E4OD) (Motorcraft FT113)..... <b>18264</b>	F Super Duty w/V8-460 (7.5L) Eng. (Cont'd) <b>In-Line Fuel</b> (1992-97) (FOTZ9155B)..... <b>BF1166</b> <b>Air</b> ..... <b>PA2164</b> <b>Crankcase Breather</b> ..... <b>SA2159</b> <b>Trans. Pan-Type</b> ..... <b>18264</b>	F53 w/V10-415 (6.8L) Eng. (2005-2006) <b>Lube</b> (Motorcraft FL-820-S)..... <b>B329</b> <b>Fuel</b> (Motorcraft FG-872)..... <b>BF1166</b> <b>Fuel</b> (Motorcraft FG1083)..... <b>BF7802</b> <b>Air</b> (Motorcraft FA-1782)..... <b>PA4172</b> <b>Trans. Ele.</b> (Motorcraft FT145)..... <b>P7247</b>
Econoline Super Duty w/V8-445 (7.3L) FI Turbo Diesel Eng. (1/12/1998-on) <b>Lube</b> ..... <b>B7039</b> <b>Fuel Ele.</b> (F81Z9N184AA)..... <b>PF7698</b> <b>Air</b> ..... <b>[2] PA2237</b> <b>Trans. Pan-Type</b> (4R70W)..... <b>18029</b> <b>Trans. Pan-Type</b> (4R100) (Motorcraft FT113)..... <b>18264</b>	F53 w/V8-445 (7.3L) Eng. (2020) <b>Lube</b> (Motorcraft FL820S)..... <b>B329</b> <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Air</b> (Motorcraft FA1782)..... <b>PA4172</b> <b>Trans.</b> (Motorcraft FT187)..... <b>20028</b>	F53 w/V10-415 (6.8L) Eng. (2007) <b>Lube</b> (Motorcraft FL-820-S)..... <b>B329</b> <b>Fuel</b> (Motorcraft FG-872)..... <b>BF1166</b> <b>Fuel</b> (Motorcraft FG1083)..... <b>BF7802</b> <b>Air</b> (Motorcraft FA-1782)..... <b>PA4172</b> <b>Trans. Ele.</b> (Motorcraft FT145)..... <b>P7247</b>
Econoline Super Duty w/V8-445 (7.3L) FI Turbo Diesel Eng. (To 1/12/1998) <b>Lube</b> ..... <b>B7039</b> <b>Fuel Ele.</b> (F4TZ9N184A)..... <b>PF7678</b> <b>Air</b> ..... <b>[2] PA2237</b> <b>Trans. Pan-Type</b> (4R70W)..... <b>18029</b> <b>Trans. Pan-Type</b> (4R100) (Motorcraft FT113)..... <b>18264</b>	F53 w/V8-445 (7.3L) Eng. (2021) <b>Lube</b> (Motorcraft FL820S)..... <b>B329</b> <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Air</b> (Motorcraft FA1782)..... <b>PA4172</b> <b>Trans.</b> (Motorcraft FT187)..... <b>20028</b>	F53 w/V10-415 (6.8L) Eng. (2008) <b>Lube</b> (Motorcraft FL-820-S)..... <b>B329</b> <b>Fuel</b> (Motorcraft FG1083)..... <b>BF7802</b> <b>Air</b> (Motorcraft FA1883)..... <b>PA4323</b>
Econoline Super Duty w/V8-460 (7.5L) FI Eng. <b>Lube</b> (Motorcraft FL1A)..... <b>B2 +</b> <b>In-Line Fuel</b> (Motorcraft FG872)... <b>BF1166</b> <b>Air</b> (Motorcraft FA1046)..... <b>PA2164</b> <b>Crankcase Breather</b> (Motorcraft FA1603)..... <b>SA2047</b> <b>Trans. Pan-Type</b> (Motorcraft FT52)..... <b>19828</b>	F53 w/V8-460 (7.5L) Eng. (1990-91) <b>Std. Lube</b> (Motorcraft FL1A)..... <b>B2 +</b> <b>Heavy Duty Lube</b> (Motorcraft FL1HP)..... <b>BT8328</b> <b>In-Line Fuel</b> (Motorcraft FG800A)..... <b>BF966</b> <b>Round Air</b> (Motorcraft FA1057)... <b>PA2092</b> <b>Panel Air</b> (Motorcraft FA1046)..... <b>PA2164</b> <b>Crankcase Breather</b> (Motorcraft FA1047)..... <b>SA2159</b> <b>Trans.</b> (E4OD) (Motorcraft FT108)..... <b>18264</b>	F53 w/V10-415 (6.8L) Eng. (2009) <b>Lube</b> (Motorcraft FL-820-S)..... <b>B329</b> <b>Fuel</b> (Motorcraft FG1083)..... <b>BF7802</b> <b>Air</b> (Motorcraft FA1883)..... <b>PA4323</b> <b>Trans. Pan-Type</b> (Motorcraft FT-180)..... <b>20021</b>
F Super Duty w/V8-445 (7.3L) Naturally Aspirated Diesel Eng. <b>Lube</b> ..... <b>B134</b> <b>Fuel/Water Separator</b> (w/Sensor Port)..... <b>BF1222-SP +</b> <b>Fuel/Water Separator</b> (w/o Sensor Port)..... <b>BF1222 +</b> <b>Fuel/Water Separator</b> (Open End for Bowl)..... <b>BF1222-O +</b> <b>Air</b> ..... <b>PA2092</b> <b>Trans. Pan-Type</b> ..... <b>18264</b>	F53 w/V8-460 (7.5L) Eng. (1992-97) <b>Std. Lube</b> (Motorcraft FL1A)..... <b>B2 +</b> <b>Heavy Duty Lube</b> (Motorcraft FL1HP)..... <b>BT8328</b> <b>In-Line Fuel</b> (Motorcraft FG872)... <b>BF1166</b> <b>Round Air</b> (Motorcraft FA1057)... <b>PA2092</b> <b>Panel Air</b> (Motorcraft FA1046)..... <b>PA2164</b> <b>Crankcase Breather</b> (Motorcraft FA1047)..... <b>SA2159</b> <b>Trans.</b> (E4OD) (Motorcraft FT108)..... <b>18264</b>	F53 w/V10-415 (6.8L) Eng. (2011-16) <b>Lube</b> (Motorcraft FL-820-S)..... <b>B329</b> <b>Fuel</b> (Motorcraft FG1083)..... <b>BF7802</b> <b>Air</b> (Motorcraft FA-1782)..... <b>PA4172</b> <b>Trans. Pan-Type</b> (Motorcraft FT-180)..... <b>20021</b>
F Super Duty w/V8-445 (7.3L) Turbo Diesel Eng. <b>Lube</b> (Motorcraft FL1995)..... <b>B7039</b> <b>Fuel/Water Separator</b> (w/Sensor Port)..... <b>BF1222-SP +</b> <b>Fuel/Water Separator</b> (w/o Sensor Port)..... <b>BF1222 +</b> <b>Fuel/Water Separator</b> (Open End for Bowl)..... <b>BF1222-O +</b> <b>Fuel Ele.</b> ..... <b>PF7678</b> <b>Oval Air</b> ..... <b>PA2233</b> <b>Panel Air</b> ..... <b>PA4073</b> <b>Cab. Air</b> (Opt.) (Motorcraft FP7A). <b>PA4133</b> <b>Trans. Pan-Type</b> ..... <b>18264</b>	F53 w/V8-460 (7.5L) Eng. (1999-2003) <b>Lube</b> (Motorcraft FL-820-S)..... <b>B329</b> <b>Fuel</b> (Motorcraft FG-872)..... <b>BF1166</b> <b>Air</b> (Motorcraft FA-1046)..... <b>PA2164</b> <b>Breather</b> (Motorcraft FA-1603)..... <b>SA2047</b>	F53 w/V10-415 (6.8L) Eng. (2017-18) <b>Lube</b> (Motorcraft FL-820-S)..... <b>B329</b> <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Air</b> (Motorcraft FA-1782)..... <b>PA4172</b> <b>Trans.</b> (5 Spd.) (Motorcraft FT180)..... <b>20021</b> <b>Trans.</b> (6 Spd.) (Motorcraft FT-187)..... <b>20028</b>
F Super Duty w/V8-460 (7.5L) Eng. <b>Std. Lube</b> ..... <b>B2 +</b> <b>Heavy Duty Lube</b> ..... <b>BT8328</b> <b>In-Line Fuel</b> (1988-91) (E9TZ9B072CA)..... <b>BF966</b>	F53 w/V10-415 (6.8L) Eng. (2004) <b>Lube</b> (Motorcraft FL-820-S)..... <b>B329</b> <b>Fuel</b> (Motorcraft FG-872)..... <b>BF1166</b> <b>Air</b> (Motorcraft FA-1634)..... <b>PA4075</b>	F53 w/V10-415 (6.8L) Eng. (2019) <b>Lube</b> (Motorcraft FL820S)..... <b>B329</b> <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Air</b> (Motorcraft FA1782)..... <b>PA4172</b> <b>Trans.</b> (Motorcraft FT187)..... <b>20028</b>
	F-59 Commercial Chassis w/V10 6.8L Eng. (2011-15) <b>Lube</b> (Motorcraft FL-820-S)..... <b>B329</b> <b>Air</b> (Motorcraft FA-1782)..... <b>PA4172</b> <b>Trans.</b> (Motorcraft FT-180)..... <b>20021</b>	F-59 Commercial Chassis w/V10 6.8L Eng. (2016-18) <b>Lube</b> (Motorcraft FL-820-S)..... <b>B329</b> <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Air</b> (Motorcraft FA-1782)..... <b>PA4172</b> <b>Trans.</b> (5 Spd.) (Motorcraft FT180)..... <b>20021</b> <b>Trans.</b> (6 Spd.) (Motorcraft FT-187)..... <b>20028</b>


+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)
F-59 Commercial Chassis w/V10 6.8L Eng. (2019) Lube (Motorcraft FL820S)..... <b>B329</b> Fuel (N/S)..... <b>N/S</b> Air (Motorcraft FA1782)..... <b>PA4172</b> Trans. (Motorcraft FT187)..... <b>20028</b>	F-450 Super Duty w/V8-391 (6.4L) Turbo Diesel Eng. (Cont'd) Lube (w/Screw on Cap) (Wix 57312)..... <b>P7436</b> Fuel Kit (Motorcraft FD4609)..... <b>PF7934 KIT</b> <sup>76</sup> Air (Motorcraft FA1886)..... <b>CA5369</b> Trans. (Motorcraft FT144)..... <b>20005</b> Trans. (Motorcraft FT180)..... <b>20021</b>	F-450 Super Duty w/V8-406 (6.7L) Turbo Diesel Eng. (2021) Lube (Motorcraft FL2051S)..... <b>B7379</b> Fuel (Motorcraft FD4625AA)..... <b>PF46174 KIT</b> Air (Foam) (Motorcraft FA1952).... <b>SA10429</b> Cab Air (Motorcraft FP92)..... <b>PA10103</b> Trans. (6R100) (Motorcraft FT188)..... <b>20029</b> Trans. (6R140) (Motorcraft FT187)..... <b>20028</b>
F-59 Commercial Chassis w/V8 7.3L Eng. (2020) Lube (Motorcraft FL820S)..... <b>B329</b> Fuel (N/S)..... <b>N/S</b> Air (Motorcraft FA1782)..... <b>PA4172</b> Trans. (Motorcraft FT187)..... <b>20028</b>	F-450 Super Duty w/V8-406 (6.7L) Turbo Diesel Eng. (2011-16) Lube (Motorcraft FL2051)..... <b>B7379</b> Fuel Kit (Motorcraft FD4615)..... <b>BF9895 KIT</b> Air (Foam) (Motorcraft FA1909).... <b>PA10011</b> Air (Main) (FA1902)..... <b>PA4433</b> Trans. (6R140) (Motorcraft FT187)..... <b>20028</b>	F-450 Super Duty w/V8-406 (6.7L) Turbo Diesel Eng. (2022) Lube (Motorcraft FL2051S)..... <b>B7379</b> Fuel (Motorcraft FD4625AA)..... <b>PF46174 KIT</b> Air (Foam) (Motorcraft FA1952).... <b>SA10429</b> Cab Air (Motorcraft FP92)..... <b>PA10103</b> Trans. (Motorcraft FT187)..... <b>20028</b>
F-59 Commercial Chassis w/V8 7.3L Eng. (2021) Lube (Motorcraft FL820S)..... <b>B329</b> Fuel (N/S)..... <b>N/S</b> Air (Motorcraft FA1782)..... <b>PA4172</b> Trans. (Motorcraft FT187)..... <b>20028</b>	F-450 Super Duty w/V8-406 (6.7L) Turbo Diesel Eng. (2017) Lube (Motorcraft FL2051S)..... <b>B7379</b> Fuel Kit (Motorcraft FD4625)..... <b>PF46174 KIT</b> Air (Motorcraft FA1927)..... <b>PA10061</b> Cab Air (Motorcraft FP79)..... <b>PA10103</b> Trans. (6R140) (Motorcraft FT187)..... <b>20028</b>	F-450 Super Duty w/V8-406 (6.7L) Turbo Diesel Eng. (2023) Lube (Motorcraft FL2051S)..... <b>B7379</b> Fuel (Motorcraft FD4625AA)..... <b>PF46174 KIT</b> Air (Foam) (Motorcraft FA1952).... <b>SA10429</b> Cab Air (Motorcraft FP92)..... <b>PA10103</b>
F-450 w/V10-415 (6.8L) Eng. (2008-09) Lube (Motorcraft FL820S)..... <b>B329</b> In-Line Fuel (Motorcraft FG1083)..... <b>BF7802</b> Air (Motorcraft FA1883)..... <b>PA4323</b> Crankcase Breather (Motorcraft FA1047)..... <b>SA2159</b>	F-450 Super Duty w/V8-406 (6.7L) Turbo Diesel Eng. (2018) Lube (Motorcraft FL-2051-S)..... <b>B7379</b> Fuel Kit (Motorcraft FD-4625)..... <b>PF46174 KIT</b> Air (Motorcraft FA-1927)..... <b>PA10061</b> Cab Air (Motorcraft FP79)..... <b>PA10103</b> Trans. (5R110W) (Motorcraft FT-180)..... <b>20021</b> Trans. (6R140) (Motorcraft FT187)..... <b>20028</b>	F-450 Super Duty w/V8-406 (6.7L) Turbo Diesel Eng. (2000-01) Lube (Motorcraft FL820S)..... <b>B329</b> In-Line Fuel (Motorcraft FG872)... <b>BF1166</b> Air (Motorcraft FA1632)..... <b>PA4075</b> Cab Air (F65Z19N619AB)..... <b>PA4133</b> Crankcase Breather (Motorcraft FA1047)..... <b>SA2159</b> Trans. Pan-Type (4R100 4 X 2) (Motorcraft FT113)..... <b>18264</b> Trans. Pan-Type (4R100 4 X 4) (Motorcraft FT114)..... <b>18265</b>
F-450 Super Duty w/V8-363 (6.0L) Turbo Diesel Eng. Lube (w/o Screw-on Cap) (3C3Z6731AA)..... <b>P7235</b> Lube (w/Screw on Cap) (Wix 57312)..... <b>P7436</b> Fuel Kit (3C3Z-9N184-AA)..... <b>PF7812 KIT</b> <sup>76</sup> Air (Motorcraft FA1778)..... <b>CA4999</b> Trans. (Ele.) (Motorcraft FT145)... <b>P7247</b> Trans. (Pan-Type) (3C3Z-7A098-AA)..... <b>20005</b>	F-450 Super Duty w/V8-406 (6.7L) Turbo Diesel Eng. (2019) Lube (Motorcraft FL2051S)..... <b>B7379</b> Fuel Kit (Motorcraft FD4625)..... <b>PF46174 KIT</b> Air (Motorcraft FA1927)..... <b>PA10061</b> Cab Air (Motorcraft FP79)..... <b>PA10103</b> Trans. (Motorcraft FT187)..... <b>20028</b>	F-450 Super Duty w/V10-415 (6.8L) Eng. (2002-03) Lube (Motorcraft FL820S)..... <b>B329</b> In-Line Fuel (Motorcraft FG872)... <b>BF1166</b> Air (Motorcraft FA1632)..... <b>PA4075</b> Crankcase Breather (Motorcraft FA1047)..... <b>SA2159</b> Trans. Pan-Type (4R100 4 X 2) (Motorcraft FT113)..... <b>18264</b> Trans. Pan-Type (4R100 4 X 4) (Motorcraft FT114)..... <b>18265</b>
F-450 Super Duty w/V8-378 (6.2L) Eng. (2019) Lube (Motorcraft FL820S)..... <b>B329</b> Fuel (N/S)..... <b>N/S</b> Air (Motorcraft FA1928)..... <b>PA10068</b> Cab Air (Motorcraft FP79)..... <b>PA10103</b> Trans. (6R100) (Motorcraft FT188)..... <b>20029</b> Trans. (6R140) (Motorcraft FT187)..... <b>20028</b>	F-450 Super Duty w/V8-406 (6.7L) Turbo Diesel Eng. (2020) Lube (Motorcraft FL2051S)..... <b>B7379</b> Fuel (Motorcraft FD4625AA)..... <b>PF46174 KIT</b> Air (Motorcraft FA1951)..... <b>PA10428</b> Air (Pre-Filter) (Motorcraft FA1952)..... <b>SA10429</b> Cab Air (Motorcraft FP79)..... <b>PA10103</b> Trans. (6R100) (Motorcraft FT188)..... <b>20029</b> Trans. (6R140) (Motorcraft FT187)..... <b>20028</b>	F-450 Super Duty w/V10-415 (6.8L) Eng. (2004) Lube (Motorcraft FL820S)..... <b>B329</b> In-Line Fuel (Motorcraft FG872)... <b>BF1166</b> Air (Motorcraft FA1632)..... <b>PA4075</b> Trans. Pan-Type (4R100 4 X 2) (Motorcraft FT113)..... <b>18264</b> Trans. Pan-Type (4R100 4 X 4) (Motorcraft FT114)..... <b>18265</b>
F-450 Super Duty w/V8-378 (6.2L) Eng. (2020) Lube (Motorcraft FL820S)..... <b>B329</b> Fuel (N/S)..... <b>N/S</b> Air (Motorcraft FA1950)..... <b>PA10427</b> Cab Air (Motorcraft FP79)..... <b>PA10103</b> Trans. (6 Spd.) (Motorcraft FT188)..... <b>20029</b>		
F-450 Super Duty w/V8-391 (6.4L) Turbo Diesel Eng. Lube (w/o Screw-on Cap) (3C3Z-6731-AA)..... <b>P7235</b>		

<sup>76</sup> Contains Pri. and Sec. Fuel Elements.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)
F-450 Super Duty w/V10-415 (6.8L) Eng. (2005-07) <b>Lube</b> (Motorcraft FL820S)..... <b>B329</b> <b>In-Line Fuel</b> (Motorcraft FG1083)..... <b>BF7802</b> <b>Air</b> (Motorcraft FA1782)..... <b>PA4172</b> <b>Trans. Ele.</b> (5R110W) (Motorcraft FT145)..... <b>P7247</b>	F-450 Super Duty w/V8-445 (7.3L) Turbo Diesel Eng. (1999-2003) (Cont'd) <b>Trans.</b> (4R100 4 X 4) (Motorcraft FT114)..... <b>18265</b> <b>Panel Air for Opt. Wix Hsg.</b> ..... <b>83490</b> F-450 Super Duty w/V8-445 (7.3L) Eng. (2020) <b>Lube</b> (Motorcraft FL820S)..... <b>B329</b> <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Air</b> (Motorcraft FA1950)..... <b>PA10427</b> <b>Cab Air</b> (Motorcraft FP79)..... <b>PA10103</b> <b>Trans.</b> (6R100) (Motorcraft FT188)..... <b>20029</b> <b>Trans.</b> (6R140) (Motorcraft FT187)..... <b>20028</b>	F-550 Super Duty w/V8-378 (6.2L) Eng. (2019) (Cont'd) <b>Trans.</b> (6R140) (Motorcraft FT187)..... <b>20028</b> F-550 Super Duty w/V8-378 (6.2L) Eng. (2020) <b>Lube</b> (Motorcraft FL820S)..... <b>B329</b> <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Air</b> (Motorcraft FA1950)..... <b>PA10427</b> <b>Cab Air</b> (Motorcraft FP79)..... <b>PA10103</b> <b>Trans.</b> (6R100) (Motorcraft FT188)..... <b>20029</b> <b>Trans.</b> (6R140) (Motorcraft FT187)..... <b>20028</b>
F-450 Super Duty w/V10-415 (6.8L) Eng. (2008-10) <b>Lube</b> (Motorcraft FL820S)..... <b>B329</b> <b>In-Line Fuel</b> (Motorcraft FG1083)..... <b>BF7802</b> <b>Air</b> (Motorcraft FA1883)..... <b>PA4323</b> <b>Trans. Ele.</b> (5R110W) (Motorcraft FT145)..... <b>P7247</b>	F-450 Super Duty w/V8-445 (7.3L) Eng. (2021) <b>Lube</b> (Motorcraft FL820S)..... <b>B329</b> <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Air</b> (Motorcraft FA1950)..... <b>PA10427</b> <b>Cab Air</b> (Motorcraft FP79)..... <b>PA10103</b> <b>Trans.</b> (6R100) (Motorcraft FT188)..... <b>20029</b> <b>Trans.</b> (6R140) (Motorcraft FT187)..... <b>20028</b>	F-550 Super Duty w/V8-378 (6.2L) Eng. (2023) <b>Lube</b> (Motorcraft FL820S)..... <b>B329</b> <b>Air</b> (Motorcraft FA1950)..... <b>PA10427</b> <b>Cab Air</b> (Motorcraft FP92)..... <b>PA10103</b>
F-450 Super Duty w/V10-415 (6.8L) Eng. (2011-16) <b>Lube</b> (Motorcraft FL820S)..... <b>B329</b> <b>In-Line Fuel</b> (Motorcraft FG1083)..... <b>BF7802</b> <b>Air</b> (Motorcraft FA1883)..... <b>PA4323</b> <b>Trans. Ele.</b> (5R110W) (Motorcraft FT145)..... <b>P7247</b> <b>Trans.</b> (6R140) (Motorcraft FT187)..... <b>20028</b>	F-450 Super Duty w/V8-445 (7.3L) Eng. (2022) <b>Lube</b> (Motorcraft FL820S)..... <b>B329</b> <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Air</b> (Motorcraft FA1950)..... <b>PA10427</b> <b>Cab Air</b> (Motorcraft FP92)..... <b>PA10103</b> <b>Trans.</b> (Motorcraft FT187)..... <b>20028</b>	F-550 Super Duty w/V8-391 (6.4L) Turbo Diesel Eng. <b>Lube</b> (w/o Screw-on Cap) (3C3Z-6731-AA)..... <b>P7235</b> <b>Lube</b> (w/Screw on Cap) (Wix 57312)..... <b>P7436</b> <b>Fuel Kit</b> (Motorcraft FD4609)..... <b>PF7934 KIT</b> <sup>76</sup> <b>Air</b> (Motorcraft FA1886)..... <b>CA5369</b> <b>Trans.</b> (Motorcraft FT144)..... <b>20005</b> <b>Trans.</b> (Motorcraft FT180)..... <b>20021</b>
F-450 Super Duty w/V10-415 (6.8L) Eng. (2017) <b>Lube</b> (Motorcraft FL-820-S)..... <b>B329</b> <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Air</b> (Motorcraft FA-1928)..... <b>PA10068</b> <b>Cab Air</b> (Motorcraft FP79)..... <b>PA10103</b> <b>Trans.</b> (Motorcraft FT-180)..... <b>20021</b>	F-450 Super Duty w/V8-445 (7.3L) Eng. (2023) <b>Lube</b> (Motorcraft FL820S)..... <b>B329</b> <b>Air</b> (Motorcraft FA1950)..... <b>PA10427</b> <b>Cab Air</b> (Motorcraft FP92)..... <b>PA10103</b>	F-550 Super Duty w/V8-406 (6.7L) Turbo Diesel Eng. (2011-16) <b>Lube</b> (Motorcraft FL2051)..... <b>B7379</b> <b>Fuel Kit</b> (Motorcraft FD4615)..... <b>BF9895 KIT</b> <b>Air</b> (Foam) (Motorcraft FA1909)..... <b>PA10011</b> <b>Air</b> (Main) (Motorcraft FA1902)..... <b>PA4433</b> <b>Trans.</b> (6R140) (Motorcraft FT187)..... <b>20028</b>
F-450 Super Duty w/V10-415 (6.8L) Eng. (2018) <b>Lube</b> (Motorcraft FL820S)..... <b>B329</b> <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Air</b> (Motorcraft FA1928)..... <b>PA10068</b> <b>Cab Air</b> (Motorcraft FP79)..... <b>PA10103</b> <b>Trans.</b> (Motorcraft FT187)..... <b>20028</b>	F-450 Super Duty w/V8-460 (7.5L) Eng. <b>Lube</b> ..... <b>B2+</b> <b>Fuel</b> ..... <b>BF1166</b> <b>Air</b> ..... <b>PA2164</b> <b>Cab Air</b> (Opt.) (Motorcraft FP7A)..... <b>PA4133</b> <b>Crankcase Breather</b> ..... <b>SA2047</b>	F-550 Super Duty w/V8-406 (6.7L) Turbo Diesel Eng. (2017) <b>Lube</b> (Motorcraft FL-2051-S)..... <b>B7379</b> <b>Fuel Kit</b> (Motorcraft FD-4625)..... <b>PF46174 KIT</b> <b>Air</b> (Motorcraft FA-1927)..... <b>PA10061</b> <b>Cab Air</b> (Motorcraft FP79)..... <b>PA10103</b> <b>Trans.</b> (Motorcraft FT-180)..... <b>20021</b>
F-450 Super Duty w/V10-415 (6.8L) Eng. (2019) <b>Lube</b> (Motorcraft FL820S)..... <b>B329</b> <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Air</b> (Motorcraft FA1928)..... <b>PA10068</b> <b>Cab Air</b> (Motorcraft FP79)..... <b>PA10103</b> <b>Trans.</b> (Motorcraft FT187)..... <b>20028</b>	F-550 Super Duty w/V8-363 (6.0L) Turbo Diesel Eng. <b>Lube</b> (w/o Screw-on Cap) (3C3Z6731AA)..... <b>P7235</b> <b>Lube</b> (w/Screw on Cap) (Wix 57312)..... <b>P7436</b> <b>Fuel Kit</b> (3C3Z-9N184-AA)..... <b>PF7812 KIT</b> <sup>76</sup> <b>Air</b> (Motorcraft FA1778)..... <b>CA4999</b> <b>Trans.</b> (Ele.) (Motorcraft FT145)..... <b>P7247</b> <b>Trans.</b> (Pan-Type) (3C3Z-7A098-AA)..... <b>20005</b>	F-550 Super Duty w/V8-406 (6.7L) Turbo Diesel Eng. (2018) <b>Lube</b> (Motorcraft FL2051S)..... <b>B7379</b> <b>Fuel Kit</b> (Motorcraft FD4625)..... <b>PF46174 KIT</b> <b>Air</b> (Motorcraft FA1927)..... <b>PA10061</b> <b>Cab Air</b> (Motorcraft FP79)..... <b>PA10103</b> <b>Trans.</b> (Motorcraft FT187)..... <b>20028</b>
F-450 Super Duty w/V8-445 (7.3L) Turbo Diesel Eng. (1999-2003) <b>Lube</b> (Motorcraft FL1995)..... <b>B7039</b> <b>Fuel Ele.</b> (Motorcraft FD4596)..... <b>PF7698</b> <b>Air</b> (Panel To 12/7/1998) (Motorcraft FA1675)..... <b>PA4110</b> <b>Air</b> (Panel 12/7/1998-on) (Motorcraft FA1750)..... <b>PA4148</b> <b>Air</b> (Opt. Channel Flow) (Motorcraft FA1757)..... <b>CA5793</b> <b>Cab Air</b> (Opt.) (Motorcraft FP7A)..... <b>PA4133</b> <b>Trans.</b> (4R100 4 X 2) (Motorcraft FT113)..... <b>18264</b>	F-550 Super Duty w/V8-378 (6.2L) Eng. (2019) <b>Lube</b> (Motorcraft FL820S)..... <b>B329</b> <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Air</b> (Motorcraft FA1928)..... <b>PA10068</b> <b>Cab Air</b> (Motorcraft FP79)..... <b>PA10103</b> <b>Trans.</b> (6R100) (Motorcraft FT188)..... <b>20029</b>	F-550 Super Duty w/V8-406 (6.7L) Turbo Diesel Eng. (2019) <b>Lube</b> (Motorcraft FL2051S)..... <b>B7379</b> <b>Fuel Kit</b> (Motorcraft FD4625)..... <b>PF46174 KIT</b> <b>Air</b> (Motorcraft FA1927)..... <b>PA10061</b> <b>Cab Air</b> (Motorcraft FP79)..... <b>PA10103</b> <b>Trans.</b> (Motorcraft FT187)..... <b>20028</b>

\* See Product Guide for Variations of This Number. <sup>76</sup> Contains Pri. and Sec. Fuel Elements.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>FORD</b> <b>Trucks &amp; Buses (cont'd)</b>	<b>FORD</b> <b>Trucks &amp; Buses (cont'd)</b>	<b>FORD</b> <b>Trucks &amp; Buses (cont'd)</b>
F-550 Super Duty w/V8-406 (6.7L) Turbo Diesel Eng. (2020) <b>Lube</b> (Motorcraft FL2051S)..... <b>B7379</b> <b>Fuel</b> (Motorcraft FD4625AA)..... <b>PF46174 KIT</b> <b>Air</b> (Motorcraft FA1951)..... <b>PA10428</b> <b>Air</b> (Pre-Filter) (Motorcraft FA1952)..... <b>SA10429</b> <b>Cab Air</b> (Motorcraft FP79)..... <b>PA10103</b> <b>Trans.</b> (6R100) (Motorcraft FT188)..... <b>20029</b> <b>Trans.</b> (6R140) (Motorcraft FT187)..... <b>20028</b>	F-550 Super Duty w/V10-415 (6.8L) Eng. (2004) (Cont'd) <b>Trans. Pan-Type</b> (4R100 4 X 2) (Motorcraft FT113)..... <b>18264</b> <b>Trans. Pan-Type</b> (4R100 4 X 4) (Motorcraft FT114)..... <b>18265</b> F-550 Super Duty w/V10-415 (6.8L) Eng. (2005-07) <b>Lube</b> (Motorcraft FL820S)..... <b>B329</b> <b>In-Line Fuel</b> (Motorcraft FG1083)..... <b>BF7802</b> <b>Air</b> (Motorcraft FA1782)..... <b>PA4172</b> <b>Trans. Ele.</b> (5R110W) (Motorcraft FT145)..... <b>P7247</b> F-550 Super Duty w/V10-415 (6.8L) Eng. (2008-10) <b>Lube</b> (Motorcraft FL820S)..... <b>B329</b> <b>In-Line Fuel</b> (Motorcraft FG1083)..... <b>BF7802</b> <b>Air</b> (Motorcraft FA1883)..... <b>PA4323</b> <b>Trans. Ele.</b> (5R110W) (Motorcraft FT145)..... <b>P7247</b> F-550 Super Duty w/V10-415 (6.8L) Eng. (2011-16) <b>Lube</b> (Motorcraft FL820S)..... <b>B329</b> <b>In-Line Fuel</b> (Motorcraft FG1083)..... <b>BF7802</b> <b>Air</b> (Motorcraft FA1883)..... <b>PA4323</b> <b>Trans. Ele.</b> (5R110W) (Motorcraft FT145)..... <b>P7247</b> <b>Trans.</b> (6R140) (Motorcraft FT187)..... <b>20028</b> F-550 Super Duty w/V10-415 (6.8L) Eng. (2017) <b>Lube</b> (Motorcraft FL820-S)..... <b>B329</b> <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Air</b> (Motorcraft FA-1928)..... <b>PA10068</b> <b>Cab Air</b> (Motorcraft FP79)..... <b>PA10103</b> <b>Trans.</b> (Motorcraft FT-180)..... <b>20021</b> F-550 Super Duty w/V10-415 (6.8L) Eng. (2018) <b>Lube</b> (Motorcraft FL820S)..... <b>B329</b> <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Air</b> (Motorcraft FA1928)..... <b>PA10068</b> <b>Cab Air</b> (Motorcraft FP79)..... <b>PA10103</b> <b>Trans.</b> (Motorcraft FT187)..... <b>20028</b> F-550 Super Duty w/V10-415 (6.8L) Eng. (2019) <b>Lube</b> (Motorcraft FL820S)..... <b>B329</b> <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Air</b> (Motorcraft FA1928)..... <b>PA10068</b> <b>Cab Air</b> (Motorcraft FP79)..... <b>PA10103</b> <b>Trans.</b> (Motorcraft FT187)..... <b>20028</b> F-550 Super Duty w/V8-445 (7.3L) Turbo Diesel Eng. (1999-2003) <b>Lube</b> (Motorcraft FL1995)..... <b>B7039</b> <b>Fuel Ele.</b> (Motorcraft FD4596)..... <b>PF7698</b> <b>Air</b> (Panel To 12/7/1998) (Motorcraft FA1675)..... <b>PA4110</b>	F-550 Super Duty w/V8-445 (7.3L) Turbo Diesel Eng. (1999-2003) (Cont'd) <b>Air</b> (Panel 12/7/1998-on) (Motorcraft FA1750)..... <b>PA4148</b> <b>Air</b> (Opt. Channel Flow) (Motorcraft FA1757)..... <b>CA5793</b> <b>Cab Air</b> (Opt.) (Motorcraft FP7A)..... <b>PA4133</b> <b>Trans.</b> (4R100 RWD) (Motorcraft FT113)..... <b>18264</b> <b>Trans.</b> (4R100 4WD) (Motorcraft FT114)..... <b>18265</b> <b>Panel Air for Opt. Wix Hsg.</b> ..... <b>83490</b> F-550 Super Duty w/V8-445 (7.3L) Gas Eng. (2020) <b>Lube</b> (Motorcraft FL820S)..... <b>B329</b> <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Air</b> (Pre-Filter) (Motorcraft FA1952)..... <b>SA10429</b> <b>Air</b> (Motorcraft FA1951)..... <b>PA10428</b> <b>Cab Air</b> (Motorcraft FP79)..... <b>PA10103</b> <b>Trans.</b> (6R100) (Motorcraft FT188)..... <b>20029</b> <b>Trans.</b> (6R140) (Motorcraft FT187)..... <b>20028</b> F-550 Super Duty w/V8-445 (7.3L) Gas Eng. (2021) <b>Lube</b> (Motorcraft FL820S)..... <b>B329</b> <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Air</b> (Motorcraft FA1950)..... <b>PA10427</b> <b>Cab Air</b> (Motorcraft FP79)..... <b>PA10103</b> <b>Trans.</b> (6R100) (Motorcraft FT188)..... <b>20029</b> <b>Trans.</b> (6R140) (Motorcraft FT187)..... <b>20028</b> F-550 Super Duty w/V8-445 (7.3L) Gas Eng. (2022) <b>Lube</b> (Motorcraft FL820S)..... <b>B329</b> <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Air</b> (Motorcraft FA1950)..... <b>PA10427</b> <b>Cab Air</b> (Motorcraft FP79)..... <b>PA10103</b> <b>Trans.</b> (Motorcraft FT187)..... <b>20028</b> F-550 Super Duty w/V8-445 (7.3L) Gas Eng. (2023) <b>Lube</b> (Motorcraft FL820S)..... <b>B329</b> <b>Air</b> (Motorcraft FA1950)..... <b>PA10427</b> <b>Cab Air</b> (Motorcraft FP92)..... <b>PA10103</b> <b>Trans.</b> (Motorcraft FT187)..... <b>20028</b> F600 w/V8 330 4.9L Eng. <b>Lube Ele.</b> (C4TE-6744-A)..... <b>P80-HD</b> <b>Lube Spin-on</b> (B7A-6714-A)..... <b>B2+</b> <b>Fuel</b> ..... <b>PF827</b> F600 w/6.1L Gas Eng. <b>Lube</b> (D3HF6714AA)..... <b>BT251</b> <b>Fuel In-Line</b> (Motorcraft FG872)..... <b>BF1166</b> <b>Fuel Spin-on</b> (E6HZ9365C)..... <b>BF790</b> <b>5 1/2 In. Air</b> (8 9/32 In. I.D.) (Motorcraft FA718)..... <b>PA2483</b>
F-550 Super Duty w/V8-406 (6.7L) Turbo Diesel Eng. (2021) <b>Lube</b> (Motorcraft FL2051S)..... <b>B7379</b> <b>Fuel</b> (Motorcraft FD4625AA)..... <b>PF46174 KIT</b> <b>Air</b> (Foam) (Motorcraft FA1952).... <b>SA10429</b> <b>Air</b> (Motorcraft FA1951)..... <b>PA10428</b> <b>Cab Air</b> (Motorcraft FP79)..... <b>PA10103</b> <b>Trans.</b> (6R100) (Motorcraft FT188)..... <b>20029</b> <b>Trans.</b> (6R140) (Motorcraft FT187)..... <b>20028</b>	F-550 Super Duty w/V10-415 (6.8L) Eng. (2022) <b>Lube</b> (Motorcraft FL2051S)..... <b>B7379</b> <b>Fuel</b> (Motorcraft FD4625AA)..... <b>PF46174 KIT</b> <b>Air</b> (Foam) (Motorcraft FA1952).... <b>SA10429</b> <b>Air</b> (Motorcraft FA1951)..... <b>PA10428</b> <b>Cab Air</b> (Motorcraft FP92)..... <b>PA10103</b> <b>Trans.</b> (Motorcraft FT187)..... <b>20028</b>	F-550 Super Duty w/V8-445 (7.3L) Gas Eng. (2022) <b>Lube</b> (Motorcraft FL820S)..... <b>B329</b> <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Air</b> (Motorcraft FA1950)..... <b>PA10427</b> <b>Cab Air</b> (Motorcraft FP92)..... <b>PA10103</b> <b>Trans.</b> (Motorcraft FT187)..... <b>20028</b>
F-550 Super Duty w/V10-415 (6.8L) Eng. (1999-2001) <b>Lube</b> (Motorcraft FL820S)..... <b>B329</b> <b>In-Line Fuel</b> (Motorcraft FG872).... <b>BF1166</b> <b>Air</b> (Motorcraft FA1632)..... <b>PA4075</b> <b>Cab Air</b> (F65Z19N619AB)..... <b>PA4133</b> <b>Crankcase Breather</b> (Motorcraft FA1047)..... <b>SA2159</b> <b>Trans. Pan-Type</b> (4R100 4 X 2) (Motorcraft FT113)..... <b>18264</b> <b>Trans. Pan-Type</b> (4R100 4 X 4) (Motorcraft FT114)..... <b>18265</b>	F-550 Super Duty w/V10-415 (6.8L) Eng. (2002-03) <b>Lube</b> (Motorcraft FL820S)..... <b>B329</b> <b>In-Line Fuel</b> (Motorcraft FG872).... <b>BF1166</b> <b>Air</b> (Motorcraft FA1632)..... <b>PA4075</b> <b>Crankcase Breather</b> (Motorcraft FA1047)..... <b>SA2159</b> <b>Trans. Pan-Type</b> (4R100 4 X 2) (Motorcraft FT113)..... <b>18264</b> <b>Trans. Pan-Type</b> (4R100 4 X 4) (Motorcraft FT114)..... <b>18265</b>	F-550 Super Duty w/V8-445 (7.3L) Gas Eng. (2023) <b>Lube</b> (Motorcraft FL820S)..... <b>B329</b> <b>Air</b> (Motorcraft FA1950)..... <b>PA10427</b> <b>Cab Air</b> (Motorcraft FP92)..... <b>PA10103</b>
F-550 Super Duty w/V10-415 (6.8L) Eng. (2004) <b>Lube</b> (Motorcraft FL820S)..... <b>B329</b> <b>In-Line Fuel</b> (Motorcraft FG872).... <b>BF1166</b> <b>Air</b> (Motorcraft FA1632)..... <b>PA4075</b>	F-550 Super Duty w/V10-415 (6.8L) Eng. (2004) <b>Lube</b> (Motorcraft FL820S)..... <b>B329</b> <b>In-Line Fuel</b> (Motorcraft FG872).... <b>BF1166</b> <b>Air</b> (Motorcraft FA1632)..... <b>PA4075</b>	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).




<b>FORD Trucks &amp; Buses (cont'd)</b>	<b>FORD Trucks &amp; Buses (cont'd)</b>	<b>FORD Trucks &amp; Buses (cont'd)</b>
F600 w/6.1L Gas Eng. (Cont'd)	F-600 Super Duty w/V8-406 (6.7L) Turbo Diesel Eng. (2020)	F650 w/V8-406 (6.7L) Turbo Diesel Eng. (2021)
5 1/2 In. Air (9 3/4 In. I.D.)	Fuel (Motorcraft FD4625AA).....	Lube (Motorcraft FL2051S).....
(Motorcraft FA717).....	PF46174 KIT	B7379
13 7/8 In. Air (Motorcraft	Foam Air (Motorcraft FA1952).....	Fuel (Motorcraft FD4625AA).....
FA1116).....	SA10429	PF46174 KIT
	Cab Air (Motorcraft FP79).....	Air (Foam) (Motorcraft FA1909)....
	PA10103	PA10011
F600 w/V8 7.0L Eng.	F-600 Super Duty w/V8-406 (6.7L) Turbo Diesel Eng. (2021)	Air (Panel) (Motorcraft FA1923)....
Lube (Motorcraft FL299).....	Fuel (Motorcraft FD4625AA).....	PA4433
BT251	PF46174 KIT	Trans. (Motorcraft FT187).....
Fuel/Water Separator (w/o Drain	Foam Air (Motorcraft FA1952).....	20028
or Sensor Port) (Motorcraft	Cab Air (Motorcraft FP79).....	
FD3368).....	PA10103	F650 w/V8-406 (6.7L) Turbo Diesel Eng. (2022)
BF1224		Lube (Motorcraft FL2051S).....
Fuel/Water Separator (w/Drain	F-600 Super Duty w/V8-406 (6.7L) Turbo Diesel Eng. (2022)	Lube (Motorcraft FL2051S).....
(Motorcraft FD3368).....	Lube (Motorcraft FL2051S).....	B7379
BF1223	B7379	Fuel (Motorcraft FD4637).....
Fuel/Water Separator (w/Drain &	Fuel (Motorcraft FD4625AA).....	PF46172 KIT
Sensor Port) (Motorcraft FD3368).	PF46174 KIT	Air (Foam) (Motorcraft FA1909)....
BF1223-SP	SA10429	PA10011
Fuel/Water Separator (Open End	Cab Air (Motorcraft FP79).....	Air (Panel) (Motorcraft FA1923)....
for Bowl) (Motorcraft FD3368).....	PA10103	PA4433
BF1223-O		Trans. (Motorcraft FT187).....
Fuel Ele. (Motorcraft FG23).....	F-600 Super Duty w/V8-445 (7.3L) Eng. (2020)	20028
PF827	Lube (Motorcraft FL820S).....	F650 w/V8-406 (6.7L) Turbo Diesel Eng. (2023)
5 1/2 In. Air (w/8 9/32 In. I.D.)	B329	Lube (Motorcraft FL2051S).....
(D4HZ9601B).....	N/S	B7379
PA2483	Air (Motorcraft FA1950).....	Fuel (Motorcraft FD4637).....
5 1/2 In. Air (w/9 3/4 In. I.D.)	PA10427	PF46172 KIT
(E1HZ9601A).....	PA10103	Air (Foam) (Motorcraft FA1909)....
PA2472		PA10011
8 In. Air (E0HZ9601A).....	F-600 Super Duty w/V8-445 (7.3L) Eng. (2021)	Trans. (Motorcraft FT187).....
PA2596	Lube (Motorcraft FL820S).....	20028
8 1/16 In. Air (D6HZ9601B).....	B329	F650 Super Duty w/Cat 3126 (7.2L) Eng. (To
PA2548	Fuel (N/S).....	1/2004)
13 7/8 In. Air (F1HZ9601C).....	N/S	Lube (Standard Vers.).....
PA3475	Air (Motorcraft FA1950).....	B76 +
F600 w/L6-473 (7.8L) Turbo Diesel Eng.	PA10427	Lube (Severe Service).....
Fuel (E7HZ9365G).....	PA10103	B76-SS +
BF7608		Fuel/Water Separator
F600 LPO w/6.1L Gas Eng.	F-600 Super Duty w/V8-445 (7.3L) Eng. (2022)	(YC3Z-9365-AC).....
Fuel In-Line (Motorcraft F6872)...	Lube (Motorcraft FL820S).....	BF7806
BF1166	B329	Fuel (1R0751).....
Fuel Spin-on (E6HZ9365C).....	N/S	BF7632
BF790	Air (Motorcraft FA1950).....	Radial Seal O. Air
5 1/2 In. Air (8 9/32 In. I.D.)	PA10427	(YC3Z-9601-FA).....
(Motorcraft FA718).....	PA10103	RS3517
PA2483		Radial Seal XP O. Air
5 1/2 In. Air (9 3/4 In. I.D.)	F650 w/V8-406 (6.7L) Turbo Diesel Eng. (2016)	(YC3Z-9601-FA).....
(Motorcraft FA717).....	Lube (Motorcraft FL-2051-S).....	RS3517XP
PA2472	B7379	Trans. Spin-on (Allison
13 7/8 In. Air (Motorcraft	Fuel Kit (Motorcraft FD-4615).....	29539579).....
FA1116).....	BF9895 KIT	BT8460
PA3475	Foam Air Pre-Cleaner	Trans. Ele. (D. Pan w/o Gskt.)
F600 LPO w/V8 7.0L Eng.	(Motorcraft FA-1909).....	(Allison 29537966).....
Lube (Motorcraft FL299).....	PA10011	20003
BT251	Panel Air (Motorcraft FA-1902)....	Trans. Ele. (D. Pan w/Gskt.)
Fuel/Water Separator (w/o Drain	PA4433	(Allison 29537966).....
or Sensor Port) (Motorcraft	Trans. (Motorcraft FT187).....	20017
FD3368).....	20028	Trans. Ele. (S. Pan w/o Gskt.)
BF1224		(Allison 29537965).....
Fuel/Water Separator (w/Drain	F650 w/V8-406 (6.7L) Turbo Diesel Eng.	20004
(Motorcraft FD3368).....	(2017-18)	Trans. Ele. (S. Pan w/Gskt.)
BF1223	Lube (Motorcraft FL-2051-S).....	(Allison 29537965).....
Fuel/Water Separator (w/Drain &	B7379	20016
Sensor Port) (Motorcraft FD3368).	Fuel Kit (Motorcraft FD4626).....	F650 Super Duty w/Cat 3126 (7.2L) Eng.
BF1223-SP	PF46172 KIT	(1/2004-on)
Fuel/Water Separator (Open End	Foam Air Pre-Cleaner	Lube (1R1807).....
for Bowl) (Motorcraft FD3368).....	(Motorcraft FA-1909).....	B7700 +
BF1223-O	PA10011	Fuel/Water Separator
Fuel Ele. (Motorcraft FG23).....	Panel Air (Motorcraft FA1923)....	(YC3Z-9365-AC).....
PF827	PA4433	BF7806
5 1/2 In. Air (w/8 9/32 In. I.D.)	Trans. (Motorcraft FT187).....	BF7632
(D4HZ9601B).....	20028	Radial Seal Air (YC3Z-9601-FA).
PA2483	Trans. (5R110W) (Motorcraft	RS3517
5 1/2 In. Air (w/9 3/4 In. I.D.)	FT180).....	Radial Seal XP Air
(E1HZ9601A).....	20021	(YC3Z-9601-FA).....
PA2472	F650 w/V8-406 (6.7L) Turbo Diesel Eng. (2019)	RS3517XP
8 In. Air (E0HZ9601A).....	Lube (Motorcraft FL2051S).....	Trans. Spin-on (Allison
PA2596	B7379	29539579).....
8 1/16 In. Air (D6HZ9601B).....	Fuel Kit (Motorcraft FD4626).....	BT8460
PA2548	PF46172 KIT	Trans. Ele. (D. Pan w/o Gskt.)
13 7/8 In. Air (F1HZ9601C).....	Foam Air Pre-Cleaner	(Allison 29537966).....
PA3475	(Motorcraft FA-1909).....	20017
	PA10011	Trans. Ele. (S. Pan w/o Gskt.)
	Panel Air (Motorcraft FA1923)....	(Allison 29537965).....
	PA4433	20004
	Trans. (Motorcraft FT187).....	Trans. Ele. (S. Pan w/Gskt.)
	20028	(Allison 29537965).....
		20016

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>FORD</b> <b>Trucks &amp; Buses (cont'd)</b>	<b>FORD</b> <b>Trucks &amp; Buses (cont'd)</b>	<b>FORD</b> <b>Trucks &amp; Buses (cont'd)</b>
F650 Super Duty w/Cat C7 (7.2L) Eng. <b>Lube</b> (1R1807)..... <b>B7700 +</b>	F650 w/Cummins ISB (5.9L) Eng. (2008-on) <b>Lube</b> (3937736)..... <b>B7177</b>	F650 w/Cummins ISB 200 (6.7L) Eng. (Cont'd) <b>Diesel Exhaust Fluid</b> (2010 Emissions) (2888182)..... <b>PE17000</b>
<b>6 7/32 In. Fuel/Water Separator</b> (1-14 Thd.) (YC3Z-9365-AC)..... <b>BF7806</b>	<b>Fuel/Water Separator Ele.</b> ..... <b>PF7777</b>	F650 w/IHC VT365 (6.0L) Turbo Diesel Eng. <b>Lube</b> (w/o Screw on Cap) (3C3Z-6731-AA)..... <b>P7235</b>
<b>7 3/8 In. Fuel/Water Separator</b> (1-14 Thd.) (175-2949)..... <b>BF1268</b>	<b>Fuel/Water Separator Spin-on</b> (M20 x 1.5 Thd.)..... <b>BF1271</b>	<b>Lube</b> (w/Screw on Cap) (Wix 57312)..... <b>P7436</b>
<b>7 13/32 In. Fuel/Water Separator</b> (1-12 Thd.) (Racor RAIS6484)..... <b>BF7759</b>	<b>Fuel/Water Separator Spin-on</b> (1-14 Thd.) (Fleetguard FS19596)..... <b>BF1293-SPS</b>	<b>Fuel</b> (Motorcraft FD4596)..... <b>PF7698</b>
<b>P. Fuel</b> (1R0751)..... <b>BF7632</b>	<b>Fuel</b> (Fleetguard FF5632)..... <b>BF7940</b>	<b>Channel Flow Air</b> (7 5/16 In. to 11 7/16 In. O.D.) (Motorcraft FA1753)..... <b>CA5366</b>
<b>Radial Seal Air</b> (YC3Z-9601-FA). <b>RS3517</b>	<b>Channel Flow Air</b> (Motorcraft FA1889)..... <b>CA5514</b>	<b>Channel Flow Air</b> (7 31/32 In. to 12 3/32 In. O.D.) (Motorcraft FA1778)..... <b>CA4999</b>
<b>Radial Seal XP Air</b> (YC3Z-9601-FA)..... <b>RS3517XP</b>	<b>Air Dryer</b> (Bendix 109493)..... <b>BA5373</b>	<b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b>
<b>Channel Flow Air</b> (Motorcraft FA1889)..... <b>CA5514</b>	<b>Crankcase Breather</b> (4936636).... <b>CV15010</b>	<b>Trans. Ele.</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Air Dryer</b> (Bendix 109493)..... <b>BA5373</b>	<b>Coolant</b> (Fleetguard WF2053)..... <b>BW5139</b>	<b>Trans. Ele.</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Trans. Ele.</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Trans. Ele.</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	F650 w/V10-415 (6.8L) Eng. (2012-15) <b>Lube</b> (Motorcraft FL820S)..... <b>B329</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Air</b> (Motorcraft FA1883)..... <b>PA4323</b>
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Trans.</b> (Motorcraft FT187)..... <b>20028</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	F650 w/V10-415 (6.8L) Eng. (2016) <b>Lube</b> (Motorcraft FL820S)..... <b>B329</b>
F650 w/Cummins ISB (5.9L) Eng. (To 2007) <b>Lube</b> (3937736)..... <b>B7177</b>	F650 w/Cummins ISB 200 (6.7L) Eng. <b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b>	<b>Air</b> (Motorcraft FA1923)..... <b>PA4433</b>
<b>Fuel/Water Separator Ele.</b> ..... <b>PF7777</b>	<b>Fuel/Water Separator Ele.</b> (3942470)..... <b>PF7777</b>	<b>Trans.</b> (Motorcraft FT187)..... <b>20028</b>
<b>Fuel/Water Separator Spin-on</b> (M20 x 1.5 Thd.)..... <b>BF1271</b>	<b>Fuel/Water Separator Spin-on</b> (4934879)..... <b>BF1378-SPS</b>	F650 w/V10-415 (6.8L) Eng. (2017-18) <b>Lube</b> (Motorcraft FL820S)..... <b>B329</b>
<b>Fuel/Water Separator Spin-on</b> (1-14 Thd.) (Fleetguard FS19596)..... <b>BF1293-SPS</b>	<b>Fuel/Water Separator</b> (w/Drain) (Motorcraft FD4608)..... <b>BF7806</b>	<b>Fuel</b> (N/S)..... <b>N/S</b>
<b>Fuel</b> (Fleetguard FF5632)..... <b>BF7940</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (Motorcraft FD4608)..... <b>BF7806-O</b>	<b>Air</b> (Motorcraft FA1923)..... <b>PA4433</b>
<b>Radial Seal Air</b> (Don. P532966).... <b>RS3517</b>	<b>Fuel</b> (Fleetguard FF5632)..... <b>BF7940</b>	<b>Trans.</b> (5R110W) (Motorcraft FT180)..... <b>20021</b>
<b>Radial Seal XP Air</b> (Don. P532966)..... <b>RS3517XP</b>	<b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b>	<b>Trans.</b> (Motorcraft FT187)..... <b>20028</b>
<b>Air Dryer</b> (Bendix 109493)..... <b>BA5373</b>	<b>Channel Flow Air</b> (Motorcraft FA1889)..... <b>CA5514</b>	F650 w/V10-415 (6.8L) Eng. (2019) <b>Lube</b> (Motorcraft FL820S)..... <b>B329</b>
<b>Crankcase Breather</b> (4936636).... <b>CV15010</b>	<b>Panel Air</b> (BC3Z9601A)..... <b>PA4433</b>	<b>Fuel</b> (N/S)..... <b>N/S</b>
<b>Coolant</b> (Fleetguard WF2053)..... <b>BW5139</b>	<b>Foam Air</b> (Motorcraft FA1909).... <b>PA10011</b>	<b>Air</b> (Motorcraft FA1923)..... <b>PA4433</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Air Dryer</b> (Bendix 109493)..... <b>BA5373</b>	<b>Trans.</b> (Motorcraft FT187)..... <b>20028</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Crankcase Breather</b> (Fleetguard CV52001)..... <b>CV15010</b>	F650 w/IHC T444E (7.3L) Turbo Diesel Eng. <b>Lube</b> (Motorcraft FL1995)..... <b>B7039</b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Coolant</b> (Fleetguard WF2071).... <b>BW5071</b>	<b>Fuel</b> (Motorcraft FD4595)..... <b>PF7678</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Radial Seal Air</b> (Motorcraft FA1738)..... <b>RS2863</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Radial Seal XP Air</b> (Motorcraft FA1738)..... <b>RS2863XP</b>
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Trans. Ele.</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Trans. Ele.</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)
F650 w/IHC T444E (7.3L) Turbo Diesel Eng. (Cont'd) <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b>	F700 w/7.0L Gas Carb. Eng. <b>Lube</b> (D3HZ6731B)..... <b>BT251</b> <b>Fuel Spin-on</b> (E6HZ9365C)..... <b>BF790</b> <b>5 1/2 In. Air</b> (8 9/32 In. I.D.) (Motorcraft FA718)..... <b>PA2483</b> <b>5 1/2 In. Air</b> (9 3/4 In. I.D.) (Motorcraft FA717)..... <b>PA2472</b> <b>8 In. Air</b> (E0HZ9601A)..... <b>PA2596</b> <b>8 1/16 In. Air</b> (w/Lid) (D6HZ9601B)..... <b>PA2548</b> <b>13 7/8 In. Air</b> (Motorcraft FA1116)..... <b>PA3475</b>	F700 w/Cummins FD1060 (5.9L) Eng. <b>Radial Seal O. Air</b> (F3HZ9601D)..... <b>RS2863</b> <b>Radial Seal O. XP Air</b> (F3HZ9601D)..... <b>RS2863XP</b> <b>Radial Seal I. Air</b> (F3HZ9R500A)..... <b>RS3501</b> <b>Trans. Pan-Type</b> (MT Series) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (MT Series) (Allison 29510922)..... <b>BT8316-MPG</b>
F650 w/Ford V8-445 (7.3L) Eng. (2021) <b>Lube</b> (Motorcraft FL820S)..... <b>B329</b> <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Air</b> (Foam) (Motorcraft FA1909).... <b>PA10011</b> <b>Air</b> (Motorcraft FA1923)..... <b>PA4433</b> <b>Trans.</b> (Motorcraft FT187)..... <b>20028</b>	F700 w/7.0L Gas FI. Eng. <b>Lube</b> (Motorcraft FL299)..... <b>BT251</b> <b>Fuel In-Line</b> (Motorcraft FG872).... <b>BF1166</b> <b>Fuel Spin-on</b> (E6HZ9365C)..... <b>BF790</b> <b>5 1/2 In. Air</b> (8 9/32 In. I.D.) (Motorcraft FA718)..... <b>PA2483</b> <b>5 1/2 In. Air</b> (9 3/4 In. I.D.) (Motorcraft FA717)..... <b>PA2472</b> <b>8 In. Air</b> (E0HZ9601A)..... <b>PA2596</b> <b>8 1/16 In. Air</b> (w/Lid) (D6HZ9601B)..... <b>PA2548</b> <b>13 7/8 In. Air</b> (Motorcraft FA1116)..... <b>PA3475</b> <b>Trans. Pan-Type</b> (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b>	F750 w/V8-406 (6.7L) Turbo Diesel Eng. (2016) <b>Lube</b> (Motorcraft FL-2051-S)..... <b>B7379</b> <b>Fuel Kit</b> (Motorcraft FD-4615)..... <b>BF9895 KIT</b> <b>Foam Air Pre-Cleaner</b> (Motorcraft FA-1909)..... <b>PA10011</b> <b>Panel Air</b> (Motorcraft FA-1902).... <b>PA4433</b> <b>Trans.</b> (Motorcraft FT187)..... <b>20028</b>
F650 w/Ford V8-445 (7.3L) Eng. (2022) <b>Lube</b> (Motorcraft FL820S)..... <b>B329</b> <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Air</b> (Foam) (Motorcraft FA1909).... <b>PA10011</b> <b>Air</b> (Motorcraft FA1923)..... <b>PA4433</b> <b>Trans.</b> (Motorcraft FT187)..... <b>20028</b>	F700 w/6.1L Gas Eng. <b>Lube</b> (Motorcraft FL299)..... <b>BT251</b> <b>Fuel Ele.</b> (Motorcraft FG789)..... <b>PF827</b> <b>Fuel In-Line</b> (Motorcraft FG872).... <b>BF1166</b> <b>Fuel Spin-on</b> (E6HZ9365C)..... <b>BF790</b> <b>5 1/2 In. Air</b> (8 9/32 In. I.D.) (Motorcraft FA718)..... <b>PA2483</b> <b>5 1/2 In. Air</b> (9 3/4 In. I.D.) (Motorcraft FA717)..... <b>PA2472</b> <b>13 7/8 In. Air</b> (Motorcraft FA1116)..... <b>PA3475</b>	F750 w/V8-406 (6.7L) Turbo Diesel Eng. (2017-18) <b>Lube</b> (Motorcraft FL-2051-S)..... <b>B7379</b> <b>Fuel Kit</b> (Motorcraft FD4626)..... <b>PF46172 KIT</b> <b>Foam Air Pre-Cleaner</b> (Motorcraft FA-1909)..... <b>PA10011</b> <b>Panel Air</b> (Motorcraft FA1923).... <b>PA4433</b> <b>Trans.</b> (Motorcraft FT187)..... <b>20028</b> <b>Trans.</b> (5R110W) (Motorcraft FT180)..... <b>20021</b>
F650 w/Ford V8-445 (7.3L) Eng. (2023) <b>Lube</b> (Motorcraft FL820S)..... <b>B329</b> <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Trans.</b> (Motorcraft FT187)..... <b>20028</b>	F700 w/7.8L Turbo Diesel Eng. <b>F-F Lube</b> (FOHZ6731B)..... <b>[2] BT355</b> <b>Opt. B-P Lube</b> (Motorcraft FL750)..... <b>C750-E</b> <b>Fuel/Water Separator</b> (w/o SP) (E7HZ9N184A)..... <b>BF1204</b> <b>Fuel/Water Separator</b> (w/SP) (E7HZ9N184A)..... <b>BF1204-SP</b> <b>Fuel Spin-on</b> (E6HZ9365C)..... <b>BF790</b> <b>16 In. Air</b> (D5HZ9601D)..... <b>PA2425</b> <b>23 1/2 In. Air</b> (E7HZ9601A)..... <b>PA2726</b> <b>Coolant</b> (E7HZ8A424B)..... <b>BW5136</b>	F750 w/V8-406 (6.7L) Turbo Diesel Eng. (2019) <b>Lube</b> (Motorcraft FL2051S)..... <b>B7379</b> <b>Fuel Kit</b> (Motorcraft FD4626)..... <b>PF46172 KIT</b> <b>Foam Air Pre-Cleaner</b> (Motorcraft FA-1909)..... <b>PA10011</b> <b>Panel Air</b> (Motorcraft FA1923).... <b>PA4433</b> <b>Trans.</b> (Motorcraft FT187)..... <b>20028</b>
F700 w/6-401 (6.6L) Turbo Diesel Eng. (To 1990) <b>Lube</b> (D8NN6714DA)..... <b>BT343</b> <b>Lube</b> (E7HZ6731A)..... <b>[2] B157</b> <b>Fuel/Water Separator</b> (E7HZ-9N184-A)..... <b>BF1204</b> <b>Fuel Spin-on</b> ..... <b>[2] BF7608</b> <b>Air</b> (16 1/2 In.) (E6HZ-9601-A)..... <b>PA2523</b> <b>Air</b> (23 1/2 In.) (E7HZ-9601-A)..... <b>PA2726</b>	F700 w/6-401 (6.6L) Turbo Diesel Eng. (1991-on) <b>Lube</b> (D8NN6714DA)..... <b>BT343</b> <b>Lube</b> (E7HZ6731A)..... <b>[2] B157</b> <b>Fuel/Water Separator</b> (w/o Drain or Sensor Port) (F1HZ9365A)..... <b>BF1224</b> <b>Fuel/Water Separator</b> (w/Drain) (F1HZ9365A)..... <b>BF1223</b> <b>Fuel/Water Separator</b> (w/Drain & Sensor Port) (F1HZ9365A)..... <b>BF1223-SP</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (F1HZ9365A)..... <b>BF1223-O</b> <b>Fuel Spin-on</b> ..... <b>[2] BF7608</b> <b>Air</b> (16 1/2 In.) (E6HZ-9601-A)..... <b>PA2523</b> <b>Air</b> (23 1/2 In.) (E7HZ-9601-A)..... <b>PA2726</b>	F750 w/V8-406 (6.7L) Turbo Diesel Eng. (2021) <b>Lube</b> (Motorcraft FL2051S)..... <b>B7379</b> <b>Fuel</b> (Motorcraft FD4625AA)..... <b>PF46174 KIT</b> <b>Air</b> (Foam) (Motorcraft FA1909).... <b>PA10011</b> <b>Air</b> (Panel) (Motorcraft FA1923).... <b>PA4433</b> <b>Trans.</b> (Motorcraft FT187)..... <b>20028</b>
F700 w/6-401 (6.6L) Turbo Diesel Eng. (1991-on) <b>Lube</b> (D8NN6714DA)..... <b>BT343</b> <b>Lube</b> (E7HZ6731A)..... <b>[2] B157</b> <b>Fuel/Water Separator</b> (w/o Drain or Sensor Port) (F1HZ9365A)..... <b>BF1224</b> <b>Fuel/Water Separator</b> (w/Drain) (F1HZ9365A)..... <b>BF1223</b> <b>Fuel/Water Separator</b> (w/Drain & Sensor Port) (F1HZ9365A)..... <b>BF1223-SP</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (F1HZ9365A)..... <b>BF1223-O</b> <b>Fuel Spin-on</b> ..... <b>[2] BF7608</b> <b>Air</b> (16 1/2 In.) (E6HZ-9601-A)..... <b>PA2523</b> <b>Air</b> (23 1/2 In.) (E7HZ-9601-A)..... <b>PA2726</b>	F700 w/Cat 3208 (10.4L) Eng. <b>Lube</b> (1R0713)..... <b>[2] BT230 +</b> <b>Lube</b> (1R0714)..... <b>[2] B75</b> <b>Lube</b> (9L9200)..... <b>[2] BT364</b> <b>Box-Style Fuel/Water Separator</b> (8N9803)..... <b>BF912</b> <b>P. Fuel Ele.</b> (9M2341)..... <b>PF935</b> <b>P. Fuel Spin-on</b> (1R0740)..... <b>BF970 +</b> <b>S. Fuel Spin-on</b> (1R0750)..... <b>BF7633 +</b> <b>Coolant</b> (w/o Chemicals) (4355142)..... <b>B5089 +</b> <b>Coolant</b> (w/4 Units BTE) (9N3717)..... <b>BW5137</b> <b>Coolant</b> (w/8 Units BTE) (9N3718)..... <b>BW5139</b>	F750 w/V8-406 (6.7L) Turbo Diesel Eng. (2022) <b>Lube</b> (Motorcraft FL2051S)..... <b>B7379</b> <b>Fuel</b> (Motorcraft FD4637)..... <b>PF46172 KIT</b> <b>Air</b> (Foam) (Motorcraft FA1909).... <b>PA10011</b> <b>Air</b> (Panel) (Motorcraft FA1923).... <b>PA4433</b> <b>Trans.</b> (Motorcraft FT187)..... <b>20028</b>
F700 w/6-401 (6.6L) Turbo Diesel Eng. (1991-on) <b>Lube</b> (D8NN6714DA)..... <b>BT343</b> <b>Lube</b> (E7HZ6731A)..... <b>[2] B157</b> <b>Fuel/Water Separator</b> (w/o Drain or Sensor Port) (F1HZ9365A)..... <b>BF1224</b> <b>Fuel/Water Separator</b> (w/Drain) (F1HZ9365A)..... <b>BF1223</b> <b>Fuel/Water Separator</b> (w/Drain & Sensor Port) (F1HZ9365A)..... <b>BF1223-SP</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (F1HZ9365A)..... <b>BF1223-O</b> <b>Fuel Spin-on</b> ..... <b>[2] BF7608</b> <b>Air</b> (16 1/2 In.) (E6HZ-9601-A)..... <b>PA2523</b> <b>Air</b> (23 1/2 In.) (E7HZ-9601-A)..... <b>PA2726</b>	F700 w/7.8L Turbo Diesel Eng. (To 1990) <b>Lube</b> (D8NN6714DA)..... <b>BT343</b> <b>Lube</b> (E7HZ6731A)..... <b>[2] B157</b> <b>Fuel/Water Separator</b> (E7HZ-9N184-A)..... <b>BF1204</b> <b>Fuel Spin-on</b> ..... <b>[2] BF7608</b> <b>Air</b> (16 1/2 In.) (E6HZ-9601-A)..... <b>PA2523</b> <b>Air</b> (23 1/2 In.) (E7HZ-9601-A)..... <b>PA2726</b>	F750 w/V8-406 (6.7L) Turbo Diesel Eng. (2023) <b>Lube</b> (Motorcraft FL2051S)..... <b>B7379</b> <b>Fuel</b> (Motorcraft FD4637)..... <b>PF46172 KIT</b> <b>Air</b> (Foam) (Motorcraft FA1909).... <b>PA10011</b> <b>Trans.</b> (Motorcraft FT187)..... <b>20028</b>
F700 w/6-401 (6.6L) Turbo Diesel Eng. (1991-on) <b>Lube</b> (D8NN6714DA)..... <b>BT343</b> <b>Lube</b> (E7HZ6731A)..... <b>[2] B157</b> <b>Fuel/Water Separator</b> (w/o Drain or Sensor Port) (F1HZ9365A)..... <b>BF1224</b> <b>Fuel/Water Separator</b> (w/Drain) (F1HZ9365A)..... <b>BF1223</b> <b>Fuel/Water Separator</b> (w/Drain & Sensor Port) (F1HZ9365A)..... <b>BF1223-SP</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (F1HZ9365A)..... <b>BF1223-O</b> <b>Fuel Spin-on</b> ..... <b>[2] BF7608</b> <b>Air</b> (16 1/2 In.) (E6HZ-9601-A)..... <b>PA2523</b> <b>Air</b> (23 1/2 In.) (E7HZ-9601-A)..... <b>PA2726</b>	F700 w/7.8L Turbo Diesel Eng. (To 1990) <b>Lube</b> (D8NN6714DA)..... <b>BT343</b> <b>Lube</b> (E7HZ6731A)..... <b>[2] B157</b> <b>Fuel/Water Separator</b> (E7HZ-9N184A)..... <b>BF1204</b> <b>Fuel Spin-on</b> ..... <b>[2] BF7608</b> <b>Air</b> (16 1/2 In.) (E6HZ-9601-A)..... <b>PA2523</b> <b>Air</b> (23 1/2 In.) (E7HZ-9601-A)..... <b>PA2726</b>	F750 w/Cat C7 (7.2L) Eng. <b>Lube</b> (1R1807)..... <b>B7700 +</b> <b>Fuel/Water Separator</b> (175-2949)..... <b>BF1268</b> <b>Fuel</b> (1R0751)..... <b>BF7632</b> <b>Channel Flow Air</b> (2591005C1).... <b>CA5514</b> <b>Radial Seal Air</b> (YC3Z9601FA).... <b>RS3517</b>


+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)
F750 w/Cat C7 (7.2L) Eng. (Cont'd)	F750 w/Cummins ISB (5.9L) Eng. (To 2007) (Cont'd)	F750 w/Cummins ISB 200 (6.7L) Eng.
<b>Radial Seal XP Air</b> (YC3Z9601FA)..... <b>RS3517XP</b>	<b>10 1/32 In. Fuel/Water Separator</b> (3954904)..... <b>BF1293-SPS</b>	<b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b>
<b>Air Dryer</b> (Bendix 109493)..... <b>BA5373</b>	<b>Fuel</b> (Fleetguard FF5632)..... <b>BF7940</b>	<b>Fuel/Water Separator Ele.</b> (3942470)..... <b>PF7777</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Radial Seal Air</b> (YC3Z-9601-FA). <b>RS3517</b>	<b>Fuel/Water Separator Spin-on</b> (3 11/16 In. O.D.) (Fleetguard FS19596)..... <b>BF1293-SPS</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Radial Seal XP Air</b> (YC3Z-9601-FA)..... <b>RS3517XP</b>	<b>Fuel/Water Separator Spin-on</b> (3 23/32 O.D.) (4934879)..... <b>BF1378-SPS</b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Air Dryer</b> (Bendix 109493)..... <b>BA5373</b>	<b>Fuel</b> (Fleetguard FF5632)..... <b>BF7940</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	<b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Coolant</b> (Fleetguard WF2053)..... <b>BW5139</b>	<b>Channel Flow Air</b> (7C4Z-9601-AA)..... <b>CA5514</b>
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Panel Air</b> (BC3Z9601A)..... <b>PA4433</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Foam Air</b> (Motorcraft FA1909)..... <b>PA10011</b>
F750 w/Cat 3126 (7.2L) Eng. (To 1/2004)	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Air Dryer</b> (Bendix 109493)..... <b>BA5373</b>
<b>Lube</b> (Standard Vers.)..... <b>B76 +</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Crankcase Breather</b> (Fleetguard CV52001)..... <b>CV15010</b>
<b>Lube</b> (Severe Service)..... <b>B76-SS +</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b>
<b>Fuel/Water Separator</b> (w/Drain) (5C4Z9N184AB)..... <b>BF7806</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (5C4Z9N184AB)..... <b>BF7806-O</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Fuel</b> (1R0751)..... <b>BF7632</b>	F750 w/Cummins ISB (5.9L) Eng. (2008-on)	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Radial Seal Air</b> (Don. P532966)... <b>RS3517</b>	<b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Radial Seal XP Air</b> (Don. P532966)..... <b>RS3517XP</b>	<b>5 3/8 In. Fuel/Water Separator</b> (3942533)..... <b>BF1271</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Axial Seal Air</b> (Motorcraft FA1669)..... <b>PA4110</b>	<b>8 9/32 In. Fuel/Water Separator</b> (w/o SP)..... <b>BF1346 +</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
<b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>8 9/32 In. Fuel/Water Separator</b> (w/SP)..... <b>BF1346-SP +</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>10 1/32 In. Fuel/Water Separator</b> (3954904)..... <b>BF1293-SPS</b>	<b>Diesel Exhaust Fluid</b> (2888182).. <b>PE17000</b>
F750 w/Cat 3126 (7.2L) Eng. (1/2004-on)	<b>Fuel</b> (Fleetguard FF5632)..... <b>BF7940</b>	F750 w/IHC VT365 (6.0L) Turbo Diesel Eng.
<b>Lube</b> (1R1807)..... <b>B7700 +</b>	<b>Channel Flow Air</b> (Motorcraft FA1889)..... <b>CA5514</b>	<b>Lube</b> (w/o Screw on Cap) (3C3Z-6731-AA)..... <b>P7235</b>
<b>Fuel/Water Separator</b> (w/Drain) (5C4Z9N184AB)..... <b>BF7806</b>	<b>Air Dryer</b> (Bendix 109493)..... <b>BA5373</b>	<b>Lube</b> (w/Screw on Cap) (Wix 57312)..... <b>P7436</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (5C4Z9N184AB)..... <b>BF7806-O</b>	<b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	<b>Fuel</b> (Set of 2 Ele.) (3C3Z-9N184-CA)..... <b>PF7812 KIT 76</b>
<b>Fuel</b> ..... <b>BF7632</b>	<b>Coolant</b> (Fleetguard WF2053)..... <b>BW5139</b>	<b>Fuel</b> (Ele. w/Lid) (Motorcraft FD4596)..... <b>PF7698</b>
<b>Radial Seal Air</b> (Don. P532966)... <b>RS3517</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Channel Flow Air</b> (4C4Z-9601-AA)..... <b>CA5366</b>
<b>Radial Seal XP Air</b> (Don. P532966)..... <b>RS3517XP</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b>
<b>Axial Seal Air</b> (Motorcraft FA1669)..... <b>PA4110</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
<b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
F750 w/Cummins ISB (5.9L) Eng. (To 2007)	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>5 3/8 In. Fuel/Water Separator</b> (3942533)..... <b>BF1271</b>		
<b>8 9/32 In. Fuel/Water Separator</b> (w/o SP)..... <b>BF1346 +</b>		
<b>8 9/32 In. Fuel/Water Separator</b> (w/SP)..... <b>BF1346-SP +</b>		

+ See Product Guide for Variations of This Number. <sup>76</sup> Contains Pri. and Sec. Fuel Elements.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)
F750 w/V10-415 (6.8L) Eng. (2016)	F800 w/Cummins ISB 5.9 (5.9L) Eng. (1999-on)	F800 w/6-473 (7.8L) Turbo Diesel Eng. (Cont'd)
Lube (Motorcraft FL820S)..... <b>B329</b>	(Cont'd)	Air (16 In.) (D5HZ-9601-D)..... <b>PA2425 +</b>
Air (Motorcraft FA1883)..... <b>PA4323</b>	<b>Radial Seal XP O. Air</b>	Air (23 1/2 In.) (E7HZ-9601-A)..... <b>PA2726</b>
Trans. (Motorcraft FT187)..... <b>20028</b>	(F3HZ-9601-A)..... <b>RS2863XP</b>	Coolant (E7HZ-8A424-B)..... <b>BW5136</b>
F750 w/V10-415 (6.8L) Eng. (2017-18)	<b>Radial Seal I. Air</b>	F800, FT900 w/Cummins FD1460 (8.3L) Eng.
Lube (Motorcraft FL820S)..... <b>B329</b>	(F3HZ-9R500-A)..... <b>RS3501</b>	<b>Dual-Flow Lube</b> (Fleetguard
Fuel (N/S)..... <b>N/S</b>	<b>Opt. Coolant</b> (Motorcraft FW2B).. <b>BW5071</b>	LF3000)..... <b>BD103 +</b>
Air (Motorcraft FA1923)..... <b>PA4433</b>	F800 w/Cummins FD1060 (5.9L) Eng.	<b>Fuel/Water Separator</b> (3843760). <b>BF1226</b>
Trans. (5R110W) (Motorcraft	<b>Lube</b> ..... <b>BT339 +</b>	<b>Radial Seal O. Air</b>
FT180)..... <b>20021</b>	<b>Fuel/Water Separator</b> ..... <b>BF1226</b>	(F3HZ-9601-A)..... <b>RS2863</b>
Trans. (Motorcraft FT187)..... <b>20028</b>	<b>Radial Seal O. Air</b>	<b>Radial Seal XP O. Air</b>
F750 w/V10-415 (6.8L) Eng. (2019)	(F3HZ-9601-A)..... <b>RS2863</b>	(F3HZ-9601-A)..... <b>RS2863XP</b>
Lube (Motorcraft FL820S)..... <b>B329</b>	<b>Radial Seal XP O. Air</b>	<b>Radial Seal I. Air</b>
Fuel (N/S)..... <b>N/S</b>	(F3HZ-9601-A)..... <b>RS2863XP</b>	(F3HZ-9R500-A)..... <b>RS3501</b>
Air (Motorcraft FA1923)..... <b>PA4433</b>	<b>Radial Seal I. Air</b>	<b>Coolant</b> (w/4 Units BTA +)
Trans. (Motorcraft FT187)..... <b>20028</b>	(F3HZ-9R500-A)..... <b>RS3501</b>	(3315116)..... <b>BW5071</b>
F750 w/Ford V8-445 (7.3L) Eng. (2021)	<b>Coolant</b> ..... <b>BW5137</b>	<b>Coolant</b> (w/8 Units BTA +)
Lube (Motorcraft FL820S)..... <b>B329</b>	F800 w/6.1L Eng.	(Fleetguard WF2073)..... <b>BW5073</b>
Fuel (N/S)..... <b>N/S</b>	<b>Lube</b> (D2NN-6714-C)..... <b>BT251</b>	F8000 w/Cat 3208 (10.4L) Eng.
Air (Foam) (Motorcraft FA1909).... <b>PA10011</b>	<b>Fuel</b> (E6HZ-9365-C)..... <b>BF790</b>	<b>Lube</b> (1R0713)..... <b>[2] BT230 +</b>
Air (Motorcraft FA1923)..... <b>PA4433</b>	<b>Trans.</b> (14949)..... <b>19828</b>	<b>Lube</b> (1R0714)..... <b>[2] B75</b>
Trans. (Motorcraft FT187)..... <b>20028</b>	F800 w/Ford L6-401 (6.6L) Turbo Diesel Eng.	<b>Lube</b> (9L9200)..... <b>[2] BT364</b>
F750 w/Ford V8-445 (7.3L) Eng. (2022)	<b>Fuel/Water Separator</b> (w/o Drain	<b>Box-Style Fuel/Water Separator</b>
Lube (FL820S)..... <b>B329</b>	or Sensor Port) (Motorcraft	(8N9803)..... <b>BF912</b>
Fuel (N/S)..... <b>N/S</b>	FD3368)..... <b>BF1224</b>	<b>P. Fuel Ele.</b> (9M2341)..... <b>PF935</b>
Air (FA1923)..... <b>PA4433</b>	<b>Fuel/Water Separator</b> (w/Drain)	<b>P. Fuel Spin-on</b> (1R0740)..... <b>BF970 +</b>
Trans. (FT187)..... <b>20028</b>	(Motorcraft FD3368)..... <b>BF1223</b>	<b>S. Fuel Spin-on</b> (1R0750)..... <b>BF7633 +</b>
F750 w/Ford V8-445 (7.3L) Eng. (2023)	<b>Fuel/Water Separator</b> (w/Drain &	<b>Coolant</b> (w/o Chemicals)
Lube (Motorcraft FL820S)..... <b>B329</b>	Sensor Port) (Motorcraft FD3368). <b>BF1223-SP</b>	(4355142)..... <b>B5089 +</b>
Fuel (N/S)..... <b>N/S</b>	<b>Fuel/Water Separator</b> (Open End	<b>Coolant</b> (w/4 Units BTE)
Trans. (Motorcraft FT187)..... <b>20028</b>	for Bowl) (Motorcraft FD3368)..... <b>BF1223-O</b>	(9N3717)..... <b>BW5137</b>
F750 w/IHC T444E (7.3L) Turbo Diesel Eng.	<b>Fuel</b> (E7HZ9365B)..... <b>BF7608</b>	<b>Coolant</b> (w/8 Units BTE)
Lube (F4TZ-6731-A)..... <b>B7039</b>	<b>Trans. Pan-Type</b> (3.8 In. Pan, AT	(9N3718)..... <b>BW5139</b>
Fuel (F81Z-9N184-AA)..... <b>PF7698</b>	Series Trans.) (Allison 29540976). <b>19992 +</b>	<b>Trans. Pan-Type</b> (MT Series)
F800 w/Cummins ISB (5.9L) Eng. (To 1998)	<b>Trans. Pan-Type</b> (5.3 In. Pan,	(Allison 29538489)..... <b>19739 +</b>
Lube (3914395)..... <b>BT339 +</b>	A.T. Series Trans.) (Allison	<b>Trans. Spin-on</b> (MT Series)
<b>Fuel/Water Separator</b> (13/16-18	29538489)..... <b>19739 +</b>	(Allison 29510922)..... <b>BT8316-MPG</b>
Thd.) (3925274)..... <b>BF1280 +</b>	<b>Trans. Spin-on</b> (AT Series)	FT900 w/Cummins 6CT8.3 (8.3L) Eng.
<b>Fuel/Water Separator</b> (M16 x 1.5	(Allison 29510922)..... <b>BT8316-MPG</b>	<b>F-F Lube</b> (3313281)..... <b>B205 +</b>
Thd.) (Fleetguard FS1251)..... <b>BF1226</b>	F800 w/Ford 7.0L Eng.	<b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b>
<b>Fuel</b> (3903640)..... <b>BF788</b>	<b>Lube</b> (Motorcraft FL299)..... <b>BT251</b>	<b>Fuel/Water Separator</b> (3925274). <b>BF1280 +</b>
<b>Radial Seal O. Air</b>	<b>Fuel</b> (Motorcraft FD3372)..... <b>BF7608</b>	<b>Fuel/Water Separator</b> (3286503). <b>BF1226</b>
(F3HZ-9601-A)..... <b>RS2863</b>	<b>Air</b> (8 1/16 In.) (D6HZ9601B)..... <b>PA2548</b>	<b>Fuel</b> (3903640)..... <b>BF788</b>
<b>Radial Seal XP O. Air</b>	<b>Air</b> (13 7/8 In.) (F1HZ9601C)..... <b>PA3475</b>	<b>Coolant</b> (w/6 Units BTA+)
(F3HZ-9601-A)..... <b>RS2863XP</b>	<b>Coolant</b> (Motorcraft FW18)..... <b>BW5136</b>	(3318201)..... <b>BW5072</b>
<b>Radial Seal I. Air</b>	F800 w/6-473 (7.8L) Turbo Diesel Eng.	<b>Coolant</b> (w/8 Units BTA+)
(F3HZ-9R500-A)..... <b>RS3501</b>	<b>Lube</b> ..... <b>[2] B157</b>	(3315115)..... <b>BW5073</b>
<b>Opt. Coolant</b> (Motorcraft FW2B).. <b>BW5071</b>	<b>Fuel/Water Separator</b>	FT900 w/Detroit Diesel 8.2L Eng.
F800 w/Cummins ISB 5.9 (5.9L) Eng. (1999-on)	(E7HZ-9N184-A)..... <b>BF1204</b>	<b>Lube</b> ..... <b>[2] B6 +</b>
Lube (Chrysler 5083285AA)..... <b>BT7349</b>	<b>Fuel/Water Separator</b> (w/o Drain	<b>P. Fuel</b> ..... <b>BF592 +</b>
<b>Fuel/Water Separator</b> (13/16-18	or Sensor Port) (F1HZ9365A)..... <b>BF1224</b>	<b>S. Fuel</b> ..... <b>BF593</b>
Thd.) (3925274)..... <b>BF1280 +</b>	<b>Fuel/Water Separator</b> (w/Drain)	<b>Air</b> (E0HZ-9601-A)..... <b>PA2596</b>
<b>Fuel/Water Separator</b> (M16 x 1.5	(F1HZ9365A)..... <b>BF1223</b>	FT8000 w/Cat 3208 (10.4L) Eng.
Thd.) (Fleetguard FS1251)..... <b>BF1226</b>	<b>Fuel/Water Separator</b> (w/Drain &	<b>Lube</b> (1R0713)..... <b>[2] BT230 +</b>
<b>Fuel</b> (3903640)..... <b>BF788</b>	Sensor Port) (F1HZ9365A)..... <b>BF1223-SP</b>	<b>Lube</b> (1R0714)..... <b>[2] B75</b>
<b>Radial Seal O. Air</b>	<b>Fuel/Water Separator</b> (Open End	<b>Lube</b> (9L9200)..... <b>[2] BT364</b>
(F3HZ-9601-A)..... <b>RS2863</b>	for Bowl) (F1HZ9365A)..... <b>BF1223-O</b>	<b>Box-Style Fuel/Water Separator</b>
	<b>Fuel Spin-on</b> ..... <b>[2] BF7608</b>	(8N9803)..... <b>BF912</b>


+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)
FT8000 w/Cat 3208 (10.4L) Eng. (Cont'd)	L8000F w/Cummins 6CT8.3 (8.3L) Eng.	L8511 w/Cat 3126 (7.2L) Eng. (Cont'd)
P. Fuel Ele. (9M2341)..... PF935	Dual-Flow Lube (Standard Vers.) (3318853)..... BD103 +	Fuel/Water Separator (Fleetguard FS1000)..... BF1259
P. Fuel Spin-on (1R0740)..... BF970 +	Dual-Flow Lube (High Velocity) (3401544)..... BD7309 +	Fuel/Water Separator (w/Sensor Port) (1986378)..... BF7798-SP
S. Fuel Spin-on (1R0750)..... BF7633 +	Lube (Upgrade) (3401544)..... B40142 +	Fuel/Water Separator (Open End for Bowl) (1986378)..... BF7798-O
Coolant (w/o Chemicals) (4355142)..... B5089 +	Fuel/Water Separator (3286503). BF1226	Fuel Ele. (9M2342)..... [2] PF935
Coolant (w/4 Units BTE) (9N3717)..... BW5137	Fuel (3903640)..... BF788	Fuel Spin-on (1R0751)..... BF7632
Coolant (w/8 Units BTE) (9N3718)..... BW5139	Coolant (w/6 Units BTA+) (3318201)..... BW5072	L8511 w/Cummins 6CT8.3 (8.3L) Eng.
L8000 w/Cat 3208 (10.4L) Eng.	Coolant (w/8 Units BTA+) (3315115)..... BW5073	F-F Lube (3313281)..... B205 +
Lube (1R0713)..... [2] BT230 +	Trans. Ele. (3000 & 4000 Series, 2 In. Kit) (Allison 29548987)..... PT9416-MPG KIT	Dual-Flow Lube (3318853)..... BD103 +
Lube (1R0714)..... [2] B75	Trans. Ele. (3000 & 4000 Series, 4 In. Kit) (Allison 29548988)..... PT9415-MPG KIT	Fuel/Water Separator (3925274). BF1280 +
Lube (9L9200)..... [2] BT364	Trans. Pan-Type (MT Series) (Allison 29538489)..... 19739 +	Fuel/Water Separator (3286503). BF1226
Box-Style Fuel/Water Separator (8N9803)..... BF912	Trans. Spin-on (MT Series) (Allison 29510922)..... BT8316-MPG	Fuel (3903640)..... BF788
P. Fuel Spin-on (1R0740)..... BF970 +	Trans. Spin-on (Fuller 4304827).. BT223	Coolant (w/6 Units BTA+) (3318201)..... BW5072
S. Fuel Spin-on (1R0750)..... BF7633 +	Opt. Trans. Spin-on (Fuller 17237)..... B2 +	Coolant (w/8 Units BTA+) (3315115)..... BW5073
Coolant (w/o Chemicals) (4355142)..... B5089 +	L8501 w/Cat 3126 (7.2L) Eng.	L8513 w/Cat 3126 (7.2L) Eng.
Coolant (w/4 Units BTE) (9N3717)..... BW5137	Lube (Standard Vers.) (1R0739).. B76 +	Lube (Standard Vers.) (1R0739).. B76 +
Coolant (w/8 Units BTE) (9N3718)..... BW5139	Lube (Severe Service) (1R0739).. B76-SS +	Lube (Severe Service) (1R0739).. B76-SS +
Trans. Pan-Type (MT Series) (Allison 29538489)..... 19739 +	Fuel/Water Separator (1752949). BF1268	Fuel/Water Separator (1752949). BF1268
Trans. Spin-on (MT Series) (Allison 29510922)..... BT8316-MPG	Fuel/Water Separator (Fleetguard FS1000)..... BF1259	Fuel/Water Separator (Fleetguard FS1000)..... BF1259
L8000, LN8000, LNT8000, LT8000, LTS8000 w/Cat 1145, 1150, 1160 Eng.	Fuel/Water Separator (w/Sensor Port) (1986378)..... BF7798-SP	Fuel/Water Separator (w/Sensor Port) (1986378)..... BF7798-SP
Lube Spin-on..... BT364	Fuel/Water Separator (Open End for Bowl) (1986378)..... BF7798-O	Fuel/Water Separator (Open End for Bowl) (1986378)..... BF7798-O
B-P Lube Ele..... [2] C750-E +	Fuel Ele. (9M2342)..... [2] PF935	Fuel Ele. (9M2342)..... [2] PF935
Box-Style Fuel/Water Separator. BF912	Fuel Spin-on (1R0751)..... BF7632	Fuel Spin-on (1R0751)..... BF7632
Fuel Spin-on (15/16-16 Thd.)..... BF583	L8501 w/Cummins 6BT5.9 (5.9L) Eng.	L8513 w/Cummins 6CT8.3 (8.3L) Eng.
Fuel Spin-on (1-14 Thd.)..... BF970 +	Lube (3914395)..... BT339 +	F-F Lube (3313281)..... B205 +
Air (To 1973) (Don. P127915)..... PA1977-FN	Fuel/Water Separator (3903202). BF1226	Dual-Flow Lube (3318853)..... BD103 +
Air (1973-74) (Don. P127917)..... PA1979-FN	Fuel/Water Separator (3925274). BF1280 +	Fuel/Water Separator (3925274). BF1280 +
Air (1975-on) (Don. P128876)..... PA2425 +	Fuel (3903640)..... BF788	Fuel/Water Separator (3286503). BF1226
L8000, LN8000, LNT8000, LT8000, LTS8000 w/GMC 6V-53 Diesel Eng.	L8501 w/Cummins 6CT8.3 (8.3L) Eng.	Fuel (3903640)..... BF788
F-F Lube Ele..... P20-HD +	F-F Lube (3313281)..... B205 +	Coolant (w/6 Units BTA+) (3318201)..... BW5072
B-P Lube Ele..... P52	Dual-Flow Lube (3318853)..... BD103 +	Coolant (w/8 Units BTA+) (3315115)..... BW5073
P. Fuel Sock..... F916-C	Fuel/Water Separator (3925274). BF1280 +	L9000 w/Cat 3176 (10.3L) Eng.
S. Fuel Ele..... PF906	Fuel/Water Separator (3286503). BF1226	F-F Lube (Std. Efficiency) (1R0716)..... B99 +
Air (1970-72) (Don. P112872)..... PA1978-FN <sup>90</sup>	Fuel (3903640)..... BF788	F-F Eng. Lube (High Efficiency Vers.) (1R1808)..... B7299 +
Air (To 1975) (Don. P127917)..... PA1979-FN	Coolant (w/6 Units BTA+) (3318201)..... BW5072	Opt. B-P Lube (1W8845)..... B7577
Air (1975-on) (Don. P128876)..... PA2425 +	Coolant (w/8 Units BTA+) (3315115)..... BW5073	Fuel/Water Separator Ele. (8N0205)..... PF316
L8000, LN8000, LNT8000, LTS8000, W8000 w/Cummins VT225 Eng.	L8501 w/Cummins M11 (10.8L) Eng.	Fuel/Water Separator Spin-on (Fleetguard FS1000)..... BF1259
F-F Lube Ele..... P999-HD	Dual-Flow Lube..... BD103 +	P. Fuel Ele. (9M2342)..... [2] PF935
B-P Lube Ele..... C704-L	Fuel/Water Separator..... BF1259	P. Fuel Spin-on (1R0740)..... BF970 +
Fuel Spin-on..... BF957 +	L8511 w/Cat 3126 (7.2L) Eng.	P. Fuel Spin-on (1R0749)..... BF7587 +
Air (D5HZ-9601-D)..... PA2425 +	Lube (Standard Vers.) (1R0739).. B76 +	S. Fuel Spin-on (1R0750)..... BF7633 +
Coolant Spin-on..... BW5071	Lube (Severe Service) (1R0739).. B76-SS +	Coolant (w/8 Units BTE) (9N6123)..... BW5139
	Fuel/Water Separator (1752949). BF1268	Trans. Spin-on (Fuller 4304827).. BT223

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)
L9000 w/Cat 3176 (10.3L) Eng. (Cont'd) Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	L9000 w/Detroit Diesel 6V-92N, 8V-92 Series Engs. (Cont'd) <b>I. Air</b> (Motorcraft AFA94)..... <b>PA2960</b> <b>Std. Air</b> (16 1/2 In.) (D5HZ-9601-A)..... <b>PA2533</b> <b>Conical Air</b> (8 11/16 In. O.D.) (D8HZ-9601-A)..... <b>PA2500 +</b> <b>Conical Air</b> (10 13/32 In. O.D.) (D8HZ-9601-B)..... <b>PA3951</b> <b>DynaCell Panel Air</b> (D8HZ-9601-E)..... <b>PA2375 +</b> <b>Conical Air</b> (12 3/4 In. O.D.) (E2HZ-9601-A)..... <b>PA2632</b>	L9501 w/Cat C10 (10.3L) Eng. (Cont'd) <b>Fuel/Water Separator Spin-on</b> (w/Drain) (Alliance ABPN122R50421)..... <b>BF1265</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1000)..... <b>BF1259</b> <b>Fuel</b> (Standard Vers.) (1R1712)..... <b>BF614 +</b> <b>Fuel</b> (High Efficiency Vers.) (1R0749)..... <b>BF7587 +</b>
L9000 w/Cat 3306 (10.5L) Eng. <b>Lube Ele.</b> (w/Paper Wrapper) (1R0659)..... <b>PT670</b> <b>Lube Ele.</b> (w/Metal Wrapper) (1R0659)..... <b>PT7332</b> <b>F-F Lube Spin-on</b> (1R0716)..... <b>B99 +</b> <b>F-F Lube Spin-on</b> (Standard Vers.) (1R0739)..... <b>B76 +</b> <b>F-F Lube Spin-on</b> (Severe Service) (1R0739)..... <b>B76-SS +</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Box-Style Glass Fuel/Water Separator</b> (6N7617)..... <b>BF912</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1000)..... <b>BF1259</b> <b>P. Fuel Ele.</b> (9M2341)..... <b>PF935</b> <b>P. Fuel Spin-on</b> (1R0740)..... <b>BF970 +</b> <b>S. Fuel Spin-on</b> (1R0750)..... <b>BF7633 +</b>	L9000, LL9000, LN9000, LNT9000, LS9000 w/GMC 6-71N Diesel Eng. <b>F-F Lube Ele.</b> ..... <b>P20-HD +</b> <b>B-P Lube Ele.</b> (750 Size)..... <b>C750-E +</b> <b>P. Fuel Spin-on</b> ..... <b>BF5800 +</b> <b>S. Fuel Spin-on</b> ..... <b>BF5810</b> <b>Air</b> (To 1975) (Don. P127917)..... <b>PA1979-FN</b> <b>Air</b> (1975-on) (Don. P128876)..... <b>PA2425 +</b> <b>Air</b> (Don. P117437)..... <b>PA1885 +</b>	L9501 w/Cat C12 (12.0L) Eng. <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99 +</b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> <b>B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Alliance ABPN122R50421)..... <b>BF1395-O</b> <b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (Alliance ABPN122R50421)..... <b>BF1395-SP</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (Alliance ABPN122R50421)..... <b>BF1265</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1000)..... <b>BF1259</b> <b>P. Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (Standard Vers.) (1R1712)..... <b>BF614 +</b> <b>Fuel Spin-on</b> (High Efficiency Vers.) (1R0749)..... <b>BF7587 +</b> <b>Coolant</b> (w/4 Units BTE) (9N3368)..... <b>BW5137</b> <b>Coolant</b> (w/8 Units BTE) (9N3366)..... <b>BW5139</b>
L9000 w/Cummins L10 Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>F-F Lube</b> (Fleetguard LF670SC)..... <b>B196 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Fuel/Water Separator</b> (3308638)..... <b>BF1212 +</b> <b>Fuel</b> (154789)..... <b>BF957-D +</b> <b>Air</b> (E2HZ-9601-B)..... <b>PA2642</b> <b>Coolant</b> (3315116)..... <b>BW5071</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	LT9000, LTL9000, LTS9000, W9000, WT9000 w/GMC 6-71N Diesel Eng. <b>F-F Lube Ele.</b> ..... <b>P20-HD +</b> <b>B-P Lube Ele.</b> (750 Size)..... <b>C750-E +</b> <b>P. Fuel Spin-on</b> ..... <b>BF5800 +</b> <b>S. Fuel Spin-on</b> ..... <b>BF5810</b> <b>Air</b> (To 1975) (Don. P127917)..... <b>PA1979-FN</b> <b>Air</b> (1975-on) (Don. P128876)..... <b>PA2425 +</b> <b>Air</b> (Don. P117437)..... <b>PA1885 +</b>	L9501 w/Cat C10 (10.3L) Eng. <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99 +</b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> <b>B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Alliance ABPN122R50421)..... <b>BF1395-O</b> <b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (Alliance ABPN122R50421)..... <b>BF1395-SP</b>
L9000 w/Cummins M11 (10.8L) Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> (3329289)..... <b>BF1259</b> <b>Coolant</b> (w/4 Units BTA+) (3315116)..... <b>BW5071</b> <b>Coolant</b> (w/15 Units BTA+) (3318318)..... <b>BW5075</b>	L9000, LN9000, LA9000, LLA9000, LNT9000, LS9000, LTS9000, LTLA9000 w/Detroit Diesel Series 60 Eng. <b>F-F Lube</b> (1 1/2-12 Thd.) (ACDelco PF911)..... <b>[2] B95 +</b> <b>F-F Lube</b> (1 5/8-12 Thd.) (ACDelco PF2100)..... <b>[2] B495</b> <b>B-P Lube</b> (ACDelco P940)..... <b>B7577</b> <b>P. Fuel</b> ..... <b>BF5800 +</b> <b>S. Fuel</b> ..... <b>BF5810</b> <b>Air</b> (E2HZ-9601-B)..... <b>PA2642</b> <b>Coolant</b> (ACDelco WF100)..... <b>BW5137</b>	L9501 w/Cat 3306 (10.5L) Eng. <b>Lube Ele.</b> (w/Paper Wrapper) (1R0659)..... <b>PT670</b> <b>Lube Ele.</b> (w/Metal Wrapper) (1R0659)..... <b>PT7332</b> <b>F-F Lube Spin-on</b> (1R0716)..... <b>B99 +</b> <b>F-F Lube Spin-on</b> (Standard Vers.) (1R0739)..... <b>B76 +</b> <b>F-F Lube Spin-on</b> (Severe Service) (1R0739)..... <b>B76-SS +</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Box-Style Glass Fuel/Water Separator</b> (6N7617)..... <b>BF912</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1000)..... <b>BF1259</b> <b>P. Fuel Ele.</b> (9M2341)..... <b>PF935</b> <b>P. Fuel Spin-on</b> (1R0740)..... <b>BF970 +</b> <b>S. Fuel Spin-on</b> (1R0750)..... <b>BF7633 +</b>
L9000 w/Cummins N14 (14.0L) Eng. <b>F-F Lube</b> (Fleetguard LF670SC)..... <b>B196 +</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Fuel/Water Separator Spin-on</b> (3329289)..... <b>BF1259</b> <b>Fuel/Water Separator Spin-on</b> (3406889)..... <b>BF1293-SPS</b> <b>Fuel</b> (154789)..... <b>BF957-D +</b> <b>Coolant</b> (3315116)..... <b>BW5071</b>	L9501 w/Cat C10 (10.3L) Eng. <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99 +</b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> <b>B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Alliance ABPN122R50421)..... <b>BF1395-O</b> <b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (Alliance ABPN122R50421)..... <b>BF1395-SP</b>	
L9000 w/Detroit Diesel 6V-92N, 8V-92 Series Engs. <b>F-F Lube Ele.</b> ..... <b>P20-HD +</b> <b>B-P Lube Ele.</b> (750 Size)..... <b>C750-E +</b> <b>P. Fuel Spin-on</b> ..... <b>BF5800 +</b> <b>S. Fuel Spin-on</b> ..... <b>BF5810</b> <b>O. Air</b> (Motorcraft AFA93)..... <b>PA2959-FN<sup>90</sup></b>		

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.

Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)
L9501 w/Cummins M11 (10.8L) Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> (3329289)..... <b>BF1259</b> <b>Coolant</b> (w/4 Units BTA+) (3315116)..... <b>BW5071</b> <b>Coolant</b> (w/15 Units BTA+) (3318318)..... <b>BW5075</b>	L9511 w/Cat C12 (12.0L) Eng. (Cont'd) <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1000)..... <b>BF1259</b> <b>P. Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (Standard Vers.) (1R1712)..... <b>BF614 +</b> <b>Fuel Spin-on</b> (High Efficiency Vers.) (1R0749)..... <b>BF7587 +</b> <b>Coolant</b> (w/4 Units BTE) (9N3368)..... <b>BW5137</b> <b>Coolant</b> (w/8 Units BTE) (9N3366)..... <b>BW5139</b>	L9513 w/Cat C10 (10.3L) Eng. (Cont'd) <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Alliance ABPN122R50421)..... <b>BF1395-O</b> <b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (Alliance ABPN122R50421)..... <b>BF1395-SP</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (Alliance ABPN122R50421)..... <b>BF1265</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1000)..... <b>BF1259</b> <b>Fuel</b> (Standard Vers.) (1R1712)... <b>BF614 +</b> <b>Fuel</b> (High Efficiency Vers.) (1R0749)..... <b>BF7587 +</b>
L9501 w/Cummins N14 (14.0L) Eng. <b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196 +</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Fuel/Water Separator Spin-on</b> (3329289)..... <b>BF1259</b> <b>Fuel/Water Separator Spin-on</b> (3406889)..... <b>BF1293-SPS</b> <b>Fuel</b> (154789)..... <b>BF957-D +</b> <b>Coolant</b> (3315116)..... <b>BW5071</b>	L9511 w/Cat 3306 (10.5L) Eng. <b>Lube Ele.</b> (w/Paper Wrapper) (1R0659)..... <b>PT670</b> <b>Lube Ele.</b> (w/Metal Wrapper) (1R0659)..... <b>PT7332</b> <b>F-F Lube Spin-on</b> (1R0716)..... <b>B99 +</b> <b>F-F Lube Spin-on</b> (Standard Vers.) (1R0739)..... <b>B76 +</b> <b>F-F Lube Spin-on</b> (Severe Service) (1R0739)..... <b>B76-SS +</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Box-Style Glass Fuel/Water Separator</b> (6N7617)..... <b>BF912</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1000)..... <b>BF1259</b> <b>P. Fuel Ele.</b> (9M2341)..... <b>PF935</b> <b>P. Fuel Spin-on</b> (1R0740)..... <b>BF970 +</b> <b>S. Fuel Spin-on</b> (1R0750)..... <b>BF7633 +</b>	L9513 w/Cat C12 (12.0L) Eng. <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99 +</b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> <b>B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Alliance ABPN122R50421)..... <b>BF1395-O</b> <b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (Alliance ABPN122R50421)..... <b>BF1395-SP</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (Alliance ABPN122R50421)..... <b>BF1265</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1000)..... <b>BF1259</b> <b>Fuel</b> (Standard Vers.) (1R1712)... <b>BF614 +</b> <b>Fuel</b> (High Efficiency Vers.) (1R0749)..... <b>BF7587 +</b>
L9511 w/Cat C10 (10.3L) Eng. <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99 +</b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> <b>B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Alliance ABPN122R50421)..... <b>BF1395-O</b> <b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (Alliance ABPN122R50421)..... <b>BF1395-SP</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (Alliance ABPN122R50421)..... <b>BF1265</b>	L9511 w/Cummins M11 (10.8L) Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> (3329289)..... <b>BF1259</b> <b>Coolant</b> (w/4 Units BTA+) (3315116)..... <b>BW5071</b> <b>Coolant</b> (w/15 Units BTA+) (3318318)..... <b>BW5075</b>	L9513 w/Cat C12 (12.0L) Eng. <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99 +</b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> <b>B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Alliance ABPN122R50421)..... <b>BF1395-O</b> <b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (Alliance ABPN122R50421)..... <b>BF1395-SP</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (Alliance ABPN122R50421)..... <b>BF1265</b>
L9511 w/Cat C12 (12.0L) Eng. <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99 +</b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> <b>B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Alliance ABPN122R50421)..... <b>BF1395-O</b> <b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (Alliance ABPN122R50421)..... <b>BF1395-SP</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (Alliance ABPN122R50421)..... <b>BF1265</b>	L9511 w/Cummins N14 (14.0L) Eng. <b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196 +</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Fuel/Water Separator Spin-on</b> (3329289)..... <b>BF1259</b> <b>Fuel/Water Separator Spin-on</b> (3406889)..... <b>BF1293-SPS</b> <b>Fuel</b> (154789)..... <b>BF957-D +</b> <b>Coolant</b> (3315116)..... <b>BW5071</b>	L9513 w/Cat 3176 (10.3L) Eng. <b>F-F Lube</b> (Std. Efficiency) (1R0716)..... <b>B99 +</b> <b>F-F Eng. Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> <b>Opt. B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1000)..... <b>BF1259</b> <b>P. Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>P. Fuel Spin-on</b> (1R0740)..... <b>BF970 +</b> <b>P. Fuel Spin-on</b> (1R0749)..... <b>BF7587 +</b> <b>S. Fuel Spin-on</b> (1R0750)..... <b>BF7633 +</b> <b>Coolant</b> (w/8 Units BTE) (9N6123)..... <b>BW5139</b>
L9511 w/Cat C10 (10.3L) Eng. <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99 +</b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> <b>B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Alliance ABPN122R50421)..... <b>BF1395-O</b> <b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (Alliance ABPN122R50421)..... <b>BF1395-SP</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (Alliance ABPN122R50421)..... <b>BF1265</b>	L9513 w/Cat C10 (10.3L) Eng. <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99 +</b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> <b>B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).




FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)
L9513 w/Cat 3306 (10.5L) Eng. Lube Ele. (w/Paper Wrapper) (1R0659)..... <b>PT670</b> Lube Ele. (w/Metal Wrapper) (1R0659)..... <b>PT7332</b> F-F Lube Spin-on (1R0716)..... <b>B99 +</b> F-F Lube Spin-on (Standard Vers.) (1R0739)..... <b>B76 +</b> F-F Lube Spin-on (Severe Service) (1R0739)..... <b>B76-SS +</b> Fuel/Water Separator Ele. (8N0205)..... <b>PF316</b> Box-Style Glass Fuel/Water Separator (6N7617)..... <b>BF912</b> Fuel/Water Separator Spin-on (Fleetguard FS1000)..... <b>BF1259</b> P. Fuel Ele. (9M2341)..... <b>PF935</b> P. Fuel Spin-on (1R0740)..... <b>BF970 +</b> S. Fuel Spin-on (1R0750)..... <b>BF7633 +</b>	L9513 w/Detroit Diesel Series 60 (11.1L) or (12.7L) Eng. F-F Lube (23518480)..... <b>[2] B495</b> Fuel/Water Separator (w/Drain) (23512317)..... <b>BF5813 +</b> Fuel/Water Separator (Open End for Bowl) (23512317)..... <b>BF5813-O +</b> Opt. Fuel/Water Separator (23516189)..... <b>BF5812</b> Opt. Fuel/Water Separator (Alliance ABPN122R50407)..... <b>BF1283-SP +</b> P. Fuel (25014274)..... <b>BF5800 +</b> S. Fuel (23518482)..... <b>BF5810</b> L9522 w/Cat C10 (10.3L) Eng. F-F Lube (Std. Version) (1R0716)..... <b>B99 +</b> F-F Lube (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> B-P Lube (1W8845)..... <b>B7577</b> Fuel/Water Separator Ele. (8N0205)..... <b>PF316</b> Fuel/Water Separator Spin-on (Open End for Bowl) (Alliance ABPN122R50421)..... <b>BF1395-O</b> Fuel/Water Separator Spin-on (w/Sensor Port) (Alliance ABPN122R50421)..... <b>BF1395-SP</b> Fuel/Water Separator Spin-on (w/Drain) (Alliance ABPN122R50421)..... <b>BF1265</b> Fuel/Water Separator Spin-on (Fleetguard FS1000)..... <b>BF1259</b> Fuel (Standard Vers.) (1R1712)..... <b>BF614 +</b> Fuel (High Efficiency Vers.) (1R0749)..... <b>BF7587 +</b> LA8000F w/Cummins 6CT8.3 (8.3L) Eng. F-F Lube (3313281)..... <b>B205 +</b> Dual-Flow Lube (3318853)..... <b>BD103 +</b> Fuel/Water Separator (3925274)..... <b>BF1280 +</b> Fuel/Water Separator (3286503)..... <b>BF1226</b> Fuel (3903640)..... <b>BF788</b> Coolant (w/6 Units BTA+) (3318201)..... <b>BW5072</b> Coolant (w/8 Units BTA+) (3315115)..... <b>BW5073</b> LA8000F w/7.8L Diesel Eng. Lube (E7HZ-6731-A)..... <b>[2] B157</b> Fuel (E7HZ-9365-B)..... <b>[2] BF7608</b> 16 In. Air (D5HZ-9601-D)..... <b>PA2425 +</b> 16 1/2 In. Air (E7HZ-9601-B)..... <b>PA2538</b> 23 1/2 In. Air (E7HZ-9601-A)..... <b>PA2726</b> LA9000 w/Cat 3306 (10.5L) Eng. Lube Ele. (w/Paper Wrapper) (1R0659)..... <b>PT670</b> Lube Ele. (w/Metal Wrapper) (1R0659)..... <b>PT7332</b> F-F Lube Spin-on (1R0716)..... <b>B99 +</b>	LA9000 w/Cat 3306 (10.5L) Eng. (Cont'd) F-F Lube Spin-on (Standard Vers.) (1R0739)..... <b>B76 +</b> F-F Lube Spin-on (Severe Service) (1R0739)..... <b>B76-SS +</b> Fuel/Water Separator Ele. (8N0205)..... <b>PF316</b> Box-Style Glass Fuel/Water Separator (6N7617)..... <b>BF912</b> Fuel/Water Separator Spin-on (Fleetguard FS1000)..... <b>BF1259</b> P. Fuel Ele. (9M2341)..... <b>PF935</b> P. Fuel Spin-on (1R0740)..... <b>BF970 +</b> S. Fuel Spin-on (1R0750)..... <b>BF7633 +</b> LA9000 w/Cummins L10 (10.0L) Eng. F-F Lube (Fleetguard LF670SC).. <b>B196 +</b> Dual-Flow Lube (3318853)..... <b>BD103 +</b> B-P Lube (3304232)..... <b>B7577</b> Fuel/Water Separator Spin-on (3315843)..... <b>BF1212 +</b> Fuel (154789)..... <b>BF957-D +</b> Coolant (w/4 Units BTA+) (3315116)..... <b>BW5071</b> Coolant (w/8 Units BTA+) (3315115)..... <b>BW5073</b> LA9000 w/Cummins M11 (10.8L) Eng. (To 12/1995) Dual-Flow Lube (3318853)..... <b>BD103 +</b> Fuel/Water Separator Ele. (Fleetguard FS1029W)..... <b>PF7680</b> Fuel/Water Separator Spin-on (3308638)..... <b>BF1212 +</b> Coolant (3318318)..... <b>BW5075</b> LA9000 w/Cummins M11 (10.8L) Eng. (12/1995-on) Dual-Flow Lube (3318853)..... <b>BD103 +</b> Fuel/Water Separator Ele. (Fleetguard FS1029W)..... <b>PF7680</b> Fuel/Water Separator Spin-on (3329289)..... <b>BF1259</b> Coolant (3318318)..... <b>BW5075</b> LA9000 w/Cummins N14 Eng. F-F Lube (Fleetguard LF670SC).. <b>B196 +</b> B-P Lube (3304232)..... <b>B7577</b> Dual-Flow Lube (3318853)..... <b>BD103 +</b> Opt. Fuel/Water Separator (3308638)..... <b>BF1212 +</b> Fuel (154789)..... <b>BF957-D +</b> Coolant..... <b>BW5071</b> LA9000, LL9000, LTA9000, LTL9000 w/Cat 3176 Eng. Lube..... <b>B99 +</b> Fuel Spin-on..... <b>BF614 +</b> Air (Don. P142831)..... <b>PA2632</b>
L9513 w/Cat 3406 (14.6L) Eng. F-F Lube (Std. Efficiency) (1R0716)..... <b>B99 +</b> F-F Eng. Lube (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> Fuel/Water Separator Spin-on (Fleetguard FS1000)..... <b>BF1259</b> Fuel Spin-on (1R0749)..... <b>BF7587 +</b> Fuel Spin-on (1R0712)..... <b>BF614 +</b> Coolant (w/4 Units BTE) (9N3368)..... <b>BW5137</b> Coolant (w/8 Units BTE) (9N6123)..... <b>BW5139</b>	L9513 w/Cummins M11 (10.8L) Eng. Dual-Flow Lube (3318853)..... <b>BD103 +</b> Fuel/Water Separator Ele. (Fleetguard FS1029W)..... <b>PF7680</b> Fuel/Water Separator Spin-on (3329289)..... <b>BF1259</b> Coolant (w/4 Units BTA+) (3315116)..... <b>BW5071</b> Coolant (w/15 Units BTA+) (3318318)..... <b>BW5075</b>	LA9000 w/Cummins M11 (10.8L) Eng. (12/1995-on) Dual-Flow Lube (3318853)..... <b>BD103 +</b> Fuel/Water Separator Ele. (Fleetguard FS1029W)..... <b>PF7680</b> Fuel/Water Separator Spin-on (3329289)..... <b>BF1259</b> Coolant (3318318)..... <b>BW5075</b>
L9513 w/Cummins N14 (14.0L) Eng. F-F Lube (Fleetguard LF670SC).. <b>B196 +</b> Dual-Flow Lube (3318853)..... <b>BD103 +</b> B-P Lube (3304232)..... <b>B7577</b> Fuel/Water Separator Spin-on (3329289)..... <b>BF1259</b> Fuel/Water Separator Spin-on (3406889)..... <b>BF1293-SPS</b> Fuel (154789)..... <b>BF957-D +</b> Radial Seal O. Air (Standard) (F1HZ9601B)..... <b>RS3518</b> Radial Seal XP O. Air (Upgrade) (F1HZ9601B)..... <b>RS3518XP</b> Coolant (3315116)..... <b>BW5071</b>	LA9000F w/7.8L Diesel Eng. Lube (E7HZ-6731-A)..... <b>[2] B157</b> Fuel (E7HZ-9365-B)..... <b>[2] BF7608</b> 16 In. Air (D5HZ-9601-D)..... <b>PA2425 +</b> 16 1/2 In. Air (E7HZ-9601-B)..... <b>PA2538</b> 23 1/2 In. Air (E7HZ-9601-A)..... <b>PA2726</b>	LA9000 w/Cummins N14 Eng. F-F Lube (Fleetguard LF670SC).. <b>B196 +</b> B-P Lube (3304232)..... <b>B7577</b> Dual-Flow Lube (3318853)..... <b>BD103 +</b> Opt. Fuel/Water Separator (3308638)..... <b>BF1212 +</b> Fuel (154789)..... <b>BF957-D +</b> Coolant..... <b>BW5071</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)
LA9000, LTA9000 w/Cat C12 Eng. F-F Lube (1R0716)..... B99 + Fuel (1R1712)..... BF614 + Radial Seal Air (F6HZ9601AB).... RS3548 Radial Seal XP Air (F6HZ9601AB)..... RS3548XP	LL9000 w/Cummins N14 (14.0L) Eng. (Cont'd) Fuel (154789)..... BF957-D + Conical-Shaped Air (F8HZ9601A)..... PA2500 + Conical-Shaped Air (E2HZ9601A)..... PA2632 Air (E2HZ9601B)..... PA2642 Radial Seal O. Air (Standard) (F1HZ9601B)..... RS3518 Radial Seal XP O. Air (Upgrade) (F1HZ9601B)..... RS3518XP Coolant (3315116)..... BW5071	LLA9000 w/Cummins L10 (10.0L) Eng. F-F Lube (Fleetguard LF670SC).. B196 + Dual-Flow Lube (3318853)..... BD103 + B-P Lube (3304232)..... B7577 Fuel/Water Separator Spin-on (3315843)..... BF1212 + Fuel (154789)..... BF957-D + Coolant (w/4 Units BTA+) (3315116)..... BW5071 Coolant (w/8 Units BTA+) (3315115)..... BW5073
LCF w/IHC VT275 (4.5L) Eng. (2006-08) Lube Ele. (Motorcraft FL2029).... P7423 Lube Spin-on (Motorcraft FL1995)..... B7039 Fuel (Frame) (Motorcraft FD4596)..... PF7698 Some Fuel (Motorcraft FD4604)... PF7812 KIT Air (Motorcraft FA1779)..... RS4992 Trans. (Motorcraft FT145)..... P7247	CL9000, CLT9000, L9000, LN9000, LNT9000, LS9000, LTL9000, LTS9000 w/GMC 6V-92, 8V-92 Series Diesel E F-F Lube Ele. .... P20-HD + B-P Lube Ele. (750 Size)..... C750-E + P. Fuel Spin-on..... BF5800 + S. Fuel Spin-on..... BF5810 O. Air (Motorcraft AFA93)..... PA2959-FN 90 I. Air (Motorcraft AFA94)..... PA2960 Std. Air (16 1/2 In.) (D5HZ-9601-A)..... PA2533 Conical Air (8 11/16 In. O.D.) (D8HZ-9601-A)..... PA2500 + Conical Air (10 13/32 In. O.D.) (D8HZ-9601-B)..... PA3951 DynaCell Panel Air (D8HZ-9601-E)..... PA2375 + Conical Air (12 3/4 In. O.D.) (E2HZ-9601-A)..... PA2632	LLA9000 w/Cummins M11 (10.8L) Eng. (To 12/1995) Dual-Flow Lube (3318853)..... BD103 + Fuel/Water Separator Ele. (Fleetguard FS1029W)..... PF7680 Fuel/Water Separator Spin-on (3308638)..... BF1212 + Coolant (w/4 Units BTA+) (3315116)..... BW5071 Coolant (w/15 Units BTA+) (3318318)..... BW5075
LCF w/IHC VT275 (4.5L) Eng. (2009) Lube Spin-on (Motorcraft FL1995)..... B7039 Fuel (Frame) (Motorcraft FD4596)..... PF7698 Some Fuel (Motorcraft FD4604)... PF7812 KIT Air (Motorcraft FA1779)..... RS4992 Trans. (Motorcraft FT145)..... P7247	LLA9000 w/Cat 3176 (10.3L) Eng. F-F Lube (Std. Efficiency) (1R0716)..... B99 + F-F Eng. Lube (High Efficiency Vers.) (1R1808)..... B7299 + Opt. B-P Lube (1W8845)..... B7577 Fuel/Water Separator Ele. (8N0205)..... PF316 Fuel/Water Separator Spin-on (Fleetguard FS1000)..... BF1259 P. Fuel Ele. (9M2342)..... [2] PF935 P. Fuel Spin-on (1R0740)..... BF970 + P. Fuel Spin-on (1R0749)..... BF7587 + S. Fuel Spin-on (1R0750)..... BF7633 + Coolant (w/8 Units BTE) (9N6123)..... BW5139	LLA9000 w/Cummins M11 (10.8L) Eng. (12/1995-on) Dual-Flow Lube (3318853)..... BD103 + Fuel/Water Separator Ele. (Fleetguard FS1029W)..... PF7680 Fuel/Water Separator Spin-on (3329289)..... BF1259 Coolant (w/4 Units BTA+) (3315116)..... BW5071 Coolant (w/15 Units BTA+) (3318318)..... BW5075
LCF w/IHC VT275 (4.5L) Eng. (2010) Lube Spin-on (Motorcraft FL1995)..... B7039 Fuel (Frame) (Motorcraft FD4596)..... PF7698 Air (Motorcraft FA1779)..... RS4992 Trans. (Motorcraft FT145)..... P7247	LLA9000 w/Cat 3406 (14.6L) Eng. F-F Lube (Std. Efficiency) (1R0716)..... B99 + F-F Eng. Lube (High Efficiency Vers.) (1R1808)..... B7299 + Fuel/Water Separator Spin-on (Fleetguard FS1000)..... BF1259 Fuel Spin-on (1R0749)..... BF7587 +	LLA9000 w/Cummins N14 (14.0L) Eng. F-F Lube (Fleetguard LF670SC).. B196 + Dual-Flow Lube (3318853)..... BD103 + B-P Lube (3304232)..... B7577 Fuel/Water Separator Spin-on (3329289)..... BF1259 Fuel/Water Separator Spin-on (3406889)..... BF1293-SPS Fuel (154789)..... BF957-D + Coolant (3315116)..... BW5071
LL9000 w/Cummins L10 (10.0L) Eng. F-F Lube (Fleetguard LF670SC).. B196 + Dual-Flow Lube (3318853)..... BD103 + B-P Lube (3304232)..... B7577 Fuel/Water Separator Spin-on (3329289)..... BF1259 Fuel/Water Separator Spin-on (3406889)..... BF1293-SPS	LLS9000 w/Cat 3176 (10.3L) Eng. F-F Lube (Std. Efficiency) (1R0716)..... B99 + F-F Eng. Lube (High Efficiency Vers.) (1R1808)..... B7299 + Opt. B-P Lube (1W8845)..... B7577 Fuel/Water Separator Ele. (8N0205)..... PF316 Fuel/Water Separator Spin-on (Fleetguard FS1000)..... BF1259 P. Fuel Ele. (9M2342)..... [2] PF935 P. Fuel Spin-on (1R0740)..... BF970 + P. Fuel Spin-on (1R0749)..... BF7587 + S. Fuel Spin-on (1R0750)..... BF7633 +	LLS9000 w/Cat 3176 (10.3L) Eng. F-F Lube (Std. Efficiency) (1R0716)..... B99 + F-F Eng. Lube (High Efficiency Vers.) (1R1808)..... B7299 + Opt. B-P Lube (1W8845)..... B7577 Fuel/Water Separator Ele. (8N0205)..... PF316 Fuel/Water Separator Spin-on (Fleetguard FS1000)..... BF1259 P. Fuel Ele. (9M2342)..... [2] PF935 P. Fuel Spin-on (1R0740)..... BF970 + P. Fuel Spin-on (1R0749)..... BF7587 + S. Fuel Spin-on (1R0750)..... BF7633 +

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).


FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)
LLS9000 w/Cat 3176 (10.3L) Eng. (Cont'd) Coolant (w/8 Units BTE) (9N6123)..... <b>BW5139</b>	LN700, LN750, LN800 w/Ford 6.4L Eng. F-F Lube..... <b>BT251</b> B-P Lube..... <b>C704-L</b> Fuel..... <b>PF827</b> Air..... <b>PA2379-K</b>	LN8000 w/Cat 3208 (10.4L) Eng. Lube (1R0713)..... [2] <b>BT230 +</b> Lube (1R0714)..... [2] <b>B75</b> Lube (9L9200)..... [2] <b>BT364</b> <b>Box-Style Fuel/Water Separator</b> (8N9803)..... <b>BF912</b> P. Fuel Ele. (9M2341)..... <b>PF935</b> P. Fuel Spin-on (1R0740)..... <b>BF970 +</b> S. Fuel Spin-on (1R0750)..... <b>BF7633 +</b> Air (D0HZ9601D)..... <b>PA1986-K</b> Coolant (w/o Chemicals) (4355142)..... <b>B5089 +</b> Coolant (w/4 Units BTE) (9N3717)..... <b>BW5137</b> Coolant (w/8 Units BTE) (9N3718)..... <b>BW5139</b> Trans. Pan-Type (MT Series) (Allison 29538489)..... <b>19739 +</b> Trans. Spin-on (MT Series) (Allison 29510922)..... <b>BT8316-MPG</b>
LLS9000 w/Cat 3406 (14.6L) Eng. F-F Lube (Std. Efficiency) (1R0716)..... <b>B99 +</b> F-F Eng. Lube (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1000)..... <b>BF1259</b> Fuel Spin-on (1R0749)..... <b>BF7587 +</b>	LN7000 w/Ford L6-473 (7.8L) Turbo Diesel Eng. Lube (E7HZ6731A)..... [2] <b>B157</b> LN7000 w/Ford 6.6L Eng. Lube (E7HZ-6731-A)..... [2] <b>B157</b> Fuel/Water Separator (3 11/16 In. O.D., (w/o SP)) (E7HZ-9N184-A)..... <b>BF1204</b> Fuel/Water Separator (3 11/16 In. O.D., (w/SP)) (E7HZ-9N184-A) <b>BF1204-SP</b> Fuel/Water Separator (w/o Drain or Sensor Port) (F1HZ9365A)..... <b>BF1224</b> Fuel/Water Separator (w/Drain) (F1HZ9365A)..... <b>BF1223</b> Fuel/Water Separator (w/Drain & Sensor Port) (F1HZ9365A)..... <b>BF1223-SP</b> Fuel/Water Separator (Open End for Bowl) (F1HZ9365A)..... <b>BF1223-O</b> Fuel (E6HZ-9365-A)..... [2] <b>BF790</b> Air (D5HZ-9601-D)..... <b>PA2425 +</b> Coolant (w/8 Units BTA+)..... <b>BW5073</b> Coolant (w/2 Units BTE) (E7HZ-8A424-A)..... <b>BW5136</b>	LN8000 w/Cummins 6C 8.3L Eng. F-F Lube (3313281)..... <b>B205 +</b> Dual-Flow Lube (3318853)..... <b>BD103 +</b> Fuel/Water Separator (M16 x 1.5 Thd.) (3843760)..... <b>BF1226</b> Fuel/Water Separator (13/16-18 Thd.) (3925274)..... <b>BF1280 +</b> Fuel (3903640)..... <b>BF788</b> Coolant (3315115)..... <b>BW5073</b> Trans. Pan-Type (Allison 29538489)..... <b>19739 +</b> Trans. Spin-on (Allison 29510922)..... <b>BT8316-MPG</b>
LLS9000 w/Cummins L10 (10.0L) Eng. F-F Lube (Fleetguard LF670SC).. <b>B196 +</b> Dual-Flow Lube (3318853)..... <b>BD103 +</b> B-P Lube (3304232)..... <b>B7577</b> <b>Fuel/Water Separator Spin-on</b> (3315843)..... <b>BF1212 +</b> Fuel (154789)..... <b>BF957-D +</b> Coolant (w/4 Units BTA+)..... <b>BW5071</b> Coolant (w/8 Units BTA+)..... <b>BW5073</b>	LN8000 w/6-473 (7.8L) Turbo Diesel Eng. (To 1990) Lube..... [2] <b>B157</b> Fuel/Water Separator (E7HZ-9N184-A)..... <b>BF1204</b> Fuel Spin-on..... [2] <b>BF7608</b> Air (16 In.) (D5HZ-9601-D)..... <b>PA2425 +</b> Air (23 1/2 In.) (E7HZ-9601-A)..... <b>PA2726</b> Coolant (E7HZ-8A424-B)..... <b>BW5136</b> Steering (F0HZ-3C602-A)..... <b>PT8407</b>	LN9000 w/Cat 3176 (10.3L) Eng. F-F Lube (Std. Efficiency) (1R0716)..... <b>B99 +</b> F-F Eng. Lube (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> Opt. B-P Lube (1W8845)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1000)..... <b>BF1259</b> P. Fuel Ele. (9M2342)..... [2] <b>PF935</b> P. Fuel Spin-on (1R0740)..... <b>BF970 +</b> P. Fuel Spin-on (1R0749)..... <b>BF7587 +</b> S. Fuel Spin-on (1R0750)..... <b>BF7633 +</b> Coolant (w/8 Units BTE) (9N6123)..... <b>BW5139</b>
LLS9000 w/Detroit Diesel Series 60 (11.1L) Eng. F-F Lube (23518480)..... [2] <b>B495</b> Fuel/Water Separator (w/Drain) (23512317)..... <b>BF5813 +</b> Fuel/Water Separator (Open End for Bowl) (23512317)..... <b>BF5813-O +</b> Opt. Fuel/Water Separator (23516189)..... <b>BF5812</b> Opt. Fuel/Water Separator (Alliance ABPN122R50407)..... <b>BF1283-SP +</b> P. Fuel (25014274)..... <b>BF5800 +</b> S. Fuel (23518482)..... <b>BF5810</b>	LN8000 w/6-473 (7.8L) Turbo Diesel Eng. (1991-on) Lube..... [2] <b>B157</b> Fuel/Water Separator (w/o Drain or Sensor Port) (F1HZ9365A)..... <b>BF1224</b> Fuel/Water Separator (w/Drain) (F1HZ9365A)..... <b>BF1223</b> Fuel/Water Separator (w/Drain & Sensor Port) (F1HZ9365A)..... <b>BF1223-SP</b> Fuel/Water Separator (Open End for Bowl) (F1HZ9365A)..... <b>BF1223-O</b> Fuel Spin-on..... [2] <b>BF7608</b> Air (16 In.) (D5HZ-9601-D)..... <b>PA2425 +</b> Air (23 1/2 In.) (E7HZ-9601-A)..... <b>PA2726</b> Coolant (E7HZ-8A424-B)..... <b>BW5136</b> Steering (F0HZ-3C602-A)..... <b>PT8407</b>	LN9000 w/Cat 3306 (10.5L) Eng. Lube Ele. (w/Paper Wrapper) (1R0659)..... <b>PT670</b> Lube Ele. (w/Metal Wrapper) (1R0659)..... <b>PT7332</b> F-F Lube Spin-on (1R0716)..... <b>B99 +</b> F-F Lube Spin-on (Standard Vers.) (1R0739)..... <b>B76 +</b> F-F Lube Spin-on (Severe Service) (1R0739)..... <b>B76-SS +</b>
Louisville LT8501 w/Cat 3126 (7.2L) Eng. Lube (Standard Vers.) (1R0739).. <b>B76 +</b> Lube (Severe Service) (1R0739).. <b>B76-SS +</b> Fuel (1R0751)..... <b>BF7632</b> Radial Seal Air (F6HZ9601AB).... <b>RS3548</b> Radial Seal XP Air (F6HZ9601AB)..... <b>RS3548XP</b>	LN600, LN700, LN800 w/Ford 6.1L Gas Eng. Lube (D2NN6714C)..... <b>BT251</b> Fuel (Motorcraft FG789)..... <b>PF827</b>	
Louisville LT8501 w/Cummins 6CT8.3 Eng. F-F Lube (3313281)..... <b>B205 +</b> Dual-Flow Lube (3318853)..... <b>BD103 +</b> Fuel/Water Separator (3925274). <b>BF1280 +</b> S. Fuel (3903640)..... <b>BF788</b> Radial Seal Air (F6HZ9601AB).... <b>RS3548</b> Radial Seal XP Air (F6HZ9601AB)..... <b>RS3548XP</b>	LN700 w/Ford 7.0L Eng. Lube (D2NN-6714-C)..... <b>BT251</b> Fuel Ele. (Motorcraft FG789)..... <b>PF827</b> Air (E0HZ-9601-A)..... <b>PA2596</b>	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)
LN9000 w/Cat 3306 (10.5L) Eng. (Cont'd) Fuel/Water Separator Ele. (8N0205)..... PF316 Box-Style Glass Fuel/Water Separator (6N7617)..... BF912 Fuel/Water Separator Spin-on (Fleetguard FS1000)..... BF1259 P. Fuel Ele. (9M2341)..... PF935 P. Fuel Spin-on (1R0740)..... BF970 + S. Fuel Spin-on (1R0750)..... BF7633 +	LNT9000 w/Cummins VT903 V8 Turbo Eng. O. Air (Motorcraft AFA92)..... PA3786-FN 90 LN9000 w/Cummins V8 Turbo Eng. O. Air (Motorcraft AFA92)..... PA3786-FN 90 LN9000, LT9000, LTS9000 w/Cummins L10 Eng. F-F Lube (3313279)..... B196 + B-P Lube (3313283)..... B7577 Fuel/Water Separator (3308638)..... BF1212 + Fuel (154709)..... BF957 + Air (E2HZ-9601-B)..... PA2642 Coolant (w/4 Units BTA+) (3315116)..... BW5071 Coolant (w/8 Units BTA+) (3315115)..... BW5073	LNT9000 w/Cat 3306 (10.5L) Eng. Lube Ele. (w/Paper Wrapper) (1R0659)..... PT670 Lube Ele. (w/Metal Wrapper) (1R0659)..... PT7332 F-F Lube Spin-on (1R0716)..... B99 + F-F Lube Spin-on (Standard Vers.) (1R0739)..... B76 + F-F Lube Spin-on (Severe Service) (1R0739)..... B76-SS + Fuel/Water Separator Ele. (8N0205)..... PF316 Box-Style Glass Fuel/Water Separator (6N7617)..... BF912 Fuel/Water Separator Spin-on (Fleetguard FS1000)..... BF1259 P. Fuel Ele. (9M2341)..... PF935 P. Fuel Spin-on (1R0740)..... BF970 + S. Fuel Spin-on (1R0750)..... BF7633 +
LN9000 w/Cummins M11 (10.8L) Eng. (To 12/1995) Dual-Flow Lube (3318853)..... BD103 + Fuel/Water Separator Ele. (Fleetguard FS1029W)..... PF7680 Fuel/Water Separator Spin-on (3308638)..... BF1212 + Coolant (w/4 Units BTA+) (3315116)..... BW5071 Coolant (w/15 Units BTA+) (3318318)..... BW5075	LNT8000 w/Cat 3208 (10.4L) Eng. Lube (1R0713)..... [2] BT230 + Lube (1R0714)..... [2] B75 Lube (9L9200)..... [2] BT364 Box-Style Fuel/Water Separator (8N9803)..... BF912 P. Fuel Ele. (9M2341)..... PF935 P. Fuel Spin-on (1R0740)..... BF970 + S. Fuel Spin-on (1R0750)..... BF7633 + Coolant (w/o Chemicals) (4355142)..... B5089 + Coolant (w/4 Units BTE) (9N3717)..... BW5137 Coolant (w/8 Units BTE) (9N3718)..... BW5139	LNT9000 w/Cummins L10 (10.0L) Eng. F-F Lube (Fleetguard LF670SC).. B196 + Dual-Flow Lube (3318853)..... BD103 + B-P Lube (3304232)..... B7577 Fuel/Water Separator Spin-on (3315843)..... BF1212 + Fuel (154789)..... BF957-D + Coolant (w/4 Units BTA+) (3315116)..... BW5071 Coolant (w/8 Units BTA+) (3315115)..... BW5073
LN9000 w/Cummins M11 (10.8L) Eng. (12/1995-on) Dual-Flow Lube (3318853)..... BD103 + Fuel/Water Separator Ele. (Fleetguard FS1029W)..... PF7680 Fuel/Water Separator Spin-on (3329289)..... BF1259 Coolant (w/4 Units BTA+) (3315116)..... BW5071 Coolant (w/15 Units BTA+) (3318318)..... BW5075	LNT8000F w/Cummins 6CT8.3 (8.3L) Eng. Dual-Flow Lube (3318853)..... BD103 + Fuel/Water Separator (3286503)..... BF1226 Fuel (3903640)..... BF788 Coolant (w/6 Units BTA+) (3318201)..... BW5072 Coolant (w/8 Units BTA+) (3315115)..... BW5073	LNT9000 w/Cummins M11 (10.8L) Eng. (To 12/1995) Dual-Flow Lube (3318853)..... BD103 + Fuel/Water Separator Ele. (Fleetguard FS1029W)..... PF7680 Fuel/Water Separator Spin-on (3308638)..... BF1212 + Coolant (w/4 Units BTA+) (3315116)..... BW5071 Coolant (w/15 Units BTA+) (3318318)..... BW5075
LN9000 w/Cummins N14 Eng. F-F Lube (Fleetguard LF670SC).. B196 + B-P Lube (3304232)..... B7577 Dual-Flow Lube (3318853)..... BD103 + Fuel (154789)..... BF957-D +	LNT9000 w/Cat 3176 Eng. F-F Lube (1R0716)..... B99 + B-P Lube (1W8845)..... B7577 Fuel (1R0712)..... BF614 + Air (E2HZ-9601-B)..... PA2642	LNT9000 w/Cummins M11 (10.8L) Eng. (12/1995-on) Dual-Flow Lube (3318853)..... BD103 + Fuel/Water Separator Ele. (Fleetguard FS1029W)..... PF7680 Fuel/Water Separator Spin-on (3329289)..... BF1259 Coolant (w/4 Units BTA+) (3315116)..... BW5071 Coolant (w/15 Units BTA+) (3318318)..... BW5075
LN9000 w/Detroit Diesel 6V-92N, 8V-92 Series Engs. F-F Lube Ele..... P20-HD + B-P Lube Ele. (750 Size)..... C750-E + P. Fuel Spin-on..... BF5800 + S. Fuel Spin-on..... BF5810 O. Air (Motorcraft AFA93)..... PA2959-FN 90 I. Air (Motorcraft AFA94)..... PA2960 Std. Air (16 1/2 In.) (D5HZ-9601-A)..... PA2533 Conical Air (8 11/16 In. O.D.) (D8HZ-9601-A)..... PA2500 + Conical Air (10 13/32 In. O.D.) (D8HZ-9601-B)..... PA3951 DynaCell Panel Air (D8HZ-9601-E)..... PA2375 + Conical Air (12 3/4 In. O.D.) (E2HZ-9601-A)..... PA2632	LNT9000 w/Cat 3208 (10.4L) Eng. Lube (1R0713)..... [2] BT230 + Lube (1R0714)..... [2] B75 Lube (9L9200)..... [2] BT364 Box-Style Fuel/Water Separator (8N9803)..... BF912 P. Fuel Ele. (9M2341)..... PF935 P. Fuel Spin-on (1R0740)..... BF970 + S. Fuel Spin-on (1R0750)..... BF7633 + Coolant (w/o Chemicals) (4355142)..... B5089 + Coolant (w/4 Units BTE) (9N3717)..... BW5137 Coolant (w/8 Units BTE) (9N3718)..... BW5139	LNT9000 w/Cummins N14 Eng. F-F Lube (Fleetguard LF670SC).. B196 + B-P Lube (3304232)..... B7577 Dual-Flow Lube (3318853)..... BD103 + Fuel (154789)..... BF957-D +

+ See Product Guide for Variations of This Number. 90 Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)
LNT9000 w/Detroit Diesel 6V-92N, 8V-92 Series Engs.	LS8000; LT8000; LNT8000; LTS8000 w/6-473 (7.8L) Turbo Diesel Eng. (1991-on) (Cont'd)	LS9000 w/Cummins M11 (10.8L) Eng. (12/1995-on)
F-F Lube Ele..... P20-HD +	Steering (F0HZ-3C602-A)..... PT8407	Dual-Flow Lube (3318853)..... BD103 +
B-P Lube Ele. (750 Size)..... C750-E +	LS8000F w/Cummins 6CT8.3 (8.3L) Eng.	Fuel/Water Separator Ele. (Fleetguard FS1029W)..... PF7680
P. Fuel Spin-on..... BF5800 +	Dual-Flow Lube (3318853)..... BD103 +	Fuel/Water Separator Spin-on (3329289)..... BF1259
S. Fuel Spin-on..... BF5810	Fuel/Water Separator (3286503)..... BF1226	Coolant (w/4 Units BTA+) (3315116)..... BW5071
O. Air (Motorcraft AFA93)..... PA2959-FN <sup>90</sup>	Fuel (3903640)..... BF788	Coolant (w/15 Units BTA+) (3318318)..... BW5075
I. Air (Motorcraft AFA94)..... PA2960	Coolant (w/6 Units BTA+) (3318201)..... BW5072	
Std. Air (16 1/2 In.) (D5HZ-9601-A)..... PA2533	Coolant (w/8 Units BTA+) (3315115)..... BW5073	LS9000 w/Cummins M11 (10.8L) Eng. (To 12/1995)
Conical Air (8 11/16 In. O.D.) (D8HZ-9601-A)..... PA2500 +	LS9000 w/Cat 3176 (10.3L) Eng.	Dual-Flow Lube (3318853)..... BD103 +
Conical Air (10 13/32 In. O.D.) (D8HZ-9601-B)..... PA3951	F-F Lube (Std. Efficiency) (1R0716)..... B99 +	Fuel/Water Separator Ele. (Fleetguard FS1029W)..... PF7680
DynaCell Panel Air (D8HZ-9601-E)..... PA2375 +	F-F Eng. Lube (High Efficiency Vers.) (1R1808)..... B7299 +	Fuel/Water Separator Spin-on (3308638)..... BF1212 +
Conical Air (12 3/4 In. O.D.) (E2HZ-9601-A)..... PA2632	Opt. B-P Lube (1W8845)..... B7577	Coolant (w/4 Units BTA+) (3315116)..... BW5071
LS8000 w/Cat 3208 (10.4L) Eng.	Fuel/Water Separator Ele. (8N0205)..... PF316	Coolant (w/15 Units BTA+) (3318318)..... BW5075
Lube (1R0713)..... [2] BT230 +	Fuel/Water Separator Spin-on (Fleetguard FS1000)..... BF1259	LS9000 w/Cummins N14 (14.0L) Eng.
Lube (1R0714)..... [2] B75	P. Fuel Ele. (9M2342)..... [2] PF935	F-F Lube (Fleetguard LF670SC)..... B196 +
Lube (9L9200)..... [2] BT364	P. Fuel Spin-on (1R0740)..... BF970 +	Dual-Flow Lube (3318853)..... BD103 +
Box-Style Fuel/Water Separator (8N9803)..... BF912	P. Fuel Spin-on (1R0749)..... BF7587 +	B-P Lube (3304232)..... B7577
P. Fuel Ele. (9M2341)..... PF935	S. Fuel Spin-on (1R0750)..... BF7633 +	Fuel/Water Separator Spin-on (3329289)..... BF1259
P. Fuel Spin-on (1R0740)..... BF970 +	Coolant (w/8 Units BTE) (9N6123)..... BW5139	Fuel/Water Separator Spin-on (3406889)..... BF1293-SPS
S. Fuel Spin-on (1R0750)..... BF7633 +	LS9000 w/Cat 3306 (10.5L) Eng.	Fuel (154789)..... BF957-D +
Coolant (w/o Chemicals) (4355142)..... B5089 +	Lube Ele. (w/Paper Wrapper) (1R0659)..... PT670	Coolant (3315116)..... BW5071
Coolant (w/4 Units BTE) (9N3717)..... BW5137	Lube Ele. (w/Metal Wrapper) (1R0659)..... PT7332	LS9000 w/Detroit Diesel 6V-92N, 8V-92 Series Engs.
Coolant (w/8 Units BTE) (9N3718)..... BW5139	F-F Lube Spin-on (1R0716)..... B99 +	F-F Lube Ele..... P20-HD +
LS8000; LT8000; LNT8000; LTS8000 w/6-473 (7.8L) Turbo Diesel Eng. (To 1990)	F-F Lube Spin-on (Standard Vers.) (1R0739)..... B76 +	B-P Lube Ele. (750 Size)..... C750-E +
Lube..... [2] B157	F-F Lube Spin-on (Severe Service) (1R0739)..... B76-SS +	P. Fuel Spin-on..... BF5800 +
Fuel/Water Separator (E7HZ-9N184-A)..... BF1204	Fuel/Water Separator Ele. (8N0205)..... PF316	S. Fuel Spin-on..... BF5810
Fuel Spin-on..... [2] BF7608	Box-Style Glass Fuel/Water Separator (6N7617)..... BF912	O. Air (Motorcraft AFA93)..... PA2959-FN <sup>90</sup>
Air (16 In.) (D5HZ-9601-D)..... PA2425 +	Fuel/Water Separator Spin-on (Fleetguard FS1000)..... BF1259	I. Air (Motorcraft AFA94)..... PA2960
Air (23 1/2 In.) (E7HZ-9601-A)..... PA2726	P. Fuel Ele. (9M2341)..... PF935	Std. Air (16 1/2 In.) (D5HZ-9601-A)..... PA2533
Coolant (E7HZ-8A424-B)..... BW5136	P. Fuel Spin-on (1R0740)..... BF970 +	Conical Air (8 11/16 In. O.D.) (D8HZ-9601-A)..... PA2500 +
Steering (F0HZ-3C602-A)..... PT8407	S. Fuel Spin-on (1R0750)..... BF7633 +	Conical Air (10 13/32 In. O.D.) (D8HZ-9601-B)..... PA3951
LS8000; LT8000; LNT8000; LTS8000 w/6-473 (7.8L) Turbo Diesel Eng. (1991-on)	LS9000 w/Cummins L10 Eng.	DynaCell Panel Air (D8HZ-9601-E)..... PA2375 +
Lube..... [2] B157	Dual-Flow Lube (3318853)..... BD103 +	Conical Air (12 3/4 In. O.D.) (E2HZ-9601-A)..... PA2632
Fuel/Water Separator (w/o Drain or Sensor Port) (F1HZ9365A)..... BF1224	F-F Lube (Fleetguard LF670SC)..... B196 +	LT8000 w/Cat 3208 (10.4L) Eng.
Fuel/Water Separator (w/Drain) (F1HZ9365A)..... BF1223	B-P Lube (3304232)..... B7577	Lube (1R0713)..... [2] BT230 +
Fuel/Water Separator (w/Drain & Sensor Port) (F1HZ9365A)..... BF1223-SP	Opt. Fuel/Water Separator (3308638)..... BF1212 +	Lube (1R0714)..... [2] B75
Fuel/Water Separator (Open End for Bowl) (F1HZ9365A)..... BF1223-O	Fuel (154789)..... BF957-D +	Lube (9L9200)..... [2] BT364
Fuel Spin-on..... [2] BF7608	Air (E2HZ-9601-B)..... PA2642	Box-Style Fuel/Water Separator (8N9803)..... BF912
Air (16 In.) (D5HZ-9601-D)..... PA2425 +	Coolant (w/4 Units BTA+) (3315116)..... BW5071	P. Fuel Ele. (9M2341)..... PF935
Air (23 1/2 In.) (E7HZ-9601-A)..... PA2726	Coolant (w/6 Units BTA+) (3315115)..... BW5073	P. Fuel Spin-on (1R0740)..... BF970 +
Coolant (E7HZ-8A424-B)..... BW5136		

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.


Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)
LT8000 w/Cat 3208 (10.4L) Eng. (Cont'd)	LT8513 w/Cat 3126 (7.2L) Eng.	LT9000 w/Cat 3306 Eng.
S. Fuel Spin-on (1R0750)..... <b>BF7633 +</b>	Lube (Standard Vers.) (1R0739).. <b>B76 +</b>	Lube (Standard Vers.) (1R0739).. <b>B76 +</b>
Coolant (w/o Chemicals)	Lube (Severe Service) (1R0739).. <b>B76-SS +</b>	Lube (Severe Service) (1R0739).. <b>B76-SS +</b>
(4355142)..... <b>B5089 +</b>	Fuel/Water Separator (1752949). <b>BF1268</b>	Fuel/Water Separator
Coolant (w/4 Units BTE)	Fuel/Water Separator	(256-8753)..... <b>BF1259</b>
(9N3717)..... <b>BW5137</b>	(Fleetguard FS1000)..... <b>BF1259</b>	P. Fuel (1R1740)..... <b>BF970 +</b>
Coolant (w/8 Units BTE)	Fuel/Water Separator (w/Sensor	S. Fuel (1R0750)..... <b>BF7633 +</b>
(9N3718)..... <b>BW5139</b>	Port) (1986378)..... <b>BF7798-SP</b>	
LT8000 w/Cummins ISC Eng.	Fuel/Water Separator (Open End	LT9000 w/Cat 3406E Eng.
Dual-Flow Lube (Fleetguard	for Bowl) (1986378)..... <b>BF7798-O</b>	Lube..... <b>B99 +</b>
LF3000)..... <b>BD103 +</b>	Fuel Ele. (9M2342)..... <b>[2] PF935</b>	P. Fuel Ele..... <b>PF935</b>
Fuel/Water Separator (13/16-18	Fuel Spin-on (1R0751)..... <b>BF7632</b>	Fuel Spin-on..... <b>BF7587 +</b>
Thd.) (Fleetguard FS1280)..... <b>BF1280 +</b>	Trans. (Fuller 4304827)..... <b>BT223</b>	P. Fuel Spin-on (E6HZ-9155-E).. <b>BF5800 +</b>
Fuel/Water Separator (M16 x 1.5	Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	O. Air (Motorcraft AFA93)..... <b>PA2959-FN<sup>90</sup></b>
Thd.) (Fleetguard FS1251)..... <b>BF1226</b>		I. Air (Motorcraft AFA94)..... <b>PA2960</b>
Radial Seal Air (Fleetguard	LT8513 w/Cummins 6CT8.3 (8.3L) Eng.	Radial Seal O. Air
AF25354)..... <b>RS3548</b>	F-F Lube (3313281)..... <b>B205 +</b>	(F6HZ-9601-CA)..... <b>RS3738</b>
Radial Seal XP Air (Fleetguard	Dual-Flow Lube (3318853)..... <b>BD103 +</b>	Radial Seal I. Air
AF25354)..... <b>RS3548XP</b>	Fuel/Water Separator (3925274). <b>BF1280 +</b>	(F6HZ-9602-AA)..... <b>RS3739</b>
Coolant (Fleetguard WF2071)..... <b>BW5071</b>	Fuel/Water Separator (3286503). <b>BF1226</b>	Air (15 3/4 In. O.D., w/Fins) (Don.
	Fuel (3903640)..... <b>BF788</b>	P127918)..... <b>PA1980-FN</b>
LT8000F w/Cummins 6CT8.3 (8.3L) Eng.	Coolant (w/6 Units BTA+)..... <b>BW5072</b>	Conical Air (8 11/16 In. O.D.)
F-F Lube (3313281)..... <b>B205 +</b>	(3318201)..... <b>BW5072</b>	(Don. P129472)..... <b>PA2500 +</b>
Dual-Flow Lube (3318853)..... <b>BD103 +</b>	Coolant (w/8 Units BTA+)..... <b>BW5073</b>	Air (7 7/16 In. O.D.) (Don.
Fuel/Water Separator (3925274). <b>BF1280 +</b>	(3315115)..... <b>BW5073</b>	P142367)..... <b>PA2642</b>
Fuel/Water Separator (3286503). <b>BF1226</b>		Conical Air (12 3/4 In. O.D.)
Fuel (3903640)..... <b>BF788</b>	LT9000 w/Cat 3176 (10.3L) Eng.	(Don. P141228)..... <b>PA2632</b>
Coolant (w/6 Units BTA+)..... <b>BW5072</b>	F-F Lube (Std. Efficiency)	Conical Air (10 13/32 In. O.D.)
(3318201)..... <b>BW5072</b>	(1R0716)..... <b>B99 +</b>	(D8HZ-9601-B)..... <b>PA3951</b>
Coolant (w/8 Units BTA+)..... <b>BW5073</b>	F-F Eng. Lube (High Efficiency	Radial Seal O. Air (Standard)
(3315115)..... <b>BW5073</b>	Vers.) (1R1808)..... <b>B7299 +</b>	(F1HZ-9601-B)..... <b>RS3518</b>
Trans. (Fuller 4304827)..... <b>BT223</b>	Opt. B-P Lube (1W8845)..... <b>B7577</b>	Radial Seal XP O. Air (Upgrade)
Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	Fuel/Water Separator Ele.	(F1HZ9601B)..... <b>RS3518XP</b>
	(8N0205)..... <b>PF316</b>	Coolant (w/4 Units BTA+)..... <b>BW5071</b>
LT8511 w/Cat 3126 (7.2L) Eng.	Fuel/Water Separator Spin-on	Coolant (w/8 Units BTE)
Lube (Standard Vers.) (1R0739).. <b>B76 +</b>	(Fleetguard FS1000)..... <b>BF1259</b>	(9N-6123)..... <b>BW5139</b>
Lube (Severe Service) (1R0739).. <b>B76-SS +</b>	P. Fuel Ele. (9M2342)..... <b>[2] PF935</b>	
Fuel/Water Separator (1752949). <b>BF1268</b>	P. Fuel Spin-on (1R0740)..... <b>BF970 +</b>	LT9000 w/Cummins 8.3L Eng.
Fuel/Water Separator	P. Fuel Spin-on (1R0749)..... <b>BF7587 +</b>	Dual-Flow Lube..... <b>BD103 +</b>
(Fleetguard FS1000)..... <b>BF1259</b>	S. Fuel Spin-on (1R0750)..... <b>BF7633 +</b>	Fuel/Water Separator..... <b>BF1226</b>
Fuel/Water Separator (w/Sensor	Coolant (w/8 Units BTE)	Radial Seal O. Air
Port) (1986378)..... <b>BF7798-SP</b>	(9N6123)..... <b>BW5139</b>	(F6HZ-9601-CA)..... <b>RS3738</b>
Fuel/Water Separator (Open End		Radial Seal I. Air
for Bowl) (1986378)..... <b>BF7798-O</b>	LT9000 w/Cat 3208 (10.4L) Eng.	(F6HZ-9602-AA)..... <b>RS3739</b>
Fuel Ele. (9M2342)..... <b>[2] PF935</b>	Lube (1R0713)..... <b>[2] BT230 +</b>	
Fuel Spin-on (1R0751)..... <b>BF7632</b>	Lube (1R0714)..... <b>[2] B75</b>	LT9000 w/Cummins M11 (10.8L) Eng. (To
Trans. (Fuller 4304827)..... <b>BT223</b>	Lube (9L9200)..... <b>[2] BT364</b>	12/1995)
Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	Box-Style Fuel/Water Separator	Dual-Flow Lube (3318853)..... <b>BD103 +</b>
	(8N9803)..... <b>BF912</b>	Fuel/Water Separator Ele.
LT8511 w/Cummins 6CT8.3 (8.3L) Eng.	P. Fuel Ele. (9M2341)..... <b>PF935</b>	(Fleetguard FS1029W)..... <b>PF7680</b>
F-F Lube (3313281)..... <b>B205 +</b>	P. Fuel Spin-on (1R0740)..... <b>BF970 +</b>	Fuel/Water Separator Spin-on
Dual-Flow Lube (3318853)..... <b>BD103 +</b>	S. Fuel Spin-on (1R0750)..... <b>BF7633 +</b>	(3308638)..... <b>BF1212 +</b>
Fuel/Water Separator (3925274). <b>BF1280 +</b>	Coolant (w/o Chemicals)	Coolant (w/4 Units BTA+)
Fuel/Water Separator (3286503). <b>BF1226</b>	(4355142)..... <b>B5089 +</b>	(3315116)..... <b>BW5071</b>
Fuel (3903640)..... <b>BF788</b>	Coolant (w/4 Units BTE)	Coolant (w/15 Units BTA+)
Coolant (w/6 Units BTA+)..... <b>BW5072</b>	(9N3717)..... <b>BW5137</b>	(3318318)..... <b>BW5075</b>
(3318201)..... <b>BW5072</b>	Coolant (w/8 Units BTE)	Trans. Ele. (HT Series) (Allison
Coolant (w/8 Units BTA+)..... <b>BW5073</b>	(9N3718)..... <b>BW5139</b>	29510918)..... <b>PT8330-MPG</b>
(3315115)..... <b>BW5073</b>		

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)
LT9000 w/Cummins M11 (10.8L) Eng. (12/1995-on)	LT9501 w/Cat 3306 (10.5L) Eng. Lube Ele. (w/Paper Wrapper) (1R0659).....	LT9501 w/Cat C12 (12.0L) Eng. (Cont'd) Fuel/Water Separator Spin-on (Fleetguard FS1000).....
Dual-Flow Lube (3318853).....	PT670	BF1259
Fuel/Water Separator Ele. (Fleetguard FS1029W).....	Lube Ele. (w/Metal Wrapper) (1R0659).....	P. Fuel Ele. (9M2342).....
PF7680	PT7332	[2] PF935
Fuel/Water Separator Spin-on (3329289).....	F-F Lube Spin-on (1R0716).....	Fuel Spin-on (Standard Vers.) (1R1712).....
BF1259	B99 +	BF614 +
Coolant (w/4 Units BTA+) (3315116).....	F-F Lube Spin-on (Standard Vers.) (1R0739).....	Fuel Spin-on (High Efficiency Vers.) (1R0749).....
BW5071	B76 +	BF7587 +
Coolant (w/15 Units BTA+) (3318318).....	F-F Lube Spin-on (Severe Service) (1R0739).....	Coolant (w/4 Units BTE) (9N3368).....
BW5075	B76-SS +	BW5137
Trans. Ele. (HT Series) (Allison 29510918).....	Fuel/Water Separator Ele. (8N0205).....	Coolant (w/8 Units BTE) (9N3366).....
PT8330-MPG	PF316	BW5139
LT9000 w/Cummins N14 (14.0L) Eng. F-F Lube (Fleetguard LF670SC)..	Box-Style Glass Fuel/Water Separator (6N7617).....	LT9501 w/Cummins M11 (10.8L) Eng. Dual-Flow Lube (3318853).....
B196 +	BF912	BD103 +
Dual-Flow Lube (3318853).....	Fuel/Water Separator Spin-on (Fleetguard FS1000).....	Fuel/Water Separator Ele. (Fleetguard FS1029W).....
BD103 +	BF1259	PF7680
B-P Lube (3304232).....	P. Fuel Ele. (9M2341).....	Fuel/Water Separator Spin-on (3329289).....
B7577	PF935	BF1259
Fuel/Water Separator Spin-on (3329289).....	P. Fuel Spin-on (1R0740).....	Coolant (w/4 Units BTA+) (3315116).....
BF1259	BF970 +	BW5071
Fuel/Water Separator Spin-on (3406889).....	S. Fuel Spin-on (1R0750).....	Coolant (w/15 Units BTA+) (3318318).....
BF1293-SPS	BF7633 +	BW5075
Fuel (154789).....	LT9501 w/Cat C10 (10.3L) Eng. F-F Lube (Std. Version) (1R0716).....	LT9501 w/Cummins N14 (14.0L) Eng. F-F Lube (Fleetguard LF670SC)..
BF957-D +	B99 +	B196 +
Coolant (3315116).....	F-F Lube (High Efficiency Vers.) (1R1808).....	Dual-Flow Lube (3318853).....
BW5071	B7299 +	BD103 +
Trans. (Fuller 4304827).....	B7577	B7577
BT223	B-P Lube (1W8845).....	Fuel/Water Separator Spin-on (3329289).....
Opt. Trans. (Fuller 17237).....	Fuel/Water Separator Ele. (8N0205).....	BF1259
B2 +	PF316	Fuel/Water Separator Spin-on (3406889).....
LT9000 w/Detroit Diesel Series 60 (11.1L) or (12.7L) Eng. F-F Lube (23518480).....	Fuel/Water Separator Spin-on (Open End for Bowl) (Alliance ABPN122R50421).....	BF1293-SPS
[2] B495	BF1395-O	Fuel (154789).....
Fuel/Water Separator (w/Drain) (23512317).....	Fuel/Water Separator Spin-on (w/Sensor Port) (Alliance ABPN122R50421).....	BF957-D +
BF5813 +	BF1395-SP	BW5071
Fuel/Water Separator (Open End for Bowl) (23512317).....	Fuel/Water Separator Spin-on (w/Drain) (Alliance ABPN122R50421).....	LT9501 w/Detroit Diesel Series 60 (11.1L) or (12.7L) Eng. F-F Lube (23518480).....
BF5813-O +	BF1265	[2] B495
Opt. Fuel/Water Separator (23516189).....	Fuel/Water Separator Spin-on (Fleetguard FS1000).....	Fuel/Water Separator (w/Drain) (23512317).....
BF5812	BF1259	BF5813 +
Opt. Fuel/Water Separator (Alliance ABPN122R50407).....	Fuel (Standard Vers.) (1R1712)...	Fuel/Water Separator (Open End for Bowl) (23512317).....
BF1283-SP +	BF614 +	BF5813-O +
P. Fuel (25014274).....	Fuel (High Efficiency Vers.) (1R0749).....	Opt. Fuel/Water Separator (23516189).....
BF5800 +	BF7587 +	BF5812
S. Fuel (23518482).....	LT9501 w/Cat C12 (12.0L) Eng. F-F Lube (Std. Version) (1R0716).....	Opt. Fuel/Water Separator (Alliance ABPN122R50407).....
BF5810	B99 +	BF1283-SP +
PA2642	F-F Lube (High Efficiency Vers.) (1R1808).....	P. Fuel (25014274).....
LT9501 w/Cat 3176 (10.3L) Eng. F-F Lube (Std. Efficiency) (1R0716).....	B7299 +	BF5800 +
B99 +	B7577	BF5810
F-F Eng. Lube (High Efficiency Vers.) (1R1808).....	Fuel/Water Separator Ele. (8N0205).....	S. Fuel (23518482).....
B7299 +	PF316	BF5810
Opt. B-P Lube (1W8845).....	Fuel/Water Separator Spin-on (Open End for Bowl) (Alliance ABPN122R50421).....	LT9511 w/Cat 3306 (10.5L) Eng. Lube Ele. (w/Paper Wrapper) (1R0659).....
B7577	BF1395-O	PT670
Fuel/Water Separator Ele. (8N0205).....	Fuel/Water Separator Spin-on (w/Sensor Port) (Alliance ABPN122R50421).....	Lube Ele. (w/Metal Wrapper) (1R0659).....
PF316	BF1395-SP	PT7332
Fuel/Water Separator Spin-on (Fleetguard FS1000).....	Fuel/Water Separator Spin-on (w/Drain) (Alliance ABPN122R50421).....	F-F Lube Spin-on (1R0716).....
BF1259	BF1265	B99 +
[2] PF935	Fuel/Water Separator Spin-on (w/Drain) (Alliance ABPN122R50421).....	F-F Lube Spin-on (Standard Vers.) (1R0739).....
BF970 +	BF1265	B76 +
BF7587 +	Coolant (w/8 Units BTE) (9N6123).....	F-F Lube Spin-on (Severe Service) (1R0739).....
BF7633 +	BW5139	B76-SS +
BF7633 +		Fuel/Water Separator Ele. (8N0205).....
BF7633 +		PF316

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)
LT9511 w/Cat 3306 (10.5L) Eng. (Cont'd) <b>Box-Style Glass Fuel/Water Separator</b> (6N7617)..... <b>BF912</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1000)..... <b>BF1259</b> <b>P. Fuel Ele.</b> (9M2341)..... <b>PF935</b> <b>P. Fuel Spin-on</b> (1R0740)..... <b>BF970 +</b> <b>S. Fuel Spin-on</b> (1R0750)..... <b>BF7633 +</b>	LT9511 w/Cat C12 (12.0L) Eng. (Cont'd) <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1000)..... <b>BF1259</b> <b>P. Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (Standard Vers.) (1R1712)..... <b>BF614 +</b> <b>Fuel Spin-on</b> (High Efficiency Vers.) (1R0749)..... <b>BF7587 +</b> <b>Coolant</b> (w/4 Units BTE) (9N3368)..... <b>BW5137</b> <b>Coolant</b> (w/8 Units BTE) (9N3366)..... <b>BW5139</b>	LT9513 w/Cat 3126 Eng. (Cont'd) <b>Radial Seal XP Air</b> (F6HZ9601AB)..... <b>RS3548XP</b> <b>Trans.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>
LT9511 w/Cat 3406 (14.6L) Eng. <b>F-F Lube</b> (Std. Efficiency) (1R0716)..... <b>B99 +</b> <b>F-F Eng. Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1000)..... <b>BF1259</b> <b>Fuel Spin-on</b> (1R0749)..... <b>BF7587 +</b> <b>Coolant</b> (w/4 Units BTE) (9N3368)..... <b>BW5137</b> <b>Coolant</b> (w/8 Units BTE) (9N3366)..... <b>BW5139</b>	LT9511 w/Cummins M11 (10.8L) Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> (3329289)..... <b>BF1259</b> <b>Coolant</b> (w/4 Units BTA+) (3315116)..... <b>BW5071</b> <b>Coolant</b> (w/15 Units BTA+) (3318318)..... <b>BW5075</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	LT9513 w/Cat 3176 (10.3L) Eng. <b>F-F Lube</b> (Std. Efficiency) (1R0716)..... <b>B99 +</b> <b>F-F Eng. Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> <b>Opt. B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1000)..... <b>BF1259</b> <b>P. Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>P. Fuel Spin-on</b> (1R0740)..... <b>BF970 +</b> <b>P. Fuel Spin-on</b> (1R0749)..... <b>BF7587 +</b> <b>S. Fuel Spin-on</b> (1R0750)..... <b>BF7633 +</b> <b>Coolant</b> (w/8 Units BTE) (9N6123)..... <b>BW5139</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>
LT9511 w/Cat C10 (10.3L) Eng. <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99 +</b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> <b>B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Alliance ABPN122R50421)..... <b>BF1395-O</b> <b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (Alliance ABPN122R50421)..... <b>BF1395-SP</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (Alliance ABPN122R50421)..... <b>BF1265</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1000)..... <b>BF1259</b> <b>Fuel</b> (Standard Vers.) (1R1712)..... <b>BF614 +</b> <b>Fuel</b> (High Efficiency Vers.) (1R0749)..... <b>BF7587 +</b>	LT9511 w/Cummins N14 (14.0L) Eng. <b>F-F Lube</b> (Fleetguard LF670SC)..... <b>B196 +</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Fuel/Water Separator Spin-on</b> (3329289)..... <b>BF1259</b> <b>Fuel/Water Separator Spin-on</b> (3406889)..... <b>BF1293-SPS</b> <b>Fuel</b> (154789)..... <b>BF957-D +</b> <b>Coolant</b> (3315116)..... <b>BW5071</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	LT9513 w/Cat 3306 (10.5L) Eng. <b>Lube Ele.</b> (w/Paper Wrapper) (1R0659)..... <b>PT670</b> <b>Lube Ele.</b> (w/Metal Wrapper) (1R0659)..... <b>PT7332</b> <b>F-F Lube Spin-on</b> (1R0716)..... <b>B99 +</b> <b>F-F Lube Spin-on</b> (Standard Vers.) (1R0739)..... <b>B76 +</b> <b>F-F Lube Spin-on</b> (Severe Service) (1R0739)..... <b>B76-SS +</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Box-Style Glass Fuel/Water Separator</b> (6N7617)..... <b>BF912</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1000)..... <b>BF1259</b> <b>P. Fuel Ele.</b> (9M2341)..... <b>PF935</b> <b>P. Fuel Spin-on</b> (1R0740)..... <b>BF970 +</b> <b>S. Fuel Spin-on</b> (1R0750)..... <b>BF7633 +</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>
LT9511 w/Cat C12 (12.0L) Eng. <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99 +</b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> <b>B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Alliance ABPN122R50421)..... <b>BF1395-O</b> <b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (Alliance ABPN122R50421)..... <b>BF1395-SP</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (Alliance ABPN122R50421)..... <b>BF1265</b>	LT9511 w/Detroit Diesel Series 60 (11.1L) or (12.7L) Eng. <b>F-F Lube</b> (23518480)..... <b>[2] B495</b> <b>Fuel/Water Separator</b> (w/Drain) (23512317)..... <b>BF5813 +</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (23512317)..... <b>BF5813-O +</b> <b>Opt. Fuel/Water Separator</b> (23516189)..... <b>BF5812</b> <b>Opt. Fuel/Water Separator</b> (Alliance ABPN122R50407)..... <b>BF1283-SP +</b> <b>P. Fuel</b> (25014274)..... <b>BF5800 +</b> <b>S. Fuel</b> (23518482)..... <b>BF5810</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	LT9513 w/Cat 3406 (14.6L) Eng. <b>F-F Lube</b> (Std. Efficiency) (1R0716)..... <b>B99 +</b> <b>F-F Eng. Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1000)..... <b>BF1259</b> <b>Fuel Spin-on</b> (1R0749)..... <b>BF7587 +</b> <b>Coolant</b> (w/4 Units BTE) (9N3368)..... <b>BW5137</b> <b>Coolant</b> (w/8 Units BTE) (9N3366)..... <b>BW5139</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).




FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)
LT9513 w/Cat 3406 (14.6L) Eng. (Cont'd) <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2+</b>	LT9513 w/Cummins M11 (10.8L) Eng. (Cont'd) <b>Coolant</b> (w/15 Units BTA+) (3318318)..... <b>BW5075</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2+</b>	LT9522 w/Cat C10 (10.3L) Eng. (Cont'd) <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Alliance ABPN122R50421)..... <b>BF1395-O</b> <b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (Alliance ABPN122R50421)..... <b>BF1395-SP</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (Alliance ABPN122R50421)..... <b>BF1265</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1000)..... <b>BF1259</b> <b>Fuel</b> (Standard Vers.) (1R1712)... <b>BF614+</b> <b>Fuel</b> (High Efficiency Vers.) (1R0749)..... <b>BF7587+</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2+</b>
LT9513 w/Cat C10 (10.3L) Eng. (Std. Version)..... <b>B99+</b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299+</b> <b>B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Alliance ABPN122R50421)..... <b>BF1395-O</b> <b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (Alliance ABPN122R50421)..... <b>BF1395-SP</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (Alliance ABPN122R50421)..... <b>BF1265</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1000)..... <b>BF1259</b> <b>Fuel</b> (Standard Vers.) (1R1712)... <b>BF614+</b> <b>Fuel</b> (High Efficiency Vers.) (1R0749)..... <b>BF7587+</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2+</b>	LT9513 w/Cummins N14 (14.0L) Eng. <b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196+</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103+</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Fuel/Water Separator Spin-on</b> (3329289)..... <b>BF1259</b> <b>Fuel/Water Separator Spin-on</b> (3406889)..... <b>BF1293-SPS</b> <b>Fuel</b> (154789)..... <b>BF957-D+</b> <b>Radial Seal O. Air</b> (Standard) (F1HZ9601B)..... <b>RS3518</b> <b>Radial Seal XP O. Air</b> (Upgrade) (F1HZ9601B)..... <b>RS3518XP</b> <b>Coolant</b> (3315116)..... <b>BW5071</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2+</b>	LT9522 w/Cat C12 (12.0L) Eng. <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99+</b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299+</b> <b>B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (1335673)... <b>BF1395-O</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (1335673)..... <b>BF1265</b> <b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (1335673)..... <b>BF1395-SP</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1000)..... <b>BF1259</b> <b>P. Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (Standard Vers.) (1R1712)..... <b>BF614+</b> <b>Fuel Spin-on</b> (High Efficiency Vers.) (1R0749)..... <b>BF7587+</b> <b>Coolant</b> (w/4 Units BTE) (9N3368)..... <b>BW5137</b> <b>Coolant</b> (w/8 Units BTE) (9N3366)..... <b>BW5139</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2+</b>
LT9513 w/Cat C12 (12.0L) Eng. <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99+</b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299+</b> <b>B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (1335673)... <b>BF1395-O</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (1335673)..... <b>BF1265</b> <b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (1335673)..... <b>BF1395-SP</b> <b>P. Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (Standard Vers.) (1R1712)..... <b>BF614+</b> <b>Fuel Spin-on</b> (High Efficiency Vers.) (1R0749)..... <b>BF7587+</b> <b>Coolant</b> (w/4 Units BTE) (9N3368)..... <b>BW5137</b> <b>Coolant</b> (w/8 Units BTE) (9N3366)..... <b>BW5139</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2+</b>	LT9513 w/Detroit Diesel Series 60 (11.1L) or (12.7L) Eng. <b>F-F Lube</b> (23518480)..... <b>[2] B495</b> <b>Fuel/Water Separator</b> (w/Drain) (23512317)..... <b>BF5813+</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (23512317)..... <b>BF5813-O+</b> <b>Opt. Fuel/Water Separator</b> (23516189)..... <b>BF5812</b> <b>Opt. Fuel/Water Separator</b> (Alliance ABPN122R50407)..... <b>BF1283-SP+</b> <b>P. Fuel</b> (25014274)..... <b>BF5800+</b> <b>S. Fuel</b> (23518482)..... <b>BF5810</b>	LT9522 w/Cat C10 (10.3L) Eng. (Cont'd) <b>Fuel/Water Separator Spin-on</b> (w/Drain) (1335673)..... <b>BF1265</b> <b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (1335673)..... <b>BF1395-SP</b> <b>Fuel Spin-on</b> (Standard Vers.) (1R1712)..... <b>BF614+</b> <b>Fuel Spin-on</b> (High Efficiency Vers.) (1R0749)..... <b>BF7587+</b> <b>Coolant</b> (w/4 Units BTE) (9N3368)..... <b>BW5137</b> <b>Coolant</b> (w/8 Units BTE) (9N3366)..... <b>BW5139</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2+</b>
LT9513 w/Cat C12 (12.0L) Eng. <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99+</b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299+</b> <b>B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (1335673)... <b>BF1395-O</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (1335673)..... <b>BF1265</b> <b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (1335673)..... <b>BF1395-SP</b> <b>P. Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (Standard Vers.) (1R1712)..... <b>BF614+</b> <b>Fuel Spin-on</b> (High Efficiency Vers.) (1R0749)..... <b>BF7587+</b> <b>Coolant</b> (w/4 Units BTE) (9N3368)..... <b>BW5137</b> <b>Coolant</b> (w/8 Units BTE) (9N3366)..... <b>BW5139</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2+</b>	LT9513 w/HD1460 Eng. <b>Dual-Flow Lube</b> ..... <b>BD103+</b> <b>Fuel/Water Separator</b> ..... <b>BF1226</b>	LT9522 w/Cummins M11 (10.8L) Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103+</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> (3329289)..... <b>BF1259</b> <b>Coolant</b> (w/4 Units BTA+) (3315116)..... <b>BW5071</b> <b>Coolant</b> (w/15 Units BTA+) (3318318)..... <b>BW5075</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2+</b>
LT9513 w/Cat 3406 (14.6L) Eng. <b>F-F Lube</b> (Std. Efficiency) (1R0716)..... <b>B99+</b> <b>F-F Eng. Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299+</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1000)..... <b>BF1259</b> <b>Fuel Spin-on</b> (1R0749)..... <b>BF7587+</b> <b>Coolant</b> (w/4 Units BTE) (9N3368)..... <b>BW5137</b> <b>Coolant</b> (w/8 Units BTE) (9N3366)..... <b>BW5139</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2+</b>	LT9513 w/HD1460 Eng. <b>Dual-Flow Lube</b> ..... <b>BD103+</b> <b>Fuel/Water Separator</b> ..... <b>BF1226</b>	LT9522 w/Cummins M11 (10.8L) Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103+</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> (3329289)..... <b>BF1259</b> <b>Coolant</b> (w/4 Units BTA+) (3315116)..... <b>BW5071</b> <b>Coolant</b> (w/15 Units BTA+) (3318318)..... <b>BW5075</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2+</b>
LT9513 w/Cummins M11 (10.8L) Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103+</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> (3329289)..... <b>BF1259</b> <b>Coolant</b> (w/4 Units BTA+) (3315116)..... <b>BW5071</b>	LT9522 w/Cat C10 (10.3L) Eng. <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99+</b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299+</b> <b>B-P Lube</b> (1W8845)..... <b>B7577</b>	LT9522 w/Cummins M11 (10.8L) Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103+</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> (3329289)..... <b>BF1259</b> <b>Coolant</b> (w/4 Units BTA+) (3315116)..... <b>BW5071</b> <b>Coolant</b> (w/15 Units BTA+) (3318318)..... <b>BW5075</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2+</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)
LT9522 w/Cummins N14 (14.0L) Eng. F-F Lube (Fleetguard LF670SC).. <b>B196 +</b> Dual-Flow Lube (3318853)..... <b>BD103 +</b> B-P Lube (3304232)..... <b>B7577</b> Fuel/Water Separator Spin-on (3329289)..... <b>BF1259</b> Fuel/Water Separator Spin-on (3406889)..... <b>BF1293-SPS</b> Fuel (154789)..... <b>BF957-D +</b> Coolant (3315116)..... <b>BW5071</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	LTA9000 w/Cummins M11 (10.8L) Eng. (To 12/1995) (Cont'd) Fuel/Water Separator Ele. (Fleetguard FS1029W)..... <b>PF7680</b> Fuel/Water Separator Spin-on (3308638)..... <b>BF1212 +</b> Coolant (3318318)..... <b>BW5075</b>	LTL9000 w/Cummins L10 (10.0L) Eng. (Cont'd) Coolant (w/4 Units BTA+)..... <b>BW5071</b> (3315116)..... Coolant (w/8 Units BTA+)..... <b>BW5073</b> (3315115)..... Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b>
LT9522 w/Detroit Diesel Series 60 (12.7L) Eng. F-F Lube (23518480)..... <b>[2] B495</b> Fuel/Water Separator (w/Drain) (23512317)..... <b>BF5813 +</b> Fuel/Water Separator (Open End for Bowl) (23512317)..... <b>BF5813-O +</b> Opt. Fuel/Water Separator (23516189)..... <b>BF5812</b> Opt. Fuel/Water Separator (Alliance ABPN122R50407)..... <b>BF1283-SP +</b> P. Fuel (25014274)..... <b>BF5800 +</b> S. Fuel (23518482)..... <b>BF5810</b>	LTA9000 w/Cummins M11 (10.8L) Eng. (12/1995-on) Dual-Flow Lube (3318853)..... <b>BD103 +</b> Fuel/Water Separator Ele. (Fleetguard FS1029W)..... <b>PF7680</b> Fuel/Water Separator Spin-on (3329289)..... <b>BF1259</b> Coolant (3318318)..... <b>BW5075</b>	LTL9000 w/Cummins M11 (10.8L) Eng. (To 12/1995) Dual-Flow Lube (3318853)..... <b>BD103 +</b> Fuel/Water Separator Ele. (Fleetguard FS1029W)..... <b>PF7680</b> Fuel/Water Separator Spin-on (3308638)..... <b>BF1212 +</b> Coolant (w/4 Units BTA+)..... <b>BW5071</b> (3315116)..... Coolant (w/15 Units BTA+)..... <b>BW5075</b> (3318318)..... Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b>
LTA9000 w/Cat 3306 (10.5L) Eng. Lube Ele. (w/Paper Wrapper) (1R0659)..... <b>PT670</b> Lube Ele. (w/Metal Wrapper) (1R0659)..... <b>PT7332</b> F-F Lube Spin-on (1R0716)..... <b>B99 +</b> F-F Lube Spin-on (Standard Vers.) (1R0739)..... <b>B76 +</b> F-F Lube Spin-on (Severe Service) (1R0739)..... <b>B76-SS +</b> Fuel/Water Separator Ele. (8N0205)..... <b>PF316</b> Box-Style Glass Fuel/Water Separator (6N7617)..... <b>BF912</b> Fuel/Water Separator Spin-on (Fleetguard FS1000)..... <b>BF1259</b> P. Fuel Ele. (9M2341)..... <b>PF935</b> P. Fuel Spin-on (1R0740)..... <b>BF970 +</b> S. Fuel Spin-on (1R0750)..... <b>BF7633 +</b>	LTA9000 w/Detroit Diesel Series 60 (11.1L) or (12.7L) Eng. (1993-on) F-F Lube (23518480)..... <b>[2] B495</b> Fuel/Water Separator (w/Drain) (23512317)..... <b>BF5813 +</b> Fuel/Water Separator (Open End for Bowl) (23512317)..... <b>BF5813-O +</b> Opt. Fuel/Water Separator (23516189)..... <b>BF5812</b> Opt. Fuel/Water Separator (Alliance ABPN122R50407)..... <b>BF1283-SP +</b> P. Fuel (25014274)..... <b>BF5800 +</b> S. Fuel (23518482)..... <b>BF5810</b>	LTL9000 w/Cummins M11 (10.8L) Eng. (12/1995-on) Dual-Flow Lube (3318853)..... <b>BD103 +</b> Fuel/Water Separator Ele. (Fleetguard FS1029W)..... <b>PF7680</b> Fuel/Water Separator Spin-on (3329289)..... <b>BF1259</b> Coolant (w/4 Units BTA+)..... <b>BW5071</b> (3315116)..... Coolant (w/15 Units BTA+)..... <b>BW5075</b> (3318318)..... Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b>
LTA9000 w/Detroit Diesel Series 60 (11.1L) or (12.7L) Eng. (To 1992) F-F Lube (25010495)..... <b>[2] B95 +</b> B-P Lube (23530413)..... <b>B7577</b> Fuel/Water Separator (w/Drain) (23512317)..... <b>BF5813 +</b> Fuel/Water Separator (Open End for Bowl) (23512317)..... <b>BF5813-O +</b> Opt. Fuel/Water Separator (23516189)..... <b>BF5812</b> Opt. Fuel/Water Separator (Alliance ABPN122R50407)..... <b>BF1283-SP +</b> P. Fuel (25014274)..... <b>BF5800 +</b> S. Fuel (23518482)..... <b>BF5810</b>	LTA9000 w/Detroit Diesel Series 60 (11.1L) or (12.7L) Eng. (To 1992) F-F Lube (25010495)..... <b>[2] B95 +</b> B-P Lube (23530413)..... <b>B7577</b> Fuel/Water Separator (w/Drain) (23512317)..... <b>BF5813 +</b> Fuel/Water Separator (Open End for Bowl) (23512317)..... <b>BF5813-O +</b> Opt. Fuel/Water Separator (23516189)..... <b>BF5812</b> Opt. Fuel/Water Separator (Alliance ABPN122R50407)..... <b>BF1283-SP +</b> P. Fuel (25014274)..... <b>BF5800 +</b> S. Fuel (23518482)..... <b>BF5810</b>	LTL9000 w/Cummins VT225 (9.1L) Eng. F-F Lube (3313281)..... <b>B205 +</b> B-P Lube (3304232)..... <b>B7577</b> Fuel (158172)..... <b>BF957 +</b> Coolant (w/4 Units BTA+)..... <b>BW5071</b> (3315116)..... Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b>
LTA9000 w/Cummins L10 Eng. Dual-Flow Lube (3318853)..... <b>BD103 +</b> F-F Lube (Fleetguard LF670SC).. <b>B196 +</b> B-P Lube (3304232)..... <b>B7577</b> Opt. Fuel/Water Separator (3308638)..... <b>BF1212 +</b> Fuel (154789)..... <b>BF957-D +</b> Coolant (w/4 Units BTA+)..... <b>BW5071</b> (3315116)..... Coolant (w/15 Units BTA+)..... <b>BW5075</b> (Fleetguard WF2075).....	LTA9000 w/Detroit Diesel Series 60 (11.1L) or (12.7L) Eng. (To 1992) F-F Lube (25010495)..... <b>[2] B95 +</b> B-P Lube (23530413)..... <b>B7577</b> Fuel/Water Separator (w/Drain) (23512317)..... <b>BF5813 +</b> Fuel/Water Separator (Open End for Bowl) (23512317)..... <b>BF5813-O +</b> Opt. Fuel/Water Separator (23516189)..... <b>BF5812</b> Opt. Fuel/Water Separator (Alliance ABPN122R50407)..... <b>BF1283-SP +</b> P. Fuel (25014274)..... <b>BF5800 +</b> S. Fuel (23518482)..... <b>BF5810</b>	LTL9000 w/Detroit Diesel 6V-92N, 8V-92 Series Engs. F-F Lube Ele..... <b>P20-HD +</b> B-P Lube Ele. (750 Size)..... <b>C750-E +</b> P. Fuel Spin-on..... <b>BF5800 +</b> S. Fuel Spin-on..... <b>BF5810</b> O. Air (Motorcraft AFA93)..... <b>PA2959-FN<sup>90</sup></b> I. Air (Motorcraft AFA94)..... <b>PA2960</b> Std. Air (16 1/2 In.) (D5HZ-9601-A)..... <b>PA2533</b> Conical Air (8 11/16 In. O.D.) (D8HZ-9601-A)..... <b>PA2500 +</b> Conical Air (10 13/32 In. O.D.) (D8HZ-9601-B)..... <b>PA3951</b> DynaCell Panel Air (D8HZ-9601-E)..... <b>PA2375 +</b>
LTA9000 w/Cummins M11 (10.8L) Eng. (To 12/1995) Dual-Flow Lube (3318853)..... <b>BD103 +</b>	LTA9000, LTL9000 w/Cummins N14 Eng. Dual-Flow Lube..... <b>BD103 +</b> Fuel/Water Separator..... <b>BF1212 +</b> Std. O. Air (Motorcraft AFA106)..... <b>PA2956-FN</b> Std. I. Air (Motorcraft AFA107)..... <b>PA2957</b> Radial Seal O. Air (Standard) (F1HZ-9601-B)..... <b>RS3518</b> Radial Seal XP O. Air (Upgrade) (F1HZ9601B)..... <b>RS3518XP</b>	LTL9000 w/Detroit Diesel 6V-92N, 8V-92 Series Engs. F-F Lube Ele..... <b>P20-HD +</b> B-P Lube Ele. (750 Size)..... <b>C750-E +</b> P. Fuel Spin-on..... <b>BF5800 +</b> S. Fuel Spin-on..... <b>BF5810</b> O. Air (Motorcraft AFA93)..... <b>PA2959-FN<sup>90</sup></b> I. Air (Motorcraft AFA94)..... <b>PA2960</b> Std. Air (16 1/2 In.) (D5HZ-9601-A)..... <b>PA2533</b> Conical Air (8 11/16 In. O.D.) (D8HZ-9601-A)..... <b>PA2500 +</b> Conical Air (10 13/32 In. O.D.) (D8HZ-9601-B)..... <b>PA3951</b> DynaCell Panel Air (D8HZ-9601-E)..... <b>PA2375 +</b>
LTA9000 w/Cummins M11 (10.8L) Eng. (To 12/1995) Dual-Flow Lube (3318853)..... <b>BD103 +</b>	LTL9000 w/Cummins L10 (10.0L) Eng. F-F Lube (Fleetguard LF670SC).. <b>B196 +</b> Dual-Flow Lube (3318853)..... <b>BD103 +</b> B-P Lube (3304232)..... <b>B7577</b> Fuel/Water Separator Spin-on (3315843)..... <b>BF1212 +</b> Fuel (154789)..... <b>BF957-D +</b>	

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)
LTL9000 w/Detroit Diesel 6V-92N, 8V-92 Series Eng. (Cont'd) Conical Air (12 3/4 In. O.D.) (E2HZ-9601-A)..... <b>PA2632</b>	LTLA9000 w/Cummins M11 (10.8L) Eng. (12/1995-on) Dual-Flow Lube (3318853)..... <b>BD103 +</b> Fuel/Water Separator Ele. (Fleetguard FS1029W)..... <b>PF7680</b> Fuel/Water Separator Spin-on (3329289)..... <b>BF1259</b> Coolant (w/4 Units BTA+) (3315116)..... <b>BW5071</b> Coolant (w/15 Units BTA+) (3318318)..... <b>BW5075</b>	LTLS9000 w/Cummins L10 (10.0L) Eng. (Cont'd) Coolant (w/8 Units BTA+) (3315115)..... <b>BW5073</b>
LTLA9000 w/Cat 3176 (10.3L) Eng. F-F Lube (Std. Efficiency) (1R0716)..... <b>B99 +</b> F-F Eng. Lube (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> Opt. B-P Lube (1W8845)..... <b>B7577</b> Fuel/Water Separator Ele. (8N0205)..... <b>PF316</b> Fuel/Water Separator Spin-on (Fleetguard FS1000)..... <b>BF1259</b> P. Fuel Ele. (9M2342)..... <b>[2] PF935</b> P. Fuel Spin-on (1R0740)..... <b>BF970 +</b> P. Fuel Spin-on (1R0749)..... <b>BF7587 +</b> S. Fuel Spin-on (1R0750)..... <b>BF7633 +</b> Coolant (w/8 Units BTE) (9N6123)..... <b>BW5139</b>	LTLA9000 w/Cummins N14 (14.0L) Eng. F-F Lube (Fleetguard LF670SC).. <b>B196 +</b> Dual-Flow Lube (3318853)..... <b>BD103 +</b> B-P Lube (3304232)..... <b>B7577</b> Fuel/Water Separator Spin-on (3329289)..... <b>BF1259</b> Fuel/Water Separator Spin-on (3406889)..... <b>BF1293-SPS</b> Fuel (154789)..... <b>BF957-D +</b> Coolant (3315116)..... <b>BW5071</b>	LTLS9000 w/Cummins M11 (10.8L) Eng. (12/1995-on) Dual-Flow Lube (3318853)..... <b>BD103 +</b> Fuel/Water Separator Ele. (Fleetguard FS1029W)..... <b>PF7680</b> Fuel/Water Separator Spin-on (3329289)..... <b>BF1259</b> Coolant (w/4 Units BTA+) (3315116)..... <b>BW5071</b> Coolant (w/15 Units BTA+) (3318318)..... <b>BW5075</b>
LTLA9000 w/Cat 3406 (14.6L) Eng. F-F Lube (Std. Efficiency) (1R0716)..... <b>B99 +</b> F-F Eng. Lube (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> Fuel/Water Separator Spin-on (Fleetguard FS1000)..... <b>BF1259</b> Fuel Spin-on (1R0749)..... <b>BF7587 +</b> Coolant (w/4 Units BTE) (9N3368)..... <b>BW5137</b> Coolant (w/8 Units BTE) (9N3366)..... <b>BW5139</b>	LTLA9000 w/Cummins L10 (10.0L) Eng. F-F Lube (Fleetguard LF670SC).. <b>B196 +</b> Dual-Flow Lube (3318853)..... <b>BD103 +</b> B-P Lube (3304232)..... <b>B7577</b> Fuel/Water Separator Spin-on (3315843)..... <b>BF1212 +</b> Fuel (154789)..... <b>BF957-D +</b> Coolant (w/4 Units BTA+) (3315116)..... <b>BW5071</b> Coolant (w/8 Units BTA+) (3315115)..... <b>BW5073</b>	LTLS9000 w/Cummins M11 (10.8L) Eng. (To 12/1995) Dual-Flow Lube (3318853)..... <b>BD103 +</b> Fuel/Water Separator Ele. (Fleetguard FS1029W)..... <b>PF7680</b> Fuel/Water Separator Spin-on (3308638)..... <b>BF1212 +</b> Coolant (w/4 Units BTA+) (3315116)..... <b>BW5071</b> Coolant (w/15 Units BTA+) (3318318)..... <b>BW5075</b>
LTLA9000 w/Cummins M11 (10.8L) Eng. (To 12/1995) Dual-Flow Lube (3318853)..... <b>BD103 +</b> Fuel/Water Separator Ele. (Fleetguard FS1029W)..... <b>PF7680</b> Fuel/Water Separator Spin-on (3308638)..... <b>BF1212 +</b> Coolant (w/4 Units BTA+) (3315116)..... <b>BW5071</b> Coolant (w/15 Units BTA+) (3318318)..... <b>BW5075</b>	LTLA9000 w/Cummins N14 (14.0L) Eng. F-F Lube (Fleetguard LF670SC).. <b>B196 +</b> Dual-Flow Lube (3318853)..... <b>BD103 +</b> B-P Lube (3304232)..... <b>B7577</b> Fuel/Water Separator Spin-on (Fleetguard FS1000)..... <b>BF1259</b> P. Fuel Ele. (9M2342)..... <b>[2] PF935</b> P. Fuel Spin-on (1R0740)..... <b>BF970 +</b> P. Fuel Spin-on (1R0749)..... <b>BF7587 +</b> S. Fuel Spin-on (1R0750)..... <b>BF7633 +</b> Coolant (w/8 Units BTE) (9N6123)..... <b>BW5139</b>	LTLS9000 w/Cummins N14 (14.0L) Eng. F-F Lube (Fleetguard LF670SC).. <b>B196 +</b> Dual-Flow Lube (3318853)..... <b>BD103 +</b> B-P Lube (3304232)..... <b>B7577</b> Fuel/Water Separator Spin-on (3329289)..... <b>BF1259</b> Fuel/Water Separator Spin-on (3406889)..... <b>BF1293-SPS</b> Fuel (154789)..... <b>BF957-D +</b> Coolant (3315116)..... <b>BW5071</b>
LTLA9000 w/Cummins M11 (10.8L) Eng. (To 12/1995) Dual-Flow Lube (3318853)..... <b>BD103 +</b> Fuel/Water Separator Ele. (Fleetguard FS1029W)..... <b>PF7680</b> Fuel/Water Separator Spin-on (3308638)..... <b>BF1212 +</b> Coolant (w/4 Units BTA+) (3315116)..... <b>BW5071</b> Coolant (w/15 Units BTA+) (3318318)..... <b>BW5075</b>	LTLA9000 w/Cat 3406 (14.6L) Eng. F-F Lube (Std. Efficiency) (1R0716)..... <b>B99 +</b> F-F Eng. Lube (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> Fuel/Water Separator Spin-on (Fleetguard FS1000)..... <b>BF1259</b> Fuel Spin-on (1R0749)..... <b>BF7587 +</b> Coolant (w/4 Units BTE) (9N3368)..... <b>BW5137</b> Coolant (w/8 Units BTE) (9N3366)..... <b>BW5139</b>	LTLA9000 w/Detroit Diesel Series 60 (11.1L) or (12.7L) Eng. (To 1992) F-F Lube (25010495)..... <b>[2] B95 +</b> B-P Lube (23530413)..... <b>B7577</b> Fuel/Water Separator (w/Drain) (23512317)..... <b>BF5813 +</b> Fuel/Water Separator (Open End for Bowl) (23512317)..... <b>BF5813-O +</b> Opt. Fuel/Water Separator (23516189)..... <b>BF5812</b> Opt. Fuel/Water Separator (Alliance ABPN122R50407)..... <b>BF1283-SP +</b> P. Fuel (25014274)..... <b>BF5800 +</b> S. Fuel (23518482)..... <b>BF5810</b>
LTLA9000 w/Cummins M11 (10.8L) Eng. (To 12/1995) Dual-Flow Lube (3318853)..... <b>BD103 +</b> Fuel/Water Separator Ele. (Fleetguard FS1029W)..... <b>PF7680</b> Fuel/Water Separator Spin-on (3308638)..... <b>BF1212 +</b> Coolant (w/4 Units BTA+) (3315116)..... <b>BW5071</b> Coolant (w/15 Units BTA+) (3318318)..... <b>BW5075</b>	LTLA9000 w/Cummins L10 (10.0L) Eng. F-F Lube (Fleetguard LF670SC).. <b>B196 +</b> Dual-Flow Lube (3318853)..... <b>BD103 +</b> B-P Lube (3304232)..... <b>B7577</b> Fuel/Water Separator Spin-on (3315843)..... <b>BF1212 +</b> Fuel (154789)..... <b>BF957-D +</b> Coolant (w/4 Units BTA+) (3315116)..... <b>BW5071</b>	LTLA9000 w/Detroit Diesel Series 60 (11.1L) or (12.7L) Eng. (1993-on) F-F Lube (23518480)..... <b>[2] B495</b> Fuel/Water Separator (w/Drain) (23512317)..... <b>BF5813 +</b> Fuel/Water Separator (Open End for Bowl) (23512317)..... <b>BF5813-O +</b>


\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)	FORD Trucks & Buses (cont'd)
LTS9000 w/Detroit Diesel Series 60 (11.1L) or (12.7L) Eng. (1993-on) (Cont'd) <b>Opt. Fuel/Water Separator</b> (23516189)..... <b>BF5812</b> <b>Opt. Fuel/Water Separator</b> (Alliance ABPN122R50407)..... <b>BF1283-SP +</b> <b>P. Fuel</b> (25014274)..... <b>BF5800 +</b> <b>S. Fuel</b> (23518482)..... <b>BF5810</b>	LTS9000 w/Cat 3306 (10.5L) Eng. (Cont'd) <b>F-F Lube Spin-on</b> (Severe Service) (1R0739)..... <b>B76-SS +</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Box-Style Glass Fuel/Water Separator</b> (6N7617)..... <b>BF912</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1000)..... <b>BF1259</b> <b>P. Fuel Ele.</b> (9M2341)..... <b>PF935</b> <b>P. Fuel Spin-on</b> (1R0740)..... <b>BF970 +</b> <b>S. Fuel Spin-on</b> (1R0750)..... <b>BF7633 +</b>	LTS9000 w/Detroit Diesel 6V-92N, 8V-92 Series Engs. <b>F-F Lube Ele.</b> ..... <b>P20-HD +</b> <b>B-P Lube Ele.</b> (750 Size)..... <b>C750-E +</b> <b>P. Fuel Spin-on</b> ..... <b>BF5800 +</b> <b>S. Fuel Spin-on</b> ..... <b>BF5810</b> <b>O. Air</b> (Motorcraft AFA93)..... <b>PA2959-FN<sup>90</sup></b> <b>I. Air</b> (Motorcraft AFA94)..... <b>PA2960</b> <b>Std. Air</b> (16 1/2 In.) (D5HZ-9601-A)..... <b>PA2533</b> <b>Conical Air</b> (8 11/16 In. O.D.) (D8HZ-9601-A)..... <b>PA2500 +</b> <b>Conical Air</b> (10 13/32 In. O.D.) (D8HZ-9601-B)..... <b>PA3951</b> <b>DynaCell Panel Air</b> (D8HZ-9601-E)..... <b>PA2375 +</b> <b>Conical Air</b> (12 3/4 In. O.D.) (E2HZ-9601-A)..... <b>PA2632</b>
LTS8000 w/Cat 3208 (10.4L) Eng. <b>Lube</b> (1R0713)..... <b>[2] BT230 +</b> <b>Lube</b> (1R0714)..... <b>[2] B75</b> <b>Lube</b> (9L9200)..... <b>[2] BT364</b> <b>Box-Style Fuel/Water Separator</b> (8N9803)..... <b>BF912</b> <b>P. Fuel Ele.</b> (9M2341)..... <b>PF935</b> <b>P. Fuel Spin-on</b> (1R0740)..... <b>BF970 +</b> <b>S. Fuel Spin-on</b> (1R0750)..... <b>BF7633 +</b> <b>Coolant</b> (w/o Chemicals) (4355142)..... <b>B5089 +</b> <b>Coolant</b> (w/4 Units BTE) (9N3717)..... <b>BW5137</b> <b>Coolant</b> (w/8 Units BTE) (9N3718)..... <b>BW5139</b>	LTS9000 w/Cummins M11 (10.8L) Eng. (To 12/1995) <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> (3308638)..... <b>BF1212 +</b> <b>Coolant</b> (w/4 Units BTA+) (3315116)..... <b>BW5071</b> <b>Coolant</b> (w/15 Units BTA+) (3318318)..... <b>BW5075</b>	Motorhomes w/V8-351 Eng. <b>Lube</b> (1977-on)..... <b>B2 +</b> <b>Fuel</b> (1977-on)..... <b>BF995</b> <b>Air</b> (1977-on)..... <b>PA2051</b>
LTS8000F w/Cummins 6CT8.3 (8.3L) Eng. <b>F-F Lube</b> (3313281)..... <b>B205 +</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Fuel/Water Separator</b> (3925274)..... <b>BF1280 +</b> <b>Fuel/Water Separator</b> (3286503)..... <b>BF1226</b> <b>Fuel</b> (3903640)..... <b>BF788</b> <b>Coolant</b> (w/6 Units BTA+) (3318201)..... <b>BW5072</b> <b>Coolant</b> (w/8 Units BTA+) (3315115)..... <b>BW5073</b>	LTS9000 w/Cummins M11 (10.8L) Eng. (12/1995-on) <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> (3329289)..... <b>BF1259</b> <b>Coolant</b> (w/4 Units BTA+) (3315116)..... <b>BW5071</b> <b>Coolant</b> (w/15 Units BTA+) (3318318)..... <b>BW5075</b>	Motorhomes w/V8-460 Eng. <b>Lube</b> (1978-on)..... <b>B2 +</b> <b>Air</b> (1978-on)..... <b>PA2002</b>
LTS9000 w/Cat 3176 (10.3L) Eng. <b>F-F Lube</b> (Std. Efficiency) (1R0716)..... <b>B99 +</b> <b>F-F Eng. Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> <b>Opt. B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1000)..... <b>BF1259</b> <b>P. Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>P. Fuel Spin-on</b> (1R0740)..... <b>BF970 +</b> <b>P. Fuel Spin-on</b> (1R0749)..... <b>BF7587 +</b> <b>S. Fuel Spin-on</b> (1R0750)..... <b>BF7633 +</b> <b>Coolant</b> (w/8 Units BTE) (9N6123)..... <b>BW5139</b>	LTS9000 w/Cummins M11 (10.8L) Eng. (12/1995-on) <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> (3329289)..... <b>BF1259</b> <b>Coolant</b> (w/4 Units BTA+) (3315116)..... <b>BW5071</b> <b>Coolant</b> (w/15 Units BTA+) (3318318)..... <b>BW5075</b>	P800 w/Cummins 6BT5.9 (5.9L) Eng. <b>Lube</b> (3914395)..... <b>BT339 +</b> <b>Fuel/Water Separator</b> (3903202)..... <b>BF1226</b> <b>Fuel/Water Separator</b> (3925274)..... <b>BF1280 +</b> <b>Fuel</b> (3903640)..... <b>BF788</b>
LTS9000 w/Cat 3306 (10.5L) Eng. <b>Lube Ele.</b> (w/Paper Wrapper) (1R0659)..... <b>PT670</b> <b>Lube Ele.</b> (w/Metal Wrapper) (1R0659)..... <b>PT7332</b> <b>F-F Lube Spin-on</b> (1R0716)..... <b>B99 +</b> <b>F-F Lube Spin-on</b> (Standard Vers.) (1R0739)..... <b>B76 +</b>	LTS9000 w/Cummins M11 (10.8L) Eng. (12/1995-on) <b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Opt. Fuel/Water Separator</b> (3308638)..... <b>BF1212 +</b> <b>Fuel</b> (154789)..... <b>BF957-D +</b> <b>Coolant</b> ..... <b>BW5071</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	P3500, P4000, P5000 w/4-220 Eng. <b>Lube</b> (1963-65)..... <b>P15</b> <b>Lube</b> (1966-on)..... <b>P190</b>
	LTS9000 w/Cummins N14 (14.0L) Eng. (To 12/1995) <b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Opt. Fuel/Water Separator</b> (3308638)..... <b>BF1212 +</b> <b>Fuel</b> (154789)..... <b>BF957-D +</b> <b>Coolant</b> ..... <b>BW5071</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	P3500, P4000, P5000 w/4-242 Eng. <b>Lube</b> (1969-on)..... <b>P15</b>
	LTS9000 w/Cummins N14 (14.0L) Eng. (12/1995-on) <b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Opt. Fuel/Water Separator</b> (3329289)..... <b>BF1259</b> <b>Fuel</b> (154789)..... <b>BF957-D +</b> <b>Coolant</b> ..... <b>BW5071</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	T5000 w/6 Cyl. Dorset Diesel Eng. <b>Lube</b> (1967)..... <b>PT12</b>
	LTS9000 w/Cat 3306 (10.5L) Eng. <b>Lube Ele.</b> (w/Paper Wrapper) (1R0659)..... <b>PT670</b> <b>Lube Ele.</b> (w/Metal Wrapper) (1R0659)..... <b>PT7332</b> <b>F-F Lube Spin-on</b> (1R0716)..... <b>B99 +</b> <b>F-F Lube Spin-on</b> (Standard Vers.) (1R0739)..... <b>B76 +</b>	W1000, WT1000 w/Cummins C160, CF160, C180 Eng. <b>F-F Lube Bag</b> ..... <b>P996</b> <b>F-F Lube Ele.</b> ..... <b>P999-HD</b> <b>B-P Lube Ele.</b> ..... <b>C750-E +</b> <b>Fuel/Water Separator</b> ..... <b>BF1212 +</b> <b>4 3/8 In. Fuel Spin-on</b> ..... <b>BF948 +</b> <b>5 3/4 In. Fuel Spin-on</b> ..... <b>BF957 +</b> <b>Breather</b> ..... <b>PA643</b> <b>Turbocharger</b> ..... <b>BT112</b>
	LTS9000 w/Cat 3306 (10.5L) Eng. <b>Lube Ele.</b> (w/Paper Wrapper) (1R0659)..... <b>PT670</b> <b>Lube Ele.</b> (w/Metal Wrapper) (1R0659)..... <b>PT7332</b> <b>F-F Lube Spin-on</b> (1R0716)..... <b>B99 +</b> <b>F-F Lube Spin-on</b> (Standard Vers.) (1R0739)..... <b>B76 +</b>	<b>FOTON Trucks</b> Aumark 3000 w/Cummins ISF3.8 Eng. <b>Lube</b> (5262313)..... <b>B40050</b> Aumark 4000 w/Cummins ISF3.8 Eng. <b>Lube</b> (5262313)..... <b>B40050</b>

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>FOTON Trucks (cont'd)</b>	<b>FREIGHTLINER Chassis (cont'd)</b>	<b>FREIGHTLINER Chassis (cont'd)</b>
Aumark 5000 w/Cummins ISF3.8 Eng. Lube (5262313)..... <b>B40050</b>	B2 Chassis w/Cat C7 Eng. (Cont'd) <b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b>	B2 Chassis w/Cummins B6.7 (6.7L) Eng. (2020) (Cont'd) <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
Aumark 6000 w/Cummins ISF3.8 Eng. Lube (5262313)..... <b>B40050</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
Aumark 7000 w/Cummins ISF3.8 Eng. Lube (5262313)..... <b>B40050</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	B2 Chassis w/Cummins B6.7 (6.7L) Eng. (2021) <b>Lube</b> (3937736)..... <b>B7177</b>
BJ1049 w/Cummins ISF2.8 Eng. Lube (Fleetguard LF17356)..... <b>B40051</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Fuel</b> (5303743)..... <b>BF63000</b>
ISF 2.8 MWB w/Cummins ISF 2.8 Eng. Lube (Fleetguard LF17356)..... <b>B40051</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Crankcase Breather</b> (4936636).. <b>Trans.</b> (Spin-on) (Allison 29539579)..... <b>BT8460</b>
<b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
ISF 2.8I SWB With Tray w/Cummins ISF 2.8 Eng. Lube (Fleetguard LF17356)..... <b>B40051</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
<b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
ISF 3.8 MWB w/Cummins ISF 2.8 Eng. Lube (Fleetguard LF17356)..... <b>B40051</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>	<b>Steering</b> (VMLT1808D)..... <b>BT9388</b>	B2 Chassis w/Cummins B6.7 (6.7L) Eng. (2022) <b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b>
OLN 3500 w/Perkins Phaser 110Ti 4.0L Eng. Mexico <b>Fuel</b> (15514352)..... <b>BF988 +</b>	B2 Chassis w/Cummins B6.7 (6.7L) Eng. (2018) <b>Lube</b> (3937736)..... <b>B7177</b>	B2 Chassis w/Cummins B6.7 (6.7L) Eng. (2023) <b>Lube</b> (3937736)..... <b>B7177</b>
OLN 4500 w/Perkins Phaser 135Ti 4.0L Eng. Mexico <b>Lube Spin-on</b> (T64101001)..... <b>BT216 +</b>	<b>Fuel/Water Separator</b> (Fleetguard FS20081)..... <b>PF46171</b>	B2 Chassis w/Cummins ISB (5.9L) Eng. <b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b>
<b>Fuel</b> (15514352)..... <b>BF988 +</b>	<b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b>	<b>Fuel/Water Separator</b> (w/Drain) (Racor R50419)..... <b>BF1347</b>
OLN 5500 w/Perkins Phaser 135Ti 4.0L Eng. Mexico <b>Lube Spin-on</b> (T64101001)..... <b>BT216 +</b>	<b>Fuel</b> (5660774)..... <b>BF63000</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R50419)..... <b>BF1347-O</b>
<b>Fuel</b> (15514352)..... <b>BF988 +</b>	<b>Channel Flow Primary Air</b> (Don. P607955)..... <b>CA4700</b>	<b>Fuel/Water Separator</b> (w/Sensor Port) (Racor R50419)..... <b>BF1373-SP</b>
<b>FREIGHTLINER Auxiliary Power Units (APU)</b>	<b>Channel Flow Secondary Air</b> (Don. P616400)..... <b>PA4701</b>	<b>Fuel</b> (Fleetguard FF5632)..... <b>BF7940</b>
RestSmart w/Thermo King 2.70M Eng. <b>Lube</b> (Thermo King 11-6182)..... <b>B161-S</b>	<b>Cab Air</b> (BOA91559)..... <b>PA4857</b>	<b>Channel Flow Air</b> (Std. Media) (Don. P607955)..... <b>CA4700 +</b>
<b>Fuel/Water Separator</b> (Thermo King 11-9342)..... <b>BF9894</b>	<b>Crankcase Breather</b> (4936636).. <b>CV15010</b>	<b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960) <b>CA5420 +</b>
<b>Radial Seal Air</b> (Thermo King 11-9059)..... <b>RS3715</b>	<b>Diesel Exhaust Fluid</b> (Fleetguard UF106)..... <b>PE17002 KIT</b>	<b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b>
<b>FREIGHTLINER Chassis</b>	B2 Chassis w/Cummins B6.7 (6.7L) Eng. (2019) <b>Lube</b> (3937736)..... <b>B7177</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>
B2 Chassis w/Cat C7 Eng. <b>Lube</b> (1R1807)..... <b>B7700 +</b>	<b>Fuel/Water Separator</b> (Fleetguard FS20081)..... <b>PF46171</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>
<b>Fuel/Water Separator</b> (w/Drain) (Alliance ABPS3226FL01)..... <b>BF1347</b>	<b>Fuel</b> (5660774)..... <b>BF63000</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (Alliance ABPS3226FL01)..... <b>BF1347-O</b>	<b>Crankcase Breather</b> (4936636).. <b>CV15010</b>	<b>Crankcase Breather</b> (Fleetguard CV52001)..... <b>CV15010</b>
<b>Fuel/Water Separator</b> (w/Sensor Port) (Alliance ABPS3226FL01).. <b>BF1373-SP</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R50418)..... <b>BF9898-O</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537966)..... <b>20016</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Fuel</b> (1R0751)..... <b>BF7632</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Channel Flow Air</b> (Std. Media) (Don. P607955)..... <b>CA4700 +</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960) <b>CA5420 +</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Steering</b> (VMLT1808D)..... <b>BT9388</b>
	B2 Chassis w/Cummins B6.7 (6.7L) Eng. (2020) <b>Lube</b> (3937736)..... <b>B7177</b>	
	<b>Fuel</b> (5303743)..... <b>BF63000</b>	
	<b>Crankcase Breather</b> (4936636).. <b>CV15010</b>	
	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	
	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	
	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>FREIGHTLINER Chassis (cont'd)</b>	<b>FREIGHTLINER Chassis (cont'd)</b>	<b>FREIGHTLINER Chassis (cont'd)</b>
B2 Chassis w/Cummins ISB 6.7 (6.7L) Eng. (2008-17) <b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b> <b>Fuel/Water Separator</b> (w/Drain) (Racor R50419)..... <b>BF1347</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R50419)..... <b>BF1347-O</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (Racor R50419)..... <b>BF1373-SP</b> <b>Fuel</b> (Fleetguard FF5632)..... <b>BF7940</b> <b>Channel Flow Air</b> (Std. Media) (Don. P607955)..... <b>CA4700 +</b> <b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960) <b>CA5420 +</b> <b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b> <b>Cab Air</b> (36000006)..... <b>PA5359</b> <b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Crankcase Breather</b> (Fleetguard CV52001)..... <b>CV15010</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Steering</b> (VMLT1808D)..... <b>BT9388</b>	B2 Chassis w/Cummins ISB6.7 (6.7L) Eng. (2020) (Cont'd) <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>B2 Chassis w/Detroit DD5 (5.1L) Eng. (2020)</b> <b>Lube</b> (A9341801410)..... <b>P40017</b> <b>Fuel</b> (A4700903151)..... <b>PF9908 KIT</b> <b>B2 Chassis w/Detroit DD5 (5.1L) Eng. (2021)</b> <b>Lube</b> (A9341800009)..... <b>P40017</b> <b>Pan-Type Trans.</b> (S. Pan, w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Pan-Type Trans.</b> (S. Pan, w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Pan-Type Trans.</b> (D. Pan, w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Pan-Type Trans.</b> (D. Pan, w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>B2 Chassis w/Detroit DD5 (5.1L) Eng. (2022)</b> <b>Lube</b> (A9341801410)..... <b>P40017</b> <b>B2 Chassis w/Mercedes Benz MBE904 Eng. 5 5/16 In. F-F Lube</b> (1801609)..... <b>P7199</b> <b>8 3/8 In. F-F Lube</b> (A0001801709)..... <b>P7188</b> <b>Opt. B-P Lube Spinner</b> (A9061810086)..... <b>BC7326 +</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R90P)..... <b>BF46083-O</b> <b>Fuel/Water Separator</b> (w/Bowl) (Racor R90P)..... <b>BF46072</b> <b>Fuel/Water Separator</b> (w/Drain) (Racor R90P)..... <b>BF1329</b> <b>Fuel/Water Separator</b> (Sensor Port Thd. 9/16-18) (Racor R90P)..... <b>BF1329-SP</b> <b>Fuel/Water Separator</b> (Sensor Port Thd. 1/2-20) (Racor R90P).... <b>BF1339-SP +</b> <b>Fuel</b> (A5410920805)..... <b>PF7761</b> <b>Channel Flow Air</b> (Std. Media) (Don. P607955)..... <b>CA4700 +</b> <b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960) <b>CA5420 +</b> <b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b> <b>Cab Air</b> (36000006)..... <b>PA5359</b> <b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (Fleetguard WF2077)..... <b>B5134 +</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	B2 Chassis w/Mercedes Benz MBE904 Eng. (Cont'd) <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Steering</b> (VMLT1808D)..... <b>BT9388</b> <b>B2 Chassis w/Mercedes-Benz MBE906 Eng. F-F Lube</b> (A0001801709)..... <b>P7188</b> <b>B-P Lube</b> (A9061810086)..... <b>BC7326 +</b> <b>Fuel</b> (4 1/16 In.) (A0000901551)... <b>PF7735</b> <b>Fuel</b> (7 31/32 In.) (A5410920805). <b>PF7761</b> <b>B2 Chassis w/Mercedes-Benz MBE926 Eng. Fuel/Water Separator</b> (Open End for Bowl) (Racor R50418)..... <b>BF9898-O</b> <b>Channel Flow Air</b> (Don. P607955)..... <b>CA4700 +</b> <b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Steering</b> (T1808D)..... <b>BT9388</b> <b>B2 Chassis w/Mercedes-Benz OM906 Eng. Lube</b> (A0001801609)..... <b>P7199</b> <b>Fuel</b> (A9060920305)..... <b>PF7735</b> <b>C2 w/Cat C7 Eng. Lube</b> (To 1/2004 (Std. Version)) (1R0739)..... <b>B76</b> <b>Lube</b> (1/2004-on) (1R1807)..... <b>B7700 +</b> <b>Fuel/Water Separator</b> (w/o SP) (Alliance ABP-S3226FL02)..... <b>BF1346 +</b> <b>Fuel/Water Separator</b> (w/SP) (Alliance ABP-S3226FL02)..... <b>BF1346-SP +</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R50418)..... <b>BF9898-O</b> <b>Fuel</b> (High Efficiency) (1R0751).... <b>BF7632</b> <b>Air</b> (End Inlet) (Farr 114500-003).. <b>PA3556</b> <b>Air</b> (Side Inlet) (Farr 114880-003). <b>PA3493</b> <b>Channel Flow Air</b> (Don. P607955)..... <b>CA4700</b> <b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960) <b>CA5420</b> <b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b> <b>Cab Air</b> (Main AirCond. Unit) (VCC36000006)..... <b>PA5359</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Chassis (cont'd)	FREIGHTLINER Chassis (cont'd)	FREIGHTLINER Chassis (cont'd)
C2 w/Cat C7 Eng. (Cont'd)	C2 w/Cummins ISB Eng. (Cont'd)	FB 65 w/Cat C7 (7.2L) Eng. (1/2004-on)
<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b>	<b>Lube</b> (1R1807)..... <b>B7700+</b>
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>Opt. Lube</b> (1R1808)..... <b>B7299+</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Steering</b> (VMLT1808D)..... <b>BT9388</b>	<b>Suction Line Fuel/Water Separator</b> (256-8753)..... <b>BF1259</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	C2 w/Mercedes-Benz MBE900 Eng.	<b>Fuel/Water Separator</b> (175-2949)..... <b>BF1268</b>
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>F-F Lube Ele.</b> (A0001801709)..... <b>P7188</b>	<b>Fuel</b> (1R0751)..... <b>BF7632</b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Opt. B-P Lube Spinner</b> (A9061810086)..... <b>BC7326+</b>	FB 65 w/Cat 3126 (7.2L) Eng. (To 1/2004)
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Fuel/Water Separator Ele.</b> (Davco 382114)..... <b>PF7748</b>	<b>Lube</b> (Standard Vers.) (1R0739).. <b>B76</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Racor R50418)..... <b>BF9898-O</b>	<b>Suction Line Fuel/Water Separator</b> (175-2949)..... <b>BF1268</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Fuel</b> (4 1/16 In.) (A0000901551)... <b>PF7735</b>	<b>Fuel/Water Separator</b> (256-8753)..... <b>BF1259</b>
<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>Fuel</b> (7 31/32 In.) (5410900151)... <b>PF7761</b>	<b>Fuel</b> (1R0751)..... <b>BF7632</b>
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b>	<b>Channel Flow Air</b> (Don. P607955)..... <b>CA4700</b>	FB 65 w/Cat 3126 (7.2L) Eng. (1/2004-on)
<b>Steering</b> (VMLT1808D)..... <b>BT9388</b>	<b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960) <b>CA5420</b>	<b>Lube</b> (1R1807)..... <b>B7700+</b>
C2 w/Cummins ISB Eng.	<b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b>	<b>Suction Line Fuel/Water Separator</b> (175-2949)..... <b>BF1268</b>
<b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b>	<b>Cab Air</b> (Main AirCond. Unit) (VCC36000006)..... <b>PA5359</b>	<b>Fuel/Water Separator</b> (256-8753)..... <b>BF1259</b>
<b>Fuel/Water Separator</b> (w/Drain) (Racor S3226T)..... <b>BF1347</b>	<b>Air Dryer</b> (AD-SP System) (Bendix 65624)..... <b>BA5373</b>	<b>Fuel</b> (1R0751)..... <b>BF7632</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor S3226T)..... <b>BF1347-O</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	FB 65 w/Cummins 6B Series Eng.
<b>Fuel/Water Separator</b> (w/Sensor Port) (Racor S3226T)..... <b>BF1373-SP</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Lube</b> (Chrysler 5083285AA)..... <b>BT7349</b>
<b>Channel Flow Air</b> (Don. P607955)..... <b>CA4700</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Fuel/Water Separator</b> (3925274). <b>BF1280+</b>
<b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960) <b>CA5420</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>S. Fuel</b> (3903640)..... <b>BF788</b>
<b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	FB 65 w/Cummins ISB Eng.
<b>Cab Air</b> (Main AirCond. Unit) (VCC36000006)..... <b>PA5359</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Lube</b> (1 1/8-16 Thd.) (Fleetguard LF3970)..... <b>B7177</b>
<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Lube</b> (M27 x 2.0 Thd.) (4897898). <b>BT7237</b>
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>P. Fuel</b> (Fleetguard FF5632)..... <b>BF7940</b>
<b>Crankcase Breather</b> (2007-on) (Fleetguard CV52001)..... <b>CV15010</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	FB 65 w/Mercedes-Benz MBE904 Eng.
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b>	<b>F-F Lube</b> (5 15/16 In.) (1801609). <b>P7199</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Steering</b> (VMLT1808D)..... <b>BT9388</b>	<b>F-F Lube</b> (8 3/8 In.) (A0001801709)..... <b>P7188</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	FB 65 w/Cat C7 (7.2L) Eng. (To 1/2004)	<b>Opt. B-P Lube</b> (A9061810086).... <b>BC7326+</b>
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Lube</b> (Standard Vers.) (1R0739).. <b>B76+</b>	<b>P. Fuel</b> (4 1/16 In.) (A0000901551)..... <b>PF7735</b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Opt. Lube</b> (1R1808)..... <b>B7299+</b>	<b>P. Fuel</b> (7 31/32 In.) (A5410920805)..... <b>PF7761</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Lube</b> (Severe Service) (1R0739).. <b>B76-SS+</b>	FB 65 w/Mercedes-Benz MBE906 Eng.
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Suction Line Fuel/Water Separator</b> (256-8753)..... <b>BF1259</b>	<b>F-F Lube</b> (A0001801709)..... <b>P7188</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Fuel/Water Separator</b> (175-2949)..... <b>BF1268</b>	<b>Opt. B-P Lube</b> (A9061810086).... <b>BC7326+</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Fuel</b> (1R0751)..... <b>BF7632</b>	<b>P. Fuel</b> (4 1/16 In.) (A0000901551)..... <b>PF7735</b>
		<b>P. Fuel</b> (7 31/32 In.) (A5410920805)..... <b>PF7761</b>
		FRED w/Cummins 5.9L Eng.
		<b>Lube</b> (Fleetguard LF3349)..... <b>BT339+</b>
		<b>Fuel</b> (Fleetguard FF5052)..... <b>BF788</b>
		<b>Air</b> (End Inlet) (Farr 114500-003).. <b>PA3556</b>
		<b>Air</b> (Side Inlet) (Farr 114880-003). <b>PA3493</b>
		<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
		<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
		<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Chassis (cont'd)	FREIGHTLINER Chassis (cont'd)	FREIGHTLINER Chassis (cont'd)
FRED w/Cummins 5.9L Eng. (Cont'd) <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	MB-55 Series w/Cummins ISB Eng. <b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b> <b>Lube</b> (4897898)..... <b>BT7237</b> <b>Lube</b> (Fleetguard LF3729)..... <b>BT595</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19579)..... <b>PF7777</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS19519)..... <b>BF1271</b> <b>Fuel/Water Separator Spin-on</b> (Remote Mtd.) (Fleetguard FS19596)..... <b>BF1293-SPS</b> <b>Fuel</b> (Racor RAI-025RAC10)..... <b>BF46006</b> <b>Air</b> (End Inlet) (Farr 114500-003)..... <b>PA3556</b> <b>Air</b> (Side Inlet) (Farr 114880-003)..... <b>PA3493</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	MC Line w/Cummins B6.7 (6.7L) Eng. (2018) (Cont'd) <b>Crankcase Breather</b> (4936636).... <b>CV15010</b> MC Line w/Cummins B6.7 (6.7L) Eng. (2019) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636).... <b>CV15010</b> MC Line w/Cummins B6.7 (6.7L) Eng. (2020) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636).... <b>CV15010</b> MC Line w/Cummins B6.7 (6.7L) Eng. (2021) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636).... <b>CV15010</b> MC Line w/Cummins B6.7 (6.7L) Eng. (2022) <b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b> MC Line w/Cummins ISB Eng. <b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b> <b>Lube</b> (4897898)..... <b>BT7237</b> <b>Fuel</b> (Fleetguard FF5632)..... <b>BF7940</b> MC Line w/Cummins N14 Eng. <b>F-F Lube</b> (9 15/16 In.) (Fleetguard LF670SC)..... <b>B196 +</b> <b>F-F Lube</b> (11 9/32 In.) (Fleetguard LF670SC)..... <b>B96 +</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Fuel/Water Separator</b> (3308638)..... <b>BF1212 +</b> <b>Fuel</b> (154789)..... <b>BF957-D +</b>
MB Line w/Cat 3126B Eng. <b>Lube</b> (To 1/2004 (Std. Version)) (1R0739)..... <b>B76</b> <b>Lube</b> (1/2004-on) (1R1807)..... <b>BT700 +</b> <b>Fuel/Water Separator</b> (175-2949)..... <b>BF1268</b> <b>Fuel/Water Separator</b> (256-8753)..... <b>BF1259</b> <b>Fuel</b> (1R0751)..... <b>BF7632</b>	MB60 w/Mercedes-Benz OM366LA Eng. <b>Lube</b> (Mann HU9471/n)..... <b>P7305</b> <b>Fuel</b> (Mann BFU700x)..... <b>F834-F</b> <b>Radial Seal O. Air</b> (Don. P526678)..... <b>RS3520</b> <b>Radial Seal I. Air</b> (Don. P529548)..... <b>RS3521</b>	RIV w/Cummins ISM Eng. <b>Dual-Flow Lube</b> (11 13/16 In.) (Fleetguard LF9001)..... <b>BD7154 +</b> <b>Dual-Flow Lube</b> (14 7/32 In.) (Fleetguard LF9000)..... <b>BD7153 +</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> (3406889)..... <b>BF1293-SPS</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1000)..... <b>BF1259</b>
MB Line w/Cummins 4B Series Eng. <b>Lube</b> (3903224)..... <b>BT427 +</b> <b>Fuel/Water Separator</b> (3903202)..... <b>BF1226</b> <b>Fuel</b> (3903640)..... <b>BF788</b>	MB70 w/Cat 3126B Eng. <b>Lube</b> (To 1/2004 (Std. Version)) (1R0739)..... <b>B76</b> <b>Lube</b> (1/2004-on) (1R1807)..... <b>BT700 +</b> <b>Suction Line Fuel/Water Separator</b> (175-2949)..... <b>BF1268</b> <b>Fuel/Water Separator</b> (256-8753)..... <b>BF1259</b> <b>Fuel</b> (1R0751)..... <b>BF7632</b> <b>Radial Seal O. Air</b> (Don. P526678)..... <b>RS3520</b> <b>Radial Seal I. Air</b> (Don. P529548)..... <b>RS3521</b>	RIV w/Detroit Diesel Series 60 Eng. <b>F-F Lube</b> (23530573)..... <b>[2] B495</b> <b>F-F Lube</b> (Upgrade) (Don. DELF3998)..... <b>[2] B495-SS</b> <b>Fuel/Water Separator</b> (w/Drain) (23535985)..... <b>BF5813 +</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (23535985)..... <b>BF5813-O +</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (To 12/03) (23530707).... <b>BF5810</b> <b>S. Fuel</b> (12/03-on) (23533726).... <b>BF5816</b>
MB Line w/Cummins 6B Series Eng. <b>Lube</b> (To 1998) (3914395)..... <b>BT339 +</b> <b>Lube</b> (1998-on) (Chrysler 5083285AA)..... <b>BT7349</b> <b>Fuel/Water Separator</b> (3925274)..... <b>BF1280 +</b> <b>S. Fuel</b> (3903640)..... <b>BF788</b>	MB70 w/Mercedes-Benz OM366LA Eng. <b>Lube</b> (Mann HU9471/n)..... <b>P7305</b> <b>Fuel</b> (Mann BFU700x)..... <b>F834-F</b> <b>Radial Seal O. Air</b> (Don. P526678)..... <b>RS3520</b> <b>Radial Seal I. Air</b> (Don. P529548)..... <b>RS3521</b>	MC Line w/Cummins B6.7 (6.7L) Eng. (2018) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636).... <b>CV15010</b>
MB Line w/Cummins 6C Series Eng. <b>F-F Lube</b> (3313281)..... <b>B205 +</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Fuel/Water Separator</b> (3925274)..... <b>BF1280 +</b> <b>S. Fuel</b> (3903640)..... <b>BF788</b>	MC Line w/Cummins B6.7 (6.7L) Eng. (2018) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636).... <b>CV15010</b>	MC Line w/Cummins B6.7 (6.7L) Eng. (2019) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636).... <b>CV15010</b>
MB Line w/Cummins B5.9 Natural Gas Eng. <b>Lube</b> (3937743)..... <b>BT7349</b>	MC Line w/Cummins B6.7 (6.7L) Eng. (2020) <b>Lube</b> (Researching)..... <b>B7177</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636).... <b>CV15010</b>	MC Line w/Cummins B6.7 (6.7L) Eng. (2022) <b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b>
MB Line w/Cummins B6.7 (6.7L) Eng. (2018) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636).... <b>CV15010</b>	MC Line w/Cummins B6.7 (6.7L) Eng. (2018) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> <b>Primary Channel Flow Air</b> (Don. P607955)..... <b>CA4700</b> <b>Secondary Channel Flow Air</b> (Don. P616400)..... <b>PA4701</b> <b>Cab Air</b> (BOA91559)..... <b>PA4857</b>	MC Line w/Cummins B6.7 (6.7L) Eng. (2018) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b>
MB Line w/Cummins B6.7 (6.7L) Eng. (2020) <b>Lube</b> (Researching)..... <b>B7177</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636).... <b>CV15010</b>	MC Line w/Cummins B6.7 (6.7L) Eng. (2018) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> <b>Primary Channel Flow Air</b> (Don. P607955)..... <b>CA4700</b> <b>Secondary Channel Flow Air</b> (Don. P616400)..... <b>PA4701</b> <b>Cab Air</b> (BOA91559)..... <b>PA4857</b>	MC Line w/Cummins B6.7 (6.7L) Eng. (2018) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b>
MB Line w/Cummins B6.7 (6.7L) Eng. (2020) <b>Lube</b> (Researching)..... <b>B7177</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636).... <b>CV15010</b>	MC Line w/Cummins B6.7 (6.7L) Eng. (2018) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> <b>Primary Channel Flow Air</b> (Don. P607955)..... <b>CA4700</b> <b>Secondary Channel Flow Air</b> (Don. P616400)..... <b>PA4701</b> <b>Cab Air</b> (BOA91559)..... <b>PA4857</b>	MC Line w/Cummins B6.7 (6.7L) Eng. (2018) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b>
MB Line w/Cummins B6.7 (6.7L) Eng. (2022) <b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b>	MC Line w/Cummins B6.7 (6.7L) Eng. (2018) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> <b>Primary Channel Flow Air</b> (Don. P607955)..... <b>CA4700</b> <b>Secondary Channel Flow Air</b> (Don. P616400)..... <b>PA4701</b> <b>Cab Air</b> (BOA91559)..... <b>PA4857</b>	MC Line w/Cummins B6.7 (6.7L) Eng. (2018) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b>
MB Line w/Cummins ISB Eng. <b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b> <b>Lube</b> (4897898)..... <b>BT7237</b> <b>Fuel</b> (Fleetguard FF5632)..... <b>BF7940</b>	MC Line w/Cummins B6.7 (6.7L) Eng. (2018) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> <b>Primary Channel Flow Air</b> (Don. P607955)..... <b>CA4700</b> <b>Secondary Channel Flow Air</b> (Don. P616400)..... <b>PA4701</b> <b>Cab Air</b> (BOA91559)..... <b>PA4857</b>	MC Line w/Cummins B6.7 (6.7L) Eng. (2018) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b>
MB Line w/Mercedes-Benz MBE904 Eng. <b>F-F Lube</b> (5 15/16 In.) (1801609)..... <b>P7199</b> <b>F-F Lube</b> (8 3/8 In.) (A0001801709)..... <b>P7188</b> <b>Opt. B-P Lube</b> (A9061810086).... <b>BC7326 +</b> <b>Fuel</b> (4 1/16 In.) (A0000901551).... <b>PF7735</b> <b>Fuel</b> (7 31/32 In.) (A5410920805).... <b>PF7761</b>	MC Line w/Cummins B6.7 (6.7L) Eng. (2018) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> <b>Primary Channel Flow Air</b> (Don. P607955)..... <b>CA4700</b> <b>Secondary Channel Flow Air</b> (Don. P616400)..... <b>PA4701</b> <b>Cab Air</b> (BOA91559)..... <b>PA4857</b>	MC Line w/Cummins B6.7 (6.7L) Eng. (2018) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



FREIGHTLINER Chassis (cont'd)	FREIGHTLINER Chassis (cont'd)	FREIGHTLINER Chassis (cont'd)
S2 Bus Chassis w/Cummins ISB Eng. <b>Lube</b> (Fleetguard LF3972)..... <b>BT7349</b> <b>Fuel</b> (Fleetguard FF5421)..... <b>BF7966</b>	S2RV w/Cummins B6.7 (6.7L) Eng. (2019) (Cont'd) <b>Crankcase Breather</b> (4936636).. <b>CV15010</b>	XB Line w/Cat C10 Eng. <b>F-F Lube</b> (1R0716)..... <b>B99 +</b> <b>F-F Lube</b> (High Efficiency) (1R1808)..... <b>B7299 +</b> <b>B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Fuel Ele.</b> (9M2342)..... <b>PF935</b> <b>Fuel Spin-on</b> (1R1712)..... <b>BF614 +</b> <b>Fuel Spin-on</b> (High Efficiency) (1R0749)..... <b>BF7587 +</b>
S2 Bus Chassis w/Mercedes-Benz OM906 Eng. <b>Lube</b> (A0001801609)..... <b>P7199</b> <b>Fuel</b> (A9060920305)..... <b>PF7735</b>	S2RV w/Cummins B6.7 (6.7L) Eng. (2020) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	XB Line w/Cat 3126 (7.2L) Eng. (To 1/2004) <b>Lube</b> (Standard Vers.) (1R0739).. <b>B76</b> <b>Fuel/Water Separator</b> (175-2949)..... <b>BF1268</b> <b>Fuel/Water Separator</b> (256-8753)..... <b>BF1259</b> <b>P. Fuel</b> (1R0751)..... <b>BF7632</b>
S2C w/Cummins B6.7 (6.7L) Eng. (2018) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> <b>Cab Air</b> (BOA91559)..... <b>PA4857</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	S2RV w/Cummins B6.7 (6.7L) Eng. (2021) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	XB Line w/Cat 3126 (7.2L) Eng. (1/2004-on) <b>Lube</b> (1R1807)..... <b>B7700 +</b> <b>Fuel/Water Separator</b> (175-2949)..... <b>BF1268</b> <b>Fuel/Water Separator</b> (256-8753)..... <b>BF1259</b> <b>P. Fuel</b> (1R0751)..... <b>BF7632</b>
S2C w/Cummins B6.7 (6.7L) Eng. (2019) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Cab Air</b> (BOA91559)..... <b>PA4857</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	S2RV w/Cummins B6.7 (6.7L) Eng. (2022) <b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b> <b>Sport Chassis w/Detroit DD13 (12.8L) Eng.</b> (2018) <b>Lube</b> (A4731800109)..... <b>P7505</b> <b>Fuel</b> (A4720900651)..... <b>PF9908 KIT</b> <b>Sport Chassis w/Detroit DD13 (12.8L) Eng.</b> (2020) <b>Lube</b> (To Eng. S/N 472910S0690710) (A4731800409)..... <b>P7505</b> <b>Fuel</b> (A4700903151)..... <b>PF9908 KIT</b> <b>Sport Chassis w/Detroit DD13 (12.8L) Eng.</b> (2021) <b>Fuel</b> (A4700903151)..... <b>PF9908 KIT</b> <b>Sport Chassis w/Detroit DD13 (12.8L) Eng.</b> (2022) <b>Fuel</b> (A4700903151)..... <b>PF9908 KIT</b>	XB Line w/Cummins 6BT5.9 (5.9L) Eng. (To 1998) <b>Lube</b> (3914395)..... <b>BT339 +</b> <b>Fuel/Water Separator</b> (3925274). <b>BF1280 +</b> <b>S. Fuel</b> (3903640)..... <b>BF788</b>
S2C w/Cummins B6.7 (6.7L) Eng. (2020) (3937736)..... <b>B7177</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	<b>Sport Chassis w/Detroit DD13 (12.8L) Eng.</b> (2022) <b>Fuel</b> (A4700903151)..... <b>PF9908 KIT</b>	XB Line w/Cummins 6BT5.9 (5.9L) Eng. (1998-on) <b>Lube</b> (Chrysler 5083285AA)..... <b>BT7349</b> <b>Fuel/Water Separator</b> (3925274). <b>BF1280 +</b> <b>S. Fuel</b> (3903640)..... <b>BF788</b>
S2C w/Cummins B6.7 (6.7L) Eng. (2021) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	<b>V Line w/Cat 3126B Eng.</b> <b>Lube</b> (To 1/2004 (Std. Version)) (1R0739)..... <b>B76</b> <b>Lube</b> (1/2004-on) (1R1807)..... <b>B7700 +</b> <b>Fuel/Water Separator</b> (175-2949)..... <b>BF1268</b> <b>Fuel/Water Separator</b> (256-8753)..... <b>BF1259</b> <b>Fuel</b> (1R0751)..... <b>BF7632</b>	XB Line w/Cummins 6CT8.3 Eng. <b>F-F Lube</b> (3313281)..... <b>B205 +</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Fuel/Water Separator</b> (3925274). <b>BF1280 +</b> <b>S. Fuel</b> (3903640)..... <b>BF788</b>
S2C w/Cummins B6.7 (6.7L) Eng. (2022) <b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b>	<b>V Line w/Cummins 6B Series Eng.</b> <b>Lube</b> (To 1998) (3914395)..... <b>BT339 +</b> <b>Lube</b> (1998-on) (Chrysler 5083285AA)..... <b>BT7349</b> <b>Fuel/Water Separator</b> (3925274). <b>BF1280 +</b> <b>S. Fuel</b> (3903640)..... <b>BF788</b>	XB Line w/Cummins L10 Eng. <b>F-F Lube</b> (9 15/16 In.) (Fleetguard LF670SC)..... <b>B196 +</b> <b>F-F Lube</b> (11 9/32 In.) (Fleetguard LF670SC)..... <b>B96 +</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Fuel</b> (154789)..... <b>BF957-D +</b>
S2RV w/Cummins B6.7 (6.7L) Eng. (2018) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	<b>V Line w/Cummins 6C Series Eng.</b> <b>F-F Lube</b> (3313281)..... <b>B205 +</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Fuel/Water Separator</b> (3925274). <b>BF1280 +</b> <b>S. Fuel</b> (3903640)..... <b>BF788</b>	XB Line w/Cummins B6.7 (6.7L) Eng. (2018) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b>
S2RV w/Cummins B6.7 (6.7L) Eng. (2019) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Cab Air</b> (BOA91559)..... <b>PA4857</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>V Line w/Cummins M11 Eng.</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> (3329289)..... <b>BF1259</b>	XB Line w/Cummins B6.7 (6.7L) Eng. (2020) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>FREIGHTLINER Chassis (cont'd)</b>	<b>FREIGHTLINER Chassis (cont'd)</b>	<b>FREIGHTLINER Chassis (cont'd)</b>
<b>XB-Series w/Cat C7 (7.2L) Eng. (To 1/2004)</b> <b>Lube</b> (Standard Vers.) (1R0739).. <b>B76 +</b> <b>Lube</b> (Severe Service) (1R0739).. <b>B76-SS +</b> <b>Fuel/Water Separator</b> (w/o SP) (Alliance ABP-S3226FL02)..... <b>BF1346 +</b> <b>Fuel/Water Separator</b> (w/SP) (Alliance ABP-S3226FL02)..... <b>BF1346-SP +</b> <b>Fuel</b> (1R0751)..... <b>BF7632</b> <b>Air</b> (End Inlet) (Farr 114500-003).. <b>PA3556</b> <b>Air</b> (Side Inlet) (Farr 114880-003).. <b>PA3493</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>XB-Series w/Cummins ISB 6.7 (6.7L) Eng.                      (Cont'd)</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Steering</b> (Nelson 87972A)..... <b>PT9386-MPG</b> <b>XB-Series w/Cummins ISB (5.9L) Eng.</b> <b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b> <b>Lube</b> (4897898)..... <b>BT7237</b> <b>Lube</b> (Fleetguard LF3729)..... <b>BT595</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19579)..... <b>PF7777</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS19519)..... <b>BF1271</b> <b>Fuel/Water Separator Spin-on</b> (Remote Mtd.) (Fleetguard FS19596)..... <b>BF1293-SPS</b> <b>Fuel</b> (Racor RAI-025RAC10)..... <b>BF46006</b> <b>Air</b> (End Inlet) (Farr 114500-003).. <b>PA3556</b> <b>Air</b> (Side Inlet) (Farr 114880-003).. <b>PA3493</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Steering</b> (Nelson 87972A)..... <b>PT9386-MPG</b> <b>XB Straight Rail w/Cummins B6.7 (6.7L) Eng.                      (2018)</b> <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b> <b>XB Straight Rail w/Cummins B6.7 (6.7L) Eng.                      (2019)</b> <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b> <b>XB Straight Rail w/Cummins B6.7 (6.7L) Eng.                      (2020)</b> <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b> <b>XB Straight Rail w/Cummins B6.7 (6.7L) Eng.                      (2021)</b> <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	<b>XB Straight Rail w/Cummins B6.7 (6.7L) Eng.                      (2022)</b> <b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b> <b>XB Straight Rail w/Cummins ISB 6.7 (6.7L) Eng.                      (2018)</b> <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>XB Straight Rail w/Cummins L9 (9.0L) Eng.                      (2018)</b> <b>Lube</b> (3401544)..... <b>B40142</b> <b>Fuel</b> (Fleetguard FF63008)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b> <b>XB Straight Rail w/Cummins L9 (9.0L) Eng.                      (2020)</b> <b>Lube</b> (5444774)..... <b>B40142</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>XB Straight Rail w/Cummins L9 (9.0L) Eng.                      (2022)</b> <b>Lube</b> (5520789)..... <b>B40142</b> <b>XC Lowered Rail w/Cummins L9 (9.0L) Eng.                      (2018)</b> <b>Lube</b> (3401544)..... <b>B40142</b> <b>Fuel</b> (Fleetguard FF63008)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b> <b>XC Modular Rail w/Cummins B6.7 (6.7L) Eng.                      (2018)</b> <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b> <b>XC Modular Rail w/Cummins B6.7 (6.7L) Eng.                      (2019)</b> <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b> <b>XC Modular Rail w/Cummins B6.7 (6.7L) Eng.                      (2020)</b> <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b>

+ See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Chassis (cont'd)	FREIGHTLINER Chassis (cont'd)	FREIGHTLINER Chassis (cont'd)
XC Modular Rail w/Cummins B6.7 (6.7L) Eng. (2021) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	XC Modular Rail w/Cummins X15 (14.9L) Eng. (2018) (Cont'd) <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	XC Raised Rail w/Cummins ISB 6.7 (6.7L) Eng. (2018) (Cont'd) <b>Crankcase Breather</b> (4936636)... <b>CV15010</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
XC Modular Rail w/Cummins B6.7 (6.7L) Eng. (2022) <b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b>	XC Modular Rail w/Cummins X15 (14.9L) Eng. (2020) <b>Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel</b> (5365988)..... <b>BF46129</b>	XC Raised Rail w/Cummins ISL 8.9 (8.9L) Eng. (2018) <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
XC Modular Rail w/Cummins L9 (9.0L) Eng. (2018) <b>Lube</b> (3401544)..... <b>B40142</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	XC Raised Rail w/Cummins B6.7 (6.7L) Eng. (2018) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	XC Raised Rail w/Cummins ISX 15.0 (14.9L) Eng. (2018) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel</b> (Fleetguard FF5825NN)..... <b>BF46129 +</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
XC Modular Rail w/Cummins L9 (9.0L) Eng. (2019) <b>Lube</b> (3401544)..... <b>B40142</b> <b>Fuel</b> (5303743)..... <b>BF63000</b>	XC Raised Rail w/Cummins B6.7 (6.7L) Eng. (2019) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	XC Raised Rail w/Cummins ISX 15.0 (14.9L) Eng. (2019) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b>
XC Modular Rail w/Cummins L9 (9.0L) Eng. (2020) <b>Lube</b> (5444774)..... <b>B40142</b> <b>Fuel</b> (5303743)..... <b>BF63000</b>	XC Raised Rail w/Cummins B6.7 (6.7L) Eng. (2020) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	XC Raised Rail w/Cummins ISB 6.7 (6.7L) Eng. (2018) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b>
XC Modular Rail w/Cummins L9 (9.0L) Eng. (2021) <b>Lube</b> (5444774)..... <b>B40142</b> <b>Fuel</b> (5303743)..... <b>BF63000</b>	XC Raised Rail w/Cummins B6.7 (6.7L) Eng. (2021) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	XC Raised Rail w/Cummins ISX 15.0 (14.9L) Eng. (2019) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel</b> (5365988)..... <b>BF46129 +</b>
XC Modular Rail w/Cummins L9 (9.0L) Eng. (2022) <b>Lube</b> (5520789)..... <b>B40142</b>	XC Raised Rail w/Cummins B6.7 (6.7L) Eng. (2021) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	XC Raised Rail w/Cummins ISX 15.0 (14.9L) Eng. (2019) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel</b> (5365988)..... <b>BF46129 +</b>
XC Modular Rail w/Cummins X15 (14.9L) Eng. (2018) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel</b> (Fleetguard FF5825NN)..... <b>BF46129 +</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	XC Raised Rail w/Cummins B6.7 (6.7L) Eng. (2021) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	XC Raised Rail w/Cummins ISX 15.0 (14.9L) Eng. (2019) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel</b> (5365988)..... <b>BF46129 +</b>


+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Chassis (cont'd)	FREIGHTLINER Chassis (cont'd)	FREIGHTLINER Chassis (cont'd)
XC Raised Rail w/Cummins L9 (9.0L) Eng. (2018) Lube (3401544)..... <b>B40142</b> Fuel (Fleetguard FF63009)..... <b>BF63000</b> Crankcase Breather (4936636)... <b>CV15010</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	XC Raised Rail w/Cummins X15 (14.9L) Eng. (2019) Dual-Flow Lube (4367100)..... <b>BD50000</b> Fuel (5365988)..... <b>BF46129 +</b> XC Raised Rail w/Cummins X15 (14.9L) Eng. (2020) Dual-Flow Lube (4367100)..... <b>BD50000</b> Fuel (5365988)..... <b>BF46129</b> XC Raised Rail w/Cummins X15 (14.9L) Eng. (2021) Lube (5575298)..... <b>B40145</b> Fuel (5365988)..... <b>BF46129</b> XC Series w/Cat C7 (7.2L) Eng. (To 1/2004) Lube (Standard Vers.) (1R0739).. <b>B76 +</b> Lube (Severe Service) (1R0739).. <b>B76-SS +</b> Fuel/Water Separator (w/o SP) (Alliance ABP-S3226FL02)..... <b>BF1346 +</b> Fuel/Water Separator (w/SP) (Alliance ABP-S3226FL02)..... <b>BF1346-SP +</b> Fuel (1R0751)..... <b>BF7632</b> Air (End Inlet) (Farr 114500-003). <b>PA3556</b> Air (Side Inlet) (Farr 114880-003). <b>PA3493</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> XC Series w/Cat C7 (7.2L) Eng. (1/2004-on) Lube (1R1807)..... <b>B7700 +</b> Fuel/Water Separator (w/o SP) (Alliance ABP-S3226FL02)..... <b>BF1346 +</b> Fuel/Water Separator (w/SP) (Alliance ABP-S3226FL02)..... <b>BF1346-SP +</b> Fuel (1R0751)..... <b>BF7632</b> Air (End Inlet) (Farr 114500-003). <b>PA3556</b> Air (Side Inlet) (Farr 114880-003). <b>PA3493</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> XC Series w/Cat C11 (11.1L) Eng. (To 1/2004) Lube (1R0716)..... <b>B99 +</b> Fuel/Water Separator (256-8753)..... <b>BF1259</b> Fuel (1R1712)..... <b>BF614 +</b> Fuel (High Efficiency) (1R0749).... <b>BF7587 +</b> Fuel (1R0762)..... <b>BF7753</b>	XC Series w/Cat C11 (11.1L) Eng. (1/2004-on) Lube (1R1808)..... <b>B7299 +</b> Fuel/Water Separator (256-8753)..... <b>BF1259</b> Fuel (1R1712)..... <b>BF614 +</b> Fuel (High Efficiency) (1R0749).... <b>BF7587 +</b> Fuel (1R0762)..... <b>BF7753</b> XC Series w/Cat 3126 (7.2L) Eng. (To 1/2004) Lube (Standard Vers.) (1R0739).. <b>B76</b> Fuel/Water Separator (175-2949)..... <b>BF1268</b> Fuel/Water Separator (256-8753)..... <b>BF1259</b> P. Fuel (1R0751)..... <b>BF7632</b> XC Series w/Cat 3126 (7.2L) Eng. (1/2004-on) Lube (1R1807)..... <b>B7700 +</b> Fuel/Water Separator (175-2949)..... <b>BF1268</b> Fuel/Water Separator (256-8753)..... <b>BF1259</b> P. Fuel (1R0751)..... <b>BF7632</b> XC Series w/Cummins B5.9G (5.9L) CNG Eng. Lube (3937743)..... <b>BT7349</b> XC Series w/Cummins B5.9 Gas Eng. Lube (3937743)..... <b>BT7349</b> XC Series w/Cummins 6BT5.9 Eng. Lube (Chrysler 5083285AA)..... <b>BT7349</b> Fuel/Water Separator (3925274). <b>BF1280 +</b> S. Fuel (3903640)..... <b>BF788</b> XC Series w/Cummins ISB (5.9L) Eng. Lube (Fleetguard LF3970)..... <b>B7177</b> Lube (4897898)..... <b>BT7237</b> Lube (Fleetguard LF3729)..... <b>BT595</b> Fuel/Water Separator Ele. (Fleetguard FS19579)..... <b>PF7777</b> Fuel/Water Separator Spin-on (Fleetguard FS19519)..... <b>BF1271</b> Fuel/Water Separator Spin-on (Remote Mtd.) (Fleetguard FS19596)..... <b>BF1293-SPS</b> Fuel (Racor RAI-025RAC10)..... <b>BF46006</b> Air (End Inlet) (Farr 114500-003).. <b>PA3556</b> Air (Side Inlet) (Farr 114880-003). <b>PA3493</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> XC Series w/Cummins ISB 5.9 (5.9L) Eng. Lube (Fleetguard LF3970)..... <b>B7177</b> Lube (4897898)..... <b>BT7237</b> Lube (Fleetguard LF3729)..... <b>BT595</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).


FREIGHTLINER Chassis (cont'd)	FREIGHTLINER Chassis (cont'd)	FREIGHTLINER Chassis (cont'd)
XC Series w/Cummins ISB 5.9 (5.9L) Eng. (Cont'd)	XC Series w/Cummins ISL 8.9 (8.9L) Eng. (1/2005-on) (Cont'd)	XC Straight Rail w/Cummins B6.7 (6.7L) Eng. (2021)
<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19579)..... <b>PF7777</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Fuel</b> (3937736)..... <b>B7177</b>
<b>Fuel/Water Separator Spin-on</b> (Fleetguard FS19519)..... <b>BF1271</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Fuel</b> (5303743)..... <b>BF63000</b>
<b>Fuel/Water Separator Spin-on</b> (Remote Mtd.) (Fleetguard FS19596)..... <b>BF1293-SPS</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Crankcase Breather</b> (4936636)... <b>CV15010</b>
<b>Fuel</b> (Racor RAI-025RAC10)..... <b>BF46006</b>	XC Series w/Mercedes-Benz MBE906 Eng.	XC Straight Rail w/Cummins L9 (9.0L) Eng. (2020)
<b>Air</b> (End Inlet) (Farr 114500-003).. <b>PA3556</b>	<b>F-F Lube</b> (A0001801709)..... <b>P7188</b>	<b>Lube</b> (5444774)..... <b>B40142</b>
<b>Air</b> (Side Inlet) (Farr 114880-003). <b>PA3493</b>	<b>Opt. B-P Lube</b> (A9061810086)... <b>BC7326 +</b>	<b>Fuel</b> (5303743)..... <b>BF63000</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Fuel</b> (4 1/16 In.) (A0000901551)... <b>PF7735</b>	XC Straight Rail w/Cummins L9 (9.0L) Eng. (2021)
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Fuel</b> (7 31/32 In.) (A5410920805). <b>PF7761</b>	<b>Lube</b> (5444774)..... <b>B40142</b>
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	XC Series w/Mercedes-Benz MBE926 Eng.	<b>Fuel</b> (5303743)..... <b>BF63000</b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>F-F Lube Ele.</b> (A0001801709)..... <b>P7188</b>	XC Straight Rail w/Cummins L9 (9.0L) Eng. (2022)
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Opt. B-P Lube Spinner</b> (A9061810086)..... <b>BC7326 +</b>	<b>Lube</b> (5520789)..... <b>B40142</b>
XC Series w/Cummins ISC 8.3 (8.3L) Eng.	<b>Fuel</b> (A0000901551)..... <b>PF7735</b>	<b>FREIGHTLINER Trucks &amp; Buses</b>
<b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	108SD w/Cummins B6.7 (6.7L) Eng. (2018)
<b>P. Fuel</b> (Fleetguard FF5488)..... <b>BF7815</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Lube</b> (3937736)..... <b>B7177</b>
<b>P. Fuel</b> (Fleetguard FF5636)..... <b>BF7924</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b>
XC Series w/Cummins ISL 8.9 (8.9L) Eng. (To 1/2005)	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Channel Flow Air</b> (Don. P621097)..... <b>CA30131</b>
<b>Dual-Flow Lube</b> (Fleetguard LF3000)..... <b>BD103 +</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>
<b>Fuel/Water Separator</b> (Remote Mtd.) (Fleetguard FS1022)..... <b>BF1272-SPS</b>	XC Straight Rail w/Cummins B6.7 (6.7L) Eng. (2018)	<b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b>
<b>Fuel</b> (Fleetguard FF5488)..... <b>BF7815</b>	<b>Lube</b> (3937736)..... <b>B7177</b>	<b>Crankcase Breather</b> (4936636)... <b>CV15010</b>
<b>Air</b> (Side Inlet) (Farr 62891001)... <b>PA2721</b>	<b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Steering</b> (1417927000)..... <b>PT23629</b>
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	108SD w/Cummins B6.7 (6.7L) Eng. (2019)
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Lube</b> (3937736)..... <b>B7177</b>
XC Series w/Cummins ISL 8.9 (8.9L) Eng. (1/2005-on)	<b>Trans. (2 In. Kit)</b> (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Fuel/Water Separator</b> (Fleetguard FS20081)..... <b>PF46171</b>
<b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b>	<b>Trans. (4 In. Kit)</b> (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Fuel</b> (5660774)..... <b>BF63000</b>
<b>Fuel/Water Separator</b> (Remote Mtd.) (Fleetguard FS1022)..... <b>BF1272-SPS</b>	<b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	<b>Primary Channel Flow Air</b> (Don. P621097)..... <b>CA30131</b>
<b>Fuel</b> (Fleetguard FF5488)..... <b>BF7815</b>	XC Straight Rail w/Cummins B6.7 (6.7L) Eng. (2019)	<b>Secondary Channel Flow Air</b> (Don. P616400)..... <b>PA4701</b>
<b>Air</b> (Side Inlet) (Farr 62891001)... <b>PA2721</b>	<b>Lube</b> (3937736)..... <b>B7177</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Fuel</b> (5303743)..... <b>BF63000</b>	<b>Air Dryer</b> (Wabco R950068A)..... <b>BA5379</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	<b>Crankcase Breather</b> (4936636)... <b>CV15010</b>
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	XC Straight Rail w/Cummins B6.7 (6.7L) Eng. (2020)	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Lube</b> (3937736)..... <b>B7177</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Fuel</b> (5303743)..... <b>BF63000</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
XC Series w/Cummins ISL 8.9 (8.9L) Eng. (1/2005-on)	<b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
<b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b>	XC Straight Rail w/Cummins B6.7 (6.7L) Eng. (2020)	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>Fuel/Water Separator</b> (Remote Mtd.) (Fleetguard FS1022)..... <b>BF1272-SPS</b>	<b>Lube</b> (3937736)..... <b>B7177</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>
<b>Fuel</b> (Fleetguard FF5488)..... <b>BF7815</b>	<b>Fuel</b> (5303743)..... <b>BF63000</b>	
<b>Air</b> (Side Inlet) (Farr 62891001)... <b>PA2721</b>	<b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>		
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>		

\* See Product Guide for Variations of This Number. Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
108SD w/Cummins B6.7 (6.7L) Eng. (2019) (Cont'd) Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> Steering (1417927000)..... <b>PT23629</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	108SD w/Cummins ISB (6.7L) Eng. (Cont'd) Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Trans. Ele. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2+</b> Steering (T1808D)..... <b>BT9388</b> Diesel Exhaust Fluid (5303604).. <b>PE17000</b>	108SD w/Cummins ISL (8.9L) Eng. (2014-18) (Cont'd) Steering (1417927000)..... <b>PT23629</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b> Diesel Exhaust Fluid (4388378).. <b>PE17002 KIT</b> Diesel Exhaust Fluid (5303604).. <b>PE17000</b>
108SD w/Cummins B6.7 (6.7L) Eng. (2020) Lube (3937736)..... <b>B7177</b> Fuel (5303743)..... <b>BF63000</b> Channel Flow Air (Don. P621097)..... <b>CA30131</b> Cab Air (36000006)..... <b>PA5359</b> Air Dryer (Bendix 107796PG)..... <b>BA5377</b> Crankcase Breather (4936636).. <b>CV15010</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Steering (1417927000)..... <b>PT23629</b>	108SD w/Cummins ISC (8.3L) Eng. Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309+</b> Fuel/Water Separator (Fleetguard FS1065)..... <b>BF1378-SPS</b> Fuel (Fleetguard FF5636)..... <b>BF7924</b> Cab Air (36000006)..... <b>PA5359</b> Air Dryer (Wabco R950011)..... <b>BA5374+</b> Coolant (Fleetguard WF2071)..... <b>BW5071</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Trans. Ele. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2+</b> Steering (T1808D)..... <b>BT9388</b> Diesel Exhaust Fluid (2888182).. <b>PE17000</b>	108SD w/Cummins ISL9 (9.0L) Eng. (2019) Lube (3401544)..... <b>B40142</b> Fuel/Water Separator (Racor R61709)..... <b>PF46235</b> Fuel (5303743)..... <b>BF63000</b> Channel Flow Primary Air (Don. P621097)..... <b>CA30131</b> Channel Flow Secondary Air (Don. P616400)..... <b>PA4701</b> Cab Air (36000006)..... <b>PA5359</b> Air Dryer (Wabco R950068A)..... <b>BA5379+</b> Trans. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Steering (1417927000)..... <b>PT23629</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>
108SD w/Cummins B6.7 (6.7L) Eng. (2021) Lube (3937736)..... <b>B7177</b> Fuel (5303743)..... <b>BF63000</b> Channel Flow Air (P621097)..... <b>CA30131</b> Cab Air (ABPN10G36000006)..... <b>PA5359</b> Air Dryer (Bendix 5008414PG)..... <b>BA5379</b> Crankcase Breather (4936636).. <b>CV15010</b> Steering (1417927000)..... <b>PT23629</b>	108SD w/Cummins ISC (8.3L) Eng. Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309+</b> Fuel/Water Separator (Alliance ABPN122R50550)..... <b>BF9871-O</b> Fuel/Water Separator (Fleetguard FS19551)..... <b>BF1390-O</b> Fuel/Water Separator (Racor R61709)..... <b>PF46235</b> Fuel (5303743)..... <b>BF63000</b> Channel Flow Primary Air (Don. P621097)..... <b>CA30131</b> Channel Flow Secondary Air (Don. P616400)..... <b>PA4701</b> Cab Air (N10G36000006)..... <b>PA5359</b> Air Dryer (Wabco R950011)..... <b>BA5374+</b> Trans. Ele. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> Steering (T1808D)..... <b>BT9388</b>	108SD w/Cummins L9 (9.0L) Eng. (2018) Lube (3401544)..... <b>B40142</b> Fuel/Water Separator (Fleetguard FS20081)..... <b>PF46171</b> Fuel/Water Separator (Racor R61709)..... <b>PF46235</b> Fuel (Fleetguard FF63008)..... <b>BF63000</b> Channel Flow Air (Don. P621097)..... <b>CA30131</b> Cab Air (36000006)..... <b>PA5359</b> Air Dryer (Bendix 5008414)..... <b>BA5374+</b> Crankcase Breather (4936636).. <b>CV15010</b> Trans. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> Steering (1417927000)..... <b>PT23629</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b> Diesel Exhaust Fluid (4388378).. <b>PE17002 KIT</b>
108SD w/Cummins B6.7 (6.7L) Eng. (2022) Lube (Fleetguard LF3970)..... <b>B7177</b> Channel Flow EXO Air (P621097)..... <b>CA30131</b>	108SD w/Cummins ISL (8.9L) Eng. (2014-18) Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309+</b> Fuel/Water Separator (Alliance ABPN122R50550)..... <b>BF9871-O</b> Fuel/Water Separator (Fleetguard FS19551)..... <b>BF1390-O</b> Fuel/Water Separator (Racor R61709)..... <b>PF46235</b> Fuel (5303743)..... <b>BF63000</b> Channel Flow Primary Air (Don. P621097)..... <b>CA30131</b> Channel Flow Secondary Air (Don. P616400)..... <b>PA4701</b> Cab Air (N10G36000006)..... <b>PA5359</b> Air Dryer (Wabco R950011)..... <b>BA5374+</b> Trans. Ele. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> Steering (T1808D)..... <b>BT9388</b>	108SD w/Cummins L9 (9.0L) Eng. (2019) Lube (3401544)..... <b>B40142</b> Fuel/Water Separator (Fleetguard FS20081)..... <b>PF46171</b> Fuel/Water Separator (Racor R61709)..... <b>PF46235</b> Fuel (5660774)..... <b>BF63000</b> Channel Flow Primary Air (Don. P621097)..... <b>CA30131</b> Channel Flow Secondary Air (Don. P616400)..... <b>PA4701</b> Cab Air (36000006)..... <b>PA5359</b> Air Dryer (Wabco R950068A)..... <b>BA5379+</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
108SD w/Cummins L9 (9.0L) Eng. (2019) (Cont'd)	108SD w/Detroit DD8 (7.7L) Eng. (2019) (Cont'd)	114SD w/Cummins ISC (8.3L) Eng. (Cont'd)
Trans. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	Channel Flow Primary Air (Flame Retardant Media) (Don. P605960) <b>CA5419</b>
Trans. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	Channel Flow Secondary Air (Don. P547520)..... <b>PA5418</b>
Steering (1417927000)..... <b>PT23629</b>	Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>	Cab Air (36000006)..... <b>PA5359</b>
Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	Air Dryer (Wabco R950011)..... <b>BA5374 +</b>
108SD w/Cummins L9 (9.0L) Eng. (2020)	Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	Coolant (Fleetguard WF2071)..... <b>BW5071</b>
Lube (5444774)..... <b>B40142</b>	Steering (1417927000)..... <b>PT23629</b>	Trans. Ele. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>
Fuel/Water Separator (Fleetguard FS20081)..... <b>PF46171</b>	Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>
Fuel/Water Separator (Racor R61709)..... <b>PF46235</b>	Diesel Exhaust Fluid (A0001421089)..... <b>PE17002 KIT</b>	Trans. Spin-on (Fuller 4304827)..... <b>BT223</b>
Fuel (5660774)..... <b>BF63000</b>	Crankcase Breather (N/S)..... <b>N/S</b>	Steering (T1808D)..... <b>BT9388</b>
Channel Flow Air (P621097)..... <b>CA30131</b>	108SD w/Detroit DD8 (7.7L) Eng. (2020)	Diesel Exhaust Fluid (2888182)..... <b>PE17000</b>
Cab Air (36000006)..... <b>PA5359</b>	Fuel/Water Separator (Racor R61709)..... <b>PF46235</b>	114SD w/Cummins ISL (8.9L) Eng. (2012-17)
Air Dryer (Bendix 107796PG)..... <b>BA5377</b>	Channel Flow Air (P621097)..... <b>CA30131</b>	Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309 +</b>
Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	Cab Air (36000006)..... <b>PA5359</b>	Fuel/Water Separator Ele. (Racor R61709)..... <b>PF46235</b>
Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	Air Dryer (Bendix 107796PG)..... <b>BA5377</b>	Fuel/Water Separator Ele. (Fleetguard FS19764)..... <b>PF9814</b>
Steering (1417927000)..... <b>PT23629</b>	Trans. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	Fuel/Water Separator Spin-on (3 23/32 O.D.) (Fleetguard FS1065)..... <b>BF1378-SPS</b>
108SD w/Cummins L9 (9.0L) Eng. (2021)	Trans. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	Fuel/Water Separator Spin-on (4 5/16 O.D.) (Alliance ABPN122R50550)..... <b>BF9871-O</b>
Lube (5444774)..... <b>B40142</b>	Steering (1417927000)..... <b>PT23629</b>	Fuel (Fleetguard FF5636)..... <b>BF7924</b>
Fuel/Water Separator (A0000904851)..... <b>PF46171</b>	Diesel Exhaust Fluid (A0001421089)..... <b>PE17002 KIT</b>	Fuel (Fleetguard FF63009)..... <b>BF63000</b>
Fuel (5303743)..... <b>BF63000</b>	108SD w/Detroit DD8 (7.7L) Eng. (2021)	Channel Flow Primary Air (Don. P619498)..... <b>CA30132</b>
Channel Flow Air (P621097)..... <b>CA30131</b>	Channel Flow Air (P621097)..... <b>CA30131</b>	Secondary Air (Don. P616400)..... <b>PA4701</b>
Cab Air (ABPN10G36000006)..... <b>PA5359</b>	Cab Air (ABPN10G36000006)..... <b>PA5359</b>	Channel Flow Primary Air (Standard Media) (Don. P607965)..... <b>CA5368</b>
Air Dryer (Bendix 5008414PG)..... <b>BA5379</b>	Air Dryer (Bendix 5008414PG)..... <b>BA5379</b>	Channel Flow Primary Air (Flame Retardant Media) (Don. P605960) <b>CA5419</b>
Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	Trans. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	Channel Flow Secondary Air (Don. P547520)..... <b>PA5418</b>
Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	Trans. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	Cab Air (36000006)..... <b>PA5359</b>
Steering (1417927000)..... <b>PT23629</b>	Steering (1417927000)..... <b>PT23629</b>	Air Dryer (Wabco R950011)..... <b>BA5374 +</b>
108SD w/Cummins L9 (9.0L) Eng. (2022)	Diesel Exhaust Fluid (A0001421089)..... <b>PE17002 KIT</b>	Coolant (Fleetguard WF2071)..... <b>BW5071</b>
Lube (5520789)..... <b>B40142</b>	108SD w/Detroit DD8 (7.7L) Eng. (2022)	Trans. Ele. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>
Fuel/Water Separator (Racor R61709)..... <b>PF46235</b>	Channel Flow EXO Air (P621097)..... <b>CA30131</b>	Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>
Channel Flow EXO Air (P621097)..... <b>CA30131</b>	114SD w/Cummins ISC (8.3L) Eng.	Trans. Spin-on (Fuller 4304827)..... <b>BT223</b>
108SD w/Cummins L9 (9.0L) Eng. (2023)	Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309 +</b>	Steering (T1808D)..... <b>BT9388</b>
Lube (5520789)..... <b>B40142</b>	Fuel/Water Separator (Fleetguard FS1065)..... <b>BF1378-SPS</b>	Steering (1417927000)..... <b>PT23629</b>
108SD w/Detroit DD8 (7.7L) Eng. (2019)	Fuel (Fleetguard FF5636)..... <b>BF7924</b>	Diesel Exhaust Fluid (5303604)..... <b>PE17000</b>
Fuel/Water Separator (A0000904851)..... <b>PF46171</b>	Channel Flow Primary Air (Don. P619498)..... <b>CA30132</b>	114SD w/Cummins ISL 8.9 (8.9L) Eng. (2018)
Channel Flow Primary Air (Don. P621097)..... <b>CA30131</b>	Channel Flow Secondary Air (Don. P616400)..... <b>PA4701</b>	Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309 +</b>
Channel Flow Secondary Air (Don. P616400)..... <b>PA4701</b>	Channel Flow Primary Air (Standard Media) (Don. P607965)..... <b>CA5368</b>	Fuel/Water Separator (Racor R61709)..... <b>PF46235</b>
Cab Air (36000006)..... <b>PA5359</b>		Fuel (Fleetguard FF63009)..... <b>BF63000</b>
Air Dryer (Wabco R950068A)..... <b>BA5379 +</b>		Channel Flow Primary Air (Don. P619498)..... <b>CA30132</b>
Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>		
Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>		


+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
114SD w/Cummins ISL 8.9 (8.9L) Eng. (2018) (Cont'd)	114SD w/Cummins ISL-G (8.9L) Eng. (2013-18) (Cont'd)	114SD w/Cummins ISX 11.9G (11.9L) Eng. (2019) (Cont'd)
Channel Flow Secondary Air (Don. P616400)..... PA4701	Steering (1417927000)..... PT23629	Opt. Rear Axle (Meritor 3280V8394)..... B233
Channel Flow Primary Air (Standard Media) (Don. P607965)..... CA5368	114SD w/Cummins ISL-G (8.9L) Eng. (2019)	114SD w/Cummins ISX 11.9G (11.9L) Eng. (2020)
Channel Flow Primary Air (Flame Retardant Media) (Don. P605960) CA5419	Lube (3401544)..... B40142	Dual-Flow Lube (Fleetguard LF14000NN)..... BD50000
Channel Flow Secondary Air (Don. P547520)..... PA5418	Fuel (3606712)..... BF7695	Fuel (Fleetguard NG5900)..... BF7695
Cab Air (36000006)..... PA5359	Channel Flow Air (Don. P634517)..... CA30132	Channel Flow Air (Don. P634517)..... CA30132
Air Dryer (Bendix 107796)..... BA5377	Cab Air (ABPN10G36000006).... PA5359	Cab Air (36000006)..... PA5359
Trans. Ele. (2 In. Kit) (Allison 29548987)..... PT9416-MPG KIT	Air Dryer (Bendix 5008414PG).... BA5379	Air Dryer (Bendix 107796PG).... BA5377
Trans. Ele. (4 In. Kit) (Allison 29548988)..... PT9415-MPG KIT	Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	Trans. (2 In. Kit) (Allison 29548987)..... PT9416-MPG KIT
Steering (1417927000)..... PT23629	Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Trans. (4 In. Kit) (Allison 29548988)..... PT9415-MPG KIT
Opt. Rear Axle (Meritor 3280V8394)..... B233	Steering (1417927000)..... PT23629	Steering (1417927000)..... PT23629
Diesel Exhaust Fluid (Fleetguard UF106)..... PE17002 KIT	Opt. Rear Axle (Meritor 3280V8394)..... B233	Opt. Rear Axle (Meritor 3280V8394)..... B233
114SD w/Cummins ISL9 (9.0L) Eng. (2020)	114SD w/Cummins ISX 11.9G (11.9L) Eng. (2018)	114SD w/Cummins ISX 11.9G (11.9L) Eng. (2021)
Lube (5444774)..... B40142	Dual-Flow Lube (4367100)..... BD50000	Lube (5575298)..... B40145
Fuel/Water Separator (A0000904851)..... PF46171	Fuel/Water Separator (3607140). BF7695	Fuel (3607140)..... BF7695
Fuel (5303743)..... BF63000	Channel Flow Primary Air (Don. P619498)..... CA30132	Channel Flow EXO Air (Don. P634517)..... CA30132
Channel Flow Air (Don. P634517)..... CA30132	Channel Flow Secondary Air (Don. P616400)..... PA4701	Cab Air (ABPN10G36000006).... PA5359
Cab Air (36000006)..... PA5359	Channel Flow Primary Air (Standard Media) (Don. P607965)..... CA5368	Air Dryer (Wabco R950068)..... BA5379
Air Dryer (Bendix 107796PG).... BA5377	Channel Flow Primary Air (Flame Retardant Media) (Don. P605960) CA5419	Coolant (3680434)..... B5087
Trans. Ele. (2 In. Kit) (Allison 29558117)..... PT9416-MPG KIT	Channel Flow Secondary Air (Don. P547520)..... PA5418	Steering (1417927000)..... PT23629
Trans. Ele. (4 In. Kit) (Allison 29558118)..... PT9415-MPG KIT	Cab Air (36000006)..... PA5359	114SD w/Cummins ISX 11.9G (11.9L) Eng. (2022)
Steering (1417927000)..... PT23629	Air Dryer (Bendix 107796)..... BA5377	Channel Flow EXO Air (Don. P634517)..... CA30132
Opt. Rear Axle (Meritor 3280V8394)..... B233	Coolant (3680434)..... B5087	Cab Air (36000006)..... PA5359
114SD w/Cummins ISL-G (8.9L) Eng. (2013-18)	Trans. (2 In. Kit) (Allison 29548987)..... PT9416-MPG KIT	Air Dryer (Bendix 107794)..... BA5377
Channel Flow Primary Air (Don. P619498)..... CA30132	Trans. (4 In. Kit) (Allison 29548988)..... PT9415-MPG KIT	114SD w/Cummins L9 (9.0L) Eng. (2018)
Channel Flow Secondary Air (Don. P616400)..... PA4701	Steering (1417927000)..... PT23629	Lube (3401544)..... B40142
Channel Flow Primary Air (Standard Media) (Don. P607965)..... CA5368	Opt. Rear Axle (Meritor 3280V8394)..... B233	Fuel/Water Separator (Racor R61709)..... PF46235
Channel Flow Primary Air (Flame Retardant Media) (Don. P605960) CA5419	114SD w/Cummins ISX 11.9G (11.9L) Eng. (2019)	Fuel (Fleetguard FF63008)..... BF63000
Channel Flow Secondary Air (Don. P547520)..... PA5418	Dual-Flow Lube (Fleetguard LF9080)..... BD7154	Channel Flow Primary Air (Don. P619498)..... CA30132
Cab Air (36000006)..... PA5359	Fuel/Water Separator (Fleetguard NG5900)..... BF7695	Channel Flow Secondary Air (Don. P616400)..... PA4701
Air Dryer (Bendix 107796)..... BA5377	Channel Flow Air (Don. P634517)..... CA30132	Channel Flow Primary Air (Standard Media) (Don. P607965)..... CA5368
Air Dryer (Wabco R950011)..... BA5374 +	Cab Air (ABPN10G36000006).... PA5359	Channel Flow Primary Air (Flame Retardant Media) (Don. P605960) CA5419
Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	Air Dryer (Bendix 5008414PG).... BA5379	Channel Flow Secondary Air (Don. P547520)..... PA5418
Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Trans. (2 In. Kit) (Allison 29548987)..... PT9416-MPG KIT	Cab Air (36000006)..... PA5359
Trans. Spin-on (Fuller 4304827).. BT223	Trans. (4 In. Kit) (Allison 29548988)..... PT9415-MPG KIT	Air Dryer (Bendix 107796)..... BA5377
Steering (T1808D)..... BT9388	Steering (1417927000)..... PT23629	Crankcase Breather (4936636)... CV15010
		Trans. (2 In. Kit) (Allison 29548987)..... PT9416-MPG KIT

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
114SD w/Cummins L9 (9.0L) Eng. (2018) (Cont'd) Trans. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> Steering (1417927000)..... <b>PT23629</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b> Diesel Exhaust Fluid (4388378).. <b>PE17002 KIT</b>	114SD w/Cummins L9 (9.0L) Eng. (2022) Lube (5520789)..... <b>B40142</b> Channel Flow EXO Air (Don. P634517)..... <b>CA30132</b> Cab Air (36000006)..... <b>PA5359</b> Air Dryer (Bendix 107794)..... <b>BA5377</b>	114SD w/Cummins X12 (11.9L) Eng. (2020) (Cont'd) Trans. (2 In. Kit) (Allison 29558328)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29558329)..... <b>PT9415-MPG KIT</b> Steering (1417927000)..... <b>PT23629</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>
114SD w/Cummins L9 (9.0L) Eng. (2019) Lube (3401544)..... <b>B40142</b> Fuel/Water Separator (A0000904851)..... <b>PF46171</b> Fuel (5660774)..... <b>BF63000</b> Channel Flow Air (Don. P634517)..... <b>CA30132</b> Cab Air (ABPN10G36000006)..... <b>PA5359</b> Air Dryer (Bendix 5008414PG)..... <b>BA5379</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Steering (1417927000)..... <b>PT23629</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	114SD w/Cummins L9N (9.0L) Eng. (2019) Lube (3401544)..... <b>B40142</b> Fuel/Water Separator (Fleetguard NG5900)..... <b>BF7695</b> Channel Flow EXO Air (Don. P634517)..... <b>CA30132</b> Cab Air (Alliance ABPN10G36000006)..... <b>PA5359</b> Air Dryer (Bendix 5008414PG)..... <b>BA5379</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Steering (1417927000)..... <b>PT23629</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	114SD w/Cummins X12 (11.9L) Eng. (2021) Dual-Flow Lube (4367100)..... <b>BD50000</b> Fuel/Water Separator (BR90FRT10)..... <b>BF9871-O</b> Fuel (5365988)..... <b>BF46129</b> Channel Flow EXO Air (Don. P634517)..... <b>CA30132</b> Cab Air (ABPN10G36000006)..... <b>PA5359</b> Air Dryer (Wabco R950068)..... <b>BA5379</b> Trans. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Steering (1417927000)..... <b>PT23629</b>
114SD w/Cummins L9 (9.0L) Eng. (2020) Lube (5444774)..... <b>B40142</b> Fuel/Water Separator (A0000904851)..... <b>PF46171</b> Fuel/Water Separator (Fleetguard FS20176)..... <b>PF46235</b> Fuel (5660774)..... <b>BF63000</b> Channel Flow Air (Don. P634517)..... <b>CA30132</b> Cab Air (36000006)..... <b>PA5359</b> Air Dryer (Bendix 107796PG)..... <b>BA5377</b> Coolant (Fleetguard WF2123)..... <b>B5090</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Steering (1417927000)..... <b>PT23629</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	114SD w/Cummins L9N (9.0L) Eng. (2020) Lube (3401544)..... <b>B40142</b> Fuel (3607140)..... <b>BF7695</b> Channel Flow Air (Don. P634517)..... <b>CA30132</b> Cab Air (36000006)..... <b>PA5359</b> Air Dryer (Bendix 107796PG)..... <b>BA5377</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Steering (1417927000)..... <b>PT23629</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	114SD w/Cummins X12 (11.9L) Eng. (2022) Lube (5575298)..... <b>B40145</b> Fuel (5365988)..... <b>BF46129</b> Channel Flow EXO Air (Don. P634517)..... <b>CA30132</b> Cab Air (36000006)..... <b>PA5359</b> Air Dryer (Bendix 107794)..... <b>BA5377</b> Trans. Ele. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>
114SD w/Cummins L9 (9.0L) Eng. (2021) Lube (5444774)..... <b>B40142</b> Fuel (5303743)..... <b>BF63000</b> Channel Flow EXO Air (Don. P634517)..... <b>CA30132</b> Cab Air (ABPN10G36000006)..... <b>PA5359</b> Air Dryer (Wabco R950068)..... <b>BA5379</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Steering (1417927000)..... <b>PT23629</b>	114SD w/Cummins L9N (8.9L) Eng. (2021) Lube (Fleetguard LF14002NN)..... <b>B40142</b> Fuel (Fleetguard NG5900)..... <b>BF7695</b> Channel Flow Air (Don. P634517)..... <b>CA30132</b> Cab Air (ABPN10G36000006)..... <b>PA5359</b> Air Dryer (Wabco R950068)..... <b>BA5379</b> Steering (1417927000)..... <b>PT23629</b>	114SD w/Detroit DD8 (7.7L) Eng. (2019) Channel Flow EXO Air (Don. P634517)..... <b>CA30132</b> Cab Air (Alliance ABPN10G36000006)..... <b>PA5359</b> Air Dryer (Bendix 5008414PG)..... <b>BA5379</b> Crankcase Breather (N/S)..... <b>N/S</b> Trans. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Steering (1417927000)..... <b>PT23629</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>
114SD w/Cummins L9 (9.0L) Eng. (2021) Lube (5444774)..... <b>B40142</b> Fuel (5303743)..... <b>BF63000</b> Channel Flow EXO Air (Don. P634517)..... <b>CA30132</b> Cab Air (ABPN10G36000006)..... <b>PA5359</b> Air Dryer (Wabco R950068)..... <b>BA5379</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Steering (1417927000)..... <b>PT23629</b>	114SD w/Cummins L9N (8.9L) Eng. (2022) Channel Flow EXO Air (Don. P634517)..... <b>CA30132</b> Cab Air (36000006)..... <b>PA5359</b> Air Dryer (Bendix 107794)..... <b>BA5377</b>	114SD w/Detroit DD8 (7.7L) Eng. (2020) Channel Flow EXO Air (Don. P634517)..... <b>CA30132</b> Cab Air (36000006)..... <b>PA5359</b> Air Dryer (Bendix 107796PG)..... <b>BA5377</b> Trans. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Steering (1417927000)..... <b>PT23629</b>
114SD w/Cummins L9 (9.0L) Eng. (2021) Lube (5444774)..... <b>B40142</b> Fuel (5303743)..... <b>BF63000</b> Channel Flow EXO Air (Don. P634517)..... <b>CA30132</b> Cab Air (ABPN10G36000006)..... <b>PA5359</b> Air Dryer (Wabco R950068)..... <b>BA5379</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Steering (1417927000)..... <b>PT23629</b>	114SD w/Cummins X12 (11.9L) Eng. (2020) Dual-Flow Lube (4367100)..... <b>BD50000</b> Fuel/Water Separator (Alliance R50550)..... <b>BF9871-O</b> Fuel (5365988)..... <b>BF46129</b> Channel Flow Element (Don. P634517)..... <b>CA30132</b> Cab Air (36000006)..... <b>PA5359</b> Air Dryer (Bendix 107796PG)..... <b>BA5377</b>	


Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
114SD w/Detroit DD8 (7.7L) Eng. (2020) (Cont'd) Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	114SD w/Detroit DD13 (12.8L) Eng. (2018) <b>Lube</b> (A4731800109)..... <b>P7505</b> <b>Fuel/Water Separator</b> (A0000903651)..... <b>PF9804</b> <b>Fuel Kit</b> (A4720900651)..... <b>PF9908 KIT</b> <b>Channel Flow Primary Air</b> (Don. P619498)..... <b>CA30132</b> <b>Channel Flow Secondary Air</b> (Don. P616400)..... <b>PA4701</b> <b>Channel Flow Primary Air</b> (Standard Media) (Don. P607965)..... <b>CA5368</b> <b>Channel Flow Primary Air</b> (Flame Retardant Media) (Don. P605960) <b>CA5419</b> <b>Channel Flow Secondary Air</b> (Don. P547520)..... <b>PA5418</b> <b>Cab Air</b> (36000006)..... <b>PA5359</b> <b>Air Dryer</b> (Bendix 107794)..... <b>BA5377</b>	114SD w/Detroit DD13 (12.8L) Eng. (2020) (Cont'd) <b>Air Dryer</b> (Bendix 107796PG)..... <b>BA5377</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b>
114SD w/Detroit DD8 (7.7L) Eng. (2021) <b>Channel Flow EXO Air</b> (Don. P634517)..... <b>CA30132</b> <b>Cab Air</b> (ABPN10G36000006)..... <b>PA5359</b> <b>Air Dryer</b> (Wabco R950068)..... <b>BA5379</b> <b>Steering</b> (1417927000)..... <b>PT23629</b>	114SD w/Detroit DD13 (12.8L) Eng. (2012-17) <b>Lube</b> (A4731800109)..... <b>P7505</b> <b>Fuel/Water Separator</b> (A0000905051)..... <b>PF46145</b> <b>Fuel/Water Separator</b> (Racor R61709)..... <b>PF46235</b> <b>Fuel/Water Separator Ele.</b> (A0000903651)..... <b>PF9804</b> <b>Opt. Fuel/Water Separator Spin-on</b> (Cummins 154789)..... <b>BF957-D +</b> <b>Fuel Kit</b> (2 Filter Kit) (A4720900651)..... <b>PF9908 KIT</b> <b>Fuel Kit</b> (3 Filter Kit) (A0000904251)..... <b>PF9924 KIT</b> <b>Channel Flow Primary Air</b> (Don. P619498)..... <b>CA30132</b> <b>Channel Flow Secondary Air</b> (Don. P616400)..... <b>PA4701</b> <b>Channel Flow Primary Air</b> (Standard Media) (Don. P607965)..... <b>CA5368</b> <b>Channel Flow Primary Air</b> (Flame Retardant Media) (Don. P605960) <b>CA5419</b> <b>Channel Flow Secondary Air</b> (Don. P547520)..... <b>PA5418</b> <b>Cab Air</b> (36000006)..... <b>PA5359</b> <b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b> <b>Air Dryer</b> (Wabco R950068)..... <b>BA5379 +</b> <b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (A4722030255)..... <b>P5092</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (T1808D)..... <b>BT9388</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b> <b>Diesel Exhaust Fluid</b> (A0001420289)..... <b>PE5272</b>	114SD w/Detroit DD13 (12.8L) Eng. (2021) <b>Fuel</b> (A4700903151)..... <b>PF9908 KIT</b> <b>Channel Flow EXO Air</b> (Don. P634517)..... <b>CA30132</b> <b>Cab Air</b> (ABPN10G36000006)..... <b>PA5359</b> <b>Air Dryer</b> (Wabco R950068)..... <b>BA5379</b> <b>Trans.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b>
114SD w/Detroit DD13 (12.8L) Eng. (2022) <b>Channel Flow EXO Air</b> (Don. P634517)..... <b>CA30132</b> <b>Cab Air</b> (36000006)..... <b>PA5359</b> <b>Air Dryer</b> (Bendix 107794)..... <b>BA5377</b> <b>Trans.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	114SD w/Detroit DD13 (12.8L) Eng. (2019) <b>Lube</b> (A4731800409)..... <b>P7505</b> <b>Fuel Kit</b> (A4720900651)..... <b>PF9908 KIT</b> <b>Channel Flow Air</b> (Don. P634517)..... <b>CA30132</b> <b>Cab Air</b> (ABPN10G36000006)..... <b>PA5359</b> <b>Air Dryer</b> (Bendix 5008414PG).... <b>BA5379</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b>	114SD w/Detroit DD13 (12.8L) Eng. (2023) <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
114SD w/Detroit DD13 (12.8L) Eng. (2020) <b>Lube</b> (To Eng. S/N A472910S0690710) (A4731800409)..... <b>P7505</b> <b>Fuel/Water Separator</b> (A0000905051)..... <b>PF46145</b> <b>Fuel</b> (A4700903151)..... <b>PF9908 KIT</b> <b>Channel Flow Air</b> (Don. P634517)..... <b>CA30132</b> <b>Cab Air</b> (36000006)..... <b>PA5359</b>	122SD w/Cummins ISX 15.0 (14.9L) Eng. (2013) <b>11 7/8 In. Dual-Flow Lube</b> (3406809)..... <b>BD7154 +</b> <b>14 In. Dual-Flow Lube</b> (3406810)..... <b>BD7153 +</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19763)..... <b>PF7928</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19764)..... <b>PF9814</b> <b>Fuel/Water Separator Spin-on</b> (3331096)..... <b>BF1274-SP</b> <b>Fuel</b> (Fleetguard FF5686)..... <b>BF9860 +</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
122SD w/Cummins ISX 15.0 (14.9L) Eng. (2013) (Cont'd)	122SD w/Cummins ISX 15.0 (14.9L) Eng. (2014) (Cont'd)	122SD w/Cummins ISX 15.0 (14.9L) Eng. (2015) (Cont'd)
Fuel (Fleetguard FF2200)..... <b>BF7766</b>	<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Radial Seal Air</b> (Standard) (Don. P535717)..... <b>RS3518</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>
<b>Radial Seal XP Air</b> (Upgrade) (Don. P535717)..... <b>RS3518XP</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Steering</b> (T1808D)..... <b>BT9388</b>
<b>EnduraCube Air</b> (3-36867-010)... <b>[2] PA32002</b>	<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>	<b>Some Rear Axle</b> (Meritor 3280-V-8394)..... <b>B233</b>
<b>Cab Air</b> (91559)..... <b>PA4857</b>	<b>Crankcase Breather</b> (3685528)... <b>CV15000</b>	<b>Diesel Exhaust Fluid</b> (2880298).. <b>PE17000</b>
<b>Cab Air</b> (BOA91621)..... <b>PA5773</b>	<b>Coolant</b> (Fleetguard WF2126)..... <b>BW5086</b>	122SD w/Cummins ISX 15.0 (14.9L) Eng. (2016)
<b>Cab Air</b> (36000006)..... <b>PA5359</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>11 7/8 In. Dual-Flow Lube</b> (3406809)..... <b>BD7154 +</b>
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>14 In. Dual-Flow Lube</b> (3406810)..... <b>BD7153 +</b>
<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>
<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Steering</b> (T1808D)..... <b>BT9388</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19763)..... <b>PF7928</b>
<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Some Rear Axle</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19764)..... <b>PF9814</b>
<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>	<b>Diesel Exhaust Fluid</b> (2880298).. <b>PE17000</b>	<b>Fuel/Water Separator Spin-on</b> (3331096)..... <b>BF1274-SP</b>
<b>Crankcase Breather</b> (3685528)... <b>CV15000</b>	122SD w/Cummins ISX 15.0 (14.9L) Eng. (2015)	<b>Fuel</b> (Fleetguard FF5686)..... <b>BF9860 +</b>
<b>Coolant</b> (Fleetguard WF2126)..... <b>BW5086</b>	<b>11 7/8 In. Dual-Flow Lube</b> (3406809)..... <b>BD7154 +</b>	<b>Fuel</b> (Fleetguard FF2200)..... <b>BF7766</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>14 In. Dual-Flow Lube</b> (3406810)..... <b>BD7153 +</b>	<b>Radial Seal Air</b> (Standard) (Don. P535717)..... <b>RS3518</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>	<b>Radial Seal XP Air</b> (Upgrade) (Don. P535717)..... <b>RS3518XP</b>
<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19763)..... <b>PF7928</b>	<b>EnduraCube Air</b> (3-36867-010)... <b>[2] PA32002</b>
<b>Steering</b> (T1808D)..... <b>BT9388</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19764)..... <b>PF9814</b>	<b>Cab Air</b> (91559)..... <b>PA4857</b>
<b>Some Rear Axle</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Fuel/Water Separator Spin-on</b> (3331096)..... <b>BF1274-SP</b>	<b>Cab Air</b> (BOA91621)..... <b>PA5773</b>
<b>Diesel Exhaust Fluid</b> (2880298).. <b>PE17000</b>	<b>Fuel</b> (Fleetguard FF5686)..... <b>BF9860 +</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>
122SD w/Cummins ISX 15.0 (14.9L) Eng. (2014)	<b>Fuel/Water Separator Spin-on</b> (3331096)..... <b>BF1274-SP</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
<b>11 7/8 In. Dual-Flow Lube</b> (3406809)..... <b>BD7154 +</b>	<b>Fuel</b> (Fleetguard FF5686)..... <b>BF9860 +</b>	<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>
<b>14 In. Dual-Flow Lube</b> (3406810)..... <b>BD7153 +</b>	<b>Fuel</b> (Fleetguard FF2200)..... <b>BF7766</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>
<b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>	<b>Radial Seal Air</b> (Standard) (Don. P535717)..... <b>RS3518</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>
<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19763)..... <b>PF7928</b>	<b>Radial Seal XP Air</b> (Upgrade) (Don. P535717)..... <b>RS3518XP</b>	<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>
<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19764)..... <b>PF9814</b>	<b>EnduraCube Air</b> (3-36867-010)... <b>[2] PA32002</b>	<b>Crankcase Breather</b> (3685528)... <b>CV15000</b>
<b>Fuel/Water Separator Spin-on</b> (3331096)..... <b>BF1274-SP</b>	<b>Cab Air</b> (91559)..... <b>PA4857</b>	<b>Coolant</b> (Fleetguard WF2126)..... <b>BW5086</b>
<b>Fuel</b> (Fleetguard FF5686)..... <b>BF9860 +</b>	<b>Cab Air</b> (BOA91621)..... <b>PA5773</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Fuel</b> (Fleetguard FF2200)..... <b>BF7766</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Radial Seal Air</b> (Standard) (Don. P535717)..... <b>RS3518</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>
<b>Radial Seal XP Air</b> (Upgrade) (Don. P535717)..... <b>RS3518XP</b>	<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>	<b>Steering</b> (T1808D)..... <b>BT9388</b>
<b>EnduraCube Air</b> (3-36867-010)... <b>[2] PA32002</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Some Rear Axle</b> (Meritor 3280-V-8394)..... <b>B233</b>
<b>Cab Air</b> (91559)..... <b>PA4857</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Diesel Exhaust Fluid</b> (2880298).. <b>PE17000</b>
<b>Cab Air</b> (BOA91621)..... <b>PA5773</b>	<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>	122SD w/Cummins ISX 15.0 (14.9L) Eng. (2017)
<b>Cab Air</b> (36000006)..... <b>PA5359</b>	<b>Crankcase Breather</b> (3685528)... <b>CV15000</b>	<b>11 7/8 In. Dual-Flow Lube</b> (3406809)..... <b>BD7154 +</b>
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Coolant</b> (Fleetguard WF2126)..... <b>BW5086</b>	
	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
122SD w/Cummins ISX 15.0 (14.9L) Eng. (2017) (Cont'd)	122SD w/Cummins ISX 15.0 (14.9L) Eng. (2018) (Cont'd)	122SD w/Cummins X15 (14.9L) Eng. (2018) (Cont'd)
<b>14 In. Dual-Flow Lube</b> (3406810)..... <b>BD7153 +</b>	<b>Coolant Spin-on</b> (Fleetguard WF2127)..... <b>B5087</b>	<b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>
<b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	122SD w/Cummins X15 (14.9L) Eng. (2019)
<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19763)..... <b>PF7928</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	<b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b>
<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19764)..... <b>PF9814</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>Fuel/Water Separator</b> (Alliance ABPN122R50550)..... <b>BF9871-O</b>
<b>Fuel/Water Separator Spin-on</b> (3331096)..... <b>BF1274-SP</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Fuel</b> (5365988)..... <b>BF46129 +</b>
<b>Fuel</b> (Fleetguard FF5686)..... <b>BF9860 +</b>	<b>Steering</b> (1417927000)..... <b>PT23629</b>	<b>EnduraCube Air</b> (Don. P616380) <b>PA32002</b>
<b>Fuel</b> (Fleetguard FF2200)..... <b>BF7766</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	<b>Cab Air</b> (Fresh Air) (ABPN10G36000006)..... <b>PA5359</b>
<b>Radial Seal Air</b> (Standard) (Don. P535717)..... <b>RS3518</b>	<b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>	<b>Cab Air</b> (Recirculation Air) (ABPN10G91621)..... <b>PA5773</b>
<b>Radial Seal XP Air</b> (Upgrade) (Don. P535717)..... <b>RS3518XP</b>	122SD w/Cummins ISX 15.0 (14.9L) Eng. (2019)	<b>Air Dryer</b> (Wabco R950068A)..... <b>BA5379 +</b>
<b>EnduraCube Air</b> (3-36867-010).... <b>[2] PA32002</b>	<b>Lube</b> (4367100)..... <b>BD50000</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>
<b>Cab Air</b> (91559)..... <b>PA4857</b>	<b>Fuel</b> (5365988)..... <b>BF46129</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>
<b>Cab Air</b> (BOA91621)..... <b>PA5773</b>	<b>EnduraCube Air</b> (336867010).... <b>PA32002</b>	<b>Steering</b> (1417927000)..... <b>PT23629</b>
<b>Cab Air</b> (36000006)..... <b>PA5359</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Air Dryer</b> (Wabco R950068A)..... <b>BA5379 +</b>	122SD w/Cummins X15 (14.9L) Eng. (2020)
<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>	<b>Trans.</b> (Fuller 4304827)..... <b>BT223</b>	<b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b>
<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Steering</b> (1417927000)..... <b>PT23629</b>	<b>Fuel/Water Separator</b> (Fleetguard FS19915)..... <b>PF9804</b>
<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	<b>Fuel</b> (5365988)..... <b>BF46129</b>
<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>	122SD w/Cummins ISX 15.0 (14.9L) Eng. (2020)	<b>EnduraCube Air</b> (336867010).... <b>PA32002</b>
<b>Crankcase Breather</b> (3685528).... <b>CV15000</b>	<b>Dual-Flow Lube</b> (Fleetguard LF14000NN)..... <b>BD50000</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>
<b>Coolant</b> (Fleetguard WF2126)..... <b>BW5086</b>	<b>Fuel/Water Separator</b> (Alliance ABPN122R50550)..... <b>BF9871-O</b>	<b>Air Dryer</b> (Wabco R950068A)..... <b>BA5379 +</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Fuel Spin-on</b> (Standard) (Fleetguard FF5776)..... <b>BF9885 +</b>	<b>Trans.</b> (Fuller 4304827)..... <b>BT223</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Fuel Spin-on</b> (Upgrade) (Fleetguard FF5825NN)..... <b>BF46129</b>	<b>Steering</b> (1417927000)..... <b>PT23629</b>
<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>EnduraCube Air</b> (336867010).... <b>PA32002</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
<b>Steering</b> (T1808D)..... <b>BT9388</b>	<b>Cab Air</b> (N10G36000006)..... <b>PA5359</b>	122SD w/Cummins X15 (14.9L) Eng. (2021)
<b>Some Rear Axle</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Air Dryer</b> (Wabco R950068)..... <b>BA5379 +</b>	<b>Lube</b> (5575298)..... <b>B40145</b>
<b>Diesel Exhaust Fluid</b> (2880298).. <b>PE17000</b>	<b>Crankcase Breather</b> (Fleetguard CV50634)..... <b>CV15000</b>	<b>Fuel/Water Separator</b> (Fleetguard FS19915)..... <b>PF9804</b>
122SD w/Cummins ISX 15.0 (14.9L) Eng. (2018)	<b>Coolant Spin-on</b> (Fleetguard WF2127)..... <b>B5087</b>	<b>Fuel</b> (5365988)..... <b>BF46129</b>
<b>Dual-Flow Lube</b> (Fleetguard LF14000NN)..... <b>BD50000</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	<b>EnduraCube Air</b> (336867010).... <b>PA32002</b>
<b>Fuel/Water Separator</b> (Alliance ABPN122R50550)..... <b>BF9871-O</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>
<b>Fuel Spin-on</b> (Standard) (Fleetguard FF5776)..... <b>BF9885 +</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b>
<b>Fuel Spin-on</b> (Upgrade) (Fleetguard FF5825NN)..... <b>BF46129</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Trans.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>
<b>EnduraCube Air</b> (336867010).... <b>PA32002</b>	<b>Steering</b> (1417927000)..... <b>PT23629</b>	<b>Trans.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>
<b>Cab Air</b> (N10G36000006)..... <b>PA5359</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	<b>Steering</b> (1417927000)..... <b>PT23629</b>
<b>Air Dryer</b> (Wabco R950068)..... <b>BA5379 +</b>	122SD w/Detroit DD13 (12.8L) Eng. (2013)	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
<b>Crankcase Breather</b> (Fleetguard CV50634)..... <b>CV15000</b>	<b>Lube</b> (A4731800109)..... <b>P7505</b>	<b>Fuel Kit</b> (2 Filter Kit) (A4720900651)..... <b>PF9908 KIT</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
122SD w/Detroit DD13 (12.8L) Eng. (2013) (Cont'd)	122SD w/Detroit DD13 (12.8L) Eng. (2015) (Cont'd)	122SD w/Detroit DD13 (12.8L) Eng. (2017) (Cont'd)
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>	<b>Cab Air</b> (BOA91559)..... <b>PA4857</b>
<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>
<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>
<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>	<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>	<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>
<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Steering</b> (T1808D)..... <b>BT9388</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Some Rear Axle</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Steering</b> (T1808D)..... <b>BT9388</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>
<b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b>	<b>Some Rear Axle</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Steering</b> (T1808D)..... <b>BT9388</b>
122SD w/Detroit DD13 (12.8L) Eng. (2014)	<b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b>	<b>Some Rear Axle</b> (Meritor 3280-V-8394)..... <b>B233</b>
<b>Lube</b> (A4731800109)..... <b>P7505</b>	122SD w/Detroit DD13 (12.8L) Eng. (2016)	<b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b>
<b>Fuel Kit</b> (2 Filter Kit) (A4720900651)..... <b>PF9908 KIT</b>	<b>Lube</b> (A4731800109)..... <b>P7505</b>	122SD w/Detroit DD13 (12.8L) Eng. (2018)
<b>Fuel Kit</b> (3 Filter Kit) (A0000904251)..... <b>PF9924 KIT</b>	<b>Fuel Kit</b> (2 Filter Kit) (A4720900651)..... <b>PF9908 KIT</b>	<b>Lube</b> (A4731800409)..... <b>P7505</b>
<b>EnduraCube Air</b> (336867010)..... <b>[2] PA32002</b>	<b>Fuel Kit</b> (3 Filter Kit) (A0000904251)..... <b>PF9924 KIT</b>	<b>Fuel/Water Separator</b> (A0000905051)..... <b>PF46145</b>
<b>Cab Air</b> (BOA91559)..... <b>PA4857</b>	<b>EnduraCube Air</b> (336867010)..... <b>[2] PA32002</b>	<b>Fuel/Water Separator</b> (Racor R61709)..... <b>PF46235</b>
<b>Cab Air</b> (36000006)..... <b>PA5359</b>	<b>Cab Air</b> (BOA91559)..... <b>PA4857</b>	<b>Fuel</b> (A4720900651)..... <b>PF9908 KIT</b>
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>	<b>EnduraCube Air</b> (336867010)..... <b>PA32002</b>
<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>
<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Air Dryer</b> (Wabco R950068)..... <b>BA5379</b>
<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Trans.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>
<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>	<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>	<b>Trans.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>	<b>Steering</b> (1417927000)..... <b>PT23629</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b>
<b>Steering</b> (T1808D)..... <b>BT9388</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	122SD w/Detroit DD13 (12.8L) Eng. (2019)
<b>Some Rear Axle</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Steering</b> (T1808D)..... <b>BT9388</b>	<b>Lube</b> (A4731800409)..... <b>P7505</b>
<b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b>	<b>Some Rear Axle</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Fuel/Water Separator</b> (A0000905051)..... <b>PF46145</b>
122SD w/Detroit DD13 (12.8L) Eng. (2015)	<b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b>	<b>Fuel Kit</b> (A4720900651)..... <b>PF9908 KIT</b>
<b>Lube</b> (A4731800109)..... <b>P7505</b>	122SD w/Detroit DD13 (12.8L) Eng. (2017)	<b>EnduraCube Air</b> (Don. P616380) <b>PA32002</b>
<b>Fuel Kit</b> (2 Filter Kit) (A4720900651)..... <b>PF9908 KIT</b>	<b>Lube</b> (A4731800109)..... <b>P7505</b>	<b>Cab Air</b> (Fresh Air) (ABPN10G36000006)..... <b>PA5359</b>
<b>Fuel Kit</b> (3 Filter Kit) (A0000904251)..... <b>PF9924 KIT</b>	<b>Fuel Kit</b> (2 Filter Kit) (A4720900651)..... <b>PF9908 KIT</b>	<b>Cab Air</b> (Recirculation Air) (ABPN10G91621)..... <b>PA5773</b>
<b>EnduraCube Air</b> (336867010)..... <b>[2] PA32002</b>	<b>Fuel Kit</b> (3 Filter Kit) (A0000904251)..... <b>PF9924 KIT</b>	<b>Air Dryer</b> (Wabco R950068A)..... <b>BA5379 +</b>
<b>Cab Air</b> (BOA91559)..... <b>PA4857</b>	<b>EnduraCube Air</b> (336867010)..... <b>[2] PA32002</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>
		<b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>
		<b>Steering</b> (1417927000)..... <b>PT23629</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
122SD w/Detroit DD13 (12.8L) Eng. (2019) (Cont'd) <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b>	122SD w/Detroit DD15 (14.8L) Eng. (2013) <b>Lube</b> (A4731800109)..... <b>P7505</b> <b>Fuel/Water Separator</b> (A0000903651)..... <b>PF9804</b> <b>Fuel</b> (2 Filter Kit) (A4720900651). <b>PF9908 KIT</b> <b>Fuel</b> (3 Filter Kit) (A0000904251). <b>PF9924 KIT</b> <b>EnduraCube Air</b> (336867010).... <b>[2] PA32002</b> <b>Cab Air</b> (ABPN10G36000006).... <b>PA5359</b> <b>Cab Air</b> (BOA91559)..... <b>PA4857</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b> <b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b> <b>Coolant</b> (A4722030255)..... <b>P5092</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Steering</b> (T1808D)..... <b>BT9388</b> <b>Some Rear Axle</b> (Meritor 3280-V-8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b> <b>Diesel Exhaust Fluid</b> (A0001420289)..... <b>PE5272</b>	122SD w/Detroit DD15 (14.8L) Eng. (2014) (Cont'd) <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Steering</b> (T1808D)..... <b>BT9388</b> <b>Some Rear Axle</b> (Meritor 3280-V-8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b> <b>Diesel Exhaust Fluid</b> (A0001420289)..... <b>PE5272</b>
122SD w/Detroit DD13 (12.8L) Eng. (2020) <b>Lube</b> (To Eng. S/N A472910S0690710) (A4731800409)..... <b>P7505</b> <b>Fuel/Water Separator</b> (A0000905051)..... <b>PF46145</b> <b>Fuel</b> (A4700903151)..... <b>PF9908 KIT</b> <b>EnduraCube Air</b> (336867010).... <b>PA32002</b> <b>Cab Air</b> (36000006)..... <b>PA5359</b> <b>Air Dryer</b> (Wabco R950068A)..... <b>BA5379 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b>	122SD w/Detroit DD15 (14.8L) Eng. (2014) <b>Lube</b> (A4731800109)..... <b>P7505</b> <b>Fuel/Water Separator</b> (A0000903651)..... <b>PF9804</b> <b>Fuel</b> (2 Filter Kit) (A4720900651). <b>PF9908 KIT</b> <b>Fuel</b> (3 Filter Kit) (A0000904251). <b>PF9924 KIT</b> <b>EnduraCube Air</b> (336867010).... <b>[2] PA32002</b> <b>Cab Air</b> (ABPN10G36000006).... <b>PA5359</b> <b>Cab Air</b> (BOA91559)..... <b>PA4857</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b> <b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b> <b>Coolant</b> (A4722030255)..... <b>P5092</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Steering</b> (T1808D)..... <b>BT9388</b> <b>Some Rear Axle</b> (Meritor 3280-V-8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b> <b>Diesel Exhaust Fluid</b> (A0001420289)..... <b>PE5272</b>	122SD w/Detroit DD15 (14.8L) Eng. (2015) <b>Lube</b> (A4731800109)..... <b>P7505</b> <b>Fuel/Water Separator</b> (A0000903651)..... <b>PF9804</b> <b>Fuel</b> (2 Filter Kit) (A4720900651). <b>PF9908 KIT</b> <b>Fuel</b> (3 Filter Kit) (A0000904251). <b>PF9924 KIT</b> <b>EnduraCube Air</b> (336867010).... <b>[2] PA32002</b> <b>Cab Air</b> (ABPN10G36000006).... <b>PA5359</b> <b>Cab Air</b> (BOA91559)..... <b>PA4857</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b> <b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b> <b>Coolant</b> (A4722030255)..... <b>P5092</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Steering</b> (T1808D)..... <b>BT9388</b> <b>Some Rear Axle</b> (Meritor 3280-V-8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b> <b>Diesel Exhaust Fluid</b> (A0001420289)..... <b>PE5272</b>
122SD w/Detroit DD13 (12.8L) Eng. (2021) <b>Fuel/Water Separator</b> (A0000905051)..... <b>PF46145</b> <b>Fuel</b> (A4700903151)..... <b>PF9908 KIT</b> <b>EnduraCube Air</b> (336867010).... <b>PA32002</b> <b>Cab Air</b> (36000006)..... <b>PA5359</b> <b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b>	122SD w/Detroit DD15 (14.8L) Eng. (2014) <b>Lube</b> (A4731800109)..... <b>P7505</b> <b>Fuel/Water Separator</b> (A0000903651)..... <b>PF9804</b> <b>Fuel</b> (2 Filter Kit) (A4720900651). <b>PF9908 KIT</b> <b>Fuel</b> (3 Filter Kit) (A0000904251). <b>PF9924 KIT</b> <b>EnduraCube Air</b> (336867010).... <b>[2] PA32002</b> <b>Cab Air</b> (ABPN10G36000006).... <b>PA5359</b> <b>Cab Air</b> (BOA91559)..... <b>PA4857</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b> <b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b> <b>Coolant</b> (A4722030255)..... <b>P5092</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	122SD w/Detroit DD15 (14.8L) Eng. (2016) <b>Lube</b> (A4731800109)..... <b>P7505</b> <b>Fuel/Water Separator</b> (A0000903651)..... <b>PF9804</b> <b>Fuel</b> (2 Filter Kit) (A4720900651). <b>PF9908 KIT</b> <b>Fuel</b> (3 Filter Kit) (A0000904251). <b>PF9924 KIT</b> <b>EnduraCube Air</b> (336867010).... <b>[2] PA32002</b> <b>Cab Air</b> (ABPN10G36000006).... <b>PA5359</b> <b>Cab Air</b> (BOA91559)..... <b>PA4857</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
122SD w/Detroit DD13 (12.8L) Eng. (2022) <b>Fuel/Water Separator</b> (Racor R61709)..... <b>PF46235</b> <b>Fuel</b> (A4700903151)..... <b>PF9908 KIT</b> <b>Channel Flow EXO Air</b> (Don. P634517)..... <b>CA30132</b> <b>Cab Air</b> (ABPN10G36000006).... <b>PA5359</b> <b>Trans.</b> (2 In. Kit) (Allison 29558328)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29558329)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
122SD w/Detroit DD15 (14.8L) Eng. (2016) (Cont'd)	122SD w/Detroit DD15 (14.8L) Eng. (2017) (Cont'd)	122SD w/Detroit DD15 (14.8L) Eng. (2021) (Cont'd)
<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Diesel Exhaust Fluid</b> (A0001420289)..... <b>PE5272</b>	<b>EnduraCube Air</b> (336867010)..... <b>PA32002</b>
<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	122SD w/Detroit DD15 (14.8L) Eng. (2018)	<b>Cab Air</b> (36000006)..... <b>PA5359</b>
<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>	<b>Lube</b> (A4731800409)..... <b>P7505</b>	<b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b>
<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>	<b>Fuel/Water Separator</b> (A4720921205)..... <b>PF9804</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>
<b>Coolant</b> (A4722030255)..... <b>P5092</b>	<b>Fuel</b> (A4720900651)..... <b>PF9908 KIT</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>EnduraCube Air</b> (336867010)..... <b>PA32002</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2</b>
<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>Air Dryer</b> (Wabco R950068)..... <b>BA5379</b>	<b>Steering</b> (1417927000)..... <b>PT23629</b>
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Trans.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
<b>Steering</b> (1417927000)..... <b>PT23629</b>	<b>Trans.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	<b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b>
<b>Steering</b> (T1808D)..... <b>BT9388</b>	<b>Steering</b> (1417927000)..... <b>PT23629</b>	122SD w/Detroit DD15 (14.8L) Eng. (2022)
<b>Some Rear Axle</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	<b>Fuel/Water Separator</b> (A0000905051)..... <b>PF46145</b>
<b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b>	<b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b>	<b>Channel Flow EXO Air</b> (Don. P634517)..... <b>CA30132</b>
<b>Diesel Exhaust Fluid</b> (A0001420289)..... <b>PE5272</b>	122SD w/Detroit DD15 (14.8L) Eng. (2019)	<b>Cab Air</b> (ABPN10G36000006)..... <b>PA5359</b>
122SD w/Detroit DD15 (14.8L) Eng. (2017)	<b>Lube</b> (A4731800109)..... <b>P7505</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2</b>
<b>Lube</b> (A4731800109)..... <b>P7505</b>	<b>Fuel/Water Separator</b> (A0000905051)..... <b>PF46145</b>	<b>Steering</b> (1417927000)..... <b>PT23629</b>
<b>Fuel/Water Separator</b> (A0000903651)..... <b>PF9804</b>	<b>Fuel Kit</b> (A4720900651)..... <b>PF9908 KIT</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
<b>Fuel</b> (2 Filter Kit) (A4720900651)..... <b>PF9908 KIT</b>	<b>EnduraCube Air</b> (Don. P616380) <b>PA32002</b>	122SD w/Detroit DD16 (15.6L) Eng. (2013)
<b>Fuel</b> (3 Filter Kit) (A0000904251)..... <b>PF9924 KIT</b>	<b>Cab Air</b> (Fresh Air) (ABPN10G36000006)..... <b>PA5359</b>	<b>Lube</b> (A4731800409)..... <b>P7505</b>
<b>EnduraCube Air</b> (336867010)..... <b>[2] PA32002</b>	<b>Cab Air</b> (Recirculation Air) (ABPN10G91621)..... <b>PA5773</b>	<b>Fuel/Water Separator</b> (A0000903651)..... <b>PF9804</b>
<b>Cab Air</b> (ABPN10G36000006)..... <b>PA5359</b>	<b>Air Dryer</b> (Wabco R950068A)..... <b>BA5379 +</b>	<b>Fuel</b> (2 Filter Kit) (A4720900651)..... <b>PF9908 KIT</b>
<b>Cab Air</b> (BOA91559)..... <b>PA4857</b>	<b>Trans.</b> (Fuller 4304827)..... <b>BT223</b>	<b>Fuel</b> (3 Filter Kit) (A0000904251)..... <b>PF9924 KIT</b>
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Steering</b> (1417927000)..... <b>PT23629</b>	<b>EnduraCube Air</b> (336867010)..... <b>[2] PA32002</b>
<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	<b>Cab Air</b> (ABPN10G36000006)..... <b>PA5359</b>
<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b>	<b>Cab Air</b> (BOA91559)..... <b>PA4857</b>
<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>	122SD w/Detroit DD15 (14.8L) Eng. (2020)	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>	<b>Lube</b> (To Eng. S/N A472910S0690710) (A4731800409)..... <b>P7505</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>
<b>Coolant</b> (A4722030255)..... <b>P5092</b>	<b>Fuel/Water Separator</b> (A0000905051)..... <b>PF46145</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Fuel</b> (A4700903151)..... <b>PF9908 KIT</b>	<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>EnduraCube Air</b> (336867010)..... <b>PA32002</b>	<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>
<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>	<b>Coolant</b> (A4722030255)..... <b>P5092</b>
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Air Dryer</b> (Wabco R950068A)..... <b>BA5379 +</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Steering</b> (1417927000)..... <b>PT23629</b>	<b>Trans.</b> (Fuller 4304827)..... <b>BT223</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Steering</b> (T1808D)..... <b>BT9388</b>	<b>Steering</b> (1417927000)..... <b>PT23629</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>
<b>Some Rear Axle</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
<b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b>	<b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b>	<b>Steering</b> (1417927000)..... <b>PT23629</b>
122SD w/Detroit DD15 (14.8L) Eng. (2021)	122SD w/Detroit DD15 (14.8L) Eng. (2021)	<b>Steering</b> (T1808D)..... <b>BT9388</b>
<b>Fuel/Water Separator</b> (A0000905051)..... <b>PF46145</b>	<b>Fuel/Water Separator</b> (A0000905051)..... <b>PF46145</b>	<b>Some Rear Axle</b> (Meritor 3280-V-8394)..... <b>B233</b>
<b>Fuel</b> (A4700903151)..... <b>PF9908 KIT</b>	<b>Fuel</b> (A4700903151)..... <b>PF9908 KIT</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
122SD w/Detroit DD16 (15.6L) Eng. (2013) (Cont'd) <b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b>	122SD w/Detroit DD16 (15.6L) Eng. (2015) (Cont'd) <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Steering</b> (T1808D)..... <b>BT9388</b> <b>Some Rear Axle</b> (Meritor 3280-V-8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b>	122SD w/Detroit DD16 (15.6L) Eng. (2017) (Cont'd) <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374+</b> <b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374+</b> <b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379+</b> <b>Coolant</b> (A4722030255)..... <b>P5092</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Steering</b> (T1808D)..... <b>BT9388</b> <b>Some Rear Axle</b> (Meritor 3280-V-8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b>
122SD w/Detroit DD16 (15.6L) Eng. (2014) <b>Lube</b> (A4731800409)..... <b>P7505</b> <b>Fuel/Water Separator</b> (A0000903651)..... <b>PF9804</b> <b>Fuel</b> (2 Filter Kit) (A4720900651). <b>PF9908 KIT</b> <b>Fuel</b> (3 Filter Kit) (A0000904251). <b>PF9924 KIT</b> <b>EnduraCube Air</b> (336867010)..... <b>[2] PA32002</b> <b>Cab Air</b> (ABPN10G36000006)..... <b>PA5359</b> <b>Cab Air</b> (BOA91559)..... <b>PA4857</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374+</b> <b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374+</b> <b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379+</b> <b>Coolant</b> (A4722030255)..... <b>P5092</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Steering</b> (T1808D)..... <b>BT9388</b> <b>Some Rear Axle</b> (Meritor 3280-V-8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b>	122SD w/Detroit DD16 (15.6L) Eng. (2016) <b>Lube</b> (A4731800409)..... <b>P7505</b> <b>Fuel/Water Separator</b> (A0000903651)..... <b>PF9804</b> <b>Fuel</b> (2 Filter Kit) (A4720900651). <b>PF9908 KIT</b> <b>Fuel</b> (3 Filter Kit) (A0000904251). <b>PF9924 KIT</b> <b>EnduraCube Air</b> (336867010)..... <b>[2] PA32002</b> <b>Cab Air</b> (ABPN10G36000006)..... <b>PA5359</b> <b>Cab Air</b> (BOA91559)..... <b>PA4857</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374+</b> <b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374+</b> <b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379+</b> <b>Coolant</b> (A4722030255)..... <b>P5092</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Steering</b> (T1808D)..... <b>BT9388</b> <b>Some Rear Axle</b> (Meritor 3280-V-8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b>	122SD w/Detroit DD16 (15.6L) Eng. (2018) <b>Lube</b> (A4731800109)..... <b>P7505</b> <b>Fuel/Water Separator</b> (A0000903651)..... <b>PF9804</b> <b>Fuel</b> (A4720900651)..... <b>PF9908 KIT</b> <b>EnduraCube Air</b> (336867010)..... <b>PA32002</b> <b>Cab Air</b> (36000006)..... <b>PA5359</b> <b>Air Dryer</b> (Wabco R950068)..... <b>BA5379</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b>
122SD w/Detroit DD16 (15.6L) Eng. (2015) <b>Lube</b> (A4731800409)..... <b>P7505</b> <b>Fuel/Water Separator</b> (A0000903651)..... <b>PF9804</b> <b>Fuel</b> (2 Filter Kit) (A4720900651). <b>PF9908 KIT</b> <b>Fuel</b> (3 Filter Kit) (A0000904251). <b>PF9924 KIT</b> <b>EnduraCube Air</b> (336867010)..... <b>[2] PA32002</b> <b>Cab Air</b> (ABPN10G36000006)..... <b>PA5359</b> <b>Cab Air</b> (BOA91559)..... <b>PA4857</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374+</b> <b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374+</b> <b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379+</b> <b>Coolant</b> (A4722030255)..... <b>P5092</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	122SD w/Detroit DD16 (15.6L) Eng. (2017) <b>Lube</b> (A4731800409)..... <b>P7505</b> <b>Fuel/Water Separator</b> (A0000903651)..... <b>PF9804</b> <b>Fuel</b> (2 Filter Kit) (A4720900651). <b>PF9908 KIT</b> <b>Fuel</b> (3 Filter Kit) (A0000904251). <b>PF9924 KIT</b> <b>EnduraCube Air</b> (336867010)..... <b>[2] PA32002</b> <b>Cab Air</b> (ABPN10G36000006)..... <b>PA5359</b> <b>Cab Air</b> (BOA91559)..... <b>PA4857</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	122SD w/Detroit DD16 (15.6L) Eng. (2019) <b>Lube</b> (A4731800109)..... <b>P7505</b> <b>Fuel/Water Separator</b> (A0000905051)..... <b>PF46145</b> <b>Fuel Kit</b> (A4720900651)..... <b>PF9908 KIT</b> <b>EnduraCube Air</b> (Don. P616380) <b>PA32002</b> <b>Cab Air</b> (Fresh Air) (ABPN10G36000006)..... <b>PA5359</b> <b>Cab Air</b> (Recirculation Air) (ABPN10G91621)..... <b>PA5773</b> <b>Air Dryer</b> (Wabco R950068A)..... <b>BA5379+</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b>
		122SD w/Detroit DD16 (15.6L) Eng. (2020) <b>Lube</b> (To Eng. S/N A472910S0690710) (A4731800409)..... <b>P7505</b> <b>Fuel/Water Separator</b> (A0000905051)..... <b>PF46145</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).




FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
122SD w/Detroit DD16 (15.6L) Eng. (2020) (Cont'd)	Argosy w/Cat C10 Eng. (Cont'd)	Argosy w/Cat C15 Eng. (To 01/2004) (Cont'd)
Fuel (A4700903151)..... PF9908 KIT	<b>B-P Lube</b> (1W8845)..... B7577	<b>Cab Air</b> (8 5/8 In.) (22-46891-000)..... PA5722
EnduraCube Air (336867010).... PA32002	<b>Fuel/Water Separator</b> (Alliance ABPN122R50551)..... BF46016-O	<b>Cab Air</b> (10 19/32 In.) (22-44665-000)..... PA5319
<b>Cab Air</b> (36000006)..... PA5359	<b>S. Fuel</b> (1R0712)..... BF614 +	<b>Air Dryer</b> (AD-IS System) (Bendix 109994)..... BA5374 +
<b>Air Dryer</b> (Wabco R950068A)..... BA5379	<b>Radial Seal Air</b> (Standard) (Don. P535717)..... RS3518	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... BA5377
<b>Coolant</b> (A4722030355)..... P5092	<b>Radial Seal XP Air</b> (Upgrade) (Don. P535717)..... RS3518XP	<b>Coolant</b> (Fleetguard WF2077)..... B5134 +
<b>Trans.</b> (Fuller 4304827)..... BT223	Argosy w/Cat C12 Eng. (New Zealand)	<b>Trans.</b> (Fuller 4304827)..... BT223
<b>Steering</b> (1417927000)..... PT23629	<b>Lube</b> (1R0716)..... B99 +	<b>Steering</b> (Nelson 87904M)..... PT9354-MPG
<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... B233	<b>Fuel/Water Separator</b> (Fleetguard FS1212)..... BF1212 +	<b>Rear Axle</b> (Meritor 3280-V-8394). B233
<b>Diesel Exhaust Fluid</b> (A0001421089)..... PE17002 KIT	<b>Fuel</b> (1R0749)..... BF7587 +	Argosy w/Cat C15 Eng. (01/2004-on)
122SD w/Detroit DD16 (15.6L) Eng. (2021)	<b>Radial Seal Air</b> (Standard) (Don. P185069)..... RS3518	<b>Lube</b> (1R1808)..... B7299 +
<b>Fuel/Water Separator</b> (A0000905051)..... PF46145	<b>Radial Seal XP Air</b> (Upgrade) (Don. P185069)..... RS3518XP	<b>Fuel/Water Separator</b> (Fleetguard FS1212)..... BF1212 +
<b>Fuel</b> (A4700903151)..... PF9908 KIT	<b>Air Dryer</b> (Bendix 107796)..... BA5377	<b>Fuel/Water Separator</b> (Racor RAI32FRT02)..... BF1279
EnduraCube Air (336867010).... PA32002	<b>Coolant</b> (Fleetguard WF2077)..... B5134 +	<b>Fuel</b> (1R0749)..... BF7587 +
<b>Cab Air</b> (36000006)..... PA5359	<b>Trans.</b> (Fuller 4304827)..... BT223	<b>Radial Seal Air</b> (Standard) (Don. P185069)..... RS3518
<b>Air Dryer</b> (Wabco R950011)..... BA5374 +	<b>Steering</b> (Nelson 87904A)..... PT9354-MPG	<b>Radial Seal XP Air</b> (Upgrade) (Don. P185069)..... RS3518XP
<b>Trans. Spin-on</b> (Fuller 4304827).. BT223	<b>Rear Axle</b> (Meritor 3280-V-8394). B233	<b>Cab Air</b> (8 5/8 In.) (22-46891-000)..... PA5722
<b>Steering</b> (1417927000)..... PT23629	Argosy w/Cat C12 Eng. (North America)	<b>Cab Air</b> (10 19/32 In.) (22-44665-000)..... PA5319
<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... B233	<b>F-F Lube</b> (1R0716)..... B99 +	<b>Air Dryer</b> (AD-IS System) (Bendix 109994)..... BA5374 +
<b>Diesel Exhaust Fluid</b> (A0001421089)..... PE17002 KIT	<b>B-P Lube</b> (1W8845)..... B7577	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... BA5377
122SD w/Detroit DD16 (15.6L) Eng. (2022)	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... PF7680	<b>Coolant</b> (Fleetguard WF2077)..... B5134 +
<b>Fuel</b> (A4700903151)..... PF9908 KIT	<b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1212)..... BF1212 +	<b>Trans.</b> (Fuller 4304827)..... BT223
<b>Channel Flow EXO Air</b> (Don. P634517)..... CA30132	<b>Fuel/Water Separator Spin-on</b> (Alliance ABPN122R50551)..... BF46016-O	<b>Steering</b> (Nelson 87904M)..... PT9354-MPG
<b>Cab Air</b> (ABPN10G36000006).... PA5359	<b>Fuel Spin-on</b> (Std. Efficiency) (1R0712)..... BF614 +	<b>Rear Axle</b> (Meritor 3280-V-8394). B233
<b>Trans.</b> (Fuller 4304827)..... BT223	<b>Fuel Spin-on</b> (High Efficiency) (1R0749)..... BF7587 +	Argosy w/Cat C16 Eng. (To 1/2004)
<b>Steering</b> (1417927000)..... PT23629	<b>Radial Seal Air</b> (Standard) (Don. P185069)..... RS3518	<b>Lube</b> (1R0716)..... B99 +
<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... B233	<b>Radial Seal XP Air</b> (Upgrade) (Don. P185069)..... RS3518XP	<b>Fuel/Water Separator</b> (Alliance ABPN122R50551)..... BF46016-O
Argosy w/Cat 3126 (7.2L) Eng.	<b>Cab Air</b> (22-44665-000)..... PA5319	<b>Fuel/Water Separator</b> (311365).... BF1212 +
<b>Lube</b> (Standard Vers.) (1R0739).. B76	<b>Air Dryer</b> (AD-IS, AD-SP System) (Bendix 109994)..... BA5374 +	<b>Fuel</b> (Std. Efficiency) (1R0712).... BF614 +
<b>Suction Line Fuel/Water Separator</b> (175-2949)..... BF1268	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... BA5373	<b>Fuel</b> (High Efficiency) (1R0749).... BF7587 +
<b>Fuel/Water Separator</b> (256-8753)..... BF1259	<b>Coolant</b> (Fleetguard WF2077)..... B5134 +	<b>Radial Seal Air</b> (Standard) (Don. P535717)..... RS3518
<b>Fuel</b> (1R0751)..... BF7632	<b>Trans.</b> (Fuller 4304827)..... BT223	<b>Radial Seal XP Air</b> (Upgrade) (Don. P535717)..... RS3518XP
Argosy w/Cat 3406 Eng.	<b>Steering</b> (Nelson 87904A)..... PT9354-MPG	Argosy w/Cat C16 Eng. (1/2004-on)
<b>Lube</b> (Std. Version) (1R0716)..... B99 +	Argosy w/Cat C15 Eng. (To 01/2004)	<b>Lube</b> (1R1808)..... B7299 +
<b>Lube</b> (High Efficiency) (1R1808).. B7299 +	<b>Lube</b> (1R0716)..... B99 +	<b>Fuel/Water Separator</b> (Alliance ABPN122R50551)..... BF46016-O
<b>Fuel/Water Separator</b> (Alliance ABPN122R50551)..... BF46016-O	<b>Fuel/Water Separator</b> (Fleetguard FS1212)..... BF1212 +	<b>Fuel/Water Separator</b> (311365).... BF1212 +
<b>Fuel/Water Separator</b> (256-8753)..... BF1259	<b>Fuel/Water Separator</b> (Racor RAI32FRT02)..... BF1279	<b>Fuel</b> (Std. Efficiency) (1R0712).... BF614 +
<b>P. Fuel Ele.</b> (9M2342)..... PF935	<b>Fuel</b> (1R0749)..... BF7587 +	<b>Fuel</b> (High Efficiency) (1R0749).... BF7587 +
<b>P. Fuel Spin-on</b> (4N5823)..... BF614 +	<b>Radial Seal Air</b> (Standard) (Don. P185069)..... RS3518	<b>Radial Seal Air</b> (Standard) (Don. P535717)..... RS3518
<b>S. Fuel</b> (High Efficiency) (1R0749)..... BF7587 +	<b>Radial Seal XP Air</b> (Upgrade) (Don. P185069)..... RS3518XP	<b>Radial Seal XP Air</b> (Upgrade) (Don. P535717)..... RS3518XP
Argosy w/Cat C10 Eng.	Argosy w/Cat C15 Eng. (To 01/2004)	
<b>F-F Lube</b> (Std. Efficiency) (1R0716)..... B99 +	<b>Lube</b> (1R0716)..... B99 +	
<b>F-F Lube</b> (High Efficiency) (1R1808)..... B7299 +	<b>Fuel/Water Separator</b> (Fleetguard FS1212)..... BF1212 +	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
Argosy w/Cummins 4B Series Eng. <b>Lube</b> (3903224)..... <b>BT427 +</b> <b>Fuel/Water Separator</b> (3903202)..... <b>BF1226</b> <b>Fuel</b> (3903640)..... <b>BF788</b>	Argosy w/Cummins ISX Eng. (Cont'd) <b>Radial Seal XP Air</b> (Upgrade) (Don. P185069)..... <b>RS3518XP</b> <b>Air Dryer</b> (AD-IS System) (Bendix 109994)..... <b>BA5374 +</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (Fleetguard WF2127)..... <b>B5087</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Rear Axle</b> (Meritor 3280-V-8394)..... <b>B233</b>	Argosy w/Detroit Diesel Series 60 Eng. (North America) (To 12/2003) <b>F-F Lube</b> (23530573)..... [2] <b>B495</b> <b>Opt. B-P Lube</b> (Paper Insert) (Spinner II 73165)..... <b>BC7456 KIT</b> <b>Fuel/Water Separator Ele.</b> (23521528)..... <b>PF7744</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (Racor S3226P)..... <b>BF1346-O</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (Racor S3226P)..... <b>BF1346-SP</b> <b>Fuel/Water Separator</b> (w/Drain) (Racor S3226P)..... <b>BF1346</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (23535985)..... <b>BF5813 +</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (23535985).. <b>BF5813-O +</b> <b>Fuel/Water Separator Spin-on</b> (Alliance ABPN122R50551)..... <b>BF46016-O</b> <b>P. Fuel</b> (23518481)..... <b>BF5800 +</b> <b>S. Fuel</b> (23518482)..... <b>BF5810</b> <b>Axial Seal Air</b> (Don. P142100)..... <b>PA2631</b> <b>15 1/4 In. Radial Seal Air</b> (Standard) (Don. P535717)..... <b>RS3518</b> <b>15 1/4 In. Radial Seal XP Air</b> (Upgrade) (Don. P535717)..... <b>RS3518XP</b> <b>23 7/16 In. Radial Seal Air</b> (Don. P531026)..... <b>RS3516</b> <b>23 7/16 In. Radial Seal XP Air</b> (Don. DBA5106)..... <b>RS3516XP</b> <b>Cab Air</b> (22-44665-000)..... <b>PA5319</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-IP System) (Bendix 109994)..... <b>BA5374 +</b> <b>Coolant</b> (Fleetguard WF2077)..... <b>B5134 +</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Steering</b> (Nelson 87904A)..... <b>PT9354-MPG</b>
Argosy w/Cummins ISM (10.8L) Eng. <b>11 7/8 In. Dual-Flow Lube</b> (3406809)..... <b>BD7154 +</b> <b>14 In. Dual-Flow Lube</b> (3406810)..... <b>BD7153 +</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (w/Drain) (Alliance S3226FL01)..... <b>BF1347</b> <b>Fuel/Water Separator</b> (Alliance ABPN122R50551)..... <b>BF46016-O</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (Alliance S3226FL01).... <b>BF1347-O</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (Alliance S3226FL01)..... <b>BF1373-SP</b> <b>Fuel/Water Separator</b> (w/o SP) (Fleetguard FS1212)..... <b>BF1212 +</b> <b>Fuel/Water Separator</b> (w/M14 x 2.0 SP Thd.) (3406889)..... <b>BF1293-SPS</b> <b>Axial Seal Air</b> (Don. P142100).... <b>PA2631</b> <b>Radial Seal Air</b> (Standard) (Don. P535717)..... <b>RS3518</b> <b>Radial Seal XP Air</b> (Upgrade) (Don. P535717)..... <b>RS3518XP</b> <b>Air Dryer</b> (AD-IS System) (Bendix 109994)..... <b>BA5374 +</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134 +</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>2 23/32 In. Steering</b> (Nelson 87904A)..... <b>PT9354-MPG</b> <b>4 3/16 In. Steering</b> (Nelson 83213M)..... <b>P528</b>	Argosy w/Cummins M11 Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> (3329289)..... <b>BF1259</b>	Argosy w/Detroit Diesel Series 60 Eng. (North America) (12/2003-on) <b>F-F Lube</b> (23530573)..... [2] <b>B495</b> <b>Opt. B-P Lube</b> (Paper Insert) (Spinner II 73165)..... <b>BC7456 KIT</b> <b>Fuel/Water Separator Ele.</b> (23521528)..... <b>PF7744</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (Racor S3226P)..... <b>BF1346-O</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (Racor S3226P)..... <b>BF1346-SP</b> <b>Fuel/Water Separator</b> (w/Drain) (Racor S3226P)..... <b>BF1346</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (23535985)..... <b>BF5813 +</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (23535985).. <b>BF5813-O +</b> <b>Fuel/Water Separator Spin-on</b> (Alliance ABPN122R50551)..... <b>BF46016-O</b> <b>P. Fuel</b> (23518481)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530645)..... <b>BF5815</b>
Argosy w/Cummins ISM (10.8L) Eng. <b>11 7/8 In. Dual-Flow Lube</b> (3406809)..... <b>BD7154 +</b> <b>14 In. Dual-Flow Lube</b> (3406810)..... <b>BD7153 +</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (w/Drain) (Alliance S3226FL01)..... <b>BF1347</b> <b>Fuel/Water Separator</b> (Alliance ABPN122R50551)..... <b>BF46016-O</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (Alliance S3226FL01).... <b>BF1347-O</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (Alliance S3226FL01)..... <b>BF1373-SP</b> <b>Fuel/Water Separator</b> (w/o SP) (Fleetguard FS1212)..... <b>BF1212 +</b> <b>Fuel/Water Separator</b> (w/M14 x 2.0 SP Thd.) (3406889)..... <b>BF1293-SPS</b> <b>Axial Seal Air</b> (Don. P142100).... <b>PA2631</b> <b>Radial Seal Air</b> (Standard) (Don. P535717)..... <b>RS3518</b> <b>Radial Seal XP Air</b> (Upgrade) (Don. P535717)..... <b>RS3518XP</b> <b>Air Dryer</b> (AD-IS System) (Bendix 109994)..... <b>BA5374 +</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134 +</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>2 23/32 In. Steering</b> (Nelson 87904A)..... <b>PT9354-MPG</b> <b>4 3/16 In. Steering</b> (Nelson 83213M)..... <b>P528</b>	Argosy w/Cummins N14 (14.0L) Eng. <b>9 15/16 In. F-F Lube</b> (Fleetguard LF670SC)..... <b>B196 +</b> <b>11 9/32 In. F-F Lube</b> (Fleetguard LF670SC)..... <b>B96 +</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Fuel/Water Separator</b> (Alliance ABPN122R50551)..... <b>BF46016-O</b> <b>Fuel/Water Separator</b> (3329289)..... <b>BF1259</b> <b>Fuel</b> (154789)..... <b>BF957-D +</b>	Argosy w/Detroit Diesel Series 60 Eng. (North America) (12/2003-on) <b>F-F Lube</b> (23530573)..... [2] <b>B495</b> <b>Opt. B-P Lube</b> (Paper Insert) (Spinner II 73165)..... <b>BC7456 KIT</b> <b>Fuel/Water Separator Ele.</b> (23521528)..... <b>PF7744</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (Racor S3226P)..... <b>BF1346-O</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (Racor S3226P)..... <b>BF1346-SP</b> <b>Fuel/Water Separator</b> (w/Drain) (Racor S3226P)..... <b>BF1346</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (23535985)..... <b>BF5813 +</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (23535985).. <b>BF5813-O +</b> <b>Fuel/Water Separator Spin-on</b> (Alliance ABPN122R50551)..... <b>BF46016-O</b> <b>P. Fuel</b> (23518481)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530645)..... <b>BF5815</b>
Argosy w/Cummins ISX Eng. <b>Dual-Flow Lube</b> (3101869)..... <b>BD7154 +</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19557)..... <b>PF7749</b> <b>Fuel/Water Separator Spin-on</b> (3101872)..... <b>BF1277-SPS</b> <b>Fuel/Water Separator Spin-on</b> (3331096)..... <b>BF1274-SP</b> <b>Fuel/Water Separator Ele.</b> (Davco 380087)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> (Alliance ABPN122R50551)..... <b>BF46016-O</b> <b>Fuel Spin-on</b> (4088272)..... <b>BF7766</b> <b>Radial Seal Air</b> (Standard) (Don. P185069)..... <b>RS3518</b>	Argosy w/Cummins Signature 600 Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9000)..... <b>BD7153 +</b> <b>Fuel/Water Separator</b> (3331096)..... <b>BF1274-SP</b> <b>Fuel/Water Separator</b> (4010651)..... <b>BF1277-SPS</b>	Argosy w/Detroit Diesel Series 60 Eng. (North America) (12/2003-on) <b>F-F Lube</b> (23530573)..... [2] <b>B495</b> <b>Opt. B-P Lube</b> (Paper Insert) (Spinner II 73165)..... <b>BC7456 KIT</b> <b>Fuel/Water Separator Ele.</b> (23521528)..... <b>PF7744</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (Racor S3226P)..... <b>BF1346-O</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (Racor S3226P)..... <b>BF1346-SP</b> <b>Fuel/Water Separator</b> (w/Drain) (Racor S3226P)..... <b>BF1346</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (23535985)..... <b>BF5813 +</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (23535985).. <b>BF5813-O +</b> <b>Fuel/Water Separator Spin-on</b> (Alliance ABPN122R50551)..... <b>BF46016-O</b> <b>P. Fuel</b> (23518481)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530645)..... <b>BF5815</b>
Argosy w/Cummins ISX Eng. <b>Dual-Flow Lube</b> (3101869)..... <b>BD7154 +</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19557)..... <b>PF7749</b> <b>Fuel/Water Separator Spin-on</b> (3101872)..... <b>BF1277-SPS</b> <b>Fuel/Water Separator Spin-on</b> (3331096)..... <b>BF1274-SP</b> <b>Fuel/Water Separator Ele.</b> (Davco 380087)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> (Alliance ABPN122R50551)..... <b>BF46016-O</b> <b>Fuel Spin-on</b> (4088272)..... <b>BF7766</b> <b>Radial Seal Air</b> (Standard) (Don. P185069)..... <b>RS3518</b>	Argosy w/Detroit Diesel Series 60 Eng. (North America) (12/2003-on) <b>F-F Lube</b> (23530573)..... [2] <b>B495</b> <b>Opt. B-P Lube</b> (Paper Insert) (Spinner II 73165)..... <b>BC7456 KIT</b> <b>Fuel/Water Separator Ele.</b> (23521528)..... <b>PF7744</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (Racor S3226P)..... <b>BF1346-O</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (Racor S3226P)..... <b>BF1346-SP</b> <b>Fuel/Water Separator</b> (w/Drain) (Racor S3226P)..... <b>BF1346</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (23535985)..... <b>BF5813 +</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (23535985).. <b>BF5813-O +</b> <b>Fuel/Water Separator Spin-on</b> (Alliance ABPN122R50551)..... <b>BF46016-O</b> <b>P. Fuel</b> (23518481)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530645)..... <b>BF5815</b>	Argosy w/Detroit Diesel Series 60 Eng. (North America) (12/2003-on) <b>F-F Lube</b> (23530573)..... [2] <b>B495</b> <b>Opt. B-P Lube</b> (Paper Insert) (Spinner II 73165)..... <b>BC7456 KIT</b> <b>Fuel/Water Separator Ele.</b> (23521528)..... <b>PF7744</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (Racor S3226P)..... <b>BF1346-O</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (Racor S3226P)..... <b>BF1346-SP</b> <b>Fuel/Water Separator</b> (w/Drain) (Racor S3226P)..... <b>BF1346</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (23535985)..... <b>BF5813 +</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (23535985).. <b>BF5813-O +</b> <b>Fuel/Water Separator Spin-on</b> (Alliance ABPN122R50551)..... <b>BF46016-O</b> <b>P. Fuel</b> (23518481)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530645)..... <b>BF5815</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
Argosy w/Detroit Diesel Series 60 Eng. (North America) (12/2003-on) (Cont'd)	Business Class M2 w/Cat 3126 (7.2L) Eng. (1/2004-on) (Cont'd)	Business Class M2 w/Cat C7 (7.2L) Eng. (To 1/2004) (Cont'd)
<b>Axial Seal Air</b> (Don. P142100)..... <b>PA2631</b>	<b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960) <b>CA5420 +</b>	<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>
<b>15 1/4 In. Radial Seal Air</b> (Standard) (Don. P535717)..... <b>RS3518</b>	<b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b>	<b>Coolant</b> (9N3368)..... <b>BW5137</b>
<b>15 1/4 In. Radial Seal XP Air</b> (Upgrade) (Don. P535717)..... <b>RS3518XP</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>23 7/16 In. Radial Seal Air</b> (Don. P531026)..... <b>RS3516</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>23 7/16 In. Radial Seal XP Air</b> (Don. DBA5106)..... <b>RS3516XP</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Cab Air</b> (22-44665-000)..... <b>PA5319</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Air Dryer</b> (AD-IP System) (Bendix 109994)..... <b>BA5374 +</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>Coolant</b> (Fleetguard WF2077)..... <b>B5134 +</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
<b>Trans.</b> (Fuller 4304827)..... <b>BT223</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29526899)..... <b>PT9416-MPG KIT</b>	<b>Steering</b> (VML/T1808D)..... <b>BT9388</b>
<b>Steering</b> (Nelson 87904A)..... <b>PT9354-MPG</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29526898)..... <b>PT9415-MPG KIT</b>	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>
Business Class M2 w/Cat 3126 (7.2L) Eng. (To 1/2004)	<b>Steering</b> (T1808D)..... <b>BT9388</b>	Business Class M2 w/Cat C7 (7.2L) Eng. (1/2004-on)
<b>Lube</b> (Standard Vers.) (1R0739).. <b>B76</b>	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Lube</b> (1R1807)..... <b>B7700 +</b>
<b>Fuel</b> (1R0751)..... <b>BF7632</b>	Business Class M2 w/Cat C7 (7.2L) Eng. (To 1/2004)	<b>Fuel/Water Separator Spin-on</b> (w/Drain) (Alliance ABP/S3226FL02)..... <b>BF1346 +</b>
<b>Opt. S. Fuel</b> (Davco 101377)..... <b>BF788</b>	<b>Lube</b> (Standard Vers.) (1R0739).. <b>B76 +</b>	<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Alliance ABP/N122-R50418)..... <b>BF9898-O</b>
<b>Channel Flow Air</b> (Std. Media) (Don. P607955)..... <b>CA4700 +</b>	<b>Lube</b> (Severe Service) (1R0739).. <b>B76-SS +</b>	<b>Suction line Fuel/Water Separator Spin-on</b> (175-2949)..... <b>BF1268</b>
<b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960) <b>CA5420 +</b>	<b>Fuel/Water Separator Spin-on</b> (w/Drain) (Alliance ABP/S3226FL02)..... <b>BF1346 +</b>	<b>Fuel Spin-on</b> (1R0751)..... <b>BF7632</b>
<b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b>	<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Alliance ABP/N122-R50418)..... <b>BF9898-O</b>	<b>Opt. Fuel In-Line</b> (Fleetguard FF5079)..... <b>BF1173</b>
<b>Cab Air</b> (36000006)..... <b>PA5359</b>	<b>Suction line Fuel/Water Separator Spin-on</b> (175-2949)..... <b>BF1268</b>	<b>Channel Flow Air</b> (Std. Media) (Don. P607955)..... <b>CA4700 +</b>
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Fuel Spin-on</b> (1R0751)..... <b>BF7632</b>	<b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960) <b>CA5420 +</b>
<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Opt. Fuel In-Line</b> (Fleetguard FF5079)..... <b>BF1173</b>	<b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Channel Flow Air</b> (Std. Media) (Don. P607955)..... <b>CA4700 +</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960) <b>CA5420 +</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29526899)..... <b>PT9416-MPG KIT</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29526898)..... <b>PT9415-MPG KIT</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Coolant</b> (9N3368)..... <b>BW5137</b>
<b>Steering</b> (T1808D)..... <b>BT9388</b>	<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>		
Business Class M2 w/Cat 3126 (7.2L) Eng. (1/2004-on)		
<b>Lube</b> (1R1807)..... <b>B7700 +</b>		
<b>Fuel</b> (1R0751)..... <b>BF7632</b>		
<b>Opt. S. Fuel</b> (Davco 101377)..... <b>BF788</b>		
<b>Channel Flow Air</b> (Std. Media) (Don. P607955)..... <b>CA4700 +</b>		

\* See Product Guide for Variations of This Number. Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>	<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>	<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>
Business Class M2 w/Cat C7 (7.2L) Eng. (1/2004-on) (Cont'd)	Business Class M2 w/Cat C9 (8.8L) Eng. (Cont'd)	Business Class M2 w/Cat C11 Eng. (To 1/2004) (Cont'd)
Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Steering Ele. (Fleetguard 87904M)..... <b>PT9354-MPG</b>
Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	Steering Spin-on (VML/T1808D). <b>BT9388</b>
Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	Steering (VML/T1808D)..... <b>BT9388</b>	Some Differential (Meritor 3280-V-8394)..... <b>B233</b>
Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	Some Differential (Meritor 3280-V-8394)..... <b>B233</b>	Business Class M2 w/Cat C11 Eng. (1/2004-on)
Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	Business Class M2 w/Cat C11 Eng. (To 1/2004)	<b>Lube</b> (1R1808)..... <b>B7299 +</b>
Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>	<b>Lube</b> (1R0716)..... <b>B99 +</b>	<b>Suction Line Fuel/Water Separator</b> BF1268
Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	<b>Suction Line Fuel/Water Separator</b> BF1268	<b>Fuel/Water Separator</b> (3 11/16 In. O.D.) (256-8753)..... <b>BF1259</b>
Steering (VML/T1808D)..... <b>BT9388</b>	<b>Fuel/Water Separator</b> (3 11/16 In. O.D.) (256-8753)..... <b>BF1259</b>	<b>Fuel/Water Separator</b> (4 9/32 In. O.D.)..... <b>BF1339-SP +</b>
Some Differential (Meritor 3280-V-8394)..... <b>B233</b>	<b>Fuel/Water Separator</b> (4 5/16 In. O.D.), (Open End for Bowl) (BR90FRT10)..... <b>BF9871-O</b>	<b>Fuel/Water Separator</b> (4 5/16 In. O.D.), (Open End for Bowl) (BR90FRT10)..... <b>BF9871-O</b>
Business Class M2 w/Cat C9 (8.8L) Eng.	<b>Fuel</b> (1R0749)..... <b>BF7587 +</b>	<b>Channel Flow Air</b> (12 25/32 O.D.; Std. Media) (Don. P548070)..... <b>CA4700 +</b>
<b>Lube</b> (1R1808)..... <b>B7299 +</b>	<b>Channel Flow Air</b> (12 25/32 O.D.; Std. Media) (Don. P548070)..... <b>CA4700 +</b>	<b>Channel Flow Air</b> (11 21/32 In. O.D.; Flame Retardant Media) (Don. P607960)..... <b>CA5420 +</b>
<b>7 3/8 In. Fuel/Water Separator</b> (175-2949)..... <b>BF1268</b>	<b>Channel Flow Air</b> (11 21/32 In. O.D.; Flame Retardant Media) (Don. P607960)..... <b>CA5420 +</b>	<b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b>
<b>8 9/32 In. Fuel/Water Separator</b> (S3226FL02)..... <b>BF1346-SP +</b>	<b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b>	<b>Channel Flow Air</b> (14 7/8 In. O.D.; Std. Media) (Don. P607965)..... <b>CA5368 +</b>
<b>Fuel/Water Separator</b> (Alliance ABPN122R50551)..... <b>BF46016-O</b>	<b>Channel Flow Air</b> (14 7/8 In. O.D.; Std. Media) (Don. P607965)..... <b>CA5368 +</b>	<b>Channel Flow Air</b> (14 7/8 In. O.D.; Flame Retardant Media) (Don. P605960)..... <b>CA5419 +</b>
<b>Fuel</b> (1R0751)..... <b>BF7632</b>	<b>Channel Flow Air</b> (14 7/8 In. O.D.; Flame Retardant Media) (Don. P605960)..... <b>CA5419 +</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>
<b>Channel Flow Air</b> (Std. Media) (Don. P607955)..... <b>CA4700 +</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
<b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960)..... <b>CA5420 +</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>
<b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>
<b>Cab Air</b> (36000006)..... <b>PA5359</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>	<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>
<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>Coolant</b> (9N6123)..... <b>BW5139</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Steering Ele.</b> (Fleetguard 87904M)..... <b>PT9354-MPG</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>		
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>		
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>		
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>		
<b>Steering Ele.</b> (Fleetguard 87904M)..... <b>PT9354-MPG</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
Business Class M2 w/Cat C11 Eng. (1/2004-on) (Cont'd)	Business Class M2 w/Cat C13 Eng. (To 1/2004) (Cont'd)	Business Class M2 w/Cat C13 Eng. (1/2004-on) (Cont'd)
<b>Steering Spin-on</b> (VML/T1808D)..... <b>BT9388</b>	<b>Fuel/Water Separator</b> (w/Drain) (Fleetguard FS19593)..... <b>BF1346</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (Alliance ABPS3226FL01)..... <b>BF1347-O</b>
<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Fuel/Water Separator</b> (256-8753)..... <b>BF1259</b>	<b>Fuel/Water Separator</b> (w/Sensor Port) (Alliance ABPS3226FL01).... <b>BF1373-SP</b>
Business Class M2 w/Cat C12 Eng.	<b>Fuel/Water Separator</b> (Racor BR90FRT10)..... <b>BF9871-O</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (Fleetguard FS19593).... <b>BF1346-O</b>
<b>Lube</b> (To 1/2004) (1R0716)..... <b>B99 +</b>	<b>Fuel/Water Separator</b> (1752949)..... <b>BF1268</b>	<b>Fuel/Water Separator</b> (Alliance ABPN122R50418)..... <b>BF9898-O</b>
<b>Lube</b> (1/2004-on) (1R1808)..... <b>B7299 +</b>	<b>Fuel</b> (1R0749)..... <b>BF7587 +</b>	<b>Fuel/Water Separator</b> (w/Sensor Port) (Fleetguard FS19593)..... <b>BF1346-SP</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (Fleetguard FS19593).... <b>BF1346-O</b>	<b>Channel Flow Air</b> (12 25/32 O.D.; Std. Media) (Don. P548070)..... <b>CA4700 +</b>	<b>Fuel/Water Separator</b> (w/Drain) (Fleetguard FS19593)..... <b>BF1346</b>
<b>Fuel/Water Separator</b> (w/Drain) (Fleetguard FS19593)..... <b>BF1346</b>	<b>Channel Flow Air</b> (11 21/32 In. O.D.; Flame Retardant Media) (Don. P607960)..... <b>CA5420 +</b>	<b>Fuel/Water Separator</b> (Alliance ABPN122R50418)..... <b>BF9898-O</b>
<b>Fuel/Water Separator</b> (w/Sensor Port) (Fleetguard FS19593)..... <b>BF1346-SP</b>	<b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b>	<b>Fuel/Water Separator</b> (w/Sensor Port) (Fleetguard FS19593)..... <b>BF1346-SP</b>
<b>Fuel</b> (1R0749)..... <b>BF7587 +</b>	<b>Channel Flow Air</b> (14 7/8 In. O.D.; Std. Media) (Don. P607965) <b>CA5368 +</b>	<b>Fuel/Water Separator</b> (w/Drain) (Fleetguard FS19593)..... <b>BF1346</b>
<b>Channel Flow Air</b> (Std. Media) (Don. P548070)..... <b>CA4700 +</b>	<b>Channel Flow Air</b> (14 7/8 In. O.D.; Flame Retardant Media) (Don. P605960)..... <b>CA5419 +</b>	<b>Fuel/Water Separator</b> (256-8753)..... <b>BF1259</b>
<b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960) <b>CA5420 +</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>	<b>Fuel/Water Separator</b> (Racor BR90FRT10)..... <b>BF9871-O</b>
<b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Fuel/Water Separator</b> (1752949)..... <b>BF1268</b>
<b>Cab Air</b> (36000006)..... <b>PA5359</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Fuel</b> (1R0749)..... <b>BF7587 +</b>
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Channel Flow Air</b> (12 25/32 O.D.; Std. Media) (Don. P548070).... <b>CA4700 +</b>
<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Channel Flow Air</b> (11 21/32 In. O.D.; Flame Retardant Media) (Don. P607960)..... <b>CA5420 +</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Channel Flow Air</b> (14 7/8 In. O.D.; Std. Media) (Don. P607965) <b>CA5368 +</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Channel Flow Air</b> (14 7/8 In. O.D.; Flame Retardant Media) (Don. P605960)..... <b>CA5419 +</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
<b>Steering</b> (T1808D)..... <b>BT9388</b>	<b>Steering</b> (VML/T1808D)..... <b>BT9388</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>
<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>
Business Class M2 w/Cat C13 Eng. (To 1/2004)	Business Class M2 w/Cat C13 Eng. (1/2004-on)	<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>
<b>Lube</b> (1R0716)..... <b>B99 +</b>	<b>Lube</b> (1R1808)..... <b>B7299 +</b>	<b>Crankcase Breather</b> (2007-on) (296-8325)..... <b>CV15008</b>
<b>Opt. Lube</b> (249-2347)..... <b>[2] B7402</b>	<b>Opt. Lube</b> (249-2347)..... <b>[2] B7402</b>	<b>Coolant</b> (Cummins 3315116)..... <b>BW5071</b>
<b>Fuel/Water Separator</b> (w/Drain) (Alliance ABPS3226FL01)..... <b>BF1347</b>	<b>Fuel/Water Separator</b> (w/Drain) (Alliance ABPS3226FL01)..... <b>BF1347</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (Alliance ABPS3226FL01)..... <b>BF1347-O</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (Alliance ABPS3226FL01)..... <b>BF1347-O</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Fuel/Water Separator</b> (w/Sensor Port) (Alliance ABPS3226FL01).... <b>BF1373-SP</b>	<b>Fuel/Water Separator</b> (w/Sensor Port) (Fleetguard FS19593).... <b>BF1346-O</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (Fleetguard FS19593).... <b>BF1346-O</b>	<b>Fuel/Water Separator</b> (w/Sensor Port) (Fleetguard FS19593).... <b>BF1346-SP</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
<b>Fuel/Water Separator</b> (w/Sensor Port) (Fleetguard FS19593).... <b>BF1346-SP</b>	<b>Fuel/Water Separator</b> (Alliance ABPN122R50418)..... <b>BF9898-O</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>Fuel/Water Separator</b> (Alliance ABPN122R50418)..... <b>BF9898-O</b>		<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
		<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
Business Class M2 w/Cat C13 Eng. (1/2004-on) (Cont'd)	Business Class M2 w/Cummins ISB 6.7 (6.7L) Eng. (2008-09) (Cont'd)	Business Class M2 w/Cummins ISB 6.7 (6.7L) Eng. (2010-on) (Cont'd)
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b>	<b>Channel Flow Secondary Air</b> (Don. P616400)..... <b>PA4701</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374+</b>
<b>Steering</b> (VMLT1808D)..... <b>BT9388</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>
<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374+</b>
Business Class M2 w/Cummins 4BT3.9 (3.9L) Eng.	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374+</b>	<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379+</b>
<b>Lube</b> (3903224)..... <b>BT427+</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Crankcase Breather</b> (Fleetguard CV52001)..... <b>CV15010</b>
<b>Fuel/Water Separator</b> (3903202)..... <b>BF1226</b>	<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374+</b>	<b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b>
<b>P. Fuel</b> (3903640)..... <b>BF788</b>	<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379+</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
Business Class M2 w/Cummins 6C Series Eng.	<b>Crankcase Breather</b> (Fleetguard CV52001)..... <b>CV15010</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>F-F Lube</b> (3313281)..... <b>B205+</b>	<b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Dual-Flow Lube</b> (3318853)..... <b>BD103+</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
<b>Fuel/Water Separator</b> (3925274)..... <b>BF1280+</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>S. Fuel</b> (3903640)..... <b>BF788</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
Business Class M2 w/Cummins ISB (5.9L) Eng.	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Lube</b> (3937144)..... <b>B7177</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b>
<b>Fuel/Water Separator</b> (4934879)..... <b>BF1378-SPS</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Steering Ele.</b> (Nelson 87904M).... <b>PT9354-MPG</b>
<b>Fuel</b> (4934845)..... <b>BF7940</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b>	<b>Steering Spin-on</b> (VMLT1808D).. <b>BT9388</b>
<b>Channel Flow Air</b> (Don. P607955)..... <b>CA4700+</b>	<b>Steering Ele.</b> (Nelson 87904M).... <b>PT9354-MPG</b>	<b>Steering</b> (1417927000)..... <b>PT23629</b>
<b>Channel Flow Secondary Air</b> (Don. P616400)..... <b>PA4701</b>	<b>Steering Spin-on</b> (VMLT1808D).. <b>BT9388</b>	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>
<b>Cab Air</b> (VCC36000006)..... <b>PA5359</b>	<b>Steering</b> (1417927000)..... <b>PT23629</b>	<b>Diesel Exhaust Fluid</b> (A0001420289)..... <b>PE5272</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Diesel Exhaust Fluid</b> (2888182).. <b>PE17000</b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	Business Class M2 w/Cummins ISB 6.7 (6.7L) Eng. (2010-on)	Business Class M2 w/Cummins ISB6.7-200 Series (6.7L) Eng.
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b>	<b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	<b>Fuel/Water Separator</b> (Alliance ABP/N122BR90FRT-30)..... <b>BF46016-O</b>	<b>Fuel/Water Separator</b> (Alliance ABP/N122BR90FRT-30)..... <b>BF46016-O</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	<b>Fuel/Water Separator</b> (Alliance ABPN122R50550)..... <b>BF9871-O</b>	<b>Fuel/Water Separator</b> (Alliance ABPN122R50550)..... <b>BF9871-O</b>
<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>Fuel</b> (Fleetguard FF5632)..... <b>BF7940</b>	<b>Fuel</b> (Fleetguard FF5632)..... <b>BF7940</b>
<b>Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b>	<b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b>
Business Class M2 w/Cummins ISB 6.7 (6.7L) Eng. (2008-09)	<b>Channel Flow Air</b> (Std. Media) (Don. P607955)..... <b>CA4700+</b>	<b>Channel Flow Air</b> (Std. Media) (Don. P607955)..... <b>CA4700+</b>
<b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b>	<b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960)..... <b>CA5420+</b>	<b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960)..... <b>CA5420+</b>
<b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b>	<b>Channel Flow Secondary Air</b> (Don. P616400)..... <b>PA4701</b>	<b>Channel Flow Secondary Air</b> (Don. P616400)..... <b>PA4701</b>
<b>Fuel/Water Separator</b> (Alliance ABP/N122BR90FRT-30)..... <b>BF46016-O</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>
<b>Fuel/Water Separator</b> (Alliance ABPN122R50550)..... <b>BF9871-O</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
<b>Fuel</b> (Fleetguard FF5632)..... <b>BF7940</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374+</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374+</b>
<b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b>		
<b>Channel Flow Air</b> (Std. Media) (Don. P607955)..... <b>CA4700+</b>		
<b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960)..... <b>CA5420+</b>		

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
Business Class M2 w/Cummins ISB6.7-200 Series (6.7L) Eng. (Cont'd)	Business Class M2 w/Cummins ISB6.7-300 Series (6.7L) Eng. (Cont'd)	Business Class M2 w/Cummins ISC 8.3 (8.3L) Eng. (To 12/2006) (Cont'd)
<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>
<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>	<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>
<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>	<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>	<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>
<b>Crankcase Breather</b> (Fleetguard CV52001)..... <b>CV15010</b>	<b>Crankcase Breather</b> (Fleetguard CV52001)..... <b>CV15010</b>	<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>
<b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b>	<b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b>	<b>Coolant</b> (w/Chemical) (Fleetguard WF2071)..... <b>BW5071</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134 +</b>
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Steering Ele.</b> (Nelson 87904M).... <b>PT9354-MPG</b>	<b>Steering Ele.</b> (Nelson 87904M).... <b>PT9354-MPG</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
<b>Steering Spin-on</b> (VMLT1808D).. <b>BT9388</b>	<b>Steering Spin-on</b> (VMLT1808D).. <b>BT9388</b>	<b>Steering</b> (VMLT1808D)..... <b>BT9388</b>
<b>Steering</b> (1417927000)..... <b>PT23629</b>	<b>Steering</b> (1417927000)..... <b>PT23629</b>	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>
<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>
<b>Diesel Exhaust Fluid</b> (2010 Emissions) (A0001420289)..... <b>PE5272</b>	<b>Diesel Exhaust Fluid</b> (2010 Emissions) (A0001420289)..... <b>PE5272</b>	
<b>Diesel Exhaust Fluid</b> (2010 Emissions) (2888182)..... <b>PE17000</b>	<b>Diesel Exhaust Fluid</b> (2010 Emissions) (2888182)..... <b>PE17000</b>	
Business Class M2 w/Cummins ISB6.7-300 Series (6.7L) Eng.	Business Class M2 w/Cummins ISC 8.3 (8.3L) Eng. (To 12/2006)	Business Class M2 w/Cummins ISC 8.3 (8.3L) Eng. (1/2007-on)
<b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b>	<b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b>	<b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b>
<b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19763)..... <b>PF7928</b>	<b>Fuel/Water Separator Spin-on</b> (w/Drain) (Alliance S3226FL01).... <b>BF1347</b>
<b>Fuel/Water Separator</b> (Alliance ABP/N122BR90FRT-30)..... <b>BF46016-O</b>	<b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1022)..... <b>BF1272-SPS</b>	<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Alliance S3226FL01)..... <b>BF1347-O</b>
<b>Fuel/Water Separator</b> (Alliance ABPN122R50550)..... <b>BF9871-O</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (Alliance ABPN122BR90FRT10)..... <b>BF9871-O</b>	<b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (Alliance S3226FL01)..... <b>BF1373-SP</b>
<b>Fuel</b> (Fleetguard FF5632)..... <b>BF7940</b>	<b>Opt. Fuel/Water Separator Spin-on</b> (3800394)..... <b>BF1293-SPS</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19763)..... <b>PF7928</b>
<b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b>	<b>Fuel</b> (Fleetguard FF5488)..... <b>BF7815</b>	<b>Some Fuel/Water Separator Spin-on</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b>
<b>Channel Flow Air</b> (Std. Media) (Don. P607955)..... <b>CA4700 +</b>	<b>Channel Flow Air</b> (Std. Media) (Don. P607955)..... <b>CA4700 +</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (Alliance ABPN122BR90FRT10)..... <b>BF9871-O</b>
<b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960) <b>CA5420 +</b>	<b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960) <b>CA5420 +</b>	<b>Opt. Fuel/Water Separator Spin-on</b> (3800394)..... <b>BF1293-SPS</b>
<b>Channel Flow Secondary Air</b> (Don. P616400)..... <b>PA4701</b>	<b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b>	<b>Fuel</b> (Fleetguard FF5636)..... <b>BF7924</b>
<b>Cab Air</b> (36000006)..... <b>PA5359</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>	<b>Channel Flow Air</b> (Std. Media) (Don. P607955)..... <b>CA4700 +</b>
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960) <b>CA5420 +</b>
<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
Business Class M2 w/Cummins ISC 8.3 (8.3L) Eng. (1/2007-on) (Cont'd)	Business Class M2 w/Cummins ISC-280 (8.3L) Eng. (To 12/2006) (Cont'd)	Business Class M2 w/Cummins ISC-280 (8.3L) Eng. (1/2007-on) (Cont'd)
<b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b>	<b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960) <b>CA5420 +</b>	<b>Opt. Fuel/Water Separator Spin-on</b> (3800394)..... <b>BF1293-SPS</b>
<b>Cab Air</b> (36000006)..... <b>PA5359</b>	<b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b>	<b>Fuel</b> (Fleetguard FF5636)..... <b>BF7924</b>
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>	<b>Channel Flow Air</b> (Std. Media) (Don. P607955)..... <b>CA4700 +</b>
<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960) <b>CA5420 +</b>
<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b>
<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>
<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>	<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
<b>Coolant</b> (w/Chemical) (Fleetguard WF2071)..... <b>BW5071</b>	<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>
<b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134 +</b>	<b>Coolant</b> (w/Chemical) (Fleetguard WF2071)..... <b>BW5071</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134 +</b>	<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Coolant</b> (w/Chemical) (Fleetguard WF2071)..... <b>BW5071</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134 +</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
<b>Steering</b> (VML/T1808D)..... <b>BT9388</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Steering</b> (VML/T1808D)..... <b>BT9388</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Diesel Exhaust Fluid</b> (2010 Emissions) (A0001420289)..... <b>PE5272</b>	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Diesel Exhaust Fluid</b> (2010 Emissions) (2888182)..... <b>PE17000</b>	Business Class M2 w/Cummins ISC-280 (8.3L) Eng. (1/2007-on)	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
Business Class M2 w/Cummins ISC-280 (8.3L) Eng. (To 12/2006)	<b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b>	<b>Steering</b> (VML/T1808D)..... <b>BT9388</b>
<b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b>	<b>Fuel/Water Separator Spin-on</b> (w/Drain) (Alliance S3226FL01).... <b>BF1347</b>	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>
<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19763)..... <b>PF7928</b>	<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Alliance S3226FL01)..... <b>BF1347-O</b>	<b>Diesel Exhaust Fluid</b> (2010 Emissions) (A0001420289)..... <b>PE5272</b>
<b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1022)..... <b>BF1272-SPS</b>	<b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (Alliance S3226FL01)..... <b>BF1373-SP</b>	<b>Diesel Exhaust Fluid</b> (2010 Emissions) (2888182)..... <b>PE17000</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (Alliance ABPN122BR90FRT10)..... <b>BF9871-O</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19763)..... <b>PF7928</b>	Business Class M2 w/Cummins ISC-300 Series (8.3L) Eng. (To 12/2006)
<b>Opt. Fuel/Water Separator Spin-on</b> (3800394)..... <b>BF1293-SPS</b>	<b>Some Fuel/Water Separator Spin-on</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b>	<b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b>
<b>Fuel</b> (Fleetguard FF5488)..... <b>BF7815</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (Alliance ABPN122BR90FRT10)..... <b>BF9871-O</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19763)..... <b>PF7928</b>
<b>Channel Flow Air</b> (Std. Media) (Don. P607955)..... <b>CA4700 +</b>		<b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1022)..... <b>BF1272-SPS</b>
		<b>Some Fuel/Water Separator</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
Business Class M2 w/Cummins ISC-300 Series (8.3L) Eng. (To 12/2006) (Cont'd)	Business Class M2 w/Cummins ISC-300 Series (8.3L) Eng. (1/2007-on) (Cont'd)	Business Class M2 w/Cummins ISL 8.9 (8.9L) Eng.
<b>Spin-on</b> (2007-on) (Fleetguard FS1065)..... <b>BF1378-SPS</b>	<b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (Alliance S3226FL01)..... <b>BF1373-SP</b>	<b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (Alliance ABPN122BR90FRT10)..... <b>BF9871-O</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19763)..... <b>PF7928</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19764)..... <b>PF9814</b>
<b>Opt. Fuel/Water Separator Spin-on</b> (3800394)..... <b>BF1293-SPS</b>	<b>Some Fuel/Water Separator Spin-on</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b>	<b>Fuel/Water Separator Spin-on</b> (Alliance ABP/N122-R50550)..... <b>BF9871-O</b>
<b>Fuel</b> (Fleetguard FF5488)..... <b>BF7815</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (Alliance ABPN122BR90FRT10)..... <b>BF9871-O</b>	<b>Fuel</b> (Fleetguard FF5636)..... <b>BF7924</b>
<b>Channel Flow Air</b> (Std. Media) (Don. P607955)..... <b>CA4700 +</b>	<b>Opt. Fuel/Water Separator Retardant Media</b> (Don. P607960)..... <b>BF1293-SPS</b>	<b>Fuel/Water Separator Spin-on</b> (Fleetguard FF63009)..... <b>BF63000</b>
<b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960)..... <b>CA5420 +</b>	<b>Fuel</b> (Fleetguard FF5636)..... <b>BF7924</b>	<b>12 25/32 In. O.D. Channel Flow Air</b> (Don. P607955)..... <b>CA4700 +</b>
<b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b>	<b>Channel Flow Air</b> (Std. Media) (Don. P607955)..... <b>CA4700 +</b>	<b>14 7/8 In. O.D. Channel Flow Air</b> (Fleetguard AF26424)..... <b>CA5368 +</b>
<b>Cab Air</b> (36000006)..... <b>PA5359</b>	<b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960)..... <b>CA5420 +</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b>	<b>Air Dryer</b> (SS1200 Plus) (Wabco R950011)..... <b>BA5374 +</b>
<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>	<b>Air Dryer</b> (System Saver 1800) (Wabco R950068)..... <b>BA5379 +</b>
<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Coolant</b> (w/Chemical) (Fleetguard WF2071)..... <b>BW5071</b>	<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
<b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134 +</b>	<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Coolant</b> (w/Chemical) (Fleetguard WF2071)..... <b>BW5071</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134 +</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Steering</b> (VML/T1808D)..... <b>BT9388</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Steering</b> (1417927000)..... <b>PT23629</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Diesel Exhaust Fluid</b> (5303604)..... <b>PE17000</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	Business Class M2 w/Cummins ISL-300 Series (8.9L) Eng.
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b>
<b>Steering</b> (VML/T1808D)..... <b>BT9388</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19764)..... <b>PF9814</b>
<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Fuel/Water Separator Spin-on</b> (Alliance ABP/N122-R50550)..... <b>BF9871-O</b>
Business Class M2 w/Cummins ISC-300 Series (8.3L) Eng. (1/2007-on)	<b>Steering</b> (VML/T1808D)..... <b>BT9388</b>	<b>Fuel</b> (Fleetguard FF5636)..... <b>BF7924</b>
<b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b>	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Fuel/Water Separator Spin-on</b> (Fleetguard FF63009)..... <b>BF63000</b>
<b>Fuel/Water Separator Spin-on</b> (w/Drain) (Alliance S3226FL01).... <b>BF1347</b>	<b>Diesel Exhaust Fluid</b> (2010 Emissions) (A0001420289)..... <b>PE5272</b>	<b>12 25/32 In. O.D. Channel Flow Air</b> (Don. P607955)..... <b>CA4700 +</b>
<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Alliance S3226FL01)..... <b>BF1347-O</b>	<b>Diesel Exhaust Fluid</b> (2010 Emissions) (2888182)..... <b>PE17000</b>	<b>14 7/8 In. O.D. Channel Flow Air</b> (Fleetguard AF26424)..... <b>CA5368 +</b>
		<b>Cab Air</b> (36000006)..... <b>PA5359</b>
		<b>Air Dryer</b> (SS1200 Plus) (Wabco R950011)..... <b>BA5374 +</b>
		<b>Air Dryer</b> (System Saver 1800) (Wabco R950068)..... <b>BA5379 +</b>
		<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
Business Class M2 w/Cummins ISL-300 Series (8.9L) Eng. (Cont'd)	Business Class M2 w/Detroit Diesel DD13 (12.8L) Eng. (Cont'd)	Business Class M2 w/Mercedes-Benz MBE460 Eng. (Cont'd)
Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965).....	Trans. Ele. (2 In. Kit) (Allison 29540493).....	Air Dryer (AD-IS System) (Bendix 5008414).....
20016	PT9416-MPG KIT	BA5374 +
Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966).....	Trans. Ele. (4 In. Kit) (Allison 29540494).....	Coolant (Fleetguard WF2077).....
20003	PT9415-MPG KIT	B5134 +
Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966).....	Opt. Trans. Spin-on (Fuller 17237).....	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965).....
20017	B2 +	20004
Trans. Spin-on (Allison 29539579).....	Steering (T1808D).....	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965).....
BT8460	BT9388	20016
Trans. Ele. (2 In. Kit) (Allison 29548987).....	Some Differential (Meritor 3280-V-8394).....	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966).....
PT9416-MPG KIT	B233	20003
Trans. Ele. (4 In. Kit) (Allison 29548988).....	Diesel Exhaust Fluid (2010 Emissions) (A0001420289).....	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966).....
PT9415-MPG KIT	PE5272	20017
Opt. Trans. Spin-on (Fuller 17237).....	Business Class M2 w/Detroit Diesel Series 55 Eng.	Trans. Spin-on (Allison 29539579).....
B2 +	Eng. (23550401).....	BT8460
Steering (VML/T1808D).....	Lube (23550401).....	Trans. Ele. (2 In. Kit) (Allison 29540493).....
BT9388	B7135	PT9416-MPG KIT
Steering (1417927000).....	P. Fuel (23530707).....	Trans. Ele. (4 In. Kit) (Allison 29540494).....
PT23629	BF5810	PT9415-MPG KIT
Diesel Exhaust Fluid (5303604).....	Business Class M2 w/Detroit Diesel Series 60 (14.0L) Eng.	Trans. Spin-on (Fuller 4304827).....
PE17000	Lube (23530573).....	BT223
Business Class M2 w/Detroit Diesel DD13 (12.8L) Eng.	Fuel/Water Separator (w/Drain) (23535985).....	Steering Ele. (Nelson 87904M).....
Lube (A4731800109).....	BF5813 +	PT9354-MPG
P7505	Fuel/Water Separator (Open End for Bowl) (23535985).....	BT9388
Opt. Fuel/Water Separator (Davco 482) (A0000903651).....	P. Fuel (23530706).....	Some Differential (Meritor 3280-V-8394).....
PF9804	BF5810 +	B233
Fuel Kit (2 Filter Kit) (A4720900451).....	S. Fuel (23530707).....	Business Class M2 w/Mercedes-Benz MBE900 Eng.
PF9908 KIT	BF5810	Eng.
Fuel Kit (3 Filter Kit) (A0000904251).....	Coolant (23516489).....	F-F Lube Ele. (1801709).....
PF9924 KIT	BW5200	P7188
11 21/32 In. O.D. Channel Flow Air (w/Flame Retardant Media) (Don. P607960).....	Business Class M2 w/Mercedes-Benz MBE460 Eng.	Opt. B-P Lube Spinner (A9061810086).....
CA5420 +	Lube (1802109).....	BC7326 +
12 25/32 In. O.D. Channel Flow Air (Std. Media) (Don. P548070).....	Fuel/Water Separator Ele. (Davco 382113).....	Fuel/Water Separator (w/Drain) (Alliance ABP/S3226FL02).....
CA4700 +	PF7748	BF1346 +
14 7/8 In. O.D. Channel Flow Air (Std. Media) (Don. P607965).....	Fuel/Water Separator Spin-on (w/SP) (S3226FL02Y).....	Fuel/Water Separator (Open End for Bowl) (Alliance ABP/N122-R50418).....
CA5368 +	BF1339-SP +	BF9898-O
Channel Flow Secondary Air (Don. P616400).....	Fuel/Water Separator Spin-on (Open End for Bowl) (S3226FL02Y).....	Fuel/Water Separator (Alliance ABP/N122-BRFRT10).....
PA4701	BF46083-O	BF9871-O
Cab Air (36000006).....	Fuel/Water Separator Spin-on (Alliance S3226FL02).....	Fuel/Water Separator (Alliance ABP/N122-BR90FRT30).....
PA5359	BF1346-SP +	BF46016-O
Air Dryer (AD-9 System) (Bendix 107796).....	Fuel/Water Separator (Open End for Bowl) (Fleetguard FS19593).....	Fuel (901551).....
BA5377	BF1346-O	PF7735
Air Dryer (AD-IP System) (Bendix 65624).....	Fuel/Water Separator (w/Drain) (FS19593).....	Fuel Screen (901351).....
BA5373	BF1346	PF7974 +
Air Dryer (AD-IS System) (Bendix 5008414).....	4 1/16 In. Fuel (901551).....	PF7939 +
BA5374 +	PF7735	PF9901 KIT
Air Dryer (SS1200 Plus) (Wabco R950068).....	8 In. Fuel (5410900151).....	Channel Flow Air (12 25/32 O.D.; Std. Media) (Don. P607955).....
BA5379 +	PF7761	CA4700 +
Air Dryer (System Saver 1200) (Wabco R950011).....	Screen Fuel (901351).....	Channel Flow Air (11 21/32 In. O.D.; Flame Retardant Media) (Don. P607960).....
BA5374 +	PF7974 +	CA5420 +
Coolant (A4722030255).....	Radial Seal XP Air (Don. EAF5067).....	Channel Flow Secondary Air (Don. P544432).....
P5092	RS2863XP	PA4701
Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965).....	Channel Flow Air (Std. Media) (Don. P544325).....	Channel Flow Air (14 7/8 In. O.D.; Std. Media) (Don. P607965).....
20004	CA5368 +	CA5368 +
Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965).....	Channel Flow Air (w/Flame Retardant Media) (Don. P605960).....	Channel Flow Air (14 7/8 In. O.D.; Flame Retardant Media) (Don. P605960).....
20016	CA5419 +	CA5419 +
Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966).....	Channel Flow Secondary Air (Don. P544432).....	Cab Air (Paper Ele.) (36000006).....
20003	PA4701	PA5359
Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966).....	Cab Air (36000006).....	PA5773
20017	PA5359	Air Dryer (AD-9 System) (Bendix 107796).....
Trans. Spin-on (Allison 29539579).....	Air Dryer (AD-9 System) (Bendix 107796).....	BA5377
BT8460	BA5377	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>FREIGHTLINER</b> <b>Trucks &amp; Buses (cont'd)</b>	<b>FREIGHTLINER</b> <b>Trucks &amp; Buses (cont'd)</b>	<b>FREIGHTLINER</b> <b>Trucks &amp; Buses (cont'd)</b>
Business Class M2 w/Mercedes-Benz MBE900 Eng. (Cont'd) <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b> <b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b> <b>Coolant</b> (23524403)..... <b>B5134 +</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (VML/T1808D)..... <b>BT9388</b> <b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	Business Class M2 w/Mercedes-Benz MBE904 Eng. (Cont'd) <b>Trans. Ele.</b> (2 In. Kit) (Allison 29526899)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29526898)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (T1808D)..... <b>BT9388</b> <b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b> Business Class M2 w/Mercedes-Benz MBE906 (6.4L) Eng. <b>F-F Lube Ele.</b> (1801709)..... <b>P7188</b> <b>Opt. B-P Lube Spinner</b> (A9061810086)..... <b>BC7326 +</b> <b>Fuel/Water Separator</b> (Closed End) (S3226FL02Y)..... <b>BF1339-SP +</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (S3226FL02Y)..... <b>BF46083-O</b> <b>Fuel Ele.</b> (901551)..... <b>PF7735</b> <b>Fuel Screen</b> (901351)..... <b>PF7974 +</b> <b>Channel Flow Air</b> (Std. Media) (Don. P607955)..... <b>CA4700 +</b> <b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960)..... <b>CA5420 +</b> <b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b> <b>Radial Seal Air</b> (Don. P532966)..... <b>RS3517</b> <b>Radial Seal XP Air</b> (Don. P532966)..... <b>RS3517XP</b> <b>Cab Air</b> (36000006)..... <b>PA5359</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b> <b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b> <b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (T1808D)..... <b>BT9388</b> <b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	Business Class M2 w/Mercedes-Benz MBE926 (7.2L) Eng. <b>F-F Lube Ele.</b> (1801709)..... <b>P7188</b> <b>Opt. B-P Lube Spinner</b> (A9061810086)..... <b>BC7326 +</b> <b>Screen Fuel</b> (901351)..... <b>PF7974 +</b> <b>4 In. Fuel</b> (901551)..... <b>PF7735</b> <b>8 In. Fuel</b> (5410900151)..... <b>PF7761</b> <b>Channel Flow Air</b> (Std. Media) (Don. P607955)..... <b>CA4700 +</b> <b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960)..... <b>CA5420 +</b> <b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b> <b>Cab Air</b> (36000006)..... <b>PA5359</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (T1808D)..... <b>BT9388</b> <b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b> Business Class M2 w/Mercedes-Benz MBE4000 (12.8L) Eng. <b>Lube</b> (A0001802909)..... <b>P7230</b> <b>3 3/4 In. O.D. Fuel/Water Separator Ele.</b> (Fleetguard FS19624)..... <b>PF7748</b> <b>4 3/16 In. O.D. Fuel/Water Separator Ele.</b> (Fleetguard FS19763)..... <b>PF7928</b> <b>Fuel/Water Separator Spin-on</b> (Alliance S3226FL02)..... <b>BF1346-SP +</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain and SP) (S3226FL02Y)..... <b>BF1339-SP +</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (S3226FL02Y)..... <b>BF46083-O</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (Alliance ABP/N122BR90FRT-10)..... <b>BF9871-O</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Alliance BR90FRT30)..... <b>BF46016-O</b> <b>Fuel</b> (5410900151)..... <b>PF7761</b>

+ See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>	<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>	<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>
Business Class M2 w/Mercedes-Benz MBE4000 (12.8L) Eng. (Cont'd)	Business Class M2 106 w/Cummins B6.7 (6.7L) Eng. (2018) (Cont'd)	Business Class M2 106 w/Cummins ISB 6.7 (6.7L) Eng.
12 25/32 In. O.D. Channel Flow Air (Std. Media) (Don. P548070).. CA4700 +	Channel Flow Primary Air (Standard Media) (Don. P607955)..... CA4700	Lube (Fleetguard LF3970)..... B7177
11 21/32 In. O.D. Channel Flow Air (w/Flame Retardant Media) (Don. P607960)..... CA5420 +	Channel Flow Primary Air (Flame Retardant Media) (Don. P607960) CA5420	Fuel/Water Separator (Alliance ABPN122R50550)..... BF9871-O
Channel Flow Secondary Air (Don. P544432)..... PA4701	Secondary Air (Don. P616400)... PA4701	Fuel (Fleetguard FF63009)..... BF63000
14 7/8 In. O.D. Channel Flow Air (Std. Media) (Don. P607965)..... CA5368 +	Cab Air (36000006)..... PA5359	Channel Flow Air (Std. Media) (Don. P607955)..... CA4700 +
14 7/8 In. O.D. Channel Flow Air (w/Flame Retardant Media) (Don. P605960)..... CA5419 +	Air Dryer (Desiccant) (Wabco R950011)..... BA5374 +	Channel Flow Air (w/Flame Retardant Media) (Don. P607960) CA5420 +
Cab Air (36000006)..... PA5359	Air Dryer (Coalescer) (Wabco R950068)..... BA5379 +	Channel Flow Secondary Air (Don. P616400)..... PA4701
Air Dryer (AD-9 System) (Bendix 107796)..... BA5377	Crankcase Breather (4936636)... CV15010	Cab Air (36000006)..... PA5359
Air Dryer (AD-IP System) (Bendix 65624)..... BA5373	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004	Air Dryer (AD-9 System) (Bendix 107796)..... BA5377
Air Dryer (AD-IS System) (Bendix 5008414)..... BA5374 +	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016	Crankcase Breather (Fleetguard CV52001)..... CV15010
Air Dryer (System Saver 1200) (Wabco R950011)..... BA5374 +	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004
Air Dryer (SS1200 Plus) (Wabco R950068)..... BA5379 +	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016
Coolant (23524403)..... B5134 +	Trans. Spin-on (Allison 29539579)..... BT8460	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003
Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004	Steering (1417927000)..... PT23629	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003
Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016	Diesel Exhaust Fluid (4388378).. PE17002 KIT	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017
Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003	Business Class M2 106 w/Cummins B6.7 (6.7L) Eng. (2019)	Trans. Spin-on (Allison 29539579)..... BT8460
Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017	Lube (3937736)..... B7177	29539579)..... BT8460
Trans. Spin-on (Allison 29539579)..... BT8460	Fuel/Water Separator (Racor R61709)..... PF46235	Steering (1417927000)..... PT23629
Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	Fuel (5303743)..... BF63000	Diesel Exhaust Fluid (5303604).. PE17000
Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Channel Flow Primary Air (Don. P607955)..... CA4700	Business Class M2 106 w/Cummins ISL 8.9 (8.9L) Eng.
Opt. Trans. Spin-on (Fuller 17237)..... B2 +	Channel Flow Secondary Air (Don. P616400)..... PA4701	Dual-Flow Lube (Fleetguard LF9009)..... BD7309 +
Steering (VMLT1808D)..... BT9388	Cab Air (Alliance ABPN10G36000006)..... PA5359	Fuel/Water Separator (Alliance ABPN122R50550)..... BF9871-O
Some Differential (Meritor 3280-V-8394)..... B233	Air Dryer (Wabco R950011)..... BA5374 +	Fuel (Fleetguard FF63009)..... BF63000
Business Class M2 w/Mercedes-Benz OM906 Eng.	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004	Channel Flow Air (Don. P607955)..... CA4700 +
Lube (A0001801609)..... P7199	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016	Channel Flow Secondary Air (Don. P616400)..... PA4701
Fuel (A9060920305)..... PF7735	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003	Cab Air (36000006)..... PA5359
Radial Seal Air (Don. P532966).. RS3517	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017	Air Dryer (AD-9 System) (Bendix 107796)..... BA5377
Radial Seal XP Air (Don. P532966)..... RS3517XP	Trans. Spin-on (Allison 29539579)..... BT8460	Trans. Ele. (2 In. Kit) (Allison 29548987)..... PT9416-MPG KIT
Business Class M2 106 w/Cummins B6.7 (6.7L) Eng. (2018)	Trans. Ele. (2 In. Kit) (Allison 29558117)..... PT9416-MPG KIT	Trans. Ele. (4 In. Kit) (Allison 29548988)..... PT9415-MPG KIT
Lube (3937736)..... B7177	Trans. Ele. (4 In. Kit) (Allison 29558118)..... PT9415-MPG KIT	Steering (1417927000)..... PT23629
Fuel/Water Separator (Racor R61709)..... PF46235	Steering (1417927000)..... PT23629	Diesel Exhaust Fluid (5303604).. PE17000
Fuel (Fleetguard FF63009)..... BF63000	Crankcase Breather (4936636).. CV15010	Business Class M2 106 w/Cummins L9 (9.0L) Eng. (2018)

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
Business Class M2 106 w/Cummins L9 (9.0L) Eng. (2018) (Cont'd)	Business Class M2 106 w/Detroit DD5 (5.1L) Eng. (2017-18) (Cont'd)	Business Class M2e Hybrid w/Cummins ISB Eng. (Cont'd)
<b>Channel Flow Primary Air</b> (Flame Retardant Media) (Don. P607960) <b>CA5420</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
<b>Secondary Air</b> (Don. P616400)... <b>PA4701</b>	<b>Steering</b> (1417927000)..... <b>PT23629</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>
<b>Cab Air</b> (36000006)..... <b>PA5359</b>	<b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b>	<b>Crankcase Breather</b> (Fleetguard CV52001)..... <b>CV15010</b>
<b>Air Dryer</b> (Desiccant) (Wabco R950011)..... <b>BA5374 +</b>	Business Class M2 112 w/Cummins ISL 8.9 (8.9L) Eng.	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Air Dryer</b> (Coalescer) (Wabco R950068)..... <b>BA5379 +</b>	<b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	<b>Fuel/Water Separator</b> (Alliance ABPN122R50550)..... <b>BF9871-O</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Trans.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	<b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
<b>Trans.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	<b>Channel Flow Air</b> (Don. P607965)..... <b>CA5368 +</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>Steering</b> (1417927000)..... <b>PT23629</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
Business Class M2 106 w/Cummins L9 (9.0L) Eng. (2019)	<b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Lube</b> (3401544)..... <b>B40142</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
<b>Fuel/Water Separator</b> (Racor R61709)..... <b>PF46235</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	<b>Steering Ele.</b> (Nelson 87904M).... <b>PT9354-MPG</b>
<b>Fuel</b> (5303743)..... <b>BF63000</b>	<b>Steering</b> (1417927000)..... <b>PT23629</b>	<b>Steering Spin-on</b> (VMLT1808D).. <b>BT9388</b>
<b>Fuel</b> (5660774)..... <b>BF63000</b>	<b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>
<b>Channel Flow Primary Air</b> (Don. P607955)..... <b>CA4700</b>	Business Class M2 NG w/Cummins ISL-G Eng.	C2 School Bus w/Cat C7 Eng.
<b>Channel Flow Secondary Air</b> (Don. P616400)..... <b>PA4701</b>	<b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b>	<b>Lube</b> (To 1/2004 (Std. Version)) (1R0739)..... <b>B76</b>
<b>Cab Air</b> (ABPN10G36000006).... <b>PA5359</b>	<b>Fuel</b> (Fleetguard NG5900)..... <b>BF7695</b>	<b>Lube</b> (1/2004-on) (1R1807)..... <b>B7700 +</b>
<b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b>	<b>Channel Flow Air</b> (Don. P607965)..... <b>CA5368 +</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19729)..... <b>PF7755</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>	<b>Fuel/Water Separator Spin-on</b> (w/o SP) (Alliance ABP-S3226FL02)..... <b>BF1346 +</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Fuel/Water Separator Spin-on</b> (w/SP) (Alliance ABP-S3226FL02)..... <b>BF1346-SP +</b>
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Air Dryer</b> (Wabco R950068)..... <b>BA5379 +</b>	<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Racor R50418)..... <b>BF9898-O</b>
Business Class M2 106 w/Detroit DD5 (5.1L) Eng. (2017-18)	<b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b>	<b>Fuel</b> (High Efficiency) (1R0751).... <b>BF7632</b>
<b>Lube</b> (A9341801410)..... <b>P40017</b>	<b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Disposable Air Hsg.</b> (Thomas 61100179)..... <b>PA3891</b>
<b>Fuel/Water Separator</b> (Racor R61709)..... <b>PF46235</b>	<b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Channel Flow Air</b> (Std. Media) (Don. P607955)..... <b>CA4700 +</b>
<b>Channel Flow Primary Air</b> (Standard Media) (Don. P607955)..... <b>CA4700</b>	<b>Steering</b> (VMLT1808D)..... <b>BT9388</b>	<b>Channel Flow Air</b> (Flame Retardant Media) (Don. P607960) <b>CA5420 +</b>
<b>Channel Flow Primary Air</b> (Flame Retardant Media) (Don. P607960) <b>CA5420</b>	<b>Some Rear Axle</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b>
<b>Secondary Air</b> (Don. P616400)... <b>PA4701</b>	Business Class M2e Hybrid w/Cummins ISB Eng.	<b>Cab Air</b> (Main AirCond. Unit) (VCC36000006)..... <b>PA5359</b>
<b>Cab Air</b> (36000006)..... <b>PA5359</b>	<b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
<b>Air Dryer</b> (Desiccant) (Wabco R950011)..... <b>BA5374 +</b>	<b>Fuel/Water Separator</b> (Fleetguard FS19624)..... <b>PF7748</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>
<b>Air Dryer</b> (Coalescer) (Wabco R950068)..... <b>BA5379 +</b>	<b>Fuel/Water Separator</b> (Racor BR90FRT10)..... <b>BF9871-O</b>	
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Fuel</b> (Fleetguard FF5632)..... <b>BF7940</b>	
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Channel Flow Air</b> (Std. Media) (Don. P607955)..... <b>CA4700 +</b>	
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Channel Flow Air</b> (Flame Retardant Media) (Don. P607960) <b>CA5420 +</b>	
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b>	
	<b>Cab Air</b> (36000006)..... <b>PA5359</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>	<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>	<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>
C2 School Bus w/Cat C7 Eng. (Cont'd)	C2 School Bus w/Cummins ISB Eng. (Cont'd)	Cargo FC80 w/Cummins 6BT5.9 Series Eng.
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965).....	<b>Trans. Spin-on</b> (Fuller 4304827)..	<b>Lube</b> (Chrysler 5083285AA).....
20004	BT223	BT7349
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537966).....	<b>Steering</b> (VMLT1808D).....	<b>Fuel/Water Separator</b> (3925274).....
20017	BT9388	BF1280 +
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966).....	C2 School Bus w/Mercedes MBE900 Eng.	<b>Fuel</b> (3903640).....
20003	<b>F-F Lube Ele.</b> (A0001801709).....	BF788
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537965).....	<b>Opt. B-P Lube Spinner</b>	<b>Radial Seal Air</b> (Don. P527484)...
20016	(A9061810086).....	RS2863
<b>Trans. Spin-on</b> (Allison 29539579).....	<b>Fuel/Water Separator Ele.</b>	<b>Radial Seal XP Air</b> (Don. P527484).....
BT8460	(Fleetguard FS19624).....	RS2863XP
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493).....	<b>Fuel/Water Separator Spin-on</b>	Cargo FC80 w/Cummins ISB (5.9L) Eng.
PT9416-MPG KIT	(Open End for Bowl) (Racor R50418).....	(1999-2006)
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494).....	<b>4 1/16 In. Fuel</b> (A0000901551)....	<b>Lube</b> (3937736).....
PT9415-MPG KIT	PF7735	B7177
<b>Trans. Spin-on</b> (Fuller 4304827)..	<b>7 31/32 In. Fuel</b> (5410900151)....	<b>Fuel/Water Separator Ele.</b>
BT223	PF7761	(3942470).....
<b>Opt. Trans. Spin-on</b> (Fuller 17237).....	<b>Disposable Air Hsg.</b> (Thomas 61100179).....	<b>Fuel/Water Separator Spin-on</b>
B2 +	PA3891	(3954904).....
<b>Steering</b> (VMLT1808D).....	<b>Channel Flow Air</b> (Std. Media) (Don. P607955).....	<b>Fuel/Water Separator Spin-on</b>
BT9388	CA4700 +	(Open End for Bowl) (Bowl Thd. 3 3/4-10 UNS B) (Alliance ABPN122R50419).....
C2 School Bus w/Cummins ISB Eng.	<b>Channel Flow Air</b> (Flame Retardant Media) (Don. P607960).....	BF46098-O
<b>Lube</b> (Fleetguard LF3970).....	<b>Channel Flow Air</b> (Flame Retardant Media) (Don. P607960).....	<b>Fuel/Water Separator Spin-on</b>
B7177	CA5420 +	(w/Sensor Port) (Alliance ABPN122R50419).....
<b>Opt. Fuel/Water Separator</b> (w/Drain) (Racor S3226T).....	<b>Channel Flow Secondary Air</b> (Don. P544432).....	BF1373-SP
BF1347	PA4701	<b>Fuel/Water Separator Spin-on</b>
<b>Opt. Fuel/Water Separator</b> (Open End for Bowl) (Racor S3226T).....	<b>Cab Air</b> (Main AirCond. Unit) (VCC36000006).....	(Fleetguard FS1065).....
BF1347-O	PA5359	BF1378-SPS
<b>Opt. Fuel/Water Separator</b> (w/Sensor Port) (Racor S3226T).....	<b>Air Dryer</b> (AD-IP System) (Bendix 65624).....	<b>Radial Seal Air</b> (Don. P530300)...
BF1373-SP	BA5373	RS2863
<b>Disposable Air Hsg.</b> (Thomas 61100179).....	<b>Air Dryer</b> (AD-9 System) (Bendix 107796).....	<b>Radial Seal XP Air</b> (Don. P530300).....
PA3891	BA5377	RS2863XP
<b>Channel Flow Air</b> (Std. Media) (Don. P607955).....	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965).....	<b>Cab Air</b> (22-44665-000).....
CA4700 +	20004	PA5319
<b>Channel Flow Air</b> (Flame Retardant Media) (Don. P607960).....	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965).....	<b>Air Dryer</b> (Bendix 107796).....
CA5420 +	20016	BA5377
<b>Channel Flow Secondary Air</b> (Don. P544432).....	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966).....	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966).....
PA4701	20003	20003
<b>Cab Air</b> (Main AirCond. Unit) (VCC36000006).....	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966).....	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966).....
PA5359	20017	20017
<b>Air Dryer</b> (AD-9 System) (Bendix 107796).....	<b>Trans. Spin-on</b> (Allison 29539579).....	<b>Trans. Spin-on</b> (Allison 29539579).....
BA5377	BT8460	BT8460
<b>Air Dryer</b> (AD-IP System) (Bendix 65624).....	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493).....	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493).....
BA5373	PT9416-MPG KIT	PT9416-MPG KIT
<b>Crankcase Breather</b> (2007-on) (Fleetguard CV52001).....	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494).....	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494).....
CV15010	PT9415-MPG KIT	PT9415-MPG KIT
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493).....	<b>Trans. Spin-on</b> (Fuller 4304827)..	<b>Trans. Ele.</b> (HT Series) (Fleetguard HF6389).....
PT9416-MPG KIT	BT223	PT8330-MPG
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494).....	<b>Opt. Trans. Spin-on</b> (Fuller 17237).....	<b>Steering</b> (T1808D).....
PT9415-MPG KIT	B2 +	BT9388
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965).....	<b>Steering</b> (VMLT1808D).....	Cargo FC80 w/Cummins ISB 5.9 Eng.
20004	BT9388	(3937736).....
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965).....	Cargo FC80 w/Cat 3126 (7.2L) Eng.	<b>Lube</b> (3937736).....
20016	<b>Lube</b> (Standard Vers.) (1R0739)..	B7177
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966).....	<b>Fuel/Water Separator</b> (175-2949).....	<b>Fuel/Water Separator Ele.</b>
20003	BF1268	(3942470).....
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966).....	<b>Fuel/Water Separator</b> (256-8753).....	PF7777
20017	BF1259	<b>Fuel/Water Separator Spin-on</b>
<b>Trans. Spin-on</b> (Allison 29539579).....	<b>Fuel Ele.</b> (9M2342).....	(3954904).....
BT8460	[2] PF935	BF1293-SPS
<b>Opt. Trans. Spin-on</b> (Fuller 17237).....	<b>Fuel</b> (1R0751).....	<b>Fuel/Water Separator Spin-on</b>
B2 +	BF7632	(Open End for Bowl) (Bowl Thd. 3 3/4-10 UNS B) (Alliance ABPN122R50419).....
	RS2863	BF46098-O
	<b>Radial Seal Air</b> (Don. P527484)...	<b>Fuel/Water Separator Spin-on</b>
	<b>Radial Seal XP Air</b> (Don. P527484).....	(w/Sensor Port) (Alliance ABPN122R50419).....
	RS2863XP	BF1373-SP

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
Cargo FC80 w/Cummins ISB 5.9 Eng. (Cont'd)	Cascadia w/Cat C15 Eng. (Cont'd)	Cascadia w/Cummins ISX 11.9 (11.9L) Eng. (Cont'd)
<b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b>	<b>Coolant</b> (w/11 1/2 Units BTA+) (Fleetguard WF2126)..... <b>BW5086</b>
<b>Fuel</b> (Fleetguard FF5632)..... <b>BF7940</b>	<b>Steering</b> (VML/T1808D)..... <b>BT9388</b>	<b>Coolant</b> (w/o Chemicals) (Fleetguard WF2127)..... <b>B5087</b>
<b>Radial Seal Air</b> (Don. P530300)... <b>RS2863</b>	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Coolant</b> (w/o Chemicals) (Fleetguard WF2122)..... <b>B5088+</b>
<b>Radial Seal XP Air</b> (Don. P530300)..... <b>RS2863XP</b>	Cascadia w/Cummins ISC 8.3 (8.3L) Eng.	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Cab Air</b> (22-44665-000)..... <b>PA5319</b>	<b>Channel Flow Air</b> (P610260)..... <b>CA5790</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b>	<b>Cab Fresh Air</b> (VCCT1000921S). <b>PA4857</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>
<b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	<b>Cab Recirculation Air</b> (VCCT1000906J)..... <b>PA30165</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Steering</b> (T1808D)..... <b>BT9388</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374+</b>	<b>Some Differential</b> (Meritor 3280V8394)..... <b>B233</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	Cascadia w/Cummins ISX 11.9G (11.9L) CNG Eng. (2013-16)
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374+</b>	<b>Dual-Flow Lube</b> (4331005)..... <b>BD7154+</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379+</b>	<b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Fuel/Water Separator</b> (3607140). <b>[2] BF7695</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Channel Flow Air</b> (P610260)..... <b>CA5790</b>
<b>Trans. Ele.</b> (HT Series) (Fleetguard HF6389)..... <b>PT8330-MPG</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>Cab Air</b> (Alliance ABPN10G91559)..... <b>PA4857</b>
<b>Steering</b> (T1808D)..... <b>BT9388</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b>	<b>Air Dryer</b> (Wabco R950068)..... <b>BA5379+</b>
Cascadia w/Cat C15 Eng.	<b>Steering</b> (T1808D)..... <b>BT9388</b>	<b>Coolant</b> (3680434)..... <b>B5087</b>
<b>Lube</b> (1R1808)..... <b>B7299+</b>	<b>Some Differential</b> (Meritor 3280V8394)..... <b>B233</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>
<b>Fuel/Water Separator Ele.</b> (Alliance ABP/N10G-FS19624).... <b>PF7748</b>	Cascadia w/Cummins ISL-G Eng.	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>
<b>Fuel/Water Separator</b> (Alliance ABPN122BR90FRT10)..... <b>BF9871-O</b>	<b>Fuel</b> (Fleetguard NG5900)..... <b>[2] BF7695</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>
<b>Fuel/Water Separator Spin-on</b> (256-8753)..... <b>BF1259</b>	Cascadia w/Cummins ISX 11.9 (11.9L) Eng.	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b>
<b>Fuel</b> (1R0749)..... <b>BF7587+</b>	<b>Dual-Flow Lube</b> (Std. Version) (Fleetguard LF9080)..... <b>BD7154+</b>	<b>Steering</b> (1417927000)..... <b>PT23629</b>
<b>Channel Flow Air</b> (P610260)..... <b>CA5790</b>	<b>Dual-Flow Lube</b> (High Efficiency) (Fleetguard LF9080)..... <b>BD50000</b>	Cascadia w/Cummins ISX 11.9G (11.9L) CNG Eng. (2018)
<b>Cab Air</b> (Fresh Air) (VCCT1000921S)..... <b>PA4857</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19764)..... <b>PF9814</b>	<b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b>
<b>Cab Air</b> (Recirculation) (VCCT1000906J)..... <b>PA30165</b>	<b>Fuel</b> (Standard) (Fleetguard FF5776)..... <b>BF9885+</b>	<b>Fuel/Water Separator</b> (3607140). <b>BF7695</b>
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Fuel</b> (Upgrade) (Fleetguard FF5825NN)..... <b>BF46129</b>	<b>Cab Air</b> (Alliance ABPN10G91559)..... <b>PA4857</b>
<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374+</b>	<b>Channel Flow Air</b> (P610260)..... <b>CA5790</b>	<b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374+</b>
<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Cab Fresh Air</b> (VCCT1000921S). <b>PA4857</b>	<b>Coolant</b> (3680424)..... <b>B5087</b>
<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374+</b>	<b>Cab Recirculation Air</b> (VCCT1000906J)..... <b>PA30165</b>	<b>Trans.</b> (Fuller 4304827)..... <b>BT223</b>
<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379+</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Steering</b> (1417927000)..... <b>PT23629</b>
<b>Crankcase Breather</b> (296-8325).. <b>CV15008</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374+</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
<b>Coolant</b> (Nalcool NF2088)..... <b>BW5200</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	Cascadia w/Cummins ISX 11.9G (11.9L) CNG Eng. (2019)
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374+</b>	<b>Dual-Flow Lube</b> (Fleetguard LF14000NN)..... <b>BD50000</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379+</b>	<b>Fuel</b> (Fleetguard NG5900)..... <b>BF7695</b>
<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>		<b>Cab Air</b> (BOA91559)..... <b>PA4857</b>
		<b>Air Dryer</b> (Wabco R950068A)..... <b>BA5379</b>
		<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>	<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>	<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>
Cascadia w/Cummins ISX 11.9G (11.9L) CNG Eng. (2019) (Cont'd) Opt. Trans. Spin-on (Fuller 17237)..... <b>B2+</b> Steering (1417927000)..... <b>PT23629</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	Cascadia w/Cummins ISX (15.0L) Eng. (Cont'd) <b>Cab Recirculation Air</b> (VCCT1000906J)..... <b>PA30165</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374+</b> <b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b> <b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374+</b> <b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379+</b> <b>Crankcase Breather</b> (Fleetguard CV50634)..... <b>CV15000</b> <b>Coolant</b> (w/o Chemical) (Fleetguard WF2127)..... <b>B5087</b> <b>Coolant</b> (w/1 1/2 Units BTA+) (Fleetguard WF2126)..... <b>BW5086</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Steering</b> (T1808D)..... <b>BT9388</b> <b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (5303604)..... <b>PE17000</b>	Cascadia w/Cummins X12 (11.9L) Eng. (2022) <b>Lube</b> (5575298)..... <b>B40145</b> <b>Fuel</b> (5365988)..... <b>BF46129</b> <b>Cab Air</b> (Alliance ABPN10G91559)..... <b>PA4857</b> <b>ABPN10G91559</b> ..... <b>PA4857</b> <b>Air Dryer</b> (Alliance ABPN10G91559)..... <b>PA4857</b> <b>ABPN10G91559</b> ..... <b>PA4857</b> <b>Air Dryer</b> (4329012482)..... <b>BA5379</b> <b>Coolant</b> (3680434)..... <b>B5087</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
Cascadia w/Cummins ISX 11.9G (11.9L) CNG Eng. (2020) <b>Dual-Flow Lube</b> (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel</b> (Fleetguard NG5900)..... <b>BF7695</b> <b>EnduraCube Air</b> (336867010)..... <b>PA32002</b> <b>Cab Air</b> (Main) (Alliance ABPN10G91559)..... <b>PA4857</b> <b>Air Dryer</b> (Wabco R950068)..... <b>BA5379</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	Cascadia w/Cummins ISX 11.9G (11.9L) CNG Eng. (2021) <b>Lube</b> (5575298)..... <b>B40145</b> <b>Fuel</b> (3607140)..... <b>BF7695</b> <b>Cab Air</b> (Alliance ABPN10G91559)..... <b>PA4857</b> <b>Air Dryer</b> (4329012482)..... <b>BA5379</b> <b>Coolant</b> (3680434)..... <b>B5087</b> <b>Steering</b> (1417927000)..... <b>PT23629</b>	Cascadia w/Cummins X15 (14.9L) Eng. (2018) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (Racor R61709)..... <b>PF46235</b> <b>Fuel</b> (Fleetguard FF5825NN)..... <b>BF46129</b> <b>Channel Flow Air</b> (P610260)..... <b>CA5790</b> <b>Cab Air</b> (Fresh Air) (Alliance ABPN10G91559)..... <b>PA4857</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374+</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2+</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
Cascadia w/Cummins ISX 11.9G (11.9L) CNG Eng. (2022) <b>Cab Air</b> (Alliance ABPN10G91559)..... <b>PA4857</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	Cascadia w/Cummins ISX 15.0 (14.9L) Eng. (2020) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (Fleetguard FS19764)..... <b>PF9814</b> <b>Fuel/Water Separator</b> (Fleetguard FS20083)..... <b>PF46145</b> <b>Fuel</b> (5365988)..... <b>BF46129</b> <b>Cab Air</b> (Main) (Alliance ABPN10G91559)..... <b>PA4857</b> <b>Air Dryer</b> (Wabco R950068)..... <b>BA5379</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827)..... <b>BT223</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	Cascadia w/Cummins X15 (14.9L) Eng. (2019) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (A0000905051)..... <b>PF46145</b> <b>Fuel</b> (5365988)..... <b>BF46129+</b> <b>Cab Air</b> (BOA91559)..... <b>PA4857</b> <b>Air Dryer</b> (Wabco R950068A)..... <b>BA5379+</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
Cascadia w/Cummins ISX (15.0L) Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9080)..... <b>BD7154+</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19764)..... <b>PF9814</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19905)..... <b>PF46092</b> <b>Fuel/Water Separator Spin-on</b> (Racor BR90FRT30)..... <b>BF46016-O</b> <b>Fuel/Water Separator Spin-on</b> (Alliance ABPN122R50550)..... <b>BF9871-O</b> <b>8 27/32 In. Fuel</b> (2010 Emissions) (Fleetguard FF5776)..... <b>BF9885+</b> <b>Fuel</b> (2007 Emissions) (Fleetguard FF2200)..... <b>BF7766</b> <b>8 27/32 In. Fuel</b> (Upgrade) (Fleetguard FF5825NN)..... <b>BF46129</b> <b>11 9/16 In. Fuel</b> (2010 Emissions) (Fleetguard FF5686)..... <b>BF9860+</b> <b>Channel Flow Air</b> (P610260)..... <b>CA5790</b> <b>Cab Fresh Air</b> (VCCT1000921S)..... <b>PA4857</b>	Cascadia w/Cummins ISX 15.0 (14.9L) Eng. (2020) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (A0000905051)..... <b>PF46145</b> <b>Fuel</b> (5365988)..... <b>BF46129</b> <b>Cab Air</b> (Alliance ABPN10G91559)..... <b>PA4857</b> <b>Air Dryer</b> (4329012482)..... <b>BA5379</b> <b>Steering</b> (1417927000)..... <b>PT23629</b>	Cascadia w/Cummins X15 (14.9L) Eng. (2020) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (Fleetguard FS19764)..... <b>PF9814</b> <b>Fuel/Water Separator</b> (Fleetguard FS20083)..... <b>PF46145</b> <b>Fuel</b> (5365988)..... <b>BF46129</b> <b>Cab Air</b> (Main) (Alliance ABPN10G91559)..... <b>PA4857</b> <b>Air Dryer</b> (Wabco R950068)..... <b>BA5379</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827)..... <b>BT223</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
	Cascadia w/Cummins X12 (11.9L) Eng. (2021) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (A0000905051)..... <b>PF46145</b> <b>Fuel</b> (5365988)..... <b>BF46129</b> <b>Cab Air</b> (Alliance ABPN10G91559)..... <b>PA4857</b> <b>Air Dryer</b> (4329012482)..... <b>BA5379</b> <b>Steering</b> (1417927000)..... <b>PT23629</b>	Cascadia w/Cummins X15 (14.9L) Eng. (2021) <b>Lube</b> (5575298)..... <b>B40145</b> <b>Fuel/Water Separator</b> (A0000905051)..... <b>PF46145</b> <b>Fuel</b> (5365988)..... <b>BF46129</b> <b>Cab Air</b> (Alliance ABPN10G91559)..... <b>PA4857</b> <b>Air Dryer</b> (4329012482)..... <b>BA5379</b> <b>Steering</b> (1417927000)..... <b>PT23629</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
Cascadia w/Cummins X15 (14.9L) Eng. (2022)	Cascadia w/Detroit DD13 (12.8L) Eng. (2019)	Cascadia w/Detroit Diesel DD15 Eng. (2008-18)
<b>Lube</b> (5575298)..... <b>B40145</b>	<b>Lube</b> (A4731800409)..... <b>P7505</b>	(Cont'd)
<b>Fuel</b> (5575143)..... <b>BF46248</b>	<b>Fuel/Water Separator</b>	<b>Fuel Kit</b> (2 Filter Kit)
<b>Cab Air</b> (Alliance	(A0000905051)..... <b>PF46145</b>	(A4720900451)..... <b>PF9908 KIT</b>
ABPN10G91559)..... <b>PA4857</b>	<b>Fuel Kit</b> (A4720900651)..... <b>PF9908 KIT</b>	<b>Fuel Kit</b> (3 Filter Kit)
<b>Steering</b> (1417927000)..... <b>PT23629</b>	<b>Cab Air</b> (BOA91559)..... <b>PA4857</b>	(A0000904251)..... <b>PF9924 KIT</b>
<b>Opt. Rear Axle</b> (Meritor	<b>Air Dryer</b> (Wabco R950068A)..... <b>BA5379 +</b>	<b>Channel Flow Air</b> (P610260)..... <b>CA5790</b>
3280V8394)..... <b>B233</b>	<b>Steering</b> (1417927000)..... <b>PT23629</b>	<b>EnduraCube Air</b> (3-36867-010)..... <b>PA32002</b>
Cascadia w/Detroit Diesel DD13 (12.8L) Eng. (2009-18)	<b>Opt. Rear Axle</b> (Meritor	<b>Cab Air</b> (Fresh Air)
<b>Lube</b> (A4731800109)..... <b>P7505</b>	3280V8394)..... <b>B233</b>	(VCC-T-1000921-S)..... <b>PA4857</b>
<b>Fuel/Water Separator</b>	<b>Diesel Exhaust Fluid</b>	<b>Cab Air</b> (Recirculation)
(A0000903651)..... <b>PF9804</b>	(A0001421089)..... <b>PE17002 KIT</b>	(VCC-T-1000906-J)..... <b>PA30165</b>
<b>Fuel/Water Separator</b>	Cascadia w/Detroit DD13 (12.8L) Eng. (2020)	<b>Air Dryer</b> (AD-9 System) (Bendix
(A0000905051)..... <b>PF46145</b>	<b>Lube</b> (To Eng. S/N	107796)..... <b>BA5377</b>
<b>Fuel/Water Separator</b> (Racor	A472910S0690710)	<b>Air Dryer</b> (AD-IS, AD-9si System)
R61709)..... <b>PF46235</b>	(A4731800409)..... <b>P7505</b>	(Bendix 5008414)..... <b>BA5374 +</b>
<b>Fuel Kit</b> (2 Filter Kit)	<b>Fuel/Water Separator</b>	<b>Air Dryer</b> (AD-IP System) (Bendix
(A4720900451)..... <b>PF9908 KIT</b>	(A0000905051)..... <b>PF46145</b>	65624)..... <b>BA5373</b>
<b>Fuel Kit</b> (3 Filter Kit)	<b>Fuel</b> (A4700903151)..... <b>PF9908 KIT</b>	<b>Air Dryer</b> (System Saver 1200)
(A0000904251)..... <b>PF9924 KIT</b>	<b>Cab Air</b> (Main) (Alliance	(Wabco R950011)..... <b>BA5374 +</b>
<b>Channel Flow Air</b> (P610260)..... <b>CA5790</b>	ABPN10G91559)..... <b>PA4857</b>	<b>Air Dryer</b> (SS1200 Plus) (Wabco
<b>Cab Air</b> (Fresh Air)	<b>Air Dryer</b> (Wabco R950068)..... <b>BA5379</b>	R950068)..... <b>BA5379 +</b>
(VCC-T-1000921-S)..... <b>PA4857</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison	<b>Coolant</b> (A4722030255)..... <b>P5092</b>
<b>Cab Air</b> (Recirculation)	29558117)..... <b>PT9416-MPG KIT</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison
(VCC-T-1000906-J)..... <b>PA30165</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison	29540493)..... <b>PT9416-MPG KIT</b>
<b>Air Dryer</b> (AD-9 System) (Bendix	29558118)..... <b>PT9415-MPG KIT</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison
107796)..... <b>BA5377</b>	<b>Trans. Spin-on</b> (Fuller 4304827)..... <b>BT223</b>	29540494)..... <b>PT9415-MPG KIT</b>
<b>Air Dryer</b> (AD-9si System)	<b>Steering</b> (1417927000)..... <b>PT23629</b>	<b>Trans. Spin-on</b> (Fuller 4304827).....
(Bendix 5008414)..... <b>BA5374 +</b>	<b>Opt. Rear Axle</b> (Meritor	17237)..... <b>B2 +</b>
<b>Air Dryer</b> (AD-IP System) (Bendix	3280V8394)..... <b>B233</b>	<b>Steering</b> (1417927000)..... <b>PT23629</b>
65624)..... <b>BA5373</b>	<b>Diesel Exhaust Fluid</b>	<b>Steering</b> (VML/T1808D)..... <b>BT9388</b>
<b>Air Dryer</b> (AD-IS System) (Bendix	(A0001421089)..... <b>PE17002 KIT</b>	<b>Opt. Rear Axle</b> (Meritor
5008414)..... <b>BA5374 +</b>	Cascadia w/Detroit DD13 (12.8L) Eng. (2021)	3280V8394)..... <b>B233</b>
<b>Air Dryer</b> (System Saver 1200)	<b>Fuel/Water Separator</b>	<b>Diesel Exhaust Fluid</b>
(Wabco R950011)..... <b>BA5374 +</b>	(A0000905051)..... <b>PF46145</b>	(A0001420289)..... <b>PE5272</b>
<b>Air Dryer</b> (SS1200 Plus) (Wabco	<b>Fuel</b> (A4700903151)..... <b>PF9908 KIT</b>	<b>Diesel Exhaust Fluid</b>
R950068)..... <b>BA5379 +</b>	<b>Cab Air</b> (Alliance	(A0001420789)..... <b>PE17002 KIT</b>
<b>Coolant</b> (A4722030255)..... <b>P5092</b>	ABPN10G91559)..... <b>PA4857</b>	<b>Diesel Exhaust Fluid</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison	<b>Air Dryer</b> (4329012482)..... <b>BA5379</b>	(A0001421089)..... <b>PE17002 KIT</b>
29540493)..... <b>PT9416-MPG KIT</b>	<b>Steering</b> (1417927000)..... <b>PT23629</b>	Cascadia w/Detroit DD15 (14.8L) Eng. (2019)
<b>Trans. Ele.</b> (4 In. Kit) (Allison	<b>Diesel Exhaust Fluid</b>	<b>Lube</b> (A4731800109)..... <b>P7505</b>
29540494)..... <b>PT9415-MPG KIT</b>	(A0001421089)..... <b>PE17002 KIT</b>	<b>Fuel/Water Separator</b>
<b>Trans. Spin-on</b> (Fuller 4304827)..... <b>BT223</b>	Cascadia w/Detroit DD13 (12.8L) Eng. (2022)	(A0000905051)..... <b>PF46145</b>
<b>Opt. Trans. Spin-on</b> (Fuller	<b>Fuel/Water Separator</b>	<b>Fuel/Water Separator</b> (Racor
17237)..... <b>B2 +</b>	(A0000905051)..... <b>PF46171</b>	R61709)..... <b>PF46235</b>
<b>Steering</b> (1417927000)..... <b>PT23629</b>	<b>Fuel</b> (A4700903151)..... <b>PF9908 KIT</b>	<b>Fuel Kit</b> (A4720900651)..... <b>PF9908 KIT</b>
<b>Steering</b> (T1808D)..... <b>BT9388</b>	<b>Cab Air</b> (Alliance	<b>Cab Air</b> (BOA91559)..... <b>PA4857</b>
<b>Opt. Rear Axle</b> (Meritor	ABPN10G91559)..... <b>PA4857</b>	<b>Air Dryer</b> (Wabco R950068A)..... <b>BA5379 +</b>
3280V8394)..... <b>B233</b>	<b>Steering</b> (1417927000)..... <b>PT23629</b>	<b>Trans. Spin-on</b> (Fuller 4304827)..... <b>BT223</b>
<b>Diesel Exhaust Fluid</b>	<b>Opt. Rear Axle</b> (Meritor	<b>Opt. Trans. Spin-on</b> (Fuller
(A0001421089)..... <b>PE17002 KIT</b>	3280V8394)..... <b>B233</b>	17237)..... <b>B2 +</b>
<b>Diesel Exhaust Fluid</b>	Cascadia w/Detroit Diesel DD15 Eng. (2008-18)	<b>Steering</b> (1417927000)..... <b>PT23629</b>
(A0001420789)..... <b>PE17002 KIT</b>	<b>Lube</b> (A4731800409)..... <b>P7505</b>	<b>Opt. Rear Axle</b> (Meritor
<b>Diesel Exhaust Fluid</b> (2010	<b>Fuel/Water Separator Ele.</b>	3280V8394)..... <b>B233</b>
Emissions) (A0001420289)..... <b>PE5272</b>	(Davco 482) (A0000903651)..... <b>PF9804</b>	<b>Diesel Exhaust Fluid</b>
	<b>Fuel/Water Separator Ele.</b>	(A0001421089)..... <b>PE17002 KIT</b>
	(DDER61709)..... <b>PF46235</b>	
	<b>Fuel/Water Separator Ele.</b>	
	(A0000905051)..... <b>PF46145</b>	


\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
Cascadia w/Detroit DD15 (14.8L) Eng. (2020) Lube (To Eng. S/N A472910S0690710) (A4731800409)..... <b>P7505</b> <b>Fuel/Water Separator</b> (A0000905051)..... <b>PF46145</b> <b>Fuel</b> (A4700903151)..... <b>PF9908 KIT</b> <b>Cab Air</b> (Main) (Alliance ABPN10G91559)..... <b>PA4857</b> <b>Air Dryer</b> (Wabco R950068)..... <b>BA5379</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b>	Cascadia w/Detroit Diesel DD16 (15.6L) Eng. (2011-16) (Cont'd) <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (VMLT1808D)..... <b>BT9388</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Some Differential</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b> Cascadia w/Detroit DD16 (15.6L) Eng. (2017-18) <b>Lube</b> (A4731800109)..... <b>P7505</b> <b>Fuel Kit</b> (2 Filter Kit) (A4720900651)..... <b>PF9908 KIT</b> <b>Channel Flow Air</b> (P610260)..... <b>CA5790</b> <b>Cab Air</b> (Fresh Air) (Alliance ABPN10G91559)..... <b>PA4857</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b>	Cascadia w/Detroit DD16 (15.6L) Eng. (2020) (Cont'd) <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (A0001420289)..... <b>PE5272</b> Cascadia w/Detroit DD16 (15.6L) Eng. (2021) <b>Fuel/Water Separator</b> (A0000905051)..... <b>PF46145</b> <b>Fuel</b> (A4700903151)..... <b>PF9908 KIT</b> <b>Cab Air</b> (Alliance ABPN10G91559)..... <b>PA4857</b> <b>Air Dryer</b> (4329012482)..... <b>BA5379</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> Cascadia w/Detroit DD16 (15.6L) Eng. (2022) <b>Fuel</b> (A4700903151)..... <b>PF9908 KIT</b> <b>Cab Air</b> (Alliance ABPN10G91559)..... <b>PA4857</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> Cascadia w/Detroit Diesel Series 60 (14.0L) Eng. <b>F-F Lube</b> (23518480)..... <b>[2] B495</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (Alliance ABPN122R50419)..... <b>BF1347</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Bowl Thd. 3.75-10 UNS-2B) (Alliance ABPN122R50419)..... <b>BF1347-O</b> <b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (Alliance ABPN122R50419)..... <b>BF1373-SP</b> <b>3 3/4 In. O.D. Fuel/Water Separator Ele.</b> (Fleetguard FS19624)..... <b>PF7748</b> <b>4 3/16 In. O.D. Fuel/Water Separator Ele.</b> (Fleetguard FS19763)..... <b>PF7928</b> <b>Fuel/Water Separator</b> (Alliance ABP/N122BR90FRT30)..... <b>BF46016-O</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Bowl Thd. 3 3/4-10 UNS B) (Alliance ABPN122R50419)..... <b>BF46098-O</b> <b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (Alliance ABP/N122R50421)..... <b>BF1395-SP</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (Alliance ABP/N122R50421)..... <b>BF1265</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Alliance ABP/N122R50421)..... <b>BF1395-O</b>
Cascadia w/Detroit DD15 (14.8L) Eng. (2021) <b>Fuel/Water Separator</b> (A0000905051)..... <b>PF46145</b> <b>Fuel</b> (A4700903151)..... <b>PF9908 KIT</b> <b>Cab Air</b> (Alliance ABPN10G91559)..... <b>PA4857</b> <b>Air Dryer</b> (4329012482)..... <b>BA5379</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b>	Cascadia w/Detroit DD16 (15.6L) Eng. (2019) <b>Lube</b> (A4731800109)..... <b>P7505</b> <b>Fuel</b> (A4720900651)..... <b>PF9908 KIT</b> <b>Channel Flow Air</b> (Don. P618478)..... <b>CA5790</b> <b>Cab Air</b> (BOA91559)..... <b>PA4857</b> <b>Air Dryer</b> (Wabco R950068A)..... <b>BA5379</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (A0001420089)..... <b>PE5272</b>	Cascadia w/Detroit Diesel DD16 (15.6L) Eng. (2011-16) <b>Lube</b> (A4731800409)..... <b>P7505</b> <b>Fuel Kit</b> (2 Filter Kit) (A4720900651)..... <b>PF9908 KIT</b> <b>Fuel Kit</b> (3 Filter Kit) (A0000904251)..... <b>PF9924 KIT</b> <b>Channel Flow Air</b> (Don. P618478)..... <b>CA5790</b> <b>Cab Air</b> (Fresh Air) (VCCT1000921S)..... <b>PA4857</b> <b>Cab Air</b> (Recirculating Air) (VCCT1000906J)..... <b>PA30165</b> <b>Air Dryer</b> (Wabco R950068)..... <b>BA5379 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>
Cascadia w/Detroit DD15 (14.8L) Eng. (2022) <b>Fuel/Water Separator</b> (Racor R61709)..... <b>PF46235</b> <b>Cab Air</b> (Alliance ABPN10G91559)..... <b>PA4857</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	Cascadia w/Detroit DD16 (15.6L) Eng. (2020) <b>Lube</b> (To Eng. S/N A472910S0690710) (A4731800409)..... <b>P7505</b> <b>Fuel/Water Separator</b> (A0000905051)..... <b>PF46145</b> <b>Fuel</b> (A4700903151)..... <b>PF9908 KIT</b> <b>Cab Air</b> (Main) (Alliance ABPN10G91559)..... <b>PA4857</b> <b>Air Dryer</b> (Wabco R950068)..... <b>BA5379</b> <b>Coolant</b> (A4722030355)..... <b>P5092</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	Cascadia w/Detroit Diesel Series 60 (14.0L) Eng. <b>3 3/4 In. O.D. Fuel/Water Separator Ele.</b> (Fleetguard FS19624)..... <b>PF7748</b> <b>4 3/16 In. O.D. Fuel/Water Separator Ele.</b> (Fleetguard FS19763)..... <b>PF7928</b> <b>Fuel/Water Separator</b> (Alliance ABP/N122BR90FRT30)..... <b>BF46016-O</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Bowl Thd. 3 3/4-10 UNS B) (Alliance ABPN122R50419)..... <b>BF46098-O</b> <b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (Alliance ABP/N122R50421)..... <b>BF1395-SP</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (Alliance ABP/N122R50421)..... <b>BF1265</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Alliance ABP/N122R50421)..... <b>BF1395-O</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).


FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
Cascadia w/Detroit Diesel Series 60 (14.0L) Eng. (Cont'd)	Cascadia w/Mercedes-Benz MBE 4000 Eng. (Cont'd)	Cascadia Evolution w/Detroit DD13 Eng. (Cont'd)
<b>Fuel/Water Separator Spin-on</b> (Racor BR90FRT10)..... <b>BF9871-O</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Fuel</b> (2 Filter Kit) (A4720900451)..... <b>PF9908 KIT</b>
<b>Fuel/Water Separator Spin-on</b> (w/Drain) (23535985)..... <b>BF5813 +</b>	<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>	<b>Channel Flow Air</b> (P610260)..... <b>CA5790</b>
<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (23535985).. <b>BF5813-O +</b>	<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>	<b>Cab Air</b> (Fresh Air) (Alliance ABPN10G91559)..... <b>PA4857</b>
<b>P. Fuel</b> (23530706)..... <b>BF5800 +</b>	<b>Coolant</b> (w/o Chemical) (23524403)..... <b>B5134 +</b>	<b>Cab Air</b> (Recirc.) (VCCT1000906J)..... <b>PA30165</b>
<b>S. Fuel</b> (23530645)..... <b>BF5815</b>	<b>Coolant</b> (Controlled Release) (Nalcool NF2088)..... <b>BW5200</b>	<b>Cab Air</b> (Recirc.) (VCCT1000906J)..... <b>PA30165</b>
<b>S. Fuel</b> (23533726)..... <b>BF5816</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Cab Air</b> (Bunk Recirc.) (VCCT1000917R)..... <b>PA30166</b>
<b>Channel Flow Air</b> (P610260)..... <b>CA5790</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Air Dryer</b> (AD-9si System) (Bendix 5008414)..... <b>BA5374 +</b>
<b>Cab Air</b> (Fresh Air) (VCCT1000921S)..... <b>PA4857</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>Air Dryer</b> (System Saver 1200) (Desiccant) (Wabco R950011)..... <b>BA5374 +</b>
<b>Cab Air</b> (Recirculation) (VCCT1000906J)..... <b>PA30165</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Air Dryer</b> (System Saver 1200) (Coalescer) (Wabco R950068)..... <b>BA5379 +</b>
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Steering</b> (VML/T1808D)..... <b>BT9388</b>	<b>Coolant</b> (A4722030255)..... <b>P5092</b>
<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>
<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	Cascadia Evolution w/Cummins ISX Eng.	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>
<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>	<b>Dual-Flow Lube</b> (2882674)..... <b>BD7154 +</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>
<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>	<b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
<b>Coolant</b> (w/Chemical) (Fleetguard WF2071)..... <b>BW5071</b>	<b>Fuel/Water Separator</b> (Fleetguard FS19764)..... <b>PF9814</b>	<b>Steering</b> (1417927000)..... <b>PT23629</b>
<b>Coolant</b> (w/o Chemical) (23524403)..... <b>B5134 +</b>	<b>Fuel</b> (3685306)..... <b>BF9860 +</b>	<b>Steering</b> (T1808D)..... <b>BT9388</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Fuel</b> (2864993)..... <b>BF9885 +</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Channel Flow Air</b> (P610260)..... <b>CA5790</b>	<b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b>
<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>Cab Air</b> (Fresh Air) (Alliance ABPN10G91559)..... <b>PA4857</b>	<b>Diesel Exhaust Fluid</b> (A0001420289)..... <b>PE5272</b>
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Cab Air</b> (Recirc.) (VCCT1000906J)..... <b>PA30165</b>	Cascadia Evolution w/Detroit DD15 Eng.
<b>Steering</b> (VML/T1808D)..... <b>BT9388</b>	<b>Cab Air</b> (Bunk Recirc.) (VCCT1000917R)..... <b>PA30166</b>	<b>Lube</b> (A4731800109)..... <b>P7505</b>
<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b>	<b>Fuel/Water Separator Ele.</b> (Davco 485/487) (A0000903651).. <b>PF9804</b>
Cascadia w/Mercedes-Benz MBE 4000 Eng.	<b>Air Dryer</b> (Wabco R950068)..... <b>BA5379 +</b>	<b>Opt. Fuel/Water Separator Spin-on</b> (Cummins 154789)..... <b>BF957-D +</b>
<b>Lube</b> (A0001802109)..... <b>P7230</b>	<b>Crankcase Breather</b> (3685528).. <b>CV15000</b>	<b>Fuel/Water Separator Ele.</b> (DDER61709)..... <b>PF46235</b>
<b>Fuel/Water Separator Ele.</b> (Alliance ABP/N10G-FS19624)..... <b>PF7748</b>	<b>Coolant</b> (Fleetguard WF2127)..... <b>B5087</b>	<b>Fuel/Water Separator</b> (A0000905051)..... <b>PF46145</b>
<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Alliance ABP/N122R50418)..... <b>BF9898-O</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Fuel</b> (2 Filter Kit) (A4720900451)..... <b>PF9908 KIT</b>
<b>Fuel/Water Separator</b> (Alliance ABPN122BR90FRT30)..... <b>BF46016-O</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Channel Flow Air</b> (P610260)..... <b>CA5790</b>
<b>Fuel</b> (5410900151)..... <b>PF7761</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Cab Air</b> (Fresh Air) (Alliance ABPN10G91559)..... <b>PA4857</b>
<b>Channel Flow Air</b> (P610260)..... <b>CA5790</b>	<b>Steering</b> (T1808D)..... <b>BT9388</b>	<b>Cab Air</b> (Recirc.) (VCCT1000906J)..... <b>PA30165</b>
<b>Cab Air</b> (Fresh Air) (VCCT1000921S)..... <b>PA4857</b>	<b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>	<b>Cab Air</b> (Bunk Recirc.) (VCCT1000917R)..... <b>PA30166</b>
<b>Cab Air</b> (Recirculation) (VCCT1000906J)..... <b>PA30165</b>	Cascadia Evolution w/Detroit DD13 Eng.	<b>Air Dryer</b> (Wabco R950068)..... <b>BA5379 +</b>
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Lube</b> (A4731800109)..... <b>P7505</b>	<b>Air Dryer</b> (AD-9si System) (Bendix 5008414)..... <b>BA5374 +</b>
<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Fuel/Water Separator Ele.</b> (A0000903651)..... <b>PF9804</b>	<b>Coolant</b> (A4722030255)..... <b>P5092</b>
	<b>Fuel/Water Separator</b> (Davco 485) (A0000905051)..... <b>PF46145</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>
	<b>Opt. Fuel/Water Separator Spin-on</b> (Cummins 154789)..... <b>BF957-D +</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>
	<b>Fuel/Water Separator</b> (Racor R61709)..... <b>PF46235</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
Cascadia Evolution w/Detroit DD15 Eng. (Cont'd)	Century Class w/Cat 3406 (14.6L) Eng. (Cont'd)	Century Class w/Cat C11 Eng. (Cont'd)
Opt. Trans. Spin-on (Fuller 17237).....	Fuel/Water Separator (w/Bowl) (Racor R90P).....	Radial Seal Air (Standard) (Don. EAF5069).....
B2 +	BF46072	RS3518
Steering (1417927000).....	Fuel/Water Separator (w/Drain) (Racor R90P).....	Radial Seal XP Air (Upgrade) (Don. EAF5069).....
PT23629	BF1329	RS3518XP
Steering (T1808D).....	Fuel/Water Separator (Sensor Port Thd. 9/16-18) (Racor R90P)..	Cab Air (91559).....
BT9388	BF1329-SP	PA4857
Opt. Rear Axle (Meritor 3280V8394).....	Fuel/Water Separator (Sensor Port Thd. 1/2-20) (Racor R90P)....	Air Dryer (AD-9 System) (Bendix 107796).....
B233	BF1339-SP +	BA5377
Diesel Exhaust Fluid (A0001420289).....	Fuel/Water Separator (Alliance ABPN122R50551).....	Air Dryer (AD-IP System) (Bendix 65624).....
PE5272	BF46016-O	BA5373
Diesel Exhaust Fluid (A0001421089).....	Fuel (1R-0749).....	Air Dryer (AD-IS System) (Bendix 5008414).....
PE17002 KIT	BF7587 +	BA5374 +
Century Class w/Cat 3126 (7.2L) Eng.	Radial Seal Air (Standard) (Don. EAF5069).....	Air Dryer (System Saver 1200) (Wabco R950011).....
Lube (Standard Vers.) (1R0739)..	RS3518	BA5374 +
Lube (Severe Service) (1R0739)..	Radial Seal XP Air (Upgrade) (Don. EAF5069).....	Air Dryer (SS1200 Plus) (Wabco R950068).....
B76 +	RS3518XP	BA5379 +
B76-SS +	Cab Air (22-44665-000).....	BA5379 +
Fuel Ele. (9M2342).....	PA5319	BA5379 +
[2] PF935	Air Dryer (AD-IS System) (Bendix 109994).....	BA5379 +
Fuel Spin-on (1R0751).....	BA5374 +	BA5379 +
BF7632	Air Dryer (AD-9 System) (Bendix 107796).....	BA5379 +
Century Class w/Cat 3176 (10.3L) Eng.	BA5377	BA5379 +
F-F Lube (Std. Efficiency) (1R0716).....	BA5377	BA5379 +
B99 +	BA5377	BA5379 +
F-F Lube (High Efficiency) (1R1808).....	BA5377	BA5379 +
B7299 +	BA5377	BA5379 +
Opt. F-F Lube (1R0713).....	BA5377	BA5379 +
BT230 +	BA5377	BA5379 +
Opt. B-P Lube (1W8845).....	BA5377	BA5379 +
B7577	BA5377	BA5379 +
Fuel/Water Separator (256-8753).....	BA5377	BA5379 +
BF1259	BA5377	BA5379 +
P. Fuel (1R1740).....	BA5377	BA5379 +
BF970 +	BA5377	BA5379 +
S. Fuel (1R0750).....	BA5377	BA5379 +
BF7633 +	BA5377	BA5379 +
Radial Seal O. Air (Standard) (Don. EAF5069).....	BA5377	BA5379 +
RS3518	BA5377	BA5379 +
Radial Seal XP O. Air (Upgrade) (Don. EAF5069).....	BA5377	BA5379 +
RS3518XP	BA5377	BA5379 +
Radial Seal I. Air (Don. P527683).....	BA5377	BA5379 +
RS3519	BA5377	BA5379 +
Century Class w/Cat 3306 Eng.	Century Class w/Cat C10 (10.3L) Eng.	Century Class w/Cat C12 Eng. (Australia)
Lube (Standard Vers.) (1R0739)..	F-F Lube (Std. Efficiency) (1R0716).....	F-F Lube (1R0716).....
B76 +	B99 +	B99 +
Lube (Severe Service) (1R0739)..	F-F Lube (High Efficiency) (1R1808).....	Opt. B-P Lube (1W8845).....
B76-SS +	B7299 +	B7577
Fuel/Water Separator Box-Style (6N7617).....	B-P Lube (1W8845).....	B7577
BF912	B7577	B7577
Fuel/Water Separator Ele. (8N0205).....	Fuel/Water Separator (Alliance ABPN122R50551).....	Fuel/Water Separator (Racor RAI32FRT02).....
PF316	BF46016-O	BF1279
Fuel/Water Separator Spin-on (256-8753).....	P. Fuel (Std. Efficiency) (1R1712).....	Fuel (1R0749).....
BF1259	BF614 +	BF7587 +
PF935	BF614 +	BF7587 +
P. Fuel Ele. (9M2341).....	P. Fuel (High Efficiency) (1R0749).....	BF7587 +
PF935	BF7587 +	BF7587 +
P. Fuel Spin-on (1R1740).....	Radial Seal O. Air (Standard) (Don. EAF5069).....	BF7587 +
BF970 +	RS3518	BF7587 +
S. Fuel (1R0750).....	Radial Seal XP O. Air (Upgrade) (Don. EAF5069).....	BF7587 +
BF7633 +	RS3518XP	BF7587 +
Radial Seal O. Air (Standard) (Don. EAF5069).....	Radial Seal I. Air (Don. P527683).....	BF7587 +
RS3518	RS3519	BF7587 +
Radial Seal XP O. Air (Upgrade) (Don. EAF5069).....	Century Class w/Cat C11 Eng.	BF7587 +
RS3518XP	F-F Lube (To 1/2004) (1R0716)..	BF7587 +
Radial Seal I. Air (Don. P527683).....	F-F Lube (1/2004-on) (1R1808)...	BF7587 +
RS3519	Opt. F-F Lube (249-2347).....	BF7587 +
Century Class w/Cat 3406 (14.6L) Eng.	Some B-P Lube (1W8845).....	BF7587 +
Lube (1R0716).....	B7577	BF7587 +
B99 +	Fuel/Water Separator Ele. (Fleetguard FS19624).....	BF7587 +
Fuel/Water Separator (Fleetguard FS1212).....	PF7748	BF7587 +
BF1212 +	Fuel/Water Separator Spin-on (Alliance ABPN122S3226FL02)....	BF7587 +
Fuel/Water Separator (Open End for Bowl) (Racor R90P).....	BF9898-O +	BF7587 +
BF46083-O	Fuel/Water Separator Spin-on (175-2949).....	BF7587 +
	BF1268	BF7587 +
	Fuel/Water Separator Spin-on (256-8753).....	BF7587 +
	BF1259	BF7587 +
	Fuel (1R0749).....	BF7587 +
	BF7587 +	BF7587 +

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
Century Class w/Cat C12 (12.0L) Eng. (North America) (Cont'd)	Century Class w/Cat C13 (12.5L) Eng. (To 1/2004) (Cont'd)	Century Class w/Cat C15 Eng. (Australia) (Cont'd)
<b>Fuel/Water Separator Spin-on</b> (Racor RAI32FRT02)..... <b>BF1279</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b>	<b>Radial Seal I. Air</b> (Don. P537286)..... <b>RS3519</b>
<b>Fuel/Water Separator Spin-on</b> (Alliance ABPN122R50551)..... <b>BF46016-O</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>Air Dryer</b> (Bendix 109994)..... <b>BA5374+</b>
<b>Fuel</b> (1R-0749)..... <b>BF7587+</b>	<b>Steering</b> (VML/T1808D)..... <b>BT9388</b>	<b>Coolant</b> (Fleetguard WF2077)..... <b>B5134+</b>
<b>Radial Seal O. Air</b> (Standard) (Don. P185069)..... <b>RS3518</b>	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Trans.</b> (Fuller 4304827)..... <b>BT223</b>
<b>Radial Seal XP O. Air</b> (Upgrade) (Don. P185069)..... <b>RS3518XP</b>	Century Class w/Cat C13 (12.5L) Eng. (1/2004-on)	<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>
<b>Opt. Radial Seal I. Air</b> (Don. P537286)..... <b>RS3519</b>	<b>F-F Lube</b> (1R1808)..... <b>B7299+</b>	<b>Some Rear Axle</b> (Meritor 3280-V-8394)..... <b>B233</b>
<b>Cab Air</b> (22-44665-000)..... <b>PA5319</b>	<b>Opt. F-F Lube</b> (249-2347)..... <b>[2] B7402</b>	Century Class w/Cat C15 (14.6L) Eng. (North America)
<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Some B-P Lube</b> (1W8845)..... <b>B7577</b>	<b>Lube</b> (1R1808)..... <b>B7299+</b>
<b>Air Dryer</b> (AD-IS System) (Bendix 109994)..... <b>BA5374+</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19624)..... <b>PF7748</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19624)..... <b>PF7748</b>
<b>Coolant</b> (Fleetguard WF2077)..... <b>B5134+</b>	<b>Fuel/Water Separator Spin-on</b> (Alliance ABPN122S3226FL02)..... <b>BF9898-O+</b>	<b>Fuel/Water Separator Spin-on</b> (256-8753)..... <b>BF1259</b>
<b>Trans.</b> (Fuller 4304827)..... <b>BT223</b>	<b>Fuel/Water Separator Spin-on</b> (175-2949)..... <b>BF1268</b>	<b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1212)..... <b>BF1212+</b>
<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2+</b>	<b>Fuel/Water Separator Spin-on</b> (256-8753)..... <b>BF1259</b>	<b>Fuel/Water Separator Spin-on</b> (Racor 32FRT02)..... <b>BF1376</b>
<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>Fuel</b> (1R0749)..... <b>BF7587+</b>	<b>Fuel</b> (1R0749)..... <b>BF7587+</b>
<b>Some Rear Axle</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Radial Seal Air</b> (Standard) (Don. EAF5069)..... <b>RS3518</b>	<b>Radial Seal Air</b> (Standard) (Don. P527682)..... <b>RS3518</b>
Century Class w/Cat C13 (12.5L) Eng. (To 1/2004)	<b>Radial Seal XP Air</b> (Upgrade) (Don. EAF5069)..... <b>RS3518XP</b>	<b>Radial Seal XP Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b>
<b>F-F Lube</b> (1R0716)..... <b>B99+</b>	<b>Cab Air</b> (91559)..... <b>PA4857</b>	<b>Cab Air</b> (8 5/8 In.) (22-46891-000)..... <b>PA5722</b>
<b>Opt. F-F Lube</b> (249-2347)..... <b>[2] B7402</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Cab Air</b> (10 5/8 In.) (91559)..... <b>PA4857</b>
<b>Some B-P Lube</b> (1W8845)..... <b>B7577</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Cab Air</b> (10 19/32 In.) (22-44665-000)..... <b>PA5319</b>
<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19624)..... <b>PF7748</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374+</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
<b>Fuel/Water Separator Spin-on</b> (Alliance ABPN122S3226FL02)..... <b>BF9898-O+</b>	<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374+</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>
<b>Fuel/Water Separator Spin-on</b> (175-2949)..... <b>BF1268</b>	<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379+</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374+</b>
<b>Fuel/Water Separator Spin-on</b> (256-8753)..... <b>BF1259</b>	<b>Crankcase Breather</b> (C13 Eng. 2007-on) (296-8325)..... <b>CV15008</b>	<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374+</b>
<b>Fuel</b> (1R0749)..... <b>BF7587+</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379+</b>
<b>Radial Seal Air</b> (Standard) (Don. EAF5069)..... <b>RS3518</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Crankcase Breather</b> (2007-on) (296-8325)..... <b>CV15008</b>
<b>Radial Seal XP Air</b> (Upgrade) (Don. EAF5069)..... <b>RS3518XP</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b>	<b>Coolant</b> (Fleetguard WF2077)..... <b>B5134+</b>
<b>Cab Air</b> (91559)..... <b>PA4857</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Steering</b> (VML/T1808D)..... <b>BT9388</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>
<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374+</b>	Century Class w/Cat C15 Eng. (Australia)	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b>
<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374+</b>	<b>Lube</b> (1R0716)..... <b>B99+</b>	<b>Steering</b> (VML/T1808D)..... <b>BT9388</b>
<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379+</b>	<b>Fuel/Water Separator</b> (Racor RAI32FRT02)..... <b>BF1279</b>	<b>Steering</b> (Nelson 87904A)..... <b>PT9354-MPG</b>
<b>Crankcase Breather</b> (C13 Eng. 2007-on) (296-8325)..... <b>CV15008</b>	<b>Fuel</b> (1R0749)..... <b>BF7587+</b>	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Radial Seal O. Air</b> (Standard) (Don. P185069)..... <b>RS3518</b>	Century Class w/Cat C16 (15.8L) Eng.
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Radial Seal XP O. Air</b> (Upgrade) (Don. P185069)..... <b>RS3518XP</b>	<b>Lube</b> (1R0716)..... <b>B99+</b>
		<b>Fuel/Water Separator</b> (Open End for Bowl) (1335673)..... <b>BF1395-O</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>	<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>	<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>
Century Class w/Cat C16 (15.8L) Eng. (Cont'd) <b>Fuel/Water Separator</b> (w/Drain) (1335673)..... <b>BF1265</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (1335673)..... <b>BF1395-SP</b> <b>Fuel/Water Separator</b> (3 11/16 In. O.D.) (256-8753)..... <b>BF1259</b> <b>Fuel</b> (Std. Efficiency) (1R1712).... <b>BF614 +</b> <b>Fuel</b> (High Efficiency) (1R0749).... <b>BF7587 +</b>	Century Class w/Cummins ISX (15.0L) Eng. (Cont'd) <b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> (3101872)..... <b>BF1277-SPS</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1007)..... <b>BF1274-SP</b> <b>Radial Seal O. Air</b> (Standard) (Don. P185069)..... <b>RS3518</b> <b>Radial Seal XP O. Air</b> (Upgrade) (Don. P185069)..... <b>RS3518XP</b> <b>Opt. Radial Seal I. Air</b> (Don. P537286)..... <b>RS3519</b> <b>Cab Air</b> (22-44665-000)..... <b>PA5319</b> <b>Air Dryer</b> (Bendix 109994)..... <b>BA5374 +</b> <b>Coolant</b> (3680434)..... <b>B5087</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Rear Axle</b> (Meritor 3280-V-8394). <b>B233</b>	Century Class w/Cummins N14 (14.0L) Eng. <b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Dual-Flow Lube</b> (Std. Vers.) (3318853)..... <b>BD103 +</b> <b>Dual-Flow Lube</b> (High Velocity) (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R90P)..... <b>BF46083-O</b> <b>Fuel/Water Separator</b> (w/Bowl) (Racor R90P)..... <b>BF46072</b> <b>Fuel/Water Separator</b> (w/Drain) (Racor R90P)..... <b>BF1329</b> <b>Fuel/Water Separator</b> (Sensor Port Thd. 9/16-18) (Racor R90P).. <b>BF1329-SP</b> <b>Fuel/Water Separator</b> (Sensor Port Thd. 1/2-20) (Racor R90P).... <b>BF1339-SP +</b> <b>Fuel/Water Separator</b> (Fleetguard FS1000)..... <b>BF1259</b> <b>Fuel</b> (Fleetguard FF1108)..... <b>BF888</b> <b>Radial Seal Air</b> (Standard) (Don. EAF5069)..... <b>RS3518</b> <b>Radial Seal XP Air</b> (Upgrade) (Don. EAF5069)..... <b>RS3518XP</b> <b>Cab Air</b> (22-44665-000)..... <b>PA5319</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-IS System) (Bendix 109994)..... <b>BA5374 +</b> <b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904A)..... <b>PT9354-MPG</b> <b>Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>
Century Class w/Cummins 4B Series Eng. <b>Lube</b> (3903224)..... <b>BT427 +</b> <b>Fuel/Water Separator</b> (3903202). <b>BF1226</b> <b>Fuel</b> (3903640)..... <b>BF788</b>	Century Class w/Cummins L10 Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>F-F Lube</b> (9 15/16 In.) (Fleetguard LF670SC)..... <b>B196 +</b> <b>F-F Lube</b> (11 9/32 In.) (Fleetguard LF670SC)..... <b>B96 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Fuel/Water Separator</b> (3308638). <b>BF1212 +</b> <b>Fuel</b> (154789)..... <b>BF957-D +</b> <b>Radial Seal O. Air</b> (Standard) (Don. EAF5069)..... <b>RS3518</b> <b>Radial Seal XP O. Air</b> (Upgrade) (Don. EAF5069)..... <b>RS3518XP</b> <b>Radial Seal I. Air</b> (Don. P527683)..... <b>RS3519</b>	Century Class w/Cummins Signature 600 (15.0L) Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9000)..... <b>BD7153 +</b> <b>Fuel/Water Separator</b> (3331096). <b>BF1274-SP</b> <b>Fuel/Water Separator</b> (4010651). <b>BF1277-SPS</b> <b>Radial Seal O. Air</b> (Standard) (Don. EAF5069)..... <b>RS3518</b> <b>Radial Seal XP O. Air</b> (Upgrade) (Don. EAF5069)..... <b>RS3518XP</b> <b>Radial Seal I. Air</b> (Don. P527683)..... <b>RS3519</b>
Century Class w/Cummins ISB (3.9L) Eng. <b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b> <b>Fuel/Water Separator</b> (Fleetguard FS19596)..... <b>BF1293-SPS</b> <b>Fuel</b> (4897833)..... <b>BF7813</b>	Century Class w/Cummins M11 (10.8L) Eng. <b>Dual-Flow Lube</b> (Std. Vers.) (3318853)..... <b>BD103 +</b> <b>Dual-Flow Lube</b> (High Velocity) (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel/Water Separator Ele.</b> (23521528)..... <b>PF7744</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1000)..... <b>BF1259</b> <b>Fuel/Water Separator Spin-on</b> (Alliance ABPN122R50551)..... <b>BF46016-O</b> <b>Radial Seal Air</b> (Standard) (Don. P535717)..... <b>RS3518</b> <b>Radial Seal XP Air</b> (Upgrade) (Don. P535717)..... <b>RS3518XP</b> <b>8 5/8 In. Cab Air</b> (22-46891-000). <b>PA5722</b> <b>10 19/32 In. Cab Air</b> (22-44665-000)..... <b>PA5319</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904A)..... <b>PT9354-MPG</b> <b>Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	Century Class w/Detroit Diesel DD15 (14.8L) Eng. <b>Lube</b> (A4731800109)..... <b>P7505</b> <b>Fuel Kit</b> (A0000904251)..... <b>PF9924 KIT</b> <b>Radial Seal O. Air</b> (Standard) (Don. P527682)..... <b>RS3518</b> <b>Channel Flow Air</b> (P610260)..... <b>CA5790</b> <b>Radial Seal XP O. Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b> <b>Panel Cab Air</b> (BOA91559)..... <b>PA4857</b> <b>Cab Air Foam</b> (Recirculation) (BOA91621)..... <b>PA5773</b>
Century Class w/Cummins ISM (10.8L) Eng. <b>11 25/32 In. Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154 +</b> <b>14 7/32 In. Dual-Flow Lube</b> (Fleetguard LF9000)..... <b>BD7153 +</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (Alliance ABPS3226FL01)..... <b>BF1347</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Alliance ABPS3226FL01)..... <b>BF1347-O</b> <b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (Alliance ABPS3226FL01)..... <b>BF1373-SP</b> <b>Fuel/Water Separator Ele.</b> (Davco 380087)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> (Alliance ABPN122R50551)..... <b>BF46016-O</b> <b>Radial Seal Air</b> (Standard) (Don. P535717)..... <b>RS3518</b> <b>Radial Seal XP Air</b> (Upgrade) (Don. P535717)..... <b>RS3518XP</b> <b>8 5/8 In. Cab Air</b> (22-46891-000). <b>PA5722</b> <b>10 19/32 In. Cab Air</b> (22-44665-000)..... <b>PA5319</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904A)..... <b>PT9354-MPG</b> <b>Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	Century Class w/Cummins ISX (15.0L) Eng. <b>Dual-Flow Lube</b> (3101869)..... <b>BD7154 +</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
Century Class w/Detroit Diesel DD15 (14.8L) Eng. (Cont'd)	Century Class w/Detroit Diesel Series 60 (11.1L),(12.7L), & (14.0L) Engs (North America) (To 12/03) (Cont'd)	Century Class w/Detroit Diesel Series 60 (11.1L),(12.7L), & (14.0L) Engs (North America) (12/03-on) (Cont'd)
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Fuel/Water Separator</b> (w/Drain) (Racor S3226P)..... <b>BF1346</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor S3226P)..... <b>BF1346-O</b>
<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Bowl Thd. 3 3/4-10 UNS B) (Alliance ABPN122R50419)..... <b>BF46098-O</b>	<b>Fuel/Water Separator</b> (w/Sensor Port) (Racor S3226P)..... <b>BF1346-SP</b>
<b>Coolant</b> (A4722030255)..... <b>P5092</b>	<b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (Alliance ABPN122R50419)..... <b>BF1373-SP</b>	<b>Fuel/Water Separator</b> (w/Drain) (Racor S3226P)..... <b>BF1346</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Fuel/Water Separator Spin-on</b> (w/Drain) (23535985)..... <b>BF5813 +</b>	<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Bowl Thd. 3 3/4-10 UNS B) (Alliance ABPN122R50419)..... <b>BF46098-O</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (Alliance ABPN122R50419)..... <b>BF1373-SP</b>	<b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (Alliance ABPN122R50419)..... <b>BF1373-SP</b>
<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>Fuel/Water Separator Spin-on</b> (Alliance ABPN122R50551)..... <b>BF46016-O</b>	<b>Fuel/Water Separator Spin-on</b> (w/Drain) (23535985)..... <b>BF5813 +</b>
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>P. Fuel</b> (23518481)..... <b>BF5800 +</b>	<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (23535985).. <b>BF5813-O +</b>
<b>Steering</b> (VML/T1808D)..... <b>BT9388</b>	<b>S. Fuel</b> (23518482)..... <b>BF5810</b>	<b>Fuel/Water Separator Spin-on</b> (Alliance ABPN122R50551)..... <b>BF46016-O</b>
<b>Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Radial Seal O. Air</b> (Standard) (Don. P527682)..... <b>RS3518</b>	<b>P. Fuel</b> (23518481)..... <b>BF5800 +</b>
Century Class w/Detroit Diesel Series 50 (8.5L) Eng.	<b>Radial Seal XP O. Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b>	<b>S. Fuel</b> (23530645)..... <b>BF5815</b>
<b>Lube</b> (23530573)..... <b>[2] B495</b>	<b>Opt. Radial Seal I. Air</b> (Don. P537286)..... <b>RS3519</b>	<b>S. Fuel</b> (23533726)..... <b>BF5816</b>
<b>Fuel/Water Separator</b> (1-14 Thd.) (23516189)..... <b>BF5812</b>	<b>Cab Air</b> (5/8 In. Thick) (91595).... <b>PA5494</b>	<b>Radial Seal O. Air</b> (Standard) (Don. P527682)..... <b>RS3518</b>
<b>Fuel/Water Separator</b> (w/Drain) (23535985)..... <b>BF5813 +</b>	<b>Cab Air</b> (3/4 In. Thick) (22-44665-000)..... <b>PA5319</b>	<b>Radial Seal XP O. Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (23535985)..... <b>BF5813-O +</b>	<b>Cab Air</b> (1 In. Thick) (91559)..... <b>PA4857</b>	<b>Opt. Radial Seal I. Air</b> (Don. P537286)..... <b>RS3519</b>
<b>P. Fuel</b> (23530706)..... <b>BF5800 +</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Cab Air</b> (5/8 In. Thick) (91595).... <b>PA5494</b>
<b>S. Fuel</b> (23530707)..... <b>BF5810</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Cab Air</b> (3/4 In. Thick) (22-44665-000)..... <b>PA5319</b>
<b>Radial Seal O. Air</b> (Standard) (Don. EAF5069)..... <b>RS3518</b>	<b>Coolant</b> (w/o Chemical) (23524403)..... <b>B5134 +</b>	<b>Cab Air</b> (1 In. Thick) (91559)..... <b>PA4857</b>
<b>Radial Seal XP O. Air</b> (Upgrade) (Don. EAF5069)..... <b>RS3518XP</b>	<b>Coolant</b> (Controlled Release) (Nalcool NF2088)..... <b>BW5200</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
<b>Radial Seal I. Air</b> (Don. P527683)..... <b>RS3519</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Cab Air</b> (5/8 In. Thick) (91595).... <b>PA5319</b>
Century Class w/Detroit Diesel Series 55 (12.0L) Eng.	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Cab Air</b> (3/4 In. Thick) (22-44665-000)..... <b>PA5319</b>
<b>Lube</b> (23550401)..... <b>B7135</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>Cab Air</b> (1 In. Thick) (91559)..... <b>PA4857</b>
<b>Fuel</b> (23530707)..... <b>BF5810</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
<b>Radial Seal O. Air</b> (Standard) (Don. EAF5069)..... <b>RS3518</b>	<b>Steering Ele.</b> (Nelson 87904M).... <b>PT9354-MPG</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>
<b>Radial Seal XP O. Air</b> (Upgrade) (Don. EAF5069)..... <b>RS3518XP</b>	<b>Steering Spin-on</b> (VML/T1808D). <b>BT9388</b>	<b>Coolant</b> (w/o Chemical) (23524403)..... <b>B5134 +</b>
<b>Radial Seal I. Air</b> (Don. P527683)..... <b>RS3519</b>	<b>Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Coolant</b> (Controlled Release) (Nalcool NF2088)..... <b>BW5200</b>
Century Class w/Detroit Diesel Series 60 (11.1L),(12.7L), & (14.0L) Engs (North America) (To 12/03)	Century Class w/Detroit Diesel Series 60 (11.1L),(12.7L), & (14.0L) Engs (North America) (12/03-on)	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Lube</b> (23518480)..... <b>[2] B495</b>	<b>Lube</b> (23518480)..... <b>[2] B495</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>3 3/4 In. O.D. Fuel/Water Separator Ele.</b> (Fleetguard FS19624)..... <b>PF7748</b>	<b>3 3/4 In. O.D. Fuel/Water Separator Ele.</b> (Fleetguard FS19624)..... <b>PF7748</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>
<b>4 3/16 In. O.D. Fuel/Water Separator Ele.</b> (Fleetguard FS19763)..... <b>PF7928</b>	<b>4 3/16 In. O.D. Fuel/Water Separator Ele.</b> (Fleetguard FS19763)..... <b>PF7928</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor S3226P)..... <b>BF1346-O</b>		<b>Steering Ele.</b> (Nelson 87904M).... <b>PT9354-MPG</b>
<b>Fuel/Water Separator</b> (w/Sensor Port) (Racor S3226P)..... <b>BF1346-SP</b>		<b>Steering Spin-on</b> (VML/T1808D). <b>BT9388</b>
		<b>Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>
		Century Class w/Detroit Diesel Series 60 Eng. (Australia)
		<b>Lube</b> (23530573)..... <b>[2] B495</b>
		<b>P. Fuel</b> (23530706)..... <b>BF5800 +</b>
		<b>S. Fuel</b> (23530707)..... <b>BF5810</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
Century Class w/Detroit Diesel Series 60 Eng. (Australia) (Cont'd)	Century Class w/Mercedes-Benz MBE4000 (12.8L) Eng. (Cont'd)	Classic w/Cat C15 Eng.
Single Air (Don. P141228)..... PA2632	Air Dryer (AD-9 System) (Bendix 107796)..... BA5377	Lube (1R1808)..... B7299 +
Radial Seal O. Air (Standard) (Don. P185069)..... RS3518	Air Dryer (AD-IP System) (Bendix 65624)..... BA5373	Fuel/Water Separator Ele. (Fleetguard FS19624)..... PF7748
Radial Seal XP O. Air (Upgrade) (Don. P185069)..... RS3518XP	Air Dryer (AD-IS System) (Bendix 5008414)..... BA5374 +	Fuel/Water Separator Spin-on (Alliance ABPN122-R50404)..... BF1362
Radial Seal I. Air (Don. P537286)..... RS3519	Air Dryer (SS1200 Plus) (Wabco R950068)..... BA5379 +	Fuel/Water Separator Spin-on (256-8753)..... BF1259
Cab Air (8 5/8 In.) (22-46891-000)..... PA5722	Coolant (Fleetguard WF2077)..... B5134 +	Fuel (1R0749)..... BF7587 +
Cab Air (10 19/32 In.) (22-44665-000)..... PA5319	Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	Radial Seal Air (Fleetguard AF25247)..... [2] RS3539
Air Dryer (AD-SP System) (Bendix 109994)..... BA5374 +	Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Cab Air (22-46891-000)..... PA5722
Air Dryer (AD-9 System) (Bendix 107796)..... BA5377	Trans. Spin-on (Fuller 4304827)..... BT223	Air Dryer (AD-9 System) (Bendix 107796)..... BA5377
Coolant (Fleetguard WF2077)..... B5134 +	Opt. Trans. Spin-on (Fuller 17237)..... B2 +	Air Dryer (AD-IP System) (Bendix 65624)..... BA5373
Trans. (Fuller 4304827)..... BT223	Steering Ele. (Nelson 87904M)..... PT9354-MPG	Air Dryer (AD-IS System) (Bendix 5008414)..... BA5374 +
Steering (Nelson 87904M)..... PT9354-MPG	Steering Spin-on (VML/T1808D)..... BT9388	Air Dryer (SS1200 Plus) (Wabco R950068)..... BA5379 +
Some Differential (Meritor 3280-V-8394)..... B233	Some Differential (Meritor 3280-V-8394)..... B233	Crankcase Breather (2968325)..... CV15008
Century Class w/Mercedes-Benz MBE904 (4.3L) Eng.	Champion Bus w/Cummins B5.9 Eng.	Coolant (Controlled Release) (Nalcool NF2088)..... BW5200
5 15/16 In. F-F Lube (1801609).... P7199	Lube (3932217)..... BT339 +	Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT
8 3/8 In. F-F Lube (A0001801709)..... P7188	Fuel/Water Separator (w/Drain) (Fleetguard FS1242)..... BF1249	Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT
Opt. B-P Lube (A9061810086).... BC7326 +	Fuel/Water Separator (Open End for Bowl) (Fleetguard FS1242)..... BF1249-O	Trans. Spin-on (Fuller 4304827)..... BT223
4 1/16 In. Fuel (A0000901551).... PF7735	Fuel/Water Separator (w/Drain & Sensor Port) (Fleetguard FS1242)..... BF1249-SP	Opt. Trans. Spin-on (Fuller 17237)..... B2 +
7 31/32 In. Fuel (A5410920805).... PF7761	Fuel/Water Separator (w/Drain & Sensor Port, High Efficiency Version) (Fleetguard FS1242)..... BF1393-SP	Steering Ele. (Nelson 87904M).... PT9354-MPG
Century Class w/Mercedes-Benz MBE906 (6.4L) Eng.	Fuel (3931063)..... BF788	Steering Spin-on (T1808D)..... BT9388
F-F Lube (A0001801709)..... P7188	Trans. Pan-Type (3.8 In. Pan) (Allison 29540976)..... 19992 +	Some Differential (Meritor 3280-V-8394)..... B233
Opt. B-P Lube (A9061810086).... BC7326 +	Trans. Pan-Type (5.3 In. Pan) (Allison 29538489)..... 19739 +	Classic w/Cummins ISM (10.8L) Eng.
4 1/16 In. Fuel (A0000901551).... PF7735	Trans. Spin-on (Allison 29510922)..... BT8316-MPG	Dual-Flow Lube (3406810)..... BD7153 +
7 31/32 In. Fuel (A5410920805).... PF7761	Trans. Spin-on (ACDelco PF897)..... BT230	Fuel/Water Separator (Alliance ABPN122R50551)..... BF46016-O
Century Class w/Mercedes-Benz MBE4000 (12.8L) Eng.	Classic w/Cat C12 Eng.	Fuel/Water Separator (3406889)..... BF1293-SPS
Lube (1802109)..... P7230	F-F Lube (1R0716)..... B99 +	Classic w/Cummins N14 (14.0L) Eng.
Fuel/Water Separator Ele. (Fleetguard FS19624)..... PF7748	B-P Lube (1W8845)..... B7577	Dual-Flow Lube (3401544)..... BD7309 +
Fuel/Water Separator (Open End for Bowl) (Racor S3226P)..... BF1346-O	Fuel/Water Separator Spin-on (Alliance ABPN122R50551)..... BF46016-O	Lube (Upgrade) (3401544)..... B40142 +
Fuel/Water Separator (w/Sensor Port) (Racor S3226P)..... BF1346-SP	Fuel (1R0712)..... BF614 +	Fuel/Water Separator (3889716)..... BF1259
Fuel/Water Separator (w/Drain) (Racor S3226P)..... BF1346	Classic w/Cat C13 (12.5L) Eng.	Fuel/Water Separator (Alliance ABPN122R50551)..... BF46016-O
Fuel/Water Separator Spin-on (Alliance ABPN122R50551)..... BF46016-O	F-F Lube (1R1808)..... B7299 +	Classic w/Detroit Diesel Series 60 Eng. (To 12/2003)
Fuel (5410900151)..... PF7761	B-P Lube (249-2347)..... B7402	Lube (23527033)..... [2] B495
Radial Seal Air (Standard) (Don. P527682)..... RS3518	Fuel/Water Separator (256-8753)..... BF1259	Fuel/Water Separator Ele. (Davco 382114)..... PF7748
Radial Seal XP Air (Upgrade) (Don. P527682)..... RS3518XP	Fuel (Std. Efficiency) (1R1712).... BF614 +	Fuel/Water Separator Spin-on (Alliance ABPN122R50551)..... BF46016-O
Cab Air (5/8 In. Thick) (91595).... PA5494	Fuel (High Efficiency) (1R0749).... BF7587 +	Conical Air (Don. P522293)..... PA2732
Cab Air (3/4 In. Thick) (22-44665-000)..... PA5319		Radial Seal Air (Don. P534816).... [2] RS3539
Cab Air (1 In. Thick) (91559)..... PA4857		Radial Seal XP Air (Don. P534816)..... [2] RS3539XP
		Cab Air (22-46891-000)..... PA5722
		Air Dryer (AD-9 System) (Bendix 107796)..... BA5377

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).




FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
Classic w/Detroit Diesel Series 60 Eng. (To 12/2003) (Cont'd)	Classic w/Detroit Diesel Series 60 Eng. (12/2006-on)	Classic w/Mercedes-Benz MBE4000 Eng. (Cont'd)
<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Lube</b> (23527033)..... <b>[2] B495</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Fuel/Water Separator Ele.</b> (Davco 382114)..... <b>PF7748</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>	<b>Fuel/Water Separator Spin-on</b> (Alliance ABPN122R50551)..... <b>BF46016-O</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>
<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>	<b>S. Fuel Spin-on</b> (23533726)..... <b>BF5816</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
<b>Coolant</b> (Fleetguard WF2077)..... <b>B5134 +</b>	<b>S. Fuel Spin-on</b> (23530645)..... <b>BF5815</b>	<b>Steering Ele.</b> (Nelson 87904M).... <b>PT9354-MPG</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Conical Air</b> (Don. P522293)..... <b>PA2732</b>	<b>Steering Spin-on</b> (VML/T1808D). <b>BT9388</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Radial Seal Air</b> (Don. P534816).... <b>[2] RS3539</b>	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>
<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>Radial Seal XP Air</b> (Don. P534816)..... <b>[2] RS3539XP</b>	
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Cab Air</b> (22-46891-000)..... <b>PA5722</b>	Classic XL w/Cat C15 Eng.
<b>Steering Ele.</b> (Nelson 87904M).... <b>PT9354-MPG</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Lube</b> (To 1/2004) (1R0716)..... <b>B99 +</b>
<b>Steering Spin-on</b> (VML/T1808D). <b>BT9388</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Lube</b> (1/2004-on) (1R1808)..... <b>B7299 +</b>
<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Fuel/Water Separator</b> (Alliance ABP/S3226FL02)..... <b>BF1346 +</b>
	<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>	<b>Fuel/Water Separator</b> (Alliance ABP/N122-S3226FL02)..... <b>BF9898-O</b>
	<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>	<b>Fuel/Water Separator</b> (311365).... <b>BF1212 +</b>
	<b>Coolant</b> (Fleetguard WF2077)..... <b>B5134 +</b>	<b>Fuel/Water Separator</b> (256-8753)..... <b>BF1259</b>
	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Fuel Spin-on</b> (1R0749)..... <b>BF7587 +</b>
	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>19 3/8 In. Radial Seal Air</b> (Vortox VF120W)..... <b>RS3730</b>
	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>23 23/32 In. Radial Seal Air</b> (Fleetguard AF25247)..... <b>RS3539</b>
	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>24 27/32 In. Radial Seal Air</b> (Don. P537355)..... <b>RS4646</b>
	<b>Steering Ele.</b> (Nelson 87904M).... <b>PT9354-MPG</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
	<b>Steering Spin-on</b> (VML/T1808D). <b>BT9388</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>
	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>
		<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>
Classic w/Detroit Diesel Series 60 Eng. (12/2003-12/2006)	Classic w/Mercedes-Benz MBE4000 Eng. (1802109)..... <b>P7230</b>	<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>
<b>Lube</b> (23527033)..... <b>[2] B495</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19624)..... <b>PF7748</b>	<b>Crankcase Breather</b> (296-8325).. <b>CV15008</b>
<b>Fuel/Water Separator Ele.</b> (Davco 382114)..... <b>PF7748</b>	<b>Fuel/Water Separator Spin-on</b> (Racor BR90FRT30)..... <b>BF46016-O</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Fuel/Water Separator Spin-on</b> (Alliance ABPN122R50551)..... <b>BF46016-O</b>	<b>Fuel</b> (5410900151)..... <b>PF7761</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>S. Fuel Spin-on</b> (23533726)..... <b>BF5816</b>	<b>Axial Seal Air</b> (Don. P153551).... <b>PA2705</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>
<b>S. Fuel Spin-on</b> (23530645)..... <b>BF5815</b>	<b>Radial Seal Air</b> (Fleetguard AF25247)..... <b>[2] RS3539</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
<b>Conical Air</b> (Don. P522293)..... <b>PA2732</b>	<b>Conical Air</b> (Don. P522293)..... <b>PA2732</b>	<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>
<b>Radial Seal Air</b> (Don. P534816).... <b>[2] RS3539</b>	<b>Cab Air</b> (22-46891-000)..... <b>PA5722</b>	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>
<b>Radial Seal XP Air</b> (Don. P534816)..... <b>[2] RS3539XP</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	
<b>Cab Air</b> (22-46891-000)..... <b>PA5722</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	Classic XL w/Cummins ISM (10.8L) Eng.
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Dual-Flow Lube</b> (3406810)..... <b>BD7153 +</b>
<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>	<b>Fuel/Water Separator</b> (Alliance ABPN122R50551)..... <b>BF46016-O</b>
<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>	<b>Fuel/Water Separator</b> (3406889). <b>BF1293-SPS</b>
<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>	<b>Coolant</b> (23524403)..... <b>B5134 +</b>	
<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>		
<b>Coolant</b> (Fleetguard WF2077)..... <b>B5134 +</b>		
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>		
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>		
<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>		
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>		
<b>Steering Ele.</b> (Nelson 87904M).... <b>PT9354-MPG</b>		
<b>Steering Spin-on</b> (VML/T1808D). <b>BT9388</b>		
<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>	<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>	<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>
Classic XL w/Cummins N14 (14.0L) Eng. <b>Dual-Flow Lube</b> (3401544)..... <b>BD7309 +</b> <b>Lube</b> (Upgrade) (3401544)..... <b>B40142 +</b> <b>Fuel/Water Separator</b> (3889716). <b>BF1259</b> <b>Fuel/Water Separator</b> (Alliance ABPN122R50551)..... <b>BF46016-O</b>	Classic XL w/Detroit Diesel Series 60 Eng. (12/2003-12/2006) <b>Lube</b> (23530573)..... <b>[2] B495</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19624)..... <b>PF7748</b> <b>Fuel/Water Separator Spin-on</b> (Alliance ABPN122S3226FL02).... <b>BF9898-O +</b> <b>Fuel/Water Separator Spin-on</b> (Alliance ABP/N122-R50407)..... <b>BF1283-SP +</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (Alliance ABPN122BR90FRT10)..... <b>BF9871-O</b> <b>Fuel/Water Separator Spin-on</b> (Alliance ABPN122R50551)..... <b>BF46016-O</b> <b>P. Fuel</b> (23518481)..... <b>BF5800 +</b> <b>S. Fuel</b> (23518482)..... <b>BF5810</b> <b>Radial Seal O. Air</b> (Standard) (Don. P527682)..... <b>RS3518</b> <b>Radial Seal XP O. Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b> <b>Radial Seal Air</b> (Don. P534816)... <b>[2] RS3539</b> <b>Radial Seal XP Air</b> (Don. P534816)..... <b>[2] RS3539XP</b> <b>Cab Air</b> (22-30530-000)..... <b>CLN&amp;R</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b> <b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b> <b>Coolant</b> (Fleetguard WF2077)..... <b>B5134 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering Ele.</b> (Open Both Ends) (Nelson 83213D)..... <b>PT951</b> <b>Steering Ele.</b> (Open one end) (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Steering Spin-on</b> (VML/T1808D). <b>BT9388</b> <b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	Classic XL w/Detroit Diesel Series 60 Eng. (12/2006-on) (Cont'd) <b>Fuel/Water Separator</b> (Open End for Bowl) (Alliance ABPN122BR90FRT10)..... <b>BF9871-O</b> <b>Fuel/Water Separator Spin-on</b> (Alliance ABPN122R50551)..... <b>BF46016-O</b> <b>P. Fuel</b> (23518481)..... <b>BF5800 +</b> <b>S. Fuel</b> (23533726)..... <b>BF5816</b> <b>S. Fuel</b> (23530645)..... <b>BF5815</b> <b>Radial Seal O. Air</b> (Standard) (Don. P527682)..... <b>RS3518</b> <b>Radial Seal XP O. Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b> <b>Radial Seal Air</b> (Don. P534816)... <b>[2] RS3539</b> <b>Radial Seal XP Air</b> (Don. P534816)..... <b>[2] RS3539XP</b> <b>Cab Air</b> (22-30530-000)..... <b>CLN&amp;R</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b> <b>Air Dryer</b> (AD-IS System) (Bendix 109994)..... <b>BA5374 +</b> <b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b> <b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b> <b>Coolant</b> (Fleetguard WF2077)..... <b>B5134 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering Ele.</b> (Open Both Ends) (Nelson 83213D)..... <b>PT951</b> <b>Steering Ele.</b> (Open one end) (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Steering Spin-on</b> (VML/T1808D). <b>BT9388</b> <b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>
Classic XL w/Detroit Diesel Series 60 Eng. (12/2003)	Classic XL w/Detroit Diesel Series 60 Eng. (12/2006-on)	Columbia w/Cat 3176 (10.3L) Eng. <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b>
Classic XL w/Detroit Diesel Series 60 Eng. (12/2003)	Classic XL w/Detroit Diesel Series 60 Eng. (12/2006-on)	Columbia w/Cat 3406 (14.6L) Eng. <b>F-F Lube</b> (Std. Efficiency) (1R0716)..... <b>B99 +</b> <b>Lube</b> (High Efficiency) (1R1808).. <b>B7299 +</b> <b>Opt. B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Fuel/Water Separator Spin-on</b> (2568753)..... <b>BF1259</b> <b>Fuel/Water Separator Spin-on</b> (Alliance ABPN122R50551)..... <b>BF46016-O</b> <b>P. Fuel</b> (1R1740)..... <b>BF970 +</b> <b>S. Fuel</b> (1R0750)..... <b>BF7633 +</b> <b>Radial Seal Air</b> (Standard) (Don. P527682)..... <b>RS3518</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
Columbia w/Cat 3406 (14.6L) Eng. (Cont'd) <b>Radial Seal XP Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b>	Columbia w/Cat C12 Eng. (Cont'd) <b>Air Dryer</b> (System Saver 1200 Model) (Wabco R950011)..... <b>BA5374 +</b> <b>Coolant</b> (Fleetguard WF2077)..... <b>B5134 +</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	Columbia w/Cat C13 Eng. (To 1/2004) (Cont'd) <b>Steering Spin-on</b> (VML/T1808D). <b>BT9388</b> <b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>
Columbia w/Cat C10 (10.3L) Eng. <b>F-F Lube</b> (Std. Efficiency) (1R0716)..... <b>B99 +</b> <b>F-F Lube</b> (High Efficiency) (1R1808)..... <b>B7299 +</b> <b>B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Fuel/Water Separator</b> (Alliance ABPN122R50551)..... <b>BF46016-O</b> <b>Fuel</b> (Std. Efficiency) (1R1712).... <b>BF614 +</b> <b>Fuel</b> (High Efficiency) (1R0749).... <b>BF7587 +</b> <b>Radial Seal Air</b> (Standard) (Don. P527682)..... <b>RS3518</b> <b>Radial Seal XP Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b>	Columbia w/Cat C13 Eng. (To 1/2004) <b>F-F Lube</b> (1R0716)..... <b>B99 +</b> <b>Opt. F-F Lube</b> (249-2347)..... <b>[2] B7402</b> <b>B-P Lube</b> (9Y4468)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (Davco 382113)..... <b>PF7748</b> <b>Fuel/Water Separator Spin-on</b> (Alliance ABP/S3226FL02)..... <b>BF1346 +</b> <b>Fuel/Water Separator Spin-on</b> (256-8753)..... <b>BF1259</b> <b>Fuel/Water Separator Spin-on</b> (Racor R50404)..... <b>BF1362</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (1335673)..... <b>BF1395-O</b> <b>Fuel/Water Separator</b> (w/Drain) (1335673)..... <b>BF1265</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (1335673)..... <b>BF1395-SP</b> <b>Fuel Ele.</b> (9M2342)..... <b>PF935</b> <b>Fuel Spin-on</b> (1R0749)..... <b>BF7587 +</b> <b>Radial Seal Air</b> (Standard) (Don. P527682)..... <b>RS3518</b> <b>Radial Seal XP Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b> <b>Cab Air</b> (BOA91559)..... <b>PA4857</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b> <b>Crankcase Breather</b> (2007-on) (296-8325)..... <b>CV15008</b> <b>Coolant</b> (w/4 Units BTE) (9N3717)..... <b>BW5137</b> <b>Coolant</b> (w/8 Units BTE) (9N6123)..... <b>BW5139</b> <b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134 +</b> <b>Coolant</b> (Controlled Release) (Nalcool NF2088)..... <b>BW5200</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Steering Spin-on</b> (VML/T1808D). <b>BT9388</b> <b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	Columbia w/Cat C13 Eng. (1/2004-on) <b>F-F Lube</b> (1R1808)..... <b>B7299 +</b> <b>Opt. F-F Lube</b> (249-2347)..... <b>[2] B7402</b> <b>B-P Lube</b> (9Y4468)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (Davco 382113)..... <b>PF7748</b> <b>Fuel/Water Separator Spin-on</b> (Alliance ABP/S3226FL02)..... <b>BF1346 +</b> <b>Fuel/Water Separator Spin-on</b> (256-8753)..... <b>BF1259</b> <b>Fuel/Water Separator Spin-on</b> (Racor R50404)..... <b>BF1362</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (1335673)..... <b>BF1395-O</b> <b>Fuel/Water Separator</b> (w/Drain) (1335673)..... <b>BF1265</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (1335673)..... <b>BF1395-SP</b> <b>Fuel Ele.</b> (9M2342)..... <b>PF935</b> <b>Fuel Spin-on</b> (1R0749)..... <b>BF7587 +</b> <b>Radial Seal Air</b> (Standard) (Don. P527682)..... <b>RS3518</b> <b>Radial Seal XP Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b> <b>Cab Air</b> (BOA91559)..... <b>PA4857</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b> <b>Crankcase Breather</b> (2007-on) (296-8325)..... <b>CV15008</b> <b>Coolant</b> (w/4 Units BTE) (9N3717)..... <b>BW5137</b> <b>Coolant</b> (w/8 Units BTE) (9N6123)..... <b>BW5139</b> <b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134 +</b> <b>Coolant</b> (Controlled Release) (Nalcool NF2088)..... <b>BW5200</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Steering Spin-on</b> (VML/T1808D). <b>BT9388</b> <b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>
Columbia w/Cat C11 Eng. <b>Lube</b> (1R1808)..... <b>B7299 +</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19624)..... <b>PF7748</b> <b>Fuel</b> (1R0749)..... <b>BF7587 +</b> <b>Radial Seal Air</b> (Standard) (Don. P527682)..... <b>RS3518</b> <b>Radial Seal XP Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b> <b>Cab Air</b> (91595)..... <b>PA5494</b> <b>Air Dryer</b> (AD-IS System) (Bendix 109994)..... <b>BA5374 +</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (T1808D)..... <b>BT9388</b>	Columbia w/Cat C12 Eng. <b>F-F Lube</b> (Std. Efficiency) (1R0716)..... <b>B99 +</b> <b>F-F Lube</b> (High Efficiency) (1R1808)..... <b>B7299 +</b> <b>Fuel/Water Separator Ele.</b> (6 29/32 In.) (Fleetguard FS1029W). <b>PF7680</b> <b>Fuel/Water Separator Ele.</b> (7 1/32 In.) (Davco 382113)..... <b>PF7748</b> <b>Opt. Fuel/Water Separator Spin-on</b> (Racor 32FRT02)..... <b>BF1376</b> <b>Fuel/Water Separator Spin-on</b> (Alliance ABPN122R50551)..... <b>BF46016-O</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1212)..... <b>BF1212 +</b> <b>Fuel</b> (Std. Efficiency) (1R1712).... <b>BF614 +</b> <b>Fuel</b> (High Efficiency) (1R0749).... <b>BF7587 +</b> <b>Axial Seal Air</b> (Don. P153551).... <b>PA2705</b> <b>Radial Seal Air</b> (Standard) (Don. P527682)..... <b>RS3518</b> <b>Radial Seal XP Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b> <b>Cab Air</b> (BOA91621)..... <b>PA5773</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-IS System) (Bendix 109994)..... <b>BA5374 +</b>	


+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
Columbia w/Cat C15 Eng. Lube (1R1808)..... B7299 + Fuel/Water Separator Ele. (Davco 382113)..... PF7748 Fuel/Water Separator Spin-on (Racor RK50423)..... BF1370 Fuel/Water Separator Spin-on (256-8753)..... BF1259 Opt. Fuel/Water Separator Spin-on (Racor 32FRT02)..... BF1376 Fuel/Water Separator Spin-on (Fleetguard FS1212)..... BF1212 + Fuel/Water Separator Spin-on (Racor BR90FRT10)..... BF9871-O Fuel/Water Separator Spin-on (Racor R50404)..... BF1362 P. Fuel Ele. (8H7204)..... PF935 P. Fuel Spin-on (1R0749)..... BF7587 + Radial Seal O. Air (Standard) (Don. P527682)..... RS3518 Radial Seal XP O. Air (Upgrade) (Don. P527682)..... RS3518XP Opt. Radial Seal I. Air (Don. P537286)..... RS3519 Cab Air (BOA91559)..... PA4857 Air Dryer (AD-9 System) (Bendix 107796)..... BA5377 Air Dryer (AD-IP System) (Bendix 65624)..... BA5373 Air Dryer (AD-IS System) (Bendix 5008414)..... BA5374 + Air Dryer (System Saver 1200 Model) (Wabco R950011)..... BA5374 + Air Dryer (SS1200 Plus) (Wabco R950068)..... BA5379 + Crankcase Breather (2007-on) (296-8325)..... CV15008 Coolant (Fleetguard WF2077)..... B5134 + Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT Trans. Spin-on (Fuller 4304827)..... BT223 Opt. Trans. Spin-on (Fuller 17237)..... B2 + Steering Ele. (Nelson 87904M)..... PT9354-MPG Steering Spin-on (VML/T1808D)..... BT9388 Some Differential (Meritor 3280-V-8394)..... B233	Columbia w/Cat C16 (15.8L) Eng. (To 1/2004) (Cont'd) Fuel (Std. Efficiency) (1R0712)..... BF614 + Fuel (High Efficiency) (1R0749)..... BF7587 + Radial Seal Air (Standard) (Don. P527682)..... RS3518 Radial Seal XP Air (Upgrade) (Don. P527682)..... RS3518XP Columbia w/Cat C16 (15.8L) Eng. (1/2004-on) Lube (1R1808)..... B7299 + Fuel/Water Separator (Open End for Bowl) (1335673)..... BF1395-O Fuel/Water Separator (w/Drain) (1335673)..... BF1265 Fuel/Water Separator (w/Sensor Port) (1335673)..... BF1395-SP Fuel/Water Separator (3 11/16 In. O.D.) (256-8753)..... BF1259 Fuel (Std. Efficiency) (1R0712)..... BF614 + Fuel (High Efficiency) (1R0749)..... BF7587 + Radial Seal Air (Standard) (Don. P527682)..... RS3518 Radial Seal XP Air (Upgrade) (Don. P527682)..... RS3518XP Columbia w/Cummins 4B Series Eng. Lube (3903224)..... BT427 + Fuel/Water Separator (3903202)..... BF1226 Fuel (3903640)..... BF788 Radial Seal Air (Standard) (Don. P527682)..... RS3518 Radial Seal XP Air (Upgrade) (Don. P527682)..... RS3518XP Columbia w/Cummins ISB Eng. Lube (4897898)..... BT7237 Fuel (4897833)..... BF7813 Radial Seal Air (Standard) (Don. P527682)..... RS3518 Radial Seal XP Air (Upgrade) (Don. P527682)..... RS3518XP Columbia w/Cummins ISL (8.9L) Eng. Dual-Flow Lube (Fleetguard LF9009)..... BD7309 + Fuel/Water Separator (Fleetguard FS1022)..... BF1272-SPS Fuel/Water Separator (Fleetguard FS1065)..... BF1378-SPS Fuel (Fleetguard FF5488)..... BF7815 Fuel (Fleetguard FF5636)..... BF7924 Radial Seal Air (Standard) (Don. P527682)..... RS3518 Radial Seal XP Air (Upgrade) (Don. P527682)..... RS3518XP Columbia w/Cummins ISM (10.8L) Eng. 11 25/32 In. Dual-Flow Lube (Fleetguard LF9001)..... BD7154 + 14 7/32 In. Dual-Flow Lube (Fleetguard LF9000)..... BD7153 +	Columbia w/Cummins ISM (10.8L) Eng. (Cont'd) Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... BD50000 Fuel/Water Separator Ele. (Fleetguard FS1029W)..... PF7680 Fuel/Water Separator Spin-on (Alliance ABPN122R50551)..... BF46016-O Radial Seal Air (Standard) (Don. EAF5069)..... RS3518 Radial Seal XP Air (Upgrade) (Don. EAF5069)..... RS3518XP Cab Air (22-44665-000)..... PA5319 Air Dryer (AD-IS System) (Bendix 109994)..... BA5374 + Air Dryer (AD-IP System) (Bendix 65624)..... BA5373 Opt. Trans. (Fuller 17237)..... B2 + Steering (Nelson 87904A)..... PT9354-MPG Some Differential (Meritor 3280-V-8394)..... B233 Columbia w/Cummins ISX Eng. 11 5/32 In. Dual-Flow Lube (3406809)..... BD7154 + 14 7/32 In. Dual-Flow Lube (3406810)..... BD7153 + Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... BD50000 6 15/32 In. Fuel/Water Separator Ele. (Fleetguard FS19557)..... PF7749 7 1/32 In. Fuel/Water Separator Ele. (Fleetguard FS19624)..... PF7748 Fuel/Water Separator Spin-on (3331096)..... BF1274-SP Radial Seal Air (Standard) (Don. P527682)..... RS3518 Radial Seal XP Air (Upgrade) (Don. P527682)..... RS3518XP Cab Air (BOA91559)..... PA4857 Air Dryer (AD-9 System) (Bendix 107796)..... BA5377 Air Dryer (AD-IS System) (Bendix 109994)..... BA5374 + Coolant (11/16-16 Thd.) (Fleetguard WF2077)..... B5134 + Coolant (M36 x 2.0 Thd.) (Fleetguard WF2127)..... B5087 Opt. Trans. (Fuller 17237)..... B2 + Steering (Nelson 87904A)..... PT9354-MPG Some Differential (Meritor 3280-V-8394)..... B233 Columbia w/Cummins N14 (14.0L) Eng. F-F Lube (Fleetguard LF670SC)..... B196 + B-P Lube (3304232)..... B7577 Dual-Flow Lube (3318853)..... BD103 + Fuel/Water Separator Ele. (Davco 382113)..... PF7748 Fuel/Water Separator Ele. (301SD19B)..... PF7680

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
Columbia w/Cummins N14 (14.0L) Eng. (Cont'd)	Columbia w/Detroit Diesel Series 50 (8.5L) Eng. (Cont'd)	Columbia w/Detroit Diesel Series 60 Eng. (To 12/2003) (Cont'd)
<b>Fuel/Water Separator Spin-on</b> (Alliance ABPN122R50551)..... <b>BF46016-O</b>	<b>Radial Seal Air</b> (Standard) (Don. P527682)..... <b>RS3518</b>	<b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134 +</b>
<b>Radial Seal Air</b> (Standard) (Don. P527682)..... <b>RS3518</b>	<b>Radial Seal XP Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b>	<b>Coolant</b> (Controlled Release) (Nalcool NF2088)..... <b>BW5200</b>
<b>Radial Seal XP Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b>	Columbia w/Detroit Diesel Series 55 (12.0L) Eng.	<b>Coolant</b> (w/8 units BTA +) (Fleetguard WF2073)..... <b>BW5073</b>
<b>Cab Air</b> (91595)..... <b>PA5494</b>	<b>Lube</b> (23550401)..... <b>B7135</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Fuel</b> (23530707)..... <b>BF5810</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Radial Seal Air</b> (Standard) (Don. P527682)..... <b>RS3518</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>
<b>Coolant</b> (Fleetguard WF2077)..... <b>B5134 +</b>	<b>Radial Seal XP Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	Columbia w/Detroit Diesel Series 60 Eng. (To 12/2003)	<b>Steering Ele.</b> (Nelson 87904M).... <b>PT9354-MPG</b>
<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>Lube</b> (23527033)..... <b>[2] B495</b>	<b>Steering Spin-on</b> (VML/T1808D). <b>BT9388</b>
<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b>	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>
Columbia w/Cummins M11 Eng.	<b>Fuel/Water Separator Ele.</b> (23521528)..... <b>PF7744</b>	Columbia w/Detroit Diesel Series 60 Eng. (12/2003-on)
<b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19763)..... <b>PF7928</b>	<b>Lube</b> (23527033)..... <b>[2] B495</b>
<b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b>	<b>Fuel/Water Separator Ele.</b> (Davco 382113)..... <b>PF7748</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b>
<b>Fuel/Water Separator Spin-on</b> (3329289)..... <b>BF1259</b>	<b>Fuel/Water Separator</b> (w/Drain) (Racor S3226P)..... <b>BF1346</b>	<b>Fuel/Water Separator Ele.</b> (23521528)..... <b>PF7744</b>
<b>Radial Seal Air</b> (Standard) (Don. P527682)..... <b>RS3518</b>	<b>Fuel/Water Separator</b> (w/Sensor Port) (Racor S3226P)..... <b>BF1346-SP</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19763)..... <b>PF7928</b>
<b>Radial Seal XP Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor S3226P)..... <b>BF1346-O</b>	<b>Fuel/Water Separator Ele.</b> (Davco 382113)..... <b>PF7748</b>
Columbia w/Detroit Diesel DD15 Eng.	<b>Fuel/Water Separator</b> (Open End for Bowl) (Alliance ABPN122BR90FRT10)..... <b>BF9871-O</b>	<b>Fuel/Water Separator</b> (w/Drain) (Racor S3226P)..... <b>BF1346</b>
<b>Lube</b> (A4731800109)..... <b>P7505</b>	<b>Fuel/Water Separator Spin-on</b> (Alliance ABPN122R50551)..... <b>BF46016-O</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b>
<b>Fuel/Water Separator</b> (A0000903651)..... <b>PF9804</b>	<b>Fuel/Water Separator Spin-on</b> (Racor R50407)..... <b>BF1283-SP +</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19763)..... <b>PF7928</b>
<b>Fuel Kit</b> (A0000904251)..... <b>PF9924 KIT</b>	<b>Fuel/Water Separator Spin-on</b> (w/Drain) (23535985)..... <b>BF5813 +</b>	<b>Fuel/Water Separator Ele.</b> (Davco 382113)..... <b>PF7748</b>
<b>Radial Seal O. Air</b> (Standard) (Don. P527682)..... <b>RS3518</b>	<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (23535985).. <b>BF5813-O +</b>	<b>Fuel/Water Separator</b> (w/Drain) (Racor S3226P)..... <b>BF1346</b>
<b>Radial Seal XP O. Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b>	<b>P. Fuel Spin-on</b> (23518481)..... <b>BF5800 +</b>	<b>Fuel/Water Separator</b> (w/Sensor Port) (Racor S3226P)..... <b>BF1346-SP</b>
<b>Channel Flow Air</b> (P610260)..... <b>CA5790</b>	<b>S. Fuel</b> (23518482)..... <b>BF5810</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor S3226P)..... <b>BF1346-O</b>
<b>Cab Air</b> (BOA91559)..... <b>PA4857</b>	<b>Conical Air</b> (Don. P522293)..... <b>PA2732</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (Alliance ABPN122BR90FRT10)..... <b>BF9871-O</b>
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Radial Seal Air</b> (Standard) (Don. P527682)..... <b>RS3518</b>	<b>Fuel/Water Separator Spin-on</b> (Alliance ABPN122R50551)..... <b>BF46016-O</b>
<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Radial Seal XP Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b>	<b>Fuel/Water Separator Spin-on</b> (Racor R50407)..... <b>BF1283-SP +</b>
<b>Coolant</b> (A4722030255)..... <b>P5092</b>	<b>Cab Air</b> (Square) (BOA91559)..... <b>PA4857</b>	<b>Fuel/Water Separator Spin-on</b> (Alliance ABPN122R50551)..... <b>BF46016-O</b>
<b>Trans.</b> (Fuller 4304827)..... <b>BT223</b>	<b>Cab Air</b> (Irregular) (BOA91621).... <b>PA5773</b>	<b>Fuel/Water Separator Spin-on</b> (Racor R50407)..... <b>BF1283-SP +</b>
<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Fuel/Water Separator Spin-on</b> (w/Drain) (23535985)..... <b>BF5813 +</b>
<b>Steering</b> (VML/T1808D)..... <b>BT9388</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (23535985).. <b>BF5813-O +</b>
<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>P. Fuel Spin-on</b> (23518481)..... <b>BF5800 +</b>
Columbia w/Detroit Diesel Series 50 (8.5L) Eng.	<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>	<b>S. Fuel</b> (23533726)..... <b>BF5816</b>
<b>Lube</b> (23530573)..... <b>[2] B495</b>		<b>S. Fuel</b> (23530645)..... <b>BF5815</b>
<b>Fuel/Water Separator</b> (23516189)..... <b>BF5812</b>		<b>Conical Air</b> (Don. P522293)..... <b>PA2732</b>
<b>Fuel/Water Separator</b> (w/Drain) (23535985)..... <b>BF5813 +</b>		<b>Radial Seal Air</b> (Standard) (Don. P527682)..... <b>RS3518</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (23535985)..... <b>BF5813-O +</b>		<b>Radial Seal XP Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b>
<b>P. Fuel</b> (23530706)..... <b>BF5800 +</b>		<b>Cab Air</b> (Square) (BOA91559)..... <b>PA4857</b>
<b>S. Fuel</b> (23530707)..... <b>BF5810</b>		<b>Cab Air</b> (Irregular) (BOA91621).... <b>PA5773</b>
		<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
		<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>
		<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>
		<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>
		<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>	<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>	<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>
Columbia w/Detroit Diesel Series 60 Eng. (12/2003-on) (Cont'd)	Columbia w/Mercedes-Benz MBE4000 Eng. (Cont'd)	Condor w/Cat C7 Eng. (To 1/2004) (Cont'd)
<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Radial Seal XP O. Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b>
<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Radial Seal I. Air</b> (Don. P527683)..... <b>RS3519</b>
<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>	<b>Air Dryer</b> (System Saver 1200 Model) (Wabco R950011)..... <b>BA5374 +</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
<b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134 +</b>	<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29526899)..... <b>PT9416-MPG KIT</b>
<b>Coolant</b> (Controlled Release) (Nalcool NF2088)..... <b>BW5200</b>	<b>Coolant</b> (Fleetguard WF2077)..... <b>B5134 +</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29526898)..... <b>PT9415-MPG KIT</b>
<b>Coolant</b> (w/8 units BTA +) (Fleetguard WF2073)..... <b>BW5073</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Steering</b> (Nelson 83804E)..... <b>P528</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Trans. Spin-on</b> (Fuller 4304827)..... <b>BT223</b>	Condor w/Cat C7 Eng. (1/2004-on)
<b>Trans. Spin-on</b> (Fuller 4304827)..... <b>BT223</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Lube</b> (1R1807)..... <b>B7700 +</b>
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Steering Ele.</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>Fuel/Water Separator</b> (Alliance ABPN12232FRT02)..... <b>BF1376</b>
<b>Steering Ele.</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>Steering Spin-on</b> (VML/T1808D)..... <b>BT9388</b>	<b>P. Fuel</b> (1R0751)..... <b>BF7632</b>
<b>Steering Spin-on</b> (VML/T1808D)..... <b>BT9388</b>	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>P. Fuel</b> (1R0759)..... <b>BF7634</b>
<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	Columbia w/Mercedes-Benz OM906 (6.4L) Eng.	<b>Radial Seal O. Air</b> (Standard) (Don. P527682)..... <b>RS3518</b>
Columbia w/Mercedes-Benz MBE460 Eng.	<b>Lube</b> (A0001801609)..... <b>P7199</b>	<b>Radial Seal XP O. Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b>
<b>Lube</b> (A0001802909)..... <b>P7230</b>	<b>Fuel/Water Separator</b> (w/Drain) (A0004771302)..... <b>BF1363</b>	<b>Radial Seal I. Air</b> (Don. P527683)..... <b>RS3519</b>
<b>Fuel/Water Separator</b> (Fleetguard FS19624)..... <b>PF7748</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
<b>Fuel</b> (A5410900151)..... <b>PF7761</b>	<b>Fuel</b> (A9060920305)..... <b>PF7735</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29526899)..... <b>PT9416-MPG KIT</b>
<b>Radial Seal Air</b> (Standard) (Don. P527682)..... <b>RS3518</b>	Condor w/Cat 3126 Eng. (To 1/2004)	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29526898)..... <b>PT9415-MPG KIT</b>
<b>Radial Seal XP Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b>	<b>Lube</b> (Standard Vers.) (1R0739)..... <b>B76</b>	<b>Steering</b> (Nelson 83804E)..... <b>P528</b>
<b>Cab Air</b> (BOA91559)..... <b>PA4857</b>	<b>Fuel</b> (1R0751)..... <b>BF7632</b>	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>
<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Air</b> (Don. P116918)..... <b>PA2317 +</b>	Condor w/Cat C9 Eng. (To 1/2004)
<b>Coolant</b> (Fleetguard WF2077)..... <b>B5134 +</b>	Condor w/Cat 3126 Eng. (1/2004-on)	<b>Lube</b> (1R0716)..... <b>B99 +</b>
<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	<b>Lube</b> (1R1807)..... <b>B7700 +</b>	<b>Fuel/Water Separator</b> (Alliance ABPN122-R50417)..... <b>BF1283-SP +</b>
<b>Steering</b> (T1808D)..... <b>BT9388</b>	<b>Fuel</b> (1R0751)..... <b>BF7632</b>	<b>P. Fuel</b> (1R0751)..... <b>BF7632</b>
<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Air</b> (Don. P116918)..... <b>PA2317 +</b>	<b>P. Fuel</b> (1R0759)..... <b>BF7634</b>
Columbia w/Mercedes-Benz MBE4000 Eng.	Condor w/Cat 3406 Eng.	<b>Radial Seal O. Air</b> (Standard) (Don. P527682)..... <b>RS3518</b>
<b>Lube</b> (A0001802109)..... <b>P7230</b>	<b>Lube</b> (1R0716)..... <b>B99 +</b>	<b>Radial Seal XP O. Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b>
<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19624)..... <b>PF7748</b>	<b>Lube</b> (High Efficiency) (1R1808)..... <b>B7299 +</b>	<b>Radial Seal I. Air</b> (Don. P527683)..... <b>RS3519</b>
<b>Fuel/Water Separator Spin-on</b> (Alliance ABPS3226FL02)..... <b>BF1346 +</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1029W)..... <b>PF7680</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
<b>Fuel/Water Separator Spin-on</b> (Racor BR90FRT30)..... <b>BF46016-O</b>	<b>Fuel Ele.</b> (8H7204)..... <b>PF935</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Fuel</b> (A5410900151)..... <b>PF7761</b>	<b>Air</b> (Don. P153551)..... <b>PA2705</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Radial Seal Air</b> (Standard) (Don. P527682)..... <b>RS3518</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Steering</b> (Nelson 83284D)..... <b>PT8487</b>
<b>Radial Seal XP Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b>	<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>
<b>Cab Air</b> (BOA91559)..... <b>PA4857</b>	<b>Steering</b> (Nelson 83213M)..... <b>P528</b>	Condor w/Cat C7 Eng. (To 1/2004)
<b>Cab Air</b> (BOA91621)..... <b>PA5773</b>	Condor w/Cat C7 Eng. (To 1/2004)	<b>Lube</b> (Standard Vers.) (1R0739)..... <b>B76 +</b>
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Lube</b> (Severe Service) (1R0739)..... <b>B76-SS +</b>	<b>Fuel/Water Separator</b> (Alliance ABPN12232FRT02)..... <b>BF1376</b>
	<b>Fuel/Water Separator</b> (Alliance ABPN12232FRT02)..... <b>BF1376</b>	<b>P. Fuel</b> ..... <b>BF7632</b>
	<b>P. Fuel</b> ..... <b>BF7632</b>	<b>P. Fuel</b> (1R0759)..... <b>BF7634</b>
	<b>P. Fuel</b> (1R0759)..... <b>BF7634</b>	<b>Radial Seal O. Air</b> (Standard) (Don. P527682)..... <b>RS3518</b>
	<b>Radial Seal O. Air</b> (Standard) (Don. P527682)..... <b>RS3518</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
Condor w/Cat C9 Eng. (1/2004-on) <b>Lube</b> (1R1808)..... <b>B7299 +</b> <b>Fuel/Water Separator</b> (Alliance ABPN122-R50417)..... <b>BF1283-SP +</b> <b>P. Fuel</b> (1R0751)..... <b>BF7632</b> <b>P. Fuel</b> (1R0759)..... <b>BF7634</b> <b>Radial Seal O. Air</b> (Standard) (Don. P527682)..... <b>RS3518</b> <b>Radial Seal XP O. Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b> <b>Radial Seal I. Air</b> (Don. P527683)..... <b>RS3519</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (Nelson 83284D)..... <b>PT8487</b> <b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	Condor w/Cat C11 (11.1L) Eng. (To 1/2004) (Cont'd) <b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b> Condor w/Cat C11 (11.1L) Eng. (1/2004-on) <b>Lube</b> (1R1808)..... <b>B7299 +</b> <b>Fuel/Water Separator</b> (w/Drain) (ABPN122S3226FL01)..... <b>BF1347</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (ABPN122S3226FL01).. <b>BF1347-O</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (ABPN122S3226FL01)..... <b>BF1373-SP</b> <b>Fuel/Water Separator</b> (Alliance ABPN122-32FRT02)..... <b>BF1376</b> <b>Fuel/Water Separator</b> (Racor RAI32FRT02)..... <b>BF1279</b> <b>Fuel</b> (1R0749)..... <b>BF7587 +</b> <b>Radial Seal O. Air</b> (Standard) (Don. P527682)..... <b>RS3518</b> <b>Radial Seal XP O. Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b> <b>Radial Seal I. Air</b> (Don. P527683)..... <b>RS3519</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (Fleetguard WF2077)..... <b>B5134 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 83284D)..... <b>PT8487</b> <b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	Condor w/Cat C12 (12.0L) Eng. (To 1/2004) (Cont'd) <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 83284D)..... <b>PT8487</b> <b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b> Condor w/Cat C12 (12.0L) Eng. (1/2004-on) <b>Lube</b> (1R1808)..... <b>B7299 +</b> <b>Fuel/Water Separator</b> (w/Drain) (ABPN122S3226FL01)..... <b>BF1347</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (ABPN122S3226FL01).. <b>BF1347-O</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (ABPN122S3226FL01)..... <b>BF1373-SP</b> <b>Fuel/Water Separator</b> (Alliance ABPN122-32FRT02)..... <b>BF1376</b> <b>Fuel/Water Separator</b> (Racor RAI32FRT02)..... <b>BF1279</b> <b>Fuel</b> (1R0749)..... <b>BF7587 +</b> <b>Radial Seal O. Air</b> (Standard) (Don. P527682)..... <b>RS3518</b> <b>Radial Seal XP O. Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b> <b>Radial Seal I. Air</b> (Don. P527683)..... <b>RS3519</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (Fleetguard WF2077)..... <b>B5134 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 83284D)..... <b>PT8487</b> <b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>
Condor w/Cat C10 Eng. <b>F-F Lube</b> (1R0716)..... <b>B99 +</b> <b>Opt. B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Fuel</b> (1R0712)..... <b>BF614 +</b> <b>Air</b> (Don. P116918)..... <b>PA2317 +</b> <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Condor w/Cat C11 (11.1L) Eng. (To 1/2004) <b>Lube</b> (1R0716)..... <b>B99 +</b> <b>Fuel/Water Separator</b> (w/Drain) (ABPN122S3226FL01)..... <b>BF1347</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (ABPN122S3226FL01).. <b>BF1347-O</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (ABPN122S3226FL01)..... <b>BF1373-SP</b> <b>Fuel/Water Separator</b> (Alliance ABPN122-32FRT02)..... <b>BF1376</b> <b>Fuel/Water Separator</b> (Racor RAI32FRT02)..... <b>BF1279</b> <b>Fuel</b> (1R0749)..... <b>BF7587 +</b> <b>Radial Seal O. Air</b> (Standard) (Don. P527682)..... <b>RS3518</b> <b>Radial Seal XP O. Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b> <b>Radial Seal I. Air</b> (Don. P527683)..... <b>RS3519</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (Fleetguard WF2077)..... <b>B5134 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 83284D)..... <b>PT8487</b>	Condor w/Cat C12 (12.0L) Eng. (To 1/2004) <b>Lube</b> (1R0716)..... <b>B99 +</b> <b>Fuel/Water Separator</b> (w/Drain) (ABPN122S3226FL01)..... <b>BF1347</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (ABPN122S3226FL01).. <b>BF1347-O</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (ABPN122S3226FL01)..... <b>BF1373-SP</b> <b>Fuel/Water Separator</b> (Alliance ABPN122-32FRT02)..... <b>BF1376</b> <b>Fuel/Water Separator</b> (Racor RAI32FRT02)..... <b>BF1279</b> <b>Fuel</b> (1R0749)..... <b>BF7587 +</b> <b>Radial Seal O. Air</b> (Standard) (Don. P527682)..... <b>RS3518</b> <b>Radial Seal XP O. Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b> <b>Radial Seal I. Air</b> (Don. P527683)..... <b>RS3519</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (Fleetguard WF2077)..... <b>B5134 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
Condor w/Cat C13 Eng. (1/2004-on) <b>Lube</b> (1R1808)..... <b>B7299 +</b> <b>Fuel/Water Separator</b> (w/Drain) (ABPN122S3226FL01)..... <b>BF1347</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (ABPN122S3226FL01).. <b>BF1347-O</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (ABPN122S3226FL01)..... <b>BF1373-SP</b> <b>Fuel/Water Separator</b> (Alliance ABPN122-32FRT02)..... <b>BF1376</b> <b>Fuel/Water Separator</b> (Racor RAI32FRT02)..... <b>BF1279</b> <b>Fuel</b> (1R0749)..... <b>BF7587 +</b> <b>Radial Seal O. Air</b> (Standard) (Don. P527682)..... <b>RS3518</b> <b>Radial Seal XP O. Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b> <b>Radial Seal I. Air</b> (Don. P527683)..... <b>RS3519</b>		

+ See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
Condor w/Cat C13 Eng. (1/2004-on) (Cont'd) <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (Fleetguard WF2077)..... <b>B5134 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 83284D)..... <b>PT8487</b> <b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	Condor w/Cummins ISC 8.3 (8.3L) Eng. (Cont'd) <b>Fuel</b> (3959612)..... <b>BF7815</b> <b>Radial Seal O. Air</b> (Standard) (Don. P527682)..... <b>RS3518</b> <b>Radial Seal XP O. Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b> <b>Radial Seal I. Air</b> (Don. P527683)..... <b>RS3519</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (Nelson 83284D)..... <b>PT8487</b> <b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	Condor w/Cummins ISX (15.0L) Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154 +</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b> <b>Air</b> (Don. P153551)..... <b>PA2705</b> <b>Cab Air</b> (22-46891-000)..... <b>PA5722</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 83213M)..... <b>P528</b>
Condor w/Cat C13 Eng. (To 1/2004) <b>Lube</b> (1R0716)..... <b>B99 +</b> <b>Fuel/Water Separator</b> (w/Drain) (ABPN122S3226FL01)..... <b>BF1347</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (ABPN122S3226FL01)..... <b>BF1347-O</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (ABPN122S3226FL01)..... <b>BF1373-SP</b> <b>Fuel/Water Separator</b> (Alliance ABPN122-32FRT02)..... <b>BF1376</b> <b>Fuel/Water Separator</b> (Racor RAI32FRT02)..... <b>BF1279</b> <b>Fuel</b> (1R0749)..... <b>BF7587 +</b> <b>Radial Seal O. Air</b> (Standard) (Don. P527682)..... <b>RS3518</b> <b>Radial Seal XP O. Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b> <b>Radial Seal I. Air</b> (Don. P527683)..... <b>RS3519</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (Fleetguard WF2077)..... <b>B5134 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 83284D)..... <b>PT8487</b> <b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	Condor w/Cummins ISL 8.9 (8.9L) Eng. (3318853)..... <b>BD103 +</b> <b>Dual-Flow Lube</b> (High Velocity) (3401544)..... <b>BD7309 +</b> <b>Lube</b> (Upgrade) (3401544)..... <b>B40142 +</b> <b>Fuel/Water Separator</b> (w/Drain) (3355903)..... <b>BF1249</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (3355903)..... <b>BF1249-O</b> <b>Fuel/Water Separator</b> (w/Drain & Sensor Port) (3355903)..... <b>BF1249-SP</b> <b>Fuel/Water Separator</b> (w/Drain & Sensor Port, High Efficiency Version) (3355903)..... <b>BF1393-SP</b> <b>Fuel/Water Separator</b> (w/o SP) (Fleetguard FS1000)..... <b>BF1259</b> <b>Radial Seal O. Air</b> (Standard) (Don. P527682)..... <b>RS3518</b> <b>Radial Seal XP O. Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b> <b>Radial Seal I. Air</b> (Don. P527683)..... <b>RS3519</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (Nelson 83284D)..... <b>PT8487</b> <b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	Condor w/Cummins M11 Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> (3329289)..... <b>BF1259</b> <b>Air</b> (Don. P153551)..... <b>PA2705</b> <b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (83213M)..... <b>P528</b>
Condor w/Cummins 6C Series Eng. <b>F-F Lube</b> (3313281)..... <b>B205 +</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Fuel/Water Separator</b> (3925274)..... <b>BF1280 +</b> <b>S. Fuel</b> (3903640)..... <b>BF788</b>	Condor w/Cummins ISM 10.8 (10.8L) Eng. <b>Dual-Flow Lube</b> (3406809)..... <b>BD7154 +</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (3406889)..... <b>BF1293-SPS</b>	Condor w/Detroit Series 60 Eng. <b>Lube</b> (23530573)..... [2] <b>B495</b> <b>Fuel/Water Separator Ele.</b> (23521528)..... <b>PF7744</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>Air</b> (Don. P153551)..... <b>PA2705</b> <b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (Fleetguard WF2077)..... <b>B5134 +</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 83213M)..... <b>P528</b>
Condor w/Cummins C8.3G (8.3L) Eng. <b>F-F Lube</b> (3313281)..... <b>B205 +</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b>	Condor w/Cummins ISM 10.8 (10.8L) Eng. <b>Dual-Flow Lube</b> (3406809)..... <b>BD7154 +</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (3406889)..... <b>BF1293-SPS</b>	Coronado w/Cat C15 (14.6L) Eng. (To 1/2004) <b>Lube</b> (1R0716)..... <b>B99 +</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19624)..... <b>PF7748</b> <b>Fuel/Water Separator Ele.</b> (Davco 380087)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> (256-8753)..... <b>BF1259</b> <b>Fuel/Water Separator Spin-on</b> (Alliance ABP/S3226FL02)..... <b>BF1346 +</b> <b>Fuel/Water Separator Spin-on</b> (1752949)..... <b>BF1268</b> <b>Fuel/Water Separator Spin-on</b> (311365)..... <b>BF1212 +</b> <b>Fuel/Water Separator</b> (Alliance ABPN122BR90FRT10)..... <b>BF9871-O</b> <b>Fuel Spin-on</b> (1R0749)..... <b>BF7587 +</b> <b>Radial Seal Air</b> (Standard) (Don. EAF5069)..... <b>RS3518</b> <b>Radial Seal XP Air</b> (Upgrade) (Don. EAF5069)..... <b>RS3518XP</b> <b>Cab Air</b> (BOA91559)..... <b>PA4857</b>

+ See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
Coronado w/Cat C15 (14.6L) Eng. (To 1/2004) (Cont'd)	Coronado w/Cat C15 (14.6L) Eng. (1/2004-on) (Cont'd)	Coronado w/Cat C16 (15.8L) Eng. (To 01/2004) (Cont'd)
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Air Dryer</b> (AD-SP System) (Wabco R950011)..... <b>BA5374 +</b>	<b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134 +</b>
<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>	<b>Coolant</b> (Controlled Release) (Nalcool NF2088)..... <b>BW5200</b>
<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Crankcase Breather</b> (C15 Eng. 2007-on) (296-8325)..... <b>CV15008</b>	<b>Coolant</b> (4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>
<b>Air Dryer</b> (AD-SP System) (Wabco R950011)..... <b>BA5374 +</b>	<b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134 +</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>	<b>Coolant</b> (Controlled Release) (Nalcool NF2088)..... <b>BW5200</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Crankcase Breather</b> (C15 Eng. 2007-on) (296-8325)..... <b>CV15008</b>	<b>Coolant</b> (4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>
<b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134 +</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
<b>Coolant</b> (Controlled Release) (Nalcool NF2088)..... <b>BW5200</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>
<b>Coolant</b> (4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>Steering</b> (VML/T1808D)..... <b>BT9388</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	Coronado w/Cat C16 (15.8L) Eng. (01/2004-on)
<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>Steering</b> (VML/T1808D)..... <b>BT9388</b>	<b>Lube</b> (1R1808)..... <b>B7299 +</b>
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19624)..... <b>PF7748</b>
<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	Coronado w/Cat C16 (15.8L) Eng. (To 01/2004)	<b>Fuel/Water Separator Ele.</b> (Davco 380087)..... <b>PF7680</b>
<b>Steering</b> (VML/T1808D)..... <b>BT9388</b>	<b>Lube</b> (1R0716)..... <b>B99 +</b>	<b>Fuel/Water Separator Spin-on</b> (256-8753)..... <b>BF1259</b>
<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19624)..... <b>PF7748</b>	<b>Fuel/Water Separator Spin-on</b> (Alliance ABP/S3226FL02)..... <b>BF1346 +</b>
Coronado w/Cat C15 (14.6L) Eng. (1/2004-on)	<b>Fuel/Water Separator Ele.</b> (Davco 380087)..... <b>PF7680</b>	<b>Fuel/Water Separator Spin-on</b> (1752949)..... <b>BF1268</b>
<b>Lube</b> (1R1808)..... <b>B7299 +</b>	<b>Fuel/Water Separator Spin-on</b> (256-8753)..... <b>BF1259</b>	<b>Fuel/Water Separator Spin-on</b> (311365)..... <b>BF1212 +</b>
<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19624)..... <b>PF7748</b>	<b>Fuel/Water Separator Spin-on</b> (Alliance ABP/S3226FL02)..... <b>BF1346 +</b>	<b>Fuel/Water Separator</b> (Alliance ABPN122BR90FRT10)..... <b>BF9871-O</b>
<b>Fuel/Water Separator Ele.</b> (Davco 380087)..... <b>PF7680</b>	<b>Fuel/Water Separator Spin-on</b> (1752949)..... <b>BF1268</b>	<b>Fuel Spin-on</b> (1R0749)..... <b>BF7587 +</b>
<b>Fuel/Water Separator Spin-on</b> (256-8753)..... <b>BF1259</b>	<b>Fuel/Water Separator Spin-on</b> (311365)..... <b>BF1212 +</b>	<b>Radial Seal Air</b> (Standard) (Don. EAF5069)..... <b>RS3518</b>
<b>Fuel/Water Separator Spin-on</b> (Alliance ABP/S3226FL02)..... <b>BF1346 +</b>	<b>Fuel/Water Separator</b> (Alliance ABPN122BR90FRT10)..... <b>BF9871-O</b>	<b>Radial Seal XP Air</b> (Upgrade) (Don. EAF5069)..... <b>RS3518XP</b>
<b>Fuel/Water Separator Spin-on</b> (1752949)..... <b>BF1268</b>	<b>Fuel Spin-on</b> (1R0749)..... <b>BF7587 +</b>	<b>Cab Air</b> (BOA91559)..... <b>PA4857</b>
<b>Fuel/Water Separator Spin-on</b> (311365)..... <b>BF1212 +</b>	<b>Radial Seal Air</b> (Standard) (Don. EAF5069)..... <b>RS3518</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
<b>Fuel/Water Separator</b> (Alliance ABPN122BR90FRT10)..... <b>BF9871-O</b>	<b>Radial Seal XP Air</b> (Upgrade) (Don. EAF5069)..... <b>RS3518XP</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>
<b>Fuel Spin-on</b> (1R0749)..... <b>BF7587 +</b>	<b>Cab Air</b> (BOA91559)..... <b>PA4857</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>
<b>Radial Seal Air</b> (Standard) (Don. EAF5069)..... <b>RS3518</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Air Dryer</b> (AD-SP System) (Wabco R950011)..... <b>BA5374 +</b>
<b>Radial Seal XP Air</b> (Upgrade) (Don. EAF5069)..... <b>RS3518XP</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>
<b>Cab Air</b> (BOA91559)..... <b>PA4857</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Crankcase Breather</b> (C15 Eng. 2007-on) (296-8325)..... <b>CV15008</b>
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Air Dryer</b> (AD-SP System) (Wabco R950011)..... <b>BA5374 +</b>	<b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134 +</b>
<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>	<b>Coolant</b> (Controlled Release) (Nalcool NF2088)..... <b>BW5200</b>
<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Crankcase Breather</b> (C15 Eng. 2007-on) (296-8325)..... <b>CV15008</b>	<b>Coolant</b> (4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>	<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>	<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>
Coronado w/Cat C16 (15.8L) Eng. (01/2004-on) (Cont'd) <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Steering</b> (VMLT1808D)..... <b>BT9388</b> <b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	Coronado w/Cummins ISX 15.0 (14.9L) Eng. (2018) <b>Dual-Flow Lube</b> (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (Alliance ABPN122R50550)..... <b>BF9871-O</b> <b>Fuel Spin-on</b> (Standard) (Fleetguard FF5776)..... <b>BF9885 +</b> <b>Fuel Spin-on</b> (Upgrade) (Fleetguard FF5825NN)..... <b>BF46129</b> <b>EnduraCube Air</b> (336867010).... <b>PA32002</b> <b>Cab Air</b> (N10G36000006)..... <b>PA5359</b> <b>Air Dryer</b> (Wabco R950068)..... <b>BA5379 +</b> <b>Crankcase Breather</b> (Fleetguard CV50634)..... <b>CV15000</b> <b>Coolant Spin-on</b> (Fleetguard WF2127)..... <b>B5087</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>	Coronado w/Cummins X15 (14.9L) Eng. (2018) (Cont'd) <b>Crankcase Breather</b> (Fleetguard CV50634)..... <b>CV15000</b> <b>Coolant Spin-on</b> (Fleetguard WF2127)..... <b>B5087</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>
Coronado w/Cummins ISX 15.0 (14.9L) Eng. (2011-17) <b>11 7/8 In. Dual-Flow Lube</b> (3406809)..... <b>BD7154 +</b> <b>14 In. Dual-Flow Lube</b> (3406810)..... <b>BD7153 +</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19763)..... <b>PF7928</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19764)..... <b>PF9814</b> <b>Fuel/Water Separator Spin-on</b> (3331096)..... <b>BF1274-SP</b> <b>Fuel</b> (Fleetguard FF5686)..... <b>BF9860 +</b> <b>Fuel</b> (Fleetguard FF2200)..... <b>BF7766</b> <b>Radial Seal Air</b> (Standard) (Don. P535717)..... <b>RS3518</b> <b>Radial Seal XP Air</b> (Upgrade) (Don. P535717)..... <b>RS3518XP</b> <b>EnduraCube Air</b> (3-36867-010)... <b>[2] PA32002</b> <b>Cab Air</b> (91559)..... <b>PA4857</b> <b>Cab Air</b> (BOA91621)..... <b>PA5773</b> <b>Cab Air</b> (36000006)..... <b>PA5359</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b> <b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b> <b>Crankcase Breather</b> (3685528)... <b>CV15000</b> <b>Coolant</b> (Fleetguard WF2126)..... <b>BW5086</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Steering</b> (T1808D)..... <b>BT9388</b> <b>Some Rear Axle</b> (Meritor 3280-V-8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (2880298).. <b>PE17000</b>	Coronado w/Cummins ISX 15.0 (14.9L) Eng. (2019) <b>Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (Alliance ABPN122R50550)..... <b>BF9871-O</b> <b>Fuel</b> (5365988)..... <b>BF46129</b> <b>EnduraCube Air</b> (336867002).... <b>PA32002</b> <b>Cab Air</b> (Fresh Air) (36000006).... <b>PA5359</b> <b>Cab Air</b> (Recirculation Air) (Alliance ABPN10G91621)..... <b>PA5773</b> <b>Air Dryer</b> (Wabco R950068A).... <b>BA5379 +</b> <b>Trans.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	Coronado w/Cummins X15 (14.9L) Eng. (2019) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (Alliance ABPN122R50550)..... <b>BF9871-O</b> <b>Fuel</b> (5365988)..... <b>BF46129 +</b> <b>EnduraCube Air</b> (Don. P616380) <b>PA32002</b> <b>Cab Air</b> (Fresh Air) (ABPN10G36000006)..... <b>PA5359</b> <b>Cab Air</b> (Recirculation Air) (ABPN10G91621)..... <b>PA5773</b> <b>Air Dryer</b> (Wabco R950068A).... <b>BA5379 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (1417927000)..... <b>PT23629</b>
	Coronado w/Cummins ISX 15.0 (14.9L) Eng. (2019) <b>Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (Alliance ABPN122R50550)..... <b>BF9871-O</b> <b>Fuel</b> (5365988)..... <b>BF46129</b> <b>EnduraCube Air</b> (336867002).... <b>PA32002</b> <b>Cab Air</b> (Fresh Air) (36000006).... <b>PA5359</b> <b>Cab Air</b> (Recirculation Air) (Alliance ABPN10G91621)..... <b>PA5773</b> <b>Air Dryer</b> (Wabco R950068A).... <b>BA5379 +</b> <b>Trans.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	Coronado w/Detroit DD13 (12.8L) Eng. (2010-17) <b>Lube</b> (A4731800109)..... <b>P7505</b> <b>Fuel Kit</b> (2 Filter Kit) (A4720900651)..... <b>PF9908 KIT</b> <b>Fuel Kit</b> (3 Filter Kit) (A0000904251)..... <b>PF9924 KIT</b> <b>EnduraCube Air</b> (336867010).... <b>[2] PA32002</b> <b>Cab Air</b> (BOA91559)..... <b>PA4857</b> <b>Cab Air</b> (36000006)..... <b>PA5359</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b> <b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Steering</b> (T1808D)..... <b>BT9388</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
Coronado w/Detroit DD13 (12.8L) Eng. (2010-17) (Cont'd)	Coronado w/Detroit DD13 (12.8L) Eng. (2019) (Cont'd)	Coronado w/Detroit DD15 (14.8L) Eng. (2018) (Cont'd)
Some Rear Axle (Meritor 3280-V-8394)..... <b>B233</b>	Diesel Exhaust Fluid (A0001421089)..... <b>PE17002 KIT</b>	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2+</b>
Diesel Exhaust Fluid (A0001421089)..... <b>PE17002 KIT</b>	Coronado w/Detroit DD15 (14.8L) Eng. (2010-17)	Steering (T1808D)..... <b>BT9388</b>
Coronado w/Detroit DD13 (12.8L) Eng. (2018)	Lube (A4731800109)..... <b>P7505</b>	Steering (1417927000)..... <b>PT23629</b>
Lube (A4731800109)..... <b>P7505</b>	Fuel/Water Separator (A0000903651)..... <b>PF9804</b>	Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>
Opt. Fuel/Water Separator (A0000903651)..... <b>PF9804</b>	Fuel (2 Filter Kit) (A4720900651)..... <b>PF9908 KIT</b>	Diesel Exhaust Fluid (A0001421089)..... <b>PE17002 KIT</b>
Fuel/Water Separator (A0000905051)..... <b>PF46145</b>	Fuel (3 Filter Kit) (A0000904251)..... <b>PF9924 KIT</b>	Diesel Exhaust Fluid (A0001420789)..... <b>PE17002 KIT</b>
Fuel/Water Separator (Racor R61709)..... <b>PF46235</b>	EnduraCube Air (336867010)..... <b>[2] PA32002</b>	Coronado w/Detroit DD15 (14.8L) Eng. (2019)
Fuel Kit (2 Filter Kit) (A4720900651)..... <b>PF9908 KIT</b>	Cab Air (ABPN10G36000006)..... <b>PA5359</b>	Lube (A4731800109)..... <b>P7505</b>
Fuel Kit (3 Filter Kit) (A0000904251)..... <b>PF9924 KIT</b>	Cab Air (BOA91559)..... <b>PA4857</b>	Fuel/Water Separator (A0000905051)..... <b>PF46145</b>
EnduraCube Air (336867010)..... <b>PA32002</b>	Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	Fuel Kit (A4720900651)..... <b>PF9908 KIT</b>
Cab Air (N10G36000006)..... <b>PA5359</b>	Air Dryer (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	EnduraCube Air (Don. P616380)..... <b>PA32002</b>
Air Dryer (Bendix 107794)..... <b>BA5377</b>	Air Dryer (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	Cab Air (Fresh Air) (ABPN10G36000006)..... <b>PA5359</b>
Air Dryer (Wabco R950068)..... <b>BA5379 +</b>	Air Dryer (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>	Cab Air (Recirculation Air) (ABPN10G91621)..... <b>PA5773</b>
Coolant (A4722030255)..... <b>P5092</b>	Air Dryer (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>	Air Dryer (Wabco R950068A)..... <b>BA5379 +</b>
Trans. Ele. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	Coolant (A4722030255)..... <b>P5092</b>	Trans. (Fuller 4304827)..... <b>BT223</b>
Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	Steering (1417927000)..... <b>PT23629</b>
Trans. Spin-on (Fuller 4304827)..... <b>BT223</b>	Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>
Opt. Trans. Spin-on (Fuller 17237)..... <b>B2+</b>	Trans. Spin-on (Fuller 4304827)..... <b>BT223</b>	Diesel Exhaust Fluid (A0001421089)..... <b>PE17002 KIT</b>
Steering (T1808D)..... <b>BT9388</b>	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2+</b>	Coronado w/Detroit DD15 (14.8L) Eng. (2020)
Steering (1417927000)..... <b>PT23629</b>	Steering (1417927000)..... <b>PT23629</b>	Lube (To Eng. S/N A472910S0690710) (A4731800409)..... <b>P7505</b>
Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	Steering (T1808D)..... <b>BT9388</b>	Fuel/Water Separator (A0000903651)..... <b>PF9804</b>
Diesel Exhaust Fluid (A0001421089)..... <b>PE17002 KIT</b>	Some Rear Axle (Meritor 3280-V-8394)..... <b>B233</b>	Fuel (A4700903151)..... <b>PF9908 KIT</b>
Diesel Exhaust Fluid (A0001420089)..... <b>PE5272</b>	Diesel Exhaust Fluid (A0001421089)..... <b>PE17002 KIT</b>	EnduraCube Air (336867010)..... <b>PA32002</b>
Diesel Exhaust Fluid (A0001420789)..... <b>PE17002 KIT</b>	Diesel Exhaust Fluid (A0001420289)..... <b>PE5272</b>	Cab Air (36000006)..... <b>PA5359</b>
Coronado w/Detroit DD13 (12.8L) Eng. (2019)	Coronado w/Detroit DD15 (14.8L) Eng. (2018)	Air Dryer (Wabco R950068)..... <b>BA5379</b>
Lube (A4731800409)..... <b>P7505</b>	Lube (A4731800409)..... <b>P7505</b>	Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>
Fuel/Water Separator (A0000905051)..... <b>PF46145</b>	Fuel/Water Separator (A0000903651)..... <b>PF9804</b>	Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>
Fuel Kit (A4720900651)..... <b>PF9908 KIT</b>	Fuel/Water Separator (Racor R61709)..... <b>PF46235</b>	Trans. Spin-on (Fuller 4304827)..... <b>BT223</b>
EnduraCube Air (Don. P616380)..... <b>PA32002</b>	Fuel (2 Filter Kit) (A4720900651)..... <b>PF9908 KIT</b>	Steering (1417927000)..... <b>PT23629</b>
Cab Air (Fresh Air) (ABPN10G36000006)..... <b>PA5359</b>	Fuel (3 Filter Kit) (A0000904251)..... <b>PF9924 KIT</b>	Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>
Cab Air (Recirculation Air) (ABPN10G91621)..... <b>PA5773</b>	EnduraCube Air (336867010)..... <b>PA32002</b>	Diesel Exhaust Fluid (A0001421089)..... <b>PE17002 KIT</b>
Air Dryer (Wabco R950068A)..... <b>BA5379 +</b>	Cab Air (36000006)..... <b>PA5359</b>	Coronado w/Detroit DD16 (15.6L) Eng. (2011-17)
Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	Air Dryer (Bendix 107794)..... <b>BA5377</b>	Lube (A4731800409)..... <b>P7505</b>
Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	Air Dryer (Wabco R950068)..... <b>BA5379 +</b>	Fuel/Water Separator (A0000903651)..... <b>PF9804</b>
Steering (1417927000)..... <b>PT23629</b>	Coolant (A4722030255)..... <b>P5092</b>	Fuel (2 Filter Kit) (A4720900651)..... <b>PF9908 KIT</b>
Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	Trans. Ele. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	Fuel (3 Filter Kit) (A0000904251)..... <b>PF9924 KIT</b>
	Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	EnduraCube Air (336867010)..... <b>[2] PA32002</b>
	Trans. Spin-on (Fuller 4304827)..... <b>BT223</b>	Cab Air (ABPN10G36000006)..... <b>PA5359</b>
		Cab Air (BOA91559)..... <b>PA4857</b>

\* See Product Guide for Variations of This Number. Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>	<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>	<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>
Coronado w/Detroit DD16 (15.6L) Eng. (2011-17) (Cont'd)	Coronado w/Detroit DD16 (15.6L) Eng. (2019) (Cont'd)	Coronado w/Detroit Diesel Series 60 Eng. (To 12/2003) (Cont'd)
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Cab Air</b> (Fresh Air) (ABPN10G3600006)..... <b>PA5359</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>
<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Cab Air</b> (Recirculation Air) (ABPN10G91621)..... <b>PA5773</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>
<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Air Dryer</b> (Wabco R950068A)..... <b>BA5379 +</b>	<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>
<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>	<b>Trans.</b> (Fuller 4304827)..... <b>BT223</b>	<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>
<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>	<b>Steering</b> (1417927000)..... <b>PT23629</b>	<b>Coolant</b> (w/2 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>
<b>Coolant</b> (A4722030255)..... <b>P5092</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	<b>Coolant</b> (Controlled Release) (23516489)..... <b>BW5200</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b>	<b>Coolant</b> (w/o Chemical) (23524403)..... <b>B5134 +</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Coronado w/Detroit DD16 (15.6L) Eng. (2020)	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Trans. Spin-on</b> (Fuller 4304827)..... <b>BT223</b>	<b>Lube</b> (To Eng. S/N A472910S0690710) (A4731800409)..... <b>P7505</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Fuel</b> (A4700903151)..... <b>PF9908 KIT</b>	<b>Trans. Spin-on</b> (Fuller 4304827)..... <b>BT223</b>
<b>Steering</b> (1417927000)..... <b>PT23629</b>	<b>EnduraCube Air</b> (336867010)..... <b>PA32002</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
<b>Steering</b> (T1808D)..... <b>BT9388</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>	<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>
<b>Some Rear Axle</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Air Dryer</b> (Wabco R950068)..... <b>BA5379</b>	<b>Steering</b> (VML/T1808D)..... <b>BT9388</b>
<b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b>	<b>Coolant</b> (A4722030355)..... <b>P5092</b>	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>
Coronado w/Detroit DD16 (15.6L) Eng. (2018)	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	Coronado w/Detroit Diesel Series 60 Eng. (12/2003-on)
<b>Lube</b> (A4731800409)..... <b>P7505</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	<b>Lube</b> (23527033)..... <b>[2] B495</b>
<b>Fuel/Water Separator</b> (A0000903651)..... <b>PF9804</b>	<b>Trans. Spin-on</b> (Fuller 4304827)..... <b>BT223</b>	<b>Lube</b> (Upgrade) (Don. DELF3998)..... <b>[2] B495-SS</b>
<b>Fuel</b> (2 Filter Kit) (A4720900651)..... <b>PF9908 KIT</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19763)..... <b>PF7928</b>
<b>Fuel</b> (3 Filter Kit) (A0000904251)..... <b>PF9924 KIT</b>	<b>Steering</b> (T1808D)..... <b>BT9388</b>	<b>Fuel/Water Separator Ele.</b> (23533816)..... <b>PF7748</b>
<b>EnduraCube Air</b> (336867010)..... <b>PA32002</b>	<b>Steering</b> (1417927000)..... <b>PT23629</b>	<b>Fuel/Water Separator Spin-on</b> (w/Drain) (23512317)..... <b>BF5813 +</b>
<b>Cab Air</b> (36000006)..... <b>PA5359</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (23512317)..... <b>BF5813-O +</b>
<b>Air Dryer</b> (Wabco R950068)..... <b>BA5379 +</b>	<b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b>	<b>Fuel/Water Separator Spin-on</b> (Alliance ABP/N122-R50422)..... <b>BF1375</b>
<b>Coolant</b> (A4722030255)..... <b>P5092</b>	<b>Diesel Exhaust Fluid</b> (A0001420289)..... <b>PE5272</b>	<b>Fuel/Water Separator Spin-on</b> (Alliance ABP/N122-R50416)..... <b>BF1377</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	<b>Diesel Exhaust Fluid</b> (A0001420789)..... <b>PE17002 KIT</b>	<b>Fuel/Water Separator Spin-on</b> (RAIBR90FRT10)..... <b>BF9871-O</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	Coronado w/Detroit DD16 (15.6L) Eng. (2019)	<b>P. Fuel</b> (23518481)..... <b>BF5800 +</b>
<b>Trans. Spin-on</b> (Fuller 4304827)..... <b>BT223</b>	<b>Lube</b> (A4731800109)..... <b>P7505</b>	<b>S. Fuel</b> (23533726)..... <b>BF5816</b>
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Fuel/Water Separator</b> (A0000905051)..... <b>PF46145</b>	<b>S. Fuel</b> (23530645)..... <b>BF5815</b>
<b>Steering</b> (T1808D)..... <b>BT9388</b>	<b>Fuel Kit</b> (A4720900651)..... <b>PF9908 KIT</b>	<b>Radial Seal Air</b> (Standard) (Don. EAF5069)..... <b>RS3518</b>
<b>Steering</b> (1417927000)..... <b>PT23629</b>	<b>EnduraCube Air</b> (Don. P616380)..... <b>PA32002</b>	<b>Radial Seal XP Air</b> (Upgrade) (Don. EAF5069)..... <b>RS3518XP</b>
<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>		<b>Cab Air</b> (BOA91559)..... <b>PA4857</b>
<b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b>		<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
<b>Diesel Exhaust Fluid</b> (A0001420289)..... <b>PE5272</b>		<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>
<b>Diesel Exhaust Fluid</b> (A0001420789)..... <b>PE17002 KIT</b>		
Coronado w/Detroit DD16 (15.6L) Eng. (2019)		
<b>Lube</b> (A4731800109)..... <b>P7505</b>		
<b>Fuel/Water Separator</b> (A0000905051)..... <b>PF46145</b>		
<b>Fuel Kit</b> (A4720900651)..... <b>PF9908 KIT</b>		
<b>EnduraCube Air</b> (Don. P616380)..... <b>PA32002</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).


FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
Coronado w/Detroit Diesel Series 60 Eng. (12/2003-on) (Cont'd)	Coronado SD w/Cummins ISX (15.0L) Eng. (Cont'd)	Coronado SD w/Detroit DD13 Eng. (Cont'd)
<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Coolant</b> (w/o Chemical) (Fleetguard WF2127)..... <b>B5087</b>	<b>Coolant</b> (A4722030255)..... <b>P5092</b>
<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>
<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>
<b>Coolant</b> (w/2 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>
<b>Coolant</b> (Controlled Release) (23516489)..... <b>BW5200</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
<b>Coolant</b> (w/o Chemical) (23524403)..... <b>B5134 +</b>	<b>Steering</b> (T1808D)..... <b>BT9388</b>	<b>Steering</b> (T1808D)..... <b>BT9388</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Some Rear Axle</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Steering</b> (1417927000)..... <b>PT23629</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Diesel Exhaust Fluid</b> (2888182).. <b>PE17000</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	Coronado SD w/Cummins X15 (14.9L) Eng.	<b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b>
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b>	<b>Diesel Exhaust Fluid</b> (A0001420289)..... <b>PE5272</b>
<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>Fuel/Water Separator</b> (Fleetguard FS19915)..... <b>PF9804</b>	Coronado SD w/Detroit DD15 Eng.
<b>Steering</b> (VML/T1808D)..... <b>BT9388</b>	<b>Fuel/Water Separator</b> (Fleetguard FS19764)..... <b>PF9814</b>	<b>Lube</b> (A4731800409)..... <b>P7505</b>
<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Fuel</b> (Fleetguard FF5825NN)..... <b>BF46129</b>	<b>Fuel/Water Separator</b> (A0000903651)..... <b>PF9804</b>
Coronado SD w/Cummins ISX (15.0L) Eng.	<b>EnduraCube Air</b> (336867010)..... <b>PA32002</b>	<b>Fuel Kit</b> (2 Filter Kit) (A4720900451)..... <b>PF9908 KIT</b>
<b>Dual-Flow Lube</b> (Fleetguard LF9031)..... <b>BD7509 +</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>	<b>Fuel Kit</b> (3 Filter Kit) (A0000904251)..... <b>PF9924 KIT</b>
<b>Dual-Flow Lube</b> (Fleetguard LF9080)..... <b>BD7154 +</b>	<b>Air Dryer</b> (Wabco R950068)..... <b>BA5379 +</b>	<b>EnduraCube Air</b> (3-36867-010)... <b>PA32002</b>
<b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	<b>Channel Flow Air</b> (P610260)..... <b>CA5790</b>
<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19727)..... <b>PF7895</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	<b>Cab Air</b> (8 5/8 In.) (36000006)..... <b>PA5359</b>
<b>Fuel/Water Separator Spin-on</b> (Racor BR90FRT10)..... <b>BF9871-O</b>	<b>Steering</b> (1417927000)..... <b>PT23629</b>	<b>Cab Air</b> (10 5/8 In.) (BOA91559).. <b>PA4857</b>
<b>Fuel</b> (Fleetguard FF5686)..... <b>BF9860 +</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
<b>Fuel</b> (Standard) (Fleetguard FF5776)..... <b>BF9885 +</b>	Coronado SD w/Detroit DD13 Eng.	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>
<b>Fuel</b> (Upgrade) (Fleetguard FF5825NN)..... <b>BF46129</b>	<b>Lube</b> (A4731800109)..... <b>P7505</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>
<b>EnduraCube Air</b> (3-36867-010)... <b>PA32002</b>	<b>Fuel/Water Separator</b> (A0000905051)..... <b>PF46145</b>	<b>Air Dryer</b> (System Saver 1200 Plus) (Wabco R950011)..... <b>BA5374 +</b>
<b>Channel Flow Air</b> (P610260)..... <b>CA5790</b>	<b>Opt. Fuel/Water Separator</b> (A0000903651)..... <b>PF9804</b>	<b>Opt. Coalescing Air Dryer</b> (System Saver 1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>
<b>Cab Air 8 5/8 In.</b> (36000006)..... <b>PA5359</b>	<b>Fuel/Water Separator</b> (Racor R61709)..... <b>PF46235</b>	<b>Coolant</b> (A4722030255)..... <b>P5092</b>
<b>Cab Air 10 5/8 In.</b> (BOA91559)... <b>PA4857</b>	<b>Fuel Kit</b> (2 Filter Kit) (A4720900451)..... <b>PF9908 KIT</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Fuel Kit</b> (3 Filter Kit) (A0000904251)..... <b>PF9924 KIT</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>
<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>EnduraCube Air</b> (3-36867-010)... <b>PA32002</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>
<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Channel Flow Air</b> (P610260)..... <b>CA5790</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
<b>Air Dryer</b> (System Saver 1200 Plus) (Wabco R950011)..... <b>BA5374 +</b>	<b>Cab Air</b> (8 5/8 In.) (36000006)..... <b>PA5359</b>	<b>Steering</b> (T1808D)..... <b>BT9388</b>
<b>Opt. Coalescing Air Dryer</b> (System Saver 1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>	<b>Cab Air</b> (10 5/8 In.) (BOA91559).. <b>PA4857</b>	<b>Steering</b> (1417927000)..... <b>PT23629</b>
<b>Crankcase Breather</b> (3685528)... <b>CV15000</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
<b>Coolant</b> (w/Chemical) (Fleetguard WF2126)..... <b>BW5086</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b>
	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Diesel Exhaust Fluid</b> (A0001420289)..... <b>PE5272</b>
	<b>Air Dryer</b> (System Saver 1200 Plus) (Wabco R950011)..... <b>BA5374 +</b>	
	<b>Opt. Coalescing Air Dryer</b> (System Saver 1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
Coronado SD w/Detroit DD16 Eng. <b>Lube</b> (A4731800109)..... <b>P7505</b> <b>Fuel/Water Separator</b> (Davco 482) (A0000903651)..... <b>PF9804</b> <b>Fuel</b> (2 Filter Kit) (A4720900651). <b>PF9908 KIT</b> <b>Fuel</b> (3 Filter Kit) (A0000904251). <b>PF9924 KIT</b> <b>EnduraCube Air</b> (3-36867-010)... <b>PA32002</b> <b>Channel Flow Air</b> (P610260)..... <b>CA5790</b> <b>8 5/8 In. Cab Air</b> (36000006)..... <b>PA5359</b> <b>10 5/8 In. Cab Air</b> (BOA91559).... <b>PA4857</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b> <b>Air Dryer</b> (System Saver 1200 Plus) (Wabco R950011)..... <b>BA5374 +</b> <b>Opt. Coalescing Air Dryer</b> (System Saver 1200 Plus) (Wabco R950068)..... <b>BA5379 +</b> <b>Coolant</b> (A4722030255)..... <b>P5092</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (T1808D)..... <b>BT9388</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b> <b>Diesel Exhaust Fluid</b> (A0001420289)..... <b>PE5272</b>	FC70 w/Cummins ISB 5.9 (5.9L) Eng. (1999-2003) (Cont'd) <b>Fuel/Water Separator Ele.</b> (3942470)..... <b>PF7777</b> <b>Fuel/Water Separator Spin-on</b> (3954904)..... <b>BF1293-SPS</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b> <b>Radial Seal Air</b> (Don. P530300)... <b>RS2863</b> <b>Radial Seal XP Air</b> (Don. P530300)..... <b>RS2863XP</b> <b>Cab Air</b> (22-44665-000)..... <b>PA5319</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Ele.</b> (Fleetguard HF6389).. <b>PT8330-MPG</b> <b>Trans. Pan-Type</b> (MT Series) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (MT Series, 1 1/2-16 Thd.) (Allison 29510922).... <b>BT8316-MPG</b> <b>Trans. Spin-on</b> (MT Series, 1 1/8-16 Thd.) (ACDelco PF897)..... <b>BT230</b> <b>Steering</b> (T1808D)..... <b>BT9388</b>	FC70 w/Cummins ISB-E Series (5.9L) Eng. (2004) (Cont'd) <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Ele.</b> (Fleetguard HF6389).. <b>PT8330-MPG</b> <b>Trans. Pan-Type</b> (MT Series) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (MT Series, 1 1/2-16 Thd.) (Allison 29510922).... <b>BT8316-MPG</b> <b>Trans. Spin-on</b> (MT Series, 1 1/8-16 Thd.) (ACDelco PF897)..... <b>BT230</b> <b>Steering</b> (T1808D)..... <b>BT9388</b>
EconicSD w/Detroit DD8 (7.7L) Eng. (2019) <b>Breather</b> (N/S)..... <b>N/S</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	FC70 w/Cummins ISB-E Series (5.9L) Eng. (2004) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (Alliance ABPS3226FL01)..... <b>BF1347</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Alliance ABPS3226FL01)..... <b>BF1347-O</b> <b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (Alliance ABPS3226FL01)..... <b>BF1373-SP</b> <b>Fuel/Water Separator Ele.</b> (3942470)..... <b>PF7777</b> <b>Fuel/Water Separator Spin-on</b> (3954904)..... <b>BF1293-SPS</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b> <b>Fuel Spin-on</b> (Fleetguard FF5632)..... <b>BF7940</b> <b>Radial Seal Air</b> (Don. P530300)... <b>RS2863</b> <b>Radial Seal XP Air</b> (Don. P530300)..... <b>RS2863XP</b> <b>Cab Air</b> (22-44665-000)..... <b>PA5319</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	FC70 w/Cummins ISB Eng. (2005-on) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (Alliance ABPS3226FL01)..... <b>BF1347</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Alliance ABPS3226FL01)..... <b>BF1347-O</b> <b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (Alliance ABPS3226FL01)..... <b>BF1373-SP</b> <b>Fuel/Water Separator Ele.</b> (3942470)..... <b>PF7777</b> <b>Fuel/Water Separator Spin-on</b> (3954904)..... <b>BF1293-SPS</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b> <b>Fuel Spin-on</b> (Fleetguard FF5632)..... <b>BF7940</b> <b>Radial Seal Air</b> (Don. P530300)... <b>RS2863</b> <b>Radial Seal XP Air</b> (Don. P530300)..... <b>RS2863XP</b> <b>Cab Air</b> (22-44665-000)..... <b>PA5319</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
EconicSD w/Detroit DD8 (7.7L) Eng. (2020) <b>Trans.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	FC70 w/Cummins ISB-E Series (5.9L) Eng. (2004) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (Alliance ABPS3226FL01)..... <b>BF1347</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Alliance ABPS3226FL01)..... <b>BF1347-O</b> <b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (Alliance ABPS3226FL01)..... <b>BF1373-SP</b> <b>Fuel/Water Separator Ele.</b> (3942470)..... <b>PF7777</b> <b>Fuel/Water Separator Spin-on</b> (3954904)..... <b>BF1293-SPS</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b> <b>Radial Seal Air</b> (Don. P530300)... <b>RS2863</b> <b>Radial Seal XP Air</b> (Don. P530300)..... <b>RS2863XP</b> <b>Cab Air</b> (22-44665-000)..... <b>PA5319</b>	
EconicSD w/Detroit DD8 (7.7L) Eng. (2021) <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>		
FC70 w/Cummins ISB 5.9 (5.9L) Eng. (1999-2003) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (Alliance ABPS3226FL01)..... <b>BF1347</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Alliance ABPS3226FL01)..... <b>BF1347-O</b> <b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (Alliance ABPS3226FL01)..... <b>BF1373-SP</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
<b>FC70 w/Cummins ISB Eng. (2005-on) (Cont'd)</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Ele.</b> (Fleetguard HF6389).. <b>PT8330-MPG</b> <b>Trans. Pan-Type</b> (MT Series) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (MT Series, 1 1/2-16 Thd.) (Allison 29510922).... <b>BT8316-MPG</b> <b>Trans. Spin-on</b> (MT Series, 1 1/8-16 Thd.) (ACDelco PF897)..... <b>BT230</b> <b>Steering</b> (T1808D)..... <b>BT9388</b>	<b>FL50 w/Cat 3126 (7.2L) Eng. (To 1/2004)</b> <b>Lube</b> (Standard Vers.) (1R0739).. <b>B76</b> <b>7 3/8 In. Fuel/Water Separator</b> <b>Spin-on</b> (175-2949)..... <b>BF1268</b> <b>9 17/32 In. Fuel/Water Separator</b> <b>Spin-on</b> (256-8753)..... <b>BF1259</b> <b>Fuel</b> (Davco 101377)..... <b>BF788</b> <b>Fuel</b> (1R0751)..... <b>BF7632</b> <b>Radial Seal Air</b> (Don. P532966)... <b>RS3517</b> <b>Radial Seal XP Air</b> (Don. P532966)..... <b>RS3517XP</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b> <b>Steering</b> (S1414)..... <b>PT8407</b>	<b>FL50 w/Cat C7 (7.2L) Eng. (1/2004-on)</b> <b>Lube</b> (1R1807)..... <b>B7700 +</b> <b>Lube</b> (1R1808)..... <b>B7299 +</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19624)..... <b>PF7748</b> <b>7 3/8 In. Fuel/Water Separator</b> <b>Spin-on</b> (175-2949)..... <b>BF1268</b> <b>9 17/32 In. Fuel/Water Separator</b> <b>Spin-on</b> (256-8753)..... <b>BF1259</b> <b>Fuel</b> (1R0751)..... <b>BF7632</b> <b>Radial Seal Air</b> (Don. P532966)... <b>RS3517</b> <b>Radial Seal XP Air</b> (Don. P532966)..... <b>RS3517XP</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (Nelson 87904A)..... <b>PT9354-MPG</b>
<b>FC70 w/Cummins ISC (8.3L) Eng.</b> <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel/Water Separator</b> (Fleetguard FS1003)..... <b>BF1293-SPS</b> <b>Fuel</b> (Fleetguard FF5488)..... <b>BF7815</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>FL50 w/Cat 3126 (7.2L) Eng. (1/2004-on)</b> <b>Lube</b> (1R1807)..... <b>B7700 +</b> <b>7 3/8 In. Fuel/Water Separator</b> <b>Spin-on</b> (175-2949)..... <b>BF1268</b> <b>9 17/32 In. Fuel/Water Separator</b> <b>Spin-on</b> (256-8753)..... <b>BF1259</b> <b>Fuel</b> (Davco 101377)..... <b>BF788</b> <b>Fuel</b> (1R0751)..... <b>BF7632</b> <b>Radial Seal Air</b> (Don. P532966)... <b>RS3517</b> <b>Radial Seal XP Air</b> (Don. P532966)..... <b>RS3517XP</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b> <b>Steering</b> (S1414)..... <b>PT8407</b>	<b>FL50 w/Chrysler 5.9L Gas Eng.</b> <b>Lube</b> (5281090)..... <b>B34</b> <b>Radial Seal Air</b> (Don. P532966)... <b>RS3517</b> <b>Radial Seal XP Air</b> (Don. P532966)..... <b>RS3517XP</b>
<b>FC70 Cargo w/Cummins 6B Series Eng.</b> <b>Lube</b> (Chrysler 5083285AA)..... <b>BT7349</b> <b>Fuel/Water Separator</b> (3925274). <b>BF1280 +</b> <b>Fuel</b> (3903640)..... <b>BF788</b> <b>Radial Seal Air</b> (Don. P527484)... <b>RS2863</b> <b>Radial Seal XP Air</b> (Don. P527484)..... <b>RS2863XP</b>	<b>FL50 w/Cat C7 (7.2L) Eng. (To 1/2004)</b> <b>Lube</b> (Standard Vers.) (1R0739).. <b>B76 +</b> <b>Lube</b> (1R1808)..... <b>B7299 +</b> <b>Lube</b> (Severe Service) (1R0739).. <b>B76-SS +</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19624)..... <b>PF7748</b> <b>7 3/8 In. Fuel/Water Separator</b> <b>Spin-on</b> (175-2949)..... <b>BF1268</b> <b>9 17/32 In. Fuel/Water Separator</b> <b>Spin-on</b> (256-8753)..... <b>BF1259</b> <b>Fuel</b> (1R0751)..... <b>BF7632</b> <b>Radial Seal Air</b> (Don. P532966)... <b>RS3517</b> <b>Radial Seal XP Air</b> (Don. P532966)..... <b>RS3517XP</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (Nelson 87904A)..... <b>PT9354-MPG</b>	<b>FL50 w/Cummins 6BT5.9 (5.9L) Eng.</b> <b>Lube</b> (Fleetguard LF3349)..... <b>BT339 +</b> <b>Fuel/Water Separator</b> (Fleetguard FS1251)..... <b>BF1226</b> <b>Fuel/Water Separator</b> (Fleetguard FS1280)..... <b>BF1280 +</b> <b>Fuel</b> (Fleetguard FF5052)..... <b>BF788</b>
<b>FC70 w/Detroit Diesel Series 50 (8.5L) Eng.</b> <b>Lube</b> (23530573)..... <b>[2] B495</b> <b>Fuel/Water Separator</b> (w/Drain) (23535985)..... <b>BF5813 +</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (23535985)..... <b>BF5813-O +</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b>	<b>FL50 w/Cat C7 (7.2L) Eng. (To 1/2004)</b> <b>Lube</b> (Standard Vers.) (1R0739).. <b>B76 +</b> <b>Lube</b> (1R1808)..... <b>B7299 +</b> <b>Lube</b> (Severe Service) (1R0739).. <b>B76-SS +</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19624)..... <b>PF7748</b> <b>7 3/8 In. Fuel/Water Separator</b> <b>Spin-on</b> (175-2949)..... <b>BF1268</b> <b>9 17/32 In. Fuel/Water Separator</b> <b>Spin-on</b> (256-8753)..... <b>BF1259</b> <b>Fuel</b> (1R0751)..... <b>BF7632</b> <b>Radial Seal Air</b> (Don. P532966)... <b>RS3517</b> <b>Radial Seal XP Air</b> (Don. P532966)..... <b>RS3517XP</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (Nelson 87904A)..... <b>PT9354-MPG</b>	<b>FL50 w/Cummins B5.9G (5.9L) Eng.</b> <b>Lube</b> ..... <b>BT339 +</b> <b>Lube</b> (Fleetguard LF3894)..... <b>BT7349</b> <b>Fuel/Water Separator</b> (Fleetguard FS1251)..... <b>BF1226</b> <b>Fuel/Water Separator</b> (Fleetguard FS1280)..... <b>BF1280 +</b> <b>Fuel/Water Separator</b> (w/o SP) (Racor S3225P)..... <b>BF1348</b> <b>Fuel/Water Separator</b> (w/SP) (Racor S3225P)..... <b>BF1348-SP</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (Racor S3225P)..... <b>BF1348-O</b> <b>S. Fuel</b> ..... <b>BF788</b> <b>15 In. Radial Seal Air</b> (Don. P526678)..... <b>RS3520</b> <b>19 In. Radial Seal Air</b> (Don. P532966)..... <b>RS3517</b> <b>19 In. Radial Seal XP Air</b> (Don. P532966)..... <b>RS3517XP</b> <b>Steering</b> (S1414)..... <b>PT8407</b>
<b>FC80 w/Cummins ISC 8.3 (8.3L) Eng.</b> <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b> <b>Fuel</b> (Fleetguard FF5636)..... <b>BF7924</b> <b>Coolant</b> (Fleetguard WC2071)..... <b>BW5071</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>	<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>	<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>
FL50 w/Cummins C8.3G (8.3L) CNG, LPG Eng. F-F Lube (3313281)..... <b>B205 +</b> Dual-Flow Lube (3318853)..... <b>BD103 +</b> Radial Seal Air (Don. P532966)... <b>RS3517</b> Radial Seal XP Air (Don. P532966)..... <b>RS3517XP</b>	FL50, FL60, FL70 w/Cummins ISC (8.3L) Eng. (Cont'd) Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b> Coolant (Fleetguard WF2071)..... <b>BW5071</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Steering (S1414)..... <b>PT8407</b>	FL60 w/Cat 3126 (7.2L) Eng. (Cont'd) Fuel/Water Separator (Sensor Port Thd. 9/16-18) (Racor R90P).. <b>BF1329-SP</b> Fuel/Water Separator (Sensor Port Thd. 1/2-20) (Racor R90P).... <b>BF1339-SP +</b> Fuel..... <b>BF7632</b> Radial Seal Air (Don. P532966)... <b>RS3517</b> Radial Seal XP Air (Don. P532966)..... <b>RS3517XP</b> Air Dryer (Bendix 107796)..... <b>BA5377</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Trans. Pan-Type (MT Series) (Allison 29538489)..... <b>19739 +</b> Trans. Spin-on (MT Series) (Allison 29510922)..... <b>BT8316-MPG</b> 2 23/32 In. Steering (Nelson 87904A)..... <b>PT9354-MPG</b> 4 5/32 In. Steering (S1414)..... <b>PT8407</b>
FL50 w/Cummins M11 Eng. Dual-Flow Lube (3318853)..... <b>BD103 +</b> Fuel/Water Separator Ele. (Fleetguard FS1029W)..... <b>PF7680</b> Fuel/Water Separator Spin-on (3329289)..... <b>BF1259</b> Radial Seal Air (Don. P532966)... <b>RS3517</b> Radial Seal XP Air (Don. P532966)..... <b>RS3517XP</b>	FL50, FL60, FL70, FL80 w/Cummins ISB (5.9L) Eng. Lube..... <b>B7177</b> Fuel/Water Separator (w/Drain) (Alliance ABPS3226FL01)..... <b>BF1347</b> Fuel/Water Separator (Open End for Bowl) (Alliance ABPS3226FL01)..... <b>BF1347-O</b> Fuel/Water Separator (w/Sensor Port) (Alliance ABPS3226FL01).... <b>BF1373-SP</b> Fuel/Water Separator (M20 x 1.5 Thd.)..... <b>BF1271</b> Fuel Ele..... <b>PF7777</b> 15 In. Radial Seal O. Air (Don. P526678)..... <b>RS3520</b> Radial Seal I. Air (Don. P529548)..... <b>RS3521</b> 18 15/16 In. Radial Seal O. Air (Don. P532966)..... <b>RS3517</b> Radial Seal I. Air (Don. P533781)..... <b>RS3717</b> Single Radial Seal Air (Don. P530300)..... <b>RS2863</b> Single Radial Seal XP Air (Don. P530300)..... <b>RS2863XP</b> Trans. Pan-Type (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> Trans. Pan-Type (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> Trans. Spin-on (Allison 29510922)..... <b>BT8316-MPG</b> Trans. Spin-on (ACDelco PF897)..... <b>BT230</b> Steering (S1414)..... <b>PT8407</b> Steering (T1808D)..... <b>BT9388</b>	FL60 w/Cat 3176 Eng. F-F Lube (1R0716)..... <b>B99 +</b> F-F Lube (High Efficiency) (1R1808)..... <b>B7299 +</b> Opt. B-P Lube (1W8845)..... <b>B7577</b> Fuel/Water Separator (256-8753)..... <b>BF1259</b> P. Fuel (1R1740)..... <b>BF970 +</b> S. Fuel (1R0750)..... <b>BF7633 +</b> Radial Seal Air (Don. P532966)... <b>RS3517</b> Radial Seal XP Air (Don. P532966)..... <b>RS3517XP</b>
FL50 w/Mercedes-Benz MBE904 (4.3L) Eng. Lube (1801609)..... <b>P7199</b> Radial Seal Air (Don. P532966)... <b>RS3517</b> Radial Seal XP Air (Don. P532966)..... <b>RS3517XP</b>	FL50 w/Mercedes-Benz MBE906 (6.4L) Eng. F-F Lube Ele. (A0001801709)..... <b>P7188</b> Opt. B-P Lube Spinner (A9061810086)..... <b>BC7326 +</b> Fuel (A0000901551)..... <b>PF7735</b> Radial Seal Air (Don. P532966)... <b>RS3517</b> Radial Seal XP Air (Don. P532966)..... <b>RS3517XP</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Steering (Nelson 87904A)..... <b>PT9354-MPG</b>	FL60 w/Cat C7 (7.2L) Eng. (To 1/2004) Lube (Standard Vers.) (1R0739).. <b>B76 +</b> Lube (Severe Service) (1R0739).. <b>B76-SS +</b> Fuel/Water Separator (256-8753)..... <b>BF1259</b> Fuel/Water Separator (175-2949)..... <b>BF1268</b> Fuel/Water Separator (w/o SP) (Racor S3225P)..... <b>BF1348</b> Fuel/Water Separator (w/SP) (Racor S3225P)..... <b>BF1348-SP</b> Fuel/Water Separator (Open End for Bowl) (Racor S3225P)..... <b>BF1348-O</b> Fuel/Water Separator (Open End for Bowl) (Racor R90P)..... <b>BF46083-O</b> Fuel/Water Separator (w/Bowl) (Racor R90P)..... <b>BF46072</b> Fuel/Water Separator (w/Drain) (Racor R90P)..... <b>BF1329</b>
FL50, FL60, FL70 w/Cummins ISC (8.3L) Eng. Dual-Flow Lube..... <b>BD7309 +</b> Fuel/Water Separator (3800394). <b>BF1272-SPS</b> Fuel/Water Separator (Open End for Bowl) (Racor R90P)..... <b>BF46083-O</b> Fuel/Water Separator (w/Bowl) (Racor R90P)..... <b>BF46072</b> Fuel/Water Separator (w/Drain) (Racor R90P)..... <b>BF1329</b> Fuel/Water Separator (Sensor Port Thd. 9/16-18) (Racor R90P).. <b>BF1329-SP</b> Fuel/Water Separator (Sensor Port Thd. 1/2-20) (Racor R90P).... <b>BF1339-SP +</b> Radial Seal O. Air (Don. P532966)..... <b>RS3517</b> Radial Seal XP Air (Don. P532966)..... <b>RS3517XP</b> Radial Seal I. Air (Don. P533781)..... <b>RS3717</b>	FL60 w/Cat 3126 (7.2L) Eng. Lube (Standard Vers.)..... <b>B76</b> Fuel/Water Separator (w/o SP) (Racor S3225P)..... <b>BF1348</b> Fuel/Water Separator (w/SP) (Racor S3225P)..... <b>BF1348-SP</b> Fuel/Water Separator (Open End for Bowl) (Racor S3225P)..... <b>BF1348-O</b> Fuel/Water Separator (Open End for Bowl) (Racor R90P)..... <b>BF46083-O</b> Fuel/Water Separator (w/Bowl) (Racor R90P)..... <b>BF46072</b> Fuel/Water Separator (w/Drain) (Racor R90P)..... <b>BF1329</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
FL60 w/Cat C7 (7.2L) Eng. (To 1/2004) (Cont'd) Radial Seal XP Air (Don. P532966)..... <b>RS3517XP</b> Steering (Nelson 87904A)..... <b>PT9354-MPG</b>	FL60 w/Cummins 6CT8.3 (8.3L) Diesel Eng. (Cont'd) Radial Seal Air (Don. P532966)... <b>RS3517</b> Radial Seal XP Air (Don. P532966)..... <b>RS3517XP</b>	FL60 w/Detroit Diesel Series 50 Eng. (Cont'd) P. Fuel (23530706)..... <b>BF5800 +</b> S. Fuel (23530707)..... <b>BF5810</b> Radial Seal Air (Don. P532966)... <b>RS3517</b> Radial Seal XP Air (Don. P532966)..... <b>RS3517XP</b>
FL60 w/Cat C7 (7.2L) Eng. (1/2004-on) Lube (1R1807)..... <b>B7700 +</b> Fuel/Water Separator (256-8753)..... <b>BF1259</b> Fuel/Water Separator (175-2949)..... <b>BF1268</b> Fuel/Water Separator (w/o SP) (Racor S3225P)..... <b>BF1348</b> Fuel/Water Separator (w/SP) (Racor S3225P)..... <b>BF1348-SP</b> Fuel/Water Separator (Open End for Bowl) (Racor S3225P)..... <b>BF1348-O</b> Fuel (1R0751)..... <b>BF7632</b> Radial Seal Air (Don. P532966)... <b>RS3517</b> Radial Seal XP Air (Don. P532966)..... <b>RS3517XP</b> Steering (Nelson 87904A)..... <b>PT9354-MPG</b>	FL60 w/Cummins B5.9G (5.9L) CNG & LPG Eng. Lube..... <b>BT339 +</b> FL60 w/Cummins C8.3G (8.3L) CNG, LPG Eng. F-F Lube (3313281)..... <b>B205 +</b> Dual-Flow Lube (3318853)..... <b>BD103 +</b> Radial Seal Air (Don. P532966)... <b>RS3517</b> Radial Seal XP Air (Don. P532966)..... <b>RS3517XP</b>	FL60 w/Mercedes-Benz MBE904 (4.3L) Eng. Lube (1801609)..... <b>P7199</b> Radial Seal Air (Don. P532966)... <b>RS3517</b> Radial Seal XP Air (Don. P532966)..... <b>RS3517XP</b>
FL60 w/Cat C10 Eng. F-F Lube (1R0716)..... <b>B99 +</b> F-F Lube (High Efficiency) (1R1808)..... <b>B7299 +</b> B-P Lube (1W8845)..... <b>B7577</b> Fuel (1R1712)..... <b>BF614 +</b> Fuel (High Efficiency) (1R0749)... <b>BF7587 +</b> Radial Seal Air (Don. P532966)... <b>RS3517</b> Radial Seal XP Air (Don. P532966)..... <b>RS3517XP</b>	FL60 w/Cummins ISB (5.9L) Eng. Lube (Fleetguard LF3970)..... <b>B7177</b> Fuel/Water Separator (w/o SP) (Racor S3225P)..... <b>BF1348</b> Fuel/Water Separator (w/SP) (Racor S3225P)..... <b>BF1348-SP</b> Fuel/Water Separator (Open End for Bowl) (Racor S3225P)..... <b>BF1348-O</b> Fuel (Davco 101377)..... <b>BF788</b> Radial Seal Air (Don. P532966)... <b>RS3517</b> Radial Seal XP Air (Don. P532966)..... <b>RS3517XP</b> Air Dryer (Bendix 107796)..... <b>BA5377</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> 2 23/32 In. Steering (Nelson 87904A)..... <b>PT9354-MPG</b> 4 5/32 In. Steering (S1414)..... <b>PT8407</b>	FL60 w/Mercedes-Benz MBE906 (6.4L) Eng. F-F Lube (A0001801709)..... <b>P7188</b> Opt. B-P Lube Spinner (A9061810086)..... <b>BC7326 +</b> Fuel/Water Separator (Open End for Bowl) (Racor S3226P)..... <b>BF1346-O</b> Fuel/Water Separator (w/Sensor Port) (Racor S3226P)..... <b>BF1346-SP</b> Fuel/Water Separator (w/Drain) (Racor S3226P)..... <b>BF1346</b> Fuel (A0000901551)..... <b>PF7735</b> Radial Seal Air (Don. P532966)... <b>RS3517</b> Radial Seal XP Air (Don. P532966)..... <b>RS3517XP</b> Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> 2 23/32 In. Steering (Nelson 87904A)..... <b>PT9354-MPG</b> 4 5/32 In. Steering (S1414)..... <b>PT8407</b>
FL60 w/Chrysler 5.9L Eng. Lube (5281090)..... <b>B34</b> Radial Seal Air (Don. P532966)... <b>RS3517</b> Radial Seal XP Air (Don. P532966)..... <b>RS3517XP</b>	FL60 w/Cummins 6BT5.9 (5.9L) Eng. Lube (Fleetguard LF3349)..... <b>BT339 +</b> Fuel/Water Separator (Fleetguard FS1251)..... <b>BF1226</b> Fuel/Water Separator (Fleetguard FS1280)..... <b>BF1280 +</b> Fuel (Fleetguard FF5052)..... <b>BF788</b> Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	FL60 w/Mercedes-Benz OM906 Eng. Lube (A0001801609)..... <b>P7199</b> Fuel/Water Separator (Open End for Bowl) (Racor S3226P)..... <b>BF1346-O</b> Fuel/Water Separator (w/Sensor Port) (Racor S3226P)..... <b>BF1346-SP</b> Fuel/Water Separator (w/Drain) (Racor S3226P)..... <b>BF1346</b> Fuel Ele. (A9060920305)..... <b>PF7735</b> Radial Seal Air (Don. P532966)... <b>RS3517</b> Radial Seal XP Air (Don. P532966)..... <b>RS3517XP</b> Air Dryer (Bendix 107796)..... <b>BA5377</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
FL60 w/Cummins 6C Series Natural Gas Eng. F-F Lube (3313281)..... <b>B205 +</b> Dual-Flow Lube (3318853)..... <b>BD103 +</b> Radial Seal Air (Don. P532966)... <b>RS3517</b> Radial Seal XP Air (Don. P532966)..... <b>RS3517XP</b>	FL60 w/Cummins M11 Eng. Dual-Flow Lube (3318853)..... <b>BD103 +</b> Fuel/Water Separator Ele. (Fleetguard FS1029W)..... <b>PF7680</b> Fuel/Water Separator Spin-on (3329289)..... <b>BF1259</b> Radial Seal Air (Don. P532966)... <b>RS3517</b> Radial Seal XP Air (Don. P532966)..... <b>RS3517XP</b>	FL60 w/Detroit Diesel Series 50 Eng. Lube (To 1993) (23530407)..... <b>[2] B95 +</b> Lube (1993-on) (23530573)..... <b>[2] B495</b> Fuel/Water Separator (23516189)..... <b>BF5812</b> Fuel/Water Separator (w/Drain) (23535985)..... <b>BF5813 +</b> Fuel/Water Separator (Open End for Bowl) (23535985)..... <b>BF5813-O +</b>
FL60 w/Cummins 6CT8.3 (8.3L) Diesel Eng. F-F Lube (3313281)..... <b>B205 +</b> Dual-Flow Lube (3318853)..... <b>BD103 +</b> Fuel/Water Separator (3925274). <b>BF1280 +</b> Fuel (3903640)..... <b>BF788</b>		

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>	<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>	<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>
FL60 w/Mercedes-Benz OM906 Eng. (Cont'd)	FL70 w/Cat C7 (7.2L) Eng. (Cont'd)	FL70 w/Cat C16 Eng. (Cont'd)
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Racor S3225P)..... <b>BF1348-O</b>	<b>Fuel/Water Separator</b> (256-8753)..... <b>BF1259</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Fuel Ele.</b> (9M2342)..... <b>PF935</b>	<b>Fuel</b> (1R1712)..... <b>BF614 +</b>
<b>Steering</b> (Nelson 87904A)..... <b>PT9354-MPG</b>	<b>Fuel</b> (Davco 101377)..... <b>BF788</b>	<b>Fuel</b> (High Efficiency) (1R0749).... <b>BF7587 +</b>
FL70 w/Cat 3126 (7.2L) Eng.	<b>Fuel Spin-on</b> (1R0751)..... <b>BF7632</b>	<b>Radial Seal Air</b> (Don. P532966).... <b>RS3517</b>
<b>Lube</b> (Standard Vers.)..... <b>B76</b>	<b>Single Radial Seal Air</b> (Don. P532966)..... <b>RS3517</b>	<b>Radial Seal XP Air</b> (Don. P532966)..... <b>RS3517XP</b>
<b>Lube</b> (High Efficiency) (1R1807).. <b>B7700 +</b>	<b>Single Radial Seal XP Air</b> (Don. P532966)..... <b>RS3517XP</b>	FL70 w/Chrysler 5.9L Eng.
<b>Fuel/Water Separator Ele.</b> (Davco 382113)..... <b>PF7748</b>	<b>Radial Seal O. Air</b> (Don. P532503)..... <b>RS3506</b>	<b>Lube</b> (5281090)..... <b>B34</b>
<b>Fuel/Water Separator Spin-on</b> (w/o SP) (Racor S3225P)..... <b>BF1348</b>	<b>Radial Seal XP O. Air</b> (Don. P532503)..... <b>RS3506XP</b>	<b>Radial Seal Air</b> (Don. P532966).... <b>RS3517</b>
<b>Fuel/Water Separator Spin-on</b> (w/SP) (Racor S3225P)..... <b>BF1348-SP</b>	<b>Radial Seal I. Air</b> (Don. P532504)..... <b>RS3507</b>	<b>Radial Seal XP Air</b> (Don. P532966)..... <b>RS3517XP</b>
<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Racor S3225P)..... <b>BF1348-O</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	FL70 w/Cummins 6B Series Natural Gas Eng.
<b>Fuel Ele.</b> (9M2342)..... <b>PF935</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Lube</b> (To 1998) (3914395)..... <b>BT339 +</b>
<b>Fuel</b> (Davco 101377)..... <b>BF788</b>	<b>Coolant</b> (w/8 Units BTE) (9N3367)..... <b>BW5139</b>	<b>Lube</b> (1998-on) (Chrysler 5083285AA)..... <b>BT7349</b>
<b>Fuel Spin-on</b> (1R0751)..... <b>BF7632</b>	<b>Coolant</b> (w/4 Units BTE) (9N3368)..... <b>BW5137</b>	<b>Radial Seal Air</b> (Don. P532966).... <b>RS3517</b>
<b>Single Radial Seal Air</b> (Don. P532966)..... <b>RS3517</b>	<b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Radial Seal XP Air</b> (Don. P532966)..... <b>RS3517XP</b>
<b>Single Radial Seal XP Air</b> (Don. P532966)..... <b>RS3517XP</b>	<b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	FL70 w/Cummins 6BT5.9 (5.9L) Eng.
<b>Radial Seal O. Air</b> (Don. P532503)..... <b>RS3506</b>	<b>2 23/32 In. Steering</b> (Nelson 87904A)..... <b>PT9354-MPG</b>	<b>Lube</b> (3932217)..... <b>BT339 +</b>
<b>Radial Seal XP O. Air</b> (Don. P532503)..... <b>RS3506XP</b>	<b>4 5/32 In. Steering</b> (S1414)..... <b>PT8407</b>	<b>Fuel/Water Separator</b> (3903202). <b>BF1226</b>
<b>Radial Seal I. Air</b> (Don. P532504)..... <b>RS3507</b>	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Fuel</b> (Don. P550440)..... <b>BF788</b>
<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	FL70 w/Cat C15 Eng.	FL70 w/Cummins 6CT8.3 (8.3L) Diesel Eng.
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Lube</b> (To 1/2004) (1R0716)..... <b>B99 +</b>	<b>F-F Lube</b> (1 1/2-12 Thd.) (3313281)..... <b>B205 +</b>
<b>Coolant</b> (w/8 Units BTE) (9N3367)..... <b>BW5139</b>	<b>Lube</b> (1/2004-on) (1R1808)..... <b>B7299 +</b>	<b>F-F Lube</b> (1-16 Thd.) (Fleetguard LF3959)..... <b>BT7349</b>
<b>Coolant</b> (w/4 Units BTE) (9N3368)..... <b>BW5137</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (1335673)..... <b>BF1395-O</b>	<b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b>
<b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Fuel/Water Separator</b> (w/Drain) (1335673)..... <b>BF1265</b>	<b>Fuel/Water Separator</b> (13/16-18 Thd.) (3925274)..... <b>BF1280 +</b>
<b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Fuel/Water Separator</b> (w/Sensor Port) (1335673)..... <b>BF1395-SP</b>	<b>Fuel/Water Separator</b> (M16 x 1.5 Thd.) (Fleetguard F51251)..... <b>BF1226</b>
<b>2 23/32 In. Steering</b> (Nelson 87904A)..... <b>PT9354-MPG</b>	<b>Fuel/Water Separator</b> (256-8753)..... <b>BF1259</b>	<b>Fuel</b> (3903640)..... <b>BF788</b>
<b>4 5/32 In. Steering</b> (S1414)..... <b>PT8407</b>	<b>Fuel</b> (1R1712)..... <b>BF614 +</b>	<b>15 In. Radial Seal Air</b> (Don. P526678)..... <b>RS3520</b>
<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Fuel</b> (High Efficiency) (1R0749).... <b>BF7587 +</b>	<b>18 15/16 In. Radial Seal Air</b> (Don. P532966)..... <b>RS3517</b>
FL70 w/Cat C7 (7.2L) Eng.	<b>Radial Seal Air</b> (Don. P532966).... <b>RS3517</b>	<b>18 15/16 In. Radial Seal XP Air</b> (Don. P532966)..... <b>RS3517XP</b>
<b>Lube</b> (Standard Vers.)..... <b>B76 +</b>	<b>Radial Seal XP Air</b> (Don. P532966)..... <b>RS3517XP</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>
<b>Lube</b> (High Efficiency) (1R1807).. <b>B7700 +</b>	FL70 w/Cat C16 Eng.	<b>Steering</b> (S1414)..... <b>PT8407</b>
<b>Lube</b> (Severe Service)..... <b>B76-SS +</b>	<b>Lube</b> (To 1/2004) (1R0716)..... <b>B99 +</b>	FL70 w/Cummins 6C Series Natural Gas Eng.
<b>Fuel/Water Separator Ele.</b> (Davco 382113)..... <b>PF7748</b>	<b>Lube</b> (1/2004-on) (1R1808)..... <b>B7299 +</b>	<b>F-F Lube</b> (3313281)..... <b>B205 +</b>
<b>Fuel/Water Separator Spin-on</b> (w/o SP) (Racor S3225P)..... <b>BF1348</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (1335673)..... <b>BF1395-O</b>	<b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b>
<b>Fuel/Water Separator Spin-on</b> (w/SP) (Racor S3225P)..... <b>BF1348-SP</b>	<b>Fuel/Water Separator</b> (w/Drain) (1335673)..... <b>BF1265</b>	<b>Radial Seal Air</b> (15 In.) (Don. P526678)..... <b>RS3520</b>
	<b>Fuel/Water Separator</b> (w/Sensor Port) (1335673)..... <b>BF1395-SP</b>	<b>Radial Seal Air</b> (18 15/16 In.) (Don. P532966)..... <b>RS3517</b>
		<b>Radial Seal XP Air</b> (18 15/16 In.) (Don. P532966)..... <b>RS3517XP</b>
		FL70 w/Cummins B5.9G (5.9) CNG & LPG Eng.
		<b>Lube</b> (3937743)..... <b>BT7349</b>
		<b>Fuel/Water Separator</b> (w/o SP) (Racor S3225P)..... <b>BF1348</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
FL70 w/Cummins B5.9G (5.9) CNG & LPG Eng. (Cont'd)	FL70 w/Cummins C8.3G (8.3L) CNG, LPG Eng. (Cont'd)	FL70 w/Mercedes-Benz MBE906 (6.4L) Eng. (Cont'd)
<b>Fuel/Water Separator (w/SP)</b> (Racor S3225P)..... <b>BF1348-SP</b>	<b>Trans. (4 In. Kit)</b> (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b>
<b>Fuel/Water Separator (Open End for Bowl)</b> (Racor S3225P)..... <b>BF1348-O</b>	<b>2 23/32 In. Steering</b> (Nelson 87904A)..... <b>PT9354-MPG</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>
<b>Radial Seal Air</b> (Don. P532966).... <b>RS3517</b>	<b>4 5/32 In. Steering</b> (S1414)..... <b>PT8407</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
<b>Radial Seal XP Air</b> (Don. P532966)..... <b>RS3517XP</b>	FL70 w/Cummins ISL Eng.	<b>Trans. Ele. (2 In. Kit)</b> (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b>	<b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b>	<b>Trans. Ele. (4 In. Kit)</b> (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Trans. Ele. (2 In. Kit)</b> (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Air</b> (Don. P153551)..... <b>PA2705</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
<b>Trans. Ele. (4 In. Kit)</b> (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	<b>Steering Ele.</b> (Nelson 87904A).... <b>PT9354-MPG</b>
<b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b>	<b>Steering</b> (Nelson 83213M)..... <b>P528</b>	<b>Steering Spin-on</b> (T1808D)..... <b>BT9388</b>
<b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>	FL70 w/Detroit Diesel Series 60 Eng.	FL80 w/Cat C7 Eng. (To 1/2004)
<b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b>	<b>F-F Lube</b> (To 1993) (23530407).... <b>[2] B95 +</b>	<b>Lube</b> (Standard Vers.) (1R0739).. <b>B76 +</b>
<b>Steering</b> (S1414)..... <b>PT8407</b>	<b>F-F Lube</b> (1993-on) (23530573).... <b>[2] B495</b>	<b>Lube</b> (Severe Service) (1R0739).. <b>B76-SS +</b>
FL70 w/Cummins C8.3G (8.3L) CNG, LPG Eng.	<b>B-P Lube</b> (To 1993) (23530413).. <b>B7577</b>	<b>Fuel/Water Separator Ele.</b> (Davco 382113)..... <b>PF7748</b>
<b>Dual-Flow Lube</b> (Std. Vers.) (3318853)..... <b>BD103 +</b>	<b>Fuel/Water Separator Spin-on</b> (12/03-on (w/Drain)) (23512317).... <b>BF5813 +</b>	<b>Fuel/Water Separator Spin-on</b> (256-8753)..... <b>BF1259</b>
<b>Dual-Flow Lube</b> (High Velocity) (Fleetguard LF9009)..... <b>BD7309 +</b>	<b>Fuel/Water Separator Spin-on</b> (12/03-on (Open End for Bowl)) (23512317)..... <b>BF5813-O +</b>	<b>Fuel/Water Separator Spin-on</b> (175-2949)..... <b>BF1268</b>
<b>F-F Lube</b> (3313281)..... <b>B205 +</b>	<b>P. Fuel</b> (23530706)..... <b>BF5800 +</b>	<b>Fuel</b> (1R0751)..... <b>BF7632</b>
<b>Fuel/Water Separator (w/Drain)</b> (Alliance ABPS3226FL01)..... <b>BF1347</b>	<b>S. Fuel</b> (To 12/03) (23530707).... <b>BF5810</b>	<b>Radial Seal Air</b> (Don. P532966).... <b>RS3517</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (Alliance ABPS3226FL01)..... <b>BF1347-O</b>	<b>S. Fuel</b> (12/03-on) (23533726).... <b>BF5816</b>	<b>Radial Seal XP Air</b> (Don. P532966)..... <b>RS3517XP</b>
<b>Fuel/Water Separator (w/Sensor Port)</b> (Alliance ABPS3226FL01).... <b>BF1373-SP</b>	<b>15 1/4 In. Radial Seal Air</b> (Standard) (Don. P527682)..... <b>RS3518</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
<b>Fuel/Water Separator</b> (3925274). <b>BF1280 +</b>	<b>15 1/4 In. Radial Seal XP Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b>	<b>Steering</b> (Nelson 87904A)..... <b>PT9354-MPG</b>
<b>Fuel/Water Separator (w/o SP)</b> (Racor S3225P)..... <b>BF1348</b>	<b>18 15/16 In. Radial Seal Air</b> (Don. P532966)..... <b>RS3517</b>	FL80 w/Cat C7 Eng. (1/2004-on)
<b>Fuel/Water Separator (w/SP)</b> (Racor S3225P)..... <b>BF1348-SP</b>	<b>18 15/16 In. Radial Seal XP Air</b> (Don. P532966)..... <b>RS3517XP</b>	<b>Lube</b> (1R1807)..... <b>B7700 +</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor S3225P)..... <b>BF1348-O</b>	<b>Steering</b> (Nelson 87904A)..... <b>PT9354-MPG</b>	<b>Fuel/Water Separator Ele.</b> (Davco 382113)..... <b>PF7748</b>
<b>Fuel/Water Separator</b> (3843760). <b>BF1226</b>	FL70 w/Mercedes-Benz MBE904 (4.3L) Eng.	<b>Fuel/Water Separator Spin-on</b> (256-8753)..... <b>BF1259</b>
<b>Fuel</b> (3903640)..... <b>BF788</b>	<b>Lube</b> (1801609)..... <b>P7199</b>	<b>Fuel/Water Separator Spin-on</b> (175-2949)..... <b>BF1268</b>
<b>15 In. Radial Seal Air</b> (Don. P526678)..... <b>RS3520</b>	<b>Radial Seal Air</b> (Don. P532966).... <b>RS3517</b>	<b>Fuel</b> (1R0751)..... <b>BF7632</b>
<b>18 15/16 In. Radial Seal Air</b> (Don. P532966)..... <b>RS3517</b>	<b>Radial Seal XP Air</b> (Don. P532966)..... <b>RS3517XP</b>	<b>Radial Seal Air</b> (Don. P532966).... <b>RS3517</b>
<b>18 15/16 In. Radial Seal XP Air</b> (Don. P532966)..... <b>RS3517XP</b>	FL70 w/Mercedes-Benz MBE906 (6.4L) Eng.	<b>Radial Seal XP Air</b> (Don. P532966)..... <b>RS3517XP</b>
<b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b>	<b>F-F Lube</b> (A0001801709)..... <b>P7188</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
<b>Coolant (w/4 Units BTA+)</b> (Fleetguard WF2071)..... <b>BW5071</b>	<b>(Opt.) B-P Lube</b> (A9061810086).. <b>BC7326 +</b>	<b>Steering</b> (Nelson 87904A)..... <b>PT9354-MPG</b>
<b>Coolant (w/6 Units BTA+)</b> (3318201)..... <b>BW5072</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor S3226P)..... <b>BF1346-O</b>	FL80 w/Cat C10 Eng.
<b>Coolant (w/12 Units BTA+)</b> (Fleetguard WF2074)..... <b>BW5074</b>	<b>Fuel/Water Separator</b> (w/Sensor Port) (Racor S3226P)..... <b>BF1346-SP</b>	<b>F-F Lube</b> (1R0716)..... <b>B99 +</b>
<b>Trans. (2 In. Kit)</b> (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Fuel/Water Separator</b> (w/Drain) (Racor S3226P)..... <b>BF1346</b>	<b>F-F Lube</b> (High Efficiency) (1R1808)..... <b>B7299 +</b>
	<b>4 1/16 In. Fuel</b> (A0000901551).... <b>PF7735</b>	<b>B-P Lube</b> (1W8845)..... <b>B7577</b>
	<b>8 In. Fuel</b> (A5410920805)..... <b>PF7761</b>	<b>P. Fuel</b> (1R1712)..... <b>BF614 +</b>
	<b>Radial Seal Air</b> (Don. P532966).... <b>RS3517</b>	<b>P. Fuel</b> (High Efficiency) (1R0749)..... <b>BF7587 +</b>
	<b>Radial Seal XP Air</b> (Don. P532966)..... <b>RS3517XP</b>	<b>Radial Seal Air</b> (Don. P532966).... <b>RS3517</b>
	<b>Channel Flow Air</b> (w/o Flame Retardant Media) (Don. P548070) <b>CA4700 +</b>	<b>Radial Seal XP Air</b> (Don. P532966)..... <b>RS3517XP</b>
	<b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960) <b>CA5420 +</b>	


\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
FL80 w/Cat C12 Eng. F-F Lube (1R0716)..... B99 + F-F Lube (High Efficiency) (1R1808)..... B7299 + B-P Lube (1W8845)..... B7577 Fuel/Water Separator (Open End for Bowl) (1335673)..... BF1395-O Fuel/Water Separator (w/Drain) (1335673)..... BF1265 Fuel/Water Separator (w/Sensor Port) (1335673)..... BF1395-SP Fuel/Water Separator (256-8753)..... BF1259 P. Fuel (1R1712)..... BF614 + P. Fuel (High Efficiency) (1R0749)..... BF7587 + Radial Seal Air (Don. P532966)... RS3517 Radial Seal XP Air (Don. P532966)..... RS3517XP	FL80 w/Cummins B5.9L Eng. Lube..... BT339 + Lube (Fleetguard LF3959)..... BT7349 Fuel/Water Separator (M16 x 1.5 Thd.) (Fleetguard FS1251)..... BF1226 Fuel/Water Separator (13/16-18 Thd.)..... BF1280 + S. Fuel..... BF788 Radial Seal Air (Don. P532966)... RS3517 Radial Seal XP Air (Don. P532966)..... RS3517XP Trans. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT Steering (S1414)..... PT8407	FL80 w/Cummins C8.3 (Australia) (Cont'd) Opt. Radial Seal I. Air (Don. P533781)..... RS3717 Air Dryer (Bendix 107796)..... BA5377 Coolant (w/4 Units BTA+) (3315116)..... BW5071 Coolant (w/12 Units BTA+) (Fleetguard WF2074)..... BW5074 Trans. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT Steering (S1414)..... PT8407
FL80 w/Cat 3126 Eng. Lube (Standard Vers.) (1R0739).. B76 Lube (1R-1807)..... B7700 + Fuel/Water Separator Spin-on.... BF1259 Fuel/Water Separator Spin-on (175-2949)..... BF1268 Fuel/Water Separator Spin-on (w/o SP) (Racor S3225P)..... BF1348 Fuel/Water Separator Spin-on (w/SP) (Racor S3225P)..... BF1348-SP Fuel/Water Separator Spin-on (Open End for Bowl) (Racor S3225P)..... BF1348-O Fuel (Davco 210) (Davco 101377)..... BF788 Fuel (1R0751)..... BF7632 Radial Seal O. Air (Don. P532966)..... RS3517 Radial Seal XP O. Air (Don. P532966)..... RS3517XP Radial Seal I. Air (Don. P533781)..... RS3717 Air Dryer (AD-9 System) (Bendix 107796)..... BA5377 Trans. Ele. (2 In. Kit) (Allison 29548987)..... PT9416-MPG KIT Trans. Ele. (4 In. Kit) (Allison 29548988)..... PT9415-MPG KIT Opt. Trans. Spin-on (Fuller 17237)..... B2 + 2 23/32 In. Steering (Nelson 87904A)..... PT9354-MPG 4 5/32 In. Steering (S1414)..... PT8407	FL80 w/Cummins 6B Series Natural Gas Eng. Lube (To 1998) (3914395)..... BT339 + Lube (1998-on) (Chrysler 5083285AA)..... BT7349 Radial Seal Air (Don. P532966)... RS3517 Radial Seal XP Air (Don. P532966)..... RS3517XP	FL80 w/Cummins C8.3 (North America) F-F Lube (3313281)..... B205 + Dual-Flow Lube (3318853)..... BD103 + Fuel/Water Separator (w/o SP) (Racor S3225P)..... BF1348 Fuel/Water Separator (w/SP) (Racor S3225P)..... BF1348-SP Fuel/Water Separator (Open End for Bowl) (Racor S3225P)..... BF1348-O Fuel/Water Separator (Fleetguard FS1251)..... BF1226 Radial Seal Air (Don. P532966)... RS3517 Radial Seal XP Air (Don. P532966)..... RS3517XP Air Dryer (AD-9 System) (Bendix 107796)..... BA5377 Coolant (w/6 Units BTA+) (Fleetguard WF2072)..... BW5072 Coolant (w/12 Units BTA+) (Fleetguard WF2074)..... BW5074 Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT Opt. Trans. Spin-on (Fuller 17237)..... B2 + Steering (S1414)..... PT8407
FL80 w/Cummins 6C Series Natural Gas Eng. F-F Lube (3313281)..... B205 + Dual-Flow Lube (3318853)..... BD103 + Radial Seal Air (Don. P532966)... RS3517 Radial Seal XP Air (Don. P532966)..... RS3517XP	FL80 w/Cummins 6BT5.9 (5.9L) Eng. Lube (3914395)..... BT339 + Fuel/Water Separator (Fleetguard FS1251)..... BF1226 Fuel/Water Separator (Fleetguard FS1280)..... BF1280 + S. Fuel (3903640)..... BF788 Radial Seal Air (Don. P532966)... RS3517 Radial Seal XP Air (Don. P532966)..... RS3517XP Trans. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	FL80 w/Cummins ISC (8.3L) Eng. Dual-Flow Lube (3401544)..... BD7309 + Lube (Upgrade) (3401544)..... B40142 + Fuel/Water Separator (3944269). BF1272-SPS Fuel/Water Separator (Open End for Bowl) (Racor R90P)..... BF46083-O Fuel/Water Separator (w/Bowl) (Racor R90P)..... BF46072 Fuel/Water Separator (w/Drain) (Racor R90P)..... BF1329 Fuel/Water Separator (Sensor Port Thd. 9/16-18) (Racor R90P).. BF1329-SP Fuel/Water Separator (Sensor Port Thd. 1/2-20) (Racor R90P)... BF1339-SP + Radial Seal O. Air (Don. P532966)..... RS3517 Radial Seal XP O. Air (Don. P532966)..... RS3517XP
FL80 w/Cummins 4B Series Eng. Lube (3903224)..... BT427 + Fuel/Water Separator (3903202). BF1226 Fuel (3903640)..... BF788 Radial Seal Air (Don. P532966)... RS3517 Radial Seal XP Air (Don. P532966)..... RS3517XP	FL80 w/Cummins 6CT8.3 (8.3L) Eng. Lube (Don. P551381)..... B7005 Fuel/Water Separator (3843760). BF1226 Radial Seal O. Air (Don. P526678)..... RS3520 Radial Seal I. Air (Don. P529548)..... RS3521 Coolant (3318201)..... BW5072	FL80 w/Cummins C8.3 (Australia) Dual-Flow Lube (3318853)..... BD103 + Fuel/Water Separator (3843760). BF1226 Radial Seal O. Air (Don. P532966)..... RS3517 Radial Seal XP O. Air (Don. P532966)..... RS3517XP

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
FL80 w/Cummins ISC (8.3L) Eng. (Cont'd)	FL80 w/Mercedes-Benz MBE900 Eng.	FL106 w/Detroit Diesel Series 50 (8.5L) Eng. (To 1993) (Cont'd)
Radial Seal I. Air (Don. P533781).....	F-F Lube Ele. (A0001801709).....	Fuel/Water Separator (Sensor Port Thd. 1/2-20) (Racor R90P)....
RS3717	P7188	BF1339-SP +
Air Dryer (Bendix 107796).....	Opt. B-P Lube Spinner (A9061810086).....	P. Fuel (23518481).....
BA5377	BC7326 +	BF5800 +
Coolant (Fleetguard WF2071).....	Fuel/Water Separator (Open End for Bowl) (Racor S3226P).....	S. Fuel.....
BW5071	BF1346-O	BF5810
Trans. Ele. (2 In. Kit) (Allison 29540493).....	Fuel/Water Separator (w/Sensor Port) (Racor S3226P).....	15 In. Radial Seal Air (Don. P526678).....
PT9416-MPG KIT	BF1346-SP	RS3520
Trans. Ele. (4 In. Kit) (Allison 29540494).....	Fuel/Water Separator (w/Drain) (Racor S3226P).....	18 15/16 In. Radial Seal Air (Don. P532966).....
PT9415-MPG KIT	BF1346	RS3517
Opt. Trans. Spin-on (Fuller 17237).....	Fuel (A0000901551).....	18 15/16 In. Radial Seal XP Air (Don. P532966).....
B2 +	PF7735	RS3517XP
Steering (S1414).....	Radial Seal Air (Don. P532966)...	Air Dryer (AD-9 System) (Bendix 107796).....
PT8407	RS3517	BA5377
FL80 w/Cummins ISL Eng.	Radial Seal XP Air (Don. P532966).....	Opt. Trans. Spin-on (Fuller 17237).....
Dual-Flow Lube (Fleetguard LF9009).....	RS3517XP	B2 +
BD7309 +	Air Dryer (AD-IP System) (Bendix 65624).....	2 23/32 In. Steering (Nelson 87904A).....
Fuel/Water Separator (Fleetguard FS1022).....	BA5373	PT9354-MPG
BF1272-SPS	Air Dryer (AD-9 System) (Bendix 107796).....	4 5/32 In. Steering (S1414).....
Fuel/Water Separator (Fleetguard FS1065).....	BA5377	PT8407
BF1378-SPS	Opt. Trans. Spin-on (Fuller 17237).....	FL106 w/Detroit Diesel Series 50 (8.5L) Eng. (1993-on)
P. Fuel (Fleetguard FF5488).....	B2 +	F-F Lube (23530573).....
BF7815	PT8407	[2] B495
P. Fuel (Fleetguard FF5636).....	4 5/32 In. Steering (Nelson 87904A).....	B-P Lube (ACDelco P940).....
BF7924	PT9354-MPG	B7577
Radial Seal Air (Don. P532966)...	FL106 w/Cat 3126B Eng.	Fuel/Water Separator Ele. (Davco 382) (23521528).....
RS3517	Lube (To 1/2004 (Standard Vers.)) (1R0739).....	PF7744
Radial Seal XP Air (Don. P532966).....	B76	Fuel/Water Separator Ele. (Davco 382) (Davco 382113).....
RS3517XP	Lube (1/2004-on) (1R1807).....	PF7748
FL80 w/Cummins M11 Eng.	B7700 +	Fuel/Water Separator Ele. (Davco 382) (Davco 102185).....
Dual-Flow Lube (3318853).....	Fuel/Water Separator (175-2949).....	PF680
BD103 +	BF1268	Fuel/Water Separator (Open End for Bowl) (Racor R90P).....
Fuel/Water Separator Ele. (Fleetguard FS1029W).....	Fuel/Water Separator (256-8753).....	BF46083-O
PF7680	BF1259	Fuel/Water Separator (w/Bowl) (Racor R90P).....
Fuel/Water Separator Spin-on (3329289).....	BF7632	BF46072
BF1259	FL106 w/Cummins N14 Eng.	Fuel/Water Separator (w/Drain) (Racor R90P).....
Radial Seal Air (Don. P532966)...	F-F Lube (9 15/16 In.) (Fleetguard LF670SC).....	BF1329
RS3517	B196 +	Fuel/Water Separator (Sensor Port Thd. 9/16-18) (Racor R90P)..
Radial Seal XP Air (Don. P532966).....	F-F Lube (11 9/32 In.) (Fleetguard LF670SC).....	BF1329-SP
RS3517XP	B96 +	Fuel/Water Separator (Sensor Port Thd. 1/2-20) (Racor R90P)....
FL80 w/Detroit Diesel 6-71 Eng.	Dual-Flow Lube (3318853).....	BF1339-SP +
Lube (23530407).....	BD103 +	P. Fuel (23518481).....
B95 +	B-P Lube (3304232).....	BF5800 +
Lube (Upgrade) (23530408).....	B7577	BF5810
B95-MPG +	Fuel/Water Separator (3329289).....	S. Fuel (Upgrade) (23530645).....
P. Fuel (23530706).....	BF1259	BF5815
BF5800 +	BF957-D +	Radial Seal Air (Don. P532966)...
S. Fuel (23530707).....	FL106 w/Detroit Diesel Series 50 (8.5L) Eng. (To 1993)	RS3517
BF5810	F-F Lube (ACDelco PF911).....	Radial Seal XP Air (Don. P532966).....
BF5815	[2] B95 +	RS3517XP
Radial Seal Air (Don. P532966)...	B-P Lube (ACDelco P940).....	FL80 w/Detroit Diesel Series 50 Eng.
RS3517	B7577	Lube (23530573).....
Radial Seal XP Air (Don. P532966).....	Fuel/Water Separator Ele. (Davco 382) (23521528).....	[2] B495
RS3517XP	PF7744	Fuel/Water Separator (23516189).....
FL80 w/Detroit Diesel Series 50 Eng.	Fuel/Water Separator Ele. (Davco 382) (Davco 382113).....	BF5812
Lube (23530573).....	PF7748	Fuel/Water Separator (w/Drain) (23535985).....
[2] B495	Fuel/Water Separator Ele. (Davco 382) (Davco 102185).....	BF5813 +
Fuel/Water Separator (23516189).....	PF680	Fuel/Water Separator (Open End for Bowl) (23535985).....
BF5812	Fuel/Water Separator (Open End for Bowl) (Racor R90P).....	BF5813-O +
Fuel/Water Separator (w/Drain) (23535985).....	BF46083-O	P. Fuel (23530706).....
BF5813 +	Fuel/Water Separator (w/Bowl) (Racor R90P).....	BF5800 +
Fuel/Water Separator (Open End for Bowl) (23535985).....	BF46072	BF5810
BF5813-O +	Fuel/Water Separator (w/Drain) (Racor R90P).....	Radial Seal Air (Don. P532966)...
P. Fuel (23530706).....	BF1329	RS3517
BF5800 +	Fuel/Water Separator (Sensor Port Thd. 9/16-18) (Racor R90P)..	Radial Seal XP Air (Don. P532966).....
S. Fuel (23530707).....	BF1329-SP	RS3517XP
BF5810	FL112 w/Cat C10 Eng.	FL112 w/Cat C10 Eng.
Radial Seal Air (Don. P532966)...	Lube (1R0716).....	Lube (1R0716).....
RS3517	B99 +	B99 +
Radial Seal XP Air (Don. P532966).....	Fuel/Water Separator Ele. (Davco 382113).....	Fuel/Water Separator Ele. (Davco 382113).....
RS3517XP	PF7748	PF7748

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>	<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>	<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>
FL112 w/Cat C10 Eng. (Cont'd)	FL112 w/Cat C12 Eng. (Cont'd)	FL112 w/Cummins ISM Eng. (Australia) (Cont'd)
<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor S3226P)..... <b>BF1346-O</b>	<b>Fuel/Water Separator</b> (w/Drain) (Racor S3226P)..... <b>BF1346</b>	<b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b>
<b>Fuel/Water Separator</b> (w/Sensor Port) (Racor S3226P)..... <b>BF1346-SP</b>	<b>Fuel</b> (1R-0749)..... <b>BF7587 +</b>	<b>Trans.</b> (Fuller 4304827)..... <b>BT223</b>
<b>Fuel/Water Separator</b> (w/Drain) (Racor S3226P)..... <b>BF1346</b>	<b>Axial Seal Air</b> (Don. P153551).... <b>PA2705</b>	<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R90P)..... <b>BF46083-O</b>	<b>Radial Seal Air</b> (Standard) (Don. EAF5069)..... <b>RS3518</b>	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>
<b>Fuel/Water Separator</b> (w/Bowl) (Racor R90P)..... <b>BF46072</b>	<b>Radial Seal XP Air</b> (Upgrade) (Don. EAF5069)..... <b>RS3518XP</b>	FL112 w/Cummins ISM (10.8L) Eng. (North America)
<b>Fuel/Water Separator</b> (w/Drain) (Racor R90P)..... <b>BF1329</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>11 25/32 In. Dual-Flow Lube</b> (3101869)..... <b>BD7154 +</b>
<b>Fuel/Water Separator</b> (Sensor Port Thd. 9/16-18) (Racor R90P).. <b>BF1329-SP</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>
<b>Fuel/Water Separator</b> (Sensor Port Thd. 1/2-20) (Racor R90P).... <b>BF1339-SP +</b>	<b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134 +</b>	<b>14 7/32 In. Dual-Flow Lube</b> ..... <b>BD7153 +</b>
<b>Fuel</b> (1R0749)..... <b>BF7587 +</b>	<b>Coolant</b> (w/Chemical) (Nalcool NF2088)..... <b>BW5200</b>	<b>Fuel/Water Separator Spin-on</b> (w/Drain) (Alliance ABPS3226FL01)..... <b>BF1347</b>
<b>Radial Seal Air</b> (Standard) (Don. P527682)..... <b>RS3518</b>	<b>Trans.</b> (Fuller 4304827)..... <b>BT223</b>	<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Alliance ABPS3226FL01)..... <b>BF1347-O</b>
<b>Radial Seal XP Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b>	<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	<b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (Alliance ABPS3226FL01)..... <b>BF1373-SP</b>
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>Fuel/Water Separator Ele.</b> (Racor 2020PMOR)..... <b>PF7890-30</b>
<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Fuel/Water Separator Spin-on</b> (3329289)..... <b>BF1259</b>
<b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134 +</b>	FL112 w/Cat 3126 Eng.	<b>Axial Seal Air</b> (Don. P153551).... <b>PA2705</b>
<b>Coolant</b> (w/Chemical) (Nalcool NF2088)..... <b>BW5200</b>	<b>Lube</b> (1R1807)..... <b>B7700 +</b>	<b>15 1/4 In. Radial Seal Air</b> (Standard) (Don. EAF5069)..... <b>RS3518</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Fuel</b> (1R0751)..... <b>BF7632</b>	<b>15 1/4 In. Radial Seal XP Air</b> (Upgrade) (Don. EAF5069)..... <b>RS3518XP</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Radial Seal Air</b> (Don. P532966).. <b>RS3517</b>	<b>18 15/16 In. Radial Seal Air</b> (Don. P532966)..... <b>RS3517</b>
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Radial Seal XP Air</b> (Don. P532966)..... <b>RS3517XP</b>	<b>18 15/16 In. Radial Seal XP Air</b> (Don. P532966)..... <b>RS3517XP</b>
<b>Steering</b> (Nelson 87904A)..... <b>PT9354-MPG</b>	<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Steering</b> (S1414)..... <b>PT8407</b>	<b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134 +</b>
FL112 w/Cat C12 Eng.	FL112 w/Cat 3176 Eng.	<b>Coolant</b> (w/Chemical) (3100304). <b>BW5071</b>
<b>Lube</b> (1R0716)..... <b>B99 +</b>	<b>F-F Lube</b> (1R0716)..... <b>B99 +</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Fuel/Water Separator Spin-on</b> (w/Drain) (Alliance S3226FL01).... <b>BF1347</b>	<b>F-F Lube</b> (High Efficiency) (1R1808)..... <b>B7299 +</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Alliance S3226FL01)..... <b>BF1347-O</b>	<b>F-F Lube</b> (1R0713)..... <b>BT230 +</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
<b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (Alliance S3226FL01)..... <b>BF1373-SP</b>	<b>Opt. B-P Lube</b> (1W8845)..... <b>B7577</b>	<b>3 3/8 In. O.D. Steering</b> (Nelson 87904A)..... <b>PT9354-MPG</b>
<b>Fuel/Water Separator Ele.</b> (Davco 382113)..... <b>PF7748</b>	<b>Fuel/Water Separator</b> (256-8753)..... <b>BF1259</b>	<b>4 1/32 In. O.D. Steering</b> (S1414).. <b>PT8407</b>
<b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1212)..... <b>BF1212 +</b>	<b>4 3/8 In. O.D. Steering</b> (Nelson 83213M)..... <b>P528</b>
<b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1212)..... <b>BF1212 +</b>	<b>Fuel Ele.</b> (8H7204)..... <b>PF935</b>	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor S3226P)..... <b>BF1346-O</b>	<b>Fuel Spin-on</b> (1R1740)..... <b>BF970 +</b>	FL112 w/Cummins L10 Eng.
<b>Fuel/Water Separator</b> (w/Sensor Port) (Racor S3226P)..... <b>BF1346-SP</b>	<b>Air</b> (Don. P153551)..... <b>PA2705</b>	<b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b>
	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>9 15/16 In. F-F Lube</b> (Fleetguard LF670SC)..... <b>B196 +</b>
	<b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134 +</b>	
	<b>Coolant</b> (w/Chemical) (Fleetguard WF2054)..... <b>BW5140</b>	
	<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	
	<b>Steering</b> (Nelson 83213M)..... <b>P528</b>	
	FL112 w/Cummins ISM Eng. (Australia)	
	<b>Dual-Flow Lube</b> (3406810)..... <b>BD7153 +</b>	
	<b>Fuel/Water Separator</b> (3329289). <b>BF1259</b>	
	<b>Radial Seal Air</b> (Standard) (Don. EAF5069)..... <b>RS3518</b>	
	<b>Radial Seal XP Air</b> (Upgrade) (Don. EAF5069)..... <b>RS3518XP</b>	
	<b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
FL112 w/Cummins L10 Eng. (Cont'd)	FL112 w/Detroit Diesel Series 50 (8.5L) Eng. (Cont'd)	FL112 w/Mercedes-Benz MBE4000 Eng. (Cont'd)
11 9/32 In. F-F Lube (Fleetguard LF670SC).....	S. Fuel (23530707).....	Fuel (A5410900151).....
B96 +	BF5810	PF7761
Fuel/Water Separator (3308638).....	FL112 w/Detroit Diesel Series 55 Eng. Lube (23550401).....	Radial Seal Air (Standard) (Don. P527682).....
BF1212 +	B7135	RS3518
Fuel (154789).....	Fuel/Water Separator Ele. (23521528).....	Radial Seal XP Air (Upgrade) (Don. P527682).....
BF957-D +	PF7744	RS3518XP
Conical Air (Don. P151097).....	Fuel/Water Separator (Open End for Bowl) (Racor S3226P).....	Air Dryer (AD-9 System) (Bendix 107796).....
PA3951	BF1346-O	BA5377
Axial Seal Air (Don. P153551).....	Fuel/Water Separator (w/Sensor Port) (Racor S3226P).....	Coolant (Fleetguard WF2077).....
PA2705	BF1346-SP	B5134 +
Air Dryer (AD-9 System) (Bendix 107796).....	Fuel/Water Separator (w/Drain) (Racor S3226P).....	Opt. Trans. (Fuller 17237).....
BA5377	BF1346	B2 +
Opt. Trans. (Fuller 17237).....	Fuel (23530707).....	Steering (Nelson 83213D).....
B2 +	BF5810	PT951
Steering (Nelson 83213D).....	Radial Seal Air (Standard) (Don. EAF5069).....	Some Differential (Fleetguard LF651).....
PT951	RS3518	B27
Some Differential (Fleetguard LF651).....	Radial Seal XP Air (Upgrade) (Don. EAF5069).....	
B27	RS3518XP	
FL112 w/Cummins M11 (10.8L) Eng.	Air Dryer (AD-9 System) (Bendix 107796).....	FL360 w/Mitsubishi 4M50-3AT7 (4.9L) Turbo Diesel (Mexico)
Dual-Flow Lube (3318853).....	Coolant (Fleetguard WF2077).....	Lube (Mitsubishi ME088532).....
BD103 +	B5134 +	B7121
Fuel/Water Separator Ele. (Fleetguard FS1029W).....	Opt. Trans. (Fuller 17237).....	Fuel (Mitsubishi ME222135).....
PF7680	B2 +	PF9803 +
Fuel/Water Separator (Open End for Bowl) (Racor R90P).....	FL112 w/Detroit Diesel Series 60 Eng.	Radial Seal Air (Mitsubishi ME017246).....
BF46083-O	Lube (23530573).....	RS4806
Fuel/Water Separator (w/Bowl) (Racor R90P).....	P. Fuel (23530706).....	FLA w/Cat 3176 Eng.
BF46072	[2] B495	F-F Lube (1R0716).....
Fuel/Water Separator (w/Drain) (Racor R90P).....	S. Fuel (23530707).....	B99 +
BF1329	BF5810	F-F Lube (High Efficiency) (1R1808).....
Fuel/Water Separator (Sensor Port Thd. 9/16-18) (Racor R90P).....	Axial Seal Air (w/Lid) (Don. P150695).....	B7299 +
BF1329-SP	PA2680	Opt. B-P Lube (1W8845).....
Fuel/Water Separator (Sensor Port Thd. 1/2-20) (Racor R90P).....	Conical Air (Don. P141228).....	B7577
BF1339-SP +	PA2632	Fuel/Water Separator (256-8753).....
Fuel/Water Separator Spin-on (3161407).....	Air Dryer (AD-9 System) (Bendix 107796).....	BF1259
BF1259	BA5377	P. Fuel (1R1740).....
Conical Air (Don. P154575).....	Coolant (w/Chemical) (23507189).....	BF970 +
PA2715	BW5140	S. Fuel (1R0750).....
22 9/16 In. Std. Air (Don. P153551).....	Coolant (w/o Chemical) (Fleetguard WF2077).....	BF7633 +
PA2705	B5134 +	Air (Don. P525493).....
Radial Seal Air (Standard) (Don. EAF5069).....	Trans. (Fuller 4304827).....	
RS3518	BT223	FLA w/Cat 3306 Eng.
Radial Seal XP Air (Upgrade) (Don. EAF5069).....	Opt. Trans. (Fuller 17237).....	Lube (1R0716).....
RS3518XP	B2 +	B99 +
Air Dryer (AD-IP System) (Bendix 65624).....	Some Differential (Meritor 3280-V-8394).....	Lube (To 1/2004 (Std. Version)) (1R0739).....
BA5373	B233	B76
Air Dryer (AD-9 System) (Bendix 107796).....	FL112 w/Mercedes-Benz MBE906 Eng.	Lube (1/2004-on) (1R1807).....
BA5377	F-F Lube (A0001801709).....	B7700 +
Air Dryer (Haldex DA33120).....	P7188	Fuel/Water Separator (256-8753).....
BA5371	Opt. B-P Lube (A9061810086).....	BF1259
Coolant (w/o Chemical) (Fleetguard WF2077).....	BC7326 +	P. Fuel (9M2341).....
B5134 +	PF7735	PF935
Coolant (w/Chemical) (Fleetguard WF2071).....	S. Fuel (A5410920805).....	P. Fuel (1R0740).....
BW5071	PF7761	BF970 +
Opt. Trans. (Fuller 17237).....	FL112 w/Mercedes-Benz MBE4000 Eng.	S. Fuel (1R0750).....
B2 +	Lube (A0001802109).....	BF7633 +
2 23/32 In. Steering Ele. (Nelson 87904A).....	P7230	18 9/16 In. Air (Nelson 70140N)...
PT9354-MPG	Fuel/Water Separator (w/Drain) (Alliance S3226FL01).....	PA2333
4 3/16 In. Steering Ele. (Nelson 83213M).....	BF1347	22 9/16 In. Std. Air (Don. P153551).....
P528	Fuel/Water Separator (Open End for Bowl) (Alliance S3226FL01).....	PA2705
Some Differential (Meritor 3280-V-8394).....	BF1347-O	29 In. Conical Air (Nelson 70179N).....
B233	BF1373-SP	PA3951
FL112 w/Detroit Diesel Series 50 (8.5L) Eng.	Fuel/Water Separator (w/Sensor Port) (Alliance S3226FL01).....	FLA w/Cat 3406 Eng.
Lube (23530573).....	BF1346-O	F-F Lube (1R0716).....
[2] B495	BF1346-O	B99 +
Fuel/Water Separator (w/Drain) (23535985).....	Fuel/Water Separator (Open End for Bowl) (Racor S3226P).....	F-F Lube (High Efficiency) (1R1808).....
BF5813 +	BF1346-SP	B7299 +
Fuel/Water Separator (Open End for Bowl) (23535985).....	Fuel/Water Separator (w/Drain) (Racor S3226P).....	Fuel/Water Separator Ele. (Racor 2020PMOR).....
BF5813-O +	BF1346	PF7890-30
P. Fuel (23530706).....		Fuel/Water Separator Spin-on (256-8753).....
BF5800 +		BF1259
		Fuel/Water Separator Spin-on (Fleetguard FS1212).....
		BF1212 +
		P. Fuel Ele. (9M2342).....
		PF935
		Fuel Spin-on (4N5823).....
		BF614 +
		Fuel Spin-on (High Efficiency) (1R0749).....
		BF7587 +
		Axial Seal Air (Nelson 70140N)...
		PA2333

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
FLA w/Cat 3406 Eng. (Cont'd)	FLA w/Detroit Diesel Series 60 Eng. (Cont'd)	FLB w/Cat C12 Eng.
P153551)..... PA2705	S. Fuel (12/03-12/06)..... BF5816	F-F Lube (1R0716)..... B99 +
29 In. Conical Air (Nelson 70179N)..... PA3951	Axial Seal Air (Don. P153551)..... PA2705	F-F Lube (High Efficiency) (1R1808)..... B7299 +
Radial Seal Air (Don. P531026).... RS3516	Radial Seal Air (Don. P531026).... RS3516	B-P Lube (1W8845)..... B7577
Radial Seal XP Air (Don. DBA5106)..... RS3516XP	Radial Seal XP Air (Don. DBA5106)..... RS3516XP	Fuel/Water Separator Ele. (Racor 2020TMOR)..... PF7890-10
Air Dryer (Haldex DA33120)..... BA5371	Air Dryer (AD-9 System) (Bendix 107796)..... BA5377	Fuel/Water Separator Ele. (Racor 2020PMOR)..... PF7890-30
Coolant (w/o Chemical) (Fleetguard WF2077)..... B5134 +	Coolant (w/12 Units BTE) (Nalcool NF2088)..... BW5200	Fuel/Water Separator (Open End for Bowl) (1335673)..... BF1395-O
Opt. Trans. (Fuller 17237)..... B2 +	Coolant (w/16 Units BTE) (Fleetguard WF2055)..... BW5140	Fuel/Water Separator (w/Drain) (1335673)..... BF1265
Steering (Nelson 83213M)..... P528	Opt. Trans. (Fuller 17237)..... B2 +	Fuel/Water Separator (w/Sensor Port) (1335673)..... BF1395-SP
FLA w/Cummins L-10 Eng.	Steering (Nelson 83213M)..... P528	Fuel/Water Separator Spin-on (Fleetguard FS1212)..... BF1212 +
Dual-Flow Lube (3318853)..... BD103 +	FLA w/Detroit Diesel 6V92 Eng.	Fuel/Water Separator Spin-on (256-8753)..... BF1259
F-F Lube (Fleetguard LF670SC)..... B196 +	Lube (23530407)..... B95 +	P. Fuel (1R1712)..... BF614 +
B-P Lube (3304232)..... B7577	Lube (Upgrade) (23530408)..... B95-MPG +	P. Fuel (High Efficiency) (1R0749)..... BF7587 +
Fuel (154789)..... BF957-D +	P. Fuel (23530706)..... BF5800 +	Radial Seal Air (Don. P531026).... RS3516
18 9/16 In. Air (Nelson 70140N).... PA2333	S. Fuel (23530707)..... BF5810	Radial Seal XP Air (Don. DBA5106)..... RS3516XP
20 17/32 In. Air w/Lid (Don. P155842)..... PA2704	S. Fuel (Upgrade) (23530645).... BF5815	Air Dryer (AD-SP System) (Bendix 109994)..... BA5374 +
22 9/16 In. Std. Air (Don. P153551)..... PA2705	Radial Seal Air (Don. P525493).... PA2705	Air Dryer (AD-9 System) (Bendix 107796)..... BA5377
29 In. Conical Air (Nelson 70179N)..... PA3951	FLA w/Detroit Diesel 8V71 Eng.	Coolant (Fleetguard WF2077)..... B5134 +
FLA w/Cummins N14 Eng.	Lube (23530407)..... B95 +	Trans. (Fuller 4304827)..... BT223
F-F Lube (9 15/16 In.) (Fleetguard LF670SC)..... B196 +	Lube (Upgrade) (23530408).... B95-MPG +	Steering (Nelson 83213M)..... P528
F-F Lube (11 9/32 In.) (Fleetguard LF670SC)..... B96 +	P. Fuel (23530706)..... BF5800 +	Some Differential (Meritor 3280-V-8394)..... B233
B-P Lube (3304232)..... B7577	S. Fuel (23530707)..... BF5810	FLB w/Cat 3126 (7.2L) Eng.
Fuel/Water Separator (To 12/1995) (3308638)..... BF1212 +	S. Fuel (Upgrade) (23530645).... BF5815	Lube (Standard Vers.) (1R0739).. B76
Fuel/Water Separator (12/1995-on) (3329289)..... BF1259	Radial Seal Air (Don. P525493).... PA2705	Fuel/Water Separator (175-2949)..... BF1268
Fuel (154789)..... BF957-D +	FLA w/Detroit Diesel 8V92 Eng.	Fuel/Water Separator (256-8753)..... BF1259
Air (Don. P525493)..... PA2705	Lube (23530407)..... B95 +	Fuel (1R0751)..... BF7632
Air Dryer (Bendix 107796)..... BA5377	Lube (Upgrade) (23530408).... B95-MPG +	FLB w/Cat 3176 Eng.
Coolant (Fleetguard WF2076).... BW5076	P. Fuel (23530706)..... BF5800 +	F-F Lube (1R0716)..... B99 +
Opt. Trans. (Fuller 17237)..... B2 +	S. Fuel (23530707)..... BF5810	F-F Lube (High Efficiency) (1R1808)..... B7299 +
Steering (Nelson 83213M)..... P528	S. Fuel (Upgrade) (23530645).... BF5815	F-F Lube (1R0713)..... BT230 +
Some Rear Axle (Meritor 3280-V-8394)..... B233	Radial Seal Air (Don. P525493).... PA2705	(Opt.) B-P Lube (1W8845)..... B7577
FLA w/Cummins NTC-855 Eng.	FLB w/Cat C10 Eng.	Fuel/Water Separator Ele. (Racor 2020TMOR)..... PF7890-10
F-F Lube (3313279)..... B196 +	F-F Lube (1R0716)..... B99 +	Fuel/Water Separator Ele. (Racor 2020PMOR)..... PF7890-30
Dual-Flow Lube (3318853)..... BD103 +	F-F Lube (High Efficiency) (1R1808)..... B7299 +	Fuel/Water Separator Spin-on (256-8753)..... BF1259
B-P Lube (3313283)..... B7577	B-P Lube (1W8845)..... B7577	P. Fuel (1R0751)..... BF7632 +
Fuel/Water Separator (3308638).... BF1212 +	Fuel/Water Separator Ele. (Racor 2020PMOR)..... PF7890-30	S. Fuel (1R0750)..... BF7633 +
Fuel (154709)..... BF957 +	P. Fuel (1R1712)..... BF614 +	Radial Seal Air (Don. P531026).... RS3516
22 9/16 In. Air (Don. P153551).... PA2705	P. Fuel (High Efficiency) (1R0749)..... BF7587 +	Radial Seal XP Air (Don. DBA5106)..... RS3516XP
28 9/16 In. Air (Don. P150695).... PA2680	Radial Seal Air (Don. P531026).... RS3516	Air Dryer (AD-9 System) (Bendix 107796)..... BA5377
FLA w/Detroit Diesel Series 60 Eng.	Radial Seal XP Air (Don. DBA5106)..... RS3516XP	Coolant (w/o Chemical) (Fleetguard WF2077)..... B5134 +
Lube (To 1993) (23530407)..... [2] B95 +	Air Dryer (AD-9 System) (Bendix 107796)..... BA5377	Opt. Trans. (Fuller 17237)..... B2 +
Lube (1993-on) (23530573)..... [2] B495	Coolant (w/o Chemical) (Fleetguard WF2077)..... B5134 +	Steering (Nelson 83213M)..... P528
Fuel/Water Separator (23521528)..... PF7744	Opt. Trans. (Fuller 17237)..... B2 +	
P. Fuel (23530706)..... BF5800 +	Steering (Nelson 83213M)..... P528	
S. Fuel (To 12/03) (23530707).... BF5810		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
FLB w/Cat 3176 Eng. (Cont'd)	FLB w/Cummins N14 Eng. (Australia) (Cont'd)	FLC w/Cat 3126 (7.2L) Eng. (Cont'd)
Opt. Trans. (Fuller 17237)..... B2 +	Steering (Nelson 83213A)..... PT951	Fuel/Water Separator
Steering (Nelson 83213M)..... P528	Rear Axle (Meritor 3280-V-8394). B233	(256-8753)..... BF1259
FLB w/Cat 3406 (14.6L) Eng.	FLB w/Cummins N14 Eng. (North America)	Fuel (1R0751)..... BF7632
F-F Lube (1R0716)..... B99 +	F-F Lube (9 15/16 In.)	Air (Don. P525493)..... PA2705
B-P Lube (Fleetguard LF777)..... B7577	(Fleetguard LF670SC)..... B196 +	FLC w/Cat 3176 Eng.
Fuel/Water Separator	F-F Lube (11 9/32 In.)	F-F Lube (1R0716)..... B99 +
(Fleetguard FS1212)..... BF1212 +	(Fleetguard LF670SC)..... B96 +	F-F Lube (High Efficiency)
P. Fuel Ele..... [2] PF935	Dual-Flow Lube (3318853)..... BD103 +	(1R1808)..... B7299 +
Fuel Spin-on (1R-0749)..... BF7587 +	B-P Lube (3304232)..... B7577	F-F Lube (1R0713)..... BT230 +
Radial Seal Air (Don. P531026)... RS3516	Fuel/Water Separator (3308638). BF1212 +	Opt. B-P Lube (1W8845)..... B7577
Radial Seal XP Air (Don. DBA5106)..... RS3516XP	Fuel/Water Separator (3329289). BF1259	Fuel/Water Separator
Air Dryer (AD-9 System) (Bendix 107796)..... BA5377	P. Fuel (154789)..... BF957-D +	(256-8753)..... BF1259
Coolant (Fleetguard WF2077)..... B5134 +	Radial Seal Air (Don. P531026)... RS3516	Fuel/Water Separator
Opt. Trans. (Fuller 17237)..... B2 +	Radial Seal XP Air (Don. DBA5106)..... RS3516XP	(Fleetguard FS1212)..... BF1212 +
Steering (Nelson 83213M)..... P528	Air Dryer (AD-9 System) (Bendix 107796)..... BA5377	P. Fuel (1R1740)..... BF970 +
FLB w/Cummins L10 Eng.	Opt. Trans. (Fuller 17237)..... B2 +	S. Fuel (1R0750)..... BF7633 +
F-F Lube (9 15/16 In.)	Steering (Nelson 83213M)..... P528	Air (Don. P525493)..... PA2705
(Fleetguard LF670SC)..... B196 +	FLB w/Detroit Diesel Series 50 Eng.	Air Dryer (AD-9 System) (Bendix 107796)..... BA5377
F-F Lube (11 9/32 In.)	Lube (To 1993) (23530407)..... [2] B95 +	Coolant (Fleetguard WF2054)..... BW5140
(Fleetguard LF670SC)..... B96 +	Lube (1993-on) (23530573)..... [2] B495	Opt. Trans. (Fuller 17237)..... B2 +
Dual-Flow Lube (3318853)..... BD103 +	Fuel/Water Separator	Steering (Nelson 83213M)..... P528
B-P Lube (3304232)..... B7577	(23516189)..... BF5812	FLC w/Cat 3306 Eng.
Fuel/Water Separator (3308638). BF1212 +	Fuel/Water Separator (w/Drain)	Lube Ele. (5S0484)..... PT670
Fuel (154789)..... BF957-D +	(23535985)..... BF5813 +	Lube Spin-on (1R0716)..... B99 +
FLB w/Cummins M11 Eng.	Fuel/Water Separator (Open End for Bowl) (23535985)..... BF5813-O +	Lube Spin-on (Standard Vers.) (1R0739)..... B76
Dual-Flow Lube (Fleetguard LF3000)..... BD103 +	P. Fuel (23530706)..... BF5800 +	Fuel/Water Separator Box-Style (6N7617)..... BF912
Fuel/Water Separator (w/Drain) (Fleetguard FS1242)..... BF1249	S. Fuel (23530707)..... BF5810	Fuel/Water Separator Ele. (8N0205)..... PF316
Fuel/Water Separator (Open End for Bowl) (Fleetguard FS1242)..... BF1249-O	FLB w/Detroit Diesel Series 60 Eng.	Fuel/Water Separator Spin-on (256-8753)..... BF1259
Fuel/Water Separator (w/Drain & Sensor Port) (Fleetguard FS1242) BF1249-SP	Lube (23530573)..... [2] B495	P. Fuel Ele. (7W8910)..... CLN&R
Fuel/Water Separator (w/Drain & Sensor Port, High Efficiency Version) (Fleetguard FS1242)..... BF1393-SP	Fuel/Water Separator (23521528)..... PF7744	P. Fuel Ele. (9M2341)..... PF935
Fuel/Water Separator (Fleetguard FS1000)..... BF1259	P. Fuel (23518481)..... BF5800 +	P. Fuel Spin-on (1R1740)..... BF970 +
Fuel/Water Separator (Fleetguard FS1212)..... BF1212 +	S. Fuel (23530707)..... BF5810	S. Fuel (1R0750)..... BF7633 +
Radial Seal Air (Don. P531026)... RS3516	Axial Seal Air (Don. P142100).... PA2631	16 1/2 In. Std. Air (Don. P521055)..... PA1886
Radial Seal XP Air (Don. DBA5106)..... RS3516XP	Radial Seal Air (Don. P531026)... RS3516	16 1/2 In. XP Air (Don. P521055)..... PA1886XP
Air Dryer (AD-9 System) (Bendix 107796)..... BA5377	Radial Seal XP Air (Don. DBA5106)..... RS3516XP	22 9/16 In. Air (Don. P525493)..... PA2705
Coolant (w/o Chemical) (Fleetguard WF2077)..... B5134 +	Air Dryer (AD-9 System) (Bendix 107796)..... BA5377	Trans. Ele. (Allison 29538489)..... 19739 +
Coolant (w/Chemical) (Fleetguard WF2075)..... BW5075	Coolant (w/o Chemical) (Fleetguard WF2077)..... B5134 +	Trans. Spin-on (Allison 29510922)..... BT8316-MPG
Opt. Trans. (Fuller 17237)..... B2 +	Coolant (Controlled Release) (Nalcool NF2088)..... BW5200	Steering (Nelson 83284D)..... PT8487
Steering (Nelson 83213M)..... P528	Coolant (w/16 Units BTE) (Fleetguard WF2055)..... BW5140	FLC w/Cat 3406 Eng.
FLB w/Cummins N14 Eng. (Australia)	Trans. (Fuller 4304827)..... BT223	Lube (1R0716)..... B99 +
Dual-Flow Lube (3318853)..... BD103 +	Opt. Trans. (Fuller 17237)..... B2 +	Lube (High Efficiency) (1R1808).. B7299 +
Fuel/Water Separator (3329289). BF1259	Steering (Nelson 83213M)..... P528	Fuel/Water Separator Ele. (Fleetguard FS1029W)..... PF7680
Air Dryer (Bendix 107796)..... BA5377	Some Differential (Meritor 3280-V-8394)..... B233	Fuel/Water Separator Spin-on (256-8753)..... BF1259
Trans. (Fuller 4304827)..... BT223	FLC w/Cat 3126 (7.2L) Eng.	Fuel/Water Separator Spin-on (Fleetguard FS1212)..... BF1212 +
	Lube (Standard Vers.) (1R0739).. B76	P. Fuel Ele. (9M2342)..... PF935
	Fuel/Water Separator (175-2949)..... BF1268	P. Fuel Spin-on (4N5823)..... BF614 +

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
FLC w/Cat 3406 Eng. (Cont'd)	FLC w/Cat C12 Eng. (Cont'd)	FLC w/Cummins M11 Eng. (Cont'd)
P. Fuel Spin-on (High Efficiency) (1R0749).....	Air Dryer (AD-9 System) (Bendix 107796).....	Fuel/Water Separator Spin-on (w/Sensor Port) (Alliance ABPS3226FL01).....
22 9/16 In. Std. Air (Don. P525493).....	Coolant (Fleetguard WF2077).....	Fuel/Water Separator Ele. (Fleetguard FS1029W).....
23 In. Std. Air (Nelson 84831S).....	Opt. Trans. (Fuller 17237).....	Fuel/Water Separator Spin-on (3329289).....
Radial Seal Air (Standard) (Don. EAF5069).....	Steering (Nelson 87904A).....	Axial Seal Air (Don. P525493).....
Radial Seal XP Air (Upgrade) (Don. EAF5069).....	Steering (Nelson 83213M).....	Radial Seal Air (Standard) (Don. EAF5069).....
Air Dryer (AD-IP System) (Bendix 65624).....	FLC w/Cummins 6CT8.3 (8.3L) Eng.	Radial Seal XP Air (Upgrade) (Don. EAF5069).....
Air Dryer (AD-9 System) (Bendix 107796).....	F-F Lube (3313281).....	Air Dryer (AD-9 System) (Bendix 107796).....
Coolant (Fleetguard WF2077).....	Dual-Flow Lube (3318853).....	Coolant (Fleetguard WF2071).....
Opt. Trans. (Fuller 17237).....	Fuel/Water Separator (3925274).....	Opt. Trans. (Fuller 17237).....
Steering (Nelson 83213M).....	S. Fuel (3903640).....	Steering (Nelson 87904A).....
Steering (Nelson 87904A).....	Air (Don. P525493).....	Steering (Nelson 83213M).....
FLC w/Cat 3408 Eng.	FLC w/Cummins KT 1150 Eng.	FLC w/Cummins N14 Eng. (To 12/1995)
Lube (1R0716).....	F-F Lube (9 15/16 In.) (3313279).....	F-F Lube (9 15/16 In.) (Fleetguard LF670SC).....
P. Fuel Ele. (9M2342).....	F-F Lube (11 9/32 In.) (3313279).....	F-F Lube (11 9/32 In.) (Fleetguard LF670SC).....
P. Fuel Spin-on (4N5823).....	B-P Lube Ele. (256838).....	Dual-Flow Lube (3318853).....
P. Fuel Spin-on (High Efficiency) (1R0749).....	B-P Lube Spin-on (3313283).....	B-P Lube (3304232).....
FLC w/Cat C12 Eng.	Fuel/Water Separator (3308638).....	Fuel/Water Separator Ele. (Fleetguard FS1011).....
F-F Lube (1R0716).....	Fuel (156172).....	Fuel/Water Separator Spin-on (3308638).....
F-F Lube (High Efficiency) (1R1808).....	Air (Don. P525493).....	Fuel (154789).....
B-P Lube (1W8845).....	Air Dryer (AD-9 System) (Bendix 107796).....	Axial Seal Air (Don. P525493).....
Fuel/Water Separator Ele. (Fleetguard FS1011).....	Opt. Trans. (Fuller 17237).....	Radial Seal Air (Standard) (Don. EAF5069).....
Fuel/Water Separator Ele. (Davco 380 System) (23521528).....	Steering (Nelson 83213D).....	Radial Seal XP Air (Upgrade) (Don. EAF5069).....
Fuel/Water Separator Ele. (Davco 382 System) (Fleetguard FS1029W).....	FLC w/Cummins L10 Eng.	Cab Air (22-44665-000).....
Fuel/Water Separator Ele. (Davco 382) (Davco 382113).....	F-F Lube (9 15/16 In.) (Fleetguard LF670SC).....	Air Dryer (AD-9 System) (Bendix 107796).....
Fuel/Water Separator (Open End for Bowl) (1335673).....	F-F Lube (11 9/32 In.) (Fleetguard LF670SC).....	Coolant (Nalcool NF2088).....
Fuel/Water Separator (w/Drain) (1335673).....	Dual-Flow Lube (3318853).....	Opt. Trans. (Fuller 17237).....
Fuel/Water Separator (w/Sensor Port) (1335673).....	B-P Lube (3304232).....	Steering (Nelson 83213D).....
Fuel/Water Separator Spin-on (Fleetguard FS1212).....	Fuel/Water Separator (3308638).....	Steering (Nelson 83213M).....
Fuel/Water Separator Spin-on (256-8753).....	P. Fuel (154789).....	Steering (Nelson 87904A).....
Fuel (1R1712).....	Air (Don. P525493).....	FLC w/Cummins N14 Eng. (12/1995-on)
Fuel (High Efficiency) (1R0749).....	Air Dryer (AD-9 System) (Bendix 107796).....	F-F Lube (9 15/16 In.) (Fleetguard LF670SC).....
Axial Seal Air (Don. P525493).....	Opt. Trans. (Fuller 17237).....	F-F Lube (11 9/32 In.) (Fleetguard LF670SC).....
Radial Seal Air (Standard) (Don. EAF5069).....	Steering (Nelson 83284D).....	Dual-Flow Lube (3318853).....
Radial Seal XP Air (Upgrade) (Don. EAF5069).....	Differential (Fleetguard LF651).....	B-P Lube (3304232).....
Cab Air (2244665000).....	FLC w/Cummins LTA Eng.	Fuel/Water Separator Ele. (Fleetguard FS1011).....
Cab Air (91621).....	F-F Lube (Fleetguard LF670SC).....	Fuel/Water Separator Spin-on (3329289).....
Air Dryer (AD-IP System) (Bendix 65624).....	B-P Lube (3304232).....	Fuel (154789).....
	Fuel (154789).....	Axial Seal Air (Don. P525493).....
	Std. Air (Don. P521055).....	Radial Seal Air (Standard) (Don. EAF5069).....
	XP Air (Don. P521055).....	
	Opt. Trans. (Fuller 17237).....	
	Steering (Nelson 83284D).....	
	Differential (Fleetguard LF651).....	
	FLC w/Cummins LTA10 Eng.	
	Lube (Fleetguard LF3363).....	
	Air (Don. P151097).....	
	Coolant (Fleetguard WF2074).....	
	Opt. Trans. (Fuller 17237).....	
	Steering (Nelson 83213D).....	
	FLC w/Cummins M11 Eng.	
	Dual-Flow Lube (3318853).....	
	Fuel/Water Separator Spin-on (w/Drain) (Alliance ABPS3226FL01).....	
	Fuel/Water Separator Spin-on (Open End for Bowl) (Alliance ABPS3226FL01).....	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>	<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>	<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>
FLC w/Cummins N14 Eng. (12/1995-on) (Cont'd)	FLC w/Detroit Diesel 8V71 Eng. (Cont'd)	FLC w/Mercedes-Benz MBE4000 Eng. (Cont'd)
Radial Seal XP Air (Upgrade) (Don. EAF5069).....	S. Fuel Spin-on (23530645).....	Channel Flow Secondary Air (Don. P544432).....
RS3518XP	BF5815	PA4701
Cab Air (22-44665-000).....	Air (Don. P525493).....	Cab Air (91621).....
PA5319	PA2705	PA5773
Air Dryer (AD-9 System) (Bendix 107796).....	FLC w/Detroit Diesel 8V92 Eng.	Cab Air (36000006).....
BA5377	Lube (23530407).....	PA5359
Coolant (Nalcool NF2088).....	Lube (Upgrade) (23530408).....	Air Dryer (AD-IS System) (Bendix 5008414).....
BW5200	B95 +	BA5374 +
Opt. Trans. (Fuller 17237).....	P. Fuel (23530706).....	Air Dryer (AD-9 System) (Bendix 107796).....
B2 +	BF5800 +	BA5377
Steering (Nelson 83213D).....	S. Fuel (23530707).....	Trans. Ele. (2 In. Kit) (Allison 29540493).....
PT951	BF5810	PT9416-MPG KIT
Steering (Nelson 83213M).....	S. Fuel (23530645).....	Trans. Ele. (4 In. Kit) (Allison 29540494).....
P528	BF5815	PT9415-MPG KIT
Steering (Nelson 87904A).....	FLC w/Detroit Diesel Series 60 Eng.	Opt. Trans. Spin-on (Fuller 17237).....
PT9354-MPG	Lube.....	B2 +
FLC w/Cummins NTC Eng.	[2] B495	Steering (T1808D).....
Lube Ele. (158139).....	Fuel/Water Separator (Davco 380) (23514049).....	BT9388
P999-HD	PF7680	FLC w/Mercedes-Benz OM366 Eng.
F-F Lube Spin-on (9 15/16 In.) (3313279).....	Fuel/Water Separator (Davco 382) (23521528).....	Lube (Mann HU947/1N).....
B196 +	PF7744	P7305
F-F Lube Spin-on (11 9/32 In.) (3313279).....	Fuel/Water Separator (Davco 382) (Fleetguard FS19624).....	Fuel (Mann BFU700x).....
B96 +	PF7748	F834-F
Dual-Flow Lube Spin-on (3318853).....	P. Fuel (23518481).....	PA2705
BD103 +	BF5800 +	FLC112 w/Cat C10 (10.3L) Eng.
C750-E +	BF5810	F-F Lube (1R0716).....
B7577	PA2705	B99 +
Fuel/Water Separator (3308638). Fuel (154709).....	Axial Seal Air (Don. P153551).....	F-F Lube (High Efficiency) (1R1808).....
BF1212 +	PA2705	B7299 +
BF957 +	Radial Seal Air (Standard) (Don. P535717).....	B7577
PA2705	RS3518XP	B-P Lube (1W8845).....
PA3951	Cab Air (7 7/8 In.) (91595).....	BF614 +
BT359	PA5494	BF7587 +
PT951	Cab Air (8 5/8 In.) (22-46891-000).....	Std. Air (Don. P181041).....
FLC w/Cummins VT903 Eng.	PA5722	PA1886
Lube Ele. (158139).....	Cab Air (10 19/32 In.) (22-44665-000).....	PA1886XP
P999-HD	PA5319	FLD w/Cat 3126 (7.2L) Eng.
B196 +	Air Dryer (AD-9 System) (Bendix 107796).....	Lube (Standard Vers.) (1R0739).. Fuel/Water Separator (175-2949).....
B96 +	BA5377	B76
C750-E +	Air Dryer (AD-IS System) (Bendix 5008414).....	Fuel/Water Separator (256-8753).....
B7577	BA5374 +	BF1259
BF1212 +	BA5374 +	P. Fuel (1R0751).....
BF957-D +	Coolant (w/o Chemical) (Fleetguard WF2077).....	BF7632
FLC w/Detroit Diesel 6-71 Eng.	B5134 +	PA2705
Lube (23530407).....	Coolant (w/Chemical) (Nalcool NF2088).....	Disposable Air Hsg. (Farr C71338-2).....
B95 +	BW5200	PA2650
B95-MPG +	B2 +	FLD w/Cat 3176 (10.3L) Eng.
BF5800 +	PT9354-MPG	Lube.....
BF5810	P528	B99 +
BF5815	Steering Ele. (Nelson 83213M).... Steering Spin-on (T1808D).....	Fuel/Water Separator (Fleetguard FS1212).....
PA2705	BT9388	BF1212 +
FLC w/Detroit Diesel 6V92 Eng.	FLC w/Mercedes-Benz MBE4000 Eng.	P. Fuel Ele. (8H7204).....
Lube (23530407).....	Lube (A0001802109).....	[2] PF935
B95 +	P7230	BF614 +
B95-MPG +	Fuel/Water Separator (S3226FL02Y).....	BF7587 +
BF5800 +	BF1339-SP +	PA2715
BF5810	BF46083-O	PA2705
BF5815	Fuel/Water Separator (Open End for Bowl) (S3226FL02Y).....	BA5371
PA2705	BF9898-O	Air Dryer (Haldex DA33120).....
FLC w/Detroit Diesel 8V71 Eng.	PF7761	Air Dryer (AD-9 System) (Bendix 107796).....
F-F Lube (23530407).....	RS3518	BA5377
B95 +	RS3518XP	Coolant (w/o Chemical) (Fleetguard WF2077).....
B95-MPG +	Channel Flow Air (Don. P607965).....	B5134 +
PF845	CA5368 +	BW5140
BF5800 +	CA5419 +	Coolant (Controlled Release) (Nalcool NF2088).....
PF902	Channel Flow Air (w/Flame Retardant Media) (Don. P605960)	BW5200
BF5810	Opt. Trans. (Fuller 17237).....	B2 +

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>	<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>	<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>
FLD w/Cat 3176 (10.3L) Eng. (Cont'd)	FLD w/Cat C9 Eng.	FLD w/Cat C11 Eng. (To 1/2004) (Cont'd)
Steering (Nelson 83213M)..... P528	Lube (1R1808)..... B7299 +	Air (Don. P525493)..... PA2705
Differential (Meritor 3280-V-8394)..... B233	Fuel/Water Separator (Alliance ABPN122R50418)..... BF9898-O	Disposable Air Hsg. (Farr C71338-2)..... PA2650
FLD w/Cat 3306 Eng.	Fuel (1R0751)..... BF7632	FLD w/Cat C11 Eng. (1/2004-on)
Lube Ele. (5S0484)..... PT670	Radial Seal Air (Don. P537355)..... RS4646	Lube (1R1808)..... B7299 +
Lube Spin-on (1R0716)..... B99 +	Air Dryer (AD-9 System) (Bendix 107796)..... BA5377	Fuel/Water Separator (256-8753)..... BF1259
Lube Spin-on (Standard Vers.) (1R0739)..... B76	Air Dryer (AD-IS System) (Bendix 5008414)..... BA5374 +	P. Fuel (1R0712)..... BF614 +
Fuel/Water Separator Box-Style (6N7617)..... BF912	Coolant (Fleetguard WF2077)..... B5134 +	P. Fuel (High Efficiency) (1R0749)..... BF7587 +
Fuel/Water Separator Ele. (8N0205)..... PF316	Opt. Trans. (Fuller 17237)..... B2 +	P. Fuel (1R0762)..... BF7753
Fuel/Water Separator Spin-on (256-8753)..... BF1259	Steering (Nelson 87904M)..... PT9354-MPG	Air (Don. P525493)..... PA2705
P. Fuel Ele. (7W8910)..... CLN&R	Some Differential (Meritor 3280-V-8394)..... B233	Disposable Air Hsg. (Farr C71338-2)..... PA2650
P. Fuel Ele. (9M2341)..... PF935	FLD w/Cat C10 Eng.	Cab Air (Alliance ABPN10G91559)..... PA4857
P. Fuel Spin-on (1R1740)..... BF970 +	F-F Lube (1R0716)..... B99 +	FLD w/Cat C12 Eng.
S. Fuel (1R0750)..... BF7633 +	B-P Lube (1W8845)..... B7577	Lube..... B99 +
Air (Don. P525493)..... PA2705	Fuel/Water Separator Spin-on (w/Drain) (Alliance S3226FL01)..... BF1347	Fuel/Water Separator Ele. (Davco 380) (23521528)..... PF7744
Disposable Air Hsg. (Farr C71338-2)..... PA2650	Fuel/Water Separator Spin-on (Open End for Bowl) (Alliance S3226FL01)..... BF1347-O	Fuel/Water Separator Ele. (Davco 382) (Davco 382113)..... PF7748
FLD w/Cat 3406 (14.6L) Eng.	Fuel/Water Separator Spin-on (w/Sensor Port) (Alliance S3226FL01)..... BF1373-SP	Fuel/Water Separator Ele. (Davco 382) (Fleetguard FS1029W)..... PF7680
Lube (1R0716)..... B99 +	Fuel/Water Separator Ele. (Fleetguard FS1029W)..... PF7680	Fuel/Water Separator Spin-on (175-2949)..... BF1268
Fuel/Water Separator Ele. (Davco 382) (Fleetguard FS1029W)..... PF7680	Fuel/Water Separator Spin-on (175-2949)..... BF1268	Fuel/Water Separator Spin-on (Fleetguard FS1212)..... BF1212 +
Fuel/Water Separator Ele. (Racor 2020TMOR)..... PF7890-10	Fuel/Water Separator Spin-on (Fleetguard FS1212)..... BF1212 +	Fuel Spin-on..... BF614 +
Fuel/Water Separator Ele. (Racor 2020PMOR)..... PF7890-30	Fuel (1R0712)..... BF614 +	Fuel Spin-on (High Efficiency) (1R0749)..... BF7587 +
Fuel/Water Separator Spin-on (Fleetguard FS1212)..... BF1212 +	Fuel (1R0749)..... BF7587 +	Axial Seal Air (Don. P153551)..... PA2705
Fuel Spin-on..... BF7587 +	Axial Seal Air (Don. P153551)..... PA2705	Conical Air (Nelson 84831S)..... PA2703
Disposable Air Hsg. (Farr C713382)..... PA2650	Radial Seal Air (Standard) (Don. EAF5069)..... RS3518	Air Dryer (AD-IP System) (Bendix 65624)..... BA5373
Axial Seal Air (Don. P153551)..... PA2705	Radial Seal XP Air (Upgrade) (Don. EAF5069)..... RS3518XP	Air Dryer (AD-SP System) (Bendix 5008414)..... BA5374 +
Conical Air (Don. P141317)..... PA2703	Air Dryer (AD-IP System) (Bendix 65624)..... BA5373	Air Dryer (AD-9 System) (Bendix 107796)..... BA5377
Radial Seal Air (Don. P534816)..... [2] RS3539	Air Dryer (AD-9 System) (Bendix 107796)..... BA5377	Coolant (w/o Chemical) (Fleetguard WF2077)..... B5134 +
Radial Seal XP Air (Don. P534816)..... [2] RS3539XP	Coolant (Fleetguard WF2077)..... B5134 +	Coolant (w/Chemical) (Nalcool NF2088)..... BW5200
Air Dryer (AD-9 System) (Bendix 107796)..... BA5377	Opt. Trans. (Fuller 17237)..... B2 +	Opt. Trans. (Fuller 17237)..... B2 +
Air Dryer (AD-IP System) (Bendix 65624)..... BA5373	2 23/32 In. Steering (Nelson 87904A)..... PT9354-MPG	2 23/32 In. Steering (Nelson 87904M)..... PT9354-MPG
Coolant (w/Chemical) (Fleetguard WF2076)..... BW5076	4 3/16 In. Steering (Nelson 84148A)..... P528	4 3/16 In. Steering (Nelson 84148A)..... P528
Coolant (w/o Chemical) (Fleetguard WF2077)..... B5134 +	Some Differential (Meritor 3280-V-8394)..... B233	Differential (Meritor 3280-V-8394)..... B233
Opt. Trans. (Fuller 17237)..... B2 +	FLD w/Cat C11 Eng. (To 1/2004)	FLD w/Cat C13 Eng.
Trans. (Fuller 4304827)..... BT223	Lube (1R0716)..... B99 +	Lube (1R1808)..... B7299 +
4 1/16 In. Steering (Nelson 87972A)..... PT9386-MPG	Fuel/Water Separator (256-8753)..... BF1259	Fuel/Water Separator (Alliance ABPS3226FL02)..... BF1346 +
4 3/16 In. Steering (Nelson 83213M)..... P528	P. Fuel (1R0712)..... BF614 +	Fuel/Water Separator (Open End for Bowl) (Alliance ABPN122R50418)..... BF9898-O
Some Differential (Meritor 3280-V-8394)..... B233	P. Fuel (High Efficiency) (1R0749)..... BF7587 +	
	P. Fuel (1R0762)..... BF7753	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
FLD w/Cat C13 Eng. (Cont'd)	FLD w/Cat C15 Eng. (To 1/2004) (Cont'd)	FLD w/Cat C15 Eng. (1/2004-on) (Cont'd)
<b>Fuel</b> (1R0749)..... <b>BF7587 +</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>15 1/4 In. Radial Seal Air</b> (Standard) (Don. P535717)..... <b>RS3518</b>
<b>Conical Air</b> (Don. P522293)..... <b>PA2732</b>	<b>Air Dryer</b> (AD-SP System) (Bendix 109994)..... <b>BA5374 +</b>	<b>15 1/4 In. Radial Seal XP Air</b> (Upgrade) (Don. P535717)..... <b>RS3518XP</b>
<b>Radial Seal Air</b> (Don. P537355)... <b>[2] RS4646</b>	<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>	<b>23 13/16 In. Radial Seal Air</b> (Don. P534816)..... <b>[2] RS3539</b>
<b>Cab Air</b> (22-30530-000)..... <b>CLN&amp;R</b>	<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>	<b>23 13/16 In. Radial Seal XP Air</b> (Don. P534816)..... <b>[2] RS3539XP</b>
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Crankcase Breather</b> (296-8325).. <b>CV15008</b>	<b>24 27/32 In. Radial Seal Air</b> (Don. P537355)..... <b>[2] RS4646</b>
<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134 +</b>	<b>Cab Air</b> (Alliance ABPN10G91559)..... <b>PA4857</b>
<b>Coolant</b> (Fleetguard WF2077)..... <b>B5134 +</b>	<b>Coolant</b> (w/Chemical) (Nalcool NF2088)..... <b>BW5200</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
<b>Trans.</b> (Fuller 4304827)..... <b>BT223</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>
<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>
<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Air Dryer</b> (AD-SP System) (Bendix 109994)..... <b>BA5374 +</b>
<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>
FLD w/Cat C15 Eng. (To 1/2004)	<b>2 23/32 In. Steering Ele.</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>
<b>Lube</b> (1R0716)..... <b>B99 +</b>	<b>4 3/16 In. Steering Ele.</b> (Nelson 83213M)..... <b>P528</b>	<b>Crankcase Breather</b> (296-8325).. <b>CV15008</b>
<b>Fuel/Water Separator</b> (w/Drain) (ABPN122S3226FL01)..... <b>BF1347</b>	<b>Steering Spin-on</b> (T1808D)..... <b>BT9388</b>	<b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134 +</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (ABPN122S3226FL01).. <b>BF1347-O</b>	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Coolant</b> (w/Chemical) (Nalcool NF2088)..... <b>BW5200</b>
<b>Fuel/Water Separator</b> (w/Sensor Port) (ABPN122S3226FL01)..... <b>BF1373-SP</b>	FLD w/Cat C15 Eng. (1/2004-on)	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b>	<b>Lube</b> (1R1808)..... <b>B7299 +</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19763)..... <b>PF7928</b>	<b>Fuel/Water Separator</b> (w/Drain) (ABPN122S3226FL01)..... <b>BF1347</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
<b>Fuel/Water Separator Spin-on</b> (Alliance ABPN122R50423)..... <b>BF1370</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (ABPN122S3226FL01).. <b>BF1347-O</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>
<b>Fuel/Water Separator Spin-on</b> (Racor R50404)..... <b>BF1362</b>	<b>Fuel/Water Separator</b> (w/Sensor Port) (ABPN122S3226FL01)..... <b>BF1373-SP</b>	<b>2 23/32 In. Steering Ele.</b> (Nelson 87904M)..... <b>PT9354-MPG</b>
<b>Fuel/Water Separator Spin-on</b> (Alliance ABPN12232FRT02)..... <b>BF1376</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b>	<b>4 3/16 In. Steering Ele.</b> (Nelson 83213M)..... <b>P528</b>
<b>Fuel/Water Separator Spin-on</b> (175-2949)..... <b>BF1268</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19763)..... <b>PF7928</b>	<b>Steering Spin-on</b> (T1808D)..... <b>BT9388</b>
<b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1212)..... <b>BF1212 +</b>	<b>Fuel/Water Separator Spin-on</b> (Alliance ABPN122R50423)..... <b>BF1370</b>	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>
<b>Fuel/Water Separator Spin-on</b> (256-8753)..... <b>BF1259</b>	<b>Fuel/Water Separator Spin-on</b> (Racor R50404)..... <b>BF1362</b>	FLD w/Cat C16 Eng. (To 1/2004)
<b>Fuel</b> (1R0749)..... <b>BF7587 +</b>	<b>Fuel/Water Separator Spin-on</b> (Alliance ABPN12232FRT02)..... <b>BF1376</b>	<b>Lube</b> (1R0716)..... <b>B99 +</b>
<b>Axial Seal Air</b> (Don. P153551)..... <b>PA2705</b>	<b>Fuel/Water Separator Spin-on</b> (175-2949)..... <b>BF1268</b>	<b>Fuel/Water Separator</b> (256-8753)..... <b>BF1259</b>
<b>23 In. Conical Air</b> (Nelson 84831S)..... <b>PA2703</b>	<b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1212)..... <b>BF1212 +</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (1335673)..... <b>BF1395-O</b>
<b>29 In. Conical Air</b> (Don. P522293)..... <b>PA2732</b>	<b>Fuel/Water Separator Spin-on</b> (256-8753)..... <b>BF1259</b>	<b>Fuel/Water Separator</b> (w/Drain) (1335673)..... <b>BF1265</b>
<b>15 1/4 In. Radial Seal Air</b> (Standard) (Don. P535717)..... <b>RS3518</b>	<b>Fuel</b> (1R0749)..... <b>BF7587 +</b>	<b>Fuel/Water Separator</b> (w/Sensor Port) (1335673)..... <b>BF1395-SP</b>
<b>15 1/4 In. Radial Seal XP Air</b> (Upgrade) (Don. P535717)..... <b>RS3518XP</b>	<b>Axial Seal Air</b> (Don. P153551)..... <b>PA2705</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1212)..... <b>BF1212 +</b>
<b>23 13/16 In. Radial Seal Air</b> (Don. P534816)..... <b>[2] RS3539</b>	<b>23 In. Conical Air</b> (Nelson 84831S)..... <b>PA2703</b>	<b>Fuel Ele.</b> (9M-2342)..... <b>PF935</b>
<b>23 13/16 In. Radial Seal XP Air</b> (Don. P534816)..... <b>[2] RS3539XP</b>	<b>29 In. Conical Air</b> (Don. P522293)..... <b>PA2732</b>	<b>Fuel Spin-on</b> (1R0749)..... <b>BF7587 +</b>
<b>24 27/32 In. Radial Seal Air</b> (Don. P537355)..... <b>[2] RS4646</b>		<b>Axial Seal Air</b> (Don. P153551)..... <b>[2] PA2705</b>
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>		
<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>		


+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
FLD w/Cat C16 Eng. (To 1/2004) (Cont'd)	FLD w/Cummins 6BT5.9 (5.9L) Eng. (1994-97) (Cont'd)	FLD w/Cummins ISM Eng. (Cont'd)
Conical Air (Don. P154575)..... PA2715	Disposable Air Hsg. (Farr C71338-2)..... PA2650	Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... BD50000
Radial Seal Air (Don. P534816)... [2] RS3539		Dual-Flow Lube (14 7/32 In.) (Fleetguard LF9000)..... BD7153 +
Radial Seal XP Air (Don. P534816)..... [2] RS3539XP	FLD w/Cummins 6BT5.9 (5.9L) Eng. (1998-2001)	Fuel/Water Separator Ele. (Davco 382113)..... PF7748
Air Dryer (AD-9 System) (Bendix 107796)..... BA5377	Lube (Chrysler 5083285AA)..... BT7349	Fuel/Water Separator Ele. (Fleetguard FS1029W)..... PF7680
Coolant (w/o Chemical) (Fleetguard WF2077)..... B5134 +	Fuel/Water Separator (3925274)..... BF1280 +	Fuel/Water Separator Spin-on (3406889)..... BF1293-SPS
Coolant (w/8 Units BTE) (9N-6123)..... BW5139	S. Fuel (3903640)..... BF788	Fuel/Water Separator Spin-on (Fleetguard FS1000)..... BF1259
Trans. (Fuller 4304827)..... BT223	Air (Don. P525493)..... PA2705	22 1/2 In. Air (Don. P154575)..... PA2715
Steering (Nelson 83213M)..... P528	Disposable Air Hsg. (Farr C71338-2)..... PA2650	22 9/16 In. Air (Don. P153551)..... PA2705
Some Rear Axle (Meritor 3280-V-8394)..... B233	FLD w/Cummins 6CT8.3 (8.3L) Eng.	Radial Seal Air (Standard) (Don. EAF5069)..... RS3518
FLD w/Cat C16 Eng. (1/2004-on)	F-F Lube (3313281)..... B205 +	Radial Seal XP Air (Upgrade) (Don. EAF5069)..... RS3518XP
Lube (1R1808)..... B7299 +	Dual-Flow Lube (3318853)..... BD103 +	Air Dryer (AD-IP System) (Bendix 65624)..... BA5373
Fuel/Water Separator (256-8753)..... BF1259	Fuel/Water Separator (3925274)..... BF1280 +	Air Dryer (Wabco R950011)..... BA5374 +
Fuel/Water Separator (Open End for Bowl) (1335673)..... BF1395-O	S. Fuel (3903640)..... BF788	Air Dryer (AD-9 System) (Bendix 107796)..... BA5377
Fuel/Water Separator (w/Drain) (1335673)..... BF1265	Air (Don. P525493)..... PA2705	Coolant (w/o Chemical) (Fleetguard WF2077)..... B5134 +
Fuel/Water Separator (w/Sensor Port) (1335673)..... BF1395-SP	Disposable Air Hsg. (Farr C71338-2)..... PA2650	Coolant (w/Chemical) (Fleetguard WF2071)..... BW5071
Fuel/Water Separator (Fleetguard FS1212)..... BF1212 +	FLD w/Cummins C8.3 Eng.	Opt. Trans. (Fuller 17237)..... B2 +
Fuel Ele. (9M-2342)..... PF935	Dual-Flow Lube (3318853)..... BD103 +	Steering (2 23/32 In.) (Nelson 87904M)..... PT9354-MPG
Fuel Spin-on (1R0749)..... BF7587 +	FLD w/Cummins ISB (3.9L) Eng.	Steering (4 3/16 In.) (Nelson 83213M)..... P528
Axial Seal Air (Don. P153551)..... [2] PA2705	Lube (Fleetguard LF3970)..... B7177	FLD w/Cummins ISX 15.0 (14.9L) Eng.
Conical Air (Don. P154575)..... PA2715	Lube (4897898)..... BT7237	14 7/32 In. Dual-Flow Lube (Fleetguard LF9000)..... BD7153 +
Radial Seal Air (Don. P534816)... [2] RS3539	P. Fuel (Fleetguard FF5632)..... BF7940	Opt. 11 13/16 In. Dual-Flow Lube (Fleetguard LF14000NN)..... BD50000
Radial Seal XP Air (Don. P534816)..... [2] RS3539XP	Air (Don. P525493)..... PA2705	Fuel/Water Separator Ele. (Fleetguard FS1029W)..... PF7680
Cab Air (Alliance ABPN10G91559)..... PA4857	Disposable Air Hsg. (Farr C71338-2)..... PA2650	Fuel/Water Separator Spin-on (Fleetguard FS1007)..... BF1274-SP
Air Dryer (AD-9 System) (Bendix 107796)..... BA5377	FLD w/Cummins ISC Eng.	Axial Seal Air (Don. P153551)..... PA2705
Coolant (w/o Chemical) (Fleetguard WF2077)..... B5134 +	Dual-Flow Lube (Fleetguard LF9009)..... BD7309 +	Radial Seal Air (Nelson 870710A)..... RS4563
Coolant (w/8 Units BTE) (9N-6123)..... BW5139	Fuel (Fleetguard FF5488)..... BF7815	Radial Seal Air (Don. P534816)... [2] RS3539
Trans. (Fuller 4304827)..... BT223	Fuel (Fleetguard FF5636)..... BF7924	Radial Seal XP Air (Don. P534816)..... [2] RS3539XP
Steering (Nelson 83213M)..... P528	Air (Don. P525493)..... PA2705	Cab Air (Alliance ABPN10G91559)..... PA4857
Some Rear Axle (Meritor 3280-V-8394)..... B233	Disposable Air Hsg. (Farr C71338-2)..... PA2650	Cab Air (22-46891-000)..... PA5722
FLD w/Cummins 4BT3.9 (3.9L) Eng.	Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071	Air Dryer (AD-9 System) (Bendix 107796)..... BA5377
Lube (3903224)..... BT427 +	Opt. Trans. (Fuller 17237)..... B2 +	Air Dryer (Wabco R950011)..... BA5374 +
Fuel/Water Separator (3903202)..... BF1226	Steering (Nelson 84148A)..... P528	Coolant (Fleetguard WF2126)..... BW5086
Fuel (3903640)..... BF788	FLD w/Cummins ISL 8.9 (8.9L) Eng.	Opt. Trans. (Fuller 17237)..... B2 +
Air (Don. P525493)..... PA2705	Dual-Flow Lube (Fleetguard LF9009)..... BD7309 +	Trans. (Fuller 4304827)..... BT223
Disposable Air Hsg. (Farr C71338-2)..... PA2650	Fuel/Water Separator (Fleetguard FS1022)..... BF1272-SPS	
FLD w/Cummins 6BT5.9 (5.9L) Eng. (1994-97)	Fuel/Water Separator (Fleetguard FS1065)..... BF1378-SPS	
Lube (3914395)..... BT339 +	P. Fuel (Fleetguard FF5488)..... BF7815	
Fuel/Water Separator (3925274)..... BF1280 +	P. Fuel (Fleetguard FF5636)..... BF7924	
S. Fuel (3903640)..... BF788	Air (Don. P525493)..... PA2705	
Air (Don. P525493)..... PA2705	Disposable Air Hsg. (Farr C71338-2)..... PA2650	
	Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071	
	Opt. Trans. (Fuller 17237)..... B2 +	
	Steering (Nelson 84148A)..... P528	
	FLD w/Cummins ISM Eng.	
	Dual-Flow Lube (11 13/16 In.) (Fleetguard LF9001)..... BD7154 +	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
FLD w/Cummins ISX 15.0 (14.9L) Eng. (Cont'd)	FLD w/Cummins M11 Eng. (Cont'd)	FLD w/Cummins N14 Eng. (12/1995-on)
2 23/32 In. Steering (Nelson 87904M).....	Air Dryer (AD-IP System) (Bendix 65624).....	(Cont'd)
PT9354-MPG	BA5373	Coolant (w/4 Units BTA+) (3315116).....
4 1/16 In. Steering (Nelson 87972A).....	Air Dryer (AD-9 System) (Bendix 107796).....	BW5071
PT9386-MPG	BA5377	Coolant (w/23 Units BTA+) (Fleetguard WF2076).....
4 3/16 In. Steering (Nelson 83213M).....	Coolant (w/4 Units BTA+) (Fleetguard WF2071).....	BW5076
P528	BW5071	Opt. Trans. (Fuller 17237).....
Some Differential (Meritor 3280-V-8394).....	Coolant (w/15 Units BTA+) (Fleetguard WF2075).....	B2+
B233	BW5075	Steering (Nelson 83213M).....
FLD w/Cummins KT 1150 Eng.	Opt. Trans. (Fuller 17237).....	P528
F-F Lube (9 15/16 In.) (3313279).....	Steering (Nelson 83213M).....	B2+
B196+	P528	FLD w/Cummins NTC Eng.
F-F Lube (11 9/32 In.) (3313279).....	FLD w/Cummins N14 Eng. (To 12/1995)	F-F Lube (9 15/16 In.) (3313279).....
B96+	F-F Lube (9 15/16 In.) (Fleetguard LF670SC).....	B196+
B-P Lube Ele. (256838).....	B196+	F-F Lube (11 9/32 In.) (3313279).....
C750-E+	F-F Lube (11 9/32 In.) (Fleetguard LF670SC).....	B96+
B-P Lube Spin-on (3313283).....	B96+	Dual-Flow Lube (3318853).....
BF1212+	Dual-Flow Lube (3318853).....	BD103+
Fuel/Water Separator (3308638).....	BD103+	B-P Lube Ele. (256838).....
BF957-D+	B-P Lube (3304232).....	C750-E+
Fuel (156172).....	B7577	B-P Lube Spin-on (3313283).....
BF957-D+	Fuel/Water Separator Ele. (Fleetguard FS1029W).....	B7577
Air (Don. P525493).....	PF7680	Fuel/Water Separator Ele. (Racor 2020PMOR).....
PA2705	Fuel/Water Separator Spin-on (3308638).....	PF7890-30
Disposable Air Hsg. (Farr C71338-2).....	BF1212+	Fuel/Water Separator Spin-on (3308638).....
PA2650	Fuel (154789).....	BF1212+
FLD w/Cummins L10 Eng.	BF957-D+	Fuel (154709).....
F-F Lube (9 15/16 In.) (Fleetguard LF670SC).....	PA2705	BF957+
B196+	Disposable Air Hsg. (Farr C71338-2).....	PA2705
F-F Lube (11 9/32 In.) (Fleetguard LF670SC).....	PA2650	Disposable Air Hsg. (Farr C71338-2).....
B96+	Radial Seal Air (Don. P534816).....	PA2650
Dual-Flow Lube (3318853).....	[2] RS3539	Opt. Trans. (Fuller 17237).....
BD103+	Radial Seal XP Air (Don. P534816).....	B2+
B-P Lube (3304232).....	[2] RS3539XP	Steering (Nelson 83213D).....
B7577	Air Dryer (AD-9 System) (Bendix 107796).....	PT951
Fuel/Water Separator Ele. (Racor 2020TMOR).....	BA5377	FLD w/Cummins Signature 600 (15.0L) Eng.
PF7890-10	Coolant (w/4 Units BTA+) (3315116).....	14 7/32 In. Dual-Flow Lube (Fleetguard LF9000).....
Fuel/Water Separator Ele. (Racor 2020PMOR).....	BW5071	BD7153+
PF7890-30	Coolant (w/23 Units BTA+) (Fleetguard WF2076).....	Opt. 11 13/16 In. Dual-Flow Lube (Fleetguard LF14000NN).....
Fuel/Water Separator Spin-on (3308638).....	BW5076	BD7154+
BF1212+	Opt. Trans. (Fuller 17237).....	Dual-Flow Lube (Upgrade) (Fleetguard FS1029W).....
Fuel (154789).....	B2+	PF7680
BF957-D+	Steering (Nelson 83213M).....	Fuel/Water Separator Spin-on (Fleetguard FS1007).....
Air (Don. P525493).....	P528	BF1274-SP
PA2705	Some Differential (Meritor 3280-V-8394).....	Axial Seal Air (Don. P153551).....
Disposable Air Hsg. (Farr C71338-2).....	B233	PA2705
PA2650	FLD w/Cummins N14 Eng. (12/1995-on)	Radial Seal Air (Nelson 870710A).....
Air Dryer (AD-9 System) (Bendix 107796).....	F-F Lube (9 15/16 In.) (Fleetguard LF670SC).....	RS4563
BA5377	B196+	Radial Seal Air (Don. P534816).....
Coolant (w/o Chemical) (Fleetguard WF2077).....	F-F Lube (11 9/32 In.) (Fleetguard LF670SC).....	[2] RS3539
B5134+	B96+	Radial Seal XP Air (Don. P534816).....
Coolant (w/12 Units BTA+) (Luberfiner LFW4075).....	Dual-Flow Lube (3318853).....	[2] RS3539XP
BW5075	BD103+	Cab Air (22-46891-000).....
Coolant (Controlled Release w/12 Units BTE) (Nalcool NF2088).....	B7577	PA5722
BW5200	Fuel/Water Separator Ele. (Fleetguard FS1029W).....	Air Dryer (AD-9 System) (Bendix 107796).....
Opt. Trans. (Fuller 17237).....	PF7680	BA5377
B2+	Fuel/Water Separator Spin-on (3329289).....	BA5374+
Steering (Nelson 83213M).....	BF1259	Coolant (Fleetguard WF2126).....
P528	Fuel (154789).....	BW5086
FLD w/Cummins M11 Eng.	BF957-D+	Opt. Trans. (Fuller 17237).....
Dual-Flow Lube (3318853).....	PA2705	B2+
BD103+	Disposable Air Hsg. (Farr C71338-2).....	Trans. (Fuller 4304827).....
Dual-Flow Lube (3401544).....	PA2650	BT223
BD7309+	Radial Seal Air (Don. P534816).....	2 23/32 In. Steering (Nelson 87904M).....
Lube (Upgrade) (3401544).....	[2] RS3539	PT9354-MPG
B40142+	Radial Seal XP Air (Don. P534816).....	4 1/16 In. Steering (Nelson 87972A).....
Fuel/Water Separator Ele. (Davco 380087).....	[2] RS3539XP	PT9386-MPG
PF7680	Air Dryer (AD-9 System) (Bendix 107796).....	4 3/16 In. Steering (Nelson 83213M).....
Fuel/Water Separator Ele. (Racor 2020PMOR).....	BA5377	P528
PF7890-30	FLD w/Cummins N14 Eng. (12/1995-on)	Some Differential (Meritor 3280-V-8394).....
Fuel/Water Separator Spin-on (Fleetguard FS1000).....	F-F Lube (9 15/16 In.) (Fleetguard LF670SC).....	B233
BF1259	B196+	
Fuel/Water Separator Spin-on (3308638).....	F-F Lube (11 9/32 In.) (Fleetguard LF670SC).....	
BF1212+	B96+	
Air (Don. P153551).....	Dual-Flow Lube (3318853).....	
PA2705	BD103+	
	B7577	
	Fuel/Water Separator Ele. (Fleetguard FS1029W).....	
	PF7680	
	Fuel/Water Separator Spin-on (3329289).....	
	BF1259	
	Fuel (154789).....	
	BF957-D+	
	PA2705	
	Air (Don. P525493).....	
	PA2650	
	Radial Seal Air (Don. P534816).....	
	[2] RS3539	
	Radial Seal XP Air (Don. P534816).....	
	[2] RS3539XP	
	Air Dryer (AD-9 System) (Bendix 107796).....	
	BA5377	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

**Trucks & Buses Applications** **BALDWIN FILTERS**

<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>	<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>	<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>
FLD w/Cummins VT903 Eng. F-F Lube Ele. (158139)..... <b>P999-HD</b> F-F Lube Spin-on (9 15/16 In.) (3313279)..... <b>B196 +</b> F-F Lube Spin-on (11 9/32 In.) (3313279)..... <b>B96 +</b> B-P Lube Ele. (256838)..... <b>C750-E +</b> B-P Lube Spin-on (3313283)..... <b>B7577</b> Fuel/Water Separator (3308638)..... <b>BF1212 +</b> Fuel (156172)..... <b>BF957-D +</b> Air (Don. P525493)..... <b>PA2705</b> Disposable Air Hsg. (Farr C71338-2)..... <b>PA2650</b>	FLD w/Detroit Diesel Series 50 Eng. (1994-on) (Cont'd) Fuel/Water Separator (w/Drain) (23535985)..... <b>BF5813 +</b> Fuel/Water Separator (Open End for Bowl) (23535985)..... <b>BF5813-O +</b> P. Fuel (23530706)..... <b>BF5800 +</b> S. Fuel (23530707)..... <b>BF5810</b> Air (Don. P525493)..... <b>PA2705</b> Disposable Air Hsg. (Farr C71338-2)..... <b>PA2650</b>	FLD w/Detroit Diesel Series 60 Eng. (To 12/2003) (Cont'd) Air Dryer (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> Air Dryer (Haldex DA33120)..... <b>BA5371</b> Air Dryer (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b> Air Dryer (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b> Coolant (w/o Chemical) (Fleetguard WF2077)..... <b>B5134 +</b> Coolant (w/Chemical) (Nalcool NF2088)..... <b>BW5200</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> 2 23/32 In. Steering Ele. (Nelson 87904M)..... <b>PT9354-MPG</b> 4 3/16 In. Steering Ele. (Nelson 84148A)..... <b>P528</b> Steering Spin-on (T1808D)..... <b>BT9388</b> Some Differential (Meritor 3280-V-8394)..... <b>B233</b>
FLD w/Detroit Diesel 6V92 Eng. Lube (23530407)..... <b>B95 +</b> Lube (Upgrade) (23530408)..... <b>B95-MPG +</b> P. Fuel (23530706)..... <b>BF5800 +</b> S. Fuel (23530707)..... <b>BF5810</b> S. Fuel (Upgrade) (23530645)..... <b>BF5815</b> Air (Don. P525493)..... <b>PA2705</b> Disposable Air Hsg. (Farr C71338-2)..... <b>PA2650</b>	FLD w/Detroit Diesel Series 55 Eng. Lube (23550401)..... <b>B7135</b> S. Fuel (23530707)..... <b>BF5810</b> Air (Don. P153551)..... <b>PA2705</b> Disposable Air Hsg. (Farr C71338-2)..... <b>PA2650</b> Air Dryer (AD-SP System) (Bendix 109994)..... <b>BA5374 +</b> Coolant (Nalcool NF2088)..... <b>BW5200</b> Steering (Nelson 83213M)..... <b>P528</b>	FLD w/Detroit Diesel Series 60 Eng. (To 12/2003) Lube (23518480)..... <b>[2] B495</b> Fuel/Water Separator Ele. (23521528)..... <b>PF7744</b> Fuel/Water Separator Ele. (Fleetguard FS19763)..... <b>PF7928</b> Fuel/Water Separator Ele. (Fleetguard FS19624)..... <b>PF7748</b> Fuel/Water Separator Ele. (Fleetguard FS1005)..... <b>PF7680</b> Fuel/Water Separator Spin-on (Alliance ABP/N122-R50422)..... <b>BF1375</b> Fuel/Water Separator Spin-on (Racor R50407)..... <b>BF1283-SP +</b> P. Fuel..... <b>BF5800 +</b> Some S. Fuel (23530645)..... <b>BF5815</b> Conical Air (Don. P522293)..... <b>PA2732</b> Axial Seal Air (Don. P153551)..... <b>PA2705</b>
FLD w/Detroit Diesel 8V71 Eng. Lube (23530407)..... <b>B95 +</b> Lube (Upgrade) (23530408)..... <b>B95-MPG +</b> P. Fuel (23530706)..... <b>BF5800 +</b> S. Fuel (23530707)..... <b>BF5810</b> S. Fuel (Upgrade) (23530645)..... <b>BF5815</b> Air (Don. P525493)..... <b>PA2705</b> Disposable Air Hsg. (Farr C71338-2)..... <b>PA2650</b>	FLD w/Detroit Diesel Series 60 Eng. (To 12/2003) 15 1/4 In. Radial Seal Air (Standard) (Don. P527682)..... <b>RS3518</b> 15 1/4 In. Radial Seal XP Air (Upgrade) (Don. P527682)..... <b>RS3518XP</b> 19 3/8 In. Radial Seal Air (Vortex VF120W)..... <b>[2] RS3730</b> 23 23/32 In. Radial Seal Air (Don. P534816)..... <b>[2] RS3539</b> 23 23/32 In. Radial Seal XP Air (Don. P534816)..... <b>[2] RS3539XP</b> 24 27/32 In. Radial Seal Air (Don. P537355)..... <b>[2] RS4646</b> Conical Radial Seal Air (Nelson 870710A)..... <b>[2] RS4563</b> Cab Air (91621)..... <b>PA5773</b> Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b> Air Dryer (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	FLD w/Detroit Diesel Series 60 Eng. (12/2003-12/2006) Lube (23518480)..... <b>[2] B495</b> Fuel/Water Separator Ele. (23521528)..... <b>PF7744</b> Fuel/Water Separator Ele. (Fleetguard FS19763)..... <b>PF7928</b> Fuel/Water Separator Ele. (Fleetguard FS19624)..... <b>PF7748</b> Fuel/Water Separator Ele. (Fleetguard FS1005)..... <b>PF7680</b> Fuel/Water Separator Spin-on (Alliance ABP/N122-R50422)..... <b>BF1375</b> Fuel/Water Separator Spin-on (Racor R50407)..... <b>BF1283-SP +</b> P. Fuel..... <b>BF5800 +</b> S. Fuel (23533726)..... <b>BF5816</b> Some S. Fuel (23530645)..... <b>BF5815</b> Conical Air (Don. P522293)..... <b>PA2732</b> Axial Seal Air (Don. P153551)..... <b>PA2705</b> 15 1/4 In. Radial Seal Air (Standard) (Don. P527682)..... <b>RS3518</b> 15 1/4 In. Radial Seal XP Air (Upgrade) (Don. P527682)..... <b>RS3518XP</b> 19 3/8 In. Radial Seal Air (Vortex VF120W)..... <b>[2] RS3730</b> 23 23/32 In. Radial Seal Air (Don. P534816)..... <b>[2] RS3539</b> 23 23/32 In. Radial Seal XP Air (Don. P534816)..... <b>[2] RS3539XP</b> 24 27/32 In. Radial Seal Air (Don. P537355)..... <b>[2] RS4646</b>
FLD w/Detroit Diesel 8V92 Eng. Lube (23530407)..... <b>B95 +</b> Lube (Upgrade) (23530408)..... <b>B95-MPG +</b> P. Fuel (23530706)..... <b>BF5800 +</b> S. Fuel (23530707)..... <b>BF5810</b> S. Fuel (Upgrade) (23530645)..... <b>BF5815</b> Air (Don. P525493)..... <b>PA2705</b> Disposable Air Hsg. (Farr C71338-2)..... <b>PA2650</b>	FLD w/Detroit Diesel Series 50 Eng. (To 1993) Lube (23530407)..... <b>[2] B95 +</b> Fuel/Water Separator (23516189)..... <b>BF5812</b> Fuel/Water Separator (w/Drain) (23535985)..... <b>BF5813 +</b> Fuel/Water Separator (Open End for Bowl) (23535985)..... <b>BF5813-O +</b> P. Fuel (23530706)..... <b>BF5800 +</b> S. Fuel (23530707)..... <b>BF5810</b> Air (Don. P525493)..... <b>PA2705</b> Disposable Air Hsg. (Farr C71338-2)..... <b>PA2650</b>	FLD w/Detroit Diesel Series 60 Eng. (12/2003-12/2006) 15 1/4 In. Radial Seal Air (Standard) (Don. P527682)..... <b>RS3518</b> 15 1/4 In. Radial Seal XP Air (Upgrade) (Don. P527682)..... <b>RS3518XP</b> 19 3/8 In. Radial Seal Air (Vortex VF120W)..... <b>[2] RS3730</b> 23 23/32 In. Radial Seal Air (Don. P534816)..... <b>[2] RS3539</b> 23 23/32 In. Radial Seal XP Air (Don. P534816)..... <b>[2] RS3539XP</b> 24 27/32 In. Radial Seal Air (Don. P537355)..... <b>[2] RS4646</b>
FLD w/Detroit Diesel Series 50 Eng. (1994-on) Lube (23530573)..... <b>[2] B495</b> Fuel/Water Separator (23516189)..... <b>BF5812</b>	FLD w/Detroit Diesel Series 50 Eng. (1994-on) Lube (23530573)..... <b>[2] B495</b> Fuel/Water Separator (23516189)..... <b>BF5812</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
FLD w/Detroit Diesel Series 60 Eng. (12/2003-12/2006) (Cont'd)	FLD w/Detroit Diesel Series 60 Eng. (12/2006-on) (Cont'd)	FLD w/Mercedes-Benz MBE900 Eng. (Cont'd)
<b>Conical Radial Seal Air</b> (Nelson 870710A)..... [2] <b>RS4563</b>	<b>15 1/4 In. Radial Seal XP Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>
<b>Cab Air</b> (Alliance ABPN10G91559)..... <b>PA4857</b>	<b>19 3/8 In. Radial Seal Air</b> (Vortex VF120W)..... [2] <b>RS3730</b>	<b>Trans.</b> (Fuller 4304827)..... <b>BT223</b>
<b>Cab Air</b> (91621)..... <b>PA5773</b>	<b>23 23/32 In. Radial Seal Air</b> (Don. P534816)..... [2] <b>RS3539</b>	<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>23 23/32 In. Radial Seal XP Air</b> (Don. P534816)..... [2] <b>RS3539XP</b>	<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>
<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>24 27/32 In. Radial Seal Air</b> (Don. P537355)..... [2] <b>RS4646</b>	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>
<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Conical Radial Seal Air</b> (Nelson 870710A)..... [2] <b>RS4563</b>	FLD w/Mercedes-Benz MBE904 Eng.
<b>Air Dryer</b> (Haldex DA33120)..... <b>BA5371</b>	<b>Cab Air</b> (91621)..... <b>PA5773</b>	<b>Lube</b> (1801609)..... <b>P7199</b>
<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Lube</b> (A0001801709)..... <b>P7188</b>
<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Opt. B-P Lube</b> (A9061810086).... <b>BC7326 +</b>
<b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134 +</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Fuel</b> (A0000901551)..... <b>PF7735</b>
<b>Coolant</b> (w/Chemical) (Nalcool NF2088)..... <b>BW5200</b>	<b>Air Dryer</b> (Haldex DA33120)..... <b>BA5371</b>	<b>Fuel</b> (A5410920805)..... <b>PF7761</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>	<b>Air</b> (Don. P525493)..... <b>PA2705</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>	<b>Disposable Air Hsg.</b> (Farr C71338-2)..... <b>PA2650</b>
<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134 +</b>	FLD w/Mercedes-Benz MBE4000 Eng.
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Coolant</b> (w/Chemical) (Nalcool NF2088)..... <b>BW5200</b>	<b>Lube</b> (1802109)..... <b>P7230</b>
<b>2 23/32 In. Steering Ele.</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19624)..... <b>PF7748</b>
<b>4 3/16 In. Steering Ele.</b> (Nelson 84148A)..... <b>P528</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Fuel/Water Separator Spin-on</b> (Racor BR90FRT30)..... <b>BF46016-O</b>
<b>Steering Spin-on</b> (T1808D)..... <b>BT9388</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Alliance ABPN122-R50418)..... <b>BF9898-O</b>
<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Fuel</b> (5410900151)..... <b>PF7761</b>
FLD w/Detroit Diesel Series 60 Eng. (12/2006-on)	<b>2 23/32 In. Steering Ele.</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>Axial Seal Air</b> (Don. P153551).... <b>PA2705</b>
<b>Lube</b> (23518480)..... [2] <b>B495</b>	<b>4 3/16 In. Steering Ele.</b> (Nelson 84148A)..... <b>P528</b>	<b>Conical Air</b> (Fleetguard AF4588M)..... <b>PA2732</b>
<b>Fuel/Water Separator Ele.</b> (23521528)..... <b>PF7744</b>	<b>Steering Spin-on</b> (T1808D)..... <b>BT9388</b>	<b>15 1/4 In. Radial Seal Air</b> (Standard) (Don. P527682)..... <b>RS3518</b>
<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19763)..... <b>PF7928</b>	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>15 1/4 In. Radial Seal XP Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b>
<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19624)..... <b>PF7748</b>	FLD w/Mercedes-Benz MBE900 Eng.	<b>24 27/32 In. Radial Seal Air</b> (Don. P537355)..... [2] <b>RS4646</b>
<b>Fuel/Water Separator Ele.</b> (Fleetguard FS1005)..... <b>PF7680</b>	<b>F-F Lube Ele.</b> (1801709)..... <b>P7188</b>	<b>Cab Air</b> (Alliance ABPN10G91559)..... <b>PA4857</b>
<b>Fuel/Water Separator Spin-on</b> (Alliance ABP/N122-R50422)..... <b>BF1375</b>	<b>F-F Lube Ele.</b> (A0001802909)..... <b>P7230</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
<b>Fuel/Water Separator Spin-on</b> (Racor R50407)..... <b>BF1283-SP +</b>	<b>Opt. B-P Lube Spinner</b> (A9061810086)..... <b>BC7326 +</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>
<b>P. Fuel</b> ..... <b>BF5800 +</b>	<b>Fuel/Water Separator</b> (w/o SP) (Alliance ABPS3226FL02)..... <b>BF1346 +</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>
<b>S. Fuel</b> (23533726)..... <b>BF5816</b>	<b>Fuel/Water Separator</b> (w/SP) (Alliance ABPS3226FL02)..... <b>BF1346-SP +</b>	<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>
<b>Some S. Fuel</b> (23530645)..... <b>BF5815</b>	<b>Fuel</b> (901551)..... <b>PF7735</b>	<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>
<b>Conical Air</b> (Don. P522293)..... <b>PA2732</b>	<b>Fuel</b> (A5410900151)..... <b>PF7761</b>	<b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134 +</b>
<b>Axial Seal Air</b> (Don. P153551).... <b>PA2705</b>	<b>Radial Seal Air</b> (Don. P537355) [2] <b>RS4646</b>	<b>Coolant</b> (w/Chemical) (Nalcool NF3000)..... <b>BW5137</b>
<b>15 1/4 In. Radial Seal Air</b> (Standard) (Don. P527682)..... <b>RS3518</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
		<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
		<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>
		<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>	<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>	<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>
FLD w/Mercedes-Benz MBE4000 Eng. (Cont'd)	FLL w/Cat 3126B Eng.	FLL w/Cummins L10 Eng.
Steering Ele. (Open Both Ends) (Nelson 84365A)..... <b>PT951</b>	Lube (Standard Vers.) (1R0739).. <b>B76</b>	F-F Lube (9 15/16 In.) (Fleetguard LF670SC)..... <b>B196 +</b>
Steering Ele. (Open one end) (Nelson 87904M)..... <b>PT9354-MPG</b>	Fuel/Water Separator (175-2949)..... <b>BF1268</b>	F-F Lube (11 9/32 In.) (Fleetguard LF670SC)..... <b>B96 +</b>
Steering Spin-on (T1808D)..... <b>BT9388</b>	Fuel/Water Separator (256-8753)..... <b>BF1259</b>	Dual-Flow Lube (3318853)..... <b>BD103 +</b>
Some Differential (Meritor 3280-V-8394)..... <b>B233</b>	Fuel (1R0751)..... <b>BF7632</b>	B-P Lube (3304232)..... <b>B7577</b>
FLD w/Mercedes-Benz OM366 Eng.	Air (w/Lid) (Don. P181099)..... <b>PA2333</b>	Fuel/Water Separator (3308638)..... <b>BF1212 +</b>
Lube (Mann HU947/1N)..... <b>P7305</b>	Conical Air (25 In.) (Don. P530866)..... <b>PA2631</b>	P. Fuel (154789)..... <b>BF957-D +</b>
Fuel (Mann BFU700X)..... <b>F834-F</b>	Conical Air (29 In.) (Don. P185024)..... <b>PA3951</b>	Air (w/Lid) (Don. P181099)..... <b>PA2333</b>
Air (Don. P525493)..... <b>PA2705</b>	FLL w/Cat 3176 Eng.	Conical Air (25 In.) (Don. P530866)..... <b>PA2631</b>
Disposable Air Hsg. (Farr C71338-2)..... <b>PA2650</b>	F-F Lube (1R0716)..... <b>B99 +</b>	Conical Air (29 In.) (Don. P185024)..... <b>PA3951</b>
FLD w/Mercedes-Benz OM447 Eng.	F-F Lube (High Efficiency) (1R1808)..... <b>B7299 +</b>	FLL w/Cummins M11 Eng.
Air (Don. P525493)..... <b>PA2705</b>	F-F Lube (1R0713)..... <b>BT230 +</b>	Dual-Flow Lube (3318853)..... <b>BD103 +</b>
Disposable Air Hsg. (Farr C71338-2)..... <b>PA2650</b>	Opt. B-P Lube (1W8845)..... <b>B7577</b>	Fuel/Water Separator Ele. (Fleetguard FS1029W)..... <b>PF7680</b>
FLD w/Mercedes-Benz OM906 Eng.	Fuel/Water Separator (256-8753)..... <b>BF1259</b>	Fuel/Water Separator Spin-on (3329289)..... <b>BF1259</b>
Lube (A0001801609)..... <b>P7199</b>	P. Fuel (1R1740)..... <b>BF970 +</b>	Air (w/Lid) (Don. P181099)..... <b>PA2333</b>
Fuel (A9060920305)..... <b>PF7735</b>	S. Fuel (1R0750)..... <b>BF7633 +</b>	Conical Air (25 In.) (Don. P530866)..... <b>PA2631</b>
Air (Don. P525493)..... <b>PA2705</b>	Air (w/Lid) (Don. P181099)..... <b>PA2333</b>	Conical Air (29 In.) (Don. P185024)..... <b>PA3951</b>
Disposable Air Hsg. (Farr C71338-2)..... <b>PA2650</b>	Conical Air (25 In.) (Don. P530866)..... <b>PA2631</b>	FLL w/Cummins N14 Eng.
FLL w/Cat C10 Eng.	Conical Air (29 In.) (Don. P185024)..... <b>PA3951</b>	F-F Lube (9 15/16 In.) (Fleetguard LF670SC)..... <b>B196 +</b>
F-F Lube (1R0716)..... <b>B99 +</b>	FLL w/Cat 3306 Eng.	F-F Lube (11 9/32 In.) (Fleetguard LF670SC)..... <b>B96 +</b>
F-F Lube (High Efficiency) (1R1808)..... <b>B7299 +</b>	Lube Ele. (5S0484)..... <b>PT670</b>	Dual-Flow Lube (3318853)..... <b>BD103 +</b>
B-P Lube (1W8845)..... <b>B7577</b>	Lube Spin-on (1R0716)..... <b>B99 +</b>	B-P Lube (3304232)..... <b>B7577</b>
B-P Lube (1W8845)..... <b>B7577</b>	Lube Spin-on (Standard Vers.) (1R0739)..... <b>B76</b>	Fuel/Water Separator (To 12/1995) (3308638)..... <b>BF1212 +</b>
P. Fuel Ele. (9M2342)..... <b>PF935</b>	Fuel/Water Separator (256-8753)..... <b>BF1259</b>	Fuel/Water Separator (12/1995-on) (3329289)..... <b>BF1259</b>
P. Fuel Spin-on (1R1712)..... <b>BF614 +</b>	P. Fuel (1R1740)..... <b>BF970 +</b>	Fuel (154789)..... <b>BF957-D +</b>
P. Fuel Spin-on (High Efficiency) (1R0749)..... <b>BF7587 +</b>	S. Fuel (1R0750)..... <b>BF7633 +</b>	Air (w/Lid) (Don. P181099)..... <b>PA2333</b>
Air (w/Lid) (Don. P181099)..... <b>PA2333</b>	Air (w/Lid) (Don. P181099)..... <b>PA2333</b>	Conical Air (25 In.) (Don. P530866)..... <b>PA2631</b>
Conical Air (25 In.) (Don. P530866)..... <b>PA2631</b>	Conical Air (25 In.) (Don. P530866)..... <b>PA2631</b>	Conical Air (29 In.) (Don. P185024)..... <b>PA3951</b>
Conical Air (29 In.) (Don. P185024)..... <b>PA3951</b>	Conical Air (29 In.) (Don. P185024)..... <b>PA3951</b>	FLL w/Cummins 6B Series Eng.
FLL w/Cat C12 Eng.	FLL w/Cat 3406 Eng.	Lube (To 1998) (3914395)..... <b>BT339 +</b>
F-F Lube (1R0716)..... <b>B99 +</b>	Lube (1R0716)..... <b>B99 +</b>	Lube (1998-on) (Chrysler 5083285AA)..... <b>BT7349</b>
F-F Lube (High Efficiency) (1R1808)..... <b>B7299 +</b>	Lube (High Efficiency) (1R1808).. <b>B7299 +</b>	Fuel/Water Separator (3925274)..... <b>BF1280 +</b>
B-P Lube (1W8845)..... <b>B7577</b>	Fuel/Water Separator (256-8753)..... <b>BF1259</b>	S. Fuel (3903640)..... <b>BF788</b>
Fuel/Water Separator (Open End for Bowl) (1335673)..... <b>BF1395-O</b>	P. Fuel Ele. (9M2342)..... <b>PF935</b>	Air (w/Lid) (Don. P181099)..... <b>PA2333</b>
Fuel/Water Separator (w/Drain) (1335673)..... <b>BF1265</b>	P. Fuel Spin-on (4N5823)..... <b>BF614 +</b>	Conical Air (25 In.) (Don. P530866)..... <b>PA2631</b>
Fuel/Water Separator (w/Sensor Port) (1335673)..... <b>BF1395-SP</b>	P. Fuel (High Efficiency) (1R0749)..... <b>BF7587 +</b>	Conical Air (29 In.) (Don. P185024)..... <b>PA3951</b>
Fuel/Water Separator (256-8753)..... <b>BF1259</b>	Air (w/Lid) (Don. P181099)..... <b>PA2333</b>	FLL w/Cummins 6C Series Eng.
Fuel (1R1712)..... <b>BF614 +</b>	Conical Air (25 In.) (Don. P530866)..... <b>PA2631</b>	F-F Lube (3313281)..... <b>B205 +</b>
Fuel (High Efficiency) (1R0749).... <b>BF7587 +</b>	Conical Air (29 In.) (Don. P185024)..... <b>PA3951</b>	Dual-Flow Lube (3318853)..... <b>BD103 +</b>
Air (w/Lid) (Don. P181099)..... <b>PA2333</b>		Fuel/Water Separator (3925274)..... <b>BF1280 +</b>
Conical Air (25 In.) (Don. P530866)..... <b>PA2631</b>		S. Fuel (3903640)..... <b>BF788</b>
Conical Air (29 In.) (Don. P185024)..... <b>PA3951</b>		Air (w/Lid) (Don. P181099)..... <b>PA2333</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).


FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
<b>FLL w/Cummins 6C Series Eng. (Cont'd)</b> <b>Conical Air</b> (25 In.) (Don. P530866)..... <b>PA2631</b> <b>Conical Air</b> (29 In.) (Don. P185024)..... <b>PA3951</b>	<b>FLT w/Cat 3306 Eng. (Cont'd)</b> <b>P. Fuel Spin-on</b> (1R0740)..... <b>BF970 +</b> <b>S. Fuel</b> (1R0750)..... <b>BF7633 +</b>	<b>FLT w/Cummins NTC Eng. (Cont'd)</b> <b>B-P Lube Ele.</b> (256838)..... <b>C750-E +</b> <b>B-P Lube Spin-on</b> (3313283)..... <b>B7577</b> <b>Fuel/Water Separator</b> (3308638)..... <b>BF1212 +</b> <b>P. Fuel</b> (154709)..... <b>BF957 +</b>
<b>FLL w/Detroit Diesel Series 50 Eng.</b> <b>Lube</b> (23530573)..... <b>[2] B495</b> <b>Fuel/Water Separator</b> (23516189)..... <b>BF5812</b> <b>Fuel/Water Separator</b> (w/Drain) (23535985)..... <b>BF5813 +</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (23535985)..... <b>BF5813-O +</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b> <b>Air</b> (w/Lid) (Don. P181099)..... <b>PA2333</b> <b>Conical Air</b> (25 In.) (Don. P530866)..... <b>PA2631</b> <b>Conical Air</b> (29 In.) (Don. P185024)..... <b>PA3951</b>	<b>FLT w/Cat 3406 Eng.</b> <b>Lube</b> (1R0716)..... <b>B99 +</b> <b>Lube</b> (High Efficiency) (1R1808)..... <b>B7299 +</b> <b>Fuel/Water Separator</b> (256-8753)..... <b>BF1259</b> <b>P. Fuel Ele.</b> (9M2342)..... <b>PF935</b> <b>P. Fuel Spin-on</b> (4N5823)..... <b>BF614 +</b> <b>P. Fuel Spin-on</b> (High Efficiency) (1R0749)..... <b>BF7587 +</b>	<b>FLT w/Detroit Diesel Series 60 Eng. (To 1993)</b> <b>Lube</b> (23530407)..... <b>[2] B95 +</b> <b>B-P Lube</b> (23530413)..... <b>B7577</b> <b>Fuel/Water Separator</b> (w/Drain) (23535985)..... <b>BF5813 +</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (23535985)..... <b>BF5813-O +</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b>
<b>FLL w/Detroit Diesel Series 60 Eng.</b> <b>F-F Lube</b> (To 1993) (23530407).... <b>[2] B95 +</b> <b>F-F Lube</b> (1993-on) (23530573).... <b>[2] B495</b> <b>F-F Lube</b> (1993-on (Upgrade)) (Don. DELF3998)..... <b>[2] B495-SS</b> <b>B-P Lube</b> (To 1993) (23530413)..... <b>B7577</b> <b>Fuel/Water Separator</b> (w/Drain) (23535985)..... <b>BF5813 +</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (23535985)..... <b>BF5813-O +</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b> <b>Air</b> (w/Lid) (Don. P181099)..... <b>PA2333</b> <b>Conical Air</b> (25 In.) (Don. P530866)..... <b>PA2631</b> <b>Conical Air</b> (29 In.) (Don. P185024)..... <b>PA3951</b>	<b>FLT w/Cat 3408 Eng.</b> <b>Lube</b> (1R0716)..... <b>B99 +</b> <b>P. Fuel Ele.</b> (9M2342)..... <b>PF935</b> <b>Fuel Spin-on</b> (4N5823)..... <b>BF614 +</b> <b>Fuel Spin-on</b> (High Efficiency) (1R0749)..... <b>BF7587 +</b>	<b>FLT w/Detroit Diesel Series 60 Eng. (1993-2003)</b> <b>Lube</b> (23530573)..... <b>[2] B495</b> <b>Fuel/Water Separator</b> (w/Drain) (23535985)..... <b>BF5813 +</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (23535985)..... <b>BF5813-O +</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b>
<b>FLL w/Detroit Diesel Series 60 Eng.</b> <b>F-F Lube</b> (1993-on (Upgrade)) (Don. DELF3998)..... <b>[2] B495-SS</b> <b>B-P Lube</b> (To 1993) (23530413)..... <b>B7577</b> <b>Fuel/Water Separator</b> (w/Drain) (23535985)..... <b>BF5813 +</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (23535985)..... <b>BF5813-O +</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b> <b>Air</b> (w/Lid) (Don. P181099)..... <b>PA2333</b> <b>Conical Air</b> (25 In.) (Don. P530866)..... <b>PA2631</b> <b>Conical Air</b> (29 In.) (Don. P185024)..... <b>PA3951</b>	<b>FLT w/Cummins L10 Eng.</b> <b>F-F Lube</b> (9 15/16 In.) (Fleetguard LF670SC)..... <b>B196 +</b> <b>F-F Lube</b> (11 9/32 In.) (Fleetguard LF670SC)..... <b>B96 +</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Fuel/Water Separator</b> (3308638)..... <b>BF1212 +</b> <b>P. Fuel</b> (154789)..... <b>BF957-D +</b>	<b>FLT w/Detroit Diesel Series 60 Eng. (2004)</b> <b>Lube</b> (23530573)..... <b>[2] B495</b> <b>Fuel/Water Separator</b> (w/Drain) (23535985)..... <b>BF5813 +</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (23535985)..... <b>BF5813-O +</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23533726)..... <b>BF5816</b>
<b>FLL w/Detroit Diesel 6V92 Eng.</b> <b>Lube</b> (23530407)..... <b>B95 +</b> <b>Lube</b> (Upgrade) (23530408)..... <b>B95-MPG +</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b> <b>S. Fuel</b> (Upgrade) (23530645)..... <b>BF5815</b> <b>Air</b> (w/Lid) (Don. P181099)..... <b>PA2333</b> <b>Conical Air</b> (25 In.) (Don. P530866)..... <b>PA2631</b> <b>Conical Air</b> (29 In.) (Don. P185024)..... <b>PA3951</b>	<b>FLT w/Cummins N14 Eng.</b> <b>F-F Lube</b> (9 15/16 In.) (Fleetguard LF670SC)..... <b>B196 +</b> <b>F-F Lube</b> (11 9/32 In.) (Fleetguard LF670SC)..... <b>B96 +</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Fuel/Water Separator</b> (3308638)..... <b>BF1212 +</b> <b>P. Fuel</b> (154789)..... <b>BF957-D +</b>	<b>FLT w/Detroit Diesel 6-71 Eng.</b> <b>Lube</b> (23530407)..... <b>B95 +</b> <b>Lube</b> (Upgrade) (23530408)..... <b>B95-MPG +</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b> <b>S. Fuel</b> (Upgrade) (23530645)..... <b>BF5815</b>
<b>FLL w/Detroit Diesel 6V92 Eng.</b> <b>Lube</b> (23530407)..... <b>B95 +</b> <b>Lube</b> (Upgrade) (23530408)..... <b>B95-MPG +</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b> <b>S. Fuel</b> (Upgrade) (23530645)..... <b>BF5815</b> <b>Air</b> (w/Lid) (Don. P181099)..... <b>PA2333</b> <b>Conical Air</b> (25 In.) (Don. P530866)..... <b>PA2631</b> <b>Conical Air</b> (29 In.) (Don. P185024)..... <b>PA3951</b>	<b>FLT w/Cummins VT903 Eng.</b> <b>F-F Lube</b> (9 15/16 In.) (3313279)..... <b>B196 +</b> <b>F-F Lube</b> (11 9/32 In.) (3313279)..... <b>B96 +</b> <b>B-P Lube Ele.</b> (256838)..... <b>C750-E +</b> <b>B-P Lube Spin-on</b> (3313283)..... <b>B7577</b> <b>Fuel/Water Separator</b> (3308638)..... <b>BF1212 +</b> <b>Fuel</b> (156172)..... <b>BF957-D +</b>	<b>FLT w/Detroit Diesel 6V-92N (9.0L) Eng.</b> <b>Lube</b> (23530407)..... <b>B95 +</b> <b>Lube</b> (Upgrade) (23530408)..... <b>B95-MPG +</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b> <b>S. Fuel</b> (Upgrade) (23530645)..... <b>BF5815</b>
<b>FLT w/Cat 3306 Eng.</b> <b>Lube Ele.</b> (5S0484)..... <b>PT670</b> <b>Lube Spin-on</b> (1R0716)..... <b>B99 +</b> <b>Fuel/Water Separator Box-Style</b> (6N7617)..... <b>BF912</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Fuel/Water Separator Spin-on</b> (256-8753)..... <b>BF1259</b> <b>P. Fuel Ele.</b> (7W8910)..... <b>CLN&amp;R</b> <b>P. Fuel Ele.</b> (9M2341)..... <b>PF935</b>	<b>FLT w/Cummins KT 1150 Eng.</b> <b>F-F Lube</b> (9 15/16 In.) (3313279)..... <b>B196 +</b> <b>F-F Lube</b> (11 9/32 In.) (3313279)..... <b>B96 +</b> <b>B-P Lube Ele.</b> (256838)..... <b>C750-E +</b> <b>B-P Lube Spin-on</b> (3313283)..... <b>B7577</b> <b>Fuel/Water Separator</b> (3308638)..... <b>BF1212 +</b> <b>P. Fuel</b> (156172)..... <b>BF957-D +</b>	<b>FLT w/Detroit Diesel 8V-71 (9.3L) Eng.</b> <b>Lube</b> (23530407)..... <b>B95 +</b> <b>Lube</b> (Upgrade) (23530408)..... <b>B95-MPG +</b> <b>P. Fuel Sock</b> (5574980)..... <b>F844-A</b> <b>P. Fuel Ele.</b> (5575032)..... <b>PF845</b> <b>P. Fuel Spin-on</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel Ele.</b> (5574508)..... <b>PF902</b> <b>S. Fuel Ele.</b> (6436719)..... <b>PF846</b> <b>S. Fuel Spin-on</b> (23530707)..... <b>BF5810</b> <b>S. Fuel Spin-on</b> (Upgrade) (23530645)..... <b>BF5815</b>
<b>FLT w/Cummins NTC Eng.</b> <b>F-F Lube Ele.</b> (158139)..... <b>P999-HD</b> <b>F-F Lube Spin-on</b> (9 15/16 In.) (3313279)..... <b>B196 +</b> <b>F-F Lube Spin-on</b> (11 9/32 In.) (3313279)..... <b>B96 +</b> <b>Dual-Flow Lube Spin-on</b> (3318853)..... <b>BD103 +</b>		

+ See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
FLT w/Detroit Diesel 8V-92 (12.1L) Eng. Lube (23530407)..... <b>B95+</b> Lube (Upgrade) (23530408)..... <b>B95-MPG+</b> P. Fuel (23530706)..... <b>BF5800+</b> S. Fuel (23530707)..... <b>BF5810</b> S. Fuel (23530645)..... <b>BF5815</b>	FS-65 Bus w/Cat 3126 (7.2L) Eng. (1/2004-on) (Cont'd) Fuel/Water Separator (Open End for Bowl) (Racor S3225P)..... <b>BF1348-O</b> Fuel (1R0751)..... <b>BF7632</b> Single Radial Seal Air (Don. P532966)..... <b>RS3517</b> Single Radial Seal XP Air (Don. P532966)..... <b>RS3517XP</b> Radial Seal O. Air (Don. P532503)..... <b>RS3506</b> Radial Seal XP O. Air (Don. P532503)..... <b>RS3506XP</b> Radial Seal I. Air (Don. P532504)..... <b>RS3507</b> Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b> Trans. Pan-Type (AT Series, 3.8 In. Pan) (Allison 29540976)..... <b>19992+</b> Trans. Pan-Type (AT Series, 5.3 In. Pan) (Allison 29538489)..... <b>19739+</b> Trans. Spin-on (AT Series) (Allison 29510922)..... <b>BT8316-MPG</b> Trans. Pan-Type (2000 Series, S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (2000 Series, S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (2000 Series, D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (2000 Series, D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (2000 Series) (Allison 29539579)..... <b>BT8460</b> Trans. Ele. (3000 Series, 2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (3000 Series, 4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Steering (VML/S1414)..... <b>PT8407</b>	FS-65 Bus w/Cat C7 (7.2L) Eng. (To 1/2004) (Cont'd) Fuel (1R0751)..... <b>BF7632</b> Single Radial Seal Air (Don. P532966)..... <b>RS3517</b> Single Radial Seal XP Air (Don. P532966)..... <b>RS3517XP</b> Radial Seal O. Air (Don. P532503)..... <b>RS3506</b> Radial Seal XP O. Air (Don. P532503)..... <b>RS3506XP</b> Radial Seal I. Air (Don. P532504)..... <b>RS3507</b> Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b> Trans. Pan-Type (AT Series, 3.8 In. Pan) (Allison 29540976)..... <b>19992+</b> Trans. Pan-Type (AT Series, 5.3 In. Pan) (Allison 29538489)..... <b>19739+</b> Trans. Spin-on (AT Series) (Allison 29510922)..... <b>BT8316-MPG</b> Trans. Pan-Type (2000 Series, S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (2000 Series, S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (2000 Series, D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (2000 Series, D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (2000 Series) (Allison 29539579)..... <b>BT8460</b> Trans. Ele. (3000 Series, 2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (3000 Series, 4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Steering (VML/S1414)..... <b>PT8407</b>
FS-65 Bus w/Cat 3126 (7.2L) Eng. (1/2004-on) Lube (Standard Vers.) (1R0739).. <b>B76</b> Fuel/Water Separator (w/o SP) (Racor S3225P)..... <b>BF1348</b> Fuel/Water Separator (w/SP) (Racor S3225P)..... <b>BF1348-SP</b> Fuel/Water Separator (Open End for Bowl) (Racor S3225P)..... <b>BF1348-O</b> Fuel (1R0751)..... <b>BF7632</b> Single Radial Seal Air (Don. P532966)..... <b>RS3517</b> Single Radial Seal XP Air (Don. P532966)..... <b>RS3517XP</b> Radial Seal O. Air (Don. P532503)..... <b>RS3506</b> Radial Seal XP O. Air (Don. P532503)..... <b>RS3506XP</b> Radial Seal I. Air (Don. P532504)..... <b>RS3507</b> Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b> Trans. Pan-Type (AT Series, 3.8 In. Pan) (Allison 29540976)..... <b>19992+</b> Trans. Pan-Type (AT Series, 5.3 In. Pan) (Allison 29538489)..... <b>19739+</b> Trans. Spin-on (AT Series) (Allison 29510922)..... <b>BT8316-MPG</b> Trans. Pan-Type (2000 Series, S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (2000 Series, S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (2000 Series, D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (2000 Series, D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (2000 Series) (Allison 29539579)..... <b>BT8460</b> Trans. Ele. (3000 Series, 2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (3000 Series, 4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Steering (VML/S1414)..... <b>PT8407</b>	FS-65 Bus w/Cat C7 (7.2L) Eng. (To 1/2004) Lube (Standard Vers.) (1R0739).. <b>B76+</b> Lube (Severe Service) (1R0739).. <b>B76-SS+</b> Fuel/Water Separator (w/o Sensor Port) (Racor S3225P)..... <b>BF1348</b> Fuel/Water Separator (w/Sensor Port) (Racor S3225P)..... <b>BF1348-SP</b> Fuel/Water Separator (Open End for Bowl) (Racor S3225P)..... <b>BF1348-O</b> Fuel/Water Separator (198-6378)..... <b>BF7798-SP</b> Fuel/Water Separator (Open End for Bowl) (Racor S3226P)..... <b>BF1346-O</b> Fuel/Water Separator (w/Sensor Port) (Racor S3226P)..... <b>BF1346-SP</b> Fuel/Water Separator (w/Drain) (Racor S3226P)..... <b>BF1346</b> Fuel (1R0751)..... <b>BF7632</b> Single Radial Seal Air (Don. P532966)..... <b>RS3517</b>	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
FS-65 Bus w/Cat C7 (7.2L) Eng. (1/2004-on) (Cont'd)	FS-65 Bus w/Cummins B5.9 (5.9L) Eng.	FS-65 Bus w/Cummins ISB (3.9L) Eng. (Cont'd)
Single Radial Seal XP Air (Don. P532966).....	Lube.....	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965).....
<b>RS3517XP</b>	<b>BT339 +</b>	<b>20016</b>
Radial Seal O. Air (Don. P532503).....	Radial Seal O. Air (Don. P526678).....	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966).....
<b>RS3506</b>	<b>RS3520</b>	<b>20003</b>
Radial Seal XP O. Air (Don. P532503).....	Radial Seal I. Air (Don. P529548).....	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966).....
<b>RS3506XP</b>	<b>RS3521</b>	<b>20017</b>
Radial Seal I. Air (Don. P532504).....	Radial Seal Air (Don. P532966)...	Trans. Spin-on (Allison 29539579).....
<b>RS3507</b>	<b>RS3517</b>	<b>BT8460</b>
Air Dryer (AD-9 System) (Bendix 107796).....	Radial Seal XP Air (Don. P532966).....	Trans. Ele. (2 In. Kit) (Allison 29548987).....
<b>BA5377</b>	<b>RS3517XP</b>	<b>PT9416-MPG KIT</b>
Trans. Pan-Type (AT Series, 3.8 In. Pan) (Allison 29540976).....	FS-65 Bus w/Cummins 6BT5.9 (5.9L) Eng. (To 1998)	Trans. Ele. (4 In. Kit) (Allison 29548988).....
<b>19992 +</b>	Lube (3914395).....	<b>PT9415-MPG KIT</b>
Trans. Pan-Type (AT Series, 5.3 In. Pan) (Allison 29538489).....	Fuel/Water Separator (3925274).....	
<b>19739 +</b>	<b>BT339 +</b>	
Trans. Spin-on (AT Series) (Allison 29510922).....	S. Fuel (3903640).....	
<b>BT8316-MPG</b>	<b>BF1280 +</b>	
Trans. Pan-Type (2000 Series, S. Pan w/o Gskt.) (Allison 29537965).....	Radial Seal Air (Don. P532966)...	
<b>20004</b>	<b>BF788</b>	
Trans. Pan-Type (2000 Series, S. Pan w/Gskt.) (Allison 29537965).....	Radial Seal XP Air (Don. P532966).....	
<b>20016</b>	<b>RS3517</b>	
Trans. Pan-Type (2000 Series, D. Pan w/o Gskt.) (Allison 29537966).....	<b>RS3517XP</b>	
<b>20003</b>	FS-65 Bus w/Cummins 6BT5.9 (5.9L) Eng. (1998-on)	
Trans. Pan-Type (2000 Series, D. Pan w/Gskt.) (Allison 29537966).....	Lube (Chrysler 5083285AA).....	
<b>20017</b>	<b>BT7349</b>	
Trans. Spin-on (2000 Series) (Allison 29539579).....	Fuel/Water Separator (3925274).....	
<b>BT8460</b>	<b>BF1280 +</b>	
Trans. Ele. (3000 Series, 2 In. Kit) (Allison 29540493).....	S. Fuel (3903640).....	
<b>PT9416-MPG KIT</b>	<b>BF788</b>	
Trans. Ele. (3000 Series, 4 In. Kit) (Allison 29540494).....	Radial Seal Air (Don. P532966)...	
<b>PT9415-MPG KIT</b>	<b>RS3517</b>	
Steering (VML/S1414).....	Radial Seal XP Air (Don. P532966).....	
<b>PT8407</b>	<b>RS3517XP</b>	
FS-65 Bus w/Cat C11(11.1L) Eng. (To 1/2004)	FS-65 Bus w/Cummins 6C Series Eng.	
Lube (1R0716).....	F-F Lube (3313281).....	
<b>B99 +</b>	<b>B205 +</b>	
Lube (1R1808).....	Dual-Flow Lube (3318853).....	
<b>B7299 +</b>	<b>BD103 +</b>	
Fuel/Water Separator (256-8753).....	Fuel/Water Separator (3925274).....	
<b>BF1259</b>	<b>BF1280 +</b>	
Fuel (1R1712).....	S. Fuel (3903640).....	
<b>BF614 +</b>	<b>BF788</b>	
Fuel (High Efficiency) (1R0749)...	Radial Seal Air (Don. P532966)...	
<b>BF7587 +</b>	<b>RS3517</b>	
Fuel (1R0762).....	Radial Seal XP Air (Don. P532966).....	
<b>BF7753</b>	<b>RS3517XP</b>	
Radial Seal Air (Don. P532966)...	FS-65 Bus w/Cummins ISB (3.9L) Eng.	
<b>RS3517</b>	Lube (Fleetguard LF3970).....	
Radial Seal XP Air (Don. P532966).....	<b>B7177</b>	
<b>RS3517XP</b>	Fuel/Water Separator Ele. (3942470).....	
FS-65 Bus w/Cat C11(11.1L) Eng. (1/2004-on)	<b>PF7777</b>	
Lube (1R1808).....	Fuel/Water Separator Spin-on (w/o SP) (Racor S3225P).....	
<b>B7299 +</b>	<b>BF1348</b>	
Fuel/Water Separator (256-8753).....	Fuel/Water Separator Spin-on (Open End for Bowl) (Racor S3225P).....	
<b>BF1259</b>	<b>BF1348-O</b>	
Fuel (1R1712).....	Fuel/Water Separator Spin-on (w/SP) (Racor S3225P).....	
<b>BF614 +</b>	<b>BF1348-SP</b>	
Fuel (High Efficiency) (1R0749)...	Radial Seal O. Air (Don. P532503).....	
<b>BF7587 +</b>	<b>RS3506</b>	
Fuel (1R0762).....	Radial Seal XP O. Air (Don. P532503).....	
<b>BF7753</b>	<b>RS3506XP</b>	
Radial Seal Air (Don. P532966)...	Radial Seal I. Air (Don. P532504).....	
<b>RS3517</b>	<b>RS3507</b>	
Radial Seal XP Air (Don. P532966).....	Radial Seal Air (Don. P532966)...	
<b>RS3517XP</b>	<b>RS3517</b>	
	Radial Seal XP Air (Don. P532966).....	
	<b>RS3517XP</b>	
	Disposable Air Hsg. (Farr 11488005L).....	
	<b>PA4655</b>	
	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965).....	
	<b>20004</b>	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>	<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>	<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>
FS-65 Bus w/Cummins ISB (5.9L) Eng. (Cont'd) <b>Trans. Ele.</b> (3000 Series, 4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT (Opt. Oil Cooler) Trans.</b> (ACDelco PF897)..... <b>BT230</b> <b>Steering</b> (VMLS1414)..... <b>PT8407</b>	FS-65 Bus w/Mercedes MBE904 (4.3L) Eng. (Cont'd) <b>Trans. Pan-Type</b> (2000 Series, D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (2000 Series, D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (2000 Series) (Allison 29539579)..... <b>BT8460</b> <b>Trans. Ele.</b> (3000 Series, 2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (3000 Series, 4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (VMLS1414)..... <b>PT8407</b>	FS-65 Bus w/Mercedes MBE906 (6.4L) Eng. (Cont'd) <b>Trans. Pan-Type</b> (2000 Series, D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (2000 Series, D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (2000 Series) (Allison 29539579)..... <b>BT8460</b> <b>Trans. Ele.</b> (3000 Series, 2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (3000 Series, 4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (VMLS1414)..... <b>PT8407</b>
FS-65 Bus w/Cummins ISC (8.3L) Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel/Water Separator</b> (Fleetguard FS1003)..... <b>BF1293-SPS</b> <b>Fuel</b> (Fleetguard FF5488)..... <b>BF7815</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b> <b>Coolant</b> (w/23 Units BTA+) (Fleetguard WF2076)..... <b>BW5076</b>	FS-65 Bus w/Mercedes MBE906 (6.4L) Eng. <b>5 5/16 In. F-F Lube</b> (1801609)..... <b>P7199</b> <b>8 3/8 In. F-F Lube</b> (1801709)..... <b>P7188</b> <b>Opt. B-P Lube</b> (A9061810086).... <b>BC7326 +</b> <b>Fuel/Water Separator</b> (w/Drain) (Racor R60P)..... <b>BF1329</b> <b>Fuel/Water Separator</b> (SP Thd. 9/16-18) (Racor R60P)..... <b>BF1329-SP</b> <b>Fuel/Water Separator</b> (SP Thd. 1/2-20) (Racor R60P)..... <b>BF1339-SP</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R60P)..... <b>BF46147-O</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R90P)..... <b>BF46083-O</b> <b>Fuel/Water Separator</b> (w/Bowl) (Racor R90P)..... <b>BF46072</b> <b>Fuel/Water Separator</b> (w/Drain) (Racor R90P)..... <b>BF1329</b> <b>Fuel/Water Separator</b> (Sensor Port Thd. 9/16-18) (Racor R90P)..... <b>BF1329-SP</b> <b>Fuel/Water Separator</b> (Sensor Port Thd. 1/2-20) (Racor R90P).... <b>BF1339-SP +</b> <b>4 1/16 In. Fuel</b> (A0000901551).... <b>PF7735</b> <b>7 31/32 In. Fuel</b> (A5410920805).... <b>PF7761</b> <b>Single Radial Seal Air</b> (Don. P532966)..... <b>RS3517</b> <b>Single Radial Seal XP Air</b> (Don. P532966)..... <b>RS3517XP</b> <b>Radial Seal O. Air</b> (Don. P532503)..... <b>RS3506</b> <b>Radial Seal XP O. Air</b> (Don. P532503)..... <b>RS3506XP</b> <b>Radial Seal I. Air</b> (Don. P532504)..... <b>RS3507</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Trans. Pan-Type</b> (AT Series, 3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (AT Series, 5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (AT Series) (Allison 29510922)..... <b>BT8316-MPG</b> <b>Trans. Pan-Type</b> (2000 Series, S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (2000 Series, S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	FS-65 Bus w/Mercedes MBE924 (4.8L) Eng. <b>F-F Lube Ele.</b> (1801609)..... <b>P7199</b> <b>Opt. B-P Lube Spinner</b> (A9061810086)..... <b>BC7326 +</b> <b>4 1/16 In. Fuel Ele.</b> (A0000901551)..... <b>PF7735</b> <b>7 31/32 In. Fuel Ele.</b> (A5410920805)..... <b>PF7761</b>
FS-65 Bus w/Mercedes MBE904 (4.3L) Eng. <b>5 5/16 In. F-F Lube</b> (1801609).... <b>P7199</b> <b>8 3/8 In. F-F Lube</b> (1801709)..... <b>P7188</b> <b>Opt. B-P Lube</b> (A9061810086).... <b>BC7326 +</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R90P)..... <b>BF46083-O</b> <b>Fuel/Water Separator</b> (w/Bowl) (Racor R90P)..... <b>BF46072</b> <b>Fuel/Water Separator</b> (w/Drain) (Racor R90P)..... <b>BF1329</b> <b>Fuel/Water Separator</b> (Sensor Port Thd. 9/16-18) (Racor R90P).... <b>BF1329-SP</b> <b>Fuel/Water Separator</b> (Sensor Port Thd. 1/2-20) (Racor R90P).... <b>BF1339-SP +</b> <b>4 1/16 In. Fuel</b> (A0000901551).... <b>PF7735</b> <b>7 31/32 In. Fuel</b> (A5410920805).... <b>PF7761</b> <b>Single Radial Seal Air</b> (Don. P532966)..... <b>RS3517</b> <b>Single Radial Seal XP Air</b> (Don. P532966)..... <b>RS3517XP</b> <b>Radial Seal O. Air</b> (Don. P532503)..... <b>RS3506</b> <b>Radial Seal XP O. Air</b> (Don. P532503)..... <b>RS3506XP</b> <b>Radial Seal I. Air</b> (Don. P532504)..... <b>RS3507</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (Fleetguard WF2077)..... <b>B5134 +</b> <b>Trans. Pan-Type</b> (AT Series, 3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (AT Series, 5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (AT Series) (Allison 29510922)..... <b>BT8316-MPG</b> <b>Trans. Pan-Type</b> (2000 Series, S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (2000 Series, S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	FS-65 Bus w/Mercedes MBE926 (7.2L) Eng. <b>Lube</b> (1801709)..... <b>P7188</b> <b>Opt. B-P Lube</b> (A9061810086).... <b>BC7326 +</b> <b>Fuel/Water Separator</b> (w/Drain) (Racor R60P)..... <b>BF1329</b> <b>Fuel/Water Separator</b> (SP Thd. 9/16-18) (Racor R60P)..... <b>BF1329-SP</b> <b>Fuel/Water Separator</b> (SP Thd. 1/2-20) (Racor R60P)..... <b>BF1339-SP</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R60P)..... <b>BF46147-O</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R90P)..... <b>BF46083-O</b> <b>Fuel/Water Separator</b> (w/Bowl) (Racor R90P)..... <b>BF46072</b> <b>Fuel</b> (901551)..... <b>PF7735</b> <b>Channel Flow Air</b> (Don. P548070)..... <b>CA4700 +</b> <b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960) <b>CA5420 +</b> <b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Trans. Pan-Type</b> (AT Series, 3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (AT Series, 5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (AT Series) (Allison 29510922)..... <b>BT8316-MPG</b> <b>Trans. Pan-Type</b> (2000 Series, S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (2000 Series, S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
FS-65 Bus w/Mercedes MBE926 (7.2L) Eng. (Cont'd)	M2 w/Mercedes-Benz MBE906 (6.4L) Eng. (2015-17)	M2 100 w/Mercedes-Benz MBE904 (4.3L) Eng. (2004-06) (Cont'd)
<b>Trans. Pan-Type</b> (2000 Series, D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>F-F Lube Ele.</b> (1801709)..... <b>P7188</b>	<b>Channel Flow Air</b> (Std. Media) (Don. P607955)..... <b>CA4700 +</b>
<b>Trans. Pan-Type</b> (2000 Series, D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Opt. B-P Lube Spinner</b> (A9061810086)..... <b>BC7326 +</b>	<b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960) <b>CA5420 +</b>
<b>Trans. Spin-on</b> (2000 Series) (Allison 29539579)..... <b>BT8460</b>	<b>Fuel/Water Separator</b> (Closed End) (S3226FL02Y)..... <b>BF1339-SP +</b>	<b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b>
<b>Trans. Ele.</b> (3000 Series, 2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (S3226FL02Y)..... <b>BF46083-O</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>
<b>Trans. Ele.</b> (3000 Series, 4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Fuel Ele.</b> (901551)..... <b>PF7735</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
<b>Steering</b> (VML/S1414)..... <b>PT8407</b>	<b>Fuel Screen</b> (901351)..... <b>PF7974 +</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>
FS-65 Bus w/Mercedes OM906 Eng.	<b>Channel Flow Air</b> (Std. Media) (Don. P607955)..... <b>CA4700 +</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Lube</b> (A0001801609)..... <b>P7199</b>	<b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960) <b>CA5420 +</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R90P)..... <b>BF46083-O</b>	<b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Fuel/Water Separator</b> (w/Bowl) (Racor R90P)..... <b>BF46072</b>	<b>Radial Seal Air</b> (Don. P532966)... P532966)..... <b>RS3517</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
<b>Fuel/Water Separator</b> (w/Drain) (Racor R90P)..... <b>BF1329</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>Fuel/Water Separator</b> (Sensor Port Thd. 9/16-18) (Racor R90P)... <b>BF1329-SP</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29526899)..... <b>PT9416-MPG KIT</b>
<b>Fuel/Water Separator</b> (Sensor Port Thd. 1/2-20) (Racor R90P)... <b>BF1339-SP +</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29526898)..... <b>PT9415-MPG KIT</b>
<b>Fuel</b> (A9060920305)..... <b>PF7735</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Steering</b> (T1808D)..... <b>BT9388</b>
<b>Radial Seal Air</b> (Don. P532966)... P532966)..... <b>RS3517</b>	<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>
<b>Radial Seal XP Air</b> (Don. P532966)..... <b>RS3517XP</b>	<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>	M2 100 w/Mercedes-Benz MBE906 (6.4L) Eng. (2002-05)
<b>Trans. Pan-Type</b> (AT Series, 3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>F-F Lube Ele.</b> (1801709)..... <b>P7188</b>
<b>Trans. Pan-Type</b> (AT Series, 5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Opt. B-P Lube Spinner</b> (A9061810086)..... <b>BC7326 +</b>
<b>Trans. Spin-on</b> (AT Series) (Allison 29510922)..... <b>BT8316-MPG</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Fuel/Water Separator</b> (Closed End) (S3226FL02Y)..... <b>BF1339-SP +</b>
<b>Trans. Pan-Type</b> (2000 Series, S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (S3226FL02Y)..... <b>BF46083-O</b>
<b>Trans. Pan-Type</b> (2000 Series, S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Fuel Ele.</b> (901551)..... <b>PF7735</b>
<b>Trans. Pan-Type</b> (2000 Series, D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Fuel Screen</b> (901351)..... <b>PF7974 +</b>
<b>Trans. Pan-Type</b> (2000 Series, D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Channel Flow Air</b> (Std. Media) (Don. P607955)..... <b>CA4700 +</b>
<b>Trans. Spin-on</b> (2000 Series) (Allison 29539579)..... <b>BT8460</b>	<b>Steering</b> (T1808D)..... <b>BT9388</b>	<b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960) <b>CA5420 +</b>
<b>Trans. Ele.</b> (3000 Series, 2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b>
<b>Trans. Ele.</b> (3000 Series, 4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	M2 100 w/Mercedes-Benz MBE904 (4.3L) Eng. (2004-06)	<b>Radial Seal Air</b> (Don. P532966)... P532966)..... <b>RS3517XP</b>
<b>Steering</b> (VMLS1414)..... <b>PT8407</b>	<b>F-F Lube Ele.</b> (1801609)..... <b>P7199</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>
	<b>Opt. B-P Lube Spinner</b> (A9061810086)..... <b>BC7326 +</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
	<b>Fuel/Water Separator</b> (Alliance ABP/N122-S3226FL02)..... <b>BF9898-O</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>
	<b>Pre-Fuel</b> (A0000901351)..... <b>PF7974 +</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>
	<b>P. Fuel</b> (902051)..... <b>PF7939 +</b>	<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>
	<b>S. Fuel</b> (901551)..... <b>PF7735</b>	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
M2 100 w/Mercedes-Benz MBE906 (6.4L) Eng. (2002-05) (Cont'd)	M2 106 w/Cat 3126 (7.2L) Eng. (1/2004-on) (Cont'd)	M2 106 w/Cat C7 (7.2L) Eng. (2004-07) (Cont'd)
<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>	<b>Channel Flow Air</b> (Std. Media) (Don. P607955)..... <b>CA4700 +</b>	<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960) <b>CA5420 +</b>	<b>Coolant</b> (9N3368)..... <b>BW5137</b>
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
<b>Steering</b> (T1808D)..... <b>BT9388</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
M2 106 w/Cat 3126 (7.2L) Eng. (To 1/2004)	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Steering</b> (VML/T1808D)..... <b>BT9388</b>
<b>Lube</b> (Standard Vers.) (1R0739).. <b>B76 +</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29526899)..... <b>PT9416-MPG KIT</b>	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>
<b>Lube</b> (Severe Service) (1R0739).. <b>B76-SS +</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29526898)..... <b>PT9415-MPG KIT</b>	M2 106 w/Cat C9 (8.8L) Eng. (2004-07)
<b>Fuel</b> (1R0751)..... <b>BF7632</b>	<b>Steering</b> (T1808D)..... <b>BT9388</b>	<b>Lube</b> (1R1808)..... <b>B7299 +</b>
<b>Opt. S. Fuel</b> (Davco 101377)..... <b>BF788</b>	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>7 3/8 In. Fuel/Water Separator</b> (175-2949)..... <b>BF1268</b>
<b>Channel Flow Air</b> (Std. Media) (Don. P607955)..... <b>CA4700 +</b>	M2 106 w/Cat C7 (7.2L) Eng. (2004-07)	<b>8 9/32 In. Fuel/Water Separator</b> (S3226FL02)..... <b>BF1346-SP +</b>
<b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960) <b>CA5420 +</b>	<b>Lube</b> (1R1807)..... <b>B7700 +</b>	<b>Fuel/Water Separator</b> (Alliance ABPN122R50551)..... <b>BF46016-O</b>
<b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b>	<b>Fuel/Water Separator Spin-on</b> (w/Drain) (Alliance ABP/S3226FL02)..... <b>BF1346 +</b>	<b>Fuel</b> (1R0751)..... <b>BF7632</b>
<b>Cab Air</b> (36000006)..... <b>PA5359</b>	<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Alliance ABP/N122-R50418)..... <b>BF9898-O</b>	<b>Channel Flow Air</b> (Std. Media) (Don. P607955)..... <b>CA4700 +</b>
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Suction line Fuel/Water Separator Spin-on</b> (175-2949)..... <b>BF1268</b>	<b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960) <b>CA5420 +</b>
<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Fuel Spin-on</b> (1R0751)..... <b>BF7632</b>	<b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Opt. Fuel In-Line</b> (Fleetguard FF5079)..... <b>BF1173</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Channel Flow Air</b> (Std. Media) (Don. P607955)..... <b>CA4700 +</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960) <b>CA5420 +</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>	<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29526899)..... <b>PT9416-MPG KIT</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29526898)..... <b>PT9415-MPG KIT</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Coolant</b> (9N6123)..... <b>BW5139</b>
<b>Steering</b> (T1808D)..... <b>BT9388</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
M2 106 w/Cat 3126 (7.2L) Eng. (1/2004-on)		<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Lube</b> (1R1807)..... <b>B7700 +</b>		<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
<b>Fuel</b> (1R0751)..... <b>BF7632</b>		
<b>Opt. S. Fuel</b> (Davco 101377)..... <b>BF788</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
M2 106 w/Cat C9 (8.8L) Eng. (2004-07) (Cont'd)	M2 106 w/Cat C11 (11.1L) Eng. (2006) (Cont'd)	M2 106 w/Cummins B6.7 (6.7L) Eng. (2019)
Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>	29540494)..... <b>PT9415-MPG KIT</b>	(Cont'd)
Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2+</b>	Cab Air (Alliance ABPN10G36000006)..... <b>PA5359</b>
Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Steering Ele. (Fleetguard 87904M)..... <b>PT9354-MPG</b>	Air Dryer (Wabco R950011)..... <b>BA5374+</b>
Opt. Trans. Spin-on (Fuller 17237)..... <b>B2+</b>	Steering Spin-on (VML/T1808D). <b>BT9388</b>	Crankcase Breather (4936636)... <b>CV15010</b>
Steering (VML/T1808D)..... <b>BT9388</b>	Some Differential (Meritor 3280-V-8394)..... <b>B233</b>	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
Some Differential (Meritor 3280-V-8394)..... <b>B233</b>	M2 106 w/Cummins 4BT3.9 (3.9L) Eng. (2004-07)	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
M2 106 w/Cat C11 (11.1L) Eng. (2006)	Lube (3903224)..... <b>BT427+</b>	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
Lube (1R1808)..... <b>B7299+</b>	Fuel/Water Separator (3903202). <b>BF1226</b>	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
Suction Line Fuel/Water Separator <b>BF1268</b>	P. Fuel (3903640)..... <b>BF788</b>	Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>
Fuel/Water Separator (3 11/16 In. O.D.) (256-8753)..... <b>BF1259</b>	M2 106 w/Cummins B6.7 (6.7L) Eng. (2018)	Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>
Fuel/Water Separator (4 9/32 In. O.D.)..... <b>BF1339-SP+</b>	Lube (3937736)..... <b>B7177</b>	Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>
Fuel/Water Separator (4 5/16 In. O.D., (Open End for Bowl) (BR90FRT10)..... <b>BF9871-O</b>	Fuel/Water Separator (Fleetguard FS20081)..... <b>PF46171</b>	Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>
Fuel (1R0749)..... <b>BF7587+</b>	Fuel/Water Separator (Racor R61709)..... <b>PF46235</b>	M2 106 w/Cummins B6.7 (6.7L) Eng. (2020)
Channel Flow Air (12 25/32 O.D.; Std. Media) (Don. P548070)..... <b>CA4700+</b>	Fuel (Fleetguard FF63009)..... <b>BF63000</b>	Lube (3937736)..... <b>B7177</b>
Channel Flow Air (11 21/32 In. O.D.; Flame Retardant Media) (Don. P607960)..... <b>CA5420+</b>	Fuel (5660774)..... <b>BF63000</b>	Fuel/Water Separator (Fleetguard FS20081)..... <b>PF46171</b>
Channel Flow Secondary Air (Don. P544432)..... <b>PA4701</b>	Channel Flow Primary Air (Standard Media) (Don. P607955)..... <b>CA4700</b>	Fuel/Water Separator (Racor R61709)..... <b>PF46235</b>
Channel Flow Air (14 7/8 In. O.D.; Std. Media) (Don. P607965) <b>CA5368+</b>	Channel Flow Primary Air (Flame Retardant Media) (Don. P607960) <b>CA5420</b>	Fuel (5660774)..... <b>BF63000</b>
Channel Flow Air (14 7/8 In. O.D.; Flame Retardant Media) (Don. P605960)..... <b>CA5419+</b>	Secondary Air (Don. P616400)... <b>PA4701</b>	Channel Flow Primary Air (Don. P607955)..... <b>CA4700</b>
Cab Air (36000006)..... <b>PA5359</b>	Cab Air (36000006)..... <b>PA5359</b>	Channel Flow Secondary Air (Don. P616400)..... <b>PA4701</b>
Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	Air Dryer (Desiccant) (Wabco R950011)..... <b>BA5374+</b>	Cab Air (36000006)..... <b>PA5359</b>
Air Dryer (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	Air Dryer (Coalescer) (Wabco R950068)..... <b>BA5379+</b>	Air Dryer (Wabco R950011)..... <b>BA5374+</b>
Air Dryer (AD-IS System) (Bendix 5008414)..... <b>BA5374+</b>	Crankcase Breather (4936636)... <b>CV15010</b>	Crankcase Breather (4936636)... <b>CV15010</b>
Air Dryer (System Saver 1200) (Wabco R950011)..... <b>BA5374+</b>	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
Air Dryer (SS1200 Plus) (Wabco R950068)..... <b>BA5379+</b>	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>	Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>
Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	Steering (1417927000)..... <b>PT23629</b>	Trans. Ele. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>
Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>	Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>
Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	Diesel Exhaust Fluid (4388378).. <b>PE17002 KIT</b>	Steering (1417927000)..... <b>PT23629</b>
Trans. Ele. (4 In. Kit) (Allison	M2 106 w/Cummins B6.7 (6.7L) Eng. (2019)	Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>
	Lube (3937736)..... <b>B7177</b>	M2 106 w/Cummins B6.7 (6.7L) Eng. (2021)
	Fuel/Water Separator (Fleetguard FS20081)..... <b>PF46171</b>	Lube (3937736)..... <b>B7177</b>
	Fuel/Water Separator (Racor R61709)..... <b>PF46235</b>	Fuel/Water Separator (R61709).. <b>PF46235</b>
	Fuel (5660774)..... <b>BF63000</b>	Fuel (5303743)..... <b>BF63000</b>
	Channel Flow Primary Air (Don. P607955)..... <b>CA4700</b>	Channel Flow Primary Air (Don. P607955)..... <b>CA4700</b>
	Channel Flow Secondary Air (Don. P616400)..... <b>PA4701</b>	


+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
M2 106 w/Cummins B6.7 (6.7L) Eng. (2021) (Cont'd)	M2 106 w/Cummins ISB (5.9L) Eng. (2007)	M2 106 w/Cummins ISB 6.7 (6.7L) Eng. (2008-09) (Cont'd)
Channel Flow Secondary Air (Don. P616400)..... PA4701	Lube (3937144)..... B7177	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016
Cab Air (ABPN10G36000006)..... PA5359	Fuel/Water Separator (4934879)..... BF1378-SPS	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003
Air Dryer (Bendix 107796PG)..... BA5377	Fuel (4934845)..... BF7940	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017
Crankcase Breather (4936636)..... CV15010	Channel Flow Air (Don. P607955)..... CA4700 +	Trans. Spin-on (Allison 29539579)..... BT8460
Pan-Type Trans. (S. Pan, w/o Gskt.) (Allison 29537965)..... 20004	Channel Flow Secondary Air (Don. P616400)..... PA4701	Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT
Pan-Type Trans. (S. Pan, w/Gskt.) (Allison 29537965)..... 20016	Cab Air (VCC36000006)..... PA5359	Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT
Pan-Type Trans. (D. Pan, w/o Gskt.) (Allison 29537966)..... 20003	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004	Opt. Trans. Spin-on (Fuller 17237)..... B2 +
Pan-Type Trans. (D. Pan, w/Gskt.) (Allison 29537966)..... 20017	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016	Steering Ele. (Nelson 87904M).... PT9354-MPG
Trans. Spin-on (Allison 29539579)..... BT8460	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003	Steering Spin-on (VMLT1808D).. BT9388
Trans. Ele. (2 In. Kit) (Allison 29558117)..... PT9416-MPG KIT	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017	Steering (1417927000)..... PT23629
Trans. Ele. (4 In. Kit) (Allison 29558118)..... PT9415-MPG KIT	Trans. Spin-on (Allison 29539579)..... BT8460	Some Differential (Meritor 3280-V-8394)..... B233
Steering (1417927000)..... PT23629	Trans. Ele. (2 In. Kit) (Allison 29548987)..... PT9416-MPG KIT	
Opt. Rear Axle (Meritor 3280V8394)..... B233	Trans. Ele. (4 In. Kit) (Allison 29548988)..... PT9415-MPG KIT	
	Steering (Nelson 87904M)..... PT9354-MPG	
	Differential (Meritor 3280-V-8394)..... B233	
M2 106 w/Cummins B6.7 (6.7L) Eng. (2022)	M2 106 w/Cummins ISB 6.7 (6.7L) Eng. (2008-09)	M2 106 w/Cummins ISB 6.7 (6.7L) Eng. (2010-17)
Lube (Fleetguard LF3970)..... B7177	Lube (Fleetguard LF3970)..... B7177	Lube (Fleetguard LF3970)..... B7177
Fuel/Water Separator (R61709).. PF46235	Fuel/Water Separator (Fleetguard FS1065)..... BF1378-SPS	Fuel/Water Separator (Fleetguard FS1065)..... BF1378-SPS
Channel Flow Air (Don. P607955)..... CA4700	Fuel/Water Separator (Alliance ABPN122BR90FRT-30)..... BF46016-O	Fuel/Water Separator (Alliance ABPN122R50550)..... BF9871-O
Cab Air (ABPN10G36000006)..... PA5359	Fuel/Water Separator (Alliance ABPN122R50550)..... BF9871-O	Fuel (Fleetguard FF5632)..... BF7940
Coalescer Air Dryer (Bendix 5008414PG)..... BA5379	Fuel (Fleetguard FF63009)..... BF63000	Fuel (Fleetguard FF63009)..... BF63000
Desiccant Air Dryer (Wabco R950011)..... BA5374	Channel Flow Air (Std. Media) (Don. P607955)..... CA4700 +	Channel Flow Air (Std. Media) (Don. P607955)..... CA4700 +
Pan-Type Trans. (S. Pan, w/o Gskt.) (Allison 29537965)..... 20004	Channel Flow Air (w/Flame Retardant Media) (Don. P607960) CA5420 +	Channel Flow Air (w/Flame Retardant Media) (Don. P607960) CA5420 +
Pan-Type Trans. (S. Pan, w/Gskt.) (Allison 29537965)..... 20016	Channel Flow Secondary Air (Don. P616400)..... PA4701	Channel Flow Secondary Air (Don. P616400)..... PA4701
Pan-Type Trans. (D. Pan, w/o Gskt.) (Allison 29537966)..... 20003	Cab Air (36000006)..... PA5359	Cab Air (36000006)..... PA5359
Pan-Type Trans. (D. Pan, w/Gskt.) (Allison 29537966)..... 20017	Air Dryer (AD-9 System) (Bendix 107796)..... BA5377	Air Dryer (AD-9 System) (Bendix 107796)..... BA5377
Trans. Spin-on (Allison 29539579)..... BT8460	Air Dryer (AD-IS System) (Bendix 5008414)..... BA5374 +	Air Dryer (AD-IS System) (Bendix 5008414)..... BA5374 +
Trans. Ele. (2 In. Kit) (Allison 29558117)..... PT9416-MPG KIT	Air Dryer (AD-IP System) (Bendix 65624)..... BA5373	Air Dryer (AD-IP System) (Bendix 65624)..... BA5373
Trans. Ele. (4 In. Kit) (Allison 29558118)..... PT9415-MPG KIT	Air Dryer (System Saver 1200) (Wabco R950011)..... BA5374 +	Air Dryer (System Saver 1200) (Wabco R950011)..... BA5374 +
Steering (1417927000)..... PT23629	Air Dryer (SS1200 Plus) (Wabco R950068)..... BA5379 +	Air Dryer (SS1200 Plus) (Wabco R950068)..... BA5379 +
	Crankcase Breather (Fleetguard CV52001)..... CV15010	Crankcase Breather (Fleetguard CV52001)..... CV15010
	Coolant (Fleetguard WF2071)..... BW5071	Coolant (Fleetguard WF2071)..... BW5071
	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004
	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016
	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
M2 106 w/Cummins ISB 6.7 (6.7L) Eng. (2010-17) (Cont'd)	M2 106 w/Cummins ISB (6.7L) Eng. (2019) (Cont'd)	M2 106 w/Cummins ISB6.7-200 (6.7L) Eng. (2007-13) (Cont'd)
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Cab Air</b> (Alliance ABPN10G36000006)..... <b>PA5359</b>	<b>Channel Flow Air</b> (Std. Media) (Don. P607955)..... <b>CA4700 +</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b>	<b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960) <b>CA5420 +</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Channel Flow Secondary Air</b> (Don. P616400)..... <b>PA4701</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
<b>Steering Ele.</b> (Nelson 87904M).... <b>PT9354-MPG</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>
<b>Steering Spin-on</b> (VMLT1808D).. <b>BT9388</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>
<b>Steering</b> (1417927000)..... <b>PT23629</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>
<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>
<b>Diesel Exhaust Fluid</b> (A0001420289)..... <b>PE5272</b>	<b>Steering</b> (1417927000)..... <b>PT23629</b>	<b>Crankcase Breather</b> (Fleetguard CV52001)..... <b>CV15010</b>
<b>Diesel Exhaust Fluid</b> (2888182).. <b>PE17000</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	<b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b>
M2 106 w/Cummins ISB 6.7 (6.7L) Eng. (2018)	<b>Crankcase Breather</b> (4936636).... <b>CV15010</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Lube</b> (3937736)..... <b>B7177</b>	M2 106 w/Cummins ISB (6.7L) Eng. (2020)	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Fuel/Water Separator</b> (Racor R61709)..... <b>PF46235</b>	<b>Lube</b> (3937736)..... <b>B7177</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b>	<b>Fuel/Water Separator</b> (Racor R61709)..... <b>PF46235</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
<b>Channel Flow Primary Air</b> (Standard Media) (Don. P607955)..... <b>CA4700</b>	<b>Fuel</b> (5303743)..... <b>BF63000</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>Channel Flow Primary Air</b> (Flame Retardant Media) (Don. P607960) <b>CA5420</b>	<b>Channel Flow Primary Air</b> (Don. P607955)..... <b>CA4700</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Channel Flow Secondary Air</b> (Don. P616400)..... <b>PA4701</b>	<b>Channel Flow Secondary Air</b> (Don. P616400)..... <b>PA4701</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Cab Air</b> (36000006)..... <b>PA5359</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
<b>Air Dryer</b> (Wabco R950068)..... <b>BA5379 +</b>	<b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b>	<b>Steering Ele.</b> (Nelson 87904M).... <b>PT9354-MPG</b>
<b>Crankcase Breather</b> (4936636).... <b>CV15010</b>	<b>Crankcase Breather</b> (4936636).... <b>CV15010</b>	<b>Steering Spin-on</b> (VMLT1808D).. <b>BT9388</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Steering</b> (1417927000)..... <b>PT23629</b>
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Diesel Exhaust Fluid</b> (2010 Emissions) (A0001420289)..... <b>PE5272</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Diesel Exhaust Fluid</b> (2010 Emissions) (2888182)..... <b>PE17000</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	M2 106 w/Cummins ISB6.7-300 (6.7L) Eng. (2007-13)
<b>Steering</b> (1417927000)..... <b>PT23629</b>	<b>Steering</b> (1417927000)..... <b>PT23629</b>	<b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b>
<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b>
<b>Diesel Exhaust Fluid</b> (4388378).. <b>PE17002 KIT</b>	M2 106 w/Cummins ISB6.7-200 (6.7L) Eng. (2007-13)	<b>Fuel/Water Separator</b> (Alliance ABP/N122BR90FRT-30)..... <b>BF46016-O</b>
M2 106 w/Cummins ISB (6.7L) Eng. (2019)	(2007-13)	<b>Fuel/Water Separator</b> (Alliance ABPN122R50550)..... <b>BF9871-O</b>
<b>Lube</b> (3937736)..... <b>B7177</b>	<b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b>	<b>Fuel</b> (Fleetguard FF5632)..... <b>BF7940</b>
<b>Fuel/Water Separator</b> (Racor R61709)..... <b>PF46235</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b>	<b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b>
<b>Fuel</b> (5303743)..... <b>BF63000</b>	<b>Fuel/Water Separator</b> (Alliance ABP/N122BR90FRT-30)..... <b>BF46016-O</b>	
<b>Channel Flow Primary Air</b> (Don. P607955)..... <b>CA4700 +</b>	<b>Fuel/Water Separator</b> (Alliance ABPN122R50550)..... <b>BF9871-O</b>	
<b>Channel Flow Secondary Air</b> (Don. P616400)..... <b>PA4701</b>	<b>Fuel</b> (Fleetguard FF5632)..... <b>BF7940</b>	
	<b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>	<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>	<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>
M2 106 w/Cummins ISB6.7-300 (6.7L) Eng. (2007-13) (Cont'd)	M2 106 w/Cummins ISC 8.3 (8.3L) Eng. (2001-12/2006) (Cont'd)	M2 106 w/Cummins ISC 8.3 (8.3L) Eng. (1/2007-2016) (Cont'd)
<b>Channel Flow Air</b> (Std. Media) (Don. P607955)..... <b>CA4700 +</b>	<b>Opt. Fuel/Water Separator Spin-on</b> (3800394)..... <b>BF1293-SPS</b>	<b>Some Fuel/Water Separator Spin-on</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b>
<b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960) <b>CA5420 +</b>	<b>Fuel</b> (Fleetguard FF5488)..... <b>BF7815</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (Alliance ABPN122BR90FRT10)..... <b>BF9871-O</b>
<b>Channel Flow Secondary Air</b> (Don. P616400)..... <b>PA4701</b>	<b>Channel Flow Air</b> (Std. Media) (Don. P607955)..... <b>CA4700 +</b>	<b>Opt. Fuel/Water Separator Spin-on</b> (3800394)..... <b>BF1293-SPS</b>
<b>Cab Air</b> (36000006)..... <b>PA5359</b>	<b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960) <b>CA5420 +</b>	<b>Fuel</b> (Fleetguard FF5636)..... <b>BF7924</b>
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b>	<b>Channel Flow Air</b> (Std. Media) (Don. P607955)..... <b>CA4700 +</b>
<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>	<b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960) <b>CA5420 +</b>
<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b>
<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>
<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
<b>Crankcase Breather</b> (Fleetguard CV52001)..... <b>CV15010</b>	<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>
<b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b>	<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Coolant</b> (w/Chemical) (Fleetguard WF2071)..... <b>BW5071</b>	<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134 +</b>	<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Coolant</b> (w/Chemical) (Fleetguard WF2071)..... <b>BW5071</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134 +</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
<b>Steering Ele.</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>Steering Spin-on</b> (VMLT1808D)..... <b>BT9388</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Steering</b> (1417927000)..... <b>PT23629</b>	<b>Steering</b> (VMLT1808D)..... <b>BT9388</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
<b>Diesel Exhaust Fluid</b> (2010 Emissions) (A0001420289)..... <b>PE5272</b>	M2 106 w/Cummins ISC 8.3 (8.3L) Eng. (1/2007-2016)	<b>Steering</b> (VMLT1808D)..... <b>BT9388</b>
<b>Diesel Exhaust Fluid</b> (2010 Emissions) (2888182)..... <b>PE17000</b>	<b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b>	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>
M2 106 w/Cummins ISC 8.3 (8.3L) Eng. (2001-12/2006)	<b>Fuel/Water Separator Spin-on</b> (w/Drain) (Alliance S3226FL01).... <b>BF1347</b>	<b>Diesel Exhaust Fluid</b> (2010 Emissions) (A0001420289)..... <b>PE5272</b>
<b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b>	<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Alliance S3226FL01)..... <b>BF1347-O</b>	<b>Diesel Exhaust Fluid</b> (2010 Emissions) (2888182)..... <b>PE17000</b>
<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19763)..... <b>PF7928</b>	<b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (Alliance S3226FL01)..... <b>BF1373-SP</b>	
<b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1022)..... <b>BF1272-SPS</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19763)..... <b>PF7928</b>	M2 106 w/Cummins ISC 8.3 (8.3L) Eng. (2020)
<b>Fuel/Water Separator</b> (Open End for Bowl) (Alliance ABPN122BR90FRT10)..... <b>BF9871-O</b>		<b>Channel Flow Primary Air</b> (Don. P607955)..... <b>CA4700</b>
		<b>Channel Flow Secondary Air</b> (Don. P616400)..... <b>PA4701</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
M2 106 w/Cummins ISC 8.3 (8.3L) Eng. (2020) (Cont'd)	M2 106 w/Cummins ISC-280 (8.3L) Eng. (2007-12) (Cont'd)	M2 106 w/Cummins ISC-300 (8.3L) Eng. (2007-12) (Cont'd)
<b>Cab Air</b> (36000006)..... <b>PA5359</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134 +</b>
<b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Steering</b> (1417927000)..... <b>PT23629</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
M2 106 w/Cummins ISC-280 (8.3L) Eng. (2007-12)	<b>Steering</b> (VML/T1808D)..... <b>BT9388</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
<b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b>	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>Fuel/Water Separator Spin-on</b> (w/Drain) (Alliance S3226FL01).... <b>BF1347</b>	<b>Diesel Exhaust Fluid</b> (2010 Emissions) (A0001420289)..... <b>PE5272</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Alliance S3226FL01)..... <b>BF1347-O</b>	<b>Diesel Exhaust Fluid</b> (2010 Emissions) (2888182)..... <b>PE17000</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (Alliance S3226FL01)..... <b>BF1373-SP</b>	M2 106 w/Cummins ISC-300 (8.3L) Eng. (2007-12)	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19763)..... <b>PF7928</b>	<b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b>	<b>Steering</b> (VML/T1808D)..... <b>BT9388</b>
<b>Some Fuel/Water Separator Spin-on</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b>	<b>Fuel/Water Separator Spin-on</b> (w/Drain) (Alliance S3226FL01).... <b>BF1347</b>	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (Alliance ABPN122BR90FRT10)..... <b>BF9871-O</b>	<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Alliance S3226FL01)..... <b>BF1347-O</b>	<b>Diesel Exhaust Fluid</b> (2010 Emissions) (A0001420289)..... <b>PE5272</b>
<b>Opt. Fuel/Water Separator Spin-on</b> (3800394)..... <b>BF1293-SPS</b>	<b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (Alliance S3226FL01)..... <b>BF1373-SP</b>	<b>Diesel Exhaust Fluid</b> (2010 Emissions) (2888182)..... <b>PE17000</b>
<b>Fuel</b> (Fleetguard FF5636)..... <b>BF7924</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19763)..... <b>PF7928</b>	M2 106 w/Cummins ISL 8.9 (8.9L) Eng. (2013-17)
<b>Channel Flow Air</b> (Std. Media) (Don. P607955)..... <b>CA4700 +</b>	<b>Some Fuel/Water Separator Spin-on</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b>	<b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b>
<b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960) <b>CA5420 +</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (Alliance ABPN122BR90FRT10)..... <b>BF9871-O</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19764)..... <b>PF9814</b>
<b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b>	<b>Opt. Fuel/Water Separator Spin-on</b> (3800394)..... <b>BF1293-SPS</b>	<b>Fuel/Water Separator Spin-on</b> (Alliance ABPN122-R50550)..... <b>BF9871-O</b>
<b>Cab Air</b> (36000006)..... <b>PA5359</b>	<b>Fuel</b> (Fleetguard FF5636)..... <b>BF7924</b>	<b>Fuel</b> (Fleetguard FF5636)..... <b>BF7924</b>
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Channel Flow Air</b> (Std. Media) (Don. P607955)..... <b>CA4700 +</b>	<b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b>
<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960) <b>CA5420 +</b>	<b>12 25/32 In. O.D. Channel Flow Air</b> (Don. P607955)..... <b>CA4700 +</b>
<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b>	<b>14 7/8 In. O.D. Channel Flow Air</b> (Fleetguard AF26424)..... <b>CA5368 +</b>
<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>
<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Air Dryer</b> (SS1200 Plus) (Wabco R950011)..... <b>BA5374 +</b>
<b>Coolant</b> (w/Chemical) (Fleetguard WF2071)..... <b>BW5071</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Air Dryer</b> (System Saver 1800) (Wabco R950068)..... <b>BA5379 +</b>
<b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134 +</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Coolant</b> (w/Chemical) (Fleetguard WF2071)..... <b>BW5071</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>		<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
		<b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>


+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
M2 106 w/Cummins ISL 8.9 (8.9L) Eng. (2013-17) (Cont'd) Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Steering (VML/T1808D)..... <b>BT9388</b> Steering (1417927000)..... <b>PT23629</b> Diesel Exhaust Fluid (5303604)..... <b>PE17000</b>	M2 106 w/Cummins ISL 8.9 (8.9L) Eng. (2020) (Cont'd) Channel Flow Secondary Air (Don. P616400)..... <b>PA4701</b> Cab Air (36000006)..... <b>PA5359</b> Air Dryer (Wabco R950011)..... <b>BA5374 +</b> Trans. Ele. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> Steering (1417927000)..... <b>PT23629</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	M2 106 w/Cummins ISL-300 Series (8.9L) Eng. (2013) (Cont'd) Trans. Ele. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Steering (VML/T1808D)..... <b>BT9388</b> Steering (1417927000)..... <b>PT23629</b> Diesel Exhaust Fluid (5303604)..... <b>PE17000</b>
M2 106 w/Cummins ISL 8.9 (8.9L) Eng. (2018) Lube (3937736)..... <b>B7177</b> Fuel/Water Separator (A0000904851)..... <b>PF46171</b> Fuel (Fleetguard FF63008)..... <b>BF63000</b> Channel Flow Primary Air (Standard Media) (Don. P607955)..... <b>CA4700</b> Channel Flow Primary Air (Flame Retardant Media) (Don. P607960) <b>CA5420</b> Channel Flow Secondary Air (Don. P616400)..... <b>PA4701</b> Cab Air (36000006)..... <b>PA5359</b> Air Dryer (Wabco R950068)..... <b>BA5379 +</b> Crankcase Breather (4936636)..... <b>CV15010</b> Trans. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Steering (1417927000)..... <b>PT23629</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b> Diesel Exhaust Fluid (4388378)..... <b>PE17002 KIT</b>	M2 106 w/Cummins ISL9 (9.0L) Eng. (2020) Lube (5444774)..... <b>B40142</b> Fuel (5303743)..... <b>BF63000</b> Primary Channel Flow Air (Don. P607955)..... <b>CA4700</b> Secondary Channel Flow Air (Don. P616400)..... <b>PA4701</b> Cab Air (36000006)..... <b>PA5359</b> Air Dryer (Wabco R950011)..... <b>BA5374</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Steering (1417927000)..... <b>PT23629</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	M2 106 w/Cummins L9 (9.0L) Eng. (2018) Lube (3937736)..... <b>B7177</b> Fuel/Water Separator (Racor R61709)..... <b>PF46235</b> Fuel (Fleetguard FF63008)..... <b>BF63000</b> Channel Flow Primary Air (Std. Media) (Don. P607955)..... <b>CA4700</b> Channel Flow Primary Air (Flame Retardant Media) (Don. P607960) <b>CA5420</b> Channel Flow Secondary Air (Don. P616400)..... <b>PA4701</b> Cab Air (36000006)..... <b>PA5359</b> Air Dryer (Desiccant) (Wabco R950011)..... <b>BA5374 +</b> Air Dryer (Coalescer) (Wabco R950068)..... <b>BA5379 +</b> Crankcase Breather (4936636)..... <b>CV15010</b> Coolant (Fleetguard WF2123)..... <b>B5090</b> Trans. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Steering (1417927000)..... <b>PT23629</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b> Diesel Exhaust Fluid (4388378)..... <b>PE17002 KIT</b>
M2 106 w/Cummins ISL9 (9.0L) Eng. (2019) Lube (3401544)..... <b>B40142</b> Fuel/Water Separator (Racor R61709)..... <b>PF46235</b> Fuel (5303743)..... <b>BF63000</b> Channel Flow Primary Air (Don. P607955)..... <b>CA4700 +</b> Channel Flow Secondary Air (Don. P616400)..... <b>PA4701</b> Cab Air (Alliance ABPN10G36000006)..... <b>PA5359</b> Air Dryer (Wabco R950011)..... <b>BA5374 +</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Steering (1417927000)..... <b>PT23629</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	M2 106 w/Cummins ISL-300 Series (8.9L) Eng. (2013) Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309 +</b> Fuel/Water Separator Ele. (Fleetguard FS19764)..... <b>PF9814</b> Fuel/Water Separator Spin-on (Alliance ABP/N122-R50550)..... <b>BF9871-O</b> Fuel (Fleetguard FF5636)..... <b>BF7924</b> Fuel (Fleetguard FF63009)..... <b>BF63000</b> 12 25/32 In. O.D. Channel Flow Air (Don. P607955)..... <b>CA4700 +</b> 14 7/8 In. O.D. Channel Flow Air (Fleetguard AF26424)..... <b>CA5368 +</b> Cab Air (36000006)..... <b>PA5359</b> Air Dryer (SS1200 Plus) (Wabco R950011)..... <b>BA5374 +</b> Air Dryer (System Saver 1800) (Wabco R950068)..... <b>BA5379 +</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>	M2 106 w/Cummins L9 (9.0L) Eng. (2019) Lube (3401544)..... <b>B40142</b> Fuel/Water Separator (Racor R61709)..... <b>PF46235</b> Fuel (5303743)..... <b>BF63000</b> Channel Flow Primary Air (Don. P607955)..... <b>CA4700 +</b> Channel Flow Secondary Air (Don. P616400)..... <b>PA4701</b> Cab Air (Alliance ABPN10G36000006)..... <b>PA5359</b> Air Dryer (Wabco R950011)..... <b>BA5374 +</b> Coolant (Fleetguard WF2123)..... <b>B5090</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Steering (1417927000)..... <b>PT23629</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>
M2 106 w/Cummins ISL 8.9 (8.9L) Eng. (2020) Lube (5444774)..... <b>B40142</b> Fuel (5303743)..... <b>BF63000</b> Fuel (5660774)..... <b>BF63000</b> Channel Flow Primary Air (Don. P607955)..... <b>CA4700</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
M2 106 w/Cummins L9 (9.0L) Eng. (2020)	M2 106 w/Detroit DD5 (5.1L) Eng. (2017-18)	M2 106 w/Detroit DD5 (5.1L) Eng. (2020)
Lube (5444774)..... <b>B40142</b>	Lube (A9341801410)..... <b>P40017</b>	(Cont'd)
Fuel/Water Separator (Racor R61709)..... <b>PF46235</b>	Fuel/Water Separator (Racor R61709)..... <b>PF46235</b>	Primary Channel Flow Air (Don. P607955)..... <b>CA4700</b>
Fuel (5303743)..... <b>BF63000</b>	Channel Flow Primary Air (Standard Media) (Don. P607955)..... <b>CA4700</b>	Secondary Channel Flow Air (Don. P616400)..... <b>PA4701</b>
Channel Flow Primary Air (Don. P607955)..... <b>CA4700</b>	Channel Flow Primary Air (Flame Retardant Media) (Don. P607960) <b>CA5420</b>	Cab Air (36000006)..... <b>PA5359</b>
Channel Flow Secondary Air (Don. P616400)..... <b>PA4701</b>	Channel Flow Secondary Air (Don. P616400)..... <b>PA4701</b>	Air Dryer (Wabco R950011)..... <b>BA5374 +</b>
Cab Air (36000006)..... <b>PA5359</b>	Cab Air (36000006)..... <b>PA5359</b>	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
Air Dryer (Wabco R950011)..... <b>BA5374 +</b>	Air Dryer (Wabco R950068)..... <b>BA5379</b>	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
Coolant (Fleetguard WF2123)..... <b>B5090</b>	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
Trans. Ele. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>
Steering (1417927000)..... <b>PT23629</b>	Steering (1417927000)..... <b>PT23629</b>	Steering (1417927000)..... <b>PT23629</b>
Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>
M2 106 w/Cummins L9 (9.0L) Eng. (2021)	M2 106 w/Detroit DD5 (5.1L) Eng. (2019)	M2 106 w/Detroit DD5 (5.1L) Eng. (2021)
Lube (5444774)..... <b>B40142</b>	Lube (A9341801410)..... <b>P40017</b>	Lube (A9341800009)..... <b>P40017</b>
Fuel/Water Separator (A0000904851)..... <b>PF46171</b>	Fuel/Water Separator (Racor R61709)..... <b>PF46235</b>	Primary Channel Flow Air (Don. P607955)..... <b>CA4700</b>
Fuel (5303743)..... <b>BF63000</b>	Channel Flow Primary Air (Don. P607955)..... <b>CA4700 +</b>	Secondary Channel Flow Air (Don. P616400)..... <b>PA4701</b>
Channel Flow Primary Air (Don. P607955)..... <b>CA4700</b>	Channel Flow Secondary Air (Don. P616400)..... <b>PA4701</b>	Cab Air (ABPN10G36000006)..... <b>PA5359</b>
Channel Flow Secondary Air (Don. P616400)..... <b>PA4701</b>	Cab Air (Alliance ABPN10G36000006)..... <b>PA5359</b>	Air Dryer (Bendix 107796PG)..... <b>BA5377</b>
Cab Air (ABPN10G36000006)..... <b>PA5359</b>	Air Dryer (Wabco R950011)..... <b>BA5374 +</b>	Air Dryer (Bendix 107796PG)..... <b>BA5377</b>
Air Dryer (Bendix 107796PG)..... <b>BA5377</b>	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	Pan-Type Trans. (S. Pan, w/o Gskt.) (Allison 29537965)..... <b>20016</b>
Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	Pan-Type Trans. (D. Pan, w/o Gskt.) (Allison 29537966)..... <b>20003</b>
Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	Pan-Type Trans. (D. Pan, w/Gskt.) (Allison 29537966)..... <b>20017</b>
Steering (1417927000)..... <b>PT23629</b>	Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>	Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>
Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	Steering (1417927000)..... <b>PT23629</b>	Steering (1417927000)..... <b>PT23629</b>
M2 106 w/Cummins L9 (9.0L) Eng. (2022)	Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>
Lube (5520789)..... <b>B40142</b>	Diesel Exhaust Fluid (A0001421089)..... <b>PE17002 KIT</b>	M2 106 w/Detroit DD5 (5.1L) Eng. (2022)
Channel Flow Air (Don. P607955)..... <b>CA4700</b>	M2 106 w/Detroit DD5 (5.1L) Eng. (2020)	Lube (A9341801410)..... <b>P40017</b>
Cab Air (ABPN10G36000006)..... <b>PA5359</b>	Lube (A9341801410)..... <b>P40017</b>	Fuel/Water Separator (A0000904851)..... <b>PF46171</b>
Coalescer Air Dryer (Bendix 5008414PG)..... <b>BA5379</b>	Fuel/Water Separator (A0000904851)..... <b>PF46171</b>	Channel Flow Air (Don. P607955)..... <b>CA4700</b>
Desiccant Air Dryer (Wabco R950011)..... <b>BA5374</b>	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	Cab Air (ABPN10G36000006)..... <b>PA5359</b>
Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	Coalescer Air Dryer (Bendix 5008414PG)..... <b>BA5379</b>
Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	Pan-Type Trans. (S. Pan, w/o Gskt.) (Allison 29537965)..... <b>20004</b>	Desiccant Air Dryer (Wabco R950011)..... <b>BA5374</b>
Steering (1417927000)..... <b>PT23629</b>	Pan-Type Trans. (S. Pan, w/Gskt.) (Allison 29537965)..... <b>20016</b>	Pan-Type Trans. (S. Pan, w/o Gskt.) (Allison 29537965)..... <b>20004</b>
M2 106 w/Cummins L9 (9.0L) Eng. (2023)		Pan-Type Trans. (S. Pan, w/Gskt.) (Allison 29537965)..... <b>20016</b>
Lube (5520789)..... <b>B40142</b>		
Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>		
Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>		
Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
M2 106 w/Detroit DD5 (5.1L) Eng. (2022) (Cont'd)	M2 106 w/Detroit DD8 (7.7L) Eng. (2019)	M2 106 w/Detroit DD8 (7.7L) Eng. (2020) (Cont'd)
<b>Pan-Type Trans.</b> (D. Pan, w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Fuel/Water Separator</b> (Racor R61709)..... <b>PF46235</b>	<b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b>
<b>Pan-Type Trans.</b> (D. Pan, w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Fuel/Water Separator</b> (A0000904851)..... <b>PF46171</b>	M2 106 w/Detroit DD8 (7.7L) Eng. (2021)
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Channel Flow Primary Air</b> (Don. P607955)..... <b>CA4700 +</b>	<b>Primary Channel Flow Air</b> (Don. P607955)..... <b>CA4700</b>
<b>Steering</b> (1417927000)..... <b>PT23629</b>	<b>Channel Flow Secondary Air</b> (Don. P616400)..... <b>PA4701</b>	<b>Secondary Channel Flow Air</b> (Don. P616400)..... <b>PA4701</b>
M2 106 w/Detroit DD5 (5.1L) Eng. (2023)	<b>Cab Air</b> (Alliance ABPN10G36000006)..... <b>PA5359</b>	<b>Cab Air</b> (ABPN10G36000006)..... <b>PA5359</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b>	<b>Air Dryer</b> (Bendix 107796PG)..... <b>BA5377</b>
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Crankcase Breather</b> (N/S)..... <b>N/S</b>	<b>Pan-Type Trans.</b> (S. Pan, w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Pan-Type Trans.</b> (S. Pan, w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Pan-Type Trans.</b> (D. Pan, w/o Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Pan-Type Trans.</b> (D. Pan, w/Gskt.) (Allison 29537966)..... <b>20017</b>
<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
M2 106 w/Detroit DD8 (7.7L) Eng. (2018)	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>
<b>Fuel/Water Separator</b> (Racor R61709)..... <b>PF46235</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>
<b>Fuel/Water Separator</b> (A0000904851)..... <b>PF46171</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	<b>Steering</b> (1417927000)..... <b>PT23629</b>
<b>Primary Channel Flow Air</b> (Standard Media) (Don. P607955)..... <b>CA4700</b>	<b>Steering</b> (1417927000)..... <b>PT23629</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
<b>Primary Channel Flow Air</b> (Flame Retardant Media) (Don. P607960)..... <b>CA5420</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	<b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b>
<b>Secondary Channel Flow Air</b> (Don. P616400)..... <b>PA4701</b>	M2 106 w/Detroit DD8 (7.7L) Eng. (2020)	M2 106 w/Detroit DD8 (7.7L) Eng. (2022)
<b>Cab Air</b> (36000006)..... <b>PA5359</b>	<b>Fuel/Water Separator</b> (Racor R61709)..... <b>PF46235</b>	<b>Fuel/Water Separator</b> (R61709)..... <b>PF46235</b>
<b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b>	<b>Channel Flow Primary Air</b> (Don. P607955)..... <b>CA4700</b>	<b>Channel Flow Air</b> (Don. P607955)..... <b>CA4700</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Channel Flow Secondary Air</b> (Don. P616400)..... <b>PA4701</b>	<b>Cab Air</b> (ABPN10G36000006)..... <b>PA5359</b>
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>	<b>Coalescer Air Dryer</b> (Bendix 5008414PG)..... <b>BA5379</b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b>	<b>Desiccant Air Dryer</b> (Wabco R950011)..... <b>BA5374</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Pan-Type Trans.</b> (S. Pan, w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Pan-Type Trans.</b> (S. Pan, w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Pan-Type Trans.</b> (D. Pan, w/o Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Pan-Type Trans.</b> (D. Pan, w/Gskt.) (Allison 29537966)..... <b>20017</b>
<b>Steering</b> (1417927000)..... <b>PT23629</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>
<b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>
	<b>Steering</b> (1417927000)..... <b>PT23629</b>	<b>Steering</b> (1417927000)..... <b>PT23629</b>
	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	M2 106 w/Detroit DD8 (7.7L) Eng. (2023)
		<b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>
		<b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>
		<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
M2 106 w/Detroit Diesel Series 55 (12.0L) Eng. (2004) <b>Lube</b> (23550401)..... <b>B7135</b> <b>P. Fuel</b> (23530707)..... <b>BF5810</b>	M2 106 w/Mercedes-Benz MBE906 (6.4L) Eng. (2002-17) (Cont'd) <b>Fuel/Water Separator</b> (Closed End) (S3226FL02Y)..... <b>BF1339-SP +</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (S3226FL02Y)..... <b>BF46083-O</b> <b>Fuel Ele.</b> (901551)..... <b>PF7735</b> <b>Fuel Screen</b> (901351)..... <b>PF7974 +</b> <b>Channel Flow Air</b> (Std. Media) (Don. P607955)..... <b>CA4700 +</b> <b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960) <b>CA5420 +</b> <b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b> <b>Radial Seal Air</b> (Don. P532966)... <b>RS3517</b> <b>Radial Seal XP Air</b> (Don. P532966)..... <b>RS3517XP</b> <b>Cab Air</b> (36000006)..... <b>PA5359</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b> <b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b> <b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29526899)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29526898)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (T1808D)..... <b>BT9388</b> <b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	M2 106 w/Mercedes-Benz MBE926 (7.2L) Eng. (2004-06) (Cont'd) <b>Cab Air</b> (36000006)..... <b>PA5359</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (T1808D)..... <b>BT9388</b> <b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>
M2 106 w/Detroit Diesel Series 60 (14.0L) Eng. (2006) <b>Lube</b> (23530573)..... <b>[2] B495</b> <b>Fuel/Water Separator</b> (w/Drain) (23535985)..... <b>BF5813 +</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (23535985)..... <b>BF5813-O +</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b> <b>Coolant</b> (23516489)..... <b>BW5200</b>	M2 106 w/Mercedes-Benz MBE904 (4.3L) Eng. (2004-07) <b>F-F Lube Ele.</b> (1801609)..... <b>P7199</b> <b>Opt. B-P Lube Spinner</b> (A9061810086)..... <b>BC7326 +</b> <b>Fuel/Water Separator</b> (Alliance ABP/N122-S3226FL02)..... <b>BF9898-O</b> <b>Pre-Fuel</b> (A0000901351)..... <b>PF7974 +</b> <b>P. Fuel</b> (902051)..... <b>PF7939 +</b> <b>S. Fuel</b> (901551)..... <b>PF7735</b> <b>Channel Flow Air</b> (Std. Media) (Don. P607955)..... <b>CA4700 +</b> <b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960) <b>CA5420 +</b> <b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b> <b>Cab Air</b> (36000006)..... <b>PA5359</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29526899)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29526898)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (T1808D)..... <b>BT9388</b> <b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	M2 106 w/Mercedes-Benz MBE4000 (12.8L) Eng. (2004-07) <b>Lube</b> (A0001802909)..... <b>P7230</b> <b>3 3/4 In. O.D. Fuel/Water Separator Ele.</b> (Fleetguard FS19624)..... <b>PF7748</b> <b>4 3/16 In. O.D. Fuel/Water Separator Ele.</b> (Fleetguard FS19763)..... <b>PF7928</b> <b>Fuel/Water Separator Spin-on</b> (Alliance S3226FL02)..... <b>BF1346-SP +</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain and SP) (S3226FL02Y).. <b>BF1339-SP +</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (S3226FL02Y)..... <b>BF46083-O</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (Alliance ABP/N122BR90FRT-10)..... <b>BF9871-O</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Alliance BR90FRT30)..... <b>BF46016-O</b> <b>Fuel</b> (5410900151)..... <b>PF7761</b> <b>12 25/32 In. O.D. Channel Flow Air</b> (Std. Media) (Don. P548070).. <b>CA4700 +</b> <b>11 21/32 In. O.D. Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960)..... <b>CA5420 +</b> <b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b> <b>14 7/8 In. O.D. Channel Flow Air</b> (Std. Media) (Don. P607965)..... <b>CA5368 +</b> <b>14 7/8 In. O.D. Channel Flow Air</b> (w/Flame Retardant Media) (Don. P605960)..... <b>CA5419 +</b>
M2 106 w/Mercedes-Benz MBE906 (6.4L) Eng. (2002-17) <b>F-F Lube Ele.</b> (1801709)..... <b>P7188</b> <b>Opt. B-P Lube Spinner</b> (A9061810086)..... <b>BC7326 +</b>	M2 106 w/Mercedes-Benz MBE926 (7.2L) Eng. (2004-06) <b>F-F Lube Ele.</b> (1801709)..... <b>P7188</b> <b>Opt. B-P Lube Spinner</b> (A9061810086)..... <b>BC7326 +</b> <b>Screen Fuel</b> (901351)..... <b>PF7974 +</b> <b>4 In. Fuel</b> (901551)..... <b>PF7735</b> <b>8 In. Fuel</b> (5410900151)..... <b>PF7761</b> <b>Channel Flow Air</b> (Std. Media) (Don. P607955)..... <b>CA4700 +</b> <b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960) <b>CA5420 +</b> <b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>	<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>	<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>
M2 106 w/Mercedes-Benz MBE4000 (12.8L) Eng. (2004-07) (Cont'd)	M2 112 w/Cat C9 (8.8L) Eng. (2004-07) (Cont'd)	M2 112 w/Cat C11 (11.1L) Eng. (2004-07) (Cont'd)
<b>Cab Air</b> (36000006)..... <b>PA5359</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>
<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>	<b>Coolant</b> (9N6123)..... <b>BW5139</b>
<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Coolant</b> (9N6123)..... <b>BW5139</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
<b>Roolant</b> (23524403)..... <b>B5134 +</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Steering Ele.</b> (Fleetguard 87904M)..... <b>PT9354-MPG</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Steering</b> (VML/T1808D)..... <b>BT9388</b>	<b>Steering Spin-on</b> (VML/T1808D)..... <b>BT9388</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	M2 112 w/Cat C11 (11.1L) Eng. (2004-07)	M2 112 w/Cat C13 (12.5L) Eng. (2004-10)
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Lube</b> (1R1808)..... <b>B7299 +</b>	<b>Lube</b> (1R1808)..... <b>B7299 +</b>
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Suction Line Fuel/Water Separator</b> BF1268	<b>Opt. Lube</b> (249-2347)..... <b>[2] B7402</b>
<b>Steering</b> (VML/T1808D)..... <b>BT9388</b>	<b>Fuel/Water Separator</b> (3 11/16 In. O.D.) (256-8753)..... <b>BF1259</b>	<b>Fuel/Water Separator</b> (w/Drain) (Alliance ABPS3226FL01)..... <b>BF1347</b>
<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Fuel/Water Separator</b> (4 9/32 In. O.D.)..... <b>BF1339-SP +</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (Alliance ABPS3226FL01)..... <b>BF1347-O</b>
M2 106 w/Mercedes-Benz OM906 (6.4L) Eng. (2008)	<b>Fuel/Water Separator</b> (4 5/16 In. O.D.) (Open End for Bowl) (BR90FRT10)..... <b>BF9871-O</b>	<b>Fuel/Water Separator</b> (w/Sensor Port) (Alliance ABPS3226FL01)..... <b>BF1373-SP</b>
<b>Lube</b> (A0001801609)..... <b>P7199</b>	<b>Fuel</b> (1R0749)..... <b>BF7587 +</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (Fleetguard FS19593)..... <b>BF1346-O</b>
<b>Fuel</b> (A9060920305)..... <b>PF7735</b>	<b>Channel Flow Air</b> (12 25/32 O.D.; Std. Media) (Don. P548070)..... <b>CA4700 +</b>	<b>Fuel/Water Separator</b> (Alliance ABPN122R50418)..... <b>BF9898-O</b>
<b>Radial Seal Air</b> (Don. P532966)..... <b>RS3517</b>	<b>Channel Flow Air</b> (11 21/32 In. O.D.; Flame Retardant Media) (Don. P607960)..... <b>CA5420 +</b>	<b>Fuel/Water Separator</b> (w/Sensor Port) (Fleetguard FS19593)..... <b>BF1346-SP</b>
<b>Radial Seal XP Air</b> (Don. P532966)..... <b>RS3517XP</b>	<b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b>	<b>Fuel/Water Separator</b> (w/Drain) (Fleetguard FS19593)..... <b>BF1346</b>
M2 112 w/Cat C9 (8.8L) Eng. (2004-07)	<b>Channel Flow Air</b> (14 7/8 In. O.D.; Std. Media) (Don. P607965)..... <b>CA5368 +</b>	<b>Fuel/Water Separator</b> (256-8753)..... <b>BF1259</b>
<b>Lube</b> (1R1808)..... <b>B7299 +</b>	<b>Channel Flow Air</b> (14 7/8 In. O.D.; Flame Retardant Media) (Don. P605960)..... <b>CA5419 +</b>	<b>Fuel/Water Separator</b> (Racor BR90FRT10)..... <b>BF9871-O</b>
<b>7 3/8 In. Fuel/Water Separator</b> (175-2949)..... <b>BF1268</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>	<b>Fuel/Water Separator</b> (1752949)..... <b>BF1268</b>
<b>8 9/32 In. Fuel/Water Separator</b> (S3226FL02)..... <b>BF1346-SP +</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Fuel</b> (1R0749)..... <b>BF7587 +</b>
<b>Fuel/Water Separator</b> (Alliance ABPN122R50551)..... <b>BF46016-O</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Channel Flow Air</b> (12 25/32 O.D.; Std. Media) (Don. P548070)..... <b>CA4700 +</b>
<b>Fuel</b> (1R0751)..... <b>BF7632</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Channel Flow Air</b> (11 21/32 In. O.D.; Flame Retardant Media) (Don. P607960)..... <b>CA5420 +</b>
<b>Channel Flow Air</b> (Std. Media) (Don. P607955)..... <b>CA4700 +</b>		<b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b>
<b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960)..... <b>CA5420 +</b>		
<b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b>		
<b>Cab Air</b> (36000006)..... <b>PA5359</b>		
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
M2 112 w/Cat C13 (12.5L) Eng. (2004-10) (Cont'd)	M2 112 w/Cummins ISC 8.3 (8.3L) Eng. (2013) (Cont'd)	M2 112 w/Cummins ISL 8.9 (8.9L) Eng. (2012-17) (Cont'd)
<b>Channel Flow Air</b> (14 7/8 In. O.D.; Std. Media) (Don. P607965) <b>CA5368 +</b>	<b>Channel Flow Air</b> (Std. Media) (Don. P607955)..... <b>CA4700 +</b>	<b>14 7/8 In. O.D. Channel Flow Air</b> (Fleetguard AF26424)..... <b>CA5368 +</b>
<b>Channel Flow Air</b> (14 7/8 In. O.D.; Flame Retardant Media) (Don. P605960)..... <b>CA5419 +</b>	<b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960) <b>CA5420 +</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>
<b>Cab Air</b> (36000006)..... <b>PA5359</b>	<b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b>	<b>Air Dryer</b> (SS1200 Plus) (Wabco R950011)..... <b>BA5374 +</b>
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>	<b>Air Dryer</b> (System Saver 1800) (Wabco R950068)..... <b>BA5379 +</b>
<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Crankcase Breather</b> (2007-on) (296-8325)..... <b>CV15008</b>	<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
<b>Coolant</b> (Cummins 3315116)..... <b>BW5071</b>	<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Coolant</b> (w/Chemical) (Fleetguard WF2071)..... <b>BW5071</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134 +</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Steering</b> (VML/T1808D)..... <b>BT9388</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Steering</b> (1417927000)..... <b>PT23629</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	M2 112 w/Cummins ISL 8.9 (8.9L) Eng. (2018)
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Lube</b> (3937736)..... <b>B7177</b>
<b>Steering</b> (VML/T1808D)..... <b>BT9388</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Fuel/Water Separator</b> (A0000904851)..... <b>PF46171</b>
<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Fuel</b> (Fleetguard FF63008)..... <b>BF63000</b>
M2 112 w/Cummins ISC 8.3 (8.3L) Eng. (2013)	<b>Steering</b> (VML/T1808D)..... <b>BT9388</b>	<b>Channel Flow Primary Air</b> (Standard Media) (Don. P607955)..... <b>CA4700</b>
<b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b>	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Channel Flow Primary Air</b> (Flame Retardant Media) (Don. P607960) <b>CA5420</b>
<b>Fuel/Water Separator Spin-on</b> (w/Drain) (Alliance S3226FL01).... <b>BF1347</b>	<b>Diesel Exhaust Fluid</b> (2010 Emissions) (A0001420289)..... <b>PE5272</b>	<b>Channel Flow Secondary Air</b> (Don. P616400)..... <b>PA4701</b>
<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Alliance S3226FL01)..... <b>BF1347-O</b>	<b>Diesel Exhaust Fluid</b> (2010 Emissions) (2888182)..... <b>PE17000</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>
<b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (Alliance S3226FL01)..... <b>BF1373-SP</b>	M2 112 w/Cummins ISL 8.9 (8.9L) Eng. (2012-17)	<b>Air Dryer</b> (Wabco R950068)..... <b>BA5379 +</b>
<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19763)..... <b>PF7928</b>	<b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b>	<b>Crankcase Breather</b> (4936636).... <b>CV15010</b>
<b>Some Fuel/Water Separator Spin-on</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19764)..... <b>PF9814</b>	<b>Trans.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (Alliance ABPN122BR90FRT10)..... <b>BF9871-O</b>	<b>Fuel/Water Separator Spin-on</b> (Alliance ABP/N122-R50550)..... <b>BF9871-O</b>	<b>Trans.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>
<b>Opt. Fuel/Water Separator Spin-on</b> (3800394)..... <b>BF1293-SPS</b>	<b>Fuel</b> (Fleetguard FF5636)..... <b>BF7924</b>	<b>Steering</b> (1417927000)..... <b>PT23629</b>
<b>Fuel</b> (Fleetguard FF5636)..... <b>BF7924</b>	<b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
	<b>12 25/32 In. O.D. Channel Flow Air</b> (Don. P607955)..... <b>CA4700 +</b>	<b>Diesel Exhaust Fluid</b> (4388378).. <b>PE17002 KIT</b>
		M2 112 w/Cummins ISL9 (9.0L) Eng. (2019)
		<b>Lube</b> (3401544)..... <b>B40142</b>
		<b>Fuel/Water Separator</b> (Racor R61709)..... <b>PF46235</b>
		<b>Fuel/Water Separator</b> (Fleetguard FS20081)..... <b>PF46171</b>
		<b>Fuel</b> (5303743)..... <b>BF63000</b>
		<b>Fuel</b> (5660774)..... <b>BF63000</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>	<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>	<b>FREIGHTLINER Trucks &amp; Buses (cont'd)</b>
M2 112 w/Cummins ISL9 (9.0L) Eng. (2019) (Cont'd) <b>Channel Flow Air</b> (Don. P605960)..... <b>CA5419 +</b> <b>Cab Air</b> (ABPN10G36000006)..... <b>PA5359</b> <b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	M2 112 w/Cummins ISL-G (8.9L) Eng. (2010-18) (Cont'd) <b>Cab Air</b> (36000006)..... <b>PA5359</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Air Dryer</b> (Wabco R950068)..... <b>BA5379 +</b> <b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b> <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (VMLT1808D)..... <b>BT9388</b> <b>Some Rear Axle</b> (Meritor 3280-V-8394)..... <b>B233</b>	M2 112 w/Cummins L9 (9.0L) Eng. (2019) (Cont'd) <b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
M2 112 w/Cummins ISL-300 Series (8.9L) Eng. (2013) <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19764)..... <b>PF9814</b> <b>Fuel/Water Separator Spin-on</b> (Alliance ABP/N122-R50550)..... <b>BF9871-O</b> <b>Fuel</b> (Fleetguard FF5636)..... <b>BF7924</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> <b>12 25/32 In. O.D. Channel Flow Air</b> (Don. P607955)..... <b>CA4700 +</b> <b>14 7/8 In. O.D. Channel Flow Air</b> (Fleetguard AF26424)..... <b>CA5368 +</b> <b>Cab Air</b> (36000006)..... <b>PA5359</b> <b>Air Dryer</b> (SS1200 Plus) (Wabco R950011)..... <b>BA5374 +</b> <b>Air Dryer</b> (System Saver 1800) (Wabco R950068)..... <b>BA5379 +</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (VMLT1808D)..... <b>BT9388</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Diesel Exhaust Fluid</b> (5303604)..... <b>PE17000</b>	M2 112 w/Cummins ISL-G (8.9L) Eng. (2019) <b>Channel Flow Primary Air</b> (Don. P607955)..... <b>CA4700</b> <b>Channel Flow Secondary Air</b> (Don. P616400)..... <b>PA4701</b> <b>Cab Air</b> (ABPN10G36000006)..... <b>PA5359</b> <b>Air Dryer</b> (Wabco R950011)..... <b>BA5374</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	M2 112 w/Cummins L9 (9.0L) Eng. (2020) <b>Lube</b> (5444774)..... <b>B40142</b> <b>Fuel/Water Separator</b> (FS20081)..... <b>PF46171</b> <b>Fuel/Water Separator</b> (Racor R61709)..... <b>PF46235</b> <b>Fuel</b> (5660774)..... <b>BF63000</b> <b>Channel Flow Air</b> (Don. P607965)..... <b>CA5368</b> <b>Cab Air</b> (36000006)..... <b>PA5359</b> <b>Air Dryer</b> (Wabco R950011)..... <b>BA5374</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (1417927000)..... <b>PT23629</b>
M2 112 w/Cummins L9 (9.0L) Eng. (2018) <b>Lube</b> (3401544)..... <b>B40142</b> <b>Fuel/Water Separator</b> (Racor R61709)..... <b>PF46235</b> <b>Fuel</b> (Fleetguard FF63008)..... <b>BF63000</b> <b>Channel Flow Primary Air</b> (Std. Media) (Don. P607955)..... <b>CA4700</b> <b>Channel Flow Primary Air</b> (Flame Retardant Media) (Don. P607960)..... <b>CA5420</b> <b>Channel Flow Secondary Air</b> (Don. P616400)..... <b>PA4701</b> <b>Cab Air</b> (36000006)..... <b>PA5359</b> <b>Air Dryer</b> (Desiccant) (Wabco R950011)..... <b>BA5374 +</b> <b>Air Dryer</b> (Coalescer) (Wabco R950068)..... <b>BA5379 +</b> <b>Crankcase Breather</b> (4936636)..... <b>CV15010</b> <b>Trans.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (4388378)..... <b>PE17002 KIT</b>	M2 112 w/Cummins L9 (9.0L) Eng. (2021) <b>Lube</b> (5444774)..... <b>B40142</b> <b>Fuel/Water Separator</b> (A0000904851)..... <b>PF46171</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Channel Flow Primary Air</b> (Don. P607965)..... <b>CA5368</b> <b>Channel Flow Secondary Air</b> (Don. P616400)..... <b>PA4701</b> <b>Cab Air</b> (ABPN10G36000006)..... <b>PA5359</b> <b>Air Dryer</b> (Bendix 107796PG)..... <b>BA5377</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	M2 112 w/Cummins L9 (9.0L) Eng. (2022) <b>Lube</b> (5520789)..... <b>B40142</b> <b>Coalescer Air Dryer</b> (Bendix 5008414PG)..... <b>BA5379</b> <b>Desiccant Air Dryer</b> (Wabco R950011)..... <b>BA5374</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (1417927000)..... <b>PT23629</b>
M2 112 w/Cummins ISL-G (8.9L) Eng. (2010-18) <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel</b> (Fleetguard NG5900)..... <b>BF7695</b> <b>Channel Flow Air</b> (Don. P607965)..... <b>CA5368 +</b>	M2 112 w/Cummins L9 (9.0L) Eng. (2019) <b>Lube</b> (3401544)..... <b>B40142</b> <b>Fuel/Water Separator</b> (Racor R61709)..... <b>PF46235</b> <b>Fuel/Water Separator</b> (Fleetguard FS20081)..... <b>PF46171</b> <b>Fuel</b> (5660774)..... <b>BF63000</b> <b>Channel Flow Air</b> (Don. P605960)..... <b>CA5419 +</b> <b>Cab Air</b> (ABPN10G36000006)..... <b>PA5359</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
M2 112 w/Cummins L9 (9.0L) Eng. (2023) Lube (5520789)..... <b>B40142</b>	M2 112 w/Detroit DD13 (12.8L) Eng. (2011-18) (Cont'd)	M2 112 w/Detroit DD13 (12.8L) Eng. (2019) (Cont'd)
M2 112 w/Cummins L9N (8.9L) Eng. (2019) Lube (3401544)..... <b>B40142</b>	<b>11 21/32 In. O.D. Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960)..... <b>CA5420 +</b>	<b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b>
<b>Fuel/Water Separator</b> (Fleetguard NG5900)..... <b>BF7695</b>	<b>12 25/32 In. O.D. Channel Flow Air</b> (Std. Media) (Don. P548070)..... <b>CA4700 +</b>	M2 112 w/Detroit DD13 (12.8L) Eng. (2020) Lube (To Eng. S/N A472910S0690710) (A4731800409)..... <b>P7505</b>
<b>Channel Flow Air</b> (Don. P607955)..... <b>CA4700</b>	<b>14 7/8 In. O.D. Channel Flow Air</b> (Std. Media) (Don. P607965)..... <b>CA5368 +</b>	<b>Fuel/Water Separator</b> (A0000905051)..... <b>PF46145</b>
<b>Cab Air</b> (VCC36000006)..... <b>PA5359</b>	<b>Channel Flow Secondary Air</b> (Don. P616400)..... <b>PA4701</b>	<b>Fuel</b> (A4700903151)..... <b>PF9908 KIT</b>
<b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>	<b>Channel Flow Air</b> (Don. P607965)..... <b>CA5368</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Cab Air</b> (36000006)..... <b>PA5359</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Air Dryer</b> (Wabco R950011)..... <b>BA5374</b>
<b>Steering</b> (1417927000)..... <b>PT23629</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Steering</b> (1417927000)..... <b>PT23629</b>
<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	<b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b>	<b>Diesel Exhaust Fluid</b> (A0001420289)..... <b>PE5272</b>
M2 112 w/Cummins L9N (8.9L) Eng. (2020) Lube (3401544)..... <b>B40142</b>	<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>	M2 112 w/Detroit DD13 (12.8L) Eng. (2021) Lube (3401544)..... <b>B40142</b>
<b>Fuel</b> (3607140)..... <b>BF7695</b>	<b>Coolant</b> (A4722030255)..... <b>P5092</b>	<b>Fuel/Water Separator</b> (A0000905051)..... <b>PF46145</b>
<b>Channel Flow Air</b> (Don. P607965)..... <b>CA5368</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Fuel</b> (A4700903151)..... <b>PF9908 KIT</b>
<b>Cab Air</b> (36000006)..... <b>PA5359</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Channel Flow Primary Air</b> (Don. P607965)..... <b>CA5368</b>
<b>Air Dryer</b> (Wabco R950011)..... <b>BA5374</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Channel Flow Secondary Air</b> (Don. P616400)..... <b>PA4701</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Cab Air</b> (ABPN10G36000006)..... <b>PA5359</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Air Dryer</b> (Bendix 107796PG)..... <b>BA5377</b>
<b>Steering</b> (1417927000)..... <b>PT23629</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2</b>
M2 112 w/Cummins L9N (8.9L) Eng. (2021) Lube (Fleetguard LF14002NN)..... <b>B40142</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Steering</b> (1417927000)..... <b>PT23629</b>
<b>Fuel</b> (Fleetguard NG5900)..... <b>BF7695</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
<b>Channel Flow Primary Air</b> (Don. P607965)..... <b>CA5368</b>	<b>Steering</b> (T1808D)..... <b>BT9388</b>	<b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b>
<b>Channel Flow Secondary Air</b> (Don. P616400)..... <b>PA4701</b>	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	M2 112 w/Detroit DD13 (12.8L) Eng. (2022) Lube (A4731800409)..... <b>P7505</b>
<b>Cab Air</b> (ABPN10G36000006)..... <b>PA5359</b>	<b>Diesel Exhaust Fluid</b> (2010 Emissions) (A0001420289)..... <b>PE5272</b>	<b>Fuel</b> (A4720900651)..... <b>PF9908 KIT</b>
<b>Air Dryer</b> (Bendix 107794)..... <b>BA5377</b>	M2 112 w/Detroit DD13 (12.8L) Eng. (2019) Lube (A4731800409)..... <b>P7505</b>	<b>Channel Flow Air</b> (Don. P607955)..... <b>CA4700</b>
<b>Steering</b> (1417927000)..... <b>PT23629</b>	<b>Fuel</b> (A4720900651)..... <b>PF9908 KIT</b>	<b>Coalescer Air Dryer</b> (Bendix 5008414PG)..... <b>BA5379</b>
<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	<b>Channel Flow Air</b> (Don. P605960)..... <b>CA5419 +</b>	<b>Desiccant Air Dryer</b> (Wabco R950011)..... <b>BA5374</b>
M2 112 w/Cummins L9N (8.9L) Eng. (2022) Channel Flow Air (Don. P607955)..... <b>CA4700</b>	<b>Cab Air</b> (ABPN10G36000006)..... <b>PA5359</b>	<b>Steering</b> (1417927000)..... <b>PT23629</b>
<b>Coalescer Air Dryer</b> (Bendix 5008414PG)..... <b>BA5379</b>	<b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b>	M2 112 w/Detroit DD13 (12.8L) Eng. (2011-18) Lube (A4731800109)..... <b>P7505</b>
<b>Desiccant Air Dryer</b> (Wabco R950011)..... <b>BA5374</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	<b>Opt. Fuel/Water Separator</b> (Davco 482) (A0000903651)..... <b>PF9804</b>
<b>Steering</b> (1417927000)..... <b>PT23629</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	<b>Fuel Kit</b> (2 Filter Kit) (A4720900451)..... <b>PF9908 KIT</b>
M2 112 w/Detroit DD13 (12.8L) Eng. (2011-18) Lube (A4731800109)..... <b>P7505</b>	<b>Steering</b> (1417927000)..... <b>PT23629</b>	<b>Fuel Kit</b> (3 Filter Kit) (A0000904251)..... <b>PF9924 KIT</b>
<b>Opt. Fuel/Water Separator</b> (Davco 482) (A0000903651)..... <b>PF9804</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	
<b>Fuel Kit</b> (2 Filter Kit) (A4720900451)..... <b>PF9908 KIT</b>		
<b>Fuel Kit</b> (3 Filter Kit) (A0000904251)..... <b>PF9924 KIT</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
<b>M2 112 w/Mercedes-Benz MBE4000 (12.8L Eng. (2003-13) (Cont'd)</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (S3226FL02Y)..... <b>BF46083-O</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (Alliance ABP/N122BR90FRT-10)..... <b>BF9871-O</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Alliance BR90FRT30)..... <b>BF46016-O</b> <b>Fuel</b> (5410900151)..... <b>PF7761</b> <b>12 25/32 In. O.D. Channel Flow Air</b> (Std. Media) (Don. P548070).. <b>CA4700 +</b> <b>11 21/32 In. O.D. Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960)..... <b>CA5420 +</b> <b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b> <b>14 7/8 In. O.D. Channel Flow Air</b> (Std. Media) (Don. P607965)..... <b>CA5368 +</b> <b>14 7/8 In. O.D. Channel Flow Air</b> (w/Flame Retardant Media) (Don. P605960)..... <b>CA5419 +</b> <b>Cab Air</b> (360000006)..... <b>PA5359</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b> <b>Air Dryer</b> (SS1200 Plus) (Wabco R950068)..... <b>BA5379 +</b> <b>Coolant</b> (23524403)..... <b>B5134 +</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (VMLT1808D)..... <b>BT9388</b> <b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>MB60 w/Mercedes-Benz OM366LA (6.0L) Eng.</b> <b>Lube Ele.</b> (4011840025)..... <b>P242</b> <b>Fuel Ele.</b> (926901)..... <b>[2] PF834</b> <b>Radial Seal O. Air</b> (Don. P526678)..... <b>RS3520</b> <b>Radial Seal I. Air</b> (Don. P529548)..... <b>RS3521</b> <hr/> <b>MB70 w/Mercedes-Benz OM366LA (6.0L) Eng.</b> <b>Lube Ele.</b> (4011840025)..... <b>P242</b> <b>Fuel Ele.</b> (926901)..... <b>[2] PF834</b> <b>Radial Seal O. Air</b> (Don. P526678)..... <b>RS3520</b> <b>Radial Seal I. Air</b> (Don. P529548)..... <b>RS3521</b> <hr/> <b>MB80 w/Cat 3126B Eng.</b> <b>Lube</b> (To 1/2004 (Std. Version)) (1R0739)..... <b>B76 +</b> <b>Lube</b> (1/2004-on) (1R1807)..... <b>B7700 +</b> <b>Lube</b> (To 1/2004 (Severe Service)) (1R0739)..... <b>B76-SS +</b> <b>Fuel/Water Separator</b> (175-2949)..... <b>BF1268</b> <b>Fuel/Water Separator</b> (256-8753)..... <b>BF1259</b> <b>Fuel</b> (1R0751)..... <b>BF7632</b> <b>Radial Seal O. Air</b> (Don. P526678)..... <b>RS3520</b> <b>Radial Seal I. Air</b> (Don. P529548)..... <b>RS3521</b> <hr/> <b>MB80 w/Mercedes-Benz OM366LA Eng.</b> <b>Fuel</b> (3900920001)..... <b>BF970 +</b> <b>Radial Seal Air</b> (Don. P526678)..... <b>RS3520</b> <hr/> <b>MT35 w/Cummins 4BT3.9 (3.9L) Eng.</b> <b>Lube</b> (3908616)..... <b>BT427 +</b> <b>Fuel/Water Separator</b> (13/16-18 Thd.) (3903410)..... <b>BF1280 +</b> <b>Fuel/Water Separator</b> (M16 x 1.5 Thd.) (3903202)..... <b>BF1226</b> <b>Fuel</b> (3903640)..... <b>BF788</b> <b>Disposable Air Hsg.</b> (Farr 114880005)..... <b>PA4655</b> <hr/> <b>MT35 w/Cummins ISB (3.9L) Eng.</b> <b>Lube</b> (4897898)..... <b>BT7237</b> <b>Fuel/Water Separator</b> (Racor R45FRT01)..... <b>BF9912-O</b> <b>Fuel/Water Separator</b> (3903202)..... <b>BF1226</b> <b>Fuel/Water Separator</b> (3903410)..... <b>BF1280 +</b> <b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b> <b>Fuel</b> (4897833)..... <b>BF7813</b> <b>S. Fuel</b> (3903640)..... <b>BF788</b> <b>Disposable Air Hsg.</b> (Farr 114880005)..... <b>PA4655</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>MT35 w/Cummins ISB (3.9L) Eng. (Cont'd)</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Pan-Type</b> (3.8 In. Pan, AT Series Trans.) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan, AT Series Trans) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b> <hr/> <b>MT35 w/Cummins ISB (5.9L) Eng.</b> <b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b> <b>Fuel/Water Separator</b> (w/Drain) (Fleetguard FS1242)..... <b>BF1249</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (Fleetguard FS1242)..... <b>BF1249-O</b> <b>Fuel/Water Separator</b> (w/Drain & Sensor Port) (Fleetguard FS1242)..... <b>BF1249-SP</b> <b>Fuel/Water Separator</b> (w/Drain & Sensor Port, High Efficiency Version) (Fleetguard FS1242)..... <b>BF1393-SP</b> <b>Fuel/Water Separator</b> (Fleetguard FS1251)..... <b>BF1226</b> <b>Fuel</b> (Fleetguard FF5632)..... <b>BF7940</b> <b>Fuel</b> (Fleetguard FF5052)..... <b>BF788</b> <b>Disposable Air Hsg.</b> (Farr 114880005)..... <b>PA4655</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b> <hr/> <b>MT45 w/Cummins B5.9G (5.9L) CNG Eng.</b> <b>Lube</b> (3937743)..... <b>BT7349</b> <hr/> <b>MT45 w/Cummins B6.7 (6.7L) Eng. (2018)</b> <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel/Water Separator</b> (Racor R61709)..... <b>PF46235</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> <b>Fuel</b> (5660774)..... <b>BF63000</b> <b>Air</b> (Farr 94973004)..... <b>PA3891</b> <b>Crankcase Breather</b> (4936636)..... <b>CV15010</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Steering</b> (VMLT1808F)..... <b>BT9388</b> <b>Diesel Exhaust Fluid</b> (Fleetguard UF106)..... <b>PE17002 KIT</b>

+ See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
MT45 w/Cummins B6.7 (6.7L) Eng. (2019)	MT45 w/Cummins ISB 5.9 (5.9L) Eng. (Cont'd)	MT45 w/Cummins ISB 6.7 (6.7L) Eng. (2008-17) (Cont'd)
<b>Lube</b> (3937736)..... <b>B7177</b>	<b>Fuel/Water Separator Spin-on</b>	<b>Fuel</b> (2010 Emissions)
<b>Fuel/Water Separator</b> (Racor R61709)..... <b>PF46235</b>	(w/Sensor Port) (Racor S3226T)... <b>BF1373-SP</b>	(Fleetguard FF5632)..... <b>BF7940</b>
<b>Fuel</b> (5660774)..... <b>BF63000</b>	<b>Fuel/Water Separator Ele.</b>	<b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b>
<b>Air</b> (Farr 94973004)..... <b>PA3891</b>	(Fleetguard FS19624)..... <b>PF7748</b>	<b>Disposable Air Hsg.</b> (4 In. Inlet, Closed End) (Farr 114810007).... <b>PA3555</b>
<b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	<b>Fuel/Water Separator Ele.</b>	<b>Disposable Air Hsg.</b> (4 In. Inlet) (Farr 114880005)..... <b>PA4655</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	(3942470)..... <b>PF7777</b>	<b>Disposable Air Hsg.</b> (6 In. Inlet) (Farr 94973004)..... <b>PA3891</b>
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Fuel/Water Separator Spin-on</b>	<b>Crankcase Breather</b> (4936636)... <b>CV15010</b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	(Fleetguard FS19596)..... <b>BF1293-SPS</b>	<b>Trans. Pan-Type</b> (AT Series, 3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Fuel</b> (2010 Emissions)	<b>Trans. Pan-Type</b> (AT Series, 5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	(Fleetguard FF5632)..... <b>BF7940</b>	<b>Trans. Spin-on</b> (AT Series) (Allison 29510922)..... <b>BT8316-MPG</b>
<b>Steering</b> (1417927000)..... <b>PT23629</b>	<b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	<b>Disposable Air Hsg.</b> (4 In. Inlet, Closed End) (Farr 114810007).... <b>PA3555</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
MT45 w/Cummins B6.7 (6.7L) Eng. (2020)	<b>Disposable Air Hsg.</b> (4 In. Inlet) (Farr 114880005)..... <b>PA4655</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Lube</b> (3937736)..... <b>B7177</b>	<b>Disposable Air Hsg.</b> (6 In. Inlet) (Farr 94973004)..... <b>PA3891</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Fuel/Water Separator</b> (Racor R61709)..... <b>PF46235</b>	<b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Fuel</b> (5660774)..... <b>BF63000</b>	<b>Trans. Pan-Type</b> (AT Series, 3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
<b>Air</b> (Farr 94973004)..... <b>PA3891</b>	<b>Trans. Pan-Type</b> (AT Series, 5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	<b>Trans. Spin-on</b> (AT Series) (Allison 29510922)..... <b>BT8316-MPG</b>	<b>Steering</b> (VMLT1808F)..... <b>BT9388</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Diesel Exhaust Fluid</b> (2010 Emissions) (5303604)..... <b>PE17000</b>
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	MT45 w/Cummins ISB 6.7 (6.7L) Eng. (2018)
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Lube</b> (3937736)..... <b>B7177</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Fuel/Water Separator</b> (Racor R61709)..... <b>PF46235</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b>
<b>Steering</b> (1417927000)..... <b>PT23629</b>	<b>Steering</b> (T1808D)..... <b>BT9388</b>	<b>Air</b> (Farr 94973004)..... <b>PA3891</b>
MT45 w/Cummins B6.7 (6.7L) Eng. (2021)	<b>Diesel Exhaust Fluid</b> (2010 Emissions) (5303604)..... <b>PE17000</b>	<b>Crankcase Breather</b> (4936636)... <b>CV15010</b>
<b>Lube</b> (3937736)..... <b>B7177</b>	MT45 w/Cummins ISB 6.7 (6.7L) Eng. (2008-17)	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Fuel</b> (5303743)..... <b>BF63000</b>	<b>Lube</b> (3937144)..... <b>B7177</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	<b>Fuel/Water Separator Ele.</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
MT45 w/Cummins B6.7 (6.7L) Eng. (2022)	(Fleetguard FS19624)..... <b>PF7748</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
<b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b>	<b>Fuel/Water Separator Ele.</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>Fuel/Water Separator</b> (Racor R61709)..... <b>PF46235</b>	(3942470)..... <b>PF7777</b>	<b>Steering</b> (VMLT1808F)..... <b>BT9388</b>
<b>Air</b> (Racor 94973004)..... <b>PA3891</b>	<b>Fuel/Water Separator Spin-on</b>	MT45 w/Cummins ISB 6.7 (6.7L) Eng. (2019)
<b>Steering</b> (1417927000)..... <b>PT23629</b>	(w/Drain) (Racor S3226T)..... <b>BF1347</b>	<b>Lube</b> (3937736)..... <b>B7177</b>
MT45 w/Cummins ISB (3.9L) Eng.	<b>Fuel/Water Separator Spin-on</b>	<b>Fuel/Water Separator</b> (Racor R61709)..... <b>PF46235</b>
<b>Lube</b> (3942365)..... <b>B7177</b>	(Open End for Bowl) (Racor S3226T)..... <b>BF1347-O</b>	<b>Fuel</b> (5303743)..... <b>BF63000</b>
<b>Lube</b> (4897898)..... <b>BT7237</b>	<b>Fuel/Water Separator Spin-on</b>	<b>Air</b> (Farr 94973004)..... <b>PA3891</b>
<b>Fuel</b> (4897833)..... <b>BF7813</b>	(w/Sensor Port) (Racor S3226T)... <b>BF1373-SP</b>	<b>Crankcase Breather</b> (4936636)... <b>CV15010</b>
MT45 w/Cummins ISB 5.9 (5.9L) Eng.	<b>Fuel/Water Separator Spin-on</b>	<b>Pan-Type Trans.</b> (S. Pan, w/o Gskt.) (29537965)..... <b>20004</b>
<b>Lube</b> (3937144)..... <b>B7177</b>	(3942533)..... <b>BF1271</b>	
<b>Fuel/Water Separator Spin-on</b>	<b>Fuel/Water Separator Spin-on</b>	
(w/Drain) (Racor S3226T)..... <b>BF1347</b>	(Fleetguard FS19596)..... <b>BF1293-SPS</b>	
<b>Fuel/Water Separator Spin-on</b>		
(Open End for Bowl) (Racor S3226T)..... <b>BF1347-O</b>		

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
MT45 w/Cummins ISB 6.7 (6.7L) Eng. (2019) (Cont'd) <b>Pan-Type Trans.</b> (S. Pan, w/Gskt.) (29537965)..... <b>20016</b> <b>Pan-Type Trans.</b> (D. Pan, w/o Gskt.) (29537966)..... <b>20003</b> <b>Pan-Type Trans.</b> (D. Pan, w/Gskt.) (29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (29539579)..... <b>BT8460</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	MT45 w/Power Solutions International V8-365 (6.0L) Eng. (2018) (Cont'd) <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Steering</b> (VMLT1808F)..... <b>BT9388</b>	MT45 w/Mercedes-Benz MBE904 (4.3L) Eng. (Cont'd) <b>Disposable Air Hsg.</b> (Side Inlet) (Farr 114880005)..... <b>PA4655</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Pan-Type</b> (AT Series, 3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (AT Series, 5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (AT Series) (Allison 29510922)..... <b>BT8316-MPG</b> <b>Steering</b> (T1808D)..... <b>BT9388</b>
MT45 w/Cummins ISB 6.7 (6.7L) Eng. (2020) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel/Water Separator</b> (Racor R61709)..... <b>PF46235</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Fuel</b> (5660774)..... <b>BF63000</b> <b>Air</b> (Farr 94973004)..... <b>PA3891</b> <b>Crankcase Breather</b> (4936636)..... <b>CV15010</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Steering</b> (1417927000)..... <b>PT23629</b>	MT45 w/Power Solutions International V8-365 (6.0L) Eng. (2019) <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Channel Flow Air</b> (Don. P608666)..... <b>CA5514</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	MT55 w/Cummins B5.9 Natural Gas Eng. <b>Lube</b> (3937743)..... <b>BT7349</b>
MT45 w/Cummins ISB 6.7 (6.7L) Eng. (2020) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel/Water Separator</b> (Racor R61709)..... <b>PF46235</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Fuel</b> (5660774)..... <b>BF63000</b> <b>Air</b> (Farr 94973004)..... <b>PA3891</b> <b>Crankcase Breather</b> (4936636)..... <b>CV15010</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Steering</b> (1417927000)..... <b>PT23629</b>	MT45 w/Power Solutions International V8-365 (6.0L) Eng. (2020) <b>Lube</b> (ACDelco PF48)..... <b>B160</b> <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Channel Flow Air</b> (Don. P617499)..... <b>CA5514</b> <b>Steering</b> (1417927000)..... <b>PT23629</b>	MT55 w/Cummins B6.7 (6.7L) Eng. (2018) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel/Water Separator</b> (Racor R61709)..... <b>PF46235</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> <b>Air</b> (Farr 94973004)..... <b>PA3891</b> <b>Crankcase Breather</b> (4936636)..... <b>CV15010</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Steering</b> (VMLT1808F)..... <b>BT9388</b>
MT45 w/Cummins ISC 8.3 (8.3L) Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel</b> (Fleetguard FF5488)..... <b>BF7815</b> <b>Fuel</b> (Fleetguard FF5636)..... <b>BF7924</b>	MT45 w/Power Solutions International V8-365 (6.0L) Eng. (2021) <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	MT55 w/Cummins B6.7 (6.7L) Eng. (2019) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel/Water Separator</b> (Racor R61709)..... <b>PF46235</b> <b>Fuel</b> (5660774)..... <b>BF63000</b> <b>Air</b> (Farr 94973004)..... <b>PA3891</b> <b>Crankcase Breather</b> (4936636)..... <b>CV15010</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Steering</b> (VMLT1808F)..... <b>BT9388</b>
MT45 w/Detroit DD5 (5.1L) Eng. (2021) <b>Lube</b> (A9341800009)..... <b>P40017</b>	MT45 w/Power Solutions International V8-365 (6.0L) Eng. (2021) <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	MT55 w/Cummins B6.7 (6.7L) Eng. (2019) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel/Water Separator</b> (Racor R61709)..... <b>PF46235</b> <b>Fuel</b> (5660774)..... <b>BF63000</b> <b>Air</b> (Farr 94973004)..... <b>PA3891</b> <b>Crankcase Breather</b> (4936636)..... <b>CV15010</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Steering</b> (1417927000)..... <b>PT23629</b>
MT45 w/Detroit DD5 (5.1L) Eng. (2022) <b>Lube</b> (A9341801410)..... <b>P40017</b> <b>Air</b> (Racor 94973004)..... <b>PA3891</b>	MT45 w/Power Solutions International V8-365 (6.0L) Eng. (2018) <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Channel Flow Air</b> (Don. P617499)..... <b>CA5514</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20017</b>	MT55 w/Cummins B6.7 (6.7L) Eng. (2019) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel/Water Separator</b> (Racor R61709)..... <b>PF46235</b> <b>Fuel</b> (5660774)..... <b>BF63000</b> <b>Air</b> (Farr 94973004)..... <b>PA3891</b> <b>Crankcase Breather</b> (4936636)..... <b>CV15010</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Steering</b> (1417927000)..... <b>PT23629</b>
MT45 w/General Motors V8-365 (6.0L) Eng. (2022) <b>Air</b> (Racor 94973004)..... <b>PA3891</b> <b>Steering</b> (141792700)..... <b>PT23629</b>	MT45 w/Power Solutions International V8-365 (6.0L) Eng. (2018) <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Channel Flow Air</b> (Don. P617499)..... <b>CA5514</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20017</b>	MT55 w/Cummins B6.7 (6.7L) Eng. (2019) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel/Water Separator</b> (Racor R61709)..... <b>PF46235</b> <b>Fuel</b> (5660774)..... <b>BF63000</b> <b>Air</b> (Farr 94973004)..... <b>PA3891</b> <b>Crankcase Breather</b> (4936636)..... <b>CV15010</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Steering</b> (1417927000)..... <b>PT23629</b>
MT45 w/Power Solutions International V8-365 (6.0L) Eng. (2018) <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Channel Flow Air</b> (Don. P617499)..... <b>CA5514</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20017</b>	MT45 w/Power Solutions International V8-365 (6.0L) Eng. (2021) <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	MT55 w/Cummins B6.7 (6.7L) Eng. (2019) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel/Water Separator</b> (Racor R61709)..... <b>PF46235</b> <b>Fuel</b> (5660774)..... <b>BF63000</b> <b>Air</b> (Farr 94973004)..... <b>PA3891</b> <b>Crankcase Breather</b> (4936636)..... <b>CV15010</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Steering</b> (1417927000)..... <b>PT23629</b>
MT45 w/General Motors V8-365 (6.0L) Eng. (2022) <b>Air</b> (Racor 94973004)..... <b>PA3891</b> <b>Steering</b> (141792700)..... <b>PT23629</b>	MT45 w/Mercedes-Benz MBE904 (4.3L) Eng. <b>5 15/16 In. F-F Lube</b> (A0001801609)..... <b>P7199</b> <b>8 3/8 In. F-F Lube</b> (A0001801709)..... <b>P7188</b> <b>Opt. B-P Lube Spinner</b> (A9061810086)..... <b>BC7326 +</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19624)..... <b>PF7748</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Racor R50418)..... <b>BF9898-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Disposable Air Hsg.</b> (Top Inlet) (Farr 114810007)..... <b>PA3555</b>	MT55 w/Cummins B6.7 (6.7L) Eng. (2019) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel/Water Separator</b> (Racor R61709)..... <b>PF46235</b> <b>Fuel</b> (5660774)..... <b>BF63000</b> <b>Air</b> (Farr 94973004)..... <b>PA3891</b> <b>Crankcase Breather</b> (4936636)..... <b>CV15010</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Steering</b> (1417927000)..... <b>PT23629</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
MT55 w/Cummins B6.7 (6.7L) Eng. (2019) (Cont'd) <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	MT55 w/Cummins ISB 5.9 (5.9L) Eng. (1999-2004) (Cont'd) <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b> <b>Steering</b> (T1808D)..... <b>BT9388</b>	MT55 w/Cummins ISB 6.7 (6.7L) Eng. (2008-17) (Cont'd) <b>Fuel/Water Separator Ele.</b> (3942470)..... <b>PF7777</b> <b>Fuel/Water Separator Spin-on</b> (3942533)..... <b>BF1271</b> <b>Fuel</b> (2010 Emissions) (Fleetguard FF5632)..... <b>BF7940</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> <b>Disposable Air Hsg.</b> (4 In. Inlet, Closed End) (Farr 114810007).... <b>PA3555</b> <b>Disposable Air Hsg.</b> (4 In. Inlet) (Farr 114880005)..... <b>PA4655</b> <b>Disposable Air Hsg.</b> (6 In. Inlet) (Farr 94973004)..... <b>PA3891</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b> <b>Trans. Ele.</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Ele.</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Ele.</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Ele.</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Steering</b> (VMLT1808F)..... <b>BT9388</b> <b>Diesel Exhaust Fluid</b> (2010 Emissions) (5303604)..... <b>PE17000</b>
MT55 w/Cummins B6.7 (6.7L) Eng. (2020) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel/Water Separator</b> (R61709).. <b>PF46235</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Disposable Air Hsg.</b> (Farr 94973004)..... <b>PA3891</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Steering</b> (1417927000)..... <b>PT23629</b>	MT55 w/Cummins ISB 5.9 (5.9L) Eng. (2005-2011) <b>Lube</b> (3937144)..... <b>B7177</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (Racor S3226T)..... <b>BF1347</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Racor S3226T)..... <b>BF1347-O</b> <b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (Racor S3226T)... <b>BF1373-SP</b> <b>Fuel/Water Separator Ele.</b> (3942470)..... <b>PF7777</b> <b>Fuel/Water Separator Spin-on</b> (3942533)..... <b>BF1271</b> <b>Fuel</b> (2010 Emissions) (Fleetguard FF5632)..... <b>BF7940</b> <b>Disposable Air Hsg.</b> (4 In. Inlet, Closed End) (Farr 114810007).... <b>PA3555</b> <b>Disposable Air Hsg.</b> (4 In. Inlet) (Farr 114880005)..... <b>PA4655</b> <b>Disposable Air Hsg.</b> (6 In. Inlet) (Farr 94973004)..... <b>PA3891</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b> <b>Trans. Ele.</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Ele.</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Ele.</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Ele.</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b> <b>Steering</b> (T1808D)..... <b>BT9388</b>	MT55 w/Cummins ISB 6.7 (6.7L) Eng. (2019) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel/Water Separator</b> (Racor R61709)..... <b>PF46235</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Air</b> (Farr 94973004)..... <b>PA3891</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b> <b>Pan-Type Trans.</b> (S. Pan, w/o Gskt.) (29537965)..... <b>20004</b> <b>Pan-Type Trans.</b> (S. Pan, w/Gskt.) (29537965)..... <b>20016</b> <b>Pan-Type Trans.</b> (D. Pan, w/o Gskt.) (29537966)..... <b>20003</b> <b>Pan-Type Trans.</b> (D. Pan, w/Gskt.) (29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (29539579)..... <b>BT8460</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
MT55 w/Cummins B6.7 (6.7L) Eng. (2022) <b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b>	MT55 w/Cummins ISB 5.9 (5.9L) Eng. (1999-2004) <b>Lube</b> (3937144)..... <b>B7177</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (Racor S3226T)..... <b>BF1347</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Racor S3226T)..... <b>BF1347-O</b> <b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (Racor S3226T)... <b>BF1373-SP</b> <b>Fuel/Water Separator Ele.</b> (3942470)..... <b>PF7777</b> <b>Fuel/Water Separator Spin-on</b> (3942533)..... <b>BF1271</b> <b>Disposable Air Hsg.</b> (4 In. Inlet) (Farr 114880005)..... <b>PA4655</b> <b>Disposable Air Hsg.</b> (6 In. Inlet) (Farr 94973004)..... <b>PA3891</b> <b>Trans. Ele.</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Ele.</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Ele.</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Ele.</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b>	MT55 w/Cummins ISB 6.7 (6.7L) Eng. (2019) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel/Water Separator</b> (Racor R61709)..... <b>PF46235</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Air</b> (Farr 94973004)..... <b>PA3891</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b> <b>Pan-Type Trans.</b> (S. Pan, w/o Gskt.) (29537965)..... <b>20004</b> <b>Pan-Type Trans.</b> (S. Pan, w/Gskt.) (29537965)..... <b>20016</b> <b>Pan-Type Trans.</b> (D. Pan, w/o Gskt.) (29537966)..... <b>20003</b> <b>Pan-Type Trans.</b> (D. Pan, w/Gskt.) (29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (29539579)..... <b>BT8460</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
	MT55 w/Cummins ISB 6.7 (6.7L) Eng. (2008-17) <b>Lube</b> (3937144)..... <b>B7177</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (Racor S3226T)..... <b>BF1347</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Racor S3226T)..... <b>BF1347-O</b> <b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (Racor S3226T)... <b>BF1373-SP</b>	MT55 w/Cummins ISB 6.7 (6.7L) Eng. (2020) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel/Water Separator</b> (R61709).. <b>PF46235</b> <b>Fuel</b> (5303743)..... <b>BF63000</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)	FREIGHTLINER Trucks & Buses (cont'd)
MT55 w/Cummins ISB 6.7 (6.7L) Eng. (2020) (Cont'd)	MT55 w/Mercedes MBE906 (6.4L) Eng.	S2G w/Agility 488LPI (8.0L) Eng. (2020)
Disposable Air Hsg. (Farr 94973004)..... PA3891	Lube Ele. (A0001801709)..... P7188	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004
Crankcase Breather (4936636)... CV15010	Opt. Lube Spinner (A9061810086)..... BC7326 +	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016
Pan-Type Trans. (S. Pan, w/o Gskt.) (29537965)..... 20004	Fuel (4 1/16 In.) (A0000901551)... PF7735	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003
Pan-Type Trans. (S. Pan, w/Gskt.) (29537965)..... 20016	Fuel (8 In.) (A5410920805)..... PF7761	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017
Pan-Type Trans. (D. Pan, w/o Gskt.) (29537966)..... 20003	Trans. Ele. (2 In. Kit) (Allison 29558117)..... PT9416-MPG KIT	Trans. Spin-on (Allison 29539579)..... BT8460
Pan-Type Trans. (D. Pan, w/Gskt.) (29537966)..... 20017	Trans. Ele. (4 In. Kit) (Allison 29558118)..... PT9415-MPG KIT	Trans. Ele. (2 In. Kit) (Allison 29558117)..... PT9416-MPG KIT
Trans. Spin-on (29539579)..... BT8460	Trans. Ele. (HT Series) (Allison 29510918)..... PT8330-MPG	Trans. Ele. (4 In. Kit) (Allison 29558118)..... PT9415-MPG KIT
Steering (1417927000)..... PT23629	Trans. Ele. (MT Series) (Allison 29510922)..... BT8316-MPG	
MT55 w/Cummins ISX 11.9 (11.9L) Eng.	Trans. Pan-Type (MT Series) (Allison 29538489)..... 19739	S2G w/Agility 488LPI (8.0L) Eng. (2021)
Dual-Flow Lube (Std. Version) (Fleetguard LF9001)..... BD7154 +	Steering (T1808D)..... BT9388	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004
Dual-Flow Lube (Upgrade) (Fleetguard LF9001)..... BD50000	MT55 w/Power Solutions International (6.0L) Eng. (2018)	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016
Fuel/Water Separator (3942533). BF1271	Fuel (N/S)..... N/S	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003
Coolant (w/o Chemical) (Fleetguard WF2127)..... B5087	Channel Flow Air (Don. P617499)..... CA5514	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017
Coolant (w/Chemical) (Fleetguard WF2126)..... BW5086	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004	Trans. Spin-on (Allison 29539579)..... BT8460
Steering (T1808D)..... BT9388	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016	Trans. Ele. (2 In. Kit) (Allison 29558117)..... PT9416-MPG KIT
MT55 w/Detroit DD5 (5.1L) Eng. (2021)	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003	Trans. Ele. (4 In. Kit) (Allison 29558118)..... PT9415-MPG KIT
Lube (A9341800009)..... P40017	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017	
MT55 w/Detroit DD5 (5.1L) Eng. (2022)	Trans. Spin-on (Allison 29539579)..... BT8460	S2G w/Cummins B6.7 (6.7L) Eng. (2018)
Lube (A9341801410)..... P40017	Steering (VMLT1808F)..... BT9388	Lube (3937736)..... B7177
MT55 w/General Motors V8-365 (6.0L) Eng. (2022)	MT55 w/Power Solutions International (6.0L) Eng. (2019)	Fuel (Fleetguard FF63009)..... BF63000
Steering (1417927000)..... PT23629	Fuel (N/S)..... N/S	Channel Flow Air (Standard Media) (Don. P607955)..... CA4700
MT55 w/Mercedes MBE904 Eng.	Channel Flow Air (Don. P608666)..... CA5514	Channel Flow Air (Flame Retardant Media) (Don. P607960) CA5420
5 5/16 In. F-F Lube Ele. (1801609)..... P7199	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004	Air Dryer (65624)..... BA5373
8 3/8 In. F-F Lube Ele. (A0001801709)..... P7188	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016	Crankcase Breather (4936636)... CV15010
Opt. B-P Lube Spinner (A9061810086)..... BC7326 +	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003	
Fuel/Water Separator Ele. (Fleetguard FS19624)..... PF7748	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017	S2G w/Powertrain Integration V8 8.0L Eng. (To 2017)
4 1/16 In. Fuel (A0000901551)... PF7735	Trans. Spin-on (Allison 29539579)..... BT8460	Lube (11020)..... B1428 +
7 31/32 In. Fuel (A5410920805)... PF7761	Steering (1417927000)..... PT23629	Channel Flow Air (Don. P607955)..... CA4700 +
Disposable Air Hsg. (Farr 114880005)..... PA4655	Opt. Rear Axle (Meritor 3280V8394)..... B233	Channel Flow Secondary Air (Don. P616400)..... PA4701
Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004	MT55 w/Power Solutions International (6.0L) Eng. (2020)	Cab Air (36000006)..... PA5359
Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016	Lube (ACDelco PF48)..... B160	Air Dryer (AD-9 System) (Bendix 107796)..... BA5377
Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003	Steering (1417927000)..... PT23629	Air Dryer (AD-IP System) (Bendix 65624)..... BA5373
Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017		Trans. Ele. (S. Pan w/o Gskt.) (Allison 29537965)..... 20004
Trans. Spin-on (Allison 29539579)..... BT8460		Trans. Ele. (S. Pan w/Gskt.) (Allison 29537965)..... 20016
Steering (T1808D)..... BT9388		Trans. Ele. (D. Pan w/o Gskt.) (Allison 29537966)..... 20003
		Trans. Ele. (D. Pan w/Gskt.) (Allison 29537966)..... 20017


+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



<b>FWD CORPORATION</b> Trucks (cont'd)	<b>GAZ</b> Trucks	<b>GENERAC</b> RV Generators (cont'd)
CB66, CB86, CB108 w/GMC 6-71 Eng. F-F Lube Ele..... P20-HD + P. Fuel Spin-on..... BF5800 + S. Fuel Spin-on..... BF5810	10353 w/Cummins ISF3.8 Eng. Lube (Fleetguard LF16352)..... B40050 Fuel/Water Separator (Fleetguard FS19732)..... BF46065-SPS	862-1 Lube (70185)..... B33 Air (73111)..... PA2222
CB66, CB86, FD86, CB108 w/Cummins NTC230, NTC250 Engs. F-F Lube Spin-on..... B196 + F-F Lube Ele..... P999-HD B-P Lube Ele..... C750-E + Fuel Spin-on..... BF957 + Coolant Spin-on..... BW5071	10354 w/Cummins ISF3.8 Eng. Lube (Fleetguard LF16352)..... B40050 Fuel/Water Separator (Fleetguard FS19732)..... BF46065-SPS	862-2 Lube (70185)..... B33 Air (73111)..... PA2222
HA, HAY, HG, HGY, HR, HRT, HRY, HR6x6, LD Custom Lube..... P41 +	10478 w/Cummins ISF3.8 Eng. Lube (Fleetguard LF16352)..... B40050 Fuel/Water Separator (Fleetguard FS19732)..... BF46065-SPS	916-1 Lube (70185)..... B33 Air (73111)..... PA2222
HC6x6D, HCY6x6D, SUD, YUD w/GMC 4-71 Diesel Eng. B-P Lube (5572425)..... P52 B-P Lube (Fram F43P)..... P116	10761 w/Cummins ISF3.8 Eng. Lube (Fleetguard LF16352)..... B40050 Fuel/Water Separator (Fleetguard FS19732)..... BF46065-SPS	919-0 Lube (70185)..... B33 Air (73111)..... PA2222
MU6x6D, ZUD w/GMC 6-71 Diesel Eng. B-P Lube..... P52 P. Fuel Sock..... F916-C S. Fuel Ele..... PF902	<b>GENERAC</b> RV Generators	919-1 Lube (70185)..... B33 Air (73111)..... PA2222
R4-426V, R4-466V w/Ford 534 Eng. Lube..... P47 Air..... PA654	595 Lube (70185)..... B33	940 Lube (70185)..... B33
R6-411D w/GMC 6-110 Eng. Lube (Fram F43P)..... P116	595-0 Lube (70185)..... B33	940-1 Lube (70185)..... B33
RS6-404D, RS6-411D w/GMC Diesel Eng. F-F Lube..... P20-HD + B-P Lube..... P52	595-1 Lube (70185)..... B33	940-2 Lube (70185)..... B33
T47 w/IHC Red Diamond Eng. B-P Lube Sock (1957-on)..... CU406 <sup>90</sup>	661 Lube (70185)..... B33	941 Lube (70185)..... B33
<b>GALBREATH</b> Waste Equipment	661-4 Lube (70185)..... B33	941-1 Lube (70185)..... B33
Models	661-5 Lube (70185)..... B33	941-2 Lube (70185)..... B33
Hyd. (3540)..... PF902	784-1 Lube (70185)..... B33	941-4 Lube (70185B)..... B33
<b>GEN-STAR</b> Auxiliary Power Units (APU)	784-2 Lube (70185)..... B33	2010 Lube (70185)..... B33 Air (73111)..... PA2222
Gen-Star w/Lombardini LDW 702 Eng. Lube (107-2175-117)..... B7276 Fuel (Fram P4102A)..... BF788 Air (2175-1640)..... PA3953	802 Lube (70185)..... B33	2010-0 Lube (70185)..... B33 Air (73111)..... PA2222
Gen-Star w/Perkins 402C-05 Eng. Fuel (130366040)..... PF937 Air..... CLN&R	802-3 Lube (70185)..... B33	2010-1 Lube (70185)..... B33 Air (73111)..... PA2222
6000 w/Lombardini 6LBDL Eng. Lube (Luberfiner PH8A)..... B2 +	803 Lube (70185)..... B33	2010-2 Lube (70185)..... B33 Air (73111)..... PA2222
<b>GEN-PAC</b> Auxiliary Power Units (APU)	803-4 Lube (70185)..... B33	4164 Lube (70185)..... B33 Air (73111)..... PA2222
Gen-Pac w/Kubota D905 Eng. Lube (16271-32090)..... B161-S Pre-Fuel In-Line (13351-43010).. BF840 + Fuel Spin-on (70000-43081)..... BF7683 Air (70000-11221)..... PA1865-FN	843-0 Lube (70185)..... B33	4164-0 Lube (70185)..... B33 Air (73111)..... PA2222
	860-0 Lube (70185)..... B33	4164-1 Lube (70185)..... B33 Air (73111)..... PA2222
	861-0 Lube (70185)..... B33	4164-2 Lube (70185)..... B33 Air (73111)..... PA2222
	862 Lube (70185)..... B33 Air (73111)..... PA2222	

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

GENERAC RV Generators (cont'd)	GENERAC RV Generators (cont'd)	GENERAC RV Generators (cont'd)
4164-3 Lube (70185)..... B33 Air (73111)..... PA2222	9344 w/Diesel Eng. Lube (709390126)..... B113 Fuel (69858)..... BF954 + Air (70941)..... PA3643	9734 Lube (70185)..... B33
4270 Lube (709390126)..... B113 Fuel (69858)..... BF954 +	9344 w/LP Eng. Lube (709390126)..... B113 Fuel (69858)..... BF954 + Air (70941)..... PA3643	9734-3 Lube (70185)..... B33
4270-0 Fuel (69858)..... BF954 +	9344-1 Fuel (69858)..... BF954 + Air (70941)..... PA3643	9734-4 Lube (70185)..... B33
4270-1 Lube (709390126)..... B113 Fuel (69858)..... BF954 +	9344-2 Lube (709390126)..... B113 Fuel (69858)..... BF954 + Air (70941)..... PA3643	9734-5 Lube (70185)..... B33
4270-2 Lube (709390126)..... B113	9410 Lube (709390126)..... B113 Fuel (69858)..... BF954 + Air (70941)..... PA3643	9735 Lube (70185)..... B33
4614-1 Lube (709390126)..... B113 Fuel (69858)..... BF954 +	9557 Lube (70185)..... B33	9735-3 Lube (70185)..... B33
4700-0 Lube (70185B)..... B33	9591 Lube (70185)..... B33	9735-4 Lube (70185)..... B33
4701-0 Lube (70185B)..... B33	9592 Lube (70185)..... B33	9735-5 Lube (70185)..... B33
4702-0 Lube (70185B)..... B33	9592-3 Lube (70185)..... B33	9736 Lube (70185)..... B33
4703-0 Lube (70185B)..... B33	9592-4 Lube (70185)..... B33	9736-3 Lube (70185)..... B33
4704-0 Lube (70185B)..... B33	9592-5 Lube (70185)..... B33	9840 Lube (70185)..... B33 Air (73111)..... PA2222
4705-0 Lube (70185B)..... B33	9593-3 Lube (70185)..... B33	9843 Lube (70185)..... B33
4706-0 Lube (70185B)..... B33	9600 Lube (70185)..... B33	9843-2 Lube (70185)..... B33
4707-0 Lube (70185B)..... B33	9600-3 Lube (70185)..... B33	9843-3 Lube (70185)..... B33
4766-0 Lube (70185B)..... B33	9600-4 Lube (70185)..... B33	9847 Lube (70185)..... B33
4767-0 Lube (70185B)..... B33	9600-5 Lube (70185)..... B33	9848 Lube (70185)..... B33
9290-4 Lube (70185)..... B33	9629 Lube (70185)..... B33	QP-75D w/1.0L ISM Eng. Lube (709390126)..... B113 Fuel (69858)..... BF954 +
9309 Lube (70185)..... B33	9648 Lube (70185)..... B33	<b>GENERAL MOTORS CORP.</b> <b>Gas Engines</b>
9310 Lube (70185)..... B33	9693 Lube (70185)..... B33	173 V6 3 1/2 In. Lube..... B43-S 4 27/32 In. Lube..... B35-S + Fuel (1982-85)..... PF894-RV Fuel (1986, 1988-on)..... BF868 Fuel (1987)..... BF853 Air (1982-85)..... PA2113 Air (1986-on)..... PA2106
9327 Lube (70185)..... B33	9712 Lube (70185)..... B33 Air (73111)..... PA2222	200 V6 Lube..... B43-S Fuel..... PF894-RV Air..... PA1680
9328 Lube (70185)..... B33		229 V6 Lube (To 1981)..... B43-S Lube (1981-on)..... B35-S + Fuel (To 1982)..... PF894-RV
9343 Lube (709390126)..... B113 Fuel (69858)..... BF954 + Air (70941)..... PA3643		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



GENERAL MOTORS CORP. Gas Engines (cont'd)	GENERAL MOTORS CORP. Gas Engines (cont'd)	GENERAL MOTORS CORP. Gas Engines (cont'd)
<b>350 V8 (Cont'd)</b> Air (1969-on) (2236986)..... PA1800 + Air (1969-on) (6483645)..... PA2006 Air (1970-72) (6424027)..... PA1841 Air (1970-on) (6483864)..... PA1680 Air (1970-on) (6484235)..... PA2008 Air (1973) (5649797)..... PA658 Air (1980-on) (8997890)..... PA2091 Air (702025)..... PA1922-FN	<b>396 V8</b> Std. Lube Ele. (To 1969)..... P18 Lube Ele. (1969-72)..... P476 5 5/16 In. Lube Spin-on..... B6 + 8 23/32 In. Lube Spin-on..... B7 1 1/32 In. Fuel (1968-on, (Paper))..... PF893 Fuel (1969, (SintBronze))..... SF898 3 15/32 In. Fuel Ele. (To 1970).... PF827 Air (To 1968) (5645017)..... PA625 Air (1969-71) (6483645)..... PA2006 Opt. Air (6421746)..... PA1758	<b>454 V8 (Cont'd)</b> In-Line Fuel (Carb.)..... BF836 In-Line Fuel (FI)..... BF853 3 15/32 In. Fuel Ele..... PF827 3 In. Air (1970-72)..... PA1758 2 1/2 In. Air (1972)..... PA2006 3 15/32 In. Air (1972-on)..... PA2008 1 7/8 In. Air (1973)..... PA658 Air (w/Fins), 1979-80..... PA1922-FN 5 7/16 In. Air (1980-on)..... PA2091 4 In. Air (1988-on)..... PA2073
<b>351, 351C, 351M V6</b> Lube Ele. (1960-69)..... P20-HD + 4 3/8 In. Lube Spin-on..... B39 5 9/32 In. Lube Spin-on..... B9 2 1/8 In. Fuel Ele. (1960-65)..... PF860 3 15/32 In. Fuel Ele. (1960-on).... PF827 1 1/32 In. Fuel Ele. (1966-68)..... PF857 1 1/32 In. Fuel (1967, (Carb.))..... PF893 In-Line Fuel (5/16 In. Lines)..... BF840 + In-Line Fuel (3/8 In. Lines)..... BF836 11 5/16 In. O.D. Air (1966-72) (6420680)..... PA625 Opt. Air (1967-68) (2493708)..... PA1786 Air (1968) (6483864)..... PA1680 Air (2236986)..... PA1800 +	<b>400 V8</b> 4 3/8 In. Lube Spin-on..... B27 5 5/16 In. Lube Spin-on..... B6 + 8 23/32 In. Lube Spin-on..... B7 Fuel (1975-on, (2 Bbl.))..... PF893 Fuel (1975-on, (4 Bbl.))..... PF894-RV Std. 9 3/4 In. O.D. Air (1975-on).. PA1680 Opt. 12 In. O.D. Air (1975-on).... PA2008	<b>478, 478M V6</b> Lube Ele..... P20-HD + Fuel Ele..... PF827 In-Line Fuel..... BF840 + Axial Seal Air (1971-74) (8877141)..... PA1798 + Opt. Air (1971-74) (2236986)..... PA1800 + Air (6420690)..... PA625 Air (702025)..... PA1922-FN
<b>360 6 Cyl.</b> Lube (1955-59)..... P52 1 1/32 In. O.D. Fuel (1957-59)..... PF857 3 In. O.D. Fuel (1957-59)..... PF860 Crankcase Breather..... PA1603	<b>401, 401M V6</b> Lube Ele..... P20-HD + Fuel Ele..... PF827 In-Line Fuel..... BF840 + Axial Seal Air (1971-74) (8877141)..... PA1798 + Opt. Air (w/Foam Wrap)..... PA1800 Opt. Air (6420690)..... PA625	<b>503 6 Cyl.</b> Lube (1955-59)..... P52 1 1/32 In. O.D. Fuel (1957-59).... PF857 3 In. O.D. Fuel (1957-59)..... PF860 Crankcase Breather..... PA1603
<b>365 V8 (6.0L)</b> Lube (To 2003)..... B1432 Lube (2003-on)..... B31 Fuel (Trucks)..... BF853 Fuel (2003 (Vans))..... BF1171	<b>402 V8</b> Lube Ele..... P476 Lube Spin-on..... B6 + 1 1/32 In. Fuel (Carb.)..... PF893 3 15/32 In. Fuel Ele..... PF827 Air (1971-72)..... PA2006	<b>637 V8</b> Lube Ele. (1966-72)..... P20-HD + Fuel (1966-72 (Exc. 1970))..... PF827 Fuel (1970)..... PF902
<b>366 V8</b> Lube Ele. (1967-72)..... P476 5 5/16 In. Lube Spin-on..... B6 + 8 23/32 In. Lube Spin-on..... B7 3 15/32 In. Fuel Ele. (1966-on).... PF827 Fuel Spin-on..... BF782 Air (6422556)..... PA1800 Air (6487958)..... PA2008 Air (699505)..... PA2316 Air (702025)..... PA1922-FN	<b>427 6 Cyl.</b> Lube (1955-59)..... P52 1 1/32 In. O.D. Fuel (1957-59).... PF857 3 In. O.D. Fuel (1957-59)..... PF860 Crankcase Breather..... PA1603	<b>702B V12</b> Lube Ele..... P20-HD + 1 1/32 In. Fuel Ele..... PF857 3 15/32 In. Fuel Ele..... PF827 In-Line Fuel..... BF840 +
<b>370 V8</b> Lube..... P25 In-Line Fuel (1955-56)..... BF840 + Fuel Ele. (1957-59)..... PF857	<b>427 V8</b> Lube Ele. (1966) (5574540)..... P18-HD Lube Ele. (1967-72)..... P476 Lube Spin-on..... B7 Fuel Ele..... PF827 Air (6422556)..... PA1800 Air (702025)..... PA1922-FN	<div style="text-align: center;"><b>GENERAL MOTORS CORP.</b> Trucks, Buses &amp; Vans</div> 1000, 1500, 2500, 3500 Series w/6 Cyl. 194 Eng. 4 3/8 In. Lube..... B27 5 5/16 In. Lube..... B6 + Fuel (SintBronze)..... SF898 Axial Seal Air..... PA658 Heavy Duty Air..... PA1680
<b>379 V6</b> Opt. Lube Ele..... P20-HD + 4 3/8 In. Lube Spin-on..... B39 5 9/32 In. Lube Spin-on..... B9 In-Line Fuel (1974)..... BF840 + 3 15/32 In. Fuel Ele..... PF827 Air (2236986)..... PA1800 + Air (702025)..... PA1922-FN	<b>432, 432M V6</b> Lube Ele..... P20-HD + In-Line Fuel (1973-74) (73103).... BF836-K4 Air (2236986)..... PA1800 + Air (702025)..... PA1922-FN	1000, 1500, 2500, 3500 Series w/6-230 Eng. 4 3/8 In. Lube..... B27 5 5/16 In. Lube..... B6 + Fuel Ele. (1968-69)..... PF893 Fuel (1963-70, (SintBronze))..... SF898 Axial Seal Air..... PA658 Heavy Duty Air..... PA1680
<b>396 V8</b> Std. Lube Ele. (To 1969)..... P18 Lube Ele. (1969-72)..... P476 5 5/16 In. Lube Spin-on..... B6 + 8 23/32 In. Lube Spin-on..... B7 Fuel (1970-71 (SintBronze))..... SF898 1 1/32 In. Fuel (1972-75)..... PF893 2 1/32 In. Fuel (Carb.) 1975-on.... PF894-RV	<b>454 V8</b> 4 3/8 In. Lube..... B27 5 5/16 In. Lube..... B6 + 8 23/32 In. Lube..... B7 Fuel (1970-71 (SintBronze))..... SF898 1 1/32 In. Fuel (1972-75)..... PF893 2 1/32 In. Fuel (Carb.) 1975-on.... PF894-RV	1500, 2500 Series w/4 Cyl. 153 Eng. 4 3/8 In. Lube..... B27 5 5/16 In. Lube..... B6 + Fuel (1962-66, (SintBronze))..... SF898 Axial Seal Air..... PA658 Heavy Duty Air..... PA1680

+ See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

GENERAL MOTORS CORP. Trucks, Buses & Vans (cont'd)	GENERAL MOTORS CORP. Trucks, Buses & Vans (cont'd)	GENERAL MOTORS CORP. Trucks, Buses & Vans (cont'd)
1500, 2500, 3500 Series w/6 Cyl. 250 Eng. 4 3/8 In. Lube..... B27 5 5/16 In. Lube..... B6 + Fuel (1966-70, (SintBronze))..... SF898 1 1/32 In. Fuel (1968-on, (Carb.))..... PF893 3 15/32 In. Fuel Ele. (1969-72)..... PF827 2 1/32 In. Fuel (1979-on, (Carb.))..... PF894-RV Air (1966-78) (5649797)..... PA658 Heavy Duty Air (1966-72) (6483864)..... PA1680 Air (1967-72) (6424027)..... PA1841 Air (1970-78) (5648003)..... PA648 Air (1979-on)..... PA2077	1500, 2500, 3500 Series w/V6-351 Eng. Lube..... B39 Fuel Ele. (1966-68)..... PF857 1 1/32 In. Fuel (1967, (Carb.))..... PF893 In-Line Fuel (1968)..... BF840 + Air (1966) (5645017)..... PA625 Opt. Air (1967) (2493708)..... PA1786 Air (1968) (6483864)..... PA1680 1500, 2500, 3500 Series w/V8-283 Eng. Lube..... P18 Fuel Ele. (1963-67)..... PF827 Fuel (1967, (SintBronze))..... SF898 Air (1964-67) (5645017)..... PA625 Air (1967-68) (6459892)..... PA1680 1500, 2500, 3500 Series w/V8-305 Eng. Lube (1988-on, (K Series))..... B35-S + Lube (Exc. K Series)..... B6 + 1 1/32 In. Fuel (Carb.)..... PF893 2 1/32 In. Fuel (Carb.)..... PF894-RV Fuel (FI)..... BF853 Air (1976-80 (Exc. G Series Vans))..... PA2006 Air (1976-on (G Series Vans))..... PA1680 Other 3 15/32 In. Air (1981-on).... PA2008 Other 5 7/16 In. Air (1981-on).... PA2091	1500, 2500, 3500 Series w/V8-350 Gas Eng. (Cont'd) 3 15/32 In. Air (1972-on)..... PA2008 5 7/16 In. Air (1980-on)..... PA2091 4 In. Air (1988-on)..... PA2073 1500, 2500, 3500 Series w/V8-379 (6.2L) Diesel Eng. Lube..... B6 + P. Fuel (1982-83, (Exc. 1983 Vans))..... BF781 P. Fuel (1983, (Vans))..... BF592 + S. Fuel (1982-83, (Exc. 1983 Vans))..... BF782 Box-Style S. Fuel (1983, (Vans)). BF855 Box-Style Fuel (1984-on)..... BF856 Air..... PA2073 1500, 2500, 3500 Series w/V8-396 Eng. Lube Ele. (To 1969)..... P476 Lube Ele. (1969-72)..... P18 Lube Spin-on..... B6 + Fuel (Carb.)..... PF893 Fuel (SintBronze) (Carb.)..... SF898 3 15/32 In. Fuel Ele..... PF827 Air (6421746)..... PA1758 Air (6483645)..... PA2006 1500, 2500, 3500 Series w/V8-400 Eng. 1 Qt. Lube..... B6 + 2 Qt. Lube..... B7 1 1/32 In. Fuel (1975-on, (Carb.))..... PF893 2 1/32 In. Fuel (1975-on, (Carb.))..... PF894-RV Air (1975-on, (Exc. Vans))..... PA2008 Air (1975-on, (Vans))..... PA1680 1500, 2500, 3500 Series w/V8-402 Eng. Lube..... B6 + Fuel Ele..... PF827 1500, 2500, 3500 Series w/V8-454 Eng. 1 Qt. Lube..... B6 + 2 Qt. Lube..... B7 In-Line Fuel (Carb.)..... BF836 1 1/32 In. Fuel (Carb.)..... PF893 2 1/32 In. Fuel (Carb.)..... PF894-RV Fuel (FI)..... BF853 Air (To 1986, (Exc. 1980-85 Calif.))..... PA2008 Air (1980-85, (Calif.))..... PA2091 5 7/16 In. Air (1986-on)..... PA2091 3 15/32 In. Air (1987-on)..... PA2008 4 In. Air (1988-on)..... PA2073 2500, 3500 Series w/Detroit Diesel 3-53 Eng. Lube..... PT11 P. Fuel Sock..... F916-C S. Fuel Ele..... PF906
1500, 2500, 3500 Series w/V6-262 Eng. Lube..... B35-S + Fuel (4 Bbl.)..... PF894-RV Fuel (FI)..... BF853 Air..... PA1680 1500, 2500, 3500 Series w/6 Cyl. 292 Eng. Opt. Lube Ele. (1966-75)..... P476 4 3/8 In. Lube Spin-on..... B27 5 5/16 In. Lube Spin-on..... B6 + Fuel Ele. (1962-71)..... PF827 Fuel (1963-71, (SintBronze) (Carb.))..... SF898 1 1/32 In. Fuel (1968-86, (Carb.))..... PF893 Fuel (1988-on)..... PF894-RV In-Line Fuel..... BF836 Air (1962-67) (5645017)..... PA625 Air (1967-74) (6424027)..... PA1841 Air (1968-72) (6483864)..... PA1680 Air (1971-on) (5648003)..... PA648 1500, 2500, 3500 Series w/6 Cyl. 305A, 305D Eng. Lube Ele. (1960-65)..... P25 Fuel (854347)..... PF857 1500, 2500, 3500 Series w/V6-305C Eng. Lube Ele..... P20-HD + 4 3/8 In. Lube Spin-on..... B39 5 9/32 In. Lube Spin-on..... B9 Fuel (1960-65)..... PF827 Fuel (1966-68)..... PF857 Fuel (1969)..... BF836 Fuel (1970-74)..... PF893 Air (2493708)..... PA1786 Air (5645017)..... PA625 1500, 2500, 3500 Series w/V6-305E Eng. Lube Ele..... P25 4 3/8 In. Lube Spin-on..... B39 5 9/32 In. Lube Spin-on..... B9 Fuel Ele. (1960-68)..... PF857 1 1/32 In. Fuel (1967, (Carb.))..... PF893 In-Line Fuel (1968-69)..... BF840 + Air (2493708)..... PA1786 Air (5645017)..... PA625	1500, 2500, 3500 Series w/V8-307 Eng. Lube Ele..... P18 Lube Spin-on..... B6 + Fuel (Carb.)..... PF893 Fuel (SintBronze) (Carb.)..... SF898 3 15/32 In. Fuel Ele..... PF827 2 1/2 In. Air..... PA2006 3 9/16 In. Air..... PA1680 1500, 2500, 3500 Series w/V8-327 Eng. Lube Ele..... P18 1 1/32 In. Fuel Ele. (Carb.)..... PF893 3 15/32 In. Fuel Ele..... PF827 Air (1964-67) (5645017)..... PA625 Air (1968-on) (6483645)..... PA2006 1500, 2500, 3500 Series w/V8-350 Diesel Eng. Lube (1978)..... B39 Lube (1979-on)..... B30 Box-Style Fuel..... BF806 Air..... PA2073 1500, 2500, 3500 Series w/V8-350 Gas Eng. Lube Ele..... P18 Lube Spin-on (Exc. K Series)..... B6 + Lube Spin-on (1988-on, (K Series))..... B35-S + Fuel Ele..... PF827 1 1/32 In. Fuel (Carb.)..... PF893 2 1/32 In. Fuel (Carb.)..... PF894-RV In-Line Fuel (Carb.)..... BF836 In-Line Fuel (FI)..... BF853 Fuel (SintBronze) (Carb.)..... SF898 Air (1969-71)..... PA2006 Air (1972-on, (Vans))..... PA1680 2 1/2 In. Air (1972-78)..... PA2006	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



GENERAL MOTORS CORP. Trucks, Buses & Vans (cont'd)	GENERAL MOTORS CORP. Trucks, Buses & Vans (cont'd)	GENERAL MOTORS CORP. Trucks, Buses & Vans (cont'd)
<b>4000 Series w/Isuzu Eng.</b> F-F Lube (94169778)..... B244 B-P Lube (94169779)..... B222 Fuel Spin-on (94414796)..... [2] BF954 + Air (94156052)..... PA2712 Air (94430250)..... PA2761	<b>4000-6500 Series w/GMC V6-305E Eng.</b> Lube Ele..... P25 4 3/8 In. Lube Spin-on..... B39 5 9/32 In. Lube Spin-on..... B9 In-Line Fuel (1969)..... BF840 + 1 3/4 In. O.D. Fuel Ele. (1960-68) ..... PF857 11/16 In. O.D. Fuel Ele. (Carb.)... PF893 3 15/32 In. Fuel Ele..... PF827 Air (2493708)..... PA1786 Air (5645017)..... PA625 Heavy Duty Air (2236986)..... PA1800 +	<b>4000-6500 Series w/GMC V8-350 Eng.</b> 1 Qt. Lube Ele..... P18 2 Qt. Lube Ele..... P476 4 3/8 In. Lube Spin-on..... B27 5 5/16 In. Lube Spin-on..... B6 + 8 23/32 In. Lube Spin-on..... B7 1 1/32 In. Fuel (Carb.)..... PF893 2 1/32 In. Fuel (Carb.)..... PF894-RV 3 15/32 In. Fuel Ele..... PF827 Air (1968-on) (6483645)..... PA2006 Air (2236986)..... PA1800 + Air (6423239)..... PA1798 + Air (6424027)..... PA1841 Air (702025)..... PA1922-FN Comp. Breather (8875051)..... PA1909 Comp. Breather (9028042)..... PA1600
<b>4000-6500 Series w/GMC 4-53N Eng.</b> F-F Lube Ele..... P20-HD + P. Fuel Sock..... F916-C 3 5/8 In. S. Fuel Ele..... PF906 7 13/16 In. S. Fuel Ele..... PF902 Air (2009007)..... PA2465 Air (2014573)..... PA2550 Air (2031381)..... PA2540 +	<b>4000-6500 Series w/GMC V6-351 Eng.</b> Lube Ele..... P20-HD + 2 1/8 In. Fuel..... PF860 3 15/32 In. Fuel..... PF827	<b>4000-6500 Series w/GMC V8-366 Eng.</b> Lube Ele..... P476 5 5/16 In. Lube Spin-on..... B6 + 8 23/32 In. Lube Spin-on..... B7 Fuel Ele..... PF827 Air (2236986)..... PA1800 + Air (6423239)..... PA1798 + Air (699505)..... PA2316 Air (702025)..... PA1922-FN Comp. Breather (8875051)..... PA1909 Comp. Breather (9028042)..... PA1600
<b>4000-6500 Series w/GMC 6 Cyl. 250 Eng.</b> 4 3/8 In. Lube Spin-on..... B27 5 5/16 In. Lube Spin-on..... B6 + 1 1/32 In. Fuel (Carb.)..... PF893 3 15/32 In. Fuel Ele..... PF827 In-Line Fuel..... BF840 + Fuel (SintBronze)..... SF898 1 7/8 In. Air (5649797)..... PA658 3 In. Air (3979576)..... PA648 3 1/8 In. Air (6424027)..... PA1841 3 9/16 In. Air (6483864)..... PA1680	<b>4000-6500 Series w/GMC V6-351C Eng.</b> Lube Ele. (1969-on)..... P20-HD + 4 3/8 In. Lube Spin-on..... B39 5 9/32 In. Lube Spin-on..... B9 1 1/32 In. Fuel Ele..... PF857 3 15/32 In. Fuel Ele..... PF827 In-Line Fuel..... BF840 + Air (2236986)..... PA1800 + Air (2493708)..... PA1786 Air (5645017)..... PA625 Comp. Breather (2467368)..... PA1704 Comp. Breather (8875051)..... PA1909 Comp. Breather (9028042)..... PA1600	<b>4000-6500 Series w/GMC V8-427 Eng.</b> 1 Qt. Lube Ele..... P18 2 Qt. Lube Ele..... P476 5 5/16 In. Lube Spin-on..... B6 + 8 23/32 In. Lube Spin-on..... B7 Fuel Ele..... PF827 Air (2236986)..... PA1800 + Air (6423239)..... PA1798 + Air (702025)..... PA1922-FN Comp. Breather (8875051)..... PA1909
<b>4000-6500 Series w/GMC 6 Cyl. 292 Eng.</b> Lube Ele. (1963-67)..... P20-HD + Lube Ele. (1968-on)..... P476 4 3/8 In. Lube Spin-on..... B27 5 5/16 In. Lube Spin-on..... B6 + 8 23/32 In. Lube Spin-on..... B7 1 1/32 In. Fuel Ele. (Carb.)..... PF893 3 15/32 In. Fuel Ele..... PF827 In-Line Fuel..... BF840 + Fuel (SintBronze) (7013404)..... SF898 Air (1962-67) (5645017)..... PA625 Air (1968-72) (6424027)..... PA1841 Air (1968-72) (6483864)..... PA1680 Air (1971-on) (5648003)..... PA648 Comp. Breather (Bendix)..... PA1600 Comp. Breather (Midland)..... PA1909	<b>4000-6500 Series w/GMC V6-351M Eng.</b> Lube Ele..... P20-HD + In-Line Fuel (73103)..... BF836-K4 Fuel Ele..... PF827 Air (2236986)..... PA1800 + Comp. Breather (2467368)..... PA1704 Comp. Breather (8875051)..... PA1909	<b>4000-6500 Series w/GMC V8-427 Eng.</b> 1 Qt. Lube Ele..... P18 2 Qt. Lube Ele..... P476 5 5/16 In. Lube Spin-on..... B6 + 8 23/32 In. Lube Spin-on..... B7 Fuel Ele..... PF827 Air (2236986)..... PA1800 + Air (6423239)..... PA1798 + Air (702025)..... PA1922-FN Comp. Breather (8875051)..... PA1909
<b>4000-6500 Series w/GMC 6 Cyl. 292 Eng.</b> Lube Ele. (1963-67)..... P20-HD + Lube Ele. (1968-on)..... P476 4 3/8 In. Lube Spin-on..... B27 5 5/16 In. Lube Spin-on..... B6 + 8 23/32 In. Lube Spin-on..... B7 1 1/32 In. Fuel Ele. (Carb.)..... PF893 3 15/32 In. Fuel Ele..... PF827 In-Line Fuel..... BF840 + Fuel (SintBronze) (7013404)..... SF898 Air (1962-67) (5645017)..... PA625 Air (1968-72) (6424027)..... PA1841 Air (1968-72) (6483864)..... PA1680 Air (1971-on) (5648003)..... PA648 Comp. Breather (Bendix)..... PA1600 Comp. Breather (Midland)..... PA1909	<b>4000-6500 Series w/GMC V6-379 Eng.</b> Lube Ele..... P20-HD + 4 3/8 In. Lube Spin-on..... B39 5 9/32 In. Lube Spin-on..... B9 In-Line Fuel..... BF836 Fuel Ele..... PF827 Air (2236986)..... PA1800 + Air (702025)..... PA1922-FN Comp. Breather (2467368)..... PA1704 Comp. Breather (8875051)..... PA1909	<b>4000-6500 Series w/GMC D478, DH478 Diesel Eng.</b> Lube Ele. (1964-74)..... P20-HD + P. Fuel Sock..... F916-C P. Fuel Ele..... PF902 Comp. Breather (2467368)..... PA1704 Comp. Breather (8875051)..... PA1909 Comp. Breather (9028042)..... PA1600
<b>4000-6500 Series w/GMC V6-305C Eng.</b> Lube Ele..... P20-HD + 4 3/8 In. Lube Spin-on..... B39 5 9/32 In. Lube Spin-on..... B9 In-Line Fuel (5650780)..... BF840-K1 + 11/16 In. O.D. Fuel (5651393)..... PF893 1 3/4 In. O.D. Fuel (854347)..... PF857 2 1/16 In. O.D. Fuel..... PF827 Air (2236986)..... PA1800 + Air (2493708)..... PA1786 Air (5645017)..... PA625 Air (6423239)..... PA1798 + Air (702025)..... PA1922-FN Comp. Breather (2467368)..... PA1704 Comp. Breather (8875051)..... PA1909 Comp. Breather (9028042)..... PA1600	<b>4000-6500 Series w/GMC V6-432 Eng.</b> Lube Ele. (1966-on)..... P20-HD + In-Line Fuel..... BF836 Air (1973-on) (2236986)..... PA1800 + Air (702025)..... PA1922-FN Comp. Breather (2467368)..... PA1704 Comp. Breather (8875051)..... PA1909	<b>4500 w/D351 Diesel Eng.</b> Lube Ele..... P20-HD + Fuel Ele..... PF902
<b>4000-6500 Series w/GMC V6-478 Eng.</b> Lube Ele..... P20-HD + Fuel Ele..... PF827 Air (w/Foam Wrap)..... PA1800 + Air (w/o Foam Wrap)..... PA1798 +	<b>6500 w/Cat 3208 Eng.</b> Lube Spin-on..... [2] BT364 Box-Style Fuel/Water Separator. BF912 Fuel Spin-on..... BF970 + Air (2009007)..... PA2465	<b>6500 w/V6-401M Eng.</b> Lube Ele..... P20-HD + In-Line Fuel..... BF840 + Comp. Breather (2467368)..... PA1704 Comp. Breather (8875051)..... PA1909


+ See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

GENERAL MOTORS CORP. Trucks, Buses & Vans (cont'd)	GENERAL MOTORS CORP. Trucks, Buses & Vans (cont'd)	GENERAL MOTORS CORP. Trucks, Buses & Vans (cont'd)
7000 Series w/Cat 3208 Eng. Box-Style Fuel/Water Separator. BF912 Fuel Spin-on..... BF970 +	7500, 8500 Series w/V6-478 Eng. (Cont'd) Comp. Breather (2467368)..... PA1704 Comp. Breather (8875051)..... PA1909	9500, 9502 Series w/Cummins Eng. (Cont'd) Trans. Breather (Fuller RT510) (2355484)..... P187 Coolant..... BW5071
7500 Series w/Cat 3208 Eng. Lube..... BT364 Box-Style Fuel/Water Separator. BF912 Fuel Spin-on..... BF970 + Air (2009007)..... PA2465 Comp. Breather (8875051)..... PA1909	7500, 9000 Series w/V6-351 Eng. Lube Ele..... P20-HD + 2 1/8 In. Fuel..... PF860 3 15/32 In. Fuel..... PF827	9500, 9502 Series w/GMC 6-71, 6-71N, 6V-71N, 8V-71N, 8V-71T, 8V-71TT Eng. F-F Lube Ele..... P20-HD + B-P Lube Ele..... C750-E + P. Fuel Sock (5574961)..... F916-C P. Fuel Sock (5574980)..... F844-A P. Fuel Ele. (5575032)..... PF845 P. Fuel Spin-on..... BF5800 + S. Fuel Ele. (5574508)..... PF902 S. Fuel Ele. (6436719)..... PF846 S. Fuel Spin-on..... BF5810 Air (1971-on) (684801)..... PA2316 Air (2017021)..... PA2503 Air (2034763)..... PA2531 Air (2034764)..... PA2532 Air (654158)..... PA1892-FN <sup>90</sup> Air (717702)..... PA2515 Std. Air (9034222)..... PA1846 + Air (Upgrade) (9034222)..... PA1846XP Air (Farr C45800)..... PA2350 Air (Don. P126442)..... PA2516 Air (Don. P129396)..... PA3951 Air (Don. P129472)..... PA2500 + Comp. Breather (2467368)..... PA1704 Comp. Breather (9028042)..... PA1600 Trans. Breather (Fuller) (2355484)..... P187 Coolant Spin-on (Maintenance).. BW5137 Coolant Spin-on (Pre-Charge).... BW5139
7500 Series w/V6-432M Eng. Lube Ele..... P20-HD + Fuel Ele..... PF827 Air (United 250A28)..... PA1798 + Air (Don. Hsg.)..... PA1922-FN Comp. Breather (2467368)..... PA1704 Comp. Breather (8875051)..... PA1909	7500, 9500 Series w/6V-53N Diesel Eng. F-F Lube Ele..... P20-HD + B-P Lube Ele..... C750-E + 5 3/4 In. P. Fuel Sock..... F916-C 8 5/16 In. P. Fuel Ele..... PF845 P. Fuel Spin-on..... BF5800 + S. Fuel Ele..... PF906 S. Fuel Spin-on..... BF5810 Comp. Breather (2467368)..... PA1704 Comp. Breather (8875051)..... PA1909 Comp. Breather (9028042)..... PA1600	9500, 9502 Series w/GMC 6V-92N, 6V-92T, 6V-92TT, 8V-92N, 8V-92T, 8V-92TT Eng. F-F Lube Ele..... P20-HD + B-P Lube Ele..... C750-E + P. Fuel Ele..... PF845 P. Fuel Spin-on..... BF5800 + S. Fuel Ele..... PF902 S. Fuel Spin-on..... BF5810 Air (2010760)..... PA2500 + Air (2014558)..... PA3951 Air (2017021)..... PA2503 Air (2034764)..... PA2532 Std. Air (700016)..... PA1846 + Air (Upgrade)..... PA1846XP Air (717714)..... PA2516 Air (Farr C45800)..... PA2350 Air (Don. P124490)..... PA2515 Coolant Spin-on..... BW5137
7500 Series w/V8-427 Eng. 1 Qt. Lube Ele..... P18 2 Qt. Lube Ele..... P476 5 5/16 In. Lube Spin-on..... B6 + 8 23/32 In. Lube Spin-on..... B7 Fuel Ele..... PF827 Air (2236986)..... PA1800 + Air (6423239)..... PA1798 + Comp. Breather (8875051)..... PA1909	7500, 9500 Series w/D637, DH637 Diesel Eng. F-F Lube Ele. (1964-74)..... P20-HD + B-P Lube Ele..... C750-E + Fuel Ele..... PF902 Comp. Breather (2467368)..... PA1704 Comp. Breather (8875051)..... PA1909 Trans. Breather (Fuller RT510) (2355484)..... P187	9502 w/Cat 3406 Eng. Lube..... B99 + B-P Lube Ele..... C750-E + Fuel Spin-on..... BF614 + Std. Air (700016)..... PA1846 + Air (Upgrade) (700016)..... PA1846XP Coolant..... BW5137
7500 Series w/D478, DH478 Diesel Eng. Lube Ele. (1964-74)..... P20-HD + P. Fuel Ele..... PF902 Comp. Breather (2467368)..... PA1704 Comp. Breather (8875051)..... PA1909	7500, 9502 Series w/V8-637 Eng. F-F Lube Ele..... P20-HD + B-P Lube Ele..... C750-E + Fuel Ele. (1966-72)..... PF827 Fuel Ele. (1970-72) (5574508).... PF902 Air (8877141)..... PA1798 + Comp. Breather (2467368)..... PA1704 Comp. Breather (8875051)..... PA1909 Trans. Breather (1966-72, (Fuller RT910))..... P187	
7500, 8500 Series w/V6-351C Eng. Lube Ele..... P20-HD + 4 3/8 In. Lube Spin-on..... B39 5 9/32 In. Lube Spin-on..... B9 In-Line Fuel..... BF840 + 1 1/32 In. Fuel Ele..... PF857 3 15/32 In. Fuel Ele..... PF827 Air (2493708)..... PA1786 Air (5645017)..... PA625 Air (8877141)..... PA1798 + Comp. Breather (2467368)..... PA1704 Comp. Breather (8875051)..... PA1909	8500, C8500 Series w/Cat 3126 Eng. Lube (Standard Vers.)..... B76 Fuel..... BF7632	
7500, 8500 Series w/V6-351M, V6-401M Eng. Lube Ele..... P20-HD + In-Line Fuel..... BF840 + Fuel Ele..... PF827 Air (6420690)..... PA625 Air (8877141)..... PA1798 + Comp. Breather (2467368)..... PA1704 Comp. Breather (8875051)..... PA1909	9500, 9502 Series w/Cummins Eng. F-F Lube Ele..... P999-HD B-P Lube Ele..... C750-E + F-F Lube Spin-on..... B196 + Fuel/Water Separator..... BF1212 + 4 3/8 In. Fuel Spin-on..... BF948 + 5 3/4 In. Fuel Spin-on..... BF957 + Air (2017021)..... PA2503 Air (706193)..... PA2468 <sup>90</sup> Std. Air (Don. P106632)..... PA1846 + Air (Upgrade) (Don. P106632)..... PA1846XP Air (Don. P118398)..... PA1892-FN <sup>90</sup> Air (Don. P121471)..... PA2316 Air (Don. P124490)..... PA2515 Air (Don. P126442)..... PA2516 Breather Ele. (w/Turbo) (255963) PA643 Breather Ele. (w/o Turbo) (256837)..... PA1627	
7500, 8500 Series w/V6-478 Eng. Lube Ele..... P20-HD + In-Line Fuel..... BF840 + Fuel Ele..... PF827 Air (United 250A28)..... PA1798 + Air (6420690)..... PA625 Air (702025)..... PA1922-FN Air (8877141)..... PA1800 +		

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).


GENERAL MOTORS CORP. Trucks, Buses & Vans (cont'd)	GENERAL MOTORS CORP. Trucks, Buses & Vans (cont'd)	GENERAL MOTORS CORP. Trucks, Buses & Vans (cont'd)
9502 Series w/GMC 12V-71 Eng. F-F Lube Ele..... [2] P20-HD + B-P Lube Ele..... [2] C750-E + 9 In. P. Fuel Sock (5574980)..... F844-A P. Fuel Spin-on..... BF5800 + S. Fuel Ele. (6436719)..... PF846 S. Fuel Spin-on..... BF5810 Std. Air (700016)..... PA1846 + Air (Upgrade) (700016)..... PA1846XP Coolant..... BW5137	Astro w/Detroit Diesel 6V-92 (9.0L) Eng. F-F Lube Ele..... P20-HD + B-P Lube Ele..... C750-E + P. Fuel Spin-on..... BF5800 + S. Fuel Spin-on..... BF5810 Air (w/Lid) (15515589)..... PA2333 Conical Air (2014558)..... PA3951 Air (29 In.) (2017021)..... PA2503 Coolant..... BW5137	B7 w/V8-395 (6.5L) Turbo Diesel Eng. (Cont'd) S. Fuel/Water Separator (ACDelco TP1263)..... BF7674-D P. Fuel (ACDelco TP936)..... BF592 + Std. Air (ACDelco A348C)..... PA2008 Radial Seal O. Air (15696245)..... RS2863 Radial Seal XP O. Air (Upgrade) (15696245)..... RS2863XP Radial Seal I. Air (12544543)..... RS3501 Trans. (25011122)..... BT230
Astro w/Cat 3406 (14.6L) Eng. Lube..... B99 + Fuel Spin-on..... BF614 + Conical Air (2014558)..... PA3951 Std. Air (700016)..... PA1846 + Air (Upgrade) (700016)..... PA1846XP	Astro w/Detroit Diesel 8V-71 Series Eng. F-F Lube Ele..... P20-HD + B-P Lube Ele..... C750-E + P. Fuel Spin-on..... BF5800 + S. Fuel Spin-on..... BF5810 Std. Air (700016)..... PA1846 + Air (Upgrade) (700016)..... PA1846XP Conical Air (2014558)..... PA3951 Air (29 In.) (2017021)..... PA2503 Coolant..... BW5137	B7 w/V8-427 (7.0L) Eng. Lube (1 Qt.) (ACDelco PF1218).... B1428 + Lube (2 Qt.) (25010754)..... B7 Fuel In-Line (25055052)..... BF853 Std. Air (ACDelco A348C)..... PA2008 Trans. (25011122)..... BT230
Astro w/Cummins KT450 Eng. F-F Lube Spin-on..... [2] B196 + B-P Lube Ele..... C750-E + Fuel Spin-on..... BF957 +	Astro w/Detroit Diesel 8V-92 Series Eng. F-F Lube Ele..... P20-HD + B-P Lube Ele..... C750-E + P. Fuel Spin-on..... BF5800 + S. Fuel Spin-on..... BF5810 Air (w/Lid) (15515589)..... PA2333 Conical Air (2014558)..... PA3951 Std. Air (2067009)..... PA2658 Coolant..... BW5137	B7 w/V8-454 (7.4L) Eng. 3 3/16 In. Lube (ACDelco PF454)..... B1438 5 11/32 In. Lube (ACDelco PF1218)..... B1428 + Fuel In-Line (ACDelco GF652).... BF853 Radial Seal Air (ACDelco A1301C)..... RS3706 Trans. (25011122)..... BT230
Astro w/Cummins N14 (14.0L) Eng. F-F Lube (Fleetguard LF670SC).. B196 + B-P Lube (3304232)..... B7577 Dual-Flow Lube (3318853)..... BD103 + Fuel/Water Separator (3308638). BF1212 + Fuel (154789)..... BF957-D +	B7 w/Cat 3116 (6.6L) Eng. Lube (Standard Vers.) (1R0739).. B76 + Lube (High Efficiency Vers.) (1R-1807)..... B7700 + Lube (Severe Service) (1R0739).. B76-SS + Fuel/Water Separator (8N9803).. BF912 Fuel (1R0750)..... BF7633 + Trans. (3.8 In. Pan) (Allison 29540976)..... 19992 + Trans. (5.3 In. Pan) (Allison 29538489)..... 19739 +	B7 w/V8-496 (8.1L) Eng. 3 3/16 In. Lube (ACDelco PF454)..... B1438 5 11/32 In. Lube (ACDelco PF1218)..... B1428 + Fuel In-Line (ACDelco GF481).... BF853 Radial Seal Air (ACDelco A1301C)..... RS3706 Trans. (25011122)..... BT230
Astro w/Cummins NTC290, NTC350, NTC400 Eng. F-F Lube Ele..... P999-HD F-F Lube Spin-on..... B196 + B-P Lube Ele..... C750-E + Fuel Spin-on..... BF957 + Air (w/Lid) (15515589)..... PA2333 Air (29 In.) (2017021)..... PA2503 Std. Air (700016)..... PA1846 + Air (Upgrade) (700016)..... PA1846XP	B7 w/Cat 3126 (7.2L) Eng. Lube (Standard Vers.) (1R0739).. B76 + Lube (Severe Service) (1R0739).. B76-SS + Fuel (1R0751)..... BF7632	B6000 w/V8-366 (6.0L) Eng. F-F Lube..... B7 Lube (25160561)..... B1428 Fuel Ele..... PF827 Comp. Air..... PA1909 Trans. (Allison AT540)..... 19992 +
Astro w/Cummins NTC300, Formula 300, Formula 400 Eng. F-F Lube Spin-on..... B196 + B-P Lube Ele..... C750-E + B-P Lube Spin-on..... B7577 Fuel Spin-on..... BF957 + Air (w/Lid) (15515589)..... PA2333 Air (29 In.) (2017021)..... PA2503 Std. Air (700016)..... PA1846 + Air (Upgrade) (700016)..... PA1846XP Coolant..... BW5071	B7 w/V8-366 (6.0L) Eng. Lube (ACDelco PF35)..... B6 + Fuel (ACDelco GF173)..... PF827 3 15/32 In. Air (6484235)..... PA2008 5 9/16 In. Air (6423239)..... PA1798 +	B6000 w/V8-427 (7.0L) Eng. Lube..... B7 Fuel Ele..... PF827 Comp. Air..... PA1909 Trans. (Allison AT540)..... 19992 +
Astro w/Detroit Diesel 6-71N, 6-71T Eng. F-F Lube Ele..... P20-HD + B-P Lube Ele..... C750-E + P. Fuel Spin-on..... BF5800 + S. Fuel Spin-on..... BF5810 Conical Air (2014558)..... PA3951 Std. Air (700016)..... PA1846 + Air (Upgrade) (700016)..... PA1846XP Coolant..... BW5137	B7 w/V8-395 (6.5L) Turbo Diesel Eng. Lube (w/o Anti-Drainback Valve) (ACDelco PF35L)..... B6-HPG + Lube (w/Anti-Drainback Valve) (ACDelco PF1218)..... B1428 + P. Fuel/Water Separator (w/Drain) (Racor S3212)..... BF1266 P. Fuel/Water Separator (Open End for Bowl) (Racor S3212)..... BF1278-O	B6000 w/Cummins N14 (14.0L) Eng. F-F Lube (Fleetguard LF670SC).. B196 + Dual-Flow Lube (3318853)..... BD103 + B-P Lube (3304232)..... B7577 Opt. Fuel/Water Separator (3308638)..... BF1212 + Fuel (154789)..... BF957-D + Coolant (3315116)..... BW5071
		B6000, C5000, C6000 w/V8-350 (5.7L) Eng. 1 Qt. Lube..... B6 + 2 Qt. Lube..... B7 1 1/32 In. Fuel (Rochester Carb.).. PF893 3 15/32 In. Fuel Ele..... PF827

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

GENERAL MOTORS CORP. Trucks, Buses & Vans (cont'd)	GENERAL MOTORS CORP. Trucks, Buses & Vans (cont'd)	GENERAL MOTORS CORP. Trucks, Buses & Vans (cont'd)
B6000, C5000, C6000 w/V8-350 (5.7L) Eng. (Cont'd)	Brigadier w/Cummins N14 Eng.	Brigadier w/Detroit Diesel 6V-92N (9.0L) Eng. (Cont'd)
Air (Std.) (6422556)..... PA1800 +	F-F Lube (Fleetguard LF670SC).. B196 +	Coolant..... BW5137
Air (w/Fins) (702025)..... PA1922-FN	B-P Lube (3304232)..... B7577	Brigadier w/Detroit Diesel 8V-71N (9.3L) Eng.
Comp. Air..... PA1909	Dual-Flow Lube (3318853)..... BD103 +	F-F Lube Ele..... P20-HD +
Trans. (Allison AT540)..... 19992 +	Fuel/Water Separator (3308638). BF1212 +	B-P Lube Ele..... C750-E +
B6000, C6000, C7000 w/Detroit Diesel 8.2L Eng.	Fuel (154789)..... BF957-D +	P. Fuel Spin-on..... BF5800 +
Lube..... [2] B6 +	Brigadier w/Cummins NTC290 Eng.	S. Fuel Spin-on..... BF5810
P. Fuel Spin-on..... BF592 +	F-F Lube Ele..... P999-HD	Air (1979) (2034764)..... PA2532
S. Fuel Spin-on..... BF593	F-F Lube Spin-on..... B196 +	Air (1980) (2017021)..... PA2503
Air (2062062)..... PA2599	B-P Lube Ele..... C750-E +	Air (2014558)..... PA3951
Comp. Air..... PA1909	Fuel Spin-on..... BF957 +	Air (2052116)..... PA2482
Trans. (Allison AT540)..... 19992 +	Air (1979) (2034764)..... PA2532	Comp. Air (Midland 100696A)..... PA1909
Brigadier w/V8-427 (7.0L) Eng.	Air (1980) (2017021)..... PA2503	Coolant..... BW5137
Lube..... B7	Air (2014558)..... PA3951	C3500HD w/V8-350 (5.7L) FI Eng. (VIN K)
Fuel Ele..... PF827	Comp. Air..... PA1909	Lube (25160561)..... B1428 +
Air (6422556)..... PA1800 +	Brigadier w/Cummins NTC300 Eng.	In-Line Fuel (25171792)..... BF853
Comp. Air (Midland 100696A)..... PA1909	F-F Lube Spin-on..... B196 +	Air (6484235)..... PA2008
Brigadier w/Cat 3208 (10.4L) Eng.	B-P Lube Ele..... C750-E +	Trans. (8684221)..... 18007
F-F Lube (9L9200)..... [2] BT364	Fuel Spin-on..... BF957 +	C3500HD w/V8-395 (6.5L) Turbo Diesel Eng. (VIN F) (1992-96)
F-F Lube (9N5570)..... [2] BT230	Air (2014558)..... PA3951	Lube (ACDelco PF1218)..... B1428 +
B-P Lube Ele..... C750-E +	Air (2017021)..... PA2503	Fuel/Water Separator (ACDelco TP1256)..... BF1201
Box-Style Fuel/Water Separator. BF912	Comp. Air..... PA1909	In-Line Fuel (12339208)..... BF46007
Fuel Spin-on..... BF970 +	Brigadier w/Cummins NTC350 Eng.	Panel Air (ACDelco A1236C)..... PA2232
Air (15506047)..... PA2656	F-F Lube Ele..... P999-HD	Trans. (8684221)..... 18007
Air (2009007)..... PA2465	F-F Lube Spin-on..... B196 +	C3500HD w/V8-395 (6.5L) Turbo Diesel Eng. (VIN F) (1997-2002)
Comp. Air..... PA1909	B-P Lube Ele..... C750-E +	Lube (ACDelco PF1218)..... B1428 +
Brigadier w/Cat 3406 (14.6L) Eng. (1981-83)	Fuel Spin-on..... BF957 +	Fuel/Water Separator (ACDelco TP1256)..... BF1201
Lube..... B99 +	Air (1979) (2034764)..... PA2532	In-Line Fuel (12339208)..... BF46007
Fuel Spin-on..... BF614 +	Air (1980) (2017021)..... PA2503	Radial Seal Air (Std.) (ACDelco A1300C)..... RS3707
Brigadier w/Cummins Formula 300 Eng.	Air (2014558)..... PA3951	Radial Seal Air (w/Foam) (ACDelco A1306C)..... RS3735 <sup>90</sup>
F-F Lube Spin-on..... B196 +	Comp. Air..... PA1909	Trans. (24210956)..... 18027
B-P Lube Spin-on..... B7577	Brigadier w/Cummins VT225 Eng.	C3500HD w/V8-454 (7.4L) FI Eng. (VIN N) (1991-95)
Fuel Spin-on..... BF957 +	F-F Lube Ele..... P999-HD	Lube (25160561)..... B1428 +
Air (2014558)..... PA3951	F-F Lube Spin-on..... B196 +	In-Line Fuel (25171792)..... BF853
Air (2017021)..... PA2503	Fuel Spin-on..... BF957 +	Air (6484235)..... PA2008
Coolant..... BW5071	Coolant Spin-on..... BW5071	Trans. (8684221)..... 18007
Brigadier w/Cummins Formula 350 Eng.	Brigadier w/Detroit Diesel 6V-53N (5.2L) Eng.	C3500HD w/V8-454 (7.4L) FI Eng. (VIN J) (1996)
F-F Lube Spin-on..... B196 +	F-F Lube Ele..... P20-HD +	Lube (25160561)..... B1428 +
B-P Lube Spin-on..... B7577	P. Fuel Spin-on..... BF5800 +	In-Line Fuel (25171792)..... BF853
Fuel Spin-on..... BF957 +	S. Fuel Spin-on..... BF5810	Radial Seal Air (Std.) (25168081) RS3707
Air (2014558)..... PA3951	Air (2052116)..... PA2482	Radial Seal Air (w/Foam) (25173426)..... RS3735 <sup>90</sup>
Air (2017021)..... PA2503	Comp. Air..... PA1909	Radial Seal Air (Heavy Duty) (25168082)..... RS3706
Coolant..... BW5071	Brigadier w/Detroit Diesel 6-71 (7.0L) Eng. (1981-88)	Trans. (8684221)..... 18007
Brigadier w/Cummins L10 (10.0L) Eng. (1984-88)	Lube (23530407)..... B95 +	
F-F Lube Spin-on..... B196 +	P. Fuel (23530706)..... BF5800 +	
B-P Lube Spin-on..... B7577	S. Fuel (23530707)..... BF5810	
Fuel Spin-on..... BF957 +	Opt. Trans. (Fuller 17237)..... B2 +	
Air (2014558)..... PA3951	Brigadier w/Detroit Diesel 6V-92N (9.0L) Eng.	
Air (2017021)..... PA2503	F-F Lube Ele..... P20-HD +	
Coolant..... BW5071	B-P Lube Ele..... C750-E +	
	P. Fuel Spin-on..... BF5800 +	
	S. Fuel Spin-on..... BF5810	
	Air (1979) (2034764)..... PA2532	
	Air (1980) (2017021)..... PA2503	
	Air (2014558)..... PA3951	
	Air (2052116)..... PA2482	
	Comp. Air (Midland 100696A)..... PA1909	

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

GENERAL MOTORS CORP. Trucks, Buses & Vans (cont'd)	GENERAL MOTORS CORP. Trucks, Buses & Vans (cont'd)	GENERAL MOTORS CORP. Trucks, Buses & Vans (cont'd)
C3500HD w/V8-454 (7.4L) FI Eng. (VIN J) (1997-5/10/1999)	C4500 TopKick w/V8 6.6L Turbo Diesel (LLY) Eng. (2004-07)	C4500 TopKick w/V8-496 (8.1L) Eng. (2005-on) (Cont'd)
Lube (25160561)..... <b>B1428 +</b>	Lube (ACDelco PF2232)..... <b>B1441</b>	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
In-Line Fuel (25171792)..... <b>BF853</b>	Fuel/Water Separator (Upgrade) (ACDelco TP3018)..... <b>BF46062<sup>89</sup></b>	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
Radial Seal Air (Std.) (25168081) <b>RS3707</b>	Radial Seal Air (ACDelco A2032C)..... <b>RS4859</b>	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
Radial Seal Air (w/Foam) (25173426)..... <b>RS3735<sup>90</sup></b>	Panel Air (ACDelco A3102C)..... <b>PA5428</b>	Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>
Radial Seal Air (Heavy Duty) (25168082)..... <b>RS3706</b>	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	Steering (88892858)..... <b>P106-HD</b>
Trans. (24208847)..... <b>18027</b>	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	C5000 w/Detroit Diesel 8.2L Naturally Aspirated Eng.
C3500HD w/V8-454 (7.4L) FI Eng. (VIN J) (5/10/99-2000)	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	Lube..... <b>[2] B6 +</b>
Lube (25324052)..... <b>B1438</b>	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	P. Fuel..... <b>BF592 +</b>
In-Line Fuel (25171792)..... <b>BF853</b>	Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>	S. Fuel..... <b>BF593</b>
Radial Seal Air (Std.) (25168081) <b>RS3707</b>	Steering (88892858)..... <b>P106-HD</b>	Air (2062063)..... <b>PA2596</b>
Radial Seal Air (w/Foam) (25173426)..... <b>RS3735<sup>90</sup></b>	C4500 TopKick w/V8 6.6L Turbo Diesel (LMM) Eng. (2007-09)	C5000 w/Detroit Diesel 8.2L Turbocharged Eng.
Radial Seal Air (Heavy Duty) (25168082)..... <b>RS3706</b>	Lube (ACDelco PF2232)..... <b>B1441</b>	Lube..... <b>[2] B6 +</b>
Trans. (24208847)..... <b>18027</b>	Fuel/Water Separator (Upgrade) (ACDelco TP3018)..... <b>BF46062<sup>89</sup></b>	P. Fuel..... <b>BF592 +</b>
C3500HD w/V8-454 (7.4L) FI Eng. (VIN J) (2001-02)	Radial Seal Air (ACDelco A2032C)..... <b>RS4859</b>	S. Fuel..... <b>BF593</b>
Lube (25324052)..... <b>B1438</b>	Panel Air (ACDelco A3102C)..... <b>PA5428</b>	Air (2062062)..... <b>PA2599</b>
In-Line Fuel (25171792)..... <b>BF853</b>	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	C5000 w/6 Cyl. (4.8L) Eng.
Radial Seal Air (Std.) (25168081) <b>RS3707</b>	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	Lube..... <b>B6 +</b>
Radial Seal Air (w/Foam) (25173426)..... <b>RS3735<sup>90</sup></b>	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	1 1/32 In. Fuel (Rochester Carb.) <b>PF893</b>
Radial Seal Air (Heavy Duty) (25168082)..... <b>RS3706</b>	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	3 15/32 In. Fuel Ele..... <b>PF827</b>
C3500HD w/V8-496 (8.1L) FI Eng. (VIN G)	Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>	Air (United 250A35WR)..... <b>PA648</b>
Lube (ACDelco PF454)..... <b>B1438</b>	Steering (88892858)..... <b>P106-HD</b>	C5000 Topkick w/V8-366 (6.0L) Eng.
In-Line Fuel (ACDelco GF652).... <b>BF853</b>	C4500 TopKick w/V8-496 (8.1L) Eng. (2003-04)	Fuel Ele. (5651879)..... <b>PF827</b>
Radial Seal Air (Std.) (ACDelco A1300C)..... <b>RS3707</b>	Lube (ACDelco PF454)..... <b>B1438</b>	Fuel In-Line (25171792)..... <b>BF853</b>
Radial Seal Air (w/Foam) (ACDelco A1306C)..... <b>RS3735<sup>90</sup></b>	Fuel (ACDelco GF652)..... <b>BF853</b>	Fuel Spin-on (25010793)..... <b>BF5800 +</b>
Trans. (24210956)..... <b>18027</b>	Axial Seal Air (25313349)..... <b>PA4113</b>	C5500 Topkick w/V8 6.6L Turbo Diesel LB7 Eng. (2003-04)
C4500 TopKick w/V8 6.6L Turbo Diesel (LB7) Eng. (2003-04)	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	Lube (ACDelco PF2232)..... <b>B1441</b>
Lube (ACDelco PF2232)..... <b>B1441</b>	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	Fuel/Water Separator (Upgrade) (ACDelco TP3018)..... <b>BF46062<sup>89</sup></b>
Fuel/Water Separator (Upgrade) (ACDelco TP3018)..... <b>BF46062<sup>89</sup></b>	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	Fuel (ACDelco TP1247)..... <b>BF790</b>
Radial Seal Air (ACDelco A2032C)..... <b>RS4859</b>	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20017</b>	Radial Seal Air (88937527)..... <b>RS4859</b>
Panel Air (ACDelco A3102C)..... <b>PA5428</b>	Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>	Panel Air (ACDelco A3102C)..... <b>PA5428</b>
Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	Steering (88892858)..... <b>P106-HD</b>	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	C4500 TopKick w/V8-496 (8.1L) Eng. (2005-on)	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	Lube (ACDelco PF454)..... <b>B1438</b>	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20017</b>	Radial Seal Air (88937527)..... <b>RS4859</b>	Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>
Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
Steering (88892858)..... <b>P106-HD</b>		Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
		Steering (88892858)..... <b>P106-HD</b>


+ See Product Guide for Variations of This Number. <sup>89</sup> Inner Fender Liner Removal Recommended for Proper Installation. <sup>90</sup> Obsolete Pending. Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

GENERAL MOTORS CORP. Trucks, Buses & Vans (cont'd)	GENERAL MOTORS CORP. Trucks, Buses & Vans (cont'd)	GENERAL MOTORS CORP. Trucks, Buses & Vans (cont'd)
C5500 Topkick w/V8 6.6L Turbo Diesel LLY Eng. (2004-07)	C5500 Topkick w/V8-496 (8.1L) Eng. (2003-04) (Cont'd)	C6000 w/Cat 3208 (10.4L) Eng.
Lube (ACDelco PF2232)..... B1441	Trans. Spin-on (Allison 29539579)..... BT8460	Lube (1R0713)..... [2] BT230 +
Fuel/Water Separator (Upgrade) (ACDelco TP3018)..... BF46062 <sup>89</sup>	Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	Lube (1R0714)..... [2] B75
Fuel (ACDelco TP1247)..... BF790	Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Lube (9L9200)..... [2] BT364
Radial Seal Air (88937527)..... RS4859	Steering (88892858)..... P106-HD	Box-Style Fuel/Water Separator (8N9803)..... BF912
Panel Air (ACDelco A3102C)..... PA5428	C5500 Topkick w/V8-496 (8.1L) Eng. (2005-on)	P. Fuel Ele. (9M2341)..... PF935
Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004	Lube (ACDelco PF454)..... B1438	P. Fuel Spin-on (1R0740)..... BF970 +
Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016	Fuel (ACDelco TP1247)..... BF790	S. Fuel Spin-on (1R0750)..... BF7633 +
Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003	Radial Seal Air (ACDelco A2032C)..... RS4859	C6000 w/Cummins N14 (14.0L) Eng.
Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004	F-F Lube (Fleetguard LF670SC).. B196 +
Trans. Spin-on (Allison 29539579)..... BT8460	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016	Dual-Flow Lube (3318853)..... BD103 +
Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003	B-P Lube (3304232)..... B7577
Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017	Opt. Fuel/Water Separator (3308638)..... BF1212 +
Steering (88892858)..... P106-HD	Trans. Spin-on (Allison 29539579)..... BT8460	Fuel (154789)..... BF957-D +
C5500 Topkick w/V8 6.6L Turbo Diesel LMM Eng. (2007-09)	Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	Coolant (3315116)..... BW5071
Lube (ACDelco PF2232)..... B1441	Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	C6000, C7000 w/Detroit Diesel 4-53T Eng.
Fuel/Water Separator (Upgrade) (ACDelco TP3018)..... BF46062 <sup>89</sup>	Steering (88892858)..... P106-HD	F-F Lube Ele..... P20-HD +
Fuel (ACDelco TP1247)..... BF790	C6000 w/6 Cyl. (4.8L) Eng.	P. Fuel Sock..... F916-C
Radial Seal Air (88937527)..... RS4859	Lube..... B6 +	S. Fuel Ele..... PF906
Panel Air (ACDelco A3102C)..... PA5428	1 1/32 In. Fuel (Rochester Carb.)..... PF893	Std. Air (2014573)..... PA2550
Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004	3 15/32 In. Fuel Ele..... PF827	Conical Air (2031381)..... PA2540 +
Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016	Air (United 250A35WR)..... PA648	Comp. Air..... PA1909
Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003	C6000 w/V8-366 (6.0L) Carb. Eng.	C6000 TopKick w/V8-366 (6.0L), V8-427 (7.0L) Eng.
Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017	F-F Lube (8N9586)..... BT230 +	Lube..... B7
Trans. Spin-on (Allison 29539579)..... BT8460	B-P Lube Ele. (15525633)..... C750-E +	Fuel Ele..... PF827
Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	Lube (25160561)..... B1428	Air (w/Foam) (6422556)..... PA1800 +
Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Fuel Ele. (5651879)..... PF827	Air (w/Fins) (702025)..... PA1922-FN
Steering (88892858)..... P106-HD	Fuel Spin-on (25010793)..... BF5800 +	Comp. Air..... PA1909
C5500 Topkick w/V8-496 (8.1L) Eng. (2003-04)	Air (25041372)..... PA2599	C6000 TopKick w/Cat 3116 Eng.
Lube (ACDelco PF454)..... B1438	Air (25043585)..... PA2148 +	Lube (Standard Vers.) (1R0739).. B76
Fuel (ACDelco GF652)..... BF853	Air (6487958)..... PA2008	Lube (High Efficiency Vers.) (1R1807)..... B7700 +
Air (25313349)..... PA4113	C6000 w/V8-366 (6.0L) FI. Eng.	Box-Style Fuel/Water Separator..... BF912
Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004	F-F Lube (8N9586)..... BT230 +	Std. Fuel (1R0740)..... BF970 +
Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016	B-P Lube Ele. (15525633)..... C750-E +	Fuel (High Efficiency) (1R0750).... BF7633 +
Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003	Fuel Ele. (5651879)..... PF827	P. Fuel Spin-on (7E9763)..... BF984
Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017	Fuel In-Line (25055480)..... BF853	Radial Seal O. Air (15619013).... RS2863
	Fuel Spin-on (25010793)..... BF5800 +	Radial Seal O. Air (Upgrade) (15619013)..... RS2863XP
	Air (25041372)..... PA2599	Radial Seal I. Air..... RS3501
	Air (25043585)..... PA2148 +	Breather (9L2169)..... PA1704
	Air (6487958)..... PA2008	Coolant (4 Units BTE) (9N3717).. BW5137
	C6000 w/V8-427 (7.0L) Eng.	Coolant (8 Units BTE) (9N6123).. BW5139
	F-F Lube (8N9586)..... BT230 +	Trans. Pan-Type (Allison 29538489)..... 19739 +
	B-P Lube Ele. (15525633)..... C750-E +	Trans. Spin-on (Allison 29510922)..... BT8316-MPG
	Fuel Ele. (5651879)..... PF827	C6500 TopKick w/Cat 3116 (6.6L) Eng.
	Fuel Spin-on (25010793)..... BF5800 +	Lube (Standard Vers.) (1R0739).. B76 +
	Air (25041372)..... PA2599	Lube (Severe Service) (1R0739).. B76-SS +
	Air (25043585)..... PA2148 +	Fuel (1R0751)..... BF7632
	Air (6487958)..... PA2008	Radial Seal O. Air..... RS2863
	C6000 w/V8-427 (7.0L) Eng.	Radial Seal O. Air (Upgrade)..... RS2863XP
	F-F Lube (8N9586)..... BT230 +	Trans. (ACDelco PF897F)..... BT230
	B-P Lube Ele. (15525633)..... C750-E +	
	Fuel Ele. (5651879)..... PF827	
	Fuel Spin-on (25010793)..... BF5800 +	

+ See Product Guide for Variations of This Number. <sup>89</sup> Inner Fender Liner Removal Recommended for Proper Installation. Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

GENERAL MOTORS CORP. Trucks, Buses & Vans (cont'd)	GENERAL MOTORS CORP. Trucks, Buses & Vans (cont'd)	GENERAL MOTORS CORP. Trucks, Buses & Vans (cont'd)
C6500 TopKick w/Cat 3126 (7.2L) Eng. (To 1/2004)	C6500 Topkick w/Cat C7 (7.2L) Eng. (To 1/2004) (Cont'd)	C6500 Topkick w/Isuzu 6HK1-TC (7.8L) Eng. (Cont'd)
<b>Lube</b> (Standard Vers.) (1R0739).. <b>B76</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Fuel/Water Separator</b> (ACDelco TP1519)..... <b>BF7759</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Fuel</b> (1-12 Thd.) (ACDelco TP915D)..... <b>BF5800 +</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Fuel</b> (7/8-14 Thd.) (1R-0751)..... <b>BF7632</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
<b>Radial Seal O. Air</b> (Std.) (88915422)..... <b>RS2863</b>	<b>Steering</b> (88892858)..... <b>P106-HD</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>Radial Seal O. Air</b> (Upgrade) (88915422)..... <b>RS2863XP</b>	C6500 Topkick w/Cat C7 (7.2L) Eng. (1/2004-on)	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Radial Seal I. Air</b> (12544543)..... <b>RS3501</b>	<b>Lube</b> (1R1807)..... <b>B7700 +</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	<b>Fuel/Water Separator</b> (ACDelco TP1519)..... <b>BF7759</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	<b>Fuel</b> (1-12 Thd.) (ACDelco TP915D)..... <b>BF5800 +</b>	<b>Steering</b> (88892858)..... <b>P106-HD</b>
<b>Trans. Spin-on</b> (ACDelco TF338)..... <b>BT8316-MPG</b>	<b>Fuel</b> (7/8-14 Thd.) (1R0751)..... <b>BF7632</b>	C6500 Topkick w/V8-454 (7.4L) Eng.
<b>Steering</b> (88892858)..... <b>P106-HD</b>	<b>Radial Seal O. Air</b> (88937525)..... <b>RS4672</b>	<b>Lube</b> (ACDelco PF932)..... <b>B7</b>
C6500 TopKick w/Cat 3126 (7.2L) Eng. (1/2004-on)	<b>Radial Seal I. Air</b> ..... <b>RS4673</b>	<b>Fuel</b> (ACDelco GF481)..... <b>BF853</b>
<b>Lube</b> (1R1807)..... <b>B7700 +</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Radial Seal Air</b> (Don. P533355)..... <b>RS3706</b>
<b>Fuel/Water Separator</b> (ACDelco TP1519)..... <b>BF7759</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Trans.</b> (25011122)..... <b>BT230</b>
<b>Fuel</b> (1-12 Thd.) (ACDelco TP915D)..... <b>BF5800 +</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	C6500 Topkick w/GM L18 (8.1L) Eng. (To 2002)
<b>Fuel</b> (7/8-14 Thd.) (1R-0751)..... <b>BF7632</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Lube</b> (ACDelco PF454)..... <b>B1438</b>
<b>Radial Seal O. Air</b> (Std.) (88915422)..... <b>RS2863</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Radial Seal Air</b> (ACDelco A1301C)..... <b>RS3706</b>
<b>Radial Seal O. Air</b> (Upgrade) (88915422)..... <b>RS2863XP</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Radial Seal O. Air</b> (88937525)..... <b>RS4672</b>
<b>Radial Seal I. Air</b> (12544543)..... <b>RS3501</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Comp. Air</b> (ACDelco A507CF)..... <b>PA1909</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	<b>Steering</b> (88892858)..... <b>P106-HD</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Trans. Spin-on</b> (ACDelco TF338)..... <b>BT8316-MPG</b>	C6500 TopKick w/GM 6.0L Eng.	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Steering</b> (88892858)..... <b>P106-HD</b>	<b>Lube</b> (ACDelco PF932)..... <b>B7</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20017</b>
C6500 Topkick w/Cat C7 (7.2L) Eng. (To 1/2004)	<b>Fuel</b> (ACDelco GF621)..... <b>BF853</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Lube</b> (Standard Vers.) (1R0739).. <b>B76 +</b>	<b>3 15/32 In. Air</b> (ACDelco A477C). <b>PA2008</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Lube</b> (Severe Service) (1R0739).. <b>B76-SS +</b>	<b>5 19/32 In. Air</b> (42122)..... <b>PA1798 +</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
<b>Fuel/Water Separator</b> (ACDelco TP1519)..... <b>BF7759</b>	C6500 Topkick w/Isuzu 6HK1-TC (7.8L) Eng.	<b>Steering</b> (88892858)..... <b>P106-HD</b>
<b>Fuel</b> (1-12 Thd.) (ACDelco TP915D)..... <b>BF5800 +</b>	<b>Lube</b> (94037791)..... <b>B75</b>	C6500 Topkick w/GM L18 (8.1L) Eng. (2003-04)
<b>Fuel</b> (7/8-14 Thd.) (1R0751)..... <b>BF7632</b>	<b>7 13/32 In. Fuel/Water Separator</b> (ACDelco TP1519)..... <b>BF7759</b>	<b>Lube</b> (ACDelco PF454)..... <b>B1438</b>
<b>Radial Seal O. Air</b> (88937525)..... <b>RS4672</b>	<b>Fuel/Water Separator</b> (w/Drain) (15618921)..... <b>BF5813 +</b>	<b>Fuel</b> (ACDelco GF652)..... <b>BF853</b>
<b>Radial Seal I. Air</b> ..... <b>RS4673</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (15618921)..... <b>BF5813-O +</b>	<b>Radial Seal O. Air</b> (ACDelco A2031C)..... <b>RS4672</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Fuel Ele.</b> (8980370110)..... <b>PF9919</b>	<b>Comp. Air</b> (ACDelco A507CF)..... <b>PA1909</b>
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Fuel Spin-on</b> (94392474)..... <b>BF7602</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Radial Seal O. Air</b> (88937525)..... <b>RS4672</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Radial Seal I. Air</b> (ACDelco A2035C)..... <b>RS4673</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
	<b>Single Radial Seal Air</b> (ACDelco A3101C)..... <b>RS5767</b>	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

GENERAL MOTORS CORP. Trucks, Buses & Vans (cont'd)	GENERAL MOTORS CORP. Trucks, Buses & Vans (cont'd)	GENERAL MOTORS CORP. Trucks, Buses & Vans (cont'd)
<p>C6500 Topkick w/GM L18 (8.1L) Eng. (2003-04) (Cont'd)</p> <p><b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b></p> <p><b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b></p> <p><b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b></p> <p><b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b></p> <p><b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b></p> <p><b>Steering</b> (88892858)..... <b>P106-HD</b></p>	<p>C7000 w/Cat 3208 (10.4L) Eng.</p> <p><b>Lube</b> (w/By-Pass Valve) (9L9200)..... <b>[2] BT364</b></p> <p><b>Std. Lube</b> (9N5570)..... <b>[2] BT230</b></p> <p><b>B-P Lube Ele.</b> (15525633)..... <b>C750-E+</b></p> <p><b>Box-Style Fuel/Water Separator.</b> <b>BF912</b></p> <p><b>Fuel Ele.</b> (5651879)..... <b>PF827</b></p> <p><b>Fuel Spin-on</b>..... <b>BF970+</b></p> <p><b>Air</b> (25041372)..... <b>PA2599</b></p> <p><b>Air</b> (25043585)..... <b>PA2148+</b></p> <p><b>Air</b> (15506047)..... <b>PA2656</b></p> <p><b>Air</b> (2003497)..... <b>PA2465</b></p>	<p>C7500 Topkick w/GMC 7.0L Eng.</p> <p><b>Lube</b> (ACDelco PF932)..... <b>B7</b></p> <p><b>Fuel</b> (ACDelco GF652)..... <b>BF853</b></p> <p><b>3 15/32 In. Air</b> (ACDelco A477C). <b>PA2008</b></p> <p><b>5 9/16 In. Air</b> (ACDelco A269CW)..... <b>PA1798+</b></p>
<p>C6500 Topkick w/GM L18 (8.1L) Eng. (2005-on)</p> <p><b>Lube</b> (ACDelco PF454)..... <b>B1438</b></p> <p><b>Fuel</b> (ACDelco TP1247)..... <b>BF790</b></p> <p><b>Radial Seal O. Air</b> (ACDelco A2031C)..... <b>RS4672</b></p> <p><b>Comp. Air</b> (ACDelco A507CF)..... <b>PA1909</b></p> <p><b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b></p> <p><b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b></p> <p><b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b></p> <p><b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b></p> <p><b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b></p> <p><b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b></p> <p><b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b></p> <p><b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b></p> <p><b>Steering</b> (88892858)..... <b>P106-HD</b></p>	<p>C7000 w/Cummins VT225 Eng.</p> <p><b>F-F Lube Ele.</b>..... <b>P999-HD</b></p> <p><b>F-F Lube Spin-on</b>..... <b>B196+</b></p> <p><b>Fuel Spin-on</b>..... <b>BF957+</b></p> <p><b>Coolant Spin-on</b>..... <b>BW5071</b></p>	<p>C7500 Topkick w/V8 7.4L Eng.</p> <p><b>Lube</b> (ACDelco PF454)..... <b>B1438</b></p> <p><b>Lube</b> (ACDelco PF1218)..... <b>B1428+</b></p> <p><b>Fuel In-Line</b> (ACDelco GF652).... <b>BF853</b></p> <p><b>Fuel Spin-on</b> (ACDelco TP1227). <b>BF790</b></p> <p><b>Radial Seal Air</b> (ACDelco A1301C)..... <b>RS3706+</b></p> <p><b>Trans. Spin-on</b> (ACDelco TF338)..... <b>BT8316-MPG</b></p>
<p>C7000 w/v8-366 (6.0L) Carb. Eng.</p> <p><b>F-F Lube</b> (8N9586)..... <b>BT230+</b></p> <p><b>B-P Lube Ele.</b> (15525633)..... <b>C750-E+</b></p> <p><b>Lube Spin-on</b> (25160561)..... <b>B1428</b></p> <p><b>Fuel Ele.</b> (5651879)..... <b>PF827</b></p> <p><b>Fuel Spin-on</b> (25010793)..... <b>BF5800+</b></p>	<p>C7000 w/Deutz BF6L913 Eng.</p> <p><b>Lube</b>..... <b>B218</b></p> <p><b>P. Fuel</b> (2133558)..... <b>BF586</b></p> <p><b>S. Fuel</b> (2133943)..... <b>BF587</b></p> <p><b>Std. Fuel</b> (1160243)..... <b>BF988+</b></p> <p><b>Air</b> (2063585)..... <b>PA2520</b></p>	<p>C7500 Topkick w/V8-496 (8.1L) Eng. (To 2002)</p> <p><b>Lube</b> (ACDelco PF454)..... <b>B1438</b></p> <p><b>11 3/32 In. Radial Seal O. Air</b> (ACDelco A1301C)..... <b>RS3706+</b></p> <p><b>18 1/2 In. Radial Seal O. Air</b> (ACDelco A2034C)..... <b>RS4672</b></p> <p><b>Comp. Air</b> (ACDelco A507CF).... <b>PA1909</b></p> <p><b>Air Dryer</b> (89040662)..... <b>BA5374+</b></p> <p><b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b></p> <p><b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b></p> <p><b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b></p> <p><b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b></p> <p><b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b></p> <p><b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b></p> <p><b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b></p> <p><b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b></p> <p><b>Steering</b> (88892858)..... <b>P106-HD</b></p>
<p>C7000 w/v8-366 (6.0L) FI. Eng.</p> <p><b>F-F Lube</b> (8N9586)..... <b>BT230+</b></p> <p><b>B-P Lube Ele.</b> (15525633)..... <b>C750-E+</b></p> <p><b>Fuel Ele.</b> (5651879)..... <b>PF827</b></p> <p><b>Fuel In-Line</b> (25055480)..... <b>BF853</b></p> <p><b>Fuel Spin-on</b> (25010793)..... <b>BF5800+</b></p>	<p>C7000 w/GMC V8-454 (7.4L) Eng.</p> <p><b>Lube</b>..... <b>B7</b></p> <p><b>Fuel Ele.</b>..... <b>PF827</b></p> <p><b>Air</b> (702025)..... <b>PA1922-FN</b></p> <p><b>Comp. Air</b>..... <b>PA1909</b></p>	<p>C7500 Topkick w/V8-496 (8.1L) Eng. (2003-04)</p> <p><b>Lube</b> (ACDelco PF454)..... <b>B1438</b></p> <p><b>Fuel</b> (ACDelco GF652)..... <b>BF853</b></p> <p><b>11 3/32 In. Radial Seal O. Air</b> (ACDelco A1301C)..... <b>RS3706+</b></p> <p><b>18 1/2 In. Radial Seal O. Air</b> (ACDelco A2034C)..... <b>RS4672</b></p> <p><b>Comp. Air</b> (ACDelco A507CF).... <b>PA1909</b></p> <p><b>Air Dryer</b> (89040662)..... <b>BA5374+</b></p> <p><b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b></p> <p><b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b></p> <p><b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b></p> <p><b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b></p> <p><b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b></p>
<p>C7000 w/v8-427 (7.0L) Eng.</p> <p><b>F-F Lube</b> (8N9586)..... <b>BT230+</b></p> <p><b>B-P Lube Ele.</b> (15525633)..... <b>C750-E+</b></p> <p><b>Fuel Ele.</b> (5651879)..... <b>PF827</b></p> <p><b>Fuel Spin-on</b> (25010793)..... <b>BF5800+</b></p> <p><b>Air</b> (25041372)..... <b>PA2599</b></p> <p><b>Air</b> (25043585)..... <b>PA2148+</b></p>	<p>C7000 Topkick w/V8-366 (6.0L) Eng.</p> <p><b>Lube</b> (25010754)..... <b>B7</b></p> <p><b>Fuel</b> (25055052)..... <b>BF853</b></p> <p><b>Air</b> (6484235)..... <b>PA2008</b></p> <p><b>Trans.</b> (25011122)..... <b>BT230</b></p>	
<p>C7000 w/v8-427 (7.0L) Eng.</p> <p><b>F-F Lube</b> (8N9586)..... <b>BT230+</b></p> <p><b>B-P Lube Ele.</b> (15525633)..... <b>C750-E+</b></p> <p><b>Fuel Ele.</b> (5651879)..... <b>PF827</b></p> <p><b>Fuel Spin-on</b> (25010793)..... <b>BF5800+</b></p> <p><b>Air</b> (25041372)..... <b>PA2599</b></p> <p><b>Air</b> (25043585)..... <b>PA2148+</b></p>	<p>C7000 Topkick w/Cat 3116 (6.6L) Eng.</p> <p><b>Lube</b> (Standard Vers.) (1R0739).. <b>B76+</b></p> <p><b>Lube</b> (Severe Service) (1R0739).. <b>B76-SS+</b></p> <p><b>Box-Style Glass Fuel/Water Separator</b> (6N7617)..... <b>BF912</b></p> <p><b>Fuel/Water Coalescer Ele. w/Drain</b> (1174089)..... <b>BF7679-D</b></p> <p><b>Fuel/Water Separator Spin-on</b> (1456695)..... <b>BF1350-SP</b></p> <p><b>Fuel</b> (1P2299)..... <b>BF970+</b></p> <p><b>Fuel</b> (1R0750)..... <b>BF7633+</b></p> <p><b>Fuel</b> (1R0751)..... <b>BF7632</b></p>	
	<p>C7500 Topkick w/V8-366 (6.0L) Eng.</p> <p><b>F-F Lube</b> (8N9586)..... <b>BT230+</b></p> <p><b>F-F Lube</b> (25013977)..... <b>B1428+</b></p> <p><b>B-P Lube Ele.</b> (15525633)..... <b>C750-E+</b></p> <p><b>Fuel Ele.</b> (5651879)..... <b>PF827</b></p> <p><b>Fuel In-Line</b> (25055480)..... <b>BF853</b></p> <p><b>Fuel Spin-on</b> (25010793)..... <b>BF5800+</b></p>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



GENERAL MOTORS CORP. Trucks, Buses & Vans (cont'd)	GENERAL MOTORS CORP. Trucks, Buses & Vans (cont'd)	GENERAL MOTORS CORP. Trucks, Buses & Vans (cont'd)
C7500 Topkick w/V8-496 (8.1L) Eng. (2003-04) (Cont'd)	C7500 Topkick w/Cat 3116 (6.6L) Eng. (1/2004-on) (Cont'd)	C7500 Topkick w/Cat C7 (7.2L) Eng. (To 1/2004) (Cont'd)
Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	Fuel/Water Separator (88983117)..... <b>BF7759</b>	Radial Seal I. Air..... <b>RS4673</b>
Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Fuel (7/8-14 Thd.) (1R0751)..... <b>BF7632</b>	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
Opt. Trans. Spin-on (Fuller 17237)..... <b>B2+</b>	Fuel (1-14 Thd.) (1R-0750)..... <b>BF7633+</b>	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
Steering (88892858)..... <b>P106-HD</b>	Radial Seal O. Air (15619013).... <b>RS2863</b>	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
C7500 Topkick w/V8-496 (8.1L) Eng. (2005-on)	Radial Seal O. Air (Upgrade) (15619013)..... <b>RS2863XP</b>	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
Lube (ACDelco PF454)..... <b>B1438</b>	Radial Seal I. Air..... <b>RS3501</b>	Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>
Fuel (ACDelco TP1247)..... <b>BF790</b>	Trans. Ele. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
11 3/32 In. Radial Seal O. Air (ACDelco A1301C)..... <b>RS3706+</b>	Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
18 1/2 In. Radial Seal O. Air (ACDelco A2034C)..... <b>RS4672</b>	Trans. Spin-on (ACDelco PF897F)..... <b>BT230</b>	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2+</b>
Comp. Air (ACDelco A507CF)..... <b>PA1909</b>	Steering (88892858)..... <b>P106-HD</b>	Steering (88892858)..... <b>P106-HD</b>
Air Dryer (89040662)..... <b>BA5374+</b>	C7500 Topkick w/Cat 3126 (7.2L) Eng. (1R0739)..... <b>B76+</b>	C7500 Topkick w/Cat C7 (7.2L) Eng. (1/2004-on)
Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	F-F Lube (Standard Vers.) (1R1807)..... <b>B7700+</b>	Lube (1R1807)..... <b>B7700+</b>
Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	F-F Lube (High Velocity) (1R1807)..... <b>B7700+</b>	Fuel/Water Separator (ACDelco TP1519)..... <b>BF7759</b>
Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	B-P Lube (15525633)..... <b>C750-E+</b>	Fuel (1-12 Thd.) (ACDelco TP915D)..... <b>BF5800+</b>
Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	F-F Lube (Severe Service) (1R0739)..... <b>B76-SS+</b>	Fuel (7/8-14 Thd.) (1R0751)..... <b>BF7632</b>
Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>	Fuel/Water Separator (15152281)..... <b>BF7759</b>	Radial Seal O. Air (88937525).... <b>RS4672</b>
Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	Fuel/Water Separator (w/Drain) (15618921)..... <b>BF5813+</b>	Radial Seal I. Air..... <b>RS4673</b>
Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Fuel/Water Separator (Open End for Bowl) (15618921)..... <b>BF5813-O+</b>	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
Opt. Trans. Spin-on (Fuller 17237)..... <b>B2+</b>	Fuel (7/8-14 Thd.) (1R0751)..... <b>BF7632</b>	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
Steering (88892858)..... <b>P106-HD</b>	Fuel (1-12 Thd.) (ACDelco TP915D)..... <b>BF5800+</b>	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
C7500 Topkick w/Cat 3116 (6.6L) Eng. (To 1/2004)	12 3/4 In. Radial Seal Air (15696245)..... <b>RS2863</b>	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
Lube (Standard Vers.) (1R0739).. <b>B76+</b>	12 3/4 In. Radial Seal XP O. Air (15696245)..... <b>RS2863XP</b>	Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>
Lube (Severe Service) (1R0739).. <b>B76-SS+</b>	Radial Seal I. Air (12544543)..... <b>RS3501</b>	Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
Fuel/Water Separator (88983117)..... <b>BF7759</b>	18 1/2 In. Radial Seal O. Air (ACDelco A2031C)..... <b>RS4672</b>	Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
Fuel (7/8-14 Thd.) (1R0751)..... <b>BF7632</b>	Trans. Ele. (3000 Series, 2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2+</b>
Fuel (1-14 Thd.) (1R-0750)..... <b>BF7633+</b>	Trans. Ele. (3000 Series, 4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	Steering (88892858)..... <b>P106-HD</b>
Radial Seal O. Air (15619013).... <b>RS2863</b>	Trans. Pan-Type (MT Series) (Allison 29538489)..... <b>19739+</b>	C7500 Topkick w/Isuzu 6HK1-TC (7.8L) Turbo Eng.
Radial Seal O. Air (Upgrade) (15619013)..... <b>RS2863XP</b>	Trans. Spin-on (MT Series) (Allison 29510922)..... <b>BT8316-MPG</b>	Lube (94037791)..... <b>B75</b>
Radial Seal I. Air..... <b>RS3501</b>	C7500 Topkick w/Cat C7 (7.2L) Eng. (To 1/2004)	Fuel/Water Separator (ACDelco TP1519)..... <b>BF7759</b>
Trans. Ele. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	Lube (Standard Vers.) (1R0739).. <b>B76+</b>	Fuel/Water Separator (w/Drain) (15618921)..... <b>BF5813+</b>
Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	Lube (Severe Service) (1R0739).. <b>B76-SS+</b>	Fuel/Water Separator (Open End for Bowl) (15618921)..... <b>BF5813-O+</b>
Trans. Spin-on (ACDelco PF897F)..... <b>BT230</b>	Fuel/Water Separator (ACDelco TP1519)..... <b>BF7759</b>	Fuel Ele. (8980370110)..... <b>PF9919</b>
Steering (88892858)..... <b>P106-HD</b>	Fuel (1-12 Thd.) (ACDelco TP915D)..... <b>BF5800+</b>	Fuel Spin-on (94392474)..... <b>BF7602</b>
C7500 Topkick w/Cat 3116 (6.6L) Eng. (1/2004-on)	Fuel (7/8-14 Thd.) (1R0751)..... <b>BF7632</b>	Radial Seal O. Air (88937525).... <b>RS4672</b>
Lube (1R1807)..... <b>B7700+</b>	Radial Seal O. Air (88937525).... <b>RS4672</b>	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

GENERAL MOTORS CORP. Trucks, Buses & Vans (cont'd)	GENERAL MOTORS CORP. Trucks, Buses & Vans (cont'd)	GENERAL MOTORS CORP. Trucks, Buses & Vans (cont'd)
<p>C7500 Topkick w/Isuzu 6HK1-TC (7.8L) Turbo Eng. (Cont'd)</p> <p>Radial Seal I. Air (ACDelco A2035C)..... <b>RS4673</b></p> <p>Single Radial Seal Air (ACDelco A3101C)..... <b>RS5767</b></p> <p>Air Dryer (89040662)..... <b>BA5374 +</b></p> <p>Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b></p> <p>Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b></p> <p>Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b></p> <p>Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b></p> <p>Trans. Spin-on (Allison 29539579)..... <b>BT8460</b></p> <p>Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b></p> <p>Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b></p> <p>Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b></p> <p>Steering (88892858)..... <b>P106-HD</b></p>	<p>TopKick C8500 w/Cat C7 (7.2L) Eng. (To 1/2004) (Cont'd)</p> <p>Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b></p> <p>Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b></p> <p>Steering (88892858)..... <b>P106-HD</b></p> <p>TopKick C8500 w/Cat C7 (7.2L) Eng. (1/2004-07)</p> <p>Lube (1R1807)..... <b>B7700 +</b></p> <p>Fuel (ACDelco TP915D)..... <b>BF5800 +</b></p> <p>Fuel (1R0751)..... <b>BF7632</b></p> <p>Radial Seal O. Air (88937525)..... <b>RS4672</b></p> <p>Radial Seal I. Air..... <b>RS4673</b></p> <p>Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b></p> <p>Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b></p> <p>Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b></p> <p>Steering (88892858)..... <b>P106-HD</b></p>	<p>TopKick C8500 w/8.1L Eng. (2005-on)</p> <p>Lube (ACDelco PF454)..... <b>B1438</b></p> <p>Fuel (ACDelco TP1247)..... <b>BF790</b></p> <p>Radial Seal O. Air (ACDelco A2031C)..... <b>RS4672</b></p> <p>Comp. Air (ACDelco A507CF)..... <b>PA1909</b></p> <p>Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b></p> <p>Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b></p> <p>Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b></p> <p>Steering (88892858)..... <b>P106-HD</b></p>
<p>TopKick C8500 w/Cat 3126E Eng. Lube (To 1/2004 (Standard Vers.)) (1R0739)..... <b>B76</b></p> <p>Lube (1/2004-on) (1R1807)..... <b>B7700 +</b></p> <p>Radial Seal O. Air (88915422)..... <b>RS2863</b></p> <p>Radial Seal XP O. Air (88915422)..... <b>RS2863XP</b></p> <p>Radial Seal I. Air (12544543)..... <b>RS3501</b></p>	<p>TopKick C8500 w/Cat C7 (7.2L) Eng. (2003-05)</p> <p>Fuel/Water Separator (ACDelco TP1519)..... <b>BF7759</b></p> <p>Fuel (ACDelco TP915D)..... <b>BF5800 +</b></p> <p>Fuel (1R0751)..... <b>BF7632</b></p> <p>Radial Seal O. Air (88937525)..... <b>RS4672</b></p> <p>Radial Seal I. Air..... <b>RS4673</b></p> <p>Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b></p> <p>Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b></p> <p>Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b></p> <p>Steering (88892858)..... <b>P106-HD</b></p>	<p>TopKick C8500 w/8.1L Eng. (2003-05)</p> <p>Lube (ACDelco PF454)..... <b>B1438</b></p> <p>Fuel (ACDelco GF652)..... <b>BF853</b></p> <p>Radial Seal O. Air (ACDelco A2031C)..... <b>RS4672</b></p> <p>Comp. Air (ACDelco A507CF)..... <b>PA1909</b></p> <p>Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b></p> <p>Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b></p> <p>Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b></p> <p>Steering (88892858)..... <b>P106-HD</b></p>
<p>TopKick C8500 w/Cat C7 (7.2L) Eng. (2007-on)</p> <p>Lube (1R1807)..... <b>B7700 +</b></p> <p>Fuel/Water Separator (w/Drain) (15618921)..... <b>BF5813 +</b></p> <p>Fuel/Water Separator (Open End for Bowl) (15618921)..... <b>BF5813-O +</b></p> <p>Fuel (ACDelco TP915D)..... <b>BF5800 +</b></p> <p>Fuel (1R0751)..... <b>BF7632</b></p> <p>Radial Seal O. Air (88937525)..... <b>RS4672</b></p> <p>Radial Seal I. Air..... <b>RS4673</b></p> <p>Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b></p> <p>Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b></p> <p>Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b></p> <p>Steering (88892858)..... <b>P106-HD</b></p>	<p>TopKick C8500 w/Isuzu 7.8L Eng. (2003-08)</p> <p>Lube (94037791)..... <b>B75</b></p> <p>Fuel/Water Separator (w/Drain) (15618921)..... <b>BF5813 +</b></p> <p>Fuel/Water Separator (Open End for Bowl) (15618921)..... <b>BF5813-O +</b></p> <p>Fuel/Water Separator (ACDelco TP1519)..... <b>BF7759</b></p> <p>Fuel Ele. (8980370110)..... <b>PF9919</b></p> <p>Fuel Spin-on (94392474)..... <b>BF7602</b></p> <p>Radial Seal O. Air (88937525)..... <b>RS4672</b></p> <p>Radial Seal I. Air (ACDelco A2035C)..... <b>RS4673</b></p> <p>Radial Seal Air (ACDelco A3101C)..... <b>RS5767</b></p> <p>Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b></p> <p>Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b></p> <p>Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b></p> <p>Steering (88892858)..... <b>P106-HD</b></p>	<p>General w/Cat 3406 (14.6L) Eng.</p> <p>F-F Lube Spin-on..... <b>B99 +</b></p> <p>B-P Lube Ele..... <b>C750-E +</b></p> <p>Fuel Spin-on..... <b>BF614 +</b></p> <p>23 In. Air (2038573)..... <b>PA2317 +</b></p> <p>20 In. Air (717702)..... <b>PA2515</b></p> <p>Axle Breather (Rockwell SQHP).. <b>B27</b></p> <p>General w/Cummins L10 (10.0L) Eng.</p> <p>F-F Lube Ele..... <b>P999-HD</b></p> <p>F-F Lube Spin-on..... <b>B196 +</b></p> <p>B-P Lube Ele..... <b>C750-E +</b></p> <p>B-P Lube Spin-on..... <b>B7577</b></p> <p>Fuel Spin-on..... <b>BF957 +</b></p> <p>23 In. Air (2038573)..... <b>PA2317 +</b></p> <p>20 In. Air (717702)..... <b>PA2515</b></p> <p>Axle Breather (Rockwell SQHP).. <b>B27</b></p>
<p>TopKick C8500 w/Cat C7 (7.2L) Eng. (To 1/2004)</p> <p>Lube (Standard Vers.) (1R0739).. <b>B76 +</b></p> <p>Lube (Severe Service) (1R0739).. <b>B76-SS +</b></p> <p>Fuel (ACDelco TP915D)..... <b>BF5800 +</b></p> <p>Fuel (1R0751)..... <b>BF7632</b></p> <p>Radial Seal O. Air (88937525)..... <b>RS4672</b></p> <p>Radial Seal I. Air..... <b>RS4673</b></p> <p>Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b></p>	<p>TopKick C8500 w/Cat C7 (7.2L) Eng. (To 1/2004)</p> <p>Lube (Standard Vers.) (1R0739).. <b>B76 +</b></p> <p>Lube (Severe Service) (1R0739).. <b>B76-SS +</b></p> <p>Fuel (ACDelco TP915D)..... <b>BF5800 +</b></p> <p>Fuel (1R0751)..... <b>BF7632</b></p> <p>Radial Seal O. Air (88937525)..... <b>RS4672</b></p> <p>Radial Seal I. Air..... <b>RS4673</b></p> <p>Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b></p> <p>Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b></p> <p>Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b></p> <p>Steering (88892858)..... <b>P106-HD</b></p>	<p>General w/Cummins N14 (14.0L) Eng.</p> <p>F-F Lube Ele..... <b>P999-HD</b></p> <p>F-F Lube Spin-on..... <b>B196 +</b></p> <p>B-P Lube Ele..... <b>C750-E +</b></p> <p>B-P Lube Spin-on..... <b>B7577</b></p> <p>Fuel Spin-on..... <b>BF957 +</b></p> <p>23 In. Air (2038573)..... <b>PA2317 +</b></p> <p>20 In. Air (717702)..... <b>PA2515</b></p> <p>Axle Breather (Rockwell SQHP).. <b>B27</b></p> <p>General w/Cummins NTC Eng.</p> <p>F-F Lube Ele..... <b>P999-HD</b></p> <p>F-F Lube Spin-on..... <b>B196 +</b></p> <p>B-P Lube Ele..... <b>C750-E +</b></p> <p>Fuel Spin-on..... <b>BF957 +</b></p> <p>Air (717702)..... <b>PA2515</b></p> <p>Axle Breather (Rockwell SQHP).. <b>B27</b></p>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

GENERAL MOTORS CORP. Trucks, Buses & Vans (cont'd)	GENERAL MOTORS CORP. Trucks, Buses & Vans (cont'd)	GENERAL MOTORS CORP. Trucks, Buses & Vans (cont'd)
General w/Detroit Diesel 6-71 (7.0L) Eng. F-F Lube Ele..... P20-HD + B-P Lube Ele..... C750-E + P. Fuel Spin-on..... BF5800 + S. Fuel Spin-on..... BF5810 Air (717702)..... PA2515 Coolant..... BW5137 Axle Breather (Rockwell SQHP).. B27	Low Cab Forward w/7.8L V6 Turbo Eng. (2000-02) Radial Seal Air (ACDelco A2012C)..... RS3548 Radial Seal XP Air (ACDelco A2012C)..... RS3548XP Trans. (ACDelco PF897F)..... BT230	P4500 w/V6-262 (4.3L) Eng. Lube (25012760)..... B35-S + Fuel In-Line (25055480)..... BF853
General w/Detroit Diesel 6V-92N (9.0L) Eng. F-F Lube Ele..... P20-HD + F-F Lube Spin-on..... B95 + B-P Lube Ele..... C750-E + P. Fuel Spin-on..... BF5800 + S. Fuel Spin-on..... BF5810 23 In. Air (2038573)..... PA2317 + 20 In. Air (717702)..... PA2515 26 In. Air (717714)..... PA2516 Coolant..... BW5137 Axle Breather (Rockwell SQHP).. B27	Mexico Med Conventional w/7.2L L6 Turbo Eng. Lube (To 1/2004 (Standard Vers.)) (1R0739)..... B76 Lube (1/2004-on) (1R1807)..... B7700 + Fuel (1R0751)..... BF7632 Radial Seal Air (ACDelco A1169C)..... RS2863 Radial Seal XP Air (ACDelco A1169C)..... RS2863XP Trans. (2002) (ACDelco PF897F)..... BT230	P4500 w/L6-292 (4.8L) Eng. Lube (25324052)..... B1438 Fuel (5651920)..... PF893-RV
General w/Detroit Diesel 8V-71 (9.3L) Eng. F-F Lube Ele..... P20-HD + B-P Lube Ele..... C750-E + P. Fuel Spin-on..... BF5800 + S. Fuel Spin-on..... BF5810 Air (717702)..... PA2515 Coolant..... BW5137 Axle Breather (Rockwell SQHP).. B27	Mexico Med Conventional w/8.1L V8 Eng. Lube (ACDelco PF454)..... B1438 Fuel (ACDelco GF652)..... BF853 Trans. (2002) (ACDelco PF897F)..... BT230	P6500 w/V8-366 (6.0L) Eng. Fuel Ele. (5651879)..... PF827 Fuel In-Line (25055480)..... BF853 Fuel Spin-on (25010793)..... BF5800 + Trans. Pan-Type (AT Series, 3.8 In. Pan) (Allison 29540976)..... 19992 + Trans. Pan-Type (AT Series, 5.3 In. Pan) (Allison 29538489)..... 19739 + Trans. Spin-on (AT Series) (Allison 29510922)..... BT8316-MPG
General w/Detroit Diesel 8V-92 (12.1L) Eng. F-F Lube Ele..... P20-HD + B-P Lube Ele..... C750-E + P. Fuel Spin-on..... BF5800 + S. Fuel Spin-on..... BF5810 Air (717714)..... PA2516 Coolant..... BW5137 Axle Breather (Rockwell SQHP).. B27	MD Isuzu Truck Forward w/V8 6.0L Eng. Lube (To 2006) (ACDelco PF46).. B31 Lube (2007-on) (ACDelco PF48).. B160	P6500 w/V8-427 (7.0L) Eng. Trans. Pan-Type (AT Series, 3.8 In. Pan) (Allison 29540976)..... 19992 + Trans. Pan-Type (AT Series, 5.3 In. Pan) (Allison 29538489)..... 19739 + Trans. Spin-on (AT Series) (Allison 29510922)..... BT8316-MPG
General w/Detroit Diesel Series 60 (11.1L) & (12.7L) Eng. F-F Lube Ele..... P20-HD + F-F Lube Spin-on..... B95 + B-P Lube Ele..... C750-E + P. Fuel Spin-on..... BF5800 + S. Fuel Spin-on..... BF5810 23 In. Air (2038573)..... PA2317 + 20 In. Air (717702)..... PA2515 26 In. Air (717714)..... PA2516 Coolant..... BW5137 Axle Breather (Rockwell SQHP).. B27	Motorhomes w/V8-350 Eng. Lube (1975-on)..... B6 + Opt. 2 Qt. Lube..... B7 Fuel Ele..... PF894-RV In-Line Fuel..... BF836 Air (1975)..... PA2008 Air (1976-on)..... PA1680	P6500 w/Cat 3116 (6.6L) Eng. Lube (Standard Vers.) (1R0739).. B76 + Lube (Severe Service) (1R0739).. B76-SS + Box-Style Glass Fuel/Water Separator (6N7617)..... BF912 Fuel/Water Coalescer Ele. w/Drain (1174089)..... BF7679-D Fuel/Water Separator Spin-on (1456695)..... BF1350-SP Fuel (1P2299)..... BF970 + Fuel (1R0750)..... BF7633 + Fuel (1R0751)..... BF7632 Trans. Pan-Type (AT Series, 3.8 In. Pan) (Allison 29540976)..... 19992 + Trans. Pan-Type (AT Series, 5.3 In. Pan) (Allison 29538489)..... 19739 + Trans. Spin-on (AT Series) (Allison 29510922)..... BT8316-MPG
Low Cab Forward w/7.2L V6 Turbo Eng. (2000-02) Fuel/Water Separator (ACDelco TP1519)..... BF7759 Fuel (ACDelco TP915D)..... BF5800 + Radial Seal Air (ACDelco A2012C)..... RS3548 Radial Seal XP Air (ACDelco A2012C)..... RS3548XP Trans. (ACDelco PF897F)..... BT230	Motorhomes w/V8-400 Eng. Lube..... B6 + Opt. 2 Qt. Lube..... B7 Fuel..... PF894-RV Air..... PA1680	Savana 4500 w/V8-364 (6.0L) CNG Eng. Lube (ACDelco PF48)..... B160 Radial Seal Air (ACDelco A3097C)..... RS4131 Trans. (24236933)..... 20022
	Motorhomes w/V8-403 Eng. 4 3/8 In. Lube..... B39 5 3/8 In. Lube..... B9 Fuel..... PF894-RV Air..... PA1758	Savana 4500 w/V8-364 (6.0L) Gas Eng. (2009) Lube (ACDelco PF48)..... B160 Fuel (N/S)..... N/S Radial Seal Air (ACDelco A3097C)..... RS4131 Trans. (4L60-E) (24208576)..... 18056 Trans. (4L80-E) (24210956)..... 18027
	Motorhomes w/V8-454 Eng. Lube..... B6 + Opt. 2 Qt. Lube..... B7 Fuel Ele. (1973-75)..... PF893 Fuel Ele. (1976-on)..... PF894-RV In-Line Fuel..... BF836 Portable Storage Tank In-Line Fuel (1989-91) (25055347)..... BF7691 Air..... PA2008	Savana 4500 w/V8-364 (6.0L) Flex Fuel Eng. (2010-16) Lube (ACDelco PF48)..... B160 Fuel (N/S)..... N/S
	Motorhomes w/V8-455 Eng. 4 3/8 In. Lube..... B39 5 3/8 In. Lube..... B9 Fuel..... PF894-RV Portable Storage Tank In-Line Fuel (1989-91) (25055347)..... BF7691 Air..... PA1758	

+ See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

GENERAL MOTORS CORP. Trucks, Buses & Vans (cont'd)	GENERAL MOTORS CORP. Trucks, Buses & Vans (cont'd)	GENERAL MOTORS CORP. Trucks, Buses & Vans (cont'd)
Savana 4500 w/V8-364 (6.0L) Flex Fuel Eng. (2010-16) (Cont'd) <b>Radial Seal Air</b> (ACDelco A3097C)..... <b>RS4131</b> <b>Trans.</b> (6L90) (24236933)..... <b>20022</b>	T6500 w/V8-366 (6.0L) Eng. (ACDelco PF35L)..... <b>B6-HPG +</b> <b>Lube</b> (w/ Anti-Drainback Valve) (ACDelco PF1218)..... <b>B1428 +</b> <b>Fuel</b> (ACDelco GF652)..... <b>BF853</b> <b>Air</b> (ACDelco A348C)..... <b>PA2008</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b>	T6500 w/Cat 3126 (7.2L) Eng. (1998-2001) (Cont'd) <b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> T6500 w/Cat 3126 (7.2L) Eng. (2002) <b>F-F Lube</b> (Standard Vers.) (1R0739)..... <b>B76 +</b> <b>B-P Lube</b> (15525633)..... <b>C750-E +</b> <b>F-F Lube</b> (Severe Service) (1R0739)..... <b>B76-SS +</b> <b>Fuel/Water Separator</b> (15152281)..... <b>BF7759</b> <b>Fuel</b> (1R0751)..... <b>BF7632</b> <b>Single Radial Seal Air</b> (ACDelco A2012C)..... <b>RS3548</b> <b>Single Radial Seal XP Air</b> (ACDelco A2012C)..... <b>RS3548XP</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>
Savana 4500 w/V8-364 (6.0L) Eng. (2017) <b>Lube</b> (ACDelco PF48)..... <b>B160</b> <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Radial Seal Air</b> (84000015)..... <b>RS4131</b> <b>Trans.</b> (24236933)..... <b>20022</b>	T6500 w/Cat 3116 (6.6L) Eng. <b>F-F Lube</b> (Standard Vers.) (1R0739)..... <b>B76 +</b> <b>B-P Lube</b> (15525633)..... <b>C750-E +</b> <b>F-F Lube</b> (Severe Service) (1R0739)..... <b>B76-SS +</b> <b>Fuel/Water Separator</b> (15152281)..... <b>BF7759</b> <b>Fuel</b> (ACDelco TP915D)..... <b>BF5800 +</b> <b>Air</b> (ACDelco A1075C)..... <b>PA2577</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b>	T6500 w/Cat 3126 (7.2L) Eng. (1998-2001) <b>F-F Lube</b> (Standard Vers.) (1R0739)..... <b>B76 +</b> <b>B-P Lube</b> (15525633)..... <b>C750-E +</b> <b>F-F Lube</b> (Severe Service) (1R0739)..... <b>B76-SS +</b> <b>Fuel/Water Separator</b> (15152281)..... <b>BF7759</b> <b>Fuel</b> (1R0751)..... <b>BF7632</b> <b>Radial Seal O. Air</b> (ACDelco A2012C)..... <b>RS3548</b> <b>Radial Seal O. XP Air</b> (ACDelco A2012C)..... <b>RS3548XP</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
Savana 4500 w/V8-364 (6.0L) Eng. (2018) <b>Lube</b> (ACDelco PF48)..... <b>B160</b> <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Radial Seal Air</b> (84000015)..... <b>RS4131</b> <b>Trans.</b> (24236933)..... <b>20022</b>	T6500 w/Cat 3126 (7.2L) Eng. (1998-2001) <b>F-F Lube</b> (Standard Vers.) (1R0739)..... <b>B76 +</b> <b>B-P Lube</b> (15525633)..... <b>C750-E +</b> <b>F-F Lube</b> (Severe Service) (1R0739)..... <b>B76-SS +</b> <b>Fuel/Water Separator</b> (15152281)..... <b>BF7759</b> <b>Fuel</b> (ACDelco TP915D)..... <b>BF5800 +</b> <b>Air</b> (ACDelco A1075C)..... <b>PA2577</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b>	T6500 w/Isuzu 6HK1-TC (7.8L) Eng. <b>Lube</b> (94037791)..... <b>B75</b> <b>Fuel/Water Separator</b> (Upgrade) (ACDelco TP3018)..... <b>BF46062 89</b> <b>Fuel/Water Separator</b> (w/Drain) (15618921)..... <b>BF5813 +</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (15618921)..... <b>BF5813-O +</b> <b>Fuel Ele.</b> (8980370110)..... <b>PF9919</b> <b>Fuel Spin-on</b> (94392474)..... <b>BF7602</b> <b>Radial Seal Air</b> (ACDelco A2012C)..... <b>RS3548</b> <b>Radial Seal XP Air</b> (ACDelco A2012C)..... <b>RS3548XP</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
Savana 4500 w/V8-364 (6.0L) Eng. (2019) <b>Lube</b> (89017524)..... <b>B160</b> <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Radial Seal Air</b> (22909882)..... <b>RS4131</b> <b>Trans.</b> (24236933)..... <b>20022</b>	T6500 w/Cat 3126 (7.2L) Eng. (1998-2001) <b>F-F Lube</b> (Standard Vers.) (1R0739)..... <b>B76 +</b> <b>B-P Lube</b> (15525633)..... <b>C750-E +</b> <b>F-F Lube</b> (Severe Service) (1R0739)..... <b>B76-SS +</b> <b>Fuel/Water Separator</b> (15152281)..... <b>BF7759</b> <b>Fuel</b> (1R0751)..... <b>BF7632</b> <b>Radial Seal O. Air</b> (ACDelco A2012C)..... <b>RS3548</b> <b>Radial Seal O. XP Air</b> (ACDelco A2012C)..... <b>RS3548XP</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	T6500 w/Isuzu 6HK1-TC (7.8L) Eng. <b>Lube</b> (94037791)..... <b>B75</b> <b>Fuel/Water Separator</b> (Upgrade) (ACDelco TP3018)..... <b>BF46062 89</b> <b>Fuel/Water Separator</b> (w/Drain) (15618921)..... <b>BF5813 +</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (15618921)..... <b>BF5813-O +</b> <b>Fuel Ele.</b> (8980370110)..... <b>PF9919</b> <b>Fuel Spin-on</b> (94392474)..... <b>BF7602</b> <b>Radial Seal Air</b> (ACDelco A2012C)..... <b>RS3548</b> <b>Radial Seal XP Air</b> (ACDelco A2012C)..... <b>RS3548XP</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
Savana 4500 w/V8-364 (6.0L) Eng. (2020) <b>Lube</b> (89017525)..... <b>B7449</b> <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Radial Seal Air</b> (84000015)..... <b>RS4131</b>	T6500 w/Cat 3116 (6.6L) Eng. <b>F-F Lube</b> (Standard Vers.) (1R0739)..... <b>B76 +</b> <b>B-P Lube</b> (15525633)..... <b>C750-E +</b> <b>F-F Lube</b> (Severe Service) (1R0739)..... <b>B76-SS +</b> <b>Fuel/Water Separator</b> (15152281)..... <b>BF7759</b> <b>Fuel</b> (ACDelco TP915D)..... <b>BF5800 +</b> <b>Air</b> (ACDelco A1075C)..... <b>PA2577</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b>	T6500 w/Isuzu 6HK1-TC (7.8L) Eng. <b>Lube</b> (94037791)..... <b>B75</b> <b>Fuel/Water Separator</b> (Upgrade) (ACDelco TP3018)..... <b>BF46062 89</b> <b>Fuel/Water Separator</b> (w/Drain) (15618921)..... <b>BF5813 +</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (15618921)..... <b>BF5813-O +</b> <b>Fuel Ele.</b> (8980370110)..... <b>PF9919</b> <b>Fuel Spin-on</b> (94392474)..... <b>BF7602</b> <b>Radial Seal Air</b> (ACDelco A2012C)..... <b>RS3548</b> <b>Radial Seal XP Air</b> (ACDelco A2012C)..... <b>RS3548XP</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
Savana 4500 w/V8-401 (6.6L) Gas Eng. (2021) <b>Lube</b> (12707246)..... <b>B7449</b> <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Air</b> (ACDelco A3228C)..... <b>PA10423</b> <b>Trans.</b> (24258269)..... <b>N/S</b>	T6500 w/Cat 3126 (7.2L) Eng. (1998-2001) <b>F-F Lube</b> (Standard Vers.) (1R0739)..... <b>B76 +</b> <b>B-P Lube</b> (15525633)..... <b>C750-E +</b> <b>F-F Lube</b> (Severe Service) (1R0739)..... <b>B76-SS +</b> <b>Fuel/Water Separator</b> (15152281)..... <b>BF7759</b> <b>Fuel</b> (1R0751)..... <b>BF7632</b> <b>Radial Seal O. Air</b> (ACDelco A2012C)..... <b>RS3548</b> <b>Radial Seal O. XP Air</b> (ACDelco A2012C)..... <b>RS3548XP</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	T6500 w/Isuzu 6HK1-TC (7.8L) Eng. <b>Lube</b> (94037791)..... <b>B75</b> <b>Fuel/Water Separator</b> (Upgrade) (ACDelco TP3018)..... <b>BF46062 89</b> <b>Fuel/Water Separator</b> (w/Drain) (15618921)..... <b>BF5813 +</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (15618921)..... <b>BF5813-O +</b> <b>Fuel Ele.</b> (8980370110)..... <b>PF9919</b> <b>Fuel Spin-on</b> (94392474)..... <b>BF7602</b> <b>Radial Seal Air</b> (ACDelco A2012C)..... <b>RS3548</b> <b>Radial Seal XP Air</b> (ACDelco A2012C)..... <b>RS3548XP</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
Savana 4500 w/V8-403 (6.6L) Turbo Diesel Eng. (2009) <b>Lube</b> (ACDelco PF2232)..... <b>B1441</b> <b>Fuel Kit</b> (ACDelco TP1537)..... <b>BF9918 KIT 76</b> <b>Channel Flow Air</b> (ACDelco A2959C)..... <b>CA5370</b> <b>Trans.</b> (4L60-E S. Pan) (24200796)..... <b>18010</b> <b>Trans.</b> (4L60-E D. Pan) (24208813)..... <b>18056</b> <b>Trans.</b> (4L80-E) (24210956)..... <b>18027</b>	T6500 w/Cat 3126 (7.2L) Eng. (1998-2001) <b>F-F Lube</b> (Standard Vers.) (1R0739)..... <b>B76 +</b> <b>B-P Lube</b> (15525633)..... <b>C750-E +</b> <b>F-F Lube</b> (Severe Service) (1R0739)..... <b>B76-SS +</b> <b>Fuel/Water Separator</b> (15152281)..... <b>BF7759</b> <b>Fuel</b> (1R0751)..... <b>BF7632</b> <b>Radial Seal O. Air</b> (ACDelco A2012C)..... <b>RS3548</b> <b>Radial Seal O. XP Air</b> (ACDelco A2012C)..... <b>RS3548XP</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	T6500 w/Isuzu 6HK1-TC (7.8L) Eng. <b>Lube</b> (94037791)..... <b>B75</b> <b>Fuel/Water Separator</b> (Upgrade) (ACDelco TP3018)..... <b>BF46062 89</b> <b>Fuel/Water Separator</b> (w/Drain) (15618921)..... <b>BF5813 +</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (15618921)..... <b>BF5813-O +</b> <b>Fuel Ele.</b> (8980370110)..... <b>PF9919</b> <b>Fuel Spin-on</b> (94392474)..... <b>BF7602</b> <b>Radial Seal Air</b> (ACDelco A2012C)..... <b>RS3548</b> <b>Radial Seal XP Air</b> (ACDelco A2012C)..... <b>RS3548XP</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
Savana 4500 w/V8-403 (6.6L) Turbo Diesel Eng. (2010-11) <b>Lube</b> (ACDelco PF2232)..... <b>B1441</b> <b>Fuel Kit</b> (ACDelco TP1537)..... <b>BF9918 KIT 76</b> <b>Channel Flow Air</b> (ACDelco A2959C)..... <b>CA5370</b> <b>Trans.</b> (6L90) (24236933)..... <b>20022</b>	T6500 w/Cat 3126 (7.2L) Eng. (1998-2001) <b>F-F Lube</b> (Standard Vers.) (1R0739)..... <b>B76 +</b> <b>B-P Lube</b> (15525633)..... <b>C750-E +</b> <b>F-F Lube</b> (Severe Service) (1R0739)..... <b>B76-SS +</b> <b>Fuel/Water Separator</b> (15152281)..... <b>BF7759</b> <b>Fuel</b> (1R0751)..... <b>BF7632</b> <b>Radial Seal O. Air</b> (ACDelco A2012C)..... <b>RS3548</b> <b>Radial Seal O. XP Air</b> (ACDelco A2012C)..... <b>RS3548XP</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	T6500 w/Isuzu 6HK1-TC (7.8L) Eng. <b>Lube</b> (94037791)..... <b>B75</b> <b>Fuel/Water Separator</b> (Upgrade) (ACDelco TP3018)..... <b>BF46062 89</b> <b>Fuel/Water Separator</b> (w/Drain) (15618921)..... <b>BF5813 +</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (15618921)..... <b>BF5813-O +</b> <b>Fuel Ele.</b> (8980370110)..... <b>PF9919</b> <b>Fuel Spin-on</b> (94392474)..... <b>BF7602</b> <b>Radial Seal Air</b> (ACDelco A2012C)..... <b>RS3548</b> <b>Radial Seal XP Air</b> (ACDelco A2012C)..... <b>RS3548XP</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
Savana 4500 w/V8-403 (6.6L) Turbo Diesel Eng. (2012-16) <b>Lube</b> (ACDelco PF2232)..... <b>B1441</b> <b>Fuel/Water Separator</b> (Upgrade) (ACDelco TP3018)..... <b>BF46062 89</b> <b>Channel Flow Air</b> (ACDelco A2959C)..... <b>CA5370</b> <b>Trans.</b> (6L90) (24236933)..... <b>20022</b>	T6500 w/Cat 3126 (7.2L) Eng. (1998-2001) <b>F-F Lube</b> (Standard Vers.) (1R0739)..... <b>B76 +</b> <b>B-P Lube</b> (15525633)..... <b>C750-E +</b> <b>F-F Lube</b> (Severe Service) (1R0739)..... <b>B76-SS +</b> <b>Fuel/Water Separator</b> (15152281)..... <b>BF7759</b> <b>Fuel</b> (1R0751)..... <b>BF7632</b> <b>Radial Seal O. Air</b> (ACDelco A2012C)..... <b>RS3548</b> <b>Radial Seal O. XP Air</b> (ACDelco A2012C)..... <b>RS3548XP</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	T6500 w/Isuzu 6HK1-TC (7.8L) Eng. <b>Lube</b> (94037791)..... <b>B75</b> <b>Fuel/Water Separator</b> (Upgrade) (ACDelco TP3018)..... <b>BF46062 89</b> <b>Fuel/Water Separator</b> (w/Drain) (15618921)..... <b>BF5813 +</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (15618921)..... <b>BF5813-O +</b> <b>Fuel Ele.</b> (8980370110)..... <b>PF9919</b> <b>Fuel Spin-on</b> (94392474)..... <b>BF7602</b> <b>Radial Seal Air</b> (ACDelco A2012C)..... <b>RS3548</b> <b>Radial Seal XP Air</b> (ACDelco A2012C)..... <b>RS3548XP</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>

+ See Product Guide for Variations of This Number. <sup>76</sup> Contains Pri. and Sec. Fuel Elements. <sup>89</sup> Inner Fender Liner Removal Recommended for Proper Installation. Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

GENERAL MOTORS CORP. Trucks, Buses & Vans (cont'd)	GENERAL MOTORS CORP. Trucks, Buses & Vans (cont'd)	GENERAL MOTORS CORP. Trucks, Buses & Vans (cont'd)
T7500 w/V8-366 (6.0L) Eng. <b>Lube</b> (w/o Anti-Drainback Valve) (ACDelco PF35L)..... <b>B6-HPG +</b> <b>Lube</b> (w/Anti-Drainback Valve) (ACDelco PF1218)..... <b>B1428 +</b> <b>Fuel</b> (25171792)..... <b>BF853</b> <b>Air</b> (ACDelco A348C)..... <b>PA2008</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b>	T7500 w/Cat 3126 (7.2L) Eng. (2002) (Cont'd) <b>Single Radial Seal XP Air</b> (ACDelco A2012C)..... <b>RS3548XP</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	T8500 w/Isuzu 7.8L V8 Turbo Eng. (Cont'd) <b>Radial Seal XP Air</b> (ACDelco A2012C)..... <b>RS3548XP</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
T7500 w/Cat 3116 Eng. <b>Lube</b> (Standard Vers.) (1R0739).. <b>B76</b> <b>Fuel</b> (1R0751)..... <b>BF7632</b> <b>Axial Seal Air</b> (Don. P134353).... <b>PA2577</b> <b>Radial Seal Air</b> (Don. P533930)... <b>RS3548</b> <b>Radial Seal XP Air</b> (Don. P533930)..... <b>RS3548XP</b>	T7500 w/Isuzu 6HK1-TC (7.8L) Turbo Eng. <b>Lube</b> (94037791)..... <b>B75</b> <b>Fuel/Water Separator</b> (w/Drain) (Racor S3202)..... <b>BF5813 +</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (Racor S3202)..... <b>BF5813-O +</b> <b>Fuel/Water Separator</b> (Upgrade) (ACDelco TP3018)..... <b>BF46062<sup>89</sup></b> <b>Fuel Ele.</b> (8980370110)..... <b>PF9919</b> <b>Fuel Spin-on</b> (94392474)..... <b>BF7602</b> <b>Radial Seal Air</b> (ACDelco A2012C)..... <b>RS3548</b> <b>Radial Seal XP Air</b> (ACDelco A2012C)..... <b>RS3548XP</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	W6N042, W7N042 w/V8-350 Eng. <b>Lube</b> ..... <b>B7</b> <b>1 1/32 In. Fuel</b> (Rochester Carb.)... <b>PF893</b> <b>3 15/32 In. Fuel Ele.</b> ..... <b>PF827</b> <b>Comp. Air</b> ..... <b>PA1909</b>
T7500 w/Cat 3126 (7.2L) Eng. (1998-2001) <b>F-F Lube</b> (Standard Vers.) (1R0739)..... <b>B76 +</b> <b>B-P Lube</b> (15525633)..... <b>C750-E +</b> <b>F-F Lube</b> (Severe Service) (1R0739)..... <b>B76-SS +</b> <b>Fuel/Water Separator</b> (15152281)..... <b>BF7759</b> <b>Fuel</b> (1R0751)..... <b>BF7632</b> <b>Radial Seal O. Air</b> (ACDelco A2012C)..... <b>RS3548</b> <b>Radial Seal O. XP Air</b> (ACDelco A2012C)..... <b>RS3548XP</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	W6N042, W7N042 w/V8-366, V8-427 Eng. <b>Lube</b> ..... <b>B7</b> <b>Fuel Ele.</b> ..... <b>PF827</b> <b>Air</b> (6422556)..... <b>PA1800</b> <b>Comp. Air</b> ..... <b>PA1909</b>	W3500 w/Isuzu 4HE1 (4.8L) Eng. <b>Fuel</b> (97714339)..... <b>BF7602</b> (94430250)..... <b>PA2761</b>
T7500 w/Cat 3126 (7.2L) Eng. (2002) <b>F-F Lube</b> (Standard Vers.) (1R0739)..... <b>B76 +</b> <b>B-P Lube</b> (15525633)..... <b>C750-E +</b> <b>F-F Lube</b> (Severe Service) (1R0739)..... <b>B76-SS +</b> <b>Fuel/Water Separator</b> (15152281)..... <b>BF7759</b> <b>Fuel</b> (1R0751)..... <b>BF7632</b> <b>Single Radial Seal Air</b> (ACDelco A2012C)..... <b>RS3548</b>	T8500 w/Isuzu 7.8L V8 Turbo Eng. <b>Lube</b> (94037791)..... <b>B75</b> <b>Fuel/Water Separator</b> (Upgrade) (ACDelco TP3018)..... <b>BF46062<sup>89</sup></b> <b>Fuel/Water Separator</b> (w/Drain) (15618921)..... <b>BF5813 +</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (15618921)..... <b>BF5813-O +</b> <b>Fuel Ele.</b> (8980370110)..... <b>PF9919</b> <b>Fuel Spin-on</b> (94392474)..... <b>BF7602</b> <b>Radial Seal Air</b> (ACDelco A2012C)..... <b>RS3548</b>	W3500 w/Isuzu 4HK1 (5.2L) Eng. <b>Dual-Flow Lube</b> (8-97148-270-0) <b>BD7169</b> <b>Fuel/Water Separator</b> (94369299)..... <b>BF7534</b> <b>Fuel</b> (1-13240-079-1)..... <b>BF7602</b> <b>Air</b> (8-94430250-0)..... <b>PA2761</b>
		W3500 Forward w/V8-350 (5.7L) Eng. <b>Lube</b> (25160561)..... <b>B1428 +</b> <b>Fuel</b> (25055129)..... <b>BF853</b> <b>Air</b> (94430250)..... <b>PA2761</b>
		W3500 Forward w/Isuzu 4BD2 (3.9L) Eng. <b>Dual-Flow Lube</b> (2906546000).... <b>BD7166</b> <b>Fuel</b> (5873103350)..... <b>BF7648</b>
		W4500 Forward w/V8-364 (6.0L) Eng. <b>Lube</b> (13/16-16 Thd.) (ACDelco PF46)..... <b>B31</b> <b>Lube</b> (M22 x 1.5 Thd.) (89017524)..... <b>B160</b> <b>Fuel/Water Separator</b> (94369299)..... <b>BF7534</b> <b>Fuel In-Line</b> (25055129)..... <b>BF853</b> <b>Axial Seal Air</b> (94430250)..... <b>PA2761</b> <b>Radial Seal Air</b> (8970622940).... <b>RS5434</b> <b>Trans.</b> (4L80-E) (24210956)..... <b>18027</b>

+ See Product Guide for Variations of This Number. <sup>89</sup> Inner Fender Liner Removal Recommended for Proper Installation.

Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

GENERAL MOTORS CORP. Trucks, Buses & Vans (cont'd)	GENERAL MOTORS CORP. Trucks, Buses & Vans (cont'd)	GENERAL MOTORS CORP. Trucks, Buses & Vans (cont'd)
W4500 Forward w/Isuzu 4BD1T (3.9L) Eng. F-F Lube (1986-91) (94463715)... <b>B131</b> B-P Lube (1986-91) (94360419)... <b>B494</b> Fuel (1986-98) (97718401)..... <b>[2] BF7648</b> Air (Cab Chassis) (94430250)..... <b>PA2761</b> Air (Strip Chassis) (94156052)..... <b>PA2712</b>	W5500 Forward w/Isuzu 6HE1 (7.1L) Eng. (1988-94) O. Air (94058234)..... <b>PA2779</b> I. Air (94037809)..... <b>PA2545</b>	W7500 Forward w/Isuzu 6BG1 (6.5L) Eng. (1984-07/1987) F-F Lube Spin-on (94037791)..... <b>B75</b> Fuel (94051085)..... <b>BF7602</b> O. Air (94058234)..... <b>PA2779</b> I. Air (94037809)..... <b>PA2545</b>
W4500 Forward w/Isuzu 4BD2 (3.9L) Eng. Dual-Flow Lube (97049282)..... <b>BD7166</b> Fuel (97718401)..... <b>[2] BF7648</b> Air (Cab Chassis) (94430250)..... <b>PA2761</b> Air (Strip Chassis) (94156052)..... <b>PA2712</b>	W5500 Forward w/Isuzu 6HE1 (7.1L) Eng. (1995-97) F-F Lube Spin-on (94037791)..... <b>B75</b> B-P Lube Spin-on (94054123)..... <b>B7124</b> Fuel (97714339)..... <b>BF7602</b> Air (94058235)..... <b>PA2577</b>	W7500 Forward w/Isuzu 6BG1 (6.5L) Eng. (08/1987-96) F-F Lube Spin-on (94037791)..... <b>B75</b> B-P Lube Spin-on (94054123)..... <b>B7124</b> Fuel (94051085)..... <b>BF7602</b> O. Air (94058234)..... <b>PA2779</b> I. Air (94037809)..... <b>PA2545</b> Single Air (94058235)..... <b>PA2577</b>
W4500 Forward w/Isuzu 4HE1 (4.8L) Eng. Dual-Flow Lube (8-97148-270-0) <b>BD7169</b> Fuel (97714339)..... <b>BF7602</b> Air (Cab Chassis) (94430250)..... <b>PA2761</b> Air (Strip Chassis) (94156052)..... <b>PA2712</b>	W5500 Forward w/Isuzu 6HK1-TC (7.8L) Eng. Lube (1132401220)..... <b>B75</b>	W7500 Forward w/Isuzu 6BG1 (6.5L) Eng. (1997-98) F-F Lube Spin-on (94037791)..... <b>B75</b> Fuel (94051085)..... <b>BF7602</b>
W4500 Forward w/Isuzu 4HK1 (5.2L) Eng. Dual-Flow Lube (8-97148-270-0) <b>BD7169</b> Fuel/Water Separator (94369299)..... <b>BF7534</b> Fuel (1-13240-079-1)..... <b>BF7602</b> Air (8-94430250-0)..... <b>PA2761</b>	W5500HD Forward w/Isuzu 4HE1 (4.8L) Turbo Diesel Eng. Dual-Flow Lube (w/Inter-Cooler) (2906548000)..... <b>BD7169</b> Dual-Flow Lube (w/o Inter-Cooler) (8943381810)..... <b>BD7159</b> Fuel (5873103350)..... <b>BF7648</b>	W7500 Forward w/Isuzu 6BG1 (6.5L) Eng. (1997-98) F-F Lube Spin-on (94037791)..... <b>B75</b> Fuel (94051085)..... <b>BF7602</b>
W5500 Forward w/Isuzu 4HE1 (4.8L) Turbo Diesel Eng. Dual-Flow Lube (w/Inter-Cooler) (2906548000)..... <b>BD7169</b> Dual-Flow Lube (w/o Inter-Cooler) (8943381810)..... <b>BD7159</b> Fuel (97714339)..... <b>BF7602</b> Air (8944302500)..... <b>PA2761</b>	W5500HD Forward w/Isuzu 4HK1 (5.2L) Eng. Dual-Flow Lube (8-97148-270-0) <b>BD7169</b> Fuel/Water Separator (94369299)..... <b>BF7534</b> Fuel (1-13240-079-1)..... <b>BF7602</b> Air (8-94430250-0)..... <b>PA2761</b>	W7500 Forward w/Isuzu 6SA1 (8.4L) Eng. F-F Lube..... <b>B75</b> B-P Lube Spin-on (94054123)..... <b>B7124</b> Fuel (94051085)..... <b>BF7602</b>
W5500 Forward w/Isuzu 4HK1 (5.2L) Eng. Dual-Flow Lube (8-97148-270-0) <b>BD7169</b> Fuel/Water Separator (94369299)..... <b>BF7534</b> Fuel (1-13240-079-1)..... <b>BF7602</b> Air (8-94430250-0)..... <b>PA2761</b>	W6500 Forward w/Isuzu 6BD1 (5.8L) Naturally Aspirated Diesel Eng. Lube Ele. (1878100751)..... <b>P723</b> Fuel Ele. (9885111911)..... <b>PF311</b> Fuel Spin-on (13240018)..... <b>BF954 +</b>	<b>GENERAL MOTORS CORP.</b> <b>South America Trucks</b> 12170 (6.6) w/Cat 3116 Eng. (01/96-12/02) Fuel/Water Separator (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> Fuel/Water Separator (With Bowl) (Mann WK1060/1)..... <b>BF46072</b> Fuel/Water Separator (With Drain) (Mann WK1060/1)..... <b>BF1329</b> Fuel/Water Separator (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b> Fuel/Water Separator (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b>
W5500 Forward w/Isuzu 4HK1 (5.2L) Eng. Dual-Flow Lube (8-97148-270-0) <b>BD7169</b> Fuel/Water Separator (94369299)..... <b>BF7534</b> Fuel (1-13240-079-1)..... <b>BF7602</b> Air (8-94430250-0)..... <b>PA2761</b>	W6500 Forward w/Isuzu 6BD1 (5.8L) Turbo Diesel Eng. F-F Lube..... <b>B75</b> B-P Lube Spin-on (94054123)..... <b>B7124</b> Fuel (94051085)..... <b>BF7602</b> O. Air (94058234)..... <b>PA2779</b> I. Air (94037809)..... <b>PA2545</b> Air (94058235)..... <b>PA2577</b>	14190 (6.6) w/Cat 3116 Eng. (01/96-12/02) Fuel/Water Separator (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> Fuel/Water Separator (With Bowl) (Mann WK1060/1)..... <b>BF46072</b> Fuel/Water Separator (With Drain) (Mann WK1060/1)..... <b>BF1329</b> Fuel/Water Separator (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b> Fuel/Water Separator (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b>
W5500 Forward w/Isuzu 6BG1 (6.5L) Eng. (1988-91) F-F Lube Spin-on (94037791)..... <b>B75</b> B-P Lube Spin-on (94054123)..... <b>B7124</b> Fuel (97714339)..... <b>BF7602</b> O. Air (94058234)..... <b>PA2779</b> I. Air (94037809)..... <b>PA2545</b>	W6500 Forward w/Isuzu 6BG1 (6.5L) Eng. F-F Lube (94037791)..... <b>B75</b> B-P Lube Spin-on (94054123)..... <b>B7124</b> Fuel (97714339)..... <b>BF7602</b> O. Air (94058234)..... <b>PA2779</b> I. Air (94037809)..... <b>PA2545</b>	
W5500 Forward w/Isuzu 6BG1 (6.5L) Eng. (1992-94) B-P Lube Spin-on (94054123)..... <b>B7124</b> Fuel (97714339)..... <b>BF7602</b> O. Air (94058234)..... <b>PA2779</b> I. Air (94037809)..... <b>PA2545</b>	W6500 Forward w/Isuzu 6HE1 (7.1L) Eng. F-F Lube (94037791)..... <b>B75</b> B-P Lube (94054123)..... <b>B7124</b> Fuel (97714339)..... <b>BF7602</b> O. Air (94058235)..... <b>PA2577</b>	
W5500 Forward w/Isuzu 6BG1 (6.5L) Eng. (1995-on) B-P Lube Spin-on (94054123)..... <b>B7124</b> Air (94058235)..... <b>PA2577</b>	W7500 Forward w/Isuzu 6BD1 (5.8L) Turbo Diesel Eng. F-F Lube..... <b>B75</b> B-P Lube Spin-on (94054123)..... <b>B7124</b> Fuel (94051085)..... <b>BF7602</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).


GENERAL MOTORS CORP. South America Trucks (cont'd)	GILLIG Trucks & Buses (cont'd)	GILLIG Trucks & Buses (cont'd)
15190 (6.6) w/Cat 3116 Eng. (01/97-on) <b>Fuel/Water Separator</b> (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b>	Low Floor w/Cummins ISB 6.7 (6.7L) Eng. (2021) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	Low Floor w/Cummins ISM Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154 +</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (Fleetguard FS1000)..... <b>BF1259</b> <b>Fuel/Water Separator</b> (Fleetguard FS1003)..... <b>BF1293-SPS</b> <b>Fuel/Water Separator</b> (Fleetguard FS1282)..... <b>BF1282 +</b> <b>Coolant</b> (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b> <b>Coolant</b> (w/o Chemical) (Fleetguard WF2122)..... <b>B5088 +</b>
16220 (6.6) w/Cat 3116 Eng. (01/96-12/02) <b>Fuel/Water Separator</b> (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b>	Low Floor w/Cummins ISL 8.9 (8.9L) Eng. (2001-14) <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel/Water Separator</b> (Fleetguard FS1003)..... <b>BF1293-SPS</b> <b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b> <b>Fuel</b> (Fleetguard FF5636)..... <b>BF7924</b> <b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b>	Low Floor w/Detroit Series 50 Eng. (2003-05) <b>Lube</b> (23518480)..... <b>[2] B495</b> <b>P. Fuel</b> ..... <b>BF5800 +</b> <b>S. Fuel</b> ..... <b>BF5810</b> <b>Air</b> (Don. P129472)..... <b>PA2500 +</b> <b>Coolant</b> (23524403)..... <b>B5134 +</b> <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (GMC 15513845)..... <b>PT8487</b>
<b>GIANT Trucks &amp; Buses</b> GF3600 w/CA4DC2-10E4 (3.2L) Turbo Diesel <b>Lube</b> (103.2 mm) (Fram PH2849A)..... <b>B161-S</b> <b>Lube</b> (130.2 mm) (Fram PH2849A)..... <b>B199</b>	Low Floor w/Cummins ISL 8.9 (8.9L) Eng. (2018) <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b>	Phantom w/Cummins ISC Eng. (2000-01) <b>Dual-Flow Lube</b> ..... <b>BD103 +</b> <b>Fuel/Water Separator</b> ..... <b>BF1272-SPS</b> <b>Air</b> ..... <b>PA3951</b> <b>Coolant</b> ..... <b>B5134 +</b> <b>Trans.</b> (ZF 4139298038)..... <b>PT8385</b> <b>Steering</b> ..... <b>PT8487</b>
GF-7000 w/w/Cummins ISF (3.8L) Eng. <b>Lube</b> (Fleetguard LF16352)..... <b>B40050</b>	Low Floor w/Cummins ISL 8.9 (8.9L) Eng. (2019) <b>Lube</b> (3401544)..... <b>B40142</b> <b>Fuel</b> (5303743)..... <b>BF63000</b>	Phantom w/Cummins ISL Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel/Water Separator</b> (Fleetguard FS1003)..... <b>BF1293-SPS</b> <b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b> <b>Fuel</b> (Fleetguard FF5636)..... <b>BF7924</b> <b>Air</b> (Don. P129396)..... <b>PA3951</b> <b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b>
<b>GILLIG Trucks &amp; Buses</b> Models w/Cat 1160 Eng. <b>Lube</b> ..... <b>[2] BT364</b> <b>Fuel</b> ..... <b>BF583</b>	Low Floor w/Cummins ISL-G 8.9 (8.9L) Eng. (2020) <b>Lube</b> (5444774)..... <b>B40142</b> <b>Fuel</b> (5303743)..... <b>BF63000</b>	Low Floor w/Cummins ISM Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154 +</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (Fleetguard FS1000)..... <b>BF1259</b> <b>Fuel/Water Separator</b> (Fleetguard FS1003)..... <b>BF1293-SPS</b> <b>Fuel/Water Separator</b> (Fleetguard FS1282)..... <b>BF1282 +</b> <b>Air</b> (Don. P129396)..... <b>PA3951</b> <b>Coolant</b> (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b> <b>Coolant</b> (w/o Chemical) (Fleetguard WF2122)..... <b>B5088 +</b>
Low Floor w/Cummins ISB 6.7 (6.7L) Eng. (2018) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	Low Floor w/Cummins ISL-G 8.9 (8.9L) Eng. (2019) <b>Lube</b> (Fleetguard LF9009)..... <b>B40142</b> <b>Fuel/Water Separator</b> (NG5900). <b>BF7695</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b>	Phantom w/Cummins ISL Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel/Water Separator</b> (Fleetguard FS1003)..... <b>BF1293-SPS</b> <b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b> <b>Fuel</b> (Fleetguard FF5636)..... <b>BF7924</b> <b>Air</b> (Don. P129396)..... <b>PA3951</b> <b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b>
Low Floor w/Cummins ISB 6.7 (6.7L) Eng. (2019) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	Low Floor w/Cummins ISL-G 8.9 (8.9L) Eng. (2020) <b>Lube</b> (Fleetguard LF9009)..... <b>B40142</b> <b>Fuel</b> (Fleetguard NG5900)..... <b>BF7695</b>	Low Floor w/Cummins ISM Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154 +</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (Fleetguard FS1000)..... <b>BF1259</b> <b>Fuel/Water Separator</b> (Fleetguard FS1003)..... <b>BF1293-SPS</b> <b>Fuel/Water Separator</b> (Fleetguard FS1282)..... <b>BF1282 +</b> <b>Air</b> (Don. P129396)..... <b>PA3951</b> <b>Coolant</b> (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b> <b>Coolant</b> (w/o Chemical) (Fleetguard WF2122)..... <b>B5088 +</b>
Low Floor w/Cummins ISB 6.7 (6.7L) Eng. (2020) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	Low Floor w/Cummins ISL-G (8.9L) Eng. (2022) <b>Lube</b> (5444774)..... <b>B40142</b> <b>Fuel/Water Separator</b> (3607140). <b>BF7695</b>	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>GILLIG</b> Trucks & Buses (cont'd)	<b>GIRARDIN</b> Buses (cont'd)	<b>GIRARDIN</b> Buses (cont'd)
Phantom w/Detroit 6V92 Eng. (1991)	MB-II w/GM 4.8L Gas Eng. (Cont'd)	MB-IV/G5 w/Ford 6.0L Diesel Eng.
Lube..... [2] B95 +	Fuel (2006-on) (N/S)..... N/S	Lube (w/o Screw on Cap)
P. Fuel..... BF5800 +	Radial Seal Air (ACDelco	(Motorcraft FL2016)..... P7235
S. Fuel..... BF5810	A1621C)..... RS4131	Lube (w/Screw on Cap) (Wix
Air..... PA3951	Trans. (4L60-E S. Pan)	57312)..... P7436
Coolant..... BW5137	(24200796)..... 18010	Fuel (Motorcraft FD4606)..... PF7852 KIT
Trans..... BT359	Trans. (4L60-E D. Pan)	Channel Flow Air (Motorcraft
Hyd..... BT287-10	(24208576)..... 18056	FA1746)..... CA4999
Phantom w/Diesel Eng. (1995-96)	Trans. (4L80-E) (24210956)..... 18027	Trans. Ele. (Motorcraft FT145)..... P7247
Lube..... [2] B495	MB-II w/GM 6.0L Gas Eng.	Trans. Pan-Type (To 11/07)
P. Fuel..... BF5800 +	Lube (2003-06) (ACDelco PF46).. B31	(Motorcraft FT144)..... 20005
S. Fuel..... BF5810	Lube (2007-on)..... B160	Trans. Pan-Type (11/07-on)
Air..... PA3951	Fuel (2003-05 (Thd. Both Ends))	(Motorcraft FT180)..... 20021
Trans. (2 In. Kit)..... PT9416-MPG KIT	(ACDelco GF652)..... BF853	MB-IV/G5 w/Ford 6.8L Gas Eng.
Motorhome w/Cat 3208 Eng.	Fuel (2003-05 (Thd. One End))	Lube (Motorcraft FL820S)..... B329
Lube (1R0713)..... [2] BT230 +	(ACDelco GF578)..... BF1171	Fuel (To 2002) (Motorcraft
Lube (1R0714)..... [2] B75	Fuel (2006-on) (N/S)..... N/S	FG872)..... BF1166
Lube (9L9200)..... [2] BT364	Radial Seal Air (ACDelco	Fuel (2003-on) (Motorcraft
Fuel/Water Separator (8N9803).. BF912	A1621C)..... RS4131	FG986B)..... BF7668 +
Fuel Ele. (9M2341)..... PF935	Trans. (4L60-E S. Pan)	Air (Motorcraft FA1632)..... PA4075
Fuel Spin-on (1R0740)..... BF970 +	(24200796)..... 18010	Trans. (E4OD) (Motorcraft
Fuel Spin-on (1R0750)..... BF7633 +	Trans. (4L60-E D. Pan)	FT113)..... 18264
	(24208576)..... 18056	Trans. (4R100) (Motorcraft
	Trans. (4L80-E) (24210956)..... 18027	FT105)..... 18029
<b>GIRARDIN</b> Buses	MB-II w/GM 6.6L Diesel Eng.	MB-IV/G5 w/GM 6.0L Gas Eng.
MB-II w/Ford 5.4L Gas Eng.	Lube (ACDelco PF2232)..... B1441	Lube (2003-06) (ACDelco PF46).. B31
Lube (Motorcraft FL820S)..... B329	Fuel/Water Separator (Upgrade)	Lube (2007-on)..... B160
Fuel (Motorcraft FG986B)..... BF7668 +	(ACDelco TP3018)..... BF46062 <sup>89</sup>	Fuel (2003-05 (Thd. Both Ends))
Air (Motorcraft FA1634)..... PA4075	Radial Seal Air (ACDelco	(ACDelco GF652)..... BF853
Trans. (4R100 S. Pan)	A2032C)..... RS4859	Fuel (2003-05 (Thd. One End))
(Motorcraft FT113)..... 18264	Trans. Pan-Type (S. Pan w/o	(ACDelco GF578)..... BF1171
Trans. (4R100 D. Pan)	Gskt.) (Allison 29537965)..... 20004	Fuel (2006-on) (N/S)..... N/S
(Motorcraft FT114)..... 18265	Trans. Pan-Type (S. Pan	Radial Seal Air (ACDelco
Trans. (4R70W) (Motorcraft	w/Gskt.) (Allison 29537965)..... 20016	A1621C)..... RS4131
FT105)..... 18029	Trans. Pan-Type (D. Pan w/o	Trans. (4L60-E S. Pan)
Trans. (5R110W) (Motorcraft	Gskt.) (Allison 29537966)..... 20003	(24200796)..... 18010
FT144)..... 20005	Trans. Pan-Type (D. Pan	Trans. (4L60-E D. Pan)
Trans. Ele. (5R110W) (Motorcraft	w/Gskt.) (Allison 29537966)..... 20017	(24208576)..... 18056
FT145)..... P7247	Trans. Spin-on (Allison	Trans. (4L80-E) (24210956)..... 18027
MB-II w/Ford 6.0L Diesel Eng.	29539579)..... BT8460	MB-IV/G5 w/GM 6.6L Diesel Eng.
Lube (w/o Screw on Cap)	Steering (88892858)..... P106-HD	Lube (ACDelco PF2232)..... B1441
(Motorcraft FL2016)..... P7235	MB-IV/G5 w/Ford 5.4L Gas Eng.	Fuel/Water Separator (Upgrade)
Lube (w/Screw on Cap) (Wix	Lube (Motorcraft FL820S)..... B329	(ACDelco TP3018)..... BF46062 <sup>89</sup>
57312)..... P7436	Fuel (Motorcraft FG986B)..... BF7668 +	Radial Seal Air (ACDelco
Fuel (Motorcraft FD4606)..... PF7852 KIT	Air (Motorcraft FA1634)..... PA4075	A2032C)..... RS4859
Channel Flow Air (Motorcraft	Trans. (4R100 S. Pan)	Trans. Pan-Type (S. Pan w/o
FA1746)..... CA4999	(Motorcraft FT113)..... 18264	Gskt.) (Allison 29537965)..... 20004
Trans. Ele. (Motorcraft FT145)..... P7247	Trans. (4R100 D. Pan)	Trans. Pan-Type (S. Pan
Trans. Pan-Type (To 11/07)	(Motorcraft FT114)..... 18265	w/Gskt.) (Allison 29537965)..... 20016
(Motorcraft FT144)..... 20005	Trans. (4R70W) (Motorcraft	Trans. Pan-Type (D. Pan w/o
Trans. Pan-Type (11/07-on)	FT105)..... 18029	Gskt.) (Allison 29537966)..... 20003
(Motorcraft FT180)..... 20021	Trans. (5R110W, To 11/07)	Trans. Pan-Type (D. Pan
MB-II w/GM 4.8L Gas Eng.	(Motorcraft FT144)..... 20005	w/Gskt.) (Allison 29537966)..... 20017
Lube (2003-05) (ACDelco PF46).. B31	Trans. (5R110W, 11/07-on)	Trans. Spin-on (Allison
Lube (2006-on)..... B160	(Motorcraft FT180)..... 20021	29539579)..... BT8460
Fuel (2003-05 (Thd. Both Ends))	Trans. Ele. (5R110W) (Motorcraft	Steering (88892858)..... P106-HD
(ACDelco GF652)..... BF853	FT145)..... P7247	
Fuel (2003-05 (Thd. One End))		
(ACDelco GF578)..... BF1171		

+ See Product Guide for Variations of This Number. <sup>89</sup> Inner Fender Liner Removal Recommended for Proper Installation. Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



<b>GLAVAL Buses</b>	<b>GMC-DETROIT DIESEL Diesel Engines (cont'd)</b>	<b>GMC-DETROIT DIESEL Diesel Engines (cont'd)</b>
Apollo w/Cummins ISB Eng. <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	4-53 Series <b>Lube Ele.</b> ..... <b>P20-HD +</b> <b>Lube Spin-on</b> (23518671)..... <b>B95 +</b> <b>Lube Spin-on</b> (Upgrade) (23518524)..... <b>B95-MPG +</b> <b>P. Fuel Sock</b> ..... <b>F916-C</b> <b>P. Fuel Spin-on</b> (23518527)..... <b>BF592 +</b> <b>3 5/8 In. S. Fuel Ele.</b> (5573263).... <b>PF906</b> <b>7 13/16 In. S. Fuel Ele.</b> (5574508)..... <b>PF902</b> <b>S. Fuel Spin-on</b> (23518526)..... <b>BF593</b>	6V-71 Series (Cont'd) <b>5 3/4 In. P. Fuel Sock</b> (5574961). <b>F916-C</b> <b>8 5/16 In. P. Fuel Ele.</b> (5575032). <b>PF845</b> <b>9 In. P. Fuel Sock</b> (5574980)..... <b>F844-A</b> <b>P. Fuel Spin-on</b> (23518481)..... <b>BF5800 +</b> <b>7 13/16 In. S. Fuel Ele.</b> (5574508)..... <b>PF902</b> <b>8 1/4 In. S. Fuel Ele.</b> (6436719).... <b>PF846</b> <b>S. Fuel Spin-on</b> (23518482)..... <b>BF5810</b> <b>S. Fuel Spin-on</b> (Upgrade) (23518530)..... <b>BF5815</b>
<b>GLOBE TRAILERS Trailers</b>	4-71 Series <b>F-F Lube Ele.</b> ..... <b>P20-HD +</b> <b>F-F Lube Spin-on</b> (23518671)..... <b>B95 +</b> <b>F-F Lube Spin-on</b> (Upgrade) (23518524)..... <b>B95-MPG +</b> <b>B-P Lube</b> (5572425)..... <b>P52</b> <b>P. Fuel Sock</b> (1951-on)..... <b>F916-C</b> <b>P. Fuel Spin-on</b> (23518527)..... <b>BF592 +</b> <b>S. Fuel Ele.</b> (1951-56)..... <b>PF902</b> <b>S. Fuel Ele.</b> (1957-on)..... <b>PF906</b> <b>S. Fuel Spin-on</b> (23518526)..... <b>BF593</b>	6V-92 Series <b>F-F Lube Ele.</b> ..... <b>P20-HD +</b> <b>F-F Lube Spin-on</b> (23518671)..... <b>B95 +</b> <b>F-F Lube Spin-on</b> (Upgrade) (23518524)..... <b>B95-MPG +</b> <b>P. Fuel Ele.</b> ..... <b>PF845</b> <b>P. Fuel Spin-on</b> (23518481)..... <b>BF5800 +</b> <b>S. Fuel Ele.</b> ..... <b>PF902</b> <b>S. Fuel Spin-on</b> (23518482)..... <b>BF5810</b> <b>S. Fuel Spin-on</b> (Upgrade) (23518530)..... <b>BF5815</b>
<b>GMC-DETROIT DIESEL Diesel Engines</b>	6-71 <b>F-F Lube Ele.</b> ..... <b>P20-HD +</b> <b>F-F Lube Spin-on</b> (23518671)..... <b>B95 +</b> <b>F-F Lube Spin-on</b> (Upgrade) (23518524)..... <b>B95-MPG +</b> <b>B-P Lube Ele.</b> (5572425)..... <b>P52</b> <b>5 3/4 In. P. Fuel Sock</b> (1951-on).... <b>F916-C</b> <b>8 5/16 In. P. Fuel Ele.</b> ..... <b>PF845</b> <b>P. Fuel Spin-on</b> (23518481)..... <b>BF5800 +</b> <b>S. Fuel Ele.</b> (1951-on)..... <b>PF902</b> <b>S. Fuel Spin-on</b> (23518482)..... <b>BF5810</b> <b>S. Fuel Spin-on</b> (Upgrade) (23518530)..... <b>BF5815</b>	8.2 L <b>Lube</b> (23518668)..... <b>[2] B6-HPG +</b> <b>P. Fuel</b> (23518527)..... <b>BF592 +</b> <b>S. Fuel</b> (23518526)..... <b>BF593</b>
2-53 <b>F-F Lube</b> (5574978)..... <b>PT11</b> <b>B-P Lube</b> (5572288)..... <b>P53</b> <b>Opt. B-P Lube</b> (5572425)..... <b>P52</b> <b>P. Fuel Sock</b> ..... <b>F916-C</b> <b>S. Fuel Ele.</b> ..... <b>PF906</b>	6-110 Series <b>F-F Lube Ele.</b> ..... <b>[2] P20-HD +</b> <b>B-P Lube Ele.</b> (5572425)..... <b>[2] P52</b> <b>P. Fuel Sock</b> ..... <b>F916-C</b> <b>S. Fuel Ele.</b> ..... <b>PF902</b>	8V-53 Series <b>Lube Ele.</b> ..... <b>P20-HD +</b> <b>P. Fuel Sock</b> ..... <b>F916-C</b> <b>S. Fuel Ele.</b> ..... <b>PF906</b>
2-71 <b>F-F Lube Ele.</b> ..... <b>P20-HD +</b> <b>F-F Lube Spin-on</b> ..... <b>B95 +</b> <b>Std. 8 In. B-P Lube</b> (5572425)..... <b>P52</b> <b>P. Fuel Sock</b> (1951-on)..... <b>F916-C</b> <b>P. Fuel Spin-on</b> ..... <b>BF592 +</b> <b>S. Fuel Ele.</b> (1951-on)..... <b>PF906</b> <b>S. Fuel Spin-on</b> ..... <b>BF593</b> <b>Std. Fuel</b> (To 1951) (5578946).... <b>PF804</b>	6V-53 <b>F-F Lube Ele.</b> ..... <b>P20-HD +</b> <b>F-F Lube Spin-on</b> (23518671)..... <b>B95 +</b> <b>F-F Lube Spin-on</b> (Upgrade) (23518524)..... <b>B95-MPG +</b> <b>B-P Lube Ele.</b> ..... <b>P52</b> <b>P. Fuel Sock</b> ..... <b>F916-C</b> <b>P. Fuel Spin-on</b> (23518481)..... <b>BF5800 +</b> <b>S. Fuel Ele.</b> (5573261)..... <b>PF906</b> <b>S. Fuel Spin-on</b> (23518482)..... <b>BF5810</b> <b>Fuel Spin-on</b> (Upgrade) (23518530)..... <b>BF5815</b>	8V-71 Series <b>F-F Lube Ele.</b> ..... <b>P20-HD +</b> <b>F-F Lube Spin-on</b> (23518671)..... <b>B95 +</b> <b>F-F Lube Spin-on</b> (Upgrade) (23518524)..... <b>B95-MPG +</b> <b>B-P Lube Ele.</b> ..... <b>P52</b> <b>5 3/4 In. P. Fuel Sock</b> (5574961). <b>F916-C</b> <b>8 5/16 In. P. Fuel Ele.</b> (5575032). <b>PF845</b> <b>9 In. P. Fuel Sock</b> (5574980)..... <b>F844-A</b> <b>P. Fuel Spin-on</b> (23518481)..... <b>BF5800 +</b> <b>7 13/16 In. S. Fuel Ele.</b> (5574508)..... <b>PF902</b> <b>8 1/4 In. S. Fuel Ele.</b> (6436719).... <b>PF846</b> <b>S. Fuel Spin-on</b> (23518482)..... <b>BF5810</b> <b>S. Fuel Spin-on</b> (Upgrade) (23518530)..... <b>BF5815</b>
3-53 Series <b>F-F Lube Ele.</b> (5573014)..... <b>P20-HD +</b> <b>F-F Lube Spin-on</b> (23518525)..... <b>B105 +</b> <b>Opt. F-F Lube</b> (5574978)..... <b>PT11</b> <b>P. Fuel Sock</b> ..... <b>F916-C</b> <b>P. Fuel Spin-on</b> (23518527)..... <b>BF592 +</b> <b>3 5/8 In. S. Fuel Ele.</b> (5573263).... <b>PF906</b> <b>7 13/16 In. S. Fuel Ele.</b> (5574508)..... <b>PF902</b> <b>S. Fuel Spin-on</b> (23518526)..... <b>BF593</b>	6V-71 Series <b>F-F Lube Ele.</b> ..... <b>P20-HD +</b> <b>F-F Lube Spin-on</b> (23518671)..... <b>B95 +</b> <b>F-F Lube Spin-on</b> (Upgrade) (23518524)..... <b>B95-MPG +</b> <b>B-P Lube Ele.</b> ..... <b>P52</b> <b>P. Fuel Sock</b> ..... <b>F916-C</b> <b>P. Fuel Spin-on</b> (23518481)..... <b>BF5800 +</b> <b>S. Fuel Ele.</b> (5573261)..... <b>PF906</b> <b>S. Fuel Spin-on</b> (23518482)..... <b>BF5810</b> <b>Fuel Spin-on</b> (Upgrade) (23518530)..... <b>BF5815</b>	8V-92 Series <b>F-F Lube Ele.</b> ..... <b>P20-HD +</b> <b>F-F Lube Spin-on</b> (23518671)..... <b>B95 +</b> <b>F-F Lube Spin-on</b> (Upgrade) (23518524)..... <b>B95-MPG +</b> <b>P. Fuel Ele.</b> ..... <b>PF845</b> <b>P. Fuel Spin-on</b> (23518481)..... <b>BF5800 +</b> <b>S. Fuel Ele.</b> ..... <b>PF902</b> <b>S. Fuel Spin-on</b> (23518482)..... <b>BF5810</b> <b>S. Fuel Spin-on</b> (Upgrade) (23518530)..... <b>BF5815</b>
3-71 <b>F-F Lube Ele.</b> ..... <b>P20-HD +</b> <b>F-F Lube Spin-on</b> (23518671)..... <b>B95 +</b> <b>F-F Lube Spin-on</b> (Upgrade) (23518524)..... <b>B95-MPG +</b> <b>B-P Lube</b> ..... <b>P52</b> <b>P. Fuel Sock</b> (1951-on)..... <b>F916-C</b> <b>P. Fuel Spin-on</b> (23518527)..... <b>BF592 +</b> <b>S. Fuel Ele.</b> (1951-on)..... <b>PF906</b> <b>S. Fuel Spin-on</b> (23518526)..... <b>BF593</b> <b>Std. Fuel</b> (To 1951) (5578946).... <b>PF804</b>	6V-53 <b>F-F Lube Ele.</b> ..... <b>P20-HD +</b> <b>F-F Lube Spin-on</b> (23518671)..... <b>B95 +</b> <b>F-F Lube Spin-on</b> (Upgrade) (23518524)..... <b>B95-MPG +</b> <b>B-P Lube Ele.</b> ..... <b>P52</b> <b>P. Fuel Sock</b> ..... <b>F916-C</b> <b>P. Fuel Spin-on</b> (23518481)..... <b>BF5800 +</b> <b>S. Fuel Ele.</b> (5573261)..... <b>PF906</b> <b>S. Fuel Spin-on</b> (23518482)..... <b>BF5810</b> <b>Fuel Spin-on</b> (Upgrade) (23518530)..... <b>BF5815</b>	8V-71 Series <b>F-F Lube Ele.</b> ..... <b>P20-HD +</b> <b>F-F Lube Spin-on</b> (23518671)..... <b>B95 +</b> <b>F-F Lube Spin-on</b> (Upgrade) (23518524)..... <b>B95-MPG +</b> <b>B-P Lube Ele.</b> ..... <b>P52</b>
4-51 <b>P. Fuel Sock</b> ..... <b>F916-C</b> <b>S. Fuel Ele.</b> ..... <b>PF906</b>	6V-71 Series <b>F-F Lube Ele.</b> ..... <b>P20-HD +</b> <b>F-F Lube Spin-on</b> (23518671)..... <b>B95 +</b> <b>F-F Lube Spin-on</b> (Upgrade) (23518524)..... <b>B95-MPG +</b> <b>B-P Lube Ele.</b> ..... <b>P52</b>	8V-92 Series <b>F-F Lube Ele.</b> ..... <b>P20-HD +</b> <b>F-F Lube Spin-on</b> (23518671)..... <b>B95 +</b> <b>F-F Lube Spin-on</b> (Upgrade) (23518524)..... <b>B95-MPG +</b> <b>P. Fuel Ele.</b> ..... <b>PF845</b> <b>P. Fuel Spin-on</b> (23518481)..... <b>BF5800 +</b> <b>S. Fuel Ele.</b> ..... <b>PF902</b> <b>S. Fuel Spin-on</b> (23518482)..... <b>BF5810</b> <b>S. Fuel Spin-on</b> (Upgrade) (23518530)..... <b>BF5815</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

GMC-DETROIT DIESEL Diesel Engines (cont'd)	GMC-DETROIT DIESEL Diesel Engines (cont'd)	GMC-DETROIT DIESEL Diesel Engines (cont'd)
8V-149 Series Lube (23518524)..... [3] B95-MPG + P. Fuel Spin-on (23518528)..... [2] BF784 S. Fuel Spin-on (23518529)..... BF7697	16V-92 Series (Cont'd) B-P Lube Ele..... [2] P52 P. Fuel Sock (5574980)..... F844-A P. Fuel Spin-on (23518528)..... BF784 S. Fuel Ele. (6436719)..... PF846 S. Fuel Spin-on (23518532)..... BF785 S. Fuel Spin-on (Upgrade) (23518529)..... BF7697	677 (11.1L), 774 (12.7L) Series 60 F-F Lube (To 1993) (ACDelco PF911)..... [2] B95 + F-F Lube (1993-on) (ACDelco PF2100)..... [2] B495 F-F Lube (1993-on (Upgrade)) (23524251)..... B495-SS B-P Lube (To 1993)..... B7577 P. Fuel/Water Separator (w/Drain) (23512317)..... BF5813 + P. Fuel/Water Separator (Open End for Bowl) (23512317)..... BF5813-O + Opt. Fuel/Water Separator (23516189)..... BF5812 Opt. Fuel/Water Separator (Davco) (15152281)..... BF7759 P. Fuel..... BF5800 + S. Fuel..... BF5810
12V-71 Series F-F Lube Ele..... [2] P20-HD + F-F Lube Spin-on (23518671)..... [2] B95 + F-F Lube Spin-on (Upgrade) (23518524)..... [2] B95-MPG + B-P Lube Ele..... [2] P52 8 5/16 In. P. Fuel Ele. (5575032). PF845 9 In. P. Fuel Sock (5574980)..... F844-A P. Fuel Spin-on (23518528)..... BF784 S. Fuel Ele. (6436719)..... PF846 S. Fuel Spin-on (23518532)..... BF785 S. Fuel Spin-on (Upgrade) (23518529)..... BF7697	16V-149 Series F-F Lube Ele..... [4] P20-HD + F-F Lube Spin-on (23518524)..... [4] B95-MPG + F-F Lube Spin-on (Tube, Shell Oil Cooler-Equipped) (23518524). [6] B95-MPG + B-P Lube Ele..... [4] P52 P. Fuel Sock (6436874)..... F908-A P. Fuel Spin-on (23518528)..... [2] BF784 S. Fuel Ele. (6436719)..... PF846 S. Fuel Spin-on (23518529)..... [2] BF7697	D351, D478, DH478 Lube Ele..... P20-HD + P. Fuel Sock..... F916-C S. Fuel Ele..... PF902
12V-92 Series F-F Lube Ele..... [2] P20-HD + F-F Lube Spin-on (23518671)..... [2] B95 + F-F Lube Spin-on (Upgrade) (23518524)..... [2] B95-MPG + Some F-F Lube Spin-on (23518671)..... [4] B95 + P. Fuel Sock (5574980)..... F844-A P. Fuel Spin-on (23518528)..... BF784 S. Fuel Ele. (6436719)..... PF846 S. Fuel Spin-on (23518532)..... BF785 S. Fuel Spin-on (Upgrade) (23518529)..... BF7697	20V-149 Series F-F Lube Spin-on (23518531)..... [6] B95-MPG + P. Fuel Spin-on (23518528)..... [2] BF784 S. Fuel Spin-on (23518529)..... [2] BF7697 Single Fuel Spin-on (Fuel Pro 40) (23512631)..... BF7639-D	D637, DH637 Lube Ele..... P20-HD + S. Fuel Ele..... PF902
12V-149 Series F-F Lube Ele..... [4] P20-HD + F-F Lube Spin-on (23518524)..... [4] B95-MPG + Some F-F Lube Spin-on (23518524)..... [6] B95-MPG + P. Fuel Sock (6436874)..... F908-A P. Fuel Spin-on (25014341)..... [2] BF784 S. Fuel Ele. (6436719)..... PF846 S. Fuel Spin-on (25013535)..... [2] BF7697	350 V8 (Olds) Lube (1978)..... B39 Lube (1979-on)..... B30 Box-Style Fuel..... BF806 Air..... PA2073	Series 50 Lube (23518480)..... [2] B495 P. Fuel/Water Separator (w/Drain) (23512317)..... BF5813 + Opt. Fuel/Water Separator (23516189)..... BF5812 P. Fuel (23518481)..... BF5800 + S. Fuel (23518482)..... BF5810 P. Fuel/Water Separator (Open End for Bowl) (23512317)..... BF5813-O + S. Fuel (Upgrade) (23518530)..... BF5815
12V-149 Series F-F Lube Ele..... [4] P20-HD + F-F Lube Spin-on (23518524)..... [4] B95-MPG + Some F-F Lube Spin-on (23518524)..... [6] B95-MPG + P. Fuel Sock (6436874)..... F908-A P. Fuel Spin-on (25014341)..... [2] BF784 S. Fuel Ele. (6436719)..... PF846 S. Fuel Spin-on (25013535)..... [2] BF7697	379 (6.2L) V8 Lube..... B6 + P. Fuel (1982-83, (Exc. 1983 Vans))..... BF781 P. Fuel (1983, (Vans))..... BF592 + S. Fuel (1982-83, (Exc. 1983 Vans))..... BF782 Box-Style S. Fuel (1983, (Vans)). BF855 Box-Style Fuel (1984-on)..... BF856 Air..... PA2073	Series 55 Lube (23550401)..... B7135 P. Fuel (23518481)..... BF5800 + S. Fuel (23518482)..... BF5810 S. Fuel (Upgrade) (23518530)..... BF5815
16V-71 Series F-F Lube Ele..... [2] P20-HD + F-F Lube Spin-on (23518671)..... [2] B95 + F-F Lube Spin-on (Upgrade) (23518524)..... [2] B95-MPG + B-P Lube Ele..... [2] P52 P. Fuel Sock (5574980)..... F844-A P. Fuel Spin-on (23518528)..... BF784 S. Fuel Ele. (6436719)..... PF846 S. Fuel Spin-on (23518532)..... BF785 S. Fuel Spin-on (Upgrade) (23518529)..... BF7697	395 (6.5L) V8 Lube..... B1428 + Fuel/Water Separator Ele. (To 1995)..... BF1201 Air (1992-on)..... PA2232	Series 60 F-F Lube (To 1993) (23518671).... [2] B95 + F-F Lube (1993-on) (23518480).... [2] B495 F-F Lube (1993-on (Upgrade)) (23524251)..... [2] B495-SS B-P Lube (To 1993)..... B7577 P. Fuel/Water Separator (w/Drain) (23512317)..... BF5813 + P. Fuel/Water Separator (Open End for Bowl) (23512317)..... BF5813-O + Opt. Fuel/Water Separator (23516189)..... BF5812 Opt. Fuel/Water Separator (Davco) (15152281)..... BF7759 P. Fuel (23518481)..... BF5800 + S. Fuel (23518482)..... BF5810 S. Fuel (Upgrade) (23518530)..... BF5815
16V-92 Series F-F Lube Ele..... [2] P20-HD + F-F Lube Spin-on (23518671)..... [2] B95 + F-F Lube Spin-on (Upgrade) (23518524)..... [2] B95-MPG + Some F-F Lube Spin-on (23518671)..... [4] B95 +	509 CID (8.2L) Lube..... [2] B6 + P. Fuel Spin-on..... BF592 + S. Fuel Spin-on..... BF593	
	518 CID (8.5L) Series 50 Lube..... [2] B495 P. Fuel/Water Separator (w/Drain) (23512317)..... BF5813 + P. Fuel/Water Separator (Open End for Bowl) (23512317)..... BF5813-O + Opt. Fuel/Water Separator (23516189)..... BF5812 P. Fuel..... BF5800 + S. Fuel..... BF5810	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>GMC-DETROIT DIESEL</b> Diesel Engines (cont'd)	
Series 60 (Cont'd)	
Opt. Fuel Ele. (Davco) (23514049).....	PF7680

<b>GRANDE WEST</b> Buses	
30 Foot w/Cummins ISB 6.7 (6.7L) Eng. (2018)	
Lube (3937736).....	B7177
Fuel (Fleetguard FF63009).....	BF63000
Crankcase Breather (4936636)...	CV15010
30 Foot w/Cummins ISB 6.7 (6.7L) Eng. (2019)	
Lube (3937736).....	B7177
Fuel (5303743).....	BF63000
Crankcase Breather (4936636)...	CV15010
30 Foot w/Cummins ISB 6.7 (6.7L) Eng. (2020)	
Lube (3937736).....	B7177
Fuel (Researching).....	BF63000
Crankcase Breather (4936636)...	CV15010
30 Foot w/Cummins ISB 6.7 (6.7L) Eng. (2021)	
Lube (3937736).....	B7177
Fuel (5303743).....	BF63000
Crankcase Breather (4936636)...	CV15010
38 Foot w/Cummins ISB 6.7 (6.7L) Eng. (2021)	
Lube (3937736).....	B7177
Fuel (5303743).....	BF63000
Crankcase Breather (4936636)...	CV15010
35 Foot w/Cummins ISB 6.7 (6.7L) Eng. (2019)	
Lube (3937736).....	B7177
Fuel (5303743).....	BF63000
Crankcase Breather (4936636)...	CV15010

<b>HANOMAG</b> Buses	
SC1, 3, 5, HS160	
Lube Ele. (5985421000).....	P235
P. Fuel Ele. (5984520700).....	PF231
S. Fuel Ele. (5984520800).....	PF950
HS200	
Lube Ele. (5125420100).....	P42
P. Fuel Ele. (5984520700).....	PF231
S. Fuel Ele. (5984520800).....	PF950

<b>HANOMAG</b> Trucks	
40KA	
Fuel Ele. (153187003).....	F953-F
F/H111, 112, 121, 122, 131, 140, 141, 150, 151, 161, 170, 191, 201, 221, 261, 320, 321	
Lube (711922604).....	B236 +
Lube (711922853).....	BT292
Opt. Fuel/Water Separator.....	BF1221 +
Fuel (711983614).....	BF988 +
Steering.....	P106-HD
Hyd. (921488).....	PT691
F20, 25, 30, 35 w/Austin A60 Eng.	
F-F Lube (6171840025).....	P102
Fuel (153187002).....	PF834

<b>HANOMAG</b> Trucks (cont'd)	
F20, 25, 30, 35, 36, 40B	
B-P Lube (1848525).....	P40
F45, 46, 55, 65, 66, 75, 76, 85, 86	
Lube Spin-on (860114932108)....	BT267
P. Fuel Spin-on (114924119).....	BF586
S. Fuel Spin-on (114924144).....	BF7591-D
F45A, F55KA w/Mercedes-Benz OM314 Eng.	
Lube (1845825).....	P41
Fuel Ele. (513173000).....	PF950
F130, F150 w/Mercedes-Benz OM352, OM360 Engs.	
B-P Lube (5125420100).....	P42
P. Fuel Ele. (5984520700).....	PF231
S. Fuel Ele. (5984520800).....	PF950
F163, 203, 223, 263 w/Mercedes-Benz OM403 Eng.	
Lube Ele. (5125420100).....	P42
P. Fuel Ele. (5984520700).....	PF231
S. Fuel Ele. (5984520800).....	PF950
Hyd. (921488).....	PT691
Garant, Garants, Markant w/D351 Eng.	
Fuel (153187002).....	PF834
HS3-125, HS3-180, HK20, HS34, HS100, HS120, HS140, HS145	
Lube Ele. (5985421000).....	P235
P. Fuel Ele. (5984520700).....	PF231
S. Fuel Ele. (5984520800).....	PF950
HS11, 12, 14, 15, 16, 19, 22, 26 w/6R1215G Eng.	
Lube Spin-on (711922604).....	B236 +
P. Fuel Ele. (5984520700).....	PF231
S. Fuel Ele. (5984520800).....	PF950

HS22TL	
Lube Ele. (5985421000).....	P235
Lube Ele.....	P721
P. Fuel Ele. (5984520700).....	PF231
S. Fuel Ele. (5984520800).....	PF950
HS90, HS95, HS115	
B-P Lube Ele. (5125420100).....	P42
P. Fuel Ele. (5984520700).....	PF231
S. Fuel Ele. (5984520800).....	PF950
HS100 w/512DJ Eng.	
B-P Lube (5125420100).....	P42
Fuel Ele. (5984520800).....	PF950
HS165, HS170	
P. Fuel Ele. (5984520700).....	PF231
S. Fuel Ele. (5984520800).....	PF950
Kurier II w/D301 Eng.	
S. Fuel Ele. (5984520800).....	PF950
Garant, Markant, Kurier I, Kurier II, AL28, L28	
Fuel (153187003).....	PF834

HS22TL	
Lube Ele. (5985421000).....	P235
Lube Ele.....	P721
P. Fuel Ele. (5984520700).....	PF231
S. Fuel Ele. (5984520800).....	PF950
HS90, HS95, HS115	
B-P Lube Ele. (5125420100).....	P42
P. Fuel Ele. (5984520700).....	PF231
S. Fuel Ele. (5984520800).....	PF950
HS100 w/512DJ Eng.	
B-P Lube (5125420100).....	P42
Fuel Ele. (5984520800).....	PF950
HS165, HS170	
P. Fuel Ele. (5984520700).....	PF231
S. Fuel Ele. (5984520800).....	PF950
Kurier II w/D301 Eng.	
S. Fuel Ele. (5984520800).....	PF950
Garant, Markant, Kurier I, Kurier II, AL28, L28	
Fuel (153187003).....	PF834

HS22TL	
Lube Ele. (5985421000).....	P235
Lube Ele.....	P721
P. Fuel Ele. (5984520700).....	PF231
S. Fuel Ele. (5984520800).....	PF950
HS90, HS95, HS115	
B-P Lube Ele. (5125420100).....	P42
P. Fuel Ele. (5984520700).....	PF231
S. Fuel Ele. (5984520800).....	PF950
HS100 w/512DJ Eng.	
B-P Lube (5125420100).....	P42
Fuel Ele. (5984520800).....	PF950
HS165, HS170	
P. Fuel Ele. (5984520700).....	PF231
S. Fuel Ele. (5984520800).....	PF950
Kurier II w/D301 Eng.	
S. Fuel Ele. (5984520800).....	PF950
Garant, Markant, Kurier I, Kurier II, AL28, L28	
Fuel (153187003).....	PF834

HS22TL	
Lube Ele. (5985421000).....	P235
Lube Ele.....	P721
P. Fuel Ele. (5984520700).....	PF231
S. Fuel Ele. (5984520800).....	PF950
HS90, HS95, HS115	
B-P Lube Ele. (5125420100).....	P42
P. Fuel Ele. (5984520700).....	PF231
S. Fuel Ele. (5984520800).....	PF950
HS100 w/512DJ Eng.	
B-P Lube (5125420100).....	P42
Fuel Ele. (5984520800).....	PF950
HS165, HS170	
P. Fuel Ele. (5984520700).....	PF231
S. Fuel Ele. (5984520800).....	PF950
Kurier II w/D301 Eng.	
S. Fuel Ele. (5984520800).....	PF950
Garant, Markant, Kurier I, Kurier II, AL28, L28	
Fuel (153187003).....	PF834

HS22TL	
Lube Ele. (5985421000).....	P235
Lube Ele.....	P721
P. Fuel Ele. (5984520700).....	PF231
S. Fuel Ele. (5984520800).....	PF950
HS90, HS95, HS115	
B-P Lube Ele. (5125420100).....	P42
P. Fuel Ele. (5984520700).....	PF231
S. Fuel Ele. (5984520800).....	PF950
HS100 w/512DJ Eng.	
B-P Lube (5125420100).....	P42
Fuel Ele. (5984520800).....	PF950
HS165, HS170	
P. Fuel Ele. (5984520700).....	PF231
S. Fuel Ele. (5984520800).....	PF950
Kurier II w/D301 Eng.	
S. Fuel Ele. (5984520800).....	PF950
Garant, Markant, Kurier I, Kurier II, AL28, L28	
Fuel (153187003).....	PF834

HS22TL	
Lube Ele. (5985421000).....	P235
Lube Ele.....	P721
P. Fuel Ele. (5984520700).....	PF231
S. Fuel Ele. (5984520800).....	PF950
HS90, HS95, HS115	
B-P Lube Ele. (5125420100).....	P42
P. Fuel Ele. (5984520700).....	PF231
S. Fuel Ele. (5984520800).....	PF950
HS100 w/512DJ Eng.	
B-P Lube (5125420100).....	P42
Fuel Ele. (5984520800).....	PF950
HS165, HS170	
P. Fuel Ele. (5984520700).....	PF231
S. Fuel Ele. (5984520800).....	PF950
Kurier II w/D301 Eng.	
S. Fuel Ele. (5984520800).....	PF950
Garant, Markant, Kurier I, Kurier II, AL28, L28	
Fuel (153187003).....	PF834

<b>HEIL</b> Hydraulic Systems	
Models	
Hyd. (750912030).....	PT23139-MPG

<b>HENDRICKSON</b> Trucks	
Custom	
Lube.....	P42
H-2-34-C5, H-3-38-C13 w/Cummins Eng.	
F-F Lube Ele.....	P999-HD
F-F Lube Spin-on.....	B196 +
B-P Lube Ele.....	C750-E +
Fuel Spin-on.....	BF957 +
Coolant Spin-on.....	BW5071
H-3-38-C13 w/GMC Diesel Eng.	
F-F Lube Ele.....	P20-HD +
P. Fuel Spin-on.....	BF5800 +
S. Fuel Spin-on.....	BF5810

<b>HENSCHEL</b> Diesel Engines, Trucks	
HS19	
Fuel.....	[2] PF834
HS100, HS100N, HS115, HS120, HS120AK, HS120K, HS120N, HS140, HS140N, HS170, HS190	
S. Fuel Ele.....	PF950

<b>HERCULES</b> Engines	
440	
Lube.....	[3] P52
590	
B-P Lube Sock.....	V1240-C

<b>HEULIEZ</b> Buses	
GX127 w/Tector 6 F4A Eng. (Euro 4)	
Lube Spin-on (2992242).....	BT7237
Fuel/Water Separator (5001859295).....	BF1217
Fuel Spin-on (2992241).....	BF7813
Radial Seal Air (42536332).....	RS5535
Air Dryer (503137484).....	BA5379
Crankcase Breather (2992447)...	P7336 KIT
Steering (42559501).....	P106-HD
Urea Oil/Air Separator (503139396).....	OAS98000
Urea (42553548).....	PE5270

GX327 w/Iveco Cursor 8 (F2B) Eng. (Euro 4/5)	
Lube Spin-on (99445200).....	B7174-MPG
Fuel/Water Separator (2992662).....	BF1365
Radial Seal Air (42536332).....	RS5535
Radial Seal Air (09/09-on) (5006254879).....	RS30062
Air Dryer (503137484).....	BA5379
Breather (Turbocharger) (2996238).....	BT9408
Crankcase Breather (504209107).....	CV15002
Trans. (ZF) (42535049).....	PT8385
Steering (42559501).....	P106-HD

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

HEULIEZ Buses (cont'd)	HIGER Buses	HINO Engines (cont'd)
GX327 w/Iveco Cursor 8 (F2B) Eng. (Euro 4/5) (Cont'd) <b>Urea Oil/Air Separator</b> (503139396)..... OAS98000 <b>Urea</b> (42553548)..... PE5270	KLQ6920Q w/Cummins ISDE285-30 Eng. <b>Lube</b> (Fleetguard LF16015)..... BT7237 <b>Fuel</b> (Fleetguard FF5612)..... BF7922 <b>Air Dryer</b> (Fleetguard AF27817).... BA5374 + <b>Steering</b> (Fleetguard HF6162)..... P106-HD	W04C (3.8L) <b>F-F Lube</b> (156071750)..... B404 W06E (6.0L) <b>F-F Lube</b> (156071740)..... B7005
GX327 CNG w/Iveco F2B E0642 GAZ Eng. <b>Lube Spin-on</b> (99445200)..... B7174-MPG <b>Radial Seal Air</b> (42536332)..... RS5535 <b>Radial Seal Air</b> (09/09-on) (5006254879)..... RS30062 <b>Air Dryer</b> (503137484)..... BA5379 <b>Crankcase Breather</b> (504209107)..... CV15002 <b>Trans. (ZF)</b> (42535049)..... PT8385 <b>Steering</b> (42559501)..... P106-HD	<b>HINO Buses</b> AK17 w/EH700 Eng. <b>Lube</b> (15607-1090)..... P723 <b>Fuel</b> (23401-1060)..... PF7550 <b>Air</b> (17801-1720)..... PA2961-FN	<b>HINO Trucks</b> 145 w/J05D (4.7L) Eng. (2005-on) <b>Lube</b> (156072051A)..... B7155 <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19624)..... PF7748 <b>Fuel/Water Separator Spin-on</b> (w/o Heater) (234011700A)..... BF1360 <b>Radial Seal Air</b> (178013430A).... RS2863 <b>Radial Seal XP Air</b> (178013430A)..... RS2863XP <b>Cab Air</b> (872121200A)..... CLN&R
GX337 w/FPT Tector 7 Eng. (Euro 6) <b>Lube Spin-on</b> (2992242)..... BT7237 <b>Fuel/Water Separator</b> (42549295)..... BF1292-O <b>Fuel Spin-on</b> (504292579)..... BF7922 <b>Channel Flow Primary Air</b> (5801699113)..... CA5514 <b>Channel Flow Secondary Air</b> (5801699114)..... PA5515 <b>Air Dryer</b> (5801382289)..... BA5379 <b>Crankcase Breather</b> (504153151)..... CV15006 <b>Steering</b> (42559501)..... P106-HD <b>Urea</b> (5801667204)..... PE17000	P-RB145 w/W04C-T (3.8L) Eng. <b>Fuel</b> (Don. P550127)..... BF46111 P-RH160 w/W04C-T (3.8L) Eng. <b>Fuel</b> (Don. P550127)..... BF46111	155 w/J05E-TP (5.0L) Eng. (2013) <b>Dual-Flow Lube</b> (S156071733).... BD7105 155 w/J05E-TP (5.0L) Eng. (2018) <b>Lube</b> (S156072051)..... B7155 <b>Fuel</b> (23304EV360)..... PF46138 <b>Cab Air</b> (8856837020)..... PA10157 <b>Diesel Exhaust Fluid</b> (S17K0E0011)..... PE17000
GX427 CNG w/Iveco Cursor 8 Gas Eng. <b>Lube Spin-on</b> (99445200)..... B7174-MPG <b>Some Radial Seal Air</b> (42536332)..... RS5535 <b>Some Radial Seal Air</b> (5006254879)..... RS30062 <b>Air Dryer</b> (503137484)..... BA5379 <b>Crankcase Breather</b> (504209107)..... CV15002 <b>Trans. (ZF)</b> (42535049)..... PT8385 <b>Steering</b> (42559501)..... P106-HD	RG1J <b>O. Air</b> (178012910M)..... PA3914 <b>I. Air</b> (178012900M)..... PA3915	155 w/J05E-TP (5.0L) Eng. (2019) <b>Lube</b> (S156072051)..... B7155 <b>Fuel</b> (23304EV360)..... PF46138 <b>Cab Air</b> (8856837020)..... PA10157 <b>Crankcase Breather</b> (S1222EV011)..... CV15011 <b>Diesel Exhaust Fluid</b> (S17K0E0011)..... PE17000
GX427 w/Iveco Cursor 8 Eng. (Euro 5) <b>Lube Spin-on</b> (99445200)..... B7174-MPG <b>Fuel/Water Separator</b> (2992662).... BF1365 <b>Some Radial Seal Air</b> (42536332)..... RS5535 <b>Some Radial Seal Air</b> (5006254879)..... RS30062 <b>Air Dryer</b> (503137484)..... BA5379 <b>Crankcase Breather</b> (504209107)..... CV15002 <b>Steering</b> (42559501)..... P106-HD <b>Hyd. (Turbocharger)</b> (2996238).... BT9408 <b>Urea</b> (42553548)..... PE5270 <b>Urea Oil/Air Separator</b> (503139396)..... OAS98000	RG197K <b>O. Air</b> (178012480M)..... PA2688 <b>I. Air</b> (178012460M)..... PA2621 U-AB2W w/W04D (4.0L) Eng. (1989-95) <b>Fuel</b> (Don. P550127)..... BF46111 U-RB1W w/W04C-T (3.0L) Eng. (1985) <b>Fuel</b> (Don. P550127)..... BF46111	155 w/J05E-TP (5.0L) Eng. (2020) <b>Lube</b> (S156072051)..... B7155 <b>Fuel</b> (23304EV360)..... PF46138 <b>Cab Air</b> (8856837020)..... PA10157 155 DC w/J05E-TP (5.0L) Eng. (2018) <b>Lube</b> (S156072051)..... B7155 <b>Fuel</b> (23304EV360)..... PF46138 <b>Cab Air</b> (8856837020)..... PA10157 <b>Diesel Exhaust Fluid</b> (S17K0E0011)..... PE17000
GX427 w/Iveco Cursor 8 Eng. (Euro 5) <b>Lube Spin-on</b> (99445200)..... B7174-MPG <b>Fuel/Water Separator</b> (2992662).... BF1365 <b>Some Radial Seal Air</b> (42536332)..... RS5535 <b>Some Radial Seal Air</b> (5006254879)..... RS30062 <b>Air Dryer</b> (503137484)..... BA5379 <b>Crankcase Breather</b> (504209107)..... CV15002 <b>Steering</b> (42559501)..... P106-HD <b>Hyd. (Turbocharger)</b> (2996238).... BT9408 <b>Urea</b> (42553548)..... PE5270 <b>Urea Oil/Air Separator</b> (503139396)..... OAS98000	<b>HINO Engines</b> EK100 <b>Lube Ele.</b> (15607-1101)..... P7053 H06C (6.5L) <b>F-F Lube</b> (156071740)..... B7005 <b>B-P Lube</b> (156071860)..... B7124 H07C (6.7L) <b>F-F Lube</b> (156071740)..... B7005 <b>B-P Lube</b> (156071860)..... B7124 H07D (6.7L) <b>Lube</b> (15607-1732)..... BD7105 <b>Fuel Ele.</b> (23401-1090)..... PF7572 <b>Fuel Spin-on</b> (23401-1332)..... BF7967 J05C (5.3L) <b>F-F Lube</b> (156072170)..... B7155 J05E (5.0L) <b>Lube</b> (156072050)..... B7155 <b>Fuel</b> (23304EV360)..... PF46138 J05D (4.7L) <b>F-F Lube</b> (156072051)..... B7155 J08C (8.0L) <b>F-F Lube</b> (156072170)..... B7155 J08E (7.7L) & (8.0L) <b>Dual-Flow Lube</b> (156072190).... BD7325 <b>F-F Lube</b> (15613E0030)..... B7513 <b>Lube</b> (15613E0110)..... B7155	155 DC w/J05E-TP (5.0L) Eng. (2019) <b>Lube</b> (S156072051)..... B7155 <b>Fuel</b> (23304EV360)..... PF46138 <b>Cab Air</b> (8856837020)..... PA10157 <b>Crankcase Breather</b> (S1222EV011)..... CV15011 <b>Diesel Exhaust Fluid</b> (S17K0E0011)..... PE17000 155 DC w/J05E-TP (5.0L) Eng. (2020) <b>Lube</b> (S156072051)..... B7155 <b>Fuel</b> (23304EV360)..... PF46138 <b>Cab Air</b> (8856837020)..... PA10157

+ See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

HINO Trucks (cont'd)	HINO Trucks (cont'd)	HINO Trucks (cont'd)
155h (Hybrid) w/J05E Eng. <b>Dual-Flow Lube</b> (S156071733).... <b>BD7105</b>	195h w/J05E-UG (5.0L) Eng. (2014) <b>Dual-Flow Lube</b> (S156071733).... <b>BD7105</b> <b>F-F Lube</b> (S156072051)..... <b>B7155</b>	238 w/J08E-TA (7.7L) Eng. (2005-10) (Cont'd) <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
165 w/J05D (4.7L) Eng. (2005-on) <b>Lube</b> (156072051A)..... <b>B7155</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19624)..... <b>PF7748</b> <b>Fuel/Water Separator Spin-on</b> (w/o Heater) (234011700A)..... <b>BF1360</b> <b>Radial Seal Air</b> (178013430A).... <b>RS2863</b> <b>Radial Seal XP Air</b> (178013430A)..... <b>RS2863XP</b> <b>Cab Air</b> (872121200A)..... <b>CLN&amp;R</b>	195h w/J05E-UG (5.0L) Eng. (2017) <b>Lube</b> (156072051A)..... <b>B7155</b> <b>Fuel</b> (23304EV360)..... <b>PF46138</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Diesel Exhaust Fluid</b> (S17K0E0011)..... <b>PE17000</b>
185 w/J05D (4.7L) Eng. (2005-on) <b>Lube</b> (156072051)..... <b>B7155</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19624)..... <b>PF7748</b> <b>Fuel/Water Separator Spin-on</b> (w/o Heater) (234011700)..... <b>BF1360</b> <b>Radial Seal Air</b> (178013430A).... <b>RS2863</b> <b>Radial Seal XP Air</b> (178013430A)..... <b>RS2863XP</b> <b>Cab Air</b> (872121200A)..... <b>CLN&amp;R</b>	195h w/J05E-UG (5.0L) Eng. (2019) <b>Lube</b> (S156072051)..... <b>B7155</b> <b>Fuel</b> (23304EV360)..... <b>PF46138</b> <b>Cab Air</b> (Pollen) (8856837020).... <b>PA10157</b> <b>Diesel Exhaust Fluid</b> (S17K0E0011)..... <b>PE17000</b>	238 w/J08E-TV (7.7L) Eng. (2008-10) <b>F-F Lube</b> (15613E0030)..... <b>B7513</b> <b>Dual-Flow Lube</b> (S156072190).... <b>BD7325</b> <b>Fuel/Water Separator Ele.</b> (FS1962490)..... <b>PF7748</b> <b>Fuel/Water Separator Spin-on</b> (w/o Heater) (234011700)..... <b>BF1360</b> <b>Radial Seal Air</b> (178013440A).... <b>RS2863</b> <b>Radial Seal XP Air</b> (178013440A)..... <b>RS2863XP</b> <b>Cab Air</b> (872121200A)..... <b>CLN&amp;R</b>
195 w/J05E-TP (5.0L) Eng. (2013-14) <b>Dual-Flow Lube</b> (S156071733).... <b>BD7105</b> <b>F-F Lube</b> (S156072051)..... <b>B7155</b>	195h DC w/J05E-UG (5.0L) Eng. (2014) <b>Lube</b> (S156072051)..... <b>B7155</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gasket)) (Allison 29537965).... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gasket)) (Allison 29537966).... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
195 w/J05E-TP (5.0L) Eng. (2017) <b>Lube</b> (S156072051)..... <b>B7155</b> <b>Fuel</b> (23304EV360)..... <b>PF46138</b> <b>Diesel Exhaust Fluid</b> (S17K0E0011)..... <b>PE17000</b>	195h DC w/J05E-UG (5.0L) Eng. (2019) <b>Lube</b> (S156072051)..... <b>B7155</b> <b>Fuel</b> (23304EV360)..... <b>PF46138</b> <b>Cab Air</b> (Pollen) (8856837020).... <b>PA10157</b> <b>Diesel Exhaust Fluid</b> (S17K0E0011)..... <b>PE17000</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Diesel Exhaust Fluid</b> (S17K0E0011)..... <b>PE17000</b>
195 w/J05E-TP (5.0L) Eng. (2018) <b>Lube</b> (S156072051)..... <b>B7155</b> <b>Fuel</b> (23304EV360)..... <b>PF46138</b> <b>Cab Air</b> (8856837020)..... <b>PA10157</b> <b>Diesel Exhaust Fluid</b> (S17K0E0011)..... <b>PE17000</b>	198 w/J08E Eng. (2013-17) <b>Trans. Pan-Type</b> (S. Pan (w/o Gasket)) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan (w/Gasket)) (Allison 29537965).... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan (w/o Gasket)) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan (w/Gasket)) (Allison 29537966).... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Diesel Exhaust Fluid</b> (S17K0E0011)..... <b>PE17000</b>
195 w/J05E-TP (5.0L) Eng. (2019) <b>Lube</b> (S156072051)..... <b>B7155</b> <b>Fuel</b> (23304EV360)..... <b>PF46138</b> <b>Cab Air</b> (8856837020)..... <b>PA10157</b> <b>Crankcase Breather</b> (S1222EV011)..... <b>CV15011</b> <b>Diesel Exhaust Fluid</b> (S17K0E0011)..... <b>PE17000</b>	198 w/J08E-VC (7.7L) Eng. (2018) <b>Dual-Flow Lube</b> (156072190A).... <b>BD7325</b>	238 w/J08E-VC (7.7L) Eng. (2011-14) <b>F-F Lube</b> (15613E0030)..... <b>B7513</b> <b>Dual-Flow Lube</b> (S156072190).... <b>BD7325</b> <b>Fuel/Water Separator Ele.</b> (FS1962490)..... <b>PF7748</b> <b>Fuel/Water Separator Spin-on</b> (w/o Heater) (234011700)..... <b>BF1360</b> <b>Radial Seal Air</b> (178013440A).... <b>RS2863</b> <b>Radial Seal XP Air</b> (178013440A)..... <b>RS2863XP</b> <b>Cab Air</b> (872121200A)..... <b>CLN&amp;R</b>
195 w/J05E-TP (5.0L) Eng. (2019) <b>Lube</b> (S156072051)..... <b>B7155</b> <b>Fuel</b> (23304EV360)..... <b>PF46138</b> <b>Cab Air</b> (8856837020)..... <b>PA10157</b> <b>Crankcase Breather</b> (S1222EV011)..... <b>CV15011</b> <b>Diesel Exhaust Fluid</b> (S17K0E0011)..... <b>PE17000</b>	198 w/J08E-VC (7.7L) Eng. (2019) <b>Lube</b> (15613E0110)..... <b>B7155</b> <b>Fuel/Water Separator</b> (23304E0020)..... <b>PF7894</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Diesel Exhaust Fluid</b> (S17K0E0011)..... <b>PE17000</b>
195 w/J05E-TP (5.1L) Eng. (2020) <b>Lube</b> (S156072051)..... <b>B7155</b> <b>Fuel</b> (23304EV360)..... <b>PF46138</b> <b>Diesel Exhaust Fluid</b> (S17K0E0011)..... <b>PE17000</b>	198 w/J08E-VC (7.7L) Eng. (2020) <b>Lube</b> (15613E0110)..... <b>B7155</b> <b>Fuel/Water Separator</b> (23304E0020)..... <b>PF7894</b> <b>Crankcase Breather</b> (S1222EV011)..... <b>CV15011</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Diesel Exhaust Fluid</b> (S17K0E0011)..... <b>PE17000</b>
195DC w/J05E-TP (5.0L) Eng. (2014) <b>Lube</b> (S156072051)..... <b>B7155</b>	238 w/J08E-TA (7.7L) Eng. (2005-10) <b>F-F Lube</b> (15613E0030)..... <b>B7513</b> <b>Dual-Flow Lube</b> (S156072190).... <b>BD7325</b> <b>Fuel/Water Separator Ele.</b> (FS1962490)..... <b>PF7748</b> <b>Fuel/Water Separator Spin-on</b> (w/o Heater) (234011700)..... <b>BF1360</b> <b>Radial Seal Air</b> (178013440A).... <b>RS2863</b> <b>Radial Seal XP Air</b> (178013440A)..... <b>RS2863XP</b> <b>Cab Air</b> (872121200A)..... <b>CLN&amp;R</b>	
195DC w/J05E-TP (5.0L) Eng. (2018) <b>Lube</b> (S156072051)..... <b>B7155</b> <b>Fuel</b> (23304EV360)..... <b>PF46138</b> <b>Cab Air</b> (8856837020)..... <b>PA10157</b> <b>Diesel Exhaust Fluid</b> (S17K0E0011)..... <b>PE17000</b>		

Check Original Equipment Numbers In Parentheses.




**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

**Trucks & Buses Applications** **BALDWIN FILTERS**

<b>HINO Trucks (cont'd)</b>	<b>HINO Trucks (cont'd)</b>	<b>HINO Trucks (cont'd)</b>
238 w/J08E Eng. (2015-17) Lube (15613E0030)..... <b>B7513</b> Fuel/Water Separator (23304E0020)..... <b>PF7894</b> Radial Seal Air (178013440A).... <b>RS2863</b> Radial Seal XP Air (178013440A)..... <b>RS2863XP</b> Trans. Pan-Type (S. Pan w/o Gasket) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gasket) (Allison 29537965).... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gasket) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gasket) (Allison 29537966).... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>	258 w/Cummins B6.7 (6.7L) Eng. (2023) (Cont'd) Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> 258 w/J08E-TV (7.7L) Eng. (2009) Lube (15613E0030)..... <b>B7513</b> Fuel/Water Separator Ele. (FS1962490)..... <b>PF7748</b> Fuel/Water Separator Spin-on (234011700)..... <b>BF1360</b> Radial Seal Air (178013440A).... <b>RS2863</b> Radial Seal XP Air (178013440A)..... <b>RS2863XP</b> Cab Air (872121200A)..... <b>CLN&amp;R</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Diesel Exhaust Fluid (S17K0E0011)..... <b>PE17000</b>	258 w/J08E-VC (7.7L) Eng. (2015) (Cont'd) Pan-Type Trans. (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> 258 w/J08E-VC (7.7L) Eng. (2016) Dual-Flow Lube (156072190A).... <b>BD7325</b> Fuel/Water Separator (FS1962490)..... <b>PF7748</b> Radial Seal Air (178013440)..... <b>RS2863</b> Radial Seal XP Air (178013440).. <b>RS2863XP</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> 258 w/J08E (7.7L) Eng. (2017) Lube (15613E0110)..... <b>B7155</b> Fuel/Water Separator (Fleetguard FS19624)..... <b>PF7748</b> Fuel/Water Separator (23304E0020)..... <b>PF7894</b> Radial Seal Air (S178013440).... <b>RS2863</b> Trans. (Pan Type w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. (Pan-Type w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. (Spin-on) (Allison 29539579)..... <b>BT8460</b>
238ALP w/J08E Eng. (2008-on) Lube (15613E0030)..... <b>B7513</b> Fuel/Water Separator Ele. (FS1962490)..... <b>PF7748</b> Fuel/Water Separator Spin-on (234011700A)..... <b>BF1360</b> Radial Seal Air (178013440A).... <b>RS2863</b> Radial Seal XP Air (178013440A)..... <b>RS2863XP</b> Cab Air (S872121200)..... <b>CLN&amp;R</b>	258 w/J08E-TV (7.7L) Eng. (2010) Lube (15613E0030)..... <b>B7513</b> Fuel/Water Separator Ele. (FS1962490)..... <b>PF7748</b> Fuel/Water Separator Spin-on (234011700)..... <b>BF1360</b> Radial Seal Air (178013440A).... <b>RS2863</b> Radial Seal XP Air (178013440A)..... <b>RS2863XP</b> Cab Air (872121200A)..... <b>CLN&amp;R</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Diesel Exhaust Fluid (S17K0E0011)..... <b>PE17000</b>	258 w/J08E-VC (7.7L) Eng. (2018) Dual-Flow Lube (156072190A).... <b>BD7325</b> Fuel/Water Separator (FS1962490)..... <b>PF7748</b> Fuel/Water Separator (23304E0020)..... <b>PF7894</b> Radial Seal Air (178013440)..... <b>RS2863</b> Radial Seal XP Air (178013440).. <b>RS2863XP</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>
238LP w/J08E Eng. (2005-on) Dual-Flow Lube (15613E0030).... <b>B7513</b> Fuel/Water Separator Ele. (Fleetguard FS19624)..... <b>PF7748</b> Fuel/Water Separator Spin-on (w/o Heater) (234011700)..... <b>BF1360</b> Radial Seal Air (178013440)..... <b>RS2863</b> Radial Seal XP Air (178013440).. <b>RS2863XP</b> Cab Air (872121200A)..... <b>CLN&amp;R</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>	258 w/J08E-TV (7.7L) Eng. (2010) Lube (15613E0030)..... <b>B7513</b> Fuel/Water Separator Ele. (FS1962490)..... <b>PF7748</b> Fuel/Water Separator Spin-on (234011700)..... <b>BF1360</b> Radial Seal Air (178013440A).... <b>RS2863</b> Radial Seal XP Air (178013440A)..... <b>RS2863XP</b> Cab Air (872121200A)..... <b>CLN&amp;R</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Diesel Exhaust Fluid (S17K0E0011)..... <b>PE17000</b>	258 w/J08E-VC (7.7L) Eng. (2018) Dual-Flow Lube (156072190A).... <b>BD7325</b> Fuel/Water Separator (FS1962490)..... <b>PF7748</b> Fuel/Water Separator (23304E0020)..... <b>PF7894</b> Radial Seal Air (178013440)..... <b>RS2863</b> Radial Seal XP Air (178013440).. <b>RS2863XP</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>
258 w/Cummins B6.7 (6.7L) Eng. (2022) Lube (Fleetguard LF3970)..... <b>B7177</b>	258 w/J08E-VC (7.7L) Eng. (2015) Dual-Flow Lube (156072190A).... <b>BD7325</b> Radial Seal Air (178013440).... <b>RS2863</b> Radial Seal XP Air (178013440).. <b>RS2863XP</b> Pan-Type Trans. (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Pan-Type Trans. (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Pan-Type Trans. (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	258 w/J08E-VC (7.7L) Eng. (2019) Lube (15613E0110)..... <b>B7155</b> Fuel/Water Separator (Fleetguard FS19624)..... <b>PF7748</b> Fuel/Water Separator (23304E0020)..... <b>PF7894</b> Radial Seal Air (178013440A).... <b>RS2863</b>
258 w/Cummins B6.7 (6.7L) Eng. (2023) Lube (3937736)..... <b>B7177</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	258 w/J08E-VC (7.7L) Eng. (2015) Dual-Flow Lube (156072190A).... <b>BD7325</b> Radial Seal Air (178013440).... <b>RS2863</b> Radial Seal XP Air (178013440).. <b>RS2863XP</b> Pan-Type Trans. (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Pan-Type Trans. (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Pan-Type Trans. (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	258 w/J08E-VC (7.7L) Eng. (2019) Lube (15613E0110)..... <b>B7155</b> Fuel/Water Separator (Fleetguard FS19624)..... <b>PF7748</b> Fuel/Water Separator (23304E0020)..... <b>PF7894</b> Radial Seal Air (178013440A).... <b>RS2863</b>

Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

HINO Trucks (cont'd)	HINO Trucks (cont'd)	HINO Trucks (cont'd)
258 w/J08E-VC (7.7L) Eng. (2019) (Cont'd)	258ALP w/J08E-TV (7.7L) Eng. (2005-10) (Cont'd)	258ALP w/J08E-VB (7.7L) Eng. (2018) (Cont'd)
<b>Radial Seal XP Air</b> (178013440A)..... <b>RS2863XP</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Radial Seal XP Air</b> (178013440A)..... <b>RS2863XP</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Cab Air</b> (S872121200)..... <b>CLN&amp;R</b>
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Crankcase Breather</b> (S1222EV011)..... <b>CV15011</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Diesel Exhaust Fluid</b> (S17K0E0011)..... <b>PE17000</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	258ALP w/J08E-VC (7.7L) Eng. (2011-14)	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
258 w/J08E-VC (7.7L) Eng. (2020)	<b>Lube</b> (15613E0011)..... <b>B7155</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>Fuel/Water Separator</b> (23304E0020)..... <b>PF7894</b>	<b>Fuel/Water Separator Ele.</b> (FS1962490)..... <b>PF7748</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Fuel/Water Separator</b> (Fleetguard FS19624)..... <b>PF7748</b>	<b>Fuel/Water Separator Spin-on</b> (w/o Heater) (234011700)..... <b>BF1360</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
<b>Radial Seal Air</b> (178013440A)..... <b>RS2863</b>	<b>Radial Seal Air</b> (178013440A)..... <b>RS2863</b>	<b>Diesel Exhaust Fluid</b> (S17K0E0011)..... <b>PE17000</b>
<b>Radial Seal XP Air</b> (178013440A)..... <b>RS2863XP</b>	<b>Radial Seal XP Air</b> (178013440A)..... <b>RS2863XP</b>	258ALP w/J08E-VB (7.7L) Eng. (2019)
<b>Cab Air</b> (S872121200)..... <b>CLN&amp;R</b>	<b>Cab Air</b> (872121200A)..... <b>CLN&amp;R</b>	<b>Lube</b> (15613E0110)..... <b>B7155</b>
<b>Crankcase Breather</b> (S1222EV011)..... <b>CV15011</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Fuel/Water Separator</b> (Fleetguard FS19624)..... <b>PF7748</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Fuel/Water Separator</b> (23304E0020)..... <b>PF7894</b>
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Radial Seal Air</b> (178013440A)..... <b>RS2863</b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Radial Seal XP Air</b> (178013440A)..... <b>RS2863XP</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Cab Air</b> (S872121200)..... <b>CLN&amp;R</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Diesel Exhaust Fluid</b> (S17K0E0011)..... <b>PE17000</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
258 w/J08E-VB (7.7L) Eng. (2021)	258ALP w/J08E-TV (7.7L) Eng. (2015-17)	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Fuel/Water Separator</b> (Fleetguard FS19624)..... <b>PF7748</b>	<b>Lube</b> (15613E0030)..... <b>B7513</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Fuel/Water Separator</b> (23304E0020)..... <b>PF7894</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Radial Seal Air</b> (178013440A)..... <b>RS2863</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Radial Seal XP Air</b> (178013440A)..... <b>RS2863XP</b>	258ALP w/J08E-VC (7.7L) Eng. (2020)
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Trans. Pan-Type</b> (S. Pan (w/o Gasket)) (Allison 29537965)..... <b>20004</b>	<b>Lube</b> (15613E0110)..... <b>B7155</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Trans. Pan-Type</b> (S. Pan (w/Gasket)) (Allison 29537965)..... <b>20016</b>	<b>Fuel/Water Separator</b> (Fleetguard FS19624)..... <b>PF7748</b>
258ALP w/J08E-TV (7.7L) Eng. (2005-10)	<b>Trans. Pan-Type</b> (D. Pan (w/o Gasket)) (Allison 29537966)..... <b>20003</b>	<b>Fuel/Water Separator</b> (23304E0020)..... <b>PF7894</b>
<b>Lube</b> (15613E0030)..... <b>B7513</b>	<b>Trans. Pan-Type</b> (D. Pan (w/Gasket)) (Allison 29537966)..... <b>20017</b>	<b>Radial Seal Air</b> (178013440A)..... <b>RS2863</b>
<b>Fuel/Water Separator Ele.</b> (FS1962490)..... <b>PF7748</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Radial Seal XP Air</b> (178013440A)..... <b>RS2863XP</b>
<b>Fuel/Water Separator Spin-on</b> (w/o Heater) (234011700)..... <b>BF1360</b>	258ALP w/J08E-VB (7.7L) Eng. (2018)	<b>Cab Air</b> (S872121200)..... <b>CLN&amp;R</b>
<b>Radial Seal Air</b> (178013440A)..... <b>RS2863</b>	<b>Lube</b> (15613E0110)..... <b>B7155</b>	<b>Crankcase Breather</b> (S1222EV011)..... <b>CV15011</b>
<b>Radial Seal XP Air</b> (178013440A)..... <b>RS2863XP</b>	<b>Fuel/Water Separator</b> (Fleetguard FS19624)..... <b>PF7748</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Cab Air</b> (872121200A)..... <b>CLN&amp;R</b>	<b>Fuel</b> (23304E0020)..... <b>PF7894</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
	<b>Radial Seal Air</b> (178013440A)..... <b>RS2863</b>	


+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

**Trucks & Buses Applications** **BALDWIN FILTERS**

<b>HINO Trucks (cont'd)</b>	<b>HINO Trucks (cont'd)</b>	<b>HINO Trucks (cont'd)</b>
258ALP w/J08E-VC (7.7L) Eng. (2020) (Cont'd) <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	258LP w/J08E-VC (7.7L) Eng. (2011-14) (Cont'd) <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Diesel Exhaust Fluid</b> (S17K0E0011)..... <b>PE17000</b>	258LP w/J08E-VC (7.7L) Eng. (2020) (Cont'd) <b>Radial Seal Air</b> (178013440A)..... <b>RS2863</b> <b>Radial Seal XP Air</b> (178013440A)..... <b>RS2863XP</b> <b>Cab Air</b> (S872121200A)..... <b>CLN&amp;R</b> <b>Crankcase Breather</b> (S1222EV011)..... <b>CV15011</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
258LP w/J08E-TA (7.7L) Eng. (2005-07) <b>Lube</b> (15613-E0030)..... <b>B7513</b> <b>Fuel/Water Separator Ele.</b> (FS1962490)..... <b>PF7748</b> <b>Fuel/Water Separator Spin-on</b> (w/o Heater) (234011700)..... <b>BF1360</b> <b>Radial Seal Air</b> (178013440A)..... <b>RS2863</b> <b>Radial Seal XP Air</b> (178013440A)..... <b>RS2863XP</b> <b>Cab Air</b> (872121200A)..... <b>CLN&amp;R</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	258LP w/J08E Eng. (2015-17) <b>Lube</b> (15613E0030)..... <b>B7513</b> <b>Fuel/Water Separator</b> (23304E0020)..... <b>PF7894</b> <b>Radial Seal Air</b> (178013440A)..... <b>RS2863</b> <b>Radial Seal XP Air</b> (178013440A)..... <b>RS2863XP</b> <b>Trans. Pan-Type</b> (S. Pan (w/o Gasket)) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan (w/Gasket)) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan (w/o Gasket)) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan (w/Gasket)) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	268 w/Cummins B6.7 (6.7L) Eng. (2022) <b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
258LP w/J08E-TV (7.7L) Eng. (2008-10) <b>Lube</b> (15613-E0030)..... <b>B7513</b> <b>Fuel/Water Separator Ele.</b> (FS1962490)..... <b>PF7748</b> <b>Fuel/Water Separator Spin-on</b> (w/o Heater) (234011700)..... <b>BF1360</b> <b>Radial Seal Air</b> (178013440A)..... <b>RS2863</b> <b>Radial Seal XP Air</b> (178013440A)..... <b>RS2863XP</b> <b>Cab Air</b> (872121200A)..... <b>CLN&amp;R</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Diesel Exhaust Fluid</b> (S17K0E0011)..... <b>PE17000</b>	258LP w/J08E-WU (7.7L) Eng. (2019) <b>Lube</b> (15613E0110)..... <b>B7155</b> <b>Fuel/Water Separator</b> (Fleetguard FS19624)..... <b>PF7748</b> <b>Fuel/Water Separator</b> (23304E0020)..... <b>PF7894</b> <b>Radial Seal Air</b> (178013440A)..... <b>RS2863</b> <b>Radial Seal XP Air</b> (178013440A)..... <b>RS2863XP</b> <b>Cab Air</b> (S872121200)..... <b>CLN&amp;R</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	268 w/Cummins B6.7 (6.7L) Eng. (2023) <b>Lube</b> (3937736)..... <b>B7177</b>
258LP w/J08E-VC (7.7L) Eng. (2011-14) <b>Lube</b> (15613-E0030)..... <b>B7513</b> <b>Fuel/Water Separator Ele.</b> (FS1962490)..... <b>PF7748</b> <b>Fuel/Water Separator Spin-on</b> (w/o Heater) (234011700)..... <b>BF1360</b> <b>Radial Seal Air</b> (178013440A)..... <b>RS2863</b> <b>Radial Seal XP Air</b> (178013440A)..... <b>RS2863XP</b> <b>Cab Air</b> (872121200A)..... <b>CLN&amp;R</b>	258LP w/J08E-VC (7.7L) Eng. (2020) <b>Lube</b> (15613E0110)..... <b>B7155</b> <b>Fuel/Water Separator</b> (23304E0020)..... <b>PF7894</b> <b>Fuel/Water Separator</b> (Fleetguard FS19624)..... <b>PF7748</b>	268 w/J08E-TA (7.7L) Eng. (2005-07) <b>Lube</b> (15613E0030)..... <b>B7513</b> <b>Fuel/Water Separator Ele.</b> (FS1962490)..... <b>PF7748</b> <b>Fuel/Water Separator Spin-on</b> (w/o Heater) (234011700)..... <b>BF1360</b> <b>Radial Seal Air</b> (178013440A)..... <b>RS2863</b> <b>Radial Seal XP Air</b> (178013440A)..... <b>RS2863XP</b> <b>Cab Air</b> (872121200A)..... <b>CLN&amp;R</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
258LP w/J08E-TV (7.7L) Eng. (2008-10) <b>Lube</b> (15613E0030)..... <b>B7513</b> <b>Fuel/Water Separator Ele.</b> (FS1962490)..... <b>PF7748</b> <b>Fuel/Water Separator Spin-on</b> (w/o Heater) (234011700)..... <b>BF1360</b> <b>Radial Seal Air</b> (178013440A)..... <b>RS2863</b>	268 w/J08E-TV (7.7L) Eng. (2008-10) <b>Lube</b> (15613E0030)..... <b>B7513</b> <b>Fuel/Water Separator Ele.</b> (FS1962490)..... <b>PF7748</b> <b>Fuel/Water Separator Spin-on</b> (w/o Heater) (234011700)..... <b>BF1360</b> <b>Radial Seal Air</b> (178013440A)..... <b>RS2863</b>	

Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



HINO Trucks (cont'd)	HINO Trucks (cont'd)	HINO Trucks (cont'd)
268 w/J08E-TV (7.7L) Eng. (2008-10) (Cont'd)	268 w/J08E-WU (7.7L) Eng. (2018)	268A w/J08E-VC (7.7L) Eng. (2020) (Cont'd)
<b>Radial Seal XP Air</b> (178013440A)..... <b>RS2863XP</b>	<b>Lube</b> (15613E0110)..... <b>B7155</b>	<b>Crankcase Breather</b> (S1222EV011)..... <b>CV15011</b>
<b>Cab Air</b> (872121200A)..... <b>CLN&amp;R</b>	<b>Fuel/Water Separator</b> (Fleetguard FS19624)..... <b>PF7748</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Fuel</b> (23304E0020)..... <b>PF7894</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Radial Seal Air</b> (178013440A)..... <b>RS2863</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Radial Seal XP Air</b> (178013440A)..... <b>RS2863XP</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Cab Air</b> (S872121200)..... <b>CLN&amp;R</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Crankcase Breather</b> (S1222EV011)..... <b>CV15011</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>Diesel Exhaust Fluid</b> (2010 Emissions) (S17K0E0011)..... <b>PE17000</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	268A w/J08E-TV (7.7L) Eng. (2005-10)
268 w/J08E-VC (7.7L) Eng. (2011-14)	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Lube</b> (15613E0030)..... <b>B7513</b>
<b>Lube</b> (15613E0030)..... <b>B7513</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Fuel/Water Separator Ele.</b> (FS1962490)..... <b>PF7748</b>
<b>Fuel/Water Separator Ele.</b> (FS1962490)..... <b>PF7748</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Fuel/Water Separator Spin-on</b> (w/o Heater) (234011700)..... <b>BF1360</b>
<b>Fuel/Water Separator Spin-on</b> (w/o Heater) (234011700)..... <b>BF1360</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Radial Seal Air</b> (178013440A)..... <b>RS2863</b>
<b>Radial Seal Air</b> (178013440A)..... <b>RS2863</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	<b>Radial Seal XP Air</b> (178013440A)..... <b>RS2863XP</b>
<b>Radial Seal XP Air</b> (178013440A)..... <b>RS2863XP</b>	<b>Diesel Exhaust Fluid</b> (S17K0E0011)..... <b>PE17000</b>	<b>Cab Air</b> (872121200A)..... <b>CLN&amp;R</b>
<b>Cab Air</b> (872121200A)..... <b>CLN&amp;R</b>	268 w/J08E-WU (7.7L) Eng. (2019)	<b>Air Dryer</b> (Bendix 109493)..... <b>BA5373</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Lube</b> (15613E0110)..... <b>B7155</b>	<b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b>
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Fuel/Water Separator</b> (Fleetguard FS19624)..... <b>PF7748</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Fuel/Water Separator</b> (23304E0020)..... <b>PF7894</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Radial Seal Air</b> (178013440A)..... <b>RS2863</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Radial Seal XP Air</b> (178013440A)..... <b>RS2863XP</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
<b>Diesel Exhaust Fluid</b> (S17K0E0011)..... <b>PE17000</b>	<b>Cab Air</b> (S872121200)..... <b>CLN&amp;R</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
268 w/J08E Eng. (2015-17)	<b>Crankcase Breather</b> (S1222EV011)..... <b>CV15011</b>	<b>Diesel Exhaust Fluid</b> (2010 Emissions) (S17K0E0011)..... <b>PE17000</b>
<b>Lube</b> (15613E0030)..... <b>B7513</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	268A w/J08E-VC (7.7L) Eng. (2011-14)
<b>Fuel/Water Separator</b> (23304E0020)..... <b>PF7894</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Lube</b> (15613E0030)..... <b>B7513</b>
<b>Radial Seal Air</b> (178013440A)..... <b>RS2863</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Fuel/Water Separator Ele.</b> (FS1962490)..... <b>PF7748</b>
<b>Radial Seal XP Air</b> (178013440A)..... <b>RS2863XP</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Fuel/Water Separator Spin-on</b> (w/o Heater) (234011700)..... <b>BF1360</b>
<b>Trans. Pan-Type</b> (S. Pan (w/o Gasket)) (Allison 29537965)..... <b>20004</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Radial Seal Air</b> (178013440A)..... <b>RS2863</b>
<b>Trans. Pan-Type</b> (S. Pan (w/Gasket)) (Allison 29537965)..... <b>20016</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	<b>Radial Seal XP Air</b> (178013440A)..... <b>RS2863XP</b>
<b>Trans. Pan-Type</b> (D. Pan (w/o Gasket)) (Allison 29537966)..... <b>20003</b>	268A w/J08E-VC (7.7L) Eng. (2020)	<b>Cab Air</b> (872121200A)..... <b>CLN&amp;R</b>
<b>Trans. Pan-Type</b> (D. Pan (w/Gasket)) (Allison 29537966)..... <b>20017</b>	<b>Lube</b> (15613E0110)..... <b>B7155</b>	<b>Air Dryer</b> (Bendix 109493)..... <b>BA5373</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Fuel/Water Separator</b> (Fleetguard FS19624)..... <b>PF7748</b>	<b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b>
	<b>Fuel/Water Separator</b> (23304E0020)..... <b>PF7894</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
	<b>Radial Seal Air</b> (178013440A)..... <b>RS2863</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
	<b>Radial Seal XP Air</b> (178013440A)..... <b>RS2863XP</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
	<b>Cab Air</b> (S872121200)..... <b>CLN&amp;R</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
		<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

HINO Trucks (cont'd)	HINO Trucks (cont'd)	HINO Trucks (cont'd)
268A w/J08E-VC (7.7L) Eng. (2011-14) (Cont'd) <b>Diesel Exhaust Fluid</b> (S17K0E0011)..... <b>PE17000</b>	268A w/J08E-VB (7.7L) Eng. (2019) (Cont'd) <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	338 w/J08E-TB (7.7L) Eng. (2005-07) (Cont'd) <b>Fuel/Water Separator Spin-on</b> (w/Drain & Sensor Port) (234011440A)..... <b>BF1223-SP</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (234011440A)..... <b>BF1223-O</b> <b>Radial Seal Air</b> (178013440A).... <b>RS2863</b> <b>Radial Seal XP Air</b> (178013440A)..... <b>RS2863XP</b> <b>Cab Air</b> (872121200A)..... <b>CLN&amp;R</b> <b>Air Dryer</b> (Bendix 109493)..... <b>BA5373</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29526899)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29526898)..... <b>PT9415-MPG KIT</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
268A w/J08E Eng. (2015-17) <b>Lube</b> (15613E0030)..... <b>B7513</b> <b>Fuel/Water Separator</b> (23304E0020)..... <b>PF7894</b> <b>Radial Seal Air</b> (178013440A).... <b>RS2863</b> <b>Radial Seal XP Air</b> (178013440A)..... <b>RS2863XP</b> <b>Trans. Pan-Type</b> (S. Pan (w/o Gasket)) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan (w/Gasket)) (Allison 29537965).... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan (w/o Gasket)) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan (w/Gasket)) (Allison 29537966).... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	308 w/J08E-TA (7.7L) Eng. (2005-08) <b>Dual-Flow Lube</b> (156072190)..... <b>BD7325</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19624)..... <b>PF7748</b> <b>Fuel/Water Separator Spin-on</b> (w/o Heater) (234011700)..... <b>BF1360</b> <b>Radial Seal Air</b> (178013440)..... <b>RS2863</b> <b>Radial Seal XP Air</b> (178013440).. <b>RS2863XP</b> <b>Cab Air</b> (872121200A)..... <b>CLN&amp;R</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	338 w/J08E-TW (7.7L) Eng. (2008-10) <b>Lube</b> (15613E0030)..... <b>B7513</b> <b>F-F Lube</b> (156072051A)..... <b>B7155</b> <b>Fuel/Water Separator Ele.</b> (FS1962490)..... <b>PF7748</b> <b>Fuel/Water Separator Spin-on</b> (w/o Heater) (234011700)..... <b>BF1360</b> <b>Fuel/Water Separator Spin-on</b> (w/o Drain or Sensor Port) (234011440A)..... <b>BF1224</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (234011440A)..... <b>BF1223</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain & Sensor Port) (234011440A)..... <b>BF1223-SP</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (234011440A)..... <b>BF1223-O</b> <b>Radial Seal Air</b> (178013440A).... <b>RS2863</b> <b>Radial Seal XP Air</b> (178013440A)..... <b>RS2863XP</b> <b>Cab Air</b> (872121200A)..... <b>CLN&amp;R</b> <b>Air Dryer</b> (Bendix 109493)..... <b>BA5373</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29526899)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29526898)..... <b>PT9415-MPG KIT</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
268A w/J08E-VB (7.7L) Eng. (2018) <b>Lube</b> (15613E0110)..... <b>B7155</b> <b>Fuel/Water Separator</b> (Fleetguard FS19624)..... <b>PF7748</b> <b>Fuel</b> (23304E0020)..... <b>PF7894</b> <b>Radial Seal Air</b> (178013440A).... <b>RS2863</b> <b>Radial Seal XP Air</b> (178013440A)..... <b>RS2863XP</b> <b>Cab Air</b> (S872121200)..... <b>CLN&amp;R</b> <b>Crankcase Breather</b> (S1222EV011)..... <b>CV15011</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (S17K0E0011)..... <b>PE17000</b>	300 Series 414 w/N04C-TU Diesel Eng. Mexico <b>Fuel</b> (23355-78020)..... <b>PF9897</b> 300 Series 614 w/N04C-TU Diesel Eng. Mexico <b>Fuel</b> (23355-78020)..... <b>PF9897</b> 300 Series 616 w/N04C-TU Diesel Eng. Mexico <b>Fuel</b> (23355-78020)..... <b>PF9897</b> 300 Series 716 w/N04C-TU Diesel Eng. Mexico <b>Fuel</b> (23355-78020)..... <b>PF9897</b> 300 Series 816 w/N04C-TU Diesel Eng. Mexico <b>Fuel</b> (23355-78020)..... <b>PF9897</b> 338 w/Cummins B6.7 (6.7L) Eng. (2022) <b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b> 338 w/Cummins B6.7 (6.7L) Eng. (2023) <b>Lube</b> (3937736)..... <b>B7177</b>	
268A w/J08E-VB (7.7L) Eng. (2019) <b>Lube</b> (15613E0110)..... <b>B7155</b> <b>Fuel/Water Separator</b> (Fleetguard FS19624)..... <b>PF7748</b> <b>Fuel/Water Separator</b> (23304E0020)..... <b>PF7894</b> <b>Radial Seal Air</b> (178013440A).... <b>RS2863</b> <b>Radial Seal XP Air</b> (178013440A)..... <b>RS2863XP</b> <b>Cab Air</b> (S872121200)..... <b>CLN&amp;R</b> <b>Crankcase Breather</b> (S1222EV011)..... <b>CV15011</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	338 w/J08E-TB (7.7L) Eng. (2005-07) <b>Lube</b> (15613E0030)..... <b>B7513</b> <b>F-F Lube</b> (156072051A)..... <b>B7155</b> <b>Fuel/Water Separator Ele.</b> (FS1962490)..... <b>PF7748</b> <b>Fuel/Water Separator Spin-on</b> (w/o Heater) (234011700)..... <b>BF1360</b> <b>Fuel/Water Separator Spin-on</b> (w/o Drain or Sensor Port) (234011440A)..... <b>BF1224</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (234011440A)..... <b>BF1223</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain & Sensor Port) (234011440A)..... <b>BF1223-SP</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (234011440A)..... <b>BF1223-O</b> <b>Radial Seal Air</b> (178013440A).... <b>RS2863</b> <b>Radial Seal XP Air</b> (178013440A)..... <b>RS2863XP</b> <b>Cab Air</b> (872121200A)..... <b>CLN&amp;R</b> <b>Air Dryer</b> (Bendix 109493)..... <b>BA5373</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29526899)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29526898)..... <b>PT9415-MPG KIT</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

HINO Trucks (cont'd)	HINO Trucks (cont'd)	HINO Trucks (cont'd)
338 w/J08E-TW (7.7L) Eng. (2008-10) (Cont'd)	338 w/J08E-VB (7.7L) Eng. (2015-17) (Cont'd)	338 w/J08E-VB (7.7L) Eng. (2019) (Cont'd)
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Trans. Pan-Type</b> (S. Pan (w/Gasket)) (Allison 29537965)..... <b>20016</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Trans. Pan-Type</b> (D. Pan (w/o Gasket)) (Allison 29537966)..... <b>20003</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Trans. Pan-Type</b> (D. Pan (w/Gasket)) (Allison 29537966)..... <b>20017</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>Diesel Exhaust Fluid</b> (2010 Emissions) (S17K0E0011)..... <b>PE17000</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>
338 w/J08E-VB (7.7L) Eng. (2011-14)	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>
<b>Lube</b> (15613E0030)..... <b>B7513</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
<b>F-F Lube</b> (156072051A)..... <b>B7155</b>	338 w/J08E-VB (7.7L) Eng. (2018)	<b>Diesel Exhaust Fluid</b> (UF101)..... <b>PE17000</b>
<b>Fuel/Water Separator Ele.</b> (FS1962490)..... <b>PF7748</b>	<b>Lube</b> (15613E0110)..... <b>B7155</b>	338 w/J08E-VB (7.7L) Eng. (2020)
<b>Fuel/Water Separator Spin-on</b> (w/o Heater) (234011700)..... <b>BF1360</b>	<b>Fuel/Water Separator</b> (Fleetguard FS19624)..... <b>PF7748</b>	<b>Lube</b> (15613E0110)..... <b>B7155</b>
<b>Fuel/Water Separator Spin-on</b> (w/o Drain or Sensor Port) (234011440A)..... <b>BF1224</b>	<b>Fuel</b> (23304E0020)..... <b>PF7894</b>	<b>Fuel/Water Separator</b> (23304E0020)..... <b>PF7894</b>
<b>Fuel/Water Separator Spin-on</b> (w/Drain) (234011440A)..... <b>BF1223</b>	<b>Radial Seal Air</b> (178013440A)..... <b>RS2863</b>	<b>Fuel/Water Separator</b> (Fleetguard FS19624)..... <b>PF7748</b>
<b>Fuel/Water Separator Spin-on</b> (w/Drain & Sensor Port) (234011440A)..... <b>BF1223-SP</b>	<b>Radial Seal XP Air</b> (178013440A)..... <b>RS2863XP</b>	<b>Radial Seal Air</b> (178013440A)..... <b>RS2863</b>
<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (234011440A)..... <b>BF1223-O</b>	<b>Cab Air</b> (S872121200)..... <b>CLN&amp;R</b>	<b>Radial Seal XP Air</b> (178013440A)..... <b>RS2863XP</b>
<b>Radial Seal Air</b> (178013440A)..... <b>RS2863</b>	<b>Crankcase Breather</b> (S1222EV011)..... <b>CV15011</b>	<b>Cab Air</b> (S872121200)..... <b>CLN&amp;R</b>
<b>Radial Seal XP Air</b> (178013440A)..... <b>RS2863XP</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Breather</b> (S1222EV011)..... <b>CV15011</b>
<b>Cab Air</b> (872121200A)..... <b>CLN&amp;R</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29526899)..... <b>PT9416-MPG KIT</b>
<b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29526898)..... <b>PT9415-MPG KIT</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29526899)..... <b>PT9416-MPG KIT</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29526898)..... <b>PT9415-MPG KIT</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Diesel Exhaust Fluid</b> (S17K0E0011)..... <b>PE17000</b>	338 w/J08E-VC (7.7L) Eng. (2020)
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	338 w/J08E-VB (7.7L) Eng. (2019)	<b>Lube</b> (15613E0110)..... <b>B7155</b>
<b>Diesel Exhaust Fluid</b> (S17K0E0011)..... <b>PE17000</b>	<b>Lube</b> (15613E0110)..... <b>B7155</b>	<b>Fuel/Water Separator</b> (23304E0020)..... <b>PF7894</b>
338 w/J08E-VB (7.7L) Eng. (2015-17)	<b>Fuel/Water Separator</b> (Fleetguard FS19624)..... <b>PF7748</b>	<b>Fuel/Water Separator</b> (Fleetguard FS19624)..... <b>PF7748</b>
<b>Lube</b> (15613E0030)..... <b>B7513</b>	<b>Fuel/Water Separator</b> (23304E0020)..... <b>PF7894</b>	<b>Fuel</b> (23304E0020)..... <b>PF7894</b>
<b>Fuel/Water Separator</b> (23304E0020)..... <b>PF7894</b>	<b>Radial Seal Air</b> (178013440A)..... <b>RS2863</b>	<b>Radial Seal Air</b> (178013440A)..... <b>RS2863</b>
<b>Radial Seal Air</b> (178013440A)..... <b>RS2863</b>	<b>Radial Seal XP Air</b> (178013440A)..... <b>RS2863XP</b>	<b>Radial Seal XP Air</b> (178013440A)..... <b>RS2863XP</b>
<b>Radial Seal XP Air</b> (178013440A)..... <b>RS2863XP</b>	<b>Cab Air</b> (S872121200)..... <b>CLN&amp;R</b>	<b>Cab Air</b> (S872121200)..... <b>CLN&amp;R</b>
<b>Cab Air</b> (872121200A)..... <b>CLN&amp;R</b>	<b>Air Dryer</b> (5008414)..... <b>BA5374 +</b>	<b>Crankcase Breather</b> (S1222EV011)..... <b>CV15011</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gasket)) (Allison 29537965)..... <b>20004</b>	<b>Crankcase Breather</b> (S1222EV011)..... <b>CV15011</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29526899)..... <b>PT9416-MPG KIT</b>
	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29526898)..... <b>PT9415-MPG KIT</b>
	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>


+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

HINO Trucks (cont'd)	HINO Trucks (cont'd)	HINO Trucks (cont'd)
338 w/J08E-VC (7.7L) Eng. (2020) (Cont'd)	338CT w/J08E-VB (7.7L) Eng. (2011-14) (Cont'd)	358 w/J08E-VC (7.7L) Eng. (2020)
Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016	Fuel/Water Separator Spin-on (w/Drain) (234011440A)..... BF1223	Lube (15613E0110)..... B7155
Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003	Fuel/Water Separator Spin-on (w/Drain & Sensor Port) (234011440A)..... BF1223-SP	Fuel (23304E0020)..... PF7894
Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017	Fuel/Water Separator Spin-on (Open End for Bowl) (234011440A)..... BF1223-O	Crankcase Breather (S1222EV011)..... CV15011
Trans. Spin-on (Allison 29539579)..... BT8460	Radial Seal Air (178013440A)..... RS2863	414 (Serie 300) w/N04C-TU Diesel Eng. Mexico Fuel (23355-78020)..... PF9897
338CT w/J08E-TW (7.7L) Eng. (2005-10)	Radial Seal XP Air (178013440A)..... RS2863XP	500 Series w/J08E Eng.
Lube (15613E0030)..... B7513	Cab Air (872121200A)..... CLN&R	Dual-Flow Lube (156072190)..... BD7325
F-F Lube (156072051A)..... B7155	Air Dryer (Bendix 5008414)..... BA5374 +	500 Series 1018 w/J05D Eng. Mexico
Fuel/Water Separator Ele. (FS1962490)..... PF7748	Trans. Ele. (2 In. Kit) (Allison 29526899)..... PT9416-MPG KIT	Lube (S1560-72051)..... B7155
Fuel/Water Separator Spin-on (w/o Heater) (234011700)..... BF1360	Trans. Ele. (4 In. Kit) (Allison 29526898)..... PT9415-MPG KIT	Fuel (S2340-11740)..... PF9897
Fuel/Water Separator Spin-on (w/o Drain or Sensor Port) (234011440A)..... BF1224	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004	Radial Seal I. Air (S1780-13371)..... RS30239
Fuel/Water Separator Spin-on (w/Drain) (234011440A)..... BF1223	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016	500 Series 1524 w/J08E Eng. Mexico
Fuel/Water Separator Spin-on (w/Drain & Sensor Port) (234011440A)..... BF1223-SP	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003	Lube (S1560-72051)..... B7155
Fuel/Water Separator Spin-on (Open End for Bowl) (234011440A)..... BF1223-O	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017	Fuel (S2340-11740)..... PF9897
Radial Seal Air (178013440A)..... RS2863	Trans. Spin-on (Allison 29539579)..... BT8460	Radial Seal I. Air (S1780-13371)..... RS30239
Radial Seal XP Air (178013440A)..... RS2863XP	Diesel Exhaust Fluid (S17K0E0011)..... PE17000	500 Series 1724 w/J08E Eng. Mexico
Cab Air (872121200A)..... CLN&R	358 w/J08E-TW (7.7L) Eng. (2008-10)	Lube (S1560-72051)..... B7155
Air Dryer (Bendix 109493)..... BA5373	Dual-Flow Lube (156072190)..... BD7325	Fuel (S2340-11740)..... PF9897
Trans. Ele. (2 In. Kit) (Allison 29526899)..... PT9416-MPG KIT	F-F Lube (15613E0030)..... B7513	Radial Seal I. Air (S1780-13371)..... RS30239
Trans. Ele. (4 In. Kit) (Allison 29526898)..... PT9415-MPG KIT	Fuel/Water Separator (FS1962490)..... PF7748	500 Series 1727 w/J08E Eng. Mexico
Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004	Cab Air (S872121200)..... CLN&R	Lube (S1560-72051)..... B7155
Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016	358 w/J08E-VB (7.7L) Eng. (2011-17)	Fuel (S2340-11740)..... PF9897
Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003	Dual-Flow Lube (156072190)..... BD7325	Radial Seal I. Air (S1780-13371)..... RS30239
Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017	F-F Lube (15613E0030)..... B7513	500 Series 1720L w/J08C-TP Eng.
Trans. Spin-on (Allison 29539579)..... BT8460	Cab Air (872121200A)..... CLN&R	Lube (15607-2170)..... B7155
Diesel Exhaust Fluid (2010 Emissions) (S17K0E0011)..... PE17000	Trans. Ele. (2 In. Kit) (Allison 29526899)..... PT9416-MPG KIT	Fuel/Water Separator (23401-1441)..... BF1348 +
338CT w/J08E-VB (7.7L) Eng. (2011-14)	Trans. Ele. (4 In. Kit) (Allison 29526898)..... PT9415-MPG KIT	Air (17801-2810)..... PA3600
Lube (15613E0030)..... B7513	358 w/J08E-VC (7.7L) Eng. (2018)	AM100 w/EC100 Eng.
F-F Lube (156072051A)..... B7155	Dual-Flow Lube (156072190A)..... BD7325	Lube Ele. (15607-1090)..... P723
Fuel/Water Separator Ele. (FS1962490)..... PF7748	358 w/J08E-VC (7.7L) Eng. (2019)	Fuel Ele. (23401-1060)..... PF7550
Fuel/Water Separator Spin-on (w/o Heater) (234011700)..... BF1360	Lube (15613E0110)..... B7155	BG100 w/DK20 Eng. (1972-80)
Fuel/Water Separator Spin-on (w/o Drain or Sensor Port) (234011440A)..... BF1224	Fuel/Water Separator (23304E0020)..... PF7894	Fuel (23401-1040)..... PF7551 <sup>90</sup>
	358 w/J08E-VB (7.7L) Eng. (2020)	BX320 w/EH100 Eng.
	Lube (15613E0110)..... B7155	Lube Ele. (15607-1090)..... P723
	Fuel/Water Separator (23304E0020)..... PF7894	Fuel Ele. (23401-1060)..... PF7550
	Breather (S1222EV011)..... CV15011	Dutro w/S05C-TB Eng. (Australia Truck)
		Dual-Flow Lube (156071733)..... BD7105
		FA (1987-91)
		Lube (156071750A)..... B404
		Fuel (Fuel Tank) (235011010A)..... BF984
		O. Air (178012620A)..... PA3448 <sup>90</sup>
		I. Air (178012610A)..... PA3657
		FA (1992-2007)
		Lube (156071750A)..... B404
		Opt. Fuel/Water Separator Ele. (FS1962490)..... PF7748
		Opt. Fuel/Water Separator Spin-on (w/o Drain or Sensor Port) (234011440A)..... BF1224
		Opt. Fuel/Water Separator Spin-on (w/Drain & Sensor Port) (234011440A)..... BF1223-SP

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

HINO Trucks (cont'd)	HINO Trucks (cont'd)	HINO Trucks (cont'd)
FA (1992-2007) (Cont'd)	FA15 w/W04C (3.8L) Eng. (1992-97) (Cont'd)	FA1517 w/J05C (5.3L) Eng. (2004) (Cont'd)
<b>Opt. Fuel/Water Separator Spin-on</b> (Open End for Bowl) (234011440A)..... <b>BF1223-O</b>	<b>Trans.</b> (349261041)..... <b>BT230 +</b>	<b>Fuel/Water Separator</b> (w/Drain) (234011440A)..... <b>BF1223</b>
<b>Opt. Fuel/Water Separator Spin-on</b> (w/Drain) (234011440A)..... <b>BF1223</b>	FA1415 w/W04C-TH (3.8L) Eng. (1993-94)	<b>Fuel/Water Separator</b> (w/Drain & Sensor Port) (234011440A)..... <b>BF1223-SP</b>
<b>Fuel</b> (Fuel Tank) (235011010A).... <b>BF984</b>	<b>Lube</b> (156071750)..... <b>B404</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (234011440A)..... <b>BF1223-O</b>
<b>Fuel</b> (Engine) (234011510A)..... <b>BF7967</b>	<b>Fuel</b> (By Fuel Tank) (235011010)..... <b>BF984</b>	<b>Fuel</b> (By Engine) (234011510A).... <b>BF7967</b>
<b>Air</b> (178012800A)..... <b>PA2784</b>	<b>Fuel</b> (By Engine) (234011411)..... <b>BF7648</b>	<b>Radial Seal Air</b> (178013000)..... <b>RS3733</b>
<b>Opt. Cab Air</b> (S872121200)..... <b>CLN&amp;R</b>	<b>Air</b> (178012800)..... <b>PA2784</b>	<b>Trans.</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b>
<b>Trans.</b> (1998-2001) (349261041A)..... <b>BT230</b>	<b>Trans.</b> (349261041)..... <b>BT230 +</b>	<b>Trans.</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>
FA4J w/J05C Eng. (1998-2003)	FA1415 w/W04C-TM (3.8L) Eng. (1995-97)	FA1817 w/J08C Eng. (2004)
<b>Lube</b> (156072170)..... <b>B7155</b>	<b>Lube</b> (156071750)..... <b>B404</b>	<b>Lube</b> (156072170)..... <b>B7155</b>
<b>Fuel/Water Separator</b> (w/o Drain or Sensor Port) (234011440)..... <b>BF1224</b>	<b>Fuel</b> (By Fuel Tank) (235011010)..... <b>BF984</b>	<b>Fuel/Water Separator</b> (w/o Drain or Sensor Port) (234011440A)..... <b>BF1224</b>
<b>Fuel/Water Separator</b> (w/Drain) (234011440)..... <b>BF1223</b>	<b>Fuel</b> (By Engine) (234011411)..... <b>BF7648</b>	<b>Fuel/Water Separator</b> (w/Drain) (234011440A)..... <b>BF1223</b>
<b>Fuel/Water Separator</b> (w/Drain & Sensor Port) (234011440)..... <b>BF1223-SP</b>	<b>Air</b> (178012800)..... <b>PA2784</b>	<b>Fuel/Water Separator</b> (w/Drain & Sensor Port) (234011440A)..... <b>BF1223-SP</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (234011440)..... <b>BF1223-O</b>	<b>Trans.</b> (349261041)..... <b>BT230 +</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (234011440A)..... <b>BF1223-O</b>
<b>Fuel</b> (234011510)..... <b>BF7967</b>	FA1517 w/J05C-TB (5.3L) Eng. (1998)	<b>Fuel</b> (234011510A)..... <b>BF7967</b>
<b>Radial Seal Air</b> (178013000)..... <b>RS3733</b>	<b>Lube</b> (156072170)..... <b>B7155</b>	<b>12 3/4 In. Radial Seal Air</b> (178013430A)..... <b>RS2863</b>
<b>Trans.</b> (1998-2001) (349261041)..... <b>BT230 +</b>	<b>Fuel/Water Separator</b> (w/o Drain or Sensor Port) (234011440)..... <b>BF1224</b>	<b>12 3/4 In. Radial Seal XP Air</b> (178013430A)..... <b>RS2863XP</b>
FA4J w/J05C Eng. (2004)	<b>Fuel/Water Separator</b> (w/Drain) (234011440)..... <b>BF1223</b>	<b>13 3/4 In. Radial Seal Air</b> (178013000)..... <b>RS3733</b>
<b>Lube</b> (156072170)..... <b>B7155</b>	<b>Fuel/Water Separator</b> (w/Drain & Sensor Port) (234011440)..... <b>BF1223-SP</b>	<b>Trans.</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b>
<b>Fuel/Water Separator</b> (w/o Drain or Sensor Port) (234011440A)..... <b>BF1224</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (234011440)..... <b>BF1223-O</b>	<b>Trans.</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>
<b>Fuel/Water Separator</b> (w/Drain) (234011440A)..... <b>BF1223</b>	<b>Fuel</b> (234011510)..... <b>BF7967</b>	FB (1987-91)
<b>Fuel/Water Separator</b> (w/Drain & Sensor Port) (234011440A)..... <b>BF1223-SP</b>	<b>Radial Seal Air</b> (178013000)..... <b>RS3733</b>	<b>Lube</b> (156071750A)..... <b>B404</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (234011440A)..... <b>BF1223-O</b>	<b>Trans.</b> (349261041)..... <b>BT230 +</b>	<b>Fuel</b> (Fuel Tank) (235011010A).... <b>BF984</b>
<b>Fuel</b> (234011510A)..... <b>BF7967</b>	FA1517 w/J05C-TD (5.3L) Eng. (1999-2001)	<b>O. Air</b> (178012620A)..... <b>PA3448<sup>90</sup></b>
<b>12 3/4 In. Radial Seal Air</b> (178013430A)..... <b>RS2863</b>	<b>Lube</b> (156072170)..... <b>B7155</b>	<b>I. Air</b> (178012610A)..... <b>PA3657</b>
<b>12 3/4 In. Radial Seal XP O. Air</b> (178013430A)..... <b>RS2863XP</b>	<b>Fuel/Water Separator</b> (w/o Drain or Sensor Port) (234011440)..... <b>BF1224</b>	FB (1992-2007)
<b>13 3/4 In. Radial Seal Air</b> (178013000)..... <b>RS3733</b>	<b>Fuel/Water Separator</b> (w/Drain) (234011440)..... <b>BF1223</b>	<b>Lube</b> (156071750A)..... <b>B404</b>
<b>Trans.</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b>	<b>Fuel/Water Separator</b> (w/Drain & Sensor Port) (234011440)..... <b>BF1223-SP</b>	<b>Opt. Fuel/Water Separator</b> (FS1962490)..... <b>PF7748</b>
<b>Trans.</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (234011440)..... <b>BF1223-O</b>	<b>Fuel/Water Separator Spin-on</b> (w/o Drain or Sensor Port) (234011440)..... <b>BF1224</b>
FA14 w/W04C (3.8L) Eng. (1989-91)	<b>Fuel</b> (234011510)..... <b>BF7967</b>	<b>Fuel/Water Separator Spin-on</b> (w/Drain) (234011440)..... <b>BF1223</b>
<b>Lube</b> (15607-1750)..... <b>B404</b>	<b>Radial Seal Air</b> (178013000)..... <b>RS3733</b>	<b>Fuel/Water Separator Spin-on</b> (w/Drain & Sensor Port) (234011440)..... <b>BF1223-SP</b>
<b>Fuel</b> (By Fuel Tank) (23501-1010)..... <b>BF984</b>	<b>Trans.</b> (349261041)..... <b>BT230 +</b>	<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (234011440)..... <b>BF1223-O</b>
<b>Fuel</b> (By Engine) (23401-1411).... <b>BF7648</b>	FA1517 w/J05C (5.3L) Eng. (2002-2003)	<b>Fuel</b> (Fuel Tank) (235011010A).... <b>BF984</b>
<b>O. Air</b> (17801-2620)..... <b>PA3448<sup>90</sup></b>	<b>Lube</b> (156072170)..... <b>B7155</b>	<b>Fuel</b> (Engine) (234011510A)..... <b>BF7967</b>
<b>I. Air</b> (17801-2610)..... <b>PA3657</b>	<b>Fuel/Water Separator</b> (w/o Drain or Sensor Port) (234011440)..... <b>BF1224</b>	<b>Air</b> (178012800A)..... <b>PA2784</b>
<b>Trans.</b> (34926-1041)..... <b>BT230 +</b>	<b>Fuel/Water Separator</b> (w/Drain) (234011440)..... <b>BF1223</b>	<b>Opt. Cab Air</b> (S872121200)..... <b>CLN&amp;R</b>
FA15 w/W04C (3.8L) Eng. (1992-97)	<b>Fuel/Water Separator</b> (w/Drain & Sensor Port) (234011440)..... <b>BF1223-SP</b>	
<b>Lube</b> (156071750)..... <b>B404</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (234011440)..... <b>BF1223-O</b>	
<b>Fuel</b> (By Fuel Tank) (235011010)..... <b>BF984</b>	<b>Fuel</b> (234011510)..... <b>BF7967</b>	
<b>Fuel</b> (By Engine) (234011411)..... <b>BF7648</b>	<b>Radial Seal Air</b> (178013000)..... <b>RS3733</b>	
<b>Air</b> (178012800)..... <b>PA2784</b>	FA1517 w/J05C (5.3L) Eng. (2004)	
	<b>Lube</b> (156072051)..... <b>B7155</b>	
	<b>Fuel/Water Separator</b> (By Fuel Tank) (234011441)..... <b>BF1348 +</b>	
	<b>Fuel/Water Separator</b> (w/o Drain or Sensor Port) (234011440A)..... <b>BF1224</b>	


+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.

Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>HINO Trucks (cont'd)</b>	<b>HINO Trucks (cont'd)</b>	<b>HINO Trucks (cont'd)</b>
FB (1992-2007) (Cont'd) Trans. (1998-2001) (349261041A)..... <b>BT230</b>	FB1817 w/J05C-TB (5.3L) Eng. (1998) <b>Lube</b> (156072170)..... <b>B7155</b> <b>Fuel/Water Separator</b> (w/o Drain or Sensor Port) (234011440)..... <b>BF1224</b> <b>Fuel/Water Separator</b> (w/Drain) (234011440)..... <b>BF1223</b> <b>Fuel/Water Separator</b> (w/Drain & Sensor Port) (234011440)..... <b>BF1223-SP</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (234011440)..... <b>BF1223-O</b> <b>Fuel</b> (234011510)..... <b>BF7967</b> <b>Radial Seal Air</b> (178013000)..... <b>RS3733</b> Trans. (349261041)..... <b>BT230 +</b>	FC3J (500 Series) w/J07C Eng. <b>Lube</b> (15607-1780)..... <b>B404</b> <b>P. Fuel/Water Separator</b> (w/o Drain or Sensor Port) (234011440)..... <b>BF1224</b> <b>P. Fuel/Water Separator</b> (w/Drain) (234011440)..... <b>BF1223</b> <b>P. Fuel/Water Separator</b> (w/Drain & Sensor Port) (234011440)..... <b>BF1223-SP</b> <b>P. Fuel/Water Separator</b> (Open End for Bowl) (234011440)..... <b>BF1223-O</b> <b>S. Fuel</b> (Engine) (23401-1510)..... <b>BF7967</b> <b>Radial Seal O. Air</b> (S17801-3360)..... <b>RS30238</b>
FB2W w/W04D Eng. <b>Lube</b> (15607-1480)..... <b>B7045</b> <b>P. Fuel Ele.</b> (Fuel Tank) (23401-1090)..... <b>PF7572</b> <b>S. Fuel</b> (Engine) (S23401-1133)..... <b>BF940</b>	FB1817 w/J05C-TD (5.3L) Eng. (1999-2001) <b>Lube</b> (156072170)..... <b>B7155</b> <b>Fuel/Water Separator</b> (w/o Drain or Sensor Port) (234011440)..... <b>BF1224</b> <b>Fuel/Water Separator</b> (w/Drain) (234011440)..... <b>BF1223</b> <b>Fuel/Water Separator</b> (w/Drain & Sensor Port) (234011440)..... <b>BF1223-SP</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (234011440)..... <b>BF1223-O</b> <b>Fuel</b> (234011510)..... <b>BF7967</b> <b>Radial Seal Air</b> (178013000)..... <b>RS3733</b> Trans. (349261041)..... <b>BT230 +</b>	FC4J (500 Series) w/J05C-TI Eng. <b>Dual-Flow Lube</b> (15607-1733)..... <b>BD7105</b> <b>Fuel</b> (S23401-1510)..... <b>BF7967</b>
FB4J w/J05C Eng. (New Zealand) <b>Lube</b> (15607-1780)..... <b>B404</b> <b>P. Fuel/Water Separator</b> (w/o Drain or Sensor Port) (234011440)..... <b>BF1224</b> <b>P. Fuel/Water Separator</b> (w/Drain) (234011440)..... <b>BF1223</b> <b>P. Fuel/Water Separator</b> (w/Drain & Sensor Port) (234011440)..... <b>BF1223-SP</b> <b>P. Fuel/Water Separator</b> (Open End for Bowl) (234011440)..... <b>BF1223-O</b> <b>S. Fuel</b> (S23401-1133)..... <b>BF940</b>	FB1817 w/J05C-TD (5.3L) Eng. (2002-2004) <b>Lube</b> (156072170)..... <b>B7155</b> <b>Fuel/Water Separator</b> (w/o Drain or Sensor Port) (234011440)..... <b>BF1224</b> <b>Fuel/Water Separator</b> (w/Drain) (234011440)..... <b>BF1223</b> <b>Fuel/Water Separator</b> (w/Drain & Sensor Port) (234011440)..... <b>BF1223-SP</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (234011440)..... <b>BF1223-O</b> <b>Fuel</b> (234011510)..... <b>BF7967</b> <b>Radial Seal Air</b> (178013000)..... <b>RS3733</b> Trans. (349261041)..... <b>BT230 +</b>	FD1J w/J08C Eng. <b>Dual-Flow Lube</b> (15607-1733)..... <b>BD7105</b> <b>P. Fuel/Water Separator</b> (w/o Drain or Sensor Port) (234011440)..... <b>BF1224</b> <b>P. Fuel/Water Separator</b> (w/Drain) (234011440)..... <b>BF1223</b> <b>P. Fuel/Water Separator</b> (w/Drain & Sensor Port) (234011440)..... <b>BF1223-SP</b> <b>P. Fuel/Water Separator</b> (Open End for Bowl) (234011440)..... <b>BF1223-O</b> <b>S. Fuel</b> (Engine) (23401-1332)..... <b>BF7967</b> <b>O. Air</b> (17801-2600)..... <b>PA2779</b> <b>I. Air</b> (17801-2840)..... <b>PA2545</b>
FB4J w/J05C Eng. (1998-2003) (North America) <b>Lube</b> (156072170)..... <b>B7155</b> <b>Fuel/Water Separator</b> (w/o Drain or Sensor Port) (234011440)..... <b>BF1224</b> <b>Fuel/Water Separator</b> (w/Drain) (234011440)..... <b>BF1223</b> <b>Fuel/Water Separator</b> (w/Drain & Sensor Port) (234011440)..... <b>BF1223-SP</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (234011440)..... <b>BF1223-O</b> <b>Fuel</b> (234011510)..... <b>BF7967</b> <b>Radial Seal Air</b> (178013000)..... <b>RS3733</b> Trans. (1998-2001) (349261041)..... <b>BT230 +</b>	FD16 w/W06E Eng. (1986-87) <b>Lube</b> (15607-1740)..... <b>B7005</b> <b>Fuel</b> (By Fuel Tank) (23501-1010)..... <b>BF984</b> <b>Fuel</b> (By Engine) (23401-1411)..... <b>BF7648</b> <b>O. Air</b> (17801-2480)..... <b>PA2688</b> <b>I. Air</b> (17801-2460)..... <b>PA2621</b> Trans. (34926-1041)..... <b>BT230 +</b>	FD1J (500 Series) w/J08C Eng. <b>Dual-Flow Lube</b> (15607-1733)..... <b>BD7105</b> <b>P. Fuel/Water Separator</b> (w/o Drain or Sensor Port) (234011440)..... <b>BF1224</b> <b>P. Fuel/Water Separator</b> (w/Drain) (234011440)..... <b>BF1223</b> <b>P. Fuel/Water Separator</b> (w/Drain & Sensor Port) (234011440)..... <b>BF1223-SP</b> <b>P. Fuel/Water Separator</b> (Open End for Bowl) (234011440)..... <b>BF1223-O</b> <b>S. Fuel</b> (Engine) (S23401-1510)..... <b>BF7967</b>
FB14 w/W04C (3.8L) Eng. (1987-91) <b>Lube</b> (15607-1750)..... <b>B404</b> <b>Fuel</b> (By Fuel Tank) (23501-1010)..... <b>BF984</b> <b>Fuel</b> (By Engine) (23401-1411)..... <b>BF7648</b> <b>O. Air</b> (17801-2620)..... <b>PA3448<sup>90</sup></b> <b>I. Air</b> (17801-2610)..... <b>PA3657</b> Trans. (34926-1041)..... <b>BT230 +</b>	FC3J w/J07C Eng. <b>Lube</b> (15607-1780)..... <b>B404</b> <b>P. Fuel/Water Separator</b> (w/o Drain or Sensor Port) (234011440)..... <b>BF1224</b> <b>P. Fuel/Water Separator</b> (w/Drain) (234011440)..... <b>BF1223</b> <b>P. Fuel/Water Separator</b> (w/Drain & Sensor Port) (234011440)..... <b>BF1223-SP</b> <b>P. Fuel/Water Separator</b> (Open End for Bowl) (234011440)..... <b>BF1223-O</b> <b>S. Fuel</b> (Engine) (23401-1332)..... <b>BF7967</b> <b>Radial Seal O. Air</b> (17801-3000)..... <b>RS3733</b>	FD2J w/J08C Eng. (1998-2003) <b>Lube</b> (156072170)..... <b>B7155</b> <b>Fuel/Water Separator</b> (w/o Drain or Sensor Port) (234011440)..... <b>BF1224</b> <b>Fuel/Water Separator</b> (w/Drain) (234011440)..... <b>BF1223</b> <b>Fuel/Water Separator</b> (w/Drain & Sensor Port) (234011440)..... <b>BF1223-SP</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (234011440)..... <b>BF1223-O</b> <b>Fuel</b> (1998-2002) (234011402)..... <b>BF957 +</b> <b>Fuel</b> (2003) (234011510A)..... <b>BF7967</b> <b>Air</b> (178012810)..... <b>PA3600</b> Trans. (1998-2001) (349261041)..... <b>BT230 +</b>
FB15 w/W04C (3.8L) Eng. (1992-97) <b>Lube</b> (156071750)..... <b>B404</b> <b>Fuel</b> (By Fuel Tank) (235011010)..... <b>BF984</b> <b>Fuel</b> (By Engine) (234011411)..... <b>BF7648</b> <b>Air</b> (178012800)..... <b>PA2784</b> Trans. (349261041)..... <b>BT230 +</b>	FB1715 w/W04C-TH (3.8L) Eng. (1993-94) <b>Lube</b> (156071750)..... <b>B404</b> <b>Fuel</b> (By Fuel Tank) (235011010)..... <b>BF984</b> <b>Fuel</b> (By Engine) (234011411)..... <b>BF7648</b> <b>Air</b> (178012800)..... <b>PA2784</b> Trans. (349261041)..... <b>BT230 +</b>	
FB1715 w/W04C-TM (3.8L) Eng. (1995-97) <b>Lube</b> (156071750)..... <b>B404</b> <b>Fuel</b> (By Fuel Tank) (235011010)..... <b>BF984</b> <b>Fuel</b> (By Engine) (234011411)..... <b>BF7648</b> <b>Air</b> (178012800)..... <b>PA2784</b> Trans. (349261041)..... <b>BT230 +</b>		

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

HINO Trucks (cont'd)	HINO Trucks (cont'd)	HINO Trucks (cont'd)
FD5H w/H06C Eng. (1993-97)	FD2220 w/J08C (8.0L) Eng. (2003)	FD2320DH w/J08C (8.0L) Eng. (2004) (Cont'd)
F-F Lube (156071740)..... B7005	Lube (156072170)..... B7155	Fuel/Water Separator (w/Drain & Sensor Port) (234011440)..... BF1223-SP
B-P Lube (156071860)..... B7124	Fuel/Water Separator (w/o Drain or Sensor Port) (234011440)..... BF1224	Fuel/Water Separator (Open End for Bowl) (234011440)..... BF1223-O
Fuel (By Fuel Tank) (235011010)..... BF984	Fuel/Water Separator (w/Drain) (234011440)..... BF1223	Fuel (234011510A)..... BF7967
Fuel (By Engine) (234011402)..... BF957 +	Fuel/Water Separator (w/Drain & Sensor Port) (234011440)..... BF1223-SP	Std. Air (17801-2810)..... PA3600
Air (178012810)..... PA3600	Fuel/Water Separator (Open End for Bowl) (234011440)..... BF1223-O	Radial Seal Air (17801-3000)..... RS3733
Trans. (349261041)..... BT230 +	Fuel (234011510A)..... BF7967	Trans. Spin-on (Allison 29539579)..... BT8460
FD17 w/H07C (6.7L) Eng. (1988-92)	Air (178012810)..... PA3600	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004
Lube (15607-1740)..... B7005	FD2220 w/J08C-TP (8.0L) Eng. (1999-2001)	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016
Fuel (By Fuel Tank) (23501-1010)..... BF984	Lube (156072170)..... B7155	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003
Fuel (By Engine) (23401-1402)..... BF957 +	Fuel/Water Separator (w/o Drain or Sensor Port) (234011440)..... BF1224	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017
O. Air (17801-2480)..... PA2688	Fuel/Water Separator (w/Drain) (234011440)..... BF1223	Trans. Ele. (AT Series; 3.8 In. Pan) (Allison 29540976)..... 19992 +
I. Air (17801-2460)..... PA2621	Fuel/Water Separator (w/Drain & Sensor Port) (234011440)..... BF1223-SP	Trans. Ele. (AT Series; 5.3 In. Pan) (Allison 29538489)..... 19739 +
Coolant (16304-1011)..... BW5139	Fuel/Water Separator (Open End for Bowl) (234011440)..... BF1223-O	
Trans. (34926-1041)..... BT230 +	Fuel (234011402A)..... BF948	FD2320LP w/J08C (8.0L) Eng. (2004)
FD20 w/H06C (6.5L) Eng. (1992)	Fuel (234011402)..... BF957 +	Lube (156072170)..... B7155
F-F Lube (15607-1740)..... B7005	Air (178012810)..... PA3600	Fuel/Water Separator (w/o Drain or Sensor Port) (234011440)..... BF1224
B-P Lube (15607-1860)..... B7124	Trans. (349261041)..... BT230 +	Fuel/Water Separator (w/Drain) (234011440)..... BF1223
Fuel (By Fuel Tank) (23501-1010)..... BF984	FD2220 w/J08C-TD (8.0L) Eng. (1998)	Fuel/Water Separator (w/Drain & Sensor Port) (234011440)..... BF1223-SP
Fuel (By Engine) (23401-1400)..... BF957 +	Lube (156072170)..... B7155	Fuel/Water Separator (Open End for Bowl) (234011440)..... BF1223-O
Air (17801-2810)..... PA3600	Fuel/Water Separator (w/o Drain or Sensor Port) (234011440)..... BF1224	Fuel (234011510A)..... BF7967
Trans. (34926-1041)..... BT230 +	Fuel/Water Separator (w/Drain) (234011440)..... BF1223	Std. Air (17801-2810)..... PA3600
FD2218 w/H06C-TP (6.5L) Eng. (1993-94)	Fuel/Water Separator (w/Drain & Sensor Port) (234011440)..... BF1223-SP	Radial Seal Air (17801-3000)..... RS3733
F-F Lube (15607-1740)..... B7005	Fuel/Water Separator (Open End for Bowl) (234011440)..... BF1223-O	Trans. Spin-on (Allison 29539579)..... BT8460
B-P Lube (15607-1860)..... B7124	Fuel (234011402A)..... BF948	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004
Fuel (By Fuel Tank) (23501-1010)..... BF984	Fuel (234011402)..... BF957 +	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016
Fuel (By Engine) (23401-1400)..... BF957 +	Air (178012810)..... PA3600	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003
Air (17801-2810)..... PA3600	Trans. (349261041)..... BT230 +	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017
Trans. (349261041)..... BT230 +	FD2220 w/J08C-TP (8.0L) Eng. (2002)	Trans. Ele. (AT Series; 3.8 In. Pan) (Allison 29540976)..... 19992 +
FD2218 w/H06C-TT (6.5L) Eng. (1995-97)	Lube (156072170)..... B7155	Trans. Ele. (AT Series; 5.3 In. Pan) (Allison 29538489)..... 19739 +
F-F Lube (15607-1740)..... B7005	Fuel/Water Separator (w/o Drain or Sensor Port) (234011440)..... BF1224	FE1J w/J08C Eng.
B-P Lube (15607-1860)..... B7124	Fuel/Water Separator (w/Drain) (234011440)..... BF1223	Dual-Flow Lube (15607-1733)..... BD7105
Fuel (By Fuel Tank) (23501-1010)..... BF984	Fuel/Water Separator (w/Drain & Sensor Port) (234011440)..... BF1223-SP	P. Fuel/Water Separator (w/o Drain or Sensor Port) (234011440)..... BF1224
Fuel (By Engine) (23401-1400)..... BF957 +	Fuel/Water Separator (Open End for Bowl) (234011440)..... BF1223-O	P. Fuel/Water Separator (w/Drain) (234011440)..... BF1223
Air (17801-2810)..... PA3600	Fuel (234011402A)..... BF948	P. Fuel/Water Separator (w/Drain & Sensor Port) (234011440)..... BF1223-SP
Trans. (349261041)..... BT230 +	Fuel (234011402)..... BF957 +	P. Fuel/Water Separator (Open End for Bowl) (234011440)..... BF1223-O
FD2218LP w/H06C-TP (6.5L) Eng. (1995-97)	Air (178012810)..... PA3600	
F-F Lube (15607-1740)..... B7005	FD2220LP w/J08C (8.0L) Eng. (2004)	
B-P Lube (15607-1860)..... B7124	Lube (156072170)..... B7155	
Fuel (By Fuel Tank) (23501-1010)..... BF984	Fuel/Water Separator (w/o Drain or Sensor Port) (234011440)..... BF1224	
Fuel (By Engine) (23401-1400)..... BF957 +	Fuel/Water Separator (w/Drain) (234011440)..... BF1223	
Air (17801-2810)..... PA3600	Fuel/Water Separator (w/Drain & Sensor Port) (234011440)..... BF1223-SP	
Trans. (349261041)..... BT230 +	Fuel/Water Separator (Open End for Bowl) (234011440)..... BF1223-O	
FD2218LP w/H06C-TP (6.5L) Eng. (1993-94)	Fuel (234011402A)..... BF948	
F-F Lube (15607-1740)..... B7005	Fuel (234011402)..... BF957 +	
B-P Lube (15607-1860)..... B7124	Air (178012810)..... PA3600	
Fuel (By Fuel Tank) (23501-1010)..... BF984	FD2320DH w/J08C (8.0L) Eng. (2004)	
Fuel (By Engine) (23401-1400)..... BF957 +	Lube (156072170)..... B7155	
Air (17801-2810)..... PA3600	Fuel/Water Separator (w/o Drain or Sensor Port) (234011440)..... BF1224	
Trans. (349261041)..... BT230 +	Fuel/Water Separator (w/Drain) (234011440)..... BF1223	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

**Trucks & Buses Applications** **BALDWIN FILTERS**

<b>HINO Trucks (cont'd)</b>	<b>HINO Trucks (cont'd)</b>	<b>HINO Trucks (cont'd)</b>
FE1J w/J08C Eng. (Cont'd)	FE19 w/H06C-T (6.5L) Eng. (1985-89)	FE2620 w/J08C-TP (8.0L) Eng. (1999-2001)
S. Fuel (Engine) (23401-1332)..... <b>BF7967</b>	F-F Lube (15607-1740)..... <b>B7005</b>	Lube (156072170)..... <b>B7155</b>
O. Air (17801-2600)..... <b>PA2779</b>	5 3/8 In. B-P Lube (15607-1471).. <b>B50 +</b>	Fuel/Water Separator (w/o Drain or Sensor Port) (234011440)..... <b>BF1224</b>
I. Air (17801-2840)..... <b>PA2545</b>	5 7/8 In. B-P Lube (15607-1860).. <b>B7124</b>	Fuel/Water Separator (w/Drain) (234011440)..... <b>BF1223</b>
FE2J w/J08C Eng. (1998-2004)	P. Fuel (By Fuel Tank) (23501-1010)..... <b>BF984</b>	Fuel/Water Separator (w/Drain & Sensor Port) (234011440)..... <b>BF1223-SP</b>
Lube (156072170)..... <b>B7155</b>	Fuel Spin-on (By Engine) (23401-1400)..... <b>BF957 +</b>	Fuel/Water Separator (Open End for Bowl) (234011440)..... <b>BF1223-O</b>
Fuel/Water Separator (w/o Drain or Sensor Port) (234011440)..... <b>BF1224</b>	O. Air (17801-2480)..... <b>PA2688</b>	Fuel (234011402)..... <b>BF957 +</b>
Fuel/Water Separator (w/Drain) (234011440)..... <b>BF1223</b>	I. Air (17801-2460)..... <b>PA2621</b>	Air (17801-2810)..... <b>PA3600</b>
Fuel/Water Separator (w/Drain & Sensor Port) (234011440)..... <b>BF1223-SP</b>	Coolant (16304-1011)..... <b>BW5139</b>	Trans. (34926-1041)..... <b>BT230 +</b>
Fuel/Water Separator (Open End for Bowl) (234011440)..... <b>BF1223-O</b>	Trans. (34926-1041)..... <b>BT230 +</b>	FE2620 w/J08C-TP (8.0L) Eng. (2002)
Fuel (1998-2002) (234011402)..... <b>BF957 +</b>	FE19 w/H07C Eng. (1984-91)	Lube (156072170)..... <b>B7155</b>
Fuel (2003-04) (234011510A)..... <b>BF7967</b>	F-F Lube (156071740)..... <b>B7005</b>	Fuel/Water Separator (w/o Drain or Sensor Port) (234011440)..... <b>BF1224</b>
Air (178012810)..... <b>PA3600</b>	B-P Lube (156071860)..... <b>B7124</b>	Fuel/Water Separator (w/Drain) (234011440)..... <b>BF1223</b>
Trans. (1998-2001) (349261041). <b>BT230 +</b>	Fuel (By Fuel Tank) (235011010). <b>BF984</b>	Fuel/Water Separator (w/Drain & Sensor Port) (234011440)..... <b>BF1223-SP</b>
FE5H w/H06C Eng. (1993-97)	Fuel (By Engine) (234011402)..... <b>BF957 +</b>	Fuel/Water Separator (Open End for Bowl) (234011440)..... <b>BF1223-O</b>
F-F Lube (156071740)..... <b>B7005</b>	O. Air (178012480)..... <b>PA2688</b>	Fuel (234011402)..... <b>BF957 +</b>
B-P Lube (156071860)..... <b>B7124</b>	I. Air (178012460)..... <b>PA2621</b>	Air (17801-2810)..... <b>PA3600</b>
Fuel (By Fuel Tank) (235011010). <b>BF984</b>	Trans. (349261041)..... <b>BT230 +</b>	FE2620 w/J08C-TP (8.0L) Eng. (2003-04)
Fuel (By Engine) (234011402)..... <b>BF957 +</b>	FE20 w/H06C (6.5L) Eng. (1992)	Lube (156072170)..... <b>B7155</b>
Air (178012810)..... <b>PA3600</b>	F-F Lube (15607-1740)..... <b>B7005</b>	Fuel/Water Separator (w/o Drain or Sensor Port) (234011440)..... <b>BF1224</b>
Trans. (349261041)..... <b>BT230 +</b>	B-P Lube (15607-1860)..... <b>B7124</b>	Fuel/Water Separator (w/Drain) (234011440)..... <b>BF1223</b>
FE16 w/W06E Eng. (1986-87)	Fuel (By Fuel Tank) (23501-1010)..... <b>BF984</b>	Fuel/Water Separator (w/Drain & Sensor Port) (234011440)..... <b>BF1223-SP</b>
Lube (15607-1740)..... <b>B7005</b>	Fuel (By Engine) (23401-1400).... <b>BF957 +</b>	Fuel/Water Separator (Open End for Bowl) (234011440)..... <b>BF1223-O</b>
Fuel (By Fuel Tank) (23501-1010)..... <b>BF984</b>	Air (17801-2810)..... <b>PA3600</b>	Fuel (234011510A)..... <b>BF7967</b>
Fuel (By Engine) (23401-1411).... <b>BF7648</b>	Trans. (34926-1041)..... <b>BT230 +</b>	Air (17801-2810)..... <b>PA3600</b>
O. Air (17801-2480)..... <b>PA2688</b>	FE2618 w/H06C-TP (6.5L) Eng. (1993-94)	FF1J w/J08CT Eng.
I. Air (17801-2460)..... <b>PA2621</b>	F-F Lube (156071740)..... <b>B7005</b>	Dual-Flow Lube (15607-1733)..... <b>BD7105</b>
Trans. (34926-1041)..... <b>BT230 +</b>	B-P Lube (156071860)..... <b>B7124</b>	P. Fuel/Water Separator (w/o Drain or Sensor Port) (234011440)..... <b>BF1224</b>
FE17 w/H07C (6.7L) Eng. (1984-92)	Fuel (By Fuel Tank) (235011010). <b>BF984</b>	P. Fuel/Water Separator (w/Drain) (234011440)..... <b>BF1223</b>
Lube (15607-1740)..... <b>B7005</b>	Fuel (By Engine) (234011402)..... <b>BF957 +</b>	P. Fuel/Water Separator (w/Drain & Sensor Port) (234011440)..... <b>BF1223-SP</b>
Fuel (By Fuel Tank) (23501-1010)..... <b>BF984</b>	Air (178012810)..... <b>PA3600</b>	P. Fuel/Water Separator (Open End for Bowl) (234011440)..... <b>BF1223-O</b>
Fuel (By Engine) (23401-1402).... <b>BF957 +</b>	Trans. (349261041)..... <b>BT230 +</b>	S. Fuel (Engine) (23401-1332)..... <b>BF7967</b>
O. Air (17801-2480)..... <b>PA2688</b>	FE2618 w/H06C-TT (6.5L) Eng. (1995-97)	O. Air (17801-2600)..... <b>PA2779</b>
I. Air (17801-2460)..... <b>PA2621</b>	F-F Lube (156071740)..... <b>B7005</b>	I. Air (17801-2840)..... <b>PA2545</b>
Coolant (16304-1011)..... <b>BW5139</b>	B-P Lube (156071860)..... <b>B7124</b>	FF2J w/J08C Eng. (1998-2003)
Trans. (34926-1041)..... <b>BT230 +</b>	Fuel (By Fuel Tank) (235011010). <b>BF984</b>	Lube (156072170)..... <b>B7155</b>
FE19 w/H06C-TJ (6.5L) Eng. (1990-92)	Fuel (By Engine) (234011402)..... <b>BF957 +</b>	Fuel/Water Separator (w/o Drain or Sensor Port) (234011440)..... <b>BF1224</b>
F-F Lube (15607-1740)..... <b>B7005</b>	Air (178012810)..... <b>PA3600</b>	Fuel/Water Separator (w/Drain) (234011440)..... <b>BF1223</b>
5 3/8 In. B-P Lube (15607-1471).. <b>B50 +</b>	Trans. (349261041)..... <b>BT230 +</b>	Fuel/Water Separator (w/Drain & Sensor Port) (234011440)..... <b>BF1223-SP</b>
5 7/8 In. B-P Lube (15607-1860).. <b>B7124</b>	FE2620 w/J08C-TD (8.0L) Eng. (1998)	P. Fuel/Water Separator (Open End for Bowl) (234011440)..... <b>BF1223-O</b>
P. Fuel (By Fuel Tank) (23501-1010)..... <b>BF984</b>	Lube (156072170)..... <b>B7155</b>	S. Fuel (Engine) (23401-1332)..... <b>BF7967</b>
Fuel Spin-on (By Engine) (23401-1400)..... <b>BF957 +</b>	Fuel/Water Separator (w/o Drain or Sensor Port) (234011440)..... <b>BF1224</b>	O. Air (17801-2600)..... <b>PA2779</b>
O. Air (17801-2480)..... <b>PA2688</b>	Fuel/Water Separator (w/Drain) (234011440)..... <b>BF1223</b>	I. Air (17801-2840)..... <b>PA2545</b>
I. Air (17801-2460)..... <b>PA2621</b>	Fuel/Water Separator (w/Drain & Sensor Port) (234011440)..... <b>BF1223-SP</b>	FF2J w/J08C Eng. (1998-2003)
Coolant (16304-1011)..... <b>BW5139</b>	Fuel/Water Separator (Open End for Bowl) (234011440)..... <b>BF1223-O</b>	Lube (156072170)..... <b>B7155</b>
Trans. (34926-1041)..... <b>BT230 +</b>	Fuel (234011402)..... <b>BF957 +</b>	Fuel/Water Separator (w/o Drain or Sensor Port) (234011440)..... <b>BF1224</b>
FE19 w/H06C-TJ (6.5L) Eng. (1990-92)	Air (17801-2810)..... <b>PA3600</b>	Fuel/Water Separator (w/Drain) (234011440)..... <b>BF1223</b>
F-F Lube (15607-1740)..... <b>B7005</b>	Trans. (349261041)..... <b>BT230 +</b>	Fuel/Water Separator (w/Drain & Sensor Port) (234011440)..... <b>BF1223-SP</b>
5 3/8 In. B-P Lube (15607-1471).. <b>B50 +</b>	FE2620 w/J08C-TP (8.0L) Eng. (1998)	
5 7/8 In. B-P Lube (15607-1860).. <b>B7124</b>	Lube (156072170)..... <b>B7155</b>	
P. Fuel (By Fuel Tank) (23501-1010)..... <b>BF984</b>	Fuel/Water Separator (w/o Drain or Sensor Port) (234011440)..... <b>BF1224</b>	
Fuel Spin-on (By Engine) (23401-1400)..... <b>BF957 +</b>	Fuel/Water Separator (w/Drain) (234011440)..... <b>BF1223</b>	
O. Air (17801-2480)..... <b>PA2688</b>	Fuel/Water Separator (w/Drain & Sensor Port) (234011440)..... <b>BF1223-SP</b>	
I. Air (17801-2460)..... <b>PA2621</b>	Fuel/Water Separator (Open End for Bowl) (234011440)..... <b>BF1223-O</b>	
Coolant (16304-1011)..... <b>BW5139</b>	Fuel (234011402)..... <b>BF957 +</b>	
Trans. (34926-1041)..... <b>BT230 +</b>	Air (17801-2810)..... <b>PA3600</b>	
	Trans. (349261041)..... <b>BT230 +</b>	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



HINO Trucks (cont'd)	HINO Trucks (cont'd)	HINO Trucks (cont'd)
FF2J w/J08C Eng. (1998-2003) (Cont'd)	FF20 w/H06C (6.5L) Eng. (1992) (Cont'd)	FF197, FF197KA w/H06T-C Eng.
Fuel/Water Separator (Open End for Bowl) (234011440).....	Fuel (By Engine) (23401-1400)....	Lube Ele.....
Fuel (1998-2002) (234011402).....	Air (17801-2810).....	Fuel Ele.....
Fuel (2003) (234011510A).....	Trans. (34926-1041).....	Air.....
Air (178012810).....		
Trans. (1998-2001) (349261041).....	FF23 w/H06C (6.5L) Eng. (1992)	FF197LA, FG197LA w/H06T-C Eng.
	F-F Lube (156071740).....	Dual-Flow Lube.....
FF4H w/H06C Eng.	B-P Lube (15607-1860).....	Fuel Ele. (23401-1290).....
F-F Lube (156071740).....	Fuel (By Fuel Tank) (23501-1010).....	Fuel Spin-on (23401-1410).....
B-P Lube (156071860).....	Fuel (By Engine) (23401-1402)....	Air (17801-2280).....
Fuel (By Fuel Tank) (235011010).....	Single Air (17801-2810).....	
Fuel (By Engine) (234011402).....	Trans. (34926-1041).....	FF3018 w/H06C-TP (6.5L) Eng. (1993-94)
Air (178012810).....		F-F Lube (156071740).....
Trans. (349261041).....	FF172, FF172LA w/H07C Eng.	B-P Lube (156071860).....
	Lube Ele. (15607-1220).....	Fuel (By Fuel Tank) (235011010).....
FF17 w/H07C (6.7L) Eng. (1984-91)	Fuel Ele. (23401-1290).....	Fuel (By Engine) (234011402).....
Lube (15607-1740).....	Air (17801-2200).....	Air (178012810).....
Fuel (By Fuel Tank) (23501-1010).....		Trans. (349261041).....
Fuel (By Engine) (23401-1402)....	FF172, FF172KA w/EH700 Eng.	
O. Air (17801-2480).....	Lube Ele. (15607-1220).....	FF3018 w/H06C-TU (6.5L) Eng. (1995-97)
I. Air (17801-2460).....	Fuel Ele. (23401-1290).....	F-F Lube (156071740).....
Coolant (16304-1011).....	Air (17801-2200).....	B-P Lube (156071860).....
Trans. (34926-1041).....		Fuel (By Fuel Tank) (235011010).....
	FF173, FF173LA w/H07C Eng.	Fuel (By Engine) (234011402).....
FF19 w/H06C-T (6.5L) Eng. (1984-1989)	Lube Ele. (15607-1220).....	Air (178012810).....
F-F Lube (156071740A).....	Fuel Ele. (23401-1290).....	Trans. (349261041).....
B-P Lube (156071860A).....	Air (17801-2200).....	
Fuel (By Fuel Tank) (235011010A).....		FF3018 w/J08C-TP Eng.
Fuel (By Engine) (234011402A)...	FF173, FF173KA w/EH700 Eng.	F-F Lube (15607-1740).....
O. Air (178012480A).....	Lube Ele. (15607-1220).....	B-P Lube (15607-1860).....
I. Air (178012460A).....	Fuel Ele. (23401-1290).....	P. Fuel (By Fuel Tank) (23501-1010).....
Trans. (349261041A).....	Air (17801-2200).....	Fuel Spin-on (By Engine) (23401-1400).....
		Air (17801-2810).....
FF19 w/H06C-TJ (6.5L) Eng. (1990-92)	FF177, FF177LA, FF177LD w/H07C Eng.	
F-F Lube (156071740A).....	Lube Ele. (15607-1220).....	FF3020 w/H06C-TN (6.5L) Eng. (1993-94)
B-P Lube (156071860A).....	Fuel Ele. (23401-1290).....	F-F Lube (156071740).....
Fuel (By Fuel Tank) (235011010A).....	Air (17801-2200).....	B-P Lube (156071860).....
Fuel (By Engine) (234011402A)...		Fuel (By Fuel Tank) (235011010).....
O. Air (178012480A).....	FF177, FF177KA w/EH700 Eng.	Fuel (By Engine) (234011402).....
I. Air (178012460A).....	Lube Ele. (15607-1220).....	Air (178012810).....
Trans. (349261041A).....	Fuel Ele. (23401-1290).....	Trans. (349261041).....
	Air (17801-2200).....	
FF19 w/H07C Eng. (1984-91)	FF192, FF192KD w/H06C-T Eng.	
F-F Lube (156071740).....	Lube Ele.....	FF3020 w/H06C-TU (6.5L) Eng. (1995-97)
B-P Lube (156071860).....	Fuel Ele.....	F-F Lube (156071740).....
Fuel (By Fuel Tank) (235011010).....	Air.....	B-P Lube (156071860).....
Fuel (By Engine) (234011402).....		Fuel (By Fuel Tank) (235011010).....
O. Air (178012480).....	FF192LD, FG192, FG192LD w/H06C-T Eng.	Fuel (By Engine) (234011402).....
I. Air (178012460).....	Dual-Flow Lube.....	Air (178012810).....
Trans. (349261041).....	Fuel Ele. (23401-1290).....	Trans. (349261041).....
	Fuel Spin-on (23401-1410).....	
FF19 w/Cummins 6BT5.9 (5.9L) Eng.	Air (17801-2280).....	FF3020 w/J08C-TD (8.0L) Eng. (1998)
Lube (3914395).....		Lube (156072170).....
Fuel/Water Separator (3925274).....	FF193, FF193KA w/H06T-C Eng.	Fuel/Water Separator (w/o Drain or Sensor Port) (234011440).....
S. Fuel (3903640).....	Lube Ele.....	Fuel/Water Separator (w/Drain) (234011440).....
	Fuel Ele.....	Fuel/Water Separator (w/Drain & Sensor Port) (234011440).....
FF20 w/H06C (6.5L) Eng. (1992)	Air.....	Fuel/Water Separator (Open End for Bowl) (234011440).....
F-F Lube (15607-1740).....	FF193LA, FF193LA, FG193LD w/H06T-C Eng.	Fuel (234011402).....
B-P Lube (15607-1860).....	Dual-Flow Lube.....	Air (178012810).....
Fuel (By Fuel Tank) (23501-1010).....	Fuel Ele. (23401-1290).....	Trans. (349261041).....
	Fuel Spin-on (23401-1410).....	
	Air (17801-2280).....	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>HINO Trucks (cont'd)</b>	<b>HINO Trucks (cont'd)</b>	<b>HINO Trucks (cont'd)</b>
FF3020 w/J08C-TP (8.0L) Eng. (1999-2001) Lube (156072170)..... <b>B7155</b> Fuel/Water Separator (w/o Drain or Sensor Port) (234011440)..... <b>BF1224</b> Fuel/Water Separator (w/Drain) (234011440)..... <b>BF1223</b> Fuel/Water Separator (w/Drain & Sensor Port) (234011440)..... <b>BF1223-SP</b> Fuel/Water Separator (Open End for Bowl) (234011440)..... <b>BF1223-O</b> Fuel (234011402)..... <b>BF957 +</b> Air (178012810)..... <b>PA3600</b> Trans. (349261041)..... <b>BT230 +</b>	FG1J w/J08C Eng. (Cont'd) S. Fuel (Engine) (23401-1332)..... <b>BF7967</b> O. Air (17801-2600)..... <b>PA2779</b> I. Air (17801-2840)..... <b>PA2545</b> FG1J (500 Series) w/J08C-TI Eng. Dual-Flow Lube (15607-1733)..... <b>BD7105</b> Fuel (Engine) (S23401-1510)..... <b>BF7967</b> FG19 w/H06C Eng. (1984-86) F-F Lube (156071740)..... <b>B7005</b> B-P Lube (156071860)..... <b>B7124</b> B-P Lube (15607-1471)..... <b>B50 +</b> Fuel (By Fuel Tank) (235011010)..... <b>BF984</b> Fuel (By Engine) (234011402)..... <b>BF957 +</b> O. Air (178012480)..... <b>PA2688</b> I. Air (178012460)..... <b>PA2621</b> Trans. (349261041)..... <b>BT230 +</b> FG22 w/EM100 Eng. (1984-85) F-F Lube (15607-1740)..... <b>B7005</b> B-P Lube (15607-1760)..... <b>B7577</b> Fuel (By Fuel Tank) (23501-1010)..... <b>BF984</b> Fuel (By Engine) (23401-1400)..... <b>BF957 +</b> O. Air (17801-2480)..... <b>PA2688</b> I. Air (17801-2460)..... <b>PA2621</b> Coolant (16304-1011)..... <b>BW5139</b> Trans. (34926-1041)..... <b>BT230 +</b> FG172LD w/H07C Eng. Lube Spin-on (15607-1750)..... <b>B404</b> Fuel Ele. (23401-1290)..... <b>[2] PF311</b> Fuel Spin-on (23401-1410)..... <b>BF7967</b> Air (17801-2200)..... <b>PA2880</b> FG173LD w/H07C Eng. Lube Spin-on (15607-1750)..... <b>B404</b> Fuel Ele. (23401-1290)..... <b>[2] PF311</b> Fuel Spin-on (23401-1410)..... <b>BF7967</b> Air (17801-2200)..... <b>PA2880</b> FG175LA w/H07C Eng. Lube Spin-on (15607-1750)..... <b>B404</b> Fuel Ele. (23401-1290)..... <b>[2] PF311</b> Fuel Spin-on (23401-1410)..... <b>BF7967</b> Air (17801-2200)..... <b>PA2880</b> FG177LA w/H07C Eng. Lube Spin-on (15607-1750)..... <b>B404</b> Fuel Ele. (23401-1290)..... <b>[2] PF311</b> Fuel Spin-on (23401-1410)..... <b>BF7967</b> Air (17801-2200)..... <b>PA2880</b> FG195, FG195LA w/H06T-C Eng. Dual-Flow Lube..... <b>BD7105</b> Fuel Ele. (23401-1290)..... <b>[2] PF311</b> Fuel Spin-on (23401-1410)..... <b>BF7967</b> Air (17801-2280)..... <b>PA2779</b> FM1J w/J08C-TI Eng. (European Truck) Dual-Flow Lube (15607-1733)..... <b>BD7105</b> F-F Lube (15607-2051)..... <b>B7155</b> P. Fuel/Water Separator (23401-1441)..... <b>BF1348 +</b>	FM1J w/J08C-TI Eng. (European Truck) (Cont'd) P. Fuel/Water Separator (w/o Drain or Sensor Port) (234011440) <b>BF1224</b> P. Fuel/Water Separator (w/Drain) (234011440)..... <b>BF1223</b> P. Fuel/Water Separator (w/Drain & Sensor Port) (234011440)..... <b>BF1223-SP</b> P. Fuel/Water Separator (Open End for Bowl) (234011440)..... <b>BF1223-O</b> S. Fuel (234011510)..... <b>BF7967</b> O. Air (17801-2600)..... <b>PA2779</b> I. Air (17801-2840)..... <b>PA2545</b> FM1J (500 Series) w/J08C-TI Eng. Dual-Flow Lube (15607-1733)..... <b>BD7105</b> P. Fuel/Water Separator (w/o Drain or Sensor Port) (234011440) <b>BF1224</b> P. Fuel/Water Separator (w/Drain) (234011440)..... <b>BF1223</b> P. Fuel/Water Separator (w/Drain & Sensor Port) (234011440)..... <b>BF1223-SP</b> P. Fuel/Water Separator (Open End for Bowl) (234011440)..... <b>BF1223-O</b> S. Fuel (Engine) (S23401-1510).... <b>BF7967</b> FM1JNLA w/J08C Eng. Dual-Flow Lube (15607-1733)..... <b>BD7105</b> P. Fuel/Water Separator (w/o Drain or Sensor Port) (234011440) <b>BF1224</b> P. Fuel/Water Separator (w/Drain) (234011440)..... <b>BF1223</b> P. Fuel/Water Separator (w/Drain & Sensor Port) (234011440)..... <b>BF1223-SP</b> P. Fuel/Water Separator (Open End for Bowl) (234011440)..... <b>BF1223-O</b> S. Fuel (Engine) (23401-1332)..... <b>BF7967</b> O. Air (17801-2280)..... <b>PA2779</b> FM2K w/K13D Eng. Lube Ele. (Large) (15607-1580)... <b>P7185</b> Lube Ele. (Small) (15607-1562)... <b>P7053</b> Fuel (Fuel Tank) (23401-1400)..... <b>BF957 +</b> O. Std. Air (17801-2490)..... <b>PA2676 +</b> O. XP Air (17801-2490)..... <b>PA2676XP</b> FR1K Lube (15607-1560)..... <b>P7053</b> Fuel (23401-1090)..... <b>PF7572</b> FS1E (700 Series) w/E13C-TI Eng. Radial Seal O. Air (S17801-3450)..... <b>RS3710</b> Radial Seal O. Air (S17801-3360)..... <b>RS30238</b> FS2K w/K13D Eng. F-F Lube Ele..... <b>P7053</b> B-P Lube Ele..... <b>P7185</b> Fuel Ele. (23401-1090)..... <b>PF7572</b> Fuel Spin-on (23401-1221)..... <b>BF984</b> Air (17801-2960)..... <b>PA3914</b>
FF3020 w/J08C-TP (8.0L) Eng. (2002) Lube (156072170)..... <b>B7155</b> Fuel/Water Separator (w/o Drain or Sensor Port) (234011440)..... <b>BF1224</b> Fuel/Water Separator (w/Drain) (234011440)..... <b>BF1223</b> Fuel/Water Separator (w/Drain & Sensor Port) (234011440)..... <b>BF1223-SP</b> Fuel/Water Separator (Open End for Bowl) (234011440)..... <b>BF1223-O</b> Fuel (234011402)..... <b>BF957 +</b> Air (178012810)..... <b>PA3600</b>	FG3020 w/J08C-TP (8.0L) Eng. (2003-04) Lube (156072170)..... <b>B7155</b> Fuel/Water Separator (w/o Drain or Sensor Port) (234011440)..... <b>BF1224</b> Fuel/Water Separator (w/Drain) (234011440)..... <b>BF1223</b> Fuel/Water Separator (w/Drain & Sensor Port) (234011440)..... <b>BF1223-SP</b> Fuel/Water Separator (Open End for Bowl) (234011440)..... <b>BF1223-O</b> Fuel (234011510A)..... <b>BF7967</b> Air (178012810)..... <b>PA3600</b>	FFC1 w/Cummins 6BT (5.9L) Eng. (1986-88) Lube (3908615)..... <b>BT339 +</b> Fuel/Water Separator (M16 x 1.5 Thd.) (3903202)..... <b>BF1226</b> Some Fuel/Water Separator (13/16-18 Thd.) (3903410)..... <b>BF1280 +</b> S. Fuel (3903640)..... <b>BF788</b> O. Air (17801-2480A)..... <b>PA2688</b> I. Air (17801-2460A)..... <b>PA2621</b> Coolant (3315788)..... <b>BW5140</b> Trans. (349261041A)..... <b>BT230 +</b>
FG1J w/J08C Eng. Dual-Flow Lube (15607-1733)..... <b>BD7105</b> P. Fuel/Water Separator (w/o Drain or Sensor Port) (234011440) <b>BF1224</b> P. Fuel/Water Separator (w/Drain) (234011440)..... <b>BF1223</b> P. Fuel/Water Separator (w/Drain & Sensor Port) (234011440)..... <b>BF1223-SP</b> P. Fuel/Water Separator (Open End for Bowl) (234011440)..... <b>BF1223-O</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

HINO Trucks (cont'd)	
FS270 w/EK100 Eng.	
F-F Lube Ele. (15607-1560).....	P7053
B-P Lube Ele. (15607-2160).....	P7185
Fuel (23401-1080).....	PF7572
Air (17801-2020).....	LL1886 +
FS270KD, FS271 w/EK100 Eng.	
F-F Lube Ele. (15607-1560).....	P7053
B-P Lube Ele. (15607-2160).....	P7185
Fuel (23401-1080).....	PF7572
Std. Air (17801-2170).....	PA2676 +
XP Air (17801-2170).....	PA2676XP +
FT163 (4x4), FT163LA, FD164, FD164LA, GD164, GD164LA, FD166, FD166LA, GD166 w/WO6E Eng.	
Lube (15607-1750).....	B404
Fuel Ele. (23401-1290).....	PF311
Fuel Spin-on (23401-1330).....	BF7967
Air (17801-2200).....	PA2880
FU633, K-FS633, K-FN634, K-FR634, K-FS634, K-FN636, K-FR636, K-FS636 w/EF750 Eng.	
Lube Ele. (15607-1560).....	P7053
Fuel (23401-1090).....	PF7572
Std. Air (17801-2290).....	PA1886 +
XP Air (17801-2290).....	PA1886XP +
FY1E (700 Series) w/E13C-TI Eng.	
Radial Seal O. Air (S17801-3450).....	RS3710
Radial Seal O. Air (S17801-3360).....	RS30238
GC17 w/H07C (6.7L) Eng. (1990-91)	
Lube (15607-1740).....	B7005
Fuel (By Fuel Tank (23501-1010).....	BF984
Fuel (By Engine) (23401-1402)....	BF957 +
O. Air (17801-2480).....	PA2688
I. Air (17801-2460).....	PA2621
Coolant (16304-1011).....	BW5139
Trans. (34926-1041).....	BT230 +
GC20 w/H06C (6.5L) Eng. (1992)	
F-F Lube (15607-1740).....	B7005
B-P Lube (15607-1860).....	B7124
Fuel (By Fuel Tank (23501-1010).....	BF984
Fuel (By Engine) (23401-1400)....	BF957 +
Air (17801-2810).....	PA3600
Trans. (34926-1041).....	BT230 +
GD1J w/J08C Eng.	
Dual-Flow Lube (15607-1733).....	BD7105
P. Fuel/Water Separator (w/o Drain or Sensor Port) (234011440)	BF1224
P. Fuel/Water Separator (w/Drain) (234011440).....	BF1223
P. Fuel/Water Separator (w/Drain & Sensor Port) (234011440).....	BF1223-SP
P. Fuel/Water Separator (Open End for Bowl) (234011440).....	BF1223-O
S. Fuel (Engine) (23401-1332).....	BF7967
Air (17801-2600).....	PA2779
GT1J (500 Series) w/J08C-TI Eng.	
Dual-Flow Lube (15607-1733).....	BD7105
P. Fuel/Water Separator (w/o Drain or Sensor Port) (234011440)	BF1224
P. Fuel/Water Separator (w/Drain) (234011440).....	BF1223
P. Fuel/Water Separator (w/Drain & Sensor Port) (234011440).....	BF1223-SP
P. Fuel/Water Separator (Open End for Bowl) (234011440).....	BF1223-O
S. Fuel (Engine) (S23401-1510)...	BF7967

HINO Trucks (cont'd)	
GD1J w/J08C Eng. (Cont'd)	
O. Air (17801-2600).....	PA2779
I. Air (17801-2840).....	PA2545
GD1J (500 Series) w/J08C-TI Eng.	
Dual-Flow Lube (15607-1733).....	BD7105
P. Fuel/Water Separator (w/o Drain or Sensor Port) (234011440)	BF1224
P. Fuel/Water Separator (w/Drain) (234011440).....	BF1223
P. Fuel/Water Separator (w/Drain & Sensor Port) (234011440).....	BF1223-SP
P. Fuel/Water Separator (Open End for Bowl) (234011440).....	BF1223-O
S. Fuel (Engine) (S23401-1510)...	BF7967
GH1J w/J08C-TI Eng.	
Dual-Flow Lube (15607-1733).....	BD7105
P. Fuel/Water Separator (w/o Drain or Sensor Port) (234011440)	BF1224
P. Fuel/Water Separator (w/Drain) (234011440).....	BF1223
P. Fuel/Water Separator (w/Drain & Sensor Port) (234011440).....	BF1223-SP
P. Fuel/Water Separator (Open End for Bowl) (234011440).....	BF1223-O
S. Fuel (Engine) (23401-1332).....	BF7967
O. Air (17801-2600).....	PA2779
I. Air (17801-2840).....	PA2545
GH1J (500 Series) w/J08C-TI Eng.	
Dual-Flow Lube (15607-1733).....	BD7105
P. Fuel/Water Separator (w/o Drain or Sensor Port) (234011440)	BF1224
P. Fuel/Water Separator (w/Drain) (234011440).....	BF1223
P. Fuel/Water Separator (w/Drain & Sensor Port) (234011440).....	BF1223-SP
P. Fuel/Water Separator (Open End for Bowl) (234011440).....	BF1223-O
S. Fuel (Engine) (S23401-1510)...	BF7967
GT1J w/J08C-TI Eng.	
Dual-Flow Lube (15607-1733).....	BD7105
P. Fuel/Water Separator (w/o Drain or Sensor Port) (234011440)	BF1224
P. Fuel/Water Separator (w/Drain) (234011440).....	BF1223
P. Fuel/Water Separator (w/Drain & Sensor Port) (234011440).....	BF1223-SP
P. Fuel/Water Separator (Open End for Bowl) (234011440).....	BF1223-O
S. Fuel (Engine) (23401-1332).....	BF7967
Air (17801-2600).....	PA2779
GT1J (500 Series) w/J08C-TI Eng.	
Dual-Flow Lube (15607-1733).....	BD7105
P. Fuel/Water Separator (w/o Drain or Sensor Port) (234011440)	BF1224
P. Fuel/Water Separator (w/Drain) (234011440).....	BF1223
P. Fuel/Water Separator (w/Drain & Sensor Port) (234011440).....	BF1223-SP
P. Fuel/Water Separator (Open End for Bowl) (234011440).....	BF1223-O
S. Fuel (Engine) (23401-1332).....	BF7967
Air (17801-2600).....	PA2779


HINO Trucks (cont'd)	
GT1J (500 Series) w/J08C-TI Eng. (Cont'd)	
P. Fuel/Water Separator (Open End for Bowl) (234011440).....	BF1223-O
S. Fuel (Engine) (S23401-1510)...	BF7967
GT173 (4x4), GT173 (4x4) MA w/H07C Eng.	
Lube (15607-1750).....	B404
Fuel Ele. (23401-1290).....	PF311
O. Air (17801-2200).....	PA2880
Air (17801-2620).....	PA3448 <sup>90</sup>
GT173 (4x4) KA w/EH700 Eng.	
Lube Ele. (15607-1320).....	P7106
Fuel Ele. (23401-1290).....	PF311
O. Air (17801-2200).....	PA2880
GT175 (4x4), GT175 (4x4) MA w/H07C Eng.	
Lube (15607-1750).....	B404
Fuel Ele. (23401-1290).....	PF311
O. Air (17801-2200).....	PA2880
Air (17801-2620).....	PA3448 <sup>90</sup>
GT175 (4x4) KA w/EH700 Eng.	
Lube Ele. (15607-1320).....	P7106
Fuel Ele. (23401-1290).....	PF311
O. Air (17801-2200).....	PA2880
GN1F	
Lube (15607-1560).....	P7053
Fuel (23401-1090).....	PF7572
GN2F	
Lube (15607-1560).....	P7053
Fuel (23401-1090).....	PF7572
GS221, GS221KD, GS221KM w/EM100 Eng.	
Lube (15607-1010).....	P7127
Lube (15607-1220).....	P723
Fuel (23401-1080).....	PF7572
O. Air (17801-2480).....	PA2688
I. Air (17801-2460).....	PA2621
GS224, GS224KA w/EM100 Eng.	
Lube (15607-1010).....	P7127
Lube (15607-1220).....	P723
Fuel (23401-1080).....	PF7572
O. Air (17801-2480).....	PA2688
I. Air (17801-2460).....	PA2621
HL300 w/EC100 Eng.	
Lube Ele. (15607-1090).....	P723
Fuel Ele. (23401-1060).....	PF7550
HL500 w/EH100 Eng.	
Lube Ele. (15607-1090).....	P723
Fuel Ele. (23401-1060).....	PF7550
HV10	
Lube (1560A41010).....	B2 +
Fuel Spin-on (2330D56030).....	BF7967
Air (1780B44070).....	PA3863
KA340 w/EF100 Eng.	
Fuel (23401-1040).....	PF7551 <sup>90</sup>

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>HINO Trucks (cont'd)</b>	<b>HINO Trucks (cont'd)</b>	<b>HINO Trucks (cont'd)</b>
K-AM101 w/EH100 Eng. Lube Ele. (15607-1090)..... <b>P723</b> Fuel Ele. (23401-1060)..... <b>PF7550</b> Air (17801-1720)..... <b>PA2961-FN</b>	KF766 w/EF300 Eng. Lube (15607-1010)..... <b>P7127</b> Lube (15607-1521)..... <b>P723</b> Fuel Ele. (23401-1290)..... <b>PF311</b> Air (17801-1020)..... <b>PA1637-FN</b>	K-FH272, K-FN272, K-FR272 w/EK100 Eng. (Cont'd) Std. Air (17801-2290)..... <b>PA1886 +</b> XP Air (17801-2290)..... <b>PA1886XP +</b>
KB112D w/EB300 Eng. (1971-72) Fuel (23401-1040)..... <b>PF7551 90</b>	KF783 w/EF300 Eng. Lube (15607-1010)..... <b>P7127</b> Lube (15607-1521)..... <b>P723</b> Fuel Ele. (23401-1290)..... <b>PF311</b> Air (17801-1020)..... <b>PA1637-FN</b>	K-FN204 w/EK100 Eng. Lube (15607-1560)..... <b>P7053</b> Fuel (23401-1080)..... <b>PF7572</b> Std. Air (17801-2290)..... <b>PA1886 +</b> XP Air (17801-2290)..... <b>PA1886XP +</b>
KB113.122 w/EB300 Eng. (1971-1/79) Fuel (23401-1040)..... <b>PF7551 90</b>	KF786 w/EF300 Eng. Lube (15607-1010)..... <b>P7127</b> Lube (15607-1521)..... <b>P723</b> Fuel Ele. (23401-1290)..... <b>PF311</b> Air (17801-1020)..... <b>PA1637-FN</b>	K-KF787 w/EF350 Eng. Lube (15607-1560)..... <b>P7053</b> Fuel Ele. (23401-1290)..... <b>PF311</b> Air (17801-1020)..... <b>PA1637-FN</b>
KB301D w/EB100 Eng. (1968-71) Fuel (23401-1040)..... <b>PF7551 90</b>	KF797 w/EF300 Eng. Lube (15607-1010)..... <b>P7127</b> Lube (15607-1521)..... <b>P723</b> Fuel Ele. (23401-1290)..... <b>PF311</b> Air (17801-1020)..... <b>PA1637-FN</b>	K-KF797 w/EF350 Eng. Lube (15607-1560)..... <b>P7053</b> Fuel Ele. (23401-1290)..... <b>PF311</b> Air (17801-1020)..... <b>PA1637-FN</b>
KB302D w/EB300 Eng. (1971-72) Fuel (23401-1040)..... <b>PF7551 90</b>	K-FD120 w/EC100 Eng. Lube Ele. (15607-1090)..... <b>P723</b> Fuel Ele. (23401-1060)..... <b>PF7550</b>	K-FN274, K-FP274, K-FR274, K-FS274, K-FW274 w/EK100 Eng. Lube (15607-1560)..... <b>P7053</b> Fuel (23401-1090)..... <b>PF7572</b> Std. Air (17801-2290)..... <b>PA1886 +</b> XP Air (17801-2290)..... <b>PA1886XP +</b>
KB303 w/EB300 Eng. (1973-on) Fuel (23401-1040)..... <b>PF7551 90</b>	K-FF505 w/EF550 Eng. Lube (15607-1560)..... <b>P7053</b> Air (17801-1020)..... <b>PA1637-FN</b>	K-FN276, K-FP276, K-FR276, K-FS276, K-FW276 w/EK100 Eng. Lube (15607-1560)..... <b>P7053</b> Fuel (23401-1090)..... <b>PF7572</b> Std. Air (17801-2290)..... <b>PA1886 +</b> XP Air (17801-2290)..... <b>PA1886XP +</b>
KB304 w/EB300 Eng. (1973-on) Fuel (23401-1040)..... <b>PF7551 90</b>	K-FH221, K-FH222 w/EM100 Eng. Lube (15607-1010)..... <b>P7127</b> Lube (15607-1220)..... <b>P723</b> Fuel (23401-1080)..... <b>PF7572</b> Air (17801-2280)..... <b>PA2779</b>	K-FN278, K-FR276, K-FP279, K-FR279, K-FW279 w/EK100 Eng. Lube (15607-1560)..... <b>P7053</b> Fuel (23401-1090)..... <b>PF7572</b> Std. Air (17801-2290)..... <b>PA1886 +</b> XP Air (17801-2290)..... <b>PA1886XP +</b>
KB721 w/EF350 Eng. (10/75-80) Fuel (23401-1040)..... <b>PF7551 90</b>	K-FH224 w/EM100 Eng. Lube (15607-1010)..... <b>P7127</b> Lube (15607-1220)..... <b>P723</b> Fuel (23401-1080)..... <b>PF7572</b> Air (17801-2280)..... <b>PA2779</b>	K-FN282, K-FN284, K-FP284, K-FR284 w/EP100, EP100T Engs. Lube (15607-1560)..... <b>P7053</b> Fuel (23401-1090)..... <b>PF7572</b> Std. Air (17801-2290)..... <b>PA1886 +</b> XP Air (17801-2290)..... <b>PA1886XP +</b>
KB1110 w/EB100 Eng. (1968-71) Fuel (23401-1040)..... <b>PF7551 90</b>	K-FH226 w/EM100 Eng. Lube (15607-1010)..... <b>P7127</b> Lube (15607-1220)..... <b>P723</b> Fuel (23401-1080)..... <b>PF7572</b> Air (17801-2280)..... <b>PA2779</b>	K-FN286, K-FP286, K-FR286, K-FN288, K-FP288, K-FR288, K-FP289, K-FR289 w/EP100, EP100T Engs. Lube (15607-1560)..... <b>P7053</b> Std. Air (17801-2290)..... <b>PA1886 +</b> XP Air (17801-2290)..... <b>PA1886XP +</b>
KC320 w/DS70 Eng. (1965-76) Fuel (23401-1040)..... <b>PF7551 90</b>	K-FH228, K-FH229 w/EM100 Eng. Lube (15607-1010)..... <b>P7127</b> Lube (15607-1220)..... <b>P723</b> Fuel (23401-1080)..... <b>PF7572</b> Air (17801-2280)..... <b>PA2779</b>	K-FN600, K-FR600, K-FS600, K-FN638 w/EF550 Eng. Lube Ele. (15607-1010)..... <b>P7127</b> Lube Ele. (15607-1560)..... <b>P7053</b> Fuel (23401-1080)..... <b>PF7572</b> Std. Air (17801-2290)..... <b>PA1886 +</b> XP Air (17801-2290)..... <b>PA1886XP +</b>
KF300 w/ED100 Eng. (1971-75) Fuel (23401-1040)..... <b>PF7551 90</b>	K-FH270, K-FN270, K-FP270, K-FR270, K-FS270, K-FW270, P-FH270 w/EK100 Eng. F-F Lube Ele. (15607-1560)..... <b>P7053</b> B-P Lube Ele. (15607-2160)..... <b>P7185</b> Fuel (23401-1080)..... <b>PF7572</b> Air (17801-2020)..... <b>LL1886 +</b>	
KF305 w/ED100 Eng. (1971-75) Fuel (23401-1040)..... <b>PF7551 90</b>	K-FH272, K-FN272, K-FR272 w/EK100 Eng. F-F Lube Ele. (15607-1560)..... <b>P7053</b> B-P Lube Ele. (15607-2160)..... <b>P7185</b> Fuel (23401-1090)..... <b>PF7572</b>	
KF501, KJ501, KL501 w/EH100, EH300 Engs. Lube Ele. (15607-1090)..... <b>P723</b> Fuel Ele. (23401-1060)..... <b>PF7550</b> Air (17801-1720)..... <b>PA2961-FN</b>		
KM701, ZM701 w/DK10 Eng. (1969-72) Fuel (23401-1040)..... <b>PF7551 90</b>		
KF703 w/EF300 Eng. Lube (15607-1010)..... <b>P7127</b> Lube (15607-1090)..... <b>P723</b> Fuel (23401-1080)..... <b>PF7572</b> Air (17801-1020)..... <b>PA1637-FN</b>		
KF706 w/EF300 Eng. Lube (15607-1010)..... <b>P7127</b> Lube (15607-1090)..... <b>P723</b> Fuel (23401-1080)..... <b>PF7572</b> Air (17801-1020)..... <b>PA1637-FN</b>		
KF707 w/EF300 Eng. Lube (15607-1010)..... <b>P7127</b> Lube (15607-1090)..... <b>P723</b> Fuel (23401-1080)..... <b>PF7572</b> Air (17801-1020)..... <b>PA1637-FN</b>		
KF746 w/EF300 Eng. Lube (15607-1010)..... <b>P7127</b> Lube (15607-1521)..... <b>P723</b> Fuel Ele. (23401-1290)..... <b>PF311</b> Air (17801-1020)..... <b>PA1637-FN</b>		

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

HINO Trucks (cont'd)	HINO Trucks (cont'd)	HINO Trucks (cont'd)
K-FN602, K-FR602, K-FN604, K-FR604, K-FS604 w/EK550 Eng. <b>Lube</b> (15607-1560)..... <b>P7053</b> <b>Fuel</b> (23401-1090)..... <b>PF7572</b> <b>Std. Air</b> (17801-2290)..... <b>PA1886 +</b> <b>XP Air</b> (17801-2290)..... <b>PA1886XP +</b>	K-HT226, K-HU226 w/ER200 Eng. <b>Lube</b> (15607-1400)..... <b>P723</b> <b>Fuel</b> (23401-1090)..... <b>PF7572</b> <b>Air</b> (17801-1150)..... <b>PA1750-FN</b>	K-KC562, K-TC562 w/EF700 Eng. <b>Lube Ele.</b> (15607-1070)..... <b>P7053</b> <b>Air</b> (17801-1020)..... <b>PA1637-FN</b>
K-FN605, K-FR605, K-FN606, K-FR606, K-FS606 w/EK550 Eng. <b>Lube</b> (15607-1560)..... <b>P7053</b> <b>Std. Air</b> (17801-2290)..... <b>PA1886 +</b> <b>XP Air</b> (17801-2290)..... <b>PA1886XP +</b>	K-HT236 w/M10U Eng. <b>Lube</b> (15607-1400)..... <b>P723</b> <b>Fuel</b> (23401-1090)..... <b>PF7572</b> <b>Air</b> (17801-2280)..... <b>PA2779</b>	K-KF505 w/EF500 Eng. <b>Lube</b> (15607-1560)..... <b>P7053</b> <b>Fuel</b> (23401-1080)..... <b>PF7572</b> <b>Air</b> (17801-1020)..... <b>PA1637-FN</b>
K-FN630, K-FR630, K-FS630 w/EF750 Eng. <b>Lube Ele.</b> (15607-1560)..... <b>P7053</b> <b>Fuel</b> (23401-1090)..... <b>PF7572</b> <b>Std. Air</b> (17801-2290)..... <b>PA1886 +</b> <b>XP Air</b> (17801-2290)..... <b>PA1886XP +</b>	K-HT275, K-HU275 w/EK200 Eng. <b>Lube</b> (15607-1400)..... <b>P723</b> <b>Fuel</b> (23401-1090)..... <b>PF7572</b> <b>Std. Air</b> (1984-8/85) (17801-2290)..... <b>PA1886 +</b> <b>XP Air</b> (1984-8/85) (17801-2290). <b>PA1886XP +</b> <b>Air</b> (8/85-on) (17801-1020)..... <b>PA1637-FN</b>	K-KF700 w/EF350 Eng. <b>Lube</b> (15607-1560)..... <b>P7053</b> <b>Fuel</b> (23401-1080)..... <b>PF7572</b> <b>Air</b> (17801-1020)..... <b>PA1637-FN</b>
K-FN638, K-FR638, K-FS638 w/EF750 Eng. <b>Lube Ele.</b> (15607-1560)..... <b>P7053</b> <b>Fuel</b> (23401-1090)..... <b>PF7572</b> <b>Std. Air</b> (17801-2290)..... <b>PA1886 +</b> <b>XP Air</b> (17801-2290)..... <b>PA1886XP +</b>	K-HT276, K-HU276 w/EK200 Eng. <b>Lube</b> (15607-1400)..... <b>P723</b> <b>Fuel</b> (23401-1090)..... <b>PF7572</b> <b>Std. Air</b> (1984-8/85) (17801-2290)..... <b>PA1886 +</b> <b>XP Air</b> (1984-8/85) (17801-2290). <b>PA1886XP +</b> <b>Air</b> (8/85-on) (17801-1020)..... <b>PA1637-FN</b>	K-KF704 w/EF350 Eng. <b>Lube</b> (15607-1560)..... <b>P7053</b> <b>Fuel Ele.</b> (23401-1290)..... <b>PF311</b> <b>Air</b> (17801-1020)..... <b>PA1637-FN</b>
KFR608, KFS608 w/EK550 Eng. <b>Lube</b> (15607-1560)..... <b>P7053</b> <b>Std. Air</b> (17801-2290)..... <b>PA1886 +</b> <b>XP Air</b> (17801-2290)..... <b>PA1886XP +</b>	KJ300, KL300 w/EC100 Eng. <b>Lube Ele.</b> (15607-1090)..... <b>P723</b> <b>Fuel Ele.</b> (Engine) (23401-1060).. <b>PF7550</b> <b>Fuel Ele.</b> (In Tank) (23401-1290). <b>PF311</b>	K-KF724 w/EF350 Eng. <b>Lube</b> (15607-1560)..... <b>P7053</b> <b>Fuel Ele.</b> (23401-1290)..... <b>PF311</b> <b>Air</b> (17801-1020)..... <b>PA1637-FN</b>
KFR609 w/EK550 Eng. <b>Lube</b> (15607-1560)..... <b>P7053</b> <b>Std. Air</b> (17801-2290)..... <b>PA1886 +</b> <b>XP Air</b> (17801-2290)..... <b>PA1886XP +</b>	KJ500, KL500, K-KL500, LB500 w/EH100, EH300 Engs. <b>Lube Ele.</b> (15607-1090)..... <b>P723</b> <b>Fuel Ele.</b> (23401-1060)..... <b>PF7550</b> <b>Air</b> (17801-1720)..... <b>PA2961-FN</b>	K-KF747 w/EF350 Eng. <b>Lube</b> (15607-1560)..... <b>P7053</b> <b>Fuel Ele.</b> (23401-1290)..... <b>PF311</b> <b>Air</b> (17801-1020)..... <b>PA1637-FN</b>
K-HE366 w/EF700 Eng. <b>Lube Ele.</b> (15607-1070)..... <b>P7053</b> <b>Air</b> (17801-1020)..... <b>PA1637-FN</b>	K-KB314 w/EB300 Eng. (9/79-5/81) <b>Fuel</b> (23401-1040)..... <b>PF7551<sup>90</sup></b> <b>Air</b> (17801-1020)..... <b>PA1637-FN</b>	K-KF767 w/EF350 Eng. <b>Lube</b> (15607-1560)..... <b>P7053</b> <b>Fuel Ele.</b> (23401-1290)..... <b>PF311</b> <b>Air</b> (17801-1020)..... <b>PA1637-FN</b>
K-HE526 <b>Lube</b> (1560A41010)..... <b>B2 +</b> <b>Fuel Spin-on</b> (2330D56030)..... <b>BF7967</b> <b>Air</b> (1780B44070)..... <b>PA3863</b>	K-KB324 w/EB300 Eng. (9/79-5/81) <b>Fuel</b> (23401-1040)..... <b>PF7551<sup>90</sup></b> <b>Air</b> (17801-1020)..... <b>PA1637-FN</b>	KL340 w/EC100 Eng. <b>Lube Ele.</b> (15607-1090)..... <b>P723</b> <b>Fuel Ele.</b> (Engine) (23401-1060).. <b>PF7550</b> <b>Fuel Ele.</b> (In Tank) (23401-1290). <b>PF311</b>
K-HH341 w/EF700 Eng. <b>Lube Ele.</b> (15607-1070)..... <b>P7053</b> <b>Air</b> (17801-1020)..... <b>PA1637-FN</b>	K-KB344 w/EB300 Eng. (9/79-5/81) <b>Fuel</b> (23401-1040)..... <b>PF7551<sup>90</sup></b> <b>Air</b> (17801-1020)..... <b>PA1637-FN</b>	KL505, K-KL505 w/EH700 Eng. <b>Lube Ele.</b> (15607-1090)..... <b>P723</b> <b>Fuel Ele.</b> (23401-1060)..... <b>PF7550</b> <b>Air</b> (17801-1720)..... <b>PA2961-FN</b>
K-HT223 w/M10U Eng. <b>Lube</b> (15607-1400)..... <b>P723</b> <b>Fuel</b> (23401-1090)..... <b>PF7572</b> <b>Air</b> (17801-2280)..... <b>PA2779</b>	K-KB384 w/EB300 Eng. (9/79-5/81) <b>Fuel</b> (23401-1040)..... <b>PF7551<sup>90</sup></b> <b>Air</b> (17801-1020)..... <b>PA1637-FN</b>	KL580 w/EC100 Eng. <b>Lube Ele.</b> (15607-1090)..... <b>P723</b> <b>Fuel Ele.</b> (23401-1060)..... <b>PF7550</b>
K-HT223, K-HU223 w/ER200 Eng. <b>Lube</b> (15607-1400)..... <b>P723</b> <b>Fuel</b> (23401-1090)..... <b>PF7572</b> <b>Air</b> (17801-1150)..... <b>PA1750-FN</b>	K-KB394 w/EB300 Eng. (9/79-5/81) <b>Fuel</b> (23401-1040)..... <b>PF7551<sup>90</sup></b> <b>Air</b> (17801-1020)..... <b>PA1637-FN</b>	KR305 w/EH700 Eng. <b>Lube Ele.</b> (15607-1090)..... <b>P723</b> <b>Fuel Ele.</b> (23401-1060)..... <b>PF7550</b> <b>Air</b> (17801-1720)..... <b>PA2961-FN</b>
K-HT225 w/M10U Eng. <b>Lube</b> (15607-1400)..... <b>P723</b> <b>Fuel</b> (23401-1090)..... <b>PF7572</b> <b>Air</b> (17801-2280)..... <b>PA2779</b>	KB501, K-KB501 w/EK100 Eng. (1979-on) <b>Lube</b> (15607-1010)..... <b>P7127</b> <b>Lube</b> (15607-1090)..... <b>P723</b> <b>Fuel Ele.</b> (23401-1030A)..... <b>PF311</b> <b>Air</b> (17801-1020)..... <b>PA1637-FN</b>	KR360E w/EC300 Eng. <b>Lube Ele.</b> (15607-1090)..... <b>P723</b> <b>Fuel Ele.</b> (23401-1060)..... <b>PF7550</b> <b>Air</b> (17801-1720)..... <b>PA2961-FN</b>
K-HT225, K-HU225 w/ER200 Eng. <b>Lube</b> (15607-1400)..... <b>P723</b> <b>Fuel</b> (23401-1090)..... <b>PF7572</b> <b>Air</b> (17801-1150)..... <b>PA1750-FN</b>	K-KB721.980 w/EB300 Eng. (1980-5/81) <b>Fuel</b> (23401-1040)..... <b>PF7551<sup>90</sup></b> <b>Air</b> (17801-1020)..... <b>PA1637-FN</b>	K-RC301, RC301 w/ER200 Eng. <b>Lube Ele.</b> (15607-1010)..... <b>P7127</b> <b>Lube Ele.</b> (15607-1040)..... <b>P723</b> <b>Fuel Ele.</b> (23401-1090)..... <b>PF7572</b> <b>Air</b> (17801-1150)..... <b>PA1750-FN</b>
		K-RC321, RC321 w/ER200 Eng. <b>Lube Ele.</b> (15607-1010)..... <b>P7127</b> <b>Lube Ele.</b> (15607-1040)..... <b>P723</b> <b>Fuel Ele.</b> (23401-1090)..... <b>PF7572</b> <b>Air</b> (17801-1150)..... <b>PA1750-FN</b>

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.


Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

HINO Trucks (cont'd)	HINO Trucks (cont'd)	HINO Trucks (cont'd)
K-RC701 w/EK200 Eng. Lube (15607-1040)..... P723 Fuel (23401-1090)..... PF7572 Air (17801-1020)..... PA1637-FN	K-RT226 w/EM100 Eng. Lube Ele. (15607-1010)..... P7127 Lube Ele. (15607-1040)..... P723 Fuel Ele. (23401-1090)..... PF7572 Air (17801-2280)..... PA2779	KS390, KS391 w/EK100 Eng. Lube (15607-1010)..... P7127 Lube (15607-1090)..... P723 Fuel Ele. (23401-1030A)..... PF311 Air (17801-1020)..... PA1637-FN
K-RC721 w/EK200 Eng. Lube (15607-1040)..... P723 Fuel (23401-1090)..... PF7572 Air (17801-1020)..... PA1637-FN	K-RU606, K-RU607 w/EF550 Eng. Lube (15607-1560)..... P7053 Fuel (23401-1090)..... PF7572 Std. Air (17801-2290)..... PA1886 + XP Air (17801-2290)..... PA1886XP +	K-SH600 w/EF550, EF700 Engs. Lube Ele. (15607-1070)..... P7053
K-RD301 w/EH700 Eng. Lube Ele. (15607-1090)..... P723 Fuel Ele. (23401-1060)..... PF7550 Air (17801-1720)..... PA2961-FN	KRU608 w/EF550 Eng. Lube (15607-1560)..... P7053 Fuel (23401-1090)..... PF7572 Std. Air (17801-2290)..... PA1886 + XP Air (17801-2290)..... PA1886XP +	K-TC582, K-TC585 w/EF500 Eng. Lube (15607-1560)..... P7053 Fuel (23401-1080)..... PF7572 Air (17801-1020)..... PA1637-FN
K-RE101 w/EB400 Eng. (1977-on) Fuel (23401-1040)..... PF7551 90 Air (17801-1150)..... PA1750-FN	K-RU638 w/EF550 Eng. Lube (15607-1560)..... P7053 Fuel (23401-1090)..... PF7572 Std. Air (17801-2290)..... PA1886 + XP Air (17801-2290)..... PA1886XP +	K-TC703 w/EF350 Eng. Lube (15607-1560)..... P7053 Fuel (23401-1080)..... PF7572 Air (17801-1020)..... PA1637-FN
K-RS121, K-RS121P w/EF350 Eng. Lube (15607-1560)..... P7053 Fuel (23401-1090)..... PF7572 Air (17801-1020)..... PA1637-FN	K-RU636, K-RU637 w/EF550 Eng. Lube (15607-1560)..... P7053 Fuel (23401-1090)..... PF7572 Std. Air (17801-2290)..... PA1886 + XP Air (17801-2290)..... PA1886XP +	K-TC922 w/EK100 Eng. Lube (15607-1010)..... P7127 Lube (15607-1090)..... P723 Fuel Ele. (23401-1030)..... PF311 Air (17801-1020)..... PA1637-FN
K-RS141, K-RS141P w/EF350 Eng. Lube (15607-1560)..... P7053 Fuel (23401-1090)..... PF7572 Air (17801-1020)..... PA1637-FN	K-RV531 w/EF500 Eng. (1979-on) Lube (15607-1560)..... P7053 Fuel (23401-1080)..... PF7572 Air (17801-1020)..... PA1637-FN	K-TC942 w/EK100 Eng. Lube (15607-1010)..... P7127 Lube (15607-1090)..... P723 Fuel Ele. (23401-1030)..... PF311 Air (17801-1020)..... PA1637-FN
K-RS161, K-RS161P w/EF350 Eng. Lube (15607-1560)..... P7053 Fuel (23401-1090)..... PF7572 Air (17801-1020)..... PA1637-FN	K-RV561 w/EF500 Eng. (1979-on) Lube (15607-1560)..... P7053 Fuel (23401-1080)..... PF7572 Air (17801-1020)..... PA1637-FN	KU581 w/EH300 Eng. Lube Ele. (15607-1090)..... P723 Fuel Ele. (23401-1060)..... PF7550 Air (17801-1720)..... PA2961-FN
K-RS320, K-RS320P w/EF500 Eng. Lube (15607-1560)..... P7053 Fuel (23401-1090)..... PF7572 Air (17801-1020)..... PA1637-FN	K-RV731 w/EF350 Eng. Lube (15607-1560)..... P7053 Air (17801-1020)..... PA1637-FN	K-ZC101 w/EK100 Eng. Lube (15607-1010)..... P7127 Lube (15607-1521)..... P723 Fuel Ele. (23401-1030)..... PF311 Air (17801-1020)..... PA1637-FN
K-RS340 w/EF500 Eng. Lube (15607-1560)..... P7053 Fuel (23401-1090)..... PF7572 Air (17801-1020)..... PA1637-FN	K-RV732 w/EF350 Eng. Lube (15607-1560)..... P7053 Fuel (23401-1080)..... PF7572 Air (17801-1020)..... PA1637-FN	K-ZC121 w/EK100 Eng. Lube (15607-1010)..... P7127 Lube (15607-1521)..... P723 Fuel Ele. (23401-1030)..... PF311 Air (17801-1020)..... PA1637-FN
K-RS360, K-RS360P w/EF500 Eng. Lube (15607-1560)..... P7053 Fuel (23401-1090)..... PF7572 Air (17801-1020)..... PA1637-FN	K-RV741 w/EF350 Eng. Lube (15607-1560)..... P7053 Air (17801-1020)..... PA1637-FN	K-ZC210 w/EK100 Eng. F-F Lube Ele. (15607-1560)..... P7053 B-P Lube Ele. (15607-2160)..... P7185 Fuel (23401-1080)..... PF7572 Std. Air (17801-2290)..... PA1886 + XP Air (17801-2290)..... PA1886XP +
K-SH630, K-SS630 w/EF550, EF700 Engs. Lube Ele. (15607-1070)..... P7053 Air (17801-2020)..... LL1886 +	K-RV742 w/EF350 Eng. Lube (15607-1560)..... P7053 Fuel (23401-1080)..... PF7572 Air (17801-1020)..... PA1637-FN	K-ZM302 w/EK100 Eng. Lube (15607-1010)..... P7127 Lube (15607-1090)..... P723 Fuel Ele. (23401-1030)..... PF311 Air (17801-1020)..... PA1637-FN
K-RT223, K-RU223 w/EM100 Eng. Lube Ele. (15607-1010)..... P7127 Lube Ele. (15607-1040)..... P723 Fuel Ele. (23401-1090)..... PF7572 Air (17801-2280)..... PA2779	K-RV761 w/EF350 Eng. Lube (15607-1560)..... P7053 Air (17801-1020)..... PA1637-FN	K-ZM303, ZM303 w/EK100 Eng. Lube (15607-1010)..... P7127 Lube (15607-1090)..... P723 Fuel Ele. (23401-1030)..... PF311 Air (17801-1020)..... PA1637-FN
K-RT225 w/EM100 Eng. Lube Ele. (15607-1010)..... P7127 Lube Ele. (15607-1040)..... P723 Fuel Ele. (23401-1090)..... PF7572 Air (17801-2280)..... PA2779	K-KS341, KS341 w/EK100 Eng. Lube (15607-1010)..... P7127 Lube (15607-1090)..... P723 Fuel Ele. (23401-1030A)..... PF311 Air (17801-1020)..... PA1637-FN	

+ See Product Guide for Variations of This Number. 90 Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

HINO Trucks (cont'd)	HINO Trucks (cont'd)	HINO Trucks (cont'd)
K-ZM500 w/EF500 Eng. Lube (15607-1560)..... P7053 Fuel (23401-1080)..... PF7572 Air (17801-1020)..... PA1637-FN	LB560 w/EH300 Eng. Lube Ele. (15607-1090)..... P723 Fuel Ele. (23401-1060)..... PF7550 Air (17801-1720)..... PA2961-FN	Ranger Pro GH w/J08C Eng. Lube (156072051)..... B7155 O. Air (178012280)..... PA2779 I. Air (178012840M)..... PA2545
K-ZM540 w/EF500 Eng. Lube (15607-1560)..... P7053 Fuel (23401-1090)..... PF7572 Air (17801-1020)..... PA1637-FN	LB595 w/EH100 Eng. Lube Ele. (15607-1090)..... P723 Fuel Ele. (23401-1060)..... PF7550	Ranger Pro GT w/J08C Eng. Lube (156072051)..... B7155 O. Air (178012280M)..... PA2779 I. Air (178012840M)..... PA2545
K-ZM560 w/EF500 Eng. Lube (15607-1560)..... P7053 Fuel (23401-1090)..... PF7572 Air (17801-1020)..... PA1637-FN	P-CG277 w/EK200 Eng. Lube (15607-1560)..... P7053 Fuel (23401-1090)..... PF7572 Std. Air (17801-2290)..... PA1886 + XP Air (17801-2290)..... PA1886XP +	RC300 w/DK20 Eng. (1969-79) Fuel (23401-1040)..... PF7551 <sup>90</sup>
K-ZM704 w/EF300 Eng. Lube (15607-1010)..... P7127 Fuel Ele. (23401-1030)..... PF311 Air (17801-1020)..... PA1637-FN	P-FH272 w/EK100 Eng. Lube (15607-1560)..... P7053 Fuel (23401-1080)..... PF7572 16 1/2 In. Std. Air (17801-2290)..... PA1886 + 16 1/2 In. XP Air (17801-2290)..... PA1886XP + 19 1/2 In. Std. Air (17801-2170)..... PA2676 + 19 1/2 In. XP Air (17801-2170)..... PA2676XP +	TC301 w/DK10 Eng. (1969-73) Fuel (23401-1040)..... PF7551 <sup>90</sup>
K-ZM705 w/EF350 Eng. Lube (15607-1560)..... P7053 Fuel (23401-1080)..... PF7572 Air (17801-1020)..... PA1637-FN	P-FN334, P-FR334, P-FS334, P-FN336, P-FR336, P-FS336, P-FN338, P-FR338, P-FS338 w/K13C-T Eng. Lube (15607-1560)..... P7053	RC320, RC320P w/DK20 Eng. (1969-79) Fuel (23401-1040)..... PF7551 <sup>90</sup>
KZM706 w/EF350 Eng. Lube (15607-1560)..... P7053 Fuel (23401-1080)..... PF7572 Air (17801-1020)..... PA1637-FN	P-KK196 w/H06C-T Eng. Lube Ele..... P7106 Fuel Ele..... PF311 Air..... PA2779	RD100 w/DS70 Eng. (1970-76) Fuel (23401-1040)..... PF7551 <sup>90</sup>
K-ZM744 w/EF300 Eng. Lube (15607-1010)..... P7127 Fuel Ele. (23401-1030)..... PF311 Air (17801-1020)..... PA1637-FN	P-KK198, P-KK199 w/H06T-C Eng. Lube Ele..... P7106 Fuel Ele..... PF311 Air..... PA2779	RD120 w/DS70 Eng. (1970-76) Fuel (23401-1040)..... PF7551 <sup>90</sup>
K-ZM745 w/EF350 Eng. Lube (15607-1560)..... P7053 Fuel (23401-1090)..... PF7572 Air (17801-1020)..... PA1637-FN	P-RR192, P-RU192 w/H06C-T Eng. Dual-Flow Lube..... BD7105 Fuel Spin-on (23401-1410)..... BF7967 Air (17801-2280)..... PA2779	RE100 w/EB200 Eng. (1967-77) Fuel (23401-1040)..... PF7551 <sup>90</sup>
K-ZM764 w/EF300 Eng. Lube (15607-1010)..... P7127 Fuel Ele. (23401-1030)..... PF311 Air (17801-1020)..... PA1637-FN	Ranger Pro FD w/J08C Eng. Lube (156072051)..... B7155 O. Air (178012280)..... PA2779 I. Air (178012840M)..... PA2545	RE101 w/EB400 Eng. (1977-on) Fuel (23401-1040)..... PF7551 <sup>90</sup> Air (17801-1150)..... PA1750-FN
K-ZM765 w/EF350 Eng. Lube (15607-1560)..... P7053 Fuel (23401-1090)..... PF7572 Air (17801-1020)..... PA1637-FN	Ranger Pro FG w/J08C Eng. Lube (156072051)..... B7155 O. Air (178012280)..... PA2779 I. Air (178012840M)..... PA2545	RE120 w/EB200 Eng. (1967-77) Fuel (23401-1040)..... PF7551 <sup>90</sup>
K-ZM785 w/EF350 Eng. Lube (15607-1560)..... P7053 Fuel (23401-1090)..... PF7572 Air (17801-1020)..... PA1637-FN	Ranger Pro FL w/J08C Eng. Lube (156072051)..... B7155	RE121 w/EB400 Eng. (1977-on) Fuel (23401-1040)..... PF7551 <sup>90</sup> Air (17801-1150)..... PA1750-FN
K-ZM940 w/EF700T Eng. Lube (15607-1560)..... P7053 Fuel (23401-1090)..... PF7572 Std. Air (17801-2290)..... PA1886 + XP Air (17801-2290)..... PA1886XP +	Ranger Pro FM w/J08C Eng. Lube (156072051)..... B7155 O. Air (178012280)..... PA2779 I. Air (178012840M)..... PA2545	RE140 w/EB200 Eng. (1967-77) Fuel (23401-1040)..... PF7551 <sup>90</sup>
KB500 w/ED100 Eng. (7174-2176) Fuel (23401-1040)..... PF7551 <sup>90</sup>	Ranger Pro GD w/J08C Eng. Lube (156072051)..... B7155 O. Air (178012280)..... PA2779 I. Air (178012840M)..... PA2545	RE141 w/EB400 Eng. (1977-on) Fuel (23401-1040)..... PF7551 <sup>90</sup> Air (17801-1150)..... PA1750-FN
LB520 w/EH300 Eng. Lube Ele. (15607-1090)..... P723 Fuel Ele. (23401-1060)..... PF7550 Air (17801-1720)..... PA2961-FN		RL100 w/EC100 Eng. Lube Ele. (15607-1090)..... P723 Fuel Ele. (23401-1060)..... PF7550

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.




**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

**Trucks & Buses Applications** **BALDWIN FILTERS**

<b>HINO Trucks (cont'd)</b>	<b>HINO Trucks (cont'd)</b>	<b>HINO Trucks (cont'd)</b>
RV100P w/EA100 Eng. (1969-72) Lube (15607-1090)..... <b>P723</b> Fuel (23401-1040)..... <b>PF7551</b> <sup>90</sup>	SF17 w/H07C (6.7L) Eng. (1988-91) Lube (15607-1740)..... <b>B7005</b> Fuel (By Fuel Tank) (23501-1010)..... <b>BF984</b> Fuel (By Engine) (23401-1402).... <b>BF957</b> + O. Air (17801-2480)..... <b>PA2688</b> I. Air (17801-2460)..... <b>PA2621</b> Coolant (16304-1011)..... <b>BW5139</b> Trans. (34926-1041)..... <b>BT230</b> +	SG2J w/J08C Eng. (1998-2003) (Cont'd) Fuel/Water Separator (w/Drain) (234011440)..... <b>BF1223</b> Fuel/Water Separator (w/Drain) (234011440)..... <b>BF1223</b> Fuel/Water Separator (w/Drain & Sensor Port) (234011440)..... <b>BF1223-SP</b> Fuel/Water Separator (w/Drain & Sensor Port) (234011440)..... <b>BF1223-SP</b> Fuel/Water Separator (Open End for Bowl) (234011440)..... <b>BF1223-O</b> Fuel/Water Separator (Open End for Bowl) (234011440)..... <b>BF1223-O</b> Fuel (1998-2002) (234011402A).. <b>BF948</b> Fuel (1998-2002) (234011402A).. <b>FF922</b> Fuel (1998-2002) (234011402).... <b>BF957</b> + Fuel (2003) (234011510A)..... <b>BF967</b> Air (178012810A)..... <b>PA3600</b> Air (178012810)..... <b>PA3600</b> Trans. (1998-2001) (349261041). <b>BT230</b> +
RV531 w/EF500 Eng. (1978-79) Lube (15607-1010)..... <b>P7127</b> Lube (15607-1090)..... <b>P723</b> Fuel (23401-1080)..... <b>PF7572</b> Air (17801-1020)..... <b>PA1637-FN</b>	SG1H w/H06C Eng. (1993-97) F-F Lube (156071740)..... <b>B7005</b> B-P Lube (156071860)..... <b>B7124</b> Fuel (By Fuel Tank) (235011010). <b>BF984</b> Fuel (By Engine) (234011402).... <b>BF957</b> + Air (178012810)..... <b>PA3600</b> Trans. (349261041)..... <b>BT230</b> +	SG4H w/H06C Eng. (1993-97) F-F Lube (156071740)..... <b>B7005</b> B-P Lube (156071860)..... <b>B7124</b> Fuel (By Fuel Tank) (235011010). <b>BF984</b> Fuel (By Engine) (234011402).... <b>BF957</b> + Air (178012810)..... <b>PA3600</b> Trans. (349261041)..... <b>BT230</b> +
RV541 w/EF500 Eng. (1978-79) Lube (15607-1010)..... <b>P7127</b> Lube (15607-1090)..... <b>P723</b> Fuel (23401-1080)..... <b>PF7572</b> Air (17801-1020)..... <b>PA1637-FN</b>	SG1HD w/H06C Eng. (1993-97) F-F Lube (156071740)..... <b>B7005</b> B-P Lube (156071860)..... <b>B7124</b> Fuel (By Fuel Tank) (235011010). <b>BF984</b> Fuel (By Engine) (234011402).... <b>BF957</b> + Air (178012810)..... <b>PA3600</b> Trans. (349261041)..... <b>BT230</b> +	SG19 w/H06C-T (6.5L) Eng. (1986-89) F-F Lube (156071740)..... <b>B7005</b> 5 3/8 In. B-P Lube (15607-1471).. <b>B50</b> + 5 7/8 In. B-P Lube (156071860)... <b>B7124</b> Fuel (By Fuel Tank) (235011010). <b>BF984</b> Fuel (By Engine) (234011402).... <b>BF957</b> + O. Air (178012480)..... <b>PA2688</b> I. Air (178012460)..... <b>PA2621</b> Trans. (349261041)..... <b>BT230</b> +
RV561 w/EF500 Eng. (1978-79) Lube (15607-1010)..... <b>P7127</b> Lube (15607-1090)..... <b>P723</b> Fuel (23401-1080)..... <b>PF7572</b> Air (17801-1020)..... <b>PA1637-FN</b>	SG1J w/J08C Eng. (1998-2003) Lube (156072170)..... <b>B7155</b> Fuel/Water Separator (w/o Drain or Sensor Port) (234011440)..... <b>BF1224</b> Fuel/Water Separator (w/Drain) (234011440)..... <b>BF1223</b> Fuel/Water Separator (w/Drain & Sensor Port) (234011440)..... <b>BF1223-SP</b> Fuel/Water Separator (Open End for Bowl) (234011440)..... <b>BF1223-O</b> Fuel (1998-2002) (234011402).... <b>BF957</b> + Fuel (2003) (234011510A)..... <b>BF967</b> Air (178012810)..... <b>PA3600</b> Trans. (1998-2001) (349261041). <b>BT230</b> +	SG19 w/H06C-TJ (6.5L) Eng. (1990-92) F-F Lube (156071740)..... <b>B7005</b> 5 3/8 In. B-P Lube (15607-1471).. <b>B50</b> + 5 7/8 In. B-P Lube (156071860)... <b>B7124</b> Fuel (By Fuel Tank) (235011010). <b>BF984</b> Fuel (By Engine) (234011402).... <b>BF957</b> + O. Air (178012480)..... <b>PA2688</b> I. Air (178012460)..... <b>PA2621</b> Trans. (349261041)..... <b>BT230</b> +
RV731 w/EF300 Eng. (1978-79) Lube (15607-1010)..... <b>P7127</b> Lube (15607-1090)..... <b>P723</b> Fuel (23401-1080)..... <b>PF7572</b> Air (17801-1020)..... <b>PA1637-FN</b>	SG1J w/J08C Eng. (2004) Lube (156072170)..... <b>B7155</b> Fuel/Water Separator (w/o Heater) (234011700)..... <b>BF1360</b> Fuel (234011510A)..... <b>BF967</b> Air (178012810)..... <b>PA3600</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2</b> + Trans. Ele. (2 In. Kit) (Allison 29526899)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29526898)..... <b>PT9415-MPG KIT</b> Trans. Pan-Type (Allison 29538489)..... <b>19739</b> +	SG20 w/H06C (6.5L) Eng. (1992) F-F Lube (15607-1740)..... <b>B7005</b> B-P Lube (15607-1860)..... <b>B7124</b> Fuel (By Fuel Tank) (23501-1010)..... <b>BF984</b> Fuel (By Engine) (23401-1400).... <b>BF957</b> + Air (17801-2810)..... <b>PA3600</b> Trans. (34926-1041)..... <b>BT230</b> +
RV741 w/EF300 Eng. (1978-79) Lube (15607-1010)..... <b>P7127</b> Lube (15607-1090)..... <b>P723</b> Fuel (23401-1080)..... <b>PF7572</b> Air (17801-1020)..... <b>PA1637-FN</b>	SG2J w/J08C Eng. (1998-2003) Lube (156072170)..... <b>B7155</b> Fuel/Water Separator (w/o Drain or Sensor Port) (234011440)..... <b>BF1224</b> Fuel/Water Separator (w/o Drain or Sensor Port) (234011440)..... <b>BF1224</b>	SG22 w/EM100 Eng. F-F Lube (15607-1740)..... <b>B7005</b> B-P Lube (15607-1760)..... <b>B7577</b> Fuel (By Fuel Tank) (23501-1010)..... <b>BF984</b>
RV761 w/EF300 Eng. (1978-79) Lube (15607-1010)..... <b>P7127</b> Lube (15607-1090)..... <b>P723</b> Fuel (23401-1080)..... <b>PF7572</b> Air (17801-1020)..... <b>PA1637-FN</b>		
Serie 300 414/614 w/N04C-TU Diesel Eng. Mexico Fuel (23355-78020)..... <b>PF9897</b>		
Serie 300 616/716/816 w/N04C-TU Diesel Eng. Mexico Fuel (23355-78020)..... <b>PF9897</b>		
Serie 500 (1018, 1524, 1724, 1727) w/6 Cyl. Toyota Eng. Mexico Lube (S1560-72051)..... <b>B7155</b> Fuel (23355-78020)..... <b>PF9897</b> Fuel (S2340-11740)..... <b>PF9897</b>		
SF17 w/H06C-T (6.5L) Eng. Lube (156071740A)..... <b>B7005</b> Fuel (By Fuel Tank) (235011010A)..... <b>BF984</b> Fuel (By Engine) (234011402A)... <b>BF948</b> + O. Air (178012480A)..... <b>PA2688</b> I. Air (178012460A)..... <b>PA2621</b> Trans. (349261041A)..... <b>BT230</b> +		

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



HINO Trucks (cont'd)	HINO Trucks (cont'd)	HINO Trucks (cont'd)
SG22 w/EM100 Eng. (Cont'd)	SG231 w/H06C-TM (6.5L) Eng. (1992) (Cont'd)	SG3323 w/H06C-TM (6.5L) Eng. (1993-94)
Fuel (By Engine) (23401-1400).... <b>BF957 +</b>	Trans. (349261041A)..... <b>BT230 +</b>	F-F Lube (15607-1740)..... <b>B7005</b>
O. Air (17801-2480)..... <b>PA2688</b>	SG3320 w/H06C-TN (6.5L) Eng. (1993-94)	B-P Lube (15607-1860)..... <b>B7124</b>
I. Air (17801-2460)..... <b>PA2621</b>	F-F Lube (156071740)..... <b>B7005</b>	Fuel (By Fuel Tank)
Coolant (16304-1011)..... <b>BW5139</b>	B-P Lube (156071860)..... <b>B7124</b>	(23501-1010)..... <b>BF984</b>
Trans. (34926-1041)..... <b>BT230 +</b>	Fuel (By Fuel Tank) (235011010)..... <b>BF984</b>	Fuel (By Engine) (234011402)..... <b>BF957 +</b>
SG23 w/H06C-T (6.5L) Eng. (1987-89)	Fuel (By Engine) (234011402)..... <b>BF957 +</b>	Air (17801-2810)..... <b>PA3600</b>
F-F Lube (156071740)..... <b>B7005</b>	Air (178012810)..... <b>PA3600</b>	Trans. (349261041)..... <b>BT230 +</b>
B-P Lube (156071860)..... <b>B7124</b>	Trans. (349261041)..... <b>BT230 +</b>	SG3323 w/H06C-TV (6.5L) Eng. (1995-97)
Fuel (Fuel Tank) (235011010A).... <b>BF984</b>	SG3320 w/H06C-TU (6.5L) Eng. (1995-97)	F-F Lube (15607-1740)..... <b>B7005</b>
Fuel (Engine) (234011402A)..... <b>BF948 +</b>	F-F Lube (156071740)..... <b>B7005</b>	B-P Lube (15607-1860)..... <b>B7124</b>
O. Air (178012480A)..... <b>PA2688</b>	B-P Lube (156071860)..... <b>B7124</b>	Fuel (By Fuel Tank)
I. Air (178012460A)..... <b>PA2621</b>	Fuel (By Fuel Tank) (235011010)..... <b>BF984</b>	(23501-1010)..... <b>BF984</b>
SG23 w/H06C-TI (6.5L) Eng. (1990-91)	Fuel (By Engine) (234011402)..... <b>BF957 +</b>	Fuel (By Engine) (234011402)..... <b>BF957 +</b>
F-F Lube (156071740)..... <b>B7005</b>	Air (178012810)..... <b>PA3600</b>	Air (17801-2810)..... <b>PA3600</b>
B-P Lube (156071860)..... <b>B7124</b>	Trans. (349261041)..... <b>BT230 +</b>	Trans. (349261041)..... <b>BT230 +</b>
Fuel (Fuel Tank) (235011010A).... <b>BF984</b>	SG3320 w/J08C-TD (8.0L) Eng. (1998)	SG3325 w/J08C-TD (8.0L) Eng. (1998)
Fuel (Engine) (234011402A)..... <b>BF948 +</b>	Lube (156072170)..... <b>B7155</b>	Lube (156072170)..... <b>B7155</b>
O. Air (178012480A)..... <b>PA2688</b>	Fuel/Water Separator (w/o Drain	Fuel/Water Separator (w/o Drain
I. Air (178012460A)..... <b>PA2621</b>	or Sensor Port) (234011440)..... <b>BF1224</b>	or Sensor Port) (234011440)..... <b>BF1224</b>
SG23 w/H06C-TM (6.5L) Eng. (1992)	Fuel/Water Separator (w/Drain)	Fuel/Water Separator (w/Drain)
F-F Lube (156071740)..... <b>B7005</b>	(234011440)..... <b>BF1223</b>	(234011440)..... <b>BF1223</b>
5 3/8 In. B-P Lube (15607-1471).. <b>B50 +</b>	Fuel/Water Separator (w/Drain &	Fuel/Water Separator (w/Drain &
5 7/8 In. B-P Lube (15607-1860).. <b>B7124</b>	Sensor Port) (234011440)..... <b>BF1223-SP</b>	Sensor Port) (234011440)..... <b>BF1223-SP</b>
Fuel (By Fuel Tank)	Fuel/Water Separator (Open End	Fuel/Water Separator (Open End
(23501-1010)..... <b>BF984</b>	for Bowl) (234011440)..... <b>BF1223-O</b>	for Bowl) (234011440)..... <b>BF1223-O</b>
Fuel (By Engine) (23401-1402).... <b>BF957 +</b>	Fuel (234011402)..... <b>BF957 +</b>	Fuel (234011402)..... <b>BF957 +</b>
Single Air (17801-2810)..... <b>PA3600</b>	Air (17801-2810)..... <b>PA3600</b>	Air (178012810)..... <b>PA3600</b>
O. Air (17801-2480)..... <b>PA2688</b>	Trans. (349261041)..... <b>BT230 +</b>	Trans. (349261041)..... <b>BT230 +</b>
I. Air (17801-2460)..... <b>PA2621</b>	SG3320 w/J08C-TP (8.0L) Eng. (1999-2001)	SG3325 w/J08C-TP (8.0L) Eng. (1999)
Coolant (16304-1011)..... <b>BW5139</b>	Lube (156072170)..... <b>B7155</b>	Lube (156072170)..... <b>B7155</b>
Trans. (34926-1041)..... <b>BT230 +</b>	Fuel/Water Separator (w/o Drain	Fuel/Water Separator (w/o Drain
SG231 w/H06C-T (6.5L) Eng. (1989)	or Sensor Port) (234011440)..... <b>BF1224</b>	or Sensor Port) (234011440)..... <b>BF1224</b>
F-F Lube (156071740A)..... <b>B7005</b>	Fuel/Water Separator (w/Drain)	Fuel/Water Separator (w/Drain)
B-P Eng. Lube (156071860A)..... <b>B7124</b>	(234011440)..... <b>BF1223</b>	(234011440)..... <b>BF1223</b>
Fuel (By Fuel Tank)	Fuel/Water Separator (w/Drain &	Fuel/Water Separator (w/Drain &
(235011010A)..... <b>BF984</b>	Sensor Port) (234011440)..... <b>BF1223-SP</b>	Sensor Port) (234011440)..... <b>BF1223-SP</b>
Fuel (By Engine) (234011402A).... <b>BF948 +</b>	Fuel/Water Separator (Open End	Fuel/Water Separator (Open End
O. Air (178012480A)..... <b>PA2688</b>	for Bowl) (234011440)..... <b>BF1223-O</b>	for Bowl) (234011440)..... <b>BF1223-O</b>
I. Air (178012460A)..... <b>PA2621</b>	Fuel (234011402)..... <b>BF957 +</b>	Fuel (234011402)..... <b>BF957 +</b>
Trans. (349261041A)..... <b>BT230 +</b>	Air (17801-2810)..... <b>PA3600</b>	Air (178012810)..... <b>PA3600</b>
SG231 w/H06C-TI (6.5L) Eng. (1990-91)	Trans. (349261041)..... <b>BT230 +</b>	Trans. (349261041)..... <b>BT230 +</b>
F-F Lube (156071740A)..... <b>B7005</b>	SG3320 w/J08C-TP (8.0L) Eng. (2002)	SG3325 w/J08C-TR (8.0L) Eng. (2000-01)
B-P Eng. Lube (156071860A)..... <b>B7124</b>	Lube (156072170)..... <b>B7155</b>	Lube (156072170)..... <b>B7155</b>
Fuel (By Fuel Tank)	Fuel (234011402)..... <b>BF957 +</b>	Fuel/Water Separator (w/o Drain
(235011010A)..... <b>BF984</b>	Air (17801-2810)..... <b>PA3600</b>	or Sensor Port) (234011440)..... <b>BF1224</b>
Fuel (By Engine) (234011402A).... <b>BF948 +</b>	SG3320 w/J08C-TP (8.0L) Eng. (2003)	Fuel/Water Separator (w/Drain)
O. Air (178012480A)..... <b>PA2688</b>	Lube (156072170)..... <b>B7155</b>	(234011440)..... <b>BF1223</b>
I. Air (178012460A)..... <b>PA2621</b>	Fuel/Water Separator (w/o Drain	Fuel/Water Separator (w/Drain &
Trans. (349261041A)..... <b>BT230 +</b>	or Sensor Port) (234011440)..... <b>BF1224</b>	Sensor Port) (234011440)..... <b>BF1223-SP</b>
SG231 w/H06C-TM (6.5L) Eng. (1992)	Fuel/Water Separator (w/Drain)	Fuel/Water Separator (Open End
F-F Lube (156071740A)..... <b>B7005</b>	(234011440)..... <b>BF1223</b>	for Bowl) (234011440)..... <b>BF1223-O</b>
B-P Eng. Lube (156071860A)..... <b>B7124</b>	Fuel/Water Separator (w/Drain &	Fuel (234011402)..... <b>BF957 +</b>
Fuel (By Fuel Tank)	Sensor Port) (234011440)..... <b>BF1223-SP</b>	Air (178012810)..... <b>PA3600</b>
(235011010A)..... <b>BF984</b>	Fuel/Water Separator (Open End	Trans. (349261041)..... <b>BT230 +</b>
Fuel (By Engine) (234011402A).... <b>BF948 +</b>	for Bowl) (234011440)..... <b>BF1223-O</b>	
O. Air (178012480A)..... <b>PA2688</b>	Fuel (234011510A)..... <b>BF7967</b>	
I. Air (178012460A)..... <b>PA2621</b>	Air (17801-2810)..... <b>PA3600</b>	
Trans. (349261041A)..... <b>BT230 +</b>		

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.




**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

**Trucks & Buses Applications** **BALDWIN FILTERS**

<b>HINO Trucks (cont'd)</b>	<b>HINO Trucks (cont'd)</b>	<b>HINO Trucks (cont'd)</b>
SG3325 w/J08C-TR (8.0L) Eng. (2002) Lube (156072170)..... <b>B7155</b> Fuel/Water Separator (w/o Drain or Sensor Port) (234011440)..... <b>BF1224</b> Fuel/Water Separator (w/Drain) (234011440)..... <b>BF1223</b> Fuel/Water Separator (w/Drain & Sensor Port) (234011440)..... <b>BF1223-SP</b> Fuel/Water Separator (Open End for Bowl) (234011440)..... <b>BF1223-O</b> Fuel (234011402)..... <b>BF957 +</b> Air (178012810)..... <b>PA3600</b>	TC921 w/ED100 Eng. (1972-75) Fuel (23401-1040)..... <b>PF7551 90</b> TE100 w/DS70 Eng. (1965-76) Fuel (23401-1040)..... <b>PF7551 90</b> UFS2K Lube (15607-1560)..... <b>P7053</b> Fuel (23401-1090)..... <b>PF7572</b> UFW2K Lube (15607-1560)..... <b>P7053</b> Fuel (23401-1090)..... <b>PF7572</b> UFN2K Lube (15607-1560)..... <b>P7053</b> Fuel (23401-1090)..... <b>PF7572</b> WB310 w/EC100 Eng. Lube Ele. (15607-1090)..... <b>P723</b> Fuel Ele. (23401-1060)..... <b>PF7550</b> K-WB311, WB311 w/EH100 Eng. Lube Ele. (15607-1090)..... <b>P723</b> Fuel Ele. (23401-1060)..... <b>PF7550</b> Air (17801-1720)..... <b>PA2961-FN</b> K-WD300D (4x4), WD300D (4x4) w/EK100 Eng. Lube (15607-1010)..... <b>P7127</b> Lube (15607-1090)..... <b>P723</b> Fuel Ele. (23401-1030A)..... <b>PF311</b> Air (17801-1020)..... <b>PA1637-FN</b> XL7 w/A09 (8.9L) Eng. (2020) Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827)..... <b>BT223</b> XL8 w/A09 (8.9L) Eng. (2020) Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827)..... <b>BT223</b> XZU307R (300 Series) w/S05C-TI Eng. Fuel (23355-78020)..... <b>PF9897</b> XZU347R (300 Series) w/S05C-TI Eng. Fuel (23355-78020)..... <b>PF9897</b> XZU407R (300 Series) w/N04C-TI Eng. Pre-Fuel (23355-78020)..... <b>PF9897</b> XZU414R (300 Series) w/S05C-TI Eng. Dual-Flow Lube (15607-1733)..... <b>BD7105</b> XZU417R (300 Series) w/N04C-TI Eng. Pre-Fuel (23355-78020)..... <b>PF9897</b> XZU424R (300 Series) w/S05C-TI Eng. Dual-Flow Lube (15607-1733)..... <b>BD7105</b> XZU427R (300 Series) w/N04C-TI Eng. Pre-Fuel (23355-78020)..... <b>PF9897</b>	XZU434R (300 Series) w/S05C-TI Eng. Dual-Flow Lube (15607-1733)..... <b>BD7105</b> XZU437R (300 Series) w/N04C-TI Eng. Pre-Fuel (23355-78020)..... <b>PF9897</b> ZC100, ZH100 w/ED100 Eng. (1975-79) Fuel (23401-1040)..... <b>PF7551 90</b> ZC120 w/ED100 Eng. (1975-79) Fuel (23401-1040)..... <b>PF7551 90</b> ZG150 w/ED100 Eng. (1978-on) Fuel (23401-1040)..... <b>PF7551 90</b> ZH100 w/ED100 Eng. (1978-on) Fuel (23401-1040)..... <b>PF7551 90</b> ZH100D w/ED100 Eng. (1972-77) Fuel (23401-1040)..... <b>PF7551 90</b> ZH102 w/ED100 Eng. (1975-on) Fuel (23401-1040)..... <b>PF7551 90</b> ZH110D w/ED100 Eng. (1972-77) Fuel (23401-1040)..... <b>PF7551 90</b> ZM101D, ZM102D w/ED100 Eng. (1972-76) Fuel (23401-1040)..... <b>PF7551 90</b> ZM300 w/ED100 Eng. (1972-76) Fuel (23401-1040)..... <b>PF7551 90</b> ZM301 w/ED100 Eng. (1972-76) Fuel (23401-1040)..... <b>PF7551 90</b> ZM302 w/EK100 Eng. Lube (15607-1010)..... <b>P7127</b> Lube (15607-1090)..... <b>P723</b> Fuel Ele. (23401-1030)..... <b>PF311</b> Air (17801-1020)..... <b>PA1637-FN</b> ZM500 w/EF500 Eng. Lube (15607-1010)..... <b>P7127</b> Lube (15607-1090)..... <b>P723</b> Fuel (23401-1080)..... <b>PF7572</b> Air (17801-1020)..... <b>PA1637-FN</b> ZM540 w/EF500 Eng. Lube (15607-1010)..... <b>P7127</b> Lube (15607-1090)..... <b>P723</b> Fuel (23401-1080)..... <b>PF7572</b> Air (17801-1020)..... <b>PA1637-FN</b> ZM560 w/EF500 Eng. Lube (15607-1010)..... <b>P7127</b> Lube (15607-1090)..... <b>P723</b> Fuel (23401-1080)..... <b>PF7572</b> Air (17801-1020)..... <b>PA1637-FN</b> ZM704 w/EF300 Eng. Lube (15607-1010)..... <b>P7127</b> Lube (15607-1090)..... <b>P723</b> Fuel (23401-1080)..... <b>PF7572</b> Air (17801-1020)..... <b>PA1637-FN</b> ZM705 w/EF300 Eng. Lube (15607-1010)..... <b>P7127</b> Lube (15607-1090)..... <b>P723</b> Fuel (23401-1080)..... <b>PF7572</b> Air (17801-1020)..... <b>PA1637-FN</b>
SG3325 w/J08C-TR (8.0L) Eng. (2003) Lube (156072170)..... <b>B7155</b> Fuel/Water Separator (w/o Drain or Sensor Port) (234011440)..... <b>BF1224</b> Fuel/Water Separator (w/Drain) (234011440)..... <b>BF1223</b> Fuel/Water Separator (w/Drain & Sensor Port) (234011440)..... <b>BF1223-SP</b> Fuel/Water Separator (Open End for Bowl) (234011440)..... <b>BF1223-O</b> Fuel (234011510A)..... <b>BF7967</b> Air (178012810)..... <b>PA3600</b>		
SG3325 w/J08C (8.0L) Eng. (2004) Lube (156072170)..... <b>B7155</b> Fuel/Water Separator (w/o Heater) (234011700)..... <b>BF1360</b> Fuel/Water Separator (w/o Drain or Sensor Port) (234011440)..... <b>BF1224</b> Fuel/Water Separator (w/Drain) (234011440)..... <b>BF1223</b> Fuel/Water Separator (w/Drain & Sensor Port) (234011440)..... <b>BF1223-SP</b> Fuel/Water Separator (Open End for Bowl) (234011440)..... <b>BF1223-O</b> Fuel (234011510A)..... <b>BF7967</b> Air (178012810)..... <b>PA3600</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Trans. Ele. (2 In. Kit) (Allison 29526899)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29526898)..... <b>PT9415-MPG KIT</b> Trans. Pan-Type (Allison 29538489)..... <b>19739 +</b>		
SG5523 w/H06C (6.5L) Eng. (1993-97) F-F Lube (15607-1740)..... <b>B7005</b> B-P Lube (15607-1860)..... <b>B7124</b> Fuel (By Fuel Tank) (23501-1010)..... <b>BF984</b> Fuel (By Engine) (23401-1402)..... <b>BF957 +</b> Air (17801-2810)..... <b>PA3600</b> Trans. (349261041)..... <b>BT230 +</b>		
TC302 w/ED100 Eng. (1969-73) Fuel (23401-1040)..... <b>PF7551 90</b>		

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

HME Fire Truck Chassis	HME Fire Truck Chassis (cont'd)	HOLIDAY RAMBLER Motor Homes (cont'd)
1871-Classic Tilt w/Detroit Diesel Series 60 Eng. F-F Lube (To 1993) (23530407)... [2] B95 + F-F Lube (1993-on) (23530573)... [2] B495 B-P Lube (To 1993) (23530413)... B7577 P. Fuel (23530706)..... BF5800 + S. Fuel (To 12/03) (23530707)..... BF5810 S. Fuel (12/03-on) (23533726)..... BF5816 Trans. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	1871-SFO w/Cummins ISC Eng. (Cont'd) Trans. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT  <b>HODYON</b> <b>Auxiliary Power Units (APU)</b> Dynasys G1D w/Yanmar 3TVN Eng. Lube (119305-35150)..... B1400 Fuel/Water Separator (119810-55650)..... PF981 Fuel (171081-55910)..... PF7869  <b>HOLIDAY RAMBLER</b> <b>Motor Homes</b> Ambassador w/Cummins ISC Eng. (Unit number to 142831) Dual-Flow Lube (Fleetguard LF3000)..... BD103 + P. Fuel/Water Separator (w/Drain) (Fleetguard FS1242)..... BF1249 P. Fuel/Water Separator (Open End for Bowl) (Fleetguard FS1242)..... BF1249-O P. Fuel/Water Separator (w/Drain & Sensor Port) (Fleetguard FS1242)..... BF1249-SP P. Fuel/Water Separator (w/Drain & Sensor Port, High Efficiency Version) (Fleetguard FS1242)..... BF1393-SP S. Fuel/Water Separator (Fleetguard FS1022)..... BF1272-SPS Radial Seal Air (Don. P533930)... RS3548 Radial Seal XP Air (Don. P533930)..... RS3548XP Steering (Nelson 84365A)..... PT951 Ambassador w/Cummins ISC Eng. (Unit number 142831-on) Dual-Flow Lube (Fleetguard LF9009)..... BD7309 + P. Fuel/Water Separator (Fleetguard FS1003)..... BF1293-SPS S. Fuel (Fleetguard FF5488)..... BF7815 Radial Seal Air (Don. P533930)... RS3548 Radial Seal XP Air (Don. P533930)..... RS3548XP Steering (Nelson 84365A)..... PT951 Endeavor w/Cummins ISC Eng. (Unit number to 142788) Dual-Flow Lube (Fleetguard LF3000)..... BD103 + P. Fuel/Water Separator (w/Drain) (Fleetguard FS1242)..... BF1249 P. Fuel/Water Separator (Open End for Bowl) (Fleetguard FS1242)..... BF1249-O P. Fuel/Water Separator (w/Drain & Sensor Port) (Fleetguard FS1242)..... BF1249-SP P. Fuel/Water Separator (w/Drain & Sensor Port, High Efficiency Version) (Fleetguard FS1242)..... BF1393-SP S. Fuel/Water Separator (Fleetguard FS1022)..... BF1272-SPS Air (Don. P537448)..... PA2722 Coolant (Fleetguard WF2071)..... BW5071 Imperial w/Cummins ISL Eng. (Unit number 142766-on) Dual-Flow Lube (Fleetguard LF9009)..... BD7309 + P. Fuel/Water Separator (Fleetguard FS1003)..... BF1293-SPS Air (Don. P537448)..... PA2722	Endeavor w/Cummins ISC Eng. (Unit number to 142788) (Cont'd) P. Fuel/Water Separator (w/Drain & Sensor Port, High Efficiency Version) (Fleetguard FS1242)..... BF1393-SP S. Fuel/Water Separator (Fleetguard FS1022)..... BF1272-SPS Radial Seal Air (Don. P533930)... RS3548 Radial Seal XP Air (Don. P533930)..... RS3548XP Endeavor w/Cummins ISC Eng. (Unit number 142788-on) Dual-Flow Lube (Fleetguard LF9009)..... BD7309 + P. Fuel/Water Separator (Fleetguard FS1003)..... BF1293-SPS S. Fuel (Fleetguard FF5488)..... BF7815 Radial Seal Air (Don. P533930)... RS3548 Radial Seal XP Air (Don. P533930)..... RS3548XP Imperial w/Cummins ISC Eng. (Unit number to 142766) Dual-Flow Lube (Fleetguard LF3000)..... BD103 + P. Fuel/Water Separator (w/Drain) (Fleetguard FS1242)..... BF1249 P. Fuel/Water Separator (Open End for Bowl) (Fleetguard FS1242)..... BF1249-O P. Fuel/Water Separator (w/Drain & Sensor Port) (Fleetguard FS1242)..... BF1249-SP P. Fuel/Water Separator (w/Drain & Sensor Port, High Efficiency Version) (Fleetguard FS1242)..... BF1393-SP S. Fuel/Water Separator (Fleetguard FS1022)..... BF1272-SPS Air (Don. P537448)..... PA2722 Coolant (Fleetguard WF2071)..... BW5071 Imperial w/Cummins ISL Eng. (Unit number 142766-on) Dual-Flow Lube (Fleetguard LF9009)..... BD7309 + P. Fuel/Water Separator (Fleetguard FS1003)..... BF1293-SPS Air (Don. P537448)..... PA2722  <b>HUALING</b> <b>Trucks</b> Models w/280 HP Engine O. Air (K3250)..... PA5445  <b>IBEX</b> <b>Trucks</b> Models w/Cat 3208 Eng. Lube (9L9200)..... [2] BT364 Lube (9N5570)..... [2] BT230 Box-Style Fuel/Water Separator. BF912 Fuel Spin-on..... BF970 +
1871-Low Pro Tilt w/Detroit Diesel Series 60 Eng. F-F Lube (To 1993) (23530407)... [2] B95 + F-F Lube (1993-on) (23530573)... [2] B495 B-P Lube (To 1993) (23530413)... B7577 P. Fuel (23530706)..... BF5800 + S. Fuel (To 12/03) (23530707)..... BF5810 S. Fuel (12/03-on) (23533726)..... BF5816 Trans. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	1871-P w/Detroit Diesel Series 40 Eng. F-F Lube (23529744)..... B7030 Trans. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Imperial w/Cummins ISC Eng. (Unit number to 142766) Dual-Flow Lube (Fleetguard LF3000)..... BD103 + P. Fuel/Water Separator (w/Drain) (Fleetguard FS1242)..... BF1249 P. Fuel/Water Separator (Open End for Bowl) (Fleetguard FS1242)..... BF1249-O P. Fuel/Water Separator (w/Drain & Sensor Port) (Fleetguard FS1242)..... BF1249-SP P. Fuel/Water Separator (w/Drain & Sensor Port, High Efficiency Version) (Fleetguard FS1242)..... BF1393-SP S. Fuel/Water Separator (Fleetguard FS1022)..... BF1272-SPS Air (Don. P537448)..... PA2722 Coolant (Fleetguard WF2071)..... BW5071
1871-P2 w/Cummins ISC Eng. Dual-Flow Lube (Fleetguard LF9009)..... BD7309 + Fuel (3959612)..... BF7815 Trans. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	1871-P2 w/Cummins ISC Eng. Dual-Flow Lube (Fleetguard LF9009)..... BD7309 + P. Fuel/Water Separator (Fleetguard FS1003)..... BF1293-SPS S. Fuel (Fleetguard FF5488)..... BF7815 Radial Seal Air (Don. P533930)... RS3548 Radial Seal XP Air (Don. P533930)..... RS3548XP Steering (Nelson 84365A)..... PT951	Imperial w/Cummins ISL Eng. (Unit number 142766-on) Dual-Flow Lube (Fleetguard LF9009)..... BD7309 + P. Fuel/Water Separator (Fleetguard FS1003)..... BF1293-SPS Air (Don. P537448)..... PA2722
1871-Series w/Cummins M11 Eng. Dual-Flow Lube..... BD103 + Trans. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	1871-Series w/Cummins M11 Eng. Dual-Flow Lube..... BD103 + Trans. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Imperial w/Cummins ISL Eng. (Unit number 142766-on) Dual-Flow Lube (Fleetguard LF9009)..... BD7309 + P. Fuel/Water Separator (Fleetguard FS1003)..... BF1293-SPS Air (Don. P537448)..... PA2722
1871-Series w/Detroit Diesel Series 60 Eng. F-F Lube (To 1993) (23530407)... [2] B95 + F-F Lube (1993-on) (23530573)... [2] B495 B-P Lube (To 1993) (23530413)... B7577 P. Fuel (23530706)..... BF5800 + S. Fuel (To 12/03) (23530707)..... BF5810 S. Fuel (12/03-on) (23533726)..... BF5816 Trans. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	1871-Series w/Detroit Diesel Series 60 Eng. F-F Lube (To 1993) (23530407)... [2] B95 + F-F Lube (1993-on) (23530573)... [2] B495 B-P Lube (To 1993) (23530413)... B7577 P. Fuel (23530706)..... BF5800 + S. Fuel (To 12/03) (23530707)..... BF5810 S. Fuel (12/03-on) (23533726)..... BF5816 Trans. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Imperial w/Cummins ISL Eng. (Unit number 142766-on) Dual-Flow Lube (Fleetguard LF9009)..... BD7309 + P. Fuel/Water Separator (Fleetguard FS1003)..... BF1293-SPS Air (Don. P537448)..... PA2722
1871-SFO w/Cummins ISC Eng. Dual-Flow Lube (Fleetguard LF9009)..... BD7309 + Fuel (3959612)..... BF7815	1871-SFO w/Cummins ISC Eng. (Unit number to 142788) Dual-Flow Lube (Fleetguard LF3000)..... BD103 + P. Fuel/Water Separator (w/Drain) (Fleetguard FS1242)..... BF1249 P. Fuel/Water Separator (Open End for Bowl) (Fleetguard FS1242)..... BF1249-O P. Fuel/Water Separator (w/Drain & Sensor Port) (Fleetguard FS1242)..... BF1249-SP	Imperial w/Cummins ISL Eng. (Unit number 142766-on) Dual-Flow Lube (Fleetguard LF9009)..... BD7309 + P. Fuel/Water Separator (Fleetguard FS1003)..... BF1293-SPS Air (Don. P537448)..... PA2722

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>IBEX</b> Trucks (cont'd)	<b>IC CORPORATION</b> Buses (Also see International) (cont'd)	<b>IC CORPORATION</b> Buses (Also see International) (cont'd)
Models w/Cummins Eng.	1300 FBC w/Cummins ISB (5.9L) Eng. (Cont'd)	3000IC w/DT466 (7.6L) Eng.
F-F Lube Bag..... P996	<b>Fuel/Water Separator</b>	<b>Dual-Flow Lube</b> (1842639C91)... <b>BD7250</b>
F-F Lube Ele..... P999-HD	(Fleetguard FS1065)..... <b>BF1378-SPS</b>	<b>Fuel/Water Separator Ele.</b>
F-F Lube Spin-on..... B196 +	<b>Fuel</b> (Fleetguard FF5632)..... <b>BF7940</b>	(1842638C92)..... <b>PF7779</b>
B-P Lube Ele..... C750-E +	1300 FBC w/DT466 (7.6L) Eng. (2006-15)	<b>Fuel</b> (625625C1)..... <b>BF984</b>
Fuel/Water Separator..... BF1212 +	<b>Dual-Flow Lube</b> (1842639-C91).. <b>BD7250</b>	<b>Fuel</b> (625627C1)..... <b>BF979 +</b>
Fuel Spin-on..... BF948 +	<b>Coolant</b> (4 3/8 In. (w/4 Units	<b>Coolant</b> (w/4 Units BTA+)
Fuel Spin-on..... BF957 +	BTA+)) (Fleetguard WF2071)..... <b>BW5071</b>	(Fleetguard WF2071)..... <b>BW5071</b>
Fuel Spin-on..... BF596 +	<b>Coolant</b> (5 3/8 In. (w/4 Units BTA	<b>Coolant</b> (w/12 Units BTA+)
Breather Ele. (w/Turbo) (255963) <b>PA643</b>	+)) (1822313-C1)..... <b>BW5082</b>	(1820361C1)..... <b>BW5074</b>
Breather Ele. (w/o Turbo	<b>Coolant</b> (w/12 Units BTA+)	3000IC w/DT530 (8.7L) Eng.
(256837)..... <b>PA1627</b>	(1820361-C1)..... <b>BW5074</b>	<b>F-F Lube</b> (1819452C1)..... <b>B7030</b>
<b>Turbocharger</b> ..... <b>BT112</b>	1652 SC w/T444E (7.3L) Eng.	<b>Dual-Flow Lube</b> (1842639C91)... <b>BD7250</b>
Models w/GMC 4-53 Eng.	<b>Lube</b> (1814562-C1)..... <b>B7039</b>	<b>Fuel/Water Separator Ele.</b>
<b>Lube Ele.</b> ..... <b>P20-HD +</b>	<b>Lube</b> (Fleetguard LF3344)..... <b>B134</b>	(1842638C92)..... <b>PF7779</b>
<b>P. Fuel Sock</b> ..... <b>F916-C</b>	<b>Fuel/Water Separator</b>	<b>Fuel</b> (1820479C1)..... <b>BF7531</b>
<b>P. Fuel Spin-on</b> ..... <b>BF5800 +</b>	(702255-C1)..... <b>BF891</b>	<b>Coolant</b> (1822313C1)..... <b>BW5082</b>
<b>S. Fuel Ele.</b> ..... <b>PF906</b>	<b>S. Fuel</b> (1804459-C1)..... <b>BF786</b>	3000IC w/T444E (7.3L) Eng.
<b>S. Fuel Spin-on</b> ..... <b>BF5810</b>	<b>Axial Seal Air</b> (588213-C1)..... <b>[2] PA2116</b>	<b>Lube</b> (1814562C1)..... <b>B7039</b>
Models w/GMC 6V-53 Eng.	<b>Radial Seal Air</b> (1691027-C1)..... <b>RS2863</b>	<b>3 9/16 In. Fuel</b> (1825864C92)..... <b>PF7698</b>
<b>F-F Lube Ele.</b> ..... <b>P20-HD +</b>	<b>Radial Seal XP Air</b>	<b>4 17/32 In. Fuel</b> (1822631C91)..... <b>PF7678</b>
<b>B-P Lube Ele.</b> ..... <b>P52</b>	(1691027-C1)..... <b>RS2863XP</b>	<b>Std. O. Air</b> (476741C1)..... <b>PA2521</b>
<b>P. Fuel Sock</b> ..... <b>F916-C</b>	<b>Coolant</b> (w/4 Units BTA+)	<b>Std. I. Air</b> (482644C1)..... <b>PA2522</b>
<b>P. Fuel Spin-on</b> ..... <b>BF5800 +</b>	(Fleetguard WF2071)..... <b>BW5071</b>	<b>Radial Seal Air</b> (1691027C1)..... <b>RS2863</b>
<b>S. Fuel Ele.</b> ..... <b>PF906</b>	<b>Coolant</b> (w/6 Units BTA+)	<b>Radial Seal XP Air</b> (1691027C1). <b>RS2863XP</b>
<b>S. Fuel Spin-on</b> ..... <b>BF5810</b>	(Fleetguard WF2072)..... <b>BW5072</b>	<b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b>
F2, 702 w/Ford 391 Eng.	<b>Coolant</b> (w/12 Units BTA+)	<b>3 31/32 In. Steering</b>
<b>F-F Lube Spin-on</b> ..... <b>BT251</b>	(Fleetguard WF2074)..... <b>BW5074</b>	(1691121C1)..... <b>P106-HD</b>
<b>B-P Lube Ele.</b> ..... <b>C704-L +</b>	<b>Coolant</b> (Controlled Release)	<b>5 1/32 In. Steering</b> (1695528C1).. <b>PT9419-MPG</b>
<b>Fuel</b> ..... <b>PF827</b>	(Nalcool NF2088)..... <b>BW5200</b>	3000IC w/VT365 (6.0L) Eng.
<b>IC CORPORATION</b>	<b>Trans.</b> (3.8 In. Pan) (Allison	<b>Lube</b> (w/o Screw-on Cap)
<b>Buses (Also see International)</b>	29540976)..... <b>19992 +</b>	(1844588C91)..... <b>P7235</b>
1000 SC w/T444E (7.3L) Eng.	<b>Trans.</b> (5.3 In. Pan) (Allison	<b>Lube</b> (w/Screw on Cap)..... <b>P7436</b>
<b>Lube</b> (1814562C1)..... <b>B7039</b>	29538489)..... <b>19739 +</b>	<b>Fuel Ele.</b> (1825864C92)..... <b>PF7698</b>
<b>Fuel/Water Separator</b>	<b>Trans. Spin-on</b> (595722-C91)..... <b>BT839-10</b>	3200 w/VT365 (6.0L) Eng.
(1677004C91)..... <b>BF1345-O</b>	<b>Steering</b> (2 25/32 In.)	<b>Lube</b> (w/o Screw on Cap)
<b>Fuel Ele.</b> (1825864C92)..... <b>PF7698</b>	(279294-C92)..... <b>PT903</b>	(1844588-C91)..... <b>P7235</b>
<b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b>	<b>Steering</b> (3 31/32 In.) (Fleetguard	<b>Lube</b> (w/Screw on Cap) (Wix
1300 FBC w/Cummins B6.7 (6.7L) Eng. (2018)	HF6162)..... <b>P106-HD</b>	57312)..... <b>P7436</b>
<b>Lube</b> (3937736)..... <b>B7177</b>	<b>Steering</b> (4 5/32 In.)	<b>Fuel</b> (1825864-C92)..... <b>PF7698</b>
<b>Fuel</b> (3937736)..... <b>BF63000</b>	(1681202-C91)..... <b>PT8407</b>	<b>Radial Seal O. Air</b> (3532799-C1). <b>RS4636 +</b>
<b>Fuel</b> (FF63009)..... <b>BF63000</b>	<b>Steering</b> (5 1/32 In.)	<b>Radial Seal I. Air</b> (3532800-C1)... <b>RS4637</b>
<b>Crankcase Breather</b> (4936636).. <b>CV15010</b>	(1695528-C1)..... <b>PT9419-MPG</b>	<b>Trans. Pan-Type</b> (S. Pan w/o
1300 FBC w/Cummins B6.7 (6.7L) Eng. (2019)	3000 Chassis w/DT466 (7.6L) Eng.	Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Lube</b> (3937736)..... <b>B7177</b>	<b>Dual-Flow Lube</b> (1842639C91)... <b>BD7250</b>	<b>Trans. Pan-Type</b> (S. Pan
<b>Fuel</b> (5303743)..... <b>BF63000</b>	<b>Fuel/Water Separator Ele.</b>	w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Crankcase Breather</b> (4936636).. <b>CV15010</b>	(1842638C92)..... <b>PF7779</b>	<b>Trans. Pan-Type</b> (D. Pan w/o
1300 FBC w/Cummins B6.7 (6.7L) Eng. (2020)	<b>Fuel</b> (625625C1)..... <b>BF984</b>	Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Lube</b> (3937736)..... <b>B7177</b>	<b>Fuel</b> (625627C1)..... <b>BF979 +</b>	<b>Trans. Pan-Type</b> (D. Pan
<b>Fuel</b> (5303743)..... <b>BF63000</b>	<b>Coolant</b> (w/4 Units BTA+)	w/Gskt.) (Allison 29537966)..... <b>20017</b>
<b>Crankcase Breather</b> (4936636).. <b>CV15010</b>	(Fleetguard WF2071)..... <b>BW5071</b>	<b>Trans. Spin-on</b> (Allison
1300 FBC w/Cummins ISB (5.9L) Eng.	<b>Coolant</b> (w/12 Units BTA+)	29539579)..... <b>BT8460</b>
<b>Lube</b> (3937736)..... <b>B7177</b>	(1820361C1)..... <b>BW5074</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison
<b>Lube</b> (4897898)..... <b>BT7237</b>	3000 Chassis w/VT365 (6.0L) Eng.	29540493)..... <b>PT9416-MPG KIT</b>
<b>Fuel/Water Separator</b> (3942533). <b>BF1271</b>	<b>Lube</b> (w/o Screw-on Cap)	<b>Trans. Ele.</b> (4 In. Kit) (Allison
<b>Fuel/Water Separator</b>	(1844588C91)..... <b>P7235</b>	29540494)..... <b>PT9415-MPG KIT</b>
(Fleetguard FS19596)..... <b>BF1293-SPS</b>	<b>Lube</b> (w/Screw on Cap)..... <b>P7436</b>	<b>Steering</b> (1691121-C1)..... <b>P106-HD</b>
	<b>Fuel Ele.</b> (1825864C92)..... <b>PF7698</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IC CORPORATION Buses (Also see International) (cont'd)	IC CORPORATION Buses (Also see International) (cont'd)	IC CORPORATION Buses (Also see International) (cont'd)
3300 Chassis w/DT466 (7.6L) Eng. <b>Dual-Flow Lube</b> (1842639C91)... <b>BD7250</b> <b>Fuel/Water Separator Ele.</b> (1842638C92)..... <b>PF7779</b> <b>Fuel</b> (625625C1)..... <b>BF984</b> <b>Fuel</b> (625627C1)..... <b>BF979 +</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (1820361C1)..... <b>BW5074</b>	AE School Bus w/MaxxForce 7 (6.4L) Eng. (Cont'd) <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	CE w/Cummins B6.7 (6.7L) Eng. (2019) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>EnduraCube Air</b> (2517298C1)..... <b>PA32001</b> <b>Crankcase Breather</b> (4936636).... <b>CV15010</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Crankcase Breather</b> (4936636).... <b>CV15010</b>
3300 Chassis w/VT365 (6.0L) Eng. <b>Lube</b> (w/o Screw-on Cap) (1844588C91)..... <b>P7235</b> <b>Lube</b> (w/Screw on Cap)..... <b>P7436</b> <b>Fuel Ele.</b> (1825864C92)..... <b>PF7698</b>	AR School Bus w/MaxxForce 7 (6.4L) Eng. <b>Lube Ele.</b> (w/o Screw on Cap) (1840752C91)..... <b>P7235</b> <b>Lube Ele.</b> (w/Screw on Cap) (Wix 57312)..... <b>P7436</b> <b>Lube Spin-on</b> (1899332C91)..... <b>B7506</b> <b>Fuel/Water Separator</b> (1878042C91)..... <b>PF7978</b> <b>Fuel Strainer</b> (1873910C91)..... <b>PF7994</b> <b>Fuel Kit</b> (1884207C91)..... <b>PF9914 KIT</b> <b>Fuel Kit</b> (1876533C93)..... <b>BF9858 KIT</b> <b>Crankcase Breather</b> ..... <b>N/S</b>	CE w/DTA360 Eng. <b>Lube</b> (1811953-C1)..... <b>B309</b> <b>Lube</b> (Fleetguard LF3420)..... <b>[2] BT261</b> <b>Fuel/Water Separator</b> (Engs. w/S/N 72707-on w/Davco) (Fleetguard FF105D)..... <b>BF957-D +</b> <b>Fuel</b> (w/o Drain) (Eng. S/N to 72706) (1822588-C1)..... <b>BF7629 +</b> <b>Fuel Strainer</b> (1817677-C91)..... <b>PF9907</b> <b>Single Air</b> (1661755-C91)..... <b>PA2521</b> <b>O. Air</b> (476741-C1)..... <b>PA2521</b> <b>I. Air</b> (Fleetguard AF987)..... <b>PA2522</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/6 Units BTA+) (Fleetguard WF2072)..... <b>BW5072</b> <b>Coolant</b> (w/8 Units BTA+) (Fleetguard WF2073)..... <b>BW5073</b> <b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b> <b>Coolant</b> (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b> <b>Steering</b> (To 8/30/91) (1681202-C91)..... <b>PT8407</b> <b>Steering</b> (8/31/91-on) (Fleetguard HF6162)..... <b>P106-HD</b>
AC Commercial Bus w/MaxxForce 7 (6.4L) Eng. <b>Lube Ele.</b> (w/o Screw on Cap) (1840752C91)..... <b>P7235</b> <b>Lube Ele.</b> (w/Screw on Cap) (Wix 57312)..... <b>P7436</b> <b>Lube Spin-on</b> (1899332C91)..... <b>B7506</b> <b>Fuel/Water Separator</b> (1878042C91)..... <b>PF7978</b> <b>Fuel Strainer</b> (1873910C91)..... <b>PF7994</b> <b>Fuel Kit</b> (1884207C91)..... <b>PF9914 KIT</b> <b>Fuel Kit</b> (1876533C93)..... <b>BF9858 KIT</b> <b>Crankcase Breather</b> ..... <b>N/S</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	BE w/MaxxForce 7 Eng. <b>Lube</b> (w/o Screw on Cap) (1840752-C91)..... <b>P7235</b> <b>Lube</b> (w/Screw on Cap) (Wix 57312)..... <b>P7436</b> <b>Fuel/Water Separator</b> (1878042-C91)..... <b>PF7978</b> <b>Fuel Strainer</b> (1873910-C91)..... <b>PF7994</b> <b>Radial Seal Air</b> (3532799-C1)..... <b>RS4636 +</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Steering</b> (2503221C1)..... <b>BT9388</b>	CE w/DTA360 Eng. <b>Lube</b> (1811953-C1)..... <b>B309</b> <b>Lube</b> (Fleetguard LF3420)..... <b>[2] BT261</b> <b>Fuel/Water Separator</b> (Engs. w/S/N 72707-on w/Davco) (Fleetguard FF105D)..... <b>BF957-D +</b> <b>Fuel</b> (w/o Drain) (Eng. S/N to 72706) (1822588-C1)..... <b>BF7629 +</b> <b>Fuel Strainer</b> (1817677-C91)..... <b>PF9907</b> <b>Single Air</b> (1661755-C91)..... <b>PA2521</b> <b>O. Air</b> (476741-C1)..... <b>PA2521</b> <b>I. Air</b> (Fleetguard AF987)..... <b>PA2522</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/6 Units BTA+) (Fleetguard WF2072)..... <b>BW5072</b> <b>Coolant</b> (w/8 Units BTA+) (Fleetguard WF2073)..... <b>BW5073</b> <b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b> <b>Coolant</b> (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b> <b>Steering</b> (To 8/30/91) (1681202-C91)..... <b>PT8407</b> <b>Steering</b> (8/31/91-on) (Fleetguard HF6162)..... <b>P106-HD</b>
AE School Bus w/MaxxForce 7 (6.4L) Eng. <b>Lube Ele.</b> (w/o Screw on Cap) (1840752C91)..... <b>P7235</b> <b>Lube Ele.</b> (w/Screw on Cap) (Wix 57312)..... <b>P7436</b> <b>Lube Spin-on</b> (1899332C91)..... <b>B7506</b> <b>Fuel/Water Separator</b> (1878042C91)..... <b>PF7978</b> <b>Fuel Strainer</b> (1873910C91)..... <b>PF7994</b> <b>Fuel Kit</b> (1884207C91)..... <b>PF9914 KIT</b> <b>Fuel Kit</b> (1876533C93)..... <b>BF9858 KIT</b> <b>Primary EnduraCube Air</b> (2602212C1)..... <b>PA32001</b> <b>Secondary EnduraCube Air</b> (2602211C1)..... <b>PA32004</b> <b>Crankcase Breather</b> ..... <b>N/S</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	BE w/VT365 Eng. <b>Lube</b> (w/o Screw on Cap) (1840752-C91)..... <b>P7235</b> <b>Lube</b> (w/Screw on Cap) (Wix 57312)..... <b>P7436</b> <b>Fuel</b> (1825864-C92)..... <b>PF7698</b> <b>Radial Seal Air</b> (3532799-C1)..... <b>RS4636 +</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Steering</b> (2503221C1)..... <b>BT9388</b>	CE w/DT466 (7.6L) Eng. (To 2005) <b>F-F Lube</b> (1819452-C1)..... <b>B7030</b> <b>Fuel/Water Separator</b> (1842638-C91)..... <b>PF7779</b> <b>Fuel Strainer</b> (1817677-C91)..... <b>PF9907</b> <b>Radial Seal O. Air</b> (3532799-C1).... <b>RS4636 +</b> <b>Radial Seal I. Air</b> (3532800-C1).... <b>RS4637</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>IC CORPORATION</b> <b>Buses (Also see International) (cont'd)</b>	<b>IC CORPORATION</b> <b>Buses (Also see International) (cont'd)</b>	<b>IC CORPORATION</b> <b>Buses (Also see International) (cont'd)</b>
CE w/DT466 (7.6L) Eng. (To 2005) (Cont'd)	CE w/MaxxForce 7 Eng. (Cont'd)	CE w/VT365 Eng. (Cont'd)
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Steering</b> (2503221-C1)..... <b>BT9388</b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	CE Commercial w/Cummins ISB (5.9L) Eng. (2015-17)
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Lube</b> (3937736)..... <b>B7177</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Steering</b> (2503221-C1)..... <b>BT9388</b>	<b>Lube</b> (4897898)..... <b>BT7237</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	CE w/MaxxForce DT Eng.	<b>Fuel/Water Separator</b> (3942533)..... <b>BF1271</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Dual-Flow Lube</b> (1842639-C91).. <b>BD7250</b>	<b>Fuel/Water Separator</b> (Fleetguard FS19596)..... <b>BF1293-SPS</b>
<b>Steering</b> (2503221-C1)..... <b>BT9388</b>	<b>Fuel/Water Separator</b> (1878042-C91)..... <b>PF7978</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b>
CE w/DT466 (7.6L) Eng. (2005-on)	<b>Fuel/Water Separator</b> (1822638-C91)..... <b>PF7779</b>	<b>Fuel</b> (Fleetguard FF5632)..... <b>BF7940</b>
<b>Dual-Flow Lube</b> (1842639-C91).. <b>BD7250</b>	<b>Fuel Strainer</b> (1873910-C91)..... <b>PF7994</b>	<b>Radial Seal O. Air</b> (3532799C1).. <b>RS4636 +</b>
<b>Fuel/Water Separator</b> (1842638-C91)..... <b>PF7779</b>	<b>Radial Seal O. Air</b> (3532799-C1)..... <b>RS4636 +</b>	<b>Radial Seal I. Air</b> (3532800C1).... <b>RS4637</b>
<b>Fuel Strainer</b> (1817677-C91)..... <b>PF9907</b>	<b>Radial Seal I. Air</b> (3532800-C1)... <b>RS4637</b>	<b>Air Dryer</b> (Bendix 107794)..... <b>BA5377</b>
<b>Radial Seal O. Air</b> (3532799-C1)..... <b>RS4636 +</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Radial Seal I. Air</b> (3532800-C1)... <b>RS4637</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Steering</b> (2503221C1)..... <b>BT9388</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	CE Commercial w/Cummins ISB (5.9L) Eng. (2018)
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Steering</b> (2503221-C1)..... <b>BT9388</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	CE w/VT365 Eng.	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Steering</b> (2503221-C1)..... <b>BT9388</b>	<b>Lube</b> (w/o Screw on Cap) (1844588-C91)..... <b>P7235</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
CE w/MaxxForce 7 Eng.	<b>Lube</b> (w/Screw on Cap) (Wix 57312)..... <b>P7436</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>Lube</b> (w/o Screw on Cap) (1840752C91)..... <b>P7235</b>	<b>Fuel</b> (1825864-C92)..... <b>PF7698</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Lube</b> (w/Screw on Cap) (Wix 57312)..... <b>P7436</b>	<b>Radial Seal O. Air</b> (3532799-C1)..... <b>RS4636 +</b>	<b>Trans. (4 In. Kit)</b> (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Fuel/Water Separator</b> (1878042-C91)..... <b>PF7978</b>	<b>Radial Seal I. Air</b> (3532800-C1)... <b>RS4637</b>	CE Commercial w/Cummins ISB (5.9L) Eng. (2019)
<b>Fuel Strainer</b> (1873910-C91)..... <b>PF7994</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b>
<b>Fuel Kit</b> (1876533-C93)..... <b>BF9858 KIT</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b>
<b>Radial Seal O. Air</b> (3532799-C1)..... <b>RS4636 +</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>EnduraCube Air</b> (2517298C1).... <b>PA32001</b>
<b>Radial Seal I. Air</b> (3532800-C1)... <b>RS4637</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>		

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IC CORPORATION Buses (Also see International) (cont'd)	IC CORPORATION Buses (Also see International) (cont'd)	IC CORPORATION Buses (Also see International) (cont'd)
CE Commercial w/Cummins ISB (5.9L) Eng. (2020)	CE School Bus w/T444E (7.3L) Eng. (2003) (Cont'd)	CE School Bus w/Cummins ISB 5.9 (5.9L) Eng. (2021)
Lube (3937736)..... B7177	Trans. Spin-on (Allison 29539579)..... BT8460	Lube (3937736)..... B7177
Fuel (5303743)..... BF63000		Fuel (5303743)..... BF63000
CE Commercial w/Cummins ISB (5.9L) Eng. (2021)	CE School Bus w/T444E (7.3L) Eng. (2004)	Breather (4936636)..... CV15010
Lube (3937736)..... B7177	Lube (1814562C1)..... B7039	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004
Fuel (5303743)..... BF63000	Fuel (1825864C92)..... PF7698	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016
Breather (4936636)..... CV15010	Std. Air (Fleetguard AF979M)..... PA2521	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003
Trans. Spin-on (Allison 29539579)..... BT8460	Long Life Air (Fleetguard AF979M)..... LL2521	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017
Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004	Opt. Coolant (Fleetguard WF2071)..... BW5071	Trans. Spin-on (Allison 29539579)..... BT8460
Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004	CE School Bus w/Cummins ISB (5.9L) Eng. (2022)
Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004
Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016
CE Commercial w/T444E (7.3L) Eng.	Trans. Spin-on (Allison 29539579)..... BT8460	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003
Lube (1814562C1)..... B7039	CE School Bus w/Cummins B6.7 (6.7L) Eng. (2019)	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017
Fuel/Water Separator (1677004C91)..... BF1345-O	Lube (Fleetguard LF3970)..... B7177	Trans. Spin-on (Allison 29539579)..... BT8460
Fuel Ele..... PF7678	Fuel (Fleetguard FF63009)..... BF63000	CE School Bus w/Power Solutions International V8-537 (8.8L) Eng. (2018)
Radial Seal O. Air (3532799C1)..... RS4636 *	EnduraCube Air (2517298C1)..... PA32001	EnduraCube Air (2517298C1)..... PA32001
Radial Seal I. Air (3532800C1)..... RS4637	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004	Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT
Air Dryer (Bendix 107794)..... BA5377	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016	Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT
Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004
Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20016
Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004	Trans. Spin-on (Allison 29539579)..... BT8460	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003
Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016	Crankcase Breather (4936636)..... CV15010	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017
Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003	CE School Bus w/Cummins B6.7 (6.7L) Eng. (2020)	Trans. Spin-on (Allison 29539579)..... BT8460
Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017	Lube (3937736)..... B7177	CE School Bus w/Power Solutions International V8-537 (8.8L) Eng. (2019)
Trans. Spin-on (Allison 29539579)..... BT8460	Fuel (5303743)..... BF63000	EnduraCube Air (2517298C1)..... PA32001
Steering (2503221C1)..... BT9388	Crankcase Breather (4936636)..... CV15010	Trans. Ele. (2 In. Kit) (Allison 29558117)..... PT9416-MPG KIT
CE School Bus w/T444E (7.3L) Eng. (2003)	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004	Trans. Ele. (4 In. Kit) (Allison 29558118)..... PT9415-MPG KIT
Lube (1814562C1)..... B7039	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004
Fuel (1825864C92)..... PF7698	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016
Std. Air (Fleetguard AF979M)..... PA2521	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003
Long Life Air (Fleetguard AF979M)..... LL2521	Trans. Spin-on (Allison 29539579)..... BT8460	
Opt. Coolant (Fleetguard WF2071)..... BW5071	CE School Bus w/Cummins ISB/ISB 5.9 (5.9L) Eng. (2020)	
Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004	Lube (3937736)..... B7177	
Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016	Fuel (5303743)..... BF63000	
Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003		
Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017		

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IC CORPORATION Buses (Also see International) (cont'd)	IC CORPORATION Buses (Also see International) (cont'd)	IC CORPORATION Buses (Also see International) (cont'd)
CE School Bus w/Power Solutions International V8-537 (8.8L) Eng. (2019) (Cont'd) <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	FE Commercial w/DT360 Eng. <b>Lube</b> (1811953-C1)..... <b>[2] B309</b> <b>Lube</b> (Fleetguard LF3420)..... <b>[2] BT261</b> <b>Fuel/Water Separator</b> (7/8-14 Thd.) (1808623-C1)..... <b>BF7584 +</b> <b>Fuel/Water Separator</b> (1-14 Thd.) (Fleetguard FF105D)..... <b>BF957-D +</b> <b>Fuel/Water Separator Box-Style</b> (Fleetrite FSR81205)..... <b>BF912</b> <b>Fuel</b> (9/1993-on) (1822588-C1).... <b>BF7629 +</b> <b>O. Air</b> (476741-C1)..... <b>PA2521</b> <b>I. Air</b> (Fleetguard AF987)..... <b>PA2522</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (w/6 Units BTA+) (Fleetguard WF2072)..... <b>BW5072</b> <b>Coolant</b> (w/8 Units BTA+) (Fleetguard WF2073)..... <b>BW5073</b> <b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b> <b>Coolant</b> (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b> <b>Trans.</b> (595722-C91)..... <b>[2] BT839-10</b>	FE Commercial w/DT466 (7.6L) Eng. (Cont'd) <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Pan-Type</b> (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b> <b>Trans. Spin-on</b> (595722-C91).... <b>BT839-10</b> <b>Steering</b> (2503221C1)..... <b>BT9388</b> <b>Steering</b> (2 25/32 In.) (Fleetguard LF634)..... <b>PT903</b> <b>Steering</b> (3 31/32 In.) (Fleetguard HF6162)..... <b>P106-HD</b>
CE School Bus w/Power Solutions International V8-537 (8.8L) Eng. (2020) <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	FE Commercial w/DT466 (7.6L) Eng. <b>Dual-Flow Lube</b> (1842639-C91).. <b>BD7250</b> <b>Fuel/Water Separator</b> (1822638-C91)..... <b>PF7779</b> <b>Fuel/Water Separator</b> (1878042-C91)..... <b>PF7978</b> <b>Fuel Strainer</b> (1873910-C91)..... <b>PF7994</b> <b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Steering</b> (2503221C1)..... <b>BT9388</b>	
CE School Bus w/Power Solutions International V8-537 (8.8L) Eng. (2021) <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	FE Commercial w/DT466 (7.6L) Eng. <b>F-F Lube</b> (1833121-C1)..... <b>B7030</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (1693965C91)..... <b>BF1347</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (1693965C91)..... <b>BF1347-O</b> <b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (1693965C91).... <b>BF1373-SP</b> <b>Fuel/Water Separator Box-Style</b> (Fleetrite FSR81205)..... <b>BF912</b> <b>Fuel/Water Separator Spin-on</b> (1618386-C92)..... <b>BF1345-O</b> <b>Fuel</b> (1822588-C1)..... <b>BF7629 +</b> <b>Fuel</b> (1820479-C1)..... <b>BF7531</b> <b>Some I. Air</b> (482644-C1)..... <b>[2] PA2522</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (w/o Chemical) (Fleetguard WF2101)..... <b>B5134 +</b> <b>Coolant</b> (w/4 Units BTA+) (1822313-C1)..... <b>BW5082</b> <b>Coolant</b> (w/12 Units BTA+) (1820361-C1)..... <b>BW5074</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	FE Commercial w/MaxxForce DT Eng. <b>Trans. Spin-on</b> (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Steering</b> (2503221C1)..... <b>BT9388</b>
CE School Bus w/Power Solutions International V8-537 (8.8L) Eng. (2022) <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	FE Integrated w/DT360 Eng. <b>Lube</b> (1811953-C1)..... <b>[2] B309</b> <b>Lube</b> (Fleetguard LF3420)..... <b>[2] BT261</b> <b>Fuel/Water Separator</b> (7/8-14 Thd.) (1808623-C1)..... <b>BF7584 +</b> <b>Fuel/Water Separator</b> (1-14 Thd.) (Fleetguard FF105D)..... <b>BF957-D +</b> <b>Fuel/Water Separator Box-Style</b> (Fleetrite FSR81205)..... <b>BF912</b> <b>Fuel</b> (9/1993-on) (1822588-C1).... <b>BF7629 +</b> <b>O. Air</b> (476741-C1)..... <b>PA2521</b> <b>I. Air</b> (Fleetguard AF987)..... <b>PA2522</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (w/6 Units BTA+) (Fleetguard WF2072)..... <b>BW5072</b> <b>Coolant</b> (w/8 Units BTA+) (Fleetguard WF2073)..... <b>BW5073</b> <b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b> <b>Coolant</b> (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b> <b>Trans.</b> (595722-C91)..... <b>[2] BT839-10</b>	CE School Bus w/Power Solutions International V8-537 (8.8L) Eng. (2023) <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



IC CORPORATION Buses (Also see International) (cont'd)	IC CORPORATION Buses (Also see International) (cont'd)	IC CORPORATION Buses (Also see International) (cont'd)
FE Integrated w/DT466 (7.6L) Eng. <b>F-F Lube</b> (1833121-C1)..... <b>B7030</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (1693965C91)..... <b>BF1347</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (1693965C91)..... <b>BF1347-O</b> <b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (1693965C91)..... <b>BF1373-SP</b> <b>Fuel/Water Separator Box-Style</b> (Fleetrite FSR81205)..... <b>BF912</b> <b>Fuel/Water Separator Spin-on</b> (1618386-C92)..... <b>BF1345-O</b> <b>Fuel</b> (1822588-C1)..... <b>BF7629 +</b> <b>Fuel</b> (1820479-C1)..... <b>BF7531</b> <b>Some I. Air</b> (482644-C1)..... <b>[2] PA2522</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (w/o Chemical) (Fleetguard WF2101)..... <b>B5134 +</b> <b>Coolant</b> (w/4 Units BTA+) (1822313-C1)..... <b>BW5082</b> <b>Coolant</b> (w/12 Units BTA+) (1820361-C1)..... <b>BW5074</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Pan-Type</b> (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b> <b>Trans. Spin-on</b> (595722-C91)..... <b>BT839-10</b> <b>Steering</b> (2503221C1)..... <b>BT9388</b> <b>Steering</b> (2 25/32 In.) (Fleetguard LF634)..... <b>PT903</b> <b>Steering</b> (3 31/32 In.) (Fleetguard HF6162)..... <b>P106-HD</b>	FE Integrated w/MaxxForce DT Eng. (Cont'd) <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Steering</b> (2503221C1)..... <b>BT9388</b> FE School Bus w/DT360 Eng. <b>Lube</b> (1811953-C1)..... <b>[2] B309</b> <b>Lube</b> (Fleetguard LF3420)..... <b>[2] BT261</b> <b>Fuel/Water Separator</b> (7/8-14 Thd.) (1808623-C1)..... <b>BF7584 +</b> <b>Fuel/Water Separator</b> (1-14 Thd.) (Fleetguard FF105D)..... <b>BF957-D +</b> <b>Fuel/Water Separator Box-Style</b> (Fleetrite FSR81205)..... <b>BF912</b> <b>Fuel</b> (9/1993-on) (1822588-C1)..... <b>BF7629 +</b> <b>O. Air</b> (476741-C1)..... <b>PA2521</b> <b>I. Air</b> (Fleetguard AF987)..... <b>PA2522</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (w/6 Units BTA+) (Fleetguard WF2072)..... <b>BW5072</b> <b>Coolant</b> (w/8 Units BTA+) (Fleetguard WF2073)..... <b>BW5073</b> <b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b> <b>Coolant</b> (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b> <b>Trans.</b> (595722-C91)..... <b>[2] BT839-10</b> FE School Bus w/DT466 (7.6L) Eng. <b>F-F Lube</b> (1833121-C1)..... <b>B7030</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (1693965C91)..... <b>BF1347</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (1693965C91)..... <b>BF1347-O</b> <b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (1693965C91)..... <b>BF1373-SP</b> <b>Fuel/Water Separator Box-Style</b> (Fleetrite FSR81205)..... <b>BF912</b> <b>Fuel/Water Separator Spin-on</b> (1618386-C92)..... <b>BF1345-O</b> <b>Fuel</b> (1822588-C1)..... <b>BF7629 +</b> <b>Fuel</b> (1820479-C1)..... <b>BF7531</b> <b>Some I. Air</b> (482644-C1)..... <b>[2] PA2522</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (w/o Chemical) (Fleetguard WF2101)..... <b>B5134 +</b> <b>Coolant</b> (w/4 Units BTA+) (1822313-C1)..... <b>BW5082</b>	FE School Bus w/DT466 (7.6L) Eng. (Cont'd) <b>Coolant</b> (w/12 Units BTA+) (1820361-C1)..... <b>BW5074</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Pan-Type</b> (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b> <b>Trans. Spin-on</b> (595722-C91)..... <b>BT839-10</b> <b>Steering</b> (2503221C1)..... <b>BT9388</b> <b>Steering</b> (2 25/32 In.) (Fleetguard LF634)..... <b>PT903</b> <b>Steering</b> (3 31/32 In.) (Fleetguard HF6162)..... <b>P106-HD</b> FE School Bus w/MaxxForce DT Eng. <b>Dual-Flow Lube</b> (1842639-C91).. <b>BD7250</b> <b>Fuel/Water Separator</b> (1822638-C91)..... <b>PF7779</b> <b>Fuel/Water Separator</b> (1878042-C91)..... <b>PF7978</b> <b>Fuel Strainer</b> (1873910-C91)..... <b>PF7994</b> <b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IC CORPORATION Buses (Also see International) (cont'd)	IC CORPORATION Buses (Also see International) (cont'd)	IC CORPORATION Buses (Also see International) (cont'd)
HC Integrated Commercial w/DT466 (7.6L) Eng. <b>Dual-Flow Lube</b> (1842639-C91).. <b>BD7250</b> <b>P. Fuel</b> (625625-C1)..... <b>BF984</b> <b>P. Fuel</b> (625627-C1)..... <b>BF979 +</b> <b>Fuel</b> (1820479-C1)..... <b>BF7531</b> <b>Coolant</b> (4 3/8 In. (w/4 Units BTA+)) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (5 3/8 In. (w/4 Units BTA+)) (1822313-C1)..... <b>BW5082</b> <b>Coolant</b> (w/12 Units BTA+) (1820361-C1)..... <b>BW5074</b>	HC Integrated Commercial w/VT365 (6.0L) Eng. (Cont'd) <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Steering</b> (2503221C1)..... <b>BT9388</b> HC w/MaxxFace DT Eng. <b>Dual-Flow Lube</b> (1842639-C91).. <b>BD7250</b> <b>Fuel/Water Separator</b> (1878042-C91)..... <b>PF7978</b> <b>Fuel/Water Separator</b> (1822638-C91)..... <b>PF7779</b> <b>Fuel Strainer</b> (1873910-C91)..... <b>PF7994</b> <b>Radial Seal Air</b> (3532799-C1)..... <b>RS4636 +</b> <b>Opt. Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b> <b>Opt. Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	RE Commercial w/DT466 (7.6L) Eng. <b>Lube</b> (1819452-C1)..... <b>B7030</b> <b>Fuel/Water Separator</b> (1677004C-91)..... <b>BF1345-O</b> <b>Fuel</b> (1809789-C1)..... <b>BF7629 +</b> <b>Air</b> (476741-C1)..... <b>PA2521</b> <b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Steering Ele.</b> (1691121C1)..... <b>P106-HD</b> <b>Steering Spin-on</b> (2503221-C1).. <b>BT9388</b>
HC Integrated Commercial w/MaxxFace 7 (6.4L) Eng. <b>Lube</b> (w/o Screw on Cap) (1840752-C91)..... <b>P7235</b> <b>Lube</b> (w/Screw on Cap) (Wix 57312)..... <b>P7436</b> <b>Fuel/Water Separator</b> (1878042-C91)..... <b>PF7978</b> <b>Fuel Strainer</b> (1873910-C91)..... <b>PF7994</b> <b>Opt. Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b> <b>Opt. Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	RE Commercial w/Cummins ISL 8.9 (8.9L) Eng. (2019) <b>Lube</b> (3401544)..... <b>B40142</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Channel Flow Primary Air</b> (2591005C1)..... <b>CA5514</b> <b>Channel Flow Secondary Air</b> (2591007C1)..... <b>PA5515</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	RE Commercial w/DT530 (8.7L) Eng. <b>F-F Lube</b> (1819452-C1)..... <b>B7030</b> <b>Dual-Flow Lube</b> (1842639-C91).. <b>BD7250</b> <b>Fuel</b> (1820479-C1)..... <b>BF7531</b> <b>Coolant (w/4 Units BTA+)</b> (1822313-C1)..... <b>BW5082</b>
HC Integrated Commercial w/VT365 (6.0L) Eng. <b>Lube</b> (w/o Screw-on Cap) (1844588C91)..... <b>P7235</b> <b>Lube</b> (w/Screw on Cap)..... <b>P7436</b> <b>Fuel Ele.</b> (1825864C92)..... <b>PF7698</b> <b>Radial Seal Air</b> (3532799C1)..... <b>RS4636 +</b> <b>Air Dryer</b> (AD-IP System) (Bendix 109493)..... <b>BA5373</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29526899)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29526898)..... <b>PT9415-MPG KIT</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	RE Commercial w/Cummins ISL 8.9 (8.9L) Eng. (2020) <b>Lube</b> (5444774)..... <b>B40142</b> <b>Fuel</b> (5303743)..... <b>BF63000</b>	RE Commercial w/T444E (7.3L) Eng. <b>Lube</b> (1814562C1)..... <b>B7039</b> <b>Fuel</b> (1822631C91)..... <b>PF7678</b> <b>O. Air</b> (476741-C1)..... <b>[2] PA2521</b> <b>I. Air</b> (Fleetguard AF987)..... <b>[2] PA2522</b> <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (Fleetguard HF6162)..... <b>P106-HD</b>
	RE Commercial w/Cummins ISL 8.9 (8.9L) Eng. (2021) <b>Lube</b> (5444774)..... <b>B40142</b>	RE Commercial w/VT365 (6.0L) Eng. <b>Lube</b> (w/o Screw-on Cap) (1844588C91)..... <b>P7235</b> <b>Lube</b> (w/Screw on Cap)..... <b>P7436</b> <b>Fuel Ele.</b> (1825864C92)..... <b>PF7698</b> <b>O. Air</b> (476741C1)..... <b>PA2521</b> <b>Cab Air</b> (1696834C1)..... <b>PA5691</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29526899)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29526898)..... <b>PT9415-MPG KIT</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
	RE Commercial w/Cummins ISL 8.9 (8.9L) Eng. (2022) <b>Lube</b> (5444774)..... <b>B40142</b> <b>Fuel</b> (5660774)..... <b>BF63000</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IC CORPORATION Buses (Also see International) (cont'd)	IC CORPORATION Buses (Also see International) (cont'd)	IC CORPORATION Buses (Also see International) (cont'd)
RE Commercial w/VT365 (6.0L) Eng. (Cont'd) <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Steering</b> (11507425104)..... <b>P106-HD</b>	RE School Bus w/Cummins ISL 8.9 (8.9L) Eng. (2019) (Cont'd) <b>Trans.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	RE School Bus w/T444E (7.3L) Eng. <b>Lube</b> (1814562C1)..... <b>B7039</b> <b>Fuel</b> (1822631C91)..... <b>PF7678</b> <b>O. Air</b> (476741-C1)..... <b>[2] PA2521</b> <b>I. Air</b> (Fleetguard AF987)..... <b>[2] PA2522</b> <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (Fleetguard HF6162)..... <b>P106-HD</b>
RE Integrated w/DT466 (7.6L) Eng. <b>Lube</b> (1819452-C1)..... <b>B7030</b> <b>Fuel/Water Separator</b> (1677004C-91)..... <b>BF1345-O</b> <b>Fuel</b> (1809789-C1)..... <b>BF7629 +</b> <b>Air</b> (476741-C1)..... <b>PA2521</b> <b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Steering Ele.</b> (1691121C1)..... <b>P106-HD</b> <b>Steering Spin-on</b> (2503221-C1)..... <b>BT9388</b>	RE School Bus w/Cummins ISL 8.9 (8.9L) Eng. (2020) <b>Lube</b> (5444774)..... <b>B40142</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Channel Flow Primary Air</b> (2591005C1)..... <b>CA5514</b> <b>Channel Flow Secondary Air</b> (2591007C1)..... <b>PA5515</b> <b>Trans.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	RE School Bus w/VT365 (6.0L) Eng. <b>Lube</b> (w/o Screw-on Cap) (1844588C91)..... <b>P7235</b> <b>Lube</b> (w/Screw on Cap)..... <b>P7436</b> <b>Fuel Ele.</b> (1825864C92)..... <b>PF7698</b> <b>O. Air</b> (476741C1)..... <b>PA2521</b> <b>Cab Air</b> (1696834C1)..... <b>PA5691</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29526899)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29526898)..... <b>PT9415-MPG KIT</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Steering</b> (11507425104)..... <b>P106-HD</b>
RE Integrated w/VT365 (6.0L) Eng. <b>Lube</b> (w/o Screw-on Cap) (1844588C91)..... <b>P7235</b> <b>Lube</b> (w/Screw on Cap)..... <b>P7436</b> <b>Fuel Ele.</b> (1825864C92)..... <b>PF7698</b> <b>O. Air</b> (476741C1)..... <b>PA2521</b> <b>Cab Air</b> (1696834C1)..... <b>PA5691</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29526899)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29526898)..... <b>PT9415-MPG KIT</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Steering</b> (11507425104)..... <b>P106-HD</b>	RE School Bus w/Cummins ISL 8.9 (8.9L) Eng. (2021) <b>Lube</b> (5444774)..... <b>B40142</b> <b>Trans.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	RE w/MaxxFace DT Eng. <b>Dual-Flow Lube</b> (1842639-C91)..... <b>BD7250</b> <b>Fuel/Water Separator</b> (1822638-C91)..... <b>PF7779</b> <b>Fuel/Water Separator</b> (1878042-C91)..... <b>PF7978</b> <b>Fuel Strainer</b> (1873910-C91)..... <b>PF7994</b> <b>Some Air</b> (476741-C1)..... <b>PA2521</b> <b>Channel Flow Air</b> (2591005C1)..... <b>CA5514</b> <b>Channel Flow Secondary Air</b> (2591007-C1)..... <b>PA5515</b> <b>Cab Air</b> (Foam) (1696834C1)..... <b>PA5691</b> <b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Steering Ele.</b> (1691121C1)..... <b>P106-HD</b> <b>Steering Spin-on</b> (2503221-C1)..... <b>BT9388</b>
RE School Bus w/Cummins ISL 8.9 (8.9L) Eng. (2019) <b>Lube</b> (3401544)..... <b>B40142</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Channel Flow Primary Air</b> (2591005C1)..... <b>CA5514</b> <b>Channel Flow Secondary Air</b> (2591007C1)..... <b>PA5515</b> <b>Trans.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	RE School Bus w/Cummins ISL 8.9 (8.9L) Eng. (2022) <b>Lube</b> (5444774)..... <b>B40142</b> <b>Fuel</b> (5660774)..... <b>BF63000</b>	RE School Bus w/DT466 (7.6L) Eng. <b>Lube</b> (1819452-C1)..... <b>B7030</b> <b>Fuel/Water Separator</b> (1677004C-91)..... <b>BF1345-O</b> <b>Fuel</b> (1809789-C1)..... <b>BF7629 +</b> <b>Air</b> (476741-C1)..... <b>PA2521</b> <b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Steering Ele.</b> (1691121C1)..... <b>P106-HD</b> <b>Steering Spin-on</b> (2503221-C1)..... <b>BT9388</b>
	RE School Bus w/DT530 (8.7L) Eng. <b>F-F Lube</b> (1819452-C1)..... <b>B7030</b> <b>Dual-Flow Lube</b> (1842639-C91)..... <b>BD7250</b> <b>Fuel</b> (1820479-C1)..... <b>BF7531</b> <b>Coolant</b> (1822313-C1)..... <b>BW5082</b>	TC Commercial Bus w/Cummins ISB 5.9 (5.9L) Eng. (2020) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (5303743)..... <b>BF63000</b>


+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IC CORPORATION Buses (Also see International) (cont'd)	INTERNATIONAL Engines (cont'd)	INTERNATIONAL Engines (cont'd)
TC Commercial Bus w/Cummins ISB (5.9L) Eng. (2021)	196 4 Cyl. (Cont'd)	392 V8
Lube (3937736)..... B7177	Air (1967-68) (332623-C1)..... PA642	Lube Ele. (133205-R91)..... P183
Fuel (5303743)..... BF63000	Air (1969-on) (369500-C1)..... PA1735	Lube Ele. (210297-R91)..... PT82-HD +
Crankcase Breather (4936636).... CV15010		Lube Ele. (214731-R91)..... P203
<b>IDLE SOLUTIONS</b>	220 6 Cyl.	5 9/32 In. Lube Spin-on..... B2 +
<b>Auxiliary Power Units (APU)</b>	F-F Lube Ele. (214731-R91)..... P203	7 1/8 In. Lube Spin-on..... B167
Idle Solutions w/Perkins 403C-11 Eng.	F-F Lube Ele. (236649-R91)..... P206 <sup>90</sup>	Fuel Ele..... PF859
Lube (140517050)..... B1405	B-P Lube Sock (70690H)..... CU406 <sup>90</sup>	In-Line Fuel..... BF840 +
Fuel (26561117)..... BF825 +	In-Line Fuel..... BF840 +	Opt. Air (369500-C1)..... PA1735
Radial Seal Air (Don. P822686).... RS3715	Opt. Air (188791-R91)..... PA604	Converted Air (863725-C91)..... PA602
<b>IDLEBUSTER</b>	232 6 Cyl.	400 V8
<b>Auxiliary Power Units (APU)</b>	4 3/8 In. Lube Spin-on..... B39	4 3/8 In. Lube Spin-on..... B39
Class 8 Sprinter System w/Kubota LP1RV Eng.	5 9/32 In. Lube Spin-on..... B9	5 9/32 In. Lube Spin-on..... B9
Lube..... CLN&R	Fuel Ele..... PF859	In-Line Fuel..... BF840 +
Fuel (15231-43560)..... PF872	In-Line Fuel..... BF840 +	Opt. Air (369500-C1)..... PA1735
Air (14971-11180)..... PA3983-FN	Opt. Air (369500-C1)..... PA1735	
Idlebuster w/Kubota Z482 Diesel Eng.	240 6 Cyl.	404, MV404, MV406 V8
Lube (Installed before 4/07, To S/N 382) (70000-15241)..... B179	F-F Lube Ele. (214731-R91)..... P203	5 9/32 In. Lube Spin-on..... B2 +
Lube (Installed after 4/07, S/N 383-on) (70000-32431)..... B243	F-F Lube Ele. (236649-R91)..... P206 <sup>90</sup>	7 1/8 In. Lube Spin-on..... B167
Fuel/Water Separator (w/Drain and Sensor Port) (Racor R12-S).... BF1379	B-P Lube Sock (70690H)..... CU406 <sup>90</sup>	In-Line Fuel..... BF840 +
Fuel/Water Separator (w/Drain and Sensor Port) (Racor R12T).... BF1380	In-Line Fuel..... BF840 +	Opt. Air (446661-C1)..... PA2061
Fuel/Water Separator (Open End for Bowl) (Racor R12-S)..... BF1379-O	Opt. Air (188791-R91)..... PA604	Opt. Air (446661-C2)..... PA2092
Fuel/Water Separator (Open End for Bowl) (Racor R12T)..... BF1380-O	258 6 Cyl.	420 V8 (6.9L)
Fuel/Water Separator (Cold Weather) (Racor R12-P)..... BF1381	4 3/8 In. Lube Spin-on..... B39	Lube..... [2] B134
Fuel/Water Separator (Open End for Bowl) (Racor R12-P)..... BF1381-O	5 9/32 In. Lube Spin-on..... B9	P. Fuel..... BF891
Radial Seal Air (K1211-82320).... RS3715	Fuel Ele..... PF859	S. Fuel..... BF786
	In-Line Fuel..... BF840 +	Air..... PA2116
	Opt. Air (369500-C1)..... PA1735	
<b>INGERSOLL RAND</b>	266 V8	444 V8 (7.3L)
<b>Engines</b>	Lube Ele. (133205-R91)..... P183	Lube..... [2] B134
1K270M Eng.	Lube Ele. (210297-R91)..... PT82-HD +	Fuel/Water Separator..... BF1222 +
Lube (Thermo King 11-6182)..... B161-S	Lube Ele. (214731-R91)..... P203	446, MV446 V8 (7.3L)
	5 9/32 In. Lube Spin-on..... B2 +	5 9/32 In. Lube Spin-on..... B2 +
<b>INTERNATIONAL</b>	7 1/8 In. Lube Spin-on..... B167	7 1/8 In. Lube Spin-on..... B167
<b>Auxiliary Power Units (APU)</b>	Fuel Ele..... PF859	In-Line Fuel..... BF840 +
Fleetrite w/Cat C0.5 Eng.	In-Line Fuel..... BF840 +	Opt. Air (446661-C1)..... PA2061
Lube (ACDelco PF1233)..... B33	Opt. Air (369500-C1)..... PA1735	Opt. Air (446661-C2)..... PA2092
Fuel (Wix 33262)..... PF937	Converted Air (863725-C91)..... PA602	
Air (Mann C1140)..... PA4758		551CID (9.0L)
		Lube..... B167
<b>INTERNATIONAL</b>	304, 304A V8	P. Fuel..... BF984
<b>Engines</b>	Lube Ele. (133205-R91)..... P183	S. Fuel..... BF588
152 4 Cyl.	Lube Ele. (210297-R91)..... PT82-HD +	A26 (12.4L)
Lube Ele..... P203	Lube Ele. (214731-R91)..... P203	Lube (3007498C94)..... P7494
Lube Spin-on..... B2 +	5 9/32 In. Lube Spin-on..... B2 +	Fuel (2517615C91)..... PF7986
Fuel Ele..... PF859	7 1/8 In. Lube Spin-on..... B167	BD264
In-Line Fuel..... BF840 +	Fuel Ele..... PF859	F-F Lube Ele. (214731-R91)..... P203
196 4 Cyl.	In-Line Fuel..... BF840 +	F-F Lube Ele. (236649-R91)..... P206 <sup>90</sup>
Lube Ele..... P203	Opt. Air (369500-C1)..... PA1735	B-P Lube Sock (70690H)..... CU406 <sup>90</sup>
Lube Spin-on..... B2 +	Converted Air (863725-C91)..... PA602	Fuel Ele..... PF859
Fuel Ele..... PF859		In-Line Fuel..... BF840 +
In-Line Fuel..... BF840 +		Opt. Air (188791-R91)..... PA604
		BD269
		B-P Lube Sock..... CU406 <sup>90</sup>
		In-Line Fuel..... BF840 +
		BD282
		F-F Lube Ele..... P203
		B-P Lube Sock..... CU406 <sup>90</sup>
		Fuel Ele..... PF859
		In-Line Fuel..... BF840 +

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Engines (cont'd)	INTERNATIONAL Engines (cont'd)	INTERNATIONAL Engines (cont'd)
BD282 (Cont'd) Opt. Air (188791-R91)..... PA604	DT466, DT466C, DTA466, DTA466C, DTI466, DVT466 (7.6L) F-F Lube (To 1994) (1808896-C1)..... [2] B299 +	DT466HT Dual-Flow Lube (1842639-C91).. BD7250 Fuel/Water Separator (1842638-C92)..... PF7779
BD308 F-F Lube Ele..... P203 B-P Lube Sock..... CU406 <sup>90</sup> Fuel Ele..... PF859 In-Line Fuel..... BF840 + Opt. Air (188791-R91)..... PA604	F-F Lube (To 1994) (1811953-C1)..... [2] B309 F-F Lube (1994-2004) (1819452-C1)..... B7030 Dual-Flow Lube (2005-on) (1842639-C91)..... BD7250 Opt. Fuel/Water Separator (1808623-C1)..... BF7584 + Fuel/Water Separator (1842638-C92)..... PF7779	DT466P F-F Lube (1833121-C1)..... B7030 Fuel (1822588-C1)..... BF7629 + Coolant (w/o Chemical) (Fleetguard WF2101)..... B5134 + Coolant (w/4 Units BTA+) (Fleetguard WF2106)..... BW5082 Coolant (w/12 Units BTA+) (1820361-C1)..... BW5074
BG241 Lube Ele. (214731-R91)..... P203 Lube Ele. (236649-R91)..... P206 <sup>90</sup> Fuel Ele..... PF859 In-Line Fuel..... BF840 +	5 5/16 In. P. Fuel Spin-on (625625-C1)..... BF984 8 23/32 In. P. Fuel Spin-on (625627-C1)..... BF979 + P. Fuel (To S/N 638218) (Fleetguard FF5020)..... BF979 + P. Fuel (Trucks) S/N 594840-up (1809789-C1)..... BF7629 + P. Fuel (Buses) (1820479-C1)..... BF7531 S. Fuel (Trucks) To S/N 594839 (672603-C3)..... BF588 Opt. O. Air (476741-C1)..... PA2521 Opt. I. Air (482644-C1)..... PA2522 Opt. Air (472098-C1)..... PA2429 Opt. Air (478974-C1)..... PA2520	DT530 (8.7L) F-F Lube (1819452-C1)..... B7030 Dual-Flow Lube (1842639-C91).. BD7250 Fuel/Water Separator (Trucks) (1808623-C1)..... BF7584 + Fuel/Water Separator (1842638-C91)..... PF7779 Fuel (Trucks) (1809789-C1)..... BF7629 + Fuel (Buses) (1820479-C1)..... BF7531 Coolant (1822313-C1)..... BW5082
BG265 Lube Ele..... P203 In-Line Fuel..... BF840 +	4 3/8 In. Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071 5 3/8 In. Coolant (w/4 Units BTA+) (1822313-C1)..... BW5082 Coolant (w/12 Units BTA+) (1820361-C1)..... BW5074	DT570, HT570 (9.3L) 10 11/32 In. Dual-Flow Lube (1842543-C1)..... BD7252 14 7/32 In. Dual-Flow Lube (1842639-C91)..... BD7250 B-P Lube Spinner (1842825-C91)..... BC7394 Fuel/Water Separator (1842638-C92)..... PF7779 Breather (DT570 Engine)..... CLN&R
D150 7 1/8 In. Lube Spin-on..... B167 P. Fuel Spin-on..... BF979 + S. Fuel Spin-on..... BF888 Opt. Air (461236-C1)..... PA2473 Opt. Air (447417-C1)..... PA2376 Opt. Air (472098-C1)..... PA2429	DT466E (7.6L) F-F Lube (1833121-C1)..... B7030 10 11/32 In. Dual-Flow Lube (1842655-C91)..... BD7252 14 7/32 In. Dual-Flow Lube (1842639-C91)..... BD7250 B-P Lube Spinner (1842825-C91)..... BC7394 Fuel/Water Separator Ele. (1842638-C91)..... PF7779 Fuel Spin-on (Trucks) (1822588-C1)..... BF7629 + Fuel Spin-on (Buses) (1820479-C1)..... BF7531 Coolant (w/o Chemical) (Fleetguard WF2101)..... B5134 + Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071 Coolant (w/12 Units BTA+) (1820361-C1)..... BW5074	DV462 Lube Ele..... [2] P276 Lube Spin-on..... [2] B167 P. Fuel Spin-on..... BF979 + S. Fuel Spin-on..... BF888 S. Fuel Ele. (323960-R92)..... PF225 F. Fuel (259099-C91)..... BF968 Opt. Air (303642-C91)..... PA1786 Opt. Air (461236-C1)..... PA2473
D170, D190 7 1/8 In. Lube Spin-on..... B167 P. Fuel Spin-on..... BF979 + S. Fuel Spin-on..... BF888 Opt. Air (461236-C1)..... PA2473 Opt. Air (447417-C1)..... PA2376 Opt. Air (472098-C1)..... PA2429	DT360, DTA360 (5.9L) Lube (1808896-C1)..... B299 + Lube (1811953-C1)..... B309 Opt. Fuel/Water Separator (1808623-C1)..... BF7584 + Fuel (1809789-C1)..... BF7629 + Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071 Coolant (w/12 Units BTA+) (1820361-C1)..... BW5074 Coolant (w/8 Units BTE)..... BW5139	DV550, DV550B, DV550BTC (9.0L) Lube Ele..... [2] P276 Lube Spin-on..... [2] B167 P. Fuel Spin-on..... BF979 + S. Fuel Ele. (323960-R92)..... PF225 F. Fuel (259099-C91)..... BF968 Opt. Air (303642-C91)..... PA1786 Opt. Air (461236-C1)..... PA2473 Opt. Air (w/Turbo) (478974-C1)..... PA2520
D301 Lube Ele..... PT185 Lube Spin-on..... B167 Fuel Ele..... PF828	DT408 Lube (1819452-C1)..... B7030 Fuel/Water Separator (Trucks) (1808623-C1)..... BF7584 + Fuel (Trucks) (1809789-C1)..... BF7629 + Fuel (Buses) (1820479-C1)..... BF7531 Coolant (w/o Chemical) (Fleetguard WF2101)..... B5134 + Coolant (w/4 Units BTA+) (1822313-C1)..... BW5082 Coolant (w/12 Units BTA+) (1820361-C1)..... BW5074	DVT573 Lube Ele..... [2] PT86-HD P. Fuel Spin-on..... BF979 + S. Fuel Spin-on..... BF588 Fuel Ele..... [2] PF225


+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Engines (cont'd)	INTERNATIONAL Engines (cont'd)	INTERNATIONAL Engines (cont'd)
I530E F-F Lube (1833121-C1)..... <b>B7030</b> P. Fuel Strainer (1817677-C91)... <b>PF9907</b> S. Fuel (1822588-C1)..... <b>BF7629 +</b> Coolant (w/o Chemical) (Fleetguard WF2101)..... <b>B5134 +</b> Coolant (4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> Coolant (w/12 Units BTA+) (1820361-C1)..... <b>BW5074</b>	MaxxFace 10 (9.3L) Dual-Flow Lube (To 2011) (1842639-C91)..... <b>BD7250</b> Lube (2012-on) (1889124-C91).... <b>B7503</b> Lube Centrifuge (2606467-C91). <b>BC7485 +</b> Lube (1885920C2)..... <b>B40053</b> Fuel/Water Separator (1878042-C91)..... <b>PF7978</b> Fuel Strainer (1873910-C91)..... <b>PF7994</b>	RD372 F-F Lube Ele..... <b>P204</b> B-P Lube Sock..... <b>CU406<sup>90</sup></b> In-Line Fuel..... <b>BF840 +</b> Opt. Air (204514-R91)..... <b>PA638</b>
I530P F-F Lube (1833121-C1)..... <b>B7030</b> Fuel (1822588-C1)..... <b>BF7629 +</b> Coolant (w/o Chemical) (Fleetguard WF2101)..... <b>B5134 +</b> Coolant (w/4 Units BTA+) (Fleetguard WF2106)..... <b>BW5082</b> Coolant (w/12 Units BTA+) (1820361-C1)..... <b>BW5074</b>	MaxxFace 11 (10.5L) Lube (2007 Emissions) (3006874C91)..... <b>P7508</b> Lube (2010 Emissions) (3007498C92)..... <b>P7494</b> Lube Centrifuge (2012-on) (2606467-C91)..... <b>BC7485 +</b> Fuel/Water Separator (2588149-C1)..... <b>PF7748</b> Fuel/Water Separator (3004473-C91)..... <b>PF7986</b> P. Fuel (A0000902051)..... <b>PF7939</b>	RD406 F-F Lube Ele..... <b>P204</b> B-P Lube Sock..... <b>CU406<sup>90</sup></b> In-Line Fuel..... <b>BF840 +</b> Opt. Air (180237-R91)..... <b>PA653</b> Opt. Air (204514-R91)..... <b>PA638</b>
MaxxFace 5 (4.5L) Lube (1847174-C91)..... <b>P7423</b> Fuel (1847170-C93)..... <b>PF7812 KIT</b>	MaxxFace 13 (12.4L) Lube (2007 Emissions) (3006874C91)..... <b>P7508</b> Lube (2010 Emissions) (3007498-C92)..... <b>P7494</b> Lube Centrifuge (2606467C91)... <b>BC7485 +</b> Fuel/Water Separator (3004473C91)..... <b>PF7986</b> P. Fuel (3004474C91)..... <b>PF7939</b>	RD450 F-F Lube Ele..... <b>P204</b> B-P Lube Sock..... <b>CU406<sup>90</sup></b> In-Line Fuel..... <b>BF840 +</b> Opt. Air (204514-R91)..... <b>PA638</b>
MaxxFace 6 Lube (w/o Screw on Cap) (1840752-C91)..... <b>P7235</b> Lube (w/Screw on Cap) (Wix 57312)..... <b>P7436</b> Fuel (1825864-C92)..... <b>PF7698</b>	MaxxFace 15 (15.2L) Lube (w/o O-Rings) (1R1808)..... <b>B7299 +</b> Lube (w/3 O-Rings) (3014491-C91)..... <b>B7507</b> Fuel (3014300-C1)..... <b>BF7587</b>	RD501 F-F Lube Ele..... <b>P204</b> B-P Lube Sock..... <b>CU406<sup>90</sup></b> In-Line Fuel..... <b>BF840 +</b> Air (Buses) (180237-R91)..... <b>[2] PA653</b> Opt. Air (204514-R91)..... <b>PA638</b>
MaxxFace 7 (6.4L) Lube Ele. (w/o Screw on Cap) (1840752-C91)..... <b>P7235</b> Lube Ele. (w/Screw on Cap) (Wix 57312)..... <b>P7436</b> Lube Spin-on (2012-on) (1899332C-91)..... <b>B7506</b> Fuel/Water Separator (1878042-C91)..... <b>PF7978</b> Fuel Strainer (1873910-C91)..... <b>PF7994</b> Fuel Kit (1884207-C91)..... <b>PF9914 KIT</b> Fuel Kit (1876533-C93)..... <b>BF9858 KIT</b> Breather (7/12/2012-on) (7085773-C91)..... <b>N/S</b>	MaxxFace DT (7.6L) Dual-Flow Lube (To 2011) (1842639-C91)..... <b>BD7250</b> Lube (2012-on) (1889124-C91).... <b>B7503</b> Fuel/Water Separator (1878042-C91)..... <b>PF7978</b> Fuel/Water Separator (1822638-C91)..... <b>PF7779</b> Fuel Strainer (1873910-C91)..... <b>PF7994</b> Fuel Kit (1876533-C93)..... <b>BF9858 KIT</b>	T444E (7.3L) Lube (1814562-C1)..... <b>B7039</b> Opt. Fuel/Water Separator Spin-on..... <b>BF1345-SP</b> Fuel Ele..... <b>PF7678</b> Coolant (Fleetguard WF2071)..... <b>BW5071</b>
MaxxFace 9 (9.3L) Dual-Flow Lube (To 2011) (1842639-C91)..... <b>BD7250</b> Lube (2012-on) (1889124-C91).... <b>B7503</b> Lube Centrifuge (2012-on) (2606467-C91)..... <b>BC7485 +</b> Lube (1885920C2)..... <b>B40053</b> Fuel/Water Separator (1842638-C92)..... <b>PF7779</b> Fuel/Water Separator (1878042-C92)..... <b>PF7978</b> Fuel Strainer (1873910-C91)..... <b>PF7994</b>	N9 (9.3L) Lube (1884508C2)..... <b>B7503</b>	V304 Lube Spin-on..... <b>B167</b> Fuel Ele..... <b>PF827</b>
N9 (9.3L) Lube (1884508C2)..... <b>B7503</b>	N10 (9.3L) Lube (1884508C2)..... <b>B7503</b>	V345 Lube Spin-on..... <b>B167</b> Fuel Ele. (531546-R91)..... <b>PF827</b> Opt. Air (446661-C1)..... <b>PA2061</b> Opt. Air (446661-C2)..... <b>PA2092</b>
N13 (12.4L) Lube (3007498-C94)..... <b>P7494</b> Lube Centrifuge (Opt.) (2606467-C91)..... <b>BC7485 +</b> Fuel/Water Separator (3004473-C93)..... <b>PF7986</b> Fuel Screen (3004474-C92)..... <b>PF7939 +</b>	N13 (12.4L) Lube (3007498-C94)..... <b>P7494</b> Lube Centrifuge (Opt.) (2606467-C91)..... <b>BC7485 +</b> Fuel/Water Separator (3004473-C93)..... <b>PF7986</b> Fuel Screen (3004474-C92)..... <b>PF7939 +</b>	V392 Lube Spin-on..... <b>B167</b> Fuel Ele. (531546-R91)..... <b>PF827</b> Opt. Air (446661-C1)..... <b>PA2061</b> Opt. Air (446661-C2)..... <b>PA2092</b>
		V401, VS401 B-P Lube Sock (1956-57)..... <b>CU406<sup>90</sup></b> Lube Ele. (1958)..... <b>PT154</b> Lube Ele. (1959-on)..... <b>P204</b> Air (COE Series) (150868-R91).... <b>PA655</b> Opt. Air (204514-R91)..... <b>PA638</b>
		V461 B-P Lube Sock (1956-57)..... <b>CU406<sup>90</sup></b> Lube Ele. (1958)..... <b>PT154</b> Lube Ele. (1959-on)..... <b>P204</b> Air (COE Series) (150868-R91).... <b>PA655</b> Opt. Air (204514-R91)..... <b>PA638</b>

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Engines (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
V478, VS478	400 Transtar Series w/Cummins Eng. (Cont'd)	1452SC w/V8 7.3L Eng. (Cont'd)
B-P Lube Sock (1956-57)..... <b>CU406<sup>90</sup></b>	11 7/32 In. Fuel Spin-on..... <b>BF596 +</b>	Fuel/Water Separator Spin-on
Lube Ele. (1958)..... <b>PT154</b>	Air (250552-C92)..... <b>PA1637-FN</b>	(Open End for Bowl)
Lube Ele. (1959-on)..... <b>P204</b>	Breather Ele. (w/Turbo) (255963) <b>PA643</b>	(1813104C91)..... <b>BF1222-O +</b>
Air (COE Series) (150868-R91).... <b>PA655</b>	Breather Ele. (w/o Turbo)	Fuel/Water Separator Spin-on
Opt. Air (204514-R91)..... <b>PA638</b>	(256837)..... <b>PA1627</b>	(w/SP) (1813104C91)..... <b>BF1222-SP +</b>
V537	Turbocharger..... <b>BT112</b>	Fuel (1804459C1)..... <b>BF786</b>
F-F Lube Spin-on..... <b>[2] B167</b>	400 Transtar Series w/GMC 6-71, 6V-71 Eng.	Air (588213C1)..... <b>PA2116</b>
B-P Lube Ele..... <b>C750-E +</b>	F-F Lube Ele..... <b>P20-HD</b>	Steering (w/o Gskt.)
Fuel Ele. (296951-R91)..... <b>PF821-S</b>	B-P Lube Ele..... <b>P52</b>	(279294C92)..... <b>PT951</b>
V549, VS549 (9.0L)	P. Fuel Sock..... <b>F916-C</b>	Steering (w/Gskt.) (279294C92).. <b>PT903</b>
B-P Lube Sock (1956-57)..... <b>CU406<sup>90</sup></b>	S. Fuel Ele..... <b>PF902</b>	1552SC w/T444E (7.3L) Eng. (To 1998)
Lube Ele. (1958)..... <b>PT154</b>	Tube-Type Air (6483682)..... <b>PA1781</b>	Lube (1814562C1)..... <b>B7039</b>
Lube Ele. (1959-on)..... <b>P204</b>	Air (8873271)..... <b>PA1637-FN</b>	Fuel/Water Separator
Air (COE Series) (150868-R91).... <b>PA655</b>	400 Transtar Series w/GMC 8V-71 Eng.	(1677004C91)..... <b>BF1345-O</b>
Opt. Air (204514-R91)..... <b>PA638</b>	F-F Lube Ele..... <b>P20-HD</b>	Fuel (1822631C91)..... <b>PF7678</b>
V605	P. Fuel Spin-on..... <b>BF5800 +</b>	Coolant (Fleetguard BW5071).... <b>BW5071</b>
F-F Lube Spin-on..... <b>[2] B167</b>	S. Fuel Spin-on..... <b>BF5810</b>	1552SC w/T444E (7.3L) Eng. (1999-on)
B-P Lube Ele..... <b>C750-E +</b>	Air (281667-C91)..... <b>PA1750-FN</b>	Lube (1814562C1)..... <b>B7039</b>
V800	Air (672019-C1)..... <b>PA2414</b>	Fuel/Water Separator
Lube Ele..... <b>[2] PT86-HD</b>	405 Series w/V401, V461, V549 Eng.	(1677004C91)..... <b>BF1345-O</b>
Lube Spin-on..... <b>[2] B97</b>	Lube Ele. (1959-on)..... <b>P204</b>	Fuel (1825864C92)..... <b>PF7698</b>
P. Fuel/Water Separator..... <b>BF891</b>	Air (150868-R91)..... <b>PA655</b>	Coolant (Fleetguard BW5071).... <b>BW5071</b>
P. Fuel Spin-on..... <b>BF979 +</b>	Air (204514-R91)..... <b>PA638</b>	1600 Loadstar Series w/V345 Eng.
7 11/32 In. S. Fuel Spin-on..... <b>BF588</b>	500 Series w/Nissan FE6 Eng.	Lube Spin-on (427207-C1)..... <b>B167</b>
8 11/16 In. S. Fuel Spin-on..... <b>BF888</b>	Fuel Spin-on..... <b>BF954 +</b>	Fuel Ele. (531546-R91)..... <b>PF827</b>
Opt. Air (420051-C1)..... <b>PA2333</b>	500 w/T444E (7.3L) Eng.	Opt. Air (446661-C1)..... <b>PA2061</b>
Opt. Air (472098-C1)..... <b>PA2429</b>	Lube (1814562C1)..... <b>B7039</b>	Opt. Air (446661-C2)..... <b>PA2092</b>
Coolant Spin-on..... <b>BW5137</b>	Fuel/Water Separator	1600 Loadstar Series w/DT466 Eng.
VT275 (4.5L)	(1677004C91)..... <b>BF1345-O</b>	Lube (1811953-C1)..... <b>B309</b>
Lube (1847174C91)..... <b>P7423</b>	Fuel (1822631C91)..... <b>PF7678</b>	Lube (675617-C91)..... <b>BT261</b>
Fuel (1847170-C93)..... <b>PF7812 KIT</b>	Coolant (Fleetguard WF2071).... <b>BW5071</b>	P. Fuel Spin-on..... <b>BF979 +</b>
VT365 (6.0L) Turbo Diesel	700, 900 w/Nissan NE6, NE6T Eng.	S. Fuel Spin-on..... <b>BF588</b>
Lube (w/o Screw on Cap)	Lube (15274-99186)..... <b>BT234</b>	1624 S Series w/D170 Eng.
(1844588-C91)..... <b>P7235</b>	Fuel Spin-on..... <b>BF970 +</b>	Lube Spin-on..... <b>B167</b>
Lube (w/Screw on Cap) (Wix	O. Air..... <b>PA2504</b>	P. Fuel Spin-on..... <b>BF979 +</b>
57312)..... <b>P7436</b>	I. Air..... <b>PA2545</b>	S. Fuel Spin-on..... <b>BF888</b>
P. Fuel (1825864-C92)..... <b>PF7698</b>	Coolant..... <b>BW5137</b>	1624 S Series w/MV404 Eng.
<b>INTERNATIONAL</b>	1050B Cargostar Series w/Cat 1145, 1150	Lube Spin-on..... <b>B167</b>
<b>Trucks &amp; Buses</b>	Eng.	In-Line Fuel..... <b>BF840 +</b>
400 w/Nissan FE6 Eng.	Lube..... <b>[2] BT364</b>	Opt. Air (446661-C2)..... <b>PA2092</b>
Lube (15274-99186)..... <b>BT234</b>	Fuel..... <b>BF583</b>	1650 Loadstar Series w/D150 Eng.
Fuel Spin-on..... <b>BF954 +</b>	1050B Cargostar Series w/DV550B Eng.	Lube Spin-on..... <b>B167</b>
400 w/T444E (7.3L) Eng.	Lube Spin-on..... <b>[2] B167</b>	P. Fuel Spin-on..... <b>BF979 +</b>
Lube (1814562C1)..... <b>B7039</b>	P. Fuel Spin-on..... <b>BF979 +</b>	S. Fuel Spin-on..... <b>BF888</b>
Fuel/Water Separator	S. Fuel Spin-on..... <b>BF588</b>	1652SC w/V8-420 (6.9L) Diesel Eng.
(1677004C91)..... <b>BF1345-O</b>	1452SC w/V8-420 (6.9L) Diesel Eng.	Lube (1804442C1)..... <b>B134</b>
Fuel (1822631C91)..... <b>PF7678</b>	Lube (1804442C1)..... <b>B134</b>	Fuel/Water Separator
Coolant (Fleetguard WF2071).... <b>BW5071</b>	Fuel/Water Separator	(702255C1)..... <b>BF891</b>
400 Transtar Series w/Cummins Eng.	(702255C1)..... <b>BF891</b>	Fuel (1804459C1)..... <b>BF786</b>
F-F Lube Bag..... <b>P996</b>	Fuel (1804459C1)..... <b>BF786</b>	1652SC w/T444E (7.3L) Eng.
F-F Lube Ele..... <b>P999-HD</b>	1452SC w/V8 7.3L Eng.	Lube (1804442C1)..... <b>B134</b>
F-F Lube Spin-on..... <b>B196 +</b>	Lube (1804442C1)..... <b>B134</b>	Fuel/Water Separator Box-Style
B-P Lube Ele..... <b>C750-E +</b>	Fuel/Water Separator Box-Style	(548348C1)..... <b>BF912</b>
Fuel/Water Separator..... <b>BF1212 +</b>	(548348C1)..... <b>BF912</b>	Fuel/Water Separator Spin-on
4 3/8 In. Fuel Spin-on..... <b>BF948 +</b>	Fuel/Water Separator Spin-on	(w/o SP) (1813104C91)..... <b>BF1222 +</b>
5 3/4 In. Fuel Spin-on..... <b>BF957 +</b>	(w/o SP) (1813104C91)..... <b>BF1222 +</b>	

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.

Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
1652SC w/T444E (7.3L) Eng. (Cont'd)	1654 w/ V8-420 (6.9L) Diesel Eng.	1754 w/DT360 (5.9L) Eng. (Cont'd)
<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (1813104C91)..... <b>BF1222-O +</b>	<b>Lube</b> (1804442-C1)..... <b>B134</b>	<b>Coolant</b> (w/4 Units BTE) (1801090-C1)..... <b>BW5137</b>
<b>Fuel/Water Separator Spin-on</b> (w/SP) (1813104C91)..... <b>BF1222-SP +</b>	<b>Fuel/Water Separator</b> (702255-C1)..... <b>BF891</b>	<b>Coolant</b> (w/8 Units BTA+) (Fleetguard WF2073)..... <b>BW5073</b>
<b>Fuel/Water Separator Spin-on</b> (1677004C91)..... <b>BF1345-O</b>	<b>Fuel/Water Separator</b> (598435-C1)..... <b>BF1212 +</b>	<b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b>
<b>Fuel Ele.</b> (1822631C91)..... <b>PF7678</b>	<b>P. Fuel</b> ..... <b>BF891</b>	<b>Coolant</b> (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b>
<b>Fuel Spin-on</b> (1804459C1)..... <b>BF786</b>	<b>S. Fuel</b> (1804459-C1)..... <b>BF786</b>	<b>Steering</b> (1660345-C91)..... <b>PT8407</b>
<b>Air</b> (588213C1)..... <b>PA2116</b>	<b>Single Air</b> ..... <b>PA2116</b>	
<b>2 25/32 In. Steering</b> (w/o Gskt.) (279294C92)..... <b>PT951</b>	1654 w/V8-444 (7.3L) Diesel Eng.	1754 w/DTA360 Eng.
<b>2 25/32 In. Steering</b> (w/Gskt.) (279294C92)..... <b>PT903</b>	<b>Lube</b> (1804442-C1)..... <b>[2] B134</b>	<b>Lube</b> ..... <b>B299 +</b>
<b>5 1/32 In. Steering</b> (1695528C1).. <b>PT9419-MPG</b>	<b>Fuel/Water Separator</b> ..... <b>BF1222 +</b>	<b>Fuel/Water Separator</b> (1808623-C1)..... <b>BF7584 +</b>
1652SC w/DT360 (5.9L) Eng.	<b>Fuel/Water Separator</b> (702255-C1)..... <b>BF891</b>	<b>Fuel</b> (1809789-C1)..... <b>BF7629 +</b>
<b>Lube</b> (1811953C1)..... <b>B309</b>	<b>Fuel/Water Separator</b> (598435-C1)..... <b>BF1212 +</b>	<b>O. Air</b> (476741-C1)..... <b>PA2521</b>
<b>Fuel/Water Separator Box-Style</b> (548348C1)..... <b>BF912</b>	<b>Air</b> (588213-C1)..... <b>PA2116</b>	<b>I. Air</b> (Fleetguard AF987)..... <b>PA2522</b>
<b>Fuel/Water Separator Spin-on</b> (1677004C91)..... <b>BF1345-O</b>	1654 w/V8-551 (9.0L) Diesel Eng.	<b>Coolant</b> (w/4 Units BTE) (1801090-C1)..... <b>BW5137</b>
<b>Fuel</b> (1809789C1)..... <b>BF7629 +</b>	<b>Lube</b> ..... <b>B167</b>	<b>Coolant</b> (w/8 Units BTA+) (Fleetguard WF2073)..... <b>BW5073</b>
<b>Radial Seal Air</b> (1691027C1)..... <b>RS2863</b>	<b>P. Fuel</b> ..... <b>BF984</b>	<b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b>
<b>Radial Seal XP Air</b> (1691027C1). <b>RS2863XP</b>	<b>S. Fuel</b> ..... <b>BF588</b>	<b>Coolant</b> (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b>
<b>Steering</b> (w/o Gskt.) (279294C92)..... <b>PT951</b>	<b>Air</b> (478974-C1)..... <b>PA2520</b>	<b>Steering</b> (1660345-C91)..... <b>PT8407</b>
<b>Steering</b> (w/Gskt.) (279294C92).. <b>PT903</b>	1724 w/V345 Eng.	1754 w/DT466 (7.6L) Eng.
1652SC w/VT365 (6.0L) Eng.	<b>Lube Spin-on</b> ..... <b>B167</b>	<b>Lube Spin-on</b> ..... <b>[2] B299 +</b>
<b>Lube</b> (1844588C91)..... <b>P7235</b>	<b>Fuel Ele.</b> (531546-R91)..... <b>PF827</b>	<b>P. Fuel Spin-on</b> ..... <b>BF979 +</b>
<b>Lube</b> (1843162C91)..... <b>PF7698</b>	<b>Opt. Air</b> (446661-C2)..... <b>PA2092</b>	<b>S. Fuel Spin-on</b> ..... <b>BF588</b>
<b>Fuel</b> (Motorcraft FD4606)..... <b>PF7852 KIT</b>	1724 w/MV404 (6.6L) Eng.	<b>Air</b> (478974-C1)..... <b>PA2520</b>
<b>Radial Seal Air</b> (1691027C1)..... <b>RS2863</b>	<b>Lube Spin-on</b> ..... <b>B167</b>	1754 w/DV550 (9.0L) Eng.
<b>Radial Seal XP Air</b> (1691027C1). <b>RS2863XP</b>	<b>In-Line Fuel</b> ..... <b>BF840 +</b>	<b>Lube Ele.</b> (313117-C92)..... <b>[2] P276</b>
1652UPS w/V8-444 (7.3L) Turbo Diesel Eng.	<b>Opt. Air</b> (446661-C2)..... <b>PA2092</b>	<b>Lube Spin-on</b> (427207-C2)..... <b>[2] B167</b>
<b>Lube</b> (1804442C1)..... <b>B134</b>	1750 Loadstar Series w/Cat 1145 Eng.	<b>P. Fuel Spin-on</b> (S/N 7164-up).... <b>BF979 +</b>
<b>Fuel/Water Separator</b> (w/Drain) (Ford E8TZ9N184A)..... <b>BF1222 +</b>	<b>Lube</b> ..... <b>[2] BT364</b>	<b>S. Fuel Ele.</b> (S/N 5118-7163)..... <b>PF225</b>
<b>Fuel/Water Separator</b> (w/Sensor Port) (Ford E8TZ9N184A)..... <b>BF1222-SP +</b>	<b>Fuel</b> ..... <b>BF583</b>	<b>S. Fuel Spin-on</b> (S/N 7164-up).... <b>BF888</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (Ford E8TZ9N184A)..... <b>BF1222-O +</b>	1750 Loadstar Series w/Cat 3208 Eng.	<b>Air</b> (S/N 36674-up) (303642-C91) <b>PA1786</b>
1652UPS w/T444E (7.3L) Eng. (To 1998)	<b>Lube</b> (9L9200)..... <b>[2] BT364</b>	1754 w/V8-551 (9.0L) Eng.
<b>Lube</b> (1814562C1)..... <b>B7039</b>	<b>Lube</b> (9N5570)..... <b>[2] BT230 +</b>	<b>Lube</b> ..... <b>B167</b>
<b>Fuel/Water Separator</b> (1677004C91)..... <b>BF1345-O</b>	<b>Box-Style Fuel/Water Separator</b> . <b>BF912</b>	<b>P. Fuel</b> ..... <b>BF984</b>
<b>Fuel</b> (1822631C91)..... <b>PF7678</b>	<b>Fuel Spin-on</b> ..... <b>BF970 +</b>	<b>S. Fuel</b> ..... <b>BF588</b>
<b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b>	1750 Loadstar Series w/D150, D170 Engs.	1800 Loadstar Series w/D301 Diesel Eng.
1652UPS w/T444E (7.3L) Eng. (1999-on)	<b>Lube Spin-on</b> ..... <b>B167</b>	<b>Lube Ele.</b> ..... <b>PT185</b>
<b>Lube</b> (1814562C1)..... <b>B7039</b>	<b>P. Fuel Spin-on</b> ..... <b>BF979 +</b>	<b>S. Fuel Ele.</b> ..... <b>PF828</b>
<b>Fuel/Water Separator</b> (1677004C91)..... <b>BF1345-O</b>	<b>S. Fuel Spin-on</b> ..... <b>BF888</b>	1800 Loadstar Series w/V345, V392 Engs.
<b>Fuel</b> (1825864C92)..... <b>PF7698</b>	1750 Loadstar Series w/404 Gas Eng.	<b>Lube Spin-on</b> ..... <b>B167</b>
<b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b>	<b>5 9/32 In. Lube Spin-on</b> ..... <b>B2 +</b>	<b>Fuel</b> (531546-R91)..... <b>PF827</b>
1652UPS w/T444E (7.3L) Eng. (1999-on)	<b>7 1/8 In. Lube Spin-on</b> ..... <b>B167</b>	<b>Opt. Air</b> (446661-C1)..... <b>PA2061</b>
<b>Lube</b> (1814562C1)..... <b>B7039</b>	<b>In-Line Fuel</b> ..... <b>BF840 +</b>	<b>Opt. Air</b> (446661-C2)..... <b>PA2092</b>
<b>Fuel/Water Separator</b> (1677004C91)..... <b>BF1345-O</b>	<b>Opt. Air</b> (446661-C2)..... <b>PA2092</b>	1800 Loadstar Series w/VS401, VS478 Engs.
<b>Fuel</b> (1825864C92)..... <b>PF7698</b>	1754 w/DT360 (5.9L) Eng.	<b>Lube</b> (213445-R91)..... <b>P204</b>
<b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b>	<b>Lube</b> ..... <b>B299 +</b>	1800 Loadstar Series w/Perkins D354 Eng.
	<b>Fuel/Water Separator</b> (1808623-C1)..... <b>BF7584 +</b>	<b>Lube</b> ..... <b>PT12</b>
	<b>Fuel</b> (1809789-C1)..... <b>BF7629 +</b>	<b>Can-Type Fuel</b> (796051-R91)..... <b>BF825 +</b>
	<b>O. Air</b> (476741-C1)..... <b>PA2521</b>	
	<b>I. Air</b> (Fleetguard AF987)..... <b>PA2522</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
1824 w/MV404 (6.6L) Eng. 7 1/8 In. Lube Spin-on..... B167 In-Line Fuel..... BF840 + Opt. Air (446661-C2)..... PA2092	1890 Loadstar Series w/GMC 6V-53N Eng. F-F Lube Ele..... P20-HD B-P Lube Ele..... P52 P. Fuel Sock..... F916-C S. Fuel Ele..... PF906	1954 w/Cummins N14 (14.0L) Eng. Dual-Flow Lube (3318853)..... BD103 + F-F Lube (Standard Vers.) (Fleetguard LF670SC)..... B196 + F-F Lube (Ext. Life) (Fleetguard LF670SC)..... B96 + B-P Lube (3304232)..... B7577 Fuel/Water Separator (154789)... BF957-D + Fuel/Water Separator (3308638)... BF1212 + Coolant (w/4 Units BTA+) (3315116)..... BW5071
1824 w/MV446 (7.3L) Eng. 7 1/8 In. Lube Spin-on..... B167 In-Line Fuel..... BF840 + Opt. Air (446661-C2)..... PA2092	1890 Loadstar Series w/Perkins D354 Eng. Lube..... PT12 Can-Type Fuel (796051-R91)..... BF825 +	1954, 1955 w/Cat 3208 Eng. Lube (9L9200)..... [2] BT364 Lube (9N5570)..... [2] BT230 + Box-Style Fuel/Water Separator... BF912 Fuel Spin-on..... BF970 +
1824 w/v392 (6.4L) Eng. Lube (3059247R91)..... B167 Fuel Ele. (998429R91)..... PF827	1924 S w/MV446 (7.3L) Eng. Lube Spin-on..... B167 In-Line Fuel..... BF840 + Opt. Air (446661-C2)..... PA2092	1954, 1955 w/D170, D190 Engs. Lube Spin-on..... B167 P. Fuel Spin-on..... BF979 + S. Fuel Spin-on..... BF888
1850 Loadstar Series w/Cat 1145, 1150 Engs. Lube..... [2] BT364 Fuel..... BF583	1924 S w/MV404 (6.6L) Eng. Lube Spin-on..... B167 In-Line Fuel..... BF840 + Opt. Air (446661-C2)..... PA2092	1954, 1955 w/M404, MV466 Engs. 7 1/8 In. Lube Spin-on..... B167 In-Line Fuel..... BF840 + Opt. Air (446661-C2)..... PA2092
1850 Loadstar Series w/GMC 6V-53N Eng. F-F Lube Ele..... P20-HD + B-P Lube Ele..... P52 P. Fuel Sock..... F916-C S. Fuel Ele..... PF906	1924 S, 1925 S w/Cat 3208 Eng. Lube (9L9200)..... [2] BT364 Lube (9N5570)..... [2] BT230 + Box-Style Fuel/Water Separator... BF912 Fuel Spin-on..... BF970 +	1954, 1955 w/DT360 Eng. Lube (1811953-C1)..... [2] B309 Fuel/Water Separator (1808623-C1)..... BF7584 + Fuel (1809789-C1)..... BF7629 + Single Air (470185-C92)..... PA2521 O. Air (476741-C1)..... PA2521 I. Air (Fleetguard AF987)..... PA2522 Steering (1660345-C91)..... PT8407
1854 w/Cat 3208 Eng. Lube (9L9200)..... [2] BT364 Lube (9N5570)..... [2] BT230 + Box-Style Fuel/Water Separator... BF912 Fuel Spin-on..... BF970 +	1925 S w/MV446 (7.3L) Eng. Lube Spin-on..... B167 In-Line Fuel..... BF840 + Opt. Air (446661-C2)..... PA2092	1954, 1955 w/DT466 (7.6L) Eng. Lube (1808896-C1)..... [2] B299 + Lube (1811953-C1)..... [2] B309 Fuel/Water Separator Spin-on (702255-C1)..... BF891 Fuel/Water Separator Spin-on (598435-C1)..... BF1212 + Fuel Ele. (854569)..... PF827 P. Fuel Spin-on..... BF979 + S. Fuel Spin-on..... BF588 O. Air (476741-C1)..... PA2521 Opt. I. Air (Fleetguard AF987)..... PA2522 O. Air (478974-C1)..... PA2520 I. Air (530778-C1)..... PA2586 Coolant..... BW5137 Steering (1653998-C91)..... P7134
1854 w/D190 Eng. Lube Spin-on..... B167 P. Fuel Spin-on..... BF979 + S. Fuel Spin-on..... BF888	1925 S w/MV404 (6.6L) Eng. Lube Spin-on..... B167 In-Line Fuel..... BF840 + Opt. Air (446661-C2)..... PA2092	1954, 1955 w/DTA466, DTI466 Engs. Lube (1808896-C1)..... [2] B299 + Lube (1811953-C1)..... [2] B309 Fuel/Water Separator Spin-on (702255-C1)..... BF891 Fuel/Water Separator Spin-on (598435-C1)..... BF1212 + Fuel Ele. (854569)..... PF827 P. Fuel Spin-on..... BF979 +
1854 w/DT360 (5.9L) Eng. Lube (1808896C1)..... B299 + Lube (1811953C1)..... B309 Fuel/Water Separator (1808623C1)..... BF7584 + Fuel (1809789C1)..... BF7629 + Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071 Coolant (w/12 Units BTA+) (1820361C1)..... BW5074 Coolant (w/8 Units BTE) (1801089C1)..... BW5139	1925 S w/DT466 Eng. Lube (1808896-C1)..... [2] B299 + Lube (1811953-C1)..... [2] B309 P. Fuel Spin-on..... BF979 + S. Fuel Spin-on..... BF588 Air (476741-C1)..... PA2521	1954, 1955 w/DTA466, DTI466 Engs. Lube (1808896-C1)..... [2] B299 + Lube (1811953-C1)..... [2] B309 Fuel/Water Separator Spin-on (702255-C1)..... BF891 Fuel/Water Separator Spin-on (598435-C1)..... BF1212 + Fuel Ele. (854569)..... PF827 P. Fuel Spin-on..... BF979 + S. Fuel Spin-on..... BF588 O. Air (476741-C1)..... PA2521 Opt. I. Air (Fleetguard AF987)..... PA2522 O. Air (478974-C1)..... PA2520 I. Air (530778-C1)..... PA2586 Coolant..... BW5137 Steering (1653998-C91)..... P7134
1854 w/DT466 (7.6L) Eng. Lube (1808896-C1)..... [2] B299 + Lube (1811953-C1)..... [2] B309 5 9/32 In. Fuel Spin-on..... BF984 8 23/32 In. P. Fuel Spin-on..... BF979 + S. Fuel Spin-on..... BF588 O. Air (476741-C1)..... PA2521 I. Air (482644-C1)..... PA2522 Coolant (Maintenance)..... BW5137	1954 w/Detroit Diesel 6V-92N (9.0L) Eng. Lube (23530407)..... B95 + Lube (23530408)..... B95-MPG + P. Fuel (23530706)..... BF5800 + S. Fuel (23530707)..... BF5810 S. Fuel (23530645)..... BF5815	1954, 1955 w/DTA466, DTI466 Engs. Lube (1808896-C1)..... [2] B299 + Lube (1811953-C1)..... [2] B309 Fuel/Water Separator Spin-on (702255-C1)..... BF891 Fuel/Water Separator Spin-on (598435-C1)..... BF1212 + Fuel Ele. (854569)..... PF827 P. Fuel Spin-on..... BF979 + S. Fuel Spin-on..... BF588 O. Air (476741-C1)..... PA2521 Opt. I. Air (Fleetguard AF987)..... PA2522 O. Air (478974-C1)..... PA2520 I. Air (530778-C1)..... PA2586 Coolant..... BW5137 Steering (1653998-C91)..... P7134
1854 w/DV550 (9.0L) Eng. Lube Ele..... [2] P276 Lube Spin-on..... [2] B167 P. Fuel Spin-on (S/N 7164-up).... BF979 + S. Fuel Ele. (S/N 5118-7163)..... PF225 S. Fuel Spin-on (S/N 7164-up).... BF888 Air (S/N 36674-up) (303642-C91) PA1786	1954 w/Cummins L10 (10.0L) Eng. Dual-Flow Lube (3318853)..... BD103 + F-F Lube (Standard Vers.) (Fleetguard LF670SC)..... B196 + F-F Lube (Ext. Life) (Fleetguard LF670SC)..... B96 + B-P Lube (3304232)..... B7577 Fuel/Water Separator (154789)... BF957-D + Coolant (w/4 Units BTA+) (3315116)..... BW5071 Coolant (w/15 Units BTA+) (Fleetguard WF2075)..... BW5075	1954, 1955 w/DTA466, DTI466 Engs. Lube (1808896-C1)..... [2] B299 + Lube (1811953-C1)..... [2] B309 Fuel/Water Separator Spin-on (702255-C1)..... BF891 Fuel/Water Separator Spin-on (598435-C1)..... BF1212 + Fuel Ele. (854569)..... PF827 P. Fuel Spin-on..... BF979 +

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>INTERNATIONAL Trucks &amp; Buses (cont'd)</b>	<b>INTERNATIONAL Trucks &amp; Buses (cont'd)</b>	<b>INTERNATIONAL Trucks &amp; Buses (cont'd)</b>
1954, 1955 w/DTA466, DTI466 Eng. (Cont'd)	2050 Fleetstar Series w/Cat 1160 Eng.	2070 Fleetstar Series w/Cummins Eng. (Cont'd)
S. Fuel Spin-on..... BF588	Lube..... [2] BT364	Fuel/Water Separator..... BF1212 +
Single Air (470185-C92)..... PA2521	Fuel..... BF583	4 3/8 In. Fuel Spin-on..... BF948 +
O. Air (476741-C1)..... PA2521	2050 Fleetstar Series w/Cat 3208 Eng.	5 3/4 In. Fuel Spin-on..... BF957 +
I. Air (Fleetguard AF987)..... PA2522	Lube (9N5570)..... [2] BT230 +	11 7/32 In. Fuel Spin-on..... BF596 +
O. Air (478974-C1)..... PA2520	Lube (9L9200)..... [2] BT364	Air (420051-C1)..... PA2333
I. Air (530778-C1)..... PA2586	Box-Style Fuel/Water Separator. BF912	Breather Ele. (w/Turbo) (255963) PA643
Coolant..... BW5137	Fuel Spin-on..... BF970 +	Breather Ele. (w/o Turbo) (256837)..... PA1627
Steering (1653998-C91)..... P7134	2050 Fleetstar Series w/Cat 3406 Eng.	Turbocharger..... BT112
1954, 1955 w/V8-551 (9.0L) Eng.	Lube..... B99 +	2070A Fleetstar Series w/GMC 6-71N Eng.
Lube..... B167	Fuel Spin-on..... BF614 +	F-F Lube Ele..... P20-HD
P. Fuel..... BF984	Coolant..... BW5137	P. Fuel Spin-on..... BF5800 +
S. Fuel..... BF588	2050 Fleetstar Series w/Cummins Eng.	S. Fuel Spin-on..... BF5810
2000 Fleetstar Series w/Cummins Eng.	F-F Lube Ele..... P999-HD	2125 S Series w/V537 Eng.
F-F Lube Bag..... P996	F-F Lube Spin-on..... B196 +	F-F Lube Spin-on..... [2] B167
F-F Lube Ele..... P999-HD	F-F Lube Bag..... P996	Fuel Ele. (296951-R91)..... PF821-S
F-F Lube Spin-on..... B196 +	B-P Lube Ele..... C750-E +	2125, 2155 w/Cat 3208 Eng.
B-P Lube Ele..... C750-E +	Fuel/Water Separator..... BF1212 +	Lube (9L9200)..... [2] BT364
Fuel/Water Separator..... BF1212 +	4 3/8 In. Fuel Spin-on..... BF948 +	Lube (9N5570)..... [2] BT230 +
4 3/8 In. Fuel Spin-on..... BF948 +	5 3/4 In. Fuel Spin-on..... BF957 +	Box-Style Fuel/Water Separator. BF912
5 3/4 In. Fuel Spin-on..... BF957 +	11 7/32 In. Fuel Spin-on..... BF596 +	Fuel Spin-on..... BF970 +
11 7/32 In. Fuel Spin-on..... BF596 +	Breather Ele. (w/Turbo) (255963) PA643	2125, 2155 w/DT466 (7.6L) Eng.
Air (250552-C92)..... PA1637-FN	Breather Ele. (w/o Turbo) (256837)..... PA1627	Lube (1808896-C1)..... [2] B299 +
Breather Ele. (w/Turbo) (255963) PA643	Turbocharger..... BT112	Lube (1811953-C1)..... [2] B309
Breather Ele. (w/o Turbo) (256837)..... PA1627	2050 Fleetstar Series w/GMC 6V-53 Eng.	P. Fuel Spin-on..... BF979 +
Turbocharger..... BT112	F-F Lube Ele..... P20-HD	S. Fuel Spin-on..... BF588
2000 Fleetstar Series w/GMC 6-71, 6V-71N Eng.	B-P Lube Ele..... P52	Air (476741-C1)..... PA2521
F-F Lube Ele..... P20-HD	P. Fuel Sock..... F916-C	2125, 2155 w/DTA466, DTI466 Eng.
P. Fuel Sock..... F916-C	S. Fuel Ele..... PF906	Lube (1808896-C1)..... [2] B299 +
S. Fuel Ele..... PF902	2050 Fleetstar Series w/D170, D190 Eng.	Lube (1811953-C1)..... [2] B309
Tube-Type Air (6483682)..... PA1781	Lube Spin-on..... B167	P. Fuel Spin-on..... BF979 +
Air (8873271)..... PA1637-FN	P. Fuel Spin-on..... BF979 +	S. Fuel Spin-on..... BF588
2000 Fleetstar Series w/GMC 8V-71N Eng.	S. Fuel Spin-on..... BF888	Air (476741-C1)..... PA2521
F-F Lube Ele..... P20-HD	2050 Fleetstar Series w/DT466 Eng.	2155 w/V8-551 (9.0L) Diesel Eng.
P. Fuel Ele..... PF845	Lube (1808896-C1)..... [2] B299 +	Lube (427207C3)..... B167
S. Fuel Ele..... PF902	Lube (1811953-C1)..... [2] B309	P. Fuel (625625C1)..... BF984
Air (304766-C91)..... PA1676-FN +	7 In. P. Fuel Spin-on..... BF991	S. Fuel (672603C2)..... BF588
2000 Fleetstar Series w/RD372, RD406, RD450, RD501 Eng.	S. Fuel Spin-on..... BF588	2275 w/Cat 3406 Eng.
F-F Lube Ele..... P204	Steering (279294-C91)..... PT951	F-F Lube Spin-on..... B99 +
B-P Lube Sock..... CU406 <sup>90</sup>	2050 Fleetstar Series w/DV550B Eng.	B-P Lube Ele..... C750-E +
In-Line Fuel..... BF840 +	Lube Ele..... [2] P276	Fuel Spin-on..... BF614 +
2010 Fleetstar Series w/VS401, VS478, VS549 Eng.	Lube Spin-on..... [2] B167	Coolant Spin-on..... BW5137
Lube Ele. (1959-on)..... P204	P. Fuel Spin-on..... BF979 +	2275 w/Cummins N14 (14.0L) Eng.
2010 Fleetstar Series w/RD450, RD501 Eng.	S. Fuel Ele. (S/N 5118-7163)..... PF225	Dual-Flow Lube (3318853)..... BD103 +
F-F Lube Ele..... P204	S. Fuel Spin-on..... BF888	F-F Lube (Standard Vers.) (Fleetguard LF670SC)..... B196 +
B-P Lube Sock..... CU406 <sup>90</sup>	3 In. Air (303642-C91)..... PA1786	F-F Lube (Ext. Life) (Fleetguard LF670SC)..... B96 +
In-Line Fuel..... BF840 +	8 1/2 In. Air (461236-C1)..... PA2473	B-P Lube (3304232)..... B7577
Opt. Air (204514-R91)..... PA638	2070 Fleetstar Series w/Cat 3406 Eng.	Fuel/Water Separator (154789)..... BF957-D +
2010 Fleetstar Series w/V537 Eng.	Lube..... B99 +	Fuel/Water Separator (3308638)..... BF1212 +
Lube Spin-on..... [2] B167	Fuel Spin-on..... BF614 +	Coolant (w/4 Units BTA+) (3315116)..... BW5071
Fuel Ele. (296951-R91)..... PF821-S	Coolant Spin-on..... BW5137	
	2070 Fleetstar Series w/Cummins Eng.	
	F-F Lube Bag..... P996	
	F-F Lube Ele..... P999-HD	
	F-F Lube Spin-on..... B196 +	
	B-P Lube Ele..... C750-E +	

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
2275 w/Detroit Diesel 6-71N (7.0L) Eng. Lube (23530407)..... B95 + Lube (23530408)..... B95-MPG + P. Fuel (23530706)..... BF5800 + S. Fuel (23530707)..... BF5810 S. Fuel (23530645)..... BF5815	2276 S w/Detroit Diesel 6-71N (7.0L) Eng. (Cont'd) S. Fuel (23530707)..... BF5810 S. Fuel (23530645)..... BF5815	2554 w/Cummins ISM 10.8 (10.8L) Eng. Dual-Flow Lube (3101869)..... BD7154 + Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... BD50000 Fuel/Water Separator (3329289)..... BF1259 Crankcase Breather (3683918)..... CV15000 Coolant (w/o Chemicals) (Fleetguard WF2127)..... B5087 Coolant (Controlled Release BTA+) (Fleetguard WF2121)..... BW5250 Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071 Coolant (w/12 Units BTA+) (Fleetguard WF2074)..... BW5074
2275 w/Detroit Diesel 6V-92N (9.0L) Eng. Lube (23530407)..... B95 + P. Fuel (23530706)..... BF5800 + S. Fuel (23530707)..... BF5810 16 7/16 In. Air (476741C1)..... PA2521 18 1/2 In. Air (476743C1)..... PA2525	2276 S w/Detroit Diesel 6V-92N (9.0L) Eng. Lube (23530407)..... B95 + Lube (23530408)..... B95-MPG + P. Fuel (23530706)..... BF5800 + S. Fuel (23530707)..... BF5810 S. Fuel (23530645)..... BF5815	2554 w/Cummins N14 (14.0L) Eng. Dual-Flow Lube (Fleetguard LF3000)..... BD103 + F-F Lube (Standard Vers.) (Fleetguard LF670SC)..... B196 + F-F Lube (Ext. Life) (Fleetguard LF670SC)..... B96 + B-P Lube (3304232)..... B7577 Fuel/Water Separator (3329289)..... BF1259 Fuel/Water Separator (Fleetguard FS1212)..... BF1212 + O. Air (1674320-C2)..... PA2525 Opt. I. Air (1674319-C2)..... PA2526 Air Dryer (AD-9 System) (Bendix 107796)..... BA5377 Coolant (Fleetguard WF2074)..... BW5074 Coolant (Fleetguard WF2071)..... BW5071 Coolant (w/o Chemical) (Fleetguard WF2077)..... B5134 + Coolant (Controlled Release) (Nalcoo NF2088)..... BW5200 Opt. Trans. (Fuller 17237)..... B2 + 2 25/32 In. Steering (279294-C92)..... PT903 3 In. Steering (1696766-C1)..... P7178 3 31/32 In. Steering (1691121-C1)..... P106-HD
2275 w/Detroit Diesel 8V-71N (9.3L) Eng. F-F Lube (23530407)..... B95 + F-F Lube (23530408)..... B95-MPG + B-P Lube Ele. (5570092)..... P52 P. Fuel (23530706)..... BF5800 + S. Fuel (23530707)..... BF5810 S. Fuel (23530645)..... BF5815	2276 S w/Detroit Diesel 8V-71N (9.3L) Eng. F-F Lube (23530407)..... B95 + F-F Lube (23530408)..... B95-MPG + B-P Lube Ele. (5570092)..... P52 P. Fuel (23530706)..... BF5800 + S. Fuel (23530707)..... BF5810 S. Fuel (23530645)..... BF5815	2554 w/Cummins N14 (14.0L) Eng. Dual-Flow Lube (Fleetguard LF3000)..... BD103 + Dual-Flow Lube (High Velocity) (Fleetguard LF9009)..... BD7309 + Fuel/Water Separator (Fleetguard FS1251)..... BF1226 Coolant (Fleetguard WF2073)..... BW5073
2275 w/V537 Eng. F-F Lube Spin-on..... [2] B167 B-P Lube Ele..... C750-E + Fuel Ele. (296951-R91)..... PF821-S	2350G w/Cummins 6C8.3 Eng. Dual-Flow Lube (Fleetguard LF3000)..... BD103 + Dual-Flow Lube (High Velocity) (Fleetguard LF9009)..... BD7309 + Fuel/Water Separator (Fleetguard FS1251)..... BF1226 Coolant (Fleetguard WF2073)..... BW5073	2554 w/Cummins N14 (14.0L) Eng. Dual-Flow Lube (Fleetguard LF3000)..... BD103 + F-F Lube (Standard Vers.) (Fleetguard LF670SC)..... B196 + F-F Lube (Ext. Life) (Fleetguard LF670SC)..... B96 + B-P Lube (3304232)..... B7577 Fuel/Water Separator (3329289)..... BF1259 Fuel/Water Separator (Fleetguard FS1212)..... BF1212 + O. Air (1674320-C2)..... PA2525 Opt. I. Air (1674319-C2)..... PA2526 Air Dryer (AD-9 System) (Bendix 107796)..... BA5377 Coolant (Fleetguard WF2074)..... BW5074 Coolant (Fleetguard WF2071)..... BW5071 Coolant (w/o Chemical) (Fleetguard WF2077)..... B5134 + Coolant (Controlled Release) (Nalcoo NF2088)..... BW5200 Opt. Trans. (Fuller 17237)..... B2 + 2 25/32 In. Steering (279294-C92)..... PT903 3 In. Steering (1696766-C1)..... P7178 3 31/32 In. Steering (1691121-C1)..... P106-HD
2275 w/V800 Eng. F-F Lube Spin-on..... B97 B-P Lube Ele..... C750-E + P. Fuel Spin-on..... BF979 + S. Fuel Spin-on..... BF888 Coolant Spin-on..... BW5137	2375 S w/Cummins L10 (10.0L) Eng. Dual-Flow Lube (3318853)..... BD103 + F-F Lube (Standard Vers.) (Fleetguard LF670SC)..... B196 + F-F Lube (Ext. Life) (Fleetguard LF670SC)..... B96 + B-P Lube (3304232)..... B7577 Fuel/Water Separator (154789)..... BF957-D + Coolant (w/4 Units BTA+) (3315116)..... BW5071 Coolant (w/15 Units BTA+) (Fleetguard WF2075)..... BW5075	2554 w/DTA466C (7.6L) Eng. 7 5/32 In. Lube (1808896-C1)..... [2] B299 + 7 3/8 In. Lube (1811953-C1)..... [2] B309 12 3/32 In. Lube (1819452-C1)..... B7030 B-P Lube Ele..... C750-E + 7 In. P. Fuel (1822588-C1)..... BF7629 + 8 23/32 In. P. Fuel..... BF979 + 4 27/32 In. S. Fuel (Fleetguard FF5052)..... BF788 7 11/32 In. S. Fuel..... BF588 O. Air (1674320-C1)..... PA2525 I. Air (1674319-C1)..... PA3480 Some I. Air (476741-C1)..... PA2521 Radial Seal Air (2005895-C1)..... RS3530 Radial Seal XP Air (2005895-C1)..... RS3530XP Air Dryer (AD-9 System) (Bendix 107796)..... BA5377
2275 w/V8-551 (9.0L) Diesel Eng. Lube (427207C3)..... B167 P. Fuel (625625C1)..... BF984 S. Fuel (672603C2)..... BF588	2375 S w/DT466 (7.6L) Eng. Lube (1808896C1)..... [2] B299 + Lube (1811953C1)..... [2] B309 Fuel/Water Separator Ele. (1842638C92)..... PF7779 Fuel (625625C1)..... BF984 Fuel (625627C1)..... BF979 + Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071 Coolant (w/12 Units BTA+) (1820361C1)..... BW5074	2554 w/DTA466C (7.6L) Eng. 7 5/32 In. Lube (1808896-C1)..... [2] B299 + 7 3/8 In. Lube (1811953-C1)..... [2] B309 12 3/32 In. Lube (1819452-C1)..... B7030 B-P Lube Ele..... C750-E + 7 In. P. Fuel (1822588-C1)..... BF7629 + 8 23/32 In. P. Fuel..... BF979 + 4 27/32 In. S. Fuel (Fleetguard FF5052)..... BF788 7 11/32 In. S. Fuel..... BF588 O. Air (1674320-C1)..... PA2525 I. Air (1674319-C1)..... PA3480 Some I. Air (476741-C1)..... PA2521 Radial Seal Air (2005895-C1)..... RS3530 Radial Seal XP Air (2005895-C1)..... RS3530XP Air Dryer (AD-9 System) (Bendix 107796)..... BA5377
2275, 2375 S w/GMC Diesel Eng. F-F Lube Ele..... P20-HD F-F Lube Spin-on..... B95 + B-P Lube Ele..... C750-E + P. Fuel Spin-on..... BF5800 + S. Fuel Spin-on..... BF5810 Air (476741-C1)..... PA2521 Air (476743-C1)..... PA2525 Coolant Spin-on..... BW5137	2375 S w/DT466 (7.6L) Eng. Lube (1808896C1)..... [2] B299 + Lube (1811953C1)..... [2] B309 Fuel/Water Separator Ele. (1842638C92)..... PF7779 Fuel (625625C1)..... BF984 Fuel (625627C1)..... BF979 + Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071 Coolant (w/12 Units BTA+) (1820361C1)..... BW5074	2554 w/DTA466C (7.6L) Eng. 7 5/32 In. Lube (1808896-C1)..... [2] B299 + 7 3/8 In. Lube (1811953-C1)..... [2] B309 12 3/32 In. Lube (1819452-C1)..... B7030 B-P Lube Ele..... C750-E + 7 In. P. Fuel (1822588-C1)..... BF7629 + 8 23/32 In. P. Fuel..... BF979 + 4 27/32 In. S. Fuel (Fleetguard FF5052)..... BF788 7 11/32 In. S. Fuel..... BF588 O. Air (1674320-C1)..... PA2525 I. Air (1674319-C1)..... PA3480 Some I. Air (476741-C1)..... PA2521 Radial Seal Air (2005895-C1)..... RS3530 Radial Seal XP Air (2005895-C1)..... RS3530XP Air Dryer (AD-9 System) (Bendix 107796)..... BA5377
2276 S w/Cummins N14 (14.0L) Eng. Dual-Flow Lube (3318853)..... BD103 + F-F Lube (Standard Vers.) (Fleetguard LF670SC)..... B196 + F-F Lube (Ext. Life) (Fleetguard LF670SC)..... B96 + B-P Lube (3304232)..... B7577 Fuel/Water Separator (154789)..... BF957-D + Fuel/Water Separator (3308638)..... BF1212 + Coolant (w/4 Units BTA+) (3315116)..... BW5071	2524, 2624, 2654, 2674 S Series w/V800 Eng. F-F Lube Spin-on..... B97 B-P Lube Ele..... C750-E + P. Fuel Spin-on..... BF979 + S. Fuel Spin-on..... BF888 Coolant Spin-on..... BW5137	2554 w/DTA466C (7.6L) Eng. 7 5/32 In. Lube (1808896-C1)..... [2] B299 + 7 3/8 In. Lube (1811953-C1)..... [2] B309 12 3/32 In. Lube (1819452-C1)..... B7030 B-P Lube Ele..... C750-E + 7 In. P. Fuel (1822588-C1)..... BF7629 + 8 23/32 In. P. Fuel..... BF979 + 4 27/32 In. S. Fuel (Fleetguard FF5052)..... BF788 7 11/32 In. S. Fuel..... BF588 O. Air (1674320-C1)..... PA2525 I. Air (1674319-C1)..... PA3480 Some I. Air (476741-C1)..... PA2521 Radial Seal Air (2005895-C1)..... RS3530 Radial Seal XP Air (2005895-C1)..... RS3530XP Air Dryer (AD-9 System) (Bendix 107796)..... BA5377
2276 S w/Detroit Diesel 6-71N (7.0L) Eng. Lube (23530407)..... B95 + Lube (23530408)..... B95-MPG + P. Fuel (23530706)..... BF5800 +		

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>INTERNATIONAL Trucks &amp; Buses (cont'd)</b>	<b>INTERNATIONAL Trucks &amp; Buses (cont'd)</b>	<b>INTERNATIONAL Trucks &amp; Buses (cont'd)</b>
2554 w/DTA466C (7.6L) Eng. (Cont'd)	2554 w/DT466 (7.6L) Eng. (Cont'd)	2574 w/Cummins L10 (10.0L) Eng. (Cont'd)
Coolant (w/4 Units BTE)..... <b>BW5137</b>	Coolant (w/4 Units BTE)..... <b>BW5137</b>	Coolant (w/4 Units BTA+) (3315116)..... <b>BW5071</b>
Coolant (w/4 Units BTA+) (1822313-C1)..... <b>BW5082</b>	Coolant (w/4 Units BTA+) (1822313-C1)..... <b>BW5082</b>	Coolant (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b>
Coolant (w/12 Units BTA+) (1820361-C1)..... <b>BW5074</b>	Coolant (w/12 Units BTA+) (1820361-C1)..... <b>BW5074</b>	Trans. (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b>
Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	2574 w/Detroit Diesel 6-71N (7.0L) Eng.
2 25/32 In. Steering (279294-C92)..... <b>PT903</b>	2 25/32 In. Steering (279294-C92)..... <b>PT903</b>	Lube (23530407)..... <b>B95 +</b>
3 In. Steering (1696766-C1)..... <b>P7178</b>	3 In. Steering (1696766-C1)..... <b>P7178</b>	P. Fuel (23530706)..... <b>BF5800 +</b>
3 31/32 In. Steering (1691121-C1)..... <b>P106-HD</b>	3 31/32 In. Steering (1691121-C1)..... <b>P106-HD</b>	S. Fuel (23530707)..... <b>BF5810</b>
2554 w/DTA466 (7.6L) Eng.	2554, 2654 w/Cat 3208 Eng.	2574 w/Detroit Diesel 6V-92N (9.0L) Eng.
7 5/32 In. Lube (1808896-C1)..... <b>[2] B299 +</b>	Lube (9L9200)..... <b>[2] BT364</b>	Lube (23530407)..... <b>B95 +</b>
7 3/8 In. Lube (1811953-C1)..... <b>[2] B309</b>	Lube (9N5570)..... <b>[2] BT230 +</b>	Lube (23530408)..... <b>B95-MPG +</b>
12 3/32 In. Lube (1819452-C1)..... <b>B7030</b>	B-P Lube Ele..... <b>C750-E +</b>	P. Fuel (23530706)..... <b>BF5800 +</b>
B-P Lube Ele..... <b>C750-E +</b>	Box-Style Fuel/Water Separator..... <b>BF912</b>	S. Fuel (23530707)..... <b>BF5810</b>
7 In. P. Fuel (1822588-C1)..... <b>BF7629 +</b>	Fuel Spin-on..... <b>BF970 +</b>	S. Fuel (23530645)..... <b>BF5815</b>
8 23/32 In. P. Fuel..... <b>BF979 +</b>	2554, 2654 w/DT530 (8.7L) Eng.	2574 w/Detroit Diesel 8V-71N (9.3L) Eng.
4 27/32 In. S. Fuel (Fleetguard FF5052)..... <b>BF788</b>	Lube (1819452-C1)..... <b>B7030</b>	F-F Lube (23530407)..... <b>B95 +</b>
7 11/32 In. S. Fuel..... <b>BF588</b>	Fuel/Water Separator (1677004-C91)..... <b>BF1345-O</b>	F-F Lube (23530408)..... <b>B95-MPG +</b>
O. Air (1674320-C1)..... <b>PA2525</b>	Fuel (1822588C1)..... <b>BF7629 +</b>	B-P Lube Ele. (5570092)..... <b>P52</b>
I. Air (1674319-C1)..... <b>PA3480</b>	Air (1674320-C2)..... <b>PA2525</b>	P. Fuel (23530706)..... <b>BF5800 +</b>
Some I. Air (476741-C1)..... <b>PA2521</b>	Cab Air (1696834-C1)..... <b>PA5691</b>	S. Fuel (23530707)..... <b>BF5810</b>
Radial Seal Air (2005895-C1)..... <b>RS3530</b>	Coolant (w/o Chemical) (Fleetguard WF2101)..... <b>B5134 +</b>	S. Fuel (23530645)..... <b>BF5815</b>
Radial Seal XP Air (2005895-C1)..... <b>RS3530XP</b>	Coolant (w/4 Units BTA+) (1822313-C1)..... <b>BW5082</b>	2574, 2575, 2674 w/Cat C10 (10.3L) Eng.
Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	Coolant (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b>	F-F Lube (1R0716)..... <b>B99 +</b>
Coolant (w/4 Units BTE)..... <b>BW5137</b>	Steering (1696766-C1)..... <b>P7178</b>	Lube (High Efficiency) (1R1808)..... <b>B7299 +</b>
Coolant (w/4 Units BTA+) (1822313-C1)..... <b>BW5082</b>	2574 w/DT466 (7.6L) Eng.	Fuel/Water Separator (w/o SP) (1685159-C91)..... <b>BF1346 +</b>
Coolant (w/12 Units BTA+) (1820361-C1)..... <b>BW5074</b>	Lube (1819452C1)..... <b>B7030</b>	Fuel/Water Separator (w/SP) (1685159-C91)..... <b>BF1346-SP +</b>
Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	Fuel (1822588C1)..... <b>BF7629 +</b>	Air (1674320-C2)..... <b>PA2525</b>
2 25/32 In. Steering (279294-C92)..... <b>PT903</b>	Trans. Ele. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	Cab Air (1696834-C1)..... <b>PA5691</b>
3 In. Steering (1696766-C1)..... <b>P7178</b>	Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
3 31/32 In. Steering (1691121-C1)..... <b>P106-HD</b>	Trans. Spin-on (Fuller 4304827)..... <b>BT223</b>	Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
2554 w/DT466 (7.6L) Eng.	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
7 5/32 In. Lube (1808896-C1)..... <b>[2] B299 +</b>	2574 w/DT466 (7.6L) Eng.	Steering (1696766-C1)..... <b>P7178</b>
7 3/8 In. Lube (1811953-C1)..... <b>[2] B309</b>	Lube (1819452C1)..... <b>B7030</b>	2574, 2575, 2674 w/Cat C12 (12.0) Eng.
12 3/32 In. Lube (1819452-C1)..... <b>B7030</b>	Fuel (1822588C1)..... <b>BF7629 +</b>	F-F Lube (1R0716)..... <b>B99 +</b>
B-P Lube Ele..... <b>C750-E +</b>	Trans. Ele. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	F-F Lube (High Efficiency) (1R1808)..... <b>B7299 +</b>
7 In. P. Fuel (1822588-C1)..... <b>BF7629 +</b>	Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	Fuel/Water Separator (598435-C1)..... <b>BF1212 +</b>
8 23/32 In. P. Fuel..... <b>BF979 +</b>	Trans. Spin-on (Fuller 4304827)..... <b>BT223</b>	Air (1674320-C2)..... <b>PA2525</b>
4 27/32 In. S. Fuel (Fleetguard FF5052)..... <b>BF788</b>	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	Cab Air (1696834-C1)..... <b>PA5691</b>
7 11/32 In. S. Fuel..... <b>BF588</b>	2574 w/Cummins L10 (10.0L) Eng.	Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
O. Air (1674320-C1)..... <b>PA2525</b>	Dual-Flow Lube (3318853)..... <b>BD103 +</b>	Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
I. Air (1674319-C1)..... <b>PA3480</b>	F-F Lube (Standard Vers.) (Fleetguard LF670SC)..... <b>B196 +</b>	Steering (1696766-C1)..... <b>P7178</b>
Some I. Air (476741-C1)..... <b>PA2521</b>	F-F Lube (Ext. Life) (Fleetguard LF670SC)..... <b>B96 +</b>	2574, 2575, 2674 w/Cat 3406 (14.6L) Eng.
Radial Seal Air (2005895-C1)..... <b>RS3530</b>	B-P Lube (3304232)..... <b>B7577</b>	F-F Lube Spin-on..... <b>B99 +</b>
Radial Seal XP Air (2005895-C1)..... <b>RS3530XP</b>	Fuel/Water Separator (154789)..... <b>BF957-D +</b>	B-P Lube Ele..... <b>C750-E +</b>
Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b>		Fuel Spin-on..... <b>BF614 +</b>
		Coolant Spin-on..... <b>BW5137</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
2574, 2575, 2674 w/GMC Diesel Eng. <b>F-F Lube Ele.</b> ..... P20-HD <b>F-F Lube Spin-on</b> ..... B95 + <b>B-P Lube Ele.</b> ..... C750-E + <b>P. Fuel Spin-on</b> ..... BF5800 + <b>S. Fuel Spin-on</b> ..... BF5810 <b>16 7/16 In. Air (476741-C1)</b> ..... PA2521 <b>18 1/2 In. Air (476743-C1)</b> ..... PA2525 <b>Coolant Spin-on</b> ..... BW5137	2574 S Series, 2575 S Series, 2674 S Series, 2675 S Series w/Cummins M11 (10.8L) Eng. (Cont'd) <b>Coolant (w/4 Units BTA+)</b> (Fleetguard WF2071)..... BW5071 <b>Coolant (w/6 Units BTA+)</b> (Fleetguard WF2072)..... BW5072 <b>Coolant (w/8 Units BTA+)</b> (Fleetguard WF2073)..... BW5073 <b>Coolant (w/12 Units BTA+)</b> (Fleetguard WF2074)..... BW5074 <b>Coolant (w/15 Units BTA+)</b> (Fleetguard WF2075)..... BW5075 <b>Opt. Trans. (Fuller 17237)</b> ..... B2 + <b>2 25/32 In. Steering</b> (279294-C92)..... PT903 <b>3 31/32 In. Steering</b> (1691121-C1)..... P106-HD	2574 S Series, 2674 S Series w/DT530 (8.7L) Eng. (Cont'd) <b>Coolant (w/o Chemical)</b> (Fleetguard WF2101)..... B5134 + <b>4 3/8 In. Coolant (w/4 Units</b> BTA+) (Fleetguard WF2071)..... BW5071 <b>5 3/8 In. Coolant (w/4 Units</b> BTA+) (1822313-C1)..... BW5082 <b>Coolant (w/12 Units BTA+)</b> (1820361-C1)..... BW5074 <b>Opt. Trans. (Fuller 17237)</b> ..... B2 + <b>2 25/32 In. Steering</b> (279294-C92)..... PT951 <b>3 31/32 In. Steering</b> (1691121-C1)..... P106-HD
2574, 2575, 2674, 2675 S Series w/Cummins ISM (10.8L) Eng. <b>F-F Lube Ele.</b> ..... P999-HD <b>F-F Lube Spin-on</b> ..... B196 + <b>B-P Lube Ele.</b> ..... C750-E + <b>B-P Lube Spin-on</b> ..... B7577 <b>Fuel Spin-on</b> ..... BF957 + <b>16 7/16 In. Air (476741-C1)</b> ..... PA2521 <b>18 1/2 In. Air (476743-C1)</b> ..... PA2525 <b>Cab Air (1696834-C1)</b> ..... PA5691 <b>Air Dryer (AD-IP System) (Bendix</b> 65624)..... BA5373 <b>Coolant Spin-on</b> ..... BW5071 <b>Opt. Trans. (Fuller 17237)</b> ..... B2 + <b>Steering (1696766-C1)</b> ..... P7178	2574 S Series, 2575 S Series, 2674 S Series, 2675 S Series w/Cummins N14 (14.0L) Plus Eng. <b>Dual-Flow Lube (Std. Vers.)</b> (Fleetguard LF3000)..... BD103 + <b>Dual-Flow Lube (High Velocity)</b> (Fleetguard LF9009)..... BD7309 + <b>Fuel/Water Separator (w/Drain)</b> (Fleetguard FS1242B)..... BF1249 <b>Fuel/Water Separator (Open End</b> for Bowl) (Fleetguard FS1242B)... BF1249-O <b>Fuel/Water Separator (w/Drain &amp;</b> Sensor Port) (Fleetguard FS1242B)..... BF1249-SP <b>Fuel/Water Separator (w/Drain &amp;</b> Sensor Port, High Efficiency Version) (Fleetguard FS1242B)... BF1393-SP <b>Fuel/Water Separator</b> (Fleetguard FS1212)..... BF1212 + <b>O. Air (1674320-C2)</b> ..... PA2525 <b>Opt. I. Air (1674319-C2)</b> ..... PA2526 <b>Air Dryer (AD-9 System) (Bendix</b> 107796)..... BA5377 <b>Coolant (Fleetguard WF2074)</b> ..... BW5074 <b>Trans. Spin-on (Allison</b> 29510918)..... PT8330-MPG <b>2 31/32 In. Steering</b> (279294-C92)..... PT903 <b>3 In. Steering (1696766-C1)</b> ..... P7178 <b>3 31/32 In. Steering</b> (1691121-C1)..... P106-HD	2575 w/Cummins L10 (10.0L) Eng. <b>Dual-Flow Lube (3318853)</b> ..... BD103 + <b>F-F Lube (Standard Vers.)</b> (Fleetguard LF670SC)..... B196 + <b>F-F Lube (Ext. Life) (Fleetguard</b> LF670SC)..... B96 + <b>B-P Lube (3304232)</b> ..... B7577 <b>Fuel/Water Separator (154789)</b> ... BF957-D + <b>Coolant (w/4 Units BTA+)</b> (3315116)..... BW5071 <b>Coolant (w/15 Units BTA+)</b> (Fleetguard WF2075)..... BW5075
2574 S Series, 2575 S Series, 2674 S Series, 2675 S Series w/Cummins LTA10 Eng. <b>Dual-Flow Lube (3318853)</b> ..... BD103 + <b>F-F Lube (Fleetguard LF670SC)</b> .. B196 + <b>B-P Lube (3304232)</b> ..... B7577 <b>Fuel/Water Separator</b> (1677004-C91)..... BF1345-O <b>Fuel (154789)</b> ..... BF957-D + <b>Single Air (470186-C91)</b> ..... PA2525 <b>O. Air (482646-C91)</b> ..... PA2525 <b>I. Air (482646-C91)</b> ..... PA2526 <b>Air Dryer (AD-9 System) (Bendix</b> 107796)..... BA5377 <b>Coolant (Fleetguard WF2074)</b> ..... BW5074 <b>Trans. Spin-on (Allison</b> 29510918)..... PT8330-MPG <b>2 31/32 In. Steering</b> (279294-C92)..... PT903 <b>3 In. Steering (1696766-C1)</b> ..... P7178 <b>3 31/32 In. Steering</b> (1691121-C1)..... P106-HD	2574 S Series, 2575 S Series, 2674 S Series, 2675 S Series w/Cummins M11 (10.8L) Eng. <b>Dual-Flow Lube (Std. Vers.)</b> (3318853)..... BD103 + <b>Dual-Flow Lube (High Velocity)</b> (Fleetguard LF9009)..... BD7309 + <b>O. Air (1674320-C2)</b> ..... PA2525 <b>Opt. I. Air (1674319-C2)</b> ..... PA2526 <b>Air Dryer (AD-9 System) (Bendix</b> 107796)..... BA5377 <b>Coolant (w/o Chemical)</b> (Fleetguard WF2077)..... B5134 +	2575 w/Detroit Diesel 6-71N (7.0L) Eng. <b>Lube (23530407)</b> ..... B95 + <b>P. Fuel (23530706)</b> ..... BF5800 + <b>S. Fuel (23530707)</b> ..... BF5810
2574 S Series, 2575 S Series, 2674 S Series, 2675 S Series w/Cummins M11 (10.8L) Eng. <b>Dual-Flow Lube (Std. Vers.)</b> (3318853)..... BD103 + <b>Dual-Flow Lube (High Velocity)</b> (Fleetguard LF9009)..... BD7309 + <b>O. Air (1674320-C2)</b> ..... PA2525 <b>Opt. I. Air (1674319-C2)</b> ..... PA2526 <b>Air Dryer (AD-9 System) (Bendix</b> 107796)..... BA5377 <b>Coolant (w/o Chemical)</b> (Fleetguard WF2077)..... B5134 +	2574 S Series, 2674 S Series w/DT530 (8.7L) Eng. <b>Lube (1819452-C1)</b> ..... B7030 <b>Fuel (7/8-14 Thd.) (1822588-C1)</b> .. BF7629 + <b>Fuel (M16 x 1.5 Thd.)</b> (Fleetguard FF5052)..... BF788 <b>O. Air (1674320-C2)</b> ..... PA2525 <b>Opt. I. Air (1674319-C2)</b> ..... PA2526	2575 w/Detroit Diesel 6V-92N (9.0L) Eng. <b>Lube (23530407)</b> ..... B95 + <b>Lube (23530408)</b> ..... B95-MPG + <b>P. Fuel (23530706)</b> ..... BF5800 + <b>S. Fuel (23530707)</b> ..... BF5810 <b>S. Fuel (23530645)</b> ..... BF5815
2574 S Series, 2575 S Series, 2674 S Series, 2675 S Series w/Cummins M11 (10.8L) Eng. <b>Dual-Flow Lube (Std. Vers.)</b> (3318853)..... BD103 + <b>Dual-Flow Lube (High Velocity)</b> (Fleetguard LF9009)..... BD7309 + <b>O. Air (1674320-C2)</b> ..... PA2525 <b>Opt. I. Air (1674319-C2)</b> ..... PA2526 <b>Air Dryer (AD-9 System) (Bendix</b> 107796)..... BA5377 <b>Coolant (w/o Chemical)</b> (Fleetguard WF2077)..... B5134 +	2574 S Series, 2674 S Series w/DT530 (8.7L) Eng. <b>Lube (1819452-C1)</b> ..... B7030 <b>Fuel (7/8-14 Thd.) (1822588-C1)</b> .. BF7629 + <b>Fuel (M16 x 1.5 Thd.)</b> (Fleetguard FF5052)..... BF788 <b>O. Air (1674320-C2)</b> ..... PA2525 <b>Opt. I. Air (1674319-C2)</b> ..... PA2526	2575 w/Detroit Diesel 8V-71N (9.3L) Eng. <b>F-F Lube (23530407)</b> ..... B95 + <b>F-F Lube (23530408)</b> ..... B95-MPG + <b>B-P Lube Ele. (5570092)</b> ..... P52 <b>P. Fuel (23530706)</b> ..... BF5800 + <b>S. Fuel (23530707)</b> ..... BF5810 <b>S. Fuel (23530645)</b> ..... BF5815
2574 S Series, 2575 S Series, 2674 S Series, 2675 S Series w/Cummins M11 (10.8L) Eng. <b>Dual-Flow Lube (Std. Vers.)</b> (3318853)..... BD103 + <b>Dual-Flow Lube (High Velocity)</b> (Fleetguard LF9009)..... BD7309 + <b>O. Air (1674320-C2)</b> ..... PA2525 <b>Opt. I. Air (1674319-C2)</b> ..... PA2526 <b>Air Dryer (AD-9 System) (Bendix</b> 107796)..... BA5377 <b>Coolant (w/o Chemical)</b> (Fleetguard WF2077)..... B5134 +	2654 w/Cummins N14 (14.0L) Eng. <b>Dual-Flow Lube (Fleetguard</b> LF3000)..... BD103 + <b>F-F Lube (Standard Vers.)</b> (Fleetguard LF670SC)..... B196 + <b>F-F Lube (Ext. Life) (Fleetguard</b> LF670SC)..... B96 + <b>B-P Lube (3304232)</b> ..... B7577 <b>Fuel/Water Separator (3329289)</b> BF1259 <b>Fuel/Water Separator</b> (Fleetguard FS1212)..... BF1212 + <b>O. Air (1674320-C2)</b> ..... PA2525 <b>Opt. I. Air (1674319-C2)</b> ..... PA2526	2654 w/Cummins N14 (14.0L) Eng. <b>Dual-Flow Lube (Fleetguard</b> LF3000)..... BD103 + <b>F-F Lube (Standard Vers.)</b> (Fleetguard LF670SC)..... B196 + <b>F-F Lube (Ext. Life) (Fleetguard</b> LF670SC)..... B96 + <b>B-P Lube (3304232)</b> ..... B7577 <b>Fuel/Water Separator (3329289)</b> BF1259 <b>Fuel/Water Separator</b> (Fleetguard FS1212)..... BF1212 + <b>O. Air (1674320-C2)</b> ..... PA2525 <b>Opt. I. Air (1674319-C2)</b> ..... PA2526

+ See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>INTERNATIONAL Trucks &amp; Buses (cont'd)</b>	<b>INTERNATIONAL Trucks &amp; Buses (cont'd)</b>	<b>INTERNATIONAL Trucks &amp; Buses (cont'd)</b>
2654 w/Cummins N14 (14.0L) Eng. (Cont'd) <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134 +</b> <b>Coolant</b> (Controlled Release) (Nalcool NF2088)..... <b>BW5200</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>2 25/32 In. Steering</b> (279294-C92)..... <b>PT903</b> <b>3 In. Steering</b> (1696766-C1)..... <b>P7178</b> <b>3 31/32 In. Steering</b> (1691121-C1)..... <b>P106-HD</b>	2654 w/DTA466 (7.6L) Eng. <b>7 5/32 In. Lube</b> (1808896-C1)..... <b>[2] B299 +</b> <b>7 3/8 In. Lube</b> (1811953-C1)..... <b>[2] B309</b> <b>12 3/32 In. Lube</b> (1819452-C1).... <b>B7030</b> <b>B-P Lube Ele.</b> ..... <b>C750-E +</b> <b>7 In. P. Fuel</b> (1822588-C1)..... <b>BF7629 +</b> <b>8 23/32 In. P. Fuel</b> ..... <b>BF979 +</b> <b>4 27/32 In. S. Fuel</b> (Fleetguard FF5052)..... <b>BF788</b> <b>7 11/32 In. S. Fuel</b> ..... <b>BF588</b> <b>O. Air</b> (1674320-C1)..... <b>PA2525</b> <b>I. Air</b> (1674319-C1)..... <b>PA3480</b> <b>Some I. Air</b> (476741-C1)..... <b>PA2521</b> <b>Radial Seal Air</b> (2005895-C1)..... <b>RS3530</b> <b>Radial Seal XP Air</b> (2005895-C1)..... <b>RS3530XP</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (w/4 Units BTE)..... <b>BW5137</b> <b>Coolant</b> (w/4 Units BTA+) (1822313-C1)..... <b>BW5082</b> <b>Coolant</b> (w/12 Units BTA+) (1820361-C1)..... <b>BW5074</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>2 25/32 In. Steering</b> (279294-C92)..... <b>PT903</b> <b>3 In. Steering</b> (1696766-C1)..... <b>P7178</b> <b>3 31/32 In. Steering</b> (1691121-C1)..... <b>P106-HD</b>	2674 w/Cummins L10 (10.0L) Eng. (Cont'd) <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT9316-MPG</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>2674 w/Detroit Diesel 6-71N (7.0L) Eng.</b> <b>Lube</b> (23530407)..... <b>B95 +</b> <b>Lube</b> (23530408)..... <b>B95-MPG +</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b> <b>S. Fuel</b> (23530645)..... <b>BF5815</b> <b>2674 w/Detroit Diesel 6V-92N (9.0L) Eng.</b> <b>Lube</b> (23530407)..... <b>B95 +</b> <b>Lube</b> (23530408)..... <b>B95-MPG +</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b> <b>S. Fuel</b> (23530645)..... <b>BF5815</b> <b>2674 w/Detroit Diesel 8V-71N (9.3L) Eng.</b> <b>F-F Lube</b> (23530407)..... <b>B95 +</b> <b>F-F Lube</b> (23530408)..... <b>B95-MPG +</b> <b>B-P Lube Ele.</b> (5570092)..... <b>P52</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b> <b>S. Fuel</b> (23530645)..... <b>BF5815</b> <b>2674 w/Detroit Diesel Series 60 (11.1L) Eng.</b> <b>Lube</b> (23530573)..... <b>[2] B495</b> <b>Fuel/Water Separator Ele.</b> (23533816)..... <b>PF7748</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (23535985)..... <b>BF5813 +</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (23535985).. <b>BF5813-O +</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b> <b>2674 w/Detroit Diesel Series 60 (12.7L) Eng.</b> <b>Lube</b> (23530573)..... <b>[2] B495</b> <b>Fuel/Water Separator Ele.</b> (23533816)..... <b>PF7748</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (23535985)..... <b>BF5813 +</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (23535985).. <b>BF5813-O +</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b> <b>2674 w/DTA466 (7.6L) Eng.</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Lube</b> (M36 x 1.5 Thd.) (1811953C1).... <b>B309</b> <b>Lube</b> (M36 x 1.5 Thd.) (1819452C1)..... <b>B7030</b> <b>P. Fuel</b> (625627C1)..... <b>BF979 +</b> <b>S. Fuel</b> (1809789C1)..... <b>BF7629 +</b> <b>Coolant</b> (1822313C1)..... <b>BW5082</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
2654 w/Detroit Diesel Series 60 (12.7L) Eng. <b>Lube</b> (23530573)..... <b>[2] B495</b> <b>Fuel/Water Separator Ele.</b> (23533816)..... <b>PF7748</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (23535985)..... <b>BF5813 +</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (23535985).. <b>BF5813-O +</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b>	2674 w/Caterpillar 3176 (10.3L) Eng. <b>F-F Lube</b> (1R0716)..... <b>B99 +</b> <b>F-F Lube</b> (1R1808)..... <b>B7299 +</b> <b>F-F Lube</b> (1R0713)..... <b>BT230 +</b> <b>F-F Lube</b> (1R0714)..... <b>B75</b> <b>B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Fuel/Water Separator Spin-on</b> (2568753)..... <b>BF1259</b> <b>P. Fuel</b> (1R1740)..... <b>BF970 +</b> <b>S. Fuel</b> (1R0750)..... <b>BF7633 +</b> <b>Coolant</b> (w/4 Units BTE) (9N3717)..... <b>BW5137</b> <b>Coolant</b> (w/8 Units BTE) (9N3366)..... <b>BW5139</b>	2674 w/Detroit Diesel Series 60 (12.7L) Eng. <b>Lube</b> (23530573)..... <b>[2] B495</b> <b>Fuel/Water Separator Ele.</b> (23533816)..... <b>PF7748</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (23535985)..... <b>BF5813 +</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (23535985).. <b>BF5813-O +</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b>
2654 w/DT466 (7.6L) Eng. <b>7 5/32 In. Lube</b> (1808896-C1)..... <b>[2] B299 +</b> <b>7 3/8 In. Lube</b> (1811953-C1)..... <b>[2] B309</b> <b>12 3/32 In. Lube</b> (1819452-C1).... <b>B7030</b> <b>B-P Lube Ele.</b> ..... <b>C750-E +</b> <b>7 In. P. Fuel</b> (1822588-C1)..... <b>BF7629 +</b> <b>8 23/32 In. P. Fuel</b> ..... <b>BF979 +</b> <b>4 27/32 In. S. Fuel</b> (Fleetguard FF5052)..... <b>BF788</b> <b>7 11/32 In. S. Fuel</b> ..... <b>BF588</b> <b>O. Air</b> (1674320-C1)..... <b>PA2525</b> <b>I. Air</b> (1674319-C1)..... <b>PA3480</b> <b>Some I. Air</b> (476741-C1)..... <b>PA2521</b> <b>Radial Seal Air</b> (2005895-C1)..... <b>RS3530</b> <b>Radial Seal XP Air</b> (2005895-C1)..... <b>RS3530XP</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (w/4 Units BTE)..... <b>BW5137</b> <b>Coolant</b> (w/4 Units BTA+) (1822313-C1)..... <b>BW5082</b> <b>Coolant</b> (w/12 Units BTA+) (1820361-C1)..... <b>BW5074</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>2 25/32 In. Steering</b> (279294-C92)..... <b>PT903</b> <b>3 In. Steering</b> (1696766-C1)..... <b>P7178</b> <b>3 31/32 In. Steering</b> (1691121-C1)..... <b>P106-HD</b>	2674 w/Cummins L10 (10.0L) Eng. <b>Lube</b> (1-12 Thd.) (1811953C1).... <b>B309</b> <b>Lube</b> (M36 x 1.5 Thd.) (1819452C1)..... <b>B7030</b> <b>P. Fuel</b> (625627C1)..... <b>BF979 +</b> <b>S. Fuel</b> (1809789C1)..... <b>BF7629 +</b> <b>Coolant</b> (1822313C1)..... <b>BW5082</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
2675 w/Cummins L10 (10.0L) Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>F-F Lube</b> (Standard Vers.) (Fleetguard LF670SC)..... <b>B196 +</b> <b>F-F Lube</b> (Ext. Life) (Fleetguard LF670SC)..... <b>B96 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Fuel/Water Separator</b> (154789)... <b>BF957-D +</b> <b>Coolant</b> (w/4 Units BTA+) (3315116)..... <b>BW5071</b> <b>Coolant</b> (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b>	3000IC w/DT466 (7.6L) Eng. <b>Dual-Flow Lube</b> (1842639C91)... <b>BD7250</b> <b>Fuel/Water Separator Ele.</b> (1842638C92)..... <b>PF7779</b> <b>Fuel</b> (625625C1)..... <b>BF984</b> <b>Fuel</b> (625627C1)..... <b>BF979 +</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (1820361C1)..... <b>BW5074</b>	3200 w/DT466 (7.6L) Eng. (Cont'd) <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (1691121-C1)..... <b>P106-HD</b>
2675 w/Detroit Diesel 6V-92N (9.0L) Eng. <b>Lube</b> (23530407)..... <b>B95 +</b> <b>Lube</b> (23530408)..... <b>B95-MPG +</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b> <b>S. Fuel</b> (23530645)..... <b>BF5815</b>	3000IC w/DT530 (8.7L) Eng. <b>F-F Lube</b> (1819452C1)..... <b>B7030</b> <b>Dual-Flow Lube</b> (1842639C91)... <b>BD7250</b> <b>Fuel/Water Separator Ele.</b> (1842638C92)..... <b>PF7779</b> <b>Fuel</b> (1820479C1)..... <b>BF7531</b> <b>Coolant</b> (1822313C1)..... <b>BW5082</b>	3200 w/DT530 (8.7L) Eng. <b>F-F Lube</b> (1819452C1)..... <b>B7030</b> <b>Dual-Flow Lube</b> (1842639C91)... <b>BD7250</b> <b>Fuel/Water Separator Ele.</b> (1842638C92)..... <b>PF7779</b> <b>Fuel</b> (1820479C1)..... <b>BF7531</b> <b>Coolant</b> (1822313C1)..... <b>BW5082</b>
3000 w/Detroit Diesel Series 50 (8.5L) Eng. <b>Lube</b> (23530573)..... <b>[2] B495</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (23535985)..... <b>BF5813 +</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (23535985).. <b>BF5813-O +</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b>	3000IC w/T444E (7.3L) Eng. <b>Lube</b> (1814562C1)..... <b>B7039</b> <b>3 9/16 In. Fuel</b> (1825864C92)..... <b>PF7698</b> <b>4 17/32 In. Fuel</b> (1822631C91).... <b>PF7678</b> <b>Std. O. Air</b> (476741C1)..... <b>PA2521</b> <b>Std. I. Air</b> (482644C1)..... <b>PA2522</b> <b>Radial Seal Air</b> (1691027C1)..... <b>RS2863</b> <b>Radial Seal XP Air</b> (1691027C1).. <b>RS2863XP</b> <b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b> <b>3 31/32 In. Steering</b> (1691121C1)..... <b>P106-HD</b> <b>5 1/32 In. Steering</b> (1695528C1).. <b>PT9419-MPG</b>	3200 w/VT365 (6.0L) Eng. <b>Lube</b> (w/o Screw on Cap) (1844588-C91)..... <b>P7235</b> <b>Lube</b> (w/Screw on Cap) (Wix 57312)..... <b>P7436</b> <b>Fuel</b> (1825864-C92)..... <b>PF7698</b> <b>Radial Seal O. Air</b> (3532799-C1).. <b>RS4636 +</b> <b>Radial Seal I. Air</b> (3532800-C1)... <b>RS4637</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (1691121-C1)..... <b>P106-HD</b>
3000 w/DT466 (7.6L) Eng. <b>Lube</b> (1819452C1)..... <b>B7030</b> <b>Fuel/Water Separator Ele.</b> (1842638C92)..... <b>PF7779</b> <b>Fuel</b> (625625C1)..... <b>BF984</b> <b>Fuel</b> (625627C1)..... <b>BF979 +</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (1820361C1)..... <b>BW5074</b>	3000IC w/VT365 (6.0L) Eng. <b>Lube</b> (w/o Screw-on Cap) (1844588C91)..... <b>P7235</b> <b>Lube</b> (w/Screw on Cap)..... <b>P7436</b> <b>Fuel Ele.</b> (1825864C92)..... <b>PF7698</b>	3200 w/MaxxFORCE 7 Eng. <b>Lube</b> (w/o Screw on Cap) (1838489-C1)..... <b>P7235</b> <b>Lube</b> (w/Screw on Cap) (Wix 57312)..... <b>P7436</b> <b>Fuel Kit</b> (1876533-C93)..... <b>BF9858 KIT</b> <b>Radial Seal Air</b> (3532799-C1)..... <b>RS4636 +</b> <b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
3000RE w/DT466 (7.6L) Eng. <b>Lube</b> (1814562C1)..... <b>B7039</b> <b>3 9/16 In. Fuel</b> (1825864C92)..... <b>PF7698</b> <b>4 17/32 In. Fuel</b> (1822631C91).... <b>PF7678</b> <b>O. Air</b> (476741C1)..... <b>PA2521</b> <b>I. Air</b> (482644C1)..... <b>PA2522</b> <b>Radial Seal Air</b> (1691027C1)..... <b>RS2863</b> <b>Radial Seal XP Air</b> (1691027C1).. <b>RS2863XP</b> <b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b> <b>Steering</b> (1691121C1)..... <b>P106-HD</b>	3000RE w/DT530 (8.7L) Eng. <b>F-F Lube</b> (1819452C1)..... <b>B7030</b> <b>Dual-Flow Lube</b> (1842639C91)... <b>BD7250</b> <b>Fuel/Water Separator Ele.</b> (1842638C92)..... <b>PF7779</b> <b>Fuel</b> (625625C1)..... <b>BF984</b> <b>Fuel</b> (625627C1)..... <b>BF979 +</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (1820361C1)..... <b>BW5074</b>	
3000FE w/DT466 (7.6L) Eng. <b>F-F Lube</b> (1819452C91)..... <b>B7030</b> <b>Fuel/Water Separator Ele.</b> (1842638C92)..... <b>PF7779</b> <b>Fuel</b> (625625C1)..... <b>BF984</b> <b>Fuel</b> (625627C1)..... <b>BF979 +</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (1820361C1)..... <b>BW5074</b>	3200 w/DT466 (7.6L) Eng. <b>Lube</b> (1833121-C1)..... <b>B7030</b> <b>Fuel</b> (1822588-C1)..... <b>BF7629 +</b> <b>Radial Seal O. Air</b> (3532799-C1).. <b>RS4636 +</b> <b>Radial Seal I. Air</b> (3532800-C1)... <b>RS4637</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
3200 w/MaxxForce 7 Eng. (Cont'd)	3400 w/T444E (7.3L) Eng. (To 1999) (Cont'd)	3600 w/DT360 (5.9L) Eng. (Cont'd)
Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017	Trans. Pan-Type (3.8 In. Pan) (Allison 29540976)..... 19992 +	Radial Seal XP Air (1691027C1). RS2863XP
Trans. Spin-on (Allison 29539579)..... BT8460	Trans. Pan-Type (5.3 In. Pan) (Allison 29538489)..... 19739 +	2 25/32 In. Steering (w/Gskt.) (279294C92)..... PT903
Steering (2503221-C1)..... BT9388	Trans. Spin-on (Allison 29510922)..... BT8316-MPG	2 25/32 In. Steering (w/o Gskt.) (279294C92)..... PT951
3300 w/VT365 (6.0L) Eng.	Trans. Spin-on (596606-C1)..... BT839-10	3 9/16 In. Steering (1653998C91)..... P7134
Lube (w/o Screw on Cap) (1844588-C91)..... P7235	3 31/32 In. Steering (1691121-C1)..... P106-HD	3 31/32 In. Steering (1691121C1)..... P106-HD
Lube (w/Screw on Cap) (Wix 57312)..... P7436	5 1/32 In. Steering (1695528-C1)..... PT9419-MPG	4 5/32 In. Steering (1681202C91)..... PT8407
Fuel (1825864-C92)..... PF7698	3400 w/T444E (7.3L) Eng. (1999-on)	3600 w/DTA360 (5.9L) Eng.
Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004	Lube (1814562-C1)..... B7039	Lube (1811953-C1)..... [2] B309
Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016	Fuel (1825864-C92)..... PF7698	Lube (Fleetguard LF3420)..... BT261
Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003	O. Air (476741C1)..... PA2521	5 11/16 In. Fuel/Water Separator (702255-C1)..... BF891
Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017	I. Air (482644-C1)..... PA2522	8 17/32 In. Fuel/Water Separator (1808623-C1)..... BF7584 +
Trans. Spin-on (Allison 29539579)..... BT8460	Radial Seal Air (1691027-C1)..... RS2863	5 7/16 In. Fuel (Fleetguard FF105D)..... BF957-D +
Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	Radial Seal XP Air (1691027-C1)..... RS2863XP	7 In. Fuel (1822588-C1)..... BF7629 +
Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Cab Air (1696834-C1)..... PA5691	Fuel Strainer (1817677-C91)..... PF9907
Steering (1691121-C1)..... P106-HD	Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071	Radial Seal Air (1691027-C1)..... RS2863
3300 w/DT466 Eng.	Coolant (w/o Chemical) (1825314-C1)..... B5089 +	Radial Seal XP Air (1691027-C1)..... RS2863XP
Lube (1819452-C1)..... B7030	Trans. Pan-Type (3.8 In. Pan) (Allison 29540976)..... 19992 +	Air Dryer (Bendix 107796)..... BA5377
Fuel (1822588-C1)..... BF7629 +	Trans. Pan-Type (5.3 In. Pan) (Allison 29538489)..... 19739 +	Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071
Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004	Trans. Spin-on (Allison 29510922)..... BT8316-MPG	Coolant (w/6 Units BTA+) (Fleetguard WF2072)..... BW5072
Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016	Trans. Spin-on (596606-C1)..... BT839-10	Coolant (w/8 Units BTA+) (Fleetguard WF2073)..... BW5073
Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003	3 31/32 In. Steering (1691121-C1)..... P106-HD	Coolant (w/12 Units BTA+) (Fleetguard WF2074)..... BW5074
Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017	5 1/32 In. Steering (1695528-C1)..... PT9419-MPG	Coolant (w/15 Units BTA+) (Fleetguard WF2075)..... BW5075
Trans. Spin-on (Allison 29539579)..... BT8460	3400 w/DT466E Eng.	Trans. Pan-Type (3.8 In. Pan) (Allison 29540976)..... 19992 +
Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	Lube (1819452-C1)..... B7030	Trans. Pan-Type (5.3 In. Pan) (Allison 29538489)..... 19739 +
Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Fuel (1822588-C1)..... BF7629 +	Trans. Spin-on (Allison 29510922)..... BT8316-MPG
Steering (1691121-C1)..... P106-HD	O. Air (476741-C1)..... PA2521	Trans. Spin-on (595722-C91)..... BT839-10
3400 w/T444E (7.3L) Eng. (To 1999)	I. Air (482644-C1)..... PA2522	3 31/32 In. Steering (Fleetguard HF6162)..... P106-HD
Lube (1814562-C1)..... B7039	Cab Air (1696834-C1)..... PA5691	4 5/32 In. Steering (1681202-C91)..... PT8407
Fuel (1822631-C91)..... PF7678	Trans. Pan-Type (3.8 In. Pan) (Allison 29540976)..... 19992 +	3600 w/DT408 (6.7L) Eng.
O. Air (476741C1)..... PA2521	Trans. Pan-Type (5.3 In. Pan) (Allison 29538489)..... 19739 +	Lube (1819452C1)..... B7030
I. Air (482644-C1)..... PA2522	Trans. Spin-on (Allison 29510922)..... BT8316-MPG	Fuel/Water Separator (1677004C91)..... BF1345-O
Radial Seal Air (1691027-C1)..... RS2863	Trans. Spin-on (596606-C1)..... BT839-10	Fuel (M16 x 1.5 Thd.) (Fleetguard FF5052)..... BF788
Radial Seal XP Air (1691027-C1)..... RS2863XP	Steering (1691121-C1)..... P106-HD	Fuel (7/8-14 Thd.) (1822588C1)..... BF7629 +
Cab Air (1696834-C1)..... PA5691	3600 w/DT360 (5.9L) Eng.	O. Air (476741C1)..... PA2521
Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071	Lube (1811953C1)..... B309	I. Air (482644C1)..... PA2522
Coolant (w/o Chemical) (1825314-C1)..... B5089 +	Fuel/Water Separator (1677004C91)..... BF1345-O	Radial Seal Air (1691027C1)..... RS2863
	Fuel/Water Separator (1808623C1)..... BF7584 +	Radial Seal XP Air (1691027C1). RS2863XP
	Fuel (1809789C1)..... BF7629 +	
	Air (476741C1)..... [2] PA2521	
	Radial Seal Air (1691027C1)..... RS2863	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
3600 w/DT408 (6.7L) Eng. (Cont'd)	3600 w/T444E (7.3L) Eng. (Cont'd)	3700 w/V8 7.3L Diesel Eng. (Cont'd)
<b>Coolant</b> (1822313C1)..... <b>BW5082</b>	<b>O. Air</b> (476741-C1)..... <b>PA2521</b>	<b>Trans. Spin-on</b> (595722-C91)..... <b>BT839-10</b>
<b>Steering</b> (Fleetguard HF6162)..... <b>P106-HD</b>	<b>I. Air</b> (482644-C1)..... <b>PA2522</b>	<b>3 31/32 In. Steering</b> (Fleetguard HF6162)..... <b>P106-HD</b>
3600 w/DT466 (7.6L) Eng.	<b>Radial Seal Air</b> (1691027-C1)..... <b>RS2863</b>	<b>4 5/32 In. Steering</b> (1681202-C91)..... <b>PT8407</b>
<b>Lube</b> (1819452-C1)..... <b>B7030</b>	<b>Radial Seal XP Air</b> (1691027-C1)..... <b>RS2863XP</b>	<b>5 1/32 In. Steering</b> (1695528-C1)..... <b>PT9419-MPG</b>
<b>Fuel/Water Separator</b> (1677004-C91)..... <b>BF1345-O</b>	<b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b>	3700 w/DT360 (5.9L) Eng.
<b>Fuel</b> (1822588-C1)..... <b>BF7629 +</b>	<b>Coolant</b> (1822627-C1)..... <b>BW5071</b>	<b>Lube</b> (1811953C1)..... <b>[2] B309</b>
<b>Fuel</b> (3903640)..... <b>BF788</b>	<b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b>	<b>Fuel/Water Separator</b> (Fleetrite FSR81205)..... <b>BF912</b>
<b>Radial Seal Air</b> (1691027C1)..... <b>RS2863</b>	<b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>	<b>Fuel/Water Separator</b> (1677004C91)..... <b>BF1345-O</b>
<b>Radial Seal XP Air</b> (1691027C1)..... <b>RS2863XP</b>	<b>Trans. Spin-on</b> (Allison 23042062)..... <b>BT8316-MPG</b>	<b>Fuel/Water Separator</b> (1808623C1)..... <b>BF7584 +</b>
<b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b>	<b>Trans. Spin-on</b> (595722-C91)..... <b>BT839-10</b>	<b>Fuel</b> (1809789C1)..... <b>BF7629 +</b>
<b>Coolant</b> (w/4 Units BTA+) (1822313-C1)..... <b>BW5082</b>	<b>3 31/32 In. Steering</b> (1691121-C1)..... <b>P106-HD</b>	<b>Radial Seal Air</b> (1691027C1)..... <b>RS2863</b>
<b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b>	<b>4 5/32 In. Steering</b> (1681202-C91)..... <b>PT8407</b>	<b>Radial Seal XP Air</b> (1691027C1)..... <b>RS2863XP</b>
<b>Coolant</b> (w/o Chemical) (Fleetguard WF2101)..... <b>B5134 +</b>	<b>5 1/32 In. Steering</b> (1695528C1)..... <b>PT9419-MPG</b>	<b>2 25/32 In. Steering</b> (w/Gskt.) (279294C92)..... <b>PT903</b>
<b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b>	3700 w/Cat C13 Eng.	<b>2 25/32 In. Steering</b> (w/o Gskt.) (279294C92)..... <b>PT951</b>
<b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>	<b>Lube</b> (1R1808)..... <b>B7299 +</b>	<b>3 9/16 In. Steering</b> (1653998C91)..... <b>P7134</b>
<b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b>	<b>Fuel</b> (1R0749)..... <b>BF7587 +</b>	<b>3 31/32 In. Steering</b> (Fleetguard HF6162)..... <b>P106-HD</b>
<b>Trans. Spin-on</b> (596606-C1)..... <b>BT839-10</b>	3700 w/Cat 3406 (14.6L) Eng.	<b>4 5/32 In. Steering</b> (1681202C91)..... <b>PT8407</b>
<b>3 31/32 In. Steering</b> (1691121C1)..... <b>P106-HD</b>	<b>Lube</b> (Standard Vers.) (1R0716).. <b>B99 +</b>	<b>5 1/32 In. Steering</b> (1695528C1)..... <b>PT9419-MPG</b>
<b>5 1/32 In. Steering</b> (1695528C1)..... <b>PT9419-MPG</b>	<b>Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b>	3700 w/DTA360 (5.9L) Eng.
3600 w/DTA466 (7.6L) Eng.	<b>Fuel/Water Separator</b> (2568753)..... <b>BF1259</b>	<b>Lube</b> (1811953C1)..... <b>[2] B309</b>
<b>Lube</b> (1819452-C1)..... <b>B7030</b>	<b>Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b>	<b>Fuel/Water Separator</b> (Fleetrite FSR81205)..... <b>BF912</b>
<b>Fuel/Water Separator</b> (1677004-C91)..... <b>BF1345-O</b>	<b>Fuel Spin-on</b> (Standard Vers.) (4N5823)..... <b>BF614 +</b>	<b>Fuel/Water Separator</b> (1677004C91)..... <b>BF1345-O</b>
<b>Fuel</b> (1822588-C1)..... <b>BF7629 +</b>	<b>Fuel Spin-on</b> (High Efficiency Vers.)..... <b>BF7587 +</b>	<b>Fuel/Water Separator</b> (1808623C1)..... <b>BF7584 +</b>
<b>Fuel</b> (3903640)..... <b>BF788</b>	3700 w/Cummins N14 (14.0L) Eng.	<b>Fuel</b> (1809789C1)..... <b>BF7629 +</b>
<b>Radial Seal Air</b> (1691027C1)..... <b>RS2863</b>	<b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b>	<b>Radial Seal Air</b> (1691027C1)..... <b>RS2863</b>
<b>Radial Seal XP Air</b> (1691027C1)..... <b>RS2863XP</b>	<b>F-F Lube</b> (Standard Vers.) (Fleetguard LF670SC)..... <b>B196 +</b>	<b>Radial Seal XP Air</b> (1691027C1)..... <b>RS2863XP</b>
<b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b>	<b>F-F Lube</b> (Ext. Life) (Fleetguard LF670SC)..... <b>B96 +</b>	<b>2 25/32 In. Steering</b> (w/Gskt.) (279294C92)..... <b>PT903</b>
<b>Coolant</b> (w/4 Units BTA+) (1822313-C1)..... <b>BW5082</b>	<b>B-P Lube</b> (3304232)..... <b>B7577</b>	<b>2 25/32 In. Steering</b> (w/o Gskt.) (279294C92)..... <b>PT951</b>
<b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b>	<b>Fuel/Water Separator</b> (3308638)..... <b>BF1212 +</b>	<b>3 9/16 In. Steering</b> (1653998C91)..... <b>P7134</b>
<b>Coolant</b> (w/o Chemical) (Fleetguard WF2101)..... <b>B5134 +</b>	<b>Coolant</b> (w/4 Units BTA+) (3315116)..... <b>BW5071</b>	<b>3 31/32 In. Steering</b> (Fleetguard HF6162)..... <b>P106-HD</b>
<b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b>	3700 w/V8 7.3L Diesel Eng.	<b>4 5/32 In. Steering</b> (1681202C91)..... <b>PT8407</b>
<b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>	<b>Lube</b> (Fleetguard LF3344)..... <b>B134</b>	<b>5 1/32 In. Steering</b> (1695528C1)..... <b>PT9419-MPG</b>
<b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b>	<b>Fuel/Water Separator Box-Style</b> (Fleetguard FS1205)..... <b>BF912</b>	3700 w/DT466 (7.6L) Eng.
<b>Trans. Spin-on</b> (596606-C1)..... <b>BT839-10</b>	<b>Fuel/Water Separator Spin-on</b> (702255-C1)..... <b>BF891</b>	<b>Lube</b> (1-12 Thd.) (1811953C1)..... <b>[2] B309</b>
<b>3 31/32 In. Steering</b> (1691121C1)..... <b>P106-HD</b>	<b>Fuel</b> (1804459-C1)..... <b>BF786</b>	<b>Lube</b> (M36 x 1.5 Thd.) (1819452C1)..... <b>B7030</b>
<b>5 1/32 In. Steering</b> (1695528C1)..... <b>PT9419-MPG</b>	<b>Air</b> (588213-C1)..... <b>PA2116</b>	<b>Fuel/Water Separator</b> (Fleetrite FSR81205)..... <b>BF912</b>
3600 w/T444E (7.3L) Eng.	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	
<b>Lube</b> (1814562-C1)..... <b>B7039</b>	<b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b>	
<b>Fuel Ele.</b> (1822631-C91)..... <b>PF7678</b>	<b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>	
<b>5 7/8 In. Fuel Spin-on</b> (1820479C1)..... <b>BF7531</b>	<b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b>	
<b>7 In. Fuel Spin-on</b> (1822588C1)..... <b>BF7629 +</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>INTERNATIONAL Trucks &amp; Buses (cont'd)</b>	<b>INTERNATIONAL Trucks &amp; Buses (cont'd)</b>	<b>INTERNATIONAL Trucks &amp; Buses (cont'd)</b>
3700 w/DT466 (7.6L) Eng. (Cont'd) <b>Fuel/Water Separator</b> (1677004C91)..... <b>BF1345-O</b> <b>4 27/32 In. Fuel</b> (Fleetguard FF5052)..... <b>BF788</b> <b>5 5/16 In. Fuel</b> (625625C1)..... <b>BF984</b> <b>5 7/8 In. Fuel</b> (1820479C1)..... <b>BF7531</b> <b>7 In. Fuel</b> (1822588C1)..... <b>BF7629 +</b> <b>8 23/32 In. Fuel</b> (625627C1)..... <b>BF979 +</b> <b>O. Air</b> (476741C1)..... <b>[2] PA2521</b> <b>I. Air</b> (482644C1)..... <b>[2] PA2522</b> <b>Coolant</b> (1822313C1)..... <b>BW5082</b> <b>2 25/32 In. Steering</b> (w/Gskt.) (279294C92)..... <b>PT903</b> <b>2 25/32 In. Steering</b> (w/o Gskt.) (279294C92)..... <b>PT951</b> <b>3 9/16 In. Steering</b> (1653998C91)..... <b>P7134</b> <b>3 31/32 In. Steering</b> (1691121C1)..... <b>P106-HD</b> <b>4 5/32 In. Steering</b> (1681202C91)..... <b>PT8407</b>	3800 w/Cummins N14 (14.0L) Eng. (Cont'd) <b>Coolant</b> (w/4 Units BTA+) (3315116)..... <b>BW5071</b> <b>3800 w/Detroit Diesel 6V-92N (9.0L) Eng.</b> <b>Lube</b> (23530407)..... <b>B95 +</b> <b>Lube</b> (23530408)..... <b>B95-MPG +</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b> <b>S. Fuel</b> (23530645)..... <b>BF5815</b> <b>3800 w/Detroit Diesel Series 50 (8.5L) Eng.</b> <b>Lube</b> (23530573)..... <b>[2] B495</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (23535985)..... <b>BF5813 +</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (23535985).. <b>BF5813-O +</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b> <b>3800 w/Detroit Diesel Series 60 (11.1L) Eng.</b> <b>Lube</b> (23530573)..... <b>[2] B495</b> <b>Fuel/Water Separator Ele.</b> (23533816)..... <b>PF7748</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (23535985)..... <b>BF5813 +</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (23535985).. <b>BF5813-O +</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b> <b>3800 w/Detroit Diesel Series 60 (12.7L) Eng.</b> <b>Lube</b> (23530573)..... <b>[2] B495</b> <b>Fuel/Water Separator Ele.</b> (23533816)..... <b>PF7748</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (23535985)..... <b>BF5813 +</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (23535985).. <b>BF5813-O +</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b> <b>3800 w/DT360 (5.9L) Eng. (To 8/30/1991)</b> <b>Lube</b> (1811953C1)..... <b>[2] B309</b> <b>Fuel/Water Separator</b> (w/Drain) (1693965C91)..... <b>BF1347</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (1693965C91)..... <b>BF1347-O</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (1693965C91)..... <b>BF1373-SP</b> <b>Some Fuel/Water Separator</b> (w/Drain & Eng. S/N to 72706) (1808623-C1)..... <b>BF7584 +</b> <b>Fuel/Water Separator</b> (Engs. w/S/N 72707-on w/Davco) (Fleetguard FF105D)..... <b>BF957-D +</b> <b>Fuel/Water Separator</b> (1618386-C92)..... <b>BF1345-O</b> <b>Fuel</b> (Engs. w/S/N to-72706, 84779-on) (1822588-C1)..... <b>BF7629 +</b> <b>O. Air</b> (476741C1)..... <b>PA2521</b> <b>Opt. I. Air</b> (Fleetguard AF987)..... <b>PA2522</b> <b>Radial Seal Air</b> (1691027-C1)..... <b>RS2863</b>	3800 w/DT360 (5.9L) Eng. (To 8/30/1991) (Cont'd) <b>Radial Seal XP Air</b> (1691027-C1)..... <b>RS2863XP</b> <b>Coolant</b> (w/6 Units BTA+) (Fleetguard WF2072)..... <b>BW5072</b> <b>Coolant</b> (w/8 Units BTA+) (Fleetguard WF2073)..... <b>BW5073</b> <b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b> <b>Coolant</b> (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b> <b>Steering</b> (1681202C91)..... <b>PT8407</b> <b>Steering</b> (1695528-C1)..... <b>PT9419-MPG</b> <b>3800 w/DT360 (5.9L) Eng. (8/30/1991-on)</b> <b>Lube</b> (1811953C1)..... <b>[2] B309</b> <b>Fuel/Water Separator</b> (w/Drain) (1693965C91)..... <b>BF1347</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (1693965C91)..... <b>BF1347-O</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (1693965C91)..... <b>BF1373-SP</b> <b>Some Fuel/Water Separator</b> (w/Drain & Eng. S/N to 72706) (1808623-C1)..... <b>BF7584 +</b> <b>Fuel/Water Separator</b> (Engs. w/S/N 72707-on w/Davco) (Fleetguard FF105D)..... <b>BF957-D +</b> <b>Fuel/Water Separator</b> (1618386-C92)..... <b>BF1345-O</b> <b>Fuel</b> (Engs. w/S/N to-72706, 84779-on) (1822588-C1)..... <b>BF7629 +</b> <b>O. Air</b> (476741C1)..... <b>PA2521</b> <b>Opt. I. Air</b> (Fleetguard AF987)..... <b>PA2522</b> <b>Radial Seal Air</b> (1691027-C1)..... <b>RS2863</b> <b>Radial Seal XP Air</b> (1691027-C1)..... <b>RS2863XP</b> <b>Coolant</b> (w/6 Units BTA+) (Fleetguard WF2072)..... <b>BW5072</b> <b>Coolant</b> (w/8 Units BTA+) (Fleetguard WF2073)..... <b>BW5073</b> <b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b> <b>Coolant</b> (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b> <b>Steering</b> (Fleetguard HF6162)..... <b>P106-HD</b> <b>Steering</b> (1695528-C1)..... <b>PT9419-MPG</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
3800 w/DTA360 (5.9L) Eng. (To 8/30/1991) <b>Lube</b> (1811953C1)..... [2] <b>B309</b> <b>Fuel/Water Separator</b> (w/Drain) (1693965C91)..... <b>BF1347</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (1693965C91)..... <b>BF1347-O</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (1693965C91)..... <b>BF1373-SP</b> <b>Some Fuel/Water Separator</b> (w/Drain & Eng. S/N to 72706) (1808623-C1)..... <b>BF7584 +</b> <b>Fuel/Water Separator</b> (Engs. w/S/N 72707-on w/Davco) (Fleetguard FF105D)..... <b>BF957-D +</b> <b>Fuel/Water Separator</b> (1618386-C92)..... <b>BF1345-O</b> <b>Fuel</b> (Engs. w/S/N to-72706, 84779-on) (1822588-C1)..... <b>BF7629 +</b> <b>O. Air</b> (476741C1)..... <b>PA2521</b> <b>Opt. I. Air</b> (Fleetguard AF987)..... <b>PA2522</b> <b>Radial Seal Air</b> (1691027-C1)..... <b>RS2863</b> <b>Radial Seal XP Air</b> (1691027-C1)..... <b>RS2863XP</b> <b>Coolant</b> (w/6 Units BTA+) (Fleetguard WF2072)..... <b>BW5072</b> <b>Coolant</b> (w/8 Units BTA+) (Fleetguard WF2073)..... <b>BW5073</b> <b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b> <b>Coolant</b> (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b> <b>Steering</b> (1681202C91)..... <b>PT8407</b> <b>Steering</b> (1695528-C1)..... <b>PT9419-MPG</b>	3800 w/DTA360 (5.9L) Eng. (8/30/1991-on) (Cont'd) <b>Radial Seal Air</b> (1691027-C1)..... <b>RS2863</b> <b>Radial Seal XP Air</b> (1691027-C1)..... <b>RS2863XP</b> <b>Coolant</b> (w/6 Units BTA+) (Fleetguard WF2072)..... <b>BW5072</b> <b>Coolant</b> (w/8 Units BTA+) (Fleetguard WF2073)..... <b>BW5073</b> <b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b> <b>Coolant</b> (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b> <b>Steering</b> (Fleetguard HF6162)..... <b>P106-HD</b> <b>Steering</b> (1695528-C1)..... <b>PT9419-MPG</b> 3800 w/DT408 (6.7L) Eng. (To 8/30/1991) <b>Lube</b> (1819452-C1)..... <b>B7030</b> <b>Fuel</b> (672603-C2)..... <b>BF588</b> <b>O. Air</b> (476741-C1)..... <b>PA2521</b> <b>I. Air</b> (482644-C1)..... <b>PA2522</b> <b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (1822313-C1)..... <b>BW5082</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b> <b>Trans. Spin-on</b> (595722-C91)..... <b>BT839-10</b> <b>Steering</b> (1681202C91)..... <b>PT8407</b> 3800 w/DT408 (6.7L) Eng. (8/30/1991-on) <b>Lube</b> (1819452-C1)..... <b>B7030</b> <b>Fuel</b> (672603-C2)..... <b>BF588</b> <b>O. Air</b> (476741-C1)..... <b>PA2521</b> <b>I. Air</b> (482644-C1)..... <b>PA2522</b> <b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (1822313-C1)..... <b>BW5082</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b> <b>Trans. Spin-on</b> (595722-C91)..... <b>BT839-10</b> <b>Steering</b> (1681202C91)..... <b>PT8407</b> 3800 w/DT466 (7.6L) Eng. (To 8/30/1991) <b>Lube</b> (1811953-C1)..... [2] <b>B309</b> <b>Lube</b> (1819452-C1)..... <b>B7030</b> <b>Fuel/Water Separator</b> (w/Drain) (Racor S3226T)..... <b>BF1347</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (Racor S3226T)..... <b>BF1347-O</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (Racor S3226T)..... <b>BF1373-SP</b> <b>Fuel/Water Separator</b> (Fleetguard FS1205)..... <b>BF912</b> <b>Fuel/Water Separator</b> (1618386-C93)..... <b>BF1345-O</b>	3800 w/DT466 (7.6L) Eng. (To 8/30/1991) (Cont'd) <b>Fuel/Water Separator</b> (w/Sensor Port) (Racor S3226T)..... <b>BF1373-SP</b> <b>Fuel/Water Separator</b> (Fleetguard FS1205)..... <b>BF912</b> <b>Fuel/Water Separator</b> (1618386-C93)..... <b>BF1345-O</b> <b>Fuel/Water Separator</b> (702255-C1)..... <b>BF891</b> <b>Fuel/Water Separator</b> (Engs. w/S/N 618496-on) (Fleetguard FF105D)..... <b>BF957-D +</b> <b>P. Fuel</b> (Engs. w/S/N 567492 to 599779) (625627-C1)..... <b>BF979 +</b> <b>S. Fuel</b> (Engs. w/S/N 567492-on) (672603-C3)..... <b>BF588</b> <b>Fuel</b> (1822588-C1)..... <b>BF7629 +</b> <b>Fuel</b> (Fleetguard FF5052)..... <b>BF788</b> <b>Fuel</b> (1820479-C1)..... <b>BF7531</b> <b>O. Air</b> (476741-C1)..... <b>PA2521</b> <b>I. Air</b> (482644-C1)..... <b>PA2522</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (w/o Chemical) (Fleetguard WF2101)..... <b>B5134 +</b> <b>4 3/8 In. Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>5 3/8 In. Coolant</b> (w/4 Units BTA+) (1822313-C1)..... <b>BW5082</b> <b>Coolant</b> (w/6 Units BTA+) (Fleetguard WF2072)..... <b>BW5072</b> <b>Coolant</b> (w/8 Units BTA+) (Fleetguard WF2073)..... <b>BW5073</b> <b>Coolant</b> (w/12 Units BTA+) (1820361-C1)..... <b>BW5074</b> <b>Coolant</b> (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b> <b>Trans. Spin-on</b> (595722-C91)..... <b>BT839-10</b> <b>Steering</b> (1681202C91)..... <b>PT8407</b> 3800 w/DT466 (7.6L) Eng. (8/30/1991-on) <b>Lube</b> (1811953-C1)..... [2] <b>B309</b> <b>Lube</b> (1819452-C1)..... <b>B7030</b> <b>Fuel/Water Separator</b> (w/Drain) (Racor S3226T)..... <b>BF1347</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (Racor S3226T)..... <b>BF1347-O</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (Racor S3226T)..... <b>BF1373-SP</b> <b>Fuel/Water Separator</b> (Fleetguard FS1205)..... <b>BF912</b> <b>Fuel/Water Separator</b> (1618386-C93)..... <b>BF1345-O</b>


+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
3800 w/DT466 (7.6L) Eng. (8/30/1991-on) (Cont'd) <b>Fuel/Water Separator</b> (702255-C1)..... <b>BF891</b> <b>Fuel/Water Separator</b> (Engs. w/S/N 618496-on) (Fleetguard FF105D)..... <b>BF957-D +</b> <b>P. Fuel</b> (Engs. w/S/N 567492 to 599779) (625627-C1)..... <b>BF979 +</b> <b>S. Fuel</b> (Engs. w/S/N 567492-on) (672603-C3)..... <b>BF588</b> <b>Fuel</b> (1822588-C1)..... <b>BF7629 +</b> <b>Fuel</b> (Fleetguard FF5052)..... <b>BF788</b> <b>Fuel</b> (1820479-C1)..... <b>BF7531</b> <b>O. Air</b> (476741-C1)..... <b>PA2521</b> <b>I. Air</b> (482644-C1)..... <b>PA2522</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (w/o Chemical) (Fleetguard WF2101)..... <b>B5134 +</b> <b>4 3/8 In. Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>5 3/8 In. Coolant</b> (w/4 Units BTA+) (1822313-C1)..... <b>BW5082</b> <b>Coolant</b> (w/6 Units BTA+) (Fleetguard WF2072)..... <b>BW5072</b> <b>Coolant</b> (w/8 Units BTA+) (Fleetguard WF2073)..... <b>BW5073</b> <b>Coolant</b> (w/12 Units BTA+) (1820361-C1)..... <b>BW5074</b> <b>Coolant</b> (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b> <b>Trans. Spin-on</b> (595722-C91)..... <b>BT839-10</b> <b>Steering</b> (1691121-C1)..... <b>P106-HD</b>	3800 w/DT466C (7.6L) Eng. (To 8/30/1991) (Cont'd) <b>P. Fuel</b> (Engs. w/S/N 567492 to 599779) (625627-C1)..... <b>BF979 +</b> <b>S. Fuel</b> (Engs. w/S/N 567492-on) (672603-C3)..... <b>BF588</b> <b>Fuel</b> (1822588-C1)..... <b>BF7629 +</b> <b>Fuel</b> (Fleetguard FF5052)..... <b>BF788</b> <b>Fuel</b> (1820479-C1)..... <b>BF7531</b> <b>O. Air</b> (476741-C1)..... <b>PA2521</b> <b>I. Air</b> (482644-C1)..... <b>PA2522</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (w/o Chemical) (Fleetguard WF2101)..... <b>B5134 +</b> <b>4 3/8 In. Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>5 3/8 In. Coolant</b> (w/4 Units BTA+) (1822313-C1)..... <b>BW5082</b> <b>Coolant</b> (w/6 Units BTA+) (Fleetguard WF2072)..... <b>BW5072</b> <b>Coolant</b> (w/8 Units BTA+) (Fleetguard WF2073)..... <b>BW5073</b> <b>Coolant</b> (w/12 Units BTA+) (1820361-C1)..... <b>BW5074</b> <b>Coolant</b> (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b> <b>Trans. Spin-on</b> (595722-C91)..... <b>BT839-10</b> <b>Steering</b> (1681202C91)..... <b>PT8407</b>	3800 w/DT466C (7.6L) Eng. (8/30/1991-on) (Cont'd) <b>Fuel</b> (1820479-C1)..... <b>BF7531</b> <b>O. Air</b> (476741-C1)..... <b>PA2521</b> <b>I. Air</b> (482644-C1)..... <b>PA2522</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (w/o Chemical) (Fleetguard WF2101)..... <b>B5134 +</b> <b>4 3/8 In. Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>5 3/8 In. Coolant</b> (w/4 Units BTA+) (1822313-C1)..... <b>BW5082</b> <b>Coolant</b> (w/6 Units BTA+) (Fleetguard WF2072)..... <b>BW5072</b> <b>Coolant</b> (w/8 Units BTA+) (Fleetguard WF2073)..... <b>BW5073</b> <b>Coolant</b> (w/12 Units BTA+) (1820361-C1)..... <b>BW5074</b> <b>Coolant</b> (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b> <b>Trans. Spin-on</b> (595722-C91)..... <b>BT839-10</b> <b>Steering</b> (1691121-C1)..... <b>P106-HD</b>
3800 w/DT466C (7.6L) Eng. (To 8/30/1991) <b>Lube</b> (1811953-C1)..... <b>[2] B309</b> <b>Lube</b> (1819452-C1)..... <b>B7030</b> <b>Fuel/Water Separator</b> (w/Drain) (Racor S3226T)..... <b>BF1347</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (Racor S3226T)..... <b>BF1347-O</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (Racor S3226T)..... <b>BF1373-SP</b> <b>Fuel/Water Separator</b> (Fleetguard FS1205)..... <b>BF912</b> <b>Fuel/Water Separator</b> (1618386-C93)..... <b>BF1345-O</b> <b>Fuel/Water Separator</b> (702255-C1)..... <b>BF891</b> <b>Fuel/Water Separator</b> (Engs. w/S/N 618496-on) (Fleetguard FF105D)..... <b>BF957-D +</b>	3800 w/DT466C (7.6L) Eng. (8/30/1991-on) <b>Lube</b> (1811953-C1)..... <b>[2] B309</b> <b>Lube</b> (1819452-C1)..... <b>B7030</b> <b>Fuel/Water Separator</b> (w/Drain) (Racor S3226T)..... <b>BF1347</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (Racor S3226T)..... <b>BF1347-O</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (Racor S3226T)..... <b>BF1373-SP</b> <b>Fuel/Water Separator</b> (Fleetguard FS1205)..... <b>BF912</b> <b>Fuel/Water Separator</b> (1618386-C93)..... <b>BF1345-O</b> <b>Fuel/Water Separator</b> (702255-C1)..... <b>BF891</b> <b>Fuel/Water Separator</b> (Engs. w/S/N 618496-on) (Fleetguard FF105D)..... <b>BF957-D +</b> <b>P. Fuel</b> (Engs. w/S/N 567492 to 599779) (625627-C1)..... <b>BF979 +</b> <b>S. Fuel</b> (Engs. w/S/N 567492-on) (672603-C3)..... <b>BF588</b> <b>Fuel</b> (1822588-C1)..... <b>BF7629 +</b> <b>Fuel</b> (Fleetguard FF5052)..... <b>BF788</b>	3800 w/DTA466 (7.6L) Eng. (To 8/30/1991) <b>Lube</b> (1811953-C1)..... <b>[2] B309</b> <b>Lube</b> (1819452-C1)..... <b>B7030</b> <b>Fuel/Water Separator</b> (w/Drain) (Racor S3226T)..... <b>BF1347</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (Racor S3226T)..... <b>BF1347-O</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (Racor S3226T)..... <b>BF1373-SP</b> <b>Fuel/Water Separator</b> (Fleetguard FS1205)..... <b>BF912</b> <b>Fuel/Water Separator</b> (1618386-C93)..... <b>BF1345-O</b> <b>Fuel/Water Separator</b> (702255-C1)..... <b>BF891</b> <b>Fuel/Water Separator</b> (Engs. w/S/N 618496-on) (Fleetguard FF105D)..... <b>BF957-D +</b> <b>P. Fuel</b> (Engs. w/S/N 567492 to 599779) (625627-C1)..... <b>BF979 +</b> <b>S. Fuel</b> (Engs. w/S/N 567492-on) (672603-C3)..... <b>BF588</b> <b>Fuel</b> (1822588-C1)..... <b>BF7629 +</b> <b>Fuel</b> (Fleetguard FF5052)..... <b>BF788</b> <b>Fuel</b> (1820479-C1)..... <b>BF7531</b> <b>O. Air</b> (476741-C1)..... <b>PA2521</b> <b>I. Air</b> (482644-C1)..... <b>PA2522</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
3800 w/DTA466 (7.6L) Eng. (To 8/30/1991) (Cont'd)	3800 w/DTA466 (7.6L) Eng. (8/30/1991-on) (Cont'd)	3800 w/DTA466C (7.6L) Eng. (To 8/30/1991) (Cont'd)
<b>Coolant</b> (w/o Chemical) (Fleetguard WF2101)..... <b>B5134 +</b>	<b>Coolant</b> (w/6 Units BTA+) (Fleetguard WF2072)..... <b>BW5072</b>	<b>Coolant</b> (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b>
<b>4 3/8 In. Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>	<b>Coolant</b> (w/8 Units BTA+) (Fleetguard WF2073)..... <b>BW5073</b>	<b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b>
<b>5 3/8 In. Coolant</b> (w/4 Units BTA+) (1822313-C1)..... <b>BW5082</b>	<b>Coolant</b> (w/12 Units BTA+) (1820361-C1)..... <b>BW5074</b>	<b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>
<b>Coolant</b> (w/6 Units BTA+) (Fleetguard WF2072)..... <b>BW5072</b>	<b>Coolant</b> (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b>	<b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b>
<b>Coolant</b> (w/8 Units BTA+) (Fleetguard WF2073)..... <b>BW5073</b>	<b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b>	<b>Trans. Spin-on</b> (595722-C91)..... <b>BT839-10</b>
<b>Coolant</b> (w/12 Units BTA+) (1820361-C1)..... <b>BW5074</b>	<b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>	<b>Steering</b> (1681202C91)..... <b>PT8407</b>
<b>Coolant</b> (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b>	<b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b>	3800 w/DTA466C (7.6L) Eng. (8/30/1991-on)
<b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b>	<b>Trans. Spin-on</b> (595722-C91)..... <b>BT839-10</b>	<b>Lube</b> (1811953-C1)..... <b>[2] B309</b>
<b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>	<b>Steering</b> (1691121-C1)..... <b>P106-HD</b>	<b>Lube</b> (1819452-C1)..... <b>B7030</b>
<b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b>	3800 w/DTA466C (7.6L) Eng. (To 8/30/1991)	<b>Fuel/Water Separator</b> (w/Drain) (Racor S3226T)..... <b>BF1347</b>
<b>Trans. Spin-on</b> (595722-C91)..... <b>BT839-10</b>	<b>Lube</b> (1811953-C1)..... <b>[2] B309</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor S3226T)..... <b>BF1347-O</b>
<b>Steering</b> (1681202C91)..... <b>PT8407</b>	<b>Lube</b> (1819452-C1)..... <b>B7030</b>	<b>Fuel/Water Separator</b> (w/Sensor Port) (Racor S3226T)..... <b>BF1373-SP</b>
3800 w/DTA466 (7.6L) Eng. (8/30/1991-on)	<b>Fuel/Water Separator</b> (w/Drain) (Racor S3226T)..... <b>BF1347</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1205)..... <b>BF912</b>
<b>Lube</b> (1811953-C1)..... <b>[2] B309</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor S3226T)..... <b>BF1347-O</b>	<b>Fuel/Water Separator</b> (1618386-C93)..... <b>BF1345-O</b>
<b>Lube</b> (1819452-C1)..... <b>B7030</b>	<b>Fuel/Water Separator</b> (w/Sensor Port) (Racor S3226T)..... <b>BF1373-SP</b>	<b>Fuel/Water Separator</b> (702255-C1)..... <b>BF891</b>
<b>Fuel/Water Separator</b> (w/Drain) (Racor S3226T)..... <b>BF1347</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1205)..... <b>BF912</b>	<b>Fuel/Water Separator</b> (Engs. w/S/N 618496-on) (Fleetguard FF105D)..... <b>BF957-D +</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor S3226T)..... <b>BF1347-O</b>	<b>Fuel/Water Separator</b> (1618386-C93)..... <b>BF1345-O</b>	<b>P. Fuel</b> (Engs. w/S/N 567492 to 599779) (625627-C1)..... <b>BF979 +</b>
<b>Fuel/Water Separator</b> (w/Sensor Port) (Racor S3226T)..... <b>BF1373-SP</b>	<b>Fuel/Water Separator</b> (702255-C1)..... <b>BF891</b>	<b>S. Fuel</b> (Engs. w/S/N 567492-on) (672603-C3)..... <b>BF588</b>
<b>Fuel/Water Separator</b> (Fleetguard FS1205)..... <b>BF912</b>	<b>Fuel/Water Separator</b> (Engs. w/S/N 618496-on) (Fleetguard FF105D)..... <b>BF957-D +</b>	<b>Fuel</b> (1822588-C1)..... <b>BF7629 +</b>
<b>Fuel/Water Separator</b> (1618386-C93)..... <b>BF1345-O</b>	<b>Fuel</b> (1822588-C1)..... <b>BF788</b>	<b>Fuel</b> (Fleetguard FF5052)..... <b>BF788</b>
<b>Fuel/Water Separator</b> (702255-C1)..... <b>BF891</b>	<b>Fuel</b> (1820479-C1)..... <b>BF7531</b>	<b>Fuel</b> (1820479-C1)..... <b>BF7531</b>
<b>Fuel/Water Separator</b> (Engs. w/S/N 618496-on) (Fleetguard FF105D)..... <b>BF957-D +</b>	<b>O. Air</b> (476741-C1)..... <b>PA2521</b>	<b>O. Air</b> (476741-C1)..... <b>PA2521</b>
<b>P. Fuel</b> (Engs. w/S/N 567492 to 599779) (625627-C1)..... <b>BF979 +</b>	<b>I. Air</b> (482644-C1)..... <b>PA2522</b>	<b>I. Air</b> (482644-C1)..... <b>PA2522</b>
<b>S. Fuel</b> (Engs. w/S/N 567492-on) (672603-C3)..... <b>BF588</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
<b>Fuel</b> (1822588-C1)..... <b>BF7629 +</b>	<b>Coolant</b> (w/o Chemical) (Fleetguard WF2101)..... <b>B5134 +</b>	<b>Coolant</b> (w/o Chemical) (Fleetguard WF2101)..... <b>B5134 +</b>
<b>Fuel</b> (Fleetguard FF5052)..... <b>BF788</b>	<b>4 3/8 In. Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>	<b>4 3/8 In. Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>
<b>Fuel</b> (1820479-C1)..... <b>BF7531</b>	<b>5 3/8 In. Coolant</b> (w/4 Units BTA+) (1822313-C1)..... <b>BW5082</b>	<b>5 3/8 In. Coolant</b> (w/4 Units BTA+) (1822313-C1)..... <b>BW5082</b>
<b>O. Air</b> (476741-C1)..... <b>PA2521</b>	<b>Coolant</b> (w/6 Units BTA+) (Fleetguard WF2072)..... <b>BW5072</b>	<b>Coolant</b> (w/6 Units BTA+) (Fleetguard WF2072)..... <b>BW5072</b>
<b>I. Air</b> (482644-C1)..... <b>PA2522</b>	<b>Coolant</b> (w/8 Units BTA+) (Fleetguard WF2073)..... <b>BW5073</b>	<b>Coolant</b> (w/8 Units BTA+) (Fleetguard WF2073)..... <b>BW5073</b>
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Coolant</b> (w/12 Units BTA+) (1820361-C1)..... <b>BW5074</b>	<b>Coolant</b> (w/12 Units BTA+) (1820361-C1)..... <b>BW5074</b>
<b>Coolant</b> (w/o Chemical) (Fleetguard WF2101)..... <b>B5134 +</b>	<b>Coolant</b> (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b>	<b>Coolant</b> (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b>
<b>4 3/8 In. Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>	<b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b>	<b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b>
<b>5 3/8 In. Coolant</b> (w/4 Units BTA+) (1822313-C1)..... <b>BW5082</b>	<b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>	<b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>INTERNATIONAL Trucks &amp; Buses (cont'd)</b>	<b>INTERNATIONAL Trucks &amp; Buses (cont'd)</b>	<b>INTERNATIONAL Trucks &amp; Buses (cont'd)</b>
3800 w/DTA466C (7.6L) Eng. (8/30/1991-on) (Cont'd) Trans. Spin-on (Allison 29510922)..... <b>BT8316-MPG</b> Trans. Spin-on (595722-C91)..... <b>BT839-10</b> Steering (1691121-C1)..... <b>P106-HD</b>	3900FC w/DT360 (5.9L) Eng. Lube (1811953C1)..... <b>B309</b> Fuel/Water Separator (1808623C1)..... <b>BF7584 +</b> Fuel/Water Separator (1677004C91)..... <b>BF1345-O</b> Fuel (1809789C1)..... <b>BF7629 +</b> Std. O. Air (476741C1)..... <b>PA2521</b> Std. I. Air (482644C1)..... <b>PA2522</b> Radial Seal Air (1691027C1)..... <b>RS2863</b> Radial Seal XP Air (1691027C1)..... <b>RS2863XP</b> 2 25/32 In. Steering (w/o Gskt.) (279294C92)..... <b>PT951</b> 2 25/32 In. Steering (w/Gskt.) (279294C92)..... <b>PT903</b> 3 9/16 In. Steering (1653998C91)..... <b>P7134</b> 3 31/32 In. Steering (1691121C1)..... <b>P106-HD</b> 4 5/32 In. Steering (1681202C91)..... <b>PT8407</b> 5 1/32 In. Steering (1695528C1)..... <b>PT9419-MPG</b>	3900FC w/DTA360 (5.9L) Eng. (Cont'd) Std. O. Air (476741C1)..... <b>PA2521</b> Std. I. Air (482644C1)..... <b>PA2522</b> Radial Seal Air (1691027C1)..... <b>RS2863</b> Radial Seal XP Air (1691027C1)..... <b>RS2863XP</b> 2 25/32 In. Steering (w/o Gskt.) (279294C92)..... <b>PT951</b> 2 25/32 In. Steering (w/Gskt.) (279294C92)..... <b>PT903</b> 3 9/16 In. Steering (1653998C91)..... <b>P7134</b> 3 31/32 In. Steering (1691121C1)..... <b>P106-HD</b> 4 5/32 In. Steering (1681202C91)..... <b>PT8407</b> 5 1/32 In. Steering (1695528C1)..... <b>PT9419-MPG</b> 4000 Series w/GMC 6-71, 6V-71N Engs. F-F Lube Ele..... <b>P20-HD</b> P. Fuel Sock..... <b>F916-C</b> S. Fuel Ele..... <b>PF902</b> Tube-Type Air (6483682)..... <b>PA1781</b> Air (8873271)..... <b>PA1637-FN</b> 4000 Series w/GMC 8V-71N Eng. F-F Lube Ele..... <b>P20-HD</b> P. Fuel Ele..... <b>PF845</b> S. Fuel Ele..... <b>PF902</b> Air (304766-C91)..... <b>PA1676-FN +</b> 4000 Series w/DV462, DV550 Diesel Engs. Lube Ele. (313117-C92)..... <b>[2] P276</b> Lube Spin-on (427207-C2)..... <b>[2] B167</b> P. Fuel Spin-on (S/N 7164-up).... <b>BF979 +</b> S. Fuel Ele. (S/N 5118-7163)..... <b>PF225</b> S. Fuel Spin-on (S/N 7164-up).... <b>BF588</b> P. Fuel Spin-on (To S/N 5118).... <b>BF968</b> Air (S/N 36674-up) (303642-C91) <b>PA1786</b> 4000 Series w/DVT573 Eng. Lube..... <b>PT86-HD</b> P. Fuel Spin-on (S/N 1934-up).... <b>BF979 +</b> S. Fuel Spin-on (S/N 1934-up).... <b>BF588</b> Fuel Ele. (To S/N 1934)..... <b>[2] PF225</b> 4070 Transtar II Series w/Cat 3406 Eng. Lube..... <b>B99 +</b> Fuel Spin-on..... <b>BF614 +</b> Air (420051-C1)..... <b>PA2333</b> Coolant Spin-on..... <b>BW5137</b> 4070 Transtar II Series w/Cummins Eng. F-F Lube Bag..... <b>P996</b> F-F Lube Ele..... <b>P999-HD</b> F-F Lube Spin-on..... <b>B196 +</b> B-P Lube Ele..... <b>C750-E +</b> Fuel/Water Separator..... <b>BF1212 +</b> 5 7/16 In. Fuel Spin-on..... <b>BF957 +</b> 11 7/32 In. Fuel Spin-on..... <b>BF596 +</b> Air (420051-C1)..... <b>PA2333</b> Air (8873271)..... <b>PA1637-FN</b> Breather Ele. (w/Turbo) (255963) <b>PA643</b> Breather Ele. (w/o Turbo) (256837)..... <b>PA1627</b>
3800 w/T444E (7.3L) Eng. (To 8/30/1991) Lube (1814562-C1)..... <b>B7039</b> Fuel/Water Separator (1618385-C91)..... <b>BF1345-O</b> Fuel Ele. (2/94-1998) (1825864-C92)..... <b>PF7698</b> Fuel Ele. (1999-on) (1822631-C91)..... <b>PF7678</b> O. Air (476741-C1)..... <b>PA2521</b> I. Air (482644-C1)..... <b>PA2522</b> Radial Seal Air (1691027C1)..... <b>RS2863</b> Radial Seal XP Air (1691027C1)..... <b>RS2863XP</b> Air Dryer (Bendix 107796)..... <b>BA5377</b> Coolant (w/4 Units BTA+) (1822627-C1)..... <b>BW5071</b> Coolant (w/8 Units BTE) (1801089-C1)..... <b>BW5139</b> Trans. Pan-Type (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> Trans. Pan-Type (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> Trans. Spin-on (Allison 29510922)..... <b>BT8316-MPG</b> Trans. Spin-on (595722-C91)..... <b>BT839-10</b> Steering (1681202C91)..... <b>PT8407</b> Steering (1695528-C1)..... <b>PT9419-MPG</b>	3900FC w/DT408 (6.7L) Eng. Lube (1819452C1)..... <b>B7030</b> Fuel/Water Separator (1677004C91)..... <b>BF1345-O</b> 5 7/8 In. Fuel (1820479C1)..... <b>BF7531</b> 7 In. Fuel (1809789C1)..... <b>BF7629 +</b> Std. O. Air (476741C1)..... <b>PA2521</b> Std. I. Air (482644C1)..... <b>PA2522</b> Radial Seal Air (1691027C1)..... <b>RS2863</b> Radial Seal XP Air (1691027C1)..... <b>RS2863XP</b> Coolant (1822313C1)..... <b>BW5082</b> Steering (1691121C1)..... <b>P106-HD</b>	4000 Series w/DV462, DV550 Diesel Engs. Lube Ele. (313117-C92)..... <b>[2] P276</b> Lube Spin-on (427207-C2)..... <b>[2] B167</b> P. Fuel Spin-on (S/N 7164-up).... <b>BF979 +</b> S. Fuel Ele. (S/N 5118-7163)..... <b>PF225</b> S. Fuel Spin-on (S/N 7164-up).... <b>BF588</b> P. Fuel Spin-on (To S/N 5118).... <b>BF968</b> Air (S/N 36674-up) (303642-C91) <b>PA1786</b>
3800 w/T444E (7.3L) Eng. (8/30/1991-on) Lube (1814562-C1)..... <b>B7039</b> Fuel/Water Separator (1618385-C91)..... <b>BF1345-O</b> Fuel Ele. (1825864-C92)..... <b>PF7698</b> Fuel Ele. (1822631-C91)..... <b>PF7678</b> O. Air (476741-C1)..... <b>PA2521</b> I. Air (482644-C1)..... <b>PA2522</b> Radial Seal Air (1691027C1)..... <b>RS2863</b> Radial Seal XP Air (1691027C1)..... <b>RS2863XP</b> Air Dryer (Bendix 107796)..... <b>BA5377</b> Coolant (w/4 Units BTA+) (1822627-C1)..... <b>BW5071</b> Coolant (w/8 Units BTE) (1801089-C1)..... <b>BW5139</b> Trans. Pan-Type (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> Trans. Pan-Type (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> Trans. Spin-on (Allison 29510922)..... <b>BT8316-MPG</b> Trans. Spin-on (595722-C91)..... <b>BT839-10</b> Steering (1691121-C1)..... <b>P106-HD</b> Steering (1695528-C1)..... <b>PT9419-MPG</b>	3900FC w/DT466 (7.6L) Eng. Lube (1-12 Thd.) (1811953C1).... <b>B309</b> Lube (M36 x 1.5 Thd.) (1819452C1)..... <b>B7030</b> Fuel/Water Separator (1677004C91)..... <b>BF1345-O</b> 5 5/16 In. Fuel (625625C1)..... <b>BF984</b> 5 7/8 In. Fuel (1820479C1)..... <b>BF7531</b> 7 In. Fuel (1822588C1)..... <b>BF7629 +</b> Std. O. Air (476741C1)..... <b>PA2521</b> Std. I. Air (482644C1)..... <b>PA2522</b> Coolant (1822313C1)..... <b>BW5082</b> 2 25/32 In. Steering (w/o Gskt.) (279294C92)..... <b>PT951</b> 2 25/32 In. Steering (w/Gskt.) (279294C92)..... <b>PT903</b> 3 31/32 In. Steering (1691121C1)..... <b>P106-HD</b>	4070 Transtar II Series w/Cummins Eng. F-F Lube Bag..... <b>P996</b> F-F Lube Ele..... <b>P999-HD</b> F-F Lube Spin-on..... <b>B196 +</b> B-P Lube Ele..... <b>C750-E +</b> Fuel/Water Separator..... <b>BF1212 +</b> 5 7/16 In. Fuel Spin-on..... <b>BF957 +</b> 11 7/32 In. Fuel Spin-on..... <b>BF596 +</b> Air (420051-C1)..... <b>PA2333</b> Air (8873271)..... <b>PA1637-FN</b> Breather Ele. (w/Turbo) (255963) <b>PA643</b> Breather Ele. (w/o Turbo) (256837)..... <b>PA1627</b>
3900FC w/DTA360 (5.9L) Eng. Lube (1811953C1)..... <b>B309</b> Fuel/Water Separator (1808623C1)..... <b>BF7584 +</b> Fuel/Water Separator (1677004C91)..... <b>BF1345-O</b> Fuel (1809789C1)..... <b>BF7629 +</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
4070 Transtar II Series w/Cummins Eng. (Cont'd) Coolant Spin-on..... BW5071 Turbocharger..... BT112	4100 w/VT365 (6.0L) Eng. (Cont'd) Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016 Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003 Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017 Trans. Spin-on (Allison 29539579)..... BT8460 Steering (2503221-C1)..... BT9388	4200 DuraStar w/MaxxForce 6 Eng. (Mexico) (Cont'd) Fuel/Water Separator (Open End for Bowl) (1816568-C91)..... BF1222-O + Fuel (1825864-C92)..... PF7698 Radial Seal O. Air (3532799-C1)..... RS4636 + Radial Seal I. Air (3532800-C1)..... RS4637
4070 Transtar II Series w/GMC Eng. F-F Lube Ele..... P20-HD F-F Lube Spin-on..... B95 + P. Fuel Spin-on..... BF5800 + S. Fuel Spin-on..... BF5810 Air (420051-C1)..... PA2333	4100 SBA w/VT365 (6.0L) Eng. Lube (w/o Screw on Cap) (1840752-C91)..... P7235 Lube (w/Screw on Cap) (Wix 57312)..... P7436 Fuel/Water Separator (1878042-C91)..... PF7978 Fuel Strainer (1873910-C91)..... PF7994 Radial Seal O. Air (3532799-C1)..... RS4636 + Radial Seal I. Air (3532800-C1)..... RS4637 Cab Air (2506656-C1)..... PA4985 Air Dryer (Wabco R950011)..... BA5374 + Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004 Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016 Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003 Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017 Trans. Spin-on (Allison 29539579)..... BT8460 Steering (2503221-C1)..... BT9388	4200 DuraStar w/VT230 Eng. Lube (w/o Screw on Cap) (1840752-C91)..... P7235 Lube (w/Screw on Cap) (Wix 57312)..... P7436 Fuel (1825864-C92)..... PF7698 Radial Seal O. Air (3532799-C1)..... RS4636 + Radial Seal I. Air (3532800-C1)..... RS4637 Cab Air (2506656-C1)..... PA4985 Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004 Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016 Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003 Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017 Trans. Spin-on (Allison 29539579)..... BT8460 Steering (2503221-C1)..... BT9388
4070 Transtar II Series w/V800 Eng. Lube Ele..... [2] PT86-HD Lube Spin-on..... [2] B97 Fuel/Water Separator..... BF891 P. Fuel Spin-on..... BF979 + 7 11/32 In. S. Fuel Spin-on..... BF588 8 11/16 In. S. Fuel Spin-on..... BF888 Air (420051-C1)..... PA2333 Coolant Spin-on..... BW5137	4100 Transtar Conco w/Cummins Eng. F-F Lube Spin-on..... B196 + B-P Lube Ele..... C750-E + Fuel/Water Separator..... BF1212 + 5 3/4 In. Fuel Spin-on..... BF957 + 11 7/32 In. Fuel Spin-on..... BF596 + Breather Ele. (w/Turbo) (255963) PA643 Breather Ele. (w/o Turbo) (256837)..... PA1627	4200 DuraStar w/VT365 (6.0L) Eng. Lube (w/o Screw on Cap) (1840752-C91)..... P7235 Lube (w/Screw on Cap) (Wix 57312)..... P7436 Opt. Fuel/Water Separator (w/o SP) (1816568C91)..... BF1223 + Opt. Fuel/Water Separator (w/SP) (1816568C91)..... BF1223-SP + Fuel (1825864-C92)..... PF7698 Radial Seal O. Air (3532799-C1)..... RS4636 + Radial Seal I. Air (3532800-C1)..... RS4637 Cab Air (2506656-C1)..... PA4985 Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004 Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016 Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003 Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017 Trans. Spin-on (Allison 29539579)..... BT8460 Steering (2503221-C1)..... BT9388
4100 w/MaxxForce 7 (6.4L) Eng. Lube (w/o Screw on Cap) (1840752-C91)..... P7235 Lube (w/Screw on Cap) (Wix 57312)..... P7436 Fuel/Water Separator (1878042-C91)..... PF7978 Fuel Strainer (1873910-C91)..... PF7994 Radial Seal O. Air (3532799-C1)..... RS4636 + Radial Seal I. Air (3532800-C1)..... RS4637 Cab Air (2506656-C1)..... PA4985 Air Dryer (Wabco R950011)..... BA5374 + Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004 Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016 Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003 Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017 Trans. Spin-on (Allison 29539579)..... BT8460 Steering (2503221-C1)..... BT9388	4100 Transtar Conco w/GMC 8V-71, 8V-92T Eng. F-F Lube Ele..... P20-HD B-P Lube Ele..... C750-E + P. Fuel Spin-on..... BF5800 + S. Fuel Spin-on..... BF5810	4200LP DuraStar w/VT365 (6.0L) Eng. Lube (w/o Screw on Cap) (1840752-C91)..... P7235 Lube (w/Screw on Cap) (Wix 57312)..... P7436 Opt. Fuel/Water Separator (w/o SP) (1816568C91)..... BF1223 +

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
4200LP DuraStar w/VT365 (6.0L) Eng. (Cont'd) <b>Opt. Fuel/Water Separator</b> (w/SP) (1816568C91)..... <b>BF1223-SP +</b> <b>Fuel</b> (1825864-C92)..... <b>PF7698</b> <b>Radial Seal O. Air</b> (3532799-C1)..... <b>RS4636 +</b> <b>Radial Seal I. Air</b> (3532800-C1)..... <b>RS4637</b> <b>Cab Air</b> (2506656-C1)..... <b>PA4985</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Steering</b> (2503221-C1)..... <b>BT9388</b>	4300 w/Cummins B6.7 (6.7L) Eng. (2019) (Cont'd) <b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Crankcase Breather</b> (4936636)..... <b>CV15010</b>	4300 w/Cummins ISB (6.7L) Eng. (2014-17) (Cont'd) <b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (2503221-C1)..... <b>BT9388</b> <b>Diesel Exhaust Fluid</b> (5303604)..... <b>PE17000</b>
4270, 4370 Transtar Series w/Cat 3406 Eng. <b>Lube</b> ..... <b>B99 +</b> <b>Fuel Spin-on</b> ..... <b>BF614 +</b> <b>Air</b> (420051-C1)..... <b>PA2333</b> <b>Coolant</b> ..... <b>BW5137</b>	4300 w/Cummins B6.7 (6.7L) Eng. (2020) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Primary EnduraCube Air</b> (2517298C1)..... <b>PA32001</b> <b>Secondary EnduraCube Air</b> (2602211C1)..... <b>PA32004</b> <b>Cab Air</b> (CFN6100)..... <b>PA30260</b> <b>Air Dryer</b> (Bendix 65624)..... <b>BA5373</b> <b>Crankcase Breather</b> (4936636)..... <b>CV15010</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	4300 w/Cummins ISB 6.7 (6.7L) Eng. (2018) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel/Water Separator</b> (2514003C1)..... <b>BF46181-O</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> <b>Primary EnduraCube Air</b> (2602212C1)..... <b>PA32001</b> <b>Secondary EnduraCube Air</b> (2602211C1)..... <b>PA32004</b> <b>Cab Air</b> (3839141C1)..... <b>PA5679</b> <b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b> <b>Crankcase Breather</b> (4936636)..... <b>CV15010</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Diesel Exhaust Fluid</b> (4388378)..... <b>PE17002 KIT</b>
4270, 4370 Series w/GMC 6V-92, 8V-71, 8V-92 Series Engs. <b>F-F Lube Ele.</b> ..... <b>P20-HD</b> <b>P. Fuel Spin-on</b> ..... <b>BF5800 +</b> <b>S. Fuel Spin-on</b> ..... <b>BF5810</b> <b>Air</b> (420051-C1)..... <b>PA2333</b>	4300 w/Cummins ISB (6.7L) Eng. (2014-17) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel/Water Separator</b> (4934879)..... <b>BF1378-SPS</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Fuel</b> (5660774)..... <b>BF63000</b> <b>Primary EnduraCube Air</b> (2602212-C1)..... <b>PA32001</b> <b>Secondary EnduraCube Air</b> (2602211-C1)..... <b>PA32004</b> <b>Cab Air</b> (3839141-C1)..... <b>PA5679</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-IS, AD-SP System) (Bendix 109994)..... <b>BA5374 +</b> <b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b> <b>Crankcase Breather</b> (4936636)..... <b>CV15010</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	4300 w/Cummins ISB 6.7 (6.7L) Eng. (2019) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel/Water Separator</b> (4080114C2)..... <b>BF46169-O</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Primary EnduraCube Air</b> (2517298C1)..... <b>PA32001</b> <b>Secondary EnduraCube Air</b> (2602211C1)..... <b>PA32004</b> <b>Cab Air</b> (3839141C1)..... <b>PA5679</b> <b>Air Dryer</b> (Bendix 65624)..... <b>BA5373</b> <b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>
4270, 4370 Transtar Series w/V800 Eng. <b>Lube Ele.</b> ..... <b>[2] PT86-HD</b> <b>Lube Spin-on</b> ..... <b>[2] B97</b> <b>Fuel/Water Separator</b> ..... <b>BF891</b> <b>P. Fuel Spin-on</b> ..... <b>BF979 +</b> <b>7 11/32 In. S. Fuel Spin-on</b> ..... <b>BF588</b> <b>8 11/16 In. S. Fuel Spin-on</b> ..... <b>BF888</b> <b>Coolant Spin-on</b> ..... <b>BW5137</b>	4300 w/Cummins B6.7 (6.7L) Eng. (2019) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel/Water Separator</b> (4080114C2)..... <b>BF46169-O</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Primary EnduraCube Air</b> (2517298C1)..... <b>PA32001</b> <b>Secondary EnduraCube Air</b> (2602211C1)..... <b>PA32004</b> <b>Cab Air</b> (3839141C1)..... <b>PA5679</b> <b>Air Dryer</b> (Bendix 65624)..... <b>BA5373</b> <b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
4300 w/Cummins ISB 6.7 (6.7L) Eng. (2019) (Cont'd)	4300 DuraStar w/DT466 (7.6L) Eng. (Cont'd)	4300 w/MaxxForce DT (7.6L) Eng. (2012-17)
Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	<b>Cab Air</b> (2506656-C1)..... <b>PA4985</b>	<b>Lube</b> (1889124-C91)..... <b>B7503</b>
<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	<b>Air Dryer</b> (AD-SP System) (Bendix 109994)..... <b>BA5374 +</b>	<b>Fuel/Water Separator</b> (1878042-C92)..... <b>PF7978</b>
<b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Fuel/Water Separator</b> (1822638-C91)..... <b>PF7779</b>
4300 w/Cummins ISB 6.7 (6.7L) Eng. (2020)	<b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b>	<b>Fuel Strainer</b> (1873910-C91)..... <b>PF7994</b>
<b>Lube</b> (3937736)..... <b>B7177</b>	<b>Coolant</b> (1822627-C1)..... <b>BW5071</b>	<b>Primary EnduraCube Air</b> (2602212-C1)..... <b>PA32001</b>
<b>Fuel</b> (5303743)..... <b>BF63000</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Secondary EnduraCube Air</b> (2602211-C1)..... <b>PA32004</b>
<b>Primary EnduraCube Air</b> (2517298C1)..... <b>PA32001</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Cab Air</b> (6 5/32 In. Width) (3839141-C1)..... <b>PA5679</b>
<b>Secondary EnduraCube Air</b> (2602211C1)..... <b>PA32004</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Cab Air</b> (7 1/4 In. Width) (2506656-C1)..... <b>PA4985</b>
<b>Cab Air</b> (CFFN6100)..... <b>PA30260</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Air Dryer</b> (AD-SP System) (Bendix 109994)..... <b>BA5374 +</b>
<b>Air Dryer</b> (Bendix 65624)..... <b>BA5373</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
<b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29526899)..... <b>PT9416-MPG KIT</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>
4300 w/Cummins L9 Eng. (2018)	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29526898)..... <b>PT9415-MPG KIT</b>	<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>
<b>Lube</b> (3401544)..... <b>B40142</b>	<b>Steering</b> (2503221-C1)..... <b>BT9388</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Fuel/Water Separator</b> (2514003C1)..... <b>BF46181-O</b>	4300 w/MaxxForce DT (7.6L) Eng. (To 2012)	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Fuel</b> (Fleetguard FF63008)..... <b>BF63000</b>	<b>Dual-Flow Lube</b> (1842639-C91).. <b>BD7250</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Primary EnduraCube Air</b> (2602212C1)..... <b>PA32001</b>	<b>Fuel/Water Separator</b> (1878042-C92)..... <b>PF7978</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
<b>Secondary EnduraCube Air</b> (2602211C1)..... <b>PA32004</b>	<b>Fuel/Water Separator</b> (1822638-C91)..... <b>PF7779</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>Cab Air</b> (3839141C1)..... <b>PA5679</b>	<b>Fuel Strainer</b> (1873910-C91)..... <b>PF7994</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
<b>Cab Air</b> (CFFN6100)..... <b>PA30260</b>	<b>Radial Seal O. Air</b> (3532799-C1).. <b>RS4636 +</b>	<b>Steering</b> (2503221-C1)..... <b>BT9388</b>
<b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b>	<b>Radial Seal I. Air</b> (3532800-C1)... <b>RS4637</b>	4300 w/MaxxForce DT (7.6L) Eng. (2018)
<b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	<b>Cab Air</b> (6 5/32 In. Width) (3839141-C1)..... <b>PA5679</b>	<b>Lube</b> (1889124C91)..... <b>B7503</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	<b>Cab Air</b> (7 1/4 In. Width) (2506656-C1)..... <b>PA4985</b>	<b>Fuel/Water Separator</b> (1878042C91)..... <b>PF7978</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	<b>Air Dryer</b> (AD-SP System) (Bendix 109994)..... <b>BA5374 +</b>	<b>Fuel</b> (1876533C93)..... <b>BF9858 KIT</b>
4300 w/Detroit Diesel Series 50 (8.5L) Eng.	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Primary EnduraCube Air</b> (2602212C1)..... <b>PA32001</b>
<b>Lube</b> (23530573)..... <b>[2] B495</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Secondary EnduraCube Air</b> (2602211C1)..... <b>PA32004</b>
<b>Fuel/Water Separator Spin-on</b> (w/Drain) (23535985)..... <b>BF5813 +</b>	<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>	<b>Cab Air</b> (3839141C1)..... <b>PA5679</b>
<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (23535985).. <b>BF5813-O +</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b>
<b>P. Fuel</b> (23530706)..... <b>BF5800 +</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>S. Fuel</b> (23530707)..... <b>BF5810</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29526898)..... <b>PT9415-MPG KIT</b>
4300 DuraStar w/DT466 (7.6L) Eng.	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	4300 w/MaxxForce 7 (6.4L) Eng. (To 2012)
<b>F-F Lube</b> (1819452-C1)..... <b>B7030</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Lube Ele.</b> (w/o Screw on Cap) (1840752-C91)..... <b>P7235</b>
<b>Dual-Flow Lube</b> (1842655-C91).. <b>BD7252</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Lube Ele.</b> (w/Screw on Cap) (Wix 57312)..... <b>P7436</b>
<b>Dual-Flow Lube</b> (1842639-C91).. <b>BD7250</b>	<b>Steering</b> (2503221-C1)..... <b>BT9388</b>	<b>Lube Spin-on</b> (1899332C-91)..... <b>B7506</b>
<b>B-P Lube Spinner</b> (1842825-C91)..... <b>BC7394</b>		<b>Fuel/Water Separator</b> (1878042-C91)..... <b>PF7978</b>
<b>Fuel/Water Separator Ele.</b> (1842638-C91)..... <b>PF7779</b>		
<b>Fuel/Water Separator Ele.</b> (1878042-C91)..... <b>PF7978</b>		
<b>Fuel Spin-on</b> (7/8-14 Thd.) (1822588-C1)..... <b>BF7629 +</b>		
<b>Fuel Spin-on</b> (M16 x 1.5 Thd.) (Fleetguard FF5052)..... <b>BF788</b>		
<b>Radial Seal O. Air</b> (3532799-C1).. <b>RS4636 +</b>		
<b>Radial Seal I. Air</b> (3532800-C1)... <b>RS4637</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>INTERNATIONAL Trucks &amp; Buses (cont'd)</b>	<b>INTERNATIONAL Trucks &amp; Buses (cont'd)</b>	<b>INTERNATIONAL Trucks &amp; Buses (cont'd)</b>
4300 w/MaxxFace 7 (6.4L) Eng. (To 2012) (Cont'd)	4300 w/MaxxFace 7 (6.4L) Eng. (2012-on) (Cont'd)	4300LP w/Cummins ISB 6.7 (6.7L) Eng. (2016-17) (Cont'd)
<b>Fuel Strainer</b> (1873910-C91)..... <b>PF7994</b>	<b>Crankcase Breather</b> (7085773C91)..... <b>N/S</b>	<b>Secondary EnduraCube Air</b> (2602211-C1)..... <b>PA32004</b>
<b>Fuel Kit</b> (1876533-C93)..... <b>BF9858 KIT</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Cab Air</b> (3839141-C1)..... <b>PA5679</b>
<b>Radial Seal O. Air</b> (3532799-C1)..... <b>RS4636 +</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
<b>Radial Seal I. Air</b> (3532800-C1)..... <b>RS4637</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Air Dryer</b> (AD-IS, AD-SP System) (Bendix 109994)..... <b>BA5374 +</b>
<b>Cab Air</b> (6 5/32 In. Width) (3839141-C1)..... <b>PA5679</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b>
<b>Cab Air</b> (7 1/4 In. Width) (2506656-C1)..... <b>PA4985</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Crankcase Breather</b> (4936636)..... <b>CV15010</b>
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Air Dryer</b> (AD-SP System) (Bendix 109994)..... <b>BA5374 +</b>	<b>Steering</b> (2503221-C1)..... <b>BT9388</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>		<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Crankcase Breather</b> (7085773C91)..... <b>N/S</b>		<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	4300 w/VT365 (6.0L) Eng.	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Lube</b> (w/o Screw-on Cap) (1844588C91)..... <b>P7235</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Lube</b> (w/Screw on Cap)..... <b>P7436</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Fuel Ele.</b> (1825864C92)..... <b>PF7698</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	4300LP w/Cummins B6.7 (6.7L) Eng. (2019)	<b>Steering</b> (2503221-C1)..... <b>BT9388</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Lube</b> (3937736)..... <b>B7177</b>	<b>Diesel Exhaust Fluid</b> (5303604)..... <b>PE17000</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Fuel/Water Separator</b> (4080114C2)..... <b>BF46169-O</b>	<b>Diesel Exhaust Fluid</b> (5303604)..... <b>PE17000</b>
<b>Steering</b> (2503221-C1)..... <b>BT9388</b>	<b>Fuel</b> (5303743)..... <b>BF63000</b>	
	<b>Primary EnduraCube Air</b> (2517298C1)..... <b>PA32001</b>	4300LP w/Cummins ISB 6.7 (6.7L) Eng. (2018)
	<b>Cab Air</b> (3839141C1)..... <b>PA5679</b>	<b>Lube</b> (3937736)..... <b>B7177</b>
	<b>Air Dryer</b> (Bendix 65624)..... <b>BA5373</b>	<b>Fuel/Water Separator</b> (2514003C1)..... <b>BF46181-O</b>
	<b>Air Dryer</b> (Wabco R950011)..... <b>BA5374</b>	<b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b>
	<b>Crankcase Breather</b> (4936636)..... <b>CV15010</b>	<b>Primary EnduraCube Air</b> (2602212C1)..... <b>PA32001</b>
	<b>Trans.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	<b>Secondary EnduraCube Air</b> (2602211C1)..... <b>PA32004</b>
	<b>Trans.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	<b>Cab Air</b> (3839141C1)..... <b>PA5679</b>
	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b>
	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Crankcase Breather</b> (4936636)..... <b>CV15010</b>
	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
		<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
	4300LP w/Cummins ISB 6.7 (6.7L) Eng. (2016-17)	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>
	<b>Lube</b> (3937736)..... <b>B7177</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>
	<b>Fuel/Water Separator</b> (4934879)..... <b>BF1378-SPS</b>	<b>Diesel Exhaust Fluid</b> (4388378)..... <b>PE17002 KIT</b>
	<b>Fuel</b> (5303743)..... <b>BF63000</b>	
	<b>Primary EnduraCube Air</b> (2602212-C1)..... <b>PA32001</b>	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
4300LP w/Cummins ISB 6.7 (6.7L) Eng. (2019) Lube (3937736)..... <b>B7177</b> Fuel/Water Separator (4080114C2)..... <b>BF46169-O</b> Fuel (5303743)..... <b>BF63000</b> Primary EnduraCube Air (2517298C1)..... <b>PA32001</b> Secondary EnduraCube Air (2602211C1)..... <b>PA32004</b> Cab Air (3839141C1)..... <b>PA5679</b> Air Dryer (Bendix 65624)..... <b>BA5373</b> Air Dryer (Wabco R950011)..... <b>BA5374 +</b> Crankcase Breather (4936636)..... <b>CV15010</b> Trans. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	4300LP DuraStar w/MaxxFORCE DT Eng. Dual-Flow Lube (1842639-C91).. <b>BD7250</b> Fuel/Water Separator (1878042-C91)..... <b>PF7978</b> Fuel/Water Separator (1822638-C91)..... <b>PF7779</b> Fuel Strainer (1873910-C91)..... <b>PF7994</b> Radial Seal O. Air (3532799-C1).. <b>RS4636 +</b> Radial Seal I. Air (3532800-C1)... <b>RS4637</b> Cab Air (2506656-C1)..... <b>PA4985</b> Air Dryer (Bendix 109994)..... <b>BA5374 +</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Steering (2503221-C1)..... <b>BT9388</b>	4400 w/Cummins ISL 8.9 (8.9L) Eng. (2017) Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309 +</b> Fuel (Fleetguard FF63009)..... <b>BF63000</b> Primary EnduraCube Air (2602212C1)..... <b>PA32001</b> Secondary EnduraCube Air (2602211C1)..... <b>PA32004</b> Air Dryer (Bendix 107794)..... <b>BA5377</b> Trans. Ele. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> Diesel Exhaust Fluid (5303604).. <b>PE17000</b>
4300LP DuraStar w/DT466 (7.6L) Eng. Dual-Flow Lube (1842639-C91).. <b>BD7250</b> Fuel/Water Separator Ele. (1842638-C91)..... <b>PF7779</b> Fuel/Water Separator Ele. (1878042C91)..... <b>PF7978</b> Fuel/Water Separator Spin-on (1677004-C91)..... <b>BF1345-O</b> Fuel (1822588-C1)..... <b>BF7629 +</b> Radial Seal O. Air (3532799-C1).. <b>RS4636 +</b> Radial Seal I. Air (3532800-C1)... <b>RS4637</b> Cab Air (2506656-C1)..... <b>PA4985</b> Air Dryer (Bendix 109994)..... <b>BA5374 +</b> Coolant (Fleetguard WF2071)..... <b>BW5071</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Trans. Ele. (2 In. Kit) (Allison 29526899)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29526898)..... <b>PT9415-MPG KIT</b> Steering (2503221-C1)..... <b>BT9388</b>	4300LP DuraStar w/MaxxFORCE 7 Eng. Lube (w/o Screw on Cap) (1840752-C91)..... <b>P7235</b> Lube (w/Screw on Cap) (Wix 57312)..... <b>P7436</b> Fuel/Water Separator (1878042-C91)..... <b>PF7978</b> Fuel Strainer (1873910-C91)..... <b>PF7994</b> Radial Seal O. Air (3532799-C1).. <b>RS4636 +</b> Radial Seal I. Air (3532800-C1)... <b>RS4637</b> Cab Air (2506656-C1)..... <b>PA4985</b> Air Dryer (Bendix 109994)..... <b>BA5374 +</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Steering (2503221-C1)..... <b>BT9388</b>	4400 w/Cummins ISL 8.9 (8.9L) Eng. (2018) Lube (3937736)..... <b>B7177</b> Fuel/Water Separator (2514003C1)..... <b>BF46181-O</b> Fuel (Fleetguard FF63008)..... <b>BF63000</b> Primary EnduraCube Air (2602212C1)..... <b>PA32001</b> Secondary EnduraCube Air (2602211C1)..... <b>PA32004</b> Cab Air (3839141C1)..... <b>PA5679</b> Air Dryer (Wabco R950011)..... <b>BA5374 +</b> Crankcase Breather (4936636)..... <b>CV15010</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>
		4400 w/Cummins ISL 8.9 (8.9L) Eng. (2019) Lube (3401544)..... <b>B40142</b> Fuel/Water Separator (4080114C2)..... <b>BF46169-O</b> Fuel (5303743)..... <b>BF63000</b> Primary EnduraCube Air (2517298C1)..... <b>PA32001</b> Secondary EnduraCube Air (2602211C1)..... <b>PA32004</b> Cab Air (3839141C1)..... <b>PA5679</b> Air Dryer (Bendix 65924)..... <b>BA5373</b> Air Dryer (Wabco R950011)..... <b>BA5374 +</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>
		4400 w/Cummins ISL 8.9 (8.9L) Eng. (2020) Lube (5444774)..... <b>B40142</b> Fuel/Water Separator (4080114C2)..... <b>BF46169-O</b> Fuel (5303743)..... <b>BF63000</b> Primary EnduraCube Air (2517298C1)..... <b>PA32001</b> Secondary EnduraCube Air (2602211C1)..... <b>PA32004</b> Cab Air (CFN6100)..... <b>PA30260</b> Air Dryer (Bendix 65624)..... <b>BA5373</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
4400 w/Cummins ISL 8.9 (8.9L) Eng. (2020) (Cont'd)	4400 w/Detroit Diesel Series 50 (8.5L) Eng. (Cont'd)	4400 DuraStar w/DT466 (7.6L) Eng. (Cont'd)
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Trans. Ele.</b> (HT Series) (Allison 29510918)..... <b>PT8330-MPG</b>	<b>Fuel Spin-on</b> ..... <b>BF7629 +</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Trans. Ele.</b> (MT Series) (Allison 29510922)..... <b>BT8316-MPG</b>	<b>Radial Seal O. Air</b> (3532799-C1)..... <b>RS4636 +</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Trans. Pan-Type</b> (MT Series) (Allison 29538489)..... <b>19739</b>	<b>Radial Seal I. Air</b> (3532800-C1)..... <b>RS4637</b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Steering</b> (2503221C1)..... <b>BT9388</b>	<b>Cab Air</b> (2506656-C1)..... <b>PA4985</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	4400 w/N9 (9.3L) Eng. (2015-18)	<b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b>
4400 w/Cummins L9 (9.0L) Eng. (2018)	<b>Lube</b> (1884508C2)..... <b>B7503</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Lube</b> (3401544)..... <b>B40142</b>	<b>Fuel/Water Separator</b> (1878042C93)..... <b>PF7978</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Fuel/Water Separator</b> (2514003C1)..... <b>BF46181-O</b>	<b>Primary EnduraCube Air</b> (2602212C1)..... <b>PA32001</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
<b>Fuel</b> (5303743)..... <b>BF63000</b>	<b>Secondary EnduraCube Air</b> (2602211C1)..... <b>PA32004</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>Primary EnduraCube Air</b> (2602212C1)..... <b>PA32001</b>	<b>Cab Air</b> (3839141C1)..... <b>PA5679</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29526899)..... <b>PT9416-MPG KIT</b>
<b>Secondary EnduraCube Air</b> (2602211C1)..... <b>PA32004</b>	<b>Air Dryer</b> (Bendix 107794)..... <b>BA5377</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29526898)..... <b>PT9415-MPG KIT</b>
<b>Cab Air</b> (3839141C1)..... <b>PA5679</b>	<b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b>	<b>Steering</b> (2503221-C1)..... <b>BT9388</b>
<b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b>	<b>Trans.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	4400 DuraStar w/DT530 (8.7L) Eng.
<b>Crankcase Breather</b> (4936636)..... <b>CV15010</b>	<b>Trans.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	<b>F-F Lube</b> ..... <b>B7030</b>
<b>Trans.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	<b>Diesel Exhaust Fluid</b> (5303604)..... <b>PE17000</b>	<b>Dual-Flow Lube</b> (1842639-C91)..... <b>BD7250</b>
<b>Trans.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	4400 w/N9 (9.3L) Eng. (2019)	<b>B-P Lube</b> (1842816-C2)..... <b>B7314</b>
4400 w/Cummins L9 (9.0L) Eng. (2019)	<b>F-F Lube</b> (1884508C2)..... <b>B7503</b>	<b>Fuel/Water Separator Ele.</b> (1842638-C91)..... <b>PF7779</b>
<b>Lube</b> (3401544)..... <b>B40142</b>	<b>Centrifugal Lube</b> (2606467C91)..... <b>BC7485</b>	<b>Fuel Spin-on</b> ..... <b>BF7629 +</b>
<b>Fuel/Water Separator</b> (Fleetguard FS19551)..... <b>BF1390-O</b>	<b>Fuel/Water Separator</b> (1873917C91)..... <b>PF7978</b>	<b>Radial Seal O. Air</b> (3532799-C1)..... <b>RS4636 +</b>
<b>Fuel/Water Separator</b> (4080114C2)..... <b>BF46169-O</b>	<b>Primary EnduraCube Air</b> (2517298C1)..... <b>PA32001</b>	<b>Radial Seal I. Air</b> (3532800-C1)..... <b>RS4637</b>
<b>Fuel</b> (5303743)..... <b>BF63000</b>	<b>Secondary EnduraCube Air</b> (2602211C1)..... <b>PA32004</b>	<b>Cab Air</b> (2506656-C1)..... <b>PA4985</b>
<b>Primary EnduraCube Air</b> (2517298C1)..... <b>PA32001</b>	<b>Cab Air</b> (3839141C1)..... <b>PA5679</b>	<b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b>
<b>Secondary EnduraCube Air</b> (2602211C1)..... <b>PA32004</b>	<b>Air Dryer</b> (Bendix 65624)..... <b>BA5373</b>	<b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b>
<b>Cab Air</b> (3839141C1)..... <b>PA5679</b>	<b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Air Dryer</b> (Bendix 65624)..... <b>BA5373</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b>	4400 w/VT365 (6.0L) Eng.	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	<b>Lube</b> (1840752C91)..... <b>P7235</b>	<b>Steering</b> (2503221-C1)..... <b>BT9388</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	4400 DuraStar w/DT570 (9.3L) Eng.
<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	<b>10 11/32 In. Dual-Flow Lube</b> (1842543-C1)..... <b>BD7252</b>
4400 w/Detroit Diesel Series 50 (8.5L) Eng.	<b>Trans. Spin-on</b> (Fuller 4304827)..... <b>BT223</b>	<b>14 7/32 In. Dual-Flow Lube</b> (1842639-C91)..... <b>BD7250</b>
<b>F-F Lube</b> (23530573)..... <b>[2] B495</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Fuel/Water Separator Ele.</b> (1842638-C91)..... <b>PF7779</b>
<b>P. Fuel</b> (23530706)..... <b>BF5800 +</b>	4400 DuraStar w/DT466 (7.6L) Eng.	<b>Radial Seal O. Air</b> (3532799-C1)..... <b>RS4636 +</b>
<b>S. Fuel</b> (23530707)..... <b>BF5810</b>	<b>F-F Lube</b> (1819452-C1)..... <b>B7030</b>	<b>Radial Seal I. Air</b> (3532800-C1)..... <b>RS4637</b>
<b>Cab. Air</b> (2506656C1)..... <b>PA4985</b>	<b>10 11/32 In. Dual-Flow Lube</b> (1842655-C91)..... <b>BD7252</b>	<b>Cab Air</b> (2506656-C1)..... <b>PA4985</b>
<b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b>	<b>14 7/32 In. Dual-Flow Lube</b> (1842639-C91)..... <b>BD7250</b>	<b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	<b>B-P Lube Spinner</b> (1842825-C91)..... <b>BC7394</b>	<b>Crankcase Breather</b> ..... <b>CLN&amp;R</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	<b>Fuel/Water Separator Ele.</b> (1842638-C92)..... <b>PF7779</b>	<b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
4400 DuraStar w/MaxxForce DT (7.6L) Eng. (To 2012)	4400 DuraStar w/MaxxForce DT (7.6L) Eng. (2012-on) (Cont'd)	4400 w/MaxxForce 10 (9.3L) Eng. (To 2011)
Dual-Flow Lube (1842639-C91).. BD7250	Trans. Spin-on (Allison 29539579)..... BT8460	Dual-Flow Lube (1842639-C91).. BD7250
Fuel/Water Separator (1878042-C92)..... PF7978	Steering (2503221-C1)..... BT9388	Centrifugal Lube (2606467-C91) BC7485 +
Fuel Strainer (1873910-C91)..... PF7994	4400 DuraStar w/MaxxForce 9 (9.3L) Eng. (To 2012)	Fuel/Water Separator (1878042-C91)..... PF7978
Radial Seal O. Air (3532799-C1). RS4636 +	Dual-Flow Lube (1842639-C91).. BD7250	Fuel Strainer (1873910-C91)..... PF7994
Radial Seal I. Air (3532800-C1)... RS4637	Lube (1885920C2)..... B40053	Air Dryer (Bendix 107796)..... BA5377
Cab Air (6 5/32 In. Width) (3839141-C1)..... PA5679	F-F Lube (1884508-C2)..... B7503	Air Dryer (Wabco R950011)..... BA5374 +
Cab Air (7 1/4 In. Width) (2506656-C1)..... PA4985	Fuel/Water Separator (1878042-C92)..... PF7978	Steering (2503221C1)..... BT9388
Air Dryer (AD-9 System) (Bendix 107796)..... BA5377	Fuel/Water Separator (1842638-C92)..... PF7779	4400 w/MaxxForce 10 (9.3L) Eng. (2012-16)
Air Dryer (Wabco R950011)..... BA5374 +	Fuel Strainer (1873910-C91)..... PF7994	Lube (1889124-C91)..... B7503
Trans. Ele. (2 In. Kit) (Allison 29526899)..... PT9416-MPG KIT	Radial Seal O. Air (3532799-C1). RS4636 +	Lube (1885920C2)..... B40053
Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Radial Seal I. Air (3532800-C1)... RS4637	Centrifugal Lube (2606467-C91) BC7485 +
Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004	Primary EnduraCube Air (2602212-C1)..... PA32001	Fuel/Water Separator (1878042-C91)..... PF7978
Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016	Secondary EnduraCube Air (2602211-C1)..... PA32004	Fuel Strainer (1873910-C91)..... PF7994
Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003	Cab Air (6 5/32 In. Width) (3839141-C1)..... PA5679	Radial Seal O. Air (2013-16) (3532799C1)..... RS4636
Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017	Cab Air (7 1/4 In. Width) (2506656-C1)..... PA4985	Radial Seal I. Air (2013-16) (3532800C1)..... RS4637
Trans. Spin-on (Allison 29539579)..... BT8460	Air Dryer (Bendix 107796)..... BA5377	Cab Air (6 5/32 In. Width) (3839141C1)..... PA5679
Steering (2503221-C1)..... BT9388	Air Dryer (Wabco R950011)..... BA5374 +	Cab Air (7 1/4 In. Width) (2506656C1)..... PA4985
4400 DuraStar w/MaxxForce DT (7.6L) Eng. (2012-on)	Trans. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	Trans. Ele. (2 In. Kit) (Allison 29558117)..... PT9416-MPG KIT
Lube (1889124-C91)..... B7503	Trans. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Trans. Ele. (4 In. Kit) (Allison 29558118)..... PT9415-MPG KIT
Fuel/Water Separator (1878042-C92)..... PF7978	Steering (2503221-C1)..... BT9388	Trans. Spin-on (Fuller 4304827).. BT223
Fuel Strainer (1873910-C91)..... PF7994	4400 DuraStar w/MaxxForce 9 (9.3L) Eng. (2012-on)	Opt. Trans. Spin-on (Fuller 17237)..... B2
Primary EnduraCube Air (2602212-C1)..... PA32001	F-F Lube (1884508-C2)..... B7503	4400LP w/Cummins ISL 8.9 (8.9L) Eng. (2019)
Secondary EnduraCube Air (2602211-C1)..... PA32004	Centrifugal Lube (2606467-C92) BC7485 +	Lube (3401544)..... B40142
Cab Air (6 5/32 In. Width) (3839141-C1)..... PA5679	Fuel/Water Separator (1878042-C92)..... PF7978	Fuel/Water Separator (4080114C2)..... BF46169-O
Cab Air (7 1/4 In. Width) (2506656-C1)..... PA4985	Fuel/Water Separator (1842638-C92)..... PF7779	Fuel (5303743)..... BF63000
Air Dryer (AD-9 System) (Bendix 107796)..... BA5377	Fuel Strainer (1873910-C91)..... PF7994	Radial Seal O. Air (3532799C1).. RS4636
Air Dryer (Wabco R950011)..... BA5374 +	Primary EnduraCube Air (2602212-C1)..... PA32001	Radial Seal I. Air (3532800C1)... RS4637
Trans. Ele. (2 In. Kit) (Allison 29526899)..... PT9416-MPG KIT	Secondary EnduraCube Air (2602211-C1)..... PA32004	Cab Air (3839141C1)..... PA5679
Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Cab Air (6 5/32 In. Width) (3839141-C1)..... PA5679	Air Dryer (Bendix 65624)..... BA5373
Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004	Cab Air (7 1/4 In. Width) (2506656-C1)..... PA4985	Air Dryer (Wabco R950011)..... BA5374
Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016	Air Dryer (Bendix 107796)..... BA5377	Trans. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT
Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003	Air Dryer (Wabco R950011)..... BA5374 +	Trans. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT
Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017	Trans. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	Opt. Rear Axle (Meritor 3280V8394)..... B233
	Trans. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	4400LP DuraStar w/DT466 (7.6L) Eng.
	Steering (2503221-C1)..... BT9388	Dual-Flow Lube (1842639-C91).. BD7250
		Fuel/Water Separator (1842638-C92)..... PF7779
		Fuel/Water Separator (1878042-C91)..... PF7978
		Radial Seal O. Air (3532799-C1). RS4636 +
		Radial Seal I. Air (3532800-C1)... RS4637
		Cab Air (2506656-C1)..... PA4985
		Air Dryer (Bendix 107796)..... BA5377
		Trans. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT

+ See Product Guide for Variations of This Number. Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
4400LP DuraStar w/DT466 (7.6L) Eng. (Cont'd) Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Steering (2503221-C1)..... <b>BT9388</b>	4400LP w/N9 (9.3L) Eng. (2018) Lube (1884508C2)..... <b>B7503</b> Fuel/Water Separator (1878042C93)..... <b>PF7978</b> Primary EnduraCube Air (2602212C1)..... <b>PA32001</b> Secondary EnduraCube Air (2602211C1)..... <b>PA32004</b> Cab Air (3839141C1)..... <b>PA5679</b> Air Dryer (Wabco R950011)..... <b>BA5374 +</b> Trans. (2 In. Kit) (Allison 29558328)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29558329)..... <b>PT9415-MPG KIT</b>	4700 w/Cat 3406 (14.6L) Eng. (Cont'd) Fuel Spin-on (High Efficiency Vers.)..... <b>BF7587 +</b>
4400LP w/DT530 (8.7L) Eng. F-F Lube (1819452-C1)..... <b>B7030</b> Dual-Flow Lube (1842639-C91).. <b>BD7250</b> Fuel (1809789-C1)..... <b>BF7629 +</b> Coolant (1822313-C1)..... <b>BW5082</b>	4600 Series w/T444E (7.3L) Eng. Lube (1814562-C1)..... <b>B7039</b> Fuel/Water Separator Box-Style (548348-C1)..... <b>BF912</b> Air (476741-C1)..... <b>PA2521</b> Cab Air (1696834-C1)..... <b>PA5691</b> Coolant (w/Chemical) (Fleetguard WF2071)..... <b>BW5071</b> Coolant (w/o Chemical) (1825314-C1)..... <b>B5089 +</b> Trans. (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> Trans. (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> Trans. Spin-on (Allison 29510922)..... <b>BT8316-MPG</b> Trans. Spin-on (596606-C1)..... <b>BT839-10</b> Steering (1695528-C1)..... <b>PT9419-MPG</b>	4700 w/Cummins L10 (10.0L) Eng. Dual-Flow Lube (3318853)..... <b>BD103 +</b> F-F Lube (Standard Vers.) (Fleetguard LF670SC)..... <b>B196 +</b> F-F Lube (Ext. Life) (Fleetguard LF670SC)..... <b>B96 +</b> B-P Lube (3304232)..... <b>B7577</b> Fuel/Water Separator (154789)... <b>BF957-D +</b> Coolant (w/4 Units BTA+) (3315116)..... <b>BW5071</b> Coolant (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b>
4400LP DuraStar w/DT570 (9.3L) Eng. Dual-Flow Lube (1842639-C91).. <b>BD7250</b> Fuel/Water Separator Ele. (1842638-C91)..... <b>PF7779</b> Radial Seal O. Air (3532799-C1). <b>RS4636 +</b> Radial Seal I. Air (3532800-C1)... <b>RS4637</b> Cab Air (2506656-C1)..... <b>PA4985</b> Air Dryer (Bendix 107796)..... <b>BA5377</b> Crankcase Breather..... <b>CLN&amp;R</b> Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Steering (2503221-C1)..... <b>BT9388</b>	4600 w/v8-444 (7.3L) Turbo Diesel Eng. Lube (1804442C1)..... <b>B134</b> Fuel/Water Separator (w/Drain) (Ford E8TZ9N184A)..... <b>BF1222 +</b> Fuel/Water Separator (w/Sensor Port) (Ford E8TZ9N184A)..... <b>BF1222-SP +</b> Fuel/Water Separator (Open End for Bowl) (Ford E8TZ9N184A)..... <b>BF1222-O +</b>	4700 w/Cummins N14 (14.0L) Eng. Dual-Flow Lube (3318853)..... <b>BD103 +</b> F-F Lube (Standard Vers.) (Fleetguard LF670SC)..... <b>B196 +</b> F-F Lube (Ext. Life) (Fleetguard LF670SC)..... <b>B96 +</b> B-P Lube (3304232)..... <b>B7577</b> Fuel/Water Separator (3308638). <b>BF1212 +</b> Fuel (154789)..... <b>BF957-D +</b> Coolant (w/4 Units BTA+) (3315116)..... <b>BW5071</b>
4400LP w/MaxxForce DT (7.6L) Eng. (To 2012) Dual-Flow Lube (1842639C91)... <b>BD7250</b> Fuel/Water Separator Ele. (1878042C92)..... <b>PF7978</b> Fuel/Water Separator Ele. (1822638C91)..... <b>PF7779</b> Fuel Strainer (1873910C91)..... <b>PF7994</b> Fuel Kit (1876533C93)..... <b>BF9858 KIT</b> Radial Seal O. Air (3532799C1).. <b>RS4636 +</b> Radial Seal I. Air (3532800C1).... <b>RS4637</b> Cab Air (2506656C1)..... <b>PA4985</b> Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b> Trans. Ele. (2 In. Kit) (Allison 29526899)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Steering (2503221C1)..... <b>BT9388</b>	4600 w/Cummins N14 (14.0L) Eng. Dual-Flow Lube (3318853)..... <b>BD103 +</b> F-F Lube (Standard Vers.) (Fleetguard LF670SC)..... <b>B196 +</b> F-F Lube (Ext. Life) (Fleetguard LF670SC)..... <b>B96 +</b> B-P Lube (3304232)..... <b>B7577</b> Fuel/Water Separator (3308638). <b>BF1212 +</b> Fuel (154789)..... <b>BF957-D +</b> Coolant (w/4 Units BTA+) (3315116)..... <b>BW5071</b>	4700 w/Detroit Diesel Series 50 (8.5L) Eng. Lube (23530573)..... <b>[2] B495</b> Fuel/Water Separator Spin-on (w/Drain) (23535985)..... <b>BF5813 +</b> Fuel/Water Separator Spin-on (Open End for Bowl) (23535985).. <b>BF5813-O +</b> P. Fuel (23530706)..... <b>BF5800 +</b> S. Fuel (23530707)..... <b>BF5810</b>
4400LP w/MaxxForce DT (7.6L) Eng. (2012-on) Lube (1889124C91)..... <b>B7503</b> Fuel/Water Separator Ele. (1878042C92)..... <b>PF7978</b> Fuel/Water Separator Ele. (1822638C91)..... <b>PF7779</b> Fuel Strainer (1873910C91)..... <b>PF7994</b> Fuel Kit (1876533C93)..... <b>BF9858 KIT</b> Radial Seal O. Air (3532799C1).. <b>RS4636 +</b> Radial Seal I. Air (3532800C1).... <b>RS4637</b> Cab Air (2506656C1)..... <b>PA4985</b> Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b> Trans. Ele. (2 In. Kit) (Allison 29526899)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Steering (2503221C1)..... <b>BT9388</b>	4700 Series w/Detroit Diesel Series 60 (11.1L) Eng. Lube (23530573)..... <b>[2] B495</b> Fuel/Water Separator Ele. (23533816)..... <b>PF7748</b> Fuel/Water Separator Spin-on (w/Drain) (23535985)..... <b>BF5813 +</b> Fuel/Water Separator Spin-on (Open End for Bowl) (23535985).. <b>BF5813-O +</b> P. Fuel (23530706)..... <b>BF5800 +</b> S. Fuel (23530707)..... <b>BF5810</b>	4700 Series w/Detroit Diesel Series 60 (12.7L) Eng. Lube (23530573)..... <b>[2] B495</b> Fuel/Water Separator Ele. (23533816)..... <b>PF7748</b> Fuel/Water Separator Spin-on (w/Drain) (23535985)..... <b>BF5813 +</b> Fuel/Water Separator Spin-on (Open End for Bowl) (23535985).. <b>BF5813-O +</b> P. Fuel (23530706)..... <b>BF5800 +</b> S. Fuel (23530707)..... <b>BF5810</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
4700 Series w/DT360 (5.9L) Eng. <b>Lube</b> (1811953-C1)..... <b>B309</b> <b>5 7/16 In. Fuel/Water Separator</b> (Fleetguard FF105D)..... <b>BF957-D +</b> <b>5 11/16 In. Fuel/Water Separator</b> (702255-C1)..... <b>BF891</b> <b>Fuel</b> (1809789-C1)..... <b>BF7629 +</b> <b>O. Air</b> (476741-C1)..... <b>PA2521</b> <b>I. Air</b> (Fleetguard AF987)..... <b>PA2522</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (w/6 Units BTA+) (Fleetguard WF2072)..... <b>BW5072</b> <b>Coolant</b> (w/8 Units BTA+) (Fleetguard WF2073)..... <b>BW5073</b> <b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b> <b>Coolant</b> (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b> <b>Trans. Spin-on</b> (595722-C91)..... <b>BT839-10</b> <b>3 31/32 In. Steering</b> (Fleetguard HF6162)..... <b>P106-HD</b> <b>4 5/32 In. Steering</b> (1681202-C91)..... <b>PT8407</b>	4700 Series w/DTA360 (5.9L) Eng. (Cont'd) <b>4 5/32 In. Steering</b> (1681202-C91)..... <b>PT8407</b> <hr/> 4700 Series w/DT408 (6.7L) Eng. <b>Lube</b> (1819452-C1)..... <b>B7030</b> <b>P. Fuel</b> (1809789-C1)..... <b>BF7629 +</b> <b>S. Fuel</b> (Fleetguard FF5052)..... <b>BF788</b> <b>O. Air</b> (476741-C1)..... <b>PA2521</b> <b>Opt. I. Air</b> (Fleetguard AF987)..... <b>PA2522</b> <b>Coolant</b> (w/o Chemical) (Fleetguard WF2101)..... <b>B5134 +</b> <b>Coolant</b> (w/4 Units BTA+) (1822313-C1)..... <b>BW5082</b> <b>Coolant</b> (w/12 Units BTA+) (1820361-C1)..... <b>BW5074</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b> <b>3 31/32 In. Steering</b> (Fleetguard HF6162)..... <b>P106-HD</b> <b>4 5/32 In. Steering</b> (1681202-C91)..... <b>PT8407</b> <hr/> 4700 Series w/T444E (7.3L) Eng. <b>Lube</b> (1814562-C1)..... <b>B7039</b> <b>Fuel/Water Separator</b> (1618386-C92)..... <b>BF1345-O</b> <b>Fuel Ele.</b> ..... <b>PF7678</b> <b>O. Air</b> (476741-C1)..... <b>PA2521</b> <b>I. Air</b> (482644-C1)..... <b>PA2522</b> <b>Radial Seal Air</b> (1691027-C1)..... <b>RS2863</b> <b>Radial Seal XP Air</b> (1691027-C1)..... <b>RS2863XP</b> <b>Cab Air</b> (7 1/4 In. Length) (2506656C1)..... <b>PA4985</b> <b>Cab Air</b> (11 13/16 In. Length) (1696834-C1)..... <b>PA5691</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Ele.</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b>	4700 Series w/T444E (7.3L) Eng. (Cont'd) <b>Trans. Ele.</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b> <b>3 31/32 In. Steering</b> (1691121-C1)..... <b>P106-HD</b> <b>4 5/32 In. Steering</b> (1681202-C91)..... <b>PT8407</b> <b>Steering</b> (1695528-C1)..... <b>PT9419-MPG</b> <hr/> 4700 Series w/DT466 (7.6L) Eng. (To 1994) <b>F-F Lube</b> (1811953-C1)..... <b>B309</b> <b>Dual-Flow Lube</b> (1841606-C1)..... <b>BD7250</b> <b>Fuel/Water Separator</b> (1618385-C91)..... <b>BF1345-O</b> <b>P. Fuel</b> ..... <b>BF979 +</b> <b>S. Fuel</b> (672603-C3)..... <b>BF588</b> <b>Single Fuel</b> (1809789-C1)..... <b>BF7629 +</b> <b>Fuel</b> (Fleetguard FF5052)..... <b>BF788</b> <b>O. Air</b> (476741-C1)..... <b>PA2521</b> <b>I. Air</b> (482644-C1)..... <b>PA2522</b> <b>Cab Air</b> (1696834-C1)..... <b>PA5691</b> <b>Coolant</b> (w/o Chemical) (Fleetguard WF2101)..... <b>B5134 +</b> <b>Coolant</b> (w/4 Units BTA+) (1822313-C1)..... <b>BW5082</b> <b>Coolant</b> (w/12 Units BTA+) (1820361-C1)..... <b>BW5074</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b> <b>Trans. Spin-on</b> (596606-C1)..... <b>BT839-10</b> <b>3 31/32 In. Steering</b> (1691121-C1)..... <b>P106-HD</b> <b>4 5/32 In. Steering</b> (1681202-C91)..... <b>PT8407</b> <hr/> 4700 Series w/DT466 (7.6L) Eng. (1994-on) <b>F-F Lube</b> (1819452-C1)..... <b>B7030</b> <b>Dual-Flow Lube</b> (1841606-C1)..... <b>BD7250</b> <b>Fuel/Water Separator</b> (1618385-C91)..... <b>BF1345-O</b> <b>P. Fuel</b> ..... <b>BF979 +</b> <b>S. Fuel</b> (672603-C3)..... <b>BF588</b> <b>Single Fuel</b> (1809789-C1)..... <b>BF7629 +</b> <b>Fuel</b> (Fleetguard FF5052)..... <b>BF788</b> <b>O. Air</b> (476741-C1)..... <b>PA2521</b> <b>I. Air</b> (482644-C1)..... <b>PA2522</b> <b>Cab Air</b> (1696834-C1)..... <b>PA5691</b> <b>Coolant</b> (w/o Chemical) (Fleetguard WF2101)..... <b>B5134 +</b> <b>Coolant</b> (w/4 Units BTA+) (1822313-C1)..... <b>BW5082</b> <b>Coolant</b> (w/12 Units BTA+) (1820361-C1)..... <b>BW5074</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
4700 Series w/DT466 (7.6L) Eng. (1994-on) (Cont'd) <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b> <b>Trans. Spin-on</b> (596606-C1)..... <b>BT839-10</b> <b>3 31/32 In. Steering</b> (1691121-C1)..... <b>P106-HD</b> <b>4 5/32 In. Steering</b> (1681202-C91)..... <b>PT8407</b>	4700 Series w/DT466C (7.6L) Eng. (1994-on) (Cont'd) <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b> <b>Trans. Spin-on</b> (596606-C1)..... <b>BT839-10</b> <b>3 31/32 In. Steering</b> (1691121-C1)..... <b>P106-HD</b> <b>4 5/32 In. Steering</b> (1681202-C91)..... <b>PT8407</b>	4700 Series w/DTA466 (7.6L) Eng. (1994-on) (Cont'd) <b>Coolant</b> (w/12 Units BTA+) (1820361-C1)..... <b>BW5074</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b> <b>Trans. Spin-on</b> (596606-C1)..... <b>BT839-10</b> <b>3 31/32 In. Steering</b> (1691121-C1)..... <b>P106-HD</b> <b>4 5/32 In. Steering</b> (1681202-C91)..... <b>PT8407</b>
4700 Series w/DT466C (7.6L) Eng. (To 1994) <b>F-F Lube</b> (1811953-C1)..... <b>B309</b> <b>Dual-Flow Lube</b> (1841606-C1).... <b>BD7250</b> <b>Fuel/Water Separator</b> (1618385-C91)..... <b>BF1345-O</b> <b>P. Fuel</b> ..... <b>BF979 +</b> <b>S. Fuel</b> (672603-C3)..... <b>BF588</b> <b>Single Fuel</b> (1809789-C1)..... <b>BF7629 +</b> <b>Fuel</b> (Fleetguard FF5052)..... <b>BF788</b> <b>O. Air</b> (476741-C1)..... <b>PA2521</b> <b>I. Air</b> (482644-C1)..... <b>PA2522</b> <b>Cab Air</b> (1696834-C1)..... <b>PA5691</b> <b>Coolant</b> (w/o Chemical) (Fleetguard WF2101)..... <b>B5134 +</b> <b>Coolant</b> (w/4 Units BTA+) (1822313-C1)..... <b>BW5082</b> <b>Coolant</b> (w/12 Units BTA+) (1820361-C1)..... <b>BW5074</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b> <b>Trans. Spin-on</b> (596606-C1)..... <b>BT839-10</b> <b>3 31/32 In. Steering</b> (1691121-C1)..... <b>P106-HD</b> <b>4 5/32 In. Steering</b> (1681202-C91)..... <b>PT8407</b>	4700 Series w/DTA466 (7.6L) Eng. (To 1994) <b>F-F Lube</b> (1811953-C1)..... <b>B309</b> <b>Dual-Flow Lube</b> (1841606-C1).... <b>BD7250</b> <b>Fuel/Water Separator</b> (1618385-C91)..... <b>BF1345-O</b> <b>P. Fuel</b> ..... <b>BF979 +</b> <b>S. Fuel</b> (672603-C3)..... <b>BF588</b> <b>Single Fuel</b> (1809789-C1)..... <b>BF7629 +</b> <b>Fuel</b> (Fleetguard FF5052)..... <b>BF788</b> <b>O. Air</b> (476741-C1)..... <b>PA2521</b> <b>I. Air</b> (482644-C1)..... <b>PA2522</b> <b>Cab Air</b> (1696834-C1)..... <b>PA5691</b> <b>Coolant</b> (w/o Chemical) (Fleetguard WF2101)..... <b>B5134 +</b> <b>Coolant</b> (w/4 Units BTA+) (1822313-C1)..... <b>BW5082</b> <b>Coolant</b> (w/12 Units BTA+) (1820361-C1)..... <b>BW5074</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b> <b>Trans. Spin-on</b> (596606-C1)..... <b>BT839-10</b> <b>3 31/32 In. Steering</b> (1691121-C1)..... <b>P106-HD</b> <b>4 5/32 In. Steering</b> (1681202-C91)..... <b>PT8407</b>	4700 Series w/DTA466C (7.6L) Eng. (To 1994) <b>F-F Lube</b> (1811953-C1)..... <b>B309</b> <b>Dual-Flow Lube</b> (1841606-C1).... <b>BD7250</b> <b>Fuel/Water Separator</b> (1618385-C91)..... <b>BF1345-O</b> <b>P. Fuel</b> ..... <b>BF979 +</b> <b>S. Fuel</b> (672603-C3)..... <b>BF588</b> <b>Single Fuel</b> (1809789-C1)..... <b>BF7629 +</b> <b>Fuel</b> (Fleetguard FF5052)..... <b>BF788</b> <b>O. Air</b> (476741-C1)..... <b>PA2521</b> <b>I. Air</b> (482644-C1)..... <b>PA2522</b> <b>Cab Air</b> (1696834-C1)..... <b>PA5691</b> <b>Coolant</b> (w/o Chemical) (Fleetguard WF2101)..... <b>B5134 +</b> <b>Coolant</b> (w/4 Units BTA+) (1822313-C1)..... <b>BW5082</b> <b>Coolant</b> (w/12 Units BTA+) (1820361-C1)..... <b>BW5074</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b> <b>Trans. Spin-on</b> (596606-C1)..... <b>BT839-10</b> <b>3 31/32 In. Steering</b> (1691121-C1)..... <b>P106-HD</b> <b>4 5/32 In. Steering</b> (1681202-C91)..... <b>PT8407</b>
4700 Series w/DT466C (7.6L) Eng. (1994-on) <b>F-F Lube</b> (1819452-C1)..... <b>B7030</b> <b>Dual-Flow Lube</b> (1841606-C1).... <b>BD7250</b> <b>Fuel/Water Separator</b> (1618385-C91)..... <b>BF1345-O</b> <b>P. Fuel</b> ..... <b>BF979 +</b> <b>S. Fuel</b> (672603-C3)..... <b>BF588</b> <b>Single Fuel</b> (1809789-C1)..... <b>BF7629 +</b> <b>Fuel</b> (Fleetguard FF5052)..... <b>BF788</b> <b>O. Air</b> (476741-C1)..... <b>PA2521</b> <b>I. Air</b> (482644-C1)..... <b>PA2522</b> <b>Cab Air</b> (1696834-C1)..... <b>PA5691</b> <b>Coolant</b> (w/o Chemical) (Fleetguard WF2101)..... <b>B5134 +</b> <b>Coolant</b> (w/4 Units BTA+) (1822313-C1)..... <b>BW5082</b> <b>Coolant</b> (w/12 Units BTA+) (1820361-C1)..... <b>BW5074</b>	4700 Series w/DTA466 (7.6L) Eng. (1994-on) <b>F-F Lube</b> (1819452-C1)..... <b>B7030</b> <b>Dual-Flow Lube</b> (1841606-C1).... <b>BD7250</b> <b>Fuel/Water Separator</b> (1618385-C91)..... <b>BF1345-O</b> <b>P. Fuel</b> ..... <b>BF979 +</b> <b>S. Fuel</b> (672603-C3)..... <b>BF588</b> <b>Single Fuel</b> (1809789-C1)..... <b>BF7629 +</b> <b>Fuel</b> (Fleetguard FF5052)..... <b>BF788</b> <b>O. Air</b> (476741-C1)..... <b>PA2521</b> <b>I. Air</b> (482644-C1)..... <b>PA2522</b> <b>Cab Air</b> (1696834-C1)..... <b>PA5691</b> <b>Coolant</b> (w/o Chemical) (Fleetguard WF2101)..... <b>B5134 +</b> <b>Coolant</b> (w/4 Units BTA+) (1822313-C1)..... <b>BW5082</b>	4700 Series w/DTA466C (7.6L) Eng. (1994-on) <b>F-F Lube</b> (1819452-C1)..... <b>B7030</b> <b>Dual-Flow Lube</b> (1841606-C1).... <b>BD7250</b> <b>Fuel/Water Separator</b> (1618385-C91)..... <b>BF1345-O</b> <b>P. Fuel</b> ..... <b>BF979 +</b> <b>S. Fuel</b> (672603-C3)..... <b>BF588</b> <b>Single Fuel</b> (1809789-C1)..... <b>BF7629 +</b> <b>Fuel</b> (Fleetguard FF5052)..... <b>BF788</b> <b>O. Air</b> (476741-C1)..... <b>PA2521</b> <b>I. Air</b> (482644-C1)..... <b>PA2522</b> <b>Cab Air</b> (1696834-C1)..... <b>PA5691</b> <b>Coolant</b> (w/o Chemical) (Fleetguard WF2101)..... <b>B5134 +</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
4700 Series w/DTA466C (7.6L) Eng. (1994-on) (Cont'd)	4800 w/DT408 (6.7L) Eng. (Cont'd)	4800 w/DT466C (7.6L) Eng. (Cont'd)
<b>Coolant</b> (w/4 Units BTA+) (1822313-C1)..... <b>BW5082</b>	<b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b>	<b>Coolant</b> (w/o Chemical) (Fleetguard WF2101)..... <b>B5134 +</b>
<b>Coolant</b> (w/12 Units BTA+) (1820361-C1)..... <b>BW5074</b>	<b>Steering</b> (1691121C1)..... <b>P106-HD</b>	<b>Coolant</b> (w/4 Units BTA+) (1822313-C1)..... <b>BW5082</b>
<b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b>	4800 w/DT466 (7.6L) Eng.	<b>Coolant</b> (w/6 Units BTA+) (Fleetguard WF2072)..... <b>BW5072</b>
<b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>	<b>Lube</b> (1819452-C1)..... <b>B7030</b>	<b>Coolant</b> (w/8 Units BTA+) (Fleetguard WF2073)..... <b>BW5073</b>
<b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b>	<b>Fuel/Water Separator</b> (Fleetguard FF105D)..... <b>BF957-D +</b>	<b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b>
<b>Trans. Spin-on</b> (596606-C1)..... <b>BT839-10</b>	<b>Fuel/Water Separator</b> (1677004-C91)..... <b>BF1345-O</b>	<b>Coolant</b> (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b>
<b>3 31/32 In. Steering</b> (1691121-C1)..... <b>P106-HD</b>	<b>Fuel/Water Separator</b> (702255C1)..... <b>BF891</b>	<b>Trans. Pan-Type</b> (Allison 29538489)..... <b>19739 +</b>
<b>4 5/32 In. Steering</b> (1681202-C91)..... <b>PT8407</b>	<b>Fuel Spin-on</b> (1822588-C1)..... <b>BF7629 +</b>	<b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b>
4700 Series w/DT530 (8.7L) Eng.	<b>O. Air</b> (476741-C1)..... <b>PA2521</b>	<b>3 31/32 In. Steering</b> (1691121-C1)..... <b>P106-HD</b>
<b>Lube</b> (1819452-C1)..... <b>B7030</b>	<b>I. Air</b> (482644-C1)..... <b>PA2522</b>	<b>4 5/32 In. Steering</b> (1681202-C91)..... <b>PT8407</b>
<b>Fuel/Water Separator</b> (702255-C1)..... <b>BF891</b>	<b>Radial Seal Air</b> (1691027-C1)..... <b>RS2863</b>	4800 w/DTA360 (5.9L) Eng.
<b>Fuel</b> (Fleetguard FF5052)..... <b>BF788</b>	<b>Radial Seal XP Air</b> (1691027-C1)..... <b>RS2863XP</b>	<b>Lube</b> (1811953-C1)..... <b>[2] B309</b>
<b>O. Air</b> (476741-C1)..... <b>PA2521</b>	<b>Cab Air</b> (1696834-C1)..... <b>PA5691</b>	<b>5 7/16 In. Fuel/Water Separator</b> (Fleetguard FF105D)..... <b>BF957-D +</b>
<b>I. Air</b> (Fleetguard AF987)..... <b>PA2522</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>5 11/16 In. Fuel/Water Separator</b> (702255-C1)..... <b>BF891</b>
<b>Coolant</b> (w/4 Units BTA+) (1822313-C1)..... <b>BW5082</b>	<b>Coolant</b> (w/o Chemical) (Fleetguard WF2101)..... <b>B5134 +</b>	<b>8 17/32 In. Fuel/Water Separator</b> (1808623-C1)..... <b>BF7584 +</b>
<b>Coolant</b> (w/6 Units BTA+) (Fleetguard WF2072)..... <b>BW5072</b>	<b>Coolant</b> (w/4 Units BTA+) (1822313-C1)..... <b>BW5082</b>	<b>Fuel</b> (1822588-C1)..... <b>BF7629 +</b>
<b>Coolant</b> (w/8 Units BTA+) (Fleetguard WF2073)..... <b>BW5073</b>	<b>Coolant</b> (w/6 Units BTA+) (Fleetguard WF2072)..... <b>BW5072</b>	<b>O. Air</b> (476741-C1)..... <b>PA2521</b>
<b>Coolant</b> (w/12 Units BTA+) (1820361-C1)..... <b>BW5074</b>	<b>Coolant</b> (w/8 Units BTA+) (Fleetguard WF2073)..... <b>BW5073</b>	<b>I. Air</b> (Fleetguard AF987)..... <b>PA2522</b>
<b>Coolant</b> (w/o Chemical) (Fleetguard WF2101)..... <b>B5134 +</b>	<b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Coolant</b> (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b>	<b>Coolant</b> (w/6 Units BTA+) (Fleetguard WF2072)..... <b>BW5072</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Trans. Pan-Type</b> (Allison 29538489)..... <b>19739 +</b>	<b>Coolant</b> (w/8 Units BTA+) (Fleetguard WF2073)..... <b>BW5073</b>
<b>3 31/32 In. Steering</b> (Fleetguard HF6162)..... <b>P106-HD</b>	<b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b>	<b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b>
<b>4 5/32 In. Steering</b> (1681202-C91)..... <b>PT8407</b>	<b>3 31/32 In. Steering</b> (1691121-C1)..... <b>P106-HD</b>	<b>Coolant</b> (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b>
4800 w/Detroit Diesel Series 50 (8.5L) Eng.	<b>4 5/32 In. Steering</b> (1681202-C91)..... <b>PT8407</b>	<b>Trans. Ele.</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b>
<b>Lube</b> (23530573)..... <b>[2] B495</b>	4800 w/DT466C (7.6L) Eng.	<b>Trans. Ele.</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>
<b>Fuel/Water Separator Spin-on</b> (w/Drain) (23535985)..... <b>BF5813 +</b>	<b>Lube</b> (1819452-C1)..... <b>B7030</b>	<b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b>
<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (23535985)..... <b>BF5813-O +</b>	<b>Fuel/Water Separator</b> (Fleetguard FF105D)..... <b>BF957-D +</b>	<b>Trans. Spin-on</b> (595722-C91)..... <b>BT839-10</b>
<b>P. Fuel</b> (23530706)..... <b>BF5800 +</b>	<b>Fuel/Water Separator</b> (1677004-C91)..... <b>BF1345-O</b>	<b>3 31/32 In. Steering</b> (Fleetguard HF6162)..... <b>P106-HD</b>
<b>S. Fuel</b> (23530707)..... <b>BF5810</b>	<b>Fuel/Water Separator</b> (702255C1)..... <b>BF891</b>	<b>4 5/32 In. Steering</b> (1681202-C91)..... <b>PT8407</b>
4800 w/DT408 (6.7L) Eng.	<b>Fuel Spin-on</b> (1822588-C1)..... <b>BF7629 +</b>	4800 w/DTA466 (7.6L) Eng.
<b>Lube</b> (1819452C1)..... <b>B7030</b>	<b>O. Air</b> (476741-C1)..... <b>PA2521</b>	<b>Lube</b> (1819452-C1)..... <b>B7030</b>
<b>Fuel/Water Separator</b> (1677004C91)..... <b>BF1345-O</b>	<b>I. Air</b> (482644-C1)..... <b>PA2522</b>	<b>Fuel/Water Separator</b> (Fleetguard FF105D)..... <b>BF957-D +</b>
<b>Fuel</b> (1822588C1)..... <b>BF7629 +</b>	<b>Radial Seal Air</b> (1691027-C1)..... <b>RS2863</b>	<b>Fuel/Water Separator</b> (1677004-C91)..... <b>BF1345-O</b>
<b>O. Air</b> (476741C1)..... <b>PA2521</b>	<b>Radial Seal XP Air</b> (1691027-C1)..... <b>RS2863XP</b>	
<b>I. Air</b> (482644C1)..... <b>PA2522</b>	<b>Cab Air</b> (1696834-C1)..... <b>PA5691</b>	
<b>Coolant</b> (1822313C1)..... <b>BW5082</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	
<b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b>		
<b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>		


+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

**Trucks & Buses Applications** **BALDWIN FILTERS**

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
4800 w/DTA466 (7.6L) Eng. (Cont'd)	4800 w/DTA466C (7.6L) Eng. (Cont'd)	4900 w/Cat C12 (12.0L) Eng. (Cont'd)
<b>Fuel/Water Separator</b> (702255C1)..... <b>BF891</b>	<b>Coolant</b> (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b>	<b>Fuel Spin-on</b> (Standard Vers.) (4N5823)..... <b>BF614 +</b>
<b>Fuel Spin-on</b> (1822588-C1)..... <b>BF7629 +</b>	<b>Trans. Pan-Type</b> (Allison 29538489)..... <b>19739 +</b>	<b>Fuel Spin-on</b> (High Efficiency Vers.)..... <b>BF7587 +</b>
<b>O. Air</b> (476741-C1)..... <b>PA2521</b>	<b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b>	4900 w/Cummins L10 (10.0L) Eng.
<b>I. Air</b> (482644-C1)..... <b>PA2522</b>	<b>3 31/32 In. Steering</b> (1691121-C1)..... <b>P106-HD</b>	<b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b>
<b>Radial Seal Air</b> (1691027-C1)..... <b>RS2863</b>	<b>4 5/32 In. Steering</b> (1681202-C91)..... <b>PT8407</b>	<b>F-F Lube</b> (Standard Vers.) (Fleetguard LF670SC)..... <b>B196 +</b>
<b>Radial Seal XP Air</b> (1691027-C1)..... <b>RS2863XP</b>	4800 w/DT530 (8.7L) Eng.	<b>F-F Lube</b> (Ext. Life) (Fleetguard LF670SC)..... <b>B96 +</b>
<b>Cab Air</b> (1696834-C1)..... <b>PA5691</b>	<b>Lube</b> (1819452-C1)..... <b>B7030</b>	<b>B-P Lube</b> (3304232)..... <b>B7577</b>
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Fuel/Water Separator</b> (1677004-C91)..... <b>BF1345-O</b>	<b>Fuel/Water Separator</b> (154789)... <b>BF957-D +</b>
<b>Coolant</b> (w/o Chemical) (Fleetguard WF2101)..... <b>B5134 +</b>	<b>Fuel/Water Separator</b> (702255C1)..... <b>BF891</b>	<b>Coolant</b> (w/4 Units BTA+) (3315116)..... <b>BW5071</b>
<b>Coolant</b> (w/4 Units BTA+) (1822313-C1)..... <b>BW5082</b>	<b>Fuel</b> (1822529-C1)..... <b>BF788</b>	<b>Coolant</b> (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b>
<b>Coolant</b> (w/6 Units BTA+) (Fleetguard WF2072)..... <b>BW5072</b>	<b>O. Air</b> (1661756-C91)..... <b>PA2521</b>	4900 w/Cummins N14 (14.0L) Eng.
<b>Coolant</b> (w/8 Units BTA+) (Fleetguard WF2073)..... <b>BW5073</b>	<b>Opt. I. Air</b> (1661756-C91)..... <b>PA2522</b>	<b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b>
<b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>F-F Lube</b> (Standard Vers.) (Fleetguard LF670SC)..... <b>B196 +</b>
<b>Coolant</b> (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b>	<b>Coolant</b> (w/o Chemical) (Fleetguard WF2101)..... <b>B5134 +</b>	<b>F-F Lube</b> (Ext. Life) (Fleetguard LF670SC)..... <b>B96 +</b>
<b>Trans. Pan-Type</b> (Allison 29538489)..... <b>19739 +</b>	<b>Coolant</b> (w/4 Units BTA+) (1822313-C1)..... <b>BW5082</b>	<b>B-P Lube</b> (3304232)..... <b>B7577</b>
<b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b>	<b>Coolant</b> (w/12 Units BTA+) (1820361-C1)..... <b>BW5074</b>	<b>Fuel/Water Separator</b> (3308638). <b>BF1212 +</b>
<b>3 31/32 In. Steering</b> (1691121-C1)..... <b>P106-HD</b>	<b>3 31/32 In. Steering</b> (Fleetguard HF6162)..... <b>P106-HD</b>	<b>Fuel</b> (154789)..... <b>BF957-D +</b>
<b>4 5/32 In. Steering</b> (1681202-C91)..... <b>PT8407</b>	<b>4 5/32 In. Steering</b> (1681202-C91)..... <b>PT8407</b>	<b>Coolant</b> (w/4 Units BTA+) (3315116)..... <b>BW5071</b>
4800 w/DTA466C (7.6L) Eng.	4800 w/T444E (7.3L) Eng.	4900 w/Detroit Diesel Series 50 (8.5L) Eng.
<b>Lube</b> (1819452-C1)..... <b>B7030</b>	<b>Lube</b> (1814562C1)..... <b>B7039</b>	<b>Lube</b> (23530573)..... <b>[2] B495</b>
<b>Fuel/Water Separator</b> (Fleetguard FF105D)..... <b>BF957-D +</b>	<b>3 9/16 In. Fuel</b> (1825864C92)..... <b>PF7698</b>	<b>Fuel/Water Separator Spin-on</b> (w/Drain) (23535985)..... <b>BF5813 +</b>
<b>Fuel/Water Separator</b> (1677004-C91)..... <b>BF1345-O</b>	<b>4 17/32 In. Fuel</b> (1822631C91)..... <b>PF7678</b>	<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (23535985).. <b>BF5813-O +</b>
<b>Fuel/Water Separator</b> (702255C1)..... <b>BF891</b>	<b>Radial Seal Air</b> (1691027C1)..... <b>RS2863</b>	<b>P. Fuel</b> (23530706)..... <b>BF5800 +</b>
<b>Fuel Spin-on</b> (1822588-C1)..... <b>BF7629 +</b>	<b>Radial Seal XP Air</b> (1691027C1). <b>RS2863XP</b>	<b>S. Fuel</b> (23530707)..... <b>BF5810</b>
<b>O. Air</b> (476741-C1)..... <b>PA2521</b>	<b>O. Air</b> (476741C1)..... <b>PA2521</b>	4900 Series w/Detroit Diesel Series 60 Eng.
<b>I. Air</b> (482644-C1)..... <b>PA2522</b>	<b>I. Air</b> (482644C1)..... <b>PA2522</b>	<b>Lube</b> ..... <b>[2] B495</b>
<b>Radial Seal Air</b> (1691027-C1)..... <b>RS2863</b>	<b>Coolant</b> (1822627C1)..... <b>BW5071</b>	<b>Fuel/Water Separator Ele.</b> (23533816)..... <b>PF7748</b>
<b>Radial Seal XP Air</b> (1691027-C1)..... <b>RS2863XP</b>	<b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b>	<b>Fuel/Water Separator Spin-on</b> (w/Drain) (23535985)..... <b>BF5813 +</b>
<b>Cab Air</b> (1696834-C1)..... <b>PA5691</b>	<b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>	<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (23535985).. <b>BF5813-O +</b>
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b>	<b>P. Fuel</b> ..... <b>BF5800 +</b>
<b>Coolant</b> (w/o Chemical) (Fleetguard WF2101)..... <b>B5134 +</b>	<b>Steering</b> (1691121C1)..... <b>P106-HD</b>	<b>S. Fuel</b> ..... <b>BF5810</b>
<b>Coolant</b> (w/4 Units BTA+) (1822313-C1)..... <b>BW5082</b>	4900 Series w/Cat 3406 (14.6L) Eng.	<b>Air</b> (w/Lid) (Don. P153551)..... <b>PA2705</b>
<b>Coolant</b> (w/6 Units BTA+) (Fleetguard WF2072)..... <b>BW5072</b>	<b>Lube</b> ..... <b>B99 +</b>	<b>Steering</b> (1681202-C91)..... <b>PT8407</b>
<b>Coolant</b> (w/8 Units BTA+) (Fleetguard WF2073)..... <b>BW5073</b>	<b>Fuel Spin-on</b> ..... <b>BF614 +</b>	4900 Series w/V8 7.3L Eng.
<b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b>	<b>Coolant</b> ..... <b>BW5137</b>	<b>Lube</b> (1804442C1)..... <b>B134</b>
	4900 w/Cat C12 (12.0L) Eng.	<b>Fuel/Water Separator</b> (1677004C91)..... <b>BF1345-O</b>
	<b>Lube</b> (Standard Vers.) (1R0716).. <b>B99 +</b>	<b>Fuel</b> (1804459C1)..... <b>BF786</b>
	<b>Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b>	<b>O. Air</b> (476741C1)..... <b>[2] PA2521</b>
	<b>B-P Lube</b> (1W8845)..... <b>B7577</b>	<b>I. Air</b> (482644C1)..... <b>[2] PA2522</b>
	<b>Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b>	<b>Trans.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
4900 Series w/V8 7.3L Eng. (Cont'd)	4900 Series w/DT408 (6.7L) Eng. (Cont'd)	4900 Series w/DT466 (7.6L) Eng. (1994-on)
Trans. (4 In. Kit) (Allison 29548988).....	Trans. Spin-on (Fuller 4304827)..	(Cont'd)
PT9415-MPG KIT	BT223	P. Fuel Spin-on.....
2 25/32 In. Steering (w/o Gskt.) (279294C92).....	Opt. Trans. Spin-on (Fuller 17237).....	BF979 +
PT951	B2 +	4 27/32 In. S. Fuel (Fleetguard FF5052).....
2 25/32 In. Steering (w/Gskt.) (279294C92).....	Steering (1681202C91).....	BF788
PT903	PT8407	7 11/32 In. S. Fuel (672603-C3)...
3 31/32 In. Steering (1691121C1).....	4900 Series w/DT466 (7.6L) Eng. (To 1994)	BF588
P106-HD	F-F Lube (1811953-C1).....	Single Fuel (1809789-C1).....
4900 Series w/DT360 (5.9L) Eng.	Dual-Flow Lube (1841606-C1)....	BF7629 +
Lube (1811953C1).....	5 9/32 In. Fuel/Water Separator (1618385-C91).....	O. Air (476741-C1).....
[2] B309	BF1345-O	PA2522
Fuel/Water Separator (1677004C91).....	5 7/16 In. Fuel/Water Separator (Fleetguard FF105D).....	PA2522
BF1345-O	BF957-D +	I. Air (482644C1).....
Fuel (1804459C1).....	5 11/16 In. Fuel/Water Separator (702255-C1).....	PA2522
BF786	BF891	Trans. (2 In. Kit) (Allison 29548987).....
O. Air (476741C1).....	P. Fuel Spin-on.....	PT9416-MPG KIT
PA2521	BF979 +	Trans. (4 In. Kit) (Allison 29548988).....
I. Air (482644C1).....	4 27/32 In. S. Fuel (Fleetguard FF5052).....	PT9415-MPG KIT
PA2522	BF788	2 25/32 In. Steering (w/o Gskt.) (279294C92).....
Trans. (2 In. Kit) (Allison 29548987).....	7 11/32 In. S. Fuel (672603-C3)...	PT951
PT9416-MPG KIT	Single Fuel (1809789-C1).....	2 25/32 In. Steering (w/Gskt.) (279294C92).....
Trans. (4 In. Kit) (Allison 29548988).....	O. Air (476741-C1).....	PT903
PT9415-MPG KIT	PA2521	3 31/32 In. Steering (1691121C1).....
2 25/32 In. Steering (w/o Gskt.) (279294C92).....	I. Air (482644-C1).....	P106-HD
PT951	Cab Air (1696834-C1).....	4900 Series w/DTA360 (5.9L) Eng.
2 25/32 In. Steering (w/Gskt.) (279294C92).....	Air Dryer (AD-IP System) (Bendix 65624).....	Lube (1811953C1).....
PT903	BA5373	B309
3 31/32 In. Steering (1691121C1).....	Air Dryer (AD-9 System) (Bendix 107796).....	Fuel/Water Separator (1677004C91).....
P106-HD	BA5377	BF1345-O
4900 Series w/DTA360 (5.9L) Eng.	4 3/8 In. Coolant (w/4 Units BTA+) (Fleetguard WF2071).....	Fuel (1809789C1).....
Lube (1811953C1).....	BW5071	BF7629 +
B309	5 3/8 In. Coolant (w/4 Units BTA+) (1822313-C1).....	PA2521
Fuel/Water Separator (1677004C91).....	BW5082	PA2522
BF1345-O	Coolant (w/6 Units BTA+) (Fleetguard WF2072).....	I. Air (482644C1).....
Fuel (1809789C1).....	BW5072	PA2522
BF7629 +	Coolant (w/8 Units BTA+) (Fleetguard WF2073).....	Trans. (2 In. Kit) (Allison 29548987).....
O. Air (476741C1).....	BW5073	PT9416-MPG KIT
PA2521	Coolant (w/12 Units BTA+) (Fleetguard WF2074).....	Trans. (4 In. Kit) (Allison 29548988).....
I. Air (482644C1).....	BW5074	PT9415-MPG KIT
PA2522	Coolant (w/15 Units BTA+) (Fleetguard WF2075).....	2 25/32 In. Steering (w/o Gskt.) (279294C92).....
Trans. (2 In. Kit) (Allison 29548987).....	BW5075	PT951
PT9416-MPG KIT	Coolant (w/o Chemical) (Fleetguard WF2101).....	2 25/32 In. Steering (w/Gskt.) (279294C92).....
Trans. (4 In. Kit) (Allison 29548988).....	B5134 +	PT903
PT9415-MPG KIT	Trans. Pan-Type (Allison 29538489).....	4 5/32 In. Steering (1684202C91).....
2 25/32 In. Steering (w/o Gskt.) (279294C92).....	19739 +	PT8407
PT951	Trans. Spin-on (Allison 29510922).....	4900 Series w/DT408 (6.7L) Eng.
2 25/32 In. Steering (w/Gskt.) (279294C92).....	BT8316-MPG	Lube (1819452C1).....
PT903	2 25/32 In. Steering (Fleetguard LF634).....	B7030
4 5/32 In. Steering (1684202C91).....	PT903	Fuel/Water Separator (1677004C91).....
PT8407	3 31/32 In. Steering (1691121-C1).....	BF1345-O
4900 Series w/DT408 (6.7L) Eng.	P106-HD	BF7629 +
Lube (1819452C1).....	4 5/32 In. Steering (1681202-C91).....	PA2521
B7030	PT8407	PA2522
Fuel/Water Separator (1677004C91).....	4900 Series w/DT466 (7.6L) Eng. (1994-on)	BW5082
BF1345-O	F-F Lube (1819452-C1).....	Trans. Ele. (2 In. Kit) (Allison 29548987).....
Fuel (1822588C1).....	B7030	PT9416-MPG KIT
BF7629 +	Dual-Flow Lube (1841606-C1)....	Trans. Ele. (4 In. Kit) (Allison 29548988).....
O. Air (476741C1).....	5 9/32 In. Fuel/Water Separator (1618385-C91).....	PT9415-MPG KIT
PA2521	BF1345-O	Trans. Pan-Type (Allison 29538489).....
I. Air (482644C1).....	5 7/16 In. Fuel/Water Separator (Fleetguard FF105D).....	19739 +
PA2522	BF957-D +	Trans. Spin-on (Allison 29510922).....
Coolant (1822313C1).....	5 11/16 In. Fuel/Water Separator (702255-C1).....	BT8316-MPG
BW5082	BF891	
Trans. Ele. (2 In. Kit) (Allison 29548987).....	4900 Series w/DT466C (7.6L) Eng. (To 1994)	
PT9416-MPG KIT	F-F Lube (1811953-C1).....	
Trans. Ele. (4 In. Kit) (Allison 29548988).....	[2] B309	
PT9415-MPG KIT	Dual-Flow Lube (1841606-C1)....	
Trans. Pan-Type (Allison 29538489).....	5 9/32 In. Fuel/Water Separator (1618385-C91).....	
19739 +	BF1345-O	
Trans. Spin-on (Allison 29510922).....	5 7/16 In. Fuel/Water Separator (Fleetguard FF105D).....	
BT8316-MPG	BF957-D +	
	5 11/16 In. Fuel/Water Separator (702255-C1).....	
	BF891	
	P. Fuel Spin-on.....	
	BF979 +	
	4 27/32 In. S. Fuel (Fleetguard FF5052).....	
	BF788	
	7 11/32 In. S. Fuel (672603-C3)...	
	BF588	
	Single Fuel (1809789-C1).....	
	BF7629 +	
	O. Air (476741-C1).....	
	PA2521	
	I. Air (482644-C1).....	
	PA2522	
	Cab Air (1696834-C1).....	
	PA5691	
	Air Dryer (AD-IP System) (Bendix 65624).....	
	BA5373	
	Air Dryer (AD-9 System) (Bendix 107796).....	
	BA5377	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
4900 Series w/DT466C (7.6L) Eng. (To 1994) (Cont'd)	4900 Series w/DT466C (7.6L) Eng. (1994-on) (Cont'd)	4900 Series w/DTA466 (7.6L) Eng. (1994-on)
4 3/8 In. Coolant (w/4 Units BTA+) (Fleetguard WF2071).....	Coolant (w/o Chemical) (Fleetguard WF2101).....	F-F Lube (1819452-C1).....
BW5071	B5134 +	B7030
5 3/8 In. Coolant (w/4 Units BTA+) (1822313-C1).....	Trans. Pan-Type (Allison 29538489).....	Dual-Flow Lube (1841606-C1)....
BW5082	19739 +	BD7250
Coolant (w/6 Units BTA+) (Fleetguard WF2072).....	Trans. Spin-on (Allison 29510922).....	5 9/32 In. Fuel/Water Separator (1618385-C91).....
BW5072	BT8316-MPG	BF1345-O
Coolant (w/8 Units BTA+) (Fleetguard WF2073).....	2 25/32 In. Steering (Fleetguard LF634).....	5 7/16 In. Fuel/Water Separator (Fleetguard FF105D).....
BW5073	PT903	BF957-D +
Coolant (w/12 Units BTA+) (Fleetguard WF2074).....	3 31/32 In. Steering (1691121-C1).....	5 11/16 In. Fuel/Water Separator (702255-C1).....
BW5074	P106-HD	BF891
Coolant (w/15 Units BTA+) (Fleetguard WF2075).....	4 5/32 In. Steering (1681202-C91).....	P. Fuel Spin-on.....
BW5075	PT8407	BF979 +
Coolant (w/o Chemical) (Fleetguard WF2101).....	4900 Series w/DTA466 (7.6L) Eng. (To 1994)	4 27/32 In. S. Fuel (Fleetguard FF5052).....
B5134 +	F-F Lube (1811953-C1).....	BF788
Trans. Pan-Type (Allison 29538489).....	Dual-Flow Lube (1841606-C1)....	BF588
19739 +	BD7250	BF7629 +
Trans. Spin-on (Allison 29510922).....	5 9/32 In. Fuel/Water Separator (1618385-C91).....	O. Air (476741-C1).....
BT8316-MPG	BF1345-O	PA2521
2 25/32 In. Steering (Fleetguard LF634).....	5 7/16 In. Fuel/Water Separator (Fleetguard FF105D).....	I. Air (482644-C1).....
PT903	BF957-D +	PA2522
3 31/32 In. Steering (1691121-C1).....	5 11/16 In. Fuel/Water Separator (702255-C1).....	PA5691
P106-HD	BF891	Air Dryer (AD-IP System) (Bendix 65624).....
4 5/32 In. Steering (1681202-C91).....	P. Fuel Spin-on.....	BA5373
PT8407	BF979 +	Air Dryer (AD-9 System) (Bendix 107796).....
4900 Series w/DT466C (7.6L) Eng. (1994-on)	7 11/32 In. S. Fuel (672603-C3)...	BA5377
F-F Lube (1819452-C1).....	BF588	4 3/8 In. Coolant (w/4 Units BTA+) (Fleetguard WF2071).....
B7030	BF7629 +	BW5071
Dual-Flow Lube (1841606-C1)....	PA2521	5 3/8 In. Coolant (w/4 Units BTA+) (1822313-C1).....
BD7250	PA5691	BW5082
5 9/32 In. Fuel/Water Separator (1618385-C91).....	Air Dryer (AD-IP System) (Bendix 65624).....	Coolant (w/6 Units BTA+) (Fleetguard WF2072).....
BF1345-O	BA5373	BW5072
5 7/16 In. Fuel/Water Separator (Fleetguard FF105D).....	Air Dryer (AD-9 System) (Bendix 107796).....	Coolant (w/8 Units BTA+) (Fleetguard WF2073).....
BF957-D +	BA5377	BW5073
5 11/16 In. Fuel/Water Separator (702255-C1).....	4 3/8 In. Coolant (w/4 Units BTA+) (Fleetguard WF2071).....	Coolant (w/12 Units BTA+) (Fleetguard WF2074).....
BF891	BW5071	BW5074
P. Fuel Spin-on.....	5 3/8 In. Coolant (w/4 Units BTA+) (1822313-C1).....	Coolant (w/15 Units BTA+) (Fleetguard WF2075).....
BF979 +	BW5082	BW5075
4 27/32 In. S. Fuel (Fleetguard FF5052).....	Coolant (w/6 Units BTA+) (Fleetguard WF2072).....	Coolant (w/o Chemical) (Fleetguard WF2101).....
BF788	BW5072	B5134 +
BF588	BW5073	Trans. Pan-Type (Allison 29538489).....
BF7629 +	BW5074	19739 +
PA2521	BT8316-MPG	Trans. Spin-on (Allison 29510922).....
PA2522	PT903	BT8316-MPG
PA5691	3 31/32 In. Steering (1691121-C1).....	2 25/32 In. Steering (Fleetguard LF634).....
Air Dryer (AD-IP System) (Bendix 65624).....	P106-HD	PT903
BA5373	4 5/32 In. Steering (1681202-C91).....	PT8407
Air Dryer (AD-9 System) (Bendix 107796).....	PT8407	4900 Series w/T444E (7.3L) Eng.
BA5377	4900 Series w/T444E (7.3L) Eng.	Lube (1814562-C1).....
4 3/8 In. Coolant (w/4 Units BTA+) (Fleetguard WF2071).....	Lube (1814562-C1).....	B7030
BW5071	Fuel (1822631-C91).....	PF7678
5 3/8 In. Coolant (w/4 Units BTA+) (1822313-C1).....	O. Air (476741-C1).....	PA2521
BW5082	I. Air (482644-C1).....	PA2522
Coolant (w/6 Units BTA+) (Fleetguard WF2072).....	Radial Seal Air (1691027-C1)....	RS2863
BW5072	Coolant (1822627-C1).....	BW5071
Coolant (w/8 Units BTA+) (Fleetguard WF2073).....	Trans. Pan-Type (3.8 In. Pan) (Allison 29540976).....	19992 +
BW5073	Trans. Pan-Type (5.3 In. Pan) (Allison 29538489).....	19739 +
Coolant (w/12 Units BTA+) (Fleetguard WF2074).....	Trans. Spin-on (Allison 29510922).....	BT8316-MPG
BW5074	Trans. Spin-on (595722-C91)....	BT839-10
Coolant (w/15 Units BTA+) (Fleetguard WF2075).....		
BW5075		

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
4900 Series w/T444E (7.3L) Eng. (Cont'd)	4900 Series w/HT570 Eng.	5000 w/Cummins N14 (14.0L) Eng. (To 12/1995)
<b>3 31/32 In. Steering</b> (1691121-C1)..... <b>P106-HD</b>	<b>Dual-Flow Lube</b> (1842639-C91).. <b>BD7250</b>	<b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b>
<b>4 5/32 In. Steering</b> (1681202-C91)..... <b>PT8407</b>	<b>Lube Spinner</b> (1842825-C91)..... <b>BC7394</b>	<b>F-F Lube</b> (Standard Vers.) (Fleetguard LF670SC)..... <b>B196 +</b>
<b>5 1/32 In. Steering</b> (1695528-C1)..... <b>PT9419-MPG</b>	<b>Fuel/Water Separator Ele.</b> (1842638-C91)..... <b>PF7779</b>	<b>F-F Lube</b> (Ext. Life) (Fleetguard LF670SC)..... <b>B96 +</b>
4900 Series w/DT530 (8.7L) Eng.	<b>Radial Seal O. Air</b> (3532801-C1). <b>RS30090-FN</b>	<b>B-P Lube</b> (3304232)..... <b>B577</b>
<b>Lube</b> (1833121-C1)..... <b>B7030</b>	<b>Steering</b> (1681202-C91)..... <b>PT8407</b>	<b>Fuel/Water Separator</b> (3308638). <b>BF1212 +</b>
<b>Fuel/Water Separator</b> (1618386-C93)..... <b>BF1345-O</b>	4970 Transtar II Series w/GMC 8V-71, 8V-92T Engs.	<b>Fuel</b> (154789)..... <b>BF957-D +</b>
<b>Fuel</b> (1822588-C1)..... <b>BF7629 +</b>	<b>Lube</b> ..... <b>P20-HD</b>	<b>Coolant</b> (w/4 Units BTA+) (3315116)..... <b>BW5071</b>
<b>Fuel</b> (Fleetguard FF5052)..... <b>BF788</b>	<b>P. Fuel Spin-on</b> ..... <b>BF5800 +</b>	5000 w/Cummins N14 (14.0L) Eng. (12/1995-on)
<b>O. Air</b> (476741-C1)..... <b>PA2521</b>	<b>S. Fuel Spin-on</b> ..... <b>BF5810</b>	<b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b>
<b>I. Air</b> (482644-C1)..... <b>PA2522</b>	5000 w/Cummins ISM (10.8L) Eng.	<b>F-F Lube</b> (Standard Vers.) (Fleetguard LF670SC)..... <b>B196 +</b>
<b>Cab Air</b> (1696834-C1)..... <b>PA5691</b>	<b>Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154 +</b>	<b>F-F Lube</b> (Ext. Life) (Fleetguard LF670SC)..... <b>B96 +</b>
<b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b>	<b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>	<b>B-P Lube</b> (3304232)..... <b>B577</b>
<b>Coolant</b> (w/o Chemical) (Fleetguard WF2101)..... <b>B5134 +</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1000)..... <b>BF1259</b>	<b>Fuel/Water Separator</b> (3329289). <b>BF1259</b>
<b>4 3/8 In. Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>	<b>O. Air</b> (530561-C1)..... <b>PA2330</b>	<b>Fuel</b> (154789)..... <b>BF957-D +</b>
<b>5 3/8 In. Coolant</b> (w/4 Units BTA+) (1822313-C1)..... <b>BW5082</b>	<b>I. Air</b> (530560-C2)..... <b>PA2579</b>	<b>Coolant</b> (w/4 Units BTA+) (3315116)..... <b>BW5071</b>
<b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b>	<b>Radial Seal O. Air</b> (Standard) (3560734-C1)..... <b>RS3518</b>	5000 w/DT530 (8.7L) Eng.
<b>Trans. Pan-Type</b> (Allison 29538489)..... <b>19739 +</b>	<b>Radial Seal XP O. Air</b> (Upgrade) (3560734-C1)..... <b>RS3518XP</b>	<b>Lube</b> (1819452-C1)..... <b>B7030</b>
<b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b>	<b>Radial Seal I. Air</b> (3520401-C1)... <b>RS3519</b>	<b>Fuel</b> (1809789-C1)..... <b>BF7629 +</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Coolant</b> (1822313-C1)..... <b>BW5082</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b>	5000 Paystar w/Cat C12 Eng.
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	<b>F-F Lube</b> (1R0716)..... <b>B99 +</b>
<b>3 31/32 In. Steering</b> (Fleetguard HF6162)..... <b>P106-HD</b>	<b>Steering Ele.</b> (279294-C92)..... <b>PT903</b>	<b>F-F Lube</b> (High Efficiency) (1R1808)..... <b>B7299 +</b>
<b>4 5/32 In. Steering</b> (1681202-C91)..... <b>PT8407</b>	<b>Steering Spin-on</b> (2503221-C1).. <b>BT9388</b>	<b>Fuel/Water Separator</b> (w/o SP) (1685159-C91)..... <b>BF1346 +</b>
4900 Series w/DT570 Eng.	5000 w/Cummins L10 (10.0L) Eng.	<b>Fuel/Water Separator</b> (w/SP) (1685159-C91)..... <b>BF1346-SP +</b>
<b>Dual-Flow Lube</b> (1842639-C91).. <b>BD7250</b>	<b>Dual-Flow Lube</b> (Fleetguard LF3000)..... <b>BD103 +</b>	<b>O. Air</b> (530561-C1)..... <b>PA2330</b>
<b>Fuel/Water Separator</b> (1842638-C91)..... <b>PF7779</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1212)..... <b>BF1212 +</b>	<b>I. Air</b> (530560-C2)..... <b>PA2579</b>
<b>Fuel</b> (1822588-C1)..... <b>BF7629 +</b>	<b>O. Air</b> (Fleetguard AF994)..... <b>PA2330</b>	<b>Cab Air</b> (498144-C1)..... <b>PA5690</b>
<b>O. Air</b> ..... <b>LL2521</b>	<b>I. Air</b> (Fleetguard AF984)..... <b>PA2579</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
<b>I. Air</b> ..... <b>PA2522</b>	<b>Single Air</b> (1685307C1)..... <b>PA2333</b>	<b>Coolant</b> (1822627-C1)..... <b>BW5071</b>
<b>Cab Air</b> (1696834-C1)..... <b>PA5691</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b>	<b>Coolant</b> (Fleetguard WF2074)..... <b>BW5074</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Crankcase Breather</b> ..... <b>CLN&amp;R</b>	<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	<b>Trans. Spin-on</b> (Fleetguard HF6107)..... <b>B252</b>
<b>Coolant</b> ..... <b>BW5071</b>	<b>Steering</b> (w/o Gasket) (279294-C92)..... <b>PT903</b>	<b>Steering Ele.</b> (279294-C92)..... <b>PT903</b>
<b>Trans. Pan-Type</b> (Allison 29538489)..... <b>19739 +</b>	<b>Steering</b> (w/Gasket) (279294-C92)..... <b>PT951</b>	5000 Paystar w/Cat 3176 Eng.
<b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b>	5000 w/Cummins M11 (10.8L) Eng.	<b>Lube Spin-on</b> ..... <b>B99 +</b>
<b>Steering</b> (1681202-C91)..... <b>PT8407</b>	<b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b>	<b>P. Fuel Ele.</b> ..... <b>[2] PF935</b>
	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b>	<b>Fuel Spin-on</b> ..... <b>BF614 +</b>
	<b>Fuel/Water Separator Spin-on</b> (2568753)..... <b>BF1259</b>	5000 Paystar w/Cat 3306 Eng.
		<b>Lube Spin-on</b> (Standard Vers.) (1R0739)..... <b>B76</b>
		<b>Fuel Spin-on</b> (1R0740)..... <b>BF970 +</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
5000 Paystar w/Cat 3406 Eng. F-F Lube (1R0716)..... B99 + F-F Lube (High Efficiency) (1R1808)..... B7299 + <b>Fuel/Water Separator</b> (598435-C1)..... BF1212 + <b>Air</b> (1685307-C1)..... PA2333 <b>Cab Air</b> (498144-C1)..... PA5690 <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... BA5377 <b>Coolant</b> (1822627-C1)..... BW5071 <b>Trans.</b> (Fuller 4304827)..... BT223 <b>Steering</b> (279294-C92)..... PT903 <b>Some Differential</b> (Meritor 3280-V-8394)..... B233	5050 Paystar Series w/Cat 3208 Eng. Lube (9L9200)..... [2] BT364 Lube (9N5570)..... [2] BT230 + <b>Box-Style Fuel/Water Separator.</b> BF912 <b>Fuel Spin-on</b> ..... BF970 + 5050 Paystar Series w/Cummins V555, VT555 Engs. F-F Lube Ele..... P999-HD F-F Lube Spin-on..... B196 + B-P Lube Ele..... C704-L <b>Fuel Spin-on</b> ..... BF957 + <b>Breather Ele.</b> (w/o Turbo)..... PA1627 <b>Coolant Spin-on</b> ..... BW5071 5050 Paystar Series w/GMC 6V-53 Eng. F-F Lube Ele..... P20-HD P. Fuel Sock..... F916-C S. Fuel Ele..... PF906 5050 Paystar Series w/D190 Eng. Lube Spin-on..... B167 P. Fuel Spin-on..... BF979 + S. Fuel Spin-on..... BF588 5050 Paystar Series w/DT466 Eng. Lube (1808896-C1)..... [2] B299 + Lube (1811953-C1)..... [2] B309 7 In. P. Fuel..... BF991 S. Fuel..... BF588 5050 Paystar Series w/DV550B Eng. Lube Ele. (313117-C92)..... [2] P276 Lube Spin-on (427207-C2)..... [2] B167 P. Fuel Spin-on (S/N 7164-up)..... BF979 + S. Fuel Ele. (S/N 5118-7163)..... PF225 S. Fuel Spin-on (S/N 7164-up)..... BF888 Air (S/N 36674-up) (303642-C91) PA1786 5070 Paystar Series w/Cummins Eng. F-F Lube Ele..... P999-HD F-F Lube Spin-on..... B196 + B-P Lube Ele..... C750-E + <b>Fuel Spin-on</b> ..... BF957 + <b>Coolant Spin-on</b> ..... BW5071 5070 Paystar Series w/GMC 6-71, 8V-71 Series Diesel Engs. F-F Lube Ele..... P20-HD P. Fuel Spin-on..... BF5800 + S. Fuel Spin-on..... BF5810 5070 Paystar Series w/V800 Eng. Lube Ele..... [2] PT86-HD Lube Spin-on..... [2] B97 <b>Fuel/Water Separator</b> ..... BF891 P. Fuel Spin-on..... BF979 + 7 11/32 In. S. Fuel Spin-on..... BF588 8 11/16 In. S. Fuel Spin-on..... BF888 <b>Coolant Spin-on</b> ..... BW5137 5500i w/Cummins ISM 10.8 (10.8L) Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9001)..... BD7154 + <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... BD50000	5500i w/Cummins ISM 10.8 (10.8L) Eng. (Cont'd) <b>Fuel/Water Separator</b> (Fleetguard FS1000)..... BF1259 <b>Fuel</b> ..... BF7766 <b>Radial Seal O. Air</b> (Standard) (3560734-C1)..... RS3518 <b>Radial Seal XP O. Air</b> (Upgrade) (3560734-C1)..... RS3518XP <b>Radial Seal I. Air</b> (3520401-C1)... RS3519 <b>Cab Air</b> (1699956-C1)..... PA5637 <b>Air Dryer</b> (Bendix 107796)..... BA5377 <b>Crankcase Breather</b> (3683918)... CV15000 <b>Coolant</b> (Fleetguard WF2071)..... BW5071 <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT <b>Trans. Spin-on</b> (Fuller 4304827).. BT223 <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... B2 + <b>Steering</b> (2503221-C1)..... BT9388 5500i w/Cummins N14 (14.0L) Eng. <b>Dual-Flow Lube</b> (3318853)..... BD103 + <b>F-F Lube</b> (Standard Vers.) (Fleetguard LF670SC)..... B196 + <b>F-F Lube</b> (Ext. Life) (Fleetguard LF670SC)..... B96 + <b>B-P Lube</b> (3304232)..... B7577 <b>Fuel/Water Separator</b> (3329289). BF1259 <b>Fuel</b> (154789)..... BF957-D + <b>Coolant</b> (w/4 Units BTA+) (3315116)..... BW5071 5500i w/DT466 (7.6L) Eng. F-F Eng. Lube (1819452C1)..... B7030 <b>Fuel/Water Separator Ele.</b> (1842638C92)..... PF7779 <b>Fuel</b> (625625C1)..... BF984 <b>Fuel</b> (625627C1)..... BF979 + <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071 <b>Coolant</b> (w/12 Units BTA+) (1820361C1)..... BW5074 5500i w/IHC HT530 Eng. Lube (1833121-C1)..... B7030 <b>Fuel</b> (1822588-C1)..... BF7629 + <b>Radial Seal O. Air</b> (Standard) (3560734-C1)..... RS3518 <b>Radial Seal XP O. Air</b> (Upgrade) (3560734-C1)..... RS3518XP <b>Radial Seal I. Air</b> (3520401-C1)... RS3519 <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... BA5377 <b>Opt. Trans.</b> (Fuller 17237)..... B2 + <b>Steering</b> (2503221-C1)..... BT9388 <b>Some Differential</b> (Meritor 3280-V-8394)..... B233

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
5500i, 5600i w/Cat C10, C12 Engs.	5500i PayStar, 5600i PayStar w/Cat C13 Eng.	5500i PayStar, 5600i PayStar w/Cummins ISX Eng.
<b>Lube</b> ..... B99 +	<b>Lube</b> (1R1808)..... B7299 +	<b>Dual-Flow Lube</b> (Fleetguard LF9001)..... BD7154 +
<b>Fuel/Water Separator</b> (Fleetguard FS1212)..... BF1212 +	<b>10 1/2 In. Fuel</b> (1R0749)..... BF7587 +	<b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... BD50000
<b>Fuel</b> ..... BF7587 +	<b>11 7/32 In. Fuel</b> (3563465-C1)..... BF596 +	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19729)..... PF7755
<b>Fuel</b> (3563465-C1)..... BF596 +	<b>Radial Seal O. Air</b> (Standard) (3560734-C1)..... RS3518	<b>Fuel</b> (Fleetguard FF2200)..... BF7766
<b>Radial Seal O. Air</b> (Standard) (3560734-C1)..... RS3518	<b>Radial Seal XP O. Air</b> (Upgrade) (3560734-C1)..... RS3518XP	<b>Fuel</b> (Fleetguard FF2203)..... BF7760
<b>Radial Seal XP O. Air</b> (Upgrade) (3560734-C1)..... RS3518XP	<b>Radial Seal I. Air</b> (3520401-C1)... RS3519	<b>Fuel</b> (Standard) (Fleetguard FF5776)..... BF9885 +
<b>Radial Seal I. Air</b> (3520401-C1)... RS3519	<b>Cab Air</b> (1699956-C1)..... PA5637	<b>Fuel</b> (Upgrade) (Fleetguard FF5825NN)..... BF46129
<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... BA5373	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... BA5377	<b>Radial Seal O. Air</b> (Standard) (3560734-C1)..... RS3518
<b>Air Dryer</b> (AD-9 Dryer) (Bendix 107796)..... BA5377	<b>Air Dryer</b> (AD-SP System) (Bendix 109994)..... BA5374 +	<b>Radial Seal XP O. Air</b> (Upgrade) (3560734-C1)..... RS3518XP
<b>Opt. Trans.</b> (Fuller 17237)..... B2 +	<b>Crankcase Breather</b> (2007-on) (296-8325)..... CV15008	<b>Radial Seal I. Air</b> (3520401-C1)... RS3519
<b>Steering</b> (2503221-C1)..... BT9388	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	<b>Cab Air</b> (1699956-C1)..... PA5637
<b>Some Differential</b> (Meritor 3280-V-8394)..... B233	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... BA5377
5500i, 5600i w/DT530 (8.7L) Eng.	<b>Trans. Spin-on</b> (Fuller 4304827).. BT223	<b>Air Dryer</b> (AD-SP System) (Bendix 109994)..... BA5374 +
<b>F-F Lube</b> (1819452-C1)..... B7030	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... B2 +	<b>Crankcase Breather</b> (3683918)... CV15000
<b>Dual-Flow Lube</b> (1842639-C91).. BD7250	<b>Steering</b> (2503221-C1)..... BT9388	<b>Coolant</b> (w/11 1/2 Units BTA+) (Fleetguard WF2126)..... BW5086
<b>Fuel</b> (1822588-C1)..... BF7629 +	5500i PayStar, 5600i PayStar w/Cat C15 Eng.	<b>Coolant</b> (w/o Chemical) (Fleetguard WF2127)..... B5087
<b>Radial Seal Air</b> (Standard) (3560734-C1)..... RS3518	<b>Lube</b> (1R1808)..... B7299 +	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT
<b>Radial Seal XP Air</b> (Upgrade) (3560734-C1)..... RS3518XP	<b>Fuel/Water Separator Ele.</b> (2588149-C1)..... PF7748	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... BA5377	<b>Fuel/Water Separator Spin-on</b> (Cummins 3309437)..... BF1216 +	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... B2 +
<b>Opt. Trans.</b> (Fuller 17237)..... B2 +	<b>Fuel</b> (1R0749)..... BF7587 +	<b>Steering</b> (2503221-C1)..... BT9388
<b>Steering</b> (2503221-C1)..... BT9388	<b>Fuel</b> (Fleetguard FF202)..... BF596 +	5600 Series w/Cat C12 Eng.
<b>Some Differential</b> (Meritor 3280-V-8394)..... B233	<b>Radial Seal O. Air</b> (Standard) (3560734-C1)..... RS3518	<b>F-F Lube</b> (1R0716)..... B99 +
5500i PayStar w/Cummins ISL (8.9L) Eng.	<b>Radial Seal XP O. Air</b> (Upgrade) (3560734-C1)..... RS3518XP	<b>F-F Lube</b> (High Efficiency) (1R1808)..... B7299 +
<b>Dual-Flow Lube</b> (Fleetguard LF9009)..... BD7309 +	<b>Radial Seal I. Air</b> (3520401-C1)... RS3519	<b>Fuel/Water Separator</b> (Fleetguard FS1212)..... BF1212 +
<b>Fuel/Water Separator</b> (Fleetguard FS1065)..... BF1378-SPS	<b>Cab Air</b> (1699956-C1)..... PA5637	<b>Fuel</b> (1R1712)..... BF614 +
<b>Fuel/Water Separator</b> (Fleetguard FS1003)..... BF1293-SPS	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... BA5377	<b>Fuel</b> (High Efficiency) (1R0749)... BF7587 +
<b>Fuel</b> (Fleetguard FF5636)..... BF7924	<b>Air Dryer</b> (AD-SP System) (Bendix 109994)..... BA5374 +	<b>O. Air</b> (530561-C1)..... PA2330
<b>Fuel</b> (Fleetguard FF5488)..... BF7815	<b>Crankcase Breather</b> (2007-on) (296-8325)..... CV15008	<b>I. Air</b> (530560-C2)..... PA2579
<b>Radial Seal O. Air</b> (Standard) (3560734C1)..... RS3518	<b>Coolant</b> (w/o Chemical) (Fleetguard WF2101)..... B5134 +	<b>Cab Air</b> (498144-C1)..... PA5690
<b>Radial Seal XP O. Air</b> (Upgrade) (3560734C1)..... RS3518XP	<b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071	<b>Coolant</b> (1822627-C1)..... BW5071
<b>Radial Seal I. Air</b> (3520401C1)... RS3519	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	<b>Opt. Trans.</b> (Fuller 17237)..... B2 +
<b>Cab Air</b> (1699956C1)..... PA5637	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	5600 Series w/Cat 3406E Eng.
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... BA5377	<b>Trans. Spin-on</b> (Fuller 4304827).. BT223	<b>Lube</b> (1R0716)..... B99 +
<b>Air Dryer</b> (System Saver 1200) (Wabco 950011)..... BA5374 +	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... B2 +	<b>Fuel/Water Separator</b> (598435-C1)..... BF1212 +
<b>Trans.</b> (Fuller 4304827)..... BT223	<b>Steering</b> (2503221-C1)..... BT9388	<b>Fuel</b> (1R0749)..... BF7587 +
<b>Opt. Trans.</b> (Fuller 17237)..... B2 +		<b>Radial Seal Air</b> (Standard) (3540117-C1)..... RS3518
<b>Steering</b> (2503221C1)..... BT9388		<b>Radial Seal Air</b> (Upgrade) (3540117-C1)..... RS3518XP

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
5600 Series w/Cat 3406E Eng. (Cont'd)	5600i w/Cummins ISM 10.8 (10.8L) Eng. (Cont'd)	5900i PayStar w/Cat C13 Eng.
Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	Fuel..... <b>BF7766</b>	Lube (1R1808)..... <b>B7299 +</b>
Trans. (Fuller 4304827)..... <b>BT223</b>	Radial Seal O. Air (Standard) (3560734-C1)..... <b>RS3518</b>	Fuel/Water Separator (Fleetguard FS1212)..... <b>BF1212 +</b>
Steering (2503221-C1)..... <b>BT9388</b>	Radial Seal XP O. Air (Upgrade) (3560734-C1)..... <b>RS3518XP</b>	Fuel (Fleetguard FF202)..... <b>BF596 +</b>
Some Differential (1685141-C1)..... <b>B233</b>	Radial Seal I. Air (3520401-C1)..... <b>RS3519</b>	Fuel (1R0749)..... <b>BF7587 +</b>
5600 Series w/Cummins N14 (14.0L) Eng.	Cab Air (1699956-C1)..... <b>PA5637</b>	Fuel Strainer (Fleetguard FF2203)..... <b>BF7760</b>
F-F Lube (Fleetguard LF670SC)..... <b>B196 +</b>	Air Dryer (Bendix 107796)..... <b>BA5377</b>	Radial Seal Air (3507421-C1)..... <b>[2] RS3743</b>
B-P Lube (3304232)..... <b>B7577</b>	Crankcase Breather (3683918)..... <b>CV15000</b>	Radial Seal O. Air (Standard) (3560734C1)..... <b>RS3518</b>
Dual-Flow Lube (Std. Vers.) (3318853)..... <b>BD103 +</b>	Coolant (Fleetguard WF2071)..... <b>BW5071</b>	Radial Seal XP O. Air (Upgrade) (3560734C1)..... <b>RS3518XP</b>
Dual-Flow Lube (High Velocity) (Fleetguard LF9009)..... <b>BD7309 +</b>	Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	Radial Seal I. Air (3520401-C1)..... <b>RS3519</b>
Fuel/Water Separator (Fleetguard FS1000)..... <b>BF1259</b>	Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Cab Air (1699956-C1)..... <b>PA5637</b>
Fuel (154789)..... <b>BF957-D +</b>	Trans. Spin-on (Fuller 4304827)..... <b>BT223</b>	Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
Radial Seal Air (Standard) (3560734-C1)..... <b>RS3518</b>	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	Air Dryer (AD-IP System) (Bendix 65624)..... <b>BA5373</b>
Radial Seal XP Air (Upgrade) (3560734-C1)..... <b>RS3518XP</b>	Steering (2503221-C1)..... <b>BT9388</b>	Air Dryer (AD-SP System) (Bendix 109994)..... <b>BA5374 +</b>
Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	5600i w/DT466 (7.6L) Eng.	Crankcase Breather (2007-on) (296-8325)..... <b>CV15008</b>
Coolant (Fleetguard WF2071)..... <b>BW5071</b>	F-F Eng. Lube (1819452C1)..... <b>B7030</b>	Coolant (9N3368)..... <b>BW5137</b>
Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	Fuel/Water Separator Ele. (1842638C92)..... <b>PF7779</b>	Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
Steering (2503221-C1)..... <b>BT9388</b>	Fuel (625625C1)..... <b>BF984</b>	Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
Some Differential (Meritor 3280-V-8394)..... <b>B233</b>	Fuel (625627C1)..... <b>BF979 +</b>	Trans. Spin-on (Fuller 4304827)..... <b>BT223</b>
5600 Series w/IHC HT530 Eng.	Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>
Lube (1833121-C1)..... <b>B7030</b>	Coolant (w/12 Units BTA+) (1820361C1)..... <b>BW5074</b>	Steering (2503221-C1)..... <b>BT9388</b>
Fuel (1822588-C1)..... <b>BF7629 +</b>	5900i w/Cat C10, C12 Engs.	
Radial Seal Air (Standard) (3560734-C1)..... <b>RS3518</b>	Lube..... <b>B99 +</b>	5900i PayStar w/Cat C15 Eng.
Radial Seal XP Air (Upgrade) (3560734-C1)..... <b>RS3518XP</b>	Fuel/Water Separator (Fleetguard FS1212)..... <b>BF1212 +</b>	Lube (1R1808)..... <b>B7299 +</b>
Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	Fuel..... <b>BF7587 +</b>	Fuel/Water Separator Ele. (2588149-C1)..... <b>PF7748</b>
Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	Radial Seal Air (Standard) (3560734-C1)..... <b>RS3518</b>	Fuel (1R0749)..... <b>BF7587 +</b>
Steering (2503221-C1)..... <b>BT9388</b>	Radial Seal XP Air (Upgrade) (3560734-C1)..... <b>RS3518XP</b>	Fuel (3313306)..... <b>BF596 +</b>
5600i w/Cummins ISL (8.9L) Eng.	Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	Radial Seal Air (3507421-C1)..... <b>[2] RS3743</b>
Dual-Flow Lube (3825970)..... <b>BD103 +</b>	Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	Cab Air (1699956-C1)..... <b>PA5637</b>
Fuel/Water Separator (3406889)..... <b>BF1293-SPS</b>	Steering (2503221-C1)..... <b>BT9388</b>	Air Dryer (AD-IP System) (Bendix 65624)..... <b>BA5373</b>
Fuel/Water Separator (4934879)..... <b>BF1378-SPS</b>	Some Differential (Meritor 3280-V-8394)..... <b>B233</b>	Air Dryer (AD-SP System) (Bendix 109994)..... <b>BA5374 +</b>
Fuel (4940647)..... <b>BF7924</b>	5900i PayStar w/Cummins ISX	Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
Radial Seal O. Air (Standard) (3560734C1)..... <b>RS3518</b>	Dual-Flow Lube (Fleetguard LF14000NN)..... <b>BD50000</b>	Crankcase Breather (2007-on) (296-8325)..... <b>CV15008</b>
Radial Seal XP O. Air (Upgrade) (3560734C1)..... <b>RS3518XP</b>	Fuel/Water Separator (Fleetguard FS19764)..... <b>PF9814</b>	Opt. Crankcase Breather (3805839)..... <b>CV15007</b>
Radial Seal I. Air (3520401C1)..... <b>RS3519</b>	Fuel (Standard) (Fleetguard FF5776)..... <b>BF9885 +</b>	Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
Air Dryer (Wabco 950011)..... <b>BA5374 +</b>	Fuel (Upgrade) (Fleetguard FF5825NN)..... <b>BF46129</b>	Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
Trans. (Fuller 4304827)..... <b>BT223</b>	Steering (2503221C3)..... <b>BT9388</b>	Trans. Spin-on (Fuller 4304827)..... <b>BT223</b>
Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	Diesel Exhaust Fluid (5303604)..... <b>PE17000</b>	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>
Steering (2503221C1)..... <b>BT9388</b>		Steering (2503221-C1)..... <b>BT9388</b>
5600i w/Cummins ISM 10.8 (10.8L) Eng.		
Dual-Flow Lube (Fleetguard LF9001)..... <b>BD7154 +</b>		
Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>		
Fuel/Water Separator (Fleetguard FS1000)..... <b>BF1259</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
5900i PayStar w/MaxxForce 13 Eng. Lube (3007498-C92)..... <b>P7494</b> Centrifugal Lube (2606467-C91) <b>BC7485 +</b> Fuel/Water Separator (3004473-C93)..... <b>PF7986</b> Fuel/Water Separator (Fleetguard FS19764)..... <b>PF9814</b> Fuel/Water Separator (Open End for Bowl) (2611236C1)..... <b>BF46018-O</b> Fuel/Water Separator (w/Drain) (2611236C1)..... <b>BF1281</b> Pre-Fuel (3004474-C92)..... <b>PF7939 +</b> Radial Seal Air (Don. P539765)... <b>[2] RS3743</b> Oval Air (2609683-C1)..... <b>PA30066</b> Cab Air (1699956-C1)..... <b>PA5637</b> Air Dryer (AD-9 System) (Bendix 107794)..... <b>BA5377</b> Air Dryer (AD-SP System) (Bendix 5008414)..... <b>BA5374 +</b> Trans. Ele. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Steering (2503221-C1)..... <b>BT9388</b>	5900i SBA w/Cummins ISM (10.8L) Eng. (Cont'd) Air Dryer (AD-SP System) (Bendix 109994)..... <b>BA5374 +</b> Air Dryer (AD-IP System) (Bendix 65624)..... <b>BA5373</b> Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b> Crankcase Breather (3683918)... <b>CV15000</b> Coolant (Fleetguard WF2071)..... <b>BW5071</b> Coolant (w/o Chemicals) (4920476)..... <b>B5090</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Steering (2503221-C1)..... <b>BT9388</b>	5900i SBA w/Cummins ISX (15.0L) Eng. (Cont'd) Coolant (w/o Chemical) (Fleetguard WF2127)..... <b>B5087</b> Coolant (w/11 1/2 Units BTA+) (Fleetguard WF2126)..... <b>BW5086</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Steering (2503221-C1)..... <b>BT9388</b> Diesel Exhaust Fluid (5303604).. <b>PE17000</b>
5900i PayStar w/MaxxForce 15 Eng. Lube (7092005C91)..... <b>B7507</b> Fuel/Water Separator Ele. (Fleetguard FS19765)..... <b>PF7930</b> Fuel/Water Separator (Open End for Bowl) (2611236C1)..... <b>BF46018-O</b> Fuel/Water Separator (w/Drain) (2611236C1)..... <b>BF1281</b> Fuel (3014300C1)..... <b>BF7587</b> Radial Seal Air (3507421-C1)..... <b>[2] RS3743</b> Oval Air (2609683C1)..... <b>PA30066</b> Cab Air (1699956C1)..... <b>PA5637</b> Air Dryer (AD-SP System) (Bendix 5008414)..... <b>BA5374 +</b> Air Dryer (AD-9 System) (Bendix 107794)..... <b>BA5377</b> Trans. Ele. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Steering (2503221C1)..... <b>BT9388</b>	5900i SBA w/Cummins ISX (15.0L) Eng. Dual-Flow Lube (Fleetguard LF9001)..... <b>BD7154 +</b> Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> Fuel/Water Separator Ele. (Fleetguard FS19729)..... <b>PF7755</b> Fuel/Water Separator Ele. (Fleetguard FS19764)..... <b>PF9814</b> Fuel/Water Separator Spin-on (3591076-C1)..... <b>BF7760</b> Fuel/Water Separator (Open End for Bowl) (2611236C1)..... <b>BF46018-O</b> Fuel/Water Separator (w/Drain) (2611236C1)..... <b>BF1281</b> Fuel (Pre-2010 Emissions) (Fleetguard FF2200)..... <b>BF7766</b> 8 27/32 In. Fuel (2010 Emissions) (Fleetguard FF5776)... <b>BF9885 +</b> 11 9/16 In. Fuel (2010 Emissions) (Fleetguard FF5686)... <b>BF9860 +</b> 8 27/32 In. Fuel (Upgrade) (Fleetguard FF5825NN)..... <b>BF46129</b> Radial Seal O. Air (Standard) (3560734-C1)..... <b>RS3518</b> Radial Seal XP O. Air (Upgrade) (3560734-C1)..... <b>RS3518XP</b> Radial Seal I. Air (3520401-C1)... <b>RS3519</b> Radial Seal Air (3507421-C1)..... <b>[2] RS3743</b> Cab Air (1699956-C1)..... <b>PA5637</b> Air Dryer (AD-IP System) (Bendix 65624)..... <b>BA5373</b> Air Dryer (AD-SP System) (Bendix 109994)..... <b>BA5374 +</b> Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b> Crankcase Breather (Fleetguard CV50634)..... <b>CV15000</b>	5900i SBA w/Cummins N14 (14.0L) Eng. Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309 +</b> Fuel/Water Separator..... <b>BF1259</b>
5900i SBA w/Cummins ISM (10.8L) Eng. Dual-Flow Lube (Fleetguard LF9001)..... <b>BD7154 +</b> Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> Fuel/Water Separator (3329289). <b>BF1259</b> Radial Seal Air (3507421-C1)..... <b>[2] RS3743</b> Cab Air (1699956-C1)..... <b>PA5637</b>	7070 Conco Series w/Cummins NTC290 Eng. F-F Lube Ele..... <b>P999-HD</b> F-F Lube Spin-on..... <b>B196 +</b> B-P Lube Ele..... <b>C750-E +</b> Fuel Spin-on..... <b>BF957 +</b> Coolant Spin-on..... <b>BW5071</b>	7100 w/DT466 (7.6L) Eng. Lube (1811953-C1)..... <b>B309</b> Fuel/Water Separator (1677004-C91)..... <b>BF1345-O</b> Fuel/Water Separator (1660332-C1)..... <b>BF957-D +</b> Fuel/Water Separator (Fleetguard FS1205)..... <b>BF912</b> 5 5/16 In. P. Fuel Spin-on (625625-C1)..... <b>BF984</b> 8 23/32 In. P. Fuel Spin-on..... <b>BF979 +</b> 7 In. S. Fuel (1822588-C1)..... <b>BF7629 +</b> 7 11/32 In. S. Fuel..... <b>BF588</b> O. Air (1661755-C91)..... <b>PA2521</b> I. Air (Fleetguard AF987)..... <b>PA2522</b> Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> Coolant (w/6 Units BTA+) (Fleetguard WF2072)..... <b>BW5072</b> Coolant (w/8 Units BTA+) (Fleetguard WF2073)..... <b>BW5073</b> Coolant (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b> Coolant (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b> 3 31/32 In. Steering (Fleetguard HF6162)..... <b>P106-HD</b> 4 5/32 In. Steering (1681202-C91)..... <b>PT8407</b>
		7100 w/DT466C (7.6L) Eng. Lube (1811953-C1)..... <b>B309</b> Fuel/Water Separator (1677004-C91)..... <b>BF1345-O</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
7100 w/DTA466C (7.6L) Eng. (Cont'd)	7100 w/DTA466C (7.6L) Eng.	7300 w/Cummins ISB 6.7 (6.7L) Eng. (2016)
<b>Fuel/Water Separator</b> (1660332-C1)..... <b>BF957-D +</b>	<b>Lube</b> (1811953-C1)..... <b>B309</b>	<b>Dual-Flow Lube</b> (Fleetguard LF3000)..... <b>BD103 +</b>
<b>Fuel/Water Separator</b> (Fleetguard FS1205)..... <b>BF912</b>	<b>Fuel/Water Separator</b> (1677004-C91)..... <b>BF1345-O</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1212)..... <b>BF1212 +</b>
<b>5 5/16 In. P. Fuel Spin-on</b> (625625-C1)..... <b>BF984</b>	<b>Fuel/Water Separator</b> (1660332-C1)..... <b>BF957-D +</b>	<b>Fuel</b> (5303743)..... <b>BF63000</b>
<b>8 23/32 In. P. Fuel Spin-on</b> ..... <b>BF979 +</b>	<b>Fuel/Water Separator</b> (Fleetguard WF1205)..... <b>BF912</b>	<b>Radial Seal Air</b> (Fleetguard AF25707)..... <b>RS4636</b>
<b>7 In. S. Fuel</b> (1822588-C1)..... <b>BF7629 +</b>	<b>5 5/16 In. P. Fuel Spin-on</b> (625625-C1)..... <b>BF984</b>	<b>Cab Air</b> (3839141C1)..... <b>PA5679</b>
<b>7 11/32 In. S. Fuel</b> ..... <b>BF588</b>	<b>8 23/32 In. P. Fuel Spin-on</b> ..... <b>BF979 +</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>
<b>O. Air</b> (1661755-C91)..... <b>PA2521</b>	<b>7 In. S. Fuel</b> (1822588-C1)..... <b>BF7629 +</b>	<b>Air Dryer</b> (AD-SP System) (Bendix 109994)..... <b>BA5374 +</b>
<b>I. Air</b> (Fleetguard AF987)..... <b>PA2522</b>	<b>7 11/32 In. S. Fuel</b> ..... <b>BF588</b>	<b>Crankcase Breather</b> (Fleetguard CV52001)..... <b>CV15010</b>
<b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>	<b>O. Air</b> (1661755-C91)..... <b>PA2521</b>	<b>Coolant</b> (Fleetguard WF2077)..... <b>B5134 +</b>
<b>Coolant</b> (w/6 Units BTA+) (Fleetguard WF2072)..... <b>BW5072</b>	<b>I. Air</b> (Fleetguard AF987)..... <b>PA2522</b>	<b>Trans.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>
<b>Coolant</b> (w/8 Units BTA+) (Fleetguard WF2073)..... <b>BW5073</b>	<b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>	<b>Trans.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>
<b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b>	<b>Coolant</b> (w/6 Units BTA+) (Fleetguard WF2072)..... <b>BW5072</b>	<b>Diesel Exhaust Fluid</b> (Fleetguard UF101)..... <b>PE17000</b>
<b>Coolant</b> (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b>	<b>Coolant</b> (w/8 Units BTA+) (Fleetguard WF2073)..... <b>BW5073</b>	
<b>3 31/32 In. Steering</b> (Fleetguard HF6162)..... <b>P106-HD</b>	<b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b>	7300 w/Cummins ISB 6.7 (6.7L) Eng. (2017)
<b>4 5/32 In. Steering</b> (1681202-C91)..... <b>PT8407</b>	<b>Coolant</b> (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b>	<b>F-F Lube</b> (Fleetguard LF3970)..... <b>B7177</b>
7100 w/DTA466 (7.6L) Eng.	<b>3 31/32 In. Steering</b> (Fleetguard HF6162)..... <b>P106-HD</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b>
<b>Lube</b> (1811953-C1)..... <b>B309</b>	<b>4 5/32 In. Steering</b> (1681202-C91)..... <b>PT8407</b>	<b>Fuel/Water Separator</b> (2514003C1)..... <b>BF46181-O</b>
<b>Fuel/Water Separator</b> (1677004-C91)..... <b>BF1345-O</b>	7100 w/DT530 (8.7L) Eng.	<b>Fuel/Water Separator</b> (4080114C1)..... <b>BF46169-O</b>
<b>Fuel/Water Separator</b> (1660332-C1)..... <b>BF957-D +</b>	<b>F-F Lube</b> (1819452C1)..... <b>B7030</b>	<b>Fuel</b> (5303743)..... <b>BF63000</b>
<b>Fuel/Water Separator</b> (Fleetguard FS1205)..... <b>BF912</b>	<b>Dual-Flow Lube</b> (1842639C91)..... <b>BD7250</b>	<b>Radial Seal Air</b> (Fleetguard AF25707)..... <b>RS4636</b>
<b>5 5/16 In. P. Fuel Spin-on</b> (625625-C1)..... <b>BF984</b>	<b>Fuel/Water Separator Ele.</b> (1842638C92)..... <b>PF7779</b>	<b>Cab Air</b> (3839141C1)..... <b>PA5679</b>
<b>8 23/32 In. P. Fuel Spin-on</b> ..... <b>BF979 +</b>	<b>Fuel</b> (1820479C1)..... <b>BF7531</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>
<b>7 In. S. Fuel</b> (1822588-C1)..... <b>BF7629 +</b>	<b>Coolant</b> (1822313C1)..... <b>BW5082</b>	<b>Air Dryer</b> (AD-SP System) (Bendix 109994)..... <b>BA5374 +</b>
<b>7 11/32 In. S. Fuel</b> ..... <b>BF588</b>	7100 w/T444E (7.3L) Eng.	<b>Crankcase Breather</b> (Fleetguard CV52001)..... <b>CV15010</b>
<b>O. Air</b> (1661755-C91)..... <b>PA2521</b>	<b>Lube</b> (1814562C1)..... <b>B7039</b>	<b>Trans.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>
<b>I. Air</b> (Fleetguard AF987)..... <b>PA2522</b>	<b>Fuel/Water Separator</b> (1677004C91)..... <b>BF1345-O</b>	<b>Trans.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>
<b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>	<b>Fuel</b> (1822631C91)..... <b>PF7678</b>	<b>Diesel Exhaust Fluid</b> (Fleetguard UF101)..... <b>PE17000</b>
<b>Coolant</b> (w/6 Units BTA+) (Fleetguard WF2072)..... <b>BW5072</b>	<b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b>	
<b>Coolant</b> (w/8 Units BTA+) (Fleetguard WF2073)..... <b>BW5073</b>	7300 w/Cummins B6.7 (6.7L) Eng. (2019)	7300 w/Cummins ISB 6.7 (6.7L) Eng. (2018)
<b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b>	<b>Lube</b> (3937736)..... <b>B7177</b>	<b>F-F Lube</b> (Fleetguard LF3970)..... <b>B7177</b>
<b>Coolant</b> (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b>	<b>Fuel</b> (5303743)..... <b>BF63000</b>	<b>Fuel</b> (5303743)..... <b>BF63000</b>
<b>3 31/32 In. Steering</b> (Fleetguard HF6162)..... <b>P106-HD</b>	<b>Radial Seal O. Air</b> (3532799C1)..... <b>RS4636</b>	<b>Primary EnduraCube Air</b> (2517298C1)..... <b>PA32001</b>
<b>4 5/32 In. Steering</b> (1681202-C91)..... <b>PT8407</b>	<b>Radial Seal I. Air</b> (3532800C1)..... <b>RS4637</b>	<b>Cab Air</b> (3839141C1)..... <b>PA5679</b>
	<b>Cab Air</b> (3839141C1)..... <b>PA5679</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>
	<b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b>	<b>Air Dryer</b> (AD-SP System) (Bendix 109994)..... <b>BA5374 +</b>
	<b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b>	<b>Crankcase Breather</b> (Fleetguard CV52001)..... <b>CV15010</b>
	<b>Crankcase Breather</b> (4936636)..... <b>CV15010</b>	
	<b>Trans.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	
	<b>Trans.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	
	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
7300 w/Cummins ISB 6.7 (6.7L) Eng. (2018) (Cont'd) Trans. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	7300 WorkStar w/DT466 (7.6L) Eng. (Cont'd) Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Steering (2503221-C1)..... <b>BT9388</b>	7300 WorkStar w/MaxxForce DT (7.6L) Eng. (2012-on) (Cont'd) Steering (2503221-C1)..... <b>BT9388</b> 7400 w/Cat C11 (11.1L) Eng. Lube (1R1808)..... <b>B7299 +</b> Fuel/Water Separator (2568753)..... <b>BF1259</b> Fuel (Standard Vers.) (1R1712)..... <b>BF614 +</b> Fuel (High Efficiency Vers.) (1R0749)..... <b>BF7587 +</b> Radial Seal O. Air (3532799C1)..... <b>RS4636 +</b> Radial Seal I. Air (3532800C1)..... <b>RS4637</b> Cab Air (2506656C1)..... <b>PA4985</b> Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b> Air Dryer (Mann & Hummel TB1374X)..... <b>BA5374 +</b> Trans. Ele. (2 In. Kit) (Allison 29526899)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Steering (2503221C1)..... <b>BT9388</b> Some Differential (Meritor 3280V8394)..... <b>B233</b>
7300 w/Cummins ISB 6.7 (6.7L) Eng. (2019) Lube (3937736)..... <b>B7177</b> Fuel (5303743)..... <b>BF63000</b> Radial Seal O. Air (3532799C1)..... <b>RS4636</b> Radial Seal I. Air (3532800C1)..... <b>RS4637</b> Cab Air (3839141C1)..... <b>PA5679</b> Air Dryer (Bendix 107796)..... <b>BA5377</b> Air Dryer (Wabco R950011)..... <b>BA5374 +</b> Crankcase Breather (4936636)..... <b>CV15010</b> Trans. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	7300 WorkStar w/MaxxForce DT (7.6L) Eng. (To 2012) Dual-Flow Lube (1842639-C91)..... <b>BD7250</b> Fuel/Water Separator (1878042-C91)..... <b>PF7978</b> Fuel/Water Separator (1822638-C91)..... <b>PF7779</b> Fuel Strainer (1873910-C91)..... <b>PF7994</b> Radial Seal O. Air (3532799-C1)..... <b>RS4636 +</b> Radial Seal I. Air (3532800-C1)..... <b>RS4637</b> Cab Air (31/32 In. Thick) (2506656-C1)..... <b>PA4985</b> Cab Air (1 3/16 In. Thick) (3839141-C1)..... <b>PA5679</b> Air Dryer (Wabco R950011)..... <b>BA5374 +</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Steering (2503221-C1)..... <b>BT9388</b>	7400 w/Cat C12 (12.0L) Eng. Lube (Standard Vers.) (1R0716)..... <b>B99 +</b> Lube (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> B-P Lube (1W8845)..... <b>B7577</b> Fuel Ele. (9M2342)..... <b>[2] PF935</b> Fuel Spin-on (Standard Vers.) (4N5823)..... <b>BF614 +</b> Fuel Spin-on (High Efficiency Vers.)..... <b>BF7587 +</b>
7300 w/Cummins ISB 6.7 (6.7L) Eng. (2020) Lube (3937736)..... <b>B7177</b> Fuel (5303743)..... <b>BF63000</b> Crankcase Breather (4936636)..... <b>CV15010</b>	7300 w/Cummins ISB 6.7 (6.7L) Eng. (2021) Lube (3937736)..... <b>B7177</b> Fuel (5303743)..... <b>BF63000</b> Crankcase Breather (4936636)..... <b>CV15010</b>	7400 w/Cummins ISL 8.9 (8.9L) Eng. (2017) Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309 +</b> Fuel (Fleetguard FF63009)..... <b>BF63000</b> Radial Seal Air (3532799C1)..... <b>RS4636</b> Cab Air (3839141C1)..... <b>PA5679</b> Air Dryer (Bendix 107794)..... <b>BA5377</b> Trans. Ele. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> Diesel Exhaust Fluid (5303604)..... <b>PE17000</b>
7300 w/N9 (9.3L) Eng. Lube (1884508C2)..... <b>B7503</b> Fuel/Water Separator (1878042C93)..... <b>PF7978</b> Cab Air (3839141C1)..... <b>PA5679</b> Cab Air (Optional) (CFFN6100)..... <b>PA30260</b> Air Dryer (Bendix 107794)..... <b>BA5377</b> Trans. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> Diesel Exhaust Fluid (5303604)..... <b>PE17000</b>	7300 WorkStar w/DT466 (7.6L) Eng. (2012-on) Lube (1889124-C91)..... <b>B7503</b> Fuel/Water Separator (1878042-C91)..... <b>PF7978</b> Fuel/Water Separator (1822638-C91)..... <b>PF7779</b> Fuel Strainer (1873910-C91)..... <b>PF7994</b> Radial Seal O. Air (3532799-C1)..... <b>RS4636 +</b> Radial Seal I. Air (3532800-C1)..... <b>RS4637</b> Cab Air (31/32 In. Thick) (2506656-C1)..... <b>PA4985</b> Cab Air (1 3/16 In. Thick) (3839141-C1)..... <b>PA5679</b> Air Dryer (Wabco R950011)..... <b>BA5374 +</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	7400 w/Cummins ISL 8.9 (8.9L) Eng. (2018) Lube (3937736)..... <b>B7177</b> Fuel/Water Separator (2514003C1)..... <b>BF46181-O</b> Fuel (Fleetguard FF63008)..... <b>BF63000</b> Radial Seal O. Air (3532799C1)..... <b>RS4636</b> Radial Seal I. Air (3532800C1)..... <b>RS4637</b> Cab Air (3839141C1)..... <b>PA5679</b> Air Dryer (Wabco R950011)..... <b>BA5374 +</b> Air Dryer (Bendix 109994)..... <b>BA5374 +</b> Crankcase Breather (4936636)..... <b>CV15010</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
7400 w/Cummins ISL 8.9 (8.9L) Eng. (2018) (Cont'd) Trans. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	7400 w/Cummins L9 (9.0L) Eng. (2018) (Cont'd) Cab Air (3839141C1)..... <b>PA5679</b> Air Dryer (Bendix 109994)..... <b>BA5374 +</b> Crankcase Breather (4936636)..... <b>CV15010</b> Trans. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	7400 w/DT466 (7.6L) Eng. (2005-on) (Cont'd) Air Dryer (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b> Trans. Ele. (2 In. Kit) (Allison 29526899)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29526898)..... <b>PT9415-MPG KIT</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Steering (2503221-C1)..... <b>BT9388</b> Some Differential (Meritor 3280-V-8394)..... <b>B233</b>
7400 w/Cummins ISL 8.9 (8.9L) Eng. (2019) Lube (3401544)..... <b>B40142</b> Fuel/Water Separator (4080114C2)..... <b>BF46169-O</b> Fuel (5303743)..... <b>BF63000</b> Radial Seal Air (3532799C1)..... <b>RS4636</b> Cab Air (3839141C1)..... <b>PA5679</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Trans. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	7400 w/Cummins L9 (9.0L) Eng. (2019) Lube (3401544)..... <b>B40142</b> Fuel/Water Separator (4080114C2)..... <b>BF46169-O</b> Fuel (5303743)..... <b>BF63000</b> Radial Seal Air (3532799C1)..... <b>RS4636</b> Cab Air (3839141C1)..... <b>PA5679</b> Air Dryer (Bendix 5008414)..... <b>BA5374</b> Trans. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	7400 w/MaxxForce DT (7.6L) Eng. (To 2012) Dual-Flow Lube (1842639-C91).. <b>BD7250</b> Fuel/Water Separator (1878042-C91)..... <b>PF7978</b> Fuel/Water Separator (1822638-C91)..... <b>PF7779</b> Fuel Strainer (1873910-C91)..... <b>PF7994</b> Radial Seal O. Air (3532801-C1). <b>RS30090-FN</b> Radial Seal O. Air (3532799-C1). <b>RS4636 +</b> Opt. Radial Seal I. Air (3532800-C1)..... <b>RS4637</b> Cab Air (6 5/32 In. Width) (3839141-C1)..... <b>PA5679</b> Cab Air (7 1/4 In. Width) (2506656-C1)..... <b>PA4985</b> Air Dryer (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b> Air Dryer (AD-IP System) (Bendix 65624)..... <b>BA5373</b> Air Dryer (AD-SP System) (Bendix 109994)..... <b>BA5374 +</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Steering (2503221-C1)..... <b>BT9388</b> Some Differential (Meritor 3280-V-8394)..... <b>B233</b>
7400 w/Cummins ISL 8.9 (8.9L) Eng. (2020) Lube (5444774)..... <b>B40142</b> Fuel (5303743)..... <b>BF63000</b>	7400 w/DT466 (7.6L) Eng. (To 2005) Lube (1833121-C1)..... <b>B7030</b> Fuel/Water Separator (1878042-C91)..... <b>PF7978</b> Fuel (1822588-C1)..... <b>BF7629 +</b> Radial Seal O. Air (3532801-C1). <b>RS30090-FN</b> Radial Seal O. Air (3532799-C1). <b>RS4636 +</b> Radial Seal I. Air (3532800-C1)... <b>RS4637</b> Cab Air (2506656-C1)..... <b>PA4985</b> Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b> Air Dryer (AD-SP System) (Bendix 109994)..... <b>BA5374 +</b> Air Dryer (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b> Trans. Ele. (2 In. Kit) (Allison 29526899)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29526898)..... <b>PT9415-MPG KIT</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Steering (2503221-C1)..... <b>BT9388</b> Some Differential (Meritor 3280-V-8394)..... <b>B233</b>	
7400 w/Cummins ISM 10.8 (10.8L) Eng. Dual-Flow Lube (3101869)..... <b>BD7154 +</b> Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> Fuel/Water Separator (3329289). <b>BF1259</b> Crankcase Breather (3683918)... <b>CV15000</b> Coolant (w/o Chemicals) (Fleetguard WF2127)..... <b>B5087</b> Coolant (Controlled Release BTA+) (Fleetguard WF2121)..... <b>BW5250</b> Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> Coolant (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b>		
7400 w/Cummins ISX 15.0 (14.9L) Eng. (2019) Dual-Flow Lube (4367100)..... <b>BD50000</b> Fuel/Water Separator (4080114C2)..... <b>BF46169-O</b> Fuel (5365988)..... <b>BF46129 +</b> Radial Seal Air (3532799C1)..... <b>RS4636</b> Cab Air (3839141C1)..... <b>PA5679</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Trans. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>		
7400 w/Cummins L9 (9.0L) Eng. (2018) Lube (3401544)..... <b>B40142</b> Fuel/Water Separator (2514003C1)..... <b>BF46181-O</b> Fuel (5303743)..... <b>BF63000</b> Radial Seal O. Air (3532799C1).. <b>RS4636</b> Radial Seal I. Air (3532800C1).... <b>RS4637</b>	7400 w/DT466 (7.6L) Eng. (2005-on) Dual-Flow Lube (1842639C-91).. <b>BD7250</b> Fuel/Water Separator (1842638-C92)..... <b>PF7779</b> Fuel/Water Separator (1878042-C91)..... <b>PF7978</b> Radial Seal O. Air (3532801-C1). <b>RS30090-FN</b> Radial Seal O. Air (3532799-C1). <b>RS4636 +</b> Radial Seal I. Air (3532800-C1)... <b>RS4637</b> Cab Air (2506656-C1)..... <b>PA4985</b> Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b> Air Dryer (AD-SP System) (Bendix 109994)..... <b>BA5374 +</b>	7400 w/MaxxForce DT (7.6L) Eng. (2012-on) Lube (1889124-C91)..... <b>B7503</b> Fuel/Water Separator (1878042-C91)..... <b>PF7978</b> Fuel/Water Separator (1822638-C91)..... <b>PF7779</b> Fuel Strainer (1873910-C91)..... <b>PF7994</b> Radial Seal O. Air (3532801-C1). <b>RS30090-FN</b> Radial Seal O. Air (3532799-C1). <b>RS4636 +</b> Opt. Radial Seal I. Air (3532800-C1)..... <b>RS4637</b> Cab Air (6 5/32 In. Width) (3839141-C1)..... <b>PA5679</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
7400 w/MaxxForce DT (7.6L) Eng. (2012-on) (Cont'd)	7400 WorkStar w/DT530 (8.7L) Eng. (Cont'd)	7400 WorkStar w/MaxxForce 9 Eng. (Cont'd)
<b>Cab Air</b> (7 1/4 In. Width) (2506656-C1)..... <b>PA4985</b>	<b>Radial Seal O. Air</b> (3532799-C1)... <b>RS4636 +</b>	<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>
<b>Cab Air</b> (CFFN6100)..... <b>PA30260</b>	<b>Radial Seal I. Air</b> (3532800-C1)... <b>RS4637</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>	<b>Cab Air</b> (2506656-C1)..... <b>PA4985</b>	<b>Air Dryer</b> (AD-SP System) (Bendix 109994)..... <b>BA5374 +</b>
<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Air Dryer</b> (AD-SP System) (Bendix 109994)..... <b>BA5374 +</b>	<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Steering</b> (2503221-C1)..... <b>BT9388</b>
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Steering</b> (2503221-C1)..... <b>BT9388</b>	
<b>Steering</b> (2503221-C1)..... <b>BT9388</b>	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	
<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>		
7400 w/N9 (9.3L) Eng. (2015-18)	7400 WorkStar w/DT570 (9.3L) Eng.	7400 WorkStar w/MaxxForce 9 Eng. (2012-on)
<b>Lube</b> (1884508C2)..... <b>B7503</b>	<b>10 11/32 In. Dual-Flow Lube</b> (1842543-C1)..... <b>BD7252</b>	<b>Dual-Flow Lube</b> (1841606-C1).... <b>BD7250</b>
<b>Fuel/Water Separator</b> (1878042C93)..... <b>PF7978</b>	<b>14 7/32 In. Dual-Flow Lube</b> (1842639-C91)..... <b>BD7250</b>	<b>Oil Cooler Lube</b> (1822731-C1).... <b>B7039</b>
<b>Radial Seal O. Air</b> (3532799C1).. <b>RS4636 +</b>	<b>Fuel/Water Separator Ele.</b> (1842638-C91)..... <b>PF7779</b>	<b>Lube</b> (1889124-C91)..... <b>B7503</b>
<b>Radial Seal I. Air</b> (3532800C1).... <b>RS4637</b>	<b>Radial Seal O. Air</b> (3532799-C1)... <b>RS4636 +</b>	<b>Lube</b> (1885920C2)..... <b>B40053</b>
<b>Cab Air</b> (3839141C1)..... <b>PA5679</b>	<b>Radial Seal I. Air</b> (3532800-C1)... <b>RS4637</b>	<b>Centrifugal Lube</b> (2606467-C92) <b>BC7485 +</b>
<b>Cab Air</b> (Optional) (CFFN6100).... <b>PA30260</b>	<b>Air Dryer</b> (AD-SP System) (Bendix 109994)..... <b>BA5374 +</b>	<b>Fuel/Water Separator</b> (1878042-C92)..... <b>PF7978</b>
<b>Air Dryer</b> (Bendix 107794)..... <b>BA5377</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Fuel Strainer</b> (1873910-C91)..... <b>PF7994</b>
<b>Air Dryer</b> (Bendix 109994)..... <b>BA5374 +</b>	<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>	<b>Single Radial Seal Air</b> (3532799-C1)..... <b>RS4636 +</b>
<b>Trans.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	<b>Crankcase Breather</b> ..... <b>CLN&amp;R</b>	<b>Radial Seal O. Air</b> (3532799-C1)... <b>RS4636 +</b>
<b>Trans.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29526899)..... <b>PT9416-MPG KIT</b>	<b>Radial Seal I. Air</b> (3532800-C1)... <b>RS4637</b>
<b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29526898)..... <b>PT9415-MPG KIT</b>	<b>Cab Air</b> (6 5/32 In. Width) (3839141-C1)..... <b>PA5679</b>
7400 w/N9 (9.3L) Eng. (2019)	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Cab Air</b> (7 1/4 In. Width) (3548705-C1)..... <b>PA4985</b>
<b>F-F Lube</b> (1884508C2)..... <b>B7503</b>	<b>Steering</b> (2503221-C1)..... <b>BT9388</b>	<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>
<b>Centrifugal Lube</b> (2606467C91).. <b>BC7485</b>	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
<b>Radial Seal Air</b> (3532799C1)..... <b>RS4636</b>		<b>Air Dryer</b> (AD-SP System) (Bendix 109994)..... <b>BA5374 +</b>
<b>Cab Air</b> (3839141C1)..... <b>PA5679</b>		<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b>		<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>		<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>		<b>Steering</b> (2503221-C1)..... <b>BT9388</b>
<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>		<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>
7400 WorkStar w/DT530 (8.7L) Eng.	7400 WorkStar w/MaxxForce 9 Eng.	7400 WorkStar w/MaxxForce 10 Eng.
<b>F-F Lube</b> ..... <b>B7030</b>	<b>Dual-Flow Lube</b> (1841606-C1).... <b>BD7250</b>	<b>Dual-Flow Lube</b> (1842639-C91).. <b>BD7250</b>
<b>Dual-Flow Lube</b> (1842639-C91).. <b>BD7250</b>	<b>Oil Cooler Lube</b> (1822731-C1).... <b>B7039</b>	<b>Lube</b> (1885920C2)..... <b>B40053</b>
<b>Fuel/Water Separator Ele.</b> (1842638-C91)..... <b>PF7779</b>	<b>Fuel/Water Separator</b> (1878042-C92)..... <b>PF7978</b>	<b>Lube</b> (1884508-C2)..... <b>B7503</b>
<b>Fuel/Water Separator Spin-on</b> (1677004-C91)..... <b>BF1345-O</b>	<b>Fuel Strainer</b> (1873910-C91)..... <b>PF7994</b>	<b>Fuel/Water Separator</b> (1878042-C91)..... <b>PF7978</b>
<b>Fuel Spin-on</b> ..... <b>BF7629 +</b>	<b>Single Radial Seal Air</b> (3532799-C1)..... <b>RS4636 +</b>	<b>Fuel Strainer</b> (1873910-C91)..... <b>PF7994</b>
	<b>Radial Seal O. Air</b> (3532799-C1)... <b>RS4636 +</b>	<b>Radial Seal O. Air</b> (3532799-C1)... <b>RS4636 +</b>
	<b>Radial Seal O. Air</b> (3532801-C1)... <b>RS30090-FN</b>	<b>Radial Seal I. Air</b> (3532800-C1)... <b>RS4637</b>
	<b>Radial Seal I. Air</b> (3532800-C1)... <b>RS4637</b>	<b>Radial Seal I. Air</b> (3532800-C1)... <b>RS4637</b>
	<b>Cab Air</b> (6 5/32 In. Width) (3839141-C1)..... <b>PA5679</b>	
	<b>Cab Air</b> (7 1/4 In. Width) (3548705-C1)..... <b>PA4985</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

**Trucks & Buses Applications** **BALDWIN FILTERS**

<b>INTERNATIONAL Trucks &amp; Buses (cont'd)</b>	<b>INTERNATIONAL Trucks &amp; Buses (cont'd)</b>	<b>INTERNATIONAL Trucks &amp; Buses (cont'd)</b>
7400 WorkStar w/MaxxForce 10 Eng. (Cont'd) <b>Cab Air</b> (31/32 In. Thick) (2506656-C1)..... <b>PA4985</b> <b>Cab Air</b> (1 3/16 In. Thick) (3839141-C1)..... <b>PA5679</b> <b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (2503221-C1)..... <b>BT9388</b> <b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	7500 w/Cummins ISL 8.9 (8.9L) Eng. (2019) <b>Lube</b> (3401544)..... <b>B40142</b> <b>Fuel/Water Separator</b> (4080114C2)..... <b>BF46169-O</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Radial Seal Air</b> (3532799C1)..... <b>RS4636</b> <b>Cab Air</b> (3839141C1)..... <b>PA5679</b> <b>Air Dryer</b> (Bendix R950011)..... <b>BA5374 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	7500 w/N10 (9.3L) Eng. (2019) (Cont'd) <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (5303604)..... <b>PE17000</b>
7500 w/Cummins ISL Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> <b>Radial Seal O. Air</b> (3532801C1)..... <b>RS30090-FN</b> <b>Radial Seal I. Air</b> (3532800C1)..... <b>RS4637</b> <b>Cab Air</b> (3839141C1)..... <b>PA5679</b> <b>Air Dryer</b> (Bendix 109994)..... <b>BA5374 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Diesel Exhaust Fluid</b> (5303604)..... <b>PE17000</b>	7500 w/Cummins ISL 8.9 (8.9L) Eng. (2020) <b>Lube</b> (5444774)..... <b>B40142</b> <b>Fuel</b> (5303743)..... <b>BF63000</b>	7500 w/DT466 (7.6L) Eng. <b>F-F Eng. Lube</b> (1819452C1)..... <b>B7030</b> <b>Fuel/Water Separator Ele.</b> (1842638C92)..... <b>PF7779</b> <b>Fuel</b> (625625C1)..... <b>BF984</b> <b>Fuel</b> (625627C1)..... <b>BF979 +</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (1820361C1)..... <b>BW5074</b>
7500 w/Cummins ISL 8.9 (8.9L) Eng. (2017) <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> <b>Radial Seal O. Air</b> (3532801C1)..... <b>RS30090-FN</b> <b>Radial Seal I. Air</b> (3532800C1)..... <b>RS4637</b> <b>Cab Air</b> (3839141C1)..... <b>PA5679</b> <b>Air Dryer</b> (Bendix 109994)..... <b>BA5374 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Diesel Exhaust Fluid</b> (5303604)..... <b>PE17000</b>	7500 w/Cummins L9 (9.0L) Eng. (2019) <b>Lube</b> (3401544)..... <b>B40142</b> <b>Fuel/Water Separator</b> (4080114C2)..... <b>BF46169-O</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Radial Seal Air</b> (3532799C1)..... <b>RS4636</b> <b>Cab Air</b> (3839141C1)..... <b>PA5679</b> <b>Air Dryer</b> (Bendix R950011)..... <b>BA5374 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	7500 w/DT530 (8.7L) Eng. <b>F-F Lube</b> (1819452C1)..... <b>B7030</b> <b>Dual-Flow Lube</b> (1842639C91)..... <b>BD7250</b> <b>Fuel/Water Separator</b> (1842638C91)..... <b>PF7779</b> <b>Fuel</b> (1820479C1)..... <b>BF7531</b> <b>Coolant</b> (1822313C1)..... <b>BW5082</b>
7500 w/Cummins ISL 8.9 (8.9L) Eng. (2018) <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309</b> <b>Fuel/Water Separator</b> (2514003C1)..... <b>BF46181-O</b> <b>Fuel</b> (Fleetguard FF63008)..... <b>BF63000</b> <b>Radial Seal Air</b> (Fleetguard AF25707)..... <b>RS4636</b> <b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b> <b>Trans.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (Fleetguard HF35476)..... <b>BT9388</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (5303604)..... <b>PE17000</b>	7500 w/N10 (9.3L) Eng. (2018) <b>Lube</b> (1884508C2)..... <b>B7503</b> <b>Fuel/Water Separator</b> (1878042C93)..... <b>PF7978</b> <b>Radial Seal O. Air</b> (3532799C1)..... <b>RS4636</b> <b>Radial Seal I. Air</b> (3532800C1)..... <b>RS4637</b> <b>Cab Air</b> (3839141C1)..... <b>PA5679</b> <b>Cab Air</b> (Optional) (CFFN6100)..... <b>PA30260</b> <b>Air Dryer</b> (Bendix 109994)..... <b>BA5374 +</b> <b>Trans.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (2503221C1)..... <b>BT9388</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (Fleetguard UF101)..... <b>PE17000</b>	7500 WorkStar w/HT530 (8.7L) Eng. <b>Lube</b> (1833121-C1)..... <b>B7030</b> <b>Fuel/Water Separator</b> (1677004-C91)..... <b>BF1345-O</b> <b>Fuel</b> (1822588-C1)..... <b>BF7629 +</b> <b>Single Radial Seal Air</b> (3532799-C1)..... <b>RS4636 +</b> <b>Radial Seal O. Air</b> (3532801-C1)..... <b>RS30090-FN</b> <b>Radial Seal I. Air</b> (3532800-C1)..... <b>RS4637</b> <b>Cab Air</b> (3548705-C1)..... <b>PA4985</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (2503221-C1)..... <b>BT9388</b>
7500 w/Cummins ISL 8.9 (8.9L) Eng. (2018) <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309</b> <b>Fuel/Water Separator</b> (2514003C1)..... <b>BF46181-O</b> <b>Fuel</b> (Fleetguard FF63008)..... <b>BF63000</b> <b>Radial Seal Air</b> (Fleetguard AF25707)..... <b>RS4636</b> <b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b> <b>Trans.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (Fleetguard HF35476)..... <b>BT9388</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (5303604)..... <b>PE17000</b>	7500 w/N10 (9.3L) Eng. (2019) <b>F-F Lube</b> (1884508C2)..... <b>B7503</b> <b>Centrifugal Lube</b> (2606467C91)..... <b>BC7485</b> <b>Radial Seal Air</b> (3532799C1)..... <b>RS4636</b> <b>Cab Air</b> (3839141C1)..... <b>PA5679</b> <b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b>	7500 WorkStar w/HT570 (9.3L) Eng. <b>10 11/32 In. Dual-Flow Lube</b> (1842543-C1)..... <b>BD7252</b> <b>14 7/32 In. Dual-Flow Lube</b> (1842639-C91)..... <b>BD7250</b> <b>Fuel/Water Separator Ele.</b> (1842638-C91)..... <b>PF7779</b> <b>Radial Seal O. Air</b> (3532799-C1)..... <b>RS4636 +</b> <b>Radial Seal I. Air</b> (3532800-C1)..... <b>RS4637</b> <b>Cab Air</b> (2506656-C1)..... <b>PA4985</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-SP System) (Bendix 109994)..... <b>BA5374 +</b> <b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b> <b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b> <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
7500 WorkStar w/HT570 (9.3L) Eng. (Cont'd) Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (2503221-C1)..... <b>BT9388</b> <b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	7500 WorkStar w/MaxxForce 10 (9.3L) Eng. (To 2012) (Cont'd) <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (2503221-C1)..... <b>BT9388</b> <b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	7600 w/Cat C10 Eng. (Cont'd) <b>Radial Seal O. Air</b> (3551814-C1)..... <b>RS4862</b> <b>Opt. Radial Seal I. Air</b> (3551815-C1)..... <b>RS4863</b> <b>Cab Air</b> (2506656-C1)..... <b>PA4985</b> <b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (2503221-C1)..... <b>BT9388</b> <b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>
7500 WorkStar w/MaxxForce DT Eng. <b>Dual-Flow Lube</b> (1842639-C91).. <b>BD7250</b> <b>Fuel/Water Separator</b> (1878042-C91)..... <b>PF7978</b> <b>Fuel/Water Separator</b> (1822638-C91)..... <b>PF7779</b> <b>Fuel Strainer</b> (1873910-C91)..... <b>PF7994</b> <b>Radial Seal O. Air</b> (3532799-C1)..... <b>RS4636 +</b> <b>Radial Seal I. Air</b> (3532800-C1).... <b>RS4637</b> <b>Cab Air</b> (2506656-C1)..... <b>PA4985</b> <b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b> <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (2503221-C1)..... <b>BT9388</b> <b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	7500 WorkStar w/MaxxForce 10 (9.3L) Eng. (2012-on) <b>Lube</b> (1885920C2)..... <b>B40053</b> <b>Oil Cooler Lube</b> (1822731-C1).... <b>B7039</b> <b>Lube</b> (1889124-C91)..... <b>B7503</b> <b>Lube Centrifuge</b> (2606467-C91).... <b>BC7485 +</b> <b>Fuel/Water Separator</b> (1878042-C91)..... <b>PF7978</b> <b>Fuel Strainer</b> (1873910-C91)..... <b>PF7994</b> <b>Radial Seal O. Air</b> (3532799-C1).... <b>RS4636 +</b> <b>Radial Seal I. Air</b> (3532800-C1).... <b>RS4637</b> <b>Radial Seal O. Air</b> (3532801-C1).... <b>RS30090-FN</b> <b>Cab Air</b> (6 5/32 In. Width) (3839141-C1)..... <b>PA5679</b> <b>Cab Air</b> (7 1/4 In. Width) (2506656-C1)..... <b>PA4985</b> <b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (2503221-C1)..... <b>BT9388</b> <b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	7600 w/Cat C12 Eng. <b>F-F Lube</b> ..... <b>B99 +</b> <b>B-P Lube</b> ..... <b>B7577</b> <b>Fuel</b> ..... <b>BF7587 +</b> <b>Fuel</b> (3563465-C1)..... <b>BF596 +</b> <b>Single Radial Seal Air</b> (3551814-C1)..... <b>RS4862</b> <b>Radial Seal O. Air</b> (3551816-C1).... <b>RS5389-FN</b> <b>Radial Seal I. Air</b> (3551815-C1).... <b>RS4863</b> <b>Cab Air</b> (2506656C1)..... <b>PA4985</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (2503221-C1)..... <b>BT9388</b> <b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>
7500 WorkStar w/MaxxForce 9 Eng. <b>Lube</b> (1889124-C91)..... <b>B7503</b> <b>Lube Centrifuge</b> (2606467-C91).... <b>BC7485 +</b> <b>Fuel/Water Separator</b> (1878042-C91)..... <b>PF7978</b> <b>Radial Seal Air</b> (3532799-C1)..... <b>RS4636 +</b> <b>Cab Air</b> (6 5/32 In. Width) (3839141-C1)..... <b>PA5679</b> <b>Cab Air</b> (7 1/4 In. Width) (2506656-C1)..... <b>PA4985</b> <b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b> <b>Steering</b> (2503221-C1)..... <b>BT9388</b>	7500 WorkStar w/MaxxForce 10 (9.3L) Eng. (To 2012) <b>Dual-Flow Lube</b> (1842639-C91).. <b>BD7250</b> <b>Oil Cooler Lube</b> (1822731-C1).... <b>B7039</b> <b>Fuel/Water Separator</b> (1878042-C91)..... <b>PF7978</b> <b>Fuel Strainer</b> (1873910-C91)..... <b>PF7994</b> <b>Radial Seal O. Air</b> (3532799-C1).... <b>RS4636 +</b> <b>Radial Seal I. Air</b> (3532800-C1).... <b>RS4637</b> <b>Radial Seal O. Air</b> (3532801-C1).... <b>RS30090-FN</b> <b>Cab Air</b> (6 5/32 In. Width) (3839141-C1)..... <b>PA5679</b> <b>Cab Air</b> (7 1/4 In. Width) (2506656-C1)..... <b>PA4985</b> <b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	7600 w/Cummins M11 Eng. <b>Dual-Flow Lube</b> ..... <b>BD103 +</b> <b>Fuel/Water Separator</b> ..... <b>BF1259</b> <b>Cab Air</b> (2506656C1)..... <b>PA4985</b>
7500 WorkStar w/MaxxForce 10 (9.3L) Eng. (To 2012) <b>Dual-Flow Lube</b> (1842639-C91).. <b>BD7250</b> <b>Oil Cooler Lube</b> (1822731-C1).... <b>B7039</b> <b>Fuel/Water Separator</b> (1878042-C91)..... <b>PF7978</b> <b>Fuel Strainer</b> (1873910-C91)..... <b>PF7994</b> <b>Radial Seal O. Air</b> (3532799-C1).... <b>RS4636 +</b> <b>Radial Seal I. Air</b> (3532800-C1).... <b>RS4637</b> <b>Radial Seal O. Air</b> (3532801-C1).... <b>RS30090-FN</b> <b>Cab Air</b> (6 5/32 In. Width) (3839141-C1)..... <b>PA5679</b> <b>Cab Air</b> (7 1/4 In. Width) (2506656-C1)..... <b>PA4985</b> <b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	7500 WorkStar w/N10 (9.3L) Eng. <b>Lube</b> (1884508C2)..... <b>B7503</b> <b>Fuel/Water Separator</b> (1878042C93)..... <b>PF7978</b> <b>Radial Seal O. Air</b> (3532801C1).. <b>RS30090-FN</b> <b>Radial Seal I. Air</b> (3532800C1).... <b>RS4637</b> <b>Cab Air</b> (3839141C1)..... <b>PA5679</b> <b>Cab Air</b> (Optional) (CFFN6100).... <b>PA30260</b> <b>Air Dryer</b> (Bendix 109994)..... <b>BA5374 +</b> <b>Trans.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (2503221C1)..... <b>BT9388</b>	7600 w/IHC DT466 Eng. <b>F-F Lube</b> (1808896-C1)..... <b>B299 +</b> <b>F-F Lube</b> (1811953-C1)..... <b>B309</b> <b>Air</b> (1661755-C91)..... <b>PA2521</b> <b>Air</b> (1661756-C91)..... <b>[2] PA2521</b> <b>3 31/32 In. Steering</b> (Fleetguard HF6162)..... <b>P106-HD</b> <b>4 5/32 In. Steering</b> (1681202-C91)..... <b>PT8407</b>
7500 WorkStar w/MaxxForce 10 (9.3L) Eng. (To 2012) <b>Dual-Flow Lube</b> (1842639-C91).. <b>BD7250</b> <b>Oil Cooler Lube</b> (1822731-C1).... <b>B7039</b> <b>Fuel/Water Separator</b> (1878042-C91)..... <b>PF7978</b> <b>Fuel Strainer</b> (1873910-C91)..... <b>PF7994</b> <b>Radial Seal O. Air</b> (3532799-C1).... <b>RS4636 +</b> <b>Radial Seal I. Air</b> (3532800-C1).... <b>RS4637</b> <b>Radial Seal O. Air</b> (3532801-C1).... <b>RS30090-FN</b> <b>Cab Air</b> (6 5/32 In. Width) (3839141-C1)..... <b>PA5679</b> <b>Cab Air</b> (7 1/4 In. Width) (2506656-C1)..... <b>PA4985</b> <b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	7600 w/DT570 (9.3L) Eng. <b>Dual-Flow Lube</b> (1842543C1)..... <b>BD7252</b> <b>Dual-Flow Lube</b> (1842639C91).... <b>BD7250</b> <b>B-P Lube</b> (1842825C91)..... <b>BC7394</b> <b>Fuel/Water Separator</b> (1842638C91)..... <b>PF7779</b> <b>Radial Seal O. Air</b> (3551814C1).... <b>RS4862</b> <b>Radial Seal I. Air</b> (3551815C1).... <b>RS4863</b> <b>Cab Air</b> (2506656C1)..... <b>PA4985</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-SP System) (Bendix 109994)..... <b>BA5374 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (2503221C1)..... <b>BT9388</b> <b>Some Differential</b> (Meritor 3280V8394)..... <b>B233</b>	
7600 w/Cat C10 Eng. <b>F-F Lube</b> ..... <b>B99 +</b> <b>B-P Lube</b> ..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (2503566-C1)..... <b>PF7680</b> <b>Fuel/Water Separator Ele.</b> (2588149-C1)..... <b>PF7748</b> <b>Fuel</b> ..... <b>BF7587 +</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
7600 w/N13 (12.4L) Eng. (2019) <b>Lube</b> (3007498C94)..... <b>P7494</b> <b>Fuel/Water Separator</b> (Fleetguard FS19765)..... <b>PF7930</b> <b>Fuel/Water Separator</b> (3004473C93)..... <b>PF7986</b> <b>Radial Seal Air</b> (Fleetguard AF26103)..... <b>RS4862</b> <b>Cab Air</b> (3839141C1)..... <b>PA5679</b> <b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>	7600 WorkStar w/Cat C13 Eng. (Cont'd) <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (2503221-C1)..... <b>BT9388</b> <b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	7600 WorkStar w/MaxxForce 11 (10.5L) Eng. (To 2012) (Cont'd) <b>Steering</b> (2503221-C1)..... <b>BT9388</b>
7600 WorkStar w/Cat C11 Eng. <b>Lube</b> (1R1808)..... <b>B7299 +</b> <b>Fuel/Water Separator</b> (Fleetguard FS1006)..... <b>BF1262</b> <b>Fuel/Water Separator</b> (Fleetguard FS1216)..... <b>BF1216 +</b> <b>Fuel</b> (1R0749)..... <b>BF7587 +</b> <b>Radial Seal O. Air</b> (3551814C1).. <b>RS4862</b> <b>Radial Seal I. Air</b> (3551815C1).... <b>RS4863</b> <b>Cab Air</b> (2506656C1)..... <b>PA4985</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-SP System) (Bendix 109994)..... <b>BA5374 +</b> <b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (2503221C1)..... <b>BT9388</b> <b>Some Differential</b> (Meritor 3280V8394)..... <b>B233</b>	7600 WorkStar w/Cummins ISM (10.8L) Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154 +</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (3329289). <b>BF1259</b> <b>Radial Seal O. Air</b> (3551814-C1). <b>RS4862</b> <b>Radial Seal I. Air</b> (3551815-C1)... <b>RS4863</b> <b>Cab Air</b> (2506656-C1)..... <b>PA4985</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-SP System) (Bendix 109994)..... <b>BA5374 +</b> <b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b> <b>Crankcase Breather</b> (3683918).. <b>CV15000</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (2503221-C1)..... <b>BT9388</b> <b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	7600 WorkStar w/MaxxForce 11 (10.5L) Eng. (2012-on) <b>Lube</b> (3007498C92)..... <b>P7494</b> <b>Fuel/Water Separator Ele.</b> (2588149-C1)..... <b>PF7748</b> <b>Fuel/Water Separator</b> (3004473-C91)..... <b>PF7986</b> <b>P. Fuel</b> ..... <b>PF7939 +</b> <b>Radial Seal O. Air</b> (3551814-C1). <b>RS4862</b> <b>Radial Seal I. Air</b> (3551815-C1)... <b>RS4863</b> <b>Single Radial Seal Air</b> (3551816-C1)..... <b>RS5389-FN</b> <b>Cab Air</b> (3839141-C1)..... <b>PA5679</b> <b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (2503221-C1)..... <b>BT9388</b>
7600 WorkStar w/Cat C13 Eng. <b>Lube</b> (1R1808)..... <b>B7299 +</b> <b>Fuel/Water Separator</b> (Fleetguard FS19624)..... <b>PF7748</b> <b>Fuel/Water Separator</b> (Fleetguard FS19536)..... <b>PF7894</b> <b>Fuel</b> (1R0749)..... <b>BF7587 +</b> <b>S. Fuel</b> (3563465-C1)..... <b>BF596 +</b> <b>Radial Seal O. Air</b> (3551814-C1). <b>RS4862</b> <b>Radial Seal I. Air</b> (3551815-C1)... <b>RS4863</b> <b>Single Radial Seal Air</b> (3551816-C1)..... <b>RS5389-FN</b> <b>Cab Air</b> (2506656-C1)..... <b>PA4985</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-SP System) (Bendix 109994)..... <b>BA5374 +</b> <b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b> <b>Crankcase Breather</b> (2007-on) (296-8325)..... <b>CV15008</b>	7600 WorkStar w/MaxxForce 13 Eng. <b>Lube</b> (2007 Emissions) (3006874C91)..... <b>P7508</b> <b>Lube</b> (2010 Emissions) (3007498C92)..... <b>P7494</b> <b>Fuel/Water Separator Ele.</b> (2588149-C1)..... <b>PF7748</b> <b>Fuel/Water Separator</b> (3004473-C91)..... <b>PF7986</b> <b>P. Fuel</b> ..... <b>PF7939 +</b> <b>Radial Seal O. Air</b> (3551814-C1). <b>RS4862</b> <b>Radial Seal I. Air</b> (3551815-C1)... <b>RS4863</b> <b>Single Radial Seal Air</b> (3551816-C1)..... <b>RS5389-FN</b> <b>Cab Air</b> (3548705-C1)..... <b>PA4985</b> <b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (2503221-C1)..... <b>BT9388</b>	7600 WorkStar w/MaxxForce 13 Eng. <b>Lube</b> (2007 Emissions) (3006874C91)..... <b>P7508</b> <b>Lube</b> (2010 Emissions) (3007498-C94)..... <b>P7494</b> <b>Opt. Lube Centrifuge</b> (2012-on) (2606467-C91)..... <b>BC7485 +</b> <b>Fuel/Water Separator Ele.</b> (2588149-C1)..... <b>PF7748</b> <b>Fuel/Water Separator</b> (3004473-C93)..... <b>PF7986</b> <b>Opt. P. Fuel</b> ..... <b>PF7939 +</b> <b>Radial Seal O. Air</b> (3551816-C1). <b>RS5389-FN</b> <b>Radial Seal I. Air</b> (3551815-C1)... <b>RS4863</b> <b>Cab Air</b> (31/32 In. Thick) (3548705-C1)..... <b>PA4985</b> <b>Cab Air</b> (1 3/16 In. Thick) (3839141-C1)..... <b>PA5679</b> <b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (2503221-C1)..... <b>BT9388</b>
	7600 WorkStar w/N13 Eng. <b>Lube Ele.</b> (3007498-C94)..... <b>P7494</b> <b>Lube Centrifuge</b> (2606467-C91). <b>BC7485 +</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (2611236C1)..... <b>BF46018-O</b> <b>Fuel/Water Separator</b> (w/Drain) (2611236C1)..... <b>BF1281</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
7600 WorkStar w/N13 Eng. (Cont'd)	7700 WorkStar w/Cat C11 Eng. (Cont'd)	7700 WorkStar w/Cummins ISM (10.8L) Eng. (Cont'd)
<b>Fuel/Water Separator</b> (3004473-C93).....	<b>Opt. Trans. Spin-on</b> (Fuller 17237).....	<b>Opt. Trans. Spin-on</b> (Fuller 17237).....
PF7986	B2 +	B2 +
<b>Fuel Screen</b> (3004474-C92).....	<b>Steering</b> (2503221-C1).....	<b>Steering</b> (2503221-C1).....
PF7939 +	BT9388	BT9388
<b>Single Radial Seal Air</b> (3551814C1).....	<b>Some Differential</b> (Meritor 3280-V-8394).....	<b>Some Differential</b> (Meritor 3280-V-8394).....
RS4862	B233	B233
<b>Radial Seal O. Air</b> (3551816-C1).....	7700 WorkStar w/Cat C13 Eng.	7700 WorkStar w/MaxxForce 13 Eng.
RS5389-FN	<b>Lube</b> (1R1808).....	<b>Lube</b> (2007 Emissions) (3006874C91).....
RS4863	B7299 +	P7508
<b>Radial Seal I. Air</b> (3551815-C1)...	<b>Fuel Spin-on</b> (3563465-C1).....	<b>Lube</b> (2010 Emissions) (3007498C92).....
PA5679	BF596 +	P7494
<b>Cab Air</b> (3839141-C1).....	<b>Fuel Spin-on</b> (1R0749).....	<b>Fuel/Water Separator</b> (2588149-C1).....
PA30260	BF7587 +	PF7748
<b>Cab Air</b> (Optional) (CFFN6100)....	<b>Radial Seal O. Air</b> (3551814-C1).....	<b>Fuel/Water Separator</b> (3004473-C91).....
BA5374 +	RS4862	PF7986
<b>Air Dryer</b> (Bendix 5008414).....	<b>Some Radial Seal I. Air</b> (3551815-C1).....	<b>P. Fuel</b> (3004474-C91).....
<b>Trans.</b> (2 In. Kit) (Allison 29548987).....	RS4863	PF7939 +
PT9416-MPG KIT	<b>Cab Air</b> (2506656-C1).....	RS4862
<b>Trans.</b> (4 In. Kit) (Allison 29548988).....	PA4985	RS4863
PT9415-MPG KIT	<b>Air Dryer</b> (AD-SP System) (Bendix 109994).....	PA4985
<b>Trans. Spin-on</b> (Fuller 4304827)...	BA5374 +	<b>Air Dryer</b> (AD-9 System) (Bendix 107796).....
BT223	BA5377	BA5377
<b>Opt. Trans. Spin-on</b> (Fuller 17237).....	<b>Air Dryer</b> (AD-9 System) (Bendix 107796).....	<b>Air Dryer</b> (Wabco R950011).....
B2 +	BA5377	BA5374 +
<b>Steering</b> (2503221-C1).....	<b>Air Dryer</b> (System Saver 1200) (Wabco R950011).....	BT9388
BT9388	BA5374 +	BT223
<b>Diesel Exhaust Fluid</b> (5303604)...	<b>Crankcase Breather</b> (2007-on) (296-8325).....	BT9388
PE17000	CV15008	<b>Steering</b> (2503221-C1).....
7700 w/HT570 (9.3L) Eng.	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493).....	B233
<b>Dual-Flow Lube</b> (1842543C1).....	PT9416-MPG KIT	7700 WorkStar w/Cummins ISM (10.8L) Eng.
BD7252	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494).....	<b>Dual-Flow Lube</b> (Fleetguard LF9001).....
<b>Dual-Flow Lube</b> (1842639C91)...	PT9415-MPG KIT	BD7154 +
BD7250	<b>Opt. Trans. Spin-on</b> (Fuller 17237).....	<b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN).....
<b>B-P Lube</b> (1842825C91).....	B2 +	BD50000
BC7394	<b>Steering</b> (2503221-C1).....	<b>Fuel/Water Separator Ele.</b> (2588149-C1).....
<b>Fuel/Water Separator</b> (1842638C91).....	BT9388	PF7748
PF7779	<b>Some Differential</b> (Meritor 3280-V-8394).....	<b>Fuel/Water Separator Spin-on</b> (3329289).....
<b>Radial Seal O. Air</b> (3551814C1)...	B233	BF1259
RS4862	7700 WorkStar w/Cummins ISM (10.8L) Eng.	RS4862
<b>Radial Seal I. Air</b> (3551815C1)...	<b>Dual-Flow Lube</b> (Fleetguard LF9001).....	RS5389-FN
RS4863	BD7154 +	RS4863
<b>Cab Air</b> (2506656C1).....	<b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN).....	PA4985
PA4985	BD50000	<b>Air Dryer</b> (AD-SP System) (Bendix 109994).....
<b>Air Dryer</b> (AD-9 System) (Bendix 107796).....	<b>Fuel/Water Separator Ele.</b> (2588149-C1).....	BA5374 +
BA5377	PF7748	BA5377
<b>Air Dryer</b> (AD-SP System) (Bendix 109994).....	<b>Fuel/Water Separator Spin-on</b> (3329289).....	BA5374 +
BA5374 +	BF1259	CV15000
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493).....	<b>Radial Seal O. Air</b> (3551814-C1).....	BW5071
PT9416-MPG KIT	<b>Radial Seal O. Air</b> (3551816-C1).....	<b>Coolant</b> (Fleetguard WF2071).....
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494).....	RS4863	B5090
PT9415-MPG KIT	<b>Cab Air</b> (2506656-C1).....	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493).....
<b>Opt. Trans. Spin-on</b> (Fuller 17237).....	PA4985	PT9416-MPG KIT
B2 +	<b>Air Dryer</b> (AD-SP System) (Bendix 109994).....	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494).....
<b>Steering</b> (2503221C1).....	BA5374 +	PT9415-MPG KIT
BT9388	BA5377	
<b>Some Differential</b> (Meritor 3280V8394).....	<b>Air Dryer</b> (AD-9 System) (Bendix 107796).....	
B233	BA5377	
7700 WorkStar w/Cat C11 Eng.	<b>Air Dryer</b> (System Saver 1200) (Wabco R950011).....	
<b>Lube</b> (1R1808).....	BA5374 +	
B7299 +	<b>Crankcase Breather</b> (3683918)...	
<b>Fuel</b> (1R0749).....	CV15000	
BF7587 +	<b>Coolant</b> (w/o Chemicals) (4920476).....	
<b>Fuel</b> (Fleetguard FF202).....	BW5071	
BF596 +	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493).....	
<b>Radial Seal O. Air</b> (3551814-C1).....	PT9416-MPG KIT	
RS4862	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494).....	
<b>Radial Seal I. Air</b> (3551815-C1)...	PT9415-MPG KIT	
RS4863		
<b>Cab Air</b> (2506656-C1).....		
PA4985		
<b>Air Dryer</b> (AD-SP System) (Bendix 109994).....		
BA5374 +		
<b>Air Dryer</b> (AD-9 System) (Bendix 107796).....		
BA5377		
<b>Air Dryer</b> (System Saver 1200) (Wabco R950011).....		
BA5374 +		
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493).....		
PT9416-MPG KIT		
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494).....		
PT9415-MPG KIT		
		8100 w/Cat 3176 (10.3L) Eng. (To 1993)
		<b>Lube</b> .....
		B99 +
		<b>Opt. B-P Lube</b> (1W8845).....
		B7577
		<b>Fuel/Water Separator</b> (Fleetguard FS1212).....
		BF1212 +
		<b>P. Fuel Ele.</b> (9M2342).....
		[2] PF935
		<b>Fuel Spin-on</b> .....
		BF614 +
		<b>O. Air</b> (1674320-C2).....
		PA2525
		<b>I. Air</b> (1674319-C2).....
		PA2526
		<b>O. Air</b> (476741-C1).....
		PA2521
		<b>I. Air</b> (Fleetguard AF987).....
		PA2522
		<b>Air Dryer</b> (Bendix 107796).....
		BA5377
		8100 w/Cat 3176 (10.3L) Eng. (1994-on)
		<b>Lube</b> .....
		B99 +
		<b>Opt. B-P Lube</b> (1W8845).....
		B7577
		<b>Fuel/Water Separator</b> (Fleetguard FS1212).....
		BF1212 +
		<b>P. Fuel Ele.</b> (9M2342).....
		[2] PF935
		<b>Fuel Spin-on</b> .....
		BF614 +
		<b>O. Air</b> (1674320-C2).....
		PA2525
		<b>I. Air</b> (1674319-C2).....
		PA2526
		<b>O. Air</b> (476741-C1).....
		PA2521
		<b>I. Air</b> (Fleetguard AF987).....
		PA2522
		<b>Air Dryer</b> (Bendix 107796).....
		BA5377

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
8100 w/Cat 3176 (10.3L) Eng. (1994-on) (Cont'd) <b>Coolant</b> (w/Chemical) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134 +</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (w/Gasket) (279294-C92)..... <b>PT903</b> <b>Steering</b> (w/o Gasket) (279294-C92)..... <b>PT951</b> <b>Steering</b> (1691121-C1)..... <b>P106-HD</b>	8100 w/Cummins M11 (10.8L) Eng. (1994-on) <b>Dual-Flow Lube</b> (Std. Vers.) (3318853)..... <b>BD103 +</b> <b>Dual-Flow Lube</b> (High Velocity) (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel/Water Separator</b> (3329289)..... <b>BF1259</b> <b>Fuel/Water Separator</b> (Fleetguard FF105D)..... <b>BF957-D +</b> <b>Fuel/Water Separator</b> (w/Drain) (Fleetguard FS19513)..... <b>BF5813 +</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (Fleetguard FS19513).... <b>BF5813-O +</b> <b>Fuel/Water Separator</b> (Closed End) (3843447)..... <b>BF1282 +</b> <b>Fuel/Water Separator</b> (Open End for Bowl)..... <b>BF1282-O +</b> <b>Single Air</b> (1661755-C91)..... <b>PA2521</b> <b>O. Air</b> (1674320-C2)..... <b>PA2525</b> <b>I. Air</b> (1674319-C2)..... <b>PA2526</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (w/Chemicals) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134 +</b> <b>Coolant</b> (Controlled Release) (Nalcool NF2088)..... <b>BW5200</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>2 25/32 In. Steering</b> (279294-C92)..... <b>PT903</b> <b>3 In. Steering</b> (1696766-C1)..... <b>P7178</b> <b>3 31/32 In. Steering</b> (1691121-C1)..... <b>P106-HD</b>	8100 w/Cummins M11 (10.8L) Eng. (To 1994) (Cont'd) <b>Coolant</b> (Controlled Release) (Nalcool NF2088)..... <b>BW5200</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>2 25/32 In. Steering</b> (279294-C92)..... <b>PT903</b> <b>3 In. Steering</b> (1696766-C1)..... <b>P7178</b> <b>3 31/32 In. Steering</b> (1691121-C1)..... <b>P106-HD</b>
8100 w/Cat 3406 (14.6L) Eng. <b>Lube</b> (Std. Version) (1R0716)..... <b>B99 +</b> <b>Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> <b>Fuel/Water Separator</b> (3329289)..... <b>BF1259</b> <b>Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (Standard Vers.) (4N5823)..... <b>BF614 +</b> <b>Fuel Spin-on</b> (High Efficiency Vers.)..... <b>BF7587 +</b>	8100 w/Cummins M11 (10.8L) Eng. (To 1994) <b>Dual-Flow Lube</b> (Std. Vers.) (3318853)..... <b>BD103 +</b> <b>Dual-Flow Lube</b> (High Velocity) (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel/Water Separator</b> (3329289)..... <b>BF1259</b> <b>Fuel/Water Separator</b> (Fleetguard FF105D)..... <b>BF957-D +</b> <b>Fuel/Water Separator</b> (w/Drain) (Fleetguard FS19513)..... <b>BF5813 +</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (Fleetguard FS19513).... <b>BF5813-O +</b> <b>Fuel/Water Separator</b> (Closed End) (3843447)..... <b>BF1282 +</b> <b>Fuel/Water Separator</b> (Open End for Bowl)..... <b>BF1282-O +</b> <b>Single Air</b> (1661755-C91)..... <b>PA2521</b> <b>O. Air</b> (1674320-C2)..... <b>PA2525</b> <b>I. Air</b> (1674319-C2)..... <b>PA2526</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (w/Chemicals) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134 +</b> <b>Coolant</b> (Controlled Release) (Nalcool NF2088)..... <b>BW5200</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>2 25/32 In. Steering</b> (279294-C92)..... <b>PT903</b> <b>3 In. Steering</b> (1696766-C1)..... <b>P7178</b> <b>3 31/32 In. Steering</b> (1691121-C1)..... <b>P106-HD</b>	8100 w/Cummins N14 (14.0L) Eng. (To 1994) <b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Fuel</b> (154789)..... <b>BF957-D +</b> <b>O. Air</b> (1674320C2)..... <b>PA2525</b> <b>I. Air</b> (1674319C2)..... <b>PA2526</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (w/Chemicals) (Fleetguard WF2074)..... <b>BW5074</b> <b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134 +</b> <b>Coolant</b> (Controlled Release) (Nalcool NF2088)..... <b>BW5200</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>2 25/32 In. Steering</b> (Fleetguard LF634)..... <b>PT903</b> <b>3 31/32 In. Steering</b> (Fleetguard HF6162)..... <b>P106-HD</b>
8100 w/Cat C10 Eng. <b>F-F Lube</b> ..... <b>B99 +</b> <b>B-P Lube</b> ..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (2588149-C1)..... <b>PF7748</b> <b>Fuel/Water Separator Ele.</b> (2503566-C1)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> ..... <b>BF5812</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1212)..... <b>BF1212 +</b> <b>Fuel Spin-on</b> ..... <b>BF7587 +</b> <b>O. Air</b> (476741-C1)..... <b>PA2521</b> <b>I. Air</b> ..... <b>PA2522</b> <b>Cab Air</b> (1696834-C1)..... <b>PA5691</b> <b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (Controlled Release) (2014314-C1)..... <b>BW5200</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (1696766-C1)..... <b>P7178</b>	8100 w/Cummins M11 (10.8L) Eng. (To 1994) <b>Dual-Flow Lube</b> (Std. Vers.) (3318853)..... <b>BD103 +</b> <b>Dual-Flow Lube</b> (High Velocity) (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel/Water Separator</b> (3329289)..... <b>BF1259</b> <b>Fuel/Water Separator</b> (Fleetguard FF105D)..... <b>BF957-D +</b> <b>Fuel/Water Separator</b> (w/Drain) (Fleetguard FS19513)..... <b>BF5813 +</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (Fleetguard FS19513).... <b>BF5813-O +</b> <b>Fuel/Water Separator</b> (Closed End) (3843447)..... <b>BF1282 +</b> <b>Fuel/Water Separator</b> (Open End for Bowl)..... <b>BF1282-O +</b> <b>Single Air</b> (1661755-C91)..... <b>PA2521</b> <b>O. Air</b> (1674320-C2)..... <b>PA2525</b> <b>I. Air</b> (1674319-C2)..... <b>PA2526</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (w/Chemicals) (Fleetguard WF2074)..... <b>BW5074</b> <b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134 +</b>	8100 w/Cummins N14 (14.0L) Eng. (1994-on) <b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Fuel</b> (154789)..... <b>BF957-D +</b> <b>O. Air</b> (1674320C2)..... <b>PA2525</b> <b>I. Air</b> (1674319C2)..... <b>PA2526</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (w/Chemicals) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134 +</b> <b>Coolant</b> (Controlled Release) (Nalcool NF2088)..... <b>BW5200</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>2 25/32 In. Steering</b> (Fleetguard LF634)..... <b>PT903</b> <b>3 31/32 In. Steering</b> (Fleetguard HF6162)..... <b>P106-HD</b>
8100 w/Cat C12 (12.0L) Eng. <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99 +</b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> <b>B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (Standard Vers.) (4N5823)..... <b>BF614 +</b> <b>Fuel Spin-on</b> (High Efficiency Vers.)..... <b>BF7587 +</b>	8100 w/Detroit Diesel Series 50 (8.5L) Eng. <b>Lube</b> (23530573)..... <b>[2] B495</b> <b>Fuel</b> (23530706)..... <b>BF5800 +</b> <b>O. Air</b> (1674320-C2)..... <b>PA2525</b> <b>Opt. I. Air</b> (1674319-C2)..... <b>PA2526</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>2 25/32 In. Steering</b> (279294-C92)..... <b>PT903</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
8100 w/Detroit Diesel Series 50 (8.5L) Eng. (Cont'd)	8100 w/DT530 (8.7L) Eng. (Cont'd)	8200 w/Cat 3176 Eng. (Cont'd)
3 In. Steering (1696766-C1)..... P7178	Steering (1696766-C1)..... P7178	Coolant (w/o Chemical)
3 31/32 In. Steering (1691121-C1)..... P106-HD	8100, 8200, 8300 w/Cummins ISM (10.8L) Eng.	(Fleetguard WF2077)..... B5134 +
8100 w/Detroit Diesel Series 55 (12.0L) Eng.	Dual-Flow Lube (Fleetguard LF9001)..... BD7154 +	Opt. Trans. (Fuller 17237)..... B2 +
Lube (23550401)..... B7135	Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... BD50000	Steering (w/Gasket) (279294-C92)..... PT903
Fuel (23530707)..... BF5810	Fuel/Water Separator Ele. (Fleetguard FS1029W)..... PF7680	Steering (w/o Gasket) (279294-C92)..... PT951
8100 w/Detroit Diesel Series 60 (11.1L) & (12.7L) Eng.	Fuel/Water Separator Ele. (2588149-C1)..... PF7748	Steering (1691121-C1)..... P106-HD
O. Air (1674320-C2)..... PA2525	Air (476741C1)..... PA2521	8200 w/Cat 3406E Eng.
Opt. I. Air (1674319-C2)..... PA2526	Cab Air (1696834-C1)..... PA5691	F-F Lube (1R0716)..... B99 +
Air Dryer (AD-9 System) (Bendix 107796)..... BA5377	Air Dryer (Wabco R950011)..... BA5374 +	F-F Lube (High Efficiency) (1R1808)..... B7299 +
Coolant (w/o Chemical) (Fleetguard WF2077)..... B5134 +	Air Dryer (AD-9 System) (Bendix 107796)..... BA5377	Fuel/Water Separator (Fleetguard FS1212)..... BF1212 +
Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071	Coolant (Fleetguard WF2071)..... BW5071	Fuel (1R0712)..... BF614 +
Coolant (w/12 Units BTA+) (Fleetguard WF2074)..... BW5074	Opt. Trans. (Fuller 17237)..... B2 +	Fuel (High Efficiency) (1R0749)..... BF7587 +
Coolant (Controlled Release) (Nalcool NF2088)..... BW5200	Steering (1696766C1)..... P7178	Single Air (1674320-C2)..... PA2525
2 25/32 In. Steering (Fleetguard LF634)..... PT903	8100, 8200, 8300 Series w/Cummins L10 (10.0L) Eng.	O. Air (1674320-C2)..... PA2525
3 31/32 In. Steering (Fleetguard HF6162)..... P106-HD	F-F Lube..... B196 +	I. Air (1674319-C2)..... PA2526
8100 w/DT466 (7.6L) Eng.	Dual-Flow Lube..... BD103 +	Air Dryer (AD-9 System) (Bendix 107796)..... BA5377
Lube (1819452-C1)..... B7030	B-P Lube..... B7577	Coolant (w/o Chemical) (Fleetguard WF2077)..... B5134 +
P. Fuel (1822588-C1)..... BF7629 +	Opt. Fuel/Water Separator..... BF1212 +	Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071
S. Fuel (Fleetguard FF5052)..... BF788	Fuel/Water Separator (Fleetguard FS1000)..... BF1259	Coolant (w/12 Units BTA+) (Fleetguard WF2074)..... BW5074
O. Air (1661756-C91)..... PA2521	Fuel Spin-on..... BF957-D +	Coolant (Controlled Release) (Nalcool NF2088)..... BW5200
Opt. I. Air (1661756-C91)..... PA2522	16 7/16 In. O. Air (476741-C1)..... PA2521	Opt. Trans. (Fuller 17237)..... B2 +
Cab Air (1696834-C1)..... PA5691	13 7/8 In. I. Air (482644-C1)..... PA2522	2 25/32 In. Steering (279294-C92)..... PT903
Air Dryer (AD-9 System) (Bendix 107796)..... BA5377	18 1/2 In. O. Air (1674320-C2)..... PA2525	3 In. Steering (1696766-C1)..... P7178
Coolant (w/4 Units BTA+) (1822313-C1)..... BW5082	15 7/8 In. I. Air (1674319-C2)..... PA2526	3 31/32 In. Steering (1691121-C1)..... P106-HD
Coolant (w/12 Units BTA+) (Fleetguard WF2074)..... BW5074	Air Dryer (AD-9 System) (Bendix 107796)..... BA5377	Some Rear Axle (Fleetguard LF689)..... B233
Coolant (w/o Chemical) (Fleetguard WF2101)..... B5134 +	Coolant (w/8 units BTA +)..... BW5073	8200 w/Cat C10 Eng.
Opt. Trans. (Fuller 17237)..... B2 +	Coolant (w/12 Units BTA+) (Fleetguard WF2074)..... BW5074	F-F Lube (1R0716)..... B99 +
Steering (1696766-C1)..... P7178	Opt. Trans. (Fuller 17237)..... B2 +	F-F Lube (High Efficiency) (1R1808)..... B7299 +
8100 w/DT530 (8.7L) Eng.	2 25/32 In. Steering (279294-C92)..... PT951	Fuel (1R1712)..... BF614 +
Lube (1819452-C1)..... B7030	3 In. Steering (1696766-C1)..... P7178	Fuel (High Efficiency) (1R0749)..... BF7587 +
Fuel/Water Separator (1677004-C91)..... BF1345-O	3 31/32 In. Steering (1691121-C1)..... P106-HD	Air Dryer (AD-9 System) (Bendix 107796)..... BA5377
Fuel (1809789-C1)..... BF7629 +	8200 w/Cat 3176 Eng.	Coolant (w/o Chemical) (Fleetguard WF2077)..... B5134 +
Air (476741-C1)..... PA2521	Lube..... B99 +	Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071
Air Dryer (AD-9 System) (Bendix 107796)..... BA5377	Opt. B-P Lube (1W8845)..... B7577	Coolant (w/12 Units BTA+) (Fleetguard WF2074)..... BW5074
Coolant (w/4 Units BTA+) (1822313-C1)..... BW5082	Fuel/Water Separator (Fleetguard FS1212)..... BF1212 +	Opt. Trans. (Fuller 17237)..... B2 +
Coolant (w/12 Units BTA+) (Fleetguard WF2074)..... BW5074	P. Fuel Ele. (9M2342)..... [2] PF935	2 25/32 In. Steering (279294-C92)..... PT903
Coolant (w/o Chemical) (Fleetguard WF2101)..... B5134 +	Fuel Spin-on..... BF614 +	3 In. Steering (1696766-C1)..... P7178
Opt. Trans. (Fuller 17237)..... B2 +	O. Air (1674320-C2)..... PA2525	3 31/32 In. Steering (1691121-C1)..... P106-HD
	I. Air (1674319-C2)..... PA2526	
	O. Air (476741-C1)..... PA2521	
	I. Air (Fleetguard AF987)..... PA2522	
	Air Dryer (Bendix 107796)..... BA5377	
	Coolant (1994-on) (Fleetguard WF2071)..... BW5071	
	Coolant (To 1994) (Fleetguard WF2074)..... BW5074	


\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>INTERNATIONAL Trucks &amp; Buses (cont'd)</b>	<b>INTERNATIONAL Trucks &amp; Buses (cont'd)</b>	<b>INTERNATIONAL Trucks &amp; Buses (cont'd)</b>
8200 w/Cummins M11 (10.8L) Eng. (To 1993) <b>Dual-Flow Lube</b> (Std. Vers.) (3318853)..... <b>BD103 +</b> <b>Dual-Flow Lube</b> (High Velocity) (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel/Water Separator</b> (3329289). <b>BF1259</b> <b>Fuel/Water Separator</b> (Fleetguard FF105D)..... <b>BF957-D +</b> <b>Fuel/Water Separator</b> (w/Drain) (Fleetguard FS19513)..... <b>BF5813 +</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (Fleetguard FS19513).... <b>BF5813-O +</b> <b>Fuel/Water Separator</b> (Closed End) (3843447)..... <b>BF1282 +</b> <b>Fuel/Water Separator</b> (Open End for Bowl)..... <b>BF1282-O +</b> <b>Single Air</b> (1661755-C91)..... <b>PA2521</b> <b>O. Air</b> (1674320-C2)..... <b>PA2525</b> <b>I. Air</b> (1674319-C2)..... <b>PA2526</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (w/Chemicals) (Fleetguard WF2074)..... <b>BW5074</b> <b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134 +</b> <b>Coolant</b> (Controlled Release) (Nalcool NF2088)..... <b>BW5200</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>2 25/32 In. Steering</b> (279294-C92)..... <b>PT903</b> <b>3 In. Steering</b> (1696766-C1)..... <b>P7178</b> <b>3 31/32 In. Steering</b> (1691121-C1)..... <b>P106-HD</b>	8200 w/Cummins M11 (10.8L) Eng. (1994-on) (Cont'd) <b>Coolant</b> (Controlled Release) (Nalcool NF2088)..... <b>BW5200</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>2 25/32 In. Steering</b> (279294-C92)..... <b>PT903</b> <b>3 In. Steering</b> (1696766-C1)..... <b>P7178</b> <b>3 31/32 In. Steering</b> (1691121-C1)..... <b>P106-HD</b> <hr/> 8200 w/Cummins N14 (14.0L) Eng. (To 1994) <b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Fuel</b> (154789)..... <b>BF957-D +</b> <b>O. Air</b> (1674320C2)..... <b>PA2525</b> <b>I. Air</b> (1674319C2)..... <b>PA2526</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (w/Chemicals) (Fleetguard WF2074)..... <b>BW5074</b> <b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134 +</b> <b>Coolant</b> (Controlled Release) (Nalcool NF2088)..... <b>BW5200</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>2 25/32 In. Steering</b> (Fleetguard LF634)..... <b>PT903</b> <b>3 31/32 In. Steering</b> (Fleetguard HF6162)..... <b>P106-HD</b> <hr/> 8200 w/Cummins N14 (14.0L) Eng. (1994-on) <b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Fuel</b> (154789)..... <b>BF957-D +</b> <b>O. Air</b> (1674320C2)..... <b>PA2525</b> <b>I. Air</b> (1674319C2)..... <b>PA2526</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (w/Chemicals) (Fleetguard WF2074)..... <b>BW5071</b> <b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134 +</b> <b>Coolant</b> (Controlled Release) (Nalcool NF2088)..... <b>BW5200</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>2 25/32 In. Steering</b> (Fleetguard LF634)..... <b>PT903</b> <b>3 31/32 In. Steering</b> (Fleetguard HF6162)..... <b>P106-HD</b> <hr/> 8200 w/Detroit Diesel Series 50 (8.5L) Eng. <b>Lube</b> (23530573)..... <b>[2] B495</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (23535985)..... <b>BF5813 +</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (23535985).. <b>BF5813-O +</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b>	8200 w/Detroit Diesel Series 60 (11.1L) & (12.7L) Eng. <b>Lube</b> (23530573)..... <b>[2] B495</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b> <b>O. Air</b> (1674320-C2)..... <b>PA2525</b> <b>Opt. I. Air</b> (1674319-C2)..... <b>PA2526</b> <b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134 +</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b> <b>Coolant</b> (Controlled Release) (Nalcool NF2088)..... <b>BW5200</b> <b>2 25/32 In. Steering</b> (279294-C92)..... <b>PT903</b> <b>3 In. Steering</b> (1696766-C1)..... <b>P7178</b> <b>3 31/32 In. Steering</b> (1691121-C1)..... <b>P106-HD</b> <b>Some Rear Axle</b> (Fleetguard LF689)..... <b>B233</b> <hr/> 8200 w/DT466 (7.6L) Eng. <b>Lube</b> (1819452C1)..... <b>B7030</b> <b>Fuel</b> (1822588C1)..... <b>BF7629 +</b> <b>Coolant</b> (1822313C1)..... <b>BW5082</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (w/o Gskt.) (279294C92)..... <b>PT951</b> <b>Steering</b> (w/Gskt.) (279294C92).. <b>PT903</b> <hr/> 8200 w/DT530 (8.7L) Eng. <b>F-F Lube</b> (1819452C1)..... <b>B7030</b> <b>Dual-Flow Lube</b> (1842639C91)... <b>BD7250</b> <b>Fuel/Water Separator</b> (1842638C91)..... <b>PF7779</b> <b>Fuel</b> (1820479C1)..... <b>BF7531</b> <b>Coolant</b> (1822313C1)..... <b>BW5082</b> <hr/> 8300 w/Cat 3176 Eng. <b>Lube</b> ..... <b>B99 +</b> <b>Opt. B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Fuel/Water Separator</b> (Fleetguard FS1212)..... <b>BF1212 +</b> <b>P. Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> ..... <b>BF614 +</b> <b>O. Air</b> (1674320-C2)..... <b>PA2525</b> <b>I. Air</b> (1674319-C2)..... <b>PA2526</b> <b>O. Air</b> (476741-C1)..... <b>PA2521</b> <b>I. Air</b> (Fleetguard AF987)..... <b>PA2522</b> <b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (1994-on) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (To 1994) (Fleetguard WF2074)..... <b>BW5074</b> <b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134 +</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
8300 w/Cat 3176 Eng. (Cont'd)	8300 w/Cummins N14 (14.0L) Eng. (To 1994) (Cont'd)	8500 w/DT530 (8.7L) Eng.
<b>Steering</b> (w/Gasket) (279294-C92)..... <b>PT903</b>	<b>3 31/32 In. Steering</b> (Fleetguard HF6162)..... <b>P106-HD</b>	<b>F-F Lube</b> (1819452C1)..... <b>B7030</b>
<b>Steering</b> (w/o Gasket) (279294-C92)..... <b>PT951</b>	8300 w/Cummins N14 (14.0L) Eng. (1994-on)	<b>Dual-Flow Lube</b> (1842639C91)... <b>BD7250</b>
<b>Steering</b> (1691121-C1)..... <b>P106-HD</b>	<b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196 +</b>	<b>Fuel/Water Separator</b> (1842638C91)..... <b>PF7779</b>
8300 w/Cummins M11 (10.8L) Eng.	<b>B-P Lube</b> (3304232)..... <b>B7577</b>	<b>Fuel</b> (1820479C1)..... <b>BF7531</b>
<b>Dual-Flow Lube</b> (Std. Vers.) (3318853)..... <b>BD103 +</b>	<b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b>	<b>Coolant</b> (1822313C1)..... <b>BW5082</b>
<b>Dual-Flow Lube</b> (High Velocity) (Fleetguard LF9009)..... <b>BD7309 +</b>	<b>Fuel</b> (154789)..... <b>BF957-D +</b>	8500 w/DT570 (9.3L) Eng.
<b>Fuel/Water Separator</b> (3329289). <b>BF1259</b>	<b>O. Air</b> (1674320C2)..... <b>PA2525</b>	<b>Dual-Flow Lube</b> (1842639C91)... <b>BD7250</b>
<b>Fuel/Water Separator</b> (Fleetguard FF105D)..... <b>BF957-D +</b>	<b>I. Air</b> (1674319C2)..... <b>PA2526</b>	<b>Lube Centrifuge</b> (1842825C91)... <b>BC7394</b>
<b>Fuel/Water Separator</b> (w/Drain) (Fleetguard FS19513)..... <b>BF5813 +</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Single Radial Seal Air</b> (3532799C1)..... <b>RS4636 +</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (Fleetguard FS19513)... <b>BF5813-O +</b>	<b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b>	<b>Radial Seal O. Air</b> (3551814C1).. <b>RS4862</b>
<b>Fuel/Water Separator</b> (Closed End) (3843447)..... <b>BF1282 +</b>	<b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134 +</b>	<b>Radial Seal I. Air</b> (3551815C1)... <b>RS4863</b>
<b>Fuel/Water Separator</b> (Open End for Bowl)..... <b>BF1282-O +</b>	<b>Coolant</b> (Controlled Release) (Nalcool NF2088)..... <b>BW5200</b>	<b>Cab Air</b> (2506656C1)..... <b>PA4985</b>
<b>Single Air</b> (1661755-C91)..... <b>PA2521</b>	<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	8500 w/HT570 (9.3L) Eng.
<b>O. Air</b> (1674320-C2)..... <b>PA2525</b>	<b>2 25/32 In. Steering</b> (Fleetguard LF634)..... <b>PT903</b>	<b>10 11/32 In. Dual-Flow Lube</b> (1842543-C1)..... <b>BD7252</b>
<b>I. Air</b> (1674319-C2)..... <b>PA2526</b>	<b>3 31/32 In. Steering</b> (Fleetguard HF6162)..... <b>P106-HD</b>	<b>14 7/32 In. Dual-Flow Lube</b> (1842639-C91)..... <b>BD7250</b>
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	8300 w/Detroit Diesel Series 60 (11.1L) & (12.7L) Eng.	<b>B-P Lube Spinner</b> (1842825-C91)..... <b>BC7394</b>
<b>Coolant</b> (To 1994) (Fleetguard WF2074)..... <b>BW5074</b>	<b>F-F Lube</b> (23530407)..... <b>[2] B95 +</b>	<b>Fuel/Water Separator</b> (1842638-C92)..... <b>PF7779</b>
<b>Coolant</b> (1994-on) (Fleetguard WF2071)..... <b>BW5071</b>	<b>B-P Lube</b> (23530413)..... <b>B7577</b>	<b>Radial Seal O. Air</b> (3551814-C1). <b>RS4862</b>
<b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134 +</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1212)..... <b>BF1212 +</b>	<b>Radial Seal I. Air</b> (3551815-C1)... <b>RS4863</b>
<b>Coolant</b> (Controlled Release) (Nalcool NF2088)..... <b>BW5200</b>	<b>P. Fuel</b> (23530706)..... <b>BF5800 +</b>	<b>Single Radial Seal Air</b> (3532799-C1)..... <b>RS4636 +</b>
<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	<b>S. Fuel</b> (23530707)..... <b>BF5810</b>	<b>Opt. Cab Air</b> (2506656-C1)..... <b>PA4985</b>
<b>2 25/32 In. Steering</b> (279294-C92)..... <b>PT903</b>	<b>O. Air</b> (1674320-C2)..... <b>PA2525</b>	<b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b>
<b>3 In. Steering</b> (1696766-C1)..... <b>P7178</b>	<b>Opt. I. Air</b> (1674319-C2)..... <b>PA2526</b>	<b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b>
<b>3 31/32 In. Steering</b> (1691121-C1)..... <b>P106-HD</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>
8300 w/Cummins N14 (14.0L) Eng. (To 1994)	<b>Coolant</b> (w/o Coolant) (Fleetguard WF2077)..... <b>B5134 +</b>	<b>Steering</b> (2503221-C1)..... <b>BT9388</b>
<b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196 +</b>	<b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>	8500 TranStar w/Cummins ISM (10.8L) Eng.
<b>B-P Lube</b> (3304232)..... <b>B7577</b>	<b>Coolant</b> (w/12 Units BTA+) (1815588-C1)..... <b>BW5074</b>	<b>Radial Seal O. Air</b> (3551814C1).. <b>RS4862</b>
<b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b>	<b>Coolant</b> (Controlled Release) (Nalcool NF2088)..... <b>BW5200</b>	<b>Radial Seal I. Air</b> (3551815C1)... <b>RS4863</b>
<b>Fuel</b> (154789)..... <b>BF957-D +</b>	<b>2 25/32 In. Steering</b> (Fleetguard LF634)..... <b>PT903</b>	<b>Trans.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>
<b>O. Air</b> (1674320C2)..... <b>PA2525</b>	<b>3 31/32 In. Steering</b> (Fleetguard HF6162)..... <b>P106-HD</b>	<b>Trans.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>
<b>I. Air</b> (1674319C2)..... <b>PA2526</b>	8500 w/DT466 (7.6L) Eng.	8500 TranStar w/DT570 (9.3L) Eng.
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>F-F Lube</b> (1819452C1)..... <b>B7030</b>	<b>Dual-Flow Lube</b> (1842639C91)... <b>BD7250</b>
<b>Coolant</b> (w/Chemicals) (Fleetguard WF2074)..... <b>BW5074</b>	<b>Fuel/Water Separator Ele.</b> (1842638C92)..... <b>PF7779</b>	<b>Lube Centrifuge</b> (1842825C91)... <b>BC7394</b>
<b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134 +</b>	<b>Fuel</b> (625625C1)..... <b>BF984</b>	<b>Single Radial Seal Air</b> (3532799C1)..... <b>RS4636 +</b>
<b>Coolant</b> (Controlled Release) (Nalcool NF2088)..... <b>BW5200</b>	<b>Fuel</b> (625627C1)..... <b>BF979 +</b>	<b>Radial Seal O. Air</b> (3551814C1).. <b>RS4862</b>
<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	<b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>	<b>Radial Seal I. Air</b> (3551815C1)... <b>RS4863</b>
<b>2 25/32 In. Steering</b> (Fleetguard LF634)..... <b>PT903</b>	<b>Coolant</b> (w/12 Units BTA+) (1820361C1)..... <b>BW5074</b>	<b>Cab Air</b> (2506656C1)..... <b>PA4985</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
8500 TranStar w/HT530 Eng. (Cont'd) Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT Opt. Trans. Spin-on (Fuller 17237)..... B2 + Steering (2503221-C1)..... BT9388	8600 SBA w/Cat C11 (11.1L) Eng. (Cont'd) Opt. Trans. Spin-on (Fuller 17237)..... B2 + 8600 SBA w/Cat C12 (12.0L) Eng. Lube (Std. Version) (1R0716)..... B99 + Lube (High Efficiency Vers.) (1R1808)..... B7299 + B-P Lube (1W8845)..... B7577 Fuel Ele. (9M2342)..... [2] PF935 Fuel Spin-on (Standard Vers.) (4N5823)..... BF614 + Fuel Spin-on (High Efficiency Vers.)..... BF7587 + Radial Seal O. Air (3551814C1).. RS4862 Radial Seal I. Air (3551815C1)... RS4863 Cab Air (2506656C1)..... PA4985 Air Dryer (Bendix 107794)..... BA5377 Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT Opt. Trans. Spin-on (Fuller 17237)..... B2 +	8600 SBA w/Cummins ISM 10.8 (10.8L) Eng. (Cont'd) Fuel/Water Separator Spin-on (3329289)..... BF1259 Fuel/Water Separator Spin-on (Fleetguard FS19683)..... BF1268 Radial Seal O. Air (3551814C1).. RS4862 Radial Seal I. Air (3551815C1)... RS4863 Cab Air (2506656C1)..... PA4985 Air Dryer (Bendix 107794)..... BA5377 Crankcase Breather (3683918)... CV15000 Coolant (w/o Chemical) (Fleetguard WF2127)..... B5087 Coolant (Controlled Release) (Fleetguard WF2121)..... BW5250 Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071 Coolant (w/12 Units BTA+) (Fleetguard WF2074)..... BW5074 Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT Opt. Trans. Spin-on (Fuller 17237)..... B2 + 8600 SBA w/HT570 (9.3L) Eng. 10 11/32 In. Dual-Flow Lube (1842543C1)..... BD7252 14 7/32 In. Dual-Flow Lube (1841606C1)..... BD7250 Trans. (Fuller 4304827)..... BT223 Opt. Trans. (Fuller 17237)..... B2 + 8600 TranStar w/Cat C10, C11, C12 Eng. Lube (To 1/2004) (1R0716)..... B99 + Lube (1/2004-on) (1R1808)..... B7299 + Fuel/Water Separator Ele. (Davco 382113)..... PF7748 Fuel/Water Separator Ele..... PF7755 Fuel/Water Separator Spin-on (Fleetguard FS19683)..... BF1268 Fuel (1R0749)..... BF7587 + Fuel (Fleetguard FF202)..... BF596 + Radial Seal O. Air (3551814-C1). RS4862 Radial Seal I. Air (3551815-C1)... RS4863 Cab Air (2506656-C1)..... PA4985 Air Dryer (Bendix 107796)..... BA5377 Crankcase Breather (C13 Eng. 2007-on) (296-8325)..... CV15008 Coolant (w/4 Units BTA+)..... BW5071 Coolant (w/4 Units BTE)..... BW5137 Coolant (w/8 Units BTE)..... BW5139 Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT Opt. Trans. Spin-on (Fuller 17237)..... B2 + Steering (2503221-C1)..... BT9388
8500 TranStar w/MaxxForce 10 Eng. Dual-Flow Lube (1842639-C91).. BD7250 Lube (1885920C2)..... B40053 Fuel/Water Separator (1842638-C91)..... PF7779 Fuel Strainer (1873910-C91)..... PF7994 Single Radial Seal Air (3532799-C1)..... RS4636 + Radial Seal O. Air (3551814-C1). RS4862 Radial Seal I. Air (3551815-C1).. RS4863 Opt. Cab Air (2506656-C1)..... PA4985 Air Dryer (Wabco R950011)..... BA5374 + Opt. Trans. (Fuller 17237)..... B2 + Steering (2503221-C1)..... BT9388	8600 SBA w/Cat C10 (10.3L) Eng. Lube (1R0716)..... B99 + Fuel/Water Separator (Open End for Bowl) (1335673)..... BF1395-O Fuel/Water Separator (w/Drain) (1335673)..... BF1265 Fuel/Water Separator (w/Sensor Port) (1335673)..... BF1395-SP Fuel Ele. (9M2342)..... PF935 Radial Seal O. Air (3551814C1).. RS4862 Radial Seal I. Air (3551815C1)... RS4863 Cab Air (2506656C1)..... PA4985 Coolant (w/4 Units BTE) (9N3717)..... BW5137 Coolant (w/8 Units BTE) (9N6123)..... BW5139 Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT Opt. Trans. Spin-on (Fuller 17237)..... B2 +	8600 SBA w/Cat C13 (12.5L) Eng. Lube (1R1808)..... B7299 + Fuel/Water Separator (3329289).. BF1259 Fuel (Standard Vers.) (4N5823)... BF614 + Fuel (High Efficiency Vers.)..... BF7587 + Radial Seal O. Air (3551814C1).. RS4862 Radial Seal I. Air (3551815C1)... RS4863 Cab Air (2506656C1)..... PA4985 Air Dryer (Bendix 107794)..... BA5377 Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT Opt. Trans. Spin-on (Fuller 17237)..... B2 + 8600 SBA w/Cummins 6BT5.9 (5.9L) Eng. Lube (Chrysler 5083285AA)..... BT7349 Fuel/Water Separator (3925274).. BF1280 + Fuel (3903640)..... BF788 Radial Seal O. Air (3551814C1).. RS4862 Radial Seal I. Air (3551815C1)... RS4863 Cab Air (2506656C1)..... PA4985 Air Dryer (Bendix 107794)..... BA5377 Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT Opt. Trans. Spin-on (Fuller 17237)..... B2 + 8600 SBA w/Cummins ISM 10.8 (10.8L) Eng. Dual-Flow Lube (3101869)..... BD7154 + Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... BD50000 Fuel/Water Separator Ele. (Fleetguard FS19765)..... PF7930
8600 SBA w/Cat C11 (11.1L) Eng. Lube (1R1808)..... B7299 + Fuel/Water Separator (3329289).. BF1259 Fuel (Standard Vers.) (4N5823)... BF614 + Fuel (High Efficiency Vers.)..... BF7587 + Fuel (1R0762)..... BF7753 Radial Seal O. Air (3551814C1).. RS4862 Radial Seal I. Air (3551815C1)... RS4863 Cab Air (2506656C1)..... PA4985 Air Dryer (Bendix 107794)..... BA5377 Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT		

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
8600 TranStar w/Cat C13 (12.5L) Eng. (To 1/2004)	8600 TranStar w/Cummins ISM (10.8L) Eng.	8600 TranStar w/MaxxForce 7 Eng.
Lube (1R0716)..... B99 +	Dual-Flow Lube (Fleetguard LF9001)..... BD7154 +	Lube Ele. (w/o Screw on Cap) (1840752-C91)..... P7235
Fuel/Water Separator Ele. (Davco 382113)..... PF7748	Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... BD50000	Lube Ele. (w/Screw on Cap) (Wix 57312)..... P7436
Fuel/Water Separator Ele..... PF7755	Fuel/Water Separator Ele. (Davco 382113)..... PF7748	Lube Spin-on (1899332C-91)..... B7506
Fuel/Water Separator Spin-on (Fleetguard FS19683)..... BF1268	Fuel/Water Separator Ele..... PF7755	Fuel/Water Separator (1878042-C91)..... PF7978
Fuel (1R0749)..... BF7587 +	Fuel/Water Separator Ele. (Fleetguard FS1029W)..... PF7680	Fuel Strainer (1873910-C91)..... PF7994
Fuel (Fleetguard FF202)..... BF596 +	Fuel/Water Separator Spin-on..... BF1272-SPS	Radial Seal Air (3551814-C1)..... RS4862
Radial Seal O. Air (3551814-C1)..... RS4862	Fuel/Water Separator Spin-on (3292289)..... BF1259	Cab Air (3548705-C1)..... PA4985
Radial Seal I. Air (3551815-C1)..... RS4863	Radial Seal O. Air (3551814-C1)..... RS4862	Air Dryer (Wabco R950011)..... BA5374 +
Cab Air (2506656-C1)..... PA4985	Radial Seal I. Air (3551815-C1)..... RS4863	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004
Air Dryer (Bendix 107796)..... BA5377	Cab Air (2506656-C2)..... PA4985	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016
Coolant (w/4 Units BTA+)..... BW5071	Air Dryer (Bendix 107796)..... BA5377	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003
Coolant (w/4 Units BTE)..... BW5137	Air Dryer (Wabco R950011)..... BA5374 +	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017
Coolant (w/8 Units BTE)..... BW5139	Crankcase Breather (3683918)..... CV15000	Trans. Spin-on (Allison 29539579)..... BT8460
Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	Coolant (w/4 Units BTE)..... BW5137	Steering (2503221-C1)..... BT9388
Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Coolant (w/4 Units BTA+)..... BW5071	
Opt. Trans. Spin-on (Fuller 17237)..... B2 +	Coolant (w/11 1/2 Units BTA+) (Fleetguard WF2126)..... BW5086	8600 TranStar w/MaxxForce 11 Eng.
Steering (2503221-C1)..... BT9388	Coolant (w/o Chemicals) (4920476)..... B5090	Lube (2007 Emissions) (3006874C91)..... P7508
	Coolant (w/o Chemical) (1833690-C1)..... B5088 +	Lube (2010 Emissions) (3007498-C92)..... P7494
8600 TranStar w/Cat C13 (12.5L) Eng. (1/2004-on)	Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	Fuel/Water Separator Ele. (2588149-C1)..... PF7748
Lube (1R1808)..... B7299 +	Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Fuel/Water Separator (3004473-C93)..... PF7986
Fuel/Water Separator Ele. (Davco 382113)..... PF7748	Opt. Trans. Spin-on (Fuller 17237)..... B2 +	Fuel Pre-Screen (3004474C92)..... PF7939 +
Fuel/Water Separator Ele..... PF7755	Steering (2503221-C1)..... BT9388	Radial Seal Air (3551814-C1)..... RS4862
Fuel/Water Separator Spin-on (Fleetguard FS19683)..... BF1268		Cab Air (6 5/32 In. Width) (3839141-C1)..... PA5679
Fuel (1R0749)..... BF7587 +	8600 TranStar w/Cummins ISX Eng.	Cab Air (7 1/4 In. Width) (3548705-C1)..... PA4985
Fuel (Fleetguard FF202)..... BF596 +	Dual-Flow Lube (Fleetguard LF9001)..... BD7154 +	Air Dryer (Wabco R950011)..... BA5374 +
Radial Seal O. Air (3551814-C1)..... RS4862	Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... BD50000	Air Dryer (2500518-C91)..... BA5373
Radial Seal I. Air (3551815-C1)..... RS4863	Fuel (Fleetguard FF2200)..... BF7766	Opt. Trans. (Fuller 17237)..... B2 +
Cab Air (2506656-C1)..... PA4985	Radial Seal O. Air (3551814-C1)..... RS4862	Steering (2503221-C1)..... BT9388
Air Dryer (Bendix 107796)..... BA5377	Radial Seal I. Air (3551815-C1)..... RS4863	
Crankcase Breather (296-8325)..... CV15008	Cab Air (2506656-C1)..... PA4985	8600 TranStar w/MaxxForce 13 (12.4L) Eng. (To 2012)
Coolant (w/4 Units BTA+)..... BW5071	Air Dryer (Bendix 107796)..... BA5377	Lube (2007 Emissions) (3006874C91)..... P7508
Coolant (w/4 Units BTE)..... BW5137	Crankcase Breather (3683918)..... CV15000	Lube (2010 Emissions) (3007498-C92)..... P7494
Coolant (w/8 Units BTE)..... BW5139	Coolant (w/11 1/2 Units BTA+) (Fleetguard WF2126)..... BW5086	Fuel/Water Separator (2588149-C1)..... PF7748
Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	Coolant (w/o Chemical) (Fleetguard WF2127)..... B5087	Fuel/Water Separator (3004473-C93)..... PF7986
Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	Opt. P. Fuel (3004474C91)..... PF7939 +
Opt. Trans. Spin-on (Fuller 17237)..... B2 +	Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Radial Seal O. Air (3551814-C1)..... RS4862
Steering (2503221-C1)..... BT9388	Opt. Trans. Spin-on (Fuller 17237)..... B2 +	Radial Seal I. Air (Fleetguard AF26268)..... RS4863
	Steering (2503221-C1)..... BT9388	Cab Air (6 5/32 In. Width) (3839141-C1)..... PA5679
8600 TranStar w/Cummins ISL-G (8.9L) Eng.		
Dual-Flow Lube (3401544)..... BD7309 +		
Lube (Upgrade) (3401544)..... B40142 +		
Fuel/Water Separator (3606712)..... BF7695		
Coolant (w/4 units BTA+) (3100304)..... BW5071		
Coolant (w/12 Units BTA+) (3100307)..... BW5074		

+ See Product Guide for Variations of This Number. Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
8600 TranStar w/MaxxForce 13 (12.4L) Eng. (To 2012) (Cont'd)	8600 TranStar w/N13 Eng. (2014-18) (Cont'd)	9100i w/Cat C10 Eng. (Cont'd)
<b>Cab Air</b> (7 1/4 In. Width) (3548705-C1)..... <b>PA4985</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	<b>Fuel/Water Separator Spin-on</b> (w/o SP) (1685159-C91)..... <b>BF1346 +</b>
<b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>Fuel/Water Separator Spin-on</b> (w/SP) (1685159-C91)..... <b>BF1346-SP +</b>
<b>Air Dryer</b> (2500518-C91)..... <b>BA5373</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Fuel</b> (1R1712)..... <b>BF614 +</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Steering</b> (2503221C1)..... <b>BT9388</b>	<b>Fuel</b> (1R0749)..... <b>BF7587 +</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	9100 SBA w/Cummins ISM 10.8 (10.8L) Eng.	<b>15 1/4 In. Radial Seal Air</b> (Standard) (3560734-C1)..... <b>RS3518</b>
<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>Dual-Flow Lube</b> (3101869)..... <b>BD7154 +</b>	<b>15 1/4 In. Radial Seal Air</b> (Upgrade) (3560734-C1)..... <b>RS3518XP</b>
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>	<b>18 5/8 In. Radial Seal Air</b> (1694039-C1)..... <b>RS3530</b>
<b>Steering</b> (2503221-C1)..... <b>BT9388</b>	<b>Fuel/Water Separator</b> (3329289).. <b>BF1259</b>	<b>18 5/8 In. Radial Seal XP Air</b> (1694039-C1)..... <b>RS3530XP</b>
8600 TranStar w/MaxxForce 13 (12.4L) Eng. (2012-on)	<b>Crankcase Breather</b> (3683918).. <b>CV15000</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
<b>Lube</b> (3007498-C92)..... <b>P7494</b>	<b>Coolant</b> (w/o Chemicals) (Fleetguard WF2127)..... <b>B5087</b>	<b>Coolant</b> (1822627-C1)..... <b>BW5071</b>
<b>Lube Centrifuge</b> (2606467-C91).. <b>BC7485 +</b>	<b>Coolant</b> (Controlled Release BTA+) (Fleetguard WF2121)..... <b>BW5250</b>	<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>
<b>Fuel/Water Separator</b> (2588149-C1)..... <b>PF7748</b>	<b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>	<b>Steering</b> (2503221-C1)..... <b>BT9388</b>
<b>Fuel/Water Separator</b> (3004473-C93)..... <b>PF7986</b>	<b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b>	9100i w/Cat C12 Eng.
<b>Opt. P. Fuel</b> (3004474C91)..... <b>PF7939 +</b>	9100 SBA w/Cummins M11 (10.8L) Eng.	<b>F-F Lube</b> (1R0716)..... <b>B99 +</b>
<b>Radial Seal O. Air</b> (3551814-C1).. <b>RS4862</b>	<b>Radial Seal Air</b> (2005895C1)..... <b>RS3530</b>	<b>F-F Lube</b> (High Efficiency) (1R1808)..... <b>B7299 +</b>
<b>Radial Seal I. Air</b> (Fleetguard AF26268)..... <b>RS4863</b>	<b>Radial Seal XP Air</b> (2005895C1).. <b>RS3530XP</b>	<b>Fuel/Water Separator Ele.</b> (2503566-C1)..... <b>PF7680</b>
<b>Cab Air</b> (6 5/32 In. Width) (3839141-C1)..... <b>PA5679</b>	<b>Trans.</b> (Fuller 4304827)..... <b>BT223</b>	<b>Fuel/Water Separator Ele.</b> (2588149-C1)..... <b>PF7748</b>
<b>Cab Air</b> (7 1/4 In. Width) (3548705-C1)..... <b>PA4985</b>	<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	<b>Fuel/Water Separator Spin-on</b> (w/o SP) (1685159-C91)..... <b>BF1346 +</b>
<b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b>	<b>Steering</b> (2503221C1)..... <b>BT9388</b>	<b>Fuel/Water Separator Spin-on</b> (w/SP) (1685159-C91)..... <b>BF1346-SP +</b>
<b>Air Dryer</b> (2500518-C91)..... <b>BA5373</b>	9100 SBA w/Cummins N14 (14.0L) Eng.	<b>Fuel</b> (1R1712)..... <b>BF614 +</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b>	<b>Radial Seal Air</b> (Standard) (3560734-C1)..... <b>RS3518</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>F-F Lube</b> (Standard Vers.) (Fleetguard LF670SC)..... <b>B196 +</b>	<b>Radial Seal XP O. Air</b> (Upgrade) (3560734-C1)..... <b>RS3518XP</b>
<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>F-F Lube</b> (Ext. Life) (Fleetguard LF670SC)..... <b>B96 +</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>B-P Lube</b> (3304232)..... <b>B7577</b>	<b>Coolant</b> (1822627-C1)..... <b>BW5071</b>
<b>Steering</b> (2503221-C1)..... <b>BT9388</b>	<b>Fuel/Water Separator</b> (3329289).. <b>BF1259</b>	<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>
8600 TranStar w/N13 Eng. (2014-18)	<b>Fuel</b> (154789)..... <b>BF957-D +</b>	<b>Steering</b> (2503221-C1)..... <b>BT9388</b>
<b>Lube</b> (3007498C94)..... <b>P7494</b>	<b>Coolant</b> (w/4 Units BTA+) (3315116)..... <b>BW5071</b>	9100i SBA w/Cummins ISM (10.8L) Eng.
<b>Lube Centrifuge</b> (2606467C91).. <b>BC7485 +</b>	9100 SBA w/Detroit Diesel Series 60 (11.1L) Eng.	<b>Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154 +</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (2611236C1)..... <b>BF46018-O</b>	<b>Lube</b> (23530573)..... <b>[2] B495</b>	<b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>
<b>Fuel/Water Separator</b> (w/Drain) (2611236C1)..... <b>BF1281</b>	<b>Fuel/Water Separator Ele.</b> (23533816)..... <b>PF7748</b>	<b>Fuel/Water Separator</b> ..... <b>BF1259</b>
<b>Fuel/Water Separator</b> (3004473C93)..... <b>PF7986</b>	<b>Fuel/Water Separator Spin-on</b> (w/Drain) (23535985)..... <b>BF5813 +</b>	<b>15 1/4 In. Radial Seal Air</b> (Standard) (3520400-C1)..... <b>RS3518</b>
<b>Fuel Screen</b> (3004474C92)..... <b>PF7939 +</b>	<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (23535985).. <b>BF5813-O +</b>	<b>18 5/8 In. Radial Seal Air</b> (1694039-C1)..... <b>RS3530</b>
<b>Radial Seal O. Air</b> (3551816C1).. <b>RS5389-FN</b>	<b>P. Fuel</b> (23530706)..... <b>BF5800 +</b>	<b>15 1/4 In. Radial Seal Air</b> (Upgrade) (DBA5069)..... <b>RS3518XP</b>
<b>Radial Seal O. Air</b> (Fleetguard AF26103)..... <b>RS4862</b>	<b>S. Fuel</b> (23530707)..... <b>BF5810</b>	<b>18 5/8 In. Radial Seal XP Air</b> (1694039-C1)..... <b>RS3530XP</b>
<b>Radial Seal I. Air</b> (Fleetguard AF26268)..... <b>RS4863</b>	<b>Air</b> (w/Lid) (Don. P153551)..... <b>PA2705</b>	<b>Cab Air</b> (498144-C1)..... <b>PA5690</b>
<b>Cab Air</b> (3839141-C1)..... <b>PA5679</b>	9100i w/Cat C10 Eng.	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
<b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b>	<b>F-F Lube</b> (1R0716)..... <b>B99 +</b>	
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	<b>F-F Lube</b> (High Efficiency) (1R1808)..... <b>B7299 +</b>	
	<b>Fuel/Water Separator Ele.</b> (2503566-C1)..... <b>PF7680</b>	
	<b>Fuel/Water Separator Ele.</b> (2588149-C1)..... <b>PF7748</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
9100i SBA w/Cummins ISM (10.8L) Eng. (Cont'd)	9200 w/Cat 3406E Eng. (Cont'd)	9200 SBA w/Cat C10 (10.3L) Eng. (Cont'd)
Coolant (Fleetguard WF2122)..... B5088 +	P. Fuel Ele. (9M2342)..... [2] PF935	Fuel Spin-on (3563465-C1)..... BF596 +
Trans. (Fuller 4304827)..... BT223	Fuel Spin-on (1R0749)..... BF7587 +	Radial Seal O. Air (2005895-C1)..... RS3530
Opt. Trans. (Fuller 17237)..... B2 +	Radial Seal O. Air (2005895-C1)..... RS3530	Radial Seal XP O. Air (2005895-C1)..... RS3530XP
Steering (1698964-C91)..... PT9354-MPG	Radial Seal XP O. Air (2005895-C1)..... RS3530XP	Radial Seal I. Air (2022289-C1)..... RS3531
Some Differential (1685141-C1)..... B233	Radial Seal I. Air (2022289-C1)..... RS3531	Radial Seal Air (Standard) (3560734-C1)..... RS3518
9100i SBA w/Cummins N14 (14.0L) Eng.	Radial Seal Air (3507421-C1)..... [2] RS3743	Radial Seal XP Air (Upgrade) (3560734-C1)..... RS3518XP
Dual-Flow Lube (Fleetguard LF9009)..... BD7309 +	Air Dryer (AD-9 System) (Bendix 107796)..... BA5377	Air Dryer (System Saver 1200) (Wabco R950011)..... BA5374 +
Fuel/Water Separator Ele. (2503566-C1)..... PF7680	Coolant (1822627-C1)..... BW5071	Air Dryer (AD-9 System) (Bendix 107796)..... BA5377
Fuel/Water Separator Ele. (2588149-C1)..... PF7748	Trans. (Fuller 4304827)..... BT223	Coolant (1822627-C1)..... BW5071
Fuel/Water Separator Spin-on (3329289)..... BF1259	Steering (w/Gasket) (279294-C92)..... PT903	Opt. Trans. (Fuller 17237)..... B2 +
Radial Seal Air (Standard) (3560734-C1)..... RS3518	Steering (w/o Gasket) (279294-C92)..... PT951	Steering Ele. (1698964-C91)..... PT9354-MPG
Radial Seal XP Air (Upgrade) (3560734-C1)..... RS3518XP	Some Differential (Meritor 3280-V-8394)..... B233	Steering Spin-on (2503221-C1)..... BT9388
Radial Seal O. Air (1694039-C1)..... RS3530	9200 w/Detroit Diesel Series 60 (11.1L) & (12.7L) Eng.	9200 SBA w/Cat C12 (12.0L) Eng.
Radial Seal XP Air (1694039-C1)..... RS3530XP	Lube..... [2] B495	F-F Lube..... B99 +
Radial Seal I. Air (2003338-C92)..... RS3531	Fuel/Water Separator Ele. (1696265-C1)..... PF7680	B-P Lube..... B7577
Air Dryer (AD-9 System) (Bendix 107796)..... BA5377	P. Fuel..... PF5800 +	Fuel/Water Separator (23516189)..... BF5812
Air Dryer (AD-SP System) (Bendix 5008415)..... BA5374 +	S. Fuel..... BF5810	Fuel/Water Separator (Fleetguard FS1212)..... BF1212 +
Coolant (Fleetguard WF2071)..... BW5071	Radial Seal O. Air (2005895-C1)..... RS3530	Fuel Spin-on..... BF614 +
Trans. (Fuller 4304827)..... BT223	Radial Seal XP O. Air (2005895-C1)..... RS3530XP	Fuel Spin-on (3563465-C1)..... BF596 +
Opt. Trans. (Fuller 17237)..... B2 +	Radial Seal I. Air (2022289-C1)..... RS3531	Radial Seal O. Air (2005895-C1)..... RS3530
Steering Ele. (1698964-C91)..... PT9354-MPG	Air Dryer (System Saver 1200) (Wabco R950011)..... BA5374 +	Radial Seal XP O. Air (2005895-C1)..... RS3530XP
Steering Spin-on (2503221-C1)..... BT9388	Coolant..... BW5137	Radial Seal I. Air (2022289-C1)..... RS3531
9100i SBA w/Detroit Series 60 (11.1L) & (12.7L) Eng.	2 23/32 In. Steering (1698964-C91)..... PT9354-MPG	Radial Seal Air (Standard) (3560734-C1)..... RS3518
F-F Lube (23530573)..... [2] B495	2 25/32 In. Steering..... PT951	Radial Seal XP Air (Upgrade) (3560734-C1)..... RS3518XP
Fuel/Water Separator Ele. (1696265-C1)..... PF7680	9200 SBA w/Cat 3176 (10.3L) Eng.	Air Dryer (System Saver 1200) (Wabco R950011)..... BA5374 +
Fuel/Water Separator Ele. (2588149-C1)..... PF7748	F-F Lube (1R0716)..... B99 +	Air Dryer (AD-9 System) (Bendix 107796)..... BA5377
P. Fuel (23530706)..... BF5800 +	F-F Lube (1R1808)..... B7299 +	Coolant (1822627-C1)..... BW5071
15 1/4 In. Radial Seal Air (Standard) (3516347-C92)..... RS3518	F-F Lube (1R0713)..... BT230 +	Opt. Trans. (Fuller 17237)..... B2 +
15 1/4 In. Radial Seal Air (Upgrade) (3516347-C92)..... RS3518XP	F-F Lube (1R0714)..... B75	Steering Ele. (1698964-C91)..... PT9354-MPG
18 5/8 In. Radial Seal Air (2005895C1)..... RS3530	B-P Lube (1W8845)..... B7577	Steering Spin-on (2503221-C1)..... BT9388
18 5/8 In. Radial Seal XP Air (2005895C1)..... RS3530XP	Fuel/Water Separator Ele. (8N0205)..... PF316	9200 SBA w/Cummins L10 (10.0L) Eng.
Air Dryer (AD-9 System) (Bendix 107796)..... BA5377	Fuel/Water Separator Spin-on (2568753)..... BF1259	Dual-Flow Lube (Fleetguard LF3000)..... BD103 +
Trans. (Fuller 4304827)..... BT223	P. Fuel (1R1740)..... BF970 +	Dual-Flow Lube (Fleetguard LF9009)..... BD7309 +
Opt. Trans. (Fuller 17237)..... B2 +	S. Fuel (1R0750)..... BF7633 +	Fuel/Water Separator (Fleetguard FS1212)..... BF1212 +
Steering (2503221-C1)..... BT9388	Coolant (w/4 Units BTE) (9N3717)..... BW5137	Fuel (Fleetguard FF105)..... BF957 +
9200 w/Cat 3406E Eng.	Coolant (w/8 Units BTE) (9N3366)..... BW5139	Coolant (w/4 Units BTA+) (3315116)..... BW5071
Lube..... B99 +	9200 SBA w/Cat C10 (10.3L) Eng.	Coolant (w/15 Units BTA+) (Fleetguard WF2075)..... BW5075
Opt. B-P Lube (1W8845)..... B7577	F-F Lube..... B99 +	Opt. Trans. Spin-on (Fuller 17237)..... B2 +
Fuel/Water Separator (598435-C1)..... BF1212 +	B-P Lube..... B7577	
	Fuel/Water Separator (23516189)..... BF5812	
	Fuel/Water Separator (Fleetguard FS1212)..... BF1212 +	
	Fuel Spin-on..... BF614 +	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
9200 SBA w/Cummins M11 (10.8L) Eng. Dual-Flow Lube..... <b>BD103 +</b> Fuel/Water Separator..... <b>BF1212 +</b> Radial Seal O. Air (1694039-C1).. <b>RS3530</b> Radial Seal XP O. Air (1694039-C1)..... <b>RS3530XP</b> Radial Seal I. Air (2003338-C92).. <b>RS3531</b> Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> 2 23/32 In. Steering (1698964-C91)..... <b>PT9354-MPG</b> 2 25/32 In. Steering (279294-C92)..... <b>PT903</b> 4 3/16 In. Steering (598698-C1).. <b>P528</b>	9200 SBA; 9200i SBA w/Cummins ISM (10.8L) Eng. (Cont'd) Fuel/Water Separator Spin-on (w/Drain) (Mann WK1060/1)..... <b>BF1329</b> Fuel/Water Separator Spin-on (Sensor Port Thd. 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b> Fuel/Water Separator Spin-on (Sensor Port Thd. 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b> Fuel (Fleetguard FF2200)..... <b>BF7766</b> Radial Seal O. Air (Standard) (3560734-C1)..... <b>RS3518</b> Radial Seal XP O. Air (Upgrade) (3560734-C1)..... <b>RS3518XP</b> Radial Seal I. Air (3520401-C1)... <b>RS3519</b> Cab Air (1699956-C1)..... <b>PA5637</b> Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b> Air Dryer (AD-SP System) (Bendix 109994)..... <b>BA5374 +</b> Air Dryer (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b> Crankcase Breather (3683918)... <b>CV15000</b> Coolant (w/4 units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> Coolant (w/4 units BTE)..... <b>BW5137</b> Coolant (w/o Chemicals) (4920476)..... <b>B5090</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Steering (2503221-C1)..... <b>BT9388</b>	9200i SBA w/Cat C10 (10.3L) Eng. (To 1/2004) (Cont'd) Air Dryer (AD-SP System) (Bendix 109994)..... <b>BA5374 +</b> Air Dryer (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b> Coolant (w/4 Units BTA+)..... <b>BW5071</b> Coolant (w/4 Units BTE)..... <b>BW5137</b> Coolant (w/8 Units BTE) (9N3718)..... <b>BW5139</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Steering (2503221-C1)..... <b>BT9388</b>
9200 SBA w/Cummins N14 (14.0L) Eng. Dual-Flow Lube..... <b>BD103 +</b> F-F Lube..... <b>B196 +</b> B-P Lube..... <b>B7577</b> Opt. Fuel/Water Separator..... <b>BF1212 +</b> Fuel Spin-on..... <b>BF957-D +</b> Axial Seal Air (420051-C1)..... <b>PA2333</b> Radial Seal Air (1694039-C1)..... <b>RS3530</b> Radial Seal XP Air (1694039-C1)..... <b>RS3530XP</b> Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b> Coolant..... <b>BW5071</b> Steering..... <b>PT951</b>	9200i SBA w/Cat 3406 (14.6L) Eng. Lube (Standard Vers.) (1R0716).. <b>B99 +</b> Lube (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> Fuel/Water Separator (2568753). <b>BF1259</b> Fuel Ele. (9M2342)..... <b>[2] PF935</b> Fuel Spin-on (Standard Vers.) (4N5823)..... <b>BF614 +</b> Fuel Spin-on (High Efficiency Vers.)..... <b>BF7587 +</b>	9200i SBA w/Cat C10 (10.3L) Eng. (To 1/2004) (Cont'd) Fuel/Water Separator Ele. (Davco)..... <b>PF7680</b> Fuel/Water Separator Ele. (Fleetguard FS19729)..... <b>PF7755</b> Fuel Spin-on (1R0749)..... <b>BF7587 +</b> Fuel Spin-on (3563465-C1)..... <b>BF596 +</b> Radial Seal Air (Standard) (3560734-C1)..... <b>RS3518</b> Radial Seal XP Air (Upgrade) (3560734-C1)..... <b>RS3518XP</b> Cab Air (1699956-C1)..... <b>PA5637</b> Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b> Air Dryer (AD-SP System) (Bendix 109994)..... <b>BA5374 +</b>
9200 SBA w/Cummins Signature 600 (15.0L) Eng. 11 25/32 In. Dual-Flow Lube (Fleetguard LF9001)..... <b>BD7154 +</b> 14 7/32 In. Dual-Flow Lube (Fleetguard LF9000)..... <b>BD7153 +</b> Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> Fuel/Water Separator (3331096). <b>BF1274-SP</b> Fuel/Water Separator (4010651). <b>BF1277-SPS</b> Coolant (Fleetguard WF2126)..... <b>BW5086</b>	9200 SBA; 9200i SBA w/Cummins ISM (10.8L) Eng. Dual-Flow Lube (Fleetguard LF9001)..... <b>BD7154 +</b> Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> Fuel/Water Separator Ele. (2588149-C1)..... <b>PF7748</b> Fuel/Water Separator Ele..... <b>PF7755</b> Fuel/Water Separator Spin-on (3329289)..... <b>BF1259</b> Fuel/Water Separator Spin-on..... <b>BF1272-SPS</b> Fuel/Water Separator Spin-on (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> Fuel/Water Separator Spin-on (w/Bowl) (Mann WK1060/1)..... <b>BF46072</b>	9200i SBA w/Cat C12 (12.0L) Eng. (To 1/2004) (Cont'd) F-F Lube..... <b>B99 +</b> B-P Lube..... <b>B7577</b> Fuel/Water Separator Ele. (Davco)..... <b>PF7680</b> Fuel/Water Separator Ele. (Fleetguard FS19729)..... <b>PF7755</b> Fuel Spin-on (1R0749)..... <b>BF7587 +</b> Fuel Spin-on (3563465-C1)..... <b>BF596 +</b> Radial Seal Air (Standard) (3560734-C1)..... <b>RS3518</b> Radial Seal XP Air (Upgrade) (3560734-C1)..... <b>RS3518XP</b> Cab Air (1699956-C1)..... <b>PA5637</b> Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b> Air Dryer (AD-SP System) (Bendix 109994)..... <b>BA5374 +</b>

+ See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
9200i SBA w/Cat C12 (12.0L) Eng. (To 1/2004) (Cont'd) <b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b> <b>Coolant</b> (w/4 Units BTA+)..... <b>BW5071</b> <b>Coolant</b> (w/4 Units BTE)..... <b>BW5137</b> <b>Coolant</b> (w/8 Units BTE) (9N3718)..... <b>BW5139</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (2503221-C1)..... <b>BT9388</b>	9200i SBA w/Cat C13 (12.5L) Eng. (To 1/2004) (Cont'd) <b>Coolant</b> (w/4 Units BTE)..... <b>BW5137</b> <b>Coolant</b> (w/8 Units BTE) (9N3718)..... <b>BW5139</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (2503221-C1)..... <b>BT9388</b>	9200i SBA w/Cat C15 (14.6L) Eng. (To 1/2004) (Cont'd) <b>Coolant</b> (w/8 Units BTE) (9N3718)..... <b>BW5139</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (2503221-C1)..... <b>BT9388</b>
9200i SBA w/Cat C12 (12.0L) Eng. (1/2004-on) <b>F-F Lube</b> (1R1808)..... <b>B7299 +</b> <b>B-P Lube</b> ..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (Davco)..... <b>PF7680</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19729)..... <b>PF7755</b> <b>Fuel Spin-on</b> (1R0749)..... <b>BF7587 +</b> <b>Fuel Spin-on</b> (3563465-C1)..... <b>BF596 +</b> <b>Radial Seal Air</b> (Standard) (3560734-C1)..... <b>RS3518</b> <b>Radial Seal XP Air</b> (Upgrade) (3560734-C1)..... <b>RS3518XP</b> <b>Cab Air</b> (1699956-C1)..... <b>PA5637</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-SP System) (Bendix 109994)..... <b>BA5374 +</b> <b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b> <b>Coolant</b> (w/4 Units BTA+)..... <b>BW5071</b> <b>Coolant</b> (w/4 Units BTE)..... <b>BW5137</b> <b>Coolant</b> (w/8 Units BTE) (9N3718)..... <b>BW5139</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (2503221-C1)..... <b>BT9388</b>	9200i SBA w/Cat C13 (12.5L) Eng. (1/2004-on) <b>F-F Lube</b> (1R1808)..... <b>B7299 +</b> <b>B-P Lube</b> ..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (Davco)..... <b>PF7680</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19729)..... <b>PF7755</b> <b>Fuel Spin-on</b> (1R0749)..... <b>BF7587 +</b> <b>Fuel Spin-on</b> (3563465-C1)..... <b>BF596 +</b> <b>Radial Seal Air</b> (Standard) (3560734-C1)..... <b>RS3518</b> <b>Radial Seal XP Air</b> (Upgrade) (3560734-C1)..... <b>RS3518XP</b> <b>Cab Air</b> (1699956-C1)..... <b>PA5637</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-SP System) (Bendix 109994)..... <b>BA5374 +</b> <b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b> <b>Crankcase Breather</b> (296-8325).. <b>CV15008</b> <b>Coolant</b> (w/4 Units BTA+)..... <b>BW5071</b> <b>Coolant</b> (w/4 Units BTE)..... <b>BW5137</b> <b>Coolant</b> (w/8 Units BTE) (9N3718)..... <b>BW5139</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (2503221-C1)..... <b>BT9388</b>	9200i SBA w/Cat C15 (14.6L) Eng. (1/2004-on) <b>F-F Lube</b> (1R1808)..... <b>B7299 +</b> <b>B-P Lube</b> ..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (Davco)..... <b>PF7680</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19729)..... <b>PF7755</b> <b>Fuel Spin-on</b> (1R0749)..... <b>BF7587 +</b> <b>Fuel Spin-on</b> (3563465-C1)..... <b>BF596 +</b> <b>Radial Seal Air</b> (Standard) (3560734-C1)..... <b>RS3518</b> <b>Radial Seal XP Air</b> (Upgrade) (3560734-C1)..... <b>RS3518XP</b> <b>Cab Air</b> (1699956-C1)..... <b>PA5637</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-SP System) (Bendix 109994)..... <b>BA5374 +</b> <b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b> <b>Coolant</b> (w/4 Units BTA+)..... <b>BW5071</b> <b>Coolant</b> (w/4 Units BTE)..... <b>BW5137</b> <b>Coolant</b> (w/8 Units BTE) (9N3718)..... <b>BW5139</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (2503221-C1)..... <b>BT9388</b>
9200i SBA w/Cat C13 (12.5L) Eng. (To 1/2004) <b>F-F Lube</b> ..... <b>B99 +</b> <b>B-P Lube</b> ..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (Davco)..... <b>PF7680</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19729)..... <b>PF7755</b> <b>Fuel Spin-on</b> (1R0749)..... <b>BF7587 +</b> <b>Fuel Spin-on</b> (3563465-C1)..... <b>BF596 +</b> <b>Radial Seal Air</b> (Standard) (3560734-C1)..... <b>RS3518</b> <b>Radial Seal XP Air</b> (Upgrade) (3560734-C1)..... <b>RS3518XP</b> <b>Cab Air</b> (1699956-C1)..... <b>PA5637</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-SP System) (Bendix 109994)..... <b>BA5374 +</b> <b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b> <b>Coolant</b> (w/4 Units BTA+)..... <b>BW5071</b>	9200i SBA w/Cat C15 (14.6L) Eng. (To 1/2004) <b>F-F Lube</b> ..... <b>B99 +</b> <b>B-P Lube</b> ..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (Davco)..... <b>PF7680</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19729)..... <b>PF7755</b> <b>Fuel Spin-on</b> (1R0749)..... <b>BF7587 +</b> <b>Fuel Spin-on</b> (3563465-C1)..... <b>BF596 +</b> <b>Radial Seal Air</b> (Standard) (3560734-C1)..... <b>RS3518</b> <b>Radial Seal XP Air</b> (Upgrade) (3560734-C1)..... <b>RS3518XP</b> <b>Cab Air</b> (1699956-C1)..... <b>PA5637</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-SP System) (Bendix 109994)..... <b>BA5374 +</b> <b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b> <b>Coolant</b> (w/4 Units BTA+)..... <b>BW5071</b> <b>Coolant</b> (w/4 Units BTE)..... <b>BW5137</b>	9200i SBA w/Cummins ISX 15.0 (14.9L) Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154 +</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19729)..... <b>PF7755</b> <b>Fuel/Water Separator Spin-on</b> ..... <b>BF1277-SP</b> <b>Fuel</b> (Fleetguard FF2200)..... <b>BF7766</b> <b>Fuel</b> (Fleetguard FF2203)..... <b>BF7760</b> <b>Radial Seal O. Air</b> (Standard) (3560734-C1)..... <b>RS3518</b> <b>Radial Seal I. Air</b> (3520401-C1).. <b>RS3519</b> <b>Radial Seal XP O. Air</b> (Upgrade) (3560734-C1)..... <b>RS3518XP</b> <b>Cab Air</b> (1699956-C1)..... <b>PA5637</b> <b>Air Dryer</b> (AD-SP System) (Bendix 109994)..... <b>BA5374 +</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b> <b>Crankcase Breather</b> (3683918).. <b>CV15000</b> <b>Coolant</b> (w/4 units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
9200i SBA w/Cummins ISX 15.0 (14.9L) Eng. (Cont'd) <b>Coolant</b> (w/11 1/2 units BTA+) (Fleetguard WF2126)..... <b>BW5086</b> <b>Coolant</b> (w/4 units BTE)..... <b>BW5137</b> <b>Coolant</b> (w/o Chemical) (Fleetguard WF2127)..... <b>B5087</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 *</b> <b>Steering</b> (2503221-C1)..... <b>BT9388</b>	9200i SBA w/Detroit Diesel Series 60 (11.1L) & (12.7L) Eng. (Cont'd) <b>15 1/4 In. Radial Seal XP Air</b> (Upgrade) (3560734-C1)..... <b>RS3518XP</b> <b>18 5/8 In. Radial Seal Air</b> (1694039-C1)..... <b>RS3530</b> <b>18 5/8 In. Radial Seal XP Air</b> (1694039-C1)..... <b>RS3530XP</b> <b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 *</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (Controlled Release) (2014314-C1)..... <b>BW5200</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 *</b> <b>Steering Ele.</b> (1698964-C91)..... <b>PT9354-MPG</b> <b>Steering Spin-on</b> (2503221-C1).. <b>BT9388</b>	9300 w/Cummins L10 (10.0L) Eng. <b>Dual-Flow Lube</b> (Fleetguard LF3000)..... <b>BD103 *</b> <b>F-F Lube</b> (Std. Version) (Fleetguard LF670SC)..... <b>B196 *</b> <b>F-F Lube</b> (Ext. Life) (Fleetguard LF670SC)..... <b>B96 *</b> <b>B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Fuel/Water Separator</b> (154789)... <b>BF957-D *</b> <b>Coolant</b> (w/4 Units BTA+) (3315116)..... <b>BW5071</b> <b>Coolant</b> (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b>
9200i SBA w/Cummins N14 (14.0L) Eng. <b>Dual-Flow Lube</b> (Std. Vers.) (Fleetguard LF3000)..... <b>BD103 *</b> <b>Dual-Flow Lube</b> (High Velocity)... <b>BD7309 *</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1000)..... <b>BF1259</b> <b>Radial Seal Air</b> (Standard) (Fleetguard AF25139M)..... <b>RS3518</b> <b>Radial Seal Air</b> (Upgrade) (DBA5069)..... <b>RS3518XP</b> <b>Cab Air</b> (1699956-C1)..... <b>PA5637</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-SP System) (Bendix 109994)..... <b>BA5374 *</b> <b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 *</b> <b>Steering Ele.</b> (1698964-C91)..... <b>PT9354-MPG</b> <b>Steering Spin-on</b> (2503221-C1).. <b>BT9388</b>	9300 w/Cat 3176 (10.3L) Eng. <b>F-F Lube</b> (1R0716)..... <b>B99 *</b> <b>F-F Lube</b> (1R1808)..... <b>B7299 *</b> <b>F-F Lube</b> (1R0713)..... <b>BT230 *</b> <b>F-F Lube</b> (1R0714)..... <b>B75</b> <b>B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Fuel/Water Separator Spin-on</b> (2568753)..... <b>BF1259</b> <b>P. Fuel</b> (1R1740)..... <b>BF970 *</b> <b>S. Fuel</b> (1R0750)..... <b>BF7633 *</b> <b>Coolant</b> (w/4 Units BTE) (9N3717)..... <b>BW5137</b> <b>Coolant</b> (w/8 Units BTE) (9N3366)..... <b>BW5139</b>	9300 w/Cummins M11 (10.8L) Eng. <b>Dual-Flow Lube</b> ..... <b>BD103 *</b> <b>F-F Lube</b> ..... <b>B196 *</b> <b>B-P Lube</b> ..... <b>B7577</b> <b>Opt. Fuel/Water Separator</b> ..... <b>BF1212 *</b> <b>Fuel Spin-on</b> ..... <b>BF957-D *</b> <b>Axial Seal Air</b> (420051-C1)..... <b>PA2333</b> <b>Radial Seal Air</b> (1694039-C1)..... <b>RS3530</b> <b>Radial Seal XP Air</b> (1694039-C1)..... <b>RS3530XP</b> <b>Cab Air</b> (498144-C1)..... <b>PA5690</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (System Saver 1000) (Wabco R950011)..... <b>BA5374 *</b> <b>Coolant</b> ..... <b>BW5071</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Steering</b> (w/Gasket) (279294-C92)..... <b>PT903</b> <b>Steering</b> (w/o Gasket)..... <b>PT951</b>
9200i SBA w/Cummins Signature 600 (15.0L) Eng. <b>11 25/32 In. Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154 *</b> <b>14 7/32 In. Dual-Flow Lube</b> (Fleetguard LF9000)..... <b>BD7153 *</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (3331096). <b>BF1274-SP</b> <b>Fuel/Water Separator</b> (4010651). <b>BF1277-SPS</b> <b>Coolant</b> (Fleetguard WF2126)..... <b>BW5086</b>	9300 w/Cat 3406E Eng. <b>Lube</b> ..... <b>B99 *</b> <b>Opt. B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Fuel/Water Separator</b> (598435-C1)..... <b>BF1212 *</b> <b>P. Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (1R0749)..... <b>BF7587 *</b> <b>Radial Seal O. Air</b> (2005895-C1). <b>RS3530</b> <b>Radial Seal XP O. Air</b> (2005895-C1)..... <b>RS3530XP</b> <b>Radial Seal I. Air</b> (2022289-C1)... <b>RS3531</b> <b>Radial Seal Air</b> (3507421-C1)..... <b>[2] RS3743</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (1822627-C1)..... <b>BW5071</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 *</b> <b>Steering</b> (w/Gasket) (279294-C92)..... <b>PT903</b> <b>Steering</b> (w/o Gasket) (279294-C92)..... <b>PT951</b> <b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	9300 w/Cummins N14 (14.0L) Eng. <b>Dual-Flow Lube</b> ..... <b>BD103 *</b> <b>F-F Lube</b> ..... <b>B196 *</b> <b>B-P Lube</b> ..... <b>B7577</b> <b>Opt. Fuel/Water Separator</b> ..... <b>BF1212 *</b> <b>Fuel Spin-on</b> ..... <b>BF957-D *</b> <b>Axial Seal Air</b> (420051-C1)..... <b>PA2333</b> <b>Radial Seal Air</b> (1694039-C1)..... <b>RS3530</b> <b>Radial Seal XP Air</b> (1694039-C1)..... <b>RS3530XP</b> <b>Cab Air</b> (498144-C1)..... <b>PA5690</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (System Saver 1000) (Wabco R950011)..... <b>BA5374 *</b> <b>Coolant</b> ..... <b>BW5071</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Steering</b> (w/Gasket) (279294-C92)..... <b>PT903</b> <b>Steering</b> (w/o Gasket)..... <b>PT951</b>
9200i SBA w/Detroit Diesel Series 60 (11.1L) & (12.7L) Eng. <b>Lube</b> ..... <b>[2] B495</b> <b>Fuel/Water Separator Ele.</b> (2503565-C1)..... <b>PF7680</b> <b>P. Fuel/Water Separator Spin-on</b> (w/Drain) (23512317)..... <b>BF5813 *</b> <b>P. Fuel/Water Separator Spin-on</b> (Open End for Bowl) (23512317).. <b>BF5813-O *</b> <b>Fuel/Water Separator Spin-on</b> (w/o SP) (1685159-C91)..... <b>BF1346 *</b> <b>Fuel/Water Separator Spin-on</b> (w/SP) (1685159-C91)..... <b>BF1346-SP *</b> <b>15 1/4 In. Radial Seal Air</b> (Standard) (3560734-C1)..... <b>RS3518</b>	9300 w/Cummins NTC Series Eng. <b>18 9/16 In. Air</b> (Fleetguard AF872M)..... <b>LL2333</b> <b>19 1/2 In. Air</b> (Fleetguard AF870)..... <b>PA2393</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 *</b> <b>Steering</b> (w/Gasket) (279294-C92)..... <b>PT903</b> <b>Steering</b> (w/o Gasket) (279294-C92)..... <b>PT951</b> <b>Steering</b> (598698-C1)..... <b>P528</b>	9300 w/Cummins Signature 600 (15.0L) Eng. <b>11 25/32 In. Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154 *</b> <b>14 7/32 In. Dual-Flow Lube</b> (Fleetguard LF9000)..... <b>BD7153 *</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (3331096). <b>BF1274-SP</b> <b>Fuel/Water Separator</b> (4010651). <b>BF1277-SPS</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
9300 w/Cummins Signature 600 (15.0L) Eng. (Cont'd) Coolant (Fleetguard WF2126)..... <b>BW5086</b>	9370 w/Cat 3406 (14.6L) Eng. (Cont'd) Air Dryer (AD-IP System) (Bendix 65624)..... <b>BA5373</b> Coolant (w/4 Units BTA+) (1822627-C1)..... <b>BW5071</b> Coolant (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b> Coolant (w/4 Units BTE) (9N3368)..... <b>BW5137</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> <b>2 25/32 In. Steering</b> (279294-C92)..... <b>PT951</b> <b>4 3/16 In. Steering</b> (598698-C1).. <b>P528</b>	9370 w/Cummins N14 (14.0L) Eng. (Cont'd) Air (420051-C1)..... <b>PA2333</b> Coolant..... <b>BW5071</b>
9300 w/Detroit Diesel 6V-92N (9.0L) Eng. Lube (23530407)..... <b>B95 +</b> Lube (23530408)..... <b>B95-MPG +</b> P. Fuel (23530706)..... <b>BF5800 +</b> S. Fuel (23530707)..... <b>BF5810</b> S. Fuel (23530645)..... <b>BF5815</b>	9370 w/Cummins Formula 300 Eng. B-P Lube (1666053-C1)..... <b>B7577</b> Fuel/Water Separator (1214920-H1)..... <b>BF1212 +</b> Fuel/Water Separator (w/Drain) (Fleetguard FS19513)..... <b>BF5813 +</b> Fuel/Water Separator (Open End for Bowl) (Fleetguard FS19513).... <b>BF5813-O +</b> Fuel Spin-on (244458-R91)..... <b>BF957 +</b> Single Air (Fleetguard AF870)..... <b>PA2393</b> O. Air (476741-C1)..... <b>PA2521</b> I. Air (482644-C1)..... <b>PA2522</b> Air Dryer (AD-4 System) (Bendix 107796)..... <b>BA5377</b> Coolant (258265)..... <b>BW5076</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Steering (598698-C1)..... <b>P528</b>	9370 w/Detroit Diesel 6V-92N (9.0L) Eng. F-F Lube Ele..... <b>P20-HD</b> F-F Lube Spin-on..... <b>B95 +</b> P. Fuel Spin-on..... <b>BF5800 +</b> S. Fuel Spin-on..... <b>BF5810</b> Air (420051-C1)..... <b>PA2333</b>
9300 w/Detroit Diesel 8V-92N (12.1L) Eng. Lube Ele. (5573013)..... <b>P20-HD</b> Lube Spin-on (23530407)..... <b>B95 +</b> Lube Spin-on (23530408)..... <b>B95-MPG +</b> P. Fuel Ele. (9717391)..... <b>PF845</b> P. Fuel Spin-on (23530706)..... <b>BF5800 +</b> S. Fuel Ele. (5574508)..... <b>PF902</b> S. Fuel Spin-on (23530707)..... <b>BF5810</b> S. Fuel Spin-on (23530645)..... <b>BF5815</b>	9370 w/Cummins L10 (10.0L) Eng. F-F Lube Spin-on..... <b>B196 +</b> B-P Lube Ele..... <b>C750-E +</b> B-P Lube Spin-on..... <b>B7577</b> Fuel Spin-on..... <b>BF957 +</b> Air (420051-C1)..... <b>PA2333</b> Coolant..... <b>BW5071</b>	9370 w/Detroit Diesel 8V-92 (12.1L) Eng. F-F Lube Ele..... <b>P20-HD</b> F-F Lube Spin-on..... <b>B95 +</b> P. Fuel Spin-on..... <b>BF5800 +</b> S. Fuel Spin-on..... <b>BF5810</b> Air (420051-C1)..... <b>PA2333</b>
9300 w/Detroit Diesel Series 60 (11.1L) & (12.7L) Eng. F-F Lube (23530573)..... <b>[2] B495</b> F-F Lube (Upgrade) (Don. DELF3998)..... <b>[2] B495-SS</b> P. Fuel (23530706)..... <b>BF5800 +</b> S. Fuel (23530707)..... <b>BF5810</b> Radial Seal Air (1694039-C1)..... <b>RS3530</b> Radial Seal XP Air (1694039-C1)..... <b>RS3530XP</b> Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b> Air Dryer (Wabco R950011)..... <b>BA5374 +</b> Coolant (1822627-C1)..... <b>BW5071</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Steering (279294-C92)..... <b>PT903</b>	9370 w/Cummins NTC350 Eng. B-P Lube (1666053-C1)..... <b>B7577</b> Fuel/Water Separator (1214920-H1)..... <b>BF1212 +</b> Fuel/Water Separator (w/Drain) (Fleetguard FS19513)..... <b>BF5813 +</b> Fuel/Water Separator (Open End for Bowl) (Fleetguard FS19513).... <b>BF5813-O +</b> Fuel Spin-on (244458-R91)..... <b>BF957 +</b> Single Air (Fleetguard AF870)..... <b>PA2393</b> O. Air (476741-C1)..... <b>PA2521</b> I. Air (482644-C1)..... <b>PA2522</b> Air Dryer (AD-4 System) (Bendix 107796)..... <b>BA5377</b> Coolant (258265)..... <b>BW5076</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Steering (598698-C1)..... <b>P528</b>	9400 w/Cat 3176 (10.3L) Eng. F-F Lube (1R0716)..... <b>B99 +</b> F-F Lube (1R1808)..... <b>B7299 +</b> F-F Lube (1R0713)..... <b>BT230 +</b> F-F Lube (1R0714)..... <b>B75</b> B-P Lube (1W8845)..... <b>B7577</b> Fuel/Water Separator Ele. (8N0205)..... <b>PF316</b> Fuel/Water Separator Spin-on (2568753)..... <b>BF1259</b> P. Fuel (1R1740)..... <b>BF970 +</b> S. Fuel (1R0750)..... <b>BF7633 +</b> Coolant (w/4 Units BTE) (9N3717)..... <b>BW5137</b> Coolant (w/8 Units BTE) (9N3366)..... <b>BW5139</b>
9300 w/DT466 (7.6L) Eng. Lube (1808896C1)..... <b>[2] B299 +</b> Lube (1811953C1)..... <b>[2] B309</b> Fuel/Water Separator Ele. (1842638C92)..... <b>PF7779</b> Fuel (625625C1)..... <b>BF984</b> Fuel (625627C1)..... <b>BF979 +</b> Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> Coolant (w/12 Units BTA+) (1820361C1)..... <b>BW5074</b>	9370 w/Cummins N14 (14.0L) Eng. F-F Lube Spin-on..... <b>B196 +</b> B-P Lube Ele..... <b>C750-E +</b> B-P Lube Spin-on..... <b>B7577</b> Fuel Spin-on..... <b>BF957 +</b> Air (420051-C1)..... <b>PA2333</b> Coolant..... <b>BW5071</b>	9400 w/Cat 3406 (14.6L) Eng. Lube..... <b>B99 +</b> Fuel/Water Separator (w/Drain) (Fleetguard FS19513)..... <b>BF5813 +</b> Fuel/Water Separator (Open End for Bowl) (Fleetguard FS19513).... <b>BF5813-O +</b> Fuel Spin-on (1R0712)..... <b>BF614 +</b> Axial Seal Air (420051-C1)..... <b>PA2333</b> Radial Seal Air (1694039-C1)..... <b>RS3530</b> Radial Seal XP Air (1694039-C1)..... <b>RS3530XP</b> Air Dryer (AD-9 System) (Bendix 65624)..... <b>BA5373</b> Coolant (w/4 Units BTE)..... <b>BW5137</b> Coolant (w/4 Units BTA+) (1822627-C1)..... <b>BW5071</b> Coolant (w/8 Units BTE)..... <b>BW5139</b> Coolant (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> <b>2 25/32 In. Steering</b> (279294-C92)..... <b>PT951</b> <b>4 3/16 In. Steering</b> (598698-C1).. <b>P528</b>
9370 w/Cat 3406 (14.6L) Eng. Lube..... <b>B99 +</b> Fuel/Water Separator (598435-C1)..... <b>BF1212 +</b> Fuel Spin-on..... <b>BF614 +</b> Axial Seal Air (Fleetguard AF870)..... <b>PA2393</b> Axial Seal Air (w/Lid) (Don. P181099)..... <b>PA2333</b> Radial Seal O. Air (1694039-C1). <b>RS3530</b> Radial Seal XP O. Air (1694039-C1)..... <b>RS3530XP</b> Radial Seal I. Air (2003338-C92). <b>RS3531</b>	9370 w/Cummins N14 (14.0L) Eng. F-F Lube Spin-on..... <b>B196 +</b> B-P Lube Ele..... <b>C750-E +</b> B-P Lube Spin-on..... <b>B7577</b> Fuel Spin-on..... <b>BF957 +</b>	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
9400 w/Cummins L10 (10.0L) Eng. Dual-Flow Lube (Fleetguard LF3000)..... <b>BD103 +</b> F-F Lube (Std. Version) (Fleetguard LF670SC)..... <b>B196 +</b> F-F Lube (Ext. Life) (Fleetguard LF670SC)..... <b>B96 +</b> B-P Lube (1W8845)..... <b>B7577</b> Fuel/Water Separator (154789)... <b>BF957-D +</b> Coolant (w/4 Units BTA+) (3315116)..... <b>BW5071</b> Coolant (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b>	9400 SBA, 9400i SBA w/Cummins ISM (10.8L) Eng. (Cont'd) 9 5/32 In. Fuel (Fleetguard FF2200)..... <b>BF7766</b> 11 7/32 In. Fuel (3563465-C1).... <b>BF596 +</b> Radial Seal O. Air (Standard) (3520400-C1)..... <b>RS3518</b> Radial Seal O. Air (Upgrade) (DBA5069)..... <b>RS3518XP</b> Cab Air (1699956-C1)..... <b>PA5637</b> Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b> Air Dryer (AD-SP System) (Bendix 109994)..... <b>BA5374 +</b> Crankcase Breather (3683918)... <b>CV15000</b> Coolant (w/4 Units BTA+)..... <b>BW5071</b> Coolant (w/4 Units BTE)..... <b>BW5137</b> Coolant (w/11 1/2 Units BTA+) (Fleetguard WF2126)..... <b>BW5086</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Steering (2503221-C1)..... <b>BT9388</b>	9400i SBA w/Cat C12 (12.0L) Eng. (Cont'd) Fuel Ele. (9M2342)..... <b>[2] PF935</b> Fuel Spin-on (Standard Vers.) (4N5823)..... <b>BF614 +</b> Fuel Spin-on (High Efficiency Vers.)..... <b>BF7587 +</b> Radial Seal Air (Standard) (3516347-C92)..... <b>RS3518</b> Radial Seal Air (Upgrade) (3516347-C92)..... <b>RS3518XP</b> Air Dryer (AD-IP System) (Bendix 65624)..... <b>BA5373</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Steering (2503221-C1)..... <b>BT9388</b>
9400 w/Cummins M11 (10.8L) Eng. Dual-Flow Lube (3318853)..... <b>BD103 +</b> Fuel/Water Separator Ele. (Fleetguard FS1029W)..... <b>PF7680</b> Fuel/Water Separator Spin-on (2568753)..... <b>BF1259</b>	9400i SBA w/Cat 3406 (14.6L) Eng. Lube (Standard Vers.) (1R0716).. <b>B99 +</b> Lube (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> Fuel/Water Separator (2568753). <b>BF1259</b> Fuel/Water Separator (w/Drain) (Fleetguard FS19513)..... <b>BF5813 +</b> Fuel/Water Separator (Open End for Bowl) (Fleetguard FS19513).... <b>BF5813-O +</b> Fuel Ele. (9M2342)..... <b>[2] PF935</b> Fuel Spin-on (Standard Vers.) (4N5823)..... <b>BF614 +</b> Fuel Spin-on (High Efficiency Vers.)..... <b>BF7587 +</b> Axial Seal Air (420051-C1)..... <b>PA2333</b> Radial Seal XP Air (1694039-C1)..... <b>RS3530XP</b> Air Dryer (AD-9 System) (Bendix 65624)..... <b>BA5373</b> Coolant (w/4 Units BTE)..... <b>BW5137</b> Coolant (w/4 Units BTA+) (1822627-C1)..... <b>BW5071</b> Coolant (w/8 Units BTE)..... <b>BW5139</b> Coolant (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> 2 25/32 In. Steering (279294-C92)..... <b>PT951</b> 4 3/16 In. Steering (598698-C1).. <b>P528</b>	9400i SBA w/Cat C13 (12.5L) Eng. (To 1/2004) Lube (1R0716)..... <b>B99 +</b> Fuel/Water Separator Ele. (2588149C1)..... <b>PF7748</b> Fuel/Water Separator Ele. (Davco Hsg.)..... <b>PF7680</b> Fuel/Water Separator Ele. (Fleetguard FS19729)..... <b>PF7755</b> Fuel/Water Separator (Fleetguard FS1212)..... <b>BF1212 +</b> Fuel/Water Separator (Open End for Bowl) (1335673)..... <b>BF1395-O</b> Fuel/Water Separator (w/Drain) (1335673)..... <b>BF1265</b> Fuel/Water Separator (w/Sensor Port) (1335673)..... <b>BF1395-SP</b> Fuel Ele. (9M2342)..... <b>PF935</b> Fuel Spin-on (1R0749)..... <b>BF7587 +</b> Radial Seal O. Air (2005895-C1). <b>RS3530</b> Radial Seal XP O. Air (2005895-C1)..... <b>RS3530XP</b> Radial Seal I. Air (2022289-C1)... <b>RS3531</b> Radial Seal Air (Standard) (3560734-C1)..... <b>RS3518</b> Radial Seal XP Air (Upgrade) (3560734-C1)..... <b>RS3518XP</b> Cab Air (1699956-C1)..... <b>PA5637</b> Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b> Air Dryer (AD-SP System) (Bendix 109994)..... <b>BA5374 +</b> Coolant (w/4 units BTA+)..... <b>BW5071</b> Coolant (w/4 units BTE) (9N3368)..... <b>BW5137</b> Coolant (w/8 units BTE) (9N3367)..... <b>BW5139</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Steering (2503221-C1)..... <b>BT9388</b> Some Differential (1685141-C1). <b>B233</b>
9400 w/Detroit Diesel Series 60 (11.1L) & (12.7L) Eng. Lube..... <b>[2] B495</b> Fuel/Water Separator (1696265-C1)..... <b>PF7680</b> P. Fuel..... <b>BF5800 +</b> S. Fuel..... <b>BF5810</b> Radial Seal O. Air (2005895-C1). <b>RS3530</b> Radial Seal XP O. Air (2005895-C1)..... <b>RS3530XP</b> Radial Seal I. Air (2022289-C1)... <b>RS3531</b> Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b> Coolant (w/4 Units BTA+) (1822627-C1)..... <b>BW5071</b> Coolant (Controlled Release BTE) (Nalcool NF2088)..... <b>BW5200</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Steering (1698964-C91)..... <b>PT9354-MPG</b>	9400 SBA, 9400i SBA w/Cummins ISM (10.8L) Eng. Dual-Flow Lube (Fleetguard LF9001)..... <b>BD7154 +</b> Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> Fuel/Water Separator Ele..... <b>PF7755</b> Fuel/Water Separator Spin-on (Fleetguard FS1003)..... <b>BF1293-SPS</b> Fuel/Water Separator Spin-on (3329289)..... <b>BF1259</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
9400i SBA w/Cat C13 (12.5L) Eng. (1/2004-on)	9400i SBA w/Cat C15 (14.6L) Eng. (To 1/2004)	9400i SBA w/Cat C15 (14.6L) Eng. (1/2004-on)
Lube (1R1808)..... B7299 +	(Cont'd)	(Cont'd)
Fuel/Water Separator Ele. (2588149C1)..... PF7748	Radial Seal XP O. Air (2005895-C1)..... RS3530XP	Trans. (Fuller 4304827)..... BT223
Fuel/Water Separator Ele. (Davco Hsg.)..... PF7680	Radial Seal I. Air (2022289-C1)... RS3531	Opt. Trans. (Fuller 17237)..... B2 +
Fuel/Water Separator Ele. (Fleetguard FS19729)..... PF7755	Radial Seal Air (Standard) (3560734-C1)..... RS3518	Steering (2503221-C1)..... BT9388
Fuel/Water Separator Spin-on (Fleetguard FS1212)..... BF1212 +	Radial Seal XP Air (Upgrade) (3560734-C1)..... RS3518XP	Some Differential (1685141-C1). B233
Fuel/Water Separator (Open End for Bowl) (1335673)..... BF1395-O	Cab Air (1699956-C1)..... PA5637	9400i SBA w/Cat C15 (15.2L) Eng. (To 1/2004)
Fuel/Water Separator (w/Drain) (1335673)..... BF1265	Air Dryer (AD-9 System) (Bendix 107796)..... BA5377	Lube (1R0716)..... B99 +
Fuel/Water Separator (w/Sensor Port) (1335673)..... BF1395-SP	Air Dryer (AD-SP System) (Bendix 109994)..... BA5374 +	Fuel/Water Separator Ele. (2588149C1)..... PF7748
Fuel Ele. (9M2342)..... PF935	Coolant (w/4 units BTA+)..... BW5071	Fuel/Water Separator Ele. (Davco Hsg.)..... PF7680
Fuel Spin-on (1R0749)..... BF7587 +	Coolant (w/4 units BTE) (9N3368)..... BW5137	Fuel/Water Separator Ele. (Fleetguard FS19729)..... PF7755
Radial Seal O. Air (2005895-C1). RS3530	Coolant (w/8 units BTE) (9N3367)..... BW5139	Fuel/Water Separator Spin-on (Fleetguard FS1212)..... BF1212 +
Radial Seal XP O. Air (2005895-C1)..... RS3530XP	Trans. (Fuller 4304827)..... BT223	Fuel/Water Separator (Open End for Bowl) (1335673)..... BF1395-O
Radial Seal I. Air (2022289-C1)... RS3531	Opt. Trans. (Fuller 17237)..... B2 +	Fuel/Water Separator (w/Drain) (1335673)..... BF1265
Radial Seal Air (Standard) (3560734-C1)..... RS3518	Steering (2503221-C1)..... BT9388	Fuel/Water Separator (w/Sensor Port) (1335673)..... BF1395-SP
Radial Seal XP Air (Upgrade) (3560734-C1)..... RS3518XP	Some Differential (1685141-C1). B233	Fuel Ele. (9M2342)..... PF935
Cab Air (1699956-C1)..... PA5637	9400i SBA w/Cat C15 (14.6L) Eng. (1/2004-on)	Fuel Spin-on (1R0749)..... BF7587 +
Air Dryer (AD-9 System) (Bendix 107796)..... BA5377	Lube (1R1808)..... B7299 +	Radial Seal O. Air (2005895-C1). RS3530
Air Dryer (AD-SP System) (Bendix 109994)..... BA5374 +	Fuel/Water Separator Ele. (2588149C1)..... PF7748	Radial Seal XP O. Air (2005895-C1)..... RS3530XP
Coolant (w/4 units BTA+)..... BW5071	Fuel/Water Separator Ele. (Davco Hsg.)..... PF7680	Radial Seal I. Air (2022289-C1)... RS3531
Coolant (w/4 units BTE) (9N3368)..... BW5137	Fuel/Water Separator Ele. (Fleetguard FS19729)..... PF7755	Radial Seal Air (Standard) (3560734-C1)..... RS3518
Coolant (w/8 units BTE) (9N3367)..... BW5139	Fuel/Water Separator Spin-on (Fleetguard FS1212)..... BF1212 +	Radial Seal XP Air (Upgrade) (3560734-C1)..... RS3518XP
Trans. (Fuller 4304827)..... BT223	Fuel/Water Separator (Open End for Bowl) (1335673)..... BF1395-O	Cab Air (1699956-C1)..... PA5637
Opt. Trans. (Fuller 17237)..... B2 +	Fuel/Water Separator (w/Drain) (1335673)..... BF1265	Air Dryer (AD-9 System) (Bendix 107796)..... BA5377
Steering (2503221-C1)..... BT9388	Fuel/Water Separator (w/Sensor Port) (1335673)..... BF1395-SP	Air Dryer (AD-SP System) (Bendix 109994)..... BA5374 +
Some Differential (1685141-C1). B233	Fuel Ele. (9M2342)..... PF935	Coolant (w/4 units BTA+)..... BW5071
9400i SBA w/Cat C15 (14.6L) Eng. (To 1/2004)	Fuel Spin-on (1R0749)..... BF7587 +	Coolant (w/4 units BTE) (9N3368)..... BW5137
Lube (1R0716)..... B99 +	Radial Seal O. Air (2005895-C1). RS3530	Coolant (w/8 units BTE) (9N3367)..... BW5139
Fuel/Water Separator Ele. (2588149C1)..... PF7748	Radial Seal XP O. Air (2005895-C1)..... RS3530XP	Trans. (Fuller 4304827)..... BT223
Fuel/Water Separator Ele. (Davco Hsg.)..... PF7680	Radial Seal I. Air (2022289-C1)... RS3531	Opt. Trans. (Fuller 17237)..... B2 +
Fuel/Water Separator Ele. (Fleetguard FS19729)..... PF7755	Radial Seal Air (Standard) (3560734-C1)..... RS3518	Steering (2503221-C1)..... BT9388
Fuel/Water Separator Spin-on (Fleetguard FS1212)..... BF1212 +	Radial Seal XP Air (Upgrade) (3560734-C1)..... RS3518XP	Some Differential (1685141-C1). B233
Fuel/Water Separator (Open End for Bowl) (1335673)..... BF1395-O	Cab Air (1699956-C1)..... PA5637	9400i SBA w/Cat C15 (15.2L) Eng. (1/2004-on)
Fuel/Water Separator (w/Drain) (1335673)..... BF1265	Air Dryer (AD-9 System) (Bendix 107796)..... BA5377	Lube (1R1808)..... B7299 +
Fuel/Water Separator (w/Sensor Port) (1335673)..... BF1395-SP	Air Dryer (AD-SP System) (Bendix 109994)..... BA5374 +	Fuel/Water Separator Ele. (2588149C1)..... PF7748
Fuel Ele. (9M2342)..... PF935	Coolant (w/4 units BTA+)..... BW5071	Fuel/Water Separator Ele. (Davco Hsg.)..... PF7680
Fuel Spin-on (1R0749)..... BF7587 +	Coolant (w/4 units BTE) (9N3368)..... BW5137	Fuel/Water Separator Ele. (Fleetguard FS19729)..... PF7755
Radial Seal O. Air (2005895-C1). RS3530	Coolant (w/8 units BTE) (9N3367)..... BW5139	Fuel/Water Separator Spin-on (Fleetguard FS1212)..... BF1212 +
		Fuel/Water Separator (Open End for Bowl) (1335673)..... BF1395-O

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
9400i SBA w/Cat C15 (15.2L) Eng. (1/2004-on) (Cont'd)	9400i SBA w/Cummins ISX 15.0 (14.9L) Eng. (Cont'd)	9400i SBA w/Cummins Signature 600 (15.0L) Eng.
Fuel/Water Separator (w/Drain) (1335673)..... <b>BF1265</b>	Coolant (w/4 Units BTE)..... <b>BW5137</b>	<b>11 25/32 In. Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154 +</b>
Fuel/Water Separator (w/Sensor Port) (1335673)..... <b>BF1395-SP</b>	Coolant (w/11 1/2 Units BTA+) (Fleetguard WF2126)..... <b>BW5086</b>	<b>14 7/32 In. Dual-Flow Lube</b> (Fleetguard LF9000)..... <b>BD7153 +</b>
Fuel Ele. (9M2342)..... <b>PF935</b>	Trans. (Fuller 4304827)..... <b>BT223</b>	<b>Dual-Flow Lube (Upgrade)</b> (Fleetguard LF14000NN)..... <b>BD50000</b>
Fuel Spin-on (1R0749)..... <b>BF7587 +</b>	Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	Fuel/Water Separator (3331096). <b>BF1274-SP</b>
Radial Seal O. Air (2005895-C1). <b>RS3530</b>	Steering (2503221-C1)..... <b>BT9388</b>	Fuel/Water Separator (4010651). <b>BF1277-SPS</b>
Radial Seal XP O. Air (2005895-C1)..... <b>RS3530XP</b>	9400i SBA w/Cummins N14 (14.0L) Eng.	Radial Seal O. Air (2005895-C1). <b>RS3530</b>
Radial Seal I. Air (2022289-C1)... <b>RS3531</b>	Dual-Flow Lube (Std. Vers.) (3825970)..... <b>BD103 +</b>	Radial Seal XP O. Air (2005895-C1)..... <b>RS3530XP</b>
Radial Seal Air (Standard) (3560734-C1)..... <b>RS3518</b>	Dual-Flow Lube (High Velocity) (Fleetguard LF9009)..... <b>BD7309 +</b>	Radial Seal I. Air (2022289-C1)... <b>RS3531</b>
Radial Seal XP Air (Upgrade) (3560734-C1)..... <b>RS3518XP</b>	Fuel/Water Separator Ele. (2503566-C1)..... <b>PF7680</b>	Coolant (Fleetguard WF2126)..... <b>BW5086</b>
Cab Air (1699956-C1)..... <b>PA5637</b>	Fuel/Water Separator Ele. (2588149-C1)..... <b>PF7748</b>	9400i SBA w/Detroit Diesel Series 50 (8.5L) Eng.
Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	7 7/16 In. Fuel/Water Separator Spin-on (3315843)..... <b>BF1212 +</b>	Lube (23530573)..... <b>[2] B495</b>
Air Dryer (AD-SP System) (Bendix 109994)..... <b>BA5374 +</b>	9 17/32 In. Fuel/Water Separator Spin-on..... <b>BF1259</b>	Fuel/Water Separator Spin-on (w/Drain) (23535985)..... <b>BF5813 +</b>
Coolant (w/4 units BTA+)..... <b>BW5071</b>	Fuel/Water Separator Spin-on (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b>	Fuel/Water Separator Spin-on (Open End for Bowl) (23535985).. <b>BF5813-O +</b>
Coolant (w/4 units BTE) (9N3368)..... <b>BW5137</b>	Fuel/Water Separator Spin-on (w/Bowl) (Mann WK1060/1)..... <b>BF46072</b>	P. Fuel (23530706)..... <b>BF5800 +</b>
Coolant (w/8 units BTE) (9N3367)..... <b>BW5139</b>	Fuel/Water Separator Spin-on (w/Drain) (Mann WK1060/1)..... <b>BF1329</b>	S. Fuel (23530707)..... <b>BF5810</b>
Trans. (Fuller 4304827)..... <b>BT223</b>	Fuel/Water Separator Spin-on (Sensor Port Thd. 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b>	9400i SBA w/Detroit Diesel Series 55 (12.0L) Eng.
Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	Fuel/Water Separator Spin-on (Sensor Port Thd. 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b>	Lube (23550401)..... <b>B7135</b>
Steering (2503221-C1)..... <b>BT9388</b>	Radial Seal Air (Standard) (3516347-C92)..... <b>RS3518</b>	Fuel (23530707)..... <b>BF5810</b>
Some Differential (1685141-C1). <b>B233</b>	Radial Seal Air (Upgrade) (3516347-C92)..... <b>RS3518XP</b>	9400i SBA w/Detroit Diesel Series 60 (11.1L) & (12.7L) Eng.
9400i SBA w/Cummins ISX 15.0 (14.9L) Eng.	Radial Seal O. Air (2005895-C1). <b>RS3530</b>	F-F Lube (23530573)..... <b>[2] B495</b>
Dual-Flow Lube (Fleetguard LF9001)..... <b>BD7154 +</b>	Radial Seal XP O. Air (2005895-C1)..... <b>RS3530XP</b>	Fuel/Water Separator (1696265C1)..... <b>PF7680</b>
Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>	Radial Seal I. Air (2022289-C1)... <b>RS3531</b>	P. Fuel (23530706)..... <b>BF5800 +</b>
Fuel/Water Separator Ele. (Fleetguard FF5369)..... <b>PF7744</b>	Air Dryer (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	S. Fuel..... <b>BF5810</b>
Fuel/Water Separator Ele. (Fleetguard FS19729)..... <b>PF7755</b>	Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	Radial Seal O. Air (2003338-C92)..... <b>RS3530</b>
Fuel/Water Separator Spin-on..... <b>BF1274-SP</b>	Coolant (3844234)..... <b>BW5076</b>	Radial Seal XP O. Air (2003338-C92)..... <b>RS3530XP</b>
Fuel/Water Separator Spin-on (Fleetguard FS1040)..... <b>BF1277-SPS</b>	Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	Radial Seal I. Air (2003338-C92). <b>RS3531</b>
Fuel (Fleetguard FF2200)..... <b>BF7766</b>	2 23/32 In. Steering Ele. (1698964-C91)..... <b>PT9354-MPG</b>	Radial Seal O. Air (Standard) (3520400-C1)..... <b>RS3518</b>
Fuel (Fleetguard FF2203)..... <b>BF7760</b>	2 25/32 In. Steering Ele. (279294C92)..... <b>PT903</b>	Radial Seal XP O. Air (Upgrade) (DBA5069)..... <b>RS3518XP</b>
Radial Seal Air (Standard) (3560734-C1)..... <b>RS3518</b>	4 3/16 In. Steering Ele. (598698C1)..... <b>P528</b>	Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
Radial Seal XP Air (Upgrade) (3560734-C1)..... <b>RS3518XP</b>	Steering Spin-on (2503221-C1).. <b>BT9388</b>	Air Dryer (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>
Cab Air (1699956-C1)..... <b>PA5637</b>		Coolant (w/4 Units BTA+) (1822627-C1)..... <b>BW5071</b>
Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b>		Coolant (Controlled Release BTE) (Nalcool NF2088)..... <b>BW5200</b>
Air Dryer (AD-SP System) (Bendix 109994)..... <b>BA5374 +</b>		Opt. Trans. (Fuller 17237)..... <b>B2 +</b>
Air Dryer (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>		Steering (2503221-C1)..... <b>BT9388</b>
Crankcase Breather (3683918).. <b>CV15000</b>		
Coolant (w/o Chemical) (Fleetguard WF2127)..... <b>B5087</b>		
Coolant (w/4 Units BTA+)..... <b>BW5071</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
9600 Series w/Cummins L10 (10.0L) Eng. <b>Dual-Flow Lube</b> (3825970)..... <b>BD103+</b> <b>F-F Lube</b> (3889310)..... <b>B196+</b> <b>B-P Lube</b> (3889311)..... <b>B7577</b> <b>Conical 23 In. Air</b> (574844C1)..... <b>PA2703</b> <b>Conical 25 In. Air</b> (594240C1)..... <b>PA2631</b> <b>Conical 29 In. Air</b> (587425C1)..... <b>PA2500+</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2+</b> <b>2 25/32 In. Steering</b> (w/Gskt.) (279294C92)..... <b>PT903</b> <b>2 25/32 In. Steering</b> (w/o Gskt.) (279294C92)..... <b>PT951</b> <b>4 3/16 In. Steering</b> (598698C1).... <b>P528</b>	9600 w/Detroit Diesel Series 60 (11.1L) & (12.7L) Eng. (Cont'd) <b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b> <b>Coolant</b> (Controlled Release) (Nalcool NF2088)..... <b>BW5200</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2+</b> <b>Steering</b> ..... <b>PT951</b> 9600, 9670, 9700 Series w/Cat 3406, 3406B Engs. <b>Lube</b> ..... <b>B99+</b> <b>Fuel/Water Separator</b> (Fleetguard FF105D)..... <b>BF957-D+</b> <b>Fuel/Water Separator</b> (Fleetrite FSR81213)..... <b>BF1213</b> <b>Fuel/Water Separator</b> (Fleetguard FS1212)..... <b>BF1212+</b> <b>Fuel Ele.</b> (151940)..... <b>PF116</b> <b>Fuel Spin-on</b> ..... <b>BF614+</b> <b>28 1/2 In. Air</b> (Fleetrite AFR81846)..... <b>PA2660</b> <b>29 In. Air</b> (587426-C1)..... <b>PA3951</b> <b>Air Dryer</b> (AD-4 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (w/o Chemical) (Fleetrite WFR82077)..... <b>B5134+</b> <b>Coolant</b> (w/6 Units BTA+) (Fleetrite WFR82072)..... <b>BW5072</b> <b>Coolant</b> (w/12 Units BTA+) (Fleetrite WFR82074)..... <b>BW5074</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2+</b> <b>Steering</b> (279294-C92)..... <b>PT903</b> <b>Some Differential</b> (1665311-C1). <b>B233</b>	9670 Series w/Cummins KTA525, KTA600 Engs. <b>F-F Lube Spin-on</b> ..... <b>[2] B196+</b> <b>B-P Lube Ele</b> ..... <b>C750-E+</b> <b>Fuel Spin-on</b> ..... <b>[2] BF957+</b> <b>Coolant</b> ..... <b>BW5073</b> 9700 Series w/Cat 3176B Eng. <b>F-F Lube</b> (1R0716)..... <b>B99+</b> <b>F-F Lube</b> (High Efficiency) (1R1808)..... <b>B7299+</b> <b>Fuel/Water Separator</b> (Fleetguard FS1212)..... <b>BF1212+</b> <b>Fuel/Water Separator</b> (w/o SP) (1685159-C91)..... <b>BF1346+</b> <b>Fuel/Water Separator</b> (w/SP) (1685159-C91)..... <b>BF1346-SP+</b> <b>Air</b> (1651566-C1)..... <b>[2] PA2718</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134+</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/6 Units BTA+) (Fleetguard WF2072)..... <b>BW5072</b> <b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b> <b>Coolant</b> (Controlled Release) (Nalcool NF2088)..... <b>BW5200</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2+</b> <b>Steering</b> (Fleetguard LF634)..... <b>PT903</b> 9700 Series w/Cummins L10 (10.0L) Eng. <b>Dual-Flow Lube</b> (3825970)..... <b>BD103+</b> <b>F-F Lube</b> (3889310)..... <b>B196+</b> <b>B-P Lube</b> (3889311)..... <b>B7577</b> <b>Fuel</b> (3315844)..... <b>BF957+</b> <b>23 In. Conical Air</b> (Fleetguard AF1742M)..... <b>PA2623</b> <b>25 In. Conical Air</b> (594240C1)..... <b>PA2631</b> <b>28 1/2 In. Conical Air</b> (Don. P150694)..... <b>PA2660</b> <b>29 In. Conical Air</b> (587425C1)..... <b>PA2500+</b> <b>Air</b> (w/Lid) (1651566C1)..... <b>PA2718</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2+</b> <b>2 25/32 In. Steering</b> (w/o Gskt.) (279294C92)..... <b>PT951</b> <b>2 25/32 In. Steering</b> (w/Gskt.) (279294C92)..... <b>PT903</b> <b>4 3/4 In. Steering</b> (598698C1)..... <b>P528</b>
9600 Series w/Cummins M11 (10.8L) Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103+</b> <b>Fuel/Water Separator</b> (Fleetguard FS1212)..... <b>BF1212+</b> <b>Fuel/Water Separator</b> (1660332-C1)..... <b>BF957-D+</b> <b>Fuel</b> (13/16-12 Thd.) (Fleetguard FF5206)..... <b>BF5810</b> <b>Fuel</b> (1-14 Thd.) (1613245-C2).... <b>BF880-FP</b> <b>Conical Air</b> (Fleetguard AF1742M)..... <b>PA2623</b> <b>22 9/16 In. Air</b> (Fleetguard AF1968M)..... <b>PA2705</b> <b>28 1/2 In. Air</b> (1651566-C1)..... <b>PA2718</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2+</b> <b>Steering</b> (Fleetguard LF634)..... <b>PT903</b>	9600 w/Cummins N14 (14.0L) Eng. <b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196+</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103+</b> <b>Fuel/Water Separator</b> (Fleetguard FS1212)..... <b>BF1212+</b> <b>Fuel</b> (154789)..... <b>BF957-D+</b> <b>Air</b> (Fleetguard AF1846)..... <b>PA2660</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2+</b> <b>Steering</b> (Fleetguard LF634)..... <b>PT903</b>	9670 Series w/Cummins Formula 270, Formula 290, Formula 300, NTC300, Formula 350, NTC350 Engs. <b>F-F Lube Ele</b> ..... <b>P999-HD</b> <b>F-F Lube Spin-on</b> ..... <b>B196+</b> <b>B-P Lube Ele</b> ..... <b>C750-E+</b> <b>B-P Lube Spin-on</b> ..... <b>B7577</b> <b>Fuel Spin-on</b> ..... <b>BF957+</b> <b>Air</b> (587426-C1)..... <b>PA3951</b> <b>Coolant</b> (Maintenance)..... <b>BW5071</b> 9670 Series w/Cummins Formula 400 Big Cam IV Eng. <b>F-F Lube Spin-on</b> ..... <b>B196+</b> <b>B-P Lube Spin-on</b> ..... <b>B7577</b> <b>Fuel Spin-on</b> ..... <b>BF957+</b>
9600 w/Detroit Diesel Series 60 (11.1L) & (12.7L) Eng. <b>Lube</b> ..... <b>[2] B495</b> <b>P. Fuel</b> ..... <b>BF5800+</b> <b>S. Fuel</b> ..... <b>BF5810</b> <b>Radial Seal O. Air</b> (2005895-C1). <b>RS3530</b> <b>Radial Seal XP O. Air</b> (2005895-C1)..... <b>RS3530XP</b> <b>Radial Seal I. Air</b> (2022289-C1)... <b>RS3531</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134+</b> <b>Coolant</b> (w/4 Units BTA+) (1822627-C1)..... <b>BW5071</b> <b>Coolant</b> (w/6 Units BTA+) (Fleetguard WF2072)..... <b>BW5072</b>	9670 Series w/Cummins NTC400, NTCC400 Engs. <b>F-F Lube Spin-on</b> ..... <b>B196+</b> <b>B-P Lube Ele</b> ..... <b>C750-E+</b> <b>Fuel Spin-on</b> ..... <b>BF957+</b> <b>Air</b> (574845-C1)..... <b>PA2623</b> <b>Air</b> (587425-C1)..... <b>PA2500+</b> <b>Air</b> (587426-C1)..... <b>PA3951</b> <b>Coolant</b> (Maintenance)..... <b>BW5071</b>	9700 Series w/Cummins NTC Eng. <b>Fuel</b> (154709)..... <b>BF957+</b> <b>Air</b> (Donaldson Hsg.) (573138-C91)..... <b>PA2660</b> <b>Air</b> (Farr Hsg.) (Fleetrite AHR81103)..... <b>PA2650</b> <b>Coolant</b> (w/o Chemical) (Fleetrite WFR82077)..... <b>B5134+</b> <b>Coolant</b> (w/6 Units BTA+) (Fleetrite WFR82072)..... <b>BW5072</b>

+ See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
9700 Series w/Cummins NTC Eng. (Cont'd) <b>Coolant</b> (w/12 Units BTA+) (Fleetrite WFR82074)..... <b>BW5074</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2</b> + <b>Steering</b> (w/Gasket) (279294-C92)..... <b>PT903</b> <b>Steering</b> (w/o Gasket) (279294-C92)..... <b>PT951</b> <b>Some Differential</b> (1665311-C1)..... <b>B233</b>	9700 Series w/Detroit Series 60 (11.1L) & (12.7L) Eng. (Cont'd) <b>Coolant</b> (Controlled Release) (Nalcool NF2088)..... <b>BW5200</b> <b>Steering</b> (Fleetguard LF634)..... <b>PT903</b> 9800 SBA w/Cummins ISM (10.8L) Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154</b> + <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF1400NN)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (2503566-C1)..... <b>PF7680</b> <b>Fuel/Water Separator Ele.</b> (2588149C1)..... <b>PF7748</b> <b>Radial Seal Air</b> (1698941-C1)..... <b>RS3516</b> <b>Radial Seal XP Air</b> (Don. DBA5106)..... <b>RS3516XP</b> <b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b> <b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2</b> + <b>Steering</b> (279294-C92)..... <b>PT903</b>	9800 SBA w/Detroit Diesel Series 60 (11.1L) & (12.7L) Eng. <b>Lube</b> ..... [2] <b>B495</b> <b>Fuel/Water Separator Ele.</b> (1696265-C1)..... <b>PF7680</b> <b>P. Fuel</b> (1-12 Thd.)..... <b>BF5800</b> + <b>P. Fuel</b> (1-14 Thd.) (Fleetguard FF5290)..... <b>BF880-FP</b> <b>S. Fuel</b> ..... <b>BF5810</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2</b> + <b>Steering</b> (279294-C92)..... <b>PT951</b>
9700 Series w/Cummins M11 (10.8L) Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103</b> + <b>Fuel/Water Separator</b> (Fleetguard FS1212)..... <b>BF1212</b> + <b>Fuel/Water Separator</b> (1660332-C1)..... <b>BF957-D</b> + <b>Fuel</b> (13/16-12 Thd.) (Fleetguard FF5206)..... <b>BF5810</b> <b>Fuel</b> (1-14 Thd.) (1613245-C2)..... <b>BF880-FP</b> <b>Conical Air</b> (Fleetguard AF1742M)..... <b>PA2623</b> <b>22 9/16 In. Air</b> (Fleetguard AF1968M)..... <b>PA2705</b> <b>28 1/2 In. Air</b> (1651566-C1)..... <b>PA2718</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2</b> + <b>Steering</b> (Fleetguard LF634)..... <b>PT903</b>	9800 SBA w/Cummins M11 (10.8L) Eng. <b>F-F Lube</b> (1665311-C1)..... <b>B233</b> <b>Dual-Flow Lube</b> ..... <b>BD103</b> + <b>Fuel/Water Separator Ele.</b> (1696265-C1)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> (1-14 Thd.)..... <b>BF1212</b> + <b>Fuel</b> (13/16-12 Thd.) (Fleetguard FF5206)..... <b>BF5810</b> <b>Fuel</b> (1613245-C2)..... <b>BF880-FP</b> <b>Radial Seal Air</b> (1698941-C1)..... <b>RS3516</b> <b>Radial Seal XP Air</b> (Don. DBA5106)..... <b>RS3516XP</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2</b> + <b>Opt. Trans.</b> (Fleetguard HF6107)..... <b>B252</b> <b>Steering</b> (279294-C92)..... <b>PT903</b> <b>Some Differential</b> (Fleetguard LF689)..... <b>B233</b>	9900i w/Cat C12, C13 Eng. <b>Lube</b> (To 1/2004) (1R0716)..... <b>B99</b> + <b>Lube</b> (1/2004-on) (1R1808)..... <b>B7299</b> + <b>Fuel/Water Separator</b> (Fleetguard FS19729)..... <b>PF7755</b> <b>Fuel</b> (1R0749)..... <b>BF7587</b> + <b>Fuel</b> (3563465-C1)..... <b>BF596</b> + <b>Radial Seal Air</b> (3507421-C1)..... [2] <b>RS3743</b> <b>Radial Seal O. Air</b> (Standard) (3560734-C1)..... <b>RS3518</b> <b>Radial Seal XP O. Air</b> (Upgrade) (3560734-C1)..... <b>RS3518XP</b> <b>Radial Seal I. Air</b> (3520401-C1)..... <b>RS3519</b> <b>Cab Air</b> (1699956-C1)..... <b>PA5637</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-SP System) (Bendix 109994)..... <b>BA5374</b> + <b>Crankcase Breather</b> (C13 2007-on) (296-8325)..... <b>CV15008</b> <b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134</b> + <b>Coolant</b> (w/4 units BTA+)..... <b>BW5071</b> <b>Coolant</b> (w/4 units BTE)..... <b>BW5137</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2</b> + <b>Steering</b> (2503221-C1)..... <b>BT9388</b>
9700 Series w/Cummins N14 (14.0L) Eng. <b>Dual-Flow Lube</b> ..... <b>BD103</b> + <b>F-F Lube</b> ..... <b>B196</b> + <b>B-P Lube</b> ..... <b>B7577</b> <b>Opt. Fuel/Water Separator</b> ..... <b>BF1212</b> + <b>Fuel Spin-on</b> ..... <b>BF957-D</b> + <b>Air</b> (Fleetguard AF1846)..... <b>PA2660</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2</b> + <b>Steering</b> (w/o Gskt.) (279294-C92)..... <b>PT951</b> <b>Steering</b> (w/Gskt.) (Fleetguard LF634)..... <b>PT903</b>	9800 SBA w/Cummins N14 (14.0L) Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309</b> + <b>Fuel/Water Separator</b> (Fleetguard FS1000)..... <b>BF1259</b> <b>Radial Seal Air</b> (1698941-C1)..... <b>RS3516</b> <b>Radial Seal XP Air</b> (Don. DBA5106)..... <b>RS3516XP</b> <b>Air Dryer</b> (Wabco R950011)..... <b>BA5374</b> + <b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2</b> + <b>Steering</b> (w/Gasket) (279294-C92)..... <b>PT903</b> <b>Steering</b> (w/o Gasket) (279294-C92)..... <b>PT951</b>	9900i w/Cat C15 Eng. <b>Lube</b> (To 1/2004) (1R0716)..... <b>B99</b> + <b>Lube</b> (1/2004-on) (1R1808)..... <b>B7299</b> + <b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b> <b>Fuel/Water Separator Ele.</b> ..... <b>PF7755</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19624)..... <b>PF7748</b> <b>Fuel/Water Separator Spin-on</b> (598435-C1)..... <b>BF1212</b> + <b>Fuel</b> (1R0749)..... <b>BF7587</b> + <b>Fuel</b> (3563465-C1)..... <b>BF596</b> + <b>Radial Seal Air</b> (3507421-C1)..... [2] <b>RS3743</b> <b>Radial Seal Air</b> (Standard) (3560734-C1)..... <b>RS3518</b> <b>Radial Seal XP Air</b> (Upgrade) (3560734-C1)..... <b>RS3518XP</b> <b>Cab Air</b> (1699956-C1)..... <b>PA5637</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
9900i w/Cat C15 Eng. (Cont'd)	9900i w/Cummins ISX 15.0 (14.9L) Eng. (To 2017) (Cont'd)	9900i, 9900ix w/Cummins Signature 600 Eng.
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (2510993C1)..... <b>BF1395-O</b>	<b>14 7/32 In. Dual-Flow Lube</b> ..... <b>BD7153 +</b>
<b>Air Dryer</b> (AD-SP System) (Bendix 109994)..... <b>BA5374 +</b>	<b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (2510993C1)..... <b>BF1395-SP</b>	<b>Opt. 11 13/16 In. Dual-Flow Lube Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>
<b>Crankcase Breather</b> (2007-on) (296-8325)..... <b>CV15008</b>	<b>S. Fuel</b> (Fleetguard FF2200)..... <b>BF7766</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1007)..... <b>BF1274-SP</b>
<b>Opt. Crankcase Breather</b> (3805839)..... <b>CV15007</b>	<b>Fuel</b> (Fleetguard FF2203)..... <b>BF7760</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1040)..... <b>BF1277-SPS</b>
<b>Coolant</b> (w/4 units BTA+)..... <b>BW5071</b>	<b>Fuel</b> (2010 Emissions) (Fleetguard FF5686)..... <b>BF9860 +</b>	<b>Coolant</b> (w/11 1/2 Units BTA+) (Fleetguard WF2126)..... <b>BW5086</b>
<b>Coolant</b> (w/4 units BTE)..... <b>BW5137</b>	<b>Fuel</b> (2010 Emissions) (Fleetguard FF5776)..... <b>BF9885 +</b>	<b>Coolant</b> (w/o Chemicals) (Fleetguard WF2127)..... <b>B5087</b>
<b>Coolant</b> (w/8 units BTE) (9N-3718)..... <b>BW5139</b>	<b>Fuel</b> (Upgrade) (Fleetguard FF5825NN)..... <b>BF46129</b>	<b>Steering</b> (2503221-C1)..... <b>BT9388</b>
<b>Trans.</b> (Fuller 4304827)..... <b>BT223</b>	<b>Radial Seal Air</b> (Standard) (3560734-C1)..... <b>RS3518</b>	9900ix w/Cat C15, C16 Engs.
<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	<b>Radial Seal XP Air</b> (Upgrade) (3560734-C1)..... <b>RS3518XP</b>	<b>Lube</b> (To 1/2004) (1R0716)..... <b>B99 +</b>
<b>Steering</b> (2503221-C1)..... <b>BT9388</b>	<b>Radial Seal Air</b> (3507421-C1)..... <b>[2] RS3743</b>	<b>Lube</b> (1/2004-on) (1R1808)..... <b>B7299 +</b>
<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Cab Air</b> (1699956C1)..... <b>PA5637</b>	<b>Fuel/Water Separator Ele.</b> (Davco)..... <b>PF7680</b>
9900i w/Cat 3406 Eng.	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Fuel/Water Separator Ele.</b> (Davco 382114)..... <b>PF7748</b>
<b>Lube</b> (1R0716)..... <b>B99 +</b>	<b>Air Dryer</b> (AD-SP System) (Bendix 109994)..... <b>BA5374 +</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19729)..... <b>PF7755</b>
<b>Fuel/Water Separator Ele.</b> (1698250-C1)..... <b>PF7755</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Fuel Spin-on</b> (1R0749)..... <b>BF7587 +</b>
<b>Fuel/Water Separator Ele.</b> (2588149-C1)..... <b>PF7748</b>	<b>Crankcase Breather</b> (3691476)..... <b>CV15000</b>	<b>Fuel Spin-on</b> (3563465-C1)..... <b>BF596 +</b>
<b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1212)..... <b>BF1212 +</b>	<b>Coolant</b> (w/o Chemical) (Fleetguard WF2127)..... <b>B5087</b>	<b>Radial Seal Air</b> (3507421-C1)..... <b>[2] RS3743</b>
<b>15 1/4 In. Radial Seal Air</b> (Standard) (3520400-C1)..... <b>RS3518</b>	<b>Coolant</b> (w/4 units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>	<b>Radial Seal Air</b> (Standard) (3560734-C1)..... <b>RS3518</b>
<b>15 1/4 In. Radial Seal Air</b> (Upgrade) (DBA5069)..... <b>RS3518XP</b>	<b>Coolant</b> (w/4 units BTE)..... <b>BW5137</b>	<b>Radial Seal XP Air</b> (Upgrade) (3560734-C1)..... <b>RS3518XP</b>
<b>18 5/8 In. Radial Seal Air</b> (1694039-C1)..... <b>RS3530</b>	<b>Coolant</b> (w/11 1/2 units BTA+) (Fleetguard WF2126)..... <b>BW5086</b>	<b>Cab Air</b> (1699956-C1)..... <b>PA5637</b>
<b>18 5/8 In. Radial Seal XP Air</b> (1694039-C1)..... <b>RS3530XP</b>	<b>Trans. Spin-on</b> (Fuller 4304827)..... <b>BT223</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
<b>Cab Air</b> (498144-C1)..... <b>PA5690</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Air Dryer</b> (AD-SP System) (Bendix 109994)..... <b>BA5374 +</b>
<b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b>	<b>Steering</b> (2503221C3)..... <b>BT9388</b>	<b>Crankcase Breather</b> (2007-on) (296-8325)..... <b>CV15008</b>
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Diesel Exhaust Fluid</b> (5303604)..... <b>PE17000</b>	<b>Coolant</b> (w/4 units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>
<b>Trans.</b> (Fuller 4304827)..... <b>BT223</b>	9900i w/Cummins ISX 15.0 (14.9L) Eng. (2018)	<b>Coolant</b> (w/4 units BTE)..... <b>BW5137</b>
<b>Opt. Trans.</b> (Fuller 17237)..... <b>BT9388</b>	<b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b>	<b>Coolant</b> (w/8 units BTE)..... <b>BW5139</b>
<b>Steering</b> (2503221-C1)..... <b>BT9388</b>	<b>Fuel/Water Separator</b> (Fleetguard FS19764)..... <b>PF9814</b>	<b>Trans.</b> (Fuller 4304827)..... <b>BT223</b>
<b>Some Differential</b> (1665311-C1)..... <b>B233</b>	<b>Fuel</b> (Standard) (Fleetguard FF5776)..... <b>BF9885 +</b>	<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>
9900i w/Cummins ISX 15.0 (14.9L) Eng. (To 2017)	<b>Fuel</b> (Upgrade) (Fleetguard FF5811)..... <b>BF46179</b>	<b>Steering</b> (2503221-C1)..... <b>BT9388</b>
<b>Dual-Flow Lube</b> (Fleetguard LF9080)..... <b>BD7154 +</b>	<b>Fuel</b> (Upgrade) (Fleetguard FF5825NN)..... <b>BF46129</b>	9900ix w/Cat 3406E Eng.
<b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>	<b>Radial Seal Air</b> (3507421C1)..... <b>[2] RS3743</b>	<b>Lube</b> ..... <b>B99 +</b>
<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19764)..... <b>PF9814</b>	<b>Cab Air</b> (3839141C1)..... <b>PA5679</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1212)..... <b>BF1212 +</b>
<b>P. Fuel/Water Separator Ele.</b> (Fleetguard FS19729)..... <b>PF7755</b>	<b>Air Dryer</b> (Bendix 109994)..... <b>BA5374 +</b>	<b>Fuel Spin-on</b> ..... <b>BF7587 +</b>
<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19765G)..... <b>PF46094</b>	<b>Crankcase Breather</b> (3691476)..... <b>CV15000</b>	<b>Radial Seal Air</b> (3507421-C1)..... <b>[2] RS3743</b>
<b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1040)..... <b>BF1277-SPS</b>	<b>Trans.</b> (Fuller 4304827)..... <b>BT223</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
<b>Fuel/Water Separator Spin-on</b> (w/Drain) (2510993C1)..... <b>BF1265</b>	<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	<b>Trans.</b> (Fuller 4304827)..... <b>BT223</b>
	<b>Steering</b> (2503221C1)..... <b>BT9388</b>	<b>Steering</b> (2503221-C1)..... <b>BT9388</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
9900ix w/Cummins ISX Eng. (Cont'd)	9900 SFA; 9900i SFA w/Cummins N14 (14.0L) Eng. (Cont'd)	9900ix SFA w/Cummins ISM (10.8L) Eng. (Cont'd)
Fuel/Water Separator Ele. (Fleetguard FF5369)..... PF7744	Fuel/Water Separator (Fleetguard FS1000)..... BF1259	Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... BD50000
Fuel/Water Separator Ele. (Fleetguard FS19729)..... PF7755	15 1/4 In. Radial Seal Air (Standard) (3520400-C1)..... RS3518	Fuel/Water Separator (3406889) BF1293-SPS
Fuel (Fleetguard FF2200)..... BF7766	15 1/4 In. Radial Seal Air (Upgrade) (DBA5069)..... RS3518XP	Radial Seal O. Air (Standard) (3520400C1)..... RS3518
Fuel (Fleetguard FF2203)..... BF7760	18 5/8 In. Radial Seal Air (1694039-C1)..... RS3530	Radial Seal XP O. Air (Upgrade) (DBA5069)..... RS3518XP
Radial Seal Air (3507421-C1)..... [2] RS3743	18 5/8 In. Radial Seal XP Air (1694039-C1)..... RS3530XP	9900ix SFA w/Cummins N14 (14.0L) Eng.
Radial Seal Air (Standard) (3560734-C1)..... RS3518	23 17/32 In. Radial Seal Air (3507421-C1)..... [2] RS3743	Dual-Flow Lube..... BD7309 +
Radial Seal XP Air (Upgrade) (3560734-C1)..... RS3518XP	Cab Air (498144-C1)..... PA5690	Fuel/Water Separator (3889716) BF1259
Cab Air (1699956-C1)..... PA5637	Air Dryer (AD-9 System) (Bendix 107796)..... BA5377	Fuel/Water Separator (3945066) BF1272-SPS
Air Dryer (AD-SP System) (Bendix 109994)..... BA5374 +	Coolant (3315116)..... BW5071	Radial Seal Air (3507421-C1)..... [2] RS3743
Crankcase Breather (3683918) CV15000	Opt. Trans. (Fuller 17237)..... B2 +	Air Dryer (AD-9 System) (Bendix 107796)..... BA5377
Coolant (w/o Chemical) (Fleetguard WF2127)..... B5087	Steering (2503221-C1)..... BT9388	Trans. (Fuller 4304827)..... BT223
Coolant (w/4 units BTA+)..... BW5071	9900 SFA; 9900i SFA w/Detroit Diesel Series 60 (11.1L) & (12.7L) Eng.	Opt. Trans. (Fuller 17237)..... B2 +
Coolant (w/11 1/2 units BTA+) (Fleetguard WF2126)..... BW5086	F-F Lube (23518480)..... B495	Steering (2503221-C1)..... BT9388
Coolant (w/4 units BTE)..... BW5137	P. Fuel (23530706)..... BF5800 +	9900ix SFA w/Detroit Diesel Series 60 (12.7L) Eng.
Trans. (Fuller 4304827)..... BT223	S. Fuel (23530707)..... BF5810	F-F Lube (23518480)..... B495
Opt. Trans. (Fuller 17237)..... B2 +	Radial Seal Air (Standard) (3560734-C1)..... RS3518	P. Fuel (23530706)..... BF5800 +
Steering (2503221-C1)..... BT9388	Radial Seal XP Air (Upgrade) (3560734-C1)..... RS3518XP	S. Fuel (23530707)..... BF5810
9900 SFA; 9900i SFA w/Cummins ISM (10.8L) Eng.	Radial Seal Air (3507421-C1)..... [2] RS3743	Radial Seal Air (Standard) (3560734-C1)..... RS3518
11 13/16 In. Dual-Flow Lube..... BD7154 +	Air Dryer (Wabco R950011)..... BA5374 +	Radial Seal XP Air (Upgrade) (3560734-C1)..... RS3518XP
14 7/32 In. Dual-Flow Lube..... BD7153 +	Air Dryer (AD-9 System) (Bendix 107796)..... BA5377	Radial Seal Air (3507421-C1)..... [2] RS3743
Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... BD50000	Opt. Trans. (Fuller 17237)..... B2 +	Air Dryer (Wabco R950011)..... BA5374 +
Fuel/Water Separator Ele..... PF7755	Steering (2503221-C1)..... BT9388	Air Dryer (AD-9 System) (Bendix 107796)..... BA5377
Fuel/Water Separator Spin-on (Fleetguard FS1003)..... BF1293-SPS	Some Differential (Meritor 3280-V-8394)..... B233	Opt. Trans. (Fuller 17237)..... B2 +
Fuel (Fleetguard FF202)..... BF596 +	9900ix SFA w/Cat 3406 (14.6L) Eng.	Steering (2503221-C1)..... BT9388
Radial Seal O. Air (Standard) (3520400-C1)..... RS3518	F-F Lube (Std. Version) (1R0716)..... B99 +	9900ix SFA w/Cummins ISM (10.8L) Eng.
Radial Seal XP O. Air (Upgrade) (DBA5069)..... RS3518XP	F-F Lube (High Efficiency) (1R1808)..... B7299 +	11 25/32 In. Dual-Flow Lube (3406809)..... BD7154 +
Radial Seal I. Air (3520401-C1)..... RS3519	Fuel Ele. (9M2342)..... [2] PF935	14 7/32 In. Dual-Flow Lube (3406810)..... BD7153 +
Single Radial Seal Air..... [2] RS3743	Fuel Spin-on (Std. Version) (1R1712)..... BF614 +	
Cab Air (1699956-C1)..... PA5637	Fuel Spin-on (High Efficiency) (1R0749)..... BF7587 +	
Air Dryer (AD-9 System) (Bendix 107796)..... BA5377	Radial Seal O. Air (Standard) (3560734C1)..... RS3518	
Air Dryer (AD-SP System) (Bendix 109994)..... BA5374 +	Radial Seal XP O. Air (Upgrade) (3560734C1)..... RS3518XP	
Coolant (w/4 units BTA+) (Fleetguard WF2071)..... BW5071	Radial Seal I. Air (350401C1)..... RS3519	
Coolant (w/4 units BTE)..... BW5137	Radial Seal Air (3507421C1)..... [2] RS3743	
Opt. Trans. (Fuller 17237)..... B2 +		
Steering (2503221-C1)..... BT9388		
9900 SFA; 9900i SFA w/Cummins N14 (14.0L) Eng.		
Dual-Flow Lube (3401544)..... BD7309 +		
Lube (Upgrade) (3401544)..... B40142 +		
Fuel/Water Separator (3331096) BF1274-SP		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
Cargostar w/DT466 (7.6L) Eng. Lube (1808896-C1)..... [2] B299 + Lube (1811953-C1)..... [2] B309 7 In. P. Fuel..... BF991 S. Fuel..... BF588 Air (478974-C1)..... PA2520	Cargostar w/V392 (6.4L) Eng. Lube Spin-on..... B167 Fuel Ele. (531546-R91)..... PF827 Opt. Air (446661-C2)..... PA2092 Cargostar w/VS401 Eng. Lube Ele. (1959-on)..... P204 Air (150868-R91)..... PA655	CF600 City Star w/VT275 (4.5L) Eng. (To 11/07) (Cont'd) Trans. Pan-Type (Motorcraft FT144)..... 20005 Trans. Ele. (Motorcraft FT145)..... P7247
Cargostar w/DT466C (7.6L) Eng. Lube (1808896-C1)..... [2] B299 + Lube (1811953-C1)..... [2] B309 7 In. P. Fuel..... BF991 S. Fuel..... BF588 Air (478974-C1)..... PA2520	Cargostar w/V8-420 (6.8L) Diesel Eng. Lube..... [2] B134 P. Fuel..... BF891 S. Fuel..... BF786	CF600 City Star w/VT275 (4.5L) Eng. (11/07-on) Lube (1847174-C91)..... P7423 Fuel (1847170-C93)..... PF7812 KIT Radial Seal Air (3587702-C1)..... RS4992 Trans. Pan-Type (Motorcraft FT180)..... 20021 Trans. Ele. (Motorcraft FT145)..... P7247
Cargostar w/DT1466C (7.6L) Eng. Lube (1808896-C1)..... [2] B299 + Lube (1811953-C1)..... [2] B309 7 In. P. Fuel..... BF991 S. Fuel..... BF588 Air (478974-C1)..... PA2520	Cargostar w/VS549 Eng. Lube Ele. (1959-on)..... P204 Air (150868-R91)..... PA655	CO9670 w/Cummins L10 (10.0L) Eng. Dual-Flow Lube (Fleetguard LF3000)..... BD103 + F-F Lube (Std. Version) (Fleetguard LF670SC)..... B196 + F-F Lube (Ext. Life) (Fleetguard LF670SC)..... B96 + B-P Lube (1W8845)..... B7577 Fuel/Water Separator (154789)..... BF957-D + Coolant (w/4 Units BTA+) (3315116)..... BW5071 Coolant (w/15 Units BTA+) (Fleetguard WF2075)..... BW5075
Cargostar w/DV550B Eng. Lube Ele..... [2] P276 Lube Spin-on..... [2] B167 P. Fuel Spin-on..... BF979 + S. Fuel Ele. (S/N 5118-7163)..... PF225 S. Fuel Spin-on (S/N 7164-up)..... BF588	Cargostar w/VS478 Eng. Lube Ele. (1959-on)..... P204 Air (150868-R91)..... PA655	CO9670 w/Cummins N14 (14.0L) Eng. Dual-Flow Lube..... BD103 + F-F Lube..... B196 + B-P Lube..... B7577 Fuel/Water Separator (3308638)..... BF1212 + Fuel Spin-on..... BF957-D + Coolant..... BW5071
Cargostar w/DVT573 Eng. Lube (323961-R91)..... PT86-HD Fuel Ele. (To S/N 1934)..... [2] PF225 P. Fuel Spin-on (S/N 1934-up)..... BF979 + S. Fuel Spin-on (S/N 1934-up)..... BF588	Cargostar w/VS537 (8.8L) Eng. Lube Spin-on..... [2] B167 Fuel Ele. (296951-R91)..... PF821-S	CO9670 w/Detroit Diesel 6V-92N (9.0L) Eng. F-F Lube (23530407)..... B95 + F-F Lube (Upgrade) (23530408)..... B95-MPG + P. Fuel (23530706)..... BF5800 + S. Fuel (23530645)..... BF5815 S. Fuel (23530707)..... BF5810 Conical Air (526059-C91)..... PA3951
Cargostar w/GMC 6V-53 Diesel Eng. F-F Lube Ele..... P20-HD P. Fuel Sock..... F916-C S. Fuel Ele..... PF906	CF500 w/VT275 (4.5L) Eng. (11/2007-on) Lube (1847174-C91)..... P7423 Fuel (1847170-C93)..... PF7812 KIT Radial Seal Air (3587702-C1)..... RS4992 Trans. Pan-Type (Motorcraft FT180)..... 20021 Trans. Ele. (Motorcraft FT145)..... P7247	CO9670 w/Detroit Diesel 8V-71N (9.3L) Eng. F-F Lube (23530407)..... B95 + F-F Lube (Upgrade) (23530408)..... B95-MPG + B-P Lube (23519155)..... P52
Cargostar w/MV404 (6.6L) Eng. 7 1/8 In. Lube Spin-on..... B167 In-Line Fuel..... BF840 + Opt. Air (446661-C2)..... PA2092	CF500 w/VT275 (4.5L) Eng. (To 11/2007) Lube (1847174-C91)..... P7423 Fuel (1847170-C93)..... PF7812 KIT Radial Seal Air (3587702-C1)..... RS4992 Trans. Pan-Type (Motorcraft FT144)..... 20005 Trans. Ele. (Motorcraft FT145)..... P7247	CO9670 w/Detroit Diesel 8V-92N (12.1L) Eng. F-F Lube Ele. (23518666)..... P20-HD + F-F Lube Spin-on (23530407)..... B95 + F-F Lube Spin-on (23530408)..... B95-MPG + P. Fuel (9717391)..... PF845 P. Fuel (23530706)..... BF5800 + S. Fuel Ele. (23519152)..... PF902 S. Fuel Spin-on (23530707)..... BF5810 S. Fuel Spin-on (23530645)..... BF5815 Conical Air (526059-C91)..... PA3951
Cargostar w/MV446 (7.3L) Eng. 7 1/8 In. Lube Spin-on..... B167 In-Line Fuel..... BF840 + Opt. Air (446661-C2)..... PA2092	CF600 City Star w/MaxxFORCE 5 Eng. Lube (1847174-C91)..... P7423 Fuel (1847170-C93)..... PF7812 KIT Radial Seal Air (3587702-C1)..... RS4992 Trans. Pan-Type (To 11/07) (Motorcraft FT144)..... 20005 Trans. Pan-Type (11/07-on) (Motorcraft FT180)..... 20021 Trans. Ele. (Motorcraft FT145)..... P7247	COF5870 Paystar w/Cummins N14 (14.0L) Eng. Dual-Flow Lube..... BD103 + F-F Lube..... B196 + B-P Lube..... B7577 Fuel/Water Separator (3308638)..... BF1212 +
Cargostar w/RD406, RD450 Eng. F-F Lube Ele..... P204 B-P Lube Sock..... CU406 <sup>90</sup> In-Line Fuel..... BF840 +	CF600 City Star w/VT275 (4.5L) Eng. (To 11/07) Lube (1847174-C91)..... P7423 Fuel (1847170-C93)..... PF7812 KIT Radial Seal Air (3587702-C1)..... RS4992	
Cargostar w/RD501 Eng. F-F Lube Ele..... P204 B-P Lube Sock..... CU406 <sup>90</sup> In-Line Fuel..... BF840 +		
Cargostar w/V345 (5.7L) Eng. Lube Spin-on..... B167 Fuel Ele. (531546-R91)..... PF827 Opt. Air (446661-C2)..... PA2092		

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.

Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
COF5870 Paystar w/Cummins N14 (14.0L) Eng. (Cont'd) Fuel Spin-on..... BF957-D + Coolant..... BW5071	CV515 w/V8-403 (6.6L) Eng. (2019) (Cont'd) Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004 Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016 Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003 Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017 Trans. Spin-on (Allison 29539579)..... BT8460	CXT w/DT466 (7.6L) Eng. (To 2005) (Cont'd) Trans. Ele. (4 In. Kit) (Allison 29526898)..... PT9415-MPG KIT Steering (2503221-C1)..... BT9388
COF5870 Paystar w/Detroit Diesel 6V-92N (9.0L) Eng. Lube (23530407)..... B95 + Lube (23530408)..... B95-MPG + P. Fuel (23530706)..... BF5800 + S. Fuel (23530707)..... BF5810 S. Fuel (23530645)..... BF5815	CV515 w/V8-403 (6.6L) Eng. (2020) Lube (6040648C1)..... B40150 Fuel/Water Separator (2515892C91)..... PF46250 Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004 Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016 Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003 Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017 Trans. Spin-on (Allison 29539579)..... BT8460	CXT w/DT466 (7.6L) Eng. (2005-on) Dual-Flow Lube (1842655C-91).. BD7252 Some Dual-Flow Lube (1842639-C91)..... BD7250 Fuel/Water Separator (1842638-C91)..... PF7779 Radial Seal O. Air (3532799-C1)..... RS4636 + Radial Seal I. Air (3532800-C1)... RS4637 Cab Air (2506656-C1)..... PA4985 Trans. Ele. (2 In. Kit) (Allison 29526899)..... PT9416-MPG KIT Trans. Ele. (4 In. Kit) (Allison 29526898)..... PT9415-MPG KIT Steering (2503221-C1)..... BT9388
COF9670 w/Cummins L10 (10.0L) Eng. Dual-Flow Lube (Fleetguard LF3000)..... BD103 + F-F Lube (Std. Version) (Fleetguard LF670SC)..... B196 + F-F Lube (Ext. Life) (Fleetguard LF670SC)..... B96 + B-P Lube (1W8845)..... B7577 Fuel/Water Separator (154789)... BF957-D + Coolant (w/4 Units BTA+) (3315116)..... BW5071 Coolant (w/15 Units BTA+) (Fleetguard WF2075)..... BW5075	CV515 w/V8-403 (6.6L) Eng. (2021) Lube (6040648C1)..... B40150 Fuel (2522151C91)..... PF46126 Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004 Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016 Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003 Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017 Trans. Spin-on (Allison 29539579)..... BT8460	CXT w/DT570 (9.3L) Eng. Dual-Flow Lube (1842639-C91).. BD7250 Fuel/Water Separator (1842638-C91)..... PF7779 Radial Seal O. Air (3532799-C1)..... RS4636 + Radial Seal I. Air (3532800-C1)... RS4637 Cab Air (2506656-C1)..... PA4985 Crankcase Breather..... CLN&R Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT Steering (2503221-C1)..... BT9388
COF9670 w/Cummins N14 (14.0L) Eng. Dual-Flow Lube..... BD103 + F-F Lube..... B196 + B-P Lube..... B7577 Fuel/Water Separator (3308638)..... BF1212 + Fuel Spin-on..... BF957-D + Coolant..... BW5071	CV515 w/V8-403 (6.6L) Eng. (2022) Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004 Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016 Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003 Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017 Trans. Spin-on (Allison 29539579)..... BT8460	CXT w/VT365 (6.0L) Eng. Lube (w/o Screw-on Cap) (1844588C91)..... P7235 Lube (w/Screw on Cap)..... P7436 Fuel Ele. (1825864C92)..... PF7698 Radial Seal O. Air (3532799C1).. RS4636 + Radial Seal I. Air (3532800C1)... RS4637 Cab Air (2506656C1)..... PA4985 Trans. Ele. (2 In. Kit) (Allison 29526899)..... PT9416-MPG KIT Trans. Ele. (4 In. Kit) (Allison 29526898)..... PT9415-MPG KIT Steering (2503221C1)..... BT9388
COF9670 w/Detroit Diesel 6V-92N (9.0L) Eng. F-F Lube Spin-on (23530407).... B95 + F-F Lube Spin-on (23530408).... B95-MPG + P. Fuel Spin-on (23530706)..... BF5800 + S. Fuel Spin-on (23530707)..... BF5810 S. Fuel Spin-on (23530645)..... BF5815 Conical Air (526059-C91)..... PA3951	CV515 w/V8-403 (6.6L) Eng. (2022) Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004 Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016 Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003 Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017 Trans. Spin-on (Allison 29539579)..... BT8460	CXT w/DT466 (7.6L) Eng. (To 2005) Lube (1833121-C1)..... B7030 B-P Lube (1842825-C91)..... BC7394 Fuel (1822588-C1)..... BF7629 + Radial Seal O. Air (3532799-C1)..... RS4636 + Radial Seal I. Air (3532800-C1)... RS4637 Cab Air (2506656-C1)..... PA4985 Coolant (Fleetguard WF2123).... B5090 + Trans. Ele. (2 In. Kit) (Allison 29526899)..... PT9416-MPG KIT
COF9670 w/Detroit Diesel 8V-71N (9.3L) Eng. F-F Lube Spin-on (23530407).... B95 + F-F Lube Spin-on (23530408).... B95-MPG + B-P Lube (23519155)..... P52	CXT w/DT466 (7.6L) Eng. (To 2005) Lube (1833121-C1)..... B7030 B-P Lube (1842825-C91)..... BC7394 Fuel (1822588-C1)..... BF7629 + Radial Seal O. Air (3532799-C1)..... RS4636 + Radial Seal I. Air (3532800-C1)... RS4637 Cab Air (2506656-C1)..... PA4985 Coolant (Fleetguard WF2123).... B5090 + Trans. Ele. (2 In. Kit) (Allison 29526899)..... PT9416-MPG KIT	DuraStar w/MaxxForce DT Eng. Dual-Flow Lube (To 2011) (1842639-C91)..... BD7250 Lube (2012-on) (1889124-C91)... B7503 Fuel/Water Separator (1878042-C91)..... PF7978 Fuel/Water Separator (1822638-C91)..... PF7779 Fuel Strainer (1873910-C91)..... PF7994 Radial Seal O. Air (3532799-C1)..... RS4636 + Radial Seal I. Air (3532800-C1)... RS4637 Cab Air (2506656-C1)..... PA4985 Air Dryer (Bendix 5008414)..... BA5374 + Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT
COF9670 w/Detroit Diesel 8V-92N (12.1L) Eng. F-F Lube Ele. (23518666)..... P20-HD + F-F Lube Spin-on (23530407).... B95 + F-F Lube Spin-on (23530408).... B95-MPG + P. Fuel Ele. (9717391)..... PF845 P. Fuel Spin-on (23530706)..... BF5800 + S. Fuel Ele. (23519152)..... PF902 S. Fuel Spin-on (23530707)..... BF5810 S. Fuel Spin-on (23530645)..... BF5815 Conical Air (526059-C91)..... PA3951	CV515 w/V8-403 (6.6L) Eng. (2019) Lube (6040648C1)..... B40150 Fuel/Water Separator (2515892C91)..... PF46250	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
DuraStar w/MaxxFlex DT Eng. (Cont'd)	DuraStar w/MaxxFlex 9 Eng. (Cont'd)	DuraStar w/DT570 Eng. (Cont'd)
Trans. Ele. (4 In. Kit) (Allison 29540494).....	Steering (2503221-C1).....	Trans. Ele. (2 In. Kit) (Allison 29526899).....
PT9415-MPG KIT	BT9388	PT9416-MPG KIT
Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965).....	DuraStar w/DT466 (7.6L) Eng.	Trans. Ele. (4 In. Kit) (Allison 29540494).....
20004	Dual-Flow Lube (1842639-C91)..	PT9415-MPG KIT
Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965).....	Fuel/Water Separator (1842638-C92).....	Opt. Trans. Spin-on (Fuller 17237).....
20016	PF7779	B2 +
Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966).....	Fuel/Water Separator (1878042-C91).....	Steering (2503221-C1).....
20003	PF7978	BT9388
Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966).....	Fuel.....	DuraStar w/VT230 Eng.
20017	BF7629 +	Lube (w/o Screw on Cap) (1840752-C91).....
Trans. Spin-on (Allison 29539579).....	Radial Seal O. Air (3532799-C1)..	P7235
BT8460	Radial Seal I. Air (3532800-C1)...	Lube (w/Screw on Cap) (Wix 57312).....
Steering (2503221-C1).....	EnduraCube Air (2602212C1)....	P7436
BT9388	PA32001	Fuel (1825864-C92).....
DuraStar w/MaxxFlex 7 Eng.	Cab Air (2506656-C1).....	PF7698
Lube Ele. (w/o Screw on Cap) (1840752-C91).....	Air Dryer (Bendix 107796).....	Radial Seal Air (3532799-C1)....
P7235	BA5377	Cab Air (2506656-C1).....
Lube Ele. (w/Screw on Cap) (Wix 57312).....	Trans. Ele. (2 In. Kit) (Allison 29526899).....	PA4985
P7436	PT9416-MPG KIT	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965).....
Lube Spin-on (1899332C-91).....	Trans. Ele. (4 In. Kit) (Allison 29540494).....	20004
B7506	PT9415-MPG KIT	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965).....
Fuel/Water Separator (1878042-C91).....	Steering (2503221-C1).....	20016
PF7978	BT9388	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966).....
Fuel Strainer (1873910-C91).....	DuraStar w/DT466HT Eng.	20003
PF7994	Dual-Flow Lube (1842639-C91)..	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966).....
Radial Seal O. Air (3532799-C1)..	Fuel/Water Separator (1842638-C92).....	20017
RS4637 +	PF7779	Trans. Spin-on (Allison 29539579).....
Radial Seal I. Air (3532800-C1)...	Fuel/Water Separator (1878042-C91).....	BT8460
RS4637	PF7978	Steering (2503221-C1).....
Cab Air (2506656-C1).....	Radial Seal O. Air (3532799-C1)..	BT9388
PA4985	Radial Seal I. Air (3532800-C1)...	DuraStar w/VT365 Eng.
Air Dryer (Bendix 109994).....	Cab Air (2506656-C1).....	Lube (w/o Screw on Cap) (1840752-C91).....
BA5374 +	Air Dryer (Bendix 107796).....	P7235
Trans. Ele. (2 In. Kit) (Allison 29548987).....	Trans. Ele. (2 In. Kit) (Allison 29526899).....	Lube (w/Screw on Cap) (Wix 57312).....
PT9416-MPG KIT	PT9416-MPG KIT	P7436
Trans. Ele. (4 In. Kit) (Allison 29548988).....	Trans. Ele. (4 In. Kit) (Allison 29540494).....	PF7698
PT9415-MPG KIT	PT9415-MPG KIT	Radial Seal O. Air (3532799-C1)..
Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965).....	Steering (2503221-C1).....	RS4637 +
20004	BT9388	Radial Seal I. Air (3532800-C1)...
Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965).....	DuraStar w/DT530 Eng.	RS4637
20016	Dual-Flow Lube (1842639-C91)..	Cab Air (2506656-C1).....
Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966).....	Fuel/Water Separator (1842638-C91).....	PA4985
20017	PF7779	Air Dryer (Bendix 107796).....
Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966).....	Radial Seal O. Air (3532799-C1)..	BA5377
20003	Radial Seal I. Air (3532800-C1)...	Coolant (Fleetguard WF2071).....
Trans. Spin-on (Allison 29539579).....	Cab Air (2506656-C1).....	Trans. Ele. (2 In. Kit) (Allison 29526899).....
BT8460	Air Dryer (Bendix 107796).....	PT9416-MPG KIT
Steering (2503221-C1).....	Trans. Ele. (4 In. Kit) (Allison 29540494).....	PT9415-MPG KIT
BT9388	PT9415-MPG KIT	BT9388
DuraStar w/MaxxFlex 9 Eng.	Opt. Trans. Spin-on (Fuller 17237).....	F1954 w/9.0L (9.0L) Naturally Aspirated Diesel Eng.
Dual-Flow Lube (To 2011) (1842639-C91).....	Steering (2503221-C1).....	Lube (427207C3).....
BD7250	BT9388	B167
Lube (2012-on) (1889124-C91)...	DuraStar w/DT570 Eng.	P. Fuel (625625C1).....
B7503	Dual-Flow Lube (1842639-C91)..	BF984
Fuel/Water Separator (1878042-C91).....	Fuel/Water Separator (1842638-C91).....	S. Fuel (672603C2).....
PF7978	PF7779	BF588
Fuel/Water Separator (1842638-C91).....	Radial Seal O. Air (3532799-C1)..	F1954 w/Cat 3176 (10.3L) Eng.
PF7779	Radial Seal I. Air (3532800-C1)...	F-F Lube (1R0716).....
Fuel Strainer (1873910-C91).....	Cab Air (2506656-C1).....	B99 +
PF7994	Air Dryer (Bendix 107796).....	F-F Lube (1R1808).....
Radial Seal O. Air (3532799-C1)..	Trans. Ele. (2 In. Kit) (Allison 29526899).....	B7299 +
RS4637 +	PT9416-MPG KIT	F-F Lube (1R0713).....
Radial Seal I. Air (3532800-C1)...	Trans. Ele. (4 In. Kit) (Allison 29540494).....	BT230 +
RS4637	PT9415-MPG KIT	F-F Lube (1R0714).....
Cab Air (2506656-C1).....	Steering (2503221-C1).....	B75
PA4985	BT9388	B-P Lube (1W8845).....
Air Dryer (Bendix 107796).....	DuraStar w/DT570 Eng.	B7577
BA5377	Dual-Flow Lube (1842639-C91)..	
Trans. Ele. (2 In. Kit) (Allison 29526899).....	Fuel/Water Separator (1842638-C91).....	
PT9416-MPG KIT	PF7779	
Trans. Ele. (4 In. Kit) (Allison 29540494).....	Radial Seal O. Air (3532799-C1)..	
PT9415-MPG KIT	Radial Seal I. Air (3532800-C1)...	
	Cab Air (2506656-C1).....	
	Air Dryer (Bendix 107796).....	
	Trans. Ele. (2 In. Kit) (Allison 29526899).....	
	PT9416-MPG KIT	
	Trans. Ele. (4 In. Kit) (Allison 29540494).....	
	PT9415-MPG KIT	
	Steering (2503221-C1).....	
	BT9388	
	DuraStar w/DT570 Eng.	
	Dual-Flow Lube (1842639-C91)..	
	BD7250	
	Fuel/Water Separator (1842638-C91).....	
	PF7779	
	Radial Seal O. Air (3532799-C1)..	
	Radial Seal I. Air (3532800-C1)...	
	Cab Air (2506656-C1).....	
	Air Dryer (Bendix 107796).....	
	BA5377	
	Crankcase Breather.....	
	CLN&R	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>INTERNATIONAL Trucks &amp; Buses (cont'd)</b>	<b>INTERNATIONAL Trucks &amp; Buses (cont'd)</b>	<b>INTERNATIONAL Trucks &amp; Buses (cont'd)</b>
F1954 w/Cat 3176 (10.3L) Eng. (Cont'd) <b>Fuel/Water Separator Ele.</b> (8N0205)..... PF316 <b>Fuel/Water Separator Spin-on</b> (2568753)..... BF1259 <b>P. Fuel</b> (1R1740)..... BF970 + <b>S. Fuel</b> (1R0750)..... BF7633 + <b>Coolant</b> (w/4 Units BTE) (9N3717)..... BW5137 <b>Coolant</b> (w/8 Units BTE) (9N3366)..... BW5139	F2275 w/Cummins N14 (14.0L) Eng. <b>Dual-Flow Lube</b> ..... BD103 + <b>F-F Lube</b> ..... B196 + <b>B-P Lube</b> ..... B7577 <b>Fuel/Water Separator</b> (3308638)..... BF1212 + <b>Fuel Spin-on</b> ..... BF957-D + <b>Coolant</b> ..... BW5071	F2375 S w/Cummins L10 (10.0L) Eng. (Cont'd) <b>F-F Lube</b> (Ext. Life) (Fleetguard LF670SC)..... B96 + <b>B-P Lube</b> (1W8845)..... B7577 <b>Fuel/Water Separator</b> (154789)... BF957-D + <b>Coolant</b> (w/4 Units BTA+) (3315116)..... BW5071 <b>Coolant</b> (w/15 Units BTA+) (Fleetguard WF2075)..... BW5075
F1954 w/Cat 3406 (14.6L) Eng. <b>Lube</b> (Standard Vers.) (1R0716).. B99 + <b>Lube</b> (High Efficiency Vers.) (1R1808)..... B7299 + <b>Fuel/Water Separator</b> (2568753)..... BF1259 <b>Fuel Ele.</b> (9M2342)..... [2] PF935 <b>Fuel Spin-on</b> (Standard Vers.) (4N5823)..... BF614 + <b>Fuel Spin-on</b> (High Efficiency Vers.)..... BF7587 +	F2275 w/Detroit Diesel 6-71N (7.0L) Eng. <b>Lube</b> (23530407)..... B95 + <b>Lube</b> (23530408)..... B95-MPG + <b>P. Fuel</b> (23530706)..... BF5800 + <b>S. Fuel</b> (23530707)..... BF5810 <b>S. Fuel</b> (23530645)..... BF5815	F2554 w/DT466 (7.6L) Eng. <b>Lube</b> (1808896C1)..... [2] B299 + <b>Lube</b> (1811953C1)..... [2] B309 <b>Fuel/Water Separator Ele.</b> (1842638C92)..... PF7779 <b>Fuel</b> (625625C1)..... BF984 <b>Fuel</b> (625627C1)..... BF979 + <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071 <b>Coolant</b> (w/12 Units BTA+) (1820361C1)..... BW5074
F1954 w/Cummins N14 (14.0L) Eng. <b>Dual-Flow Lube</b> ..... BD103 + <b>F-F Lube</b> ..... B196 + <b>B-P Lube</b> ..... B7577 <b>Fuel/Water Separator</b> (3308638)..... BF1212 + <b>Fuel Spin-on</b> ..... BF957-D + <b>Coolant</b> ..... BW5071	F2275 w/Detroit Diesel 6V-92N (9.0L) Eng. <b>Lube</b> (23530407)..... B95 + <b>Lube</b> (23530408)..... B95-MPG + <b>P. Fuel</b> (23530706)..... BF5800 + <b>S. Fuel</b> (23530707)..... BF5810 <b>S. Fuel</b> (23530645)..... BF5815	F2574 w/Cummins L10 (10.0L) Eng. <b>Dual-Flow Lube</b> (Fleetguard LF3000)..... BD103 + <b>F-F Lube</b> (Std. Version) (Fleetguard LF670SC)..... B196 + <b>F-F Lube</b> (Ext. Life) (Fleetguard LF670SC)..... B96 + <b>B-P Lube</b> (1W8845)..... B7577 <b>Fuel/Water Separator</b> (154789)... BF957-D + <b>Coolant</b> (w/4 Units BTA+) (3315116)..... BW5071 <b>Coolant</b> (w/15 Units BTA+) (Fleetguard WF2075)..... BW5075
F1954 w/Detroit Diesel 6V-92N (9.0L) Eng. <b>Lube</b> (23530407)..... B95 + <b>Lube</b> (23530408)..... B95-MPG + <b>P. Fuel</b> (23530706)..... BF5800 + <b>S. Fuel</b> (23530707)..... BF5810 <b>S. Fuel</b> (23530645)..... BF5815	F2276 S w/Cummins N14 (14.0L) Eng. <b>Dual-Flow Lube</b> ..... BD103 + <b>F-F Lube</b> ..... B196 + <b>B-P Lube</b> ..... B7577 <b>Fuel/Water Separator</b> (3308638)..... BF1212 + <b>Fuel Spin-on</b> ..... BF957-D + <b>Coolant</b> ..... BW5071	F2574 w/Cummins N14 (14.0L) Eng. <b>Dual-Flow Lube</b> ..... BD103 + <b>F-F Lube</b> ..... B196 + <b>B-P Lube</b> ..... B7577 <b>Fuel/Water Separator</b> (3308638)..... BF1212 + <b>Fuel Spin-on</b> ..... BF957-D + <b>Coolant</b> ..... BW5071
F1954 w/DT466 (7.6L) Eng. <b>Lube</b> (1808896C1)..... [2] B299 + <b>Lube</b> (1811953C1)..... [2] B309 <b>Fuel/Water Separator Ele.</b> (1842638C92)..... PF7779 <b>Fuel</b> (625625C1)..... BF984 <b>Fuel</b> (625627C1)..... BF979 + <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071 <b>Coolant</b> (w/12 Units BTA+) (1820361C1)..... BW5074	F2276 S w/Detroit Diesel 6-71N (7.0L) Eng. <b>Lube</b> (23530407)..... B95 + <b>Lube</b> (23530408)..... B95-MPG + <b>P. Fuel</b> (23530706)..... BF5800 + <b>S. Fuel</b> (23530707)..... BF5810 <b>S. Fuel</b> (23530645)..... BF5815	F2574 w/Detroit Diesel 6-71N (7.0L) Eng. <b>Lube</b> (23530407)..... B95 + <b>Lube</b> (23530408)..... B95-MPG + <b>P. Fuel</b> (23530706)..... BF5800 + <b>S. Fuel</b> (23530707)..... BF5810 <b>S. Fuel</b> (23530645)..... BF5815
F1954 w/DT466C (7.6L) Eng. <b>Lube</b> (1808896C1)..... [2] B299 + <b>Lube</b> (1811953C1)..... [2] B309 <b>Fuel/Water Separator Ele.</b> (1842638C92)..... PF7779 <b>Fuel</b> (625625C1)..... BF984 <b>Fuel</b> (625627C1)..... BF979 + <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071 <b>Coolant</b> (w/12 Units BTA+) (1820361C1)..... BW5074	F2276 S w/Detroit Diesel 6V-92N (9.0L) Eng. <b>Lube</b> (23530407)..... B95 + <b>Lube</b> (23530408)..... B95-MPG + <b>P. Fuel</b> (23530706)..... BF5800 + <b>S. Fuel</b> (23530707)..... BF5810 <b>S. Fuel</b> (23530645)..... BF5815	F2574 w/Detroit Diesel 6-71N (7.0L) Eng. <b>Lube</b> (23530407)..... B95 + <b>Lube</b> (23530408)..... B95-MPG + <b>P. Fuel</b> (23530706)..... BF5800 + <b>S. Fuel</b> (23530707)..... BF5810 <b>S. Fuel</b> (23530645)..... BF5815
F1954 w/DT466C (7.6L) Eng. <b>Lube</b> (1808896C1)..... [2] B299 + <b>Lube</b> (1811953C1)..... [2] B309 <b>Fuel/Water Separator Ele.</b> (1842638C92)..... PF7779 <b>Fuel</b> (625625C1)..... BF984 <b>Fuel</b> (625627C1)..... BF979 + <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071 <b>Coolant</b> (w/12 Units BTA+) (1820361C1)..... BW5074	F2276 S w/Detroit Diesel 8V-71N (9.3L) Eng. <b>F-F Lube</b> (23530407)..... B95 + <b>F-F Lube</b> (23530408)..... B95-MPG + <b>B-P Lube Ele.</b> (5570092)..... P52 <b>P. Fuel Spin-on</b> (23530706)..... BF5800 + <b>S. Fuel Spin-on</b> (23530707)..... BF5810 <b>S. Fuel Spin-on</b> (23530645)..... BF5815	F2574 w/Detroit Diesel 6V-92N (9.0L) Eng. <b>Lube</b> (23530407)..... B95 + <b>Lube</b> (23530408)..... B95-MPG + <b>P. Fuel</b> (23530706)..... BF5800 + <b>S. Fuel</b> (23530707)..... BF5810 <b>S. Fuel</b> (23530645)..... BF5815
F1954 w/DT466C (7.6L) Eng. <b>Lube</b> (1808896C1)..... [2] B299 + <b>Lube</b> (1811953C1)..... [2] B309 <b>Fuel/Water Separator Ele.</b> (1842638C92)..... PF7779 <b>Fuel</b> (625625C1)..... BF984 <b>Fuel</b> (625627C1)..... BF979 + <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071 <b>Coolant</b> (w/12 Units BTA+) (1820361C1)..... BW5074	F2276 S w/Detroit Diesel 8V-71N (9.3L) Eng. <b>F-F Lube</b> (23530407)..... B95 + <b>F-F Lube</b> (23530408)..... B95-MPG + <b>B-P Lube Ele.</b> (5570092)..... P52 <b>P. Fuel Spin-on</b> (23530706)..... BF5800 + <b>S. Fuel Spin-on</b> (23530707)..... BF5810 <b>S. Fuel Spin-on</b> (23530645)..... BF5815	F2574 w/Detroit Diesel 8V-71N (9.3L) Eng. <b>F-F Lube</b> (23530407)..... B95 + <b>F-F Lube</b> (23530408)..... B95-MPG + <b>B-P Lube Ele.</b> (5570092)..... P52 <b>P. Fuel Spin-on</b> (23530706)..... BF5800 + <b>S. Fuel Spin-on</b> (23530707)..... BF5810
F1954 w/DT466C (7.6L) Eng. <b>Lube</b> (1808896C1)..... [2] B299 + <b>Lube</b> (1811953C1)..... [2] B309 <b>Fuel/Water Separator Ele.</b> (1842638C92)..... PF7779 <b>Fuel</b> (625625C1)..... BF984 <b>Fuel</b> (625627C1)..... BF979 + <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071 <b>Coolant</b> (w/12 Units BTA+) (1820361C1)..... BW5074	F2375 S w/Cummins L10 (10.0L) Eng. <b>Dual-Flow Lube</b> (Fleetguard LF3000)..... BD103 + <b>F-F Lube</b> (Std. Version) (Fleetguard LF670SC)..... B196 +	F2574 w/Detroit Diesel 8V-71N (9.3L) Eng. <b>F-F Lube</b> (23530407)..... B95 + <b>F-F Lube</b> (23530408)..... B95-MPG + <b>B-P Lube Ele.</b> (5570092)..... P52 <b>P. Fuel Spin-on</b> (23530706)..... BF5800 + <b>S. Fuel Spin-on</b> (23530707)..... BF5810

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



<b>INTERNATIONAL Trucks &amp; Buses (cont'd)</b>	
F2574 w/Detroit Diesel 8V-71N (9.3L) Eng. (Cont'd)	
S. Fuel Spin-on (23530645).....	<b>BF5815</b>
F2575 w/Cummins L10 (10.0L) Eng.	
Dual-Flow Lube (Fleetguard LF3000).....	<b>BD103 +</b>
F-F Lube (Std. Version) (Fleetguard LF670SC).....	<b>B196 +</b>
F-F Lube (Ext. Life) (Fleetguard LF670SC).....	<b>B96 +</b>
B-P Lube (1W8845).....	<b>B7577</b>
Fuel/Water Separator (154789)...	<b>BF957-D +</b>
Coolant (w/4 Units BTA+) (3315116).....	<b>BW5071</b>
Coolant (w/15 Units BTA+) (Fleetguard WF2075).....	<b>BW5075</b>
F2575 w/Cummins N14 (14.0L) Eng.	
Dual-Flow Lube.....	<b>BD103 +</b>
F-F Lube.....	<b>B196 +</b>
B-P Lube.....	<b>B7577</b>
Fuel/Water Separator (3308638).....	<b>BF1212 +</b>
Fuel Spin-on.....	<b>BF957-D +</b>
Coolant.....	<b>BW5071</b>
F2575 w/Detroit Diesel 6-71N (7.0L) Eng.	
Lube (23530407).....	<b>B95 +</b>
Lube (23530408).....	<b>B95-MPG +</b>
P. Fuel (23530706).....	<b>BF5800 +</b>
S. Fuel (23530707).....	<b>BF5810</b>
S. Fuel (23530645).....	<b>BF5815</b>
F2575 w/Detroit Diesel 6V-92N (9.0L) Eng.	
Lube (23530407).....	<b>B95 +</b>
Lube (23530408).....	<b>B95-MPG +</b>
P. Fuel (23530706).....	<b>BF5800 +</b>
S. Fuel (23530707).....	<b>BF5810</b>
S. Fuel (23530645).....	<b>BF5815</b>
F2575 w/Detroit Diesel 8V-71N (9.3L) Eng.	
F-F Lube (23530407).....	<b>B95 +</b>
F-F Lube (23530408).....	<b>B95-MPG +</b>
B-P Lube Ele. (5570092).....	<b>P52</b>
P. Fuel Spin-on (23530706).....	<b>BF5800 +</b>
S. Fuel Spin-on (23530707).....	<b>BF5810</b>
S. Fuel Spin-on (23530645).....	<b>BF5815</b>
F2654 w/DT466 (7.6L) Eng.	
Lube (1808896C1).....	<b>[2] B299 +</b>
Lube (1811953C1).....	<b>[2] B309</b>
Fuel/Water Separator Ele. (1842638C92).....	<b>PF7779</b>
Fuel (625625C1).....	<b>BF984</b>
Fuel (625627C1).....	<b>BF979 +</b>
Coolant (w/4 Units BTA+) (Fleetguard WF2071).....	<b>BW5071</b>
Coolant (w/12 Units BTA+) (1820361C1).....	<b>BW5074</b>
F2674 w/Cummins L10 (10.0L) Eng.	
Dual-Flow Lube (Fleetguard LF3000).....	<b>BD103 +</b>
F-F Lube (Std. Version) (Fleetguard LF670SC).....	<b>B196 +</b>
F-F Lube (Ext. Life) (Fleetguard LF670SC).....	<b>B96 +</b>
B-P Lube (1W8845).....	<b>B7577</b>
Fuel/Water Separator (154789)...	<b>BF957-D +</b>
Coolant (w/4 Units BTA+) (3315116).....	<b>BW5071</b>
Coolant (w/15 Units BTA+) (Fleetguard WF2075).....	<b>BW5075</b>
F2675 w/Cummins N14 (14.0L) Eng.	
Dual-Flow Lube.....	<b>BD103 +</b>
F-F Lube.....	<b>B196 +</b>
B-P Lube.....	<b>B7577</b>
Fuel/Water Separator (3308638).....	<b>BF1212 +</b>
Fuel Spin-on.....	<b>BF957-D +</b>
Coolant.....	<b>BW5071</b>

<b>INTERNATIONAL Trucks &amp; Buses (cont'd)</b>	
F2674 w/Cummins L10 (10.0L) Eng. (Cont'd)	
F-F Lube (Ext. Life) (Fleetguard LF670SC).....	<b>B96 +</b>
B-P Lube (1W8845).....	<b>B7577</b>
Fuel/Water Separator (154789)...	<b>BF957-D +</b>
Coolant (w/4 Units BTA+) (3315116).....	<b>BW5071</b>
Coolant (w/15 Units BTA+) (Fleetguard WF2075).....	<b>BW5075</b>
F2674 w/Cummins N14 (14.0L) Eng.	
Dual-Flow Lube.....	<b>BD103 +</b>
F-F Lube.....	<b>B196 +</b>
B-P Lube.....	<b>B7577</b>
Fuel/Water Separator (3308638).....	<b>BF1212 +</b>
Fuel Spin-on.....	<b>BF957-D +</b>
Coolant.....	<b>BW5071</b>
F2674 w/Detroit Diesel 6-71N (7.0L) Eng.	
Lube (23530407).....	<b>B95 +</b>
Lube (23530408).....	<b>B95-MPG +</b>
P. Fuel (23530706).....	<b>BF5800 +</b>
S. Fuel (23530707).....	<b>BF5810</b>
S. Fuel (23530645).....	<b>BF5815</b>
F2674 w/Detroit Diesel 6V-92N (9.0L) Eng.	
Lube (23530407).....	<b>B95 +</b>
Lube (23530408).....	<b>B95-MPG +</b>
P. Fuel (23530706).....	<b>BF5800 +</b>
S. Fuel (23530707).....	<b>BF5810</b>
S. Fuel (23530645).....	<b>BF5815</b>
F2674 w/Detroit Diesel 8V-71N (9.3L) Eng.	
F-F Lube (23530407).....	<b>B95 +</b>
F-F Lube (23530408).....	<b>B95-MPG +</b>
B-P Lube Ele. (5570092).....	<b>P52</b>
P. Fuel Spin-on (23530706).....	<b>BF5800 +</b>
S. Fuel Spin-on (23530707).....	<b>BF5810</b>
S. Fuel Spin-on (23530645).....	<b>BF5815</b>
F2675 w/Cummins L10 (10.0L) Eng.	
Dual-Flow Lube (Fleetguard LF3000).....	<b>BD103 +</b>
F-F Lube (Std. Version) (Fleetguard LF670SC).....	<b>B196 +</b>
F-F Lube (Ext. Life) (Fleetguard LF670SC).....	<b>B96 +</b>
B-P Lube (1W8845).....	<b>B7577</b>
Fuel/Water Separator (154789)...	<b>BF957-D +</b>
Coolant (w/4 Units BTA+) (3315116).....	<b>BW5071</b>
Coolant (w/15 Units BTA+) (Fleetguard WF2075).....	<b>BW5075</b>
F2675 w/Cummins N14 (14.0L) Eng.	
Dual-Flow Lube.....	<b>BD103 +</b>
F-F Lube.....	<b>B196 +</b>
B-P Lube.....	<b>B7577</b>
Fuel/Water Separator (3308638).....	<b>BF1212 +</b>
Fuel Spin-on.....	<b>BF957-D +</b>
Coolant.....	<b>BW5071</b>

<b>INTERNATIONAL Trucks &amp; Buses (cont'd)</b>	
F9370 w/Cat 3406 (14.6L) Eng.	
Lube (Standard Vers.) (1R0716).....	<b>B99 +</b>
Lube (High Efficiency Vers.) (1R1808).....	<b>B7299 +</b>
Fuel/Water Separator (2568753).....	<b>BF1259</b>
Fuel Ele. (9M2342).....	<b>[2] PF935</b>
Fuel Spin-on (Standard Vers.) (4N5823).....	<b>BF614 +</b>
Fuel Spin-on (High Efficiency Vers.).....	<b>BF7587 +</b>
F9370 w/Cummins L10 (10.0L) Eng.	
Dual-Flow Lube (Fleetguard LF3000).....	<b>BD103 +</b>
F-F Lube (Std. Version) (Fleetguard LF670SC).....	<b>B196 +</b>
F-F Lube (Ext. Life) (Fleetguard LF670SC).....	<b>B96 +</b>
B-P Lube (1W8845).....	<b>B7577</b>
Fuel/Water Separator (154789)...	<b>BF957-D +</b>
Coolant (w/4 Units BTA+) (3315116).....	<b>BW5071</b>
Coolant (w/15 Units BTA+) (Fleetguard WF2075).....	<b>BW5075</b>
F9370 w/Cummins N14 (14.0L) Eng.	
Dual-Flow Lube.....	<b>BD103 +</b>
F-F Lube.....	<b>B196 +</b>
B-P Lube.....	<b>B7577</b>
Fuel/Water Separator (3308638).....	<b>BF1212 +</b>
Fuel Spin-on.....	<b>BF957-D +</b>
Coolant.....	<b>BW5071</b>
F9370 w/Cummins VT903 (14.8L) Eng.	
B-P Lube Ele. (256838).....	<b>C750-E +</b>
Lube Ele. (158139).....	<b>P999-HD</b>
F-F Lube Spin-on.....	<b>B196 +</b>
B-P Eng. Lube (3313283).....	<b>B7577</b>
Fuel/Water Separator (3308638).....	<b>BF1212 +</b>
Fuel Spin-on.....	<b>BF957-D +</b>
F9370 w/Detroit Diesel 6V-92N (9.0L) Eng.	
Lube (23530407).....	<b>B95 +</b>
Lube (23530408).....	<b>B95-MPG +</b>
P. Fuel (23530706).....	<b>BF5800 +</b>
S. Fuel (23530707).....	<b>BF5810</b>
S. Fuel (23530645).....	<b>BF5815</b>
F9370 w/Detroit Diesel 8V-92N (12.1L) Eng.	
Lube Ele. (5573013).....	<b>P20-HD</b>
Lube Spin-on (23530407).....	<b>B95 +</b>
Lube Spin-on (23530408).....	<b>B95-MPG +</b>
P. Fuel Ele. (9717391).....	<b>PF845</b>
P. Fuel Spin-on (23530706).....	<b>BF5800 +</b>
S. Fuel Ele. (5574508).....	<b>PF902</b>
S. Fuel Spin-on (23530707).....	<b>BF5810</b>
S. Fuel Spin-on (23530645).....	<b>BF5815</b>
G1904 w/V392 (6.4L) Eng.	
Lube (3059247R91).....	<b>B167</b>
Fuel (998429R91).....	<b>PF827</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

**Trucks & Buses Applications** **BALDWIN FILTERS**

<b>INTERNATIONAL Trucks &amp; Buses (cont'd)</b>	<b>INTERNATIONAL Trucks &amp; Buses (cont'd)</b>	<b>INTERNATIONAL Trucks &amp; Buses (cont'd)</b>
G2105 w/V392 (6.4L) Eng. Lube (3059247R91)..... <b>B167</b> Fuel (998429R91)..... <b>PF827</b>	HV507 w/Cummins ISB 6.7 (6.7L) Eng. (2021) (Cont'd) <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	HV507 w/Cummins L9 (9.0L) Eng. (2019) Lube (3401544)..... <b>B40142</b> <b>Fuel/Water Separator</b> (4080114C1)..... <b>BF46169-O</b> Fuel (5303743)..... <b>BF63000</b> <b>Radial Seal Air</b> (3532799C1)..... <b>RS4636</b> <b>Cab Air</b> (Intake) (4070948C1)..... <b>PA30093</b> <b>Air Dryer</b> (Wabco R950011)..... <b>BA5374</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
Genesis RE w/DT466 (7.6L) Eng. Lube (1819452C1)..... <b>B7030</b> <b>Fuel/Water Separator Ele.</b> (1842638C92)..... <b>PF7779</b> Fuel (625625C1)..... <b>BF984</b> Fuel (625627C1)..... <b>BF979 +</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (1820361C1)..... <b>BW5074</b>	HV507 w/Cummins ISB 6.7 (6.7L) Eng. (2022) Lube (Fleetguard LF3970)..... <b>B7177</b>	HV507 w/Cummins L9 (9.0L) Eng. (2020) Lube (5444774)..... <b>B40142</b> <b>Fuel/Water Separator</b> (4080114C1)..... <b>BF46169-O</b> Fuel (5303743)..... <b>BF63000</b> <b>Radial Seal Air</b> (3532799C1)..... <b>RS4636</b> <b>Cab Air</b> (Intake) (4070948C1)..... <b>PA30093</b> <b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
Genesis RE w/DT530 (8.7L) Eng. F-F Lube (1819452C1)..... <b>B7030</b> Dual-Flow Lube (1842639C91)..... <b>BD7250</b> <b>Fuel/Water Separator Ele.</b> (1842638C92)..... <b>PF7779</b> Fuel (1820479C1)..... <b>BF7531</b> <b>Coolant</b> (w/4 Units BTA+) (1822313C1)..... <b>BW5082</b>	HV507 w/Cummins ISL 8.9 (8.9L) Eng. (2019) Lube (3401544)..... <b>B40142</b> <b>Fuel/Water Separator</b> (4080114C1)..... <b>BF46169-O</b> Fuel (5303743)..... <b>BF63000</b> <b>Radial Seal Air</b> (3532799C1)..... <b>RS4636</b> <b>Cab Air</b> (Intake) (4070948C1)..... <b>PA30093</b> <b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	HV507 w/Cummins L9 (9.0L) Eng. (2020) Lube (5444774)..... <b>B40142</b> <b>Fuel/Water Separator</b> (4080114C1)..... <b>BF46169-O</b> Fuel (5303743)..... <b>BF63000</b> <b>Radial Seal Air</b> (3532799C1)..... <b>RS4636</b> <b>Cab Air</b> (4070948C1)..... <b>PA30093</b> <b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>
Genesis RE w/T444E (7.3L) Eng. Lube (1814562C1)..... <b>B7039</b> <b>Fuel/Water Separator</b> (1677004C91)..... <b>BF1345-O</b> Fuel Ele..... <b>PF7678</b> <b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b>	HV507 w/Cummins ISL 8.9 (8.9L) Eng. (2020) Lube (5444774)..... <b>B40142</b> <b>Fuel/Water Separator</b> (4080114C1)..... <b>BF46169-O</b> Fuel (5303743)..... <b>BF63000</b> <b>Radial Seal Air</b> (3532799C1)..... <b>RS4636</b> <b>Cab Air</b> (4070948C1)..... <b>PA30093</b> <b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	HV513 w/A26 (12.4L) Eng. (2019) Lube (3007498C94)..... <b>P7494</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (2611236C1)..... <b>BF46018-O</b> <b>Fuel/Water Separator</b> (w/Drain) (2611236C1)..... <b>BF1281</b> Fuel (2517615C91)..... <b>PF7986</b> <b>Radial Seal Air</b> (3551814C1)..... <b>RS4862</b> <b>Cab Air</b> (Intake) (4070948C1)..... <b>PA30093</b> <b>Air Dryer</b> (Bendix 65624)..... <b>BA5373</b> <b>Trans.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
HV507 w/Cummins ISB 6.7 (6.7L) Eng. (2019) Lube (3937736)..... <b>B7177</b> Fuel (5303743)..... <b>BF63000</b> <b>Radial Seal Air</b> (3532799C1)..... <b>RS4636</b> <b>Cab Air</b> (Intake) (4070948C1)..... <b>PA30093</b> <b>Air Dryer</b> (Wabco R950011)..... <b>BA5374</b> <b>Crankcase Breather</b> (4936636)..... <b>CV15010</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	HV507 w/Cummins ISL 8.9 (8.9L) Eng. (2021) Lube (5444774)..... <b>B40142</b> <b>Fuel/Water Separator</b> (4080114C2)..... <b>BF46169-O</b> <b>Radial Seal Air</b> (Fleetguard AF25707)..... <b>RS4636</b> <b>Trans.</b> (Allison 29558328)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (Allison 29558329)..... <b>PT9415-MPG KIT</b>	HV513 w/A26 (12.4L) Eng. (2020) Lube (3007498C94)..... <b>P7494</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (2611236C1)..... <b>BF46018-O</b> <b>Fuel/Water Separator</b> (w/Drain) (2611236C1)..... <b>BF1281</b> Fuel (4040481C1)..... <b>PF46261</b> <b>Radial Seal Air</b> (3551814C1)..... <b>RS4862</b> <b>Cab Air</b> (4070948C1)..... <b>PA30093</b> <b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b> <b>Trans.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Opt. Rear Axle</b> (3280V8394)..... <b>B233</b>
HV507 w/Cummins ISB 6.7 (6.7L) Eng. (2020) Lube (3937736)..... <b>B7177</b> Fuel (5303743)..... <b>BF63000</b> <b>Radial Seal Air</b> (3532799C1)..... <b>RS4636</b> <b>Cab Air</b> (4070948C1)..... <b>PA30093</b> <b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b> <b>Crankcase Breather</b> (4936636)..... <b>CV15010</b>	HV507 w/Cummins ISL 8.9 (8.9L) Eng. (2022) Lube (5444774)..... <b>B40142</b> Fuel (5660774)..... <b>BF63000</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	
HV507 w/Cummins ISB 6.7 (6.7L) Eng. (2021) Lube (3937736)..... <b>B7177</b> Fuel (5303743)..... <b>BF63000</b> <b>Radial Seal Air</b> (Fleetguard AF25707)..... <b>RS4636</b> <b>Crankcase Breather</b> (4936636)..... <b>CV15010</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	HV507 w/Cummins ISL 8.9 (8.9L) Eng. (2023) <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
HV513 w/A26 (12.4L) Eng. (2020) (Cont'd) Diesel Exhaust Fluid (Fleetguard UF106)..... <b>PE17002 KIT</b>	HV607 w/Cummins ISB 6.7 (6.7L) Eng. (2021) (Cont'd) Crankcase Breather (4936636)... <b>CV15010</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	HV607 w/Cummins ISL 8.9 (8.9L) Eng. (2021) (Cont'd) Cab Air (4070948C1)..... <b>PA30093</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>
HV513 w/A26 (12.4L) Eng. (2021) Lube (3007498C94)..... <b>P7494</b> Fuel/Water Separator (Open End for Bowl) (2611236C1)..... <b>BF46018-O</b> Fuel/Water Separator (w/Drain) (2611236C1)..... <b>BF1281</b> Fuel (2517615C91)..... <b>PF7986</b> Radial Seal Air (3551814C1)..... <b>RS4862</b> Trans. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	HV607 w/Cummins ISB 6.7 (6.7L) Eng. (2022) Lube (Fleetguard LF3970)..... <b>B7177</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	HV607 w/Cummins ISL 8.9 (8.9L) Eng. (2022) Lube (5444774)..... <b>B40142</b> Fuel (5660774)..... <b>BF63000</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>
HV513 w/A26 (12.4L) Eng. (2022) Lube (3007498C94)..... <b>P7494</b> Fuel (2517615C91)..... <b>PF7986</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	HV607 w/Cummins ISL 8.9 (8.9L) Eng. (2019) Lube (3401544)..... <b>B40142</b> Fuel/Water Separator (4080114C2)..... <b>BF46169-O</b> Fuel (5303743)..... <b>BF63000</b> EnduraCube Air (2517298C1)..... <b>PA32001</b> Cab Air (4070948C1)..... <b>PA30093</b> Air Dryer (Wabco R950011)..... <b>BA5374 +</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Steering (2503221C1)..... <b>BT9388</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	HV607 w/Cummins ISL 8.9 (8.9L) Eng. (2023) Lube (5520789)..... <b>B40142</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>
HV607 w/Cummins ISB 6.7 (6.7L) Eng. (2019) Lube (3937736)..... <b>B7177</b> Fuel/Water Separator (Fleetguard FS1067)..... <b>BF1378-SPS</b> Fuel (5303743)..... <b>BF63000</b> Air Dryer (Wabco R950011)..... <b>BA5374</b> Crankcase Breather (4936636)... <b>CV15010</b> Trans. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	HV607 w/Cummins ISL 8.9 (8.9L) Eng. (2020) Lube (5444774)..... <b>B40142</b> Fuel/Water Separator (4080114C1)..... <b>BF46169-O</b> Fuel (5303743)..... <b>BF63000</b> Radial Seal Air (3532799C1)..... <b>RS4636</b> Air Dryer (Bendix 107796)..... <b>BA5377</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Steering (2503221C1)..... <b>BT9388</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	HV607 w/Cummins L9 (9.0L) Eng. (2019) Lube (3401544)..... <b>B40142</b> Fuel/Water Separator (4080114C2)..... <b>BF46169-O</b> Fuel (5303743)..... <b>BF63000</b> EnduraCube Air (2517298C1)..... <b>PA32001</b> Cab Air (4070948C1)..... <b>PA30093</b> Air Dryer (Wabco R950011)..... <b>BA5374 +</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Steering (2503221C1)..... <b>BT9388</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>
HV607 w/Cummins ISB 6.7 (6.7L) Eng. (2020) Lube (3937736)..... <b>B7177</b> Fuel (5303743)..... <b>BF63000</b> Radial Seal Air (3532799C1)..... <b>RS4636</b> Air Dryer (Bendix 107796)..... <b>BA5377</b> Crankcase Breather (4936636)... <b>CV15010</b> Trans. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Steering (2503221C1)..... <b>BT9388</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	HV607 w/Cummins ISL 8.9 (8.9L) Eng. (2020) Lube (5444774)..... <b>B40142</b> Fuel/Water Separator (4080114C1)..... <b>BF46169-O</b> Fuel (5303743)..... <b>BF63000</b> Radial Seal Air (3532799C1)..... <b>RS4636</b> Air Dryer (Bendix 107796)..... <b>BA5377</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Steering (2503221C1)..... <b>BT9388</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	HV607 w/Cummins L9 (9.0L) Eng. (2020) Lube (5444774)..... <b>B40142</b> Fuel/Water Separator (4080114C1)..... <b>BF46169-O</b> Fuel (5303743)..... <b>BF63000</b> Radial Seal Air (3532799C1)..... <b>RS4636</b> Air Dryer (Bendix 107796)..... <b>BA5377</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Steering (2503221C1)..... <b>BT9388</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>
HV607 w/Cummins ISB 6.7 (6.7L) Eng. (2021) Lube (3937736)..... <b>B7177</b> Fuel (5303743)..... <b>BF63000</b> Radial Seal O. Air (Fleetguard AF25707)..... <b>RS4636</b> Radial Seal I. Air (Fleetguard AF25732)..... <b>RS4637</b> Cab Air (4070948C1)..... <b>PA30093</b>	HV607 w/Cummins ISL 8.9 (8.9L) Eng. (2021) Lube (5444774)..... <b>B40142</b> Fuel/Water Separator (Fleetguard FS20081)..... <b>PF46171</b> Radial Seal O. Air (Fleetguard AF25707)..... <b>RS4636</b> Radial Seal I. Air (Fleetguard AF25732)..... <b>RS4637</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
HV613 w/A26 (12.4L) Eng. (2019) Lube (3007498C94)..... P7494 Fuel/Water Separator (Open End for Bowl) (2611236C1)..... BF46018-O Fuel/Water Separator (w/Drain) (2611236C1)..... BF1281 Fuel (2517615C91)..... PF7986 Radial Seal O. Air (3551814C1)..... RS4862 Radial Seal I. Air (3551815C1)..... RS4863 Cab Air (4070948C1)..... PA30093 Air Dryer (Wabco R950011)..... BA5374 + Trans. (2 In. Kit) (Allison 29558117)..... PT9416-MPG KIT Trans. (4 In. Kit) (Allison 29558118)..... PT9415-MPG KIT Trans. Spin-on (Fuller 4304827)..... BT223 Steering (2503221C1)..... BT9388 Opt. Rear Axle (Meritor 3280V8394)..... B233	HV613 w/A26 (12.4L) Eng. (2022) (Cont'd) Trans. Ele. (4 In. Kit) (Allison 29558118)..... PT9415-MPG KIT Trans. Spin-on (Fuller 4304827)..... BT223 Opt. Rear Axle (Meritor 3280V8394)..... B233 HX515 w/A26 (12.4L) Eng. (2019) Lube (3007498C94)..... P7494 Fuel/Water Separator (Fleetguard FS19765)..... PF7930 Fuel (2517615C91)..... PF7986 Radial Seal Air (3560734C1)..... RS3518 Radial Seal XP Air (3560734C1)..... RS3518XP Cab Air (1699956C1)..... PA5637 Air Dryer (Bendix 107796)..... BA5377 Trans. Ele. (2 In. Kit) (Allison 29558117)..... PT9416-MPG KIT Trans. Ele. (4 In. Kit) (Allison 29558118)..... PT9415-MPG KIT Opt. Rear Axle (Meritor 3280V8394)..... B233 HX515 w/A26 (12.4L) Eng. (2020) Lube (3007498C94)..... P7494 Fuel (4040481C1)..... PF46261 Radial Seal O. Air (3560734C1)..... RS3518 Radial Seal O. XP Air (3560734C1)..... RS3518XP Radial Seal I. Air (3520401C1)..... RS3519 Cab Air (1699956C1)..... PA5637 Trans. (Fuller 4304827)..... BT223 Opt. Rear Axle (Meritor 3280V8394)..... B233 Diesel Exhaust Fluid (Fleetguard UF106)..... PE17002 KIT HX515 w/A26 (12.4L) Eng. (2021) Lube (3007498C94)..... P7494 Fuel/Water Separator (Fleetguard FS19765)..... PF7930 Fuel (2517615C91)..... PF7986 Radial Seal Air (3560734C1)..... RS3518 Radial Seal XP Air (3560734C1)..... RS3518XP Cab Air (1699956C1)..... PA5637 Trans. Ele. (2 In. Kit) (Allison 29558117)..... PT9416-MPG KIT Trans. Ele. (4 In. Kit) (Allison 29558118)..... PT9415-MPG KIT HX515 w/A26 (12.4L) Eng. (2022) Lube (3007498C94)..... P7494 Fuel (2517615C91)..... PF7986 HX515 w/N13 (12.4L) Eng. (2017-18) Lube (3007498-C94)..... P7494 Fuel/Water Separator (Open End for Bowl) (2611236C1)..... BF46018-O Fuel/Water Separator (w/Drain) (2611236C1)..... BF1281 Fuel/Water Separator (3004473-C93)..... PF7986	HX515 w/N13 (12.4L) Eng. (2017-18) (Cont'd) Radial Seal Air (Standard) (3560734C1)..... RS3518 Radial Seal XP Air (Upgrade) (3560734C1)..... RS3518XP Cab Air (1699956C1)..... PA5637 Air Dryer (Bendix 107794)..... BA5377 Trans. Ele. (2 In. Kit) (Allison 29548987)..... PT9416-MPG KIT Trans. Ele. (4 In. Kit) (Allison 29548988)..... PT9415-MPG KIT Trans. Spin-on (Fuller 4304827)..... BT223 Opt. Trans. Spin-on (Fuller 17237)..... B2 + Opt. Rear Axle (Meritor 3280V8394)..... B233 HX515 w/N13 (12.4L) Eng. (2019) Lube (3007498C94)..... P7494 Fuel/Water Separator (3004473C93)..... PF7986 Fuel/Water Separator (Open End for Bowl) (2611236C1)..... BF46018-O Fuel/Water Separator (w/Drain) (2611236C1)..... BF1281 Radial Seal Air (3560734C1)..... RS3518 Radial Seal XP Air (3560734C1)..... RS3518XP Cab Air (1699956C1)..... PA5637 Air Dryer (Bendix 107796)..... BA5377 Trans. Ele. (2 In. Kit) (Allison 29548987)..... PT9416-MPG KIT Trans. Ele. (4 In. Kit) (Allison 29548988)..... PT9415-MPG KIT Opt. Rear Axle (Meritor 3280V8394)..... B233 Diesel Exhaust Fluid (Fleetguard UF101)..... PE17000 HX520 w/A26 (12.4L) Eng. (2022) Lube (3007498C94)..... P7494 Fuel (2517615C91)..... PF7986 Opt. Rear Axle (Meritor 3280V8394)..... B233 HX520 w/Cummins ISX 15 (14.9L) Eng. (2018) Dual-Flow Lube (4367100)..... BD50000 Fuel/Water Separator (w/Drain) (2510993C1)..... BF1265 Fuel/Water Separator (Open End for Bowl) (2510993C1)..... BF1395-O Fuel/Water Separator (w/Sensor Port) (2510993C1)..... BF1395-SP Fuel (5365988)..... BF46129 Fuel (Upgrade) (2893612)..... BF9885 + Radial Seal Air (3507421C1)..... [2] RS3743 Cab Air (1699956C1)..... PA5637 Air Dryer (AD-9 System) (Bendix 107796)..... BA5377 Trans. (Fuller 4304827)..... BT223 Opt. Trans. (Fuller 17237)..... B2 + Opt. Rear Axle (Meritor 3280V8394)..... B233
HV613 w/A26 (12.4L) Eng. (2020) Lube (3007498C94)..... P7494 Fuel/Water Separator (w/Drain) (2611236C1)..... BF1281 Fuel/Water Separator (Open End for Bowl) (2611236C1)..... BF46018-O Fuel (4040481C1)..... PF46261 Radial Seal Air (3551814C1)..... RS4862 Cab Air (4070948C1)..... PA30093 Air Dryer (Wabco R950011)..... BA5374 Trans. (2 In. Kit) (Allison 29558117)..... PT9416-MPG KIT Trans. (4 In. Kit) (Allison 29558118)..... PT9415-MPG KIT Opt. Rear Axle (Meritor 3280V8394)..... B233	HV613 w/A26 (12.4L) Eng. (2021) Lube (3007498C94)..... P7494 Fuel/Water Separator (Open End for Bowl) (2611236C1)..... BF46018-O Fuel/Water Separator (w/Drain) (2611236C1)..... BF1281 Fuel (2517615C91)..... PF7986 Radial Seal Air (Fleetguard AF26103)..... RS4862 Cab Air (4070948C1)..... PA30093 Trans. Ele. (2 In. Kit) (Allison 29558117)..... PT9416-MPG KIT Trans. Ele. (4 In. Kit) (Allison 29558118)..... PT9415-MPG KIT Opt. Rear Axle (Meritor 3280V8394)..... B233	HV613 w/A26 (12.4L) Eng. (2022) Lube (3007498C94)..... P7494 Fuel/Water Separator (Fleetguard FS19765)..... PF7930 Fuel (2517615C91)..... PF7986 Trans. Ele. (2 In. Kit) (Allison 29558117)..... PT9416-MPG KIT

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
HX520 w/Cummins ISX 15 (14.9L) Eng. (2019) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (Fleetguard FS19764)..... <b>PF9814</b> <b>Fuel</b> (5365988)..... <b>BF46129</b> <b>Radial Seal Air</b> (3507421C1)..... <b>[2] RS3743</b> <b>Cab Air</b> (1699956C1)..... <b>PA5637</b> <b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	HX520 w/Cummins ISX 15.0 (14.9L) Eng. (2022) (Cont'd) <b>Fuel/Water Separator Spin-on</b> (w/Drain) (2510993C2)..... <b>BF1265</b> <b>Fuel</b> (5575143)..... <b>BF46248</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	HX615 w/A26 (12.4L) Eng. (2021) <b>Lube</b> (3007498C94)..... <b>P7494</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (2611236C1)..... <b>BF46018-O</b> <b>Fuel/Water Separator</b> (w/Drain) (2611236C1)..... <b>BF1281</b> <b>Fuel</b> (2517615C91)..... <b>PF7986</b> <b>Radial Seal O. Air</b> (3560734C1).. <b>RS3518</b> <b>Radial Seal XP O. Air</b> (3560734C1)..... <b>RS3518XP</b> <b>Radial Seal I. Air</b> (3520401C1).... <b>RS3519</b> <b>Radial Seal Air</b> (3507421C1)..... <b>[2] RS3743</b> <b>Cab Air</b> (1699956C1)..... <b>PA5637</b> <b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
HX520 w/Cummins ISX 15 (14.9L) Eng. (2020) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19764G)..... <b>PF46091</b> <b>Fuel/Water Separator Spin-on</b> (2510993C1)..... <b>BF1395-SP</b> <b>Fuel</b> (5365988)..... <b>BF46129</b> <b>Radial Seal O. Air</b> (3560734C1).. <b>RS3518</b> <b>Radial Seal XP O. Air</b> (3560734C1)..... <b>RS3518XP</b> <b>Radial Seal I. Air</b> (3520401C1).... <b>RS3519</b> <b>Radial Seal Air</b> (3507421C1)..... <b>[2] RS3743</b> <b>Cab Air</b> (1699956C1)..... <b>PA5637</b> <b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	HX520 w/Cummins ISX 15.0 (14.9L) Eng. (2023) <b>Lube</b> (5575298)..... <b>B40145</b> <b>Fuel</b> (5575143)..... <b>BF46248</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	HX615 w/A26 (12.4L) Eng. (2022) <b>Lube</b> (3007498C94)..... <b>P7494</b> <b>Fuel</b> (2517615C91)..... <b>PF7986</b> HX615 w/N13 (12.4L) Eng. (2017-18) <b>Lube</b> (3007498-C94)..... <b>P7494</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (2611236C1)..... <b>BF46018-O</b> <b>Fuel/Water Separator</b> (w/Drain) (2611236C1)..... <b>BF1281</b> <b>Fuel/Water Separator</b> (3004473-C93)..... <b>PF7986</b> <b>Fuel Screen</b> (3004474C92)..... <b>PF7939 +</b> <b>Radial Seal Air</b> (Standard) (Fleetguard AF25139M)..... <b>RS3518</b> <b>Radial Seal Air</b> (Upgrade) (DBA5069)..... <b>RS3518XP</b> <b>Cab Air</b> (1699956C1)..... <b>PA5637</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107794)..... <b>BA5377</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29526899)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29526898)..... <b>PT9415-MPG KIT</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
HX520 w/Cummins ISX 15 (14.9L) Eng. (2021) <b>Lube</b> (5575298)..... <b>B40145</b> <b>Fuel/Water Separator</b> (Fleetguard FS19764)..... <b>PF9814</b> <b>Fuel/Water Separator</b> (Fleetguard FS19764G)..... <b>PF46091</b> <b>Fuel</b> (5365988)..... <b>BF46129</b> <b>Radial Seal Air</b> (3507421C1)..... <b>RS3743</b> <b>Cab Air</b> (1699956C1)..... <b>PA5637</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	HX615 w/A26 (12.4L) Eng. (2019) <b>Lube</b> (3007498C94)..... <b>P7494</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (2611236C1)..... <b>BF46018-O</b> <b>Fuel/Water Separator</b> (w/Drain) (2611236C1)..... <b>BF1281</b> <b>Fuel</b> (2517615C91)..... <b>PF7986</b> <b>Radial Seal O. Air</b> (3560734C1).. <b>RS3518</b> <b>Radial Seal XP O. Air</b> (3560734C1)..... <b>RS3518XP</b> <b>Radial Seal I. Air</b> (3520401C1).... <b>RS3519</b> <b>Cab Air</b> (1699956C1)..... <b>PA5637</b> <b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (4388378).. <b>PE17002 KIT</b>	HX615 w/N13 (12.4L) Eng. (2019) <b>Lube</b> (3007498C94)..... <b>P7494</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (2611236C1)..... <b>BF46018-O</b> <b>Fuel/Water Separator</b> (3004473C93)..... <b>PF7986</b> <b>Fuel/Water Separator</b> (w/Drain) (2611236C1)..... <b>BF1281</b> <b>Radial Seal O. Air</b> (3560734C1).. <b>RS3518</b> <b>Radial Seal XP O. Air</b> (3560734C1)..... <b>RS3518XP</b> <b>Radial Seal I. Air</b> (3520401C1).... <b>RS3519</b> <b>Cab Air</b> (1699956C1)..... <b>PA5637</b>
HX520 w/Cummins ISX 15.0 (14.9L) Eng. (2022) <b>Lube</b> (5575298)..... <b>B40145</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19764G)..... <b>PF46091</b> <b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (2510993C2)..... <b>BF1395-SP</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (2510993C2)..... <b>BF1395-O</b>	HX615 w/A26 (12.4L) Eng. (2020) <b>Lube</b> (3007498C94)..... <b>P7494</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (2611236C1)..... <b>BF46018-O</b> <b>Fuel/Water Separator</b> (w/Drain) (2611236C1)..... <b>BF1281</b> <b>Fuel</b> (4040481C1)..... <b>PF46261</b> <b>Radial Seal O. Air</b> (3560734C1).. <b>RS3518</b> <b>Radial Seal O. XP Air</b> (3560734C1)..... <b>RS3518XP</b> <b>Cab Air</b> (1699956C1)..... <b>PA5637</b> <b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b> <b>Trans.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (4388378).. <b>PE17002 KIT</b>	HX615 w/N13 (12.4L) Eng. (2019) <b>Lube</b> (3007498C94)..... <b>P7494</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (2611236C1)..... <b>BF46018-O</b> <b>Fuel/Water Separator</b> (3004473C93)..... <b>PF7986</b> <b>Fuel/Water Separator</b> (w/Drain) (2611236C1)..... <b>BF1281</b> <b>Radial Seal O. Air</b> (3560734C1).. <b>RS3518</b> <b>Radial Seal XP O. Air</b> (3560734C1)..... <b>RS3518XP</b> <b>Radial Seal I. Air</b> (3520401C1).... <b>RS3519</b> <b>Cab Air</b> (1699956C1)..... <b>PA5637</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
HX615 w/N13 (12.4L) Eng. (2019) (Cont'd) <b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b> Trans. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (Fleetguard UF101)..... <b>PE17000</b>	HX620 w/Cummins ISX 15.0 (14.9L) Eng. (2018) <b>Dual-Flow Lube</b> (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19764)..... <b>PF9814</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (2510993C1)..... <b>BF1265</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (2510993C1)..... <b>BF1395-O</b> <b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (2510993C1)..... <b>BF1395-SP</b> <b>Fuel</b> (5365988)..... <b>BF46129</b> <b>Cab Air</b> (1699956C1)..... <b>PA5637</b> <b>Air Dryer</b> (Bendix 107794)..... <b>BA5377</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>	HX620 w/Cummins ISX 15.0 (14.9L) Eng. (2021) <b>Lube</b> (5575298)..... <b>B40145</b> <b>Fuel/Water Separator</b> (Fleetguard FS19764G)..... <b>PF46091</b> <b>Fuel</b> (5365988)..... <b>BF46129</b> <b>Cab Air</b> (1699956C1)..... <b>PA5637</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b>
HX620 w/A26 (12.4L) Eng. (2022) <b>Lube</b> (3007498C94)..... <b>P7494</b> <b>Fuel/Water Separator</b> (Fleetguard FS19764G)..... <b>PF46091</b> <b>Fuel</b> (2517615C91)..... <b>PF7986</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	HX620 w/A26 (12.4L) Eng. (2023) Trans. Ele. (2 In. Kit) (Allison 29526899)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29526898)..... <b>PT9415-MPG KIT</b>	HX620 w/Cummins ISX 15.0 (14.9L) Eng. (2022) <b>Lube</b> (5575298)..... <b>B40145</b> <b>Fuel/Water Separator</b> (Fleetguard FS19764G)..... <b>PF46091</b> <b>Fuel</b> (5575143)..... <b>BF46248</b> Trans. Ele. (2 In. Kit) (Allison 29558328)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558329)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
HX620 w/A26 (12.4L) Eng. (2023) Trans. Ele. (2 In. Kit) (Allison 29526899)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29526898)..... <b>PT9415-MPG KIT</b>	HX620 w/Cummins ISX 15.0 (14.9L) Eng. (2019) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (Fleetguard FS19764)..... <b>PF9814</b> <b>Fuel</b> (5365988)..... <b>BF46129 +</b> <b>Cab Air</b> (1699956C1)..... <b>PA5637</b> <b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	HX620 w/Cummins ISX 15.0 (14.9L) Eng. (2023) Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Trans. Ele. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>
HX620 w/Cummins ISX 15.0 (14.9L) Eng. (2017) <b>Dual-Flow Lube</b> (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19764)..... <b>PF9814</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (2510993C1)..... <b>BF1265</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (2510993C1)..... <b>BF1395-O</b> <b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (2510993C1)..... <b>BF1395-SP</b> <b>Fuel</b> (2893612)..... <b>BF9885 +</b> <b>Fuel</b> (Upgrade) (Fleetguard FF5811)..... <b>BF46179</b> <b>Cab Air</b> (1699956C1)..... <b>PA5637</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Air Dryer</b> (Wabco R950068)..... <b>BA5379 +</b> <b>Air Dryer</b> (Bendix 107794)..... <b>BA5377</b> <b>Crankcase Breather</b> (3691476).. <b>CV15000</b> Trans. Ele. (2 In. Kit) (Allison 29526899)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29526898)..... <b>PT9415-MPG KIT</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> <b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>	HX620 w/Cummins ISX 15.0 (14.9L) Eng. (2020) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19764G)..... <b>PF46091</b> <b>Fuel/Water Separator Spin-on</b> (2510993C1)..... <b>BF1395-SP</b> <b>Fuel</b> (5365988)..... <b>BF46129</b> <b>Cab Air</b> (1699956C1)..... <b>PA5637</b> <b>Air Dryer</b> (Bendix 107794)..... <b>BA5377</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	HX620 w/Cummins ISX 15.0 (14.9L) Eng. (2023) Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Trans. Ele. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>
HX620 w/Cummins ISX 15.0 (14.9L) Eng. (2020) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19764G)..... <b>PF46091</b> <b>Fuel/Water Separator Spin-on</b> (2510993C1)..... <b>BF1395-SP</b> <b>Fuel</b> (5365988)..... <b>BF46129</b> <b>Cab Air</b> (1699956C1)..... <b>PA5637</b> <b>Air Dryer</b> (Bendix 107794)..... <b>BA5377</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	Loadstar w/MaxxForce 10 (9.3L) Eng. <b>Lube</b> (1889124C91)..... <b>B7503</b> <b>Centrifugal Lube</b> (2606467C91).. <b>BC7485 +</b> <b>Fuel/Water Separator Ele.</b> (1878042C91)..... <b>PF7978</b> <b>Fuel Strainer</b> (1873910C91)..... <b>PF7994</b> Trans. Ele. (2 In. Kit) (Allison 29526899)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29526898)..... <b>PT9415-MPG KIT</b>	Loadstar w/MaxxForce 10 (9.3L) Eng. <b>Lube</b> (1889124C91)..... <b>B7503</b> <b>Centrifugal Lube</b> (2606467C91).. <b>BC7485 +</b> <b>Fuel/Water Separator</b> (2588149C1)..... <b>PF7748</b> <b>Fuel/Water Separator</b> (3004473C91)..... <b>PF7986</b> <b>Fuel Strainer</b> (A0000902051)..... <b>PF7939 +</b> Trans. Ele. (2 In. Kit) (Allison 29526899)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29526898)..... <b>PT9415-MPG KIT</b>
HX620 w/Cummins ISX 15.0 (14.9L) Eng. (2020) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19764G)..... <b>PF46091</b> <b>Fuel/Water Separator Spin-on</b> (2510993C1)..... <b>BF1395-SP</b> <b>Fuel</b> (5365988)..... <b>BF46129</b> <b>Cab Air</b> (1699956C1)..... <b>PA5637</b> <b>Air Dryer</b> (Bendix 107794)..... <b>BA5377</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	Loadstar w/MaxxForce 11 (10.5L) Eng. <b>Lube</b> (3007498C92)..... <b>P7494</b> <b>Centrifugal Lube</b> (2606467C91).. <b>BC7485 +</b> <b>Fuel/Water Separator</b> (2588149C1)..... <b>PF7748</b> <b>Fuel/Water Separator</b> (3004473C91)..... <b>PF7986</b> <b>Fuel Strainer</b> (A0000902051)..... <b>PF7939 +</b> Trans. Ele. (2 In. Kit) (Allison 29526899)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29526898)..... <b>PT9415-MPG KIT</b>	Loadstar w/MaxxForce 11 (10.5L) Eng. <b>Lube</b> (3007498C92)..... <b>P7494</b> <b>Centrifugal Lube</b> (2606467C91).. <b>BC7485 +</b>
HX620 w/Cummins ISX 15.0 (14.9L) Eng. (2020) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19764G)..... <b>PF46091</b> <b>Fuel/Water Separator Spin-on</b> (2510993C1)..... <b>BF1395-SP</b> <b>Fuel</b> (5365988)..... <b>BF46129</b> <b>Cab Air</b> (1699956C1)..... <b>PA5637</b> <b>Air Dryer</b> (Bendix 107794)..... <b>BA5377</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	Loadstar w/MaxxForce 13 (12.4L) Eng. <b>Lube</b> (3007498C92)..... <b>P7494</b> <b>Centrifugal Lube</b> (2606467C91).. <b>BC7485 +</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
<b>Loadstar w/MaxxForce 13 (12.4L) Eng. (Cont'd)</b> <b>Fuel/Water Separator</b> (3004473C91)..... <b>PF7986</b> <b>Fuel Strainer</b> (A0000902051)..... <b>PF7939 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29526899)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29526898)..... <b>PT9415-MPG KIT</b> <hr/> <b>LoneStar w/Cat C15 Eng.</b> <b>F-F Lube</b> (1R1808)..... <b>B7299 +</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19763)..... <b>PF7928</b> <b>Opt. Fuel/Water Separator Ele.</b> (Fleetguard FS19624)..... <b>PF7748</b> <b>Fuel/Water Separator Spin-on</b> (256-8753)..... <b>BF1259</b> <b>Fuel</b> (1R0749)..... <b>BF7587 +</b> <b>Cab Air</b> (2506656-C1)..... <b>PA4985</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Crankcase Breather</b> (296-8325).. <b>CV15008</b> <b>Opt. Crankcase Breather</b> (3805839)..... <b>CV15000</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (2503221-C1)..... <b>BT9388</b> <hr/> <b>LoneStar w/Cummins ISM 10.8 (10.8L) Eng.</b> <b>Dual-Flow Lube</b> (3101869)..... <b>BD7154 +</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (3329289). <b>BF1259</b> <b>Cab Air</b> (2506656C1)..... <b>PA4985</b> <b>Air Dryer</b> (Mann & Hummel TB1374X)..... <b>BA5374 +</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (2503221C1)..... <b>BT9388</b> <hr/> <b>LoneStar w/Cummins ISX 15.0 (14.9L) Eng. (2009-17)</b> <b>Dual-Flow Lube</b> (Fleetguard LF9080)..... <b>BD7154 +</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Opt. Fuel/Water Separator Ele.</b> (Fleetguard FS19729)..... <b>PF7755</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19765)..... <b>PF7930</b> <b>Opt. Fuel/Water Separator Ele.</b> (Fleetguard FS19905)..... <b>PF46092</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19764)..... <b>PF9814</b> <b>Fuel</b> (Fleetguard FF2203)..... <b>BF7760</b> <b>Fuel</b> (Fleetguard FF2200)..... <b>BF7766</b> <b>Fuel</b> (2010 Emissions) (Fleetguard FF5686)..... <b>BF9860 +</b> <b>Fuel</b> (2010 Emissions) (Fleetguard FF5776)..... <b>BF9885 +</b> <b>Fuel</b> (Upgrade) (Fleetguard FF5825NN)..... <b>BF46129</b> <b>Cab Air</b> (Bunk) (2506656-C1)..... <b>PA4985</b>	<b>LoneStar w/Cummins ISX 15.0 (14.9L) Eng. (2009-17) (Cont'd)</b> <b>Cab Air</b> (Main) (3839141C1)..... <b>PA5679</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Crankcase Breather</b> (Fleetguard CV50634)..... <b>CV15000</b> <b>Coolant</b> (w/o Chemical) (Fleetguard WF2127)..... <b>B5087</b> <b>Coolant</b> (w/Chemical) (Fleetguard WF2126)..... <b>BW5086</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (2503221-C1)..... <b>BT9388</b> <b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b> <hr/> <b>LoneStar w/Cummins ISX 15.0 (14.9L) Eng. (2018)</b> <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (Fleetguard FS19764)..... <b>PF9814</b> <b>Fuel</b> (5365988)..... <b>BF46129</b> <b>Cab Air</b> (Fleetguard AF27958)..... <b>PA5679</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Diesel Exhaust Fluid</b> (Fleetguard UF101)..... <b>PE17000</b> <hr/> <b>LoneStar w/Cummins ISX 15.0 (14.9L) Eng. (2019)</b> <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (Fleetguard FS19764G)..... <b>PF46091</b> <b>Fuel</b> (5365988)..... <b>BF46129 +</b> <b>Cab Air</b> (4070948C1)..... <b>PA30093</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <hr/> <b>LoneStar w/Cummins ISX 15.0 (14.9L) Eng. (2020)</b> <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (Fleetguard FS19764G)..... <b>PF46091</b> <b>Fuel</b> (5365988)..... <b>BF46129</b> <b>Cab Air</b> (Front) (4070948C1)..... <b>PA30093</b> <b>Cab Air</b> (Rear) (Fleetrite FLTC26430IN)..... <b>PA4985</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <hr/> <b>LoneStar w/Cummins ISX 15.0 (14.9L) Eng. (2021)</b> <b>Lube</b> (5575298)..... <b>B40145</b> <b>Fuel/Water Separator</b> (Fleetguard FS19764)..... <b>PF9814</b> <b>Fuel</b> (5365988)..... <b>BF46129</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b>	<b>LoneStar w/Cummins ISX 15.0 (14.9L) Eng. (2022)</b> <b>Lube</b> (5575298)..... <b>B40145</b> <b>Fuel</b> (5575143)..... <b>BF46248</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <hr/> <b>LoneStar w/Cummins ISX 15.0 (14.9L) Eng. (2023)</b> <b>Lube</b> (5575298)..... <b>B40145</b> <b>Fuel</b> (5575143)..... <b>BF46248</b> <hr/> <b>LoneStar w/Cummins X15 (14.9L) Eng. (2018)</b> <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (Fleetguard FS19764)..... <b>PF9814</b> <b>Fuel</b> (5365988)..... <b>BF46129</b> <b>Cab Air</b> (Fleetguard AF27958)..... <b>PA5679</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Diesel Exhaust Fluid</b> (Fleetguard UF101)..... <b>PE17000</b> <hr/> <b>LoneStar w/Cummins X15 (14.9L) Eng. (2019)</b> <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (Fleetguard FS19764G)..... <b>PF46091</b> <b>Fuel</b> (5365988)..... <b>BF46129 +</b> <b>Cab Air</b> (4070948C1)..... <b>PA30093</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <hr/> <b>LoneStar w/Cummins X15 (14.9L) Eng. (2020)</b> <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (Fleetguard FS19764G)..... <b>PF46091</b> <b>Fuel</b> (5365988)..... <b>BF46129</b> <b>Cab Air</b> (Front) (4070948C1)..... <b>PA30093</b> <b>Cab Air</b> (Rear) (Fleetrite FLTC26430IN)..... <b>PA4985</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <hr/> <b>LoneStar w/MaxxForce 13 Eng.</b> <b>Lube</b> (2007 Emissions) (3006874C91)..... <b>P7508</b> <b>Lube</b> (2010 Emissions) (3007498C92)..... <b>P7494</b> <b>Lube Centrifuge</b> (2606467-C91). <b>BC7485 +</b> <b>Fuel/Water Separator</b> (Fleetguard FS19765)..... <b>PF7930</b> <b>Fuel/Water Separator</b> (3004473-C91)..... <b>PF7986</b> <b>P. Fuel</b> (3004474-C91)..... <b>PF7939 +</b> <b>Cab Air</b> (7 1/4 In. Width) (2506656-C1)..... <b>PA4985</b> <b>Cab Air</b> (Fresh Air, 6 5/32 In. Width) (3839141C1)..... <b>PA5679</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (2503221-C1)..... <b>BT9388</b>

+ See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
LT625 w/A26 (12.4L) Eng. (2018) Lube (3007498C94)..... P7494 Fuel/Water Separator (Open End for Bowl) (2611236C1)..... BF46018-O Fuel/Water Separator (w/Drain) (2611236C1)..... BF1281 Fuel (2517615C91)..... PF7986 Cab Air (Intake) (4070948C1)..... PA30093 Air Dryer (Bendix 5008414)..... BA5374 + Trans. (Fuller 4304827)..... BT223 Opt. Trans. (Fuller 17237)..... B2 + Opt. Rear Axle (Meritor 3280V8394)..... B233 Diesel Exhaust Fluid (5303604)..... PE17000	LT625 w/Cummins ISX 15.0 (14.9L) / X15 (14.9L) Eng. (2017-18) Dual-Flow Lube (4367100)..... BD50000 Fuel/Water Separator Ele. (Fleetguard FS19764G)..... PF46091 Fuel/Water Separator Ele. (Fleetguard FS19765)..... PF7930 Fuel/Water Separator (w/Drain) (2510993C1)..... BF1265 Fuel/Water Separator Spin-on (Open End for Bowl) (2510993C1)..... BF1395-O Fuel/Water Separator Spin-on (w/Sensor Port) (2510993C1)..... BF1395-SP Fuel (5365988)..... BF46129 Cab Air (Intake) (4070948C1)..... PA30093 Air Dryer (Bendix 5008414)..... BA5374 + Trans. (Fuller 4304827)..... BT223 Opt. Trans. (Fuller 17237)..... B2 + Opt. Rear Axle (Meritor 3280V8394)..... B233 Diesel Exhaust Fluid (N/S)..... N/S	LT625 w/Cummins ISX 15.0 (14.9L) Eng. (2021) (Cont'd) Cab Air (Intake Duct) (4070948C1)..... PA30093 Opt. Trans. Spin-on (Fuller 17237)..... B2 LT625 w/Cummins ISX 15.0 (14.9L) Eng. (2022) Lube (5575298)..... B40145 Fuel/Water Separator Ele. (Fleetguard FS19764G)..... PF46091 Fuel/Water Separator Spin-on (w/Sensor Port) (2510993C2)..... BF1395-SP Fuel/Water Separator Spin-on (Open End for Bowl) (2510993C2)..... BF1395-O Fuel/Water Separator Spin-on (w/Drain) (2510993C2)..... BF1265 Fuel (5575143)..... BF46248 Fuel (5365988)..... BF46129 Cab Air (Fleetguard AF55839)..... PA30093 Opt. Trans. (Fuller 17237)..... B2 Opt. Rear Axle (Meritor 3280V8394)..... B233 LT625 w/Cummins ISX 15.0 (14.9L) Eng. (2023) Lube (5575298)..... B40145 Fuel (5575143)..... BF46248 LT625 w/Cummins X15 (14.9L) Eng. (2019) Dual-Flow Lube (4367100)..... BD50000 Fuel/Water Separator Ele. (Fleetguard FS19764G)..... PF46091 Fuel/Water Separator Spin-on (w/Drain) (2510993C1)..... BF1265 Fuel/Water Separator Spin-on (Open End for Bowl) (2510993C1)..... BF1395-O Fuel/Water Separator Spin-on (w/Sensor Port) (2510993C1)..... BF1395-SP Fuel (5365988)..... BF46129 + Cab Air (4070948C1)..... PA30093 Air Dryer (Bendix 5008414)..... BA5377 Trans. (Fuller 4304827)..... BT223 Steering (Fleetguard HF35476)..... BT9388 Opt. Rear Axle (Meritor 3280V8394)..... B233 LT625 w/Cummins ISX 15.0 (14.9L) Eng. (2020) Dual-Flow Lube (4367100)..... BD50000 Fuel/Water Separator (Fleetguard FS19764G)..... PF46091 Fuel (5365988)..... BF46129 Cab Air (Intake Duct) (4070948C1)..... PA30093 Air Dryer (Bendix 5008414)..... BA5374 + Trans. Spin-on (Fuller 4304827)..... BT223 Opt. Trans. Spin-on (Fuller 17237)..... B2 Opt. Rear Axle (Meritor 3280V8394)..... B233 LT625 w/Cummins X15 (14.9L) Eng. (2020) Dual-Flow Lube (4367100)..... BD50000 Fuel/Water Separator (Fleetguard FS19764G)..... PF46091 Fuel (5365988)..... BF46129 Cab Air (Intake Duct) (4070948C1)..... PA30093 Air Dryer (Bendix 5008414)..... BA5374 + Trans. Spin-on (Fuller 4304827)..... BT223 Opt. Trans. Spin-on (Fuller 17237)..... B2 Opt. Rear Axle (Meritor 3280V8394)..... B233
LT625 w/A26 (12.4L) Eng. (2019) Lube (3007498C94)..... P7494 Fuel/Water Separator (Open End for Bowl) (2611236C1)..... BF46018-O Fuel/Water Separator (w/Drain) (2611236C1)..... BF1281 Fuel (2517615C91)..... PF7986 Cab Air (4070948C1)..... PA30093 Air Dryer (Bendix 5008414)..... BA5374 + Steering (Fleetguard HF35476)..... BT9388 Opt. Rear Axle (Meritor 3280V8394)..... B233 Diesel Exhaust Fluid (4388378)..... PE17002 KIT	LT625 w/Cummins ISX 15.0 (14.9L) Eng. (2019) Dual-Flow Lube (4367100)..... BD50000 Fuel/Water Separator Ele. (Fleetguard FS19764G)..... PF46091 Fuel/Water Separator Spin-on (w/Drain) (2510993C1)..... BF1265 Fuel/Water Separator Spin-on (Open End for Bowl) (2510993C1)..... BF1395-O Fuel/Water Separator Spin-on (w/Sensor Port) (2510993C1)..... BF1395-SP Fuel (5365988)..... BF46129 + Cab Air (4070948C1)..... PA30093 Air Dryer (Bendix 5008414)..... BA5377 Trans. (Fuller 4304827)..... BT223 Steering (Fleetguard HF35476)..... BT9388 Opt. Rear Axle (Meritor 3280V8394)..... B233	LT625 w/Cummins ISX 15.0 (14.9L) Eng. (2023) Lube (5575298)..... B40145 Fuel (5575143)..... BF46248 LT625 w/Cummins X15 (14.9L) Eng. (2019) Dual-Flow Lube (4367100)..... BD50000 Fuel/Water Separator Ele. (Fleetguard FS19764G)..... PF46091 Fuel/Water Separator Spin-on (w/Drain) (2510993C1)..... BF1265 Fuel/Water Separator Spin-on (Open End for Bowl) (2510993C1)..... BF1395-O Fuel/Water Separator Spin-on (w/Sensor Port) (2510993C1)..... BF1395-SP Fuel (5365988)..... BF46129 + Cab Air (4070948C1)..... PA30093 Air Dryer (Bendix 5008414)..... BA5374 + Trans. (Fuller 4304827)..... BT223 Opt. Trans. (Fuller 17237)..... B2 + Steering (Fleetguard HF35476)..... BT9388 Opt. Rear Axle (Meritor 3280V8394)..... B233 LT625 w/Cummins X15 (14.9L) Eng. (2020) Dual-Flow Lube (4367100)..... BD50000 Fuel/Water Separator (Fleetguard FS19764G)..... PF46091 Fuel (5365988)..... BF46129 Cab Air (Intake Duct) (4070948C1)..... PA30093 Air Dryer (Bendix 5008414)..... BA5374 + Trans. Spin-on (Fuller 4304827)..... BT223 Opt. Trans. Spin-on (Fuller 17237)..... B2 Opt. Rear Axle (Meritor 3280V8394)..... B233
LT625 w/A26 (12.4L) Eng. (2020) Lube (3007498C94)..... P7494 Fuel/Water Separator (2517615C91)..... PF7986 Fuel (4040481C1)..... PF46261 Cab Air (Intake Duct) (4070948C1)..... PA30093 Air Dryer (Bendix 5008414)..... BA5374 + Opt. Coolant (Fleetguard WF2077)..... B5134 Opt. Trans. Spin-on (Fuller 17237)..... B2 Opt. Rear Axle (Meritor 3280V8394)..... B233 Diesel Exhaust Fluid (Fleetguard UF106)..... PE17002 KIT	LT625 w/Cummins ISX 15.0 (14.9L) Eng. (2020) Dual-Flow Lube (4367100)..... BD50000 Fuel/Water Separator (Fleetguard FS19764G)..... PF46091 Fuel (5365988)..... BF46129 Cab Air (Intake Duct) (4070948C1)..... PA30093 Air Dryer (Bendix 5008414)..... BA5374 + Trans. Spin-on (Fuller 4304827)..... BT223 Opt. Trans. Spin-on (Fuller 17237)..... B2 Opt. Rear Axle (Meritor 3280V8394)..... B233	LT625 w/Cummins X15 (14.9L) Eng. (2020) Dual-Flow Lube (4367100)..... BD50000 Fuel/Water Separator (Fleetguard FS19764G)..... PF46091 Fuel (5365988)..... BF46129 Cab Air (Intake Duct) (4070948C1)..... PA30093 Air Dryer (Bendix 5008414)..... BA5374 + Trans. Spin-on (Fuller 4304827)..... BT223 Opt. Trans. Spin-on (Fuller 17237)..... B2 Opt. Rear Axle (Meritor 3280V8394)..... B233
LT625 w/A26 (12.4L) Eng. (2021) Lube (3007498C94)..... P7494 Fuel/Water Separator (Fleetguard FS19765)..... PF7930 Fuel (2517615C91)..... PF7986 Cab Air (Intake Duct) (4070948C1)..... PA30093 Opt. Trans. Spin-on (Fuller 17237)..... B2	LT625 w/Cummins ISX 15.0 (14.9L) Eng. (2021) Lube (5575298)..... B40145 Fuel/Water Separator (Fleetguard FS19764G)..... PF46091 Fuel (5365988)..... BF46129	LT625 w/Cummins X15 (14.9L) Eng. (2020) Dual-Flow Lube (4367100)..... BD50000 Fuel/Water Separator (Fleetguard FS19764G)..... PF46091 Fuel (5365988)..... BF46129 Cab Air (Intake Duct) (4070948C1)..... PA30093 Air Dryer (Bendix 5008414)..... BA5374 + Trans. Spin-on (Fuller 4304827)..... BT223 Opt. Trans. Spin-on (Fuller 17237)..... B2 Opt. Rear Axle (Meritor 3280V8394)..... B233
LT625 w/A26 (12.4L) Eng. (2022) Lube (3007498C94)..... P7494 Fuel (2517615C91)..... PF7986 Cab Air (Fleetguard AF55839)..... PA30093 Opt. Rear Axle (Meritor 3280V8394)..... B233	LT625 w/Cummins ISX 15.0 (14.9L) Eng. (2021) Lube (5575298)..... B40145 Fuel/Water Separator (Fleetguard FS19764G)..... PF46091 Fuel (5365988)..... BF46129	LT625 w/Cummins X15 (14.9L) Eng. (2020) Dual-Flow Lube (4367100)..... BD50000 Fuel/Water Separator (Fleetguard FS19764G)..... PF46091 Fuel (5365988)..... BF46129 Cab Air (Intake Duct) (4070948C1)..... PA30093 Air Dryer (Bendix 5008414)..... BA5374 + Trans. Spin-on (Fuller 4304827)..... BT223 Opt. Trans. Spin-on (Fuller 17237)..... B2 Opt. Rear Axle (Meritor 3280V8394)..... B233

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
M1400 Metro II w/V8 7.3L Eng. Lube (1804442C1)..... <b>B134</b> Fuel (1804459C1)..... <b>BF786</b> Air (588213C1)..... <b>PA2116</b>	MV607 w/Cummins B6.7 (6.7L) Eng. (2020) (Cont'd) Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>	MV607 w/Cummins ISB 6.7 (6.7L) Eng. (2021) Lube (3937736)..... <b>B7177</b> Fuel (5303743)..... <b>BF63000</b> Primary EnduraCube Air (2517298C1)..... <b>PA32001</b> Secondary EnduraCube Air (2602211C1)..... <b>PA32004</b> Cab Air (Intake) (4070948C1)..... <b>PA30093</b> Crankcase Breather (4936636)..... <b>CV15010</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>
M1600 Metro II w/V8 7.3L Eng. Lube (1804442C1)..... <b>B134</b> Fuel (1804459C1)..... <b>BF786</b> Air (588213C1)..... <b>PA2116</b>	MV607 w/Cummins ISB 6.7 (6.7L) Eng. (2019) Lube (3937736)..... <b>B7177</b> Fuel/Water Separator (4080114C2)..... <b>BF46169-O</b> Fuel (5303743)..... <b>BF63000</b> Primary EnduraCube Air (2517298C1)..... <b>PA32001</b> Secondary EnduraCube Air (2602211C1)..... <b>PA32004</b> Cab Air (Intake) (4070948C1)..... <b>PA30093</b> Air Dryer (Bendix 107796)..... <b>BA5377</b> Crankcase Breather (4936636)..... <b>CV15010</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Steering (2503221C1)..... <b>BT9388</b>	MV607 w/Cummins ISB 6.7 (6.7L) Eng. (2022) Lube (Fleetguard LF3970)..... <b>B7177</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>
M6123 w/RD372, RD406, RD450, RD501 Engs. F-F Lube Ele..... <b>P204</b> B-P Lube Sock..... <b>CU406<sup>90</sup></b> Air (180237-R91)..... <b>PA653</b> Air (204514-R91)..... <b>PA638</b>	MV607 w/Cummins B6.7 (6.7L) Eng. (2019) Lube (3937736)..... <b>B7177</b> Fuel/Water Separator (4080114C2)..... <b>BF46169-O</b> Fuel (5303743)..... <b>BF63000</b> Primary EnduraCube Air (2517298C1)..... <b>PA32001</b> Secondary EnduraCube Air (2602211C1)..... <b>PA32004</b> Cab Air (Intake) (4070948C1)..... <b>PA30093</b> Air Dryer (Bendix 107796)..... <b>BA5377</b> Crankcase Breather (4936636)..... <b>CV15010</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Steering (2503221C1)..... <b>BT9388</b>	MV607 w/Cummins ISB 6.7 (6.7L) Eng. (2019) Lube (3401544)..... <b>B40142</b> Fuel/Water Separator (2514003C1)..... <b>BF46181-O</b> Fuel/Water Separator (4080114C2)..... <b>BF46169-O</b> Fuel (5303743)..... <b>BF63000</b> Primary EnduraCube Air (2517298C1)..... <b>PA32001</b> Secondary EnduraCube Air (2602211C1)..... <b>PA32004</b> Cab Air (Intake) (4070948C1)..... <b>PA30093</b> Air Dryer (Bendix 107796)..... <b>BA5377</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2<sup>+</sup></b> Steering (2503221C1)..... <b>BT9388</b>
M8234, M8234CBE w/RD372, RD406, RD450, RD501 Engs. F-F Lube Ele..... <b>P204</b> B-P Lube Sock..... <b>CU406<sup>90</sup></b>	MV607 w/Cummins ISB 6.7 (6.7L) Eng. (2020) Lube (3937736)..... <b>B7177</b> Fuel (5303743)..... <b>BF63000</b> Primary EnduraCube Air (2517298C1)..... <b>PA32001</b> Secondary EnduraCube Air (2602211C1)..... <b>PA32004</b> Cab Air (Intake) (4070948C1)..... <b>PA30093</b> Air Dryer (Wabco R950068A)..... <b>BA5379</b> Crankcase Breather (4936636)..... <b>CV15010</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>	MV607 w/Cummins ISL 8.9 (8.9L) Eng. (2019) Lube (3401544)..... <b>B40142</b> Fuel/Water Separator (2514003C1)..... <b>BF46181-O</b> Fuel/Water Separator (4080114C2)..... <b>BF46169-O</b> Fuel (5303743)..... <b>BF63000</b> Primary EnduraCube Air (2517298C1)..... <b>PA32001</b> Secondary EnduraCube Air (2602211C1)..... <b>PA32004</b> Cab Air (Intake) (4070948C1)..... <b>PA30093</b> Air Dryer (Bendix 107796)..... <b>BA5377</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2<sup>+</sup></b> Steering (2503221C1)..... <b>BT9388</b>
MV607 w/Cummins B6.7 (6.7L) Eng. (2019) Lube (3937736)..... <b>B7177</b> Fuel (5303743)..... <b>BF63000</b> Primary EnduraCube Air (2517298C1)..... <b>PA32001</b> Secondary EnduraCube Air (2602211C1)..... <b>PA32004</b> Cab Air (Intake) (4070948C1)..... <b>PA30093</b> Air Dryer (Bendix 107796)..... <b>BA5377</b> Crankcase Breather (4936636)..... <b>CV15010</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	MV607 w/Cummins ISB 6.7 (6.7L) Eng. (2020) Lube (3937736)..... <b>B7177</b> Fuel (5303743)..... <b>BF63000</b> Primary EnduraCube Air (2517298C1)..... <b>PA32001</b> Secondary EnduraCube Air (2602211C1)..... <b>PA32004</b> Cab Air (Intake) (4070948C1)..... <b>PA30093</b> Air Dryer (Wabco R950068A)..... <b>BA5379</b> Crankcase Breather (4936636)..... <b>CV15010</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>	MV607 w/Cummins ISL 8.9 (8.9L) Eng. (2019) Lube (3401544)..... <b>B40142</b> Fuel/Water Separator (2514003C1)..... <b>BF46181-O</b> Fuel/Water Separator (4080114C2)..... <b>BF46169-O</b> Fuel (5303743)..... <b>BF63000</b> Primary EnduraCube Air (2517298C1)..... <b>PA32001</b> Secondary EnduraCube Air (2602211C1)..... <b>PA32004</b> Cab Air (Intake) (4070948C1)..... <b>PA30093</b> Air Dryer (Bendix 107796)..... <b>BA5377</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2<sup>+</sup></b> Steering (2503221C1)..... <b>BT9388</b>
MV607 w/Cummins B6.7 (6.7L) Eng. (2020) Lube (3937736)..... <b>B7177</b> Fuel (5303743)..... <b>BF63000</b> Primary EnduraCube Air (2517298C1)..... <b>PA32001</b> Secondary EnduraCube Air (2602211C1)..... <b>PA32004</b> Cab Air (Intake) (4070948C1)..... <b>PA30093</b> Air Dryer (Wabco R950068A)..... <b>BA5379</b> Crankcase Breather (4936636)..... <b>CV15010</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	MV607 w/Cummins ISB 6.7 (6.7L) Eng. (2020) Lube (3937736)..... <b>B7177</b> Fuel (5303743)..... <b>BF63000</b> Primary EnduraCube Air (2517298C1)..... <b>PA32001</b> Secondary EnduraCube Air (2602211C1)..... <b>PA32004</b> Cab Air (Intake) (4070948C1)..... <b>PA30093</b> Air Dryer (Wabco R950068A)..... <b>BA5379</b> Crankcase Breather (4936636)..... <b>CV15010</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>	MV607 w/Cummins ISL 8.9 (8.9L) Eng. (2019) Lube (3401544)..... <b>B40142</b> Fuel/Water Separator (2514003C1)..... <b>BF46181-O</b> Fuel/Water Separator (4080114C2)..... <b>BF46169-O</b> Fuel (5303743)..... <b>BF63000</b> Primary EnduraCube Air (2517298C1)..... <b>PA32001</b> Secondary EnduraCube Air (2602211C1)..... <b>PA32004</b> Cab Air (Intake) (4070948C1)..... <b>PA30093</b> Air Dryer (Bendix 107796)..... <b>BA5377</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2<sup>+</sup></b> Steering (2503221C1)..... <b>BT9388</b>

\* See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.

Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
MV607 w/Cummins ISL 8.9 (8.9L) Eng. (2020) Lube (5444774)..... <b>B40142</b> Fuel/Water Separator (4080114C2)..... <b>BF46169-O</b> Fuel (5303743)..... <b>BF63000</b> Primary EnduraCube Air (2517298C1)..... <b>PA32001</b> Secondary EnduraCube Air (2602211C1)..... <b>PA32004</b> Cab Air (Intake) (4070948C1)..... <b>PA30093</b> Air Dryer (Wabco R950068A)..... <b>BA5379</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	MV607 w/Cummins L9 (9.0L) Eng. (2020) Lube (5444774)..... <b>B40142</b> Fuel/Water Separator (4080114C2)..... <b>BF46169-O</b> Fuel (5303743)..... <b>BF63000</b> Primary EnduraCube Air (2517298C1)..... <b>PA32001</b> Secondary EnduraCube Air (2602211C1)..... <b>PA32004</b> Air Dryer (Wabco R950068A)..... <b>BA5379</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> MXT w/VT365 (6.0L) Eng. Lube (w/o Screw on Cap) (1840752-C91)..... <b>P7235</b> Lube (w/Screw on Cap) (Wix 57312)..... <b>P7436</b> Fuel (1825864-C92)..... <b>PF7698</b> Radial Seal O. Air (1691027-C1)..... <b>RS2863</b> Radial Seal XP O. Air (1691027-C1)..... <b>RS2863XP</b> Opt. Radial Seal I. Air (Don. P527680)..... <b>RS3501</b> Cab Air (2506656-C1)..... <b>PA4985</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Steering (2503221C1)..... <b>BT9388</b>	ProStar w/Cat C15 (15.2L) Eng. Lube (1R1808)..... <b>B7299 +</b> Fuel/Water Separator (Open End for Bowl) (1335673)..... <b>BF1395-O</b> Fuel/Water Separator (w/Drain) (1335673)..... <b>BF1265</b> Fuel/Water Separator (w/Sensor Port) (1335673)..... <b>BF1395-SP</b> Fuel/Water Separator (2568753)..... <b>BF1259</b> Fuel Spin-on (Standard Vers.) (4N5823)..... <b>BF614 +</b> Fuel Spin-on (High Efficiency Vers.)..... <b>BF7587 +</b> Radial Seal O. Air (3551814-C1)..... <b>RS4862</b> Radial Seal I. Air (3551815-C1)..... <b>RS4863</b> Cab Air (2506656-C1)..... <b>PA4985</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Opt. Crankcase Breather (3805839)..... <b>CV15007</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Trans. (Fuller 4304827)..... <b>BT223</b> Steering (2503221-C1)..... <b>BT9388</b> ProStar w/Cummins ISM (10.8L) Eng. Dual-Flow Lube (Fleetguard LF9001)..... <b>BD7154 +</b> Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> Fuel/Water Separator (Fleetguard FS1000)..... <b>BF1259</b> Radial Seal O. Air (3551814-C1)..... <b>RS4862</b> Radial Seal I. Air (3551815-C1)..... <b>RS4863</b> Cab Air (2506656-C1)..... <b>PA4985</b> Air Dryer (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> Crankcase Breather (3683918)..... <b>CV15000</b> Coolant (Fleetguard WF2071)..... <b>BW5071</b> Trans. (Fuller 4304827)..... <b>BT223</b> Steering (2503221-C1)..... <b>BT9388</b> ProStar w/Cummins ISX Eng. Dual-Flow Lube (Fleetguard LF9080)..... <b>BD7154 +</b> Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> Fuel/Water Separator Ele. (Fleetguard FS19729)..... <b>PF7755</b> Fuel/Water Separator Ele. (Fleetguard FS1029W)..... <b>PF7680</b> Fuel/Water Separator Ele. (Fleetguard FS19764)..... <b>PF9814</b> Fuel/Water Separator Spin-on (Open End for Bowl) (2611236C1)..... <b>BF46018-O</b> Fuel/Water Separator (Fleetguard FS19764G)..... <b>PF46091</b> Fuel/Water Separator Spin-on (w/Drain) (2611236C1)..... <b>BF1281</b> Fuel (Fleetguard FF2200)..... <b>BF7766</b> Fuel (Fleetguard FF2203)..... <b>BF7760</b>
MV607 w/Cummins ISL 8.9 (8.9L) Eng. (2021) Lube (5444774)..... <b>B40142</b> Fuel/Water Separator (2514003C1)..... <b>BF46181-O</b> Primary EnduraCube Air (2517298C1)..... <b>PA32001</b> Secondary EnduraCube Air (2602211C1)..... <b>PA32004</b> Cab Air (Intake) (4070948C1)..... <b>PA30093</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	MV607 w/Cummins ISL 8.9 (8.9L) Eng. (2022) Lube (5444774)..... <b>B40142</b> Fuel (5660774)..... <b>BF63000</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	
MV607 w/Cummins ISL 8.9 (8.9L) Eng. (2023) Lube (5520789)..... <b>B40142</b>	MV607 w/Cummins L9 (9.0L) Eng. (2019) Lube (3401544)..... <b>B40142</b> Fuel/Water Separator (4080114C2)..... <b>BF46169-O</b> Fuel (5303743)..... <b>BF63000</b> Primary EnduraCube Air (2517298C1)..... <b>PA32001</b> Secondary EnduraCube Air (2602211C1)..... <b>PA32004</b> Cab Air (Intake) (4070948C1)..... <b>PA30093</b> Air Dryer (Bendix 107796)..... <b>BA5377</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Steering (2503221C1)..... <b>BT9388</b>	
	ProStar w/Cat C13 Eng. Lube (1R1808)..... <b>B7299 +</b> Fuel/Water Separator (2586814-C1)..... <b>PF7755</b> Fuel (1R0749)..... <b>BF7587 +</b> Radial Seal O. Air (3551814-C1)..... <b>RS4862</b> Radial Seal I. Air (3551815-C1)..... <b>RS4863</b> Cab Air (2506656-C1)..... <b>PA4985</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Crankcase Breather (2007-on) (296-8325)..... <b>CV15008</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Trans. (Fuller 4304827)..... <b>BT223</b> Steering (2503221-C1)..... <b>BT9388</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
ProStar w/Cummins ISX Eng. (Cont'd)	ProStar w/MaxxForce 11 Eng.	ProStar w/MaxxForce 15 Eng. (Cont'd)
<b>Fuel</b> (2010 Emissions) (Fleetguard FF5686)..... <b>BF9860</b> +	<b>Lube</b> (2007 Emissions) (3006874C91)..... <b>P7508</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (2611236C1)..... <b>BF46018-O</b>
<b>Fuel</b> (2010 Emissions) (Fleetguard FF5776)..... <b>BF9885</b> +	<b>Lube</b> (2010 Emissions) (3007498C92)..... <b>P7494</b>	<b>Fuel/Water Separator</b> (w/Drain) (2611236C1)..... <b>BF1281</b>
<b>Fuel</b> (Upgrade) (Fleetguard FF5825NN)..... <b>BF46129</b>	<b>Fuel/Water Separator</b> (2588149-C1)..... <b>PF7748</b>	<b>Fuel</b> (3014300-C1)..... <b>BF7587</b>
<b>Radial Seal O. Air</b> (3551814-C1).. <b>RS4862</b>	<b>Fuel/Water Separator</b> (3004473-C91)..... <b>PF7986</b>	<b>Radial Seal Air</b> (3551814-C1)..... <b>RS4862</b>
<b>Opt. Radial Seal I. Air</b> (3551815-C1)..... <b>RS4863</b>	<b>P. Fuel</b> ..... <b>PF7939</b> +	<b>Opt. Radial Seal I. Air</b> (3551815-C1)..... <b>RS4863</b>
<b>Cab Air</b> (6 5/32 In. Width) (3839141-C1)..... <b>PA5679</b>	<b>Radial Seal O. Air</b> (3551814C1).. <b>RS4862</b>	<b>Cab Air</b> (6 5/32 In. Width) (3839141-C1)..... <b>PA5679</b>
<b>Cab Air</b> (7 1/4 In. Width) (2506656-C1)..... <b>PA4985</b>	<b>Radial Seal I. Air</b> (3551815C1).... <b>RS4863</b>	<b>Cab Air</b> (7 1/4 In. Width) (2506656-C1)..... <b>PA4985</b>
<b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374</b> +	<b>Cab Air</b> (2506656-C1)..... <b>PA4985</b>	<b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374</b> +
<b>Crankcase Breather</b> (Fleetguard CV50634)..... <b>CV15000</b>	<b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374</b> +	<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2</b> +
<b>Coolant</b> (w/11 1/2 Units BTA+) (Fleetguard WF2126)..... <b>BW5086</b>	<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2</b> +	<b>Trans.</b> (Fuller 4304827)..... <b>BT223</b>
<b>Coolant</b> (w/o Chemical) (Fleetguard WF2127)..... <b>B5087</b>	<b>Trans.</b> (Fuller 4304827)..... <b>B2</b> +	<b>Steering</b> (2503221-C1)..... <b>BT9388</b>
<b>Trans.</b> (Fuller 4304827)..... <b>BT223</b>	<b>Steering</b> (2503221-C1)..... <b>BT9388</b>	
<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2</b> +		
<b>Steering</b> (2503221-C1)..... <b>BT9388</b>		
<b>Diesel Exhaust Fluid</b> (2010 Emissions) (5303604)..... <b>PE17000</b>		
ProStar w/Cummins ISX 15.0 (14.9L) Eng. (2018)	ProStar w/MaxxForce 13 Eng.	ProStar w/N13 (12.4L) Eng. (2014-18)
<b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b>	<b>Lube</b> (2007 Emissions) (3006874C91)..... <b>P7508</b>	<b>Lube</b> (3007498-C94)..... <b>P7494</b>
<b>Fuel/Water Separator</b> (w/Drain) (2510993C1)..... <b>BF1265</b>	<b>Lube</b> (2010 Emissions) (3007498-C94)..... <b>P7494</b>	<b>Lube Centrifuge (Opt.)</b> (2606467-C91)..... <b>BC7485</b> +
<b>Fuel/Water Separator</b> (Open End for Bowl) (2510993C1)..... <b>BF1395-O</b>	<b>Centrifugal Lube</b> (2606467-C92) <b>BC7485</b> +	<b>Fuel/Water Separator</b> (Open End for Bowl) (2611236C1)..... <b>BF46018-O</b>
<b>Fuel/Water Separator</b> (w/Sensor Port) (2510993C1)..... <b>BF1395-SP</b>	<b>Fuel/Water Separator Ele.</b> (2503566-C1)..... <b>PF7680</b>	<b>Fuel/Water Separator</b> (w/Drain) (2611236C1)..... <b>BF1281</b>
<b>Fuel</b> (Fleetguard FF5776)..... <b>BF9885</b>	<b>Fuel/Water Separator Ele.</b> (2588149-C1)..... <b>PF7748</b>	<b>Fuel/Water Separator</b> (3004473-C93)..... <b>PF7986</b>
<b>Fuel</b> (Upgrade) (Fleetguard FF5811)..... <b>BF46179</b>	<b>Fuel/Water Separator</b> (3007448-C1)..... <b>PF7986</b>	<b>Fuel/Water Separator</b> (Fleetguard FS19765)..... <b>PF7930</b>
<b>Radial Seal I. Air</b> (3551815C1).... <b>RS4863</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19764)..... <b>PF9814</b>	<b>Fuel Screen</b> (3004474-C92)..... <b>PF7939</b> +
<b>Radial Seal O. Air</b> (3551814C1).. <b>RS4862</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19765)..... <b>PF7930</b>	<b>Radial Seal Air</b> (3532799-C1)..... <b>RS4636</b> +
<b>Cab Air</b> (2506656C1)..... <b>PA4985</b>	<b>P. Fuel</b> (3004474C91)..... <b>PF7939</b> +	<b>Radial Seal Air</b> (Fleetguard AF26103)..... <b>RS4862</b>
<b>Air Dryer</b> (Wabco R950011)..... <b>BA5374</b> +	<b>Radial Seal O. Air</b> (3551814C1).. <b>RS4862</b>	<b>Cab Air</b> (Fresh Air) (2506656-C1) <b>PA4985</b>
<b>Crankcase Breather</b> (3691476)... <b>CV15000</b>	<b>Radial Seal I. Air</b> (3551815C1).... <b>RS4863</b>	<b>Cab Air</b> (3839141C1)..... <b>PA5679</b>
<b>Trans.</b> (Fuller 4304827)..... <b>BT223</b>	<b>Cab Air</b> (6 5/32 In. Width) (3839141-C1)..... <b>PA5679</b>	<b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374</b> +
<b>Steering</b> (2503221C1)..... <b>BT9388</b>	<b>Cab Air</b> (7 1/4 In. Width) (2506656-C1)..... <b>PA4985</b>	<b>Trans.</b> (Fuller 4304827)..... <b>BT223</b>
<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	<b>Air Dryer</b> (AD-IS Model) (Bendix 5008414)..... <b>BA5374</b> +	<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2</b> +
ProStar w/Cummins ISX 15.0 (14.9L) Eng. (2019)	<b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b>	<b>Steering</b> (2503221-C1)..... <b>BT9388</b>
<b>Dual-Flow Lube</b> (43967100)..... <b>BD50000</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	ProStar w/N13 (12.4L) Eng. (2019)
<b>Fuel</b> (5365988)..... <b>BF46129</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	<b>Lube</b> (3007498C94)..... <b>P7494</b>
ProStar w/Cummins ISX 15.0 (14.9L) Eng. (2020)	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>Fuel</b> (3004473C93)..... <b>PF7986</b>
<b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2</b> +	<b>RH613 w/A26</b> (12.4L) Eng. (2018)
<b>Fuel</b> (5365988)..... <b>BF46129</b>	<b>Steering</b> (2503221-C1)..... <b>BT9388</b>	<b>Lube</b> (3007498C94)..... <b>P7494</b>
		<b>Fuel/Water Separator</b> (Fleetguard FS19764)..... <b>PF9814</b>
		<b>Fuel/Water Separator</b> (Fleetguard FS19765)..... <b>PF7930</b>
		<b>Fuel</b> (2517615C91)..... <b>PF7986</b>
		<b>Radial Seal Air</b> (3551814C1)..... <b>RS4862</b>
		<b>Cab Air</b> (Intake) (4070948C1)..... <b>PA30093</b>
		<b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374</b> +
		<b>Trans.</b> (Fuller 4304827)..... <b>BT223</b>
		<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2</b> +
		<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
		<b>Diesel Exhaust Fluid</b> (4388378).. <b>PE17002 KIT</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
RH613 w/A26 (12.4L) Eng. (2019) Lube (3007498C94)..... P7494 Fuel/Water Separator (Open End for Bowl) (2611236C1)..... BF46018-O Fuel/Water Separator (w/Drain) (2611236C1)..... BF1281 Fuel (2517615C91)..... PF7986 Radial Seal Air (3551814C1)..... RS4862 Cab Air (4070948C1)..... PA30093 Air Dryer (Bendix 5008414)..... BA5374 + Trans. Ele. (Allison 29545780)..... PT9415-MPG KIT Opt. Trans. Spin-on (Fuller 17237)..... B2 + Opt. Rear Axle (Meritor 3280V8394)..... B233 Diesel Exhaust Fluid (4388378).. PE17002 KIT	RXT w/DT570 (9.3L) Eng. (Cont'd) Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT Steering (2503221-C1)..... BT9388 RXT w/MaxxForce 7 Eng. Lube (w/o Screw on Cap) (1840752-C91)..... P7235 Lube (w/Screw on Cap) (Wix 57312)..... P7436 Fuel Strainer (1873910-C91)..... PF7994 Fuel Kit (1876533-C93)..... BF9858 KIT Radial Seal Air (3532799-C1)..... RS4636 + Cab Air (3548705-C1)..... PA4985 Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004 Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016 Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003 Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017 Trans. Spin-on (Allison 29539579)..... BT8460 Steering (2503221-C1)..... BT9388 RXT w/MaxxForce 9 Eng. Dual-Flow Lube (1842639-C91).. BD7250 Fuel/Water Separator (1842638-C92)..... PF7779 Fuel/Water Separator (1878042-C91)..... PF7978 Fuel Strainer (1873910-C91)..... PF7994 Radial Seal O. Air (3532799-C1)..... RS4636 + Radial Seal I. Air (3532800-C1)..... RS4637 Cab Air (2506656-C1)..... PA4985 Steering (2503221-C1)..... BT9388	S1654 w/DT466C (7.6L) Eng. F-F Lube (1808896C1)..... [2] B299 + F-F Lube (1811953C1)..... [2] B309 Fuel/Water Separator Ele. (1842638C92)..... PF7779 Fuel (625625C1)..... BF984 Fuel (625627C1)..... BF979 + Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071 Coolant (w/12 Units BTA+) (1820361C1)..... BW5074 S1654LP w/V8-444 (7.3L) Turbo Diesel Eng. Lube (1804442C1)..... B134 Fuel/Water Separator (Ford E8TZ9N184A)..... BF1222 + S1723 w/MV404 (6.6L) Eng. F-F Lube (Fleetguard LF33136).... B2 + F-F Lube (427207C3)..... B167 In-Line Fuel (Fleetguard FF149).. BF840 + S1723 w/V345 (5.7L) Eng. Lube (3059247R91)..... B167 Fuel (531546R91)..... PF827 S1723 w/V392 (6.4L) Eng. Lube (3059247R91)..... B167 Fuel (531546R91)..... PF827 S1724 w/MV404 (6.6L) Eng. F-F Lube (Fleetguard LF33136).... B2 + F-F Lube (427207C3)..... B167 In-Line Fuel (Fleetguard FF149).. BF840 + S1724 w/V345 (5.7L) Eng. Lube (3059247R91)..... B167 Fuel (531546R91)..... PF827 S1724 w/V392 (6.4L) Eng. Lube (3059247R91)..... B167 Fuel (531546R91)..... PF827 S1753 w/V8-420 (6.8L) Diesel Eng. Lube..... [2] B134 P. Fuel..... BF891 S. Fuel..... BF786 Air..... PA2116 S1753 w/V8-444 (7.3L) Turbo Diesel Eng. Lube (1804442-C1)..... B134 Fuel/Water Separator (w/o SP) (1813104-C91)..... BF1222 + Fuel/Water Separator (w/SP) (1813104-C91)..... BF1222-SP + Fuel/Water Separator (Open End for Bowl)..... BF1222-O + Air (588213-C1)..... PA2116 Trans. Pan-Type (3.8 In. Pan, A.T. Series Trans.) (Allison 29540976)..... 19992 + Trans. Pan-Type (5.3 In. Pan, A.T. Series Trans) (Allison 29538489)..... 19739 + Trans. Spin-on (A.T. Series Trans) (Allison 29510922)..... BT8316-MPG
RH613 w/A26 (12.4L) Eng. (2020) Lube (3007498C94)..... P7494 Fuel/Water Separator (Open End for Bowl) (2611236C1)..... BF46018-O Fuel/Water Separator (w/Drain) (2611236C1)..... BF1281 Fuel (4040481C1)..... PF46261 Radial Seal O. Air (3551814C1).. RS4862 Radial Seal I. Air (3551815C1).... RS4863 Cab Air (Fresh Air) (4070948C1). PA30093 Air Dryer (Desiccant) (Bendix 109994)..... BA5374 + Air Dryer (Coalescer) (Bendix 5008414PG)..... BA5379 Opt. Coolant (Fleetguard WF2077)..... B5134 Trans. Ele. (Allison 29545780)..... PT9415-MPG KIT Opt. Rear Axle (3280V8394)..... B233 Diesel Exhaust Fluid (4388378).. PE17002 KIT	RXT w/VT365 (6.0L) Eng. Lube (w/o Screw on Cap) (1840752-C91)..... P7235 Lube (w/Screw on Cap) (Wix 57312)..... P7436 Fuel (1825864-C92)..... PF7698 Radial Seal O. Air (3532799-C1)..... RS4636 + Radial Seal I. Air (3532800-C1)..... RS4637 Cab Air (2506656-C1)..... PA4985 Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT Steering (2503221-C1)..... BT9388 S1624 w/V345 (5.7L) Eng. Lube (3059247R91)..... B167 Fuel (531546R91)..... PF827 Opt. Air (446661-C2)..... PA2092 S1654 w/V8-444 (7.3L) Turbo Diesel Eng. Lube (1804442C1)..... B134 Fuel/Water Separator (Ford E8TZ9N184A)..... BF1222 +	
RH613 w/A26 (12.4L) Eng. (2021) Lube (3007498C94)..... P7494 Fuel (2517615C91)..... PF7986 Radial Seal Air (3551814C1)..... RS4862 Coolant (Opt.) (Fleetguard WF2077)..... B5134 Opt. Trans. Spin-on (Fuller 17237)..... B2 Opt. Rear Axle (Meritor 3280V8394)..... B233		
RH613 w/A26 (12.4L) Eng. (2022) Lube (3007498C94)..... P7494 Fuel (2517615C91)..... PF7986		
RXT w/DT570 (9.3L) Eng. Dual-Flow Lube (1842639-C91).. BD7250 Fuel/Water Separator (1842638-C91)..... PF7779 Radial Seal O. Air (3532799-C1)..... RS4636 + Radial Seal I. Air (3532800-C1)..... RS4637 Cab Air (2506656-C1)..... PA4985 Crankcase Breather..... CLN&R Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
S1753 w/V8-444 (7.3L) Turbo Diesel Eng. (Cont'd) Trans. Ele. (475606-C2)..... PT374 Trans. Spin-on (595722-C91)..... BT839-10	S1754 w/DT466C (7.6L) Eng. (Cont'd) Coolant (w/12 Units BTA+) (1820361C1)..... BW5074	S1853 w/DTA360 (5.9L) Eng. (Cont'd) Coolant (w/12 Units BTA+) (1820361C1)..... BW5074 Trans. Ele. (475606-C2)..... PT374 Trans. Spin-on (595722-C91)..... BT839-10 Steering (1660345-C91)..... PT8407
S1753 w/DT466 (7.6L) Eng. F-F Lube (1808896C1)..... [2] B299 + F-F Lube (1811953C1)..... [2] B309 Fuel/Water Separator Ele. (1842638C92)..... PF7779 Fuel (625625C1)..... BF984 Fuel (625627C1)..... BF979 + Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071 Coolant (w/12 Units BTA+) (1820361C1)..... BW5074	S1823 w/MV404 (6.6L) Eng. F-F Lube (Fleetguard LF33136)... B2 + F-F Lube (427207C3)..... B167 In-Line Fuel (Fleetguard FF149).. BF840 + S1823 w/MV446 (7.3L) Eng. F-F Lube (Fleetguard LF33136)... B2 + F-F Lube (427207C3)..... B167 In-Line Fuel (Fleetguard FF149).. BF840 + S1823 w/V345 (5.7L) Eng. Lube (3059247R91)..... B167 Fuel (531546R91)..... PF827	S1853 w/DT466 (7.6L) Eng. F-F Lube (1808896C1)..... [2] B299 + F-F Lube (1811953C1)..... [2] B309 Fuel/Water Separator Ele. (1842638C92)..... PF7779 Fuel (625625C1)..... BF984 Fuel (625627C1)..... BF979 + Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071 Coolant (w/12 Units BTA+) (1820361C1)..... BW5074
S1754 w/V8-551 (9.0L) Diesel Eng. Lube..... B167 P. Fuel..... BF984 S. Fuel..... BF588 O. Air..... PA2521 I. Air..... PA2522	S1824 w/MV404 (6.6L) Eng. F-F Lube (Fleetguard LF33136)... B2 + F-F Lube (427207C3)..... B167 In-Line Fuel (Fleetguard FF149).. BF840 + S1824 w/MV446 (7.3L) Eng. F-F Lube (Fleetguard LF33136)... B2 + F-F Lube (427207C3)..... B167 In-Line Fuel (Fleetguard FF149).. BF840 + S1824 w/V345 (5.7L) Eng. Lube (3059247R91)..... B167 Fuel (531546R91)..... PF827	S1853 w/DT466C (7.6L) Eng. F-F Lube (1808896C1)..... [2] B299 + F-F Lube (1811953C1)..... [2] B309 Fuel/Water Separator Ele. (1842638C92)..... PF7779 Fuel (625625C1)..... BF984 Fuel (625627C1)..... BF979 + Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071 Coolant (w/12 Units BTA+) (1820361C1)..... BW5074
S1754 w/V8-444 (7.3L) Turbo Diesel Eng. Lube (1804442-C1)..... B134 Fuel/Water Separator (w/o SP) (1813104-C91)..... BF1222 + Fuel/Water Separator (w/SP) (1813104-C91)..... BF1222-SP + Fuel/Water Separator (Open End for Bowl)..... BF1222-O +	S1824 w/V392 (6.4L) Eng. Lube (3059247R91)..... B167 Fuel (531546R91)..... PF827	S1853 w/DTA466 (7.6L) Eng. F-F Lube (1808896C1)..... [2] B299 + F-F Lube (1811953C1)..... [2] B309 Fuel/Water Separator Ele. (1842638C92)..... PF7779 Fuel (625625C1)..... BF984 Fuel (625627C1)..... BF979 + Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071 Coolant (w/12 Units BTA+) (1820361C1)..... BW5074
S1754 w/DT360 (5.9L) Eng. Lube (1808896C1)..... B299 + Lube (1811953C1)..... B309 Fuel/Water Separator Spin-on (1808623C1)..... BF7584 + Fuel (1809789C1)..... BF7629 + Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071 Coolant (w/12 Units BTA+) (1820361C1)..... BW5074	S1853 w/DT360 (5.9L) Eng. Lube (1808896C1)..... B299 + Lube (1811953C1)..... B309 Fuel/Water Separator Spin-on (1808623C1)..... BF7584 + Fuel (1809789C1)..... BF7629 + Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071 Coolant (w/12 Units BTA+) (1820361C1)..... BW5074	S1853 w/DTA466C (7.6L) Eng. F-F Lube (1808896C1)..... [2] B299 + F-F Lube (1811953C1)..... [2] B309 Fuel/Water Separator Ele. (1842638C92)..... PF7779 Fuel (625625C1)..... BF984 Fuel (625627C1)..... BF979 + Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071 Coolant (w/12 Units BTA+) (1820361C1)..... BW5074
S1754 w/DTA360 (5.9L) Eng. Lube (1808896C1)..... B299 + Lube (1811953C1)..... B309 Fuel/Water Separator Spin-on (1808623C1)..... BF7584 + Fuel (1809789C1)..... BF7629 + Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071 Coolant (w/12 Units BTA+) (1820361C1)..... BW5074	S1853 w/DTA360 (5.9L) Eng. Lube (1811953C1)..... B309 Lube (1808896-C1)..... B299 + Fuel/Water Separator Spin-on (1808623C1)..... BF7584 + Fuel/Water Separator Ele. (3 29/32 In.) (Fleetguard FS1207).... PF7889 Fuel/Water Separator Ele. (8 29/32 In.) (Fleetguard FS1206).... PF7890 Fuel/Water Separator Spin-on (702255-C1)..... BF891 Fuel/Water Separator Spin-on (598435-C1)..... BF1212 + Fuel (1809789C1)..... BF7629 + Fuel Ele. (854569)..... PF827 O. Air (482647-C91)..... PA2521 Opt. I. Air (482647-C91)..... PA2522 Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071	S1853 w/DTA466C (7.6L) Eng. F-F Lube (1808896C1)..... [2] B299 + F-F Lube (1811953C1)..... [2] B309 Fuel/Water Separator Ele. (1842638C92)..... PF7779 Fuel (625625C1)..... BF984 Fuel (625627C1)..... BF979 + Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071 Coolant (w/12 Units BTA+) (1820361C1)..... BW5074
S1754 w/DT466C (7.6L) Eng. F-F Lube (1808896C1)..... [2] B299 + F-F Lube (1811953C1)..... [2] B309 Fuel/Water Separator Ele. (1842638C92)..... PF7779 Fuel (625625C1)..... BF984 Fuel (625627C1)..... BF979 + Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071		S1853 w/DTI466C (7.6L) Eng. F-F Lube (1808896C1)..... [2] B299 + F-F Lube (1811953C1)..... [2] B309 Fuel/Water Separator Ele. (1842638C92)..... PF7779 Fuel (625625C1)..... BF984 Fuel (625627C1)..... BF979 +

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
S1853 w/DT1466C (7.6L) Eng. (Cont'd) <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (1820361C1)..... <b>BW5074</b>	S1854 w/DT466C (7.6L) Eng. <b>F-F Lube</b> (1808896C1)..... <b>[2] B299 +</b> <b>F-F Lube</b> (1811953C1)..... <b>[2] B309</b> <b>Fuel/Water Separator Ele.</b> (1842638C92)..... <b>PF7779</b> <b>Fuel</b> (625625C1)..... <b>BF984</b> <b>Fuel</b> (625627C1)..... <b>BF979 +</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (1820361C1)..... <b>BW5074</b>	S1924, S1925 w/MV404 (6.6L) Eng. <b>F-F Lube</b> (Fleetguard LF33136).... <b>B2 +</b> <b>F-F Lube</b> (427207C3)..... <b>B167</b> <b>In-Line Fuel</b> (Fleetguard FF149).. <b>BF840 +</b>
S1853FC w/DT466C (7.6L) Eng. <b>F-F Lube</b> (1808896C1)..... <b>[2] B299 +</b> <b>F-F Lube</b> (1811953C1)..... <b>[2] B309</b> <b>Fuel/Water Separator Ele.</b> (1842638C92)..... <b>PF7779</b> <b>Fuel</b> (625625C1)..... <b>BF984</b> <b>Fuel</b> (625627C1)..... <b>BF979 +</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (1820361C1)..... <b>BW5074</b>	S1854 w/DTA466 (7.6L) Eng. <b>F-F Lube</b> (1808896C1)..... <b>[2] B299 +</b> <b>F-F Lube</b> (1811953C1)..... <b>[2] B309</b> <b>Fuel/Water Separator Ele.</b> (1842638C92)..... <b>PF7779</b> <b>Fuel</b> (625625C1)..... <b>BF984</b> <b>Fuel</b> (625627C1)..... <b>BF979 +</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (1820361C1)..... <b>BW5074</b>	S1924, S1925 w/MV446 (7.3L) Eng. <b>F-F Lube</b> (Fleetguard LF33136).... <b>B2 +</b> <b>F-F Lube</b> (427207C3)..... <b>B167</b> <b>In-Line Fuel</b> (Fleetguard FF149).. <b>BF840 +</b>
S1853FC w/DTA466 (7.6L) Eng. <b>F-F Lube</b> (1808896C1)..... <b>[2] B299 +</b> <b>F-F Lube</b> (1811953C1)..... <b>[2] B309</b> <b>Fuel/Water Separator Ele.</b> (1842638C92)..... <b>PF7779</b> <b>Fuel</b> (625625C1)..... <b>BF984</b> <b>Fuel</b> (625627C1)..... <b>BF979 +</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (1820361C1)..... <b>BW5074</b>	S1854 w/DTI466C (7.6L) Eng. <b>F-F Lube</b> (1808896C1)..... <b>[2] B299 +</b> <b>F-F Lube</b> (1811953C1)..... <b>[2] B309</b> <b>Fuel/Water Separator Ele.</b> (1842638C92)..... <b>PF7779</b> <b>Fuel</b> (625625C1)..... <b>BF984</b> <b>Fuel</b> (625627C1)..... <b>BF979 +</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (1820361C1)..... <b>BW5074</b>	S1925 w/DT466 (7.6L) Eng. <b>Lube</b> (1811953-C1)..... <b>[2] B309</b> <b>Lube</b> (1808896-C1)..... <b>[2] B299 +</b> <b>Lube</b> (675616-C91)..... <b>[2] BT261</b> <b>P. Fuel</b> ..... <b>BF979 +</b> <b>S. Fuel</b> ..... <b>BF588</b> <b>O. Air</b> (476741-C1)..... <b>PA2521</b> <b>Opt. I. Air</b> (Fleetguard AF987)..... <b>PA2522</b> <b>O. Air</b> (478974-C1)..... <b>PA2520</b> <b>I. Air</b> (530778-C1)..... <b>PA2586</b> <b>Comp. Air</b> ..... <b>PA1704</b> <b>Coolant</b> (w/4 Unit BTE) (1801090-C1)..... <b>BW5137</b> <b>Coolant</b> (w/6 Units BTA+) (Fleetguard WF2072)..... <b>BW5072</b> <b>Coolant</b> (w/8 Units BTA+) (Fleetguard WF2073)..... <b>BW5073</b> <b>Coolant</b> (w/12 Units BTA+) (1815588-C1)..... <b>BW5074</b> <b>Coolant</b> (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b> <b>Steering</b> (1653998C91)..... <b>P7134</b>
S1854 w/DT360 (5.9L) Eng. <b>Lube</b> (1808896C1)..... <b>B299 +</b> <b>Lube</b> (1811953C1)..... <b>B309</b> <b>Fuel/Water Separator Spin-on</b> (1808623C1)..... <b>BF7584 +</b> <b>Fuel</b> (1809789C1)..... <b>BF7629 +</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (1820361C1)..... <b>BW5074</b>	S1854 w/DTI466C (7.6L) Eng. <b>F-F Lube</b> (1808896C1)..... <b>[2] B299 +</b> <b>F-F Lube</b> (1811953C1)..... <b>[2] B309</b> <b>Fuel/Water Separator Ele.</b> (1842638C92)..... <b>PF7779</b> <b>Fuel</b> (625625C1)..... <b>BF984</b> <b>Fuel</b> (625627C1)..... <b>BF979 +</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (1820361C1)..... <b>BW5074</b>	S1925 w/DT466 (7.6L) Eng. <b>Lube</b> (1811953-C1)..... <b>[2] B309</b> <b>Lube</b> (1808896-C1)..... <b>[2] B299 +</b> <b>Lube</b> (675616-C91)..... <b>[2] BT261</b> <b>P. Fuel</b> ..... <b>BF979 +</b> <b>S. Fuel</b> ..... <b>BF588</b> <b>O. Air</b> (476741-C1)..... <b>PA2521</b> <b>Opt. I. Air</b> (Fleetguard AF987)..... <b>PA2522</b> <b>O. Air</b> (478974-C1)..... <b>PA2520</b> <b>I. Air</b> (530778-C1)..... <b>PA2586</b> <b>Comp. Air</b> ..... <b>PA1704</b> <b>Coolant</b> (w/4 Unit BTE) (1801090-C1)..... <b>BW5137</b> <b>Coolant</b> (w/6 Units BTA+) (Fleetguard WF2072)..... <b>BW5072</b> <b>Coolant</b> (w/8 Units BTA+) (Fleetguard WF2073)..... <b>BW5073</b> <b>Coolant</b> (w/12 Units BTA+) (1815588-C1)..... <b>BW5074</b> <b>Coolant</b> (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b> <b>Steering</b> (1653998C91)..... <b>P7134</b>
S1854 w/DTA360 (5.9L) Eng. <b>Lube</b> (1808896C1)..... <b>B299 +</b> <b>Lube</b> (1811953C1)..... <b>B309</b> <b>Fuel/Water Separator Spin-on</b> (1808623C1)..... <b>BF7584 +</b> <b>Fuel</b> (1809789C1)..... <b>BF7629 +</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (1820361C1)..... <b>BW5074</b>	S1854 w/DT466 (7.6L) Eng. <b>F-F Lube</b> (1808896C1)..... <b>[2] B299 +</b> <b>F-F Lube</b> (1811953C1)..... <b>[2] B309</b> <b>Fuel/Water Separator Ele.</b> (1842638C92)..... <b>PF7779</b> <b>Fuel</b> (625625C1)..... <b>BF984</b> <b>Fuel</b> (625627C1)..... <b>BF979 +</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (1820361C1)..... <b>BW5074</b>	S1924 w/DT466 (7.6L) Eng. <b>Lube</b> (1811953-C1)..... <b>[2] B309</b> <b>Lube</b> (1808896-C1)..... <b>[2] B299 +</b> <b>Lube</b> (675616-C91)..... <b>[2] BT261</b> <b>P. Fuel</b> ..... <b>BF979 +</b> <b>S. Fuel</b> ..... <b>BF588</b> <b>O. Air</b> (476741-C1)..... <b>PA2521</b> <b>Opt. I. Air</b> (Fleetguard AF987)..... <b>PA2522</b> <b>O. Air</b> (478974-C1)..... <b>PA2520</b> <b>I. Air</b> (530778-C1)..... <b>PA2586</b> <b>Comp. Air</b> ..... <b>PA1704</b> <b>Coolant</b> (w/4 Unit BTE) (1801090-C1)..... <b>BW5137</b> <b>Coolant</b> (w/6 Units BTA+) (Fleetguard WF2072)..... <b>BW5072</b> <b>Coolant</b> (w/8 Units BTA+) (Fleetguard WF2073)..... <b>BW5073</b> <b>Coolant</b> (w/12 Units BTA+) (1815588-C1)..... <b>BW5074</b> <b>Coolant</b> (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b> <b>Steering</b> (1653998C91)..... <b>P7134</b>
S1854 w/DT466 (7.6L) Eng. <b>F-F Lube</b> (1808896C1)..... <b>[2] B299 +</b> <b>F-F Lube</b> (1811953C1)..... <b>[2] B309</b> <b>Fuel/Water Separator Ele.</b> (1842638C92)..... <b>PF7779</b> <b>Fuel</b> (625625C1)..... <b>BF984</b> <b>Fuel</b> (625627C1)..... <b>BF979 +</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (1820361C1)..... <b>BW5074</b>	S1854 w/DT466C (7.6L) Eng. <b>F-F Lube</b> (1808896C1)..... <b>[2] B299 +</b> <b>F-F Lube</b> (1811953C1)..... <b>[2] B309</b> <b>Fuel/Water Separator Ele.</b> (1842638C92)..... <b>PF7779</b> <b>Fuel</b> (625625C1)..... <b>BF984</b> <b>Fuel</b> (625627C1)..... <b>BF979 +</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (1820361C1)..... <b>BW5074</b>	S1924 w/DT466C (7.6L) Eng. <b>Lube</b> (1811953-C1)..... <b>[2] B309</b> <b>Lube</b> (1808896-C1)..... <b>[2] B299 +</b> <b>Lube</b> (675616-C91)..... <b>[2] BT261</b> <b>P. Fuel</b> ..... <b>BF979 +</b> <b>S. Fuel</b> ..... <b>BF588</b> <b>O. Air</b> (476741-C1)..... <b>PA2521</b> <b>Opt. I. Air</b> (Fleetguard AF987)..... <b>PA2522</b> <b>O. Air</b> (478974-C1)..... <b>PA2520</b> <b>I. Air</b> (530778-C1)..... <b>PA2586</b> <b>Comp. Air</b> ..... <b>PA1704</b> <b>Coolant</b> (w/4 Unit BTE) (1801090-C1)..... <b>BW5137</b> <b>Coolant</b> (w/6 Units BTA+) (Fleetguard WF2072)..... <b>BW5072</b> <b>Coolant</b> (w/8 Units BTA+) (Fleetguard WF2073)..... <b>BW5073</b> <b>Coolant</b> (w/12 Units BTA+) (1815588-C1)..... <b>BW5074</b> <b>Coolant</b> (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b> <b>Steering</b> (1653998C91)..... <b>P7134</b>
S1854 w/DT466 (7.6L) Eng. <b>F-F Lube</b> (1808896C1)..... <b>[2] B299 +</b> <b>F-F Lube</b> (1811953C1)..... <b>[2] B309</b> <b>Fuel/Water Separator Ele.</b> (1842638C92)..... <b>PF7779</b> <b>Fuel</b> (625625C1)..... <b>BF984</b> <b>Fuel</b> (625627C1)..... <b>BF979 +</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (1820361C1)..... <b>BW5074</b>	S1854 w/DT466C (7.6L) Eng. <b>F-F Lube</b> (1808896C1)..... <b>[2] B299 +</b> <b>F-F Lube</b> (1811953C1)..... <b>[2] B309</b> <b>Fuel/Water Separator Ele.</b> (1842638C92)..... <b>PF7779</b> <b>Fuel</b> (625625C1)..... <b>BF984</b> <b>Fuel</b> (625627C1)..... <b>BF979 +</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (1820361C1)..... <b>BW5074</b>	S1924 w/DT466C (7.6L) Eng. <b>Lube</b> (1811953-C1)..... <b>[2] B309</b> <b>Lube</b> (1808896-C1)..... <b>[2] B299 +</b> <b>Lube</b> (675616-C91)..... <b>[2] BT261</b> <b>P. Fuel</b> ..... <b>BF979 +</b> <b>S. Fuel</b> ..... <b>BF588</b> <b>O. Air</b> (476741-C1)..... <b>PA2521</b> <b>Opt. I. Air</b> (Fleetguard AF987)..... <b>PA2522</b> <b>O. Air</b> (478974-C1)..... <b>PA2520</b> <b>I. Air</b> (530778-C1)..... <b>PA2586</b> <b>Comp. Air</b> ..... <b>PA1704</b> <b>Coolant</b> (w/4 Unit BTE) (1801090-C1)..... <b>BW5137</b> <b>Coolant</b> (w/6 Units BTA+) (Fleetguard WF2072)..... <b>BW5072</b> <b>Coolant</b> (w/8 Units BTA+) (Fleetguard WF2073)..... <b>BW5073</b> <b>Coolant</b> (w/12 Units BTA+) (1815588-C1)..... <b>BW5074</b> <b>Coolant</b> (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b> <b>Steering</b> (1653998C91)..... <b>P7134</b>
S1854 w/DT466 (7.6L) Eng. <b>F-F Lube</b> (1808896C1)..... <b>[2] B299 +</b> <b>F-F Lube</b> (1811953C1)..... <b>[2] B309</b> <b>Fuel/Water Separator Ele.</b> (1842638C92)..... <b>PF7779</b> <b>Fuel</b> (625625C1)..... <b>BF984</b> <b>Fuel</b> (625627C1)..... <b>BF979 +</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (1820361C1)..... <b>BW5074</b>	S1854 w/DT466C (7.6L) Eng. <b>F-F Lube</b> (1808896C1)..... <b>[2] B299 +</b> <b>F-F Lube</b> (1811953C1)..... <b>[2] B309</b> <b>Fuel/Water Separator Ele.</b> (1842638C92)..... <b>PF7779</b> <b>Fuel</b> (625625C1)..... <b>BF984</b> <b>Fuel</b> (625627C1)..... <b>BF979 +</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (1820361C1)..... <b>BW5074</b>	S1924 w/DT466C (7.6L) Eng. <b>Lube</b> (1811953-C1)..... <b>[2] B309</b> <b>Lube</b> (1808896-C1)..... <b>[2] B299 +</b> <b>Lube</b> (675616-C91)..... <b>[2] BT261</b> <b>P. Fuel</b> ..... <b>BF979 +</b> <b>S. Fuel</b> ..... <b>BF588</b> <b>O. Air</b> (476741-C1)..... <b>PA2521</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
S1954 w/DT466C (7.6L) Eng. (Cont'd)	S1954 w/DTA466C (7.6L) Eng. (Cont'd)	S1955 w/DT466C (7.6L) Eng. (Cont'd)
Opt. I. Air (Fleetguard AF987)..... PA2522	Coolant (w/15 Units BTA+)..... BW5075	Comp. Air..... PA1704
O. Air (478974-C1)..... PA2520	(Fleetguard WF2075).....	Coolant (w/4 Unit BTE)
I. Air (530778-C1)..... PA2586	Steering (1653998C91)..... P7134	(1801090-C1)..... BW5137
Comp. Air..... PA1704	S1954 w/DTI466C (7.6L) Eng.	Coolant (w/6 Units BTA+)
Coolant (w/4 Unit BTE)	Lube (1811953-C1)..... [2] B309	(Fleetguard WF2072)..... BW5072
(1801090-C1)..... BW5137	Lube (1808896-C1)..... [2] B299 +	Coolant (w/8 Units BTA+)
Coolant (w/6 Units BTA+)	Lube (675616-C91)..... [2] BT261	(Fleetguard WF2073)..... BW5073
(Fleetguard WF2072)..... BW5072	P. Fuel..... BF979 +	Coolant (w/12 Units BTA+)
Coolant (w/8 Units BTA+)	S. Fuel..... BF588	(1815588-C1)..... BW5074
(Fleetguard WF2073)..... BW5073	O. Air (476741-C1)..... PA2521	Coolant (w/15 Units BTA+)
Coolant (w/12 Units BTA+)	Opt. I. Air (Fleetguard AF987)..... PA2522	(Fleetguard WF2075)..... BW5075
(1815588-C1)..... BW5074	O. Air (478974-C1)..... PA2520	Steering (1653998C91)..... P7134
Coolant (w/15 Units BTA+)	I. Air (530778-C1)..... PA2586	S1955 w/DTA466 (7.6L) Eng.
(Fleetguard WF2075)..... BW5075	Comp. Air..... PA1704	Lube (1811953-C1)..... [2] B309
Steering (1653998C91)..... P7134	Coolant (w/4 Unit BTE)	Lube (1808896-C1)..... [2] B299 +
S1954 w/DTA466 (7.6L) Eng.	(1801090-C1)..... BW5137	Lube (675616-C91)..... [2] BT261
Lube (1811953-C1)..... [2] B309	Coolant (w/6 Units BTA+)	P. Fuel..... BF979 +
Lube (1808896-C1)..... [2] B299 +	(Fleetguard WF2072)..... BW5072	S. Fuel..... BF588
Lube (675616-C91)..... [2] BT261	Coolant (w/8 Units BTA+)	Single Air (470185-C92)..... PA2521
P. Fuel..... BF979 +	(Fleetguard WF2073)..... BW5073	O. Air (476741-C1)..... PA2521
S. Fuel..... BF588	Coolant (w/12 Units BTA+)	I. Air (Fleetguard AF987)..... PA2522
Single Air (470185-C92)..... PA2521	(1815588-C1)..... BW5074	O. Air (478974-C1)..... PA2520
O. Air (476741-C1)..... PA2521	Coolant (w/15 Units BTA+)	I. Air (530778-C1)..... PA2586
I. Air (Fleetguard AF987)..... PA2522	(Fleetguard WF2075)..... BW5075	Comp. Air..... PA1704
O. Air (478974-C1)..... PA2520	Steering (1653998C91)..... P7134	Coolant (w/4 Unit BTE)
I. Air (530778-C1)..... PA2586	S1955 w/DT466 (7.6L) Eng.	(1801090-C1)..... BW5137
Comp. Air..... PA1704	Lube (1811953-C1)..... [2] B309	Coolant (w/6 Units BTA+)
Coolant (w/4 Unit BTE)	Lube (1808896-C1)..... [2] B299 +	(Fleetguard WF2072)..... BW5072
(1801090-C1)..... BW5137	Lube (675616-C91)..... [2] BT261	Coolant (w/8 Units BTA+)
Coolant (w/6 Units BTA+)	P. Fuel..... BF979 +	(Fleetguard WF2073)..... BW5073
(Fleetguard WF2072)..... BW5072	S. Fuel..... BF588	Coolant (w/12 Units BTA+)
Coolant (w/8 Units BTA+)	O. Air (476741-C1)..... PA2521	(1815588-C1)..... BW5074
(Fleetguard WF2073)..... BW5073	Opt. I. Air (Fleetguard AF987)..... PA2522	Coolant (w/15 Units BTA+)
Coolant (w/12 Units BTA+)	O. Air (478974-C1)..... PA2520	(Fleetguard WF2075)..... BW5075
(1815588-C1)..... BW5074	I. Air (530778-C1)..... PA2586	Steering (1653998C91)..... P7134
Coolant (w/15 Units BTA+)	Comp. Air..... PA1704	S1955 w/DTA466C (7.6L) Eng.
(Fleetguard WF2075)..... BW5075	Coolant (w/4 Unit BTE)	Lube (1811953-C1)..... [2] B309
Steering (1653998C91)..... P7134	(1801090-C1)..... BW5137	Lube (1808896-C1)..... [2] B299 +
S1954 w/DTA466C (7.6L) Eng.	Coolant (w/6 Units BTA+)	Lube (675616-C91)..... [2] BT261
Lube (1811953-C1)..... [2] B309	(Fleetguard WF2072)..... BW5072	P. Fuel..... BF979 +
Lube (1808896-C1)..... [2] B299 +	Coolant (w/8 Units BTA+)	S. Fuel..... BF588
Lube (675616-C91)..... [2] BT261	(Fleetguard WF2073)..... BW5073	Single Air (470185-C92)..... PA2521
P. Fuel..... BF979 +	Coolant (w/12 Units BTA+)	O. Air (476741-C1)..... PA2521
S. Fuel..... BF588	(1815588-C1)..... BW5074	I. Air (Fleetguard AF987)..... PA2522
Single Air (470185-C92)..... PA2521	Coolant (w/15 Units BTA+)	O. Air (478974-C1)..... PA2520
O. Air (476741-C1)..... PA2521	(Fleetguard WF2075)..... BW5075	I. Air (530778-C1)..... PA2586
I. Air (Fleetguard AF987)..... PA2522	Steering (1653998C91)..... P7134	Comp. Air..... PA1704
O. Air (478974-C1)..... PA2520	S1955 w/DT466C (7.6L) Eng.	Coolant (w/4 Unit BTE)
I. Air (530778-C1)..... PA2586	Lube (1811953-C1)..... [2] B309	(1801090-C1)..... BW5137
Comp. Air..... PA1704	Lube (1808896-C1)..... [2] B299 +	Coolant (w/6 Units BTA+)
Coolant (w/4 Unit BTE)	Lube (675616-C91)..... [2] BT261	(Fleetguard WF2072)..... BW5072
(1801090-C1)..... BW5137	P. Fuel..... BF979 +	Coolant (w/8 Units BTA+)
Coolant (w/6 Units BTA+)	S. Fuel..... BF588	(Fleetguard WF2073)..... BW5073
(Fleetguard WF2072)..... BW5072	Single Air (470185-C92)..... PA2521	Coolant (w/12 Units BTA+)
Coolant (w/8 Units BTA+)	O. Air (476741-C1)..... PA2521	(1815588-C1)..... BW5074
(Fleetguard WF2073)..... BW5073	I. Air (Fleetguard AF987)..... PA2522	Coolant (w/15 Units BTA+)
Coolant (w/12 Units BTA+)	O. Air (478974-C1)..... PA2520	(Fleetguard WF2075)..... BW5075
(1815588-C1)..... BW5074	I. Air (530778-C1)..... PA2586	Steering (1653998C91)..... P7134


\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
S1955 w/DTI466C (7.6L) Eng. Lube (1811953-C1)..... [2] B309 Lube (1808896-C1)..... [2] B299 + Lube (675616-C91)..... [2] BT261 P. Fuel..... BF979 + S. Fuel..... BF588 Single Air (470185-C92)..... PA2521 O. Air (476741-C1)..... PA2521 I. Air (Fleetguard AF987)..... PA2522 O. Air (478974-C1)..... PA2520 I. Air (530778-C1)..... PA2586 Comp. Air..... PA1704 Coolant (w/4 Unit BTE) (1801090-C1)..... BW5137 Coolant (w/6 Units BTA+) (Fleetguard WF2072)..... BW5072 Coolant (w/8 Units BTA+) (Fleetguard WF2073)..... BW5073 Coolant (w/12 Units BTA+) (1815588-C1)..... BW5074 Coolant (w/15 Units BTA+) (Fleetguard WF2075)..... BW5075 Steering (1653998C91)..... P7134	S2155 w/DTA466 (7.6L) Eng. F-F Lube (1808896C1)..... [2] B299 + F-F Lube (1811953C1)..... [2] B309 Fuel/Water Separator Ele. (1842638C92)..... PF7779 Fuel (625625C1)..... BF984 Fuel (625627C1)..... BF979 + Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071 Coolant (w/12 Units BTA+) (1820361C1)..... BW5074 S2155 w/DTA466C (7.6L) Eng. F-F Lube (1808896C1)..... [2] B299 + F-F Lube (1811953C1)..... [2] B309 Fuel/Water Separator Ele. (1842638C92)..... PF7779 Fuel (625625C1)..... BF984 Fuel (625627C1)..... BF979 + Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071 Coolant (w/12 Units BTA+) (1820361C1)..... BW5074 S2155 w/DTI466C (7.6L) Eng. F-F Lube (1808896C1)..... [2] B299 + F-F Lube (1811953C1)..... [2] B309 Fuel/Water Separator Ele. (1842638C92)..... PF7779 Fuel (625625C1)..... BF984 Fuel (625627C1)..... BF979 + Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071 Coolant (w/12 Units BTA+) (1820361C1)..... BW5074 S2375 w/DTA466 (7.6L) Eng. F-F Lube (1808896C1)..... [2] B299 + F-F Lube (1811953C1)..... [2] B309 Fuel/Water Separator Ele. (1842638C92)..... PF7779 Fuel (625625C1)..... BF984 Fuel (625627C1)..... BF979 + Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071 Coolant (w/12 Units BTA+) (1820361C1)..... BW5074 S2524 w/DT466 (7.6L) Eng. F-F Lube (1808896C1)..... [2] B299 + F-F Lube (1811953C1)..... [2] B309 Fuel/Water Separator Ele. (1842638C92)..... PF7779 Fuel (625625C1)..... BF984 Fuel (625627C1)..... BF979 + Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071 Coolant (w/12 Units BTA+) (1820361C1)..... BW5074	S2554 w/DT466 (7.6L) Eng. F-F Lube (1808896C1)..... [2] B299 + F-F Lube (1811953C1)..... [2] B309 Fuel/Water Separator Ele. (1842638C92)..... PF7779 Fuel (625625C1)..... BF984 Fuel (625627C1)..... BF979 + Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071 Coolant (w/12 Units BTA+) (1820361C1)..... BW5074 S2554 w/DT466C (7.6L) Eng. F-F Lube (1808896C1)..... [2] B299 + F-F Lube (1811953C1)..... [2] B309 Fuel/Water Separator Ele. (1842638C92)..... PF7779 Fuel (625625C1)..... BF984 Fuel (625627C1)..... BF979 + Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071 Coolant (w/12 Units BTA+) (1820361C1)..... BW5074 S2554 w/DTA466 (7.6L) Eng. F-F Lube (1808896C1)..... [2] B299 + F-F Lube (1811953C1)..... [2] B309 Fuel/Water Separator Ele. (1842638C92)..... PF7779 Fuel (625625C1)..... BF984 Fuel (625627C1)..... BF979 + Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071 Coolant (w/12 Units BTA+) (1820361C1)..... BW5074 S2554 w/DTA466C (7.6L) Eng. F-F Lube (1808896C1)..... [2] B299 + F-F Lube (1811953C1)..... [2] B309 Fuel/Water Separator Ele. (1842638C92)..... PF7779 Fuel (625625C1)..... BF984 Fuel (625627C1)..... BF979 + Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071 Coolant (w/12 Units BTA+) (1820361C1)..... BW5074 S2650 w/Cummins NTC Eng. Dual-Flow Lube (3318853)..... BD103 + Fuel/Water Separator (3315843)..... BF1212 + S3600 w/Cummins N14 Eng. Dual-Flow Lube (3825970)..... BD103 + Fuel/Water Separator (3315843)..... BF1212 + Coolant (3844234)..... BW5076 TerraStar w/MaxxForce 7 (6.4L) Eng. (To 2011) Lube Ele. (w/o Screw on Cap) (1840752-C91)..... P7235 Lube Ele. (w/Screw on Cap) (Wix 57312)..... P7436 Lube Spin-on (1899332-C91)..... B7506

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)	INTERNATIONAL Trucks & Buses (cont'd)
TerraStar w/MaxxFace 7 (6.4L) Eng. (To 2011) (Cont'd)	TerraStar w/MaxxFace 7 (6.4L) Eng. (2017) (Cont'd)	TranStar w/Cat C13 Eng. (Cont'd)
<b>Fuel/Water Separator</b> (1878042-C91)..... PF7978	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... 20017	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT
<b>Primary EnduraCube Air</b> (2602212-C1)..... PA32001	<b>Trans. Spin-on</b> (Allison 29539579)..... BT8460	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... B2+
<b>Secondary EnduraCube Air</b> (2602211-C1)..... PA32004	TerraStar w/MaxxFace 7 (6.4L) Eng. (2018)	<b>Steering</b> (2503221-C1)..... BT9388
<b>Cab Air</b> (3839141-C1)..... PA5679	<b>Lube</b> (1899332C91)..... B7506	TranStar w/Cummins ISM Eng.
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... 20004	<b>Fuel/Water Separator</b> (1878042C91)..... PF7978	<b>Dual-Flow Lube</b> (Fleetguard LF9001)..... BD7154+
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... 20016	<b>Fuel</b> (1884207C92)..... PF9914 KIT	<b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... BD50000
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... 20003	<b>Primary EnduraCube Air</b> (2517298C1)..... PA32001	<b>Fuel/Water Separator Ele.</b> ..... PF7748
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... 20017	<b>Secondary EnduraCube Air</b> (2602211C1)..... PA32004	<b>Fuel/Water Separator Ele.</b> ..... PF7680
<b>Trans. Spin-on</b> (Allison 29539579)..... BT8460	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... 20004	<b>Fuel/Water Separator Spin-on</b> ..... BF1259
<b>Steering</b> (2503221C3)..... BT9388	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... 20016	<b>Radial Seal O. Air</b> (3551814-C1)..... RS4862
TerraStar w/MaxxFace 7 (6.4L) Eng. (2012-16)	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... 20003	<b>Radial Seal I. Air</b> (3551815-C1)..... RS4863
<b>Lube Ele.</b> (w/o Screw on Cap) (1840752-C91)..... P7235	<b>Trans. Spin-on</b> (Allison 29539579)..... BT8460	<b>Cab Air</b> (2506656-C1)..... PA4985
<b>Lube Ele.</b> (w/Screw on Cap) (Wix 57312)..... P7436	TranStar w/Cat C11 Eng.	<b>Air Dryer</b> (Bendix 107796)..... BA5377
<b>Lube Spin-on</b> (1899332-C91)..... B7506	<b>Lube</b> (1R1808)..... B7299+	<b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071
<b>Fuel/Water Separator</b> (1878042-C91)..... PF7978	<b>Fuel/Water Separator</b> (Fleetguard FS19683)..... BF1268	<b>Coolant</b> (w/4 Units BTE)..... BW5137
<b>Fuel Kit</b> (1884207-C91)..... PF9914 KIT	<b>Fuel</b> (1R0749)..... BF7587+	<b>Coolant</b> (w/8 Units BTE)..... BW5139
<b>Primary EnduraCube Air</b> (2602212-C1)..... PA32001	<b>Radial Seal O. Air</b> (3551814-C1)..... RS4862	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29526899)..... PT9416-MPG KIT
<b>Secondary EnduraCube Air</b> (2602211-C1)..... PA32004	<b>Radial Seal I. Air</b> (3551815-C1)..... RS4863	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT
<b>Cab Air</b> (3839141-C1)..... PA5679	<b>Cab Air</b> (2506656-C1)..... PA4985	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... B2+
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... 20004	<b>Air Dryer</b> (Bendix 107796)..... BA5377	<b>Steering</b> (2503221-C1)..... BT9388
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... 20016	<b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071	TranStar w/MaxxFace 10 Eng.
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... 20003	<b>Coolant</b> (w/4 Units BTE)..... BW5137	<b>Dual-Flow Lube</b> (1842639-C91)..... BD7250
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... 20017	<b>Coolant</b> (w/8 Units BTE)..... BW5139	<b>Fuel/Water Separator Ele.</b> (1842638-C91)..... PF7779
<b>Trans. Spin-on</b> (Allison 29539579)..... BT8460	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29526899)..... PT9416-MPG KIT	<b>Radial Seal O. Air</b> (3532799-C1)..... RS4636+
<b>Steering</b> (2503221C3)..... BT9388	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	<b>Cab Air</b> (2506656-C1)..... PA4985
TerraStar w/MaxxFace 7 (6.4L) Eng. (2017)	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... B2+	<b>Air Dryer</b> (Wabco R950011)..... BA5374+
<b>Lube</b> (1899332C91)..... B7506	<b>Steering</b> (2503221-C1)..... BT9388	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... B2+
<b>Fuel Kit</b> (1884207C92)..... PF9914 KIT	TranStar w/Cat C13 Eng.	<b>Steering</b> (2503221-C1)..... BT9388
<b>Primary EnduraCube Air</b> (2517298C1)..... PA32001	<b>Lube</b> (1R1808)..... B7299+	Workstar 7600 w/N13 (12.4L) Eng. (2019)
<b>Secondary EnduraCube Air</b> (2602211C1)..... PA32004	<b>Fuel/Water Separator</b> ..... PF7748	<b>Lube</b> (3007498C94)..... P7494
<b>Cab Air</b> (3839141C1)..... PA5679	<b>Fuel</b> (1R0749)..... BF7587+	<b>Fuel/Water Separator</b> (Fleetguard FS19765)..... PF7930
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... 20004	<b>Radial Seal O. Air</b> (3551814-C1)..... RS4862	<b>Fuel/Water Separator</b> (3004473C93)..... PF7986
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... 20016	<b>Radial Seal I. Air</b> (3551815-C1)..... RS4863	<b>Radial Seal Air</b> (Fleetguard AF26103)..... RS4862
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... 20003	<b>Cab Air</b> (2506656-C1)..... PA4985	<b>Cab Air</b> (3839141C1)..... PA5679
	<b>Air Dryer</b> (Bendix 107796)..... BA5377	<b>Air Dryer</b> (Wabco R950011)..... BA5374+
	<b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071	
	<b>Coolant</b> (w/4 Units BTE)..... BW5137	
	<b>Coolant</b> (w/8 Units BTE)..... BW5139	
	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29526899)..... PT9416-MPG KIT	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

**Trucks & Buses Applications** **BALDWIN FILTERS**

<b>INTERNATIONAL Trucks &amp; Buses (cont'd)</b>	<b>INTERNATIONAL Trucks &amp; Buses (cont'd)</b>	<b>ISUZU Engines</b>
Workstar 7600 w/N13 (12.4L) Eng. (2019) (Cont'd) Trans. (Fuller 4304827)..... <b>BT223</b>	WorkStar w/DT530 Eng. (Cont'd) <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-SP System) (Bendix 109994)..... <b>BA5374 +</b> <b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Steering</b> (2503221-C1)..... <b>BT9388</b>	2AB1, 3AB1 <b>Lube</b> ..... <b>B229</b> <b>Fuel Spin-on</b> ..... <b>BF954 +</b>
WorkStar w/Cat C11 Eng. <b>Lube</b> (1R1808)..... <b>B7299 +</b> <b>Fuel/Water Separator</b> ..... <b>BF1262</b> <b>Fuel</b> (1R0749)..... <b>BF7587 +</b> <b>Fuel</b> (Fleetguard FF202)..... <b>BF596 +</b> <b>Radial Seal O. Air</b> (3551814-C1)..... <b>RS4862</b> <b>Radial Seal I. Air</b> (3551815-C1)..... <b>RS4863</b> <b>Cab Air</b> (2506656-C1)..... <b>PA4985</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-SP System) (Bendix 109994)..... <b>BA5374 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29526899)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (2503221-C1)..... <b>BT9388</b>	4BA1 <b>Lube</b> (9-88511-194-2)..... <b>P7050</b> <b>Fuel Ele.</b> (5-87810-050-0)..... <b>PF313</b> <b>Fuel Spin-on</b> (5-13240-023-0)..... <b>BF7648</b>	
WorkStar w/DT466 Eng. <b>Dual-Flow Lube</b> (1842638-C91)..... <b>BD7250</b> <b>Fuel/Water Separator</b> (1842638-C91)..... <b>PF7779</b> <b>Radial Seal O. Air</b> (3532799-C1)..... <b>RS4636 +</b> <b>Radial Seal I. Air</b> (3532800-C1)..... <b>RS4637</b> <b>Cab Air</b> (2506656-C1)..... <b>PA4985</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-SP System) (Bendix 109994)..... <b>BA5374 +</b> <b>Crankcase Breather</b> (2007 Emissions) (3683918)..... <b>CV15000</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29526899)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Steering</b> (2503221-C1)..... <b>BT9388</b>	4BB1, 4BD1 (3.9L) <b>Lube Ele.</b> (9-88513-106-1)..... <b>P266</b> <b>Lube Spin-on</b> (13201-2)..... <b>B118</b> <b>Fuel Ele.</b> ..... <b>PF313</b> <b>Fuel Spin-on</b> ..... <b>BF954 +</b>	
WorkStar w/DT530 Eng. <b>Dual-Flow Lube</b> (1842638-C91)..... <b>BD7250</b> <b>Fuel/Water Separator</b> (1842638-C91)..... <b>PF7779</b> <b>Fuel</b> ..... <b>BF7629 +</b> <b>Radial Seal O. Air</b> (3532799-C1)..... <b>RS4636 +</b> <b>Radial Seal I. Air</b> (3532800-C1)..... <b>RS4637</b> <b>Cab Air</b> (2506656-C1)..... <b>PA4985</b>	WorkStar w/DT570 Eng. <b>Dual-Flow Lube</b> (1842639-C91)..... <b>BD7250</b> <b>Fuel/Water Separator</b> ..... <b>PF7782</b> <b>Radial Seal O. Air</b> (3532799-C1)..... <b>RS4636 +</b> <b>Radial Seal I. Air</b> (3532800-C1)..... <b>RS4637</b> <b>Cab Air</b> (2506656-C1)..... <b>PA4985</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-SP System) (Bendix 109994)..... <b>BA5374 +</b> <b>Crankcase Breather</b> ..... <b>CLN&amp;R</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Steering</b> (2503221-C1)..... <b>BT9388</b>	4BC1, 4BC2 <b>Lube</b> (9-88511-194-2)..... <b>P7050</b> <b>Fuel Ele.</b> (5-87810-050-0)..... <b>PF313</b> <b>Fuel Spin-on</b> (5-13240-023-0)..... <b>BF7648</b>
WorkStar w/DT530 Eng. <b>Dual-Flow Lube</b> (1842639-C91)..... <b>BD7250</b> <b>Fuel/Water Separator</b> (1842638-C91)..... <b>PF7779</b> <b>Fuel</b> ..... <b>BF7629 +</b> <b>Radial Seal O. Air</b> (3532799-C1)..... <b>RS4636 +</b> <b>Radial Seal I. Air</b> (3532800-C1)..... <b>RS4637</b> <b>Cab Air</b> (2506656-C1)..... <b>PA4985</b>	WorkStar w/HT570 Eng. <b>Dual-Flow Lube</b> (1842639-C91)..... <b>BD7250</b> <b>Fuel/Water Separator</b> (1842638-C91)..... <b>PF7779</b> <b>Radial Seal Air</b> (3532799-C1)..... <b>RS4636 +</b> <b>Cab Air</b> (2506656-C1)..... <b>PA4985</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-SP System) (Bendix 109994)..... <b>BA5374 +</b> <b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (2503221-C1)..... <b>BT9388</b>	4BD1T (3.9L) <b>F-F Lube</b> (8-94169-778-2)..... <b>B244</b> <b>B-P Lube</b> (8-94169-779-2)..... <b>B222</b> <b>Fuel</b> ..... <b>[2] BF7648</b>
		4BD2T (3.9L) <b>Dual-Flow Lube</b> (8-97148-280-0)..... <b>BD7166</b> <b>Fuel</b> (5-87310-335-0)..... <b>BF7648</b>
		4BG1, 4BG1T (4.3L) <b>Lube</b> (8-94321-219-1)..... <b>B7144</b> <b>Some Fuel Spin-on</b> ..... <b>BF954 +</b>
		4HE1T, 4HF1T (4.8L) <b>Dual-Flow Lube</b> (w/Inter-Cooler) (8-97148-270-0)..... <b>BD7169</b> <b>Dual-Flow Lube</b> (w/o Inter-Cooler) (8-94338-181-1)..... <b>BD7159</b> <b>Fuel Spin-on</b> (8-94151-744-0)..... <b>BF7648</b>
		4HG1 <b>Dual-Flow Lube</b> (w/Inter-Cooler) (8-97148-270-0)..... <b>BD7169</b> <b>Dual-Flow Lube</b> (w/o Inter-Cooler) (8-94338-181-1)..... <b>BD7159</b> <b>Fuel Spin-on</b> (8-94151-744-0)..... <b>BF7648</b>
		4HJ1 <b>Dual-Flow Lube</b> (w/Inter-Cooler) (8-97148-270-0)..... <b>BD7169</b> <b>Fuel</b> (8-97172-549-0)..... <b>BF7648</b>
		4HK1 (5.2L) <b>Lube</b> (8982984040)..... <b>B40137</b> <b>Dual-Flow Lube</b> (8-97148-270-1)..... <b>BD7169</b> <b>Fuel/Water Separator</b> (2004-07) (94369299)..... <b>BF7534</b> <b>Fuel</b> (2008-10) (8-98037-011-0)..... <b>PF9919</b> <b>Fuel</b> (2011-on (Engine Side)) (8-98147-525-0)..... <b>PF46059</b> <b>Fuel</b> (2011-on (Chassis Side)) (8-98147-570-0)..... <b>PF40052</b>
		4JJ1-TC (3.0L) <b>Lube Ele.</b> (8980188580)..... <b>P40021</b> <b>Lube Spin-on</b> (8982984040)..... <b>B40137</b> <b>Fuel/Water Separator</b> (8-98037-481-0)..... <b>BF7534</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

ISUZU Engines (cont'd)	ISUZU Engines (cont'd)	ISUZU Trucks (cont'd)
4JJ1-TC (3.0L) (Cont'd)	QD90, QD100	CXH300 w/6RA1TRC Eng. (1987-90)
Fuel Ele. (8981475250)..... PF46059	Lube Ele. (9-88513-106-1)..... P266	S. Fuel (1878103670)..... PF7618
S. Fuel (8-98162-897-0)..... PF9919	Lube Spin-on (13201-2)..... B118	I. Air (1142150810)..... PA2903
6BB1, 6BD1 (5.8L)	Fuel Ele. .... PF313	CXH350 w/6RB1TRC Eng. (1987-90)
Lube Ele. (9878100750)..... P723	Fuel Spin-on..... BF954 +	S. Fuel (1878103670)..... PF7618
Fuel Ele. (9885131160)..... PF311	QD100T Auto	I. Air (1142150810)..... PA2903
Fuel Spin-on (5876100110)..... BF954 +	F-F Lube..... B244	CXH370 w/6RB1TRC Eng. (1991-95)
6BD1T (5.8L)	B-P Lube..... B222	S. Fuel (1878103670)..... PF7618
F-F Lube (1-13200-487-0)..... B75	QD130, QD145, QD145T	I. Air (1142150810)..... PA2903
B-P Lube (1-13240-089-0)..... B7124	Lube (1-87810-075-01)..... P723	Coolant (After Eng. Flush)
Fuel (1-13240-074-0)..... BF7602	Fuel Ele. (9-88511-191-1)..... PF311	(ACDelco WF102)..... BW5140
6BG1, 6BG1T (6.5L)	Fuel Spin-on..... BF954 +	Coolant (Every 32000km)
F-F Lube (1-13200-487-0)..... B75	QD200, QD200T	(ACDelco WF100)..... BW5137
B-P Lube (1-13240-089-0)..... B7124	Lube Ele..... PT466	CXZ w/6WA1TC Eng. (1997-on)
Fuel (1-13240-074-0)..... BF7602	<b>ISUZU Trucks</b>	S. Fuel (1132401940)..... PF9897
6HK1 (7.8L)	BE20 w/4BB1 Eng.	CXZ w/6WG1TCN Eng. (1997-on)
Lube (94037791)..... B75	Lube Ele. (9-88511-194-2)..... P7050	S. Fuel (1132401940)..... PF9897
Fuel (2008-on) (8-98037-011-0).... PF9919	Fuel Ele. (5-87810-050-0)..... PF313	CXZ16QRXT w/6RA1TRC Eng. (1991-95)
6SA1, 6SA1T	Fuel Spin-on (5-13240-023-0).... BF7648	S. Fuel (1878103670)..... PF7618
F-F Lube (1-13200-487-0)..... B75	BL34 w/4BA1 Eng.	I. Air (1142150810)..... PA2903
B-P Lube (1-13240-089-0)..... B7124	Lube Ele. (9-88511-194-2)..... P7050	CXZ16QXT w/6RA1TRC Eng. (1987-90)
Fuel (1-13240-074-0)..... BF7602	Fuel Spin-on (5-13240-023-0).... BF7648	S. Fuel (1878103670)..... PF7618
C223	BLD30 w/4BA1 Eng.	I. Air (1142150810)..... PA2903
Lube..... B7585	Lube Ele. (9-88511-194-2)..... P7050	CXZ18QRX3T w/6RB1TRC Eng. (1991-95)
C240 (2.4L)	Fuel Spin-on (5-13240-023-0).... BF7648	S. Fuel (1878103670)..... PF7618
Lube Ele..... P266	CXH16VRXT w/6RA1TRC Eng. (1991-95)	I. Air (1142150810)..... PA2903
Lube Spin-on..... B118	S. Fuel (1878103670)..... PF7618	CXZ18QX3T w/6RB1TRC Eng. (1987-90)
Fuel Spin-on (X13240-015)..... BF7648	I. Air (1142150810)..... PA2903	S. Fuel (1878103670)..... PF7618
D500	CXH16VXT w/6RA1TRC Eng. (1987-90)	I. Air (1142150810)..... PA2903
Fuel Ele. (9-88511-191-1)..... PF311	S. Fuel (1878103670)..... PF7618	CXZ164 w/6RA1 Eng. (1984-on)
DA120	I. Air (1142150810)..... PA2903	S. Fuel (1878103670)..... PF7618
Lube..... P150	CXH18 w/6RB1TRC Eng. (1991-95)	O. Std. Air (1142151160)..... PA2676 +
Fuel Ele..... PF950	S. Fuel (1878103670)..... PF7618	O. XP Air (1142151160)..... PA2676XP
DA220	I. Air (1142150810)..... PA2903	I. Air (1142151270)..... PA3668
Lube..... P150	Coolant (After Eng. Flush)	CXZ167T, CXZ167TRC w/6RA1T, 6RA1TRC
DA640	(ACDelco WF102)..... BW5140	Eng. (1984-87)
Lube (9-88513-264-1)..... P7084	Coolant (Every 32000km)	S. Fuel (1878103670)..... PF7618
Fuel Ele. (9-88511-191-1)..... PF311	(ACDelco WF100)..... BW5137	I. Air (1142150810)..... PA2903
E120, E120T	CXH18, CXZ18 w/6RB1TRC Eng. (1995-97)	CXZ300 w/6RA1TRC Eng. (1987-90)
Lube Ele. (9-88513-265-0)..... PT466	S. Fuel (1878103670)..... PF7618	S. Fuel (1878103670)..... PF7618
11B (5.2L)	I. Air (1142150810)..... PA2903	I. Air (1142150810)..... PA2903
Lube (98298404)..... B40137	CXH18VX3T w/6RB1TRC Eng. (1987-90)	CXZ350 w/6RB1TRC Eng. (1987-90)
Fuel/Water Separator (Chassis	S. Fuel (1878103670)..... PF7618	S. Fuel (1878103670)..... PF7618
Side) (98037481)..... BF7534	I. Air (1142150810)..... PA2903	I. Air (1142150810)..... PA2903
Fuel (Eng. Side) (98147525)..... PF46059	CXH50 w/6WA1TC Eng. (1997-on)	CXZ370 w/6RB1TRC Eng. (1991-95)
QD27, QD40	S. Fuel (1132401940)..... PF9897	S. Fuel (1878103670)..... PF7618
Lube..... B229	CXH52 w/6WG1TCN Eng. (1997-on)	I. Air (1142150810)..... PA2903
Fuel Spin-on..... BF954 +	S. Fuel (1132401940)..... PF9897	ELF150 w/C190, C240 Engs.
QD60	CXH169T, CXH169TRC w/6RA1T, 6RA1TRC	Lube Ele. (9-88511-194-2)..... P7050
Lube Ele. (9-88513-106-1)..... P266	Eng. (1984-87)	Fuel Spin-on (8-94143-479-0).... BF7648
Lube Spin-on..... B118	S. Fuel (1878103670)..... PF7618	Air (8-94156-052-0)..... PA2712
Fuel Spin-on..... BF954 +	I. Air (1142150810)..... PA2903	ELF 200/300 w/4JJ1-TC (3.0L) Turbo Diesel
		Eng. Mexico
		Lube (8980188580)..... P40021
		Fuel (8-98037-011-0)..... PF9919

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>ISUZU Trucks (cont'd)</b>	<b>ISUZU Trucks (cont'd)</b>	<b>ISUZU Trucks (cont'd)</b>
ELF 200/300 w/4J1-TC (3.0L) Turbo Diesel Eng. Mexico (Cont'd) <b>Radial Seal Air</b> (8970622940)..... <b>RS5434</b>	EXR16DRXT w/6RA1TRC Eng. (1991-95) <b>S. Fuel</b> (1878103670)..... <b>PF7618</b> <b>I. Air</b> (1142150810)..... <b>PA2903</b>	EXZ w/6WA1TC Eng. (1997-on) <b>S. Fuel</b> (1132401940)..... <b>PF9897</b>
ELF250 w/4HF1 (4.3L) Eng. <b>Dual-Flow Lube</b> (8-94338-181-1) <b>BD7159</b> <b>Fuel Spin-on</b> (8-94151-744-0)..... <b>BF7648</b>	EXR16DXT w/6RA1TRC Eng. (1987-90) <b>S. Fuel</b> (1878103670)..... <b>PF7618</b> <b>I. Air</b> (1142150810)..... <b>PA2903</b>	EXZ w/6WG1TCN Eng. (1997-on) <b>S. Fuel</b> (1132401940)..... <b>PF9897</b>
ELF250 w/4HG1 Eng. <b>Dual-Flow Lube</b> (8-97096-777-0) <b>BD7159</b> <b>Fuel</b> (4/95-5/97) (8-94370-621-0). <b>BF954</b> <b>Fuel</b> (5/97-5/99) (8-97172-549-0). <b>BF7648</b> <b>Air</b> (8-94156-052-0)..... <b>PA2712</b>	EXR18 w/6RB1 Eng. (1995-97) <b>S. Fuel</b> (1878103670)..... <b>PF7618</b> <b>O. Std. Air</b> (1142151160)..... <b>PA2676 +</b> <b>O. XP Air</b> (1142151160)..... <b>PA2676XP</b> <b>I. Air</b> (1142151270)..... <b>PA3668</b>	EXZ16JRXT w/6RA1TRC Eng. (1991-96) <b>S. Fuel</b> (1878103670)..... <b>PF7618</b> <b>I. Air</b> (1142150810)..... <b>PA2903</b>
ELF250 w/4HK1 Eng. <b>Dual-Flow Lube</b> (8-97096777-0).. <b>BD7159</b> <b>Fuel/Water Separator</b> (4/99-on) (8-94369-299-3)..... <b>BF7534</b>	EXR18DX w/6RB1 Eng. (1987-90) <b>S. Fuel</b> (1878103670)..... <b>PF7618</b> <b>O. Std. Air</b> (1142151160)..... <b>PA2676 +</b> <b>O. XP Air</b> (1142151160)..... <b>PA2676XP</b> <b>I. Air</b> (1142151270)..... <b>PA3668</b>	EXZ16JXT w/6RA1TRC Eng. (1987-90) <b>S. Fuel</b> (1878103670)..... <b>PF7618</b> <b>I. Air</b> (1142150810)..... <b>PA2903</b>
ELF350 w/4.6L Eng. <b>Dual-Flow Lube</b> (8-97096-777-0) <b>BD7159</b>	EXR181T w/6RA1T Eng. (1984-87) <b>S. Fuel</b> (1878103670)..... <b>PF7618</b> <b>I. Air</b> (1142150810)..... <b>PA2903</b>	EXZ18 w/6RB1TC Eng. (1995-97) <b>S. Fuel</b> (1878103670)..... <b>PF7618</b> <b>I. Air</b> (1142150810)..... <b>PA2903</b>
ELF 400/500/600 w/4HK1-TC (5.2L) Turbo Diesel Eng. Mexico <b>Dual-Flow Lube</b> (8973713340).... <b>BD7159</b> <b>Radial Seal Air</b> (8970622940)..... <b>RS5434</b>	EXR181T w/6RB1 Eng. (1984-on) <b>S. Fuel</b> (1878103670)..... <b>PF7618</b> <b>O. Std. Air</b> (1142151160)..... <b>PA2676 +</b> <b>O. XP Air</b> (1142151160)..... <b>PA2676XP</b> <b>I. Air</b> (1142151270)..... <b>PA3668</b>	EXZ18JRX3T w/6RB1TC Eng. (1991-95) <b>S. Fuel</b> (1878103670)..... <b>PF7618</b> <b>I. Air</b> (1142150810)..... <b>PA2903</b>
EVR w/6BG1TC Eng. <b>F-F Lube</b> (1987-92) (1-13200-487-0)..... <b>B75</b> <b>B-P Lube</b> (1990-92) (1-13240-089-0)..... <b>B7124</b> <b>Fuel</b> (1987-92) (1-13240-079-1)... <b>BF7602</b> <b>O. Air</b> (1987-5/89) (1-14215-152-0)..... <b>PA2577</b> <b>I. Air</b> (1987-10/88) (1-14215-151-0)..... <b>PA2578</b> <b>Single Air</b> (1992) (1-14215-172-0)..... <b>PA2779</b>	EXR18DRX, EXR18DRX3T w/6RB1 Eng. (1991-95) <b>S. Fuel</b> (1878103670)..... <b>PF7618</b> <b>O. Std. Air</b> (1142151160)..... <b>PA2676 +</b> <b>O. XP Air</b> (1142151160)..... <b>PA2676XP</b> <b>I. Air</b> (1142151270)..... <b>PA3668</b>	EXZ18JX3T w/6RB1TC Eng. (1987-90) <b>S. Fuel</b> (1878103670)..... <b>PF7618</b> <b>I. Air</b> (1142150810)..... <b>PA2903</b>
EVR w/6SA1 (8.4L) Eng. (1985) <b>B-P Lube</b> (1-13240-067-0)..... <b>B7577</b>	EXR255 w/6RB1 Eng. (1987-90) <b>S. Fuel</b> (1878103670)..... <b>PF7618</b> <b>O. Std. Air</b> (1142151160)..... <b>PA2676 +</b> <b>O. XP Air</b> (1142151160)..... <b>PA2676XP</b> <b>I. Air</b> (1142151270)..... <b>PA3668</b>	EXZ164T w/6RA1T Eng. (1984-87) <b>S. Fuel</b> (1878103670)..... <b>PF7618</b> <b>I. Air</b> (1142150810)..... <b>PA2903</b>
EVR w/6SA1 (8.4L) Eng. (1987-10/88) <b>F-F Lube</b> (1-13200-487-0)..... <b>B75</b> <b>B-P Lube</b> (1-13240-067-0)..... <b>B7577</b> <b>Fuel</b> (1-13240-079-1)..... <b>BF7602</b> <b>O. Air</b> (1-14215-181-0)..... <b>PA2577</b> <b>I. Air</b> (1-14215-151-0)..... <b>PA2578</b>	EXR300 w/6RA1TRC Eng. (1987-90) <b>S. Fuel</b> (1878103670)..... <b>PF7618</b> <b>I. Air</b> (1142150810)..... <b>PA2903</b>	EXZ164T w/6RA1TRC Eng. <b>S. Fuel</b> (1878103670)..... <b>PF7618</b> <b>I. Air</b> (1142150810)..... <b>PA2903</b>
EVR w/6SA1 (8.4L) Eng. (10/88-91) <b>F-F Lube</b> (1-13200-487-0)..... <b>B75</b> <b>B-P Lube</b> (1-13240-067-0)..... <b>B7577</b> <b>Fuel</b> (1-13240-079-1)..... <b>BF7602</b> <b>Single Air</b> (1-14215-181-0)..... <b>PA2577</b>	EXR300 w/6RA1TRC Eng. (1991-95) <b>S. Fuel</b> (1878103670)..... <b>PF7618</b> <b>I. Air</b> (1142150810)..... <b>PA2903</b>	EXZ300 w/6RA1TRC Eng. (1987-96) <b>S. Fuel</b> (1878103670)..... <b>PF7618</b> <b>I. Air</b> (1142150810)..... <b>PA2903</b>
EVR w/6SA1 (8.4L) Eng. (1992) <b>F-F Lube</b> (1-13200-487-0)..... <b>B75</b> <b>B-P Lube</b> (1-13240-067-0)..... <b>B7577</b> <b>Fuel</b> (1-13240-079-1)..... <b>BF7602</b>	EXZ w/Cummins NTC350 Eng. (1985) <b>F-F Lube</b> (25010495)..... <b>B95 +</b> <b>B-P Lube</b> (25011188)..... <b>B7577</b> <b>Fuel/Water Separator</b> (25011689)..... <b>BF1212 +</b> <b>I. Air</b> (1142150810)..... <b>PA2903</b>	EXZ350 w/6RB1TC Eng. (1987-95) <b>S. Fuel</b> (1878103670)..... <b>PF7618</b> <b>I. Air</b> (1142150810)..... <b>PA2903</b>
EXR w/6WA1TC Eng. (1997-on) <b>S. Fuel</b> (1132401940)..... <b>PF9897</b>	EXZ w/Detroit 6V92 Eng. (1985) <b>F-F Lube</b> (25011106)..... <b>B105 +</b> <b>B-P Lube</b> (25011188)..... <b>B7577</b> <b>P. Fuel</b> (25014274)..... <b>BF5800 +</b> <b>S. Fuel</b> (25014342)..... <b>BF5810</b>	EXZ370 w/6RB1TC Eng. (1995-95) <b>S. Fuel</b> (1878103670)..... <b>PF7618</b> <b>I. Air</b> (1142150810)..... <b>PA2903</b>
		FRR w/6BD1T Eng. <b>F-F Lube</b> (1995-on) (1-13200-487-0)..... <b>B75</b> <b>B-P Lube</b> (1995-96) (1-13240-089-2)..... <b>B7124</b> <b>Fuel</b> (1-13240-079-1)..... <b>BF7602</b> <b>Air</b> (1-14215-181-0)..... <b>PA2577</b> <b>Trans.</b> ..... <b>BT230 +</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

ISUZU Trucks (cont'd)	ISUZU Trucks (cont'd)	ISUZU Trucks (cont'd)
<b>FRR w/6HK1 (7.8L) Eng. (1995-96)</b> <b>Lube</b> (2-90654-820-0)..... <b>B7124</b> <b>Lube</b> (1-13200-487-2)..... <b>B75</b> <b>Fuel/Water Separator</b> (w/Drain) (15618-921)..... <b>BF5813 +</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (15618921)..... <b>BF5813-O +</b> <b>Fuel Spin-on</b> (2-90654-940-0)..... <b>BF7602</b> <b>Single Air</b> (1-14215-181-0)..... <b>PA2577</b> <b>Trans. Pan-Type</b> (AT542) (1-32569-021-0)..... <b>BT230</b>	<b>FRR w/6HK1 (7.8L) Eng. (2005-on)</b> <b>Lube</b> (1-13200-487-2)..... <b>B75</b> <b>Fuel/Water Separator</b> (w/Drain) (15618-921)..... <b>BF5813 +</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (15618921)..... <b>BF5813-O +</b> <b>Fuel Spin-on</b> (2-90654-940-0)..... <b>BF7602</b> <b>O. Air</b> (1-14215-181-0)..... <b>PA2577</b> <b>I. Air</b> (1-14215-151-0)..... <b>PA2578</b> <b>FSR w/6BD1 (5.8L) Eng.</b> <b>F-F Lube</b> (1-13200-487-0)..... <b>B75</b> <b>B-P Lube Spin-on</b> (1-13240-089-0)..... <b>B7124</b> <b>Fuel</b> (1-13240-074-0)..... <b>BF7602</b> <b>O. Air</b> (1-14215-172-0)..... <b>PA2779</b> <b>I. Air</b> (1-14215-111-0)..... <b>PA2545</b> <b>Single Air</b> (1-14215-181-0)..... <b>PA2577</b> <b>FSR w/6BG1 (6.5L) Eng. (1990-94)</b> <b>F-F Lube</b> (1132004870)..... <b>B75</b> <b>B-P Lube</b> (2906548200)..... <b>B7124</b> <b>Fuel</b> (1132400740)..... <b>BF7602</b> <b>O. Air</b> (1142151720)..... <b>PA2779</b> <b>I. Air</b> (1142151110)..... <b>PA2545</b> <b>FSR w/6HE1 (7.1L) Eng. (1995-98)</b> <b>F-F Lube</b> (1132004870)..... <b>B75</b> <b>B-P Lube</b> (1132400892)..... <b>B7124</b> <b>Fuel</b> (1132400740)..... <b>BF7602</b> <b>O. Air</b> (1142151720)..... <b>PA2779</b> <b>I. Air</b> (1142151110)..... <b>PA2545</b> <b>FSR w/6HH1 Eng. (1996-on)</b> <b>Fuel</b> (8943940791)..... <b>BF13</b> <b>Fuel</b> (1132401940)..... <b>PF9897</b> <b>Single Air</b> (25043888)..... <b>PA2504</b> <b>O. Air</b> (25043888)..... <b>PA2504</b> <b>I. Air</b> (25043912)..... <b>PA2545</b> <b>FSR w/6HK1 (7.8L) Eng. (1998-2002)</b> <b>Lube</b> (8943924750)..... <b>B75</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (8156189210)..... <b>BF5813-O +</b> <b>Fuel/Water Separator</b> (w/Drain) (8156189210)..... <b>BF5813</b> <b>Fuel</b> (8943924740)..... <b>BF7602</b> <b>Std. O. Air</b> (1142151810)..... <b>PA2577</b> <b>Std. I. Air</b> (1142151510)..... <b>PA2578</b> <b>Radial Seal O. Air</b> (Don. P533930)..... <b>RS3548</b> <b>Radial Seal XP O. Air</b> (Don. P533930)..... <b>RS3548XP</b> <b>Radial Seal I. Air</b> (Don. P538456)..... <b>RS3722</b> <b>FSR11HV w/6BD1 Eng. (1989-92)</b> <b>F-F Lube</b> (1878100752)..... <b>P723</b> <b>Fuel</b> (9885111911)..... <b>[3] PF311</b> <b>O. Air</b> (1142151640)..... <b>PA3415</b> <b>I. Air</b> (1142151570)..... <b>PA3416</b>	<b>FSR11HX w/6BD1 Eng. (1986-92)</b> <b>Lube</b> (1878100752)..... <b>P723</b> <b>Fuel</b> (9885111911)..... <b>[3] PF311</b> <b>O. Air</b> (25043888)..... <b>PA2504</b> <b>I. Air</b> (25043912)..... <b>PA2545</b> <b>FSR11HXR w/6BG1 Eng. (1986-89)</b> <b>Lube</b> (1878100752)..... <b>P723</b> <b>Fuel</b> (9885111911)..... <b>[3] PF311</b> <b>O. Air</b> (25043888)..... <b>PA2504</b> <b>I. Air</b> (25043912)..... <b>PA2545</b> <b>FSR12HK, FSR12HXR w/6BG1 Eng. (1989-92)</b> <b>Lube</b> (1878100752)..... <b>P723</b> <b>Fuel</b> (9885111911)..... <b>[3] PF311</b> <b>O. Air</b> (25043888)..... <b>PA2504</b> <b>I. Air</b> (25043912)..... <b>PA2545</b> <b>FSR12HV w/6BG1 Eng. (1986-89)</b> <b>Lube</b> (1878100752)..... <b>P723</b> <b>Fuel</b> (9885111911)..... <b>[3] PF311</b> <b>O. Air</b> (25043888)..... <b>PA2504</b> <b>I. Air</b> (1142151570)..... <b>PA3416</b> <b>FSR113N, FSR113X w/6BD1 Eng. (1985-86)</b> <b>Lube</b> (1878100752)..... <b>P723</b> <b>Fuel</b> (9885111911)..... <b>[2] PF311</b> <b>O. Air</b> (25043888)..... <b>PA2504</b> <b>I. Air</b> (25043912)..... <b>PA2545</b> <b>FSR32HRXN16, FSR32HRXN16R w/6HE1N Eng. (1992-96)</b> <b>Fuel Ele.</b> (9885111911)..... <b>[2] PF311</b> <b>Fuel Spin-on</b> (8943940791)..... <b>BF13</b> <b>O. Air</b> (25043888)..... <b>PA2504</b> <b>I. Air</b> (25043912)..... <b>PA2545</b> <b>FSR500 w/6BD1 Eng. (1989-92)</b> <b>Lube</b> (1878100752)..... <b>P723</b> <b>Fuel</b> (9885111911)..... <b>[3] PF311</b> <b>O. Air</b> (25043888)..... <b>PA2504</b> <b>I. Air</b> (25043912)..... <b>PA2545</b> <b>FSR500 w/6HE1N Eng. (1992-96)</b> <b>Fuel Ele.</b> (9885111911)..... <b>[2] PF311</b> <b>Fuel Spin-on</b> (8943940791)..... <b>BF13</b> <b>O. Air</b> (25043888)..... <b>PA2504</b> <b>I. Air</b> (25043912)..... <b>PA2545</b> <b>FSR500C w/6BD1 Eng. (1989-92)</b> <b>F-F Lube</b> (1878100752)..... <b>P723</b> <b>Fuel</b> (9885111911)..... <b>[3] PF311</b> <b>O. Air</b> (1142151640)..... <b>PA3415</b> <b>I. Air</b> (1142151570)..... <b>PA3416</b> <b>FSR600 w/6BG1 Eng. (1989-92)</b> <b>Lube</b> (1878100752)..... <b>P723</b> <b>Fuel</b> (9885111911)..... <b>[3] PF311</b> <b>O. Air</b> (25043888)..... <b>PA2504</b> <b>I. Air</b> (25043912)..... <b>PA2545</b> <b>FSR600 w/6HE1N Eng. (1992-96)</b> <b>Fuel Ele.</b> (9885111911)..... <b>[2] PF311</b> <b>Fuel Spin-on</b> (8943940791)..... <b>BF13</b> <b>O. Air</b> (25043888)..... <b>PA2504</b> <b>I. Air</b> (25043912)..... <b>PA2545</b>

+ See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

ISUZU Trucks (cont'd)	ISUZU Trucks (cont'd)	ISUZU Trucks (cont'd)
FTR w/4HK1 (5.2L) Eng. (2018) Lube (8982984040)..... <b>B40137</b> Fuel/Water Separator (8980374810)..... <b>BF7534</b> Fuel (8981475250)..... <b>PF46059</b> Radial Seal Air (8980714210)..... <b>RS3538</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>	FTR w/6BD1 (5.8L) Eng. F-F Lube (1-13200-487-2)..... <b>B75</b> B-P Lube Spin-on (1-13240-089-0)..... <b>B7124</b> Fuel (8-94392-474-0)..... <b>BF7602</b> O. Air (1-14215-172-0)..... <b>PA2779</b> I. Air (1-14215-111-0)..... <b>PA2545</b> Single Air (1-14215-181-0)..... <b>PA2577</b> FTR w/6BG1 (6.5L) Eng. (1990-94) F-F Lube (1132004870)..... <b>B75</b> B-P Lube (1132400890)..... <b>B7124</b> Fuel (1132400740)..... <b>BF7602</b> 13 1/2 In. O. Air (1142151720)..... <b>PA2779</b> I. Air (1142151110)..... <b>PA2545</b> 15 1/2 In. O. Air (1142151810)..... <b>PA2577</b> I. Air (1142151510)..... <b>PA2578</b> FTR w/6HE1 (7.1L) Eng. (1995-98) F-F Lube (1132004870)..... <b>B75</b> B-P Lube (2906548200)..... <b>B7124</b> Fuel (1132400740)..... <b>BF7602</b> O. Air (1142151810)..... <b>PA2577</b> I. Air (1142151510)..... <b>PA2578</b> FTR w/6HH1 Eng. (1996-on) Fuel (8943940791)..... <b>BF13</b> Fuel (1132401940)..... <b>PF9897</b> Single Air (25043888)..... <b>PA2504</b> O. Air (25043888)..... <b>PA2504</b> I. Air (25043912)..... <b>PA2545</b> FTR w/6HK1 (7.8L) Eng. (1996-97) F-F Lube (1-13200-487-2)..... <b>B75</b> B-P Lube (8-94392-475-0)..... <b>B75</b> Fuel/Water Separator (w/Drain) (Racor S3202)..... <b>BF5813 +</b> Fuel/Water Separator (Open End for Bowl) (Racor S3202)..... <b>BF5813-O +</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> FTR w/6HK1 (7.8L) Eng. (1998-2002) F-F Lube (1-13200-487-2)..... <b>B75</b> B-P Lube (8-94392-475-0)..... <b>B75</b> Fuel/Water Separator (w/Drain) (Racor S3202)..... <b>BF5813 +</b> Fuel/Water Separator (Open End for Bowl) (Racor S3202)..... <b>BF5813-O +</b> Radial Seal O. Air (Don. P533930)..... <b>RS3548</b>	FTR w/6HK1 (7.8L) Eng. (1998-2002) (Cont'd) Radial Seal XP Air (Don. P533930)..... <b>RS3548XP</b> Radial Seal I. Air (Don. P538456)..... <b>RS3722</b> O. Air (1-14215-181-0)..... <b>PA2577</b> I. Air (1-14215-151-0)..... <b>PA2578</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> FTR w/6HK1 (7.8L) Eng. (2003-06) F-F Lube (1-13200-487-2)..... <b>B75</b> B-P Lube (8-94392-475-0)..... <b>B75</b> Fuel/Water Separator (w/Drain) (Racor S3202)..... <b>BF5813 +</b> Fuel/Water Separator (Open End for Bowl) (Racor S3202)..... <b>BF5813-O +</b> Radial Seal O. Air (Don. P533930)..... <b>RS3548</b> Radial Seal XP Air (Don. P533930)..... <b>RS3548XP</b> Radial Seal I. Air (Don. P538456)..... <b>RS3722</b> O. Air (1-14215-181-0)..... <b>PA2577</b> I. Air (1-14215-151-0)..... <b>PA2578</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Steering (88892-858)..... <b>P106-HD</b> FTR w/6HK1 (7.8L) Eng. (2007) F-F Lube (1-13200-487-2)..... <b>B75</b> B-P Lube (8-94392-475-0)..... <b>B75</b> Fuel/Water Separator (w/Drain) (Racor S3202)..... <b>BF5813 +</b> Fuel/Water Separator (Open End for Bowl) (Racor S3202)..... <b>BF5813-O +</b>
FTR w/4HK1 (5.2L) Eng. (2019) Lube (8982984040)..... <b>B40137</b> Fuel/Water Separator (8-98037-481-0)..... <b>BF7534</b> Fuel (8-98147-525-0)..... <b>PF46059</b> Radial Seal Air (8-98071-421-0)..... <b>RS3538</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>	FTR w/4HK1 (5.2L) Eng. (2020) Lube (2906544040)..... <b>B40137</b> Fuel/Water Separator (8980374810)..... <b>BF7534</b> Radial Seal Air (8980714210)..... <b>RS3538</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>	FTR w/4HK1 (5.2L) Eng. (2021) Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

ISUZU Trucks (cont'd)	ISUZU Trucks (cont'd)	ISUZU Trucks (cont'd)
FTR w/6HK1 (7.8L) Eng. (2007) (Cont'd)	FTR w/6HK1 (7.8L) Eng. (2009) (Cont'd)	FTR12KX w/6BG1 Eng. (1986-89)
Radial Seal O. Air (Don. P533930).....	Fuel (8-98037-011-0).....	Lube (1878100752).....
RS3548	Fuel Ele. (8-98037-011-0).....	P723
Radial Seal XP Air (Don. P533930).....	Radial Seal Air (Standard) (97728673).....	Fuel (9885111911).....
RS3548XP	RS3548	[3] PF311
Radial Seal I. Air (Don. P538456).....	Radial Seal XP Air (Upgrade) (97728673).....	O. Air (25043888).....
RS3722	RS3548XP	PA2504
O. Air (1-14215-181-0).....	Air Dryer (89040-662).....	I. Air (25043912).....
PA2577	BA5374 *	PA2545
I. Air (1-14215-151-0).....	Breather (8-97606-318-0).....	FTR12KX w/6BG1TRC Eng. (1989-92)
PA2578	CV15011	F-F Lube (1132004872).....
Breather (8-97606-318-0).....	Trans. Ele. (2 In. Kit) (Allison 29540493).....	B75
CV15011	PT9416-MPG KIT	B-P Lube (1132400892).....
Trans. Ele. (2 In. Kit) (Allison 29540493).....	Trans. Ele. (4 In. Kit) (Allison 29540494).....	B7124
PT9416-MPG KIT	PT9415-MPG KIT	Fuel (9885111911).....
Trans. Ele. (4 In. Kit) (Allison 29540494).....	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965).....	[3] PF311
PT9415-MPG KIT	20004	O. Air (25043888).....
Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965).....	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965).....	PA2504
20004	20016	I. Air (25043912).....
Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965).....	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966).....	PA2545
20016	20003	FTR32KRX16 w/6HE1S Eng. (1992-96)
Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966).....	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966).....	Fuel Ele. (9885111911).....
20003	20017	[2] PF311
Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966).....	Trans. Spin-on (Allison 29539579).....	Fuel Spin-on (8943940791).....
20017	BT8460	BF13
Trans. Spin-on (Allison 29539579).....	Steering (88892-858).....	O. Air (25043888).....
BT8460	P106-HD	PA2504
Steering (88892-858).....	FTR w/6HK1 (7.8L) Eng. (2010-on)	I. Air (25043912).....
P106-HD	F-F Lube (1-13200-487-2).....	PA2545
FTR w/6HK1 (7.8L) Eng. (2008)	B-P Lube (8-94392-475-0).....	FTR115T w/6BD1T Eng. (1985-86)
F-F Lube (1-13200-487-2).....	Fuel/Water Separator (w/Drain) (Racor S3202).....	F-F Lube (1878100752).....
B75	BF5813 +	P723
B-P Lube (8-94392-475-0).....	Fuel/Water Separator (Open End for Bowl) (Racor S3202).....	Fuel (9885111911).....
B75	BF5813-O +	[2] PF311
Fuel/Water Separator (w/Drain) (Racor S3202).....	Fuel (8-98037-011-0).....	O. Air (25043888).....
BF5813 +	PF9919	PA2504
Fuel/Water Separator (Open End for Bowl) (Racor S3202).....	Radial Seal Air (Standard) (97728673).....	I. Air (25043912).....
BF5813-O +	RS3548	PA2545
Fuel (8-98037-011-0).....	Radial Seal XP Air (Upgrade) (97728673).....	FTR124 w/6BG1 Eng. (1985-86)
PF9919	RS3548XP	Lube (1878100752).....
Fuel Ele. (8-98037-011-0).....	Trans. Ele. (2 In. Kit) (Allison 29540493).....	P723
PF9919	PT9416-MPG KIT	Fuel (9885111911).....
Radial Seal Air (2-90646-940-0).....	Trans. Ele. (4 In. Kit) (Allison 29540494).....	[2] PF311
RS3548	PT9415-MPG KIT	O. Air (25043888).....
Air Dryer (89040-662).....	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965).....	PA2504
BA5374 *	20004	I. Air (25043912).....
Breather (8-97606-318-0).....	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965).....	PA2545
CV15011	20016	FTR124 w/6BG1 Eng. (1985-86)
Trans. Ele. (2 In. Kit) (Allison 29540493).....	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966).....	Lube (1878100752).....
PT9416-MPG KIT	20003	P723
Trans. Ele. (4 In. Kit) (Allison 29540494).....	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966).....	Fuel (9885111911).....
PT9415-MPG KIT	20017	[2] PF311
Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965).....	Trans. Spin-on (Allison 29539579).....	O. Air (25043888).....
20004	BT8460	PA2504
Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965).....	FTR w/Cummins B6.7 (6.7L) Eng. (2022)	I. Air (25043912).....
20016	Lube (Fleetguard LF3970).....	PA2545
Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966).....	B7177	FTR700 w/6BG1TRC Eng. (1989-92)
20003	FTR12HV w/6BG1 Eng. (1989-92)	F-F Lube (1132004872).....
Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966).....	F-F Lube (1878100752).....	B75
20017	P723	B-P Lube (1132400892).....
Trans. Spin-on (Allison 29539579).....	Fuel (9885111911).....	B7124
BT8460	[3] PF311	Fuel (9885111911).....
Steering (88892-858).....	O. Air (1142151640).....	[3] PF311
P106-HD	PA3415	O. Air (25043888).....
FTR w/6HK1 (7.8L) Eng. (2009)	I. Air (1142151570).....	PA2504
F-F Lube (1-13200-487-2).....		I. Air (25043912).....
B75		PA2545
B-P Lube (8-94392-475-0).....		FTR700 w/6HE1S Eng. (1992-96)
B75		Fuel Ele. (9885111911).....
Fuel/Water Separator (w/Drain) (Racor S3202).....		[2] PF311
BF5813 +		Fuel Spin-on (8943940791).....
Fuel/Water Separator (Open End for Bowl) (Racor S3202).....		BF13
BF5813-O +		O. Air (25043888).....
		PA2504
		I. Air (25043912).....
		PA2545

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>ISUZU Trucks (cont'd)</b>	<b>ISUZU Trucks (cont'd)</b>	<b>ISUZU Trucks (cont'd)</b>
FTR700T w/6BG1TRC Eng. (1989-92) F-F Lube (1132004872)..... <b>B75</b> B-P Lube (1132400892)..... <b>B7124</b> Fuel (9885111911)..... <b>[3] PF311</b> O. Air (25043888)..... <b>PA2504</b> I. Air (25043912)..... <b>PA2545</b>	FVR w/6BG1 (6.5L) Eng. (10/88-89) F-F Lube (1-13200-487-0)..... <b>B75</b> Fuel (1-13240-074-0)..... <b>BF7602</b> Air (1-14215-152-0)..... <b>PA2577</b>	FVR w/6HK1 (7.8L) Eng. (1998-2002) (Cont'd) Fuel/Water Separator (Open End for Bowl) (15618-921)..... <b>BF5813-O +</b> Fuel (8-94392-474-0)..... <b>BF7602</b> Radial Seal O. Air (Don. P533930)..... <b>RS3548</b> Radial Seal XP Air (Don. P533930)..... <b>RS3548XP</b> Radial Seal I. Air (Don. P538456)..... <b>RS3722</b> O. Air (1-14215-181-0)..... <b>PA2577</b> I. Air (1-14215-151-0)..... <b>PA2578</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>
FTS12HRX w/6BG1 Eng. (1992-96) Fuel (9885111911)..... <b>[3] PF311</b> O. Air (25043888)..... <b>PA2504</b> I. Air (25043912)..... <b>PA2545</b>	FVR w/6BG1 (6.5L) Eng. (1990-94) F-F Lube (1-13200-487-0)..... <b>B75</b> B-P Lube (1-13240-089-0)..... <b>B7124</b> Fuel (1-13240-074-0)..... <b>BF7602</b> Air (1-14215-172-0)..... <b>PA2779</b>	FVR w/6HK1 (7.8L) Eng. (2003-07) F-F Lube (1-13200-487-2)..... <b>B75</b> Fuel/Water Separator (w/Drain) (15618-921)..... <b>BF5813 +</b> Fuel/Water Separator (Open End for Bowl) (15618-921)..... <b>BF5813-O +</b> Fuel (8-94392-474-0)..... <b>BF7602</b> Radial Seal O. Air (Don. P533930)..... <b>RS3548</b> Radial Seal XP Air (Don. P533930)..... <b>RS3548XP</b> Radial Seal I. Air (Don. P538456)..... <b>RS3722</b> O. Air (1-14215-181-0)..... <b>PA2577</b> I. Air (1-14215-151-0)..... <b>PA2578</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Steering (88892-858)..... <b>P106-HD</b>
FTS12HX w/6BG1 Eng. (1987-92) Fuel (9885111911)..... <b>[3] PF311</b> O. Air (25043888)..... <b>PA2504</b> I. Air (25043912)..... <b>PA2545</b>	FVR w/6BG1 (6.5L) Eng. (1995-96) F-F Lube (1-13200-487-0)..... <b>B75</b> B-P Lube (1-13240-089-0)..... <b>B7124</b> Fuel (1-13240-074-0)..... <b>BF7602</b>	
FTS33 w/6HH1 Eng. (1996-on) Fuel (8943940791)..... <b>BF13</b> Fuel (1132401940)..... <b>PF9897</b> Single Air (25043888)..... <b>PA2504</b> O. Air (25043888)..... <b>PA2504</b> I. Air (25043912)..... <b>PA2545</b>	FVR w/6BG1 (6.5L) Eng. (1997-4/98) F-F Lube (1-13200-487-0)..... <b>B75</b> Fuel (1-13240-074-0)..... <b>BF7602</b>	
FTS123 w/6BG1 Eng. (1985-86) Fuel (9885111911)..... <b>[2] PF311</b> O. Air (25043888)..... <b>PA2504</b> I. Air (25043912)..... <b>PA2545</b>	FVR w/6HE1 (7.1L) Eng. (1986-5/89) F-F Lube (1-13200-487-0)..... <b>B75</b> B-P Lube (1-13240-067-0)..... <b>B7577</b> Fuel (1-13240-074-0)..... <b>BF7602</b> O. Air (1-14215-181-0)..... <b>PA2577</b> I. Air (1-14215-151-0)..... <b>PA2578</b>	
FTS600 w/6BG1 Eng. (1989-92) Fuel (9885111911)..... <b>[3] PF311</b> O. Air (25043888)..... <b>PA2504</b> I. Air (25043912)..... <b>PA2545</b>	FVR w/6HE1 (7.1L) Eng. (1995-on) F-F Lube (1-13200-487-0)..... <b>B75</b> B-P Lube (1-13240-067-0)..... <b>B7577</b> Fuel (1-13240-074-0)..... <b>BF7602</b> Air (1-14215-181-0)..... <b>PA2577</b>	
FTS600 w/6BG1 Eng. (1992-96) Fuel (9885111911)..... <b>[3] PF311</b> O. Air (25043888)..... <b>PA2504</b> I. Air (25043912)..... <b>PA2545</b>	FVR w/6HH1 Eng. (1996-on) Fuel (8943940791)..... <b>BF13</b> Fuel (1132401940)..... <b>PF9897</b> Single Air (25043888)..... <b>PA2504</b> O. Air (25043888)..... <b>PA2504</b> I. Air (25043912)..... <b>PA2545</b>	
FVM w/6SD1-TC Eng. (1996-on) F-F Lube (1132401681)..... <b>B75</b> B-P Lube (1132401632)..... <b>B7577</b> Fuel (8943940791)..... <b>BF13</b> Fuel (1132401940)..... <b>PF9897</b> O. Air (1142151810)..... <b>PA2577</b> I. Air (1142151250)..... <b>PA2578</b> Single Air (1142151810)..... <b>PA2577</b>	FVR w/6HK1 (7.8L) Eng. (1996-97) F-F Lube (1-13200-487-2)..... <b>B75</b> Fuel/Water Separator (w/Drain) (15618-921)..... <b>BF5813 +</b> Fuel/Water Separator (Open End for Bowl) (15618-921)..... <b>BF5813-O +</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>	
FVM13SRX17T w/6SA1T Eng. (1992-96) F-F Lube (1878100752)..... <b>P723</b> B-P Lube (25011188)..... <b>B7577</b> Fuel (9885111911)..... <b>[3] PF311</b> O. Air (25096438)..... <b>PA2577</b> I. Air (25096436)..... <b>PA2578</b>	FVR w/6HK1 (7.8L) Eng. (1998-2002) F-F Lube (1-13200-487-2)..... <b>B75</b> Fuel/Water Separator (w/Drain) (15618-921)..... <b>BF5813 +</b>	
FVM1400 w/6SA1T Eng. (1988-96) F-F Lube (1878100752)..... <b>P723</b> B-P Lube (25011188)..... <b>B7577</b> Fuel (9885111911)..... <b>[3] PF311</b> O. Air (25096438)..... <b>PA2577</b> I. Air (25096436)..... <b>PA2578</b>		
FVR w/6BG1 (6.5L) Eng. (1986-10/88) F-F Lube (1-13200-487-0)..... <b>B75</b> Fuel (1-13240-074-0)..... <b>BF7602</b> O. Air (1-14215-152-0)..... <b>PA2577</b> I. Air (1-14215-125-1)..... <b>PA2578</b>		

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



ISUZU Trucks (cont'd)	ISUZU Trucks (cont'd)	ISUZU Trucks (cont'd)
FVR w/6HK1 (7.8L) Eng. (2008)	FVR w/6HK1 (7.8L) Eng. (2010-on) (Cont'd)	FVR13ET, FVR13LT w/6SA1T Eng. (1988-92) (Cont'd)
F-F Lube (1-13200-487-2)..... <b>B75</b>	Fuel (8-98037-011-0)..... <b>PF9919</b>	I. Air (25096436)..... <b>PA2578</b>
Fuel/Water Separator (w/Drain) (15618-921)..... <b>BF5813 +</b>	Radial Seal Air (Standard) (97728673)..... <b>RS3548</b>	FVR13LRX17T w/6SA1T Eng. (1992-96)
Fuel/Water Separator (Open End for Bowl) (15618-921)..... <b>BF5813-O +</b>	Radial Seal XP Air (Upgrade) (97728673)..... <b>RS3548XP</b>	F-F Lube (1878100752)..... <b>P723</b>
Fuel (8-98037-011-0)..... <b>PF9919</b>	Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	B-P Lube (25011188)..... <b>B7577</b>
Radial Seal Air (2-90646-940-0)..... <b>RS3548</b>	Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Fuel (9885111911)..... <b>[3] PF311</b>
Air Dryer (89040-662)..... <b>BA5374 +</b>	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	O. Air (25096438)..... <b>PA2577</b>
Breather (8-97606-318-0)..... <b>CV15011</b>	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	I. Air (25096436)..... <b>PA2578</b>
Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	FVR13LX w/6SA1 Eng. (1986-89)
Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	F-F Lube (1878100752)..... <b>P723</b>
Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>	B-P Lube (25011188)..... <b>B7577</b>
Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	Steering (88892-858)..... <b>P106-HD</b>	Fuel (9885111911)..... <b>[3] PF311</b>
Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	FVR w/6SA1 (8.4L) Eng.	O. Air (1132401940)..... <b>PF9897</b>
Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	F-F Lube (1132401681)..... <b>B75</b>	O. Air (1142151810)..... <b>PA2577</b>
Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>	B-P Lube (1132401632)..... <b>B7577</b>	I. Air (1142151250)..... <b>PA2578</b>
Steering (88892-858)..... <b>P106-HD</b>	Fuel (1132400890)..... <b>B7124</b>	FVR32LXR17 w/6HE1S Eng. (1992-96)
FVR w/6HK1 (7.8L) Eng. (2009)	Fuel (8943924740)..... <b>BF7602</b>	Fuel (9885111911)..... <b>[3] PF311</b>
F-F Lube (1-13200-487-2)..... <b>B75</b>	O. Air (1142151810)..... <b>PA2577</b>	O. Air (25043888)..... <b>PA2504</b>
Fuel/Water Separator (w/Drain) (15618-921)..... <b>BF5813 +</b>	I. Air (1142151510)..... <b>PA2578</b>	I. Air (25043912)..... <b>PA2545</b>
Fuel/Water Separator (Open End for Bowl) (15618-921)..... <b>BF5813-O +</b>	FVR w/6SD1-TC Eng. (1996-on)	FVR123 w/6BG1 Eng. (1985-86)
Fuel (8-98037-011-0)..... <b>PF9919</b>	F-F Lube (1132401681)..... <b>B75</b>	Lube (1878100752)..... <b>P723</b>
Radial Seal Air (Standard) (97728673)..... <b>RS3548</b>	B-P Lube (1132400892)..... <b>B7124</b>	Fuel (9885111911)..... <b>[2] PF311</b>
Radial Seal XP Air (Upgrade) (97728673)..... <b>RS3548XP</b>	Fuel (8943940791)..... <b>BF13</b>	O. Air (25043888)..... <b>PA2504</b>
Air Dryer (89040-662)..... <b>BA5374 +</b>	Fuel (1132401940)..... <b>PF9897</b>	I. Air (25043912)..... <b>PA2545</b>
Breather (8-97606-318-0)..... <b>CV15011</b>	O. Air (1142151810)..... <b>PA2577</b>	FVR800, FVR800L w/6BG1TRC Eng. (1989-92)
Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	I. Air (1142151250)..... <b>PA2578</b>	F-F Lube (1132401681)..... <b>B75</b>
Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Single Air (1142151810)..... <b>PA2577</b>	B-P Lube (1132400892)..... <b>B7124</b>
Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	FVR12HX w/6BG1 Eng. (1986-89)	Fuel (9885111911)..... <b>[3] PF311</b>
Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	Lube (1878100752)..... <b>P723</b>	O. Air (25043888)..... <b>PA2504</b>
Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	Fuel (9885111911)..... <b>[3] PF311</b>	I. Air (25043912)..... <b>PA2545</b>
Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	O. Air (25043888)..... <b>PA2504</b>	FVR900, FVR900L w/6SA1T Eng. (1988-92)
Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>	I. Air (25043912)..... <b>PA2545</b>	F-F Lube (1878100752)..... <b>P723</b>
Steering (88892-858)..... <b>P106-HD</b>	FVR12KXT w/6BG1TRC Eng. (1989-92)	B-P Lube (25011188)..... <b>B7577</b>
FVR w/6HK1 (7.8L) Eng. (2010-on)	F-F Lube (1132401681)..... <b>B75</b>	Fuel (9885111911)..... <b>[3] PF311</b>
F-F Lube (1-13200-487-2)..... <b>B75</b>	B-P Lube (1132400892)..... <b>B7124</b>	O. Air (25043888)..... <b>PA2577</b>
Fuel/Water Separator (w/Drain) (15618-921)..... <b>BF5813 +</b>	Fuel (9885111911)..... <b>[3] PF311</b>	I. Air (25096436)..... <b>PA2578</b>
Fuel/Water Separator (Open End for Bowl) (15618-921)..... <b>BF5813-O +</b>	O. Air (25043912)..... <b>PA2545</b>	FVR900L w/6SA1T Eng. (1992-96)
	FVR12LX w/6BG1TRC Eng. (1989-92)	F-F Lube (1878100752)..... <b>P723</b>
	F-F Lube (1132004872)..... <b>B75</b>	B-P Lube (25011188)..... <b>B7577</b>
	B-P Lube (1132400892)..... <b>B7124</b>	Fuel (9885111911)..... <b>[3] PF311</b>
	Fuel (9885111911)..... <b>[3] PF311</b>	O. Air (25096438)..... <b>PA2577</b>
	O. Air (25043888)..... <b>PA2504</b>	I. Air (25096436)..... <b>PA2578</b>
	I. Air (25043912)..... <b>PA2545</b>	FVZ13LT w/6SA1T Eng. (1988-92)
	FVR13ET, FVR13LT w/6SA1T Eng. (1988-92)	F-F Lube (1878100752)..... <b>P723</b>
	F-F Lube (1878100752)..... <b>P723</b>	B-P Lube (25011188)..... <b>B7577</b>
	B-P Lube (25011188)..... <b>B7577</b>	Fuel (9885111911)..... <b>[3] PF311</b>
	Fuel (9885111911)..... <b>[3] PF311</b>	O. Air (25096438)..... <b>PA2577</b>
	O. Air (25096438)..... <b>PA2577</b>	I. Air (25096436)..... <b>PA2578</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>ISUZU Trucks (cont'd)</b>	<b>ISUZU Trucks (cont'd)</b>	<b>ISUZU Trucks (cont'd)</b>
FVZ13SRX17T w/6SA1T Eng. (1992-96)	FXR w/6HK1 (7.8L) Eng. (2003-07) (Cont'd)	FXR w/6HK1 (7.8L) Eng. (2009) (Cont'd)
F-F Lube (1878100752)..... <b>P723</b>	Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
B-P Lube (25011188)..... <b>B7577</b>	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
Fuel (9885111911)..... <b>[3] PF311</b>	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
O. Air (25096438)..... <b>PA2577</b>	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
I. Air (25096436)..... <b>PA2578</b>	Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>	Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>
FVZ23 w/6SD1-TC Eng. (1996-on)	Steering (88892-858)..... <b>P106-HD</b>	Steering (88892-858)..... <b>P106-HD</b>
F-F Lube (1132401681)..... <b>B75</b>	FXR w/6HK1 (7.8L) Eng. (2008)	FXR w/6HK1 (7.8L) Eng. (2010-on)
B-P Lube (1132401632)..... <b>B7577</b>	F-F Lube (1-13200-487-2)..... <b>B75</b>	F-F Lube (1-13200-487-2)..... <b>B75</b>
Fuel (8943940791)..... <b>BF13</b>	Fuel/Water Separator (w/Drain) (Racor S3202)..... <b>BF5813 +</b>	B-P Lube (8943924750)..... <b>B75</b>
Fuel (1132401940)..... <b>PF9897</b>	Fuel/Water Separator (Open End for Bowl) (Racor S3202)..... <b>BF5813-O +</b>	Fuel/Water Separator (w/Drain) (Racor S3202)..... <b>BF5813 +</b>
O. Air (1142151810)..... <b>PA2577</b>	Fuel Ele. (8-98037-011-0)..... <b>PF9919</b>	Fuel/Water Separator (Open End for Bowl) (Racor S3202)..... <b>BF5813-O +</b>
I. Air (1142151250)..... <b>PA2578</b>	Radial Seal Air (2-90646-940-0)..... <b>RS3548</b>	Fuel (8-98037-011-0)..... <b>PF9919</b>
Single Air (1142151810)..... <b>PA2577</b>	Radial Seal XP Air (2-90646-940-0)..... <b>RS3548XP</b>	Radial Seal Air (Standard) (97728673)..... <b>RS3548</b>
FVZ1400 w/6SA1T Eng. (1988-96)	Air Dryer (Bendix 5008414)..... <b>BA5374 +</b>	Radial Seal XP Air (Upgrade) (97728673)..... <b>RS3548XP</b>
F-F Lube (1878100752)..... <b>P723</b>	Breather (8-97606-318-0)..... <b>CV15011</b>	Air Dryer (Bendix 5008414)..... <b>BA5374 +</b>
B-P Lube (25011188)..... <b>B7577</b>	Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
Fuel (9885111911)..... <b>[3] PF311</b>	Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
O. Air (25096438)..... <b>PA2577</b>	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
I. Air (25096436)..... <b>PA2578</b>	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
FXR w/6HK1 (7.8L) Eng. (1998-2002)	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
F-F Lube (1-13200-487-2)..... <b>B75</b>	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>
Fuel/Water Separator (w/Drain) (Racor S3202)..... <b>BF5813 +</b>	Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>	Steering (88892-858)..... <b>P106-HD</b>
Fuel/Water Separator (Open End for Bowl) (Racor S3202)..... <b>BF5813-O +</b>	Steering (88892-858)..... <b>P106-HD</b>	FXZ23 w/6SD1-TC Eng. (1999-on)
Fuel (8-94392-474-0)..... <b>BF7602</b>	FXR w/6HK1 (7.8L) Eng. (2009)	F-F Lube (1878100752)..... <b>P723</b>
O. Air (1-14215-181-0)..... <b>PA2577</b>	F-F Lube (1-13200-487-2)..... <b>B75</b>	B-P Lube (1132401632)..... <b>B7577</b>
I. Air (1-14215-151-0)..... <b>PA2578</b>	B-P Lube (8943924750)..... <b>B75</b>	Fuel (1132401940)..... <b>PF9897</b>
Air Dryer (Bendix 5008414)..... <b>BA5374 +</b>	Fuel/Water Separator (w/Drain) (Racor S3202)..... <b>BF5813 +</b>	O. Air (1142151810)..... <b>PA2577</b>
Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	Fuel/Water Separator (Open End for Bowl) (Racor S3202)..... <b>BF5813-O +</b>	I. Air (1142151250)..... <b>PA2578</b>
Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Fuel (8-98037-011-0)..... <b>PF9919</b>	FXZ270 w/6SD1-TC Eng. (1999-on)
Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	Radial Seal Air (Standard) (97728673)..... <b>RS3548</b>	F-F Lube (1878100752)..... <b>P723</b>
Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	Radial Seal XP Air (Upgrade) (97728673)..... <b>RS3548XP</b>	B-P Lube (1132401632)..... <b>B7577</b>
Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	Air Dryer (Bendix 5008414)..... <b>BA5374 +</b>	Fuel (1132401940)..... <b>PF9897</b>
Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	Breather (8-97606-318-0)..... <b>CV15011</b>	O. Air (1142151810)..... <b>PA2577</b>
Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>	Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	I. Air (1142151250)..... <b>PA2578</b>
Steering (88892-858)..... <b>P106-HD</b>	Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	HTR w/6HK1 (7.8L) Eng. Lube (1-13200-487-2)..... <b>B75</b>
FXR w/6HK1 (7.8L) Eng. (2003-07)		Fuel/Water Separator (w/Drain) (15618921)..... <b>BF5813 +</b>
F-F Lube (1-13200-487-2)..... <b>B75</b>		Fuel/Water Separator (Open End for Bowl) (15618921)..... <b>BF5813-O +</b>
Fuel/Water Separator (w/Drain) (Racor S3202)..... <b>BF5813 +</b>		Fuel (8-94392-474-0)..... <b>BF7602</b>
Fuel/Water Separator (Open End for Bowl) (Racor S3202)..... <b>BF5813-O +</b>		
Fuel (8-94392-474-0)..... <b>BF7602</b>		
Fuel Ele. (8-98037-011-0)..... <b>PF9919</b>		
O. Air (1-14215-181-0)..... <b>PA2577</b>		
I. Air (1-14215-151-0)..... <b>PA2578</b>		
Air Dryer (Bendix 5008414)..... <b>BA5374 +</b>		
Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>		

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

ISUZU Trucks (cont'd)	ISUZU Trucks (cont'd)	ISUZU Trucks (cont'd)
HTR w/6HK1 (7.8L) Eng. (Cont'd)	JCR w/6BD1 Eng. (1980-85)	K-SKS390 w/8PA1 Eng.
Fuel (8-98037-011-0)..... PF9919	Lube (1878100752)..... P723	Air (9-14215-193-1)..... PA1646-FN
Radial Seal Air (ACDelco A2031C)..... RS4672	Fuel (9885111911)..... PF311	KT25 w/4BC1 Eng. (1980-84) (New Zealand)
Radial Seal O. Air (19179832)..... RS5767	Air (6424690)..... PA1681-FN	Lube (9885111942)..... P7050
Radial Seal I. Air (88937548)..... RS4673	JCR Turbo w/6BD1T Eng. (1982-85)	Fuel (8943940791)..... BF13
Trans. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	F-F Lube (1878100752)..... P723	KT25 w/4BC1 Eng. (North America)
Trans. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Fuel (9885111911)..... PF311	Lube Ele. (9-88511-194-2)..... P7050
Steering (88892-858)..... P106-HD	O. Air (25043888)..... PA2504	Fuel Spin-on (8-94143-479-0)..... BF7648
HVR w/6HK1 (7.8L) Eng.	I. Air (25043912)..... PA2545	KT26 w/4BC2 Eng. (1982-84) (New Zealand)
Lube (1-13200-487-2)..... B75	JCS420 w/6BD1 Eng. (1983-85)	Lube (9885111942)..... P7050
Fuel/Water Separator (w/Drain (15618921)..... BF5813 +	Fuel (9885111911)..... PF311	Fuel (8943940791)..... BF13
Fuel/Water Separator (Open End for Bowl) (15618921)..... BF5813-O +	Air (6424690)..... PA1681-FN	KT26 w/4BC2 Eng. (North America)
Fuel (8-94392-474-0)..... BF7602	JCR420W w/6BD1 Eng. (1982-85)	Lube Ele. (9-88511-194-2)..... P7050
Fuel (8-98037-011-0)..... PF9919	Lube (1878100752)..... P723	Fuel Spin-on (8-94143-479-0)..... BF7648
Radial Seal Air (ACDelco A2031C)..... RS4672	Fuel (9885111911)..... PF311	K-TXD23.60 w/DA640 Eng.
Radial Seal O. Air (19179832)..... RS5767	Air (6424690)..... PA1681-FN	Lube Ele. (9-88513-264-1)..... P7084
Radial Seal I. Air (88937548)..... RS4673	JCR500S w/6BD1T Eng. (1982-85)	Fuel Ele. (9-88511-191-1)..... PF311
Opt. Air Dryer (89040-662)..... BA5374 +	F-F Lube (1878100752)..... P723	LT w/6BD1 Naturally Aspirated (5.8L) Eng.
Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	Fuel (9885111911)..... PF311	F-F Lube (9878100750)..... P723
Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	O. Air (25043888)..... PA2504	Fuel Ele. (9885131160)..... PF311
Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004	I. Air (25043912)..... PA2545	Fuel Spin-on (5876100110)..... BF954 +
Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016	KAG51 OHV w/G161AB Eng. (1982-84)	LT w/6BD1 Turbo (5.8L) Eng.
Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003	Lube (8944637151)..... B131	F-F Lube (1-13200-487-0)..... B75
Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017	Fuel (5132000661)..... BF840 +	B-P Lube (1-13240-089-0)..... B7124
Trans. Spin-on (Allison 29539579)..... BT8460	KC-NKR66 w/4HF1, 4HF1T Engs.	Fuel Spin-on (1-13240-074-0)..... BF7602
Steering (88892-858)..... P106-HD	Dual-Flow Lube (w/Inter-Cooler) (8-97148-270-0)..... BD7169	MR w/6BD1 (5.8L) Eng.
HXR w/6HK1-TC Eng.	Dual-Flow Lube (w/o Inter-Cooler) (8-94338-181-1)..... BD7159	F-F Lube (1132401681)..... B75
Lube (1-13200-487-2)..... B75	Fuel Spin-on (8-94151-744-0)..... BF7648	B-P Lube (1132400890)..... B7124
Fuel/Water Separator (w/Drain (15618921)..... BF5813 +	Fuel (8-94370-621-0)..... BF954	Fuel (8943924740)..... BF7602
Fuel/Water Separator (Open End for Bowl) (15618921)..... BF5813-O +	KC-NPR71 w/4HG1 Eng.	O. Air (1142151720)..... PA2779
Fuel (8-94392-474-0)..... BF7602	Dual-Flow Lube (w/Inter-Cooler) (8-97148-270-0)..... BD7169	I. Air (1142151110)..... PA2545
Fuel (8-98037-011-0)..... PF9919	Dual-Flow Lube (w/o Inter-Cooler) (8-94338-181-1)..... BD7159	NHR55 w/4JB1 Eng. (1994-on)
Radial Seal Air (ACDelco A2031C)..... RS4672	Fuel Spin-on (8-94151-744-0)..... BF7648	Dual-Flow Lube (8941432050)..... BD142
Radial Seal O. Air (19179832)..... RS5767	KC-NPR72 w/4HJ1 Eng.	Air (Single Cab) (8941560520)..... PA2712
Radial Seal I. Air (88937548)..... RS4673	Dual-Flow Lube (w/Inter-Cooler) (8-97148-270-0)..... BD7169	Air (Crew Cab) (8971732100)..... PA2904
Air Dryer (89040-662)..... BA5374 +	Dual-Flow Lube (w/o Inter-Cooler) (8-94338-181-1)..... BD7159	NHR55E w/4JB1 Eng. (1992-94)
Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	Fuel (8-97172-549-0)..... BF7648	Dual-Flow Lube (8941432050)..... BD142
Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	KS21 w/4BB1 Eng. (1974-81)	Air (8941560520)..... PA2712
Steering (88892-858)..... P106-HD	Lube (9885111942)..... P7050	Air (Crew Cab) (8971732100)..... PA2904
	Fuel (5878100500)..... PF313	NHR125 w/4JB1 Eng. (1992-94)
	KS22 w/4BC2 Eng. (1985)	Dual-Flow Lube (8941432050)..... BD142
	Lube Ele. (5-87810-293-0)..... P7050	Air (8941560520)..... PA2712
	Fuel Ele. (5-87810-050-0)..... PF313	Air (Crew Cab) (8971732100)..... PA2904
	KS32 w/4BD1 Eng. (1982-84) (New Zealand)	NKR55 w/4NJ1 Eng. (1994-on)
	Lube (9885111942)..... P7050	Dual-Flow Lube (8941432050)..... BD142
	Fuel (5878100500)..... PF313	Air (Single Cab) (8941560520)..... PA2712
	KS32 w/4BC2, 4BD1 Engs. (North America)	Air (Crew Cab) (8971732100)..... PA2904
	Lube Ele. (9-88511-194-2)..... P7050	NKR55E w/4JB1 Eng. (1987-94)
	Fuel Ele. (5-87810-050-0)..... PF313	Dual-Flow Lube (8941432050)..... BD142
	Fuel Spin-on (8-94143-479-0)..... BF7648	Air (8941560520)..... PA2712

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

**Trucks & Buses Applications** **BALDWIN FILTERS**

<b>ISUZU Trucks (cont'd)</b>	<b>ISUZU Trucks (cont'd)</b>	<b>ISUZU Trucks (cont'd)</b>
NKR55W w/4JB1 Eng. (1986-94) Dual-Flow Lube (8941432050).... <b>BD142</b> Air (8971732100)..... <b>PA2904</b>	NKR575W w/4BC2 Eng. (1985-86) Lube (9885111942)..... <b>P7050</b> Air (8971732100)..... <b>PA2904</b>	NPR w/GM V8-364 (6.0L) Eng. (2003-07) (Cont'd) Fuel (94392474)..... <b>BF7602</b> Air (8-94430-250-0)..... <b>PA2761</b> Trans. (8-08684-221-0)..... <b>18007</b> Trans. Pan-Type (24208847)..... <b>18027</b> Steering..... <b>CLN&amp;R</b>
NKR57 w/4BC2 Eng. (1987-94) B-P Lube (8943402591)..... <b>B201-S</b> Air (8941560520)..... <b>PA2712</b>	NKS58GR w/4BE1 Eng. (1988-94) B-P Lube (8943402591)..... <b>B201-S</b> Fuel/Water Separator (8943692993)..... <b>BF7534</b> Air (8971732100)..... <b>PA2904</b>	NPR w/GM V8-364 (6.0L) Eng. (2008-10) Lube (89017-524)..... <b>B160</b> Fuel/Water Separator (w/Drain) (25165075)..... <b>BF5813 +</b> Fuel/Water Separator (Open End for Bowl) (25165075)..... <b>BF5813-O +</b> Fuel (In Tank) (N/S)..... <b>N/S</b> Fuel (94392474)..... <b>BF7602</b> Radial Seal Air (8-97062-294-0).. <b>RS5434</b> Trans. Pan-Type (24208847)..... <b>18027</b> Trans. Spin-on (8-97182-282-0).. <b>B114</b> Steering..... <b>CLN&amp;R</b>
NKR57E, NKR57L, NPR57L w/4BC2 Eng. Lube Ele. (9-88511-194-2)..... <b>P7050</b> Fuel Spin-on (8-94143-479-0).... <b>BF7648</b>	NKS66 w/4HF1 Eng. (1994-95) Air (8941560520)..... <b>PA2712</b>	NPR w/GM V8-364 (6.0L) Eng. (2011-15) Lube (89017-524)..... <b>B160</b> Fuel/Water Separator (w/Drain) (25165075)..... <b>BF5813 +</b> Fuel/Water Separator (Open End for Bowl) (25165075)..... <b>BF5813-O +</b> Fuel (In Tank) (N/S)..... <b>N/S</b> Fuel (94392474)..... <b>BF7602</b> Radial Seal Air (8-97062-294-0).. <b>RS5434</b> Trans. Spin-on (8-97182-282-0).. <b>B114</b> Trans. Pan-Type (24236933)..... <b>20022</b> Steering..... <b>CLN&amp;R</b>
NKR57LW w/4BC2 Eng. (1986-90) B-P Lube (8943402591)..... <b>B201-S</b> Air (8971732100)..... <b>PA2904</b>	NKS71 w/4HG1 Eng. (1995-on) Air (8941560520)..... <b>PA2712</b>	NPR w/GM V8-364 (6.0L) Eng. (2016-17) Fuel (N/S)..... <b>N/S</b> Radial Seal Air (8981772710)..... <b>RS5434</b>
NKR58 w/4BE1 Eng. (1990-94) B-P Lube (8943402591)..... <b>B201-S</b> Air (8941560520)..... <b>PA2712</b>	NKS200 w/4HG1 Eng. (1995-on) Air (8941560520)..... <b>PA2712</b>	NPR w/GM V8-364 (6.0L) Eng. (2018) Lube (8193039750)..... <b>B160</b> Fuel (N/S)..... <b>N/S</b> Radial Seal Air (8981772710)..... <b>RS5434</b>
NKR58 w/4BE1 Eng. (1994-on) B-P Lube (8943402591)..... <b>B201-S</b> Air (Single Cab) (8941560520).... <b>PA2712</b> Air (Crew Cab) (8971732100).... <b>PA2904</b>	NPR w/GM V8-350 (5.7L) Eng. (1992-1995) Lube (w/o Anti-Drainback Valve) (8064383840)..... <b>B6 +</b> Lube (w/Anti-Drainback Valve) (8251605610)..... <b>B1428 +</b> Fuel (8250551290)..... <b>BF853</b> Air (8064842350)..... <b>PA2008</b> Trans. (4L80-E) (8086842210).... <b>18007</b>	NPR w/GM V8-364 (6.0L) Eng. (2019) Lube (8193039750)..... <b>B160</b> Fuel (N/S)..... <b>N/S</b> Radial Seal Air (8-98177-271-0).. <b>RS5434</b>
NKR66 w/4HF1 Eng. (1997-on) Air (8941560520)..... <b>PA2712</b>	NPR w/GM V8-350 (5.7L) Eng. (1996-2002) Lube (w/o Anti-Drainback Valve) (8064383840)..... <b>B6 +</b> Lube (w/Anti-Drainback Valve) (8251605610)..... <b>B1428 +</b> Fuel (8250551290)..... <b>BF853</b> Air (8944302500)..... <b>PA2761</b> Trans. (4L80-E) (8086842210).... <b>18007</b>	NPR w/4BD1 (3.9L) Eng. (1986-1991) F-F Lube (8-94463-715-0)..... <b>B131</b> B-P Lube (8-94360-419-1)..... <b>B494</b> Fuel (5-87310-335-0)..... <b>[2] BF7648</b> Air (Cab Chassis) (8-94430-250-0)..... <b>PA2761</b> Air (Strip Chassis) (8-94156-052-0)..... <b>PA2712</b>
NKR150 w/4JB1 Eng. (1987-94) Dual-Flow Lube (8941432050).... <b>BD142</b> Air (8941560520)..... <b>PA2712</b>	NPR w/GM V8-364 (6.0L) Eng. (1993-95) Lube (8-06438-384-0)..... <b>B6 +</b> Fuel/Water Separator (w/Drain) (25165075)..... <b>BF5813 +</b> Fuel/Water Separator (Open End for Bowl) (25165075)..... <b>BF5813-O +</b> Fuel (8-25055-052-0)..... <b>BF853</b> Air (8-06484-235-0)..... <b>PA2008</b> Trans. Pan-Type (24208847)..... <b>18027</b> Steering..... <b>CLN&amp;R</b>	NPR w/4BD1 (3.9L) Eng. (1992-1998) Fuel (5-87310-335-0)..... <b>[2] BF7648</b> Air (Cab Chassis) (8-94430-250-0)..... <b>PA2761</b> Air (Strip Chassis) (8-94156-052-0)..... <b>PA2712</b>
NKR150C w/4JB1 Eng. (1986-94) Dual-Flow Lube (8941432050).... <b>BD142</b> Air (8971732100)..... <b>PA2904</b>	NPR w/GM V8-364 (6.0L) Eng. (1996-2002) Lube (8-25160-561-0)..... <b>B1428 +</b> Fuel/Water Separator (w/Drain) (25165075)..... <b>BF5813 +</b> Fuel/Water Separator (Open End for Bowl) (25165075)..... <b>BF5813-O +</b> Fuel (8-25055-052-0)..... <b>BF853</b> Air (8-94430-250-0)..... <b>PA2761</b> Trans. Pan-Type (24208847)..... <b>18027</b> Steering..... <b>CLN&amp;R</b>	
NKR200 w/4JB1 Eng. (1994-on) Dual-Flow Lube (8941432050).... <b>BD142</b> Air (Single Cab) (8941560520).... <b>PA2712</b> Air (Crew Cab) (8971732100).... <b>PA2904</b>	NKR w/GM V8-364 (6.0L) Eng. (2003-07) Lube (8-88984-215-0)..... <b>B31</b> Fuel/Water Separator (w/Drain) (25165075)..... <b>BF5813 +</b> Fuel/Water Separator (Open End for Bowl) (25165075)..... <b>BF5813-O +</b> Fuel (In Tank) (N/S)..... <b>N/S</b>	
NKR200C, NKR200S w/4BE1 Eng. (1994-on) B-P Lube (8943402591)..... <b>B201-S</b> Air (Single Cab) (8941560520).... <b>PA2712</b> Air (Crew Cab) (8971732100).... <b>PA2904</b>		
NKR250 w/4BC2 Eng. (1987-94) B-P Lube (8943402591)..... <b>B201-S</b> Air (8941560520)..... <b>PA2712</b>		
NKR250C, NKR250S w/4BE1 Eng. (1994-on) B-P Lube (8943402591)..... <b>B201-S</b> Air (Single Cab) (8941560520).... <b>PA2712</b> Air (Crew Cab) (8971732100).... <b>PA2904</b>		
NKR250 w/4BC2 Eng. (Crew Cab) (1986-90) B-P Lube (8943402591)..... <b>B201-S</b> Air (8971732100)..... <b>PA2904</b>		
NKR250S w/4BE1 Eng. (1990-94) B-P Lube (8943402591)..... <b>B201-S</b> Air (8941560520)..... <b>PA2712</b>		
NKR275C w/4HF1 Eng. (1997-on) Air (8941560520)..... <b>PA2712</b>		
NKR552 w/4JB1 Eng. (1985-87) Lube (9885132653)..... <b>PT466</b> Air (8941560520)..... <b>PA2712</b>		
NKR575 w/4BC2 Eng. (1985-87) Lube (9885111942)..... <b>P7050</b> Air (8941560520)..... <b>PA2712</b>		

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).


ISUZU Trucks (cont'd)	ISUZU Trucks (cont'd)	ISUZU Trucks (cont'd)
NPR w/4BD2 (3.9L) Eng. <b>Dual-Flow Lube</b> (8-97148-280-0)..... <b>BD7166</b> <b>Fuel</b> (5-87310-335-0)..... <b>BF7648</b> <b>Air</b> (Cab Chassis) (8-94430-250-0)..... <b>PA2761</b> <b>Air</b> (Strip Chassis) (8-94156-052-0)..... <b>PA2712</b>	NPR w/4HK1 (5.2L) Eng. (2011-12) (Cont'd) <b>Diesel Exhaust Fluid</b> (8-98169-403-0)..... <b>PE17000</b>	NPR w/4JJ1 (3.0L) Eng. (2011-16) (Cont'd) <b>Trans. Spin-on</b> (8-97182-282-0).. <b>B114</b> <b>Diesel Exhaust Fluid</b> (8-98169-403-0)..... <b>PE17000</b>
NPR w/4HE1 (4.8L) Eng. <b>Dual-Flow Lube</b> (2-90654-800-0) <b>BD7169</b> <b>Lube</b> (2946541000)..... <b>B40138</b> <b>Fuel</b> (290654-9400)..... <b>BF7602</b> <b>10 1/2 In. Air</b> (8-94156-052-0)..... <b>PA2712</b> <b>13 1/2 In. Air</b> (8-94430-250-0)..... <b>PA2761</b> <b>Trans. (w/Inter-Cooler)</b> (8-97182-282-0)..... <b>B114</b>	NPR w/4HK1 (5.2L) Eng. (2013) <b>Lube</b> (8982984040)..... <b>B40137</b> <b>Fuel Ele.</b> (8-98165-375-0)..... <b>PF40052</b> <b>Fuel</b> (8-98147-525-0)..... <b>PF46059</b> <b>Some Air</b> (8-94430-250-0)..... <b>PA2761</b> <b>Air</b> (8-98177-271-0)..... <b>RS5434</b> <b>Cab Air</b> ..... <b>CLN&amp;R</b> <b>Trans.</b> (97182282)..... <b>B114</b> <b>Diesel Exhaust Fluid</b> (8-98169-403-0)..... <b>PE17000</b>	NPR w/4JJ1 (3.0L) Eng. (2017) <b>Lube</b> (2945611030)..... <b>P40021</b> <b>Fuel/Water Separator</b> (2945611060)..... <b>BF7534</b> <b>Fuel</b> (8981475250)..... <b>PF46059</b> <b>Air</b> (5876100200)..... <b>RS5434</b> <b>Diesel Exhaust Fluid</b> (8981694030)..... <b>PE17000</b>
NPR w/4HK1 (5.2L) Eng. (2004-05) <b>Dual-Flow Lube</b> (97148270)..... <b>BD7169</b> <b>Fuel/Water Separator</b> (8-98037-480-0)..... <b>BF7534</b> <b>Radial Seal Air</b> (8-97062-294-0)..... <b>RS5434</b> <b>Axial Seal Air</b> (2906469100)..... <b>PA2761</b> <b>Trans. Spin-on</b> (97182282)..... <b>B114</b>	NPR w/4HK1 (5.2L) Eng. (2014-16) <b>Lube</b> (8982984040)..... <b>B40137</b> <b>Fuel</b> (8-98147-525-0)..... <b>PF46059</b> <b>Fuel</b> (8981653750)..... <b>PF40052</b> <b>Radial Seal Air</b> (8981772710)..... <b>RS5434</b> <b>Some Air</b> (8-94430-250-0)..... <b>PA2761</b> <b>Trans.</b> (97182282)..... <b>B114</b> <b>Diesel Exhaust Fluid</b> (8-98169-403-0)..... <b>PE17000</b>	NPR w/4JJ1 (3.0L) Eng. (2018) <b>Lube</b> (2945611030)..... <b>P40021</b> <b>Fuel/Water Separator</b> (8980374810)..... <b>BF7534</b> <b>Radial Seal Air</b> (2945611130)..... <b>RS5434</b> <b>Steering</b> (8970947320)..... <b>CLN&amp;R</b> <b>Diesel Exhaust Fluid</b> (8981694030)..... <b>PE17000</b>
NPR w/4HK1 (5.2L) Eng. (2006-07) <b>Dual-Flow Lube</b> (97148270)..... <b>BD7169</b> <b>Fuel/Water Separator</b> (8-98037-480-0)..... <b>BF7534</b> <b>Radial Seal Air</b> (8-97062-294-0)..... <b>RS5434</b> <b>Axial Seal Air</b> (2906469100)..... <b>PA2761</b> <b>Trans. Spin-on</b> (97182282)..... <b>B114</b>	NPR w/4HK1 (5.2L) Eng. (2017) <b>Lube</b> (8982984040)..... <b>B40137</b> <b>Fuel/Water Separator</b> (8980374810)..... <b>BF7534</b> <b>Fuel</b> (8981475250)..... <b>PF46059</b> <b>Fuel</b> (8981653750)..... <b>PF40052</b> <b>Radial Seal Air</b> (8981772710)..... <b>RS5434</b> <b>Steering</b> (8970947320)..... <b>CLN&amp;R</b>	NPR Eco Max w/4JJ1-TC Eng. <b>Lube</b> (8980188580)..... <b>P40021</b> <b>Fuel/Water Separator</b> (8-98037-481-0)..... <b>BF7534</b> <b>Fuel</b> (8-98162-897-0)..... <b>PF9919</b> <b>Radial Seal Air</b> (8-97062-294-0)..... <b>RS5434</b> <b>Trans. Spin-on</b> (8-97182-282-0)..... <b>B114</b> <b>Diesel Exhaust Fluid</b> (8-98169-403-0)..... <b>PE17000</b>
NPR w/4HK1 (5.2L) Eng. (2008-09) <b>Dual-Flow Lube</b> (97148270)..... <b>BD7169</b> <b>Fuel/Water Separator</b> (8-98037-480-0)..... <b>BF7534</b> <b>Fuel</b> (8-98037-011-0)..... <b>PF9919</b> <b>Radial Seal Air</b> (8-97062-294-0)..... <b>RS5434</b> <b>Trans. Spin-on</b> (97182282)..... <b>B114</b> <b>Steering</b> (8-97094-732-0)..... <b>CLN&amp;R</b>	NPR w/4HK1 (5.2L) Eng. (2018) <b>Lube</b> (8982984040)..... <b>B40137</b> <b>Fuel/Water Separator</b> (8980374810)..... <b>BF7534</b> <b>Fuel</b> (8981475250)..... <b>PF46059</b> <b>Fuel</b> (8981653750)..... <b>PF40052</b> <b>Radial Seal Air</b> (8981772710)..... <b>RS5434</b> <b>Steering</b> (8970947320)..... <b>CLN&amp;R</b>	NPR-HD w/GM V8-350 (5.7L) Eng. (1999-2002) <b>Lube</b> (8064383840)..... <b>B6+</b> <b>Fuel</b> (8250551290)..... <b>BF853</b> <b>Air</b> (8944302500)..... <b>PA2761</b>
NPR w/4HK1 (5.2L) Eng. (2010) <b>Dual-Flow Lube</b> (8-97148-270-1) <b>BD7169</b> <b>Fuel/Water Separator</b> (8-98037-480-0)..... <b>BF7534</b> <b>Fuel</b> (8-98037-011-0)..... <b>PF9919</b> <b>Some Air</b> (8-94430-250-0)..... <b>PA2761</b> <b>Radial Seal Air</b> (Single Cab) (8-97062-294-0)..... <b>RS5434</b> <b>Trans.</b> (97182282)..... <b>B114</b> <b>Steering</b> ..... <b>CLN&amp;R</b> <b>Diesel Exhaust Fluid</b> (2010 Emissions) (8-98169-403-0)..... <b>PE17000</b>	NPR w/4HK1 (5.2L) Eng. (2019) <b>Lube</b> (8982984040)..... <b>B40137</b> <b>Fuel/Water Separator</b> (8980374810)..... <b>BF7534</b> <b>Fuel</b> (8-98147-525-0)..... <b>PF46059</b> <b>Fuel</b> (8981653750)..... <b>PF40052</b> <b>Radial Seal Air</b> (8-98177-271-0)..... <b>RS5434</b>	NPR-HD w/GM V8-364 (6.0L) Eng. (2003-07) <b>Lube</b> (8-88984-215-0)..... <b>B31</b> <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Air</b> (8-94430-250-0)..... <b>PA2761</b> <b>Trans.</b> (8-97182-282-0)..... <b>B114</b> <b>Steering</b> ..... <b>CLN&amp;R</b>
NPR w/4HK1 (5.2L) Eng. (2011-12) <b>Lube</b> (8982984040)..... <b>B40137</b> <b>Fuel</b> (8-98147-525-0)..... <b>PF46059</b> <b>Fuel</b> (8981653750)..... <b>PF40052</b> <b>Some Air</b> (8-94430-250-0)..... <b>PA2761</b> <b>Radial Seal Air</b> (Single Cab) (8-97062-294-0)..... <b>RS5434</b> <b>Trans.</b> (97182282)..... <b>B114</b> <b>Steering</b> ..... <b>CLN&amp;R</b>	NPR w/4HK1 (5.2L) Eng. (2020) <b>Lube</b> (2906544040)..... <b>B40137</b> <b>Fuel/Water Separator</b> (8980374810)..... <b>BF7534</b> <b>Fuel</b> (8981653750)..... <b>PF40052</b> <b>Radial Seal Air</b> (29007N0000)..... <b>RS5434</b> <b>Steering</b> (8970947320)..... <b>CLN&amp;R</b>	NPR-HD w/GM V8-364 (6.0L) Eng. (2008-12) <b>Lube</b> (89017-524)..... <b>B160</b> <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Radial Seal Air</b> (8-97062-294-0)..... <b>RS5434</b> <b>Trans.</b> (8-97182-282-0)..... <b>B114</b> <b>Steering</b> ..... <b>CLN&amp;R</b>
	NPR w/4JJ1 (3.0L) Eng. (2011-16) <b>Lube</b> (8980188580)..... <b>P40021</b> <b>Fuel/Water Separator</b> (8-98037-481-0)..... <b>BF7534</b> <b>Fuel</b> (8-98162-897-0)..... <b>PF9919</b> <b>Radial Seal Air</b> (8-97062-294-0)..... <b>RS5434</b>	NPR-HD w/GM V8-364 (6.0L) Eng. (2013-16) <b>Lube</b> (89017-524)..... <b>B160</b> <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Radial Seal Air</b> (8-97062-294-0)..... <b>RS5434</b> <b>Cab Air</b> ..... <b>CLN&amp;R</b> <b>Trans.</b> (8-97182-282-0)..... <b>B114</b> <b>Steering</b> ..... <b>CLN&amp;R</b>
		NPR-HD w/GM V8-364 (6.0L) Eng. (2017) <b>Radial Seal Air</b> (8981772710)..... <b>RS5434</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

ISUZU Trucks (cont'd)	ISUZU Trucks (cont'd)	ISUZU Trucks (cont'd)
NPR-HD w/GM V8-364 (6.0L) Eng. (2018) Lube (8193039750)..... <b>B160</b> Fuel (N/S)..... <b>N/S</b> Radial Seal Air (8981772710)..... <b>RS5434</b>	NPR-HD w/4HK1 (5.2L) Eng. (2014-16) Lube (8982984040)..... <b>B40137</b> Fuel (8-98147-525-0)..... <b>PF46059</b> Fuel (8981653750)..... <b>PF40052</b> Radial Seal Air (8981772710)..... <b>RS5434</b> Some Air (8-94430-250-0)..... <b>PA2761</b> Trans. (97182282)..... <b>B114</b> Diesel Exhaust Fluid (8-98169-403-0)..... <b>PE17000</b>	NPR-XD w/4HK1-TC (5.2L) Eng. (2016) (Cont'd) Radial Seal Air (8981772710)..... <b>RS5434</b> Steering (8970947320)..... <b>CLN&amp;R</b>
NPR-HD w/GM V8-364 (6.0L) Eng. (2019) Fuel (N/S)..... <b>N/S</b> Air (8-98177-271-0)..... <b>RS5434</b>	NPR-HD w/4HK1 (5.2L) Eng. (2017) Lube (8982984040)..... <b>B40137</b> Fuel/Water Separator (8980374810)..... <b>BF7534</b> Fuel (8981475250)..... <b>PF46059</b> Fuel (8981653750)..... <b>PF40052</b> Radial Seal Air (8981772710)..... <b>RS5434</b> Steering (8970947320)..... <b>CLN&amp;R</b>	NPR-XD w/4HK1-TC (5.2L) Eng. (2017) Lube (8982984040)..... <b>B40137</b> Fuel/Water Separator (8980374810)..... <b>BF7534</b> Fuel (8981475250)..... <b>PF46059</b> Radial Seal Air (8981772710)..... <b>RS5434</b> Steering (8970947320)..... <b>CLN&amp;R</b> Diesel Exhaust Fluid (8981694030)..... <b>PE17000</b>
NPR-HD w/GM V8-364 (6.0L) Eng. (2020) Fuel (N/S)..... <b>N/S</b> Radial Seal Air (29007N0000)..... <b>RS5434</b>	NPR-HD w/4HK1 (5.2L) Eng. (2018) Lube (8982984040)..... <b>B40137</b> Fuel/Water Separator (8980374810)..... <b>BF7534</b> Fuel (8981475250)..... <b>PF46059</b> Fuel (8981653750)..... <b>PF40052</b> Radial Seal Air (8981772710)..... <b>RS5434</b> Steering (8970947320)..... <b>CLN&amp;R</b>	NPR-XD w/4HK1 (5.2L) Eng. (2018) Lube (8982984040)..... <b>B40137</b> Fuel/Water Separator (8980374810)..... <b>BF7534</b> Fuel (8981653750)..... <b>PF40052</b> Radial Seal Air (8981772710)..... <b>RS5434</b> Steering (8970947320)..... <b>CLN&amp;R</b>
NPR-HD w/4HE1 (4.8L) Eng. (1999-2004) Dual-Flow Lube (8971482700)..... <b>BD7169</b> Fuel (1132400791)..... <b>BF7602</b> 10 1/2 In. Air (8941560520)..... <b>PA2712</b> 13 1/2 In. Air (8944302500)..... <b>PA2761</b>	NPR-HD w/4HK1 (5.2L) Eng. (2018) Lube (8982984040)..... <b>B40137</b> Fuel/Water Separator (8980374810)..... <b>BF7534</b> Fuel (8981475250)..... <b>PF46059</b> Fuel (8981653750)..... <b>PF40052</b> Radial Seal Air (8981772710)..... <b>RS5434</b> Steering (8970947320)..... <b>CLN&amp;R</b>	NPR-XD w/4HK1 (5.2L) Eng. (2019) Lube (8982984040)..... <b>B40137</b> Fuel/Water Separator (8980374810)..... <b>BF7534</b> Fuel (8981653750)..... <b>PF40052</b> Fuel (8-98147-525-0)..... <b>PF46059</b> Radial Seal Air (8-98177-271-0)..... <b>RS5434</b>
NPR-HD w/4HK1 (5.2L) Eng. (To 2007) Dual-Flow Lube (8-97148-270-1) <b>BD7169</b> Fuel/Water Separator (8-98037-480-0)..... <b>BF7534</b> Some Air (8-94430-250-0)..... <b>PA2761</b> Radial Seal Air (Single Cab) (8-97062-294-0)..... <b>RS5434</b> Trans. (97182282)..... <b>B114</b> Steering..... <b>CLN&amp;R</b>	NPR-HD w/4HK1 (5.2L) Eng. (2019) Lube (8982984040)..... <b>B40137</b> Fuel/Water Separator (8980374810)..... <b>BF7534</b> Fuel (8-98147-525-0)..... <b>PF46059</b> Fuel (8981653750)..... <b>PF40052</b> Radial Seal Air (8981772710)..... <b>RS5434</b> Steering (8970947320)..... <b>CLN&amp;R</b>	NPR-XD w/4HK1 (5.2L) Eng. (2020) Lube (2906544040)..... <b>B40137</b> Fuel/Water Separator (8980374810)..... <b>BF7534</b> Fuel (8981653750)..... <b>PF40052</b> Air (29007N0000)..... <b>RS5434</b> Steering (8970947320)..... <b>CLN&amp;R</b>
NPR-HD w/4HK1 (5.2L) Eng. (2008-10) Dual-Flow Lube (8-97148-270-1) <b>BD7169</b> Fuel/Water Separator (8-98037-480-0)..... <b>BF7534</b> Fuel (8-98037-011-0)..... <b>PF9919</b> Some Air (8-94430-250-0)..... <b>PA2761</b> Radial Seal Air (Single Cab) (8-97062-294-0)..... <b>RS5434</b> Trans. (97182282)..... <b>B114</b> Steering..... <b>CLN&amp;R</b> Diesel Exhaust Fluid (2010 Emissions) (8-98169-403-0)..... <b>PE17000</b>	NPR-HD w/4HK1 (5.2L) Eng. (2020) Lube (2906544040)..... <b>B40137</b> Fuel/Water Separator (8980374810)..... <b>BF7534</b> Fuel (8981653750)..... <b>PF40052</b> Radial Seal Air (29007N0000)..... <b>RS5434</b> Steering (8970947320)..... <b>CLN&amp;R</b>	NPR-XD w/4HK1 (5.2L) Eng. (2022) Lube (2906544040)..... <b>B40137</b> Fuel/Water Separator (8980374810)..... <b>BF7534</b> Fuel (8981653750)..... <b>PF40052</b> Radial Seal Air (29007N0000)..... <b>RS5434</b> Steering (8970947320)..... <b>CLN&amp;R</b>
NPR-HD w/4HK1 (5.2L) Eng. (2011-12) Lube (8982984040)..... <b>B40137</b> Fuel (8-98147-525-0)..... <b>PF46059</b> Fuel (8-98147-570-0)..... <b>PF40052</b> Some Air (8-94430-250-0)..... <b>PA2761</b> Radial Seal Air (Single Cab) (8-97062-294-0)..... <b>RS5434</b> Trans. (97182282)..... <b>B114</b> Steering..... <b>CLN&amp;R</b> Diesel Exhaust Fluid (8-98169-403-0)..... <b>PE17000</b>	NPR-HD w/4HK1 (5.2L) Eng. (2022) Lube (2906544040)..... <b>B40137</b> Fuel/Water Separator (8980374810)..... <b>BF7534</b> Fuel (8981653750)..... <b>PF40052</b> Radial Seal Air (29007N0000)..... <b>RS5434</b> Steering (8970947320)..... <b>CLN&amp;R</b>	NPR-XD w/4HK1-TC (5.2L) Eng. (2015) Lube (8982984040)..... <b>B40137</b> Fuel/Water Separator (8980374810)..... <b>BF7534</b> Fuel (8981475250)..... <b>PF46059</b> Radial Seal Air (8981772710)..... <b>RS5434</b> Steering (8970947320)..... <b>CLN&amp;R</b>
NPR-HD w/4HK1 (5.2L) Eng. (2013) Lube (8982984040)..... <b>B40137</b> Fuel Ele. (8-98165-375-0)..... <b>PF40052</b> Fuel (8-98147-525-0)..... <b>PF46059</b> Some Air (8-94430-250-0)..... <b>PA2761</b> Air (8-98177-271-0)..... <b>RS5434</b> Cab Air..... <b>CLN&amp;R</b> Trans. (97182282)..... <b>B114</b> Diesel Exhaust Fluid (8-98169-403-0)..... <b>PE17000</b>	NPR-XD w/4HK1-TC (5.2L) Eng. (2016) Lube (8982984040)..... <b>B40137</b> Fuel/Water Separator (8980374810)..... <b>BF7534</b> Fuel (8981475250)..... <b>PF46059</b>	NPR57L w/4BC2 Eng. (1986-90) B-P Lube (8943402591)..... <b>B201-S</b> Air (8941560520)..... <b>PA2712</b>
		NPR58 w/4BE1 Eng. (1989-94) B-P Lube (8943402591)..... <b>B201-S</b> Air (8941560520)..... <b>PA2712</b>
		NPR59 w/4BD1 Eng. (1986-89) B-P Lube (8943402591)..... <b>B201-S</b> Air (8941560520)..... <b>PA2712</b>
		NPR59 w/4BD1T Eng. (1989-96) B-P Lube (8943402591)..... <b>B201-S</b> Air (8941560520)..... <b>PA2712</b>
		NPR59P, NPR59PJ w/4BD1 Eng. Lube Ele. (9-88511-194-2)..... <b>P7050</b> Fuel Spin-on..... <b>BF7648</b> Air (8-94156-052-0)..... <b>PA2712</b>

Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

ISUZU Trucks (cont'd)	ISUZU Trucks (cont'd)	ISUZU Trucks (cont'd)
NPR65 w/4BD2TC Eng. (1996-on) Dual-Flow Lube (8971482800).... <b>BD7166</b> Air (8941560520)..... <b>PA2712</b>	NPS71 w/4HG1 Eng. (1995-97) Air (8941560520)..... <b>PA2712</b>	NQR w/4HK1 (5.2L) Eng. (2013-16) (Cont'd) Diesel Exhaust Fluid (8-98169-403-0)..... <b>PE17000</b>
NPR66 w/4HF1 Eng. (1994-on) Air (8941560520)..... <b>PA2712</b>	NPS72 w/4HJ1 Eng. (1998-on) ..... <b>PA2712</b>	NQR w/4HK1 (5.2L) Eng. (2017) Lube (8982984040)..... <b>B40137</b> Fuel/Water Separator (8980374810)..... <b>BF7534</b> Fuel (8981475250)..... <b>PF46059</b> Fuel (8981653750)..... <b>PF40052</b> Radial Seal Air (8981772710)..... <b>RS5434</b> Steering (8970947320)..... <b>CLN&amp;R</b> Diesel Exhaust Fluid (8981694030)..... <b>PE17000</b>
NPR70 w/4HE1T Eng. (1998-on) Radial Seal Air (8970622940)..... <b>RS5434</b>	NPS400 w/4BD1T Eng. (1989-94) B-P Lube (8943402591)..... <b>B201-S</b> Air (8941560520)..... <b>PA2712</b>	NQR w/4HK1 (5.2L) Eng. (2018) Lube (8982984040)..... <b>B40137</b> Fuel/Water Separator (8980374810)..... <b>BF7534</b> Fuel (8981475250)..... <b>PF46059</b> Fuel (8981653750)..... <b>PF40052</b> Radial Seal Air (8981772710)..... <b>RS5434</b> Steering (8970947320)..... <b>CLN&amp;R</b> Diesel Exhaust Fluid (8981694030)..... <b>PE17000</b>
NPS w/4BD1T Eng. F-F Lube (8-94169-778-2)..... <b>B244</b> B-P Lube (8-94169-779-2)..... <b>B222</b> Fuel..... <b>[2] BF7648</b>	NPS400 w/4HF1 Eng. (1994-95) Air (8941560520)..... <b>PA2712</b>	NQR w/4HK1 (5.2L) Eng. (2019) Lube (8982984040)..... <b>B40137</b> Fuel/Water Separator (8-98037-481-0)..... <b>BF7534</b> Fuel (8-98147-525-0)..... <b>PF46059</b> Fuel (8981653750)..... <b>PF40052</b> Radial Seal Air (8-98177-271-0)..... <b>RS5434</b> Steering (8-97094-732-0)..... <b>CLN&amp;R</b> Diesel Exhaust Fluid (8-98169-403-0)..... <b>PE17000</b>
NPR71 w/4HG1 Eng. (1998-on) Radial Seal Air (8970622940)..... <b>RS5434</b>	NPS400 w/4HG1 Eng. (1995-97) Air (8941560520)..... <b>PA2712</b>	NQR w/4HK1 (5.2L) Eng. (2020) Lube (2906544040)..... <b>B40137</b> Fuel/Water Separator (8980374810)..... <b>BF7534</b> Fuel (8981653750)..... <b>PF40052</b> Radial Seal Air (29007N0000)..... <b>RS5434</b> Steering (8970947320)..... <b>CLN&amp;R</b>
NPR250 w/4HF1 (4.3L) Eng. Dual-Flow Lube (8-97096-777-0) <b>BD7159</b> P. Fuel Spin-on (8-94143-479-0) <b>BF7648</b> Air (8-94156-052-0)..... <b>PA2712</b>	NPS450 w/4HJ1 Eng. (1998-on) Air (8941560520)..... <b>PA2712</b>	NQR w/4HK1 (5.2L) Eng. (2022) Lube (2906544040)..... <b>B40137</b> Fuel/Water Separator (8980374810)..... <b>BF7534</b> Fuel (8981653750)..... <b>PF40052</b> Radial Seal Air (29007N0000)..... <b>RS5434</b> Cab Air (8970947320)..... <b>CLN&amp;R</b> Steering (8970947320)..... <b>CLN&amp;R</b>
NPR300 w/4BE1 Eng. (1989-94) B-P Lube (8943402591)..... <b>B201-S</b> Air (8941560520)..... <b>PA2712</b>	NQR w/4BD2 (3.9L) Eng. Dual-Flow Lube (8971482800).... <b>BD7166</b> Fuel (5873103350)..... <b>BF7648</b>	NQR w/General Motors (6.0L) Eng. (2022) Fuel (N/S)..... <b>N/S</b> Radial Seal Air (29007N0000)..... <b>RS5434</b> Cab Air (8970947320)..... <b>CLN&amp;R</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
NPR300 w/4HF1 (4.3L) Eng. Dual-Flow Lube (8-97096-777-0) <b>BD7159</b> P. Fuel Spin-on (8-94143-479-0) <b>BF7648</b> Air (8-94156-052-0)..... <b>PA2712</b>	NQR w/4HE1 (4.8L) Eng. Dual-Flow Lube..... <b>BD7169</b> Lube (2946541000)..... <b>B40138</b> Fuel Spin-on (1-13240-079-1)..... <b>BF7602</b> Fuel Spin-on..... <b>BF719</b> Air (8-94430-250-0)..... <b>PA2761</b> Trans. Spin-on..... <b>B252</b>	
NPR350 w/4HF1 Eng. (1994-on) Air (8941560520)..... <b>PA2712</b>	NQR w/4HK1 (5.2L) Eng. (2004-07) Dual-Flow Lube (2-90654-800-0) <b>BD7169</b> Fuel/Water Separator (94369299)..... <b>BF7534</b> Axial Seal Air (94430250)..... <b>PA2761</b> Radial Seal Air (8-97062-294-0).. <b>RS5434</b> Trans. Spin-on (8-97182-282-0).. <b>B114</b> Steering (8-97094-732-0)..... <b>CLN&amp;R</b>	
NPR400 w/4BD1 Eng. (1986-89) B-P Lube (8943402591)..... <b>B201-S</b> Air (8941560520)..... <b>PA2712</b>	NQR w/4HK1 (5.2L) Eng. (2008-10) Dual-Flow Lube (2-90654-800-0) <b>BD7169</b> Fuel/Water Separator (8-98037-480-0)..... <b>BF7534</b> Fuel (8-98037-011-0)..... <b>PF9919</b> Radial Seal Air (8-97062-294-0).. <b>RS5434</b> Trans. Spin-on (8-97182-282-0).. <b>B114</b> Steering (8-97094-732-0)..... <b>CLN&amp;R</b> Diesel Exhaust Fluid (2010 Emissions) (8-98169-403-0)..... <b>PE17000</b>	
NPR400 w/4BD1T Eng. (1994-96) B-P Lube (8943402591)..... <b>B201-S</b> Air (8941560520)..... <b>PA2712</b>	NQR w/4HK1 (5.2L) Eng. (2011-12) Dual-Flow Lube (2-90654-800-0) <b>BD7169</b> Fuel (8-98147-525-0)..... <b>PF46059</b> Fuel (8981653750)..... <b>PF40052</b> Radial Seal Air (8-97062-294-0).. <b>RS5434</b> Trans. Spin-on (8-97182-282-0).. <b>B114</b> Diesel Exhaust Fluid (8-98169-403-0)..... <b>PE17000</b>	
NPR400 w/4HF1 (4.3L) Eng. Dual-Flow Lube (8-97096-777-0) <b>BD7159</b> P. Fuel Spin-on (8-94143-479-0) <b>BF7648</b> Air (8-94156-052-0)..... <b>PA2712</b>	NQR w/4HK1 (5.2L) Eng. (2013-16) Dual-Flow Lube (2-90654-800-0) <b>BD7169</b> Fuel Ele. (8-98165-375-0)..... <b>PF40052</b> Fuel (8-98147-525-0)..... <b>PF46059</b> Radial Seal Air (8-97062-294-0).. <b>RS5434</b> Cab Air..... <b>CLN&amp;R</b> Trans. Spin-on (8-97182-282-0).. <b>B114</b>	
NPR400 w/4HG1 Eng. (1998-on) Radial Seal Air (8970622940)..... <b>RS5434</b>		
NPR450 w/4BD2TC Eng. (1996-on) Dual-Flow Lube (8971482800).... <b>BD7166</b> Air (8941560520)..... <b>PA2712</b>		
NPR575 w/4BC2 Eng. (1985-86) Lube (9885111942)..... <b>P7050</b> Air (8941560520)..... <b>PA2712</b>		
NPR596 w/4BD1 Eng. (1985-86) Lube (9885111942)..... <b>P7050</b> Air (8941560520)..... <b>PA2712</b>		
NPS59GN, NPS59LN w/4BD1T Eng. (1989-94) B-P Lube (8943402591)..... <b>B201-S</b> Air (8941560520)..... <b>PA2712</b>		
NPS66 w/4HF1 Eng. (1994-95) Air (8941560520)..... <b>PA2712</b>		

Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

ISUZU Trucks (cont'd)	ISUZU Trucks (cont'd)	ISUZU Trucks (cont'd)
NQR w/General Motors (6.0L) Eng. (2022) (Cont'd) <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Steering</b> (8970947320)..... <b>CLN&amp;R</b>	NRR w/4HK1 (5.2L) Eng. (2013) (Cont'd) <b>Cab Air</b> ..... <b>CLN&amp;R</b> <b>Trans. Spin-on</b> (97182282)..... <b>B114</b> <b>Diesel Exhaust Fluid</b> (8-98169-403-0)..... <b>PE17000</b>	NRR w/General Motors (6.0L) Eng. (2022) <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
NQR70 w/4HE1T Eng. (1998-on) <b>Radial Seal Air</b> (8970622940)..... <b>RS5434</b>	NRR w/4HK1 (5.2L) Eng. (2014-16) <b>Dual-Flow Lube</b> (8-97148-270-1) <b>BD7169</b> <b>Fuel</b> (8-98147-525-0)..... <b>PF46059</b> <b>Fuel</b> (8981653750)..... <b>PF40052</b> <b>Air</b> (8-98177-271-0)..... <b>RS5434</b> <b>Trans. Spin-on</b> (97182282)..... <b>B114</b> <b>Diesel Exhaust Fluid</b> (8-98169-403-0)..... <b>PE17000</b>	NRR w/6BG1 (6.5L) Eng. (1988-94) <b>F-F Lube</b> (1-13200-487-0)..... <b>B75</b> <b>B-P Lube</b> (1-13240-089-0)..... <b>BF124</b> <b>Fuel</b> (1-13240-079-1)..... <b>BF7602</b> <b>O. Air</b> (1-14215-172-0)..... <b>PA2779</b> <b>I. Air</b> (1-14215-111-0)..... <b>PA2545</b>
NQR500 w/4HE1T Eng. (1998-on) <b>Radial Seal Air</b> (8970622940)..... <b>RS5434</b>	NRR w/4HK1 (5.2L) Eng. (2017) <b>Lube</b> (8982984040)..... <b>B40137</b> <b>Fuel/Water Separator</b> (8980374810)..... <b>BF7534</b> <b>Fuel</b> (8981475250)..... <b>PF46059</b> <b>Fuel</b> (8981653750)..... <b>PF40052</b> <b>Radial Seal Air</b> (8981772710)..... <b>RS5434</b> <b>Steering</b> (8970947320)..... <b>CLN&amp;R</b> <b>Diesel Exhaust Fluid</b> (8981694030)..... <b>PE17000</b>	NRR w/6BG1 (6.5L) Eng. (1995-96) <b>Fuel</b> (1-13240-079-1)..... <b>BF7602</b> <b>O. Air</b> (1-14215-172-0)..... <b>PA2779</b> <b>I. Air</b> (1-14215-111-0)..... <b>PA2545</b>
NRR w/4HK1 (5.2L) Eng. (2004-05) <b>Dual-Flow Lube</b> (8-97148-270-1) <b>BD7169</b> <b>Fuel/Water Separator</b> (94369299)..... <b>BF7534</b> <b>Axial Seal Air</b> (94430250)..... <b>PA2761</b> <b>Trans. Spin-on</b> (97182282)..... <b>B114</b> <b>Steering</b> (8-97094-732-0)..... <b>CLN&amp;R</b>	NRR w/4HK1 (5.2L) Eng. (2018) <b>Lube</b> (8982984040)..... <b>B40137</b> <b>Fuel/Water Separator</b> (8980374810)..... <b>BF7534</b> <b>Fuel</b> (8981475250)..... <b>PF46059</b> <b>Fuel</b> (8981653750)..... <b>PF40052</b> <b>Radial Seal Air</b> (8981772710)..... <b>RS5434</b> <b>Steering</b> (8970947320)..... <b>CLN&amp;R</b> <b>Diesel Exhaust Fluid</b> (8981694030)..... <b>PE17000</b>	NRR w/6BG1 (6.5L) Eng. (1997-06) <b>Fuel</b> (1-13240-079-1)..... <b>BF7602</b> <b>O. Air</b> (1-14215-172-0)..... <b>PA2779</b> <b>I. Air</b> (1-14215-111-0)..... <b>PA2545</b> <b>Trans.</b> (24210956)..... <b>18027</b>
NRR w/4HK1 (5.2L) Eng. (2006-07) <b>Dual-Flow Lube</b> (8-97148-270-1) <b>BD7169</b> <b>Fuel/Water Separator</b> (94369299)..... <b>BF7534</b> <b>Axial Seal Air</b> (94430250)..... <b>PA2761</b> <b>Radial Seal Air</b> (8-97062-294-0)..... <b>RS5434</b> <b>Trans. Spin-on</b> (97182282)..... <b>B114</b> <b>Steering</b> (8-97094-732-0)..... <b>CLN&amp;R</b>	NRR w/4HK1 (5.2L) Eng. (2019) <b>Lube</b> (8982984040)..... <b>B40137</b> <b>Fuel</b> (8-98165-375-0)..... <b>PF40052</b> <b>Fuel</b> (8-98147-525-0)..... <b>PF46059</b> <b>Air</b> (8-98177-271-0)..... <b>RS5434</b> <b>Steering</b> (8-97094-732-0)..... <b>CLN&amp;R</b> <b>Diesel Exhaust Fluid</b> (8981694030)..... <b>PE17000</b>	P-BL36.46 w/4BC2 Eng. <b>Lube Ele.</b> (9-88511-194-2)..... <b>P7050</b> <b>Fuel Spin-on</b> (8-94143-479-0)..... <b>BF7648</b>
NRR w/4HK1 (5.2L) Eng. (2008-10) <b>Dual-Flow Lube</b> (8-97148-270-1) <b>BD7169</b> <b>Fuel/Water Separator</b> (8-98037-480-0)..... <b>BF7534</b> <b>Fuel</b> (8-98037-011-0)..... <b>PF9919</b> <b>Radial Seal Air</b> (8-97062-294-0)..... <b>RS5434</b> <b>Trans. Spin-on</b> (97182282)..... <b>B114</b> <b>Steering</b> (8-97094-732-0)..... <b>CLN&amp;R</b>	NRR w/4HK1 (5.2L) Eng. (2020) <b>Lube</b> (2906544040)..... <b>B40137</b> <b>Fuel/Water Separator</b> (8980374810)..... <b>BF7534</b> <b>Fuel</b> (8981653750)..... <b>PF40052</b> <b>Radial Seal Air</b> (29007N0000)..... <b>RS5434</b> <b>Steering</b> (8970947320)..... <b>CLN&amp;R</b>	Reach w/4JJ1 (3.0L) Eng. <b>Lube</b> (8980188580)..... <b>P40021</b> <b>Fuel/Water Separator</b> (8-98037-481-0)..... <b>BF7534</b> <b>Fuel</b> (8-98162-897-0)..... <b>PF9919</b> <b>Radial Seal Air</b> (8-97062-294-0)..... <b>RS5434</b> <b>Cab Air</b> ..... <b>CLN&amp;R</b> <b>Diesel Exhaust Fluid</b> (8-98169-403-0)..... <b>PE17000</b>
NRR w/4HK1 (5.2L) Eng. (2011) <b>Dual-Flow Lube</b> (8-97148-270-1) <b>BD7169</b> <b>Fuel</b> (8-98147-525-0)..... <b>PF46059</b> <b>Fuel</b> (8981653750)..... <b>PF40052</b> <b>Radial Seal Air</b> (8-97062-294-0)..... <b>RS5434</b> <b>Trans. Spin-on</b> (97182282)..... <b>B114</b> <b>Steering</b> (8-97094-732-0)..... <b>CLN&amp;R</b> <b>Diesel Exhaust Fluid</b> (8-98169-403-0)..... <b>PE17000</b>	NRR w/4HK1 (5.2L) Eng. (2022) <b>Lube</b> (2906544040)..... <b>B40137</b> <b>Fuel/Water Separator</b> (8980374810)..... <b>BF7534</b> <b>Fuel</b> (8981653750)..... <b>PF40052</b> <b>Radial Seal Air</b> (29007N0000)..... <b>RS5434</b> <b>Steering</b> (8970947320)..... <b>CLN&amp;R</b>	SBR w/6BB1 Eng. (1980-85) <b>Lube</b> (1878100752)..... <b>P723</b> <b>Fuel</b> (9885111911)..... <b>PF311</b> <b>Air</b> (6424690)..... <b>PA1681-FN</b>
NRR w/4HK1 (5.2L) Eng. (2012) <b>Dual-Flow Lube</b> (8-97148-270-1) <b>BD7169</b> <b>Fuel</b> (8-98147-525-0)..... <b>PF46059</b> <b>Fuel</b> (8-98147-570-0)..... <b>PF40052</b> <b>Air</b> (8-98177-271-0)..... <b>RS5434</b> <b>Trans. Spin-on</b> (97182282)..... <b>B114</b> <b>Steering</b> (8-97094-732-0)..... <b>CLN&amp;R</b> <b>Diesel Exhaust Fluid</b> (8-98169-403-0)..... <b>PE17000</b>	NRR w/4HK1 (5.2L) Eng. (2022) <b>Lube</b> (2906544040)..... <b>B40137</b> <b>Fuel/Water Separator</b> (8980374810)..... <b>BF7534</b> <b>Fuel</b> (8981653750)..... <b>PF40052</b> <b>Radial Seal Air</b> (29007N0000)..... <b>RS5434</b> <b>Steering</b> (8970947320)..... <b>CLN&amp;R</b>	SHH711S w/6RA1 Eng. (1982-84) <b>F-F Lube</b> (9885132653)..... <b>PT466</b> <b>Fuel</b> (1132401910)..... <b>PF332</b> <b>O. Std. Air</b> (Horizontal Hsg.) (1142151160)..... <b>PA2676 +</b> <b>O. XP Air</b> (Horizontal Hsg.) (1142151160)..... <b>PA2676XP</b> <b>I. Air</b> (Horizontal Hsg.) (1142151270)..... <b>PA3668</b> <b>O. Air</b> (Vertical Hsg.) (Don. P182046)..... <b>LL1885 +</b> <b>I. Air</b> (Vertical Hsg.) (6487136)..... <b>PA1893</b>
NRR w/4HK1 (5.2L) Eng. (2013) <b>Dual-Flow Lube</b> (8-97148-270-1) <b>BD7169</b> <b>Fuel Ele.</b> (8-98165-375-0)..... <b>PF40052</b> <b>Fuel</b> (8-98147-525-0)..... <b>PF46059</b> <b>Air</b> (8-98177-271-0)..... <b>RS5434</b>		

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



ISUZU Trucks (cont'd)	ISUZU Trucks (cont'd)	ISUZU Trucks (cont'd)
SHZ451 w/6RA1, 6RA1T, 6RB1 Engs. (3/82-84)	TFR17, TFS17 w/4ZE1 Eng. (1989-94)	Trooper UBS55 w/4JB1T Eng. (1989-92)
F-F Lube (9885132653).....	Lube (8943142633).....	Lube (5873104890).....
Fuel (1132401910).....	Fuel (5132000661).....	Fuel (8943940791).....
O. Air (Horizontal Hsg.) (25096438).....	Air (4302955).....	
PA2577	PA1657	BF146
I. Air (Horizontal Hsg.) (25096436).....		BF13
PA2578	TFR54, TFS54 w/4JA1 Eng. (1989-94)	
O. Air (Vertical Hsg.) (Don. P182046).....	Lube (5873104890).....	Dual-Flow Lube (8943604271)....
LL1885 +	Fuel (8943940791).....	Fuel/Water Separator
PA1893	Air (8943349060).....	(8943692993).....
SHZ581S w/6RA1 Eng. (1982-84)	PA2884	BF7534
F-F Lube (9885132653).....	TFS55 w/4JB1T Eng. (1989-94)	
Fuel (1132401910).....	Lube (5873104890).....	U-NPR66, U-NPS66 w/4HF1, 4HF1T Engs.
O. Std. Air (Horizontal Hsg.) (1142151160).....	Fuel (8943940791).....	Dual-Flow Lube (w/Inter-Cooler)
PA2676 +	Air (8943349060).....	(8-97148-270-0).....
O. XP Air (Horizontal Hsg.) (1142151160).....	PA2884	BD7169
PA2676XP	TLD23 w/C240 Eng. (1977-81)	Dual-Flow Lube (w/o Inter-Cooler) (8-94338-181-1).....
I. Air (Horizontal Hsg.) (1142151270).....	Lube Ele. (9885132653).....	BD7159
PA3668	Lube Spin-on (8970246071).....	Fuel Spin-on (8-94151-744-0).....
O. Air (Vertical Hsg.) (Don. P182046).....	Fuel (8943940791).....	BF7648
LL1885 +	Air (8971732100).....	BF954
PA1893	PA2904	
SLR w/DH100 Eng. (1972-79)	TLD24 w/4BA1 Eng. (1981-84) (New Zealand)	U-NPR70 w/4HF1T Eng.
Lube (9885132653).....	Lube (9885111942).....	Dual-Flow Lube (w/Inter-Cooler)
Fuel (9885111911).....	Fuel (8943940791).....	(8-97148-270-0).....
Air (1142150051).....	Air (8971732100).....	BD7169
PA466		Dual-Flow Lube (w/o Inter-Cooler) (8-94338-181-1).....
PF311	TLD24 w/4BA1 Eng. (North America)	BD7159
PA1884	Lube Ele. (9-88511-194-2).....	Fuel Spin-on (8-94151-744-0).....
SPH w/E120, E120T Engs. (1980-82)	Fuel Spin-on (8-94143-479-0).....	BF7648
F-F Lube (9885132653).....		RS5434
Fuel (1132401910).....	TLD44 w/4BA1 Eng.	
I. Air (6487136).....	Lube Ele. (9-88511-194-2).....	VHR301S w/6RA1 Eng. (1982-84)
PA1893	Fuel Spin-on (8-94143-479-0).....	F-F Lube (9885132653).....
SPZ w/E120 Eng. (1974-79)	BF7648	Fuel (1132401910).....
F-F Lube (9885132653).....	TLD54 w/4BA1 Eng.	O. Std. Air (Horizontal Hsg.) (1142151160).....
Fuel (1132401910).....	Lube Ele. (9-88511-194-2).....	PA2676 +
I. Air (6487136).....	Fuel Spin-on (8-94143-479-0).....	O. XP Air (Horizontal Hsg.) (1142151160).....
PA1884		PA2676XP
SPZ w/E120, E120T Engs. (1980-82)	TLD56 w/4BC2 Eng. (1982-84)	I. Air (Horizontal Hsg.) (1142151270).....
F-F Lube (9885132653).....	Lube (9885111942).....	PA3668
Fuel (1132401910).....	Fuel (8943940791).....	O. Air (Vertical Hsg.) (Don. P182046).....
I. Air (6487136).....	Air (8943940791).....	LL1885 +
PA1893		PA1893
SPZ451 w/E120 Eng. (1980-2/82)	TLG52 OHV w/G201 Eng. (1974-76)	I. Air (Vertical Hsg.) (6487136).....
F-F Lube (9885132653).....	Lube (9885131071).....	
Fuel (1132401910).....	Air (4302955).....	VH441S w/6RA1 Eng. (1982-84)
I. Air (6487136).....		F-F Lube (9885132653).....
PA1893	PA1657	Fuel (1132401910).....
TD70 w/DH100 Eng. (1972-79)	Trooper UBS13 w/G200Z Eng. (1981-on)	O. Std. Air (Horizontal Hsg.) (1142151160).....
Lube (9885132653).....	Lube (8943142633).....	PA2676 +
Fuel (9885111911).....	Fuel (5132000661).....	O. XP Air (Horizontal Hsg.) (1142151160).....
Air (1142150051).....	Air (4302955).....	PA2676XP
PA1884		I. Air (Horizontal Hsg.) (1142151270).....
TDK35 w/E120 Eng. (1972-74)	Trooper UBS16 w/4ZD1 Eng. (1987-88)	PA3668
Lube (9885132653).....	Lube (25013032).....	O. Air (Vertical Hsg.) (Don. P182046).....
Fuel (9885111911).....	Fuel (5132000661).....	LL1885 +
Air (1142150051).....	Air (4302955).....	PA1893
PA1884		I. Air (Vertical Hsg.) (6487136).....
TFR16 w/4ZD1 Eng. (1989-94)	Trooper UBS17 w/4ZE1 Eng. (1987-92)	
Lube (8943142633).....	Lube (25013032).....	VLR w/DH100 Eng. (1972-79)
Fuel (5132000661).....	Fuel (5132000661).....	Lube (9885132653).....
Air (4302955).....	Air (4302955).....	Fuel (9885111911).....
PA1657		PF311
	Trooper UBS25 w/6VD1 Eng. (1992-94)	PA1884
	Lube (8943142633).....	
		VPR w/E120 Eng. (1972-74)
		Lube (9885132653).....
		Fuel (9885111911).....
		Air (1142150051).....
		PT466
		PF311
		PA1884
		VPR w/E120 Eng. (1974-79)
		F-F Lube (9885132653).....
		Fuel (1132401910).....
		I. Air (6487136).....
		PT466
		PF332
		PA1893

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

**Trucks & Buses Applications** **BALDWIN FILTERS**

<b>ISUZU Trucks (cont'd)</b>	<b>ISUZU Trucks (cont'd)</b>	<b>ISUZU Trucks (cont'd)</b>
VPR w/E120 Eng. (1974-79) (Cont'd) <b>Single Air</b> (1142150051)..... <b>PA1884</b>	W4 w/Gas Eng. <b>Lube</b> (1993-95) (8-06438-384-0).. <b>B6 +</b> <b>Lube</b> (V8 5.7L Eng.) 1996-2002 (8-25160-561-0)..... <b>B1428 +</b> <b>Lube</b> (V8 6.0L Eng.) 2003-06 (8-25010-633-0)..... <b>B31</b> <b>Lube</b> (V8 6.0L Eng.) 2007-on (89017524)..... <b>B160</b> <b>Fuel</b> (1993-2002) (8-25055-052-0)..... <b>BF853</b> <b>Fuel</b> (V8 6.0L Eng.) 2003-on (N/S)..... <b>N/S</b> <b>Axial Seal Air</b> (1/93-9/95) (8-06484-235-0)..... <b>PA2008</b> <b>Axial Seal Air</b> (1996-2007) (8-94430-250-0)..... <b>PA2761</b> <b>Radial Seal Air</b> (2008-on) (8-97062-294-0)..... <b>RS5434</b> <b>Trans.</b> (1993-5/96) (8-08684-221-0)..... <b>18007</b> <b>Trans.</b> (6/96-on) (24210-956)..... <b>18027</b>	W6 (Cont'd) <b>Fuel</b> (1987-2002) (2-90654-940-0)..... <b>BF7602</b> <b>O. Air</b> (1987-10/88) (1-14215-172-0)..... <b>PA2779</b> <b>Single Air</b> (11/88-12/94) (1-14215-172-0)..... <b>PA2779</b> <b>Air</b> (1995-96) (1-14215-181-0)..... <b>PA2577</b> <b>Radial Seal O. Air</b> (1998-2002) (8-12471-801-0)..... <b>RS3548</b> <b>Radial Seal XP O. Air</b> (1998-2002) (8-12471-801-0)..... <b>RS3548XP</b> <b>Trans. Spin-on</b> (1997-2002) (25011-122)..... <b>BT230</b>
VPR w/E120, E120T Eng. (1980-82) <b>F-F Lube</b> (9885132653)..... <b>PT466</b> <b>Fuel</b> (1132401910)..... <b>PF332</b> <b>I. Air</b> (6487136)..... <b>PA1893</b>	<b>W5</b> <b>F-F Lube</b> (1988-on) (1-13200-487-2)..... <b>B75</b> <b>B-P Lube</b> (1988-96) (2-90654-820-0)..... <b>B7124</b> <b>Dual-Flow Lube</b> (2005-on) (2-90654-800-0)..... <b>BD7169</b> <b>Fuel/Water Separator</b> (2005-07) (8-94369-299-3)..... <b>BF7534</b> <b>Fuel/Water Separator</b> (2000-on) (1-13240-194-0)..... <b>PF9897</b> <b>Fuel</b> (1988-on) (2-90654-940-0).... <b>BF7602</b> <b>Fuel</b> (2008-on) (8-98037-011-0).... <b>PF9919</b> <b>Std. O. Air</b> (1988-94) (1-14215-172-0)..... <b>PA2779</b> <b>Std. I. Air</b> (1988-94) (1-14215-111-0)..... <b>PA2545</b> <b>Axial Seal Air</b> (1995-99) (1-14215-181-0)..... <b>PA2577</b> <b>Std. O. Air</b> (2000-on) (1-14215-181-0)..... <b>PA2577</b> <b>Std. I. Air</b> (2000-on) (1-14215-151-0)..... <b>PA2578</b> <b>Single Std. Air</b> (2005) (8-94430-250-0)..... <b>PA2761</b> <b>Single Radial Seal Air</b> (2006-on) (8-97062-294-0)..... <b>RS5434</b> <b>Trans. Spin-on</b> (1990-2001) (1-32569-021-0)..... <b>BT230</b> <b>Trans. Spin-on</b> (2008-on) (8-97182-282-0)..... <b>B114</b>	<b>W7H</b> <b>F-F Lube</b> (1986-on) (1-13200-487-2)..... <b>B75</b> <b>B-P Lube</b> (6SA1-T Eng.) 1986-91 (1-13240-163-2)..... <b>B7577</b> <b>B-P Lube</b> (6BG1-T, GHE1-T Eng.) 1990-96 (2-90654-820-0).... <b>B7124</b> <b>Secondary Lube</b> (2004-on) (15525-633)..... <b>C750-E +</b> <b>Fuel/Water Separator</b> (w/Drain) (15618-921)..... <b>BF5813 +</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (15618-921)..... <b>BF5813-O +</b> <b>Fuel</b> (1986-2/2007) (2-90654-940-0)..... <b>BF7602</b> <b>Fuel</b> (3/07-on) (8-98037-011-0).... <b>PF9919</b> <b>O. Air</b> (1986-10/00) (1-14215-152-0)..... <b>PA2577</b> <b>I. Air</b> (1986-10/88) (1-14215-125-0)..... <b>PA2578</b> <b>Single Air</b> (11/88-5/89) (1-14215-181-0)..... <b>PA2577</b> <b>Air</b> (6BG1-T Eng.) 1990-94 (1-14215-172-0)..... <b>PA2779</b> <b>Air</b> (6HE1-T Eng.) 1995-96 (1-14215-181-0)..... <b>PA2577</b> <b>Air</b> (6HE1 Eng.) 1997-98 (8-12386-667-0)..... <b>PA2577</b> <b>Radial Seal O. Air</b> (6HK1 Eng.) 1998-2002 (8-12471-801-0)..... <b>RS3548</b> <b>Radial Seal XP O. Air</b> (6HK1 Eng.) 1998-2002 (8-12471-801-0)..... <b>RS3548XP</b> <b>Single Radial Seal Air</b> (6HK1 Eng.) 1998-on (8-12471-801-0).... <b>RS3548</b> <b>Single Radial Seal XP Air</b> (6HK1 Eng.) 1998-on (8-12471-801-0).... <b>RS3548XP</b> <b>Trans. Spin-on</b> (1997-2002) (25011-122)..... <b>BT230</b>
VPR301 w/E120 Eng. (1980-2/82) <b>F-F Lube</b> (9885132653)..... <b>PT466</b> <b>Fuel</b> (1132401910)..... <b>PF332</b> <b>I. Air</b> (6487136)..... <b>PA1893</b>	<b>W6</b> <b>B-P Lube Spin-on</b> (8/87-1996) (2-90654-820-0)..... <b>B7124</b> <b>Fuel/Water Separator</b> (w/Drain) (15618-921)..... <b>BF5813 +</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (15618-921)..... <b>BF5813-O +</b>	<b>W7M</b> <b>F-F Lube</b> (1984-on) (1-13200-487-2)..... <b>B75</b> <b>B-P Lube Spin-on</b> (8/87-1996) (2-90654-820-0)..... <b>B7124</b> <b>Secondary Lube Ele.</b> (15525633)..... <b>C750-E +</b>
VPR301 w/E120 Eng. (1974-79) <b>F-F Lube</b> (9885132653)..... <b>PT466</b> <b>Fuel</b> (1132401910)..... <b>PF332</b> <b>I. Air</b> (6487136)..... <b>PA1893</b> <b>Single Air</b> (1142150051)..... <b>PA1884</b>		
VPR w/E120, E120T Eng. (1980-82) <b>F-F Lube</b> (9885132653)..... <b>PT466</b> <b>Fuel</b> (1132401910)..... <b>PF332</b> <b>I. Air</b> (6487136)..... <b>PA1893</b>		
VQR301 13.7I w/6RA1, 6RA1T, 6RB1 Eng. (3/82-84) <b>F-F Lube</b> (9885132653)..... <b>PT466</b> <b>Fuel</b> (1132401910)..... <b>PF332</b> <b>O. Air</b> (Horizontal Hsg.) (25096438)..... <b>PA2577</b> <b>I. Air</b> (Horizontal Hsg.) (25096436)..... <b>PA2578</b> <b>O. Air</b> (Vertical Hsg.) (Don. P182046)..... <b>LL1885 +</b> <b>I. Air</b> (Vertical Hsg.) (6487136)..... <b>PA1893</b>		
W4 w/Diesel Eng. <b>B-P Lube</b> (1986-91) (94360419).. <b>B222</b> <b>Dual-Flow Lube</b> (1992-98) (2-90654-600-0)..... <b>BD7166</b> <b>Dual-Flow Lube</b> (4HE1 Eng.) 1999-2004 (2-90654-800-0)..... <b>BD7169</b> <b>Dual-Flow Lube</b> (4HK1 Eng.) 2005-on (2-90654-800-0)..... <b>BD7169</b> <b>Fuel/Water Separator</b> (4HK1 Eng.) 2005-06 (8-94369-299-3).... <b>BF7534</b> <b>Fuel</b> (1986-98) (2-90654-910-0).... <b>BF7648</b> <b>Fuel</b> (4HE1 Eng.) 1999-2004 (2-90654-940-0)..... <b>BF7602</b> <b>Air</b> (1/86-3/86) (8-94156-052-0).... <b>PA2712</b> <b>Air</b> (Std. Chassis) 4/86-12/95 (8-94156-052-0)..... <b>PA2712</b> <b>Air</b> (Cab Chassis) 4/86-12/05 (8-94430-250-0)..... <b>PA2761</b> <b>Air</b> (Double Cab) 2006-07 (8-94430-250-0)..... <b>PA2761</b> <b>Radial Seal Air</b> (Single Cab) 2006-on (8-97062-294-0)..... <b>RS5434</b> <b>Radial Seal Air</b> (Double Cab) 2008-on (8-97062-294-0)..... <b>RS5434</b> <b>Trans. Spin-on</b> (1988-98) (2-90654-010-0)..... <b>B114</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

ISUZU Trucks (cont'd)	IVECO Buses (cont'd)	IVECO Buses (cont'd)
<b>W7M (Cont'd)</b> <b>Fuel/Water Separator (w/Drain)</b> (15618-921)..... <b>BF5813 +</b> <b>Fuel/Water Separator (Open End</b> for Bowl) (15618-921)..... <b>BF5813-O +</b> <b>Fuel (1984-2/2007)</b> (2-90654-940-0)..... <b>BF7602</b> <b>Fuel (03/07-on) (8-98037-011-0)...</b> <b>PF9919</b> <b>O. Air (1984-88) (1-14215-172-0).</b> <b>PA2779</b> <b>I. Air (1984-88) (1-14215-111-0)...</b> <b>PA2545</b> <b>Single Air (1989-94)</b> (1-14215-172-0)..... <b>PA2779</b> <b>Air (1995-96) (1-14215-181-0).....</b> <b>PA2577</b> <b>Air (6HE1 Eng.) 1997-98</b> (8-12386-667-0)..... <b>PA2577</b> <b>Radial Seal O. Air (6HK1 Eng.)</b> 1998-2002 (8-12471-801-0)..... <b>RS3548</b> <b>Radial Seal XP Air (6HK1 Eng.)</b> 1998-2002 (8-12471-801-0)..... <b>RS3548XP</b> <b>Single Radial Seal Air (6HK1</b> Eng.) 2003-on (8-12471-801-0).... <b>RS3548</b> <b>Single Radial Seal XP Air (6HK1</b> Eng.) 2003-on (8-12471-801-0).... <b>RS3548XP</b> <b>Trans. Spin-on (25011-122).....</b> <b>BT230 +</b>	<b>120L80, 120R80 w/Deutz F6L912 Eng.</b> <b>Lube (1160025)..... B236 +</b> <b>Fuel (1160243)..... BF988 +</b> <b>Air (2165049)..... PA2405</b> <hr/> <b>130R81 w/Deutz F6L913 Eng.</b> <b>Lube (1160025)..... B236 +</b> <b>Fuel/Water Separator..... BF1221 +</b> <b>Fuel (1160243)..... BF988 +</b> <b>O. Air (2165049)..... PA2405</b> <b>I. Air..... PA2835</b> <hr/> <b>150L10, 150R10, 150S10, 150S12 w/Deutz</b> <b>F6L312 Eng.</b> <b>134.9 mm Lube (1160024)..... BT292</b> <b>206.4 mm Lube (1160025)..... B236 +</b> <b>S. Fuel Ele. (1168398)..... PF950</b> <b>Hyd. (1267900)..... PT691</b> <hr/> <b>150L10, 150R10, 150S11N w/Deutz F6L714</b> <b>Eng.</b> <b>Fuel Ele. (1168398)..... PF950</b> <hr/> <b>150S12, 170L100, 170R100, 170S11H w/Deutz</b> <b>F6L413 Eng.</b> <b>Lube (1174421)..... B236 +</b> <b>P. Fuel Ele. (1168407)..... F950-F</b> <b>S. Fuel Ele. (1168398)..... PF950</b> <b>Fuel Spin-on..... BF988 +</b> <b>O. Air (2165049)..... PA2405</b> <b>I. Air..... PA2835</b> <b>Hyd. (1267900)..... PT691</b> <hr/> <b>170L100 w/Deutz F8L413 Eng.</b> <b>Lube..... B236 +</b> <b>Lube (1161934)..... B7031</b> <b>P. Fuel Ele. (1168407)..... F950-F</b> <b>S. Fuel Ele. (1168398)..... PF950</b> <b>Fuel Spin-on..... BF988 +</b> <b>349.3 mm O. Air (2165044)..... PA2845</b> <b>371.5 mm I. Air..... PA2835</b> <b>374.7 mm O. Air (2165049)..... PA2405</b> <b>Hyd. (1267900)..... PT691</b> <hr/> <b>170S11H, 170S11M w/Deutz F6L312 Eng.</b> <b>134.9 mm Lube (1160024)..... BT292</b> <b>206.4 mm Lube (1160025)..... B236 +</b> <b>P. Fuel Ele. (1168407)..... F950-F</b> <b>S. Fuel Ele. (1168398)..... PF950</b> <hr/> <b>200L100, 200L120 w/Deutz F6L413 Eng.</b> <b>134.9 mm Lube (1160024)..... BT292</b> <b>206.4 mm Lube (1160025)..... B236 +</b> <b>P. Fuel Ele. (1168407)..... F950-F</b> <b>S. Fuel Ele. (1168398)..... PF950</b> <b>Fuel Spin-on..... BF988 +</b> <b>371.5 mm Air..... PA2835</b> <b>374.7 mm Air (2165049)..... PA2405</b> <b>383.4 mm Air (2164590)..... PA2847</b> <b>Hyd. (1267900)..... PT691</b>	<b>200L100, 200L120, 200LS12, 200RS12 w/Deutz</b> <b>F8L413 Eng.</b> <b>168.3 mm Lube (1161934)..... B7031</b> <b>206.4 mm Lube..... B236 +</b> <b>P. Fuel Ele. (1168407)..... F950-F</b> <b>S. Fuel Ele. (1168398)..... PF950</b> <b>Fuel Spin-on..... BF988 +</b> <b>349.3 mm O. Air (2165044)..... PA2845</b> <b>371.5 mm I. Air (CA8305SY)..... PA2835</b> <b>374.7 mm O. Air (2165049)..... PA2405</b> <b>Hyd. (1267900)..... PT691</b> <hr/> <b>230L120 w/Deutz F8L413 Eng.</b> <b>168.3 mm Lube (1161934)..... B7031</b> <b>206.4 mm Lube..... B236 +</b> <b>P. Fuel Ele. (1168407)..... F950-F</b> <b>S. Fuel Ele. (1168398)..... PF950</b> <b>Fuel Spin-on..... BF988 +</b> <b>O. Air (2165049)..... PA2405</b> <b>I. Air (2241329)..... PA2835</b> <b>Single Air (2165044)..... PA2845</b> <b>Hyd. (1267900)..... PT691</b> <hr/> <b>M230L117 w/F8L413F Eng.</b> <b>Lube (1161934)..... B7031</b> <b>P. Fuel Ele. (1168407)..... F950-F</b> <b>S. Fuel Ele. (1168398)..... PF950</b> <b>Fuel Spin-on..... BF988 +</b> <b>349.3 mm O. Air (2165044)..... PA2845</b> <b>374.7 mm O. Air (2165049)..... PA2405</b> <b>371.5 mm I. Air..... PA2835</b> <b>295.3 mm Air (2168629)..... PA2891</b> <b>Hyd. (1267900)..... PT691</b> <hr/> <b>230L100, 230L120, 230R100 w/Deutz F6L413</b> <b>Eng.</b> <b>134.9 mm Lube (1160024)..... BT292</b> <b>206.4 mm Lube (1160025)..... B236 +</b> <b>Fuel Ele. (1168398)..... PF950</b> <b>Fuel Ele. (1168407)..... F950-F</b> <b>Fuel Spin-on..... BF988 +</b> <b>371.5 mm Air (2241329)..... PA2835</b> <b>374.7 mm Air (2165049)..... PA2405</b> <b>383.4 mm Air (2164590)..... PA2847</b> <b>Hyd. (1267900)..... PT691</b> <hr/> <b>230R120</b> <b>134.9 mm Lube (1160024)..... BT292</b> <b>168.3 mm Lube (1161934)..... B7031</b> <b>P. Fuel Ele. (1168403)..... F953-F</b> <b>S. Fuel (1160217)..... PF834</b> <hr/> <b>260L117P w/Deutz F8L413F Eng.</b> <b>Lube (1160025)..... B236 +</b> <b>Opt. Fuel/Water Separator..... BF1221 +</b> <b>Fuel (1160243)..... BF988 +</b> <b>O. Air (2165049)..... PA2405</b> <b>I. Air..... PA2835</b> <hr/> <b>306/2 Turbo</b> <b>Lube..... B2 +</b> <b>Lube (Upgrade)..... B2-HPG</b>
<b>W7T</b> <b>F-F Lube (1987-92)</b> (1-13200-487-2)..... <b>B75</b> <b>B-P Lube (6SA1-T Eng.) 1987-91</b> (1-13240-163-2)..... <b>B7577</b> <b>B-P Lube (6BG1-T Eng.)</b> 1990-92 (2-90654-820-0)..... <b>B7124</b> <b>Fuel (2-90654-940-0)..... BF7602</b> <b>O. Air (1987-10/88)</b> (1-14215-152-0)..... <b>PA2577</b> <b>I. Air (1987-10/88)</b> (1-14215-125-0)..... <b>PA2578</b> <b>Single Air (11/88-5/89)</b> (1-14215-181-0)..... <b>PA2577</b> <b>Air (6SA1-T Eng.) 1990-91</b> (1-14215-181-0)..... <b>PA2577</b> <b>Air (6BG1-T Eng.) 1992</b> (1-14215-172-0)..... <b>PA2779</b>	<b>170S11H, 170S11M w/Deutz F6L312 Eng.</b> <b>134.9 mm Lube (1160024)..... BT292</b> <b>206.4 mm Lube (1160025)..... B236 +</b> <b>P. Fuel Ele. (1168407)..... F950-F</b> <b>S. Fuel Ele. (1168398)..... PF950</b> <hr/> <b>200L100, 200L120 w/Deutz F6L413 Eng.</b> <b>134.9 mm Lube (1160024)..... BT292</b> <b>206.4 mm Lube (1160025)..... B236 +</b> <b>P. Fuel Ele. (1168407)..... F950-F</b> <b>S. Fuel Ele. (1168398)..... PF950</b> <hr/> <b>200L100, 200L120 w/Deutz F6L413 Eng.</b> <b>134.9 mm Lube (1160024)..... BT292</b> <b>206.4 mm Lube (1160025)..... B236 +</b> <b>P. Fuel Ele. (1168407)..... F950-F</b> <b>S. Fuel Ele. (1168398)..... PF950</b> <b>Fuel Spin-on..... BF988 +</b> <b>371.5 mm Air..... PA2835</b> <b>374.7 mm Air (2165049)..... PA2405</b> <b>383.4 mm Air (2164590)..... PA2847</b> <b>Hyd. (1267900)..... PT691</b>	
<b>WFR12 Van w/ZC1 Eng. (1989-91)</b> <b>Lube (8943142633)..... B1402 +</b> <b>Fuel (854619)..... BF836-K3</b> <b>Air (8942320590)..... PA3411-FN</b>		
<b>IVECO Buses</b> <b>10 EuroRider w/Cursor 10 Eng. (05/07-on)</b> <b>Radial Seal Air (A0040943704)...</b> <b>RS30305</b> <b>10 EuroRider w/F3AE3681A (Cursor 10) Eng.</b> (05/07-on) <b>Radial Seal Air (A0040943704)...</b> <b>RS30305</b> <hr/> <b>50A1</b> <b>Lube (1901603)..... BT347</b> <b>Can-Type Fuel (74621739)..... BF825 +</b>		

+ See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>IVECO Buses (cont'd)</b>	<b>IVECO Buses (cont'd)</b>	<b>IVECO Buses (cont'd)</b>
306/3.GM306 w/203H/61 Eng. F-F Lube Ele. (73104894)..... P20-HD +	370.24 w/8210 Eng. (Cont'd) I. Air..... PA2814	640RN, 640RNU, 642RN, 642R2 Lube Ele. (70759951)..... PT88-HD
308, 308L w/8200.12 Eng. Lube (4667339)..... BT349 Fuel (1909103)..... BF783 Air..... PA1884 +	370.26 w/8210.02, 8220.02 Eng. Lube (4667339)..... BT349 Fuel (1909103)..... BF783 Air (9933276)..... PA1885 +	666RN, 666RNU Lube (70759951)..... PT88-HD
309 Lube..... PT66-HD	370.30 w/8210.02, 8220.22 Eng. Lube (4667339)..... BT349 Fuel (74644293)..... BF783 419.1 mm Air (9933276)..... PA1885 + 342.9 mm Some Air..... PA1884 +	680RN, 680RNU, 682RN, 682RN2 Lube (70759951)..... PT88-HD
310 Lube Ele..... PT66-HD Lube Spin-on (4667339)..... BT349	370.35 Lube (4667339)..... BT349 Fuel (1909103)..... BF783 Air..... PA2776 Coolant (4734562)..... BW5137	A30.8, A35.8, A40.8, A40.10 w/8140 Eng. Lube (To 4/83)..... BT5 Can-Type Fuel..... BF825 + Fuel Spin-on..... BF587 Air (1902457)..... PA3836
314 Lube Ele. (4585298)..... P235	370S.10.24, 370S.12.24 w/8460.21 Eng. F-F Lube (1901919)..... B236 + Dual-Flow Lube (1903715)..... BD325 Fuel..... BF783 Air (1901925)..... PA2475	A40N Lube (4585298)..... P235
314/2, 314/3 w/8060.11, 8060.12 Eng. Lube (74027979)..... BT267 Can-Type Fuel (79918114)..... BF825 +	411 Lube (4636401)..... P20-HD +	A70.12 Lube (4600875)..... BT347 Fuel (1901607)..... BF7593
320 Air (9917419)..... PA1646-FN	414 Lube Ele. (4585298)..... P235	A135.17 w/8060.25 Eng. Dual-Flow Lube (1902076)..... BD232
329 w/CO 3/41 Eng. Lube (1901603)..... BT347 Fuel (1901607)..... BF7593	414A w/8200.12, 8210.12 Eng. Lube Ele. (74590074)..... P20-HD + Lube Spin-on (4667339)..... BT349 Fuel (1909103)..... BF783	Crealis CNG w/Cursor 8 CNG Eng. Lube Spin-on (99445200)..... B7174-MPG Radial Seal Air (5006254879)..... RS30062 Air Dryer (503137484)..... BA5379 Crankcase Breather (504209107)..... CV15002 Steering (42559501)..... P106-HD
331A w/8200.02 Eng. Lube (4667339)..... BT349 Fuel (1909103)..... BF783	416A w/806A Eng. Lube (74730587)..... BT267 Can-Type Fuel (74651986)..... BF825 +	Crealis w/Cursor 8 Eng. (Euro 4/5) Lube Spin-on (99445200)..... B7174-MPG Fuel/Water Separator (2992662)..... BF1365 Fuel Spin-on (Webasto Heater) (504113074)..... BF988 + Radial Seal Air (5006254879)..... RS30062 Air Dryer (503137484)..... BA5379 Crankcase Breather (To Eng. F2B145433) (504209107)..... CV15002 Crankcase Breather (Eng. F2B145434-up) (504153481)..... CV15002 Breather (Turbocharger) (2997535)..... BT9408 Trans. (ZF) (42535049)..... PT8385 Steering (42559501)..... P106-HD Urea (42553548)..... PE5270 Urea Oil/Air Separator (503139396)..... OAS98000
331.GM340, 331.GM350 w/220 Eng. Lube (73104894)..... P20-HD + Fuel (1909103)..... BF783	418A, 418AC, 418AL w/8200.12, 8210.12 Eng. Lube Ele. (74590074)..... P20-HD + Lube Spin-on (4667339)..... BT349 Fuel (1909103)..... BF783	Crossway 10.6M; 12M; 12.8M w/Cursor 8 Eng. (Euro 3) Lube Spin-on (99445200)..... B7174-MPG Fuel/Water Separator (2992662)..... BF1365 Air Dryer (5801382289)..... BA5379 Breather (Turbocharger) (2996238)..... BT9408 Crankcase Breather (504209107)..... CV15002 Steering (42559501)..... P106-HD Hyd. Spin-on (Hydrostatic) (5006143641)..... BT735
343, 343GT w/8200.12 Eng. Lube Ele. (74590074)..... P20-HD + Lube Spin-on (4667339)..... BT349 Fuel (1909103)..... BF783 Air (9921320)..... PA1884 +	421A, 421AL w/8200.12, 8210.12 Eng. Lube Ele. (74590074)..... P20-HD + Lube Spin-on (4667339)..... BT349 Fuel (1909103)..... BF783	
370.10.20 w/8210.02, 8220.22 Eng. Lube (4667339)..... BT349 Fuel (74644293)..... BF783 419.1 mm Air (9933276)..... PA1885 + 342.9 mm Some Air..... PA1884 +	470.20 w/8220.12 Eng. Lube (61671600)..... B236 + Fuel (1909103)..... BF783	
370.12.25 F-F Lube (4667339)..... BT349 Dual-Flow Lube (1902102)..... BD325 Fuel (74644293)..... BF783 Air..... PA2813	471.12.24 w/8220.32 Eng. Lube (1160025)..... B236 + Fuel (1160243)..... BF988 + Air (74980649)..... PA2475	
370.12.26 w/8210.02, 8220.22 Eng. Lube (4667339)..... BT349 Fuel (74644293)..... BF783 419.1 mm Air (9933276)..... PA1885 + 342.9 mm Some Air..... PA1884 +	570.20 w/8220.12 Eng. Lube (61671600)..... B236 + Fuel (1909103)..... BF783	
370.20 w/8210.02, 8220.02 Eng. Lube (4667339)..... BT349 Fuel (1909103)..... BF783 Air (9933276)..... PA1885 +	625N2P Lube (4600875)..... BT347 Can-Type Fuel (74651986)..... BF825 +	
370.24 w/8210 Eng. Lube (4667339)..... BT349 Fuel (74644293)..... BF783 O. Air..... PA2475		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IVECO Buses (cont'd)	IVECO Buses (cont'd)	IVECO Buses (cont'd)
Crossway 10.8M; 12M; 13M w/Cursor 9 Eng. (Euro 6) <b>Fuel/Water Separator</b> (5801620130)..... <b>BF1391-O</b> <b>Fuel Ele.</b> (5801439820)..... <b>PF46003</b> <b>Fuel Spin-on</b> (Webasto Heater) (504113074)..... <b>BF988 +</b> <b>Fuel Ele.</b> (Webasto Heater) (42545929)..... <b>PF7833</b> <b>Radial Seal Air</b> (42537392)..... <b>RS5508</b> <b>Air Dryer</b> (5801382289)..... <b>BA5379</b> <b>Steering</b> (42559501)..... <b>P106-HD</b> <b>Urea</b> (5801667204)..... <b>PE17000</b>	GM409 w/220H Eng. <b>Lube Ele.</b> (73104894)..... <b>P20-HD +</b> <b>Fuel</b> (1909103)..... <b>BF783</b> GM409A w/8200.12 Eng. <b>Lube</b> (4667339)..... <b>BT349</b> <b>Fuel</b> (1909103)..... <b>BF783</b> <b>Air</b> ..... <b>PA1884 +</b> GM410A w/310 H/61 Eng. <b>Lube Ele.</b> (73104894)..... <b>P20-HD +</b> GM420A w/8200.12, 8210.12 Eng. <b>Lube Ele.</b> (74590074)..... <b>P20-HD +</b> <b>Lube Spin-on</b> (4667339)..... <b>BT349</b> <b>Fuel</b> (1909103)..... <b>BF783</b> M2000/R106, M2000/R113, M2000/R119 w/F8L413F Eng. <b>Lube</b> (1160025)..... <b>B236 +</b> <b>Opt. Fuel/Water Separator</b> ..... <b>BF1221 +</b> <b>Fuel</b> (1160243)..... <b>BF988 +</b> <b>O. Air</b> (2165049)..... <b>PA2405</b> <b>I. Air</b> ..... <b>PA2835</b> Magelys w/Cursor 9 Eng. (Euro 6) <b>Fuel/Water Separator</b> (5801620130)..... <b>BF1391-O</b> <b>Fuel Ele.</b> (5801439820)..... <b>PF46003</b> <b>Fuel Spin-on</b> (Webasto Heater) (504113074)..... <b>BF988 +</b> <b>Radial Seal Air</b> (42537392)..... <b>RS5508</b> <b>Air Dryer</b> (5801382289)..... <b>BA5379</b> <b>Steering</b> (42559501)..... <b>P106-HD</b> <b>Urea</b> (5801667204)..... <b>PE17000</b>	Urbanway 10.5M w/Tector 7 286HP Eng. (Euro 6) <b>Lube Spin-on</b> (2992242)..... <b>BT7237</b> <b>Fuel/Water Separator</b> (42549295)..... <b>BF1292-O</b> <b>Fuel Spin-on</b> (504292579)..... <b>BF7922</b> <b>Fuel Spin-on</b> (Webasto Heater) (504113074)..... <b>BF988 +</b> <b>Fuel Ele.</b> (Webasto Heater) (42545929)..... <b>PF7833</b> <b>Radial Seal Air</b> (5801613591)..... <b>RS5534</b> <b>Air Dryer</b> (5801382289)..... <b>BA5379</b> <b>Steering</b> (42559501)..... <b>P106-HD</b> <b>Urea</b> (5801667204)..... <b>PE17000</b> Urbanway 10.5M w/Cursor 8 290HP CNG Eng. (Euro 6) <b>Lube Spin-on</b> (99445200)..... <b>B7174-MPG</b> <b>Channel Flow Primary Air</b> (42569259)..... <b>CA5788</b> <b>Channel Flow Secondary Air</b> (5801699114)..... <b>PA5515</b> <b>Cab Air</b> (504024890)..... <b>PA5336</b> <b>Air Dryer</b> (5801382289)..... <b>BA5379</b> <b>Crankcase Breather</b> (504209107)..... <b>CV15002</b> <b>Steering</b> (42559501)..... <b>P106-HD</b> Urbanway 12M w/Tector 7 286HP Eng. (Euro 6) <b>Lube Spin-on</b> (2992242)..... <b>BT7237</b> <b>Fuel/Water Separator</b> (42549295)..... <b>BF1292-O</b> <b>Fuel Spin-on</b> (504292579)..... <b>BF7922</b> <b>Channel Flow Primary Air</b> (5801699113)..... <b>CA5514</b> <b>Channel Flow Secondary Air</b> (5801699114)..... <b>PA5515</b> <b>Cab Air</b> (504024890)..... <b>PA5336</b> <b>Air Dryer</b> (5801382289)..... <b>BA5379</b> <b>Crankcase Breather</b> (504153151)..... <b>CV15006</b> <b>Steering</b> (42559501)..... <b>P106-HD</b> <b>Urea</b> (5801667204)..... <b>PE17000</b> Urbanway 12M w/Cursor 9 310HP Eng. (Euro 6) <b>Fuel/Water Separator</b> (5801620130)..... <b>BF1391-O</b> <b>Fuel Ele.</b> (5801439820)..... <b>PF46003</b> <b>Fuel Spin-on</b> (Webasto Heater) (504113074)..... <b>BF988 +</b> <b>Channel Flow Primary Air</b> (42569259)..... <b>CA5788</b> <b>Channel Flow Secondary Air</b> (5801699114)..... <b>PA5515</b> <b>Cab Air</b> (504024890)..... <b>PA5336</b> <b>Air Dryer</b> (5801382289)..... <b>BA5379</b> <b>Crankcase Breather</b> (504153151)..... <b>CV15006</b> <b>Steering</b> (42559501)..... <b>P106-HD</b> <b>Urea</b> (5801667204)..... <b>PE17000</b>
Crossway 10.8M; 12M; 13M w/Tector 7 Eng. (Euro 6) <b>Lube Spin-on</b> (2992242)..... <b>BT7237</b> <b>Fuel/Water Separator</b> (42549295)..... <b>BF1292-O</b> <b>Fuel Spin-on</b> (504292579)..... <b>BF7922</b> <b>Fuel Spin-on</b> (Webasto Heater) (504113074)..... <b>BF988 +</b> <b>Fuel Ele.</b> (Webasto Heater) (42545929)..... <b>PF7833</b> <b>Radial Seal Air</b> (5801613591)..... <b>RS5534</b> <b>Air Dryer</b> (5801382289)..... <b>BA5379</b> <b>Steering</b> (42559501)..... <b>P106-HD</b> <b>Urea</b> (5801667204)..... <b>PE17000</b>	Magelys w/Cursor 9 Eng. (Euro 6) <b>Fuel/Water Separator</b> (5801620130)..... <b>BF1391-O</b> <b>Fuel Ele.</b> (5801439820)..... <b>PF46003</b> <b>Fuel Spin-on</b> (Webasto Heater) (504113074)..... <b>BF988 +</b> <b>Radial Seal Air</b> (42537392)..... <b>RS5508</b> <b>Air Dryer</b> (5801382289)..... <b>BA5379</b> <b>Steering</b> (42559501)..... <b>P106-HD</b> <b>Urea</b> (5801667204)..... <b>PE17000</b> Magelys HD w/Cursor 10 Eng. (Euro 4/5) <b>Lube Spin-on</b> (2992544)..... <b>[2] B7174-MPG</b> <b>Fuel/Water Separator</b> (2992662)..... <b>BF1365</b> <b>Fuel Spin-on</b> (Webasto Heater) (504113074)..... <b>BF988 +</b> <b>Radial Seal Air</b> (42553413)..... <b>RS30305</b> <b>Air Dryer</b> (5801382289)..... <b>BA5379</b> <b>Crankcase Breather</b> (500383040)..... <b>CV15002</b> <b>Breather</b> (Turbocharger) (2996238)..... <b>BT9408</b> <b>Trans. (ZF)</b> (42563320)..... <b>PT8385</b> <b>Steering</b> (42559501)..... <b>P106-HD</b> <b>Urea</b> (42553548)..... <b>PE5270</b> Poker w/8220.22 Eng. <b>Lube</b> (4667339)..... <b>BT349</b> <b>Fuel</b> (74644293)..... <b>BF783</b> Pokerino w/8060.24 Eng. <b>Lube</b> (1901602)..... <b>BT348</b> <b>Can-Type Fuel</b> (1901687)..... <b>BF825 +</b> R81 (M2000) w/Deutz BF6L913 Eng. <b>Lube</b> ..... <b>B218</b> <b>Opt. Fuel/Water Separator</b> ..... <b>BF1221 +</b> <b>Can-Type Fuel</b> ..... <b>BF825 +</b> <b>Fuel Spin-on</b> (1160243)..... <b>BF988 +</b> <b>O. Air</b> ..... <b>PA2405</b> <b>I. Air</b> ..... <b>PA2835</b>	
Evadys w/Cursor 9 400HP Eng. (Euro 6) <b>Fuel/Water Separator</b> (5801620130)..... <b>BF1391-O</b> <b>Fuel Ele.</b> (5801439820)..... <b>PF46003</b> <b>Fuel Ele.</b> (Webasto Heater) (42545929)..... <b>PF7833</b> <b>Radial Seal Air</b> (42537392)..... <b>RS5508</b> <b>Air Dryer</b> (500055322)..... <b>BA5379</b> <b>Steering</b> (42559501)..... <b>P106-HD</b> <b>Urea</b> (5801667204)..... <b>PE17000</b>		
H12 w/Cursor 10 Eng. (09/04-on) <b>Radial Seal Air</b> (A0040943704)..... <b>RS30305</b>		
H12 w/Cursor 8 Eng. (03/04-on) <b>Radial Seal Air</b> (A0040943704)..... <b>RS30305</b>		
H12.8 w/Cursor 8 Eng. (03/04-on) <b>Radial Seal Air</b> (A0040943704)..... <b>RS30305</b>		
HD12 w/Cursor 10 (Euro 4) Eng. (09/06-on) <b>Radial Seal Air</b> (A0040943704)..... <b>RS30305</b>		
HD12 w/Cursor 10 Eng. (09/04-on) <b>Radial Seal Air</b> (A0040943704)..... <b>RS30305</b>		
GM309 w/220H Eng. <b>Lube Ele.</b> (73104894)..... <b>P20-HD +</b> <b>Fuel</b> (1909103)..... <b>BF783</b>		
GM309A w/8200.12 Eng. <b>Lube</b> (4667339)..... <b>BT349</b> <b>Fuel</b> (1909103)..... <b>BF783</b> <b>Air</b> ..... <b>PA1884 +</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IVECO Buses (cont'd)	IVECO Buses (cont'd)	IVECO Engines (cont'd)
Urbanway 12M w/Cursor 9 360HP Eng. (Euro 6) <b>Fuel/Water Separator</b> (5801620130)..... <b>BF1391-O</b> <b>Fuel Ele.</b> (5801439820)..... <b>PF46003</b> <b>Fuel Spin-on</b> (Webasto Heater) (504113074)..... <b>BF988 +</b> <b>Channel Flow Primary Air</b> (42569259)..... <b>CA5788</b> <b>Channel Flow Secondary Air</b> (5801699114)..... <b>PA5515</b> <b>Cab Air</b> (504024890)..... <b>PA5336</b> <b>Steering</b> (42559501)..... <b>P106-HD</b> <b>Urea</b> (5801667204)..... <b>PE17000</b>	Urbanway 18M w/Cursor 8 330HP CNG Eng. (Euro 6) (Cont'd) <b>Cab Air</b> (504024890)..... <b>PA5336</b> <b>Air Dryer</b> (5801382289)..... <b>BA5379</b> <b>Crankcase Breather</b> (504209107)..... <b>CV15002</b> <b>Steering</b> (42559501)..... <b>P106-HD</b>	8065.1 <b>Can-Type Fuel</b> ..... <b>BF825 +</b>
Urbanway 12M w/Cursor 8 290HP CNG Eng. (Euro 6) <b>Lube Spin-on</b> (99445200)..... <b>B7174-MPG</b> <b>Channel Flow Primary Air</b> (42569259)..... <b>CA5788</b> <b>Channel Flow Secondary Air</b> (5801699114)..... <b>PA5515</b> <b>Cab Air</b> (504024890)..... <b>PA5336</b> <b>Air Dryer</b> (5801382289)..... <b>BA5379</b> <b>Crankcase Breather</b> (504209107)..... <b>CV15002</b> <b>Steering</b> (42559501)..... <b>P106-HD</b>	<b>IVECO Engines</b> 203A/61, 309, 364A/58, 364A/60 VAR., 610.206, 610.207 <b>227.0 mm Lube</b> (Don. P550485).. <b>PT88-HD</b> <b>228.6 mm Lube</b> (Don. P550165).. <b>PT66-HD</b>	8065U <b>Lube</b> (1907567)..... <b>[2] BT348</b> <b>Fuel Spin-on</b> (1902138)..... <b>[2] BF5587-D</b>
Urbanway 18M w/Cursor 9 360HP Eng. (Euro 6) <b>Fuel/Water Separator</b> (5801620130)..... <b>BF1391-O</b> <b>Fuel Ele.</b> (5801439820)..... <b>PF46003</b> <b>Fuel Spin-on</b> (Webasto Heater) (504113074)..... <b>BF988 +</b> <b>Channel Flow Primary Air</b> (42569259)..... <b>CA5788</b> <b>Channel Flow Secondary Air</b> (5801699114)..... <b>PA5515</b> <b>Cab Air</b> (504024890)..... <b>PA5336</b> <b>Steering</b> (42559501)..... <b>P106-HD</b> <b>Urea</b> (5801667204)..... <b>PE17000</b>	804AM, 804M <b>Lube</b> ..... <b>BT347</b> <b>Can-Type Fuel</b> ..... <b>BF825 +</b>	8065.25, 8140.21, 8140.27 <b>Dual-Flow Lube</b> (1902076)..... <b>BD232</b>
Urbanway 18M w/Cursor 9 400HP Eng. (Euro 6) <b>Fuel/Water Separator</b> (5801620130)..... <b>BF1391-O</b> <b>Fuel Ele.</b> (5801439820)..... <b>PF46003</b> <b>Fuel Spin-on</b> (Webasto Heater) (504113074)..... <b>BF988 +</b> <b>Channel Flow Primary Air</b> (42569259)..... <b>CA5788</b> <b>Channel Flow Secondary Air</b> (5801699114)..... <b>PA5515</b> <b>Cab Air</b> (504024890)..... <b>PA5336</b> <b>Steering</b> (42559501)..... <b>P106-HD</b> <b>Urea</b> (5801667204)..... <b>PE17000</b>	806AM <b>Can-Type Fuel</b> ..... <b>BF825 +</b>	8200.02 <b>Lube</b> (1901604)..... <b>BT349</b> <b>Fuel Spin-on</b> (1901605)..... <b>BF783</b>
Urbanway 18M w/Cursor 8 330HP CNG Eng. (Euro 6) <b>Lube Spin-on</b> (99445200)..... <b>B7174-MPG</b> <b>Channel Flow Primary Air</b> (42569259)..... <b>CA5788</b> <b>Channel Flow Secondary Air</b> (5801699114)..... <b>PA5515</b>	820, 820-1, 820M <b>Lube</b> ..... <b>BT349</b>	8200.03 <b>Fuel Spin-on</b> (1901605)..... <b>BF783</b>
	821 <b>Lube</b> (78826586)..... <b>BT349</b> <b>Fuel Spin-on</b> (1909103)..... <b>BF783</b>	8200.12 <b>Lube</b> (1901604)..... <b>BT349</b> <b>Fuel Spin-on</b> (1901605)..... <b>BF783</b>
	821M, 821SM, 821SR1, 822, 822M <b>Lube</b> ..... <b>BT349</b>	8201V, 8210 <b>Lube</b> (1901604)..... <b>BT349</b>
	828 <b>Lube</b> (78826586)..... <b>BT349</b> <b>Fuel Spin-on</b> (1909103)..... <b>BF783</b>	8210 Series <b>Dual-Flow Lube</b> (1907582)..... <b>BD232</b> <b>Fuel/Water Separator</b> (1908547)..... <b>BF1217</b> <b>Fuel</b> (Mann WK842/2)..... <b>BF5587-D</b>
	828SM <b>Lube</b> ..... <b>BT349</b>	8220 (Unic X200), 8220 <b>Lube</b> (1901604)..... <b>BT349</b>
	8035, 8035-1, 8035M, 8040, 8045-1 <b>Lube</b> ..... <b>BT347</b> <b>Can-Type Fuel</b> ..... <b>BF825 +</b>	8220.02 <b>Lube</b> (1901604)..... <b>BT349</b> <b>Fuel Spin-on</b> (1901605)..... <b>BF783</b> <b>Coolant</b> ..... <b>BW5137</b>
	8040 Series <b>Dual-Flow Lube</b> (1907582)..... <b>BD232</b> <b>Fuel/Water Separator</b> (1908547)..... <b>BF1217</b> <b>Fuel</b> (Mann WK842/2)..... <b>BF5587-D</b>	8220.12, 8220.32 <b>Lube</b> (1902135)..... <b>BT292</b> <b>Coolant</b> ..... <b>BW5137</b>
	8041M, 8041SM <b>Lube</b> (1901603)..... <b>BT347</b>	8220.20, 8220.22 <b>Fuel Spin-on</b> ..... <b>BF783</b> <b>Coolant</b> ..... <b>BW5137</b>
	8045E (3.9L) <b>Lube</b> (1907567)..... <b>BT348</b> <b>Fuel</b> (1902138)..... <b>BF5587-D</b>	8260.02 <b>Lube</b> (1901604)..... <b>BT349</b> <b>Fuel Spin-on</b> (1901605)..... <b>BF783</b> <b>Coolant</b> ..... <b>BW5137</b>
	8060 Series <b>Dual-Flow Lube</b> (1907582)..... <b>BD232</b> <b>Fuel/Water Separator</b> (1908547)..... <b>BF1217</b> <b>Fuel</b> (Mann WK842/2)..... <b>BF5587-D</b>	8260I <b>Lube</b> (1901604)..... <b>BT349</b>
	8061M, 8062.04 <b>Lube</b> (1901602)..... <b>[2] BT348</b>	8280 Series <b>Dual-Flow Lube</b> (1907571)..... <b>BD7168</b> <b>Fuel/Water Separator</b> (1908547)..... <b>BF1217</b> <b>Fuel</b> ..... <b>BF7663</b> <b>Coolant</b> (1901776)..... <b>BW5143</b>
		8280.22 (17.2L) <b>Fuel Spin-on</b> ..... <b>BF783</b> <b>Coolant</b> ..... <b>BW5137</b>
		8282.22 <b>100.8 mm Fuel Spin-on</b> (1901607)..... <b>BF7593</b> <b>186.5 mm Fuel Spin-on</b> ..... <b>BF783</b> <b>Coolant</b> ..... <b>BW5137</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).


IVECO Engines (cont'd)	IVECO Engines (cont'd)	IVECO European Light Duty Vehicles (cont'd)
8340 Lube..... BT347 Fuel Spin-on (1901607)..... BF7593	Cursor 8 Series Lube..... B7174-MPG Fuel/Water Separator..... BF1217 Fuel/Water Separator..... BF1365 Fuel..... BF7927 Fuel..... BF7696 Breather (500339085)..... BT9408	Daily III 40-10 Turbo w/8140:23:00 Eng. (05/96-08/99) Dual-Flow Lube (1902047)..... BD232 Fuel (1902138)..... BF5587-D 336.6 mm Air (1904581)..... PA2767 Cab Air (3802821)..... PA5475
8360 Series Dual-Flow Lube (1907571)..... BD7168 Fuel/Water Separator (1908547)..... BF1217 Fuel..... BF7663 Some Coolant (1901776)..... BW5143	Cursor 10 Series Lube..... B7174-MPG Fuel/Water Separator (1908547)..... BF1217 Fuel/Water Separator..... BF1365 Fuel..... BF7696 Fuel..... BF7927 Breather (500339085)..... BT9408	Daily III 40-12 Turbo w/8140:43:00 Eng. (05/96-08/99) Dual-Flow Lube (1902047)..... BD232 Fuel (1902138)..... BF5587-D 336.6 mm Air (1904581)..... PA2767 Cab Air (3802821)..... PA5475
8460 Series Dual-Flow Lube (1907584)..... BD325 Fuel/Water Separator (1908547)..... BF1217 Fuel..... BF7663 Coolant (1901776)..... BW5143	Cursor 13 Series Lube..... B7174-MPG Fuel/Water Separator..... BF1217 Fuel..... BF7927 Breather (500339085)..... BT9408	Daily III 45-10 Turbo w/8140:23:00 Eng. (05/96-08/99) Dual-Flow Lube (1902047)..... BD232 Fuel (1902138)..... BF5587-D 336.6 mm Air (1904581)..... PA2767 Cab Air (3802821)..... PA5475
8630.04 Lube (1901604)..... BT349 Fuel Spin-on..... BF783 Coolant..... BW5137	Cursor E06 Series Lube..... B7174-MPG Fuel/Water Separator..... BF1217 Fuel..... BF7927 Fuel..... BF7696	Daily III 45-12 Turbo w/8140:43:00 Eng. (05/96-08/99) Dual-Flow Lube (1902047)..... BD232 Fuel (1902138)..... BF5587-D 336.6 mm Air (1904581)..... PA2767 Cab Air (3802821)..... PA5475
8640.41 Fuel Spin-on (1901605)..... BF783 Coolant..... BW5137	M63S Fuel..... BF797 Coolant..... BW5137	Daily III 49-10 Turbo w/8140:23:00 Eng. (05/96-08/99) Dual-Flow Lube (1902047)..... BD232 Fuel (1902138)..... BF5587-D 336.6 mm Air (1904581)..... PA2767 Cab Air (3802821)..... PA5475
9020, 9026.13, 9026.14 O. Air (Don. P181088)..... PA2845	X200 Lube..... BT292	Daily III 49-12 Turbo w/8140:43:00 Eng. (05/96-08/99) Dual-Flow Lube (1902047)..... BD232 Fuel (1902138)..... BF5587-D 336.6 mm Air (1904581)..... PA2767 Cab Air (3802821)..... PA5475
9100.1, 9103, 9103.1, 9103.5, 9103.6, 9103.7, 9104, 9105 381.0 mm O. Air (Don. P771508)..... PA2474 374.7 mm O. Air (Don. P771561)..... PA2405 I. Air (Don. P776695)..... PA2835	<b>IVECO</b> <b>European Light Duty Vehicles</b>	Daily III 30-8 w/8140.67 Eng. (05/96-08/99) Dual-Flow Lube (1902047)..... BD232 Fuel (1902138)..... BF5587-D
9105.10, 9105.11, 9105.12 O. Air (Don. P771561)..... PA2405 I. Air (Don. P776695)..... PA2835	Daily III 35-8 w/8140.63 Eng. (04/98-08/99) Dual-Flow Lube (1902047)..... BD232 Fuel (1902138)..... BF5587-D Cab Air (3802821)..... PA5475	Daily III 35-10 Turbo w/8140:23:00 Eng. (05/96-08/99) Dual-Flow Lube (1902047)..... BD232 Fuel (1902138)..... BF5587-D 336.6 mm Air (1904581)..... PA2767
9105.14, 9105.15, 9105.18, 9105.19, 9105.44, 9105.45 O. Air (Don. P771561)..... PA2405	Daily III 35-10 V Turbo w/8140.47R Eng. (05/96-08/99) Dual-Flow Lube (1902047)..... BD232 Fuel (1902138)..... BF5587-D 336.6 mm Air (1904581)..... PA2767 Cab Air (3802821)..... PA5475	Daily III 59-12 Turbo w/8140:43:00 Eng. (05/96-08/99) Dual-Flow Lube (1902047)..... BD232 Fuel (1902138)..... BF5587-D 336.6 mm Air (1904581)..... PA2767 Cab Air (3802821)..... PA5475
9156, 9156.3, 9156.8, 9156.9, 9156.11, 9157 O. Air (Don. P181137)..... PA2475 I. Air (Don. P776697)..... PA2814	Daily III 35-12 Turbo w/8140:43:00 Eng. (05/96-08/99) Dual-Flow Lube (1902047)..... BD232 Fuel (1902138)..... BF5587-D 336.6 mm Air (1904581)..... PA2767 Cab Air (3802821)..... PA5475	Daily IV 29-9 w/8140.63 Eng. (07/01-12/01) Dual-Flow Lube (1902047)..... BD232 Fuel (2992300)..... BF7970 Radial Seal Air (151849148)..... RS3544
C02D/45 VAR. 1, C02D/55 VAR. 20, C02D/60 VAR. 1, C02D/60 VAR. 10 F-F Lube Spin-on (1968-on)..... BT347		Daily IV 29-9 w/8140.63 Eng. (07/99-06/01) Dual-Flow Lube (1902047)..... BD232 Fuel (1902138)..... BF5587-D Radial Seal Air (151849148)..... RS3544
C03, C03 VAR. 4&5, C03/41, C03 VAR. 100, C03C, C03M Lube..... BT347		Daily IV 29-9 Turbo w/8140:43:00 Eng. (09/01-12/02) Dual-Flow Lube (1902047)..... BD232 Fuel (2992300)..... BF7970 Radial Seal Air (151849148)..... RS3544
C03D VAR. 20, C04D B-P Lube..... B50 *		
C0 VAR. 21, C031 Lube..... BT347		
Cursor 8 (7.8L) Lube (99445200)..... B7174-MPG Fuel (99484067)..... BF7696		

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IVECO European Light Duty Vehicles (cont'd)	IVECO European Light Duty Vehicles (cont'd)	IVECO European Light Duty Vehicles (cont'd)
Daily IV 29-10 Turbo (2.3 HPI) w/F1A Eng. (09/02-on) Lube (2992188)..... <b>B7377</b> Fuel (2992300)..... <b>BF7970</b> Radial Seal Air (151849148)..... <b>RS3544</b>	Daily IV 35-11 Turbo w/8140:43:00 Eng. (07/01-12/02) Dual-Flow Lube (1902047)..... <b>BD232</b> Fuel (2992300)..... <b>BF7970</b> Radial Seal Air (151849148)..... <b>RS3544</b>	Daily IV 40-9 Turbo w/8140:43:00 Eng. (09/01-12/02) Dual-Flow Lube (1902047)..... <b>BD232</b> Fuel (2992300)..... <b>BF7970</b> Radial Seal Air (151849148)..... <b>RS3544</b>
Daily IV 29-11 Turbo w/8140.43C Eng. (07/01-12/02) Dual-Flow Lube (1902047)..... <b>BD232</b> Fuel (2992300)..... <b>BF7970</b> Radial Seal Air (151849148)..... <b>RS3544</b>	Daily IV 35-11 Turbo w/8140:43:00 Eng. (07/99-06/01) Dual-Flow Lube (1902047)..... <b>BD232</b> Fuel (1902138)..... <b>BF5587-D</b> Radial Seal Air (151849148)..... <b>RS3544</b>	Daily IV 40-11 Turbo w/8140.43C Eng. (07/01-12/02) Dual-Flow Lube (1902047)..... <b>BD232</b> Fuel (2992300)..... <b>BF7970</b> Radial Seal Air (151849148)..... <b>RS3544</b>
Daily IV 29-11 Turbo w/8140.43C Eng. (07/99-06/01) Dual-Flow Lube (1902047)..... <b>BD232</b> Fuel (1902138)..... <b>BF5587-D</b> Radial Seal Air (151849148)..... <b>RS3544</b>	Daily IV 35-12 turbo (2.3 HPI) w/F1A Eng. (09/02-on) Lube (2992188)..... <b>B7377</b> Fuel (2992300)..... <b>BF7970</b> Radial Seal Air (151849148)..... <b>RS3544</b>	Daily IV 40-11 Turbo w/8140.43C Eng. (07/99-06/01) Dual-Flow Lube (1902047)..... <b>BD232</b> Fuel (1902138)..... <b>BF5587-D</b> Radial Seal Air (151849148)..... <b>RS3544</b>
Daily IV 29-12 Turbo (2.3 HPI) w/F1A Eng. (09/02-on) Lube (2992188)..... <b>B7377</b> Fuel (2992300)..... <b>BF7970</b> Radial Seal Air (151849148)..... <b>RS3544</b>	Daily IV 35-13 Turbo w/8140.43S Eng. (07/01-on) Dual-Flow Lube (1902047)..... <b>BD232</b> Fuel (2992300)..... <b>BF7970</b> Radial Seal Air (151849148)..... <b>RS3544</b>	Daily IV 45-13 Turbo w/8140.43SEDC Eng. (07/01-on) Dual-Flow Lube (1902047)..... <b>BD232</b> Fuel (2992300)..... <b>BF7970</b> Radial Seal Air (151849148)..... <b>RS3544</b>
Daily IV 29-13 Turbo w/8140.43SEDC Eng. (07/01-on) Dual-Flow Lube (1902047)..... <b>BD232</b> Fuel (2992300)..... <b>BF7970</b> Radial Seal Air (151849148)..... <b>RS3544</b>	Daily IV 35-13 Turbo w/8140.43S Eng. (07/99-06/01) Dual-Flow Lube (1902047)..... <b>BD232</b> Fuel (1902138)..... <b>BF5587-D</b> Radial Seal Air (151849148)..... <b>RS3544</b>	Daily IV 45-13 Turbo w/8140.43SEDC Eng. (07/99-06/01) Dual-Flow Lube (1902047)..... <b>BD232</b> Fuel (1902138)..... <b>BF5587-D</b> Radial Seal Air (151849148)..... <b>RS3544</b>
Daily IV 29-13 Turbo w/8140.43SEDC Eng. (07/99-06/01) Dual-Flow Lube (1902047)..... <b>BD232</b> Fuel (1902138)..... <b>BF5587-D</b> Radial Seal Air (151849148)..... <b>RS3544</b>	Daily IV 35-14 Turbo (2.3 HPT) w/F1A Eng. (04/05-on) Lube (2992188)..... <b>B7377</b> Fuel (2992300)..... <b>BF7970</b> Radial Seal Air (151849148)..... <b>RS3544</b> Steering (2966261)..... <b>P106-HD</b>	Daily IV 49-11 Turbo w/8140.43C Eng. (07/01-12/02) Dual-Flow Lube (1902047)..... <b>BD232</b> Fuel (2992300)..... <b>BF7970</b> Radial Seal Air (151849148)..... <b>RS3544</b>
Daily IV 29-14 Turbo (2.3 HPT) w/F1A Eng. (04/05-on) Lube (2992188)..... <b>B7377</b> Fuel (2992300)..... <b>BF7970</b> Radial Seal Air (151849148)..... <b>RS3544</b>	Daily IV 35-14 Turbo (3.0 HPI) w/136 HP Eng. (09/04-on) Lube (2995561)..... <b>B7376</b> Fuel (2992300)..... <b>BF7970</b> Radial Seal Air (151849148)..... <b>RS3544</b> Steering (2966261)..... <b>P106-HD</b>	Daily IV 49-11 Turbo w/8140.43C Eng. (07/99-06/01) Dual-Flow Lube (1902047)..... <b>BD232</b> Fuel (1902138)..... <b>BF5587-D</b> Radial Seal Air (151849148)..... <b>RS3544</b>
Daily IV 35-9 w/8140.63 Eng. (07/01-12/01) Dual-Flow Lube (1902047)..... <b>BD232</b> Fuel (2992300)..... <b>BF7970</b> Radial Seal Air (151849148)..... <b>RS3544</b>	Daily IV 35-15 Turbo w/8140.43N Eng. (09/01-on) Dual-Flow Lube (1902047)..... <b>BD232</b> Fuel (2992300)..... <b>BF7970</b> Radial Seal Air (151849148)..... <b>RS3544</b>	Daily IV 49-13 Turbo w/8140.43SEDC Eng. (07/01-on) Dual-Flow Lube (1902047)..... <b>BD232</b> Fuel (2992300)..... <b>BF7970</b> Radial Seal Air (151849148)..... <b>RS3544</b>
Daily IV 35-9 w/8140.63 Eng. (07/99-06/01) Dual-Flow Lube (1902047)..... <b>BD232</b> Fuel (1902138)..... <b>BF5587-D</b> Radial Seal Air (151849148)..... <b>RS3544</b>	Daily IV 35-17 Turbo (3.0 HPT) w/166 HP Eng. (09/04-on) Lube (2995561)..... <b>B7376</b> Fuel (2992300)..... <b>BF7970</b> Radial Seal Air (151849148)..... <b>RS3544</b>	Daily IV 49-13 Turbo w/8140.43SEDC Eng. (07/99-06/01) Dual-Flow Lube (1902047)..... <b>BD232</b> Fuel (2992300)..... <b>BF7970</b> Radial Seal Air (151849148)..... <b>RS3544</b>
Daily IV 35-9 Turbo w/8140:43:00 Eng. (09/01-12/02) Dual-Flow Lube (1902047)..... <b>BD232</b> Fuel (2992300)..... <b>BF7970</b> Radial Seal Air (151849148)..... <b>RS3544</b>	Daily IV 40-9 w/8140.63 Eng. (07/01-12/01) Dual-Flow Lube (1902047)..... <b>BD232</b> Fuel (2992300)..... <b>BF7970</b> Radial Seal Air (151849148)..... <b>RS3544</b>	Daily IV 50-11 Turbo w/8140.43C Eng. (07/01-12/02) Dual-Flow Lube (1902047)..... <b>BD232</b> Fuel (2992300)..... <b>BF7970</b> Radial Seal Air (151849148)..... <b>RS3544</b>
Daily IV 35-10 Turbo (2.3 HPI) w/F1A Eng. (09/02-on) Lube (2992188)..... <b>B7377</b> Fuel (2992300)..... <b>BF7970</b> Radial Seal Air (151849148)..... <b>RS3544</b>	Daily IV 40-9 w/8140.63 Eng. (07/99-06/01) Dual-Flow Lube (1902047)..... <b>BD232</b> Fuel (1902138)..... <b>BF5587-D</b> Radial Seal Air (151849148)..... <b>RS3544</b>	Daily IV 50-11 Turbo w/8140.43C Eng. (11/99-06/01) Dual-Flow Lube (1902047)..... <b>BD232</b> Fuel (1902138)..... <b>BF5587-D</b> Radial Seal Air (151849148)..... <b>RS3544</b>

Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).




<b>IVECO</b> <b>European Light Duty Vehicles (cont'd)</b>	<b>IVECO</b> <b>European Light Duty Vehicles (cont'd)</b>	<b>IVECO</b> <b>European Light Duty Vehicles (cont'd)</b>
Daily IV 50-13 Turbo w/8140.43SEDC Eng. (07/01-on)	Daily IV 65-15 Turbo w/8140.43N Eng. (07/01-on) (Cont'd)	Daily V 35C,11 (2.3 HPI) w/F1AE0481UA Eng. (09/09-on) (Cont'd)
Dual-Flow Lube (1902047)..... <b>BD232</b>	Radial Seal Air (151849148)..... <b>RS3544</b>	Radial Seal Air (To 09/11) (2992677)..... <b>RS3544</b>
Fuel (2992300)..... <b>BF7970</b>	Daily IV 65-15 Turbo w/8140.43N Eng. (09/00-06/01)	Cabin Air (w/o Charcoal) (3802821)..... <b>PA5475</b>
Radial Seal Air (151849148)..... <b>RS3544</b>	Dual-Flow Lube (1902047)..... <b>BD232</b>	Daily V 35C.11 w/FPT 2.3 CRD Eng. (07/06-on)
Daily IV 50-13 Turbo w/8140.43SEDC Eng. (11/99-06/01)	Fuel (1902138)..... <b>BF5587-D</b>	Lube (2995811)..... <b>B7496</b>
Dual-Flow Lube (1902047)..... <b>BD232</b>	Radial Seal Air (151849148)..... <b>RS3544</b>	Fuel (504170771)..... <b>PF9865</b>
Fuel (1902138)..... <b>BF5587-D</b>	Daily IV 65-17 Turbo (3.0 HPT) w/166 HP Eng. (09/04-on)	Radial Seal Air (1903669)..... <b>RS3544</b>
Radial Seal Air (151849148)..... <b>RS3544</b>	Lube (2995561)..... <b>B7376</b>	Cabin Air (3802821)..... <b>PA5475</b>
Daily IV 50-14 Turbo (3.0 HPI) w/136 HP Eng. (09/04-on)	Fuel (2992300)..... <b>BF7970</b>	Daily V 35C,13 (2.3 HPI) w/F1AE0481VA Eng. (09/09-on)
Lube (2995561)..... <b>B7376</b>	Radial Seal Air (151849148)..... <b>RS3544</b>	Lube (504091563)..... <b>B7496</b>
Fuel (2992300)..... <b>BF7970</b>	Daily V 29L.10 w/FPT 2.3 CRD Eng. (07/06-on)	Fuel (504170771)..... <b>PF9865</b>
Radial Seal Air (151849148)..... <b>RS3544</b>	Lube (2995811)..... <b>B7496</b>	Radial Seal Air (To 09/11) (2992677)..... <b>RS3544</b>
Daily IV 50-15 Turbo w/8140.43N Eng. (09/01-on)	Fuel (504170771)..... <b>PF9865</b>	Cabin Air (w/o Charcoal) (3802821)..... <b>PA5475</b>
Dual-Flow Lube (1902047)..... <b>BD232</b>	Radial Seal Air (To 09/14) (1903669)..... <b>RS3544</b>	Daily V 35C.13 w/FPT 2.3 CRD Eng. (07/06-on)
Fuel (2992300)..... <b>BF7970</b>	Cabin Air (w/o Charcoal) (3802821)..... <b>PA5475</b>	Lube (2995811)..... <b>B7496</b>
Radial Seal Air (151849148)..... <b>RS3544</b>	Daily V 29L 11 w/F1AE348IAA Eng. (10/1-on)	Fuel (504170771)..... <b>PF9865</b>
Steering (2966261)..... <b>P106-HD</b>	Lube (504091563)..... <b>B7496</b>	Radial Seal Air (1903669)..... <b>RS3544</b>
Daily IV 50-17 Turbo (3.0 HPT) w/166 HP Eng. (09/04-on)	Fuel (504170771)..... <b>PF9865</b>	Cabin Air (3802821)..... <b>PA5475</b>
Lube (2995561)..... <b>B7376</b>	Cabin Air (w/o Charcoal) (3802821)..... <b>PA5475</b>	Daily V 35C14 w/3.0 HPI EEV Eng.
Fuel (2992300)..... <b>BF7970</b>	Daily V 29L.12 w/FPT 2.3 CRD Eng. (07/06-on)	Lube (2995655)..... <b>B7388</b>
Radial Seal Air (151849148)..... <b>RS3544</b>	Lube (2995811)..... <b>B7496</b>	Radial Seal Air (2992677)..... <b>RS3544</b>
Daily IV 59-13 Turbo w/8140.43SEDC Eng. (07/01-on)	Fuel (504170771)..... <b>PF9865</b>	Cabin Air (w/o Charcoal) (3802821)..... <b>PA5475</b>
Dual-Flow Lube (1902047)..... <b>BD232</b>	Radial Seal Air (To 09/11) (2992677)..... <b>RS3544</b>	Daily V 35C.15 w/FPT 3.0 CRD Eng. (07/06-on)
Fuel (2992300)..... <b>BF7970</b>	Cabin Air (w/o Charcoal) (3802821)..... <b>PA5475</b>	Lube (2995655)..... <b>B7388</b>
Radial Seal Air (151849148)..... <b>RS3544</b>	Daily V 29L13 (2.3 Multijet III) w/F1AE348IBA Eng. (10/11-on)	Fuel (504170771)..... <b>PF9865</b>
Daily IV 59-13 Turbo w/8140.43SEDC Eng. (07/99-06/01)	Lube (504091563)..... <b>B7496</b>	Radial Seal Air (2992677)..... <b>RS3544</b>
Dual-Flow Lube (1902047)..... <b>BD232</b>	Fuel (504170771)..... <b>PF9865</b>	Cabin Air (w/o Charcoal) (3802821)..... <b>PA5475</b>
Fuel (1902138)..... <b>BF5587-D</b>	Cabin Air (w/o Charcoal) (3802821)..... <b>PA5475</b>	Daily V 35C,17 (3.0 HPT EEV) w/F1CE3481CC Eng. (09/06-on)
Radial Seal Air (151849148)..... <b>RS3544</b>	Daily V 29L.14 w/FPT 2.3 VGT Eng. (07/06-on)	Lube (2995655)..... <b>B7388</b>
Daily IV 60-15 Turbo w/8140.43N Eng. (07/01-on)	Lube (2995811)..... <b>B7496</b>	Fuel (504170771)..... <b>PF9865</b>
Dual-Flow Lube (1902047)..... <b>BD232</b>	Fuel (504170771)..... <b>PF9865</b>	Radial Seal Air (2992677)..... <b>RS3544</b>
Fuel (2992300)..... <b>BF7970</b>	Radial Seal Air (To 09/11) (1903669)..... <b>RS3544</b>	Cabin Air (w/o Charcoal) (3802821)..... <b>PA5475</b>
Radial Seal Air (151849148)..... <b>RS3544</b>	Cabin Air (w/o Charcoal) (3802821)..... <b>PA5475</b>	Daily V 35C.18 w/FPT 3.0 VGT Eng. (07/06-on)
Daily IV 60-15 Turbo w/8140.43N Eng. (09/00-06/01)	Daily V 29L15 (2.3 Multijet III) w/F1AE348I Eng. (10/11-on)	Lube (2995561)..... <b>B7376</b>
Dual-Flow Lube (1902047)..... <b>BD232</b>	Lube (504091563)..... <b>B7496</b>	Fuel (504170771)..... <b>PF9865</b>
Fuel (1902138)..... <b>BF5587-D</b>	Fuel (504170771)..... <b>PF9865</b>	Radial Seal Air (1903669)..... <b>RS3544</b>
Radial Seal Air (151849148)..... <b>RS3544</b>	Cabin Air (w/o Charcoal) (3802821)..... <b>PA5475</b>	Cabin Air (w/o Charcoal) (3802821)..... <b>PA5475</b>
Daily IV 65-14 Turbo (3.0 HPI) w/136 HP Eng. (09/04-on)	Daily V 35C,11 (2.3 HPI) w/F1AE0481UA Eng. (09/09-on)	Daily V 35C,21 (3.0 HPT E5) w/F1CE3481DB Eng. (10/11-on)
Lube (2995561)..... <b>B7376</b>	Lube (504091563)..... <b>B7496</b>	Lube (2995655)..... <b>B7388</b>
Fuel (2992300)..... <b>BF7970</b>	Fuel (504170771)..... <b>PF9865</b>	Fuel (504170771)..... <b>PF9865</b>
Radial Seal Air (151849148)..... <b>RS3544</b>	Cabin Air (w/o Charcoal) (3802821)..... <b>PA5475</b>	Cabin Air (w/o Charcoal) (3802821)..... <b>PA5475</b>
Daily IV 65-15 Turbo w/8140.43N Eng. (07/01-on)	Daily V 35C,11 (2.3 HPI) w/F1AE0481UA Eng. (09/09-on)	
Dual-Flow Lube (1902047)..... <b>BD232</b>	Lube (504091563)..... <b>B7496</b>	
Fuel (2992300)..... <b>BF7970</b>	Fuel (504170771)..... <b>PF9865</b>	

Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IVECO European Light Duty Vehicles (cont'd)	IVECO European Light Duty Vehicles (cont'd)	IVECO European Light Duty Vehicles (cont'd)
Daily V 35S,10 (2.3 HPI) w/F1AE0481FA Eng. (07/06-on) Lube (504091563)..... <b>B7496</b> Fuel (504170771)..... <b>PF9865</b> Radial Seal Air (To 09/11) (2992677)..... <b>RS3544</b> Cabin Air (w/o Charcoal) (3802821)..... <b>PA5475</b>	Daily V 40C,11 w/FPT 2.3 CRD Eng. (07/06-on) Lube (2995811)..... <b>B7496</b> Fuel (504170771)..... <b>PF9865</b> Radial Seal Air (1903669)..... <b>RS3544</b> Cabin Air (w/o Charcoal) (3802821)..... <b>PA5475</b>	Daily V 40C,17 (3.0 HTP EEV) w/F1CE3481CC Eng. (09/06-on) (Cont'd) Cabin Air (w/o Charcoal) (3802821)..... <b>PA5475</b>
Daily V 35S,11 w/FPT 2.3 CRD Eng. (07/06-on) Lube (2995811)..... <b>B7496</b> Fuel (504170771)..... <b>PF9865</b> Radial Seal Air (1903669)..... <b>RS3544</b> Cabin Air (w/o Charcoal) (3802821)..... <b>PA5475</b>	Daily V 40C,12 (2.3 HPI) w/F1AE0481GA Eng. (07/06-on) Lube (504091563)..... <b>B7496</b> Fuel (504170771)..... <b>PF9865</b> Radial Seal Air (To 09/11) (2992677)..... <b>RS3544</b> Cabin Air (w/o Charcoal) (3802821)..... <b>PA5475</b>	Daily V 40C,18 w/FPT 3.0 VGT Eng. (07/06-on) Lube (2995561)..... <b>B7376</b> Fuel (504170771)..... <b>PF9865</b> Radial Seal Air (1903669)..... <b>RS3544</b> Cabin Air (w/o Carbon) (3802821)..... <b>PA5475</b>
Daily V 35S,12 (2.3 HPI) w/F1AE0481GA Eng. (07/06-on) Lube (504091563)..... <b>B7496</b> Fuel (504170771)..... <b>PF9865</b> Radial Seal Air (To 09/11) (2992677)..... <b>RS3544</b> Cabin Air (w/o Charcoal) (3802821)..... <b>PA5475</b>	Daily V 40C,13 (2.3 HPT) w/F1AE0481VA Eng. (09/06-on) Lube (504091563)..... <b>B7496</b> Fuel (504170771)..... <b>PF9865</b> Radial Seal Air (To 09/11) (2992677)..... <b>RS3544</b> Cabin Air (w/o Charcoal) (3802821)..... <b>PA5475</b>	Daily V 40C,21 (3.0 HTP E5) w/F1CE3481DB Eng. (10/11-on) Lube (2995655)..... <b>B7388</b> Fuel (504170771)..... <b>PF9865</b> Cabin Air (w/o Charcoal) (3802821)..... <b>PA5475</b>
Daily V 35S,14 (2.3 HPI EEV) w/F1CE3481LC Eng. (09/06-on) Lube (2995655)..... <b>B7388</b> Fuel (504170771)..... <b>PF9865</b> Radial Seal Air (To 09/11) (2992677)..... <b>RS3544</b> Cabin Air (w/o Charcoal) (3802821)..... <b>PA5475</b>	Daily V 40C,13 w/FPT 2.3 CRD Eng. (07/06-on) Lube (2995811)..... <b>B7496</b> Fuel (504170771)..... <b>PF9865</b> Radial Seal Air (1903669)..... <b>RS3544</b> Cabin Air (w/o Carbon) (3802821)..... <b>PA5475</b>	Daily V 45C,15 (3.0 HTI) w/F1CE0481FA Eng. (07/06-on) Lube (2995655)..... <b>B7388</b> Fuel (504170771)..... <b>PF9865</b> Radial Seal Air (To 09/11) (2992677)..... <b>RS3544</b> Cabin Air (w/o Carbon) (3802821)..... <b>PA5475</b>
Daily V 35S,13 w/FPT 2.3 CRD Eng. (07/06-on) Lube (2995811)..... <b>B7496</b> Fuel (504170771)..... <b>PF9865</b> Radial Seal Air (1903669)..... <b>RS3544</b> Cabin Air (w/o Charcoal) (3802821)..... <b>PA5475</b>	Daily V 40C,14 (2.3 HPI EEV) w/F1CE3481LC Eng. (09/09-on) Lube (2995655)..... <b>B7388</b> Fuel (504170771)..... <b>PF9865</b> Radial Seal Air (To 09/11) (2992677)..... <b>RS3544</b> Cabin Air (w/o Charcoal) (3802821)..... <b>PA5475</b>	Daily V 45C,17 (3.0 HTP EEV) w/F1CE3481CC Eng. (09/09-on) Lube (2995655)..... <b>B7388</b> Fuel (504170771)..... <b>PF9865</b> Radial Seal Air (To 09/11) (2992677)..... <b>RS3544</b> Cabin Air (w/o Carbon) (3802821)..... <b>PA5475</b>
Daily V 35S,14 w/FPT 2.3 VGT Eng. (07/06-on) Lube (2995811)..... <b>B7496</b> Fuel (504170771)..... <b>PF9865</b> Radial Seal Air (1903669)..... <b>RS3544</b> Cabin Air (w/o Charcoal) (3802821)..... <b>PA5475</b>	Daily V 40C,14 CNG (3.0 CNG EEV) w/F1CE0441FA Eng. (09/09-on) Lube (504091563)..... <b>B7496</b> Fuel (504170771)..... <b>PF9865</b> Radial Seal Air (To 09/11) (2992677)..... <b>RS3544</b> Cabin Air (w/o Charcoal) (3802821)..... <b>PA5475</b>	Daily V 45C,18 (3.0 HTP) w/F1CE0481HA Eng. (07/06-on) Lube (2995655)..... <b>B7388</b> Fuel (504170771)..... <b>PF9865</b> Radial Seal Air (To 09/11) (2992677)..... <b>RS3544</b> Cabin Air (w/o Carbon) (3802821)..... <b>PA5475</b>
Daily V 35S,18 w/FPT 3.0 VGT Eng. (07/06-on) Lube (2995561)..... <b>B7376</b> Fuel (504170771)..... <b>PF9865</b> Radial Seal Air (1903669)..... <b>RS3544</b> Cabin Air (w/o Charcoal) (3802821)..... <b>PA5475</b>	Daily V 40C,14 CNG (3.0 CNG EEV) w/F1CE0441FA Eng. (09/09-on) Lube (504091563)..... <b>B7496</b> Fuel (504170771)..... <b>PF9865</b> Radial Seal Air (To 09/11) (2992677)..... <b>RS3544</b> Cabin Air (w/o Charcoal) (3802821)..... <b>PA5475</b>	Daily V 50C,14 (3.0 HTI EEV) w/F1CE0481HA Eng. (09/06-on) Lube (2995655)..... <b>B7388</b> Fuel (504170771)..... <b>PF9865</b> Radial Seal Air (To 09/11) (2992677)..... <b>RS3544</b> Cabin Air (w/o Carbon) (3802821)..... <b>PA5475</b>
Daily V 40C,10 (2.3 HPI) w/F1AE0481FA Eng. (07/06-on) Lube (504091563)..... <b>B7496</b> Fuel (504170771)..... <b>PF9865</b> Radial Seal Air (To 09/11) (2992677)..... <b>RS3544</b> Cabin Air (w/o Charcoal) (3802821)..... <b>PA5475</b>	Daily V 40C,15 w/FPT 3.0 CRD Eng. (07/06-on) Lube (2995655)..... <b>B7388</b> Fuel (504170771)..... <b>PF9865</b> Radial Seal Air (1903669)..... <b>RS3544</b> Cabin Air (w/o Carbon) (3802821)..... <b>PA5475</b>	Daily V 50C,14 CNG (3.0 CNG EEV) w/F1CE0441FA Eng. (02/07-on) Lube (504091563)..... <b>B7496</b> Radial Seal Air (To 09/11) (2992677)..... <b>RS3544</b> Cabin Air (w/o Carbon) (3802821)..... <b>PA5475</b>

Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IVECO European Light Duty Vehicles (cont'd)	IVECO European Light Duty Vehicles (cont'd)	IVECO European Light Duty Vehicles (cont'd)
Daily V 50C,15 w/FPT 3.0 CRD Eng. (07/06-on) <b>Lube</b> (2995655)..... <b>B7388</b> <b>Fuel</b> (504170771)..... <b>PF9865</b> <b>Radial Seal Air</b> (1903669)..... <b>RS3544</b> <b>Cabin Air</b> (w/o Carbon) (3802821)..... <b>PA5475</b>	Daily V 60C,17 (3.0 HTP EEV) w/F1CE3481CC Eng. (09/06-on) <b>Lube</b> (2995655)..... <b>B7388</b> <b>Fuel</b> (504170771)..... <b>PF9865</b> <b>Radial Seal Air</b> (To 09/11) (2992677)..... <b>RS3544</b> <b>Cabin Air</b> (w/o Carbon) (3802821)..... <b>PA5475</b>	Daily V 70C,14 (3.0 HTP EEV) w/F1CE3481LC Eng. (09/06-on) <b>Lube</b> (2995655)..... <b>B7388</b> <b>Fuel</b> (504170771)..... <b>PF9865</b> <b>Radial Seal Air</b> (To 09/11) (2992677)..... <b>RS3544</b> <b>Cabin Air</b> (w/o Carbon) (3802821)..... <b>PA5475</b>
Daily V 50C,14 CNG (3.0 CNG) w/F1CE0441FA Eng. (07/06-01/07) <b>Lube</b> (504091563)..... <b>B7496</b> <b>Radial Seal Air</b> (2992677)..... <b>RS3544</b> <b>Cabin Air</b> (w/o Carbon) (3802821)..... <b>PA5475</b>	Daily V 60C,18 (3.0 HTP) w/F1CE0481HA Eng. (07/06-on) <b>Lube</b> (2995655)..... <b>B7388</b> <b>Fuel</b> (504170771)..... <b>PF9865</b> <b>Radial Seal Air</b> (To 09/11) (2992677)..... <b>RS3544</b> <b>Cabin Air</b> (w/o Carbon) (3802821)..... <b>PA5475</b>	Daily V 70C,14 CNG (3.0 CNG EEV) w/F1CE0441FA Eng. (09/09-on) <b>Lube</b> (504091563)..... <b>B7496</b> <b>Radial Seal Air</b> (To 09/11) (2992677)..... <b>RS3544</b> <b>Cabin Air</b> (w/o Carbon) (3802821)..... <b>PA5475</b>
Daily V 50C,17 (3.0 HTP EEV) w/F1CE3481CC Eng. (09/09-on) <b>Lube</b> (2995655)..... <b>B7388</b> <b>Fuel</b> (504170771)..... <b>PF9865</b> <b>Radial Seal Air</b> (To 09/11) (2992677)..... <b>RS3544</b> <b>Cabin Air</b> (w/o Carbon) (3802821)..... <b>PA5475</b>	Daily V 65C,14 (3.0 HTI EEV) w/FICE3481LC Eng. (09/06-on) <b>Lube</b> (2995655)..... <b>B7388</b> <b>Fuel</b> (504170771)..... <b>PF9865</b> <b>Radial Seal Air</b> (To 09/11) (2992677)..... <b>RS3544</b> <b>Cabin Air</b> (w/o Carbon) (3802821)..... <b>PA5475</b>	Daily V 70C,15 (3.0 HTI) w/F1CE0481FA Eng. (10/09-on) <b>Lube</b> (2995655)..... <b>B7388</b> <b>Fuel</b> (504170771)..... <b>PF9865</b> <b>Radial Seal Air</b> (To 09/11) (2992677)..... <b>RS3544</b> <b>Cabin Air</b> (w/o Carbon) (3802821)..... <b>PA5475</b>
Daily V 50C,18 w/FPT 3.0 VGT Eng. (07/06-on) <b>Lube</b> (2995561)..... <b>B7376</b> <b>Fuel</b> (504170771)..... <b>PF9865</b> <b>Radial Seal Air</b> (1903669)..... <b>RS3544</b> <b>Cabin Air</b> (w/o Carbon) (3802821)..... <b>PA5475</b>	Daily V 65C,14 CNG (3.0 CNG) w/F1CE0441FA (EEV) Eng. (07/06-01/07) <b>Lube</b> (504091563)..... <b>B7496</b> <b>Radial Seal Air</b> (2992677)..... <b>RS3544</b> <b>Cabin Air</b> (w/o Carbon) (3802821)..... <b>PA5475</b>	Daily V 70C,15 w/FPT 3.0 CRD Eng. (07/06-on) <b>Lube</b> (2995655)..... <b>B7388</b> <b>Fuel</b> (504170771)..... <b>PF9865</b> <b>Radial Seal Air</b> (1903669)..... <b>RS3544</b> <b>Cabin Air</b> (w/o Carbon) (3802821)..... <b>PA5475</b>
Daily V 50C,21 (3.0 HTP E5) w/F1CE3481DB Eng. (10/11-on) <b>Lube</b> (2995655)..... <b>B7388</b> <b>Fuel</b> (504170771)..... <b>PF9865</b> <b>Cabin Air</b> (w/o Carbon) (3802821)..... <b>PA5475</b>	Daily V 65C,14 CNG (3.0 CNG) w/F1CE0441FA Eng. (02/07-on) <b>Lube</b> (504091563)..... <b>B7496</b> <b>Radial Seal Air</b> (To 09/11) (2992677)..... <b>RS3544</b> <b>Cabin Air</b> (w/o Carbon) (3802821)..... <b>PA5475</b>	Daily V 70C,17 (3.0 HTP EEV) w/F1CE3481CC Eng. (09/09-on) <b>Lube</b> (2995655)..... <b>B7388</b> <b>Fuel</b> (504170771)..... <b>PF9865</b> <b>Radial Seal Air</b> (To 09/11) (2992677)..... <b>RS3544</b> <b>Cabin Air</b> (w/o Carbon) (3802821)..... <b>PA5475</b>
Daily V 55S,17 (3.0 HTP EEV) w/F1CE3481CC Eng. (09/09-on) <b>Lube</b> (2995655)..... <b>B7388</b> <b>Fuel</b> (504170771)..... <b>PF9865</b> <b>Radial Seal Air</b> (To 09/11) (2992677)..... <b>RS3544</b> <b>Cabin Air</b> (w/o Carbon) (3802821)..... <b>PA5475</b>	Daily V 65C,15 w/FPT 3.0 CRD Eng. (07/06-on) <b>Lube</b> (2995655)..... <b>B7388</b> <b>Fuel</b> (504170771)..... <b>PF9865</b> <b>Radial Seal Air</b> (1903669)..... <b>RS3544</b> <b>Cabin Air</b> (w/o Carbon) (3802821)..... <b>PA5475</b>	Daily V 70C,18 (3.0 HTP) w/F1VE0481HA Eng. (10/09-on) <b>Lube</b> (2995655)..... <b>B7388</b> <b>Fuel</b> (504170771)..... <b>PF9865</b> <b>Radial Seal Air</b> (To 09/11) (2992677)..... <b>RS3544</b> <b>Cabin Air</b> (w/o Carbon) (3802821)..... <b>PA5475</b>
Daily V 60C,14 (3.0 HTI EEV) w/F1CE3481LC Eng. (09/06-on) <b>Lube</b> (2995655)..... <b>B7388</b> <b>Fuel</b> (504170771)..... <b>PF9865</b> <b>Radial Seal Air</b> (To 09/11) (2992677)..... <b>RS3544</b> <b>Cabin Air</b> (w/o Carbon) (3802821)..... <b>PA5475</b>	Daily V 65C,17 (3.0 HTP EEV) w/F1CE3481CC Eng. (09/09-on) <b>Lube</b> (2995655)..... <b>B7388</b> <b>Fuel</b> (504170771)..... <b>PF9865</b> <b>Radial Seal Air</b> (To 09/11) (2992677)..... <b>RS3544</b> <b>Cabin Air</b> (w/o Carbon) (3802821)..... <b>PA5475</b>	Daily V 70C,18 w/FPT 3.0 VGT Eng. (07/06-on) <b>Lube</b> (2995561)..... <b>B7376</b> <b>Fuel</b> (504170771)..... <b>PF9865</b> <b>Radial Seal Air</b> (1903669)..... <b>RS3544</b> <b>Cabin Air</b> (w/o Carbon) (3802821)..... <b>PA5475</b>
Daily V 60C,15 (3.0 HTI) w/F1CE0481FA Eng. (07/06-on) <b>Lube</b> (2995655)..... <b>B7388</b> <b>Fuel</b> (504170771)..... <b>PF9865</b> <b>Radial Seal Air</b> (To 09/11) (2992677)..... <b>RS3544</b> <b>Cabin Air</b> (w/o Carbon) (3802821)..... <b>PA5475</b>	Daily V 65C,18 w/FPT 3.0 VGT Eng. (07/06-on) <b>Lube</b> (2995561)..... <b>B7376</b> <b>Fuel</b> (504170771)..... <b>PF9865</b> <b>Radial Seal Air</b> (1903669)..... <b>RS3544</b> <b>Cabin Air</b> (w/o Carbon) (3802821)..... <b>PA5475</b>	Ecodayly 35C,14 w/FPT 3.0 EEV Twin Turbo Eng. (09/09-on) <b>Lube</b> (2995655)..... <b>B7388</b> <b>Fuel</b> (504170771)..... <b>PF9865</b> <b>Air</b> (1903669)..... <b>RS3544</b>

Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IVECO European Light Duty Vehicles (cont'd)	IVECO European Light Duty Vehicles (cont'd)	IVECO European Light Duty Vehicles (cont'd)
Ecodayly 35C.14 w/FPT 3.0 EEV Twin Turbo Eng. (09/09-on) (Cont'd) <b>Cabin Air</b> (w/o Carbon) (3802821)..... <b>PA5475</b>	Ecodayly 40C.17 w/FPT 3.0 EEV Twin Turbo Eng. (09/09-on) (Cont'd) <b>Cabin Air</b> (w/o Carbon) (3802821)..... <b>PA5475</b>	Ecodayly 70C.14 CNG w/FPT 3.0 EEV Natural Power Eng. (09/09-on) (Cont'd) <b>Cabin Air</b> (w/o Carbon) (3802821)..... <b>PA5475</b>
Ecodayly 35C.14 CNG w/FPT 3.0 EEV Natural Power Eng. (09/09-on) <b>Lube</b> (2995811)..... <b>B7496</b> <b>Radial Seal Air</b> (1903669)..... <b>RS3544</b> <b>Cabin Air</b> (w/o Carbon) (3802821)..... <b>PA5475</b>	Ecodayly 50C.14 w/FPT 3.0 EEV Twin Turbo Eng. (09/09-on) <b>Lube</b> (2995655)..... <b>B7388</b> <b>Fuel</b> (504170771)..... <b>PF9865</b> <b>Air</b> (1903669)..... <b>RS3544</b> <b>Cabin Air</b> (w/o Carbon) (3802821)..... <b>PA5475</b>	Ecodayly 70C.17 w/FPT 3.0 EEV Twin Turbo Eng. (09/09-on) <b>Lube</b> (2995655)..... <b>B7388</b> <b>Fuel</b> (504170771)..... <b>PF9865</b> <b>Air</b> (1903669)..... <b>RS3544</b> <b>Cabin Air</b> (w/o Carbon) (3802821)..... <b>PA5475</b>
Ecodayly 35C.17 w/FPT 3.0 EEV Twin Turbo Eng. (09/09-on) <b>Lube</b> (2995655)..... <b>B7388</b> <b>Fuel</b> (504170771)..... <b>PF9865</b> <b>Air</b> (1903669)..... <b>RS3544</b> <b>Cabin Air</b> (w/o Carbon) (3802821)..... <b>PA5475</b>	Ecodayly 50C.14 CNG w/FPT 3.0 EEV Natural Power Eng. (09/09-on) <b>Lube</b> (2995811)..... <b>B7496</b> <b>Radial Seal Air</b> (1903669)..... <b>RS3544</b> <b>Cabin Air</b> (w/o Carbon) (3802821)..... <b>PA5475</b>	<b>IVECO Trucks</b>
Ecodayly 35S.14 w/FPT 3.0 EEV Twin Turbo Eng. (09/09-on) <b>Lube</b> (2995655)..... <b>B7388</b> <b>Fuel</b> (504170771)..... <b>PF9865</b> <b>Air</b> (1903669)..... <b>RS3544</b> <b>Cabin Air</b> (w/o Carbon) (3802821)..... <b>PA5475</b>	Ecodayly 50C.17 w/FPT 3.0 EEV Twin Turbo Eng. (09/09-on) <b>Lube</b> (2995655)..... <b>B7388</b> <b>Fuel</b> (504170771)..... <b>PF9865</b> <b>Air</b> (1903669)..... <b>RS3544</b> <b>Cabin Air</b> (w/o Carbon) (3802821)..... <b>PA5475</b>	
Ecodayly 35S.14 CNG w/FPT 3.0 EEV Natural Power Eng. (09/09-on) <b>Lube</b> (2995811)..... <b>B7496</b> <b>Radial Seal Air</b> (1903669)..... <b>RS3544</b> <b>Cabin Air</b> (w/o Carbon) (3802821)..... <b>PA5475</b>	Ecodayly 65C.14 w/FPT 3.0 EEV Twin Turbo Eng. (09/09-on) <b>Lube</b> (2995655)..... <b>B7388</b> <b>Fuel</b> (504170771)..... <b>PF9865</b> <b>Air</b> (1903669)..... <b>RS3544</b> <b>Cabin Air</b> (w/o Carbon) (3802821)..... <b>PA5475</b>	Orsetto 1A Series <b>Lube</b> ..... <b>P235</b> <b>Fuel</b> ..... <b>PF906</b>
Ecodayly 35S.17 w/FPT 3.0 EEV Twin Turbo Eng. (09/09-on) <b>Lube</b> (2995655)..... <b>B7388</b> <b>Fuel</b> (504170771)..... <b>PF9865</b> <b>Air</b> (504064501)..... <b>RS3544</b> <b>Cabin Air</b> (w/o Carbon) (3802821)..... <b>PA5475</b>	Ecodayly 65C.14 CNG w/FPT 3.0 EEV Natural Power Eng. (09/09-on) <b>Lube</b> (2995811)..... <b>B7496</b> <b>Radial Seal Air</b> (1903669)..... <b>RS3544</b> <b>Cabin Air</b> (w/o Carbon) (3802821)..... <b>PA5475</b>	Orsetto 2A Series: A15.1L, A15.1N, A15.1NL, OM40, OM40.35, 50NC, 55NC, 616N, 616N1 <b>Lube</b> ..... <b>BT347</b> <b>Can-Type Fuel</b> ..... <b>BF825 +</b>
Ecodayly 40C.14 w/FPT 3.0 EEV Twin Turbo Eng. (09/09-on) <b>Lube</b> (2995655)..... <b>B7388</b> <b>Fuel</b> (504170771)..... <b>PF9865</b> <b>Radial Seal Air</b> (1903669)..... <b>RS3544</b> <b>Cabin Air</b> (w/o Carbon) (3802821)..... <b>PA5475</b>	Ecodayly 65C.17 w/FPT 3.0 EEV Twin Turbo Eng. (09/09-on) <b>Lube</b> (2995655)..... <b>B7388</b> <b>Fuel</b> (504170771)..... <b>PF9865</b> <b>Air</b> (1903669)..... <b>RS3544</b> <b>Cabin Air</b> (w/o Carbon) (3802821)..... <b>PA5475</b>	6RB1, 6RB1D 20C w/CO 3.20 Eng. <b>Lube</b> (1901603)..... <b>BT347</b> <b>Can-Type Fuel</b> (74651986)..... <b>BF825 +</b>
Ecodayly 40C.14 CNG w/FPT 3.0 EEV Natural Power Eng. (09/09-on) <b>Lube</b> (2995811)..... <b>B7496</b> <b>Radial Seal Air</b> (1903669)..... <b>RS3544</b> <b>Cabin Air</b> (w/o Carbon) (3802821)..... <b>PA5475</b>	Ecodayly 70C.14 w/FPT 3.0 EEV Twin Turbo Eng. (09/09-on) <b>Lube</b> (2995655)..... <b>B7388</b> <b>Fuel</b> (504170771)..... <b>PF9865</b> <b>Air</b> (1903669)..... <b>RS3544</b> <b>Cabin Air</b> (w/o Carbon) (3802821)..... <b>PA5475</b>	Jupiter (6x6) BW w/Deutz F8L714A Eng. <b>Fuel Ele.</b> (1168407)..... <b>F950-F</b> <b>Hyd.</b> (1267900)..... <b>PT691</b>
Ecodayly 40C.17 w/FPT 3.0 EEV Twin Turbo Eng. (09/09-on) <b>Lube</b> (2995655)..... <b>B7388</b> <b>Fuel</b> (504170771)..... <b>PF9865</b> <b>Air</b> (1903669)..... <b>RS3544</b>	Ecodayly 70C.14 CNG w/FPT 3.0 EEV Natural Power Eng. (09/09-on) <b>Lube</b> (2995811)..... <b>B7496</b> <b>Radial Seal Air</b> (1903669)..... <b>RS3544</b> <b>Cabin Air</b> (w/o Carbon) (3802821)..... <b>PA5475</b>	P8MC, T8MC, P9MC, T9MC w/CP3 Eng. <b>Lube Ele.</b> (78813556)..... <b>P20-HD +</b>
Ecodayly 40C.17 w/FPT 3.0 EEV Twin Turbo Eng. (09/09-on) <b>Lube</b> (2995655)..... <b>B7388</b> <b>Fuel</b> (504170771)..... <b>PF9865</b> <b>Air</b> (1903669)..... <b>RS3544</b>	Ecodayly 70C.14 w/FPT 3.0 EEV Twin Turbo Eng. (09/09-on) <b>Lube</b> (2995655)..... <b>B7388</b> <b>Fuel</b> (504170771)..... <b>PF9865</b> <b>Air</b> (1903669)..... <b>RS3544</b> <b>Cabin Air</b> (w/o Carbon) (3802821)..... <b>PA5475</b>	N12 w/Volvo TD121G Eng. <b>Lube</b> ..... <b>B76 +</b> <b>Lube</b> (Upgrade)..... <b>B76-SS +</b> <b>Fuel</b> (243004)..... <b>BF988 +</b> <b>Air</b> ..... <b>PA2707</b>
Ecodayly 40C.14 CNG w/FPT 3.0 EEV Natural Power Eng. (09/09-on) <b>Lube</b> (2995811)..... <b>B7496</b> <b>Radial Seal Air</b> (1903669)..... <b>RS3544</b> <b>Cabin Air</b> (w/o Carbon) (3802821)..... <b>PA5475</b>	Ecodayly 70C.14 w/FPT 3.0 EEV Twin Turbo Eng. (09/09-on) <b>Lube</b> (2995655)..... <b>B7388</b> <b>Fuel</b> (504170771)..... <b>PF9865</b> <b>Air</b> (1903669)..... <b>RS3544</b> <b>Cabin Air</b> (w/o Carbon) (3802821)..... <b>PA5475</b>	15DT20 w/Unic Eng. <b>206.4 mm Lube</b> ..... <b>B236 +</b> <b>231.8 mm Lube</b> (4667755)..... <b>BT349</b> <b>Fuel</b> ..... <b>BF988 +</b> <b>Fuel/Water Separator</b> ..... <b>BF1221 +</b>
Ecodayly 40C.17 w/FPT 3.0 EEV Twin Turbo Eng. (09/09-on) <b>Lube</b> (2995655)..... <b>B7388</b> <b>Fuel</b> (504170771)..... <b>PF9865</b> <b>Air</b> (1903669)..... <b>RS3544</b>	Ecodayly 70C.14 CNG w/FPT 3.0 EEV Natural Power Eng. (09/09-on) <b>Lube</b> (2995811)..... <b>B7496</b> <b>Radial Seal Air</b> (1903669)..... <b>RS3544</b> <b>Cabin Air</b> (w/o Carbon) (3802821)..... <b>PA5475</b>	Beta Z20, Z20A <b>Lube</b> (2323108)..... <b>PT29</b> <b>Fuel Ele.</b> (2177074)..... <b>PF950</b>
Ecodayly 40C.17 w/FPT 3.0 EEV Twin Turbo Eng. (09/09-on) <b>Lube</b> (2995655)..... <b>B7388</b> <b>Fuel</b> (504170771)..... <b>PF9865</b> <b>Air</b> (1903669)..... <b>RS3544</b>	Ecodayly 70C.14 w/FPT 3.0 EEV Natural Power Eng. (09/09-on) <b>Lube</b> (2995655)..... <b>B7388</b> <b>Fuel</b> (504170771)..... <b>PF9865</b> <b>Air</b> (1903669)..... <b>RS3544</b> <b>Cabin Air</b> (w/o Carbon) (3802821)..... <b>PA5475</b>	24C w/CO 3.20 Eng. <b>Lube</b> (1901603)..... <b>BT347</b> <b>Can-Type Fuel</b> (74651986)..... <b>BF825 +</b>
Ecodayly 40C.17 w/FPT 3.0 EEV Twin Turbo Eng. (09/09-on) <b>Lube</b> (2995655)..... <b>B7388</b> <b>Fuel</b> (504170771)..... <b>PF9865</b> <b>Air</b> (1903669)..... <b>RS3544</b>	Ecodayly 70C.14 CNG w/FPT 3.0 EEV Natural Power Eng. (09/09-on) <b>Lube</b> (2995811)..... <b>B7496</b> <b>Radial Seal Air</b> (1903669)..... <b>RS3544</b>	28F8 Daily/Grinta w/SOFIN 8140 Eng. <b>Can-Type Fuel</b> ..... <b>BF825 +</b>
Ecodayly 40C.17 w/FPT 3.0 EEV Twin Turbo Eng. (09/09-on) <b>Lube</b> (2995655)..... <b>B7388</b> <b>Fuel</b> (504170771)..... <b>PF9865</b> <b>Air</b> (1903669)..... <b>RS3544</b>	Ecodayly 70C.14 CNG w/FPT 3.0 EEV Natural Power Eng. (09/09-on) <b>Lube</b> (2995811)..... <b>B7496</b> <b>Radial Seal Air</b> (1903669)..... <b>RS3544</b>	28.8 Daily <b>Lube</b> (To 4/83)..... <b>B75</b> <b>Can-Type Fuel</b> ..... <b>BF825 +</b>
Ecodayly 40C.17 w/FPT 3.0 EEV Twin Turbo Eng. (09/09-on) <b>Lube</b> (2995655)..... <b>B7388</b> <b>Fuel</b> (504170771)..... <b>PF9865</b> <b>Air</b> (1903669)..... <b>RS3544</b>	Ecodayly 70C.14 CNG w/FPT 3.0 EEV Natural Power Eng. (09/09-on) <b>Lube</b> (2995811)..... <b>B7496</b> <b>Radial Seal Air</b> (1903669)..... <b>RS3544</b>	Beta Z30 <b>Lube</b> (2323108)..... <b>PT29</b> <b>Fuel Ele.</b> (2177074)..... <b>PF950</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IVECO Trucks (cont'd)	IVECO Trucks (cont'd)	IVECO Trucks (cont'd)
30.8 Daily Lube (To 4/83)..... B75 Can-Type Fuel..... BF825+	35.10 Daily Turbo Diesel Can-Type Fuel..... BF825+ Fuel Spin-on..... BF587 177.0 mm Air (To 8/85) (1902457)..... PA3836	40.10 Daily (Cont'd) 336.6 mm Air (1904581)..... PA2767
30.8, 30.8 New Daily 100.0 mm Lube (1901606)..... BT5 100.8 mm Lube (4160703)..... B163 Dual-Flow Lube (1907582)..... BD232 Can-Type Fuel..... BF825+ Fuel Spin-on..... BF587-D+ 177.0 mm Air (1902457)..... PA3836 336.6 mm Air (1904581)..... PA2767	35.10 New Turbo Daily Dual-Flow Lube (1907582)..... BD232 Fuel (1902138)..... BF5587-D 336.6 mm Air (1904581)..... PA2767	40.10, 40.10W Dual-Flow Lube..... BD232 Fuel (1902138)..... BF5587-D Steering..... P106
30F8 Daily/Grinta, 32F8 Daily/Grinta w/SOFIM 8140 Eng. Can-Type Fuel..... BF825+	35.11 w/SOFIM Eng. Dual-Flow Lube (1907582)..... BD232 Fuel (1902138)..... BF5587-D	A40.10 Dual-Flow Lube..... BD232 Fuel (1902138)..... BF5587-D Steering..... P106
30.9 Daily w/2.0L Eng. Lube..... B163 In-Line Fuel..... BF833 177.0 mm Air (1902457)..... PA3836	35.12 100.0 mm Lube (1901606)..... BT5 100.8 mm Lube (4160703)..... B163 Dual-Flow Lube (1907582)..... BD232 Can-Type Fuel..... BF825+ Fuel Spin-on..... BF587-D+ 177.0 mm Air (1902457)..... PA3836 336.6 mm Air (1904581)..... PA2767	40.11 w/SOFIM Eng. Dual-Flow Lube (1907582)..... BD232 Fuel (1902138)..... BF5587-D
32.8 Daily Lube (To 4/83)..... B75 Can-Type Fuel..... BF825+	35.13 w/SOFIM Eng. Dual-Flow Lube (1907582)..... BD232 Fuel (1902138)..... BF5587-D	40.12 Daily 100.0 mm Lube (1901606)..... BT5 100.8 mm Lube (4160703)..... B163 Dual-Flow Lube (1907582)..... BD232 Can-Type Fuel..... BF825+ Fuel Spin-on..... BF587-D+ 177.0 mm Air (1902457)..... PA3836 336.6 mm Air (1904581)..... PA2767
34C w/CO 3.31 Eng. Lube (1901603)..... BT347 Can-Type Fuel (74651986)..... BF825+	36C, 36TCA, 38D w/CO 3.31 Eng. Lube (1901603)..... BT347 Can-Type Fuel (74651986)..... BF825+	40.13 w/SOFIM Eng. Dual-Flow Lube (1907582)..... BD232 Fuel (1902138)..... BF5587-D
35.8 Daily Lube (To 4/83)..... B75 Can-Type Fuel..... BF825+	C40, C40N w/213 Vertical Eng. Lube (4585298)..... P235	45.10 Turbo Diesel Can-Type Fuel..... BF825+ Fuel Spin-on..... BF587 Air (To 8/85) (1902457)..... PA3836
35.8, 35.8 New Daily, 35.9 100.0 mm Lube (1901606)..... BT5 100.8 mm Lube (4160703)..... B163 Dual-Flow Lube (1907582)..... BD232 Can-Type Fuel..... BF825+ Fuel Spin-on..... BF587-D+ 177.0 mm Air (1902457)..... PA3836 336.6 mm Air (1904581)..... PA2767	40.35, 40NC, 40NC35 w/8040.02 Eng. Lube (1901603)..... BT347 Can-Type Fuel (74651986)..... BF825+	45.10 Daily 100.0 mm Lube (1901606)..... BT5 100.8 mm Lube (4160703)..... B163 Dual-Flow Lube (1907582)..... BD232 Can-Type Fuel..... BF825+ Fuel Spin-on (1902138)..... BF5587-D 177.0 mm Air (1902457)..... PA3836 336.6 mm Air (1904581)..... PA2767
35F8 Daily, 35F8 OM Grinta Can-Type Fuel..... BF825+	40.8 Daily Lube (To 4/83)..... B75 100.0 mm Lube (1901606)..... BT5 100.8 mm Lube (4160703)..... B163 Dual-Flow Lube (1907582)..... BD232 Can-Type Fuel..... BF825+ Fuel Spin-on..... BF587-D+ 177.0 mm Air (1902457)..... PA3836 336.6 mm Air (1904581)..... PA2767	45.10 New Turbo Daily Dual-Flow Lube (1907582)..... BD232 Fuel (1902138)..... BF5587-D 336.6 mm Air (1904581)..... PA2767
35.9 w/SOFIM Eng. Dual-Flow Lube (1907582)..... BD232 Fuel (1902138)..... BF5587-D	40F8 Daily, 40F8 OM Grinta Can-Type Fuel..... BF825+	A45.10 New Turbo Daily Dual-Flow Lube (1907582)..... BD232 Fuel (1902138)..... BF5587-D Air (1904581)..... PA2767
35.9 Daily w/2.0L Eng. Lube..... B163 In-Line Fuel..... BF833 177.0 mm Air (1902457)..... PA3836	40.9 w/SOFIM Eng. Dual-Flow Lube (1907582)..... BD232 Fuel (1902138)..... BF5587-D	45.11 Daily w/SOFIM Eng. Dual-Flow Lube (1907582)..... BD232 Fuel (1902138)..... BF5587-D
35.10 100.0 mm Lube (1901606)..... BT5 100.8 mm Lube (4160703)..... B163 Dual-Flow Lube (1907582)..... BD232 Can-Type Fuel..... BF825+ Fuel Spin-on..... BF587-D+ 177.0 mm Air (1902457)..... PA3836 336.6 mm Air (1904581)..... PA2767	40.10 Turbo Diesel Can-Type Fuel..... BF825+ Fuel Spin-on..... BF587 Air (To 8/85) (1902457)..... PA3836	45.12 Daily 100.0 mm Lube (1901606)..... BT5 100.8 mm Lube (4160703)..... B163 Dual-Flow Lube (1907582)..... BD232 Can-Type Fuel..... BF825+ Fuel Spin-on (1902138)..... BF5587-D 177.0 mm Air (1902457)..... PA3836 336.6 mm Air (1904581)..... PA2767
	40.10 Daily 100.0 mm Lube (1901606)..... BT5 100.8 mm Lube (4160703)..... B163 Dual-Flow Lube (1907582)..... BD232 Can-Type Fuel..... BF825+ Fuel Spin-on..... BF587-D+ 177.0 mm Air (1902457)..... PA3836	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

**Trucks & Buses Applications** **BALDWIN FILTERS**

IVECO Trucks (cont'd)	IVECO Trucks (cont'd)	IVECO Trucks (cont'd)
45.13 Daily w/SOFIM Eng. Dual-Flow Lube (1907582)..... <b>BD232</b> Fuel (1902138)..... <b>BF5587-D</b>	55.8 w/8040.04 Eng. Lube (1901603)..... <b>BT347</b> Can-Type Fuel (74651986)..... <b>BF825 +</b> Steering..... <b>P106</b>	EuroCargo 60E13 w/Cummins Tector Eng. (09/00-09/03) (Cont'd) Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Hyd. Breather (2992447)..... <b>P7336 KIT</b>
49.10 Turbo Diesel Can-Type Fuel..... <b>BF825 +</b> Fuel Spin-on..... <b>BF587</b> Air (To 8/85) (1902457)..... <b>PA3836</b>	55.9, 55.10 Lube (1901603)..... <b>BT347</b> Fuel (1901607)..... <b>BF7593</b>	EuroCargo II 60E13 w/Cummins Tector 4 Eng. (06/03-on) Lube..... <b>BT7237</b> Fuel..... <b>BF7813</b> Radial Seal Air..... <b>RS4968</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Hyd. Breather (2992447)..... <b>P7336 KIT</b>
49.10 Daily 100.0 mm Lube (1901606)..... <b>BT5</b> 100.8 mm Lube (4160703)..... <b>B163</b> Dual-Flow Lube (1907582)..... <b>BD232</b> Can-Type Fuel..... <b>BF825 +</b> Fuel Spin-on (1902138)..... <b>BF5587-D</b> 177.0 mm Air (1902457)..... <b>PA3836</b> 336.6 mm Air (1904581)..... <b>PA2767</b>	55L Can-Type Fuel (74651986)..... <b>BF825 +</b>	EuroCargo 60E14 w/8040.25B.4200 Eng. (01/91-04/01) Dual-Flow Lube (1903785)..... <b>BD232</b> Fuel (1902138)..... <b>BF5587-D</b> Fuel/Water Separator (1908547)..... <b>BF1217</b> Air..... <b>PA3597</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Steering..... <b>P106-HD</b>
A49.10 New Turbo Daily Dual-Flow Lube (1907582)..... <b>BD232</b> Fuel (1902138)..... <b>BF5587-D</b> Air (1904581)..... <b>PA2767</b>	55NC w/8040.02 Eng. Lube (1901603)..... <b>BT347</b> Can-Type Fuel (74651986)..... <b>BF825 +</b>	EuroCargo II 60E14 w/Cummins Tector 4 Eng. (Euro 4/5) (05/06-on) Lube (2992242)..... <b>BT7237</b> Fuel..... <b>BF7813</b> Fuel/Water Separator (2992662)..... <b>BF1365</b> Radial Seal Air..... <b>RS4968</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Hyd. Breather (2992447)..... <b>P7336 KIT</b>
49.11 Daily w/SOFIM Eng. Dual-Flow Lube (1907582)..... <b>BD232</b> Fuel Spin-on (1902138)..... <b>BF5587-D</b>	OM55 Lube (1901603)..... <b>BT347</b> Fuel (1901607)..... <b>BF7593</b>	EuroCargo 60E15 w/Cummins Tector Eng. (09/00-09/03) Lube..... <b>BT7237</b> Fuel/Water Separator (1907539)..... <b>BF1217</b> Fuel..... <b>BF7813</b> Radial Seal Air..... <b>RS4968</b> Air (2992388)..... <b>RS5535</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Hyd. Breather (2992447)..... <b>P7336 KIT</b>
49.12 Daily 100.0 mm Lube (1901606)..... <b>BT5</b> 100.8 mm Lube (4160703)..... <b>B163</b> Dual-Flow Lube (1907582)..... <b>BD232</b> Can-Type Fuel..... <b>BF825 +</b> Fuel Spin-on (1902138)..... <b>BF5587-D</b> 177.0 mm Air (1902457)..... <b>PA3836</b> 336.6 mm Air (1904581)..... <b>PA2767</b>	59.10 Daily, 59.12 Daily 100.0 mm Lube (1901606)..... <b>BT5</b> 100.8 mm Lube (4160703)..... <b>B163</b> Dual-Flow Lube (1907582)..... <b>BD232</b> Can-Type Fuel..... <b>BF825 +</b> Fuel Spin-on (1902138)..... <b>BF5587-D</b> 177.0 mm Air (1902457)..... <b>PA3836</b> 336.6 mm Air (1904581)..... <b>PA2767</b>	EuroCargo II 60E15 w/Cummins Tector 4 Eng. (06/03-on) Lube..... <b>BT7237</b> Fuel..... <b>BF7813</b> Radial Seal Air..... <b>RS4968</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Hyd. Breather (2992447)..... <b>P7336 KIT</b>
49.13 Daily w/SOFIM Eng. Dual-Flow Lube (1907582)..... <b>BD232</b> Fuel Spin-on (1902138)..... <b>BF5587-D</b>	60.8 w/8040.04 Eng. Lube (1901603)..... <b>BT347</b> Can-Type Fuel (74651986)..... <b>BF825 +</b> Steering..... <b>P106</b>	EuroCargo 60E10 w/8040.25, 8040.45 Engs. (01/91-04/01) Dual-Flow Lube (1903785)..... <b>BD232</b> Fuel (1902138)..... <b>BF5587-D</b> Fuel/Water Separator (1908547)..... <b>BF1217</b> Air..... <b>PA3597</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Steering..... <b>P106-HD</b>
50AL, 50NC w/8040.02 Eng. Lube (1901603)..... <b>BT347</b> Can-Type Fuel (74651986)..... <b>BF825 +</b>	60.10 Lube (1901603)..... <b>BT347</b> Fuel (1901607)..... <b>BF7593</b>	EuroCargo II 60E16 w/Cummins Tector 4 Eng. (Euro 4/5) (05/06-on) Lube (2992242)..... <b>BT7237</b> Fuel..... <b>BF7813</b> Fuel/Water Separator (2992662)..... <b>BF1365</b> Radial Seal Air..... <b>RS4968</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Hyd. Breather (2992447)..... <b>P7336 KIT</b>
50NC w/8060.20 Eng. Lube (74730587)..... <b>BT267</b> Can-Type Fuel (74651986)..... <b>BF825 +</b> Air..... <b>PA1822-FN</b>	EuroCargo 60E12 w/8040.25X.4000TC Eng. (01/91-04/01) Dual-Flow Lube (1903785)..... <b>BD232</b> Fuel (1902138)..... <b>BF5587-D</b> Fuel/Water Separator (1908547)..... <b>BF1217</b> Air..... <b>PA3597</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Steering..... <b>P106-HD</b>	EuroCargo 60E13 w/Cummins Tector Eng. (09/00-09/03) Lube..... <b>BT7237</b> Fuel/Water Separator (1907539)..... <b>BF1217</b> Fuel..... <b>BF7813</b> Radial Seal Air..... <b>RS4968</b> Air (2992388)..... <b>RS5535</b>
50.8 w/8040.04 Eng. Lube (1901603)..... <b>BT347</b> Can-Type Fuel (74651986)..... <b>BF825 +</b> Steering..... <b>P106</b>	EuroCargo 60E13 w/Cummins Tector Eng. (09/00-09/03) Lube..... <b>BT7237</b> Fuel/Water Separator (1907539)..... <b>BF1217</b> Fuel..... <b>BF7813</b> Radial Seal Air..... <b>RS4968</b> Air (2992388)..... <b>RS5535</b>	65.10, 65.10D w/8340.04 Eng. Lube (1901603)..... <b>BT347</b> Fuel (1901607)..... <b>BF7593</b>
50.9, 50.10 Lube (1901603)..... <b>BT347</b> Fuel (1901607)..... <b>BF7593</b>		
C50, C50N w/213 Vertical Eng. Lube (4585298)..... <b>P235</b>		
OM50 Lube (1901603)..... <b>BT347</b> Fuel (1901607)..... <b>BF7593</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IVECO Trucks (cont'd)	IVECO Trucks (cont'd)	IVECO Trucks (cont'd)
EuroCargo 65E10 w/8040.25, 8040.45 Engs. (01/91-04/01) Dual-Flow Lube (1903785)..... <b>BD232</b> Fuel (1902138)..... <b>BF5587-D</b> Fuel/Water Separator (1908547). <b>BF1217</b> Air..... <b>PA3597</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Steering..... <b>P106-HD</b>	EuroCargo II 65E14 w/Cummins Tector 4 Eng. (Euro 4/5) (05/06-on) Lube (2992242)..... <b>BT7237</b> Fuel..... <b>BF7813</b> Fuel/Water Separator (2992662). <b>BF1365</b> Radial Seal Air..... <b>RS4968</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Hyd. Breather (2992447)..... <b>P7336 KIT</b>	OM65 Lube (1901603)..... <b>BT347</b> Fuel (1901607)..... <b>BF7593</b>
EuroCargo 65E12 w/8040.25X.4000TC Eng. (01/91-04/01) Dual-Flow Lube (1903785)..... <b>BD232</b> Fuel (1902138)..... <b>BF5587-D</b> Fuel/Water Separator (1908547). <b>BF1217</b> Air..... <b>PA3597</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Steering..... <b>P106-HD</b>	EuroCargo ML65E14K w/8040TCA Eng. (12/91-on) Dual-Flow Lube..... <b>BD325</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel..... <b>BF7663</b> Air..... <b>PA3760</b> Steering..... <b>P106-HD</b>	OM65P, OM65PC (4x4) w/Iveco Eng. Lube..... <b>BT347</b> Can-Type Fuel..... <b>BF825 +</b> Air (9932594)..... <b>PA2426-FN</b>
EuroCargo ML65E12K w/8040TCA Eng. (12/91-on) Dual-Flow Lube..... <b>BD325</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel..... <b>BF7663</b> Air..... <b>PA3760</b> Steering..... <b>P106-HD</b>	EuroCargo ML65E14S w/8040TCA Eng. (12/91-on) Dual-Flow Lube..... <b>BD325</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel..... <b>BF7663</b> Air..... <b>PA3760</b> Steering..... <b>P106-HD</b>	OM65P, OM65PC (4x4) w/OM Eng. 147.6 mm Lube..... <b>BT267</b> 186.5 mm Lube..... <b>BT347</b> Can-Type Fuel..... <b>BF825 +</b> Air (9932594)..... <b>PA2426-FN</b>
EuroCargo ML65E12S w/8040TCA Eng. (12/91-on) Dual-Flow Lube..... <b>BD325</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel..... <b>BF7663</b> Air..... <b>PA3760</b> Steering..... <b>P106-HD</b>	EuroCargo 65E15 w/Cummins Tector Eng. (09/00-09/03) Lube..... <b>BT7237</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel..... <b>BF7813</b> Radial Seal Air..... <b>RS4968</b> Air (2992388)..... <b>RS5535</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Hyd. Breather (2992447)..... <b>P7336 KIT</b>	70.10 Lube (1907566)..... <b>BT347</b> Fuel (1901607)..... <b>BF7593</b>
EuroCargo 65E13 w/Cummins Tector Eng. (09/00-09/03) Lube..... <b>BT7237</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel..... <b>BF7813</b> Radial Seal Air..... <b>RS4968</b> Air (2992388)..... <b>RS5535</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Hyd. Breather (2992447)..... <b>P7336 KIT</b>	EuroCargo II 65E15 w/Cummins Tector 4 Eng. (06/03-on) Lube..... <b>BT7237</b> Fuel..... <b>BF7813</b> Fuel/Water Separator (2992662). <b>BF1365</b> Radial Seal Air..... <b>RS4968</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Hyd. Breather (2992447)..... <b>P7336 KIT</b>	70D6 w/Deutz F4L812D Eng. Lube (1160024)..... <b>BT292</b> 123.0 mm Fuel (1160243)..... <b>BF988 +</b> Opt. Fuel/Water Separator..... <b>BF1221 +</b>
EuroCargo II 65E13 w/Cummins Tector 4 Eng. (06/03-on) Lube..... <b>BT7237</b> Fuel..... <b>BF7813</b> Radial Seal Air..... <b>RS4968</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Hyd. Breather (2992447)..... <b>P7336 KIT</b>	EuroCargo 65E16 w/Cummins Tector 4 Eng. (Euro 4/5) (05/06-on) Lube (2992242)..... <b>BT7237</b> Fuel..... <b>BF7813</b> Fuel/Water Separator (2992662). <b>BF1365</b> Radial Seal Air..... <b>RS4968</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Hyd. Breather (2992447)..... <b>P7336 KIT</b>	70F, 70F10 Lube (1907566)..... <b>BT347</b> Fuel (1901607)..... <b>BF7593</b>
EuroCargo 65E14 w/8040.45.4000TCA Eng. (01/91-04/01) Dual-Flow Lube (1903785)..... <b>BD232</b> Fuel (1902138)..... <b>BF5587-D</b> Fuel/Water Separator (1908547). <b>BF1217</b> Air..... <b>PA3597</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Steering..... <b>P106-HD</b>	65F, 65F10 w/8340.04 Eng. Lube (1901603)..... <b>BT347</b> Fuel (1901607)..... <b>BF7593</b>	70L Can-Type Fuel (74651986)..... <b>BF825 +</b>
	65P, 65PC w/8040.02 Eng. Lube (1901603)..... <b>BT347</b> Can-Type Fuel (74651986)..... <b>BF825 +</b>	A70.12 w/8340.05 Eng. Lube (1901603)..... <b>BT347</b>
	65P, 65PC w/OM Eng. Lube (74730587)..... <b>BT267</b> Can-Type Fuel (74651986)..... <b>BF825 +</b> Air (9932594)..... <b>PA2426-FN</b>	75D6 w/Deutz F4L812D Eng. Lube (1160024)..... <b>BT292</b> 123.0 mm Fuel (1160243)..... <b>BF988 +</b> Opt. Fuel/Water Separator..... <b>BF1221 +</b>
		75.9 134.9 mm Lube (1174418)..... <b>BT292</b> 206.4 mm Lube (1174421)..... <b>B236 +</b> Fuel (1174423)..... <b>BF7931</b> O. Air (2165039)..... <b>PA2767</b> I. Air..... <b>PA3686</b>
		75.10 Lube (1907566)..... <b>BT347</b> Fuel (1901607)..... <b>BF7593</b>
		75F10 Lube (1907566)..... <b>BT347</b> Fuel (1901607)..... <b>BF7593</b>
		EuroCargo 75E12 w/8040.25X.4000TC Eng. (01/91-04/01) Dual-Flow Lube (1907582)..... <b>BD232</b> Fuel (1902138)..... <b>BF5587-D</b> Fuel/Water Separator (1908547). <b>BF1217</b> Air..... <b>PA3597</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Steering..... <b>P106-HD</b>
		EuroCargo 75E13 w/Cummins Tector Eng. (09/00-09/03) Lube..... <b>BT7237</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel..... <b>BF7813</b> Radial Seal Air..... <b>RS4968</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IVECO Trucks (cont'd)	IVECO Trucks (cont'd)	IVECO Trucks (cont'd)
EuroCargo 75E13 w/Cummins Tector Eng. (09/00-09/03) (Cont'd)	EuroCargo II 75E16 w/Cummins Tector 4 Eng. (Euro 4/5) (05/06-on) (Cont'd)	Eurocargo III ML75 E 14 w/Cummins Tector 4 F4A Eng. (06/08-on)
Air (2992388)..... RS5535	Radial Seal Air..... RS4968	Lube (504033399)..... BT7237
Air Dryer (Mann TB1374X)..... BA5374 *	Air Dryer (Mann TB1374X)..... BA5374 *	Fuel/Water Separator (2992662)..... BF1365
Hyd. Breather (2992447)..... P7336 KIT	Hyd. Breather (2992447)..... P7336 KIT	Fuel (2992241)..... BF7813
EuroCargo II 75E13 w/Cummins Tector 4 Eng. (06/03-on)	EuroCargo 75E17 w/Cummins Tector Eng. (09/00-09/03)	Air Dryer (1907612)..... BA5374 *
Lube..... BT7237	Lube..... BT7237	Urea (denoxtronic 1) (42562233).. PE5270
Fuel..... BF7813	Fuel/Water Separator (1907539)..... BF1217	Urea (denoxtronic 2) (42555073).. PE5271
Radial Seal Air..... RS4968	Fuel..... BF7813	EuroCargo ML75E14D w/8040TCA, 8060TCA Engs. (12/91-on)
Air Dryer (Mann TB1374X)..... BA5374 *	Radial Seal Air..... RS4968	Dual-Flow Lube..... BD325
Hyd. Breather (2992447)..... P7336 KIT	Air (2992388)..... RS5535	Fuel/Water Separator (1907539)..... BF1217
EuroCargo 75E14 w/8040.25, 8040.45, 8060.25 Engs. (01/91-04/01)	Air Dryer (Mann TB1374X)..... BA5374 *	Fuel..... BF7663
Dual-Flow Lube (1907582)..... BD232	Hyd. Breather (2992447)..... P7336 KIT	Air..... PA3760
Fuel (1902138)..... BF5587-D	EuroCargo II 75E17 w/Cummins Tector 4 Eng. (06/03-on)	Steering..... P106-HD
Fuel/Water Separator (1908547)..... BF1217	Lube..... BT7237	Eurocargo III ML75 E 16 w/Cummins Tector 4 F4A Eng. (06/08-on)
Air..... PA3597	Fuel..... BF7813	Lube (504033399)..... BT7237
Air Dryer (Mann TB1374X)..... BA5374 *	Radial Seal Air..... RS4968	Fuel/Water Separator (2992662)..... BF1365
Steering..... P106-HD	Air Dryer (Mann TB1374X)..... BA5374 *	Fuel (2992241)..... BF7813
EuroCargo II 75E14 w/Cummins Tector 4 Eng. (Euro 4/5) (05/06-on)	Hyd. Breather (2992447)..... P7336 KIT	Air Dryer (1907612)..... BA5374 *
Lube (2992242)..... BT7237	EuroCargo 75E18 w/Cummins Tector Eng. (09/00-09/03)	Urea (denoxtronic 1) (42562233).. PE5270
Fuel..... BF7813	Lube..... BT7237	Urea (denoxtronic 2) (42555073).. PE5271
Fuel/Water Separator (2992662)..... BF1365	Fuel/Water Separator (1907539)..... BF1217	OM70
Radial Seal Air..... RS4968	Fuel..... BF7813	Lube (1901603)..... BT347
Air Dryer (Mann TB1374X)..... BA5374 *	Radial Seal Air..... RS4968	Fuel (1901607)..... BF7593
Hyd. Breather (2992447)..... P7336 KIT	Air (2992388)..... RS5535	OM75
EuroCargo 75E15 w/Cummins Tector Eng. (09/00-09/03)	Air Dryer (Mann TB1374X)..... BA5374 *	Lube (1901603)..... BT347
Lube..... BT7237	Hyd. Breather (2992447)..... P7336 KIT	Fuel (1901607)..... BF7593
Fuel/Water Separator (1907539)..... BF1217	EuroCargo II 75E18 w/Cummins Tector 6 Eng. (06/03-on)	OM75P, OM75PCC (4x4) w/Iveco Eng.
Fuel..... BF7813	Lube..... BT7237	Lube..... BT267
Radial Seal Air..... RS4968	Fuel..... BF7813	Lube..... BT347
Air (2992388)..... RS5535	Radial Seal Air..... RS4968	Can-Type Fuel..... BF825 +
Air Dryer (Mann TB1374X)..... BA5374 *	Air Dryer (Mann TB1374X)..... BA5374 *	Air (9932594)..... PA2426-FN
Hyd. Breather (2992447)..... P7336 KIT	Hyd. Breather (2992447)..... P7336 KIT	EuroCargo ML75E12K w/8040TCA, 8060TCA Engs. (12/91-on)
EuroCargo 75E15 w/8060.25R.4200 Eng. (01/91-04/01)	Eurocargo III ML75 E 18 w/Cummins Tector 4 F4A Eng. (06/08-on)	Dual-Flow Lube..... BD325
Dual-Flow Lube (1907582)..... BD232	Lube (504033399)..... BT7237	Fuel/Water Separator (1907539)..... BF1217
Fuel (1902138)..... BF5587-D	Fuel/Water Separator (2992662)..... BF1365	Fuel..... BF7663
Fuel/Water Separator (1908547)..... BF1217	Fuel (2992241)..... BF7813	Air..... PA3760
Air..... PA3597	Air Dryer (1907612)..... BA5374 *	Steering..... P106-HD
Air Dryer (Mann TB1374X)..... BA5374 *	Urea (denoxtronic 1) (42562233).. PE5270	EuroCargo ML75E12S w/8040TCA, 8060TCA Engs. (12/91-on)
Steering..... P106-HD	Urea (denoxtronic 2) (42555073).. PE5271	Dual-Flow Lube..... BD325
EuroCargo II 75E15 w/Cummins Tector 4 Eng. (06/03-on)	EuroCargo II 75E19 w/Cummins Tector 6 Eng. (Euro 4/5) (05/06-on)	Fuel/Water Separator (1907539)..... BF1217
Lube..... BT7237	Lube (2992242)..... BT7237	Fuel..... BF7663
Fuel..... BF7813	Fuel..... BF7813	Air..... PA3760
Radial Seal Air..... RS4968	Fuel/Water Separator (2992662)..... BF1365	Steering..... P106-HD
Air Dryer (Mann TB1374X)..... BA5374 *	Radial Seal Air..... RS4968	EuroCargo ML75E14K w/8040TCA, 8060TCA Engs. (12/91-on)
Hyd. Breather (2992447)..... P7336 KIT	Air Dryer (Mann TB1374X)..... BA5374 *	Dual-Flow Lube..... BD325
EuroCargo II 75E16 w/Cummins Tector 4 Eng. (Euro 4/5) (05/06-on)	Hyd. Breather (2992447)..... P7336 KIT	Fuel/Water Separator (1907539)..... BF1217
Lube (2992242)..... BT7237	EuroCargo II 75E19 w/Cummins Tector 6 Eng. (Euro 4/5) (05/06-on)	Fuel..... BF7663
Fuel..... BF7813	Lube (2992242)..... BT7237	Air..... PA3760
Fuel/Water Separator (2992662)..... BF1365	Fuel..... BF7813	Steering..... P106-HD

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



IVECO Trucks (cont'd)	IVECO Trucks (cont'd)	IVECO Trucks (cont'd)
EuroCargo ML75E14S w/8040TCA, 8060TCA Eng. (12/91-on)	80.9	EuroCargo ML80E15S w/8060TCA Eng. (12/91-on)
Dual-Flow Lube..... BD325	134.9 mm Lube (1174418)..... BT292	Dual-Flow Lube..... BD325
Fuel/Water Separator (1907539). BF1217	206.4 mm Lube (1174421)..... B236 +	Fuel/Water Separator (1907539). BF1217
Fuel..... BF7663	Fuel (1174423)..... BF7931	Fuel..... BF7663
Air..... PA3760	O. Air (2165039)..... PA2767	Air..... PA3760
Steering..... P106-HD	I. Air..... PA3686	Steering..... P106-HD
EuroCargo ML75E15K w/8040TCA, 8060TCA Eng. (12/91-on)	80.13	EuroCargo II 80EL15 w/Cummins Tector 4 Eng. (06/03-on)
Dual-Flow Lube..... BD325	Lube (1174421)..... B236 +	Lube..... BT7237
Fuel/Water Separator (1907539). BF1217	Fuel (1174423)..... BF7931	Fuel..... BF7813
Fuel..... BF7663	295.3 mm Air (2168629)..... PA2891	Radial Seal Air..... RS4968
Air..... PA3760	349.3 mm Air (2165044)..... PA2845	Air Dryer (Mann TB1374X)..... BA5374 +
Steering..... P106-HD	80.13 w/GAMMA Z Eng.	Hyd. Breather (2992447)..... P7336 KIT
EuroCargo ML75E15S w/8040TCA, 8060TCA Eng. (12/91-on)	Lube (74730587)..... BT267	EuroCargo 80E/EL15 w/Cummins Tector Eng. (09/00-09/03)
Dual-Flow Lube..... BD325	Can-Type Fuel (74651986)..... BF825 +	Lube..... BT7237
Fuel/Water Separator (1907539). BF1217	80.13A	Fuel/Water Separator (1907539). BF1217
Fuel..... BF7663	Lube (1174420)..... B218	Fuel..... BF7813
Air..... PA3760	Fuel (1174423)..... BF7931	Radial Seal Air..... RS4968
Steering..... P106-HD	O. Air (2165054)..... PA2474	Air (2992388)..... RS5535
75P, 75PC w/Iveco Eng.	I. Air (2243946)..... PA2836	Air Dryer (Mann TB1374X)..... BA5374 +
Lube (1901603)..... BT347	80.13A w/Deutz BF6L913T, F6L913 Eng.	Hyd. Breather (2992447)..... P7336 KIT
Can-Type Fuel (74651986)..... BF825 +	Lube..... B236 +	EuroCargo ML80E15D w/8060TCA Eng. (12/91-on)
75P, 75PC w/OM Eng.	Fuel..... BF988 +	Dual-Flow Lube..... BD325
Lube (74730587)..... BT267	Opt. Fuel/Water Separator..... BF1221 +	Fuel/Water Separator (1907539). BF1217
Can-Type Fuel (74651986)..... BF825 +	EuroCargo 80E14 w/8040.45.4000 Eng. (01/96-04/01)	Fuel..... BF7663
Air..... PA2426-FN	Dual-Flow Lube..... BD232	Air..... PA3760
79.10	Fuel/Water Separator (1907539). BF1217	Steering..... P106-HD
Lube (1907566)..... BT347	Fuel (Mann WK842/2)..... BF5587-D	EuroCargo 80E15 w/8060.25R.4200 Eng. (01/96-04/01)
Fuel (1901607)..... BF7593	Air..... PA3597	Dual-Flow Lube..... BD232
79F10	Air Dryer (Mann TB1374X)..... BA5374 +	Fuel/Water Separator (1907539). BF1217
Lube (1907566)..... BT347	Steering..... P106-HD	Fuel (Mann WK842/2)..... BF5587-D
Fuel (1901607)..... BF7593	EuroCargo 80E15 w/8060.25, 8060.45 Eng. (01/91-04/01)	Air..... PA3597
79.12 TurboZeta	Dual-Flow Lube (1907582)..... BD232	Air Dryer (Mann TB1374X)..... BA5374 +
Dual-Flow Lube (1907583)..... BD232	Fuel (Mann WK842/2)..... BF5587-D	Steering..... P106-HD
Fuel (1902138)..... BF5587-D	Fuel/Water Separator (1908547). BF1217	EuroCargo 80E/EL17 w/Cummins Tector Eng. (09/00-09/03)
Air (1902040)..... PA1940	Air..... PA3597	Lube..... BT7237
79F13 w/8060.04 Eng.	Air Dryer (Mann TB1374X)..... BA5374 +	Fuel/Water Separator (1907539). BF1217
Lube (74730587)..... BT267	Steering..... P106-HD	Fuel..... BF7813
Can-Type Fuel (74651986)..... BF825 +	EuroCargo II 80E15 w/8060.25, 8060.45 Eng. (01/91-04/01)	Radial Seal Air..... RS4968
79.14 Series IV	Dual-Flow Lube (1907582)..... BD232	Air (2992388)..... RS5535
Lube (74730587)..... BT267	Fuel (Mann WK842/2)..... BF5587-D	Air Dryer (Mann TB1374X)..... BA5374 +
Fuel (1902138)..... BF5587-D	Fuel/Water Separator (1908547). BF1217	Hyd. Breather (2992447)..... P7336 KIT
79.14, 79.14 Series III w/8060.04 Eng.	Air..... PA3597	EuroCargo II 80E/EL17 w/Cummins 4 Tector Eng. (06/03-on)
Lube (74730587)..... BT267	Air Dryer (Mann TB1374X)..... BA5374 +	Lube..... BT7237
Can-Type Fuel (74651986)..... BF825 +	Steering..... P106-HD	Fuel..... BF7813
79.14 Zeta	EuroCargo ML80E15K w/8060TCA Eng. (12/91-on)	Radial Seal Air..... RS4968
Lube (74730587)..... BT267	Dual-Flow Lube..... BD325	Air Dryer (Mann TB1374X)..... BA5374 +
Fuel (1902138)..... BF5587-D	Fuel/Water Separator (1907539). BF1217	Hyd. Breather (2992447)..... P7336 KIT
Air (1902040)..... PA1940	Fuel..... BF7663	EuroCargo 80E18 w/Cummins Tector Eng. (09/00-04/01)
80	Air..... PA3760	Lube..... BT7237
Air..... PA1822-FN	Steering..... P106-HD	Fuel/Water Separator (1907539). BF1217
Some Air (8561046)..... PA2418-FN +		Fuel..... BF7813
		Radial Seal Air..... RS4968

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IVECO Trucks (cont'd)	IVECO Trucks (cont'd)	IVECO Trucks (cont'd)
EuroCargo 80E18 w/Cummins Tector Eng. (09/00-04/01) (Cont'd) Air (2992388)..... RS5535 Air Dryer (Mann TB1374X)..... BA5374 + Hyd. Breather (2992447)..... P7336 KIT	EuroCargo ML80E18S w/8060TCA Eng. (12/91-on) (Cont'd) Steering..... P106-HD	Eurocargo III ML80 E 22 w/Cummins Tector 6 F4A Eng. (06/08-on) (Cont'd) Urea (denoxtronic 2) (42555073).. PE5271
EuroCargo 80E18 w/8060.25V.4000 Eng. (01/91-04/01) Dual-Flow Lube..... BD232 Fuel/Water Separator (1907539). BF1217 Fuel..... BF5587-D Air..... PA3597 Air Dryer (Mann TB1374X)..... BA5374 + Steering..... P106-HD	EuroCargo II 80E19 w/Cummins Tector 6 Eng. (Euro 4/5) (05/06-on) Lube (2992242)..... BT7237 Fuel..... BF7813 Fuel/Water Separator (2992662). BF1365 Radial Seal Air..... RS4968 Air Dryer (Mann TB1374X)..... BA5374 + Hyd. Breather (2992447)..... P7336 KIT	80D, 80D6, 80D7 w/Deutz F4L812D Eng. Lube (1160024)..... BT292 123.0 mm Fuel (1160243)..... BF988 + Opt. Fuel/Water Separator..... BF1221 +
EuroCargo II 80E18 w/8060.25, 8060.45 Eng. (01/91-04/01) Dual-Flow Lube (1907582)..... BD232 Fuel (Mann WK842/2)..... BF5587-D Fuel/Water Separator (1908547). BF1217 Air..... PA3597 Air Dryer (Mann TB1374X)..... BA5374 + Steering..... P106-HD	EuroCargo 80E21 w/8060.45.4100 Eng. (01/91-04/01) Dual-Flow Lube (1907582)..... BD232 Fuel (Mann WK842/2)..... BF5587-D Fuel/Water Separator (1908547). BF1217 Air..... PA3597 Air Dryer (Mann TB1374X)..... BA5374 + Steering..... P106-HD	80D6, 80D7, 80D9 w/Deutz F4L912 Eng. Lube (1160024)..... BT292 Fuel (1160243)..... BF988 + Opt. Fuel/Water Separator..... BF1221 + 336.6 mm O. Air (2165039)..... PA2767 327.8 mm I. Air..... PA3686 349.3 mm O. Air (2165044)..... PA2845 341.3 mm I. Air..... PA2837
EuroCargo II 80E18 w/Cummins Tector 6 Eng. (06/03-on) Lube..... BT7237 Fuel..... BF7813 Radial Seal Air..... RS4968 Air Dryer (Mann TB1374X)..... BA5374 + Hyd. Breather (2992447)..... P7336 KIT	EuroCargo 80E21 w/Cummins Tector Eng. (09/00-09/03) Lube..... BT7237 Fuel/Water Separator (1907539). BF1217 Fuel..... BF7813 Radial Seal Air..... RS4968 Air (2992388)..... RS5535 Air Dryer (Mann TB1374X)..... BA5374 + Hyd. Breather (2992447)..... P7336 KIT	80F, 80F13 w/8060.04 Eng. Lube (74730587)..... BT267 Can-Type Fuel (74651986)..... BF825 +
EuroCargo II 80E/EL18 w/Cummins Tector 4 Eng. (Euro 4/5) (05/06-on) Lube (2992242)..... BT7237 Fuel..... BF7813 Fuel/Water Separator (2992662). BF1365 Radial Seal Air..... RS4968 Air Dryer (Mann TB1374X)..... BA5374 + Hyd. Breather (2992447)..... P7336 KIT	EuroCargo II 80E21 w/Cummins Tector 6 Eng. (06/03-on) Lube..... BT7237 Fuel..... BF7813 Radial Seal Air..... RS4968 Air Dryer (Mann TB1374X)..... BA5374 + Hyd. Breather (2992447)..... P7336 KIT	80NC w/8060.02 Eng. Lube (74730587)..... BT267 Can-Type Fuel (74651986)..... BF825 + Fuel Spin-on (1901607)..... BF7593 O. Air..... PA2418-FN + I. Air (79011387)..... PA2419 266.7 mm Some Air (9917419).... PA1646-FN
EuroCargo III ML80 E 18 w/Cummins Tector 4 F4A Eng. (06/08-on) Lube (504033399)..... BT7237 Fuel/Water Separator (2992662). BF1365 Fuel (2992241)..... BF7813 Air Dryer (1907612)..... BA5374 + Urea (denoxtronic 1) (42562233).. PE5270 Urea (denoxtronic 2) (42555073).. PE5271	EuroCargo ML80E21S w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... BD325 Fuel/Water Separator (1907539). BF1217 Fuel..... BF7663 Air..... PA3760 Steering..... P106-HD	80NC, 80NR, 80NT w/8060.20 Eng. Lube (74730587)..... BT267 Can-Type Fuel (74651986)..... BF825 + Air..... PA1822-FN Some Air..... PA2418-FN +
EuroCargo ML80E18K w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... BD325 Fuel/Water Separator (1907539). BF1217 Fuel..... BF7663 Air..... PA3760 Steering..... P106-HD	EuroCargo II 80E22 w/Cummins Tector 6 Eng. (Euro 4/5) (05/06-on) Lube (2992242)..... BT7237 Fuel..... BF7813 Fuel/Water Separator (2992662). BF1365 Radial Seal Air..... RS4968 Air Dryer (Mann TB1374X)..... BA5374 + Hyd. Breather (2992447)..... P7336 KIT	OM80 Lube (1901603)..... BT347 Fuel (1901607)..... BF7593
EuroCargo ML80E18S w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... BD325 Fuel/Water Separator (1907539). BF1217 Fuel..... BF7663 Air..... PA3760	Eurocargo III ML80 E 22 w/Cummins Tector 6 F4A Eng. (06/08-on) Lube (504033399)..... BT7237 Fuel/Water Separator (2992662). BF1365 Fuel (2992241)..... BF7813 Air Dryer (1907612)..... BA5374 + Urea (denoxtronic 1) (42562233).. PE5270	85D7, 85D9, 85D10, 85D11 w/Deutz F4L514 Eng. Lube Ele. (To 12/66) (1168465)... P41 Lube Spin-on (1/1967-on) (1160025)..... B236 + Fuel Ele. (1168398)..... PF950 Opt. Fuel/Water Separator..... BF1221 + Fuel Spin-on (1160243)..... BF988 +

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IVECO Trucks (cont'd)	IVECO Trucks (cont'd)	IVECO Trucks (cont'd)
EuroCargo 85E21 w/8060.25, 8060.45 Engs. Dual-Flow Lube (1907582)..... <b>BD232</b> Fuel..... <b>BF587-D +</b> Fuel/Water Separator (1908547). <b>BF1217</b> Air..... <b>PA3597</b> Steering (1902137)..... <b>P106-HD</b>	EuroCargo II 90E/EL18 w/Cummins Tector 4 Eng. (Euro 4/5) (05/06-on) Lube (2992242)..... <b>BT7237</b> Fuel..... <b>BF7813</b> Fuel/Water Separator (2992662). <b>BF1365</b> Radial Seal Air..... <b>RS4968</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Hyd. Breather (2992447)..... <b>P7336 KIT</b>	90F, 90F13 w/8060.04 Eng. Lube (74730587)..... <b>BT267</b> Can-Type Fuel (74651986)..... <b>BF825 +</b>
90.9 134.9 mm Lube (1174418)..... <b>BT292</b> 206.4 mm Lube (1174421)..... <b>B236 +</b> Fuel (1174423)..... <b>BF7931</b> O. Air (2165039)..... <b>PA2767</b> I. Air (A5309)..... <b>PA3686</b>	EuroCargo 90E21 w/Cummins Tector Eng. (09/00-09/03) Lube..... <b>BT7237</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel..... <b>BF7813</b> Radial Seal Air..... <b>RS4968</b> Air (2992388)..... <b>RS5535</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Hyd. Breather (2992447)..... <b>P7336 KIT</b>	90M5.3, 90M5.7, 90M5.9, 90M6.6, 90M7, 90M7.5 Lube (1160024)..... <b>BT292</b> Fuel (1160243)..... <b>BF988 +</b> Opt. Fuel/Water Separator..... <b>BF1221 +</b> O. Air (1975-on) (2165039)..... <b>PA2767</b> I. Air..... <b>PA3686</b>
90.13 Lube (1174421)..... <b>B236 +</b> Fuel (1174423)..... <b>BF7931</b> 295.3 mm Air (2168629)..... <b>PA2891</b> 349.3 mm Air (2165044)..... <b>PA2845</b>	EuroCargo II 90E21 w/Cummins Tector 6 Eng. (06/03-on) Lube..... <b>BT7237</b> Fuel..... <b>BF7813</b> Radial Seal Air..... <b>RS4968</b> Air (2992388)..... <b>RS5535</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Hyd. Breather (2992447)..... <b>P7336 KIT</b>	90NC w/8060.02 Eng. Lube (74730587)..... <b>BT267</b> Can-Type Fuel (74651986)..... <b>BF825 +</b> Fuel Spin-on (1901607)..... <b>BF7593</b> O. Air..... <b>PA2418-FN +</b> I. Air (79011387)..... <b>PA2419</b> 266.7 mm Some Air (9917419).... <b>PA1646-FN</b>
90.13 w/GAMMA Z Eng. Lube (74730587)..... <b>BT267</b> Can-Type Fuel (74651986)..... <b>BF825 +</b>	EuroCargo II 90E22 w/Cummins Tector 6 Eng. (Euro 4/5) (05/06-on) Lube (2992242)..... <b>BT7237</b> Fuel..... <b>BF7813</b> Fuel/Water Separator (2992662). <b>BF1365</b> Radial Seal Air..... <b>RS4968</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Hyd. Breather (2992447)..... <b>P7336 KIT</b>	90P, 90PC w/OM Eng. Lube (74730587)..... <b>BT267</b> Can-Type Fuel (74651986)..... <b>BF825 +</b> Air (9932594)..... <b>PA2426-FN</b>
EuroCargo 90E17 w/Cummins Tector Eng. (09/00-09/03) Lube..... <b>BT7237</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel..... <b>BF7813</b> 331.8 mm Radial Seal Air..... <b>RS4968</b> 410.4 mm Radial Seal Air (2992388)..... <b>RS5535</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Hyd. Breather (2992447)..... <b>P7336 KIT</b>	EuroCargo II 90E25 w/Cummins Tector 6 Eng. (Euro 4/5) (05/06-on) Lube (2992242)..... <b>BT7237</b> Fuel..... <b>BF7813</b> Fuel/Water Separator (2992662). <b>BF1365</b> Radial Seal Air..... <b>RS4968</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Hyd. Breather (2992447)..... <b>P7336 KIT</b>	90P, 90PC, 90PC/S w/Fiat Eng. Lube (1901603)..... <b>BT347</b> Can-Type Fuel (74651986)..... <b>BF825 +</b>
EuroCargo II 90E17 w/Cummins Tector 4 Eng. (06/03-on) Lube..... <b>BT7237</b> Fuel..... <b>BF7813</b> Radial Seal Air..... <b>RS4968</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Hyd. Breather (2992447)..... <b>P7336 KIT</b>	EuroCargo II 90E21 w/Cummins Tector 6 Eng. (06/03-on) Lube..... <b>BT7237</b> Fuel..... <b>BF7813</b> Radial Seal Air..... <b>RS4968</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Hyd. Breather (2992447)..... <b>P7336 KIT</b>	A90.13 Lube (1907567)..... <b>BT348</b> Can-Type Fuel (74651986)..... <b>BF825 +</b>
EuroCargo 90E18 w/Cummins Tector Eng. (09/00-09/03) Lube..... <b>BT7237</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel..... <b>BF7813</b> Radial Seal Air..... <b>RS4968</b> Air (2992388)..... <b>RS5535</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Hyd. Breather (2992447)..... <b>P7336 KIT</b>	EuroCargo II 90E21 w/Cummins Tector 6 Eng. (06/03-on) Lube..... <b>BT7237</b> Fuel..... <b>BF7813</b> Radial Seal Air..... <b>RS4968</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Hyd. Breather (2992447)..... <b>P7336 KIT</b>	OM90 Lube (1901603)..... <b>BT347</b> Fuel (1901607)..... <b>BF7593</b>
EuroCargo II 90E18 w/Cummins Tector 6 Eng. (06/03-on) Lube..... <b>BT7237</b> Fuel..... <b>BF7813</b> Radial Seal Air..... <b>RS4968</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Hyd. Breather (2992447)..... <b>P7336 KIT</b>	EuroCargo II 90E25 w/Cummins Tector 6 Eng. (Euro 4/5) (05/06-on) Lube (2992242)..... <b>BT7237</b> Fuel..... <b>BF7813</b> Fuel/Water Separator (2992662). <b>BF1365</b> Radial Seal Air..... <b>RS4968</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Hyd. Breather (2992447)..... <b>P7336 KIT</b>	OM90P, OM90PC (4x4) w/Iveco Eng. 147.6 mm Lube..... <b>BT267</b> 186.5 mm Lube..... <b>BT347</b> Can-Type Fuel..... <b>BF825 +</b> Air (9932594)..... <b>PA2426-FN</b>
EuroCargo 90E18 w/Cummins Tector 6 Eng. (06/03-on) Lube..... <b>BT7237</b> Fuel..... <b>BF7813</b> Radial Seal Air..... <b>RS4968</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Hyd. Breather (2992447)..... <b>P7336 KIT</b>	90D5.2, 90D5.5, 90D5.6, 90D6.5, 90D7.5 w/Deutz F4L913 Eng. Lube (1160024)..... <b>BT292</b> Fuel (1160243)..... <b>BF988 +</b> Opt. Fuel/Water Separator..... <b>BF1221 +</b> O. Air (1975-on) (2165039)..... <b>PA2767</b> I. Air..... <b>PA3686</b>	EuroCargo ML95E15WS w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... <b>BD325</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel..... <b>BF7663</b> Air..... <b>PA3760</b> Steering..... <b>P106-HD</b>
EuroCargo II 90E18 w/Cummins Tector 6 Eng. (06/03-on) Lube..... <b>BT7237</b> Fuel..... <b>BF7813</b> Radial Seal Air..... <b>RS4968</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Hyd. Breather (2992447)..... <b>P7336 KIT</b>	90D7, 90D11 w/Deutz F6L712 Eng. Lube Ele. (1168445)..... <b>P25</b> Fuel Ele. (1168398)..... <b>PF950</b>	EuroCargo ML95E15WT w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... <b>BD325</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel..... <b>BF7663</b> Air..... <b>PA3760</b> Steering..... <b>P106-HD</b>
EuroCargo II 90E18 w/Cummins Tector 6 Eng. (06/03-on) Lube..... <b>BT7237</b> Fuel..... <b>BF7813</b> Radial Seal Air..... <b>RS4968</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Hyd. Breather (2992447)..... <b>P7336 KIT</b>	90D7, 90D8, 90D9 w/Deutz F6L812, F6L812D Engs. Lube Ele. (1168443)..... <b>P184</b> Lube Spin-on (1160025)..... <b>B236 +</b>	EuroCargo ML95E21WS w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... <b>BD325</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel..... <b>BF7663</b> Air..... <b>PA3760</b> Steering..... <b>P106-HD</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IVECO Trucks (cont'd)	IVECO Trucks (cont'd)	IVECO Trucks (cont'd)
EuroCargo ML95E21WT w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... BD325 Fuel/Water Separator (1907539). BF1217 Fuel..... BF7663 Air..... PA3760 Steering..... P106-HD	100EL Air (8561046)..... PA2418-FN + Some Air..... PA1822-FN	EuroCargo II 100E17 w/Cummins Tector 4 Eng. (06/03-on) Lube..... BT7237 Fuel..... BF7813 Radial Seal Air..... RS4968 Air Dryer (Mann TB1374X)..... BA5374 + Hyd. Breather (2992447)..... P7336 KIT
95.14 w/8060.04 Eng. Lube (1901602)..... BT348 Can-Type Fuel (1901687)..... BF825 +	100F, 100F13 w/8060.04 Eng. Lube (1907567)..... BT348 Can-Type Fuel (74651986)..... BF825 +	EuroCargo 100E18 w/8060.25V.4000 Eng. (01/91-04/01) Dual-Flow Lube (1907582)..... BD232 Fuel (Mann WK842/2)..... BF5587-D Fuel/Water Separator (1908547). BF1217 Air (1905983)..... PA3597 Air Dryer (Mann TB1374X)..... BA5374 + Steering..... P106-HD
95.14 Series III Lube (1907567)..... BT348 Can-Type Fuel (1901929)..... BF825 + Air (1902040)..... PA1940	100NC w/8060.02 Eng. Lube (74730587)..... BT267 Can-Type Fuel (74651986)..... BF825 + Fuel Spin-on (1901607)..... BF7593 O. Air..... PA2418-FN + I. Air..... PA2419 266.7 mm Some Air..... PA1646-FN	EuroCargo 100E18 w/Cummins Tector Eng. (09/00-09/03) Lube..... BT7237 Fuel/Water Separator (1907539). BF1217 Fuel..... BF7813 Radial Seal Air..... RS4968 Air (2992388)..... RS5535 Air Dryer (Mann TB1374X)..... BA5374 + Hyd. Breather (2992447)..... P7336 KIT
95.14 Series IV, 95.14 Zeta Lube (1907567)..... BT348 Fuel (1902138)..... BF5587-D Air (1902040)..... PA1940	100NR, 100PC Air (8561046)..... PA2418-FN + Some Air..... PA1822-FN	EuroCargo II 100E18 w/Cummins Tector 4 Eng. (Euro 4/5) (05/06-on) Lube (2992242)..... BT7237 Fuel..... BF7813 Fuel/Water Separator (2992662). BF1365 Radial Seal Air..... RS4968 Air Dryer (Mann TB1374X)..... BA5374 + Hyd. Breather (2992447)..... P7336 KIT
EuroCargo 95E15 w/8060.25. Eng. (01/91-04/01) Dual-Flow Lube (1907582)..... BD232 Fuel (Mann WK842/2)..... BF5587-D Fuel/Water Separator (1908547). BF1217 Air..... PA3597 Air Dryer (Mann TB1374X)..... BA5374 + Steering (1902137)..... P106-HD	100.13 w/8060.04 Eng. Lube (1907567)..... BT348 Can-Type Fuel (74651986)..... BF825 +	EuroCargo III ML100 E 18 w/Cummins Tector 4 F4A Eng. (06/08-on) Lube (504033399)..... BT7237 Fuel/Water Separator (2992662). BF1365 Fuel (2992241)..... BF7813 Air Dryer (1907612)..... BA5374 + Urea (denoxtronic 1) (42562233).. PE5270 Urea (denoxtronic 2) (42555073).. PE5271
EuroCargo 95E18 w/w/8060.25 Eng. (01/91-09/03) Dual-Flow Lube (1903785)..... BD232 Fuel/Water Separator (1907539). BF1217 Fuel (1902138)..... BF5587-D Air (1905983)..... PA3597 Air Dryer (1907612)..... BA5374 + Steering (1902137)..... P106-HD	EuroCargo 100E15 w/8060.25R.4200 Eng. (01/91-04/01) Dual-Flow Lube (1907582)..... BD232 Fuel (Mann WK842/2)..... BF5587-D Fuel/Water Separator (1908547). BF1217 Air (1905983)..... PA3597 Air Dryer (Mann TB1374X)..... BA5374 + Steering..... P106-HD	EuroCargo ML100E18K w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... BD325 Fuel/Water Separator (1907539). BF1217 Fuel..... BF7663 Air..... PA3760 Steering..... P106-HD
EuroCargo 95E21 w/8060.45 Eng. (01/91-04/01) Dual-Flow Lube (1907582)..... BD232 Fuel (Mann WK842/2)..... BF5587-D Fuel/Water Separator (1908547). BF1217 Air..... PA3597 Air Dryer (Mann TB1374X)..... BA5374 + Steering (1902137)..... P106-HD	EuroCargo ML100E15K w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... BD325 Fuel/Water Separator (1907539). BF1217 Fuel..... BF7663 Air..... PA3760 Steering..... P106-HD	EuroCargo ML100E15S w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... BD325 Fuel/Water Separator (1907539). BF1217 Fuel..... BF7663 Air..... PA3760 Steering..... P106-HD
100EC w/8060.02 Eng. Lube (74730587)..... BT267 Can-Type Fuel (74651986)..... BF825 + Fuel Spin-on (1901607)..... BF7593 O. Air..... PA2418-FN + I. Air..... PA2419 266.7 mm Some Air..... PA1646-FN	EuroCargo ML100E15S w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... BD325 Fuel/Water Separator (1907539). BF1217 Fuel..... BF7663 Air..... PA3760 Steering..... P106-HD	EuroCargo ML100E17 w/Cummins Tector Eng. (09/00-09/03) Lube..... BT7237 Fuel/Water Separator (1907539). BF1217 Fuel..... BF7813 Radial Seal Air..... RS4968 Air (2992388)..... RS5535 Air Dryer (Mann TB1374X)..... BA5374 + Hyd. Breather (2992447)..... P7336 KIT
Series 100 Lube (To 10/72)..... BT347 Lube (10/72-on)..... BT349 Fuel Ele..... PF906	100.16 w/Deutz BF6L913 Eng. Lube..... B218 Fuel..... BF988 + O. Air..... PA2474 I. Air..... PA2836	EuroCargo ML100E18K w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... BD325 Fuel/Water Separator (1907539). BF1217 Fuel..... BF7663 Air..... PA3760 Steering..... P106-HD
100D7, 100D8, 100D10, 100D11 w/Deutz F6L812, F6L812D Eng. Lube Ele..... P184 Lube Spin-on..... B236 +		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>IVECO Trucks (cont'd)</b>	
EuroCargo ML100E18S w/8060TCA Eng. (12/91-on)	
Dual-Flow Lube.....	BD325
Fuel/Water Separator (1907539).....	BF1217
Fuel.....	BF7663
Air.....	PA3760
Steering.....	P106-HD
EuroCargo II 100E19 w/Cummins Tector 6 Eng. (Euro 4/5) (05/06-on)	
Lube (2992242).....	BT7237
Fuel.....	BF7813
Fuel/Water Separator (2992662).....	BF1365
Radial Seal Air.....	RS4968
Air Dryer (Mann TB1374X).....	BA5374 +
Hyd. Breather (2992447).....	P7336 KIT
EuroCargo 100E21 w/8060.45.4100 Eng. (01/91-04/01)	
Dual-Flow Lube (1907582).....	BD232
Fuel (Mann WK842/2).....	BF5587-D
Fuel/Water Separator (1908547).....	BF1217
Air (1905983).....	PA3597
Air Dryer (Mann TB1374X).....	BA5374 +
Steering.....	P106-HD
EuroCargo 100E21 w/Cummins Tector Eng. (09/00-09/03)	
Lube.....	BT7237
Fuel/Water Separator (1907539).....	BF1217
Fuel.....	BF7813
Radial Seal Air.....	RS4968
Air (2992388).....	RS5535
Air Dryer (Mann TB1374X).....	BA5374 +
Hyd. Breather (2992447).....	P7336 KIT
EuroCargo II 100E21 w/Cummins Tector 6 Eng. (06/03-on)	
Lube.....	BT7237
Fuel.....	BF7813
Radial Seal Air.....	RS4968
Air Dryer (Mann TB1374X).....	BA5374 +
Hyd. Breather (2992447).....	P7336 KIT
EuroCargo ML100E21S w/8060TCA Eng. (12/91-on)	
Dual-Flow Lube.....	BD325
Fuel/Water Separator (1907539).....	BF1217
Fuel.....	BF7663
Air.....	PA3760
Steering.....	P106-HD
EuroCargo II 100E22 w/Cummins Tector 6 Eng. (Euro 4/5) (05/06-on)	
Lube (2992242).....	BT7237
Fuel.....	BF7813
Fuel/Water Separator (2992662).....	BF1365
Radial Seal Air.....	RS4968
Air Dryer (Mann TB1374X).....	BA5374 +
Hyd. Breather (2992447).....	P7336 KIT

<b>IVECO Trucks (cont'd)</b>	
Eurocargo III ML100 E 22 w/Cummins Tector 6 F4A Eng. (06/08-on)	
Lube (504033399).....	BT7237
Fuel/Water Separator (2992662).....	BF1365
Fuel (2992241).....	BF7813
Air Dryer (1907612).....	BA5374 +
Urea (denoxtronic 1) (42562233).....	PE5270
Urea (denoxtronic 2) (42555073).....	PE5271
N100	
Lube.....	BT267
Can-Type Fuel.....	BF825 +
N100, OM100NC	
Air.....	PA1822-FN
Some Air (8561046).....	PA2418-FN +
Z100, Z100A w/Deutz F5L912 Eng.	
Lube.....	[2] B236 +
Can-Type Fuel.....	[2] BF825 +
Fuel Spin-on.....	[2] BF988 +
Fuel/Water Separator.....	BF1221 +
Air (998-5779).....	PA1882
109.14 Series III, Series IV, ZETA	
Lube (1907567).....	BT348
Can-Type Fuel (Series III) (1901929).....	BF825 +
Fuel (Exc. Series III) (1902138).....	BF5587-D
Air (1902040).....	PA1940
110A1	
Lube Spin-on.....	BT267
Can-Type Fuel.....	BF825 +
110D7, 110D8, 110D9, 110D11 w/Deutz F6L812 Eng.	
Lube Ele. (1168469).....	P42
Lube Spin-on (1160025).....	B236 +
Fuel/Water Separator.....	BF1221 +
P. Fuel (2133558).....	BF586
S. Fuel (2133943).....	BF587
Single Fuel (1160243).....	BF988 +
O. Air (2165044).....	PA2845
I. Air.....	PA2837
110EL, 110P, 110R, 110T	
Lube Spin-on.....	BT267
Can-Type Fuel.....	BF825 +
110.13	
Lube (1174421).....	B236 +
Fuel.....	BF988 +
Air (2168629).....	PA2891
110.14 (4x4)	
Lube (1907567).....	BT348
Can-Type Fuel.....	BF825 +
Fuel Spin-on.....	BF7593
EuroCargo ML110E15K w/8060TCA Eng. (12/91-on)	
Dual-Flow Lube.....	BD325
Fuel/Water Separator (1907539).....	BF1217
Fuel.....	BF7663
Air.....	PA3760

<b>IVECO Trucks (cont'd)</b>	
EuroCargo ML110E15K w/8060TCA Eng. (12/91-on) (Cont'd)	
Steering.....	P106-HD
EuroCargo ML110E15S w/8060TCA Eng. (12/91-on)	
Dual-Flow Lube.....	BD325
Fuel/Water Separator (1907539).....	BF1217
Fuel.....	BF7663
Air.....	PA3760
Steering.....	P106-HD
110.17 w/8360.03	
Lube (1901604).....	BT349
Fuel (1901605).....	BF783
Air (9917419).....	PA1646-FN
EuroCargo II 110EL17 w/Cummins Tector 4 Eng. (06/03-on)	
Lube.....	BT7237
Fuel.....	BF7813
Radial Seal Air.....	RS4968
Air Dryer (Mann TB1374X).....	BA5374 +
Hyd. Breather (2992447).....	P7336 KIT
EuroCargo II 110EL18 w/Cummins Tector 4 Eng. (Euro 4/5) (05/06-on)	
Lube (2992242).....	BT7237
Fuel.....	BF7813
Fuel/Water Separator (2992662).....	BF1365
Radial Seal Air.....	RS4968
Air Dryer (Mann TB1374X).....	BA5374 +
Hyd. Breather (2992447).....	P7336 KIT
EuroCargo ML110E18S w/8060TCA Eng. (12/91-on)	
Dual-Flow Lube.....	BD325
Fuel/Water Separator (1907539).....	BF1217
Fuel.....	BF7663
Air.....	PA3760
Steering.....	P106-HD
EuroCargo II 110EL21 w/Cummins Tector 6 Eng. (06/03-on)	
Lube.....	BT7237
Fuel.....	BF7813
Radial Seal Air.....	RS4968
Air Dryer (Mann TB1374X).....	BA5374 +
Hyd. Breather (2992447).....	P7336 KIT
EuroCargo II 110E22 w/Cummins Tector 6 Eng. (Euro 4/5) (05/06-on)	
Lube (2992242).....	BT7237
Fuel.....	BF7813
Fuel/Water Separator (2992662).....	BF1365
Radial Seal Air.....	RS4968
Air Dryer (Mann TB1374X).....	BA5374 +
Hyd. Breather (2992447).....	P7336 KIT
EuroCargo ML110E23K w/8060TCA Eng. (12/91-on)	
Dual-Flow Lube.....	BD325
Fuel/Water Separator (1907539).....	BF1217
Fuel.....	BF7663

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IVECO Trucks (cont'd)	IVECO Trucks (cont'd)	IVECO Trucks (cont'd)
EuroCargo ML110E23K w/8060TCA Eng. (12/91-on) (Cont'd) Air..... PA3760 Steering..... P106-HD	120 Lube Ele. (To 1972)..... P20-HD + Lube Spin-on (1972-on)..... BT349 Fuel (To 1971)..... PF906 Air..... PA1646-FN	EuroCargo ML120EL15S w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... BD325 Fuel/Water Separator (1907539) BF1217 Fuel..... BF7663 Air..... PA3760 Steering..... P106-HD
EuroCargo ML110E23S w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... BD325 Fuel/Water Separator (1907539) BF1217 Fuel..... BF7663 Air..... PA3760 Steering..... P106-HD	120 w/Deutz F6L613, F6L614, F6L913 Eng. Lube..... B236 + Fuel/Water Separator..... BF1221 + Fuel Ele. (PM325)..... PF950 Fuel Spin-on..... BF988 + Air (2168629)..... PA2891	120.16 w/Deutz BF6L913 Eng. Lube..... B218 Fuel..... BF988 + I. Air (42480759)..... PA2836
Eurocargo II 110 E/EL 25 w/Cummins Tector 6 Euro 4/5 Eng. (05/06-08/08) Lube (504033399)..... BT7237 Fuel/Water Separator (2992662) BF1365 Fuel (2992241)..... BF7813 Air Dryer (1907612)..... BA5374 + Breather (2992447)..... P7336 KIT Urea (denoxtronic 1) (42562233).. PE5270 Urea (denoxtronic 2) (42555073).. PE5271	120D7, 120D9, 120D11, 120D12, 120D13 w/Deutz Eng. Lube Ele. (1168469)..... P42 Lube Spin-on (1160025)..... B236 + Fuel/Water Separator..... BF1221 + Single Fuel (1160243)..... BF988 + P. Fuel (2133558)..... BF586 S. Fuel (2133943)..... BF587 O. Air..... PA2845 I. Air..... PA2837	EuroCargo 120EL17 w/Cummins Tector Eng. (09/00-09/03) Lube..... BT7237 Fuel/Water Separator (1907539) BF1217 Fuel..... BF7813 330.2 mm Radial Seal Air..... RS4968 414.3 mm Radial Seal Air..... RS4969 Air (2992388)..... RS5535 Air Dryer (Mann TB1374X)..... BA5374 + Hyd. Breather (2992447)..... P7336 KIT
110NC, 110NR, 110NT, 110PC w/8060.02 Eng. Lube..... BT267 Can-Type Fuel..... BF825 + Fuel Spin-on..... BF7593 O. Air..... PA2418-FN + I. Air (79011387)..... PA2419 Single Air (9917419)..... PA1646-FN	120.13 147.6 mm Lube (1907567)..... BT348 206.4 mm Lube (1174421)..... B236 + Can-Type Fuel (74651986)..... BF825 + Fuel Spin-on (1174423)..... BF7931 295.3 mm Air (2168629)..... PA2891 349.3 mm Air (2165044)..... PA2845	EuroCargo 120E18 w/8060.25V.4080 Eng. (09/91-04/01) Dual-Flow Lube (1907582)..... BD232 Fuel (1902138)..... BF5587-D Fuel/Water Separator (1908547) BF1217 Air (1905983)..... PA3597 Air Dryer (Mann TB1374X)..... BA5374 + Steering (1902137)..... P106-HD
110NL Lube Spin-on (74730587)..... BT267 Can-Type Fuel (74651986)..... BF825 + Air (9917419)..... PA1646-FN	120.13, 120.14 w/8360.04 Eng. Lube (1901604)..... BT349 Fuel Spin-on (8821823)..... BF783	EuroCargo 120E18 w/Cummins Tector Eng. (09/00-09/03) Lube..... BT7237 Fuel/Water Separator (1907539) BF1217 Fuel..... BF7813 330.2 mm Radial Seal Air..... RS4968 414.3 mm Radial Seal Air..... RS4969 Air (2992388)..... RS5535 Air Dryer (Mann TB1374X)..... BA5374 + Steering (1902137)..... P106-HD
Z110, Z110A w/8060 Eng. Lube..... BT348 Fuel Spin-on..... [2] BF988 + Can-Type Fuel..... [2] BF825 + Air..... PA1972	EuroCargo 120E15 w/8060.25R.4280 Eng. (12/91-04/01) Dual-Flow Lube (1907582)..... BD232 Fuel (1902138)..... BF5587-D Fuel/Water Separator (1908547) BF1217 Air (1905983)..... PA3597 Air Dryer (Mann TB1374X)..... BA5374 + Steering (1902137)..... P106-HD	EuroCargo 120E18 w/Cummins Tector 6 Eng. (06/03-on) Lube..... BT7237 Fuel..... BF7813 Radial Seal Air..... RS4968 Air Dryer (Mann TB1374X)..... BA5374 + Hyd. Breather (2992447)..... P7336 KIT
112 w/Deutz F6L613, F6L614, F6L913 Eng. Lube..... B236 + Fuel Ele..... PF950 Fuel Spin-on..... BF988 + Fuel/Water Separator..... BF1221 + Air (2168629)..... PA2891	EuroCargo ML120E15K w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... BD325 Fuel/Water Separator (1907539) BF1217 Fuel..... BF7663 Air..... PA3760 Steering..... P106-HD	EuroCargo II 120E18 w/Cummins Tector 6 Eng. (06/03-on) Lube..... BT7237 Fuel..... BF7813 Radial Seal Air..... RS4968 Air Dryer (Mann TB1374X)..... BA5374 + Hyd. Breather (2992447)..... P7336 KIT
115.14 Lube (1901602)..... BT348 Can-Type Fuel (1901687)..... BF825 + Fuel Spin-on (1902138)..... BF5587-D Air (1902040)..... PA1940	EuroCargo ML120E15S w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... BD325 Fuel/Water Separator (1907539) BF1217 Fuel..... BF7663 Air..... PA3760 Steering..... P106-HD	Eurocargo III ML120 E 18 w/Cummins Tector 6 F4A Eng. (06/08-on) Lube (504033399)..... BT7237 Fuel/Water Separator (2992662) BF1365 Fuel (2992241)..... BF7813 Air Dryer (1907612)..... BA5374 + Urea (denoxtronic 1) (42562233).. PE5270 Urea (denoxtronic 2) (42555073).. PE5271
115.17 Series 1 F-F Lube (1901602)..... BT348 Dual-Flow Lube (1907582)..... BD232 Can-Type Fuel..... BF825 + Air (1902077)..... PA2405		
115.17 Series 2 Dual-Flow Lube..... BD232 Fuel Spin-on (4764693)..... BF988 + Air..... PA2405		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IVECO Trucks (cont'd)	IVECO Trucks (cont'd)	IVECO Trucks (cont'd)
EuroCargo ML120E18D w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... <b>BD325</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel..... <b>BF7663</b> Air..... <b>PA3760</b> Steering..... <b>P106-HD</b>	EuroCargo ML120E18S w/8060TCA Eng. (12/91-on) (Cont'd) Air..... <b>PA3760</b> Steering..... <b>P106-HD</b>	EuroCargo ML120EL21R w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... <b>BD325</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel..... <b>BF7663</b> Air..... <b>PA3760</b> Steering..... <b>P106-HD</b>
EuroCargo ML120E18K w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... <b>BD325</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel..... <b>BF7663</b> Air..... <b>PA3760</b> Steering..... <b>P106-HD</b>	EuroCargo ML120EL18R/P w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... <b>BD325</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel..... <b>BF7663</b> Air..... <b>PA3760</b> Steering..... <b>P106-HD</b>	EuroCargo ML120EL21R/P w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... <b>BD325</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel..... <b>BF7663</b> Air..... <b>PA3760</b> Steering..... <b>P106-HD</b>
EuroCargo ML120E18R w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... <b>BD325</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel..... <b>BF7663</b> Air..... <b>PA3760</b> Steering..... <b>P106-HD</b>	EuroCargo ML120EL18RS w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... <b>BD325</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel..... <b>BF7663</b> Air..... <b>PA3760</b> Steering..... <b>P106-HD</b>	EuroCargo ML120EL21S w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... <b>BD325</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel..... <b>BF7663</b> Air..... <b>PA3760</b> Steering..... <b>P106-HD</b>
Eurocargo III ML 120 EL 18 w/Cummins Tector 4 F4A Eng. (06/08-on) Lube (504033399)..... <b>BT7237</b> Fuel/Water Separator (2992662). <b>BF1365</b> Fuel (2992241)..... <b>BF7813</b> Air Dryer (1907612)..... <b>BA5374 +</b> Urea (denoxtronic 1) (42562233).. <b>PE5270</b> Urea (denoxtronic 2) (42555073).. <b>PE5271</b>	EuroCargo ML120EL18S w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... <b>BD325</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel..... <b>BF7663</b> Air..... <b>PA3760</b> Steering..... <b>P106-HD</b>	EuroCargo II 120E22 w/Cummins Tector 6 Eng. (Euro 5/6) (05/06-on) Lube (2992242)..... <b>BT7237</b> Fuel..... <b>BF7813</b> Fuel/Water Separator (2992662). <b>BF1365</b> Radial Seal Air..... <b>RS4968</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Hyd. Breather (2992447)..... <b>P7336 KIT</b>
Eurocargo II 120 E/EL 18 w/Cummins Tector 4 Euro 4/5 Eng. (05/06-08/08) Lube (504033399)..... <b>BT7237</b> Fuel/Water Separator (2992662). <b>BF1365</b> Fuel (2992241)..... <b>BF7813</b> Air Dryer (1907612)..... <b>BA5374 +</b> Breather (2992447)..... <b>P7336 KIT</b> Urea (denoxtronic 1) (42562233).. <b>PE5270</b> Urea (denoxtronic 2) (42555073).. <b>PE5271</b>	EuroCargo ML120EL18/P w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... <b>BD325</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel..... <b>BF7663</b> Air..... <b>PA3760</b> Steering..... <b>P106-HD</b>	Eurocargo III ML 120 E 22 w/Cummins Tector 6 F4A Eng. (06/08-on) Lube (504033399)..... <b>BT7237</b> Fuel/Water Separator (2992662). <b>BF1365</b> Fuel (2992241)..... <b>BF7813</b> Air Dryer (1907612)..... <b>BA5374 +</b> Urea (denoxtronic 1) (42562233).. <b>PE5270</b> Urea (denoxtronic 2) (42555073).. <b>PE5271</b>
EuroCargo ML120E18R/P w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... <b>BD325</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel..... <b>BF7663</b> Air..... <b>PA3760</b> Steering..... <b>P106-HD</b>	EuroCargo II 120E19 w/Cummins Tector 6 Eng. (Euro 5/6) (05/06-on) Lube (2992242)..... <b>BT7237</b> Fuel..... <b>BF7813</b> Fuel/Water Separator (2992662). <b>BF1365</b> Radial Seal Air..... <b>RS4968</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Hyd. Breather (2992447)..... <b>P7336 KIT</b>	Eurocargo III ML 120 EL 22 w/Cummins Tector 6 F4A Eng. (06/08-on) Lube (504033399)..... <b>BT7237</b> Fuel/Water Separator (2992662). <b>BF1365</b> Fuel (2992241)..... <b>BF7813</b> Air Dryer (1907612)..... <b>BA5374 +</b> Urea (denoxtronic 1) (42562233).. <b>PE5270</b> Urea (denoxtronic 2) (42555073).. <b>PE5271</b>
EuroCargo ML120E18S w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... <b>BD325</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel..... <b>BF7663</b> Air..... <b>PA3760</b> Steering..... <b>P106-HD</b>	EuroCargo 120EL21 w/Cummins Tector Eng. (09/00-09/03) Lube..... <b>BT7237</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel..... <b>BF7813</b> 330.2 mm Radial Seal Air..... <b>RS4968</b> 414.3 mm Radial Seal Air..... <b>RS4969</b> Air (2992388)..... <b>RS5535</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Hyd. Breather (2992447)..... <b>P7336 KIT</b>	Eurocargo III ML 120 EL 22 w/Cummins Tector 6 F4A Eng. (06/08-on) Lube (504033399)..... <b>BT7237</b> Fuel/Water Separator (2992662). <b>BF1365</b> Fuel (2992241)..... <b>BF7813</b> Air Dryer (1907612)..... <b>BA5374 +</b> Urea (denoxtronic 1) (42562233).. <b>PE5270</b> Urea (denoxtronic 2) (42555073).. <b>PE5271</b>
EuroCargo ML120E18R/P w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... <b>BD325</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel..... <b>BF7663</b> Air..... <b>PA3760</b> Steering..... <b>P106-HD</b>	EuroCargo II 120E/EL21 w/Cummins Tector 6 Eng. (06/03-on) Lube..... <b>BT7237</b> Fuel..... <b>BF7813</b> Radial Seal Air..... <b>RS4968</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Hyd. Breather (2992447)..... <b>P7336 KIT</b>	EuroCargo 120E23 w/8060.45.6090 Eng. (02/92-04/01) Dual-Flow Lube..... <b>BD325</b> Fuel..... <b>BF7663</b> Fuel/Water Separator (1908547). <b>BF1217</b> Air..... <b>PA3760</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Steering (1902137)..... <b>P106-HD</b>
EuroCargo ML120E18S w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... <b>BD325</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel..... <b>BF7663</b>	EuroCargo ML120EL21/P w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... <b>BD325</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel..... <b>BF7663</b> Air..... <b>PA3760</b> Steering..... <b>P106-HD</b>	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IVECO Trucks (cont'd)	IVECO Trucks (cont'd)	IVECO Trucks (cont'd)
EuroCargo ML120E23K w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... <b>BD325</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel..... <b>BF7663</b> Air..... <b>PA3760</b> Steering..... <b>P106-HD</b>	EuroCargo II 120E24 w/Cummins Tector 6 Eng. (06/03-on) (Cont'd) Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Hyd. Breather (2992447)..... <b>P7336 KIT</b>	Z120TA Lube (To S/N 33436)..... <b>[2] BT348</b> Dual-Flow Lube (1902076)..... <b>BD232</b> Fuel Spin-on..... <b>[2] BF988 +</b> Air (1902077)..... <b>PA2405</b>
EuroCargo ML120E23/P w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... <b>BD325</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel..... <b>BF7663</b> Air..... <b>PA3760</b> Steering..... <b>P106-HD</b>	EuroCargo II 120E25 w/Cummins Tector 6 Eng. (Euro 4/5) (05/06-on) Lube (2992242)..... <b>BT7237</b> Fuel..... <b>BF7813</b> Fuel/Water Separator (2992662). <b>BF1365</b> Radial Seal Air..... <b>RS4968</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Hyd. Breather (2992447)..... <b>P7336 KIT</b>	125, 126 w/Deutz Eng. Lube (1160025)..... <b>B236 +</b> Fuel Ele. (1168398)..... <b>PF950</b> Fuel Spin-on (1160243)..... <b>BF988 +</b> Opt. Fuel/Water Separator..... <b>BF1221 +</b> Air (2168629)..... <b>PA2891</b>
EuroCargo ML120E23R w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... <b>BD325</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel..... <b>BF7663</b> Air..... <b>PA3760</b> Steering..... <b>P106-HD</b>	EuroCargo III ML120 E 25 w/Cummins Tector 6 F4A Eng. (06/08-on) Lube (504033399)..... <b>BT7237</b> Fuel/Water Separator (2992662). <b>BF1365</b> Fuel (2992241)..... <b>BF7813</b> Air Dryer (1907612)..... <b>BA5374 +</b> Urea (denoxtronic 1) (42562233).. <b>PE5270</b> Urea (denoxtronic 2) (42555073).. <b>PE5271</b>	159.24 w/8220.22 Eng. Lube (4667339)..... <b>BT349</b> Fuel (1901605)..... <b>BF783</b>
EuroCargo ML120E23R/P w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... <b>BD325</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel..... <b>BF7663</b> Air..... <b>PA3760</b> Steering..... <b>P106-HD</b>	EuroCargo 120E28 w/Cummins Tector Eng. (09/00-09/03) Lube..... <b>BT7237</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel..... <b>BF7813</b> 330.2 mm Radial Seal Air..... <b>RS4968</b> 414.3 mm Radial Seal Air..... <b>RS4969</b> Air (2992388)..... <b>RS5535</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Hyd. Breather (2992447)..... <b>P7336 KIT</b>	130 w/CP3, CP3.42 Engs. Air..... <b>PA1646-FN</b>
EuroCargo ML120E23S w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... <b>BD325</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel..... <b>BF7663</b> Air..... <b>PA3760</b> Steering..... <b>P106-HD</b>	EuroCargo II 120E28 w/Cummins Tector 6 Eng. (06/03-on) Lube..... <b>BT7237</b> Fuel..... <b>BF7813</b> Radial Seal Air..... <b>RS4969</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Hyd. Breather (2992447)..... <b>P7336 KIT</b>	130.13 Lube (1160025)..... <b>B236 +</b> Fuel Spin-on (1174423)..... <b>BF7931</b> 295.3 mm Air (2168629)..... <b>PA2891</b> 349.3 mm Air (2165044)..... <b>PA2845</b>
EuroCargo ML120EL23S w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... <b>BD325</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel..... <b>BF7663</b> Air..... <b>PA3760</b> Steering..... <b>P106-HD</b>	EuroCargo III ML120 E 28 w/Cummins Tector 6 F4A Eng. (06/08-on) Lube (504033399)..... <b>BT7237</b> Fuel/Water Separator (2992662). <b>BF1365</b> Fuel (2992241)..... <b>BF7813</b> Air Dryer (1907612)..... <b>BA5374 +</b> Urea (denoxtronic 1) (42562233).. <b>PE5270</b> Urea (denoxtronic 2) (42555073).. <b>PE5271</b>	EuroCargo 130E15 w/8060.25R.4280 Eng. (02/92-04/01) Dual-Flow Lube (1907582)..... <b>BD232</b> Fuel (1902138)..... <b>BF5587-D</b> Fuel/Water Separator (1908547). <b>BF1217</b> Air (1905983)..... <b>PA3597</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Steering (1902137)..... <b>P106-HD</b>
EuroCargo 120E24 w/Cummins Tector Eng. (09/00-09/03) Lube..... <b>BT7237</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel..... <b>BF7813</b> 330.2 mm Radial Seal Air..... <b>RS4968</b> 414.3 mm Radial Seal Air..... <b>RS4969</b> Air (2992388)..... <b>RS5535</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Hyd. Breather (2992447)..... <b>P7336 KIT</b>	EuroCargo II 120E30 w/Cummins Tector 6 Eng. (Euro 4/5) (05/06-on) Lube (2992242)..... <b>BT7237</b> Fuel..... <b>BF7813</b> Fuel/Water Separator (2992662). <b>BF1365</b> Radial Seal Air..... <b>RS4968</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Hyd. Breather (2992447)..... <b>P7336 KIT</b>	EuroCargo ML130E15K w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... <b>BD325</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel..... <b>BF7663</b> Air..... <b>PA3760</b> Steering..... <b>P106-HD</b>
EuroCargo II 120E24 w/Cummins Tector 6 Eng. (06/03-on) Lube..... <b>BT7237</b> Fuel..... <b>BF7813</b> Radial Seal Air..... <b>RS4969</b>		EuroCargo ML130E15/P w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... <b>BD325</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel..... <b>BF7663</b> Air..... <b>PA3760</b> Steering..... <b>P106-HD</b>
		EuroCargo ML130E15S w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... <b>BD325</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel..... <b>BF7663</b> Air..... <b>PA3760</b> Steering..... <b>P106-HD</b>
		EuroCargo 130E18 w/8060.25V.4080TC Eng. (11/91-04/01) Dual-Flow Lube (1907582)..... <b>BD232</b> Fuel (1902138)..... <b>BF5587-D</b> Fuel/Water Separator (1908547). <b>BF1217</b> Air (1905983)..... <b>PA3597</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



IVECO Trucks (cont'd)	IVECO Trucks (cont'd)	IVECO Trucks (cont'd)
EuroCargo 130E18 w/8060.25V.4080TC Eng. (11/91-04/01) (Cont'd) Air Dryer (Mann TB1374X)..... BA5374 + Steering (1902137)..... P106-HD	EuroCargo II 130E21 w/Cummins Tector 6 Eng. (06/03-on) Lube..... BT7237 Fuel..... BF7813 Radial Seal Air..... RS4968 Air Dryer (Mann TB1374X)..... BA5374 + Hyd. Breather (2992447)..... P7336 KIT	EuroCargo II 130E24 w/Cummins Tector 6 Eng. (06/03-on) (Cont'd) Air Dryer (Mann TB1374X)..... BA5374 + Hyd. Breather (2992447)..... P7336 KIT
EuroCargo 130E18 w/Cummins Tector Eng. (09/00-09/03) Lube..... BT7237 Fuel/Water Separator (1907539). BF1217 Fuel..... BF7813 Radial Seal Air..... RS4968 Air (2992388)..... RS5535 Air Dryer (Mann TB1374X)..... BA5374 + Hyd. Breather (2992447)..... P7336 KIT	EuroCargo II 130E22 w/Cummins Tector 6 Eng. (Euro 4/5) (05/06-on) Lube (2992242)..... BT7237 Fuel..... BF7813 Fuel/Water Separator (2992662). BF1365 Radial Seal Air..... RS4968 Air Dryer (Mann TB1374X)..... BA5374 + Hyd. Breather (2992447)..... P7336 KIT	EuroCargo II 130E25 w/Cummins Tector 6 Eng. (Euro 4/5) (05/06-on) Lube (2992242)..... BT7237 Fuel..... BF7813 Fuel/Water Separator (2992662). BF1365 Radial Seal Air..... RS4968 Air Dryer (Mann TB1374X)..... BA5374 + Hyd. Breather (2992447)..... P7336 KIT
EuroCargo II 130E18 w/Cummins Tector 6 Eng. (06/03-on) Lube..... BT7237 Fuel..... BF7813 Radial Seal Air..... RS4968 Air Dryer (Mann TB1374X)..... BA5374 + Hyd. Breather (2992447)..... P7336 KIT	EuroCargo 130E23 w/8060.45.6090 Eng. (04/92-04/01) Dual-Flow Lube..... BD325 Fuel/Water Separator (1907539). BF1217 Fuel..... BF7663 Air..... PA3760 Air Dryer (Mann TB1374X)..... BA5374 + Steering..... P106-HD	EuroCargo 130E28 w/Cummins Tector 6 Eng. (Euro 4/5) (05/06-on) Lube (2992242)..... BT7237 Fuel..... BF7813 Fuel/Water Separator (2992662). BF1365 Radial Seal Air..... RS4968 Air Dryer (Mann TB1374X)..... BA5374 + Hyd. Breather (2992447)..... P7336 KIT
EuroCargo ML130E18D w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... BD325 Fuel/Water Separator (1907539). BF1217 Fuel..... BF7663 Air..... PA3760 Steering..... P106-HD	EuroCargo ML130E23K w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... BD325 Fuel/Water Separator (1907539). BF1217 Fuel..... BF7663 Air..... PA3760 Steering..... P106-HD	EuroCargo 130E28 w/Cummins Tector 6 Eng. (Euro 4/5) (05/06-on) Lube (2992242)..... BT7237 Fuel..... BF7813 Fuel/Water Separator (2992662). BF1365 Radial Seal Air..... RS4968 Air Dryer (Mann TB1374X)..... BA5374 + Hyd. Breather (2992447)..... P7336 KIT
EuroCargo ML130E18K w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... BD325 Fuel/Water Separator (1907539). BF1217 Fuel..... BF7663 Air..... PA3760 Steering..... P106-HD	EuroCargo ML130E23/P w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... BD325 Fuel/Water Separator (1907539). BF1217 Fuel..... BF7663 Air..... PA3760 Steering..... P106-HD	EuroCargo II 130E28 w/Cummins Tector 6 Eng. (06/03-on) Lube..... BT7237 Fuel..... BF7813 Radial Seal Air..... RS4968 Air Dryer (Mann TB1374X)..... BA5374 + Hyd. Breather (2992447)..... P7336 KIT
EuroCargo ML130E18/P w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... BD325 Fuel/Water Separator (1907539). BF1217 Fuel..... BF7663 Air..... PA3760 Steering..... P106-HD	EuroCargo ML130E23S w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... BD325 Fuel/Water Separator (1907539). BF1217 Fuel..... BF7663 Air..... PA3760 Steering..... P106-HD	EuroCargo 130E30 w/Cummins Tector 6 Eng. (Euro 4/5) (05/06-on) Lube (2992242)..... BT7237 Fuel..... BF7813 Fuel/Water Separator (2992662). BF1365 Radial Seal Air..... RS4968 Air Dryer (Mann TB1374X)..... BA5374 + Hyd. Breather (2992447)..... P7336 KIT
EuroCargo ML130E18S w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... BD325 Fuel/Water Separator (1907539). BF1217 Fuel..... BF7663 Air..... PA3760 Steering..... P106-HD	EuroCargo 130E24 w/Cummins Tector Eng. (09/00-09/03) Lube..... BT7237 Fuel/Water Separator (1907539). BF1217 Fuel..... BF7813 Radial Seal Air..... RS4968 Air Dryer (Mann TB1374X)..... BA5374 + Hyd. Breather (2992447)..... P7336 KIT	EuroCargo 130A1, 130A1R, 130A1T, 130A1T, 130A1TH Lube (1973-on) (4951092)..... BT347
130.20, 130U20 Lube (1174421)..... B236 + Fuel (61142392)..... BF988 + Opt. Fuel/Water Separator..... BF1221 + Coolant (1901776)..... BW5143	EuroCargo II 130E24 w/Cummins Tector 6 Eng. (06/03-on) Lube..... BT7237 Fuel..... BF7813 Radial Seal Air..... RS4968	130D9, 130D11, 130D12, 130D14, 130D15, 130D16 w/Deutz F6L613, F6L614, F6L913 Engs. Lube (1160025)..... B236 + Fuel Ele. (1168398)..... PF950 Fuel/Water Separator..... BF1221 + Fuel Spin-on (1160243)..... BF988 + Air (2168629)..... PA2891

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IVECO Trucks (cont'd)	IVECO Trucks (cont'd)	IVECO Trucks (cont'd)
130M7, 130M8, 130M9, 130M11, 130M13, 130M14 w/Deutz F6L913 Eng. Lube (1160025)..... B236 + Fuel Spin-on (1160243)..... BF988 + Fuel/Water Separator..... BF1221 + O. Air (2165044)..... PA2845 I. Air..... PA2837	135.17 Series 2 Dual-Flow Lube (1907582)..... BD232 Fuel (4764693)..... BF988 + Air (1902077)..... PA2405	140.14, 140.17 w/8360.04 Eng. Lube (1901604)..... BT349 Fuel Spin-on (8821823)..... BF783
130NC, 130NR, 130NT, 130PC w/OM CP3 Eng. Lube (1901603)..... BT347 Can-Type Fuel (74651986)..... BF825 + Fuel Ele. (8825228)..... PF828 Air (9917419)..... PA1646-FN Coolant (4734562)..... BW5137	EuroCargo 135E18 w/8060.25VTC Eng. (01/94-04/01) Dual-Flow Lube..... BD232 Fuel/Water Separator (1907539)..... BF1217 Fuel (Mann WK842/2)..... BF5587-D Air..... PA3597 Air Dryer (Mann TB1374X)..... BA5374 + Trans..... P106-HD	EuroCargo ML140E15K w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... BD325 Fuel/Water Separator (1907539)..... BF1217 Fuel..... BF7663 Air..... PA3760 Steering..... P106-HD
130NC20, 130NR20, 130NT20 w/8220.02 Eng. Fuel (1909103)..... BF783 Air (9917419)..... PA1646-FN Coolant (4734562)..... BW5137	EuroCargo ML135E18WS w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... BD325 Fuel/Water Separator (1907539)..... BF1217 Fuel..... BF7663 Air..... PA3760 Steering..... P106-HD	EuroCargo ML140E15/P w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... BD325 Fuel/Water Separator (1907539)..... BF1217 Fuel..... BF7663 Air..... PA3760 Steering..... P106-HD
135D10, 135D11, 135D12, 135D14, 135D15 w/Deutz F6L312 Eng. Lube (1160025)..... B236 + P. Fuel Ele. (1168407)..... F950-F S. Fuel Ele. (1168398)..... PF950	EuroCargo ML135E18WT w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... BD325 Fuel/Water Separator (1907539)..... BF1217 Fuel..... BF7663 Air..... PA3760 Steering..... P106-HD	EuroCargo ML140E15S w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... BD325 Fuel/Water Separator (1907539)..... BF1217 Fuel..... BF7663 Air..... PA3760 Steering..... P106-HD
135D11, 135D12, 135D13, 135D14 w/Deutz F6L912 Eng. Lube (1160025)..... B236 + Fuel (1160243)..... BF988 + Fuel/Water Separator..... BF1221 + O. Air (2165044)..... PA2845 I. Air..... PA2837	EuroCargo 135E23 w/8060.45STCA Eng. (01/94-04/01) Dual-Flow Lube..... BD325 Fuel/Water Separator (1907539)..... BF1217 Fuel..... BF7663 377.0 mm Air..... PA3760 381.0 mm Air..... PA2474 Air Dryer (Mann TB1374X)..... BA5374 + Trans..... P106-HD	EuroCargo 140E18 w/Cummins Tector Eng. (09/00-09/03) Lube..... BT7237 Fuel/Water Separator (1907539)..... BF1217 Fuel..... BF7813 Radial Seal Air..... RS4968 Air (2992388)..... RS5535 Air Dryer (Mann TB1374X)..... BA5374 + Hyd. Breather (2992447)..... P7336 KIT
135D14 w/Deutz F6L413 Eng. Lube (1160025)..... B236 + Fuel (1160243)..... BF988 + Fuel/Water Separator..... BF1221 + Air (2168629)..... PA2891	EuroCargo ML135E23WS w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... BD325 Fuel/Water Separator (1907539)..... BF1217 Fuel..... BF7663 Air..... PA3760 Steering..... P106-HD	Eurocargo II 140 E 18 w/Cummins Tector 6 Eng. (05/05-08/08) Lube (504033399)..... BT7237 Fuel/Water Separator (1907539)..... BF1217 Fuel (2992241)..... BF7813 Radial Seal Air (42471161)..... RS4968 Air Dryer (1907612)..... BA5374 + Breather (2992447)..... P7336 KIT
135.14 Lube (1901602)..... BT348 Fuel (1902138)..... BF5587-D Air (1902040)..... PA1940	EuroCargo ML135E23WT w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... BD325 Fuel/Water Separator (1907539)..... BF1217 Fuel..... BF7663 Air..... PA3760 Steering..... P106-HD	Eurocargo II 140 E 18 w/Cummins Tector 4 Euro 4/5 Eng. (05/06-08/08) Lube (504033399)..... BT7237 Fuel/Water Separator (2992662)..... BF1365 Fuel (2992241)..... BF7813 Air Dryer (1907612)..... BA5374 + Breather (2992447)..... P7336 KIT Urea (denoxtronic 1) (42562233).. PE5270 Urea (denoxtronic 2) (42555073).. PE5271
135.14 w/8060.02 Eng. Lube (1901602)..... BT348 Can-Type Fuel (1901687)..... BF825 +	140.13 Lube (1174421)..... B236 + Fuel Spin-on (1174423)..... BF7931 Air (2168629)..... PA2891	Eurocargo III ML 140 E 18 w/Cummins Tector 4 F4A Eng. (06/08-on) Lube (504033399)..... BT7237 Fuel/Water Separator (2992662)..... BF1365 Fuel (2992241)..... BF7813 Air Dryer (1907612)..... BA5374 + Urea (denoxtronic 1) (42562233).. PE5270
135.17 w/8060.24 Eng. Lube..... BT349 Fuel Spin-on (1901605)..... BF783 I. Air (42480759)..... PA2836 Coolant (1901776)..... BW5143		
135.17 w/8360.03 Eng. Lube (1901604)..... BT349 Fuel (1901605)..... BF783 Some Air (9917419)..... PA1646-FN		
135.17 Series 1 F-F Lube (1907567)..... BT348 Dual-Flow Lube (1907582)..... BD232 Can-Type Fuel (1901929)..... BF825 + Air (1902077)..... PA2405		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IVECO Trucks (cont'd)	IVECO Trucks (cont'd)	IVECO Trucks (cont'd)
Eurocargo III ML 140 E 18 w/Cummins Tector 4 F4A Eng. (06/08-on) (Cont'd) Urea (denoxtronic 2) (42555073).. PE5271	EuroCargo ML140E23/P w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... BD325 Fuel/Water Separator (1907539). BF1217 Fuel..... BF7663 Air..... PA3760 Steering..... P106-HD	Eurocargo II 140 E 28 w/Cummins Tector 6 Euro 4/5 Eng. (05/06-08/08) Lube (504033399)..... BT7237 Fuel/Water Separator (2992662). BF1365 Fuel (2992241)..... BF7813 Air Dryer (1907612)..... BA5374 + Breather (2992447)..... P7336 KIT Urea (denoxtronic 1) (42562233).. PE5270 Urea (denoxtronic 2) (42555073).. PE5271
EuroCargo ML140E18K w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... BD325 Fuel/Water Separator (1907539). BF1217 Fuel..... BF7663 Air..... PA3760 Steering..... P106-HD	EuroCargo ML140E23K w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... BD325 Fuel/Water Separator (1907539). BF1217 Fuel..... BF7663 Air..... PA3760 Steering..... P106-HD	Eurocargo III ML 140 E 28 w/Cummins Tector 6 F4A Eng. (06/08-on) Lube (504033399)..... BT7237 Fuel/Water Separator (2992662). BF1365 Fuel (2992241)..... BF7813 Air Dryer (1907612)..... BA5374 + Urea (denoxtronic 1) (42562233).. PE5270 Urea (denoxtronic 2) (42555073).. PE5271
EuroCargo ML140E18S w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... BD325 Fuel/Water Separator (1907539). BF1217 Fuel..... BF7663 Air..... PA3760 Steering..... P106-HD	EuroCargo ML140E23S w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... BD325 Fuel/Water Separator (1907539). BF1217 Fuel..... BF7663 Air..... PA3760 Steering..... P106-HD	Eurocargo III ML 140 E 28 w/Cummins Tector 6 F4A Eng. (06/08-on) Lube (504033399)..... BT7237 Fuel/Water Separator (2992662). BF1365 Fuel (2992241)..... BF7813 Air Dryer (1907612)..... BA5374 + Urea (denoxtronic 1) (42562233).. PE5270 Urea (denoxtronic 2) (42555073).. PE5271
140.19 w/Deutz BF6L913 Eng. Lube (1174420)..... B218 Fuel (1174423)..... BF7931 381.0 mm O. Air (2165074)..... PA2474 379.4 mm I. Air (2243946)..... PA2836 349.3 mm Air (2165044)..... PA2845	Eurocargo II 140 E 24 w/Cummins Tector 6 Eng. (06/03-08/08) Lube (504033399)..... BT7237 Fuel/Water Separator (1907539). BF1217 Fuel (2992241)..... BF7813 Radial Seal Air (42471161)..... RS4968 Air Dryer (1907612)..... BA5374 + Breather (2992447)..... P7336 KIT	145.17 Dual-Flow Lube (1907582)..... BD232 Fuel (4764693)..... BF988 + Air (1902077)..... PA2405
140.20, 140U20 Lube (1174421)..... B236 + Fuel (61142392)..... BF988 + Opt. Fuel/Water Separator..... BF1221 + Coolant (1901776)..... BW5143	Eurocargo II 140 E 21 w/Cummins Tector 6 Eng. (05/05-08/08) Lube (504033399)..... BT7237 Fuel/Water Separator (1907539). BF1217 Fuel (2992241)..... BF7813 Radial Seal Air (42471161)..... RS4968 Air Dryer (1907612)..... BA5374 + Breather (2992447)..... P7336 KIT	D145 w/Deutz F6L613, F6L714 Engs. Fuel Ele..... PF950
Eurocargo II 140 E 22 w/Cummins Tector 6 Euro 4/5 Eng. (05/06-08/08) Lube (504033399)..... BT7237 Fuel/Water Separator (2992662). BF1365 Fuel (2992241)..... BF7813 Air Dryer (1907612)..... BA5374 + Breather (2992447)..... P7336 KIT	EuroCargo 140E24 w/Cummins Tector Eng. (09/00-09/03) Lube..... BT7237 Fuel/Water Separator (1907539). BF1217 Fuel..... BF7813 Radial Seal Air..... RS4968 Air (2992388)..... RS5535 Air Dryer (Mann TB1374X)..... BA5374 + Hyd. Breather (2992447)..... P7336 KIT	150 Lube Ele..... P235 Fuel (1A Series)..... BF719 Fuel (2A Series)..... BF797 Steering..... P106-HD
Eurocargo II 140 E 22 w/Cummins Tector 6 Euro 4/5 Eng. (05/06-08/08) Lube (504033399)..... BT7237 Fuel/Water Separator (2992662). BF1365 Fuel (2992241)..... BF7813 Air Dryer (1907612)..... BA5374 + Breather (2992447)..... P7336 KIT Urea (denoxtronic 1) (42562233).. PE5270 Urea (denoxtronic 2) (42555073).. PE5271	Eurocargo II 140 E 25 w/Cummins Tector 6 Euro 4/5 Eng. (05/06-08/08) Lube (504033399)..... BT7237 Fuel/Water Separator (2992662). BF1365 Fuel (2992241)..... BF7813 Air Dryer (1907612)..... BA5374 + Breather (2992447)..... P7336 KIT Urea (denoxtronic 1) (42562233).. PE5270 Urea (denoxtronic 2) (42555073).. PE5271	150.14 w/8360.04 Eng. Lube (1901604)..... BT349 Fuel (8821823)..... BF783
Eurocargo III ML 140 E 22 w/Cummins Tector 6 F4A Eng. (06/08-on) Lube (504033399)..... BT7237 Fuel/Water Separator (2992662). BF1365 Fuel (2992241)..... BF7813 Air Dryer (1907612)..... BA5374 + Urea (denoxtronic 1) (42562233).. PE5270 Urea (denoxtronic 2) (42555073).. PE5271	Eurocargo III ML 140 E 25 w/Cummins Tector 6 F4A Eng. (06/08-on) Lube (504033399)..... BT7237 Fuel/Water Separator (2992662). BF1365 Fuel (2992241)..... BF7813 Air Dryer (1907612)..... BA5374 + Urea (denoxtronic 1) (42562233).. PE5270 Urea (denoxtronic 2) (42555073).. PE5271	EuroCargo 150E15 w/8060.25R.4280 Eng. (12/91-04/01) Dual-Flow Lube (1907582)..... BD232 Fuel (1902138)..... BF5587-D Fuel/Water Separator (1908547). BF1217 Air (1905983)..... PA3597 Air Dryer (Mann TB1374X)..... BA5374 + Steering (1902137)..... P106-HD
		EuroCargo ML150E15K w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... BD325 Fuel/Water Separator (1907539). BF1217 Fuel..... BF7663 Air..... PA3760 Steering..... P106-HD
		EuroCargo ML150E15/P w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... BD325 Fuel/Water Separator (1907539). BF1217 Fuel..... BF7663 Air..... PA3760 Steering..... P106-HD

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IVECO Trucks (cont'd)	IVECO Trucks (cont'd)	IVECO Trucks (cont'd)
EuroCargo ML150E15S w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... BD325 Fuel/Water Separator (1907539). BF1217 Fuel..... BF7663 Air..... PA3760 Steering..... P106-HD	EuroCargo ML150E18K w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... BD325 Fuel/Water Separator (1907539). BF1217 Fuel..... BF7663 Air..... PA3760 Steering..... P106-HD	EuroCargo 150E23 w/8060.45.6090 Eng. (02/92-04/01) Dual-Flow Lube..... BD325 Fuel..... BF7663 Fuel/Water Separator (1908547). BF1217 Air..... PA3760 Air Dryer (Mann TB1374X)..... BA5374 + Steering (1902137)..... P106-HD
150.16 w/Deutz BF6L913 Eng. Lube (1173765)..... B218 123.0 mm Fuel Spin-on (1161582)..... BF988 + 136.5 mm Some Fuel Spin-on (1164620)..... BF900 O. Air (2165054)..... PA2474 I. Air (2243946)..... PA2836	EuroCargo ML150E18S w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... BD325 Fuel/Water Separator (1907539). BF1217 Fuel..... BF7663 Air..... PA3760 Steering..... P106-HD	EuroCargo ML150E23K w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... BD325 Fuel/Water Separator (1907539). BF1217 Fuel..... BF7663 Air..... PA3760 Steering..... P106-HD
150.17 w/8360.05 Eng. Lube (1901604)..... BT349 Fuel (1901605)..... BF783 O. Air (2165054)..... PA2474 I. Air (2243946)..... PA2836 Coolant (1901776)..... BW5143	150.20 Fuel (1174423)..... BF7931 Fuel/Water Separator..... BF1221 + Coolant (1901776)..... BW5143	EuroCargo ML150E23/P w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... BD325 Fuel/Water Separator (1907539). BF1217 Fuel..... BF7663 Air..... PA3760 Steering..... P106-HD
150.18 w/Deutz F6L413 Eng. Lube (1174421)..... B236 + 108.7 mm Fuel Ele. (1160217).... PF834 Fuel/Water Separator..... BF1221 + 115.1 mm Fuel Ele. (1168403).... F953-F Fuel Spin-on (1174423)..... BF7931 374.7 mm O. Air (2165049)..... PA2405 371.5 mm I. Air (2241329)..... PA2835 341.3 mm I. Air (2414950)..... PA2837 Single Air (2168629)..... PA2891	150.20 w/8220.02 Eng. 206.4 mm Lube (1174421)..... B236 + 231.8 mm Lube (1901604)..... BT349 Fuel (1901605)..... BF783 O. Air..... PA2474 I. Air..... PA2836	EuroCargo ML150E23S w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... BD325 Fuel/Water Separator (1907539). BF1217 Fuel..... BF7663 Air..... PA3760 Steering..... P106-HD
EuroCargo 150E18 w/8060.25V.4080TC Eng. (09/91-04/01) Dual-Flow Lube (1907582)..... BD232 Fuel (1902138)..... BF5587-D Fuel/Water Separator (1908547). BF1217 Air (1905983)..... PA3597 Air Dryer (Mann TB1374X)..... BA5374 + Steering (1902137)..... P106-HD	150.20, 150.20N w/Unic Eng. 206.4 mm Lube (1174421)..... B236 + 231.8 mm Lube (4667755)..... BT349 Fuel..... BF988 + Fuel/Water Separator..... BF1221 +	EuroCargo 150E24 w/Cummins Tector Eng. (09/00-09/03) Lube..... BT7237 Fuel/Water Separator (1907539). BF1217 Fuel..... BF7813 Radial Seal Air..... RS4969 Air Dryer (Mann TB1374X)..... BA5374 + Hyd. Breather (2992447)..... P7336 KIT
EuroCargo 150E18 w/Cummins Tector Eng. (09/01-09/03) Lube..... BT7237 Fuel/Water Separator (1907539). BF1217 Fuel..... BF7813 Radial Seal Air..... RS4968 Air (2992388)..... RS5535 Air Dryer (Mann TB1374X)..... BA5374 + Hyd. Breather (2992447)..... P7336 KIT	150U20 Lube (1174421)..... B236 + Fuel (61142392)..... BF988 + Fuel/Water Separator..... BF1221 + Coolant (1901776)..... BW5143	EuroCargo II 150E24 w/Cummins Tector 6 Eng. (06/03-on) Lube..... BT7237 Fuel..... BF7813 Radial Seal Air..... RS4968 Air Dryer (Mann TB1374X)..... BA5374 + Hyd. Breather (2992447)..... P7336 KIT
Eurocargo II 150 E 18 w/Cummins Tector 4 Euro 4/5 Eng. (05/06-08/08) Lube (504033399)..... BT7237 Fuel/Water Separator (2992662). BF1365 Fuel (2992241)..... BF7813 Air Dryer (1907612)..... BA5374 + Breather (2992447)..... P7336 KIT Urea (denoxtronic 1) (42562233).. PE5270 Urea (denoxtronic 2) (42555073).. PE5271	EuroCargo II 150E22 w/Cummins Tector 6 Eng. (Euro 4/5) (05/06-on) Lube (2992242)..... BT7237 Fuel..... BF7813 Fuel/Water Separator (2992662). BF1365 Radial Seal Air..... RS4968 Air Dryer (Mann TB1374X)..... BA5374 + Hyd. Breather (2992447)..... P7336 KIT	EuroCargo II 150E24 w/Cummins Tector 6 Eng. (06/03-on) Lube..... BT7237 Fuel..... BF7813 Radial Seal Air..... RS4969 Air Dryer (Mann TB1374X)..... BA5374 + Hyd. Breather (2992447)..... P7336 KIT
	150.23 w/Deutz F8L413 Eng. Lube (1174421)..... B236 + Fuel (1174423)..... BF7931 Fuel/Water Separator..... BF1221 + O. Air (9983764)..... PA2475 I. Air..... PA2814 Trans..... PT691	EuroCargo II 150E25 w/Cummins Tector 6 Eng. (Euro 4/5) (05/06-on) Lube (2992242)..... BT7237 Fuel..... BF7813 Fuel/Water Separator (2992662). BF1365 Radial Seal Air..... RS4968 Air Dryer (Mann TB1374X)..... BA5374 + Hyd. Breather (2992447)..... P7336 KIT
		EuroCargo 150E27 w/8360.46.417TCA Eng. (09/91-04/01) Dual-Flow Lube..... BD325 Fuel..... BF7663 Fuel/Water Separator (1908547). BF1217

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IVECO Trucks (cont'd)	IVECO Trucks (cont'd)	IVECO Trucks (cont'd)
EuroCargo 150E27 w/8360.46.417TCA Eng. (09/91-04/01) (Cont'd)	159F w/Unic X200 Eng. (Cont'd)	160
Air..... PA3760	496.9 mm O. Air..... PA2475	Lube..... BT349
Air Dryer (Mann TB1374X)..... BA5374 +	473.1 mm I. Air..... PA2814	Fuel..... BF783
Steering (1902137)..... P106-HD	159.17 w/8360.05 Eng.	160D11, 160D12, 160D14, 160D15, 160D16 w/Deutz BF6L913 Eng.
EuroCargo 150E28 w/Cummins Tector Eng. (09/00-09/03)	Lube (1901604)..... BT349	Lube (1164406)..... B218
Lube..... BT7237	Fuel (1901605)..... BF783	Fuel (1160243)..... BF988 +
Fuel/Water Separator (1907539)..... BF1217	O. Air..... PA2474	Fuel/Water Separator..... BF1221 +
Fuel..... BF7813	I. Air..... PA2836	O. Air (2165049)..... PA2405
Radial Seal Air..... RS4969	Coolant (1901776)..... BW5143	I. Air..... PA2835
Air Dryer (Mann TB1374X)..... BA5374 +	159.20 w/8220.02 Eng.	160D15 w/Deutz BF6L913 Eng.
Hyd. Breather (2992447)..... P7336 KIT	Lube (1901604)..... BT349	Lube..... B218
EuroCargo II 150E28 w/Cummins Tector 6 Eng. (06/03-on)	Fuel (1901605)..... BF783	Fuel..... BF988 +
Lube..... BT7237	381.0 mm O. Air (1902465)..... PA2474	O. Air (2165054)..... PA2474
Fuel..... BF7813	379.4 mm I. Air (34000191)..... PA2836	I. Air..... PA2836
Radial Seal Air..... RS4969	496.9 mm O. Air..... PA2475	160M11, 160M12, 160M14, 160M15, 160M16 w/Deutz BF6L913 Eng.
Air Dryer (Mann TB1374X)..... BA5374 +	473.1 mm I. Air..... PA2814	Lube..... B218
Hyd. Breather (2992447)..... P7336 KIT	Coolant (1901776)..... BW5143	Fuel..... BF988 +
EuroCargo II 150E30 w/Cummins Tector 6 Eng. (Euro 4/5) (05/06-on)	Steering..... P106-HD	Fuel/Water Separator..... BF1221 +
Lube (2992242)..... BT7237	159.20 w/Unic Eng.	371.5 mm Air..... PA2835
Fuel..... BF7813	206.4 mm Lube (1174421)..... B236 +	374.7 mm Air..... PA2405
Fuel/Water Separator (2992662)..... BF1365	231.8 mm Lube (4667755)..... BT349	160M16 w/Deutz BF6L913 Eng.
Radial Seal Air..... RS4968	Fuel (61142392)..... BF988 +	Lube..... B218
Air Dryer (Mann TB1374X)..... BA5374 +	Fuel/Water Separator..... BF1221 +	Fuel..... BF988 +
Hyd. Breather (2992447)..... P7336 KIT	Coolant (1901776)..... BW5143	Opt. Fuel/Water Separator..... BF1221 +
150D13 w/Deutz F6L312 Eng.	159F20T w/8220.02 Turbo Eng.	O. Air (1902465)..... PA2474
Lube (1174421)..... B236 +	Fuel (1909103)..... BF783	I. Air (Mann CF1200)..... PA2836
P. Fuel Ele. (1168407)..... F950-F	O. Air..... PA2475	Single Air (2168629)..... PA2891
S. Fuel Ele. (1168398)..... PF950	I. Air..... PA2836	160MB w/Deutz BF6L913 Eng.
150D13, 150D14, 150D21 w/Deutz F6L613, F6L714 Eng.	159N w/8220.02 Eng.	Lube..... B218
Fuel Ele. (1168398)..... PF950	Lube (4667339)..... BT349	123.0 mm Fuel (1160243)..... BF988 +
159NC17 w/8360.03 Turbo Eng.	Fuel (1909103)..... BF783	136.5 mm Fuel (1164620)..... BF900
Lube (1901604)..... BT349	381.0 mm O. Air (2165054)..... PA2474	Fuel/Water Separator..... BF1221 +
123.0 mm Fuel..... BF988 +	379.4 mm I. Air (34000191)..... PA2836	O. Air (2165054)..... PA2474
186.5 mm Fuel..... BF783	496.9 mm O. Air..... PA2475	I. Air (2243946)..... PA2836
Coolant (1901776)..... BW5143	473.1 mm I. Air..... PA2814	160NC, 160NC/U, 160NT
150NC17, 150NC20, 150NR20, 150NT20 w/8220.02 Eng.	Coolant (1901776)..... BW5143	Lube..... B236 +
Fuel (1909103)..... BF783	159NC20 w/8220.02 Eng.	Fuel (1909103)..... BF783
Air (9917419)..... PA1646-FN	Lube (4667339)..... BT349	381.0 mm O. Air (1186389)..... PA2474
Coolant (4734562)..... BW5137	Fuel (1909103)..... BF783	379.4 mm I. Air (42480759)..... PA2836
156D15, 156D16, 156D22 w/Deutz F6L814, F8L714, F8L914, F10L714, F10L914 Eng.	381.0 mm O. Air (2165054)..... PA2474	496.9 mm O. Air..... PA2475
P. Fuel Ele. (1168407)..... F950-F	379.4 mm I. Air (34000191)..... PA2836	473.1 mm I. Air..... PA2814
S. Fuel Ele. (1168398)..... PF950	496.9 mm O. Air..... PA2475	160T, 160U
Hyd. (1267900)..... PT691	473.1 mm I. Air..... PA2814	Lube..... BT349
159F w/Unic X200 Eng.	Coolant (1901776)..... BW5143	Fuel..... BF783
Lube (1901604)..... BT349	159NC20, 159NR20 w/Unic X200 Eng.	P160A2 Series 130
Fuel (61674455)..... BF988 +	Lube (1901604)..... BT349	Lube (78826586)..... BT349
Opt. Fuel/Water Separator..... BF1221 +	Fuel (61674455)..... BF988 +	Fuel (78809472)..... PF906
381.0 mm O. Air (2165054)..... PA2474	Opt. Fuel/Water Separator..... BF1221 +	160A
379.4 mm I. Air (34000191)..... PA2836	381.0 mm O. Air (2165054)..... PA2474	Lube (1901602)..... BT348
496.9 mm O. Air..... PA2475	379.4 mm I. Air (34000191)..... PA2836	Fuel (4733112)..... BF876
473.1 mm I. Air..... PA2814	496.9 mm O. Air..... PA2475	160A11FL w/8360 Eng.
159U20	473.1 mm I. Air..... PA2814	Lube..... BT349
Lube (1174421)..... B236 +	Coolant (1901776)..... BW5143	Fuel (4733112)..... BF876
Fuel (61142392)..... BF988 +	159U20	Air (998-5779)..... PA1882
Fuel/Water Separator..... BF1221 +	Lube (1174421)..... B236 +	
Coolant (1901776)..... BW5143	Fuel (61142392)..... BF988 +	
	Fuel/Water Separator..... BF1221 +	
	Coolant (1901776)..... BW5143	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IVECO Trucks (cont'd)	IVECO Trucks (cont'd)	IVECO Trucks (cont'd)
160A13FL w/8360 Eng. Lube (4667755)..... <b>BT349</b> Fuel (4733112)..... <b>BF876</b> Air (Don. P181034)..... <b>PA1884 +</b>	160.23 w/Deutz F8L413 Eng. (Cont'd) Trans..... <b>PT691</b>	Eurocargo II 160 E 30 w/Cummins Tector 6 Euro 4/5 Eng. (05/06-08/08) (Cont'd) Urea (denoxtronic 2) (42555073).. <b>PE5271</b>
160.16 w/Deutz BF6L913 Eng. Lube..... <b>B218</b> 123.0 mm Fuel (1160243)..... <b>BF988 +</b> 136.5 mm Fuel (1164620)..... <b>BF900</b> Fuel/Water Separator..... <b>BF1221 +</b> O. Air (2165054)..... <b>PA2474</b> I. Air (2243946)..... <b>PA2836</b>	Eurocargo II 160 E 24 w/Cummins Tector 6 Eng. (06/03-08/08) Lube (504033399)..... <b>BT7237</b> Fuel/Water Separator (1907539)..... <b>BF1217</b> Fuel (2992241)..... <b>BF7813</b> Radial Seal Air (504000160)..... <b>RS4969</b> Air Dryer (1907612)..... <b>BA5374 +</b> Breather (2992447)..... <b>P7336 KIT</b>	Eurocargo III ML 160 E 30 w/Cummins Tector 6 F4A Eng. (06/08-on) Lube (504033399)..... <b>BT7237</b> Fuel/Water Separator (2992662)..... <b>BF1365</b> Fuel (2992241)..... <b>BF7813</b> Air Dryer (1907612)..... <b>BA5374 +</b> Urea (denoxtronic 1) (42562233).. <b>PE5270</b> Urea (denoxtronic 2) (42555073).. <b>PE5271</b>
Eurocargo II 160 E 18 w/Cummins Tector 4 Euro 4/5 Eng. (05/06-08/08) Lube (504033399)..... <b>BT7237</b> Fuel/Water Separator (2992662)..... <b>BF1365</b> Fuel (2992241)..... <b>BF7813</b> Air Dryer (1907612)..... <b>BA5374 +</b> Breather (2992447)..... <b>P7336 KIT</b> Urea (denoxtronic 1) (42562233).. <b>PE5270</b> Urea (denoxtronic 2) (42555073).. <b>PE5271</b>	Eurocargo II 160 E 25 w/Cummins Tector 6 Euro 4/5 Eng. (05/06-08/08) Lube (504033399)..... <b>BT7237</b> Fuel/Water Separator (2992662)..... <b>BF1365</b> Fuel (2992241)..... <b>BF7813</b> Air Dryer (1907612)..... <b>BA5374 +</b> Breather (2992447)..... <b>P7336 KIT</b> Urea (denoxtronic 1) (42562233).. <b>PE5270</b> Urea (denoxtronic 2) (42555073).. <b>PE5271</b>	UA160 w/CP3, CP3-42 Engs. Air..... <b>PA1646-FN</b>
160.19 w/Deutz F6L413, F6L913 Engs. Lube (1174421)..... <b>B236 +</b> Fuel (1174423)..... <b>BF7931</b> Fuel/Water Separator..... <b>BF1221 +</b> O. Air (2165049)..... <b>PA2405</b> I. Air (2241329)..... <b>PA2835</b>	Eurocargo III ML 160 E 25 w/Cummins Tector 6 F4A Eng. (06/08-on) Lube (504033399)..... <b>BT7237</b> Fuel/Water Separator (2992662)..... <b>BF1365</b> Fuel (2992241)..... <b>BF7813</b> Air Dryer (1907612)..... <b>BA5374 +</b> Urea (denoxtronic 1) (42562233).. <b>PE5270</b> Urea (denoxtronic 2) (42555073).. <b>PE5271</b>	165.24 (1984) Lube (1901919)..... <b>B236 +</b> Fuel (1901605)..... <b>BF783</b> Air (1902048)..... <b>PA2474</b> Coolant (1901776)..... <b>BW5143</b>
Eurocargo II 160 E 21 w/Cummins Tector 6 Eng. (06/03-08/08) Lube (504033399)..... <b>BT7237</b> Fuel/Water Separator (1907539)..... <b>BF1217</b> Fuel (2992241)..... <b>BF7813</b> Radial Seal Air (42471161)..... <b>RS4968</b> Air Dryer (1907612)..... <b>BA5374 +</b> Breather (2992447)..... <b>P7336 KIT</b>	160.26 Lube..... <b>B236 +</b> Fuel (1909103)..... <b>BF783</b> O. Air (1186389)..... <b>PA2474</b> I. Air (42480759)..... <b>PA2836</b>	165.24 w/8220.22 Eng. Lube (4667339)..... <b>BT349</b> Fuel (1901605)..... <b>BF783</b>
Eurocargo II 160 E 22 w/Cummins Tector 6 Euro 4/5 Eng. (05/06-08/08) Lube (504033399)..... <b>BT7237</b> Fuel/Water Separator (2992662)..... <b>BF1365</b> Fuel (2992241)..... <b>BF7813</b> Air Dryer (1907612)..... <b>BA5374 +</b> Breather (2992447)..... <b>P7336 KIT</b> Urea (denoxtronic 1) (42562233).. <b>PE5270</b> Urea (denoxtronic 2) (42555073).. <b>PE5271</b>	Eurocargo II 160 E 28 w/Cummins Tector 6 Euro 4/5 Eng. (05/06-08/08) Lube (504033399)..... <b>BT7237</b> Fuel/Water Separator (2992662)..... <b>BF1365</b> Fuel (2992241)..... <b>BF7813</b> Air Dryer (1907612)..... <b>BA5374 +</b> Breather (2992447)..... <b>P7336 KIT</b> Urea (denoxtronic 1) (42562233).. <b>PE5270</b> Urea (denoxtronic 2) (42555073).. <b>PE5271</b>	168M14, 168M16 w/Deutz BF6L913 Eng. Lube (1164406)..... <b>B218</b> 123.0 mm Fuel (1160243)..... <b>BF988 +</b> 136.5 mm Fuel (1164620)..... <b>BF900</b> Fuel/Water Separator..... <b>BF1221 +</b> O. Air (2165054)..... <b>PA2474</b> I. Air..... <b>PA2836</b>
Eurocargo III ML 160 E 22 w/Cummins Tector 6 F4A Eng. (06/08-on) Lube (504033399)..... <b>BT7237</b> Fuel/Water Separator (2992662)..... <b>BF1365</b> Fuel (2992241)..... <b>BF7813</b> Air Dryer (1907612)..... <b>BA5374 +</b> Urea (denoxtronic 1) (42562233).. <b>PE5270</b> Urea (denoxtronic 2) (42555073).. <b>PE5271</b>	Eurocargo III ML 160 E 28 w/Cummins Tector 6 F4A Eng. (06/08-on) Lube (504033399)..... <b>BT7237</b> Fuel/Water Separator (2992662)..... <b>BF1365</b> Fuel (2992241)..... <b>BF7813</b> Air Dryer (1907612)..... <b>BA5374 +</b> Urea (denoxtronic 1) (42562233).. <b>PE5270</b> Urea (denoxtronic 2) (42555073).. <b>PE5271</b>	170.18 w/Deutz F6L413 Eng. Lube (1174421)..... <b>B236 +</b> 108.7 mm Fuel Ele. (1160217)..... <b>PF834</b> 115.1 mm Fuel Ele. (1168403)..... <b>F953-F</b> Fuel/Water Separator..... <b>BF1221 +</b> Fuel Spin-on (1174423)..... <b>BF7931</b> 349.3 mm O. Air (2165044)..... <b>PA2845</b> 341.3 mm I. Air (2414950)..... <b>PA2837</b> 374.7 mm O. Air (2165049)..... <b>PA2405</b> 371.5 mm I. Air (2241329)..... <b>PA2835</b> Single Air (2168629)..... <b>PA2891</b>
160.23 w/Deutz F8L413 Eng. Lube (1174421)..... <b>B236 +</b> Fuel (1174423)..... <b>BF7931</b> Fuel/Water Separator..... <b>BF1221 +</b> O. Air (9983764)..... <b>PA2475</b> I. Air..... <b>PA2814</b>	Eurocargo II 160 E 30 w/Cummins Tector 6 Euro 4/5 Eng. (05/06-08/08) Lube (504033399)..... <b>BT7237</b> Fuel/Water Separator (2992662)..... <b>BF1365</b> Fuel (2992241)..... <b>BF7813</b> Air Dryer (1907612)..... <b>BA5374 +</b> Breather (2992447)..... <b>P7336 KIT</b> Urea (denoxtronic 1) (42562233).. <b>PE5270</b>	EuroCargo 170E18 w/8060.25VTC Eng. (01/94-04/01) Dual-Flow Lube (1907582)..... <b>BD232</b> Fuel (1902138)..... <b>BF5587-D</b> Fuel/Water Separator (1908547)..... <b>BF1217</b> Air (1905983)..... <b>PA3597</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Steering (1902137)..... <b>P106-HD</b>
		170.20 Lube (1174421)..... <b>B236 +</b> Fuel (61142392)..... <b>BF988 +</b> Fuel/Water Separator..... <b>BF1221 +</b> Coolant (1901776)..... <b>BW5143</b>
		170.20 w/8210.02, 8220.02 Engs. 206.4 mm Lube (1174421)..... <b>B236 +</b> 231.8 mm Lube (1901604)..... <b>BT349</b> Fuel (1901605)..... <b>BF783</b> O. Air (1186389)..... <b>PA2474</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IVECO Trucks (cont'd)	IVECO Trucks (cont'd)	IVECO Trucks (cont'd)
170.20 w/8210.02, 8220.02 Engs. (Cont'd) I. Air (42480759)..... PA2836	170.35 w/8280 Eng. Lube (4667755)..... BT349	170N w/8200.03 Eng. Lube..... B236 +
170U20 Lube (1174421)..... B236 +	Fuel..... BF988 +	Fuel (1909103)..... BF783
Fuel (61142392)..... BF988 +	Fuel/Water Separator..... BF1221 +	381.0 mm O. Air (1186389)..... PA2474
Fuel/Water Separator..... BF1221 +	O. Air..... PA2475	379.4 mm I. Air (42480759)..... PA2836
Coolant (1901776)..... BW5143	I. Air..... PA2814	496.9 mm O. Air..... PA2475
Eurocargo III ML 160 E 18 w/Cummins Tector 4 F4A Eng. (06/08-on)	170.35 w/8280.02 Eng. Lube (1901604)..... BT349	473.1 mm I. Air..... PA2814
Lube (504033399)..... BT7237	Fuel (1901605)..... BF783	170NC w/8210.02 Eng. Lube..... B236 +
Fuel/Water Separator (2992662)..... BF1365	O. Air..... PA2475	Fuel (1909103)..... BF783
Fuel (2992241)..... BF7813	I. Air (42481020)..... PA2814	O. Air (1186389)..... PA2474
Air Dryer (1907612)..... BA5374 +	Air (Standard Media) (1902129)..... PA2776	I. Air..... PA2836
Urea (denoxtronic 1) (42562233)..... PE5270	Air (Flame Retardant Media) (299-6154)..... PA30235	170NC26, 170NT26 w/8200.03 Eng. Lube..... B236 +
Urea (denoxtronic 2) (42555073)..... PE5271	Coolant (1901776)..... BW5143	Fuel (1909103)..... BF783
EuroCargo 170E23 w/8060.45STCA Eng. (01/94-04/01)	170T35 w/8280 Eng. Lube (4667755)..... BT349	381.0 mm O. Air (1186389)..... PA2474
Dual-Flow Lube..... BD325	Fuel..... BF988 +	379.4 mm I. Air (42480759)..... PA2836
Fuel/Water Separator (1907539)..... BF1217	Fuel/Water Separator..... BF1221 +	496.9 mm O. Air..... PA2475
Fuel..... BF7663	O. Air..... PA2475	473.1 mm I. Air..... PA2814
Air..... PA3760	I. Air..... PA2814	170NC33, 170NC35, 170NT33, 170NT33-E w/8220.02, 8280.02 Engs. 206.4 mm Lube (61671160)..... B236 +
Air Dryer (Mann TB1374X)..... BA5374 +	170D11, 170D12, 170D13, 170D14, 170D15, 170D15.5, 170D16 w/Deutz F6L413, F8L312 Engs. Lube (1160025)..... B236 +	231.8 mm Lube (1901604)..... BT349
Steering (1902137)..... P106-HD	115.1 mm P. Fuel Ele. (1168403)..... F953-F	Fuel (1901605)..... BF783
170.26 w/8210.02 Eng. Lube (1901604)..... BT349	Fuel/Water Separator..... BF1221 +	473.9 mm O. Air..... PA2776
Fuel (1909103)..... BF783	142.9 mm P. Fuel Ele. (1168407)..... F950-F	471.5 mm I. Air (1905620)..... PA3494
O. Air (2165059)..... PA2475	108.7 mm S. Fuel (1160217)..... PF834	496.9 mm O. Air..... PA2475
I. Air..... PA2814	141.3 mm S. Fuel Ele. (1168398)..... PF950	473.1 mm I. Air..... PA2814
Coolant (1901776)..... BW5143	Fuel Spin-on (1160243)..... BF988 +	170T26 Lube (4667755)..... BT349
170.30 w/8210.22 Eng. Dual-Flow Lube (1902102)..... BD325	O. Air (2165044)..... PA2845	Fuel..... BF988 +
Fuel (1901605)..... BF783	I. Air..... PA2837	O. Air..... PA2474
374.7 mm O. Air..... PA2405	Single Air (2168629)..... PA2891	I. Air..... PA2836
371.5 mm I. Air..... PA2835	Hyd. (1267900)..... PT691	170T33, 170T33E Lube..... BT349
496.9 mm O. Air..... PA2475	170F26 w/8210 Eng. Lube (4667339)..... BT349	Fuel..... BF783
473.1 mm I. Air..... PA2814	Fuel (1909103)..... BF783	Air (1902048)..... PA2474
Coolant (1901776)..... BW5143	381.0 mm O. Air..... PA2474	175.17 Dual-Flow Lube (1907582)..... BD232
170.33 Lube (1901604)..... BT349	379.4 mm I. Air..... PA2836	Fuel (4764693)..... BF988 +
Dual-Flow Lube (1902102)..... BD325	496.9 mm O. Air..... PA2475	Air (1902048)..... PA2474
Fuel (1901605)..... BF783	473.1 mm I. Air..... PA2814	175.24 w/8460.21 Eng. Dual-Flow Lube (1903715)..... BD325
Fuel (1901605)..... BF783	170F35T w/8220.02, 8280.02 Engs. 206.4 mm Lube (61671160)..... B236 +	Fuel Ele. (1902096)..... PF312
O. Air (9983764)..... PA2475	231.8 mm Lube (1901604)..... BT349	Fuel Spin-on..... BF783
I. Air..... PA2836	Fuel (1901605)..... BF783	Air..... PA2474
Coolant (1901776)..... BW5143	473.9 mm O. Air..... PA2776	Coolant (1901776)..... BW5143
170.35 w/8220 Eng. 231.8 mm Lube (1901604)..... BT349	471.5 mm I. Air..... PA3494	175E27 w/8360.46 Eng. Dual-Flow Lube (1907584)..... BD325
206.4 mm Lube (61671160)..... B236 +	496.9 mm O. Air..... PA2475	Fuel (1902134)..... BF988 +
Fuel (1901605)..... BF783	473.1 mm I. Air..... PA2814	Fuel/Water Separator (1908547)..... BF1217
473.9 mm O. Air..... PA2776	170F38T, 170F38TP Turbo w/8280.22 Eng. Fuel (1909103)..... BF783	374.7 mm Air (1902077)..... PA2405
471.5 mm I. Air..... PA3494	Std. Air (1901780)..... PA1886 +	381.0 mm Air (1902048)..... PA2474
496.9 mm O. Air..... PA2475	XP Air (1901780)..... PA1886XP	Steering (1902137)..... P106-HD
473.1 mm I. Air..... PA2814	Coolant (1901776)..... BW5143	
Coolant (1901776)..... BW5143		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IVECO Trucks (cont'd)	IVECO Trucks (cont'd)	IVECO Trucks (cont'd)
Eurotech 175 E 27 w/8360.46.417 TCA Eng. (04/92-02/02) Dual-Flow Lube (1902102)..... <b>BD325</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel (1908312)..... <b>BF988 +</b> O. Air (1904550)..... <b>PA2776</b> I. Air (1905620)..... <b>PA3494</b> Air Dryer (1907612)..... <b>BA5374 +</b> Coolant (1901776)..... <b>BW5143</b> Steering (1902137)..... <b>P106-HD</b>	EuroCargo 180E21 w/Cummins Tector Eng. (08/01-09/03) Lube..... <b>BT7237</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel..... <b>BF7813</b> Radial Seal Air..... <b>RS4968</b> Air (2992388)..... <b>RS5535</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Hyd. Breather (2992447)..... <b>P7336 KIT</b>	180.24 w/8220.22 Eng. Lube (4667339)..... <b>BT349</b> Fuel (1901605)..... <b>BF783</b>
179E27 w/8360.46 Eng. Dual-Flow Lube (1907584)..... <b>BD325</b> Fuel (1902134)..... <b>BF988 +</b> Fuel/Water Separator (1908547). <b>BF1217</b> Air (1902048)..... <b>PA2474</b> Coolant (1901776)..... <b>BW5143</b> Steering (1902137)..... <b>P106-HD</b>	EuroCargo II 180E21 w/Cummins Tector 6 Eng. (06/03-on) Lube..... <b>BT7237</b> Fuel..... <b>BF7813</b> Radial Seal Air..... <b>RS4968</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Hyd. Breather (2992447)..... <b>P7336 KIT</b>	EuroCargo 180E24 w/Cummins Tector Eng. (09/00-09/03) Lube..... <b>BT7237</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel..... <b>BF7813</b> Radial Seal Air..... <b>RS4969</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Hyd. Breather (2992447)..... <b>P7336 KIT</b>
Eurotech 179 E 27 w/8360.46.417 TCA Eng. (04/92-02/02) Dual-Flow Lube (1902102)..... <b>BD325</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel (1908312)..... <b>BF988 +</b> O. Air (1904550)..... <b>PA2776</b> I. Air (1905620)..... <b>PA3494</b> Air Dryer (1907612)..... <b>BA5374 +</b> Coolant (1901776)..... <b>BW5143</b> Steering (1902137)..... <b>P106-HD</b>	EuroCargo ML180E21T/P w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... <b>BD325</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel..... <b>BF7663</b> Air..... <b>PA3760</b> Steering..... <b>P106-HD</b>	EuroCargo II 180E24 w/8210.42, 8360.46, 8460.41 Engs. Dual-Flow Lube (1907584)..... <b>BD325</b> Fuel (1902134)..... <b>BF988 +</b> Fuel/Water Separator (1908547). <b>BF1217</b> Air (1904550)..... <b>PA2776</b> Coolant (1901776)..... <b>BW5143</b> Steering (1902137)..... <b>P106-HD</b>
EuroCargo 180E18 w/8060.25 Eng. (01/98-05/01) Dual-Flow Lube..... <b>BD232</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel (Mann WK842/2)..... <b>BF5587-D</b> Air..... <b>PA3597</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Steering..... <b>P106-HD</b>	Eurocargo II 180 E/EL 22 w/Cummins Tector 6 Euro 4/5 Eng. (05/06-08/08) Lube (504033399)..... <b>BT7237</b> Fuel/Water Separator (2992662). <b>BF1365</b> Fuel (2992241)..... <b>BF7813</b> Air Dryer (1907612)..... <b>BA5374 +</b> Breather (2992447)..... <b>P7336 KIT</b> Urea (denoxtronic 1) (42562233).. <b>PE5270</b> Urea (denoxtronic 2) (42555073).. <b>PE5271</b>	EuroTech 180E24 w/Cursor E0618D Eng. (10/98-on) Lube..... <b>B7174-MPG</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel..... <b>BF7696</b> Air..... <b>PA2776</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Trans..... <b>PT8385</b> Steering..... <b>P106-HD</b>
EuroCargo 180E18D w/8060TCA Eng. (01/94-04/01) Dual-Flow Lube..... <b>BD325</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel..... <b>BF7663</b> Air..... <b>PA3760</b> Steering..... <b>P106-HD</b>	EuroCargo 180E23 w/8060.45S Eng. (01/98-05/01) Dual-Flow Lube..... <b>BD325</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel..... <b>BF7663</b> Air..... <b>PA3760</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Steering (1902137)..... <b>P106-HD</b>	Eurotech 180 E 24 w/8360.46R.416TCA Eng. (07/92-06/02) Dual-Flow Lube (1902102)..... <b>BD325</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel (1908312)..... <b>BF988 +</b> O. Air (1904550)..... <b>PA2776</b> I. Air (1905620)..... <b>PA3494</b> Air Dryer (1907612)..... <b>BA5374 +</b> Coolant (1901776)..... <b>BW5143</b> Steering (1902137)..... <b>P106-HD</b>
180T8, 180TS Lube..... <b>BT349</b> Fuel..... <b>BF783</b>	EuroCargo II 180E23 w/8060.45S, 8360.45 Engs. (01/98-05/01) Dual-Flow Lube..... <b>BD325</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel..... <b>BF7663</b> Air..... <b>PA3760</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Steering (1902137)..... <b>P106-HD</b>	EuroTrakker 180 E 24 w/Cursor F2BE0681D Eng. (09/99-11/04) Lube (99445200)..... <b>B7174-MPG</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel (1907460)..... <b>BF7696</b> O. Air (1904550)..... <b>PA2776</b> I. Air (1905620)..... <b>PA3494</b> Air Dryer (1907612)..... <b>BA5374 +</b> Breather (500339085)..... <b>BT9408</b> Trans. (42491185)..... <b>PT8385</b> Steering (1902137)..... <b>P106-HD</b>
EuroCargo 180E21 w/8060.45.4100TCA Eng. (04/92-04/01) Dual-Flow Lube (1907582)..... <b>BD232</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel (1902138)..... <b>BF5587-D</b> Air (1905983)..... <b>PA3597</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Steering (1902137)..... <b>P106-HD</b>	180.24 Lube..... <b>B236 +</b> Fuel (1901605)..... <b>BF783</b> Air (1901902)..... <b>PA1885 +</b> Coolant (1901776)..... <b>BW5143</b>	EuroCargo II 180E25 w/Cummins Tector 6 (Euro 4/5) Eng. (05/06-on) Lube (2992242)..... <b>BT7237</b> Fuel..... <b>BF7813</b> Fuel/Water Separator (2992662). <b>BF1365</b> Radial Seal Air..... <b>RS4968</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Hyd. Breather (2992447)..... <b>P7336 KIT</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



IVECO Trucks (cont'd)	IVECO Trucks (cont'd)	IVECO Trucks (cont'd)
<b>EuroTrakker 180 E 25 w/8460.41 Eng.</b> (01/98-11/04) <b>Dual-Flow Lube</b> (1903715)..... <b>BD325</b> <b>Fuel/Water Separator</b> (1907539). <b>BF1217</b> <b>Fuel</b> (1904640)..... <b>BF7663</b> <b>O. Air</b> (1904550)..... <b>PA2776</b> <b>I. Air</b> (1905620)..... <b>PA3494</b> <b>Air Dryer</b> (1907612)..... <b>BA5374 +</b> <b>Coolant</b> (1901776)..... <b>BW5143</b> <b>Steering</b> (1902137)..... <b>P106-HD</b>	<b>EuroTech 180E27 w/Cursor E0618C/F Eng.</b> (10/98-on) <b>Lube</b> ..... <b>B7174-MPG</b> <b>Fuel/Water Separator</b> (1907539). <b>BF1217</b> <b>Fuel</b> ..... <b>BF7696</b> <b>Air</b> ..... <b>PA2776</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Trans.</b> ..... <b>PT8385</b> <b>Steering</b> ..... <b>P106-HD</b>	<b>EuroCargo II 180E30 w/8210.42, 8360.46, 8460.41 Engs. (Cont'd)</b> <b>Coolant</b> (1901776)..... <b>BW5143</b> <b>Steering</b> (1902137)..... <b>P106-HD</b>
<b>Eurocargo III ML 180 E 25 w/Cummins Tector 6 F4A Eng. (06/08-on)</b> <b>Lube</b> (504033399)..... <b>BT7237</b> <b>Fuel/Water Separator</b> (2992662). <b>BF1365</b> <b>Fuel</b> (2992241)..... <b>BF7813</b> <b>Air Dryer</b> (1907612)..... <b>BA5374 +</b> <b>Urea</b> (denoxtronic 1) (42562233).. <b>PE5270</b> <b>Urea</b> (denoxtronic 2) (42555073).. <b>PE5271</b>	<b>Eurotech 180 E 27 w/8360.46.417 TCA Eng.</b> (07/92-06/02) <b>Dual-Flow Lube</b> (1902102)..... <b>BD325</b> <b>Fuel/Water Separator</b> (1907539). <b>BF1217</b> <b>Fuel</b> (1908312)..... <b>BF988 +</b> <b>O. Air</b> (1904550)..... <b>PA2776</b> <b>I. Air</b> (1905620)..... <b>PA3494</b> <b>Air Dryer</b> (1907612)..... <b>BA5374 +</b> <b>Coolant</b> (1901776)..... <b>BW5143</b> <b>Steering</b> (1902137)..... <b>P106-HD</b>	<b>Eurotech 180 E 30 w/8460.41C.320 Eng.</b> (07/92-06/02) <b>Dual-Flow Lube</b> (1902102)..... <b>BD325</b> <b>Fuel/Water Separator</b> (1907539). <b>BF1217</b> <b>Fuel</b> (1904640)..... <b>BF7663</b> <b>O. Air</b> (1904550)..... <b>PA2776</b> <b>I. Air</b> (1905620)..... <b>PA3494</b> <b>Air Dryer</b> (1907612)..... <b>BA5374 +</b> <b>Coolant</b> (1901776)..... <b>BW5143</b> <b>Steering</b> (1902137)..... <b>P106-HD</b>
<b>180.26</b> <b>Lube</b> (1907570)..... <b>BT349</b> <b>Fuel</b> (1901605)..... <b>BF783</b> <b>Air</b> (1901902)..... <b>PA1885 +</b>	<b>EuroCargo 180E28 w/Cummins Tector Eng.</b> (09/00-09/03) <b>Lube</b> ..... <b>BT7237</b> <b>Fuel/Water Separator</b> (1907539). <b>BF1217</b> <b>Fuel</b> ..... <b>BF7813</b> <b>Radial Seal Air</b> ..... <b>RS4969</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Hyd. Breather</b> (2992447)..... <b>P7336 KIT</b>	<b>Eurocargo III ML 180 E 30 w/Cummins Tector 6 F4A Eng. (06/08-on)</b> <b>Lube</b> (504033399)..... <b>BT7237</b> <b>Fuel/Water Separator</b> (2992662). <b>BF1365</b> <b>Fuel</b> (2992241)..... <b>BF7813</b> <b>Air Dryer</b> (1907612)..... <b>BA5374 +</b> <b>Urea</b> (denoxtronic 1) (42562233).. <b>PE5270</b> <b>Urea</b> (denoxtronic 2) (42555073).. <b>PE5271</b>
<b>180.26 w/8210.02 Eng.</b> <b>Lube</b> (1901604)..... <b>BT349</b> <b>Fuel</b> (1909103)..... <b>BF783</b> <b>O. Air</b> (2165059)..... <b>PA2475</b> <b>I. Air</b> ..... <b>PA2814</b> <b>Single Air</b> (1901902)..... <b>PA1885 +</b> <b>Coolant</b> (1901776)..... <b>BW5143</b>	<b>EuroCargo II 180E28 w/Cummins Tector 6 (Euro 4/5) Eng. (05/06-on)</b> <b>Lube</b> (2992242)..... <b>BT7237</b> <b>Fuel</b> ..... <b>BF7813</b> <b>Fuel/Water Separator</b> (2992662). <b>BF1365</b> <b>Radial Seal Air</b> ..... <b>RS4968</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Hyd. Breather</b> (2992447)..... <b>P7336 KIT</b>	<b>EuroTech 180E31 w/Cursor E0681B Eng.</b> (10/98-on) <b>Lube</b> ..... <b>B7174-MPG</b> <b>Fuel/Water Separator</b> (1907539). <b>BF1217</b> <b>Fuel</b> ..... <b>BF7696</b> <b>Air</b> ..... <b>PA2776</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Trans.</b> ..... <b>PT8385</b> <b>Steering</b> ..... <b>P106-HD</b>
<b>180.27 EuroTech</b> <b>Dual-Flow Lube</b> (1907584)..... <b>BD325</b> <b>Fuel</b> (1907640)..... <b>BF7663</b>	<b>EuroCargo II 180E28 w/Cummins Tector 6 (Euro 4/5) Eng. (05/06-on)</b> <b>Lube</b> (2992242)..... <b>BT7237</b> <b>Fuel</b> ..... <b>BF7813</b> <b>Fuel/Water Separator</b> (2992662). <b>BF1365</b> <b>Radial Seal Air</b> ..... <b>RS4968</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Hyd. Breather</b> (2992447)..... <b>P7336 KIT</b>	<b>EuroCargo II 180E34 w/8210.42, 8360.46, 8460.41 Engs.</b> <b>Dual-Flow Lube</b> (1907584)..... <b>BD325</b> <b>Fuel</b> (1902134)..... <b>BF988 +</b> <b>Fuel/Water Separator</b> (1908547). <b>BF1217</b> <b>Air</b> (1904550)..... <b>PA2776</b> <b>Coolant</b> (1901776)..... <b>BW5143</b> <b>Steering</b> (1902137)..... <b>P106-HD</b>
<b>EuroCargo 180E27 w/8360.45 Eng.</b> (01/98-05/01) <b>Dual-Flow Lube</b> ..... <b>BD325</b> <b>Fuel/Water Separator</b> (1907539). <b>BF1217</b> <b>Fuel</b> ..... <b>BF7663</b> <b>Air</b> ..... <b>PA3760</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Steering</b> (1902137)..... <b>P106-HD</b>	<b>EuroCargo III ML 180 E 28 w/Cummins Tector 6 F4A Eng. (06/08-on)</b> <b>Lube</b> (504033399)..... <b>BT7237</b> <b>Fuel/Water Separator</b> (2992662). <b>BF1365</b> <b>Fuel</b> (2992241)..... <b>BF7813</b> <b>Air Dryer</b> (1907612)..... <b>BA5374 +</b> <b>Urea</b> (denoxtronic 1) (42562233).. <b>PE5270</b> <b>Urea</b> (denoxtronic 2) (42555073).. <b>PE5271</b>	<b>EuroCargo II 180E34 w/8210.42, 8360.46, 8460.41 Engs.</b> <b>Dual-Flow Lube</b> (1907584)..... <b>BD325</b> <b>Fuel</b> (1907640)..... <b>BF7663</b> <b>Air</b> (1904550)..... <b>PA2776</b> <b>Coolant</b> (1901776)..... <b>BW5143</b> <b>Steering</b> (1902137)..... <b>P106-HD</b>
<b>EuroCargo II 180E27 w/8060.45S, 8360.45 Engs. (01/98-05/01)</b> <b>Dual-Flow Lube</b> ..... <b>BD325</b> <b>Fuel/Water Separator</b> (1907539). <b>BF1217</b> <b>Fuel</b> ..... <b>BF7663</b> <b>Air</b> ..... <b>PA3760</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Steering</b> (1902137)..... <b>P106-HD</b>	<b>EuroCargo II 180E30 w/Cummins Tector 6 (Euro 4/5) Eng. (05/06-on)</b> <b>Lube</b> (2992242)..... <b>BT7237</b> <b>Fuel</b> ..... <b>BF7813</b> <b>Fuel/Water Separator</b> (2992662). <b>BF1365</b> <b>Radial Seal Air</b> ..... <b>RS4968</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Hyd. Breather</b> (2992447)..... <b>P7336 KIT</b>	<b>EuroTech 180E34 w/8460TCA Eng.</b> <b>Dual-Flow Lube</b> (1907584)..... <b>BD325</b> <b>Fuel/Water Separator</b> (1907539). <b>BF1217</b> <b>Fuel</b> (1907640)..... <b>BF7663</b> <b>Air</b> (1904550)..... <b>PA2776</b> <b>Coolant</b> (1901776)..... <b>BW5143</b> <b>Steering</b> (1902137)..... <b>P106-HD</b>
<b>EuroCargo II 180E27 w/8210.42, 8360.46, 8460.41 Engs.</b> <b>Dual-Flow Lube</b> (1907584)..... <b>BD325</b> <b>Fuel</b> (1902134)..... <b>BF988 +</b> <b>Fuel/Water Separator</b> (1908547). <b>BF1217</b> <b>Air</b> (1904550)..... <b>PA2776</b> <b>Coolant</b> (1901776)..... <b>BW5143</b> <b>Steering</b> (1902137)..... <b>P106-HD</b>	<b>EuroCargo II 180E30 w/Cummins Tector 6 (Euro 4/5) Eng. (05/06-on)</b> <b>Lube</b> (2992242)..... <b>BT7237</b> <b>Fuel</b> ..... <b>BF7813</b> <b>Fuel/Water Separator</b> (2992662). <b>BF1365</b> <b>Radial Seal Air</b> ..... <b>RS4968</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Hyd. Breather</b> (2992447)..... <b>P7336 KIT</b>	<b>Eurotech 180 E 34 w/8460.41K.406 Eng.</b> (04/92-06/02) <b>Dual-Flow Lube</b> (1902102)..... <b>BD325</b> <b>Fuel/Water Separator</b> (1907539). <b>BF1217</b> <b>Fuel</b> (1904640)..... <b>BF7663</b> <b>O. Air</b> (1904550)..... <b>PA2776</b> <b>I. Air</b> (1905620)..... <b>PA3494</b> <b>Air Dryer</b> (1907612)..... <b>BA5374 +</b> <b>Coolant</b> (1901776)..... <b>BW5143</b> <b>Steering</b> (1902137)..... <b>P106-HD</b>
<b>EuroCargo II 180E27 w/8210.42, 8360.46, 8460.41 Engs.</b> <b>Dual-Flow Lube</b> (1907584)..... <b>BD325</b> <b>Fuel</b> (1902134)..... <b>BF988 +</b> <b>Fuel/Water Separator</b> (1908547). <b>BF1217</b> <b>Air</b> (1904550)..... <b>PA2776</b> <b>Coolant</b> (1901776)..... <b>BW5143</b> <b>Steering</b> (1902137)..... <b>P106-HD</b>	<b>EuroCargo II 180E30 w/8210.42, 8360.46, 8460.41 Engs.</b> <b>Dual-Flow Lube</b> (1907584)..... <b>BD325</b> <b>Fuel</b> (1902134)..... <b>BF988 +</b> <b>Fuel/Water Separator</b> (1908547). <b>BF1217</b> <b>Air</b> (1904550)..... <b>PA2776</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IVECO Trucks (cont'd)	IVECO Trucks (cont'd)	IVECO Trucks (cont'd)
EuroTech 180E38 w/8210TCA Eng.	EuroTech 180E43 w/8210TCA Eng. (04/92-on)	180NC, 180NT, 180NT/S
Dual-Flow Lube (1907584)..... BD325	Dual-Flow Lube (1907584)..... BD325	Lube (1901604)..... BT349
Fuel/Water Separator (1907539) BF1217	Fuel/Water Separator (1907539) BF1217	Fuel (1909103)..... BF783
Fuel (1907640)..... BF7663	Fuel (1907640)..... BF7663	O. Air..... PA2475
Air (1904550)..... PA2776	Air (1904550)..... PA2776	I. Air..... PA2814
Coolant..... BW5137	Coolant..... BW5137	
Steering..... P106-HD	Steering..... P106-HD	186D13, 186D15 w/Deutz F6L413, F8L312 Eng.
Eurotech 180 E 38 w/8460.41L.5020 Eng. (09/92-06/02)	EuroTech 180E43 w/Cursor E0681D Eng. (10/99-on)	Lube (1160025)..... B236 +
Dual-Flow Lube (1902102)..... BD325	Lube (99445200)..... B7174-MPG	115.1 mm P. Fuel Ele. (1168403)..... F953-F
Fuel/Water Separator (1907539) BF1217	Fuel/Water Separator (1907539) BF1217	142.9 mm P. Fuel Ele. (1168407)..... F950-F
Fuel (1908312)..... BF988 +	473.9 mm Air..... PA2776	Fuel/Water Separator..... BF1221 +
O. Air (1904550)..... PA2776	Air Dryer (Mann TB1374X)..... BA5374 +	108.7 mm S. Fuel Ele. (1160217)..... PF834
I. Air (1905620)..... PA3494	Trans. (5000807213)..... PT8385	141.3 mm S. Fuel Ele. (1168398)..... PF950
Air Dryer (1907612)..... BA5374 +	Steering..... P106-HD	Fuel Spin-on (1160243)..... BF988 +
Coolant (1901776)..... BW5143	EuroTech 180E52 w/8280.42 Eng. (04/92-06/02)	O. Air (2165044)..... PA2845
Steering (1902137)..... P106-HD	Dual-Flow Lube (1907571)..... BD7168	I. Air (A6212)..... PA2837
EuroTech 180E39 w/Cursor E0681E Eng. (10/99-on)	Fuel (1907640)..... BF7663	Single Air (2168629)..... PA2891
Lube..... B7174-MPG	Fuel/Water Separator (1908547) BF1217	Hyd. (1267900)..... PT691
Fuel/Water Separator (1907539) BF1217	Coolant (1901776)..... BW5143	190 w/Unic X200 Eng.
Air..... PA2776	Steering..... P106-HD	206.4 mm Lube (61671160)..... B236 +
Air Dryer (Mann TB1374X)..... BA5374 +	EuroTech 180 E 52 w/8280.42S.350 Eng. (04/92-06/02)	231.8 mm Lube (4667339)..... BT349
Trans..... PT8385	Dual-Flow Lube (1905704)..... BD7168	Fuel (61142392)..... BF988 +
Steering..... P106-HD	Fuel/Water Separator (1907539) BF1217	Fuel/Water Separator..... BF1221 +
EuroTech 180E42 w/8210TCA Eng.	Fuel (1904640)..... BF7663	O. Air..... PA2474
Dual-Flow Lube (1907584)..... BD325	I. Air (1905620)..... PA3494	I. Air..... PA2836
Fuel/Water Separator (1907539) BF1217	Air Dryer (1907612)..... BA5374 +	
Fuel (1907640)..... BF7663	Steering (1902137)..... P106-HD	190 w/V85S Eng.
Air (1904550)..... PA2776	180D12 w/Deutz F6L413, F8L312 Eng.	Can-Type Fuel (74651986)..... BF825 +
Coolant..... BW5137	Lube (1160025)..... B236 +	Fuel/Water Separator..... BF1221 +
Steering..... P106-HD	115.1 mm P. Fuel Ele. (1168403)..... F953-F	Fuel Spin-on..... BF988 +
Eurotech 180 E 42 w/8210.42L.400 Eng. (04/92-06/02)	142.9 mm P. Fuel Ele. (1168407)..... F950-F	190.17H, 190.17HW
Dual-Flow Lube (1902102)..... BD325	Fuel/Water Separator..... BF1221 +	Lube (1907570)..... BT349
Fuel/Water Separator (1907539) BF1217	108.7 mm S. Fuel Ele. (1160217)..... PF834	Fuel (1901605)..... BF783
Fuel (1902138)..... BF5587-D	141.3 mm S. Fuel Ele. (1168398)..... PF950	Air (1902465)..... PA2474
O. Air (1904550)..... PA2776	Fuel Spin-on (1160243)..... BF988 +	Coolant (1901776)..... BW5143
I. Air (1905620)..... PA3494	O. Air (2165044)..... PA2845	
Air Dryer (1907612)..... BA5374 +	I. Air..... PA2837	190.18 w/Deutz F6L413 Eng.
Steering (1902137)..... P106-HD	Single Air (2168629)..... PA2891	Lube (1174421)..... B236 +
LD180E42/P w/8210TCA Eng. (04/92-on)	Hyd. (1267900)..... PT691	Fuel/Water Separator..... BF1221 +
Dual-Flow Lube..... BD325	180N	108.7 mm Fuel Ele. (1160217)..... PF834
Fuel/Water Separator (1907539) BF1217	Lube (1901604)..... BT349	115.1 mm Fuel Ele. (1168403)..... F953-F
Fuel..... BF7663	Fuel (1909103)..... BF783	Fuel Spin-on (1174423)..... BF7931
Air..... PA2776	O. Air..... PA2475	349.3 mm O. Air (2165044)..... PA2845
Steering..... P106-HD	I. Air..... PA2814	341.3 mm I. Air (2414950)..... PA2837
EuroStar 180E43 w/Cursor E0681D (Cursor 10) Eng. (10/99-on)	180NC w/8210.02 Eng.	374.7 mm O. Air (2165049)..... PA2405
Lube (99445200)..... B7174-MPG	Lube..... B236 +	371.5 mm I. Air (2241329)..... PA2835
Fuel/Water Separator (1907539) BF1217	Fuel (1909103)..... BF783	Single Air (2168629)..... PA2891
473.9 mm Air..... PA2776	O. Air (1186389)..... PA2474	190.20
Air Dryer (Mann TB1374X)..... BA5374 +	I. Air (42480759)..... PA2836	Lube (1174421)..... B236 +
Trans. (5000807213)..... PT8385		Fuel (61142392)..... BF988 +
Steering..... P106-HD		Fuel/Water Separator..... BF1221 +
		Coolant (1901776)..... BW5143

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IVECO Trucks (cont'd)	IVECO Trucks (cont'd)	IVECO Trucks (cont'd)
190.20 w/8220.02 Eng. 206.4 mm Lube (1174421)..... <b>B236 +</b> 231.8 mm Lube (1901604)..... <b>BT349</b> Fuel (1901605)..... <b>BF783</b> O. Air (1902465)..... <b>PA2474</b> I. Air (42480759)..... <b>PA2836</b>	190.25 w/Deutz F8L413F Eng. Lube (1174421)..... <b>B236 +</b> Fuel/Water Separator..... <b>BF1221 +</b> 123.0 mm Fuel (1174423)..... <b>BF7931</b> 186.5 mm Fuel (1909103)..... <b>BF783</b> O. Air..... <b>PA2475</b> I. Air..... <b>PA2814</b>	190PAC26 w/8210 Eng. Lube (4667755)..... <b>BT349</b> Fuel..... <b>BF783</b> O. Air..... <b>PA2475</b> I. Air..... <b>PA2814</b>
190.20N w/8220.02 Eng. Lube (1901919)..... <b>B236 +</b> 123.0 mm Fuel (4764693)..... <b>BF988 +</b> 186.5 mm Fuel (1901605)..... <b>BF783</b> Coolant (1901776)..... <b>BW5143</b>	Eurocargo II 190 E/EL 25 w/Cummins Tector 6 Euro 4/5 Eng. (05/06-08/08) Lube (504033399)..... <b>BT7237</b> Fuel/Water Separator (2992662)..... <b>BF1365</b> Fuel (2992241)..... <b>BF7813</b> Air Dryer (1907612)..... <b>BA5374 +</b> Breather (2992447)..... <b>P7336 KIT</b> Urea (denoxtronic 1) (42562233).. <b>PE5270</b> Urea (denoxtronic 2) (42555073).. <b>PE5271</b>	190PAC26 w/Unic X200 Eng. 206.4 mm Lube (61671160)..... <b>B236 +</b> 231.8 mm Lube (4667339)..... <b>BT349</b> Fuel (61142392)..... <b>BF988 +</b> Fuel/Water Separator..... <b>BF1221 +</b> O. Air..... <b>PA2474</b> I. Air..... <b>PA2836</b>
190PAC20 w/8210.02, 8220.02 Eng. Lube (1174421)..... <b>B236 +</b> Fuel (1909103)..... <b>BF783</b> O. Air (1186389)..... <b>PA2474</b> I. Air (42480759)..... <b>PA2836</b>	Eurocargo III ML 190 E/EL 25 w/Cummins Tector 6 F4A Eng. (06/08-on) Lube (504033399)..... <b>BT7237</b> Fuel/Water Separator (2992662)..... <b>BF1365</b> Fuel (2992241)..... <b>BF7813</b> Air Dryer (1907612)..... <b>BA5374 +</b> Urea (denoxtronic 1) (42562233).. <b>PE5270</b> Urea (denoxtronic 2) (42555073).. <b>PE5271</b>	190PAC26, 190PAT26 w/8210.02 Eng. Lube (4667339)..... <b>BT349</b> Fuel..... <b>BF783</b> 381.0 mm O. Air..... <b>PA2474</b> 379.4 mm I. Air (42480759)..... <b>PA2836</b> 374.7 mm O. Air..... <b>PA2405</b> 473.1 mm I. Air (2394637)..... <b>PA2814</b> Coolant (4734562)..... <b>BW5137</b>
EuroTech 190E24 w/Cursor E0618D Eng. (11/98-on) Lube..... <b>B7174-MPG</b> Fuel/Water Separator (1907539)..... <b>BF1217</b> Fuel..... <b>BF7696</b> Air..... <b>PA2776</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Trans..... <b>PT8385</b> Steering..... <b>P106-HD</b>	Eurocargo III ML 190 E/EL 25 w/Cummins Tector 6 F4A Eng. (06/08-on) Lube (504033399)..... <b>BT7237</b> Fuel/Water Separator (2992662)..... <b>BF1365</b> Fuel (2992241)..... <b>BF7813</b> Air Dryer (1907612)..... <b>BA5374 +</b> Urea (denoxtronic 1) (42562233).. <b>PE5270</b> Urea (denoxtronic 2) (42555073).. <b>PE5271</b>	EuroTech 190E27 w/Cursor E0681 Eng. (11/98-on) Lube..... <b>B7174-MPG</b> Fuel/Water Separator (1907539)..... <b>BF1217</b> Fuel..... <b>BF7696</b> Air..... <b>PA2776</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Trans..... <b>PT8385</b> Steering..... <b>P106-HD</b>
Eurotech 190 E 24 w/8360.46R.416TCA Eng. (07/92-12/98) Dual-Flow Lube (1902102)..... <b>BD325</b> Fuel/Water Separator (1907539)..... <b>BF1217</b> Fuel (1908312)..... <b>BF988 +</b> O. Air (1904550)..... <b>PA2776</b> I. Air (1905620)..... <b>PA3494</b> Air Dryer (1907612)..... <b>BA5374 +</b> Coolant (1901776)..... <b>BW5143</b> Steering (1902137)..... <b>P106-HD</b>	190.26 (4x4), 190.26 (4x6) w/8210.02 Eng. Lube..... <b>BT349</b> Fuel (1901605)..... <b>BF783</b> O. Air (1186389)..... <b>PA2474</b> I. Air (42480759)..... <b>PA2836</b> Coolant (4734562)..... <b>BW5137</b>	Eurotech 190 E 27 w/8360.46.417 TCA Eng. (07/92-12/98) Dual-Flow Lube (1902102)..... <b>BD325</b> Fuel/Water Separator (1907539)..... <b>BF1217</b> Fuel (1908312)..... <b>BF988 +</b> O. Air (1904550)..... <b>PA2776</b> I. Air (1905620)..... <b>PA3494</b> Air Dryer (1907612)..... <b>BA5374 +</b> Steering (1902137)..... <b>P106-HD</b>
EuroTrakker 190 E 24 w/Cursor F2BE0681D Eng. (09/99-11/04) Lube (99445200)..... <b>B7174-MPG</b> Fuel/Water Separator (1907539)..... <b>BF1217</b> Fuel (1907460)..... <b>BF7696</b> O. Air (1904550)..... <b>PA2776</b> I. Air (1905620)..... <b>PA3494</b> Air Dryer (1907612)..... <b>BA5374 +</b> Breather (500339085)..... <b>BT9408</b> Trans. (42491185)..... <b>PT8385</b> Steering (1902137)..... <b>P106-HD</b>	190.26 w/8460.21 Eng. Dual-Flow Lube (1903715)..... <b>BD325</b> Fuel Ele. (1902096)..... <b>PF312</b> Fuel Spin-on..... <b>BF783</b> Air..... <b>PA2474</b> Coolant (1901776)..... <b>BW5143</b>	Stralis Active Day AD190S27/P w/Cursor 8-273 Eng. (06/03-on) Lube (99445200)..... <b>B7174-MPG</b> Fuel/Water Separator (6/03-12/03) (1907539)..... <b>BF1217</b> Fuel (6/03-9/04)..... <b>BF7696</b> Fuel/Water Separator (1/2004-on) (2992662)..... <b>BF1365</b> Air (6/03-9/04)..... <b>PA2776</b> Radial Seal Air (10/04-on) (41272124)..... <b>RS5356</b> Cab Air (w/o Carbon) (504024890)..... <b>PA5336</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Breather (500339085)..... <b>BT9408</b> Trans. (5000807213)..... <b>PT8385</b> Steering..... <b>P106-HD</b>
190E24, 190E27, 190E30 w/8210.42, 8360.46, 8460.41 Eng. Dual-Flow Lube (1907584)..... <b>BD325</b> Fuel/Water Separator (1907539)..... <b>BF1217</b> 148.4 mm Fuel (1907640)..... <b>BF7663</b> 157.2 mm Fuel (1902138)..... <b>BF5587-D</b> Air (1904550)..... <b>PA2776</b> Coolant (1901776)..... <b>BW5143</b> Steering (1902137)..... <b>P106-HD</b>	190.26 TRU, 190.26 TurboTech (1990) Dual-Flow Lube (1907584)..... <b>BD325</b> Fuel (1901605)..... <b>BF783</b> Air (1904550)..... <b>PA2776</b> Coolant (1901776)..... <b>BW5143</b>	


+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

Trucks & Buses Applications **BALDWIN FILTERS**

IVECO Trucks (cont'd)	IVECO Trucks (cont'd)	IVECO Trucks (cont'd)
Eurocargo II 190 E/EL 28 w/Cummins Tector 6 Euro 4/5 Eng. (05/06-08/08) Lube (504033399)..... BT7237 Fuel/Water Separator (2992662).. BF1365 Fuel (2992241)..... BF7813 Air Dryer (1907612)..... BA5374 + Breather (2992447)..... P7336 KIT Urea (denoxtronic 1) (42562233).. PE5270 Urea (denoxtronic 2) (42555073).. PE5271	190.30T w/8210.22 Eng. Lube Spin-on (1901604)..... BT349 Dual-Flow Lube (1907584)..... BD325 Fuel (1909103)..... BF783 O. Air (To 1984)..... PA2474 I. Air..... PA2836 Coolant (1901776)..... BW5143	Eurocargo III ML 190 E/EL 30 w/Cummins Tector 6 F4A Eng. (06/08-on) Lube (504033399)..... BT7237 Fuel/Water Separator (2992662).. BF1365 Fuel (2992241)..... BF7813 Air Dryer (1907612)..... BA5374 + Urea (denoxtronic 1) (42562233).. PE5270 Urea (denoxtronic 2) (42555073).. PE5271
Eurocargo III ML 190 E/EL 28 w/Cummins Tector 6 F4A Eng. (06/08-on) Lube (504033399)..... BT7237 Fuel/Water Separator (2992662).. BF1365 Fuel (2992241)..... BF7813 Air Dryer (1907612)..... BA5374 + Urea (denoxtronic 1) (42562233).. PE5270 Urea (denoxtronic 2) (42555073).. PE5271	190.30 Series III Lube (1907570)..... BT349 Fuel (1901605)..... BF783 Air (1901902)..... PA1885 +	EuroTech 190E31 w/Cursor E0681B Eng. (11/98-on) Lube..... B7174-MPG Fuel/Water Separator (1907539).. BF1217 Fuel..... BF7696 Air..... PA2776 Air Dryer (Mann TB1374X)..... BA5374 + Trans..... PT8385 Steering..... P106-HD
190.29 w/Deutz BF8L413, F8L413 Eng. Lube (1174421)..... B236 + 123.0 mm Fuel (1174423)..... BF7931 136.5 mm Fuel (1174422)..... BF900 295.3 mm Single Air (2168629).. PA2891 473.9 mm O. Air (Standard Media) (1902129)..... PA2776 473.9 mm O. Air (Flame Retardant Media) (299-6154)..... PA30235 471.5 mm I. Air..... PA3494 496.9 mm O. Air (2165059)..... PA2475	EuroTech 190E30 Dual-Flow Lube (1907584)..... BD325 Fuel (1907640)..... BF7663 Air (1904550)..... PA2776 Coolant (1901776)..... BW5143	EuroTrakker 190 E 31 w/Cursor E0681B Eng. (09/99-11/04) Lube (99445200)..... B7174-MPG Fuel/Water Separator (1907539).. BF1217 Fuel (1907460)..... BF7696 O. Air (1904550)..... PA2776 I. Air (1905620)..... PA3494 Air Dryer (1907612)..... BA5374 + Breather (500339085)..... BT9408 Trans. (42491185)..... PT8385 Steering (1902137)..... P106-HD
190.30 TRU Dual-Flow Lube (1907584)..... BD325 Fuel (1901605)..... BF783 282.6 mm O.D. Air (1901902)..... PA1885 + 303.2 mm O.D. Air (1904550)..... PA2776 308.0 mm O.D. Std. Air (1901780)..... PA1886 + 308.0 mm O.D. XP Air (1901780)..... PA1886XP	Eurotech 190 E 30 w/8460.41C.320 Eng. (07/92-06/02) Dual-Flow Lube (1902102)..... BD325 Fuel/Water Separator (1907539).. BF1217 Fuel (1904640)..... BF7663 O. Air (1904550)..... PA2776 I. Air (1905620)..... PA3494 Air Dryer (1907612)..... BA5374 + Coolant (1901776)..... BW5143 Steering (1902137)..... P106-HD	EuroTrakker 190 E 31 w/Cursor E0681B Eng. (11/98-06/02) Lube (99445200)..... B7174-MPG Fuel/Water Separator (1907539).. BF1217 Fuel (1907460)..... BF7696 O. Air (1904550)..... PA2776 I. Air (1905620)..... PA3494 Air Dryer (1907612)..... BA5374 + Breather (500339085)..... BT9408 Trans. (42491185)..... PT8385 Steering (1902137)..... P106-HD
190.30 w/8210.22 Eng. Lube Spin-on (1901604)..... BT349 Dual-Flow Lube (1907584)..... BD325 Fuel (1909103)..... BF783 374.7 mm O. Air (2165049)..... PA2405 371.5 mm I. Air..... PA2835 381.0 mm O. Air (To 1984)..... PA2474 379.4 mm I. Air (To 1984)..... PA2836 496.9 mm O. Air..... PA2475 473.1 mm I. Air (42481020)..... PA2814 Coolant (1901776)..... BW5143	Eurotech 190 E 30 w/Cursor F2BE0681E Eng. (11/98-06/02) Lube (99445200)..... B7174-MPG Fuel/Water Separator (1907539).. BF1217 Fuel (1907460)..... BF7696 O. Air (1904550)..... PA2776 I. Air (1905620)..... PA3494 Air Dryer (1907612)..... BA5374 + Breather (500339085)..... BT9408 Trans. (42491185)..... PT8385 Steering (1902137)..... P106-HD	Stralis Active Day AD190S31/P w/Cursor 8-310 Eng. (06/03-on) Lube (99445200)..... B7174-MPG Fuel/Water Separator (6/03-12/03) (1907539)..... BF1217 Fuel (6/03-9/04)..... BF7696 Fuel/Water Separator (1/2004-on) (2992662)..... BF1365 Air (6/03-9/04)..... PA2776 Radial Seal Air (10/04-on) (41272124)..... RS5356 Cab Air (w/o Carbon) (504024890)..... PA5336 Air Dryer (Mann TB1374X)..... BA5374 + Breather (500339085)..... BT9408 Trans. (5000807213)..... PT8385 Steering..... P106-HD
190.30H, 190.30HT, 190.30HW, 190.30N Lube (1901604)..... BT349 Fuel Ele. (1902096)..... PF312 Fuel Spin-on (1901605)..... BF783 374.7 mm O. Air (1902077)..... PA2405 473.9 mm O. Air (1904550)..... PA2776	EuroTrakker 190 E 30 w/8460.41C320 Eng. (01/93-11/04) Dual-Flow Lube (1903715)..... BD325 Fuel/Water Separator (1907539).. BF1217 Fuel (1904640)..... BF7663 O. Air (1904550)..... PA2776 I. Air (1905620)..... PA3494 Air Dryer (1907612)..... BA5374 + Coolant (1901776)..... BW5143 Steering (1902137)..... P106-HD	190.32 w/Deutz F10L413F Eng. Lube Spin-on (1174421)..... B236 + Dual-Flow Lube (1902102)..... BD325 123.0 mm Fuel (1174423)..... BF7931 136.5 mm Fuel (1174422)..... BF900 295.3 mm O. Air (2168629)..... PA2891 473.9 mm O. Air (Standard Media) (1902129)..... PA2776 473.9 mm O. Air (Flame Retardant Media) (299-6154)..... PA30235 471.5 mm I. Air..... PA3494 496.9 mm O. Air..... PA2475 473.1 mm I. Air..... PA2814
Eurocargo II 190 E/EL 30 w/Cummins Tector 6 Euro 4/5 Eng. (05/06-08/08) Lube (504033399)..... BT7237 Fuel/Water Separator (2992662).. BF1365 Fuel (2992241)..... BF7813 Air Dryer (1907612)..... BA5374 + Breather (2992447)..... P7336 KIT Urea (denoxtronic 1) (42562233).. PE5270 Urea (denoxtronic 2) (42555073).. PE5271	EuroTrakker 190 E 30 w/8460.41C320 Eng. (01/93-11/04) Dual-Flow Lube (1903715)..... BD325 Fuel/Water Separator (1907539).. BF1217 Fuel (1904640)..... BF7663 O. Air (1904550)..... PA2776 I. Air (1905620)..... PA3494 Air Dryer (1907612)..... BA5374 + Coolant (1901776)..... BW5143 Steering (1902137)..... P106-HD	Eurocargo II 190 E/EL 30 w/Cummins Tector 6 Euro 4/5 Eng. (05/06-08/08) Lube (504033399)..... BT7237 Fuel/Water Separator (2992662).. BF1365 Fuel (2992241)..... BF7813 Air Dryer (1907612)..... BA5374 + Breather (2992447)..... P7336 KIT Urea (denoxtronic 1) (42562233).. PE5270 Urea (denoxtronic 2) (42555073).. PE5271

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IVECO Trucks (cont'd)	IVECO Trucks (cont'd)	IVECO Trucks (cont'd)
190.32 TRU (1989), 190.32 TurboTech Dual-Flow Lube (1907584)..... <b>BD325</b> Fuel (1901605)..... <b>BF783</b> Air (1904550)..... <b>PA2776</b> Coolant (1901776)..... <b>BW5143</b>	190.35 Series III Lube (1907570)..... <b>BT349</b> Fuel (1901605)..... <b>BF783</b> Air (1901902)..... <b>PA1885 +</b> Coolant (1901776)..... <b>BW5143</b>	190.36 TRU (1987) Dual-Flow Lube (1907584)..... <b>BD325</b> 419.1 mm Std. Air (1901780)..... <b>PA1886 +</b> 419.1 mm XP Air (1901780)..... <b>PA1886XP</b> 473.9 mm Air (1904550)..... <b>PA2776</b>
190.32, 190.33P, 190.33PT, 190.33T Dual-Flow Lube (1902102)..... <b>BD325</b> Fuel..... <b>BF783</b> Std. Air (1901780)..... <b>PA1886 +</b> XP Air (1901780)..... <b>PA1886XP</b>	EuroTech 190E35 w/Cursor E0681A Eng. (11/98-on) Lube..... <b>B7174-MPG</b> Fuel/Water Separator (1907539)..... <b>BF1217</b> Fuel..... <b>BF7696</b> Air..... <b>PA2776</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Trans..... <b>PT8385</b> Steering..... <b>P106-HD</b>	190.36 TurboStar Dual-Flow Lube (1907584)..... <b>BD325</b> Fuel (1901605)..... <b>BF783</b> 419.1 mm Std. Air (1901780)..... <b>PA1886 +</b> 419.1 mm XP Air (1901780)..... <b>PA1886XP</b> 473.9 mm Air (1904550)..... <b>PA2776</b>
190.33 TurboStar Dual-Flow Lube (1907584)..... <b>BD325</b> Fuel (1901605)..... <b>BF783</b> 419.1 mm Std. Air (1901780)..... <b>PA1886 +</b> 419.1 mm XP Air (1901780)..... <b>PA1886XP</b> 473.9 mm Air (1904550)..... <b>PA2776</b>	EuroTrakker 190 E 35 w/Cursor E0681A Eng. (09/99-11/04) Lube (99445200)..... <b>B7174-MPG</b> Fuel/Water Separator (1907539)..... <b>BF1217</b> Fuel (1907460)..... <b>BF7696</b> O. Air (1904550)..... <b>PA2776</b> I. Air (1905620)..... <b>PA3494</b> Air Dryer (1907612)..... <b>BA5374 +</b> Breather (500339085)..... <b>BT9408</b> Trans. (42491185)..... <b>PT8385</b> Steering (1902137)..... <b>P106-HD</b>	190.36 TurboTech G.V. (1990) Dual-Flow Lube (1907584)..... <b>BD325</b> Fuel (1901605)..... <b>BF783</b> Air (667078)..... <b>PA2813</b>
EuroTech 190E34 w/8460TCA Eng. Dual-Flow Lube (1907584)..... <b>BD325</b> Fuel/Water Separator (1907539)..... <b>BF1217</b> Fuel (1907640)..... <b>BF7663</b> Fuel/Water Separator (Upgrade)..... <b>BF1221 +</b> Air (1904550)..... <b>PA2776</b> Coolant (1901776)..... <b>BW5143</b> Steering (1902137)..... <b>P106-HD</b>	190NC35 w/8280.02 Eng. Lube (1901604)..... <b>BT349</b> Fuel (1909103)..... <b>BF783</b> 496.9 mm O. Air..... <b>PA2475</b> 473.1 mm I. Air..... <b>PA2814</b> 473.9 mm O. Air (Standard Media) (1902129)..... <b>PA2776</b> 473.9 mm O. Air (Flame Retardant Media) (2996154)..... <b>PA30235</b> 471.5 mm I. Air (1905620)..... <b>PA3494</b> Coolant..... <b>BW5137</b>	190E37 w/8210.42, 8360.46, 8460.41 Engs. Dual-Flow Lube (1907584)..... <b>BD325</b> Fuel/Water Separator (1907539)..... <b>BF1217</b> 148.4 mm Fuel (1907640)..... <b>BF7663</b> 157.2 mm Fuel (1902138)..... <b>BF5587-D</b> Air (1904550)..... <b>PA2776</b> Coolant (1901776)..... <b>BW5143</b> Steering (1902137)..... <b>P106-HD</b>
Eurotech 190 E 34 w/8460.41K.406 Eng. (04/92-06/02) Dual-Flow Lube (1902102)..... <b>BD325</b> Fuel/Water Separator (1907539)..... <b>BF1217</b> Fuel (1904640)..... <b>BF7663</b> O. Air (1904550)..... <b>PA2776</b> I. Air (1905620)..... <b>PA3494</b> Air Dryer (1907612)..... <b>BA5374 +</b> Coolant (1901776)..... <b>BW5143</b> Steering (1902137)..... <b>P106-HD</b>	Stralis Active Day AD190S35/P w/Cursor 8-352 Eng. (06/03-on) Lube (99445200)..... <b>B7174-MPG</b> Fuel/Water Separator (6/03-12/03) (1907539)..... <b>BF1217</b> Fuel (6/03-9/04)..... <b>BF7696</b> Fuel/Water Separator (1/2004-on) (2992662)..... <b>BF1365</b> Air (6/03-9/04)..... <b>PA2776</b> Radial Seal Air (10/04-on) (41272124)..... <b>RS5356</b> Cab Air (w/o Carbon) (504024890)..... <b>PA5336</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Breather (500339085)..... <b>BT9408</b> Trans. (5000807213)..... <b>PT8385</b> Steering..... <b>P106-HD</b>	EuroTrakker 190 E 37 w/8210.42(TCA) Eng. (04/93-11/04) Dual-Flow Lube (1903715)..... <b>BD325</b> Fuel/Water Separator (1907539)..... <b>BF1217</b> Fuel (1904640)..... <b>BF7663</b> O. Air (1904550)..... <b>PA2776</b> I. Air (1905620)..... <b>PA3494</b> Air Dryer (1907612)..... <b>BA5374 +</b> Coolant (1901776)..... <b>BW5143</b> Steering (1902137)..... <b>P106-HD</b>
EuroTrakker 190 E 34 w/8460.41K.406 Eng. (04/92-11/04) Dual-Flow Lube (1903715)..... <b>BD325</b> Fuel/Water Separator (1907539)..... <b>BF1217</b> Fuel (1904640)..... <b>BF7663</b> O. Air (1904550)..... <b>PA2776</b> I. Air (1905620)..... <b>PA3494</b> Air Dryer (1907612)..... <b>BA5374 +</b> Coolant (1901776)..... <b>BW5143</b> Steering (1902137)..... <b>P106-HD</b>	190.36P, 190.36PT, 190.36T Dual-Flow Lube (1902102)..... <b>BD325</b> Fuel..... <b>BF783</b> Std. Air (1901780)..... <b>PA1886 +</b> XP Air (1901780)..... <b>PA1886XP</b>	190.38 w/8280.22 Turbo Eng. Dual-Flow Lube (1902102)..... <b>BD325</b> Fuel (1901605)..... <b>BF783</b> O. Air (Standard Media) (1902129)..... <b>PA2776</b> O. Air (Flame Retardant Media) (299-6154)..... <b>PA30235</b> I. Air..... <b>PA3494</b> Single Std. Air (1901780)..... <b>PA1886 +</b> Single XP Air (1901780)..... <b>PA1886XP</b>
190.35 w/8280.02 Eng. Lube (1901604)..... <b>BT349</b> Fuel (1909103)..... <b>BF783</b> 473.9 mm Some O. Air (Standard Media) (1902129)..... <b>PA2776</b> 473.9 mm Some O. Air (Flame Retardant Media) (299-6154)..... <b>PA30235</b> 471.5 mm Some I. Air..... <b>PA3494</b> 496.9 mm O. Air..... <b>PA2475</b> 473.1 mm I. Air..... <b>PA2814</b> Coolant..... <b>BW5137</b>	190.38T w/8280.22 Turbo Eng. Dual-Flow Lube (1902102)..... <b>BD325</b> Fuel (1901605)..... <b>BF783</b> O. Air (Standard Media) (1902129)..... <b>PA2776</b> O. Air (Flame Retardant Media) (299-6154)..... <b>PA30235</b> I. Air (1905620)..... <b>PA3494</b> Single Std. Air (1901780)..... <b>PA1886 +</b> Single XP Air (1901780)..... <b>PA1886XP</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IVECO Trucks (cont'd)	IVECO Trucks (cont'd)	IVECO Trucks (cont'd)
190.38 Series III Fuel (1901605)..... <b>BF783</b> Air (1901902)..... <b>PA1885 +</b> Coolant..... <b>BW5137</b>	EuroStar 190E40 w/Cursor E0681 Eng. (09/00-on) Lube..... <b>B7174-MPG</b> Fuel/Water Separator (1907539). <b>BF1217</b> 473.9 mm Air..... <b>PA2776</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Trans..... <b>PT8385</b> Steering..... <b>P106-HD</b>	EuroTech 190E42 w/8210TCA Eng. (04/92-on) (Cont'd) Air (1904550)..... <b>PA2776</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Coolant..... <b>BW5137</b> Steering..... <b>P106-HD</b>
190.38 TRU Fuel (1901605)..... <b>BF783</b> 419.1 mm Std. Air (1901780)..... <b>PA1886 +</b> 419.1 mm XP Air (1901780)..... <b>PA1886XP</b> 473.9 mm Air (1904550)..... <b>PA2776</b> Coolant (1901776)..... <b>BW5143</b>	EuroTech 190E40 w/Cursor E0681 Eng. (09/00-on) Lube..... <b>B7174-MPG</b> Fuel/Water Separator (1907539). <b>BF1217</b> 473.9 mm Air..... <b>PA2776</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Trans..... <b>PT8385</b> Steering..... <b>P106-HD</b>	Eurotech 190 E 42 w/8210.42L.400 Eng. (04/92-06/02) Dual-Flow Lube (1902102)..... <b>BD325</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel (1904640)..... <b>BF7663</b> O. Air (1904550)..... <b>PA2776</b> I. Air (1905620)..... <b>PA3494</b> Air Dryer (1907612)..... <b>BA5374 +</b> Steering (1902137)..... <b>P106-HD</b>
190.38 TurboStar Dual-Flow Lube (1907584)..... <b>BD325</b> Fuel (1901605)..... <b>BF783</b> 419.1 mm Std. Air (1901780)..... <b>PA1886 +</b> 419.1 mm XP Air (1901780)..... <b>PA1886XP</b> 473.9 mm Air (1904550)..... <b>PA2776</b>	EuroStar 190E40 w/Cursor E0681 Eng. (09/00-on) Lube..... <b>B7174-MPG</b> Fuel/Water Separator (1907539). <b>BF1217</b> 473.9 mm Air..... <b>PA2776</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Trans..... <b>PT8385</b> Steering..... <b>P106-HD</b>	EuroTrakker 190 E 42 w/8210.42L.TCA Eng. (01/95-11/04) Dual-Flow Lube (1903715)..... <b>BD325</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel (1904640)..... <b>BF7663</b> O. Air (1904550)..... <b>PA2776</b> I. Air (1905620)..... <b>PA3494</b> Air Dryer (1907612)..... <b>BA5374 +</b> Coolant (1901776)..... <b>BW5143</b> Steering (1902137)..... <b>P106-HD</b>
190.38 TurboTech (1990) Dual-Flow Lube (1907584)..... <b>BD325</b> Fuel (1901605)..... <b>BF783</b> Air (1904550)..... <b>PA2776</b>	Stralis Active Day AD190S40/P w/Cursor 10-400 Eng. (06/03-on) Lube..... <b>B7174-MPG</b> Fuel/Water Separator (6/03-12/03) (1907539)..... <b>BF1217</b> Fuel/Water Separator (1/2004-on) (2992662)..... <b>BF1365</b> Radial Seal Air (10/04-on) (41272124)..... <b>RS5356</b> Cab Air (w/o Carbon) (504024890)..... <b>PA5336</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Breather (500339085)..... <b>BT9408</b> Trans. (5000807213)..... <b>PT8385</b> Steering..... <b>P106-HD</b>	EuroTrakker 190 E 42 w/8210.42L.TCA Eng. (01/95-11/04) Dual-Flow Lube (1903715)..... <b>BD325</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel (1904640)..... <b>BF7663</b> O. Air (1904550)..... <b>PA2776</b> I. Air (1905620)..... <b>PA3494</b> Air Dryer (1907612)..... <b>BA5374 +</b> Coolant (1901776)..... <b>BW5143</b> Steering (1902137)..... <b>P106-HD</b>
190.38 TurboTech G.V. (1990) Dual-Flow Lube (1907584)..... <b>BD325</b> Fuel (1901605)..... <b>BF783</b> Air (667078)..... <b>PA2813</b>	190.42 TurboStar Fuel (1901605)..... <b>BF783</b> 419.1 mm Std. Air (1901780)..... <b>PA1886 +</b> 419.1 mm XP Air (1901780)..... <b>PA1886XP</b> 473.9 mm Air (1904550)..... <b>PA2776</b> Coolant (1901776)..... <b>BW5143</b>	Stralis 190S42 w/Cursor 10-420 Eng. (03/06-on) Lube..... <b>B7174-MPG</b> Lube (2996416)..... <b>P7495</b> Fuel/Water Separator..... <b>BF1365</b> Radial Seal Air (41272124)..... <b>RS5356</b> Cab Air (w/o Carbon) (504024890)..... <b>PA5336</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Breather (500339085)..... <b>BT9408</b> Trans..... <b>PT8385</b> Steering..... <b>P106-HD</b>
EuroStar 190E38 w/8460.41(TCA) Eng. (06/92-on) Dual-Flow Lube (1907584)..... <b>BD325</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel (1907640)..... <b>BF7663</b> Air (1904550)..... <b>PA2776</b> Coolant (1901776)..... <b>BW5143</b> Steering (1902137)..... <b>P106-HD</b>	EuroStar 190E42 w/8210.42L.TCA Eng. (04/92-on) Dual-Flow Lube (1907584)..... <b>BD325</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel (1907640)..... <b>BF7663</b> Air (1904550)..... <b>PA2776</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Coolant..... <b>BW5137</b> Steering..... <b>P106-HD</b>	EuroStar 190E43 w/Cursor E0681D (Cursor 10) Eng. (10/99-on) Lube (99445200)..... <b>B7174-MPG</b> Fuel/Water Separator (1907539). <b>BF1217</b> 473.9 mm Air..... <b>PA2776</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Trans. (5000807213)..... <b>PT8385</b> Steering..... <b>P106-HD</b>
EuroTrakker 190E38 w/Cursor13 Eng. (01/01-11/04) Lube..... <b>B7174-MPG</b> Fuel/Water Separator (1907539). <b>BF1217</b> 465.9 mm O. Air (41272211)..... <b>PA5364</b> 461.2 mm I. Air (41214149)..... <b>PA5365</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Trans..... <b>PT8385</b> Steering..... <b>P106-HD</b>	EuroStar 190E42 w/8210.42 Eng. (10/99-on) Lube..... <b>B7174-MPG</b> Fuel/Water Separator (1907539). <b>BF1217</b> Air..... <b>BF7663</b> Air (1904550)..... <b>PA2776</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Coolant..... <b>BW5137</b> Steering..... <b>P106-HD</b>	EuroTech 190E43 w/Cursor E0681D Eng. (10/99-on) Lube (99445200)..... <b>B7174-MPG</b> Fuel/Water Separator (1907539). <b>BF1217</b> 473.9 mm Air..... <b>PA2776</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Trans. (5000807213)..... <b>PT8385</b> Steering..... <b>P106-HD</b>
EuroStar 190E39 w/Cursor E0681E Eng. (10/99-on) Lube..... <b>B7174-MPG</b> Fuel/Water Separator (1907539). <b>BF1217</b> Air..... <b>PA2776</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Trans..... <b>PT8385</b> Steering..... <b>P106-HD</b>	EuroTech 190E42 w/8210TCA Eng. (04/92-on) Dual-Flow Lube (1907584)..... <b>BD325</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel (1907640)..... <b>BF7663</b> Air (1904550)..... <b>PA2776</b> Coolant (1901776)..... <b>BW5143</b> Steering (1902137)..... <b>P106-HD</b>	Stralis Active Day AD190S43/P w/Cursor 10-430 Eng. (06/03-on) Lube..... <b>B7174-MPG</b> Fuel/Water Separator (6/03-12/03) (1907539)..... <b>BF1217</b>
EuroTech 190E39 w/Cursor E0681E Eng. (10/99-on) Lube..... <b>B7174-MPG</b> Fuel/Water Separator (1907539). <b>BF1217</b> Air..... <b>PA2776</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Trans..... <b>PT8385</b> Steering..... <b>P106-HD</b>	EuroTech 190E42 w/8210TCA Eng. (04/92-on) Dual-Flow Lube (1907584)..... <b>BD325</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel (1907640)..... <b>BF7663</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IVECO Trucks (cont'd)	IVECO Trucks (cont'd)	IVECO Trucks (cont'd)
Stralis Active Day AD190S43/P w/Cursor 10-430 Eng. (06/03-on) (Cont'd)	EuroStar 190E47 w/8210.42M.(TCA) Eng. (04/92-05/01)	190F, 190F26 w/8210.02 Eng.
<b>Fuel/Water Separator</b> (1/2004-on) (2992662).....	<b>Dual-Flow Lube</b> .....	<b>Lube</b> (4667339).....
<b>Radial Seal Air</b> (10/04-on) (41272124).....	<b>Fuel/Water Separator</b> (1907539).....	<b>Fuel</b> (1909103).....
<b>Cab Air</b> (w/o Carbon) (504024890).....	<b>Fuel</b> .....	<b>O. Air</b> .....
.....	<b>Air</b> .....	<b>I. Air</b> .....
.....	<b>Air Dryer</b> (Mann TB1374X).....	<b>Coolant</b> (1901776).....
.....	<b>Steering</b> .....	190F35 w/8280.02 Eng.
.....	.....	<b>Lube</b> (1901604).....
.....	.....	<b>Fuel</b> (1909103).....
.....	.....	<b>496.9 mm O. Air</b> .....
.....	.....	<b>473.1 mm I. Air</b> .....
.....	.....	<b>473.9 mm O. Air</b> .....
.....	.....	<b>471.5 mm I. Air</b> .....
.....	.....	<b>473.9 mm O. Air</b> (Standard Media) (1902129).....
.....	.....	<b>473.9 mm O. Air</b> (Flame Retardant Media) (2996154).....
.....	.....	<b>Coolant</b> .....
.....	.....	190NC, 190NC20 w/8210.02, 8220.02 Eng.
.....	.....	<b>Lube</b> (1174421).....
.....	.....	<b>Fuel</b> (1909103).....
.....	.....	<b>O. Air</b> (1186389).....
.....	.....	<b>I. Air</b> (42480759).....
.....	.....	190PC30
.....	.....	<b>Lube</b> (1907570).....
.....	.....	<b>Fuel</b> (1901605).....
.....	.....	<b>374.7 mm Air</b> (1902077).....
.....	.....	<b>473.9 mm Air</b> (1904550).....
.....	.....	190T w/Unic V85S Eng.
.....	.....	<b>Steering</b> .....
.....	.....	190U20
.....	.....	<b>Lube</b> (1174421).....
.....	.....	<b>Fuel</b> (61142392).....
.....	.....	<b>Fuel/Water Separator</b> .....
.....	.....	<b>Coolant</b> (1901776).....
.....	.....	190U30
.....	.....	<b>Lube</b> (1907570).....
.....	.....	<b>Fuel</b> (1901605).....
.....	.....	<b>Air</b> (1901902).....
.....	.....	190U35
.....	.....	<b>Fuel</b> (1901605).....
.....	.....	<b>Air</b> (Standard Media) (1902129)...
.....	.....	<b>Air</b> (Flame Retardant Media) (2996154).....
.....	.....	192M14, 192M16 Turbo w/Deutz BF6L913 Eng.
.....	.....	<b>Lube</b> .....
.....	.....	<b>Fuel</b> .....
.....	.....	<b>Fuel/Water Separator</b> .....
.....	.....	<b>O. Air</b> (1902465).....
.....	.....	<b>I. Air</b> (Mann CF1200).....
.....	.....	<b>Single Air</b> (2168629).....
.....	.....	195 w/Deutz F6L814, F8L714, F8L914, F10L714, F10L914 Eng.
.....	.....	<b>P. Fuel Ele.</b> (1168407).....
.....	.....	<b>S. Fuel Ele.</b> (1168398).....
.....	.....	<b>Hyd.</b> (1267900).....

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IVECO Trucks (cont'd)	IVECO Trucks (cont'd)	IVECO Trucks (cont'd)
Jupiter 195, 200, (6x6) SK w/Deutz F8L714 Eng. P. Fuel Ele. (1168407)..... <b>F950-F</b> S. Fuel Ele. (1168398)..... <b>PF950</b>	Z220T Lube (To S/N 334356)..... <b>[2] BT348</b> Dual-Flow Lube (1902076)..... <b>BD232</b> Fuel..... <b>[2] BF988 +</b> Air (1902077)..... <b>PA2405</b>	Z235T Dual-Flow Lube (1902076)..... <b>BD232</b> Fuel..... <b>[2] BF988 +</b> Air (1902077)..... <b>PA2405</b>
T200A Lube..... <b>P235</b>	220.29 w/Deutz BF8L413 Eng. Lube (1174421)..... <b>B236 +</b> Fuel (1174422)..... <b>BF900</b> 295.3 mm Single Air (2168629)..... <b>PA2891</b> 473.9 mm O. Air (Standard Media) (1902129)..... <b>PA2776</b> 473.9 mm O. Air (Flame Retardant Media) (299-6154)..... <b>PA30235</b> 471.5 mm I. Air (1905620)..... <b>PA3494</b> 496.9 mm O. Air (2165059)..... <b>PA2475</b>	232D13, 232D14, 232D15, 232D15.5, 232D16, 232D17, 232D19 w/Deutz F8L413 Eng. Lube (1160025)..... <b>B236 +</b> Fuel/Water Separator..... <b>BF1221 +</b> P. Fuel Ele. (1168403)..... <b>F953-F</b> S. Fuel Ele. (1160217)..... <b>PF834</b> Fuel Spin-on (1160243)..... <b>BF988 +</b> O. Air (2165044)..... <b>PA2845</b> I. Air..... <b>PA2837</b> Single Air (2168629)..... <b>PA2891</b> Hyd. (1267900)..... <b>PT691</b>
200A13FL, 200A13FS w/8220 Eng. Lube..... <b>BT349</b> Fuel..... <b>BF876</b> 316.7 mm Air (998-5779)..... <b>PA1882</b> 342.9 mm Air (Don. P181034)..... <b>PA1884 +</b>	220.32 TurboTech Dual-Flow Lube (1903715)..... <b>BD325</b> Fuel..... <b>BF783</b> Air (1904550)..... <b>PA2776</b> Coolant (1901776)..... <b>BW5143</b>	235D18, 235D20, 235D22 w/Deutz F6L814, F8L714, F8L914, F10L714, F10L914 Eng. P. Fuel Ele. (1168407)..... <b>F950-F</b> S. Fuel Ele. (1168398)..... <b>PF950</b> Hyd. (1267900)..... <b>PT691</b>
200D16, 200D22, 200D26 w/Deutz F6L814, F8L714, F8L914, F10L714, F10L914 Eng. P. Fuel Ele. (1168407)..... <b>F950-F</b> S. Fuel Ele. (1168398)..... <b>PF950</b> Hyd. (1267900)..... <b>PT691</b>	220.35 w/8280.02 Eng. Lube (1901604)..... <b>BT349</b> Fuel (1901605)..... <b>BF783</b> O. Air..... <b>PA2475</b> I. Air (42481020)..... <b>PA2814</b> O. Air (Standard Media) (1902129)..... <b>PA2776</b> O. Air (Flame Retardant Media) (299-6154)..... <b>PA30235</b> Coolant (1901776)..... <b>BW5143</b>	240.26 w/8210.02 Eng. Lube (4667339)..... <b>BT349</b> Fuel (1909103)..... <b>BF783</b> 374.7 mm O. Air..... <b>PA2405</b> 473.1 mm I. Air (2394637)..... <b>PA2814</b> 381.0 mm O. Air (1186389)..... <b>PA2474</b> 379.4 mm I. Air (42480759)..... <b>PA2836</b> Coolant (4734562)..... <b>BW5139</b>
200D10FS 168.3 mm Lube (1161934)..... <b>B7031</b> 206.4 mm Lube (1160025)..... <b>B236 +</b> Fuel (1160243)..... <b>BF988 +</b> Fuel/Water Separator..... <b>BF1221 +</b>	220.36 TRU (1987) Dual-Flow Lube (1907584)..... <b>BD325</b> Fuel (1901605)..... <b>BF783</b> 419.1 mm Std. Air (1901780)..... <b>PA1886 +</b> 419.1 mm XP Air (1901780)..... <b>PA1886XP</b> 473.9 mm Air (1904550)..... <b>PA2776</b>	240.26 TRU (1988), 240.26 TurboTech Dual-Flow Lube (1907584)..... <b>BD325</b> Fuel (1901605)..... <b>BF783</b> Air (1904550)..... <b>PA2776</b> Coolant (1901776)..... <b>BW5143</b>
210D14 w/Deutz F6L413 Eng. Lube (1160025)..... <b>B236 +</b> Fuel (1160243)..... <b>BF988 +</b> Fuel/Water Separator..... <b>BF1221 +</b> Air (2168629)..... <b>PA2891</b>	220.38T w/8280.22 Turbo Eng. Dual-Flow Lube (1902102)..... <b>BD325</b> Fuel (1901605)..... <b>BF783</b> O. Air (Standard Media) (1902129)..... <b>PA2776</b> O. Air (Flame Retardant Media) (2996154)..... <b>PA30235</b> I. Air..... <b>PA3494</b> Single Std. Air (1901780)..... <b>PA1886 +</b> Single XP Air (1901780)..... <b>PA1886XP</b>	240.30 w/8210 Turbo Eng. Lube (1901604)..... <b>BT349</b> Fuel (1909103)..... <b>BF783</b> O. Air..... <b>PA2475</b> I. Air..... <b>PA2814</b>
210D16, 210D18 w/Deutz F6L814, F8L714, F8L914, F10L714, F10L914 Eng. P. Fuel Ele. (1168407)..... <b>F950-F</b> S. Fuel Ele. (1168398)..... <b>PF950</b> Hyd. (1267900)..... <b>PT691</b>	230D16, 230D22, 230D26 w/Deutz F8L914 Eng. P. Fuel Ele. (1168403)..... <b>F953-F</b> S. Fuel (1160217)..... <b>PF834</b> Hyd. (1267900)..... <b>PT691</b>	240.30 w/8210.22 Eng. Dual-Flow Lube (1902102)..... <b>BD325</b> Fuel (1901605)..... <b>BF783</b> 374.7 mm O. Air (2165049)..... <b>PA2405</b> 371.5 mm I. Air..... <b>PA2835</b> 496.9 mm O. Air..... <b>PA2475</b> 473.1 mm I. Air (42481020)..... <b>PA2814</b> Coolant (1901776)..... <b>BW5143</b>
EuroCargo ML210E23T/P w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... <b>BD325</b> Fuel/Water Separator (1907539)..... <b>BF1217</b> Fuel..... <b>BF7663</b> Air..... <b>PA3760</b> Steering..... <b>P106-HD</b>	Z220T Dual-Flow Lube (1902076)..... <b>BD232</b> Fuel..... <b>[2] BF988 +</b> Air (1902077)..... <b>PA2405</b>	Eurotech 240 E 30 w/8460.41C.320 Eng. (01/97-06/02) Dual-Flow Lube (1902102)..... <b>BD325</b> Fuel/Water Separator (1907539)..... <b>BF1217</b> Fuel (1904640)..... <b>BF7663</b> O. Air (1904550)..... <b>PA2776</b> I. Air (1905620)..... <b>PA3494</b> Air Dryer (1907612)..... <b>BA5374 +</b> Coolant (1901776)..... <b>BW5143</b> Steering (1902137)..... <b>P106-HD</b>
220.36 TurboTech, 220.38 TurboTech (1990) Dual-Flow Lube (1907584)..... <b>BD325</b> Fuel (1901605)..... <b>BF783</b> Air (1904550)..... <b>PA2776</b>		
241, 241B Lube (4236942)..... <b>BT5</b>		
290D26 w/Deutz F10L413 Eng. Lube (1174421)..... <b>B236 +</b> Fuel (1174422)..... <b>BF900</b>		
29.9, 29.11, 29.13 w/SOFIM Eng. Dual-Flow Lube (1907582)..... <b>BD232</b> Fuel Spin-on..... <b>BF587-D +</b>		
Z220, Z220A w/8060 Eng. Lube..... <b>[2] BT348</b> Fuel..... <b>[2] BF988 +</b> Air..... <b>PA1972</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



IVECO Trucks (cont'd)	IVECO Trucks (cont'd)	IVECO Trucks (cont'd)
EuroTech 240E31 w/Cursor E0681B Eng. (10/98-on) <b>Lube</b> ..... B7174-MPG <b>Fuel/Water Separator</b> (1907539). BF1217 <b>Fuel</b> ..... BF7696 <b>Air</b> ..... PA2776 <b>Air Dryer</b> (Mann TB1374X)..... BA5374 + <b>Trans.</b> ..... PT8385 <b>Steering</b> ..... P106-HD	240.36 TurboTech (1990) <b>Dual-Flow Lube</b> (1907584)..... BD325 <b>Fuel</b> (1901605)..... BF783 <b>Air</b> (1904550)..... PA2776 240.36 TurboTech G.V. (1990) <b>Dual-Flow Lube</b> (1907584)..... BD325 <b>Fuel</b> (1901605)..... BF783 <b>Air</b> (667078)..... PA2813 240.38 TurboTech (1990) <b>Dual-Flow Lube</b> (1907584)..... BD325 <b>Fuel</b> (1901605)..... BF783 <b>Air</b> (1904550)..... PA2776 240.38 w/8280.22 Turbo Eng. <b>Dual-Flow Lube</b> (1902102)..... BD325 <b>Fuel</b> (1901605)..... BF783 <b>O. Air</b> (Standard Media) (1902129)..... PA2776 <b>O. Air</b> (Flame Retardant Media) (2996154)..... PA30235 <b>I. Air</b> (1905620)..... PA3494 <b>Single Std. Air</b> (1901780)..... PA1886 + <b>Single XP Air</b> (1901780)..... PA1886XP	EuroTech 240E39 w/Cursor E0681E Eng. (10/99-on) <b>Lube</b> ..... B7174-MPG <b>Fuel/Water Separator</b> (1907539). BF1217 <b>Air</b> ..... PA2776 <b>Air Dryer</b> (Mann TB1374X)..... BA5374 + <b>Trans.</b> ..... PT8385 <b>Steering</b> ..... P106-HD EuroStar 240E42 w/8210.42L.400 Eng. (04/92-on) <b>Dual-Flow Lube</b> ..... BD325 <b>Fuel/Water Separator</b> (1907539). BF1217 <b>Fuel</b> ..... BF7663 <b>Air</b> ..... PA2776 <b>Air Dryer</b> (Mann TB1374X)..... BA5374 + <b>Steering</b> ..... P106-HD EuroTech 240E42 w/8210 Eng. (04/92-on) <b>Dual-Flow Lube</b> (1907584)..... BD325 <b>Fuel/Water Separator</b> (1907539). BF1217 <b>Fuel</b> (1907640)..... BF7663 <b>Air</b> (1904550)..... PA2776 <b>Coolant</b> (1901776)..... BW5143 <b>Steering</b> (1902137)..... P106-HD Eurotech 240 E 42 w/8210.42L.400 Eng. (04/92-06/02) <b>Dual-Flow Lube</b> (1902102)..... BD325 <b>Fuel/Water Separator</b> (1907539). BF1217 <b>Fuel</b> (1904640)..... BF7663 <b>O. Air</b> (1904550)..... PA2776 <b>I. Air</b> (1905620)..... PA3494 <b>Air Dryer</b> (1907612)..... BA5374 + <b>Coolant</b> (1901776)..... BW5143 <b>Steering</b> (1902137)..... P106-HD 240.23 w/Deutz F8L413 Eng. <b>Lube</b> (1174421)..... B236 + <b>Fuel</b> (1174423)..... BF7931 <b>Fuel/Water Separator</b> ..... BF1221 + <b>O. Air</b> (9983764)..... PA2475 <b>I. Air</b> ..... PA2814 <b>Trans.</b> ..... PT691
EuroTech 240E34 w/8210.42, 8460.41 Eng. <b>Dual-Flow Lube</b> (1907584)..... BD325 <b>Fuel/Water Separator</b> (1907539). BF1217 <b>Fuel</b> (1907640)..... BF7663 <b>Air</b> (1904550)..... PA2776 <b>Coolant</b> (1901776)..... BW5143 <b>Steering</b> (1902137)..... P106-HD 240 E 34 w/8460.41K.(TCA) Eng. (05/95-06/02) <b>Dual-Flow Lube</b> (1902102)..... BD325 <b>Fuel/Water Separator</b> (1907539). BF1217 <b>Fuel</b> (1904640)..... BF7663 <b>O. Air</b> (1904550)..... PA2776 <b>I. Air</b> (1905620)..... PA3494 <b>Air Dryer</b> (1907612)..... BA5374 + <b>Coolant</b> (1901776)..... BW5143 <b>Steering</b> (1902137)..... P106-HD 240.35 w/8280.02 Eng. <b>Lube</b> (1901604)..... BT349 <b>Fuel</b> (1901605)..... BF783 <b>O. Air</b> ..... PA2475 <b>I. Air</b> (42481020)..... PA2814 <b>O. Air</b> (Standard Media) (1902129)..... PA2776 <b>O. Air</b> (Flame Retardant Media) (2996154)..... PA30235 <b>Coolant</b> (1901776)..... BW5143	EuroStar 240E38 w/8460.41L.5020 Eng. (09/92-on) <b>Dual-Flow Lube</b> ..... BD325 <b>Fuel/Water Separator</b> (1907539). BF1217 <b>Fuel</b> ..... BF7663 <b>Air</b> ..... PA2776 <b>Air Dryer</b> (Mann TB1374X)..... BA5374 + <b>Coolant</b> (1901776)..... BW5143 <b>Steering</b> ..... P106-HD EuroTech 240E38 w/8210.42, 8460.41 Eng. <b>Dual-Flow Lube</b> (1907584)..... BD325 <b>Fuel/Water Separator</b> (1907539). BF1217 <b>Fuel</b> (1907640)..... BF7663 <b>Air</b> (1904550)..... PA2776 <b>Coolant</b> (1901776)..... BW5143 <b>Steering</b> (1902137)..... P106-HD Eurotech 240 E 38 w/8460.41L.5020 Eng. (09/92-06/02) <b>Dual-Flow Lube</b> (1902102)..... BD325 <b>Fuel/Water Separator</b> (1907539). BF1217 <b>Fuel</b> (1904640)..... BF7663 <b>O. Air</b> (1904550)..... PA2776 <b>I. Air</b> (1905620)..... PA3494 <b>Air Dryer</b> (1907612)..... BA5374 + <b>Coolant</b> (1901776)..... BW5143 <b>Steering</b> (1902137)..... P106-HD	EuroStar 240E43 w/Cursor E0681D (Cursor 10) Eng. (10/99-on) <b>Lube</b> (99445200)..... B7174-MPG <b>Fuel/Water Separator</b> (1907539). BF1217 <b>473.9 mm Air</b> ..... PA2776 <b>Air Dryer</b> (Mann TB1374X)..... BA5374 + <b>Trans.</b> (5000807213)..... PT8385 <b>Steering</b> ..... P106-HD EuroTech 240E43 w/Cursor E0681D Eng. (10/99-on) <b>Lube</b> (99445200)..... B7174-MPG <b>Fuel/Water Separator</b> (1907539). BF1217 <b>473.9 mm Air</b> ..... PA2776 <b>Air Dryer</b> (Mann TB1374X)..... BA5374 + <b>Trans.</b> (5000807213)..... PT8385 <b>Steering</b> ..... P106-HD
EuroTech 240E35 w/Cursor E0681A Eng. (10/98-on) <b>Lube</b> ..... B7174-MPG <b>Fuel/Water Separator</b> (1907539). BF1217 <b>Fuel</b> ..... BF7696 <b>Air</b> ..... PA2776 <b>Air Dryer</b> (Mann TB1374X)..... BA5374 + <b>Trans.</b> ..... PT8385 <b>Steering</b> ..... P106-HD 240.36 TRU (1987), 240.36 TurboStar <b>Dual-Flow Lube</b> (1907584)..... BD325 <b>Fuel</b> (1901605)..... BF783 <b>419.1 mm Std. Air</b> (1901780)..... PA1886 + <b>419.1 mm XP Air</b> (1901780)..... PA1886XP <b>473.9 mm Air</b> (1904550)..... PA2776		

+ See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IVECO Trucks (cont'd)	IVECO Trucks (cont'd)	IVECO Trucks (cont'd)
EuroStar 240E46 w/Cursor 13 (Euro2) Eng. (01/01-on) Lube (99445200)..... <b>B7174-MPG</b> Fuel/Water Separator (1907539)..... <b>BF1217</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Trans. (5000807213)..... <b>PT8385</b> Steering..... <b>P106-HD</b>	EuroMover 250 w/Cursor 8 Eng. (04/05-on) Lube..... <b>B7174-MPG</b> Fuel/Water Separator (1907539)..... <b>BF1217</b> Fuel..... <b>BF7696</b> Radial Seal Air (41272124)..... <b>RS5356</b> Cab Air (w/o Carbon) (504024890)..... <b>PA5336</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Breather (500339085)..... <b>BT9408</b> Steering..... <b>P106-HD</b>	EuroTech 260E24 w/Cursor E0618D Eng. (11/98-on) (Cont'd) Air..... <b>PA2776</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Trans..... <b>PT8385</b> Steering..... <b>P106-HD</b>
EuroStar 240E47 w/8210.42M (TCA) Eng. (11/95-05/01) Dual-Flow Lube (1907584)..... <b>BD325</b> Fuel/Water Separator (1907539)..... <b>BF1217</b> Fuel (1907640)..... <b>BF7663</b> Air (1904550)..... <b>PA2776</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Steering (1902137)..... <b>P106-HD</b>	250D22 w/Deutz F6L814, F8L714, F8L914, F10L714, F10L914 Engs. P. Fuel Ele. (1168407)..... <b>F950-F</b> S. Fuel Ele. (1168398)..... <b>PF950</b> Hyd. (1267900)..... <b>PT691</b>	260.25 w/Deutz F8L413 Eng. Lube..... <b>B236 +</b> Fuel..... <b>BF988 +</b> Opt. Fuel/Water Separator..... <b>BF1221 +</b> O. Air..... <b>PA2475</b> I. Air..... <b>PA2814</b>
240.48 TurboStar w/8280.42 Eng. Dual-Flow Lube (1907571)..... <b>BD7168</b> Fuel..... <b>BF988 +</b> Air..... <b>PA3754</b> Coolant..... <b>BW5137</b>	EuroCargo ML250E23T/P w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... <b>BD325</b> Fuel/Water Separator (1907539)..... <b>BF1217</b> Fuel..... <b>BF7663</b> Air..... <b>PA3760</b> Steering..... <b>P106-HD</b>	260.26 w/8210.02 Eng. Lube (1909137)..... <b>BT349</b> Fuel..... <b>BF783</b> 381.0 mm O. Air (1902465)..... <b>PA2474</b> 379.4 mm I. Air (Mann CF1200)..... <b>PA2836</b> 496.9 mm O. Air (1901925)..... <b>PA2475</b> 473.1 mm I. Air (Mann CF1300)..... <b>PA2814</b> 374.7 mm O. Air..... <b>PA2405</b> 473.1 mm I. Air (2394637)..... <b>PA2814</b> Coolant (4734562)..... <b>BW5137</b>
EuroStar 240E48 w/Cursor 13 Eng. (01/01-on) Lube (99445200)..... <b>B7174-MPG</b> Fuel/Water Separator (1907539)..... <b>BF1217</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Trans. (5000807213)..... <b>PT8385</b> Steering..... <b>P106-HD</b>	256D16 w/Deutz F8L413 Eng. Lube (1160025)..... <b>B236 +</b> Fuel (1160243)..... <b>BF988 +</b> Opt. Fuel/Water Separator..... <b>BF1221 +</b> Air (2168629)..... <b>PA2891</b>	260.26H, 260.26N, 260.26NW Lube (1907570)..... <b>BT349</b> Fuel (1901605)..... <b>BF783</b> Air (1901925)..... <b>PA2475</b>
EuroStar 240E52 w/8280.42.(TCA) Eng. (04/92-on) Dual-Flow Lube (1907571)..... <b>BD7168</b> Fuel/Water Separator (1907539)..... <b>BF1217</b> Fuel (1907640)..... <b>BF7663</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Coolant (1901776)..... <b>BW5143</b> Steering (1902137)..... <b>P106-HD</b>	256D19 Lube (1160025)..... <b>B236 +</b> Fuel (1160243)..... <b>BF988 +</b> Opt. Fuel/Water Separator..... <b>BF1221 +</b> O. Air (2165044)..... <b>PA2845</b> I. Air..... <b>PA2837</b>	EuroTech 260E27 w/Cursor E0681 Eng. (11/99-on) Lube..... <b>B7174-MPG</b> Fuel/Water Separator (1907539)..... <b>BF1217</b> Fuel..... <b>BF7696</b> Air..... <b>PA2776</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Trans..... <b>PT8385</b> Steering..... <b>P106-HD</b>
240F26, 240F35 w/8280 Eng. Lube (4667339)..... <b>BT349</b> Fuel (1909103)..... <b>BF783</b> 381.0 mm O. Air (1186389)..... <b>PA2474</b> 379.4 mm I. Air..... <b>PA2836</b> 496.9 mm O. Air (74980649)..... <b>PA2475</b> 473.1 mm I. Air..... <b>PA2814</b> Coolant (4734562)..... <b>BW5139</b>	256D22, 256D26 w/Deutz F8L413 Eng. Lube (1160025)..... <b>B236 +</b> Fuel (1160243)..... <b>BF988 +</b> Opt. Fuel/Water Separator..... <b>BF1221 +</b> Air (2168629)..... <b>PA2891</b>	Eurocargo II 260 E 28 w/Cummins Tector 6 Eng. (06/03-08/08) Lube (504033399)..... <b>BT7237</b> Fuel/Water Separator (2992662)..... <b>BF1365</b> Fuel (2992241)..... <b>BF7813</b> Radial Seal Air (504000160)..... <b>RS4969</b> Air Dryer (1907612)..... <b>BA5374 +</b> Breather (2992447)..... <b>P7336 KIT</b>
240F35 w/8210.02 Eng. Lube (4667339)..... <b>BT349</b> Fuel (1909103)..... <b>BF783</b> 496.9 mm O. Air (1186389)..... <b>PA2474</b> 379.4 mm I. Air (42480759)..... <b>PA2836</b> 374.7 mm O. Air..... <b>PA2405</b> 473.1 mm I. Air (2394637)..... <b>PA2814</b> Coolant (4734562)..... <b>BW5137</b>	256M19 w/Deutz F8L413 Eng. Lube (1174421)..... <b>B236 +</b> Fuel (1174423)..... <b>BF7931</b> Fuel/Water Separator..... <b>BF1221 +</b> O. Air (9983764)..... <b>PA2475</b> I. Air..... <b>PA2814</b> Trans. (ML480)..... <b>PT691</b>	Eurocargo II 260 E 28 w/Cummins Tector 6 Euro 4/5 Eng. (05/06-08/08) Lube (504033399)..... <b>BT7237</b> Fuel/Water Separator (2992662)..... <b>BF1365</b> Fuel (2992241)..... <b>BF7813</b> Air Dryer (1907612)..... <b>BA5374 +</b> Breather (2992447)..... <b>P7336 KIT</b> Urea (denoxtronic 1) (42562233)..... <b>PE5270</b> Urea (denoxtronic 2) (42555073)..... <b>PE5271</b>
Beta 250.251 Lube..... <b>PT48</b> Fuel Ele. (2177074)..... <b>PF950</b>	260.23 w/Deutz F8L413 Eng. Lube (1174421)..... <b>B236 +</b> Fuel (1174423)..... <b>BF7931</b> Opt. Fuel/Water Separator..... <b>BF1221 +</b> O. Air (9983764)..... <b>PA2475</b> I. Air..... <b>PA2814</b> Trans..... <b>PT691</b>	260.30 w/8210.22 Eng. Dual-Flow Lube (1902102)..... <b>BD325</b> Fuel (1901605)..... <b>BF783</b> 374.7 mm O. Air (2165049)..... <b>PA2405</b> 371.5 mm I. Air..... <b>PA2835</b>
	EuroTech 260E24 w/Cursor E0618D Eng. (11/98-on) Lube..... <b>B7174-MPG</b> Fuel/Water Separator (1907539)..... <b>BF1217</b> Fuel..... <b>BF7696</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IVECO Trucks (cont'd)	IVECO Trucks (cont'd)	IVECO Trucks (cont'd)
260.30 w/8210.22 Eng. (Cont'd)	260.32 w/Deutz F10L413F Eng.	260.36 TRU, 260.36 TurboStar
496.9 mm O. Air..... PA2475	F-F Lube (1174421)..... B236 +	Dual-Flow Lube (1907584)..... BD325
473.1 mm I. Air..... PA2814	136.5 mm Fuel (1174422)..... BF900	Fuel (1901605)..... BF783
Coolant (1901776)..... BW5143	123.0 mm Some Fuel (1174423)..... BF7931	419.1 mm Std. Air (1901780)..... PA1886 +
260.30H	295.3 mm O. Air (2168629)..... PA2891	419.1 mm XP Air (1901780)..... PA1886XP
Lube (1907570)..... BT349	473.9 mm O. Air..... PA2776	473.9 mm Air (1904550)..... PA2776
Fuel (1901605)..... BF783	471.5 mm I. Air..... PA3494	Coolant (1901776)..... BW5143
374.7 mm O. Air (1902077)..... PA2405	496.9 mm O. Air..... PA2475	EuroTrakker 260E37 w/8210.42 Eng.
473.9 mm O. Air (1904550)..... PA2776	473.1 mm I. Air..... PA2814	Dual-Flow Lube (1907584)..... BD325
260.30 TRU (1988)	260.32 TurboTech w/Iveco Eng.	Fuel/Water Separator (1907539)..... BF1217
Dual-Flow Lube (1907584)..... BD325	Dual-Flow Lube (1903715)..... BD325	Fuel (1907640)..... BF7663
Fuel (1901605)..... BF783	Fuel (1909103)..... BF783	O. Air (1904550)..... PA2776
419.1 mm Std. Air (1901780)..... PA1886 +	Air (1904550)..... PA2776	Coolant (1901776)..... BW5143
419.1 mm XP Air (1901780)..... PA1886XP	Coolant (1901776)..... BW5143	Steering (1902137)..... P106-HD
473.9 mm Air (1904550)..... PA2776	EuroTrakker 260 E 34 w/8460.41K Eng.	EuroTrakker 260 E 37 w/8210.42K(TCA) Eng.
Eurotech 260 E 30 w/Cursor F2BE0681E Eng.	(01/93-12/98)	(12/94-11/04)
(11/98-06/02)	Dual-Flow Lube (1903715)..... BD325	Dual-Flow Lube (1903715)..... BD325
Lube (99445200)..... B7174-MPG	Fuel/Water Separator (1907539)..... BF1217	Fuel/Water Separator (1907539)..... BF1217
Fuel/Water Separator (1907539)..... BF1217	Fuel (1904640)..... BF7663	Fuel (1904640)..... BF7663
Fuel (1907460)..... BF7696	O. Air (1904550)..... PA2776	O. Air (1904550)..... PA2776
O. Air (1904550)..... PA2776	I. Air (1905620)..... PA3494	I. Air (1905620)..... PA3494
Air (1905620)..... PA3494	Air Dryer (1907612)..... BA5374 +	Air Dryer (1907612)..... BA5374 +
Air Dryer (1907612)..... BA5374 +	Coolant (1901776)..... BW5143	Coolant (1901776)..... BW5143
Breather (500339085)..... BT9408	Steering (1902137)..... P106-HD	Steering (1902137)..... P106-HD
Trans. (42491185)..... PT8385	260.35 w/8280.02 Eng.	EuroStar 260E38 w/8460.41L TCA Eng.
Steering (1902137)..... P106-HD	Lube (1901604)..... BT349	(06/92-09/95)
EuroTrakker 260 E 30 w/8460.41C320 Eng.	Fuel (1901605)..... BF783	Dual-Flow Lube (1907584)..... BD325
(01/93-11/04)	O. Air..... PA2475	Fuel/Water Separator (1907539)..... BF1217
Dual-Flow Lube (1903715)..... BD325	I. Air..... PA2814	Fuel (1907640)..... BF7663
Fuel/Water Separator (1907539)..... BF1217	O. Air (Standard Media)	Air (1904550)..... PA2776
Fuel (1904640)..... BF7663	(1902129)..... PA2776	Air Dryer (Mann TB1374X)..... BA5374 +
O. Air (1904550)..... PA2776	O. Air (Flame Retardant Media)	Coolant (1901776)..... BW5143
I. Air (1905620)..... PA3494	(2996154)..... PA30235	Steering (1902137)..... P106-HD
Air Dryer (1907612)..... BA5374 +	Coolant (1901776)..... BW5143	EuroTech 260E38 w/8460.41 Eng.
Coolant (1901776)..... BW5143	EuroTech 260E35 w/Cursor E0681A Eng.	Dual-Flow Lube (1907584)..... BD325
Steering (1902137)..... P106-HD	(10/98-on)	Fuel/Water Separator (1907539)..... BF1217
EuroTech 260E31 w/Cursor E0681B Eng.	Lube..... B7174-MPG	Fuel (1907640)..... BF7663
(11/98-on)	Fuel/Water Separator (1907539)..... BF1217	Air (1904550)..... PA2776
Lube..... B7174-MPG	Fuel..... BF7696	Coolant (1901776)..... BW5143
Fuel/Water Separator (1907539)..... BF1217	Air..... PA2776	Steering (1902137)..... P106-HD
Fuel..... BF7696	Air Dryer (Mann TB1374X)..... BA5374 +	EuroTrakker 260E38 w/Cursor13 Eng.
Air..... PA2776	Trans..... PT8385	(01/01-11/04)
Air Dryer (Mann TB1374X)..... BA5374 +	Steering..... P106-HD	Lube..... B7174-MPG
Trans..... PT8385	EuroTrakker 260 E 35 w/Cursor E0681A Eng.	Fuel/Water Separator (1907539)..... BF1217
Steering..... P106-HD	(02/99-11/04)	465.9 mm O. Air (4127221)..... PA5364
EuroTrakker 260 E 31 w/Cursor E0681B Eng.	Lube (99445200)..... B7174-MPG	461.2 mm I. Air (41214149)..... PA5365
(02/99-11/04)	Fuel/Water Separator (1907539)..... BF1217	Air Dryer (Mann TB1374X)..... BA5374 +
Lube (99445200)..... B7174-MPG	Fuel (1907460)..... BF7696	Breather (500339085)..... BT9408
Fuel/Water Separator (1907539)..... BF1217	O. Air (1904550)..... PA2776	Trans..... PT8385
Fuel (1907460)..... BF7696	I. Air (1905620)..... PA3494	Steering..... P106-HD
O. Air (1904550)..... PA2776	Air Dryer (1907612)..... BA5374 +	Eurotech 260 E 38 w/8460.41L TCA Eng.
I. Air (1905620)..... PA3494	Breather (500339085)..... BT9408	(06/92-09/95)
Air Dryer (1907612)..... BA5374 +	Trans. (42491185)..... PT8385	Dual-Flow Lube (1902102)..... BD325
Breather (500339085)..... BT9408	Steering (1902137)..... P106-HD	Fuel/Water Separator (1907539)..... BF1217
Trans. (42491185)..... PT8385	EuroTrakker 260 E 38 w/8460.41L TCA Eng.	Fuel (1904640)..... BF7663
Steering (1902137)..... P106-HD	(06/92-09/95)	O. Air (1904550)..... PA2776
		I. Air (1905620)..... PA3494

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IVECO Trucks (cont'd)	IVECO Trucks (cont'd)	IVECO Trucks (cont'd)
Eurotech 260 E 38 w/8460.41L TCA Eng. (06/92-09/95) (Cont'd) Air Dryer (1907612)..... BA5374 + Coolant (1901776)..... BW5143 Steering (1902137)..... P106-HD	Eurotech 260 E 42 w/8210.42L.400 Eng. (06/92-06/02) Dual-Flow Lube (1902102)..... BD325 Fuel/Water Separator (1907539) BF1217 Fuel (1904640)..... BF7663 O. Air (1904550)..... PA2776 I. Air (1905620)..... PA3494 Air Dryer (1907612)..... BA5374 + Steering (1902137)..... P106-HD	EuroStar 260E47 w/8210.42M (TCA) Eng. (06/92-05/01) (Cont'd) Air (1904550)..... PA2776 Air Dryer (Mann TB1374X)..... BA5374 + Steering (1902137)..... P106-HD
EuroStar 260E39 w/Cursor E0681E Eng. (10/99-on) Lube..... B7174-MPG Fuel/Water Separator (1907539) BF1217 Air..... PA2776 Air Dryer (Mann TB1374X)..... BA5374 + Steering..... P106-HD	EuroTrakker 260 E 42 w/8210.42 Eng. (09/98-11/04) Dual-Flow Lube (1903715)..... BD325 Fuel/Water Separator (1907539) BF1217 Fuel (1904640)..... BF7663 O. Air (1904550)..... PA2776 I. Air (1905620)..... PA3494 Air Dryer (1907612)..... BA5374 + Coolant (1901776)..... BW5143 Steering (1902137)..... P106-HD	EuroTrakker 260 E 47 w/8210.42M (TCA) Eng. (01/00-11/04) Dual-Flow Lube (1903715)..... BD325 Fuel/Water Separator (1907539) BF1217 Fuel (1904640)..... BF7663 Air (2991793)..... PA3606 Air Dryer (1907612)..... BA5374 + Coolant (1901776)..... BW5143 Steering (1902137)..... P106-HD
EuroTech 260E39 w/Cursor E0681E Eng. (10/99-on) Lube..... B7174-MPG Fuel/Water Separator (1907539) BF1217 Air..... PA2776 Air Dryer (Mann TB1374X)..... BA5374 + Trans..... PT8385 Steering..... P106-HD	EuroStar 260E43 w/Cursor E0681D (Cursor 10) Eng. (10/99-on) Lube (99445200)..... B7174-MPG Fuel/Water Separator (1907539) BF1217 473.9 mm Air..... PA2776 Air Dryer (Mann TB1374X)..... BA5374 + Trans. (5000807213)..... PT8385 Steering..... P106-HD	260.48 TurboStar Dual-Flow Lube (1907571)..... BD7168 Fuel..... BF988 + Air..... PA3754 Coolant..... BW5137
EuroStar 260E40 w/Cursor E0681 Eng. (08/00-on) Lube..... B7174-MPG Fuel/Water Separator (1907539) BF1217 473.9 mm Air..... PA2776 Air Dryer (Mann TB1374X)..... BA5374 + Trans..... PT8385 Steering..... P106-HD	EuroTech 260E43 w/Cursor E0681D Eng. (10/99-on) Lube (99445200)..... B7174-MPG Fuel/Water Separator (1907539) BF1217 473.9 mm Air..... PA2776 Air Dryer (Mann TB1374X)..... BA5374 + Trans. (5000807213)..... PT8385 Steering..... P106-HD	EuroStar 260E48 w/Cursor 13 Eng. (01/01-on) Lube (99445200)..... B7174-MPG Fuel/Water Separator (1907539) BF1217 Air Dryer (Mann TB1374X)..... BA5374 + Trans. (5000807213)..... PT8385 Steering..... P106-HD
EuroTech 260E40 w/E0681 Eng. (08/00-on) Lube..... B7174-MPG Fuel/Water Separator (1907539) BF1217 473.9 mm Air..... PA2776 Air Dryer (Mann TB1374X)..... BA5374 + Trans..... PT8385 Steering..... P106-HD	EuroStar 260E43 w/Cursor E0681D Eng. (10/99-on) Lube (99445200)..... B7174-MPG Fuel/Water Separator (1907539) BF1217 473.9 mm Air..... PA2776 Air Dryer (Mann TB1374X)..... BA5374 + Trans. (5000807213)..... PT8385 Steering..... P106-HD	EuroStar 260E52 w/8280.42S.(TCA) Eng. (04/92-on) Dual-Flow Lube (1907571)..... BD7168 Fuel/Water Separator (1907539) BF1217 Fuel (1907640)..... BF7663 Air Dryer (Mann TB1374X)..... BA5374 + Coolant (1901776)..... BW5143 Steering (1902137)..... P106-HD
EuroStar 260E42 w/8210.42L.400 Eng. (04/92-on) Dual-Flow Lube..... BD325 Fuel/Water Separator (1907539) BF1217 Fuel..... BF7663 Air..... PA2776 Steering..... P106-HD	EuroTrakker 260E44 w/Cursor13 Eng. (01/01-11/04) Lube..... B7174-MPG Fuel/Water Separator (1907539) BF1217 465.9 mm O. Air (41272211)..... PA5364 461.2 mm I. Air (41214149)..... PA5365 Air Dryer (Mann TB1374X)..... BA5374 + Breather (500339085)..... BT9408 Trans..... PT8385 Steering..... P106-HD	EuroTech 260E52 w/8280.42 Eng. (04/92-on) Dual-Flow Lube (1907571)..... BD7168 Fuel/Water Separator (1907539) BF1217 Fuel (1907640)..... BF7663 Air Dryer (Mann TB1374X)..... BA5374 + Coolant (1901776)..... BW5143 Steering (1902137)..... P106-HD
EuroStar 260E42 w/8460.41 Eng. Dual-Flow Lube (1907584)..... BD325 Fuel/Water Separator (1907539) BF1217 Fuel (1907640)..... BF7663 Air (1904550)..... PA2776 Coolant (1901776)..... BW5143 Steering (1902137)..... P106-HD	EuroStar 260E44 w/Cursor13 Eng. (01/01-11/04) Lube..... B7174-MPG Fuel/Water Separator (1907539) BF1217 465.9 mm O. Air (41272211)..... PA5364 461.2 mm I. Air (41214149)..... PA5365 Air Dryer (Mann TB1374X)..... BA5374 + Breather (500339085)..... BT9408 Trans..... PT8385 Steering..... P106-HD	EuroTech 260E52 w/8280.42 Eng. (04/92-on) Dual-Flow Lube (1907571)..... BD7168 Fuel/Water Separator (1907539) BF1217 Fuel (1907640)..... BF7663 Air Dryer (Mann TB1374X)..... BA5374 + Coolant (1901776)..... BW5143 Steering (1902137)..... P106-HD
EuroTech 260E42 w/8460.41 Eng. Dual-Flow Lube (1907584)..... BD325 Fuel/Water Separator (1907539) BF1217 Fuel (1907640)..... BF7663 Air (1904550)..... PA2776 Coolant (1901776)..... BW5143 Steering (1902137)..... P106-HD	EuroStar 260E46 w/Cursor 13 (Euro2) Eng. (03/01-on) Lube (99445200)..... B7174-MPG Fuel/Water Separator..... BF1217 Air Dryer (Mann TB1374X)..... BA5374 + Trans. (5000807213)..... PT8385 Steering..... P106-HD	EuroTech 260 E 52 w/8280.42S.350 Eng. (04/92-06/02) Dual-Flow Lube (1905704)..... BD7168 Fuel/Water Separator (1907539) BF1217 Fuel (1904640)..... BF7663 Air Dryer (1907612)..... BA5374 + Steering (1902137)..... P106-HD
EuroStar 260E42 w/8460.41 Eng. Dual-Flow Lube (1907584)..... BD325 Fuel/Water Separator (1907539) BF1217 Fuel (1907640)..... BF7663 Air (1904550)..... PA2776 Coolant (1901776)..... BW5143 Steering (1902137)..... P106-HD	EuroStar 260E46 w/Cursor 13 (Euro2) Eng. (03/01-on) Lube (99445200)..... B7174-MPG Fuel/Water Separator..... BF1217 Air Dryer (Mann TB1374X)..... BA5374 + Trans. (5000807213)..... PT8385 Steering..... P106-HD	260, 260T w/V85S Eng. Can-Type Fuel (74651986)..... BF825 + Opt. Fuel/Water Separator..... BF1221 + Fuel Spin-on..... BF988 + Steering..... PT691
EuroStar 260E42 w/8460.41 Eng. Dual-Flow Lube (1907584)..... BD325 Fuel/Water Separator (1907539) BF1217 Fuel (1907640)..... BF7663 Air (1904550)..... PA2776 Coolant (1901776)..... BW5143 Steering (1902137)..... P106-HD	EuroStar 260E46 w/Cursor 13 (Euro2) Eng. (03/01-on) Lube (99445200)..... B7174-MPG Fuel/Water Separator..... BF1217 Air Dryer (Mann TB1374X)..... BA5374 + Trans. (5000807213)..... PT8385 Steering..... P106-HD	EuroCargo 260E23T w/8060.45S Eng. (12/91-05/01) Dual-Flow Lube (1903715)..... BD325 Fuel (1907640)..... BF7663 Fuel/Water Separator (1908547) BF1217

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IVECO Trucks (cont'd)	IVECO Trucks (cont'd)	IVECO Trucks (cont'd)
EuroCargo 260E23T w/8060.45S Eng. (12/91-05/01) (Cont'd)	Stralis Active Day AD260S31Y/P w/Cursor 8-310 Eng. (06/03-on)	Stralis Active Day AD260S35Y/PS w/Cursor 8-352 Eng. (06/03-on) (Cont'd)
Air (1907533)..... PA3760	Lube..... B7174-MPG	Fuel/Water Separator
Air Dryer (Mann TB1374X)..... BA5374 +	Fuel/Water Separator	(6/03-12/03) (1907539)..... BF1217
Steering (1902137)..... P106-HD	(6/03-12/03) (1907539)..... BF1217	Fuel (6/03-9/04)..... BF7696
260D26 w/8210 Eng.	Fuel (6/03-9/04)..... BF7696	Fuel/Water Separator
Lube..... BT349	Fuel/Water Separator	(1/2004-on)..... BF1365
Fuel (1909103)..... BF783	Air (6/03-9/04)..... PA2776	Air (6/03-9/04)..... PA2776
381.0 mm O. Air (2165054)..... PA2474	Radial Seal Air (10/04-on)	(41272124)..... RS5356
379.4 mm I. Air (2243946)..... PA2836	Cab Air (w/o Carbon)	(504024890)..... PA5336
496.9 mm O. Air (2165059)..... PA2475	Air Dryer (Mann TB1374X)..... BA5374 +	Breather (06/03-09/04)
473.1 mm I. Air..... PA2814	Breather (06/03-09/04)	(500339085)..... BT9408
EuroCargo 260E27T w/8360.46.417TCA Eng. (09/91-12/00)	Trans. (5000807213)..... PT8385	Trans. (5000807213)..... PT8385
Dual-Flow Lube (1903715)..... BD325	Steering..... P106-HD	Steering..... P106-HD
Fuel (1907640)..... BF7663	Stralis Active Day AD260S31Y/PS w/Cursor 8-310 Eng. (06/03-on)	Stralis Active Day AD260S40Y/P w/Cursor 10-400 Eng. (06/03-09/04)
Fuel/Water Separator (1908547)..... BF1217	Lube..... B7174-MPG	Lube (99445200)..... B7174-MPG
Air (1907533)..... PA3760	Fuel/Water Separator	Fuel/Water Separator
Air Dryer (Mann TB1374X)..... BA5374 +	(6/03-12/03) (1907539)..... BF1217	(6/03-12/03) (1907539)..... BF1217
Coolant (1901776)..... BW5143	Fuel (6/03-9/04)..... BF7696	Cab Air (w/o Carbon)
Steering (1902137)..... P106-HD	Fuel/Water Separator	(504024890)..... PA5336
Stralis Active Day AD260S27Y/P w/Cursor 8-273+ Eng. (06/03-on)	(1/2004-on)..... BF1365	Air Dryer (Mann TB1374X)..... BA5374 +
Lube..... B7174-MPG	Air (6/03-9/04)..... PA2776	Breather (06/03-09/04)
Fuel/Water Separator	Radial Seal Air (10/04-on)	(500339085)..... BT9408
(6/03-12/03) (1907539)..... BF1217	(41272124)..... RS5356	Trans. (5000807213)..... PT8385
Fuel (6/03-9/04)..... BF7696	Cab Air (w/o Carbon)	Steering..... P106-HD
Fuel/Water Separator	(504024890)..... PA5336	Stralis Active Day AD260S40Y/P w/Cursor 10 Eng. (01/04-on)
(1/2004-on)..... BF1365	Air Dryer (Mann TB1374X)..... BA5374 +	Lube..... B7174-MPG
Air (6/03-9/04)..... PA2776	Breather (06/03-09/04)	Fuel/Water Separator (2992662)..... BF1365
Radial Seal Air (10/04-on)	(500339085)..... BT9408	Radial Seal Air (10/04-on)
(41272124)..... RS5356	Trans. (5000807213)..... PT8385	(41272124)..... RS5356
Cab Air (w/o Carbon)	Steering..... P106-HD	Cab Air (w/o Carbon)
(504024890)..... PA5336	Stralis Active Day AD260S35Y/P w/Cursor 8-352 Eng. (06/03-on)	(504024890)..... PA5336
Air Dryer (Mann TB1374X)..... BA5374 +	Lube..... B7174-MPG	Air Dryer (Mann TB1374X)..... BA5374 +
Breather (06/03-09/04)	Fuel/Water Separator	Trans..... PT8385
(500339085)..... BT9408	(6/03-12/03) (1907539)..... BF1217	Steering..... P106-HD
Trans. (5000807213)..... PT8385	Fuel (6/03-9/04)..... BF7696	Stralis Active Day AD260S40Y/PS w/Cursor 10-400 Eng. (06/03-09/04)
Steering..... P106-HD	Fuel/Water Separator	Lube (99445200)..... B7174-MPG
Stralis Active Day AD260S27Y/PS w/Cursor 8-273+ Eng. (06/03-on)	(1/2004-on)..... BF1365	Fuel/Water Separator
Lube..... B7174-MPG	Air (6/03-9/04)..... PA2776	(6/03-12/03) (1907539)..... BF1217
Fuel/Water Separator	Radial Seal Air (10/04-on)	Cab Air (w/o Carbon)
(6/03-12/03) (1907539)..... BF1217	(41272124)..... RS5356	(504024890)..... PA5336
Fuel (6/03-9/04)..... BF7696	Cab Air (w/o Carbon)	Air Dryer (Mann TB1374X)..... BA5374 +
Fuel/Water Separator	(504024890)..... PA5336	Breather (06/03-09/04)
(1/2004-on)..... BF1365	Air Dryer (Mann TB1374X)..... BA5374 +	(500339085)..... BT9408
Air (6/03-9/04)..... PA2776	Breather (06/03-09/04)	Trans. (5000807213)..... PT8385
Radial Seal Air (10/04-on)	(500339085)..... BT9408	Steering..... P106-HD
(41272124)..... RS5356	Trans. (5000807213)..... PT8385	Stralis Active Day AD260S40Y/PS w/Cursor 10-400 Eng. (01/04-on)
Cab Air (w/o Carbon)	Steering..... P106-HD	Lube..... B7174-MPG
(504024890)..... PA5336	Stralis Active Day AD260S35Y/PS w/Cursor 8-352 Eng. (06/03-on)	Fuel/Water Separator (2992662)..... BF1365
Air Dryer (Mann TB1374X)..... BA5374 +	Lube..... B7174-MPG	Radial Seal Air (10/04-on)
Breather (06/03-09/04)	Stralis Active Day AD260S27Y/PS w/Cursor 8-273+ Eng. (06/03-on)	(41272124)..... RS5356
(500339085)..... BT9408	Lube..... B7174-MPG	
Trans. (5000807213)..... PT8385		
Steering..... P106-HD		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IVECO Trucks (cont'd)	IVECO Trucks (cont'd)	IVECO Trucks (cont'd)
Stralis Active Day AD260S40Y/PS w/Cursor 10-400 Eng. (01/04-on) (Cont'd) <b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Trans.</b> ..... <b>PT8385</b> <b>Steering</b> ..... <b>P106-HD</b>	Stralis Active Day AD260S43Y/PS w/Cursor 10-430 Eng. (06/03-09/04) <b>Lube</b> (99445200)..... <b>B7174-MPG</b> <b>Fuel/Water Separator</b> (6/03-12/03) (1907539)..... <b>BF1217</b> <b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Breather</b> (06/03-09/04) (500339085)..... <b>BT9408</b> <b>Trans.</b> (5000807213)..... <b>PT8385</b> <b>Steering</b> ..... <b>P106-HD</b>	Stralis 260S45 w/Cursor 10-450 Eng. (03/06-on) (Cont'd) <b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Breather</b> (500339085)..... <b>BT9408</b> <b>Trans.</b> ..... <b>PT8385</b> <b>Steering</b> ..... <b>P106-HD</b>
Stralis Active Space AS260S40Y/FPGV w/Cursor 10-400 Eng. (06/03-on) <b>Lube</b> ..... <b>B7174-MPG</b> <b>Fuel/Water Separator</b> (6/03-12/03) (1907539)..... <b>BF1217</b> <b>Fuel/Water Separator</b> (1/2004-on) (2992662)..... <b>BF1365</b> <b>Radial Seal Air</b> (10/04-on) (41272124)..... <b>RS5356</b> <b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Breather</b> (500339085)..... <b>BT9408</b> <b>Trans.</b> (5000807213)..... <b>PT8385</b> <b>Steering</b> ..... <b>P106-HD</b>	Stralis Active Day AD260S43Y/PS w/Cursor 10 Eng. (01/04-on) <b>Lube</b> ..... <b>B7174-MPG</b> <b>Fuel/Water Separator</b> (2992662)..... <b>BF1365</b> <b>Radial Seal Air</b> (10/04-on) (41272124)..... <b>RS5356</b> <b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Trans.</b> ..... <b>PT8385</b> <b>Steering</b> ..... <b>P106-HD</b>	Stralis 260S50 w/Cursor 10-500 Eng. (03/06-on) <b>Lube</b> ..... <b>B7174-MPG</b> <b>Lube</b> (2996416)..... <b>P7495</b> <b>Fuel/Water Separator</b> ..... <b>BF1365</b> <b>Radial Seal Air</b> (41272124)..... <b>RS5356</b> <b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Breather</b> (500339085)..... <b>BT9408</b> <b>Trans.</b> ..... <b>PT8385</b> <b>Steering</b> ..... <b>P106-HD</b>
Stralis 260S42 w/Cursor 10-420 Eng. (03/06-on) <b>Lube</b> ..... <b>B7174-MPG</b> <b>Lube</b> (2996416)..... <b>P7495</b> <b>Fuel/Water Separator</b> ..... <b>BF1365</b> <b>Radial Seal Air</b> (41272124)..... <b>RS5356</b> <b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Breather</b> (500339085)..... <b>BT9408</b> <b>Trans.</b> ..... <b>PT8385</b> <b>Steering</b> ..... <b>P106-HD</b>	Stralis Active Space AS260S43Y/FPGV w/Cursor 10-430 Eng. (06/03-on) <b>Lube</b> ..... <b>B7174-MPG</b> <b>Fuel/Water Separator</b> (6/03-12/03) (1907539)..... <b>BF1217</b> <b>Fuel/Water Separator</b> (1/2004-on) (2992662)..... <b>BF1365</b> <b>Radial Seal Air</b> (10/04-on) (41272124)..... <b>RS5356</b> <b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Breather</b> (500339085)..... <b>BT9408</b> <b>Trans.</b> (5000807213)..... <b>PT8385</b> <b>Steering</b> ..... <b>P106-HD</b>	Stralis 260S56 w/Cursor 10-560 Eng. (03/06-on) <b>Lube</b> ..... <b>B7174-MPG</b> <b>Lube</b> (2996416)..... <b>P7495</b> <b>Fuel/Water Separator</b> ..... <b>BF1365</b> <b>Radial Seal Air</b> (41272124)..... <b>RS5356</b> <b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Breather</b> (500339085)..... <b>BT9408</b> <b>Trans.</b> ..... <b>PT8385</b> <b>Steering</b> ..... <b>P106-HD</b>
Stralis Active Day AD260S43Y/P w/Cursor 10-430 Eng. (06/03-09/04) <b>Lube</b> (99445200)..... <b>B7174-MPG</b> <b>Fuel/Water Separator</b> (6/03-12/03) (1907539)..... <b>BF1217</b> <b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Breather</b> (06/03-09/04) (500339085)..... <b>BT9408</b> <b>Trans.</b> (5000807213)..... <b>PT8385</b> <b>Steering</b> ..... <b>P106-HD</b>	Stralis Active Space AS260S43Y/FPGV w/Cursor 10-430 Eng. (06/03-on) <b>Lube</b> ..... <b>B7174-MPG</b> <b>Fuel/Water Separator</b> (6/03-12/03) (1907539)..... <b>BF1217</b> <b>Fuel/Water Separator</b> (1/2004-on) (2992662)..... <b>BF1365</b> <b>Radial Seal Air</b> (10/04-on) (41272124)..... <b>RS5356</b> <b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Breather</b> (500339085)..... <b>BT9408</b> <b>Trans.</b> (5000807213)..... <b>PT8385</b> <b>Steering</b> ..... <b>P106-HD</b>	EuroStar 260F35 w/8280 Eng. <b>Lube</b> (4667339)..... <b>BT349</b> <b>Fuel</b> (1909103)..... <b>BF783</b> <b>381.0 mm O. Air</b> (1186389)..... <b>PA2474</b> <b>379.4 mm I. Air</b> ..... <b>PA2836</b> <b>496.9 mm O. Air</b> (74980649)..... <b>PA2475</b> <b>473.1 mm I. Air</b> ..... <b>PA2814</b> <b>Coolant</b> (4734562)..... <b>BW5137</b>
Stralis Active Day AD260S43Y/P w/Cursor 10 Eng. (01/04-on) <b>Lube</b> ..... <b>B7174-MPG</b> <b>Fuel/Water Separator</b> (2992662)..... <b>BF1365</b> <b>Radial Seal Air</b> (10/04-on) (41272124)..... <b>RS5356</b> <b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Trans.</b> ..... <b>PT8385</b> <b>Steering</b> ..... <b>P106-HD</b>	Stralis Active Space AS260S43Y/FSGV w/Cursor 10-430 Eng. (06/03-on) <b>Lube</b> ..... <b>B7174-MPG</b> <b>Fuel/Water Separator</b> (6/03-12/03) (1907539)..... <b>BF1217</b> <b>Fuel/Water Separator</b> (1/2004-on) (2992662)..... <b>BF1365</b> <b>Radial Seal Air</b> (10/04-on) (41272124)..... <b>RS5356</b> <b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Breather</b> (500339085)..... <b>BT9408</b> <b>Trans.</b> (5000807213)..... <b>PT8385</b> <b>Steering</b> ..... <b>P106-HD</b>	EuroStar 260PAC26 w/8210.02 Turbo Eng. <b>Lube</b> (1901604)..... <b>BT349</b> <b>Fuel</b> (1909103)..... <b>BF783</b> <b>O. Air</b> ..... <b>PA2475</b> <b>I. Air</b> (2394637)..... <b>PA2814</b>
Stralis Active Day AD260S43Y/P w/Cursor 10 Eng. (01/04-on) <b>Lube</b> ..... <b>B7174-MPG</b> <b>Fuel/Water Separator</b> (2992662)..... <b>BF1365</b> <b>Radial Seal Air</b> (10/04-on) (41272124)..... <b>RS5356</b> <b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Trans.</b> ..... <b>PT8385</b> <b>Steering</b> ..... <b>P106-HD</b>	Stralis 260S45 w/Cursor 10-450 Eng. (03/06-on) <b>Lube</b> ..... <b>B7174-MPG</b> <b>Lube</b> (2996416)..... <b>P7495</b> <b>Fuel/Water Separator</b> ..... <b>BF1365</b> <b>Radial Seal Air</b> (41272124)..... <b>RS5356</b>	EuroStar 260PAC26 w/8280 Eng. <b>Lube</b> (4667339)..... <b>BT349</b> <b>Fuel</b> (1909103)..... <b>BF783</b> <b>381.0 mm O. Air</b> (1186389)..... <b>PA2474</b> <b>379.4 mm I. Air</b> ..... <b>PA2836</b> <b>496.9 mm O. Air</b> (74980649)..... <b>PA2475</b> <b>473.1 mm I. Air</b> ..... <b>PA2814</b> <b>Coolant</b> (4734562)..... <b>BW5137</b>
		260PAC26, 260PAT26 w/8210.02 Eng. <b>Lube</b> (4667339)..... <b>BT349</b> <b>Fuel</b> ..... <b>BF783</b> <b>381.0 mm O. Air</b> (1186389)..... <b>PA2474</b> <b>379.4 mm I. Air</b> (42480759)..... <b>PA2836</b> <b>374.7 mm O. Air</b> ..... <b>PA2405</b> <b>473.1 mm I. Air</b> (2394637)..... <b>PA2814</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IVECO Trucks (cont'd)	IVECO Trucks (cont'd)	IVECO Trucks (cont'd)
260PAC26, 260PAT26 w/8210.02 Eng. (Cont'd) Coolant (4734562)..... <b>BW5137</b>	Stralis (Active day) 270 w/C78 ENT GAS Eng. (09/10-on) (Cont'd) Steering (100.8 mm) (1902137)... <b>P106-HD</b> Steering (115.8 mm) (1267900)... <b>PT691</b>	EuroCargo 280E23T w/8060.45S.6700 Eng. (12/91-05/01) (Cont'd) Steering..... <b>P106-HD</b>
EuroMover 270 w/Cursor 8 Eng. (04/05-on) Lube..... <b>B7174-MPG</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel..... <b>BF7696</b> Radial Seal Air (41272124)..... <b>RS5356</b> Cab Air (w/o Carbon) (504024890)..... <b>PA5336</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Breather (500339085)..... <b>BT9408</b> Steering..... <b>P106-HD</b>	Stralis (Active time) 270 w/Cursor 8-270 Eng. (06/03-on) Lube (99445200)..... <b>B7174-MPG</b> Fuel/Water Separator (504086268)..... <b>BF1292-O</b> Fuel/Water Separator (To 12/03) (1907539)..... <b>BF1217</b> Fuel/Water Separator (01/04-on) (2992662)..... <b>BF1365</b> Fuel (1907460)..... <b>BF7696</b> I. Air (To 09/04) (1905620)..... <b>PA3494</b> Radial Seal Air (10/04-on) (41272124)..... <b>RS5356</b> Cab Air (w/o Carbon) (504024890)..... <b>PA5336</b> Air Dryer (1907612)..... <b>BA5374 +</b> Breather (500339085)..... <b>BT9408</b> Steering (100.8 mm) (1902137)... <b>P106-HD</b> Steering (115.8 mm) (1267900)... <b>PT691</b>	290D15, 290D16, 290D19, 290D20, 290D22 w/Deutz F10L413, F12L413 Eng. Lube (1160025)..... <b>B236 +</b> Opt. Fuel/Water Separator..... <b>BF1221 +</b> P. Fuel Ele. (1168407)..... <b>F950-F</b> S. Fuel Ele. (1168398)..... <b>PF950</b> 136.5 mm Fuel Spin-on..... <b>BF900</b> 123.0 mm Some Fuel Spin-on (1160243)..... <b>BF988 +</b> Single Air (2168629)..... <b>PA2891</b> O. Air (2165049)..... <b>PA2405</b> I. Air..... <b>PA2835</b>
Stralis 270 w/Cursor 8 Eng. (06/03-09/04) Lube..... <b>B7174-MPG</b> Fuel/Water Separator (6/03-12/03) (1907539)..... <b>BF1217</b> Fuel..... <b>BF7696</b> Air..... <b>PA2776</b> Cab Air (504024890)..... <b>PA5336</b> Trans. (5000807213)..... <b>PT8385</b> Steering..... <b>P106-HD</b>	Trakker 270 w/Cursor 8 Eng. (09/04-on) Lube..... <b>B7174-MPG</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel..... <b>BF7696</b> Radial Seal Air (41272124)..... <b>RS5356</b> Air (Metal Hsg.)..... <b>PA3606</b> Cab Air (w/o Carbon) (504024890)..... <b>PA5336</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Breather (500339085)..... <b>BT9408</b> Steering..... <b>P106-HD</b>	Stralis (Active day) 300 w/Cursor 8-300 Eng. (06/03-on) Lube (99445200)..... <b>B7174-MPG</b> Fuel/Water Separator (504086268)..... <b>BF1292-O</b> Fuel/Water Separator (To 12/03) (1907539)..... <b>BF1217</b> Fuel/Water Separator (01/04-on) (2992662)..... <b>BF1365</b> Fuel (1907460)..... <b>BF7696</b> O. Air (To 09/04) (1904550)..... <b>PA2776</b> I. Air (To 09/04) (1905620)..... <b>PA3494</b> Single Radial Seal Air (10/04-on) (41272124)..... <b>RS5356</b> Cab Air (w/o Carbon) (504024890)..... <b>PA5336</b> Air Dryer (1907612)..... <b>BA5374 +</b> Breather (500339085)..... <b>BT9408</b> Steering (100.8 mm) (1902137)... <b>P106-HD</b> Steering (115.8 mm) (1267900)... <b>PT691</b> Urea (denoxtronic 1) (42562233).. <b>PE5270</b> Urea (denoxtronic 2) (42555073).. <b>PE5271</b>
Stralis 270 w/Cursor 8 Eng. (10/04-on) Lube..... <b>B7174-MPG</b> Fuel..... <b>BF7927</b> Fuel/Water Separator..... <b>BF1365</b> Radial Seal Air (41272124)..... <b>RS5356</b> Cab Air (504024890)..... <b>PA5336</b> Air Dryer..... <b>BA5374 +</b> Trans. (5000807213)..... <b>PT8385</b> Steering..... <b>P106-HD</b>	270D15.5, 270D16, 270D22, 270D26 w/Deutz F10L413, F12L413 Eng. Lube (1160025)..... <b>B236 +</b> Opt. Fuel/Water Separator..... <b>BF1221 +</b> P. Fuel Ele. (1168407)..... <b>F950-F</b> S. Fuel Ele. (1168398)..... <b>PF950</b> 136.5 mm Fuel Spin-on..... <b>BF900</b> 123.0 mm Some Fuel Spin-on (1160243)..... <b>BF988 +</b> Single Air (2168629)..... <b>PA2891</b> O. Air (2165049)..... <b>PA2405</b> I. Air..... <b>PA2835</b>	Stralis (Active time) 300 w/Cursor 8-300 Eng. (06/03-on) Lube (99445200)..... <b>B7174-MPG</b> Fuel/Water Separator (504086268)..... <b>BF1292-O</b> Fuel/Water Separator (To 12/03) (1907539)..... <b>BF1217</b> Fuel/Water Separator (01/04-on) (2992662)..... <b>BF1365</b> Fuel (1907460)..... <b>BF7696</b> I. Air (To 09/04) (1905620)..... <b>PA3494</b> Radial Seal Air (10/04-on) (41272124)..... <b>RS5356</b> Cab Air (w/o Carbon) (504024890)..... <b>PA5336</b> Air Dryer (1907612)..... <b>BA5374 +</b> Breather (500339085)..... <b>BT9408</b> Steering (100.8 mm) (1902137)... <b>P106-HD</b> Steering (115.8 mm) (1267900)... <b>PT691</b> Urea (denoxtronic 1) (42562233).. <b>PE5270</b> Urea (denoxtronic 2) (42555073).. <b>PE5271</b>
Stralis (Active day) 270 w/Cursor 8-270 Eng. (06/03-on) Lube (99445200)..... <b>B7174-MPG</b> Fuel/Water Separator (504086268)..... <b>BF1292-O</b> Fuel/Water Separator (To 12/03) (1907539)..... <b>BF1217</b> Fuel/Water Separator (01/04-on) (2992662)..... <b>BF1365</b> Fuel (1907460)..... <b>BF7696</b> O. Air (To 09/04) (1904550)..... <b>PA2776</b> I. Air (To 09/04) (1905620)..... <b>PA3494</b> Single Radial Seal Air (10/04-on) (41272124)..... <b>RS5356</b> Cab Air (w/o Carbon) (504024890)..... <b>PA5336</b> Air Dryer (1907612)..... <b>BA5374 +</b> Breather (500339085)..... <b>BT9408</b> Steering (100.8 mm) (1902137)... <b>P106-HD</b> Steering (115.8 mm) (1267900)... <b>PT691</b>	EuroCargo 280E23 w/8060TCA Eng. Dual-Flow Lube (1903715)..... <b>BD325</b> Fuel (4764693)..... <b>BF988 +</b> Air (1907533)..... <b>PA3760</b> Steering (1902137)..... <b>P106-HD</b>	
Stralis (Active day) 270 w/C78 ENT GAS Eng. (09/10-on) Lube (99445200)..... <b>B7174-MPG</b> Radial Seal Air (41272124)..... <b>RS5356</b> Cab Air (w/o Carbon) (504024890)..... <b>PA5336</b> Air Dryer (1907612)..... <b>BA5374 +</b> Breather (500339085)..... <b>BT9408</b>	EuroCargo 280E23T w/8060.45S.6700 Eng. (12/91-05/01) Dual-Flow Lube..... <b>BD325</b> Fuel/Water Separator (1907539). <b>BF1217</b> Fuel..... <b>BF7663</b> Air..... <b>PA3760</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IVECO Trucks (cont'd)	IVECO Trucks (cont'd)	IVECO Trucks (cont'd)
300 w/CP3, CP3-42 Engs. Air..... PA1646-FN	Stralis (Active time) 310 w/Cursor 8-310 Eng. (06/03-on) Lube (99445200)..... B7174-MPG	320 w/CP3, CP3-42 Engs. Air..... PA1646-FN
300P, 300PC, 300PT, 300PTU w/8210.02 Eng. Lube (4667339)..... BT349	Fuel/Water Separator (504086268)..... BF1292-O	320D32 w/8280 Eng. Lube..... BT349
Fuel (1909103)..... BF783	Fuel/Water Separator (To 12/03) (1907539)..... BF1217	Fuel (1909103)..... BF783
Air..... PA1884 +	Fuel/Water Separator (01/04-on) (2992662)..... BF1365	O. Air (2165059)..... PA2475
EuroMover 310 w/Cursor 8 Eng. (04/05-on) Lube..... B7174-MPG	Fuel (1907460)..... BF7696	I. Air..... PA2814
Fuel/Water Separator (1907539)..... BF1217	I. Air (To 09/04) (1905620)..... PA3494	320M19, 320M22, 320M26 w/Deutz F10L413 Eng. Lube (1160025)..... B236 +
Fuel..... BF7696	Radial Seal Air (10/04-on) (41272124)..... RS5356	123.0 mm Fuel (1160243)..... BF988 +
Radial Seal Air (41272124)..... RS5356	Cab Air (w/o Carbon) (504024890)..... PA5336	136.5 mm Fuel (1164620)..... BF900
Cab Air (w/o Carbon) (504024890)..... PA5336	Air Dryer (1907612)..... BA5374 +	Opt. Fuel/Water Separator..... BF1221 +
Air Dryer (Mann TB1374X)..... BA5374 +	Breather (500339085)..... BT9408	O. Air (2165059)..... PA2475
Breather (500339085)..... BT9408	Steering (100.8 mm) (1902137)..... P106-HD	I. Air..... PA2814
Steering..... P106-HD	Steering (115.8 mm) (1267900)..... PT691	EuroCargo 320E27T w/8360.46.417TCA Eng. (10/91-04/01) Dual-Flow Lube (1903715)..... BD325
Stralis 310 w/Cursor 8 Eng. (06/03-09/04) Lube..... B7174-MPG	Urea (denoxtronic 1) (42562233)..... PE5270	Fuel (1907640)..... BF7663
Fuel/Water Separator (6/03-12/03) (1907539)..... BF1217	Urea (denoxtronic 2) (42555073)..... PE5271	Fuel/Water Separator (1908547)..... BF1217
Fuel..... BF7696	Trakker 310 w/Cursor 8 (Euro 4/5) Eng. (03/06-on) Lube..... B7174-MPG	Air (1907553)..... PA3760
Air..... PA2776	Lube (2996416)..... P7495	Air Dryer (Mann TB1374X)..... BA5374 +
Cab Air (504024890)..... PA5336	Fuel/Water Separator (1907539)..... BF1217	Coolant (1901776)..... BW5143
Air Dryer..... BA5374 +	Fuel..... BF7696	Steering (1902137)..... P106-HD
Trans. (5000807213)..... PT8385	Radial Seal Air (41272124)..... RS5356	EuroCargo ML320E27T/P w/8060TCA Eng. (12/91-on) Dual-Flow Lube..... BD325
Steering..... P106-HD	Air (Metal Hsg.)..... PA3606	Fuel/Water Separator (1907539)..... BF1217
Stralis 310 w/Cursor 8 Eng. (09/04-on) Lube..... B7174-MPG	Cab Air (w/o Carbon) (504024890)..... PA5336	Fuel..... BF7663
Fuel..... BF7927	Air Dryer (Mann TB1374X)..... BA5374 +	Air..... PA3760
Fuel/Water Separator..... BF1365	Breather (500339085)..... BT9408	Steering..... P106-HD
Radial Seal Air (41272124)..... RS5356	Steering..... P106-HD	EuroCargo 320E28 w/Cummins Tector Eng. (09/00-09/03) Lube..... BT7237
Cab Air (504024890)..... PA5336	Trakker 310 w/Cursor 8 Eng. (09/04-on) Lube..... B7174-MPG	Fuel/Water Separator (1907539)..... BF1217
Air Dryer..... BA5374 +	Fuel/Water Separator (1907539)..... BF1217	Fuel..... BF7813
Trans. (5000807213)..... PT8385	Fuel..... BF7696	Radial Seal Air..... RS4968
Steering..... P106-HD	Radial Seal Air (41272124)..... RS5356	Air (2992388)..... RS5535
Stralis (Active day) 310 w/Cursor 8-310 Eng. (06/03-on) Lube (99445200)..... B7174-MPG	Air (Metal Hsg.)..... PA3606	Air Dryer (Mann TB1374X)..... BA5374 +
Fuel/Water Separator (504086268)..... BF1292-O	Cab Air (w/o Carbon) (504024890)..... PA5336	Hyd. Breather (2992447)..... P7336 KIT
Fuel/Water Separator (To 12/03) (1907539)..... BF1217	Air Dryer (Mann TB1374X)..... BA5374 +	320.31 w/Deutz F10L413 Eng. Lube (1174421)..... B236 +
Fuel/Water Separator (01/04-on) (2992662)..... BF1365	Breather (500339085)..... BT9408	Fuel (1174423)..... BF7931
Fuel (1907460)..... BF7696	Steering..... P106-HD	Opt. Fuel/Water Separator..... BF1221 +
O. Air (To 09/04) (1904550)..... PA2776	310D15.5, 310D16, 310D22, 310D26, 310D32 w/Deutz F10L413, F12L413 Engs. Lube (1160025)..... B236 +	Single Air (2168629)..... PA2891
I. Air (To 09/04) (1905620)..... PA3494	Opt. Fuel/Water Separator..... BF1221 +	O. Air (2165049)..... PA2405
Single Radial Seal Air (10/04-on) (41272124)..... RS5356	P. Fuel Ele. (1168407)..... F950-F	I. Air..... PA2835
Cab Air (w/o Carbon) (504024890)..... PA5336	S. Fuel Ele. (1168398)..... PF950	329 w/CP3, CP3-42 Engs. Air..... PA1646-FN
Air Dryer (1907612)..... BA5374 +	136.5 mm Fuel Spin-on..... BF900	Stralis (Active day) 330 w/Cursor 8-330 Eng. (03/06-on) Lube (99445200)..... B7174-MPG
Breather (500339085)..... BT9408	123.0 mm Some Fuel Spin-on (1160243)..... BF988 +	Fuel/Water Separator (504086268)..... BF1292-O
Steering (100.8 mm) (1902137)..... P106-HD	O. Air..... PA2405	Fuel/Water Separator (2992662)..... BF1365
Steering (115.8 mm) (1267900)..... PT691	I. Air..... PA2835	Fuel (1907460)..... BF7696
Urea (denoxtronic 1) (42562233)..... PE5270	Single Air (2168629)..... PA2891	Radial Seal Air (41272124)..... RS5356
Urea (denoxtronic 2) (42555073)..... PE5271		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).




IVECO Trucks (cont'd)	IVECO Trucks (cont'd)	IVECO Trucks (cont'd)
Stralis (Active day) 330 w/Cursor 8-330 Eng. (03/06-on) (Cont'd) Cab Air (w/o Carbon) (504024890)..... <b>PA5336</b> Air Dryer (1907612)..... <b>BA5374</b> + Breather (500339085)..... <b>BT9408</b> Steering (100.8 mm) (1902137)... <b>P106-HD</b> Steering (115.8 mm) (1267900)... <b>PT691</b> Urea (denoxtronic 1) (42562233)... <b>PE5270</b> Urea (denoxtronic 2) (42555073).. <b>PE5271</b>	330.26H, 330.26HT, 330.26HW, 330.26N Lube (1907570)..... <b>BT349</b> Fuel Ele. (1902096)..... <b>PF312</b> Fuel Spin-on (1901605)..... <b>BF783</b> Air (1901925)..... <b>PA2475</b> Coolant (1901776)..... <b>BW5143</b> 330.30H, 330.30HT w/8210.22 Eng. F-F Lube (4667755)..... <b>BT349</b> Dual-Flow Lube (1902102)..... <b>BD325</b> Fuel (1901605)..... <b>BF783</b> 374.7 mm O. Air (2165049)..... <b>PA2405</b> 371.5 mm I. Air (2241329)..... <b>PA2835</b> 496.9 mm O. Air..... <b>PA2475</b> 473.1 mm I. Air (42481020)..... <b>PA2814</b> 419.1 mm Some Air (9933276)... <b>PA1885</b> + Coolant (1901776)..... <b>BW5143</b> 330.30H, 330.30HT, 330.30HW Lube (1907570)..... <b>BT349</b> Fuel Ele. (1902096)..... <b>PF312</b> Fuel Spin-on (1901605)..... <b>BF783</b> Air (1904550)..... <b>PA2776</b> 330.30N Lube (1907570)..... <b>BT349</b> Fuel (1901605)..... <b>BF783</b> Air (1902077)..... <b>PA2405</b> 330.32 w/Deutz F10L413F Eng. F-F Lube..... <b>B7031</b> Fuel (1174423)..... <b>BF7931</b> 473.9 mm O. Air (Standard Media) (1902129)..... <b>PA2776</b> 473.9 mm O. Air (Flame Retardant Media) (2996154)..... <b>PA30235</b> 471.5 mm I. Air..... <b>PA3494</b> 295.3 mm Some Air..... <b>PA2891</b> 496.9 mm O. Air..... <b>PA2475</b> 473.1 mm I. Air..... <b>PA2814</b> 330.35 w/8280.02 Eng. Lube (1901604)..... <b>BT349</b> Fuel (1909103)..... <b>BF783</b> O. Air..... <b>PA2475</b> I. Air (42481020)..... <b>PA2814</b> O. Air (Standard Media) (1902129)..... <b>PA2776</b> O. Air (Flame Retardant Media) (2996154)..... <b>PA30235</b> Coolant (1901776)..... <b>BW5143</b> 330.35H, 330.35HT, 330.35HW3 Lube (1907570)..... <b>BT349</b> Fuel Ele. (1902096)..... <b>PF312</b> Fuel Spin-on (1901605)..... <b>BF783</b> Air (1901925)..... <b>PA2475</b> Coolant (1901776)..... <b>BW5143</b> 330.36 w/8220.22 Eng. Lube (1174421)..... <b>B236</b> + Fuel (1174423)..... <b>BF7931</b> Opt. Fuel/Water Separator..... <b>BF1221</b> + 473.9 mm O. Air..... <b>PA2776</b> 471.5 mm I. Air..... <b>PA3494</b>	330.36 w/8220.22 Eng. (Cont'd) 419.1 mm Some Std. Air (1901780)..... <b>PA1886</b> + 419.1 mm Some XP Air (1901780)..... <b>PA1886XP</b> 330.36, 330.36H, 330.36HT, 330.36HW Dual-Flow Lube (1903715)..... <b>BD325</b> Fuel (1901605)..... <b>BF783</b> Air (1904550)..... <b>PA2776</b> 330.40 w/Deutz BF10L413 Eng. Lube (1174421)..... <b>B236</b> + Fuel (1174422)..... <b>BF900</b> 330.42 TurboStar w/8280.22 Eng. Std. Air (1901780)..... <b>PA1886</b> + XP Air (1901780)..... <b>PA1886XP</b> EuroTrakker 330E34 Dual-Flow Lube..... <b>BD325</b> Fuel (1907640)..... <b>BF7663</b> Air (1904550)..... <b>PA2776</b> Coolant..... <b>BW5137</b> 330F35, 330F35P/T, 330R w/8280 Eng. Lube (4667339)..... <b>BT349</b> Fuel (1909103)..... <b>BF783</b> 381.0 mm O. Air (1186389)..... <b>PA2474</b> 379.4 mm I. Air..... <b>PA2836</b> 496.9 mm O. Air (74980649)..... <b>PA2475</b> 473.1 mm I. Air..... <b>PA2814</b> 330PAC26 Lube (1907570)..... <b>BT349</b> Fuel Ele. (1902096)..... <b>PF312</b> Fuel Spin-on (1901605)..... <b>BF783</b> Air (1901925)..... <b>PA2475</b> 343GT Lube (78813556)..... <b>P20-HD</b> + Fuel (1909103)..... <b>BF783</b> 340D16, 340D19, 340D22 w/Deutz F10L413, F12L413 Engs. Lube (1160025)..... <b>B236</b> + Opt. Fuel/Water Separator..... <b>BF1221</b> + P. Fuel Ele. (1168407)..... <b>F950-F</b> S. Fuel Ele. (1168398)..... <b>PF950</b> 123.0 mm Some Fuel Spin-on (1160243)..... <b>BF988</b> + 136.5 mm Fuel Spin-on (1164620)..... <b>BF900</b> O. Air (2165049)..... <b>PA2405</b> I. Air..... <b>PA2835</b> Single Air (2168629)..... <b>PA2891</b> EuroTrakker 340E34 w/8210.42 Eng. Dual-Flow Lube (1907584)..... <b>BD325</b> Fuel (1907640)..... <b>BF7663</b> Fuel/Water Separator (1908547)..... <b>BF1217</b> Air..... <b>PA2776</b> Coolant (1901776)..... <b>BW5143</b> Steering..... <b>P106-HD</b>
Stralis (Active time) 330 w/Cursor 8-330 Eng. (03/06-on) Lube (99445200)..... <b>B7174-MPG</b> Fuel/Water Separator (504086268)..... <b>BF1292-O</b> Fuel/Water Separator (2992662)..... <b>BF1365</b> Fuel (1907460)..... <b>BF7696</b> Radial Seal Air (41272124)..... <b>RS5356</b> Cab Air (w/o Carbon) (504024890)..... <b>PA5336</b> Air Dryer (1907612)..... <b>BA5374</b> + Breather (500339085)..... <b>BT9408</b> Steering (100.8 mm) (1902137)... <b>P106-HD</b> Steering (115.8 mm) (1267900)... <b>PT691</b> Urea (denoxtronic 1) (42562233)... <b>PE5270</b> Urea (denoxtronic 2) (42555073).. <b>PE5271</b>	Trakker 330 w/Cursor 8 (Euro 4/5) Eng. (03/06-on) Lube..... <b>B7174-MPG</b> Lube (2996416)..... <b>P7495</b> Fuel/Water Separator (1907539)..... <b>BF1217</b> Fuel..... <b>BF7696</b> Radial Seal Air (41272124)..... <b>RS5356</b> Air (Metal Hsg.)..... <b>PA3606</b> Cab Air (w/o Carbon) (504024890)..... <b>PA5336</b> Air Dryer (Mann TB1374X)..... <b>BA5374</b> + Breather (500339085)..... <b>BT9408</b> Steering..... <b>P106-HD</b>	330.25 w/Deutz F8L413F Eng. Lube..... <b>B7031</b> 136.5 mm Fuel (1174422)..... <b>BF900</b> 123.0 mm Fuel (1174423)..... <b>BF7931</b> Opt. Fuel/Water Separator..... <b>BF1221</b> + O. Air..... <b>PA2475</b> I. Air..... <b>PA2814</b>
330.26 w/8210.02 Eng. Lube (4667339)..... <b>BT349</b> Fuel (1909103)..... <b>BF783</b> 381.0 mm O. Air (1186389)..... <b>PA2474</b> 379.4 mm I. Air (42480759)..... <b>PA2836</b> 374.7 mm O. Air..... <b>PA2405</b> 473.1 mm I. Air (2394637)..... <b>PA2814</b> 496.9 mm O. Air (2165059)..... <b>PA2475</b> 473.1 mm I. Air..... <b>PA2814</b> Coolant (4734562)..... <b>BW5137</b>		

+ See Product Guide for Variations of This Number. Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IVECO Trucks (cont'd)	IVECO Trucks (cont'd)	IVECO Trucks (cont'd)
EuroTrakker 340 E 34 w/8460.41K Eng. (01/94-03/99)	EuroTrakker 340 E 42 w/8210.42 Eng. (06/98-05/01) (Cont'd)	Stralis (Active time) 350 w/Cursor 8-350 Eng. (06/03-on)
Dual-Flow Lube (1903715)..... BD325	Air Dryer (1907612)..... BA5374 +	Lube (99445200)..... B7174-MPG
Fuel/Water Separator (1907539). BF1217	Coolant (1901776)..... BW5143	Fuel/Water Separator (504086268)..... BF1292-O
Fuel (1904640)..... BF7663	Steering (1902137)..... P106-HD	Fuel/Water Separator (To 12/03) (1907539)..... BF1217
O. Air (1904550)..... PA2776	EuroTrakker 340E44 w/Cursor13 Eng. (01/01-11/04)	Fuel/Water Separator (01/04-on) (2992662)..... BF1365
I. Air (1905620)..... PA3494	Lube..... B7174-MPG	Fuel (1907460)..... BF7696
Single Air (2991793)..... PA3606	Fuel/Water Separator (1907539). BF1217	I. Air (To 09/04) (1905620)..... PA3494
Air Dryer (1907612)..... BA5374 +	465.9 mm O. Air (41272211)..... PA5364	Radial Seal Air (10/04-on) (41272124)..... RS5356
Coolant (1901776)..... BW5143	461.2 mm I. Air (41214149)..... PA5365	Cab Air (w/o Carbon) (504024890)..... PA5336
Steering (1902137)..... P106-HD	Air Dryer (Mann TB1374X)..... BA5374 +	Air Dryer (1907612)..... BA5374 +
EuroTrakker 340 E 35 w/Cursor E0681A Eng. (02/99-11/04)	Breather (500339085)..... BT9408	Breather (500339085)..... BT9408
Lube (99445200)..... B7174-MPG	Trans..... PT8385	Steering (100.8 mm) (1902137).... P106-HD
Fuel/Water Separator (1907539). BF1217	Steering..... P106-HD	Steering (115.8 mm) (1267900).... PT691
Fuel (1907460)..... BF7696	Z340T	Trakker 350 w/Cursor 8 Eng. (09/04-on)
O. Air (1904550)..... PA2776	Dual-Flow Lube (1902076)..... BD232	Lube..... B7174-MPG
I. Air (1905620)..... PA3494	Fuel..... [2] BF988 +	Fuel/Water Separator (1907539). BF1217
Air Dryer (1907612)..... BA5374 +	Air (1902077)..... PA2405	Fuel..... BF7696
Breather (500339085)..... BT9408	Stralis 350 w/Cursor 8 Eng. (06/03-08/04)	Radial Seal Air (41272124)..... RS5356
Trans. (42491185)..... PT8385	Lube..... B7174-MPG	Air (Metal Hsg.)..... PA3606
Steering (1902137)..... P106-HD	Fuel/Water Separator (6/03-12/03) (1907539)..... BF1217	Cab Air (w/o Carbon) (504024890)..... PA5336
EuroTrakker 340E37 w/8210.42 Eng. (02/99-11/04)	Fuel..... BF7696	Air Dryer (Mann TB1374X)..... BA5374 +
Dual-Flow Lube (1907584)..... BD325	Air..... PA2776	Breather (500339085)..... BT9408
Fuel (1907640)..... BF7663	Cab Air (504024890)..... PA5336	Steering (115.8 mm) (1267900).... PT691
Fuel/Water Separator (1908547). BF1217	Air Dryer..... BA5374 +	Urea (denoxtronic 1) (42562233).. PE5270
Air..... PA2776	Trans. (5000807213)..... PT8385	Urea (denoxtronic 2) (42555073).. PE5271
Coolant (1901776)..... BW5143	Steering..... P106-HD	Stralis (Active day) 360 w/Cursor 8-360 Eng. (03/06-on)
Steering..... P106-HD	Stralis 350 w/Cursor 8 Eng. (09/04-on)	Lube (99445200)..... B7174-MPG
EuroTrakker 340 E 37 w/8210.42 K Eng. (03/95-05/01)	Lube..... B7174-MPG	Fuel/Water Separator (504086268)..... BF1292-O
Dual-Flow Lube (1903715)..... BD325	Fuel..... BF7927	Fuel/Water Separator (2992662). BF1365
Fuel/Water Separator (1907539). BF1217	Radial Seal Air (41272124)..... RS5356	Fuel (1907460)..... BF7696
Fuel (1904640)..... BF7663	Cab Air (504024890)..... PA5336	Radial Seal Air (41272124)..... RS5356
O. Air (1904550)..... PA2776	Air Dryer..... BA5374 +	Cab Air (w/o Carbon) (504024890)..... PA5336
Single Air (2991793)..... PA3606	Trans. (5000807213)..... PT8385	Air Dryer (1907612)..... BA5374 +
I. Air (1905620)..... PA3494	Steering..... P106-HD	Breather (500339085)..... BT9408
Air Dryer (1907612)..... BA5374 +	Stralis (Active day) 350 w/Cursor 8-350 Eng. (06/03-on)	Steering (100.8 mm) (1902137).... P106-HD
Coolant (1901776)..... BW5143	Lube (99445200)..... B7174-MPG	Steering (115.8 mm) (1267900).... PT691
Steering (1902137)..... P106-HD	Fuel/Water Separator (504086268)..... BF1292-O	Urea (denoxtronic 1) (42562233).. PE5270
EuroTrakker 340 E 37 w/8210.42 K Eng. (03/95-05/01)	Fuel/Water Separator (To 12/03) (1907539)..... BF1217	Urea (denoxtronic 2) (42555073).. PE5271
Dual-Flow Lube (1903715)..... BD325	Fuel/Water Separator (01/04-on) (2992662)..... BF1365	Stralis (Active time) 360 w/Cursor 8-360 Eng. (03/06-on)
Fuel/Water Separator (1907539). BF1217	Fuel (1907460)..... BF7696	Lube (99445200)..... B7174-MPG
Fuel (1904640)..... BF7663	O. Air (To 09/04) (1904550)..... PA2776	Fuel/Water Separator (504086268)..... BF1292-O
O. Air (1904550)..... PA2776	I. Air (To 09/04) (1905620)..... PA3494	Fuel/Water Separator (2992662). BF1365
I. Air (1905620)..... PA3494	Single Radial Seal Air (10/04-on) (41272124)..... RS5356	Fuel (1907460)..... BF7696
Air Dryer (1907612)..... BA5374 +	Cab Air (w/o Carbon) (504024890)..... PA5336	Radial Seal Air (41272124)..... RS5356
Breather (500339085)..... BT9408	Air Dryer (1907612)..... BA5374 +	Cab Air (w/o Carbon) (504024890)..... PA5336
Trans..... PT8385	Breather (500339085)..... BT9408	Air Dryer (1907612)..... BA5374 +
Steering..... P106-HD	Steering (100.8 mm) (1902137).... P106-HD	Breather (500339085)..... BT9408
EuroTrakker 340 E 42 w/8210.42 Eng. (06/98-05/01)	Steering (115.8 mm) (1267900).... PT691	
Dual-Flow Lube (1903715)..... BD325		
Fuel/Water Separator (1907539). BF1217		
Fuel (1904640)..... BF7663		
O. Air (1904550)..... PA2776		
Single Air (2991793)..... PA3606		
I. Air (1905620)..... PA3494		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IVECO Trucks (cont'd)	IVECO Trucks (cont'd)	IVECO Trucks (cont'd)
Stralis (Active time) 360 w/Cursor 8-360 Eng. (03/06-on) (Cont'd)	EuroTrakker 380 E 37 w/8210.42K (TCA) Eng. (01/93-05/01) (Cont'd)	Stralis 400 w/Cursor 10 Eng. (10/04-on)
Steering (100.8 mm) (1902137)... P106-HD	I. Air (1905620)..... PA3494	Lube..... B7174-MPG
Steering (115.8 mm) (1267900)... PT691	Air Dryer (1907612)..... BA5374 +	Fuel..... BF7927
Urea (denoxtronic 1) (42562233).. PE5270	Coolant (1901776)..... BW5143	Fuel/Water Separator..... BF1365
Urea (denoxtronic 2) (42555073).. PE5271	Steering (1902137)..... P106-HD	Radial Seal Air (41272124)..... RS5356
Trakker 360 w/Cursor 8 (Euro 4/5) Eng. (03/06-on)	EuroTrakker 380E38 w/Cursor13 Eng. (01/01-11/04)	Cab Air (504024890)..... PA5336
Lube..... B7174-MPG	Lube..... B7174-MPG	Air Dryer..... BA5374 +
Lube (2996416)..... P7495	Fuel/Water Separator (1907539)..... BF1217	Trans. (5000807213)..... PT8385
Fuel/Water Separator (1907539)..... BF1217	465.9 mm O. Air (41272211)..... PA5364	Steering..... P106-HD
Fuel..... BF7696	461.2 mm I. Air (41214149)..... PA5365	Stralis (Active day) 400 w/Cursor 10-400 Eng. (06/03-on)
Radial Seal Air (41272124)..... RS5356	Air Dryer (Mann TB1374X)..... BA5374 +	Lube (99445200)..... B7174-MPG
Air (Metal Hsg.)..... PA3606	Breather (500339085)..... BT9408	Fuel/Water Separator (504086268)..... BF1292-O
Cab Air (w/o Carbon) (504024890)..... PA5336	Trans..... PT8385	Fuel/Water Separator (To 12/03) (1907539)..... BF1217
Air Dryer (Mann TB1374X)..... BA5374 +	Steering..... P106-HD	Fuel/Water Separator (01/04-on) (2992662)..... BF1365
Breather (500339085)..... BT9408	EuroTrakker 380 E 42 w/8210.42L (TCA) Eng. (01/93-05/01)	Fuel (500315480)..... BF7927
Steering..... P106-HD	Dual-Flow Lube (1903715)..... BD325	Radial Seal Air (10/04-on) (41272124)..... RS5356
360D34 w/Deutz BF10L413 Eng.	Fuel/Water Separator (1907539)..... BF1217	Cab Air (w/o Carbon) (504024890)..... PA5336
Lube (1160025)..... B236 +	Fuel (1904640)..... BF7663	Air Dryer (1907612)..... BA5374 +
Opt. Fuel/Water Separator..... BF1221 +	O. Air (1904550)..... PA2776	Breather (500339085)..... BT9408
123.0 mm Fuel (1160243)..... BF988 +	I. Air (1905620)..... PA3494	Steering (100.8 mm) (1902137)... P106-HD
136.5 mm Fuel (1164620)..... BF900	Air Dryer (1907612)..... BA5374 +	Steering (115.8 mm) (1267900)... PT691
O. Air (2165054)..... PA2474	Coolant (1901776)..... BW5143	Stralis (Active space) 400 w/Cursor 10-400 Eng. (01/02-on)
I. Air..... PA2836	Steering (1902137)..... P106-HD	Lube (99445200)..... B7174-MPG
360M19	EuroTrakker 380E44 w/Cursor13 Eng. (01/01-11/04)	Fuel/Water Separator (504086268)..... BF1292-O
Lube (1160025)..... B236 +	Lube..... B7174-MPG	Fuel/Water Separator (To 12/03) (1907539)..... BF1217
Fuel (1164620)..... BF900	Fuel/Water Separator (1907539)..... BF1217	Fuel/Water Separator (01/04-on) (2992662)..... BF1365
O. Air..... PA2776	465.9 mm O. Air (41272211)..... PA5364	Fuel (500315480)..... BF7927
I. Air..... PA3494	461.2 mm I. Air (41214149)..... PA5365	Radial Seal Air (10/04-on) (41272124)..... RS5356
Trakker 380 w/Cursor 13 Eng. (09/04-on)	Air Dryer (Mann TB1374X)..... BA5374 +	Cab Air (w/o Carbon) (504024890)..... PA5336
Lube..... B7174-MPG	Breather (500339085)..... BT9408	Air Dryer (1907612)..... BA5374 +
Fuel/Water Separator (1907539)..... BF1217	Trans..... PT8385	Breather (500339085)..... BT9408
Radial Seal Air (41272124)..... RS5356	Steering..... P106-HD	Steering (100.8 mm) (1902137)... P106-HD
Air (Metal Hsg.)..... PA3606	EuroTrakker 380 E 47 w/8210.42M (TCA) Eng. (01/00-11/04)	Steering (115.8 mm) (1267900)... PT691
Cab Air (w/o Carbon) (504024890)..... PA5336	Dual-Flow Lube (1903715)..... BD325	Stralis (Active time) 400 w/Cursor 10-400 Eng. (06/03-on)
Air Dryer (Mann TB1374X)..... BA5374 +	Fuel/Water Separator (1907539)..... BF1217	Lube (99445200)..... B7174-MPG
Breather (500339085)..... BT9408	Fuel (1904640)..... BF7663	Fuel/Water Separator (504086268)..... BF1292-O
Steering..... P106-HD	O. Air (1904550)..... PA2776	Fuel/Water Separator (To 12/03) (1907539)..... BF1217
EuroTrakker 380 E 34 w/8460.41K.406 Eng. (04/92-11/04)	I. Air (1905620)..... PA3494	Fuel/Water Separator (01/04-on) (2992662)..... BF1365
Dual-Flow Lube (1903715)..... BD325	Air Dryer (1907612)..... BA5374 +	Fuel (500315480)..... BF7927
Fuel/Water Separator (1907539)..... BF1217	Coolant (1901776)..... BW5143	Radial Seal Air (10/04-on) (41272124)..... RS5356
Fuel (1904640)..... BF7663	Steering (1902137)..... P106-HD	Cab Air (w/o Carbon) (504024890)..... PA5336
O. Air (1904550)..... PA2776	Stralis 400 w/Cursor 10 Eng. (06/03-09/04)	Air Dryer (1907612)..... BA5374 +
I. Air (1905620)..... PA3494	Lube..... B7174-MPG	Breather (500339085)..... BT9408
Air Dryer (1907612)..... BA5374 +	Fuel/Water Separator (6/03-12/03) (1907539)..... BF1217	Steering (100.8 mm) (1902137)... P106-HD
Coolant (1901776)..... BW5143	Fuel (500315480)..... BF7927	Steering (115.8 mm) (1267900)... PT691
Steering (1902137)..... P106-HD	Cab Air (504024890)..... PA5336	Stralis (Active time) 400 w/Cursor 10-400 Eng. (06/03-on)
EuroTrakker 380 E 37 w/8210.42K (TCA) Eng. (01/93-05/01)	Air Dryer..... BA5374 +	Lube (99445200)..... B7174-MPG
Dual-Flow Lube (1903715)..... BD325	Trans. (5000807213)..... PT8385	Fuel/Water Separator (504086268)..... BF1292-O
Fuel/Water Separator (1907539)..... BF1217	Steering..... P106-HD	Fuel/Water Separator (To 12/03) (1907539)..... BF1217
Fuel (1904640)..... BF7663	Stralis 400 w/Cursor 10 Eng. (06/03-09/04)	Fuel/Water Separator (01/04-on) (2992662)..... BF1365
O. Air (1904550)..... PA2776	Lube..... B7174-MPG	Fuel (1907460)..... BF7696
	Fuel/Water Separator (6/03-12/03) (1907539)..... BF1217	Radial Seal Air (10/04-on) (41272124)..... RS5356
	Fuel (500315480)..... BF7927	
	Cab Air (504024890)..... PA5336	
	Air Dryer..... BA5374 +	
	Trans. (5000807213)..... PT8385	
	Steering..... P106-HD	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IVECO Trucks (cont'd)	IVECO Trucks (cont'd)	IVECO Trucks (cont'd)
Stralis (Active time) 400 w/Cursor 10-400 Eng. (06/03-on) (Cont'd) Cab Air (w/o Carbon) (504024890)..... PA5336 Air Dryer (1907612)..... BA5374 + Breather (500339085)..... BT9408 Steering (100.8 mm) (1902137)... P106-HD Steering (115.8 mm) (1267900)... PT691	EuroTech 400E35 w/Cursor E0681A Eng. (10/98-on) Lube..... B7174-MPG Fuel/Water Separator (1907539). BF1217 Fuel..... BF7696 Air..... PA2776 Air Dryer (Mann TB1374X)..... BA5374 + Trans..... PT8385 Steering..... P106-HD	Eurotech 400 E 38 w/8460.41L.5020 Eng. (09/92-06/02) (Cont'd) Fuel (1904640)..... BF7663 O. Air (1904550)..... PA2776 I. Air (1905620)..... PA3494 Air Dryer (1907612)..... BA5374 + Coolant (1901776)..... BW5143 Steering (1902137)..... P106-HD
Eurotech 400 E 30 w/8460.41 TCA Eng. (04/92-06/02) Dual-Flow Lube (1902102)..... BD325 Fuel/Water Separator (1907539). BF1217 Fuel (1904640)..... BF7663 O. Air (1904550)..... PA2776 I. Air (1905620)..... PA3494 Air Dryer (1907612)..... BA5374 + Coolant (1901776)..... BW5143 Steering (1902137)..... P106-HD	EuroTrakker 400 E 35 w/Cursor E0681A Eng. (02/99-11/04) Lube (99445200)..... B7174-MPG Fuel/Water Separator (1907539). BF1217 Fuel (1907460)..... BF7696 O. Air (1904550)..... PA2776 I. Air (1905620)..... PA3494 Air Dryer (1907612)..... BA5374 + Breather (500339085)..... BT9408 Trans. (42491185)..... PT8385 Steering (1902137)..... P106-HD	EuroTech 400E39 w/Cursor E0681E Eng. (10/99-on) Lube..... B7174-MPG Fuel/Water Separator (1907539). BF1217 Air..... PA2776 Air Dryer (Mann TB1374X)..... BA5374 + Trans..... PT8385 Steering..... P106-HD
EuroTech 400E31 w/Cursor E0681B Eng. (10/98-on) Lube..... B7174-MPG Fuel/Water Separator (1907539). BF1217 Fuel..... BF7696 Air..... PA2776 Air Dryer (Mann TB1374X)..... BA5374 + Trans..... PT8385 Steering..... P106-HD	EuroTrakker 400E37 w/8210.42 Eng. Dual-Flow Lube (1907584)..... BD325 Fuel (1907640)..... BF7663 Fuel/Water Separator (1908547). BF1217 Air..... PA2776 Coolant (1901776)..... BW5143 Steering (1902137)..... P106-HD	EuroStar 400E42 w/8210TCA Eng. Dual-Flow Lube..... BD325 Fuel/Water Separator (1907539). BF1217 Fuel (1907640)..... BF7663 Air..... PA2776 Steering..... P106-HD
EuroTrakker 400E34 w/8460TCA Eng. Dual-Flow Lube (1907584)..... BD325 Fuel/Water Separator (1907539). BF1217 Fuel (1907640)..... BF7663 Opt. Fuel/Water Separator..... BF1221 + O. Air (1904550)..... PA2776 Coolant (1901776)..... BW5143 Steering (1902137)..... P106-HD	EuroTrakker 400 E 37 w/8210.42K.(TCA) Eng. (07/94-11/04) Dual-Flow Lube (1903715)..... BD325 Fuel/Water Separator (1907539). BF1217 Fuel (1904640)..... BF7663 O. Air (1904550)..... PA2776 I. Air (1905620)..... PA3494 Air Dryer (1907612)..... BA5374 + Coolant (1901776)..... BW5143 Steering (1902137)..... P106-HD	EuroTech 400E42 w/8210TCA Eng. (04/92-on) Dual-Flow Lube..... BD325 Fuel/Water Separator (1907539). BF1217 Fuel (1907640)..... BF7663 Air..... PA2776 Steering..... P106-HD
Eurotech 400 E 34 w/8460.41K.406 Eng. (04/92-06/02) Dual-Flow Lube (1902102)..... BD325 Fuel/Water Separator (1907539). BF1217 Fuel (1904640)..... BF7663 O. Air (1904550)..... PA2776 I. Air (1905620)..... PA3494 Air Dryer (1907612)..... BA5374 + Coolant (1901776)..... BW5143 Steering (1902137)..... P106-HD	EuroTrakker 400 E 37 w/8210.42L.(TCA) Eng. (04/92-11/04) Dual-Flow Lube (1903715)..... BD325 Fuel/Water Separator (1907539). BF1217 Fuel (1904640)..... BF7663 O. Air (1904550)..... PA2776 I. Air (1905620)..... PA3494 Air Dryer (1907612)..... BA5374 + Coolant (1901776)..... BW5143 Steering (1902137)..... P106-HD	EuroTrakker 400E42 w/8210.42 Eng. Dual-Flow Lube (1907584)..... BD325 Fuel (1907640)..... BF7663 Fuel/Water Separator (1908547). BF1217 Air..... PA2776 Coolant (1901776)..... BW5143 Steering (1902137)..... P106-HD
EuroTrakker 400 E 34 w/8460.41K Eng. (01/93-03/99) Dual-Flow Lube (1903715)..... BD325 Fuel/Water Separator (1907539). BF1217 Fuel (1904640)..... BF7663 O. Air (1904550)..... PA2776 Single Air (2991793)..... PA3606 I. Air (1905620)..... PA3494 Air Dryer (1907612)..... BA5374 + Coolant (1901776)..... BW5143 Steering (1902137)..... P106-HD	EuroStar 400E38 w/8460.41L.5020 Eng. (09/92-on) Dual-Flow Lube (1907584)..... BD325 Fuel (1907640)..... BF7663 Fuel/Water Separator (1908547). BF1217 Air..... PA2776 Air Dryer (Mann TB1374X)..... BA5374 + Coolant (1901776)..... BW5143 Steering (1902137)..... P106-HD	EuroTrakker 400 E 42 w/8210.42L.(TCA) Eng. (04/92-11/04) Dual-Flow Lube (1903715)..... BD325 Fuel/Water Separator (1907539). BF1217 Fuel (1904640)..... BF7663 O. Air (1904550)..... PA2776 I. Air (1905620)..... PA3494 Air Dryer (1907612)..... BA5374 + Coolant (1901776)..... BW5143 Steering (1902137)..... P106-HD
	400E38 w/8210.42 Eng. Dual-Flow Lube (1907584)..... BD325 Fuel (1907640)..... BF7663 Fuel/Water Separator (1908547). BF1217 Air..... PA2776 Coolant (1901776)..... BW5143 Steering (1902137)..... P106-HD	EuroStar 400E43 w/Cursor E0681D (Cursor 10) Eng. (10/99-on) Lube (99445200)..... B7174-MPG Fuel/Water Separator (1907539). BF1217 473.9 mm Air..... PA2776 Air Dryer (Mann TB1374X)..... BA5374 + Trans. (5000807213)..... PT8385 Steering..... P106-HD
	Eurotech 400 E 38 w/8460.41L.5020 Eng. (09/92-06/02) Dual-Flow Lube (1902102)..... BD325 Fuel/Water Separator (1907539). BF1217	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IVECO Trucks (cont'd)	IVECO Trucks (cont'd)	IVECO Trucks (cont'd)
EuroTech 400E43 w/Cursor E0681D Eng. (10/99-on) <b>Lube</b> (99445200)..... <b>B7174-MPG</b> <b>Fuel/Water Separator</b> (1907539). <b>BF1217</b> <b>473.9 mm Air</b> ..... <b>PA2776</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Trans.</b> (5000807213)..... <b>PT8385</b> <b>Steering</b> ..... <b>P106-HD</b>	EuroTrakker 410 E 35 w/Cursor E0681A Eng. (02/99-11/04) (Cont'd) <b>Air Dryer</b> (1907612)..... <b>BA5374 +</b> <b>Breather</b> (500339085)..... <b>BT9408</b> <b>Trans.</b> (42491185)..... <b>PT8385</b> <b>Steering</b> (1902137)..... <b>P106-HD</b> EuroTrakker 410E37 w/8210.42 Eng. <b>Dual-Flow Lube</b> (1907584)..... <b>BD325</b> <b>Fuel</b> (1907640)..... <b>BF7663</b> <b>Fuel/Water Separator</b> (1908547). <b>BF1217</b> <b>Air</b> ..... <b>PA2776</b> <b>Coolant</b> (1901776)..... <b>BW5143</b> <b>Steering</b> (1902137)..... <b>P106-HD</b>	EuroTrakker 410E44 w/Cursor13 Eng. (01/01-11/04) (Cont'd) <b>461.2 mm I. Air</b> (41214149)..... <b>PA5365</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Breather</b> (500339085)..... <b>BT9408</b> <b>Trans.</b> ..... <b>PT8385</b> <b>Steering</b> ..... <b>P106-HD</b> EuroTrakker 440 E 47 w/8210.42M (TCA) Eng. (01/00-11/04) <b>Dual-Flow Lube</b> (1903715)..... <b>BD325</b> <b>Fuel/Water Separator</b> (1907539). <b>BF1217</b> <b>Fuel</b> (1904640)..... <b>BF7663</b> <b>Air</b> (2991793)..... <b>PA3606</b> <b>Air Dryer</b> (1907612)..... <b>BA5374 +</b> <b>Coolant</b> (1901776)..... <b>BW5143</b> <b>Steering</b> (1902137)..... <b>P106-HD</b>
EuroTech 400E52 w/8280.42 Eng. (1907571)..... <b>BD7168</b> <b>Fuel/Water Separator</b> (1907539). <b>BF1217</b> <b>Fuel</b> (1907640)..... <b>BF7663</b> <b>Coolant</b> (1901776)..... <b>BW5143</b> <b>Steering</b> (1902137)..... <b>P106-HD</b>	EuroTrakker 410 E 37 w/8210.42K Eng. (04/92-05/01) <b>Dual-Flow Lube</b> (1903715)..... <b>BD325</b> <b>Fuel/Water Separator</b> (1907539). <b>BF1217</b> <b>Fuel</b> (1904640)..... <b>BF7663</b> <b>Single Air</b> (2991793)..... <b>PA3606</b> <b>O. Air</b> (1904550)..... <b>PA2776</b> <b>I. Air</b> (1905620)..... <b>PA3494</b> <b>Air Dryer</b> (1907612)..... <b>BA5374 +</b> <b>Coolant</b> (1901776)..... <b>BW5143</b> <b>Steering</b> (1902137)..... <b>P106-HD</b>	EuroTrakker 410 E 47 w/8210.42M (TCA) Eng. (01/00-11/04) <b>Dual-Flow Lube</b> (1903715)..... <b>BD325</b> <b>Fuel/Water Separator</b> (1907539). <b>BF1217</b> <b>Fuel</b> (1904640)..... <b>BF7663</b> <b>O. Air</b> (2991793)..... <b>PA3606</b> <b>I. Air</b> (1905620)..... <b>PA3494</b> <b>Air Dryer</b> (1907612)..... <b>BA5374 +</b> <b>Coolant</b> (1901776)..... <b>BW5143</b> <b>Steering</b> (1902137)..... <b>P106-HD</b>
Eurotech 400 E 52 w/8280.42S.350 Eng. (04/92-06/02) <b>Dual-Flow Lube</b> (1905704)..... <b>BD7168</b> <b>Fuel/Water Separator</b> (1907539). <b>BF1217</b> <b>Fuel</b> (1904640)..... <b>BF7663</b> <b>Air Dryer</b> (1907612)..... <b>BA5374 +</b> <b>Steering</b> (1902137)..... <b>P106-HD</b>	EuroTrakker 410E38 w/Cursor13 Eng. (01/01-11/04) <b>Lube</b> ..... <b>B7174-MPG</b> <b>Fuel/Water Separator</b> (1907539). <b>BF1217</b> <b>465.9 mm O. Air</b> (41272211)..... <b>PA5364</b> <b>461.2 mm I. Air</b> (41214149)..... <b>PA5365</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Breather</b> (500339085)..... <b>BT9408</b> <b>Trans.</b> ..... <b>PT8385</b> <b>Steering</b> ..... <b>P106-HD</b>	EuroTrakker 410 E 42 w/8210.42M (TCA) Eng. (04/92-11/04) <b>Dual-Flow Lube</b> (1903715)..... <b>BD325</b> <b>Fuel/Water Separator</b> (1907539). <b>BF1217</b> <b>Fuel</b> (1904640)..... <b>BF7663</b> <b>Single Air</b> (2991793)..... <b>PA3606</b> <b>O. Air</b> (1904550)..... <b>PA2776</b> <b>I. Air</b> (1905620)..... <b>PA3494</b> <b>Air Dryer</b> (1907612)..... <b>BA5374 +</b> <b>Coolant</b> (1901776)..... <b>BW5143</b> <b>Steering</b> (1902137)..... <b>P106-HD</b>
LD400E42T/FP, LD400E42T/P, LD400E42TX/P w/8210TCA Eng. (04/92-on) <b>Dual-Flow Lube</b> ..... <b>BD325</b> <b>Fuel/Water Separator</b> (1907539). <b>BF1217</b> <b>Fuel</b> ..... <b>BF7663</b> <b>Air</b> ..... <b>PA2776</b> <b>Steering</b> ..... <b>P106-HD</b>	EuroTrakker 410E42 w/8210.42 Eng. (01/01-11/04) <b>Dual-Flow Lube</b> (1907584)..... <b>BD325</b> <b>Fuel</b> (1907640)..... <b>BF7663</b> <b>Fuel/Water Separator</b> (1908547). <b>BF1217</b> <b>Air</b> ..... <b>PA2776</b> <b>Coolant</b> (1901776)..... <b>BW5143</b> <b>Steering</b> (1902137)..... <b>P106-HD</b>	Stralis (Active day) 420 w/Cursor 10-420 Eng. (03/06-on) <b>Lube</b> (99445200)..... <b>B7174-MPG</b> <b>Fuel/Water Separator</b> (504086268)..... <b>BF1292-O</b> <b>Fuel/Water Separator</b> (2992662). <b>BF1365</b> <b>Radial Seal Air</b> (41272124)..... <b>RS5356</b> <b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b> <b>Air Dryer</b> (1907612)..... <b>BA5374 +</b> <b>Breather</b> (500339085)..... <b>BT9408</b> <b>Steering</b> (100.8 mm) (1902137).. <b>P106-HD</b> <b>Steering</b> (115.8 mm) (1267900).. <b>PT691</b> <b>Urea</b> (denoxtronic 1) (42562233).. <b>PE5270</b> <b>Urea</b> (denoxtronic 2) (42555073).. <b>PE5271</b>
400E30, 400E34 w/8210.42, 8460.41 Eng. <b>Dual-Flow Lube</b> (1907584)..... <b>BD325</b> <b>Fuel</b> (1907640)..... <b>BF7663</b> <b>Fuel/Water Separator</b> (1908547). <b>BF1217</b> <b>Air</b> ..... <b>PA2776</b> <b>Coolant</b> (1901776)..... <b>BW5143</b> <b>Steering</b> (1902137)..... <b>P106-HD</b>	EuroTrakker 410E42 w/8210.42 Eng. (01/01-11/04) <b>Dual-Flow Lube</b> (1907584)..... <b>BD325</b> <b>Fuel</b> (1907640)..... <b>BF7663</b> <b>Fuel/Water Separator</b> (1908547). <b>BF1217</b> <b>Air</b> ..... <b>PA2776</b> <b>Coolant</b> (1901776)..... <b>BW5143</b> <b>Steering</b> (1902137)..... <b>P106-HD</b>	Stralis (Active space) 420 w/Cursor 10-420 Eng. (03/06-on) <b>Lube</b> (99445200)..... <b>B7174-MPG</b> <b>Fuel/Water Separator</b> (504086268)..... <b>BF1292-O</b> <b>Fuel/Water Separator</b> (2992662). <b>BF1365</b> <b>Radial Seal Air</b> (41272124)..... <b>RS5356</b> <b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b> <b>Air Dryer</b> (1907612)..... <b>BA5374 +</b> <b>Breather</b> (500339085)..... <b>BT9408</b> <b>Steering</b> (100.8 mm) (1902137).. <b>P106-HD</b> <b>Steering</b> (115.8 mm) (1267900).. <b>PT691</b> <b>Urea</b> (denoxtronic 1) (42562233).. <b>PE5270</b> <b>Urea</b> (denoxtronic 2) (42555073).. <b>PE5271</b>
Trakker 410 w/Cursor 13 (Euro 4/5) Eng. (03/06-on) <b>Lube</b> ..... <b>B7174-MPG</b> <b>Lube</b> (2996416)..... <b>P7495</b> <b>Fuel/Water Separator</b> (1907539). <b>BF1217</b> <b>Radial Seal Air</b> (41272124)..... <b>RS5356</b> <b>Air</b> (Metal Hsg.)..... <b>PA3606</b> <b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Breather</b> (500339085)..... <b>BT9408</b> <b>Steering</b> ..... <b>P106-HD</b>	EuroTrakker 410 E 42 w/8210.42L (TCA) Eng. (04/92-11/04) <b>Dual-Flow Lube</b> (1903715)..... <b>BD325</b> <b>Fuel/Water Separator</b> (1907539). <b>BF1217</b> <b>Fuel</b> (1904640)..... <b>BF7663</b> <b>Single Air</b> (2991793)..... <b>PA3606</b> <b>O. Air</b> (1904550)..... <b>PA2776</b> <b>I. Air</b> (1905620)..... <b>PA3494</b> <b>Air Dryer</b> (1907612)..... <b>BA5374 +</b> <b>Coolant</b> (1901776)..... <b>BW5143</b> <b>Steering</b> (1902137)..... <b>P106-HD</b>	EuroTrakker 410E44 w/Cursor13 Eng. (01/01-11/04) <b>Lube</b> ..... <b>B7174-MPG</b> <b>Fuel/Water Separator</b> (1907539). <b>BF1217</b> <b>465.9 mm O. Air</b> (41272211)..... <b>PA5364</b>
410 <b>Lube</b> (78813556)..... <b>P20-HD +</b> <b>Fuel</b> (1909103)..... <b>BF783</b>	EuroTrakker 410E44 w/Cursor13 Eng. (01/01-11/04) <b>Lube</b> ..... <b>B7174-MPG</b> <b>Fuel/Water Separator</b> (1907539). <b>BF1217</b> <b>Fuel</b> (1907460)..... <b>BF7696</b> <b>O. Air</b> (1904550)..... <b>PA2776</b> <b>I. Air</b> (1905620)..... <b>PA3494</b>	

+ See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IVECO Trucks (cont'd)	IVECO Trucks (cont'd)	IVECO Trucks (cont'd)
<b>Stralis (Active time) 420 w/Cursor 10-420 Eng. (03/06-on)</b> Lube (99445200)..... <b>B7174-MPG</b> <b>Fuel/Water Separator</b> (504086268)..... <b>BF1292-O</b> <b>Fuel/Water Separator</b> (2992662)..... <b>BF1365</b> <b>Radial Seal Air</b> (41272124)..... <b>RS5356</b> <b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b> <b>Air Dryer</b> (1907612)..... <b>BA5374 +</b> <b>Breather</b> (500339085)..... <b>BT9408</b> <b>Steering</b> (100.8 mm) (1902137)... <b>P106-HD</b> <b>Steering</b> (115.8 mm) (1267900)... <b>PT691</b> <b>Urea</b> (denoxtronic 1) (42562233).. <b>PE5270</b> <b>Urea</b> (denoxtronic 2) (42555073).. <b>PE5271</b>	<b>Eurotech 420 E 34 w/8460.41K.406 Eng. (04/92-06/02) (Cont'd)</b> Coolant (1901776)..... <b>BW5143</b> <b>Steering</b> (1902137)..... <b>P106-HD</b> <b>Stralis 430 w/Cursor 10 Eng. (06/03-09/04)</b> Lube..... <b>B7174-MPG</b> <b>Fuel/Water Separator</b> (6/03-12/03) (1907539)..... <b>BF1217</b> <b>Fuel</b> (500315480)..... <b>BF7927</b> <b>Cab Air</b> (504024890)..... <b>PA5336</b> <b>Air Dryer</b> ..... <b>BA5374 +</b> <b>Trans.</b> (5000807213)..... <b>PT8385</b> <b>Steering</b> ..... <b>P106-HD</b> <b>Stralis 430 w/Cursor 10 Eng. (10/04-on)</b> Lube..... <b>B7174-MPG</b> <b>Fuel</b> ..... <b>BF7927</b> <b>Fuel/Water Separator</b> ..... <b>BF1365</b> <b>Radial Seal Air</b> (41272124)..... <b>RS5356</b> <b>Cab Air</b> (504024890)..... <b>PA5336</b> <b>Air Dryer</b> ..... <b>BA5374 +</b> <b>Trans.</b> (5000807213)..... <b>PT8385</b> <b>Steering</b> ..... <b>P106-HD</b> <b>Stralis (Active day) 430 w/Cursor 10-430 Eng. (06/03-on)</b> Lube (99445200)..... <b>B7174-MPG</b> <b>Fuel/Water Separator</b> (504086268)..... <b>BF1292-O</b> <b>Fuel/Water Separator</b> (To 12/03) (1907539)..... <b>BF1217</b> <b>Fuel/Water Separator</b> (01/04-on) (2992662)..... <b>BF1365</b> <b>Fuel</b> (500315480)..... <b>BF7927</b> <b>Radial Seal Air</b> (10/04-on) (41272124)..... <b>RS5356</b> <b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b> <b>Air Dryer</b> (1907612)..... <b>BA5374 +</b> <b>Breather</b> (500339085)..... <b>BT9408</b> <b>Steering</b> (100.8 mm) (1902137)... <b>P106-HD</b> <b>Steering</b> (115.8 mm) (1267900)... <b>PT691</b>	<b>Stralis (Active time) 430 w/Cursor 10-430 Eng. (06/03-on)</b> Lube (99445200)..... <b>B7174-MPG</b> <b>Fuel/Water Separator</b> (504086268)..... <b>BF1292-O</b> <b>Fuel/Water Separator</b> (To 12/03) (1907539)..... <b>BF1217</b> <b>Fuel/Water Separator</b> (01/04-on) (2992662)..... <b>BF1365</b> <b>Fuel</b> (1907460)..... <b>BF7696</b> <b>Radial Seal Air</b> (10/04-on) (41272124)..... <b>RS5356</b> <b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b> <b>Air Dryer</b> (1907612)..... <b>BA5374 +</b> <b>Breather</b> (500339085)..... <b>BT9408</b> <b>Steering</b> (100.8 mm) (1902137)... <b>P106-HD</b> <b>Steering</b> (115.8 mm) (1267900)... <b>PT691</b> <b>EuroTech Z435T</b> Dual-Flow Lube (1902076)..... <b>BD232</b> <b>Fuel</b> ..... <b>[2] BF988 +</b> <b>Air</b> (1902077)..... <b>PA2405</b> <b>Trakker 440 w/Cursor 13 Eng. (09/04-on)</b> Lube..... <b>B7174-MPG</b> <b>Fuel/Water Separator</b> (1907539)..... <b>BF1217</b> <b>Radial Seal Air</b> (41272124)..... <b>RS5356</b> <b>Air</b> (Metal Hsg.)..... <b>PA3606</b> <b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Breather</b> (500339085)..... <b>BT9408</b> <b>Steering</b> ..... <b>P106-HD</b> <b>EuroTech 440E31 w/Cursor E0681B Eng. (11/98-on)</b> Lube (99445200)..... <b>B7174-MPG</b> <b>Fuel/Water Separator</b> (1907539)..... <b>BF1217</b> <b>Fuel</b> ..... <b>BF7696</b> <b>Air</b> ..... <b>PA2776</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Trans.</b> (5000807213)..... <b>PT8385</b> <b>Steering</b> ..... <b>P106-HD</b> <b>Eurotech 440 E 34 w/8460.41K.410 Eng. (04/92-06/02)</b> Dual-Flow Lube (1902102)..... <b>BD325</b> <b>Fuel/Water Separator</b> (1907539)..... <b>BF1217</b> <b>Fuel</b> (1904640)..... <b>BF7663</b> <b>O. Air</b> (1904550)..... <b>PA2776</b> <b>I. Air</b> (1905620)..... <b>PA3494</b> <b>Air Dryer</b> (1907612)..... <b>BA5374 +</b> <b>Coolant</b> (1901776)..... <b>BW5143</b> <b>Steering</b> (1902137)..... <b>P106-HD</b> <b>440E34, 440E38, 440E42 w/8210.42, 8460.41 Engs.</b> Dual-Flow Lube (1907584)..... <b>BD325</b> <b>Fuel</b> (1907640)..... <b>BF7663</b> <b>Fuel/Water Separator</b> (1908547)..... <b>BF1217</b> <b>Air</b> ..... <b>PA2776</b> <b>Coolant</b> (1901776)..... <b>BW5143</b>
<b>Strator 420 w/Cursor 10-420 Euro 5 / EEV Eng. (09/08-on)</b> Lube (2996416)..... <b>P7495</b> <b>Fuel/Water Separator</b> (504086268)..... <b>BF1292-O</b> <b>Fuel/Water Separator</b> (2992662)..... <b>BF1365</b> <b>Radial Seal Air</b> (2996126)..... <b>RS5356</b> <b>Air Dryer</b> (1907612)..... <b>BA5374 +</b> <b>Breather</b> (500339085)..... <b>BT9408</b> <b>Steering</b> (100.8 mm) (1902137)... <b>P106-HD</b> <b>Steering</b> (115.8 mm) (1267900)... <b>PT691</b> <b>Urea</b> (denoxtronic 1) (42562233).. <b>PE5270</b> <b>Urea</b> (denoxtronic 2) (42555073).. <b>PE5271</b>	<b>Stralis (Active day) 430 w/Cursor 10-430 Eng. (06/03-on)</b> Lube (99445200)..... <b>B7174-MPG</b> <b>Fuel/Water Separator</b> (504086268)..... <b>BF1292-O</b> <b>Fuel/Water Separator</b> (To 12/03) (1907539)..... <b>BF1217</b> <b>Fuel/Water Separator</b> (01/04-on) (2992662)..... <b>BF1365</b> <b>Fuel</b> (500315480)..... <b>BF7927</b> <b>Radial Seal Air</b> (10/04-on) (41272124)..... <b>RS5356</b> <b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b> <b>Air Dryer</b> (1907612)..... <b>BA5374 +</b> <b>Breather</b> (500339085)..... <b>BT9408</b> <b>Steering</b> (100.8 mm) (1902137)... <b>P106-HD</b> <b>Steering</b> (115.8 mm) (1267900)... <b>PT691</b>	<b>Eurostar 420 E 34 w/8460.41K.406 Eng. (04/92-02/02)</b> Dual-Flow Lube (1902102)..... <b>BD325</b> <b>Fuel/Water Separator</b> (1907539)..... <b>BF1217</b> <b>Fuel</b> (1904640)..... <b>BF7663</b> <b>O. Air</b> (1904550)..... <b>PA2776</b> <b>I. Air</b> (1905620)..... <b>PA3494</b> <b>Air Dryer</b> (1907612)..... <b>BA5374 +</b> <b>Coolant</b> (1901776)..... <b>BW5143</b> <b>Steering</b> (1902137)..... <b>P106-HD</b>
<b>Eurotech 420 E 34 w/8460.41K.406 Eng. (04/92-06/02)</b> Dual-Flow Lube (1902102)..... <b>BD325</b> <b>Fuel/Water Separator</b> (1907539)..... <b>BF1217</b> <b>Fuel</b> (1904640)..... <b>BF7663</b> <b>O. Air</b> (1904550)..... <b>PA2776</b> <b>I. Air</b> (1905620)..... <b>PA3494</b> <b>Air Dryer</b> (1907612)..... <b>BA5374 +</b>	<b>Stralis (Active space) 430 w/Cursor 10-430 Eng. (01/02-on)</b> Lube (99445200)..... <b>B7174-MPG</b> <b>Fuel/Water Separator</b> (504086268)..... <b>BF1292-O</b> <b>Fuel/Water Separator</b> (To 12/03) (1907539)..... <b>BF1217</b> <b>Fuel/Water Separator</b> (01/04-on) (2992662)..... <b>BF1365</b> <b>Fuel</b> (500315480)..... <b>BF7927</b> <b>Radial Seal Air</b> (10/04-on) (41272124)..... <b>RS5356</b> <b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b> <b>Air Dryer</b> (1907612)..... <b>BA5374 +</b> <b>Breather</b> (500339085)..... <b>BT9408</b> <b>Steering</b> (100.8 mm) (1902137)... <b>P106-HD</b> <b>Steering</b> (115.8 mm) (1267900)... <b>PT691</b>	

\* See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IVECO Trucks (cont'd)	IVECO Trucks (cont'd)	IVECO Trucks (cont'd)
440E34, 440E38, 440E42 w/8210.42, 8460.41 Engs. (Cont'd) Steering (1902137)..... P106-HD	Eurotech 440 E 38 w/8460.41 L(TCA) Eng. (04/93-06/02) Dual-Flow Lube (1902102)..... BD325 Fuel/Water Separator (1907539) BF1217 Fuel (1904640)..... BF7663 O. Air (1904550)..... PA2776 I. Air (1905620)..... PA3494 Air Dryer (1907612)..... BA5374 + Coolant (1901776)..... BW5143 Steering (1902137)..... P106-HD	Stralis Active Space AS440S40T/P w/Cursor 10-400 Eng. (06/03-on) Lube..... B7174-MPG Fuel/Water Separator (6/03-12/03) (1907539)..... BF1217 Fuel/Water Separator (1/2004-on)..... BF1365 Radial Seal Air (10/04-on) (41272124)..... RS5356 Cab Air (w/o Carbon)..... PA5336 Air Dryer (Mann TB1374X)..... BA5374 + Trans..... PT8385 Steering..... P106-HD
EuroTech 440E35 w/Cursor E0681A Eng. (10/98-on) Lube (99445200)..... B7174-MPG Fuel/Water Separator (1907539) BF1217 Fuel..... BF7696 Air..... PA2776 Air Dryer (Mann TB1374X)..... BA5374 + Trans. (5000807213)..... PT8385 Steering..... P106-HD	EuroTrakker 440 E 38 w/Cursor13 Eng. (01/01-11/04) Lube (99445200)..... B7174-MPG Fuel/Water Separator (1907539) BF1217 Fuel (500315480)..... BF7927 O. Air (2992374)..... PA5364 I. Air (41214149)..... PA5365 Air Dryer (1907612)..... BA5374 + Breather (500339085)..... BT9408 Trans. (42491185)..... PT8385 Steering (1902137)..... P106-HD	Stralis Active Space AS440S40T/P H w/Cursor 10-400 Eng. (06/03-on) Lube..... B7174-MPG Fuel/Water Separator (6/03-12/03) (1907539)..... BF1217 Fuel/Water Separator (1/2004-on)..... BF1365 Radial Seal Air (10/04-on) (41272124)..... RS5356 Cab Air (w/o Carbon)..... PA5336 Air Dryer (Mann TB1374X)..... BA5374 + Trans..... PT8385 Steering..... P106-HD
EuroTrakker 440 E 35 w/Cursor E0681A Eng. (02/99-11/04) Lube (99445200)..... B7174-MPG Fuel/Water Separator (1907539) BF1217 Fuel (1907460)..... BF7696 O. Air (1904550)..... PA2776 I. Air (1905620)..... PA3494 Air Dryer (1907612)..... BA5374 + Breather (500339085)..... BT9408 Trans. (42491185)..... PT8385 Steering (1902137)..... P106-HD	EuroStar 440E39 w/Cursor E0681E Eng. (10/99-on) Lube..... B7174-MPG Fuel/Water Separator (1907539) BF1217 Air..... PA2776 Air Dryer (Mann TB1374X)..... BA5374 + Trans..... PT8385 Steering..... P106-HD	Stralis Active Space AS440S40TF PLT w/Cursor 10-400 Eng. (06/03-on) Lube (99445200)..... B7174-MPG Fuel/Water Separator (6/03-12/03) (1907539)..... BF1217 Fuel/Water Separator (1/2004-on) (2992662)..... BF1365 Radial Seal Air (10/04-on) (41272124)..... RS5356 Cab Air (w/o Carbon) (Mann 504024890)..... PA5336 Air Dryer (Mann TB1374X)..... BA5374 + Breather (06/03-09/04) (500339085)..... BT9408 Trans. (5000807213)..... PT8385 Steering..... P106-HD
Stralis Active Time AT440S35T/P w/Cursor 8-352 Eng. (06/03-09/04) Lube (99445200)..... B7174-MPG Fuel/Water Separator (6/03-12/03) (1907539)..... BF1217 Fuel..... BF7696 Air..... PA2776 Cab Air (w/o Carbon) (504024890)..... PA5336 Air Dryer (Mann TB1374X)..... BA5374 + Breather (500339085)..... BT9408 Trans. (5000807213)..... PT8385 Steering..... P106-HD	EuroTech 440E39 w/Cursor E0681E Eng. (10/99-on) Lube..... B7174-MPG Fuel/Water Separator (1907539) BF1217 Air..... PA2776 Air Dryer (Mann TB1374X)..... BA5374 + Trans..... PT8385 Steering..... P106-HD	Stralis Active Space AS440S40TX/P w/Cursor 10-400 Eng. (06/03-on) Lube (99445200)..... B7174-MPG Fuel/Water Separator (6/03-12/03) (1907539)..... BF1217 Fuel/Water Separator (1/2004-on) (2992662)..... BF1365 Radial Seal Air (10/04-on) (41272124)..... RS5356 Cab Air (w/o Carbon) (Mann 504024890)..... PA5336 Air Dryer (Mann TB1374X)..... BA5374 + Breather (06/03-09/04) (500339085)..... BT9408 Trans. (5000807213)..... PT8385 Steering..... P106-HD
Stralis Active Time AT440S35T/P w/Cursor 8-352 Eng. (01/04-on) Lube..... B7174-MPG Fuel/Water Separator (2992662) BF1365 Radial Seal Air (10/04-on) (41272124)..... RS5356 Cab Air (w/o Carbon) (504024890)..... PA5336 Air Dryer..... BA5374 + Trans..... PT8385 Steering..... P106-HD	EuroStar 440E40 w/Cursor E0681 Eng. (07/00-on) Lube..... B7174-MPG Fuel/Water Separator (1907539) BF1217 473.9 mm Air..... PA2776 Air Dryer (Mann TB1374X)..... BA5374 + Trans..... PT8385 Steering..... P106-HD	Stralis Active Space AS440S40TX/P w/Cursor 10-400 Eng. (06/03-on) Lube (99445200)..... B7174-MPG Fuel/Water Separator (6/03-12/03) (1907539)..... BF1217 Fuel/Water Separator (1/2004-on) (2992662)..... BF1365 Radial Seal Air (10/04-on) (41272124)..... RS5356 Cab Air (w/o Carbon) (Mann 504024890)..... PA5336 Air Dryer (Mann TB1374X)..... BA5374 + Breather (06/03-09/04) (500339085)..... BT9408 Trans. (5000807213)..... PT8385 Steering..... P106-HD
EuroStar 440E38 w/8460.41L(TCA) Eng. (04/93-on) Dual-Flow Lube..... BD325 Fuel/Water Separator (1907539) BF1217 Fuel..... BF7663 Air..... PA2776 Air Dryer (Mann TB1374X)..... BA5374 + Coolant (1901776)..... BW5143 Steering..... P106-HD	EuroTech 440E40 w/Cursor E0681 Eng. (07/00-on) Lube..... B7174-MPG Fuel/Water Separator (1907539) BF1217 473.9 mm Air..... PA2776 Air Dryer (Mann TB1374X)..... BA5374 + Trans..... PT8385 Steering..... P106-HD	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IVECO Trucks (cont'd)	IVECO Trucks (cont'd)	IVECO Trucks (cont'd)
Stralis Active Time AT440S40T/FPCT w/Cursor 10-400 Eng. (06/03-on) Lube..... B7174-MPG Fuel/Water Separator (6/03-12/03) (1907539)..... BF1217 Fuel/Water Separator (01/04-on) BF1365 Radial Seal Air (10/04-on) (41272124)..... RS5356 Cab Air (w/o Carbon)..... PA5336 Air Dryer (Mann TB1374X)..... BA5374 + Breather (06/03-09/04) (500339085)..... BT9408 Trans..... PT8385 Steering..... P106-HD	EuroTech 440E42 w/8210TCA Eng. Dual-Flow Lube (1907584)..... BD325 Fuel (1907640)..... BF7663 Fuel/Water Separator (5039)..... BF1217 Air..... PA2776 Steering (1902137)..... P106-HD Eurotech 440 E 42 w/8210.42L.400 Eng. (04/92-06/02) Dual-Flow Lube (1902102)..... BD325 Fuel/Water Separator (1907539)..... BF1217 Fuel (1904640)..... BF7663 O. Air (1904550)..... PA2776 I. Air (1905620)..... PA3494 Air Dryer (1907612)..... BA5374 + Steering (1902137)..... P106-HD EuroTrakker 440 E 42 w/8210.42 Eng. (01/98-11/04) Dual-Flow Lube (1903715)..... BD325 Fuel/Water Separator (1907539)..... BF1217 Fuel (1904640)..... BF7663 O. Air (1904550)..... PA2776 I. Air (1905620)..... PA3494 Air Dryer (1907612)..... BA5374 + Coolant (1901776)..... BW5143 Steering (1902137)..... P106-HD Stralis 440S42 w/Cursor 10-420 Eng. (03/06-on) Lube..... B7174-MPG Lube (2996416)..... P7495 Fuel/Water Separator..... BF1365 Radial Seal Air (41272124)..... RS5356 Cab Air (w/o Carbon) (504024890)..... PA5336 Air Dryer (Mann TB1374X)..... BA5374 + Breather (500339085)..... BT9408 Trans..... PT8385 Steering..... P106-HD Eurostar 440E43 w/Cursor E0681D (Cursor 10) Eng. (10/99-on) Lube (99445200)..... B7174-MPG Fuel/Water Separator (1907539)..... BF1217 473.9 mm Air..... PA2776 Air Dryer (Mann TB1374X)..... BA5374 + Trans. (5000807213)..... PT8385 Steering..... P106-HD EuroTech 440E43 w/Cursor E0681D Eng. (10/99-on) Lube (99445200)..... B7174-MPG Fuel/Water Separator (1907539)..... BF1217 473.9 mm Air..... PA2776 Air Dryer (Mann TB1374X)..... BA5374 + Trans. (5000807213)..... PT8385 Steering..... P106-HD Stralis Active Space AS440S43T/FPCT w/Cursor 10-430 Eng. (06/03-on) Lube (99445200)..... B7174-MPG Fuel/Water Separator (6/03-12/03) (1907539)..... BF1217 Fuel/Water Separator (01/04-on) BF1365 Radial Seal Air (10/04-on) (41272124)..... RS5356 Cab Air (w/o Carbon)..... PA5336 Air Dryer (Mann TB1374X)..... BA5374 + Breather (06/03-09/04) (500339085)..... BT9408 Trans..... PT8385 Steering..... P106-HD	Stralis Active Space AS440S43T/FPCT w/Cursor 10-430 Eng. (06/03-on) (Cont'd) Fuel/Water Separator (1/2004-on) (2992662)..... BF1365 Radial Seal Air (10/04-on) (41272124)..... RS5356 Cab Air (w/o Carbon) (Mann 504024890)..... PA5336 Air Dryer (Mann TB1374X)..... BA5374 + Breather (06/03-09/04) (500339085)..... BT9408 Trans. (5000807213)..... PT8385 Steering..... P106-HD Stralis Active Space AS440S43T/P w/Cursor 10-430 Eng. (06/03-on) Lube..... B7174-MPG Fuel/Water Separator (6/03-12/03) (1907539)..... BF1217 Fuel/Water Separator (1/2004-on)..... BF1365 Radial Seal Air (10/04-on) (41272124)..... RS5356 Cab Air (w/o Carbon)..... PA5336 Air Dryer (Mann TB1374X)..... BA5374 + Trans..... PT8385 Steering..... P106-HD Stralis Active Space AS440S43TX/P w/Cursor 10-430 Eng. (06/03-on) Lube (99445200)..... B7174-MPG Fuel/Water Separator (6/03-12/03) (1907539)..... BF1217 Fuel/Water Separator (1/2004-on) (2992662)..... BF1365 Radial Seal Air (10/04-on) (41272124)..... RS5356 Cab Air (w/o Carbon) (Mann 504024890)..... PA5336 Air Dryer (Mann TB1374X)..... BA5374 + Breather (06/03-09/04) (500339085)..... BT9408 Trans. (5000807213)..... PT8385 Steering..... P106-HD Stralis Active Time AT440S43T/FPCT w/Cursor 10-430 Eng. (06/03-on) Lube..... B7174-MPG Fuel/Water Separator (6/03-12/03) (1907539)..... BF1217 Fuel/Water Separator (01/04-on) BF1365 Radial Seal Air (10/04-on) (41272124)..... RS5356 Cab Air (w/o Carbon)..... PA5336 Air Dryer (Mann TB1374X)..... BA5374 + Breather (06/03-09/04) (500339085)..... BT9408 Trans..... PT8385 Steering..... P106-HD
EuroStar 440E42 w/8210TCA Eng. Dual-Flow Lube (1907584)..... BD325 Fuel (1907640)..... BF7663 Fuel/Water Separator (5039)..... BF1217 Air..... PA2776 Steering (1902137)..... P106-HD	EuroStar 440E42 w/8210.42L.400 Eng. (04/92-on) Dual-Flow Lube..... BD325 Fuel/Water Separator (1907539)..... BF1217 Fuel..... BF7663 Air..... PA2776 Air Dryer (Mann TB1374X)..... BA5374 + Steering..... P106-HD	Stralis Active Space AS440S43T/FPCT w/Cursor 10-430 Eng. (06/03-on) (Cont'd) Fuel/Water Separator (1/2004-on) (2992662)..... BF1365 Radial Seal Air (10/04-on) (41272124)..... RS5356 Cab Air (w/o Carbon)..... PA5336 Air Dryer (Mann TB1374X)..... BA5374 + Breather (06/03-09/04) (500339085)..... BT9408 Trans..... PT8385 Steering..... P106-HD

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



IVECO Trucks (cont'd)	IVECO Trucks (cont'd)	IVECO Trucks (cont'd)
Stralis Active Time AT440S43T/FPLT w/Cursor 10-430 Eng. (06/03-on) <b>Lube</b> ..... B7174-MPG <b>Fuel/Water Separator</b> (6/03-12/03) (1907539)..... BF1217 <b>Fuel/Water Separator</b> (01/04-on) BF1365 <b>Radial Seal Air</b> (10/04-on) (41272124)..... RS5356 <b>Cab Air</b> (w/o Carbon)..... PA5336 <b>Air Dryer</b> (Mann TB1374X)..... BA5374 + <b>Breather</b> (06/03-09/04) (500339085)..... BT9408 <b>Trans.</b> ..... PT8385 <b>Steering</b> ..... P106-HD	EuroTrakker 440 E 44 w/Cursor13 Eng. (01/01-11/04) <b>Lube</b> (99445200)..... B7174-MPG <b>Fuel/Water Separator</b> (1907539) BF1217 <b>Fuel</b> (500315480)..... BF7927 <b>O. Air</b> (2992374)..... PA5364 <b>I. Air</b> (41214149)..... PA5365 <b>Air Dryer</b> (1907612)..... BA5374 + <b>Breather</b> (500339085)..... BT9408 <b>Trans.</b> (42491185)..... PT8385 <b>Steering</b> (1902137)..... P106-HD	EuroStar 440E48 w/Cursor 13 Eng. (01/01-on) <b>Lube</b> (99445200)..... B7174-MPG <b>Fuel/Water Separator</b> (1907539) BF1217 <b>Air Dryer</b> (Mann TB1374X)..... BA5374 + <b>Trans.</b> (5000807213)..... PT8385 <b>Steering</b> ..... P106-HD
Stralis Active Time AT440S43T/P w/Cursor 10-430 Eng. (06/03-on) <b>Lube</b> ..... B7174-MPG <b>Fuel/Water Separator</b> (6/03-12/03) (1907539)..... BF1217 <b>Fuel/Water Separator</b> (1/2004-on) (2992662)..... BF1365 <b>Radial Seal Air</b> (10/04-on) (41272124)..... RS5356 <b>Cab Air</b> (w/o Carbon) (504024890)..... PA5336 <b>Air Dryer</b> (Mann TB1374X)..... BA5374 + <b>Trans.</b> ..... PT8385 <b>Steering</b> ..... P106-HD	Stralis 440S45 w/Cursor 10-450 Eng. (03/06-on) <b>Lube</b> ..... B7174-MPG <b>Lube</b> (2996416)..... P7495 <b>Fuel/Water Separator</b> ..... BF1365 <b>Radial Seal Air</b> (41272124)..... RS5356 <b>Cab Air</b> (w/o Carbon) (504024890)..... PA5336 <b>Air Dryer</b> (Mann TB1374X)..... BA5374 + <b>Breather</b> (500339085)..... BT9408 <b>Trans.</b> ..... PT8385 <b>Steering</b> ..... P106-HD	Stralis 440S50 w/Cursor 10-500 Eng. (03/06-on) <b>Lube</b> ..... B7174-MPG <b>Lube</b> (2996416)..... P7495 <b>Fuel/Water Separator</b> ..... BF1365 <b>Radial Seal Air</b> (41272124)..... RS5356 <b>Cab Air</b> (w/o Carbon) (504024890)..... PA5336 <b>Air Dryer</b> (Mann TB1374X)..... BA5374 + <b>Breather</b> (500339085)..... BT9408 <b>Trans.</b> ..... PT8385 <b>Steering</b> ..... P106-HD
Stralis Active Time AT440S43TX/P w/Cursor 10-430 Eng. (06/03-on) <b>Lube</b> ..... B7174-MPG <b>Fuel/Water Separator</b> (6/03-12/03) (1907539)..... BF1217 <b>Fuel/Water Separator</b> (1/2004-on) (2992662)..... BF1365 <b>Radial Seal Air</b> (10/04-on) (41272124)..... RS5356 <b>Cab Air</b> (w/o Carbon) (504024890)..... PA5336 <b>Air Dryer</b> (Mann TB1374X)..... BA5374 + <b>Trans.</b> ..... PT8385 <b>Steering</b> ..... P106-HD	EuroStar 440E46 w/Cursor 13 (Euro2) Eng. (03/01-on) <b>Lube</b> (99445200)..... B7174-MPG <b>Fuel/Water Separator</b> ..... BF1217 <b>Air Dryer</b> (Mann TB1374X)..... BA5374 + <b>Trans.</b> (5000807213)..... PT8385 <b>Steering</b> ..... P106-HD	EuroStar 440E52 w/8280.42S.350 Eng. (04/92-on) <b>Dual-Flow Lube</b> (1907571)..... BD7168 <b>Fuel</b> (1907640)..... BF7663 <b>Fuel/Water Separator</b> ..... BF1217 <b>Air Dryer</b> (Mann TB1374X)..... BA5374 + <b>Coolant</b> (1901776)..... BW5143 <b>Steering</b> ..... P106-HD
Stralis Active Time AT440S43TX/P w/Cursor 10-430 Eng. (06/03-on) <b>Lube</b> ..... B7174-MPG <b>Fuel/Water Separator</b> (6/03-12/03) (1907539)..... BF1217 <b>Fuel/Water Separator</b> (01/04-on) BF1365 <b>Radial Seal Air</b> (1/2004-on) (41272124)..... RS5356 <b>Cab Air</b> (w/o Carbon)..... PA5336 <b>Air Dryer</b> (Mann TB1374X)..... BA5374 + <b>Breather</b> (06/03-09/04) (500339085)..... BT9408 <b>Trans.</b> ..... PT8385 <b>Steering</b> ..... P106-HD	EuroStar 440E47 w/8210.42M.(TCA) Eng. (04/92-05/01) <b>Dual-Flow Lube</b> ..... BD325 <b>Fuel/Water Separator</b> (1907539) BF1217 <b>Fuel</b> ..... BF7663 <b>Air</b> ..... PA2776 <b>Air Dryer</b> (Mann TB1374X)..... BA5374 + <b>Steering</b> ..... P106-HD	Stralis 440S56 w/Cursor 10-560 Eng. (03/06-on) <b>Lube</b> ..... B7174-MPG <b>Lube</b> (2996416)..... P7495 <b>Fuel/Water Separator</b> ..... BF1365 <b>Radial Seal Air</b> (41272124)..... RS5356 <b>Cab Air</b> (w/o Carbon) (504024890)..... PA5336 <b>Air Dryer</b> (Mann TB1374X)..... BA5374 + <b>Breather</b> (500339085)..... BT9408 <b>Trans.</b> ..... PT8385 <b>Steering</b> ..... P106-HD
Stralis Active Time AT440S43TZR HM w/Cursor 10-430 Eng. (06/03-on) <b>Lube</b> ..... B7174-MPG <b>Fuel/Water Separator</b> (6/03-12/03) (1907539)..... BF1217 <b>Fuel/Water Separator</b> (1/2004-on) (2992662)..... BF1365 <b>Radial Seal Air</b> (10/04-on) (41272124)..... RS5356 <b>Cab Air</b> (w/o Carbon) (504024890)..... PA5336 <b>Air Dryer</b> (Mann TB1374X)..... BA5374 + <b>Trans.</b> ..... PT8385 <b>Steering</b> ..... P106-HD	440E47 w/8210.42, 8460.41 Eng. <b>Dual-Flow Lube</b> (1907584)..... BD325 <b>Fuel</b> (1907640)..... BF7663 <b>Fuel/Water Separator</b> (1908547) BF1217 <b>Air</b> ..... PA2776 <b>Coolant</b> (1901776)..... BW5143 <b>Steering</b> (1902137)..... P106-HD	Stralis (Active day) 450 w/Cursor 10-450 Eng. (03/06-on) <b>Lube</b> (99445200)..... B7174-MPG <b>Fuel/Water Separator</b> (504086268)..... BF1292-O <b>Fuel/Water Separator</b> (2992662) BF1365 <b>Radial Seal Air</b> (41272124)..... RS5356 <b>Cab Air</b> (w/o Carbon) (504024890)..... PA5336 <b>Air Dryer</b> (1907612)..... BA5374 + <b>Breather</b> (500339085)..... BT9408 <b>Steering</b> (100.8 mm) (1902137)..... P106-HD <b>Steering</b> (115.8 mm) (1267900)..... PT691 <b>Urea</b> (denoxtronic 1) (42562233)..... PE5270 <b>Urea</b> (denoxtronic 2) (42555073)..... PE5271
EuroTrakker 440 E 37 w/8210.42 Eng. (01/98-11/04) <b>Dual-Flow Lube</b> (1903715)..... BD325 <b>Fuel/Water Separator</b> (1907539) BF1217 <b>Fuel</b> (1904640)..... BF7663 <b>O. Air</b> (1904550)..... PA2776 <b>I. Air</b> (1905620)..... PA3494 <b>Air Dryer</b> (1907612)..... BA5374 + <b>Coolant</b> (1901776)..... BW5143 <b>Steering</b> (1902137)..... P106-HD	Stralis (Active space) 450 w/Cursor 10-450 Eng. (03/06-on) <b>Lube</b> (99445200)..... B7174-MPG <b>Fuel/Water Separator</b> (504086268)..... BF1292-O <b>Fuel/Water Separator</b> (2992662) BF1365 <b>Radial Seal Air</b> (41272124)..... RS5356	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IVECO Trucks (cont'd)	IVECO Trucks (cont'd)	IVECO Trucks (cont'd)
Stralis (Active space) 450 w/Cursor 10-450 Eng. (03/06-on) (Cont'd)	Stralis (Active day) 460 w/Cursor 10-460 Eng. (07/11-on)	Stralis (Active space) 480 w/Cursor 13-480 Eng. (01/02-on) (Cont'd)
<b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b>	<b>Lube</b> (2996416)..... <b>P7495</b>	<b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b>
<b>Air Dryer</b> (1907612)..... <b>BA5374 +</b>	<b>Fuel/Water Separator</b> (504086268)..... <b>BF1292-O</b>	<b>Air Dryer</b> (1907612)..... <b>BA5374 +</b>
<b>Breather</b> (500339085)..... <b>BT9408</b>	<b>Fuel/Water Separator</b> (2992662)..... <b>BF1365</b>	<b>Breather</b> (500339085)..... <b>BT9408</b>
<b>Steering</b> (100.8 mm) (1902137)... <b>P106-HD</b>	<b>Radial Seal Air</b> (41272124)..... <b>RS5356</b>	<b>Steering</b> (100.8 mm) (1902137)... <b>P106-HD</b>
<b>Steering</b> (115.8 mm) (1267900)... <b>PT691</b>	<b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b>	<b>Steering</b> (115.8 mm) (1267900)... <b>PT691</b>
<b>Urea</b> (denoxtronic 1) (42562233).. <b>PE5270</b>	<b>Air Dryer</b> (1907612)..... <b>BA5374 +</b>	<b>Urea</b> (denoxtronic 1) (42562233).. <b>PE5270</b>
<b>Urea</b> (denoxtronic 2) (42555073).. <b>PE5271</b>	<b>Breather</b> (500339085)..... <b>BT9408</b>	<b>Urea</b> (denoxtronic 2) (42555073).. <b>PE5271</b>
Stralis (Active time) 450 w/Cursor 10-450 Eng. (03/06-on)	Stralis (Active space) 460 w/Cursor 10-460 Eng. (07/11-on)	Stralis (Executive space) 480 w/Cursor 13 (F3B) Eng. (09/04-on)
<b>Lube</b> (99445200)..... <b>B7174-MPG</b>	<b>Lube</b> (2996416)..... <b>P7495</b>	<b>Lube</b> (99445200)..... <b>B7174-MPG</b>
<b>Fuel/Water Separator</b> (504086268)..... <b>BF1292-O</b>	<b>Fuel/Water Separator</b> (504086268)..... <b>BF1292-O</b>	<b>Fuel/Water Separator</b> (504086268)..... <b>BF1292-O</b>
<b>Fuel/Water Separator</b> (2992662)..... <b>BF1365</b>	<b>Fuel/Water Separator</b> (2992662)..... <b>BF1365</b>	<b>Fuel/Water Separator</b> (2992662)..... <b>BF1365</b>
<b>Radial Seal Air</b> (41272124)..... <b>RS5356</b>	<b>Radial Seal Air</b> (41272124)..... <b>RS5356</b>	<b>Fuel</b> (500315480)..... <b>BF7927</b>
<b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b>	<b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b>	<b>Radial Seal Air</b> (41272124)..... <b>RS5356</b>
<b>Air Dryer</b> (1907612)..... <b>BA5374 +</b>	<b>Air Dryer</b> (1907612)..... <b>BA5374 +</b>	<b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b>
<b>Breather</b> (500339085)..... <b>BT9408</b>	<b>Breather</b> (500339085)..... <b>BT9408</b>	<b>Air Dryer</b> (1907612)..... <b>BA5374 +</b>
<b>Steering</b> (100.8 mm) (1902137)... <b>P106-HD</b>	<b>Steering</b> (100.8 mm) (1902137)... <b>P106-HD</b>	<b>Breather</b> (500339085)..... <b>BT9408</b>
<b>Steering</b> (115.8 mm) (1267900)... <b>PT691</b>	<b>Steering</b> (115.8 mm) (1267900)... <b>PT691</b>	<b>Steering</b> (100.8 mm) (1902137)... <b>P106-HD</b>
<b>Urea</b> (denoxtronic 1) (42562233).. <b>PE5270</b>	<b>Urea</b> (denoxtronic 1) (42562233).. <b>PE5270</b>	<b>Steering</b> (115.8 mm) (1267900)... <b>PT691</b>
<b>Urea</b> (denoxtronic 2) (42555073).. <b>PE5271</b>	<b>Urea</b> (denoxtronic 2) (42555073).. <b>PE5271</b>	<b>Urea</b> (denoxtronic 1) (42562233).. <b>PE5270</b>
Strator 450 w/Cursor 10-450 Euro 5 / EEV Eng. (09/08-on)	Stralis (Active time) 460 w/Cursor 10-460 Eng. (07/11-on)	Urea (denoxtronic 2) (42555073).. <b>PE5271</b>
<b>Lube</b> (2996416)..... <b>P7495</b>	<b>Lube</b> (2996416)..... <b>P7495</b>	Trakker 480 w/Cursor 13 Eng. (09/04-on)
<b>Fuel/Water Separator</b> (504086268)..... <b>BF1292-O</b>	<b>Fuel/Water Separator</b> (504086268)..... <b>BF1292-O</b>	<b>Lube</b> ..... <b>B7174-MPG</b>
<b>Fuel/Water Separator</b> (2992662)..... <b>BF1365</b>	<b>Fuel/Water Separator</b> (2992662)..... <b>BF1365</b>	<b>Fuel/Water Separator</b> (1907539)..... <b>BF1217</b>
<b>Radial Seal Air</b> (2996126)..... <b>RS5356</b>	<b>Radial Seal Air</b> (41272124)..... <b>RS5356</b>	<b>Radial Seal Air</b> (41272124)..... <b>RS5356</b>
<b>Air Dryer</b> (1907612)..... <b>BA5374 +</b>	<b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b>	<b>Air</b> (Metal Hsg.)..... <b>PA3606</b>
<b>Breather</b> (500339085)..... <b>BT9408</b>	<b>Air Dryer</b> (1907612)..... <b>BA5374 +</b>	<b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b>
<b>Steering</b> (100.8 mm) (1902137)... <b>P106-HD</b>	<b>Breather</b> (500339085)..... <b>BT9408</b>	<b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b>
<b>Steering</b> (115.8 mm) (1267900)... <b>PT691</b>	<b>Steering</b> (100.8 mm) (1902137)... <b>P106-HD</b>	<b>Breather</b> (500339085)..... <b>BT9408</b>
<b>Urea</b> (denoxtronic 1) (42562233).. <b>PE5270</b>	<b>Steering</b> (115.8 mm) (1267900)... <b>PT691</b>	<b>Steering</b> ..... <b>P106-HD</b>
<b>Urea</b> (denoxtronic 2) (42555073).. <b>PE5271</b>	<b>Urea</b> (denoxtronic 1) (42562233).. <b>PE5270</b>	Stralis (Active space) 500 w/Cursor 13-500 Eng. (03/06-on)
Trakker 450 w/Cursor 13 (Euro 4/5) Eng. (03/06-on)	<b>Urea</b> (denoxtronic 2) (42555073).. <b>PE5271</b>	<b>Lube</b> (99445200)..... <b>B7174-MPG</b>
<b>Lube</b> ..... <b>B7174-MPG</b>	Stralis (Active space) 480 w/Cursor 13-480 Eng. (01/02-on)	<b>Fuel/Water Separator</b> (504086268)..... <b>BF1292-O</b>
<b>Lube</b> (2996416)..... <b>P7495</b>	<b>Lube</b> (99445200)..... <b>B7174-MPG</b>	<b>Fuel/Water Separator</b> (2992662)..... <b>BF1365</b>
<b>Fuel/Water Separator</b> (1907539)..... <b>BF1217</b>	<b>Fuel/Water Separator</b> (504086268)..... <b>BF1292-O</b>	<b>Radial Seal Air</b> (41272124)..... <b>RS5356</b>
<b>Radial Seal Air</b> (41272124)..... <b>RS5356</b>	<b>Fuel/Water Separator</b> (To 12/03) (1907539)..... <b>BF1217</b>	<b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b>
<b>Air</b> (Metal Hsg.)..... <b>PA3606</b>	<b>Fuel/Water Separator</b> (01/04-on) (2992662)..... <b>BF1365</b>	<b>Air Dryer</b> (1907612)..... <b>BA5374 +</b>
<b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b>	<b>Fuel</b> (500315480)..... <b>BF7927</b>	<b>Breather</b> (500339085)..... <b>BT9408</b>
<b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b>	<b>Radial Seal Air</b> (10/04-on) (41272124)..... <b>RS5356</b>	<b>Steering</b> (100.8 mm) (1902137)... <b>P106-HD</b>
<b>Breather</b> (500339085)..... <b>BT9408</b>	Stralis (Executive space) 500 w/Cursor 13-500 (F3B) Eng. (03/06-on)	<b>Steering</b> (115.8 mm) (1267900)... <b>PT691</b>
<b>Steering</b> ..... <b>P106-HD</b>	<b>Lube</b> (99445200)..... <b>B7174-MPG</b>	<b>Urea</b> (denoxtronic 1) (42562233).. <b>PE5270</b>
Z450T	<b>Fuel/Water Separator</b> (41272124)..... <b>RS5356</b>	<b>Urea</b> (denoxtronic 2) (42555073).. <b>PE5271</b>
<b>Dual-Flow Lube</b> (1902076)..... <b>BD232</b>		Stralis (Executive space) 500 w/Cursor 13-500 (F3B) Eng. (03/06-on)
<b>Fuel</b> ..... <b>[2] BF988 +</b>		<b>Lube</b> (99445200)..... <b>B7174-MPG</b>
<b>Air</b> (1902077)..... <b>PA2405</b>		<b>Fuel/Water Separator</b> (504086268)..... <b>BF1292-O</b>
		<b>Fuel/Water Separator</b> (2992662)..... <b>BF1365</b>
		<b>Radial Seal Air</b> (41272124)..... <b>RS5356</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IVECO Trucks (cont'd)	IVECO Trucks (cont'd)	IVECO Trucks (cont'd)
Stralis (Executive space) 500 w/Cursor 13-500 (F3B) Eng. (03/06-on) (Cont'd)	Stralis (Executive space) 540 w/Cursor 13 (F3B) Eng. (09/04-on)	Strator 560 w/Cursor 13-500 Euro 5 / EEV Eng. (09/08-on) (Cont'd)
<b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b>	<b>Lube</b> (99445200)..... <b>B7174-MPG</b>	<b>Urea</b> (denoxtronic 2) (42555073).. <b>PE5271</b>
<b>Air Dryer</b> (1907612)..... <b>BA5374 +</b>	<b>Fuel/Water Separator</b> (504086268)..... <b>BF1292-O</b>	615N
<b>Breather</b> (500339085)..... <b>BT9408</b>	<b>Fuel/Water Separator</b> (2992662)..... <b>BF1365</b>	<b>Lube Ele.</b> (4060883)..... <b>P40</b>
<b>Steering</b> (100.8 mm) (1902137)... <b>P106-HD</b>	<b>Fuel</b> (500315480)..... <b>BF7927</b>	<b>Fuel</b> (78809472)..... <b>PF906</b>
<b>Steering</b> (115.8 mm) (1267900)... <b>PT691</b>	<b>Radial Seal Air</b> (41272124)..... <b>RS5356</b>	615N1, 615N2 w/305, 305D Engs.
<b>Urea</b> (denoxtronic 1) (42562233).. <b>PE5270</b>	<b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b>	<b>Fuel</b> (78809472)..... <b>PF906</b>
<b>Urea</b> (denoxtronic 2) (42555073).. <b>PE5271</b>	<b>Air Dryer</b> (1907612)..... <b>BA5374 +</b>	616N, 616N1, 616NM
Strator 500 w/Cursor 13-500 Euro 5 / EEV Eng. (09/08-on)	<b>Breather</b> (500339085)..... <b>BT9408</b>	<b>Lube Ele.</b> (4585298)..... <b>P235</b>
<b>Lube</b> (2996416)..... <b>P7495</b>	<b>Steering</b> (100.8 mm) (1902137)... <b>P106-HD</b>	<b>Fuel Ele.</b> ..... <b>PF906</b>
<b>Fuel/Water Separator</b> (504086268)..... <b>BF1292-O</b>	<b>Steering</b> (115.8 mm) (1267900)... <b>PT691</b>	616N2, 616N2/4, 616N3, 616N3/4 w/803A Eng.
<b>Fuel/Water Separator</b> (2992662)..... <b>BF1365</b>	<b>Urea</b> (denoxtronic 1) (42562233).. <b>PE5270</b>	<b>Lube</b> (1901603)..... <b>BT347</b>
<b>Radial Seal Air</b> (2996126)..... <b>RS5356</b>	<b>Urea</b> (denoxtronic 2) (42555073).. <b>PE5271</b>	<b>Can-Type Fuel</b> ..... <b>BF825 +</b>
<b>Air Dryer</b> (1907612)..... <b>BA5374 +</b>	Stralis (Active space) 560 w/Cursor 13-560 Eng. (03/06-on)	619 w/CP3, CP3-42 Engs.
<b>Breather</b> (500339085)..... <b>BT9408</b>	<b>Lube</b> (99445200)..... <b>B7174-MPG</b>	<b>Air</b> ..... <b>PA1646-FN</b>
<b>Steering</b> (100.8 mm) (1902137)... <b>P106-HD</b>	<b>Fuel/Water Separator</b> (504086268)..... <b>BF1292-O</b>	619N, 619T1
<b>Steering</b> (115.8 mm) (1267900)... <b>PT691</b>	<b>Fuel/Water Separator</b> (2992662)..... <b>BF1365</b>	<b>Lube</b> (9/72-on) (78826586)..... <b>BT349</b>
<b>Urea</b> (denoxtronic 1) (42562233).. <b>PE5270</b>	<b>Radial Seal Air</b> (41272124)..... <b>RS5356</b>	619N, 619T
<b>Urea</b> (denoxtronic 2) (42555073).. <b>PE5271</b>	<b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b>	<b>Lube Ele.</b> (4596890)..... <b>P20-HD +</b>
Trakker 500 w/Cursor 13 (Euro 4/5) Eng. (03/06-on)	<b>Air Dryer</b> (1907612)..... <b>BA5374 +</b>	<b>Lube Spin-on</b> (1901603)..... <b>BT347</b>
<b>Lube</b> ..... <b>B7174-MPG</b>	<b>Breather</b> (500339085)..... <b>BT9408</b>	620, 620 Crvena Zastava
<b>Lube</b> (2996416)..... <b>P7495</b>	<b>Steering</b> (100.8 mm) (1902137)... <b>P106-HD</b>	<b>Lube</b> (1354828)..... <b>B2 +</b>
<b>Fuel/Water Separator</b> (1907539)..... <b>BF1217</b>	<b>Steering</b> (115.8 mm) (1267900)... <b>PT691</b>	<b>Lube</b> (Upgrade)..... <b>B2-HPG</b>
<b>Radial Seal Air</b> (41272124)..... <b>RS5356</b>	<b>Urea</b> (denoxtronic 1) (42562233).. <b>PE5270</b>	625N, 625NP w/230 Eng.
<b>Air</b> (Metal Hsg.)..... <b>PA3606</b>	<b>Urea</b> (denoxtronic 2) (42555073).. <b>PE5271</b>	<b>Lube</b> (4600875)..... <b>BT347</b>
<b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b>	Stralis (Executive space) 560 w/Cursor 13-560 (F3B) Eng. (03/06-on)	<b>Fuel Ele.</b> ..... <b>PF906</b>
<b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b>	<b>Lube</b> (99445200)..... <b>B7174-MPG</b>	625N2, 625N3 w/804A, 8040.02 Engs.
<b>Breather</b> (500339085)..... <b>BT9408</b>	<b>Fuel/Water Separator</b> (504086268)..... <b>BF1292-O</b>	<b>Lube</b> (4600875)..... <b>BT347</b>
<b>Steering</b> ..... <b>P106-HD</b>	<b>Fuel/Water Separator</b> (2992662)..... <b>BF1365</b>	<b>Can-Type Fuel</b> (74651986)..... <b>BF825 +</b>
506-00, 506-12 Army Trucks	<b>Radial Seal Air</b> (41272124)..... <b>RS5356</b>	635N w/230 Eng.
<b>Lube</b> (2171900)..... <b>PT48</b>	<b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b>	<b>Lube</b> (4600875)..... <b>BT347</b>
Stralis (Active space) 540 w/Cursor 13-540 Eng. (01/02-on)	<b>Air Dryer</b> (1907612)..... <b>BA5374 +</b>	<b>Fuel Ele.</b> ..... <b>PF906</b>
<b>Lube</b> (99445200)..... <b>B7174-MPG</b>	<b>Breather</b> (500339085)..... <b>BT9408</b>	639N2, 639N3, 640N
<b>Fuel/Water Separator</b> (504086268)..... <b>BF1292-O</b>	<b>Steering</b> (100.8 mm) (1902137)... <b>P106-HD</b>	<b>Lube Ele.</b> (4596890)..... <b>P20-HD +</b>
<b>Fuel/Water Separator</b> (To 12/03) (1907539)..... <b>BF1217</b>	<b>Steering</b> (115.8 mm) (1267900)... <b>PT691</b>	642N, 642N2, 642N5, 642N5R, 642N6, 642N6R, 642N65R, 642N65T, 642N65T2, 642N65T6, 642N65T65
<b>Fuel/Water Separator</b> (01/04-on) (2992662)..... <b>BF1365</b>	<b>Urea</b> (denoxtronic 1) (42562233).. <b>PE5270</b>	<b>Lube Ele.</b> (4596890)..... <b>P20-HD +</b>
<b>Fuel</b> (500315480)..... <b>BF7927</b>	<b>Urea</b> (denoxtronic 2) (42555073).. <b>PE5271</b>	643E, 643EP, 643N, 643N1, 643T, 643T1 w/220 Eng.
<b>Radial Seal Air</b> (10/04-on) (41272124)..... <b>RS5356</b>	Strator 560 w/Cursor 13-500 Euro 5 / EEV Eng. (09/08-on)	<b>Lube Ele.</b> (4596890)..... <b>P20-HD +</b>
<b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b>	<b>Lube</b> (2996416)..... <b>P7495</b>	<b>Fuel</b> (1909103)..... <b>BF783</b>
<b>Air Dryer</b> (1907612)..... <b>BA5374 +</b>	<b>Fuel/Water Separator</b> (504086268)..... <b>BF1292-O</b>	<b>Air</b> (73047497)..... <b>PA1646-FN</b>
<b>Breather</b> (500339085)..... <b>BT9408</b>	<b>Fuel/Water Separator</b> (2992662)..... <b>BF1365</b>	645N, 650E, 650N
<b>Steering</b> (100.8 mm) (1902137)... <b>P106-HD</b>	<b>Radial Seal Air</b> (2996126)..... <b>RS5356</b>	<b>Lube Ele.</b> (4585298)..... <b>P235</b>
<b>Steering</b> (115.8 mm) (1267900)... <b>PT691</b>	<b>Air Dryer</b> (1907612)..... <b>BA5374 +</b>	<b>Fuel Ele.</b> (970269)..... <b>PF906</b>
<b>Urea</b> (denoxtronic 1) (42562233).. <b>PE5270</b>	<b>Breather</b> (500339085)..... <b>BT9408</b>	645N1, 645N2, 645N3, 650E1, 650N1, 650N2, 650N3 w/806A, 8060.02 Engs.
<b>Urea</b> (denoxtronic 2) (42555073).. <b>PE5271</b>	<b>Steering</b> (100.8 mm) (1902137)... <b>P106-HD</b>	<b>Fuel Ele.</b> ..... <b>PF906</b>
	<b>Steering</b> (115.8 mm) (1267900)... <b>PT691</b>	<b>Can-Type Fuel</b> (74651986)..... <b>BF825 +</b>
	<b>Urea</b> (denoxtronic 1) (42562233).. <b>PE5270</b>	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IVECO Trucks (cont'd)	IVECO Trucks (cont'd)	IVECO Trucks (cont'd)
650N1A, 650N1B, 650N3 w/8060.82 Eng. Can-Type Fuel (4621740)..... <b>BF825 +</b> Air..... <b>PA2358</b>	692N Lube Ele. (4596890)..... <b>P20-HD +</b>	EuroTrakker 720 E 44 w/Cursor13 Eng. (01/01-11/04) (Cont'd) Steering (1902137)..... <b>P106-HD</b>
655N, 655N2 w/806A, 8060.02 Eng. Fuel Ele..... <b>PF906</b> Can-Type Fuel (74651986)..... <b>BF825 +</b>	693N, 693N1, 693N2, 693T, 693T1 Lube Ele. (4596890)..... <b>P20-HD +</b> Fuel (1909103)..... <b>BF783</b>	EuroTrakker 720 E 47 w/8210.42M (TCA) Eng. (01/00-11/04) Dual-Flow Lube (1903715)..... <b>BD325</b> Fuel/Water Separator (1907539)..... <b>BF1217</b> Fuel (1904640)..... <b>BF7663</b> Air (2991793)..... <b>PA3606</b> Air Dryer (1907612)..... <b>BA5374 +</b> Coolant (1901776)..... <b>BW5143</b> Steering (1902137)..... <b>P106-HD</b>
662N Lube Ele. (4585298)..... <b>P235</b> Fuel Ele. (970269)..... <b>PF906</b>	697 (6x4), 697T (6x4) Lube (1972-on) (78826586)..... <b>BT349</b>	EuroTrakker 720E48 w/Cursor13 Eng. (01/01-11/04) Lube..... <b>B7174-MPG</b> Fuel/Water Separator (1907539)..... <b>BF1217</b> 465.9 mm O. Air (41272211)..... <b>PA5364</b> 461.2 mm I. Air (41214149)..... <b>PA5365</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Breather (500339085)..... <b>BT9408</b> Trans..... <b>PT8385</b> Steering..... <b>P106-HD</b>
662N1, 662N2 w/806A, 8060.02 Eng. Fuel Ele..... <b>PF906</b> Can-Type Fuel..... <b>BF825 +</b>	697N, 697NP, 697NP-U, 697NPG-T w/8200.02 Eng. Lube Ele. (To 1972) (4596890).... <b>P20-HD +</b> Lube Spin-on (1972-on) (4667339)..... <b>BT349</b> Fuel (4671001)..... <b>BF783</b> Air..... <b>PA1884 +</b>	Jupiter 3500 w/Deutz F6L614, F6L714 Eng. Lube (1168469)..... <b>P42</b> P. Fuel Ele. (1168407)..... <b>F950-F</b> S. Fuel Ele. (1168398)..... <b>PF950</b>
662N2P, 662N3, 662N3P w/8060.82 Eng. Can-Type Fuel (4621740)..... <b>BF825 +</b> Air..... <b>PA2358</b>	697 w/CP3, CP3-42 Eng. Air..... <b>PA1646-FN</b>	Mercur A.S3500, S3500 w/Deutz F4L514 Eng. Lube Ele. (To 1967) (1168465).... <b>P41</b> Lube Spin-on (1967-on) (1160025)..... <b>B236 +</b> Fuel Ele. (1168398)..... <b>PF950</b> Fuel Spin-on (1160243)..... <b>BF988 +</b>
671N2, 671N3 Lube (4596890)..... <b>P20-HD +</b>	EuroTrakker 720 E 37 w/8210.42K(TCA) Eng. (09/93-11/04) Dual-Flow Lube (1903715)..... <b>BD325</b> Fuel/Water Separator (1907539)..... <b>BF1217</b> Fuel (1904640)..... <b>BF7663</b> O. Air (1904550)..... <b>PA2776</b> I. Air (1905620)..... <b>PA3494</b> Air Dryer (1907612)..... <b>BA5374 +</b> Coolant (1901776)..... <b>BW5143</b> Steering (1902137)..... <b>P106-HD</b>	Pluto.S4500 w/Deutz F4L514 Eng. Lube Ele. (To 1967) (1168465).... <b>P41</b> Lube Spin-on (1967-on) (1160025)..... <b>B236 +</b> Fuel Ele..... <b>PF950</b> Fuel Spin-on..... <b>BF988 +</b>
672N w/8060.82 Eng. Can-Type Fuel (4621740)..... <b>BF825 +</b> Air..... <b>PA2358</b>	EuroTrakker 720 E 38 w/Cursor13 Eng. (01/01-11/04) Lube (99445200)..... <b>B7174-MPG</b> Fuel/Water Separator (1907539)..... <b>BF1217</b> Fuel (500315480)..... <b>BF7927</b> O. Air (2992374)..... <b>PA5364</b> I. Air (41214149)..... <b>PA5365</b> Air Dryer (1907612)..... <b>BA5374 +</b> Breather (500339085)..... <b>BT9408</b> Trans. (42491185)..... <b>PT8385</b> Steering (1902137)..... <b>P106-HD</b>	Mercur A5500 w/Deutz F6L614, F6L714 Eng. Lube Ele. (1168469)..... <b>P42</b> P. Fuel Ele. (1168407)..... <b>F950-F</b> S. Fuel Ele. (1168398)..... <b>PF950</b>
672N w/806A, 8060.02 Eng. Fuel Ele..... <b>PF906</b> Can-Type Fuel..... <b>BF825 +</b>	EuroTrakker 720 E 42 w/8210.42L(TCA) Eng. (09/93-11/04) Dual-Flow Lube (1903715)..... <b>BD325</b> Fuel/Water Separator (1907539)..... <b>BF1217</b> Fuel (1904640)..... <b>BF7663</b> O. Air (1904550)..... <b>PA2776</b> I. Air (1905620)..... <b>PA3494</b> Air Dryer (1907612)..... <b>BA5374 +</b> Coolant (1901776)..... <b>BW5143</b> Steering (1902137)..... <b>P106-HD</b>	A6500 w/Deutz F8L714 Eng. P. Fuel Ele. (1168407)..... <b>F950-F</b> S. Fuel Ele. (1168398)..... <b>PF950</b>
673N, 673N3, 673NR 673T3 w/CP3 Eng. Lube Ele. (4596890)..... <b>P20-HD +</b> Lube Spin-on (4667339)..... <b>BT349</b>	EuroTrakker 720 E 44 w/Cursor13 Eng. (01/01-11/04) Lube (99445200)..... <b>B7174-MPG</b> Fuel/Water Separator (1907539)..... <b>BF1217</b> Fuel (500315480)..... <b>BF7927</b> O. Air (2992374)..... <b>PA5364</b> I. Air (41214149)..... <b>PA5365</b> Air Dryer (1907612)..... <b>BA5374 +</b> Breather (500339085)..... <b>BT9408</b> Trans. (42491185)..... <b>PT8385</b>	S6500 w/Deutz F8L714 Eng. P. Fuel Ele. (1168407)..... <b>F950-F</b> S. Fuel Ele. (1168398)..... <b>PF950</b>
682N3, 682N4, 682T3, 682T4, 683N, 683N3, 683T1, 683T3 Lube (4596890)..... <b>P20-HD +</b>	EuroTrakker 720 E 44 w/Cursor13 Eng. (01/01-11/04) Lube (99445200)..... <b>B7174-MPG</b> Fuel/Water Separator (1907539)..... <b>BF1217</b> Fuel (500315480)..... <b>BF7927</b> O. Air (2992374)..... <b>PA5364</b> I. Air (41214149)..... <b>PA5365</b> Air Dryer (1907612)..... <b>BA5374 +</b> Breather (500339085)..... <b>BT9408</b> Trans. (42491185)..... <b>PT8385</b>	Nato A6500 w/Deutz F8L614 Eng. Lube Ele. (1168469)..... <b>P42</b> P. Fuel Ele. (1168407)..... <b>F950-F</b> S. Fuel Ele. (1168398)..... <b>PF950</b>
684N, 684NP, 684T, 684TP w/8200.02 Eng. Lube Ele. (4596890)..... <b>P20-HD +</b> Lube Spin-on (4667339)..... <b>BT349</b> Fuel (1909103)..... <b>BF783</b>	690/4, 690N4 w/8200.02 Eng. Lube Ele. (4596890)..... <b>P20-HD +</b> Lube Spin-on (4667339)..... <b>BT349</b> Fuel (1909103)..... <b>BF783</b>	190.24 w/8220.22 Eng. Lube (4667339)..... <b>BT349</b> Fuel (1901605)..... <b>BF783</b>
687NP w/8200.02 Eng. Lube Ele. (To 1972) (4596890).... <b>P20-HD +</b> Lube Spin-on (1972-on) (4667339)..... <b>BT349</b> Fuel (4671001)..... <b>BF783</b> Air..... <b>PA1884 +</b>	690N1, 690N2, 690N3, 690T1, 690T2, 690T3 Lube Ele. (4596890)..... <b>P20-HD +</b>	
691, 691N, 691T, 691TS w/8200.02 Eng. Lube Ele. (To 1972) (4596890).... <b>P20-HD +</b> Lube Spin-on (1972-on) (4667339)..... <b>BT349</b> Fuel (4671001)..... <b>BF783</b> Air..... <b>PA1884 +</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).


IVECO Trucks (cont'd)	IVECO Trucks (cont'd)	IVECO Trucks (cont'd)
190.24 TRU (1988), 190.24 TurboTech (1990)	Stralis Active Time AT190S43FP-CT w/Cursor 10-430 Eng. (06/03-on)	Stralis 330 w/Cursor 9 Eng. (2013-on) (Cont'd)
Dual-Flow Lube (1907584)..... <b>BD325</b>	Lube..... <b>B7174-MPG</b>	Steering (1902137)..... <b>P106-HD</b>
Fuel (1901605)..... <b>BF783</b>	Fuel/Water Separator	Urea (42555073)..... <b>PE5271</b>
Air (1904550)..... <b>PA2776</b>	(6/03-12/03) (1907539)..... <b>BF1217</b>	Stralis 360 w/Cursor 9 Eng. (2013-on)
Coolant (1901776)..... <b>BW5143</b>	Fuel/Water Separator	Lube (504179764)..... <b>P40031-MPG</b>
EuroTech w/Cursor Eng.	(1/2004-on)..... <b>BF1365</b>	Fuel/Water Separator
Fuel (2991585)..... <b>BF7696</b>	Radial Seal Air (10/04-on)	(42554067)..... <b>BF1391-O</b>
Orione	(41272124)..... <b>RS5356</b>	Fuel (5801439820)..... <b>PF46003</b>
Lube (4951092)..... <b>BT347</b>	Cab Air (w/o Carbon)	Radial Seal Air (41272124)..... <b>RS5356</b>
Super Orione, S.Tigre, Tigre, Tigre Aus, Tigre P	(504024890)..... <b>PA5336</b>	Cab Air (w/o Carbon)
Lube Ele..... <b>P42</b>	Air Dryer (Mann TB1374X)..... <b>BA5374 +</b>	(504024890)..... <b>PA5336</b>
Steering..... <b>P106</b>	Breather (06/03-09/04)	Air Dryer (1907612)..... <b>BA5374 +</b>
Satur w/Deutz F6L614, F6L714 Engs.	(500339085)..... <b>BT9408</b>	Air Dryer (5801382289)..... <b>BA5379</b>
Lube Ele. (1168469)..... <b>P42</b>	Trans. (5000807213)..... <b>PT8385</b>	Trans. (42491185)..... <b>PT8385</b>
P. Fuel Ele. (1168407)..... <b>F950-F</b>	Steering..... <b>P106-HD</b>	Steering (1902137)..... <b>P106-HD</b>
S. Fuel Ele. (1168398)..... <b>PF950</b>	Stralis 300 w/C78 ENT CNG eng. (01/13-on)	Urea (42555073)..... <b>PE5271</b>
Sirus L.K.K.L.S/A 4500 w/Deutz F4L514 Eng.	Lube (99445200)..... <b>B7174-MPG</b>	Stralis 400 w/Cursor 9 Eng. (2013-on)
Lube Ele. (To 1967) (1168465).... <b>P41</b>	Radial Seal Air (41272124)..... <b>RS5356</b>	Lube (504179764)..... <b>P40031-MPG</b>
Lube Spin-on (1967-on)	Cab Air (w/o Carbon)	Fuel/Water Separator
(1160025)..... <b>B236 +</b>	(504024890)..... <b>PA5336</b>	(42554067)..... <b>BF1391-O</b>
Fuel Ele. (1168398)..... <b>PF950</b>	Air Dryer (1907612)..... <b>BA5374 +</b>	Fuel (5801439820)..... <b>PF46003</b>
Fuel Spin-on (1160243)..... <b>BF988 +</b>	Air Dryer (5801382289)..... <b>BA5379</b>	Radial Seal Air (41272124)..... <b>RS5356</b>
Super Jolly	Trans. (42491185)..... <b>PT8385</b>	Cab Air (w/o Carbon)
Lube (2323108)..... <b>PT29</b>	Steering (1902137)..... <b>P106-HD</b>	(504024890)..... <b>PA5336</b>
Tigrotto 50.45L1.55.65C	Stralis 310 w/Cursor 9 Eng. (2013-on)	Air Dryer (1907612)..... <b>BA5374 +</b>
Lube (4951092)..... <b>BT347</b>	Lube (504179764)..... <b>P40031-MPG</b>	Air Dryer (5801382289)..... <b>BA5379</b>
Tigrotto 50.55.65C	Fuel/Water Separator	Trans. (42491185)..... <b>PT8385</b>
Lube..... <b>B50 +</b>	(42554067)..... <b>BF1391-O</b>	Steering (1902137)..... <b>P106-HD</b>
Fuel..... <b>PF906</b>	Fuel (5801439820)..... <b>PF46003</b>	Urea (42555073)..... <b>PE5271</b>
Tigrotto 50.55.M4.R54	Radial Seal Air (41272124)..... <b>RS5356</b>	Stralis 410 w/Cursor 13 Eng. (01/13-on)
Lube (To 1968)..... <b>P80</b>	Cab Air (w/o Carbon)	Lube (504179764)..... <b>P40031-MPG</b>
Lube (To 1968)..... <b>P80-HD</b>	(504024890)..... <b>PA5336</b>	Fuel/Water Separator
Tigrotto 55M5, 55M5L	Air Dryer (1907612)..... <b>BA5374 +</b>	(42554067)..... <b>BF1391-O</b>
Fuel..... <b>PF906</b>	Air Dryer (5801382289)..... <b>BA5379</b>	Radial Seal Air
Tigrotto A15.35N, Tigrotto A15.35S, Lupetto A15	Trans. (42491185)..... <b>PT8385</b>	(Hi-Road/Hi-Street) (41272124).... <b>RS5356</b>
(4x4), A15L, CA15L (3000, 3665), Leoncino	Steering (1902137)..... <b>P106-HD</b>	Cab Air (w/o Carbon)
Lube (4951092)..... <b>BT347</b>	Urea (42555073)..... <b>PE5271</b>	(504024890)..... <b>PA5336</b>
Fuel..... <b>BF7593</b>	Stralis 330 w/C78 ENT CNG eng. (01/13-on)	Air Dryer (1907612)..... <b>BA5374 +</b>
Tigrotto M3K (4x4) w/OM C03 VAR. 1 OR.VAR.	Lube (99445200)..... <b>B7174-MPG</b>	Air Dryer (5801382289)..... <b>BA5379</b>
2 Engs.	Radial Seal Air (41272124)..... <b>RS5356</b>	Trans. (42491185)..... <b>PT8385</b>
Lube..... <b>BT347</b>	Cab Air (w/o Carbon)	Steering (1902137)..... <b>P106-HD</b>
Titano 62DG	(504024890)..... <b>PA5336</b>	Urea (42555073)..... <b>PE5271</b>
Lube..... <b>P20-HD +</b>	Air Dryer (1907612)..... <b>BA5374 +</b>	Stralis 420 w/Cursor 11 Eng. (01/13-on)
Steering..... <b>P106</b>	Air Dryer (5801382289)..... <b>BA5379</b>	Lube (504179764)..... <b>P40031-MPG</b>
Titano DG1L, Tigre DF1L	Trans. (42491185)..... <b>PT8385</b>	Fuel/Water Separator
Lube..... <b>P20-HD +</b>	Steering (1902137)..... <b>P106-HD</b>	(42554067)..... <b>BF1391-O</b>
Troaro 270	Stralis 330 w/Cursor 9 Eng. (2013-on)	Radial Seal Air
Fuel..... <b>BF797</b>	Lube (504179764)..... <b>P40031-MPG</b>	(Hi-Road/Hi-Street) (41272124).... <b>RS5356</b>
Uranus.KW15 w/Deutz F6L712 Eng.	Fuel/Water Separator	Cab Air (w/o Carbon)
Lube Ele. (1168469)..... <b>P42</b>	(42554067)..... <b>BF1391-O</b>	(504024890)..... <b>PA5336</b>
Fuel Ele. (1168407)..... <b>F950-F</b>	Fuel (5801439820)..... <b>PF46003</b>	Air Dryer (1907612)..... <b>BA5374 +</b>
Hyd. (1267900)..... <b>PT691</b>	Radial Seal Air (41272124)..... <b>RS5356</b>	Air Dryer (5801382289)..... <b>BA5379</b>
	Cab Air (w/o Carbon)	Trans. (42491185)..... <b>PT8385</b>
	(504024890)..... <b>PA5336</b>	Steering (1902137)..... <b>P106-HD</b>
	Air Dryer (1907612)..... <b>BA5374 +</b>	Urea (42555073)..... <b>PE5271</b>
	Air Dryer (5801382289)..... <b>BA5379</b>	
	Trans. (42491185)..... <b>PT8385</b>	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IVECO Trucks (cont'd)	IVECO Trucks (cont'd)	IVECO Trucks (cont'd)
<b>Stralis 450 w/Cursor 13 Eng. (01/13-on)</b> <b>Lube</b> (504179764)..... <b>P40031-MPG</b> <b>Fuel/Water Separator</b> (42554067)..... <b>BF1391-O</b> <b>Radial Seal Air</b> (Hi-Road/Hi-Street) (41272124).... <b>RS5356</b> <b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b> <b>Air Dryer</b> (1907612)..... <b>BA5374 +</b> <b>Air Dryer</b> (5801382289)..... <b>BA5379</b> <b>Trans.</b> (42491185)..... <b>PT8385</b> <b>Steering</b> (1902137)..... <b>P106-HD</b> <b>Urea</b> (42555073)..... <b>PE5271</b>	<b>Trakker 330 w/Cursor 9 Eng. (2013-on) (Cont'd)</b> <b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b> <b>Air Dryer</b> (1907612)..... <b>BA5374 +</b> <b>Air Dryer</b> (5801382289)..... <b>BA5379</b> <b>Trans.</b> (42491185)..... <b>PT8385</b> <b>Steering</b> (1902137)..... <b>P106-HD</b> <b>Urea</b> (42555073)..... <b>PE5271</b>	<b>Stralis 310 HP w/Cursor 9 Eng. (Euro 6)</b> <b>Fuel/Water Separator</b> (5801620130)..... <b>BF1391-O</b> <b>Fuel</b> (5801439820)..... <b>PF46003</b> <b>Radial Seal O. Air</b> (Optional) (5801313604)..... <b>RS5356</b> <b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b> <b>Air Dryer</b> (2992261)..... <b>BA5374 +</b> <b>Steering</b> (2966261)..... <b>P106-HD</b> <b>Urea</b> (5801667204)..... <b>PE17000</b>
<b>Stralis 460 w/Cursor 11 Eng. (01/13-on)</b> <b>Lube</b> (504179764)..... <b>P40031-MPG</b> <b>Fuel/Water Separator</b> (42554067)..... <b>BF1391-O</b> <b>Radial Seal Air</b> (Hi-Road/Hi-Street) (41272124).... <b>RS5356</b> <b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b> <b>Air Dryer</b> (1907612)..... <b>BA5374 +</b> <b>Air Dryer</b> (5801382289)..... <b>BA5379</b> <b>Trans.</b> (42491185)..... <b>PT8385</b> <b>Steering</b> (1902137)..... <b>P106-HD</b> <b>Urea</b> (42555073)..... <b>PE5271</b>	<b>Trakker 360 w/Cursor 9 Eng. (2013-on)</b> <b>Lube</b> (504179764)..... <b>P40031-MPG</b> <b>Fuel/Water Separator</b> (42554067)..... <b>BF1391-O</b> <b>Fuel</b> (5801439820)..... <b>PF46003</b> <b>Radial Seal Air</b> (41272124)..... <b>RS5356</b> <b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b> <b>Air Dryer</b> (1907612)..... <b>BA5374 +</b> <b>Air Dryer</b> (5801382289)..... <b>BA5379</b> <b>Trans.</b> (42491185)..... <b>PT8385</b> <b>Steering</b> (1902137)..... <b>P106-HD</b> <b>Urea</b> (42555073)..... <b>PE5271</b>	<b>Stralis, XP 570 HP w/Cursor 13 Eng. (Euro 6)</b> <b>Fuel/Water Separator</b> (5801620130)..... <b>BF1391-O</b> <b>Radial Seal O. Air</b> (Optional) (5801313604)..... <b>RS5356</b> <b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b> <b>Air Dryer</b> (2992261)..... <b>BA5374 +</b> <b>Steering</b> (2966261)..... <b>P106-HD</b> <b>Urea</b> (5801667204)..... <b>PE17000</b>
<b>Stralis 480 w/Cursor 11 Eng. (01/13-on)</b> <b>Lube</b> (504179764)..... <b>P40031-MPG</b> <b>Fuel/Water Separator</b> (42554067)..... <b>BF1391-O</b> <b>Radial Seal Air</b> (Hi-Road/Hi-Street) (41272124).... <b>RS5356</b> <b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b> <b>Air Dryer</b> (1907612)..... <b>BA5374 +</b> <b>Air Dryer</b> (5801382289)..... <b>BA5379</b> <b>Trans.</b> (42491185)..... <b>PT8385</b> <b>Steering</b> (1902137)..... <b>P106-HD</b> <b>Urea</b> (42555073)..... <b>PE5271</b>	<b>Stralis 400 HP w/Cursor 9 Eng. (Euro 6)</b> <b>Fuel/Water Separator</b> (5801620130)..... <b>BF1391-O</b> <b>Fuel</b> (5801439820)..... <b>PF46003</b> <b>Radial Seal O. Air</b> (Optional) (5801313604)..... <b>RS5356</b> <b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b> <b>Air Dryer</b> (2992261)..... <b>BA5374 +</b> <b>Steering</b> (2966261)..... <b>P106-HD</b> <b>Urea</b> (5801667204)..... <b>PE17000</b>	<b>Stralis, XP 510 HP w/Cursor 13 Eng. (Euro 6)</b> <b>Fuel/Water Separator</b> (5801620130)..... <b>BF1391-O</b> <b>Radial Seal O. Air</b> (Optional) (5801313604)..... <b>RS5356</b> <b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b> <b>Air Dryer</b> (2992261)..... <b>BA5374 +</b> <b>Steering</b> (2966261)..... <b>P106-HD</b> <b>Urea</b> (5801667204)..... <b>PE17000</b>
<b>Trakker 310 w/Cursor 9 Eng. (2013-on)</b> <b>Lube</b> (504179764)..... <b>P40031-MPG</b> <b>Fuel/Water Separator</b> (42554067)..... <b>BF1391-O</b> <b>Fuel</b> (5801439820)..... <b>PF46003</b> <b>Radial Seal Air</b> (41272124)..... <b>RS5356</b> <b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b> <b>Air Dryer</b> (1907612)..... <b>BA5374 +</b> <b>Air Dryer</b> (5801382289)..... <b>BA5379</b> <b>Trans.</b> (42491185)..... <b>PT8385</b> <b>Steering</b> (1902137)..... <b>P106-HD</b> <b>Urea</b> (42555073)..... <b>PE5271</b>	<b>Stralis 360 HP w/Cursor 9 Eng. (Euro 6)</b> <b>Fuel/Water Separator</b> (5801620130)..... <b>BF1391-O</b> <b>Fuel</b> (5801439820)..... <b>PF46003</b> <b>Radial Seal O. Air</b> (Optional) (5801313604)..... <b>RS5356</b> <b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b> <b>Air Dryer</b> (2992261)..... <b>BA5374 +</b> <b>Steering</b> (2966261)..... <b>P106-HD</b> <b>Urea</b> (5801667204)..... <b>PE17000</b>	<b>Stralis, XP 480 HP w/Cursor 11 Eng. (Euro 6)</b> <b>Fuel/Water Separator</b> (5801620130)..... <b>BF1391-O</b> <b>Radial Seal O. Air</b> (Optional) (5801313604)..... <b>RS5356</b> <b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b> <b>Air Dryer</b> (2992261)..... <b>BA5374 +</b> <b>Steering</b> (2966261)..... <b>P106-HD</b> <b>Urea</b> (5801667204)..... <b>PE17000</b>
<b>Trakker 330 w/Cursor 9 Eng. (2013-on)</b> <b>Lube</b> (504179764)..... <b>P40031-MPG</b> <b>Fuel/Water Separator</b> (42554067)..... <b>BF1391-O</b> <b>Fuel</b> (5801439820)..... <b>PF46003</b> <b>Radial Seal Air</b> (41272124)..... <b>RS5356</b> <b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b> <b>Air Dryer</b> (1907612)..... <b>BA5374 +</b> <b>Air Dryer</b> (5801382289)..... <b>BA5379</b> <b>Trans.</b> (42491185)..... <b>PT8385</b> <b>Steering</b> (1902137)..... <b>P106-HD</b> <b>Urea</b> (42555073)..... <b>PE5271</b>	<b>Stralis 330 HP w/Cursor 9 Eng. (Euro 6)</b> <b>Fuel/Water Separator</b> (5801620130)..... <b>BF1391-O</b> <b>Fuel</b> (5801439820)..... <b>PF46003</b> <b>Radial Seal O. Air</b> (Optional) (5801313604)..... <b>RS5356</b> <b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b> <b>Air Dryer</b> (2992261)..... <b>BA5374 +</b> <b>Steering</b> (2966261)..... <b>P106-HD</b> <b>Urea</b> (5801667204)..... <b>PE17000</b>	<b>Stralis, XP 460 HP w/Cursor 11 Eng. (Euro 6)</b> <b>Fuel/Water Separator</b> (5801620130)..... <b>BF1391-O</b> <b>Radial Seal O. Air</b> (Optional) (5801313604)..... <b>RS5356</b> <b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b> <b>Air Dryer</b> (2992261)..... <b>BA5374 +</b> <b>Steering</b> (2966261)..... <b>P106-HD</b> <b>Urea</b> (5801667204)..... <b>PE17000</b>
<b>Trakker 330 w/Cursor 9 Eng. (2013-on)</b> <b>Lube</b> (504179764)..... <b>P40031-MPG</b> <b>Fuel/Water Separator</b> (42554067)..... <b>BF1391-O</b> <b>Fuel</b> (5801439820)..... <b>PF46003</b> <b>Radial Seal Air</b> (41272124)..... <b>RS5356</b>	<b>Stralis 330 HP w/Cursor 9 Eng. (Euro 6)</b> <b>Fuel/Water Separator</b> (5801620130)..... <b>BF1391-O</b> <b>Radial Seal O. Air</b> (Optional) (5801313604)..... <b>RS5356</b> <b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b> <b>Air Dryer</b> (2992261)..... <b>BA5374 +</b> <b>Steering</b> (2966261)..... <b>P106-HD</b> <b>Urea</b> (5801667204)..... <b>PE17000</b>	<b>Stralis, XP 420 HP w/Cursor 11 Eng. (Euro 6)</b> <b>Fuel/Water Separator</b> (5801620130)..... <b>BF1391-O</b> <b>Radial Seal O. Air</b> (Optional) (5801313604)..... <b>RS5356</b> <b>Cab Air</b> (w/o Carbon) (504024890)..... <b>PA5336</b>

+ See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

IVECO Trucks (cont'd)	KASSBOHRER Buses (cont'd)	KASSBOHRER Buses (cont'd)
Stralis, XP 420 HP w/Cursor 11 Eng. (Euro 6) (Cont'd)	S110, S110 A w/Henschel S62-6R1112-18K Eng. (Cont'd)	S208 H w/Mercedes-Benz OM352 Eng.
Air Dryer (2992261)..... BA5374 +	Air (Mann C21317)..... PA1636-FN	Lube (Mann H1282x)..... P721
Steering (2966261)..... P106-HD	Steering (Mann P919/7)..... PT691	Fuel (Mann BFU700x)..... F834-F
Urea (5801667204)..... PE17000		Air (Mann C20325/2)..... PA2405
Stralis NP 400 HP w/Cursor 9 CNG Eng. (Euro 6)	S120, S130 w/Henschel 6-6R1113-18K Eng.	S209 w/Mercedes-Benz OM401 Eng.
Cab Air (w/o Carbon) (504024890)..... PA5336	Lube (Mann W962)..... B236 +	Lube (Mann H1275x)..... P242
Air Dryer (2992261)..... BA5374 +	Fuel (Mann WK731)..... BF988 +	Fuel (Mann P707)..... PF834
Steering (2966261)..... P106-HD	Air (Mann C20325)..... PA2866	Air (Mann C20325/2)..... PA2405
Urea (5801667204)..... PE17000	Air (Mann C21317)..... PA1636-FN	
	Steering (Mann P919/7)..... PT691	S209 H w/Mercedes-Benz OM421 Eng.
<b>JAC MOTORS</b>	S120, S120 A, S130 w/Henschel 524-6R1315-20K Eng.	Lube (Mann H1275x)..... P242
<b>Trucks</b>	Lube (Mann W962)..... B236 +	Fuel (Mann BFU700x)..... F834-F
N721 w/Cummins ISF3.8 Eng.	Fuel (Mann WK731)..... BF988 +	Some Fuel (Mann BFU900x)..... F950-F
Lube (5262313)..... B40050	Air (Mann C23440)..... PA2847	Air (Mann C23440/1)..... PA2474
	Air (Mann C24516)..... PA1646-FN	
	Steering (Mann P919/7)..... PT691	S210 H w/Mercedes-Benz OM421 Eng.
<b>JOHN DEERE</b>	S130 S w/M.A.N. D2566 Eng.	Lube (To Eng. S/N 019114) (Mann H1275x)..... P242
<b>Motorhome Chassis</b>	Lube..... P294	Lube (Eng. S/N 019114-up, 9/85-on) (Mann H12110/2x)..... P294
Motorhome Chassis w/Ford 7.5L Eng.	Fuel (Mann P707)..... PF834	Fuel (Mann BFU900x)..... F950-F
Lube..... B2 +	Air (Mann C23440/1)..... PA2474	Air (Mann C23440/1)..... PA2474
Fuel SintBronze..... SF898	Steering (Mann P919/7)..... PT691	Air (Mann C24650/1)..... PA2475
Fuel Spin-on..... BF966		
	S140 ES w/M.A.N. D2566 Eng.	S210 H w/Mercedes-Benz OM441 Eng.
<b>KARRIER</b>	Lube..... P294	Lube (Mann HU947/1x)..... P7015
<b>Trucks</b>	Fuel (Mann P707)..... PF834	Fuel (Mann BFU700x)..... F834-F
Bantam MK V w/4 Cyl. Diesel Eng.	Air (Mann C23440/1)..... PA2474	Air (Mann C24650/1)..... PA2475
Lube..... P174	Steering (Mann P919/7)..... PT691	Air Dryer (Mann TB1374x)..... BA5374 +
Fuel Ele..... PF838		Steering (Mann H601/4)..... P106-HD
Gamecock w/Perkins C305 Diesel Eng.	S140 ES w/Mercedes-Benz OM407 Eng.	S211 H w/Mercedes-Benz OM401 Eng.
Lube (To S/N 3401030)..... PT12	Lube..... P294	Lube (Mann H1275x)..... P242
Lube (S/N 3401030-up)..... P15	Fuel (Mann BFU900x)..... F950-F	Fuel (Mann P707)..... PF834
Fuel Ele..... PF838	Air (Mann C23440/1)..... PA2474	Air (Mann C20325/2)..... PA2405
Gamecock w/Rootes 2.6L Eng.	Steering (Mann P919/7)..... PT691	
Lube..... P174		S211 H w/Mercedes-Benz OM421 Eng.
Fuel Ele..... PF838	S150 w/Henschel 6-6R1113-18K Eng.	Lube (Mann H12110/2x)..... P294
	Lube (Mann W962)..... B236 +	Fuel (Mann BFU900x)..... F950-F
<b>KASSBOHRER</b>	Fuel (Mann WK731)..... BF988 +	Air (Mann C23440/1)..... PA2474
<b>Buses</b>	Air (Mann C20325)..... PA2866	Air (Mann C24650/1)..... PA2475
S80 w/Henschel 552-5R1112-14K Eng.	Air (Mann C21317)..... PA1636-FN	
Lube (Mann W940/5)..... BT292	Steering (Mann P919/7)..... PT691	S211 H w/Mercedes-Benz OM422 Eng.
Fuel (Mann WK731)..... BF988 +		Lube (Mann H12110/2x)..... P294
Air (Mann C20325)..... PA2866	S150 w/Henschel 524-6R1315-20K Eng.	Fuel (Mann BFU900x)..... F950-F
Air (Mann C21317)..... PA1636-FN	Lube (Mann W962)..... B236 +	Air (Mann C23440/1)..... PA2474
	Fuel (Mann WK731)..... BF988 +	Steering (Mann H601/4)..... P106-HD
S100, S100 A w/Henschel 6R1112-16K Eng.	Air (Mann C23440)..... PA2847	
Lube (Mann W962)..... B236 +	Air (Mann C24516)..... PA1646-FN	S212 w/Mercedes-Benz OM403 Eng.
Fuel (Mann WK731)..... BF988 +	Steering (Mann P919/7)..... PT691	Lube (Mann H12110/2x)..... P294
Air (Mann C20325)..... PA2866		Fuel (Mann P707)..... PF834
Air (Mann C21317)..... PA1636-FN	S200 w/Mercedes-Benz OM403 Eng.	Air (Mann C24650/1)..... PA2475
Steering (Mann P919/7)..... PT691	Lube (Mann H12110/2x)..... P294	
S103 S w/Mercedes-Benz OM407 Eng.	Fuel (Mann P811)..... PF950	S212 H w/M.A.N. D2566 Eng.
Lube..... P294	Air (Mann C24650/1)..... PA2475	Lube..... P294
Fuel (Mann BFU900x)..... F950-F	Steering (Mann P919/7)..... PT691	Fuel (Mann P707)..... PF834
Air (Mann C23440/1)..... PA2474		Air (Mann C23440/1)..... PA2474
S110, S110 A w/Henschel S62-6R1112-18K Eng.	S208 w/Mercedes-Benz OM401 Eng.	
Lube (Mann W962)..... B236 +	Lube (Mann H1275x)..... P242	S212 H w/Mercedes-Benz OM402 Eng.
Fuel (Mann WK731)..... BF988 +	Fuel (Mann P707)..... PF834	Lube (Mann H1275x)..... P242
Air (Mann C20325)..... PA2866	Air (Mann C20325/2)..... PA2405	Some Lube (Mann H12110/2)..... P294
		Fuel (Mann P707)..... PF834
		Air (Mann C23440/1)..... PA2474

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>KASSBOHRER Buses (cont'd)</b>	<b>KASSBOHRER Buses (cont'd)</b>	<b>KASSBOHRER Buses (cont'd)</b>
S212 H w/Mercedes-Benz OM421 Eng. Lube (Mann H1275x)..... <b>P242</b> Fuel (Mann BFU700x)..... <b>F834-F</b> Some Fuel (Mann BFU900x)..... <b>F950-F</b> Air (Mann C24650/1)..... <b>PA2475</b>	S215 H w/Mercedes-Benz OM403 Eng. Lube (Mann H12110/2x)..... <b>P294</b> Fuel (Mann P707)..... <b>PF834</b> Air (Mann C24650/1)..... <b>PA2475</b>	S215 SL, S215 UL w/Mercedes-Benz OM427 Eng. Lube (Mann H12110/2x)..... <b>P294</b> Fuel Ele. (Mann BFU900x)..... <b>F950-F</b> Fuel Spin-on (Mann WK842/2).... <b>BF5587-D</b> Air (Mann C24650/1)..... <b>PA2475</b> Air Dryer (Mann TB1374x)..... <b>BA5374 +</b> Steering (Mann H601/4)..... <b>P106-HD</b>
S212 H w/Mercedes-Benz OM422 Eng. Lube (Mann H12110/2)..... <b>P294</b> Fuel (Mann BFU700x)..... <b>F834-F</b> Some Fuel (Mann BFU900x)..... <b>F950-F</b> Air (Mann C24650/1)..... <b>PA2475</b>	S215 H, S215 RL w/Mercedes-Benz OM422 Eng. Lube (Mann H12110/2)..... <b>P294</b> Fuel (Mann BFU900x)..... <b>F950-F</b> Air (Mann C24650/1)..... <b>PA2475</b> Air (Mann C30850/2)..... <b>PA2776</b> Some Air Dryer (Mann TB1374x)..... <b>BA5374 +</b> Steering (Mann H601/4)..... <b>P106-HD</b>	S216 HDS w/M.A.N. D2866 Eng. Lube (Mann H12110/2x)..... <b>P294</b> Fuel (Mann P811)..... <b>PF950</b> Air (Mann C30850/2)..... <b>PA2776</b> Steering (Mann H601/4)..... <b>P106-HD</b>
S213 H w/M.A.N. D2566 Eng. Lube..... <b>P294</b> Fuel (Mann P707)..... <b>PF834</b> Air (Mann C23440/1)..... <b>PA2474</b> Steering (Mann H601/4)..... <b>P106-HD</b>	S215 HDH-3 w/Detroit Diesel Series 60 Eng. Lube..... <b>[2] B495</b> Air Dryer (Mann TB1374x)..... <b>BA5374 +</b> Steering (Mann H601/4)..... <b>P106-HD</b>	S216 HDS w/Mercedes-Benz OM422 Eng. Lube (Mann H12110/2x)..... <b>P294</b> Fuel Ele. (Mann BFU900x)..... <b>F950-F</b> Air (Mann C30850/2)..... <b>PA2776</b> Steering (Mann H601/4)..... <b>P106-HD</b>
S213 H w/Mercedes-Benz OM402 Eng. Lube (Mann H1275x)..... <b>P242</b> Some Lube (Mann H12110/2x).... <b>P294</b> Fuel (Mann P707)..... <b>PF834</b> Air (Mann C23440/1)..... <b>PA2474</b>	S215 HDS w/Mercedes-Benz OM422 Eng. Lube (Mann H12110/2)..... <b>P294</b> Fuel (Mann BFU700x)..... <b>F834-F</b> Some Fuel (Mann BFU900x)..... <b>F950-F</b> Air (Mann C30850/2)..... <b>PA2776</b>	S217 HDH-3 w/Detroit Diesel Series 60 Eng. Lube..... <b>[2] B495</b> Air Dryer (Mann TB1374x)..... <b>BA5374 +</b>
S213 H w/Mercedes-Benz OM403 Eng. Lube (Mann H12110/2x)..... <b>P294</b> Fuel (Mann P707)..... <b>PF834</b> Air (Mann C24650/1)..... <b>PA2475</b>	S215 HR w/Mercedes-Benz OM422 Eng. Fuel (Mann BFU900x)..... <b>F950-F</b> Air (Mann C24650/1)..... <b>PA2475</b> Steering (Mann H601/4)..... <b>P106-HD</b>	S228 DT w/Mercedes-Benz OM422, OM442 Eng. Lube (Mann H12110/2x)..... <b>P294</b> Fuel (Mann BFU900x)..... <b>F950-F</b> Air (Mann C30850/2)..... <b>PA2776</b> Air (10/93-on) (Mann C331840).... <b>PA3765</b> Some Air Dryer (Mann TB1374x)..... <b>BA5374 +</b> Steering (Mann H601/4)..... <b>P106-HD</b>
S213 H w/Mercedes-Benz OM422 Eng. Lube (Mann H12110/2)..... <b>P294</b> Fuel (Mann BFU900x)..... <b>F950-F</b> Air (Mann C30850/2)..... <b>PA2776</b> Steering (Mann H601/4)..... <b>P106-HD</b>	S215 NR w/Mercedes-Benz OM447 Eng. Lube (Mann H12110/2x)..... <b>P294</b> Fuel/Water Separator (Mann WDK724)..... <b>BF1372</b> Air (Mann C24650/1)..... <b>PA2475</b> Steering (Mann H601/4)..... <b>P106-HD</b>	S250 Special w/M.A.N. D2866 Eng. Lube (Mann H12110/2)..... <b>P294</b> Fuel/Water Separator Spin-on (Mann WDK724)..... <b>BF1372</b> Fuel Ele. (Mann P811)..... <b>PF950</b> Air (Mann C30850/2)..... <b>PA2776</b> Air Dryer (Mann TB1374x)..... <b>BA5374 +</b> Steering (Mann H601/4)..... <b>P106-HD</b>
S214 H w/M.A.N. D2866 Eng. Lube (Mann H12110/2x)..... <b>P294</b> Fuel (Mann P811)..... <b>PF950</b> Air (Mann C30850/2)..... <b>PA2776</b> Steering (Mann H601/4)..... <b>P106-HD</b>	S215 SL w/Mercedes-Benz OM447 Eng. Lube (Mann H12110/2x)..... <b>P294</b> Fuel Ele. (Mann BFU900x)..... <b>F950-F</b> Fuel Spin-on (Mann WK842/2).... <b>BF5587-D</b> Air (Mann C24650/1)..... <b>PA2475</b> Steering (Mann H601/4)..... <b>P106-HD</b>	S300 N w/M.A.N. D2866 Eng. Lube (Mann H12110/2)..... <b>P294</b> Fuel/Water Separator Spin-on (Mann WDK724)..... <b>BF1372</b> Fuel Ele. (Mann P811)..... <b>PF950</b> Air (Mann C23440/1)..... <b>PA2474</b> Air Dryer (Mann TB1374x)..... <b>BA5374 +</b> Steering (Mann H601/4)..... <b>P106-HD</b>
S214 HD w/Mercedes-Benz OM422 Eng. Lube (Mann H12110/2x)..... <b>P294</b> Fuel (Mann BFU900x)..... <b>F950-F</b> Air (Mann C30850/2)..... <b>PA2776</b> Steering (Mann H601/4)..... <b>P106-HD</b>	S215 SL, S215 UL w/M.A.N. D2566 Eng. Lube (Mann H12110/2)..... <b>P294</b> Fuel (Mann P811)..... <b>PF950</b> Air (Mann C23440/1)..... <b>PA2474</b>	S309 HD w/Mercedes-Benz OM401 Eng. Lube (Mann H12110/2x)..... <b>P294</b> Fuel (Mann BFU900x)..... <b>F950-F</b> Air (Mann C24650/1)..... <b>PA2475</b> Air Dryer (Mann TB1374x)..... <b>BA5374 +</b> Steering (Mann H601/4)..... <b>P106-HD</b>
S215 w/Mercedes-Benz OM401 Eng. Lube (Mann H1275x)..... <b>P242</b> Fuel (Mann P707)..... <b>PF834</b> Air (Mann C20325/2)..... <b>PA2405</b>	S215 SL, S215 UL w/M.A.N. D2866 Eng. Lube (Mann H12110/2)..... <b>P294</b> Fuel (Mann P811)..... <b>PF950</b> Air (Mann C30850/2)..... <b>PA2776</b> Steering (Mann H601/4)..... <b>P106-HD</b>	S309 HD, S312 HD w/Mercedes-Benz OM441 Eng. Lube (Mann HU947/1z-2)..... <b>P7016</b> Fuel (Mann BFU900x)..... <b>F950-F</b> Air (Mann C30850/2)..... <b>PA2776</b>
S215 H w/M.A.N. D2866 Eng. Lube (Mann H12110/2x)..... <b>P294</b> Fuel (Mann P811)..... <b>PF950</b> Air (Mann C30850/2)..... <b>PA2776</b> Air Dryer (Mann TB1374x)..... <b>BA5374 +</b> Steering (Mann H601/4)..... <b>P106-HD</b>	S215 SL, S215 UL w/Mercedes-Benz OM407 Eng. Lube (Mann H12110/2x)..... <b>P294</b> Fuel (Mann BFU900x)..... <b>F950-F</b> Air (Mann C24650/1)..... <b>PA2475</b> Steering (Mann H601/4)..... <b>P106-HD</b>	
S215 H w/Mercedes-Benz OM402 Eng. Lube (Mann H1275x)..... <b>P242</b> Some Lube (Mann H12110/2x).... <b>P294</b> Fuel (Mann P707)..... <b>PF834</b> Air (Mann C23440/1)..... <b>PA2474</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



KASSBOHRER Buses (cont'd)	KASSBOHRER Buses (cont'd)	KASSBOHRER Buses (cont'd)
S309 HD, S312 HD w/Mercedes-Benz OM441 Eng. (Cont'd) Air Dryer (Mann TB1374x)..... BA5374 + Steering (Mann H601/4)..... P106-HD	S315 HD, S315 HDH w/Mercedes-Benz OM442 Eng. Lube (Mann H12110/2x)..... P294 Fuel (Mann BFU900x)..... F950-F Air (Mann C24650/1)..... PA2475 Air Dryer (Mann TB1374x)..... BA5374 + Steering (Mann H601/4)..... P106-HD Some Steering (Mann P919/7).... PT691	S316 UL w/Mercedes-Benz OM457 Eng. Lube (Mann H12110/2x)..... P294 Some Lube (Mann HU945/2x).... P7188 Fuel (Mann PU999/1x)..... PF7761 Air Dryer (Mann TB1374x)..... BA5374 + Steering (Mann H601/4)..... P106-HD
S313 UL w/M.A.N. D2866 Eng. Lube (Mann H12110/2)..... P294 Fuel/Water Separator Spin-on (Mann WDK724)..... BF1372 Air (Mann C30850/2)..... PA2776 Air Dryer (Mann TB1374x)..... BA5374 + Trans. (ZF HP500) (Mann H710/1x)..... PT8385 Steering (Mann H601/4)..... P106-HD	S315 HD, S315 HDH w/Mercedes-Benz OM442A Eng. Lube (Mann H12110/2x)..... P294 Fuel (Mann BFU900x)..... F950-F Air (Mann C30850/2)..... PA2776 Radial Seal Air (Mann C311414)..... RS5484 Air Dryer (Mann TB1374x)..... BA5374 + Steering (Mann H601/4)..... P106-HD Some Steering (Mann P919/7).... PT691	S317 GT-HD w/Mercedes-Benz OM442 Eng. Lube (Mann HU947/1z-2)..... P7016 Fuel/Water Separator (Mann WDK724)..... BF1372 Air (Mann C331840)..... PA3765 Air Dryer (Mann TB1374x)..... BA5374 + Steering (Mann H601/4)..... P106-HD Some Steering (Mann P919/7).... PT691
S313 UL w/Mercedes-Benz OM447 Eng. Lube (Mann H12110/2x)..... P294 Fuel/Water Separator Spin-on (Mann WDK724)..... BF1372 Fuel Ele. (Mann BFU900x)..... F950-F Air Dryer (Mann TB1374x)..... BA5374 + Trans. (ZF HP500, HP50) (Mann H710/1x)..... PT8385 Steering (Mann H601/4)..... P106-HD	S315 HD, S315 HDH w/Scania DS11.22 Eng. Fuel (Mann WK842/2)..... BF5587-D Air (Mann C24650/1)..... PA2475 Air Dryer (Mann TB1374x)..... BA5374 + Turbocharger (Mann W92017).... B120 Steering (Mann H601/4)..... P106-HD Some Steering (Mann P919/7).... PT691	S317 GT-HD w/Mercedes-Benz OM457 Eng. Lube (Mann HU945/2x)..... P7188 Fuel (Mann PU999/1x)..... PF7761 Air Dryer (Mann TB1374x)..... BA5374 + Steering (Mann H601/4)..... P106-HD Some Steering (Mann P919/7).... PT691
S313 UL w/Mercedes-Benz OM457 Eng. Fuel (Mann PU999/1x)..... PF7761 Air Dryer (Mann TB1374x)..... BA5374 + Steering (Mann H601/4)..... P106-HD	S315 NF w/Mercedes-Benz OM447 Eng. Lube (H12110/2x)..... P294 Some Lube (Mann H1275x)..... P242 Fuel/Water Separator (Mann WDK724)..... BF1372 Air (Mann C24650/1)..... PA2475 Radial Seal Air (Mann C31980).... RS5483 Air Dryer (Mann TB1374x)..... BA5374 + Trans. (ZF HP500, HP590) (Mann H710/1x)..... PT8385 Steering (Mann H601/4)..... P106-HD	S317 HDH w/Mercedes-Benz OM442 Eng. Lube (Mann HU945/2x)..... P294 Fuel (Mann BFU900x)..... F950-F Air (Mann C30850/2)..... PA2776 Air Dryer (Mann TB1374x)..... BA5374 + Steering (Mann H601/4)..... P106-HD Some Steering (Mann P919/7).... PT691
S315 GT, S315 GT-HD, S315 H w/Mercedes-Benz OM457 Eng. Lube (Mann HU945/2x)..... P7188 Fuel Ele. (Mann PU999/1x)..... PF7761 Air Dryer (Mann TB1374x)..... BA5374 + Steering (Mann H601/4)..... P106-HD	S315 NF, S315 UL w/Mercedes-Benz OM457 Eng. Lube (HU945/2x)..... P7188 Fuel (Mann PU999/1x)..... PF7761 Air Dryer (Mann TB1374x)..... BA5374 + Steering (Mann H601/4)..... P106-HD	S317 HDH-3 w/Mercedes-Benz OM502 Eng. F-F Lube (Mann H12140x)..... P7192 Fuel/Water Separator Spin-on (Mann WDK724)..... BF1372 Fuel Ele. (Mann PU999/1x)..... PF7761 Air (Mann C331840)..... PA3765 Air Dryer (Mann TB1374x)..... BA5374 + Steering (Mann H601/4)..... P106-HD Some Steering (Mann P919/7).... PT691
S315 GT-HD w/M.A.N. D2866 Eng. Lube (Mann H12110/2)..... P294 Fuel/Water Separator Spin-on (Mann WDK724)..... BF1372 Air (Mann C30850/2)..... PA2776 Air Dryer (Mann TB1374x)..... BA5374 + Steering (Mann H601/4)..... P106-HD	S315 NF, S315 UL w/Mercedes-Benz OM457 Eng. Lube (HU945/2x)..... P7188 Fuel (Mann PU999/1x)..... PF7761 Air Dryer (Mann TB1374x)..... BA5374 + Steering (Mann H601/4)..... P106-HD	S317 UL w/Mercedes-Benz OM457 Eng. Lube (Mann HU945/2x)..... P7188 Fuel (Mann PU999/1x)..... PF7761 Air Dryer (Mann TB1374x)..... BA5374 + Steering (Mann H601/4)..... P106-HD Some Steering (Mann P919/7).... PT691
S315 GT-HD w/Mercedes-Benz OM441 Eng. Lube (Mann HU947/1z-2)..... P7016 Fuel (Mann BFU900x)..... F950-F Air (Mann C301537)..... PA2776 Air Dryer (Mann TB1374x)..... BA5374 + Steering (Mann H601/4)..... P106-HD	S315 UL w/Mercedes-Benz OM447 Eng. Lube (H12110/2x)..... P294 Some Lube (Mann HU945/2x).... P7188 Fuel/Water Separator (Mann WDK724)..... BF1372 Air Dryer (Mann TB1374x)..... BA5374 + Trans. (ZF HP500, HP590) (Mann H710/1x)..... PT8385 Steering (Mann H601/4)..... P106-HD	S319 GT-HD w/Mercedes-Benz OM442 Eng. Lube (Mann H12110/2x)..... P294 Some Lube (Mann HU947/2x).... P7145 Fuel/Water Separator Spin-on (Mann WDK724)..... BF1372 Fuel Ele. (Mann BFU900x)..... F950-F Air Dryer (Mann TB1374x)..... BA5374 + Steering (Mann H601/4)..... P106-HD Some Steering (Mann P919/7).... PT691
S315 H, S315 HD, S315 HDH w/Mercedes-Benz OM441 Eng. Lube (Mann HU947/1z-2)..... P7016 Fuel (Mann BFU900x)..... F950-F Air (Mann C301537)..... PA2776 Radial Seal Air (Mann C311414)..... RS5484 Air Dryer (Mann TB1374x)..... BA5374 + Steering (Mann H601/4)..... P106-HD Some Steering (Mann P919/7).... PT691	S316 HDS w/Mercedes-Benz OM442 Eng. Lube (Mann H12110/2x)..... P294 Fuel (Mann BFU900x)..... F950-F Air (Mann C30850/2)..... PA2776 Air Dryer (Mann TB1374x)..... BA5374 + Steering (Mann H601/4)..... P106-HD	S319 GT-HD, S319 NF w/Mercedes-Benz OM457 Eng. Lube (Mann HU945/2x)..... P7188 Fuel (Mann PU999/1x)..... PF7761 Air Dryer (Mann TB1374x)..... BA5374 + Steering (Mann H601/4)..... P106-HD Some Steering (Mann P919/7).... PT691

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>KASSBOHRER Buses (cont'd)</b>	<b>KASSBOHRER Buses (cont'd)</b>	<b>KASSBOHRER Buses (cont'd)</b>
S319 NF, S319 UL w/Mercedes-Benz OM447 Eng. Lube (Mann H12110/2x)..... <b>P294</b> Fuel/Water Separator Spin-on (Mann WDK724)..... <b>BF1372</b> Fuel Ele. (Mann BFU900x)..... <b>F950-F</b> Air Dryer (Mann TB1374x)..... <b>BA5374 +</b> Steering (Mann H601/4)..... <b>P106-HD</b> Some Steering (Mann P919/7).... <b>PT691</b>	SG219 SL w/Mercedes-Benz OM407 Eng. Lube (Mann H12110/2x)..... <b>P294</b> Fuel Ele. (Mann BFU900x)..... <b>F950-F</b> Air (Mann C24650/1)..... <b>PA2475</b> Steering (Mann H601/4)..... <b>P106-HD</b>	SG321 UL w/Mercedes-Benz OM447 Eng. (Cont'd) Steering (Mann H601/4)..... <b>P106-HD</b> Some Steering (Mann P919/7).... <b>PT691</b>
S319 UL w/M.A.N. D2866 Eng. Lube (Mann H12110/2)..... <b>P294</b> Fuel/Water Separator (Mann WDK724)..... <b>BF1372</b> Air (To 1/97) (Mann C24650/1).... <b>PA2475</b> Radial Seal Air (1/97-on) (Mann C31980)..... <b>RS5483</b> Air Dryer (Mann TB1374x)..... <b>BA5374 +</b> Steering (Mann H601/4)..... <b>P106-HD</b> Some Steering (Mann P919/7).... <b>PT691</b>	SG219 SL w/Mercedes-Benz OM427 Eng. Lube (Mann H12110/2x)..... <b>P294</b> Fuel (Mann BFU900x)..... <b>F950-F</b> Air (Mann C24650/1)..... <b>PA2475</b> Air (Mann C30850/2)..... <b>PA2776</b> Steering (Mann H601/4)..... <b>P106-HD</b>	SG321 UL w/Mercedes-Benz OM457 Eng. Lube (Mann HU945/2x)..... <b>P7188</b> Fuel (Mann PU999/1x)..... <b>PF7761</b> Radial Seal Air (Mann C31980).... <b>RS5483</b> Air Dryer (Mann TB1374x)..... <b>BA5374 +</b> Steering (Mann H601/4)..... <b>P106-HD</b> Some Steering (Mann P919/7).... <b>PT691</b>
S319 UL w/Mercedes-Benz OM457 Eng. Lube (Mann HU945/2x)..... <b>P7188</b> Fuel (Mann PU999/1x)..... <b>PF7761</b> Air Dryer (Mann TB1374x)..... <b>BA5374 +</b> Steering (Mann H601/4)..... <b>P106-HD</b> Some Steering (Mann P919/7).... <b>PT691</b>	SG221 UL w/M.A.N. D2566 Eng. Lube (Mann H12110/2)..... <b>P294</b> Fuel (Mann P811)..... <b>PF950</b> Air (Mann C23440/1)..... <b>PA2474</b> Air (Mann C24650/1)..... <b>PA2475</b> Steering (Mann H601/4)..... <b>P106-HD</b>	S328 DT w/Mercedes-Benz OM442 Eng. Lube (Mann H12110/2x)..... <b>P294</b> Fuel (Mann BFU900x)..... <b>F950-F</b> Air (Mann C30850/2)..... <b>PA2776</b> Air (Mann C331840)..... <b>PA3765</b> Air Dryer (Mann TB1374x)..... <b>BA5374 +</b> Steering (Mann H601/4)..... <b>P106-HD</b> Some Steering (Mann P919/7).... <b>PT691</b>
SG175 w/M.A.N. U12D Eng. Lube (Mann H12113)..... <b>PT86-HD</b> Fuel (Mann P811)..... <b>PF950</b> Steering (Mann P919/7)..... <b>PT691</b>	SG221 UL w/Mercedes-Benz OM407 Eng. Lube (Mann H12110/2x)..... <b>P294</b> Fuel (Mann BFU900x)..... <b>F950-F</b> Air (Mann C24650/1)..... <b>PA2475</b> Steering (Mann H601/4)..... <b>P106-HD</b>	S411 HD w/Mercedes-Benz OM501 Eng. F-F Lube (Mann H12140x)..... <b>P7192</b> Fuel Ele. (Mann PU999/1x)..... <b>PF7761</b> Air Dryer (Mann TB1374x)..... <b>BA5374 +</b> Steering (Mann H601/4)..... <b>P106-HD</b>
SG175 w/Henschel 6U1215 Eng. Fuel (Mann P811)..... <b>PF950</b> Steering (Mann P919/7)..... <b>PT691</b>	SG221 UL w/Mercedes-Benz OM422 Eng. Lube (Mann H12110/2x)..... <b>P294</b> Fuel (Mann BFU900x)..... <b>F950-F</b> Air (Mann C30850/2)..... <b>PA2776</b> Steering (Mann H601/4)..... <b>P106-HD</b>	S415 HD, S415 HDH w/Mercedes-Benz OM457 Eng. Lube (Mann HU945/2x)..... <b>P7188</b> Fuel (Mann PU999/1x)..... <b>PF7761</b> Air Dryer (Mann TB1374x)..... <b>BA5374 +</b> Steering (Mann H601/4)..... <b>P106-HD</b>
SG180 w/M.A.N. D2556 Eng. Lube (Mann H12110/2)..... <b>P294</b> Fuel (To 7/76) (Mann P811)..... <b>PF950</b> Fuel (7/76-12/85) (Mann P707).... <b>PF834</b>	SG221 UL w/Mercedes-Benz OM427 Eng. Lube (Mann H12110/2x)..... <b>P294</b> Fuel (Mann BFU900x)..... <b>F950-F</b> Air (Mann C24650/1)..... <b>PA2475</b> Steering (Mann H601/4)..... <b>P106-HD</b>	S415 HD, S415 HDH w/Mercedes-Benz OM502 Eng. F-F Lube (Mann HU12140x)..... <b>P7192</b> Fuel (Mann PU999/1x)..... <b>PF7761</b> Air Dryer (Mann TB1374x)..... <b>BA5374 +</b> Steering (Mann H601/4)..... <b>P106-HD</b>
SG180 w/Mercedes-Benz OM407 Eng. Lube..... <b>P294</b> Fuel (Mann BFU900x)..... <b>F950-F</b> Air (Mann C23440/1)..... <b>PA2474</b> Steering (Mann P919/7)..... <b>PT691</b>	SG321 UL w/M.A.N. D2866 Eng. Lube (Mann H12110/2)..... <b>P294</b> Fuel/Water Separator (Mann WDK724)..... <b>BF1372</b> Air (To 1/97) (Mann C24650/1).... <b>PA2475</b> Radial Seal Air (1/97-on) (Mann C31980)..... <b>RS5483</b> Air Dryer (Mann TB1374x)..... <b>BA5374 +</b> Steering (Mann H601/4)..... <b>P106-HD</b> Some Steering (Mann P919/7).... <b>PT691</b>	S417 HDH w/Mercedes-Benz OM502 Eng. F-F Lube (Mann HU12140x)..... <b>P7192</b> Fuel (Mann PU999/1x)..... <b>PF7761</b> Air Dryer (Mann TB1374x)..... <b>BA5374 +</b> Steering (Mann H601/4)..... <b>P106-HD</b>
SG180, SG180 UE w/M.A.N. U12D Eng. Lube (Mann H12113)..... <b>PT86-HD</b> Fuel (Mann P811)..... <b>PF950</b> Air (Mann C24700/1)..... <b>PA3572</b>	SG321 UL w/Mercedes-Benz OM447 Eng. Lube (Mann H12110/2x)..... <b>P294</b> Fuel/Water Separator Spin-on (Mann WDK724)..... <b>BF1372</b> Fuel Ele. (Mann BFU900x)..... <b>F950-F</b> Radial Seal Air (1/97-on) (Mann C31980)..... <b>RS5483</b> Air Dryer (Mann TB1374x)..... <b>BA5374 +</b> Steering (Mann H601/4)..... <b>P106-HD</b> Some Steering (Mann P919/7).... <b>PT691</b>	S431 DT w/Mercedes-Benz OM502 Eng. F-F Lube (Mann HU12140x)..... <b>P7192</b> Fuel (Mann PU999/1x)..... <b>PF7761</b> Air Dryer (Mann TB1374x)..... <b>BA5374 +</b> Steering (Mann H601/4)..... <b>P106-HD</b>
SG219 SL w/M.A.N. D2566 Eng. Lube (Mann H12110/2)..... <b>P294</b> Fuel (Mann P811)..... <b>PF950</b> Air (Mann C23440/1)..... <b>PA2474</b> Steering (Mann H601/4)..... <b>P106-HD</b>	SG219 SL w/M.A.N. D2866 Eng. Lube (Mann H12110/2)..... <b>P294</b> Fuel (Mann P811)..... <b>PF950</b> Air (Mann C30850/2)..... <b>PA2776</b> Steering (Mann H601/4)..... <b>P106-HD</b>	<div style="text-align: center;"><b>KENWORTH</b></div> <div style="text-align: center;"><b>Trucks</b></div> 13-210, 22-210 w/Cummins C8.3 (8.3L) Eng. F-F Lube..... <b>B205 +</b> P. Fuel/Water Separator..... <b>BF1280 +</b> S. Fuel..... <b>BF788</b> Air (Don. P129545)..... <b>PA2521</b> Coolant..... <b>BW5070</b>

\* See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)
104B w/Cummins ISX Eng. Dual-Flow Lube (Fleetguard LF9031)..... <b>BD7509 +</b>	C500 w/Cat C11 (11.1L) Eng. (To 1/2004) (Cont'd) Trans. Ele. (Pall 1907008)..... <b>PT8330-MPG</b>	C500 w/Cat C13 (12.5L) Eng. (To 1/2004) (Cont'd) Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>
Dual-Flow Lube (Fleetguard LF9080)..... <b>BD7154 +</b>	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	Steering (Nelson 83804E)..... <b>P528</b>
Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>	C500 w/Cat C11 (11.1L) Eng. (1/2004-on) Lube (1R1808)..... <b>B7299 +</b>	C500 w/Cat C13 (12.5L) Eng. (1/2004-on) Lube (1R1808)..... <b>B7299 +</b>
Fuel/Water Separator (Fleetguard FS1040)..... <b>BF1277-SPS</b>	Fuel/Water Separator Ele..... <b>PF7755</b>	Fuel/Water Separator Ele..... <b>PF7755</b>
Fuel/Water Separator (Upgrade) (Fleetguard FS1007)..... <b>BF1274-SP</b>	Fuel/Water Separator Spin-on..... <b>BF1259</b>	Fuel/Water Separator Spin-on..... <b>BF1259</b>
Coolant (Fleetguard WF2126)..... <b>BW5086</b>	Fuel (1R0749)..... <b>BF7587 +</b>	Fuel (1R0749)..... <b>BF7587 +</b>
Trans. (Fuller 4304827)..... <b>BT223</b>	Radial Seal Air (Don. P549644)..... <b>RS3750</b>	Radial Seal Air (Don. P549644)..... <b>RS3750</b>
521, 522, C523 w/GMC Diesel Eng. F-F Lube Ele..... <b>P20-HD +</b>	Radial Seal XP Air (Don. P549644)..... <b>RS3750XP</b>	Radial Seal XP Air (Don. P549644)..... <b>RS3750XP</b>
B-P Lube Ele. (750 Size)..... <b>C750-E +</b>	Axial Seal Air..... <b>PA1626-2 +</b>	Axial Seal Air..... <b>PA1626-2 +</b>
P. Fuel Sock..... <b>F916-C</b>	Axial Seal Air (Don. P181037)..... <b>PA1642-2</b>	Axial Seal Air (Don. P181037)..... <b>PA1642-2</b>
S. Fuel Ele..... <b>PF902</b>	Air Dryer (Bendix 5008414)..... <b>BA5374 +</b>	Air Dryer (Bendix 5008414)..... <b>BA5374 +</b>
548CH w/Cummins N14 (14.0L) Eng. F-F Lube (Fleetguard LF670SC)..... <b>B196 +</b>	Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>	Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>
Dual-Flow Lube (3318853)..... <b>BD103 +</b>	Coolant (w/4 Units BTE) (9N-3368)..... <b>BW5137</b>	Coolant (w/4 Units BTE) (9N-3368)..... <b>BW5137</b>
B-P Lube (3304232)..... <b>B7577</b>	Coolant (w/8 Units BTE) (9N-3367)..... <b>BW5139</b>	Coolant (w/8 Units BTE) (9N-3367)..... <b>BW5139</b>
Fuel (154789)..... <b>BF957-D +</b>	Trans. Ele..... <b>PT189</b>	Trans. Ele..... <b>PT189</b>
Coolant (3315116)..... <b>BW5071</b>	Trans. Ele. (Pall 1907008)..... <b>PT8330-MPG</b>	Trans. Ele. (Pall 1907008)..... <b>PT8330-MPG</b>
921, 922, 923, 924 w/GMC Diesel Eng. F-F Lube Ele..... <b>P20-HD +</b>	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>
B-P Lube Ele. (750 Size)..... <b>C750-E +</b>	Steering (Nelson 83804E)..... <b>P528</b>	Steering (Nelson 83804E)..... <b>P528</b>
P. Fuel Sock..... <b>F916-C</b>	C500 w/Cat C12 Eng. Lube (1R1808)..... <b>B7299 +</b>	C500 w/Cat C15 Eng. Lube (To 1/2004) (1R0716)..... <b>B99 +</b>
S. Fuel Ele..... <b>PF902</b>	Fuel/Water Separator (256-8753)..... <b>BF1259</b>	Lube (1/2004-on) (1R1808)..... <b>B7299 +</b>
Brute, Hustler w/Cummins Eng. F-F Lube Ele..... <b>P999-HD</b>	Fuel (1R0749)..... <b>BF7587 +</b>	Fuel/Water Separator Ele..... <b>PF7755</b>
F-F Lube Spin-on..... <b>B196 +</b>	Radial Seal Air (Don. P534816)..... <b>RS3539</b>	Fuel/Water Separator Ele. (Davco 380087)..... <b>PF7680</b>
B-P Lube Ele..... <b>C750-E +</b>	Radial Seal XP Air (Don. P534816)..... <b>RS3539XP</b>	Fuel/Water Separator Spin-on (Fleetguard FS1000)..... <b>BF1259</b>
Fuel Spin-on..... <b>BF957 +</b>	Air Dryer (Bendix 5008414)..... <b>BA5374 +</b>	5 11/16 In. Fuel (Fleetguard FF2203)..... <b>BF7760</b>
Coolant Spin-on..... <b>BW5071</b>	Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	10 1/2 In. Fuel (1R0749)..... <b>BF7587 +</b>
Brute, Hustler w/GMC Diesel Eng. F-F Lube Ele..... <b>P20-HD +</b>	Steering (Nelson 87972A)..... <b>PT9386-MPG</b>	15 21/32 In. Radial Seal Air (Don. P549644)..... <b>RS3750</b>
B-P Lube Ele..... <b>C750-E +</b>	C500 w/Cat C13 (12.5L) Eng. (To 1/2004) Lube (1R0716)..... <b>B99 +</b>	15 21/32 In. Radial Seal XP Air (Don. P549644)..... <b>RS3750XP</b>
P. Fuel Spin-on..... <b>BF5800 +</b>	Fuel/Water Separator Ele..... <b>PF7755</b>	23 23/32 In. Radial Seal Air (Don. P534816)..... <b>RS3539</b>
S. Fuel Spin-on..... <b>BF5810</b>	Fuel/Water Separator Spin-on..... <b>BF1259</b>	23 23/32 In. Radial Seal XP Air (Don. P534816)..... <b>RS3539XP</b>
C500 w/Cat C11 (11.1L) Eng. (To 1/2004) Lube (1R0716)..... <b>B99 +</b>	Fuel (1R0749)..... <b>BF7587 +</b>	10 In. Axial Seal Air..... <b>PA1626-2 +</b>
Fuel/Water Separator Ele..... <b>PF7755</b>	Radial Seal Air (Don. P549644)..... <b>RS3750</b>	13 In. Axial Seal Air (Don. P181037)..... <b>PA1642-2</b>
Fuel/Water Separator Spin-on..... <b>BF1259</b>	Radial Seal XP Air (Don. P549644)..... <b>RS3750XP</b>	Air Dryer (Bendix 5008414)..... <b>BA5374 +</b>
Fuel (1R0749)..... <b>BF7587 +</b>	Axial Seal Air..... <b>PA1626-2 +</b>	Coolant (2007-on) (296-8325)..... <b>CV15008</b>
Radial Seal Air (Don. P549644)..... <b>RS3750</b>	Axial Seal Air (Don. P181037)..... <b>PA1642-2</b>	Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>
Radial Seal XP Air (Don. P549644)..... <b>RS3750XP</b>	Air Dryer (Bendix 5008414)..... <b>BA5374 +</b>	Coolant (w/4 Units BTE) (9N-3368)..... <b>BW5137</b>
Axial Seal Air..... <b>PA1626-2 +</b>	Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>	Coolant (w/4 Units BTE) (9N-3367)..... <b>BW5139</b>
Axial Seal Air (Don. P181037)..... <b>PA1642-2</b>	Coolant (w/4 Units BTE) (9N-3368)..... <b>BW5137</b>	Coolant (w/8 Units BTE) (9N-3367)..... <b>BW5139</b>
Air Dryer (Bendix 5008414)..... <b>BA5374 +</b>	Coolant (w/8 Units BTE) (9N-3367)..... <b>BW5139</b>	Trans. Ele..... <b>PT189</b>
Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>	Trans. Ele..... <b>PT189</b>	Trans. Ele. (Pall 1907008)..... <b>PT8330-MPG</b>
Coolant (w/4 Units BTE) (9N-3368)..... <b>BW5137</b>	Trans. Ele. (Pall 1907008)..... <b>PT8330-MPG</b>	
Coolant (w/8 Units BTE) (9N-3367)..... <b>BW5139</b>		
Coolant (w/8 Units BTE) (9N-3367)..... <b>BW5139</b>		
Trans. Ele..... <b>PT189</b>		
Trans. Ele. (Pall 1907008)..... <b>PT8330-MPG</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)
C500 w/Cat C15 Eng. (Cont'd)	C500 w/Cummins ISM 10.8 (10.8L) Eng. (To 2007)	C500 w/Cummins ISM 10.8 (10.8L) Eng. (2007-on) (Cont'd)
Trans. Spin-on (Fuller 4304827).. BT223	Dual-Flow Lube Spin-on..... BD7154 +	Opt. Trans. (Fuller 17237)..... B2 +
Opt. Trans. Spin-on (Fuller 17237)..... B2 +	Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... BD50000	Steering..... P528
Steering (To 2006) (Nelson 83804E)..... P528	B-P Lube Ele. (Don. P550750).... C750-E +	
Steering (2007-on) (Nelson 87972A)..... PT9386-MPG	B-P Lube Spin-on (Don. P550777)..... B7577	
C500 w/Cat C16 Eng.	Fuel/Water Separator Ele. (Fleetguard FS19727)..... PF7895	C500 w/Cummins ISX Eng. (1999-2015)
Lube..... B99 +	Fuel/Water Separator Ele. (Fleetguard FS1029W)..... PF7680	Dual-Flow Lube Spin-on (Fleetguard LF9080)..... BD7154 +
Fuel Spin-on..... BF7587 +	Fuel/Water Separator Ele. (Fleetguard FS1029W)..... PF7755	Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... BD50000
C500 w/Cat 3176 (10.3L) Eng.	Fuel/Water Separator Spin-on.... BF1272-SPS	B-P Lube Ele. (Don. P550750).... C750-E +
F-F Lube (Std. Efficiency) (1R0716)..... B99 +	Fuel/Water Separator Spin-on (Fleetguard FS1000)..... BF1259	B-P Lube Spin-on (Don. P550777)..... B7577
F-F Eng. Lube (High Efficiency Vers.) (1R1808)..... B7299 +	Fuel (Don. P550105)..... BF957 +	Fuel/Water Separator Ele. (Fleetguard FS1029W)..... PF7680
F-F Eng. Lube (1R0713)..... [2] BT230 +	Fuel (Don. P550202)..... BF596 +	Fuel/Water Separator Ele. (Fleetguard FS19729)..... PF7755
F-F Lube (1R0714)..... [2] B75	Air (Don. P181003)..... PA2482	Fuel/Water Separator Spin-on (Fleetguard FS1040)..... BF1277-SPS
Opt. B-P Lube (1W8845)..... B7577	Air (Don. P181007)..... PA2312	Fuel (Don. P550105)..... BF957 +
P. Fuel Ele. (9M2342)..... [2] PF935	Air (Don. P181008)..... PA2317 +	Fuel (Don. P550202)..... BF596 +
P. Fuel Spin-on (1R0740)..... BF970 +	Air (Don. P181009)..... PA2357 +	P. Fuel (Pre-Filter) (Fleetguard FF2203)..... BF7760
S. Fuel Spin-on (1R0750)..... BF7633 +	Air Dryer (Bendix 5008414)..... BA5374 +	S. Fuel (Fleetguard FF2200)..... BF7766
Trans. Spin-on (Fuller 4304827).. BT223	Breather (255963)..... PA643	Fuel (Standard) (Fleetguard FF5776)..... BF9885 +
Opt. Trans. Spin-on (Fuller 17237)..... B2 +	Breather (256837)..... PA1627	Fuel (Upgrade) (Fleetguard FF5825NN)..... BF46129
C500 w/Cat 3306 (10.5L) Eng.	Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071	Axial Seal Air (Don. P181003).... PA2482
Lube Ele. (w/Paper Wrapper) (1R0659)..... PT670	Coolant (w/4 Units BTE)..... BW5137	Axial Seal Air (Don. P181007).... PA2312
F-F Lube Spin-on (1R0716)..... B99 +	Opt. Trans. (Fuller 17237)..... B2 +	Axial Seal Air (Don. P181008).... PA2317 +
F-F Lube Spin-on (Standard Vers.) (1R0739)..... B76 +	Steering..... P528	Axial Seal Air (Don. P181009).... PA2357 +
F-F Lube Spin-on (Severe Service) (1R0739)..... B76-SS +	C500 w/Cummins ISM 10.8 (10.8L) Eng. (2007-on)	22 29/32 In. Std. Radial Seal Air (P614986)..... [2] RS5288
P. Fuel Ele. (9M2341)..... PF935	Dual-Flow Lube Spin-on..... BD7154 +	22 29/32 In. Radial Seal XP Air (Paccar P614986)..... [2] RS5288XP
P. Fuel Spin-on (1R0740)..... BF970 +	Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... BD50000	23 23/32 In. Radial Seal Air (Don. P534816)..... RS3539
S. Fuel Spin-on (1R0750)..... BF7633 +	B-P Lube Ele. (Don. P550750).... C750-E +	23 23/32 In. Radial Seal XP Air (Don. EAF5100)..... RS3539XP
Trans. Spin-on (Fuller 4304827).. BT223	B-P Lube Spin-on (Don. P550777)..... B7577	Air Dryer (Bendix 5008414)..... BA5374 +
Opt. Trans. Spin-on (Fuller 17237)..... B2 +	Fuel/Water Separator Ele. (Fleetguard FS19727)..... PF7895	Breather (255963)..... PA643
C500 w/Cat 3306 (10.5L) Eng.	Fuel/Water Separator Ele. (Fleetguard FS1029W)..... PF7680	Breather (256837)..... PA1627
Lube Ele. (w/Metal Wrapper) (1R0659)..... PT7332	Fuel/Water Separator Ele. (Fleetguard FS1029W)..... PF7755	Breather (4312013)..... CV15000
C500 w/Cat 3406 (14.6L) Eng.	Fuel/Water Separator Spin-on.... BF1272-SPS	Coolant (w/o Chemical) (Fleetguard WF2127)..... B5087
Lube Spin-on..... B99 +	Fuel/Water Separator Spin-on (Fleetguard FS1000)..... BF1259	Coolant (w/4 Units BTE)..... BW5137
Opt. Fuel/Water Separator..... BF1218 +	Fuel (Don. P550105)..... BF957 +	Coolant (w/11 1/2 Units BTA+) (Fleetguard WF2126)..... BW5086
Fuel/Water Separator (Fleetguard FS1212)..... BF1212 +	Fuel (Don. P550202)..... BF596 +	Trans. Ele. (2 In. Kit) (Allison 29548987)..... PT9416-MPG KIT
Fuel Spin-on..... BF614 +	Air (Don. P181003)..... PA2482	Trans. Ele. (4 In. Kit) (Allison 29548988)..... PT9415-MPG KIT
Air (Don. P181003)..... PA2482	Air (Don. P181007)..... PA2312	Trans. Spin-on (Fuller 4304827).. BT223
Air (Don. P181007)..... [2] PA2312	Air (Don. P181008)..... PA2317 +	Opt. Trans. Spin-on (Fuller 17237)..... B2 +
Air (Don. P181008)..... PA2317 +	Air (Don. P181009)..... PA2357 +	Steering (Nelson 83804E)..... P528
Coolant Spin-on (Maintenance).. BW5137	Air Dryer (Bendix 5008414)..... BA5374 +	Steering (Nelson 87972A)..... PT9386-MPG
Coolant Spin-on (Pre-Charge).... BW5139	Breather (255963)..... PA643	
Coolant (Fleetguard WF2055)..... BW5140	Breather (256837)..... PA1627	
Opt. Trans. (Fuller 17237)..... B2 +	Breather (3683918)..... CV15000	
Steering (Fleetguard LF637)..... P528	Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071	
	Coolant (w/4 Units BTE)..... BW5137	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)
<p>C500 w/Cummins L10 (10.0L) Eng.</p> <p>F-F Lube (Fleetguard LF670SC).. <b>B196 +</b></p> <p>Dual-Flow Lube (3318853)..... <b>BD103 +</b></p> <p>B-P Lube (3304232)..... <b>B7577</b></p> <p>Fuel (154789)..... <b>BF957-D +</b></p> <p>Coolant (w/4 Units BTA+) (3315116)..... <b>BW5071</b></p> <p>Coolant (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b></p> <p>Trans. Spin-on (Fuller 4304827).. <b>BT223</b></p> <p>Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b></p> <hr/> <p>C500 w/Cummins M11 (10.8L) Eng.</p> <p>Dual-Flow Lube (3318853)..... <b>BD103 +</b></p> <p>Fuel/Water Separator Ele. (Fleetguard FS1029W)..... <b>PF7680</b></p> <p>Fuel/Water Separator Spin-on (3329289)..... <b>BF1259</b></p> <p>Trans. Spin-on (Fuller 4304827).. <b>BT223</b></p> <p>Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b></p> <hr/> <p>C500 w/Cummins N14 Eng.</p> <p>F-F Lube Spin-on..... <b>B196 +</b></p> <p>B-P Lube Ele..... <b>C750-E +</b></p> <p>B-P Lube Spin-on..... <b>B7577</b></p> <p>Fuel/Water Separator..... <b>BF1212 +</b></p> <p>Fuel Spin-on (3313306)..... <b>BF596 +</b></p> <p>Fuel Spin-on (158172)..... <b>BF957 +</b></p> <p>Air (Don. P181003)..... <b>PA2482</b></p> <p>Air (Don. P181007)..... <b>PA2312</b></p> <p>Air (Don. P181008)..... <b>PA2317 +</b></p> <p>Air (Don. P181009)..... <b>PA2357 +</b></p> <p>Breather Ele. (w/Turbo) (255963) <b>PA643</b></p> <p>Breather Ele. (w/o Turbo) (256837)..... <b>PA1627</b></p> <p>Coolant Spin-on..... <b>BW5071</b></p> <hr/> <p>C500 w/Detroit Diesel 6-71 (7.0L) Eng.</p> <p>F-F Lube (23530407)..... <b>B95 +</b></p> <p>F-F Lube (23530408)..... <b>B95-MPG +</b></p> <p>P. Fuel (23530706)..... <b>BF5800 +</b></p> <p>S. Fuel (23530707)..... <b>BF5810</b></p> <p>S. Fuel (23530645)..... <b>BF5815</b></p> <p>Trans. Spin-on (Fuller 4304827).. <b>BT223</b></p> <p>Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b></p> <hr/> <p>C500 w/Detroit Diesel 6V-92N (9.0L) Eng.</p> <p>F-F Lube (23530407)..... <b>B95 +</b></p> <p>F-F Lube (23530408)..... <b>B95-MPG +</b></p> <p>P. Fuel (23530706)..... <b>BF5800 +</b></p> <p>S. Fuel (23530707)..... <b>BF5810</b></p> <p>S. Fuel (23530645)..... <b>BF5815</b></p> <p>Trans. Spin-on (Fuller 4304827).. <b>BT223</b></p> <p>Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b></p>	<p>C500 w/Detroit Diesel 8V-92 (12.1L) Eng.</p> <p>F-F Lube Ele..... <b>P20-HD +</b></p> <p>F-F Lube Spin-on..... <b>B95 +</b></p> <p>P. Fuel Spin-on..... <b>BF5800 +</b></p> <p>S. Fuel Spin-on..... <b>BF5810</b></p> <p>Air (Don. P181007)..... <b>PA2312</b></p> <p>Air (Don. P181008)..... <b>PA2317 +</b></p> <hr/> <p>C500 w/Cummins ISX 15.0 (14.9L) Eng. (2018)</p> <p>Dual-Flow Lube (4367100)..... <b>BD50000</b></p> <p>Fuel (Fleetguard FF5825NN)..... <b>BF46129</b></p> <p>Fuel (Fleetguard FF5776)..... <b>BF9885</b></p> <p>Crankcase Breather (3691476).. <b>CV15000</b></p> <hr/> <p>C500 w/Cummins ISX 15.0 (14.9L) Eng. (2019)</p> <p>Dual-Flow Lube (4367100)..... <b>BD50000</b></p> <p>Fuel (5365988)..... <b>BF46129</b></p> <hr/> <p>C500 w/Detroit Diesel Series 60 (12.7L) Eng. (To 12/03)</p> <p>Lube..... <b>[2] B495</b></p> <p>P. Fuel (23518481)..... <b>BF5800 +</b></p> <p>S. Fuel (23518482)..... <b>BF5810</b></p> <p>Air (KW852M)..... <b>LL2317 +</b></p> <p>Air Dryer (Bendix 5008414)..... <b>BA5374 +</b></p> <p>Coolant (w/4 Units BTE)..... <b>BW5137</b></p> <p>Opt. Trans. (Fuller 17237)..... <b>B2 +</b></p> <p>Steering..... <b>P528</b></p> <hr/> <p>C500 w/Detroit Diesel Series 60 (12.7L) Eng. (12/03-on)</p> <p>Lube..... <b>[2] B495</b></p> <p>P. Fuel (23518481)..... <b>BF5800 +</b></p> <p>S. Fuel (23533726)..... <b>BF5816</b></p> <p>Air (KW852M)..... <b>LL2317 +</b></p> <p>Air Dryer (Bendix 5008414)..... <b>BA5374 +</b></p> <p>Coolant (w/4 Units BTE)..... <b>BW5137</b></p> <p>Opt. Trans. (Fuller 17237)..... <b>B2 +</b></p> <p>Steering..... <b>P528</b></p> <hr/> <p>C523, C524, C525, C823, C824, C825 w/Cummins Eng.</p> <p>F-F Lube Bag..... <b>P996</b></p> <p>F-F Lube Ele..... <b>P999-HD</b></p> <p>F-F Lube Spin-on..... <b>B196 +</b></p> <p>B-P Lube Ele..... <b>C750-E +</b></p> <p>Fuel/Water Separator..... <b>BF1212 +</b></p> <p>Fuel Spin-on..... <b>BF596 +</b></p> <p>Fuel Spin-on..... <b>BF948 +</b></p> <p>Fuel Spin-on..... <b>BF957 +</b></p> <p>Breather Ele. (w/Turbo) (255963) <b>PA643</b></p> <p>Breather Ele. (w/o Turbo) (256837)..... <b>PA1627</b></p> <p>Turbocharger..... <b>BT112</b></p> <hr/> <p>C540 w/Cat 3408 (18.0L) Eng.</p> <p>F-F Lube (1R0716)..... <b>[2] B99 +</b></p> <p>Fuel Ele. (9M2342)..... <b>[2] PF935</b></p> <p>Fuel Spin-on (Std. Efficiency) (4N5823)..... <b>BF614 +</b></p> <p>Fuel Spin-on (High Efficiency Vers.) (1R0749)..... <b>BF7587 +</b></p> <p>Trans. Spin-on (Fuller 4304827).. <b>BT223</b></p>	<p>C540 w/Cat 3408 (18.0L) Eng. (Cont'd)</p> <p>Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b></p> <hr/> <p>C540 w/Cummins N14 (14.0L) Eng.</p> <p>F-F Lube (Fleetguard LF670SC).. <b>B196 +</b></p> <p>Dual-Flow Lube (3318853)..... <b>BD103 +</b></p> <p>B-P Lube (3304232)..... <b>B7577</b></p> <p>Fuel (154789)..... <b>BF957-D +</b></p> <p>Coolant (3315116)..... <b>BW5071</b></p> <p>Trans. Spin-on (Fuller 4304827).. <b>BT223</b></p> <p>Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b></p> <hr/> <p>C550 w/Cat 3306 (10.5L) Eng.</p> <p>Lube Ele. (w/Paper Wrapper) (1R0659)..... <b>PT670</b></p> <p>F-F Lube Spin-on (1R0716)..... <b>B99 +</b></p> <p>F-F Lube Spin-on (Standard Vers.) (1R0739)..... <b>B76 +</b></p> <p>F-F Lube Spin-on (Severe Service) (1R0739)..... <b>B76-SS +</b></p> <p>P. Fuel Ele. (9M2341)..... <b>PF935</b></p> <p>P. Fuel Spin-on (1R0740)..... <b>BF970 +</b></p> <p>S. Fuel Spin-on (1R0750)..... <b>BF7633 +</b></p> <p>Trans. Spin-on (Fuller 4304827).. <b>BT223</b></p> <p>Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b></p> <hr/> <p>C550 w/Cat 3306 (10.5L) Eng.</p> <p>Lube Ele. (w/Metal Wrapper) (1R0659)..... <b>PT7332</b></p> <hr/> <p>C550 w/Cat 3406 (14.6L) Eng.</p> <p>F-F Lube (Std. Efficiency) (1R0716)..... <b>B99 +</b></p> <p>F-F Eng. Lube (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b></p> <p>Fuel/Water Separator Spin-on (2568753)..... <b>BF1259</b></p> <p>P. Fuel Ele. (9M2342)..... <b>[2] PF935</b></p> <p>Fuel Spin-on (Std. Efficiency) (4N5823)..... <b>BF614 +</b></p> <p>Fuel Spin-on (High Efficiency Vers.) (1R0749)..... <b>BF7587 +</b></p> <p>Trans. Spin-on (Fuller 4304827).. <b>BT223</b></p> <p>Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b></p> <hr/> <p>C550 w/Cat C15 Eng.</p> <p>Lube (1R1808)..... <b>B7299 +</b></p> <p>Fuel (1R0749)..... <b>BF7587 +</b></p> <hr/> <p>C550 w/Cummins ISX Eng.</p> <p>Dual-Flow Lube (Fleetguard LF9080)..... <b>BD7154 +</b></p> <p>Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b></p> <p>Fuel (Fleetguard FF2200)..... <b>BF7766</b></p> <p>Fuel (Standard) (Fleetguard FF5776)..... <b>BF9885 +</b></p> <p>Fuel (Upgrade) (Fleetguard FF5825NN)..... <b>BF46129</b></p>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)
C550 w/Cummins ISX Eng. (Cont'd)	C550 w/Detroit Diesel Series 60 (12.7L) Eng. (1993-on) (Cont'd)	K100 w/Cat 1693T, 1693TA Eng. (Cont'd)
22 29/32 In. Std. Radial Seal Air (P614986)..... [2] RS5288	Opt. Trans. Spin-on (Fuller 17237)..... B2+	Air Comp. Breather..... PA1704
22 29/32 In. Radial Seal XP Air (Paccar P614986)..... [2] RS5288XP	C550 w/Detroit Diesel Series 60 (12.7L) Eng. (To 1993)	K100 w/Cat 3306 (10.5L) Eng.
23 23/32 In. Radial Seal Air (Don. P534816)..... [2] RS3539	Lube (23530573)..... [2] B495	Lube (Standard Vers.) (1R0739).. B76+
23 23/32 In. Radial Seal XP Air (Don. P534816)..... [2] RS3539XP	Lube (Don. DELF3998)..... [2] B495-SS	Lube (Severe Service) (1R0739).. B76-SS+
Air Dryer (AD-IS System) (Bendix 5008414)..... BA5374+	B-P Lube (23530413)..... B7577	Fuel Spin-on (1R0740)..... BF970+
Breather (4312013)..... CV15000	Fuel/Water Separator Spin-on (w/Drain) (23535985)..... BF5813+	Air (Don. P150694)..... PA2660
Coolant (Fleetguard WF2127)..... B5087	Fuel/Water Separator Spin-on (Open End for Bowl) (23535985).. BF5813-O+	Air (Don. P181000)..... PA1637-FN
Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	P. Fuel (23530706)..... BF5800+	Air (Don. P181003)..... PA2482
Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	S. Fuel (23530707)..... BF5810	Air (Don. P181008)..... PA2317+
Trans. Spin-on (Fuller 4304827).. BT223	Coolant (23516489)..... BW5200	Tube-Type Air (Farr 71338-002).. PA2650
Opt. Trans. Spin-on (Fuller 17237)..... B2+	Trans. Spin-on (Fuller 4304827).. BT223	K100 w/Cat 3406 (14.6L) Eng.
Diesel Exhaust Fluid (2888182).. PE17000	Opt. Trans. Spin-on (Fuller 17237)..... B2+	Lube Spin-on..... B99+
C500 w/Cummins L10 (10.0L) Eng.	C800 w/Cat C15 Eng.	Fuel/Water Separator (Fleetguard FS1212)..... BF1212+
F-F Lube (Fleetguard LF670SC).. B196+	Lube..... B99+	Fuel Spin-on..... BF614+
Dual-Flow Lube (3318853)..... BD103+	Fuel Spin-on..... BF7587+	Air (Don. P150694)..... PA2660
B-P Lube (3304232)..... B7577	G500 w/Cat C15 Eng.	Air (Don. P181001)..... PA1676-FN+
Fuel (154789)..... BF957-D+	Lube (1R0716)..... B99+	Air (Don. P181007)..... PA2312
Coolant (w/4 Units BTA+) (3315116)..... BW5071	Fuel/Water Separator (Open End for Bowl) (1335673)..... BF1395-O	Air (Don. P181008)..... PA2317+
Coolant (w/15 Units BTA+) (Fleetguard WF2075)..... BW5075	Fuel/Water Separator (w/Drain) (1335673)..... BF1265	Air (Don. P181009)..... PA2357+
Trans. Spin-on (Fuller 4304827).. BT223	Fuel/Water Separator (w/Sensor Port) (1335673)..... BF1395-SP	Tube-Type Air (Farr 71338-002).. PA2650
Opt. Trans. Spin-on (Fuller 17237)..... B2+	Fuel (1R-0749)..... BF7587+	Coolant Spin-on..... BW5137
C550 w/Cummins N14 Eng.	Coolant (9N-6123)..... BW5139	Steering (Fleetguard LF637)..... P528
F-F Lube (Fleetguard LF670SC).. B196+	Trans. (Fuller 4304827)..... BT223	K100 w/Cat 3408 (18.0L) Eng.
B-P Lube (3304232)..... B7577	Hustler w/Cat 3306 Eng.	Lube Spin-on..... B99+
Dual-Flow Lube (3318853)..... BD103+	Lube Spin-on (Standard Vers.) (1R0739)..... B76	Fuel/Water Separator (Fleetguard FS1212)..... BF1212+
Fuel/Water Separator (Fleetguard FS1000)..... BF1259	Box-Style Fuel/Water Separator. BF912	Fuel Spin-on..... BF614+
Fuel Ele. (8H7204)..... PF935	Fuel Spin-on (1R0740)..... BF970+	Air (Don. P181001)..... PA1676-FN+
Fuel Spin-on (154789)..... BF957-D+	K100 w/Allis Chalmers 21000, 25000 Eng.	Air (Don. P181007)..... PA2312
Air (Don. P537791)..... [2] PA2705	F-F Lube Ele..... P20-HD+	Air (Don. P181008)..... PA2317+
Air Dryer (AD-IS System) (Bendix 5008414)..... BA5374+	S. Fuel Ele. (4052172)..... PF910	Air (Don. P181009)..... PA2357+
Coolant (Fleetguard WF2122)..... B5088+	Air (Don. P116918)..... PA2317+	Air (Don. P150694)..... PA2660
Trans. (Fuller 4304827)..... BT223	Air (Don. P117331)..... PA1637-FN	Tube-Type Air (Farr 71338-002).. PA2650
Steering (Nelson 83804E)..... P528	K100 w/Cat 1673C, 1674 Eng.	Coolant Spin-on..... BW5137
C550 w/Detroit Diesel Series 60 (12.7L) Eng. (1993-on)	Lube Ele..... PT670	Steering (Fleetguard LF637)..... P528
Lube (23530573)..... [2] B495	Box-Style Fuel/Water Separator. BF912	K100 w/Cummins L10 (10.0L) Eng.
Lube (Don. DELF3998)..... [2] B495-SS	Fuel Spin-on..... BF970+	F-F Lube (Fleetguard LF670SC).. B196+
Fuel/Water Separator Spin-on (w/Drain) (23535985)..... BF5813+	Air (Don. P117331)..... PA1637-FN	Dual-Flow Lube (3318853)..... BD103+
Fuel/Water Separator Spin-on (Open End for Bowl) (23535985).. BF5813-O+	Air (Don. P117797)..... PA2312	B-P Lube (3304232)..... B7577
P. Fuel (23530706)..... BF5800+	Air Comp. Breather..... PA1704	Fuel (154789)..... BF957-D+
S. Fuel (23530707)..... BF5810	K100 w/Cat 1693T, 1693TA Eng.	Coolant (w/4 Units BTA+) (3315116)..... BW5071
Coolant (23516489)..... BW5200	Lube Ele. (To S/N 65B6080)..... [2] PT88-HD	Coolant (w/15 Units BTA+) (Fleetguard WF2075)..... BW5075
Trans. Spin-on (Fuller 4304827).. BT223	Lube Spin-on (S/N 65B6080-up). B99+	Trans. Spin-on (Fuller 4304827).. BT223
	Fuel Ele. (To S/N 65B782)..... [2] PF823+	Opt. Trans. Spin-on (Fuller 17237)..... B2+
	Fuel Spin-on (S/N 65B782-up).... [2] BF970+	K100 w/Cummins N14 (14.0L) Eng.
	Air (Don. P116918)..... PA2317+	F-F Lube Bag..... P996
	Air (Don. P117332)..... PA1676-FN+	F-F Lube Ele..... P999-HD
		F-F Lube Spin-on..... B196+
		Dual-Flow Lube..... BD103+
		B-P Lube Ele..... C750-E+
		B-P Lube Spin-on..... B7577
		Fuel/Water Separator..... BF1212+
		4 3/8 In. Fuel Spin-on..... BF948+

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)
<b>K100 w/Cummins N14 (14.0L) Eng. (Cont'd)</b> 5 3/4 In. Fuel Spin-on..... <b>BF957 +</b> 11 7/32 In. Fuel Spin-on..... <b>BF596 +</b> Air (Don. P116918)..... <b>PA2317 +</b> Air (Don. P117331)..... <b>PA1637-FN</b> Air (Don. P117332)..... <b>PA1676-FN +</b> Air (Don. P117797)..... <b>PA2312</b> Air (Don. P150694)..... <b>PA2660</b> Air (Don. P181009)..... <b>PA2357 +</b> Air (Don. P181011)..... <b>PA2458</b> Tube-Type Air (Farr 71338-002).. <b>PA2650</b> Breather Ele. (w/Turbo) (255963) <b>PA643</b> Breather Ele. (w/o Turbo) (256837)..... <b>PA1627</b> Turbocharger..... <b>BT112</b>	<b>K100 w/WT225 (9.1L) Eng.</b> F-F Lube (3313281)..... <b>B205 +</b> B-P Lube (3304232)..... <b>B7577</b> Fuel (158172)..... <b>BF957 +</b> Coolant (w/4 Units BTA+) (3315116)..... <b>BW5071</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	<b>K100E w/Cat 3408 (18.0L) Eng.</b> Lube Spin-on..... <b>B99 +</b> Fuel/Water Separator (Fleetguard FS1212)..... <b>BF1212 +</b> Fuel Spin-on..... <b>BF614 +</b> Air (Don. P150694)..... <b>PA2660</b> Air (Don. P181001)..... <b>PA1676-FN +</b> Air (Don. P181007)..... <b>PA2312</b> Air (Don. P181008)..... <b>PA2317 +</b> Air (Don. P181009)..... <b>PA2357 +</b> Tube-Type Air (Farr 71338-002).. <b>PA2650</b> Coolant Spin-on..... <b>BW5137</b> Steering (Fleetguard LF637)..... <b>P528</b>
<b>K100 w/Detroit Diesel 6V-92N (9.0L) Eng.</b> F-F Lube Ele..... <b>P20-HD +</b> F-F Lube Spin-on..... <b>B95 +</b> B-P Lube Ele..... <b>C750-E +</b> P. Fuel Spin-on..... <b>BF5800 +</b> S. Fuel Spin-on..... <b>BF5810</b> Air (Don. P116918)..... <b>PA2317 +</b> Air (Don. P117331)..... <b>PA1637-FN</b> Air (Don. P117332)..... <b>PA1676-FN +</b> Air (Don. P117797)..... <b>PA2312</b> Air (Don. P129396)..... <b>PA3951</b> Air (Don. P150694)..... <b>PA2660</b> Air (Don. P181003)..... <b>PA2482</b> Air (Don. P181009)..... <b>PA2357 +</b> Air (Don. P181011)..... <b>PA2458</b> Tube-Type Air (Farr 71338-002).. <b>PA2650</b>	<b>K100 w/WT903 (14.8L) Eng.</b> F-F Lube Ele. (158139)..... <b>P999-HD</b> F-F Lube Spin-on (3313279)..... <b>B196 +</b> B-P Lube Ele. (256838)..... <b>C750-E +</b> B-P Lube Spin-on (3313283)..... <b>B7577</b> Fuel (154789)..... <b>BF957-D +</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	<b>K100E w/Cat C11 (11.1L) Eng.</b> Lube (1R1808)..... <b>B7299 +</b> Fuel/Water Separator (3329289) <b>BF1259</b> Fuel (Standard Vers.) (4N5823).. <b>BF614 +</b> Fuel (High Efficiency Vers.) (1R0749)..... <b>BF7587 +</b> Fuel (1R0762)..... <b>BF7753</b> Radial Seal O. Air (3551814C1).. <b>RS4862</b> Radial Seal I. Air (3551815C1)... <b>RS4863</b> Cab Air (2506656C1)..... <b>PA4985</b> Air Dryer (Bendix 107794)..... <b>BA5377</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>
<b>K100 w/Detroit Diesel 8V-92 (12.1L) Eng.</b> F-F Lube Ele..... <b>P20-HD +</b> F-F Lube Spin-on..... <b>B95 +</b> B-P Lube Ele..... <b>C750-E +</b> P. Fuel Spin-on..... <b>BF5800 +</b> S. Fuel Spin-on..... <b>BF5810</b> Air (Don. P116918)..... <b>PA2317 +</b> Air (Don. P117331)..... <b>PA1637-FN</b> Air (Don. P117332)..... <b>PA1676-FN +</b> Air (Don. P117797)..... <b>PA2312</b> Air (Don. P129396)..... <b>PA3951</b> Air (Don. P150694)..... <b>PA2660</b> Air (Don. P181003)..... <b>PA2482</b> Air (Don. P181009)..... <b>PA2357 +</b> Air (Don. P181011)..... <b>PA2458</b> Tube-Type Air (Farr 71338-002).. <b>PA2650</b>	<b>K100E w/Cat 3176 (10.3L) Eng.</b> F-F Lube (Std. Efficiency) (1R0716)..... <b>B99 +</b> F-F Eng. Lube (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> F-F Eng. Lube (1R0713)..... <b>[2] BT230 +</b> F-F Lube (1R0714)..... <b>[2] B75</b> Opt. B-P Lube (1W8845)..... <b>B7577</b> P. Fuel Ele. (9M2342)..... <b>[2] PF935</b> P. Fuel Spin-on (1R0740)..... <b>BF970 +</b> S. Fuel Spin-on (1R0750)..... <b>BF7633 +</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	<b>K100E w/Cummins ISM 10.8 (10.8L) Eng.</b> Dual-Flow Lube (Fleetguard LF9001)..... <b>BD7154 +</b> Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> Coolant (w/o Chemical) (Fleetguard WF2127)..... <b>B5087</b> Coolant (Controlled Release BTA+) (Fleetguard WF2121)..... <b>BW5250</b> Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> Coolant (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b>
<b>K100 w/GMC 12V-71 Eng.</b> F-F Lube Ele..... <b>[2] P20-HD +</b> B-P Lube Ele..... <b>C750-E +</b> P. Fuel Spin-on..... <b>BF5800 +</b> S. Fuel Spin-on..... <b>BF5810</b> Air (Don. P117331)..... <b>[2] PA1637-FN</b> Air (Don. P117797)..... <b>[2] PA2312</b> Tube-Type Air (Farr 71338-002).. <b>PA2650</b>	<b>K100E w/Cat 3306 (10.5L) Eng.</b> Lube (Standard Vers.) (1R0739).. <b>B76 +</b> Lube (Severe Service) (1R0739).. <b>B76-SS +</b> Fuel Spin-on (1R0740)..... <b>BF970 +</b> Air (Don. P150694)..... <b>PA2660</b> Air (Don. P181000)..... <b>PA1637-FN</b> Air (Don. P181003)..... <b>PA2482</b> Air (Don. P181008)..... <b>PA2317 +</b> Tube-Type Air (Farr 71338-002).. <b>PA2650</b>	<b>K100E w/Cat 3406 (14.6L) Eng.</b> Lube Spin-on..... <b>B99 +</b> Fuel/Water Separator (Fleetguard FS1212)..... <b>BF1212 +</b> Fuel Spin-on..... <b>BF614 +</b> Air (Don. P150694)..... <b>PA2660</b> Air (Don. P181001)..... <b>PA1676-FN +</b> Air (Don. P181007)..... <b>PA2312</b> Air (Don. P181008)..... <b>PA2317 +</b> Air (Don. P181009)..... <b>PA2357 +</b> Tube-Type Air (Farr 71338-002).. <b>PA2650</b> Coolant Spin-on..... <b>BW5137</b> Steering (Fleetguard LF637)..... <b>P528</b>
		<b>K100E w/Cummins L10 (10.0L) Eng.</b> F-F Lube (Fleetguard LF670SC).. <b>B196 +</b> Dual-Flow Lube (3318853)..... <b>BD103 +</b> B-P Lube (3304232)..... <b>B7577</b> Fuel (154789)..... <b>BF957-D +</b> Coolant (w/4 Units BTA+) (3315116)..... <b>BW5071</b> Coolant (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>

+ See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)
<b>K100E w/Cummins M11 (10.8L) Eng. (To 12/1995)</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Fuel/Water Separator</b> (3308638).. <b>BF1212 +</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>K100E w/Detroit Diesel 6V-92N (9.0L) Eng. (Cont'd)</b> <b>Air</b> (Don. P129396)..... <b>PA3951</b> <b>Air</b> (Don. P150694)..... <b>PA2660</b> <b>Air</b> (Don. P181003)..... <b>PA2482</b> <b>Air</b> (Don. P181009)..... <b>PA2357 +</b> <b>Air</b> (Don. P181011)..... <b>PA2458</b> <b>Tube-Type Air</b> (Farr 71338-002).. <b>PA2650</b>	<b>K104 w/Cat C16 Eng.</b> <b>Lube</b> (To 1/2004) (1R0716)..... <b>B99 +</b> <b>Lube</b> (1/2004-on) (1R1808)..... <b>B7299 +</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (1335673)..... <b>BF1395-O</b> <b>Fuel/Water Separator</b> (w/Drain) (1335673)..... <b>BF1265</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (1335673)..... <b>BF1395-SP</b> <b>Fuel</b> (1R0749)..... <b>BF7587 +</b> <b>Coolant</b> (9N6123)..... <b>BW5139</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b>
<b>K100E w/Cummins M11 (10.8L) Eng. (12/1995-on)</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Fuel/Water Separator</b> (3329289).. <b>BF1259</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>K100E w/Detroit Diesel 8V-92 (12.1L) Eng.</b> <b>F-F Lube Ele.</b> ..... <b>P20-HD +</b> <b>F-F Lube Spin-on</b> ..... <b>B95 +</b> <b>B-P Lube Ele.</b> ..... <b>C750-E +</b> <b>P. Fuel Spin-on</b> ..... <b>BF5800 +</b> <b>S. Fuel Spin-on</b> ..... <b>BF5810</b> <b>Air</b> (Don. P116918)..... <b>PA2317 +</b> <b>Air</b> (Don. P117331)..... <b>PA1637-FN</b> <b>Air</b> (Don. P117332)..... <b>PA1676-FN +</b> <b>Air</b> (Don. P117797)..... <b>PA2312</b> <b>Air</b> (Don. P129396)..... <b>PA3951</b> <b>Air</b> (Don. P150694)..... <b>PA2660</b> <b>Air</b> (Don. P181003)..... <b>PA2482</b> <b>Air</b> (Don. P181009)..... <b>PA2357 +</b> <b>Air</b> (Don. P181011)..... <b>PA2458</b> <b>Tube-Type Air</b> (Farr 71338-002).. <b>PA2650</b>	<b>K104 w/Cummins ISX Eng.</b> <b>Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154 +</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (Fleetguard FS1040)..... <b>BF1277-SPS</b> <b>Fuel/Water Separator</b> (Upgrade) (Fleetguard FS1007)..... <b>BF1274-SP</b> <b>Coolant</b> (Fleetguard WF2126)..... <b>BW5086</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b>
<b>K100E w/Cummins NTC (14.0L) Eng.</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>F-F Lube Ele.</b> (158139)..... <b>P999-HD</b> <b>F-F Lube Spin-on</b> (3313279)..... <b>B196 +</b> <b>B-P Lube Ele.</b> (256838)..... <b>C750-E +</b> <b>B-P Lube Spin-on</b> (3313283)..... <b>B7577</b> <b>Fuel/Water Separator</b> (3308638).. <b>BF1212 +</b> <b>Fuel</b> (158172)..... <b>BF957 +</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>K100E w/Detroit Diesel Series 60 (12.7L) Eng.</b> <b>F-F Lube</b> (23527033)..... <b>[2] B495</b> <b>B-P Lube</b> (23518672)..... <b>B7577</b> <b>Fuel/Water Separator</b> (Fleetguard FS1212)..... <b>BF1212 +</b> <b>Fuel</b> (23518482)..... <b>BF5810</b> <b>Air</b> (Don. P150694)..... <b>PA2660</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Fleetguard LF637)..... <b>P528</b>	<b>K104 w/Cummins Signature 500 Eng.</b> <b>Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154 +</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (Fleetguard FS1040)..... <b>BF1277-SPS</b> <b>Fuel/Water Separator</b> (Upgrade) (Fleetguard FS1007)..... <b>BF1274-SP</b> <b>Coolant</b> (Fleetguard WF2126)..... <b>BW5086</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b>
<b>K100E w/Cummins N14 (14.0L) Eng.</b> <b>F-F Lube Bag</b> ..... <b>P996</b> <b>F-F Lube Ele.</b> ..... <b>P999-HD</b> <b>F-F Lube Spin-on</b> ..... <b>B196 +</b> <b>Dual-Flow Lube</b> ..... <b>BD103 +</b> <b>B-P Lube Ele.</b> ..... <b>C750-E +</b> <b>B-P Lube Spin-on</b> ..... <b>B7577</b> <b>Fuel/Water Separator</b> ..... <b>BF1212 +</b> <b>4 3/8 In. Fuel Spin-on</b> ..... <b>BF948 +</b> <b>5 3/4 In. Fuel Spin-on</b> ..... <b>BF957 +</b> <b>11 7/32 In. Fuel Spin-on</b> ..... <b>BF596 +</b> <b>Air</b> (Don. P116918)..... <b>PA2317 +</b> <b>Air</b> (Don. P117331)..... <b>PA1637-FN</b> <b>Air</b> (Don. P117332)..... <b>PA1676-FN +</b> <b>Air</b> (Don. P117797)..... <b>PA2312</b> <b>Air</b> (Don. P150694)..... <b>PA2660</b> <b>Air</b> (Don. P181009)..... <b>PA2357 +</b> <b>Air</b> (Don. P181011)..... <b>PA2458</b> <b>Tube-Type Air</b> (Farr 71338-002).. <b>PA2650</b> <b>Breather Ele.</b> (w/Turbo) (255963) <b>PA643</b> <b>Breather Ele.</b> (w/o Turbo) (256837)..... <b>PA1627</b> <b>Turbocharger</b> ..... <b>BT112</b>	<b>K100G Prime Mover w/Cummins N14+ Eng.</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Fuel/Water Separator</b> (Fleetguard FS1000)..... <b>BF1259</b> <b>Coolant</b> (3844234)..... <b>BW5076</b>	<b>K104 w/Detroit Diesel Series 60 Eng.</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b>
<b>K100E w/Detroit Diesel 6V-92N (9.0L) Eng.</b> <b>F-F Lube Ele.</b> ..... <b>P20-HD +</b> <b>F-F Lube Spin-on</b> ..... <b>B95 +</b> <b>B-P Lube Ele.</b> ..... <b>C750-E +</b> <b>P. Fuel Spin-on</b> ..... <b>BF5800 +</b> <b>S. Fuel Spin-on</b> ..... <b>BF5810</b> <b>Air</b> (Don. P116918)..... <b>PA2317 +</b> <b>Air</b> (Don. P117331)..... <b>PA1637-FN</b> <b>Air</b> (Don. P117332)..... <b>PA1676-FN +</b> <b>Air</b> (Don. P117797)..... <b>PA2312</b>	<b>K104 w/Cat C12 Eng.</b> <b>F-F Lube</b> (1R0716)..... <b>B99 +</b> <b>B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Coolant</b> (4 Units BTE) (9N3717).. <b>BW5137</b> <b>Coolant</b> (8 Units BTE) (9N3718).. <b>BW5139</b>	<b>K104 w/Detroit Diesel Series 60 Eng.</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>K108 w/Cat C15 Eng.</b> <b>Lube</b> (1R-1808)..... <b>B7299 +</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (1335673)..... <b>BF1395-O</b> <b>Fuel/Water Separator</b> (w/Drain) (1335673)..... <b>BF1265</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (1335673)..... <b>BF1395-SP</b> <b>Fuel</b> (1R-0749)..... <b>BF7587 +</b> <b>Coolant</b> (9N-6123)..... <b>BW5139</b>
<b>K100E w/Detroit Diesel 6V-92N (9.0L) Eng.</b> <b>F-F Lube Ele.</b> ..... <b>P20-HD +</b> <b>F-F Lube Spin-on</b> ..... <b>B95 +</b> <b>B-P Lube Ele.</b> ..... <b>C750-E +</b> <b>P. Fuel Spin-on</b> ..... <b>BF5800 +</b> <b>S. Fuel Spin-on</b> ..... <b>BF5810</b> <b>Air</b> (Don. P116918)..... <b>PA2317 +</b> <b>Air</b> (Don. P117331)..... <b>PA1637-FN</b> <b>Air</b> (Don. P117332)..... <b>PA1676-FN +</b> <b>Air</b> (Don. P117797)..... <b>PA2312</b>	<b>K104 w/Cat C15 Eng.</b> <b>Lube</b> (1R0716)..... <b>B99 +</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (1335673)..... <b>BF1395-O</b> <b>Fuel/Water Separator</b> (w/Drain) (1335673)..... <b>BF1265</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (1335673)..... <b>BF1395-SP</b> <b>Fuel</b> (1R0749)..... <b>BF7587 +</b> <b>Coolant</b> (9N6123)..... <b>BW5139</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b>	<b>K108 w/Cummins ISX Eng.</b> <b>Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154 +</b> <b>Dual-Flow Lube</b> (Fleetguard LF9031)..... <b>BD7509 +</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel</b> (Fleetguard FF2200)..... <b>BF7766</b> <b>Coolant</b> (Fleetguard WF2126)..... <b>BW5086</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b>

+ See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)
K120 w/Cat 3406E Eng. Lube (1R0716)..... <b>B99 +</b> Fuel (1R-0749)..... <b>BF7587 +</b>	K270 w/Paccar PX-6 Eng. (Cont'd) Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Diesel Exhaust Fluid (5303604).. <b>PE17000</b>	K270 w/Paccar PX-7 (6.7L) Eng. (2020) (Cont'd) Air Dryer (Wabco R950068A)..... <b>BA5379</b> Crankcase Breather (4936636).... <b>CV15010</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Steering (229348PAC)..... <b>P106-HD</b>
K121, K122, K123, K124, K125 w/Cummins Eng. F-F Lube Bag..... <b>P996</b> F-F Lube Ele..... <b>P999-HD</b> F-F Lube Spin-on..... <b>B196 +</b> B-P Lube Ele..... <b>C750-E +</b> Fuel/Water Separator..... <b>BF1212 +</b> 4 3/8 In. Fuel Spin-on..... <b>BF948 +</b> 5 3/4 In. Fuel Spin-on..... <b>BF957 +</b> 11 7/32 In. Fuel Spin-on..... <b>BF596 +</b> Breather Ele. (w/Turbo) (255963) <b>PA643</b> Breather Ele. (w/o Turbo) (256837)..... <b>PA1627</b> Turbocharger..... <b>BT112</b>	K270 w/Paccar PX-7 (6.7L) Eng. (2014-18) Lube (Fleetguard LF9104)..... <b>B7177</b> Fuel/Water Separator (Fleetguard FS1065)..... <b>BF1378-SPS</b> Fuel (Fleetguard FF63009)..... <b>BF63000</b> Radial Seal Air (1679397)..... <b>RS5692</b> Cab Air (SR2000059)..... <b>PA30281</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Breather (Rear Eng. Mounted) (Fleetguard CV50607)..... <b>CV15000</b> Crankcase Breather (4936636).... <b>CV15010</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Diesel Exhaust Fluid (5303604).. <b>PE17000</b> Diesel Exhaust Fluid (5303604).. <b>PE17000</b>	K270 w/Paccar PX-7 (6.7L) Eng. (2021) Lube (3937736)..... <b>B7177</b> Fuel (5303743)..... <b>BF63000</b> Crankcase Breather (4936636).... <b>CV15010</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>
K130 w/Cummins C8.3 (8.3L) Eng. Lube..... <b>B205 +</b> Opt. Fuel/Water Separator..... <b>BF1226</b> P. Fuel/Water Separator..... <b>BF1280 +</b> S. Fuel..... <b>BF788</b> Air..... <b>LL2521</b>	K270 w/Paccar PX-7 (6.7L) Eng. (2019) Lube (3937736)..... <b>B7177</b> Fuel/Water Separator (Fleetguard FS1065)..... <b>BF1378-SPS</b> Fuel (5303743)..... <b>BF63000</b> Radial Seal Air (1679397)..... <b>RS5692</b> Air Dryer (Wabco R950068A)..... <b>BA5379</b> Crankcase Breather (4936636).... <b>CV15010</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Steering (229348)..... <b>P106-HD</b> Diesel Exhaust Fluid (4388378).. <b>PE17002 KIT</b>	K270 w/Paccar PX-7 (6.7L) Eng. (2022) Lube (3937736)..... <b>B7177</b>
K150 w/Cummins C8.3 (8.3L) Eng. Lube..... <b>B205 +</b> Opt. Fuel/Water Separator..... <b>BF1226</b> P. Fuel/Water Separator..... <b>BF1280 +</b> S. Fuel..... <b>BF788</b> Air..... <b>LL2521</b>	K270 w/Paccar PX-6 Eng. (Hybrid) Lube (Fleetguard LF3970)..... <b>B7177</b> Fuel/Water Separator (Fleetguard FS19689)..... <b>BF7942</b> Fuel (Fleetguard FF5421)..... <b>BF7966</b> Radial Seal Air (Don. P527484).... <b>RS2863</b> Radial Seal XP Air (Don. P527484)..... <b>RS2863XP</b> Crankcase Breather (4936636).... <b>CV15010</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	K300 w/Cummins 6BT5.9 (5.9L) Eng. Lube (3914395)..... <b>BT339 +</b> Fuel/Water Separator (3925274). <b>BF1280 +</b> Fuel (3903640)..... <b>BF788</b>
K220 w/Cummins C8.3 (8.3L) Eng. Lube..... <b>B205 +</b> Opt. Fuel/Water Separator..... <b>BF1226</b> P. Fuel/Water Separator..... <b>BF1280 +</b> S. Fuel..... <b>BF788</b>	K270 w/Paccar PX-6 Eng. Lube (Fleetguard LF3970)..... <b>B7177</b> Fuel/Water Separator (Fleetguard FS1065)..... <b>BF1378-SPS</b> Fuel (Fleetguard FF5632)..... <b>BF7940</b> Radial Seal Air (1679397)..... <b>RS5692</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Crankcase Breather (Fleetguard CV52001)..... <b>CV15010</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	K300 w/Cummins 6CT8.3 (8.3L) Eng. F-F Lube (3313281)..... <b>B205 +</b> Dual-Flow Lube (3318853)..... <b>BD103 +</b> Fuel/Water Separator (3925274). <b>BF1280 +</b> Fuel (3903640)..... <b>BF788</b>
K260 w/Paccar PX-6 Eng. (2020) Lube (3937736)..... <b>B7177</b> Fuel/Water Separator (Fleetguard FS1065)..... <b>BF1378-SPS</b> Fuel (Fleetguard FF63009)..... <b>BF63000</b> Radial Seal Air (1679397)..... <b>RS5692</b>	K270 w/Paccar PX-7 (6.7L) Eng. (2020) Lube (3937736)..... <b>B7177</b> Fuel/Water Separator (Fleetguard FS1065)..... <b>BF1378-SPS</b> Fuel (Fleetguard FF63009)..... <b>BF63000</b> Radial Seal Air (1679397)..... <b>RS5692</b>	K300 w/Cummins ISB (5.9L) Eng. F-F Lube (Fleetguard LF3937).... <b>B7177</b> F-F Lube (Fleetguard LF3729).... <b>BT595</b> Fuel/Water Separator Ele..... <b>PF7777</b> Fuel/Water Separator Spin-on (Fleetguard FS19519)..... <b>BF1271</b> Radial Seal Air (Don. P527484).... <b>RS2863</b> Radial Seal Air (Extreme Performance Version) (Don. P527484)..... <b>RS2863XP</b> Air Dryer (Bendix 65624)..... <b>BA5373</b>
K120 w/Cat 3406E Eng. Lube (1R0716)..... <b>B99 +</b> Fuel (1R-0749)..... <b>BF7587 +</b>	K270 w/Paccar PX-6 Eng. (Cont'd) Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Diesel Exhaust Fluid (5303604).. <b>PE17000</b>	K270 w/Paccar PX-7 (6.7L) Eng. (2020) (Cont'd) Air Dryer (Wabco R950068A)..... <b>BA5379</b> Crankcase Breather (4936636).... <b>CV15010</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Steering (229348PAC)..... <b>P106-HD</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)
K300 w/Cummins ISB 5.9 (5.9L) Eng. (Cont'd) Radial Seal XP Air (Don. P527484)..... <b>RS2863XP</b> Air Dryer (Bendix 65624)..... <b>BA5373</b>	K300, K333 w/Cummins C8.3 (8.3L) Eng. (Cont'd) S. Fuel..... <b>BF788</b> Radial Seal Air (Don. P527484)..... <b>RS2863</b> Radial Seal XP Air (Don. P527484)..... <b>RS2863XP</b> Coolant (Fleetguard WF2055)..... <b>BW5140</b> Trans. Pan-Type (Allison 29538489)..... <b>19739 +</b> Trans. Spin-on (Allison 25011159)..... <b>BT230 +</b> Steering (ZF 7632-141-102)..... <b>P106-HD</b>	K370 w/Paccar PX-7 (6.7L) Eng. (2014-17) (Cont'd) Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Trans. Ele. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Diesel Exhaust Fluid (5303604).. <b>PE17000</b> Diesel Exhaust Fluid (5303604).. <b>PE17000</b>
K300 w/Cummins ISC (8.3L) Eng. Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309 +</b> Dual-Flow Lube (Fleetguard LF9548)..... <b>BD324 +</b> Fuel (Fleetguard FF5488)..... <b>BF7815</b> Fuel (Fleetguard FF5636)..... <b>BF7924</b> Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> Coolant (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b> Coolant (w/23 Units BTA+) (Fleetguard WF2076)..... <b>BW5076</b> Coolant (w/Controlled Release) (Fleetguard WF2121)..... <b>BW5250</b>	K360 w/Paccar PX-6 Eng. (Hybrid) Lube (Fleetguard LF3970)..... <b>B7177</b> Fuel/Water Separator (Fleetguard FS1065)..... <b>BF1378-SPS</b> Fuel (Fleetguard FF5421)..... <b>BF7966</b> Radial Seal Air (Don. P527484)..... <b>RS2863</b> Radial Seal XP Air (Don. P527484)..... <b>RS2863XP</b> Crankcase Breather (4936636)..... <b>CV15010</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	K370 w/Paccar PX-7 (6.7L) Eng. (2018) Lube (3937736)..... <b>B7177</b> Fuel/Water Separator (Fleetguard FS1065)..... <b>BF1378-SPS</b> Fuel (Fleetguard FF63009)..... <b>BF63000</b> Radial Seal Air (1679397)..... <b>RS5692</b> Cab Air (SR2000059)..... <b>PA30281</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Crankcase Breather (4936636)..... <b>CV15010</b> Trans. Pan-Type (S. Pan w/o Gskt.) (29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (29537966)..... <b>20017</b> Trans. Spin-on (29539579)..... <b>BT8460</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Diesel Exhaust Fluid (5303604).. <b>PE17000</b>
K300 w/Paccar PX-6 Eng. Lube (Fleetguard LF3970)..... <b>B7177</b> Fuel/Water Separator (Fleetguard FS1065)..... <b>BF1378-SPS</b> Fuel (Fleetguard FF5421)..... <b>BF7966</b> Radial Seal Air (Don. P527484)..... <b>RS2863</b> Radial Seal XP Air (Don. P527484)..... <b>RS2863XP</b> Crankcase Breather (4936636)..... <b>CV15010</b> Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	K370 w/Paccar PX-6 (6.7L) Eng. (2013) Lube (Fleetguard LF3970)..... <b>B7177</b> Fuel/Water Separator (Fleetguard FS1065)..... <b>BF1378-SPS</b> Fuel (Fleetguard FF5632)..... <b>BF7940</b> Radial Seal Air..... <b>RS2863</b> Radial Seal XP Air..... <b>RS2863XP</b> Radial Seal Air (1679397)..... <b>RS5692</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	K370 w/Paccar PX-7 (6.7L) Eng. (2019) Lube (3937736)..... <b>B7177</b> Fuel/Water Separator (Fleetguard FS1065)..... <b>BF1378-SPS</b> Fuel (5303743)..... <b>BF63000</b> Radial Seal Air (1679397)..... <b>RS5692</b> Air Dryer (Wabco R950068A)..... <b>BA5379</b> Crankcase Breather (4936636)..... <b>CV15010</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Steering (229348)..... <b>P106-HD</b> Diesel Exhaust Fluid (4388378).. <b>PE17002 KIT</b>
K300 w/Paccar PX-8 Eng. Dual-Flow Lube..... <b>BD7309 +</b> Fuel/Water Separator (Fleetguard FS19596)..... <b>BF1293-SPS</b> Fuel/Water Separator (Fleetguard FS1065)..... <b>BF1378-SPS</b> Fuel..... <b>BF7815</b> Radial Seal Air (Don. P527484)..... <b>RS2863</b> Radial Seal XP Air (Don. P527484)..... <b>RS2863XP</b> Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	K370 w/Paccar PX-7 (6.7L) Eng. (2014-17) Lube (Fleetguard LF9104)..... <b>B7177</b> Fuel/Water Separator (Fleetguard FS1065)..... <b>BF1378-SPS</b> Fuel (Fleetguard FF63009)..... <b>BF63000</b> Radial Seal Air (Don. P527484)..... <b>RS2863</b> Radial Seal XP Air (Don. P527484)..... <b>RS2863XP</b> Radial Seal Air (1679397)..... <b>RS5692</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Breather (Rear Eng. Mounted) (Fleetguard CV50607)..... <b>CV15000</b> Crankcase Breather (Rocker Lever Cover Mounted) (Fleetguard CV52001)..... <b>CV15010</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	
K300, K333 w/Cummins B Series Engs. Lube (3.9L)..... <b>BT427</b> Lube (5.9L)..... <b>BT339 +</b> P. Fuel/Water Separator..... <b>BF1280 +</b> S. Fuel..... <b>BF788</b>		
K300, K333 w/Cummins C8.3 (8.3L) Eng. F-F Lube..... <b>B205 +</b> Dual-Flow Lube (3318853)..... <b>BD103 +</b> P. Fuel/Water Separator (3843760)..... <b>BF1226</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)
K370 w/Paccar PX-7 (6.7L) Eng. (2020)	L700 w/Cummins L10 (10.0L) Eng.	S2 w/Cummins V-903 Eng.
Lube (3937736)..... B7177	F-F Lube (Fleetguard LF670SC).. B196 +	Fuel (Fleetguard FF101)..... PF821-S
<b>Fuel/Water Separator</b>	<b>Dual-Flow Lube</b> (3318853)..... BD103 +	<b>Coolant</b> (209606)..... BW5137
(Fleetguard FS1065)..... BF1378-SPS	<b>B-P Lube</b> (3304232)..... B7577	T170 w/Paccar PX-6 (6.7L) Eng.
<b>Fuel</b> (Fleetguard FF63009)..... BF63000	<b>Fuel</b> (154789)..... BF957-D +	Lube (Fleetguard LF3970)..... B7177
<b>Radial Seal Air</b> (1679397)..... RS5692	<b>Coolant</b> (w/4 Units BTA+)..... BW5071	<b>Fuel/Water Separator</b>
<b>Air Dryer</b> (Wabco R950068A)..... BA5379	(3315116)..... BW5071	(Fleetguard FS1065)..... BF1378-SPS
<b>Crankcase Breather</b> (4936636)..... CV15010	<b>Coolant</b> (w/15 Units BTA+)..... BW5075	<b>Fuel</b> (Fleetguard FF5632)..... BF7940
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... 20004	(Fleetguard WF2075)..... BT223	<b>Radial Seal Air</b> (Don. P527484)..... RS2863
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... 20016	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... B2 +	<b>Radial Seal XP Air</b> (Don. P527484)..... RS2863XP
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... 20003	L700 w/Cummins N14 (14.0L) Eng.	<b>Crankcase Breather</b> (4936636)..... CV15010
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... 20017	F-F Lube (Fleetguard LF670SC).. B196 +	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... 20004
<b>Trans. Spin-on</b> (Allison 29539579)..... BT8460	<b>Dual-Flow Lube</b> (3318853)..... BD103 +	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... 20016
<b>Steering</b> (229348PAC)..... P106-HD	<b>B-P Lube</b> (3304232)..... B7577	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... 20003
K370 w/Paccar PX-7 (6.7L) Eng. (2021)	<b>Fuel</b> (154789)..... BF957-D +	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... 20017
Lube (3937736)..... B7177	<b>Coolant</b> (3315116)..... BW5071	<b>Trans. Spin-on</b> (Allison 29539579)..... BT8460
<b>Fuel</b> (5303743)..... BF63000	<b>Trans. Spin-on</b> (Fuller 4304827)..... BT223	<b>Steering</b> (Nelson 87904M)..... PT9354-MPG
<b>Crankcase Breather</b> (4936636)..... CV15010	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... B2 +	<b>Diesel Exhaust Fluid</b> (2888182)..... PE17000
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... 20004	L700 w/Detroit Diesel 6-71 (7.0L) Eng.	T170 w/Paccar PX-7 (6.7L) Eng. (2014-18)
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... 20016	F-F Lube (23530407)..... B95 +	Lube (Fleetguard LF3970)..... B7177
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... 20003	F-F Lube (23530408)..... B95-MPG +	<b>Fuel/Water Separator</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... 20017	<b>P. Fuel</b> (23530706)..... BF5800 +	(Fleetguard FS1065)..... BF1378-SPS
<b>Trans. Spin-on</b> (Allison 29539579)..... BT8460	<b>S. Fuel</b> (23530707)..... BF5810	<b>Fuel</b> (Fleetguard FF63009)..... BF63000
K370 w/Paccar PX-7 (6.7L) Eng. (2022)	<b>S. Fuel</b> (23530645)..... BF5815	<b>Radial Seal Air</b> (Don. P527484)..... RS2863
Lube (3937736)..... B7177	<b>Trans. Spin-on</b> (Fuller 4304827)..... BT223	<b>Radial Seal XP Air</b> (Don. P527484)..... RS2863XP
KW45 w/Paccar 4 Cil. 160 HP Eng. (Mexico)	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... B2 +	<b>Air Dryer</b> (Bendix 5008414)..... BA5374 +
Lube (1399494)..... BT7237	L700 w/Detroit Diesel 6V-92N (9.0L) Eng.	<b>Crankcase Breather</b> (Rocker Lever Cover Mounted) (Fleetguard CV52001)..... CV15010
<b>Fuel/Water Separator</b> (1437070)..... BF7941	F-F Lube (23530407)..... B95 +	<b>Breather</b> (Rear Engine Mounted) (Fleetguard CV50633)..... CV15000
<b>Fuel</b> (1399760)..... BF7813	F-F Lube (23530408)..... B95-MPG +	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... 20004
<b>Radial Seal Air</b> (1668000)..... RS5433	<b>P. Fuel</b> (23530706)..... BF5800 +	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... 20016
KW45 w/Paccar 6 Cil. 225 HP Eng. (Mexico)	<b>S. Fuel</b> (23530707)..... BF5810	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... 20003
Lube (1399494)..... BT7237	<b>S. Fuel</b> (23530645)..... BF5815	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... 20017
<b>Fuel/Water Separator</b> (1618993)..... BF7942	<b>Trans. Spin-on</b> (Fuller 4304827)..... BT223	<b>Trans. Spin-on</b> (Allison 29539579)..... BT8460
<b>Fuel</b> (1399760)..... BF7813	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... B2 +	<b>Steering</b> (Nelson 87904M)..... PT9354-MPG
KW55 w/Paccar 6 Cil. 225 HP Eng. (Mexico)	L700 w/GMC Diesel Eng.	<b>Diesel Exhaust Fluid</b> (5303604)..... PE17000
Lube (1399494)..... BT7237	F-F Lube Ele..... P20-HD +	T170 w/Paccar PX-7 (6.7L) Eng. (2019)
<b>Fuel/Water Separator</b> (1618993)..... BF7942	F-F Lube Spin-on..... B95 +	Lube (3937736)..... B7177
<b>Fuel</b> (1399760)..... BF7813	<b>P. Fuel Spin-on</b> ..... BF5800 +	<b>Fuel/Water Separator</b> (4934879)..... BF1378-SPS
L700 w/Cat 3208 Eng.	<b>S. Fuel Spin-on</b> ..... BF5810	<b>Fuel</b> (5303743)..... BF63000
Lube (9N5570)..... [2] BT230 +	PD221, PD223, PD225 w/Cummins Eng.	<b>Radial Seal Air</b> (Don. P527484)..... RS2863
Lube (9L9200)..... [2] BT364	F-F Lube Bag..... P996	<b>Radial Seal XP Air</b> (Don. P527484)..... RS2863XP
<b>Box-Style Fuel/Water Separator</b> ..... BF912	F-F Lube Ele..... P999-HD	<b>Cab Air</b> (SR2000059)..... PA30281
<b>Fuel Spin-on</b> ..... BF970 +	F-F Lube Spin-on..... B196 +	<b>Air Dryer</b> (Bendix 5008414)..... BA5374 +
L700 w/Cat 3306 (10.5L) Eng.	<b>B-P Lube Ele</b> ..... C750-E +	
Lube (Standard Vers.) (1R0739)..... B76 +	<b>Fuel/Water Separator</b> ..... BF1212 +	
Lube (Severe Service) (1R0739)..... B76-SS +	<b>4 3/8 In. Fuel Spin-on</b> ..... BF948 +	
<b>Box-Style Fuel/Water Separator</b> ..... BF912	<b>5 3/4 In. Fuel Spin-on</b> ..... BF957 +	
<b>Fuel Spin-on</b> (1R0740)..... BF970 +	<b>11 7/32 In. Fuel Spin-on</b> ..... BF596 +	
	<b>Breather Ele.</b> (w/Turbo) (255963) PA643	
	<b>Breather Ele.</b> (w/o Turbo) (256837)..... PA1627	
	<b>Turbocharger</b> ..... BT112	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)
T170 w/Paccar PX-7 (6.7L) Eng. (2019) (Cont'd) <b>Crankcase Breather</b> (4936636)... <b>CV15010</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (4388378).. <b>PE17002 KIT</b>	T270 w/Paccar PX-6 (6.7L) Eng. (Cont'd) <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Diesel Exhaust Fluid</b> (2888182).. <b>PE17000</b>	T270 w/Paccar PX-7 (6.7L) Eng. (2019) (Cont'd) <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (4388378).. <b>PE17002 KIT</b>
T170 w/Paccar PX-7 (6.7L) Eng. (2020) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel/Water Separator</b> (Fleetguard FS1067)..... <b>BF1378-SPS</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> <b>Radial Seal Air</b> (Don. P527484).. <b>RS2863</b> <b>Radial Seal XP Air</b> (Don. P527484)..... <b>RS2863XP</b> <b>Crankcase Breather</b> (4936636).. <b>CV15010</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	T270 w/Paccar PX-7 (6.7L) Eng. (2014-18) <b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b> <b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> <b>Radial Seal Air</b> (Don. P527484).. <b>RS2863</b> <b>Radial Seal XP Air</b> (Don. P527484)..... <b>RS2863XP</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Crankcase Breather</b> (Rocker Lever Cover Mounted) (Fleetguard CV52001)..... <b>CV15010</b> <b>Breather</b> (Rear Engine Mounted) (Fleetguard CV50607)..... <b>CV15000</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b> <b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>	T270 w/Paccar PX-7 (6.7L) Eng. (2020) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> <b>Radial Seal Air</b> (Don. P527484).. <b>RS2863</b> <b>Radial Seal XP Air</b> (Don. P527484)..... <b>RS2863XP</b> <b>Cab Air</b> (SR2000059)..... <b>PA30281</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Crankcase Breather</b> (4936636).. <b>CV15010</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
T170 w/Paccar PX-7 (6.7L) Eng. (2021) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636).. <b>CV15010</b>	T270 w/Paccar PX-7 (6.7L) Eng. (2019) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel/Water Separator</b> (4934879). <b>BF1378-SPS</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Radial Seal Air</b> (Don. P527484).. <b>RS2863</b> <b>Radial Seal XP Air</b> (Don. P527484)..... <b>RS2863XP</b> <b>Cab Air</b> (SR2000059)..... <b>PA30281</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Crankcase Breather</b> (4936636).. <b>CV15010</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29545776)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29545779)..... <b>PT9415-MPG KIT</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	T270 w/Paccar PX-7 (6.7L) Eng. (2021) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636).. <b>CV15010</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
T170 w/Paccar PX-7 (6.7L) Eng. (2022) <b>Lube</b> (3937736)..... <b>B7177</b>		
T270 w/Paccar PX-6 (6.7L) Eng. <b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b> <b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b> <b>Fuel</b> (Fleetguard FF5421)..... <b>BF7966</b> <b>Fuel</b> (Fleetguard FF5632)..... <b>BF7940</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> <b>Radial Seal Air</b> (Don. P527484).. <b>RS2863</b> <b>Radial Seal XP Air</b> (Don. P527484)..... <b>RS2863XP</b> <b>Air Dryer</b> (AD-IS, AD-SP System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b> <b>Crankcase Breather</b> (4936636).. <b>CV15010</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)
T270 w/Paccar PX-7 (6.7L) Eng. (2022)	T270 w/Paccar PX-8 (8.3L) Eng. (2020) (Cont'd)	T270 w/Paccar PX-9 (8.9L) Eng. (2019) (Cont'd)
<b>Lube</b> (3937736)..... <b>B7177</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>
<b>Air Dryer</b> (Bendix 5008414PF).... <b>BA5379</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Diesel Exhaust Fluid</b> (4388378).. <b>PE17002 KIT</b>
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	T270 w/Paccar PX-9 (8.9L) Eng. (2020)
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Lube</b> (3401544)..... <b>B40142</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1003)..... <b>BF1293-SPS</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b>
<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	T270 w/Paccar PX-9 (8.9L) Eng. (2014-18)	<b>Fuel</b> (5303743)..... <b>BF63000</b>
T270 w/Paccar PX-7 (6.7L) Eng. (2023)	<b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b>	<b>Radial Seal Air</b> (Don. P527484)... <b>RS2863</b>
<b>Lube</b> (3937736)..... <b>B7177</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1003)..... <b>BF1293-SPS</b>	<b>Radial Seal XP Air</b> (Don. P527484)..... <b>RS2863XP</b>
T270 w/Paccar PX-8 (8.3L) Eng. (2008-14)	<b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b>	<b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b>
<b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b>	<b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>
<b>Fuel/Water Separator</b> (Fleetguard FS1003)..... <b>BF1293-SPS</b>	<b>Radial Seal Air</b> (Don. P527484)... <b>RS2863</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>
<b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b>	<b>Radial Seal XP Air</b> (Don. P527484)..... <b>RS2863XP</b>	<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>
<b>Fuel</b> (Fleetguard FF5488)..... <b>BF7815</b>	<b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
<b>Fuel</b> (Fleetguard FF5636)..... <b>BF7924</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	T270 w/Paccar PX-9 (8.9L) Eng. (2021)
<b>Radial Seal Air</b> (Don. P527484)... <b>RS2863</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Lube</b> (5444774)..... <b>B40142</b>
<b>Radial Seal XP Air</b> (Don. P527484)..... <b>RS2863XP</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Fuel</b> (5303743)..... <b>BF63000</b>
<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>
<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	T270 w/Paccar PX-9 (8.9L) Eng. (2022)
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	<b>Lube</b> (5444774)..... <b>B40142</b>
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>Air Dryer</b> (Bendix 5008414PG).... <b>BA5379</b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Diesel Exhaust Fluid</b> (4388378).. <b>PE17002 KIT</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>	T280 w/Paccar PX-7 (6.7L) Eng. (2021)
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>	<b>Lube</b> (3937736)..... <b>B7177</b>
<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	T270 w/Paccar PX-9 (8.9L) Eng. (2019)	<b>Fuel</b> (5303743)..... <b>BF63000</b>
<b>Diesel Exhaust Fluid</b> (2888182).. <b>PE17000</b>	<b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b>	<b>Crankcase Breather</b> (4936636).... <b>CV15010</b>
T270 w/Paccar PX-8 (8.3L) Eng. (2020)	<b>Fuel/Water Separator</b> (Fleetguard FS1003)..... <b>BF1293-SPS</b>	T280 w/Paccar PX-7 (6.7L) Eng. (2022)
<b>Radial Seal Air</b> (Don. P527484)... <b>RS2863</b>	<b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b>	<b>Lube</b> (3937736)..... <b>B7177</b>
<b>Radial Seal XP Air</b> (Don. P527484)..... <b>RS2863XP</b>	<b>Radial Seal Air</b> (Don. P527484)... <b>RS2863</b>	T280 w/Paccar PX-9 (8.9L) Eng. (2022)
<b>Cab Air</b> (SR2000059)..... <b>PA30281</b>	<b>Radial Seal XP Air</b> (Don. P527484)..... <b>RS2863XP</b>	<b>Lube</b> (5444774)..... <b>B40142</b>
<b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b>	<b>Cab Air</b> (SR2000059)..... <b>PA30281</b>	<b>Fuel</b> (5303743)..... <b>BF63000</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b>	T300 w/Cat 3126 (7.2L) Eng. (1/2004-on)
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	<b>Lube</b> (1R1807)..... <b>B7700 +</b>
	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	<b>Opt. Fuel/Water Separator</b> ..... <b>BF1259</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>KENWORTH Trucks (cont'd)</b>	<b>KENWORTH Trucks (cont'd)</b>	<b>KENWORTH Trucks (cont'd)</b>
T300 w/Cat 3126 (7.2L) Eng. (1/2004-on) (Cont'd)	T300 w/Cat C7 (7.2L) Eng. (1/2004-on) (Cont'd)	T300 w/Cummins 6BT5.9 (5.9L) Eng. (To 1998)
<b>Coolant</b> (9N-3718)..... <b>BW5139</b>	<b>Coolant</b> (w/4 Units BTE) (9N-3368)..... <b>BW5137</b>	<b>Lube</b> (3914395)..... <b>BT339 +</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Coolant</b> (w/8 Units BTE) (9N-3367)..... <b>BW5139</b>	<b>Fuel/Water Separator</b> (3925274)..... <b>BF1280 +</b>
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Fuel</b> (3903640)..... <b>BF788</b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	T300 w/Cummins 6CT8.3 (8.3L) Eng.
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>F-F Lube</b> (3313281)..... <b>B205 +</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29526899)..... <b>PT9416-MPG KIT</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Fuel/Water Separator</b> (3925274)..... <b>BF1280 +</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29526898)..... <b>PT9415-MPG KIT</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Fuel</b> (3903640)..... <b>BF788</b>
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Radial Seal Air</b> (Don. P527484)..... <b>RS2863</b>
<b>Steering</b> (ZF 7632-141-107)..... <b>P106-HD</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Radial Seal Air</b> (Extreme Performance Version) (Don. P527484)..... <b>RS2863XP</b>
T300 w/Cat 3126 (7.2L) Eng. (To 1/2004)	<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	T300 w/Cummins C8.3 (8.3L) Eng.
<b>Lube</b> (Standard Vers.) (1R0739)..... <b>B76 +</b>	T300 w/Cat C7 (7.2L) Eng. (To 1/2004)	<b>Dual-Flow Lube</b> (Fleetguard LF3000)..... <b>BD103 +</b>
<b>Lube</b> (Severe Service) (1R0739)..... <b>B76-SS +</b>	<b>Lube</b> (Standard Vers.) (1R0739)..... <b>B76 +</b>	<b>P. Fuel/Water Separator</b> ..... <b>BF1280 +</b>
<b>Opt. Fuel/Water Separator</b> ..... <b>BF1259</b>	<b>Lube</b> (Severe Service) (1R0739)..... <b>B76-SS +</b>	<b>S. Fuel</b> (Fleetguard FF5052)..... <b>BF788</b>
<b>Fuel</b> (1R0751)..... <b>BF7632</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1000)..... <b>BF1259</b>	<b>Radial Seal O. Air</b> (Don. P527484)..... <b>RS2863</b>
<b>Radial Seal O. Air</b> (Don. P527484)..... <b>RS2863</b>	<b>Fuel</b> (1R0751)..... <b>BF7632</b>	<b>Radial Seal XP Air</b> (Don. P527484)..... <b>RS2863XP</b>
<b>Radial Seal XP O. Air</b> (Don. P527484)..... <b>RS2863XP</b>	<b>Radial Seal Air</b> (Don. P527484)..... <b>RS2863</b>	<b>Radial Seal I. Air</b> (Fleetguard AF25215)..... <b>RS3501</b>
<b>Opt. Radial Seal I. Air</b> (Don. P527680)..... <b>RS3501</b>	<b>Radial Seal XP Air</b> (Don. P527484)..... <b>RS2863XP</b>	<b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b>
<b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b>	<b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b>	<b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b>
<b>Coolant</b> (9N-3718)..... <b>BW5139</b>	<b>Coolant</b> (w/4 Units BTE) (9N-3368)..... <b>BW5137</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Coolant</b> (w/8 Units BTE) (9N-3367)..... <b>BW5139</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29526899)..... <b>PT9416-MPG KIT</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29526899)..... <b>PT9416-MPG KIT</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29526898)..... <b>PT9415-MPG KIT</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29526898)..... <b>PT9415-MPG KIT</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Steering</b> (ZF 7632-141-107)..... <b>P106-HD</b>
<b>Steering</b> (ZF 7632-141-107)..... <b>P106-HD</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	T300 w/Cummins ISB (5.9L) Eng. (To 2007)
T300 w/Cat C7 (7.2L) Eng. (1/2004-on)	<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b>
<b>Lube</b> (1R1807)..... <b>B7700 +</b>	T300 w/Cummins 6BT5.9 (5.9L) Eng. (1998-on)	<b>Fuel/Water Separator Ele.</b> (3942470)..... <b>PF7777</b>
<b>Fuel/Water Separator</b> (Fleetguard FS1000)..... <b>BF1259</b>	<b>Lube</b> (Chrysler 5083285AA)..... <b>BT7349</b>	<b>7 3/8 In. Fuel/Water Separator</b> <b>Spin-on</b> (Fleetguard FS19732)..... <b>BF1385-SPS</b>
<b>Fuel</b> (1R0751)..... <b>BF7632</b>	<b>Fuel/Water Separator</b> (3925274)..... <b>BF1280 +</b>	<b>10 1/32 In. Fuel/Water Separator</b> <b>Spin-on</b> (Fleetguard FS19596)..... <b>BF1293-SPS</b>
<b>Radial Seal Air</b> (Don. P527484)..... <b>RS2863</b>	<b>Fuel</b> (3903640)..... <b>BF788</b>	<b>P. Fuel Pre-Filter</b> (Fleetguard FF2203)..... <b>BF7760</b>
<b>Radial Seal XP Air</b> (Don. P527484)..... <b>RS2863XP</b>		<b>S. Fuel</b> (Fleetguard FF2200)..... <b>BF7766</b>
<b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b>		<b>Fuel</b> (Fleetguard FF5421)..... <b>BF7966</b>
		<b>Radial Seal O. Air</b> (Don. P527484)..... <b>RS2863</b>
		<b>Radial Seal XP Air</b> (Don. P527484)..... <b>RS2863XP</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)
T300 w/Cummins ISB (5.9L) Eng. (To 2007) (Cont'd)	T300 w/Cummins ISC 8.3 (8.3L) Eng. (To 2007)	T300 w/Cummins ISC 8.3 (8.3L) Eng. (2007-on) (Cont'd)
<b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b>	<b>Dual-Flow Lube</b> (3401544)..... <b>BD7309 +</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
<b>Coolant</b> ..... <b>BW5071</b>	<b>Lube</b> (Upgrade) (3401544)..... <b>B40142 +</b>	<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1003)..... <b>BF1293-SPS</b>	T300 w/Cummins ISM Eng. (To 2007)
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Fuel</b> (Fleetguard FF5488)..... <b>BF7815</b>	<b>Dual-Flow Lube</b> (3406810)..... <b>BD7153 +</b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Radial Seal Air</b> (Don. P527484)... <b>RS2863</b>	<b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Radial Seal XP Air</b> (Don. P527484)..... <b>RS2863XP</b>	<b>Fuel/Water Separator</b> (3406889). <b>BF1293-SPS</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b>	<b>Fuel</b> ..... <b>BF7815</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29526899)..... <b>PT9416-MPG KIT</b>	<b>Coolant</b> (w/4 Units BTA+) (3315116)..... <b>BW5071</b>	<b>Radial Seal Air</b> (Don. P527484)... <b>RS2863</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Coolant</b> (w/4 Units BTE) (Fleetguard WF2051)..... <b>BW5137</b>	<b>Radial Seal XP Air</b> (Don. P527484)..... <b>RS2863XP</b>
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b>
<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b>
T300 w/Cummins ISB (5.9L) Eng. (2007-on)	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
<b>Fuel/Water Separator Ele.</b> (3942470)..... <b>PF7777</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>7 3/8 In. Fuel/Water Separator Spin-on</b> (Fleetguard FS19732)..... <b>BF1385-SPS</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>10 1/32 In. Fuel/Water Separator Spin-on</b> (Fleetguard FS19596)..... <b>BF1293-SPS</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>
<b>Fuel</b> (Fleetguard FF5421)..... <b>BF7966</b>	<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>
<b>Fuel</b> (Fleetguard FF5632)..... <b>BF7940</b>	T300 w/Cummins ISC 8.3 (8.3L) Eng. (2007-on)	T300 w/Cummins ISM Eng. (2007-on)
<b>Radial Seal O. Air</b> (Don. P527484)..... <b>RS2863</b>	<b>Dual-Flow Lube</b> (3401544)..... <b>BD7309 +</b>	<b>Dual-Flow Lube</b> (3406810)..... <b>BD7153 +</b>
<b>Radial Seal XP Air</b> (Don. P527484)..... <b>RS2863XP</b>	<b>Lube</b> (Upgrade) (3401544)..... <b>B40142 +</b>	<b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b>
<b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b>	<b>Fuel/Water Separator</b> (3406889). <b>BF1293-SPS</b>
<b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	<b>Fuel</b> (Fleetguard FF5636)..... <b>BF7924</b>	<b>Fuel</b> ..... <b>BF7815</b>
<b>Coolant</b> ..... <b>BW5071</b>	<b>Radial Seal Air</b> (Don. P527484)... <b>RS2863</b>	<b>Radial Seal Air</b> (Don. P527484)... <b>RS2863</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Radial Seal XP Air</b> (Don. P527484)..... <b>RS2863XP</b>	<b>Radial Seal XP Air</b> (Don. P527484)..... <b>RS2863XP</b>
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b>	<b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Coolant</b> (w/4 Units BTA+) (3315116)..... <b>BW5071</b>	<b>Breather</b> (3683918)..... <b>CV15000</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Coolant</b> (w/4 Units BTE) (Fleetguard WF2051)..... <b>BW5137</b>	<b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29526899)..... <b>PT9416-MPG KIT</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)
T300 w/Cummins ISM Eng. (2007-on) (Cont'd) <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	T300 w/Paccar PX-8 Eng. (Cont'd) <b>Fuel/Water Separator</b> (Fleetguard FS1003)..... <b>BF1293-SPS</b>	T370 w/Cummins ISC 8.3 (8.3L) Eng. (Cont'd) <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
T300 w/Cummins N14 (14.0L) Eng. <b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196 +</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Fuel</b> (154789)..... <b>BF957-D +</b> <b>Coolant</b> (3315116)..... <b>BW5071</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b> <b>Fuel</b> (Fleetguard FF5488)..... <b>BF7815</b> <b>Radial Seal Air</b> (Don. P527484).. <b>RS2863</b> <b>Radial Seal XP Air</b> (Don. P527484)..... <b>RS2863XP</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>
T300 w/Cummins Natural Gas 5.9L Eng. <b>Lube</b> ..... <b>BT339 +</b> <b>Radial Seal Air</b> ..... <b>RS2863</b> <b>Radial Seal XP Air</b> ..... <b>RS2863XP</b>	T300 w/Cummins NTC (14.0L) Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>F-F Lube Ele.</b> (158139)..... <b>P999-HD</b> <b>F-F Lube Spin-on</b> (3313279)..... <b>B196 +</b> <b>B-P Lube Ele.</b> (256838)..... <b>C750-E +</b> <b>B-P Lube Spin-on</b> (3313283)..... <b>B7577</b> <b>Fuel/Water Separator</b> (3308638)..... <b>BF1212 +</b> <b>Fuel</b> (158172)..... <b>BF957 +</b>	T370 w/Paccar PX-6 (6.7L) Eng. <b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b> <b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b> <b>Fuel/Water Separator</b> (Fleetguard FS1003)..... <b>BF1293-SPS</b> <b>Fuel</b> (Fleetguard FF5632)..... <b>BF7940</b> <b>Fuel</b> (Fleetguard FF5636)..... <b>BF7924</b> <b>Radial Seal Air</b> (Don. P527484).. <b>RS2863</b> <b>Radial Seal XP Air</b> (Don. P527484)..... <b>RS2863XP</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b> <b>Crankcase Breather</b> (4936636).. <b>CV15010</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>
T300 w/Paccar PX-6 Eng. <b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b> <b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b> <b>Fuel/Water Separator</b> (Fleetguard FS1003)..... <b>BF1293-SPS</b> <b>Fuel</b> (Fleetguard FF5632)..... <b>BF7940</b> <b>Fuel</b> (Fleetguard FF5636)..... <b>BF7924</b> <b>Radial Seal Air</b> (Don. P527484).. <b>RS2863</b> <b>Radial Seal XP Air</b> (Don. P527484)..... <b>RS2863XP</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b> <b>Crankcase Breather</b> (4936636).. <b>CV15010</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	T358 w/Cummins ISC Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel</b> (Fleetguard FF5488)..... <b>BF7815</b> <b>Coolant</b> (Fleetguard WF2074)..... <b>BW5074</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>
T300 w/Paccar PX-8 Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel/Water Separator</b> (Fleetguard FS1000)..... <b>BF1259</b>	T370 w/Cummins ISC 8.3 (8.3L) Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Dual-Flow Lube</b> (Fleetguard LF9548)..... <b>BD324 +</b> <b>Fuel</b> (Fleetguard FF5488)..... <b>BF7815</b> <b>Fuel</b> (Fleetguard FF5636)..... <b>BF7924</b> <b>Radial Seal Air</b> (Don. P527484).. <b>RS2863</b> <b>Radial Seal XP Air</b> (Don. P527484)..... <b>RS2863XP</b> <b>Air Dryer</b> (AD-IP) (Bendix 65624). <b>BA5373</b> <b>Air Dryer</b> (AD-IS, AD-SP System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b> <b>Coolant</b> (w/23 Units BTA+) (Fleetguard WF2076)..... <b>BW5076</b> <b>Coolant</b> (w/Controlled Release) (Fleetguard WF2121)..... <b>BW5250</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537966)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Diesel Exhaust Fluid</b> (2010 Emissions) (5303604)..... <b>PE17000</b>
		T370 w/Paccar PX-7 (6.7L) Eng. (2014-18) <b>Lube</b> (Fleetguard LF9104)..... <b>B7177</b> <b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Radial Seal Air</b> (Don. P527484).. <b>RS2863</b> <b>Radial Seal XP Air</b> (Don. P527484)..... <b>RS2863XP</b> <b>Cab Air</b> (SR2000059)..... <b>PA30281</b> <b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)
T370 w/Paccar PX-7 (6.7L) Eng. (2014-18) (Cont'd)	T370 w/Paccar PX-7 (6.7L) Eng. (2020) (Cont'd)	T370 w/Paccar PX-7 (6.7L) Eng. (2023)
<b>Air Dryer</b> (AD-SP System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Radial Seal XP Air</b> (Don. P527484)..... <b>RS2863XP</b>	<b>Lube</b> (3937736)..... <b>B7177</b>
<b>Crankcase Breather</b> (Rocker Lever Cover Mounted) (Fleetguard CV52001)..... <b>CV15010</b>	<b>Cab Air</b> (SR2000059)..... <b>PA30281</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Breather</b> (Rear Eng. Mounted) (Fleetguard CV50633)..... <b>CV15000</b>	<b>Air Dryer</b> (Bendix 5008414PG).... <b>BA5379</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	T370 w/Paccar PX-8 (8.3L) Eng. (2008-16)
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1003)..... <b>BF1293-SPS</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b>
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	<b>Fuel</b> (Fleetguard FF5488)..... <b>BF7815</b>
<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	T370 w/Paccar PX-7 (6.7L) Eng. (2021)	<b>Fuel</b> (Fleetguard FF5636)..... <b>BF7924</b>
<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	<b>Lube</b> (3937736)..... <b>B7177</b>	<b>Radial Seal Air</b> (Don. P527484)... <b>RS2863</b>
<b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>	<b>Fuel</b> (5303743)..... <b>BF63000</b>	<b>Radial Seal XP Air</b> (Don. P527484)..... <b>RS2863XP</b>
<b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>	<b>Radial Seal Air</b> (Don. P527484)... <b>RS2863</b>	<b>Crankcase Breather</b> (4936636)... <b>CV15010</b>
T370 w/Paccar PX-7 (6.7L) Eng. (2019)	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Lube</b> (3937736)..... <b>B7177</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Fuel/Water Separator</b> (4934879). <b>BF1378-SPS</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Fuel</b> (5303743)..... <b>BF63000</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Radial Seal Air</b> (Don. P527484)... <b>RS2863</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
<b>Radial Seal XP Air</b> (Don. P527484)..... <b>RS2863XP</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>Cab Air</b> (SR2000059)..... <b>PA30281</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
<b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b>	T370 w/Paccar PX-7 (6.7L) Eng. (2022)	<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>
<b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	<b>Lube</b> (3937736)..... <b>B7177</b>	<b>Diesel Exhaust Fluid</b> (2010 Emissions) (2888182)..... <b>PE17000</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Air Dryer</b> (Bendix 5008414PG).... <b>BA5379</b>	T370 w/Paccar PX-8 (8.3L) Eng. (2020)
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	<b>Radial Seal Air</b> (Don. P527484)... <b>RS2863</b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	<b>Radial Seal XP Air</b> (Don. P527484)..... <b>RS2863XP</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	<b>Cab Air</b> (SR2000059)..... <b>PA30281</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	T370 w/Paccar PX-7 (6.7L) Eng. (2020)	<b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b>
<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>Lube</b> (3937736)..... <b>B7177</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
T370 w/Paccar PX-7 (6.7L) Eng. (2020)	<b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Lube</b> (3937736)..... <b>B7177</b>	<b>Radial Seal Air</b> (Don. P527484)... <b>RS2863</b>	

+ See Product Guide for Variations of This Number. Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)
T370 w/Paccar PX-8 (8.3L) Eng. (2020) (Cont'd)	T370 w/Paccar PX-9 (8.9L) Eng. (2019) (Cont'd)	T370 Hybrid w/Paccar PX-6 Eng. (Cont'd)
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29545779)..... <b>PT9415-MPG KIT</b>	<b>Radial Seal Air</b> (Don. P527484)... <b>RS2863</b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>Radial Seal XP Air</b> (Don. P527484)..... <b>RS2863XP</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	<b>Air Dryer</b> (AD-IS, AD-SP System) (Bendix 5008414)..... <b>BA5374 +</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	T370 w/Paccar PX-9 (8.9L) Eng. (2020)	<b>Diesel Exhaust Fluid</b> (2880298).. <b>PE17000</b>
<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>Lube</b> (3401544)..... <b>B40142</b>	T380 w/Paccar PX-7 (6.7L) Eng. (2022)
<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1003)..... <b>BF1293-SPS</b>	<b>Lube</b> (3937736)..... <b>B7177</b>
T370 w/Paccar PX-9 (8.9L) Eng. (2014-18)	<b>Fuel</b> (5303743)..... <b>BF63000</b>	T380 w/Paccar PX-9 (8.9L) Eng. (2022)
<b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b>	<b>Radial Seal Air</b> (Don. P527484)... <b>RS2863</b>	<b>Lube</b> (5444774)..... <b>B40142</b>
<b>Fuel/Water Separator</b> (Fleetguard FS1003)..... <b>BF1293-SPS</b>	<b>Radial Seal XP Air</b> (Don. P527484)..... <b>RS2863XP</b>	<b>Fuel</b> (5303743)..... <b>BF63000</b>
<b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b>	<b>Cab Air</b> (SR2000059)..... <b>PA30281</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>
<b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b>	<b>Air Dryer</b> (Bendix 5008414PG).... <b>BA5379</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>
<b>Radial Seal Air</b> (Don. P527484)... <b>RS2863</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	T380 w/Paccar PX-9 (8.9L) Eng. (2023)
<b>Radial Seal XP Air</b> (Don. P527484)..... <b>RS2863XP</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	<b>Lube</b> (5520789)..... <b>B40142</b>
<b>Cab Air</b> (SR2000059)..... <b>PA30281</b>	<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>
<b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	T370 w/Paccar PX-9 (8.9L) Eng. (2021)	T400 w/Cat 3176 (10.3L) Eng.
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Lube</b> (5444774)..... <b>B40142</b>	<b>Lube</b> (1R0716)..... <b>B99 +</b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1003)..... <b>BF1293-SPS</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1212)..... <b>BF1212 +</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Fuel</b> (5303743)..... <b>BF63000</b>	<b>Fuel</b> (1R-0749)..... <b>BF7587 +</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Radial Seal Air</b> (Don. P527484)... <b>RS2863</b>	<b>Air</b> (Don. P153551)..... <b>PA2705</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	<b>Radial Seal XP Air</b> (Don. P527484)..... <b>RS2863XP</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>
<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	<b>Steering</b> (Fleetguard LF637)..... <b>P528</b>
<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	T400 w/Cat 3306 (10.5L) Eng.
<b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>	T370 w/Paccar PX-9 (8.9L) Eng. (2022)	<b>Lube</b> (Standard Vers.) (1R0739).. <b>B76 +</b>
<b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>	<b>Lube</b> (5444774)..... <b>B40142</b>	<b>Lube</b> (Severe Service) (1R0739).. <b>B76-SS +</b>
<b>Diesel Exhaust Fluid</b> (4388378).. <b>PE17002 KIT</b>	<b>Fuel</b> (5303743)..... <b>BF63000</b>	<b>Fuel Spin-on</b> (1R0740)..... <b>BF970 +</b>
T370 w/Paccar PX-9 (8.9L) Eng. (2019)	<b>Air Dryer</b> (Bendix 5008414PG).... <b>BA5379</b>	T400 w/Cat 3406 (14.6L) Eng.
<b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	<b>F-F Lube</b> (Std. Efficiency) (1R0716)..... <b>B99 +</b>
<b>Fuel/Water Separator</b> (Fleetguard FS1003)..... <b>BF1293-SPS</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	<b>F-F Eng. Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b>
<b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	<b>Fuel/Water Separator Spin-on</b> (2568753)..... <b>BF1259</b>
<b>Radial Seal Air</b> (Don. P527484)... <b>RS2863</b>	T370 w/Paccar PX-9 (8.9L) Eng. (2023)	<b>Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b>
<b>Radial Seal XP Air</b> (Don. P527484)..... <b>RS2863XP</b>	<b>Lube</b> (5520789)..... <b>B40142</b>	<b>Fuel Spin-on</b> (Std. Efficiency) (4N5823)..... <b>BF614 +</b>
<b>Cab Air</b> (SR2000059)..... <b>PA30281</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	<b>Fuel Spin-on</b> (High Efficiency Vers.) (1R0749)..... <b>BF7587 +</b>
<b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	T400 w/Cummins 6CT8.3 (8.3L) Eng.
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29545776)..... <b>PT9416-MPG KIT</b>	T370 Hybrid w/Paccar PX-6 Eng.	<b>Lube</b> (3313281)..... <b>B205 +</b>
	<b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b>	<b>Fuel/Water Separator</b> (3925274).. <b>BF1280 +</b>
	<b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b>	<b>Fuel</b> (3903640)..... <b>BF788</b>
	<b>Fuel</b> (Fleetguard FF5632)..... <b>BF7940</b>	<b>Conical Air</b> (Don. P154575)..... <b>PA2715</b>
		<b>Air</b> (Don. P153551)..... <b>PA2705</b>
		<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>
		<b>Steering</b> (Fleetguard LF637)..... <b>P528</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)
T400 w/Cummins ISL 8.9 (8.9L) Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Dual-Flow Lube</b> (Fleetguard LF9548)..... <b>BD324 +</b> <b>Fuel</b> (Fleetguard FF5488)..... <b>BF7815</b> <b>Fuel</b> (Fleetguard FF5636)..... <b>BF7924</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/Controlled Release) (Fleetguard WF2121)..... <b>BW5250</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	T400 w/Cummins ISL-G (8.9L) Eng. (2019) (Cont'd) <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> T400 w/Cummins ISL-G (8.9L) Eng. (2020) <b>Lube</b> (Fleetguard LF9009)..... <b>B40142</b> <b>Fuel</b> (Fleetguard NG5900)..... <b>BF7695</b> <b>Channel Flow EXO Air</b> (P611698)..... <b>CA30102</b> <b>Cab Air</b> (SR2000059)..... <b>PA30281</b> <b>Air Dryer</b> (Bendix 5008414PG).... <b>BA5379</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> T400 w/Cummins ISL-G (8.9L) Eng. (2022) <b>Lube</b> (5444774)..... <b>B40142</b> <b>Fuel/Water Separator</b> (3607140). <b>BF7695</b> T400 w/Cummins L10 (10.0L) Eng. <b>F-F Lube</b> ..... <b>B196 +</b> <b>B-P Lube</b> ..... <b>B7577</b> <b>Dual-Flow Lube</b> ..... <b>BD103 +</b> <b>Fuel/Water Separator</b> (Fleetguard FS1212)..... <b>BF1212 +</b> <b>Air</b> (w/Lid) (Don. P153551)..... <b>PA2705</b> <b>Air</b> (w/o Lid) (Don. P154575)..... <b>PA2715</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 83804E)..... <b>P528</b> T400 w/Cummins M11 Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Fuel/Water Separator</b> (Fleetguard FS1212)..... <b>BF1212 +</b> <b>Air</b> (Don. P537791)..... <b>PA2705</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 83804E)..... <b>P528</b> T400 w/Cummins N14 (14.0L) Eng. <b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196 +</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Fuel</b> (154789)..... <b>BF957-D +</b> <b>Coolant</b> (3315116)..... <b>BW5071</b> T400 w/Detroit Diesel Series 50 (8.5L) Eng. <b>Lube</b> (23530573)..... <b>[2] B495</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (23535985)..... <b>BF5813 +</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (23535985).. <b>BF5813-O +</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	T400 w/Detroit Diesel Series 50 (8.5L) Eng. (Cont'd) <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> T400 w/Detroit Diesel Series 60 (12.7L) Eng. <b>Lube</b> (23530407)..... <b>B95 +</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (23535985)..... <b>BF5813 +</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (23535985).. <b>BF5813-O +</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b> <b>Coolant</b> (23516489)..... <b>BW5200</b> T400 w/Paccar PX-8 (8.3L) Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel/Water Separator</b> (Fleetguard FS1000)..... <b>BF1259</b> <b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b> <b>Fuel</b> (Fleetguard FF5488)..... <b>BF7815</b> <b>Fuel</b> (Fleetguard FF5636)..... <b>BF7924</b> <b>Trans. Ele. (2 In. Kit)</b> (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele. (4 In. Kit)</b> (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> T400 w/Paccar PX-9 (8.9L) Eng. (2013-18) <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel/Water Separator</b> (Fleetguard FS1003)..... <b>BF1293-SPS</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Channel Flow Air</b> (P611698)..... <b>CA30102</b> <b>Cab Air</b> (SR2000059)..... <b>PA30281</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (Fleetguard UF101)..... <b>PE17000</b> T400 w/Paccar PX-9 (8.9L) Eng. (2019) <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel/Water Separator</b> (Fleetguard FS1003)..... <b>BF1293-SPS</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> <b>Cab Air</b> (SR2000059)..... <b>PA30281</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374</b>
T400 w/Cummins ISL-G (8.9L) Eng. (2011-17) <b>Dual-Flow Lube</b> (Std. Version) (Fleetguard LF3000)..... <b>BD103 +</b> <b>Dual-Flow Lube</b> (High Velocity) (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel/Water Separator</b> (Fleetguard NG5900)..... <b>BF7695</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/Controlled Release) (Fleetguard WF2121)..... <b>BW5250</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>		
T400 w/Cummins ISL-G (8.9L) Eng. (2018) <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel/Water Separator</b> (Fleetguard NG5900)..... <b>BF7695</b> <b>Channel Flow Air</b> (P611698)..... <b>CA30102</b> <b>Cab Air</b> (SR2000059)..... <b>PA30281</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>		
T400 w/Cummins ISL-G (8.9L) Eng. (2019) <b>Lube</b> (3401544)..... <b>B40142</b> <b>Fuel</b> (3606712)..... <b>BF7695</b> <b>Cab Air</b> (SR2000059)..... <b>PA30281</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>KENWORTH Trucks (cont'd)</b>	<b>KENWORTH Trucks (cont'd)</b>	<b>KENWORTH Trucks (cont'd)</b>
T400 w/Paccar PX-9 (8.9L) Eng. (2019) (Cont'd) Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	T404 w/Cummins ISX Eng. Dual-Flow Lube (Fleetguard LF9001)..... <b>BD7154 +</b> Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> Fuel/Water Separator (Fleetguard FS1040)..... <b>BF1277-SPS</b> Fuel/Water Separator (Upgrade) (Fleetguard FS1007)..... <b>BF1274-SP</b> Coolant (Fleetguard WF2126)..... <b>BW5086</b> Trans. (Fuller 4304827)..... <b>BT223</b>	T440 w/Cummins ISL-G Eng. (Cont'd) Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>
T400 w/Paccar PX-9 (8.9L) Eng. (2020) Lube (3401544)..... <b>B40142</b> Fuel/Water Separator (Fleetguard FS1003)..... <b>BF1293-SPS</b> Fuel (5303743)..... <b>BF63000</b> Channel Flow EXO Air (P611698)..... <b>CA30102</b> Cab Air (SR2000059)..... <b>PA30281</b> Air Dryer (Bendix 5008414PG).... <b>BA5379</b> Trans. (2 In. Kit) (29558117)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (29558118)..... <b>PT9415-MPG KIT</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	T404 w/Cummins N14 Eng. Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309 +</b> Fuel/Water Separator (Fleetguard FS1000)..... <b>BF1259</b> Coolant (Fleetguard WF2076)..... <b>BW5076</b>	T440 w/Paccar PX-8 Eng. Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309 +</b> Fuel/Water Separator (Fleetguard FS1003)..... <b>BF1293-SPS</b> Fuel/Water Separator (Fleetguard FS1065)..... <b>BF1378-SPS</b> Channel Flow Air (P611698)..... <b>CA30102</b> Air Dryer (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> Trans. Ele. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Diesel Exhaust Fluid (2888182).. <b>PE17000</b>
T400 w/Paccar PX-9 (8.9L) Eng. (2021) Lube (5444774)..... <b>B40142</b> Fuel (5303743)..... <b>BF63000</b>	T408 w/Cummins ISX Eng. Trans. (Fuller 4304827)..... <b>BT223</b>	T440 w/Paccar PX-9 (8.9L) Eng. (2017-18) Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309 +</b> Fuel/Water Separator Ele. (Fleetguard FS19764)..... <b>PF9814</b> Fuel/Water Separator Spin-on (Fleetguard FS1065)..... <b>BF1378-SPS</b> Fuel/Water Separator Spin-on (Fleetguard FS1003)..... <b>BF1293-SPS</b> Fuel (Fleetguard FF63009)..... <b>BF63000</b> Channel Flow Air (P611696)..... <b>CA5500</b> Channel Flow EXO Air (P611698)..... <b>CA30102</b> Cab Air (X1987001)..... <b>PA30093</b> Cab Air (SR2000059)..... <b>PA30281</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Trans. Ele. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b> Diesel Exhaust Fluid (5303604).. <b>PE17000</b> Diesel Exhaust Fluid (5303604).. <b>PE17000</b>
T400 w/Paccar PX-9 (8.9L) Eng. (2022) Lube (5444774)..... <b>B40142</b>	T409 w/Cummins ISX Eng. Dual-Flow Lube (Fleetguard LF9031)..... <b>BD7509 +</b> Dual-Flow Lube (Fleetguard LF9080)..... <b>BD7154 +</b> Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> Fuel (Fleetguard FF2200)..... <b>BF7766</b> Breather (Fleetguard CV50617).... <b>CV15000</b> Coolant (Fleetguard WF2126)..... <b>BW5086</b> Trans. (Fuller 4304827)..... <b>BT223</b>	T440 w/Paccar PX-9 (8.9L) Eng. (2019) Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309 +</b> Fuel/Water Separator (Fleetguard FS1003)..... <b>BF1293-SPS</b> Fuel (Fleetguard FF63009)..... <b>BF63000</b> Channel Flow Air (P611698)..... <b>CA5500</b> Channel Flow EXO Air (P611698)..... <b>CA30102</b> Cab Air (X1987001)..... <b>PA30093</b> Cab Air (SR2000059)..... <b>PA30281</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Trans. Ele. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b> Diesel Exhaust Fluid (5303604).. <b>PE17000</b> Diesel Exhaust Fluid (5303604).. <b>PE17000</b>
T401 Prime Mover w/Cat C12 Eng. F-F Lube (1R0716)..... <b>B99 +</b> B-P Lube (1W-8845)..... <b>B7577</b> Fuel/Water Separator (Open End for Bowl) (1335673)..... <b>BF1395-O</b> Fuel/Water Separator (w/Drain) (1335673)..... <b>BF1265</b> Fuel/Water Separator (w/Sensor Port) (1335673)..... <b>BF1395-SP</b> Fuel (1R-0749)..... <b>BF7587 +</b> Coolant (w/4 Units BTE) (9N-3368)..... <b>BW5137</b> Coolant (w/8 Units BTE) (9N-3367)..... <b>BW5139</b>	T440 w/Cummins ISL Eng. Dual-Flow Lube (3401544)..... <b>BD7309 +</b> Lube (Upgrade) (3401544)..... <b>B40142 +</b> Fuel/Water Separator Ele. (Fleetguard FS19764)..... <b>PF9814</b> Fuel/Water Separator Spin-on (Fleetguard FS1003)..... <b>BF1293-SPS</b> Fuel (4940647)..... <b>BF7924</b> Channel Flow Air (P611698)..... <b>CA30102</b> Air Dryer (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Diesel Exhaust Fluid (2888182).. <b>PE17000</b>	T440 w/Cummins ISL-G Eng. Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309 +</b> Coalescer Fuel (Fleetguard NG5900)..... <b>BF7695</b> Channel Flow Air (P611696)..... <b>CA5500</b> Air Dryer (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>
T404 w/Cat C15 Eng. Lube (1R0716)..... <b>B99 +</b> Fuel/Water Separator (Open End for Bowl) (1335673)..... <b>BF1395-O</b> Fuel/Water Separator (w/Drain) (1335673)..... <b>BF1265</b> Fuel/Water Separator (w/Sensor Port) (1335673)..... <b>BF1395-SP</b> Fuel Ele. (9M2342)..... <b>PF935</b> Fuel Spin-on (1R-0749)..... <b>BF7587 +</b> Coolant (9N-6123)..... <b>BW5139</b> Trans. (Fuller 4304827)..... <b>BT223</b>	T440 w/Cummins ISL-G Eng. Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309 +</b> Coalescer Fuel (Fleetguard NG5900)..... <b>BF7695</b> Channel Flow Air (P611696)..... <b>CA5500</b> Air Dryer (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	T440 w/Paccar PX-9 (8.9L) Eng. (2019) Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309 +</b> Fuel/Water Separator (Fleetguard FS1003)..... <b>BF1293-SPS</b> Fuel (Fleetguard FF63009)..... <b>BF63000</b> Channel Flow Air (P611698)..... <b>CA30102</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)
T440 w/Paccar PX-9 (8.9L) Eng. (2019) (Cont'd)	T450 w/Cummins 6BT5.9 (5.9L) Eng. (Cont'd)	T460 w/Cummins ISL Eng. (Mexico) (Cont'd)
<b>Cab Air</b> (SR2000059)..... <b>PA30281</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374</b>	T450 w/Cummins 6CT8.3 (8.3L) Eng.	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29545776)..... <b>PT9416-MPG KIT</b>	<b>F-F Lube</b> (3313281)..... <b>B205+</b>	T470 w/Cummins ISL Eng.
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29545779)..... <b>PT9415-MPG KIT</b>	<b>Dual-Flow Lube</b> (3318853)..... <b>BD103+</b>	<b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309+</b>
<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>Fuel/Water Separator</b> (3925274)..... <b>BF1280+</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1003)..... <b>BF1293-SPS</b>
<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	<b>Fuel</b> (3903640)..... <b>BF788</b>	<b>Fuel</b> (Fleetguard FF5636)..... <b>BF7924</b>
T440 w/Paccar PX-9 (8.9L) Eng. (2020)	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>Channel Flow Air</b> (P611698)..... <b>CA30102</b>
<b>Lube</b> (3401544)..... <b>B40142</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374+</b>
<b>Fuel/Water Separator</b> (Fleetguard FS1003)..... <b>BF1293-SPS</b>	T450 w/Cummins L10 Eng.	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Fuel</b> (5303743)..... <b>BF63000</b>	<b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196+</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Channel Flow EXO Air</b> (P611698)..... <b>CA30102</b>	<b>B-P Lube</b> (3304232)..... <b>B7577</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b>
<b>Cab Air</b> (SR2000059)..... <b>PA30281</b>	<b>Dual-Flow Lube</b> (3318853)..... <b>BD103+</b>	<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>
<b>Air Dryer</b> (Bendix 5008414PG)..... <b>BA5379</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1212)..... <b>BF1212+</b>	<b>Diesel Exhaust Fluid</b> (2010 Emissions) (2888182)..... <b>PE17000</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	<b>Fuel</b> (154789)..... <b>BF957-D+</b>	T470 w/Paccar PX-8 Eng.
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	<b>Air</b> (Don. P537791)..... <b>PA2705</b>	<b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309+</b>
<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1003)..... <b>BF1293-SPS</b>
<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	T450 w/Cummins M11 (10.8L) Eng. (To 12/1995)	<b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b>
T450 w/Cat 3176 (10.3L) Eng.	<b>Dual-Flow Lube</b> (3318853)..... <b>BD103+</b>	<b>Fuel</b> (Fleetguard FF5636)..... <b>BF7924</b>
<b>F-F Lube</b> ..... <b>B99+</b>	<b>Fuel/Water Separator</b> (3308638)..... <b>BF1212+</b>	<b>Channel Flow Air</b> (P611698)..... <b>CA30102</b>
<b>Fuel/Water Separator</b> (Fleetguard FS1212)..... <b>BF1212+</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374+</b>
<b>Fuel Spin-on</b> (1R0712)..... <b>BF614+</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Air</b> (w/Lid) (Don. P153551)..... <b>PA2705</b>	T450 w/Cummins M11 (10.8L) Eng. (12/1995-on)	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Air</b> (w/o Lid) (Don. P154575)..... <b>PA2715</b>	<b>Dual-Flow Lube</b> (3318853)..... <b>BD103+</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b>
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Fuel/Water Separator</b> (3329289)..... <b>BF1259</b>	<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>
<b>Air Dryer</b> (AD-SP System) (Bendix 5008414)..... <b>BA5374+</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>Diesel Exhaust Fluid</b> (2880298).. <b>PE17000</b>
<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2+</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b>	T470 w/Paccar PX-9 Eng.
T450 w/Cat 3306 (10.5L) Eng.	T450 w/Detroit Diesel Series 50 (8.5L) Eng.	<b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309+</b>
<b>Lube Ele.</b> (w/Paper Wrapper) (1R0659)..... <b>PT670</b>	<b>Lube</b> (23530573)..... <b>[2] B495</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1003)..... <b>BF1293-SPS</b>
<b>Lube Ele.</b> (w/Metal Wrapper) (1R0659)..... <b>PT7332</b>	<b>Fuel/Water Separator Spin-on</b> (w/Drain) (23535985)..... <b>BF5813+</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b>
<b>F-F Lube Spin-on</b> (1R0716)..... <b>B99+</b>	<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (23535985).. <b>BF5813-O+</b>	<b>Fuel</b> (Fleetguard FF5636)..... <b>BF7924</b>
<b>F-F Lube Spin-on</b> (Standard Vers.) (1R0739)..... <b>B76+</b>	<b>P. Fuel</b> (23530706)..... <b>BF5800+</b>	<b>Channel Flow Air</b> (P611698)..... <b>CA30102</b>
<b>F-F Lube Spin-on</b> (Severe Service) (1R0739)..... <b>B76-SS+</b>	<b>S. Fuel</b> (23530707)..... <b>BF5810</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374+</b>
<b>P. Fuel Ele.</b> (9M2341)..... <b>PF935</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>
<b>P. Fuel Spin-on</b> (1R0740)..... <b>BF970+</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>
<b>S. Fuel Spin-on</b> (1R0750)..... <b>BF7633+</b>	T460 w/Cummins ISL Eng. (Mexico)	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>
<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154+</b>	<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b>	<b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>	<b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>
T450 w/Cummins 6BT5.9 (5.9L) Eng.	<b>Fuel/Water Separator</b> (Fleetguard FS1000)..... <b>BF1259</b>	
<b>Lube</b> (3914395)..... <b>BT339+</b>	<b>Air</b> (Don. P153351)..... <b>PA1646-FN</b>	
<b>Fuel/Water Separator</b> (3925274)..... <b>BF1280+</b>	<b>Coolant</b> (Fleetguard WF2075)..... <b>BW5075</b>	
<b>Fuel</b> (3903640)..... <b>BF788</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	
<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>KENWORTH Trucks (cont'd)</b>	<b>KENWORTH Trucks (cont'd)</b>	<b>KENWORTH Trucks (cont'd)</b>
T470 w/Paccar PX-9 Eng. (Cont'd) <b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>	T600 w/Cummins ISX Eng. (Cont'd) <b>Radial Seal XP Air</b> (Don. P527484)..... <b>RS2863XP</b>	T600 w/Detroit Diesel Series 60 Eng. (Cont'd) <b>Fuel/Water Separator</b> (Open End for Bowl) (Racor S3226P)..... <b>BF1346-O</b>
T470 w/Paccar MX-13 (12.9L) Eng. (2019) <b>F-F Lube</b> (2047411PE)..... <b>P40069</b>	<b>Axial Seal Air</b> (Don. P153551)..... <b>PA2705</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1212)..... <b>BF1212 +</b>
<b>Centrifugal Lube</b> (1922496PE).... <b>BC40148</b>	<b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b>	<b>S. Fuel</b> ..... <b>BF5810</b>
<b>Fuel/Water Separator</b> (K371022) <b>PF46237</b>	<b>Breather</b> (1/07-on) (3683918)..... <b>CV15000</b>	<b>23 In. Air</b> (KW852M)..... <b>LL2317 +</b>
<b>Fuel/Water Separator</b> (2133096PE)..... <b>PF46106</b>	<b>Coolant</b> (w/o Chemical) (Fleetguard WF2127)..... <b>B5087</b>	<b>22 9/16 In. Air</b> (Don. P537791).... <b>PA2705</b>
<b>Cab Air</b> (SR2000059)..... <b>PA30281</b>	<b>Coolant</b> (w/4 Units BTE)..... <b>BW5137</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>
<b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374</b>	<b>Coolant</b> (w/11 1/2 Units BTA+) (Fleetguard WF2126)..... <b>BW5086</b>	<b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>
<b>Coolant</b> (1843659PE)..... <b>B5088 +</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>Coolant</b> (w/16 Units BTE) (Fleetguard WF2055)..... <b>BW5140</b>
<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>
<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>Steering</b> (Fleetguard LF637)..... <b>P528</b>
T480 w/Paccar PX-9 (8.9L) Eng. (2022) <b>Lube</b> (5444774)..... <b>B40142</b>	T600 w/Cummins NTC Series Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b>	T600, T600B w/Cat C15 Eng. <b>Lube</b> (1R1808)..... <b>B7299 +</b>
T600 w/Cat C12 Eng. <b>Lube</b> (1R0716)..... <b>B99 +</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1212)..... <b>BF1212 +</b>	<b>Fuel/Water Separator Ele.</b> (Davco 380087)..... <b>PF7680</b>
<b>Opt. Fuel/Water Separator</b> ..... <b>BF1259</b>	<b>Air</b> (Don. P537791)..... <b>PA2705</b>	<b>Fuel/Water Separator Spin-on</b> (256-8753)..... <b>BF1259</b>
<b>Fuel Spin-on</b> (1R0749)..... <b>BF7587 +</b>	<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	<b>Fuel/Water Separator Spin-on</b> ..... <b>BF1212 +</b>
<b>Air</b> (Don. P153551)..... <b>PA2705</b>	<b>Steering</b> (Fleetguard LF637)..... <b>P528</b>	<b>Fuel</b> ..... <b>BF7587 +</b>
<b>Air</b> (Don. P154575)..... <b>PA2715</b>	T600 w/Cummins M11 Eng. <b>Dual-Flow Lube</b> (Fleetguard LF3000)..... <b>BD103 +</b>	<b>Air</b> (Don. P153551)..... <b>PA2705</b>
<b>Coolant</b> ..... <b>BW5137</b>	<b>Fuel/Water Separator</b> (3308638)..... <b>BF1212 +</b>	<b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b>
<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	<b>Fuel</b> (158172)..... <b>BF957 +</b>	<b>Coolant</b> (Fleetguard WF2122).... <b>B5088 +</b>
<b>Steering</b> (Nelson 83804E)..... <b>P528</b>	<b>Std. Air</b> (Don. P153551)..... <b>PA2705</b>	<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>
T600 w/Cat C13 Eng. <b>Lube</b> (1R1808)..... <b>B7299 +</b>	<b>Conical Air</b> (Don. P154575)..... <b>PA2715</b>	<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>
<b>Fuel/Water Separator Ele.</b> ..... <b>PF7755</b>	<b>Coolant</b> (209606)..... <b>BW5137</b>	T600, T600A w/Cat 3406 (14.6L) Eng. <b>Lube</b> (1R0716)..... <b>B99 +</b>
<b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1000)..... <b>BF1259</b>	<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	<b>Opt. Fuel/Water Separator</b> ..... <b>BF1259</b>
<b>Fuel</b> (1R0749)..... <b>BF7587 +</b>	<b>Steering</b> (Nelson 83804E)..... <b>P528</b>	<b>Fuel Spin-on</b> (1R-0749)..... <b>BF7587 +</b>
<b>Air</b> (Don. P153551)..... <b>PA2705</b>	T600 w/Cummins N14 Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b>	<b>Air</b> (Don. P153551)..... <b>PA2705</b>
<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>
<b>Coolant</b> (Fleetguard WF2071).... <b>BW5071</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1212)..... <b>BF1212 +</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	<b>Fuel</b> (Fleetguard FF1108)..... <b>BF888</b>	<b>Coolant</b> (w/o Chemical) (Fleetguard WF2122)..... <b>B5088 +</b>
<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>Air</b> (KW852M)..... <b>LL2317 +</b>	<b>Coolant</b> (w/4 Units BTE)..... <b>BW5137</b>
T600 w/Cat 3126 Eng. <b>Lube</b> (1R0716)..... <b>B99 +</b>	<b>Air</b> (Don. P153551)..... <b>PA2705</b>	<b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>
<b>Fuel Ele.</b> (8H7204)..... <b>PF935</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>
<b>Fuel Spin-on</b> (1R-0749)..... <b>BF7587 +</b>	<b>Coolant</b> (w/4 Units BTA+) (3315116)..... <b>BW5071</b>	T600A w/Cat 3306 Eng. <b>Lube</b> (Standard Vers.) (1R0739).. <b>B76</b>
<b>Air</b> (Don. P537791)..... <b>PA2705</b>	<b>Coolant</b> (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b>	<b>Fuel Spin-on</b> (1R0740)..... <b>BF970 +</b>
<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	<b>Coolant</b> (w/23 Units BTA+) (Fleetguard WF2076)..... <b>BW5076</b>	<b>Air</b> (Don. P154575)..... <b>PA2715</b>
<b>Steering</b> (Nelson 83213H)..... <b>PT903</b>	<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	<b>Air</b> (Don. P153551)..... <b>PA2705</b>
T600 w/Cummins ISX Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154 +</b>	<b>Steering</b> (Nelson 83804E)..... <b>P528</b>	T600A w/Cat 3408 (18.0L) Eng. <b>F-F Lube</b> (1R0716)..... <b>[2] B99 +</b>
<b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>	T600 w/Detroit Diesel Series 60 Eng. <b>F-F Lube</b> (To 1993)..... <b>B95 +</b>	<b>Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b>
<b>Fuel/Water Separator Ele.</b> (Fleetguard FF5369)..... <b>PF7744</b>	<b>F-F Lube</b> (1993-on) (23527033)... <b>[2] B495</b>	<b>Fuel Spin-on</b> (Std. Efficiency) (4N5823)..... <b>BF614 +</b>
<b>Fuel/Water Separator Ele.</b> ..... <b>PF7755</b>	<b>B-P Lube</b> (To 1993)..... <b>B7577</b>	<b>Fuel Spin-on</b> (High Efficiency Vers.) (1R0749)..... <b>BF7587 +</b>
<b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1040)..... <b>BF1277-SPS</b>	<b>Fuel/Water Separator</b> (w/Drain) (Racor S3226P)..... <b>BF1346</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>
<b>Fuel</b> (Fleetguard FF2200)..... <b>BF7766</b>	<b>Fuel/Water Separator</b> (w/Sensor Port) (Racor S3226P)..... <b>BF1346-SP</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
<b>Fuel</b> (Fleetguard FF2203)..... <b>BF7760</b>		
<b>Radial Seal Air</b> (Don. P527484).... <b>RS2863</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)
T600A w/Cat 3408 (18.0L) Eng. (Cont'd) <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	T600A w/Cummins ISB (5.9L) Eng. <b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b> <b>Lube</b> (4897898)..... <b>BT237</b> <b>Fuel</b> (Fleetguard FF5632)..... <b>BF7940</b> <b>Air</b> (White 220055064)..... <b>PA2705</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	T600A w/Cummins ISX 15.0 (14.9L) Eng. (Cont'd) <b>Trans. Ele. (2 In. Kit)</b> (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele. (4 In. Kit)</b> (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2+</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>
T600A w/Cat C10 Eng. <b>F-F Lube</b> ..... <b>B99+</b> <b>B-P Lube</b> ..... <b>B7577</b> <b>Fuel/Water Separator</b> ..... <b>BF5812</b> <b>Fuel Spin-on</b> ..... <b>BF614+</b> <b>Air</b> ..... <b>PA2705</b>	T600A w/Cummins ISC 8.3 (8.3L) Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309+</b> <b>Dual-Flow Lube</b> (Fleetguard LF9548)..... <b>BD324+</b> <b>Fuel</b> (Fleetguard FF5488)..... <b>BF7815</b> <b>Fuel</b> (Fleetguard FF5636)..... <b>BF7924</b> <b>Air</b> (White 220055064)..... <b>PA2705</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b> <b>Coolant</b> (w/23 Units BTA+) (Fleetguard WF2076)..... <b>BW5076</b> <b>Coolant</b> (w/Controlled Release) (Fleetguard WF2121)..... <b>BW5250</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	T600A w/Cummins L10 Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103+</b> <b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196+</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Fuel</b> (154789)..... <b>BF957-D+</b>
T600A w/Cat C11 (11.1L) Eng. <b>Lube</b> (1R1808)..... <b>B7299+</b> <b>Fuel/Water Separator</b> (3329289). <b>BF1259</b> <b>Fuel</b> (Standard Vers.) (4N5823)... <b>BF614+</b> <b>Fuel</b> (High Efficiency Vers.) (1R0749)..... <b>BF7587+</b> <b>Fuel</b> (1R0762)..... <b>BF7753</b> <b>Air</b> (White 220055064)..... <b>PA2705</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	T600A w/Cummins M11 (10.8L) Eng. (To 12/1995) <b>Dual-Flow Lube</b> (3318853)..... <b>BD103+</b> <b>Fuel/Water Separator</b> (3308638). <b>BF1212+</b> <b>Air</b> (White 220055064)..... <b>PA2705</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	T600A w/Cummins M11 (10.8L) Eng. (12/1995-on) <b>Dual-Flow Lube</b> (3318853)..... <b>BD103+</b> <b>Fuel/Water Separator</b> (3329289). <b>BF1259</b> <b>Air</b> (White 220055064)..... <b>PA2705</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>
T600A w/Cat C12 (12.0L) Eng. <b>Lube</b> (Standard Vers.) (1R0716).. <b>B99+</b> <b>Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299+</b> <b>B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (Standard Vers.) (4N5823)..... <b>BF614+</b> <b>Fuel Spin-on</b> (High Efficiency Vers.)..... <b>BF7587+</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2+</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	T600A w/Cummins ISM 10.8 (10.8L) Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154+</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Air</b> (White 220055064)..... <b>PA2705</b> <b>Coolant</b> (w/o Chemical) (Fleetguard WF2127)..... <b>B5087</b> <b>Coolant</b> (Controlled Release BTA+) (Fleetguard WF2121)..... <b>BW5250</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b> <b>Trans. Ele. (2 In. Kit)</b> (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele. (4 In. Kit)</b> (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2+</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	T600A w/Cummins M11 (10.8L) Eng. (12/1995-on) <b>Dual-Flow Lube</b> (3318853)..... <b>BD103+</b> <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309+</b> <b>Fuel/Water Separator</b> (3308638). <b>BF1212+</b> <b>Fuel/Water Separator</b> (3889716). <b>BF1259</b> <b>Fuel/Water Separator</b> (3406889). <b>BF1293-SPS</b> <b>Fuel</b> (154789)..... <b>BF957-D+</b> <b>Air</b> (Don. P153551)..... <b>PA2705</b> <b>Air</b> (Don. P154575)..... <b>PA2715</b> <b>Coolant</b> (3315116)..... <b>BW5071</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>
T600A w/Cat C13 (12.5L) Eng. <b>Lube</b> (1R1808)..... <b>B7299+</b> <b>Lube</b> (2492347)..... <b>[2] B7402</b> <b>Fuel/Water Separator</b> (3329289). <b>BF1259</b> <b>Fuel</b> (Standard Vers.) (4N5823)... <b>BF614+</b> <b>Fuel</b> (High Efficiency Vers.) (1R0749)..... <b>BF7587+</b> <b>Air</b> (White 220055064)..... <b>PA2705</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	T600A w/Cummins ISM 10.8 (10.8L) Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154+</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel</b> (4088272)..... <b>BF7766</b> <b>Air</b> (White 220055064)..... <b>PA2705</b> <b>Coolant</b> (Fleetguard WF2127)..... <b>B5087</b>	T600A w/Cummins N14 (14.0L) Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103+</b> <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309+</b> <b>Fuel/Water Separator</b> (3308638). <b>BF1212+</b> <b>Fuel/Water Separator</b> (3889716). <b>BF1259</b> <b>Fuel/Water Separator</b> (3406889). <b>BF1293-SPS</b> <b>Fuel</b> (154789)..... <b>BF957-D+</b> <b>Air</b> (Don. P153551)..... <b>PA2705</b> <b>Air</b> (Don. P154575)..... <b>PA2715</b> <b>Coolant</b> (3315116)..... <b>BW5071</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>
T600A w/Cummins 6BT5.9L (5.9L) Eng. <b>Lube</b> (3914395)..... <b>BT339+</b> <b>Lube</b> (Chrysler 5083285AA)..... <b>BT7349</b> <b>Fuel/Water Separator</b> (3925274). <b>BF1280+</b> <b>Fuel</b> (3903640)..... <b>BF788</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	T600A w/Cummins ISX 15.0 (14.9L) Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154+</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel</b> (4088272)..... <b>BF7766</b> <b>Air</b> (White 220055064)..... <b>PA2705</b> <b>Coolant</b> (Fleetguard WF2127)..... <b>B5087</b>	T600A w/Detroit Diesel Series 50 (8.5L) Eng. <b>Lube</b> (23530573)..... <b>[2] B495</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (23535985)..... <b>BF5813+</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (23535985).. <b>BF5813-O+</b> <b>P. Fuel</b> (23530706)..... <b>BF5800+</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b> <b>Air</b> (Don. P153551)..... <b>PA2705</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)
T600A w/Detroit Diesel Series 50 (8.5L) Eng. (Cont'd) Opt. Trans. Spin-on (Fuller 17237)..... <b>B2+</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	T800 w/Cat 3176 (10.3L) Eng. F-F Lube (Std. Efficiency) (1R0716)..... <b>B99+</b> F-F Eng. Lube (High Efficiency Vers.) (1R1808)..... <b>B7299+</b> F-F Eng. Lube (1R0713)..... <b>[2] BT230+</b> F-F Lube (1R0714)..... <b>[2] B75</b> Opt. B-P Lube (1W8845)..... <b>B7577</b> P. Fuel Ele. (9M2342)..... <b>[2] PF935</b> P. Fuel Spin-on (1R0740)..... <b>BF970+</b> S. Fuel Spin-on (1R0750)..... <b>BF7633+</b> Air (Don. P154575)..... <b>PA2715</b> Air (Don. P153551)..... <b>PA2705</b> Trans. Spin-on (Fuller 4304827)..... <b>BT223</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2+</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	T604 w/Cummins ISX Eng. Dual-Flow Lube (Fleetguard LF9001)..... <b>BD7154+</b> Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> Dual-Flow Lube (Fleetguard LF9031)..... <b>BD7509+</b> Fuel/Water Separator (Fleetguard FS1040)..... <b>BF1277-SPS</b> Fuel/Water Separator (Upgrade) (Fleetguard FS1007)..... <b>BF1274-SP</b> Coolant (Fleetguard WF2126)..... <b>BW5086</b> Trans. (Fuller 4304827)..... <b>BT223</b>
T600A w/Detroit Diesel Series 60 (12.7L) Eng. (To 1993) Lube (23530573)..... <b>[2] B495</b> Lube (Don. DELF3998)..... <b>[2] B495-SS</b> B-P Lube (23530413)..... <b>B7577</b> Fuel/Water Separator Spin-on (w/Drain) (23535985)..... <b>BF5813+</b> Fuel/Water Separator Spin-on (Open End for Bowl) (23535985)..... <b>BF5813-O+</b> P. Fuel (23530706)..... <b>BF5800+</b> S. Fuel (23530707)..... <b>BF5810</b> Air (Don. P153551)..... <b>PA2705</b> Air (Don. P154575)..... <b>PA2715</b> Air (Don. P182008)..... <b>LL2317+</b> Air Dryer..... <b>BA5374+</b> Coolant (w/4 Units BTA+) (25012893)..... <b>BW5071</b> Coolant (Controlled Release BTE) (23516489)..... <b>BW5201</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827)..... <b>BT223</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2+</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	T600B w/Cat C13 Eng. Lube (1R1808)..... <b>B7299+</b> Fuel/Water Separator..... <b>BF1212+</b> Fuel (1R0749)..... <b>BF7587+</b> Air (Don. P153551)..... <b>PA2705</b> Air Dryer (Bendix 5008414)..... <b>BA5374+</b> Opt. Trans. (Fuller 17237)..... <b>B2+</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	T608 w/Cat C15 Eng. Lube (1R0716)..... <b>B99+</b> Fuel/Water Separator (Open End for Bowl) (1335673)..... <b>BF1395-O</b> Fuel/Water Separator (w/Drain) (1335673)..... <b>BF1265</b> Fuel/Water Separator (w/Sensor Port) (1335673)..... <b>BF1395-SP</b> Fuel (1R-0749)..... <b>BF7587+</b> Coolant (9N-6123)..... <b>BW5139</b> Trans. (Fuller 4304827)..... <b>BT223</b>
T600A w/Detroit Diesel Series 60 (12.7L) Eng. (1993-on) Lube (23530573)..... <b>[2] B495</b> Lube (Don. DELF3998)..... <b>[2] B495-SS</b> Fuel/Water Separator Spin-on (w/Drain) (23535985)..... <b>BF5813+</b> Fuel/Water Separator Spin-on (Open End for Bowl) (23535985)..... <b>BF5813-O+</b> P. Fuel (23530706)..... <b>BF5800+</b> S. Fuel (23530707)..... <b>BF5810</b> Air (Don. P153551)..... <b>PA2705</b> Air (Don. P154575)..... <b>PA2715</b> Air (Don. P182008)..... <b>LL2317+</b> Air Dryer..... <b>BA5374+</b> Coolant (w/4 Units BTA+) (25012893)..... <b>BW5071</b> Coolant (Controlled Release BTE) (23516489)..... <b>BW5201</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827)..... <b>BT223</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2+</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	T600B w/Cummins ISX Eng. Dual-Flow Lube (3406809)..... <b>BD7154+</b> Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> Fuel/Water Separator Ele. (Davco 380087)..... <b>PF7680</b> Fuel/Water Separator Spin-on..... <b>BF1212+</b> Fuel (4088272)..... <b>BF7766</b> Fuel Spin-on (Fleetguard FF2203)..... <b>BF7760</b> Air (w/o Lid) (Don. P154575)..... <b>PA2715</b> Air (w/Lid) (Don. P153551)..... <b>PA2705</b> Air Dryer (Bendix 5008414)..... <b>BA5374+</b> Breather (1/07-on) (3683918)..... <b>CV15000</b> Coolant (Fleetguard WF2127)..... <b>B5087</b> Opt. Trans. (Fuller 17237)..... <b>B2+</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	T609 w/Cummins ISX Eng. Dual-Flow Lube (Fleetguard LF9031)..... <b>BD7509+</b> Dual-Flow Lube (Fleetguard LF9080)..... <b>BD7154+</b> Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> Fuel (Fleetguard FF2200)..... <b>BF7766</b> Coolant (Fleetguard WF2126)..... <b>BW5086</b> Trans. (Fuller 4304827)..... <b>BT223</b>
T600A w/Detroit Diesel Series 60 (12.7L) Eng. (1993-on) Lube (23530573)..... <b>[2] B495</b> Lube (Don. DELF3998)..... <b>[2] B495-SS</b> Fuel/Water Separator Spin-on (w/Drain) (23535985)..... <b>BF5813+</b> Fuel/Water Separator Spin-on (Open End for Bowl) (23535985)..... <b>BF5813-O+</b> P. Fuel (23530706)..... <b>BF5800+</b> S. Fuel (23530707)..... <b>BF5810</b> Air (Don. P153551)..... <b>PA2705</b> Air (Don. P154575)..... <b>PA2715</b> Air (Don. P182008)..... <b>LL2317+</b> Air Dryer..... <b>BA5374+</b> Coolant (w/4 Units BTA+) (25012893)..... <b>BW5071</b> Coolant (Controlled Release BTE) (23516489)..... <b>BW5201</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827)..... <b>BT223</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2+</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	T600B w/Cummins N14 Eng. F-F Lube..... <b>B196+</b> B-P Lube..... <b>B7577</b> Dual-Flow Lube..... <b>BD103+</b> Fuel..... <b>BF957-D+</b> Air (Don. P153551)..... <b>PA2705</b>	T650 w/Cat C15 Eng. Lube (1R0716)..... <b>B99+</b> Fuel/Water Separator (Open End for Bowl) (1335673)..... <b>BF1395-O</b> Fuel/Water Separator (w/Drain) (1335673)..... <b>BF1265</b> Fuel/Water Separator (w/Sensor Port) (1335673)..... <b>BF1395-SP</b> Fuel (1R-0749)..... <b>BF7587+</b> Coolant (9N-6123)..... <b>BW5139</b> Trans. (Fuller 4304827)..... <b>BT223</b>
	T604 w/Caterpillar C15 Eng. Lube (1R0716)..... <b>B99+</b> Fuel/Water Separator (Open End for Bowl) (1335673)..... <b>BF1395-O</b> Fuel/Water Separator (w/Drain) (1335673)..... <b>BF1265</b> Fuel/Water Separator (w/Sensor Port) (1335673)..... <b>BF1395-SP</b> Fuel (1R-0749)..... <b>BF7587+</b> Coolant (9N-6123)..... <b>BW5139</b> Trans. (Fuller 4304827)..... <b>BT223</b>	T650 w/Cummins ISX Eng. Dual-Flow Lube (Fleetguard LF9001)..... <b>BD7154+</b> Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> Fuel/Water Separator (Fleetguard FS1040)..... <b>BF1277-SPS</b> Fuel/Water Separator (Upgrade) (Fleetguard FS1007)..... <b>BF1274-SP</b> Coolant (Fleetguard WF2126)..... <b>BW5086</b> Trans. (Fuller 4304827)..... <b>BT223</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)
T660 w/Cat C11 Eng. Lube (1R1808)..... <b>B7299 +</b> Fuel (1R0749)..... <b>BF7587 +</b> Channel Flow Air (P611696)..... <b>CA5500</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	T660 w/Cummins ISM 10.8 (10.8L) Eng. (Cont'd) Air Dryer (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> Breather (3683918)..... <b>CV15000</b> Coolant (Fleetguard WF2071)..... <b>BW5071</b> Coolant (w/o Chemicals) (4920476)..... <b>B5090</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Diesel Exhaust Fluid (5303604)..... <b>PE17000</b>	T660 w/Cummins ISX 11.9G (11.9L) Eng. (Cont'd) Coolant (w/11 1/2 Units BTA+) (4907485)..... <b>BW5086</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>
T660 w/Cat C13 Eng. F-F Lube (1R1808)..... <b>B7299 +</b> F-F Lube (249-2347)..... <b>[2] B7402</b> Fuel/Water Separator (256-8753)..... <b>BF1259</b> Fuel (1R0749)..... <b>BF7587 +</b> Channel Flow Air (P611696)..... <b>CA5500</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Breather (2007-on) (296-8325)..... <b>CV15008</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Trans. (Fuller 4304827)..... <b>BT223</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	T660 w/Cummins ISX 11.9 Eng. Dual-Flow Lube (3101869)..... <b>BD7154 +</b> Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> Fuel/Water Separator Ele. (Fleetguard FS1029W)..... <b>PF7680</b> Fuel/Water Separator Ele. (Fleetguard FS19729)..... <b>PF7755</b> Fuel/Water Separator Ele. (Fleetguard FS19764)..... <b>PF9814</b> Fuel/Water Separator Ele. (Fleetguard FS19765)..... <b>PF7930</b> Fuel/Water Separator (K371004)..... <b>PF9928</b> Fuel (Pre-2010 Emissions) (4920586)..... <b>BF7766</b> Fuel (Pre-2010 Emissions) (Fleetguard FF2203)..... <b>BF7760</b> Fuel (2010 Emissions) (Fleetguard FF5686)..... <b>BF9860 +</b> Fuel (2010 Emissions) (Fleetguard FF5776)..... <b>BF9885 +</b> Fuel (Upgrade) (Fleetguard FF5825NN)..... <b>BF46129</b> Channel Flow Air (P611696)..... <b>CA5500</b> Air Dryer (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> Breather (4312013)..... <b>CV15000</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b> Diesel Exhaust Fluid (5303604)..... <b>PE17000</b>	T660 w/Cummins ISX15 Eng. Dual-Flow Lube (4331005)..... <b>BD7154 +</b> Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> Fuel/Water Separator (K371011)..... <b>PF46081</b> Fuel/Water Separator Ele. (Fleetguard FS19764)..... <b>PF9814</b> Fuel (Standard) (Fleetguard FF5776)..... <b>BF9885 +</b> Fuel (Upgrade) (Fleetguard FF5825NN)..... <b>BF46129</b> Fuel (Upgrade) (Fleetguard FF5811)..... <b>BF46179</b> Channel Flow Air (P611696)..... <b>CA5500</b> Cab Air (SR2000059)..... <b>PA30281</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Breather (4312013)..... <b>CV15000</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b> Diesel Exhaust Fluid (5303604)..... <b>PE17000</b>
T660 w/Cat C15 Eng. F-F Lube (1R1808)..... <b>B7299 +</b> Fuel/Water Separator Ele. (Fleetguard FF5369)..... <b>PF7744</b> Fuel/Water Separator Spin-on (256-8753)..... <b>BF1259</b> Fuel (1R0749)..... <b>BF7587 +</b> Channel Flow Air (P611696)..... <b>CA5500</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Breather (2007-on) (296-8325)..... <b>CV15008</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Trans. (Fuller 4304827)..... <b>BT223</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	T660 w/Cummins ISL Eng. Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309 +</b> Fuel/Water Separator (Fleetguard FS1065)..... <b>BF1378-SPS</b> Fuel (Fleetguard FF5636)..... <b>BF7924</b> Channel Flow Air (P611696)..... <b>CA5500</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Coolant (Fleetguard WF2071)..... <b>BW5071</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	T660 w/Paccar MX Eng. Lube Ele. (1643070)..... <b>P40019</b> Lube Spinner (1643072)..... <b>BC7326 +</b> Fuel/Water Separator Ele. (K37-1005)..... <b>PF9928</b> Fuel/Water Separator Spin-on (Fleetguard FS1000)..... <b>BF1259</b> Fuel (1655115)..... <b>BF9927</b> Channel Flow Air (P611696)..... <b>CA5500</b> Air Dryer (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> Coolant (1843659)..... <b>B5088 +</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Diesel Exhaust Fluid (5303604)..... <b>PE17000</b>
T660 w/Cummins ISM 10.8 (10.8L) Eng. Dual-Flow Lube (Fleetguard LF9001)..... <b>BD7154 +</b> Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> Fuel/Water Separator Ele. (Fleetguard FS19727)..... <b>PF7895</b> Fuel/Water Separator Ele. (Fleetguard FS1029W)..... <b>PF7680</b> Fuel/Water Separator Spin-on (Fleetguard FS1000)..... <b>BF1259</b> Fuel (2010 Emissions) (Fleetguard FF5686)..... <b>BF9860 +</b> Channel Flow Air (P611696)..... <b>CA5500</b> Channel Flow Air (P611698)..... <b>CA30102</b>	T660 w/Cummins ISX 11.9G (11.9L) Eng. Dual-Flow Lube (2882674)..... <b>BD7154 +</b> Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> Fuel/Water Separator (3606712)..... <b>BF7695</b> Channel Flow Air (Don. P616056)..... <b>CA5500</b> Air Dryer..... <b>BA5374 +</b> Coolant (w/o Chemical) (3680434)..... <b>B5087</b>	T660 w/Paccar MX-13 (12.9L) Eng. (2014-17) Lube Ele. (1643070)..... <b>P40019</b> Centrifugal Lube (1922496)..... <b>BC40148</b> Fuel/Water Separator (Fleetguard FS19728)..... <b>PF7782</b> Fuel/Water Separator (Fleetguard FS19729)..... <b>PF7755</b> Fuel/Water Separator (K371009)..... <b>PF9929</b> Fuel/Water Separator (K371012)..... <b>PF46082</b> Fuel (1852006)..... <b>PF46106</b> Channel Flow Air (P611696)..... <b>CA5500</b> Channel Flow Air (P611698)..... <b>CA30102</b> Cab Air (SR2000059)..... <b>PA30281</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>KENWORTH Trucks (cont'd)</b>	<b>KENWORTH Trucks (cont'd)</b>	<b>KENWORTH Trucks (cont'd)</b>
T660 w/Paccar MX-13 (12.9L) Eng. (2014-17) (Cont'd)	T680 w/Cummins ISX 11.9 (11.9L) Eng. (2019)	T680 w/Cummins ISX 15.0 (14.9L) Eng. (2013-18)
Coolant (1843659)..... B5088 +	Dual-Flow Lube (4367100)..... BD50000	Dual-Flow Lube (Fleetguard LF9031)..... BD7509 +
Trans. (Fuller 4304827)..... BT223	Fuel (2893612)..... BF9885	Dual-Flow Lube (4331005)..... BD7154 +
Opt. Trans. (Fuller 17237)..... B2 +	EnduraCube Air (P621725)..... PA32000	Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... BD50000
Steering (Nelson 87904M)..... PT9354-MPG	Cab Air (X1988001)..... PA30093	Fuel/Water Separator Ele. (K371004)..... PF9928
Diesel Exhaust Fluid (5303604).. PE17000	Air Dryer (Bendix 5008414)..... BA5374	Fuel/Water Separator Ele. (Fleetguard FS19765)..... PF7930
T660 w/Paccar MX-13 (12.9L) Eng. (2018)	Steering (Nelson 87904M)..... PT9354-MPG	Fuel/Water Separator (K371029) PF46081
F-F Lube (2047411PE)..... P40069	Diesel Exhaust Fluid (Fleetguard UF101)..... PE17000	Fuel (Fleetguard FF5686)..... BF9860 +
Centrifugal Lube (1922496PE).. BC40148	T680 w/Cummins ISX 11.9 (11.9L) Eng. (2020)	Fuel (Standard) (Fleetguard FF5776)..... BF9885 +
Fuel (1852006PE)..... PF46106	Lube (4367100)..... BD50000	Fuel (Upgrade) (Fleetguard FF5825NN)..... BF46129
Channel Flow Air (P611696)..... CA5500	Fuel (2893612)..... BF9885	EnduraCube Air (P621725)..... PA32000
Cab Air (SR2000059)..... PA30281	EnduraCube Air (Don. P621725) PA32000	EnduraCube Air (P621730)..... PA32003
Air Dryer (Bendix 5008414)..... BA5374 +	Cab Air (Fresh Air) (X1987001).... PA30093	Cab Air (X1987001)..... PA30093
Coolant (1843659PE)..... B5088 +	Cab Air (Recirculation) (W2084001)..... PA30107	Cab Air Foam (W2084001)..... PA30107
Trans. (Fuller 4304827)..... BT223	Air Dryer (Bendix 5008414)..... BA5374 +	Air Dryer (Bendix 5008414)..... BA5374 +
Steering (Nelson 87904M)..... PT9354-MPG	Trans. (Fuller 4304827)..... BT223	Breather (4312013)..... CV15000
Opt. Rear Axle (Meritor 3280V8394)..... B233	Steering (Nelson 87904M)..... PT9354-MPG	Coolant (Fleetguard WF2127)..... B5087
Diesel Exhaust Fluid (5303604).. PE17000	T680 w/Cummins ISX 11.9G (11.9L) Eng. (2018)	Trans. (Fuller 4304827)..... BT223
T680 w/Cummins ISX 11.9 (11.9L) Eng. (2014-17)	Dual-Flow Lube (4367100)..... BD50000	Opt. Trans. (Fuller 17237)..... B2 +
Dual-Flow Lube (Fleetguard LF9031)..... BD7509 +	Fuel/Water Separator (3607140) BF7695	Steering (Nelson 87904M)..... PT9354-MPG
Dual-Flow Lube (4331005)..... BD7154 +	EnduraCube Air (P621725)..... PA32000	Diesel Exhaust Fluid (4388378).. PE17002 KIT
Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... BD50000	Cab Air (X1987001)..... PA30093	Diesel Exhaust Fluid (5303604).. PE17000
Fuel/Water Separator Ele. (K371004)..... PF9928	Coolant (3680434)..... B5087	T680 w/Cummins ISX 15.0 (14.9L) Eng. (2019)
Fuel/Water Separator Ele. (Fleetguard FS19764)..... PF9814	Trans. (Fuller 4304827)..... BT223	Dual-Flow Lube (4367100)..... BD50000
Fuel/Water Separator Ele. (Fleetguard FS19765)..... PF7930	Steering (Nelson 87904M)..... PT9354-MPG	Fuel/Water Separator (K371021) PF46236
Fuel (Fleetguard FF5686)..... BF9860 +	T680 w/Cummins ISX 11.9G (11.9L) Eng. (2019)	Fuel (5365988)..... BF46129 +
Fuel (Standard) (Fleetguard FF5776)..... BF9885 +	Dual-Flow Lube (4367100)..... BD50000	EnduraCube Air (P621725)..... PA32000
Fuel (Upgrade) (Fleetguard FF5825NN)..... BF46129	Fuel/Water Separator (3607140) [2] BF7695	Cab Air (X1987001)..... PA30093
EnduraCube Air (P621725)..... PA32000	EnduraCube Air (P621725)..... PA32000	Air Dryer (Bendix 5008414)..... BA5374 +
EnduraCube Air (P621730)..... PA32003	Cab Air (X1987001)..... PA30093	Trans. (Fuller 4304827)..... BT223
Cab Air (X1987001)..... PA30093	Air Dryer (Bendix 5008414)..... BA5374 +	Steering (Nelson 87904M)..... PT9354-MPG
Cab Air Foam (W2084001)..... PA30107	Coolant (3680434)..... B5087	T680 w/Cummins ISX 15.0 (14.9L) Eng. (2020)
Air Dryer (Bendix 5008414)..... BA5374 +	Steering (Nelson 87904M)..... PT9354-MPG	Dual-Flow Lube (4367100)..... BD50000
Breather (4312013)..... CV15000	T680 w/Cummins ISX 11.9G (11.9L) Eng. (2020)	Fuel/Water Separator (K371021) PF46236
Coolant (Fleetguard WF2127)..... B5087	Dual-Flow Lube (Fleetguard LF14000NN)..... BD50000	Fuel (5365988)..... BF46129
Trans. (Fuller 4304827)..... BT223	Fuel (Fleetguard NG5900)..... BF7695	EnduraCube Air (Don. P621725) PA32000
Opt. Trans. (Fuller 17237)..... B2 +	EnduraCube Air (Don. P621725) PA32000	Cab Air (Fresh Air) (X1987001).... PA30093
Steering (Nelson 87904M)..... PT9354-MPG	Cab Air (Fresh Air) (X1987001).... PA30093	Cab Air (Recirculation) (W2084001)..... PA30107
Diesel Exhaust Fluid (5303604).. PE17000	Cab Air (Recirculation) (W2084001)..... PA30107	Air Dryer (Bendix 5008414)..... BA5374 +
T680 w/Cummins ISX 11.9 (11.9L) Eng. (2018)	Air Dryer (Bendix 5008414)..... BA5374 +	Trans. (Fuller 4304827)..... BT223
Dual-Flow Lube (Fleetguard LF14000NN)..... BD50000	Trans. (Fuller 4304827)..... BT223	Steering (Nelson 87904M)..... PT9354-MPG
Fuel (Fleetguard FF5776)..... BF9885	Steering (Nelson 87904M)..... PT9354-MPG	T680 w/Cummins ISX 15.0 (14.9L) Eng. (2021)
EnduraCube Air (P621725)..... PA32000	T680 w/Cummins ISX 11.9G (11.9L) Eng. (2021)	Lube (5575298)..... B40145
Cab Air (X1987001)..... PA30093	Lube (5575298)..... B40145	Fuel/Water Separator (K371029) PF46081
Trans. (Fuller 4304827)..... BT223	Fuel (3607140)..... BF7695	Fuel (5365988)..... BF46129
T680 w/Cummins ISX 11.9 (11.9L) Eng. (2018)	EnduraCube Air (P621725)..... PA32000	EnduraCube Air (P621725)..... PA32000
Dual-Flow Lube (Fleetguard LF14000NN)..... BD50000	Cab Air (Fresh Air) (X1987001).... PA30093	Cab Air (Fresh Air) (X1987001).... PA30093
Fuel (Fleetguard FF5776)..... BF9885	Cab Air (Recirc.) (W2084001).... PA30107	Cab Air (Recirc.) (W2084001).... PA30107
EnduraCube Air (P621725)..... PA32000	Coolant (3680434)..... B5087	
Cab Air (X1987001)..... PA30093		
Trans. (Fuller 4304827)..... BT223		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)
T680 w/Cummins ISX 15.0 (14.9L) Eng. (2022) Lube (5575298)..... <b>B40145</b> Fuel (5575143)..... <b>BF46248</b>	T680 w/Paccar MX Eng. (Cont'd) Cab Air (X1987001)..... <b>PA30093</b> Air Dryer (TRP AC1001)..... <b>BA5374 +</b> Coolant..... <b>B5088 +</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Diesel Exhaust Fluid (5303604).. <b>PE17000</b>	T680 w/Paccar MX-11 (10.8L) Eng. (2021) Lube (2129253PE)..... <b>P40008</b> Fuel (2277129PE)..... <b>PF46106</b> EnduraCube Air (P621725)..... <b>PA32000</b> Cab Air (Fresh Air) (X1987001)..... <b>PA30093</b> Cab Air (Recirc.) (W2084001)..... <b>PA30107</b>
T680 w/Cummins ISX 15.0 (14.9L) Eng. (2023) Lube (5575298)..... <b>B40145</b> Fuel (5575143)..... <b>BF46248</b>	T680 w/Paccar MX-11 (10.8L) Eng. (2015-17) Lube (1928868)..... <b>P40008</b> Centrifugal Lube (1928869)..... <b>BC40009</b> Fuel/Water Separator (Fleetguard FS19765)..... <b>PF7930</b> Fuel (1852006)..... <b>PF46106</b> EnduraCube Air (P621725)..... <b>PA32000</b> Cab Air (X1987001)..... <b>PA30093</b> Cab Air Foam (W2084001)..... <b>PA30107</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Coolant (1843659)..... <b>B5088 +</b> Trans. (Fuller 4304827)..... <b>BT223</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	T680 w/Paccar MX-13 (12.9L) Eng. (2014-18) Lube Ele. (1643070)..... <b>P40019</b> Lube (2047411PE)..... <b>P40069</b> Centrifugal Lube (1922496)..... <b>BC40148</b> Fuel/Water Separator (Fleetguard FS19728)..... <b>PF7782</b> Fuel/Water Separator (Fleetguard FS19729)..... <b>PF7755</b> Fuel/Water Separator (K371009)..... <b>PF9929</b> Fuel/Water Separator (K371012)..... <b>PF46082</b> Fuel (1852006)..... <b>PF46106</b> EnduraCube Air (P621725)..... <b>PA32000</b> EnduraCube Air (P621730)..... <b>PA32003</b> Cab Air (X1987001)..... <b>PA30093</b> Cab Air (W2084001)..... <b>PA30107</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Coolant (1843659)..... <b>B5088 +</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Diesel Exhaust Fluid (5303604).. <b>PE17000</b>
T680 w/Cummins ISX-G Eng. Dual-Flow Lube (Fleetguard LF9080)..... <b>BD7154 +</b> Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> Fuel (3607140)..... <b>[2] BF7695</b> EnduraCube Air (P621725)..... <b>PA32000</b> EnduraCube Air (P621730)..... <b>PA32003</b> Cab Air (X1987001)..... <b>PA30093</b> Cab Air Foam (W2084001)..... <b>PA30107</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Coolant (3680434)..... <b>B5087</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	T680 w/Paccar MX-11 (10.8L) Eng. (2018) Lube (1928868PE)..... <b>P40008</b> Centrifugal Lube (1928869PE)..... <b>BC40009</b> Fuel/Water Separator (K371012)..... <b>PF46082</b> Fuel (1852006PE)..... <b>PF46106</b> EnduraCube Air (P621725)..... <b>PA32000</b> Cab Air (X1987001)..... <b>PA30093</b> Coolant (1843659PE)..... <b>B5088 +</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Trans. (Fuller 4304827)..... <b>BT223</b>	T680 w/Paccar MX-13 (12.9L) Eng. (2019) F-F Lube (2047411PE)..... <b>P40069</b> Centrifugal Lube (1922496PE)..... <b>BC40148</b> Fuel/Water Separator (K371022)..... <b>PF46237</b> Fuel/Water Separator (2133096PE)..... <b>PF46106</b> EnduraCube Air (P621725)..... <b>PA32000</b> Cab Air (X1987001)..... <b>PA30093</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Coolant (1843659PE)..... <b>B5088 +</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Diesel Exhaust Fluid (2122909PE)..... <b>PE17002 KIT</b>
T680 w/Cummins X15 (14.9L) Eng. (2018) Dual-Flow Lube (4367100)..... <b>BD50000</b> Fuel/Water Separator (K371029)..... <b>PF46081</b> Fuel (5365988)..... <b>BF46129</b> EnduraCube Air (P621725)..... <b>PA32000</b> Cab Air (X1987001)..... <b>PA30093</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Diesel Exhaust Fluid (4388378).. <b>PE17002 KIT</b>	T680 w/Paccar MX-11 (10.8L) Eng. (2019) F-F Lube (2129253PE)..... <b>P40008</b> Centrifugal Lube (1928869PE)..... <b>BC40009</b> Fuel/Water Separator (K371012)..... <b>PF46082</b> Fuel (2133096PE)..... <b>PF46106</b> EnduraCube Air (P621725)..... <b>PA32000</b> Cab Air (X1987001)..... <b>PA30093</b> Coolant (1843659PE)..... <b>B5088</b> Trans. (Fuller 4304827)..... <b>BT223</b>	T680 w/Paccar MX-13 (12.9L) Eng. (2019) F-F Lube (2047411PE)..... <b>P40069</b> Centrifugal Lube (1922496PE)..... <b>BC40148</b> Fuel/Water Separator (K371022)..... <b>PF46237</b> Fuel/Water Separator (2133096PE)..... <b>PF46106</b> EnduraCube Air (P621725)..... <b>PA32000</b> Cab Air (X1987001)..... <b>PA30093</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Coolant (1843659PE)..... <b>B5088 +</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Diesel Exhaust Fluid (2122909PE)..... <b>PE17002 KIT</b>
T680 w/Cummins X15 (14.9L) Eng. (2019) Dual-Flow Lube (4367100)..... <b>BD50000</b> Fuel/Water Separator (K371021)..... <b>PF46236</b> Fuel (5365988)..... <b>BF46129 +</b> EnduraCube Air (P621725)..... <b>PA32000</b> Cab Air (X1987001)..... <b>PA30093</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Trans. (Fuller 4304827)..... <b>BT223</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	T680 w/Paccar MX-11 (10.8L) Eng. (2020) Lube Ele. (2151728PE)..... <b>P40069</b> Centrifugal Lube (1922496PE)..... <b>BC40148</b> Fuel/Water Separator (2133096PE)..... <b>PF46106</b> Fuel (2277129PE)..... <b>PF46106</b> EnduraCube Air (Don. P621725)..... <b>PA32000</b> Cab Air (Fresh Air) (X1987001).... <b>PA30093</b> Cab Air (Recirculation) (W2084001)..... <b>PA30107</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Coolant (1843659PE)..... <b>B5088</b> Trans. (Fuller 4304827)..... <b>BT223</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	T680 w/Paccar MX-13 (12.9L) Eng. (2020) F-F Lube (2151728PE)..... <b>P40069</b> Centrifugal Lube (1922496PE)..... <b>BC40148</b> Fuel/Water Separator (K371022)..... <b>PF46237</b> Fuel (2133096PE)..... <b>PF46106</b> EnduraCube Air (Don. P621725)..... <b>PA32000</b> Cab Air (Fresh Air) (X1987001).... <b>PA30093</b> Cab Air (Recirculation) (W2084001)..... <b>PA30107</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Coolant (1843659PE)..... <b>B5088</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>
T680 w/Cummins X15 (14.9L) Eng. (2020) Dual-Flow Lube (4367100)..... <b>BD50000</b> Fuel/Water Separator (K371021)..... <b>PF46236</b> Fuel (5365988)..... <b>BF46129</b> EnduraCube Air (Don. P621725)..... <b>PA32000</b> Cab Air (Fresh Air) (X1987001).... <b>PA30093</b> Cab Air (Recirculation) (W2084001)..... <b>PA30107</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Trans. (Fuller 4304827)..... <b>BT223</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	T680 w/Paccar MX Eng. Lube Ele. (1643070)..... <b>P40019</b> Lube Spinner (1643072)..... <b>BC7326 +</b> Fuel/Water Separator (K371004)..... <b>PF9928</b> Fuel/Water Separator (Fleetguard FS19765)..... <b>PF7930</b> EnduraCube Air (P621725)..... <b>PA32000</b>	T680 w/Paccar MX-13 (12.9L) Eng. (2020) F-F Lube (2151728PE)..... <b>P40069</b> Centrifugal Lube (1922496PE)..... <b>BC40148</b> Fuel/Water Separator (K371022)..... <b>PF46237</b> Fuel (2133096PE)..... <b>PF46106</b> EnduraCube Air (Don. P621725)..... <b>PA32000</b> Cab Air (Fresh Air) (X1987001).... <b>PA30093</b> Cab Air (Recirculation) (W2084001)..... <b>PA30107</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Coolant (1843659PE)..... <b>B5088</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>KENWORTH Trucks (cont'd)</b>	<b>KENWORTH Trucks (cont'd)</b>	<b>KENWORTH Trucks (cont'd)</b>
T680 w/Paccar MX-13 (12.9L) Eng. (2020) (Cont'd) <b>Diesel Exhaust Fluid</b> (2122909PE)..... <b>PE17002 KIT</b>	T700 w/Cummins ISX 15.0 (14.9L) Eng. (Cont'd) <b>Fuel</b> (Standard) (Fleetguard FF5776)..... <b>BF9885 +</b> <b>Fuel</b> (Upgrade) (Fleetguard FF5825NN)..... <b>BF46129</b> <b>Radial Seal Air</b> (Don. P542101)... <b>RS3750</b> <b>Radial Seal XP Air</b> (Don. P542101)..... <b>RS3750XP</b> <b>Cab Air</b> (525507BSM)..... <b>PA5306</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Breather</b> (3685528)..... <b>CV15000</b> <b>Coolant</b> (Fleetguard WF2127)..... <b>B5087</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Diesel Exhaust Fluid</b> (2888182).. <b>PE17000</b>	T800 w/Cat C7 (7.2L) Eng. (To 2006) (Cont'd) <b>Channel Flow Air</b> (Don. P616056)..... <b>CA5500</b> <b>Radial Seal Air</b> (Don. P534816)... <b>[2] RS3539</b> <b>Radial Seal XP Air</b> (Don. P534816)..... <b>[2] RS3539XP</b> <b>Air Dryer</b> ..... <b>BA5374 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (White 3105264)..... <b>P528</b>
T680 w/Paccar PX-9 (8.9L) Eng. (2018) <b>Lube</b> (3401544)..... <b>B40142</b> <b>Fuel/Water Separator</b> (Fleetguard FS1003)..... <b>BF1293-SPS</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>EnduraCube Air</b> (P621725)..... <b>PA32000</b> <b>Cab Air</b> (X1987001)..... <b>PA30093</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b>	T700 w/Paccar MX (12.9L) Eng. <b>Lube Ele.</b> (1643070)..... <b>P40019</b> <b>Lube Spinner</b> (1643072)..... <b>BC7326 +</b> <b>Fuel/Water Separator</b> (K37-1005)..... <b>PF9928</b> <b>Fuel/Water Separator</b> (Fleetguard FS19765)..... <b>PF7930</b> <b>Fuel</b> (1655115)..... <b>BF9927</b> <b>Radial Seal Air</b> (Don. P542101)... <b>RS3750</b> <b>Radial Seal XP Air</b> (Don. P542101)..... <b>RS3750XP</b> <b>Cab Air</b> (525507BSM)..... <b>PA5306</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Coolant</b> (1843659)..... <b>B5088 +</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>	T800 w/Cat C7 (7.2L) Eng. (2007-on) <b>Lube</b> (1R1807)..... <b>B7700 +</b> <b>Lube</b> (1R1808)..... <b>B7299 +</b> <b>Fuel/Water Separator</b> (1752949). <b>BF1268</b> <b>Fuel Spin-on</b> (1R0751)..... <b>BF7632</b> <b>Channel Flow Air</b> (Don. P616056)..... <b>CA5500</b> <b>Radial Seal Air</b> (Don. P534816)... <b>[2] RS3539</b> <b>Radial Seal XP Air</b> (Don. P534816)..... <b>[2] RS3539XP</b> <b>Air Dryer</b> ..... <b>BA5374 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>
T680 w/Paccar PX-9 (8.9L) Eng. (2019) <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel/Water Separator</b> (Fleetguard FS1003)..... <b>BF1293-SPS</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> <b>Cab Air</b> (X1987001)..... <b>PA30093</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	T700 w/Paccar MX-13 (12.9L) Eng. <b>Lube Ele.</b> (1643070)..... <b>P40019</b> <b>Lube Spinner</b> (1643072)..... <b>BC7326 +</b> <b>Fuel/Water Separator</b> (K37-1005)..... <b>PF9928</b> <b>Fuel/Water Separator</b> (Fleetguard FS19765)..... <b>PF7930</b> <b>Fuel</b> (1655115)..... <b>BF9927</b> <b>Radial Seal Air</b> (Don. P542101)... <b>RS3750</b> <b>Radial Seal XP Air</b> (Don. P542101)..... <b>RS3750XP</b> <b>Cab Air</b> (525507BSM)..... <b>PA5306</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Coolant</b> (1843659)..... <b>B5088 +</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>	T800 w/Cat C9 Eng. <b>Lube</b> (1R1808)..... <b>B7299 +</b> <b>Fuel/Water Separator</b> (175-2949)..... <b>BF1268</b>
T680 w/Paccar PX-9 (8.9L) Eng. (2020) <b>Lube</b> (3401544)..... <b>B40142</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>EnduraCube Air</b> (P621725)..... <b>PA32000</b> <b>Cab Air</b> (X1987001)..... <b>PA30093</b> <b>Cab Air</b> (Foam) (W2084001)..... <b>PA30107</b> <b>Air Dryer</b> (Bendix 5008414PG)... <b>BA5379</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	T700 w/Paccar MX-13 (12.9L) Eng. <b>Lube Ele.</b> (1643070)..... <b>P40019</b> <b>Lube Spinner</b> (1643072)..... <b>BC7326 +</b> <b>Fuel/Water Separator</b> (K37-1005)..... <b>PF9928</b> <b>Fuel/Water Separator</b> (Fleetguard FS19765)..... <b>PF7930</b> <b>Fuel</b> (1655115)..... <b>BF9927</b> <b>Radial Seal Air</b> (Don. P542101)... <b>RS3750</b> <b>Radial Seal XP Air</b> (Don. P542101)..... <b>RS3750XP</b> <b>Cab Air</b> (525507BSM)..... <b>PA5306</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Coolant</b> (1843659)..... <b>B5088 +</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>	
T680 w/Paccar PX-9 (8.9L) Eng. (2021) <b>Lube</b> (5444774)..... <b>B40142</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>EnduraCube Air</b> (P621725)..... <b>PA32000</b> <b>Cab Air</b> (Fresh Air) (X1987001)... <b>PA30093</b> <b>Cab Air</b> (Recirc.) (W2084001)..... <b>PA30107</b>	T800 w/Cat C7 (7.2L) Eng. (To 2006) <b>Lube</b> (1R1807)..... <b>B7700 +</b> <b>Lube</b> (1R1808)..... <b>B7299 +</b> <b>Fuel/Water Separator</b> (1752949). <b>BF1268</b> <b>Fuel Spin-on</b> (1R0751)..... <b>BF7632</b>	
T680 w/Paccar PX-9 (8.9L) Eng. (2022) <b>Lube</b> (5444774)..... <b>B40142</b>		
T700 w/Cummins ISX 15.0 (14.9L) Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154 +</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (K371004) <b>PF9928</b> <b>Fuel</b> (Fleetguard FF5686)..... <b>BF9860 +</b>		

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)
T800 w/Cat C9 Eng. (Cont'd)	T800 w/Cat C11 (11.1L) Eng. (Cont'd)	T800 w/Cat C13 (12.5L) Eng. (To 1/2004) (Cont'd)
<b>Fuel/Water Separator</b> (Fleetguard FS1000)..... <b>BF1259</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Fuel</b> (1R0751)..... <b>BF7632</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Channel Flow Air</b> (P611696)..... <b>CA5500</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
<b>Radial Seal Air</b> (Don. P534816)... <b>[2] RS3539</b>	<b>Steering</b> (Nelson 87972A)..... <b>PT9386-MPG</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>Radial Seal XP Air</b> (Don. P534816)..... <b>[2] RS3539XP</b>	T800 w/Cat C12 (12.0L) Eng.	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>
<b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b>	<b>F-F Lube</b> (1R0716)..... <b>B99 +</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>F-F Lube</b> (1R1808)..... <b>B7299 +</b>	<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>B-P Lube</b> (1W8845)..... <b>B7577</b>	T800 w/Cat C13 (12.5L) Eng. (1/2004-06)
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1000)..... <b>BF1259</b>	<b>F-F Lube</b> (1R1808)..... <b>B7299 +</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (1335673)..... <b>BF1395-O</b>	<b>F-F Lube</b> (249-2347)..... <b>[2] B7402</b>
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Fuel/Water Separator</b> (w/Drain) (1335673)..... <b>BF1265</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19536)..... <b>PF7894</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29526899)..... <b>PT9416-MPG KIT</b>	<b>Fuel/Water Separator</b> (w/Sensor Port) (1335673)..... <b>BF1395-SP</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19624)..... <b>PF7748</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Fuel Ele.</b> (9M2342)..... <b>PF935</b>	<b>Fuel/Water Separator Spin-on</b> (256-8753)..... <b>BF1259</b>
<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>Fuel Spin-on</b> (1R0712)..... <b>BF614 +</b>	<b>Fuel</b> (1R0749)..... <b>BF7587 +</b>
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Fuel Spin-on</b> (1R0749)..... <b>BF7587 +</b>	<b>Air</b> (2400 Series Hsg.) (Don. P154575)..... <b>PA2715</b>
<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>Air</b> (w/Lid) (Don. P153551)..... <b>PA2705</b>	<b>Air</b> (2500 Series Hsg.) (Don. P537791)..... <b>PA2705</b>
T800 w/Cat C10 (10.3L) Eng.	<b>Air</b> (w/o Lid) (Don. P154575)..... <b>PA2715</b>	<b>Radial Seal Air</b> (Don. P534816)... <b>[2] RS3539</b>
<b>F-F Lube</b> (1R0716)..... <b>B99 +</b>	<b>Coolant</b> (w/4 Units BTA +) (Fleetguard WF2071)..... <b>BW5071</b>	<b>Radial Seal XP Air</b> (Don. P534816)..... <b>[2] RS3539XP</b>
<b>F-F Lube</b> (1R1808)..... <b>B7299 +</b>	<b>Coolant</b> (w/4 Units BTE) (9N3368)..... <b>BW5137</b>	<b>Channel Flow Air</b> (P611696)..... <b>CA5500</b>
<b>B-P Lube</b> (1W8845)..... <b>B7577</b>	<b>Coolant</b> (w/8 Units BTE) (9N6123)..... <b>BW5139</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>
<b>Fuel/Water Separator</b> (Fleetguard FS1000)..... <b>BF1259</b>	<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	<b>Coolant</b> (Fleetguard WF2122)..... <b>B5088 +</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (1335673)..... <b>BF1395-O</b>	T800 w/Cat C13 (12.5L) Eng. (To 1/2004)	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Fuel/Water Separator</b> (w/Drain) (1335673)..... <b>BF1265</b>	<b>F-F Lube</b> (1R0716)..... <b>B99 +</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Fuel/Water Separator</b> (w/Sensor Port) (1335673)..... <b>BF1395-SP</b>	<b>F-F Lube</b> (249-2347)..... <b>[2] B7402</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Fuel Ele.</b> (9M2342)..... <b>PF935</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19536)..... <b>PF7894</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Fuel Spin-on</b> (1R0712)..... <b>BF614 +</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19624)..... <b>PF7748</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Fuel Spin-on</b> (1R0749)..... <b>BF7587 +</b>	<b>Fuel/Water Separator Spin-on</b> (256-8753)..... <b>BF1259</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
<b>Air</b> (w/Lid) (Don. P153551)..... <b>PA2705</b>	<b>Fuel</b> (1R0749)..... <b>BF7587 +</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>Air</b> (w/o Lid) (Don. P154575)..... <b>PA2715</b>	<b>Air</b> (2400 Series Hsg.) (Don. P154575)..... <b>PA2715</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>
<b>Coolant</b> (w/4 Units BTA +) (Fleetguard WF2071)..... <b>BW5071</b>	<b>Air</b> (2500 Series Hsg.) (Don. P537791)..... <b>PA2705</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
<b>Coolant</b> (w/4 Units BTE) (9N3368)..... <b>BW5137</b>	<b>Radial Seal Air</b> (Don. P534816)... <b>[2] RS3539</b>	<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>
<b>Coolant</b> (w/8 Units BTE) (9N6123)..... <b>BW5139</b>	<b>Radial Seal XP Air</b> (Don. P534816)..... <b>[2] RS3539XP</b>	T800 w/Cat C13 (12.5L) Eng. (2007-on)
<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	<b>Channel Flow Air</b> (P611696)..... <b>CA5500</b>	<b>F-F Lube</b> (1R1808)..... <b>B7299 +</b>
T800 w/Cat C11 (11.1L) Eng.	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>F-F Lube</b> (249-2347)..... <b>[2] B7402</b>
<b>Lube</b> (1R1808)..... <b>B7299 +</b>	<b>Coolant</b> (Fleetguard WF2122)..... <b>B5088 +</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19536)..... <b>PF7894</b>
<b>Fuel/Water Separator</b> (Fleetguard FS1000)..... <b>BF1259</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	
<b>Fuel</b> (1R0749)..... <b>BF7587 +</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	
<b>Air</b> (Don. P153551)..... <b>PA2705</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	
<b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b>		

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)
T800 w/Cat C13 (12.5L) Eng. (2007-on) (Cont'd)	T800 w/Cat C15 (14.6L) Eng. (To 1/2004) (Cont'd)	T800 w/Cat C15 (14.6L) Eng. (2007-on) (Cont'd)
Fuel/Water Separator Ele. (Fleetguard FS19624)..... PF7748	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017	Coolant (w/4 Units BTE) (9N3368)..... BW5137
Fuel/Water Separator Spin-on (256-8753)..... BF1259	Trans. Spin-on (Allison 29539579)..... BT8460	Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT
Fuel (1R0749)..... BF7587 +	Trans. Spin-on (Fuller 4304827).. BT223	Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT
Radial Seal Air (Don. P534816).. [2] RS3539	Opt. Trans. Spin-on (Fuller 17237)..... B2 +	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004
Radial Seal XP Air (Don. P534816)..... [2] RS3539XP	Steering (Nelson 83804E)..... P528	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016
Channel Flow Air (P611696)..... CA5500	T800 w/Cat C15 (14.6L) Eng. (1/2004-06)	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003
Air Dryer (AD-IS System) (Bendix 5008414)..... BA5374 +	F-F Lube (1R1808)..... B7299 +	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017
Coolant (Fleetguard WF2122)..... B5088 +	Fuel/Water Separator Ele. (Don. P550463)..... PF7680	Trans. Spin-on (Allison 29539579)..... BT8460
Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	Fuel/Water Separator Spin-on (256-8753)..... BF1259	Trans. Spin-on (Fuller 4304827).. BT223
Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Fuel (1R0749)..... BF7587 +	Opt. Trans. Spin-on (Fuller 17237)..... B2 +
Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004	Radial Seal Air (Don. P534816).. [2] RS3539	Steering (Nelson 87904M)..... PT9354-MPG
Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016	Radial Seal XP Air (Don. P534816)..... [2] RS3539XP	T800 w/Cat C16 (15.8L) Eng. (To 1/2004)
Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003	Channel Flow Air (P611696)..... CA5500	Lube (1R0716)..... B99 +
Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017	Air Dryer (Bendix 5008414)..... BA5374 +	Fuel Ele. (9M2342)..... [2] PF935
Trans. Spin-on (Allison 29539579)..... BT8460	Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071	Fuel Spin-on (Standard Vers.) (4N5823)..... BF614 +
Trans. Spin-on (Fuller 4304827).. BT223	Coolant (w/4 Units BTE) (9N3368)..... BW5137	Fuel Spin-on (High Efficiency Vers.) (1R0749)..... BF7587 +
Opt. Trans. Spin-on (Fuller 17237)..... B2 +	Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	Air Dryer..... BA5374 +
Steering (Nelson 87904M)..... PT9354-MPG	Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT
T800 w/Cat C15 (14.6L) Eng. (To 1/2004)	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004	Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT
F-F Lube (1R0716)..... B99 +	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016	Trans. Spin-on (Fuller 4304827).. BT223
Fuel/Water Separator Ele. (Don. P550463)..... PF7680	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003	Opt. Trans. Spin-on (Fuller 17237)..... B2 +
Fuel/Water Separator Spin-on (256-8753)..... BF1259	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017	T800 w/Cat C16 (15.8L) Eng. (1/2004-on)
Fuel (1R0749)..... BF7587 +	Trans. Spin-on (Allison 29539579)..... BT8460	Lube (1R1808)..... B7299 +
Radial Seal Air (Don. P534816).. [2] RS3539	Trans. Spin-on (Fuller 4304827).. BT223	Fuel Ele. (9M2342)..... [2] PF935
Radial Seal XP Air (Don. P534816)..... [2] RS3539XP	Opt. Trans. Spin-on (Fuller 17237)..... B2 +	Fuel Spin-on (Standard Vers.) (4N5823)..... BF614 +
Channel Flow Air (P611696)..... CA5500	Steering (Nelson 83804E)..... P528	Fuel Spin-on (High Efficiency Vers.) (1R0749)..... BF7587 +
Air Dryer (Bendix 5008414)..... BA5374 +	T800 w/Cat C15 (14.6L) Eng. (2007-on)	Air Dryer..... BA5374 +
Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071	F-F Lube (1R1808)..... B7299 +	Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT
Coolant (w/4 Units BTE) (9N3368)..... BW5137	Fuel/Water Separator Ele. (Don. P550463)..... PF7680	Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT
Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	Fuel/Water Separator Spin-on (256-8753)..... BF1259	Trans. Spin-on (Fuller 4304827).. BT223
Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Fuel (1R0749)..... BF7587 +	Opt. Trans. Spin-on (Fuller 17237)..... B2 +
Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004	Radial Seal Air (Don. P534816).. [2] RS3539	T800 Tiffin w/Cat C12 Eng.
Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016	Radial Seal XP Air (Don. P534816)..... [2] RS3539XP	F-F Lube..... B99 +
Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003	Channel Flow Air (P611696)..... CA5500	B-P Lube..... B7577
	Air Dryer (Bendix 5008414)..... BA5374 +	Fuel/Water Separator..... BF1259
	Breather (296-8325)..... CV15008	Fuel Spin-on..... BF614 +
	Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071	Air (Don. P153551)..... PA2705
		Air (Don. P154575)..... PA2715

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)
T800 w/Cat 3126 (7.2L) Eng. Lube (Standard Vers.) (1R0739).. <b>B76 +</b> Lube (Severe Service) (1R0739).. <b>B76-SS +</b> Fuel Ele. (9M2342)..... <b>[2] PF935</b> Fuel Spin-on (1R0751)..... <b>BF7632</b> Air Dryer..... <b>BA5374 +</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	T800 w/Cummins 6BT5.9 (5.9L) Eng. (Cont'd) Fuel (3903640)..... <b>BF788</b> Air Dryer..... <b>BA5374 +</b> T800 w/Cummins 6CT8.3 (8.3L) Eng. F-F Lube (3313281)..... <b>B205 +</b> Dual-Flow Lube (3318853)..... <b>BD103 +</b> Fuel/Water Separator (3925274). <b>BF1280 +</b> Fuel (3903640)..... <b>BF788</b> Air Dryer..... <b>BA5374 +</b> T800 w/Cummins ISB (5.9L) Eng. Lube (Fleetguard LF3970)..... <b>B7177</b> Lube (4897898)..... <b>BT7237</b> Fuel (Fleetguard FF5632)..... <b>BF7940</b> Air Dryer..... <b>BA5374 +</b> T800 w/Cummins ISC 8.3 (8.3L) Eng. Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309 +</b> Dual-Flow Lube (Fleetguard LF9548)..... <b>BD324 +</b> Fuel (Fleetguard FF5488)..... <b>BF7815</b> Fuel (Fleetguard FF5636)..... <b>BF7924</b> Air Dryer..... <b>BA5374 +</b> Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> Coolant (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b> Coolant (w/23 Units BTA+) (Fleetguard WF2076)..... <b>BW5076</b> Coolant (w/Controlled Release) (Fleetguard WF2121)..... <b>BW5250</b>	T800 w/Cummins ISL Eng. (To 2006) (Cont'd) Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Steering..... <b>P528</b> T800 w/Cummins ISL Eng. (2007-09) Dual-Flow Lube (3401544)..... <b>BD7309 +</b> Lube (Upgrade) (3401544)..... <b>B40142 +</b> Fuel/Water Separator (Fleetguard FS1003)..... <b>BF1293-SPS</b> Fuel/Water Separator (Fleetguard FS1065)..... <b>BF1378-SPS</b> Fuel (Fleetguard FF5636)..... <b>BF7924</b> Radial Seal Air (Don. P534816).... <b>[2] RS3539</b> Radial Seal XP Air (Don. P534816)..... <b>[2] RS3539XP</b> Channel Flow Air (P611696)..... <b>CA5500</b> Channel Flow Air (P611698)..... <b>CA30102</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Coolant (Fleetguard WF2071)..... <b>BW5071</b> Trans. Ele. (2 In. Kit) (Allison 29545776)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29545779)..... <b>PT9415-MPG KIT</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>
T800 w/Cat 3176 (10.3L) Eng. Lube (1R0716)..... <b>B99 +</b> Fuel (1R-0749)..... <b>BF7587 +</b> Air (Don. P537791)..... <b>PA2705</b> Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Steering (Nelson 83213H)..... <b>PT903</b>	T800 w/Cummins ISL Eng. (To 2006) Dual-Flow Lube (3401544)..... <b>BD7309 +</b> Lube (Upgrade) (3401544)..... <b>B40142 +</b> Fuel/Water Separator (Fleetguard FS1003)..... <b>BF1293-SPS</b> Fuel/Water Separator (Fleetguard FS1065)..... <b>BF1378-SPS</b> Fuel (Fleetguard FF5636)..... <b>BF7924</b> Radial Seal Air (Don. P534816).... <b>[2] RS3539</b> Radial Seal XP Air (Don. P534816)..... <b>[2] RS3539XP</b> Channel Flow Air (P611696)..... <b>CA5500</b> Channel Flow Air (P611698)..... <b>CA30102</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Coolant (Fleetguard WF2071)..... <b>BW5071</b> Trans. Ele. (2 In. Kit) (Allison 29545776)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29545779)..... <b>PT9415-MPG KIT</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>	T800 w/Cummins ISL Eng. (2010-on) Dual-Flow Lube (3401544)..... <b>BD7309 +</b> Lube (Upgrade) (3401544)..... <b>B40142 +</b> Fuel/Water Separator (Fleetguard FS1003)..... <b>BF1293-SPS</b> Fuel/Water Separator (Fleetguard FS1065)..... <b>BF1378-SPS</b> Fuel (Fleetguard FF5636)..... <b>BF7924</b> Radial Seal Air (Don. P534816).... <b>[2] RS3539</b> Radial Seal XP Air (Don. P534816)..... <b>[2] RS3539XP</b> Channel Flow Air (P611696)..... <b>CA5500</b> Channel Flow Air (P611698)..... <b>CA30102</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Coolant (Fleetguard WF2071)..... <b>BW5071</b> Trans. Ele. (2 In. Kit) (Allison 29545776)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29545779)..... <b>PT9415-MPG KIT</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
T800 w/Cat 3306 (10.5L) Eng. Lube (Standard Vers.) (1R0739).. <b>B76 +</b> Lube (Severe Service) (1R0739).. <b>B76-SS +</b> Box-Style Fuel/Water Separator (8N9803)..... <b>BF912</b> P. Fuel Ele. (9M2342)..... <b>PF935</b> P. Fuel Spin-on (1R0751)..... <b>BF7632</b> S. Fuel Spin-on (1R0750)..... <b>BF7633 +</b> Fuel Spin-on (1R0740)..... <b>BF970 +</b> Air (Don. P153551)..... <b>PA2705</b> Air (Don. P154575)..... <b>PA2715</b> Air Dryer..... <b>BA5374 +</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	T800 w/Cat 3406 (14.6L) Eng. Lube (1R0716)..... <b>B99 +</b> Fuel/Water Separator (Fleetguard FS1000)..... <b>BF1259</b> Fuel/Water Separator (Fleetguard FS1212)..... <b>BF1212 +</b> Fuel Spin-on (1R0712)..... <b>BF614 +</b> Fuel Spin-on (1R0749)..... <b>BF7587 +</b> Air (Don. P153551)..... <b>PA2705</b> Air (Don. P154575)..... <b>PA2715</b> Radial Seal Air (Don. P534816).... <b>[2] RS3539</b> Radial Seal XP Air (Don. P534816)..... <b>[2] RS3539XP</b> Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b> Air Dryer (AD-IP System) (Bendix 65624)..... <b>BA5373</b> Coolant (w/4 Units BTE)..... <b>BW5137</b> Coolant (w/16 Units BTE) (K251-341)..... <b>BW5140</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Steering (Fleetguard LF637)..... <b>P528</b>	T800 w/Cummins ISL Eng. (2010-on) Dual-Flow Lube (3401544)..... <b>BD7309 +</b> Lube (Upgrade) (3401544)..... <b>B40142 +</b> Fuel/Water Separator (Fleetguard FS1003)..... <b>BF1293-SPS</b> Fuel/Water Separator (Fleetguard FS1065)..... <b>BF1378-SPS</b> Fuel (Fleetguard FF5636)..... <b>BF7924</b> Radial Seal Air (Don. P534816).... <b>[2] RS3539</b> Radial Seal XP Air (Don. P534816)..... <b>[2] RS3539XP</b> Channel Flow Air (P611696)..... <b>CA5500</b> Channel Flow Air (P611698)..... <b>CA30102</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Coolant (Fleetguard WF2071)..... <b>BW5071</b> Trans. Ele. (2 In. Kit) (Allison 29545776)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29545779)..... <b>PT9415-MPG KIT</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
T800 w/Cat 3406 (14.6L) Eng. Lube (1R0716)..... <b>B99 +</b> Fuel/Water Separator (Fleetguard FS1000)..... <b>BF1259</b> Fuel/Water Separator (Fleetguard FS1212)..... <b>BF1212 +</b> Fuel Spin-on (1R0712)..... <b>BF614 +</b> Fuel Spin-on (1R0749)..... <b>BF7587 +</b> Air (Don. P153551)..... <b>PA2705</b> Air (Don. P154575)..... <b>PA2715</b> Radial Seal Air (Don. P534816).... <b>[2] RS3539</b> Radial Seal XP Air (Don. P534816)..... <b>[2] RS3539XP</b> Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b> Air Dryer (AD-IP System) (Bendix 65624)..... <b>BA5373</b> Coolant (w/4 Units BTE)..... <b>BW5137</b> Coolant (w/16 Units BTE) (K251-341)..... <b>BW5140</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Steering (Fleetguard LF637)..... <b>P528</b>	T800 w/Cummins 6BT5.9 (5.9L) Eng. Lube (3914395)..... <b>BT339 +</b> Lube (Chrysler 5083285AA)..... <b>BT7349</b> Fuel/Water Separator (3925274). <b>BF1280 +</b>	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)
T800 w/Cummins ISL Eng. (2010-on) (Cont'd) <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	T800 w/Cummins ISM 10.8 (10.8L) Eng. (To 2006) (Cont'd) <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 83804E)..... <b>P528</b>	T800 w/Cummins ISM 10.8 (10.8L) Eng. (2007-15) (Cont'd) <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> T800 w/Cummins ISM 10.8 (10.8L) Eng. (2020) <b>Channel Flow EXO Air</b> (P611696)..... <b>CA5500</b> <b>Air Dryer</b> (Bendix 5008414PG).... <b>BA5379 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
T800 w/Cummins ISL-G Eng. <b>Dual-Flow Lube Spin-on</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Coalescer Fuel</b> (Fleetguard NG5900)..... <b>BF7695</b> <b>Channel Flow Air</b> (P611696)..... <b>CA5500</b> <b>Air Dryer Spin-on</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29545776)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29545779)..... <b>PT9415-MPG KIT</b> <b>Steering Ele.</b> (Nelson 87904M).... <b>PT9354-MPG</b>	T800 w/Cummins ISM 10.8 (10.8L) Eng. (2007-15) <b>Dual-Flow Lube</b> (Std. Version) (Fleetguard LF9001)..... <b>BD7154 +</b> <b>Dual-Flow Lube</b> (High Efficiency) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (Racor S3226T)..... <b>BF1347</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Racor S3226T)..... <b>BF1347-O</b> <b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (Racor S3226T).. <b>BF1373-SP</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19727)..... <b>PF7895</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1000)..... <b>BF1259</b> <b>Conical Air</b> (Don. P154575)..... <b>PA2715</b> <b>Channel Flow Air</b> (P611698)..... <b>CA30102</b> <b>Channel Flow Air</b> (P611696)..... <b>CA5500</b> <b>Radial Seal Air</b> (Don. P534816).. <b>[2] RS3539</b> <b>Radial Seal XP Air</b> (Don. P534816)..... <b>[2] RS3539XP</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Breather</b> (3683918)..... <b>CV15000</b> <b>Coolant</b> (Fleetguard WF2071).... <b>BW5071</b> <b>Coolant</b> (w/o Chemicals) (4920476)..... <b>B5090</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	T800 w/Cummins ISX 11.9 (11.9L) Eng. (To 2006) <b>11 13/16 In. Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154 +</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>14 7/32 In. Dual-Flow Lube</b> (Fleetguard LF9000)..... <b>BD7153 +</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FF5369)..... <b>PF7744</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19729)..... <b>PF7755</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19765)..... <b>PF7930</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1007)..... <b>BF1274-SP</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1040)..... <b>BF1277-SPS</b> <b>Fuel/Water Separator</b> (K371004) <b>PF9928</b> <b>Fuel Spin-on</b> (Fleetguard FF2200)..... <b>BF7766</b> <b>Fuel Spin-on</b> (Pre-Filter) (Fleetguard FF2203)..... <b>BF7760</b> <b>Fuel</b> (Standard) (Fleetguard FF5776)..... <b>BF9885 +</b> <b>Fuel</b> (Upgrade) (Fleetguard FF5825NN)..... <b>BF46129</b> <b>Axial Seal Air</b> ..... <b>PA2705</b> <b>Channel Flow Air</b> (P611696)..... <b>CA5500</b> <b>22 29/32 In. Std. Radial Seal Air</b> (P614986)..... <b>[2] RS5288</b> <b>22 29/32 In. Radial Seal XP Air</b> (Paccar P614986)..... <b>[2] RS5288XP</b> <b>23 23/32 In. Radial Seal Air</b> (Don. P534816)..... <b>[2] RS3539</b> <b>23 23/32 In. Radial Seal XP Air</b> (Don. EAF5100)..... <b>[2] RS3539XP</b>
T800 w/Cummins ISM 10.8 (10.8L) Eng. (To 2006) <b>Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154 +</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (Racor S3226T)..... <b>BF1347</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Racor S3226T)..... <b>BF1347-O</b> <b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (Racor S3226T).. <b>BF1373-SP</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19727)..... <b>PF7895</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1000)..... <b>BF1259</b> <b>Air</b> (2400 Series Hsg.) (Don. P154575)..... <b>PA2715</b> <b>Air</b> (2500 Series Hsg.) (Don. P537791)..... <b>PA2705</b> <b>Channel Flow Air</b> (P611698)..... <b>CA30102</b> <b>Channel Flow Air</b> (P611696)..... <b>CA5500</b> <b>Radial Seal Air</b> (Don. P534816).. <b>[2] RS3539</b> <b>Radial Seal XP Air</b> (Don. P534816)..... <b>[2] RS3539XP</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Coolant</b> (Fleetguard WF2071).... <b>BW5071</b> <b>Coolant</b> (w/o Chemicals) (4920476)..... <b>B5090</b>		

\* See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)
T800 w/Cummins ISX 11.9 (11.9L) Eng. (To 2006) (Cont'd)	T800 w/Cummins ISX 11.9 (11.9L) Eng. (2007-09) (Cont'd)	T800 w/Cummins ISX 11.9 (11.9L) Eng. (2011-18) (Cont'd)
<b>Air Dryer</b> (AD-IS System) (Bendix 5008414).....	<b>22 29/32 In. Std. Radial Seal Air</b> (P614986).....	<b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1040).....
<b>BA5374 +</b>	<b>[2] RS5288</b>	<b>BF1277-SPS</b>
<b>Breather</b> (4312013).....	<b>22 29/32 In. Radial Seal XP Air</b> (Paccar P614986).....	<b>Fuel Spin-on</b> (Fleetguard FF5686).....
<b>CV15000</b>	<b>[2] RS5288XP</b>	<b>BF9860 +</b>
<b>Coolant</b> (w/o Chemical) (Fleetguard WF2127).....	<b>23 23/32 In. Radial Seal Air</b> (Don. P534816).....	<b>Fuel Spin-on</b> (Standard) (Fleetguard FF5776).....
<b>B5087</b>	<b>[2] RS3539</b>	<b>BF9885 +</b>
<b>Coolant</b> (w/11 1/2 Units BTA+) (Fleetguard WF2126).....	<b>23 23/32 In. Radial Seal XP Air</b> (Don. EAF5100).....	<b>Fuel Spin-on</b> (Upgrade) (Fleetguard FF5825NN).....
<b>BW5086</b>	<b>[2] RS3539XP</b>	<b>BF46129</b>
<b>Coolant</b> (w/4 Units BTE).....	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414).....	<b>Axial Seal Air</b> .....
<b>BW5137</b>	<b>BA5374 +</b>	<b>PA2705</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493).....	<b>Breather</b> (4312013).....	<b>Channel Flow Air</b> (P611696).....
<b>PT9416-MPG KIT</b>	<b>CV15000</b>	<b>CA5500</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494).....	<b>Coolant</b> (w/o Chemical) (Fleetguard WF2127).....	<b>22 29/32 In. Std. Radial Seal Air</b> (P614986).....
<b>PT9415-MPG KIT</b>	<b>B5087</b>	<b>[2] RS5288</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965).....	<b>Coolant</b> (w/11 1/2 Units BTA+) (Fleetguard WF2126).....	<b>22 29/32 In. Radial Seal XP Air</b> (Paccar P614986).....
<b>20004</b>	<b>BW5086</b>	<b>[2] RS5288XP</b>
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965).....	<b>Coolant</b> (w/4 Units BTE).....	<b>23 23/32 In. Radial Seal Air</b> (Don. P534816).....
<b>20016</b>	<b>BW5137</b>	<b>[2] RS3539</b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966).....	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493).....	<b>23 23/32 In. Radial Seal XP Air</b> (Don. EAF5100).....
<b>20003</b>	<b>PT9416-MPG KIT</b>	<b>[2] RS3539XP</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966).....	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494).....	<b>Cab Air</b> (X1987001).....
<b>20017</b>	<b>PT9415-MPG KIT</b>	<b>PA30093</b>
<b>Trans. Spin-on</b> (Allison 29539579).....	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965).....	<b>Cab Air</b> (W2084001).....
<b>BT8460</b>	<b>20004</b>	<b>PA30107</b>
<b>Trans. Spin-on</b> (Fuller 4304827)..	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965).....	<b>Cab Air</b> (TRP CFR19501).....
<b>BT223</b>	<b>20016</b>	<b>PA30287</b>
<b>Opt. Trans. Spin-on</b> (Fuller 17237).....	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966).....	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414).....
<b>B2 +</b>	<b>20003</b>	<b>BA5374 +</b>
<b>Steering</b> (Nelson 83804E).....	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966).....	<b>CV15000</b>
<b>P528</b>	<b>20003</b>	<b>Coolant</b> (w/o Chemical) (Fleetguard WF2127).....
T800 w/Cummins ISX 11.9 (11.9L) Eng. (2007-09)	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966).....	<b>B5087</b>
<b>11 13/16 In. Dual-Flow Lube</b> (Fleetguard LF9001).....	<b>20017</b>	<b>Coolant</b> (w/11 1/2 Units BTA+) (Fleetguard WF2126).....
<b>BD7154 +</b>	<b>Trans. Spin-on</b> (Allison 29539579).....	<b>BW5086</b>
<b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN).....	<b>Trans. Spin-on</b> (Fuller 4304827)..	<b>BW5137</b>
<b>BD50000</b>	<b>BT223</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493).....
<b>14 7/32 In. Dual-Flow Lube</b> (Fleetguard LF9000).....	<b>Opt. Trans. Spin-on</b> (Fuller 17237).....	<b>PT9416-MPG KIT</b>
<b>BD7153 +</b>	<b>B2 +</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494).....
<b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W).....	<b>Steering</b> (Nelson 87904M).....	<b>PT9415-MPG KIT</b>
<b>PF7680</b>	<b>PT9354-MPG</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965).....
<b>Fuel/Water Separator Ele.</b> (Fleetguard FF5369).....	T800 w/Cummins ISX 11.9 (11.9L) Eng. (2011-18)	<b>20004</b>
<b>PF7744</b>	<b>11 13/16 In. Dual-Flow Lube</b> (Fleetguard LF9001).....	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965).....
<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19729).....	<b>BD7154 +</b>	<b>20016</b>
<b>PF7755</b>	<b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN).....	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966).....
<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19765).....	<b>BD50000</b>	<b>20003</b>
<b>PF7930</b>	<b>14 7/32 In. Dual-Flow Lube</b> (Fleetguard LF9000).....	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966).....
<b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1007).....	<b>BD7153 +</b>	<b>20017</b>
<b>BF1274-SP</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W).....	<b>Trans. Spin-on</b> (Allison 29539579).....
<b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1040).....	<b>PF7680</b>	<b>BT8460</b>
<b>BF1277-SPS</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FF5369).....	<b>BT223</b>
<b>Fuel/Water Separator</b> (K371004) <b>PF9928</b>	<b>PF7744</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237).....
<b>Fuel Spin-on</b> (Fleetguard FF2200).....	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19729).....	<b>B2 +</b>
<b>BF7766</b>	<b>PF7755</b>	<b>Steering</b> (Nelson 87904M).....
<b>Fuel Spin-on</b> (Pre-Filter) (Fleetguard FF2203).....	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19764).....	<b>PT9354-MPG</b>
<b>BF7760</b>	<b>PF9814</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394).....
<b>Fuel</b> (Standard) (Fleetguard FF5776).....	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19765).....	<b>B233</b>
<b>BF9885 +</b>	<b>PF7930</b>	<b>Diesel Exhaust Fluid</b> (5303604)..
<b>Fuel</b> (Upgrade) (Fleetguard FF5825NN).....	<b>Fuel/Water Separator Ele.</b> (K371004).....	<b>PE17000</b>
<b>BF46129</b>	<b>PF9928</b>	T800 w/Cummins ISX 11.9 (11.9L) Eng. (2019)
<b>Axial Seal Air</b> .....	<b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1007).....	<b>Dual-Flow Lube</b> (4367100).....
<b>PA2705</b>	<b>BF1274-SP</b>	<b>BD50000</b>
<b>Channel Flow Air</b> (P611696).....		<b>Fuel/Water Separator</b> (Fleetguard FS19764).....
<b>CA5500</b>		<b>PF9814</b>
		<b>Fuel</b> (2893612).....
		<b>BF9885 +</b>
		<b>EnduraCube Air</b> (P621725).....
		<b>[2] PA32000</b>
		<b>Cab Air</b> (HVAC) (F371018).....
		<b>PA30269</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)
T800 w/Cummins ISX 11.9 (11.9L) Eng. (2019) (Cont'd)	T800 w/Cummins ISX 11.9G (11.9L) Eng. (2014-16) (Cont'd)	T800 w/Cummins ISX 15.0 (14.9L) Eng. (To 2006) (Cont'd)
<b>Cab Air</b> (Recirculation) (W2084001)..... <b>PA30107</b>	<b>Trans.</b> (Fuller 4304827)..... <b>BT223</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b>	<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	T800 w/Cummins ISX 15.0 (14.9L) Eng. (To 2006)	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>Trans. Spin-on</b> (Fuller 4304827)..... <b>BT223</b>	<b>11 13/16 In. Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154 +</b>	<b>Trans. Spin-on</b> (Fuller 4304827)..... <b>BT223</b>
<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	<b>14 7/32 In. Dual-Flow Lube</b> (Fleetguard LF9000)..... <b>BD7153 +</b>	<b>Steering</b> (Nelson 83804E)..... <b>P528</b>
<b>Diesel Exhaust Fluid</b> (Fleetguard UF101)..... <b>PE17000</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b>	T800 w/Cummins ISX 15.0 (14.9L) Eng. (2007-09)
T800 w/Cummins ISX 11.9 (11.9L) Eng. (2020)	<b>Fuel/Water Separator Ele.</b> (Fleetguard FF5369)..... <b>PF7744</b>	<b>11 13/16 In. Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154 +</b>
<b>Lube</b> (4367100)..... <b>BD50000</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19729)..... <b>PF7755</b>	<b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>
<b>Fuel/Water Separator</b> (K371029)..... <b>PF46081</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19765)..... <b>PF7930</b>	<b>14 7/32 In. Dual-Flow Lube</b> (Fleetguard LF9000)..... <b>BD7153 +</b>
<b>Fuel</b> (2893612)..... <b>BF9885</b>	<b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1007)..... <b>BF1274-SP</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b>
<b>Channel Flow Air</b> (P611696)..... <b>CA5500</b>	<b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1040)..... <b>BF1277-SPS</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FF5369)..... <b>PF7744</b>
<b>Air Dryer</b> (Bendix 5008414PG)..... <b>BA5379</b>	<b>Fuel/Water Separator</b> (K371004)..... <b>PF9928</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19729)..... <b>PF7755</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Fuel Spin-on</b> (Fleetguard FF2200)..... <b>BF7766</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19765)..... <b>PF7930</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Fuel Spin-on</b> (Pre-Filter) (Fleetguard FF2203)..... <b>BF7760</b>	<b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1007)..... <b>BF1274-SP</b>
<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>Fuel</b> (Standard) (Fleetguard FF5776)..... <b>BF9885 +</b>	<b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1040)..... <b>BF1277-SPS</b>
<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	<b>Fuel</b> (Upgrade) (Fleetguard FF5825NN)..... <b>BF46129</b>	<b>Fuel/Water Separator</b> (K371004)..... <b>PF9928</b>
T800 w/Cummins ISX 11.9G (11.9L) Eng. (2014-16)	<b>Axial Seal Air</b> ..... <b>PA2705</b>	<b>Fuel Spin-on</b> (Fleetguard FF2200)..... <b>BF7766</b>
<b>Dual-Flow Lube</b> (2882674)..... <b>BD7154 +</b>	<b>Channel Flow Air</b> (P611696)..... <b>CA5500</b>	<b>Fuel Spin-on</b> (Pre-Filter) (Fleetguard FF2203)..... <b>BF7760</b>
<b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>	<b>22 29/32 In. Std. Radial Seal Air</b> (P614986)..... <b>[2] RS5288</b>	<b>Fuel</b> (Standard) (Fleetguard FF5776)..... <b>BF9885 +</b>
<b>Fuel/Water Separator</b> (3606712)..... <b>BF7695</b>	<b>22 29/32 In. Radial Seal XP Air</b> (Paccar P614986)..... <b>[2] RS5288XP</b>	<b>Fuel</b> (Upgrade) (Fleetguard FF5825NN)..... <b>BF46129</b>
<b>Channel Flow Air</b> (Don. P616056)..... <b>CA5500</b>	<b>23 23/32 In. Radial Seal Air</b> (Don. P534816)..... <b>[2] RS3539</b>	<b>Axial Seal Air</b> ..... <b>PA2705</b>
<b>Radial Seal Air</b> (Don. P534816)..... <b>[2] RS3539</b>	<b>23 23/32 In. Radial Seal XP Air</b> (Don. EAF5100)..... <b>[2] RS3539XP</b>	<b>Channel Flow Air</b> (P611696)..... <b>CA5500</b>
<b>Radial Seal XP Air</b> (Don. P534816)..... <b>[2] RS3539XP</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>22 29/32 In. Std. Radial Seal Air</b> (P614986)..... <b>[2] RS5288</b>
<b>Cab Air</b> (TRP CFR19501)..... <b>PA30287</b>	<b>Breather</b> (4312013)..... <b>CV15000</b>	<b>22 29/32 In. Radial Seal XP Air</b> (Paccar P614986)..... <b>[2] RS5288XP</b>
<b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b>	<b>Coolant</b> (w/o Chemical) (Fleetguard WF2127)..... <b>B5087</b>	<b>23 23/32 In. Radial Seal Air</b> (Don. P534816)..... <b>[2] RS3539</b>
<b>Coolant</b> (w/o Chemical) (3680434)..... <b>B5087</b>	<b>Coolant</b> (w/11 1/2 Units BTA+) (Fleetguard WF2126)..... <b>BW5086</b>	<b>23 23/32 In. Radial Seal XP Air</b> (Don. EAF5100)..... <b>[2] RS3539XP</b>
<b>Coolant</b> (w/11 1/2 Units BTA+) (4907485)..... <b>BW5086</b>	<b>Coolant</b> (w/4 Units BTE)..... <b>BW5137</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Breather</b> (4312013)..... <b>CV15000</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Coolant</b> (w/o Chemical) (Fleetguard WF2127)..... <b>B5087</b>
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>		
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>		
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>		
<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)
T800 w/Cummins ISX 15.0 (14.9L) Eng. (2007-09) (Cont'd)	T800 w/Cummins ISX 15.0 (14.9L) Eng. (2010-18) (Cont'd)	T800 w/Cummins ISX 15.0 (14.9L) Eng. (2020) (Cont'd)
Coolant (w/11 1/2 Units BTA+) (Fleetguard WF2126)..... <b>BW5086</b>	<b>23 23/32 In. Radial Seal XP Air</b> (Don. EAF5100)..... <b>[2] RS3539XP</b>	Fuel (5365988)..... <b>BF46129</b>
Coolant (w/4 Units BTE)..... <b>BW5137</b>	Cab Air (X1987001)..... <b>PA30093</b>	Channel Flow Air (P611696)..... <b>CA5500</b>
Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	Cab Air (W2084001)..... <b>PA30107</b>	Air Dryer (Bendix 5008414PG).... <b>BA5379</b>
Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Cab Air (TRP CFR19501)..... <b>PA30287</b>	Trans. Ele. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>
Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	Air Dryer (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>
Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	Breather (4312013)..... <b>CV15000</b>	Trans. Spin-on (Fuller 4304827).. <b>BT223</b>
Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	Coolant (w/o Chemical) (Fleetguard WF2127)..... <b>B5087</b>	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>
Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	Coolant (w/11 1/2 Units BTA+) (Fleetguard WF2126)..... <b>BW5086</b>	Steering (Nelson 87904M)..... <b>PT9354-MPG</b>
Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>	Coolant (w/4 Units BTE)..... <b>BW5137</b>	Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>
Trans. Spin-on (Fuller 4304827).. <b>BT223</b>	Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	T800 w/Cummins ISX 15.0 (14.9L) Eng. (2021)
Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Lube (5575298)..... <b>B40145</b>
Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	Fuel/Water Separator (Fleetguard FS19764)..... <b>PF9814</b>
T800 w/Cummins ISX 15.0 (14.9L) Eng. (2010-18)	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	Fuel/Water Separator (Fleetguard FS19764G)..... <b>PF46091</b>
<b>11 13/16 In. Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154 +</b>	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	Fuel (5365988)..... <b>BF46129</b>
Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>
<b>14 7/32 In. Dual-Flow Lube</b> (Fleetguard LF9000)..... <b>BD7153 +</b>	Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>	Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>
Fuel/Water Separator Ele. (Fleetguard FS1029W)..... <b>PF7680</b>	Trans. Spin-on (Fuller 4304827).. <b>BT223</b>	Trans. Spin-on (Fuller 4304827).. <b>BT223</b>
Fuel/Water Separator Ele. (Fleetguard FF5369)..... <b>PF7744</b>	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	T800 w/Cummins ISX 15.0 (14.9L) Eng. (2022)
Fuel/Water Separator Ele. (Fleetguard FS19729)..... <b>PF7755</b>	Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	Lube (5575298)..... <b>B40145</b>
Fuel/Water Separator Ele. (Fleetguard FS19765)..... <b>PF7930</b>	Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	Fuel (5575143)..... <b>BF46248</b>
Fuel/Water Separator Spin-on (Fleetguard FS1007)..... <b>BF1274-SP</b>	Diesel Exhaust Fluid (5303604).. <b>PE17000</b>	T800 w/Cummins ISX 15.0 (14.9L) Eng. (2023)
Fuel/Water Separator Spin-on (Fleetguard FS1040)..... <b>BF1277-SPS</b>	T800 w/Cummins ISX 15.0 (14.9L) Eng. (2019)	Lube (5575298)..... <b>B40145</b>
Fuel/Water Separator (K371004) <b>PF9928</b>	Dual-Flow Lube (4367100)..... <b>BD50000</b>	Fuel (5575143)..... <b>BF46248</b>
Fuel/Water Separator (K371011) <b>PF46081</b>	Fuel/Water Separator (K371029) <b>PF46081</b>	Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>
Fuel (Fleetguard FF5686)..... <b>BF9860 +</b>	Fuel (5365988)..... <b>BF46129 +</b>	Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>
Fuel (Standard) (Fleetguard FF5776)..... <b>BF9885 +</b>	EnduraCube Air (P621725)..... <b>[2] PA32000</b>	T800 w/Cummins L10 Eng.
Fuel (Upgrade) (Fleetguard FF5825NN)..... <b>BF46129</b>	Cab Air (HVAC) (F371018)..... <b>PA30269</b>	F-F Lube (KW670)..... <b>B196 +</b>
Axial Seal Air..... <b>PA2705</b>	Cab Air (Recirculation) (W2084001)..... <b>PA30107</b>	B-P Lube (KW777)..... <b>B7577</b>
Channel Flow Air (P611696)..... <b>CA5500</b>	Air Dryer (Bendix 5008414)..... <b>BA5374 +</b>	Fuel/Water Separator (KW1212). <b>BF1212 +</b>
<b>22 29/32 In. Std. Radial Seal Air</b> (P614986)..... <b>[2] RS5288</b>	Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	Fuel Spin-on (K251C390)..... <b>BF957 +</b>
<b>22 29/32 In. Radial Seal XP Air</b> (Paccar P614986)..... <b>[2] RS5288XP</b>	Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Air (KW852M)..... <b>LL2317 +</b>
<b>23 23/32 In. Radial Seal Air</b> (Don. P534816)..... <b>[2] RS3539</b>	Trans. Spin-on (Fuller 4304827).. <b>BT223</b>	Air (KW853M)..... <b>LL2312</b>
	Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	Air (Don. P182009)..... <b>PA2357 +</b>
	Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	Coolant (3315116)..... <b>BW5071</b>
	T800 w/Cummins ISX 15.0 (14.9L) Eng. (2020)	T800 w/Cummins M11 Eng.
	Dual-Flow Lube (4367100)..... <b>BD50000</b>	Dual-Flow Lube (3318853)..... <b>BD103 +</b>
	Fuel/Water Separator (Fleetguard FS19764)..... <b>PF9814</b>	Fuel/Water Separator (Fleetguard FS1212)..... <b>BF1212 +</b>
	Fuel/Water Separator (Fleetguard FS19764G)..... <b>PF46091</b>	Fuel/Water Separator (Fleetguard FS1000)..... <b>BF1259</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)
T800 w/Cummins NTC Eng. Dual-Flow Lube (3825970)..... <b>BD103 +</b> Fuel/Water Separator Ele. (Racor 1000FG)..... <b>PF7890</b> Fuel/Water Separator Spin-on (Fleetguard FS1212)..... <b>BF1212 +</b> Air (Don. P537791)..... <b>PA2705</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Steering (Nelson 83804E)..... <b>P528</b>	T800 w/Cummins X15 (14.9L) Eng. (To 2018) (Cont'd) Diesel Exhaust Fluid (5303604).. <b>PE17000</b> T800 w/Cummins X15 (14.9L) Eng. (2019) Dual-Flow Lube (4367100)..... <b>BD50000</b> Fuel/Water Separator (K371029) <b>PF46081</b> Fuel (5365988)..... <b>BF46129 +</b> EnduraCube Air (P621725)..... <b>[2] PA32000</b> Cab Air (HVAC) (F371018)..... <b>PA30269</b> Cab Air (Recirculation) (W2084001)..... <b>PA30107</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	T800 w/Detroit Diesel Series 60 Eng. Lube..... <b>[2] B495</b> Fuel/Water Separator..... <b>BF5812</b> S. Fuel..... <b>BF5810</b> 22 9/16 In. Air (Don. P537791).... <b>PA2705</b> 23 In. Air (KW852M)..... <b>LL2317 +</b> Air Dryer (Wabco 950011)..... <b>BA5374 +</b> Coolant (Don. P554071)..... <b>BW5137</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Steering (Nelson 83804E)..... <b>P528</b>
T800 w/Cummins N14 Eng. F-F Lube..... <b>B196 +</b> B-P Lube..... <b>B7577</b> Dual-Flow Lube (3318853)..... <b>BD103 +</b> Fuel/Water Separator (Fleetguard FS1212)..... <b>BF1212 +</b> Fuel/Water Separator (3329289). <b>BF1259</b> Fuel Spin-on..... <b>BF957-D +</b> Air (78897-001)..... <b>[2] PA2731</b> Air (Don. P537791)..... <b>PA2705</b> Air Dryer (Bendix 107794)..... <b>BA5377</b> Coolant (3315116)..... <b>BW5071</b> Trans. (Fuller 4304827)..... <b>BT223</b> Steering (Nelson 83804E)..... <b>P528</b>	T800 w/Cummins X15 (14.9L) Eng. (2020) Dual-Flow Lube (4367100)..... <b>BD50000</b> Fuel/Water Separator (Fleetguard FS19764)..... <b>PF9814</b> Fuel/Water Separator (Fleetguard FS19764G)..... <b>PF46091</b> Fuel (5365988)..... <b>BF46129</b> Channel Flow Air (P611696)..... <b>CA5500</b> Air Dryer (Bendix 5008414PG).... <b>BA5379</b> Trans. Ele. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	T800 w/Paccar PX-6 Eng. Lube (Fleetguard LF3970)..... <b>B7177</b> Fuel/Water Separator (Fleetguard FS1003)..... <b>BF1293-SPS</b> Fuel/Water Separator (Fleetguard FS1065)..... <b>BF1378-SPS</b> Fuel (Fleetguard FF5632)..... <b>BF7940</b> Channel Flow Air (P611696)..... <b>CA5500</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Crankcase Breather (4936636).... <b>CV15010</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Trans. Ele. (2 In. Kit) (Allison 29526899)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>
T800 w/Cummins Signature 600 (15.0L) Eng. 11 25/32 In. Dual-Flow Lube (Fleetguard LF9001)..... <b>BD7154 +</b> Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> 14 7/32 In. Dual-Flow Lube (Fleetguard LF9000)..... <b>BD7153 +</b> Fuel/Water Separator (3331096). <b>BF1274-SP</b> Fuel/Water Separator (4010651). <b>BF1277-SPS</b> Air Dryer..... <b>BA5374 +</b> Coolant (Fleetguard WF2126)..... <b>BW5086</b>	T800 w/Detroit Diesel 12V71 (14.0L) Eng. Lube (23530407)..... <b>[2] B95 +</b> Lube (23530408)..... <b>[2] B95-MPG +</b> P. Fuel (23530642)..... <b>[2] BF784</b> S. Fuel (23530643)..... <b>BF785</b> S. Fuel (23530644)..... <b>BF7697</b> Air Dryer..... <b>BA5374 +</b>	T800 w/Paccar PX-8 Eng. Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309 +</b> Fuel/Water Separator (Fleetguard FS1000)..... <b>BF1259</b> Fuel/Water Separator (Fleetguard FS1003)..... <b>BF1293-SPS</b> Fuel/Water Separator (Fleetguard FS1065)..... <b>BF1378-SPS</b> Fuel (Fleetguard FF5488)..... <b>BF7815</b> Channel Flow Air (P611696)..... <b>CA5500</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
T800 w/Cummins VT225 (9.1L) Eng. F-F Lube (3313281)..... <b>B205 +</b> B-P Lube (3304232)..... <b>B7577</b> Fuel (158172)..... <b>BF957 +</b> Air Dryer..... <b>BA5374 +</b> Coolant (w/4 Units BTA+) (3315116)..... <b>BW5071</b>	T800 w/Detroit Diesel Series 50 (8.5L) Eng. Lube (23530573)..... <b>[2] B495</b> Fuel/Water Separator Spin-on (w/Drain) (23535985)..... <b>BF5813 +</b> Fuel/Water Separator Spin-on (Open End for Bowl) (23535985).. <b>BF5813-O +</b> P. Fuel (23530706)..... <b>BF5800 +</b> S. Fuel (23530707)..... <b>BF5810</b> Air Dryer..... <b>BA5374 +</b>	
T800 w/Cummins X15 (14.9L) Eng. (To 2018) Dual-Flow Lube (4367100)..... <b>BD50000</b> Fuel/Water Separator (K371011) <b>PF46081</b> Fuel (5365988)..... <b>BF46129</b> Channel Flow Air (P611696)..... <b>CA5500</b> Cab Air (TRP CFR19501)..... <b>PA30287</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Trans. Ele. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)
T800 w/Paccar PX-8 Eng. (Cont'd)	T800 w/Paccar MX-11 (10.8L) Eng. (2018)	T800 w/Paccar MX-13 (12.9L) Eng. (2014-18)
Trans. Spin-on (Allison 29539579).....	F-F Lube (1928868PE).....	(Cont'd)
BT8460	Centrifugal Lube (1928869PE)...	Channel Flow Air (P611696).....
Trans. Ele. (2 In. Kit) (Allison 29526899).....	BC40009	22 29/32 In. Std. Radial Seal Air (P614986).....
PT9416-MPG KIT	Fuel/Water Separator (K371012).....	RS5288
Trans. Ele. (4 In. Kit) (Allison 29540494).....	PF46082	22 29/32 In. Radial Seal XP Air (Paccar P614986).....
PT9415-MPG KIT	Fuel (1852006PE).....	RS5288XP
Trans. Spin-on (Fuller 4304827).....	PF46106	Cab Air (X1987001).....
BT223	Channel Flow Air (P611696).....	PA30107
Opt. Trans. Spin-on (Fuller 17237).....	CA5500	Cab Air (W2084001).....
B2 +	Cab Air (TRP CFR19501).....	PA30287
Steering (Nelson 87904M).....	PA30287	Air Dryer (Bendix 5008414).....
PT9354-MPG	Air Dryer (Bendix 5008414).....	BA5374 +
T800 w/Paccar PX-9 (8.9L) Eng. (2019)	BA5374 +	Coolant (1843659PE).....
Dual-Flow Lube (Fleetguard LF9009).....	Coolant (1843659PE).....	B5088 +
BD7309 +	Trans. (Fuller 4304827).....	Trans. Ele. (2 In. Kit) (Allison 29526899).....
Fuel/Water Separator (Fleetguard FS1003).....	BT223	PT9416-MPG KIT
BF1293-SPS	Opt. Trans. (Fuller 17237).....	Trans. Ele. (4 In. Kit) (Allison 29540494).....
Fuel (Fleetguard FF63009).....	B2 +	PT9415-MPG KIT
BF63000	Steering (Nelson 87904M).....	Trans. Spin-on (Fuller 4304827).....
EnduraCube Air (P621725).....	PT9354-MPG	BT223
[2] PA32000	Opt. Rear Axle (Meritor 3280V8394).....	Opt. Trans. Spin-on (Fuller 17237).....
Cab Air (HVAC) (F371018).....	B233	B2 +
PA30269	T800 w/Paccar MX-11 (10.8L) Eng. (2019)	Steering (Nelson 87904M).....
Cab Air (Recirculation) (W2084001).....	F-F Lube (2129253PE).....	PT9354-MPG
PA30107	P40008	Opt. Rear Axle (Meritor 3280V8394).....
Air Dryer (Bendix 5008414).....	Centrifugal Lube (1928869PE)...	B233
BA5374 +	BC40009	Diesel Exhaust Fluid (5303604).....
Steering (Nelson 87904M).....	Fuel/Water Separator (K371012).....	PE17000
PT9354-MPG	PF46082	T800 w/Paccar MX-13 (12.9L) Eng. (2019)
Opt. Rear Axle (Meritor 3280V8394).....	Fuel (2133096PE).....	F-F Lube (2047411PE).....
B233	PF46106	P40069
T800 w/Paccar MX Eng.	EnduraCube Air (P621725).....	Centrifugal Lube (1922496PE)...
Lube Ele. (1643070).....	[2] PA32000	BC40148
P40019	Cab Air (HVAC) (F371018).....	Fuel/Water Separator (2133096PE).....
Lube Spinner (1643072).....	PA30269	PF46106
BC7326 +	Cab Air (Recirculation) (W2084001).....	EnduraCube Air (P621725).....
Fuel/Water Separator (Fleetguard FS19729).....	PA30107	[2] PA32000
PF7755	Air Dryer (Bendix 5008414).....	Cab Air (HVAC) (F371018).....
Fuel/Water Separator (Fleetguard FS19765).....	BA5374 +	PA30269
PF7930	Coolant (1843659PE).....	Cab Air (Recirculation) (W2084001).....
Fuel/Water Separator (K37-1005).....	B5088 +	PA30107
PF9928	Trans. Ele. (2 In. Kit) (Allison 29558117).....	Air Dryer (Bendix 5008414).....
Fuel (1655115).....	PT9416-MPG KIT	BA5374 +
BF9927	Trans. Ele. (4 In. Kit) (Allison 29558118).....	B5088 +
Channel Flow Air (P611696).....	PT9415-MPG KIT	Trans. Ele. (2 In. Kit) (Allison 29558117).....
CA5500	Trans. Spin-on (Fuller 4304827).....	PT9416-MPG KIT
Std. Radial Seal Air (P614986)...	BT223	Trans. Ele. (4 In. Kit) (Allison 29558118).....
[2] RS5288	Opt. Trans. Spin-on (Fuller 17237).....	PT9415-MPG KIT
Radial Seal Air XP (Paccar P614986).....	B2	Trans. Spin-on (Fuller 4304827).....
[2] RS5288XP	PT9354-MPG	BT223
Air Dryer (Bendix 5008414).....	Opt. Rear Axle (Meritor 3280V8394).....	Steering (Nelson 87904M).....
BA5374 +	B233	PT9354-MPG
Coolant (1843659).....	T800 w/Paccar MX-11 (10.8L) Eng. (2020)	Opt. Rear Axle (Meritor 3280V8394).....
B5088 +	Lube Ele. (2151728PE).....	B233
Trans. (Fuller 4304827).....	P40069	Diesel Exhaust Fluid (2122909PE).....
BT223	Centrifugal Lube (1922496PE)...	PE17002 KIT
Opt. Trans. (Fuller 17237).....	BC40148	T800 w/Paccar MX-13 (12.9L) Eng. (2020)
B2 +	Fuel/Water Separator (2133096PE).....	F-F Lube (2151728PE).....
Steering (Nelson 87904M).....	PF46106	P40069
PT9354-MPG	Fuel (2277129PE).....	Centrifugal Lube (1922496PE)...
Diesel Exhaust Fluid (5303604).....	PF46106	BC40148
PE17000	Channel Flow Air (P611696).....	Fuel/Water Separator (Fleetguard FS19764G).....
T800 w/Paccar MX-11 (10.8L) Eng. (To 2017)	CA5500	PF46106
Lube (1928868PE).....	Cab Air (TRP CFR19501).....	Channel Flow Air (P611696).....
P40008	PA30287	CA5500
Centrifugal Lube (1928869PE)...	Air Dryer (Bendix 5008414).....	Air Dryer (Bendix 5008414PG)...
BC40009	BA5374 +	BA5379
Fuel/Water Separator (K371012).....	Coolant (1843659PE).....	Coolant (1843659PE).....
PF46082	B5088 +	B5088
Fuel (1852006PE).....	Trans. (Fuller 4304827).....	Trans. Ele. (2 In. Kit) (Allison 29548987).....
PF46106	BT223	PT9416-MPG KIT
Channel Flow Air (P611696).....	Opt. Trans. (Fuller 17237).....	Trans. Ele. (4 In. Kit) (Allison 29548988).....
CA5500	B2 +	PT9415-MPG KIT
Cab Air (TRP CFR19501).....	Steering (Nelson 87904M).....	Trans. Spin-on (Fuller 4304827).....
PA30287	PT9354-MPG	BT223
Air Dryer (Bendix 5008414).....	T800 w/Paccar MX-13 (12.9L) Eng. (2014-18)	
BA5374 +	Lube Ele. (1643070).....	
Coolant (1843659PE).....	P40019	
B5088 +	Lube (2047411PE).....	
Trans. (Fuller 4304827).....	P40069	
BT223	Centrifugal Lube (1922496).....	
Opt. Trans. (Fuller 17237).....	BC40148	
B2 +	Fuel/Water Separator (K371009).....	
Steering (Nelson 87904M).....	PF9929	
PT9354-MPG	Fuel/Water Separator (K371012).....	
	PF46082	
	Fuel (1852006).....	
	PF46106	

+ See Product Guide for Variations of This Number. Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)
T800 w/Paccar MX-13 (12.9L) Eng. (2020) (Cont'd) <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (2122909PE)..... <b>PE17002 KIT</b>	T880 w/Cummins ISL-G (8.9L) Eng. (2018) (Cont'd) <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	T880 w/Cummins ISX 11.9 (11.9L) Eng. (2019) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (K371029) <b>PF46081</b> <b>Fuel</b> (2893612)..... <b>BF9885 +</b> <b>EnduraCube Air</b> (P621725)..... <b>PA32000</b> <b>Cab Air</b> (X1987001)..... <b>PA30093</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>
T800 w/Paccar MX-13 (12.9L) Eng. (2021) <b>F-F Lube</b> (2234788PE)..... <b>P40069</b> <b>Centrifugal Lube</b> (1922496PE)... <b>BC40148</b> <b>Fuel</b> (2277129PE)..... <b>PF46106</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	T880 w/Cummins ISL-G (8.9L) Eng. (2019) <b>Lube</b> (3401544)..... <b>B40142</b> <b>Fuel</b> (3606712)..... <b>BF7695</b> <b>EnduraCube Air</b> (P621725)..... <b>PA32000</b> <b>Cab Air</b> (X1987001)..... <b>PA30093</b> <b>Air Dryer</b> (Bendix 5008414PG)... <b>BA5379</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	T880 w/Cummins ISX 11.9 (11.9L) Eng. (2020) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (K371029) <b>PF46081</b> <b>Fuel</b> (2893612)..... <b>BF9885</b> <b>EnduraCube Air</b> (Don. P621725) <b>PA32000</b> <b>Cab Air</b> (X1987001)..... <b>PA30093</b> <b>Air Dryer</b> (Bendix 5008414PG)... <b>BA5379 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
T800 w/Westport HD GX (15.0L) Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9080)..... <b>BD7154 +</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (Fleetguard NG5900)..... <b>BF7695</b> <b>Channel Flow Air</b> (P611696)..... <b>CA5500</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Coolant</b> (w/o Chemical) (Fleetguard WF2127)..... <b>B5087</b> <b>Coolant</b> (w/Chemical) (Fleetguard WF2126)..... <b>BW5086</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	T880 w/Cummins ISL-G (8.9L) Eng. (2020) <b>Lube</b> (Fleetguard LF9009)..... <b>B40142</b> <b>Fuel</b> (Fleetguard NG5900)..... <b>BF7695</b> <b>Channel Flow Air</b> (P611696)..... <b>CA5500</b> <b>Cab Air</b> (X1987001)..... <b>PA30093</b> <b>Air Dryer</b> (Bendix 5008414PG)... <b>BA5379</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	T880 w/Cummins ISX 11.9G (11.9L) Eng. (2018) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (3607140). <b>BF7695</b> <b>EnduraCube Air</b> (P621725)..... <b>PA32000</b> <b>EnduraCube Air</b> (P621730)..... <b>PA32003</b> <b>Cab Air</b> (X1987001)..... <b>PA30093</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Coolant</b> (36080434)..... <b>B5087</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
T880 w/Cummins ISL-G (8.9L) Eng. (2018) <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309</b> <b>Fuel/Water Separator</b> (Fleetguard NG5900)..... <b>BF7695</b> <b>EnduraCube Air</b> (P621725)..... <b>PA32000</b> <b>EnduraCube Air</b> (P621730)..... <b>PA32003</b> <b>Cab Air</b> (X1987001)..... <b>PA30093</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	T880 w/Cummins ISX 11.9 (11.9L) Eng. (2015-18) <b>Dual-Flow Lube</b> (4331005)..... <b>BD7154 +</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (Fleetguard FS19764)..... <b>PF9814</b> <b>Fuel/Water Separator</b> (Fleetguard FS19765)..... <b>PF7930</b> <b>Fuel/Water Separator</b> (K371029) <b>PF46081</b> <b>Fuel</b> (2893612)..... <b>BF9885 +</b> <b>EnduraCube Air</b> (P621725)..... <b>PA32000</b> <b>EnduraCube Air</b> (P621730)..... <b>PA32003</b> <b>Cab Air</b> (F37-1018)..... <b>PA30269</b> <b>Cab Air</b> (Cab. Intake) (X1987001)..... <b>PA30093</b> <b>Cab Air</b> (Recirculation) (W2084001)..... <b>PA30107</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Breather</b> (4312013)..... <b>CV15000</b> <b>Coolant</b> (3680434)..... <b>B5087</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b> <b>Diesel Exhaust Fluid</b> (Fleetguard UF106)..... <b>PE17002 KIT</b>	T880 w/Cummins ISX 11.9G (11.9L) Eng. (2019) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (3607140). <b>[2] BF7695</b> <b>EnduraCube Air</b> (P621725)..... <b>PA32000</b> <b>Cab Air</b> (X1987001)..... <b>PA30093</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Coolant</b> (3680434)..... <b>B5087</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>KENWORTH Trucks (cont'd)</b>	<b>KENWORTH Trucks (cont'd)</b>	<b>KENWORTH Trucks (cont'd)</b>
T880 w/Cummins ISX 11.9G (11.9L) Eng. (2020) <b>Dual-Flow Lube</b> (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel</b> (Fleetguard NG5900)..... <b>BF7695</b> <b>EnduraCube Air</b> (Don. P621725) <b>PA32000</b> <b>Cab Air</b> (X1987001)..... <b>PA30093</b> <b>Air Dryer</b> (Bendix 5008414PG).... <b>BA5379 +</b> <b>Trans.</b> (2 In. Kit) (29558117)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (29558118)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	T880 w/Cummins ISX 15.0 (14.9L) Eng. (2019) (Cont'd) <b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	T880 w/Cummins X15 (14.9L) Eng. (2018) (Cont'd) <b>Cab Air</b> (X1987001)..... <b>PA30093</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (Fleetguard UF106)..... <b>PE17002 KIT</b>
T880 w/Cummins ISX 11.9G (11.9L) Eng. (2021) <b>Lube</b> (5575298)..... <b>B40145</b> <b>Fuel</b> (3607140)..... <b>BF7695</b> <b>EnduraCube Air</b> (P621725)..... <b>PA32000</b> <b>Coolant</b> (3680434)..... <b>B5087</b>	T880 w/Cummins ISX 15.0 (14.9L) Eng. (2020) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (K371029) <b>PF46081</b> <b>Fuel</b> (5365988)..... <b>BF46129</b> <b>EnduraCube Air</b> (Don. P621725) <b>PA32000</b> <b>Cab Air</b> (X1987001)..... <b>PA30093</b> <b>Air Dryer</b> (Bendix 5008414PG).... <b>BA5379 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	T880 w/Cummins X15 (14.9L) Eng. (2019) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (Fleetguard FS19764)..... <b>PF9814</b> <b>Fuel/Water Separator</b> (K371029) <b>PF46081</b> <b>Fuel</b> (5365988)..... <b>BF46129 +</b> <b>EnduraCube Air</b> (P621725)..... <b>PA32000</b> <b>Cab Air</b> (X1987001)..... <b>PA30093</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
T880 w/Cummins ISX 15.0 (14.9L) Eng. (2015-18) <b>Dual-Flow Lube</b> (4331005)..... <b>BD7154 +</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (K371011) <b>PF46081</b> <b>Fuel/Water Separator</b> (Fleetguard FS19765)..... <b>PF7930</b> <b>Fuel</b> (2893612)..... <b>BF9885 +</b> <b>Fuel</b> (Fleetguard FF5825NN)..... <b>BF46129</b> <b>EnduraCube Air</b> (P621725)..... <b>PA32000</b> <b>EnduraCube Air</b> (P621730)..... <b>PA32003</b> <b>Cab Air</b> (F37-1018)..... <b>PA30269</b> <b>Cab Air</b> (Cab. Intake) (X1987001)..... <b>PA30093</b> <b>Cab Air</b> (Recirculation) (W2084001)..... <b>PA30107</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Breather</b> (4312013)..... <b>CV15000</b> <b>Coolant</b> (3680434)..... <b>B5087</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>	T880 w/Cummins ISX 15.0 (14.9L) Eng. (2021) <b>Lube</b> (5575298)..... <b>B40145</b> <b>Fuel/Water Separator</b> (Fleetguard FS19764G)..... <b>PF46091</b> <b>Fuel</b> (5365988)..... <b>BF46129</b> <b>EnduraCube Air</b> (P621725)..... <b>PA32000</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	T880 w/Cummins X15 (14.9L) Eng. (2020) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (K371029) <b>PF46081</b> <b>Fuel</b> (5365988)..... <b>BF46129</b> <b>EnduraCube Air</b> (Don. P621725) <b>PA32000</b> <b>Cab Air</b> (X1987001)..... <b>PA30093</b> <b>Air Dryer</b> (Bendix 5008414PG).... <b>BA5379 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
T880 w/Cummins ISX 15.0 (14.9L) Eng. (2019) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (Fleetguard FS19764)..... <b>PF9814</b> <b>Fuel/Water Separator</b> (K371029) <b>PF46081</b> <b>Fuel</b> (5365988)..... <b>BF46129 +</b> <b>EnduraCube Air</b> (P621725)..... <b>PA32000</b> <b>Cab Air</b> (X1987001)..... <b>PA30093</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b>	T880 w/Cummins ISX 15.0 (14.9L) Eng. (2023) <b>Lube</b> (5575298)..... <b>B40145</b> <b>Fuel</b> (5575143)..... <b>BF46248</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	T880 w/Paccar PX-9 (8.9L) Eng. (2018) <b>Lube</b> (3401544)..... <b>B40142</b> <b>Fuel/Water Separator</b> (Fleetguard FS1003)..... <b>BF1293-SPS</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>EnduraCube Air</b> (P621725)..... <b>PA32000</b> <b>EnduraCube Air</b> (P621730)..... <b>PA32003</b> <b>Cab Air</b> (X1987001)..... <b>PA30093</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>
T880 w/Cummins ISX 15.0 (14.9L) Eng. (2019) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (K371029) <b>PF46081</b> <b>Fuel</b> (5365988)..... <b>BF46129 +</b> <b>EnduraCube Air</b> (P621725)..... <b>PA32000</b> <b>Cab Air</b> (X1987001)..... <b>PA30093</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b>	T880 w/Cummins X15 (14.9L) Eng. (2018) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (K371029) <b>PF46081</b> <b>Fuel/Water Separator</b> (Fleetguard FS19765)..... <b>PF7930</b> <b>Fuel</b> (5365988)..... <b>BF46129</b> <b>EnduraCube Air</b> (P621725)..... <b>PA32000</b> <b>EnduraCube Air</b> (P621730)..... <b>PA32003</b>	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>KENWORTH Trucks (cont'd)</b>	<b>KENWORTH Trucks (cont'd)</b>	<b>KENWORTH Trucks (cont'd)</b>
T880 w/Paccar PX-9 (8.9L) Eng. (2018) (Cont'd) Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	T880 w/Paccar MX-11 (10.8L) Eng. (2015-18) (Cont'd) EnduraCube Air (P621730)..... <b>PA32003</b> Cab Air (Cab. Intake) (X1987001)..... <b>PA30093</b> Cab Air (Recirculation) (W2084001)..... <b>PA30107</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Coolant (1843659)..... <b>B5088 +</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b> Diesel Exhaust Fluid (5303604).. <b>PE17000</b>	T880 w/Paccar MX-11 (10.8L) Eng. (2021) Lube (2129253PE)..... <b>P40008</b> Fuel/Water Separator (K371012) <b>PF46082</b> Fuel (2277129PE)..... <b>PF46106</b> EnduraCube Air (P621725)..... <b>PA32000</b> T880 w/Paccar MX-13 (12.9L) Eng. (2014-18) Lube Ele. (1643070)..... <b>P40019</b> Lube (2047411PE)..... <b>P40069</b> Centrifugal Lube (1922496)..... <b>BC40148</b> Fuel/Water Separator (K371009) <b>PF9929</b> Fuel/Water Separator (K371012) <b>PF46082</b> Fuel (1852006)..... <b>PF46106</b> EnduraCube Air (P621725)..... <b>PA32000</b> EnduraCube Air (P621730)..... <b>PA32003</b> Cab Air (F37-1018)..... <b>PA30269</b> Cab Air (Cab. Intake) (X1987001)..... <b>PA30093</b> Cab Air (Recirculation) (W2084001)..... <b>PA30107</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Coolant (1843659)..... <b>B5088 +</b> Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> Trans. Ele. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b> Diesel Exhaust Fluid (2122909PE)..... <b>PE17002 KIT</b> Diesel Exhaust Fluid (5303604).. <b>PE17000</b>
T880 w/Paccar PX-9 (8.9L) Eng. (2019) Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309 +</b> Fuel/Water Separator (Fleetguard FS1003)..... <b>BF1293-SPS</b> Fuel (Fleetguard FF63009)..... <b>BF63000</b> EnduraCube Air (P621725)..... <b>[2] PA32000</b> Cab Air (HVAC) (F371018)..... <b>PA30269</b> Cab Air (Recirculation) (W2084001)..... <b>PA30107</b> Air Dryer (Bendix 5008414)..... <b>BA5374</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	T880 w/Paccar MX-11 (10.8L) Eng. (2019) F-F Lube (2129253PE)..... <b>P40008</b> Centrifugal Lube (1928869PE).... <b>BC40009</b> Fuel/Water Separator (K371012) <b>PF46082</b> Fuel (2133096PE)..... <b>PF46106</b> EnduraCube Air (P621725)..... <b>PA32000</b> Cab Air (X1987001)..... <b>PA30093</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Coolant (1843659PE)..... <b>B5088 +</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b> Diesel Exhaust Fluid (2122909PE)..... <b>PE17002 KIT</b>	T880 w/Paccar MX-13 (12.9L) Eng. (2019) F-F Lube (2047411PE)..... <b>P40069</b> Centrifugal Lube (1922496PE).... <b>BC40148</b> Fuel/Water Separator (Fleetguard FS19765G)..... <b>PF46094</b> Fuel/Water Separator (K371022) <b>PF46237</b> EnduraCube Air (P621725)..... <b>PA32000</b> Cab Air (X1987001)..... <b>PA30093</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Coolant (1843659PE)..... <b>B5088 +</b> Trans. Ele. (2 In. Kit) (Allison 29545776)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29545779)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b> Diesel Exhaust Fluid (2122909PE)..... <b>PE17002 KIT</b>
T880 w/Paccar PX-9 (8.9L) Eng. (2020) Lube (3401544)..... <b>B40142</b> Fuel/Water Separator (K371017) <b>PF46238</b> Fuel (5303743)..... <b>BF63000</b> EnduraCube Air (Don. P621725) <b>PA32000</b> Cab Air (X1987001)..... <b>PA30093</b> Air Dryer (Bendix 5008414PG).... <b>BA5379 +</b> Trans. Ele. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	T880 w/Paccar MX-11 (10.8L) Eng. (2020) Lube Ele. (2151728PE)..... <b>P40069</b> Centrifugal Lube (1922496PE).... <b>BC40148</b> Fuel/Water Separator (2133096PE)..... <b>PF46106</b> Fuel (2277129PE)..... <b>PF46106</b> EnduraCube Air (Don. P621725) <b>PA32000</b> Cab Air (X1987001)..... <b>PA30093</b> Air Dryer (Bendix 5008414PG).... <b>BA5379 +</b> Coolant (1843659PE)..... <b>B5088</b> Trans. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b> Diesel Exhaust Fluid (2122909PE)..... <b>PE17002 KIT</b>	T880 w/Paccar MX-13 (12.9L) Eng. (2020) F-F Lube (2151728PE)..... <b>P40069</b> Centrifugal Lube (1922496PE).... <b>BC40148</b> Fuel/Water Separator (Fleetguard FS19765)..... <b>PF7930</b> Fuel/Water Separator (Fleetguard FS19727)..... <b>PF7895</b> Fuel (1852006)..... <b>PF46106</b> EnduraCube Air (P621725)..... <b>PA32000</b>
T880 w/Paccar PX-9 (8.9L) Eng. (2021) Lube (5444774)..... <b>B40142</b> Fuel (5303743)..... <b>BF63000</b> EnduraCube Air (P621725)..... <b>PA32000</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	T880 w/Paccar MX-11 (10.8L) Eng. (2020) Lube Ele. (2151728PE)..... <b>P40069</b> Centrifugal Lube (1922496PE).... <b>BC40148</b> Fuel/Water Separator (2133096PE)..... <b>PF46106</b> Fuel (2277129PE)..... <b>PF46106</b> EnduraCube Air (Don. P621725) <b>PA32000</b> Cab Air (X1987001)..... <b>PA30093</b> Air Dryer (Bendix 5008414PG).... <b>BA5379 +</b> Coolant (1843659PE)..... <b>B5088</b> Trans. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b> Diesel Exhaust Fluid (2122909PE)..... <b>PE17002 KIT</b>	T880 w/Paccar MX-13 (12.9L) Eng. (2020) F-F Lube (2151728PE)..... <b>P40069</b> Centrifugal Lube (1922496PE).... <b>BC40148</b> Fuel/Water Separator (Fleetguard FS19765)..... <b>PF7930</b>
T880 w/Paccar PX-9 (8.9L) Eng. (2022) Lube (5444774)..... <b>B40142</b>	T880 w/Paccar PX-9 (8.9L) Eng. (2023) Lube (5520789)..... <b>B40142</b>	
T880 w/Paccar MX-11 (10.8L) Eng. (2015-18) Lube Ele. (1928868PE)..... <b>P40008</b> Centrifugal Lube (1928869)..... <b>BC40009</b> Fuel/Water Separator (Fleetguard FS19624)..... <b>PF7748</b> Fuel/Water Separator (Fleetguard FS19765)..... <b>PF7930</b> Fuel/Water Separator (Fleetguard FS19727)..... <b>PF7895</b> Fuel (1852006)..... <b>PF46106</b> EnduraCube Air (P621725)..... <b>PA32000</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)
T880 w/Paccar MX-13 (12.9L) Eng. (2020) (Cont'd)	T950 w/Cat C15 Eng.	T2000 w/Cat C12 Eng. (Cont'd)
Fuel (2133096PE)..... PF46106	Lube (1R0716)..... B99 +	25 23/32 In. Radial Seal Air (Don. P534925)..... RS3534
EnduraCube Air (Don. P621725) PA32000	Fuel/Water Separator (Open End for Bowl) (1335673)..... BF1395-O	Cab Air (525507)..... PA5306
Cab Air (X1987001)..... PA30093	Fuel/Water Separator (w/Drain) (1335673)..... BF1265	Air Dryer (AD-SP System) (Bendix 5008414)..... BA5374 +
Air Dryer (Bendix 5008414PG)..... BA5379 +	Fuel/Water Separator (w/Sensor Port) (1335673)..... BF1395-SP	Coolant (Fleetguard WF2071)..... BW5071
Coolant (1843659PE)..... B5088	Fuel (1R-0749)..... BF7587 +	Opt. Trans. (Fuller 17237)..... B2 +
Trans. Ele. (2 In. Kit) (Allison 29558117)..... PT9416-MPG KIT	Coolant (9N-6123)..... BW5139	Steering (Nelson 83804E)..... P528
Trans. Ele. (4 In. Kit) (Allison 29558118)..... PT9415-MPG KIT	T953 w/Cat 3176 Eng.	T2000 w/Cat C13 Eng.
Trans. Spin-on (Fuller 4304827) BT223	Lube..... B99 +	Lube (1R1808)..... B7299 +
Steering (Nelson 87904M)..... PT9354-MPG	Air (KW852M)..... LL2317 +	Fuel/Water Separator (256-8753)..... BF1259
Opt. Rear Axle (Meritor 3280V8394)..... B233	T2000 w/Cat C7 (7.2L) Eng.	Fuel (1R0749)..... BF7587 +
Diesel Exhaust Fluid (2122909PE)..... PE17002 KIT	Lube (Standard Vers.) (1R0739).. B76 +	Radial Seal Air (Don. P542101) RS3750
T880 w/Paccar MX-13 (12.9L) Eng. (2021)	F-F Lube (1R1808)..... B7299 +	Radial Seal XP Air (Don. P542101)..... RS3750XP
F-F Lube (2234788PE)..... P40069	Lube (Severe Service) (1R0739).. B76-SS +	Cab Air (525507)..... PA5306
Centrifugal Lube (1922496PE) BC40148	Fuel/Water Separator (1752949) BF1268	Air Dryer (Bendix 5008414) BA5374 +
Fuel (2277129PE)..... PF46106	Fuel Spin-on (1R0751)..... BF7632	Coolant (Fleetguard WF2071) BW5071
EnduraCube Air (P621725) PA32000	Trans. Spin-on (Fuller 4304827) BT223	Opt. Trans. (Fuller 17237) B2 +
Trans. Ele. (2 In. Kit) (Allison 29558117)..... PT9416-MPG KIT	Opt. Trans. Spin-on (Fuller 17237)..... B2 +	Steering (Nelson 87904M) PT9354-MPG
Trans. Ele. (4 In. Kit) (Allison 29558118)..... PT9415-MPG KIT	T2000 w/Cat C10 (10.3L) Eng.	T2000 w/Cat C15 Eng.
Trans. Spin-on (Fuller 4304827) BT223	F-F Lube (Std. Version) (1R0716)..... B99 +	F-F Lube (To 1/2004)..... B99 +
T880 w/Paccar MX-13 (12.9L) Eng. (2022)	F-F Lube (High Efficiency Vers.) (1R1808)..... B7299 +	F-F Lube (1/04 on) (1R1808) B7299 +
Trans. Ele. (2 In. Kit) (Allison 29558117)..... PT9416-MPG KIT	B-P Lube (1W8845)..... B7577	Fuel/Water Separator (256-8753)..... BF1259
Trans. Ele. (4 In. Kit) (Allison 29558118)..... PT9415-MPG KIT	Fuel (Standard Vers.) (1R1712) BF614 +	Fuel Spin-on (1R0749) BF7587 +
T904 w/Cat C15 Eng.	Fuel (High Efficiency Vers.) (1R0749)..... BF7587 +	Radial Seal XP Air (Don. EAF5107)..... RS3750XP
Lube (1R0716)..... B99 +	Trans. Spin-on (Fuller 4304827) BT223	Cab Air (525507)..... PA5306
Fuel/Water Separator (326-1641)..... BF9903-SP	Opt. Trans. Spin-on (Fuller 17237)..... B2 +	Air Dryer (Bendix 5008414) BA5374 +
Fuel/Water Separator (Open End for Bowl) (1335673)..... BF1395-O	T2000 w/Cat C11 Eng.	Coolant (w/4 Units BTA+) BW5071
Fuel/Water Separator (w/Drain) (1335673)..... BF1265	Lube (1R1808)..... B7299 +	Coolant (w/o Chemical) (Fleetguard WF2122)..... B5088 +
Fuel/Water Separator (w/Sensor Port) (1335673)..... BF1395-SP	Fuel (1R0749)..... BF7587 +	Trans. (Fuller 4304827) BT223
P. Fuel (9M-2342)..... PF935	Radial Seal XP Air (Don. EAF5107)..... RS3750XP	Opt. Trans. (Fuller 17237) B2 +
S. Fuel (1R-0749)..... BF7587 +	Cab Air (525507)..... PA5306	Steering (Nelson 87904M) PT9354-MPG
Coolant (9N-6123)..... BW5139	Air Dryer (Bendix 5008414) BA5374 +	T2000 w/Cat 3126 (7.2L) Eng.
T904 w/Cummins ISX Eng.	Opt. Trans. (Fuller 17237) B2 +	Lube (Standard Vers.) (1R0739) B76 +
Dual-Flow Lube (Fleetguard LF9031)..... BD7509 +	Steering (Nelson 87904M) PT9354-MPG	Lube (Severe Service) (1R0739) B76-SS +
Dual-Flow Lube (Fleetguard LF9080)..... BD7154 +	T2000 w/Cat C12 Eng.	Fuel Ele. (9M2342) [2] PF935
Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... BD50000	F-F Lube (1R0716)..... B99 +	Fuel Spin-on (1R0751) BF7632
Fuel/Water Separator (Fleetguard FS1040)..... BF1277-SPS	B-P Lube (1W8845)..... B7577	Trans. Spin-on (Fuller 4304827) BT223
Fuel/Water Separator (Upgrade) (Fleetguard FS1007)..... BF1274-SP	Fuel/Water Separator (Fleetguard FS1000)..... BF1259	Opt. Trans. Spin-on (Fuller 17237)..... B2 +
Coolant (Fleetguard WF2126) BW5086	Fuel Spin-on (1R0712) BF614 +	T2000 w/Cat 3406 (14.6L) Eng.
Trans. (Fuller 4304827) BT223	Single Radial Seal Air (Don. P542101)..... RS3750	Lube (1R0716)..... B99 +
	Single Radial Seal XP Air (Don. P542101)..... RS3750XP	Opt. Fuel/Water Separator (Fleetguard FS1000)..... BF1259
	15 21/32 In. Radial Seal O. Air (Don. P536142)..... RS3548	Fuel Spin-on (1R0749) BF7587 +
	15 21/32 In. Radial Seal XP O. Air (Don. P536142)..... RS3548XP	Radial Seal O. Air (Don. P542101)..... RS3750
		Radial Seal O. XP Air (Don. P542101)..... RS3750XP
		Single Radial Seal Air (Don. P536142)..... RS3548
		Single Radial Seal XP Air (Don. P536142)..... RS3548XP

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

**Trucks & Buses Applications** **BALDWIN FILTERS**

<b>KENWORTH Trucks (cont'd)</b>	<b>KENWORTH Trucks (cont'd)</b>	<b>KENWORTH Trucks (cont'd)</b>
T2000 w/Cat 3406 (14.6L) Eng. (Cont'd) <b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b> <b>Air Dryer</b> (AD-SP System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Coolant</b> (Fleetguard WF2122)..... <b>B5088 +</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 83804E)..... <b>P528</b>	T2000 w/Cummins ISM 10.8 (10.8L) Eng. (To 2006) (Cont'd) <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	T2000 w/Cummins ISX 15.0 (14.9L) Eng. (2007-on) (Cont'd) <b>Fuel</b> (Pre-Filter) (Fleetguard FF2203)..... <b>BF7760</b> <b>Radial Seal XP Air</b> (Don. EAF5107)..... <b>RS3750XP</b> <b>Cab Air</b> (525507BSM)..... <b>PA5306</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Breather</b> (3683918)..... <b>CV15000</b> <b>Coolant</b> (Fleetguard WF2127)..... <b>B5087</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>
T2000 w/Cummins 6BT5.9 (5.9L) Eng. (To 1998) <b>Lube</b> (3914395)..... <b>BT339 +</b> <b>Fuel/Water Separator</b> (3925274)..... <b>BF1280 +</b> <b>Fuel</b> (3903640)..... <b>BF788</b> <b>Trans. Spin-on</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	T2000 w/Cummins ISM 10.8 (10.8L) Eng. (2007-on) <b>Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154 +</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (Fleetguard FS1000)..... <b>BF1259</b> <b>Radial Seal XP Air</b> (Don. EAF5107)..... <b>RS3750XP</b> <b>Cab Air</b> (525507)..... <b>PA5306</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Breather</b> (3683918)..... <b>CV15000</b> <b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	T2000 w/Cummins M11 Eng. <b>Dual-Flow Lube</b> (Fleetguard LF3000)..... <b>BD103 +</b> <b>Fuel/Water Separator</b> (Fleetguard FS1000)..... <b>BF1259</b> <b>Radial Seal Air</b> (Don. P536142)..... <b>RS3548</b> <b>Radial Seal XP Air</b> (Don. P536142)..... <b>RS3548XP</b> <b>Air Dryer</b> (AD-SP System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 83804E)..... <b>P528</b>
T2000 w/Cummins 6BT5.9 (5.9L) Eng. (1998-on) <b>Lube</b> (Chrysler 5083285AA)..... <b>BT7349</b> <b>Fuel/Water Separator</b> (3925274)..... <b>BF1280 +</b> <b>Fuel</b> (3903640)..... <b>BF788</b> <b>Trans. Spin-on</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	T2000 w/Cummins ISX 15.0 (14.9L) Eng. (To 2006) <b>11 13/16 In. Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154 +</b> <b>14 7/32 In. Dual-Flow Lube</b> ..... <b>BD7153 +</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19729)..... <b>PF7755</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1007)..... <b>BF1274-SP</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1040)..... <b>BF1277-SPS</b> <b>Fuel</b> (Fleetguard FF2200)..... <b>BF7766</b> <b>Fuel</b> (Pre-Filter) (Fleetguard FF2203)..... <b>BF7760</b> <b>Radial Seal XP Air</b> (Don. EAF5107)..... <b>RS3750XP</b> <b>Cab Air</b> (525507BSM)..... <b>PA5306</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Coolant</b> (Fleetguard WF2127)..... <b>B5087</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	T2000 w/Cummins N14 Eng. <b>F-F Lube</b> ..... <b>B196 +</b> <b>B-P Lube</b> ..... <b>B7577</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Dual-Flow Lube</b> (3401544)..... <b>BD7309 +</b> <b>Lube</b> (Upgrade) (3401544)..... <b>B40142 +</b> <b>Fuel/Water Separator</b> (3889716)..... <b>BF1259</b> <b>Fuel Spin-on</b> ..... <b>BF957-D +</b> <b>Radial Seal O. Air</b> (Don. P536142)..... <b>RS3548</b> <b>Radial Seal XP Air</b> (Don. P536142)..... <b>RS3548XP</b> <b>Single Radial Seal Air</b> (Don. P542101)..... <b>RS3750</b> <b>Single Radial Seal XP Air</b> (Don. P542101)..... <b>RS3750XP</b> <b>Cab Air</b> (525507)..... <b>PA5306</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-SP System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Coolant</b> (299080)..... <b>BW5071</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>
T2000 w/Cummins ISB (5.9L) Eng. <b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b> <b>Lube</b> (4897898)..... <b>BT7237</b> <b>Fuel</b> (Fleetguard FF5632)..... <b>BF7940</b> <b>Trans. Spin-on</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	T2000 w/Cummins ISL Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b> <b>Fuel</b> (Fleetguard FF5636)..... <b>BF7924</b> <b>Radial Seal XP Air</b> (Don. EAF5107)..... <b>RS3750XP</b> <b>Cab Air</b> (525507)..... <b>PA5306</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	T2000 w/Detroit Series 60 Eng. <b>Lube</b> (23527033)..... <b>[2] B495</b> <b>Fuel/Water Separator Ele.</b> (23521528)..... <b>PF7744</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1000)..... <b>BF1259</b> <b>S. Fuel</b> (23518482)..... <b>BF5810</b> <b>5 13/16 In I.D. Radial Seal Air</b> (Don. P536142)..... <b>RS3548</b>
T2000 w/Cummins ISM 10.8 (10.8L) Eng. (To 2006) <b>Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154 +</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (Fleetguard FS1000)..... <b>BF1259</b> <b>Radial Seal XP Air</b> (Don. EAF5107)..... <b>RS3750XP</b> <b>Cab Air</b> (525507)..... <b>PA5306</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b>	T2000 w/Cummins ISX 15.0 (14.9L) Eng. (2007-on) <b>11 13/16 In. Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154 +</b> <b>14 7/32 In. Dual-Flow Lube</b> ..... <b>BD7153 +</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19729)..... <b>PF7755</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1007)..... <b>BF1274-SP</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1040)..... <b>BF1277-SPS</b> <b>Fuel</b> (Fleetguard FF2200)..... <b>BF7766</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)
T2000 w/Detroit Series 60 Eng. (Cont'd)	W900 w/Cat C10 (10.3L) Eng. (Cont'd)	W900 w/Cat C12 (12.0L) Eng. (1/2004-on) (Cont'd)
5 13/16 In I.D. Radial Seal XP Air (Don. P536142).....	Fuel (High Efficiency Vers.) (1R0749).....	Air Dryer (Bendix 5008414).....
RS3548XP	BF7587 +	BA5374 +
6 25/32 In. I.D. Radial Seal Air (Don. P542101).....	Trans. Spin-on (Fuller 4304827)..	Coolant.....
RS3750	BT223	B5088 +
6 25/32 In. I.D. Radial Seal XP Air (Don. P542101).....	Opt. Trans. Spin-on (Fuller 17237).....	Opt. Trans. (Fuller 17237).....
RS3750XP	B2 +	B2 +
Cab Air (525507).....	W900 w/Cat C11 (11.1L) Eng.	Steering (Nelson 87904M).....
PA5306	Lube (1R1808).....	PT9354-MPG
Air Dryer (AD-SP System) (Bendix 5008414).....	Fuel/Water Separator (3329289).....	W900 w/Cat C13 (12.5L) Eng. (To 1/2004)
BA5374 +	BF1259	F-F Lube.....
Air Dryer (AD-IP System) (Bendix 65624).....	Fuel (Standard Vers.) (4N5823)...	B99 +
BA5373	BF614 +	F-F Lube (249-2347).....
Opt. Trans. (Fuller 17237).....	Fuel (High Efficiency Vers.) (1R0749).....	[2] B7402
B2 +	BF7587 +	Fuel/Water Separator Ele. (Davco 380087).....
Steering (Nelson 83804E).....	BF7753	PF7680
P528	[2] RS3539	Fuel/Water Separator Spin-on (280-2700).....
T2000 w/Paccar MX Eng.	Radial Seal Air (Don. P534816)...	BF1259
Fuel/Water Separator (Fleetguard FS1000).....	Radial Seal XP Air (Don. P534816).....	BF7587 +
BF1259	[2] RS3539XP	Radial Seal Air (Don. P534816)...
T6600 w/Cummins ISX Eng.	Radial Seal Air (Don. P534925)...	[2] RS3539XP
Dual-Flow Lube (Fleetguard LF9001).....	Radial Seal XP Air (Standard Gasket) (Don. P625128).....	RS3534
BD7154 +	RS5287XP	Opt. Cab Air (Cab Fresh R19501).....
Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN).....	Radial Seal XP Air (Premium Housing Gasket) (Don. P625128)...	PA30287
BD50000	RS30187XP	Air Dryer (Bendix 5008414).....
P. Fuel Strainer (Fleetguard FF2203).....	Std. Radial Seal XP Air (P625287).....	BA5374 +
BF7760	RS5288	Opt. Trans. (Fuller 17237).....
S. Fuel (Fleetguard FF2200).....	Radial Seal XP Air (Don. P625287).....	B2 +
BF7766	RS5288XP	Trans. (Fuller 4304827).....
Air (2400 Series Hsg.) (Don. P154575).....	Std. Radial Seal Air (Don. P625128).....	BT223
PA2715	RS5287	2 23/32 In. Steering (Nelson 87904M).....
Air (2500 Series Hsg.) (Don. P537791).....	Air Dryer.....	PT9354-MPG
PA2705	BA5374 +	4 3/16 In. Steering (Nelson 83804E).....
Breather (1/07-on) (3683918).....	Trans. (Fuller 4304827).....	P528
CV15000	BT223	W900 w/Cat C13 (12.5L) Eng. (1/2004-on)
W900 w/Allis Chalmers 21000, 25000 Eng.	Opt. Trans. Spin-on (Fuller 17237).....	F-F Lube (1R1808).....
F-F Lube Ele. (4052172).....	B2 +	B7299 +
P20-HD +	P528	F-F Lube (249-2347).....
S. Fuel Ele. (4052172).....	Steering (White 3105264).....	[2] B7402
PF910	P528	Fuel/Water Separator Ele. (Davco 380087).....
Air (Don. P117331).....	Steering (Nelson 87904M).....	PF7680
PA1637-FN	PT9354-MPG	Fuel/Water Separator Spin-on (280-2700).....
Air (Don. P116918).....	W900 w/Cat C12 (12.0L) Eng. (To 1/2004)	BF1259
PA2317 +	Lube (1R0716).....	BF7587 +
W900 w/Cat C7 (7.2L) Eng.	Opt. Fuel/Water Separator (Fleetguard FS1000).....	Radial Seal Air (Don. P534816)...
Lube (1R1808).....	BF1259	[2] RS3539
B7299 +	Fuel Spin-on (1R0749).....	Radial Seal XP Air (Don. P534816).....
Fuel (1R0751).....	BF7587 +	[2] RS3539XP
BF7632	PA2705	Radial Seal Air (Don. P534925)...
Air (Don. P153551).....	Axial Seal Air (Don. P154575).....	RS3534
PA2705	PA2715	Opt. Cab Air (Cab Fresh R19501).....
Air Dryer (Bendix 5008414).....	Radial Seal Air (Don. P542101)...	PA30287
BA5374 +	Radial Seal XP Air (Don. P542101).....	Air Dryer (Bendix 5008414).....
Opt. Trans. (Fuller 17237).....	RS3750XP	BA5374 +
B2 +	[2] RS3534	Breather (296-8325).....
Steering (Nelson 870678A).....	Radial Seal Air (Don. P534925)...	CV15008
PT9394-MPG	BA5374 +	Opt. Trans. (Fuller 17237).....
W900 w/Cat C9 (8.8L) Eng.	Coolant.....	B2 +
Lube (1R1808).....	Opt. Trans. (Fuller 17237).....	BT223
B7299 +	B2 +	2 23/32 In. Steering (Nelson 87904M).....
Fuel/Water Separator (Fleetguard FS1000).....	Steering (Nelson 87904M).....	PT9354-MPG
BF1259	PT9354-MPG	4 3/16 In. Steering (Nelson 83804E).....
Fuel (1R0751).....	W900 w/Cat C12 (12.0L) Eng. (1/2004-on)	P528
BF7632	Lube (1R1808).....	W900 w/Cat C15 (14.6L) Eng. (To 1/2004)
Air (Don. P153551).....	Opt. Fuel/Water Separator (Fleetguard FS1000).....	F-F Lube.....
PA2705	BF1259	B99 +
Opt. Trans. (Fuller 17237).....	Fuel Spin-on (1R0749).....	Fuel/Water Separator Ele. (Don. P550463).....
B2 +	BF7587 +	PF7680
Steering (Nelson 870678A).....	Axial Seal Air (Don. P153551).....	Fuel/Water Separator Spin-on (256-8753).....
PT9394-MPG	PA2705	BF1259
W900 w/Cat C10 (10.3L) Eng.	Axial Seal Air (Don. P154575).....	Fuel/Water Separator Spin-on (1752949).....
F-F Lube (Std. Version) (1R0716).....	Radial Seal Air (Don. P542101)...	BF1268
B99 +	Radial Seal XP Air (Don. P542101).....	Fuel (1R0749).....
F-F Lube (High Efficiency Vers.) (1R1808).....	RS3750XP	BF7587 +
B7299 +	[2] RS3534	Axial Seal Air (Don. P153551).....
B-P Lube (1W8845).....		PA2705
B7577		
Fuel (Standard Vers.) (1R1712)...		
BF614 +		

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)
W900 w/Cat C15 (14.6L) Eng. (To 1/2004) (Cont'd) <b>Axial Seal Air</b> (Don. P154575)..... <b>PA2715</b> <b>Radial Seal Air</b> (Don. P534925).... <b>[2] RS3534</b> <b>Radial Seal Air</b> (Don. P534816).... <b>[2] RS3539</b> <b>Radial Seal XP Air</b> (Don. P534816)..... <b>[2] RS3539XP</b> <b>Channel Flow Air</b> (P611696)..... <b>CA5500</b> <b>Opt. Cab Air</b> (Cab Fresh R19501)..... <b>PA30287</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Coolant</b> (9N3368)..... <b>BW5137</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>2 23/32 In. Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>4 3/16 In. Steering</b> (Nelson 83804E)..... <b>P528</b>	W900 w/Cat C16 (15.8L) Eng. (To 1/2004) (Cont'd) <b>Radial Seal XP Air</b> (Standard Gasket) (Don. P625128)..... <b>RS5287XP</b> <b>Radial Seal XP Air</b> (Premium Housing Gasket) (Don. P625128). <b>RS30187XP</b> <b>Std. Radial Seal XP Air</b> (P625287)..... <b>RS5288</b> <b>Radial Seal XP Air</b> (Don. P625287)..... <b>RS5288XP</b> <b>Std. Radial Seal Air</b> (Don. P625128)..... <b>RS5287</b> <b>Radial Seal Air</b> (Don. P542101).... <b>RS3750</b> <b>Radial Seal XP Air</b> (Don. P542101)..... <b>RS3750XP</b> <b>Air Dryer</b> ..... <b>BA5374 +</b> <b>Trans. Ele. (2 In. Kit)</b> (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele. (4 In. Kit)</b> (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	W900 w/Cat 1673C, 1674 Engs. <b>Lube Ele.</b> ..... <b>PT670</b> <b>Box-Style Fuel/Water Separator.</b> <b>BF912</b> <b>Fuel Spin-on</b> ..... <b>BF970 +</b> <b>Air</b> (Don. P117797)..... <b>PA2312</b> <b>Air</b> (Don. P117331)..... <b>PA1637-FN</b> <b>Air Comp. Breather</b> ..... <b>PA1704</b> W900 w/Cat 1693T, 1693TA Engs. <b>Lube Ele.</b> ..... <b>[2] PT88-HD</b> <b>Lube Spin-on</b> ..... <b>B99 +</b> <b>Fuel Ele.</b> ..... <b>[2] PF823 +</b> <b>Fuel Spin-on</b> ..... <b>[2] BF970 +</b> <b>Air</b> (Don. P116918)..... <b>PA2317 +</b> <b>Air</b> (Don. P117331)..... <b>PA1637-FN</b> <b>Air</b> (Don. P117332)..... <b>PA1676-FN +</b> <b>Air</b> (Don. P117797)..... <b>PA2312</b> <b>Air Comp. Breather</b> ..... <b>PA1704</b>
W900 w/Cat C15 (14.6L) Eng. (1/2004-on) <b>F-F Lube</b> (1R1808)..... <b>B7299 +</b> <b>Fuel/Water Separator Ele.</b> (Don. P550463)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> (256-8753)..... <b>BF1259</b> <b>Fuel/Water Separator Spin-on</b> (1752949)..... <b>BF1268</b> <b>Fuel</b> (1R0749)..... <b>BF7587 +</b> <b>Axial Seal Air</b> (Don. P153551)..... <b>PA2705</b> <b>Axial Seal Air</b> (Don. P154575)..... <b>PA2715</b> <b>Radial Seal Air</b> (Don. P534925).... <b>[2] RS3534</b> <b>Radial Seal Air</b> (Don. P534816).... <b>[2] RS3539</b> <b>Radial Seal XP Air</b> (Don. P534816)..... <b>[2] RS3539XP</b> <b>Channel Flow Air</b> (P611696)..... <b>CA5500</b> <b>Opt. Cab Air</b> (Cab Fresh R19501)..... <b>PA30287</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Breather</b> (296-8325)..... <b>CV15008</b> <b>Coolant</b> (9N3368)..... <b>BW5137</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>2 23/32 In. Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>4 3/16 In. Steering</b> (Nelson 83804E)..... <b>P528</b>	W900 w/Cat C16 (15.8L) Eng. (1/2004-on) <b>Lube</b> (1R1808)..... <b>B7299 +</b> <b>Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (Standard Vers.) (4N5823)..... <b>BF614 +</b> <b>Fuel Spin-on</b> (High Efficiency Vers.) (1R0749)..... <b>BF7587 +</b> <b>Axial Seal Air</b> (Vortex VF160R).... <b>[2] PA2608 +</b> <b>Axial Seal Air</b> (Don. P153551)..... <b>PA2705</b> <b>Axial Seal Air</b> (Don. P154575).... <b>PA2715</b> <b>Radial Seal Air</b> (Don. P534925).... <b>[2] RS3534</b> <b>Radial Seal XP Air</b> (Standard Gasket) (Don. P625128)..... <b>RS5287XP</b> <b>Radial Seal XP Air</b> (Premium Housing Gasket) (Don. P625128). <b>RS30187XP</b> <b>Std. Radial Seal XP Air</b> (P625287)..... <b>RS5288</b> <b>Radial Seal XP Air</b> (Don. P625287)..... <b>RS5288XP</b> <b>Std. Radial Seal Air</b> (Don. P625128).... <b>RS5287</b> <b>Radial Seal Air</b> (Don. P542101).... <b>RS3750</b> <b>Radial Seal XP Air</b> (Don. P542101)..... <b>RS3750XP</b> <b>Air Dryer</b> ..... <b>BA5374 +</b> <b>Trans. Ele. (2 In. Kit)</b> (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele. (4 In. Kit)</b> (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	W900 w/Cat 3126 (7.2L) Eng. <b>Lube</b> (Standard Vers.) (1R0739).. <b>B76 +</b> <b>Lube</b> (Severe Service) (1R0739).. <b>B76-SS +</b> <b>Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (1R0751)..... <b>BF7632</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> W900 w/Cat 3176 (10.3L) Eng. <b>F-F Lube</b> (Std. Efficiency) (1R0716)..... <b>B99 +</b> <b>F-F Eng. Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> <b>F-F Eng. Lube</b> (1R0713)..... <b>[2] BT230 +</b> <b>F-F Lube</b> (1R0714)..... <b>[2] B75</b> <b>Opt. B-P Lube</b> (1W8845)..... <b>B7577</b> <b>P. Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>P. Fuel Spin-on</b> (1R0740)..... <b>BF970 +</b> <b>S. Fuel Spin-on</b> (1R0750)..... <b>BF7633 +</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
W900 w/Cat C16 (15.8L) Eng. (To 1/2004) <b>Lube</b> (1R0716)..... <b>B99 +</b> <b>Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (Standard Vers.) (4N5823)..... <b>BF614 +</b> <b>Fuel Spin-on</b> (High Efficiency Vers.) (1R0749)..... <b>BF7587 +</b> <b>Axial Seal Air</b> (Vortex VF160R).... <b>[2] PA2608 +</b> <b>Axial Seal Air</b> (Don. P153551)..... <b>PA2705</b> <b>Axial Seal Air</b> (Don. P154575).... <b>PA2715</b> <b>Radial Seal Air</b> (Don. P534925).... <b>[2] RS3534</b>	W900 w/Cat 3176 (10.3L) Eng. <b>F-F Lube</b> (Std. Efficiency) (1R0716)..... <b>B99 +</b> <b>F-F Eng. Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> <b>F-F Eng. Lube</b> (1R0713)..... <b>[2] BT230 +</b> <b>F-F Lube</b> (1R0714)..... <b>[2] B75</b> <b>Opt. B-P Lube</b> (1W8845)..... <b>B7577</b> <b>P. Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>P. Fuel Spin-on</b> (1R0740)..... <b>BF970 +</b> <b>S. Fuel Spin-on</b> (1R0750)..... <b>BF7633 +</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	W900 w/Cat 3208 (10.4L) Eng. <b>Lube</b> (1R0713)..... <b>[2] BT230 +</b> <b>Lube</b> (1R0714)..... <b>[2] B75</b> <b>Lube</b> (9L9200)..... <b>[2] BT364</b> <b>Box-Style Fuel/Water Separator</b> (8N9803)..... <b>BF912</b> <b>P. Fuel Ele.</b> (9M2341)..... <b>PF935</b> <b>P. Fuel Spin-on</b> (1R0740)..... <b>BF970 +</b> <b>S. Fuel Spin-on</b> (1R0750)..... <b>BF7633 +</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
		W900 w/Cat 3306 Eng. <b>Lube</b> (Standard Vers.) (1R0739).. <b>B76</b> <b>Box-Style Fuel/Water Separator.</b> <b>BF912</b> <b>Fuel Spin-on</b> (1R0740)..... <b>BF970 +</b> <b>Air</b> (Don. P181000)..... <b>PA1637-FN</b> <b>Air</b> (Don. P181003)..... <b>PA2482</b> <b>Air</b> (Don. P181007)..... <b>PA2312</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)
W900 w/Cat 3406 (14.6L) Eng. <b>Lube</b> ..... <b>B99 +</b> <b>Opt. Fuel/Water Separator</b> ..... <b>BF1259</b> <b>Fuel/Water Separator (w/Drain)</b> (Racor S3226P)..... <b>BF1346</b> <b>Fuel/Water Separator (w/Sensor Port)</b> (Racor S3226P)..... <b>BF1346-SP</b> <b>Fuel/Water Separator (Open End for Bowl)</b> (Racor S3226P)..... <b>BF1346-O</b> <b>Fuel Spin-on</b> ..... <b>BF614 +</b> <b>Fuel (1R0749)</b> ..... <b>BF7587 +</b> <b>Air (Don. P181000)</b> ..... <b>PA1637-FN</b> <b>Air (Don. P181001)</b> ..... <b>PA1676-FN +</b> <b>Air (Don. P181003)</b> ..... <b>PA2482</b> <b>Air (Don. P181007)</b> ..... <b>PA2312</b> <b>Air (Don. P181008)</b> ..... <b>PA2317 +</b> <b>Radial Seal Air (Don. P534925)</b> ... <b>[2] RS3534</b> <b>Air Dryer (AD-IP System)</b> (Bendix 65624)..... <b>BA5373</b> <b>Air Dryer (AD-9 System)</b> (Bendix 107796)..... <b>BA5377</b> <b>Coolant Spin-on</b> ..... <b>BW5137</b> <b>Opt. Trans. (Fuller 17237)</b> ..... <b>B2 +</b> <b>Trans. (Fuller 4304827)</b> ..... <b>BT223</b>	W900 w/Cummins ISC 8.3 (8.3L) Eng. (Cont'd) <b>Coolant (w/12 Units BTA+)</b> (Fleetguard WF2074)..... <b>BW5074</b> <b>Coolant (w/23 Units BTA+)</b> (Fleetguard WF2076)..... <b>BW5076</b> <b>Coolant (w/Controlled Release)</b> (Fleetguard WF2121)..... <b>BW5250</b> <b>Trans. Spin-on (Fuller 4304827)</b> .. <b>BT223</b> <b>Opt. Trans. Spin-on (Fuller 17237)</b> ..... <b>B2 +</b> W900 w/Cummins ISL Eng. <b>Dual-Flow Lube (Fleetguard LF9009)</b> ..... <b>BD7309 +</b> <b>Fuel/Water Separator (Fleetguard FS1065)</b> ..... <b>BF1378-SPS</b> <b>Fuel (Fleetguard FF5636)</b> ..... <b>BF7924</b> <b>Radial Seal Air (Don. P534816)</b> ... <b>[2] RS3539</b> <b>Radial Seal XP Air (Don. P534816)</b> ..... <b>[2] RS3539XP</b> <b>Channel Flow Air (P611696)</b> ..... <b>CA5500</b> <b>Air Dryer (Bendix 5008414)</b> ..... <b>BA5374 +</b> <b>Coolant (Fleetguard WF2071)</b> ..... <b>BW5071</b> <b>Trans. (Fuller 4304827)</b> ..... <b>BT223</b> <b>Opt. Trans. (Fuller 17237)</b> ..... <b>B2 +</b> <b>2 23/32 In. Steering (Nelson 87904M)</b> ..... <b>PT9354-MPG</b> <b>4 3/16 In. Steering (Nelson 83804E)</b> ..... <b>P528</b> W900 w/Cummins ISL-G Eng. <b>Dual-Flow Lube (3401544)</b> ..... <b>BD7309 +</b> <b>Lube (Upgrade) (3401544)</b> ..... <b>B40142 +</b> <b>Coalescer Fuel (Fleetguard NG5900)</b> ..... <b>BF7695</b> <b>Channel Flow Air (Don. P616056)</b> ..... <b>CA5500</b> <b>Air Dryer (Wabco R950011)</b> ..... <b>BA5374 +</b> <b>Trans. (2 In. Kit) (Allison 29545776)</b> ..... <b>PT9416-MPG KIT</b> <b>Trans. (4 In. Kit) (Allison 29545779)</b> ..... <b>PT9415-MPG KIT</b> <b>Steering (Nelson 87904A)</b> ..... <b>PT9354-MPG</b>	W900 w/Cummins ISM 10.8 (10.8L) Eng. (To 2006) (Cont'd) <b>Opt. Cab Air (Cab Fresh R19501)</b> ..... <b>PA30287</b> <b>Air Dryer (AD-IS System)</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Coolant (Fleetguard WF2071)</b> ..... <b>BW5071</b> <b>Trans. Ele. (2 In. Kit) (Allison 29540493)</b> ..... <b>PT9416-MPG KIT</b> <b>Trans. Ele. (4 In. Kit) (Allison 29540494)</b> ..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on (Fuller 4304827)</b> .. <b>BT223</b> <b>Opt. Trans. Spin-on (Fuller 17237)</b> ..... <b>B2 +</b> <b>2 23/32 In. Steering (Nelson 87904M)</b> ..... <b>PT9354-MPG</b> <b>4 3/16 In. Steering (Nelson 83804E)</b> ..... <b>P528</b> W900 w/Cummins ISM 10.8 (10.8L) Eng. (2007-on) <b>Dual-Flow Lube (Fleetguard LF9001)</b> ..... <b>BD7154 +</b> <b>Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)</b> ..... <b>BD50000</b> <b>Fuel/Water Separator Ele. (Fleetguard FS19727)</b> ..... <b>PF7895</b> <b>Fuel/Water Separator Ele. (Fleetguard FS1029W)</b> ..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on (Fleetguard FS1000)</b> ..... <b>BF1259</b> <b>Axial Seal Air (Don. P537791)</b> ..... <b>PA2705</b> <b>Radial Seal Air (Don. P534816)</b> ... <b>[2] RS3539</b> <b>Radial Seal XP Air (Don. P534816)</b> ..... <b>[2] RS3539XP</b> <b>Radial Seal Air (Don. P534925)</b> ... <b>RS3534</b> <b>Channel Flow Air (P611696)</b> ..... <b>CA5500</b> <b>Opt. Cab Air (Cab Fresh R19501)</b> ..... <b>PA30287</b> <b>Air Dryer (AD-IS System)</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Breather (3683918)</b> ..... <b>CV15000</b> <b>Coolant (Fleetguard WF2071)</b> ..... <b>BW5071</b> <b>Trans. Ele. (2 In. Kit) (Allison 29540493)</b> ..... <b>PT9416-MPG KIT</b> <b>Trans. Ele. (4 In. Kit) (Allison 29540494)</b> ..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on (Fuller 4304827)</b> .. <b>BT223</b> <b>Opt. Trans. Spin-on (Fuller 17237)</b> ..... <b>B2 +</b> <b>2 23/32 In. Steering (Nelson 87904M)</b> ..... <b>PT9354-MPG</b> <b>4 3/16 In. Steering (Nelson 83804E)</b> ..... <b>P528</b> W900 w/Cummins ISX 11.9 (11.9L) Eng. (2012-18) <b>Dual-Flow Lube (Fleetguard LF9001)</b> ..... <b>BD7154 +</b> <b>Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)</b> ..... <b>BD50000</b>
W900 w/Cummins 6BT5.9 (5.9L) Eng. <b>Lube (3914395)</b> ..... <b>BT339 +</b> <b>Lube (Chrysler 5083285AA)</b> ..... <b>BT7349</b> <b>Fuel/Water Separator (3925274)</b> .. <b>BF1280 +</b> <b>Fuel (3903640)</b> ..... <b>BF788</b> <b>Trans. Spin-on (Fuller 4304827)</b> .. <b>BT223</b> <b>Opt. Trans. Spin-on (Fuller 17237)</b> ..... <b>B2 +</b>	W900 w/Cummins ISL-G Eng. <b>F-F Lube (3313281)</b> ..... <b>B205 +</b> <b>Dual-Flow Lube (3318853)</b> ..... <b>BD103 +</b> <b>Fuel/Water Separator (3925274)</b> .. <b>BF1280 +</b> <b>Fuel (3903640)</b> ..... <b>BF788</b> <b>Trans. Spin-on (Fuller 4304827)</b> .. <b>BT223</b> <b>Opt. Trans. Spin-on (Fuller 17237)</b> ..... <b>B2 +</b>	
W900 w/Cummins 6CT8.3 (8.3L) Eng. <b>F-F Lube (3313281)</b> ..... <b>B205 +</b> <b>Dual-Flow Lube (3318853)</b> ..... <b>BD103 +</b> <b>Fuel/Water Separator (3925274)</b> .. <b>BF1280 +</b> <b>Fuel (3903640)</b> ..... <b>BF788</b> <b>Trans. Spin-on (Fuller 4304827)</b> .. <b>BT223</b> <b>Opt. Trans. Spin-on (Fuller 17237)</b> ..... <b>B2 +</b>	W900 w/Cummins ISL-G Eng. <b>F-F Lube (3313281)</b> ..... <b>B205 +</b> <b>Dual-Flow Lube (3318853)</b> ..... <b>BD103 +</b> <b>Fuel/Water Separator (3925274)</b> .. <b>BF1280 +</b> <b>Fuel (3903640)</b> ..... <b>BF788</b> <b>Trans. Spin-on (Fuller 4304827)</b> .. <b>BT223</b> <b>Opt. Trans. Spin-on (Fuller 17237)</b> ..... <b>B2 +</b>	
W900 w/Cummins ISB (5.9L) Eng. <b>Lube (Fleetguard LF3970)</b> ..... <b>B7177</b> <b>Lube (4897898)</b> ..... <b>BT7237</b> <b>Fuel (Fleetguard FF5632)</b> ..... <b>BF7940</b> <b>Air Dryer</b> ..... <b>BA5374 +</b> <b>Trans. Spin-on (Fuller 4304827)</b> .. <b>BT223</b> <b>Opt. Trans. Spin-on (Fuller 17237)</b> ..... <b>B2 +</b>	W900 w/Cummins ISM 10.8 (10.8L) Eng. (To 2006) <b>Dual-Flow Lube (Fleetguard LF9001)</b> ..... <b>BD7154 +</b> <b>Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)</b> ..... <b>BD50000</b> <b>Fuel/Water Separator Ele. (Fleetguard FS19727)</b> ..... <b>PF7895</b> <b>Fuel/Water Separator Ele. (Fleetguard FS1029W)</b> ..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on (Fleetguard FS1000)</b> ..... <b>BF1259</b> <b>Axial Seal Air (Don. P537791)</b> ..... <b>PA2705</b> <b>Radial Seal Air (Don. P534816)</b> ... <b>[2] RS3539</b> <b>Radial Seal XP Air (Don. P534816)</b> ..... <b>[2] RS3539XP</b> <b>Radial Seal Air (Don. P534925)</b> ... <b>RS3534</b> <b>Channel Flow Air (P611696)</b> ..... <b>CA5500</b>	
W900 w/Cummins ISC 8.3 (8.3L) Eng. <b>Dual-Flow Lube (Fleetguard LF9009)</b> ..... <b>BD7309 +</b> <b>Dual-Flow Lube (Fleetguard LF9548)</b> ..... <b>BD324 +</b> <b>Fuel (Fleetguard FF5488)</b> ..... <b>BF7815</b> <b>Fuel (Fleetguard FF5636)</b> ..... <b>BF7924</b> <b>Coolant (w/4 Units BTA+)</b> (Fleetguard WF2071)..... <b>BW5071</b>	W900 w/Cummins ISM 10.8 (10.8L) Eng. (To 2006) <b>Dual-Flow Lube (Fleetguard LF9001)</b> ..... <b>BD7154 +</b> <b>Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)</b> ..... <b>BD50000</b> <b>Fuel/Water Separator Ele. (Fleetguard FS19727)</b> ..... <b>PF7895</b> <b>Fuel/Water Separator Ele. (Fleetguard FS1029W)</b> ..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on (Fleetguard FS1000)</b> ..... <b>BF1259</b> <b>Axial Seal Air (Don. P537791)</b> ..... <b>PA2705</b> <b>Radial Seal Air (Don. P534816)</b> ... <b>[2] RS3539</b> <b>Radial Seal XP Air (Don. P534816)</b> ..... <b>[2] RS3539XP</b> <b>Radial Seal Air (Don. P534925)</b> ... <b>RS3534</b> <b>Channel Flow Air (P611696)</b> ..... <b>CA5500</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)
W900 w/Cummins ISX 11.9 (11.9L) Eng. (2012-18) (Cont'd)	W900 w/Cummins ISX 11.9 (11.9L) Eng. (2019)	W900 w/Cummins ISX 15.0 (14.9L) Eng. (1999-2017) (Cont'd)
Dual-Flow Lube (Fleetguard LF9031).....	Dual-Flow Lube (4367100).....	22 29/32 In. Std. Radial Seal Air (P614986).....
BD7509 +	BD50000	[2] RS5288
Fuel/Water Separator Ele. (Fleetguard FS1029W).....	Fuel (2893612).....	22 29/32 In. Radial Seal XP Air (Paccar P614986).....
PF7680	BF9885 +	[2] RS5288XP
Fuel/Water Separator Ele. (Fleetguard FS19729).....	Std. Radial Seal Air (X011622)...	Opt. Cab Air (Cab Fresh R19501).....
PF7755	[2] RS5287	PA30287
Fuel/Water Separator Ele. (Fleetguard FS19765).....	Radial Seal XP Air (X011622)....	Air Dryer (AD-IS System) (Bendix 5008414).....
PF7930	[2] RS5287XP	BA5374 +
Fuel/Water Separator Spin-on (Fleetguard FS1040).....	Opt. Cab Air (CF19501).....	CV15000
BF1277-SPS	PA30287	
Fuel/Water Separator Spin-on (Fleetguard FS1212).....	Air Dryer (Bendix 5008414).....	Breather (4312013).....
BF1212 +	PT9354-MPG	Coolant (w/11 1/2 Units BTA+) (Fleetguard WF2126).....
Fuel/Water Separator Spin-on (Fleetguard FS1000).....	Opt. Rear Axle (Meritor 3280V8394).....	BW5086
BF1259	B233	Coolant (w/o Chemical) (Fleetguard WF2127).....
Fuel/Water Separator (K371004) PF9928	W900 w/Cummins ISX 15.0 (14.9L) Eng. (1999-2017)	Trans. Ele. (2 In. Kit) (Allison 29540493).....
P. Fuel (Pre-2010 Emissions) (Fleetguard FF2203).....	Dual-Flow Lube (Fleetguard LF9001).....	PT9416-MPG KIT
BF7760	BD7154 +	Trans. Ele. (4 In. Kit) (Allison 29540494).....
S. Fuel (Pre-2010 Emissions) (Fleetguard FF2200).....	Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN).....	PT9415-MPG KIT
BF7766	BD50000	BT223
Fuel (2010 Emissions) (Fleetguard FF5686).....	Dual-Flow Lube (Fleetguard LF9031).....	B2 +
BF9860 +	BD7509 +	2 23/32 In. Steering (Nelson 87904M).....
Fuel (2010 Emissions) (Fleetguard FF5776).....	Fuel/Water Separator Ele. (Fleetguard FS1029W).....	PT9354-MPG
BF9885 +	PF7680	4 3/16 In. Steering (Nelson 83804E).....
Fuel (Upgrade) (Fleetguard FF5825NN).....	Fuel/Water Separator Ele. (Fleetguard FS19729).....	P528
BF46129	PF7755	Diesel Exhaust Fluid (2010 Emissions) (5303604).....
Single Radial Seal Air (Don. P534925).....	Fuel/Water Separator Ele. (Fleetguard FS19764).....	PE17000
RS3534	PF9814	
23 13/16 In. Radial Seal Air (Don. P534816).....	Fuel/Water Separator Ele. (Fleetguard FS19765).....	W900 w/Cummins ISX 15.0 (14.9L) Eng. (2018)
[2] RS3539	PF7930	Dual-Flow Lube (4367100).....
23 13/16 In. Radial Seal XP Air (Don. EAF5100).....	Fuel/Water Separator Spin-on (Fleetguard FS1040).....	BD50000
[2] RS3539XP	BF1277-SPS	Fuel/Water Separator (K371029) PF46081
24 13/16 In. Std. Radial Seal Air (P614556).....	Fuel/Water Separator Spin-on (Fleetguard FS1212).....	Fuel (5365988).....
[2] RS5287	BF1212 +	BF46129
24 13/16 In. Radial Seal XP Air (P614556).....	Fuel/Water Separator Spin-on (Fleetguard FS1000).....	Std. Radial Seal Air (P614556)...
[2] RS5287XP	BF1259	[2] RS5287
25 13/16 In. Radial Seal Air (Don. P534925).....	Fuel/Water Separator (K371004) PF9928	Radial Seal O. XP Air (P614556)...
[2] RS3534	PF46081	[2] RS5287XP
Channel Flow Air (P611696).....	Fuel/Water Separator (K371011) PF46082	Air Dryer (Bendix 5008414).....
CA5500	PF46082	BA5374 +
22 29/32 In. Std. Radial Seal Air (P614986).....	P. Fuel (Pre-2010 Emissions) (Fleetguard FF2203).....	Opt. Trans. (Fuller 17237).....
[2] RS5288	BF7760	B2 +
22 29/32 In. Radial Seal XP Air (Paccar P614986).....	S. Fuel (Pre-2010 Emissions) (Fleetguard FF2200).....	BT223
[2] RS5288XP	BF7766	PT9354-MPG
Opt. Cab Air (Cab Fresh R19501).....	Fuel (2010 Emissions) (Fleetguard FF5686).....	PE17000
PA30287	BF9860 +	W900 w/Cummins ISX 15.0 (14.9L) Eng. (2019)
Air Dryer (AD-IS System) (Bendix 5008414).....	Fuel (2010 Emissions) (Fleetguard FF5776).....	Dual-Flow Lube (4367100).....
BA5374 +	BF9885 +	BD50000
Breather (4312013).....	Fuel (Upgrade) (Fleetguard FF5825NN).....	Fuel/Water Separator (Fleetguard FS19764G).....
CV15000	BF46129	PF46091
Coolant (w/11 1/2 Units BTA+) (Fleetguard WF2126).....	Single Radial Seal Air (Don. P534925).....	BF46129 +
BW5086	RS3534	Std. Radial Seal Air (X011622)...
Coolant (w/o Chemical) (Fleetguard WF2127).....	23 13/16 In. Radial Seal Air (Don. P534816).....	[2] RS5287
B5087	[2] RS3539XP	Radial Seal XP Air (X011622)....
BT223	[2] RS5287	[2] RS5287XP
Trans. (Fuller 4304827).....	24 13/16 In. Std. Radial Seal Air (P614556).....	Opt. Cab Air (CF19501).....
BT223	[2] RS5287	PA30287
Opt. Trans. (Fuller 17237).....	24 13/16 In. Radial Seal XP Air (P614556).....	Air Dryer (Bendix 5008414).....
B2 +	[2] RS5287XP	BA5374 +
2 23/32 In. Steering (Nelson 87904M).....	25 13/16 In. Radial Seal Air (Don. P534925).....	Trans. Ele. (2 In. Kit) (Allison 29540493).....
PT9354-MPG	[2] RS3534	PT9416-MPG KIT
4 3/16 In. Steering (Nelson 83804E).....	Channel Flow Air (P611696).....	Trans. Ele. (4 In. Kit) (Allison 29540494).....
P528	CA5500	PT9415-MPG KIT
Diesel Exhaust Fluid (5303604).....		BT223
PE17000		PT9354-MPG
		Opt. Rear Axle (Meritor 3280V8394).....
		B233

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)	KENWORTH Trucks (cont'd)
W900 w/Cummins ISX 15.0 (14.9L) Eng. (2020) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (Fleetguard FS19764G)..... <b>PF46091</b> <b>Fuel</b> (5365988)..... <b>BF46129</b> <b>Radial Seal Air</b> (X011622)..... <b>RS5287</b> <b>Radial Seal XP Air</b> (X011622).... <b>RS5287XP</b> <b>Cab Air</b> (TRP CFR19501)..... <b>PA30287</b> <b>Air Dryer</b> (Bendix 5008414PG).... <b>BA5379</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	W900 w/Cummins N14 Eng. (Cont'd) <b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b> <b>Coolant</b> (3315116)..... <b>BW5071</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2+</b>	W900 w/Detroit Diesel Series 50 (8.5L) Eng. <b>Lube</b> (23530573)..... [2] <b>B495</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (23535985)..... <b>BF5813+</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (23535985).. <b>BF5813-O+</b> <b>P. Fuel</b> (23530706)..... <b>BF5800+</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b>
W900 w/Cummins ISX 15.0 (14.9L) Eng. (2021) <b>Lube</b> (5575298)..... <b>B40145</b> <b>Fuel/Water Separator</b> (Fleetguard FS19764G)..... <b>PF46091</b> <b>Fuel</b> (5365988)..... <b>BF46129</b> <b>Radial Seal Air</b> (P614986)..... [2] <b>RS5288</b> <b>Radial Seal XP Air</b> (P614986).... [2] <b>RS5288XP</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	W900 w/Cummins VT903 (14.8L) Eng. <b>F-F Lube Ele.</b> (158139)..... <b>P999-HD</b> <b>F-F Lube Spin-on</b> (3313279)..... <b>B196+</b> <b>B-P Lube Ele.</b> (256838)..... <b>C750-E+</b> <b>B-P Lube Spin-on</b> (3313283)..... <b>B7577</b> <b>Fuel/Water Separator</b> (3308638). <b>BF1212+</b> <b>Fuel</b> (154789)..... <b>BF957-D+</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b>	W900 w/Detroit Diesel Series 60 (12.7L) Eng. <b>Lube</b> ..... [3] <b>B95+</b> <b>Lube</b> (23527033)..... [2] <b>B495</b> <b>Fuel/Water Separator</b> (23521528)..... <b>PF7744</b> <b>P. Fuel</b> ..... <b>BF5800+</b> <b>S. Fuel</b> (23518482)..... <b>BF5810</b> <b>11 3/8 In. O.D. Radial Seal Air</b> (Don. P534816)..... [2] <b>RS3539</b> <b>11 3/8 In. O.D. Radial Seal XP Air</b> (Don. EAF5100)..... [2] <b>RS3539XP</b> <b>13 3/32 In. O.D. Radial Seal Air</b> (Don. P534925)..... [2] <b>RS3534</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-SP System) (Bendix 5008414)..... <b>BA5374+</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2+</b>
W900 w/Cummins ISX 15.0 (14.9L) Eng. (2022) <b>Lube</b> (5575298)..... <b>B40145</b> <b>Fuel</b> (5575143)..... <b>BF46248</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	W900 w/Cummins X15 (14.9L) Eng. (2018) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (K371029) <b>PF46081</b> <b>Fuel</b> (5365988)..... <b>BF46129</b> <b>Std. Radial Seal Air</b> (P614556)... [2] <b>RS5287</b> <b>Radial Seal O. XP Air</b> (P614556). [2] <b>RS5287XP</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374+</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2+</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>	W900 w/Detroit Diesel 6V-92N (9.0L) Eng. <b>F-F Lube Ele.</b> ..... <b>P20-HD+</b> <b>F-F Lube Spin-on</b> ..... <b>B95+</b> <b>B-P Lube Ele.</b> (750 Size)..... <b>C750-E+</b> <b>P. Fuel Spin-on</b> ..... <b>BF5800+</b> <b>S. Fuel Spin-on</b> ..... <b>BF5810</b> <b>Air</b> (Don. P116918)..... <b>PA2317+</b> <b>Air</b> (Don. P117331)..... <b>PA1637-FN</b> <b>Air</b> (Don. P117332)..... <b>PA1676-FN+</b> <b>Air</b> (Don. P117797)..... <b>PA2312</b> <b>Air</b> (Don. P181003)..... <b>PA2482</b>
W900 w/Cummins ISX 15.0 (14.9L) Eng. (2023) <b>Lube</b> (5575298)..... <b>B40145</b> <b>Fuel/Water Separator</b> (Fleetguard FS19764G)..... <b>PF46091</b> <b>Fuel</b> (5575143)..... <b>BF46248</b>	W900 w/Cummins X15 (14.9L) Eng. (2019) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (Fleetguard FS19764G)..... <b>PF46091</b> <b>Fuel</b> (5365988)..... <b>BF46129+</b> <b>Std. Radial Seal Air</b> (X011622)... [2] <b>RS5287</b> <b>Radial Seal XP Air</b> (X011622).... [2] <b>RS5287XP</b> <b>Opt. Cab Air</b> (CF19501)..... <b>PA30287</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374+</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	W900 w/Detroit Diesel 8V-71 (9.3L) Eng. <b>F-F Lube Ele.</b> ..... <b>P20-HD+</b> <b>F-F Lube Spin-on</b> ..... <b>B95+</b> <b>B-P Lube Ele.</b> (750 Size)..... <b>C750-E+</b> <b>P. Fuel Spin-on</b> ..... <b>BF5800+</b> <b>S. Fuel Spin-on</b> ..... <b>BF5810</b> <b>Air</b> (Don. P116918)..... <b>PA2317+</b> <b>Air</b> (Don. P117331)..... <b>PA1637-FN</b> <b>Air</b> (Don. P117332)..... <b>PA1676-FN+</b> <b>Air</b> (Don. P117797)..... <b>PA2312</b> <b>Air</b> (Don. P181003)..... <b>PA2482</b>
W900 w/Cummins L10 (10.0L) Eng. <b>F-F Lube</b> ..... <b>B196+</b> <b>B-P Lube</b> ..... <b>B7577</b> <b>Dual-Flow Lube</b> ..... <b>BD103+</b> <b>Fuel/Water Separator</b> ..... <b>BF1212+</b> <b>Fuel Spin-on</b> ..... <b>BF957+</b> <b>Coolant</b> ..... <b>BW5071</b>	W900 w/Cummins X15 (14.9L) Eng. (2020) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (Fleetguard FS19764G)..... <b>PF46091</b> <b>Fuel</b> (5365988)..... <b>BF46129</b> <b>Radial Seal Air</b> (X011622)..... <b>RS5287</b> <b>Radial Seal XP Air</b> (X011622).... <b>RS5287XP</b> <b>Cab Air</b> (TRP CFR19501)..... <b>PA30287</b> <b>Air Dryer</b> (Bendix 5008414PG).... <b>BA5379</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	W900 w/Detroit Diesel 8V-92 (12.1L) Eng. <b>F-F Lube Ele.</b> ..... <b>P20-HD+</b> <b>F-F Lube Spin-on</b> ..... <b>B95+</b> <b>B-P Lube Ele.</b> (750 Size)..... <b>C750-E+</b> <b>P. Fuel Spin-on</b> ..... <b>BF5800+</b> <b>S. Fuel Spin-on</b> ..... <b>BF5810</b> <b>Air</b> (Don. P116918)..... <b>PA2317+</b> <b>Air</b> (Don. P117331)..... <b>PA1637-FN</b>
W900 w/Cummins M11 (10.8L) Eng. <b>Dual-Flow Lube</b> ..... <b>BD103+</b> <b>Fuel/Water Separator</b> ..... <b>BF1212+</b>	W900 w/Cummins N14 Eng. <b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196+</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103+</b> <b>Fuel/Water Separator</b> (Fleetguard FS1212)..... <b>BF1212+</b> <b>Fuel</b> (154789)..... <b>BF957-D+</b> <b>23 In. Std. Air</b> (KW852M)..... <b>LL2317+</b> <b>Air</b> (Vortex VF160R)..... [2] <b>PA2608+</b> <b>25 In. Std. Air</b> (Don. P521598).... [2] <b>PA2729</b> <b>Radial Seal Air</b> (Don. P534925)... [2] <b>RS3534</b>	W900 w/Detroit Diesel 8V-92 (12.1L) Eng. <b>F-F Lube Ele.</b> ..... <b>P20-HD+</b> <b>F-F Lube Spin-on</b> ..... <b>B95+</b> <b>B-P Lube Ele.</b> (750 Size)..... <b>C750-E+</b> <b>P. Fuel Spin-on</b> ..... <b>BF5800+</b> <b>S. Fuel Spin-on</b> ..... <b>BF5810</b> <b>Air</b> (Don. P116918)..... <b>PA2317+</b> <b>Air</b> (Don. P117331)..... <b>PA1637-FN</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>KENWORTH Trucks (cont'd)</b>	<b>KENWORTH Trucks (cont'd)</b>	<b>KENWORTH Trucks (cont'd)</b>
W900 w/Detroit Diesel 8V-92 (12.1L) Eng. (Cont'd)	W900 w/Paccar MX-11 (10.8L) Eng. (2019)	W900 w/Paccar MX-13 (12.9L) Eng. (2020)
Air (Don. P117332)..... PA1676-FN +	Lube Ele. (2129253PE)..... P40008	F-F Lube (2151728PE)..... P40069
Air (Don. P117797)..... PA2312	Centrifugal Lube (1928869PE)... BC40009	Centrifugal Lube (1922496PE)... BC40148
Air (Don. P181003)..... PA2482	Fuel (2133096PE)..... PF46106	Fuel (2133096PE)..... PF46106
W900 w/GMC 6V-53, 6-71, 6V-71 Series Eng.	Radial Seal Air (X011622)..... [2] RS5287	Radial Seal Air (X011622)..... RS5287
F-F Lube Ele..... P20-HD +	Radial Seal XP Air (X011622).... [2] RS5287XP	Radial Seal XP Air (X011622).... RS5287XP
F-F Lube Spin-on..... B95 +	Air Dryer (Bendix 5008414)..... BA5374	Cab Air (TRP CFR19501)..... PA30287
B-P Lube Ele. (750 Size)..... C750-E +	Coolant (1843659PE)..... B5088	Air Dryer (Bendix 5008414PG).... BA5379
P. Fuel Spin-on..... BF5800 +	Steering (Nelson 87904M)..... PT9354-MPG	Coolant (1843659PE)..... B5088
S. Fuel Spin-on..... BF5810	Opt. Rear Axle (Meritor 3280V8394)..... B233	Trans. (Fuller 4304827)..... BT223
Air (Don. P116918)..... PA2317 +	W900 w/Paccar MX-13 (12.9L) Eng. (2014-17)	Steering (Nelson 87904M)..... PT9354-MPG
Air (Don. P117331)..... PA1637-FN	Lube Ele. (1643070)..... P40019	Opt. Rear Axle (Meritor 3280V8394)..... B233
Air (Don. P117332)..... PA1676-FN +	Centrifugal Lube (1922496)..... BC40148	W900 w/Paccar MX-13 (12.9L) Eng. (2021)
Air (Don. P117797)..... PA2312	Fuel/Water Separator (K371009) PF9929	F-F Lube (2234788PE)..... P40069
Air (Don. P181003)..... PA2482	Fuel/Water Separator (Fleetguard FS19765)..... PF7930	Centrifugal Lube (1922496PE)... BC40148
W900 w/GMC 12V-71 Eng.	Fuel (1852006)..... PF46106	Fuel/Water Separator (K371022) PF46082
F-F Lube Ele..... [2] P20-HD +	Std. Radial Seal Air (P614556)... [2] RS5287	Fuel (2277129PE)..... PF46106
B-P Lube Ele. (750 Size)..... C750-E +	Radial Seal XP Air (P614556).... [2] RS5287XP	Radial Seal Air (P614986)..... RS5288
P. Fuel Spin-on..... BF5800 +	Std. Radial Seal Air (P614986)... [2] RS5288	Radial Seal XP Air (P614986).... RS5288XP
S. Fuel Spin-on..... BF5810	Radial Seal XP Air (Paccar P614986)..... [2] RS5288XP	Trans. (Meritor 4304827)..... BT223
Air (Don. P117331)..... [2] PA1637-FN	Opt. Cab Air (Cab Fresh R19501)..... PA30287	W921, W922, LW923, W923, LW924, W924, W925 w/Cummins Eng.
Air (Don. P117797)..... [2] PA2312	Air Dryer (Bendix 5008414)..... BA5374 +	F-F Lube Bag..... P996
W900 w/Paccar PX-9 (8.9L) Eng. (2014-18)	Coolant (1843659)..... B5088 +	F-F Lube Ele..... P999-HD
Dual-Flow Lube (Fleetguard LF9009)..... BD7309 +	Trans. (Fuller 4304827)..... BT223	F-F Lube Spin-on..... B196 +
Fuel (5303743)..... BF63000	Opt. Trans. (Fuller 17237)..... B2 +	B-P Lube Ele..... C750-E +
Std. Radial Seal Air (P614986)... [2] RS5288	Steering (Nelson 87904M)..... PT9354-MPG	Fuel/Water Separator..... BF1212 +
Radial Seal XP Air (P614986).... [2] RS5288XP	Diesel Exhaust Fluid (5303604).. PE17000	4 3/8 In. Fuel Spin-on..... BF948 +
Std. Radial Seal Air (P614556)... [2] RS5287	W900 w/Paccar MX-13 (12.9L) Eng. (2018)	5 3/4 In. Fuel Spin-on..... BF957 +
Radial Seal XP Air (P614556).... [2] RS5287XP +	Lube (2047411PE)..... P40069	11 7/32 In. Fuel Spin-on..... BF596 +
Air Dryer (Bendix 5008414)..... BA5374 +	Centrifugal Lube (1922496PE)... BC40148	Breather Ele. (w/Turbo) (255963) PA643
Trans. Spin-on (Fuller 4304827).. BT223	Fuel/Water Separator (K371012) PF46082	Breather Ele. (w/o Turbo) (256837)..... PA1627
Opt. Trans. Spin-on (Fuller 17237)..... B2 +	Fuel (1852006PE)..... PF46106	Turbocharger..... BT112
Steering (Nelson 87904M)..... PT9354-MPG	Std. Radial Seal Air (P614556)... [2] RS5287	W990 w/Cummins ISX 15.0 (14.9L) Eng. (2019)
W900 w/Paccar MX Eng.	Radial Seal XP Air (P614556).... [2] RS5287XP +	Dual-Flow Lube (4367100)..... BD50000
Lube (1643070)..... P40019	Air Dryer (Bendix 5008414)..... BA5374 +	Fuel/Water Separator (Fleetguard FS19764)..... PF9814
Lube Spinner (1643072)..... BC7326 +	Coolant (1843659PE)..... B5088 +	Fuel (5365988)..... BF46129
Fuel/Water Separator (K37-1005)..... PF9928	Trans. (Fuller 4304827)..... BT223	Cab Air (X1987001)..... [2] PA30093
Fuel (1655115)..... BF9927	Opt. Trans. (Fuller 17237)..... B2 +	Air Dryer (Bendix 5008414)..... BA5374 +
22 29/32 In. Std. Radial Seal Air (P614986)..... [2] RS5288	Steering (Nelson 87904M)..... PT9354-MPG	Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT
22 29/32 In. Radial Seal XP Air (Paccar P614986)..... [2] RS5288XP	Diesel Exhaust Fluid (5303604).. PE17000	Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT
24 13/16 In. Std. Radial Seal Air (P614556)..... RS5287	W900 w/Paccar MX-13 (12.9L) Eng. (2019)	Trans. Spin-on (Fuller 4304827).. BT223
24 13/16 In. Radial Seal XP Air (P614556)..... RS5287XP	F-F Lube (2047411PE)..... P40069	Opt. Trans. Spin-on (Fuller 17237)..... B2
25 13/16 In. Radial Seal Air (Don. P534925)..... [2] RS3534	Fuel/Water Separator (K371022) PF46237	W990 w/Cummins ISX 15.0 (14.9L) Eng. (2020)
Air Dryer (Bendix 5008414)..... BA5374 +	Std. Radial Seal Air (X011622)... [2] RS5287	Dual-Flow Lube (4367100)..... BD50000
Coolant (1843659)..... B5088 +	Radial Seal XP Air (X011622).... [2] RS5287XP	Fuel/Water Separator (Fleetguard FS19764G)..... PF46091
Trans. (Fuller 4304827)..... BT223	Opt. Cab Air (CF19501)..... PA30287	Fuel (5365988)..... BF46129
Opt. Trans. (Fuller 17237)..... B2 +	Air Dryer (Bendix 5008414)..... BA5374 +	EnduraCube Air (P621725)..... PA32000
Steering (Nelson 87904M)..... PT9354-MPG	Coolant (1843659PE)..... B5088 +	Cab Air (Fresh Air) (X1987001)... PA30093
Diesel Exhaust Fluid (5303604).. PE17000	Steering (Nelson 87904M)..... PT9354-MPG	Cab Air (HVAC) (F371018)..... PA30269
	Opt. Rear Axle (Meritor 3280V8394)..... B233	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



<b>KENWORTH Trucks (cont'd)</b>	<b>KENWORTH Trucks (cont'd)</b>	<b>KOOL-GEN Auxiliary Power Units (APU) (cont'd)</b>
W990 w/Cummins ISX 15.0 (14.9L) Eng. (2020) (Cont'd)	W990 w/Paccar MX-13 (12.9L) Eng. (2020) (Cont'd)	KG 1000 w/Yanmar 2TNV-70 Eng. (Cont'd)
Air Dryer (Bendix 5008414PG)..... <b>BA5379</b>	Coolant (1843659PE)..... <b>B5088</b>	Radial Seal Air (Don. P822686)... <b>RS3715</b>
Trans. (Fuller 4304827)..... <b>BT223</b>	Trans. (Fuller 4304827)..... <b>BT223</b>	KG 1000X w/Yanmar Eng.
Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	Lube (119305-35151)..... <b>B1400</b>
Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	Fuel/Water Separator (Racor R11T)..... <b>PF46009</b>
W990 w/Cummins ISX 15.0 (14.9L) Eng. (2021)	Diesel Exhaust Fluid (2122909PE)..... <b>PE17002 KIT</b>	Fuel (119810-55650)..... <b>PF981</b>
Lube (5575298)..... <b>B40145</b>	W990 w/Paccar MX-13 (12.9L) Eng. (2021)	Fuel (171081-55910)..... <b>PF7869</b>
Fuel/Water Separator (Fleetguard FS19764G)..... <b>PF46091</b>	F-F Lube (2234788PE)..... <b>P40069</b>	Radial Seal Air (Don. P822686)... <b>RS3715</b>
Fuel (5365988)..... <b>BF46129</b>	Centrifugal Lube (1922496PE)... <b>BC40148</b>	<b>LEYLAND Buses</b>
EnduraCube Air (P621725)..... <b>PA32000</b>	Fuel/Water Separator (Fleetguard FS19765G)..... <b>PF46094</b>	Fleetline w/Gardner 6LXB Eng.
Trans. (Fuller 4304827)..... <b>BT223</b>	Fuel/Water Separator (K371012) <b>PF46082</b>	Lube Ele..... <b>P352</b>
W990 w/Cummins ISX 15.0 (14.9L) Eng. (2022)	Fuel (2277129PE)..... <b>PF46106</b>	P. Fuel..... <b>PF831</b>
Lube (5575298)..... <b>B40145</b>	EnduraCube Air (P621725)..... <b>PA32000</b>	Air (37H3737)..... <b>PA2581</b>
Fuel (5575143)..... <b>BF46248</b>	Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>LEYLAND Trucks</b>
Trans. (Fuller 4304827)..... <b>BT223</b>	Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	300, 350, 600, 650, 680, 800X, 850, 994
W990 w/Cummins ISX 15.0 (14.9L) Eng. (2023)	W990 w/Paccar MX-13 (12.9L) Eng. (2022)	Fuel Ele. (C.A.V. 7111/44)..... <b>PF838</b>
Lube (5575298)..... <b>B40145</b>	P. Fuel/Water Separator (Fleetguard FS19765)..... <b>PF7930</b>	Can-Type Fuel (C.A.V. 7111/296)..... <b>BF825 +</b>
Fuel (5575143)..... <b>BF46248</b>	S. Fuel/Water Separator (2277129)..... <b>PF46237</b>	Beaver, Cheetah, PD1, PS1
Trans. (Fuller 4304827)..... <b>BT223</b>	<b>KNIGHT MOTOR CORP. Trucks</b>	B-P Lube..... <b>P42</b>
W990 w/Cummins X15 (14.9L) Eng. (2020)	450R Red Ram Refuse Truck w/Chrysler V8-318 Eng.	Big J4T w/Rolls-Royce 265 Eng.
Dual-Flow Lube (4367100)..... <b>BD50000</b>	4 3/8 In. Lube..... <b>B233</b>	Lube Ele..... <b>P104</b>
Fuel/Water Separator (Fleetguard FS19764G)..... <b>PF46091</b>	5 9/32 In. Lube..... <b>B2 +</b>	Can-Type Fuel..... <b>BF825 +</b>
Fuel (5365988)..... <b>BF46129</b>	In-Line Fuel..... <b>BF840 +</b>	Fuel Spin-on..... <b>BF1102</b>
EnduraCube Air (P621725)..... <b>PA32000</b>	<b>KOHLER RV Generators</b>	Air (ACU3426)..... <b>PA1885 +</b>
Cab Air (Fresh Air) (X1987001)..... <b>PA30093</b>	9EFORD, 9EFORZD w/Yanmar 3TNE82A Eng.	Big J8 w/Rolls-Royce 205 Eng.
Cab Air (HVAC) (F371018)..... <b>PA30269</b>	Fuel Ele. (Kohler 229715)..... <b>PF981</b>	Lube Ele..... <b>P104</b>
Air Dryer (Bendix 5008414PG)..... <b>BA5379</b>	10EORD, 10EORZD w/Yanmar 3TNE82A Eng.	Can-Type Fuel..... <b>BF825 +</b>
Trans. (Fuller 4304827)..... <b>BT223</b>	Fuel Ele. (Kohler 229715)..... <b>PF981</b>	Fuel Spin-on..... <b>BF1102</b>
Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	12.5EORD, 12.5EORZD w/Yanmar 4TNE84 Eng.	Air (10906079)..... <b>PA1884 +</b>
Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	Fuel (Kohler 252765)..... <b>BF940</b>	Constructor S26, 30.19, 30.25 w/Rolls-Royce 265L, 265Li Engs.
W990 w/Paccar MX-13 (12.9L) Eng. (2019)	Air (Kohler 258646)..... <b>PA1690-FN +</b>	Lube Ele..... <b>P104</b>
Lube Ele. (2129253PE)..... <b>P40008</b>	15EORD, 15EORZD w/Yanmar 4TNE84 Eng.	Fuel Spin-on..... <b>BF1102</b>
Centrifugal Lube (1922496PE)... <b>BC40009</b>	Fuel (Kohler 252765)..... <b>BF940</b>	Air (ABU8514)..... <b>PA1846 +</b>
Fuel/Water Separator (K371022) <b>PF46237</b>	Air (Kohler 258646)..... <b>PA1690-FN +</b>	Air (ACU3731)..... <b>PA2750</b>
Cab Air (X1987001)..... <b>[2] PA30093</b>	20EORZ, 20EORZD w/Yanmar 4TNE84-T Eng.	Constructor T45 w/Gardner 6LXC Eng.
Air Dryer (Bendix 5008414)..... <b>BA5374 +</b>	Fuel (Kohler 252765)..... <b>BF940</b>	Lube Ele..... <b>P352</b>
Coolant (1843659PE)..... <b>B5088</b>	Air (Kohler 258646)..... <b>PA1690-FN +</b>	P. Fuel..... <b>PF831</b>
Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>KOOL-GEN Auxiliary Power Units (APU)</b>	Air..... <b>PA1885 +</b>
Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	KG 1000 w/Yanmar 2TNV-70 Eng.	Constructor T45 w/Rolls-Royce 220, 265L Engs.
Trans. Spin-on (Fuller 4304827).. <b>BT223</b>	Lube (119305-35151)..... <b>B1400</b>	Lube Ele..... <b>P104</b>
Opt. Trans. Spin-on (Fuller 17237)..... <b>B2</b>	Fuel/Water Separator (Racor R11T)..... <b>PF46009</b>	Fuel Spin-on..... <b>BF1102</b>
W990 w/Paccar MX-13 (12.9L) Eng. (2020)	Fuel (119810-55650)..... <b>PF981</b>	Air (ACU3426)..... <b>PA1885 +</b>
F-F Lube (2151728PE)..... <b>P40069</b>	Fuel (171081-55910)..... <b>PF7869</b>	Crusader, Crusader 4x2 w/Rolls-Royce 200, 220, 260, 280, 290 Engs.
Centrifugal Lube (1922496PE)... <b>BC40148</b>		Lube Ele..... <b>P104</b>
Fuel/Water Separator (K371012) <b>PF46082</b>		Fuel Spin-on..... <b>BF1102</b>
Fuel (2133096PE)..... <b>PF46106</b>		Air (10906079)..... <b>PA1884 +</b>
EnduraCube Air (P621725)..... <b>PA32000</b>		Air (ACU3426)..... <b>PA1885 +</b>
Cab Air (Fresh Air) (X1987001).... <b>PA30093</b>		
Cab Air (HVAC) (F371018)..... <b>PA30269</b>		
Air Dryer (Bendix 5008414PG).... <b>BA5379</b>		


\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

LEYLAND Trucks (cont'd)	LIFEFORCE Auxiliary Power Units (APU)	M.A.N. Buses (cont'd)
Handyman w/Rolls-Royce 220 Eng. Lube Ele..... P104 Fuel Spin-on..... BF1102 Air (10906079)..... PA1884 + Tube-Type Air (ABU8513)..... PA1780	LifeForce w/John Deere 6.5 HP Propane Eng. Air..... CLN&R	12.284 w/D0836 Eng. Lube (Mann W1160)..... B7116 Fuel/Water Separator (Mann WDK724)..... BF1372 Radial Seal Air (Mann C25730/1)..... RS4775 Cab Air (8169100011)..... PA3980 Air Dryer (Mann TB1374)..... BA5374 +
Marathon w/Rolls-Royce 220, 250, 260, 265, 280 Engs. Lube Ele..... P104 Fuel Spin-on..... BF1102 Air (10906079)..... PA1884 + Air (ABU8514)..... PA1846 + Air (ACU3426)..... PA1885 +	<b>LION</b> Buses LionC w/Cummins ISB 6.7 (6.7L) Eng. (2018) Lube (3937736)..... B7177 Fuel (Fleetguard FF63009)..... BF63000 Crankcase Breather (4936636)..... CV15010	12U192R14 Lube (Sakura O6201)..... P235 S. Fuel Ele..... PF231 Air (81083040024)..... PA3605 Steering (81055040007)..... PT691
OE138 Lube..... P174	<b>LYCOMING</b> Engines Models w/Mason Jar Screw Neck Filter B-P Lube..... T300-M	12U210R15 w/U11D Eng. S. Fuel Ele..... PF231
Roadrunner w/Cummins 6BT5.9 Eng. Lube..... BT339 + P. Fuel/Water Separator..... BF1280 + S. Fuel..... BF788 Air (Coopers AZA356)..... PA2859-FN 90	C2-90 Air (1956-57)..... PA652	12V160 Lube (O6201)..... P235 S. Fuel Ele..... PF231 Air (81083040024)..... PA3605 Steering (81055040007)..... PT691
Roadtrain w/Cummins Eng. F-F Lube..... B196 + B-P Lube..... B7577 Fuel/Water Separator..... BF1212 + Fuel Spin-on..... BF957-D + Air (BBU2734)..... PA2751	CV4-180 Air..... PA634	256.25 w/D0026M2, D1546M4 Engs. Lube (81055040032)..... P235 P. Fuel (81125030050)..... F953-F S. Fuel (81125030041)..... PF834
Roadtrain w/Rolls-Royce 290, 300Li, 340Li Engs. Lube Ele..... P104 Can-Type Fuel..... BF825 + Fuel Spin-on..... BF1102 Air (ACU3426)..... PA1885 + Air (ACU3731)..... PA2750	<b>M.A.N.</b> Buses 9.135 w/D0836HM7H, D0836HM9U Engs. F-F Lube (81055040023)..... PT12 P. Fuel (81125030050)..... F953-F S. Fuel (81125030041)..... PF834 Air (81083016074)..... PA2847 100.8 mm Steering..... P106-HD 115.9 mm Steering (81055040007)..... PT691	360.32 w/D0026M2, D1546M4 Engs. Lube (81055040032)..... P235 P. Fuel (81125030050)..... F953-F S. Fuel (81125030041)..... PF834
Roadtrain 16.25, 16.29 w/Rolls-Royce 290, 300Li, 340Li Engs. Lube Ele..... P104 Can-Type Fuel..... BF825 + Fuel Spin-on..... BF1102 Air (ACU3426)..... PA1885 + Air (ACU3731)..... PA2750	10U210 w/U11D Eng. P. Fuel Ele. (81125030011)..... F950-F S. Fuel Ele. (81125030042)..... PF231	415.25, 420 w/D0026M2, D1546M4 Engs. Lube (81055040032)..... P235 P. Fuel (81125030050)..... F953-F S. Fuel (81125030041)..... PF834
Routeman w/Rolls-Royce 220 Eng. Lube Ele..... P104 Fuel Spin-on..... BF1102 Air (10906079)..... PA1884 + Tube-Type Air (ABU8513)..... PA1780	11M60, 11U192R13 Lube..... P235 S. Fuel Ele..... PF231 Air (81083040024)..... PA3605 Steering (81055040007)..... PT691	530 w/D0026M Eng. Lube (81055040008)..... P42 P. Fuel Ele. (81125030011)..... F950-F S. Fuel Ele. (81125030042)..... PF231
Super Constructor 6x6 w/Rolls-Royce 260, 280 Engs. Lube Ele..... P104 Can-Type Fuel..... BF825 + Fuel Spin-on..... BF1102 Air (10906079)..... PA1884 +	11U210R13 w/U11D Eng. S. Fuel Ele..... PF231	530 w/D1546M3 Eng. Lube (81055040032)..... P235 P. Fuel Ele. (81125030011)..... F950-F S. Fuel Ele. (81125030042)..... PF231 Steering (81055040007)..... PT691
Trunker 3 w/Rolls-Royce 200, 220 Engs. Lube Ele..... P104 Fuel Spin-on..... BF1102 Air (10906079)..... PA1884 + Air (ACU3426)..... PA1885 +	11V60 Lube (Sakura O6201)..... P235 S. Fuel Ele..... PF231 Air (81083040024)..... PA3605 Steering (81055040007)..... PT691	535 w/D0026M Eng. Lube (81055040008)..... P42 P. Fuel Ele. (81125030011)..... F950-F S. Fuel Ele. (81125030042)..... PF231
	12.163 L w/D0824 Eng. Lube (Mann W1160)..... B7116 Fuel/Water Separator (Mann WDK724)..... BF1372 Cab Air (8169100011)..... PA3980 Air Dryer (Mann TB1374)..... BA5374 +	535 w/D0836HM7H, D0836HM9U Engs. F-F Lube (81055040023)..... PT12 P. Fuel (81125030050)..... F953-F S. Fuel (81125030041)..... PF834 Air (81083016074)..... PA2847 100.8 mm Steering..... P106-HD 115.9 mm Steering (81055040007)..... PT691
	12.224 L w/D0826 Eng. Lube (Mann W1160)..... B7116 Fuel/Water Separator (Mann WDK724)..... BF1372 Radial Seal O. Air (Mann C25730/1)..... RS4775 Cab Air (8169100011)..... PA3980 Air Dryer (Mann TB1374)..... BA5374 +	

+ See Product Guide for Variations of This Number. 90 Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

M.A.N. Buses (cont'd)	M.A.N. Buses (cont'd)	M.A.N. Buses (cont'd)
535HOR10, 535HOU10 w/D0836M3H Eng. Lube (81055040023)..... <b>PT12</b> P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> Steering (81055040007)..... <b>PT691</b>	760UO w/D1546M1U Eng. P. Fuel (81125030050)..... <b>F953-F</b> S. Fuel (81125030041)..... <b>PF834</b>	SG220 w/D2556, D2566MUM Engs. (Cont'd) 148.4 mm S. Fuel Ele. (81125030042)..... <b>PF231</b> Air (81083040024)..... <b>PA3605</b> Steering (81055040007)..... <b>PT691</b>
545 w/D0026M Eng. Lube (81055040008)..... <b>P42</b> P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b>	890 w/D1246HM5U, D2146HM51U Engs. F-F Lube..... <b>P235</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> 381.0 mm Air (81083040024)..... <b>PA3605</b> 383.4 mm Air (81083016074)..... <b>PA2847</b> Steering (81055040007)..... <b>PT691</b>	SG240, SG240H w/D2556 Eng. Lube (81055040041)..... <b>P294</b> 115.1 mm P. Fuel Ele. (81125030050)..... <b>F953-F</b> 142.9 mm P. Fuel Ele. (81125030011)..... <b>F950-F</b> 108.7 mm S. Fuel (81125030041)..... <b>PF834</b> 148.4 mm S. Fuel Ele. (81125030042)..... <b>PF231</b> O. Air (81083040045)..... <b>PA2474</b> I. Air (81083040046)..... <b>PA2836</b> Single Air (81055040033)..... <b>PA3572</b> Steering (81055040007)..... <b>PT691</b>
560 w/D0026M2, D1546M4 Engs. Lube (81055040032)..... <b>P235</b> P. Fuel (81125030050)..... <b>F953-F</b> S. Fuel (81125030041)..... <b>PF834</b>	890 Lube (81055040032)..... <b>P235</b> P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> Hyd. (81055040007)..... <b>PT691</b>	SG240, SG240H w/D2566 Eng. Lube (81055040041)..... <b>P294</b> P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> O. Air (81083040045)..... <b>PA2474</b> I. Air (81083040046)..... <b>PA2836</b> Single Air (81055040033)..... <b>PA3572</b> Steering (81055040007)..... <b>PT691</b>
640 w/D0836HM7H, D0836HM9U Engs. F-F Lube (81055040023)..... <b>PT12</b> P. Fuel (81125030050)..... <b>F953-F</b> S. Fuel (81125030041)..... <b>PF834</b> Air (81083016074)..... <b>PA2847</b> 100.8 mm Steering..... <b>P106-HD</b> 115.9 mm Steering (81055040007)..... <b>PT691</b>	2280 w/D0026M2, D1546M4 Engs. Lube (81055040032)..... <b>P235</b> P. Fuel (81125030050)..... <b>F953-F</b> S. Fuel (81125030041)..... <b>PF834</b>	SG240, SG240H w/D2566 Eng. Lube (81055040041)..... <b>P294</b> P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> O. Air (81083040045)..... <b>PA2474</b> I. Air (81083040046)..... <b>PA2836</b> Single Air (81083040024)..... <b>PA3605</b> Steering (81055040007)..... <b>PT691</b>
750 w/D0836HM7H, D0836HM9U Engs. F-F Lube (81055040023)..... <b>PT12</b> P. Fuel (81125030050)..... <b>F953-F</b> S. Fuel (81125030041)..... <b>PF834</b> Air (81083016074)..... <b>PA2847</b> 100.8 mm Steering..... <b>P106-HD</b> 115.9 mm Steering (81055040007)..... <b>PT691</b>	RJ240 w/D2866 Eng. Lube (81055040041)..... <b>P294</b> Fuel Ele. (81125030018)..... <b>PF950</b> Fuel Spin-on (81125030075)..... <b>BF587-D +</b> 381.0 mm Air (81083040045)..... <b>PA2474</b> Steering (81055046001)..... <b>PT691</b>	SG242, SG242H, UL242 w/D2866 Eng. Lube (81055040041)..... <b>P294</b> Fuel Ele. (81125030018)..... <b>PF950</b> Fuel Spin-on (81125030075)..... <b>BF587-D +</b> 381.0 mm Air (81083040045)..... <b>PA2474</b> Steering (81055046001)..... <b>PT691</b>
750, Standardbus VOV w/D0836HM91U, D0836HM95U Engs. Lube (81055040023)..... <b>PT12</b> P. Fuel (81125030050)..... <b>F953-F</b> S. Fuel (81125030041)..... <b>PF834</b> Air (81083040024)..... <b>PA3605</b> Steering (81055040007)..... <b>PT691</b>	RJ290, SG292, SG292H w/D2866 Eng. Lube (81055040041)..... <b>P294</b> Fuel Ele. (81125030018)..... <b>PF950</b> Fuel Spin-on (81125030075)..... <b>BF587-D +</b> 381.0 mm Air (81083040045)..... <b>PA2474</b> Steering (81055046001)..... <b>PT691</b>	SL160 w/D0846 Eng. Lube (81055040032)..... <b>P235</b> P. Fuel (81125030050)..... <b>F953-F</b> S. Fuel (81125030041)..... <b>PF834</b>
750 w/D2146HM5U, D2146HM51U Engs. Lube (81055040032)..... <b>P235</b> P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> 381.0 mm Air (81083040024)..... <b>PA3605</b> 383.4 mm Air (81083016074)..... <b>PA2847</b> Steering (81055040007)..... <b>PT691</b>	SD200, SL200 w/D2556, D2566MUM Engs. Lube (81055040041)..... <b>P294</b> 115.1 mm P. Fuel Ele. (81125030050)..... <b>F953-F</b> 142.9 mm P. Fuel Ele. (81125030011)..... <b>F950-F</b> 108.7 mm S. Fuel (81125030051)..... <b>PF834</b> 148.4 mm S. Fuel Ele. (81125030042)..... <b>PF231</b> Air (81083040024)..... <b>PA3605</b> Steering (81055040007)..... <b>PT691</b>	SL195 w/U11D Eng. P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b>
760 w/D0026M2, D1546M4 Engs. Lube (81055040032)..... <b>P235</b> P. Fuel (81125030050)..... <b>F953-F</b> S. Fuel (81125030041)..... <b>PF834</b>	SG192, SL192 Lube (81055040032)..... <b>P235</b> P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> Air (81083040024)..... <b>PA3605</b> Steering (81055040007)..... <b>PT691</b>	SL202 w/D2566 Eng. Lube (81055040041)..... <b>P294</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> Air (81083040024)..... <b>PA3605</b>
760 w/D0836HM7H, D0836HM9U Engs. F-F Lube (81055040023)..... <b>PT12</b> P. Fuel (81125030050)..... <b>F953-F</b> S. Fuel (81125030041)..... <b>PF834</b> Air (81083016074)..... <b>PA2847</b> 100.8 mm Steering (1902137)..... <b>P106-HD</b> 115.9 mm Steering (81055040007)..... <b>PT691</b>	SG220 w/D2556, D2566MUM Engs. Lube (81055040041)..... <b>P294</b> 115.1 mm P. Fuel Ele. (81125030050)..... <b>F953-F</b> 142.9 mm P. Fuel Ele. (81125030011)..... <b>F950-F</b> 108.7 mm S. Fuel (81125030051)..... <b>PF834</b>	SL202 w/D2866 Eng. Lube (81055040041)..... <b>P294</b> Fuel Ele. (81125030018)..... <b>PF950</b> 381.0 mm Air (81083040045)..... <b>PA2474</b>
	SU211 w/U11D Eng. P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b>	SU230 Lube (81055040032)..... <b>P235</b> P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> Air (81083040024)..... <b>PA3605</b> Steering (81055040007)..... <b>PT691</b>


\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

M.A.N. Buses (cont'd)	M.A.N. Buses (cont'd)	M.A.N. Engines (cont'd)
SR240, SU240 w/D2556, D2566MUM Engs. Lube (81055040041)..... P294 115.1 mm P. Fuel Ele. (81125030050)..... F953-F 142.9 mm P. Fuel Ele. (81125030011)..... F950-F 108.7 mm S. Fuel Ele. (81125030051)..... PF834 148.4 mm S. Fuel Ele. (81125030042)..... PF231 Air (81083040024)..... PA3605 Steering (81055040007)..... PT691	Lion's City C LE w/D2066 LUH Euro 6 Eng. (Cont'd) Air Dryer (82521020013)..... BA5374 + Steering (81473016005)..... P106-HD Lion's City GL LE w/D2066 LUH Euro 6 Eng. Lube Ele. (51055040122)..... P7329 Fuel/Water Separator (w/o Heater) (81125030086)..... BF7912 Fuel Ele. (51125030061)..... PF7935 Fuel Pre-filter (51125030062)..... PF7939 Fuel (Preheater) (81125030039)..... PF7833 Radial Seal Air (81083040093)..... RS30180 Air Dryer (82521020013)..... BA5374 + Steering (81473016005)..... P106-HD Lion's City L LE w/D2066 LUH Euro 6 Eng. Lube Ele. (51055040122)..... P7329 Fuel/Water Separator (w/o Heater) (81125030086)..... BF7912 Fuel Ele. (51125030061)..... PF7935 Fuel Pre-filter (51125030062)..... PF7939 Fuel (Preheater) (81125030039)..... PF7833 Radial Seal Air (81083040093)..... RS30180 Air Dryer (82521020013)..... BA5374 + Steering (81473016005)..... P106-HD	33.463DF w/D2876LF02 Eng. Lube Ele. (6/00-on) (Mann HU951x)..... P7196 Lube Spin-on (51055017160)..... B7116 Fuel..... BF587-D + D0834LF Lube..... B7116 D0834LFL Lube..... P7196 D0836 Series 177.0 mm Lube Ele. .... P7196 198.4 mm Lube Ele. (81055040032)..... P235 Lube Spin-on..... B7116 P. Fuel Ele. (81125030011)..... F950-F S. Fuel Ele. (81125030042)..... PF231 D0846 Series Lube (81055040023)..... PT12 P. Fuel (81125030050)..... F953-F S. Fuel (81125030041)..... PF834 D1546 Series Lube (81055040032)..... P235 142.9 mm Fuel Ele. (81125030011)..... F950-F 148.4 mm Fuel Ele. (81125030042)..... PF231 D2066 Series Lube..... P7329 P. Fuel (51125030061)..... PF7935 Some S. Fuel..... PF7939 D2146 Series Lube (81055040032)..... P235 142.9 mm Fuel Ele. (81125030011)..... F950-F 148.4 mm Fuel Ele. (81125030042)..... PF231 35.364F, 35.364VF w/D2865LF35 Eng. Lube (81055040026)..... P235 P. Fuel Ele. (81125030011)..... F950-F S. Fuel Ele. (81125030042)..... PF231 33.463DF w/D2876LF02 Eng. Lube (81055040026)..... P235 P. Fuel Ele. (81125030011)..... F950-F S. Fuel Ele. (81125030042)..... PF231 D2530 Series 115.1 mm P. Fuel Ele. (81125030050)..... F953-F 142.9 mm P. Fuel Ele. (81125030011)..... F950-F 108.7 mm S. Fuel Ele. (81125030041)..... PF834 148.4 mm S. Fuel Ele. (81125030042)..... PF231
SR280 w/D2566 Eng. Lube Ele. (81055040041)..... P294 P. Fuel Ele. (81125030011)..... F950-F S. Fuel Ele. (81125030042)..... PF231 379.4 mm Air (81083040046)..... PA2836 381.0 mm Air (81083040036)..... PA2474 495.3 mm Air (81055040033)..... PA3572 Steering (81055040007)..... PT691	Lion's City L LE w/D2066 LUH Euro 6 Eng. Lube Ele. (51055040122)..... P7329 Fuel/Water Separator (w/o Heater) (81125030086)..... BF7912 Fuel Ele. (51125030061)..... PF7935 Fuel Pre-filter (51125030062)..... PF7939 Fuel (Preheater) (81125030039)..... PF7833 Radial Seal Air (81083040093)..... RS30180 Air Dryer (82521020013)..... BA5374 + Steering (81473016005)..... P106-HD	
SR321 w/D2566 Eng. Lube Ele. (81055040041)..... P294 P. Fuel Ele. (81125030011)..... F950-F S. Fuel Ele. (81125030042)..... PF231 379.4 mm Air (81083040046)..... PA2836 381.0 mm Air (81083040036)..... PA2474 495.3 mm Air (81055040033)..... PA3572 Steering (81055040007)..... PT691	<b>M.A.N. Engines</b> D0026M Lube..... P42 S. Fuel Ele..... PF231 D0026, D0026M2 Lube..... P235 P. Fuel..... F953-F S. Fuel..... PF834 D083 Series Lube Ele..... P7196 Lube Spin-on (51055017160)..... B7116 Fuel/Water Separator (51125030040)..... BF1372 P. Fuel (51125030061)..... PF7935 S. Fuel (51125030062)..... PF7939 D0216 Series Lube (A5000041045)..... B114 Can-Type Fuel (81125030038)..... BF825 + D0224M, D0224MF P. Fuel Ele. (81125030011)..... F950-F S. Fuel Ele. (81125030042)..... PF231 Fuel Spin-on (51125030004)..... BF587 35.343VF w/D2865LF21 Eng. Fuel Ele. (Mann P811)..... PF950 Fuel Spin-on (51125030012)..... BF988 + D0824 Series Lube (51055017160)..... B7116 Fuel..... BF587-D +	
SR361 w/D2866KF Eng. Lube (81055040041)..... P294 P. Fuel Ele. (81125030011)..... F950-F S. Fuel Ele. (81125030042)..... PF231 O. Air (81083040038)..... PA2776 I. Air..... PA3494		
UL272 w/D2866 Eng. Lube (81055040041)..... P294 Fuel Ele. (81125030018)..... PF950 Fuel Spin-on (81125030075)..... BF587-D + 381.0 mm Air (81083040045)..... PA2474 Steering (81055046001)..... PT691		
Lion's City C w/D2066 LUH Euro 6 Eng. Lube Ele. (51055040122)..... P7329 Fuel/Water Separator (w/o Heater) (81125030086)..... BF7912 Fuel Ele. (51125030061)..... PF7935 Fuel Pre-filter (51125030062)..... PF7939 Fuel (Preheater) (81125030039)..... PF7833 Radial Seal Air (81083040093)..... RS30180 Air Dryer (82521020013)..... BA5374 + Steering (81473016005)..... P106-HD		
Lion's City C LE w/D2066 LUH Euro 6 Eng. Lube Ele. (51055040122)..... P7329 Fuel/Water Separator (w/o Heater) (81125030086)..... BF7912 Fuel Ele. (51125030061)..... PF7935 Fuel Pre-filter (51125030062)..... PF7939 Fuel (Preheater) (81125030039)..... PF7833 Radial Seal Air (81083040093)..... RS30180		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

M.A.N. Engines (cont'd)	M.A.N. Engines (cont'd)	M.A.N. Engines (cont'd)
33.463DF w/D2876LF02 Eng. Lube (81055040041)..... P294 115.1 mm P. Fuel (81125030050)..... F953-F 142.9 mm P. Fuel (81125030011)..... F950-F 108.7 mm S. Fuel (81125030041)..... PF834 148.4 mm S. Fuel (81125030042)..... PF231	D2842 Lube (81055040041)..... P294 P. Fuel Ele. (81125030011)..... F950-F S. Fuel Ele. (81125030042)..... PF231 Fuel Spin-on..... BF587-D + D2855 (U10D) Lube (88055040003)..... PT86-HD P. Fuel (81125030011)..... F950-F S. Fuel (81125030042)..... PF231	D3530 Lube (81055040041)..... P294 P. Fuel (81125030011)..... F950-F S. Fuel (81125030042)..... PF231 E2886 Series (Gas) Lube (To 2/98)..... P7145 Lube (2/98-on)..... P7190 Fuel Spin-on..... BF587-D +
D2540, D2540MTF, D2542, D2548 Fuel Ele..... PF950	35.343VF w/D2865LF21 Eng. Lube (81055040025)..... P721 P. Fuel Ele. (81125030011)..... F950-F S. Fuel Ele. (81125030042)..... PF231	TD232 V6, TD232 V8 Lube (605400350003)..... PT670 Fuel (81125030011)..... F950-F
D2555 Series Lube (81055040040)..... P242 115.1 mm P. Fuel (81125030050)..... F953-F 142.9 mm P. Fuel (81125030011)..... F950-F 108.7 mm S. Fuel (81125030041)..... PF834 148.4 mm S. Fuel (81125030042)..... PF231	D2865 Series Lube..... P7190 Fuel/Water Separator (51125030040)..... BF1372	TD226-6 Fuel (81125030011)..... F950-F
33.463DF w/D2876LF02 Eng. Lube (81055040025)..... P721 115.1 mm P. Fuel (81125030050)..... F953-F 142.9 mm P. Fuel (81125030011)..... F950-F 108.7 mm S. Fuel (81125030041)..... PF834 148.4 mm S. Fuel (81125030042)..... PF231	D2866 Series (Except D2866L Series) 148.4 mm Lube Ele. (51055040098)..... P7190 188.1 mm Some Lube Ele..... P242 264.3 mm Lube Ele..... P294 Fuel/Water Separator (51125030040)..... BF1372 P. Fuel Ele. (81125030011)..... F950-F S. Fuel Ele. (81125030042)..... PF231	U7D Lube (81055040032)..... P235 P. Fuel (81125030011)..... F950-F S. Fuel (81125030042)..... PF231
D2565 Lube (81055040040)..... P242 P. Fuel (81125030011)..... F950-F S. Fuel (81125030042)..... PF231	D2866 Series Lube..... P7190 Fuel/Water Separator (51125030040)..... BF1372 Fuel..... PF7878	U10D Lube (88055040003)..... PT86-HD P. Fuel (81125030011)..... F950-F S. Fuel (81125030042)..... PF231
35.364F, 35.364VF w/D2865LF35 Eng. Lube (81055040041)..... P294 P. Fuel Ele. (81125030011)..... F950-F S. Fuel Ele. (81125030042)..... PF231	D2866L Series Lube..... P7190 Fuel Ele. (PF7878)..... PF7878 Fuel Spin-on (51125030059)..... BF1396	U12D Lube..... PT86-HD P. Fuel Ele. (81125030011)..... F950-F S. Fuel Ele. (81125030042)..... PF231
D2658, D2758 Lube (81055040025)..... P721 P. Fuel Ele. (81125030011)..... F950-F S. Fuel Ele. (81125030042)..... PF231	D2876 Series (Except D2876LF Series) Lube Ele. (51055040098)..... P7190 Fuel Spin-on..... BF587-D +	<b>M.A.N. European Trucks</b>
D2676 Series Lube..... P7329 P. Fuel (51125030061)..... PF7935	D2876 Series Lube..... P7190 Fuel/Water Separator (51125030040)..... BF1372 Fuel..... PF7878	470, 475, 485 w/R.V.I. 712 Eng. Lube..... P7607 Fuel (A5000241676)..... PF7596
D2840LE4, D2842LE4, D2848LE4, D2866LE4 (Marine) Lube (51055040104)..... P294 Fuel/Water Separator (51125030040)..... BF1372	D2876LF Series Lube (To 9/96)..... P7145 Lube (9/96-on)..... P7190 Fuel Spin-on..... BF587-D +	4.70, 5.70F w/R.V.I. 712 Eng. Can-Type Fuel (81125030038).... BF825 +
D2840 Lube (HU947/2x)..... P7145 P. Fuel..... PF7878	D2886L, D2886LF Lube..... P7190 Fuel Spin-on..... BF587-D +	5.126, 5.136 w/R.V.I. 597, 797 Eng. Lube Spin-on (A5000041045).... B114 P. Fuel Ele. (81125030011)..... F950-F S. Fuel Ele. (81125030042)..... PF231 Fuel Spin-on..... BF790 Hyd. (81055040007)..... PT691
	D3256 Series (U12D) Lube..... PT86-HD P. Fuel Ele. (81125030011)..... F950-F S. Fuel Ele. (81125030042)..... PF231	6.90, 6.90F w/D0224M, D0224MF Eng. Fuel Spin-on (51125030004)..... BF587 O. Air (81083040054)..... PA2845 I. Air..... PA2837
		6.100 w/D0824 Eng. Lube (51055017160)..... B7116 Fuel..... BF587 Air..... PA2405
		6.115 w/D0026 Eng. Lube Ele. (81055040032)..... P235 P. Fuel (81125030050)..... F953-F S. Fuel (81125030041)..... PF834
		6.126, 6.136 w/R.V.I. 597, 797 Eng. Lube Spin-on (A5000041045).... B114 P. Fuel Ele. (81125030011)..... F950-F S. Fuel Ele. (81125030042)..... PF231 Fuel Spin-on..... BF790 Hyd. (81055040007)..... PT691

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)
7.126 w/R.V.I. 597, 797 Engs. Lube Spin-on (A5000041045)..... <b>B114</b> P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> Fuel Spin-on..... <b>BF790</b> Hyd. (81055040007)..... <b>PT691</b>	8.100 w/D0824 Eng. Lube (51055017160)..... <b>B7116</b> Fuel..... <b>BF587</b> Air..... <b>PA2405</b>	L2000 Evo 8.155 LRC, L2000 Evo 8.155 LRC air, L2000 Evo 8.155 LRC w/D0834LF(02) Eng. (05/01-on) Lube..... <b>B7116</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>Radial Seal Air</b> ..... <b>RS4775</b> <b>Cab Air</b> (85619500025)..... <b>PA5339</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> ..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>
7.135 w/D0836, D0836M2 Engs. Lube (81055040032)..... <b>P235</b> P. Fuel (81125030050)..... <b>F953-F</b> S. Fuel (81125030041)..... <b>PF834</b> Hyd. (81055040007)..... <b>PT691</b>	8.113 w/D0824 Series Engs. Lube (51055017160)..... <b>B7116</b> Air (81083040055)..... <b>PA2405</b>	8.156 w/D0836, D0836M2 Engs. Lube (81055040032)..... <b>P235</b> P. Fuel (81125030050)..... <b>F953-F</b> S. Fuel (81125030041)..... <b>PF834</b> Hyd. (81055040007)..... <b>PT691</b>
7.136 w/R.V.I. 597, 797 Engs. Lube Spin-on (A5000041045)..... <b>B114</b> P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> Fuel Spin-on..... <b>BF790</b> Hyd. (81055040007)..... <b>PT691</b>	8.126, 8.136 w/R.V.I. 597, 797 Engs. Lube Spin-on (A5000041045)..... <b>B114</b> P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> Fuel Spin-on..... <b>BF790</b> Hyd. (81055040007)..... <b>PT691</b>	8.160 F-F Lube Ele. (81055040032)..... <b>P235</b> B-P Lube Ele. (81055040008)..... <b>P42</b> P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b>
TGL 7.150 Series w/D0834LFL Eng. (06/05-on) Lube..... <b>P7196</b> P. Fuel (51125030061)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> <b>414.3 mm Radial Seal Air</b> (81084050022)..... <b>RS5409</b> <b>457.2 mm Radial Seal Air</b> (Mann 81084050018)..... <b>RS5506</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>	8.136 w/D0226MF Eng. 155.6 mm Fuel..... <b>BF587</b> <b>Fuel/Water Separator</b> ..... <b>BF1221 +</b> 123.0 mm Some Fuel..... <b>BF988 +</b> O. Air (81083040054)..... <b>PA2845</b> I. Air..... <b>PA2837</b>	8.163 w/D0824 Series Engs. Lube (51055017160)..... <b>B7116</b> Air (81083040055)..... <b>PA2405</b>
TGL 7.170 Series w/D0834LFL Eng. (06/05-on) Lube..... <b>P7196</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> <b>414.3 mm Radial Seal Air</b> (81084050022)..... <b>RS5409</b> <b>457.2 mm Radial Seal Air</b> (Mann 81084050018)..... <b>RS5506</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>	8.136F w/D0224M, D0224MF Engs. Fuel (51125030004)..... <b>BF587</b> O. Air (81083040054)..... <b>PA2845</b> I. Air (A6212)..... <b>PA2837</b>	L2000 Evo 8.163F, L2000 Evo 8.163FK w/D0834LF(02) Eng. (05/01-on) Lube..... <b>B7116</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>Radial Seal Air</b> ..... <b>RS4775</b> <b>Cab Air</b> (85619500025)..... <b>PA5339</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> ..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>
TGL 7.180 Series w/D0834LFL Eng. (06/05-on) Lube..... <b>P7196</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> <b>414.3 mm Radial Seal Air</b> (81084050022)..... <b>RS5409</b> <b>457.2 mm Radial Seal Air</b> (Mann 81084050018)..... <b>RS5506</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>	8.150 w/D0826F Eng. Lube (51055017160)..... <b>B7116</b> Fuel Spin-on..... <b>BF587</b> Air..... <b>PA2405</b>	L2000 Evo LE 8.180 BB, L2000 Evo LE 8.180 BL w/D0834LF(02) Eng. (05/01-on) Lube..... <b>B7116</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>Radial Seal Air</b> ..... <b>RS4775</b> <b>Cab Air</b> (85619500025)..... <b>PA5339</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> ..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>
TGL 7.180 Series w/D0834LFL Eng. (06/05-on) Lube..... <b>P7196</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> <b>414.3 mm Radial Seal Air</b> (81084050022)..... <b>RS5409</b> <b>457.2 mm Radial Seal Air</b> (Mann 81084050018)..... <b>RS5506</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>	TGL 8.150 w/D0834 Eng. (09/08-on) Lube..... <b>P7196</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> <b>414.3 mm Radial Seal Air</b> (81084050022)..... <b>RS5409</b> <b>457.2 mm Radial Seal Air</b> (Mann 81084050018)..... <b>RS5506</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b> <b>Air Dryer</b> (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>	L2000 Evo LE 8.180 BB, L2000 Evo LE 8.180 BL w/D0834LF(03) Eng. (05/01-on) Lube..... <b>B7116</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>Radial Seal Air</b> ..... <b>RS4775</b> <b>Cab Air</b> (85619500025)..... <b>PA5339</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> ..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>
8.90, 8.90F w/D0224M, D0224MF Engs. Fuel (51125030005)..... <b>BF587</b> O. Air (81083040054)..... <b>PA2845</b> I. Air..... <b>PA2837</b>	TGL 8.180 w/D0834 Eng. (09/08-on) Lube..... <b>P7196</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> <b>414.3 mm Radial Seal Air</b> (81084050022)..... <b>RS5409</b> <b>457.2 mm Radial Seal Air</b> (Mann 81084050018)..... <b>RS5506</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b>	TGL 8.180 w/D0834 Eng. (09/08-on) Lube..... <b>P7196</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> <b>414.3 mm Radial Seal Air</b> (81084050022)..... <b>RS5409</b> <b>457.2 mm Radial Seal Air</b> (Mann 81084050018)..... <b>RS5506</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)
TGL 8.180 w/D0834 Eng. (09/08-on) (Cont'd) <b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b> <b>Air Dryer</b> (Desiccant) (Mann TB1374x)..... <b>BA5374 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>	TGL 8.220 w/D0834 Eng. (09/08-on) (Cont'd) <b>457.2 mm Radial Seal Air</b> (Mann 81084050018)..... <b>RS5506</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b> <b>Air Dryer</b> (Desiccant) (Mann TB1374x)..... <b>BA5374 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>	TGL 8.250 w/D0836 Eng. (09/08-on) (Cont'd) <b>Steering</b> (81473016005)..... <b>P106-HD</b> 9.126, 9.136 w/R.V.I. 597, 797 Eng. <b>Lube Spin-on</b> (A5000041045)..... <b>B114</b> <b>P. Fuel Ele.</b> (81125030011)..... <b>F950-F</b> <b>S. Fuel Ele.</b> (81125030042)..... <b>PF231</b> <b>Fuel Spin-on</b> ..... <b>BF790</b> <b>Hyd.</b> (81055040007)..... <b>PT691</b>
TGL 8.180 Series w/D0834LFL Eng. (06/05-on) <b>Lube</b> ..... <b>P7196</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>414.3 mm Radial Seal Air</b> (81084050022)..... <b>RS5409</b> <b>457.2 mm Radial Seal Air</b> (Mann 81084050018)..... <b>RS5506</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>	8.224 w/D0826 Series Eng. <b>Lube</b> (51055017160)..... <b>B7116</b> <b>Air</b> (81083040036)..... <b>PA2474</b>	9.136 w/D0226MF Eng. <b>Fuel Spin-on</b> ..... <b>BF587</b> <b>Opt. Fuel/Water Separator</b> ..... <b>BF1221 +</b> <b>Some Fuel</b> ..... <b>BF988 +</b> <b>O. Air</b> (81083040054)..... <b>PA2845</b> <b>I. Air</b> ..... <b>PA2837</b>
L2000 Evo 8.185 LRC, L2000 Evo 8.185 LRC air, L2000 Evo 8.185 LRC w/D0834LF(03) Eng. (05/01-on) <b>Lube</b> ..... <b>B7116</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>Radial Seal Air</b> ..... <b>RS4775</b> <b>Cab Air</b> (85619500025)..... <b>PA5339</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> ..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>	L2000 Evo 8.224F, L2000 Evo 8.224FK w/D0834LF(03) Eng. (05/01-on) <b>Lube</b> ..... <b>B7116</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>Radial Seal Air</b> ..... <b>RS4775</b> <b>Cab Air</b> (85619500025)..... <b>PA5339</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> ..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>	9.136F w/D0224 Series Eng. <b>Fuel</b> (51125030005)..... <b>BF587</b> <b>O. Air</b> (81083040054)..... <b>PA2845</b> <b>I. Air</b> ..... <b>PA2837</b>
TGL 8.210 Series w/D0834LFL Eng. (06/05-on) <b>Lube</b> ..... <b>P7196</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>414.3 mm Radial Seal Air</b> (81084050022)..... <b>RS5409</b> <b>457.2 mm Radial Seal Air</b> (Mann 81084050018)..... <b>RS5506</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>	TGL 8.240 w/D0836LFL Eng. (06/05-on) <b>Lube</b> ..... <b>P7196</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>414.3 mm Radial Seal Air</b> (81084050022)..... <b>RS5409</b> <b>457.2 mm Radial Seal Air</b> (Mann 81084050018)..... <b>RS5506</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>	9.150 w/D0826F Eng. <b>Lube</b> (51055017160)..... <b>B7116</b> <b>Fuel Spin-on</b> ..... <b>BF587</b> <b>Air</b> ..... <b>PA2405</b>
TGL 8.220 w/D0834 Eng. (09/08-on) <b>Lube</b> ..... <b>P7196</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>414.3 mm Radial Seal Air</b> (81084050022)..... <b>RS5409</b>	TGL 8.250 w/D0836 Eng. (09/08-on) <b>Lube</b> ..... <b>P7196</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>414.3 mm Radial Seal Air</b> (81084050022)..... <b>RS5409</b> <b>457.2 mm Radial Seal Air</b> (Mann 81084050018)..... <b>RS5506</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b> <b>Air Dryer</b> (Desiccant) (Mann TB1374x)..... <b>BA5374 +</b>	9.156 w/D0836M2 Eng. <b>Lube</b> (81055040032)..... <b>P235</b> <b>P. Fuel</b> (81125030050)..... <b>F953-F</b> <b>S. Fuel</b> (81125030041)..... <b>PF834</b> <b>Hyd.</b> (81055040007)..... <b>PT691</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)
10.136 w/D0226MF Eng. Fuel Spin-on..... <b>BF587</b> Opt. Fuel/Water Separator..... <b>BF1221 +</b> Some Fuel..... <b>BF988 +</b> O. Air (81083040054)..... <b>PA2845</b> I. Air (A6212)..... <b>PA2837</b>	TGL 10.180 w/D0834 Eng. (09/08-on) Lube..... <b>P7196</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> <b>414.3 mm Radial Seal Air</b> (81084050022)..... <b>RS5409</b> <b>457.2 mm Radial Seal Air</b> (Mann 81084050018)..... <b>RS5506</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b> <b>Air Dryer</b> (Desiccant) (Mann TB1374x)..... <b>BA5374 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>	L2000 Evo 10.185 LRC, L2000 Evo 10.185 LRC air w/D0834LF(03) Eng. (05/01-on) (Cont'd) <b>Cab Air</b> (85619500025)..... <b>PA5339</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> ..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>
10.150 w/D0826F Eng. Lube (51055017160)..... <b>B7116</b> Fuel Spin-on..... <b>BF587</b> Air..... <b>PA2405</b>	L2000 Evo LE 10.180 BB, L2000 Evo LE 10.180 BL w/D0834LF(03) Eng. (05/01-on) Lube..... <b>B7116</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>Radial Seal Air</b> ..... <b>RS4775</b> <b>Cab Air</b> (85619500025)..... <b>PA5339</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> ..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>	10.210 w/D2146, D2156, D2356 Engs. Lube (81055040032)..... <b>P235</b> P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> Hyd. (81055040007)..... <b>PT691</b>
F2000 27.293 w/D2865 Eng. (01/94-04/96) Lube (1/94-1/95) (Mann HU947/1n)..... <b>P7305</b> Lube (2/95-4/96) (Mann HU947/2x)..... <b>P7145</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>Radial Seal O. Air</b> (Mann C301353)..... <b>RS3714</b> <b>Radial Seal I. Air</b> (Mann C17170)..... <b>RS4549</b> <b>Cab Air</b> (Mann CU40110)..... <b>PA3980</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b>	TGL 10.180 Series w/D0834LFL Eng. (06/05-on) Lube..... <b>P7196</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> <b>414.3 mm Radial Seal Air</b> (81084050022)..... <b>RS5409</b> <b>457.2 mm Radial Seal Air</b> (Mann 81084050018)..... <b>RS5506</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>	10.210 Series w/D0834LFL Eng. (06/05-on) Lube..... <b>P7196</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> <b>414.3 mm Radial Seal Air</b> (81084050022)..... <b>RS5409</b> <b>457.2 mm Radial Seal Air</b> (Mann 81084050018)..... <b>RS5506</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>
F2000 27.293 w/D2865 Eng. (05/96-on) Lube..... <b>P7190</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>Radial Seal O. Air</b> ..... <b>RS3714</b> <b>Radial Seal I. Air</b> ..... <b>RS4549</b> <b>Cab Air</b> ..... <b>PA3980</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> ..... <b>BA5379 +</b> Trans. (ZF Gearbox)..... <b>PT8385</b>	TGL 10.180 Series w/D0834LFL Eng. (06/05-on) Lube..... <b>P7196</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> <b>414.3 mm Radial Seal Air</b> (81084050022)..... <b>RS5409</b> <b>457.2 mm Radial Seal Air</b> (Mann 81084050018)..... <b>RS5506</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>	10.212, 10.230 F-F Lube Ele. (81055040032)..... <b>P235</b> B-P Lube Ele. (81055040008)..... <b>P42</b> P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b>
10.156 w/D0836M2 Eng. Lube (81055040032)..... <b>P235</b> P. Fuel (81125030050)..... <b>F953-F</b> S. Fuel (81125030041)..... <b>PF834</b> Hyd. (81055040007)..... <b>PT691</b>	TGL 10.220 w/D0834 Eng. (09/08-on) Lube..... <b>P7196</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> <b>414.3 mm Radial Seal Air</b> (81084050022)..... <b>RS5409</b> <b>457.2 mm Radial Seal Air</b> (Mann 81084050018)..... <b>RS5506</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b> <b>Air Dryer</b> (Desiccant) (Mann TB1374x)..... <b>BA5374 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>	TGL 10.220 w/D0834 Eng. (09/08-on) Lube..... <b>P7196</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> <b>414.3 mm Radial Seal Air</b> (81084050022)..... <b>RS5409</b> <b>457.2 mm Radial Seal Air</b> (Mann 81084050018)..... <b>RS5506</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b> <b>Air Dryer</b> (Desiccant) (Mann TB1374x)..... <b>BA5374 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>
10.160 F-F Lube Ele. (81055040032)..... <b>P235</b> B-P Lube Ele. (81055040008)..... <b>P42</b> P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b>	L2000 Evo 10.185 w/D0836LF Eng. (05/01-on) Lube..... <b>B7116</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>Radial Seal Air</b> ..... <b>RS4775</b> <b>Cab Air</b> (85619500025)..... <b>PA5339</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>	L2000 Evo LE 10.220 BB, L2000 Evo LE 10.220 BL w/D0836LF(02) Eng. (05/01-on) Lube..... <b>B7116</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>Radial Seal Air</b> ..... <b>RS4775</b> <b>Cab Air</b> (85619500025)..... <b>PA5339</b>
10.163 w/D0824 Series Engs. Lube (51055017160)..... <b>B7116</b> Air (81083040055)..... <b>PA2405</b>	L2000 Evo 10.185 LRC, L2000 Evo 10.185 LRC air w/D0834LF(03) Eng. (05/01-on) Lube..... <b>B7116</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>Radial Seal Air</b> ..... <b>RS4775</b>	L2000 Evo LE 10.220 BB, L2000 Evo LE 10.220 BL w/D0836LF(02) Eng. (05/01-on) Lube..... <b>B7116</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>Radial Seal Air</b> ..... <b>RS4775</b> <b>Cab Air</b> (85619500025)..... <b>PA5339</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)
L2000 Evo LE 10.220 BB, L2000 Evo LE 10.220 BL w/D0836LF(02) Eng. (05/01-on) (Cont'd) Air Dryer (Mann TB1374X)..... BA5374 + Air Dryer..... BA5379 + Steering (81473016005)..... P106-HD	TGL 10.240 Series w/D0836LFL Eng. (06/05-on) (Cont'd) Steering (81473016005)..... P106-HD	12.136 w/D0226MF Eng. Fuel Spin-on..... BF587 Opt. Fuel/Water Separator..... BF1221 + Some Fuel..... BF988 + O. Air (81083040054)..... PA2845 I. Air..... PA2837
L2000 Evo 10.224F, L2000 Evo 10.224FK w/D0826LF(04) Eng. (05/01-on) Lube (51055017160)..... B7116 Fuel/Water Separator (51125030040)..... BF1372 Radial Seal Air..... RS4775 Cab Air (85619500025)..... PA5339 Air Dryer (Mann TB1374X)..... BA5374 + Air Dryer..... BA5379 + Steering..... P106-HD	TGL 10.250 w/D0836 Eng. (09/08-on) Lube..... P7196 P. Fuel (51125030063)..... PF7935 S. Fuel (51125030062)..... PF7939 414.3 mm Radial Seal Air (81084050022)..... RS5409 457.2 mm Radial Seal Air (Mann 81084050018)..... RS5506 Cab Air (w/o Carbon) (81619100018)..... PA4955 Cab Air (w/Carbon) (81619100019)..... PA5477 Air Dryer (Coalescer) (81521086025)..... BA5379 + Air Dryer (Desiccant) (Mann TB1374x)..... BA5374 + Steering (81473016005)..... P106-HD	12.136 w/R.V.I. 597, 797 Eng. Lube Spin-on (A5000041045)..... B114 P. Fuel Ele. (81125030011)..... F950-F S. Fuel Ele. (81125030042)..... PF231 Fuel Spin-on..... BF790 Hyd. (81055040007)..... PT691
L2000 Evo 10.225 LRC, L2000 Evo 10.225 LRC air w/D0836LF Eng. (05/01-on) Lube (51055017160)..... B7116 Fuel/Water Separator (51125030040)..... BF1372 Radial Seal Air..... RS4775 Cab Air (85619500025)..... PA5339 Air Dryer (Mann TB1374X)..... BA5374 + Air Dryer..... BA5379 + Steering..... P106-HD	11.136 w/R.V.I. 597, 797 Eng. Lube Spin-on (A5000041045)..... B114 P. Fuel Ele. (81125030011)..... F950-F S. Fuel Ele. (81125030042)..... PF231 Fuel Spin-on..... BF790 Hyd. (81055040007)..... PT691	M2000 Evo 12.145 L w/D0834 Eng. (05/01-on) Lube..... B7116 Fuel/Water Separator (51125030040)..... BF1372 Radial Seal Air..... RS4775 Cab Air..... PA3980 Air Dryer (Mann TB1374X)..... BA5374 + Air Dryer..... BA5379 + Steering..... P106-HD
TGL 10.240 w/D0836LFL40 Eng. (06/05-on) Lube..... P7196 P. Fuel (51125030063)..... PF7935 S. Fuel (51125030062)..... PF7939 414.3 mm Radial Seal Air (81084050022)..... RS5409 457.2 mm Radial Seal Air (Mann 81084050018)..... RS5506 Cab Air (w/o Carbon) (81619100018)..... PA4955 Cab Air (w/Carbon) (81619100019)..... PA5477 Air Dryer (Coalescer) (81521086025)..... BA5379 + Air Dryer (Desiccant) (Mann TB1374x)..... BA5374 + Steering (81473016005)..... P106-HD	11.136U w/U7D Eng. Lube Ele. (81055040032)..... P235 P. Fuel Ele. (81125030011)..... F950-F S. Fuel Ele. (81125030042)..... PF231	12.156 w/D0836M2 Eng. Lube (81055040032)..... P235 P. Fuel (81125030050)..... F953-F S. Fuel (81125030041)..... PF834 Hyd. (81055040007)..... PT691
TGL 10.240 Series w/D0836LFL Eng. (06/05-on) Lube..... P7196 P. Fuel (51125030063)..... PF7935 S. Fuel (51125030062)..... PF7939 414.3 mm Radial Seal Air (81084050022)..... RS5409 Cab Air (w/o Carbon) (81619100018)..... PA4955 Cab Air (w/Carbon) (81619100019)..... PA5477 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (81521086025)..... BA5379 +	11.136U w/D0216MXUL Eng. Lube Spin-on (A5000041045)..... B114 Can-Type Fuel (81125030038)..... BF825 + Air (81083040028)..... PA2866	12.163 M2000 w/D0824 Series Eng. (4.6L) Lube (51055017160)..... B7116 Air (81083040055)..... PA2405
TGL 10.240 Series w/D0836LFL Eng. (06/05-on) Lube..... P7196 P. Fuel (51125030063)..... PF7935 S. Fuel (51125030062)..... PF7939 414.3 mm Radial Seal Air (81084050022)..... RS5409 Cab Air (w/o Carbon) (81619100018)..... PA4955 Cab Air (w/Carbon) (81619100019)..... PA5477 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (81521086025)..... BA5379 +	11.168 w/D2555 Eng. Lube (81055040040)..... P242 115.1 mm P. Fuel (81125030050)..... F953-F 142.9 mm P. Fuel (81125030011)..... F950-F 108.7 mm S. Fuel (81125030041)..... PF834 148.4 mm S. Fuel (81125030042)..... PF231 O. Air (81083040036)..... PA2474 I. Air..... PA2836 Single Air (81083040024)..... PA3605 Steering (81055040007)..... PT691	L2000 Evo 12.163F w/D0836LF(04) Eng. (05/01-on) Lube..... B7116 Fuel/Water Separator (51125030040)..... BF1372 Radial Seal Air..... RS4775 Cab Air (85619500025)..... PA5339 Air Dryer (Mann TB1374X)..... BA5374 + Air Dryer..... BA5379 + Steering (81473016005)..... P106-HD
	11.230 w/D0826 Series Eng. (1988) Lube (51055017160)..... B7116 381.0 mm O. Air (81083040045)..... PA2474 379.4 mm I. Air (81083040046)..... PA2836 374.7 mm Air (81083040055)..... PA2405 377.0 mm Air (81083040076)..... PA3760	12.168 w/D2555 Eng. Lube (81055040040)..... P242 115.1 mm P. Fuel (81125030050)..... F953-F 142.9 mm P. Fuel (81125030011)..... F950-F 108.7 mm S. Fuel (81125030041)..... PF834 148.4 mm S. Fuel (81125030042)..... PF231 O. Air (81083040036)..... PA2474 I. Air..... PA2836 Single Air (81083040024)..... PA3605 Steering (81055040007)..... PT691
		12.170 w/D0226MKF Eng. Fuel (51125030012)..... BF988 + Opt. Fuel/Water Separator..... BF1221 + Air (81083040045)..... PA2474

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)
TGL 12.180 w/D0834 Eng. (09/08-on) Lube..... P7196 P. Fuel (51125030063)..... PF7935 S. Fuel (51125030062)..... PF7939 414.3 mm Radial Seal Air (81084050022)..... RS5409 457.2 mm Radial Seal Air (Mann 81084050018)..... RS5506 Cab Air (w/o Carbon) (81619100018)..... PA4955 Cab Air (w/Carbon) (81619100019)..... PA5477 Air Dryer (Coalescer) (81521086025)..... BA5379 + Air Dryer (Desiccant) (Mann TB1374x)..... BA5374 + Steering (81473016005)..... P106-HD	L2000 Evo 12.185 LRC, L2000 Evo 12.185 LRC air w/D0834LF(03) Eng. (05/01-on) Lube..... B7116 Fuel/Water Separator (51125030040)..... BF1372 Radial Seal Air..... RS4775 Cab Air (85619500025)..... PA5339 Air Dryer (Mann TB1374X)..... BA5374 + Air Dryer..... BA5379 + Steering (81473016005)..... P106-HD 12.186 w/D2146, D2156, D2356 Engs. Lube (81055040032)..... P235 P. Fuel Ele. (81125030011)..... F950-F S. Fuel Ele. (81125030042)..... PF231 Hyd. (81055040007)..... PT691 12.192 w/D0226, D0226MKF, D0226MKM Engs. Fuel (81125030075)..... BF587-D + Air (81083040045)..... PA2474 12.192U w/D2855 (U10D) Eng. Lube (88055040003)..... PT86-HD P. Fuel Ele. (81125030011)..... F950-F S. Fuel Ele. (81125030042)..... PF231 Air (81083040024)..... PA3605 Hyd. (81055040007)..... PT691 TGL 12.210 Series w/D0834LFL Eng. (06/05-on) Lube..... P7196 P. Fuel (51125030063)..... PF7935 S. Fuel (51125030062)..... PF7939 414.3 mm Radial Seal Air (81084050022)..... RS5409 Air (Mann 81084050018)..... RS5506 Cab Air (w/o Carbon) (81619100018)..... PA4955 Cab Air (w/Carbon) (81619100019)..... PA5477 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (81521086025)..... BA5379 + Steering (81473016005)..... P106-HD 12.215, 12.230 w/D2146, D2156, D2356 Engs. Lube (81055040032)..... P235 P. Fuel Ele. (81125030011)..... F950-F S. Fuel Ele. (81125030042)..... PF231 Hyd. (81055040007)..... PT691 TGL 12.220 w/D0834 Eng. (09/08-on) Lube..... P7196 P. Fuel (51125030063)..... PF7935 S. Fuel (51125030062)..... PF7939 414.3 mm Radial Seal Air (81084050022)..... RS5409 457.2 mm Radial Seal Air (Mann 81084050018)..... RS5506 Cab Air (w/o Carbon) (81619100018)..... PA4955	TGL 12.220 w/D0834 Eng. (09/08-on) (Cont'd) Cab Air (w/Carbon) (81619100019)..... PA5477 Air Dryer (Coalescer) (81521086025)..... BA5379 + Air Dryer (Desiccant) (Mann TB1374x)..... BA5374 + Steering (81473016005)..... P106-HD L2000 Evo LE 12.220 BB, L2000 Evo LE 12.220 BL w/D0836LF(02) Eng. (05/01-on) Lube..... B7116 Fuel/Water Separator (51125030040)..... BF1372 Radial Seal Air..... RS4775 Cab Air (85619500025)..... PA5339 Air Dryer (Mann TB1374X)..... BA5374 + Air Dryer..... BA5379 + Steering (81473016005)..... P106-HD 12.224 w/D0826 Eng. Lube (51055017160)..... B7116 Air (81083040036)..... PA2474 L2000 Evo 12.224F w/D0836LF(04) Eng. (05/01-on) Lube..... B7116 Fuel/Water Separator (51125030040)..... BF1372 Radial Seal Air..... RS4775 Cab Air (85619500025)..... PA5339 Air Dryer (Mann TB1374X)..... BA5374 + Air Dryer..... BA5379 + Steering (81473016005)..... P106-HD M2000 Evo 12.225 L w/D0836 Eng. (05/01-on) Lube..... B7116 Fuel/Water Separator (51125030040)..... BF1372 Radial Seal Air..... RS4775 Cab Air..... PA3980 Air Dryer (Mann TB1374X)..... BA5374 + Air Dryer..... BA5379 + Steering..... P106-HD L2000 Evo 12.225 LRC, L2000 Evo 12.225 LRC air w/D0836LF(02) Eng. (05/01-on) Lube..... B7116 Fuel/Water Separator (51125030040)..... BF1372 Radial Seal Air..... RS4775 Cab Air (85619500025)..... PA5339 Air Dryer (Mann TB1374X)..... BA5374 + Air Dryer..... BA5379 + Steering..... P106-HD 12.232 w/D0826L Eng. Lube (51055017160)..... B7116 Fuel (81125030075)..... BF587-D + Air (81083040036)..... PA2474

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)
TGL 12.240 Series w/D0836LFL Eng. (06/05-on)	13.168 w/D0846 Eng.	13.240 w/D2556 Eng.
Lube..... P7196	F-F Lube (81055040023)..... PT12	F-F Lube (81055040025)..... P721
P. Fuel (51125030063)..... PF7935	P. Fuel (81125030050)..... F953-F	115.1 mm P. Fuel (81125030050)..... F953-F
S. Fuel (51125030062)..... PF7939	S. Fuel (81125030041)..... PF834	142.9 mm P. Fuel (81125030011)..... F950-F
414.3 mm Radial Seal Air (81084050022)..... RS5409	Air (81083040024)..... PA3605	108.7 mm S. Fuel (81125030041)..... PF834
457.2 mm Radial Seal Air (Mann 81084050018)..... RS5506	13.168 w/D2555 Eng.	148.4 mm S. Fuel (81125030042)..... PF231
Cab Air (w/o Carbon) (81619100018)..... PA4955	Lube (81055040040)..... P242	O. Air (81083040036)..... PA2474
Cab Air (w/Carbon) (81619100019)..... PA5477	115.1 mm P. Fuel (81125030050)..... F953-F	I. Air..... PA2836
Steering (81473016005)..... P106-HD	142.9 mm P. Fuel (81125030011)..... F950-F	Hyd. (81055040007)..... PT691
TGL 12.250 w/D0836 Eng. (09/08-on)	108.7 mm S. Fuel (81125030041)..... PF834	TGM 13.250 w/D0836 Eng. (09/08-on)
Lube..... P7196	148.4 mm S. Fuel (81125030042)..... PF231	Lube..... P7196
P. Fuel (51125030063)..... PF7935	O. Air (81083040036)..... PA2474	P. Fuel (51125030063)..... PF7935
S. Fuel (51125030062)..... PF7939	I. Air..... PA2836	S. Fuel (51125030062)..... PF7939
414.3 mm Radial Seal Air (81084050022)..... RS5409	Single Air (81083040024)..... PA3605	414.3 mm Radial Seal Air (81084050022)..... RS5409
457.2 mm Radial Seal Air (Mann 81084050018)..... RS5506	Steering (81055040007)..... PT691	457.2 mm Radial Seal Air (Mann 81084050018)..... RS5506
Cab Air (w/o Carbon) (81619100018)..... PA4955	13.170 w/D0226MKF Eng.	Cab Air (w/o Carbon) (81619100018)..... PA4955
Cab Air (w/Carbon) (81619100019)..... PA5477	Fuel (51125030012)..... BF988 +	Cab Air (w/Carbon) (81619100019)..... PA5477
Air Dryer (Coalescer) (81521086025)..... BA5379 +	Opt. Fuel/Water Separator..... BF1221 +	Air Dryer (Coalescer) (81521086025)..... BA5379 +
Air Dryer (Desiccant) (Mann TB1374x)..... BA5374 +	Air (81083040045)..... PA2474	Air Dryer (Desiccant) (Mann TB1374x)..... BA5374 +
Steering (81473016005)..... P106-HD	13.192 w/D0826T, D0826TF Eng.	Steering (81473016005)..... P106-HD
M2000 Evo 12.255 L w/D0836 Eng. (05/01-on)	Lube (51055017160)..... B7116	Urea (81154036015)..... PE5270
Lube..... B7116	Fuel..... BF587-D +	13.250 w/D2146, D2156, D2356 Eng.
Fuel/Water Separator (51125030040)..... BF1372	O. Air (81083040036)..... PA2474	Lube (81055040032)..... P235
Radial Seal Air..... RS4775	I. Air..... PA2836	P. Fuel Ele. (81125030011)..... F950-F
Cab Air..... PA3980	Hyd. (81055040007)..... PT691	S. Fuel Ele. (81125030042)..... PF231
Air Dryer (Mann TB1374X)..... BA5374 +	13.192 w/D2555 Eng.	Hyd. (81055040007)..... PT691
Air Dryer..... BA5379 +	Lube (81055040040)..... P242	13.250 w/D2658 Eng.
Steering..... P106-HD	115.1 mm P. Fuel (81125030050)..... F953-F	Lube (81055040025)..... P721
13.136 w/R.V.I. 597, 797 Eng.	142.9 mm P. Fuel (81125030011)..... F950-F	P. Fuel Ele. (81125030011)..... F950-F
Lube Spin-on (A5000041045)..... B114	108.7 mm S. Fuel (81125030041)..... PF834	S. Fuel Ele. (81125030042)..... PF231
P. Fuel Ele. (81125030011)..... F950-F	148.4 mm S. Fuel (81125030042)..... PF231	Hyd. (81055040007)..... PT691
S. Fuel Ele. (81125030042)..... PF231	O. Air (81083040036)..... PA2474	13.256 w/D2146, D2156, D2356 Eng.
Fuel Spin-on..... BF790	I. Air..... PA2836	Lube (81055040032)..... P235
Hyd. (81055040007)..... PT691	Single Air (81083040024)..... PA3605	P. Fuel Ele. (81125030011)..... F950-F
13.136U w/U7D Eng.	Steering (81055040007)..... PT691	S. Fuel Ele. (81125030042)..... PF231
Lube (81055040032)..... P235	13.192U w/D2855 (U10D) Eng.	Hyd. (81055040007)..... PT691
P. Fuel Ele. (81125030011)..... F950-F	F-F Lube (88055040003)..... PT86-HD	13.275, 13.304 w/D2758, D2858 Eng.
S. Fuel Ele. (81125030042)..... PF231	P. Fuel Ele. (81125030011)..... F950-F	Lube (81055040025)..... P721
13.136U w/D0216MXUL Eng.	S. Fuel Ele. (81125030042)..... PF231	P. Fuel Ele. (81125030011)..... F950-F
Lube Spin-on (A5000041045)..... B114	Air (81083040024)..... PA3605	S. Fuel Ele. (81125030042)..... PF231
Can-Type Fuel (81125030038)..... BF825 +	Hyd. (81055040007)..... PT691	Hyd. (81055040007)..... PT691
Air (81083040028)..... PA2866	13.215, 13.230 w/D2146, D2156, D2356 Eng.	TGM 13.280 w/D0836 Eng. (04/06-on)
	Lube (81055040032)..... P235	Lube..... P7196
	P. Fuel Ele. (81125030011)..... F950-F	P. Fuel (51125030063)..... PF7935
	S. Fuel Ele. (81125030042)..... PF231	S. Fuel (51125030062)..... PF7939
	Hyd. (81055040007)..... PT691	414.3 mm Radial Seal Air (81084050022)..... RS5409

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

**Trucks & Buses Applications** **BALDWIN FILTERS**

M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)
TGM 13.280 w/D0836 Eng. (04/06-on) (Cont'd) <b>457.2 mm Radial Seal Air</b> (Mann 81084050018)..... <b>RS5506</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b> <b>Steering</b> ..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>	14.168 w/D2555 Eng. (Cont'd) <b>I. Air</b> ..... <b>PA2836</b> <b>Single Air</b> (81083040024)..... <b>PA3605</b> <b>Steering</b> (81055040007)..... <b>PT691</b> 14.170 w/D0226MKF Eng. <b>Fuel</b> (51125030012)..... <b>BF988 +</b> <b>Opt. Fuel/Water Separator</b> ..... <b>BF1221 +</b> <b>Air</b> (81083040045)..... <b>PA2474</b>	M2000 Evo LE 14.220 BLS, M2000 Evo LE 14.220LL w/D0836LF Eng. (05/01-on) <b>Lube</b> ..... <b>B7116</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>Radial Seal Air</b> ..... <b>RS4775</b> <b>Cab Air</b> ..... <b>PA3980</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> ..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>
TGM 13.290 w/D0836 Eng. (09/08-on) <b>Lube</b> ..... <b>P7196</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>414.3 mm Radial Seal Air</b> (81084050022)..... <b>RS5409</b> <b>457.2 mm Radial Seal Air</b> (Mann 81084050018)..... <b>RS5506</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b> <b>Air Dryer</b> (Desiccant) (Mann TB1374x)..... <b>BA5374 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>	M2000 Evo 14.185 L/M w/D0834 Eng. (05/01-on) <b>Lube</b> ..... <b>B7116</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>Radial Seal Air</b> ..... <b>RS4775</b> <b>Cab Air</b> ..... <b>PA3980</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> ..... <b>BA5379 +</b> <b>Steering</b> ..... <b>P106-HD</b> 14.192 w/D0226, D0226MKF, D0226MKM Eng. <b>Fuel</b> ..... <b>BF587-D +</b> <b>Air</b> (81083040045)..... <b>PA2474</b>	M2000 Evo 14.224 L w/D0826 Eng. <b>Lube</b> (51055017160)..... <b>B7116</b> <b>Fuel/Water Separator Spin-on</b> (Mann WDK724)..... <b>BF1372</b> <b>Radial Seal O. Air</b> (Mann C25730/1)..... <b>RS4775</b> <b>377.0 mm Air</b> (Mann C24508)..... <b>PA3760</b> <b>381.0 mm Air</b> (81083040036)..... <b>PA2474</b> <b>Cab Air</b> (8169100011)..... <b>PA3980</b> <b>Air Dryer</b> (Mann TB1374x)..... <b>BA5374 +</b> <b>Steering</b> ..... <b>P106-HD</b>
14.136 w/D0226MF Eng. <b>Fuel</b> ..... <b>BF587</b> <b>Opt. Fuel/Water Separator</b> ..... <b>BF1221 +</b> <b>Fuel</b> ..... <b>BF988 +</b> <b>O. Air</b> (81083040054)..... <b>PA2845</b> <b>I. Air</b> ..... <b>PA2837</b>	14.192 w/D2555 Eng. <b>Lube</b> (81055040040)..... <b>P242</b> <b>115.1 mm P. Fuel</b> (81125030050)..... <b>F953-F</b> <b>142.9 mm P. Fuel</b> (81125030011)..... <b>F950-F</b> <b>108.7 mm S. Fuel</b> (81125030041)..... <b>PF834</b> <b>148.4 mm S. Fuel</b> (81125030042)..... <b>PF231</b> <b>O. Air</b> (81083040036)..... <b>PA2474</b> <b>I. Air</b> ..... <b>PA2836</b> <b>Single Air</b> (81083040024)..... <b>PA3605</b> <b>Steering</b> (81055040007)..... <b>PT691</b>	M2000 Evo 14.224F, M2000 Evo 14.224FLT 220, M2000 Evo 14.224FLT 240 w/D0836LF Eng. (05/01-on) <b>Lube</b> ..... <b>B7116</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>Radial Seal Air</b> ..... <b>RS4775</b> <b>Cab Air</b> ..... <b>PA3980</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> ..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>
CLA 14.160 w/D 0834 Eng. (10/06-on) <b>Lube</b> (51055017160)..... <b>B7116</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>O. Air</b> (81083040074)..... <b>PA3760</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>	14.192U w/D2855 (U10D) Eng. <b>F-F Lube</b> (88055040003)..... <b>PT86-HD</b> <b>P. Fuel Ele.</b> (81125030011)..... <b>F950-F</b> <b>S. Fuel Ele.</b> (81125030042)..... <b>PF231</b> <b>Air</b> (81083040024)..... <b>PA3605</b> <b>Hyd.</b> (81055040007)..... <b>PT691</b>	M2000 Evo 14.225 L/M w/D0836 Eng. (05/01-on) <b>Lube</b> ..... <b>B7116</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>Radial Seal Air</b> ..... <b>RS4775</b> <b>Cab Air</b> ..... <b>PA3980</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> ..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>
14.163, 14.163 L w/D0824 Series Eng. <b>Lube</b> (51055017160)..... <b>B7116</b> <b>Fuel/Water Separator</b> (Mann WDK724)..... <b>BF1372</b> <b>Air</b> (81083040055)..... <b>PA2405</b> <b>Cab Air</b> (8169100011)..... <b>PA3980</b> <b>Air Dryer</b> (Mann TB1374)..... <b>BA5374 +</b>	14.220 w/D2566 Eng. <b>Lube</b> (81055040041)..... <b>P294</b> <b>P. Fuel Ele.</b> (81125030011)..... <b>F950-F</b> <b>S. Fuel Ele.</b> (81125030042)..... <b>PF231</b> <b>Air</b> (81083040045)..... <b>PA2474</b> M2000 Evo LE 14.220BB, M2000 Evo LE 14.220 BL w/D0836LF Eng. (05/01-on) <b>Lube</b> ..... <b>B7116</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>Radial Seal Air</b> ..... <b>RS4775</b> <b>Cab Air</b> ..... <b>PA3980</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> ..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>	M2000 Evo 14.225 LLRT, M2000 Evo 14.225 LRC, M2000 Evo 14.225 LRC air w/D0836LF Eng. (05/01-on) <b>Lube</b> ..... <b>B7116</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>Radial Seal Air</b> ..... <b>RS4775</b> <b>Cab Air</b> ..... <b>PA3980</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>
14.168 w/D2555 Eng. <b>Lube</b> (81055040040)..... <b>P242</b> <b>115.1 mm P. Fuel</b> (81125030050)..... <b>F953-F</b> <b>142.9 mm P. Fuel</b> (81125030011)..... <b>F950-F</b> <b>108.7 mm S. Fuel</b> (81125030041)..... <b>PF834</b> <b>148.4 mm S. Fuel</b> (81125030042)..... <b>PF231</b> <b>O. Air</b> (81083040036)..... <b>PA2474</b>	14.220 w/D0826L Eng. <b>Lube</b> (51055017160)..... <b>B7116</b> <b>Fuel Spin-on</b> ..... <b>BF587-D +</b> <b>Air</b> (81083040036)..... <b>PA2474</b>	14.232 w/D0826L Eng. <b>Lube</b> (51055017160)..... <b>B7116</b> <b>Fuel Spin-on</b> ..... <b>BF587-D +</b> <b>Air</b> (81083040036)..... <b>PA2474</b>

+ See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)
14.240 w/D2566 Eng. Lube Ele. (81055040041)..... P294 P. Fuel Ele. (81125030011)..... F950-F S. Fuel Ele. (81125030042)..... PF231 377.8 mm Air..... PA2813 381.0 mm Air (81083040036)..... PA2474 495.3 mm Air (81055040033)..... PA3572 Hyd. (81055040007)..... PT691	14.284 L w/D0836 Eng. (Cont'd) Cab Air (8169100011)..... PA3980 Air Dryer (Mann TB1374x)..... BA5374 + M2000 Evo 14.284F w/D0836LF Eng. (05/01-on) Lube..... B7116 Fuel/Water Separator (51125030040)..... BF1372 Radial Seal Air..... RS4775 Cab Air..... PA3980 Air Dryer (Mann TB1374X)..... BA5374 + Air Dryer..... BA5379 + Steering (81473016005)..... P106-HD	M2000 Evo 15.185 L w/D0834 Eng. (05/01-on) Lube..... B7116 Fuel/Water Separator (51125030040)..... BF1372 Radial Seal Air..... RS4775 Cab Air..... PA3980 Air Dryer (Mann TB1374X)..... BA5374 + Air Dryer..... BA5379 + Steering (81473016005)..... P106-HD
M2000 Evo 14.255 L w/D0836 Eng. (05/01-on) Lube..... B7116 Fuel/Water Separator (51125030040)..... BF1372 Radial Seal Air..... RS4775 Cab Air..... PA3980 Air Dryer (Mann TB1374X)..... BA5374 + Air Dryer..... BA5379 + Steering (81473016005)..... P106-HD	M2000 Evo 14.285 L/M, M2000 Evo 14.285 LRC, M2000 Evo 14.285 LRC air w/D0836LF Eng. (05/01-on) Lube..... B7116 Fuel/Water Separator (51125030040)..... BF1372 Radial Seal Air..... RS4775 Cab Air..... PA3980 Air Dryer (Mann TB1374X)..... BA5374 + Air Dryer..... BA5379 + Steering (81473016005)..... P106-HD	15.192 w/D0226, D0226MKF, D0226MKM Engs. Fuel (81125030075)..... BF587-D + Air (81083040045)..... PA2474
14.262 w/D2865 Eng. 188.1 mm Lube (1989-on)..... P242 264.3 mm Lube (81055040041)..... P294 Fuel Ele. (81125030042)..... PF231 Fuel Spin-on (81125030075)..... BF587-D + Air (81083040038)..... PA2776	M2000 Evo 14.264 L w/D0826 Eng. Lube (51055017160)..... B7116 Fuel/Water Separator Spin-on (Mann WDK724)..... BF1372 Radial Seal O. Air (Mann C25730/1)..... RS4775 377.0 mm Air (Mann C24508)..... PA3760 381.0 mm Air (81083040036)..... PA2474 Cab Air (8169100011)..... PA3980 Air Dryer (Mann TB1374x)..... BA5374 + Steering..... P106-HD	15.192 w/D0826T, D0826TF Engs. Lube (51055017165)..... B7116 Fuel..... BF587-D + O. Air (81083040036)..... PA2474 I. Air..... PA2836 Hyd. (81055040007)..... PT691
M2000 Evo 14.264 L w/D0826 Eng. Lube (51055017160)..... B7116 Fuel/Water Separator Spin-on (Mann WDK724)..... BF1372 Radial Seal O. Air (Mann C25730/1)..... RS4775 377.0 mm Air (Mann C24508)..... PA3760 381.0 mm Air (81083040036)..... PA2474 Cab Air (8169100011)..... PA3980 Air Dryer (Mann TB1374x)..... BA5374 + Steering..... P106-HD	15.136 w/R.V.I. 597, 797 Engs. Lube Spin-on (A5000041045)..... B114 P. Fuel Ele. (81125030011)..... F950-F S. Fuel Ele. (81125030042)..... PF231 Fuel Spin-on..... BF790 Hyd. (81055040007)..... PT691	15.192 w/D2146, D2156, D2356 Engs. Lube (81055040032)..... P235 P. Fuel Ele. (81125030011)..... F950-F S. Fuel Ele. (81125030042)..... PF231 Hyd. (81055040007)..... PT691
14.272 w/D2865 Eng. 188.1 mm Lube (To 1989) (81055040038)..... P242 264.3 mm Lube (81055040041)..... P294 Fuel Ele. (81125030042)..... PF231 Fuel Spin-on (81125030075)..... BF587-D + Air (81083040038)..... PA2776	15.168 w/D0846 Eng. F-F Lube (81055040023)..... PT12 P. Fuel (81125030050)..... F953-F S. Fuel (81125030041)..... PF834 Air (81083040024)..... PA3605 Steering (81055040007)..... PT691	15.192 w/D2555, D2565 Engs. Lube (81055040040)..... P242 115.1 mm P. Fuel (81125030050)..... F953-F 142.9 mm P. Fuel (81125030011)..... F950-F 108.7 mm S. Fuel (81125030041)..... PF834 148.4 mm S. Fuel (81125030042)..... PF231 O. Air (81083040036)..... PA2474 I. Air..... PA2836 Single Air (81083040024)..... PA3605 Hyd. (81055040007)..... PT691
M2000 Evo LE 14.280 BB, M2000 Evo LE 14.280 BL, M2000 Evo LE 14.280 LLw/D0836L Eng. (05/01-on) Lube..... B7116 Fuel/Water Separator (51125030040)..... BF1372 Radial Seal Air..... RS4775 Cab Air..... PA3980 Air Dryer (Mann TB1374X)..... BA5374 + Air Dryer..... BA5379 + Steering (81473016005)..... P106-HD	15.168 w/D2555, D2565 Engs. Lube (81055040040)..... P242 115.1 mm P. Fuel (81125030050)..... F953-F 142.9 mm P. Fuel (81125030011)..... F950-F 108.7 mm S. Fuel (81125030041)..... PF834 148.4 mm S. Fuel (81125030042)..... PF231 O. Air (81083040036)..... PA2474 I. Air..... PA2836 Single Air (81083040024)..... PA3605 Steering (81055040007)..... PT691	15.192U w/D2855 (U10D) Eng. Lube (88055040003)..... PT86-HD P. Fuel Ele. (81125030011)..... F950-F S. Fuel Ele. (81125030042)..... PF231 Air (81083040024)..... PA3605 Hyd. (81055040007)..... PT691
14.284 L w/D0836 Eng. Lube (Mann W1160)..... B7116 Fuel/Water Separator (Mann WDK724)..... BF1372 Radial Seal Air (Mann C25730/1)..... RS4775	15.170 w/D0226MKF Eng. Fuel (51125030012)..... BF988 + Opt. Fuel/Water Separator..... BF1221 + Air (81083040045)..... PA2474	15.200 w/D2556 Eng. Lube (81055040025)..... P721 115.1 mm P. Fuel (81125030050)..... F953-F 142.9 mm P. Fuel (81125030011)..... F950-F 108.7 mm S. Fuel (81125030041)..... PF834 148.4 mm S. Fuel (81125030042)..... PF231 O. Air (81083040036)..... PA2474 I. Air..... PA2836 Hyd. (81055040007)..... PT691

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

**Trucks & Buses Applications** **BALDWIN FILTERS**

<b>M.A.N. European Trucks (cont'd)</b>	<b>M.A.N. European Trucks (cont'd)</b>	<b>M.A.N. European Trucks (cont'd)</b>
15.212 F-F Lube (81055040032)..... P235 B-P Lube (81055040008)..... P42 P. Fuel Ele. (81125030011)..... F950-F S. Fuel Ele. (81125030042)..... PF231	15.240 w/D2566 Eng. (Cont'd) 381.0 mm Single Air (81083040036)..... PA2474 495.3 mm Single Air (81055040033)..... PA3572 Hyd. (81055040007)..... PT691	TGM 15.280 w/D0836 Eng. (04/06-on) (Cont'd) Cab Air (w/Carbon) (81619100019)..... PA5477 Air Dryer (81521086025)..... BA5379 + Steering..... P106-HD Urea (81154036015)..... PE5270
15.216 w/D0836M2 Eng. Lube (81055040032)..... P235 P. Fuel (81125030050)..... F953-F S. Fuel (81125030041)..... PF834 Hyd. (81055040007)..... PT691	TGM 15.240 w/D0836 Eng. (04/06-on) Lube..... P7196 P. Fuel (51125030063)..... PF7935 S. Fuel (51125030062)..... PF7939 414.3 mm Radial Seal Air (81084050022)..... RS5409 457.2 mm Radial Seal Air (Mann 81084050018)..... RS5506 Cab Air (w/o Carbon) (81619100018)..... PA4955 Cab Air (w/Carbon) (81619100019)..... PA5477 Air Dryer (81521086025)..... BA5379 + Steering..... P106-HD Urea (81154036015)..... PE5270	M2000 Evo 15.285 L w/D0836 Eng. (05/01-on) Lube..... B7116 Fuel/Water Separator (51125030040)..... BF1372 Radial Seal Air..... RS4775 Cab Air..... PA3980 Air Dryer (Mann TB1374X)..... BA5374 + Air Dryer..... BA5379 + Steering (81473016005)..... P106-HD
15.220 w/D2566 Eng. Lube (81055040041)..... P294 P. Fuel Ele. (81125030011)..... F950-F S. Fuel Ele. (81125030042)..... PF231 Air (81083040045)..... PA2474	TGM 15.250 w/D0836 Eng. (09/08-on) Lube..... P7196 P. Fuel (51125030063)..... PF7935 S. Fuel (51125030062)..... PF7939 414.3 mm Radial Seal Air (81084050022)..... RS5409 457.2 mm Radial Seal Air (Mann 81084050018)..... RS5506 Cab Air (w/o Carbon) (81619100018)..... PA4955 Cab Air (w/Carbon) (81619100019)..... PA5477 Air Dryer (Coalescer) (81521086025)..... BA5379 + Air Dryer (Desiccant) (Mann TB1374x)..... BA5374 + Steering (81473016005)..... P106-HD Urea (81154036015)..... PE5270	TGM 15.290 w/D0836 Eng. (09/08-on) Lube..... P7196 P. Fuel (51125030063)..... PF7935 S. Fuel (51125030062)..... PF7939 414.3 mm Radial Seal Air (81084050022)..... RS5409 457.2 mm Radial Seal Air (Mann 81084050018)..... RS5506 Cab Air (w/o Carbon) (81619100018)..... PA4955 Cab Air (w/Carbon) (81619100019)..... PA5477 Air Dryer (Coalescer) (81521086025)..... BA5379 + Air Dryer (Desiccant) (Mann TB1374x)..... BA5374 + Steering (81473016005)..... P106-HD Urea (81154036015)..... PE5270
CLA 15,220 w/D 0836 Eng. (10/06-on) Lube (51055017160)..... B7116 Fuel/Water Separator (51125030040)..... BF1372 O. Air (81083040074)..... PA3760 Steering (81473016005)..... P106-HD	TGM 15.252 w/D0826 Eng. Lube (51055017160)..... B7116	16.136 w/R.V.I. 597, 797 Eng. Lube Spin-on (A5000041045)..... B114 P. Fuel Ele. (81125030011)..... F950-F S. Fuel Ele. (81125030042)..... PF231 Fuel Spin-on..... BF790 Hyd. (81055040007)..... PT691
15.224 w/D0826 Eng. Lube (51055017160)..... B7116	M2000 Evo 15.225 L w/D0836 Eng. (05/01-on) Lube..... B7116 Fuel/Water Separator (51125030040)..... BF1372 Radial Seal Air..... RS4775 Cab Air..... PA3980 Air Dryer (Mann TB1374X)..... BA5374 + Air Dryer..... BA5379 + Steering (81473016005)..... P106-HD	16.168 w/D0846 Eng. F-F Lube (81055040023)..... PT12 P. Fuel (81125030050)..... F953-F S. Fuel (81125030041)..... PF834 Air (81083040024)..... PA3605 Steering (81055040007)..... PT691
15.232 w/D0826L Eng. Lube (51055017160)..... B7116 Fuel..... BF587-D + Air (81083040036)..... PA2474	15.240 w/D2556 Eng. Lube (81055040025)..... P721 115.1 mm P. Fuel (81125030050)..... F953-F 142.9 mm P. Fuel (81125030011)..... F950-F 108.7 mm S. Fuel (81125030041)..... PF834 148.4 mm S. Fuel (81125030042)..... PF231 O. Air (81083040036)..... PA2474 I. Air..... PA2836 Hyd. (81055040007)..... PT691	16.168 w/D2555, D2565 Eng. Lube (81055040040)..... P242 115.1 mm P. Fuel (81125030050)..... F953-F 142.9 mm P. Fuel (81125030011)..... F950-F 108.7 mm S. Fuel (81125030041)..... PF834 148.4 mm S. Fuel (81125030042)..... PF231 O. Air (81083040036)..... PA2474 I. Air..... PA2836 Single Air (81083040024)..... PA3605
15.240 w/D2566 Eng. Lube Ele. (81055040041)..... P294 P. Fuel Ele. (81125030011)..... F950-F S. Fuel Ele. (81125030042)..... PF231 O. Air..... PA1885 + I. Air..... PA1893 377.8 mm Single Air..... PA2813	M2000 Evo 15.255 L w/D0836 Eng. (05/01-on) Lube..... B7116 Fuel/Water Separator (51125030040)..... BF1372 Radial Seal Air..... RS4775 Cab Air..... PA3980 Air Dryer (Mann TB1374X)..... BA5374 + Air Dryer..... BA5379 + Steering (81473016005)..... P106-HD	
	TGM 15.280 w/D0836 Eng. (04/06-on) Lube..... P7196 P. Fuel (51125030063)..... PF7935 S. Fuel (51125030062)..... PF7939 414.3 mm Radial Seal Air (81084050022)..... RS5409 457.2 mm Radial Seal Air (Mann 81084050018)..... RS5506 Cab Air (w/o Carbon) (81619100018)..... PA4955	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)
16.168 w/D2555, D2565 Engs. (Cont'd) <b>Steering</b> (81055040007)..... <b>PT691</b>	16.215 w/D2146, D2156, D2356 Engs. <b>Lube</b> (81055040032)..... <b>P235</b>	M2000 Evo ME 18.280 BB, M2000 Evo ME 18.280 BL, M2000 Evo ME 18.280 LL w/D0836LF Eng. (05/01-on) (Cont'd)
16.170 w/D0226MKF Eng. <b>Fuel</b> (51125030012)..... <b>BF988 +</b> <b>Opt. Fuel/Water Separator</b> ..... <b>BF1221 +</b> <b>Air</b> (81083040045)..... <b>PA2474</b>	<b>P. Fuel Ele.</b> (81125030011)..... <b>F950-F</b> <b>S. Fuel Ele.</b> (81125030042)..... <b>PF231</b> <b>Hyd.</b> (81055040007)..... <b>PT691</b>	<b>Cab Air</b> ..... <b>PA3980</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> ..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>
CLA 16.180 w/D0834 EURO3 Eng. (10/06-on) <b>Lube</b> ..... <b>B7116</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>O. Air</b> ..... <b>PA3760</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>	16.220 w/D2566 Eng. <b>Lube</b> (81055040041)..... <b>P294</b> <b>P. Fuel Ele.</b> (81125030011)..... <b>F950-F</b> <b>S. Fuel Ele.</b> (81125030042)..... <b>PF231</b> <b>Air</b> (81083040045)..... <b>PA2474</b>	16.250 w/D2146, D2156, D2356 Engs. <b>Lube</b> (81055040032)..... <b>P235</b> <b>P. Fuel Ele.</b> (81125030011)..... <b>F950-F</b> <b>S. Fuel Ele.</b> (81125030042)..... <b>PF231</b> <b>Hyd.</b> (81055040007)..... <b>PT691</b>
16.186 w/D2146, D2156, D2356 Engs. <b>Lube</b> (81055040032)..... <b>P235</b> <b>P. Fuel Ele.</b> (81125030011)..... <b>F950-F</b> <b>S. Fuel Ele.</b> (81125030042)..... <b>PF231</b> <b>Hyd.</b> (81055040007)..... <b>PT691</b>	CLA 16.220 w/D 0836 Eng. (10/06-on) <b>Lube</b> (51055017160)..... <b>B7116</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>O. Air</b> (81083040074)..... <b>PA3760</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>	16.250 w/D2658 Eng. <b>Lube</b> (81055040025)..... <b>P721</b> <b>P. Fuel Ele.</b> (81125030011)..... <b>F950-F</b> <b>S. Fuel Ele.</b> (81125030042)..... <b>PF231</b> <b>Hyd.</b> (81055040007)..... <b>PT691</b>
16.192 w/D0226, D0226MKF, D0226MKM Engs. <b>Lube</b> (51055017165)..... <b>B7116</b> <b>Fuel</b> (81125030075)..... <b>BF587-D +</b> <b>O. Air</b> (81083040036)..... <b>PA2474</b> <b>I. Air</b> ..... <b>PA2836</b> <b>Hyd.</b> (81055040007)..... <b>PT691</b>	16.230 w/D2146, D2156, D2356 Engs. <b>Lube</b> (81055040032)..... <b>P235</b> <b>P. Fuel Ele.</b> (81125030011)..... <b>F950-F</b> <b>S. Fuel Ele.</b> (81125030042)..... <b>PF231</b> <b>Hyd.</b> (81055040007)..... <b>PT691</b>	16.256 w/D2146, D2156, D2356 Engs. <b>Lube</b> (81055040032)..... <b>P235</b> <b>P. Fuel Ele.</b> (81125030011)..... <b>F950-F</b> <b>S. Fuel Ele.</b> (81125030042)..... <b>PF231</b> <b>Hyd.</b> (81055040007)..... <b>PT691</b>
16.192 w/D0826T, D0826T6 Engs. <b>Lube</b> (51055017160)..... <b>B7116</b> <b>Fuel</b> ..... <b>BF587-D +</b> <b>O. Air</b> (81083040036)..... <b>PA2474</b> <b>I. Air</b> ..... <b>PA2836</b> <b>Hyd.</b> (81055040007)..... <b>PT691</b>	16.232 w/D0826L Eng. <b>Lube</b> (51055017160)..... <b>B7116</b> <b>Fuel</b> ..... <b>BF587-D +</b> <b>Air</b> (81083040036)..... <b>PA2474</b>	16.256 w/D2538 Eng. <b>Lube</b> (81055040041)..... <b>P294</b> <b>115.1 mm P. Fuel</b> (81125030050)..... <b>F953-F</b> <b>142.9 mm P. Fuel</b> (81125030011)..... <b>F950-F</b> <b>108.7 mm S. Fuel</b> (81125030041)..... <b>PF834</b> <b>148.4 mm S. Fuel</b> (81125030042)..... <b>PF231</b> <b>O. Air</b> (81082050005)..... <b>PA2475</b> <b>I. Air</b> ..... <b>PA2814</b> <b>Hyd.</b> (81055040007)..... <b>PT691</b>
16.192 w/D2555, D2565 Engs. <b>Lube</b> (81055040040)..... <b>P242</b> <b>115.1 mm P. Fuel</b> (81125030050)..... <b>F953-F</b> <b>142.9 mm P. Fuel</b> (81125030011)..... <b>F950-F</b> <b>108.7 mm S. Fuel</b> (81125030041)..... <b>PF834</b> <b>148.4 mm S. Fuel</b> (81125030042)..... <b>PF231</b> <b>O. Air</b> (81083040036)..... <b>PA2474</b> <b>I. Air</b> ..... <b>PA2836</b> <b>Single Air</b> (81083040024)..... <b>PA3605</b> <b>Hyd.</b> (81055040007)..... <b>PT691</b>	16.240 w/D2556 Eng. <b>Lube</b> (81055040025)..... <b>P721</b> <b>115.1 mm P. Fuel</b> (81125030050)..... <b>F953-F</b> <b>142.9 mm P. Fuel</b> (81125030011)..... <b>F950-F</b> <b>108.7 mm S. Fuel</b> (81125030041)..... <b>PF834</b> <b>148.4 mm S. Fuel</b> (81125030042)..... <b>PF231</b> <b>O. Air</b> (81083040036)..... <b>PA2474</b> <b>I. Air</b> ..... <b>PA2836</b> <b>Hyd.</b> (81055040007)..... <b>PT691</b>	16.256U w/D3256BXUL (U12D) Eng. <b>P. Fuel Ele.</b> (81125030011)..... <b>F950-F</b> <b>S. Fuel Ele.</b> (81125030042)..... <b>PF231</b> <b>Air</b> (81055040033)..... <b>PA3572</b> <b>Hyd.</b> (81055040007)..... <b>PT691</b>
16.200 w/D2556 Eng. <b>Lube</b> (81055040025)..... <b>P721</b> <b>115.1 mm P. Fuel</b> (81125030050)..... <b>F953-F</b> <b>142.9 mm P. Fuel</b> (81125030011)..... <b>F950-F</b> <b>108.7 mm S. Fuel</b> (81125030041)..... <b>PF834</b> <b>148.4 mm S. Fuel</b> (81125030042)..... <b>PF231</b> <b>O. Air</b> (81083040036)..... <b>PA2474</b> <b>I. Air</b> ..... <b>PA2836</b> <b>Hyd.</b> (81055040007)..... <b>PT691</b>	16.240 w/D2566 Eng. <b>Lube</b> (81055040041)..... <b>P294</b> <b>P. Fuel Ele.</b> (81125030011)..... <b>F950-F</b> <b>S. Fuel Ele.</b> (81125030042)..... <b>PF231</b> <b>O. Air</b> ..... <b>PA1885 +</b> <b>I. Air</b> ..... <b>PA1893</b> <b>377.8 mm Single Air</b> ..... <b>PA2813</b> <b>381.0 mm Single Air</b> (81083040036)..... <b>PA2474</b> <b>495.3 mm Single Air</b> (81055040033)..... <b>PA3572</b> <b>Hyd.</b> (81055040007)..... <b>PT691</b>	16.272 w/D2865 Eng. <b>188.1 mm Lube</b> (To 1989) (51055040068)..... <b>P242</b> <b>264.3 mm Lube</b> (81055040041)..... <b>P294</b> <b>Fuel Ele.</b> (81125030042)..... <b>PF231</b> <b>Fuel Spin-on</b> (81125030075)..... <b>BF587-D +</b> <b>O. Air</b> (81083040038)..... <b>PA2776</b>
16.200 w/D2556 Eng. <b>Lube</b> (81055040025)..... <b>P721</b> <b>115.1 mm P. Fuel</b> (81125030050)..... <b>F953-F</b> <b>142.9 mm P. Fuel</b> (81125030011)..... <b>F950-F</b> <b>108.7 mm S. Fuel</b> (81125030041)..... <b>PF834</b> <b>148.4 mm S. Fuel</b> (81125030042)..... <b>PF231</b> <b>O. Air</b> (81083040036)..... <b>PA2474</b> <b>I. Air</b> ..... <b>PA2836</b> <b>Hyd.</b> (81055040007)..... <b>PT691</b>	M2000 Evo ME 18.280 BB, M2000 Evo ME 18.280 BL, M2000 Evo ME 18.280 LL w/D0836LF Eng. (05/01-on) <b>Lube</b> ..... <b>B7116</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>Radial Seal Air</b> ..... <b>RS4775</b>	16.275 w/D2658, D2758 Engs. <b>Lube</b> (81055040025)..... <b>P721</b> <b>P. Fuel Ele.</b> (81125030011)..... <b>F950-F</b> <b>S. Fuel Ele.</b> (81125030042)..... <b>PF231</b> <b>Hyd.</b> (81055040007)..... <b>PT691</b>
16.200 w/D2556 Eng. <b>Lube</b> (81055040025)..... <b>P721</b> <b>115.1 mm P. Fuel</b> (81125030050)..... <b>F953-F</b> <b>142.9 mm P. Fuel</b> (81125030011)..... <b>F950-F</b> <b>108.7 mm S. Fuel</b> (81125030041)..... <b>PF834</b> <b>148.4 mm S. Fuel</b> (81125030042)..... <b>PF231</b> <b>O. Air</b> (81083040036)..... <b>PA2474</b> <b>I. Air</b> ..... <b>PA2836</b> <b>Hyd.</b> (81055040007)..... <b>PT691</b>		16.280 w/D2566MT Eng. <b>Lube</b> (81055040041)..... <b>P294</b> <b>P. Fuel Ele.</b> (81125030011)..... <b>F950-F</b> <b>S. Fuel Ele.</b> (81125030042)..... <b>PF231</b> <b>496.9 mm O. Air</b> (81082050005)..... <b>PA2475</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)
16.280 w/D2566MT Eng. (Cont'd)	16.321 w/D2566MK, D2566MKF Engs.	17.220 w/D2566 Eng.
473.1 mm I. Air..... PA2814	Lube (81055040041)..... P294	Lube (81055040041)..... P294
473.9 mm O. Air..... PA2776	P. Fuel Ele. (81125030011)..... F950-F	P. Fuel Ele. (81125030011)..... F950-F
Hyd. (81055040007)..... PT691	S. Fuel Ele. (81125030042)..... PF231	S. Fuel Ele. (81125030042)..... PF231
16.281 w/D2566MK, D2566MKF Engs.	O. Air (81083040038)..... PA2776	Air (81083040045)..... PA2474
Lube (81055040041)..... P294	I. Air (81084050013)..... PA3494	
P. Fuel Ele. (81125030011)..... F950-F	16.322 w/D2865 Eng.	17.232 w/D0826L Eng.
S. Fuel Ele. (81125030042)..... PF231	188.1 mm Lube (To 1989)	Lube (51055017160)..... B7116
O. Air (81083040038)..... PA2776	(51055040068)..... P242	Fuel..... BF587-D +
I. Air..... PA3494	264.3 mm Lube (81055040041)..... P294	Air (81083040036)..... PA2474
16.291 w/D2866 Eng.	P. Fuel Ele. (81125030011)..... F950-F	17.272 w/D2865 Eng.
P. Fuel Ele. (81125030011)..... F950-F	S. Fuel Ele. (81125030042)..... PF231	188.1 mm Lube (51055040068).... P242
S. Fuel Ele. (81125030042)..... PF231	Fuel Spin-on (81125030075)..... BF587-D +	264.3 mm Lube (81055040041).... P294
O. Air (81083040043)..... PA2776	O. Air (81083040038)..... PA2776	Fuel Ele. (81125030042)..... PF231
16.304 w/D2858 Eng.	16.331 w/D2866 Eng.	Fuel Spin-on (81125030075)..... BF587-D +
Lube (81055040025)..... P721	P. Fuel Ele. (81125030011)..... F950-F	O. Air (81083040038)..... PA2776
P. Fuel Ele. (81125030011)..... F950-F	S. Fuel Ele. (81125030042)..... PF231	17.292 w/D2866 Eng.
S. Fuel Ele. (81125030042)..... PF231	Air (81083040038)..... PA2776	Lube (81055040041)..... P294
Hyd. (81055040007)..... PT691	Hyd. (81055040007)..... PT691	P. Fuel Ele. (81125030011)..... F950-F
16.320 w/D2530 Eng.	16.332, 16.362 w/D2866 Eng.	S. Fuel Ele. (81125030042)..... PF231
115.1 mm P. Fuel	Lube (81055040039)..... P294	Fuel Spin-on (81125030075)..... BF587-D +
(81125030050)..... F953-F	Fuel Ele. (81125030021)..... PF950	Air (81083040038)..... PA2776
142.9 mm P. Fuel	Fuel Spin-on (81125030075)..... BF587-D +	17.322 w/D2865 Eng.
(81125030011)..... F950-F	Air (81083040043)..... PA2776	188.1 mm Lube (51055040068).... P242
108.7 mm S. Fuel	16.372 w/D2866 Eng.	264.3 mm Lube (81055040041).... P294
(81125030041)..... PF834	Lube (81055040041)..... P294	P. Fuel Ele. (81125030011)..... F950-F
148.4 mm S. Fuel	Fuel Ele. (81125030042)..... PF231	S. Fuel Ele. (81125030042)..... PF231
(81125030042)..... PF231	Axial Seal Air (81083040038)..... PA2776	Fuel Spin-on (81125030075)..... BF587-D +
O. Air (81082050005)..... PA2475	Radial Seal O. Air	Air (81083040038)..... PA2776
I. Air..... PA2814	(81083040094)..... RS3714	17.332, 17.362, 18.362 w/D2866 Eng.
Hyd. (81055040007)..... PT691	Radial Seal I. Air (81083040084)..... RS4549	Lube (81055040039)..... P294
16.320 w/D2538 Eng.	17.136 w/D0226MF Eng.	Fuel Ele. (81125030021)..... PF950
Lube (81055040041)..... P294	123.0 mm Some Fuel..... BF988 +	Fuel Spin-on (81125030075)..... BF587-D +
115.1 mm P. Fuel	155.6 mm Fuel..... BF587	Air (81083040043)..... PA2776
(81125030050)..... F953-F	Fuel/Water Separator..... BF1221 +	17.372, 18.372 w/D2866 Eng.
142.9 mm P. Fuel	O. Air (81083040054)..... PA2845	Lube (81055040041)..... P294
(81125030011)..... F950-F	I. Air..... PA2837	Fuel Ele. (81125030042)..... PF231
108.7 mm S. Fuel	17.170 w/D0226MKF Eng.	Axial Seal Air (81083040038)..... PA2776
(81125030041)..... PF834	123.0 mm Some Fuel	Radial Seal O. Air
148.4 mm S. Fuel	(51125030012)..... BF988 +	(81083040094)..... RS3714
(81125030042)..... PF231	155.6 mm Fuel Spin-on	Radial Seal I. Air (81083040084)..... RS4549
O. Air (81082050005)..... PA2475	(81125030075)..... BF587-D +	CLA 18,160 w/D 0834 Eng. (10/06-on)
I. Air..... PA2814	Opt. Fuel/Water Separator..... BF1221 +	Lube (51055017160)..... B7116
Hyd. (81055040007)..... PT691	Air (81083040045)..... PA2474	Fuel/Water Separator
16.320 w/D3530 Eng.	17.192 w/D0226MKF, D0226MKM Engs.	(51125030040)..... BF1372
Lube (81055040041)..... P294	Lube (51055017160)..... B7116	O. Air (81083040074)..... PA3760
P. Fuel Ele. (81125030011)..... F950-F	Fuel (81125030075)..... BF587-D +	Steering (81473016005)..... P106-HD
S. Fuel Ele. (81125030042)..... PF231	Air (81083040045)..... PA2474	CLA 18,180 w/D 0834 Eng. (10/06-on)
Hyd. (81055040007)..... PT691	Hyd. (81055040007)..... PT691	Lube (51055017160)..... B7116
16.320U w/D3256BXUL (U12D) Eng.	17.192 w/D0826T Series Engs.	Fuel/Water Separator
P. Fuel Ele. (81125030011)..... F950-F	Lube (51055017165)..... B7116	(51125030040)..... BF1372
S. Fuel Ele. (81125030042)..... PF231	Fuel..... BF587-D +	O. Air (81083040074)..... PA3760
Air (81055040033)..... PA3572	O. Air (81083040036)..... PA2474	Steering (81473016005)..... P106-HD
Hyd. (81055040007)..... PT691	I. Air..... PA2836	CLA 18,220 w/D 0836 Eng. (10/06-on)
	Hyd. (81055040007)..... PT691	Lube (51055017160)..... B7116
		Fuel/Water Separator
		(51125030040)..... BF1372
		O. Air (81083040074)..... PA3760

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)
CLA 18,220 w/D 0836 Eng. (10/06-on) (Cont'd) <b>Steering</b> (81473016005)..... <b>P106-HD</b>	M2000 Evo 18.225 L/M, M2000 Evo 18.225 LAERK, M2000 Evo 18.225 LARK w/D0836 Eng. (05/01-on) <b>Lube</b> ..... <b>B7116</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>Radial Seal Air</b> ..... <b>RS4775</b> <b>Cab Air</b> ..... <b>PA3980</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> ..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>	M2000 Evo 18.255 L/M w/D0836 Eng. (05/01-on) <b>Lube</b> ..... <b>B7116</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>Radial Seal Air</b> ..... <b>RS4775</b> <b>Cab Air</b> ..... <b>PA3980</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> ..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>
M2000 Evo LE 18.220 BB, M2000 Evo LE 18.220 BL, M2000 Evo LE 18.220 LL w/D0836LF Eng. (05/01-on) <b>Lube</b> ..... <b>B7116</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>Radial Seal Air</b> ..... <b>RS4775</b> <b>Cab Air</b> ..... <b>PA3980</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> ..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>	M2000 Evo 18.225 LLRC, M2000 Evo 18.225 LRK, M2000 Evo 18.225 MLRC w/D0836 Eng. (05/01-on) <b>Lube</b> ..... <b>B7116</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>Radial Seal Air</b> ..... <b>RS4775</b> <b>Cab Air</b> ..... <b>PA3980</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> ..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>	CLA 18,280 w/D 0836 Eng. (10/06-on) <b>Lube</b> (51055017160)..... <b>B7116</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>O. Air</b> (81083040074)..... <b>PA3760</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>
M2000 Evo ME 18.220 BB, M2000 Evo 18.220 BL, M2000 Evo 18.220 LL w/D0836LF Eng. (05/01-on) <b>Lube</b> ..... <b>B7116</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>Radial Seal Air</b> ..... <b>RS4775</b> <b>Cab Air</b> ..... <b>PA3980</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> ..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>	TGM 18.240 w/D0836 Eng. (11/05-on) <b>Lube</b> ..... <b>P7196</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>414.3 mm Radial Seal Air</b> (81084050022)..... <b>RS5409</b> <b>457.2 mm Radial Seal Air</b> (Mann 81084050018)..... <b>RS5506</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>	TGM 18.280 w/D0836 Eng. (11/05-on) <b>Lube</b> ..... <b>P7196</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>414.3 mm Radial Seal Air</b> (81084050022)..... <b>RS5409</b> <b>457.2 mm Radial Seal Air</b> (Mann 81084050018)..... <b>RS5506</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>
18.224, 18.264 w/D0826 Eng. <b>Lube</b> (51055017160)..... <b>B7116</b> <b>Fuel/Water Separator</b> (Mann WDK724)..... <b>BF1372</b> <b>377.0 mm Some Air</b> (Mann C24508)..... <b>PA3760</b> <b>381.0 mm Air</b> (81083040036)..... <b>PA2474</b> <b>Some Radial Seal Air</b> (Mann C25730/1)..... <b>RS4775</b> <b>Cab Air</b> (Mann CU40110)..... <b>PA3980</b>	TGM 18.250 w/D0836 Eng. (09/08-on) <b>Lube</b> ..... <b>P7196</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>414.3 mm Radial Seal Air</b> (81084050022)..... <b>RS5409</b> <b>457.2 mm Radial Seal Air</b> (Mann 81084050018)..... <b>RS5506</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b> <b>Air Dryer</b> (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>	M2000 Evo LE 18.280 BB, M2000 Evo LE 18.280 BL, M2000 Evo LE 18.280 LL w/D0836LF Eng. (05/01-on) <b>Lube</b> ..... <b>B7116</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>Radial Seal Air</b> ..... <b>RS4775</b> <b>Cab Air</b> ..... <b>PA3980</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> ..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>
M2000 Evo 18.224FK, M2000 Evo 18.224 FL Dist, M2000 Evo 18.224 FL Urban w/D0836LF(04) Eng. (05/01-on) <b>Lube</b> ..... <b>B7116</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>Radial Seal Air</b> ..... <b>RS4775</b> <b>Cab Air</b> ..... <b>PA3980</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> ..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>	M2000 Evo 18.284FK, M2000 Evo 18.284FL Dist, M2000 Evo 18.284FL Urban w/D0836LF Eng. (05/01-on) <b>Lube</b> ..... <b>B7116</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>Radial Seal Air</b> ..... <b>RS4775</b> <b>Cab Air</b> ..... <b>PA3980</b>	18.284 w/D0836 Eng. <b>Lube</b> (Mann W1160)..... <b>B7116</b> <b>Fuel/Water Separator</b> (Mann WDK724)..... <b>BF1372</b> <b>Air</b> (Mann C24508)..... <b>PA3760</b> <b>Radial Seal Air</b> (Mann C25730/1)..... <b>RS4775</b> <b>Cab Air</b> (Mann CU40110)..... <b>PA3980</b>
M2000 Evo 18.225 w/D0836LF Eng. (05/01-on) <b>Lube</b> ..... <b>B7116</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>Radial Seal Air</b> ..... <b>RS4775</b> <b>Cab Air</b> ..... <b>PA3980</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> ..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>	M2000 Evo 18.284FK, M2000 Evo 18.284FL Dist, M2000 Evo 18.284FL Urban w/D0836LF Eng. (05/01-on) <b>Lube</b> ..... <b>B7116</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>Radial Seal Air</b> ..... <b>RS4775</b> <b>Cab Air</b> ..... <b>PA3980</b>	M2000 Evo 18.284FK, M2000 Evo 18.284FL Dist, M2000 Evo 18.284FL Urban w/D0836LF Eng. (05/01-on) <b>Lube</b> ..... <b>B7116</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>Radial Seal Air</b> ..... <b>RS4775</b> <b>Cab Air</b> ..... <b>PA3980</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)
M2000 Evo 18.284FK, M2000 Evo 18.284FL Dist, M2000 Evo 18.284FL Urban w/D0836LF Eng. (05/01-on) (Cont'd) Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer..... <b>BA5379 +</b> Steering (81473016005)..... <b>P106-HD</b>	TGM 18.290 w/D0836 Eng. (09/08-on) (Cont'd) Cab Air (w/Carbon) (81619100019)..... <b>PA5477</b> Air Dryer (Coalescer) (81521086025)..... <b>BA5379 +</b> Air Dryer (Desiccant) (Mann TB1374x)..... <b>BA5374 +</b> Steering (81473016005)..... <b>P106-HD</b> Urea (81154036015)..... <b>PE5270</b>	TGS 18.320 w/D2066 (Euro 4/5) Eng. (10/07-on) Lube..... <b>P7329</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> Fuel/Water Separator..... <b>BF7912</b> Radial Seal O. Air..... <b>RS4971</b> Radial Seal I. Air..... <b>RS5361</b> Cab Air (w/o Carbon) (81619100018)..... <b>PA4955</b> Cab Air (w/Carbon) (81619100019)..... <b>PA5477</b> Air Dryer (Desiccant)..... <b>BA5374 +</b> Air Dryer (Coalescer) (81521086025)..... <b>BA5379 +</b> Steering (81473016005)..... <b>P106-HD</b> Urea (81154036015)..... <b>PE5270</b>
M2000 Evo 18.284FLT Dist w/D0836LF Eng. (05/01-on) Lube..... <b>B7116</b> Fuel/Water Separator (51125030040)..... <b>BF1372</b> Radial Seal Air..... <b>RS4775</b> Cab Air..... <b>PA3980</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer..... <b>BA5379 +</b> Steering (81473016005)..... <b>P106-HD</b>	TGA 18.312 Series w/D2866LF Eng. (05/00-03/04) Lube (51055040098)..... <b>P7190</b> Fuel/Water Separator (81125030086)..... <b>BF7912</b> Fuel Pre-filter (51125030062)..... <b>PF7939</b> Fuel..... <b>PF7878</b> Radial Seal O. Air..... <b>RS4971</b> Radial Seal I. Air (81084050017)..... <b>RS5361</b> Cab Air (w/o Carbon) (81619100018)..... <b>PA4955</b> Cab Air (w/Carbon) (81619100019)..... <b>PA5477</b> Air Dryer (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer (Coalescer) (81521086025)..... <b>BA5379 +</b> Steering (81473016005)..... <b>P106-HD</b>	TGM 18.330 w/D0836 Eng. (11/05-on) Lube..... <b>P7196</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> <b>414.3 mm Radial Seal Air</b> (81084050022)..... <b>RS5409</b> <b>457.2 mm Radial Seal Air</b> (Mann 81084050018)..... <b>RS5506</b> Cab Air (w/o Carbon) (81619100018)..... <b>PA4955</b> Cab Air (w/Carbon) (81619100019)..... <b>PA5477</b> Air Dryer (81521086025)..... <b>BA5379 +</b> Steering (81473016005)..... <b>P106-HD</b> Urea (81154036015)..... <b>PE5270</b>
M2000 Evo 18.285 L/M w/D0836 Eng. (05/01-on) Lube..... <b>B7116</b> Fuel/Water Separator (51125030040)..... <b>BF1372</b> Radial Seal Air..... <b>RS4775</b> Cab Air..... <b>PA3980</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer..... <b>BA5379 +</b> Steering (81473016005)..... <b>P106-HD</b>	TGA 18.313 Series w/D2866LF Eng. (05/00-03/04) Lube (51055040098)..... <b>P7190</b> Fuel Pre-filter (51125030062)..... <b>PF7939</b> Fuel..... <b>PF7878</b> Radial Seal O. Air..... <b>RS4971</b> Radial Seal I. Air (81084050017)..... <b>RS5361</b> Cab Air (w/o Carbon) (81619100018)..... <b>PA4955</b> Cab Air (w/Carbon) (81619100019)..... <b>PA5477</b> Air Dryer (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer (Coalescer) (81521086025)..... <b>BA5379 +</b> Steering (81473016005)..... <b>P106-HD</b>	TGM 18.340 w/D0836 Eng. (09/08-on) Lube..... <b>P7196</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> <b>414.3 mm Radial Seal Air</b> (81084050022)..... <b>RS5409</b> <b>457.2 mm Radial Seal Air</b> (Mann 81084050018)..... <b>RS5506</b> Cab Air (w/o Carbon) (81619100018)..... <b>PA4955</b> Cab Air (w/Carbon) (81619100019)..... <b>PA5477</b> Air Dryer (Coalescer) (81521086025)..... <b>BA5379 +</b> Air Dryer (Desiccant) (Mann TB1374x)..... <b>BA5374 +</b> Steering (81473016005)..... <b>P106-HD</b> Urea (81154036015)..... <b>PE5270</b>
M2000 Evo 18.285 LAERK, M2000 Evo 18.285 LARK, M2000 Evo 18.285 LLRC w/D0836LF Eng. (05/01-on) Lube..... <b>B7116</b> Fuel/Water Separator (51125030040)..... <b>BF1372</b> Radial Seal Air..... <b>RS4775</b> Cab Air..... <b>PA3980</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer..... <b>BA5379 +</b> Steering (81473016005)..... <b>P106-HD</b>	TGS 18.320 w/w/D 2066 (Euro 6) Eng. (09/12-on) Lube (51055010009)..... <b>P40042</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> Radial Seal O. Air (81084050033)..... <b>RS4971</b> Radial Seal I. Air (81084050017)..... <b>RS5361</b> Cab Air (w/o Charcoal) (81619100018)..... <b>PA4955</b> Cab Air (w/Charcoal) (81619100019)..... <b>PA5477</b> Air Dryer (81521086025)..... <b>BA5379 +</b> Steering (81473016005)..... <b>P106-HD</b> Urea (81154036015)..... <b>PE5270</b>	TGS 18.360 w/w/D 2066 (Euro 6) Eng. (09/12-on) Lube (51055010009)..... <b>P40042</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> Radial Seal O. Air (81084050033)..... <b>RS4971</b> Radial Seal I. Air (81084050017)..... <b>RS5361</b> Cab Air (w/o Charcoal) (81619100018)..... <b>PA4955</b>
M2000 Evo 18.285 LRK, M2000 Evo 18.285 MLRC w/D0836LF Eng. (05/01-on) Lube..... <b>B7116</b> Fuel/Water Separator (51125030040)..... <b>BF1372</b> Radial Seal Air..... <b>RS4775</b> Cab Air..... <b>PA3980</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer..... <b>BA5379 +</b> Steering (81473016005)..... <b>P106-HD</b>		
TGM 18.290 w/D0836 Eng. (09/08-on) Lube..... <b>P7196</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> <b>414.3 mm Radial Seal Air</b> (81084050022)..... <b>RS5409</b> <b>457.2 mm Radial Seal Air</b> (Mann 81084050018)..... <b>RS5506</b> Cab Air (w/o Carbon) (81619100018)..... <b>PA4955</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)
TGS 18.360 w/w/D 2066 (Euro 6) Eng. (09/12-on) (Cont'd)	TGA 18.362 Series w/D2866LF Eng. (05/00-03/04) (Cont'd)	TGX 18.400 w/D2066 (Euro 4/5) Eng. (10/07-on) (Cont'd)
Cab Air (w/Charcoal) (81619100019)..... PA5477	Fuel Pre-filter (51125030062)..... PF7939	Cab Air (w/Carbon) (81619100019)..... PA5477
Air Dryer (81521086025)..... BA5379 +	Fuel..... PF7878	Air Dryer (Desiccant)..... BA5374 +
Steering (81473016005)..... P106-HD	Radial Seal O. Air..... RS4971	Air Dryer (Coalescer) (81521086025)..... BA5379 +
Urea (81154036015)..... PE5270	Radial Seal I. Air (81084050017)..... RS5361	Steering (81473016005)..... P106-HD
TGX 18.360 w/D 2066 (Euro 6) Eng. (09/12-on)	Cab Air (w/o Carbon) (81619100018)..... PA4955	Urea (81154036015)..... PE5270
Lube (51055010009)..... P40042	Cab Air (w/Carbon) (81619100019)..... PA5477	TGS 18.400 w/w/D 2066 (Euro 6) Eng. (09/12-on)
P. Fuel (51125030063)..... PF7935	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	Lube (51055010009)..... P40042
S. Fuel (51125030062)..... PF7939	Air Dryer (Coalescer) (81521086025)..... BA5379 +	P. Fuel (51125030063)..... PF7935
Radial Seal O. Air (81084050033)..... RS4971	Steering (81473016005)..... P106-HD	S. Fuel (51125030062)..... PF7939
Radial Seal I. Air (81084050017)..... RS5361	TGA 18.363 Series w/D2866LF Eng. (05/00-03/04)	Radial Seal O. Air (81084050033)..... RS4971
Cab Air (w/o Charcoal) (81619100018)..... PA4955	Lube (51055040098)..... P7190	Radial Seal I. Air (81084050017)..... RS5361
Cab Air (w/Charcoal) (81619100019)..... PA5477	Fuel/Water Separator (81125030086)..... BF7912	Cab Air (w/o Charcoal) (81619100018)..... PA4955
Air Dryer (81521086025)..... BA5379 +	Fuel Pre-filter (51125030062)..... PF7939	Cab Air (w/Charcoal) (81619100019)..... PA5477
Steering (81473016005)..... P106-HD	Fuel..... PF7878	Air Dryer (81521086025)..... BA5379 +
Urea (81154036015)..... PE5270	Radial Seal O. Air..... RS4971	Steering (81473016005)..... P106-HD
TGS 18.360 w/D2066 (Euro 4/5) Eng. (10/07-on)	Radial Seal I. Air (81084050017)..... RS5361	Urea (81154036015)..... PE5270
Lube..... P7329	Cab Air (w/o Carbon) (81619100018)..... PA4955	TGX 18.400 w/D 2066 (Euro 6) Eng. (09/12-on)
P. Fuel (51125030063)..... PF7935	Cab Air (w/Carbon) (81619100019)..... PA5477	Lube (51055010009)..... P40042
S. Fuel (51125030062)..... PF7939	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	P. Fuel (51125030063)..... PF7935
Fuel/Water Separator..... BF7912	Air Dryer (Coalescer) (81521086025)..... BA5379 +	S. Fuel (51125030062)..... PF7939
Radial Seal O. Air..... RS4971	Steering (81473016005)..... P106-HD	Radial Seal O. Air (81084050033)..... RS4971
Radial Seal I. Air..... RS5361	TGS 18.400 w/D2066 (Euro 4/5) Eng. (10/07-on)	Radial Seal I. Air (81084050017)..... RS5361
Cab Air (w/o Carbon) (81619100018)..... PA4955	Lube..... P7329	Cab Air (w/o Charcoal) (81619100018)..... PA4955
Cab Air (w/Carbon) (81619100019)..... PA5477	P. Fuel (51125030063)..... PF7935	Cab Air (w/Carbon) (81619100019)..... PA5477
Air Dryer (Desiccant)..... BA5374 +	S. Fuel (51125030062)..... PF7939	Air Dryer (81521086025)..... BA5379 +
Air Dryer (Coalescer) (81521086025)..... BA5379 +	Fuel/Water Separator..... BF7912	Steering (81473016005)..... P106-HD
Steering (81473016005)..... P106-HD	Radial Seal O. Air..... RS4971	Urea (81154036015)..... PE5270
Urea (81154036015)..... PE5270	Radial Seal I. Air..... RS5361	TGA 18.410 Series w/D2866LF Eng. (05/00-03/04)
TGX 18.360 w/D2066 (Euro 4/5) Eng. (10/07-on)	Cab Air (w/o Carbon) (81619100018)..... PA4955	Lube (51055040098)..... P7190
Lube..... P7329	Cab Air (w/Carbon) (81619100019)..... PA5477	Fuel/Water Separator (81125030086)..... BF7912
P. Fuel (51125030063)..... PF7935	Air Dryer (Desiccant)..... BA5374 +	Fuel Pre-filter (51125030062)..... PF7939
S. Fuel (51125030062)..... PF7939	Air Dryer (Coalescer) (81521086025)..... BA5379 +	Fuel..... PF7878
Fuel/Water Separator..... BF7912	Steering (81473016005)..... P106-HD	Radial Seal O. Air..... RS4971
Radial Seal O. Air..... RS4971	Urea (81154036015)..... PE5270	Radial Seal I. Air (81084050017)..... RS5361
Radial Seal I. Air..... RS5361	TGX 18.400 w/D2066 (Euro 4/5) Eng. (10/07-on)	Cab Air (w/o Carbon) (81619100018)..... PA4955
Cab Air (w/o Carbon) (81619100018)..... PA4955	Lube..... P7329	Cab Air (w/Carbon) (81619100019)..... PA5477
Cab Air (w/Carbon) (81619100019)..... PA5477	P. Fuel (51125030063)..... PF7935	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +
Air Dryer (Desiccant)..... BA5374 +	S. Fuel (51125030062)..... PF7939	Air Dryer (Coalescer) (81521086025)..... BA5379 +
Air Dryer (Coalescer) (81521086025)..... BA5379 +	Fuel/Water Separator..... BF7912	Steering (81473016005)..... P106-HD
Steering (81473016005)..... P106-HD	Radial Seal O. Air..... RS4971	Urea (81154036015)..... PE5270
Urea (81154036015)..... PE5270	Radial Seal I. Air..... RS5361	TGA 18.362 Series w/D2866LF Eng. (05/00-03/04)
TGX 18.360 w/D2066 (Euro 4/5) Eng. (10/07-on)	Cab Air (w/o Carbon) (81619100018)..... PA4955	Lube (51055040098)..... P7190
Lube..... P7329	Cab Air (w/Carbon) (81619100019)..... PA5477	Fuel/Water Separator (81125030086)..... BF7912
P. Fuel (51125030063)..... PF7935	Air Dryer (Desiccant)..... BA5374 +	Fuel Pre-filter (51125030062)..... PF7939
S. Fuel (51125030062)..... PF7939	Air Dryer (Coalescer) (81521086025)..... BA5379 +	Fuel..... PF7878
Fuel/Water Separator..... BF7912	Steering (81473016005)..... P106-HD	Radial Seal O. Air..... RS4971
Radial Seal O. Air..... RS4971	Urea (81154036015)..... PE5270	Radial Seal I. Air (81084050017)..... RS5361
Radial Seal I. Air..... RS5361	TGX 18.400 w/D2066 (Euro 4/5) Eng. (10/07-on)	Cab Air (w/o Carbon) (81619100018)..... PA4955
Cab Air (w/o Carbon) (81619100018)..... PA4955	Lube..... P7329	Cab Air (w/Carbon) (81619100019)..... PA5477
Cab Air (w/Carbon) (81619100019)..... PA5477	P. Fuel (51125030063)..... PF7935	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +
Air Dryer (Desiccant)..... BA5374 +	S. Fuel (51125030062)..... PF7939	Air Dryer (Coalescer) (81521086025)..... BA5379 +
Air Dryer (Coalescer) (81521086025)..... BA5379 +	Fuel/Water Separator..... BF7912	Steering (81473016005)..... P106-HD
Steering (81473016005)..... P106-HD	Radial Seal O. Air..... RS4971	Urea (81154036015)..... PE5270
Urea (81154036015)..... PE5270	Radial Seal I. Air..... RS5361	TGA 18.410 Series w/D2866LF Eng. (05/00-03/04)
TGA 18.362 Series w/D2866LF Eng. (05/00-03/04)	Cab Air (w/o Carbon) (81619100018)..... PA4955	Lube (51055040098)..... P7190
Lube (51055040098)..... P7190	Cab Air (w/Carbon) (81619100019)..... PA5477	Fuel/Water Separator (81125030086)..... BF7912
Fuel/Water Separator (81125030086)..... BF7912	Air Dryer (Desiccant)..... BA5374 +	Fuel Pre-filter (51125030062)..... PF7939

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>M.A.N.</b> <b>European Trucks (cont'd)</b>	<b>M.A.N.</b> <b>European Trucks (cont'd)</b>	<b>M.A.N.</b> <b>European Trucks (cont'd)</b>
TGA 18.412 Series w/D2866LF Eng. (05/00-03/04)	TGX 18.440 w/D2066 (Euro 4/5) Eng. (10/07-on) (Cont'd)	TGA 18.460FLT w/D2866LF Eng. (05/00-03/04) (Cont'd)
Lube (51055040098)..... P7190	Radial Seal I. Air..... RS5361	Steering (81473016005)..... P106-HD
Fuel/Water Separator (81125030086)..... BF7912	Cab Air (w/o Carbon) (81619100018)..... PA4955	TGA 18.462 Series w/D2876LF Eng. (04/00-on)
Fuel Pre-filter (51125030062)..... PF7939	Cab Air (w/Carbon) (81619100019)..... PA5477	Lube (51055040098)..... P7190
Fuel..... PF7878	Air Dryer (Desiccant)..... BA5374 +	Fuel/Water Separator (81125030086)..... BF7912
Radial Seal O. Air..... RS4971	Air Dryer (Coalescer) (81521086025)..... BA5379 +	Fuel Pre-filter (51125030062)..... PF7939
Radial Seal I. Air (81084050017)..... RS5361	Steering (81473016005)..... P106-HD	Fuel..... PF7878
Cab Air (w/o Carbon) (81619100018)..... PA4955	Urea (81154036015)..... PE5270	Radial Seal O. Air..... RS4971
Cab Air (w/Carbon) (81619100019)..... PA5477	TGS 18.440 w/w/D 2066, D 2676 (Euro 6) Eng. (09/12-on)	Radial Seal I. Air (81084050017)..... RS5361
Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	Lube (51055010009)..... P40042	Cab Air (w/o Carbon) (81619100018)..... PA4955
Air Dryer (Coalescer) (81521086025)..... BA5379 +	P. Fuel (51125030063)..... PF7935	Cab Air (w/Carbon) (81619100019)..... PA5477
Steering (81473016005)..... P106-HD	S. Fuel (51125030062)..... PF7939	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +
TGA 18.413 Series w/D2866LF Eng. (05/00-03/04)	Radial Seal O. Air (81084050033)..... RS4971	Air Dryer (Coalescer) (81521086025)..... BA5379 +
Lube (51055040098)..... P7190	Radial Seal I. Air (81084050017)..... RS5361	Steering (81473016005)..... P106-HD
Fuel/Water Separator (81125030086)..... BF7912	Cab Air (w/o Charcoal) (81619100018)..... PA4955	TGS 18.440 w/D2066 (Euro 4/5) Eng. (10/07-on)
Fuel Pre-filter (51125030062)..... PF7939	Cab Air (w/Charcoal) (81619100019)..... PA5477	Lube..... P7329
Fuel..... PF7878	Air Dryer (81521086025)..... BA5379 +	P. Fuel (51125030063)..... PF7935
Radial Seal O. Air..... RS4971	Steering (81473016005)..... P106-HD	S. Fuel (51125030062)..... PF7939
Radial Seal I. Air (81084050017)..... RS5361	Urea (81154036015)..... PE5270	Fuel/Water Separator..... BF7912
Cab Air (w/o Carbon) (81619100018)..... PA4955	TGX 18.440 w/D 2066, D 2676 (Euro 6) Eng. (09/12-on)	Radial Seal O. Air..... RS4971
Cab Air (w/Carbon) (81619100019)..... PA5477	Lube (51055010009)..... P40042	Radial Seal I. Air (81084050017)..... RS5361
Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	P. Fuel (51125030063)..... PF7935	Cab Air (w/o Carbon) (81619100018)..... PA4955
Air Dryer (Coalescer) (81521086025)..... BA5379 +	S. Fuel (51125030062)..... PF7939	Cab Air (w/Carbon) (81619100019)..... PA5477
Steering (81473016005)..... P106-HD	Radial Seal O. Air (81084050033)..... RS4971	Air Dryer (Mann TB1374X)..... BA5374 +
TGS 18.440 w/D2066 (Euro 4/5) Eng. (10/07-on)	Radial Seal I. Air (81084050017)..... RS5361	Air Dryer (81521086025)..... BA5379 +
Lube..... P7329	Cab Air (w/o Charcoal) (81619100018)..... PA4955	Steering (81473016005)..... P106-HD
P. Fuel (51125030063)..... PF7935	Cab Air (w/Charcoal) (81619100019)..... PA5477	TGS 18.480 w/D2676 (Euro 4/5) Eng. (10/07-on)
S. Fuel (51125030062)..... PF7939	Air Dryer (81521086025)..... BA5379 +	Lube..... P7329
Fuel/Water Separator..... BF7912	Steering (81473016005)..... P106-HD	P. Fuel (51125030063)..... PF7935
Radial Seal O. Air..... RS4971	Urea (81154036015)..... PE5270	S. Fuel (51125030062)..... PF7939
Radial Seal I. Air..... RS5361	TGA 18.460FLT w/D2866LF Eng. (05/00-03/04)	Fuel/Water Separator..... BF7912
Cab Air (w/o Carbon) (81619100018)..... PA4955	Lube (51055040098)..... P7190	Radial Seal O. Air..... RS4971
Cab Air (w/Carbon) (81619100019)..... PA5477	Fuel/Water Separator (81125030086)..... BF7912	Radial Seal I. Air..... RS5361
Air Dryer (Desiccant)..... BA5374 +	Fuel..... PF7878	Cab Air (w/o Carbon) (81619100018)..... PA4955
Air Dryer (Coalescer) (81521086025)..... BA5379 +	Fuel Pre-filter (51125030062)..... PF7939	Cab Air (w/Carbon) (81619100019)..... PA5477
Steering (81473016005)..... P106-HD	Radial Seal O. Air..... RS4971	Air Dryer (Desiccant)..... BA5374 +
Urea (81154036015)..... PE5270	Radial Seal I. Air (81084050017)..... RS5361	Air Dryer (Coalescer) (81521086025)..... BA5379 +
TGX 18.440 w/D2066 (Euro 4/5) Eng. (10/07-on)	Cab Air (w/o Carbon) (81619100018)..... PA4955	Steering (81473016005)..... P106-HD
Lube..... P7329	Cab Air (w/Carbon) (81619100019)..... PA5477	Urea (81154036015)..... PE5270
P. Fuel (51125030063)..... PF7935	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	TGX 18.480 w/D2676 (Euro 4/5) Eng. (10/07-on)
S. Fuel (51125030062)..... PF7939	Air Dryer (Coalescer) (81521086025)..... BA5379 +	Lube..... P7329
Fuel/Water Separator..... BF7912		P. Fuel (51125030063)..... PF7935
Radial Seal O. Air..... RS4971		S. Fuel (51125030062)..... PF7939
		Fuel/Water Separator..... BF7912
		Radial Seal O. Air..... RS4971
		Radial Seal I. Air..... RS5361

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)
<b>TGX 18.480 w/D2676 (Euro 4/5) Eng. (10/07-on) (Cont'd)</b> <b>Cab Air (w/o Carbon)</b> (81619100018)..... <b>PA4955</b> <b>Cab Air (w/Carbon)</b> (81619100019)..... <b>PA5477</b> <b>Air Dryer (Desiccant)</b> ..... <b>BA5374 +</b> <b>Air Dryer (Coalescer)</b> (81521086025)..... <b>BA5379 +</b> <b>Steering (81473016005)</b> ..... <b>P106-HD</b> <b>Urea (81154036015)</b> ..... <b>PE5270</b>	<b>TGS 18.540 w/D2076 (Euro 4/5) Eng. (10/07-on)</b> <b>Lube</b> ..... <b>P7329</b> <b>P. Fuel (51125030063)</b> ..... <b>PF7935</b> <b>S. Fuel (51125030062)</b> ..... <b>PF7939</b> <b>Fuel/Water Separator</b> ..... <b>BF7912</b> <b>Radial Seal O. Air</b> ..... <b>RS4971</b> <b>Radial Seal I. Air</b> ..... <b>RS5361</b> <b>Cab Air (w/o Carbon)</b> (81619100018)..... <b>PA4955</b> <b>Cab Air (w/Carbon)</b> (81619100019)..... <b>PA5477</b> <b>Air Dryer (Desiccant)</b> ..... <b>BA5374 +</b> <b>Air Dryer (Coalescer)</b> (81521086025)..... <b>BA5379 +</b> <b>Steering (81473016005)</b> ..... <b>P106-HD</b> <b>Urea (81154036015)</b> ..... <b>PE5270</b>	<b>TGX 18.540 w/D 2676 (Euro 6) Eng. (09/12-on) (Cont'd)</b> <b>Steering (81473016005)</b> ..... <b>P106-HD</b> <b>Urea (81154036015)</b> ..... <b>PE5270</b> <hr/> <b>TGX 18.680 V8 w/D2868 (Euro 5) Eng. (10/07-on)</b> <b>Lube</b> ..... <b>P7329</b> <b>P. Fuel (51125030063)</b> ..... <b>PF7935</b> <b>S. Fuel (51125030062)</b> ..... <b>PF7939</b> <b>Fuel/Water Separator</b> ..... <b>BF7912</b> <b>Radial Seal O. Air</b> ..... <b>RS4971</b> <b>Radial Seal I. Air</b> ..... <b>RS5361</b> <b>Cab Air (w/o Carbon)</b> (81619100018)..... <b>PA4955</b> <b>Cab Air (w/Carbon)</b> (81619100019)..... <b>PA5477</b> <b>Air Dryer (Desiccant)</b> ..... <b>BA5374 +</b> <b>Air Dryer (Coalescer)</b> (81521086025)..... <b>BA5379 +</b> <b>Steering (81473016005)</b> ..... <b>P106-HD</b> <b>Urea (81154036015)</b> ..... <b>PE5270</b>
<b>TGS 18.480 w/w/D 2676 (Euro 6) Eng. (09/12-on)</b> <b>Lube (51055010009)</b> ..... <b>P40042</b> <b>P. Fuel (51125030063)</b> ..... <b>PF7935</b> <b>S. Fuel (51125030062)</b> ..... <b>PF7939</b> <b>Radial Seal O. Air</b> (81084050033)..... <b>RS4971</b> <b>Radial Seal I. Air (81084050017)</b> ..... <b>RS5361</b> <b>Cab Air (w/o Charcoal)</b> (81619100018)..... <b>PA4955</b> <b>Cab Air (w/Charcoal)</b> (81619100019)..... <b>PA5477</b> <b>Air Dryer (81521086025)</b> ..... <b>BA5379 +</b> <b>Steering (81473016005)</b> ..... <b>P106-HD</b> <b>Urea (81154036015)</b> ..... <b>PE5270</b>	<b>TGX 18.540 w/D2676 (Euro 4/5) Eng. (10/07-on)</b> <b>Lube</b> ..... <b>P7329</b> <b>P. Fuel (51125030063)</b> ..... <b>PF7935</b> <b>S. Fuel (51125030062)</b> ..... <b>PF7939</b> <b>Fuel/Water Separator</b> ..... <b>BF7912</b> <b>Radial Seal O. Air</b> ..... <b>RS4971</b> <b>Radial Seal I. Air</b> ..... <b>RS5361</b> <b>Cab Air (w/o Carbon)</b> (81619100018)..... <b>PA4955</b> <b>Cab Air (w/Carbon)</b> (81619100019)..... <b>PA5477</b> <b>Air Dryer (Desiccant)</b> ..... <b>BA5374 +</b> <b>Air Dryer (Coalescer)</b> (81521086025)..... <b>BA5379 +</b> <b>Steering (81473016005)</b> ..... <b>P106-HD</b> <b>Urea (81154036015)</b> ..... <b>PE5270</b>	<b>19.168 w/D2555 Eng.</b> <b>Lube (81055040040)</b> ..... <b>P242</b> <b>115.1 mm P. Fuel (81125030050)</b> ..... <b>F953-F</b> <b>142.9 mm P. Fuel (81125030011)</b> ..... <b>F950-F</b> <b>108.7 mm S. Fuel (81125030041)</b> ..... <b>PF834</b> <b>148.4 mm S. Fuel (81125030042)</b> ..... <b>PF231</b> <b>O. Air (81083040036)</b> ..... <b>PA2474</b> <b>I. Air</b> ..... <b>PA2836</b> <b>Single Air (81083040024)</b> ..... <b>PA3605</b> <b>Steering (81055040007)</b> ..... <b>PT691</b>
<b>TGX 18.480 w/D 2676 (Euro 6) Eng. (09/12-on)</b> <b>Lube (51055010009)</b> ..... <b>P40042</b> <b>P. Fuel (51125030063)</b> ..... <b>PF7935</b> <b>S. Fuel (51125030062)</b> ..... <b>PF7939</b> <b>Radial Seal O. Air</b> (81084050033)..... <b>RS4971</b> <b>Radial Seal I. Air (81084050017)</b> ..... <b>RS5361</b> <b>Cab Air (w/o Charcoal)</b> (81619100018)..... <b>PA4955</b> <b>Cab Air (w/Charcoal)</b> (81619100019)..... <b>PA5477</b> <b>Air Dryer (81521086025)</b> ..... <b>BA5379 +</b> <b>Steering (81473016005)</b> ..... <b>P106-HD</b> <b>Urea (81154036015)</b> ..... <b>PE5270</b>	<b>TGS 18.540 w/w/D 2676 (Euro 6) Eng. (09/12-on)</b> <b>Lube (51055010009)</b> ..... <b>P40042</b> <b>P. Fuel (51125030063)</b> ..... <b>PF7935</b> <b>S. Fuel (51125030062)</b> ..... <b>PF7939</b> <b>Radial Seal O. Air</b> (81084050033)..... <b>RS4971</b> <b>Radial Seal I. Air (81084050017)</b> ..... <b>RS5361</b> <b>Cab Air (w/o Charcoal)</b> (81619100018)..... <b>PA4955</b> <b>Cab Air (w/Charcoal)</b> (81619100019)..... <b>PA5477</b> <b>Air Dryer (81521086025)</b> ..... <b>BA5379 +</b> <b>Steering (81473016005)</b> ..... <b>P106-HD</b> <b>Urea (81154036015)</b> ..... <b>PE5270</b>	<b>19.200 w/D2556 Eng.</b> <b>Lube (81055040025)</b> ..... <b>P721</b> <b>115.1 mm P. Fuel (81125030050)</b> ..... <b>F953-F</b> <b>142.9 mm P. Fuel (81125030011)</b> ..... <b>F950-F</b> <b>108.7 mm S. Fuel (81125030041)</b> ..... <b>PF834</b> <b>148.4 mm S. Fuel (81125030042)</b> ..... <b>PF231</b> <b>O. Air (81083040036)</b> ..... <b>PA2474</b> <b>I. Air</b> ..... <b>PA2836</b> <b>Hyd. (81055040007)</b> ..... <b>PT691</b>
<b>TGA 18.513 w/D2876LF Eng. (04/00-on)</b> <b>Lube (51055040098)</b> ..... <b>P7190</b> <b>Fuel/Water Separator</b> (81125030086)..... <b>BF7912</b> <b>Fuel Pre-filter (51125030062)</b> ..... <b>PF7939</b> <b>Fuel</b> ..... <b>PF7878</b> <b>Radial Seal O. Air</b> ..... <b>RS4971</b> <b>Radial Seal I. Air (81084050017)</b> ..... <b>RS5361</b> <b>Cab Air (w/o Carbon)</b> (81619100018)..... <b>PA4955</b> <b>Cab Air (w/Carbon)</b> (81619100019)..... <b>PA5477</b> <b>Air Dryer (Desiccant) (Mann TB1374X)</b> ..... <b>BA5374 +</b> <b>Air Dryer (Coalescer)</b> (81521086025)..... <b>BA5379 +</b> <b>Steering (81473016005)</b> ..... <b>P106-HD</b>	<b>TGX 18.540 w/D 2676 (Euro 6) Eng. (09/12-on)</b> <b>Lube (51055010009)</b> ..... <b>P40042</b> <b>P. Fuel (51125030063)</b> ..... <b>PF7935</b> <b>S. Fuel (51125030062)</b> ..... <b>PF7939</b> <b>Radial Seal O. Air</b> (81084050033)..... <b>RS4971</b> <b>Radial Seal I. Air (81084050017)</b> ..... <b>RS5361</b> <b>Cab Air (w/o Charcoal)</b> (81619100018)..... <b>PA4955</b> <b>Cab Air (w/Charcoal)</b> (81619100019)..... <b>PA5477</b> <b>Air Dryer (81521086025)</b> ..... <b>BA5379 +</b> <b>Steering (81473016005)</b> ..... <b>P106-HD</b> <b>Urea (81154036015)</b> ..... <b>PE5270</b>	<b>19.215, 19.230 w/D2146, D2156, D2356 Engs.</b> <b>Lube (81055040032)</b> ..... <b>P235</b> <b>P. Fuel Ele. (81125030011)</b> ..... <b>F950-F</b> <b>S. Fuel Ele. (81125030042)</b> ..... <b>PF231</b> <b>Hyd. (81055040007)</b> ..... <b>PT691</b>
	<b>TGX 18.540 w/D 2676 (Euro 6) Eng. (09/12-on)</b> <b>Lube (51055010009)</b> ..... <b>P40042</b> <b>P. Fuel (51125030063)</b> ..... <b>PF7935</b> <b>S. Fuel (51125030062)</b> ..... <b>PF7939</b> <b>Radial Seal O. Air</b> (81084050033)..... <b>RS4971</b> <b>Radial Seal I. Air (81084050017)</b> ..... <b>RS5361</b> <b>Cab Air (w/o Charcoal)</b> (81619100018)..... <b>PA4955</b> <b>Cab Air (w/Charcoal)</b> (81619100019)..... <b>PA5477</b> <b>Air Dryer (81521086025)</b> ..... <b>BA5379 +</b>	<b>19.233 w/E2886 Eng.</b> <b>Lube (To 2/98) (Mann HU947/2x)</b> ..... <b>P7145</b> <b>Lube (2/98-on) (Mann HU1381x)</b> ..... <b>P7190</b> <b>Radial Seal O. Air (Mann C301353)</b> ..... <b>RS3714</b>

+ See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)
19.233 w/E2886 Eng. (Cont'd) Radial Seal I. Air (Mann C17170)..... <b>RS4549</b> Cab Air (Mann CU40110)..... <b>PA3980</b>	19.256 w/D2538 Eng. Lube (81055040041)..... <b>P294</b> 115.1 mm P. Fuel (81125030050)..... <b>F953-F</b> 142.9 mm P. Fuel (81125030011)..... <b>F950-F</b> 108.7 mm S. Fuel (81125030041)..... <b>PF834</b> 148.4 mm S. Fuel (81125030042)..... <b>PF231</b> O. Air (81082050005)..... <b>PA2475</b> I. Air..... <b>PA2814</b> Hyd. (81055040007)..... <b>PT691</b>	19.281 w/D2566, D2566MK, D2566MKF Engs. Lube (81055040041)..... <b>P294</b> P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> O. Air (81083040038)..... <b>PA2776</b> I. Air..... <b>PA3494</b>
19.240 w/U12D Eng. Lube (81055040041)..... <b>P294</b> P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> Fuel Spin-on (81125030075)..... <b>BF587-D +</b> Air..... <b>PA3572</b> Hyd. (81055040007)..... <b>PT691</b>	19.262 w/D2865 Eng. 188.1 mm Lube (1989-on) (81055040038)..... <b>P242</b> 264.3 mm F-F Lube (81055040041)..... <b>P294</b> Fuel Ele. (81125030042)..... <b>PF231</b> Fuel Spin-on (81125030075)..... <b>BF587-D +</b> Air (81083040038)..... <b>PA2776</b>	19.291 w/D2866 Eng. P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> O. Air (81083040043)..... <b>PA2776</b>
19.240 w/D2556 Eng. Lube (81055040025)..... <b>P721</b> 115.1 mm P. Fuel (81125030050)..... <b>F953-F</b> 142.9 mm P. Fuel (81125030011)..... <b>F950-F</b> 108.7 mm S. Fuel (81125030041)..... <b>PF834</b> 148.4 mm S. Fuel (81125030042)..... <b>PF231</b> O. Air (81083040036)..... <b>PA2474</b> I. Air..... <b>PA2836</b> Hyd. (81055040007)..... <b>PT691</b>	19.264 w/D0826 Eng. Lube (Mann W1160)..... <b>B7116</b> O. Air (Mann C24508)..... <b>PA3760</b> Some Radial Seal Air (Mann C25730/1)..... <b>RS4775</b> Cab Air (Mann CU40110)..... <b>PA3980</b>	19.292 w/D2866 Eng. Lube (81055040041)..... <b>P294</b> P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> Fuel Spin-on (81125030075)..... <b>BF587-D +</b> Air (81083040038)..... <b>PA2776</b>
19.240 w/D2566 Eng. Lube Ele. (81055040041)..... <b>P294</b> P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> 377.8 mm Air..... <b>PA2813</b> 381.0 mm Air (81083040036)..... <b>PA2474</b> 495.3 mm Air (81055040033)..... <b>PA3572</b> Hyd. (81055040007)..... <b>PT691</b>	19.272 w/D2865 Eng. 188.1 mm Lube (To 1989) (81055040038)..... <b>P242</b> 264.3 mm Lube (81055040041)..... <b>P294</b> Fuel Ele. (81125030042)..... <b>PF231</b> Fuel Spin-on (81125030075)..... <b>BF587-D +</b> O. Air (81083040038)..... <b>PA2776</b>	19.293 w/D2865 Eng. (01/94-04/96) Lube Ele. (1/94-1/95) (Mann HU947/1n)..... <b>P7305</b> Lube Ele. (2/95-8/96) (51055040096)..... <b>P7145</b> Fuel/Water Separator (Mann WDK724)..... <b>BF1372</b> Radial Seal O. Air (Mann C301353)..... <b>RS3714</b> Radial Seal I. Air (Mann C17170)..... <b>RS4549</b> Cab Air (Mann CU40110)..... <b>PA3980</b>
19.240U w/U12D Eng. Lube (81055040041)..... <b>P294</b> P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> Fuel Spin-on (81125030075)..... <b>BF587-D +</b> Air..... <b>PA3572</b> Hyd. (81055040007)..... <b>PT691</b>	19.273 w/D2865, D2875 Engs. Radial Seal O. Air (81083040094)..... <b>RS3714</b> Radial Seal I. Air (81083040084)..... <b>RS4549</b>	F2000 19.293 w/D2865 Eng. (05/96-on) Lube..... <b>P7190</b> Fuel/Water Separator (51125030040)..... <b>BF1372</b> Radial Seal O. Air..... <b>RS3714</b> Radial Seal I. Air..... <b>RS4549</b> Cab Air..... <b>PA3980</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer..... <b>BA5379 +</b> Trans. (ZF Gearbox)..... <b>PT8385</b>
19.241U w/D2566 Eng. Lube (81055040041)..... <b>P294</b> P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> Air (81083040041)..... <b>PA2475</b>	19.275 w/D2758 Eng. Lube (81055040025)..... <b>P721</b> P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> Hyd. (81055040007)..... <b>PT691</b>	19.304 w/D2758, D2858 Engs. Lube (81055040025)..... <b>P721</b> P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> Hyd. (81055040007)..... <b>PT691</b>
19.242 w/D2866 Eng. Lube (81055040041)..... <b>P294</b> P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> Fuel Spin-on (81125030075)..... <b>BF587-D +</b> Air (81083040038)..... <b>PA2776</b>	19.280 w/D2566MT Eng. Lube (81055040041)..... <b>P294</b> P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> 496.9 mm O. Air (81082050005)..... <b>PA2475</b> 473.1 mm I. Air..... <b>PA2814</b> 473.9 mm O. Air..... <b>PA2776</b> Hyd. (81055040007)..... <b>PT691</b>	19.314 w/D2866 Eng. Lube (Mann HU1381X)..... <b>P7190</b> Fuel/Water Separator (Mann WDK724)..... <b>BF1372</b> Radial Seal O. Air (Mann C301353)..... <b>RS3714</b> Radial Seal I. Air (Mann C17170)..... <b>RS4549</b> Cab Air (Mann CU40110)..... <b>PA3980</b>
19.250, 19.256 w/D2146, D2156, D2356 Engs. Lube (81055040032)..... <b>P235</b> P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> Hyd. (81055040007)..... <b>PT691</b>	19.280U w/U12D Eng. Lube (88055040003)..... <b>PT86-HD</b> P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> Air (81055040033)..... <b>PA3572</b>	19.320U w/D3256BXUL (U12D) Eng. P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> Air (81055040033)..... <b>PA3572</b> Hyd. (81055040007)..... <b>PT691</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)
19.321, 19.321U w/D2566, D2566MK, D2566MKF Engs. <b>Lube</b> (81055040041)..... <b>P294</b> <b>P. Fuel Ele.</b> (81125030011)..... <b>F950-F</b> <b>S. Fuel Ele.</b> (81125030042)..... <b>PF231</b> <b>O. Air</b> (81083040038)..... <b>PA2776</b> <b>I. Air</b> (81084050013)..... <b>PA3494</b>	19.332 w/D2866 Eng. <b>Lube</b> (81055040039)..... <b>P294</b> <b>Fuel Ele.</b> (81125030021)..... <b>PF950</b> <b>Fuel Spin-on</b> (81125030075)..... <b>BF587-D +</b> <b>Air</b> (81083040043)..... <b>PA2776</b>	19.343 w/E2866 (Gas) Eng. <b>Lube</b> (1/94-1/95) (Mann HU947/1n)..... <b>P7305</b> <b>Lube</b> (2/95-8/96) (Mann HU947/2x)..... <b>P7145</b> <b>Lube</b> (9/96-on) (Mann HU1381x)..... <b>P7190</b> <b>Radial Seal O. Air</b> (Mann C301353)..... <b>RS3714</b> <b>Radial Seal I. Air</b> (Mann C17170)..... <b>RS4549</b> <b>Cab Air</b> (Mann CU40110)..... <b>PA3980</b> <b>Trans.</b> (Mann H710/1n)..... <b>PT8385</b>
19.322 w/D2865 Eng. <b>188.1 mm Lube</b> (1989-on) (81055040038)..... <b>P242</b> <b>264.3 mm F-F Lube</b> (81055040041)..... <b>P294</b> <b>P. Fuel Ele.</b> (81125030011)..... <b>F950-F</b> <b>S. Fuel Ele.</b> (81125030042)..... <b>PF231</b> <b>Fuel Spin-on</b> (81125030075)..... <b>BF587-D +</b> <b>Air</b> (81083040038)..... <b>PA2776</b>	19.342 w/D2865 Eng. <b>Lube Ele.</b> (1/94-1/95) (Mann HU947/1n)..... <b>P7305</b> <b>Lube Ele.</b> (2/95-on) (51055040096)..... <b>P7145</b> <b>Fuel/Water Separator</b> (Mann WDK724)..... <b>BF1372</b> <b>Radial Seal O. Air</b> (Mann C301353)..... <b>RS3714</b> <b>Radial Seal I. Air</b> (Mann C17170)..... <b>RS4549</b> <b>Cab Air</b> (Mann CU40110)..... <b>PA3980</b>	TGS 19.360 w/w/D 2066 (Euro 6) Eng. (09/12-on) <b>Lube</b> (51055010009)..... <b>P40042</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>Radial Seal O. Air</b> (81084050033)..... <b>RS4971</b> <b>Radial Seal I. Air</b> (81084050017)..... <b>RS5361</b> <b>Cab Air</b> (w/o Charcoal) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Charcoal) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>
19.323 w/D2865 Eng. (01/94-04/96) <b>Lube Ele.</b> (1/94-1/95) (Mann HU947/1n)..... <b>P7305</b> <b>Lube Ele.</b> (2/95-4/96) (51055040096)..... <b>P7145</b> <b>Fuel/Water Separator</b> (Mann WDK724)..... <b>BF1372</b> <b>Radial Seal O. Air</b> (Mann C301353)..... <b>RS3714</b> <b>Radial Seal I. Air</b> (Mann C17170)..... <b>RS4549</b> <b>Cab Air</b> (Mann CU40110)..... <b>PA3980</b>	TGM 13.240 w/D0836 Eng. (04/06-on) <b>Lube</b> ..... <b>P7196</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>414.3 mm Radial Seal Air</b> (81084050022)..... <b>RS5409</b> <b>457.2 mm Radial Seal Air</b> (Mann 81084050018)..... <b>RS5506</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b> <b>Steering</b> ..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>	19.360 w/D2530, D2530MTXF Engs. <b>P. Fuel Ele.</b> (81125030011)..... <b>F950-F</b> <b>S. Fuel Ele.</b> (81125030042)..... <b>PF231</b> <b>O. Air</b> (81083040038)..... <b>PA2776</b> <b>I. Air</b> (81084050013)..... <b>PA3494</b> <b>Hyd.</b> (81055040007)..... <b>PT691</b>
F2000 19.323 w/D2865 Eng. (05/96-on) <b>Lube</b> ..... <b>P7190</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>Radial Seal O. Air</b> ..... <b>RS3714</b> <b>Radial Seal I. Air</b> ..... <b>RS4549</b> <b>Cab Air</b> ..... <b>PA3980</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> ..... <b>BA5379 +</b> <b>Trans.</b> (ZF Gearbox)..... <b>PT8385</b>	19.343 w/D2865 Eng. (01/94-04/96) <b>Lube Ele.</b> (1/94-1/95) (Mann HU947/1n)..... <b>P7305</b> <b>Lube Ele.</b> (2/95-4/96) (51055040096)..... <b>P7145</b> <b>Fuel/Water Separator</b> (Mann WDK724)..... <b>BF1372</b> <b>Radial Seal O. Air</b> (Mann C301353)..... <b>RS3714</b> <b>Radial Seal I. Air</b> (Mann C17170)..... <b>RS4549</b> <b>Cab Air</b> (Mann CU40110)..... <b>PA3980</b>	19.360 w/D2540MTF Eng. (1982) <b>F-F Lube</b> (81055040041)..... <b>P294</b> <b>B-P Lube</b> (81055040048)..... <b>C750-E +</b> <b>S. Fuel Ele.</b> (81125030042)..... <b>PF231</b> <b>O. Air</b> (81083040043)..... <b>PA2776</b> <b>I. Air</b> ..... <b>PA3494</b>
19.330 w/D2530, D2530MTXF Engs. <b>P. Fuel Ele.</b> (81125030011)..... <b>F950-F</b> <b>S. Fuel Ele.</b> (81125030042)..... <b>PF231</b> <b>O. Air</b> (81083040038)..... <b>PA2776</b> <b>I. Air</b> ..... <b>PA3494</b> <b>Hyd.</b> (81055040007)..... <b>PT691</b>	F2000 19.343 w/D2865 Eng. (05/96-on) <b>Lube</b> ..... <b>P7190</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>Radial Seal O. Air</b> ..... <b>RS3714</b> <b>Radial Seal I. Air</b> ..... <b>RS4549</b> <b>Cab Air</b> ..... <b>PA3980</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> ..... <b>BA5379 +</b> <b>Trans.</b> (ZF Gearbox)..... <b>PT8385</b>	19.360F w/D2530, D2530MTXF Engs. <b>Lube</b> (81055040041)..... <b>P294</b> <b>S. Fuel Ele.</b> (81125030042)..... <b>PF231</b>
19.330FT w/D2530MF Eng. <b>Lube</b> (81055040041)..... <b>P294</b> <b>P. Fuel Ele.</b> (11/76-on) (81125030011)..... <b>F950-F</b> <b>S. Fuel Ele.</b> (11/76-on) (81125030042)..... <b>PF231</b>	19.331 w/D2866 Eng. <b>P. Fuel Ele.</b> (81125030011)..... <b>F950-F</b> <b>S. Fuel Ele.</b> (81125030042)..... <b>PF231</b> <b>Air</b> (81083040038)..... <b>PA2776</b> <b>Hyd.</b> (81055040007)..... <b>PT691</b>	19.361, 19.361U w/D2866 Eng. <b>F-F Lube</b> (81055040041)..... <b>P294</b> <b>B-P Lube</b> (81055040048)..... <b>C750-E +</b> <b>P. Fuel Ele.</b> (81125030011)..... <b>F950-F</b> <b>S. Fuel Ele.</b> (81125030042)..... <b>PF231</b> <b>O. Air</b> (81083040038)..... <b>PA2776</b> <b>I. Air</b> ..... <b>PA3494</b>
		19.362 w/D2866 Eng. <b>Lube</b> (81055040039)..... <b>P294</b> <b>Fuel Ele.</b> (81125030021)..... <b>PF950</b> <b>Fuel Spin-on</b> (81125030075)..... <b>BF587-D +</b> <b>Air</b> (81083040043)..... <b>PA2776</b> <b>Cab Air</b> (8169100011)..... <b>PA3980</b>

+ See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)
19.364 w/D2866 Eng. Lube (Mann HU1381x)..... P7190 Fuel/Water Separator (Mann WDK724)..... BF1372 Radial Seal O. Air (Mann C301353)..... RS3714 Radial Seal I. Air (Mann C17170)..... RS4549 Cab Air (Mann CU40110)..... PA3980	TGS 19.400 w/w/D 2066 (Euro 6) Eng. (09/12-on) (Cont'd) Urea (81154036015)..... PE5270 19.403 w/D2866 Eng. Lube Ele. (1/94-1/95) (Mann HU947/1n)..... P7305 Lube Ele. (2/95-8/96) (51055040096)..... P7145 Lube Ele. (9/96-on) (Mann HU138/1x)..... P7190 Fuel/Water Separator (Mann WDK724)..... BF1372 Radial Seal O. Air (Mann C301353)..... RS3714 Radial Seal I. Air (Mann C17170)..... RS4549 Cab Air (Mann CU40110)..... PA3980	TGS 19.440 w/w/D 2066 (Euro 6) Eng. (09/12-on) Lube (51055010009)..... P40042 P. Fuel (51125030063)..... PF7935 S. Fuel (51125030062)..... PF7939 Radial Seal O. Air (81084050033)..... RS4971 Radial Seal I. Air (81084050017)..... RS5361 Cab Air (w/o Charcoal) (81619100018)..... PA4955 Cab Air (w/Charcoal) (81619100019)..... PA5477 Air Dryer (81521086025)..... BA5379 + Steering (81473016005)..... P106-HD Urea (81154036015)..... PE5270
F2000 19.364FLD, F2000 19.64FLT w/D2866LF(35) Eng. (05/96-on) Lube (51055040098)..... P7190 Fuel/Water Separator (51125030040)..... BF1372 Radial Seal O. Air..... RS3714 Radial Seal I. Air (81083040084)..... RS4549 Cab Air..... PA3980 Air Dryer (Mann TB1374X)..... BA5374 + Air Dryer..... BA5379 + Trans. (ZF Gearbox)..... PT8385	19.414 w/D2866 Eng. Lube (Mann HU1381x)..... P7190 Fuel/Water Separator (Mann WDK724)..... BF1372 Radial Seal O. Air (Mann C301353)..... RS3714 Radial Seal I. Air (Mann C17170)..... RS4549 Cab Air (Mann CU40110)..... PA3980	19.462, 19.502 w/D2840 Eng. Lube (81055040041)..... P294 P. Fuel Ele. (81125030011)..... F950-F S. Fuel Ele. (81125030042)..... PF231 Fuel Spin-on (51125030004)..... BF587 Air (81082050005)..... PA2475
19.372 w/D2866 Eng. Lube (81055040041)..... P294 Fuel Ele. (81125030042)..... PF231 Axial Seal Air (81083040038)..... PA2776 Radial Seal O. Air (81083040094)..... RS3714 Radial Seal I. Air (81083040084)..... RS4549	F2000 19.414FLT w/D2866LF(31) Eng. (05/96-on) Lube (51055040098)..... P7190 Fuel/Water Separator (51125030040)..... BF1372 Radial Seal O. Air..... RS3714 Radial Seal I. Air (81083040084)..... RS4549 Cab Air..... PA3980 Air Dryer (Mann TB1374X)..... BA5374 + Air Dryer..... BA5379 + Trans. (ZF Gearbox)..... PT8385	19.463 w/D2876 Eng. Lube Ele. (1/94-1/95) (Mann HU947/1n)..... P7305 Lube Ele. (2/95-8/96) (51055040096)..... P7145 Lube Ele. (9/96-on) (Mann HU138/1x)..... P7190 Fuel/Water Separator (Mann WDK724)..... BF1372 Radial Seal O. Air (Mann C301353)..... RS3714 Radial Seal I. Air (Mann C17170)..... RS4549 Cab Air (Mann CU40110)..... PA3980
19.373, 19.402, 19.423 w/D2866 Eng. Lube Ele. (1/94-1/95) (Mann HU947/1n)..... P7305 Lube Ele. (2/95-on) (51055040096)..... P7145 Fuel/Water Separator (Mann WDK724)..... BF1372 Radial Seal O. Air (Mann C301353)..... RS3714 Radial Seal I. Air (Mann C17170)..... RS4549 Cab Air (Mann CU40110)..... PA3980	19.422 w/D2866 Eng. Lube (81055040041)..... P294 Fuel Ele. (81125030042)..... PF231 Fuel Spin-on (81125030075)..... BF587-D + Axial Seal Air (81083040038)..... PA2776 Radial Seal O. Air (81083040094)..... RS3714 Radial Seal I. Air (81083040084)..... RS4549	F2000 19.464FLT w/D2876LF(06) Eng. (05/96-on) Lube (51055040098)..... P7190 Fuel/Water Separator (51125030040)..... BF1372 Radial Seal O. Air..... RS3714 Radial Seal I. Air (81083040084)..... RS4549 Cab Air..... PA3980 Air Dryer (Mann TB1374X)..... BA5374 + Air Dryer..... BA5379 + Trans. (ZF Gearbox)..... PT8385
19.390 w/D2540MTF Eng. F-F Lube (81055040041)..... P294 B-P Lube (81055040048)..... C750-E + Fuel Ele. (81125030042)..... PF231 Air (81083040038)..... PA2776	19.423 w/D2866 Eng. Lube (1/94-1/95) (Mann HU947/1n)..... P7305 Lube (2/95-on) (Mann HU947/2x)..... P7145 Fuel/Water Separator (Mann WDK724)..... BF1372 Radial Seal O. Air (Mann C301353)..... RS3714 Radial Seal I. Air (Mann C17170)..... RS4549 Cab Air (Mann CU40110)..... PA3980 Trans. (Mann H710/1n)..... PT8385	TGS 19.480 w/w/D 2676 (Euro 6) Eng. (09/12-on) Lube (51055010009)..... P40042 P. Fuel (51125030063)..... PF7935 S. Fuel (51125030062)..... PF7939 Radial Seal O. Air (81084050033)..... RS4971 Radial Seal I. Air (81084050017)..... RS5361 Cab Air (w/o Charcoal) (81619100018)..... PA4955 Cab Air (w/Charcoal) (81619100019)..... PA5477 Air Dryer (81521086025)..... BA5379 + Steering (81473016005)..... P106-HD
TGS 19.400 w/w/D 2066 (Euro 6) Eng. (09/12-on) Lube (51055010009)..... P40042 P. Fuel (51125030063)..... PF7935 S. Fuel (51125030062)..... PF7939 Radial Seal O. Air (81084050033)..... RS4971 Radial Seal I. Air (81084050017)..... RS5361 Cab Air (w/o Charcoal) (81619100018)..... PA4955 Cab Air (w/Charcoal) (81619100019)..... PA5477 Air Dryer (81521086025)..... BA5379 + Steering (81473016005)..... P106-HD		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)
TGS 19.480 w/w/D 2676 (Euro 6) Eng. (09/12-on) (Cont'd)	20.264 w/D0826 Eng.	20.320 w/D2530 Eng. (Cont'd)
Air Dryer (81521086025)..... BA5379 +	Lube (Mann W1160)..... B7116	Hyd. (81055040007)..... PT691
Steering (81473016005)..... P106-HD	Fuel/Water Separator (Mann WDK724)..... BF1372	20.320 w/D2538 Eng.
Urea (81154036015)..... PE5270	Radial Seal Air (Mann C25730/1)..... RS4775	Lube (81055040041)..... P294
19.603 w/D2840 Eng.	Cab Air (Mann CU40110)..... PA3980	115.1 mm P. Fuel (81125030050)..... F953-F
Lube Ele. (51055040096)..... P7145	20.280 w/D2566MT Eng.	142.9 mm P. Fuel (81125030011)..... F950-F
Fuel/Water Separator (Mann WDK724)..... BF1372	Lube (81055040041)..... P294	108.7 mm S. Fuel (81125030041)..... PF834
Radial Seal Air (Mann C301353)..... RS3714	P. Fuel Ele. (81125030011)..... F950-F	148.4 mm S. Fuel (81125030042)..... PF231
Cab Air (Mann CU40110)..... PA3980	S. Fuel Ele. (81125030042)..... PF231	O. Air (81082050005)..... PA2475
20.224 w/D0826 Eng.	496.9 mm O. Air (81082050005)..... PA2475	I. Air..... PA2814
Lube (Mann W1160)..... B7116	473.1 mm I. Air..... PA2814	Hyd. (81055040007)..... PT691
Fuel/Water Separator (Mann WDK724)..... BF1372	473.9 mm O. Air..... PA2776	20.320 w/D3530 Eng.
Air (Mann C24508)..... PA3760	Hyd. (81055040007)..... PT691	Lube (81055040041)..... P294
381.8 mm Some Radial Seal Air (Mann C25730/1)..... RS4775	CLA 20.280 w/D 0836 Eng. (10/06-on)	P. Fuel Ele. (81125030011)..... F950-F
Cab Air (Mann CU40110)..... PA3980	Lube (51055017160)..... B7116	S. Fuel Ele. (81125030042)..... PF231
M2000 Evo 20.225 L w/D0836 Eng. (05/01-on)	Fuel/Water Separator (51125030040)..... BF1372	Hyd. (81055040007)..... PT691
Lube..... B7116	O. Air (81083040074)..... PA3760	20.321 w/D2566, D2566MK, D2566MKF Eng.
Fuel/Water Separator (51125030040)..... BF1372	Steering (81473016005)..... P106-HD	Lube (81055040041)..... P294
Radial Seal Air..... RS4775	20.281 w/D2566, D2566MK, D2566MKF Eng.	P. Fuel Ele. (81125030011)..... F950-F
Cab Air..... PA3980	Lube (81055040041)..... P294	S. Fuel Ele. (81125030042)..... PF231
Air Dryer (Mann TB1374X)..... BA5374 +	P. Fuel Ele. (81125030011)..... F950-F	O. Air (81083040038)..... PA2776
Air Dryer..... BA5379 +	S. Fuel Ele. (81125030042)..... PF231	I. Air (81084050013)..... PA3494
Steering (81473016005)..... P106-HD	O. Air (81084050013)..... PA3494	20.322 w/D2865 Eng.
20.240 w/U12D Eng.	I. Air (81084050013)..... PA3494	F-F Lube (81055040041)..... P294
Lube (81055040041)..... P294	20.284 w/D0836 Eng.	Lube (1989-on) (81055040038)..... P242
P. Fuel Ele. (81125030011)..... F950-F	Lube (Mann W1160)..... B7116	P. Fuel Ele. (81125030011)..... F950-F
S. Fuel Ele. (81125030042)..... PF231	Fuel/Water Separator (Mann WDK724)..... BF1372	S. Fuel Ele. (81125030042)..... PF231
Fuel Spin-on (81125030075)..... BF587-D +	Radial Seal Air (Mann C25730/1)..... RS4775	Fuel Spin-on (81125030075)..... BF587-D +
Air..... PA3572	Cab Air (Mann CU40110)..... PA3980	Air (81083040038)..... PA2776
Hyd. (81055040007)..... PT691	M2000 Evo 20.285 L w/D0836 Eng. (05/01-on)	20.331 w/D2866 Eng.
20.240 w/D2566 Eng.	Lube..... B7116	P. Fuel Ele. (81125030011)..... F950-F
Lube Ele. (81055040041)..... P294	Fuel/Water Separator (51125030040)..... BF1372	S. Fuel Ele. (81125030042)..... PF231
P. Fuel Ele. (81125030011)..... F950-F	Radial Seal Air..... RS4775	Air (81083040038)..... PA2776
S. Fuel Ele. (81125030042)..... PF231	Cab Air..... PA3980	Hyd. (81055040007)..... PT691
377.8 mm Air..... PA2813	Air Dryer (Mann TB1374X)..... BA5374 +	20.361 w/D2866 Eng.
381.0 mm Air (81083040036)..... PA2474	Air Dryer..... BA5379 +	F-F Lube (81055040041)..... P294
495.3 mm Air (81055040033)..... PA3572	Steering (81473016005)..... P106-HD	B-P Lube (81055040048)..... C750-E +
Hyd. (81055040007)..... PT691	20.291 w/D2866 Eng.	P. Fuel Ele. (81125030011)..... F950-F
20.249 w/D2556 Eng.	P. Fuel Ele. (81125030011)..... F950-F	S. Fuel Ele. (81125030042)..... PF231
Air..... PA2474	S. Fuel Ele. (81125030042)..... PF231	O. Air (81083040038)..... PA2776
M2000 Evo 20.255 L w/D0836 Eng. (05/01-on)	O. Air (81083040043)..... PA2776	I. Air (81084050013)..... PA3494
Lube..... B7116	20.320 w/D2530 Eng.	22.192 w/D2146, D2156, D2356 Eng.
Fuel/Water Separator (51125030040)..... BF1372	115.1 mm P. Fuel (81125030050)..... F953-F	Lube (81055040032)..... P235
Radial Seal Air..... RS4775	142.9 mm P. Fuel (81125030011)..... F950-F	P. Fuel Ele. (81125030011)..... F950-F
Cab Air..... PA3980	108.7 mm S. Fuel (81125030041)..... PF834	S. Fuel Ele. (81125030042)..... PF231
Air Dryer (Mann TB1374X)..... BA5374 +	148.4 mm S. Fuel (81125030042)..... PF231	Hyd. (81055040007)..... PT691
Air Dryer..... BA5379 +	O. Air (81082050005)..... PA2475	22.192 w/D2555 Eng.
Steering (81473016005)..... P106-HD	I. Air..... PA2814	Lube (81055040040)..... P242
		115.1 mm P. Fuel (81125030050)..... F953-F
		142.9 mm P. Fuel (81125030011)..... F950-F

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)
22.192 w/D2555 Eng. (Cont'd)	22.240U w/U12D Eng.	22.304 w/D2858 Eng.
108.7 mm S. Fuel (81125030041)..... PF834	Lube (81055040041)..... P294	Lube (81055040025)..... P721
148.4 mm S. Fuel (81125030042)..... PF231	P. Fuel Ele. (81125030011)..... F950-F	P. Fuel Ele. (81125030011)..... F950-F
O. Air (81083040036)..... PA2474	S. Fuel Ele. (81125030042)..... PF231	S. Fuel Ele. (81125030042)..... PF231
I. Air..... PA2836	Hyd. (81055040007)..... PT691	Hyd. (81055040007)..... PT691
Single Air (81083040024)..... PA3605	22.241UNL w/D2566 Eng.	22.320 w/D2530 Eng.
Hyd. (81055040007)..... PT691	Lube (81055040041)..... P294	115.1 mm P. Fuel (81125030050)..... F953-F
22.215 w/D2146, D2156, D2356 Eng.	P. Fuel Ele. (81125030011)..... F950-F	142.9 mm P. Fuel (81125030011)..... F950-F
Lube (81055040032)..... P235	S. Fuel Ele. (81125030042)..... PF231	108.7 mm S. Fuel (81125030041)..... PF834
P. Fuel Ele. (81125030011)..... F950-F	Air (81083040041)..... PA2475	148.4 mm S. Fuel (81125030042)..... PF231
S. Fuel Ele. (81125030042)..... PF231	22.242 w/D2866 Eng.	O. Air (81082050005)..... PA2475
Hyd. (81055040007)..... PT691	Lube (81055040041)..... P294	I. Air..... PA2814
22.220 w/D2566 Eng.	P. Fuel Ele. (81125030011)..... F950-F	Hyd. (81055040007)..... PT691
Lube (81055040041)..... P294	S. Fuel Ele. (81125030042)..... PF231	22.320 w/D2538 Eng.
142.9 mm Fuel Ele. (81125030011)..... F950-F	Fuel Spin-on (81125030075)..... BF587-D +	Lube (81055040041)..... P294
148.4 mm Fuel Ele. (81125030042)..... PF231	Air (81083040038)..... PA2776	115.1 mm P. Fuel (81125030050)..... F953-F
O. Air (81083040045)..... PA2474	22.256 w/D2146, D2156, D2356 Eng.	142.9 mm P. Fuel (81125030011)..... F950-F
22.230 w/D2146, D2156, D2356 Eng.	Lube (81055040032)..... P235	108.7 mm S. Fuel (81125030041)..... PF834
Lube (81055040032)..... P235	P. Fuel Ele. (81125030011)..... F950-F	148.4 mm S. Fuel (81125030042)..... PF231
P. Fuel Ele. (81125030011)..... F950-F	S. Fuel Ele. (81125030042)..... PF231	O. Air (81082050005)..... PA2475
S. Fuel Ele. (81125030042)..... PF231	Hyd. (81055040007)..... PT691	I. Air..... PA2814
Hyd. (81055040007)..... PT691	22.262 w/D2865 Eng.	Hyd. (81055040007)..... PT691
22.240 w/U12D Eng.	188.1 mm Lube (1989-on) (81055040038)..... P242	22.320 w/D3530 Eng.
Lube (81055040041)..... P294	264.3 mm Lube (81055040041)..... P294	Lube (81055040041)..... P294
P. Fuel Ele. (81125030011)..... F950-F	Fuel Ele. (81125030042)..... PF231	115.1 mm P. Fuel (81125030050)..... F953-F
S. Fuel Ele. (81125030042)..... PF231	Fuel Spin-on (81125030075)..... BF587-D +	142.9 mm P. Fuel (81125030011)..... F950-F
Fuel Spin-on (81125030075)..... BF587-D +	Air (81083040038)..... PA2776	108.7 mm S. Fuel (81125030041)..... PF834
Air (81055040033)..... PA3572	22.280 w/D2566MT Eng.	148.4 mm S. Fuel (81125030042)..... PF231
Hyd. (81055040007)..... PT691	Lube (81055040041)..... P294	O. Air (81082050005)..... PA2475
22.240 w/D2556 Eng.	P. Fuel Ele. (81125030011)..... F950-F	I. Air..... PA2814
Lube (81055040025)..... P721	S. Fuel Ele. (81125030042)..... PF231	Hyd. (81055040007)..... PT691
115.1 mm P. Fuel (81125030050)..... F953-F	496.9 mm O. Air (81082050005)..... PA2475	22.320U w/D3256BXUL (U12D) Eng.
142.9 mm P. Fuel (81125030011)..... F950-F	473.1 mm I. Air..... PA2814	P. Fuel Ele. (81125030011)..... F950-F
108.7 mm S. Fuel (81125030041)..... PF834	473.9 mm O. Air..... PA2776	S. Fuel Ele. (81125030042)..... PF231
148.4 mm S. Fuel (81125030042)..... PF231	Hyd. (81055040007)..... PT691	Hyd. (81055040007)..... PT691
O. Air (81083040036)..... PA2474	22.280U w/U12D Eng.	22.321, 22.321UNL w/D2566, D2566MK, D2566MKF Eng.
I. Air..... PA2836	Lube (88055040003)..... PT86-HD	Lube (81055040041)..... P294
Hyd. (81055040007)..... PT691	P. Fuel Ele. (81125030011)..... F950-F	P. Fuel Ele. (81125030011)..... F950-F
22.240, 22.240U w/D2566 Eng.	S. Fuel Ele. (81125030042)..... PF231	S. Fuel Ele. (81125030042)..... PF231
Lube Ele. (81055040041)..... P294	Air (81055040033)..... PA3572	O. Air (81083040038)..... PA2776
P. Fuel Ele. (81125030011)..... F950-F	22.281 w/D2566, D2566MK, D2566MKF Eng.	I. Air (81084050013)..... PA3494
S. Fuel Ele. (81125030042)..... PF231	Lube (81055040041)..... P294	22.322 w/D2865 Eng.
377.8 mm Air..... PA2813	P. Fuel Ele. (81125030011)..... F950-F	188.1 mm Lube (1989-on) (81055040038)..... P242
381.0 mm Air (81083040036)..... PA2474	S. Fuel Ele. (81125030042)..... PF231	264.3 mm Lube (81055040041)..... P294
495.3 mm Air (81055040033)..... PA3572	O. Air (81083040038)..... PA2776	P. Fuel Ele. (81125030011)..... F950-F
Hyd. (81055040007)..... PT691	I. Air..... PA3494	S. Fuel Ele. (81125030042)..... PF231
22.291 w/D2866 Eng.	22.292 w/D2866 Eng.	Fuel Spin-on (81125030075)..... BF587-D +
P. Fuel Ele. (81125030011)..... F950-F	Lube (81055040041)..... P294	Air (81083040038)..... PA2776
S. Fuel Ele. (81125030042)..... PF231	P. Fuel Ele. (81125030011)..... F950-F	
O. Air (81083040043)..... PA2776	S. Fuel Ele. (81125030042)..... PF231	
	Fuel Spin-on (81125030075)..... BF587-D +	
	Air (81083040038)..... PA2776	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)
22.331 w/D2866 Eng. P. Fuel Ele. (81125030011)..... F950-F S. Fuel Ele. (81125030042)..... PF231 Air (81083040038)..... PA2776 Hyd. (81055040007)..... PT691	22.422 w/D2866 Eng. Lube (81055040041)..... P294 Fuel Ele. (81125030042)..... PF231 Axial Seal Air (81083040038)..... PA2776 Radial Seal O. Air (81083040094)..... RS3714 Radial Seal I. Air (81083040084)..... RS4549	F2000 23.293 w/D2865 Eng. (05/96-on) Lube..... P7190 Fuel/Water Separator (51125030040)..... BF1372 Radial Seal O. Air..... RS3714 Radial Seal I. Air..... RS4549 Cab Air..... PA3980 Air Dryer (Mann TB1374X)..... BA5374 + Air Dryer..... BA5379 + Trans. (ZF Gearbox)..... PT8385
22.332 w/D2866 Eng. Lube (81055040039)..... P294 Fuel Ele. (81125030021)..... PF950 Fuel Spin-on (81125030075)..... BF587-D + Air (81083040043)..... PA2776	22.462, 22.502 w/D2866 Eng. Lube (81055040041)..... P294 P. Fuel Ele. (81125030011)..... F950-F S. Fuel Ele. (81125030042)..... PF231 Fuel Spin-on (81125030075)..... BF587-D + Air (81082050005)..... PA2475	23.314 w/D2866 Eng. Lube (Mann HU1381x)..... P7190 Fuel/Water Separator (Mann WDK724)..... BF1372 Radial Seal O. Air (Mann C301353)..... RS3714 Radial Seal I. Air (Mann C17170)..... RS4549 Cab Air (Mann CU40110)..... PA3980
F2000 22.343FPLT, 22.343FVLTw/D2865LF(21) Eng. (05/96-on) Lube (51055040098)..... P7190 Fuel/Water Separator (51125030040)..... BF1372 Radial Seal O. Air..... RS3714 Radial Seal I. Air (81083040084)..... RS4549 Cab Air..... PA3980 Air Dryer (Mann TB1374X)..... BA5374 + Air Dryer..... BA5379 + Trans. (ZF Gearbox)..... PT8385	F2000 22.463FPLT, F2000 22.463FVLT w/D2876LF Eng. (05/96-on) Lube (51055040098)..... P7190 Fuel/Water Separator (51125030040)..... BF1372 Radial Seal O. Air..... RS3714 Radial Seal I. Air (81083040084)..... RS4549 Cab Air..... PA3980 Air Dryer (Mann TB1374X)..... BA5374 + Air Dryer..... BA5379 + Trans. (ZF Gearbox)..... PT8385	23.321 w/D2566, D2566MK, D2566MKF Eng. Lube (81055040041)..... P294 P. Fuel Ele. (81125030011)..... F950-F S. Fuel Ele. (81125030042)..... PF231 O. Air (81083040038)..... PA2776 I. Air (81084050013)..... PA3494
22.361 w/D2866 Eng. F-F Lube (81055040041)..... P294 B-P Lube (81055040048)..... C750-E + P. Fuel Ele. (81125030011)..... F950-F S. Fuel Ele. (81125030042)..... PF231 O. Air (81083040038)..... PA2776 I. Air..... PA3494	23.273 w/D2865, D2875 Eng. Radial Seal O. Air (81083040094)..... RS3714 Radial Seal I. Air (81083040084)..... RS4549	F2000 23.343 w/D2865 Eng. (01/94-04/96) Lube (1/94-1/95) (Mann HU947/1n)..... P7305 Lube (2/95-4/96) (51055040096)..... P7145 Fuel/Water Separator (Mann WDK724)..... BF1372 Radial Seal O. Air (Mann C301353)..... RS3714 Radial Seal I. Air (Mann C17170)..... RS4549 Cab Air (Mann CU40110)..... PA3980 Air Dryer (Mann TB1374X)..... BA5374 +
22.361U w/D2866 Eng. Lube (81055040041)..... P294 S. Fuel Ele. (81125030042)..... PF231 O. Air (81083040038)..... PA2776 I. Air..... PA3494	23.284 w/D0836 Eng. Lube (Mann W1160)..... B7116 Fuel/Water Separator (Mann WDK724)..... BF1372 Radial Seal Air (Mann C25730/1)..... RS4775 Cab Air (Mann CU40110)..... PA3980	F2000 23.343 w/D2865 Eng. (05/96-on) Lube..... P7190 Fuel/Water Separator (51125030040)..... BF1372 Radial Seal O. Air..... RS3714 Radial Seal I. Air..... RS4549 Cab Air..... PA3980 Air Dryer (Mann TB1374X)..... BA5374 + Air Dryer..... BA5379 + Trans. (ZF Gearbox)..... PT8385
22.362 w/D2866 Eng. Lube (81055040039)..... P294 Fuel Ele. (81125030021)..... PF950 Fuel Spin-on (81125030075)..... BF587-D + Air (81083040043)..... PA2776	M2000 Evo 23.284FNL w/D0836LF Eng. (05/01-on) Lube..... B7116 Fuel/Water Separator (51125030040)..... BF1372 Radial Seal Air..... RS4775 Cab Air (85619500025)..... PA5339 Steering (81473016005)..... P106-HD	23.364 w/D2866 Eng. Lube (Mann HU1381x)..... P7190 Fuel/Water Separator (Mann WDK724)..... BF1372 Radial Seal O. Air (Mann C301353)..... RS3714 Radial Seal I. Air (Mann C17170)..... RS4549 Cab Air (Mann CU40110)..... PA3980
22.372 w/D2866 Eng. Lube (81055040041)..... P294 Fuel Ele. (81125030042)..... PF231 Axial Seal Air (81083040038)..... PA2776 Radial Seal O. Air (81083040094)..... RS3714 Radial Seal I. Air (81083040084)..... RS4549	F2000 23.293 w/D2865 Eng. (01/94-04/96) Lube (1/94-1/95) (Mann HU947/1n)..... P7305 Lube (2/95-4/96) (Mann HU947/2x)..... P7145 Fuel/Water Separator (Mann WDK724)..... BF1372 Radial Seal O. Air (Mann C301353)..... RS3714 Radial Seal I. Air (Mann C17170)..... RS4549 Cab Air (Mann CU40110)..... PA3980 Air Dryer (Mann TB1374X)..... BA5374 +	
F2000 22.403FPLT, F2000 22.403FVLT w/D2866LF(20) Eng. (05/96-on) Lube (51055040098)..... P7190 Fuel/Water Separator (51125030040)..... BF1372 Radial Seal O. Air..... RS3714 Radial Seal I. Air (81083040084)..... RS4549 Cab Air..... PA3980 Air Dryer (Mann TB1374X)..... BA5374 + Air Dryer..... BA5379 + Trans. (ZF Gearbox)..... PT8385		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)
23.372 w/D2866 Eng. Fuel/Water Separator (Mann WDK724)..... <b>BF1372</b> Air (Mann C30850/2)..... <b>PA2776</b> Cab Air (Mann CU40110)..... <b>PA3980</b>	23.463, 23.464 w/D2876 Eng. (Cont'd) Radial Seal O. Air (Mann C301353)..... <b>RS3714</b> Radial Seal I. Air (Mann C17170)..... <b>RS4549</b> Cab Air (Mann CU40110)..... <b>PA3980</b>	24.314 w/D2866 Eng. Lube (Mann HU1381x)..... <b>P7190</b> Fuel/Water Separator (Mann WDK724)..... <b>BF1372</b> Radial Seal O. Air (Mann C301353)..... <b>RS3714</b> Radial Seal I. Air (Mann C17170)..... <b>RS4549</b> Cab Air (Mann CU40110)..... <b>PA3980</b>
23.402 w/D2866 Eng. Lube (5/94-1/95) (Mann HU947/1n)..... <b>P7305</b> Lube (2/95-8/96) (Mann HU947/2x)..... <b>P7145</b> Fuel/Water Separator (Mann WDK724)..... <b>BF1372</b> Radial Seal O. Air (Mann C301353)..... <b>RS3714</b> Radial Seal I. Air (Mann C17170)..... <b>RS4549</b> Cab Air (Mann CU40110)..... <b>PA3980</b>	24.232 w/D0826L Eng. Lube (51055017160)..... <b>B7116</b> Fuel..... <b>BF587-D +</b> Air (81083040038)..... <b>PA2474</b>	TGS 24.320 w/D2066 (Euro 4/5) Eng. (10/07-on) Lube..... <b>P7329</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> Fuel/Water Separator..... <b>BF7912</b> Radial Seal O. Air..... <b>RS4971</b> Radial Seal I. Air..... <b>RS5361</b> Cab Air (w/o Carbon) (81619100018)..... <b>PA4955</b> Cab Air (w/Carbon) (81619100019)..... <b>PA5477</b> Air Dryer (Desiccant)..... <b>BA5374 +</b> Air Dryer (Coalescer) (81521086025)..... <b>BA5379 +</b> Steering (81473016005)..... <b>P106-HD</b> Urea (81154036015)..... <b>PE5270</b>
23.403 w/D2866 Eng. Lube (1/94-1/95) (Mann HU947/1n)..... <b>P7305</b> Lube (2/95-8/96) (Mann HU947/2x)..... <b>P7145</b> Lube (9/96-on) (Mann HU1381x)..... <b>P7190</b> Fuel/Water Separator (Mann WDK724)..... <b>BF1372</b> Radial Seal O. Air (Mann C301353)..... <b>RS3714</b> Radial Seal I. Air (Mann C17170)..... <b>RS4549</b> Cab Air (Mann CU40110)..... <b>PA3980</b>	24.242 w/D2866 Eng. Lube (81055040041)..... <b>P294</b> P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> Fuel Spin-on (81125030075)..... <b>BF587-D +</b> Air (81083040038)..... <b>PA2776</b>	TGS 24.320 w/w/D 2066 (Euro 6) Eng. (09/12-on) Lube (51055010009)..... <b>P40042</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> Radial Seal O. Air (81084050033)..... <b>RS4971</b> Radial Seal I. Air (81084050017)..... <b>RS5361</b> Cab Air (w/o Charcoal) (81619100018)..... <b>PA4955</b> Cab Air (w/Charcoal) (81619100019)..... <b>PA5477</b> Air Dryer (81521086025)..... <b>BA5379 +</b> Steering (81473016005)..... <b>P106-HD</b> Urea (81154036015)..... <b>PE5270</b>
23.414 w/D2866 Eng. Lube (Mann HU1381x)..... <b>P7190</b> Fuel/Water Separator (Mann WDK724)..... <b>BF1372</b> Radial Seal O. Air (Mann C301353)..... <b>RS3714</b> Radial Seal I. Air (Mann C17170)..... <b>RS4549</b> Cab Air (Mann CU40110)..... <b>PA3980</b>	24.262, 24.272 w/D2865 Eng. 188.1 mm Lube (1989-on) (81055040038)..... <b>P242</b> 264.3 mm Lube (81055040041)..... <b>P294</b> Fuel Ele. (81125030042)..... <b>PF231</b> Fuel Spin-on (81125030075)..... <b>BF587-D +</b> Air (81083040038)..... <b>PA2776</b>	F2000 24.323 w/D2865 Eng. (01/94-04/96) Lube (1/94-1/95) (Mann HU947/1n)..... <b>P7305</b> Lube (2/95-4/96) (Mann HU947/2x)..... <b>P7145</b> Fuel/Water Separator (Mann WDK724)..... <b>BF1372</b> Radial Seal O. Air (Mann C301353)..... <b>RS3714</b> Radial Seal I. Air (Mann C17170)..... <b>RS4549</b> Cab Air (Mann CU40110)..... <b>PA3980</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b>
23.414 FNLLD w/D2866LF(31) Eng. (05/96-on) Lube (51055040098)..... <b>P7190</b> Fuel/Water Separator (51125030040)..... <b>BF1372</b> Radial Seal O. Air..... <b>RS3714</b> Radial Seal I. Air (81083040084)..... <b>RS4549</b> Cab Air..... <b>PA3980</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer..... <b>BA5379 +</b> Trans. (ZF Gearbox)..... <b>PT8385</b>	24.273 w/D2865, D2875 Engs. Radial Seal O. Air (81083040094)..... <b>RS3714</b> Radial Seal I. Air (81083040084)..... <b>RS4549</b>	F2000 24.323 w/D2865 Eng. (01/94-04/96) Lube (1/94-1/95) (Mann HU947/1n)..... <b>P7305</b> Lube (2/95-4/96) (Mann HU947/2x)..... <b>P7145</b> Fuel/Water Separator (Mann WDK724)..... <b>BF1372</b> Radial Seal O. Air (Mann C301353)..... <b>RS3714</b> Radial Seal I. Air (Mann C17170)..... <b>RS4549</b> Cab Air (Mann CU40110)..... <b>PA3980</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b>
23.463, 23.464 w/D2876 Eng. Lube (1/94-1/95) (Mann HU947/1n)..... <b>P7305</b> Lube (2/95-8/96) (Mann HU947/2x)..... <b>P7145</b> Lube (9/96-on) (Mann HU1381x)..... <b>P7190</b> Fuel/Water Separator (Mann WDK724)..... <b>BF1372</b>	24.292 w/D2866 Eng. Lube (81055040041)..... <b>P294</b> P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> Fuel Spin-on (81125030075)..... <b>BF587-D +</b> Air (81083040038)..... <b>PA2776</b>	F2000 24.293 w/D2865 Eng. (05/96-on) Lube..... <b>P7190</b> Fuel/Water Separator (51125030040)..... <b>BF1372</b> Radial Seal O. Air..... <b>RS3714</b> Radial Seal I. Air..... <b>RS4549</b> Cab Air..... <b>PA3980</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer..... <b>BA5379 +</b> Trans. (ZF Gearbox)..... <b>PT8385</b>
	F2000 24.293 w/D2865 Eng. (05/96-on) Lube..... <b>P7190</b> Fuel/Water Separator (51125030040)..... <b>BF1372</b> Radial Seal O. Air..... <b>RS3714</b> Radial Seal I. Air..... <b>RS4549</b> Cab Air..... <b>PA3980</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer..... <b>BA5379 +</b> Trans. (ZF Gearbox)..... <b>PT8385</b>	F2000 24.323 w/D2865 Eng. (05/96-on) Lube..... <b>P7190</b> Fuel/Water Separator (51125030040)..... <b>BF1372</b> Radial Seal O. Air..... <b>RS3714</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)
<b>F2000 24.323 w/D2865 Eng. (05/96-on)</b> (Cont'd) <b>Radial Seal I. Air</b> ..... <b>RS4549</b> <b>Cab Air</b> ..... <b>PA3980</b> <b>Air Dryer (Mann TB1374X)</b> ..... <b>BA5374 +</b> <b>Air Dryer</b> ..... <b>BA5379 +</b> <b>Trans. (ZF Gearbox)</b> ..... <b>PT8385</b>	<b>TGS 24.360 w/D2066 (Euro 4/5) Eng. (10/07-on)</b> (Cont'd) <b>Air Dryer (Desiccant)</b> ..... <b>BA5374 +</b> <b>Air Dryer (Coalescer)</b> (81521086025)..... <b>BA5379 +</b> <b>Steering (81473016005)</b> ..... <b>P106-HD</b> <b>Urea (81154036015)</b> ..... <b>PE5270</b>	<b>24.364, 24.414, 24.464 w/D2866, D2876 Engs. (Cont'd)</b> <b>Radial Seal I. Air (Mann C17170)</b> ..... <b>RS4549</b> <b>Cab Air (Mann CU40110)</b> ..... <b>PA3980</b>
<b>24.332, 24.362, 24.422 w/D2866 Eng.</b> <b>Lube (81055040039)</b> ..... <b>P294</b> <b>Fuel Ele. (81125030021)</b> ..... <b>PF950</b> <b>Fuel Spin-on (81125030075)</b> ..... <b>BF587-D +</b> <b>Air (81083040043)</b> ..... <b>PA2776</b> <b>Cab Air (8169100011)</b> ..... <b>PA3980</b>	<b>TGX 24.360 w/D2066 (Euro 4/5) Eng. (10/07-on)</b> <b>Lube</b> ..... <b>P7329</b> <b>P. Fuel (51125030063)</b> ..... <b>PF7935</b> <b>S. Fuel (51125030062)</b> ..... <b>PF7939</b> <b>Fuel/Water Separator</b> ..... <b>BF7912</b> <b>Radial Seal O. Air</b> ..... <b>RS4971</b> <b>Radial Seal I. Air</b> ..... <b>RS5361</b> <b>Cab Air (w/o Carbon)</b> (81619100018)..... <b>PA4955</b> <b>Cab Air (w/Carbon)</b> (81619100019)..... <b>PA5477</b> <b>Air Dryer (Desiccant)</b> ..... <b>BA5374 +</b> <b>Air Dryer (Coalescer)</b> (81521086025)..... <b>BA5379 +</b> <b>Steering (81473016005)</b> ..... <b>P106-HD</b> <b>Urea (81154036015)</b> ..... <b>PE5270</b>	<b>24.372 w/D2866 Eng.</b> <b>Lube (81055040041)</b> ..... <b>P294</b> <b>Fuel Ele. (81125030042)</b> ..... <b>PF231</b> <b>Axial Seal Air (81083040038)</b> ..... <b>PA2776</b> <b>Radial Seal O. Air</b> (81083040094)..... <b>RS3714</b> <b>Radial Seal I. Air (81083040084)</b> ..... <b>RS4549</b>
<b>24.342 w/D2865 Eng.</b> <b>Lube (5/94-1/95) (Mann HU947/1n)</b> ..... <b>P7305</b> <b>Lube (2/95-on) (Mann HU947/2x)</b> ..... <b>P7145</b> <b>Fuel/Water Separator (Mann WDK724)</b> ..... <b>BF1372</b> <b>Radial Seal O. Air (Mann C301353)</b> ..... <b>RS3714</b> <b>Radial Seal I. Air (Mann C17170)</b> ..... <b>RS4549</b> <b>Cab Air (Mann CU40110)</b> ..... <b>PA3980</b>	<b>TGS 24.360 w/D 2066 (Euro 6) Eng. (09/12-on)</b> <b>Lube (51055010009)</b> ..... <b>P40042</b> <b>P. Fuel (51125030063)</b> ..... <b>PF7935</b> <b>S. Fuel (51125030062)</b> ..... <b>PF7939</b> <b>Radial Seal O. Air</b> (81084050033)..... <b>RS4971</b> <b>Radial Seal I. Air (81084050017)</b> ..... <b>RS5361</b> <b>Cab Air (w/o Charcoal)</b> (81619100018)..... <b>PA4955</b> <b>Cab Air (w/Charcoal)</b> (81619100019)..... <b>PA5477</b> <b>Air Dryer (81521086025)</b> ..... <b>BA5379 +</b> <b>Steering (81473016005)</b> ..... <b>P106-HD</b> <b>Urea (81154036015)</b> ..... <b>PE5270</b>	<b>24.373 w/D2866 Eng.</b> <b>Lube (1/94-1/95) (Mann HU947/1n)</b> ..... <b>P7305</b> <b>Lube (2/95-on) (Mann HU947/2x)</b> ..... <b>P7145</b> <b>Fuel/Water Separator (Mann WDK724)</b> ..... <b>BF1372</b> <b>Radial Seal O. Air (Mann C301353)</b> ..... <b>RS3714</b> <b>Radial Seal I. Air (Mann C17170)</b> ..... <b>RS4549</b> <b>Cab Air (Mann CU40110)</b> ..... <b>PA3980</b>
<b>F2000 24.343 w/D2865 Eng. (01/94-04/96)</b> <b>Lube (1/94-1/95) (Mann HU947/1n)</b> ..... <b>P7305</b> <b>Lube (2/95-4/96) (Mann HU947/2x)</b> ..... <b>P7145</b> <b>Fuel/Water Separator (Mann WDK724)</b> ..... <b>BF1372</b> <b>Radial Seal O. Air (Mann C301353)</b> ..... <b>RS3714</b> <b>Radial Seal I. Air (Mann C17170)</b> ..... <b>RS4549</b> <b>Cab Air (Mann CU40110)</b> ..... <b>PA3980</b> <b>Air Dryer (Mann TB1374X)</b> ..... <b>BA5374 +</b>	<b>TGX 24.360 w/D 2066 (Euro 6) Eng. (09/12-on)</b> <b>Lube (51055010009)</b> ..... <b>P40042</b> <b>P. Fuel (51125030063)</b> ..... <b>PF7935</b> <b>S. Fuel (51125030062)</b> ..... <b>PF7939</b> <b>Radial Seal O. Air</b> (81084050033)..... <b>RS4971</b> <b>Radial Seal I. Air (81084050017)</b> ..... <b>RS5361</b> <b>Cab Air (w/o Charcoal)</b> (81619100018)..... <b>PA4955</b> <b>Cab Air (w/Charcoal)</b> (81619100019)..... <b>PA5477</b> <b>Air Dryer (81521086025)</b> ..... <b>BA5379 +</b> <b>Steering (81473016005)</b> ..... <b>P106-HD</b> <b>Urea (81154036015)</b> ..... <b>PE5270</b>	<b>TGS 24.400 w/D2066 (Euro 4/5) Eng. (10/07-on)</b> <b>Lube</b> ..... <b>P7329</b> <b>P. Fuel (51125030063)</b> ..... <b>PF7935</b> <b>S. Fuel (51125030062)</b> ..... <b>PF7939</b> <b>Fuel/Water Separator</b> ..... <b>BF7912</b> <b>Radial Seal O. Air</b> ..... <b>RS4971</b> <b>Radial Seal I. Air</b> ..... <b>RS5361</b> <b>Cab Air (w/o Carbon)</b> (81619100018)..... <b>PA4955</b> <b>Cab Air (w/Carbon)</b> (81619100019)..... <b>PA5477</b> <b>Air Dryer (Desiccant)</b> ..... <b>BA5374 +</b> <b>Air Dryer (Coalescer)</b> (81521086025)..... <b>BA5379 +</b> <b>Steering (81473016005)</b> ..... <b>P106-HD</b> <b>Urea (81154036015)</b> ..... <b>PE5270</b>
<b>F2000 24.343 w/D2865 Eng. (05/96-on)</b> <b>Lube</b> ..... <b>P7190</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>Radial Seal O. Air</b> ..... <b>RS3714</b> <b>Radial Seal I. Air</b> ..... <b>RS4549</b> <b>Cab Air</b> ..... <b>PA3980</b> <b>Air Dryer (Mann TB1374X)</b> ..... <b>BA5374 +</b> <b>Air Dryer</b> ..... <b>BA5379 +</b> <b>Trans. (ZF Gearbox)</b> ..... <b>PT8385</b>	<b>TGX 24.360 w/D 2066 (Euro 6) Eng. (09/12-on)</b> <b>Lube (51055010009)</b> ..... <b>P40042</b> <b>P. Fuel (51125030063)</b> ..... <b>PF7935</b> <b>S. Fuel (51125030062)</b> ..... <b>PF7939</b> <b>Radial Seal O. Air</b> (81084050033)..... <b>RS4971</b> <b>Radial Seal I. Air (81084050017)</b> ..... <b>RS5361</b> <b>Cab Air (w/o Charcoal)</b> (81619100018)..... <b>PA4955</b> <b>Cab Air (w/Charcoal)</b> (81619100019)..... <b>PA5477</b> <b>Air Dryer (81521086025)</b> ..... <b>BA5379 +</b> <b>Steering (81473016005)</b> ..... <b>P106-HD</b> <b>Urea (81154036015)</b> ..... <b>PE5270</b>	<b>TGX 24.400 w/D2066 (Euro 4/5) Eng. (10/07-on)</b> <b>Lube</b> ..... <b>P7329</b> <b>P. Fuel (51125030063)</b> ..... <b>PF7935</b> <b>S. Fuel (51125030062)</b> ..... <b>PF7939</b> <b>Fuel/Water Separator</b> ..... <b>BF7912</b> <b>Radial Seal O. Air</b> ..... <b>RS4971</b> <b>Radial Seal I. Air</b> ..... <b>RS5361</b> <b>Cab Air (w/o Carbon)</b> (81619100018)..... <b>PA4955</b> <b>Cab Air (w/Carbon)</b> (81619100019)..... <b>PA5477</b> <b>Air Dryer (Desiccant)</b> ..... <b>BA5374 +</b> <b>Air Dryer (Coalescer)</b> (81521086025)..... <b>BA5379 +</b> <b>Steering (81473016005)</b> ..... <b>P106-HD</b> <b>Urea (81154036015)</b> ..... <b>PE5270</b>
<b>TGS 24.360 w/D2066 (Euro 4/5) Eng. (10/07-on)</b> <b>Lube</b> ..... <b>P7329</b> <b>P. Fuel (51125030063)</b> ..... <b>PF7935</b> <b>S. Fuel (51125030062)</b> ..... <b>PF7939</b> <b>Fuel/Water Separator</b> ..... <b>BF7912</b> <b>Radial Seal O. Air</b> ..... <b>RS4971</b> <b>Radial Seal I. Air</b> ..... <b>RS5361</b> <b>Cab Air (w/o Carbon)</b> (81619100018)..... <b>PA4955</b> <b>Cab Air (w/Carbon)</b> (81619100019)..... <b>PA5477</b>	<b>24.364, 24.414, 24.464 w/D2866, D2876 Engs.</b> <b>Lube (Mann HU1381x)</b> ..... <b>P7190</b> <b>Fuel/Water Separator (Mann WDK724)</b> ..... <b>BF1372</b> <b>Radial Seal O. Air (Mann C301353)</b> ..... <b>RS3714</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)
TGS 24.400 w/D 2066 (Euro 6) Eng. (09/12-on) Lube (51055010009)..... <b>P40042</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> Radial Seal O. Air (81084050033)..... <b>RS4971</b> Radial Seal I. Air (81084050017). <b>RS5361</b> Cab Air (w/o Charcoal) (81619100018)..... <b>PA4955</b> Cab Air (w/Charcoal) (81619100019)..... <b>PA5477</b> Air Dryer (81521086025)..... <b>BA5379 +</b> Steering (81473016005)..... <b>P106-HD</b> Urea (81154036015)..... <b>PE5270</b>	24.423 w/D2866 Eng. (Cont'd) Radial Seal O. Air (Mann C301353)..... <b>RS3714</b> Radial Seal I. Air (Mann C17170)..... <b>RS4549</b> Cab Air (Mann CU40110)..... <b>PA3980</b> TGS 24.440 w/D2066 (Euro 4/5) Eng. (10/07-on) Lube..... <b>P7329</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> Fuel/Water Separator..... <b>BF7912</b> Radial Seal O. Air..... <b>RS4971</b> Radial Seal I. Air..... <b>RS5361</b> Cab Air (w/o Carbon) (81619100018)..... <b>PA4955</b> Cab Air (w/Carbon) (81619100019)..... <b>PA5477</b> Air Dryer (Desiccant)..... <b>BA5374 +</b> Air Dryer (Coalescer) (81521086025)..... <b>BA5379 +</b> Steering (81473016005)..... <b>P106-HD</b> Urea (81154036015)..... <b>PE5270</b> TGS 24.440 w/D2066 (Euro 4/5) Eng. (10/07-on) Lube..... <b>P7329</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> Fuel/Water Separator..... <b>BF7912</b> Radial Seal O. Air..... <b>RS4971</b> Radial Seal I. Air..... <b>RS5361</b> Cab Air (w/o Carbon) (81619100018)..... <b>PA4955</b> Cab Air (w/Carbon) (81619100019)..... <b>PA5477</b> Air Dryer (Desiccant)..... <b>BA5374 +</b> Air Dryer (Coalescer) (81521086025)..... <b>BA5379 +</b> Steering (81473016005)..... <b>P106-HD</b> Urea (81154036015)..... <b>PE5270</b> TGS 24.440 w/D 2066, D 2676 (Euro 6) Eng. (09/12-on) Lube (51055010009)..... <b>P40042</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> Radial Seal O. Air (81084050033)..... <b>RS4971</b> Radial Seal I. Air (81084050017). <b>RS5361</b> Cab Air (w/o Charcoal) (81619100018)..... <b>PA4955</b> Cab Air (w/Charcoal) (81619100019)..... <b>PA5477</b> Air Dryer (81521086025)..... <b>BA5379 +</b> Steering (81473016005)..... <b>P106-HD</b> Urea (81154036015)..... <b>PE5270</b> TGS 24.440 w/D 2676 (Euro 6) Eng. (09/12-on) Lube (51055010009)..... <b>P40042</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> Radial Seal O. Air (81084050033)..... <b>RS4971</b> Radial Seal I. Air (81084050017). <b>RS5361</b>	TGX 24.440 w/D 2066 (Euro 6) Eng. (09/12-on) Lube (51055010009)..... <b>P40042</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> Radial Seal O. Air (81084050033)..... <b>RS4971</b> Radial Seal I. Air (81084050017). <b>RS5361</b> Cab Air (w/o Charcoal) (81619100018)..... <b>PA4955</b> Cab Air (w/Charcoal) (81619100019)..... <b>PA5477</b> Air Dryer (81521086025)..... <b>BA5379 +</b> Steering (81473016005)..... <b>P106-HD</b> Urea (81154036015)..... <b>PE5270</b> TGX 24.400 w/D 2066 (Euro 6) Eng. (09/12-on) Lube (51055010009)..... <b>P40042</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> Radial Seal O. Air (81084050033)..... <b>RS4971</b> Radial Seal I. Air (81084050017). <b>RS5361</b> Cab Air (w/o Charcoal) (81619100018)..... <b>PA4955</b> Cab Air (w/Charcoal) (81619100019)..... <b>PA5477</b> Air Dryer (81521086025)..... <b>BA5379 +</b> Steering (81473016005)..... <b>P106-HD</b> Urea (81154036015)..... <b>PE5270</b> 24.402 w/D2866 Eng. Lube (5/94-1/95) (Mann HU947/1n)..... <b>P7305</b> Lube (2/95-on) (Mann HU947/2x). <b>P7145</b> Fuel/Water Separator (Mann WDK724)..... <b>BF1372</b> Radial Seal O. Air (Mann C301353)..... <b>RS3714</b> Radial Seal I. Air (Mann C17170)..... <b>RS4549</b> Cab Air (Mann CU40110)..... <b>PA3980</b> 24.403, 24.463 w/D2866, D2876 Eng. Lube (1/94-1/95) (Mann HU947/1n)..... <b>P7305</b> Lube (2/95-8/96) (Mann HU947/2x)..... <b>P7145</b> Lube (9/96-on) (Mann HU1381x). <b>P7190</b> Fuel/Water Separator (Mann WDK724)..... <b>BF1372</b> Radial Seal O. Air (Mann C301353)..... <b>RS3714</b> Radial Seal I. Air (Mann C17170)..... <b>RS4549</b> Cab Air (Mann CU40110)..... <b>PA3980</b> 24.423 w/D2866 Eng. Lube (1/94-1/95) (Mann HU947/1n)..... <b>P7305</b> Lube (2/95-on) (Mann HU947/2x). <b>P7145</b> Fuel/Water Separator (Mann WDK724)..... <b>BF1372</b>
TGS 24.400 w/D 2066 (Euro 6) Eng. (09/12-on) Lube (51055010009)..... <b>P40042</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> Radial Seal O. Air (81084050033)..... <b>RS4971</b> Radial Seal I. Air (81084050017). <b>RS5361</b> Cab Air (w/o Charcoal) (81619100018)..... <b>PA4955</b> Cab Air (w/Charcoal) (81619100019)..... <b>PA5477</b> Air Dryer (81521086025)..... <b>BA5379 +</b> Steering (81473016005)..... <b>P106-HD</b> Urea (81154036015)..... <b>PE5270</b>	TGX 24.400 w/D 2066 (Euro 6) Eng. (09/12-on) Lube (51055010009)..... <b>P40042</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> Radial Seal O. Air (81084050033)..... <b>RS4971</b> Radial Seal I. Air (81084050017). <b>RS5361</b> Cab Air (w/o Charcoal) (81619100018)..... <b>PA4955</b> Cab Air (w/Charcoal) (81619100019)..... <b>PA5477</b> Air Dryer (81521086025)..... <b>BA5379 +</b> Steering (81473016005)..... <b>P106-HD</b> Urea (81154036015)..... <b>PE5270</b>	TGX 24.462, 24.502 w/D2866 Eng. Lube (81055040041)..... <b>P294</b> P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> Fuel Spin-on (81125030075)..... <b>BF587-D +</b> Air (81082050005)..... <b>PA2475</b> TGS 24.480 w/D2076 (Euro 4/5) Eng. (10/07-on) Lube..... <b>P7329</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> Fuel/Water Separator..... <b>BF7912</b> Radial Seal O. Air..... <b>RS4971</b> Radial Seal I. Air..... <b>RS5361</b> Cab Air (w/o Carbon) (81619100018)..... <b>PA4955</b> Cab Air (w/Carbon) (81619100019)..... <b>PA5477</b> Air Dryer (Desiccant)..... <b>BA5374 +</b> Air Dryer (Coalescer) (81521086025)..... <b>BA5379 +</b> Steering (81473016005)..... <b>P106-HD</b> Urea (81154036015)..... <b>PE5270</b> TGS 24.480 w/D2676 (Euro 4/5) Eng. (10/07-on) Lube..... <b>P7329</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> Fuel/Water Separator..... <b>BF7912</b> Radial Seal O. Air..... <b>RS4971</b> Radial Seal I. Air..... <b>RS5361</b> Cab Air (w/o Carbon) (81619100018)..... <b>PA4955</b> Cab Air (w/Carbon) (81619100019)..... <b>PA5477</b> Air Dryer (Desiccant)..... <b>BA5374 +</b> Air Dryer (Coalescer) (81521086025)..... <b>BA5379 +</b> Steering (81473016005)..... <b>P106-HD</b> Urea (81154036015)..... <b>PE5270</b> TGS 24.480 w/D 2676 (Euro 6) Eng. (09/12-on) Lube (51055010009)..... <b>P40042</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> Radial Seal O. Air (81084050033)..... <b>RS4971</b> Radial Seal I. Air (81084050017). <b>RS5361</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)
TGS 24.480 w/D 2676 (Euro 6) Eng. (09/12-on) (Cont'd) <b>Cab Air</b> (w/o Charcoal) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Charcoal) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>	TGS 24.540 w/D 2676 (Euro 6) Eng. (09/12-on) <b>Lube</b> (51055010009)..... <b>P40042</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>Radial Seal O. Air</b> (81084050033)..... <b>RS4971</b> <b>Radial Seal I. Air</b> (81084050017). <b>RS5361</b> <b>Cab Air</b> (w/o Charcoal) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Charcoal) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>	CLA 25.220 w/D0836 EURO2 Eng. (10/06-on) (Cont'd) <b>Steering</b> (81473016005)..... <b>P106-HD</b> 25.224 w/D0826 Eng. <b>Lube</b> (51055017160)..... <b>B7116</b> <b>Air</b> (81083040036)..... <b>PA2474</b> M2000 Evo 25.225 M w/D0836 Eng. (05/01-on) <b>Lube</b> ..... <b>B7116</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>Radial Seal Air</b> ..... <b>RS4775</b> <b>Cab Air</b> ..... <b>PA3980</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> ..... <b>BA5379 +</b> <b>Steering</b> ..... <b>P106-HD</b>
TGX 24.480 w/D 2676 (Euro 6) Eng. (09/12-on) <b>Lube</b> (51055010009)..... <b>P40042</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>Radial Seal O. Air</b> (81084050033)..... <b>RS4971</b> <b>Radial Seal I. Air</b> (81084050017). <b>RS5361</b> <b>Cab Air</b> (w/o Charcoal) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Charcoal) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>	TGX 24.540 w/D 2676 (Euro 6) Eng. (09/12-on) <b>Lube</b> (51055010009)..... <b>P40042</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>Radial Seal O. Air</b> (81084050033)..... <b>RS4971</b> <b>Radial Seal I. Air</b> (81084050017). <b>RS5361</b> <b>Cab Air</b> (w/o Charcoal) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Charcoal) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>	25.240 w/D2566 Eng. <b>Lube Ele.</b> (81055040041)..... <b>P294</b> <b>P. Fuel Ele.</b> (81125030011)..... <b>F950-F</b> <b>S. Fuel Ele.</b> (81125030042)..... <b>PF231</b> <b>377.8 mm Air</b> ..... <b>PA2813</b> <b>381.0 mm Air</b> (81083040036)..... <b>PA2474</b> <b>495.3 mm Air</b> (81055040033)..... <b>PA3572</b> <b>Hyd.</b> (81055040007)..... <b>PT691</b> M2000 Evo 25.255 M w/D0836 Eng. (05/01-on) <b>Lube</b> ..... <b>B7116</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>Radial Seal Air</b> ..... <b>RS4775</b> <b>Cab Air</b> ..... <b>PA3980</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> ..... <b>BA5379 +</b> <b>Steering</b> ..... <b>P106-HD</b>
TGS 24.540 w/D2076 (Euro 4/5) Eng. (10/07-on) <b>Lube</b> ..... <b>P7329</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>Fuel/Water Separator</b> ..... <b>BF7912</b> <b>Radial Seal O. Air</b> ..... <b>RS4971</b> <b>Radial Seal I. Air</b> ..... <b>RS5361</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (Desiccant)..... <b>BA5374 +</b> <b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>	TGX 24.680 V8 w/D 2868 Eng. (10/07-on) <b>Lube</b> (51055040108)..... <b>P7329</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>Radial Seal O. Air</b> (81084050020)..... <b>RS4971</b> <b>Radial Seal I. Air</b> (81084050017). <b>RS5361</b> <b>Cab Air</b> (w/o Charcoal) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Charcoal) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>	CLA 25.280 w/D0836 EURO3 Eng. (10/06-on) <b>Lube</b> ..... <b>B7116</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>O. Air</b> ..... <b>PA3760</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> M2000 Evo ME 25.280 BL, M2000 Evo ME 25.280 LL w/D0836LF Eng. (05/01-on) <b>Lube</b> ..... <b>B7116</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>Radial Seal Air</b> ..... <b>RS4775</b> <b>Cab Air</b> ..... <b>PA3980</b> <b>Air Dryer</b> ..... <b>BA5374 +</b> <b>Air Dryer</b> ..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>
TGX 24.540 w/D2676 (Euro 4/5) Eng. (10/07-on) <b>Lube</b> ..... <b>P7329</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>Fuel/Water Separator</b> ..... <b>BF7912</b> <b>Radial Seal O. Air</b> ..... <b>RS4971</b> <b>Radial Seal I. Air</b> ..... <b>RS5361</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (Desiccant)..... <b>BA5374 +</b> <b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>	CLA 25.180 w/D0834 EURO3 Eng. (10/06-on) <b>Lube</b> ..... <b>B7116</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>O. Air</b> ..... <b>PA3760</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> 25.220 w/D2566 Eng. <b>Lube</b> (81055040041)..... <b>P294</b> <b>P. Fuel Ele.</b> (81125030011)..... <b>F950-F</b> <b>S. Fuel Ele.</b> (81125030042)..... <b>PF231</b> <b>Air</b> (81083040045)..... <b>PA2474</b>	M2000 Evo 25.284FNL-240, M2000 Evo 25.284FNL-280 w/D0836LF Eng. (05/01-on) <b>Lube</b> ..... <b>B7116</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>Radial Seal Air</b> ..... <b>RS4775</b> <b>Cab Air</b> ..... <b>PA3980</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> ..... <b>BA5379 +</b>
	CLA 25.220 w/D0836 EURO2 Eng. (10/06-on) <b>Lube</b> ..... <b>B7116</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>O. Air</b> ..... <b>PA3760</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>M.A.N.</b> <b>European Trucks (cont'd)</b>	<b>M.A.N.</b> <b>European Trucks (cont'd)</b>	<b>M.A.N.</b> <b>European Trucks (cont'd)</b>
M2000 Evo 25.284FNL-240, M2000 Evo 25.284FNL-280 w/D0836LF Eng. (05/01-on) (Cont'd) Steering (81473016005)..... <b>P106-HD</b>	26.230 w/D2146, D2156, D2356 Engs. Lube (81055040026)..... <b>P235</b> P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> Hyd. (81055040007)..... <b>PT691</b>	26.256 w/D2538 Eng. (Cont'd) <b>148.4 mm S. Fuel</b> (81125030042)..... <b>PF231</b> <b>O. Air</b> (81082050005)..... <b>PA2475</b> <b>I. Air</b> ..... <b>PA2814</b> <b>Single Air</b> (81083040024)..... <b>PA3605</b> <b>Hyd.</b> (81055040007)..... <b>PT691</b>
M2000 Evo 25.285 M w/D0836 Eng. (05/01-on) Lube..... <b>B7116</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>Radial Seal Air</b> ..... <b>RS4775</b> <b>Cab Air</b> ..... <b>PA3980</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> ..... <b>BA5379 +</b> Steering (81473016005)..... <b>P106-HD</b>	26.240 w/D2556 Eng. Lube (81055040025)..... <b>P721</b> <b>115.1 mm P. Fuel</b> (81125030050)..... <b>F953-F</b> <b>142.9 mm P. Fuel</b> (81125030011)..... <b>F950-F</b> <b>108.7 mm S. Fuel</b> (81125030041)..... <b>PF834</b> <b>148.4 mm S. Fuel</b> (81125030042)..... <b>PF231</b> <b>O. Air</b> (81083040036)..... <b>PA2474</b> <b>I. Air</b> ..... <b>PA2836</b> <b>Hyd.</b> (81055040007)..... <b>PT691</b>	26.272 w/D2865 Eng. <b>188.1 mm Lube</b> (To 1989) (51055040085)..... <b>P242</b> <b>264.3 mm Lube</b> (81055040041)... <b>P294</b> <b>Fuel Ele.</b> (81125030042)..... <b>PF231</b> <b>Fuel Spin-on</b> (81125030075)..... <b>BF587-D +</b> <b>O. Air</b> (81083040038)..... <b>PA2776</b>
M2000 Evo 25.285 MNLRC w/D0836LF Eng. (05/01-on) Lube..... <b>B7116</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>Radial Seal Air</b> ..... <b>RS4775</b> <b>Cab Air</b> ..... <b>PA3980</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> ..... <b>BA5379 +</b> Steering (81473016005)..... <b>P106-HD</b>	TGM 26.250 w/D0836 Eng. (09/08-on) Lube..... <b>P7196</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> <b>414.3 mm Radial Seal Air</b> (81084050022)..... <b>RS5409</b> <b>457.2 mm Radial Seal Air</b> (Mann 81084050018)..... <b>RS5506</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b> <b>Air Dryer</b> (Desiccant) (Mann TB1374x)..... <b>BA5374 +</b> Steering (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>	F2000 26.273 w/D2865, D2875 Engs. (01/94-04/96) Lube (1/94-1/95) (Mann HU947/1n)..... <b>P7305</b> Lube (2/95-04/96) (Mann HU947/2x)..... <b>P7145</b> <b>Fuel/Water Separator</b> (Mann WDK724)..... <b>BF1372</b> <b>Radial Seal O. Air</b> (81083040094)..... <b>RS3714</b> <b>Radial Seal I. Air</b> (81083040084)..... <b>RS4549</b> <b>Cab Air</b> (Mann CU40110)..... <b>PA3980</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b>
25.332 w/D2866 Eng. Lube (81055040039)..... <b>P294</b> Fuel Ele. (81125030021)..... <b>PF950</b> Fuel Spin-on (81125030075)..... <b>BF587-D +</b> Air (81083040043)..... <b>PA2776</b>	M2000 Evo 26.255 L w/D0836 Eng. (05/01-on) Lube..... <b>B7116</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>Radial Seal Air</b> ..... <b>RS4775</b> <b>Cab Air</b> ..... <b>PA3980</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> ..... <b>BA5379 +</b> Steering (81473016005)..... <b>P106-HD</b>	F2000 26.273 w/D2865 Eng. (05/96-on) Lube..... <b>P7190</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>Radial Seal O. Air</b> ..... <b>RS3714</b> <b>Radial Seal I. Air</b> ..... <b>RS4549</b> <b>Cab Air</b> ..... <b>PA3980</b> <b>Air Dryer</b> ..... <b>BA5379 +</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Trans.</b> (ZF Gearbox)..... <b>PT8385</b>
25.361 w/D2866 Eng. F-F Lube (81055040041)..... <b>P294</b> B-P Lube (81055040048)..... <b>C750-E +</b> P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> O. Air (81083040038)..... <b>PA2776</b> I. Air..... <b>PA3494</b>	26.256 w/D2146, D2156, D2356 Engs. Lube (81055040032)..... <b>P235</b> P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> Hyd. (81055040007)..... <b>PT691</b>	26.280 w/D2566MT Eng. Lube (81055040041)..... <b>P294</b> P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> <b>496.9 mm O. Air</b> (81082050005).. <b>PA2475</b> <b>473.1 mm I. Air</b> ..... <b>PA2814</b> <b>473.9 mm O. Air</b> ..... <b>PA2776</b> Hyd. (81055040007)..... <b>PT691</b>
25.372 w/D2866 Eng. Lube Ele. (81055040041)..... <b>P294</b> Fuel Ele. (81125030042)..... <b>PF231</b> Axial Seal Air (81083040043)..... <b>PA2776</b> <b>Radial Seal O. Air</b> (81083040094)..... <b>RS3714</b> <b>Radial Seal I. Air</b> (81083040084)..... <b>RS4549</b>	26.256 w/D2538 Eng. Lube (81055040041)..... <b>P294</b> <b>115.1 mm P. Fuel</b> (81125030050)..... <b>F953-F</b> <b>142.9 mm P. Fuel</b> (81125030011)..... <b>F950-F</b> <b>108.7 mm S. Fuel</b> (81125030041)..... <b>PF834</b>	TGM 26.280 w/D0836 Eng. (04/06-on) Lube..... <b>P7196</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> <b>414.3 mm Radial Seal Air</b> (81084050022)..... <b>RS5409</b> <b>457.2 mm Radial Seal Air</b> (Mann 81084050018)..... <b>RS5506</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b>
CLA 26.220 w/D 0836 Eng. (10/06-on) Lube (51055017160)..... <b>B7116</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>O. Air</b> (81083040074)..... <b>PA3760</b> Steering (81473016005)..... <b>P106-HD</b>	M2000 Evo 26.225 L w/D0836 Eng. (05/01-on) Lube..... <b>B7116</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>Radial Seal Air</b> ..... <b>RS4775</b> <b>Cab Air</b> ..... <b>PA3980</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> ..... <b>BA5379 +</b> Steering (81473016005)..... <b>P106-HD</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)
TGM 26.280 w/D0836 Eng. (04/06-on) (Cont'd)	TGM 26.290 w/D0836 Eng. (09/08-on) (Cont'd)	TGS 26.320 w/D 2066 (Euro 6) Eng. (09/12-on) (Cont'd)
Steering..... P106-HD	Air Dryer (Desiccant) (Mann TB1374x)..... BA5374 +	Steering (81473016005)..... P106-HD
Urea (81154036015)..... PE5270	Steering (81473016005)..... P106-HD	Urea (81154036015)..... PE5270
CLA 26.280 w/D 0836 Eng. (10/06-on)	Urea (81154036015)..... PE5270	26.320 w/D2530 Eng.
Lube (51055017160)..... B7116	26.291 w/D2866 Eng.	Lube (81055040041)..... P294
Fuel/Water Separator (51125030040)..... BF1372	P. Fuel Ele. (81125030011)..... F950-F	115.1 mm P. Fuel (81125030050)..... F953-F
O. Air (81083040074)..... PA3760	S. Fuel Ele. (81125030042)..... PF231	142.9 mm P. Fuel (81125030011)..... F950-F
Steering (81473016005)..... P106-HD	O. Air (81083040043)..... PA2776	108.7 mm S. Fuel (81125030041)..... PF834
26.281 w/D2566MK Eng.	F2000 26.293 w/D2865 Eng. (01/94-04/96)	148.4 mm S. Fuel (81125030042)..... PF231
Lube (81055040041)..... P294	Lube (1/94-1/95) (Mann HU947/1n)..... P7305	O. Air (81082050005)..... PA2475
P. Fuel Ele. (81125030011)..... F950-F	Lube (2/95-04/96) (Mann HU947/2x)..... P7145	I. Air..... PA2814
S. Fuel Ele. (81125030042)..... PF231	Fuel/Water Separator (Mann WDK724)..... BF1372	Hyd. (81055040007)..... PT691
O. Air (81083040038)..... PA2776	Radial Seal O. Air (Mann C301353)..... RS3714	26.320 w/D2538 Eng.
I. Air..... PA3494	Radial Seal I. Air (Mann C17170)..... RS4549	Lube (81055040041)..... P294
M2000 Evo 26.284DFK Urbn w/D0836LF Eng. (05/01-on)	Cab Air (Mann CU40110)..... PA3980	115.1 mm P. Fuel (81125030050)..... F953-F
Lube..... B7116	Air Dryer (Mann TB1374X)..... BA5374 +	142.9 mm P. Fuel (81125030011)..... F950-F
Fuel/Water Separator (51125030040)..... BF1372	Air Dryer..... BA5379 +	108.7 mm S. Fuel (81125030041)..... PF834
Radial Seal Air..... RS4775	Steering (81473016005)..... P106-HD	148.4 mm S. Fuel (81125030042)..... PF231
Cab Air..... PA3980	M2000 Evo 26.285 DLRK w/D0836LF Eng. (05/01-on)	O. Air (81082050005)..... PA2475
Air Dryer (Mann TB1374X)..... BA5374 +	Lube..... B7116	I. Air..... PA2814
Air Dryer..... BA5379 +	Fuel/Water Separator (51125030040)..... BF1372	Single Air (81083040024)..... PA3605
Steering (81473016005)..... P106-HD	Radial Seal Air..... RS4775	Hyd. (81055040007)..... PT691
M2000 Evo 26.285 L w/D0836 Eng. (05/01-on)	Cab Air..... PA3980	26.320 w/D3530 Eng.
Lube..... B7116	Air Dryer (Mann TB1374X)..... BA5374 +	Lube (81055040041)..... P294
Fuel/Water Separator (51125030040)..... BF1372	Air Dryer..... BA5379 +	P. Fuel Ele. (81125030011)..... F950-F
Radial Seal Air..... RS4775	Steering (81473016005)..... P106-HD	S. Fuel Ele. (81125030042)..... PF231
Cab Air..... PA3980	M2000 Evo 26.285 L w/D0836 Eng. (05/01-on)	Hyd. (81055040007)..... PT691
Air Dryer (Mann TB1374X)..... BA5374 +	Lube..... B7116	TGS 26.320 w/D2066 (Euro 4/5) Eng. (10/07-on)
Air Dryer..... BA5379 +	Fuel/Water Separator (51125030040)..... BF1372	Lube..... P7329
Steering (81473016005)..... P106-HD	Radial Seal Air..... RS4775	P. Fuel (51125030063)..... PF7935
TGM 26.290 w/D0836 Eng. (09/08-on)	Cab Air..... PA3980	S. Fuel (51125030062)..... PF7939
Lube..... P7196	Air Dryer (Mann TB1374X)..... BA5374 +	Fuel/Water Separator..... BF7912
P. Fuel (51125030063)..... PF7935	Air Dryer..... BA5379 +	Radial Seal O. Air..... RS4971
S. Fuel (51125030062)..... PF7939	Steering (81473016005)..... P106-HD	Radial Seal I. Air..... RS5361
414.3 mm Radial Seal Air (81084050022)..... RS5409	TGM 26.290 w/D0836 Eng. (09/08-on)	Cab Air (w/o Carbon) (81619100018)..... PA4955
457.2 mm Radial Seal Air (Mann 81084050018)..... RS5506	Lube..... P7196	Cab Air (w/Carbon) (81619100019)..... PA5477
Cab Air (w/o Carbon) (81619100018)..... PA4955	Fuel/Water Separator (Mann WDK724)..... BF1372	Air Dryer (Desiccant)..... BA5374 +
Cab Air (w/Carbon) (81619100019)..... PA5477	Radial Seal O. Air (Mann C301353)..... RS3714	Air Dryer (Coalescer) (81521086025)..... BA5379 +
Air Dryer (Coalescer) (81521086025)..... BA5379 +	Radial Seal I. Air (Mann C17170)..... RS4549	Steering (81473016005)..... P106-HD
	Cab Air (Mann CU40110)..... PA3980	Urea (81154036015)..... PE5270
	TGS 26.320 w/D 2066 (Euro 6) Eng. (09/12-on)	26.321 w/D2566MK Eng.
	Lube (51055010009)..... P40042	Lube (81055040041)..... P294
	P. Fuel (51125030063)..... PF7935	P. Fuel Ele. (81125030011)..... F950-F
	S. Fuel (51125030062)..... PF7939	S. Fuel Ele. (81125030042)..... PF231
	Radial Seal O. Air (81084050033)..... RS4971	O. Air (81083040038)..... PA2776
	Radial Seal I. Air (81084050017)..... RS5361	I. Air (81084050013)..... PA3494
	Cab Air (w/o Charcoal) (81619100018)..... PA4955	
	Cab Air (w/Charcoal) (81619100019)..... PA5477	
	Air Dryer (81521086025)..... BA5379 +	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)
26.322 w/D2865 Eng. 188.1 mm Lube (To 1989) (51055040085)..... <b>P242</b> 264.3 mm Lube (81055040041)... <b>P294</b> P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> Fuel Spin-on (81125030075)..... <b>BF587-D +</b> O. Air (81083040038)..... <b>PA2776</b>	TGM 26.340 w/D0836 Eng. (09/08-on) Lube..... <b>P7196</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> 414.3 mm Radial Seal Air (81084050022)..... <b>RS5409</b> 457.2 mm Radial Seal Air (Mann 81084050018)..... <b>RS5506</b> Cab Air (w/o Carbon) (81619100018)..... <b>PA4955</b> Cab Air (w/Carbon) (81619100019)..... <b>PA5477</b> Air Dryer (Coalescer) (81521086025)..... <b>BA5379 +</b> Air Dryer (Desiccant) (Mann TB1374x)..... <b>BA5374 +</b> Steering (81473016005)..... <b>P106-HD</b> Urea (81154036015)..... <b>PE5270</b>	TGS 26.360 w/D2066 (Euro 4/5) Eng. (10/07-on) (Cont'd) Cab Air (w/o Carbon) (81619100018)..... <b>PA4955</b> Cab Air (w/Carbon) (81619100019)..... <b>PA5477</b> Air Dryer (Desiccant)..... <b>BA5374 +</b> Air Dryer (Coalescer) (81521086025)..... <b>BA5379 +</b> Steering (81473016005)..... <b>P106-HD</b> Urea (81154036015)..... <b>PE5270</b>
F2000 26.323 w/D2865 Eng. (01/94-04/96) Lube (1/94-1/95) (Mann HU947/1n)..... <b>P7305</b> Lube (2/95-4/96) (Mann HU947/2x)..... <b>P7145</b> Fuel/Water Separator (Mann WDK724)..... <b>BF1372</b> Radial Seal O. Air (Mann C301353)..... <b>RS3714</b> Radial Seal I. Air (Mann C17170)..... <b>RS4549</b> Cab Air (Mann CU40110)..... <b>PA3980</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b>	26.342 w/D2865 Eng. Lube (5/94-1/95) (Mann HU947/1n)..... <b>P7305</b> Lube (2/95-on) (Mann HU947/2x)..... <b>P7145</b> Fuel/Water Separator (Mann WDK724)..... <b>BF1372</b> Radial Seal O. Air (Mann C301353)..... <b>RS3714</b> Radial Seal I. Air (Mann C17170)..... <b>RS4549</b> Cab Air (Mann CU40110)..... <b>PA3980</b>	TGX 26.360 w/D2066 (Euro 4/5) Eng. (10/07-on) Lube..... <b>P7329</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> Fuel/Water Separator..... <b>BF7912</b> Radial Seal O. Air..... <b>RS4971</b> Radial Seal I. Air..... <b>RS5361</b> Cab Air (w/o Carbon) (81619100018)..... <b>PA4955</b> Cab Air (w/Carbon) (81619100019)..... <b>PA5477</b> Air Dryer (Desiccant)..... <b>BA5374 +</b> Air Dryer (Coalescer) (81521086025)..... <b>BA5379 +</b> Steering (81473016005)..... <b>P106-HD</b> Urea (81154036015)..... <b>PE5270</b>
F2000 26.323 w/D2865 Eng. (05/96-on) Lube..... <b>P7190</b> Fuel/Water Separator (51125030040)..... <b>BF1372</b> Radial Seal O. Air..... <b>RS3714</b> Radial Seal I. Air..... <b>RS4549</b> Cab Air..... <b>PA3980</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer..... <b>BA5379 +</b> Trans. (ZF Gearbox)..... <b>PT8385</b>	F2000 26.343 w/D2865 Eng. (01/94-04/96) Lube (1/94-1/95) (Mann HU947/1n)..... <b>P7305</b> Lube (2/95-4/96) (Mann HU947/2x)..... <b>P7145</b> Fuel/Water Separator (Mann WDK724)..... <b>BF1372</b> Radial Seal O. Air (Mann C301353)..... <b>RS3714</b> Radial Seal I. Air (Mann C17170)..... <b>RS4549</b> Cab Air (Mann CU40110)..... <b>PA3980</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b>	TGS 26.360 w/D 2066 (Euro 6) Eng. (09/12-on) Lube (51055010009)..... <b>P40042</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> Radial Seal O. Air (81084050020)..... <b>RS4971</b> Radial Seal I. Air (81084050017)..... <b>RS5361</b> Cab Air (w/o Charcoal) (81619100018)..... <b>PA4955</b> Cab Air (w/Charcoal) (81619100019)..... <b>PA5477</b> Air Dryer (81521086025)..... <b>BA5379 +</b> Steering (81473016005)..... <b>P106-HD</b> Urea (81154036015)..... <b>PE5270</b>
TGM 26.330 w/D0836 Eng. (04/06-on) Lube..... <b>P7196</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> 414.3 mm Radial Seal Air (81084050022)..... <b>RS5409</b> 457.2 mm Radial Seal Air (Mann 81084050018)..... <b>RS5506</b> Cab Air (w/o Carbon) (81619100018)..... <b>PA4955</b> Cab Air (w/Carbon) (81619100019)..... <b>PA5477</b> Air Dryer (81521086025)..... <b>BA5379 +</b> Steering..... <b>P106-HD</b> Urea (81154036015)..... <b>PE5270</b>	F2000 26.343 w/D2865 Eng. (05/96-on) Lube..... <b>P7190</b> Fuel/Water Separator (51125030040)..... <b>BF1372</b> Radial Seal O. Air..... <b>RS3714</b> Radial Seal I. Air..... <b>RS4549</b> Cab Air..... <b>PA3980</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer..... <b>BA5379 +</b> Trans. (ZF Gearbox)..... <b>PT8385</b>	TGX 26.360 w/D 2066 (Euro 6) Eng. (09/12-on) Lube (51055010009)..... <b>P40042</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> Radial Seal O. Air (81084050033)..... <b>RS4971</b> Radial Seal I. Air (81084050017)..... <b>RS5361</b> Cab Air (w/o Charcoal) (81619100018)..... <b>PA4955</b> Cab Air (w/Charcoal) (81619100019)..... <b>PA5477</b> Air Dryer (81521086025)..... <b>BA5379 +</b> Steering (81473016005)..... <b>P106-HD</b> Urea (81154036015)..... <b>PE5270</b>
26.331 w/D2866 Eng. P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> Air (81083040038)..... <b>PA2776</b> Hyd. (81055040007)..... <b>PT691</b>	TGS 26.360 w/D2066 (Euro 4/5) Eng. (10/07-on) Lube..... <b>P7329</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> Fuel/Water Separator..... <b>BF7912</b> Radial Seal O. Air..... <b>RS4971</b> Radial Seal I. Air..... <b>RS5361</b>	
26.332 w/D2866 Eng. Lube Ele. (81055040041)..... <b>P294</b> Fuel Ele. (81125030021)..... <b>PF950</b> Fuel Spin-on (81125030075)..... <b>BF587-D +</b> Air (81083040043)..... <b>PA2776</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)
26.361 w/D2866 Eng. F-F Lube (81055040041)..... <b>P294</b> B-P Lube (81055040048)..... <b>C750-E +</b> P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> O. Air (81083040038)..... <b>PA2776</b> I. Air (81084050013)..... <b>PA3494</b>	F2000 26.364FPLT, F2000 26.364FVLT w/D2866LF(35) Eng. (05/96-on) Lube (51055040098)..... <b>P7190</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>Radial Seal O. Air</b> ..... <b>RS3714</b> <b>Radial Seal I. Air</b> (81083040084). <b>RS4549</b> <b>Cab Air</b> ..... <b>PA3980</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> ..... <b>BA5379 +</b> <b>Trans.</b> (ZF Gearbox)..... <b>PT8385</b>	TGX 26.400 w/D2066 (Euro 4/5) Eng. (10/07-on) <b>Lube</b> ..... <b>P7329</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>Fuel/Water Separator</b> ..... <b>BF7912</b> <b>Radial Seal O. Air</b> ..... <b>RS4971</b> <b>Radial Seal I. Air</b> ..... <b>RS5361</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (Desiccant)..... <b>BA5374 +</b> <b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>
TGA 26.362 Series w/D2866LF Eng. (05/00-03/04) Lube (51055040098)..... <b>P7190</b> <b>Fuel/Water Separator</b> (81125030086)..... <b>BF7912</b> <b>Fuel Pre-filter</b> (51125030062)..... <b>PF7939</b> <b>Fuel</b> ..... <b>PF7878</b> <b>Radial Seal O. Air</b> ..... <b>RS4971</b> <b>Radial Seal I. Air</b> (81084050017). <b>RS5361</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>	26.365 w/D2840 Eng. F-F Lube (81055040041)..... <b>P294</b> B-P Lube (81055040048)..... <b>C750-E +</b> P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> O. Air (81083040038)..... <b>PA2776</b> I. Air..... <b>PA3494</b> Single Air (81083040061)..... <b>PA3606</b>	TGS 26.400 w/D 2066 (Euro 6) Eng. (09/12-on) <b>Lube</b> (51055010009)..... <b>P40042</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>Radial Seal O. Air</b> (81084050033)..... <b>RS4971</b> <b>Radial Seal I. Air</b> (81084050017). <b>RS5361</b> <b>Cab Air</b> (w/o Charcoal) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Charcoal) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>
26.362 w/D2866 Eng. Lube (81055040041)..... <b>P294</b> Fuel Ele. (81125030042)..... <b>PF231</b> Fuel Spin-on (81125030075)..... <b>BF587-D +</b> Air (81083040043)..... <b>PA2776</b>	26.372, 26.422 w/D2866 Eng. Lube Ele. (81055040041)..... <b>P294</b> Fuel Ele. (81125030042)..... <b>PF231</b> Axial Seal Air (81083040038)..... <b>PA2776</b> <b>Radial Seal O. Air</b> (81083040094)..... <b>RS3714</b> <b>Radial Seal I. Air</b> (81083040084). <b>RS4549</b> <b>Cab Air</b> (8169100011)..... <b>PA3980</b>	TGX 26.400 w/D 2066 (Euro 6) Eng. (09/12-on) <b>Lube</b> (51055010009)..... <b>P40042</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>Radial Seal O. Air</b> (81084050033)..... <b>RS4971</b> <b>Radial Seal I. Air</b> (81084050017). <b>RS5361</b> <b>Cab Air</b> (w/o Charcoal) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Charcoal) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>
TGA 26.363 Series w/D2866LF Eng. (05/00-03/04) Lube (51055040098)..... <b>P7190</b> <b>Fuel/Water Separator</b> (81125030086)..... <b>BF7912</b> <b>Fuel Pre-filter</b> (51125030062)..... <b>PF7939</b> <b>Fuel</b> ..... <b>PF7878</b> <b>Radial Seal O. Air</b> ..... <b>RS4971</b> <b>Radial Seal I. Air</b> (81084050017). <b>RS5361</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>	26.373, 26.402 w/D2866 Eng. Lube (1/94-1/95) (Mann HU947/1n)..... <b>P7305</b> Lube (2/95-on) (Mann HU947/2x). <b>P7145</b> <b>Fuel/Water Separator</b> (Mann WDK724)..... <b>BF1372</b> <b>Radial Seal O. Air</b> (Mann C301353)..... <b>RS3714</b> <b>Radial Seal I. Air</b> (Mann C17170)..... <b>RS4549</b> <b>Cab Air</b> (Mann CU40110)..... <b>PA3980</b>	TGX 26.400 w/D2066 (Euro 4/5) Eng. (10/07-on) <b>Lube</b> ..... <b>P7329</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>Fuel/Water Separator</b> ..... <b>BF7912</b> <b>Radial Seal O. Air</b> ..... <b>RS4971</b> <b>Radial Seal I. Air</b> ..... <b>RS5361</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (Desiccant)..... <b>BA5374 +</b> <b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>
26.364 w/D2866 Eng. Lube (Mann HU1381x)..... <b>P7190</b> <b>Fuel/Water Separator</b> (Mann WDK724)..... <b>BF1372</b> <b>Radial Seal O. Air</b> (Mann C301353)..... <b>RS3714</b> <b>Radial Seal I. Air</b> (Mann C17170)..... <b>RS4549</b> <b>Cab Air</b> (Mann CU40110)..... <b>PA3980</b>	TGS 26.400 w/D2066 (Euro 6) Eng. (10/07-on) <b>Lube</b> ..... <b>P7329</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>Fuel/Water Separator</b> ..... <b>BF7912</b> <b>Radial Seal O. Air</b> ..... <b>RS4971</b> <b>Radial Seal I. Air</b> ..... <b>RS5361</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (Desiccant)..... <b>BA5374 +</b> <b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>	26.403 w/D2866 Eng. Lube (1/94-1/95) (Mann HU947/1n)..... <b>P7305</b> Lube (2/95-8/96) (Mann HU947/2x)..... <b>P7145</b> Lube (9/96-on) (Mann HU1381x).. <b>P7190</b> <b>Fuel/Water Separator</b> (Mann WDK724)..... <b>BF1372</b> <b>Radial Seal O. Air</b> (Mann C301353)..... <b>RS3714</b> <b>Radial Seal I. Air</b> (Mann C17170)..... <b>RS4549</b> <b>Cab Air</b> (Mann CU40110)..... <b>PA3980</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>M.A.N.</b> <b>European Trucks (cont'd)</b>	<b>M.A.N.</b> <b>European Trucks (cont'd)</b>	<b>M.A.N.</b> <b>European Trucks (cont'd)</b>
TGA 26.410FPLT w/D2866LF Eng. (05/00-03/04) <b>Lube</b> (51055040098)..... <b>P7190</b> <b>Fuel/Water Separator</b> (81125030086)..... <b>BF7912</b> <b>Fuel Pre-filter</b> (51125030062)..... <b>PF7939</b> <b>Fuel</b> ..... <b>PF7878</b> <b>Radial Seal O. Air</b> ..... <b>RS4971</b> <b>Radial Seal I. Air</b> (81084050017). <b>RS5361</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>	26.414 w/D2866 Eng. (Cont'd) <b>Radial Seal O. Air</b> (Mann C301353)..... <b>RS3714</b> <b>Radial Seal I. Air</b> (Mann C17170)..... <b>RS4549</b> <b>Cab Air</b> (Mann CU40110)..... <b>PA3980</b> F2000 26.414FNLLD, F2000 26.414FPLT, F2000 26.414FVLT w/D2866LF(31) Eng. (05/96-on) <b>Lube</b> (51055040098)..... <b>P7190</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>Radial Seal O. Air</b> ..... <b>RS3714</b> <b>Radial Seal I. Air</b> (81083040084). <b>RS4549</b> <b>Cab Air</b> ..... <b>PA3980</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> ..... <b>BA5379 +</b> <b>Trans.</b> (ZF Gearbox)..... <b>PT8385</b>	TGX 26.440 w/D2066 (Euro 4/5) Eng. (10/07-on) (Cont'd) <b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b> TGS 26.440 w/D 2066, D 2676 (Euro 6) Eng. (09/12-on) <b>Lube</b> (51055010009)..... <b>P40042</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>Radial Seal O. Air</b> (81084050033)..... <b>RS4971</b> <b>Radial Seal I. Air</b> (81084050017). <b>RS5361</b> <b>Cab Air</b> (w/o Charcoal) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Charcoal) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b> TXG 26.440 w/D 2066, D 2676 (Euro 6) Eng. (09/12-on) <b>Lube</b> (51055010009)..... <b>P40042</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>Radial Seal O. Air</b> (81084050033)..... <b>RS4971</b> <b>Radial Seal I. Air</b> (81084050017). <b>RS5361</b> <b>Cab Air</b> (w/o Charcoal) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Charcoal) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>
TGA 26.412 Series w/D2866LF Eng. (05/00-03/04) <b>Lube</b> (51055040098)..... <b>P7190</b> <b>Fuel/Water Separator</b> (81125030086)..... <b>BF7912</b> <b>Fuel Pre-filter</b> (51125030062)..... <b>PF7939</b> <b>Fuel</b> ..... <b>PF7878</b> <b>Radial Seal O. Air</b> ..... <b>RS4971</b> <b>Radial Seal I. Air</b> (81084050017). <b>RS5361</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>	26.423 w/D2866 Eng. <b>Lube</b> (1/94-1/95) (Mann HU9471n)..... <b>P7305</b> <b>Lube</b> (2/95-on) (Mann HU947/2x). <b>P7145</b> <b>Fuel/Water Separator</b> (Mann WDK724)..... <b>BF1372</b> <b>Radial Seal O. Air</b> (Mann C301353)..... <b>RS3714</b> <b>Radial Seal I. Air</b> (Mann C17170)..... <b>RS4549</b> <b>Cab Air</b> (Mann CU40110)..... <b>PA3980</b> TGS 26.440 w/D2066 (Euro 4/5) Eng. (10/07-on) <b>Lube</b> ..... <b>P7329</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>Fuel/Water Separator</b> ..... <b>BF7912</b> <b>Radial Seal O. Air</b> ..... <b>RS4971</b> <b>Radial Seal I. Air</b> ..... <b>RS5361</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (Desiccant)..... <b>BA5374 +</b> <b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>	TGX 26.440 w/D2066 (Euro 4/5) Eng. (10/07-on) <b>Lube</b> ..... <b>P7329</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>Fuel/Water Separator</b> ..... <b>BF7912</b> <b>Radial Seal O. Air</b> ..... <b>RS4971</b> <b>Radial Seal I. Air</b> ..... <b>RS5361</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>
TGA 26.413 Series w/D2866LF Eng. (05/00-03/04) <b>Lube</b> (51055040098)..... <b>P7190</b> <b>Fuel/Water Separator</b> (81125030086)..... <b>BF7912</b> <b>Fuel Pre-filter</b> (51125030062)..... <b>PF7939</b> <b>Fuel</b> ..... <b>PF7878</b> <b>Radial Seal O. Air</b> ..... <b>RS4971</b> <b>Radial Seal I. Air</b> (81084050017). <b>RS5361</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>	TGX 26.440 w/D2066 (Euro 4/5) Eng. (10/07-on) <b>Lube</b> ..... <b>P7329</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>Fuel/Water Separator</b> ..... <b>BF7912</b> <b>Radial Seal O. Air</b> ..... <b>RS4971</b> <b>Radial Seal I. Air</b> ..... <b>RS5361</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (Desiccant)..... <b>BA5374 +</b> <b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>	TGA 26.462 Sereis w/D2876LF Eng. (04/00-on) <b>Lube</b> (51055040098)..... <b>P7190</b> <b>Fuel/Water Separator</b> (81125030086)..... <b>BF7912</b> <b>Fuel Pre-filter</b> (51125030062)..... <b>PF7939</b> <b>Fuel</b> ..... <b>PF7878</b> <b>Radial Seal O. Air</b> ..... <b>RS4971</b> <b>Radial Seal I. Air</b> (81084050017). <b>RS5361</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>
26.414 w/D2866 Eng. <b>Lube</b> (Mann HU1381x)..... <b>P7190</b> <b>Fuel/Water Separator</b> (Mann WDK724)..... <b>BF1372</b>	26.462, 26.502 w/D2840 Eng. <b>F-F Lube</b> (81055040041)..... <b>P294</b> <b>P. Fuel Ele.</b> (81125030011)..... <b>F950-F</b> <b>S. Fuel Ele.</b> (81125030042)..... <b>PF231</b> <b>Fuel Spin-on</b> (51125030004)..... <b>BF587</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)
26.462, 26.502 w/D2840 Eng. (Cont'd) <b>O. Air</b> (81082050005)..... <b>PA2475</b>	TGS 26.480 w/D2076 (Euro 4/5) Eng. (10/07-on) (Cont'd) <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (Desiccant)..... <b>BA5374 +</b> <b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>	TGA 26.513 Sereis w/D2876LF Eng. (04/00-on) <b>Lube</b> (51055040098)..... <b>P7190</b> <b>Fuel/Water Separator</b> (81125030086)..... <b>BF7912</b> <b>Fuel Pre-filter</b> (51125030062)..... <b>PF7939</b> <b>Fuel</b> ..... <b>PF7878</b> <b>Radial Seal O. Air</b> ..... <b>RS4971</b> <b>Radial Seal I. Air</b> (81084050017). <b>RS5361</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>
TGA 26.463 Series w/D2876LF Eng. (04/00-on) <b>Fuel/Water Separator</b> (81125030086)..... <b>BF7912</b> <b>Fuel Pre-filter</b> (51125030062)..... <b>PF7939</b> <b>Fuel</b> ..... <b>PF7878</b> <b>Radial Seal O. Air</b> ..... <b>RS4971</b> <b>Radial Seal I. Air</b> (81084050017). <b>RS5361</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b>	TGX 26.480 w/D2676 (Euro 4/5) Eng. (10/07-on) <b>Lube</b> ..... <b>P7329</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>Fuel/Water Separator</b> ..... <b>BF7912</b> <b>Radial Seal O. Air</b> ..... <b>RS4971</b> <b>Radial Seal I. Air</b> ..... <b>RS5361</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (Desiccant)..... <b>BA5374 +</b> <b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>	TGS 26.540 w/D2076 (Euro 4/5) Eng. (10/07-on) <b>Lube</b> ..... <b>P7329</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>Fuel/Water Separator</b> ..... <b>BF7912</b> <b>Radial Seal O. Air</b> ..... <b>RS4971</b> <b>Radial Seal I. Air</b> ..... <b>RS5361</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (Desiccant)..... <b>BA5374 +</b> <b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>
26.463 w/D2876 Eng. <b>Lube</b> (1/94-1/95) (Mann HU947/1n)..... <b>P7305</b> <b>Lube</b> (2/95-on) (Mann HU947/2x). <b>P7145</b> <b>Fuel/Water Separator</b> (Mann WDK724)..... <b>BF1372</b> <b>Radial Seal O. Air</b> (Mann C301353)..... <b>RS3714</b> <b>Radial Seal I. Air</b> (Mann C17170)..... <b>RS4549</b> <b>Cab Air</b> (Mann CU40110)..... <b>PA3980</b>	TGS 26.480 w/D 2676 (Euro 6) Eng. (09/12-on) <b>Lube</b> (51055010009)..... <b>P40042</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>Radial Seal O. Air</b> (81084050033)..... <b>RS4971</b> <b>Radial Seal I. Air</b> (81084050017). <b>RS5361</b> <b>Cab Air</b> (w/o Charcoal) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Charcoal) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>	TGX 26.540 w/D2676 (Euro 4/5) Eng. (10/07-on) <b>Lube</b> ..... <b>P7329</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>Fuel/Water Separator</b> ..... <b>BF7912</b> <b>Radial Seal O. Air</b> ..... <b>RS4971</b> <b>Radial Seal I. Air</b> ..... <b>RS5361</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (Desiccant)..... <b>BA5374 +</b> <b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>
26.464 w/D2876 Eng. <b>Lube</b> (Mann HU1381x)..... <b>P7190</b> <b>Fuel/Water Separator</b> (Mann WDK724)..... <b>BF1372</b> <b>Radial Seal O. Air</b> (Mann C301353)..... <b>RS3714</b> <b>Radial Seal I. Air</b> (Mann C17170)..... <b>RS4549</b> <b>Cab Air</b> (Mann CU40110)..... <b>PA3980</b>	TGX 26.480 w/D 2676 (Euro 6) Eng. (09/12-on) <b>Lube</b> (51055010009)..... <b>P40042</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>Radial Seal O. Air</b> (81084050033)..... <b>RS4971</b> <b>Radial Seal I. Air</b> (81084050017). <b>RS5361</b> <b>Cab Air</b> (w/o Charcoal) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Charcoal) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>	TGS 26.540 w/D 2676 (Euro 6) Eng. (09/12-on) <b>Lube</b> (51055010009)..... <b>P40042</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>Radial Seal O. Air</b> (81084050033)..... <b>RS4971</b> <b>Radial Seal I. Air</b> (81084050017). <b>RS5361</b> <b>Cab Air</b> (w/o Charcoal) (81619100018)..... <b>PA4955</b>
F2000 26.464FPLT, F2000 26.464FVLT w/D2876LF(06) Eng. (05/96-on) <b>Lube</b> (51055040098)..... <b>P7190</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>Radial Seal O. Air</b> ..... <b>RS3714</b> <b>Radial Seal I. Air</b> (81083040084). <b>RS4549</b> <b>Cab Air</b> ..... <b>PA3980</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> ..... <b>BA5379 +</b> <b>Trans.</b> (ZF Gearbox)..... <b>PT8385</b>	TGS 26.480 w/D2076 (Euro 4/5) Eng. (10/07-on) <b>Lube</b> ..... <b>P7329</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>Fuel/Water Separator</b> ..... <b>BF7912</b> <b>Radial Seal O. Air</b> ..... <b>RS4971</b> <b>Radial Seal I. Air</b> ..... <b>RS5361</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

**Trucks & Buses Applications** **BALDWIN FILTERS**

M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)
TGS 26.540 w/D 2676 (Euro 6) Eng. (09/12-on) (Cont'd) Cab Air (w/Charcoal) (81619100019)..... <b>PA5477</b> Air Dryer (81521086025)..... <b>BA5379 +</b> Steering (81473016005)..... <b>P106-HD</b> Urea (81154036015)..... <b>PE5270</b>	27.314, 27.364 w/D2866 Eng. (Cont'd) Radial Seal I. Air (Mann C17170)..... <b>RS4549</b> Cab Air (Mann CU40110)..... <b>PA3980</b> F2000 27.323 w/D2865 Eng. (01/94-04/96) Lube (1/94-1/95) (Mann HU947/1n)..... <b>P7305</b> Lube (2/95-4/96) (Mann HU947/2x)..... <b>P7145</b> Fuel/Water Separator (Mann WDK724)..... <b>BF1372</b> Radial Seal O. Air (Mann C301353)..... <b>RS3714</b> Radial Seal I. Air (Mann C17170)..... <b>RS4549</b> Cab Air (Mann CU40110)..... <b>PA3980</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b>	F2000 27.343 w/D2865 Eng. (05/96-on) Lube..... <b>P7190</b> Fuel/Water Separator (51125030040)..... <b>BF1372</b> Radial Seal O. Air..... <b>RS3714</b> Radial Seal I. Air..... <b>RS4549</b> Cab Air..... <b>PA3980</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer..... <b>BA5379 +</b> Trans. (ZF Gearbox)..... <b>PT8385</b>
TGX 26.540 w/D 2676 (Euro 6) Eng. (09/12-on) Lube (51055010009)..... <b>P40042</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> Radial Seal O. Air (81084050033)..... <b>RS4971</b> Radial Seal I. Air (81084050017)..... <b>RS5361</b> Cab Air (w/o Charcoal) (81619100018)..... <b>PA4955</b> Cab Air (w/Charcoal) (81619100019)..... <b>PA5477</b> Air Dryer (81521086025)..... <b>BA5379 +</b> Steering (81473016005)..... <b>P106-HD</b> Urea (81154036015)..... <b>PE5270</b>	F2000 27.323 w/D2865 Eng. (05/96-on) Lube..... <b>P7190</b> Fuel/Water Separator (51125030040)..... <b>BF1372</b> Radial Seal O. Air..... <b>RS3714</b> Radial Seal I. Air..... <b>RS4549</b> Cab Air..... <b>PA3980</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer..... <b>BA5379 +</b> Trans. (ZF Gearbox)..... <b>PT8385</b>	27.372 w/D2866 Eng. Lube (Mann H12110/2)..... <b>P294</b> Fuel/Water Separator (Mann WDK724)..... <b>BF1372</b> Air (Mann C30850/2)..... <b>PA2776</b> Cab Air (Mann CU40110)..... <b>PA3980</b>
26.603 w/D2840 Eng. Lube (Mann HU947/2x)..... <b>P7145</b> Fuel/Water Separator (Mann WDK724)..... <b>BF1372</b> Radial Seal Air (Mann C301353)..... <b>RS3714</b> Cab Air (Mann CU40110)..... <b>PA3980</b>	27.342 w/D2865 Eng. Lube (5/94-1/95) (Mann HU947/1n)..... <b>P7305</b> Lube (2/95-on) (Mann HU947/2x)..... <b>P7145</b> Fuel/Water Separator (Mann WDK724)..... <b>BF1372</b> Radial Seal O. Air (Mann C301353)..... <b>RS3714</b> Radial Seal I. Air (Mann C17170)..... <b>RS4549</b> Cab Air (Mann CU40110)..... <b>PA3980</b>	27.373, 27.402 w/D2866 Eng. Lube (1/94-1/95) (Mann HU947/1n)..... <b>P7305</b> Lube (2/95-on) (Mann HU947/2x)..... <b>P7145</b> Fuel/Water Separator (Mann WDK724)..... <b>BF1372</b> Radial Seal O. Air (Mann C301353)..... <b>RS3714</b> Radial Seal I. Air (Mann C17170)..... <b>RS4549</b> Cab Air (Mann CU40110)..... <b>PA3980</b>
TGX 26.680 V8 w/D 2868 Eng. (10/07-on) Lube (51055040108)..... <b>P7329</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> Radial Seal O. Air (81084050020)..... <b>RS4971</b> Radial Seal I. Air (81084050017)..... <b>RS5361</b> Cab Air (w/o Charcoal) (81619100018)..... <b>PA4955</b> Cab Air (w/Charcoal) (81619100019)..... <b>PA5477</b> Air Dryer (81521086025)..... <b>BA5379 +</b> Steering (81473016005)..... <b>P106-HD</b> Urea (81154036015)..... <b>PE5270</b>	F2000 27.343 w/D2865 Eng. (01/94-04/96) Lube (1/94-1/95) (Mann HU947/1n)..... <b>P7305</b> Lube (2/95-4/96) (Mann HU947/2x)..... <b>P7145</b> Fuel/Water Separator (Mann WDK724)..... <b>BF1372</b> Radial Seal O. Air (Mann C301353)..... <b>RS3714</b> Radial Seal I. Air (Mann C17170)..... <b>RS4549</b> Cab Air (Mann CU40110)..... <b>PA3980</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b>	27.403, 27.463 w/D2866, D2876 Eng. Lube (1/94-1/95) (Mann HU947/1n)..... <b>P7305</b> Lube (2/95-8/96) (Mann HU947/2x)..... <b>P7145</b> Lube (9/96-on) (Mann HU1381x)..... <b>P7190</b> Fuel/Water Separator (Mann WDK724)..... <b>BF1372</b> Radial Seal O. Air (Mann C301353)..... <b>RS3714</b> Radial Seal I. Air (Mann C17170)..... <b>RS4549</b> Cab Air (Mann CU40110)..... <b>PA3980</b>
F2000 27.273 w/D2865 Eng. (05/96-on) Lube..... <b>P7190</b> Fuel/Water Separator (51125030040)..... <b>BF1372</b> Radial Seal O. Air (81083040094)..... <b>RS3714</b> Radial Seal I. Air (81083040084)..... <b>RS4549</b> Cab Air..... <b>PA3980</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer..... <b>BA5379 +</b> Trans. (ZF Gearbox)..... <b>PT8385</b>	F2000 27.343 w/D2865 Eng. (05/96-on) Lube..... <b>P7190</b> Fuel/Water Separator (51125030040)..... <b>BF1372</b> Radial Seal O. Air..... <b>RS3714</b> Radial Seal I. Air..... <b>RS4549</b> Cab Air..... <b>PA3980</b>	27.414, 27.464 w/D2866, D2876 Eng. Lube (Mann HU1381x)..... <b>P7190</b> Fuel/Water Separator (Mann WDK724)..... <b>BF1372</b> Radial Seal O. Air (Mann C301353)..... <b>RS3714</b> Radial Seal I. Air (Mann C17170)..... <b>RS4549</b> Cab Air (Mann CU40110)..... <b>PA3980</b>
27.314, 27.364 w/D2866 Eng. Lube (Mann HU1381x)..... <b>P7190</b> Fuel/Water Separator (Mann WDK724)..... <b>BF1372</b> Radial Seal O. Air (Mann C301353)..... <b>RS3714</b>	F2000 27.343 w/D2865 Eng. (05/96-on) Lube..... <b>P7190</b> Fuel/Water Separator (51125030040)..... <b>BF1372</b> Radial Seal O. Air..... <b>RS3714</b> Radial Seal I. Air..... <b>RS4549</b> Cab Air..... <b>PA3980</b>	27.423 w/D2866 Eng. Lube (1/94-1/95) (Mann HU947/1n)..... <b>P7305</b> Lube (2/95-on) (Mann HU947/2x)..... <b>P7145</b> Fuel/Water Separator (Mann WDK724)..... <b>BF1372</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)
27.423 w/D2866 Eng. (Cont'd)	TGS 28.320 w/D 2066 (Euro 6) Eng. (09/12-on) (Cont'd)	TGS 28.360 w/D 2066 (Euro 6) Eng. (09/12-on) (Cont'd)
Radial Seal O. Air (Mann C301353)..... <b>RS3714</b>	Cab Air (w/Charcoal) (81619100019)..... <b>PA5477</b>	Cab Air (w/Charcoal) (81619100019)..... <b>PA5477</b>
Radial Seal I. Air (Mann C17170)..... <b>RS4549</b>	Air Dryer (81521086025)..... <b>BA5379 +</b>	Air Dryer (81521086025)..... <b>BA5379 +</b>
Cab Air (Mann CU40110)..... <b>PA3980</b>	Steering (81473016005)..... <b>P106-HD</b>	Steering (81473016005)..... <b>P106-HD</b>
27.603 w/D2840 Eng.	Urea (81154036015)..... <b>PE5270</b>	Urea (81154036015)..... <b>PE5270</b>
Lube (Mann HU947/2x)..... <b>P7145</b>	F2000 28.343 w/D2865 Eng. (05/96-on)	TGX 28.360 w/D 2066 (Euro 6) Eng. (09/12-on)
Fuel/Water Separator (Mann WDK724)..... <b>BF1372</b>	Lube..... <b>P7190</b>	Lube (51055010009)..... <b>P40042</b>
Radial Seal Air (Mann C301353). <b>RS3714</b>	Fuel/Water Separator (51125030040)..... <b>BF1372</b>	P. Fuel (51125030063)..... <b>PF7935</b>
Cab Air (Mann CU40110)..... <b>PA3980</b>	Radial Seal O. Air..... <b>RS3714</b>	S. Fuel (51125030062)..... <b>PF7939</b>
F2000 28.293 w/D2865 Eng. (05/96-on)	Radial Seal I. Air..... <b>RS4549</b>	S. Fuel (51125030062)..... <b>PF7939</b>
Lube..... <b>P7190</b>	Cab Air..... <b>PA3980</b>	Radial Seal O. Air (81084050033)..... <b>RS4971</b>
Fuel/Water Separator (51125030040)..... <b>BF1372</b>	Air Dryer (Mann TB1374X)..... <b>BA5374 +</b>	Radial Seal I. Air (81084050017). <b>RS5361</b>
Radial Seal O. Air..... <b>RS3714</b>	Air Dryer..... <b>BA5379 +</b>	Cab Air (w/o Charcoal) (81619100018)..... <b>PA4955</b>
Radial Seal I. Air..... <b>RS4549</b>	Trans. (ZF Gearbox)..... <b>PT8385</b>	Cab Air (w/Charcoal) (81619100019)..... <b>PA5477</b>
Cab Air..... <b>PA3980</b>	TGS 28.360 w/D2066 (Euro 4/5) Eng. (10/07-on)	Air Dryer (81521086025)..... <b>BA5379 +</b>
Air Dryer (Mann TB1374X)..... <b>BA5374 +</b>	Lube..... <b>P7329</b>	Steering (81473016005)..... <b>P106-HD</b>
Air Dryer..... <b>BA5379 +</b>	P. Fuel (51125030063)..... <b>PF7935</b>	Urea (81154036015)..... <b>PE5270</b>
Trans. (ZF Gearbox)..... <b>PT8385</b>	S. Fuel (51125030062)..... <b>PF7939</b>	TGS 28.400 w/D2066 (Euro 4/5) Eng. (10/07-on)
28.293, 28.314, 28.343, 28.403 w/D2865, D2866 Engs.	Fuel/Water Separator..... <b>BF7912</b>	Lube..... <b>P7329</b>
Lube (Mann HU1381x)..... <b>P7190</b>	Radial Seal O. Air..... <b>RS4971</b>	P. Fuel (51125030063)..... <b>PF7935</b>
Fuel/Water Separator (Mann WDK724)..... <b>BF1372</b>	Radial Seal I. Air..... <b>RS5361</b>	S. Fuel (51125030062)..... <b>PF7939</b>
Radial Seal O. Air (Mann C301353)..... <b>RS3714</b>	Cab Air (w/o Carbon) (81619100018)..... <b>PA4955</b>	Fuel/Water Separator..... <b>BF7912</b>
Radial Seal I. Air (Mann C17170)..... <b>RS4549</b>	Cab Air (w/Carbon) (81619100019)..... <b>PA5477</b>	Radial Seal O. Air..... <b>RS4971</b>
Cab Air (Mann CU40110)..... <b>PA3980</b>	Air Dryer (Desiccant)..... <b>BA5374 +</b>	Radial Seal I. Air..... <b>RS5361</b>
TGS 28.320 w/D2066 (Euro 4/5) Eng. (10/07-on)	Air Dryer (Coalescer) (81521086025)..... <b>BA5379 +</b>	Cab Air (w/o Carbon) (81619100018)..... <b>PA4955</b>
Lube..... <b>P7329</b>	Steering (81473016005)..... <b>P106-HD</b>	Cab Air (w/Carbon) (81619100019)..... <b>PA5477</b>
P. Fuel (51125030063)..... <b>PF7935</b>	Urea (81154036015)..... <b>PE5270</b>	Air Dryer (Desiccant)..... <b>BA5374 +</b>
S. Fuel (51125030062)..... <b>PF7939</b>	TGX 28.360 w/D2066 (Euro 4/5) Eng. (10/07-on)	Air Dryer (Coalescer) (81521086025)..... <b>BA5379 +</b>
Fuel/Water Separator..... <b>BF7912</b>	Lube..... <b>P7329</b>	Steering (81473016005)..... <b>P106-HD</b>
Radial Seal O. Air..... <b>RS4971</b>	P. Fuel (51125030063)..... <b>PF7935</b>	Urea (81154036015)..... <b>PE5270</b>
Radial Seal I. Air..... <b>RS5361</b>	S. Fuel (51125030062)..... <b>PF7939</b>	TGX 28.400 w/D2066 (Euro 4/5) Eng. (10/07-on)
Cab Air (w/o Carbon) (81619100018)..... <b>PA4955</b>	Fuel/Water Separator..... <b>BF7912</b>	Lube..... <b>P7329</b>
Cab Air (w/Carbon) (81619100019)..... <b>PA5477</b>	Radial Seal O. Air..... <b>RS4971</b>	P. Fuel (51125030063)..... <b>PF7935</b>
Air Dryer (Desiccant)..... <b>BA5374 +</b>	Radial Seal I. Air..... <b>RS5361</b>	S. Fuel (51125030062)..... <b>PF7939</b>
Air Dryer (Coalescer) (81521086025)..... <b>BA5379 +</b>	Cab Air (w/o Carbon) (81619100018)..... <b>PA4955</b>	Fuel/Water Separator..... <b>BF7912</b>
Steering (81473016005)..... <b>P106-HD</b>	Cab Air (w/Carbon) (81619100019)..... <b>PA5477</b>	Radial Seal O. Air..... <b>RS4971</b>
Urea (81154036015)..... <b>PE5270</b>	Air Dryer (Desiccant)..... <b>BA5374 +</b>	Radial Seal I. Air..... <b>RS5361</b>
TGS 28.320 w/D 2066 (Euro 6) Eng. (09/12-on)	Air Dryer (Coalescer) (81521086025)..... <b>BA5379 +</b>	Cab Air (w/o Carbon) (81619100018)..... <b>PA4955</b>
Lube (51055010009)..... <b>P40042</b>	Steering (81473016005)..... <b>P106-HD</b>	Cab Air (w/Carbon) (81619100019)..... <b>PA5477</b>
P. Fuel (51125030063)..... <b>PF7935</b>	Urea (81154036015)..... <b>PE5270</b>	Air Dryer (Desiccant)..... <b>BA5374 +</b>
S. Fuel (51125030062)..... <b>PF7939</b>	TGS 28.360 w/D 2066 (Euro 6) Eng. (09/12-on)	Air Dryer (Coalescer) (81521086025)..... <b>BA5379 +</b>
Radial Seal O. Air (81084050033)..... <b>RS4971</b>	Lube (51055010009)..... <b>P40042</b>	Steering (81473016005)..... <b>P106-HD</b>
Radial Seal I. Air (81084050017). <b>RS5361</b>	P. Fuel (51125030063)..... <b>PF7935</b>	Urea (81154036015)..... <b>PE5270</b>
Cab Air (w/o Charcoal) (81619100018)..... <b>PA4955</b>	S. Fuel (51125030062)..... <b>PF7939</b>	TGS 28.400 w/D 2066 (Euro 6) Eng. (09/12-on)
	Radial Seal O. Air (81084050033)..... <b>RS4971</b>	Lube (51055010009)..... <b>P40042</b>
	Radial Seal I. Air (81084050017). <b>RS5361</b>	P. Fuel (51125030063)..... <b>PF7935</b>
	Cab Air (w/o Charcoal) (81619100018)..... <b>PA4955</b>	S. Fuel (51125030062)..... <b>PF7939</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)
TGS 28.400 w/D 2066 (Euro 6) Eng. (09/12-on) (Cont'd)	TGS 28.440 w/D 2066, D 2676 (Euro 6) Eng. (09/12-on)	TGX 28.480 w/D2676 (Euro 4/5) Eng. (10/07-on)
Radial Seal O. Air (81084050033)..... RS4971	Lube (51055010009)..... P40042	Lube..... P7329
Radial Seal I. Air (81084050017). RS5361	P. Fuel (51125030063)..... PF7935	P. Fuel (51125030063)..... PF7935
Cab Air (w/o Charcoal) (81619100018)..... PA4955	S. Fuel (51125030062)..... PF7939	S. Fuel (51125030062)..... PF7939
Cab Air (w/Charcoal) (81619100019)..... PA5477	Radial Seal O. Air (81084050033)..... RS4971	Fuel/Water Separator..... BF7912
Air Dryer (81521086025)..... BA5379 +	Radial Seal I. Air (81084050017). RS5361	Radial Seal O. Air..... RS4971
Steering (81473016005)..... P106-HD	Cab Air (w/o Charcoal) (81619100018)..... PA4955	Radial Seal I. Air (81084050017). RS5361
Urea (81154036015)..... PE5270	Cab Air (w/Charcoal) (81619100019)..... PA5477	Cab Air (w/o Charcoal) (81619100018)..... PA4955
TGX 28.400 w/D 2066 (Euro 6) Eng. (09/12-on)	Air Dryer (81521086025)..... BA5379 +	Cab Air (w/Charcoal) (81619100019)..... PA5477
Lube (51055010009)..... P40042	Steering (81473016005)..... P106-HD	Air Dryer (81521086025)..... BA5379 +
P. Fuel (51125030063)..... PF7935	Urea (81154036015)..... PE5270	Steering (81473016005)..... P106-HD
S. Fuel (51125030062)..... PF7939	TGX 28.440 w/D 2066, D 2676 (Euro 6) Eng. (09/12-on)	Urea (81154036015)..... PE5270
Radial Seal O. Air (81084050033)..... RS4971	Lube (51055010009)..... P40042	TGS 28.480 w/D 2676 (Euro 6) Eng. (09/12-on)
Radial Seal I. Air (81084050017). RS5361	P. Fuel (51125030063)..... PF7935	Lube (51055010009)..... P40042
Cab Air (w/o Charcoal) (81619100018)..... PA4955	S. Fuel (51125030062)..... PF7939	P. Fuel (51125030063)..... PF7935
Cab Air (w/Charcoal) (81619100019)..... PA5477	Radial Seal O. Air (81084050033)..... RS4971	S. Fuel (51125030062)..... PF7939
Air Dryer (81521086025)..... BA5379 +	Radial Seal I. Air (81084050017). RS5361	Radial Seal O. Air (81084050033)..... RS4971
Steering (81473016005)..... P106-HD	Cab Air (w/o Charcoal) (81619100018)..... PA4955	Radial Seal I. Air (81084050017). RS5361
Urea (81154036015)..... PE5270	Cab Air (w/Charcoal) (81619100019)..... PA5477	Cab Air (w/o Charcoal) (81619100018)..... PA4955
TGS 28.440 w/D2066 (Euro 4/5) Eng. (10/07-on)	Air Dryer (81521086025)..... BA5379 +	Cab Air (w/Charcoal) (81619100019)..... PA5477
Lube..... P7329	Steering (81473016005)..... P106-HD	Air Dryer (81521086025)..... BA5379 +
P. Fuel (51125030063)..... PF7935	Urea (81154036015)..... PE5270	Steering (81473016005)..... P106-HD
S. Fuel (51125030062)..... PF7939	TGS 28.463, 28.464 w/D2876 Eng.	Urea (81154036015)..... PE5270
Fuel/Water Separator..... BF7912	Lube (Mann HU1381x)..... P7190	TGX 28.480 w/D 2676 (Euro 6) Eng. (09/12-on)
Radial Seal O. Air..... RS4971	Fuel/Water Separator (Mann WDK724)..... BF1372	Lube (51055010009)..... P40042
Radial Seal I. Air..... RS5361	Radial Seal O. Air (Mann C301353)..... RS3714	P. Fuel (51125030063)..... PF7935
Cab Air (w/o Carbon) (81619100018)..... PA4955	Radial Seal I. Air (Mann C17170)..... RS4549	S. Fuel (51125030062)..... PF7939
Cab Air (w/Carbon) (81619100019)..... PA5477	Cab Air (Mann CU40110)..... PA3980	Fuel/Water Separator..... BF7912
Air Dryer (Desiccant)..... BA5374 +	TGS 28.480 w/D2676 (Euro 4/5) Eng. (10/07-on)	Radial Seal O. Air..... RS4971
Air Dryer (Coalescer) (81521086025)..... BA5379 +	Lube..... P7329	Radial Seal I. Air..... RS5361
Steering (81473016005)..... P106-HD	P. Fuel (51125030063)..... PF7935	Cab Air (w/o Carbon) (81619100018)..... PA4955
Urea (81154036015)..... PE5270	S. Fuel (51125030062)..... PF7939	Cab Air (w/Charcoal) (81619100019)..... PA5477
TGX 28.440 w/D2066 (Euro 4/5) Eng. (10/07-on)	Fuel/Water Separator..... BF7912	Air Dryer (81521086025)..... BA5379 +
Lube..... P7329	Radial Seal O. Air..... RS4971	Steering (81473016005)..... P106-HD
P. Fuel (51125030063)..... PF7935	Radial Seal I. Air..... RS5361	Urea (81154036015)..... PE5270
S. Fuel (51125030062)..... PF7939	Cab Air (w/o Carbon) (81619100018)..... PA4955	TGS 28.540 w/D2676 (Euro 4/5) Eng. (10/07-on)
Fuel/Water Separator..... BF7912	Cab Air (w/Carbon) (81619100019)..... PA5477	Lube..... P7329
Radial Seal O. Air..... RS4971	Air Dryer (Desiccant)..... BA5374 +	P. Fuel (51125030063)..... PF7935
Radial Seal I. Air..... RS5361	Air Dryer (Coalescer) (81521086025)..... BA5379 +	S. Fuel (51125030062)..... PF7939
Cab Air (w/o Carbon) (81619100018)..... PA4955	Steering (81473016005)..... P106-HD	Fuel/Water Separator..... BF7912
Cab Air (w/Carbon) (81619100019)..... PA5477	Urea (81154036015)..... PE5270	Radial Seal O. Air..... RS4971
Air Dryer (Desiccant)..... BA5374 +	TGS 28.480 w/D2676 (Euro 4/5) Eng. (10/07-on)	Radial Seal I. Air..... RS5361
Air Dryer (Coalescer) (81521086025)..... BA5379 +	Lube..... P7329	Cab Air (w/o Carbon) (81619100018)..... PA4955
Steering (81473016005)..... P106-HD	P. Fuel (51125030063)..... PF7935	Cab Air (w/Carbon) (81619100019)..... PA5477
Urea (81154036015)..... PE5270	S. Fuel (51125030062)..... PF7939	Air Dryer (Desiccant)..... BA5374 +
	Fuel/Water Separator..... BF7912	Air Dryer (Coalescer) (81521086025)..... BA5379 +
	Radial Seal O. Air..... RS4971	Steering (81473016005)..... P106-HD
	Radial Seal I. Air..... RS5361	Urea (81154036015)..... PE5270
	Cab Air (w/o Carbon) (81619100018)..... PA4955	
	Cab Air (w/Carbon) (81619100019)..... PA5477	
	Air Dryer (Desiccant)..... BA5374 +	
	Air Dryer (Coalescer) (81521086025)..... BA5379 +	
	Steering (81473016005)..... P106-HD	
	Urea (81154036015)..... PE5270	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)
<b>TGX 28.540 w/D2676 (Euro 4/5) Eng. (10/07-on)</b> <b>Lube</b> ..... P7329 <b>P. Fuel</b> (51125030063)..... PF7935 <b>S. Fuel</b> (51125030062)..... PF7939 <b>Fuel/Water Separator</b> ..... BF7912 <b>Radial Seal O. Air</b> ..... RS4971 <b>Radial Seal I. Air</b> ..... RS5361 <b>Cab Air (w/o Carbon)</b> (81619100018)..... PA4955 <b>Cab Air (w/Carbon)</b> (81619100019)..... PA5477 <b>Air Dryer (Desiccant)</b> ..... BA5374 + <b>Air Dryer (Coalescer)</b> (81521086025)..... BA5379 + <b>Steering</b> (81473016005)..... P106-HD <b>Urea</b> (81154036015)..... PE5270	<b>29.414, 29.464 w/D2866, D2876 Engs.</b> <b>Lube (Mann HU1381x)</b> ..... P7190 <b>Fuel/Water Separator (Mann WDK724)</b> ..... BF1372 <b>Radial Seal O. Air (Mann C301353)</b> ..... RS3714 <b>Radial Seal I. Air (Mann C17170)</b> ..... RS4549 <b>Cab Air (Mann CU40110)</b> ..... PA3980 <hr/> <b>30.230 w/D2146, D2156, D2356 Engs.</b> <b>Lube</b> (81055040032)..... P235 <b>P. Fuel Ele.</b> (81125030011)..... F950-F <b>S. Fuel Ele.</b> (81125030042)..... PF231 <b>Hyd.</b> (81055040007)..... PT691 <hr/> <b>30.240 w/D2556 Eng.</b> <b>Lube</b> (81055040025)..... P721 <b>115.1 mm P. Fuel</b> (81125030050)..... F953-F <b>142.9 mm P. Fuel</b> (81125030011)..... F950-F <b>108.7 mm S. Fuel</b> (81125030041)..... PF834 <b>148.4 mm S. Fuel</b> (81125030042)..... PF231 <b>O. Air</b> (81083040036)..... PA2474 <b>I. Air</b> ..... PA2836 <b>Hyd.</b> (81055040007)..... PT691 <hr/> <b>30.240 w/D2566 Eng.</b> <b>Lube Ele.</b> (81055040041)..... P294 <b>P. Fuel Ele.</b> (81125030011)..... F950-F <b>S. Fuel Ele.</b> (81125030042)..... PF231 <b>377.8 mm Air</b> ..... PA2813 <b>381.0 mm Air</b> (81083040036)..... PA2474 <b>495.3 mm Air</b> (81055040033)..... PA3572 <b>Hyd.</b> (81055040007)..... PT691 <hr/> <b>30.256 w/D2146, D2156, D2356 Engs.</b> <b>Lube</b> (81055040032)..... P235 <b>P. Fuel Ele.</b> (81125030011)..... F950-F <b>S. Fuel Ele.</b> (81125030042)..... PF231 <b>Hyd.</b> (81055040007)..... PT691 <hr/> <b>30.256 w/D2538 Eng.</b> <b>Lube</b> (81055040041)..... P294 <b>115.1 mm P. Fuel</b> (81125030050)..... F953-F <b>142.9 mm P. Fuel</b> (81125030011)..... F950-F <b>108.7 mm S. Fuel</b> (81125030041)..... PF834 <b>148.4 mm S. Fuel</b> ..... PF231 <b>O. Air</b> (81082050005)..... PA2475 <b>I. Air</b> ..... PA2814 <b>Hyd.</b> (81055040007)..... PT691 <hr/> <b>30.280 w/D2566MT Eng.</b> <b>Lube Ele.</b> (81055040041)..... P294 <b>P. Fuel Ele.</b> (81125030011)..... F950-F <b>S. Fuel Ele.</b> (81125030042)..... PF231 <b>473.1 mm I. Air</b> ..... PA2814 <b>473.9 mm O. Air</b> ..... PA2776	<b>30.280 w/D2566MT Eng. (Cont'd)</b> <b>496.9 mm O. Air</b> (81082050005)..... PA2475 <b>Hyd.</b> (81055040007)..... PT691 <hr/> <b>30.281 w/D2566MK Eng.</b> <b>Lube</b> (81055040041)..... P294 <b>P. Fuel Ele.</b> (81125030011)..... F950-F <b>S. Fuel Ele.</b> (81125030042)..... PF231 <b>O. Air</b> (81083040038)..... PA2776 <b>I. Air</b> (81084050013)..... PA3494 <hr/> <b>30.291 w/D2866 Eng.</b> <b>P. Fuel Ele.</b> (81125030011)..... F950-F <b>S. Fuel Ele.</b> (81125030042)..... PF231 <b>O. Air</b> (81083040038)..... PA2776 <hr/> <b>F2000 30.293 w/D2865 Eng. (05/96-on)</b> <b>Lube (Mann HU1381x)</b> ..... P7190 <b>Fuel/Water Separator</b> (51125030040)..... BF1372 <b>Radial Seal O. Air (Mann C301353)</b> ..... RS3714 <b>Radial Seal I. Air (Mann C17170)</b> ..... RS4549 <b>Cab Air (Mann CU40110)</b> ..... PA3980 <b>Air Dryer (Mann TB1374X)</b> ..... BA5374 + <b>Air Dryer</b> ..... BA5379 + <b>Trans. (ZF Gearbox)</b> ..... PT8385 <b>Steering</b> ..... P106-HD <hr/> <b>30.304 w/D2858 Eng.</b> <b>Lube</b> (81055040025)..... P721 <b>P. Fuel Ele.</b> (81125030011)..... F950-F <b>S. Fuel Ele.</b> (81125030042)..... PF231 <b>Hyd.</b> (81055040007)..... PT691 <hr/> <b>30.314 w/D2866 Eng.</b> <b>Lube (Mann HU1381x)</b> ..... P7190 <b>Fuel/Water Separator (Mann WDK724)</b> ..... BF1372 <b>Radial Seal O. Air (Mann C301353)</b> ..... RS3714 <b>Radial Seal I. Air (Mann C17170)</b> ..... RS4549 <b>Cab Air (Mann CU40110)</b> ..... PA3980 <b>Trans. (Mann H710/1n)</b> ..... PT8385 <b>Steering</b> ..... P106-HD <hr/> <b>30.320 w/D2530 Eng.</b> <b>115.1 mm P. Fuel</b> (81125030050)..... F953-F <b>142.9 mm P. Fuel</b> (81125030011)..... F950-F <b>108.7 mm S. Fuel</b> (81125030041)..... PF834 <b>148.4 mm S. Fuel</b> (81125030042)..... PF231 <b>O. Air</b> (81082050005)..... PA2475 <b>I. Air</b> ..... PA2814 <b>Hyd.</b> (81055040007)..... PT691
<b>TGS 28.540 w/D 2676 (Euro 6) Eng. (09/12-on)</b> <b>Lube</b> (51055010009)..... P40042 <b>P. Fuel</b> (51125030063)..... PF7935 <b>S. Fuel</b> (51125030062)..... PF7939 <b>Radial Seal O. Air</b> (81084050033)..... RS4971 <b>Radial Seal I. Air</b> (81084050017)..... RS5361 <b>Cab Air (w/o Charcoal)</b> (81619100018)..... PA4955 <b>Cab Air (w/Charcoal)</b> (81619100019)..... PA5477 <b>Air Dryer</b> (81521086025)..... BA5379 + <b>Steering</b> (81473016005)..... P106-HD <b>Urea</b> (81154036015)..... PE5270	<b>TGX 28.540 w/D 2676 (Euro 6) Eng. (09/12-on)</b> <b>Lube</b> (51055010009)..... P40042 <b>P. Fuel</b> (51125030063)..... PF7935 <b>S. Fuel</b> (51125030062)..... PF7939 <b>Radial Seal O. Air</b> (81084050033)..... RS4971 <b>Radial Seal I. Air</b> (81084050017)..... RS5361 <b>Cab Air (w/o Charcoal)</b> (81619100018)..... PA4955 <b>Cab Air (w/Charcoal)</b> (81619100019)..... PA5477 <b>Air Dryer</b> (81521086025)..... BA5379 + <b>Steering</b> (81473016005)..... P106-HD <b>Urea</b> (81154036015)..... PE5270	
<b>TGX 28.680 V8 w/D 2868 Eng. (10/07-on)</b> <b>Lube</b> (51055040108)..... P7329 <b>P. Fuel</b> (51125030063)..... PF7935 <b>S. Fuel</b> (51125030062)..... PF7939 <b>Radial Seal O. Air</b> (81084050020)..... RS4971 <b>Radial Seal I. Air</b> (81084050017)..... RS5361 <b>Cab Air (w/o Charcoal)</b> (81619100018)..... PA4955 <b>Cab Air (w/Charcoal)</b> (81619100019)..... PA5477 <b>Air Dryer</b> (81521086025)..... BA5379 + <b>Steering</b> (81473016005)..... P106-HD <b>Urea</b> (81154036015)..... PE5270		

+ See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>M.A.N.</b> <b>European Trucks (cont'd)</b>	<b>M.A.N.</b> <b>European Trucks (cont'd)</b>	<b>M.A.N.</b> <b>European Trucks (cont'd)</b>
30.320 w/D2538 Eng. Lube (81055040041)..... <b>P294</b> 115.1 mm P. Fuel (81125030050)..... <b>F953-F</b> 142.9 mm P. Fuel (81125030011)..... <b>F950-F</b> 108.7 mm S. Fuel (81125030041)..... <b>PF834</b> 148.4 mm S. Fuel..... <b>PF231</b> O. Air (81082050005)..... <b>PA2475</b> I. Air..... <b>PA2814</b> Hyd. (81055040007)..... <b>PT691</b>	32.242 w/D2866 Eng. Lube (81055040041)..... <b>P294</b> P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> Fuel Spin-on (81125030075)..... <b>BF587-D*</b> Air (81083040038)..... <b>PA2776</b> 32.262, 32.272 w/D2865 Eng. 188.1 mm Lube (51055040068).... <b>P242</b> 264.3 mm Lube (81055040041).... <b>P294</b> Fuel Ele. (81125030042)..... <b>PF231</b> Fuel Spin-on (81125030075)..... <b>BF587-D*</b> Air (81083040038)..... <b>PA2776</b> 32.280 w/D2566MT Eng. Lube (81055040041)..... <b>P294</b> P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> 496.9 mm O. Air (81082050005).... <b>PA2475</b> 473.1 mm I. Air..... <b>PA2814</b> 473.9 mm O. Air..... <b>PA2776</b> Hyd. (81055040007)..... <b>PT691</b> 32.281 w/D2566, D2566MK, D2566MKF Eng. Lube (81055040041)..... <b>P294</b> P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> O. Air (81083040038)..... <b>PA2776</b> I. Air (81084050013)..... <b>PA3494</b> 32.291 w/D2866 Eng. P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> O. Air (81083040043)..... <b>PA2776</b> 32.292 w/D2866 Eng. Lube (81055040041)..... <b>P294</b> P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> Fuel Spin-on (81125030075)..... <b>BF587-D*</b> Air (81083040038)..... <b>PA2776</b> F2000 32.293 w/D2865 Eng. (05/96-on) Lube..... <b>P7190</b> Fuel/Water Separator (51125030040)..... <b>BF1372</b> Radial Seal O. Air..... <b>RS3714</b> Radial Seal I. Air..... <b>RS4549</b> Cab Air..... <b>PA3980</b> Air Dryer (Mann TB1374X)..... <b>BA5374*</b> Air Dryer..... <b>BA5379*</b> Trans. (ZF Gearbox)..... <b>PT8385</b> 32.293VF, 32.343 w/D2865LF24 Eng. Lube (8/95-8/96) (51055040096).... <b>P7145</b> Lube (9/96-on) (51055040098).... <b>P7190</b> Fuel (51125030031)..... <b>BF587</b> Radial Seal O. Air (81083040083)..... <b>RS3714</b> Radial Seal I. Air (81083040084).... <b>RS4549</b> Cab Air (8169100011)..... <b>PA3980</b>	32.314F, 32.314VF, 32.364 w/D2866LF34 Eng. Lube (51055040098)..... <b>P7190</b> Fuel (51125030031)..... <b>BF587</b> Radial Seal O. Air (81083040083)..... <b>RS3714</b> Radial Seal I. Air (81083040084).... <b>RS4549</b> Cab Air (8169100011)..... <b>PA3980</b> TGS 32.320 w/D2066 (Euro 4/5) Eng. (10/07-on) Lube..... <b>P7329</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> Fuel/Water Separator..... <b>BF7912</b> Radial Seal O. Air..... <b>RS4971</b> Radial Seal I. Air..... <b>RS5361</b> Cab Air (w/o Carbon) (81619100018)..... <b>PA4955</b> Cab Air (w/Carbon) (81619100019)..... <b>PA5477</b> Air Dryer (Coalescer) (81521086025)..... <b>BA5379*</b> Air Dryer (Desiccant) (Mann TB1374x)..... <b>BA5374*</b> Steering (81473016005)..... <b>P106-HD</b> Urea (81154036015)..... <b>PE5270</b> 32.320 w/D2530 Eng. 115.1 mm P. Fuel (81125030050)..... <b>F953-F</b> 142.9 mm P. Fuel (81125030011)..... <b>F950-F</b> 108.7 mm S. Fuel (81125030041)..... <b>PF834</b> 148.4 mm S. Fuel (81125030042)..... <b>PF231</b> O. Air (81082050005)..... <b>PA2475</b> I. Air..... <b>PA2814</b> Hyd. (81055040007)..... <b>PT691</b> 32.320 w/D2538 Eng. Lube (81055040041)..... <b>P294</b> 115.1 mm P. Fuel (81125030050)..... <b>F953-F</b> 142.9 mm P. Fuel (81125030011)..... <b>F950-F</b> 108.7 mm S. Fuel (81125030041)..... <b>PF834</b> 148.4 mm S. Fuel (81125030042)..... <b>PF231</b> O. Air (81082050005)..... <b>PA2475</b> I. Air..... <b>PA2814</b> Hyd. (81055040007)..... <b>PT691</b> 32.321 w/D2566MK, D2566MKF Eng. F-F Lube (81055040041)..... <b>P294</b> P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> O. Air (81083040038)..... <b>PA2776</b> I. Air..... <b>PA3494</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)
32.322 w/D2865 Eng. 188.1 mm Lube (51055040068)... <b>P242</b> 264.3 mm Lube (81055040041)... <b>P294</b> P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> Fuel Spin-on (81125030075)..... <b>BF587-D</b> + Air (81083040038)..... <b>PA2776</b>	35.364F, 35.364VF w/D2865LF35 Eng. F-F Lube (81055040041)..... <b>P294</b> B-P Lube (81055040048)..... <b>C750-E</b> + P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> O. Air (81083040038)..... <b>PA2776</b> I. Air..... <b>PA3494</b>	35.364F, 35.364VF w/D2865LF35 Eng. Lube (5/94-1/95) (Mann HU947/1n)..... <b>P7305</b> Lube (2/95-on) (Mann HU947/2x)..... <b>P7145</b> Fuel/Water Separator (Mann WDK724)..... <b>BF1372</b> Radial Seal O. Air (Mann C301353)..... <b>RS3714</b> Radial Seal I. Air (Mann C17170)..... <b>RS4549</b> Cab Air (Mann CU40110)..... <b>PA3980</b>
32.331 w/D2866 Eng. P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> Air (81083040038)..... <b>PA2776</b> Hyd. (81055040007)..... <b>PT691</b>	32.362 w/D2866 Eng. Lube (81055040039)..... <b>P294</b> Fuel Ele. (81125030021)..... <b>PF950</b> Fuel Spin-on (81125030075)..... <b>BF587-D</b> + Air (81083040038)..... <b>PA2776</b>	32.403, 32.463 w/D2866, D2876 Eng. Lube (8/95-8/96) (51055040096).. <b>P7145</b> Lube (9/96-on) (51055040098)..... <b>P7190</b> Fuel (51125030031)..... <b>BF587</b> Radial Seal O. Air (81083040083)..... <b>RS3714</b> Radial Seal I. Air (81083040084)..... <b>RS4549</b> Cab Air (8169100011)..... <b>PA3980</b>
35.343VF w/D2865LF21 Eng. Lube (81055040039)..... <b>P294</b> Fuel Ele. (81125030021)..... <b>PF950</b> Fuel Spin-on (81125030075)..... <b>BF587-D</b> + Air (81083040038)..... <b>PA2776</b>	F2000 Evo 32.364VFL w/D2866LF(31) Eng. (05/96-on) Lube (51055040098)..... <b>P7190</b> Fuel/Water Separator (51125030040)..... <b>BF1372</b> Radial Seal O. Air..... <b>RS3714</b> Radial Seal I. Air (81083040084)..... <b>RS4549</b> Cab Air..... <b>PA3980</b> Air Dryer (Mann TB1374X)..... <b>BA5374</b> + Air Dryer..... <b>BA5379</b> + Trans. (ZF Gearbox)..... <b>PT8385</b>	32.414F, 32.414VF, 32.464 w/D2866, D2876 Eng. Lube (51055040098)..... <b>P7190</b> Fuel (51125030031)..... <b>BF587</b> Radial Seal O. Air (81083040083)..... <b>RS3714</b> Radial Seal I. Air (81083040084)..... <b>RS4549</b> Cab Air (8169100011)..... <b>PA3980</b>
32.342 w/D2865 Eng. Lube (5/94-1/95) (Mann HU947/1n)..... <b>P7305</b> Lube (2/95-on) (Mann HU947/2x)..... <b>P7145</b> Fuel/Water Separator (Mann WDK724)..... <b>BF1372</b> Radial Seal O. Air (Mann C301353)..... <b>RS3714</b> Radial Seal I. Air (Mann C17170)..... <b>RS4549</b> Cab Air (Mann CU40110)..... <b>PA3980</b>	32.365, 33.365 w/D2840 Eng. F-F Lube (81055040041)..... <b>P294</b> B-P Lube (81055040048)..... <b>C750-E</b> + P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> O. Air (81083040038)..... <b>PA2776</b> I. Air..... <b>PA3494</b> Single Air (81083040061)..... <b>PA3606</b>	32.422 w/D2866 Eng. Lube (81055040039)..... <b>P294</b> Fuel Ele. (81125030042)..... <b>PF231</b> Axial Seal Air (81083040038)..... <b>PA2776</b> Radial Seal O. Air (81083040094)..... <b>RS3714</b> Radial Seal I. Air (81083040084)..... <b>RS4549</b>
F2000 32.343 w/D2865 Eng. (05/96-on) Lube..... <b>P7190</b> Fuel/Water Separator (51125030040)..... <b>BF1372</b> Radial Seal O. Air..... <b>RS3714</b> Radial Seal I. Air..... <b>RS4549</b> Cab Air..... <b>PA3980</b> Air Dryer (Mann TB1374X)..... <b>BA5374</b> + Air Dryer..... <b>BA5379</b> + Trans. (ZF Gearbox)..... <b>PT8385</b>	35.343VF w/D2865LF21 Eng. Lube (81055040039)..... <b>P294</b> Fuel Ele. (81125030042)..... <b>PF231</b> Axial Seal Air (81083040038)..... <b>PA2776</b> Radial Seal O. Air (81083040094)..... <b>RS3714</b> Radial Seal I. Air (81083040084)..... <b>RS4549</b> Cab Air (8169100011)..... <b>PA3980</b>	TGS 32.440 w/D2066 (Euro 4/5) Eng. (10/07-on) Lube..... <b>P7329</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> Fuel/Water Separator..... <b>BF7912</b> Radial Seal O. Air..... <b>RS4971</b> Radial Seal I. Air..... <b>RS5361</b> Cab Air (w/o Carbon) (81619100018)..... <b>PA4955</b> Cab Air (w/Carbon) (81619100019)..... <b>PA5477</b> Air Dryer (Coalescer) (81521086025)..... <b>BA5379</b> + Air Dryer (Desiccant) (Mann TB1374x)..... <b>BA5374</b> + Steering (81473016005)..... <b>P106-HD</b> Urea (81154036015)..... <b>PE5270</b>
TGS 32.360 w/D2066 (Euro 4/5) Eng. (10/07-on) Lube..... <b>P7329</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> Fuel/Water Separator..... <b>BF7912</b> Radial Seal O. Air..... <b>RS4971</b> Radial Seal I. Air..... <b>RS5361</b> Cab Air (w/o Carbon) (81619100018)..... <b>PA4955</b> Cab Air (w/Carbon) (81619100019)..... <b>PA5477</b> Air Dryer (Coalescer) (81521086025)..... <b>BA5379</b> + Air Dryer (Desiccant) (Mann TB1374x)..... <b>BA5374</b> + Steering (81473016005)..... <b>P106-HD</b> Urea (81154036015)..... <b>PE5270</b>	TGS 32.400 w/D2066 (Euro 4/5) Eng. (10/07-on) Lube..... <b>P7329</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> Fuel/Water Separator..... <b>BF7912</b> Radial Seal O. Air..... <b>RS4971</b> Radial Seal I. Air..... <b>RS5361</b> Cab Air (w/o Carbon) (81619100018)..... <b>PA4955</b> Cab Air (w/Carbon) (81619100019)..... <b>PA5477</b> Air Dryer (Coalescer) (81521086025)..... <b>BA5379</b> + Air Dryer (Desiccant) (Mann TB1374x)..... <b>BA5374</b> + Steering (81473016005)..... <b>P106-HD</b> Urea (81154036015)..... <b>PE5270</b>	32.462 w/D2840 Eng. Lube (81055040041)..... <b>P294</b> P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> Air (81082050005)..... <b>PA2475</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

**Trucks & Buses Applications** **BALDWIN FILTERS**

<b>M.A.N.</b> <b>European Trucks (cont'd)</b>	<b>M.A.N.</b> <b>European Trucks (cont'd)</b>	<b>M.A.N.</b> <b>European Trucks (cont'd)</b>
TGS 32.480 w/D2066 (Euro 4/5) Eng. (10/07-on)	TGS 33.320 w/D 2066 (Euro 6) Eng. (09/12-on)	F2000 33.342 w/D2865 Eng. (01/94-04/96)
Lube..... P7329	Lube (51055010009)..... P40042	Lube (1/94-1/95) (Mann
P. Fuel (51125030063)..... PF7935	P. Fuel (51125030063)..... PF7935	HU947/1n)..... P7305
S. Fuel (51125030062)..... PF7939	S. Fuel (51125030062)..... PF7939	Lube (2/95-4/96) (Mann
Fuel/Water Separator..... BF7912	Radial Seal O. Air	HU947/2x)..... P7145
Radial Seal O. Air..... RS4971	(81084050033)..... RS4971	Fuel/Water Separator (Mann
Radial Seal I. Air..... RS5361	Radial Seal I. Air (81084050017)..... RS5361	WDK724)..... BF1372
Cab Air (w/o Carbon)	Cab Air (w/o Charcoal)	Radial Seal O. Air (Mann
(81619100018)..... PA4955	(81619100018)..... PA4955	C301353)..... RS3714
Cab Air (w/Carbon)	Cab Air (w/Charcoal)	Radial Seal I. Air (Mann
(81619100019)..... PA5477	(81619100019)..... PA5477	C17170)..... RS4549
Air Dryer (Coalescer)	Air Dryer (81521086025)..... BA5379 +	Cab Air (Mann CU40110)..... PA3980
(81521086025)..... BA5379 +	Steering (81473016005)..... P106-HD	Air Dryer (Mann TB1374X)..... BA5374 +
Air Dryer (Desiccant) (Mann	Urea (81154036015)..... PE5270	
TB1374x)..... BA5374 +		35.343VF w/D2865LF21 Eng.
Steering (81473016005)..... P106-HD	33.321 w/D2566MK, D2566MKF Engs.	Lube..... P7190
Urea (81154036015)..... PE5270	F-F Lube (81055040041)..... P294	Fuel/Water Separator
	P. Fuel Ele. (81125030011)..... F950-F	(51125030040)..... BF1372
35.343VF w/D2865LF21 Eng.	S. Fuel Ele. (81125030042)..... PF231	Radial Seal O. Air..... RS3714
Lube (81055040041)..... P294	O. Air (81083040038)..... PA2776	Radial Seal I. Air..... RS4549
P. Fuel Ele. (81125030011)..... F950-F	I. Air..... PA3494	Cab Air..... PA3980
S. Fuel Ele. (81125030042)..... PF231		Air Dryer (Mann TB1374X)..... BA5374 +
Fuel Spin-on (81125030075)..... BF587-D +	33.322 w/D2865 Eng.	Air Dryer..... BA5379 +
Air (81082050005)..... PA2475	188.1 mm Lube (To 1989)	Trans. (ZF Gearbox)..... PT8385
	(51055040068)..... P242	
35.364F, 35.364VF w/D2865LF35 Eng.	264.3 mm Lube (81055040041)..... P294	33.343DF w/D2865LF21 Eng.
Lube (81055040041)..... P294	P. Fuel Ele. (81125030011)..... F950-F	Lube (1/94-1/95) (51055040094)..... P7015
P. Fuel Ele. (81125030011)..... F950-F	S. Fuel Ele. (81125030042)..... PF231	Lube (2/95-8/96) (51055040096)..... P7145
S. Fuel Ele. (81125030042)..... PF231	Fuel Spin-on (81125030075)..... BF587-D +	Lube (9/96-on) (51055040098)..... P7190
Fuel Spin-on (81125030075)..... BF587-D +	Air (81083040038)..... PA2776	Fuel (51125030031)..... BF587
Air (81083040038)..... PA2776		Radial Seal O. Air
	F2000 33.323 w/D2865 Eng. (01/94-04/96)	(81083040083)..... RS3714
33.272 w/D2865 Eng.	Lube (1/94-1/95) (Mann	Radial Seal I. Air (81083040084)..... RS4549
188.1 mm Lube (To 1989)	HU947/1n)..... P7305	Cab Air (8169100011)..... PA3980
(51055040068)..... P242	Lube (2/95-4/96) (Mann	
264.3 mm Lube (81055040041)..... P294	HU947/2x)..... P7145	TGS 33.360 w/D2066 (Euro 4/5) Eng. (10/07-on)
P. Fuel Ele. (81125030042)..... PF231	Fuel/Water Separator (Mann	Lube..... P7329
Fuel Spin-on (81125030075)..... BF587-D +	WDK724)..... BF1372	P. Fuel (51125030063)..... PF7935
Air (81083040038)..... PA2776	Radial Seal O. Air (Mann	S. Fuel (51125030062)..... PF7939
	C301353)..... RS3714	Fuel/Water Separator..... BF7912
33.463DF w/D2876LF02 Eng.	Radial Seal I. Air (Mann	Radial Seal O. Air..... RS4971
Lube (81055040041)..... P294	C17170)..... RS4549	Radial Seal I. Air..... RS5361
P. Fuel Ele. (81125030011)..... F950-F	Cab Air (Mann CU40110)..... PA3980	Cab Air (w/o Carbon)
S. Fuel Ele. (81125030042)..... PF231		(81619100018)..... PA4955
Fuel Spin-on (81125030075)..... BF587-D +	F2000 33.323 w/D2865 Eng. (05/96-on)	Cab Air (w/Carbon)
Air (81083040038)..... PA2776	Lube..... P7190	(81619100019)..... PA5477
	Fuel/Water Separator	Air Dryer (Desiccant)..... BA5374 +
TGS 33.320 w/D2066 (Euro 4/5) Eng. (10/07-on)	(51125030040)..... BF1372	Air Dryer (Coalescer)
Lube..... P7329	Radial Seal O. Air..... RS3714	(81521086025)..... BA5379 +
P. Fuel (51125030063)..... PF7935	Radial Seal I. Air..... RS4549	Steering (81473016005)..... P106-HD
S. Fuel (51125030062)..... PF7939	Cab Air..... PA3980	Urea (81154036015)..... PE5270
Fuel/Water Separator..... BF7912	Air Dryer (Mann TB1374X)..... BA5374 +	
Radial Seal O. Air..... RS4971	Air Dryer..... BA5379 +	TGX 33.360 w/D2066 (Euro 4/5) Eng. (10/07-on)
Radial Seal I. Air..... RS5361	Trans. (ZF Gearbox)..... PT8385	Lube..... P7329
Cab Air (w/o Carbon)		P. Fuel (51125030063)..... PF7935
(81619100018)..... PA4955	33.332 w/D2866 Eng.	S. Fuel (51125030062)..... PF7939
Cab Air (w/Carbon)	Lube (81055040039)..... P294	Fuel/Water Separator..... BF7912
(81619100019)..... PA5477	Fuel Ele. (81125030021)..... PF950	Radial Seal O. Air..... RS4971
Air Dryer (Desiccant)..... BA5374 +	Fuel Spin-on (81125030075)..... BF587-D +	Radial Seal I. Air..... RS5361
Air Dryer (Coalescer)	Air (81083040038)..... PA2776	Cab Air (w/o Carbon)
(81521086025)..... BA5379 +		(81619100018)..... PA4955
Steering (81473016005)..... P106-HD		Cab Air (w/Carbon)
Urea (81154036015)..... PE5270		(81619100019)..... PA5477

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)
TGX 33.360 w/D2066 (Euro 4/5) Eng. (10/07-on) (Cont'd)	33.373, 33.402 w/D2866 Eng.	TGX 33.400 w/D 2066 (Euro 6) Eng. (09/12-on)
Air Dryer (Desiccant)..... BA5374 +	Lube (1/94-1/95) (Mann HU947/1n)..... P7305	Lube (51055010009)..... P40042
Air Dryer (Coalescer) (81521086025)..... BA5379 +	Lube (2/95-on) (Mann HU947/2x)..... P7145	P. Fuel (51125030063)..... PF7935
Steering (81473016005)..... P106-HD	Fuel/Water Separator (Mann WDK724)..... BF1372	S. Fuel (51125030062)..... PF7939
Urea (81154036015)..... PE5270	Radial Seal O. Air (Mann C301353)..... RS3714	Radial Seal O. Air (81084050033)..... RS4971
TGS 33.360 w/D 2066 (Euro 6) Eng. (09/12-on)	Radial Seal I. Air (Mann C17170)..... RS4549	Radial Seal I. Air (81084050017)..... RS5361
Lube (51055010009)..... P40042	Cab Air (Mann CU40110)..... PA3980	Cab Air (w/o Charcoal) (81619100018)..... PA4955
P. Fuel (51125030063)..... PF7935	TGS 33.400 w/D2066 (Euro 4/5) Eng. (10/07-on)	Cab Air (w/Charcoal) (81619100019)..... PA5477
S. Fuel (51125030062)..... PF7939	Lube..... P7329	Air Dryer (81521086025)..... BA5379 +
Radial Seal O. Air (81084050033)..... RS4971	Fuel (51125030063)..... PF7935	Steering (81473016005)..... P106-HD
Radial Seal I. Air (81084050017)..... RS5361	Fuel/Water Separator..... BF7912	Urea (81154036015)..... PE5270
Cab Air (w/o Charcoal) (81619100018)..... PA4955	Radial Seal O. Air..... RS4971	TGS 33.440 w/D 2066, D 2676 (Euro 6) Eng. (09/12-on)
Cab Air (w/Charcoal) (81619100019)..... PA5477	Radial Seal I. Air..... RS5361	Lube (51055010009)..... P40042
Air Dryer (81521086025)..... BA5379 +	Cab Air (w/o Carbon) (81619100018)..... PA4955	P. Fuel (51125030063)..... PF7935
Steering (81473016005)..... P106-HD	Cab Air (w/Carbon) (81619100019)..... PA5477	S. Fuel (51125030062)..... PF7939
Urea (81154036015)..... PE5270	Air Dryer (Desiccant)..... BA5374 +	Radial Seal O. Air (81084050033)..... RS4971
TGX 33.360 w/D 2066 (Euro 6) Eng. (09/12-on)	Air Dryer (Coalescer) (81521086025)..... BA5379 +	Radial Seal I. Air (81084050017)..... RS5361
Lube (51055010009)..... P40042	Steering (81473016005)..... P106-HD	Cab Air (w/o Charcoal) (81619100018)..... PA4955
P. Fuel (51125030063)..... PF7935	Urea (81154036015)..... PE5270	Cab Air (w/Charcoal) (81619100019)..... PA5477
S. Fuel (51125030062)..... PF7939	TGX 33.400 w/D2066 (Euro 4/5) Eng. (10/07-on)	Air Dryer (81521086025)..... BA5379 +
Radial Seal O. Air (81084050033)..... RS4971	Lube..... P7329	Steering (81473016005)..... P106-HD
Radial Seal I. Air (81084050017)..... RS5361	P. Fuel (51125030063)..... PF7935	Urea (81154036015)..... PE5270
Cab Air (w/o Charcoal) (81619100018)..... PA4955	S. Fuel (51125030062)..... PF7939	TGX 33.440 w/D 2066, D 2676 (Euro 6) Eng. (09/12-on)
Cab Air (w/Charcoal) (81619100019)..... PA5477	Fuel/Water Separator..... BF7912	Lube (51055010009)..... P40042
Air Dryer (81521086025)..... BA5379 +	Radial Seal O. Air..... RS4971	P. Fuel (51125030063)..... PF7935
Steering (81473016005)..... P106-HD	Radial Seal I. Air..... RS5361	S. Fuel (51125030062)..... PF7939
Urea (81154036015)..... PE5270	Cab Air (w/o Carbon) (81619100018)..... PA4955	Radial Seal O. Air (81084050033)..... RS4971
35.364F, 35.364VF w/D2865LF35 Eng.	Cab Air (w/Carbon) (81619100019)..... PA5477	Radial Seal I. Air (81084050017)..... RS5361
Lube (81055040039)..... P294	Air Dryer (Desiccant)..... BA5374 +	Cab Air (w/o Charcoal) (81619100018)..... PA4955
Fuel Ele. (81125030021)..... PF950	Air Dryer (Coalescer) (81521086025)..... BA5379 +	Cab Air (w/Charcoal) (81619100019)..... PA5477
Fuel Spin-on (81125030075)..... BF587-D +	Steering (81473016005)..... P106-HD	Air Dryer (81521086025)..... BA5379 +
Air (81083040038)..... PA2776	Urea (81154036015)..... PE5270	Steering (81473016005)..... P106-HD
33.364 w/D2866 Eng.	TGS 33.400 w/D 2066 (Euro 6) Eng. (09/12-on)	Urea (81154036015)..... PE5270
Lube (51055040098)..... P7190	Lube (51055010009)..... P40042	35.343VF w/D2865LF21 Eng.
Fuel (51125030031)..... BF587	P. Fuel (51125030063)..... PF7935	Lube (1/94-1/95) (51055040094)..... P7015
Radial Seal O. Air (81083040083)..... RS3714	S. Fuel (51125030062)..... PF7939	Lube (2/95-8/96) (51055040096)..... P7145
Radial Seal I. Air (81083040084)..... RS4549	Radial Seal O. Air (81084050033)..... RS4971	Lube (9/96-on) (51055040098)..... P7190
Cab Air (8169100011)..... PA3980	Radial Seal I. Air (81084050017)..... RS5361	Fuel (51125030031)..... BF587
33.463DF w/D2876LF02 Eng.	Cab Air (w/o Charcoal) (81619100018)..... PA4955	Radial Seal O. Air (81083040083)..... RS3714
Lube (81055040039)..... P294	Cab Air (w/Charcoal) (81619100019)..... PA5477	Radial Seal I. Air (81083040084)..... RS4549
Fuel Ele. (81125030042)..... PF231	Air Dryer (81521086025)..... BA5379 +	Cab Air (8169100011)..... PA3980
Axial Seal Air (81083040038)..... PA2776	Steering (81473016005)..... P106-HD	33.414, 33.464 w/D2866, D2876 Eng.
Radial Seal O. Air (81083040094)..... RS3714	Urea (81154036015)..... PE5270	Lube (51055040098)..... P7190
Radial Seal I. Air (81083040084)..... RS4549	TGS 33.400 w/D 2066 (Euro 6) Eng. (09/12-on)	Fuel (51125030031)..... BF587
Cab Air (8169100011)..... PA3980	Lube (51055010009)..... P40042	Radial Seal O. Air (81083040083)..... RS3714
	P. Fuel (51125030063)..... PF7935	
	S. Fuel (51125030062)..... PF7939	
	Radial Seal O. Air (81084050033)..... RS4971	
	Radial Seal I. Air (81084050017)..... RS5361	
	Cab Air (w/o Charcoal) (81619100018)..... PA4955	
	Cab Air (w/Charcoal) (81619100019)..... PA5477	
	Air Dryer (81521086025)..... BA5379 +	
	Steering (81473016005)..... P106-HD	
	Urea (81154036015)..... PE5270	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)
33.414, 33.464 w/D2866, D2876 Engs. (Cont'd) <b>Radial Seal I. Air</b> (81083040084)..... <b>RS4549</b> <b>Cab Air</b> (8169100011)..... <b>PA3980</b>	TGX 33.440 w/D2066 (Euro 4/5) Eng. (10/07-on) (Cont'd) <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (Desiccant)..... <b>BA5374 +</b> <b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>	TGX 33.480 w/D2676 (Euro 4/5) Eng. (10/07-on) (Cont'd) <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (Desiccant)..... <b>BA5374 +</b> <b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>
F2000 Evo 33.414VFL w/D2866LF(31) Eng. (05/96-on) <b>Lube</b> (51055040098)..... <b>P7190</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>Radial Seal O. Air</b> ..... <b>RS3714</b> <b>Radial Seal I. Air</b> (81083040084)..... <b>RS4549</b> <b>Cab Air</b> ..... <b>PA3980</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> ..... <b>BA5379 +</b> <b>Trans.</b> (ZF Gearbox)..... <b>PT8385</b>	33.462 w/D2840 Eng. <b>Lube</b> (81055040041)..... <b>P294</b> <b>P. Fuel Ele.</b> (81125030011)..... <b>F950-F</b> <b>S. Fuel Ele.</b> (81125030042)..... <b>PF231</b> <b>Air</b> (81082050005)..... <b>PA2475</b>	TGS 33.480 w/D 2676 (Euro 6) Eng. (09/12-on) <b>Lube</b> (51055010009)..... <b>P40042</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>Radial Seal O. Air</b> (81084050033)..... <b>RS4971</b> <b>Radial Seal I. Air</b> (81084050017)..... <b>RS5361</b> <b>Cab Air</b> (w/o Charcoal) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Charcoal) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>
33.422 w/D2866 Eng. <b>Lube</b> (81055040039)..... <b>P294</b> <b>Fuel Ele.</b> (81125030021)..... <b>PF950</b> <b>Axial Seal Air</b> (81083040038)..... <b>PA2776</b> <b>Radial Seal O. Air</b> (81083040094)..... <b>RS3714</b> <b>Radial Seal I. Air</b> (81083040084)..... <b>RS4549</b>	33.463DF w/D2876LF02 Eng. <b>Lube</b> (1/94-1/95) (51055040094)..... <b>P7015</b> <b>Lube</b> (2/95-8/96) (51055040096)..... <b>P7145</b> <b>Lube</b> (9/96-on) (51055040098)..... <b>P7190</b> <b>Fuel</b> (51125030031)..... <b>BF587</b> <b>Radial Seal O. Air</b> (81083040083)..... <b>RS3714</b> <b>Radial Seal I. Air</b> (81083040084)..... <b>RS4549</b> <b>Cab Air</b> (8169100011)..... <b>PA3980</b>	TGX 33.480 w/D 2676 (Euro 6) Eng. (09/12-on) <b>Lube</b> (51055010009)..... <b>P40042</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>Radial Seal O. Air</b> (81084050033)..... <b>RS4971</b> <b>Radial Seal I. Air</b> (81084050017)..... <b>RS5361</b> <b>Cab Air</b> (w/o Charcoal) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Charcoal) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>
35.364F, 35.364VF w/D2865LF35 Eng. (1/94-1/95) (Mann HU947/1n)..... <b>P7305</b> <b>Lube</b> (2/95-on) (Mann HU947/2x)..... <b>P7145</b> <b>Fuel/Water Separator</b> (Mann WDK724)..... <b>BF1372</b> <b>Radial Seal O. Air</b> (Mann C301353)..... <b>RS3714</b> <b>Radial Seal I. Air</b> (Mann C17170)..... <b>RS4549</b> <b>Cab Air</b> (Mann CU40110)..... <b>PA3980</b>	F2000 Evo 33.464DFRT(06) w/D2876LF Eng. (05/96-on) <b>Lube</b> (51055040098)..... <b>P7190</b> <b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b> <b>Radial Seal O. Air</b> ..... <b>RS3714</b> <b>Radial Seal I. Air</b> (81083040084)..... <b>RS4549</b> <b>Cab Air</b> ..... <b>PA3980</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> ..... <b>BA5379 +</b> <b>Trans.</b> (ZF Gearbox)..... <b>PT8385</b>	TGS 33.480 w/D2676 (Euro 4/5) Eng. (10/07-on) <b>Lube</b> ..... <b>P7329</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>Fuel/Water Separator</b> ..... <b>BF7912</b> <b>Radial Seal O. Air</b> ..... <b>RS4971</b> <b>Radial Seal I. Air</b> ..... <b>RS5361</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (Desiccant)..... <b>BA5374 +</b> <b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>
TGS 33.440 w/D2066 (Euro 4/5) Eng. (10/07-on) <b>Lube</b> ..... <b>P7329</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>Fuel/Water Separator</b> ..... <b>BF7912</b> <b>Radial Seal O. Air</b> ..... <b>RS4971</b> <b>Radial Seal I. Air</b> ..... <b>RS5361</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (Desiccant)..... <b>BA5374 +</b> <b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>	TGS 33.480 w/D2676 (Euro 4/5) Eng. (10/07-on) <b>Lube</b> ..... <b>P7329</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>Fuel/Water Separator</b> ..... <b>BF7912</b> <b>Radial Seal O. Air</b> ..... <b>RS4971</b> <b>Radial Seal I. Air</b> ..... <b>RS5361</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (Desiccant)..... <b>BA5374 +</b> <b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b>	TGS 33.540 w/D2676 (Euro 4/5) Eng. (10/07-on) <b>Lube</b> ..... <b>P7329</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>Fuel/Water Separator</b> ..... <b>BF7912</b> <b>Radial Seal O. Air</b> ..... <b>RS4971</b> <b>Radial Seal I. Air</b> ..... <b>RS5361</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (Desiccant)..... <b>BA5374 +</b> <b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b>
TGX 33.440 w/D2066 (Euro 4/5) Eng. (10/07-on) <b>Lube</b> ..... <b>P7329</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>Fuel/Water Separator</b> ..... <b>BF7912</b> <b>Radial Seal O. Air</b> ..... <b>RS4971</b> <b>Radial Seal I. Air</b> ..... <b>RS5361</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b>	TGX 33.480 w/D2676 (Euro 4/5) Eng. (10/07-on) <b>Lube</b> ..... <b>P7329</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>Fuel/Water Separator</b> ..... <b>BF7912</b> <b>Radial Seal O. Air</b> ..... <b>RS4971</b> <b>Radial Seal I. Air</b> ..... <b>RS5361</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)
TGS 33.540 w/D2676 (Euro 4/5) Eng. (10/07-on) (Cont'd)	TGX 33.680 V8 w/D2868 (Euro 5) Eng. (10/07-on)	F2000 35.343 w/D2865 Eng. (05/96-on)
Steering (81473016005)..... P106-HD	Lube..... P7329	Lube..... P7190
Urea (81154036015)..... PE5270	P. Fuel (51125030063)..... PF7935	Fuel/Water Separator (51125030040)..... BF1372
TGX 33.540 w/D2676 (Euro 4/5) Eng. (10/07-on)	S. Fuel (51125030062)..... PF7939	Radial Seal O. Air..... RS3714
Lube..... P7329	Fuel/Water Separator..... BF7912	Radial Seal I. Air..... RS4549
P. Fuel (51125030063)..... PF7935	Radial Seal O. Air..... RS4971	Cab Air..... PA3980
S. Fuel (51125030062)..... PF7939	Cab Air (w/o Carbon) (81619100018)..... PA4955	Air Dryer (Mann TB1374X)..... BA5374 +
Fuel/Water Separator..... BF7912	Cab Air (w/Carbon) (81619100019)..... PA5477	Air Dryer..... BA5379 +
Radial Seal O. Air..... RS4971	Air Dryer (Desiccant)..... BA5374 +	Trans. (ZF Gearbox)..... PT8385
Radial Seal I. Air..... RS5361	Air Dryer (Coalescer) (81521086025)..... BA5379 +	35.343VF w/D2865LF21 Eng.
Cab Air (w/o Carbon) (81619100018)..... PA4955	Steering (81473016005)..... P106-HD	148.4 mm Lube (51055040098)..... P7190
Cab Air (w/Carbon) (81619100019)..... PA5477	Urea (81154036015)..... PE5270	199.2 mm Lube (51055040094)..... P7015
Air Dryer (Desiccant)..... BA5374 +	TGS 35.320 w/D2066 (Euro 4/5) Eng. (10/07-on)	213.5 mm Lube (51055040096)..... P7145
Air Dryer (Coalescer) (81521086025)..... BA5379 +	Lube..... P7329	Fuel (51125030031)..... BF587
Steering (81473016005)..... P106-HD	Fuel (51125030063)..... PF7935	Radial Seal O. Air (81083040083)..... RS3714
Urea (81154036015)..... PE5270	Fuel/Water Separator..... BF7912	Radial Seal I. Air (81083040084)..... RS4549
TGS 33.540 w/D 2676 (Euro 6) Eng. (09/12-on)	Radial Seal O. Air..... RS4971	Cab Air (8169100011)..... PA3980
Lube (51055010009)..... P40042	Radial Seal I. Air..... RS5361	TGS 35.360 w/D2066 (Euro 4/5) Eng. (10/07-on)
P. Fuel (51125030063)..... PF7935	Cab Air (w/o Carbon) (81619100018)..... PA4955	Lube..... P7329
S. Fuel (51125030062)..... PF7939	Cab Air (w/Carbon) (81619100019)..... PA5477	Fuel (51125030063)..... PF7935
Radial Seal O. Air (81084050033)..... RS4971	Air Dryer (Desiccant)..... BA5374 +	Fuel/Water Separator..... BF7912
Radial Seal I. Air (81084050017)..... RS5361	Air Dryer (Coalescer) (81521086025)..... BA5379 +	Radial Seal O. Air..... RS4971
Cab Air (w/o Charcoal) (81619100018)..... PA4955	Steering (81473016005)..... P106-HD	Radial Seal I. Air..... RS5361
Cab Air (w/Charcoal) (81619100019)..... PA5477	Urea (81154036015)..... PE5270	Cab Air (w/o Carbon) (81619100018)..... PA4955
Air Dryer (81521086025)..... BA5379 +	TGS 35.320 w/D 2066 (Euro 6) Eng. (09/12-on)	Cab Air (w/Carbon) (81619100019)..... PA5477
Steering (81473016005)..... P106-HD	Lube (51055010009)..... P40042	Air Dryer (Desiccant)..... BA5374 +
Urea (81154036015)..... PE5270	P. Fuel (51125030063)..... PF7935	Air Dryer (Coalescer) (81521086025)..... BA5379 +
TGX 33.540 w/D 2676 (Euro 6) Eng. (09/12-on)	S. Fuel (51125030062)..... PF7939	Steering (81473016005)..... P106-HD
Lube (51055010009)..... P40042	Radial Seal O. Air (81084050033)..... RS4971	Urea (81154036015)..... PE5270
P. Fuel (51125030063)..... PF7935	Radial Seal I. Air (81084050017)..... RS5361	TGX 35.360 w/D2066 (Euro 4/5) Eng. (03/08-on)
S. Fuel (51125030062)..... PF7939	Cab Air (w/o Charcoal) (81619100018)..... PA4955	Lube..... P7329
Radial Seal O. Air (81084050033)..... RS4971	Cab Air (w/Charcoal) (81619100019)..... PA5477	P. Fuel (51125030063)..... PF7935
Radial Seal I. Air (81084050017)..... RS5361	Air Dryer (81521086025)..... BA5379 +	S. Fuel (51125030062)..... PF7939
Cab Air (w/o Charcoal) (81619100018)..... PA4955	Steering (81473016005)..... P106-HD	Fuel/Water Separator..... BF7912
Cab Air (w/Charcoal) (81619100019)..... PA5477	Urea (81154036015)..... PE5270	Radial Seal O. Air..... RS4971
Air Dryer (81521086025)..... BA5379 +	35.342 w/D2865 Eng.	Radial Seal I. Air..... RS5361
Steering (81473016005)..... P106-HD	Lube (5/94-1/95) (Mann HU947/1n)..... P7305	Cab Air (w/o Carbon) (81619100018)..... PA4955
Urea (81154036015)..... PE5270	Lube (2/95-on) (Mann HU947/2x)..... P7145	Cab Air (w/Carbon) (81619100019)..... PA5477
33.603, 33.604 w/D2840 Eng.	Fuel/Water Separator (Mann WDK724)..... BF1372	Air Dryer (Coalescer) (81521086025)..... BA5379 +
Lube (Mann HU947/2x)..... P7145	Radial Seal O. Air (Mann C301353)..... RS3714	Air Dryer (Desiccant) (Mann TB1374x)..... BA5374 +
Fuel/Water Separator (Mann WDK724)..... BF1372	Radial Seal I. Air (Mann C17170)..... RS4549	Steering (81473016005)..... P106-HD
Radial Seal O. Air (81083040083)..... RS3714	Cab Air (Mann CU40110)..... PA3980	Urea (81154036015)..... PE5270
Opt. Radial Seal I. Air (81083040084)..... RS4549	Trans. (Mann H710/1n)..... PT8385	TGS 35.360 w/D 2066 (Euro 6) Eng. (09/12-on)
Cab Air (Mann CU40110)..... PA3980		Lube (51055010009)..... P40042
Trans. (Mann H710/1n)..... PT8385		P. Fuel (51125030063)..... PF7935
		S. Fuel (51125030062)..... PF7939
		Radial Seal O. Air (81084050033)..... RS4971
		Radial Seal I. Air (81084050017)..... RS5361

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)
TGX 35.360 w/D 2066 (Euro 6) Eng. (09/12-on) (Cont'd)	TGX 35.400 w/D2066 (Euro 4/5) Eng. (03/08-on)	35.403VF w/D2866 Eng.
Cab Air (w/o Charcoal) (81619100018)..... PA4955	Lube..... P7329	Lube (8/95-8/96) (Mann HU947/2x)..... P7145
Cab Air (w/Charcoal) (81619100019)..... PA5477	P. Fuel (51125030063)..... PF7935	Lube (9/96-on) (Mann HU1381x)..... P7190
Air Dryer (81521086025)..... BA5379 +	S. Fuel (51125030062)..... PF7939	Fuel/Water Separator (Mann WDK724)..... BF1372
Steering (81473016005)..... P106-HD	Fuel/Water Separator..... BF7912	Radial Seal O. Air (Mann C301353)..... RS3714
Urea (81154036015)..... PE5270	Radial Seal O. Air..... RS4971	Radial Seal I. Air (Mann C17170)..... RS4549
TGX 35.360 w/D 2066 (Euro 6) Eng. (09/12-on)	Cab Air (w/o Carbon) (81619100018)..... PA4955	Cab Air (Mann CU40110)..... PA3980
Lube (51055010009)..... P40042	Cab Air (w/Carbon) (81619100019)..... PA5477	F2000 Evo 35.414 VFRC w/D2866LF(28) Eng. (05/96-on)
P. Fuel (51125030063)..... PF7935	Air Dryer (Coalescer) (81521086025)..... BA5379 +	Lube (51055040098)..... P7190
S. Fuel (51125030062)..... PF7939	Air Dryer (Desiccant) (Mann TB1374x)..... BA5374 +	Fuel/Water Separator (51125030040)..... BF1372
Radial Seal O. Air (81084050033)..... RS4971	Steering (81473016005)..... P106-HD	Radial Seal O. Air..... RS3714
Radial Seal I. Air (81084050017)..... RS5361	Urea (81154036015)..... PE5270	Radial Seal I. Air (81083040084)..... RS4549
Cab Air (w/o Charcoal) (81619100018)..... PA4955	TGS 35.400 w/D 2066 (Euro 6) Eng. (09/12-on)	Cab Air..... PA3980
Cab Air (w/Charcoal) (81619100019)..... PA5477	Lube (51055010009)..... P40042	Air Dryer (Mann TB1374X)..... BA5374 +
Air Dryer (81521086025)..... BA5379 +	P. Fuel (51125030063)..... PF7935	Air Dryer..... BA5379 +
Steering (81473016005)..... P106-HD	S. Fuel (51125030062)..... PF7939	Trans. (ZF Gearbox)..... PT8385
Urea (81154036015)..... PE5270	Radial Seal O. Air (81084050033)..... RS4971	35.414, 35.464 w/D2866, D2876 Engs.
F2000 Evo 35.364 VFRC w/D2866LF(24) Eng. (05/96-on)	Radial Seal I. Air (81084050017)..... RS5361	Lube (Mann HU1381x)..... P7190
Lube (51055040098)..... P7190	Cab Air (w/o Charcoal) (81619100018)..... PA4955	Fuel/Water Separator (Mann WDK724)..... BF1372
Fuel/Water Separator (51125030040)..... BF1372	Cab Air (w/Charcoal) (81619100019)..... PA5477	Radial Seal O. Air (Mann C301353)..... RS3714
Radial Seal O. Air..... RS3714	Air Dryer (81521086025)..... BA5379 +	Radial Seal I. Air (Mann C17170)..... RS4549
Radial Seal I. Air (81083040084)..... RS4549	Steering (81473016005)..... P106-HD	Cab Air (Mann CU40110)..... PA3980
Cab Air..... PA3980	Urea (81154036015)..... PE5270	TGX 35.440 w/D2066 (Euro 4/5) Eng. (10/07-on)
Air Dryer (Mann TB1374X)..... BA5374 +	TGX 35.400 w/D 2066 (Euro 6) Eng. (09/12-on)	Lube..... P7329
Air Dryer..... BA5379 +	Lube (51055010009)..... P40042	Fuel (51125030063)..... PF7935
Trans. (ZF Gearbox)..... PT8385	P. Fuel (51125030063)..... PF7935	Fuel/Water Separator..... BF7912
35.364F, 35.364VF w/D2865LF35 Eng.	S. Fuel (51125030062)..... PF7939	Radial Seal O. Air..... RS4971
148.4 mm Lube (51055040098)..... P7190	Radial Seal O. Air (81084050033)..... RS4971	Radial Seal I. Air..... RS5361
199.2 mm Lube (51055040094)..... P7015	Radial Seal I. Air (81084050017)..... RS5361	Cab Air (w/o Carbon) (81619100018)..... PA4955
213.5 mm Lube (51055040096)..... P7145	Cab Air (w/o Charcoal) (81619100018)..... PA4955	Cab Air (w/Carbon) (81619100019)..... PA5477
Fuel (51125030031)..... BF587	Cab Air (w/Charcoal) (81619100019)..... PA5477	Air Dryer (Desiccant)..... BA5374 +
Radial Seal O. Air (81083040083)..... RS3714	Air Dryer (81521086025)..... BA5379 +	Air Dryer (Coalescer) (81521086025)..... BA5379 +
Radial Seal I. Air (81083040084)..... RS4549	Steering (81473016005)..... P106-HD	Steering (81473016005)..... P106-HD
Cab Air (8169100011)..... PA3980	Urea (81154036015)..... PE5270	Urea (81154036015)..... PE5270
TGS 35.400 w/D2066 (Euro 4/5) Eng. (10/07-on)	35.402 w/D2866 Eng.	TGX 35.440 w/D2066 (Euro 4/5) Eng. (03/08-on)
Lube..... P7329	Lube (5/94-1/95) (Mann HU947/1n)..... P7305	Lube..... P7329
Fuel (51125030063)..... PF7935	Lube (2/95-on) (Mann HU947/2x)..... P7145	P. Fuel (51125030063)..... PF7935
Fuel/Water Separator..... BF7912	Fuel/Water Separator (Mann WDK724)..... BF1372	S. Fuel (51125030062)..... PF7939
Radial Seal O. Air..... RS4971	Radial Seal O. Air (Mann C301353)..... RS3714	Fuel/Water Separator..... BF7912
Radial Seal I. Air..... RS5361	Radial Seal I. Air (Mann C17170)..... RS4549	Radial Seal O. Air..... RS4971
Cab Air (w/o Carbon) (81619100018)..... PA4955	Cab Air (Mann CU40110)..... PA3980	Radial Seal I. Air..... RS5361
Cab Air (w/Carbon) (81619100019)..... PA5477		Cab Air (w/o Carbon) (81619100018)..... PA4955
Air Dryer (Desiccant)..... BA5374 +		Cab Air (w/Carbon) (81619100019)..... PA5477
Air Dryer (Coalescer) (81521086025)..... BA5379 +		
Steering (81473016005)..... P106-HD		
Urea (81154036015)..... PE5270		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)
<b>TGX 35.440 w/D2066 (Euro 4/5) Eng.</b> (03/08-on) (Cont'd) <b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b> <b>Air Dryer</b> (Desiccant) (Mann TB1374x)..... <b>BA5374 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>	<b>TGS 35.480 w/D2676 (Euro 4/5) Eng.</b> (10/07-on) (Cont'd) <b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>	<b>TGS 35.540 w/D2676 (Euro 4/5) Eng.</b> (10/07-on) (Cont'd) <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (Desiccant)..... <b>BA5374 +</b> <b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>
<b>TGS 35.440 w/D 2066, D 2676 (Euro 6) Eng.</b> (09/12-on) <b>Lube</b> (51055010009)..... <b>P40042</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>Radial Seal O. Air</b> (81084050033)..... <b>RS4971</b> <b>Radial Seal I. Air</b> (81084050017). <b>RS5361</b> <b>Cab Air</b> (w/o Charcoal) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Charcoal) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>	<b>TGX 35.480 w/D2676 (Euro 4/5) Eng.</b> (03/08-on) <b>Lube</b> ..... <b>P7329</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>Fuel/Water Separator</b> ..... <b>BF7912</b> <b>Radial Seal O. Air</b> ..... <b>RS4971</b> <b>Radial Seal I. Air</b> ..... <b>RS5361</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b> <b>Air Dryer</b> (Desiccant) (Mann TB1374x)..... <b>BA5374 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>	<b>TGX 35.540 w/D2676 (Euro 4/5) Eng.</b> (03/08-on) <b>Lube</b> ..... <b>P7329</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>Fuel/Water Separator</b> ..... <b>BF7912</b> <b>Radial Seal O. Air</b> ..... <b>RS4971</b> <b>Radial Seal I. Air</b> ..... <b>RS5361</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b> <b>Air Dryer</b> (Desiccant) (Mann TB1374x)..... <b>BA5374 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>
<b>TGX 35.440 w/D 2066, D 2676 (Euro 6) Eng.</b> (09/12-on) <b>Lube</b> (51055010009)..... <b>P40042</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>Radial Seal O. Air</b> (81084050033)..... <b>RS4971</b> <b>Radial Seal I. Air</b> (81084050017). <b>RS5361</b> <b>Cab Air</b> (w/o Charcoal) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Charcoal) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>	<b>TGS 35.480 w/D 2676 (Euro 6) Eng.</b> (09/12-on) <b>Lube</b> (51055010009)..... <b>P40042</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>Radial Seal O. Air</b> (81084050033)..... <b>RS4971</b> <b>Radial Seal I. Air</b> (81084050017). <b>RS5361</b> <b>Cab Air</b> (w/o Charcoal) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Charcoal) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>	<b>TGS 35.540 w/D 2676 (Euro 6) Eng.</b> (09/12-on) <b>Lube</b> (51055010009)..... <b>P40042</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>Radial Seal O. Air</b> (81084050033)..... <b>RS4971</b> <b>Radial Seal I. Air</b> (81084050017). <b>RS5361</b> <b>Cab Air</b> (w/o Charcoal) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Charcoal) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>
<b>35.463VF w/D2876LF02 Eng.</b> <b>148.4 mm Lube</b> (51055040098)... <b>P7190</b> <b>199.2 mm Lube</b> (51055040094)... <b>P7015</b> <b>213.5 mm Lube</b> (51055040096)... <b>P7145</b> <b>Fuel</b> (51125030031)..... <b>BF587</b> <b>Radial Seal O. Air</b> (81083040083)..... <b>RS3714</b> <b>Radial Seal I. Air</b> (81083040084). <b>RS4549</b> <b>Cab Air</b> (8169100011)..... <b>PA3980</b>	<b>TGX 35.480 w/D2676 (Euro 6) Eng.</b> (09/12-on) <b>Lube</b> ..... <b>P40042</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>Radial Seal O. Air</b> (81084050033)..... <b>RS4971</b> <b>Radial Seal I. Air</b> (81084050017). <b>RS5361</b> <b>Cab Air</b> (w/o Charcoal) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Charcoal) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>	<b>TGS 35.540 w/D2676 (Euro 6) Eng.</b> (09/12-on) <b>Lube</b> (51055010009)..... <b>P40042</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>Radial Seal O. Air</b> (81084050033)..... <b>RS4971</b> <b>Radial Seal I. Air</b> (81084050017). <b>RS5361</b> <b>Cab Air</b> (w/o Charcoal) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Charcoal) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>
<b>TGS 35.480 w/D2676 (Euro 4/5) Eng.</b> (10/07-on) <b>Lube</b> ..... <b>P7329</b> <b>Fuel</b> (51125030063)..... <b>PF7935</b> <b>Fuel/Water Separator</b> ..... <b>BF7912</b> <b>Radial Seal O. Air</b> ..... <b>RS4971</b> <b>Radial Seal I. Air</b> ..... <b>RS5361</b> <b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (Desiccant)..... <b>BA5374 +</b>	<b>TGS 35.480 w/D2676 (Euro 6) Eng.</b> (09/12-on) <b>Lube</b> ..... <b>P40042</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>Radial Seal O. Air</b> (81084050033)..... <b>RS4971</b> <b>Radial Seal I. Air</b> (81084050017). <b>RS5361</b> <b>Cab Air</b> (w/o Charcoal) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Charcoal) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>	<b>TGX 35.540 w/D2676 (Euro 4/5) Eng.</b> (10/07-on) <b>Lube</b> ..... <b>P7329</b> <b>Fuel</b> (51125030063)..... <b>PF7935</b> <b>Fuel/Water Separator</b> ..... <b>BF7912</b> <b>Radial Seal O. Air</b> ..... <b>RS4971</b> <b>Radial Seal I. Air</b> ..... <b>RS5361</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)
36.604 w/D2840 Eng. Lube (Mann HU947/2x)..... P7145 Fuel/Water Separator (Mann WDK724)..... BF1372 Radial Seal O. Air (81083040083)..... RS3714 Radial Seal I. Air (81083040084)..... RS4549 Cab Air (Mann CU40110)..... PA3980 Trans. (Mann H710/1n)..... PT8385	TGS 37.440 w/D2066 (Euro 4/5) Eng. (10/07-on) (Cont'd) Radial Seal O. Air..... RS4971 Radial Seal I. Air..... RS5361 Cab Air (w/o Carbon) (81619100018)..... PA4955 Cab Air (w/Carbon) (81619100019)..... PA5477 Air Dryer (Desiccant)..... BA5374 + Air Dryer (Coalescer) (81521086025)..... BA5379 + Steering (81473016005)..... P106-HD Urea (81154036015)..... PE5270	TGS 39.320 w/D2066 (Euro 4/5) Eng. (10/07-on) (Cont'd) Radial Seal I. Air..... RS5361 Cab Air (w/o Carbon) (81619100018)..... PA4955 Cab Air (w/Carbon) (81619100019)..... PA5477 Air Dryer (Desiccant)..... BA5374 + Air Dryer (Coalescer) (81521086025)..... BA5379 + Steering (81473016005)..... P106-HD Urea (81154036015)..... PE5270
TGS 37.320 w/D2066 (Euro 4/5) Eng. (10/07-on) Lube..... P7329 Fuel (51125030063)..... PF7935 Fuel/Water Separator..... BF7912 Radial Seal O. Air..... RS4971 Radial Seal I. Air..... RS5361 Cab Air (w/o Carbon) (81619100018)..... PA4955 Cab Air (w/Carbon) (81619100019)..... PA5477 Air Dryer (Desiccant)..... BA5374 + Air Dryer (Coalescer) (81521086025)..... BA5379 + Steering (81473016005)..... P106-HD Urea (81154036015)..... PE5270	TGS 37.480 w/D2676 (Euro 4/5) Eng. (10/07-on) Lube..... P7329 Fuel (51125030063)..... PF7935 Fuel/Water Separator..... BF7912 Radial Seal O. Air..... RS4971 Radial Seal I. Air..... RS5361 Cab Air (w/o Carbon) (81619100018)..... PA4955 Cab Air (w/Carbon) (81619100019)..... PA5477 Air Dryer (Desiccant)..... BA5374 + Air Dryer (Coalescer) (81521086025)..... BA5379 + Steering (81473016005)..... P106-HD Urea (81154036015)..... PE5270	TGS 39.320 w/D 2066 (Euro 6) Eng. (09/12-on) Lube (51055010009)..... P40042 P. Fuel (51125030063)..... PF7935 S. Fuel (51125030062)..... PF7939 Radial Seal O. Air (81084050033)..... RS4971 Radial Seal I. Air (81084050017)..... RS5361 Cab Air (w/o Charcoal) (81619100018)..... PA4955 Cab Air (w/Charcoal) (81619100019)..... PA5477 Air Dryer (81521086025)..... BA5379 + Steering (81473016005)..... P106-HD Urea (81154036015)..... PE5270
TGS 37.360 w/D2066 (Euro 4/5) Eng. (10/07-on) Lube..... P7329 Fuel (51125030063)..... PF7935 Fuel/Water Separator..... BF7912 Radial Seal O. Air..... RS4971 Radial Seal I. Air..... RS5361 Cab Air (w/o Carbon) (81619100018)..... PA4955 Cab Air (w/Carbon) (81619100019)..... PA5477 Air Dryer (Desiccant)..... BA5374 + Air Dryer (Coalescer) (81521086025)..... BA5379 + Steering (81473016005)..... P106-HD Urea (81154036015)..... PE5270	38.320 w/D2530 Eng. 115.1 mm P. Fuel (81125030050)..... F953-F 142.9 mm P. Fuel (81125030011)..... F950-F 108.7 mm S. Fuel (81125030041)..... PF834 148.4 mm S. Fuel (81125030042)..... PF231 O. Air (81082050005)..... PA2475 I. Air..... PA2814 Hyd. (81055040007)..... PT691	TGS 39.360 w/D2066 (Euro 4/5) Eng. (10/07-on) Lube..... P7329 Fuel (51125030063)..... PF7935 Fuel/Water Separator..... BF7912 Radial Seal O. Air..... RS4971 Radial Seal I. Air..... RS5361 Cab Air (w/o Carbon) (81619100018)..... PA4955 Cab Air (w/Carbon) (81619100019)..... PA5477 Air Dryer (Desiccant)..... BA5374 + Air Dryer (Coalescer) (81521086025)..... BA5379 + Steering (81473016005)..... P106-HD Urea (81154036015)..... PE5270
TGS 37.400 w/D2066 (Euro 4/5) Eng. (10/07-on) Lube..... P7329 Fuel (51125030063)..... PF7935 Fuel/Water Separator..... BF7912 Radial Seal O. Air..... RS4971 Radial Seal I. Air..... RS5361 Cab Air (w/o Carbon) (81619100018)..... PA4955 Cab Air (w/Carbon) (81619100019)..... PA5477 Air Dryer (Desiccant)..... BA5374 + Air Dryer (Coalescer) (81521086025)..... BA5379 + Steering (81473016005)..... P106-HD Urea (81154036015)..... PE5270	38.320 w/D2538 Eng. Lube (81055040041)..... P294 115.1 mm P. Fuel (81125030050)..... F953-F 142.9 mm P. Fuel (81125030011)..... F950-F 108.7 mm S. Fuel (81125030041)..... PF834 148.4 mm S. Fuel (81125030042)..... PF231 O. Air (81082050005)..... PA2475 I. Air..... PA2814 Hyd. (81055040007)..... PT691	TGS 39.360 w/D 2066 (Euro 6) Eng. (09/12-on) Lube (51055010009)..... P40042 P. Fuel (51125030063)..... PF7935 S. Fuel (51125030062)..... PF7939 Radial Seal O. Air (81084050033)..... RS4971 Radial Seal I. Air (81084050017)..... RS5361 Cab Air (w/o Charcoal) (81619100018)..... PA4955 Cab Air (w/Charcoal) (81619100019)..... PA5477 Air Dryer (81521086025)..... BA5379 + Steering (81473016005)..... P106-HD Urea (81154036015)..... PE5270
TGS 37.440 w/D2066 (Euro 4/5) Eng. (10/07-on) Lube..... P7329 Fuel (51125030063)..... PF7935 Fuel/Water Separator..... BF7912	TGS 39.320 w/D2066 (Euro 4/5) Eng. (10/07-on) Lube..... P7329 Fuel (51125030063)..... PF7935 Fuel/Water Separator..... BF7912 Radial Seal O. Air..... RS4971	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)
TGS 39.400 w/D2066 (Euro 4/5) Eng. (10/07-on)	TGS 39.440 w/D 2066, D 2676 (Euro 6) Eng. (09/12-on) (Cont'd)	TGS 39.540 w/D 2676 (Euro 6) Eng. (09/12-on) (Cont'd)
Lube..... P7329	Steering (81473016005)..... P106-HD	Cab Air (w/o Charcoal) (81619100018)..... PA4955
P. Fuel (51125030063)..... PF7935	Urea (81154036015)..... PE5270	Cab Air (w/Charcoal) (81619100019)..... PA5477
S. Fuel (51125030062)..... PF7939	TGS 39.480 w/D2676 (Euro 4/5) Eng. (10/07-on)	Air Dryer (81521086025)..... BA5379 +
Fuel/Water Separator..... BF7912	Lube..... P7329	Air Dryer (Coalescer) (81521086025)..... BA5379 +
Radial Seal O. Air..... RS4971	P. Fuel (51125030063)..... PF7935	Steering (81473016005)..... P106-HD
Radial Seal I. Air..... RS5361	S. Fuel (51125030062)..... PF7939	Urea (81154036015)..... PE5270
Cab Air (w/o Carbon) (81619100018)..... PA4955	Fuel/Water Separator..... BF7912	40.242 w/D2866 Eng.
Cab Air (w/Carbon) (81619100019)..... PA5477	Radial Seal O. Air..... RS4971	Lube (81055040041)..... P294
Air Dryer (Desiccant)..... BA5374 +	Radial Seal I. Air..... RS5361	P. Fuel Ele. (81125030011)..... F950-F
Air Dryer (Coalescer) (81521086025)..... BA5379 +	Cab Air (w/o Carbon) (81619100018)..... PA4955	S. Fuel Ele. (81125030042)..... PF231
Steering (81473016005)..... P106-HD	Cab Air (w/Carbon) (81619100019)..... PA5477	Fuel Spin-on (81125030075)..... BF587-D +
Urea (81154036015)..... PE5270	Air Dryer (Desiccant)..... BA5374 +	Air (81083040038)..... PA2776
TGS 39.400 w/D 2066 (Euro 6) Eng. (09/12-on)	Air Dryer (Coalescer) (81521086025)..... BA5379 +	40.262, 40.272 w/D2865 Eng.
Lube (51055010009)..... P40042	Steering (81473016005)..... P106-HD	188.1 mm Lube (51055040068)..... P242
P. Fuel (51125030063)..... PF7935	Urea (81154036015)..... PE5270	264.3 mm Lube (81055040041)..... P294
S. Fuel (51125030062)..... PF7939	TGS 39.480 w/D 2676 (Euro 6) Eng. (09/12-on)	Fuel Ele. (81125030042)..... PF231
Radial Seal O. Air (81084050033)..... RS4971	Lube (51055010009)..... P40042	Fuel Spin-on (81125030075)..... BF587-D +
Radial Seal I. Air (81084050017)..... RS5361	P. Fuel (51125030063)..... PF7935	Air (81083040038)..... PA2776
Cab Air (w/o Charcoal) (81619100018)..... PA4955	S. Fuel (51125030062)..... PF7939	40.280 w/D2566MT Eng.
Cab Air (w/Charcoal) (81619100019)..... PA5477	Radial Seal O. Air (81084050033)..... RS4971	Lube (81055040041)..... P294
Air Dryer (81521086025)..... BA5379 +	Radial Seal I. Air (81084050017)..... RS5361	P. Fuel Ele. (81125030011)..... F950-F
Steering (81473016005)..... P106-HD	Cab Air (w/o Charcoal) (81619100018)..... PA4955	S. Fuel Ele. (81125030042)..... PF231
Urea (81154036015)..... PE5270	Cab Air (w/Charcoal) (81619100019)..... PA5477	496.9 mm O. Air (81082050005)..... PA2475
TGS 39.440 w/D2066 (Euro 4/5) Eng. (10/07-on)	Air Dryer (81521086025)..... BA5379 +	473.1 mm I. Air..... PA2814
Lube..... P7329	Steering (81473016005)..... P106-HD	473.9 mm O. Air..... PA2776
P. Fuel (51125030063)..... PF7935	Urea (81154036015)..... PE5270	Hyd. (81055040007)..... PT691
S. Fuel (51125030062)..... PF7939	TGS 39.540 w/D2676 (Euro 4/5) Eng. (10/07-on)	CLA 40.280 w/D0836 EURO3 Eng. (10/06-on)
Fuel/Water Separator..... BF7912	Lube..... P7329	Lube..... B7116
Radial Seal O. Air..... RS4971	P. Fuel (51125030063)..... PF7935	Fuel/Water Separator (51125030040)..... BF1372
Radial Seal I. Air..... RS5361	S. Fuel (51125030062)..... PF7939	O. Air..... PA3760
Cab Air (w/o Carbon) (81619100018)..... PA4955	Fuel/Water Separator..... BF7912	Steering (81473016005)..... P106-HD
Cab Air (w/Carbon) (81619100019)..... PA5477	Radial Seal O. Air..... RS4971	40.292 w/D2866 Eng.
Air Dryer (Desiccant)..... BA5374 +	Radial Seal I. Air..... RS5361	Lube (81055040041)..... P294
Air Dryer (Coalescer) (81521086025)..... BA5379 +	Cab Air (w/o Carbon) (81619100018)..... PA4955	P. Fuel Ele. (81125030011)..... F950-F
Steering (81473016005)..... P106-HD	Cab Air (w/Carbon) (81619100019)..... PA5477	S. Fuel Ele. (81125030042)..... PF231
Urea (81154036015)..... PE5270	Air Dryer (Desiccant)..... BA5374 +	Fuel Spin-on (81125030075)..... BF587-D +
TGS 39.440 w/D 2066, D 2676 (Euro 6) Eng. (09/12-on)	Air Dryer (Coalescer) (81521086025)..... BA5379 +	Air (81083040038)..... PA2776
Lube (51055010009)..... P40042	Steering (81473016005)..... P106-HD	40.320 w/D2530 Eng.
P. Fuel (51125030063)..... PF7935	Urea (81154036015)..... PE5270	115.1 mm P. Fuel (81125030050)..... F953-F
S. Fuel (51125030062)..... PF7939	TGS 39.540 w/D 2676 (Euro 6) Eng. (09/12-on)	142.9 mm P. Fuel (81125030011)..... F950-F
Radial Seal O. Air (81084050033)..... RS4971	Lube (51055010009)..... P40042	108.7 mm S. Fuel (81125030041)..... PF834
Radial Seal I. Air (81084050017)..... RS5361	P. Fuel (51125030063)..... PF7935	148.4 mm S. Fuel..... PF231
Cab Air (w/o Charcoal) (81619100018)..... PA4955	S. Fuel (51125030062)..... PF7939	O. Air..... PA2475
Cab Air (w/Charcoal) (81619100019)..... PA5477	Radial Seal O. Air (81084050033)..... RS4971	I. Air..... PA2814
Air Dryer (81521086025)..... BA5379 +	Radial Seal I. Air (81084050017)..... RS5361	Hyd. (81055040007)..... PT691

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

**Trucks & Buses Applications** **BALDWIN FILTERS**

<b>M.A.N. European Trucks (cont'd)</b>	<b>M.A.N. European Trucks (cont'd)</b>	<b>M.A.N. European Trucks (cont'd)</b>
40.320 w/D2538 Eng. Lube (81055040041)..... <b>P294</b> 115.1 mm P. Fuel (81125030050)..... <b>F953-F</b> 142.9 mm P. Fuel (81125030011)..... <b>F950-F</b> 108.7 mm S. Fuel (81125030041)..... <b>PF834</b> 148.4 mm S. Fuel (81125030042)..... <b>PF231</b> O. Air (81082050005)..... <b>PA2475</b> I. Air..... <b>PA2814</b> Hyd. (81055040007)..... <b>PT691</b>	40.400 w/D2530 Turbo Eng. Lube (81055040041)..... <b>P294</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> Air (81082050005)..... <b>PA2475</b> 40.400 w/D2540 Eng. P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> O. Air (81083040061)..... <b>PA3606</b> I. Air (81083040066)..... <b>PA3787</b> 40.402 w/D2866 Eng. Lube (Mann HU947/2x)..... <b>P7145</b> Fuel/Water Separator (Mann WDK724)..... <b>BF1372</b> Radial Seal O. Air (Mann C301353)..... <b>RS3714</b> Radial Seal I. Air (Mann C17170)..... <b>RS4549</b> Cab Air (Mann CU40110)..... <b>PA3980</b> 40.403, 40.414 w/D2866 Eng. Lube (Mann HU1381x)..... <b>P7190</b> Fuel/Water Separator (Mann WDK724)..... <b>BF1372</b> Radial Seal O. Air (Mann C301353)..... <b>RS3714</b> Radial Seal I. Air (Mann C17170)..... <b>RS4549</b> Cab Air (Mann CU40110)..... <b>PA3980</b> 40.422 w/D2866 Eng. Lube (81055040039)..... <b>P294</b> Fuel Ele. (81125030042)..... <b>PF231</b> Fuel Spin-on (81125030075)..... <b>BF587-D +</b> Axial Seal Air (81083040043)..... <b>PA2776</b> Radial Seal O. Air (81083040094)..... <b>RS3714</b> Radial Seal I. Air (81083040084)..... <b>RS4549</b> TGS 40.440 w/D 2066 (Euro 6) Eng. (09/12-on) Lube (51055010009)..... <b>P40042</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> Radial Seal O. Air (81084050033)..... <b>RS4971</b> Radial Seal I. Air (81084050017)..... <b>RS5361</b> Cab Air (w/o Charcoal) (81619100018)..... <b>PA4955</b> Cab Air (w/Charcoal) (81619100019)..... <b>PA5477</b> Air Dryer (81521086025)..... <b>BA5379 +</b> Steering (81473016005)..... <b>P106-HD</b> Urea (81154036015)..... <b>PE5270</b> 40.440 w/D2540 Eng. P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> O. Air (81083040061)..... <b>PA3606</b> I. Air..... <b>PA3787</b>	TGS 40.440 w/D2066 (Euro 4/5) Eng. (10/07-on) Lube..... <b>P7329</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> Fuel/Water Separator..... <b>BF7912</b> Radial Seal O. Air..... <b>RS4971</b> Radial Seal I. Air..... <b>RS5361</b> Cab Air (w/o Carbon) (81619100018)..... <b>PA4955</b> Cab Air (w/Carbon) (81619100019)..... <b>PA5477</b> Air Dryer (Desiccant)..... <b>BA5374 +</b> Air Dryer (Coalescer) (81521086025)..... <b>BA5379 +</b> Steering (81473016005)..... <b>P106-HD</b> Urea (81154036015)..... <b>PE5270</b> 40.462, 40.502 w/D2840 Eng. Lube (81055040041)..... <b>P294</b> P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> Fuel Spin-on (51125030005)..... <b>BF587</b> Air (81082050005)..... <b>PA2475</b> 40.463, 40.464 w/D2876 Eng. Lube (2/95-8/96) (Mann HU947/2x)..... <b>P7145</b> Lube (9/96-on) (Mann HU1381x)..... <b>P7190</b> Fuel/Water Separator (Mann WDK724)..... <b>BF1372</b> Radial Seal O. Air (Mann C301353)..... <b>RS3714</b> Radial Seal I. Air (Mann C17170)..... <b>RS4549</b> Cab Air (Mann CU40110)..... <b>PA3980</b> TGS 40.480 w/D2676 (Euro 4/5) Eng. (10/07-on) Lube..... <b>P7329</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> Fuel/Water Separator..... <b>BF7912</b> Radial Seal O. Air..... <b>RS4971</b> Radial Seal I. Air..... <b>RS5361</b> Cab Air (w/o Carbon) (81619100018)..... <b>PA4955</b> Cab Air (w/Carbon) (81619100019)..... <b>PA5477</b> Air Dryer (Desiccant)..... <b>BA5374 +</b> Air Dryer (Coalescer) (81521086025)..... <b>BA5379 +</b> Steering (81473016005)..... <b>P106-HD</b> Urea (81154036015)..... <b>PE5270</b> 40.603, 40.604 w/D2840 Eng. Lube (Mann HU947/2x)..... <b>P7145</b> Fuel/Water Separator (Mann WDK724)..... <b>BF1372</b> Radial Seal O. Air (Mann C301353)..... <b>RS3714</b> Radial Seal I. Air (Mann C17170)..... <b>RS4549</b> Cab Air (Mann CU40110)..... <b>PA3980</b> Trans. (Mann H710/1n)..... <b>PT8385</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)
41.262, 41.272 w/D2865 Eng. 188.1 mm Lube (51055040068)... P242 264.3 mm Lube (81055040041)... P294 Fuel Ele. (81125030042)... PF231 Fuel Spin-on (81125030075)... BF587-D + Air (81083040038)... PA2776	F2000 41.343 w/D2865 Eng. (05/96-on) (Cont'd) Trans. (ZF Gearbox)... PT8385 41.343 w/D2865 Eng. (01/94-04/96) Lube (8/95-4/96) (Mann HU947/2x)... P7145 Fuel/Water Separator (Mann WDK724)... BF1372 Radial Seal O. Air (Mann C301353)... RS3714 Radial Seal I. Air (Mann C17170)... RS4549 Cab Air (Mann CU40110)... PA3980	TGS 41.400 w/D2066 (Euro 4/5) Eng. (10/07-on) Lube... P7329 P. Fuel (51125030063)... PF7935 S. Fuel (51125030062)... PF7939 Fuel/Water Separator... BF7912 Radial Seal O. Air... RS4971 Radial Seal I. Air... RS5361 Cab Air (w/o Carbon) (81619100018)... PA4955 Cab Air (w/Carbon) (81619100019)... PA5477 Air Dryer (Desiccant)... BA5374 + Air Dryer (Coalescer) (81521086025)... BA5379 + Steering (81473016005)... P106-HD Urea (81154036015)... PE5270
TGS 41.320 w/D2066 (Euro 4/5) Eng. (10/07-on) Lube... P7329 P. Fuel (51125030063)... PF7935 S. Fuel (51125030062)... PF7939 Fuel/Water Separator... BF7912 Radial Seal O. Air... RS4971 Radial Seal I. Air... RS5361 Cab Air (w/o Carbon) (81619100018)... PA4955 Cab Air (w/Carbon) (81619100019)... PA5477 Air Dryer (Desiccant)... BA5374 + Air Dryer (Coalescer) (81521086025)... BA5379 + Steering (81473016005)... P106-HD Urea (81154036015)... PE5270	TGS 41.360 w/D2066 (Euro 4/5) Eng. (10/07-on) Lube... P7329 P. Fuel (51125030063)... PF7935 S. Fuel (51125030062)... PF7939 Fuel/Water Separator... BF7912 Radial Seal O. Air... RS4971 Radial Seal I. Air... RS5361 Cab Air (w/o Carbon) (81619100018)... PA4955 Cab Air (w/Carbon) (81619100019)... PA5477 Air Dryer (Desiccant)... BA5374 + Air Dryer (Coalescer) (81521086025)... BA5379 + Steering (81473016005)... P106-HD Urea (81154036015)... PE5270	41.402VF w/D2866 Eng. Lube (5/94-1/95) (Mann HU947/1n)... P7305 Lube (2/95-on) (Mann HU947/2x)... P7145 Fuel/Water Separator (Mann WDK724)... BF1372 Radial Seal O. Air (Mann C301353)... RS3714 Radial Seal I. Air (Mann C17170)... RS4549 Cab Air (Mann CU40110)... PA3980
41.322 w/D2865 Eng. Lube (81055040041)... P294 P. Fuel Ele. (81125030011)... F950-F S. Fuel Ele. (81125030042)... PF231 Air (81083040038)... PA2776	41.361 w/D2866 Eng. F-F Lube (81055040041)... P294 B-P Lube (81055040048)... C750-E + P. Fuel Ele. (81125030011)... F950-F S. Fuel Ele. (81125030042)... PF231 O. Air (81083040038)... PA2776 I. Air... PA3494	41.403, 41.463 w/D2866, D2876 Eng. Lube (8/95-8/96) (Mann HU947/2x)... P7145 Lube (9/96-on) (Mann HU1381x)... P7190 Fuel/Water Separator (Mann WDK724)... BF1372 Radial Seal O. Air (Mann C301353)... RS3714 Radial Seal I. Air (Mann C17170)... RS4549 Cab Air (Mann CU40110)... PA3980
41.332 w/D2866 Eng. Lube (81055040039)... P294 Fuel Ele. (81125030021)... PF950 Fuel Spin-on (81125030075)... BF587-D + Air (81083040043)... PA2776	41.362 w/D2866 Eng. Lube (81055040039)... P294 Fuel Ele. (81125030021)... PF950 Fuel Spin-on (81125030075)... BF587-D + Air (81083040043)... PA2776	41.414 w/D2866 Eng. Lube (Mann HU1381x)... P7190 Fuel/Water Separator (Mann WDK724)... BF1372 Radial Seal O. Air (Mann C301353)... RS3714 Radial Seal I. Air (Mann C17170)... RS4549 Cab Air (Mann CU40110)... PA3980
41.342 w/D2865 Eng. Lube (5/94-1/95) (Mann HU947/1n)... P7305 Lube (2/95-on) (Mann HU947/2x)... P7145 Fuel/Water Separator (Mann WDK724)... BF1372 Radial Seal O. Air (Mann C301353)... RS3714 Radial Seal I. Air (Mann C17170)... RS4549 Cab Air (Mann CU40110)... PA3980	41.364 w/D2866 Eng. Lube (Mann HU1381x)... P7190 Fuel/Water Separator (Mann WDK724)... BF1372 Radial Seal O. Air (Mann C301353)... RS3714 Radial Seal I. Air (Mann C17170)... RS4549 Cab Air (Mann CU40110)... PA3980	TGS 41.440 w/D2066 (Euro 4/5) Eng. (10/07-on) Lube... P7329 P. Fuel (51125030063)... PF7935 S. Fuel (51125030062)... PF7939 Fuel/Water Separator... BF7912 Radial Seal O. Air... RS4971 Radial Seal I. Air... RS5361 Cab Air (w/o Carbon) (81619100018)... PA4955 Cab Air (w/Carbon) (81619100019)... PA5477 Air Dryer (Desiccant)... BA5374 +
F2000 41.343 w/D2865 Eng. (05/96-on) Lube... P7190 Fuel/Water Separator (51125030040)... BF1372 Radial Seal O. Air... RS3714 Radial Seal I. Air... RS4549 Cab Air... PA3980 Air Dryer (Mann TB1374X)... BA5374 + Air Dryer... BA5379 +	41.372 w/D2866 Eng. Lube (81055040039)... P294 Fuel Ele. (81125030042)... PF231 Axial Seal Air (81083040038)... PA2776 Radial Seal O. Air (81083040094)... RS3714 Radial Seal I. Air (81083040084)... RS4549	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)
TGS 41.440 w/D2066 (Euro 4/5) Eng. (10/07-on) (Cont'd) Air Dryer (Coalescer) (81521086025)..... <b>BA5379 +</b> Steering (81473016005)..... <b>P106-HD</b> Urea (81154036015)..... <b>PE5270</b>	TGX 41.480 w/D 2676 (Euro 6) Eng. (09/12-on) (Cont'd) Cab Air (w/o Charcoal) (81619100018)..... <b>PA4955</b> Cab Air (w/Charcoal) (81619100019)..... <b>PA5477</b> Air Dryer (81521086025)..... <b>BA5379 +</b> Steering (81473016005)..... <b>P106-HD</b> Urea (81154036015)..... <b>PE5270</b>	TGX 41.540 w/D 2676 (Euro 6) Eng. (09/12-on) Lube (51055010009)..... <b>P40042</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> Radial Seal O. Air (81084050033)..... <b>RS4971</b> Radial Seal I. Air (81084050017)..... <b>RS5361</b> Cab Air (w/o Charcoal) (81619100018)..... <b>PA4955</b> Cab Air (w/Charcoal) (81619100019)..... <b>PA5477</b> Air Dryer (81521086025)..... <b>BA5379 +</b> Steering (81473016005)..... <b>P106-HD</b> Urea (81154036015)..... <b>PE5270</b>
TGS 41.440 w/D 2066, D 2676 (Euro 6) Eng. (09/12-on) Lube (51055010009)..... <b>P40042</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> Radial Seal O. Air (81084050033)..... <b>RS4971</b> Radial Seal I. Air (81084050017)..... <b>RS5361</b> Cab Air (w/o Charcoal) (81619100018)..... <b>PA4955</b> Cab Air (w/Charcoal) (81619100019)..... <b>PA5477</b> Air Dryer (81521086025)..... <b>BA5379 +</b> Steering (81473016005)..... <b>P106-HD</b> Urea (81154036015)..... <b>PE5270</b>	TGS 41.540 w/D2676 (Euro 4/5) Eng. (03/08-on) Lube..... <b>P7329</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> Fuel/Water Separator..... <b>BF7912</b> Radial Seal O. Air..... <b>RS4971</b> Radial Seal I. Air..... <b>RS5361</b> Cab Air (w/o Carbon) (81619100018)..... <b>PA4955</b> Cab Air (w/Carbon) (81619100019)..... <b>PA5477</b> Air Dryer (Coalescer) (81521086025)..... <b>BA5379 +</b> Air Dryer (Desiccant) (Mann TB1374x)..... <b>BA5374 +</b> Steering (81473016005)..... <b>P106-HD</b> Urea (81154036015)..... <b>PE5270</b>	41.603, 41.604 w/D2840 Eng. Lube (Mann HU947/2x)..... <b>P7145</b> Fuel/Water Separator (Mann WDK724)..... <b>BF1372</b> Radial Seal O. Air (Mann C301353)..... <b>RS3714</b> Opt. Radial Seal I. Air (Mann C17170)..... <b>RS4549</b> Cab Air (Mann CU40110)..... <b>PA3980</b> Trans. (Mann H710/1n)..... <b>PT8385</b>
TGS 41.480 w/D2676 (Euro 4/5) Eng. (10/07-on) Lube..... <b>P7329</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> Fuel/Water Separator..... <b>BF7912</b> Radial Seal O. Air..... <b>RS4971</b> Radial Seal I. Air..... <b>RS5361</b> Cab Air (w/o Carbon) (81619100018)..... <b>PA4955</b> Cab Air (w/Carbon) (81619100019)..... <b>PA5477</b> Air Dryer (Desiccant)..... <b>BA5374 +</b> Air Dryer (Coalescer) (81521086025)..... <b>BA5379 +</b> Steering (81473016005)..... <b>P106-HD</b> Urea (81154036015)..... <b>PE5270</b>	TGX 41.540 w/D2676 (Euro 4/5) Eng. (10/07-on) Lube..... <b>P7329</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> Fuel/Water Separator..... <b>BF7912</b> Radial Seal O. Air..... <b>RS4971</b> Radial Seal I. Air..... <b>RS5361</b> Cab Air (w/o Carbon) (81619100018)..... <b>PA4955</b> Cab Air (w/Carbon) (81619100019)..... <b>PA5477</b> Air Dryer (Desiccant)..... <b>BA5374 +</b> Air Dryer (Coalescer) (81521086025)..... <b>BA5379 +</b> Steering (81473016005)..... <b>P106-HD</b> Urea (81154036015)..... <b>PE5270</b>	TGX 41.680 V8 w/D2868 (Euro 5) Eng. (10/07-on) Lube..... <b>P7329</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> Fuel/Water Separator..... <b>BF7912</b> Radial Seal O. Air..... <b>RS4971</b> Radial Seal I. Air..... <b>RS5361</b> Cab Air (w/o Carbon) (81619100018)..... <b>PA4955</b> Cab Air (w/Carbon) (81619100019)..... <b>PA5477</b> Air Dryer (Desiccant)..... <b>BA5374 +</b> Air Dryer (Coalescer) (81521086025)..... <b>BA5379 +</b> Steering (81473016005)..... <b>P106-HD</b> Urea (81154036015)..... <b>PE5270</b>
TGS 41.480 w/D 2676 (Euro 6) Eng. (09/12-on) Lube (51055010009)..... <b>P40042</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> Radial Seal O. Air (81084050033)..... <b>RS4971</b> Radial Seal I. Air (81084050017)..... <b>RS5361</b> Cab Air (w/o Charcoal) (81619100018)..... <b>PA4955</b> Cab Air (w/Charcoal) (81619100019)..... <b>PA5477</b> Air Dryer (81521086025)..... <b>BA5379 +</b> Steering (81473016005)..... <b>P106-HD</b> Urea (81154036015)..... <b>PE5270</b>	TGS 41.540 w/D 2676 (Euro 6) Eng. (09/12-on) Lube (51055010009)..... <b>P40042</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> Radial Seal O. Air (81084050033)..... <b>RS4971</b> Radial Seal I. Air (81084050017)..... <b>RS5361</b> Cab Air (w/o Charcoal) (81619100018)..... <b>PA4955</b> Cab Air (w/Charcoal) (81619100019)..... <b>PA5477</b> Air Dryer (81521086025)..... <b>BA5379 +</b> Steering (81473016005)..... <b>P106-HD</b> Urea (81154036015)..... <b>PE5270</b>	42.414, 42.464 w/D2866, D2876 Eng. Lube (Mann HU1381x)..... <b>P7190</b> Fuel/Water Separator (Mann WDK724)..... <b>BF1372</b> Radial Seal O. Air (Mann C301353)..... <b>RS3714</b> Radial Seal I. Air (Mann C17170)..... <b>RS4549</b> Cab Air (Mann CU40110)..... <b>PA3980</b>
TGX 41.480 w/D 2676 (Euro 6) Eng. (09/12-on) Lube (51055010009)..... <b>P40042</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> Radial Seal O. Air (81084050033)..... <b>RS4971</b> Radial Seal I. Air (81084050017)..... <b>RS5361</b>	TGS 41.540 w/D 2676 (Euro 6) Eng. (09/12-on) Lube (51055010009)..... <b>P40042</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> Radial Seal O. Air (81084050033)..... <b>RS4971</b> Radial Seal I. Air (81084050017)..... <b>RS5361</b> Cab Air (w/o Charcoal) (81619100018)..... <b>PA4955</b> Cab Air (w/Charcoal) (81619100019)..... <b>PA5477</b> Air Dryer (81521086025)..... <b>BA5379 +</b> Steering (81473016005)..... <b>P106-HD</b> Urea (81154036015)..... <b>PE5270</b>	48.242, 48.292 w/D2866 Eng. F-F Lube (81055040041)..... <b>P294</b> P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> Fuel Spin-on (81125030075)..... <b>BF587-D +</b> Air (81083040038)..... <b>PA2776</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)
48.321 w/D2566, D2566MK, D2566MKF Engs. F-F Lube (81055040041)..... P294 P. Fuel Ele. (81125030011)..... F950-F S. Fuel Ele. (81125030042)..... PF231 O. Air (81083040038)..... PA2776 I. Air..... PA3494	50.373, 50.403, 50.414 w/D2866 Eng. Lube (Mann HU1381x)..... P7190 Fuel/Water Separator (Mann WDK724)..... BF1372 Radial Seal O. Air (Mann C301353)..... RS3714 Radial Seal I. Air (Mann C17170)..... RS4549 Cab Air (Mann CU40110)..... PA3980	LE 140C w/D0834 Eng. (01/01-on) (Cont'd) Air Dryer..... BA5379 + Steering (81473016005)..... P106-HD
48.322 w/D2865 Eng. 188.1 mm Lube (51055040068)... P242 264.3 mm Lube (81055040041)... P294 P. Fuel Ele. (81125030011)..... F950-F S. Fuel Ele. (81125030042)..... PF231 Fuel Spin-on (81125030075)..... BF587-D + Air (81083040038)..... PA2776	50.463, 50.464 w/D2876 Eng. Lube (Mann HU1381x)..... P7190 Fuel/Water Separator (Mann WDK724)..... BF1372 Radial Seal O. Air (Mann C301353)..... RS3714 Radial Seal I. Air (Mann C17170)..... RS4549 Cab Air (Mann CU40110)..... PA3980	LE 160C w/D0824LFL08 Eng. (08/00-on) Lube..... B7116 Fuel/Water Separator (51125030040)..... BF1372 Radial Seal O. Air..... RS4775 Cab Air (85619500025)..... PA5339 Air Dryer (Mann TB1374X)..... BA5374 + Air Dryer..... BA5379 + Steering (81473016005)..... P106-HD
48.331 w/D2866 Eng. P. Fuel Ele. (81125030011)..... F950-F S. Fuel Ele. (81125030042)..... PF231 Air (81083040038)..... PA2776 Hyd. (81055040007)..... PT691	TGS 50.480 w/D 2676 (Euro 6) Eng. (09/12-on) Lube (51055010009)..... P40042 P. Fuel (51125030063)..... PF7935 S. Fuel (51125030062)..... PF7939 Radial Seal O. Air (81084050033)..... RS4971 Radial Seal I. Air (81084050017)..... RS5361 Cab Air (w/o Charcoal) (81619100018)..... PA4955 Cab Air (w/Charcoal) (81619100019)..... PA5477 Air Dryer (81521086025)..... BA5379 + Steering (81473016005)..... P106-HD Urea (81154036015)..... PE5270	LE 180C w/D0834 Eng. (01/01-on) Lube..... B7116 Fuel/Water Separator (51125030040)..... BF1372 Radial Seal O. Air..... RS4775 Cab Air (85619500025)..... PA5339 Air Dryer (Mann TB1374X)..... BA5374 + Air Dryer..... BA5379 + Steering (81473016005)..... P106-HD
48.332, 48.362 w/D2866 Eng. Lube (81055040041)..... P294 Fuel Ele. (81125030021)..... PF950 Fuel Spin-on (81125030075)..... BF587-D + Air (81083040038)..... PA2776	50.603, 50.604 w/D2840 Eng. Lube (Mann HU947/2x)..... P7145 Fuel/Water Separator (Mann WDK724)..... BF1372 Radial Seal O. Air (Mann C301353)..... RS3714 Opt. Radial Seal I. Air (Mann C17170)..... RS4549 Cab Air (Mann CU40110)..... PA3980 Trans. (Mann H710/1n)..... PT8385	EL202, NL202 w/D0826 Eng. Lube..... B7116 Fuel Spin-on..... BF587-D + Air (1989-on)..... PA3760
48.372 w/D2866 Eng. Lube (81055040041)..... P294 Fuel Ele. (81125030042)..... PF231 Axial Seal Air (81083040038)..... PA2776 Radial Seal O. Air (81083040094)..... RS3714 Radial Seal I. Air (81083040084)..... RS4549	LE 110C w/D0824LFL06 Eng. (08/00-on) Lube..... B7116 Fuel/Water Separator (51125030040)..... BF1372 Radial Seal O. Air..... RS4775 Cab Air (85619500025)..... PA5339 Air Dryer (Mann TB1374X)..... BA5374 + Air Dryer..... BA5379 + Steering (81473016005)..... P106-HD	LE 220B w/D0826LFL10 Eng. (09/00-on) Lube..... B7116 Fuel/Water Separator (51125030040)..... BF1372 Radial Seal Air..... RS4775 Cab Air (85619500025)..... PA5339 Air Dryer (Mann TB1374X)..... BA5374 + Air Dryer..... BA5379 + Steering..... P106-HD
48.422 w/D2866 Eng. Lube (81055040041)..... P294 Fuel Ele. (81125030042)..... PF231 Axial Seal Air (81083040038)..... PA2776 Radial Seal O. Air (81083040094)..... RS3714 Radial Seal I. Air (81083040084)..... RS4549	LE 140C w/D0834 Eng. (01/01-on) Lube..... B7116 Fuel/Water Separator (51125030040)..... BF1372 Radial Seal O. Air..... RS4775 Cab Air (85619500025)..... PA5339 Air Dryer (Mann TB1374X)..... BA5374 + Air Dryer..... BA5379 + Steering..... P106-HD	LE 220C w/D0836 Eng. (01/01-on) Lube..... B7116 Fuel/Water Separator (51125030040)..... BF1372 Radial Seal Air..... RS4775 Cab Air (85619500025)..... PA5339 Air Dryer (Mann TB1374X)..... BA5374 + Air Dryer..... BA5379 + Steering..... P106-HD
48.462, 48.502 w/D2840 Eng. Lube (81055040041)..... P294 P. Fuel Ele. (81125030011)..... F950-F S. Fuel Ele. (81125030042)..... PF231 Fuel Spin-on (51125030004)..... BF587 Air (81082050005)..... PA2475	LE 140C w/D0834 Eng. (01/01-on) Lube..... B7116 Fuel/Water Separator (51125030040)..... BF1372 Radial Seal O. Air..... RS4775 Cab Air (85619500025)..... PA5339 Air Dryer (Mann TB1374X)..... BA5374 +	LE 220C w/D0826LFL10 Eng. (09/00-on) Lube..... B7116 Fuel/Water Separator (51125030040)..... BF1372 Radial Seal Air..... RS4775 Cab Air (85619500025)..... PA5339 Air Dryer (Mann TB1374X)..... BA5374 + Air Dryer..... BA5379 + Steering..... P106-HD
48.700 w/D2842 Eng. Lube (81055040041)..... P294 P. Fuel Ele. (81125030011)..... F950-F S. Fuel Ele. (81125030042)..... PF231 Air (81083040038)..... PA2776	CLA 49.280 w/D0836 EURO3 Eng. (10/06-on) Lube..... B7116 Fuel/Water Separator (51125030040)..... BF1372 O. Air..... PA3760 Steering (81473016005)..... P106-HD	LE 220C w/D0836 Eng. (01/01-on) Lube..... B7116 Fuel/Water Separator (51125030040)..... BF1372 Radial Seal Air..... RS4775 Cab Air (85619500025)..... PA5339

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

**Trucks & Buses Applications** **BALDWIN FILTERS**

<b>M.A.N.</b> <b>European Trucks (cont'd)</b>	<b>M.A.N.</b> <b>European Trucks (cont'd)</b>	<b>M.A.N.</b> <b>European Trucks (cont'd)</b>
LE 220C w/D0836 Eng. (01/01-on) (Cont'd)	ME 280B w/D0836 Eng. (08/00-on)	TGA TG310A w/D2866, D2876 Engs.
Air Dryer (Mann TB1374X)..... BA5374 +	Lube..... B7116	(05/00-03/04)
Air Dryer..... BA5379 +	Fuel/Water Separator	Lube (51055040098)..... P7190
Steering (81473016005)..... P106-HD	(51125030040)..... BF1372	Fuel/Water Separator
ME 220B w/D0836 Eng. (08/00-on)	Radial Seal Air..... RS4775	(81125030086)..... BF7912
Lube..... B7116	Cab Air..... PA3980	Fuel..... PF7878
Fuel/Water Separator	Air Dryer (Mann TB1374X)..... BA5374 +	Fuel Pre-filter (51125030062)..... PF7939
(51125030040)..... BF1372	Air Dryer..... BA5379 +	Radial Seal O. Air..... RS4971
Radial Seal Air..... RS4775	Steering (81473016005)..... P106-HD	Radial Seal I. Air (81084050017)..... RS5361
Cab Air..... PA3980	TGA TG280A w/D0836 Eng. (08/03-on)	Cab Air (w/o Carbon)
Air Dryer (Mann TB1374X)..... BA5374 +	Lube..... P7196	(81619100018)..... PA4955
Air Dryer..... BA5379 +	Fuel/Water Separator	Cab Air (w/Carbon)
Steering (81473016005)..... P106-HD	(81125030086)..... BF7912	(81619100019)..... PA5477
240, 270 w/R.V.I. 712 Eng.	Fuel Pre-filter (51125030062)..... PF7939	Air Dryer (Desiccant) (Mann
Lube..... P7607	Fuel (51125030048)..... PF7878	TB1374X)..... BA5374 +
Fuel (A5000241676)..... PF7596	Radial Seal O. Air..... RS4971	Air Dryer (Coalescer)
LE 250B w/D0836 Eng. (01/01-on)	Radial Seal I. Air (81084050017)..... RS5361	(81521086025)..... BA5379 +
Lube..... B7116	Cab Air (w/o Carbon)	Steering..... P106-HD
Fuel/Water Separator	(81619100018)..... PA4955	TGA TG330A w/D0836 Eng. (08/03-on)
(51125030040)..... BF1372	Cab Air (w/Carbon)	Lube..... P7196
Radial Seal Air..... RS4775	(81619100019)..... PA5477	Fuel/Water Separator
Cab Air..... PA3980	Air Dryer (Desiccant) (Mann	(81125030086)..... BF7912
Air Dryer (Mann TB1374X)..... BA5374 +	TB1374X)..... BA5374 +	Fuel (51125030048)..... PF7878
Air Dryer..... BA5379 +	Air Dryer (Coalescer)	Fuel Pre-filter (51125030062)..... PF7939
Steering (81473016005)..... P106-HD	(81521086025)..... BA5379 +	Radial Seal O. Air..... RS4971
ME 250B w/D0836 Eng. (08/00-on)	Steering..... P106-HD	Radial Seal I. Air (81084050017)..... RS5361
Lube..... B7116	FE310A w/D2866 Eng. (09/00-on)	Cab Air (w/o Carbon)
Fuel/Water Separator	Lube (51055040098)..... P7190	(81619100018)..... PA4955
(51125030040)..... BF1372	Fuel/Water Separator	Cab Air (w/Carbon)
Radial Seal Air..... RS4775	(51125030040)..... BF1372	(81619100019)..... PA5477
Cab Air..... PA3980	Radial Seal O. Air (Mann	Air Dryer (Desiccant) (Mann
Air Dryer (Mann TB1374X)..... BA5374 +	C301353)..... RS3714	TB1374X)..... BA5374 +
Air Dryer..... BA5379 +	Radial Seal I. Air (81083040084)..... RS4549	Air Dryer (Coalescer)
Steering (81473016005)..... P106-HD	Cab Air (Mann CU40110)..... PA3980	(81521086025)..... BA5379 +
ME 260 B w/D0836 Eng. (08/00-04/07)	Air Dryer (Mann TB1374X)..... BA5374 +	Steering..... P106-HD
Lube (51055017160)..... B7116	Air Dryer..... BA5379 +	TGA TG350A w/D2066 Eng. (02/04-on)
Fuel/Water Separator	Trans. (ZF Gearbox)..... PT8385	Lube (51055040108)..... P7329
(51125030040)..... BF1372	Steering (81473016005)..... P106-HD	Fuel/Water Separator
Fuel/Water Separator	TGA TG310A w/D2066 Eng. (02/04-on)	(81125030086)..... BF7912
(81125010022)..... BF7881	Lube (51055040108)..... P7329	P. Fuel (51125030063)..... PF7935
Fuel/Water Separator (Bio Diesel	Fuel/Water Separator	S. Fuel (51125030062)..... PF7939
(81125010032)..... BF7881	(81125030086)..... BF7912	Radial Seal O. Air..... RS4971
S. Fuel (51125030062)..... PF7939	P. Fuel (51125030063)..... PF7935	Radial Seal I. Air (81084050017)..... RS5361
Radial Seal Air (81084050015)..... RS4775	S. Fuel (51125030062)..... PF7939	Cab Air (w/o Carbon)
Cab Air (81619100011)..... PA3980	Radial Seal O. Air..... RS4971	(81619100018)..... PA4955
Air Dryer (81521020008)..... BA5374 +	Radial Seal I. Air (81084050017)..... RS5361	Cab Air (w/Carbon)
Air Dryer (81521086025)..... BA5379 +	Cab Air (w/o Carbon)	(81619100019)..... PA5477
Steering (81473016005)..... P106-HD	(81619100018)..... PA4955	Air Dryer (Desiccant) (Mann
LE 280B w/D0836 Eng. (01/01-on)	Cab Air (w/Carbon)	TB1374X)..... BA5374 +
Lube..... B7116	(81619100019)..... PA5477	Air Dryer (Coalescer)
Fuel/Water Separator	Air Dryer (Desiccant) (Mann	(81521086025)..... BA5379 +
(51125030040)..... BF1372	TB1374X)..... BA5374 +	Steering..... P106-HD
Radial Seal Air..... RS4775	Air Dryer (Coalescer)	FE360A w/D2866 Eng. (09/00-on)
Cab Air..... PA3980	(81521086025)..... BA5379 +	Lube (51055040098)..... P7190
Air Dryer (Mann TB1374X)..... BA5374 +	Steering..... P106-HD	Fuel/Water Separator
Air Dryer..... BA5379 +	TGA TG310A w/D2066 Eng. (02/04-on)	(51125030040)..... BF1372
Steering (81473016005)..... P106-HD	Lube (51055040108)..... P7329	Radial Seal O. Air (Mann
	Fuel/Water Separator	C301353)..... RS3714
	(81125030086)..... BF7912	Radial Seal I. Air (81083040084)..... RS4549
	P. Fuel (51125030063)..... PF7935	
	S. Fuel (51125030062)..... PF7939	
	Radial Seal O. Air..... RS4971	
	Radial Seal I. Air (81084050017)..... RS5361	
	Cab Air (w/o Carbon)	
	(81619100018)..... PA4955	
	Cab Air (w/Carbon)	
	(81619100019)..... PA5477	
	Air Dryer (Desiccant) (Mann	
	TB1374X)..... BA5374 +	
	Air Dryer (Coalescer)	
	(81521086025)..... BA5379 +	
	Steering..... P106-HD	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)
FE360A w/D2866 Eng. (09/00-on) (Cont'd)	TGA TG400A w/D2066 (Euro 5) Eng. (06/06-on) (Cont'd)	TGA TG440A w/D2066 (Euro 5) Eng. (06/06-on)
<b>Cab Air</b> (Mann CU40110)..... <b>PA3980</b>	<b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b>	<b>Lube</b> (51055040107)..... <b>P7329</b>
<b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b>	<b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b>	<b>Fuel/Water Separator</b> (81125030086)..... <b>BF7912</b>
<b>Air Dryer</b> ..... <b>BA5379 +</b>	<b>Steering</b> ..... <b>P106-HD</b>	<b>Fuel Pre-filter</b> ..... <b>PF7939</b>
<b>Trans.</b> (ZF Gearbox)..... <b>PT8385</b>	<b>Urea</b> (81154036015)..... <b>PE5270</b>	<b>Fuel</b> (51125030063)..... <b>PF7935</b>
<b>Steering</b> (81473016005)..... <b>P106-HD</b>	FE410A w/D2866 Eng. (09/00-on)	<b>Radial Seal O. Air</b> ..... <b>RS4971</b>
TGA TG360A w/D2866, D2876 Engs. (05/00-03/04)	<b>Lube</b> (51055040098)..... <b>P7190</b>	<b>Radial Seal I. Air</b> (81084050017)..... <b>RS5361</b>
<b>Lube</b> (51055040098)..... <b>P7190</b>	<b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b>	<b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b>
<b>Fuel/Water Separator</b> (81125030086)..... <b>BF7912</b>	<b>Radial Seal O. Air</b> (Mann C301353)..... <b>RS3714</b>	<b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b>
<b>Fuel Pre-filter</b> (51125030062)..... <b>PF7939</b>	<b>Radial Seal I. Air</b> (81083040084)..... <b>RS4549</b>	<b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b>
<b>Fuel</b> ..... <b>PF7878</b>	<b>Cab Air</b> (Mann CU40110)..... <b>PA3980</b>	<b>Steering</b> ..... <b>P106-HD</b>
<b>Radial Seal O. Air</b> ..... <b>RS4971</b>	<b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b>	FE 460A w/D2876 Eng. (09/00-on)
<b>Radial Seal I. Air</b> (81084050017)..... <b>RS5361</b>	<b>Air Dryer</b> ..... <b>BA5379 +</b>	<b>Lube</b> (51055040098)..... <b>P7190</b>
<b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b>	<b>Trans.</b> (ZF Gearbox)..... <b>PT8385</b>	<b>Fuel/Water Separator</b> (51125030040)..... <b>BF1372</b>
<b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b>	<b>Steering</b> (81473016005)..... <b>P106-HD</b>	<b>Radial Seal O. Air</b> (Mann C301353)..... <b>RS3714</b>
<b>Air Dryer</b> (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b>	TGA TG410A w/D2866, D2876 Engs. (05/00-03/04)	<b>Radial Seal I. Air</b> (81083040084)..... <b>RS4549</b>
<b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b>	<b>Lube</b> (51055040098)..... <b>P7190</b>	<b>Cab Air</b> (Mann CU40110)..... <b>PA3980</b>
<b>Steering</b> ..... <b>P106-HD</b>	<b>Fuel/Water Separator</b> (81125030086)..... <b>BF7912</b>	<b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b>
NL363 w/D2866 Eng.	<b>Fuel Pre-filter</b> (51125030062)..... <b>PF7939</b>	<b>Air Dryer</b> ..... <b>BA5379 +</b>
<b>Lube</b> (Mann HU1381x)..... <b>P7190</b>	<b>Fuel</b> ..... <b>PF7878</b>	<b>Trans.</b> (ZF Gearbox)..... <b>PT8385</b>
<b>Fuel/Water Separator</b> (Mann WDK724)..... <b>BF1372</b>	<b>Radial Seal O. Air</b> ..... <b>RS4971</b>	<b>Steering</b> (81473016005)..... <b>P106-HD</b>
<b>Air</b> (Mann C30850/2)..... <b>PA2776</b>	<b>Radial Seal I. Air</b> (81084050017)..... <b>RS5361</b>	RH460, RH463 w/D2876 Eng.
TGA TG390A w/D2066 Eng. (02/04-on)	<b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b>	<b>Lube</b> (Mann HU1381x)..... <b>P7190</b>
<b>Lube</b> (51055040108)..... <b>P7329</b>	<b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b>	<b>Fuel/Water Separator</b> (Mann WDK724)..... <b>BF1372</b>
<b>Fuel/Water Separator</b> (81125030086)..... <b>BF7912</b>	<b>Air Dryer</b> (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b>	<b>Air</b> (Mann C30850/2)..... <b>PA2776</b>
<b>P. Fuel</b> (51125030063)..... <b>PF7935</b>	<b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b>	TGA TG460A w/D2866 Eng. (05/00-03/04)
<b>S. Fuel</b> (51125030062)..... <b>PF7939</b>	<b>Steering</b> ..... <b>P106-HD</b>	<b>Lube</b> (51055040098)..... <b>P7190</b>
<b>Radial Seal O. Air</b> ..... <b>RS4971</b>	TGA TG430A w/D2066 Eng. (02/04-on)	<b>Fuel</b> ..... <b>PF7878</b>
<b>Radial Seal I. Air</b> (81084050017)..... <b>RS5361</b>	<b>Lube</b> (51055040108)..... <b>P7329</b>	<b>Radial Seal O. Air</b> ..... <b>RS4971</b>
<b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b>	<b>Fuel/Water Separator</b> (81125030086)..... <b>BF7912</b>	<b>Radial Seal I. Air</b> (81084050017)..... <b>RS5361</b>
<b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b>	<b>P. Fuel</b> (51125030063)..... <b>PF7935</b>	<b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b>
<b>Air Dryer</b> (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b>	<b>S. Fuel</b> (51125030062)..... <b>PF7939</b>	<b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b>
<b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b>	<b>Radial Seal O. Air</b> ..... <b>RS4971</b>	<b>Air Dryer</b> (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b>
<b>Steering</b> ..... <b>P106-HD</b>	<b>Radial Seal I. Air</b> (81084050017)..... <b>RS5361</b>	<b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b>
400, 415	<b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b>	<b>Steering</b> ..... <b>P106-HD</b>
<b>F-F Lube</b> (81055040032)..... <b>P235</b>	<b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b>	TGA TG460A w/D2876 Eng. (04/00-on)
<b>P. Fuel</b> (81125030050)..... <b>F953-F</b>	<b>Air Dryer</b> (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b>	<b>Lube</b> ..... <b>P7190</b>
<b>S. Fuel</b> (81125030041)..... <b>PF834</b>	<b>Air Dryer</b> (Coalescer) (81521086025)..... <b>BA5379 +</b>	<b>Fuel/Water Separator</b> (81125030086)..... <b>BF7912</b>
TGA TG400A w/D2066 (Euro 5) Eng. (06/06-on)	<b>Steering</b> ..... <b>P106-HD</b>	<b>Fuel</b> (51125030048)..... <b>PF7878</b>
<b>Lube</b> (51055040107)..... <b>P7329</b>	400, 415	<b>Fuel Pre-filter</b> (51125030062)..... <b>PF7939</b>
<b>Fuel/Water Separator</b> (81125030086)..... <b>BF7912</b>	<b>F-F Lube</b> (81055040032)..... <b>P235</b>	<b>Radial Seal O. Air</b> ..... <b>RS4971</b>
<b>Fuel</b> (51125030063)..... <b>PF7935</b>	<b>P. Fuel</b> (81125030050)..... <b>F953-F</b>	<b>Radial Seal I. Air</b> (81084050017)..... <b>RS5361</b>
<b>Fuel Pre-filter</b> (PF7939)..... <b>PF7939</b>	<b>S. Fuel</b> (81125030041)..... <b>PF834</b>	<b>Cab Air</b> (w/o Carbon) (81619100018)..... <b>PA4955</b>
<b>Radial Seal O. Air</b> ..... <b>RS4971</b>	TGA TG400A w/D2066 (Euro 5) Eng. (06/06-on)	<b>Cab Air</b> (w/Carbon) (81619100019)..... <b>PA5477</b>
<b>Radial Seal I. Air</b> (81084050017)..... <b>RS5361</b>	<b>Lube</b> (51055040107)..... <b>P7329</b>	<b>Air Dryer</b> (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)
TGA TG460A w/D2876 Eng. (04/00-on) (Cont'd) Air Dryer (Coalescer) (81521086025)..... <b>BA5379 +</b> Steering..... <b>P106-HD</b>	TGA TG510A w/D2876 Eng. (01/00-on) Lube..... <b>P7190</b> Fuel/Water Separator (81125030086)..... <b>BF7912</b> Fuel Pre-filter (51125030062)..... <b>PF7939</b> Fuel (51125030048)..... <b>PF7878</b> Radial Seal O. Air..... <b>RS4971</b> Radial Seal I. Air (81084050017)..... <b>RS5361</b> Cab Air (w/o Carbon)..... <b>PA4955</b> Cab Air (w/Carbon) (81619100019)..... <b>PA5477</b> Air Dryer (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer (Coalescer) (81521086025)..... <b>BA5379 +</b> Steering..... <b>P106-HD</b>	FE 600 A w/D 2840 LF21 Eng. (09/00-on) Lube (51055040096)..... <b>P7145</b> Fuel/Water Separator (51125030040)..... <b>BF1372</b> Fuel/Water Separator (81125010030)..... <b>BF7912</b> Radial Seal O. Air (81083040083)..... <b>RS3714</b> Radial Seal I. Air (81083040084)..... <b>RS4549</b> Cab Air (81619100011)..... <b>PA3980</b> Air Dryer (Coalescer Vers.) (81521086025)..... <b>BA5379 +</b> Air Dryer (Desiccant Vers.) (81521020008)..... <b>BA5374 +</b> Steering (81473016005)..... <b>P106-HD</b>
FRH462 w/D2876 Eng. Lube (Mann HU1381x)..... <b>P7190</b> Fuel/Water Separator (Mann WDK724)..... <b>BF1372</b>	520 Lube (81055040032)..... <b>P235</b> P. Fuel (81125030050)..... <b>F953-F</b> S. Fuel (81125030041)..... <b>PF834</b>	620 F-F Lube (81055040032)..... <b>P235</b> B-P Lube (81055040008)..... <b>P42</b> P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b>
TGA TG480A w/D2676 (Euro 5) Eng. (06/06-on) Lube (51055040107)..... <b>P7329</b> Fuel/Water Separator (81125030086)..... <b>BF7912</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> Radial Seal O. Air..... <b>RS4971</b> Radial Seal I. Air (81084050017)..... <b>RS5361</b> Cab Air (w/o Carbon) (81619100018)..... <b>PA4955</b> Cab Air (w/Carbon) (81619100019)..... <b>PA5477</b> Air Dryer (81521086025)..... <b>BA5379 +</b> Steering..... <b>P106-HD</b> Urea (81154036015)..... <b>PE5270</b>	TGA TG530A w/D2876 Eng. (01/03-on) Lube..... <b>P7190</b> Fuel/Water Separator (81125030086)..... <b>BF7912</b> Fuel Pre-filter (51125030062)..... <b>PF7939</b> Fuel..... <b>PF7878</b> Radial Seal O. Air..... <b>RS4971</b> Radial Seal I. Air (81084050017)..... <b>RS5361</b> Cab Air (w/o Carbon)..... <b>PA4955</b> Cab Air (w/Carbon) (81619100019)..... <b>PA5477</b> Air Dryer (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer (Coalescer) (81521086025)..... <b>BA5379 +</b> Steering..... <b>P106-HD</b>	626 w/D0836M2 Eng. Lube (81055040032)..... <b>P235</b> P. Fuel (81125030050)..... <b>F953-F</b> S. Fuel (81125030041)..... <b>PF834</b> Hyd. (81055040007)..... <b>PT691</b>
TGA TG480A w/D2876 Eng. (02/03-on) Lube..... <b>P7190</b> Fuel/Water Separator (81125030086)..... <b>BF7912</b> Fuel Pre-filter (51125030062)..... <b>PF7939</b> Fuel..... <b>PF7878</b> Radial Seal O. Air..... <b>RS4971</b> Radial Seal I. Air (81084050017)..... <b>RS5361</b> Cab Air (w/o Carbon)..... <b>PA4955</b> Cab Air (w/Carbon) (81619100019)..... <b>PA5477</b> Air Dryer (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer (Coalescer) (81521086025)..... <b>BA5379 +</b> Steering..... <b>P106-HD</b>	TGA TG540A w/D2676 (Euro 5) Eng. (06/06-on) Lube (51055040107)..... <b>P7329</b> Fuel/Water Separator (81125030086)..... <b>BF7912</b> P. Fuel (51125030063)..... <b>PF7935</b> S. Fuel (51125030062)..... <b>PF7939</b> Radial Seal O. Air..... <b>RS4971</b> Radial Seal I. Air (81084050017)..... <b>RS5361</b> Cab Air (w/o Carbon) (81619100018)..... <b>PA4955</b> Cab Air (w/Carbon) (81619100019)..... <b>PA5477</b> Air Dryer (81521086025)..... <b>BA5379 +</b> Steering..... <b>P106-HD</b> Urea (81154036015)..... <b>PE5270</b>	630 F-F Lube (81055040032)..... <b>P235</b> B-P Lube (81055040008)..... <b>P42</b> P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b>
TGA TG510A w/D2866, D2876 Engs. (05/00-03/04) Lube (51055040098)..... <b>P7190</b> Fuel..... <b>PF7878</b> Radial Seal O. Air..... <b>RS4971</b> Radial Seal I. Air (81084050017)..... <b>RS5361</b> Cab Air (w/o Carbon) (81619100018)..... <b>PA4955</b> Cab Air (w/Carbon) (81619100019)..... <b>PA5477</b> Air Dryer (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer (Coalescer) (81521086025)..... <b>BA5379 +</b> Steering..... <b>P106-HD</b>	570, 585 w/R.V.I. 712 Eng. Lube..... <b>P7607</b> Fuel (A5000241676)..... <b>PF7596</b>	630L2A, 630L2AE B-P Lube (81055040008)..... <b>P42</b> Fuel Ele. (81125030041)..... <b>PF834</b> P. Fuel Ele. (81125030011)..... <b>F950-F</b> S. Fuel Ele. (81125030042)..... <b>PF231</b> Hyd. (81055040007)..... <b>PT691</b>
		635, 650 w/D0836M2 Eng. Lube (81055040032)..... <b>P235</b> P. Fuel (81125030050)..... <b>F953-F</b> S. Fuel (81125030041)..... <b>PF834</b> Hyd. (81055040007)..... <b>PT691</b>
		TGA TG660A w/D2840 Eng. (09/02-on) Lube..... <b>P7145</b> Fuel/Water Separator (81125030086)..... <b>BF7912</b> Fuel Pre-filter (51125030062)..... <b>PF7939</b> Fuel..... <b>PF7878</b> Radial Seal O. Air..... <b>RS4971</b> Radial Seal I. Air (81084050017)..... <b>RS5361</b> Cab Air (w/o Carbon) (81619100018)..... <b>PA4955</b> Cab Air (w/Carbon) (81619100019)..... <b>PA5477</b> Air Dryer (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer (Coalescer) (81521086025)..... <b>BA5379 +</b> Steering..... <b>P106-HD</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)
690 w/R.V.I. 720 Eng. <b>Can-Type Fuel</b> (81125030038).... <b>BF825 +</b>	TGL 7220 w/D 0834 Eng. (09/08-on) (Cont'd) <b>Fuel/Water Separator</b> (Bio Diesel) (81125010032)..... <b>BF7881</b>	TGL 10290 w/D0836 Eng. (09/08-on) (Cont'd) <b>Fuel/Water Separator</b> (Bio Diesel) (81125010032)..... <b>BF7881</b>
735 w/D0836M2 Eng. <b>Lube</b> (81055040032)..... <b>P235</b>	<b>P. Fuel</b> (51125030063)..... <b>PF7935</b>	<b>P. Fuel</b> (51125030063)..... <b>PF7935</b>
<b>P. Fuel</b> (81125030050)..... <b>F953-F</b>	<b>S. Fuel</b> (51125030062)..... <b>PF7939</b>	<b>S. Fuel</b> (51125030062)..... <b>PF7939</b>
<b>S. Fuel</b> (81125030041)..... <b>PF834</b>	<b>414.3 mm Radial Seal Air</b> (81084050022)..... <b>RS5409</b>	<b>414.3 mm Radial Seal Air</b> (81084050022)..... <b>RS5409</b>
<b>Hyd.</b> (81055040007)..... <b>PT691</b>	<b>457.2 mm Radial Seal Air</b> (81084050018)..... <b>RS5506</b>	<b>457.2 mm Radial Seal Air</b> (81084050018)..... <b>RS5506</b>
750, 758, 770, 780 <b>F-F Lube</b> (81055040032)..... <b>P235</b>	<b>Cab Air</b> (w/o Charcoal) (81619100018)..... <b>PA4955</b>	<b>Cab Air</b> (w/o Charcoal) (81619100018)..... <b>PA4955</b>
<b>B-P Lube</b> (81055040008)..... <b>P42</b>	<b>Cab Air</b> (w/Charcoal) (81619100019)..... <b>PA5477</b>	<b>Cab Air</b> (w/Charcoal) (81619100019)..... <b>PA5477</b>
<b>P. Fuel Ele.</b> (81125030011)..... <b>F950-F</b>	<b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b>	<b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b>
<b>S. Fuel Ele.</b> (81125030042)..... <b>PF231</b>	<b>Steering</b> (81473016005)..... <b>P106-HD</b>	<b>Steering</b> (81473016005)..... <b>P106-HD</b>
785 w/R.V.I. 712 Eng. <b>Lube</b> ..... <b>P7607</b>	<b>Urea</b> (81154036015)..... <b>PE5270</b>	<b>Urea</b> (81154036015)..... <b>PE5270</b>
<b>Fuel</b> (A5000241676)..... <b>PF7596</b>		
790 w/Saviem Eng. <b>Can-Type Fuel</b> (81125030038).... <b>BF825 +</b>	TGL 7250 w/D 0836 Eng. (05/09-on) <b>Lube</b> (51055006073)..... <b>P7196</b>	TGM 12240 w/D 0836 Eng. (09/06-on) <b>Lube</b> (51055006073)..... <b>P7196</b>
830, 835, 845 <b>F-F Lube</b> (81055040032)..... <b>P235</b>	<b>Fuel/Water Separator</b> (81125010022)..... <b>BF7881</b>	<b>Fuel/Water Separator</b> (81125010022)..... <b>BF7881</b>
<b>B-P Lube</b> (81055040008)..... <b>P42</b>	<b>Fuel/Water Separator</b> (Bio Diesel) (81125010032)..... <b>BF7881</b>	<b>Fuel/Water Separator</b> (Bio Diesel) (81125010032)..... <b>BF7881</b>
<b>P. Fuel Ele.</b> (81125030011)..... <b>F950-F</b>	<b>P. Fuel</b> (51125030063)..... <b>PF7935</b>	<b>P. Fuel</b> (51125030063)..... <b>PF7935</b>
<b>S. Fuel Ele.</b> (81125030042)..... <b>PF231</b>	<b>S. Fuel</b> (51125030062)..... <b>PF7939</b>	<b>S. Fuel</b> (51125030062)..... <b>PF7939</b>
850 w/D0836M2 Eng. <b>F-F Lube</b> (81055040032)..... <b>P235</b>	<b>414.3 mm Radial Seal Air</b> (81084050022)..... <b>RS5409</b>	<b>414.3 mm Radial Seal Air</b> (81084050022)..... <b>RS5409</b>
<b>P. Fuel</b> (81125030050)..... <b>F953-F</b>	<b>457.2 mm Radial Seal Air</b> (81084050018)..... <b>RS5506</b>	<b>457.2 mm Radial Seal Air</b> (81084050018)..... <b>RS5506</b>
<b>S. Fuel</b> (81125030041)..... <b>PF834</b>	<b>Cab Air</b> (w/o Charcoal) (81619100018)..... <b>PA4955</b>	<b>Cab Air</b> (w/o Charcoal) (81619100018)..... <b>PA4955</b>
<b>Hyd.</b> (81055040007)..... <b>PT691</b>	<b>Cab Air</b> (w/Charcoal) (81619100019)..... <b>PA5477</b>	<b>Cab Air</b> (w/Charcoal) (81619100019)..... <b>PA5477</b>
860 <b>F-F Lube</b> (81055040032)..... <b>P235</b>	<b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b>	<b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b>
<b>B-P Lube</b> (81055040008)..... <b>P42</b>	<b>Steering</b> (81473016005)..... <b>P106-HD</b>	<b>Steering</b> (81473016005)..... <b>P106-HD</b>
<b>P. Fuel Ele.</b> (81125030011)..... <b>F950-F</b>	<b>Urea</b> (81154036015)..... <b>PE5270</b>	<b>Urea</b> (81154036015)..... <b>PE5270</b>
<b>S. Fuel Ele.</b> (81125030042)..... <b>PF231</b>		
1070, 1080 <b>F-F Lube</b> (81055040032)..... <b>P235</b>	TGL 8290 w/D 0836 Eng. (09/08-on) <b>Lube</b> (51055006073)..... <b>P7196</b>	TGM 12250 w/D 0836 Eng. (02/09-on) <b>Lube</b> (51055006073)..... <b>P7196</b>
<b>B-P Lube</b> (81055040008)..... <b>P42</b>	<b>Fuel/Water Separator</b> (81125010022)..... <b>BF7881</b>	<b>Fuel/Water Separator</b> (81125010022)..... <b>BF7881</b>
<b>P. Fuel Ele.</b> (81125030011)..... <b>F950-F</b>	<b>Fuel/Water Separator</b> (Bio Diesel) (81125010032)..... <b>BF7881</b>	<b>Fuel/Water Separator</b> (Bio Diesel) (81125010032)..... <b>BF7881</b>
<b>S. Fuel Ele.</b> (81125030042)..... <b>PF231</b>	<b>P. Fuel</b> (51125030063)..... <b>PF7935</b>	<b>P. Fuel</b> (51125030063)..... <b>PF7935</b>
1580 <b>F-F Lube</b> (81055040032)..... <b>P235</b>	<b>S. Fuel</b> (51125030062)..... <b>PF7939</b>	<b>S. Fuel</b> (51125030062)..... <b>PF7939</b>
<b>B-P Lube</b> (81055040008)..... <b>P42</b>	<b>414.3 mm Radial Seal Air</b> (81084050022)..... <b>RS5409</b>	<b>414.3 mm Radial Seal Air</b> (81084050022)..... <b>RS5409</b>
<b>P. Fuel Ele.</b> (81125030011)..... <b>F950-F</b>	<b>457.2 mm Radial Seal Air</b> (81084050018)..... <b>RS5506</b>	<b>457.2 mm Radial Seal Air</b> (81084050018)..... <b>RS5506</b>
<b>S. Fuel Ele.</b> (81125030042)..... <b>PF231</b>	<b>Cab Air</b> (w/o Charcoal) (81619100018)..... <b>PA4955</b>	<b>Cab Air</b> (w/o Charcoal) (81619100018)..... <b>PA4955</b>
F2000 Evo w/M.A.N. 12L Eng. <b>Radial Seal O. Air</b> (81083040083)..... <b>RS3714</b>	<b>Cab Air</b> (w/Charcoal) (81619100019)..... <b>PA5477</b>	<b>Cab Air</b> (w/Charcoal) (81619100019)..... <b>PA5477</b>
<b>Radial Seal I. Air</b> (81083040084)..... <b>RS4549</b>	<b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b>	<b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b>
2180 <b>F-F Lube</b> (81055040032)..... <b>P235</b>	<b>Steering</b> (81473016005)..... <b>P106-HD</b>	<b>Steering</b> (81473016005)..... <b>P106-HD</b>
<b>B-P Lube</b> (81055040008)..... <b>P42</b>	<b>Urea</b> (81154036015)..... <b>PE5270</b>	<b>Urea</b> (81154036015)..... <b>PE5270</b>
<b>P. Fuel Ele.</b> (81125030011)..... <b>F950-F</b>		
<b>S. Fuel Ele.</b> (81125030042)..... <b>PF231</b>		
TGL 7220 w/D 0834 Eng. (09/08-on) <b>Lube</b> (51055006073)..... <b>P7196</b>	TGL 10290 w/D0836 Eng. (09/08-on) <b>Lube</b> (51055006073)..... <b>P7196</b>	TGM 12280 w/D 0836 Eng. (09/06-on) <b>Lube</b> (51055006073)..... <b>P7196</b>
<b>Fuel/Water Separator</b> (81125010022)..... <b>BF7881</b>	<b>Fuel/Water Separator</b> (81125010022)..... <b>BF7881</b>	<b>Fuel/Water Separator</b> (81125010022)..... <b>BF7881</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)
TGM 12280 w/D 0836 Eng. (09/06-on) (Cont'd) <b>Fuel/Water Separator</b> (Bio Diesel) (81125010032)..... <b>BF7881</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>414.3 mm Radial Seal Air</b> (81084050022)..... <b>RS5409</b> <b>457.2 mm Radial Seal Air</b> (81084050018)..... <b>RS5506</b> <b>Cab Air</b> (w/o Charcoal) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Charcoal) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>	TGM 15330 w/D 0836 Eng. (11/05-on) (Cont'd) <b>Fuel/Water Separator</b> (Bio Diesel) (81125010032)..... <b>BF7881</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>414.3 mm Radial Seal Air</b> (81084050022)..... <b>RS5409</b> <b>457.2 mm Radial Seal Air</b> (81084050018)..... <b>RS5506</b> <b>Cab Air</b> (w/o Charcoal) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Charcoal) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>	TGS 19360 w/w/D 2066 Eng. (02/11-on) (Cont'd) <b>Radial Seal O. Air</b> (81084050020)..... <b>RS4971</b> <b>Radial Seal I. Air</b> (81084050017)..... <b>RS5361</b> <b>Cab Air</b> (w/o Charcoal) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Charcoal) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>
TGL 12290 w/D 0836 Eng. (09/08-on) <b>Lube</b> (51055006073)..... <b>P7196</b> <b>Fuel/Water Separator</b> (81125010022)..... <b>BF7881</b> <b>Fuel/Water Separator</b> (Bio Diesel) (81125010032)..... <b>BF7881</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>414.3 mm Radial Seal Air</b> (81084050022)..... <b>RS5409</b> <b>457.2 mm Radial Seal Air</b> (81084050018)..... <b>RS5506</b> <b>Cab Air</b> (w/o Charcoal) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Charcoal) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>	TGM 15340 w/D 0836 Eng. (09/08-on) <b>Lube</b> (51055006073)..... <b>P7196</b> <b>Fuel/Water Separator</b> (81125010022)..... <b>BF7881</b> <b>Fuel/Water Separator</b> (Bio Diesel) (81125010032)..... <b>BF7881</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>414.3 mm Radial Seal Air</b> (81084050022)..... <b>RS5409</b> <b>457.2 mm Radial Seal Air</b> (81084050018)..... <b>RS5506</b> <b>Cab Air</b> (w/o Charcoal) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Charcoal) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>	TGS 19400 w/w/D 2066 Eng. (02/11-on) <b>Lube</b> (51055040108)..... <b>P7329</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>Radial Seal O. Air</b> (81084050020)..... <b>RS4971</b> <b>Radial Seal I. Air</b> (81084050017)..... <b>RS5361</b> <b>Cab Air</b> (w/o Charcoal) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Charcoal) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>
TGM 12290 w/D 0836 Eng. (09/08-on) <b>Lube</b> (51055006073)..... <b>P7196</b> <b>Fuel/Water Separator</b> (81125010022)..... <b>BF7881</b> <b>Fuel/Water Separator</b> (Bio Diesel) (81125010032)..... <b>BF7881</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>414.3 mm Radial Seal Air</b> (81084050022)..... <b>RS5409</b> <b>457.2 mm Radial Seal Air</b> (81084050018)..... <b>RS5506</b> <b>Cab Air</b> (w/o Charcoal) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Charcoal) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>	TGM 16290 w/D 0836 Eng. (09/08-on) <b>Lube</b> (51055006073)..... <b>P7196</b> <b>Fuel/Water Separator</b> (81125010022)..... <b>BF7881</b> <b>Fuel/Water Separator</b> (Bio Diesel) (81125010032)..... <b>BF7881</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>414.3 mm Radial Seal Air</b> (81084050022)..... <b>RS5409</b> <b>457.2 mm Radial Seal Air</b> (81084050018)..... <b>RS5506</b> <b>Cab Air</b> (w/o Charcoal) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Charcoal) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>	TGS 19440 w/w/D 2066 Eng. (02/11-on) <b>Lube</b> (51055040108)..... <b>P7329</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>Radial Seal O. Air</b> (81084050020)..... <b>RS4971</b> <b>Radial Seal I. Air</b> (81084050017)..... <b>RS5361</b> <b>Cab Air</b> (w/o Charcoal) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Charcoal) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>
TGM 15330 w/D 0836 Eng. (11/05-on) <b>Lube</b> (51055006073)..... <b>P7196</b> <b>Fuel/Water Separator</b> (81125010022)..... <b>BF7881</b>	TGS 19360 w/w/D 2066 Eng. (02/11-on) <b>Lube</b> (51055040108)..... <b>P7329</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b>	TGS 19480 w/w/D 2676 Eng. (02/11-on) <b>Lube</b> (51055040108)..... <b>P7329</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>Radial Seal O. Air</b> (81084050020)..... <b>RS4971</b> <b>Radial Seal I. Air</b> (81084050017)..... <b>RS5361</b> <b>Cab Air</b> (w/o Charcoal) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Charcoal) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>
TGM 22240 w/D 0836 Eng. (11/05-on) <b>Lube</b> (51055006073)..... <b>P7196</b> <b>Fuel/Water Separator</b> (81125010022)..... <b>BF7881</b>		

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)
<b>TGM 22240 w/D 0836 Eng. (11/05-on) (Cont'd)</b> <b>Fuel/Water Separator</b> (Bio Diesel) (81125010032)..... <b>BF7881</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>414.3 mm Radial Seal Air</b> (81084050022)..... <b>RS5409</b> <b>457.2 mm Radial Seal Air</b> (81084050018)..... <b>RS5506</b> <b>Cab Air</b> (w/o Charcoal) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Charcoal) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>	<b>TGM 22290 w/D 0836 Eng. (06/09-on) (Cont'd)</b> <b>Fuel/Water Separator</b> (Bio Diesel) (81125010032)..... <b>BF7881</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>414.3 mm Radial Seal Air</b> (81084050022)..... <b>RS5409</b> <b>457.2 mm Radial Seal Air</b> (81084050018)..... <b>RS5506</b> <b>Cab Air</b> (w/o Charcoal) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Charcoal) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>	<b>TGX 24.520 w/D3876 (Euro 6) Eng. (08/14-on)</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>Radial Seal O. Air</b> (81084050033)..... <b>RS4971</b> <b>Radial Seal I. Air</b> (81084050017)..... <b>RS5361</b> <b>Cab Air</b> (w/o Charcoal) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Charcoal) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b> <b>Trans. (ZF Gearbox)</b> (81332150002)..... <b>PT8385</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>
<b>TGM 22250 w/D 0836 Eng. (02/09-on)</b> <b>Lube</b> (51055006073)..... <b>P7196</b> <b>Fuel/Water Separator</b> (81125010022)..... <b>BF7881</b> <b>Fuel/Water Separator</b> (Bio Diesel) (81125010032)..... <b>BF7881</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>414.3 mm Radial Seal Air</b> (81084050022)..... <b>RS5409</b> <b>457.2 mm Radial Seal Air</b> (81084050018)..... <b>RS5506</b> <b>Cab Air</b> (w/o Charcoal) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Charcoal) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>	<b>TGS 50480 w/D 2676 (Euro 6) Eng. (09/08-on)</b> <b>Lube</b> (51055040108)..... <b>P7329</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>Radial Seal O. Air</b> (81084050020)..... <b>RS4971</b> <b>Radial Seal I. Air</b> (81084050017)..... <b>RS5361</b> <b>Cab Air</b> (w/o Charcoal) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Charcoal) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>	<b>TGX 24.560 w/D3876 (Euro 6) Eng. (08/14-on)</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>Radial Seal O. Air</b> (81084050033)..... <b>RS4971</b> <b>Radial Seal I. Air</b> (81084050017)..... <b>RS5361</b> <b>Cab Air</b> (w/o Charcoal) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Charcoal) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b> <b>Trans. (ZF Gearbox)</b> (81332150002)..... <b>PT8385</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>
<b>TGM 22280 w/D 0836 Eng. (09/06-on)</b> <b>Lube</b> (51055006073)..... <b>P7196</b> <b>Fuel/Water Separator</b> (81125010022)..... <b>BF7881</b> <b>Fuel/Water Separator</b> (Bio Diesel) (81125010032)..... <b>BF7881</b> <b>P. Fuel</b> (51125030063)..... <b>PF7935</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>414.3 mm Radial Seal Air</b> (81084050022)..... <b>RS5409</b> <b>457.2 mm Radial Seal Air</b> (81084050018)..... <b>RS5506</b> <b>Cab Air</b> (w/o Charcoal) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Charcoal) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>	<b>TGX 18.520 w/D3876 (Euro 6) Eng. (08/14-on)</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>Radial Seal O. Air</b> (81084050033)..... <b>RS4971</b> <b>Radial Seal I. Air</b> (81084050017)..... <b>RS5361</b> <b>Cab Air</b> (w/o Charcoal) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Charcoal) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b> <b>Trans. (ZF Gearbox)</b> (81332150002)..... <b>PT8385</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>	<b>TGX 26.520 w/D3876 (Euro 6) Eng. (08/14-on)</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>Radial Seal O. Air</b> (81084050033)..... <b>RS4971</b> <b>Radial Seal I. Air</b> (81084050017)..... <b>RS5361</b> <b>Cab Air</b> (w/o Charcoal) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Charcoal) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b> <b>Trans. (ZF Gearbox)</b> (81332150002)..... <b>PT8385</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>
<b>TGM 22290 w/D 0836 Eng. (06/09-on)</b> <b>Lube</b> (51055006073)..... <b>P7196</b> <b>Fuel/Water Separator</b> (81125010022)..... <b>BF7881</b>	<b>TGX 18.560 w/D3876 (Euro 6) Eng. (08/14-on)</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>Radial Seal O. Air</b> (81084050033)..... <b>RS4971</b> <b>Radial Seal I. Air</b> (81084050017)..... <b>RS5361</b> <b>Cab Air</b> (w/o Charcoal) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Charcoal) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b> <b>Trans. (ZF Gearbox)</b> (81332150002)..... <b>PT8385</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>	<b>TGX 26.560 w/D3876 (Euro 6) Eng. (08/14-on)</b> <b>S. Fuel</b> (51125030062)..... <b>PF7939</b> <b>Radial Seal O. Air</b> (81084050033)..... <b>RS4971</b> <b>Radial Seal I. Air</b> (81084050017)..... <b>RS5361</b> <b>Cab Air</b> (w/o Charcoal) (81619100018)..... <b>PA4955</b> <b>Cab Air</b> (w/Charcoal) (81619100019)..... <b>PA5477</b> <b>Air Dryer</b> (81521086025)..... <b>BA5379 +</b> <b>Trans. (ZF Gearbox)</b> (81332150002)..... <b>PT8385</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Urea</b> (81154036015)..... <b>PE5270</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)	M.A.N. European Trucks (cont'd)
TGX 28.520 w/D3876 (Euro 6) Eng. (08/14-on) S. Fuel (51125030062)..... PF7939 Radial Seal O. Air (81084050033)..... RS4971 Radial Seal I. Air (81084050017). RS5361 Cab Air (w/o Charcoal) (81619100018)..... PA4955 Cab Air (w/Charcoal) (81619100019)..... PA5477 Air Dryer (81521086025)..... BA5379 + Trans. (ZF Gearbox) (81332150002)..... PT8385 Steering (81473016005)..... P106-HD Urea (81154036015)..... PE5270	TGX 33.640 w/D3876 (Euro 6) Eng. (08/14-on) S. Fuel (51125030062)..... PF7939 Radial Seal O. Air (81084050033)..... RS4971 Radial Seal I. Air (81084050017). RS5361 Cab Air (w/o Charcoal) (81619100018)..... PA4955 Cab Air (w/Charcoal) (81619100019)..... PA5477 Air Dryer (81521086025)..... BA5379 + Trans. (ZF Gearbox) (81332150002)..... PT8385 Steering (81473016005)..... P106-HD Urea (81154036015)..... PE5270	TGX 41.520 w/D3876 (Euro 6) Eng. (08/14-on) S. Fuel (51125030062)..... PF7939 Radial Seal O. Air (81084050033)..... RS4971 Radial Seal I. Air (81084050017). RS5361 Cab Air (w/o Charcoal) (81619100018)..... PA4955 Cab Air (w/Charcoal) (81619100019)..... PA5477 Air Dryer (81521086025)..... BA5379 + Trans. (ZF Gearbox) (81332150002)..... PT8385 Steering (81473016005)..... P106-HD Urea (81154036015)..... PE5270
TGX 28.560 w/D3876 (Euro 6) Eng. (08/14-on) S. Fuel (51125030062)..... PF7939 Radial Seal O. Air (81084050033)..... RS4971 Radial Seal I. Air (81084050017). RS5361 Cab Air (w/o Charcoal) (81619100018)..... PA4955 Cab Air (w/Charcoal) (81619100019)..... PA5477 Air Dryer (81521086025)..... BA5379 + Trans. (ZF Gearbox) (81332150002)..... PT8385 Steering (81473016005)..... P106-HD Urea (81154036015)..... PE5270	TGX 35.520 w/D3876 (Euro 6) Eng. (08/14-on) S. Fuel (51125030062)..... PF7939 Radial Seal O. Air (81084050033)..... RS4971 Radial Seal I. Air (81084050017). RS5361 Cab Air (w/o Charcoal) (81619100018)..... PA4955 Cab Air (w/Charcoal) (81619100019)..... PA5477 Air Dryer (81521086025)..... BA5379 + Trans. (ZF Gearbox) (81332150002)..... PT8385 Steering (81473016005)..... P106-HD Urea (81154036015)..... PE5270	TGX 41.560 w/D3876 (Euro 6) Eng. (08/14-on) S. Fuel (51125030062)..... PF7939 Radial Seal O. Air (81084050033)..... RS4971 Radial Seal I. Air (81084050017). RS5361 Cab Air (w/o Charcoal) (81619100018)..... PA4955 Cab Air (w/Charcoal) (81619100019)..... PA5477 Air Dryer (81521086025)..... BA5379 + Trans. (ZF Gearbox) (81332150002)..... PT8385 Steering (81473016005)..... P106-HD Urea (81154036015)..... PE5270
TGX 33.520 w/D3876 (Euro 6) Eng. (08/14-on) S. Fuel (51125030062)..... PF7939 Radial Seal O. Air (81084050033)..... RS4971 Radial Seal I. Air (81084050017). RS5361 Cab Air (w/o Charcoal) (81619100018)..... PA4955 Cab Air (w/Charcoal) (81619100019)..... PA5477 Air Dryer (81521086025)..... BA5379 + Trans. (ZF Gearbox) (81332150002)..... PT8385 Steering (81473016005)..... P106-HD Urea (81154036015)..... PE5270	TGX 35.560 w/D3876 (Euro 6) Eng. (08/14-on) S. Fuel (51125030062)..... PF7939 Radial Seal O. Air (81084050033)..... RS4971 Radial Seal I. Air (81084050017). RS5361 Cab Air (w/o Charcoal) (81619100018)..... PA4955 Cab Air (w/Charcoal) (81619100019)..... PA5477 Air Dryer (81521086025)..... BA5379 + Trans. (ZF Gearbox) (81332150002)..... PT8385 Steering (81473016005)..... P106-HD Urea (81154036015)..... PE5270	TGX 41.640 w/D3876 (Euro 6) Eng. (08/14-on) S. Fuel (51125030062)..... PF7939 Radial Seal O. Air (81084050033)..... RS4971 Radial Seal I. Air (81084050017). RS5361 Cab Air (w/o Charcoal) (81619100018)..... PA4955 Cab Air (w/Charcoal) (81619100019)..... PA5477 Air Dryer (81521086025)..... BA5379 + Trans. (ZF Gearbox) (81332150002)..... PT8385 Steering (81473016005)..... P106-HD Urea (81154036015)..... PE5270
TGX 33.560 w/D3876 (Euro 6) Eng. (08/14-on) S. Fuel (51125030062)..... PF7939 Radial Seal O. Air (81084050033)..... RS4971 Radial Seal I. Air (81084050017). RS5361 Cab Air (w/o Charcoal) (81619100018)..... PA4955 Cab Air (w/Charcoal) (81619100019)..... PA5477 Air Dryer (81521086025)..... BA5379 + Trans. (ZF Gearbox) (81332150002)..... PT8385 Steering (81473016005)..... P106-HD Urea (81154036015)..... PE5270	TGX 35.640 w/D3876 (Euro 6) Eng. (08/14-on) S. Fuel (51125030062)..... PF7939 Radial Seal O. Air (81084050033)..... RS4971 Radial Seal I. Air (81084050017). RS5361 Cab Air (w/o Charcoal) (81619100018)..... PA4955 Cab Air (w/Charcoal) (81619100019)..... PA5477 Air Dryer (81521086025)..... BA5379 + Trans. (ZF Gearbox) (81332150002)..... PT8385 Steering (81473016005)..... P106-HD Urea (81154036015)..... PE5270	<b>M.A.N. Mexican Trucks</b> TGS 26.480 w/D2676 Eng. Lube (51055040107)..... P7329 Pre-Fuel (51125030062)..... PF7939 Fuel (51125030063)..... PF7935 Radial Seal O. Air (81084050016)..... RS4971 Radial Seal I. Air (81084050017). RS5361
		TGX 26.480 w/D2676 Eng. Lube (51055040107)..... P7329 Pre-Fuel (51125030062)..... PF7939 Fuel (51125030063)..... PF7935 Radial Seal O. Air (81084050016)..... RS4971 Radial Seal I. Air (81084050017). RS5361

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MACDONALD JOHNSTON Sweepers	MACK Diesel Engines (cont'd)	MACK Diesel Engines (cont'd)
600 LT Series w/Hino Eng. Lube (156072051)..... <b>B7155</b> Fuel (234011510)..... <b>BF7967</b>	AC460P (Cont'd) S. Fuel (483GB476M)..... <b>BF7773</b> S. Fuel (483GB471M)..... <b>BF7657</b> Breather..... <b>CLN&amp;R</b>	E9-400, E9-450, E9-500 Fuel/Water Separator (483GB433B)..... <b>BF1219 +</b> ESI-Plus Service Kit (6 Spin-ons) <b>BK6710</b> Service Kit (5 Spin-ons + B-P Spinner)..... <b>BK6720</b>
600 LT Series w/Perkins Eng. Lube (2654403)..... <b>BT216 +</b> Fuel (To 3/00) (26561117)..... <b>BF825 +</b> I. Air (3/00-on) (61026-3)..... <b>PA2419</b>	AI (11.9L), AMI (11.9L) F-F Lube (485GB3236)..... <b>[2] B7225 +</b> B-P Lube Spinner (To 11/11/03) (236GB41M)..... <b>BC7228</b> B-P Lube Spinner (11/11/03-on) (236GB42M)..... <b>BC7242</b>	E9-440 Fuel/Water Separator (483GB433B)..... <b>BF1219 +</b> Std. Service Kit (5 Spin-ons)..... <b>BK6700</b>
605 LT Series w/Hino Eng. Lube (156072051)..... <b>B7155</b> Fuel (234011510)..... <b>BF7967</b>	Opt. Fuel/Water Separator (483GB477M)..... <b>BF1286</b> P. Fuel (483GB470AM)..... <b>BF7656</b> S. Fuel (483GB471M)..... <b>BF7657</b> Crankcase Breather..... <b>CLN&amp;R</b>	EM6-237, EM6-237R, E6-250, EM6-250, EMC6-250, EMC6-250L, EM6-250R, E6-275, EM6-275 Fuel/Water Separator (483GB433B)..... <b>BF1219 +</b> ESI-Plus Service Kit (6 Spin-ons) <b>BK6710</b> Service Kit (5 Spin-ons + B-P Spinner)..... <b>BK6720</b>
605 LT Series w/Perkins Eng. Lube (2654403)..... <b>BT216 +</b> Fuel (To 3/00) (26561117)..... <b>BF825 +</b> I. Air (3/00-on) (61026-3)..... <b>PA2419</b>	DM, MR w/Manual Transmission B-P Lube Spinner (236GB41M).. <b>BC7228</b>	EM6-275L, EM6-275M, EM6-285, EMC6-285, EM6-285R, EMC6-285R, EM6-300, EM6-300R, EM6-300T Fuel/Water Separator (483GB433B)..... <b>BF1219 +</b> ESI-Plus Service Kit (6 Spin-ons) <b>BK6710</b> Service Kit (5 Spin-ons + B-P Spinner)..... <b>BK6720</b>
Compact Sweeper w/Johnston Turbo Eng. I. Air (75695/3)..... <b>PA2689</b> Hyd. (Return) (Fleetguard HF6173)..... <b>BT366-10</b>	E4-210, EZ4-210 Scania Lube..... <b>B163</b> Fuel/Water Separator (483GB433B)..... <b>BF1219 +</b> P. Fuel..... <b>BF877 +</b> S. Fuel..... <b>BF876</b>	END465 Series Fuel Ele..... <b>PF826</b>
VT Series w/Hino Eng. Lube (156072051)..... <b>B7155</b> Fuel (234011510)..... <b>BF7967</b>	E5 Series Lube (5000133555)..... <b>B76 +</b> Severe Service F-F Lube (5000133555)..... <b>B76-SS +</b> P. Fuel (5000541768)..... <b>BF877 +</b> S. Fuel (5000133546)..... <b>BF876</b> Coolant (5000133551)..... <b>BW5178</b>	END475 Scania Fuel Ele. (237GB13)..... <b>PF819</b>
<b>MACDONALD JOHNSTON Trash Loaders</b>	E6-200 Fuel/Water Separator (483GB433B)..... <b>BF1219 +</b> ESI-Plus Service Kit (6 Spin-ons) <b>BK6710</b>	END673, END673A, END673B, END673C, END673D, END673P, ENDT673, ENDT673A, ENDT673B, ENDT673C, ENDLT673 F-F Lube Ele. (To 1961)..... <b>[2] P194 +</b> Dual-Flow Lube Ele. (1961-71).... <b>P706-M</b> B-P Lube (To 1961, (500 Size)).... <b>C704-L +</b> B-P Lube Ele. (To 1961, (750 Size))..... <b>C750-E +</b>
MKIII Hyd. (Pressure) (SL-H-009/2)..... <b>PT8955-MPG</b> Hyd. (Return) (TXW3E-GDL10).... <b>PT9479-MPG</b>	E6-315, E6-350, E6-350R, EC6-350, EC6-350R Fuel/Water Separator (483GB433B)..... <b>BF1219 +</b> ESI-Plus Service Kit (6 Spin-ons) <b>BK6710</b> Service Kit (5 Spin-ons + B-P Spinner)..... <b>BK6720</b>	Fuel/Water Separator (483GB433B)..... <b>BF1219 +</b> Fuel (w/APE Fuel Pump)..... <b>PF819</b> Fuel (w/PSJ, PSM Fuel Pump).... <b>PF826</b> Std. Service Kit (1972-on, (5 Spin-ons))..... <b>BK6700</b>
MKIV Hyd. (Return) (TXW3E-GDL10).... <b>PT9479-MPG</b>	E7 (11.9L) F-F Lube (485GB3232)..... <b>[2] B7225 +</b> B-P Lube Spinner (485GB4363M)..... <b>BC7228</b> S. Fuel (483GB476M)..... <b>BF7773</b>	END673E, ET673, ETAZ673A, ETAZB673A, ETB673 Fuel/Water Separator (483GB433B)..... <b>BF1219 +</b> Air (Don. P130774)..... <b>PA2439</b> Air (Don. P130775)..... <b>PA2438</b> Air (2MD3129)..... <b>PA2312</b> Air (2MD4003)..... <b>PA2482</b> Air (2MD455-AP2)..... <b>PA1681-FN</b> Air (2MD473P1)..... <b>PA2317 +</b> Std. Service Kit (5 Spin-ons)..... <b>BK6700</b> ESI-Plus Service Kit (1977-on, (6 Spin-ons))..... <b>BK6710</b>
Sport Gen V Hyd. (Return) (TXW3E-GDL10).... <b>PT9479-MPG</b>	E7-250, EM7-275, E7-300, EM7-300, E7-350, E7-400 Fuel/Water Separator (483GB433B)..... <b>BF1219 +</b> Service Kit (5 Spin-ons + B-P Spinner)..... <b>BK6723</b>	
<b>MACK Diesel Engines</b>	E7-EUP Fuel/Water Separator (483GB472M)..... <b>BF1256</b> P. Fuel (483GB470M)..... <b>BF7656</b> S. Fuel (483GB471M)..... <b>BF7657</b>	
ASET AC Series (S/N 300079-up) (12.0L) F-F Lube (485GB3236)..... <b>[2] B7225 +</b> B-P Lube Spinner (8/19/03-on) (236GB42M)..... <b>BC7242</b> Opt. Fuel/Water Separator (483GB477M)..... <b>BF1286</b> 9 31/32 In. P. Fuel/Water Separator (483GB472M)..... <b>BF1256</b> 7 19/32 In. P. Fuel (483GB470AM)..... <b>BF7656</b> 7 19/32 In. S. Fuel (483GB476M)..... <b>BF7773</b> 10 7/16 In. S. Fuel (483GB471M)..... <b>BF7657</b> Crankcase Breather..... <b>CLN&amp;R</b>		
AC460P F-F Lube (485GB3236)..... <b>[2] B7225 +</b> B-P Lube Spinner (To 11/11/03) (57GC2206)..... <b>BC7228</b> B-P Lube Spinner (11/11/03-on) (57GC2231)..... <b>BC7242</b> Opt. Fuel/Water Separator (483GB477M)..... <b>BF1286</b> P. Fuel..... <b>CLN&amp;R</b> P. Fuel (483GB470AM)..... <b>BF7656</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MACK Diesel Engines (cont'd)	MACK Diesel Engines (cont'd)	MACK Diesel Engines (cont'd)
END675 Series	ENDT866, ENDT866C (Cont'd)	MP10 (16.1L)
F-F Lube Ele. (To 1961)..... [2] P194 +	Coolant (25MF435)..... BW5178	F-F Lube (20539275)..... [2] B76 +
Dual-Flow Lube Ele. (1961-71)... P706-M	Std. Service Kit (1972-on, (5 Spin-ons))..... BK6700	B-P Lube (20843764)..... B7409
B-P Lube (To 1961, (500 Size))... C704-L +	ENDTB675, ENDTB676	Fuel/Water Separator (21017305)..... BF1386-O
B-P Lube Ele. (To 1961, (750 Size))..... C750-E +	Fuel/Water Separator (483GB433B)..... BF1219 +	Fuel (20972295)..... BF7943
Fuel Ele. (237GB13)..... PF819	Air (Don. P130774)..... PA2439	Fuel (20539582)..... BF7814
Fuel Ele. (237GB29)..... PF826	Air (Don. P130775)..... PA2438	Fuel (22094967)..... BF46117
Fuel Ele. (483GB215)..... PF828	Air (2MD3129)..... PA2312	Coolant (w/o Chemical) (20575545)..... B5091
END711, END711B, ENDL711, END864, ENDT864, ENDT864A, ENDTB865	Air (2MD4003)..... PA2482	Coolant (w/Chemical) (20539991)..... BW5183
Dual-Flow Lube Ele. (1962-71)... P706-M	Air (2MD455-AP2)..... PA1681-FN	Diesel Exhaust Fluid (21496421) PE17000
Fuel/Water Separator (483GB433B)..... BF1219 +	Air (2MD473P1)..... PA2317 +	Maxidyne 300
Fuel Ele. (237GB13)..... PF819	ESI-Plus Service Kit (1977-on, (6 Spin-ons))..... BK6710	Lube Spin-on (485GB3191B)..... B76 +
Fuel Ele. (237GB29)..... PF826	ETZ475	Fuel/Water Separator (483GB433B)..... BF1219 +
Air (2MD3129)..... PA2312	P. Fuel (483GB219A)..... BF877 +	P. Fuel Spin-on (483GB219)..... BF877 +
Air (2MD4003)..... PA2482	S. Fuel (483GB218C)..... BF876	S. Fuel Spin-on (483GB218C)..... BF876
Air (2MD455-AP2)..... PA1681-FN	Turbocharger (6432PER17)..... B163	Coolant..... BW5179
Service Kit (1972-on, (5 Spin-ons))..... BK6700	ETZ477	
ENDT475	Lube Spin-on..... B163	<b>MACK Gas Engines</b>
Fuel/Water Separator (483GB433B)..... BF1219 +	P. Fuel Spin-on..... BF877 +	EN291, Magnadyne EN291, EN331, Magnadyne EN331
P. Fuel Spin-on (483GB219A)..... BF877 +	S. Fuel Spin-on..... BF876	Lube..... P41
S. Fuel Spin-on (483GB218C)..... BF876	Air (Don. P116918)..... PA2317 +	EN414
Coolant Spin-on (25MF435)..... BW5178	Air (2MD3129)..... PA2312	F-F Lube..... P82
Turbocharger (6432PER17)..... B163	Air (2MD4003)..... PA2482	B-P Lube..... P41
ENDT675, ENDT676	MP7 (10.8L)	Fuel Ele..... PF827
Fuel/Water Separator (483GB433B)..... BF1219 +	F-F Lube (20539275)..... [2] B76 +	Air (3076-145756)..... PA671-1
Air (Don. P130774)..... PA2439	B-P Lube Spinner (20552379)..... BC7242	ENF377
Air (Don. P130775)..... PA2438	B-P Lube Spin-on (20843764)..... B7409	Lube Ele..... P41
Air (2MD3129)..... PA2312	Fuel/Water Separator (21017305)..... BF1386-O	<b>MACK Spin-on Kits</b>
Air (2MD4003)..... PA2482	Fuel/Water Separator (w/Drain & Sensor Port) (20539578)..... BF1384-SP	BK6185
Air (2MD455-AP2)..... PA1681-FN	Fuel (20539582)..... BF7814	F-F Lube..... [2] B7225 +
Air (2MD473P1)..... PA2317 +	Fuel (20972295)..... BF7943	B-P Lube Spinner..... BC7242
Service Kit (1972-on, (5 Spin-ons))..... BK6700	Fuel (22094967)..... BF46117	P. Fuel..... BF7656
ENDT865, ENDT865C, ENDDT865	Coolant (w/o Chemical) (20575545)..... B5091	S. Fuel..... BF7773
Dual-Flow Lube Ele. (1961-71)... P706-M	Coolant (w/Chemical) (20539991)..... BW5183	Coolant..... BW5178
Fuel/Water Separator (483GB433B)..... BF1219 +	Diesel Exhaust Fluid (21496421) PE17000	BK6613
Air (Don. P130774)..... PA2439	MP8 (12.8L)	F-F Lube..... [2] B76 +
Air (Don. P130775)..... PA2438	F-F Lube (20539275)..... [2] B76 +	B-P Lube Spinner..... BC7242
Air (2MD3129)..... PA2312	B-P Lube Spinner (20552379)..... BC7242	P. Fuel..... BF7656
Air (2MD4003)..... PA2482	B-P Lube Spin-on (20843764)..... B7409	S. Fuel..... BF7657
Air (2MD455-AP2)..... PA1681-FN	Fuel/Water Separator (21017305)..... BF1386-O	BK6658
Air (2MD473P1)..... PA2317 +	Fuel/Water Separator (w/Drain & Sensor Port) (20539578)..... BF1384-SP	F-F Lube..... [2] B7225 +
Service Kit (1972-on, (5 Spin-ons))..... BK6700	Fuel (20539582)..... BF7814	B-P Lube Spinner..... BC7242
ENDT866, ENDT866C	Fuel (20972295)..... BF7943	P. Fuel/Water Separator..... BF1256
B-P Lube Ele. (237GB27)..... C750-E +	Fuel (22094967)..... BF46117	S. Fuel..... BF7657
B-P Lube Spin-on (485GB3191B)..... [2] B76 +	Coolant (w/Chemical) (20539991)..... BW5183	BK6659
Fuel/Water Separator (483GB433B)..... BF1219 +	Diesel Exhaust Fluid (21496421) PE17000	F-F Lube..... [2] B7225 +
Fuel Ele. (237GB29A)..... PF826		B-P Lube Spinner..... BC7242
Fuel Ele. (237GB13)..... PF819		P. Fuel/Water Separator..... BF1256
P. Fuel Spin-on (483GB219A)..... BF877 +		S. Fuel..... BF7773
S. Fuel Spin-on (483GB218C)..... BF876		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



MACK Spin-on Kits (cont'd)	MACK Spin-on Kits (cont'd)	MACK Trucks (cont'd)
BK6665	BK6722	Anthem w/MP7 (10.8L) Eng. (2018) (Cont'd)
F-F Lube..... [2] B7225 +	Lube..... [2] B76 +	Steering (349619)..... P106-HD
B-P Lube Spinner..... BC7242	B-P Lube Spinner..... BC110	Opt. Rear Axle (Meritor
P. Fuel..... BF7656	P. Fuel..... BF877 +	3280V9394)..... B233
Fuel..... BF7773	S. Fuel..... BF876	<b>Diesel Exhaust Fluid (82269261) PE17001</b>
BK6693	Coolant..... BW5178	Anthem w/MP7 (10.8L) Eng. (2019)
Lube..... [2] B7225 +	BK6723	F-F Lube (21707136)..... [2] B76 +
B-P Lube Spinner..... BC7242	Lube..... [2] B76 +	B-P Lube (21707135)..... B7409
P. Fuel..... BF7656	B-P Lube Spinner..... BC110	<b>Severe Service F-F Lube</b>
S. Fuel..... BF7657	P. Fuel..... BF877 +	(21707136)..... [2] B76-SS +
BK6694	S. Fuel..... BF976	<b>Fuel/Water Separator</b>
Lube..... [2] B76 +	Coolant..... BW5178	(22094987)..... BF46182-O
B-P Lube Spinner..... BC7173	BK6780	Fuel (22094967)..... BF46117
P. Fuel..... BF7656	Air..... PA2438	<b>Radial Seal Air (25100042)..... RS4634</b>
S. Fuel..... BF7657	Air..... PA2439	<b>Radial Seal XP Air (25100042)..... RS4634XP</b>
Coolant..... BW5178	Gasket..... [2] G25-AF	<b>Cab Air (85112361)..... PA30325</b>
BK6696	<b>MACK Trucks</b>	<b>Cab Air (85112361)..... PA30325</b>
Lube..... [2] B76 +	A20, B20, D20, A30, B30, D30 w/EN291, EN331	<b>Air Dryer (21620181)..... BA5379</b>
B-P Lube Spinner..... BC7173	Engs.	<b>Air Dryer (21620181)..... BA5379</b>
P. Fuel..... BF7656	Lube (236GB232)..... P41 +	<b>Steering (349619)..... P106-HD</b>
S. Fuel..... BF7657	Anthem w/Cummins ISX 11.9G (11.9L) Eng.	<b>Opt. Rear Axle (Meritor</b>
BK6700	(2019)	3280V8394)..... B233
Lube..... [2] B76 +	<b>Dual-Flow Lube (Fleetguard</b>	<b>Diesel Exhaust Fluid Strainer</b>
P. Fuel..... BF877 +	LF9080)..... BD50000	(82269261)..... PE17001
S. Fuel..... BF876	<b>Fuel/Water Separator</b>	<b>Diesel Exhaust Fluid Ele.</b>
Coolant..... BW5178	(Fleetguard NG5900)..... BF7695	(21516231)..... PE17000
BK6702	<b>Radial Seal Air (25100042)..... RS4634</b>	Anthem w/MP7 (10.8L) Eng. (2020)
Lube..... [2] B76 +	<b>Radial Seal XP Air (25100042)..... RS4634XP</b>	F-F Lube (21707136)..... [2] B76
P. Fuel..... BF877 +	<b>Cab Air (85112361)..... PA30325</b>	B-P Lube (21707135)..... B7409
S. Fuel..... BF976	<b>Air Dryer (21620181)..... BA5379</b>	<b>Severe Service F-F Lube</b>
BK6704	<b>Steering (349619)..... P106-HD</b>	(21707136)..... [2] B76-SS +
F-F Lube..... [2] B76 +	Anthem w/Cummins ISX 11.9G (11.9L) Eng.	<b>Fuel/Water Separator</b>
B-P Lube Spinner..... BC110	(2020)	(22094987)..... BF46182-O
P. Fuel..... BF7656	<b>Dual-Flow Lube (Fleetguard</b>	Fuel (22094967)..... BF46117
S. Fuel..... BF7657	LF14000NN)..... BD50000	<b>Radial Seal Air (25100042)..... RS4634</b>
Coolant..... BW5178	Fuel (Fleetguard NG5900)..... BF7695	<b>Radial Seal XP Air (25100042)..... RS4634XP</b>
BK6705	<b>Radial Seal Air (25100042)..... RS4634</b>	<b>Cab Air (85151124)..... PA30325</b>
F-F Lube..... [2] B76 +	<b>Radial Seal XP Air (25100042)..... RS4634XP</b>	<b>Air Dryer (Bendix 107796PG)..... BA5377</b>
B-P Lube Spinner..... BC110	<b>Cab Air (85151124)..... PA30325</b>	<b>Coolant (21937331)..... BW5183</b>
P. Fuel..... BF7656	<b>Opt. Rear Axle (Meritor</b>	<b>Trans. (2 In. Kit) (Allison</b>
S. Fuel..... BF7657	3280V8394)..... B233	29548987)..... PT9416-MPG KIT
BK6710	Anthem w/MP7 (10.8L) Eng. (2018)	<b>Trans. (4 In. Kit) (Allison</b>
Lube..... [3] B76 +	F-F Lube (21707136)..... [2] B76 +	29548988)..... PT9415-MPG KIT
P. Fuel..... BF877 +	B-P Lube (21707135)..... B7409	<b>Opt. Rear Axle (Meritor</b>
S. Fuel..... BF976	<b>Severe Service F-F Lube</b>	3280V8394)..... B233
Coolant..... BW5179	(21707136)..... [2] B76-SS +	Anthem w/MP7 (10.8L) Eng. (2021)
BK6720	<b>Fuel/Water Separator</b>	F-F Lube (21707136)..... [2] B76
Lube..... [2] B76 +	(22094987)..... BF46182-O	B-P Lube (21707135)..... B7409
B-P Lube Spinner..... BC110	Fuel (22094967)..... BF46117	Anthem w/MP8 (12.8L) Eng. (2018)
P. Fuel..... BF877 +	<b>Radial Seal Air (25100042)..... RS4634</b>	F-F Lube (21707136)..... [2] B76 +
S. Fuel..... BF976	<b>Radial Seal XP Air (25100042)..... RS4634XP</b>	B-P Lube (21707135)..... B7409
Coolant..... BW5179	<b>Cab Air (85151124)..... PA30325</b>	<b>Severe Service F-F Lube</b>
BK6721	<b>Air Dryer (21620181)..... BA5379 +</b>	(21707136)..... [2] B76-SS +
Lube..... [2] B76 +	<b>Coolant (21937331)..... BW5183</b>	<b>Fuel/Water Separator</b>
B-P Lube Spinner..... BC110	<b>Trans. (Fuller 4304827)..... BT223</b>	(22094987)..... BF46182-O
P. Fuel..... BF877 +		Fuel (22094967)..... BF46117
S. Fuel..... BF976		<b>Radial Seal Air (25100042)..... RS4634</b>
		<b>Radial Seal XP Air (25100042)..... RS4634XP</b>
		<b>Cab Air (85151124)..... PA30325</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MACK Trucks (cont'd)	MACK Trucks (cont'd)	MACK Trucks (cont'd)
Anthem w/MP8 (12.8L) Eng. (2018) (Cont'd)	B33, C33, C37, B41, C41, B43, B43S, B43X, C45, C49, B53, B61, B61T, H61, H61T, B63, H63, H63ST, H63T	CH w/Cummins L10 (10.0L) Eng.
Air Dryer (21620181)..... BA5379 +	F-F Lube Ele. (236GB123A)..... [2] P194 +	Dual-Flow Lube (3318853)..... BD103 +
Coolant (21937331)..... BW5183	B-P Lube Ele. (500 Size)..... C704-L	F-F Lube (Fleetguard LF670SC).. B196 +
Trans. Ele. (22038908)..... PT9417	B-P Lube Ele. (750 Size)..... C750-E +	B-P Lube (3304232)..... B7577
Trans. Spin-on (Fuller 4304827).. BT223	Fuel Ele. (237GB13)..... PF819	Fuel/Water Separator (3308638).. BF1212 +
Steering (349619)..... P106-HD	B65, B67, B67T, H67, B75, B81, B82S, B82SX, B83, B83SX, B85SX, B87SX	Fuel (154789)..... BF957-D +
Opt. Rear Axle (Meritor 3280V9394)..... B233	F-F Lube Ele. (236GB123A)..... [2] P194 +	Coolant (4 Units BTA PLUS) (3315116)..... BW5071
Diesel Exhaust Fluid (21516231) PE17000	B-P Lube Ele. (500 Size)..... C704-L	Coolant (15 Units BTA PLUS) (3318318)..... BW5075
Anthem w/MP8 (12.8L) Eng. (2019)	B-P Lube Ele. (750 Size)..... C750-E +	CH600 w/E7 (11.9L) Eng.
F-F Lube (21707136)..... [2] B76 +	Fuel Ele. (237GB13)..... PF819	F-F Lube (482GB3191)..... [2] B76 +
B-P Lube (21707135)..... B7409	Bigfoot w/Cat C16 Eng.	B-P Lube (236GB244)..... BC110
Severe Service F-F Lube (21707136)..... [2] B76-SS +	Lube (To 1/2004) (1R0716)..... B99 +	Fuel/Water Separator (483GB433B)..... BF1219 +
Fuel/Water Separator (21737481)..... PF7930	Lube (1/2004-on) (1R1808)..... B7299 +	P. Fuel (483GB444)..... BF877 +
Fuel (22094967)..... BF46117	Coolant (9N6123)..... BW5139	S. Fuel (483GB431)..... BF976
Radial Seal Air (25100042)..... RS4634	Bigfoot w/Cummins Signature 600 Eng.	S. Fuel (483GB441)..... BF876
Radial Seal XP Air (25100042).... RS4634XP	Dual-Flow Lube (Fleetguard LF9000)..... BD7153 +	Coolant (25MF428A)..... BW5178
Cab Air (85112361)..... PA30325	Opt. Dual-Flow Lube (Fleetguard LF9001)..... BD7154 +	Service Kit (57GC2120B)..... BK6723
Air Dryer (21620181)..... BA5379 +	Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... BD50000	CH600 w/EM7 (11.9L) Eng.
Coolant (21937331)..... BW5183	Bigfoot w/Cummins QSK19 Eng.	F-F Lube (485GB3191C)..... [2] B76 +
Trans. (Fuller 4304827)..... BT223	Dual-Flow Lube (3825970)..... [2] BD103 +	B-P Lube Spinner (57GC2134A).. BC110
Steering (349619)..... P106-HD	CF w/E6 (11.0L) Eng.	Opt. Fuel/Water Separator Ele. (301SD19B)..... PF7680
Opt. Rear Axle (Meritor 3280V8394)..... B233	Fuel/Water Separator (483GB433B)..... BF1219 +	Opt. Fuel/Water Separator Spin-on (483GB477M)..... BF1286
Diesel Exhaust Fluid Strainer (82269261)..... PE17001	CF w/EM6 (11.0L) Eng.	P. Fuel (483GB444)..... BF877 +
Diesel Exhaust Fluid Ele. (21516231)..... PE17000	Fuel/Water Separator (483GB433B)..... BF1219 +	S. Fuel (483GB440)..... BF976
Anthem w/MP8 (12.8L) Eng. (2020)	CF w/EM6-L (11.0L) Eng.	Air (57MD42M)..... PA2680
F-F Lube (21707136)..... [2] B76 +	Fuel/Water Separator (483GB433B)..... BF1219 +	Coolant (25MF435B)..... BW5178
B-P Lube (21707135)..... B7409	CH Series w/AC Aset Eng.	Opt. Trans. (Fuller 17237)..... B2 +
Severe Service F-F Lube (21707136)..... [2] B76-SS +	F-F Lube (485GB3236)..... B7225 +	Steering (5839-84365A)..... PT951 +
Fuel/Water Separator Ele. (21737481)..... PF7930	B-P Lube Spinner (57GC2231)... BC7242	Service Kit (215SB210)..... BK6721
Fuel/Water Separator Spin-on (22094987)..... BF46182-O	Fuel/Water Separator (483GB477M)..... BF1286	Service Kit (57GC2120C)..... BK6723
Fuel (22094967)..... BF46117	P. Fuel (483GB470M)..... BF7656	CH602 w/E7 310/330 E-Tech Eng.
Radial Seal Air (25100042)..... RS4634	S. Fuel (483GB476M)..... BF7773	F-F Lube (485GB3191B)..... [2] B76 +
Radial Seal XP Air (25100042).... RS4634XP	CH w/E6 (11.0L) Eng.	B-P Lube Spinner (485GB3219D)..... BC110
Cab Air (85151124)..... PA30325	Fuel/Water Separator (483GB433B)..... BF1219 +	B-P Lube Spinner (57GC2187)... BC7173
Air Dryer (Bendix 107796PG)..... BA5377	Trans. (Fuller 4304827)..... BT223	Opt. Fuel/Water Separator (483GB472M)..... BF1256
Coolant (w/o Chemical) (21937298)..... B5091	Opt. Trans. (Fuller 17237)..... B2 +	P. Fuel (483GB470M)..... BF7656
Coolant (w/Chemical) (21937331)..... BW5183	CH w/EM6-L (11.0L) Eng.	S. Fuel (483GB471M)..... BF7657
Opt. Trans. Spin-on (Fuller 17237)..... B2	Fuel/Water Separator (483GB433B)..... BF1219 +	Radial Seal Air (57MD320M)..... RS4634
Opt. Rear Axle (Meritor 3280V8394)..... B233	Trans. (Fuller 4304827)..... BT223	Radial Seal XP Air (57MD320M).. RS4634XP
Anthem w/MP8 (12.8L) Eng. (2021)	Opt. Trans. (Fuller 17237)..... B2 +	Coolant (25MF435B)..... BW5178
Lube (23155587)..... [2] B40153	CH w/EM6-L (11.0L) Eng.	Opt. Trans. (Fuller 17237)..... B2 +
Fuel/Water Separator (Fleetguard FS19764G)..... PF46091	Fuel/Water Separator (483GB433B)..... BF1219 +	Steering (5839-84365A)..... PT951 +
Fuel (23856895)..... BF46117	Trans. (Fuller 4304827)..... BT223	Service Kit (57GC2188A)..... BK6696
	Opt. Trans. (Fuller 17237)..... B2 +	Service Kit (57GC2177B)..... BK6704
		CH612 w/ASET AC Eng.
		F-F Lube (To 2004) (485GB3191B)..... [2] B76 +
		F-F Lube (2004-on) (485GB3236)..... [2] B7225 +
		B-P Lube Spinner (To 11/11/03) (57GC2206)..... BC7228

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>MACK Trucks (cont'd)</b>	<b>MACK Trucks (cont'd)</b>	<b>MACK Trucks (cont'd)</b>
CH612 w/ASET AC Eng. (Cont'd)	CH613 w/AC ASET Eng.	CH613 w/E7 Eng. (Cont'd)
B-P Lube Spinner (11/11/03-on) (57GC2231)..... <b>BC7242</b>	F-F Lube (485GB3236)..... <b>[2] B7225 +</b>	Axial Seal Air..... <b>PA2680</b>
Opt. Fuel/Water Separator Ele. (301SD19B)..... <b>PF7680</b>	B-P Lube Spinner (To 11/11/03) (57GC2206)..... <b>BC7228</b>	Radial Seal Air (57MD320M)..... <b>RS4634</b>
Opt. Fuel/Water Separator Spin-on (483GB477M)..... <b>BF1286</b>	B-P Lube Spinner (11/11/03-on) (57GC2231)..... <b>BC7242</b>	Radial Seal XP Air (57MD320M)..... <b>RS4634XP</b>
Opt. Fuel/Water Separator Spin-on (483GB472M)..... <b>BF1256</b>	Opt. Fuel/Water Separator Ele. (301SD19B)..... <b>PF7680</b>	Coalescing Breather (279GB43M)..... <b>BT9408</b>
P. Fuel (483GB470M)..... <b>BF7656</b>	Opt. Fuel/Water Separator Spin-on (483GB477M)..... <b>BF1286</b>	Coolant (25MF435B)..... <b>BW5178</b>
S. Fuel (483GB476M)..... <b>BF7773</b>	Opt. Fuel/Water Separator Spin-on (483GB472M)..... <b>BF1256</b>	Trans. Ele. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>
Radial Seal Air (57MD320M)..... <b>RS4634</b>	P. Fuel (483GB470AM)..... <b>BF7656</b>	Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>
Radial Seal XP Air (57MD320M)..... <b>RS4634XP</b>	S. Fuel (483GB476M)..... <b>BF7773</b>	Trans. Spin-on (Fuller 4304827).. <b>BT223</b>
Crankcase Breather..... <b>CLN&amp;R</b>	S. Fuel (483GB471M)..... <b>BF7657</b>	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>
Coolant (25MF435B)..... <b>BW5178</b>	Radial Seal Air (57MD320M)..... <b>RS4634</b>	Steering (5839-84365A)..... <b>PT951 +</b>
Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	Radial Seal XP Air (57MD320M)..... <b>RS4634XP</b>	Service Kit (57GC2245)..... <b>BK6653</b>
Steering (5839-84365A)..... <b>PT951 +</b>	Crankcase Breather..... <b>CLN&amp;R</b>	Service Kit..... <b>BK6665</b>
Service Kit..... <b>BK6653</b>	Coolant (25MF435B)..... <b>BW5178</b>	Service Kit..... <b>BK6185</b>
Service Kit..... <b>BK6665</b>	Trans. Ele. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	CHN600 w/AMI-300 Aset Eng.
Service Kit..... <b>BK6185</b>	Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	F-F Lube (485GB3236)..... <b>[2] B7225 +</b>
CH612 w/E7 E-Tech Eng.	Trans. Spin-on (Fuller 4304827).. <b>BT223</b>	B-P Lube Spinner (57GC2231)..... <b>BC7242</b>
F-F Lube (To 2004) (485GB3191B)..... <b>[2] B76 +</b>	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	Opt. Fuel/Water Separator (483GB472M)..... <b>BF1256</b>
F-F Lube (2004-on) (485GB3236)..... <b>[2] B7225 +</b>	Steering (5839-84365A)..... <b>PT951 +</b>	P. Fuel (483GB470M)..... <b>BF7656</b>
B-P Lube Spinner (57GC2134A)..... <b>BC110</b>	Service Kit (215SB330)..... <b>BK6662</b>	S. Fuel (483GB476M)..... <b>BF7773</b>
B-P Lube Spinner (57GC2187)..... <b>BC7173</b>	Service Kit..... <b>BK6665</b>	Radial Seal Air (57MD320M)..... <b>RS4634</b>
Opt. Fuel/Water Separator Spin-on (483GB472M)..... <b>BF1256</b>	Service Kit (215SB325A)..... <b>BK6693</b>	Radial Seal XP Air (57MD320M)..... <b>RS4634XP</b>
P. Fuel (483GB470M)..... <b>BF7656</b>	Service Kit..... <b>BK6185</b>	Crankcase Breather..... <b>CLN&amp;R</b>
S. Fuel (483GB471M)..... <b>BF7657</b>	CH613 w/AI ASET Eng.	Coolant (25MF435B)..... <b>BW5178</b>
Radial Seal Air (57MD320M)..... <b>RS4634</b>	Radial Seal Air (57MD320M)..... <b>RS4634</b>	Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
Radial Seal XP Air (57MD320M)..... <b>RS4634XP</b>	Radial Seal XP Air (57MD320M)..... <b>RS4634XP</b>	Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
Coolant (25MF435B)..... <b>BW5178</b>	Trans. (Fuller 4304827)..... <b>BT223</b>	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>
Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	Steering (5839-84365A)..... <b>PT951 +</b>	Steering (5839-84365A)..... <b>PT951 +</b>
Steering (5839-84365A)..... <b>PT951 +</b>	CH613 w/AMI ASET Eng.	Service Kit (215SB332)..... <b>BK6665</b>
Service Kit..... <b>BK6696</b>	F-F Lube (485GB3236)..... <b>[2] B7225 +</b>	CHN602, CHN603 w/ASET AC Series Eng.
Service Kit (57GC2177B)..... <b>BK6704</b>	B-P Lube Spinner (57GC2231)..... <b>BC7242</b>	F-F Lube (485GB3236)..... <b>[2] B7225 +</b>
Service Kit..... <b>BK6694</b>	P. Fuel (483GB470AM)..... <b>BF7656</b>	B-P Lube Spinner (To 11/11/03) (57GC2206)..... <b>BC7228</b>
CH612 w/EM7 E-Tech Eng.	S. Fuel (483GB471M)..... <b>BF7657</b>	B-P Lube Spinner (11/11/03-on) (57GC2231)..... <b>BC7242</b>
F-F Lube (485GB3191C)..... <b>[2] B76 +</b>	Radial Seal Air (57MD320M)..... <b>RS4634</b>	Opt. Fuel/Water Separator Ele. (301SD19B)..... <b>PF7680</b>
B-P Lube Spinner (57GC2187)..... <b>BC7173</b>	Radial Seal XP Air (57MD320M)..... <b>RS4634XP</b>	Opt. Fuel/Water Separator Spin-on (483GB477M)..... <b>BF1286</b>
Opt. Fuel/Water Separator (301SD19B)..... <b>PF7680</b>	Coolant (25MF435B)..... <b>BW5178</b>	Opt. Fuel/Water Separator Spin-on (483GB472M)..... <b>BF1256</b>
P. Fuel (483GB470M)..... <b>BF7656</b>	Trans. (Fuller 4304827)..... <b>BT223</b>	P. Fuel (483GB470AM)..... <b>BF7656</b>
S. Fuel (483GB471M)..... <b>BF7657</b>	Steering (5839-84365A)..... <b>PT951 +</b>	S. Fuel (483GB372M)..... <b>CLN&amp;R</b>
Radial Seal Air (57MD320M)..... <b>RS4634</b>	CH613 w/E7 Eng.	S. Fuel (483GB471M)..... <b>BF7657</b>
Radial Seal XP Air (57MD320M)..... <b>RS4634XP</b>	F-F Lube..... <b>[2] B76 +</b>	S. Fuel (483GB476M)..... <b>BF7773</b>
Coolant (25MF435B)..... <b>BW5178</b>	B-P Lube Spinner (485GB3219D)..... <b>BC110</b>	Radial Seal Air (57MD320M)..... <b>RS4634</b>
Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	Fuel/Water Separator (483GB477M)..... <b>BF1286</b>	Radial Seal XP Air (57MD320M)..... <b>RS4634XP</b>
Steering (Open Both Ends) (Fleetguard LF634)..... <b>PT903 +</b>	Opt. Fuel/Water Separator (483GB465)..... <b>BF1219 +</b>	Air Dryer (Bendix 107796)..... <b>BA5377</b>
Steering (Closed One End) (583983213F)..... <b>PT9449</b>	P. Fuel..... <b>BF877 +</b>	Crankcase Breather..... <b>CLN&amp;R</b>
Service Kit (57GC2188A)..... <b>BK6696</b>	P. Fuel (483GB470AM)..... <b>BF7656</b>	Coolant (25MF435B)..... <b>BW5178</b>
Service Kit..... <b>BK6694</b>	S. Fuel..... <b>BF976</b>	Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
	S. Fuel (483GB471M)..... <b>BF7657</b>	Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
	S. Fuel (483GB476M)..... <b>BF7773</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

**Trucks & Buses Applications** **BALDWIN FILTERS**

<b>MACK Trucks (cont'd)</b>	<b>MACK Trucks (cont'd)</b>	<b>MACK Trucks (cont'd)</b>
CHN602, CHN603 w/ASET AC Series Eng. (Cont'd) Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Steering (5839-84365A)..... <b>PT951 +</b> Service Kit..... <b>BK6658 90</b> Service Kit..... <b>BK6659</b> Service Kit (57GC2245)..... <b>BK6653</b> Service Kit (215SB325A)..... <b>BK6693</b> Service Kit..... <b>BK6185</b> Service Kit (215SB332)..... <b>BK6665</b> Service Kit (57GC2246)..... <b>BK6662</b>	CHN613 w/AC Series ASET Eng. (Cont'd) <b>B-P Lube Spinner</b> (11/11/03-on) (57GC2231)..... <b>BC7242</b> Opt. Fuel/Water Separator Ele. (301SD19B)..... <b>PF7680</b> Opt. Fuel/Water Separator Spin-on (483GB477M)..... <b>BF1286</b> Opt. Fuel/Water Separator Spin-on (483GB472M)..... <b>BF1256</b> P. Fuel (483GB470AM)..... <b>BF7656</b> P. Fuel (483GB372M)..... <b>CLN&amp;R</b> S. Fuel (483GB471M)..... <b>BF7657</b> S. Fuel (483GB476M)..... <b>BF7773</b> Radial Seal Air (57MD320M)..... <b>RS4634</b> Radial Seal XP Air (57MD320M)..... <b>RS4634XP</b> Air Dryer (Bendix 107796)..... <b>BA5377</b> Crankcase Breather (To 01/01/07)..... <b>CLN&amp;R</b> oil Coalescing Breather (1/07-on) (279GB43M)..... <b>BT9408</b> Coolant (25MF435B)..... <b>BW5178</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Steering (5839-84365A)..... <b>PT951 +</b> Service Kit (215SB330)..... <b>BK6662</b> Service Kit..... <b>BK6665</b> Service Kit (215SB325A)..... <b>BK6693</b> Service Kit..... <b>BK6185</b>	CHN613 w/AI ASET AI Eng. (Cont'd) Service Kit..... <b>BK6693</b> CHN613 w/E7 E-Tech Eng. F-F Lube (485GB3232)..... <b>[2] B7225 +</b> <b>B-P Lube Spinner</b> (57GC2231)..... <b>BC7242</b> Opt. Fuel/Water Separator Ele. (301SD19B)..... <b>PF7680</b> Opt. Fuel/Water Separator Spin-on (483GB472M)..... <b>BF1256</b> Opt. Fuel/Water Separator Spin-on (483GB477M)..... <b>BF1286</b> P. Fuel (483GB470AM)..... <b>BF7656</b> S. Fuel (483GB476M)..... <b>BF7773</b> Radial Seal Air (57MD320M)..... <b>RS4634</b> Radial Seal XP Air (57MD320M)..... <b>RS4634XP</b> Air Dryer (Bendix 107796)..... <b>BA5377</b> Coolant (25MF435B)..... <b>BW5178</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Steering (5839-84365A)..... <b>PT951 +</b> Service Kit..... <b>BK6665</b> Service Kit..... <b>BK6185</b> CHN613 w/MP8 Eng. F-F Lube (20539275)..... <b>[2] B76 +</b> <b>B-P Lube Spin-on</b> (20843764)..... <b>B7409</b> Fuel/Water Separator (21017305)..... <b>BF1386-O</b> Fuel (20972295)..... <b>BF7943</b> Radial Seal Air (57MD320M)..... <b>RS4634</b> Radial Seal XP Air (57MD320M)..... <b>RS4634XP</b> Air Dryer (Bendix 107796)..... <b>BA5377</b> Coolant (20575545)..... <b>B5091</b> Trans. Spin-on (Fuller 4304827)..... <b>BT223</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>
CHN612 w/ASET AC Eng. F-F Lube (485GB3236)..... <b>[2] B7225 +</b> <b>B-P Lube Spinner</b> (To 11/11/03) (57GC2206)..... <b>BC7228</b> <b>B-P Lube Spinner</b> (11/11/03-on) (57GC2231)..... <b>BC7242</b> Opt. Fuel/Water Separator Ele. (301SD19B)..... <b>PF7680</b> Opt. Fuel/Water Separator Spin-on (483GB472M)..... <b>BF1256</b> P. Fuel (483GB470AM)..... <b>BF7656</b> S. Fuel (483GB471M)..... <b>BF7657</b> Fuel Spin-on (483GB476M)..... <b>BF7773</b> Radial Seal Air (57MD320M)..... <b>RS4634</b> Radial Seal XP Air (57MD320M)..... <b>RS4634XP</b> Air Dryer (Bendix 107796)..... <b>BA5377</b> Crankcase Breather..... <b>CLN&amp;R</b> Coolant (25MF435B)..... <b>BW5178</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Steering (5839-84365A)..... <b>PT951 +</b> Service Kit..... <b>BK6658 90</b> Service Kit..... <b>BK6659</b> Service Kit (215SB325A)..... <b>BK6693</b>	CHN613 w/AI ASET AI Eng. F-F Lube (485GB3236)..... <b>[2] B7225 +</b> <b>B-P Lube Spinner</b> (To 11/11/03) (57GC2206)..... <b>BC7228</b> <b>B-P Lube Spinner</b> (11/11/03-on) (57GC2231)..... <b>BC7242</b> Opt. Fuel/Water Separator Ele. (301SD19B)..... <b>PF7680</b> Opt. Fuel/Water Separator Spin-on (483GB472M)..... <b>BF1256</b> Opt. Fuel/Water Separator Spin-on (483GB477M)..... <b>BF1286</b> P. Fuel (483GB470AM)..... <b>BF7656</b> S. Fuel (483GB471M)..... <b>BF7657</b> Radial Seal Air (57MD320M)..... <b>RS4634</b> Radial Seal XP Air (57MD320M)..... <b>RS4634XP</b> Air Dryer (Bendix 107796)..... <b>BA5377</b> Crankcase Breather..... <b>CLN&amp;R</b> Coolant (25MF435B)..... <b>BW5178</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Steering (5839-84365A)..... <b>PT951 +</b> Service Kit..... <b>BK6662</b>	CHU w/MP8 (12.8L) Eng. (To 2011) F-F Lube (20539275)..... <b>[2] B76 +</b> <b>B-P Lube Spinner</b> (20552379)..... <b>BC7242</b> Severe Service F-F Lube (20539275)..... <b>[2] B76-SS +</b> Fuel/Water Separator Ele. (Davco 382 System) (Fleetguard FS19765)..... <b>PF7930</b> Fuel/Water Separator Ele. (Remote Mtd.) (301-SD-19C)..... <b>PF7680</b> Fuel/Water Separator Spin-on (21380521)..... <b>BF1386-O</b> Fuel (20539582)..... <b>BF7814</b> Fuel (20972295)..... <b>BF7943</b> Radial Seal Air (57MD320M)..... <b>RS4634</b> Radial Seal XP Air (57MD320M)..... <b>RS4634XP</b> Cab Air (3543-H9638)..... <b>PA30277</b> Air Dryer (Bendix 65624)..... <b>BA5373</b> Air Dryer (Wabco R950011)..... <b>BA5374 +</b> Air Dryer (Wabco R950068)..... <b>BA5379 +</b> Air Dryer (85110799)..... <b>BA5592 90</b> Coolant (w/Chemical) (21937331)..... <b>BW5183</b> Coolant (w/o Chemical) (20575545)..... <b>B5091</b>
CHN612 w/ASET AI Eng. F-F Lube (485GB3236)..... <b>[2] B7225 +</b> <b>B-P Lube Spinner</b> (To 11/11/03) (57GC2206)..... <b>BC7228</b> <b>B-P Lube Spinner</b> (11/11/03-on) (57GC2231)..... <b>BC7242</b> Opt. Fuel/Water Separator (483GB472M)..... <b>BF1256</b> P. Fuel (483GB470AM)..... <b>BF7656</b> S. Fuel (483GB471M)..... <b>BF7657</b> Radial Seal Air (57MD320M)..... <b>RS4634</b> Radial Seal XP Air (57MD320M)..... <b>RS4634XP</b> Air Dryer (Bendix 107796)..... <b>BA5377</b> Crankcase Breather..... <b>CLN&amp;R</b> Coolant (25MF435B)..... <b>BW5178</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Steering (5839-84365A)..... <b>PT951 +</b> Service Kit..... <b>BK6658 90</b> Service Kit (215SB325A)..... <b>BK6693</b>	CHN613 w/AC Series ASET Eng. F-F Lube (485GB3236)..... <b>[2] B7225 +</b> <b>B-P Lube Spinner</b> (To 11/11/03) (57GC2206)..... <b>BC7228</b>	

+ See Product Guide for Variations of This Number. 90 Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MACK Trucks (cont'd)	MACK Trucks (cont'd)	MACK Trucks (cont'd)
CHU w/MP8 (12.8L) Eng. (To 2011) (Cont'd)	CHU602 w/MP8 Eng.	CHU612 w/MP8 Eng.
Trans. Ele. (2 In. Kit) (Allison 29540493).....	F-F Lube (20539275).....	F-F Lube (20539275).....
PT9416-MPG KIT	[2] B76 +	[2] B76 +
Trans. Ele. (4 In. Kit) (Allison 29540494).....	B-P Lube Spinner (20552379).....	B-P Lube (20843764).....
PT9415-MPG KIT	BC7242	B7409
Opt. Trans. Spin-on (Fuller 17237).....	Fuel/Water Separator (21017305).....	Severe Service F-F Lube (20539275).....
B2 +	BF1386-O	[2] B76-SS +
Trans. Spin-on (Fuller 4304827)..	Fuel (20539582).....	Fuel/Water Separator (21017305).....
BT223	BF7814	BF1386-O
2 23/32 In. Steering (5839-87904M).....	Radial Seal Air (57MD320M).....	Fuel (20972295).....
PT9354-MPG	RS4634	BF7943
3 31/32 In. Steering (349619).....	Radial Seal XP Air (57MD320M).....	Radial Seal Air (57MD320M).....
P106-HD	RS4634XP	RS4634
Diesel Exhaust Fluid Strainer (82269261).....	Air Dryer (Bendix 65624).....	Radial Seal XP Air (57MD320M).....
PE17001	BA5373	RS4634XP
Diesel Exhaust Fluid Pump (21516231).....	Coolant (w/Chemical) (20539991).....	Air Dryer (Wabco R950011).....
PE17000	BW5183	BA5374 +
CHU w/MP8 (12.8L) Eng. (2012-15)	Coolant (w/o Chemical) (20575545).....	Air Dryer (Bendix 65624).....
F-F Lube (21707136).....	B5091	BA5373
[2] B76 +	Trans. Ele. (2 In. Kit) (Allison 29540493).....	Trans. Ele. (2 In. Kit) (Allison 29540493).....
B-P Lube Spin-on (21707135).....	PT9416-MPG KIT	PT9416-MPG KIT
B7409	Trans. Ele. (4 In. Kit) (Allison 29540494).....	Trans. Ele. (4 In. Kit) (Allison 29540494).....
Severe Service F-F Lube (21707136).....	PT9415-MPG KIT	PT9415-MPG KIT
[2] B76-SS +	Opt. Trans. Spin-on (Fuller 17237).....	Trans. Spin-on (Fuller 4304827)..
Fuel/Water Separator Ele. (Davco 382 System) (Fleetguard FS19765).....	B2 +	BT223
PF7930	Steering (5839-87904M).....	Opt. Trans. Spin-on (Fuller 17237).....
Fuel/Water Separator Ele. (Remote Mtd.) (301-SD-19C).....	PT9354-MPG	B2 +
PF7680	CHU603 w/MP8 Eng.	PT9354-MPG
Fuel/Water Separator Ele. (Fleetguard FS19728).....	F-F Lube (20539275).....	CHU613 w/MP8 (12.8L) Eng. (2016-17)
PF7782	[2] B76 +	F-F Lube (21707136).....
Fuel/Water Separator Spin-on (21380521).....	B-P Lube Spinner (20552379).....	B-P Lube (21707135).....
BF1386-O	BC7242	B7409
Fuel (20539582).....	B-P Lube Spin-on (20843764).....	Severe Service F-F Lube (21707136).....
BF7814	B7409	[2] B76-SS +
Fuel (20972295).....	Fuel/Water Separator (21017305).....	Fuel/Water Separator Ele. (Davco 382 System) (Fleetguard FS19765).....
BF7943	BF1386-O	PF7930
Radial Seal Air (57MD320M).....	Fuel (20539582).....	Fuel/Water Separator Ele. (Fleetguard FS19728).....
RS4634	BF7814	PF7782
Radial Seal XP Air (57MD320M).....	Radial Seal Air (57MD320M).....	Fuel/Water Separator Spin-on (21380521).....
RS4634XP	RS4634	BF1386-O
Cab Air (3543-H9638).....	Radial Seal XP Air (57MD320M).....	Fuel (20972295).....
PA30277	RS4634XP	BF7943
Air Dryer (Bendix 65624).....	Air Dryer (Bendix 65624).....	Radial Seal Air (25100042).....
BA5373	BA5373	RS4634
Air Dryer (Wabco R950011).....	Coolant (w/Chemical) (20539991).....	Radial Seal XP Air (25100042).....
BA5374 +	BW5183	RS4634XP
Air Dryer (Wabco R950068).....	Coolant (w/o Chemical) (20575545).....	Cab Air (3543-H9638).....
BA5379 +	B5091	PA30277
Air Dryer (85110799).....	Trans. Ele. (2 In. Kit) (Allison 29540493).....	Air Dryer (Wabco R950011).....
BA5592 <sup>90</sup>	PT9416-MPG KIT	BA5374 +
Coolant (w/Chemical) (21937331).....	Trans. Ele. (4 In. Kit) (Allison 29540494).....	Air Dryer (Bendix 65624).....
BW5183	PT9415-MPG KIT	BA5373
Coolant (w/o Chemical) (20575545).....	Opt. Trans. Spin-on (Fuller 17237).....	Coolant (w/o Chemicals) (21937298).....
B5091	B2 +	B5091
Trans. Ele. (2 In. Kit) (Allison 29540493).....	Steering (5839-87904M).....	Coolant (w/12 Units BTE) (21937331).....
PT9416-MPG KIT	PT9354-MPG	BW5183
Trans. Ele. (4 In. Kit) (Allison 29540494).....	CHU612 w/MP7 Eng.	Trans. Ele. (mDrive) (20779040).....
PT9415-MPG KIT	F-F Lube (20539275).....	PT9417
Opt. Trans. Spin-on (Fuller 17237).....	[2] B76 +	Trans. Spin-on (Fuller 4304827)..
B2 +	B-P Lube (20843764).....	BT223
Trans. Spin-on (Fuller 4304827)..	B7409	Opt. Trans. Spin-on (Fuller 17237).....
BT223	Severe Service F-F Lube (20539275).....	B2 +
2 23/32 In. Steering (5839-87904M).....	[2] B76-SS +	Steering (5839-87904M).....
PT9354-MPG	Fuel/Water Separator (21017305).....	PT9354-MPG
3 31/32 In. Steering (349619).....	Fuel (20972295).....	Diesel Exhaust Fluid Strainer (82269261).....
P106-HD	BF1386-O	PE17001
Diesel Exhaust Fluid Strainer (82269261).....	Fuel (20972295).....	CHU613 w/MP8 (12.8L) Eng. (2018)
PE17001	BF7943	F-F Lube (21707136).....
Diesel Exhaust Fluid Pump (21516231).....	Radial Seal Air (57MD320M).....	B-P Lube (21707135).....
PE17000	RS4634	B7409
	Radial Seal XP Air (57MD320M).....	Severe Service F-F Lube (21707136).....
	RS4634XP	[2] B76-SS +
	Air Dryer (Bendix 65624).....	Fuel/Water Separator Ele. (21737481).....
	Trans. Ele. (2 In. Kit) (Allison 29540493).....	PF7930
	PT9416-MPG KIT	Fuel/Water Separator (22094987).....
	Trans. Ele. (4 In. Kit) (Allison 29540494).....	BF46182-O
	PT9415-MPG KIT	BF46117
	Trans. Spin-on (Fuller 4304827)..	
	BT223	
	Steering (5839-87904M).....	
	PT9354-MPG	

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.

Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MACK Trucks (cont'd)	MACK Trucks (cont'd)	MACK Trucks (cont'd)
<b>CHU613 w/MP8 (12.8L) Eng. (2018) (Cont'd)</b> Radial Seal Air (25100042)..... <b>RS4634</b> Radial Seal XP Air (25100042).... <b>RS4634XP</b> Cab Air (3543H9638)..... <b>PA30277</b> Air Dryer (21620181)..... <b>BA5379</b> Coolant (21937331)..... <b>BW5183</b> Trans. (22038908)..... <b>PT9417</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Steering (349619)..... <b>P106-HD</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b> Diesel Exhaust Fluid (21516231) <b>PE17000</b>	<b>CHU614 w/MP8 Eng. (Cont'd)</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Steering (349619)..... <b>P106-HD</b> Diesel Exhaust Fluid Strainer (82269261)..... <b>PE17001</b> Diesel Exhaust Fluid Pump (5303604)..... <b>PE17000</b>	<b>CL613 w/E7-400 Eng.</b> F-F Lube..... <b>[2] B76 +</b> B-P Lube..... <b>BC110</b> P. Fuel..... <b>BF877 +</b> S. Fuel..... <b>BF976</b> Air (57MD42M)..... <b>PA2680</b> Coolant..... <b>BW5178</b> Service Kit..... <b>BK6723</b>
<b>CHU613 w/MP8 (12.8L) Eng. (2019)</b> F-F Lube (21707136)..... <b>[2] B76 +</b> B-P Lube (21707135)..... <b>B7409</b> Severe Service F-F Lube (21707136)..... <b>[2] B76-SS +</b> Fuel/Water Separator (Fleetguard FS19765G)..... <b>PF46094</b> Fuel/Water Separator Ele. (21737481)..... <b>PF7930</b> Fuel (22094967)..... <b>BF46117</b> Radial Seal O. Air (25100042).... <b>RS4634</b> Radial Seal O. XP Air (25100042)..... <b>RS4634XP</b> Cab Air (3543H9638)..... <b>PA30277</b> Air Dryer (Bendix 107794PG)..... <b>BA5377</b> Coolant (21937331)..... <b>BW5183</b> Trans. Ele. (22038908)..... <b>PT9417</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Steering (349619)..... <b>P106-HD</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b> Diesel Exhaust Fluid Strainer (82269261)..... <b>PE17001</b> Diesel Exhaust Fluid Ele. (21516229)..... <b>PE17000</b>	<b>CL Models w/Cat 3406C Eng.</b> Lube (1R0716)..... <b>B99 +</b> Fuel (1R0712)..... <b>BF614 +</b> Axial Seal Air..... <b>PA2680</b> Radial Seal Air..... <b>RS4634</b> Coolant (25MF214)..... <b>BW5071</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Steering (5839-870678A)..... <b>PT9394-MPG</b>	<b>CL613 w/E9 (16.4L) Eng.</b> Lube..... <b>[3] B76 +</b> P. Fuel..... <b>BF877 +</b> S. Fuel..... <b>BF976</b> Air (57MD42M)..... <b>PA2680</b> Coolant..... <b>BW5179</b> ESI-Plus Service Kit..... <b>BK6710</b>
<b>CHU614 w/MP8 Eng.</b> F-F Lube (21707136)..... <b>[2] B76 +</b> B-P Lube (21707135)..... <b>B7409</b> Severe Service F-F Lube (21707136)..... <b>[2] B76-SS +</b> Fuel/Water Separator Ele. (Davco 382 System) (Fleetguard FS19765)..... <b>PF7930</b> Fuel/Water Separator Spin-on (21380521)..... <b>BF1386-O</b> Fuel (20972295)..... <b>BF7943</b> Radial Seal Air (25100042)..... <b>RS4634</b> Radial Seal XP Air (25100042).... <b>RS4634XP</b> Cab Air (3543-H9638)..... <b>PA30277</b> Air Dryer (Wabco R950011)..... <b>BA5374 +</b> Coolant (21937331)..... <b>BW5183</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	<b>CL w/Cummins Signature 600 (15.0L) Eng.</b> 11 25/32 In. Dual-Flow Lube (Fleetguard LF9001)..... <b>BD7154 +</b> Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> 14 7/32 In. Dual-Flow Lube (Fleetguard LF9000)..... <b>BD7153 +</b> Fuel/Water Separator (3331096). <b>BF1274-SP</b> Fuel/Water Separator (4010651). <b>BF1277-SPS</b> Coolant (Fleetguard WF2126)..... <b>BW5086</b>	<b>CL703 w/Cummins ISX Eng.</b> Dual-Flow Lube (Fleetguard LF9001)..... <b>BD7154 +</b> Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> Fuel/Water Separator (301-SD-19B)..... <b>PF7680</b> Fuel (Fleetguard FF2200)..... <b>BF7766</b> Axial Seal Air (57MD42M)..... <b>PA2680</b> Radial Seal XP Air (57MD320M). <b>RS4634XP</b> Radial Seal Air (57MD320M)..... <b>RS4634</b> Air Dryer (Wabco R950011)..... <b>BA5374 +</b> Breather (1/07-on) (3683918)..... <b>CV15000</b> Coolant (Fleetguard WF2126)..... <b>BW5086</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Steering (5839-870678A)..... <b>PT9394-MPG</b>
<b>CL w/Detroit Diesel Series 60 (12.7L) Eng. (1992)</b> F-F Lube (25010495)..... <b>[2] B95 +</b> B-P Lube (23530413)..... <b>B7577</b> Fuel/Water Separator (w/Drain) (23512317)..... <b>BF5813 +</b> Fuel/Water Separator (Open End for Bowl) (23512317)..... <b>BF5813-O +</b> P. Fuel (25014274)..... <b>BF5800 +</b> S. Fuel (23518482)..... <b>BF5810</b> Coolant (23516489)..... <b>BW5200</b>	<b>CL w/Detroit Diesel Series 60 (12.7L) Eng. (1993-on)</b> F-F Lube (23518480)..... <b>[2] B495</b> Fuel/Water Separator (w/Drain) (23512317)..... <b>BF5813 +</b> Fuel/Water Separator (Open End for Bowl) (23512317)..... <b>BF5813-O +</b> P. Fuel (25014274)..... <b>BF5800 +</b> S. Fuel (23518482)..... <b>BF5810</b> Coolant (23516489)..... <b>BW5200</b>	<b>CL713 w/Cat 3406 Eng.</b> Lube (1R0716)..... <b>B99 +</b> Fuel (1R0712)..... <b>BF614 +</b> Axial Seal Air (57MD42M)..... <b>PA2680</b> Radial Seal Air (57MD320M)..... <b>RS4634</b> Radial Seal XP Air (57MD320M). <b>RS4634XP</b> Coolant (25MF214)..... <b>BW5071</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> 3 3/8 In. O.D. Steering (5839-870678A)..... <b>PT9394-MPG</b> 4 3/4 In. O.D. Steering (5839-84148A)..... <b>P528</b>
<b>CL Series w/E7 ETECH Eng.</b> F-F Lube (485GB3191C)..... <b>B76 +</b> B-P Lube Spinner (57GC2134A). <b>BC110</b> P. Fuel (483GB470M)..... <b>BF7656</b> S. Fuel (483GB471M)..... <b>BF7657</b> Air (57MD42M)..... <b>PA2680</b> Coolant (25MF435B)..... <b>BW5178</b> Trans. (25013612)..... <b>BT359</b>	<b>CL713 w/Cummins ISX 15.0 (14.9L) Eng. (To 2006)</b> Dual-Flow Lube (Fleetguard LF9001)..... <b>BD7154 +</b> Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> Fuel/Water Separator (301SD19B)..... <b>PF7680</b> P. Fuel (Fleetguard FF2200)..... <b>BF7766</b> Axial Seal Air (57MD42M)..... <b>PA2680</b> Radial Seal Air (57MD320M)..... <b>RS4634</b> Radial Seal XP Air (57MD320M). <b>RS4634XP</b> Air Dryer (Wabco 950011)..... <b>BA5374 +</b> Coolant (Fleetguard WF2126)..... <b>BW5086</b>	

+ See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MACK Trucks (cont'd)	MACK Trucks (cont'd)	MACK Trucks (cont'd)
CL713 w/Cummins ISX 15.0 (14.9L) Eng. (To 2006) (Cont'd)	CL713 w/E7 (11.9L) Eng. (To 2003)	CL733 w/Cummins ISX Eng. (Cont'd)
Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	F-F Lube..... <b>[2] B76 +</b>	Breather (1/07-on) (3683918)..... <b>CV15000</b>
Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	B-P Lube Spinner (57GC2187)... <b>BC7173</b>	Coolant (Fleetguard WF2126)..... <b>BW5086</b>
Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	B-P Lube Spinner (57GC2231)... <b>BC7242</b>	Opt. Trans. (Fuller 17237)..... <b>B2 +</b>
Trans. Spin-on (Fuller 4304827).. <b>BT223</b>	Opt. Fuel/Water Separator Ele. (301SD19B)..... <b>PF7680</b>	Trans. (Fuller 4304827)..... <b>BT223</b>
3 3/8 In. O.D. Steering (5839-870678A)..... <b>PT9394-MPG</b>	Opt. Fuel/Water Separator Spin-on (483GB472M)..... <b>BF1256</b>	3 3/8 In. O.D. Steering (5839-870678A)..... <b>PT9394-MPG</b>
4 3/4 In. O.D. Steering (5839-84148A)..... <b>P528</b>	P. Fuel (483GB470M)..... <b>BF7656</b>	4 3/4 In. O.D. Steering (5839-84148A)..... <b>P528</b>
CL713 w/Cummins ISX 15.0 (14.9L) Eng. (2007-on)	7 19/32 In. S. Fuel (483GB476M)..... <b>BF7773</b>	CM400 w/Cummins GCT8.3 (8.3L) Eng. Lube..... <b>B205 +</b>
Dual-Flow Lube (Fleetguard LF9001)..... <b>BD7154 +</b>	10 7/16 In. S. Fuel (483GB471M)..... <b>BF7657</b>	P. Fuel/Water Separator..... <b>BF1280 +</b>
Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>	Axial Seal Air (57MD42M)..... <b>PA2680</b>	S. Fuel..... <b>BF788</b>
Fuel/Water Separator (301SD19B)..... <b>PF7680</b>	Radial Seal Air (Non-Recessed Closed End) (57MD46M)..... <b>RS3936</b>	Air (57MD45M)..... <b>PA2851</b>
P. Fuel (Fleetguard FF2200)..... <b>BF7766</b>	Radial Seal Air (Recessed Closed End) (57MD320M)..... <b>RS4634</b>	Coolant (Maintenance)..... <b>BW5070</b>
Axial Seal Air (57MD42M)..... <b>PA2680</b>	Radial Seal XP Air (Recessed Closed End) (57MD320M)..... <b>RS4634XP</b>	CM400 w/E5 (9.8L) Eng. Lube (5000133555)..... <b>B76 +</b>
Radial Seal Air (57MD320M)..... <b>RS4634</b>	Air Dryer (Wabco 950011)..... <b>BA5374 +</b>	Severe Service F-F Lube (5000133555)..... <b>B76-SS +</b>
Radial Seal XP Air (57MD320M)..... <b>RS4634XP</b>	Coolant (25MF435B)..... <b>BW5178</b>	P. Fuel (5000541768)..... <b>BF877 +</b>
Air Dryer (Wabco 950011)..... <b>BA5374 +</b>	Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	S. Fuel (5000133546)..... <b>BF876</b>
Breather (3683918)..... <b>CV15000</b>	Steering (5839-84148A)..... <b>P528</b>	Coolant (5000133551)..... <b>BW5178</b>
Coolant (Fleetguard WF2126)..... <b>BW5086</b>	CL713 w/E7 (11.9L) Eng. (2004-on)	Cruise-Liner w/Cat 3406 Eng. Lube..... <b>B99 +</b>
Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	F-F Lube (485GB3232)..... <b>[2] B7225 +</b>	Fuel Spin-on..... <b>BF614 +</b>
Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	B-P Lube Spinner (57GC2187)... <b>BC7173</b>	Coolant Spin-on..... <b>BW5137</b>
Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	B-P Lube Spinner (57GC2231)... <b>BC7242</b>	Cruise-Liner w/Cummins Eng. F-F Lube Bag..... <b>P996</b>
Trans. Spin-on (Fuller 4304827).. <b>BT223</b>	Opt. Fuel/Water Separator Ele. (301SD19B)..... <b>PF7680</b>	F-F Lube Ele..... <b>P999-HD</b>
3 3/8 In. O.D. Steering (5839-870678A)..... <b>PT9394-MPG</b>	Opt. Fuel/Water Separator Spin-on (483GB472M)..... <b>BF1256</b>	F-F Lube Spin-on..... <b>B196 +</b>
4 3/4 In. O.D. Steering (5839-84148A)..... <b>P528</b>	P. Fuel (483GB470M)..... <b>BF7656</b>	B-P Lube Ele..... <b>C750-E +</b>
CL713 w/AMI ASET Eng.	7 19/32 In. S. Fuel (483GB476M)..... <b>BF7773</b>	Fuel/Water Separator..... <b>BF1212 +</b>
F-F Lube (485GB3236)..... <b>B7225 +</b>	10 7/16 In. S. Fuel (483GB471M)..... <b>BF7657</b>	4 3/8 In. Fuel Spin-on..... <b>BF948 +</b>
B-P Lube Spinner (57GC2231)... <b>BC7242</b>	Axial Seal Air (57MD42M)..... <b>PA2680</b>	5 3/4 In. Fuel Spin-on..... <b>BF957 +</b>
Opt. Fuel/Water Separator Ele. (301SD19B)..... <b>PF7680</b>	Radial Seal Air (Non-Recessed Closed End) (57MD46M)..... <b>RS3936</b>	11 7/32 In. Fuel Spin-on..... <b>BF596 +</b>
P. Fuel (483GB470AM)..... <b>BF7656</b>	Radial Seal Air (Recessed Closed End) (57MD320M)..... <b>RS4634</b>	Air (Don. P132760)..... <b>PA3951</b>
S. Fuel (483GB471M)..... <b>BF7657</b>	Radial Seal XP Air (Recessed Closed End) (57MD320M)..... <b>RS4634XP</b>	Breather Ele. (w/Turbo) (255963) <b>PA643</b>
Axial Seal Air..... <b>PA2680</b>	Air Dryer (Wabco 950011)..... <b>BA5374 +</b>	Breather Ele. (w/o Turbo) (256837)..... <b>PA1627</b>
Radial Seal Air (w/Recessed closed end)..... <b>RS4634</b>	Coolant (25MF435B)..... <b>BW5178</b>	Turbocharger..... <b>BT112 +</b>
Radial Seal Air (w/o Recessed closed end)..... <b>RS3936</b>	Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	Cruise-Liner w/GMC 8V-92 Eng. F-F Lube Ele..... <b>P20-HD +</b>
Air Dryer (Wabco 950011)..... <b>BA5374 +</b>	Steering (5839-84148A)..... <b>P528</b>	P. Fuel Spin-on..... <b>BF5800 +</b>
Breather..... <b>CLN&amp;R</b>	CL733 w/Cummins ISX Eng.	S. Fuel Spin-on..... <b>BF5810</b>
Coolant (25MF435B)..... <b>BW5178</b>	Dual-Flow Lube (3101869)..... <b>BD7154 +</b>	Air (Don. P132760)..... <b>PA3951</b>
Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>	Cruise-Liner w/ET673, ETA2673A, ENDT675, ENDT676, ENDT865, ENDT866 Eng. ESI-Plus Service Kit (1977-on, (6 Spin-ons))..... <b>BK6710</b>
2 23/32 In. Steering (5839-87904M)..... <b>PT9354-MPG</b>	Fuel/Water Separator Ele. (301-SD-19B)..... <b>PF7680</b>	Std. Service Kit (1972-on, (5 Spin-ons))..... <b>BK6700</b>
4 3/16 In. Steering (5839-84148A)..... <b>P528</b>	Fuel (Fleetguard FF2200)..... <b>BF7766</b>	CS200P w/E3-190 Eng. Lube (485GB3191B)..... <b>[2] B76 +</b>
	Axial Seal Air (57MD42M)..... <b>PA2680</b>	P. Fuel (483GB444)..... <b>BF877 +</b>
	Radial Seal Air (57MD320M)..... <b>RS4634</b>	S. Fuel (483GB441)..... <b>BF876</b>
	Radial Seal XP Air (57MD320M)..... <b>RS4634XP</b>	Conical Air (81SD44)..... <b>PA2677</b>
	Air Dryer (Wabco 950011)..... <b>BA5374 +</b>	Coolant (25MF435)..... <b>BW5178</b>


+ See Product Guide for Variations of This Number. Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MACK Trucks (cont'd)	MACK Trucks (cont'd)	MACK Trucks (cont'd)
CS200P Mid-Liner w/Renault MIDR06.02.12 (5.5L) Eng. Lube..... B76 + Severe Service F-F Lube..... B76-SS + P. Fuel..... BF877 + S. Fuel..... BF876 Air (57MD27)..... PA2540 + Air (Permatic FA1519)..... PA2474 Air (Don. P775100)..... PA2677 Coolant (25MF314B)..... BW5178	CS300P Mid-Liner w/Renault MIDR06.02.26 (6.2L) Eng. Lube..... B76 + Severe Service F-F Lube..... B76-SS + P. Fuel..... BF877 + S. Fuel..... BF876 Air (57MD27)..... PA2540 + Air (Permatic FA1519)..... PA2474 Air (Don. P775100)..... PA2677 Coolant (25MF314B)..... BW5178	CT713 w/ASET AI Series Eng. (Cont'd) B-P Lube Spinner (11/11/03-on) (57GC2231)..... BC7242 Opt. Fuel/Water Separator Ele. (301SD19B)..... PF7680 Opt. Fuel/Water Separator Spin-on (483GB477M)..... BF1286 P. Fuel (483GB470M)..... BF7656 P. Fuel (483GB372M)..... CLN&R S. Fuel (483GB476M)..... BF7773 Radial Seal Air (57MD320M)..... RS4634 Radial Seal XP Air (57MD320M)..... RS4634XP Air Dryer (Bendix 107796)..... BA5377 Crankcase Breather..... CLN&R Coolant (25MF435B)..... BW5178 Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT Opt. Trans. Spin-on (Fuller 17237)..... B2 + Steering (5839-870678A)..... PT9394-MPG Some Steering (Luberfiner LP487)..... PT951 + Service Kit..... BK6658 90 Service Kit..... BK6662 Service Kit..... BK6665 Service Kit..... BK6185
CS200P Mid-Liner w/Renault MIDR06.02.26 (6.2L) Eng. Lube..... B76 + Severe Service F-F Lube..... B76-SS + P. Fuel..... BF877 + S. Fuel..... BF876 Air (57MD27)..... PA2540 + Air (Permatic FA1519)..... PA2474 Air (Don. P775100)..... PA2677 Coolant (25MF314B)..... BW5178	CS300P Mid-Liner w/Renault MIDR06.20.30 (8.8L) Eng. Lube..... B76 + Severe Service F-F Lube..... B76-SS + P. Fuel..... BF877 + S. Fuel..... BF876 Air (57MD27)..... PA2540 + Air (Permatic FA1519)..... PA2474 Air (Don. P775100)..... PA2677 Coolant (25MF314B)..... BW5178	CT713 w/AMI-300 (11.9L) Eng. (To 2003) F-F Lube (485GB3236)..... [2] B7225 + B-P Lube Spinner (To 11/11/03) (57GC2206)..... BC7228 B-P Lube Spinner (11/11/03-on) (57GC2231)..... BC7242 Opt. Fuel/Water Separator (301SD19B)..... PF7680 P. Fuel (483GB470AM)..... BF7656 P. Fuel (483GB372M)..... CLN&R 7 19/32 In. S. Fuel (483GB476M)..... BF7773 10 7/16 In. S. Fuel (483GB471M)..... BF7657 Radial Seal Air (57MD320M)..... RS4634 Radial Seal XP Air (57MD320M)..... RS4634XP Air Dryer (Bendix 107796)..... BA5377 Crankcase Breather..... CLN&R Coolant (25MF435B)..... BW5178 Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT Opt. Trans. Spin-on (Fuller 17237)..... B2 + Steering (5839-870678A)..... PT9394-MPG Service Kit (215SB325A)..... BK6693
CS250P w/E3-190 Eng. Lube (485GB3191B)..... [2] B76 + P. Fuel (483GB444)..... BF877 + S. Fuel (483GB441)..... BF876 Conical Air (81SD44)..... PA2677 Coolant (25MF435)..... BW5178	CS300T Mid-Liner w/MIDR06.02.26 (6.2L) Eng. Lube..... B76 + Severe Service F-F Lube..... B76-SS + P. Fuel..... BF877 + S. Fuel..... BF876 Air (57MD27)..... PA2540 + Air (Permatic FA1519)..... PA2474 Air (Don. P775100)..... PA2677 Coolant (25MF314B)..... BW5178	CS250P Mid-Liner w/Renault MIDR06.02.12 (5.5L) Eng. Lube..... B76 + Severe Service F-F Lube..... B76-SS + P. Fuel..... BF877 + S. Fuel..... BF876 Air (57MD27)..... PA2540 + Air (Permatic FA1519)..... PA2474 Air (Don. P775100)..... PA2677 Coolant (25MF314B)..... BW5178
CS250P Mid-Liner w/Renault MIDR06.02.12 (5.5L) Eng. Lube..... B76 + Severe Service F-F Lube..... B76-SS + P. Fuel..... BF877 + S. Fuel..... BF876 Air (57MD27)..... PA2540 + Air (Permatic FA1519)..... PA2474 Air (Don. P775100)..... PA2677 Coolant (25MF314B)..... BW5178	CS300T Mid-Liner w/MIDR06.20.30 (8.8L) Eng. Lube..... B76 + Severe Service F-F Lube..... B76-SS + P. Fuel..... BF877 + S. Fuel..... BF876 Air (57MD27)..... PA2540 + Air (Permatic FA1519)..... PA2474 Air (Don. P775100)..... PA2677 Coolant (25MF314B)..... BW5178	CT713 w/Cummins ISM Eng. Dual-Flow Lube..... BD7153 + Fuel/Water Separator (Fleetguard FS1000)..... BF1259 Radial Seal Air (57MD320M)..... RS4634 Radial Seal XP Air (57MD320M)..... RS4634XP Air Dryer (Bendix 107796)..... BA5377 Breather (1/07-on) (3683918)..... CV15000 Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT Opt. Trans. Spin-on (Fuller 17237)..... B2 + Steering (5839-870678A)..... PT9394-MPG
CS250P Mid-Liner w/Renault MIDR06.02.26 (6.2L) Eng. Lube..... B76 + Severe Service F-F Lube..... B76-SS + P. Fuel..... BF877 + S. Fuel..... BF876 Air (57MD27)..... PA2540 + Air (Permatic FA1519)..... PA2474 Air (Don. P775100)..... PA2677 Coolant (25MF314B)..... BW5178	CT713 w/ASET AI Series Eng. F-F Lube (485GB3236)..... [2] B7225 + B-P Lube Spinner (To 11/11/03) (57GC2206)..... BC7228	CS250P Mid-Liner w/Renault MIDR06.02.26 (6.2L) Eng. Lube (485GB3191B)..... B76 + Fuel/Water Separator (Davco 330516)..... BF957-D P. Fuel (483GB444)..... BF877 + S. Fuel (483GB441)..... BF876 Air (81SD44)..... PA2677 Coolant (25MF435B)..... BW5178 Steering (5000820895)..... P106-HD

+ See Product Guide for Variations of This Number. 90 Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).




MACK Trucks (cont'd)	MACK Trucks (cont'd)	MACK Trucks (cont'd)
CT713 w/AMI-300 (11.9L) Eng. (2004-07)	CT713 w/MP7 Eng.	CTP w/MP8 (12.8L) Eng. (Cont'd)
F-F Lube (485GB3236)..... [2] B7225 +	F-F Lube (20539275)..... [2] B76 +	Trans. Ele. (4 In. Kit) (Allison
B-P Lube Spinner (57GC2231)... BC7242	B-P Lube Spinner (20552379).... BC7242	29540494)..... PT9415-MPG KIT
Opt. Fuel/Water Separator	B-P Lube Spin-on (20843764).... B7409	Trans. Spin-on (EVS Series)
(301SD19B)..... PF7680	Fuel/Water Separator	(Allison 29539579)..... BT8460
P. Fuel (483GB470AM)..... BF7656	(21017305)..... BF1386-O	Opt. Trans. Spin-on (Fuller
P. Fuel (483GB372M)..... CLN&R	Fuel (20539582)..... BF7814	17237)..... B2 +
7 19/32 In. S. Fuel	Fuel (20972295)..... BF7943	Steering (583984148A)..... P528
(483GB476M)..... BF7773	Radial Seal Air (57MD320M)..... RS4634	
10 7/16 In. S. Fuel	Radial Seal XP Air (57MD320M). RS4634XP	CTP713 w/MP7 Eng.
(483GB471M)..... BF7657	Air Dryer (Bendix 107796)..... BA5377	F-F Lube (20539275)..... [2] B76 +
Radial Seal Air (57MD320M)..... RS4634	Coolant (w/o Chemical)	B-P Lube Spinner (20552379).... BC7242
Radial Seal XP Air (57MD320M). RS4634XP	(20575545)..... B5091	Fuel/Water Separator Ele.
Air Dryer (Bendix 107796)..... BA5377	Coolant (w/Chemical)	(Remote Mtd.) (Davco 382114).... PF7748
Crankcase Breather..... CLN&R	(20539991)..... BW5183	Fuel/Water Separator Ele.
Coolant (25MF435B)..... BW5178	Trans. Ele. (2 In. Kit) (Allison	(Remote Mtd.) (301-SD-19B)..... PF7680
Trans. Ele. (2 In. Kit) (Allison	29540493)..... PT9416-MPG KIT	Fuel/Water Separator Spin-on
29540493)..... PT9416-MPG KIT	Trans. Ele. (4 In. Kit) (Allison	(21017305)..... BF1386-O
Trans. Ele. (4 In. Kit) (Allison	29540494)..... PT9415-MPG KIT	Fuel/Water Separator Spin-on
29540494)..... PT9415-MPG KIT	Opt. Trans. (Fuller 17237)..... B2 +	(w/Drain & Sensor Port)
Opt. Trans. Spin-on (Fuller	Steering (5839-870678A)..... PT9394-MPG	(20539578)..... BF1384-SP
17237)..... B2 +		Fuel (20539582)..... BF7814
Steering (5839-870678A)..... PT9394-MPG	CT713 w/MP8 Eng.	Radial Seal Air (57MD320M)..... RS4634
Service Kit (215SB325A)..... BK6693	F-F Lube (20539275)..... [2] B76 +	Radial Seal XP Air (57MD320M). RS4634XP
	B-P Lube (20843764)..... B7409	Cab Air (3543H9638)..... PA30277
	Fuel/Water Separator	Air Dryer (Bendix 107796)..... BA5377
	(21017305)..... BF1386-O	Coolant (w/o Chemical)
	Fuel (20972295)..... BF7943	(20575545)..... B5091
	Radial Seal Air (57MD320M)..... RS4634	Coolant (w/Chemical)
	Radial Seal XP Air (57MD320M). RS4634XP	(20539991)..... BW5183
	Air Dryer (Bendix 107796)..... BA5377	Trans. Ele. (2 In. Kit) (Allison
	Coolant (20575545)..... B5091	29540493)..... PT9416-MPG KIT
	Trans. Ele. (2 In. Kit) (Allison	Trans. Ele. (4 In. Kit) (Allison
	29540493)..... PT9416-MPG KIT	29540494)..... PT9415-MPG KIT
	Trans. Ele. (4 In. Kit) (Allison	Trans. Spin-on (EVS Series)
	29540494)..... PT9415-MPG KIT	(Allison 29539579)..... BT8460
	Opt. Trans. Spin-on (Fuller	Opt. Trans. Spin-on (Fuller
	17237)..... B2 +	17237)..... B2 +
	Steering (5839-870678A)..... PT9394-MPG	Steering (5839-84148A)..... P528
	CTP w/MP8 (12.8L) Eng.	CTP713B w/MP7 Eng.
	F-F Lube (20539275)..... [2] B76 +	F-F Lube Spin-on (20539275).... [2] B76 +
	B-P Lube Spin-on (20843764).... B7409	B-P Lube Spinner (20552379).... BC7242
	B-P Lube Spinner (20552379).... BC7242	Fuel/Water Separator Ele.
	Severe Service F-F Lube	(Remote Mtd.) (Davco 382114).... PF7748
	(20539275)..... [2] B76-SS +	Fuel/Water Separator Ele.
	Fuel/Water Separator Spin-on	(Remote Mtd.) (301SD19B)..... PF7680
	(21017305)..... BF1386-O	Fuel/Water Separator Spin-on
	Fuel/Water Separator Spin-on	(21017305)..... BF1386-O
	(w/Drain & Sensor Port)	Fuel/Water Separator Spin-on
	(20539578)..... BF1384-SP	(w/Drain & Sensor Port)
	Fuel (20539582)..... BF7814	(20539578)..... BF1384-SP
	Fuel (20972295)..... BF7943	S. Fuel (20539582)..... BF7814
	Radial Seal Air (57MD320M)..... RS4634	Radial Seal Air (57MD320M)..... RS4634
	Radial Seal XP Air (57MD320M). RS4634XP	Radial Seal XP Air (57MD320M). RS4634XP
	Cab Air (3543H9638)..... PA30277	Cab Air (3543-H9638)..... PA30277
	Air Dryer (Bendix 107796)..... BA5377	Air Dryer (Bendix 107796)..... BA5377
	Coolant (w/Chemical)	Coolant (w/Chemical)
	(20539991)..... BW5183	(20539991)..... BW5183
	Trans. Ele. (2 In. Kit) (Allison	Coolant (w/o Chemical)
	29540493)..... PT9416-MPG KIT	(20575545)..... B5091

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MACK Trucks (cont'd)	MACK Trucks (cont'd)	MACK Trucks (cont'd)
CTP713B w/MP7 Eng. (Cont'd)	CV w/AMI-300 (11.9L) Eng. (2004-08) (Cont'd)	CV w/E7 (11.9L) Eng. (2004-on) (Cont'd)
Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	Coolant (25MF435B)..... BW5178	Opt. Fuel/Water Separator Ele. (301SD19B)..... PF7680
Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	Opt. Fuel/Water Separator Spin-on (483GB472M)..... BF1256
Trans. Spin-on (EVS Series) (Allison 29539579)..... BT8460	Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Opt. Fuel/Water Separator Spin-on (483GB477M)..... BF1286
Opt. Trans. Spin-on (Fuller 17237)..... B2 +	Opt. Trans. Spin-on (Fuller 17237)..... B2 +	P. Fuel (483GB470AM)..... BF7656
3 3/8 In. O.D. Steering (5839-870678A)..... PT9394-MPG	2 23/32 In. Steering (5839-87904M)..... PT9354-MPG	S. Fuel (483GB476M)..... BF7773
4 3/4 In. O.D. Steering (5839-84148A)..... P528	4 3/16 In. Steering (5839-LF637)..... P528	S. Fuel (483GB471M)..... BF7657
CV w/AMI-300 (11.9L) Eng. (To 2003)	Service Kit (215SB330)..... BK6662	Radial Seal Air (57MD320M)..... RS4634
F-F Lube (485GB3236)..... [2] B7225 +	Service Kit (215SB332)..... BK6665	Radial Seal XP Air (57MD320M)..... RS4634XP
B-P Lube Spinner (To 11/11/03) (57GC2206)..... BC7228	Service Kit (215SB325A)..... BK6693	Air Dryer (Bendix 107794)..... BA5377
B-P Lube Spinner (11/11/03-on) (57GC2231)..... BC7242	CV w/E7 (11.9L) Eng. (2001-03)	Crankcase Breather..... CLN&R
Opt. Fuel/Water Separator (483GB477M)..... BF1286	F-F Lube (485GB3191B)..... [2] B76 +	Coolant (25MF435B)..... BW5178
Opt. Fuel/Water Separator (483GB472M)..... BF1256	4 1/2 In. B-P Lube Spinner (w/9/16 & 5/8 I.D.) (485GB3219D)..... BC110	Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT
P. Fuel (483GB470AM)..... BF7656	4 1/2 In. B-P Lube Spinner (w/3/8 & 1/2 I.D.) (57GC2187)..... BC7173	Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT
P. Fuel (483GB372M)..... CLN&R	7 In. B-P Lube Spinner (57GC2231)..... BC7242	Opt. Trans. Spin-on (Fuller 17237)..... B2 +
S. Fuel (483GB471M)..... BF7657	Severe Service F-F Lube (485GB3191B)..... [2] B76-SS +	2 23/32 In. Steering (5839-87904M)..... PT9354-MPG
S. Fuel (483GB476M)..... BF7773	Opt. Fuel/Water Separator (483GB472M)..... BF1256	4 3/16 In. Steering (5839-84148A)..... P528
Radial Seal Air (57MD320M)..... RS4634	Opt. Fuel/Water Separator Ele. (301SD19B)..... PF7680	Service Kit (215SB325A)..... BK6693
Radial Seal XP Air (57MD320M)..... RS4634XP	Opt. Fuel/Water Separator (483GB477M)..... BF1286	Service Kit (57GC2177B)..... BK6704
Air Dryer (Bendix 107794)..... BA5377	P. Fuel (483GB470AM)..... BF7656	CV w/EM7 (11.9L) Eng. (To 2003)
Crankcase Breather..... CLN&R	S. Fuel (483GB476M)..... BF7773	F-F Lube (485GB3191B)..... [2] B76 +
Coolant (25MF435B)..... BW5178	S. Fuel (483GB471M)..... BF7657	B-P Lube Spinner (57GC2134)..... BC110
Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	Radial Seal Air (57MD320M)..... RS4634	B-P Lube Spinner (57GC2231)..... BC7242
Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Radial Seal XP Air (57MD320M)..... RS4634XP	B-P Lube Spinner (57GC2187)..... BC7173
Opt. Trans. Spin-on (Fuller 17237)..... B2 +	Air Dryer (Bendix 107794)..... BA5377	Severe Service F-F Lube (485GB3191B)..... [2] B76-SS +
2 23/32 In. Steering (5839-87904M)..... PT9354-MPG	Coolant (25MF435B)..... BW5178	Opt. Fuel/Water Separator Ele. (301SD19B)..... PF7680
4 3/16 In. Steering (5839-LF637)..... P528	Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	Opt. Fuel/Water Separator Spin-on (483GB477M)..... BF1286
Service Kit (215SB330)..... BK6662	Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	P. Fuel (483GB470AM)..... BF7656
Service Kit (215SB332)..... BK6665	Opt. Trans. Spin-on (Fuller 17237)..... B2 +	S. Fuel (483GB471M)..... BF7657
Service Kit (215SB325A)..... BK6693	2 23/32 In. Steering (5839-87904M)..... PT9354-MPG	Radial Seal Air (57MD320M)..... RS4634
CV w/AMI-300 (11.9L) Eng. (2004-08)	4 3/16 In. Steering (5839-84148A)..... P528	Radial Seal XP Air (57MD320M)..... RS4634XP
F-F Lube (485GB3236)..... [2] B7225 +	Service Kit (57GC2188A)..... BK6696	Air Dryer (Bendix 107796)..... BA5377
B-P Lube Spinner (57GC2231)..... BC7242	Service Kit (57GC2177B)..... BK6704	Coolant (25MF435B)..... BW5178
Opt. Fuel/Water Separator (483GB477M)..... BF1286	CV w/E7 (11.9L) Eng. (2004-on)	Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT
Opt. Fuel/Water Separator (483GB472M)..... BF1256	F-F Lube (485GB3236)..... [2] B7225 +	Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT
P. Fuel (483GB470AM)..... BF7656	4 1/2 In. B-P Lube Spinner (w/9/16 & 5/8 I.D.) (485GB3219D)..... BC110	Opt. Trans. Spin-on (Fuller 17237)..... B2 +
P. Fuel (483GB372M)..... CLN&R	4 1/2 In. B-P Lube Spinner (w/3/8 & 1/2 I.D.) (57GC2187)..... BC7173	Steering (5839-870678A)..... PT9394-MPG
S. Fuel (483GB471M)..... BF7657	7 In. B-P Lube Spinner (57GC2231)..... BC7242	Service Kit (57GC2188A)..... BK6696
S. Fuel (483GB476M)..... BF7773		Service Kit (57GC2177B)..... BK6704
Radial Seal Air (57MD320M)..... RS4634		CV w/EM7 (11.9L) Eng. (2004-on)
Radial Seal XP Air (57MD320M)..... RS4634XP		F-F Lube (485GB3236)..... [2] B7225 +
Air Dryer (Bendix 107794)..... BA5377		B-P Lube Spinner (57GC2134)..... BC110
Crankcase Breather..... CLN&R		B-P Lube Spinner (57GC2231)..... BC7242
		B-P Lube Spinner (57GC2187)..... BC7173
		Opt. Fuel/Water Separator Ele. (301SD19B)..... PF7680

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).


MACK Trucks (cont'd)	MACK Trucks (cont'd)	MACK Trucks (cont'd)
CV w/EM7 (11.9L) Eng. (2004-on) (Cont'd)	Granite BF CV513 w/ASET AI Series Engs. (Cont'd)	Granite CV712, CV713 w/ASET AC, AI Series Engs.
<b>Opt. Fuel/Water Separator</b>	<b>S. Fuel</b> (483GB471M)..... <b>BF7657</b>	<b>F-F Lube</b> (485GB3236)..... [2] B7225 +
<b>Spin-on</b> (483GB477M)..... <b>BF1286</b>	<b>Radial Seal Air</b> (57MD320M)..... <b>RS4634</b>	<b>B-P Lube Spinner</b> (To 11/11/03) (57GC2206)..... <b>BC7228</b>
<b>P. Fuel</b> (483GB470M)..... <b>BF7656</b>	<b>Radial Seal XP Air</b> (57MD320M)..... <b>RS4634XP</b>	<b>B-P Lube Spinner</b> (11/11/03-on) (57GC2231)..... <b>BC7242</b>
<b>S. Fuel</b> (483GB471M)..... <b>BF7657</b>	<b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b>	<b>Opt. Fuel/Water Separator Ele.</b> (301SD19B)..... <b>PF7680</b>
<b>Radial Seal Air</b> (57MD320M)..... <b>RS4634</b>	<b>Crankcase Breather</b> ..... <b>CLN&amp;R</b>	<b>Opt. Fuel/Water Separator</b>
<b>Radial Seal XP Air</b> (57MD320M)..... <b>RS4634XP</b>	<b>Coolant</b> (25MF435B)..... <b>BW5178</b>	<b>Spin-on</b> (483GB477M)..... <b>BF1286</b>
<b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>P. Fuel</b> (483GB470AM)..... <b>BF7656</b>
<b>Coolant</b> (25MF435B)..... <b>BW5178</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>P. Fuel</b> (483GB372M)..... <b>CLN&amp;R</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>S. Fuel</b> (483GB471M)..... <b>BF7657</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>2 25/32 In. Steering</b> (9424-LF634)..... <b>PT903 +</b>	<b>S. Fuel</b> (483GB476M)..... <b>BF7773</b>
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>4 1/8 In. Steering</b> (5839-870678A)..... <b>PT9394-MPG</b>	<b>Radial Seal Air</b> (57MD320M)..... <b>RS4634</b>
<b>Steering</b> (5839-870678A)..... <b>PT9394-MPG</b>	<b>Service Kit</b> (215SB325A)..... <b>BK6693</b>	<b>Radial Seal XP Air</b> (57MD320M)..... <b>RS4634XP</b>
<b>Service Kit</b> (215SB325A)..... <b>BK6693</b>	Granite BF CV513 w/ASET AMI Series Engs.	<b>Air Dryer</b> (Bendix 107794)..... <b>BA5377</b>
CV513 w/Cummins ISL Eng.	<b>F-F Lube</b> (485GB3236)..... [2] B7225 +	<b>Crankcase Breather</b> ..... <b>CLN&amp;R</b>
<b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b>	<b>B-P Lube Spinner</b> (To 11/11/03) (57GC2206)..... <b>BC7228</b>	<b>Coolant</b> (25MF435B)..... <b>BW5178</b>
<b>Fuel/Water Separator</b> (Fleetguard FS1022)..... <b>BF1272-SPS</b>	<b>B-P Lube Spinner</b> (11/11/03-on) (57GC2231)..... <b>BC7242</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>P. Fuel</b> (483GB470M)..... <b>BF7656</b>	<b>Opt. Fuel/Water Separator</b> (483GB477M)..... <b>BF1286</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>S. Fuel</b> (483GB471M)..... <b>BF7657</b>	<b>P. Fuel</b> (483GB470AM)..... <b>BF7656</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
<b>Radial Seal Air</b> (57MD48M)..... <b>RS4634</b>	<b>S. Fuel</b> (483GB471M)..... <b>BF7657</b>	<b>2 23/32 In. Steering</b> (5839-87904M)..... <b>PT9354-MPG</b>
<b>Radial Seal XP Air</b> (57MD48M)..... <b>RS4634XP</b>	<b>Radial Seal Air</b> (57MD320M)..... <b>RS4634</b>	<b>4 1/8 In. Steering</b> (5839-870678A)..... <b>PT9394-MPG</b>
<b>Air Dryer</b> (Meritor R950011)..... <b>BA5374 +</b>	<b>Radial Seal XP Air</b> (57MD320M)..... <b>RS4634XP</b>	<b>4 3/16 In. Steering</b> (9424-LF637)..... <b>P528</b>
<b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b>	<b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b>	<b>Service Kit</b> (215SB330)..... <b>BK6662</b>
<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	<b>Crankcase Breather</b> ..... <b>CLN&amp;R</b>	<b>Service Kit</b> ..... <b>BK6665</b>
<b>Steering</b> (5839-870678A)..... <b>PT9394-MPG</b>	<b>Coolant</b> (25MF435B)..... <b>BW5178</b>	<b>Service Kit</b> ..... <b>BK6693</b>
Granite BF CV513 w/E7 Eng.	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Service Kit</b> ..... <b>BK6185</b>
<b>F-F Lube</b> (485GB3191C)..... [2] B76 +	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	CX w/AC (11.9L) Eng. (2004-05)
<b>B-P Lube Spinner</b> (57GC2134A)..... <b>BC110</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>F-F Lube</b> (485GB3232)..... [2] B7225 +
<b>B-P Lube Spinner</b> (57GC2187)..... <b>BC7173</b>	<b>Steering</b> (5839-870678A)..... <b>PT9394-MPG</b>	<b>B-P Lube Spinner</b> (57GC2231)..... <b>BC7242</b>
<b>Opt. Fuel/Water Separator</b> (483GB472M)..... <b>BF1256</b>	<b>Service Kit</b> (215SB325A)..... <b>BK6693</b>	<b>Opt. Fuel/Water Separator</b> (483GB472M)..... <b>BF1256</b>
<b>P. Fuel</b> (483GB470M)..... <b>BF7656</b>	Granite CV712 w/Cummins ISL Eng.	<b>Opt. Fuel/Water Separator</b> (483GB477M)..... <b>BF1286</b>
<b>S. Fuel</b> (483GB471M)..... <b>BF7657</b>	<b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b>	<b>P. Fuel</b> (483GB470AM)..... <b>BF7656</b>
<b>Radial Seal Air</b> (57MD320M)..... <b>RS4634</b>	<b>Dual-Flow Lube</b> (3401544)..... <b>BD7309 +</b>	<b>S. Fuel</b> (483GB471M)..... <b>BF7657</b>
<b>Radial Seal XP Air</b> (57MD320M)..... <b>RS4634XP</b>	<b>Lube</b> (Upgrade) (3401544)..... <b>B40142 +</b>	<b>Radial Seal Air</b> (57MD320M)..... <b>RS4634</b>
<b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b>	<b>Fuel/Water Separator</b> (3800394)..... <b>BF1272-SPS</b>	<b>Radial Seal XP Air</b> (57MD320M)..... <b>RS4634XP</b>
<b>Coolant</b> (25MF435B)..... <b>BW5178</b>	<b>P. Fuel</b> (Fleetguard FF5488)..... <b>BF7815</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Radial Seal Air</b> (57MD320M)..... <b>RS4634</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Radial Seal XP Air</b> (57MD320M)..... <b>RS4634XP</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Steering</b> (5839-84365A)..... <b>PT951 +</b>
<b>Steering</b> (5839-870678A)..... <b>PT9394-MPG</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Service Kit</b> (57GC2245)..... <b>BK6653</b>
<b>Service Kit</b> (215SB325A)..... <b>BK6693</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Service Kit</b> (215SB330)..... <b>BK6662</b>
Granite BF CV513 w/ASET AI Series Engs.	<b>Steering</b> (5839-87904M)..... <b>PT9354-MPG</b>	<b>Service Kit</b> (215SB325A)..... <b>BK6693</b>
<b>F-F Lube</b> (485GB3236)..... [2] B7225 +	Granite CV712 w/Cummins ISL Eng.	Vision CX612 w/ASET AC Series Eng.
<b>B-P Lube Spinner</b> (To 11/11/03) (57GC2206)..... <b>BC7228</b>	<b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b>	<b>F-F Lube</b> (485GB3232)..... [2] B7225 +
<b>B-P Lube Spinner</b> (11/11/03-on) (57GC2231)..... <b>BC7242</b>	<b>Dual-Flow Lube</b> (3401544)..... <b>BD7309 +</b>	<b>B-P Lube Spinner</b> (To 11/11/03) (485GB4363M)..... <b>BC7228</b>
<b>Opt. Fuel/Water Separator</b> (483GB477M)..... <b>BF1286</b>	<b>Lube</b> (Upgrade) (3401544)..... <b>B40142 +</b>	
<b>P. Fuel</b> (483GB470AM)..... <b>BF7656</b>	<b>Fuel/Water Separator</b> (3800394)..... <b>BF1272-SPS</b>	
<b>P. Fuel</b> (483GB372M)..... <b>CLN&amp;R</b>	<b>P. Fuel</b> (Fleetguard FF5488)..... <b>BF7815</b>	

\* See Product Guide for Variations of This Number. Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MACK Trucks (cont'd)	MACK Trucks (cont'd)	MACK Trucks (cont'd)
Vision CX612 w/ASET AC Series Eng. (Cont'd)	Vision CX613 w/ASET AC Series Engs. (Cont'd)	CXN w/AC (11.9L) Eng. (To 11/11/2003) (Cont'd)
B-P Lube Spinner (11/11/03-on) (57GC2231)..... BC7242	Service Kit (215SB330)..... BK6662	Air Dryer (Meritor R950011)..... BA5374 +
Opt. Fuel/Water Separator (483GB472M)..... BF1256	Service Kit..... BK6665	Crankcase Breather..... CLN&R
Opt. Fuel/Water Separator (483GB477M)..... BF1286	Service Kit (215SB325A)..... BK6693	Coolant (25MF435B)..... BW5178
P. Fuel (483GB470AM)..... BF7656	Service Kit..... BK6185	Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT
S. Fuel (483GB471M)..... BF7657	Vision CX613 w/E7 E-Tech Series Eng.	Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT
Radial Seal Air (57MD320M)..... RS4634	F-F Lube (To 2004) (485GB3191B)..... [2] B76 +	Trans. Spin-on (Fuller 4304827).. BT223
Radial Seal XP Air (57MD320M)..... RS4634XP	F-F Lube (2004-on) (485GB3236)..... [2] B7225 +	Opt. Trans. Spin-on (Fuller 17237)..... B2 +
Air Dryer (Bendix 107796)..... BA5377	B-P Lube Spinner (57GC2134A)..... BC110	Steering (5839-84365A)..... PT951 +
Crankcase Breather..... CLN&R	B-P Lube Spinner (57GC2231)..... BC7242	CXN w/AC (11.9L) Eng. (11/11/2003-on)
Coolant (25MF435B)..... BW5178	B-P Lube Spinner (25503228)..... BC7173	F-F Lube (485GB3236)..... [2] B7225 +
Opt. Trans. (Fuller 17237)..... B2 +	Opt. Fuel/Water Separator Ele. (301SD19B)..... PF7680	B-P Lube Spinner (57GC2231)..... BC7242
Steering (5839-84365A)..... PT951 +	Opt. Fuel/Water Separator Spin-on (483GB472M)..... BF1256	Opt. Fuel/Water Separator Ele. (301SD19B)..... PF7680
Service Kit (57GC2245)..... BK6653	P. Fuel (483GB470AM)..... BF7656	Opt. Fuel/Water Separator Spin-on (483GB477M)..... BF1286
Service Kit (215SB330)..... BK6662	7 19/32 In. S. Fuel (483GB476M)..... BF7773	P. Fuel (483GB470AM)..... BF7656
Service Kit (215SB325A)..... BK6693	10 7/16 In. S. Fuel (483GB471M)..... BF7657	P. Fuel (483GB372M)..... CLN&R
CX612 w/E-7 Eng.	Axial Seal Air (57MD42M)..... PA2680	7 19/32 In. S. Fuel (483GB476M)..... BF7773
F-F Lube (485GB3236)..... [2] B7225 +	Radial Seal Air (Recessed Closed End) (57MD320M)..... RS4634	10 7/16 In. S. Fuel (483GB471M)..... BF7657
B-P Lube Spinner (57GC2206)..... BC7228	Radial Seal XP Air (Recessed Closed End) (57MD320M)..... RS4634XP	Radial Seal Air (57MD320M)..... RS4634
P. Fuel (483GB476M)..... BF7773	Radial Seal Air (Non-Recessed Closed End) (57MD46M)..... RS3936	Radial Seal XP Air (57MD320M)..... RS4634XP
S. Fuel (483GB471M)..... BF7657	Air Dryer (Wabco R950011)..... BA5374 +	Air Dryer (AD-IP System) (Bendix 65624)..... BA5373
Radial Seal Air (57MD320M)..... RS4634	Air Dryer (Bendix 107796)..... BA5377	Air Dryer (Meritor R950011)..... BA5374 +
Radial Seal XP Air (57MD320M)..... RS4634XP	Coolant (25MF435B)..... BW5178	Crankcase Breather..... CLN&R
Air Dryer (Wabco R950011)..... BA5374 +	Trans. (Fuller 4304827)..... BT223	Coolant (25MF435B)..... BW5178
Coolant (25MF435B)..... BW5178	Opt. Trans. (Fuller 17237)..... B2 +	Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT
Opt. Trans. (Fuller 17237)..... B2 +	Steering (5839-84365A)..... PT951 +	Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT
Vision CX613 w/ASET AC Series Engs.	Service Kit..... BK6658 <sup>90</sup>	Trans. Spin-on (Fuller 4304827).. BT223
F-F Lube (485GB3232)..... [2] B7225 +	Service Kit..... BK6659	Opt. Trans. Spin-on (Fuller 17237)..... B2 +
B-P Lube Spinner (To 11/11/03) (485GB4363M)..... BC7228	Service Kit..... BK6665	Steering (5839-84365A)..... PT951 +
B-P Lube Spinner (11/11/03-on) (57GC2231)..... BC7242	Service Kit (215SB325A)..... BK6693	Service Kit (215SB332)..... BK6665
Opt. Fuel/Water Separator Ele. (Davco 382114)..... PF7748	Service Kit (57GC2177B)..... BK6704	Service Kit (215SB330)..... BK6662
Opt. Fuel/Water Separator Ele. (301SD19C)..... PF7680	Service Kit..... BK6185	Service Kit (215SB325A)..... BK6693
Opt. Fuel/Water Separator Spin-on (483GB472M)..... BF1256	CXN w/AC (11.9L) Eng. (To 11/11/2003)	CXN w/AMI-300 (11.9L) Eng. (To 2003)
Opt. Fuel/Water Separator Spin-on (483GB477M)..... BF1286	F-F Lube (485GB3236)..... [2] B7225 +	F-F Lube (485GB3236)..... [2] B7225 +
P. Fuel (483GB470AM)..... BF7656	B-P Lube Spinner (57GC2206)..... BC7228	B-P Lube Spinner (To 11/11/03) (57GC2206)..... BC7228
S. Fuel (483GB471M)..... BF7657	Opt. Fuel/Water Separator Ele. (301SD19B)..... PF7680	B-P Lube Spinner (11/11/03-on) (57GC2231)..... BC7242
S. Fuel (483GB476M)..... BF7773	Opt. Fuel/Water Separator Spin-on (483GB477M)..... BF1286	Opt. Fuel/Water Separator (301SD19B)..... PF7680
Axial Seal Air (57MD42M)..... PA2680	P. Fuel (483GB470AM)..... BF7656	P. Fuel (483GB471M)..... BF7657
Radial Seal Air (57MD320M)..... RS4634	P. Fuel (483GB372M)..... CLN&R	P. Fuel (483GB372M)..... CLN&R
Radial Seal XP Air (57MD320M)..... RS4634XP	7 19/32 In. S. Fuel (483GB476M)..... BF7773	P. Fuel (483GB470AM)..... BF7656
Air Dryer (Wabco R950011)..... BA5374 +	10 7/16 In. S. Fuel (483GB471M)..... BF7657	S. Fuel (483GB476M)..... BF7773
Air Dryer (Bendix 107796)..... BA5377	Radial Seal Air (57MD320M)..... RS4634	Radial Seal Air (57MD320M)..... RS4634
Crankcase Breather..... CLN&R	Radial Seal XP Air (57MD320M)..... RS4634XP	Radial Seal XP Air (57MD320M)..... RS4634XP
Coolant (w/o Chemical) (25MF54)..... B5176	Air Dryer (AD-IP System) (Bendix 65624)..... BA5373	Air Dryer (Meritor R950011)..... BA5374 +
Coolant (w/10 Units BTE) (25MF435B)..... BW5178		
Trans. (Fuller 4304827)..... BT223		
Opt. Trans. (Fuller 17237)..... B2 +		
Steering (5839-84365A)..... PT951 +		

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MACK Trucks (cont'd)	MACK Trucks (cont'd)	MACK Trucks (cont'd)
CXN w/AMI-300 (11.9L) Eng. (To 2003) (Cont'd)	CXP613 w/AC Aset Eng.	CXP613 w/MP8 Eng. (Cont'd)
<b>Crankcase Breather</b> ..... CLN&R	<b>F-F Lube</b> (485GB3236)..... [2] B7225 +	<b>Opt. Trans. Spin-on</b> (Fuller
<b>Coolant</b> (25MF435B)..... BW5178	<b>B-P Lube Spinner</b> (236GB42M).. BC7242	17237)..... B2 +
<b>Opt. Trans.</b> (Fuller 17237)..... B2 +	<b>Opt. Fuel/Water Separator</b>	<b>Steering</b> (5839-87904M)..... PT9354-MPG
<b>Steering</b> (5839-84365A)..... PT951 +	(483GB477M)..... BF1286	
<b>Service Kit</b> (215SB325A)..... BK6693	<b>P. Fuel</b> (483GB470AM)..... BF7656	
CXN w/AMI-300 (11.9L) Eng. (2004-07)	<b>7 19/32 In. S. Fuel</b>	CXU w/Cummins ISX 11.9G (11.9L) Eng.
<b>F-F Lube</b> (485GB3236)..... [2] B7225 +	(483GB476M)..... BF7773	(2014-17)
<b>B-P Lube Spinner</b> (57GC2231)... BC7242	<b>10 7/16 In. S. Fuel</b>	<b>Dual-Flow Lube</b> (2882674)..... BD7154 +
<b>Opt. Fuel/Water Separator</b>	(483GB471M)..... BF7657	<b>Dual-Flow Lube</b> (Upgrade)
(301SD19B)..... PF7680	<b>Radial Seal Air</b> (57MD320M)..... RS4634	(Fleetguard LF14000NN)..... BD50000
<b>P. Fuel</b> (483GB471M)..... BF7657	<b>Radial Seal XP Air</b> (57MD320M)..... RS4634XP	<b>Fuel/Water Separator</b> (3606712)..... BF7695
<b>P. Fuel</b> (483GB372M)..... CLN&R	<b>Air Dryer</b> (Bendix 107796)..... BA5377	<b>Radial Seal Air</b> (57MD320M)..... RS4634
<b>P. Fuel</b> (483GB470AM)..... BF7656	<b>Coolant</b> ..... BW5183	<b>Radial Seal XP Air</b> (57MD320M)..... RS4634XP
<b>S. Fuel</b> (483GB476M)..... BF7773	<b>Trans. Ele.</b> (2 In. Kit) (Allison	<b>Cab Air</b> (85112361)..... PA30325
<b>Radial Seal Air</b> (57MD320M)..... RS4634	29540493)..... PT9416-MPG KIT	<b>Cab Air</b> (3543-H9638)..... PA30277
<b>Radial Seal XP Air</b> (57MD320M)..... RS4634XP	<b>Trans. Ele.</b> (4 In. Kit) (Allison	<b>Air Dryer</b> (Bendix 5008414)..... BA5374 +
<b>Air Dryer</b> (Meritor R950011)..... BA5374 +	29540494)..... PT9415-MPG KIT	<b>Air Dryer</b> (Wabco R950068)..... BA5379 +
<b>Crankcase Breather</b> ..... CLN&R	<b>Opt. Trans. Spin-on</b> (Fuller	<b>Trans.</b> (Fuller 4304827)..... BT223
<b>Coolant</b> (25MF435B)..... BW5178	17237)..... B2 +	<b>Opt. Trans.</b> (Fuller 17237)..... B2 +
<b>Opt. Trans.</b> (Fuller 17237)..... B2 +	<b>Steering</b> (5839-87904M)..... PT9354-MPG	<b>2 23/32 In. Steering</b>
<b>Steering</b> (5839-84365A)..... PT951 +		(5839-87904M)..... PT9354-MPG
<b>Service Kit</b> (215SB325A)..... BK6693		<b>3 31/32 In. Steering</b> (349619)..... P106-HD
CXN w/E7 Eng.	CXP613 w/MP7 Eng.	<b>4 1/8 In. Steering</b> (Nelson
<b>F-F Lube</b> (485GB3232)..... [2] B7225 +	<b>F-F Lube</b> (20539275)..... [2] B76 +	870678A)..... PT9394-MPG
<b>B-P Lube Spinner</b> (57GC2231)... BC7242	<b>B-P Lube Spinner</b> (20552379).... BC7242	CXU w/Cummins ISX 11.9G (11.9L) Eng. (2018)
<b>Opt. Fuel/Water Separator Ele.</b>	<b>Fuel/Water Separator</b>	<b>Dual-Flow Lube</b> (Fleetguard
(301SD19B)..... PF7680	(21017305)..... BF1386-O	LF9080)..... BD50000
<b>Opt. Fuel/Water Separator</b>	<b>Fuel/Water Separator</b> (w/Drain &	<b>Fuel/Water Separator</b> (3607140)..... BF7695
<b>Spin-on</b> (483GB472M)..... BF1256	Sensor Port) (20539578)..... BF1384-SP	<b>Radial Seal Air</b> (25100042)..... RS4634
<b>P. Fuel</b> (483GB470AM)..... BF7656	<b>S. Fuel</b> (20539582)..... BF7814	<b>Radial Seal XP Air</b> (25100042)..... RS4634XP
<b>S. Fuel</b> (483GB476M)..... BF7773	<b>Radial Seal Air</b> (57MD320M)..... RS4634	<b>Cab Air</b> (3543H9638)..... PA30277
<b>Radial Seal Air</b> (57MD320M)..... RS4634	<b>Radial Seal XP Air</b> (57MD320M)..... RS4634XP	<b>Air Dryer</b> (Bendix 107794)..... BA5377
<b>Radial Seal XP Air</b> (57MD320M)..... RS4634XP	<b>Air Dryer</b> (Bendix 107796)..... BA5377	<b>Steering</b> (349619)..... P106-HD
<b>Air Dryer</b> (Meritor R950011)..... BA5374 +	<b>Coolant</b> (w/Chemical)	
<b>Coolant</b> (25MF435B)..... BW5178	(20539991)..... BW5183	CXU w/MP7 (10.8L) Eng. (2019)
<b>Opt. Trans.</b> (Fuller 17237)..... B2 +	<b>Coolant</b> (w/o Chemical)	<b>F-F Lube</b> (21707136)..... [2] B76 +
<b>Steering</b> (5839-84365A)..... PT951 +	(20575545)..... B5091	<b>B-P Lube</b> (21707135)..... B7409
<b>Service Kit</b> ..... BK6665	<b>Trans. Ele.</b> (2 In. Kit) (Allison	<b>Severe Service F-F Lube</b>
<b>Service Kit</b> ..... BK6185	29540493)..... PT9416-MPG KIT	(21707136)..... [2] B76-SS +
CXP612 w/MP7 Eng.	<b>Trans. Ele.</b> (4 In. Kit) (Allison	<b>Fuel/Water Separator</b>
<b>F-F Lube</b> (20539275)..... [2] B76 +	29540494)..... PT9415-MPG KIT	(22094987)..... BF46182-O
<b>B-P Lube Spinner</b> (20552379).... BC7242	<b>Opt. Trans. Spin-on</b> (Fuller	<b>Fuel</b> (22094967)..... BF46117
<b>Fuel/Water Separator</b>	17237)..... B2 +	<b>Radial Seal Air</b> (25100042)..... RS4634
(21017305)..... BF1386-O	<b>Steering</b> (5839-87904M)..... PT9354-MPG	<b>Radial Seal XP Air</b> (25100042).... RS4634XP
<b>Fuel/Water Separator</b> (w/Drain &		<b>Cab Air</b> (3543H9638)..... PA30277
Sensor Port) (20539578)..... BF1384-SP	CXU w/MP8 Eng.	<b>Air Dryer</b> (Bendix 107794PG)..... BA5377
<b>Fuel</b> (20539582)..... BF7814	<b>F-F Lube</b> (20539275)..... [2] B76 +	<b>Coolant</b> (21937331)..... BW5183
<b>Radial Seal Air</b> (57MD320M)..... RS4634	<b>B-P Lube Spin-on</b> (20843764).... B7409	<b>Trans.</b> (22038908)..... PT9417
<b>Radial Seal XP Air</b> (57MD320M)..... RS4634XP	<b>Fuel/Water Separator</b>	<b>Steering</b> (349619)..... P106-HD
<b>Coolant</b> (w/Chemical)	(21017305)..... BF1386-O	<b>Opt. Rear Axle</b> (Meritor
(20539991)..... BW5183	<b>Fuel</b> (20972295)..... BF7943	3280V8394)..... B233
<b>Coolant</b> (w/o Chemical)	<b>Radial Seal Air</b> (57MD320M)..... RS4634	<b>Diesel Exhaust Fluid Strainer</b>
(20575545)..... B5091	<b>Radial Seal XP Air</b> (57MD320M)..... RS4634XP	(82269261)..... PE17001
<b>Opt. Trans.</b> (Fuller 17237)..... B2 +	<b>Air Dryer</b> (Bendix 107796)..... BA5377	<b>Diesel Exhaust Fluid Ele.</b>
<b>Steering</b> (5839-87904M)..... PT9354-MPG	<b>Coolant</b> (20575545)..... B5091	(21516229)..... PE17000
	<b>Trans. Ele.</b> (2 In. Kit) (Allison	CXU602 w/MP7 (10.8L) Eng. (2008-17)
	29540493)..... PT9416-MPG KIT	<b>F-F Lube</b> (20539275)..... [2] B76 +
	<b>Trans. Ele.</b> (4 In. Kit) (Allison	<b>B-P Lube Spinner</b> (20552379).... BC7242
	29540494)..... PT9415-MPG KIT	<b>B-P Lube Spin-on</b> (20843764).... B7409
	<b>Trans. Spin-on</b> (Fuller 4304827).. BT223	


+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

**Trucks & Buses Applications** **BALDWIN FILTERS**

MACK Trucks (cont'd)	MACK Trucks (cont'd)	MACK Trucks (cont'd)
CXU602 w/MP7 (10.8L) Eng. (2008-17) (Cont'd)	CXU602 w/MP8 Eng. (Cont'd)	CXU612 w/MP7 Eng. (Cont'd)
Fuel/Water Separator Ele. (Davco 382 System) (Fleetguard FS19765).....	Steering (5839-87904M).....	Fuel/Water Separator Ele. (Davco 382 System) (Fleetguard FS19765).....
<b>PF7930</b>	<b>PT9354-MPG</b>	<b>PF7930</b>
Fuel/Water Separator Ele. (Fleetguard FS19728).....	Diesel Exhaust Fluid Strainer (2010 Emissions) (82269261).....	Fuel/Water Separator Spin-on (21017305).....
<b>PF7782</b>	<b>PE17001</b>	<b>BF1386-O</b>
Fuel/Water Separator Ele. (Remote Mtd.) (301-SD-19B).....	CXU603 w/MP7 Eng.	Fuel (21017305).....
<b>PF7680</b>	F-F Lube (20539275).....	<b>BF1386-O</b>
Fuel/Water Separator Spin-on (21017305).....	B-P Lube Spinner (20552379)....	<b>BF7943</b>
<b>BF1386-O</b>	<b>BC7242</b>	<b>BF7943</b>
Fuel (20539582).....	B-P Lube Spin-on (20843764)....	<b>RS4634</b>
<b>BF7814</b>	<b>B7409</b>	<b>RS4634XP</b>
Fuel (20972295).....	Fuel/Water Separator (21017305).....	<b>RS4634XP</b>
<b>BF7943</b>	<b>BF1386-O</b>	<b>RS4634XP</b>
Radial Seal Air (57MD320M).....	Fuel/Water Separator (Remote Mtd.) (301-SD-19B).....	<b>RS4634XP</b>
<b>RS4634</b>	<b>PF7680</b>	<b>RS4634XP</b>
Radial Seal XP Air (57MD320M).....	Fuel (20539582).....	<b>RS4634XP</b>
<b>RS4634XP</b>	<b>BF7814</b>	<b>RS4634XP</b>
Cab Air (85112361).....	Fuel (20972295).....	<b>RS4634XP</b>
<b>PA30325</b>	Radial Seal Air (57MD320M).....	<b>RS4634XP</b>
Cab Air (3543-H9638).....	Radial Seal XP Air (57MD320M).....	<b>RS4634XP</b>
<b>PA30277</b>	<b>RS4634XP</b>	<b>RS4634XP</b>
Air Dryer (Wabco R950011).....	Cab Air (3543-H9638).....	<b>PA30277</b>
<b>BA5374 +</b>	<b>PA30277</b>	<b>PA30277</b>
Air Dryer (Bendix 107796).....	Air Dryer (Wabco R950011).....	<b>BA5374 +</b>
<b>BA5377</b>	<b>BA5374 +</b>	<b>BA5377</b>
Coolant (w/o Chemical) (20575545).....	Coolant (w/o Chemical) (20575545).....	<b>BA5377</b>
<b>B5091</b>	<b>B5091</b>	<b>BA5377</b>
Coolant (w/Chemical) (20539991).....	Coolant (w/Chemical) (20539991).....	<b>BA5377</b>
<b>BW5183</b>	<b>BW5183</b>	<b>BA5377</b>
Trans. Ele. (mDrive) (20779040)..	Trans. Ele. (2 In. Kit) (Allison 29540493).....	<b>BA5377</b>
<b>PT9417</b>	<b>PT9416-MPG KIT</b>	<b>BA5377</b>
Trans. Ele. (2 In. Kit) (Allison 29540493).....	Trans. Ele. (4 In. Kit) (Allison 29540494).....	<b>BA5377</b>
<b>PT9416-MPG KIT</b>	<b>PT9415-MPG KIT</b>	<b>BA5377</b>
Trans. Ele. (4 In. Kit) (Allison 29540494).....	Trans. Spin-on (Fuller 4304827)..	<b>BA5377</b>
<b>PT9415-MPG KIT</b>	<b>BT223</b>	<b>BA5377</b>
Trans. Spin-on (Fuller 4304827)..	Opt. Trans. Spin-on (Fuller 17237).....	<b>BA5377</b>
<b>BT223</b>	<b>B2 +</b>	<b>BA5377</b>
Opt. Trans. Spin-on (Fuller 17237).....	Steering (5839-87904M).....	<b>BA5377</b>
<b>B2 +</b>	<b>PT9354-MPG</b>	<b>BA5377</b>
Steering (349619).....	CXU603 w/MP8 Eng.	<b>BA5377</b>
<b>P106-HD</b>	F-F Lube (20539275).....	<b>BA5377</b>
Steering (5839-87904M).....	B-P Lube Spinner (20552379)....	<b>BA5377</b>
<b>PT9354-MPG</b>	<b>BC7242</b>	<b>BA5377</b>
Diesel Exhaust Fluid Strainer (82269261).....	B-P Lube Spin-on (20843764)....	<b>BA5377</b>
<b>PE17001</b>	<b>B7409</b>	<b>BA5377</b>
Diesel Exhaust Fluid Pump (21516231).....	Fuel/Water Separator (21017305).....	<b>BA5377</b>
<b>PE17000</b>	<b>BF1386-O</b>	<b>BA5377</b>
CXU602 w/MP8 Eng.	Fuel (20539582).....	<b>BA5377</b>
F-F Lube (20539275).....	<b>BF7814</b>	<b>BA5377</b>
<b>[2] B76 +</b>	Fuel (20972295).....	<b>BA5377</b>
B-P Lube Spinner (20552379)....	Radial Seal Air (57MD320M).....	<b>BA5377</b>
<b>BC7242</b>	<b>RS4634</b>	<b>BA5377</b>
B-P Lube Spin-on (20843764)....	Radial Seal XP Air (57MD320M).....	<b>BA5377</b>
<b>B7409</b>	<b>RS4634XP</b>	<b>BA5377</b>
Fuel/Water Separator (20863191).....	Cab Air (3543-H9638).....	<b>BA5377</b>
<b>BF1386-O</b>	<b>PA30277</b>	<b>BA5377</b>
Fuel (20539582).....	Air Dryer (Wabco R950011).....	<b>BA5377</b>
<b>BF7814</b>	<b>BA5374 +</b>	<b>BA5377</b>
Fuel (20972295).....	Coolant (w/Chemical) (20539991).....	<b>BA5377</b>
<b>BF7943</b>	<b>BW5183</b>	<b>BA5377</b>
Radial Seal Air (57MD320M).....	Coolant (w/o Chemical) (20575545).....	<b>BA5377</b>
<b>RS4634</b>	<b>B5091</b>	<b>BA5377</b>
Radial Seal XP Air (57MD320M).....	Trans. Ele. (2 In. Kit) (Allison 29540493).....	<b>BA5377</b>
<b>RS4634XP</b>	<b>PT9416-MPG KIT</b>	<b>BA5377</b>
Cab Air (3543-H9638).....	Trans. Ele. (4 In. Kit) (Allison 29540494).....	<b>BA5377</b>
<b>PA30277</b>	<b>PT9415-MPG KIT</b>	<b>BA5377</b>
Air Dryer (Wabco R950011).....	Trans. Spin-on (Fuller 4304827)..	<b>BA5377</b>
<b>BA5374 +</b>	<b>BT223</b>	<b>BA5377</b>
Coolant (w/Chemical) (20539991).....	Opt. Trans. Spin-on (Fuller 17237).....	<b>BA5377</b>
<b>BW5183</b>	<b>B2 +</b>	<b>BA5377</b>
Coolant (w/o Chemical) (20575545).....	Steering (5839-87904M).....	<b>BA5377</b>
<b>B5091</b>	<b>PT9354-MPG</b>	<b>BA5377</b>
Trans. Ele. (2 In. Kit) (Allison 29540493).....	CXU612 w/MP7 Eng.	<b>BA5377</b>
<b>PT9416-MPG KIT</b>	F-F Lube (21707136).....	<b>BA5377</b>
Trans. Ele. (4 In. Kit) (Allison 29540494).....	B-P Lube Spinner (20552379)....	<b>BA5377</b>
<b>PT9415-MPG KIT</b>	<b>BC7242</b>	<b>BA5377</b>
Trans. Spin-on (Fuller 4304827)..	B-P Lube Spin-on (20843764)....	<b>BA5377</b>
<b>BT223</b>	<b>B7409</b>	<b>BA5377</b>
Opt. Trans. Spin-on (Fuller 17237).....	Severe Service F-F Lube (21707136).....	<b>BA5377</b>
<b>B2 +</b>	<b>[2] B76-SS +</b>	<b>BA5377</b>
CXU612 w/MP8 Eng.	F-F Lube (20539275).....	<b>BA5377</b>
F-F Lube (20539275).....	B-P Lube Spinner (20552379)....	<b>BA5377</b>
<b>[2] B76 +</b>	<b>BC7242</b>	<b>BA5377</b>
B-P Lube Spinner (20539275)....	B-P Lube Spin-on (20843764)....	<b>BA5377</b>
<b>B7409</b>	<b>B7409</b>	<b>BA5377</b>
Severe Service F-F Lube (20539275).....	Fuel/Water Separator (21017305).....	<b>BA5377</b>
<b>[2] B76-SS +</b>	<b>BF1386-O</b>	<b>BA5377</b>
Fuel/Water Separator (21017305).....	Fuel (21017305).....	<b>BA5377</b>
<b>BF1386-O</b>	<b>BF1386-O</b>	<b>BA5377</b>
Fuel (20972295).....	Fuel (20972295).....	<b>BA5377</b>
<b>BF7943</b>	<b>BF7943</b>	<b>BA5377</b>
Radial Seal Air (57MD320M).....	Radial Seal Air (57MD320M).....	<b>BA5377</b>
<b>RS4634</b>	<b>RS4634</b>	<b>BA5377</b>
Radial Seal XP Air (57MD320M).....	Radial Seal XP Air (57MD320M).....	<b>BA5377</b>
<b>RS4634XP</b>	<b>RS4634XP</b>	<b>BA5377</b>
Cab Air (3543-H9638).....	Cab Air (3543-H9638).....	<b>BA5377</b>
<b>PA30277</b>	<b>PA30277</b>	<b>BA5377</b>
Air Dryer (Wabco R950011).....	Air Dryer (Wabco R950011).....	<b>BA5377</b>
<b>BA5374 +</b>	<b>BA5374 +</b>	<b>BA5377</b>
Coolant (20575545).....	Coolant (20575545).....	<b>BA5377</b>
<b>B5091</b>	<b>B5091</b>	<b>BA5377</b>
Trans. Ele. (2 In. Kit) (Allison 29540493).....	Trans. Ele. (2 In. Kit) (Allison 29540493).....	<b>BA5377</b>
<b>PT9416-MPG KIT</b>	<b>PT9416-MPG KIT</b>	<b>BA5377</b>
Trans. Ele. (4 In. Kit) (Allison 29540494).....	Trans. Ele. (4 In. Kit) (Allison 29540494).....	<b>BA5377</b>
<b>PT9415-MPG KIT</b>	<b>PT9415-MPG KIT</b>	<b>BA5377</b>
Trans. Spin-on (Fuller 4304827)..	Trans. Spin-on (Fuller 4304827)..	<b>BA5377</b>
<b>BT223</b>	<b>BT223</b>	<b>BA5377</b>
Opt. Trans. Spin-on (Fuller 17237).....	Opt. Trans. Spin-on (Fuller 17237).....	<b>BA5377</b>
<b>B2 +</b>	<b>B2 +</b>	<b>BA5377</b>
2 23/32 In. Steering (5839-87904M).....	2 23/32 In. Steering (5839-87904M).....	<b>BA5377</b>
<b>PT9354-MPG</b>	<b>PT9354-MPG</b>	<b>BA5377</b>
4 1/8 In. Steering (Nelson 870678A).....	4 1/8 In. Steering (Nelson 870678A).....	<b>BA5377</b>
<b>PT9394-MPG</b>	<b>PT9394-MPG</b>	<b>BA5377</b>
Diesel Exhaust Fluid (21496421).....	Diesel Exhaust Fluid (21496421).....	<b>BA5377</b>
<b>PE17000</b>	<b>PE17000</b>	<b>BA5377</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MACK Trucks (cont'd)	MACK Trucks (cont'd)	MACK Trucks (cont'd)
CXU613 w/MP7 (10.8L) Eng. (2008-17)	CXU613 w/MP8 (12.8L) Eng. (2008-17)	CXU613 w/MP8 (12.8L) Eng. (2018) (Cont'd)
F-F Lube (21707136)..... [2] B76 +	F-F Lube (21707136)..... [2] B76 +	Diesel Exhaust Fluid (Tank Strainer) (82269261)..... PE17001
B-P Lube Spinner (20552379)..... BC7242	B-P Lube Spinner (20552379)..... BC7242	CXU613 w/MP8 (12.8L) Eng. (2019)
B-P Lube Spin-on (21707135)..... B7409	B-P Lube Spin-on (21707135)..... B7409	F-F Lube (21707136)..... [2] B76 +
Fuel/Water Separator Ele. (Davco 382 System) (Fleetguard FS19765)..... PF7930	Fuel/Water Separator Ele. (Davco 382 System) (Fleetguard FS19765)..... PF7930	B-P Lube (21707135)..... B7409
Fuel/Water Separator Ele. (Remote Mtd.) (301-SD-19C)..... PF7680	Fuel/Water Separator Ele. (Fleetguard FS19728)..... PF7782	Severe Service F-F Lube (21707136)..... [2] B76-SS +
Fuel/Water Separator Spin-on (21380521)..... BF1386-O	Fuel/Water Separator Ele. (Remote Mtd.) (301-SD-19B)..... PF7680	Fuel/Water Separator (21737481)..... PF7930
Fuel (20539582)..... BF7814	Fuel/Water Separator Spin-on (21017305)..... BF1386-O	Fuel/Water Separator (22094987)..... BF46182-O
Fuel (20972295)..... BF7943	Fuel (20539582)..... BF7814	Fuel/Water Separator (Fleetguard FS19765G)..... PF46094
Radial Seal Air (25100042)..... RS4634	Fuel (20972295)..... BF7943	Fuel (22094967)..... BF46117
Radial Seal XP Air (25100042)..... RS4634XP	Radial Seal Air (57MD320M)..... RS4634	Radial Seal Air (25100042)..... RS4634
Cab Air (3543-H9638)..... PA30277	Radial Seal XP Air (57MD320M)..... RS4634XP	Radial Seal XP Air (25100042)..... RS4634XP
Cab Air (85112361)..... PA30325	Cab Air (3543-H9638)..... PA30277	Cab Air (3543H9638)..... PA30277
Air Dryer (Wabco R950011)..... BA5374 +	Cab Air (85112361)..... PA30325	Air Dryer (Bendix 107794PG)..... BA5377
Air Dryer (85110799)..... BA5592 <sup>90</sup>	Air Dryer (Wabco R950011)..... BA5374 +	Coolant (21937331)..... BW5183
Air Dryer (Bendix 107796)..... BA5377	Air Dryer (Bendix 107796)..... BA5377	Trans. (22038908)..... PT9417
Air Dryer (Wabco R950068)..... BA5379 +	Air Dryer (Wabco R950068)..... BA5379 +	Steering (349619)..... P106-HD
Coolant (w/Chemical) (21937331)..... BW5183	Coolant (w/o Chemical) (20575545)..... B5091	Opt. Rear Axle (Meritor 3280V8394)..... B233
Coolant (w/o Chemical) (20575545)..... B5091	Coolant (w/Chemical) (21937331)..... BW5183	Diesel Exhaust Fluid Strainer (82269261)..... PE17001
Trans. Ele. (mDrive) (20779040)..... PT9417	Trans. Ele. (mDrive) (20779040)..... PT9417	Diesel Exhaust Fluid Ele. (21516229)..... PE17000
Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	DM w/Cat 3208 (10.4L) Eng.
Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Lube (9N5570)..... [2] BT230 +
Trans. Spin-on (Fuller 4304827)..... BT223	Trans. (Fuller 4304827)..... BT223	Lube (9L9200)..... [2] BT364
Opt. Trans. Spin-on (Fuller 17237)..... B2 +	Opt. Trans. (Fuller 17237)..... B2 +	Box-Style Fuel/Water Separator..... BF912
2 23/32 In. Steering (Nelson 87904M)..... PT9354-MPG	2 23/32 In. Steering (Nelson 87904M)..... PT9354-MPG	Fuel Spin-on..... BF970 +
3 31/32 In. Steering (349619)..... P106-HD	3 31/32 In. Steering (349619)..... P106-HD	Air (2MD3129)..... PA2312
4 1/8 In. Steering (Nelson 870678A)..... PT9394-MPG	4 1/8 In. Steering (Nelson 870678A)..... PT9394-MPG	Air (2MD4003)..... PA2482
Diesel Exhaust Fluid Strainer (2010 Emissions) (82269261)..... PE17001	Diesel Exhaust Fluid Strainer (82269261)..... PE17001	Air (2MD491)..... PA2465
Diesel Exhaust Fluid Pump (2010 Emissions) (21516231)..... PE17000	Diesel Exhaust Fluid Pump (21516231)..... PE17000	DM w/Cummins N14 (14.0L) Eng.
CXU613 w/MP7 (10.8L) Eng. (2018)	CXU613 w/MP8 (12.8L) Eng. (2018)	Dual-Flow Lube (3318853)..... BD103 +
F-F Lube (21707136)..... [2] B76 +	F-F Lube (21707136)..... [2] B76 +	F-F Lube (Fleetguard LF670SC)..... B196 +
B-P Lube (21707135)..... B7409	B-P Lube (21707135)..... B7409	B-P Lube (1W8845)..... B7577
Severe Service F-F Lube (21707136)..... [2] B76-SS +	Severe Service F-F Lube (21707136)..... [2] B76-SS +	Opt. Fuel/Water Separator (3308638)..... BF1212 +
Fuel/Water Separator (22094987)..... BF46182-O	Fuel/Water Separator (22094987)..... BF46182-O	Fuel (154789)..... BF957-D +
Fuel (22094967)..... BF46117	Fuel (22094967)..... BF46117	Coolant (4 Units BTA PLUS) (3315116)..... BW5071
Radial Seal Air (25100042)..... RS4634	Radial Seal Air (25100042)..... RS4634	DM w/AI Series Eng.
Radial Seal XP Air (25100042)..... RS4634XP	Radial Seal XP Air (25100042)..... RS4634XP	F-F Lube (485GB3236)..... [2] B7225 +
Cab Air (3543H9638)..... PA30277	Cab Air (3543H9638)..... PA30277	B-P Lube Spinner (To 11/11/03) (57GC2206)..... BC7228
Air Dryer (Bendix 107794)..... BA5377	Air Dryer (Bendix 107794)..... BA5377	B-P Lube Spinner (11/11/03-on) (57GC2231)..... BC7242
Coolant (21937331)..... BW5183	Coolant (21937331)..... BW5183	Opt. Fuel/Water Separator (483GB477M)..... BF1286
Trans. (22038908)..... PT9417	Trans. (22038908)..... PT9417	Opt. Fuel/Water Separator (483GB472M)..... BF1256
Steering (349619)..... P106-HD	Steering (349619)..... P106-HD	P. Fuel (483GB470AM)..... BF7656
Diesel Exhaust Fluid (21516231)..... PE17000	Diesel Exhaust Fluid (21516231)..... PE17000	S. Fuel (483GB471M)..... BF7657
		Radial Seal Air (57MD317)..... RS4618
		Air Dryer (Bendix 107796)..... BA5377

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.

Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MACK Trucks (cont'd)	MACK Trucks (cont'd)	MACK Trucks (cont'd)
DM w/Al Series Eng. (Cont'd)	DM w/AMI-300 (11.9L) Eng. (2004-06) (Cont'd)	DM400, MB400, R400, RD400, U400 Series w/ENDT475 Eng.
Crankcase Breather..... CLN&R	Opt. Trans. Spin-on (Fuller 17237)..... B2 +	P. Fuel Spin-on..... BF877 +
Coolant (25MF435B)..... BW5178	Steering (Open Both Ends) (5839-84148A)..... P528	S. Fuel Spin-on..... BF876
Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	Steering (Closed One End) (5839-870678A)..... PT9394-MPG	Coolant Spin-on..... BW5178
Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Service Kit (215SB325A)..... BK6693	Turbocharger (6432PER17)..... B163
Opt. Trans. Spin-on (Fuller 17237)..... B2 +	DM w/E4 (7.8L) Eng.	DM487, MB487, R487, RD487, RM487 w/ETZ477 Eng.
Steering (Open Both Ends) (5839-84148A)..... P528	Trans. (Fuller 4304827)..... BT223	Lube Spin-on..... B163
Steering (Closed One End) (5839-870678A)..... PT9394-MPG	Opt. Trans. (Fuller 17237)..... B2 +	P. Fuel Spin-on..... BF877 +
Service Kit (215SB325A)..... BK6693	DM w/E6 (11.0L) Eng.	S. Fuel Spin-on..... BF876
DM w/AMI-300 (11.9L) Eng. (To 2003)	Fuel/Water Separator (483GB433B)..... BF1219 +	Air (2MD3129)..... PA2312
F-F Lube (485GB3236)..... [2] B7225 +	Trans. (Fuller 4304827)..... BT223	Air (2MD4003)..... PA2482
B-P Lube Spinner (To 11/11/03) (57GC2206)..... BC7228	Opt. Trans. (Fuller 17237)..... B2 +	DM600, MB600, MC600, R600, RD600, RL600, RS600, U600 Series w/ENDT675, ENDT676 Engs.
B-P Lube Spinner (11/11/03-on) (57GC2231)..... BC7242	DM w/E7 (11.9L) Eng.	ESI-Plus Service Kit (1977-on, (6 Spin-ons))..... BK6710
Opt. Fuel/Water Separator (483GB477M)..... BF1286	F-F Lube (485GB3232)..... [2] B7225 +	Std. Service Kit (1972-on, (5 Spin-ons))..... BK6700
Opt. Fuel/Water Separator (483GB472M)..... BF1256	B-P Lube Spinner (57GC2206)..... BC7228	DM600, MB600, R600, RD600, RL600, RS600, U600 Series w/ENDT673, ENDT673C, ENDTL673C Engs.
P. Fuel (483GB470AM)..... BF7656	Fuel/Water Separator (483GB433B)..... BF1219 +	Dual-Flow Lube Ele. (1961-71).... P706-M
S. Fuel (483GB471M)..... BF7657	Fuel (483GB476M)..... BF7773	F-F Lube Ele. (To 1961)..... [2] P194 +
Radial Seal Air (57MD317)..... RS4618	Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	Fuel (w/APE Fuel Pump)..... PF819
Air Dryer (Bendix 107796)..... BA5377	Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Std. Service Kit (5 Spin-ons)..... BK6710
Crankcase Breather..... CLN&R	Trans. (Fuller 4304827)..... BT223	DM600, MB600, R600, RD600, U600 Series w/END673E Eng.
Coolant (25MF435B)..... BW5178	Opt. Trans. (Fuller 17237)..... B2 +	ESI-Plus Service Kit (1977-on, (6 Spin-ons))..... BK6710
Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	DM w/E9 (16.4L) Eng.	Std. Service Kit (1972-on, (5 Spin-ons))..... BK6700
Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Fuel/Water Separator (483GB433B)..... BF1219 +	DM607, MB607, R607, RD607, U607 Series w/END673E Eng.
Opt. Trans. Spin-on (Fuller 17237)..... B2 +	Trans. (Fuller 4304827)..... BT223	Air (2MD3129)..... PA2312
Steering (Open Both Ends) (5839-84148A)..... P528	Opt. Trans. (Fuller 17237)..... B2 +	Air (2MD4003)..... PA2482
Steering (Closed One End) (5839-870678A)..... PT9394-MPG	DM w/EM6 (11.0L) Eng.	ESI-Plus Service Kit (1977-on, (6 Spin-ons))..... BK6710
Service Kit (215SB325A)..... BK6693	F-F Lube..... [2] B76 +	Std. Service Kit (1972-on, (5 Spin-ons))..... BK6700
DM w/AMI-300 (11.9L) Eng. (2004-06)	B-P Lube..... BC110	DM609, R609 Series w/END711 Eng.
F-F Lube (485GB3236)..... [2] B7225 +	Severe Service F-F Lube..... [2] B76-SS +	Dual-Flow Lube Ele. (1962-71).... P706-M
B-P Lube Spinner (57GC2231).... BC7242	P. Fuel..... BF877 +	Fuel Ele. (237GB13)..... PF819
Opt. Fuel/Water Separator (483GB477M)..... BF1286	S. Fuel..... BF976	Fuel Ele. (237GB29)..... PF826
Opt. Fuel/Water Separator (483GB472M)..... BF1256	ESI-Plus Service Kit (6 Spin-ons) BK6710	Air (2MD455-AP2)..... PA1681-FN
P. Fuel (483GB470AM)..... BF7656	Service Kit (5 Spin-ons + B-P Spinner)..... BK6720	Air (2MD4003)..... PA2482
S. Fuel (483GB471M)..... BF7657	DM w/EM6-L (11.0L) Eng.	Air (2MD3129)..... PA2312
Radial Seal Air (57MD317)..... RS4618	F-F Lube..... [2] B76 +	Std. Service Kit (1972-on, (5 Spin-ons))..... BK6700
Air Dryer (Bendix 107796)..... BA5377	B-P Lube..... BC110	DM611, DMM611, R611, RD611 Series w/ET673 Eng.
Crankcase Breather..... CLN&R	Severe Service F-F Lube..... [2] B76-SS +	Air (2MD3129)..... PA2312
Coolant (25MF435B)..... BW5178	P. Fuel..... BF877 +	Air (2MD4003)..... PA2482
Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	S. Fuel..... BF976	Air (2MD455-AP2)..... PA1681-FN
Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	ESI-Plus Service Kit (6 Spin-ons) BK6710	DM611, DMM611, R611, RD611 Series w/ET673 Eng.
	Service Kit (5 Spin-ons + B-P Spinner)..... BK6720	Air (2MD3129)..... PA2312
	DM w/EM9 (16.4L) Eng.	Air (2MD4003)..... PA2482
	Trans. (Fuller 4304827)..... BT223	Air (2MD4007)..... PA2439
	Opt. Trans. (Fuller 17237)..... B2 +	Air (2MD455-AP2)..... PA1681-FN

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



MACK Trucks (cont'd)	MACK Trucks (cont'd)	MACK Trucks (cont'd)
DM611, DMM611, R611, RD611 Series w/ET673 Eng. (Cont'd) Std. Service Kit (1972-on, (5 Spin-ons))..... <b>BK6700</b>	DM690S w/EM7-L (11.9L) Eng. (Cont'd) Steering (Open Both Ends) (5839-84148A)..... <b>P528</b> Service Kit (215SB325A)..... <b>BK6693</b>	DMC w/EM6 (11.0L) Eng. Fuel/Water Separator (483GB433B)..... <b>BF1219 +</b>
DM685, DMM685, HMM685, MB685, R685, RD685, RM685, U685, DM686, DMM686, R686 RM686, U686 Air (Don. P130774)..... <b>PA2439</b> Air (Don. P130775)..... <b>PA2438</b> Air (57MD26)..... <b>PA2312</b> Air (57MD33)..... <b>PA2317 +</b> Air (2MD4003)..... <b>PA2482</b> Air (2MD4004)..... <b>PA2558</b> Air (2MD455-AP2)..... <b>PA1681-FN</b> ESI-Plus Service Kit (1977-on, (6 Spin-ons))..... <b>BK6710</b> Std. Service Kit (1972-on, (5 Spin-ons))..... <b>BK6700</b>	DM800 Series w/Cummins NTC350, NTA400 Engs. F-F Lube Spin-on..... <b>B196 +</b> B-P Lube Ele..... <b>C750-E +</b> Fuel/Water Separator..... <b>BF1212 +</b> Fuel Spin-on..... <b>BF957 +</b> Fuel Spin-on..... <b>BF596 +</b> Breather Ele. (w/Turbo) (255963) <b>PA643</b> Breather Ele. (w/o Turbo) (256837)..... <b>PA1627</b>	DMM w/E6 (11.0L) Eng. Fuel/Water Separator (483GB433B)..... <b>BF1219 +</b>
DM690S w/EM7 (11.9L) Eng. F-F Lube (485GB3236)..... <b>[2] B7225 +</b> B-P Lube Spinner (57GC2231)... <b>BC7242</b> Opt. Fuel/Water Separator (483GB477M)..... <b>BF1286</b> P. Fuel (483GB470M)..... <b>BF7656</b> S. Fuel (483GB471M)..... <b>BF7657</b> Radial Seal Air (57MD317)..... <b>RS4618</b> Air Dryer (Bendix 107796)..... <b>BA5377</b> Coolant (25MF435B)..... <b>BW5178</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Steering (Closed One End) (5839-870678A)..... <b>PT9394-MPG</b> Steering (Open Both Ends) (5839-84148A)..... <b>P528</b> Service Kit (215SB325A)..... <b>BK6693</b>	DM800, F800 Series w/ENDT673, ENDT673C, ENDT675, ENDT676, ENDT865, ENDT866 Engs. Std. Service Kit (1972-on, (5 Spin-ons))..... <b>BK6700</b> ESI-Plus Service Kit (1977-on, (6 Spin-ons))..... <b>BK6710</b>	DMM w/EM6 (11.0L) Eng. F-F Lube..... <b>[2] B76 +</b> B-P Lube..... <b>BC110</b> Severe Service F-F Lube..... <b>[2] B76-SS +</b> P. Fuel..... <b>BF877 +</b> S. Fuel..... <b>BF976</b> ESI-Plus Service Kit (6 Spin-ons) <b>BK6710</b> Service Kit (5 Spin-ons + B-P Spinner)..... <b>BK6720</b>
DM690S w/EM7-L (11.9L) Eng. F-F Lube (485GB3236)..... <b>[2] B7225 +</b> B-P Lube Spinner (57GC2231)... <b>BC7242</b> Opt. Fuel/Water Separator (483GB477M)..... <b>BF1286</b> P. Fuel (483GB470M)..... <b>BF7656</b> S. Fuel (483GB471M)..... <b>BF7657</b> Radial Seal Air (57MD317)..... <b>RS4618</b> Air Dryer (Bendix 107796)..... <b>BA5377</b> Coolant (25MF435B)..... <b>BW5178</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Steering (Closed One End) (5839-870678A)..... <b>PT9394-MPG</b> Steering (Open Both Ends) (5839-84148A)..... <b>P528</b> Service Kit (215SB325A)..... <b>BK6693</b>	DM811 w/ET673 Eng. Air (2MD455-AP2)..... <b>PA1681-FN</b> Air (57MD26)..... <b>PA2312</b> Air (Don. P130774)..... <b>PA2439</b> ESI-Plus Service Kit (1977-on, (6 Spin-ons))..... <b>BK6710</b>	DMM w/EM6-L (11.0L) Eng. F-F Lube..... <b>[2] B76 +</b> B-P Lube..... <b>BC110</b> Severe Service F-F Lube..... <b>[2] B76-SS +</b> P. Fuel..... <b>BF877 +</b> S. Fuel..... <b>BF976</b> ESI-Plus Service Kit (6 Spin-ons) <b>BK6710</b> Service Kit (5 Spin-ons + B-P Spinner)..... <b>BK6720</b>
DM690S w/EM7-L (11.9L) Eng. F-F Lube (485GB3236)..... <b>[2] B7225 +</b> B-P Lube Spinner (57GC2231)... <b>BC7242</b> Opt. Fuel/Water Separator (483GB477M)..... <b>BF1286</b> P. Fuel (483GB470M)..... <b>BF7656</b> S. Fuel (483GB471M)..... <b>BF7657</b> Radial Seal Air (57MD317)..... <b>RS4618</b> Air Dryer (Bendix 107796)..... <b>BA5377</b> Coolant (25MF435B)..... <b>BW5178</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Steering (Closed One End) (5839-870678A)..... <b>PT9394-MPG</b>	DM812 w/ETAZ673A Eng. Air (Don. P130774)..... <b>PA2439</b> Air (Don. P130775)..... <b>PA2438</b> Std. Service Kit (1972-on, (5 Spin-ons))..... <b>BK6700</b> ESI-Plus Service Kit (1977-on, (6 Spin-ons))..... <b>BK6710</b>	DMM600 w/AMI-300 Eng. F-F Lube Spin-on (485GB3236).. <b>[2] B7225 +</b> B-P Lube Spinner (57GC2231)... <b>BC7242</b> P. Fuel (483GB470M)..... <b>BF7656</b> S. Fuel (483GB471M)..... <b>BF7657</b>
DM690S w/EM7-L (11.9L) Eng. F-F Lube (485GB3236)..... <b>[2] B7225 +</b> B-P Lube Spinner (57GC2231)... <b>BC7242</b> Opt. Fuel/Water Separator (483GB477M)..... <b>BF1286</b> P. Fuel (483GB470M)..... <b>BF7656</b> S. Fuel (483GB471M)..... <b>BF7657</b> Radial Seal Air (57MD317)..... <b>RS4618</b> Air Dryer (Bendix 107796)..... <b>BA5377</b> Coolant (25MF435B)..... <b>BW5178</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Steering (Closed One End) (5839-870678A)..... <b>PT9394-MPG</b>	DM885 w/ENDT675 Eng. Air (2MD455-AP2)..... <b>PA1681-FN</b> Air (57MD26)..... <b>PA2312</b> Air (Don. P130774)..... <b>PA2439</b> Std. Service Kit (1972-on, (5 Spin-ons))..... <b>BK6700</b> ESI-Plus Service Kit (1977-on, (6 Spin-ons))..... <b>BK6710</b>	DMM600 w/E7 E-Tech Eng. F-F Lube Spin-on (485GB3191B)..... <b>[2] B76 +</b> B-P Lube Spinner (57GC2134A). <b>BC110</b> B-P Lube Spinner (57GC2187)... <b>BC7173</b> P. Fuel (483GB470M)..... <b>BF7656</b> S. Fuel (483GB471M)..... <b>BF7657</b> Coolant (25MF435B)..... <b>BW5178</b> Service Kit (57GC2177A)..... <b>BK6705</b>
DM690S w/EM7-L (11.9L) Eng. F-F Lube (485GB3236)..... <b>[2] B7225 +</b> B-P Lube Spinner (57GC2231)... <b>BC7242</b> Opt. Fuel/Water Separator (483GB477M)..... <b>BF1286</b> P. Fuel (483GB470M)..... <b>BF7656</b> S. Fuel (483GB471M)..... <b>BF7657</b> Radial Seal Air (57MD317)..... <b>RS4618</b> Air Dryer (Bendix 107796)..... <b>BA5377</b> Coolant (25MF435B)..... <b>BW5178</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Steering (Closed One End) (5839-870678A)..... <b>PT9394-MPG</b>	DM886 w/ENDT676 Eng. Air (2MD4004)..... <b>PA2558</b> Air (Don. P130774)..... <b>PA2439</b> Air (Don. P130775)..... <b>PA2438</b> Std. Service Kit (1972-on, (5 Spin-ons))..... <b>BK6700</b> ESI-Plus Service Kit (1977-on, (6 Spin-ons))..... <b>BK6710</b>	F w/E6 (11.0L) Eng. Fuel/Water Separator (483GB433B)..... <b>BF1219 +</b>
DM690S w/EM7-L (11.9L) Eng. F-F Lube (485GB3236)..... <b>[2] B7225 +</b> B-P Lube Spinner (57GC2231)... <b>BC7242</b> Opt. Fuel/Water Separator (483GB477M)..... <b>BF1286</b> P. Fuel (483GB470M)..... <b>BF7656</b> S. Fuel (483GB471M)..... <b>BF7657</b> Radial Seal Air (57MD317)..... <b>RS4618</b> Air Dryer (Bendix 107796)..... <b>BA5377</b> Coolant (25MF435B)..... <b>BW5178</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Steering (Closed One End) (5839-870678A)..... <b>PT9394-MPG</b>	DM895, DM897, F900 Series w/ENDT865 Eng. Air (57MD33)..... <b>PA2317 +</b> Std. Service Kit (1972-on, (5 Spin-ons))..... <b>BK6700</b>	F w/EM6 (11.0L) Eng. Fuel/Water Separator (483GB433B)..... <b>BF1219 +</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>MACK Trucks (cont'd)</b>	<b>MACK Trucks (cont'd)</b>	<b>MACK Trucks (cont'd)</b>
F223T F-F Lube (236GB123A)..... P194 +	F785 w/ENDT675 Eng. Air (57MD26)..... PA2312 Air (57MD33)..... PA2317 + Std. Service Kit (1972-on, (5 Spin-ons))..... BK6700 ESI-Plus Service Kit (1977-on, (6 Spin-ons))..... BK6710	Freedom L w/Renault E3 Eng. (Cont'd) P. Fuel (Renault 5000541768)..... BF877 + S. Fuel (Renault 5000133546)..... BF876 Radial Seal Air (5010315990)..... RS5301 Coolant (Renault 5000133551).... BW5178 Opt. Trans. (Fuller 17237)..... B2 + Steering (5000820895)..... P106-HD
F700, FL700, FS700, RL700, RS700, WL700, WS700 w/ENDTL673C Eng. F-F Lube Ele. (To 1961)..... [2] P194 + Dual-Flow Lube Ele. (1961-71).... P706-M Fuel (w/APE Fuel Pump)..... PF819 Fuel (w/PSJ, PSM Fuel Pump)..... PF826 Std. Service Kit (1972-on, (5 Spin-ons))..... BK6700	F786 w/ENDT676 Eng. Air (Don. P130774)..... PA2439 Air (Don. P130775)..... PA2438 Std. Service Kit (1972-on, (5 Spin-ons))..... BK6700 ESI-Plus Service Kit (1977-on, (6 Spin-ons))..... BK6710	Freedom M w/Renault E3 Eng. Lube (485GB3191B)..... B76 + P. Fuel (6449-6650559370)..... [2] BF7886 P. Fuel (Renault 5000541768)..... [2] BF877 + S. Fuel (Renault 5000133546)..... [2] BF876 Radial Seal Air (5010315990)..... RS5301 Coolant (Renault 5000133551).... BW5178 Opt. Trans. (Fuller 17237)..... B2 + Steering (5000820895)..... P106-HD
F700, FL700, FS700, RL700, RS700, WL700, WS700 Series w/ET673, END673E, ETAZ673A ENDT675, ENDT676 E ESI-Plus Service Kit (1977-on, (6 Spin-ons))..... BK6710 Std. Service Kit (1972-on, (5 Spin-ons))..... BK6700	F795, R795, RD795, F797, R797, RD797 w/ENDT866 Eng. Air (57MD26)..... PA2312 Air (57MD33)..... PA2317 + Std. Service Kit (1972-on, (5 Spin-ons))..... BK6700	Freedom MV w/Renault E3 Eng. Lube (485GB3191C)..... [2] B76 + Fuel (7/01-7/03) (6449-6650559370)..... BF7886 Fuel (7/01-7/03) (7058-36525)..... BF46064-D
F700, FL700, R700, RD700, RL700, RS700, U700, WL700, WS700 Series w/ENDT865, ENDT866 Engs. Std. Service Kit (1972-on, (5 Spin-ons))..... BK6700	FL700, FS700, RL700, RS700 Series w/Cat 1674 Eng. Lube Ele..... PT670 Lube Spin-on..... B99 + Fuel Spin-on..... BF970 + Air (w/Lid) (Don. P153551)..... PA2705 Air (w/o Lid) (Don. P154575)..... PA2715 Air Comp. Breather..... PA1704	Freedom XL w/Renault E3 Eng. Lube (485GB3191B)..... B76 + P. Fuel (6449-6650559370)..... [2] BF7886 P. Fuel (Renault 5000541768)..... BF877 + S. Fuel (Renault 5000133546)..... BF876 Radial Seal Air (5010315990)..... RS5301 Coolant (Renault 5000133551).... BW5178 Opt. Trans. (Fuller 17237)..... B2 + Steering (5000820895)..... P106-HD
F711, F712 Series w/ET673, ETAZ673A Eng. Air (57MD26)..... PA2312 Air (57MD33)..... PA2317 + Std. Service Kit (57GC294)..... BK6700 ESI-Plus Service Kit (57GC295A)..... BK6710	FL700, FS700, RL700, RS700 Series w/Cat 1693T, 1693TA Eng. Lube Ele..... [2] PT88-HD Lube Spin-on..... B99 + Fuel Ele..... [2] PF823 + Fuel Spin-on..... [2] BF970 + Air Comp. Breather..... PA1704	Freedom XXL w/Renault E3 Eng. Lube (485GB3191B)..... B76 + P. Fuel (6449-6650559370)..... [2] BF7886 P. Fuel (Renault 5000541768)..... BF877 + S. Fuel (Renault 5000133546)..... BF876 Radial Seal Air (5010315990)..... RS5301 Coolant (Renault 5000133551).... BW5178 Opt. Trans. (Fuller 17237)..... B2 + Steering (5000820895)..... P106-HD
F747 w/Cummins NTC290 Eng. F-F Lube Spin-on..... B196 + B-P Lube Ele..... C750-E + Fuel/Water Separator..... BF1212 + 5 3/4 In. Fuel Spin-on..... BF957 + 11 7/32 In. Fuel Spin-on..... BF596 + Air (57MD26)..... PA2312 Air (57MD33)..... PA2317 + Breather Ele. (w/Turbo) (255963) PA643 Breather Ele. (w/o Turbo) (256837)..... PA1627	FCM Series w/E7 E-Tech Eng. F-F Lube (485GB3191B)..... [2] B76 + B-P Lube Spinner (57GC2134A).... BC110 B-P Lube Spinner (57GC2187).... BC7173 P. Fuel (483GB470M)..... BF7656 S. Fuel (483GB471M)..... BF7657 Coolant (25MF435B)..... BW5178 Service Kit (57GC2177A)..... BK6705	Granite w/Cummins ISL 8.9 (8.9L) Eng. (2019) Lube (3401544)..... B40142 Fuel/Water Separator (Fleetguard FS19764)..... PF9814 Fuel (5303743)..... BF63000 Air (25042054)..... PA2680 Air Dryer (Bendix 107794PG)..... BA5377 Trans. (2 In. Kit) (Allison 29548987)..... PT9416-MPG KIT Trans. (4 In. Kit) (Allison 29548988)..... PT9415-MPG KIT
F767 w/Cummins NTC350 Eng. F-F Lube Spin-on..... B196 + B-P Lube Ele..... C750-E + Fuel/Water Separator..... BF1212 + 5 3/4 In. Fuel Spin-on..... BF957 + 11 7/32 In. Fuel Spin-on..... BF596 + 10 3/8 In. O.D. O. Air (57MD26).... PA2312 12 3/4 In. O.D. Air (57MD33)..... PA2317 + Breather Ele. (w/Turbo) (255963) PA643 Breather Ele. (w/o Turbo) (256837)..... PA1627	Fleet-Liner w/EAT-435 CCRS Eng. Opt. Trans. (Fuller 17237)..... B2 +	Granite w/Cummins ISL 8.9 (8.9L) Eng. (2020) Lube (5444774)..... B40142 Fuel/Water Separator (Fleetguard FS19728)..... PF7782 Fuel/Water Separator (Fleetguard FS19764)..... PF9814 Fuel (5303743)..... BF63000 Radial Seal Air (25100042)..... RS4634
F773, R773 Series w/GMC 8V-71 Eng. F-F Lube Ele..... P20-HD + P. Fuel Spin-on..... BF5800 + S. Fuel Spin-on..... BF5810 Air (57MD26)..... PA2312 Air (57MD33)..... PA2317 +	Freedom w/E3-210 Eng. F-F Lube (485GB3191C)..... [2] B76 + Fuel Spin-on (5010450824)..... BF7886 Radial Seal Air (Standard Media) (5010315990)..... RS5301 Radial Seal Air (Flame Retardant Media) (5001865724)..... RS30236	
	Freedom L w/Renault E3 Eng. Lube (485GB3191B)..... B76 + Fuel/Water Separator (7058-5001858091)..... BF7679-D P. Fuel (5001852912)..... PF7939	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).


MACK Trucks (cont'd)	MACK Trucks (cont'd)	MACK Trucks (cont'd)
Granite w/Cummins ISL 8.9 (8.9L) Eng. (2020) (Cont'd)	Granite w/MP7 (10.8L) Eng. (2020) (Cont'd)	Granite w/MP8 (12.8L) Eng. (2020) (Cont'd)
Radial Seal XP Air (25100042).... <b>RS4634XP</b>	Air Dryer (21620181)..... <b>BA5379</b>	Trans. Ele. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>
Cab Air (85151124)..... <b>PA30325</b>	Coolant (21937331)..... <b>BW5183</b>	Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>
Air Dryer (21620181)..... <b>BA5379</b>	Trans. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	Trans. Spin-on (Fuller 4304827).. <b>BT223</b>
Trans. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	Trans. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>
Trans. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	Granite w/MP8 (12.8L) Eng. (2021)
Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	Diesel Exhaust Fluid (23381558) <b>PE17000</b>	Lube (23155587)..... <b>[2] B40153</b>
Granite w/Cummins ISL 8.9 (8.9L) Eng. (2021)	Granite w/MP7 (10.8L) Eng. (2021)	Fuel/Water Separator (23879508)..... <b>BF46182-O</b>
Lube (5444774)..... <b>B40142</b>	F-F Lube (21707136)..... <b>[2] B76</b>	Fuel (23856895)..... <b>BF46117</b>
Fuel (5303743)..... <b>BF63000</b>	B-P Lube (21707135)..... <b>B7409</b>	Radial Seal Air (25100042)..... <b>RS4634</b>
Radial Seal Air (25100042)..... <b>RS4634</b>	Radial Seal Air (25100042)..... <b>RS4634XP</b>	Radial Seal XP Air (25100042).... <b>RS4634XP</b>
Radial Seal XP Air (25100042).... <b>RS4634XP</b>	Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Granite w/MP7 (10.8L) Eng. (2022)	Trans. Spin-on (Fuller 4304827).. <b>BT223</b>
Granite w/Cummins ISL 8.9 (8.9L) Eng. (2022)	Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	Granite w/MP8 (12.8L) Eng. (2022)
Lube (5444774)..... <b>B40142</b>	Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
Fuel (5660774)..... <b>BF63000</b>	Granite w/MP8 (12.8L) Eng. (2019)	Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
Granite w/MP7 (10.8L) Eng. (2018)	F-F Lube (21707136)..... <b>[2] B76 +</b>	GU432 w/Cummins ISL (8.9L) Eng. (2012-17)
F-F Lube (21707136)..... <b>[2] B76 +</b>	B-P Lube (21707135)..... <b>B7409</b>	Dual-Flow Lube (3401544)..... <b>BD7309 +</b>
B-P Lube (21707135)..... <b>B7409</b>	Fuel/Water Separator (22094987)..... <b>BF46182-O</b>	Lube (Upgrade) (3401544)..... <b>B40142 +</b>
Fuel/Water Separator (22094987)..... <b>BF46182-O</b>	Fuel (22094967)..... <b>BF46117</b>	Fuel/Water Separator Ele. (Fleetguard FS19727)..... <b>PF7895</b>
Fuel (22094967)..... <b>BF46117</b>	Coolant (21937331)..... <b>BW5183</b>	Fuel/Water Separator Ele. (Davco 382 System) (Fleetguard FS19765)..... <b>PF7930</b>
Coolant (21937331)..... <b>BW5183</b>	Granite w/MP7 (10.8L) Eng. (2019)	Fuel (Fleetguard FF63009)..... <b>BF63000</b>
Granite w/MP7 (10.8L) Eng. (2019)	F-F Lube (21707136)..... <b>[2] B76 +</b>	Fuel (Fleetguard FF5636)..... <b>BF7924</b>
F-F Lube (21707136)..... <b>[2] B76 +</b>	B-P Lube (21707135)..... <b>B7409</b>	Air (25042054)..... <b>PA2680</b>
B-P Lube (21707135)..... <b>B7409</b>	Severe Service F-F Lube (21707136)..... <b>[2] B76-SS +</b>	Radial Seal Air (25100042)..... <b>RS4634</b>
Severe Service F-F Lube (21707136)..... <b>[2] B76-SS +</b>	Fuel/Water Separator (22094987)..... <b>BF46182-O</b>	Radial Seal XP Air (25100042).... <b>RS4634XP</b>
Fuel/Water Separator (22094987)..... <b>BF46182-O</b>	Fuel/Water Separator (Davco 382 System) (21737481)..... <b>PF7930</b>	Cab Air (3543H9638)..... <b>PA30277</b>
Fuel (22094967)..... <b>BF46117</b>	Fuel (22094967)..... <b>BF46117</b>	Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
Air (25042054)..... <b>PA2680</b>	Air (25042054)..... <b>PA2680</b>	Air Dryer (AD-IP System) (Bendix 65624)..... <b>BA5373</b>
Air Dryer (Bendix 107794PG)..... <b>BA5377</b>	Coolant (21937331)..... <b>BW5183</b>	Air Dryer (SS1200 System) (Wabco R950011)..... <b>BA5374 +</b>
Coolant (21937331)..... <b>BW5183</b>	Trans. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	Air Dryer (Wabco R950068)..... <b>BA5379 +</b>
Trans. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	Trans. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	Trans. Ele. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>
Trans. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	Trans. (2038908)..... <b>PT9417</b>	Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>
Granite w/MP7 (10.8L) Eng. (2020)	Trans. Spin-on (Fuller 4304827).. <b>BT223</b>	Trans. Spin-on (Fuller 4304827).. <b>BT223</b>
F-F Lube (21707136)..... <b>[2] B76</b>	Granite w/MP8 (12.8L) Eng. (2020)	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>
B-P Lube (21707135)..... <b>B7409</b>	F-F Lube (21707136)..... <b>[2] B76 +</b>	Steering (349619)..... <b>P106-HD</b>
Severe Service F-F Lube (21707136)..... <b>[2] B76-SS +</b>	B-P Lube (21707135)..... <b>B7409</b>	Steering (5839-870678A)..... <b>PT9394-MPG</b>
Fuel/Water Separator (21737481)..... <b>PF7930</b>	Severe Service F-F Lube (21707136)..... <b>[2] B76-SS +</b>	Diesel Exhaust Fluid (5303604).. <b>PE17000</b>
Fuel/Water Separator (22094987)..... <b>BF46182-O</b>	Fuel/Water Separator (22094987)..... <b>BF46182-O</b>	Diesel Exhaust Fluid (5303604).. <b>PE17000</b>
Fuel (22094967)..... <b>BF46117</b>	Fuel (22094967)..... <b>BF46117</b>	
Radial Seal Air (25100042)..... <b>RS4634</b>	Radial Seal Air (25100042)..... <b>RS4634</b>	
Radial Seal XP Air (25100042).... <b>RS4634XP</b>	Radial Seal XP Air (25100042).... <b>RS4634XP</b>	
Cab Air (85151124)..... <b>PA30325</b>	Cab Air (85151124)..... <b>PA30325</b>	
	Air Dryer (21620181)..... <b>BA5379</b>	
	Coolant (w/o Chemical) (21937298)..... <b>B5091</b>	
	Coolant (w/Chemical) (21937331)..... <b>BW5183</b>	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>MACK Trucks (cont'd)</b>	<b>MACK Trucks (cont'd)</b>	<b>MACK Trucks (cont'd)</b>
GU432 w/Cummins ISL 8.9 (8.9L) Eng. (2018) <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel/Water Separator</b> (Fleetguard FS19763)..... <b>PF7928</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> <b>Radial Seal Air</b> (25100042)..... <b>RS4634</b> <b>Radial Seal XP Air</b> (25100042).... <b>RS4634XP</b> <b>Cab Air</b> (3543H9638)..... <b>PA30277</b> <b>Air Dryer</b> (21620181)..... <b>BA5379 +</b> <b>Trans.</b> (22038908)..... <b>PT9417</b> <b>Trans.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (5839870678A)..... <b>PT9394-MPG</b> <b>Diesel Exhaust Fluid</b> (Pump Filter) (4388378)..... <b>PE17002 KIT</b>	GU433 w/Cummins ISL (8.9L) Eng. (2018) <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel/Water Separator</b> (Fleetguard FS19763)..... <b>PF7928</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> <b>Radial Seal Air</b> (25100042)..... <b>RS4634</b> <b>Radial Seal XP Air</b> (25100042).... <b>RS4634XP</b> <b>Cab Air</b> (3543H9638)..... <b>PA30277</b> <b>Air Dryer</b> (21620181)..... <b>BA5379 +</b> <b>Trans.</b> (22038908)..... <b>PT9417</b> <b>Trans.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (5839870678A)..... <b>PT9394-MPG</b> <b>Diesel Exhaust Fluid</b> (Pump Filter) (4388378)..... <b>PE17002 KIT</b>	GU533 w/Cummins ISL (8.9L) Eng. (2012-17) <b>Dual-Flow Lube</b> ..... <b>BD7309 +</b> <b>Fuel/Water Separator</b> (Fleetguard FS19727)..... <b>PF7895</b> <b>Fuel/Water Separator</b> (Fleetguard FS19764)..... <b>PF9814</b> <b>Fuel/Water Separator</b> (Davco 382 System) (Fleetguard FS19765)..... <b>PF7930</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> <b>Radial Seal Air</b> (25100042)..... <b>RS4634</b> <b>Radial Seal XP Air</b> (25100042).... <b>RS4634XP</b> <b>Cab Air</b> (3543-H9638)..... <b>PA30277</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b> <b>Air Dryer</b> (SS1200 System) (Wabco R950011)..... <b>BA5374 +</b> <b>Air Dryer</b> (Wabco R950068)..... <b>BA5379 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (5839870678A)..... <b>PT9394-MPG</b> <b>Diesel Exhaust Fluid</b> (Pump Filter) (4388378)..... <b>PE17000</b>
GU432 w/Cummins ISL (8.9L) Eng. (2019) <b>Lube</b> (3401544)..... <b>B40142</b> <b>Fuel/Water Separator</b> (Fleetguard FS19764)..... <b>PF9814</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Air</b> (25042054)..... <b>PA2680</b> <b>Air Dryer</b> (Bendix 107794PG)..... <b>BA5377</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	GU433 w/Cummins ISL 8.9 (8.9L) Eng. (2019) <b>Lube</b> (3401544)..... <b>B40142</b> <b>Fuel/Water Separator</b> (Fleetguard FS19764)..... <b>PF9814</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Air</b> (25042054)..... <b>PA2680</b> <b>Air Dryer</b> (Bendix 107794PG)..... <b>BA5377</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	GU533 w/Cummins ISL 8.9 (8.9L) Eng. (2018) <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel/Water Separator</b> (Fleetguard FS19763)..... <b>PF7928</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> <b>Radial Seal Air</b> (25100042)..... <b>RS4634</b> <b>Radial Seal XP Air</b> (25100042).... <b>RS4634XP</b> <b>Cab Air</b> (3543H9638)..... <b>PA30277</b> <b>Air Dryer</b> (21620181)..... <b>BA5379 +</b> <b>Trans.</b> (22038908)..... <b>PT9417</b> <b>Trans.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (5839870678A)..... <b>PT9394-MPG</b> <b>Diesel Exhaust Fluid</b> (Pump Filter) (4388378)..... <b>PE17002 KIT</b>
GU433 w/Cummins ISL (8.9L) Eng. (2012-17) <b>Dual-Flow Lube</b> ..... <b>BD7309 +</b> <b>Fuel/Water Separator</b> (Fleetguard FS19727)..... <b>PF7895</b> <b>Fuel/Water Separator</b> (Davco 382 System) (Fleetguard FS19765)..... <b>PF7930</b> <b>Fuel</b> ..... <b>BF7924</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> <b>Radial Seal Air</b> (25100042)..... <b>RS4634</b> <b>Radial Seal XP Air</b> (25100042).... <b>RS4634XP</b> <b>Cab Air</b> (3543-H9638)..... <b>PA30277</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b> <b>Air Dryer</b> (SS1200 System) (Wabco R950011)..... <b>BA5374 +</b> <b>Air Dryer</b> (Wabco R950068)..... <b>BA5379 +</b> <b>Coolant</b> (Fleetguard WF2073)..... <b>BW5073</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (5839-870678A)..... <b>PT9394-MPG</b> <b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b> <b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>	GU532 w/Cummins ISL Eng. <b>Dual-Flow Lube</b> (3401544)..... <b>BD7309 +</b> <b>Lube</b> (Upgrade) (3401544)..... <b>B40142 +</b> <b>Fuel/Water Separator Ele.</b> (Davco 382 System) (Fleetguard FS19765)..... <b>PF7930</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> <b>Radial Seal Air</b> (25100042)..... <b>RS4634</b> <b>Radial Seal XP Air</b> (25100042).... <b>RS4634XP</b> <b>Cab Air</b> (3543H9638)..... <b>PA30277</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b> <b>Air Dryer</b> (SS1200 System) (Wabco R950011)..... <b>BA5374 +</b> <b>Air Dryer</b> (Wabco R950068)..... <b>BA5379 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b> <b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>	GU533 w/Cummins ISL 8.9 (8.9L) Eng. (2019) <b>Lube</b> (3401544)..... <b>B40142</b> <b>Fuel/Water Separator</b> (Fleetguard FS19764)..... <b>PF9814</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Air</b> (25042054)..... <b>PA2680</b> <b>Air Dryer</b> (Bendix 107794PG)..... <b>BA5377</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MACK Trucks (cont'd)	MACK Trucks (cont'd)	MACK Trucks (cont'd)
GU703 w/MP7 Eng.	GU712 w/MP7 Eng. (Cont'd)	GU713 w/MP7 (10.8L) Eng. (2018) (Cont'd)
F-F Lube (20539275)..... [2] B76 +	Air Dryer (85110799)..... BA5592 <sup>90</sup>	Air Dryer (21620181)..... BA5379 +
B-P Lube (20843764)..... B7409	Coolant (20539991)..... BW5183	Coolant (21937331)..... BW5183
B-P Lube Spinner (20552379)..... BC7242	Trans. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	Trans. (22038908)..... PT9417
Fuel/Water Separator (21017305)..... BF1386-O	Trans. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Trans. (2 In. Kit) (Allison 29548987)..... PT9416-MPG KIT
Fuel/Water Separator (w/Drain & Sensor Port) (20539578)..... BF1384-SP	Steering (5839-870678A)..... PT9394-MPG	Trans. (4 In. Kit) (Allison 29548988)..... PT9415-MPG KIT
Fuel (20539582)..... BF7814	Diesel Exhaust Fluid Ele. (2010 Emissions) (21516231)..... PE17000	Steering (5839870678A)..... PT9394-MPG
Radial Seal Air (57MD320M)..... RS4634	Diesel Exhaust Fluid Strainer (2010 Emissions) (82269261)..... PE17001	Diesel Exhaust Fluid Strainer (82269261)..... PE17001
Radial Seal XP Air (57MD320M)..... RS4634XP		
Cab Air (3543-H9638)..... PA30277	GU713 w/MP7 (10.8L) Eng. (2008-17)	GU713 w/MP7 (10.8L) Eng. (2019)
Air Dryer (Meritor R950011)..... BA5374 +	F-F Lube (21707136)..... [2] B76 +	F-F Lube (21707136)..... [2] B76 +
Air Dryer (85110799)..... BA5592 <sup>90</sup>	B-P Lube Spinner (20552379)..... BC7242	B-P Lube (21707135)..... B7409
Coolant (w/o Chemical) (20575545)..... B5091	B-P Lube Spin-on (21707135)..... B7409	Severe Service F-F Lube (21707136)..... [2] B76-SS +
Coolant (w/Chemical) (20539991)..... BW5183	Fuel/Water Separator Ele. (Fleetguard FS19728)..... PF7782	Fuel/Water Separator (22094987)..... BF46182-O
Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	Fuel/Water Separator Ele. (Fleetguard FS19765)..... PF7930	Fuel (22094967)..... BF46117
Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Fuel/Water Separator Spin-on (w/Drain & Sensor Port) (20539578)..... BF1384-SP	Air (25042054)..... PA2680
Opt. Trans. Spin-on (Fuller 17237)..... B2 +	Fuel (20539582)..... BF7814	Air Dryer (Bendix 107794PG)..... BA5377
Steering (5839-870678A)..... PT9394-MPG	Fuel (20972295)..... BF7943	Coolant (21937331)..... BW5183
GU703 w/MP8 Eng.	Radial Seal Air (57MD320M)..... RS4634	Trans. (2 In. Kit) (Allison 29558117)..... PT9416-MPG KIT
F-F Lube (20539275)..... [2] B76 +	Radial Seal XP Air (57MD320M)..... RS4634XP	Trans. (4 In. Kit) (Allison 29558118)..... PT9415-MPG KIT
B-P Lube Spinner (20552379)..... BC7242	Cab Air (3543-H9638)..... PA30277	Diesel Exhaust Fluid (21516231) PE17000
Fuel/Water Separator (21017305)..... BF1386-O	Air Dryer (Meritor R950011)..... BA5374 +	GU713 w/MP8 (12.8L) Eng. (2008-17)
Fuel (20539582)..... BF7814	Air Dryer (85110799)..... BA5592 <sup>90</sup>	F-F Lube (21707136)..... [2] B76 +
Fuel (20972295)..... BF7943	Air Dryer (Bendix 109493)..... BA5373	B-P Lube Spinner (20552379)..... BC7242
Radial Seal Air (57MD320M)..... RS4634	Air Dryer (Wabco R950068)..... BA5379 +	B-P Lube Spin-on (21707135)..... B7409
Radial Seal XP Air (57MD320M)..... RS4634XP	Coolant (w/o Chemical) (20575545)..... B5091	Fuel/Water Separator Ele. (Racor 2020SM-OR)..... PF7890
Cab Air (3543-H9638)..... PA30277	Coolant (w/Chemical) (21937331)..... BW5183	Fuel/Water Separator Ele. (Racor 2020TM-OR)..... PF7890-10
Air Dryer (Meritor R950011)..... BA5374 +	Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	Fuel/Water Separator Ele. (Racor 2020PM-OR)..... PF7890-30
Coolant (w/Chemical) (20539991)..... BW5183	Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Fuel/Water Separator Ele. (Fleetguard FS19728)..... PF7782
Coolant (w/o Chemical) (20575545)..... B5091	Opt. Trans. Spin-on (Fuller 17237)..... B2 +	Fuel/Water Separator Ele. (Davco 382 System) (Fleetguard FS19765)..... PF7930
Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	Trans. Spin-on (Fuller 4304827).. BT223	Fuel/Water Separator Spin-on (21380521)..... BF1386-O
Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Steering (Nelson 870678A)..... PT9394-MPG	Fuel (20539582)..... BF7814
Opt. Trans. Spin-on (Fuller 17237)..... B2 +	Diesel Exhaust Fluid Ele. (2010 Emissions) (21516231)..... PE17000	Fuel (20972295)..... BF7943
Steering (5839-870678A)..... PT9394-MPG	Diesel Exhaust Fluid Strainer (2010 Emissions) (82269261)..... PE17001	Radial Seal Air (57MD320M)..... RS4634
GU712 w/MP7 Eng.	GU713 w/MP7 (10.8L) Eng. (2018)	Radial Seal XP Air (57MD320M)..... RS4634XP
F-F Lube (20539275)..... [2] B76 +	F-F Lube (21707136)..... [2] B76 +	Cab Air (3543-H9638)..... PA30277
B-P Lube (20843764)..... B7409	B-P Lube (21707135)..... B7409	Air Dryer (Meritor R950011)..... BA5374 +
Severe Service F-F Lube (20539275)..... [2] B76-SS +	Severe Service F-F Lube (21707136)..... [2] B76-SS +	Air Dryer (85110799)..... BA5592 <sup>90</sup>
Fuel/Water Separator (21380521)..... BF1386-O	Fuel/Water Separator (22094987)..... BF46182-O	Air Dryer (Wabco R950068)..... BA5379 +
Fuel (20972295)..... BF7943	Fuel (22094967)..... BF46117	Air Dryer (Bendix 109493)..... BA5373
Radial Seal Air (57MD320M)..... RS4634	Radial Seal Air (25100042)..... RS4634	Coolant (w/Chemical) (21937331)..... BW5183
Radial Seal XP Air (57MD320M)..... RS4634XP	Radial Seal XP Air (25100042)..... RS4634XP	Coolant (w/o Chemical) (20575545)..... B5091
Cab Air (3543-H9638)..... PA30277	Cab Air (85112361)..... PA30325	Trans. Ele. (mDrive) (20779040).. PT9417
Air Dryer (Wabco R950011)..... BA5374 +		


+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.

Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>MACK Trucks (cont'd)</b>	<b>MACK Trucks (cont'd)</b>	<b>MACK Trucks (cont'd)</b>
GU713 w/MP8 (12.8L) Eng. (2008-17) (Cont'd) Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2+</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Steering (Nelson 870678A)..... <b>PT9394-MPG</b> Diesel Exhaust Fluid Ele. (2010 Emissions) (21516231)..... <b>PE17000</b> Diesel Exhaust Fluid Strainer (2010 Emissions) (82269261)..... <b>PE17001</b>	GU714 w/MP7 Eng. F-F Lube (20539275)..... <b>[2] B76+</b> B-P Lube (20843764)..... <b>B7409</b> Severe Service F-F Lube (20539275)..... <b>[2] B76-SS+</b> Fuel/Water Separator (21017305)..... <b>BF1386-O</b> Fuel (20972295)..... <b>BF7943</b> Radial Seal Air (57MD320M)..... <b>RS4634</b> Radial Seal XP Air (57MD320M). <b>RS4634XP</b> Cab Air (3543-H9638)..... <b>PA30277</b> Air Dryer (Wabco R950011)..... <b>BA5374+</b> Air Dryer (85110799)..... <b>BA5592<sup>90</sup></b> Coolant (w/o Chemical)..... <b>B5091</b> Coolant (w/Chemical)..... <b>BW5183</b> Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Steering (5839-870678A)..... <b>PT9394-MPG</b>	GU714 w/MP8 (12.8L) Eng. (2019) (Cont'd) Trans. Ele. (22038908)..... <b>PT9417</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Diesel Exhaust Fluid (Neck Filter) (82269261)..... <b>PE17001</b> Diesel Exhaust Fluid (Pump Ele.) (21516231)..... <b>PE17000</b> GU803 w/MP7 Eng. F-F Lube (20539275)..... <b>[2] B76+</b> B-P Lube (20843764)..... <b>B7409</b> B-P Lube Spinner (20552379).... <b>BC7242</b> Fuel/Water Separator (21017305)..... <b>BF1386-O</b> Fuel/Water Separator (w/Drain & Sensor Port) (20539578)..... <b>BF1384-SP</b> Fuel (20539582)..... <b>BF7814</b> Fuel (20972295)..... <b>BF7943</b> Radial Seal Air (57MD320M)..... <b>RS4634</b> Radial Seal XP Air (57MD320M). <b>RS4634XP</b> Cab Air (3543-H9638)..... <b>PA30277</b> Air Dryer (Meritor R950011)..... <b>BA5374+</b> Coolant (w/o Chemical) (20575545)..... <b>B5091</b> Coolant (w/Chemical) (20539991)..... <b>BW5183</b> Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2+</b> Steering (5839-870678A)..... <b>PT9394-MPG</b>
GU713 w/MP8 (12.8L) Eng. (2018) F-F Lube (21707136)..... <b>[2] B76+</b> B-P Lube (21707135)..... <b>B7409</b> Severe Service F-F Lube (21707136)..... <b>[2] B76-SS+</b> Fuel/Water Separator (22094987)..... <b>BF46182-O</b> Fuel (22094967)..... <b>BF46117</b> Radial Seal Air (25100042)..... <b>RS4634</b> Radial Seal XP Air (25100042).... <b>RS4634XP</b> Cab Air (85112361)..... <b>PA30325</b> Air Dryer (21620181)..... <b>BA5379+</b> Coolant (21937331)..... <b>BW5183</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Trans. (22038908)..... <b>PT9417</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2+</b> Steering (5839870678A)..... <b>PT9394-MPG</b> Diesel Exhaust Fluid (82269261) <b>PE17001</b>	GU714 w/MP8 (12.8L) Eng. (2018) F-F Lube (21707136)..... <b>[2] B76+</b> B-P Lube (21707135)..... <b>B7409</b> Severe Service F-F Lube (21707136)..... <b>[2] B76-SS+</b> Fuel/Water Separator (22094987)..... <b>BF46182-O</b> Fuel (22094967)..... <b>BF46117</b> Radial Seal Air (25100042)..... <b>RS4634</b> Radial Seal XP Air (25100042).... <b>RS4634XP</b> Cab Air (85112361)..... <b>PA30325</b> Air Dryer (21620181)..... <b>BA5379+</b> Coolant (21937331)..... <b>BW5183</b> Trans. (22038908)..... <b>PT9417</b> Trans. Ele. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2+</b> Steering (5839870678A)..... <b>PT9394-MPG</b> Diesel Exhaust Fluid (82269261) <b>PE17001</b>	GU803 w/MP8 Eng. F-F Lube (20539275)..... <b>[2] B76+</b> B-P Lube Spinner (20552379).... <b>BC7242</b> Fuel/Water Separator (21017305)..... <b>BF1386-O</b> Fuel (20539582)..... <b>BF7814</b> Fuel (20972295)..... <b>BF7943</b> Radial Seal Air (57MD320M)..... <b>RS4634</b> Radial Seal XP Air (57MD320M). <b>RS4634XP</b> Cab Air (3543-H9638)..... <b>PA30277</b> Air Dryer (Meritor R950011)..... <b>BA5374+</b> Coolant (w/Chemical) (20539991)..... <b>BW5183</b> Coolant (w/o Chemical) (20575545)..... <b>B5091</b> Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Opt. Trans. (Fuller 17237)..... <b>B2+</b> Steering (5839-870678A)..... <b>PT9394-MPG</b>
GU713 w/MP8 (12.8L) Eng. (2019) F-F Lube (21707136)..... <b>[2] B76+</b> B-P Lube (21707135)..... <b>B7409</b> Severe Service F-F Lube (21707136)..... <b>[2] B76-SS+</b> Fuel/Water Separator (22094987)..... <b>BF46182-O</b> Fuel/Water Separator (Davco 382 System) (21737481)..... <b>PF7930</b> Fuel (22094967)..... <b>BF46117</b> Air (25042054)..... <b>PA2680</b> Air Dryer (Bendix 107794PG)..... <b>BA5377</b> Coolant (21937331)..... <b>BW5183</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Trans. Ele. (22038908)..... <b>PT9417</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Diesel Exhaust Fluid (Neck Filter) (82269261)..... <b>PE17001</b> Diesel Exhaust Fluid (Pump Ele.) (21516231)..... <b>PE17000</b>	GU714 w/MP8 (12.8L) Eng. (2019) F-F Lube (21707136)..... <b>[2] B76+</b> B-P Lube (21707135)..... <b>B7409</b> Severe Service F-F Lube (21707136)..... <b>[2] B76-SS+</b> Fuel/Water Separator (22094987)..... <b>BF46182-O</b> Fuel/Water Separator (Davco 382 System) (21737481)..... <b>PF7930</b> Fuel (22094967)..... <b>BF46117</b> Air (25042054)..... <b>PA2680</b> Air Dryer (Bendix 107794PG)..... <b>BA5377</b> Coolant (21937331)..... <b>BW5183**</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	GU812 w/MP7 Eng. F-F Lube (20539275)..... <b>[2] B76+</b> B-P Lube (20843764)..... <b>B7409</b> Severe Service F-F Lube (20539275)..... <b>[2] B76-SS+</b>

\*\* Baldwin Branded Product. + See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).


MACK Trucks (cont'd)	MACK Trucks (cont'd)	MACK Trucks (cont'd)
<b>GU812 w/MP7 Eng. (Cont'd)</b> <b>Fuel/Water Separator</b> (21017305)..... <b>BF1386-O</b> <b>Fuel</b> (20972295)..... <b>BF7943</b> <b>Radial Seal Air</b> (57MD320M)..... <b>RS4634</b> <b>Radial Seal XP Air</b> (57MD320M)..... <b>RS4634XP</b> <b>Cab Air</b> (3543-H9638)..... <b>PA30277</b> <b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b> <b>Air Dryer</b> (85110799)..... <b>BA5592<sup>90</sup></b> <b>Coolant</b> (w/o Chemical)..... <b>B5091</b> <b>Coolant</b> (w/Chemical)..... <b>BW5183</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (5839-870678A)..... <b>PT9394-MPG</b>	<b>GU813 w/MP7 (10.8L) Eng. (2008-17) (Cont'd)</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain & Sensor Port) (20539578)..... <b>BF1384-SP</b> <b>Fuel</b> (20539582)..... <b>BF7814</b> <b>Fuel</b> (20972295)..... <b>BF7943</b> <b>Std. Air</b> (25042054)..... <b>PA2680</b> <b>Radial Seal Air</b> (57MD320M)..... <b>RS4634</b> <b>Radial Seal XP Air</b> (57MD320M)..... <b>RS4634XP</b> <b>Cab Air</b> (3543-H9638)..... <b>PA30277</b> <b>Air Dryer</b> (Meritor R950011)..... <b>BA5374 +</b> <b>Air Dryer</b> (85110799)..... <b>BA5592<sup>90</sup></b> <b>Air Dryer</b> (Wabco R950068)..... <b>BA5379 +</b> <b>Air Dryer</b> (Bendix 109493)..... <b>BA5373</b> <b>Coolant</b> (w/o Chemical) (20575545)..... <b>B5091</b> <b>Coolant</b> (w/Chemical) (21937331)..... <b>BW5183</b> <b>Trans. Ele.</b> (mDrive) (20779040).. <b>PT9417</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (349619)..... <b>P106-HD</b> <b>Steering</b> (Nelson 870678A)..... <b>PT9394-MPG</b> <b>Diesel Exhaust Fluid Strainer</b> (82269261)..... <b>PE17001</b> <b>Diesel Exhaust Fluid Pump</b> (21516231)..... <b>PE17000</b>	<b>GU813 w/MP7 (10.8L) Eng. (2019) (Cont'd)</b> <b>Fuel</b> (22094967)..... <b>BF46117</b> <b>Radial Seal XP Air</b> (2191DBA5114)..... <b>RS4634XP</b> <b>Air Dryer</b> (Bendix 107794PG)..... <b>BA5377</b> <b>Coolant</b> (21937331)..... <b>BW5183</b> <b>Trans.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Trans.</b> (22038908)..... <b>PT9417</b> <b>Diesel Exhaust Fluid</b> (21516231) <b>PE17000</b>
<b>GU812 w/MP8 Eng.</b> <b>F-F Lube</b> (20539275)..... <b>[2] B76 +</b> <b>B-P Lube</b> (20843764)..... <b>B7409</b> <b>Severe Service F-F Lube</b> (20539275)..... <b>[2] B76-SS +</b> <b>Fuel/Water Separator</b> (21017305)..... <b>BF1386-O</b> <b>Fuel</b> (20972295)..... <b>BF7943</b> <b>Radial Seal Air</b> (57MD320M)..... <b>RS4634</b> <b>Radial Seal XP Air</b> (57MD320M)..... <b>RS4634XP</b> <b>Cab Air</b> (3543-H9638)..... <b>PA30277</b> <b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b> <b>Air Dryer</b> (85110799)..... <b>BA5592<sup>90</sup></b> <b>Coolant</b> (w/o Chemical)..... <b>B5091</b> <b>Coolant</b> (w/Chemical)..... <b>BW5183</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (5839-870678A)..... <b>PT9394-MPG</b>	<b>GU813 w/MP7 (10.8L) Eng. (2018)</b> <b>F-F Lube</b> (21707136)..... <b>[2] B76 +</b> <b>B-P Lube</b> (21707135)..... <b>B7409</b> <b>Severe Service F-F Lube</b> (21707136)..... <b>[2] B76-SS +</b> <b>Fuel/Water Separator</b> (22094987)..... <b>BF46182-O</b> <b>Fuel</b> (22094967)..... <b>BF46117</b> <b>Radial Seal Air</b> (25100042)..... <b>RS4634</b> <b>Radial Seal XP Air</b> (25100042)..... <b>RS4634XP</b> <b>Cab Air</b> (3543H9638)..... <b>PA30277</b> <b>Air Dryer</b> (21620181)..... <b>BA5379 +</b> <b>Coolant</b> (21937331)..... <b>BW5183</b> <b>Trans.</b> (22038908)..... <b>PT9417</b> <b>Trans.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (5839870678A)..... <b>PT9394-MPG</b> <b>Diesel Exhaust Fluid</b> (82269261) <b>PE17001</b>	<b>GU813 w/MP8 (12.8L) Eng. (2008-17)</b> <b>F-F Lube</b> (21707136)..... <b>[2] B76 +</b> <b>B-P Lube Spinner</b> (20552379)..... <b>BC7242</b> <b>B-P Lube Spin-on</b> (21707135)..... <b>B7409</b> <b>Fuel/Water Separator Ele.</b> (Davco 382 System) (Fleetguard FS19765)..... <b>PF7930</b> <b>Fuel/Water Separator Ele.</b> (Racor 2020SM-OR)..... <b>PF7890</b> <b>Fuel/Water Separator Ele.</b> (Racor 2020TM-OR)..... <b>PF7890-10</b> <b>Fuel/Water Separator Ele.</b> (Racor 2020PM-OR)..... <b>PF7890-30</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19728)..... <b>PF7782</b> <b>Fuel/Water Separator Spin-on</b> (21380521)..... <b>BF1386-O</b>
<b>GU813 w/MP7 (10.8L) Eng. (2008-17)</b> <b>F-F Lube</b> (21707136)..... <b>[2] B76 +</b> <b>B-P Lube</b> (21707135)..... <b>B7409</b> <b>Severe Service F-F Lube</b> (21707136)..... <b>[2] B76-SS +</b> <b>Fuel/Water Separator</b> (22094987)..... <b>BF46182-O</b> <b>Fuel</b> (22094967)..... <b>BF46117</b> <b>Radial Seal Air</b> (25100042)..... <b>RS4634</b> <b>Radial Seal XP Air</b> (25100042)..... <b>RS4634XP</b> <b>Cab Air</b> (3543H9638)..... <b>PA30277</b> <b>Air Dryer</b> (21620181)..... <b>BA5379 +</b> <b>Coolant</b> (21937331)..... <b>BW5183</b> <b>Trans.</b> (22038908)..... <b>PT9417</b> <b>Trans.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (5839870678A)..... <b>PT9394-MPG</b> <b>Diesel Exhaust Fluid</b> (82269261) <b>PE17001</b>	<b>GU813 w/MP7 (10.8L) Eng. (2019)</b> <b>F-F Lube</b> (21707136)..... <b>[2] B76 +</b> <b>B-P Lube</b> (21707135)..... <b>B7409</b> <b>Severe Service F-F Lube</b> (21707136)..... <b>[2] B76-SS +</b> <b>Fuel/Water Separator</b> (22094987)..... <b>BF46182-O</b>	<b>GU813 w/MP8 (12.8L) Eng. (2008-17)</b> <b>F-F Lube</b> (21707136)..... <b>[2] B76 +</b> <b>B-P Lube Spinner</b> (20552379)..... <b>BC7242</b> <b>B-P Lube Spin-on</b> (21707135)..... <b>B7409</b> <b>Fuel/Water Separator Ele.</b> (Davco 382 System) (Fleetguard FS19765)..... <b>PF7930</b> <b>Fuel/Water Separator Ele.</b> (Racor 2020SM-OR)..... <b>PF7890</b> <b>Fuel/Water Separator Ele.</b> (Racor 2020TM-OR)..... <b>PF7890-10</b> <b>Fuel/Water Separator Ele.</b> (Racor 2020PM-OR)..... <b>PF7890-30</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19728)..... <b>PF7782</b> <b>Fuel/Water Separator Spin-on</b> (21380521)..... <b>BF1386-O</b>

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
 Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MACK Trucks (cont'd)	MACK Trucks (cont'd)	MACK Trucks (cont'd)
<p>GU813 w/MP8 (12.8L) Eng. (2018)</p> <p>F-F Lube (21707136)..... [2] B76 +</p> <p>B-P Lube (21707135)..... B7409</p> <p>Severe Service F-F Lube (21707136)..... [2] B76-SS +</p> <p>Fuel/Water Separator (22094987)..... BF46182-O</p> <p>Fuel (22094967)..... BF46117</p> <p>Radial Seal Air (25100042)..... RS4634</p> <p>Radial Seal XP Air (25100042)..... RS4634XP</p> <p>Cab Air (3543H9638)..... PA30277</p> <p>Air Dryer (21620181)..... BA5379 +</p> <p>Coolant (21937331)..... BW5183</p> <p>Trans. (22038908)..... PT9417</p> <p>Trans. Ele. (2 In. Kit) (Allison 29548987)..... PT9416-MPG KIT</p> <p>Trans. Ele. (4 In. Kit) (Allison 29548988)..... PT9415-MPG KIT</p> <p>Opt. Trans. Spin-on (Fuller 17237)..... B2 +</p> <p>Steering (5839870678A)..... PT9394-MPG</p> <p>Diesel Exhaust Fluid Strainer (82269261)..... PE17001</p> <hr/> <p>GU813 w/MP8 (12.8L) Eng. (2019)</p> <p>F-F Lube (21707136)..... [2] B76 +</p> <p>B-P Lube (21707135)..... B7409</p> <p>Severe Service F-F Lube (21707136)..... [2] B76-SS +</p> <p>Fuel/Water Separator (22094987)..... BF46182-O</p> <p>Fuel/Water Separator (Davco 382 System) (21737481)..... PF7930</p> <p>Fuel (22094967)..... BF46117</p> <p>Radial Seal XP Air (2191DBA5114)..... RS4634XP</p> <p>Air Dryer (Bendix 107794PG)..... BA5377</p> <p>Coolant (21937331)..... BW5183</p> <p>Trans. Ele. (2 In. Kit) (Allison 29558117)..... PT9416-MPG KIT</p> <p>Trans. Ele. (4 In. Kit) (Allison 29558118)..... PT9415-MPG KIT</p> <p>Trans. Ele. (22038908)..... PT9417</p> <p>Trans. Spin-on (Fuller 4304827)..... BT223</p> <p>Diesel Exhaust Fluid Strainer (82269261)..... PE17001</p> <p>Diesel Exhaust Fluid Ele. (21516231)..... PE17000</p> <hr/> <p>GU814 w/MP7 Eng.</p> <p>F-F Lube (20539275)..... [2] B76 +</p> <p>B-P Lube (20843764)..... B7409</p> <p>Severe Service F-F Lube (20539275)..... [2] B76-SS +</p> <p>Fuel/Water Separator (21017305)..... BF1386-O</p> <p>Fuel (20972295)..... BF7943</p> <p>Radial Seal Air (57MD320M)..... RS4634</p> <p>Radial Seal XP Air (57MD320M)..... RS4634XP</p> <p>Cab Air (3543-H9638)..... PA30277</p> <p>Air Dryer (Wabco R950011)..... BA5374 +</p> <p>Air Dryer (85110799)..... BA5592<sup>90</sup></p> <p>Coolant (w/o Chemical)..... B5091</p> <p>Coolant (w/Chemical)..... BW5183</p> <p>Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT</p> <p>Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT</p> <p>Trans. Spin-on (Fuller 4304827)..... BT223</p> <p>Opt. Trans. Spin-on (Fuller 17237)..... B2 +</p> <p>Steering (5839-870678A)..... PT9394-MPG</p> <hr/> <p>LC w/Cummins 6CT8.3 (8.3L) Eng.</p> <p>F-F Lube (3313281)..... B205 +</p> <p>Dual-Flow Lube (3318853)..... BD103 +</p> <p>Fuel/Water Separator (Fleetguard 3903410)..... BF1280 +</p> <p>Fuel/Water Separator (3286503)..... BF1226</p> <p>Fuel Spin-on (3903640)..... BF788</p> <p>Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT</p> <p>Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT</p> <hr/> <p>LE Series w/EM7-275 ETECH Eng.</p> <p>F-F Lube..... [2] B76 +</p> <p>B-P Lube Spinner (57GC2134)..... BC110</p> <p>P. Fuel..... BF877 +</p> <p>Air (57MD24)..... PA2482</p> <p>Coolant (25MF435)..... BW5178</p>	<p>GU814 w/MP7 Eng. (Cont'd)</p> <p>Air Dryer (85110799)..... BA5592<sup>90</sup></p> <p>Coolant (w/o Chemical)..... B5091</p> <p>Coolant (w/Chemical)..... BW5183</p> <p>Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT</p> <p>Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT</p> <p>Trans. Spin-on (Fuller 4304827)..... BT223</p> <p>Opt. Trans. Spin-on (Fuller 17237)..... B2 +</p> <p>Steering (5839-870678A)..... PT9394-MPG</p> <hr/> <p>GU814 w/MP8 Eng.</p> <p>F-F Lube (20539275)..... [2] B76 +</p> <p>B-P Lube (20843764)..... B7409</p> <p>Severe Service F-F Lube (20539275)..... [2] B76-SS +</p> <p>Fuel/Water Separator (21017305)..... BF1386-O</p> <p>Fuel (20972295)..... BF7943</p> <p>Radial Seal Air (57MD320M)..... RS4634</p> <p>Radial Seal XP Air (57MD320M)..... RS4634XP</p> <p>Cab Air (3543-H9638)..... PA30277</p> <p>Air Dryer (Wabco R950011)..... BA5374 +</p> <p>Air Dryer (85110799)..... BA5592<sup>90</sup></p> <p>Coolant (w/o Chemical)..... B5091</p> <p>Coolant (w/Chemical)..... BW5183</p> <p>Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT</p> <p>Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT</p> <p>Trans. Spin-on (Fuller 4304827)..... BT223</p> <p>Opt. Trans. Spin-on (Fuller 17237)..... B2 +</p> <p>Steering (5839-870678A)..... PT9394-MPG</p> <hr/> <p>LC w/Cummins 6CT8.3 (8.3L) Eng.</p> <p>F-F Lube (3313281)..... B205 +</p> <p>Dual-Flow Lube (3318853)..... BD103 +</p> <p>Fuel/Water Separator (Fleetguard 3903410)..... BF1280 +</p> <p>Fuel/Water Separator (3286503)..... BF1226</p> <p>Fuel Spin-on (3903640)..... BF788</p> <p>Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT</p> <p>Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT</p> <hr/> <p>LE Series w/EM7-275 ETECH Eng.</p> <p>F-F Lube..... [2] B76 +</p> <p>B-P Lube Spinner (57GC2134)..... BC110</p> <p>P. Fuel..... BF877 +</p> <p>Air (57MD24)..... PA2482</p> <p>Coolant (25MF435)..... BW5178</p>	<p>LE Series w/E5-250 Eng.</p> <p>F-F Lube (485GB3191B)..... [2] B76 +</p> <p>P. Fuel (483GB444)..... BF877 +</p> <p>S. Fuel (483GB441)..... BF876</p> <p>Coolant (25MF436B)..... BW5179</p> <hr/> <p>LE w/MP7 (10.8L) Eng.</p> <p>F-F Lube (485GB3191)..... [2] B76 +</p> <p>B-P Lube Spin-on (20843764)..... B7409</p> <p>B-P Lube Spinner (20552379)..... BC7242</p> <p>Severe Service F-F Lube (485GB3191)..... [2] B76-SS +</p> <p>Fuel/Water Separator Spin-on (21017305)..... BF1386-O</p> <p>Fuel/Water Separator Spin-on (w/Drain &amp; Sensor Port) (20539578)..... BF1384-SP</p> <p>Fuel (20539582)..... BF7814</p> <p>Fuel (20972295)..... BF7943</p> <p>Air (2MD2153)..... PA2317 +</p> <p>Air (57MD47)..... PA3938</p> <p>Channel Flow Air (21020786)..... CA5789</p> <p>Air Dryer (Bendix 5008414)..... BA5374 +</p> <p>Coolant (w/o Chemical) (20575545)..... B5091</p> <p>Coolant (w/Chemical) (20539991)..... BW5183</p> <p>Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT</p> <p>Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT</p> <p>Steering (583984148A)..... P528</p> <hr/> <p>LE600 w/AI-300A (11.9L) Eng. (To 2003)</p> <p>F-F Lube (485GB3236)..... [2] B7225 +</p> <p>B-P Lube Spinner (To 11/11/03) (57GC2206)..... BC7228</p> <p>B-P Lube Spinner (11/11/03-on) (57GC2231)..... BC7242</p> <p>Opt. Fuel/Water Separator (483GB472M)..... BF1256</p> <p>Opt. Fuel/Water Separator (483GB477M)..... BF1286</p> <p>P. Fuel (483GB470M)..... BF7656</p> <p>S. Fuel (483GB471M)..... BF7657</p> <p>20 1/2 In. Air (57MD47)..... PA3938</p> <p>23 In. Air (3076-CA595)..... PA2317 +</p> <p>Channel Flow Air (21020786)..... CA5789</p> <p>Air Dryer (Meritor Wabco TDAR950011)..... BA5374 +</p> <p>Crankcase Breather..... CLN&amp;R</p> <p>Coolant (25MF435B)..... BW5178</p> <p>Trans. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT</p> <p>Trans. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT</p> <p>Steering (5839-84148A)..... P528</p> <p>Service Kit (215SB325A)..... BK6693</p>

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



MACK Trucks (cont'd)	
LE600 w/AI-300A (11.9L) Eng. (2004-10)	
F-F Lube (485GB3236).....	[2] B7225 +
B-P Lube Spinner (57GC2231)...	BC7242
<b>Opt. Fuel/Water Separator</b> (483GB472M).....	BF1256
<b>Opt. Fuel/Water Separator</b> (483GB477M).....	BF1286
P. Fuel (483GB470M).....	BF7656
S. Fuel (483GB471M).....	BF7657
20 1/2 In. Air (57MD47).....	PA3938
23 In. Air (3076-CA595).....	PA2317 +
Channel Flow Air (21020786).....	CA5789
Air Dryer (Meritor Wabco TDAR950011).....	BA5374 +
Crankcase Breather.....	CLN&R
Coolant (25MF435B).....	BW5178
Trans. (2 In. Kit) (Allison 29540493).....	PT9416-MPG KIT
Trans. (4 In. Kit) (Allison 29540494).....	PT9415-MPG KIT
Steering (5839-84148A).....	P528
Service Kit (215SB325A).....	BK6693
LE600 w/AMI-300 (11.9L) Eng.	
F-F Lube (485GB3236).....	[2] B7225 +
B-P Lube Spinner (57GC2231)...	BC7242
<b>Opt. Fuel/Water Separator</b> (301SD19B).....	PF7680
P. Fuel (483GB470M).....	BF7656
S. Fuel (483GB471M).....	BF7657
20 1/2 In. Air (57MD47).....	PA3938
23 In. Air (3076-CA595).....	PA2317 +
Channel Flow Air (21020786).....	CA5789
Air Dryer (Wabco R950011).....	BA5374 +
Crankcase Breather.....	CLN&R
Coolant (25MF435B).....	BW5178
Trans. (2 In. Kit) (Allison 29540493).....	PT9416-MPG KIT
Trans. (4 In. Kit) (Allison 29540494).....	PT9415-MPG KIT
Steering (5839-870678A).....	PT9394-MPG
Service Kit (215SB325A).....	BK6693
LE600 w/E7 Eng.	
F-F Lube (485GB3191C).....	[2] B76 +
B-P Lube Spinner (57GC2134A).....	BC110
B-P Lube Spinner (57GC2187)...	BC7173
<b>Opt. Fuel/Water Separator</b> (483GB472M).....	BF1256
P. Fuel (483GB470M).....	BF7656
S. Fuel (483GB471M).....	BF7657
Air (57MD33).....	PA2317 +
Channel Flow Air (21020786).....	CA5789
Air Dryer (Meritor Wabco TDAR950011).....	BA5374 +
Coolant (25MF435B).....	BW5178
Trans. (2 In. Kit) (Allison 29540493).....	PT9416-MPG KIT
Trans. (4 In. Kit) (Allison 29540494).....	PT9415-MPG KIT
Steering (5839-83804E).....	P528

MACK Trucks (cont'd)	
LE600 w/E7 Eng. (Cont'd)	
Service Kit (57GC2177A).....	BK6705
Service Kit (57GC2177).....	BK6704
LE612 w/ASET AI Series Eng.	
F-F Lube (485GB3236).....	[2] B7225 +
B-P Lube Spinner (To 11/11/03) (57GC2206).....	BC7228
B-P Lube Spinner (11/11/03-on) (57GC2231).....	BC7242
<b>Opt. Fuel/Water Separator</b> (M22 x 1.5 Thd.) (483GB472M).....	BF1256
<b>Opt. Fuel/Water Separator</b> (M30 x 1.5 Thd.) (483GB477M).....	BF1286
P. Fuel (483GB470AM).....	BF7656
S. Fuel (483GB471M).....	BF7657
20 1/2 In. Air (57MD47).....	PA3938
23 In. Air (3076-CA595).....	PA2317 +
Channel Flow Air (21020786).....	CA5789
Air Dryer (Meritor Wabco TDAR950011).....	BA5374 +
Crankcase Breather.....	CLN&R
Coolant (25MF435B).....	BW5178
Trans. (2 In. Kit) (Allison 29540493).....	PT9416-MPG KIT
Trans. (4 In. Kit) (Allison 29540494).....	PT9415-MPG KIT
Steering.....	P528
Service Kit.....	BK6658 <sup>90</sup>
Service Kit (215SB330).....	BK6662
Service Kit (215SB325A).....	BK6693
LE613 w/ASET AI Series Eng.	
F-F Lube (485GB3236).....	[2] B7225 +
B-P Lube Spinner (To 11/11/03) (57GC2206).....	BC7228
B-P Lube Spinner (11/11/03-on) (57GC2231).....	BC7242
<b>Opt. Fuel/Water Separator</b> (483GB477M).....	BF1286
<b>Opt. Fuel/Water Separator</b> (483GB472M).....	BF1256
P. Fuel (483GB470M).....	BF7656
S. Fuel (483GB471M).....	BF7657
20 1/2 In. Air (57MD47).....	PA3938
23 In. Air (3076-CA595).....	PA2317 +
Channel Flow Air (21020786).....	CA5789
Air Dryer (Meritor Wabco TDAR950011).....	BA5374 +
Crankcase Breather.....	CLN&R
Coolant (25MF435B).....	BW5178
Trans. (2 In. Kit) (Allison 29540493).....	PT9416-MPG KIT
Trans. (4 In. Kit) (Allison 29540494).....	PT9415-MPG KIT
Steering (5839-84148A).....	P528
Service Kit.....	BK6658 <sup>90</sup>
Service Kit (215SB325A).....	BK6693

MACK Trucks (cont'd)	
LE613 w/E7 Eng.	
F-F Lube (485GB3191B).....	[2] B76 +
B-P Lube Spinner (57GC2134A).....	BC110
B-P Lube Spinner (57GC2187)...	BC7173
<b>Opt. Fuel/Water Separator</b> (483GB472M).....	BF1256
P. Fuel (483GB470M).....	BF7656
7 19/32 In. S. Fuel (483GB476M).....	BF7773
10 7/16 In. S. Fuel (483GB471M).....	BF7657
20 1/2 In. Air (57MD47).....	PA3938
23 In. Air (3076-CA595).....	PA2317 +
Channel Flow Air (21020786).....	CA5789
Air Dryer (Meritor Wabco TDAR950011).....	BA5374 +
Coolant (25MF435B).....	BW5178
Trans. (2 In. Kit) (Allison 29540493).....	PT9416-MPG KIT
Trans. (4 In. Kit) (Allison 29540494).....	PT9415-MPG KIT
Steering (5839-84148A).....	P528
Service Kit (57GC2177B).....	BK6704
LEU w/Cummins ISL-G (8.9L) Eng.	
Dual-Flow Lube (3401544).....	BD7309 +
Lube (Upgrade) (3401544).....	B40142 +
Fuel/Water Separator (3606712).....	BF7695
Air (2MD2153).....	PA2317 +
Air Dryer (Bendix 5008414).....	[2] BA5374 +
Coolant (w/4 Units BTA+) (3315116).....	BW5071
Coolant (w/12 Units BTA+) (3100307).....	BW5074
Trans. Ele. (2 In. Kit) (Allison 29540493).....	PT9416-MPG KIT
Trans. Ele. (4 In. Kit) (Allison 29540494).....	PT9415-MPG KIT
Steering (Nelson 870678A).....	PT9394-MPG
LEU602 w/MP7 Eng.	
F-F Lube (20539275).....	[2] B76 +
B-P Lube Spinner (20552379).....	BC7242
B-P Lube Spin-on (20843764).....	B7409
<b>Fuel/Water Separator</b> (21017305).....	BF1386-O
<b>Fuel/Water Separator</b> (Remote Mtd.) (301SD19B).....	PF7680
Fuel (20539582).....	BF7814
Fuel (20972295).....	BF7943
Air (57MD33).....	PA2317 +
Air Dryer (Wabco R950011).....	[2] BA5374 +
Coolant (w/o Chemical) (20575545).....	B5091
Coolant (w/Chemical) (20539991).....	BW5183
Trans. (2 In. Kit) (Allison 29540493).....	PT9416-MPG KIT
Trans. (4 In. Kit) (Allison 29540494).....	PT9415-MPG KIT
Steering (5839-870678A).....	PT9394-MPG

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.

Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MACK Trucks (cont'd)	MACK Trucks (cont'd)	MACK Trucks (cont'd)
LEU603 w/MP7 Eng. F-F Lube (20539275)..... [2] B76 + B-P Lube Spinner (20552379).... BC7242 B-P Lube Spin-on (20843764)..... B7409 Fuel/Water Separator (21017305)..... BF1386-O Fuel/Water Separator Ele. (Remote Mtd.) (301SD19B)..... PF7680 Fuel (20539582)..... BF7814 Fuel (20972295)..... BF7943 Air (57MD33)..... PA2317 + Air Dryer (Wabco R950011)..... [2] BA5374 + Coolant (w/o Chemical) (20575545)..... B5091 Coolant (w/Chemical) (20539991)..... BW5183 Trans. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT Steering (5839-870678A)..... PT9394-MPG	LEU613 w/MP7 Eng. (Cont'd) Coolant (w/Chemical) (21937331)..... BW5183 Trans. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT Steering (5839-870678A)..... PT9394-MPG Diesel Exhaust Fluid (5303604).. PE17000 LR w/Cummins ISL-G (8.9L) Eng. (2019) Lube (Fleetguard LF9009)..... B40142 Fuel/Water Separator (Fleetguard NG5900)..... BF7695 Radial Seal O. Air (21328870).... RS3744 Radial Seal O. XP Air (21328870)..... RS3744XP Radial Seal I. Air (Don. P777414)..... RS3745 Cab Air (82745222)..... PA30330 Trans. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT LR w/Cummins ISL-G (8.9L) Eng. (2020) Lube (Fleetguard LF9009)..... B40142 Fuel (Fleetguard NG5900)..... BF7695 LR w/Cummins ISL-G (8.9L) Eng. (2022) Lube (5444774)..... B40142 Fuel/Water Separator (3607140). BF7695 LR w/MP7 (10.8L) Eng. (2019) F-F Lube (21707136)..... [2] B76 + B-P Lube (21707135)..... B7409 Severe Service F-F Lube (21707136)..... [2] B76-SS + Fuel/Water Separator (21737481)..... PF7930 Fuel (22094967)..... BF46117 Radial Seal O. Air (21328870).... RS3744 Radial Seal O. XP Air (21328870)..... RS3744XP Radial Seal I. Air (Don. P777414)..... RS3745 Cab Air (82745222)..... PA30330 Coolant (21937331)..... BW5183 Trans. (2 In. Kit) (Allison 29548987)..... PT9416-MPG KIT Trans. (4 In. Kit) (Allison 29548988)..... PT9415-MPG KIT LR w/MP7 (10.8L) Eng. (2020) F-F Lube (21707136)..... [2] B76 B-P Lube (21707135)..... B7409 Fuel/Water Separator (Open End for Bowl) (22094987)..... BF46182-O Fuel (22094967)..... BF46117 Coolant (21937331)..... BW5183	LR w/MP7 (10.8L) Eng. (2021) F-F Lube (21707136)..... [2] B76 B-P Lube (21707135)..... B7409 Trans. (2 In. Kit) (Allison 29558117)..... PT9416-MPG KIT Trans. (4 In. Kit) (Allison 29558118)..... PT9415-MPG KIT LR600 w/Cummins ISL-G (8.9L) Eng. (2018) Dual-Flow Lube (Fleetguard LF9009)..... BD7309 Fuel/Water Separator (Fleetguard NG5900)..... BF7695 Radial Seal Air (21328870)..... RS3744 Radial Seal XP Air (21328870).... RS3744XP Cab Air (82745222)..... PA30330 Coolant (w/4 Units BTA +) (Fleetguard WF2071)..... BW5071 Coolant (w/12 Units BTA+) (Fleetguard WF2074)..... BW5074 Trans. Ele. (2 In. Kit) (Allison 29548987)..... PT9416-MPG KIT Trans. Ele. (4 In. Kit) (Allison 29548988)..... PT9415-MPG KIT LR600 w/Cummins ISL-G (8.9L) Eng. (2019) Dual-Flow Lube (Fleetguard LF9009)..... BD7309 Fuel/Water Separator (Fleetguard NG5900)..... BF7695 Radial Seal O. Air (21328870).... RS3744 Radial Seal O. XP Air (21328870)..... RS3744XP Radial Seal I. Air (Don. P777414)..... RS3745 Cab Air (82745222)..... PA30330 Trans. Ele. (2 In. Kit) (Allison 29548987)..... PT9416-MPG KIT Trans. Ele. (4 In. Kit) (Allison 29548988)..... PT9415-MPG KIT LR600 w/MP7 (10.8L) Eng. (2019) F-F Lube (21707136)..... [2] B76 + B-P Lube (21707135)..... B7409 Severe Service F-F Lube (21707136)..... [2] B76-SS + Fuel/Water Separator (21737481)..... PF7930 Fuel (22094967)..... BF46117 Radial Seal O. Air (21328870).... RS3744 Radial Seal O. XP Air (21328870)..... RS3744XP Radial Seal I. Air (Don. P777414)..... RS3745 Cab Air (82745222)..... PA30330 Coolant (21937331)..... BW5183 Trans. (2 In. Kit) (Allison 29548987)..... PT9416-MPG KIT Trans. (4 In. Kit) (Allison 29548988)..... PT9415-MPG KIT
LEU612 w/MP7 Eng. F-F Lube (20539275)..... [2] B76 + B-P Lube (20843764)..... B7409 Severe Service F-F Lube (20539275)..... [2] B76-SS + Fuel/Water Separator (21017305)..... BF1386-O Fuel (20972295)..... BF7943 Air (57MD33)..... PA2317 + Air Dryer (Wabco R950011)..... [2] BA5374 + Coolant (w/o Chemical)..... B5091 Coolant (w/Chemical)..... BW5183 Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT Steering (5839-870678A)..... PT9394-MPG	LEU613 w/MP7 Eng. F-F Lube (21707136)..... [2] B76 + B-P Lube (21707135)..... B7409 Fuel/Water Separator Ele. (Davco 382 System) (Fleetguard FS19765)..... PF7930 Fuel/Water Separator Spin-on (21380521)..... BF1386-O Fuel (20539582)..... BF7814 Fuel (20972295)..... BF7943 Air (57MD33)..... PA2317 + Radial Seal Air (21328870)..... RS3744 Radial Seal XP Air (21328870).... RS3744XP Air Dryer (AD-IP System) (Bendix 65624)..... BA5373 Air Dryer (AD-9 System) (Bendix 107796)..... BA5377 Air Dryer (SS1200 System) (Wabco R950011)..... [2] BA5374 + Coolant (w/o Chemical) (20575545)..... B5091	LR600 w/MP7 (10.8L) Eng. (2019) F-F Lube (21707136)..... [2] B76 + B-P Lube (21707135)..... B7409 Severe Service F-F Lube (21707136)..... [2] B76-SS + Fuel/Water Separator (21737481)..... PF7930 Fuel (22094967)..... BF46117 Radial Seal O. Air (21328870).... RS3744 Radial Seal O. XP Air (21328870)..... RS3744XP Radial Seal I. Air (Don. P777414)..... RS3745 Cab Air (82745222)..... PA30330 Coolant (21937331)..... BW5183 Trans. (2 In. Kit) (Allison 29548987)..... PT9416-MPG KIT Trans. (4 In. Kit) (Allison 29548988)..... PT9415-MPG KIT

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MACK Trucks (cont'd)	MACK Trucks (cont'd)	MACK Trucks (cont'd)
LR613 w/MP7 (10.8L) Eng. (To 2017)	MB400, MC400, R400 Series w/ETZ477 Eng.	MD6 w/Cummins B6.7 (6.7L) Eng. (2022)
F-F Lube (21707136)..... [2] B76 +	Lube Spin-on..... B163	Lube (Fleetguard LF3970)..... B7177
B-P Lube (21707135)..... B7409	P. Fuel Spin-on..... BF877 +	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004
Severe Service F-F Lube (21707136)..... [2] B76-SS +	S. Fuel Spin-on..... BF876	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016
Fuel/Water Separator Ele. (Fleetguard FS19728)..... PF7782	MB400, R400 Series w/Scania END475 Eng.	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003
Fuel/Water Separator Ele. (21737481)..... PF7930	Fuel Ele. (237GB13)..... PF819	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017
Fuel (20972295)..... BF7943	MB600, R600, RD600, RL600, RS600, U600 Series w/ET673, ENDT673C Eng.	Trans. Spin-on (Allison 29539579)..... BT8460
Radial Seal Air (21328870)..... RS3744	ESI-Plus Service Kit (1977-on, (6 Spin-ons))..... BK6710	MD6 w/Cummins ISL (6.7L) Eng. (2021)
Radial Seal XP Air (21328870).... RS3744XP	MC w/Cat 3208 (10.4L) Eng.	Lube (Fleetguard LF3970)..... B7177
Cab Air (82745222)..... PA30330	Lube (9N5570)..... [2] BT230 +	Fuel (Fleetguard FF63009)..... BF63000
Coolant (w/Chemical) (21937331)..... BW5183	Lube (9L9200)..... [2] BT364	Radial Seal Air (Fleetguard AF25962)..... RS4992
Trans. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	Box-Style Fuel/Water Separator. BF912	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004
Trans. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Fuel Spin-on..... BF970 +	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016
Steering (Nelson 870678A)..... PT9394-MPG	Air (2MD3129)..... PA2312	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003
Diesel Exhaust Fluid (21516231) PE17000	Air (2MD4003)..... PA2482	Trans. Spin-on (Allison 29539579)..... BT8460
LR613 w/MP7 (10.8L) Eng. (2018)	Air (2MD491)..... PA2465	MD7 w/Cummins B6.7 (6.7L) Eng. (2021)
F-F Lube (21707136)..... [2] B76 +	MC w/E4 (7.8L) Eng.	Lube (3937736)..... B7177
B-P Lube (21707135)..... B7409	Lube..... B163	Fuel (5303743)..... BF63000
Severe Service F-F Lube (21707136)..... [2] B76-SS +	P. Fuel..... BF877 +	Crankcase Breather (4936636).... CV15010
Fuel/Water Separator (22094987)..... BF46182-O	S. Fuel..... BF876	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004
Fuel (22094967)..... BF46117	MC w/E6 (11.0L) Eng.	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016
Radial Seal Air (21328870)..... RS3744	F-F Lube..... [2] B76 +	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20017
Radial Seal XP Air (21328870).... RS3744XP	B-P Lube..... BC110	Trans. Spin-on (Allison 29539579)..... BT8460
Cab Air (82745222)..... PA30330	Severe Service F-F Lube..... [2] B76-SS +	MD7 w/Cummins B6.7 (6.7L) Eng. (2022)
Coolant (21937331)..... BW5183	P. Fuel..... BF877 +	Lube (3937736)..... B7177
Trans. (2 In. Kit) (Allison 29548987)..... PT9416-MPG KIT	S. Fuel..... BF976	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004
Trans. (4 In. Kit) (Allison 29548988)..... PT9415-MPG KIT	ESI-Plus Service Kit (6 Spin-ons) BK6710	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016
Diesel Exhaust Fluid (82269261) PE17001	Service Kit (5 Spin-ons + B-P Spinner)..... BK6720	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003
LJT, LJSWX w/END673 Eng.	MC w/EM6 (11.0L) Eng.	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017
F-F Lube Ele. (236GB123A)..... [2] P194 +	F-F Lube..... [2] B76 +	Trans. Spin-on (Allison 29539579)..... BT8460
B-P Lube Ele. (236GB36)..... C704-L +	B-P Lube..... BC110	MD7 w/Cummins B6.7 (6.7L) Eng. (2022)
M25XT, M30X, M60X, M65X w/GMC 16V-71N Eng.	Severe Service F-F Lube..... [2] B76-SS +	Lube (Fleetguard LF3970)..... B7177
F-F Lube Ele..... [4] P20-HD +	P. Fuel..... BF877 +	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004
B-P Lube Ele..... [4] P52	S. Fuel..... BF976	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016
P. Fuel Sock (5574980)..... F844-A	ESI-Plus Service Kit (6 Spin-ons) BK6710	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003
P. Fuel Ele. (5575032)..... PF845	Service Kit (5 Spin-ons + B-P Spinner)..... BK6720	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017
S. Fuel Ele..... PF846	MC w/EM6-L (11.0L) Eng.	Trans. Spin-on (Allison 29539579)..... BT8460
M-65AX w/Detroit Diesel 16V-71T Eng.	F-F Lube..... [2] B76 +	MD7 w/Cummins B6.7 (6.7L) Eng. (2023)
Air Breather (279GB210)..... PA1704	B-P Lube..... BC110	Lube (3937736)..... B7177
Magnum w/Cummins ISX/Signature-600 Eng.	Severe Service F-F Lube..... [2] B76-SS +	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004
Dual-Flow Lube (3406810)..... BD7153 +	P. Fuel..... BF877 +	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016
Fuel/Water Separator (3331096) BF1274-SP	S. Fuel..... BF976	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003
Coolant (3680433)..... BW5086	ESI-Plus Service Kit (6 Spin-ons) BK6710	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017
	Service Kit (5 Spin-ons + B-P Spinner)..... BK6720	Trans. Spin-on (Allison 29539579)..... BT8460
	MC w/EM7 (11.9L) Eng.	MD7 w/Cummins B6.7 (6.7L) Eng. (2023)
	Fuel/Water Separator (483GB433B)..... BF1219 +	Lube (3937736)..... B7177
	MD6 w/Cummins B6.7 (6.7L) Eng. (2021)	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004
	Lube (3937736)..... B7177	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016
	Fuel (5303743)..... BF63000	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003
	Crankcase Breather (4936636).... CV15010	Trans. Spin-on (Allison 29539579)..... BT8460

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>MACK Trucks (cont'd)</b>	<b>MACK Trucks (cont'd)</b>	<b>MACK Trucks (cont'd)</b>
MD7 w/Cummins ISL (6.7L) Eng. (2021) <b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	MH w/EM6-L (11.0L) Eng. <b>Opt. Air</b> (57MD44M)..... <b>PA2755</b> <b>ESI-Plus Service Kit</b> (6 Spin-ons) <b>BK6710</b> <b>Service Kit</b> (5 Spin-ons + B-P Spinner)..... <b>BK6720</b> MH602, MH603 Series w/Cummins KT450, KTA525 Engs. <b>F-F Lube Spin-on</b> ..... <b>[2] B196 +</b> <b>B-P Lube Ele.</b> ..... <b>C750-E +</b> <b>B-P Lube Spin-on</b> ..... <b>B7577</b> <b>Fuel Spin-on</b> ..... <b>BF957 +</b> <b>Opt. Air</b> (57MD44M)..... <b>PA2755</b> <b>Coolant</b> ..... <b>BW5073</b> MH602, RW602, MH603, RW603 w/Cummins Formula 300, NTC300, Formula 350, NTC350, 400, NTC400 Engs. <b>F-F Lube Spin-on</b> ..... <b>B196 +</b> <b>B-P Lube Ele.</b> ..... <b>C750-E +</b> <b>B-P Lube Spin-on</b> ..... <b>B7577</b> <b>Fuel Spin-on</b> ..... <b>BF957 +</b> <b>Opt. Air</b> (57MD44M)..... <b>PA2755</b> <b>Coolant</b> ..... <b>BW5071</b> MR w/Cat 3208 (10.4L) Eng. <b>Lube</b> (1R0713)..... <b>[2] BT230 +</b> <b>Lube</b> (1R0714)..... <b>[2] B75</b> <b>Lube</b> (9L9200)..... <b>[2] BT364</b> <b>Box-Style Fuel/Water Separator</b> (8N9803)..... <b>BF912</b> <b>P. Fuel Ele.</b> (9M2341)..... <b>PF935</b> <b>P. Fuel Spin-on</b> (1R0740)..... <b>BF970 +</b> <b>S. Fuel Spin-on</b> (1R0750)..... <b>BF7633 +</b> MR w/Cummins L10 (10.0L) Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Fuel/Water Separator</b> (3308638).. <b>BF1212 +</b> <b>Fuel</b> (154789)..... <b>BF957-D +</b> <b>Coolant</b> (4 Units BTA PLUS) (3315116)..... <b>BW5071</b> <b>Coolant</b> (15 Units BTA PLUS) (3318318)..... <b>BW5075</b> MR w/E6 (11.0L) Eng. <b>Fuel/Water Separator</b> (483GB433B)..... <b>BF1219 +</b> <b>Trans. Ele.</b> (HT Series) (Allison 29510918)..... <b>PT8330-MPG</b> MR w/EM7 (11.9L) Eng. <b>Fuel/Water Separator</b> (483GB433B)..... <b>BF1219 +</b> <b>Trans. Ele.</b> (HT Series) (Allison 29510918)..... <b>PT8330-MPG</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	MR600 w/AMI-300 Eng. <b>F-F Lube</b> (485GB3236)..... <b>[2] B7225 +</b> <b>B-P Lube Spinner</b> (57GC2231)... <b>BC7242</b> <b>P. Fuel</b> (483GB470M)..... <b>BF7656</b> <b>S. Fuel</b> (483GB471M)..... <b>BF7657</b> MR600 w/E7 E-Tech Eng. <b>F-F Lube</b> (485GB3191B)..... <b>[2] B76 +</b> <b>B-P Lube Spinner</b> (57GC2134A). <b>BC110</b> <b>B-P Lube Spinner</b> (57GC2187)... <b>BC7173</b> <b>P. Fuel</b> (483GB470M)..... <b>BF7656</b> <b>S. Fuel</b> (483GB471M)..... <b>BF7657</b> <b>Air</b> (57MD47)..... <b>PA3938</b> <b>Coolant</b> (25MF435B)..... <b>BW5178</b> <b>Service Kit</b> (57GC2177A)..... <b>BK6705</b> MR600 w/E5-250 Eng. <b>F-F Lube</b> (485GB3191B)..... <b>[2] B76 +</b> <b>P. Fuel</b> (483GB444)..... <b>BF877 +</b> <b>S. Fuel</b> (483GB441)..... <b>BF876</b> <b>Coolant</b> (25MF436B)..... <b>BW5179</b> MR600P, MR600S w/EM6-L (11.0L) Eng. <b>ESI-Plus Service Kit</b> (6 Spin-ons) <b>BK6710</b> <b>Service Kit</b> (5 Spin-ons + B-P Spinner)..... <b>BK6720</b> MR600P, MR600S w/AMI-300 (11.9L) Eng. (To 2003) <b>F-F Lube</b> (485GB3191B)..... <b>[2] B76 +</b> <b>B-P Lube Spinner</b> (To 11/11/03) (57GC2206)..... <b>BC7228</b> <b>B-P Lube Spinner</b> (11/11/03-on) (57GC2231)..... <b>BC7242</b> <b>Severe Service F-F Lube</b> (485GB3191B)..... <b>[2] B76-SS +</b> <b>Opt. Fuel/Water Separator</b> (483GB477M)..... <b>BF1286</b> <b>Opt. Fuel/Water Separator</b> (483GB472M)..... <b>BF1256</b> <b>P. Fuel</b> (483GB470AM)..... <b>BF7656</b> <b>S. Fuel</b> (483GB471M)..... <b>BF7657</b> <b>20 1/2 In. Air</b> (57MD47)..... <b>PA3938</b> <b>22 13/16 In. Air</b> (57MD26)..... <b>PA2312</b> <b>23 In. Air</b> (57MD33)..... <b>PA2317 +</b> <b>Channel Flow Air</b> (21020786).... <b>CA5789</b> <b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b> <b>Crankcase Breather</b> ..... <b>CLN&amp;R</b> <b>Coolant</b> (25MF435B)..... <b>BW5178</b> <b>Trans. Ele.</b> (2 In. Kit, 4000 Series) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit, 4000 Series) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Ele.</b> (EVS Series) (Allison 29545785)..... <b>PT23127-MPG</b> <b>Trans. Spin-on</b> (EVS Series) (Allison 29539579)..... <b>BT8460</b> <b>Steering</b> (5839-870678A)..... <b>PT9394-MPG</b>
Metro-Liner w/Cummins ISC Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel/Water Separator</b> (w/Oval Sensor) (Fleetguard FS1022)..... <b>BF1272-SPS</b> <b>Fuel/Water Separator</b> (w/Square Sensor) (Fleetguard FS1022)..... <b>BF1293-SPS</b> <b>Fuel</b> (Fleetguard FF5488)..... <b>BF7815</b> <b>Coolant</b> (Fleetguard WF2074)..... <b>BW5074</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	MH w/Cat 3406 (14.6L) Eng. <b>Lube</b> ..... <b>B99 +</b> <b>Fuel Spin-on</b> ..... <b>BF614 +</b> <b>Opt. Air</b> (57MD44M)..... <b>PA2755</b>	MR600P, MR600S w/AMI-300 (11.9L) Eng. (To 2003) <b>F-F Lube</b> (485GB3191B)..... <b>[2] B76 +</b> <b>B-P Lube Spinner</b> (To 11/11/03) (57GC2206)..... <b>BC7228</b> <b>B-P Lube Spinner</b> (11/11/03-on) (57GC2231)..... <b>BC7242</b> <b>Severe Service F-F Lube</b> (485GB3191B)..... <b>[2] B76-SS +</b> <b>Opt. Fuel/Water Separator</b> (483GB477M)..... <b>BF1286</b> <b>Opt. Fuel/Water Separator</b> (483GB472M)..... <b>BF1256</b> <b>P. Fuel</b> (483GB470AM)..... <b>BF7656</b> <b>S. Fuel</b> (483GB471M)..... <b>BF7657</b> <b>20 1/2 In. Air</b> (57MD47)..... <b>PA3938</b> <b>22 13/16 In. Air</b> (57MD26)..... <b>PA2312</b> <b>23 In. Air</b> (57MD33)..... <b>PA2317 +</b> <b>Channel Flow Air</b> (21020786).... <b>CA5789</b> <b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b> <b>Crankcase Breather</b> ..... <b>CLN&amp;R</b> <b>Coolant</b> (25MF435B)..... <b>BW5178</b> <b>Trans. Ele.</b> (2 In. Kit, 4000 Series) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit, 4000 Series) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Ele.</b> (EVS Series) (Allison 29545785)..... <b>PT23127-MPG</b> <b>Trans. Spin-on</b> (EVS Series) (Allison 29539579)..... <b>BT8460</b> <b>Steering</b> (5839-870678A)..... <b>PT9394-MPG</b>
MH w/Cummins N14 (14.0L) Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196 +</b> <b>B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Opt. Fuel/Water Separator</b> (3308638)..... <b>BF1212 +</b> <b>Fuel</b> (154789)..... <b>BF957-D +</b> <b>Coolant</b> (4 Units BTA PLUS) (3315116)..... <b>BW5071</b>	MH w/Detroit Diesel 6V-92N (9.0L) Eng. <b>F-F Lube Ele.</b> ..... <b>P20-HD +</b> <b>F-F Lube Spin-on</b> ..... <b>B95 +</b> <b>P. Fuel Spin-on</b> ..... <b>BF5800 +</b> <b>S. Fuel Spin-on</b> ..... <b>BF5810</b> <b>Opt. Air</b> (57MD44M)..... <b>PA2755</b>	MR600P, MR600S w/AMI-300 (11.9L) Eng. (To 2003) <b>F-F Lube</b> (485GB3191B)..... <b>[2] B76 +</b> <b>B-P Lube Spinner</b> (To 11/11/03) (57GC2206)..... <b>BC7228</b> <b>B-P Lube Spinner</b> (11/11/03-on) (57GC2231)..... <b>BC7242</b> <b>Severe Service F-F Lube</b> (485GB3191B)..... <b>[2] B76-SS +</b> <b>Opt. Fuel/Water Separator</b> (483GB477M)..... <b>BF1286</b> <b>Opt. Fuel/Water Separator</b> (483GB472M)..... <b>BF1256</b> <b>P. Fuel</b> (483GB470AM)..... <b>BF7656</b> <b>S. Fuel</b> (483GB471M)..... <b>BF7657</b> <b>20 1/2 In. Air</b> (57MD47)..... <b>PA3938</b> <b>22 13/16 In. Air</b> (57MD26)..... <b>PA2312</b> <b>23 In. Air</b> (57MD33)..... <b>PA2317 +</b> <b>Channel Flow Air</b> (21020786).... <b>CA5789</b> <b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b> <b>Crankcase Breather</b> ..... <b>CLN&amp;R</b> <b>Coolant</b> (25MF435B)..... <b>BW5178</b> <b>Trans. Ele.</b> (2 In. Kit, 4000 Series) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit, 4000 Series) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Ele.</b> (EVS Series) (Allison 29545785)..... <b>PT23127-MPG</b> <b>Trans. Spin-on</b> (EVS Series) (Allison 29539579)..... <b>BT8460</b> <b>Steering</b> (5839-870678A)..... <b>PT9394-MPG</b>
MH w/E7 (11.9L) Eng. <b>F-F Lube</b> (485GB3232)..... <b>[2] B7225 +</b> <b>B-P Lube Spinner</b> (57GC2206)... <b>BC7228</b> <b>Fuel/Water Separator</b> (483GB433B)..... <b>BF1219 +</b> <b>Fuel</b> (483GB476M)..... <b>BF7773</b>	MH w/E9 (16.4L) Eng. <b>Opt. Air</b> (57MD44M)..... <b>PA2755</b> <b>Std. Service Kit</b> (5 Spin-ons)..... <b>BK6700</b>	MR600P, MR600S w/AMI-300 (11.9L) Eng. (To 2003) <b>F-F Lube</b> (485GB3191B)..... <b>[2] B76 +</b> <b>B-P Lube Spinner</b> (To 11/11/03) (57GC2206)..... <b>BC7228</b> <b>B-P Lube Spinner</b> (11/11/03-on) (57GC2231)..... <b>BC7242</b> <b>Severe Service F-F Lube</b> (485GB3191B)..... <b>[2] B76-SS +</b> <b>Opt. Fuel/Water Separator</b> (483GB477M)..... <b>BF1286</b> <b>Opt. Fuel/Water Separator</b> (483GB472M)..... <b>BF1256</b> <b>P. Fuel</b> (483GB470AM)..... <b>BF7656</b> <b>S. Fuel</b> (483GB471M)..... <b>BF7657</b> <b>20 1/2 In. Air</b> (57MD47)..... <b>PA3938</b> <b>22 13/16 In. Air</b> (57MD26)..... <b>PA2312</b> <b>23 In. Air</b> (57MD33)..... <b>PA2317 +</b> <b>Channel Flow Air</b> (21020786).... <b>CA5789</b> <b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b> <b>Crankcase Breather</b> ..... <b>CLN&amp;R</b> <b>Coolant</b> (25MF435B)..... <b>BW5178</b> <b>Trans. Ele.</b> (2 In. Kit, 4000 Series) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit, 4000 Series) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Ele.</b> (EVS Series) (Allison 29545785)..... <b>PT23127-MPG</b> <b>Trans. Spin-on</b> (EVS Series) (Allison 29539579)..... <b>BT8460</b> <b>Steering</b> (5839-870678A)..... <b>PT9394-MPG</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).


MACK Trucks (cont'd)	MACK Trucks (cont'd)	MACK Trucks (cont'd)
MR600P, MR600S w/AMI-300 (11.9L) Eng. (2004-07)	MR600S w/Al-300A (11.9L) Eng. (2004-on)	MR688P, MR688S w/ASET Al, AMI Series Engs. (Cont'd)
F-F Lube (485GB3236)..... [2] B7225 +	F-F Lube (485GB3236)..... [2] B7225 +	Service Kit (215SB325A)..... BK6693
B-P Lube Spinner (57GC2231)... BC7242	B-P Lube Spinner (57GC2231)... BC7242	Service Kit (57GC2234)..... BK6657 <sup>90</sup>
Opt. Fuel/Water Separator (483GB477M)..... BF1286	Opt. Fuel/Water Separator (483GB477M)..... BF1286	MR688S w/E7 Eng.
Opt. Fuel/Water Separator (483GB472M)..... BF1256	Opt. Fuel/Water Separator (483GB472M)..... BF1256	F-F Lube Spin-on..... [2] B7225 +
P. Fuel (483GB470AM)..... BF7656	P. Fuel (483GB470AM)..... BF7656	B-P Lube Spinner..... BC110
S. Fuel (483GB471M)..... BF7657	S. Fuel (483GB471M)..... BF7657	B-P Lube Spinner (57GC2187)... BC7173
20 1/2 In. Air (57MD47)..... PA3938	20 1/2 In. Air (57MD47)..... PA3938	P. Fuel..... BF877 +
22 13/16 In. Air (57MD26)..... PA2312	22 13/16 In. Air (57MD26)..... PA2312	S. Fuel..... BF976
23 In. Air (57MD33)..... PA2317 +	23 In. Air (57MD33)..... PA2317 +	S. Fuel (483GB471M)..... BF7657
Channel Flow Air (21020786)..... CA5789	Channel Flow Air (21020786)..... CA5789	22 13/16 In. Air..... PA2312
Air Dryer (Bendix 107796)..... BA5377	Air Dryer (Bendix 107796)..... BA5377	20 15/32 In. Air (57MD47)..... PA3938
Crankcase Breather..... CLN&R	Crankcase Breather..... CLN&R	Coolant (w/o Chemical)..... B5176
Coolant (25MF435B)..... BW5178	Coolant (25MF435B)..... BW5178	Coolant (w/Chemical) (25MF435B)..... BW5178
Trans. Ele. (2 In. Kit, 4000 Series) (Allison 29540493)..... PT9416-MPG KIT	Trans. Ele. (2 In. Kit, 4000 Series) (Allison 29540493)..... PT9416-MPG KIT	Trans. Spin-on..... BT359
Trans. Ele. (4 In. Kit, 4000 Series) (Allison 29540494)..... PT9415-MPG KIT	Trans. Ele. (4 In. Kit, 4000 Series) (Allison 29540494)..... PT9415-MPG KIT	Steering..... P528
Trans. Ele. (EVS Series) (Allison 29545785)..... PT23127-MPG	Trans. (EVS Series) (Allison 29545785)..... PT23127-MPG	MR690P w/AMI ASET Engs.
Trans. Spin-on (EVS Series) (Allison 29539579)..... BT8460	Trans. Spin-on (EVS Series) (Allison 29539579)..... BT8460	F-F Lube (To 2004) (485GB3191B)..... [2] B76 +
Steering (5839-870678A)..... PT9394-MPG	Steering (5839-870678A)..... PT9394-MPG	F-F Lube (2004-on) (485GB3236)..... [2] B7225 +
Service Kit (215SB325A)..... BK6693	Service Kit (215SB325A)..... BK6693	B-P Lube Ele. (57GC2187)..... BC7173
Service Kit (57GC2234)..... BK6657 <sup>90</sup>	Service Kit (57GC2234)..... BK6657 <sup>90</sup>	B-P Lube Spinner (To 11/11/03) (57GC2206)..... BC7228
MR600S w/Al-300A (11.9L) Eng. (To 2003)	MR688P, MR688S w/ASET Al, AMI Series Engs.	B-P Lube Spinner (11/11/03-on) (57GC2231)..... BC7242
F-F Lube (485GB3191B)..... [2] B76 +	F-F Lube (To 2004) (485GB3191B)..... [2] B76 +	Severe Service F-F Lube (To 2004) (485GB3191B)..... [2] B76-SS +
B-P Lube Spinner (To 11/11/03) (57GC2206)..... BC7228	F-F Lube (2004-on) (485GB3236)..... [2] B7225 +	Opt. Fuel/Water Separator (483GB477M)..... BF1286
B-P Lube Spinner (11/11/03-on) (57GC2231)..... BC7242	B-P Lube Spinner (To 11/11/03) (57GC2206)..... BC7228	Opt. Fuel/Water Separator (483GB472M)..... BF1256
Severe Service F-F Lube (485GB3191B)..... [2] B76-SS +	B-P Lube Spinner (11/11/03-on) (57GC2231)..... BC7242	P. Fuel (483GB470AM)..... BF7656
Opt. Fuel/Water Separator (483GB477M)..... BF1286	Opt. Fuel/Water Separator (483GB477M)..... BF1286	S. Fuel (483GB471M)..... BF7657
Opt. Fuel/Water Separator (483GB472M)..... BF1256	Opt. Fuel/Water Separator (483GB472M)..... BF1256	20 1/2 In. Air (57MD47)..... PA3938
P. Fuel (483GB470AM)..... BF7656	P. Fuel (483GB470AM)..... BF7656	22 13/16 In. Air (57MD26)..... PA2312
S. Fuel (483GB471M)..... BF7657	S. Fuel (483GB471M)..... BF7657	23 In. Air (57MD33)..... PA2317 +
20 1/2 In. Air (57MD47)..... PA3938	20 1/2 In. Air (57MD47)..... PA3938	Channel Flow Air (21020786)..... CA5789
22 13/16 In. Air (57MD26)..... PA2312	22 13/16 In. Air (57MD26)..... PA2312	Air Dryer (Bendix 107796)..... BA5377
23 In. Air (57MD33)..... PA2317 +	23 In. Air (57MD33)..... PA2317 +	Crankcase Breather..... CLN&R
Channel Flow Air (21020786)..... CA5789	Channel Flow Air (21020786)..... CA5789	Coolant (25MF435B)..... BW5178
Air Dryer (Bendix 107796)..... BA5377	Air Dryer (Bendix 107796)..... BA5377	Trans. Ele. (2 In. Kit, 4000 Series) (Allison 29540493)..... PT9416-MPG KIT
Crankcase Breather..... CLN&R	Crankcase Breather..... CLN&R	Trans. Ele. (4 In. Kit, 4000 Series) (Allison 29540494)..... PT9415-MPG KIT
Coolant (25MF435B)..... BW5178	Coolant (25MF435B)..... BW5178	Trans. Ele. (EVS Series) (Allison 29545785)..... PT23127-MPG
Trans. Ele. (2 In. Kit, 4000 Series) (Allison 29540493)..... PT9416-MPG KIT	Trans. Ele. (2 In. Kit, 4000 Series) (Allison 29540493)..... PT9416-MPG KIT	Trans. Spin-on (EVS Series) (Allison 29539579)..... BT8460
Trans. Ele. (4 In. Kit, 4000 Series) (Allison 29540494)..... PT9415-MPG KIT	Trans. Ele. (4 In. Kit, 4000 Series) (Allison 29540494)..... PT9415-MPG KIT	Steering (5839-870678A)..... PT9394-MPG
Trans. Ele. (EVS Series) (Allison 29545785)..... PT23127-MPG	Trans. Ele. (EVS Series) (Allison 29545785)..... PT23127-MPG	Service Kit..... BK6613
Trans. Spin-on (EVS Series) (Allison 29539579)..... BT8460	Trans. Spin-on (EVS Series) (Allison 29539579)..... BT8460	Service Kit..... BK6658 <sup>90</sup>
Steering (5839-870678A)..... PT9394-MPG	Steering (5839-870678A)..... PT9394-MPG	Service Kit (57GC2188A)..... BK6696
		Service Kit..... BK6694
		Service Kit (57GC2234)..... BK6657 <sup>90</sup>
		Service Kit (57GC2235)..... BK6693

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MACK Trucks (cont'd)	MACK Trucks (cont'd)	MACK Trucks (cont'd)
MR690S w/E-7 Eng. Trans. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	MRU w/MP8 (12.8L) Eng. (11/11/2008-2017) (Cont'd) <b>Radial Seal Air</b> (25100042)..... <b>RS4634</b> <b>Radial Seal XP Air</b> (25100042).... <b>RS4634XP</b> <b>Air Dryer</b> (Wabco R950011)..... <b>[2] BA5374 +</b> <b>Coolant</b> (w/o Chemical) (20575545)..... <b>B5091</b> <b>Coolant</b> (w/Chemical)..... <b>BW5183</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (5839-870678A)..... <b>PT9394-MPG</b>	MRU602 w/MP7 Eng. (Cont'd) <b>Trans. Spin-on</b> (EVS Series) (Allison 29539579)..... <b>BT8460</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (5839-870678A)..... <b>PT9394-MPG</b>
MRE w/EM6 (11.0L) Eng. <b>Fuel/Water Separator</b> (483GB433B)..... <b>BF1219 +</b>	MRU w/Cummins ISL-G (8.9L) Eng. (2011-17) <b>Dual-Flow Lube</b> (Fleetguard LF3000)..... <b>BD103 +</b> <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel</b> (Fleetguard NG5900)..... <b>BF7695</b> <b>Radial Seal Air</b> (21328870)..... <b>RS3744 +</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (5839-870678A)..... <b>PT9394-MPG</b>	MRU603 w/MP7 Eng. <b>F-F Lube</b> (20539275)..... <b>[2] B76 +</b> <b>B-P Lube Spinner</b> (20552379).... <b>BC7242</b> <b>B-P Lube Spin-on</b> (20843764).... <b>B7409</b> <b>Fuel/Water Separator</b> (20863191)..... <b>BF1386-O</b> <b>Fuel</b> (20539582)..... <b>BF7814</b> <b>Fuel</b> (20972295)..... <b>BF7943</b> <b>Air</b> (57MD311)..... <b>PA2317 +</b> <b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b> <b>Coolant</b> (w/o Chemical) (20575545)..... <b>B5091</b> <b>Coolant</b> (w/Chemical) (20539991)..... <b>BW5183</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (EVS Series) (Allison 29539579)..... <b>BT8460</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (5839-870678A)..... <b>PT9394-MPG</b>
MRU w/Cummins ISL-G (8.9L) Eng. (2018) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel/Water Separator</b> (2514003C1)..... <b>BF46181-O</b> <b>Fuel</b> (Fleetguard FF63008)..... <b>BF63000</b> <b>Radial Seal Air</b> (21328870)..... <b>RS3744</b> <b>Radial Seal XP Air</b> (21328870).... <b>RS3744XP</b> <b>Crankcase Breather</b> (4936636).... <b>CV15010</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (5839870678A)..... <b>PT9394-MPG</b>	MRU w/MP8 (12.8L) Eng. (2018) <b>F-F Lube</b> (20539275)..... <b>[2] B76 +</b> <b>B-P Lube</b> (20843764)..... <b>B7409</b> <b>Severe Service F-F Lube</b> (20539275)..... <b>[2] B76-SS +</b> <b>Fuel/Water Separator</b> (21017305)..... <b>BF1386-O</b> <b>Fuel</b> (20972295)..... <b>BF7943</b> <b>Fuel</b> (20539582)..... <b>BF7814</b> <b>Axial Seal Air</b> (57MD47)..... <b>PA3938</b> <b>Radial Seal Air</b> (25100042)..... <b>RS4634</b> <b>Radial Seal XP Air</b> (25100042).... <b>RS4634XP</b> <b>Air Dryer</b> (85110799)..... <b>BA5592<sup>90</sup></b> <b>Coolant</b> (w/o Chemical) (20575545)..... <b>B5091</b> <b>Coolant</b> (w/Chemical)..... <b>BW5183</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (5839-870678A)..... <b>PT9394-MPG</b> <b>Diesel Exhaust Fluid</b> (82269261) <b>PE17001</b>	MRU602 w/MP7 Eng. (Cont'd) <b>F-F Lube</b> (20539275)..... <b>[2] B76 +</b> <b>B-P Lube</b> (20843764)..... <b>B7409</b> <b>Severe Service F-F Lube</b> (20539275)..... <b>[2] B76-SS +</b> <b>Fuel/Water Separator</b> (21017305)..... <b>BF1386-O</b> <b>Fuel</b> (20972295)..... <b>BF7943</b> <b>Air</b> (57MD47)..... <b>PA3938</b> <b>Air Dryer</b> (Wabco R950011)..... <b>[2] BA5374 +</b> <b>Air Dryer</b> (85110799)..... <b>BA5592<sup>90</sup></b> <b>Coolant</b> (w/o Chemical)..... <b>B5091</b> <b>Coolant</b> (w/Chemical)..... <b>BW5183</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (5839-870678A)..... <b>PT9394-MPG</b>
MRU w/Cummins ISL-G (8.9L) Eng. (2019) <b>Lube</b> (Fleetguard LF9009)..... <b>B40142</b> <b>Fuel/Water Separator</b> (Fleetguard NG5900)..... <b>BF7695</b> <b>Radial Seal Air</b> (21328870)..... <b>RS3744</b> <b>Radial Seal XP Air</b> (21328870).... <b>RS3744XP</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (5839870678A)..... <b>PT9394-MPG</b>	MRU602 w/MP7 Eng. <b>F-F Lube</b> (20539275)..... <b>[2] B76 +</b> <b>B-P Lube Spinner</b> (20552379).... <b>BC7242</b> <b>B-P Lube Spin-on</b> (20843764).... <b>B7409</b> <b>Fuel/Water Separator</b> (21017305)..... <b>BF1386-O</b> <b>Fuel</b> (20539582)..... <b>BF7814</b> <b>Fuel</b> (20972295)..... <b>BF7943</b> <b>Air</b> (57MD47)..... <b>PA3938</b> <b>Air</b> (57MD33)..... <b>PA2317 +</b> <b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b> <b>Coolant</b> (w/o Chemical) (20575545)..... <b>B5091</b> <b>Coolant</b> (w/Chemical) (20539991)..... <b>BW5183</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	MRU612 w/MP7 Eng. <b>F-F Lube</b> (20539275)..... <b>[2] B76 +</b> <b>B-P Lube</b> (20843764)..... <b>B7409</b> <b>Severe Service F-F Lube</b> (20539275)..... <b>[2] B76-SS +</b> <b>Fuel/Water Separator</b> (21017305)..... <b>BF1386-O</b> <b>Fuel</b> (20972295)..... <b>BF7943</b> <b>Air</b> (57MD47)..... <b>PA3938</b> <b>Air Dryer</b> (Wabco R950011)..... <b>[2] BA5374 +</b> <b>Air Dryer</b> (85110799)..... <b>BA5592<sup>90</sup></b> <b>Coolant</b> (w/o Chemical)..... <b>B5091</b> <b>Coolant</b> (w/Chemical)..... <b>BW5183</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (5839-870678A)..... <b>PT9394-MPG</b>
MRU w/MP8 (12.8L) Eng. (11/11/2008-2017) <b>F-F Lube</b> (20539275)..... <b>[2] B76 +</b> <b>B-P Lube</b> (20843764)..... <b>B7409</b> <b>Severe Service F-F Lube</b> (20539275)..... <b>[2] B76-SS +</b> <b>Fuel/Water Separator</b> (21017305)..... <b>BF1386-O</b> <b>Fuel</b> (20972295)..... <b>BF7943</b> <b>Fuel</b> (20539582)..... <b>BF7814</b> <b>Axial Seal Air</b> (57MD47)..... <b>PA3938</b>	MRU612 w/MP8 Eng. <b>F-F Lube</b> (20539275)..... <b>[2] B76 +</b> <b>B-P Lube</b> (20843764)..... <b>B7409</b> <b>Severe Service F-F Lube</b> (20539275)..... <b>[2] B76-SS +</b> <b>Fuel/Water Separator</b> (21017305)..... <b>BF1386-O</b> <b>Fuel</b> (20972295)..... <b>BF7943</b> <b>Air</b> (57MD47)..... <b>PA3938</b> <b>Air Dryer</b> (Wabco R950011)..... <b>[2] BA5374 +</b>	

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MACK Trucks (cont'd)	MACK Trucks (cont'd)	MACK Trucks (cont'd)
MRU612 w/MP8 Eng. (Cont'd)	MRU613 w/MP7 (10.8L) Eng. (2008-17)	MRU613 w/MP8 Eng. (To 11/10/2008) (Cont'd)
Air Dryer (85110799)..... BA5592 <sup>90</sup>	(Cont'd)	Air Dryer (Wabco R950011)..... [2] BA5374 +
Coolant (w/o Chemical)..... B5091	Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	Coolant (w/o Chemical)..... B5091
Coolant (w/Chemical)..... BW5183	Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Coolant (w/Chemical)..... BW5183
Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	Trans. Spin-on (EVS Series) (Allison 29539579)..... BT8460	Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT
Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Opt. Trans. Spin-on (Fuller 17237)..... B2 +	Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT
Opt. Trans. Spin-on (Fuller 17237)..... B2 +	Steering (5839-870678A)..... PT9394-MPG	Opt. Trans. Spin-on (Fuller 17237)..... B2 +
Steering (5839-870678A)..... PT9394-MPG	Diesel Exhaust Fluid (5303604)..... PE17000	Steering (5839-870678A)..... PT9394-MPG
MRU613 w/Cummins ISL-G Eng.	MRU613 w/MP7 (10.8L) Eng. (2018)	MRU613 w/MP8 (12.8L) Eng. (11/11/2008-on)
Dual-Flow Lube (Fleetguard LF3000)..... BD103 +	F-F Lube (21707136)..... [2] B76 +	F-F Lube (20539275)..... [2] B76 +
Dual-Flow Lube (Fleetguard LF9009)..... BD7309 +	B-P Lube (21707135)..... B7409	B-P Lube (20843764)..... B7409
Fuel (Fleetguard NG5900)..... BF7695	Severe Service F-F Lube (21707136)..... [2] B76-SS +	Severe Service F-F Lube (20539275)..... [2] B76-SS +
Radial Seal Air (21328870)..... RS3744 +	Fuel/Water Separator (22094987)..... BF46182-O	Fuel/Water Separator (21017305)..... BF1386-O
Coolant (w/4 Units BTA +) (Fleetguard WF2071)..... BW5071	Fuel (22094967)..... BF46117	Fuel (20972295)..... BF7943
Coolant (w/12 Units BTA+) (Fleetguard WF2074)..... BW5074	Radial Seal Air (21328870)..... RS3744	Fuel (20539582)..... BF7814
Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	Radial Seal XP Air (21328870)..... RS3744XP	Axial Seal Air (57MD47)..... PA3938
Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Coolant (21937331)..... BW5183	Radial Seal Air (25100042)..... RS4634
Steering (5839-870678A)..... PT9394-MPG	Trans. (2 In. Kit) (Allison 29548987)..... PT9416-MPG KIT	Radial Seal XP Air (25100042)..... RS4634XP
MRU613 w/MP7 (10.8L) Eng. (2008-17)	Trans. (4 In. Kit) (Allison 29548988)..... PT9415-MPG KIT	Air Dryer (85110799)..... BA5592 <sup>90</sup>
F-F Lube (21707136)..... [2] B76 +	Steering (5839-870678A)..... PT9394-MPG	Coolant (w/o Chemical) (20575545)..... B5091
B-P Lube Spinner (20552379)..... BC7242	Diesel Exhaust Fluid (Pump Filter) (21516231)..... PE17000	Coolant (w/Chemical)..... BW5183
B-P Lube Spin-on (21707135)..... B7409	MRU613 w/MP7 (10.8L) Eng. (2019)	Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT
Fuel/Water Separator Ele. (Racor 2020SM-OR)..... PF7890	F-F Lube (21707136)..... [2] B76 +	Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT
Fuel/Water Separator Ele. (Racor 2020TM-OR)..... PF7890-10	B-P Lube (21707135)..... B7409	Opt. Trans. Spin-on (Fuller 17237)..... B2 +
Fuel/Water Separator Ele. (Racor 2020PM-OR)..... PF7890-30	Severe Service F-F Lube (21707136)..... [2] B76-SS +	Steering (5839-870678A)..... PT9394-MPG
Fuel/Water Separator Ele. (Fleetguard FS19728)..... PF7782	Fuel/Water Separator (22094987)..... BF46182-O	MS200
Fuel/Water Separator Ele. (Davco 382 System) (Fleetguard FS19765)..... PF7930	Fuel (22094967)..... BF46117	Lube (485GB3191B)..... [2] B76 +
Fuel/Water Separator Spin-on (21380521)..... BF1386-O	Radial Seal Air (21328870)..... RS3744	P. Fuel (483GB444)..... BF877 +
Fuel (20539582)..... BF7814	Radial Seal XP Air (21328870)..... RS3744XP	S. Fuel (483GB441)..... BF876
Fuel (20972295)..... BF7943	Coolant (21937331)..... BW5183	Air (57MD27)..... PA2540 +
20 15/32 In. Air (57MD47)..... PA3938	Trans. (2 In. Kit) (Allison 29548987)..... PT9416-MPG KIT	Air (w/Lid) (2191P138427)..... PA2677
23 In. Air (57MD33)..... PA2317 +	Trans. (4 In. Kit) (Allison 29548988)..... PT9415-MPG KIT	Coolant (25MF435)..... BW5178
Radial Seal Air (21328870)..... RS3744 +	Steering (5839870678A)..... PT9394-MPG	MS200P w/E3-190 Eng.
Radial Seal XP Air (21328870)..... RS3744XP +	Diesel Exhaust Fluid (21516231)..... PE17000	Lube (485GB3191B)..... [2] B76 +
Radial Seal Air (57MD320M)..... RS4634	MRU613 w/MP8 Eng. (To 11/10/2008)	P. Fuel (483GB444)..... BF877 +
Radial Seal XP Air (57MD320M)..... RS4634XP	F-F Lube (20539275)..... [2] B76 +	S. Fuel (483GB441)..... BF876
Air Dryer (Wabco R950011)..... [2] BA5374 +	B-P Lube (20843764)..... B7409	Air (Don. P775100)..... PA2677
Air Dryer (85110799)..... BA5592 <sup>90</sup>	Severe Service F-F Lube (20539275)..... [2] B76-SS +	Coolant (25MF435)..... BW5178
Coolant (w/o Chemical) (20575545)..... B5091	Fuel/Water Separator (21017305)..... BF1386-O	MS200P Mid-Liner w/Renault MIDR06.02.12 (5.5L) Eng.
Coolant (w/Chemical) (21937331)..... BW5183	Fuel (20972295)..... BF7943	Lube (485GB3191)..... B76 +
	Fuel (20539582)..... BF7814	Severe Service F-F Lube (485GB3191)..... B76-SS +
	Axial Seal Air (57MD47)..... PA3938	P. Fuel (483GB444)..... BF877 +
	Radial Seal Air (25100042)..... RS4634	S. Fuel (483GB441)..... BF876
	Radial Seal XP Air (25100042)..... RS4634XP	Conical Air (57MD27)..... PA2540 +
		Coolant (25MF428)..... BW5178

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>MACK Trucks (cont'd)</b>	<b>MACK Trucks (cont'd)</b>	<b>MACK Trucks (cont'd)</b>
MS203 Air (5010317163)..... <b>PA2474</b>	MS300P Mid-Liner w/Renault MIDS06.20.30 (8.8L) Eng. (Cont'd) Coolant (25MF428)..... <b>BW5178</b>	Pinnacle w/MP8 (12.8L) Eng. (2019) (Cont'd) <b>Fuel/Water Separator</b> (21737481)..... <b>PF7930</b> Fuel (22094967)..... <b>BF46117</b> Radial Seal Air (25100042)..... <b>RS4634</b> Radial Seal XP Air (25100042).... <b>RS4634XP</b> Cab Air (3543H9638)..... <b>PA30277</b> Air Dryer (Bendix 107794PG)..... <b>BA5377</b> Coolant (21937331)..... <b>BW5183</b> Trans. Ele. (22038908)..... <b>PT9417</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Steering (349619)..... <b>P106-HD</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid Strainer</b> (82269261)..... <b>PE17001</b> <b>Diesel Exhaust Fluid Ele.</b> (21516229)..... <b>PE17000</b>
MS250 F-F Lube (485GB3191B)..... <b>[2] B76 +</b> P. Fuel (483GB444)..... <b>BF877 +</b> S. Fuel (483GB441)..... <b>BF876</b> Air (57MD27)..... <b>PA2540 +</b> Air (w/Lid) (2191P138427)..... <b>PA2677</b> Coolant (25MF435)..... <b>BW5178</b>	MS300T Mid-Liner w/Renault MIDR06.02.26 (6.2L) Eng. Lube (485GB3191)..... <b>B76 +</b> <b>Severe Service F-F Lube</b> (485GB3191)..... <b>B76-SS +</b> P. Fuel (483GB444)..... <b>BF877 +</b> S. Fuel (483GB441)..... <b>BF876</b> Conical Air (57MD27)..... <b>PA2540 +</b> Conical Air (w/Lid) (2191P138427)..... <b>PA2677</b> Coolant (25MF428)..... <b>BW5178</b>	Pinnacle w/MP8 (12.8L) Eng. (2020) F-F Lube (21707136)..... <b>[2] B76 +</b> B-P Lube (21707135)..... <b>B7409</b> <b>Severe Service F-F Lube</b> (21707136)..... <b>[2] B76-SS +</b> <b>Fuel/Water Separator Ele.</b> (21737481)..... <b>PF7930</b> <b>Fuel/Water Separator Spin-on</b> (22094987)..... <b>BF46182-O</b> Fuel (22094967)..... <b>BF46117</b> Radial Seal Air (25100042)..... <b>RS4634</b> Radial Seal XP Air (25100042).... <b>RS4634XP</b> Cab Air (85151124)..... <b>PA30325</b> Air Dryer (Wabco R950011)..... <b>BA5374 +</b> Coolant (w/o Chemical) (21937298)..... <b>B5091</b> Coolant (w/Chemical) (21937331)..... <b>BW5183</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>
MS250P w/E3-190 Eng. F-F Lube (485GB3191B)..... <b>[2] B76 +</b> P. Fuel (483GB444)..... <b>BF877 +</b> S. Fuel (483GB441)..... <b>BF876</b> Air (81SD44)..... <b>PA2677</b> Coolant (25MF435)..... <b>BW5178</b>	MS300T Mid-Liner w/Renault MIDS06.20.30 (8.8L) Eng. Lube (485GB3191)..... <b>B76 +</b> <b>Severe Service F-F Lube</b> (485GB3191)..... <b>B76-SS +</b> P. Fuel (483GB444)..... <b>BF877 +</b> S. Fuel (483GB441)..... <b>BF876</b> Conical Air (57MD27)..... <b>PA2540 +</b> Conical Air (w/Lid) (2191P138427)..... <b>PA2677</b> Coolant (25MF428)..... <b>BW5178</b>	<b>Fuel/Water Separator Spin-on</b> (22094987)..... <b>BF46182-O</b> Fuel (22094967)..... <b>BF46117</b> Radial Seal Air (25100042)..... <b>RS4634</b> Radial Seal XP Air (25100042).... <b>RS4634XP</b> Cab Air (85151124)..... <b>PA30325</b> Air Dryer (Wabco R950011)..... <b>BA5374 +</b> Coolant (w/o Chemical) (21937298)..... <b>B5091</b> Coolant (w/Chemical) (21937331)..... <b>BW5183</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>
MS250P w/Renault MIDR06.02.12 (5.5L) Eng. Lube (485GB3191)..... <b>B76 +</b> <b>Severe Service F-F Lube</b> (485GB3191)..... <b>B76-SS +</b> P. Fuel (483GB444)..... <b>BF877 +</b> S. Fuel (483GB441)..... <b>BF876</b> Conical Air (57MD27)..... <b>PA2540 +</b> Coolant (25MF428)..... <b>BW5178</b>	MV222L w/Renault E3 Eng. Lube (485GB3191B)..... <b>B76 +</b> P. Fuel (Renault 5000541768)..... <b>BF877 +</b> S. Fuel (Renault 5000133546)..... <b>BF876</b> Coolant (Renault 5000133551).... <b>BW5178</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	Pinnacle w/MP8 (12.8L) Eng. (2021) Lube (23155587)..... <b>[2] B40153</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19764G)..... <b>PF46091</b> <b>Fuel/Water Separator Spin-on</b> (23879508)..... <b>BF46182-O</b> Fuel (23856895)..... <b>BF46117</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
MS300 F-F Lube (485GB3191B)..... <b>[2] B76 +</b> P. Fuel (483GB444)..... <b>BF877 +</b> S. Fuel (483GB441)..... <b>BF876</b> Air (57MD27)..... <b>PA2540 +</b> Air (w/Lid) (2191P138427)..... <b>PA2677</b> Coolant (25MF435)..... <b>BW5178</b>	MS300P Mid-Liner w/Renault MIDR06.02.26 (6.2L) Eng. Lube (485GB3191)..... <b>B76 +</b> <b>Severe Service F-F Lube</b> (485GB3191)..... <b>B76-SS +</b> P. Fuel (483GB444)..... <b>BF877 +</b> S. Fuel (483GB441)..... <b>BF876</b> Conical Air (57MD27)..... <b>PA2540 +</b> Conical Air (w/Lid) (2191P138427)..... <b>PA2677</b> Coolant (25MF428)..... <b>BW5178</b>	Pinnacle w/MP8 (12.8L) Eng. (2022) Opt. Trans. (Fuller 17237)..... <b>B2</b> Trans. (Fuller 4304827)..... <b>BT223</b>
MS300P w/E3-220 Eng. F-F Lube (485GB3191B)..... <b>[2] B76 +</b> P. Fuel (483GB444)..... <b>BF877 +</b> S. Fuel (483GB441)..... <b>BF876</b> Air (81SD44)..... <b>PA2677</b> Coolant (25MF435)..... <b>BW5178</b>	Pinnacle w/MP8 (12.8L) Eng. (2018) F-F Lube (21707136)..... <b>[2] B76</b> B-P Lube (21707135)..... <b>B7409</b> <b>Fuel/Water Separator</b> (22094987)..... <b>BF46182-O</b> Fuel (22094967)..... <b>BF46117</b> Radial Seal Air (25100042)..... <b>RS4634</b> Radial Seal XP Air (25100042).... <b>RS4634XP</b> Cab Air (3543H9638)..... <b>PA30277</b> Trans. (22038908)..... <b>PT9417</b> <b>Diesel Exhaust Fluid</b> (82269261) <b>PE17001</b>	Qantum w/Cummins ISX Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154 +</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> Fuel (Fleetguard FF2200)..... <b>BF7766</b>
MS300P Mid-Liner w/Renault MIDS06.20.30 (8.8L) Eng. Lube (485GB3191)..... <b>B76 +</b> <b>Severe Service F-F Lube</b> (485GB3191)..... <b>B76-SS +</b> P. Fuel (483GB444)..... <b>BF877 +</b> S. Fuel (483GB441)..... <b>BF876</b> Conical Air (57MD27)..... <b>PA2540 +</b> Conical Air (w/Lid) (2191P138427)..... <b>PA2677</b>	Pinnacle w/MP8 (12.8L) Eng. (2019) F-F Lube (21707136)..... <b>[2] B76 +</b> B-P Lube (21707135)..... <b>B7409</b> <b>Severe Service F-F Lube</b> (21707136)..... <b>[2] B76-SS +</b> <b>Fuel/Water Separator</b> (Fleetguard FS19765G)..... <b>PF46094</b>	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



MACK Trucks (cont'd)	MACK Trucks (cont'd)	MACK Trucks (cont'd)
Quantum w/Cummins ISX Eng. (Cont'd) <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2<sup>+</sup></b>	R w/ETAZ673 (11.0L) Eng. <b>Lube</b> ..... [2] <b>B76<sup>+</sup></b> <b>Severe Service F-F Lube</b> ..... [2] <b>B76-SS<sup>+</sup></b> <b>Fuel/Water Separator</b> (483GB433B)..... <b>BF1219<sup>+</sup></b> <b>P. Fuel</b> ..... <b>BF877<sup>+</sup></b> <b>S. Fuel</b> ..... <b>BF876</b> <b>Air</b> (Don. P130774)..... <b>PA2439</b> <b>Air</b> (Don. P130775)..... <b>PA2438</b> <b>Coolant</b> ..... <b>BW5178</b> <b>Std. Service Kit</b> ..... <b>BK6700</b>	RB w/EM7 (11.9L) Eng. (Cont'd) <b>Coolant</b> (25MF435B)..... <b>BW5178</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2<sup>+</sup></b> <b>Steering</b> (Nelson 84148A)..... <b>P528</b> <b>Service Kit</b> (215SB325A)..... <b>BK6693</b>
Quantum w/EAT7-370 CCRS Eng. <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2<sup>+</sup></b>	R65 w/300 Maxidyne Eng. <b>Lube</b> ..... <b>B76<sup>+</sup></b> <b>P. Fuel</b> ..... <b>BF877<sup>+</sup></b> <b>S. Fuel</b> ..... <b>BF876</b>	RB w/EM7-L (11.9L) Eng. <b>F-F Lube</b> (485GB3236)..... [2] <b>B7225<sup>+</sup></b> <b>B-P Lube Spinner</b> (57GC2231)... <b>BC7242</b> <b>Opt. Fuel/Water Separator Ele.</b> (301SD19B)..... <b>PF7680</b> <b>Opt. Fuel/Water Separator</b> <b>Spin-on</b> (483GB477M)..... <b>BF1286</b> <b>P. Fuel</b> (483GB470M)..... <b>BF7656</b> <b>S. Fuel</b> (483GB471M)..... <b>BF7657</b> <b>Radial Seal Air</b> (57MD317)..... <b>RS4618</b> <b>Coolant</b> (25MF435B)..... <b>BW5178</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2<sup>+</sup></b> <b>Steering</b> (Nelson 84148A)..... <b>P528</b> <b>Service Kit</b> (215SB325A)..... <b>BK6693</b>
R w/Cat 3208 (10.4L) Eng. <b>Lube</b> (9N5570)..... [2] <b>BT230<sup>+</sup></b> <b>Lube</b> (9L9200)..... [2] <b>BT364</b> <b>Box-Style Fuel/Water Separator.</b> <b>BF912</b> <b>Fuel Spin-on</b> ..... <b>BF970<sup>+</sup></b> <b>Air</b> (2MD3129)..... <b>PA2312</b> <b>Air</b> (2MD4003)..... <b>PA2482</b> <b>Air</b> (2MD491)..... <b>PA2465</b>	RB w/E6 (11.0L) Eng. <b>Fuel/Water Separator</b> (483GB433B)..... <b>BF1219<sup>+</sup></b>	RB600 w/E5-250 Eng. <b>Lube</b> (485GB3191B)..... [2] <b>B76<sup>+</sup></b> <b>P. Fuel</b> (483GB444)..... <b>BF877<sup>+</sup></b> <b>S. Fuel</b> (483GB441)..... <b>BF876</b> <b>Coolant</b> (25MF436B)..... <b>BW5179</b>
R w/Cat 3406 (14.6L) Eng. <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99<sup>+</sup></b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299<sup>+</sup></b> <b>Fuel/Water Separator Spin-on</b> (2568753)..... <b>BF1259</b> <b>P. Fuel Ele.</b> (9M2341)..... [2] <b>PF935</b> <b>Fuel Spin-on</b> (1R0749)..... <b>BF7587<sup>+</sup></b> <b>Fuel Spin-on</b> (1R0712)..... <b>BF614<sup>+</sup></b>	RB w/EM6-L (11.0L) Eng. <b>Fuel/Water Separator</b> (483GB433B)..... <b>BF1219<sup>+</sup></b>	RB688SX w/AI, AMI Aset Eng. <b>F-F Lube</b> (485GB3236)..... [2] <b>B7225<sup>+</sup></b> <b>B-P Lube Spinner</b> (To 11/11/03) (57GC2206)..... <b>BC7228</b> <b>B-P Lube Spinner</b> (11/11/03-on) (57GC2231)..... <b>BC7242</b> <b>Opt. Fuel/Water Separator Ele.</b> (301SD19B)..... <b>PF7680</b> <b>Opt. Fuel/Water Separator</b> <b>Spin-on</b> (483GB472M)..... <b>BF1256</b> <b>Opt. Fuel/Water Separator</b> <b>Spin-on</b> (483GB477M)..... <b>BF1286</b> <b>P. Fuel</b> (483GB470M)..... <b>BF7656</b> <b>S. Fuel</b> (483GB471M)..... <b>BF7657</b> <b>Radial Seal Air</b> (57MD317)..... <b>RS4618</b> <b>Crankcase Breather</b> ..... <b>CLN&amp;R</b> <b>Coolant</b> (25MF435B)..... <b>BW5178</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2<sup>+</sup></b> <b>Service Kit</b> ..... <b>BK6658<sup>90</sup></b> <b>Service Kit</b> (215SB330)..... <b>BK6662</b> <b>Service Kit</b> (215SB325A)..... <b>BK6693</b>
R w/Cummins N14 (14.0L) Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103<sup>+</sup></b> <b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196<sup>+</sup></b> <b>B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Opt. Fuel/Water Separator</b> (3308638)..... <b>BF1212<sup>+</sup></b> <b>Fuel</b> (154789)..... <b>BF957-D<sup>+</sup></b> <b>Coolant</b> (4 Units BTA PLUS) (3315116)..... <b>BW5071</b>	RB w/E7 (11.9L) Eng. (1990-2003) <b>F-F Lube</b> (485GB3191B)..... [2] <b>B76<sup>+</sup></b> <b>B-P Lube Spinner</b> (57GC2134A). <b>BC110</b> <b>B-P Lube Spinner</b> (57GC2187)... <b>BC7173</b> <b>B-P Lube Spinner</b> (57GC2231)... <b>BC7242</b> <b>Severe Service F-F Lube</b> (485GB3191B)..... [2] <b>B76-SS<sup>+</sup></b> <b>Opt. Fuel/Water Separator</b> <b>Spin-on</b> (483GB472M)..... <b>BF1256</b> <b>P. Fuel</b> (483GB470M)..... <b>BF7656</b> <b>S. Fuel</b> (483GB471M)..... <b>BF7657</b> <b>Radial Seal Air</b> (57MD317)..... <b>RS4618</b> <b>Coolant</b> (25MF435B)..... <b>BW5178</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2<sup>+</sup></b>	RB w/E7 (11.9L) Eng. (2004-05) <b>F-F Lube</b> (485GB3236)..... [2] <b>B7225<sup>+</sup></b> <b>B-P Lube Spinner</b> (57GC2134A). <b>BC110</b> <b>B-P Lube Spinner</b> (57GC2187)... <b>BC7173</b> <b>B-P Lube Spinner</b> (57GC2231)... <b>BC7242</b> <b>Opt. Fuel/Water Separator</b> <b>Spin-on</b> (483GB472M)..... <b>BF1256</b> <b>P. Fuel</b> (483GB470M)..... <b>BF7656</b> <b>S. Fuel</b> (483GB471M)..... <b>BF7657</b> <b>Radial Seal Air</b> (57MD317)..... <b>RS4618</b> <b>Coolant</b> (25MF435B)..... <b>BW5178</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2<sup>+</sup></b> <b>Service Kit</b> (215SB325A)..... <b>BK6693</b>
R w/Detroit Diesel 6V-92N (9.0L) Eng. <b>F-F Lube Ele.</b> ..... <b>P20-HD<sup>+</sup></b> <b>F-F Lube Spin-on</b> ..... <b>B95<sup>+</sup></b> <b>P. Fuel Spin-on</b> ..... <b>BF5800<sup>+</sup></b> <b>S. Fuel Spin-on</b> ..... <b>BF5810</b>	RB w/E7 (11.9L) Eng. (2004-05) <b>F-F Lube</b> (485GB3236)..... [2] <b>B7225<sup>+</sup></b> <b>B-P Lube Spinner</b> (57GC2134A). <b>BC110</b> <b>B-P Lube Spinner</b> (57GC2187)... <b>BC7173</b> <b>B-P Lube Spinner</b> (57GC2231)... <b>BC7242</b> <b>Opt. Fuel/Water Separator</b> <b>Spin-on</b> (483GB472M)..... <b>BF1256</b> <b>P. Fuel</b> (483GB470M)..... <b>BF7656</b> <b>S. Fuel</b> (483GB471M)..... <b>BF7657</b> <b>Radial Seal Air</b> (57MD317)..... <b>RS4618</b> <b>Coolant</b> (25MF435B)..... <b>BW5178</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2<sup>+</sup></b> <b>Service Kit</b> (215SB325A)..... <b>BK6693</b>	RB690S w/AI, AMI Aset Eng. <b>F-F Lube</b> (485GB3236)..... [2] <b>B7225<sup>+</sup></b> <b>B-P Lube Spinner</b> (To 11/11/03) (57GC2206)..... <b>BC7228</b> <b>B-P Lube Spinner</b> (11/11/03-on) (57GC2231)..... <b>BC7242</b> <b>Opt. Fuel/Water Separator Ele.</b> (301SD19B)..... <b>PF7680</b> <b>Opt. Fuel/Water Separator</b> <b>Spin-on</b> (483GB472M)..... <b>BF1256</b> <b>Opt. Fuel/Water Separator</b> <b>Spin-on</b> (483GB477M)..... <b>BF1286</b> <b>P. Fuel</b> (483GB470M)..... <b>BF7656</b> <b>S. Fuel</b> (483GB471M)..... <b>BF7657</b>
R w/E4 (7.8L) Eng. <b>Lube</b> ..... <b>B163</b> <b>P. Fuel</b> ..... <b>BF877<sup>+</sup></b> <b>S. Fuel</b> ..... <b>BF876</b>	RB w/EM7 (11.9L) Eng. <b>F-F Lube</b> (485GB3236)..... [2] <b>B7225<sup>+</sup></b> <b>B-P Lube Spinner</b> (57GC2231)... <b>BC7242</b> <b>Opt. Fuel/Water Separator Ele.</b> (301SD19B)..... <b>PF7680</b> <b>Opt. Fuel/Water Separator</b> <b>Spin-on</b> (483GB477M)..... <b>BF1286</b> <b>P. Fuel</b> (483GB470M)..... <b>BF7656</b> <b>S. Fuel</b> (483GB471M)..... <b>BF7657</b> <b>Radial Seal Air</b> (57MD317)..... <b>RS4618</b>	
R w/E6 (11.0L) Eng. <b>Fuel/Water Separator</b> (483GB433B)..... <b>BF1219<sup>+</sup></b>	RB w/EM7 (11.9L) Eng. <b>F-F Lube</b> (485GB3236)..... [2] <b>B7225<sup>+</sup></b> <b>B-P Lube Spinner</b> (57GC2231)... <b>BC7242</b> <b>Opt. Fuel/Water Separator Ele.</b> (301SD19B)..... <b>PF7680</b> <b>Opt. Fuel/Water Separator</b> <b>Spin-on</b> (483GB477M)..... <b>BF1286</b> <b>P. Fuel</b> (483GB470M)..... <b>BF7656</b> <b>S. Fuel</b> (483GB471M)..... <b>BF7657</b> <b>Radial Seal Air</b> (57MD317)..... <b>RS4618</b>	
R w/E7 (11.9L) Eng. <b>F-F Lube</b> (485GB3232)..... [2] <b>B7225<sup>+</sup></b> <b>B-P Lube Spinner</b> (57GC2206)... <b>BC7228</b> <b>Fuel/Water Separator</b> (483GB433B)..... <b>BF1219<sup>+</sup></b> <b>Fuel</b> (483GB476M)..... <b>BF7773</b>		
R w/EM6-L (11.0L) Eng. <b>ESI-Plus Service Kit</b> (6 Spin-ons) <b>BK6710</b> <b>Service Kit</b> (5 Spin-ons + B-P Spinner)..... <b>BK6720</b>		

<sup>+</sup> See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.


Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>MACK Trucks (cont'd)</b>	<b>MACK Trucks (cont'd)</b>	<b>MACK Trucks (cont'd)</b>
RB690S w/AI, AMI Aset Engs. (Cont'd)	RD w/AMI-300 (11.9L) Eng. (To 11/11/2003) (Cont'd)	RD w/E7 (11.9L) Eng. (1990-2003) (Cont'd)
Radial Seal Air (57MD317)..... RS4618	Opt. Trans. Spin-on (Fuller 17237)..... B2 +	Opt. Trans. Spin-on (Fuller 17237)..... B2 +
Crankcase Breather..... CLN&R	Steering (5839-LF637)..... P528	2 25/32 In. Steering (5839-84365A)..... PT951 +
Coolant (25MF435B)..... BW5178	RD w/AMI-300 (11.9L) Eng. (11/11/2003-on)	4 3/16 In. Steering (5839-84148A)..... P528
Opt. Trans. (Fuller 17237)..... B2 +	F-F Lube (485GB3236)..... [2] B7225 +	Service Kit (57GC2177)..... BK6704
Service Kit..... BK6658 <sup>90</sup>	B-P Lube Spinner (57GC2231).... BC7242	RD w/E7 (11.9L) Eng. (2004)
Service Kit (215SB325A)..... BK6693	Opt. Fuel/Water Separator (483GB472M)..... BF1256	F-F Lube (485GB3236)..... [2] B7225 +
RD w/Cat 3208 (10.4L) Eng.	Opt. Fuel/Water Separator (483GB477M)..... BF1286	B-P Lube Spinner (57GC2134A).... BC110
Lube (9N5570)..... [2] BT230 +	P. Fuel (483GB470AM)..... BF7656	B-P Lube Spinner (57GC2187).... BC7173
Lube (9L9200)..... [2] BT364	S. Fuel (483GB372M)..... CLN&R	B-P Lube Spinner (57GC2231).... BC7242
Box-Style Fuel/Water Separator. BF912	S. Fuel (483GB471M)..... BF7657	Opt. Fuel/Water Separator Ele. (301SD19B)..... PF7680
Fuel Spin-on..... BF970 +	S. Fuel (483GB476M)..... BF7773	Opt. Fuel/Water Separator Spin-on (483GB472M)..... BF1256
Air (2MD3129)..... PA2312	Radial Seal Air (57MD317)..... RS4618	P. Fuel (483GB470AM)..... BF7656
Air (2MD4003)..... PA2482	Crankcase Breather..... CLN&R	S. Fuel (483GB471M)..... BF7657
Air (2MD491)..... PA2465	Coolant (25MF435B)..... BW5178	11 3/8 In. O.D. Radial Seal Air (57MD317)..... RS4618
RD w/Cat 3406 (14.6L) Eng.	Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	13 3/32 In. O.D. Radial Seal Air (57MD318)..... RS4613
F-F Lube (Std. Version) (1R0716)..... B99 +	Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Coolant (25MF435B)..... BW5178
F-F Lube (High Efficiency Vers.) (1R1808)..... B7299 +	Opt. Trans. Spin-on (Fuller 17237)..... B2 +	Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT
Fuel/Water Separator Spin-on (2568753)..... BF1259	Steering (5839-LF637)..... P528	Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT
P. Fuel Ele. (9M2341)..... [2] PF935	Service Kit (215SB332)..... BK6665	Opt. Trans. Spin-on (Fuller 17237)..... B2 +
Fuel Spin-on (1R0749)..... BF7587 +	Service Kit (215SB325A)..... BK6693	2 25/32 In. Steering (5839-84365A)..... PT951 +
Fuel Spin-on (1R0712)..... BF614 +	RD w/E6 (11.0L) Eng.	4 3/16 In. Steering (5839-84148A)..... P528
RD w/Cummins N14 (14.0L) Eng.	Lube (485GB3191C)..... [2] B76 +	Service Kit (215SB325A)..... BK6693
Dual-Flow Lube (3318853)..... BD103 +	Severe Service F-F Lube (485GB3191C)..... [2] B76-SS +	RD w/EM6-L (11.0L) Eng.
F-F Lube (Fleetguard LF670SC).. B196 +	P. Fuel (483GB444)..... BF877 +	ESI-Plus Service Kit (6 Spin-ons) BK6710
B-P Lube (1W8845)..... B7577	S. Fuel (483GB441)..... BF876	Service Kit (5 Spin-ons + B-P Spinner)..... BK6720
Opt. Fuel/Water Separator (3308638)..... BF1212 +	Air (57MD26)..... PA2312	RD w/EM7 (11.9L) Eng.
Fuel (154789)..... BF957-D +	Coolant (25MF435B)..... BW5178	F-F Lube (482GB3191)..... [2] B76 +
Coolant (4 Units BTA PLUS) (3315116)..... BW5071	RD w/E7 (11.9L) Eng. (1990-2003)	B-P Lube (236GB244)..... BC110
RD w/Detroit Diesel 6V-92N (9.0L) Eng.	F-F Lube (485GB3191B)..... [2] B76 +	Severe Service F-F Lube (482GB3191)..... [2] B76-SS +
F-F Lube Ele..... P20-HD +	B-P Lube Spinner (57GC2134A).... BC110	P. Fuel (483GB444)..... BF877 +
F-F Lube Spin-on..... B95 +	B-P Lube Spinner (57GC2187).... BC7173	S. Fuel (483GB431)..... BF976
P. Fuel Spin-on..... BF5800 +	B-P Lube Spinner (57GC2231).... BC7242	S. Fuel (483GB441)..... BF876
S. Fuel Spin-on..... BF5810	Severe Service F-F Lube (485GB3191B)..... [2] B76-SS +	Air (57MD26)..... PA2312
RD w/AMI-300 (11.9L) Eng. (To 11/11/2003)	Opt. Fuel/Water Separator Ele. (301SD19B)..... PF7680	Coolant (25MF428A)..... BW5178
F-F Lube (485GB3236)..... [2] B7225 +	Opt. Fuel/Water Separator (483GB477M)..... BF1286	Service Kit (57GC120B)..... BK6723
B-P Lube Spinner (57GC2206).... BC7228	Spin-on (483GB472M)..... BF1256	RD w/ETAZ673 (11.0L) Eng.
Opt. Fuel/Water Separator (483GB472M)..... BF1256	P. Fuel (483GB470AM)..... BF7656	Lube..... [2] B76 +
Opt. Fuel/Water Separator (483GB477M)..... BF1286	S. Fuel (483GB471M)..... BF7657	Severe Service F-F Lube..... [2] B76-SS +
P. Fuel (483GB470AM)..... BF7656	11 3/8 In. O.D. Radial Seal Air (57MD317)..... RS4618	Fuel/Water Separator (483GB433B)..... BF1219 +
P. Fuel (483GB372M)..... CLN&R	13 3/32 In. O.D. Radial Seal Air (57MD318)..... RS4613	P. Fuel..... BF877 +
S. Fuel (483GB471M)..... BF7657	Coolant (25MF435B)..... BW5178	S. Fuel..... BF876
S. Fuel (483GB476M)..... BF7773	Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	Air (Don. P130774)..... PA2439
Radial Seal Air (57MD317)..... RS4618	Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Air (Don. P130775)..... PA2438
Crankcase Breather..... CLN&R		
Coolant (25MF435B)..... BW5178		
Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT		
Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT		

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MACK Trucks (cont'd)	MACK Trucks (cont'd)	MACK Trucks (cont'd)
RD w/ETAZ673 (11.0L) Eng. (Cont'd)	RL w/ETAZ673 (11.0L) Eng. (Cont'd)	RM w/E7 (11.9L) Eng. (Cont'd)
Coolant..... BW5178	P. Fuel..... BF877 +	Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT
ESI-Plus Service Kit (57GC295A)..... BK6710	S. Fuel..... BF876	Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT
Std. Service Kit (57GC294)..... BK6700	Coolant..... BW5178	Trans. (Fuller 4304827)..... BT223
RD600 w/E5-250 Eng.	Std. Service Kit..... BK6700	Opt. Trans. (Fuller 17237)..... B2 +
F-F Lube (485GB3191B)..... [2] B76 +	RL400, RS400 Series w/Cat 1150, 1160 Engs.	RM w/EM6 (11.0L) Eng.
P. Fuel (483GB444)..... BF877 +	Lube..... [2] BT364	Fuel/Water Separator (483GB433B)..... BF1219 +
S. Fuel (483GB441)..... BF876	Fuel..... BF583	Air (57MD42M)..... PA2680
Air (57MD33)..... PA2317 +	RL400, RS400 Series w/Cummins Eng.	RM w/EM6-L (11.0L) Eng.
Coolant (25MF436B)..... BW5179	F-F Lube Spin-on..... B196 +	Fuel/Water Separator (483GB433B)..... BF1219 +
Steering (583984148A)..... P528	B-P Lube Ele..... C750-E +	Air (57MD42M)..... PA2680
RD688S w/ASET AI Series Eng.	Fuel/Water Separator..... BF1212 +	RM w/EM7 (11.9L) Eng.
F-F Lube (485GB3236)..... [2] B7225 +	5 3/4 In. Fuel Spin-on..... BF957 +	Fuel/Water Separator (483GB433B)..... BF1219 +
B-P Lube Spinner (To 11/11/03) (57GC2206)..... BC7228	11 7/32 In. Fuel Spin-on..... BF596 +	RM4004, DMM4006, RM4006 Series w/ENDT475 Eng.
B-P Lube Spinner (11/11/03-on) (57GC2231)..... BC7242	Breather Ele. (w/Turbo) (255963) PA643	P. Fuel Spin-on..... BF877 +
Opt. Fuel/Water Separator Ele. (301SD19B)..... PF7680	Breather Ele. (w/o Turbo) (256837)..... PA1627	S. Fuel Spin-on..... BF876
Opt. Fuel/Water Separator Spin-on (483GB472M)..... BF1256	RL400, RS400 Series w/GMC 6V-53 Eng.	Coolant Spin-on..... BW5178
Opt. Fuel/Water Separator Spin-on (483GB477M)..... BF1286	F-F Lube Ele..... P20-HD +	Turbocharger (6432PER17)..... B163
P. Fuel (483GB470M)..... BF7656	B-P Lube Ele..... P52	RM6004, DMM6006, RM6006, HMM6856, F8006, F9006 Series w/END673E, ENDT673, ENDT673C, ENDT675, ENDT676, Std. Service Kit (1972-on, (5 Spin-ons))..... BK6700
S. Fuel (483GB471M)..... BF7657	P. Fuel Sock..... F916-C	ESI-Plus Service Kit (1977-on, (6 Spin-ons))..... BK6710
11 3/8 In. O.D. Radial Seal Air (57MD317)..... RS4618	S. Fuel Ele..... PF906	RS w/Cummins N14 (14.0L) Eng.
13 3/32 In. O.D. Radial Seal Air (57MD318)..... RS4613	RL600, RS600 Series w/Cummins V903 Eng.	Dual-Flow Lube (3318853)..... BD103 +
Crankcase Breather..... CLN&R	F-F Lube Ele..... P999-HD	F-F Lube (Fleetguard LF670SC)..... B196 +
Coolant (25MF435B)..... BW5178	F-F Lube Spin-on..... B196 +	B-P Lube (1W8845)..... B7577
Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	B-P Lube Ele..... C750-E +	Opt. Fuel/Water Separator (3308638)..... BF1212 +
Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Fuel Spin-on..... BF957 +	Fuel (154789)..... BF957-D +
Opt. Trans. Spin-on (Fuller 17237)..... B2 +	Coolant Spin-on..... BW5071	Coolant (4 Units BTA PLUS) (3315116)..... BW5071
2 25/32 In. Steering (5839-84365A)..... PT951 +	RL600, RS600 Series w/GMC 6V-71N, 8V-71N Engs.	RS w/Detroit Diesel 6V-92N (9.0L) Eng.
4 3/16 In. Steering (Fleetguard LF637)..... P528	F-F Lube Ele..... P20-HD +	F-F Lube Ele..... P20-HD +
Service Kit..... BK6658 <sup>90</sup>	B-P Lube Ele..... P52	F-F Lube Spin-on..... B95 +
Service Kit (215SB325A)..... BK6693	P. Fuel Spin-on..... BF5800 +	P. Fuel Spin-on..... BF5800 +
RD800 w/AI-350 Eng.	S. Fuel Spin-on..... BF5810	S. Fuel Spin-on..... BF5810
F-F Lube (485GB3236)..... [2] B7225 +	5 3/4 In. P. Fuel Sock..... F916-C	RS w/EM6-L (11.0L) Eng.
B-P Lube Spinner (57GC2231)..... BC7242	9 In. P. Fuel Sock..... F844-A	ESI-Plus Service Kit (6 Spin-ons) BK6710
P. Fuel (483GB470M)..... BF7656	8 5/16 In. P. Fuel Ele..... PF845	Service Kit (5 Spin-ons + B-P Spinner)..... BK6720
S. Fuel (483GB471M)..... BF7657	7 13/16 In. S. Fuel Ele..... PF902	RS w/ETAZ673 (11.0L) Eng.
RL w/E6 (11.0L) Eng.	8 1/4 In. S. Fuel Ele..... PF846	Lube..... [2] B76 +
ESI-Plus Service Kit (6 Spin-ons) BK6710	RL600, RS600, U600 Series w/GMC 6V-92 Eng.	Severe Service F-F Lube..... [2] B76-SS +
Service Kit (5 Spin-ons + B-P Spinner)..... BK6720	F-F Lube Ele..... P20-HD +	Fuel/Water Separator (483GB433B)..... BF1219 +
RL w/ETAZ673 (11.0L) Eng.	F-F Lube Spin-on..... B95 +	P. Fuel..... BF877 +
Lube..... [2] B76 +	P. Fuel Spin-on..... BF5800 +	S. Fuel..... BF876
Severe Service F-F Lube..... [2] B76-SS +	RL700, RS700, RSW700, WL700 w/Cat 3406 Eng.	Coolant..... BW5178
Fuel/Water Separator (483GB433B)..... BF1219 +	Lube Spin-on..... B99 +	
	Fuel Spin-on..... BF614 +	
	Coolant Spin-on..... BW5137	
	RM w/E6 (11.0L) Eng.	
	Fuel/Water Separator (483GB433B)..... BF1219 +	
	RM w/E7 (11.9L) Eng.	
	F-F Lube (485GB3232)..... [2] B7225 +	
	B-P Lube Spinner (57GC2206)..... BC7228	
	Fuel/Water Separator (483GB433B)..... BF1219 +	
	Fuel (483GB476M)..... BF7773	

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.

Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MACK Trucks (cont'd)	MACK Trucks (cont'd)	MACK Trucks (cont'd)
RS w/ETAZ673 (11.0L) Eng. (Cont'd) Std. Service Kit (57GC294)..... BK6700	RWL w/Cummins N14 (14.0L) Eng. (Cont'd) 4 3/8 In. Fuel Spin-on..... BF948 + 5 3/4 In. Fuel Spin-on..... BF957 + 11 7/32 In. Fuel Spin-on..... BF596 + Breather Ele. (w/Turbo) (255963) PA643 Breather Ele. (w/o Turbo) (256837)..... PA1627 Coolant Spin-on..... BW5071 Turbocharger..... BT112 +	RWS w/ET673, ENDT675, ENDT676 Engs. ESI-Plus Service Kit (1977-on, (6 Spin-ons))..... BK6710
RW w/Cat 3406 (14.6L) Eng. Lube..... B99 + Fuel Spin-on..... BF614 + Opt. Air (57MD44M)..... PA2755 Coolant..... BW5137	RWL w/E6 (11.0L) Eng. Fuel/Water Separator (483GB433B)..... BF1219 +	RWS w/ETAZ673 (11.0L) Eng. Std. Service Kit (215SB192A)..... BK6700
RW w/Cummins N14 (14.0L) Eng. F-F Lube Spin-on..... B196 + B-P Lube Spin-on..... B7577 Fuel Spin-on..... BF957-D +	RWL w/E9 (16.4L) Eng. Lube..... [2] B76 + Severe Service F-F Lube..... [2] B76-SS + Fuel/Water Separator (483GB433B)..... BF1219 + P. Fuel..... BF877 + S. Fuel..... BF976 Air (57MD42M)..... PA2680 Opt. Air (57MD44M)..... PA2755 Coolant..... BW5179	Super-Liner w/Cat 3406 Eng. Lube..... B99 + Fuel Spin-on..... BF614 + Coolant Spin-on..... BW5137
RW w/E6 (11.0L) Eng. F-F Lube..... [2] B76 + B-P Lube..... BC110 Severe Service F-F Lube..... [2] B76-SS + Fuel/Water Separator (483GB433B)..... BF1219 + P. Fuel..... BF877 + S. Fuel..... BF976 Air (57MD42M)..... PA2680 Opt. Air (57MD44M)..... PA2755 Coolant..... BW5179	RWL w/ET673, ENDT675, ENDT676 Engs. ESI-Plus Service Kit (1977-on, (6 Spin-ons))..... BK6710	Super-Liner w/Cat C15 Eng. Lube (To 1/2004) (1R0716)..... B99 + Lube (1/2004-on) (1R1808)..... B7299 + Opt. Trans. (Fuller 17237)..... B2 +
RW w/E7 (11.9L) Eng. F-F Lube (485GB3232)..... [2] B7225 + B-P Lube Spinner (57GC2206)..... BC7228 Fuel/Water Separator (483GB433B)..... BF1219 + Fuel (483GB476M)..... BF7773 Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT Trans. (Fuller 4304827)..... BT223 Opt. Trans. (Fuller 17237)..... B2 +	RWL w/ETAZ673 (11.0L) Eng. Std. Service Kit (215SB192A)..... BK6700	Super-Liner w/Cummins Eng. F-F Lube Ele..... P999-HD Lube Spin-on..... B196 + B-P Lube Ele..... C750-E + Fuel Spin-on..... BF957 + Coolant Spin-on..... BW5071
RW w/E9 (16.4L) Eng. Fuel/Water Separator (483GB433B)..... BF1219 +	RWS w/Cummins N14 (14.0L) Eng. F-F Lube Bag..... P996 F-F Lube Ele..... P999-HD F-F Lube Spin-on..... B196 + B-P Lube Ele..... C750-E + B-P Lube Spin-on..... B7577 Fuel/Water Separator..... BF1212 + 4 3/8 In. Fuel Spin-on..... BF948 + 5 3/4 In. Fuel Spin-on..... BF957 + 11 7/32 In. Fuel Spin-on..... BF596 + Breather Ele. (w/Turbo) (255963) PA643 Breather Ele. (w/o Turbo) (256837)..... PA1627 Coolant Spin-on..... BW5071 Turbocharger..... BT112 +	Super-Liner w/GMC 8V-92 Eng. F-F Lube Ele..... P20-HD + P. Fuel Spin-on..... BF5800 + S. Fuel Spin-on..... BF5810
RW w/EM6 (11.0L) Eng. Opt. Air (57MD44M)..... PA2755 ESI-Plus Service Kit (6 Spin-ons) BK6710 Service Kit (5 Spin-ons + B-P Spinner)..... BK6720	RWS w/E6 (11.0L) Eng. Fuel/Water Separator (483GB433B)..... BF1219 +	Super-Liner w/Maxidyne 300 Eng. Lube Spin-on..... B76 + P. Fuel Spin-on..... BF877 + S. Fuel Spin-on..... BF876 Coolant Spin-on..... BW5179
RW702, RW703 w/Detroit Diesel Eng. F-F Lube..... B95 + P. Fuel..... BF5800 + S. Fuel..... BF5810	RWS w/E9 (16.4L) Eng. Lube..... [2] B76 + Severe Service F-F Lube..... [2] B76-SS + Fuel/Water Separator..... BF1219 + P. Fuel..... BF877 + S. Fuel..... BF876 Coolant..... BW5178 Std. Service Kit (5 Spin-ons)..... BK6700	Super-Liner w/ET673 Eng. ESI-Plus Service Kit (1977-on, (6 Spin-ons))..... BK6710
RWL w/Cat 3406 (14.6L) Eng. Lube Spin-on..... B99 + Fuel Spin-on..... BF614 + Coolant Spin-on..... BW5137	RWS w/E6 (11.0L) Eng. Fuel/Water Separator (483GB433B)..... BF1219 +	Super-Liner, Super-Liner LT w/Cummins ISX Eng. Dual-Flow Lube (Fleetguard LF9001)..... BD7154 + Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... BD50000 Coolant (Fleetguard WF2126)..... BW5086 Opt. Trans. (Fuller 17237)..... B2 +
RWL w/Cummins N14 (14.0L) Eng. F-F Lube Bag..... P996 F-F Lube Ele..... P999-HD F-F Lube Spin-on..... B196 + B-P Lube Ele..... C750-E + B-P Lube Spin-on..... B7577 Fuel/Water Separator..... BF1212 +	RWS w/ENDT865, ENDT866 Engs. Std. Service Kit (1972-on, (5 Spin-ons))..... BK6700	Super-Liner LT w/Cummins Signature 550 Eng. Opt. Trans. (Fuller 17237)..... B2 +

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MACK Trucks (cont'd)	MACK Trucks (cont'd)	MACK Trucks (cont'd)
TD700 Titan w/MP10 (16.1L) Eng. (2010-11) (Cont'd)	TD713 w/MP10 Eng.	Terrapro w/Cummins ISL-G (8.9L) Eng. (2019)
<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>F-F Lube</b> (21707136)..... <b>[2] B76 +</b>	<b>Lube</b> (Fleetguard LF9009)..... <b>B40142</b>
<b>Air Dryer</b> (System Saver 1200) (Wabco R950068)..... <b>BA5379 +</b>	<b>B-P Lube</b> (21707135)..... <b>B7409</b>	<b>Fuel/Water Separator</b> (Fleetguard NG5900)..... <b>BF7695</b>
<b>Coolant</b> (w/o Chemical) (21937298)..... <b>B5091</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19765)..... <b>PF7930</b>	<b>Radial Seal Air</b> (21328870)..... <b>RS3744</b>
<b>Coolant</b> (w/Chemical) (20539991)..... <b>BW5183</b>	<b>Fuel/Water Separator Ele.</b> (301SD19D)..... <b>PF7680</b>	<b>Radial Seal O. Air</b> (21328870)..... <b>RS3744XP</b>
<b>Steering</b> (Nelson 870678A)..... <b>PT9394-MPG</b>	<b>Fuel/Water Separator Spin-on</b> (21017305)..... <b>BF1386-O</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
TD700 Titan w/MP10 (16.1L) Eng. (2012-17)	<b>Fuel</b> (20972295)..... <b>BF7943</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>F-F Lube</b> (21707136)..... <b>[2] B76 +</b>	<b>Cab Air</b> (3543H9638)..... <b>PA30277</b>	<b>Steering</b> (5839870678A)..... <b>PT9394-MPG</b>
<b>B-P Lube</b> (21707135)..... <b>B7409</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	Terrapro w/Cummins ISL-G (8.9L) Eng. (2020)
<b>Severe Service F-F Lube</b> (21707136)..... <b>[2] B76-SS +</b>	<b>Air Dryer</b> (1200P System) (Wabco R950068)..... <b>BA5379 +</b>	<b>Lube</b> (Fleetguard LF9009)..... <b>B40142</b>
<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19728)..... <b>PF7782</b>	<b>Coolant</b> (w/o Chemical) (21937298)..... <b>B5091</b>	<b>Fuel</b> (Fleetguard NG5900)..... <b>BF7695</b>
<b>Fuel/Water Separator Ele.</b> (301SD19C)..... <b>PF7680</b>	<b>Coolant</b> (w/Chemical) (20539991)..... <b>BW5183</b>	<b>Radial Seal Air</b> (21328870)..... <b>RS3744</b>
<b>Fuel/Water Separator Ele.</b> (85120233)..... <b>PF7930</b>	<b>Trans.</b> (Fuller 4304827)..... <b>BT223</b>	<b>Radial Seal XP Air</b> (21328870)..... <b>RS3744XP</b>
<b>Fuel/Water Separator Spin-on</b> (21017305)..... <b>BF1386-O</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Cab Air</b> ..... <b>CLN&amp;R</b>
<b>Fuel</b> (20972295)..... <b>BF7943</b>	<b>Steering</b> (Nelson 870678A)..... <b>PT9394-MPG</b>	<b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>
<b>Air</b> (21292492)..... <b>[2] PA3478</b>	TD714 w/MP10 Eng.	<b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b>
<b>XP Air</b> (21292492)..... <b>[2] PA3478XP</b>	<b>F-F Lube</b> (20539275)..... <b>[2] B76 +</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Cab Air</b> (3543H9638)..... <b>PA30277</b>	<b>B-P Lube</b> (20843764)..... <b>B7409</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b>	<b>Severe Service F-F Lube</b> (20539275)..... <b>[2] B76-SS +</b>	<b>Steering</b> (Nelson 870678A)..... <b>PT9394-MPG</b>
<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Fuel/Water Separator Ele.</b> (301SD19C)..... <b>PF7680</b>	Terrapro w/Cummins ISL-G (8.9L) Eng. (2022)
<b>Air Dryer</b> (System Saver 1200) (Wabco R950068)..... <b>BA5379 +</b>	<b>Fuel/Water Separator Spin-on</b> (21017305)..... <b>BF1386-O</b>	<b>Lube</b> (5444774)..... <b>B40142</b>
<b>Coolant</b> (w/o Chemical) (21937298)..... <b>B5091</b>	<b>Fuel</b> (20972295)..... <b>BF7943</b>	<b>Fuel/Water Separator</b> (3607140)..... <b>BF7695</b>
<b>Coolant</b> (w/Chemical) (20539991)..... <b>BW5183</b>	<b>Cab Air</b> (3543H9638)..... <b>PA30277</b>	Terrapro w/MP7 (10.8L) Eng. (2019)
<b>Trans. Ele.</b> (mDrive) (20779040)..... <b>PT9417</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>F-F Lube</b> (21707136)..... <b>[2] B76 +</b>
<b>Trans. Spin-on</b> (Fuller 4304827)..... <b>BT223</b>	<b>Coolant</b> (w/o Chemical) (20575545)..... <b>B5091</b>	<b>Severe Service F-F Lube</b> (21707136)..... <b>[2] B76-SS +</b>
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Coolant</b> (w/Chemical) (20539991)..... <b>BW5183</b>	<b>B-P Lube</b> (21707135)..... <b>B7409</b>
<b>Steering</b> (Nelson 870678A)..... <b>PT9394-MPG</b>	<b>Steering</b> (Nelson 870678A)..... <b>PT9394-MPG</b>	<b>Fuel/Water Separator</b> (22094987)..... <b>BF46182-O</b>
<b>Diesel Exhaust Fluid</b> (21516231)..... <b>PE17000</b>	Terrapro w/Cummins ISL-G Eng. (2010-11)	<b>Fuel</b> (22094967)..... <b>BF46117</b>
<b>Diesel Exhaust Fluid Strainer</b> (82269261)..... <b>PE17001</b>	<b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b>	<b>Radial Seal Air</b> (21328870)..... <b>RS3744</b>
TD700 Titan w/MP10 (16.1L) Eng. (2018)	<b>Fuel</b> (Fleetguard NG5900)..... <b>BF7695</b>	<b>Radial Seal XP Air</b> (21328870)..... <b>RS3744XP</b>
<b>F-F Lube</b> (21707136)..... <b>[2] B76 +</b>	<b>Air</b> (57MD47)..... <b>PA3938</b>	<b>Coolant</b> (21937331)..... <b>BW5183</b>
<b>B-P Lube</b> (21707135)..... <b>B7409</b>	<b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Severe Service F-F Lube</b> (21707136)..... <b>[2] B76-SS +</b>	<b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Fuel/Water Separator</b> (22094987)..... <b>BF46182-O</b>	<b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b>	<b>Steering</b> (5839870678A)..... <b>PT9394-MPG</b>
<b>Fuel</b> (20972295)..... <b>BF7943</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Diesel Exhaust Fluid</b> (21516231)..... <b>PE17000</b>
<b>Fuel</b> (22094967)..... <b>BF46117</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Terrapro w/MP7 (10.8L) Eng. (2020)
<b>Cab Air</b> (3543H9638)..... <b>PA30277</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>F-F Lube</b> (21707136)..... <b>[2] B76</b>
<b>Coolant</b> (21937298)..... <b>B5091</b>	<b>Steering</b> (5839-870678A)..... <b>PT9394-MPG</b>	<b>B-P Lube</b> (21707135)..... <b>B7409</b>
<b>Trans.</b> (22038908)..... <b>PT9417</b>		<b>Severe Service F-F Lube</b> (21707136)..... <b>[2] B76-SS +</b>
<b>Steering</b> (5839870678A)..... <b>PT9394-MPG</b>		<b>Fuel/Water Separator</b> (22094987)..... <b>BF46182-O</b>
<b>Diesel Exhaust Fluid</b> (21516231)..... <b>PE17000</b>		<b>Fuel</b> (22094967)..... <b>BF46117</b>
		<b>Radial Seal Air</b> (21328870)..... <b>RS3744</b>
		<b>Radial Seal XP Air</b> (21328870)..... <b>RS3744XP</b>
		<b>Cab Air</b> ..... <b>CLN&amp;R</b>
		<b>Coolant</b> (21937331)..... <b>BW5183</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>MACK Trucks (cont'd)</b>	<b>MACK Trucks (cont'd)</b>	<b>MACK Trucks (cont'd)</b>
Terrapro w/MP7 (10.8L) Eng. (2020) (Cont'd) Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Steering (870678A)..... <b>PT9394-MPG</b>	Titan w/Cummins ISX Eng. (Cont'd) <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel</b> (Fleetguard FF2200)..... <b>BF7766</b> <b>Coolant</b> (Fleetguard WF2126)..... <b>BW5086</b>	Value-Liner w/EA7-370 CCRS Eng. <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> WL w/Cummins N14 (14.0L) Eng. <b>F-F Lube Bag</b> ..... <b>P996</b> <b>F-F Lube Ele.</b> ..... <b>P999-HD</b> <b>F-F Lube Spin-on</b> ..... <b>B196 +</b> <b>B-P Lube Ele.</b> ..... <b>C750-E +</b> <b>B-P Lube Spin-on</b> ..... <b>B7577</b> <b>Fuel/Water Separator</b> ..... <b>BF1212 +</b> <b>4 3/8 In. Fuel Spin-on</b> ..... <b>BF948 +</b> <b>5 3/4 In. Fuel Spin-on</b> ..... <b>BF957 +</b> <b>11 7/32 In. Fuel Spin-on</b> ..... <b>BF596 +</b> <b>Breather Ele.</b> (w/Turbo) (255963) <b>PA643</b> <b>Breather Ele.</b> (w/o Turbo) (256837)..... <b>PA1627</b> <b>Coolant Spin-on</b> ..... <b>BW5071</b> <b>Turbocharger</b> ..... <b>BT112 +</b>
Terrapro w/MP7 (10.8L) Eng. (2021) <b>F-F Lube</b> (21707136)..... <b>[2] B76</b> <b>B-P Lube</b> (21707135)..... <b>B7409</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Titan w/Cummins Signature 520, Signature 580, Signature 620 Engs. (Australia) <b>Opt. Trans.</b> (Fuller 4304827)..... <b>BT223</b>	WL w/E9 (16.4L) Eng. <b>Fuel/Water Separator</b> (483GB433B)..... <b>BF1219 +</b>
Terrapro w/MP7 (10.8L) Eng. (2022) Trans. (Fuller 4304827)..... <b>BT223</b>	Trident w/EA7-470 CCRS Eng. <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	WS w/Cat 3208 (10.4L) Eng. <b>Lube</b> (1R0713)..... <b>[2] BT230 +</b> <b>Lube</b> (1R0714)..... <b>[2] B75</b> <b>Lube</b> (9L9200)..... <b>[2] BT364</b> <b>Box-Style Fuel/Water Separator</b> (8N9803)..... <b>BF912</b> <b>P. Fuel Ele.</b> (9M2341)..... <b>PF935</b> <b>P. Fuel Spin-on</b> (1R0740)..... <b>BF970 +</b> <b>S. Fuel Spin-on</b> (1R0750)..... <b>BF7633 +</b>
Terrapro w/MP8 (12.8L) Eng. (2019) <b>F-F Lube</b> (21707136)..... <b>[2] B76 +</b> <b>B-P Lube</b> (21707135)..... <b>B7409</b> <b>Fuel/Water Separator</b> (Fleetguard FS19765G)..... <b>PF46094</b> <b>Fuel/Water Separator</b> (21737481)..... <b>PF7930</b> <b>Fuel</b> (22094967)..... <b>BF46117</b> <b>Radial Seal Air</b> (21328870)..... <b>RS3744</b> <b>Radial Seal O. Air</b> (21328870)..... <b>RS3744XP</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (5839870678A)..... <b>PT9394-MPG</b> <b>Diesel Exhaust Fluid</b> (Fill Neck Strainer) (82269261)..... <b>PE17001</b> <b>Diesel Exhaust Fluid</b> (Pump Ele.) (21516229)..... <b>PE17000</b>	U w/Cummins N14 (14.0L) Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196 +</b> <b>B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Opt. Fuel/Water Separator</b> (3308638)..... <b>BF1212 +</b> <b>Fuel</b> (154789)..... <b>BF957-D +</b> <b>Coolant</b> (4 Units BTA PLUS) (3315116)..... <b>BW5071</b>	WS w/Cat 3406 (14.6L) Eng. <b>Lube Spin-on</b> ..... <b>B99 +</b> <b>Fuel Spin-on</b> ..... <b>BF614 +</b> <b>Coolant Spin-on</b> ..... <b>BW5137</b>
Terrapro w/MP8 (12.8L) Eng. (2020) <b>F-F Lube</b> (21707136)..... <b>[2] B76</b> <b>B-P Lube</b> (21707135)..... <b>B7409</b> <b>Fuel</b> (22094967)..... <b>BF46117</b> <b>Radial Seal Air</b> (21328870)..... <b>RS3744</b> <b>Radial Seal XP Air</b> (21328870)..... <b>RS3744XP</b> <b>Cab Air</b> (CLN&R)..... <b>CLN&amp;R</b> <b>Coolant</b> (w/o Chemicals) (21937298)..... <b>B5091</b> <b>Coolant</b> (w/12 Units BTE) (21937331)..... <b>BW5183</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (Nelson 870678A)..... <b>PT9394-MPG</b>	U w/E6 (11.0L) Eng. <b>Fuel/Water Separator</b> (483GB433B)..... <b>BF1219 +</b>	WS w/EM6 (11.0L) Eng. <b>Fuel/Water Separator</b> (483GB433B)..... <b>BF1219 +</b>
Terrapro w/MP8 (12.8L) Eng. (2021) <b>Lube</b> (23155587)..... <b>[2] B40153</b> <b>Fuel</b> (23856895)..... <b>BF46117</b>	U w/ETAZ673 (11.0L) Eng. <b>Lube</b> ..... <b>[2] B76 +</b> <b>Severe Service F-F Lube</b> ..... <b>[2] B76-SS +</b> <b>Fuel/Water Separator</b> (483GB433B)..... <b>BF1219 +</b> <b>P. Fuel</b> ..... <b>BF877 +</b> <b>S. Fuel</b> ..... <b>BF876</b> <b>Air</b> (Don. P130774)..... <b>PA2439</b> <b>Air</b> (Don. P130775)..... <b>PA2438</b> <b>Coolant</b> ..... <b>BW5178</b> <b>Std. Service Kit</b> ..... <b>BK6700</b>	WS w/EM6 (11.0L) Eng. <b>Fuel/Water Separator</b> (483GB433B)..... <b>BF1219 +</b>
Titan w/Cummins ISX Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9031)..... <b>BD7509 +</b> <b>Dual-Flow Lube</b> (Fleetguard LF9080)..... <b>BD7154 +</b>	U600T w/ENDT676 Eng. <b>Lube</b> ..... <b>[2] B76 +</b> <b>Severe Service F-F Lube</b> ..... <b>[2] B76-SS +</b> <b>Fuel/Water Separator</b> (483GB433B)..... <b>BF1219 +</b> <b>P. Fuel</b> ..... <b>BF877 +</b> <b>S. Fuel</b> ..... <b>BF876</b> <b>Coolant</b> ..... <b>BW5178</b>	WS w/ETAZ673 (11.0L) Eng. <b>Fuel/Water Separator</b> (483GB433B)..... <b>BF1219 +</b>
	U600T, U600ST w/EM6 (11.0L) Eng. <b>ESI-Plus Service Kit</b> (6 Spin-ons) (57GC295A)..... <b>BK6710</b> <b>Service Kit</b> (5 Spin-ons + B-P Spinner) (57GC298)..... <b>BK6720</b>	<b>MADVAC Sweepers</b> CN100 w/Kubota D1105T Eng. <b>Lube</b> (16271-32090)..... <b>B161-S</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

**MADVAC  
Sweepers (cont'd)**

PS300 w/Kubota Z482-E Eng.  
Lube (15853-32430)..... **B7285**

**MARMON MOTORS**

**Trucks**

125PHR w/Cat 3406E Eng.  
Lube..... **B99 +**  
Fuel/Water Separator..... **BF5812**  
Fuel Spin-on..... **BF7587 +**

125PHR w/Cummins N14 Eng.  
Dual-Flow Lube..... **BD103 +**  
Fuel/Water Separator..... **BF1259**

**MARMON-HERRINGTON  
Trucks & Buses**

Models w/Cat 1673 Eng.  
Lube Ele. (S/N 1L1-up)..... **[2] PT670**  
Lube Ele. (S/N 69D1-up,  
76R1-up)..... **PT670**  
Lube Ele. (All Other S/N)..... **PT88-HD**  
Opt. Box-Style Fuel/Water  
Separator..... **BF912**  
Fuel Ele. (9H4729)..... **PF824 +**  
Fuel Spin-on (1R0740)..... **BF970 +**  
11 1/2 In. Air (2S5648)..... **PA645**  
13 1/2 In. Std. Air (4M9334)..... **PA1634 +**  
13 1/2 In. Air (Upgrade  
(4M9334)..... **PA1634XP +**

Models w/Cat 1674 Eng.  
Lube Ele..... **PT670**  
Fuel Spin-on..... **BF970 +**  
12 1/4 In. Air (4L9853)..... **PA1629-S**  
Air Comp. Breather (9L2169)..... **PA1704**

Models w/Cat 1693T, 1693TA Engs.  
Lube Ele..... **[2] PT88-HD**  
Lube Spin-on..... **B99 +**  
Fuel Ele..... **PF823-E +**  
Fuel Spin-on..... **[2] BF970 +**  
Axial Seal Air (4L9853)..... **PA1629-S**  
Air (Reuse OE Foam Wrap  
(9L3420)..... **PA1630-2**  
Air Comp. Breather (9L2169)..... **PA1704**

54F, 54FS, 54P, 54PS, 54PT, 54PTX, 54PW,  
57F, 57P, 60P, 86F, 86P, 110P w/Cat 3406 Eng  
F-F Lube..... **B99 +**  
Fuel Spin-on..... **BF614 +**

54F, 54FS, 54P, 54PS, 54PT, 54PTX, 54PW,  
57F, 57P, 60P, 86F, 86P, 110P w/Detroit Diesel  
8V-92 Eng.  
F-F Lube Ele..... **P20-HD +**  
F-F Lube Spin-on..... **B95 +**  
P. Fuel Spin-on..... **BF5800 +**  
S. Fuel Spin-on..... **BF5810**

54P, 54PS, 54PT, 54PTX, 54PW, 57F, 60P,  
86F, 86P, 110P w/Cummins KT450, KTA525  
Engs.  
F-F Lube Spin-on..... **[2] B196 +**  
B-P Lube Ele..... **C750-E**  
Fuel Spin-on..... **BF957 +**

**MARMON-HERRINGTON  
Trucks & Buses (cont'd)**

54P, 54PS, 54PT, 54PTX, 54PW, 57F, 60P,  
86F, 86P, 110P w/Cummins KT450, KTA525  
Engs. (Cont'd)  
Coolant (Maintenance)..... **BW5073**

54P, 54PS, 54PT, 54PW, 57F, 57P, 60P, 86F,  
86P w/Cat 3408 Eng.  
F-F Lube..... **[2] B99 +**  
Fuel Spin-on..... **BF614 +**

57PHR, SB57R w/Cat 3406B Eng.  
Lube..... **B99 +**  
P. Fuel Ele. (Add G323 Gasket).... **[2] PF935**  
S. Fuel Spin-on..... **BF614 +**

60P, 86F, 86P, 110P w/Cummins L10, F290,  
NTC290, Formula 300, NTC350, 400 Engs.  
F-F Lube Ele..... **P999-HD**  
F-F Lube Spin-on..... **B196 +**  
B-P Lube Ele..... **C750-E +**  
B-P Lube Spin-on..... **B7577**  
Fuel Spin-on..... **BF957 +**  
Coolant (Maintenance)..... **BW5071**

86P w/Detroit Diesel Series 60 Eng.  
F-F Lube..... **[3] B95 +**  
P. Fuel..... **BF5800 +**  
S. Fuel..... **BF5810**

CHDT-AC, CHDT-BC, HDT-AC86, HDT-BC86,  
HDT-BC110 w/Cummins Eng.  
F-F Lube Ele..... **P999-HD**  
F-F Lube Spin-on..... **B196 +**  
B-P Lube Ele..... **C750-E +**  
Fuel Spin-on..... **BF957 +**  
Coolant Spin-on..... **BW5071**

CHDT-BC, HDT-BC86, HDT-BC110 w/Cat 3406  
Eng.  
Lube Spin-on..... **B99 +**  
Fuel Spin-on..... **BF614 +**

CHDT-BC, HDT-BC86, HDT-BC110 w/Cat 3408  
Eng.  
Lube Spin-on..... **[2] B99 +**  
Fuel Spin-on..... **BF614 +**

CHDT-BC, HDT-BC86, HDT-BC110 w/GMC  
Diesel Eng.  
F-F Lube Ele..... **P20-HD +**  
P. Fuel Spin-on..... **BF5800 +**  
S. Fuel Spin-on..... **BF5810**

SB125S w/Cat 3406C Eng.  
Lube..... **B99 +**  
P. Fuel Ele..... **[2] PF935**  
Fuel Spin-on..... **[2] BF614 +**

**MCI-MOTOR COACH IND.  
Buses**

96A2  
Air (T12-1009)..... **PA2839**

**MCI-MOTOR COACH IND.  
Buses (cont'd)**

102A2 w/Detroit Diesel 6V-92N (9.0L) Eng.  
Air (T12-1009)..... **PA2839**

102B3 w/Cat 3176 (10.3L) Eng.  
Air (T12-1009)..... **PA2839**

102B3 w/Cummins L10 (10.0L) Eng.  
Air (T12-1009)..... **PA2839**

102B3 w/Detroit Diesel 6V-92N (9.0L) Eng.  
Air (T12-1009)..... **PA2839**

102B3 w/Detroit Diesel 8V-92 (12.1L) Eng.  
Air (T12-1009)..... **PA2839**

102C3 w/Detroit Diesel 6V-92T Eng.  
Lube (T08-1074)..... **B96-MPG +**  
P. Fuel (T12-1019)..... **BF5800 +**  
S. Fuel (T12-1018)..... **BF5810**  
Air (T12-1009)..... **PA2839**  
Coolant (T06-1012)..... **BW5137**  
Trans. Spin-on (T17-1011)..... **BT359**  
Steering (T17-1059)..... **PT951 +**

102D3 w/Cat 3176 (10.3L) Eng.  
Air (T12-1009)..... **PA2839**

102D3 w/Cat C10 (10.3L) Eng.  
Air (T12-1009)..... **PA2839**

102D3 w/Cat C13 (12.5L) Eng.  
Air (T12-1009)..... **PA2839**

102D3 w/Cummins L10 (10.0L) Eng.  
Air (T12-1009)..... **PA2839**

102D3 w/Cummins M11 (10.8L) Eng.  
Air (T12-1009)..... **PA2839**

102D3 w/Detroit Diesel Series 60 (11.1L) or  
(12.7L) Eng.  
Air (T12-1009)..... **PA2839**

102DL3 w/Detroit Diesel Series 60 Eng.  
Lube (T08-1043)..... **[2] B495**

Fuel/Water Separator (w/Drain)  
(23512317)..... **BF5813 +**

Fuel/Water Separator (Open End  
for Bowl) (23512317)..... **BF5813-O +**

Fuel (T12-1018)..... **BF5810**  
Air (T12-1009)..... **PA2839**

Coolant (T06-1013)..... **BW5071**  
Trans. (2 In. Kit) (Allison  
29540493)..... **PT9416-MPG KIT**

Trans. (4 In. Kit) (Allison  
29540494)..... **PT9415-MPG KIT**  
Steering (T17-1059)..... **PT951 +**

A3  
Air (T12-1009)..... **PA2839**

B4000  
Air (T12-1009)..... **PA2839**

Courier 100V w/IHC Gas Eng.  
B-P Lube Sock..... **CU406<sup>90</sup>**

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>MCI-MOTOR COACH IND. Buses (cont'd)</b>	<b>MCI-MOTOR COACH IND. Buses (cont'd)</b>	<b>MCI-MOTOR COACH IND. Buses (cont'd)</b>
Courier 200A w/Continental R6572 Eng. Lube..... P54	J4500 w/Cat C13 (12.5L) Eng. (1/2004-2006) Lube (1R1808)..... B7299 + Fuel/Water Separator (Davco 380087)..... PF7680 Trans. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	MC9 Lube (T08-1074)..... B96-MPG + P. Fuel Ele. (T12-1093)..... PF845 Air (Early) (T12-1010)..... PA2357 + Air (Late) (T12-1009)..... PA2839 Coolant (T06-1012)..... BW5137 Steering (T17-1059)..... PT951 +
D4505 w/Cat C13 (12.5L) Eng. Air (T12-1111)..... PA3916 Trans. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	J4500 w/Cat C13 (12.5L) Eng. (2007-on) Lube (1R1808)..... B7299 + Fuel/Water Separator (Davco 380087)..... PF7680 Breather (296-8325)..... CV15008 Trans. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	<b>MCMILLAN ELECTRIC COMPANY</b> <b>Auxiliary Power Units (APU)</b> IdleTime w/Cat Eng. P. Fuel Ele. (130366040)..... PF937 S. Fuel In-Line (Wix 33971)..... BF45000 Radial Seal Air (Don. P822686)... RS3715
D4505 w/Detroit Diesel Series 60 (12.7L) Eng. Air (T12-1111)..... PA3916 Trans. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	J4500 w/Detroit DD13 (12.8L) Eng. (2019) Lube (A4731800409)..... P7505 Fuel (A4720900651)..... PF9908 KIT	IdleTime w/Perkins Eng. P. Fuel Ele. (130366040)..... PF937 S. Fuel In-Line (Wix 33971)..... BF45000 Radial Seal Air (Don. P822686)... RS3715
E Models Air (T12-1111)..... PA3916	J4500 w/Detroit DD13 (12.8L) Eng. (2020) Lube (To Eng. S/N 472910S0690710) (A4731800409)..... P7505 Fuel (A4700903151)..... PF9908 KIT	<b>MCNEILUS</b> <b>Hydraulic Equipment</b> Models w/CGB Hyd. Systems Hyd. (1571988)..... PT498-10
E4500 Air (T12-1111)..... PA3916 Trans. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	J4500 w/Detroit DD13 (12.8L) Eng. (2021) Fuel (A4700903151)..... PF9908 KIT	Models w/MTM Hyd. Systems Hyd. Spin-on (436)..... BT287-10
J3500 w/Cummins L9 (9.0) Eng. (2019) Lube (3401544)..... B40142 Fuel (5303743)..... BF63000	J4500 w/Detroit Series 60 Eng. Lube (23518480)..... [2] B495 Fuel/Water Separator Ele. (Davco 380087)..... PF7680 Fuel/Water Separator Ele. (23521528)..... PF7744 Fuel/Water Separator Spin-on (w/Drain) (23512317)..... BF5813 + Fuel/Water Separator Spin-on (Open End for Bowl) (23512317).. BF5813-O + Fuel (9051272)..... PF7680 P. Fuel (23518481)..... BF5800 + S. Fuel (23518482)..... BF5810 Air (T12-1111)..... PA3916 Coolant (23524403)..... B5134 + Trans. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Models w/Rex Hyd. Systems Hyd. Ele. (298-00133-53)..... P529
J3500 w/Cummins L9 (9.0) Eng. (2020) Lube (5444774)..... B40142 Fuel (5303743)..... BF63000	J4500 w/Detroit DD13 (12.8L) Eng. (2021) Fuel (A4700903151)..... PF9908 KIT	Oil Reservoirs Breather (w/Adapter) (9630.604428)..... B7024 Breather (w/o Adapter) (9630.604428)..... BT368 Hyd. (9630.604430)..... H9075
J4500 w/Cummins ISM Eng. Dual-Flow Lube (3101869)..... BD7154 + Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... BD50000 Fuel/Water Separator (Davco 380087)..... PF7680 Air (T12-1111)..... PA3916 Breather (2007-on) (3683918)..... CV15000 Trans. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	J4500 w/Detroit Series 60 Eng. Lube (23518480)..... [2] B495 Fuel/Water Separator Ele. (Davco 380087)..... PF7680 Fuel/Water Separator Ele. (23521528)..... PF7744 Fuel/Water Separator Spin-on (w/Drain) (23512317)..... BF5813 + Fuel/Water Separator Spin-on (Open End for Bowl) (23512317).. BF5813-O + Fuel (9051272)..... PF7680 P. Fuel (23518481)..... BF5800 + S. Fuel (23518482)..... BF5810 Air (T12-1111)..... PA3916 Coolant (23524403)..... B5134 + Trans. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	MCNEILUS Mixer Bridgemaster System Hyd. Spin-on (140.00436)..... BT287-3
J4500 w/Cummins ISX 15.0 (14.9L) Eng. (2019) Dual-Flow Lube (4367100)..... BD50000 Fuel (5365988)..... BF46129	J4500 w/Detroit Series 60 Eng. Lube (23518480)..... [2] B495 Fuel/Water Separator Ele. (Davco 380087)..... PF7680 Fuel/Water Separator Ele. (23521528)..... PF7744 Fuel/Water Separator Spin-on (w/Drain) (23512317)..... BF5813 + Fuel/Water Separator Spin-on (Open End for Bowl) (23512317).. BF5813-O + Fuel (9051272)..... PF7680 P. Fuel (23518481)..... BF5800 + S. Fuel (23518482)..... BF5810 Air (T12-1111)..... PA3916 Coolant (23524403)..... B5134 + Trans. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	PK6950 Gear Box Hyd. Spin-on (140.00436)..... BT287-3
J4500 w/Cummins ISX 15.0 (14.9L) Eng. (2020) Lube (4367100)..... BD50000 Fuel (5365988)..... BF46129	J4500 w/Detroit Series 60 Eng. Lube (23518480)..... [2] B495 Fuel/Water Separator Ele. (Davco 380087)..... PF7680 Fuel/Water Separator Ele. (23521528)..... PF7744 Fuel/Water Separator Spin-on (w/Drain) (23512317)..... BF5813 + Fuel/Water Separator Spin-on (Open End for Bowl) (23512317).. BF5813-O + Fuel (9051272)..... PF7680 P. Fuel (23518481)..... BF5800 + S. Fuel (23518482)..... BF5810 Air (T12-1111)..... PA3916 Coolant (23524403)..... B5134 + Trans. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Sliding Mixer System Hyd. Spin-on (140.00436)..... BT287-3
J4500 w/Cummins ISX 15.0 (14.9L) Eng. (2021) Lube (5575298)..... B40145 Fuel (5365988)..... BF46129	J4500 w/Detroit Series 60 Eng. Lube (23518480)..... [2] B495 Fuel/Water Separator Ele. (Davco 380087)..... PF7680 Fuel/Water Separator Ele. (23521528)..... PF7744 Fuel/Water Separator Spin-on (w/Drain) (23512317)..... BF5813 + Fuel/Water Separator Spin-on (Open End for Bowl) (23512317).. BF5813-O + Fuel (9051272)..... PF7680 P. Fuel (23518481)..... BF5800 + S. Fuel (23518482)..... BF5810 Air (T12-1111)..... PA3916 Coolant (23524403)..... B5134 + Trans. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	<b>MCNEILUS</b> <b>Refuse Systems</b> G & H Roll Off Hyd. (1108803)..... PT8306-10 Hyd. (10 Micron) (14000436)..... BT287-3
J4500 w/Cat C13 (12.5L) Eng. (To 1/2004) Lube (1R0716)..... B99 + Fuel/Water Separator (Davco 380087)..... PF7680 Trans. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	J4500 w/Detroit Series 60 Eng. Lube (23518480)..... [2] B495 Fuel/Water Separator Ele. (Davco 380087)..... PF7680 Fuel/Water Separator Ele. (23521528)..... PF7744 Fuel/Water Separator Spin-on (w/Drain) (23512317)..... BF5813 + Fuel/Water Separator Spin-on (Open End for Bowl) (23512317).. BF5813-O + Fuel (9051272)..... PF7680 P. Fuel (23518481)..... BF5800 + S. Fuel (23518482)..... BF5810 Air (T12-1111)..... PA3916 Coolant (23524403)..... B5134 + Trans. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Galbreath Roll Off Breather (Schroeder ABF310F)... BT367-S Hyd. Ele. (3 Micron) (Pall HC8800FKN16H)..... H9123 Hyd. Ele. (Schroeder K10)..... PT707-HD10 Hyd. Spin-on (10 Micron) (140.00436)..... BT287-3

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



<b>MCNEILUS</b> Refuse Systems (cont'd)	<b>MERCEDES-BENZ</b> Engines (cont'd)	<b>MERCEDES-BENZ</b> Engines (cont'd)
Heil 5000 Body Hyd. (MTM 1106843)..... <b>PT23595-MPG</b>	MBE904 (4.3L), MBE924 (4.8L) <b>5 5/16 In. F-F Lube Ele.</b> (1801609)..... <b>P7199</b>	OM355 (Cont'd) <b>Fuel Ele.</b> (4774515)..... <b>PF231</b> <b>Fuel Ele.</b> (4774701)..... <b>PF950</b>
Kann Systems <b>Breather</b> (Schroeder ABF310F)... <b>BT367-S</b>	<b>8 3/8 In. F-F Lube Ele.</b> (A0001801709)..... <b>P7188</b>	OM360 <b>F-F Lube</b> (Add G439 Gasket) (11843925)..... <b>P507</b>
Wayne Systems <b>Breather</b> (Schroeder ABF310F)... <b>BT367-S</b>	<b>Opt. B-P Lube Spinner</b> (A9061810086)..... <b>BC7326 +</b>	<b>B-P Lube</b> (1846725)..... <b>P42</b>
<b>MECHRON POWER SYSTEMS</b> <b>Auxiliary Power Units (APU)</b>	<b>4 1/16 In. Fuel</b> (A0000901551)..... <b>PF7735</b>	<b>Fuel Ele.</b> (3440927005)..... <b>PF834</b>
Lightning w/Kubota Z482 Eng. <b>Radial Seal Air</b> (Don. P822686)... <b>RS3715</b>	<b>7 31/32 In. Fuel</b> (A5410920805)... <b>PF7761</b>	<b>Fuel Ele.</b> (4774515)..... <b>PF231</b> <b>Fuel Ele.</b> (4774701)..... <b>PF950</b>
<b>MERCEDES-BENZ</b> <b>Engines</b>	MBE906 (6.4L), MBE926 (7.2L) <b>F-F Lube Ele.</b> (A0001801709)..... <b>P7188</b>	OM362A, OM366A <b>Lube</b> (4011840025)..... <b>P242</b> <b>Fuel</b> ..... <b>[2] PF834</b>
L311, LK311, L312 <b>Fuel Ele.</b> ..... <b>PF950</b>	<b>Opt. B-P Lube Spinner</b> (A9061810086)..... <b>BC7326 +</b>	OM401, OM402 <b>Lube</b> (4011800009)..... <b>P242</b> <b>Fuel Ele.</b> (4773815)..... <b>[2] PF834</b>
L315, LK315 <b>Fuel Ele.</b> ..... <b>PF950</b>	<b>4 1/16 In. Fuel</b> (A0000901551)..... <b>PF7735</b>	OM403, OM404, OM407 <b>Lube</b> (4031840025)..... <b>P294</b> <b>Fuel Ele.</b> (4220900051)..... <b>[2] PF950</b>
L319, O319 <b>Lube</b> ..... <b>P106</b> <b>Fuel</b> ..... <b>PF834</b>	<b>8 In. Fuel</b> (A5410920805)..... <b>PF7761</b>	OM421 <b>Lube</b> (4011800009)..... <b>P242</b> <b>Fuel Ele.</b> ..... <b>[2] PF950</b>
L325, LK325 <b>Fuel Ele.</b> ..... <b>PF950</b>	MBE4000 Series (12.8L) <b>Lube</b> (A0001802109)..... <b>P7230</b> <b>Fuel</b> (5410900151)..... <b>PF7761</b>	OM423, OM424, OM427, OM442, OM444 <b>Lube</b> (4031840025)..... <b>P294</b> <b>Fuel Ele.</b> (4220900051)..... <b>[2] PF950</b>
L3000D, D3250 <b>Fuel</b> ..... <b>PF834</b>	OM312 <b>141.3 mm Fuel</b> (4774701)..... <b>PF950</b> <b>108.7 mm Fuel</b> (4774715)..... <b>PF834</b>	OM457LA <b>Lube</b> ..... <b>P7230</b> <b>Fuel/Water Separator</b> ..... <b>BF1363</b> <b>Fuel</b> ..... <b>PF7761</b>
121-B111, M180-110 <b>Lube</b> ..... <b>P106</b>	OM314 <b>Lube</b> ..... <b>P41</b> <b>114.3 mm Fuel</b> (3524700092)..... <b>F834-F</b> <b>142.9 mm Fuel</b> (Mann BF900X)... <b>F950-F</b>	OM460LA <b>Lube</b> (A0001802909)..... <b>P7230</b> <b>Some Fuel/Water Separator</b> (Alliance ABPN122R50418)..... <b>BF9898-O</b> <b>Fuel</b> (A5410900151)..... <b>PF7761</b>
M202B, M203B, M204B <b>141.3 mm Fuel</b> (4774515)..... <b>PF950</b> <b>108.7 mm Fuel</b> (4774715)..... <b>PF834</b>	OM321 <b>S. Fuel Ele.</b> ..... <b>PF950</b>	OM501A, OM501LA, OM502A, OM502LA <b>F-F Lube</b> (5411800009)..... <b>P7192</b> <b>B-P Lube</b> (21840525)..... <b>C704-L</b> <b>Fuel/Water Separator</b> ..... <b>BF1363</b> <b>P. Fuel</b> ..... <b>PF7761</b> <b>Breather</b> (5410100080)..... <b>CV15001</b>
M315 <b>S. Fuel Ele.</b> ..... <b>PF950</b>	OM322 <b>Fuel Ele.</b> (4774515)..... <b>PF950</b>	OM611, OM612 <b>Lube</b> (Mann HU718/1k)..... <b>P1443</b> <b>Fuel</b> (Mann WK842/13)..... <b>BF7756</b>
M906LAG <b>Lube</b> ..... <b>P7188</b>	OM326 <b>S. Fuel Ele.</b> ..... <b>PF950</b>	OM615 <b>Lube Ele.</b> (1848525)..... <b>P40</b> <b>Fuel Ele.</b> (4773815)..... <b>PF834</b>
MB846A, MB846AB <b>S. Fuel Ele.</b> ..... <b>PF950</b>	OM327 <b>Lube Ele.</b> (1846725)..... <b>P42</b>	OM636 <b>Lube</b> ..... <b>P106</b> <b>4 3/16 In. S. Fuel</b> ..... <b>PF834</b> <b>5 9/16 In. S. Fuel Ele.</b> ..... <b>PF950</b>
MB851, MB852, MB853, MB854, MB856, MB861, MB862, MB863, MB864, MB866 <b>Fuel Ele.</b> (4774701)..... <b>PF950</b> <b>Fuel</b> (4774715)..... <b>PF834</b>	OM346 <b>F-F Lube</b> (Add G439 Gasket) (11843925)..... <b>P507</b> <b>B-P Lube</b> (1846725)..... <b>P42</b> <b>Fuel Ele.</b> (3440927005)..... <b>PF834</b> <b>Fuel Ele.</b> (4774515)..... <b>PF231</b> <b>Fuel Ele.</b> (4774701)..... <b>PF950</b>	OM668 <b>Fuel</b> (Mann WK842/13)..... <b>BF7756</b>
MBE600 5 Cyl. (2.7L) Turbo Diesel <b>Lube</b> (6111800009)..... <b>P1443</b> <b>Fuel</b> (6120920001)..... <b>BF7778</b>	OM352 <b>Lube</b> (1977-78)..... <b>P52</b> <b>Lube</b> (1979-on)..... <b>P7015</b> <b>Fuel Ele.</b> ..... <b>F950-F</b>	
MBE900 Series (7.2L) <b>5 15/16 In. F-F Lube</b> (A0001801609)..... <b>P7199</b>	OM352A <b>F-F Lube</b> (Add G439 Gasket) (11843925)..... <b>P507</b> <b>B-P Lube</b> (1846725)..... <b>P42</b> <b>Fuel Ele.</b> (3440927005)..... <b>PF834</b> <b>Fuel Ele.</b> (4774515)..... <b>PF231</b> <b>Fuel Ele.</b> (4774701)..... <b>PF950</b>	
<b>8 3/8 In. F-F Lube</b> (A0001801709)..... <b>P7188</b>	OM355 <b>F-F Lube Ele.</b> (To 3/78)..... <b>P52</b> <b>F-F Lube Ele.</b> (3/78-on) (3551800009)..... <b>P7052</b> <b>Fuel Ele.</b> (3440927005)..... <b>PF834</b>	
<b>Opt. B-P Lube Spinner</b> (A9061810086)..... <b>BC7326 +</b>		
<b>Opt. Fuel/Water Separator</b> <b>Spin-on</b> (Alliance ABPS3226FL02)..... <b>BF1346 +</b>		
<b>4 1/16 In. Fuel Ele.</b> (A0000901551)..... <b>PF7735</b>		
<b>7 31/32 In. Fuel Ele.</b> (A5410920805)..... <b>PF7761</b>		


+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ Engines (cont'd)	MERCEDES-BENZ European Light Duty Vehicles (cont'd)	MERCEDES-BENZ European Light Duty Vehicles (cont'd)
OM904LA, OM905LA, OM906LA, OM907LA Lube Ele. (A0001801609)..... P7199 Fuel/Water Separator..... BF1363 Fuel Ele. (A9060920305)..... PF7735	Sprinter 2/3/410D (901-2) w/OM602986 Eng. (01/97-06/00) (Cont'd) Cab Air (9018300018)..... PA4489 Cab Air (w/Carbon) (9018300418)..... PA4409	Sprinter 2/3/416 CDI (902) (with Water Sensor Connection) w/OM612DELA Eng. (01/04-on) (Cont'd) Cab Air (w/Carbon) (9018300418)..... PA4409
OM924LA Lube..... P7199 Fuel/Water Separator..... BF1363 Fuel..... PF7735	Sprinter 2/3/411 CDI (902) w/OM611DELA Eng. (04/00-on) Lube (6111800009)..... P1443 Fuel (6110920201)..... BF7756 70.6 mm Height Air (30947504).. PA4600 81.0 mm Height Air (30948204).. PA4601 Cab Air (9018300018)..... PA4489 Cab Air (w/Carbon) (9018300418)..... PA4409	Sprinter 2/3/416 CDI (902) (with Water Suction) w/OM612DELA Eng. (04/00-12/03) Lube (6111800009)..... P1443 Fuel (6120920001)..... BF7778 70.6 mm Height Air (30947504).. PA4600 81.0 mm Height Air (30948204).. PA4601 Cab Air (9018300018)..... PA4489 Cab Air (w/Carbon) (9018300418)..... PA4409
OM926LA Lube..... P7188 Fuel/Water Separator..... BF1363 Fuel..... PF7735	Sprinter 2/3/412D (901-2) w/OM602980DELA Eng. (02/95-06/00) Lube (6021800009)..... P7196 Fuel (10922201)..... BF7619 70.6 mm Height Air (30947504).. PA4600 81.0 mm Height Air (30948204).. PA4601 Cab Air (9018300018)..... PA4489 Cab Air (w/Carbon) (9018300418)..... PA4409	Sprinter 2/3/416 CDI (902) w/OM612DELA Eng. (04/00-on) Lube (6111800009)..... P1443 Fuel (6110920201)..... BF7756 70.6 mm Height Air (30947504).. PA4600 81.0 mm Height Air (30948204).. PA4601 Cab Air (9018300018)..... PA4489 Cab Air (w/Carbon) (9018300418)..... PA4409
<b>MERCEDES-BENZ</b> <b>European Light Duty Vehicles</b>	Sprinter 2/3/413 CDI (901-2) (with Water Suction) w/OM612DELA Eng. (04/00-on) Lube (6111800009)..... P1443 Fuel (6120920001)..... BF7778 70.6 mm Height Air (30947504).. PA4600 81.0 mm Height Air (30948204).. PA4601 Cab Air (9018300018)..... PA4489 Cab Air (w/Carbon) (9018300418)..... PA4409	Sprinter II 209 CDI w/OM646LA Eng. (04/06-on) Lube (6111800009)..... P1443 Fuel (w/o SP) (6460920501)..... BF9846 Fuel (w/SP) (6460920701)..... BF7972 Air (902651)..... PA4390 Cabin Air (9068300218)..... PA4488 Cabin Air (w/Carbon) (9068300318)..... PA4336
Citan 108 CDI (W415) w/OM 607.951 Eng. (10/12-on) Hyd. (1402770095)..... 20048	Sprinter 2/3/413 CDI (901-2) w/OM612DELA Eng. (04/00-on) Lube (6111800009)..... P1443 Fuel (6110920201)..... BF7756 70.6 mm Height Air (30947504).. PA4600 81.0 mm Height Air (30948204).. PA4601 Cab Air (9018300018)..... PA4489 Cab Air (w/Carbon) (9018300418)..... PA4409	Sprinter II 210 CDI w/OM651 DE22LA Eng. (05/09-on) Lube (6511840025)..... P40001 Fuel (6420901652)..... BF46001 Air (902651)..... PA4390 Cab Air (9068300318)..... PA4336
Citan 109 CDI (W415) w/OM 607.951 Eng. (10/12-on) Hyd. (1402770095)..... 20048	Sprinter 2/3/414 (901-2) w/M111979E23 Eng. (02/95-on) Lube (1041800109)..... P1419 Fuel (24772801)..... BF1195 70.6 mm Height Air (30947504).. PA4600 81.0 mm Height Air (30948204).. PA4601 Cab Air (9018300018)..... PA4489 Cab Air (w/Carbon) (9018300418)..... PA4409	Sprinter II 211 CDI w/OM646LA Eng. (04/06-on) Lube (6111800009)..... P1443 Fuel (w/o SP) (6460920501)..... BF9846 Fuel (w/SP) (6460920701)..... BF7972 Air (902651)..... PA4390 Cabin Air (9068300218)..... PA4488 Cabin Air (w/Carbon) (9068300318)..... PA4336
Citan 111 CDI (W415) w/OM 607.951 Eng. (01/13-on) Hyd. (1402770095)..... 20048	Sprinter 2/3/416 CDI (902) (with Water Sensor Connection) w/OM612DELA Eng. (01/04-on) Lube (6111800009)..... P1443 Fuel..... BF7972 70.6 mm Height Air (30947504).. PA4600 81.0 mm Height Air (30948204).. PA4601 Cab Air (9018300018)..... PA4489	Sprinter II 213 CDI w/OM646LA Eng. (04/06-on) Lube (6111800009)..... P1443 Fuel (w/o SP) (6460920501)..... BF9846 Fuel (w/SP) (6460920701)..... BF7972 Air (902651)..... PA4390 Cabin Air (9068300218)..... PA4488 Cabin Air (w/Carbon) (9068300318)..... PA4336
Sprinter 2/3/408 CDI (902) (with Water Suction) w/OM611DELA Eng. (04/00-on) Lube (6111800009)..... P1443 Fuel (6120920001)..... BF7778 70.6 mm Height Air (30947504).. PA4600 81.0 mm Height Air (30948204).. PA4601 Cab Air (9018300018)..... PA4489 Cab Air (w/Carbon) (9018300418)..... PA4409	Sprinter 2/3/408 CDI (902) w/OM611DELA Eng. (04/00-on) Lube (6111800009)..... P1443 Fuel (6110920201)..... BF7756 70.6 mm Height Air (30947504).. PA4600 81.0 mm Height Air (30948204).. PA4601 Cab Air (9018300018)..... PA4489 Cab Air (w/Carbon) (9018300418)..... PA4409	
Sprinter 2/3/408 CDI (902) w/OM611DELA Eng. (04/00-on) Lube (6111800009)..... P1443 Fuel (6110920201)..... BF7756 70.6 mm Height Air (30947504).. PA4600 81.0 mm Height Air (30948204).. PA4601 Cab Air (9018300018)..... PA4489 Cab Air (w/Carbon) (9018300418)..... PA4409	Sprinter 2/3/408D (901-2) w/OM601943 Eng. (02/95-06/00) Lube (6021800009)..... P7196 Fuel (10922201)..... BF7619 70.6 mm Height Air (30947504).. PA4600 81.0 mm Height Air (30948204).. PA4601 Cab Air (9018300018)..... PA4489 Cab Air (w/Carbon) (9018300418)..... PA4409	
Sprinter 2/3/410D (901-2) w/OM602986 Eng. (01/97-06/00) Lube (6021800009)..... P7196 Fuel (10922201)..... BF7619 70.6 mm Height Air (30947504).. PA4600 81.0 mm Height Air (30948204).. PA4601		

Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Light Duty Vehicles (cont'd)	MERCEDES-BENZ European Light Duty Vehicles (cont'd)	MERCEDES-BENZ European Light Duty Vehicles (cont'd)
Sprinter II 213 CDI w/OM651 DE22LA Eng. (05/09-on) <b>Lube</b> (6511840025)..... <b>P40001</b> <b>Fuel</b> (6420901652)..... <b>BF46001</b> <b>Air</b> (902651)..... <b>PA4390</b> <b>Cab Air</b> (9068300318)..... <b>PA4336</b>	Sprinter II 311 CDI w/OM646LA Eng. (04/06-on) <b>Lube</b> (6111800009)..... <b>P1443</b> <b>Fuel</b> (w/o SP) (6460920501)..... <b>BF9846</b> <b>Fuel</b> (w/SP) (6460920701)..... <b>BF7972</b> <b>Air</b> (902651)..... <b>PA4390</b> <b>Cabin Air</b> (9068300218)..... <b>PA4488</b> <b>Cabin Air</b> (w/Carbon) (9068300318)..... <b>PA4336</b>	Sprinter II 324 V6 w/M272E35 Eng. (04/06-on) <b>Lube</b> (1121840625)..... <b>P7493</b> <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Air</b> (902651)..... <b>PA4390</b> <b>Cabin Air</b> (9068300218)..... <b>PA4488</b> <b>Cabin Air</b> (w/Carbon) (9068300318)..... <b>PA4336</b>
Sprinter II 215 CDI w/OM646LA Eng. (04/06-on) <b>Lube</b> (6111800009)..... <b>P1443</b> <b>Fuel</b> (w/o SP) (6460920501)..... <b>BF9846</b> <b>Fuel</b> (w/SP) (6460920701)..... <b>BF7972</b> <b>Air</b> (902651)..... <b>PA4390</b> <b>Cabin Air</b> (9068300218)..... <b>PA4488</b> <b>Cabin Air</b> (w/Carbon) (9068300318)..... <b>PA4336</b>	Sprinter II 313 CDI w/OM646LA Eng. (04/06-on) <b>Lube</b> (6111800009)..... <b>P1443</b> <b>Fuel</b> (w/o SP) (6460920501)..... <b>BF9846</b> <b>Fuel</b> (w/SP) (6460920701)..... <b>BF7972</b> <b>Air</b> (902651)..... <b>PA4390</b> <b>Cabin Air</b> (9068300218)..... <b>PA4488</b> <b>Cabin Air</b> (w/Carbon) (9068300318)..... <b>PA4336</b>	Sprinter II 411 CDI w/OM646LA Eng. (04/06-on) <b>Lube</b> (6111800009)..... <b>P1443</b> <b>Fuel</b> (w/o SP) (6460920501)..... <b>BF9846</b> <b>Fuel</b> (w/SP) (6460920701)..... <b>BF7972</b> <b>Air</b> (902651)..... <b>PA4390</b> <b>Cabin Air</b> (9068300218)..... <b>PA4488</b> <b>Cabin Air</b> (w/Carbon) (9068300318)..... <b>PA4336</b>
Sprinter II 216 CDI w/OM651 DE22LA Eng. (05/09-on) <b>Lube</b> (6511840025)..... <b>P40001</b> <b>Fuel</b> (6420901652)..... <b>BF46001</b> <b>Air</b> (902651)..... <b>PA4390</b> <b>Cab Air</b> (9068300318)..... <b>PA4336</b>	Sprinter II 313 CDI w/OM651 DE22LA Eng. (05/09-on) <b>Lube</b> (6511840025)..... <b>P40001</b> <b>Fuel</b> (6420901652)..... <b>BF46001</b> <b>Air</b> (902651)..... <b>PA4390</b> <b>Cab Air</b> (9068300318)..... <b>PA4336</b>	Sprinter II 413 CDI w/OM651 DE22LA Eng. (05/09-on) <b>Lube</b> (6511840025)..... <b>P40001</b> <b>Fuel</b> (6420901652)..... <b>BF46001</b> <b>Air</b> (902651)..... <b>PA4390</b> <b>Cab Air</b> (9068300318)..... <b>PA4336</b>
Sprinter II 218 CDI V6 w/OM642LA Eng. (04/06-on) <b>Lube</b> (5175571AA)..... <b>P7413</b> <b>Fuel</b> (w/o SP) (6460920501)..... <b>BF9846</b> <b>Fuel</b> (w/SP) (6460920701)..... <b>BF7972</b> <b>Air</b> (902651)..... <b>PA4390</b> <b>Cabin Air</b> (9068300218)..... <b>PA4488</b> <b>Cabin Air</b> (w/Carbon) (9068300318)..... <b>PA4336</b>	Sprinter II 315 CDI w/OM646LA Eng. (04/06-on) <b>Lube</b> (6111800009)..... <b>P1443</b> <b>Fuel</b> (w/o SP) (6460920501)..... <b>BF9846</b> <b>Fuel</b> (w/SP) (6460920701)..... <b>BF7972</b> <b>Air</b> (902651)..... <b>PA4390</b> <b>Cabin Air</b> (9068300218)..... <b>PA4488</b> <b>Cabin Air</b> (w/Carbon) (9068300318)..... <b>PA4336</b>	Sprinter II 415 CDI w/OM646LA Eng. (04/06-on) <b>Lube</b> (6111800009)..... <b>P1443</b> <b>Fuel</b> (w/o SP) (6460920501)..... <b>BF9846</b> <b>Fuel</b> (w/SP) (6460920701)..... <b>BF7972</b> <b>Air</b> (902651)..... <b>PA4390</b> <b>Cabin Air</b> (9068300218)..... <b>PA4488</b> <b>Cabin Air</b> (w/Carbon) (9068300318)..... <b>PA4336</b>
Sprinter II 219 CDI V6 w/OM642 DE30LA Eng. (05/09-on) <b>Lube</b> (6421800009)..... <b>P7413</b> <b>Fuel</b> (6420901652)..... <b>BF46001</b> <b>Air</b> (902651)..... <b>PA4390</b> <b>Cab Air</b> (9068300318)..... <b>PA4336</b>	Sprinter II 316 CDI w/OM651 DE22LA Eng. (05/09-on) <b>Lube</b> (6511840025)..... <b>P40001</b> <b>Fuel</b> (6420901652)..... <b>BF46001</b> <b>Air</b> (902651)..... <b>PA4390</b> <b>Cab Air</b> (9068300318)..... <b>PA4336</b>	Sprinter II 416 CDI w/OM651 DE22LA Eng. (05/09-on) <b>Lube</b> (6511840025)..... <b>P40001</b> <b>Fuel</b> (6420901652)..... <b>BF46001</b> <b>Air</b> (902651)..... <b>PA4390</b> <b>Cab Air</b> (9068300318)..... <b>PA4336</b>
Sprinter II 224 V6 w/M272E35 Eng. (04/06-on) <b>Lube</b> (1121840625)..... <b>P7493</b> <b>Fuel</b> ..... <b>N/S</b> <b>Air</b> (902651)..... <b>PA4390</b> <b>Cabin Air</b> (9068300218)..... <b>PA4488</b> <b>Cabin Air</b> (w/Carbon) (9068300318)..... <b>PA4336</b>	Sprinter II 316 NGT w/M271E 18ML Eng. (05/08-on) <b>Lube</b> (2711800009)..... <b>P40099</b> <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Air</b> (902651)..... <b>PA4390</b> <b>Cab Air</b> (9068300318)..... <b>PA4336</b>	Sprinter II 418 CDI V6 w/OM642LA Eng. (04/06-on) <b>Lube</b> (5175571AA)..... <b>P7413</b> <b>Fuel</b> (w/o SP) (6460920501)..... <b>BF9846</b> <b>Fuel</b> (w/SP) (6460920701)..... <b>BF7972</b> <b>Air</b> (902651)..... <b>PA4390</b> <b>Cabin Air</b> (9068300218)..... <b>PA4488</b> <b>Cabin Air</b> (w/Carbon) (9068300318)..... <b>PA4336</b>
Sprinter II 309 CDI w/OM646LA Eng. (04/06-on) <b>Lube</b> (6111800009)..... <b>P1443</b> <b>Fuel</b> (w/o SP) (6460920501)..... <b>BF9846</b> <b>Fuel</b> (w/SP) (6460920701)..... <b>BF7972</b> <b>Air</b> (902651)..... <b>PA4390</b> <b>Cabin Air</b> (9068300218)..... <b>PA4488</b> <b>Cabin Air</b> (w/Carbon) (9068300318)..... <b>PA4336</b>	Sprinter II 318 CDI V6 w/OM642LA Eng. (04/06-on) <b>Lube</b> (5175571AA)..... <b>P7413</b> <b>Fuel</b> (w/o SP) (6460920501)..... <b>BF9846</b> <b>Fuel</b> (w/SP) (6460920701)..... <b>BF7972</b> <b>Air</b> (902651)..... <b>PA4390</b> <b>Cabin Air</b> (9068300218)..... <b>PA4488</b> <b>Cabin Air</b> (w/Carbon) (9068300318)..... <b>PA4336</b>	Sprinter II 419 CDI V6 w/OM642 DE30LA Eng. (05/09-on) <b>Lube</b> (6421800009)..... <b>P7413</b> <b>Fuel</b> (6420901652)..... <b>BF46001</b> <b>Air</b> (902651)..... <b>PA4390</b> <b>Cab Air</b> (9068300318)..... <b>PA4336</b>
Sprinter II 310 CDI w/OM651 DE22LA Eng. (05/09-on) <b>Lube</b> (6511840025)..... <b>P40001</b> <b>Fuel</b> (6420901652)..... <b>BF46001</b> <b>Air</b> (902651)..... <b>PA4390</b> <b>Cab Air</b> (9068300318)..... <b>PA4336</b>	Sprinter II 319 CDI V6 w/OM642 DE30LA Eng. (05/09-on) <b>Lube</b> (6421800009)..... <b>P7413</b> <b>Fuel</b> (6420901652)..... <b>BF46001</b> <b>Air</b> (902651)..... <b>PA4390</b> <b>Cab Air</b> (9068300318)..... <b>PA4336</b>	Sprinter II 424 V6 w/M272E35 Eng. (04/06-on) <b>Lube</b> (1121840625)..... <b>P7493</b> <b>Fuel</b> ..... <b>N/S</b> <b>Air</b> (902651)..... <b>PA4390</b> <b>Cabin Air</b> (9068300218)..... <b>PA4488</b> <b>Cabin Air</b> (w/Carbon) (9068300318)..... <b>PA4336</b>

Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Light Duty Vehicles (cont'd)	MERCEDES-BENZ European Light Duty Vehicles (cont'd)	MERCEDES-BENZ European Light Duty Vehicles (cont'd)
Sprinter II 509 CDI w/OM646LA Eng. (04/06-on) Lube (6111800009)..... P1443 Fuel (w/o SP) (6460920501)..... BF9846 Fuel (w/SP) (6460920701)..... BF7972 Air (902651)..... PA4390 Cabin Air (9068300218)..... PA4488 Cabin Air (w/Carbon) (9068300318)..... PA4336	Sprinter II 518 CDI V6 w/OM642LA Eng. (04/06-on) (Cont'd) Cabin Air (w/Carbon) (9068300318)..... PA4336	Vario 818D w/OM904.964 Eng. (09/06-on) Lube Ele. (A0001801609)..... P7199 Fuel Ele. (A0000901551)..... PF7735 Fuel Pre-filter (A0000901351)..... PF7974 Air (20949304)..... PA3843 Urea (A0001420089)..... PE5272
Sprinter II 510 CDI w/OM651 DE22LA Eng. (05/09-on) Lube (6511840025)..... P40001 Fuel (6420901652)..... BF46001 Air (902651)..... PA4390 Cab Air (9068300318)..... PA4336	Sprinter II 519 CDI V6 w/OM642 DE30LA Eng. (05/09-on) Lube (6511840025)..... P40001 Fuel (6420901652)..... BF46001 Air (902651)..... PA4390 Cab Air (9068300318)..... PA4336	Viano 2.0 CDI (639) w/109 HP OM 646 Eng. (09/03-12/06) Lube (6111800009)..... P1443 Fuel (6460920001)..... BF9846 Fuel (w/water sensor connection) (6460920201)..... BF7972 Hyd. (1402770095)..... 20048
Sprinter II 511 CDI w/OM646LA Eng. (04/06-on) Lube (6111800009)..... P1443 Fuel (w/o SP) (6460920501)..... BF9846 Fuel (w/SP) (6460920701)..... BF7972 Air (902651)..... PA4390 Cabin Air (9068300218)..... PA4488 Cabin Air (w/Carbon) (9068300318)..... PA4336	Sprinter II 524 V6 w/M272E35 Eng. (04/06-on) Lube (1121840625)..... P7493 Fuel..... N/S Air (902651)..... PA4390 Cabin Air (9068300218)..... PA4488 Cabin Air (w/Carbon) (9068300318)..... PA4336	Viano 2.0 CDI (639) w/116 HP OM 646 Eng. (09/06-08/10) Lube (6111800009)..... P1443 Fuel (6460920001)..... BF9846 Fuel (w/water sensor connection) (6460920201)..... BF7972 Hyd. (1402770095)..... 20048
Sprinter II 513 CDI w/OM646LA Eng. (04/06-on) Lube (6111800009)..... P1443 Fuel (w/o SP) (6460920501)..... BF9846 Fuel (w/SP) (6460920701)..... BF7972 Air (902651)..... PA4390 Cabin Air (9068300218)..... PA4488 Cabin Air (w/Carbon) (9068300318)..... PA4336	Vaneo 1.7 CDI w/OM668.914 Eng. (02/02-07/05) Fuel (A6110920201)..... BF7756	Viano 2.0 CDI (639) w/150 HP OM 646 Eng. (09/03-08/10) Lube (6111800009)..... P1443 Fuel (6460920001)..... BF9846 Fuel (w/water sensor connection) (6460920201)..... BF7972 Hyd. (1402770095)..... 20048
Sprinter II 513 CDI w/OM651 DE22LA Eng. (05/09-on) Lube (6511840025)..... P40001 Fuel (6420901652)..... BF46001 Air (902651)..... PA4390 Cab Air (9068300318)..... PA4336	Vario 512D w/OM602.984 Eng. (09/96-on) Lube Ele. (A6021800009)..... P7196 Fuel Spin-on (A6010900352)..... BF7619 Air (20949304)..... PA3843 Air Dryer (A0004293795)..... BA5374 +	Viano 2.0 CDI (639) w/OM 651 LA Eng. (09/10-on) Lube (6511840025)..... P40001 Fuel (6460920001)..... BF9846 Fuel (w/water sensor connection) (6460920201)..... BF7972 Hyd. (1402770095)..... 20048
Sprinter II 515 CDI w/OM646LA Eng. (04/06-on) Lube (6111800009)..... P1443 Fuel (w/o SP) (6460920501)..... BF9846 Fuel (w/SP) (6460920701)..... BF7972 Air (902651)..... PA4390 Cabin Air (9068300218)..... PA4488 Cabin Air (w/Carbon) (9068300318)..... PA4336	Vario 612D w/OM602.984, OM602.985 Eng. (09/96-on) Lube Ele. (A6021800009)..... P7196 Fuel Spin-on (A6010900352)..... BF7619 Air (20949304)..... PA3843 Air Dryer (A0004293795)..... BA5374 +	Viano 2.2 CDI (639) w/M112 Eng. (09/03-12/07) Lube (1121840625)..... P7493 Hyd. (1402770095)..... 20048
Sprinter II 515 CDI w/OM646LA Eng. (04/06-on) Lube (6111800009)..... P1443 Fuel (w/o SP) (6460920501)..... BF9846 Fuel (w/SP) (6460920701)..... BF7972 Air (902651)..... PA4390 Cabin Air (9068300218)..... PA4488 Cabin Air (w/Carbon) (9068300318)..... PA4336	Vario 614D w/OM904.908 Eng. (09/96-on) Lube Ele. (A0001801609)..... P7199 Fuel Ele. (A0000901551)..... PF7735 Fuel Pre-filter (A0000901351)..... PF7974 Air (20949304)..... PA3843 Air Dryer (A0004293795)..... BA5374 +	Viano 2.2 CDI (639) w/OM 651 LA Eng. (09/10-on) Lube (6511840025)..... P40001 Fuel (6420901652)..... BF46001 Fuel (6510900852)..... BF46037 Hyd. (1402770095)..... 20048
Sprinter II 516 CDI w/OM651 DE22LA Eng. (05/09-on) Lube (6511840025)..... P40001 Fuel (6420901652)..... BF46001 Air (902651)..... PA4390 Cab Air (9068300318)..... PA4336	Vario 812D w/OM602.944, OM602.985 Eng. (09/96-on) Lube Ele. (A6021800009)..... P7196 Fuel Spin-on (A6010900352)..... BF7619 Air (20949304)..... PA3843	Viano 3.0 (639) w/OM 642 LA Eng. (04/06-08/10) Lube (6421800009)..... P7413 Fuel (6460920001)..... BF9846 Fuel (w/water sensor connection) (6460920201)..... BF7972 Hyd. (1402770095)..... 20048
Sprinter II 518 CDI V6 w/OM642LA Eng. (04/06-on) Lube (5175571AA)..... P7413 Fuel (w/o SP) (6460920501)..... BF9846 Fuel (w/SP) (6460920701)..... BF7972 Air (902651)..... PA4390 Cabin Air (9068300218)..... PA4488	Vario 814D w/OM904.908 Eng. (09/96-on) Lube Ele. (A0001801609)..... P7199 Fuel Ele. (A0000901551)..... PF7735 Fuel Pre-filter (A0000901351)..... PF7974 Air (20949304)..... PA3843	Viano 3.0 CDI (639) w/M112.951 Eng. (09/03-12/04) Lube (1121840625)..... P7493 Hyd. (1402770095)..... 20048
	Vario 815D w/OM904.923 Eng. (09/96-on) Lube Ele. (A0001801609)..... P7199 Fuel Ele. (A0000901551)..... PF7735 Fuel Pre-filter (A0000901351)..... PF7974 Air (20949304)..... PA3843	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Light Duty Vehicles (cont'd)	MERCEDES-BENZ European Light Duty Vehicles (cont'd)	MERCEDES-BENZ European Light Duty Vehicles (cont'd)
Viano 3.0 CDI V6 (639) w/OM 642 LA Eng. (09/10-on) Lube (6421800009)..... P7413 Fuel (6460920001)..... BF9846 Fuel (w/water sensor connection) (6460920201)..... BF7972 Hyd. (1402770095)..... 20048	Vito I 112 CDI (638) w/OM611 Eng. (03/99-10/03) (Cont'd) 81.0 mm Height Air (30948204).. PA4601 Vito I 113 2.0 (638) w/OM111948E20 Eng. (11/95-10/03) Lube (1041800109)..... P1419 Fuel (24772801)..... BF1195	Vito II 120 CDI (639) w/OM642LA Eng. (04/06-on) Lube (5175571AA)..... P7413 Fuel (w/o SP) (6460920501)..... BF9846 Vito II 122 (639) w/M112 Eng. (09/03-on) Lube (1121840625)..... P7493 Vito II 122 CDI (639) w/OM 642 LA Eng. (09/10-on) Lube (6421800009)..... P7413 Fuel (6460920001)..... BF9846 Fuel (w/water sensor connection) (6460920201)..... BF7972 Hyd. (1402770095)..... 20048
Viano 3.5 (639) w/M272.972 Eng. (09/07-on) Lube (1121840625)..... P7493 Hyd. (1402770095)..... 20048	Vito I 114 2.3 (638) w/OM111978 Eng. (02/96-10/03) Lube (1041800109)..... P1419 Fuel (24772801)..... BF1195	Vito II 123 (639) w/M112E37 Eng. (09/04-on) Lube (1121840625)..... P7493 Vito II 126 CDI w/M 272 978 Eng. (09/07-on) Lube (1121840625)..... P7493 Hyd. (1402770095)..... 20048
Viano 3.7 (639) w/M112.976 Eng. (09/04-12/07) Lube (1121840625)..... P7493 Hyd. (1402770095)..... 20048	Vito II 109 CDI (639) w/CM 646 Eng. (09/06-on) Lube (6111800009)..... P1443 Fuel (6460920001)..... BF9846 Fuel (w/water sensor connection) (6460920201)..... BF7972 Hyd. (1402770095)..... 20048	<b>MERCEDES-BENZ</b> <b>European Trucks, Vans</b> Atego I 712 w/OM904LA Eng. (03/98-on) Lube..... P7199 Fuel..... PF7735 Fuel/Water Separator..... BF1391-O Radial Seal Air (30949604)..... RS5342 Cab Air (9738350147)..... PA5340 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Steering..... P106-HD
Vito I 108 CDI (638) (with Water Suction) w/OM611 Eng. (03/99-10/03) Lube (6111800009)..... P1443 Fuel (6120920001)..... BF7778 70.6 mm Height Air (30947504).. PA4600 81.0 mm Height Air (30948204).. PA4601	Vito II 109 CDI (639) w/OM646 Eng. (09/03-on) Lube (6111800009)..... P1443 Fuel (w/o SP) (6460920501)..... BF9846	Atego II 712 w/OM904LA Eng. (09/04-on) Lube..... P7199 Fuel..... PF7735 Fuel/Water Separator..... BF1391-O Radial Seal Air (30949604)..... RS5342 Cab Air (9738350147)..... PA5340 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Steering..... P106-HD
Vito I 108 CDI (638) w/OM611 Eng. (03/99-10/03) Lube (6111800009)..... P1443 Fuel (6110920201)..... BF7756 70.6 mm Height Air (30947504).. PA4600 81.0 mm Height Air (30948204).. PA4601	Vito II 110 CDI (639) w/OM 651 LA Eng. (06/10-on) Lube (6511840025)..... P40001 Fuel (6420901652)..... BF46001 Fuel (6510900852)..... BF46037 Hyd. (1402770095)..... 20048	Atego II 713 (BlueTec 4/5) w/OM904LA Eng. (09/05-on) Lube..... P7188 Fuel..... PF7735 Fuel/Water Separator..... BF1391-O Radial Seal Air (30949604)..... RS5342 Cab Air (9738350147)..... PA5340 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Steering..... P106-HD
Vito I 108D Diesel (638) w/OM601942 Eng. (01/195-10/03) Lube (6061840025)..... P7196 Fuel (10922201)..... BF7619	Vito II 111 CDI (639) w/OM 646 Eng. (09/06-on) Lube (6111800009)..... P1443 Fuel (6460920001)..... BF9846 Fuel (w/water sensor connection) (6460920201)..... BF7972 Hyd. (1402770095)..... 20048	Atego I 714 w/OM904LA Eng. (03/98-on) Lube..... P7199 Fuel..... PF7735 Fuel/Water Separator..... BF1391-O Radial Seal Air (30949604)..... RS5342 Cab Air (9738350147)..... PA5340
Vito I 110 CDI (638) (with Water Suction) w/OM611 Eng. (03/99-10/03) Lube (6111800009)..... P1443 Fuel (6120920001)..... BF7778 70.6 mm Height Air (30947504).. PA4600 81.0 mm Height Air (30948204).. PA4601	Vito II 111 CDI (639) w/OM646 Eng. (09/03-on) Lube (6111800009)..... P1443 Fuel (w/o SP) (6460920501)..... BF9846	
Vito I 110 CDI (638) w/OM611 Eng. (03/99-10/03) Lube (6111800009)..... P1443 Fuel (6110920201)..... BF7756 70.6 mm Height Air (30947504).. PA4600 81.0 mm Height Air (30948204).. PA4601	Vito II 113 CDI (639) w/OM 651 LA Eng. (09/10-on) Lube (6511840025)..... P40001 Fuel (6420901652)..... BF46001 Fuel (6510900852)..... BF46037 Hyd. (1402770095)..... 20048	
Vito I 110D (638) w/OM601970 Eng. (02/96-10/03) Lube (6021800009)..... P7196 Fuel (10922201)..... BF7619	Vito II 115 CDI (639) w/OM646 Eng. (09/03-on) Lube (6111800009)..... P1443 Fuel (w/o SP) (6460920501)..... BF9846	
Vito I 112 CDI (638) (with Water Suction) w/OM611 Eng. (03/99-10/03) Lube (6111800009)..... P1443 Fuel (6120920001)..... BF7778 70.6 mm Height Air (30947504).. PA4600 81.0 mm Height Air (30948204).. PA4601	Vito II 116 CDI (639) w/OM 651 LA Eng. (09/10-on) Lube (6511840025)..... P40001 Fuel (6420901652)..... BF46001 Fuel (6510900852)..... BF46037 Hyd. (1402770095)..... 20048	
Vito I 112 CDI (638) w/OM611 Eng. (03/99-10/03) Lube (6111800009)..... P1443 Fuel (6110920201)..... BF7756 70.6 mm Height Air (30947504).. PA4600	Vito II 119 (639) w/M112 Eng. (09/03-on) Lube (1121840625)..... P7493	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Atego I 714 w/OM904LA Eng. (03/98-on) (Cont'd) Air Dryer (Coalescer) (4295695).. BA5379 + Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Steering..... P106-HD	Atego III 721 w/OM934LA Eng. (05/13-on) Lube (A9341800009)..... P40017 Fuel/Water Separator (A9604770003)..... BF1297-O Radial Seal Air (A0040947404).. RS5342 Cab Air (A9738350147)..... PA5340 Air Dryer (A0004300969)..... BA5374 + Air Dryer (A0004295795)..... BA5379 + Steering (A0004662804)..... P106-HD Urea (A0001421089)..... PE17002 KIT	Atego I 815 w/OM904LA Eng. (03/98-on) (Cont'd) Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Steering..... P106-HD
Atego I 715 w/OM904LA Eng. (03/98-on) Lube..... P7199 Fuel..... PF7735 Fuel/Water Separator..... BF1391-O Radial Seal Air (30949604)..... RS5342 Cab Air (9738350147)..... PA5340 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Steering..... P106-HD	Atego III 723 w/OM934LA Eng. (05/13-on) Lube (A9341800009)..... P40017 Fuel/Water Separator (A9604770003)..... BF1297-O Radial Seal Air (A0040947404).. RS5342 Cab Air (A9738350147)..... PA5340 Air Dryer (A0004300969)..... BA5374 + Air Dryer (A0004295795)..... BA5379 + Steering (A0004662804)..... P106-HD Urea (A0001421089)..... PE17002 KIT	Atego II 815 w/OM904LA Eng. (09/04-on) Lube..... P7199 Fuel..... PF7735 Fuel/Water Separator..... BF1391-O Radial Seal Air (30949504)..... RS5342 Cab Air (9738350147)..... PA5340 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Steering..... P106-HD
Atego II 715 w/OM904LA Eng. (09/04-on) Lube..... P7199 Fuel..... PF7735 Fuel/Water Separator..... BF1391-O Radial Seal Air (30949604)..... RS5342 Cab Air (9738350147)..... PA5340 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Steering..... P106-HD	Atego I 812 w/OM904LA Eng. (03/98-on) Lube..... P7199 Fuel..... PF7735 Fuel/Water Separator..... BF1391-O Radial Seal Air (30949604)..... RS5342 Cab Air (9738350147)..... PA5340 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Steering..... P106-HD	Atego III 816 w/OM934LA Eng. (05/13-on) Lube (A9341800009)..... P40017 Fuel/Water Separator (A9604770003)..... BF1297-O Radial Seal Air (A0040947404).. RS5342 Cab Air (A9738350147)..... PA5340 Air Dryer (A0004300969)..... BA5374 + Air Dryer (A0004295795)..... BA5379 + Steering (A0004662804)..... P106-HD Urea (A0001421089)..... PE17002 KIT
Atego III 716 w/OM934LA Eng. (05/13-on) Lube (A9341800009)..... P40017 Fuel/Water Separator (A9604770003)..... BF1297-O Radial Seal Air (A0040947404).. RS5342 Cab Air (A9738350147)..... PA5340 Air Dryer (A0004300969)..... BA5374 + Air Dryer (A0004295795)..... BA5379 + Steering (A0004662804)..... P106-HD Urea (A0001421089)..... PE17002 KIT	Atego II 812 w/OM904LA Eng. (09/04-on) Lube..... P7199 Fuel..... PF7735 Fuel/Water Separator..... BF1391-O Radial Seal Air (30949604)..... RS5342 Cab Air (9738350147)..... PA5340 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Steering..... P106-HD	Atego II 816 (BlueTec 4/5) w/OM904LA Eng. (09/05-on) Lube..... P7188 Fuel..... PF7735 Fuel/Water Separator..... BF1391-O Radial Seal Air (30949604)..... RS5342 Cab Air (9738350147)..... PA5340 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Steering..... P106-HD
Atego I 717 w/OM904LA Eng. (03/98-on) Lube..... P7199 Fuel..... PF7735 Fuel/Water Separator..... BF1391-O Radial Seal Air (30949604)..... RS5342 Cab Air (9738350147)..... PA5340 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Steering..... P106-HD	Atego II 813 (BlueTec 4/5) w/OM904LA Eng. (09/05-on) Lube..... P7188 Fuel..... PF7735 Fuel/Water Separator..... BF1391-O Radial Seal Air (30949604)..... RS5342 Cab Air (9738350147)..... PA5340 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Steering..... P106-HD	Atego I 817 w/OM904LA Eng. (03/98-on) Lube..... P7199 Fuel..... PF7735 Fuel/Water Separator..... BF1391-O Radial Seal Air (30949604)..... RS5342 Cab Air (9738350147)..... PA5340 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Steering..... P106-HD
Atego III 718 w/OM934LA Eng. (05/13-on) Lube (A9341800009)..... P40017 Fuel/Water Separator (A9604770003)..... BF1297-O Radial Seal Air (A0040947404).. RS5342 Cab Air (A9738350147)..... PA5340 Air Dryer (A0004300969)..... BA5374 + Air Dryer (A0004295795)..... BA5379 + Steering (A0004662804)..... P106-HD Urea (A0001421089)..... PE17002 KIT	Atego I 815 w/OM904LA Eng. (03/98-on) Lube..... P7199 Fuel..... PF7735 Fuel/Water Separator..... BF1391-O Radial Seal Air (30949604)..... RS5342 Cab Air (9738350147)..... PA5340	Atego III 818 w/OM934LA Eng. (05/13-on) Lube (A9341800009)..... P40017 Fuel/Water Separator (A9604770003)..... BF1297-O Radial Seal Air (A0040947404).. RS5342 Cab Air (A9738350147)..... PA5340 Air Dryer (A0004300969)..... BA5374 + Air Dryer (A0004295795)..... BA5379 + Steering (A0004662804)..... P106-HD Urea (A0001421089)..... PE17002 KIT

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	
Atego I 818 w/OM904LA Eng. (09/00-on)	
Lube.....	P7199
Fuel.....	PF7735
Fuel/Water Separator.....	BF1391-O
Radial Seal Air (30949604).....	RS5342
Cab Air (9738350147).....	PA5340
Air Dryer (Desiccant) (Mann TB1374X).....	BA5374 +
Air Dryer (Coalescer) (4295695)..	BA5379 +
Steering.....	P106-HD
Atego II 818 w/OM904LA Eng. (09/04-on)	
Lube.....	P7199
Fuel.....	PF7735
Fuel/Water Separator.....	BF1391-O
Radial Seal Air (30949504).....	RS5342
Cab Air (9738350147).....	PA5340
Air Dryer (Desiccant) (Mann TB1374X).....	BA5374 +
Air Dryer (Coalescer) (4295695)..	BA5379 +
Steering.....	P106-HD
Atego III 821 w/OM934LA Eng. (05/13-on)	
Lube (A9341800009).....	P40017
Fuel/Water Separator (A9604770003).....	BF1297-O
Radial Seal Air (A0040947404)...	RS5342
Cab Air (A9738350147).....	PA5340
Air Dryer (A0004300969).....	BA5374 +
Air Dryer (A0004295795).....	BA5379 +
Steering (A0004662804).....	P106-HD
Urea (A0001421089).....	PE17002 KIT
Atego II 822 w/OM924LA Eng. (04/04-on)	
Lube.....	P7199
Fuel.....	PF7735
Fuel/Water Separator.....	BF1391-O
Radial Seal Air (30949504).....	RS5342
Cab Air (9738350147).....	PA5340
Air Dryer (Desiccant) (Mann TB1374X).....	BA5374 +
Air Dryer (Coalescer) (4295695)..	BA5379 +
Steering.....	P106-HD
Atego III 823 w/OM934LA Eng. (05/13-on)	
Lube (A9341800009).....	P40017
Fuel/Water Separator (A9604770003).....	BF1297-O
Radial Seal Air (A0040947404)...	RS5342
Cab Air (A9738350147).....	PA5340
Air Dryer (A0004300969).....	BA5374 +
Air Dryer (A0004295795).....	BA5379 +
Steering (A0004662804).....	P106-HD
Urea (A0001421089).....	PE17002 KIT
Atego I 823 w/OM906LA Eng. (03/98-on)	
Lube.....	P7188
Fuel.....	PF7735
Fuel/Water Separator.....	BF1391-O
Radial Seal Air (30949604).....	RS5342
Cab Air (9738350147).....	PA5340
Air Dryer (Desiccant) (Mann TB1374X).....	BA5374 +

MERCEDES-BENZ European Trucks, Vans (cont'd)	
Atego I 823 w/OM906LA Eng. (03/98-on)	
(Cont'd)	
Air Dryer (Coalescer) (4295695)..	BA5379 +
Steering.....	P106-HD
Atego II 823 w/OM906LA Eng. (09/04-on)	
Lube.....	P7188
Fuel.....	PF7735
Fuel/Water Separator.....	BF1391-O
Radial Seal Air (30949504).....	RS5342
Cab Air (9738350147).....	PA5340
Air Dryer (Desiccant) (Mann TB1374X).....	BA5374 +
Air Dryer (Coalescer) (4295695)..	BA5379 +
Steering.....	P106-HD
Atego III 824 w/OM936LA Eng. (A9361800009).....	P40003
Fuel/Water Separator (A9604770003).....	BF1297-O
Radial Seal Air (A0040947404)...	RS5342
Cab Air (A9738350147).....	PA5340
Air Dryer (A0004300969).....	BA5374 +
Air Dryer (A0004295795).....	BA5379 +
Steering (A0004662804).....	P106-HD
Urea (A0001421089).....	PE17002 KIT
Atego II 824 (BlueTec) w/OM906LA Eng. (09/05-on)	
Lube.....	P7188
Fuel.....	PF7735
Fuel/Water Separator.....	BF1391-O
Radial Seal Air (30949504).....	RS5342
Cab Air (9738350147).....	PA5340
Air Dryer (Desiccant) (Mann TB1374X).....	BA5374 +
Air Dryer (Coalescer) (4295695)..	BA5379 +
Steering.....	P106-HD
Atego I 828 F w/OM906LA Eng. (03/98-on)	
Lube.....	P7188
Fuel.....	PF7735
Fuel/Water Separator.....	BF1391-O
Radial Seal Air (30949604).....	RS5342
Cab Air (9738350147).....	PA5340
Air Dryer (Desiccant) (Mann TB1374X).....	BA5374 +
Air Dryer (Coalescer) (4295695)..	BA5379 +
Steering.....	P106-HD
Atego III 916 w/OM934LA Eng. (05/13-on)	
Lube (A9341800009).....	P40017
Fuel/Water Separator (A9604770003).....	BF1297-O
Radial Seal Air (A0040947404)...	RS5342
Cab Air (A9738350147).....	PA5340
Air Dryer (A0004300969).....	BA5374 +
Air Dryer (A0004295795).....	BA5379 +
Steering (A0004662804).....	P106-HD
Urea (A0001421089).....	PE17002 KIT

MERCEDES-BENZ European Trucks, Vans (cont'd)	
Atego II 916 (BlueTec 4/5) w/OM904LA Eng. (09/05-on)	
Lube.....	P7188
Fuel.....	PF7735
Fuel/Water Separator.....	BF1391-O
Radial Seal Air (30949604).....	RS5342
Cab Air (9738350147).....	PA5340
Air Dryer (Desiccant) (Mann TB1374X).....	BA5374 +
Air Dryer (Coalescer) (4295695)..	BA5379 +
Steering.....	P106-HD
Atego I 917 w/OM904LA Eng. (03/98-on)	
Lube.....	P7199
Fuel.....	PF7735
Fuel/Water Separator.....	BF1391-O
Radial Seal Air (30949504).....	RS5342
Cab Air (9738350147).....	PA5340
Air Dryer (Desiccant) (Mann TB1374X).....	BA5374 +
Air Dryer (Coalescer) (4295695)..	BA5379 +
Steering.....	P106-HD
Atego III 918 w/OM934LA Eng. (05/13-on)	
Lube (A9341800009).....	P40017
Fuel/Water Separator (A9604770003).....	BF1297-O
Radial Seal Air (A0040947404)...	RS5342
Cab Air (A9738350147).....	PA5340
Air Dryer (A0004300969).....	BA5374 +
Air Dryer (A0004295795).....	BA5379 +
Steering (A0004662804).....	P106-HD
Urea (A0001421089).....	PE17002 KIT
Atego I 918 w/OM904LA Eng. (09/00-on)	
Lube.....	P7199
Fuel.....	PF7735
Fuel/Water Separator.....	BF1391-O
Radial Seal Air (30949604).....	RS5342
Cab Air (9738350147).....	PA5340
Air Dryer (Desiccant) (Mann TB1374X).....	BA5374 +
Air Dryer (Coalescer) (4295695)..	BA5379 +
Steering.....	P106-HD
Atego II 918 w/OM904LA Eng. (09/04-on)	
Lube.....	P7199
Fuel.....	PF7735
Fuel/Water Separator.....	BF1391-O
Radial Seal Air (30949504).....	RS5342
Cab Air (9738350147).....	PA5340
Air Dryer (Desiccant) (Mann TB1374X).....	BA5374 +
Air Dryer (Coalescer) (4295695)..	BA5379 +
Steering.....	P106-HD
Atego III 921 w/OM934LA Eng. (05/13-on)	
Lube (A9341800009).....	P40017
Fuel/Water Separator (A9604770003).....	BF1297-O
Radial Seal Air (A0040947404)...	RS5342
Cab Air (A9738350147).....	PA5340
Air Dryer (A0004300969).....	BA5374 +

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Atego III 921 w/OM934LA Eng. (05/13-on) (Cont'd) Air Dryer (A0004295795)..... <b>BA5379 +</b> Steering (A0004662804)..... <b>P106-HD</b> Urea (A0001421089)..... <b>PE17002 KIT</b>	Atego II 924 (BlueTec 4+5) w/OM906LA Eng. (03/98-on) Lube..... <b>P7188</b> Fuel..... <b>PF7735</b> Fuel/Water Separator (w/Drain) (A0004771302)..... <b>BF1363</b> Fuel/Water Separator (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b> Radial Seal Air (30949604)..... <b>RS5342</b> Cab Air (9738350147)..... <b>PA5340</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Steering..... <b>P106-HD</b>	Atego III 1016 w/OM934LA Eng. (05/13-on) (Cont'd) Air Dryer (A0004300969)..... <b>BA5374 +</b> Air Dryer (A0004295795)..... <b>BA5379 +</b> Steering (A0004662804)..... <b>P106-HD</b> Urea (A0001421089)..... <b>PE17002 KIT</b>
Atego II 922 w/OM924LA Eng. (09/04-on) Lube..... <b>P7199</b> Fuel..... <b>PF7735</b> Fuel/Water Separator..... <b>BF1391-O</b> Radial Seal Air (30949504)..... <b>RS5342</b> Cab Air (9738350147)..... <b>PA5340</b> Air Dryer (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer (Coalescer) (4295695).. <b>BA5379 +</b> Steering..... <b>P106-HD</b>	Atego II 924 (BlueTec) w/OM906LA Eng. (09/05-on) Lube..... <b>P7188</b> Fuel..... <b>PF7735</b> Fuel/Water Separator..... <b>BF1391-O</b> Radial Seal Air (30949504)..... <b>RS5342</b> Cab Air (9738350147)..... <b>PA5340</b> Air Dryer (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer (Coalescer) (4295695).. <b>BA5379 +</b> Steering..... <b>P106-HD</b>	Atego I 1017 w/OM904LA Eng. (03/98-on) Lube..... <b>P7199</b> Fuel..... <b>PF7735</b> Fuel/Water Separator..... <b>BF1391-O</b> Radial Seal Air (30949604)..... <b>RS5342</b> Cab Air (9738350147)..... <b>PA5340</b> Air Dryer (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer (Coalescer) (4295695).. <b>BA5379 +</b> Steering..... <b>P106-HD</b>
Atego III 923 w/OM934LA Eng. (05/13-on) Lube (A9341800009)..... <b>P40017</b> Fuel/Water Separator (A9604770003)..... <b>BF1297-O</b> Radial Seal Air (A0040947404).. <b>RS5342</b> Cab Air (A9738350147)..... <b>PA5340</b> Air Dryer (A0004300969)..... <b>BA5374 +</b> Air Dryer (A0004295795)..... <b>BA5379 +</b> Steering (A0004662804)..... <b>P106-HD</b> Urea (A0001421089)..... <b>PE17002 KIT</b>	Atego I 925 w/OM906LA Eng. (03/98-on) Lube..... <b>P7188</b> Fuel..... <b>PF7735</b> Fuel/Water Separator..... <b>BF1391-O</b> Radial Seal Air (30949604)..... <b>RS5342</b> Cab Air (9738350147)..... <b>PA5340</b> Air Dryer (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer (Coalescer) (4295695).. <b>BA5379 +</b> Steering..... <b>P106-HD</b>	Atego I 1017AK w/OM904LA Eng. (03/98-on) Lube..... <b>P7199</b> Fuel..... <b>PF7735</b> Fuel/Water Separator (Fleetguard FS19737)..... <b>BF46105-O</b> Radial Seal Air (30949604)..... <b>RS5342</b> Cab Air (9738350147)..... <b>PA5340</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Steering..... <b>P106-HD</b>
Atego I 923 w/OM906LA Eng. (03/98-on) Lube..... <b>P7188</b> Fuel..... <b>PF7735</b> Fuel/Water Separator..... <b>BF1391-O</b> Radial Seal Air (30949604)..... <b>RS5342</b> Cab Air (9738350147)..... <b>PA5340</b> Air Dryer (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer (Coalescer) (4295695).. <b>BA5379 +</b> Steering..... <b>P106-HD</b>	Atego I 928 w/OM906LA Eng. (03/98-on) Lube..... <b>P7188</b> Fuel..... <b>PF7735</b> Fuel/Water Separator..... <b>BF1391-O</b> Radial Seal Air (30949604)..... <b>RS5342</b> Cab Air (9738350147)..... <b>PA5340</b> Air Dryer (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer (Coalescer) (4295695).. <b>BA5379 +</b> Steering..... <b>P106-HD</b>	Atego III 1018 w/OM934LA Eng. (05/13-on) Lube (A9341800009)..... <b>P40017</b> Fuel/Water Separator (A9604770003)..... <b>BF1297-O</b> Radial Seal Air (A0040947404).. <b>RS5342</b> Cab Air (A9738350147)..... <b>PA5340</b> Air Dryer (A0004300969)..... <b>BA5374 +</b> Air Dryer (A0004295795)..... <b>BA5379 +</b> Steering (A0004662804)..... <b>P106-HD</b> Urea (A0001421089)..... <b>PE17002 KIT</b>
Atego II 923 w/OM906LA Eng. (09/04-on) Lube..... <b>P7188</b> Fuel..... <b>PF7735</b> Fuel/Water Separator..... <b>BF1391-O</b> Radial Seal Air (30949504)..... <b>RS5342</b> Cab Air (9738350147)..... <b>PA5340</b> Air Dryer (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer (Coalescer) (4295695).. <b>BA5379 +</b> Steering..... <b>P106-HD</b>	Atego II 1015 w/OM904LA Eng. (09/04-on) Lube..... <b>P7199</b> Fuel..... <b>PF7735</b> Fuel/Water Separator..... <b>BF1391-O</b> Radial Seal Air (30949504)..... <b>RS5342</b> Cab Air (9738350147)..... <b>PA5340</b> Air Dryer (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer (Coalescer) (4295695).. <b>BA5379 +</b> Steering..... <b>P106-HD</b>	Atego I 1018 w/OM904LA Eng. (09/00-on) Lube..... <b>P7199</b> Fuel..... <b>PF7735</b> Fuel/Water Separator..... <b>BF1391-O</b> Radial Seal Air (30949604)..... <b>RS5342</b> Cab Air (9738350147)..... <b>PA5340</b> Air Dryer (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer (Coalescer) (4295695).. <b>BA5379 +</b> Steering..... <b>P106-HD</b>
Atego III 924 w/OM936LA Eng. Lube (A9361800009)..... <b>P40003</b> Fuel/Water Separator (A9604770003)..... <b>BF1297-O</b> Radial Seal Air (A0040947404).. <b>RS5342</b> Cab Air (A9738350147)..... <b>PA5340</b> Air Dryer (A0004300969)..... <b>BA5374 +</b> Air Dryer (A0004295795)..... <b>BA5379 +</b> Steering (A0004662804)..... <b>P106-HD</b> Urea (A0001421089)..... <b>PE17002 KIT</b>	Atego III 1016 w/OM934LA Eng. (05/13-on) Lube (A9341800009)..... <b>P40017</b> Fuel/Water Separator (A9604770003)..... <b>BF1297-O</b> Radial Seal Air (A0040947404).. <b>RS5342</b> Cab Air (A9738350147)..... <b>PA5340</b>	Atego II 1018 w/OM904LA Eng. (09/04-on) Lube..... <b>P7199</b> Fuel..... <b>PF7735</b> Fuel/Water Separator..... <b>BF1391-O</b> Radial Seal Air (30949504)..... <b>RS5342</b> Cab Air (9738350147)..... <b>PA5340</b> Air Dryer (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer (Coalescer) (4295695).. <b>BA5379 +</b> Steering..... <b>P106-HD</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Atego III 1021 w/OM934LA Eng. (05/13-on) Lube (A9341800009)..... P40017 Fuel/Water Separator (A9604770003)..... BF1297-O Radial Seal Air (A0040947404)... RS5342 Cab Air (A9738350147)..... PA5340 Air Dryer (A0004300969)..... BA5374 + Air Dryer (A0004295795)..... BA5379 + Steering (A0004662804)..... P106-HD Urea (A0001421089)..... PE17002 KIT	Atego III 1024 w/OM936LA Eng. (Cont'd) Steering (A0004662804)..... P106-HD Urea (A0001421089)..... PE17002 KIT Atego II 1024 (BlueTec) w/OM906LA Eng. (09/05-on) Lube..... P7188 Fuel..... PF7735 Fuel/Water Separator..... BF1391-O Radial Seal Air (30949604)..... RS5342 Cab Air (9738350147)..... PA5340 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Steering..... P106-HD	Atego III 1218 w/OM934LA Eng. (05/13-on) Lube (A9341800009)..... P40017 Fuel/Water Separator (A9604770003)..... BF1297-O Radial Seal Air (A0040947404)... RS5342 Cab Air (A9738350147)..... PA5340 Air Dryer (A0004300969)..... BA5374 + Air Dryer (A0004295795)..... BA5379 + Steering (A0004662804)..... P106-HD Urea (A0001421089)..... PE17002 KIT Atego I 1218 w/OM904LA Eng. (09/00-on) Lube..... P7199 Fuel..... PF7735 Fuel/Water Separator..... BF1391-O Radial Seal Air (30949504)..... RS5342 Cab Air (9738350147)..... PA5340 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Steering..... P106-HD
Atego II 1022 w/OM924LA Eng. (09/04-on) Lube..... P7199 Fuel..... PF7735 Fuel/Water Separator..... BF1391-O Radial Seal Air (30949604)..... RS5342 Cab Air (9738350147)..... PA5340 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Steering..... P106-HD	Atego I 1215 w/OM904LA Eng. (03/98-on) Lube..... P7199 Fuel..... PF7735 Fuel/Water Separator..... BF1391-O Radial Seal Air (30949504)..... RS5342 Cab Air (9738350147)..... PA5340 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Steering..... P106-HD	Atego II 1218 w/OM904LA Eng. (09/04-on) Lube..... P7199 Fuel..... PF7735 Fuel/Water Separator..... BF1391-O Radial Seal Air (30949604)..... RS5342 Cab Air (9738350147)..... PA5340 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Steering..... P106-HD
Atego III 1023 w/OM934LA Eng. (05/13-on) Lube (A9341800009)..... P40017 Fuel/Water Separator (A9604770003)..... BF1297-O Radial Seal Air (A0040947404)... RS5342 Cab Air (A9738350147)..... PA5340 Air Dryer (A0004300969)..... BA5374 + Air Dryer (A0004295795)..... BA5379 + Steering (A0004662804)..... P106-HD Urea (A0001421089)..... PE17002 KIT	Atego II 1215 w/OM904LA Eng. (09/04-on) Lube..... P7199 Fuel..... PF7735 Fuel/Water Separator..... BF1391-O Radial Seal Air (30949604)..... RS5342 Cab Air (9738350147)..... PA5340 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Steering..... P106-HD	Atego III 1221 w/OM934LA Eng. (05/13-on) Lube (A9341800009)..... P40017 Fuel/Water Separator (A9604770003)..... BF1297-O Radial Seal Air (A0040947404)... RS5342 Cab Air (A9738350147)..... PA5340 Air Dryer (A0004300969)..... BA5374 + Air Dryer (A0004295795)..... BA5379 + Steering (A0004662804)..... P106-HD Urea (A0001421089)..... PE17002 KIT
Atego I 1023 w/OM906LA Eng. (03/98-on) Lube..... P7188 Fuel..... PF7735 Fuel/Water Separator..... BF1391-O Radial Seal Air (30949504)..... RS5342 Cab Air (9738350147)..... PA5340 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Steering..... P106-HD	Atego III 1216 w/OM934LA Eng. (05/13-on) Lube (A9341800009)..... P40017 Fuel/Water Separator (A9604770003)..... BF1297-O Radial Seal Air (A0040947404)... RS5342 Cab Air (A9738350147)..... PA5340 Air Dryer (A0004300969)..... BA5374 + Air Dryer (A0004295795)..... BA5379 + Steering (A0004662804)..... P106-HD Urea (A0001421089)..... PE17002 KIT	Atego II 1222 w/OM924LA Eng. (09/04-on) Lube..... P7199 Fuel..... PF7735 Fuel/Water Separator..... BF1391-O Radial Seal Air (30949604)..... RS5342 Cab Air (9738350147)..... PA5340 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Steering..... P106-HD
Atego II 1023 w/OM906LA Eng. (09/04-on) Lube..... P7188 Fuel..... PF7735 Fuel/Water Separator..... BF1391-O Radial Seal Air (30949604)..... RS5342 Cab Air (9738350147)..... PA5340 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Steering..... P106-HD	Atego I 1217 w/OM904LA Eng. (03/98-on) Lube..... P7199 Fuel..... PF7735 Fuel/Water Separator..... BF1391-O Radial Seal Air (30949504)..... RS5342 Cab Air (9738350147)..... PA5340 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Steering..... P106-HD	Atego III 1223 w/OM934LA Eng. (05/13-on) Lube (A9341800009)..... P40017 Fuel/Water Separator (A9604770003)..... BF1297-O Radial Seal Air (A0040947404)... RS5342 Cab Air (A9738350147)..... PA5340 Air Dryer (A0004300969)..... BA5374 + Air Dryer (A0004295795)..... BA5379 +


+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Atego III 1223 w/OM934LA Eng. (05/13-on) (Cont'd) Steering (A0004662804)..... P106-HD Urea (A0001421089)..... PE17002 KIT	Atego II 1226 (BlueTec 4/5) w/OM906LA Eng. (09/05-on) Lube..... P7188 Fuel..... PF7735 Fuel/Water Separator..... BF1391-O Radial Seal Air (30949604)..... RS5342 Cab Air (9738350147)..... PA5340 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Steering..... P106-HD	Atego I 1317 w/OM904LA Eng. (03/98-on) (Cont'd) Air Dryer (Coalescer) (4295695).. BA5379 + Steering..... P106-HD Urea (A0001421089)..... PE17002 KIT
Atego I 1223 w/OM906LA Eng. (03/98-on) Lube..... P7188 Fuel..... PF7735 Fuel/Water Separator..... BF1391-O Radial Seal Air (30949504)..... RS5342 Cab Air (9738350147)..... PA5340 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Steering..... P106-HD	Atego III 1227 w/OM936LA Eng. Lube (A9361800009)..... P40003 Fuel/Water Separator (A9604770003)..... BF1297-O Radial Seal Air (A0040947404)... RS5342 Cab Air (A9738350147)..... PA5340 Air Dryer (A0004300969)..... BA5374 + Air Dryer (A0004295795)..... BA5379 + Steering (A0004662804)..... P106-HD Urea (A0001421089)..... PE17002 KIT	Atego I 1318 w/OM934LA Eng. (05/13-on) Lube (A9341800009)..... P40017 Fuel/Water Separator (A9604770003)..... BF1297-O Radial Seal Air (A0040947404)... RS5342 Cab Air (A9738350147)..... PA5340 Air Dryer (A0004300969)..... BA5374 + Air Dryer (A0004295795)..... BA5379 + Steering (A0004662804)..... P106-HD Urea (A0001421089)..... PE17002 KIT
Atego II 1223 w/OM906LA Eng. (09/04-on) Lube..... P7188 Fuel..... PF7735 Fuel/Water Separator..... BF1391-O Radial Seal Air (30949604)..... RS5342 Cab Air (9738350147)..... PA5340 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Steering..... P106-HD	Atego I 1228 w/OM906LA Eng. (03/98-on) Lube..... P7188 Fuel..... PF7735 Fuel/Water Separator..... BF1391-O Radial Seal Air (30949504)..... RS5342 Cab Air (9738350147)..... PA5340 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Steering..... P106-HD	Atego I 1318 w/OM904LA Eng. (09/00-on) Lube..... P7199 Fuel..... PF7735 Fuel/Water Separator..... BF1391-O Radial Seal Air (30949604)..... RS5342 Cab Air (9738350147)..... PA5340 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Steering..... P106-HD
Atego III 1224 w/OM936LA Eng. Lube (A9361800009)..... P40003 Fuel/Water Separator (A9604770003)..... BF1297-O Radial Seal Air (A0040947404)... RS5342 Cab Air (A9738350147)..... PA5340 Air Dryer (A0004300969)..... BA5374 + Air Dryer (A0004295795)..... BA5379 + Steering (A0004662804)..... P106-HD Urea (A0001421089)..... PE17002 KIT	Atego II 1228 w/OM906LA Eng. (09/04-on) Lube..... P7188 Fuel..... PF7735 Fuel/Water Separator..... BF1391-O Radial Seal Air (30949604)..... RS5342 Cab Air (9738350147)..... PA5340 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Steering..... P106-HD	Atego II 1318 w/OM904LA Eng. (09/04-on) Lube..... P7199 Fuel..... PF7735 Fuel/Water Separator..... BF1391-O Radial Seal Air (30949604)..... RS5342 Cab Air (9738350147)..... PA5340 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Steering..... P106-HD
Atego II 1224 (Blue Tec) w/OM906LA Eng. (09/05-on) Lube..... P7188 Fuel..... PF7735 Fuel/Water Separator..... BF1391-O Radial Seal Air (30949604)..... RS5342 Cab Air (9738350147)..... PA5340 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Steering..... P106-HD	Atego III 1230 w/OM936LA Eng. Lube (A9361800009)..... P40003 Fuel/Water Separator (A9604770003)..... BF1297-O Radial Seal Air (A0040947404)... RS5342 Cab Air (A9738350147)..... PA5340 Air Dryer (A0004300969)..... BA5374 + Air Dryer (A0004295795)..... BA5379 + Steering (A0004662804)..... P106-HD Urea (A0001421089)..... PE17002 KIT	Atego III 1321 w/OM934LA Eng. (05/13-on) Lube (A9341800009)..... P40017 Fuel/Water Separator (A9604770003)..... BF1297-O Radial Seal Air (A0040947404)... RS5342 Cab Air (A9738350147)..... PA5340 Air Dryer (A0004300969)..... BA5374 + Air Dryer (A0004295795)..... BA5379 + Steering (A0004662804)..... P106-HD Urea (A0001421089)..... PE17002 KIT
Atego I 1225 w/OM906LA Eng. (03/98-on) Lube..... P7188 Fuel..... PF7735 Fuel/Water Separator..... BF1391-O Radial Seal Air (30949504)..... RS5342 Cab Air (9738350147)..... PA5340 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Steering..... P106-HD	Atego I 1317 w/OM904LA Eng. (03/98-on) Lube..... P7199 Fuel..... PF7735 Fuel/Water Separator..... BF1391-O Radial Seal Air (30949504)..... RS5342 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	Atego II 1322 w/OM924LA Eng. (09/04-on) Lube..... P7199 Fuel..... PF7735 Fuel/Water Separator..... BF1391-O Radial Seal Air (30949604)..... RS5342 Cab Air (9738350147)..... PA5340 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Steering..... P106-HD

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Atego III 1323 w/OM934LA Eng. (05/13-on) Lube (A9341800009)..... P40017 Fuel/Water Separator (A9604770003)..... BF1297-O Radial Seal Air (A0040947404)... RS5342 Cab Air (A9738350147)..... PA5340 Air Dryer (A0004300969)..... BA5374 + Air Dryer (A0004295795)..... BA5379 + Steering (A0004662804)..... P106-HD Urea (A0001421089)..... PE17002 KIT	Atego I 1325 w/OM906LA Eng. (03/98-on) (Cont'd) Air Dryer (Coalescer) (4295695).. BA5379 + Steering..... P106-HD Atego II 1326 (BlueTec 4/5) w/OM906LA Eng. (09/05-on) Lube..... P7188 Fuel..... PF7735 Fuel/Water Separator..... BF1391-O Radial Seal Air (30949604)..... RS5342 Cab Air (9738350147)..... PA5340 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Steering..... P106-HD Atego III 1327 w/OM936LA Eng. Lube (A9361800009)..... P40003 Fuel/Water Separator (A9604770003)..... BF1297-O Radial Seal Air (A0040947404)... RS5342 Cab Air (A9738350147)..... PA5340 Air Dryer (A0004300969)..... BA5374 + Air Dryer (A0004295795)..... BA5379 + Steering (A0004662804)..... P106-HD Urea (A0001421089)..... PE17002 KIT Atego I 1328 w/OM906LA Eng. (03/98-on) Lube..... P7188 Fuel..... PF7735 Fuel/Water Separator..... BF1391-O Radial Seal Air (30949504)..... RS5342 Cab Air (9738350147)..... PA5340 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Steering..... P106-HD Atego III 1324 w/OM936LA Eng. Lube (A9361800009)..... P40003 Fuel/Water Separator (A9604770003)..... BF1297-O Radial Seal Air (A0040947404)... RS5342 Cab Air (A9738350147)..... PA5340 Air Dryer (A0004300969)..... BA5374 + Air Dryer (A0004295795)..... BA5379 + Steering (A0004662804)..... P106-HD Urea (A0001421089)..... PE17002 KIT Atego II 1324 (BlueTec) w/OM906LA Eng. (09/05-on) Lube..... P7188 Fuel..... PF7735 Fuel/Water Separator..... BF1391-O Radial Seal Air (30949604)..... RS5342 Cab Air (9738350147)..... PA5340 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Steering..... P106-HD Atego I 1325 w/OM906LA Eng. (03/98-on) Lube..... P7188 Fuel..... PF7735 Fuel/Water Separator..... BF1391-O Radial Seal Air (30949504)..... RS5342 Cab Air (9738350147)..... PA5340 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Steering..... P106-HD	Atego III 1330 w/OM936LA Eng. Lube (A9361800009)..... P40003 Fuel/Water Separator (A9604770003)..... BF1297-O Radial Seal Air (A0040947404)... RS5342 Cab Air (A9738350147)..... PA5340 Air Dryer (A0004300969)..... BA5374 + Air Dryer (A0004295795)..... BA5379 + Steering (A0004662804)..... P106-HD Urea (A0001421089)..... PE17002 KIT Atego I 1333 w/OM926LA Eng. (10/02-on) Lube..... P7188 Fuel..... PF7735 Fuel/Water Separator..... BF1391-O Radial Seal Air (30949504)..... RS5342 Cab Air (9738350147)..... PA5340 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Steering..... P106-HD Atego I 1517 w/OM904LA Eng. (03/98-on) Lube..... P7188 Fuel..... PF7735 Fuel/Water Separator..... BF1391-O Radial Seal Air (30949504)..... RS5342 Cab Air (9738350147)..... PA5340 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Steering..... P106-HD Atego III 1518 w/OM934LA Eng. (05/13-on) Lube (A9341800009)..... P40017 Fuel/Water Separator (A9604770003)..... BF1297-O Radial Seal Air (A0040947404)... RS5342 Cab Air (A9738350147)..... PA5340 Air Dryer (A0004300969)..... BA5374 + Air Dryer (A0004295795)..... BA5379 + Steering (A0004662804)..... P106-HD Urea (A0001421089)..... PE17002 KIT Atego I 1518 w/OM904LA Eng. (09/00-on) Lube..... P7199 Fuel..... PF7735 Fuel/Water Separator..... BF1391-O Radial Seal Air (30949504)..... RS5342 Cab Air (9738350147)..... PA5340 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Steering..... P106-HD Atego II 1518 w/OM904LA Eng. (09/04-on) Lube..... P7199 Fuel..... PF7735 Fuel/Water Separator..... BF1391-O Radial Seal Air (30949604)..... RS5342 Cab Air (9738350147)..... PA5340 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>MERCEDES-BENZ</b> <b>European Trucks, Vans (cont'd)</b>	<b>MERCEDES-BENZ</b> <b>European Trucks, Vans (cont'd)</b>	<b>MERCEDES-BENZ</b> <b>European Trucks, Vans (cont'd)</b>
Atego II 1518 w/OM904LA Eng. (09/04-on) (Cont'd) Air Dryer (Coalescer) (4295695).. <b>BA5379 +</b> Steering..... <b>P106-HD</b>	Atego III 1524 w/OM936LA Eng. Lube (A9361800009)..... <b>P40003</b> Fuel/Water Separator (A9604770003)..... <b>BF1297-O</b> Radial Seal Air (A0040947404).. <b>RS5342</b> Cab Air (A9738350147)..... <b>PA5340</b> Air Dryer (A0004300969)..... <b>BA5374 +</b> Air Dryer (A0004295795)..... <b>BA5379 +</b> Steering (A0004662804)..... <b>P106-HD</b> Urea (A0001421089)..... <b>PE17002 KIT</b>	Atego I 1528 w/OM926LA Eng. (03/98-on) (Cont'd) Air Dryer (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer (Coalescer) (4295695).. <b>BA5379 +</b> Steering..... <b>P106-HD</b>
Atego III 1521 w/OM934LA Eng. (05/13-on) Lube (A9341800009)..... <b>P40017</b> Fuel/Water Separator (A9604770003)..... <b>BF1297-O</b> Radial Seal Air (A0040947404).. <b>RS5342</b> Cab Air (A9738350147)..... <b>PA5340</b> Air Dryer (A0004300969)..... <b>BA5374 +</b> Air Dryer (A0004295795)..... <b>BA5379 +</b> Steering (A0004662804)..... <b>P106-HD</b> Urea (A0001421089)..... <b>PE17002 KIT</b>	Atego II 1524 (BlueTec) w/OM906LA Eng. (09/05-on) Lube..... <b>P7188</b> Fuel..... <b>PF7735</b> Fuel/Water Separator..... <b>BF1391-O</b> Radial Seal Air (30949604)..... <b>RS5342</b> Cab Air (9738350147)..... <b>PA5340</b> Air Dryer (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer (Coalescer) (4295695).. <b>BA5379 +</b> Steering..... <b>P106-HD</b>	Atego II 1528 w/OM906LA Eng. (09/04-on) Lube..... <b>P7188</b> Fuel..... <b>PF7735</b> Fuel/Water Separator..... <b>BF1391-O</b> Radial Seal Air (30949604)..... <b>RS5342</b> Cab Air (9738350147)..... <b>PA5340</b> Air Dryer (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer (Coalescer) (4295695).. <b>BA5379 +</b> Steering..... <b>P106-HD</b>
Atego II 1522 w/OM924LA Eng. (09/04-on) Lube..... <b>P7199</b> Fuel..... <b>PF7735</b> Fuel/Water Separator..... <b>BF1391-O</b> Radial Seal Air (30949604)..... <b>RS5342</b> Cab Air (9738350147)..... <b>PA5340</b> Air Dryer (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer (Coalescer) (4295695).. <b>BA5379 +</b> Steering..... <b>P106-HD</b>	Atego I 1525 w/OM906LA Eng. (03/98-on) Lube..... <b>P7188</b> Fuel..... <b>PF7735</b> Fuel/Water Separator..... <b>BF1391-O</b> Radial Seal Air (30949504)..... <b>RS5342</b> Cab Air (9738350147)..... <b>PA5340</b> Air Dryer (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer (Coalescer) (4295695).. <b>BA5379 +</b> Steering..... <b>P106-HD</b>	Atego II 1529 (BlueTec) w/OM906LA Eng. (09/05-on) Lube..... <b>P7188</b> Fuel..... <b>PF7735</b> Fuel/Water Separator..... <b>BF1391-O</b> Radial Seal Air (30949604)..... <b>RS5342</b> Cab Air (9738350147)..... <b>PA5340</b> Air Dryer (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer (Coalescer) (4295695).. <b>BA5379 +</b> Steering..... <b>P106-HD</b>
Atego III 1523 w/OM934LA Eng. (05/13-on) Lube (A9341800009)..... <b>P40017</b> Fuel/Water Separator (A9604770003)..... <b>BF1297-O</b> Radial Seal Air (A0040947404).. <b>RS5342</b> Cab Air (A9738350147)..... <b>PA5340</b> Air Dryer (A0004300969)..... <b>BA5374 +</b> Air Dryer (A0004295795)..... <b>BA5379 +</b> Steering (A0004662804)..... <b>P106-HD</b> Urea (A0001421089)..... <b>PE17002 KIT</b>	Atego II 1526 (BlueTec 4/5) w/OM906LA Eng. (09/05-on) Lube..... <b>P7188</b> Fuel..... <b>PF7735</b> Fuel/Water Separator..... <b>BF1391-O</b> Radial Seal Air (30949604)..... <b>RS5342</b> Cab Air (9738350147)..... <b>PA5340</b> Air Dryer (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer (Coalescer) (4295695).. <b>BA5379 +</b> Steering..... <b>P106-HD</b>	Atego II 1530 w/OM936LA Eng. Lube (A9361800009)..... <b>P40003</b> Fuel/Water Separator (A9604770003)..... <b>BF1297-O</b> Radial Seal Air (A0040947404).. <b>RS5342</b> Cab Air (A9738350147)..... <b>PA5340</b> Air Dryer (A0004300969)..... <b>BA5374 +</b> Air Dryer (A0004295795)..... <b>BA5379 +</b> Steering (A0004662804)..... <b>P106-HD</b> Urea (A0001421089)..... <b>PE17002 KIT</b>
Atego I 1523 w/OM906LA Eng. (03/98-on) Lube..... <b>P7188</b> Fuel..... <b>PF7735</b> Fuel/Water Separator..... <b>BF1391-O</b> Radial Seal Air (30949504)..... <b>RS5342</b> Cab Air (9738350147)..... <b>PA5340</b> Air Dryer (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer (Coalescer) (4295695).. <b>BA5379 +</b> Steering..... <b>P106-HD</b>	Atego III 1527 w/OM936LA Eng. Lube (A9361800009)..... <b>P40003</b> Fuel/Water Separator (A9604770003)..... <b>BF1297-O</b> Radial Seal Air (A0040947404).. <b>RS5342</b> Cab Air (A9738350147)..... <b>PA5340</b> Air Dryer (A0004300969)..... <b>BA5374 +</b> Air Dryer (A0004295795)..... <b>BA5379 +</b> Steering (A0004662804)..... <b>P106-HD</b> Urea (A0001421089)..... <b>PE17002 KIT</b>	Atego I 1533 w/OM926LA Eng. (10/02-on) Lube..... <b>P7188</b> Fuel..... <b>PF7735</b> Fuel/Water Separator..... <b>BF1391-O</b> Radial Seal Air (30949504)..... <b>RS5342</b> Cab Air (9738350147)..... <b>PA5340</b> Air Dryer (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer (Coalescer) (4295695).. <b>BA5379 +</b> Steering..... <b>P106-HD</b>
Atego II 1523 w/OM906LA Eng. (09/04-on) Lube..... <b>P7188</b> Fuel..... <b>PF7735</b> Fuel/Water Separator..... <b>BF1391-O</b> Radial Seal Air (30949604)..... <b>RS5342</b> Cab Air (9738350147)..... <b>PA5340</b> Air Dryer (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer (Coalescer) (4295695).. <b>BA5379 +</b> Steering..... <b>P106-HD</b>	Atego I 1528 w/OM926LA Eng. (03/98-on) Lube..... <b>P7188</b> Fuel..... <b>PF7735</b> Fuel/Water Separator..... <b>BF1391-O</b> Radial Seal Air (30949604)..... <b>RS5342</b> Cab Air (9738350147)..... <b>PA5340</b>	Atego II 1618 w/OM904LA (BlueTec 4/5) Eng. (03/08-on) Lube (9041800009)..... <b>P7199</b> Fuel/Water Separator (w/Drain) (A0004771302)..... <b>BF1363</b> Fuel/Water Separator (Bio Diesel) (A0004771702)..... <b>BF46105-O</b> Fuel/Water Separator (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b> Fuel Screen (A0000901351)..... <b>PF7974</b> Fuel Ele. (A0000901251)..... <b>PF7735</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Atego II 1618 w/OM904LA (BlueTec 4/5) Eng. (03/08-on) (Cont'd)	Axor II 1823 w/OM906LA Eng. (09/04-on)	Arocs 1824 w/OM936LA (BlueTec 5/6) Eng. (04/13-on)
Radial Seal Air (A0040947404)... RS5342	Lube..... P7188	Lube (A9361800009)..... P40003
Cab Air (9738350147)..... PA5340	Fuel..... PF7735	Fuel/Water Separator
Air Dryer (A0004295695)..... BA5379 +	Fuel/Water Separator..... BF1391-O	(A9604770003)..... BF1297-O
Steering (A0004660604)..... P106-HD	Pre-Fuel (924105)..... PF7939	210 mm Air (A0040947204)..... CA30105
Urea (A0001420089)..... PE5272	Radial Seal Air (30949604)..... RS5342	228 mm Air (A0040946904)..... CA30103
Atego II 1622 w/OM924LA (BlueTec 4/5) Eng. (03/08-on)	Cab Air..... PA4945	263 mm Air (A0040946804)..... CA30104
Lube (9041800009)..... P7199	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	Cab Air (A9608300018)..... PA30122
Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363	Air Dryer (Coalescer) (4295695).. BA5379 +	Cab Air (w/Carbon) (A9608300118)..... PA30123
Fuel/Water Separator (Bio Diesel) (A0004771702)..... BF46105-O	Steering..... P106-HD	Cab Air (A0008307518)..... PA5585
Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O	Econic 1823 w/OM906LA Eng. (07/98-on)	Cab Air (A9608300218)..... PA30124
Fuel Screen (A0000901351)..... PF7974	Lube..... P7188	Air Dryer (A0004295695)..... BA5379 +
Fuel Ele. (A0000901251)..... PF7735	Fuel..... PF7735	Steering (A0004660604)..... P106-HD
Radial Seal Air (A0040947404)... RS5342	Fuel/Water Separator..... BF1391-O	Urea (A0001421089)..... PE17002 KIT
Cab Air (9738350147)..... PA5340	Air..... PA3844	Axor II 1824 (BlueTec) w/OM906LA Eng. (09/05-on)
Air Dryer (A0004295695)..... BA5379 +	Radial Seal Air (30949604)..... RS5342	Lube..... P7188
Steering (A0004660604)..... P106-HD	Cab Air..... PA4945	Fuel..... PF7735
Urea (A0001420089)..... PE5272	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	Fuel/Water Separator..... BF1391-O
Atego II 1624 w/OM906LA (BlueTec 4/5) Eng. (03/08-on)	Air Dryer (Coalescer) (4295695).. BA5379 +	Pre-Fuel (924105)..... PF7939
Lube (A0001801709)..... P7188	Steering..... P106-HD	Radial Seal Air (30949604)..... RS5342
Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363	Actros II 1824 w/OM936LA (Euro 5/6) Eng. (09/12-on)	Cab Air..... PA4945
Fuel/Water Separator (Bio Diesel) (A0004771702)..... BF46105-O	Lube (A9361800009)..... P40003	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +
Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O	Fuel/Water Separator (A9604770003)..... BF1297-O	Air Dryer (Coalescer) (4295695).. BA5379 +
Fuel Screen (A0000901351)..... PF7974	210 mm Air (A0040947204)..... CA30105	Steering..... P106-HD
Fuel Ele. (A0000901251)..... PF7735	228 mm Air (A0040946904)..... CA30103	Econic 1824 w/OM906LA Eng. (09/06-on)
Radial Seal Air (A0040947404)... RS5342	263 mm Air (A0040946804)..... CA30104	Lube (A0001801709)..... P7188
Cab Air (9738350147)..... PA5340	Cab Air (A9608300018)..... PA30122	Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363
Air Dryer (A0004295695)..... BA5379 +	Cab Air (w/Carbon) (A9608300118)..... PA30123	Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O
Steering (A0004660604)..... P106-HD	Cab Air (A0008307518)..... PA5585	Fuel Screen (A0000901351)..... PF7974
Urea (A0001420089)..... PE5272	Cab Air (A9608300218)..... PA30124	Fuel Ele. (A0000901251)..... PF7735
Atego II 1629 w/OM906LA (BlueTec 4/5) Eng. (03/08-on)	Air Dryer (A0004295695)..... BA5379 +	Air (A9570940004)..... PA2500
Lube (A0001801709)..... P7188	Steering (A0004660604)..... P106-HD	Cab Air (9408350047)..... PA4945
Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363	Urea (A0001421089)..... PE17002 KIT	Air Dryer (A0004295695)..... BA5379 +
Fuel/Water Separator (Bio Diesel) (A0004771702)..... BF46105-O	Antos 1824 w/OM936LA (BlueTec 5/6) Eng. (09/12-on)	Steering (A0004660604)..... P106-HD
Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O	Lube (A9361800009)..... P40003	Urea (A0001420089)..... PE5272
Fuel Screen (A0000901351)..... PF7974	Fuel/Water Separator (A9604770003)..... BF1297-O	Axor II 1826 (BlueTec) w/OM906LA Eng. (09/05-on)
Fuel Ele. (A0000901251)..... PF7735	210 mm Air (A0040947204)..... CA30105	Lube..... P7188
Radial Seal Air (A0040947404)... RS5342	228 mm Air (A0040946904)..... CA30103	Fuel..... PF7735
Cab Air (9738350147)..... PA5340	263 mm Air (A0040946804)..... CA30104	Fuel/Water Separator..... BF1391-O
Air Dryer (A0004295695)..... BA5379 +	Cab Air (A9608300018)..... PA30122	Pre-Fuel (924105)..... PF7939
Steering (A0004660604)..... P106-HD	Cab Air (w/Carbon) (A9608300118)..... PA30123	Radial Seal Air (30949604)..... RS5342
Urea (A0001420089)..... PE5272	Cab Air (A0008307518)..... PA5585	Cab Air..... PA4945
Atego II 1823 w/OM906LA Eng. (07/98-on)	Cab Air (A9608300218)..... PA30124	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +
Lube (Mann HU945/2x)..... P7188	Air Dryer (A0004295695)..... BA5379 +	Air Dryer (Coalescer) (4295695).. BA5379 +
Fuel (Mann PU1046/1x)..... PF7735	Steering (A0004660604)..... P106-HD	Steering..... P106-HD
Fuel/Water Separator..... BF1391-O	Urea (A0001421089)..... PE17002 KIT	Atego I 1823 w/OM906LA Eng. (07/98-on)
Radial Seal Air (30949504)..... RS5342		Lube (Mann HU945/2x)..... P7188

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Atego I 1823 w/OM906LA Eng. (07/98-on) (Cont'd)	Axor II 1828 w/OM906LA Eng. (09/04-on)	Econic 1829 w/OM906LA Eng. (09/06-on) (Cont'd)
Cab Air..... PA4945	Lube..... P7188	Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O
Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	Fuel..... PF7735	Fuel Screen (A0000901351)..... PF7974
Air Dryer (Coalescer) (4295695).. BA5379 +	Fuel/Water Separator..... BF1391-O	Fuel Ele. (A0000901251)..... PF7735
Steering (11842225)..... P106-HD	Pre-Fuel (924105)..... PF7939	Air (A9570940004)..... PA2500
Actros II 1827 w/OM936LA (Euro 5/6) Eng. (09/12-on)	Radial Seal Air (30949604)..... RS5342	Cab Air (9408350047)..... PA4945
Lube (A9361800009)..... P40003	Cab Air..... PA4945	Air Dryer (A0004295695)..... BA5379 +
Fuel/Water Separator (A9604770003)..... BF1297-O	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	Steering (A0004660604)..... P106-HD
210 mm Air (A0040947204)..... CA30105	Air Dryer (Coalescer) (4295695).. BA5379 +	Urea (A0001420089)..... PE5272
228 mm Air (A0040946904)..... CA30103	Steering..... P106-HD	Actros II 1830 w/OM936LA (Euro 5/6) Eng. (09/12-on)
263 mm Air (A0040946804)..... CA30104	Econic 1828 w/OM906LA Eng. (07/98-on)	Lube (A9361800009)..... P40003
Cab Air (A9608300018)..... PA30122	Lube..... P7188	Fuel/Water Separator (A9604770003)..... BF1297-O
Cab Air (w/Carbon) (A9608300118)..... PA30123	Fuel..... PF7735	210 mm Air (A0040947204)..... CA30105
Cab Air (A0008307518)..... PA5585	Fuel/Water Separator..... BF1391-O	228 mm Air (A0040946904)..... CA30103
Cab Air (A9608300218)..... PA30124	Air..... PA3844	263 mm Air (A0040946804)..... CA30104
Air Dryer (A0004295695)..... BA5379 +	Radial Seal Air (30949604)..... RS5342	Cab Air (A9608300018)..... PA30122
Steering (A0004660604)..... P106-HD	Cab Air..... PA4945	Cab Air (w/Carbon) (A9608300118)..... PA30123
Urea (A0001421089)..... PE17002 KIT	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	Cab Air (A0008307518)..... PA5585
Antos 1827 w/OM936LA (BlueTec 5/6) Eng. (09/12-on)	Air Dryer (Coalescer) (4295695).. BA5379 +	Cab Air (A9608300218)..... PA30124
Lube (A9361800009)..... P40003	Steering..... P106-HD	Air Dryer (A0004295695)..... BA5379 +
Fuel/Water Separator (A9604770003)..... BF1297-O	Econic 1828 NTG w/M906LAG Eng. (09/02-on)	Steering (A0004660604)..... P106-HD
210 mm Air (A0040947204)..... CA30105	Lube..... P7188	Urea (A0001421089)..... PE17002 KIT
228 mm Air (A0040946904)..... CA30103	Air..... PA3844	Antos 1830 w/OM936LA (BlueTec 5/6) Eng. (09/12-on)
263 mm Air (A0040946804)..... CA30104	Radial Seal Air (30949604)..... RS5342	Lube (A9361800009)..... P40003
Cab Air (A9608300018)..... PA30122	Cab Air..... PA4945	Fuel/Water Separator (A9604770003)..... BF1297-O
Cab Air (w/Carbon) (A9608300118)..... PA30123	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	210 mm Air (A0040947204)..... CA30105
Cab Air (A0008307518)..... PA5585	Air Dryer (Coalescer) (4295695).. BA5379 +	228 mm Air (A0040946904)..... CA30103
Cab Air (A9608300218)..... PA30124	Steering..... P106-HD	263 mm Air (A0040946804)..... CA30104
Air Dryer (A0004295695)..... BA5379 +	Atego I 1828 w/OM906LA Eng. (07/98-on)	Cab Air (A9608300018)..... PA30122
Steering (A0004660604)..... P106-HD	Lube (Mann HU945/2x)..... P7188	Cab Air (w/Carbon) (A9608300118)..... PA30123
Urea (A0001421089)..... PE17002 KIT	Fuel (Mann PU1046/1x)..... PF7735	Cab Air (A0008307518)..... PA5585
Arocs 1827 w/OM936LA (BlueTec 5/6) Eng. (04/13-on)	Fuel/Water Separator..... BF1391-O	Cab Air (A9608300218)..... PA30124
Lube (A9361800009)..... P40003	Radial Seal Air (30949504)..... RS5342	Air Dryer (A0004295695)..... BA5379 +
Fuel/Water Separator (A9604770003)..... BF1297-O	Cab Air..... PA4945	Steering (A0004660604)..... P106-HD
210 mm Air (A0040947204)..... CA30105	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	Urea (A0001421089)..... PE17002 KIT
228 mm Air (A0040946904)..... CA30103	Air Dryer (Coalescer) (4295695).. BA5379 +	Arocs 1830 w/OM936LA (BlueTec 5/6) Eng. (04/13-on)
263 mm Air (A0040946804)..... CA30104	Steering (11842225)..... P106-HD	Lube (A9361800009)..... P40003
Cab Air (A9608300018)..... PA30122	Axor II 1829 (BlueTec) w/OM906LA Eng. (09/05-on)	Fuel/Water Separator (A9604770003)..... BF1297-O
Cab Air (w/Carbon) (A9608300118)..... PA30123	Lube..... P7188	210 mm Air (A0040947204)..... CA30105
Cab Air (A0008307518)..... PA5585	Fuel..... PF7735	228 mm Air (A0040946904)..... CA30103
Cab Air (A9608300218)..... PA30124	Fuel/Water Separator..... BF1391-O	263 mm Air (A0040946804)..... CA30104
Air Dryer (A0004295695)..... BA5379 +	Pre-Fuel (924105)..... PF7939	Cab Air (A9608300018)..... PA30122
Steering (A0004660604)..... P106-HD	Radial Seal Air (30949604)..... RS5342	Cab Air (w/Carbon) (A9608300118)..... PA30123
Urea (A0001421089)..... PE17002 KIT	Cab Air..... PA4945	Cab Air (A0008307518)..... PA5585
	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	Cab Air (A9608300218)..... PA30124
	Air Dryer (Coalescer) (4295695).. BA5379 +	Air Dryer (A0004295695)..... BA5379 +
	Steering..... P106-HD	Steering (A0004660604)..... P106-HD
	Econic 1829 w/OM906LA Eng. (09/06-on)	Urea (A0001421089)..... PE17002 KIT
	Lube (A0001801709)..... P7188	Arocs 1830 w/OM936LA (BlueTec 5/6) Eng. (04/13-on)
	Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363	Lube (A9361800009)..... P40003

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Arocs 1830 w/OM936LA (BlueTec 5/6) Eng. (04/13-on) (Cont'd)	Actros II 1832 w/OM501LA Eng. (02/03-on) (Cont'd)	Antos 1832 w/OM936LA (BlueTec 5/6) Eng. (09/12-on)
Urea (A0001421089)..... PE17002 KIT	Fuel/Water Separator (Open End for Bowl)..... BF1391-O	Lube (A9361800009)..... P40003
Actros I 1831 w/OM501LA Eng. (09/96-12/03)	Fuel/Water Separator (w/Drain)... BF1363	Fuel/Water Separator (A9604770003)..... BF1297-O
F-F Lube (5411800009)..... P7192	Radial Seal Air (Initial Installation) (40942404)..... RS30065 KIT	210 mm Air (A0040947204)..... CA30105
B-P Lube (21840525)..... C704-L	Radial Seal Air (Replacement Ele.) (40942404)..... RS30065	228 mm Air (A0040946904)..... CA30103
Fuel (5410920305)..... PF7761	Panel Air (A0040941104)..... PA5426	263 mm Air (A0040946804)..... CA30104
Pre-Fuel (924105)..... PF7939	38.9 mm Height Cab Air..... PA4956	Cab Air (A9608300018)..... PA30122
Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O	40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	Cab Air (w/Carbon) (A9608300118)..... PA30123
Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363	40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	Cab Air (A0008307518)..... PA5585
Radial Seal Air (A0040940204)... RS5343	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	Cab Air (A9608300218)..... PA30124
Panel Air (A0040941104)..... PA5426	Air Dryer (Coalescer) (4295695).. BA5379 +	Air Dryer (A0004295695)..... BA5379 +
261.9 mm Air (A0030949204)..... PA3838 <sup>90</sup>	Crankcase Breather (5410100080)..... CV15001	Steering (A0004660604)..... P106-HD
318.3 mm Air (A0030949104)..... PA3844	Steering..... P106-HD	Urea (A0001421089)..... PE17002 KIT
38.9 mm Height Cab Air (Mann CU3869)..... PA4956	Actros II 1832 w/OM936LA (Euro 5/6) Eng. (09/12-on)	Arocs 1832 w/OM936LA (BlueTec 5/6) Eng. (04/13-on)
40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	Lube (A9361800009)..... P40003	Lube (A9361800009)..... P40003
40.5 mm Height Cab Air (w/Charcoal) (A0008301318)..... PA5492	Fuel/Water Separator (A9604770003)..... BF1297-O	Fuel/Water Separator (A9604770003)..... BF1297-O
Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	210 mm Air (A0040947204)..... CA30105	210 mm Air (A0040947204)..... CA30105
Air Dryer (Coalescer) (4295695).. BA5379 +	228 mm Air (A0040946904)..... CA30103	228 mm Air (A0040946904)..... CA30103
Crankcase Breather (5410100080)..... CV15001	263 mm Air (A0040946804)..... CA30104	263 mm Air (A0040946804)..... CA30104
Trans. (2690321)..... PT9423	Cab Air (A9608300018)..... PA30122	Cab Air (A9608300018)..... PA30122
Steering (1902137)..... P106-HD	Cab Air (w/Carbon) (A9608300118)..... PA30123	Cab Air (w/Carbon) (A9608300118)..... PA30123
Actros II 1832 (BlueTec 4/5) w/OM501LA Eng. (02/05-on)	Cab Air (A0008307518)..... PA5585	Cab Air (A0008307518)..... PA5585
F-F Lube..... P7192	Cab Air (A9608300218)..... PA30124	Cab Air (A9608300218)..... PA30124
Pre-Fuel (924105)..... PF7939	Air Dryer (A0004295695)..... BA5379 +	Air Dryer (A0004295695)..... BA5379 +
Fuel..... PF7761	Steering (A0004660604)..... P106-HD	Steering (A0004660604)..... P106-HD
Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363	Urea (A0001421089)..... PE17002 KIT	Urea (A0001421089)..... PE17002 KIT
Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O	Actros III 1832 BlueTec 4+5 w/OM501LA Eng. (03/08-on)	Actros II 1833 w/OM470LA (Euro 5/6) Eng. (09/12-on)
338.1 mm Radial Seal Air w/Lid (Initial Installation) (40942404).... RS30065 KIT	F-F Lube..... P7192	Fuel/Water Separator (A9604770003)..... BF1297-O
322.3 mm Radial Seal Air (Replacement Ele.) (40942404)... RS30065	Fuel/Water Separator..... BF1391-O	210 mm Air (A0040947204)..... CA30105
532.6 mm Radial Seal Air (40943504)..... RS5358	P. Fuel..... PF7761	228 mm Air (A0040946904)..... CA30103
Air (w/Extra Urea Tank)..... PA3765	Pre-Fuel (924105)..... PF7939	263 mm Air (A0040946804)..... CA30104
38.9 mm Height Cab Air..... PA4956	338.1 mm Radial Seal Air w/Lid (Initial Installation) (40942404)... RS30065 KIT	Cab Air (A9608300018)..... PA30122
40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	322.3 mm Radial Seal Air (Replacement Ele.) (40942404)... RS30065	Cab Air (w/Carbon) (A9608300118)..... PA30123
40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	532.6 mm Radial Seal Air..... RS5358	Cab Air (A0008307518)..... PA5585
Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	Air (w/Extra Urea Tank)..... PA3765	Cab Air (A9608300218)..... PA30124
Air Dryer (Coalescer) (4295695).. BA5379 +	379.4 mm Cab Air..... PA4956	Air Dryer (A0004295695)..... BA5379 +
Steering..... P106-HD	381.8 mm Cab Air (w/o Charcoal) PA4912	Steering (A0004660604)..... P106-HD
Actros II 1832 w/OM501LA Eng. (02/03-on)	381.8 mm Cab Air (w/Charcoal) (A0008303418)..... PA5492	Urea (A0001421089)..... PE17002 KIT
F-F Lube..... P7192	Air Dryer (4295695)..... BA5379 +	Actros II 1833 w/OM470LA (Euro 5/6) Eng. (09/12-on)
Pre-Fuel (924105)..... PF7939	Steering..... P106-HD	Fuel/Water Separator (A9604770003)..... BF1297-O
Fuel..... PF7761	Urea (A0001420089)..... PE5272	210 mm Air (A0040947204)..... CA30105

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.


Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Antos 1833 w/OM470LA (BlueTec 5/6) Eng. (09/12-on) (Cont'd)	Eonic 1833 w/OM926LA Eng. (05/04-on)	Actros II 1835 w/OM936LA (Euro 5/6) Eng. (09/12-on)
Cab Air (A9608300218)..... PA30124	Lube..... P7188	Lube (A9361800009)..... P40003
Air Dryer (A0004295695)..... BA5379 +	Fuel..... PF7735	Fuel/Water Separator
Steering (A0004660604)..... P106-HD	Fuel/Water Separator..... BF1391-O	(A9604770003)..... BF1297-O
Urea (A0001421089)..... PE17002 KIT	Air..... PA3844	210 mm Air (A0040947204)..... CA30105
Arocs 1833 w/OM470LA (BlueTec 5/6) Eng. (04/13-on)	Radial Seal Air (30949604)..... RS5342	228 mm Air (A0040946904)..... CA30103
Fuel/Water Separator	Cab Air..... PA4945	263 mm Air (A0040946804)..... CA30104
(A9604770003)..... BF1297-O	Air Dryer (Desiccant) (Mann	Cab Air (A9608300018)..... CA30104
210 mm Air (A0040947204)..... CA30105	TB1374X)..... BA5374 +	Cab Air (w/Carbon)
228 mm Air (A0040946904)..... CA30103	Air Dryer (Coalescer) (4295695).. BA5379 +	(A9608300118)..... PA30123
263 mm Air (A0040946804)..... CA30104	Steering..... P106-HD	Cab Air (A0008307518)..... PA5585
Cab Air (A9608300018)..... PA30122	Zetros 1833 w/OM926LA Eng. (05/09-on)	Cab Air (A9608300218)..... PA30124
Cab Air (w/Carbon)	Lube (A0001801709)..... P7188	Air Dryer (A0004295695)..... BA5379 +
(A9608300118)..... PA30123	Fuel/Water Separator (w/Drain)	Steering (A0004660604)..... P106-HD
Cab Air (A0008307518)..... PA5585	(A0004771302)..... BF1363	Urea (A0001421089)..... PE17002 KIT
Cab Air (A9608300218)..... PA30124	Fuel/Water Separator (Open End	Antos 1835 w/OM936LA (BlueTec 5/6) Eng. (09/12-on)
Air Dryer (A0004295695)..... BA5379 +	for Bowl) (A0004771302)..... BF1391-O	Lube (A9361800009)..... P40003
Steering (A0004660604)..... P106-HD	Fuel Screen (A0000901351)..... PF7974	Fuel/Water Separator
Urea (A0001421089)..... PE17002 KIT	Fuel Ele. (A0000901251)..... PF7735	(A9604770003)..... BF1297-O
Atego I 1833 w/OM926LA Eng. (10/02-on)	O. Air (A0040945004)..... PA30235 +	210 mm Air (A0040947204)..... CA30105
Lube..... P7188	I. Air (3880947104)..... PA3494	228 mm Air (A0040946904)..... CA30103
Fuel..... PF7735	Cab Air (w/o Carbon)	263 mm Air (A0040946804)..... CA30104
Fuel/Water Separator..... BF1391-O	(A0008301218)..... PA4912	Cab Air (A9608300018)..... PA30122
Radial Seal Air (30949504)..... RS5342	Cab Air (w/Carbon)	Cab Air (w/Carbon)
Cab Air..... PA4945	(A0008301318)..... PA5492	(A9608300118)..... PA30123
Air Dryer (Desiccant) (Mann	Air Dryer (Desiccant Vers.)	Cab Air (A0008307518)..... PA5585
TB1374X)..... BA5374 +	(4291097)..... BA5374 +	Cab Air (A9608300218)..... PA30124
Air Dryer (Coalescer) (4295695).. BA5379 +	Air Dryer (Coalescer Vers.)	Air Dryer (A0004295695)..... BA5379 +
Steering..... P106-HD	(A0004295695)..... BA5379 +	Steering (A0004660604)..... P106-HD
Axor II 1833 (BlueTec) w/OM926LA Eng. (09/05-on)	Steering (A0004660604)..... P106-HD	Urea (A0001421089)..... PE17002 KIT
Lube..... P7188	Urea (A0001420089)..... PE5272	Arocs 1835 w/OM936LA (BlueTec 5/6) Eng. (04/13-on)
Fuel..... PF7735	Actros I 1835 w/OM501LA Eng. (09/96-12/03)	Lube (A9361800009)..... P40003
Fuel/Water Separator..... BF1391-O	F-F Lube..... P7192	Fuel/Water Separator
Pre-Fuel (924105)..... PF7939	B-P Lube (21840525)..... C704-L	(A9604770003)..... BF1297-O
Radial Seal Air (30949604)..... RS5342	Pre-Fuel (924105)..... PF7939	210 mm Air (A0040947204)..... CA30105
Cab Air..... PA4945	Fuel..... PF7761	228 mm Air (A0040946904)..... CA30103
Air Dryer (Desiccant) (Mann	Fuel/Water Separator (Open End	263 mm Air (A0040946804)..... CA30104
TB1374X)..... BA5374 +	for Bowl) (A0004771302)..... BF1391-O	Cab Air (A9608300018)..... PA30122
Air Dryer (Coalescer) (4295695).. BA5379 +	Fuel/Water Separator (w/Drain)	Cab Air (w/Carbon)
Steering..... P106-HD	(A0004771302)..... BF1363	(A9608300118)..... PA30123
Axor II 1833 w/OM926LA Eng. (09/04-on)	261.9 mm Air..... PA3838 <sup>90</sup>	Cab Air (A0008307518)..... PA5585
Lube..... P7188	318.3 mm Air..... PA3844	Cab Air (A9608300218)..... PA30124
Fuel..... PF7735	496.9 mm Air..... PA2475	Air Dryer (A0004295695)..... BA5379 +
Fuel/Water Separator..... BF1391-O	Radial Seal Air (A0040940204).. RS5343	Steering (A0004660604)..... P106-HD
Pre-Fuel (924105)..... PF7939	Panel Air (A0040941104)..... PA5426	Urea (A0001421089)..... PE17002 KIT
Radial Seal Air (30949604)..... RS5342	38.9 mm Height Cab Air..... PA4956	Axor I 1835 w/OM457LA Eng. (10/01-12/04)
Cab Air..... PA4945	40.5 mm Height Cab Air (w/o	Lube..... P7230
Air Dryer (Desiccant) (Mann	Charcoal)..... PA4912	Fuel..... PF7761
TB1374X)..... BA5374 +	40.5 mm Height Cab Air	Fuel/Water Separator..... BF1391-O
Air Dryer (Coalescer) (4295695).. BA5379 +	(w/Charcoal) (A0008303418)..... PA5492	Pre-Fuel (924105)..... PF7939
Steering..... P106-HD	Air Dryer (Desiccant) (Mann	261.9 mm Air (10/01-03/03)..... PA3838 <sup>90</sup>
	TB1374X)..... BA5374 +	318.3 mm Air (10/01-03/03)..... PA3844
	Air Dryer (Coalescer) (4295695).. BA5379 +	Cab Air..... PA4945
	Crankcase Breather	Air Dryer (Desiccant) (Mann
	(5410100080)..... CV15001	TB1374X)..... BA5374 +
	Trans. (2690321)..... PT9423	
	Steering..... P106-HD	

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Axor I 1835 w/OM457LA Eng. (10/01-12/04) (Cont'd)	Arocs 1836 w/OM470LA (BlueTec 5/6) Eng. (04/13-on) (Cont'd)	Actros III 1836 BlueTec 4+5 w/OM501LA Eng. (03/08-on) (Cont'd)
Air Dryer (Coalescer) (4295695).. BA5379 +	Cab Air (A0008307518)..... PA5585	Pre-Fuel (924105)..... PF7939
Steering..... P106-HD	Cab Air (A9608300218)..... PA30124	338.1 mm Radial Seal Air w/Lid (Initial Installation) (40942404)... RS30065 KIT
Axor II 1835 w/OM457LA Eng. (09/04-on)	Air Dryer (A0004295695)..... BA5379 +	322.3 mm Radial Seal Air (Replacement Ele.) (40942404)... RS30065
Lube..... P7230	Steering (A0004660604)..... P106-HD	532.6 mm Radial Seal Air..... RS5358
Fuel..... PF7761	Urea (A0001421089)..... PE17002 KIT	Air (w/Extra Urea Tank)..... PA3765
Fuel/Water Separator..... BF1391-O	Actros II 1836 (BlueTec 4/5) w/Mercedes OM501LA Eng. (02/05-on)	379.4 mm Cab Air..... PA4956
Pre-Fuel (924105)..... PF7939	F-F Lube..... P7192	381.8 mm Cab Air (w/o Charcoal) PA4912
Radial Seal Air (Initial Installation) (40942404)..... RS30065 KIT	Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O	381.8 mm Cab Air (w/Charcoal) (A0008303418)..... PA5492
Radial Seal Air (Replacement Ele.) (40942404)..... RS30065	Pre-Fuel (924105)..... PF7939	Air Dryer (4295695)..... BA5379 +
Cab Air..... PA4945	Fuel..... PF7761	Steering..... P106-HD
Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363	Urea (A0001420089)..... PE5272
Air Dryer (Coalescer) (4295695).. BA5379 +	338.1 mm Radial Seal Air w/Lid (Initial Installation) (40942404)... RS30065 KIT	Actros II 1839 w/OM470LA (Euro 5/6) Eng. (09/12-on)
Steering..... P106-HD	322.3 mm Radial Seal Air (Replacement Ele.) (40942404)... RS30065	Fuel/Water Separator (A9604770003)..... BF1297-O
Actros II 1836 w/OM470LA (Euro 5/6) Eng. (09/12-on)	Air (w/Extra Urea Tank)..... PA3765	210 mm Air (A0040947204)..... CA30105
Fuel/Water Separator (A9604770003)..... BF1297-O	532.6 mm Radial Seal Air (40943504)..... RS5358	228 mm Air (A0040946904)..... CA30103
210 mm Air (A0040947204)..... CA30105	38.9 mm Height Cab Air..... PA4956	263 mm Air (A0040946804)..... CA30104
228 mm Air (A0040946904)..... CA30103	40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	Cab Air (A9608300018)..... PA30122
263 mm Air (A0040946804)..... CA30104	40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	Cab Air (w/Carbon) (A9608300118)..... PA30123
Cab Air (A9608300018)..... PA30122	Air Dryer (Mann TB1374X)..... BA5374 +	Cab Air (A0008307518)..... PA5585
Cab Air (w/Carbon) (A9608300118)..... PA30123	Steering..... P106-HD	Cab Air (A9608300218)..... PA30124
Cab Air (A0008307518)..... PA5585	Actros II 1836 w/Mercedes OM501LA Eng. (02/03-on)	Air Dryer (A0004295695)..... BA5379 +
Cab Air (A9608300218)..... PA30124	F-F Lube..... P7192	Steering (A0004660604)..... P106-HD
Air Dryer (A0004295695)..... BA5379 +	Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363	Urea (A0001421089)..... PE17002 KIT
Steering (A0004660604)..... P106-HD	Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O	Antos 1839 w/OM470LA (BlueTec 5/6) Eng. (09/12-on)
Urea (A0001421089)..... PE17002 KIT	Pre-Fuel (924105)..... PF7939	Fuel/Water Separator (A9604770003)..... BF1297-O
Antos 1836 w/OM470LA (BlueTec 5/6) Eng. (09/12-on)	Fuel..... PF7761	210 mm Air (A0040947204)..... CA30105
Fuel/Water Separator (A9604770003)..... BF1297-O	338.1 mm Radial Seal Air w/Lid (Initial Installation) (40942404)... RS30065 KIT	228 mm Air (A0040946904)..... CA30103
210 mm Air (A0040947204)..... CA30105	322.3 mm Radial Seal Air (Replacement Ele.) (40942404)... RS30065	263 mm Air (A0040946804)..... CA30104
228 mm Air (A0040946904)..... CA30103	532.6 mm Radial Seal Air (40943504)..... RS5358	Cab Air (A9608300018)..... PA30122
263 mm Air (A0040946804)..... CA30104	38.9 mm Height Cab Air..... PA4956	Cab Air (w/Carbon) (A9608300118)..... PA30123
Cab Air (A9608300018)..... PA30122	40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	Cab Air (A0008307518)..... PA5585
Cab Air (w/Carbon) (A9608300118)..... PA30123	40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	Cab Air (A9608300218)..... PA30124
Cab Air (A0008307518)..... PA5585	Air Dryer (Mann TB1374X)..... BA5374 +	Air Dryer (A0004295695)..... BA5379 +
Cab Air (A9608300218)..... PA30124	Breather (5410100080)..... CV15001	Steering (A0004660604)..... P106-HD
Air Dryer (A0004295695)..... BA5379 +	Steering..... P106-HD	Urea (A0001421089)..... PE17002 KIT
Steering (A0004660604)..... P106-HD	Actros III 1836 BlueTec 4+5 w/OM501LA Eng. (03/08-on)	Arocs 1839 w/OM470LA (BlueTec 5/6) Eng. (04/13-on)
Urea (A0001421089)..... PE17002 KIT	F-F Lube..... P7192	Fuel/Water Separator (A9604770003)..... BF1297-O
Arocs 1836 w/OM470LA (BlueTec 5/6) Eng. (04/13-on)	Fuel/Water Separator..... BF1391-O	210 mm Air (A0040947204)..... CA30105
Fuel/Water Separator (A9604770003)..... BF1297-O	P. Fuel..... PF7761	228 mm Air (A0040946904)..... CA30103
210 mm Air (A0040947204)..... CA30105	Actros III 1836 BlueTec 4+5 w/OM501LA Eng. (03/08-on)	263 mm Air (A0040946804)..... CA30104
228 mm Air (A0040946904)..... CA30103	F-F Lube..... P7192	Cab Air (A9608300018)..... PA30122
263 mm Air (A0040946804)..... CA30104	Fuel/Water Separator..... BF1391-O	Cab Air (w/Carbon) (A9608300118)..... PA30123
Cab Air (A9608300018)..... PA30122	P. Fuel..... PF7761	Cab Air (A0008307518)..... PA5585
Cab Air (w/Carbon) (A9608300118)..... PA30123		Cab Air (A9608300218)..... PA30124


\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Arocs 1839 w/OM470LA (BlueTec 5/6) Eng. (04/13-on) (Cont'd) Air Dryer (A0004295695)..... <b>BA5379 +</b> Steering (A0004660604)..... <b>P106-HD</b> Urea (A0001421089)..... <b>PE17002 KIT</b>	Actros I 1840 w/OM501LA Eng. (09/96-12/03) (Cont'd) Fuel/Water Separator (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b> Radial Seal Air (40940204)..... <b>RS5343</b> 261.9 mm Air (A0030949204)..... <b>PA3838<sup>90</sup></b> 318.3 mm Air (A0030949104)..... <b>PA3844</b> Panel Air (A0040941104)..... <b>PA5426</b> 38.9 mm Height Cab Air (Mann CU3869)..... <b>PA4956</b> 40.5 mm Height Cab Air (w/o Charcoal)..... <b>PA4912</b> 40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... <b>PA5492</b> Air Dryer (Coalescer) (4295695).. <b>BA5379 +</b> Air Dryer (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> Crankcase Breather (5410100080)..... <b>CV15001</b> Trans. (2690321)..... <b>PT9423</b> Steering..... <b>P106-HD</b>	Actros II 1841 (BlueTec 4 /5) w/OM501LA Eng. (02/05-on) F-F Lube..... <b>P7192</b> Fuel/Water Separator (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b> Pre-Fuel (924105)..... <b>PF7939</b> Fuel..... <b>PF7761</b> Fuel/Water Separator (Open End for Bowl)..... <b>BF1391-O</b> Fuel/Water Separator (w/Drain) (A0004771302)..... <b>BF1363</b> 338.1 mm Radial Seal Air w/Lid (Initial Installation) (40942404)... <b>RS30065 KIT</b> 322.3 mm Radial Seal Air (Replacement Ele.) (40942404)... <b>RS30065</b> 532.6 mm Radial Seal Air (40943504)..... <b>RS5358</b> Air (w/Extra Urea Tank)..... <b>PA3765</b> 38.9 mm Height Cab Air..... <b>PA4956</b> 40.5 mm Height Cab Air (w/o Charcoal)..... <b>PA4912</b> 40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... <b>PA5492</b> Air Dryer (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer (Coalescer) (4295695).. <b>BA5379 +</b> Steering..... <b>P106-HD</b>
Actros II MP4 1840 w/OM470LA (BlueTec 5/6) Eng. (09/12-on) Fuel/Water Separator (A9604770003)..... <b>BF1297-O</b> 210 mm Air (A0040947204)..... <b>CA30105</b> 228 mm Air (A0040946904)..... <b>CA30103</b> 263 mm Air (A0040946804)..... <b>CA30104</b> Cab Air (A9608300018)..... <b>PA30122</b> Cab Air (w/Carbon) (A9608300118)..... <b>PA30123</b> Cab Air (A0008307518)..... <b>PA5585</b> Cab Air (A9608300218)..... <b>PA30124</b> Air Dryer (A0004295695)..... <b>BA5379 +</b> Steering (A0004660604)..... <b>P106-HD</b> Urea (A0001421089)..... <b>PE17002 KIT</b>	Axor I 1840 w/OM457LA Eng. (10/01-12/04) Lube..... <b>P7230</b> Fuel..... <b>PF7761</b> Fuel/Water Separator..... <b>BF1391-O</b> Pre-Fuel (924105)..... <b>PF7939</b> 261.9 mm Air (10/01-03/03)..... <b>PA3838<sup>90</sup></b> 318.3 mm Air (10/01-03/03)..... <b>PA3844</b> Cab Air..... <b>PA4945</b> Air Dryer (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer (Coalescer) (4295695).. <b>BA5379 +</b> Steering..... <b>P106-HD</b>	Actros II 1841 w/OM501LA Eng. (02/03-on) F-F Lube..... <b>P7192</b> Fuel/Water Separator (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b> Pre-Fuel (924105)..... <b>PF7939</b> Fuel..... <b>PF7761</b> Fuel/Water Separator (w/Drain) (A0004771302)..... <b>BF1363</b> Radial Seal Air (Initial Installation) (40942404)..... <b>RS30065 KIT</b> Radial Seal Air (Replacement Ele.) (40942404)..... <b>RS30065</b> 38.9 mm Height Cab Air..... <b>PA4956</b> 40.5 mm Height Cab Air (w/o Charcoal)..... <b>PA4912</b> 40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... <b>PA5492</b> Air Dryer (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer (Coalescer) (4295695).. <b>BA5379 +</b> Crankcase Breather (5410100080)..... <b>CV15001</b> Steering..... <b>P106-HD</b>
Arocs 1840 w/OM470LA (BlueTec 5/6) Eng. (04/13-on) Fuel/Water Separator (A9604770003)..... <b>BF1297-O</b> 210 mm Air (A0040947204)..... <b>CA30105</b> 228 mm Air (A0040946904)..... <b>CA30103</b> 263 mm Air (A0040946804)..... <b>CA30104</b> Cab Air (A9608300018)..... <b>PA30122</b> Cab Air (w/Carbon) (A9608300118)..... <b>PA30123</b> Cab Air (A0008307518)..... <b>PA5585</b> Cab Air (A9608300218)..... <b>PA30124</b> Air Dryer (A0004295695)..... <b>BA5379 +</b> Steering (A0004660604)..... <b>P106-HD</b> Urea (A0001421089)..... <b>PE17002 KIT</b>	Axor II 1840 w/OM457LA Eng. (09/04-on) Lube..... <b>P7230</b> Fuel..... <b>PF7761</b> Fuel/Water Separator..... <b>BF1391-O</b> Pre-Fuel (924105)..... <b>PF7939</b> Radial Seal Air (Initial Installation) (40942404)..... <b>RS30065 KIT</b> Radial Seal Air (Replacement Ele.) (40942404)..... <b>RS30065</b> Cab Air..... <b>PA4945</b> Air Dryer (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer (Coalescer) (4295695).. <b>BA5379 +</b> Steering..... <b>P106-HD</b>	Actros II 1841 w/OM501LA Eng. (02/03-on) F-F Lube..... <b>P7192</b> Fuel/Water Separator (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b> Pre-Fuel (924105)..... <b>PF7939</b> Fuel..... <b>PF7761</b> Fuel/Water Separator (w/Drain) (A0004771302)..... <b>BF1363</b> Radial Seal Air (Initial Installation) (40942404)..... <b>RS30065 KIT</b> Radial Seal Air (Replacement Ele.) (40942404)..... <b>RS30065</b> 38.9 mm Height Cab Air..... <b>PA4956</b> 40.5 mm Height Cab Air (w/o Charcoal)..... <b>PA4912</b> 40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... <b>PA5492</b> Air Dryer (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer (Coalescer) (4295695).. <b>BA5379 +</b> Crankcase Breather (5410100080)..... <b>CV15001</b> Steering..... <b>P106-HD</b>
Antos 1840 w/OM470LA (BlueTec 5/6) Eng. (09/12-on) Fuel/Water Separator (A9604770003)..... <b>BF1297-O</b> 210 mm Air (A0040947204)..... <b>CA30105</b> 228 mm Air (A0040946904)..... <b>CA30103</b> 263 mm Air (A0040946804)..... <b>CA30104</b> Cab Air (A9608300018)..... <b>PA30122</b> Cab Air (w/Carbon) (A9608300118)..... <b>PA30123</b> Cab Air (A0008307518)..... <b>PA5585</b> Cab Air (A9608300218)..... <b>PA30124</b> Air Dryer (A0004295695)..... <b>BA5379 +</b> Steering (A0004660604)..... <b>P106-HD</b> Urea (A0001421089)..... <b>PE17002 KIT</b>	Axor I 1840LS w/OM457LA Eng. (10/01-03/03) Lube..... <b>P7230</b> Fuel..... <b>PF7761</b> Fuel/Water Separator..... <b>BF1363</b> 261.9 mm Air..... <b>PA3838<sup>90</sup></b> 318.3 mm Air..... <b>PA3844</b> Cab Air..... <b>PA4945</b> Air Dryer (Mann TB1374x)..... <b>BA5374 +</b> Steering..... <b>P106-HD</b>	Actros III 1841 BlueTec 4+5 w/OM501LA Eng. (03/08-on) F-F Lube..... <b>P7192</b> Fuel/Water Separator..... <b>BF1391-O</b> P. Fuel..... <b>PF7761</b> Pre-Fuel (924105)..... <b>PF7939</b> 338.1 mm Radial Seal Air w/Lid (Initial Installation) (40942404)... <b>RS30065 KIT</b>

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Actros III 1841 BlueTec 4+5 w/OM501LA Eng. (03/08-on) (Cont'd)	Arocs 1842 w/OM471LA (BlueTec 5/6) Eng. (04/13-on) (Cont'd)	Arocs 1843 w/OM470LA (BlueTec 5/6) Eng. (04/13-on) (Cont'd)
322.3 mm Radial Seal Air (Replacement Ele.) (40942404)... RS30065	210 mm Air (A0040947204)..... CA30105	Urea (A0001421089)..... PE17002 KIT
532.6 mm Radial Seal Air..... RS5358	228 mm Air (A0040946904)..... CA30103	Actros I 1843 w/OM501LA Eng. (09/96-12/03)
Air (w/Extra Urea Tank)..... PA3765	263 mm Air (A0040946804)..... CA30104	F-F Lube (5411800009)..... P7192
379.4 mm Cab Air..... PA4956	Cab Air (A9608300018)..... PA30122	B-P Lube (21840525)..... C704-L
381.8 mm Cab Air (w/o Charcoal) PA4912	Cab Air (w/Carbon) (A9608300118)..... PA30123	Pre-Fuel (924105)..... PF7939
381.8 mm Cab Air (w/Charcoal) (A0008303418)..... PA5492	Cab Air (A0008307518)..... PA5585	Fuel (5410920305)..... PF7761
Air Dryer (4295695)..... BA5379 +	Cab Air (A9608300218)..... PA30124	Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363
Steering..... P106-HD	Air Dryer (A0004295695)..... BA5379 +	Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O
Urea (A0001420089)..... PE5272	Coolant (A4722030255)..... P5092	261.9 mm Air (A0030949204)..... PA3838 <sup>90</sup>
Actros II 1842 w/OM471LA (Euro 5/6) Eng. (09/11-on)	Steering (A0004660604)..... P106-HD	318.3 mm Air (A0030949104)..... PA3844
Lube (A4721800309)..... P7505	Urea (A0001421089)..... PE17002 KIT	496.9 mm Air (10947904)..... PA2475
Fuel/Water Separator (A9604770003)..... BF1297-O	Actros II 1843 w/OM470LA (Euro 5/6) Eng. (09/12-on)	Radial Seal Air (A0040940204)..... RS5343
Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT	Fuel/Water Separator (A9604770003)..... BF1297-O	Panel Air (A0040941104)..... PA5426
210 mm Air (A0040947204)..... CA30105	210 mm Air (A0040947204)..... CA30105	38.9 mm Height Cab Air (Mann CU3869)..... PA4956
228 mm Air (A0040946904)..... CA30103	228 mm Air (A0040946904)..... CA30103	40.5 mm Height Cab Air (w/o Charcoal)..... PA4912
263 mm Air (A0040946804)..... CA30104	263 mm Air (A0040946804)..... CA30104	40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492
Cab Air (A9608300018)..... PA30122	Cab Air (A9608300018)..... PA30122	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +
Cab Air (w/Carbon) (A9608300118)..... PA30123	Cab Air (w/Carbon) (A9608300118)..... PA30123	Air Dryer (Coalescer) (4295695)..... BA5379 +
Cab Air (A0008307518)..... PA5585	Cab Air (A0008307518)..... PA5585	Crankcase Breather (5410100080)..... CV15001
Cab Air (A9608300218)..... PA30124	Cab Air (A9608300218)..... PA30124	Trans. (2690321)..... PT9423
Air Dryer (A0004295695)..... BA5379 +	Air Dryer (A0004295695)..... BA5379 +	Steering..... P106-HD
Coolant (A4722030255)..... P5092	Steering (A0004660604)..... P106-HD	Axor I 1843 w/OM457LA Eng. (10/01-12/04)
Steering (A0004660604)..... P106-HD	Urea (A0001421089)..... PE17002 KIT	Lube..... P7230
Urea (A0001421089)..... PE17002 KIT	Antos 1843 w/OM470LA (BlueTec 5/6) Eng. (09/12-on)	Fuel..... PF7761
Antos 1842 w/OM471LA (BlueTec 5/6) Eng. (09/12-on)	Fuel/Water Separator (A9604770003)..... BF1297-O	Fuel/Water Separator..... BF1391-O
Lube (A4721800309)..... P7505	210 mm Air (A0040947204)..... CA30105	Pre-Fuel (924105)..... PF7939
Fuel/Water Separator (A9604770003)..... BF1297-O	228 mm Air (A0040946904)..... CA30103	261.9 mm Air..... PA3838 <sup>90</sup>
Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT	263 mm Air (A0040946804)..... CA30104	318.3 mm Air..... PA3844
210 mm Air (A0040947204)..... CA30105	Cab Air (A9608300018)..... PA30122	Cab Air..... PA4945
228 mm Air (A0040946904)..... CA30103	Cab Air (w/Carbon) (A9608300118)..... PA30123	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +
263 mm Air (A0040946804)..... CA30104	Cab Air (A0008307518)..... PA5585	Air Dryer (Coalescer) (4295695)..... BA5379 +
Cab Air (A9608300018)..... PA30122	Cab Air (A9608300218)..... PA30124	Steering..... P106-HD
Cab Air (w/Carbon) (A9608300118)..... PA30123	Air Dryer (A0004295695)..... BA5379 +	Axor II 1843 w/OM457LA Eng. (09/04-on)
Cab Air (A0008307518)..... PA5585	Steering (A0004660604)..... P106-HD	Lube..... P7230
Cab Air (A9608300218)..... PA30124	Urea (A0001421089)..... PE17002 KIT	Fuel..... PF7761
Air Dryer (A0004295695)..... BA5379 +	Arocs 1843 w/OM470LA (BlueTec 5/6) Eng. (04/13-on)	Fuel/Water Separator..... BF1391-O
Coolant (A4722030255)..... P5092	Fuel/Water Separator (A9604770003)..... BF1297-O	Pre-Fuel (924105)..... PF7939
Steering (A0004660604)..... P106-HD	210 mm Air (A0040947204)..... CA30105	Radial Seal Air (Initial Installation) (40942404)..... RS30065 KIT
Urea (A0001421089)..... PE17002 KIT	228 mm Air (A0040946904)..... CA30103	Radial Seal Air (Replacement Ele.) (40942404)..... RS30065
Arocs 1842 w/OM471LA (BlueTec 5/6) Eng. (04/13-on)	263 mm Air (A0040946804)..... CA30104	Cab Air..... PA4945
Lube (A4721800309)..... P7505	Cab Air (A9608300018)..... PA30122	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +
Fuel/Water Separator (A9604770003)..... BF1297-O	Cab Air (w/Carbon) (A9608300118)..... PA30123	Air Dryer (Coalescer) (4295695)..... BA5379 +
Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT	Cab Air (A0008307518)..... PA5585	Steering..... P106-HD
Arocs 1842 w/OM471LA (BlueTec 5/6) Eng. (04/13-on)	Cab Air (A9608300218)..... PA30124	
Lube (A4721800309)..... P7505	Air Dryer (A0004295695)..... BA5379 +	
Fuel/Water Separator (A9604770003)..... BF1297-O	Steering (A0004660604)..... P106-HD	
Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT		

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.


Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Axor I 1843LS w/OM457LA Eng. (10/01-12/04)	Actros III 1844 BlueTec 4+5 w/OM501LA Eng. (03/08-on)	Actros II 1844LS w/OM501LA Eng. (04/03-on)
Lube..... P7230	F-F Lube..... P7192	F-F Lube..... P7192
Fuel..... PF7761	Fuel..... PF7761	Fuel..... PF7761
<b>Fuel/Water Separator</b> (Fleetguard FS19737)..... BF46105-O	<b>Fuel/Water Separator</b> ..... BF1391-O	<b>Fuel/Water Separator</b> (Fleetguard FS19737)..... BF46105-O
261.9 mm Air..... PA3838 <sup>90</sup>	P. Fuel..... PF7761	<b>Radial Seal Air (Initial Installation)</b> (40942404)..... RS30065 KIT
318.3 mm Air..... PA3844	Pre-Fuel (924105)..... PF7939	<b>Radial Seal Air (Replacement</b> <b>Ele.)</b> (40942404)..... RS30065
Cab Air..... PA4945	322.3 mm Radial Seal Air (Replacement Ele.) (40942404)..... RS30065	Ele.) (40942404)..... RS30065
Air Dryer (Mann TB1374X)..... BA5374 +	532.6 mm Radial Seal Air..... RS5358	38.9 mm Height Cab Air..... PA4956
Steering..... P106-HD	Air (w/Extra Urea Tank)..... PA3765	40.5 mm Height Cab Air (w/o Charcoal)..... PA4912
Actros II 1844 (BlueTec 4/5) w/OM501LA Eng. (02/05-on)	338.1 mm Radial Seal Air w/Lid (Initial Installation) (40942404)..... RS30065 KIT	40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492
F-F Lube..... P7192	379.4 mm Cab Air..... PA4956	Air Dryer (Desiccant) (Mann TB1374x)..... BA5374 +
Pre-Fuel (924105)..... PF7939	381.8 mm Cab Air (w/o Charcoal) ..... PA4912	Air Dryer (Coalescer) (4295695)..... BA5379 +
Fuel..... PF7761	381.8 mm Cab Air (w/Charcoal) (A0008303418)..... PA5492	Steering..... P106-HD
<b>Fuel/Water Separator</b> (Open End for Bowl)..... BF1391-O	Air Dryer (4295695)..... BA5379 +	Actros II 1844L w/OM501LA Eng. (04/03-on)
<b>Fuel/Water Separator</b> (w/Drain) (A0004771302)..... BF1363	Steering..... P106-HD	F-F Lube..... P7192
338.1 mm Radial Seal Air w/Lid (Initial Installation) (40942404)..... RS30065 KIT	Urea (A0001420089)..... PE5272	Fuel..... PF7761
322.3 mm Radial Seal Air (Replacement Ele.) (40942404)..... RS30065	Actros II 1844LL w/OM501LA Eng. (04/03-on)	<b>Fuel/Water Separator</b> (Fleetguard FS19737)..... BF46105-O
532.6 mm Radial Seal Air (40943504)..... RS5358	F-F Lube..... P7192	<b>Radial Seal Air (Initial Installation)</b> (40942404)..... RS30065 KIT
Air (w/Extra Urea Tank)..... PA3765	Fuel..... PF7761	<b>Radial Seal Air (Replacement</b> <b>Ele.)</b> (40942404)..... RS30065
38.9 mm Height Cab Air..... PA4956	<b>Fuel/Water Separator</b> (Fleetguard FS19737)..... BF46105-O	Ele.) (40942404)..... RS30065
40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	<b>Radial Seal Air (Initial Installation)</b> (40942404)..... RS30065 KIT	38.9 mm Height Cab Air..... PA4956
40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	<b>Radial Seal Air (Replacement</b> <b>Ele.)</b> (40942404)..... RS30065	40.5 mm Height Cab Air (w/o Charcoal)..... PA4912
Air Dryer (Desiccant) (Mann TB1374x)..... BA5374 +	38.9 mm Height Cab Air..... PA4956	40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492
Air Dryer (Coalescer) (4295695)..... BA5379 +	40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	Air Dryer (Mann TB1374X)..... BA5374 +
Steering..... P106-HD	40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	Crankcase Breather (5410100080)..... CV15001
Actros II 1844 w/OM501LA Eng. (04/03-on)	Air Dryer (Mann TB1374X)..... BA5374 +	Steering..... P106-HD
F-F Lube..... P7192	Crankcase Breather (5410100080)..... CV15001	Actros II 1845 w/OM471LA (Euro 5/6) Eng. (09/11-on)
<b>Fuel/Water Separator</b> (Open End for Bowl) (A0004771302)..... BF1391-O	Steering..... P106-HD	Lube (A4721800309)..... P7505
Pre-Fuel (924105)..... PF7939	Actros II 1844LL w/OM501LA Eng. (04/03-on)	<b>Fuel/Water Separator</b> (A9604770003)..... BF1297-O
Fuel..... PF7761	F-F Lube..... P7192	Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT
<b>Fuel/Water Separator</b> (w/Drain) (A0004771302)..... BF1363	Fuel..... PF7761	210 mm Air (A0040947204)..... CA30105
<b>Radial Seal Air (Initial Installation)</b> (40942404)..... RS30065 KIT	<b>Fuel/Water Separator</b> (Fleetguard FS19737)..... BF46105-O	228 mm Air (A0040946904)..... CA30103
<b>Radial Seal Air (Replacement</b> <b>Ele.)</b> (40942404)..... RS30065	<b>Radial Seal Air (Replacement</b> <b>Ele.)</b> (40942404)..... RS30065	263 mm Air (A0040946804)..... CA30104
Panel Air (A0040941104)..... PA5426	38.9 mm Height Cab Air..... PA4956	Cab Air (A9608300018)..... PA30122
38.9 mm Height Cab Air..... PA4956	40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	Cab Air (w/Carbon) (A9608300118)..... PA30123
40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	Cab Air (A0008307518)..... PA5585
40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	Air Dryer (Mann TB1374X)..... BA5374 +	Cab Air (A9608300218)..... PA30124
Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	Crankcase Breather (5410100080)..... CV15001	Air Dryer (A0004295695)..... BA5379 +
Air Dryer (Coalescer) (4295695)..... BA5379 +	Steering..... P106-HD	Coolant (A4722030255)..... P5092
Crankcase Breather (5410100080)..... CV15001	Actros II 1844LL w/OM501LA Eng. (04/03-on)	Steering (A0004660604)..... P106-HD
Steering..... P106-HD	F-F Lube..... P7192	Urea (A0001421089)..... PE17002 KIT
	Fuel..... PF7761	Antos 1845 w/OM471LA (BlueTec 5/6) Eng. (09/12-on)
	<b>Fuel/Water Separator</b> (Fleetguard FS19737)..... BF46105-O	Lube (A4721800309)..... P7505
	<b>Radial Seal Air (Replacement</b> <b>Ele.)</b> (40942404)..... RS30065 KIT	<b>Fuel/Water Separator</b> (A9604770003)..... BF1297-O
	<b>Radial Seal Air (Replacement</b> <b>Ele.)</b> (40942404)..... RS30065	Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT
	38.9 mm Height Cab Air..... PA4956	210 mm Air (A0040947204)..... CA30105
	40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	228 mm Air (A0040946904)..... CA30103
	40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	263 mm Air (A0040946804)..... CA30104
	Air Dryer (Mann TB1374X)..... BA5374 +	Cab Air (A9608300018)..... PA30122
	Crankcase Breather (5410100080)..... CV15001	Cab Air (w/Carbon) (A9608300118)..... PA30123
	Steering..... P106-HD	Cab Air (A0008307518)..... PA5585
		Cab Air (A9608300218)..... PA30124
		Air Dryer (A0004295695)..... BA5379 +
		Coolant (A4722030255)..... P5092
		Steering (A0004660604)..... P106-HD
		Urea (A0001421089)..... PE17002 KIT

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
<b>Arocs 1845 w/OM471LA (BlueTec 5/6) Eng. (04/13-on)</b> <b>Lube (A4721800309)..... P7505</b> <b>Fuel/Water Separator (A9604770003)..... BF1297-O</b> <b>Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT</b> <b>210 mm Air (A0040947204)..... CA30105</b> <b>228 mm Air (A0040946904)..... CA30103</b> <b>263 mm Air (A0040946804)..... CA30104</b> <b>Cab Air (A9608300018)..... PA30122</b> <b>Cab Air (w/Carbon) (A9608300118)..... PA30123</b> <b>Cab Air (A0008307518)..... PA5585</b> <b>Cab Air (A9608300218)..... PA30124</b> <b>Air Dryer (A0004295695)..... BA5379 +</b> <b>Coolant (A4722030255)..... P5092</b> <b>Steering (A0004660604)..... P106-HD</b> <b>Urea (A0001421089)..... PE17002 KIT</b>	<b>Actros II 1846 (BlueTec 4/5) w/OM501LA Eng. (02/05-on) (Cont'd)</b> <b>40.5 mm Height Cab Air (w/o Charcoal)..... PA4912</b> <b>40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492</b> <b>Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +</b> <b>Air Dryer (Coalescer) (4295695).. BA5379 +</b> <b>Steering..... P106-HD</b> <b>Actros II 1846 w/OM501LA Eng. (02/03-on)</b> <b>F-F Lube..... P7192</b> <b>Pre-Fuel (924105)..... PF7939</b> <b>Fuel..... PF7761</b> <b>Fuel/Water Separator (Fleetguard FS19737)..... BF46105-O</b> <b>Radial Seal Air (Initial Installation) (40942404)..... RS30065 KIT</b> <b>Radial Seal Air (Initial Installation) (40942404)..... RS30065</b> <b>Panel Air (A0040941104)..... PA5426</b> <b>38.9 mm Height Cab Air..... PA4956</b> <b>40.5 mm Height Cab Air (w/o Charcoal)..... PA4912</b> <b>40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492</b> <b>Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +</b> <b>Air Dryer (Coalescer) (4295695).. BA5379 +</b> <b>Breather (5410100080)..... CV15001</b> <b>Steering..... P106-HD</b> <b>Actros III 1846 BlueTec 4+5 w/OM501LA Eng. (03/08-on)</b> <b>F-F Lube..... P7192</b> <b>Fuel/Water Separator..... BF1391-O</b> <b>P. Fuel..... PF7761</b> <b>Pre-Fuel (924105)..... PF7939</b> <b>338.1 mm Radial Seal Air w/Lid (Initial Installation) (40942404)... RS30065 KIT</b> <b>322.3 mm Radial Seal Air (Replacement Ele.) (40942404)... RS30065</b> <b>532.6 mm Radial Seal Air..... RS5358</b> <b>Air (w/Extra Urea Tank)..... PA3765</b> <b>379.4 mm Cab Air..... PA4956</b> <b>381.8 mm Cab Air (w/o Charcoal) PA4912</b> <b>381.8 mm Cab Air (w/Charcoal) (A0008303418)..... PA5492</b> <b>Air Dryer (4295695)..... BA5379 +</b> <b>Steering..... P106-HD</b> <b>Urea (A0001420089)..... PE5272</b> <b>Actros I 1848 w/OM502LA Eng. (09/96-12/03)</b> <b>F-F Lube (5411800009)..... P7192</b> <b>B-P Lube (21840525)..... C704-L</b> <b>Pre-Fuel (924105)..... PF7939</b> <b>Fuel (5410920305)..... PF7761</b> <b>Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O</b> <b>Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363</b>	<b>Actros I 1848 w/OM502LA Eng. (09/96-12/03) (Cont'd)</b> <b>318.3 mm Air (A0030949104)..... PA3844</b> <b>496.9 mm Air (10947904)..... PA2475</b> <b>38.9 mm Height Cab Air..... PA4956</b> <b>40.5 mm Height Cab Air (w/o Charcoal)..... PA4912</b> <b>40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492</b> <b>Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +</b> <b>Air Dryer (Coalescer) (4295695).. BA5379 +</b> <b>Crankcase Breather (5410100080)..... CV15001</b> <b>Trans. (2690321)..... PT9423</b> <b>Steering (1902137)..... P106-HD</b> <b>Actros II 1848 (BlueTec) w/OM501LA Eng. (02/05-on)</b> <b>F-F Lube..... P7192</b> <b>Pre-Fuel (924105)..... PF7939</b> <b>Fuel..... PF7761</b> <b>Fuel/Water Separator..... BF1391-O</b> <b>338.1 mm Radial Seal Air w/Lid (Initial Installation) (40942404)... RS30065 KIT</b> <b>322.3 mm Radial Seal Air (Replacement Ele.) (40942404)... RS30065</b> <b>532.6 mm Radial Seal Air (40943504)..... RS5358</b> <b>Air (w/Extra Urea Tank)..... PA3765</b> <b>38.9 mm Height Cab Air..... PA4956</b> <b>40.5 mm Height Cab Air (w/o Charcoal)..... PA4912</b> <b>40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492</b> <b>Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +</b> <b>Air Dryer (Coalescer) (4295695).. BA5379 +</b> <b>Steering..... P106-HD</b> <b>Actros II 1848 w/OM471LA (Euro 5/6) Eng. (09/11-on)</b> <b>Lube (A4721800309)..... P7505</b> <b>Fuel/Water Separator (A9604770003)..... BF1297-O</b> <b>Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT</b> <b>210 mm Air (A0040947204)..... CA30105</b> <b>228 mm Air (A0040946904)..... CA30103</b> <b>263 mm Air (A0040946804)..... CA30104</b> <b>Cab Air (A9608300018)..... PA30122</b> <b>Cab Air (w/Carbon) (A9608300118)..... PA30123</b> <b>Cab Air (A0008307518)..... PA5585</b> <b>Cab Air (A9608300218)..... PA30124</b> <b>Air Dryer (A0004295695)..... BA5379 +</b> <b>Coolant (A4722030255)..... P5092</b> <b>Steering (A0004660604)..... P106-HD</b> <b>Urea (A0001421089)..... PE17002 KIT</b>

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
 Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Actros III 1848 BlueTec 4+5 w/OM501LA Eng. (03/08-on)	Actros II 1850 w/OM502LA Eng. (04/03-on)	Actros II 1851 w/OM471LA (Euro 5/6) Eng. (09/11-on) (Cont'd)
F-F Lube..... P7192	F-F Lube..... P7192	Steering (A0004660604)..... P106-HD
Fuel/Water Separator..... BF1391-O	Pre-Fuel (924105)..... PF7939	Urea (A0001421089)..... PE17002 KIT
P. Fuel..... PF7761	Fuel..... PF7761	Actros III 1851 BlueTec 4+5 w/OM502LA Eng. (03/08-on)
Pre-Fuel (924105)..... PF7939	Fuel/Water Separator..... BF1391-O	F-F Lube..... P7192
338.1 mm Radial Seal Air w/Lid (Initial Installation) (40942404).... RS30065 KIT	Radial Seal Air (Initial Installation) (40942404)..... RS30065 KIT	Fuel/Water Separator..... BF1391-O
322.3 mm Radial Seal Air (Replacement Ele.) (40942404).... RS30065	Radial Seal Air (Replacement Ele.) (40942404)..... RS30065	P. Fuel..... PF7761
532.6 mm Radial Seal Air..... RS5358	Panel Air (A0040941104)..... PA5426	Pre-Fuel (924105)..... PF7939
Air (w/Extra Urea Tank)..... PA3765	38.9 mm Height Cab Air..... PA4956	338.1 mm Radial Seal Air w/Lid (Initial Installation) (40942404).... RS30065 KIT
379.4 mm Cab Air..... PA4956	40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	322.3 mm Radial Seal Air (Replacement Ele.) (40942404).... RS30065
381.8 mm Cab Air (w/o Charcoal)..... PA4912	40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	532.6 mm Radial Seal Air..... RS5358
381.8 mm Cab Air (w/Charcoal) (A0008301318)..... PA5492	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	Air (w/Extra Urea Tank)..... PA3765
Air Dryer (4295695)..... BA5379 +	Air Dryer (Coalescer) (4295695)..... BA5379 +	379.4 mm Cab Air..... PA4956
Steering..... P106-HD	Breather (5410100080)..... CV15001	381.8 mm Cab Air (w/o Charcoal)..... PA4912
Urea (A0001420089)..... PE5272	Steering..... P106-HD	381.8 mm Cab Air (w/Charcoal) (A0008303418)..... PA5492
Antos 1848 w/OM471LA (BlueTec 5/6) Eng. (09/12-on)	Actros II 1851 (BlueTec) w/OM502LA Eng. (07/05-on)	Air Dryer (4295695)..... BA5379 +
Lube (A4721800309)..... P7505	F-F Lube..... P7192	Steering..... P106-HD
Fuel/Water Separator (A9604770003)..... BF1297-O	Pre-Fuel (924105)..... PF7939	Urea (A0001420089)..... PE5272
Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT	Fuel..... PF7761	Antos 1851 w/OM471LA (BlueTec 5/6) Eng. (09/12-on)
210 mm Air (A0040947204)..... CA30105	Fuel/Water Separator..... BF1391-O	Lube (A4721800309)..... P7505
228 mm Air (A0040946904)..... CA30103	338.1 mm Radial Seal Air w/Lid (Initial Installation) (40942404).... RS30065 KIT	Fuel/Water Separator (A9604770003)..... BF1297-O
263 mm Air (A0040946804)..... CA30104	322.3 mm Radial Seal Air (Replacement Ele.) (40942404).... RS30065	Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT
Cab Air (A9608300018)..... PA30122	532.6 mm Radial Seal Air (40943504)..... RS5358	210 mm Air (A0040947204)..... CA30105
Cab Air (w/Carbon) (A9608300118)..... PA30123	Air (w/Extra Urea Tank)..... PA3765	228 mm Air (A0040946904)..... CA30103
Cab Air (A0008307518)..... PA5585	38.9 mm Height Cab Air..... PA4956	263 mm Air (A0040946804)..... CA30104
Cab Air (A9608300218)..... PA30124	40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	Cab Air (A9608300018)..... PA30122
Air Dryer (A0004295695)..... BA5379 +	40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	Cab Air (w/Carbon) (A9608300118)..... PA30123
Coolant (A4722030255)..... P5092	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	Cab Air (A0008307518)..... PA5585
Steering (A0004660604)..... P106-HD	Air Dryer (Coalescer) (4295695)..... BA5379 +	Cab Air (A9608300218)..... PA30124
Urea (A0001421089)..... PE17002 KIT	Steering..... P106-HD	Air Dryer (A0004295695)..... BA5379 +
Arocs 1848 w/OM471LA (BlueTec 5/6) Eng. (04/13-on)	Actros II 1851 w/OM471LA (Euro 5/6) Eng. (09/11-on)	Coolant (A4722030255)..... P5092
Lube (A4721800309)..... P7505	Lube (A4721800309)..... P7505	Steering (A0004660604)..... P106-HD
Fuel/Water Separator (A9604770003)..... BF1297-O	Fuel/Water Separator..... BF1297-O	Urea (A0001421089)..... PE17002 KIT
Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT	Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT	Arocs 1851 w/OM471LA (BlueTec 5/6) Eng. (04/13-on)
210 mm Air (A0040947204)..... CA30105	210 mm Air (A0040947204)..... CA30105	Lube (A4721800309)..... P7505
228 mm Air (A0040946904)..... CA30103	228 mm Air (A0040946904)..... CA30103	Fuel/Water Separator (A9604770003)..... BF1297-O
263 mm Air (A0040946804)..... CA30104	263 mm Air (A0040946804)..... CA30104	Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT
Cab Air (A9608300018)..... PA30122	Cab Air (A9608300018)..... PA30122	210 mm Air (A0040947204)..... CA30105
Cab Air (w/Carbon) (A9608300118)..... PA30123	Cab Air (w/Carbon) (A9608300118)..... PA30123	228 mm Air (A0040946904)..... CA30103
Cab Air (A0008307518)..... PA5585	Cab Air (A0008307518)..... PA5585	263 mm Air (A0040946804)..... CA30104
Cab Air (A9608300218)..... PA30124	Cab Air (A9608300218)..... PA30124	Cab Air (A9608300018)..... PA30122
Air Dryer (A0004295695)..... BA5379 +	Cab Air (A0004295695)..... BA5379 +	Cab Air (w/Carbon) (A9608300118)..... PA30123
Coolant (A4722030255)..... P5092	Coolant (A4722030255)..... P5092	Cab Air (A0008307518)..... PA5585
Steering (A0004660604)..... P106-HD		Cab Air (A9608300218)..... PA30124
Urea (A0001421089)..... PE17002 KIT		Air Dryer (A0004295695)..... BA5379 +

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Arocs 1851 w/OM471LA (BlueTec 5/6) Eng. (04/13-on) (Cont'd)	Actros I 1853 w/OM502LA Eng. (09/96-12/03) (Cont'd)	Actros II 1855 (BlueTec 4/5) w/OM502LA Eng. (07/05-on)
Coolant (A4722030255)..... P5092	Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363	F-F Lube..... P7192
Steering (A0004660604)..... P106-HD	Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O	Pre-Fuel (924105)..... PF7939
Urea (A0001421089)..... PE17002 KIT	318.3 mm Air (A0030949104)..... PA3844	Fuel..... PF7761
Arocs 1852 w/OM473LA (BlueTec 5/6) Eng. (04/13-on)	496.9 mm Air (10947904)..... PA2475	Fuel/Water Separator..... BF1391-O
Lube (A4731800009)..... P7505	38.9 mm Height Cab Air (Mann CU3869)..... PA4956	338.1 mm Radial Seal Air w/Lid (Initial Installation) (40942404)... RS30065 KIT
Fuel/Water Separator (A9604770003)..... BF1297-O	40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	322.3 mm Radial Seal Air (Replacement Ele.) (40942404)... RS30065
263 mm Air (A0040946804)..... CA30104	40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	532.6 mm Radial Seal Air (40943504)..... RS5358
228 mm Air (A0040946904)..... CA30103	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	Air (w/Extra Urea Tank)..... PA3765
210 mm Air (A0040947204)..... CA30105	Air Dryer (Coalescer) (4295695).. BA5379 +	38.9 mm Height Cab Air..... PA4956
Cab Air (A9608300018)..... PA30122	Crankcase Breather (5410100080)..... CV15001	40.5 mm Height Cab Air (w/o Charcoal)..... PA4912
Cab Air (w/Carbon) (A9608300118)..... PA30123	Trans. (2690321)..... PT9423	40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492
Cab Air (A0008307518)..... PA5585	Steering (1902137)..... P106-HD	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +
Cab Air (A9608300218)..... PA30124	Actros II 1854 w/OM502LA Eng. (02/03-on)	Air Dryer (Coalescer) (4295695).. BA5379 +
Air Dryer (A0004295695)..... BA5379 +	F-F Lube..... P7192	Crankcase Breather (5410100080)..... CV15001
Steering (A0004660604)..... P106-HD	Pre-Fuel (924105)..... PF7939	Steering..... P106-HD
Urea (A0001421089)..... PE17002 KIT	Fuel..... PF7761	Actros III 1855 BlueTec 4+5 w/OM502LA Eng. (03/08-on)
Antos 1852 w/OM473LA (BlueTec 6) Eng. (11/13-on)	Fuel/Water Separator..... BF1391-O	F-F Lube..... P7192
Lube (A4731800009)..... P7505	Radial Seal Air (Initial Installation) (40942404)..... RS30065 KIT	Fuel/Water Separator..... BF1391-O
Fuel/Water Separator (A9604770003)..... BF1297-O	Radial Seal Air (Replacement Ele.) (40942404)..... RS30065	P. Fuel..... PF7761
263 mm Air (A0040946804)..... CA30104	Panel Air (A0040941104)..... PA5426	Pre-Fuel (924105)..... PF7939
228 mm Air (A0040946904)..... CA30103	38.9 mm Height Cab Air..... PA4956	338.1 mm Radial Seal Air w/Lid (Initial Installation) (40942404)... RS30065 KIT
210 mm Air (A0040947204)..... CA30105	40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	322.3 mm Radial Seal Air (Replacement Ele.) (40942404)... RS30065
Cab Air (A9608300018)..... PA30122	40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	532.6 mm Radial Seal Air..... RS5358
Cab Air (w/Carbon) (A9608300118)..... PA30123	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	Air (w/Extra Urea Tank)..... PA3765
Cab Air (A0008307518)..... PA5585	Air Dryer (Coalescer) (4295695).. BA5379 +	379.4 mm Cab Air..... PA4956
Cab Air (A9608300218)..... PA30124	Crankcase Breather (5410100080)..... CV15001	381.8 mm Cab Air (w/o Charcoal) (A0008303418)..... PA5492
Air Dryer (A0004295695)..... BA5379 +	Steering..... P106-HD	381.8 mm Cab Air (w/Charcoal) (A0008303418)..... PA5492
Steering (A0004660604)..... P106-HD	Urea (A0001421089)..... PE17002 KIT	Air Dryer (4295695)..... BA5379 +
Urea (A0001421089)..... PE17002 KIT	Actros II MP4 1852 w/OM473LA (BlueTec 5/6) Eng. (11/13-on)	Steering..... P106-HD
Actros II 1854 w/OM502LA Eng. (02/03-on)	Lube (A4731800009)..... P7505	Urea (A0001420089)..... PE5272
F-F Lube..... P7192	Fuel/Water Separator (A9604770003)..... BF1297-O	Actros I 1857 w/OM502LA Eng. (09/96-12/03)
Fuel..... PF7761	263 mm Air (A0040946804)..... CA30104	F-F Lube (5411800009)..... P7192
Fuel/Water Separator..... BF1391-O	228 mm Air (A0040946904)..... CA30103	B-P Lube (21840525)..... C704-L
Radial Seal Air (Initial Installation) (40942404)..... RS30065 KIT	210 mm Air (A0040947204)..... CA30105	Pre-Fuel (924105)..... PF7939
Radial Seal Air (Replacement Ele.) (40942404)..... RS30065	Cab Air (A9608300018)..... PA30122	Fuel (5410920305)..... PF7761
Panel Air (A0040941104)..... PA5426	Cab Air (w/Carbon) (A9608300118)..... PA30123	Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363
38.9 mm Height Cab Air..... PA4956	Cab Air (A0008307518)..... PA5585	Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O
40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	Cab Air (A9608300218)..... PA30124	318.3 mm Air (A0030949104)..... PA3844
40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	Air Dryer (A0004295695)..... BA5379 +	654.1 mm Air (10947904)..... PA2475
Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	Steering (A0004660604)..... P106-HD	38.9 mm Height Cab Air..... PA4956
Air Dryer (Coalescer) (4295695).. BA5379 +	Urea (A0001421089)..... PE17002 KIT	40.5 mm Height Cab Air (w/o Charcoal)..... PA4912
Crankcase Breather (5410100080)..... CV15001	Actros I 1853 w/OM502LA Eng. (09/96-12/03)	40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492
Steering..... P106-HD	F-F Lube (5411800009)..... P7192	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +
Actros II 1854LS w/OM502LA Eng. (02/03-on)	B-P Lube (21840525)..... C704-L	
F-F Lube..... P7192	Pre-Fuel (924105)..... PF7939	
Fuel..... PF7761	Fuel (5410920305)..... PF7761	
Fuel/Water Separator (Fleetguard FS19737)..... BF46105-O		
Radial Seal Air (Initial Installation) RS30065 KIT		
Radial Seal Air (Replacement Ele.) (40942404)..... RS30065		
38.9 mm Height Cab Air..... PA4956		
40.5 mm Height Cab Air (w/o Charcoal)..... PA4912		
40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492		
Air Dryer (Mann TB1374X)..... BA5374 +		
Crankcase Breather (5410100080)..... CV15001		
Steering..... P106-HD		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Actros I 1857 w/OM502LA Eng. (09/96-12/03) (Cont'd) Air Dryer (Coalescer) (4295695).. BA5379 + Crankcase Breather (5410100080)..... CV15001 Trans. (2690321)..... PT9423 Steering (1902137)..... P106-HD	Actros II 1858 w/OM502LA Eng. (02/03-on) (Cont'd) Crankcase Breather (5410100080)..... CV15001 Steering..... P106-HD	Actros II 1861 w/OM502LA Eng. (09/04-on) (Cont'd) 40.5 mm Height Cab Air (w/o Charcoal)..... PA4912 40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Crankcase Breather (5410100080)..... CV15001 Steering..... P106-HD
Antos 1858 w/OM473LA (BlueTec 6) Eng. (11/13-on) Lube (A4731800009)..... P7505 Fuel/Water Separator (A9604770003)..... BF1297-O 263 mm Air (A0040946804)..... CA30104 228 mm Air (A0040946904)..... CA30103 210 mm Air (A0040947204)..... CA30105 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A0008307518)..... PA5585 Cab Air (A9608300218)..... PA30124 Air Dryer (A0004295695)..... BA5379 + Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT	Actros II 1860 (BlueTec 4/5) w/OM502LA Eng. (07/05-on) F-F Lube..... P7192 Pre-Fuel (924105)..... PF7939 Fuel..... PF7761 Fuel/Water Separator..... BF1391-O 338.1 mm Radial Seal Air w/Lid (Initial Installation) (40942404)... RS30065 KIT 322.3 mm Radial Seal Air (Replacement Ele.) (40942404)... RS30065 532.6 mm Radial Seal Air (40943504)..... RS5358 Air (w/Extra Urea Tank)..... PA3765 38.9 mm Height Cab Air..... PA4956 40.5 mm Height Cab Air (w/o Charcoal)..... PA4912 40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Steering..... P106-HD	Actros 1863 w/OM473LA (BlueTec 5/6) Eng. (04/13-on) Lube (A4731800009)..... P7505 Fuel/Water Separator (A9604770003)..... BF1297-O 263 mm Air (A0040946804)..... CA30104 228 mm Air (A0040946904)..... CA30103 210 mm Air (A0040947204)..... CA30105 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A0008307518)..... PA5585 Cab Air (A9608300218)..... PA30124 Air Dryer (A0004295695)..... BA5379 + Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT
Actros II MP4 1858 w/OM473LA (BlueTec 5/6) Eng. (11/13-on) Lube (A4731800009)..... P7505 Fuel/Water Separator (A9604770003)..... BF1297-O 263 mm Air (A0040946804)..... CA30104 228 mm Air (A0040946904)..... CA30103 210 mm Air (A0040947204)..... CA30105 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A0008307518)..... PA5585 Cab Air (A9608300218)..... PA30124 Air Dryer (A0004295695)..... BA5379 + Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT	Actros III 1860 BlueTec 4+5 w/OM502LA Eng. (03/08-on) F-F Lube..... P7192 Fuel/Water Separator..... BF1391-O P. Fuel..... PF7761 Pre-Fuel (924105)..... PF7939 338.1 mm Radial Seal Air w/Lid (Initial Installation) (40942404)... RS30065 KIT 322.3 mm Radial Seal Air (Replacement Ele.) (40942404)... RS30065 532.6 mm Radial Seal Air..... RS5358 Air (w/Extra Urea Tank)..... PA3765 379.4 mm Cab Air..... PA4956 381.8 mm Cab Air (w/o Charcoal) PA4912 381.8 mm Cab Air (w/Charcoal) (A0008303418)..... PA5492 Air Dryer (4295695)..... BA5379 + Steering..... P106-HD Urea (A0001420089)..... PE5272	Antos 1863 w/OM473LA (BlueTec 6) Eng. (11/13-on) Lube (A4731800009)..... P7505 Fuel/Water Separator (A9604770003)..... BF1297-O 263 mm Air (A0040946804)..... CA30104 228 mm Air (A0040946904)..... CA30103 210 mm Air (A0040947204)..... CA30105 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A0008307518)..... PA5585 Cab Air (A9608300218)..... PA30124 Air Dryer (A0004295695)..... BA5379 + Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT
Actros II 1858 w/OM502LA Eng. (02/03-on) F-F Lube..... P7192 Pre-Fuel (924105)..... PF7939 Fuel..... PF7761 Fuel/Water Separator..... BF1391-O Radial Seal Air (Initial Installation) (40942404)..... RS30065 KIT Radial Seal Air (Replacement Ele.) (40942404)..... RS30065 Panel Air (A0040941104)..... PA5426 38.9 mm Height Cab Air..... PA4956 40.5 mm Height Cab Air (w/o Charcoal)..... PA4912 40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 +	Actros II 1861 w/OM502LA Eng. (09/04-on) F-F Lube..... P7192 Pre-Fuel (924105)..... PF7939 Fuel..... PF7761 Fuel/Water Separator..... BF1391-O Radial Seal Air (Initial Installation) (40942404)..... RS30065 KIT Radial Seal Air (Replacement Ele.) (40942404)..... RS30065 Panel Air (A0040941104)..... PA5426 38.9 mm Height Cab Air..... PA4956	Actros II MP4 1863 w/OM473LA (BlueTec 5/6) Eng. (11/13-on) Lube (A4731800009)..... P7505 Fuel/Water Separator (A9604770003)..... BF1297-O 263 mm Air (A0040946804)..... CA30104 228 mm Air (A0040946904)..... CA30103 210 mm Air (A0040947204)..... CA30105 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A0008307518)..... PA5585 Cab Air (A9608300218)..... PA30124 Air Dryer (A0004295695)..... BA5379 +

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Actros II MP4 1863 w/OM473LA (BlueTec 5/6) Eng. (11/13-on) (Cont'd)	Actros II MP4 2024 w/OM936LA (BlueTec 5/6) Eng. (09/12-on) (Cont'd)	Actros II MP4 2027 w/OM936LA (BlueTec 5/6) Eng. (09/12-on)
Steering (A0004660604)..... P106-HD	Cab Air (A9608300218)..... PA30124	Lube (A9361800009)..... P40003
Urea (A0001421089)..... PE17002 KIT	Air Dryer (A0004295695)..... BA5379 +	Fuel/Water Separator (A9604770003)..... BF1297-O
Actros I 1943 w/OM501LA Eng. (09/96-12/03)	Steering (A0004660604)..... P106-HD	210 mm Air (A0040947204)..... CA30105
F-F Lube..... P7192	Urea (A0001421089)..... PE17002 KIT	228 mm Air (A0040946904)..... CA30103
B-P Lube (21840525)..... C704-L	Actros II MP4 2024 w/OM936LA (BlueTec 5/6) Eng. (09/12-on)	263 mm Air (A0040946804)..... CA30104
Pre-Fuel (924105)..... PF7939	Lube (A9361800009)..... P40003	Cab Air (A9608300018)..... PA30122
Fuel..... PF7761	Fuel/Water Separator (A9604770003)..... BF1297-O	Cab Air (w/Carbon) (A9608300118)..... PA30123
Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363	210 mm Air (A0040947204)..... CA30105	Cab Air (A0008307518)..... PA5585
Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O	228 mm Air (A0040946904)..... CA30103	Cab Air (A9608300218)..... PA30124
Radial Seal Air (A0040940204)..... RS5343	263 mm Air (A0040946804)..... CA30104	Air Dryer (A0004295695)..... BA5379 +
Panel Air (A0040941104)..... PA5426	Cab Air (A9608300018)..... PA30122	Steering (A0004660604)..... P106-HD
261.9 mm Air..... PA3838 <sup>90</sup>	Cab Air (w/Carbon) (A9608300118)..... PA30123	Urea (A0001421089)..... PE17002 KIT
318.3 mm Air..... PA3844	Cab Air (A0008307518)..... PA5585	Arocs 2030 w/OM936LA (BlueTec 5/6) Eng. (04/13-on)
38.9 mm Height Cab Air (Mann CU3869)..... PA4956	Cab Air (A9608300218)..... PA30124	Lube (A9361800009)..... P40003
40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	Air Dryer (A0004295695)..... BA5379 +	Fuel/Water Separator (A9604770003)..... BF1297-O
40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	Steering (A0004660604)..... P106-HD	210 mm Air (A0040947204)..... CA30105
Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	Urea (A0001421089)..... PE17002 KIT	228 mm Air (A0040946904)..... CA30103
Air Dryer (Coalescer) (4295695)..... BA5379 +	Arocs 2027 w/OM936LA (BlueTec 5/6) Eng. (04/13-on)	263 mm Air (A0040946804)..... CA30104
Crankcase Breather (5410100080)..... CV15001	Lube (A9361800009)..... P40003	Cab Air (A9608300018)..... PA30122
Trans. (2690321)..... PT9423	Fuel/Water Separator (A9604770003)..... BF1297-O	Cab Air (w/Carbon) (A9608300118)..... PA30123
Steering..... P106-HD	210 mm Air (A0040947204)..... CA30105	Cab Air (A0008307518)..... PA5585
Arocs 2024 w/OM936LA (BlueTec 5/6) Eng. (04/13-on)	228 mm Air (A0040946904)..... CA30103	Cab Air (A9608300218)..... PA30124
Lube (A9361800009)..... P40003	263 mm Air (A0040946804)..... CA30104	Air Dryer (A0004295695)..... BA5379 +
Fuel/Water Separator (A9604770003)..... BF1297-O	Cab Air (A9608300018)..... PA30122	Steering (A0004660604)..... P106-HD
210 mm Air (A0040947204)..... CA30105	Cab Air (w/Carbon) (A9608300118)..... PA30123	Urea (A0001421089)..... PE17002 KIT
228 mm Air (A0040946904)..... CA30103	Cab Air (A0008307518)..... PA5585	Actros II MP4 2030 w/OM936LA (BlueTec 5/6) Eng. (09/12-on)
263 mm Air (A0040946804)..... CA30104	Cab Air (A9608300218)..... PA30124	Lube (A9361800009)..... P40003
Cab Air (A9608300018)..... PA30122	Air Dryer (A0004295695)..... BA5379 +	Fuel/Water Separator (A9604770003)..... BF1297-O
Cab Air (w/Carbon) (A9608300118)..... PA30123	Steering (A0004660604)..... P106-HD	210 mm Air (A0040947204)..... CA30105
Cab Air (A0008307518)..... PA5585	Urea (A0001421089)..... PE17002 KIT	228 mm Air (A0040946904)..... CA30103
Cab Air (A9608300218)..... PA30124	Actros 2027 w/OM936LA (BlueTec 5/6) Eng. (09/12-on)	263 mm Air (A0040946804)..... CA30104
Air Dryer (A0004295695)..... BA5379 +	Lube (A9361800009)..... P40003	Cab Air (A9608300018)..... PA30122
Steering (A0004660604)..... P106-HD	Fuel/Water Separator (A9604770003)..... BF1297-O	Cab Air (w/Carbon) (A9608300118)..... PA30123
Urea (A0001421089)..... PE17002 KIT	210 mm Air (A0040947204)..... CA30105	Cab Air (A0008307518)..... PA5585
Actros 2024 w/OM936LA (BlueTec 5/6) Eng. (09/12-on)	228 mm Air (A0040946904)..... CA30103	Cab Air (A9608300218)..... PA30124
Lube (A9361800009)..... P40003	263 mm Air (A0040946804)..... CA30104	Air Dryer (A0004295695)..... BA5379 +
Fuel/Water Separator (A9604770003)..... BF1297-O	Cab Air (A9608300018)..... PA30122	Steering (A0004660604)..... P106-HD
210 mm Air (A0040947204)..... CA30105	Cab Air (w/Carbon) (A9608300118)..... PA30123	Urea (A0001421089)..... PE17002 KIT
228 mm Air (A0040946904)..... CA30103	Cab Air (A0008307518)..... PA5585	Actros II MP4 2030 w/OM936LA (BlueTec 5/6) Eng. (09/12-on)
263 mm Air (A0040946804)..... CA30104	Cab Air (A9608300218)..... PA30124	Lube (A9361800009)..... P40003
Cab Air (A9608300018)..... PA30122	Air Dryer (A0004295695)..... BA5379 +	Fuel/Water Separator (A9604770003)..... BF1297-O
Cab Air (w/Carbon) (A9608300118)..... PA30123	Steering (A0004660604)..... P106-HD	210 mm Air (A0040947204)..... CA30105
Cab Air (A0008307518)..... PA5585	Urea (A0001421089)..... PE17002 KIT	228 mm Air (A0040946904)..... CA30103
		263 mm Air (A0040946804)..... CA30104
		Cab Air (A9608300018)..... PA30122

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.


Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Actros II MP4 2030 w/OM936LA (BlueTec 5/6) Eng. (09/12-on) (Cont'd)	Actros II MP4 2032 w/OM936LA (BlueTec 5/6) Eng. (09/12-on) (Cont'd)	Actros III 2032 BlueTec 4+5 w/OM501LA Eng. (03/08-on) (Cont'd)
Cab Air (w/Carbon) (A9608300118)..... PA30123	263 mm Air (A0040946804)..... CA30104	532.6 mm Radial Seal Air..... RS5358
Cab Air (A0008307518)..... PA5585	Cab Air (A9608300018)..... PA30122	Air (w/Extra Urea Tank)..... PA3765
Cab Air (A9608300218)..... PA30124	Cab Air (w/Carbon) (A9608300118)..... PA30123	379.4 mm Cab Air..... PA4956
Air Dryer (A0004295695)..... BA5379 +	Cab Air (A0008307518)..... PA5585	381.8 mm Cab Air (w/o Charcoal) PA4912
Steering (A0004660604)..... P106-HD	Cab Air (A9608300218)..... PA30124	381.8 mm Cab Air (w/Charcoal) (A0008303418)..... PA5492
Urea (A0001421089)..... PE17002 KIT	Air Dryer (A0004295695)..... BA5379 +	Air Dryer (4295695)..... BA5379 +
Actros I 2031 w/OM501LA Eng. (09/96-12/03)	Steering (A0004660604)..... P106-HD	Steering..... P106-HD
F-F Lube..... P7192	Urea (A0001421089)..... PE17002 KIT	Urea (A0001420089)..... PE5272
B-P Lube (21840525)..... C704-L	Actros II MP4 2032 w/OM936LA (BlueTec 5/6) Eng. (09/12-on)	Actros II MP4 2033 w/OM470LA (BlueTec 5/6) Eng. (09/12-on)
Pre-Fuel (924105)..... PF7939	Lube (A9361800009)..... P40003	Fuel/Water Separator (A9604770003)..... BF1297-O
Fuel..... PF7761	Fuel/Water Separator (A9604770003)..... BF1297-O	210 mm Air (A0040947204)..... CA30105
Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363	210 mm Air (A0040947204)..... CA30105	228 mm Air (A0040946904)..... CA30103
Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O	228 mm Air (A0040946904)..... CA30103	263 mm Air (A0040946804)..... CA30104
261.9 mm Air..... PA3838 <sup>90</sup>	263 mm Air (A0040946804)..... CA30104	Cab Air (A9608300018)..... PA30122
318.3 mm Air..... PA3844	Cab Air (A9608300018)..... PA30122	Cab Air (w/Carbon) (A9608300118)..... PA30123
496.9 mm Air..... PA2475	Cab Air (w/Carbon) (A9608300118)..... PA30123	Cab Air (A0008307518)..... PA5585
Radial Seal Air (40940204)..... RS5343	Cab Air (A0008307518)..... PA5585	Cab Air (A9608300218)..... PA30124
Panel Air (A0040941104)..... PA5426	Cab Air (A9608300218)..... PA30124	Air Dryer (A0004295695)..... BA5379 +
38.9 mm Height Cab Air..... PA4956	Air Dryer (A0004295695)..... BA5379 +	Steering (A0004660604)..... P106-HD
40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	Steering (A0004660604)..... P106-HD	Urea (A0001421089)..... PE17002 KIT
40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	Urea (A0001421089)..... PE17002 KIT	Arcos 2033 w/OM470LA (BlueTec 5/6) Eng. (04/13-on)
Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	Actros II 2032 w/OM501LA Eng. (04/03-on)	Fuel/Water Separator (A9604770003)..... BF1297-O
Air Dryer (Coalescer) (4295695)..... BA5379 +	F-F Lube..... P7192	210 mm Air (A0040947204)..... CA30105
Crankcase Breather (5410100080)..... CV15001	Pre-Fuel (924105)..... PF7939	228 mm Air (A0040946904)..... CA30103
Trans. (2690321)..... PT9423	Fuel..... PF7761	263 mm Air (A0040946804)..... CA30104
Steering..... P106-HD	Fuel/Water Separator..... BF1391-O	Cab Air (A9608300018)..... PA30122
Arcos 2032 w/OM936LA (BlueTec 5/6) Eng. (04/13-on)	Radial Seal Air (Initial Installation) (40942404)..... RS30065 KIT	Cab Air (w/Carbon) (A9608300118)..... PA30123
Lube (A9361800009)..... P40003	Radial Seal Air (Replacement Ele.) (40942404)..... RS30065	Cab Air (A0008307518)..... PA5585
Fuel/Water Separator (A9604770003)..... BF1297-O	Panel Air (A0040941104)..... PA5426	Cab Air (A9608300218)..... PA30124
210 mm Air (A0040947204)..... CA30105	38.9 mm Height Cab Air..... PA4956	Air Dryer (A0004295695)..... BA5379 +
228 mm Air (A0040946904)..... CA30103	40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	Steering (A0004660604)..... P106-HD
263 mm Air (A0040946804)..... CA30104	40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	Urea (A0001421089)..... PE17002 KIT
Cab Air (A9608300018)..... PA30122	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	Actros 2033 w/OM470LA (BlueTec 5/6) Eng. (09/12-on)
Cab Air (w/Carbon) (A9608300118)..... PA30123	Air Dryer (Coalescer) (4295695)..... BA5379 +	Fuel/Water Separator (A9604770003)..... BF1297-O
Cab Air (A0008307518)..... PA5585	Crankcase Breather (5410100080)..... CV15001	210 mm Air (A0040947204)..... CA30105
Cab Air (A9608300218)..... PA30124	Steering..... P106-HD	228 mm Air (A0040946904)..... CA30103
Air Dryer (A0004295695)..... BA5379 +	Actros III 2032 BlueTec 4+5 w/OM501LA Eng. (03/08-on)	263 mm Air (A0040946804)..... CA30104
Steering (A0004660604)..... P106-HD	F-F Lube..... P7192	Cab Air (A9608300018)..... PA30122
Urea (A0001421089)..... PE17002 KIT	Fuel/Water Separator..... BF1391-O	Cab Air (w/Carbon) (A9608300118)..... PA30123
Actros 2032 w/OM936LA (BlueTec 5/6) Eng. (09/12-on)	P. Fuel..... PF7761	Cab Air (A0008307518)..... PA5585
Lube (A9361800009)..... P40003	Pre-Fuel (924105)..... PF7939	Cab Air (A9608300218)..... PA30124
Fuel/Water Separator (A9604770003)..... BF1297-O	338.1 mm Radial Seal Air w/Lid (Initial Installation) (40942404)..... RS30065 KIT	Air Dryer (A0004295695)..... BA5379 +
210 mm Air (A0040947204)..... CA30105	322.3 mm Radial Seal Air (Replacement Ele.) (40942404)..... RS30065	Steering (A0004660604)..... P106-HD
228 mm Air (A0040946904)..... CA30103		Urea (A0001421089)..... PE17002 KIT

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
<b>Arocs 2035 w/OM936LA (BlueTec 5/6) Eng. (04/13-on)</b> <b>Lube (A9361800009)..... P40003</b> <b>Fuel/Water Separator (A9604770003)..... BF1297-O</b> <b>210 mm Air (A0040947204)..... CA30105</b> <b>228 mm Air (A0040946904)..... CA30103</b> <b>263 mm Air (A0040946804)..... CA30104</b> <b>Cab Air (A9608300018)..... PA30122</b> <b>Cab Air (w/Carbon) (A9608300118)..... PA30123</b> <b>Cab Air (A0008307518)..... PA5585</b> <b>Cab Air (A9608300218)..... PA30124</b> <b>Air Dryer (A0004295695)..... BA5379 +</b> <b>Steering (A0004660604)..... P106-HD</b> <b>Urea (A0001421089)..... PE17002 KIT</b>	<b>Actros I 2035 w/OM501LA Eng. (09/96-12/03) (Cont'd)</b> <b>Panel Air (A0040941104)..... PA5426</b> <b>Radial Seal Air (A0040940204).... RS5343</b> <b>38.9 mm Height Cab Air..... PA4956</b> <b>40.5 mm Height Cab Air (w/o Charcoal)..... PA4912</b> <b>40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492</b> <b>Air Dryer (Mann TB1374X)..... BA5374 +</b> <b>Crankcase Breather (5410100080)..... CV15001</b> <b>Trans. (2690321)..... PT9423</b> <b>Steering..... P106-HD</b>	<b>Actros 2036 w/OM470LA (BlueTec 5/6) Eng. (09/12-on) (Cont'd)</b> <b>Urea (A0001421089)..... PE17002 KIT</b> <b>Actros II 2036 w/OM501LA Eng. (04/03-on)</b> <b>F-F Lube..... P7192</b> <b>Pre-Fuel (924105)..... PF7939</b> <b>Fuel..... PF7761</b> <b>Fuel/Water Separator..... BF1391-O</b> <b>Radial Seal Air (Initial Installation) (40942404)..... RS30065 KIT</b> <b>Radial Seal Air (Replacement Ele.) (40942404)..... RS30065</b> <b>Panel Air (A0040941104)..... PA5426</b> <b>38.9 mm Height Cab Air..... PA4956</b> <b>40.5 mm Height Cab Air (w/o Charcoal)..... PA4912</b> <b>40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492</b> <b>Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +</b> <b>Air Dryer (Coalescer) (4295695).... BA5379 +</b> <b>Crankcase Breather (5410100080)..... CV15001</b> <b>Steering..... P106-HD</b>
<b>Actros 2035 w/OM936LA (BlueTec 5/6) Eng. (09/12-on)</b> <b>Lube (A9361800009)..... P40003</b> <b>Fuel/Water Separator (A9604770003)..... BF1297-O</b> <b>210 mm Air (A0040947204)..... CA30105</b> <b>228 mm Air (A0040946904)..... CA30103</b> <b>263 mm Air (A0040946804)..... CA30104</b> <b>Cab Air (A9608300018)..... PA30122</b> <b>Cab Air (w/Carbon) (A9608300118)..... PA30123</b> <b>Cab Air (A0008307518)..... PA5585</b> <b>Cab Air (A9608300218)..... PA30124</b> <b>Air Dryer (A0004295695)..... BA5379 +</b> <b>Steering (A0004660604)..... P106-HD</b> <b>Urea (A0001421089)..... PE17002 KIT</b>	<b>Actros II MP4 2036 w/OM470LA (BlueTec 5/6) Eng. (09/12-on)</b> <b>Fuel/Water Separator (A9604770003)..... BF1297-O</b> <b>210 mm Air (A0040947204)..... CA30105</b> <b>228 mm Air (A0040946904)..... CA30103</b> <b>263 mm Air (A0040946804)..... CA30104</b> <b>Cab Air (A9608300018)..... PA30122</b> <b>Cab Air (w/Carbon) (A9608300118)..... PA30123</b> <b>Cab Air (A0008307518)..... PA5585</b> <b>Cab Air (A9608300218)..... PA30124</b> <b>Air Dryer (A0004295695)..... BA5379 +</b> <b>Steering (A0004660604)..... P106-HD</b> <b>Urea (A0001421089)..... PE17002 KIT</b>	<b>Actros III 2036 BlueTec 4+5 w/OM501LA Eng. (03/08-on)</b> <b>F-F Lube..... P7192</b> <b>Fuel/Water Separator..... BF1391-O</b> <b>P. Fuel..... PF7761</b> <b>Pre-Fuel (924105)..... PF7939</b> <b>338.1 mm Radial Seal Air w/Lid (Initial Installation)..... RS30065 KIT</b> <b>322.3 mm Radial Seal Air (Replacement Ele.)..... RS30065</b> <b>532.6 mm Radial Seal Air..... RS5358</b> <b>Air (w/Extra Urea Tank)..... PA3765</b> <b>379.4 mm Cab Air..... PA4956</b> <b>381.8 mm Cab Air (w/o Charcoal)..... PA4912</b> <b>381.8 mm Cab Air (w/Charcoal) (A0008303418)..... PA5492</b> <b>Air Dryer (4295695)..... BA5379 +</b> <b>Steering..... P106-HD</b> <b>Urea (A0001420089)..... PE5272</b>
<b>Arocs 2036 w/OM470LA (BlueTec 5/6) Eng. (04/13-on)</b> <b>Fuel/Water Separator (A9604770003)..... BF1297-O</b> <b>210 mm Air (A0040947204)..... CA30105</b> <b>228 mm Air (A0040946904)..... CA30103</b> <b>263 mm Air (A0040946804)..... CA30104</b> <b>Cab Air (A9608300018)..... PA30122</b> <b>Cab Air (w/Carbon) (A9608300118)..... PA30123</b> <b>Cab Air (A0008307518)..... PA5585</b> <b>Cab Air (A9608300218)..... PA30124</b> <b>Air Dryer (A0004295695)..... BA5379 +</b> <b>Steering (A0004660604)..... P106-HD</b> <b>Urea (A0001421089)..... PE17002 KIT</b>	<b>Arocs 2036 w/OM470LA (BlueTec 5/6) Eng. (04/13-on)</b> <b>Fuel/Water Separator (A9604770003)..... BF1297-O</b> <b>210 mm Air (A0040947204)..... CA30105</b> <b>228 mm Air (A0040946904)..... CA30103</b> <b>263 mm Air (A0040946804)..... CA30104</b> <b>Cab Air (A9608300018)..... PA30122</b> <b>Cab Air (w/Carbon) (A9608300118)..... PA30123</b> <b>Cab Air (A0008307518)..... PA5585</b> <b>Cab Air (A9608300218)..... PA30124</b> <b>Air Dryer (A0004295695)..... BA5379 +</b> <b>Steering (A0004660604)..... P106-HD</b> <b>Urea (A0001421089)..... PE17002 KIT</b>	<b>Actros II MP4 2040 w/OM470LA (BlueTec 5/6) Eng. (09/12-on)</b> <b>Fuel/Water Separator (A9604770003)..... BF1297-O</b> <b>210 mm Air (A0040947204)..... CA30105</b> <b>228 mm Air (A0040946904)..... CA30103</b> <b>263 mm Air (A0040946804)..... CA30104</b> <b>Cab Air (A9608300018)..... PA30122</b> <b>Cab Air (w/Carbon) (A9608300118)..... PA30123</b> <b>Cab Air (A0008307518)..... PA5585</b> <b>Cab Air (A9608300218)..... PA30124</b> <b>Air Dryer (A0004295695)..... BA5379 +</b> <b>Steering (A0004660604)..... P106-HD</b> <b>Urea (A0001421089)..... PE17002 KIT</b>
<b>Actros I 2035 w/OM501LA Eng. (09/96-12/03)</b> <b>F-F Lube..... P7192</b> <b>B-P Lube (21840525)..... C704-L</b> <b>Fuel..... PF7761</b> <b>Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363</b> <b>Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O</b> <b>261.9 mm Air (Mann C421404).... PA3838 <sup>90</sup></b> <b>318.3 mm Air (Mann C421729).... PA3844</b>	<b>Actros II MP4 2035 w/OM936LA (BlueTec 5/6) Eng. (09/12-on)</b> <b>Lube (A9361800009)..... P40003</b> <b>Fuel/Water Separator (A9604770003)..... BF1297-O</b> <b>210 mm Air (A0040947204)..... CA30105</b> <b>228 mm Air (A0040946904)..... CA30103</b> <b>263 mm Air (A0040946804)..... CA30104</b> <b>Cab Air (A9608300018)..... PA30122</b> <b>Cab Air (w/Carbon) (A9608300118)..... PA30123</b> <b>Cab Air (A0008307518)..... PA5585</b> <b>Cab Air (A9608300218)..... PA30124</b> <b>Air Dryer (A0004295695)..... BA5379 +</b> <b>Steering (A0004660604)..... P106-HD</b> <b>Urea (A0001421089)..... PE17002 KIT</b>	

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.

Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>MERCEDES-BENZ</b> European Trucks, Vans (cont'd)	<b>MERCEDES-BENZ</b> European Trucks, Vans (cont'd)	<b>MERCEDES-BENZ</b> European Trucks, Vans (cont'd)
<b>Arocs 2040 w/OM470LA (BlueTec 5/6) Eng. (04/13-on)</b> <b>Fuel/Water Separator</b> (A9604770003)..... <b>BF1297-O</b> <b>210 mm Air</b> (A0040947204)..... <b>CA30105</b> <b>228 mm Air</b> (A0040946904)..... <b>CA30103</b> <b>263 mm Air</b> (A0040946804)..... <b>CA30104</b> <b>Cab Air</b> (A9608300018)..... <b>PA30122</b> <b>Cab Air (w/Carbon)</b> (A9608300118)..... <b>PA30123</b> <b>Cab Air</b> (A0008307518)..... <b>PA5585</b> <b>Cab Air</b> (A9608300218)..... <b>PA30124</b> <b>Air Dryer</b> (A0004295695)..... <b>BA5379 +</b> <b>Steering</b> (A0004660604)..... <b>P106-HD</b> <b>Urea</b> (A0001421089)..... <b>PE17002 KIT</b>	<b>Actros II 2041 w/OM501LA Eng. (04/03-on)</b> <b>F-F Lube</b> ..... <b>P7192</b> <b>Pre-Fuel</b> (924105)..... <b>PF7939</b> <b>Fuel</b> ..... <b>PF7761</b> <b>Fuel/Water Separator</b> ..... <b>BF1391-O</b> <b>Radial Seal Air (Initial Installation)</b> (40942404)..... <b>RS30065 KIT</b> <b>Radial Seal Air (Replacement Ele.)</b> (40942404)..... <b>RS30065</b> <b>Panel Air</b> (A0040941104)..... <b>PA5426</b> <b>38.9 mm Height Cab Air</b> ..... <b>PA4956</b> <b>40.5 mm Height Cab Air (w/o Charcoal)</b> ..... <b>PA4912</b> <b>40.5 mm Height Cab Air (w/Charcoal)</b> (A0008303418)..... <b>PA5492</b> <b>Air Dryer</b> (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> (Coalescer) (4295695).. <b>BA5379 +</b> <b>Crankcase Breather</b> (5410100080)..... <b>CV15001</b> <b>Steering</b> ..... <b>P106-HD</b>	<b>Actros II 2042 w/OM471LA (BlueTec 5/6) Eng. (09/12-on)</b> <b>Lube</b> (A4731800009)..... <b>P7505</b> <b>Fuel/Water Separator</b> (A9604770003)..... <b>BF1297-O</b> <b>Fuel</b> (Mahle Assembly) (A4710909052)..... <b>PF9908 KIT</b> <b>263 mm Air</b> (A0040946804)..... <b>CA30104</b> <b>228 mm Air</b> (A0040946904)..... <b>CA30103</b> <b>210 mm Air</b> (A0040947204)..... <b>CA30105</b> <b>Cab Air</b> (A9608300018)..... <b>PA30122</b> <b>Cab Air (w/Carbon)</b> (A9608300118)..... <b>PA30123</b> <b>Cab Air</b> (A9608300218)..... <b>PA30124</b> <b>Cab Air</b> (A0008307518)..... <b>PA5585<sup>90</sup></b> <b>Air Dryer</b> (A0004295695)..... <b>BA5379 +</b> <b>Coolant</b> (A4722030255)..... <b>P5092</b> <b>Steering</b> (A0004660604)..... <b>P106-HD</b> <b>Urea</b> (A0001421089)..... <b>PE17002 KIT</b>
<b>Antos 2040 w/OM470LA (BlueTec 5/6) Eng. (09/12-on)</b> <b>Fuel/Water Separator</b> (A9604770003)..... <b>BF1297-O</b> <b>210 mm Air</b> (A0040947204)..... <b>CA30105</b> <b>228 mm Air</b> (A0040946904)..... <b>CA30103</b> <b>263 mm Air</b> (A0040946804)..... <b>CA30104</b> <b>Cab Air</b> (A9608300018)..... <b>PA30122</b> <b>Cab Air (w/Carbon)</b> (A9608300118)..... <b>PA30123</b> <b>Cab Air</b> (A0008307518)..... <b>PA5585</b> <b>Cab Air</b> (A9608300218)..... <b>PA30124</b> <b>Air Dryer</b> (A0004295695)..... <b>BA5379 +</b> <b>Steering</b> (A0004660604)..... <b>P106-HD</b> <b>Urea</b> (A0001421089)..... <b>PE17002 KIT</b>	<b>Actros III 2041 BlueTec 4+5 w/OM501LA Eng. (03/08-on)</b> <b>F-F Lube</b> ..... <b>P7192</b> <b>Fuel/Water Separator</b> ..... <b>BF1391-O</b> <b>P. Fuel</b> ..... <b>PF7761</b> <b>Pre-Fuel</b> (924105)..... <b>PF7939</b> <b>338.1 mm Radial Seal Air w/Lid (Initial Installation)</b> ..... <b>RS30065 KIT</b> <b>322.3 mm Radial Seal Air (Replacement Ele.)</b> ..... <b>RS30065</b> <b>532.6 mm Radial Seal Air</b> ..... <b>RS5358</b> <b>Air (w/Extra Urea Tank)</b> ..... <b>PA3765</b> <b>379.4 mm Cab Air</b> ..... <b>PA4956</b> <b>381.8 mm Cab Air (w/o Charcoal)</b> ..... <b>PA4912</b> <b>381.8 mm Cab Air (w/Charcoal)</b> (A0008303418)..... <b>PA5492</b> <b>Air Dryer</b> (4295695)..... <b>BA5379 +</b> <b>Steering</b> ..... <b>P106-HD</b> <b>Urea</b> (A0001420089)..... <b>PE5272</b>	<b>Actros II MP4 2042 w/OM471LA (BlueTec 5/6) Eng. (09/11-on)</b> <b>Lube</b> (A4731800009)..... <b>P7505</b> <b>Fuel/Water Separator</b> (A9604770003)..... <b>BF1297-O</b> <b>Fuel</b> (Mahle Assembly) (A4710909052)..... <b>PF9908 KIT</b> <b>263 mm Air</b> (A0040946804)..... <b>CA30104</b> <b>228 mm Air</b> (A0040946904)..... <b>CA30103</b> <b>210 mm Air</b> (A0040947204)..... <b>CA30105</b> <b>Cab Air</b> (A9608300018)..... <b>PA30122</b> <b>Cab Air (w/Carbon)</b> (A9608300118)..... <b>PA30123</b> <b>Cab Air</b> (A9608300218)..... <b>PA30124</b> <b>Cab Air</b> (A0008307518)..... <b>PA5585<sup>90</sup></b> <b>Air Dryer</b> (A0004295695)..... <b>BA5379 +</b> <b>Coolant</b> (A4722030255)..... <b>P5092</b> <b>Steering</b> (A0004660604)..... <b>P106-HD</b> <b>Urea</b> (A0001421089)..... <b>PE17002 KIT</b>
<b>Actros I 2040 w/OM501LA Eng. (09/96-12/03)</b> <b>F-F Lube</b> ..... <b>P7192</b> <b>B-P Lube</b> (21840525)..... <b>C704-L</b> <b>Pre-Fuel</b> (924105)..... <b>PF7939</b> <b>Fuel</b> ..... <b>PF7761</b> <b>Fuel/Water Separator (w/Drain)</b> (A0004771302)..... <b>BF1363</b> <b>Fuel/Water Separator (Open End for Bowl)</b> (A0004771302)..... <b>BF1391-O</b> <b>261.9 mm Air</b> ..... <b>PA3838<sup>90</sup></b> <b>318.3 mm Air</b> ..... <b>PA3844</b> <b>Radial Seal Air</b> (40940204)..... <b>RS5343</b> <b>Panel Air</b> (A0040941104)..... <b>PA5426</b> <b>38.9 mm Height Cab Air</b> ..... <b>PA4956</b> <b>40.5 mm Height Cab Air (w/o Charcoal)</b> ..... <b>PA4912</b> <b>40.5 mm Height Cab Air (w/Charcoal)</b> (A0008303418)..... <b>PA5492</b> <b>Air Dryer</b> (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> (Coalescer) (4295695).. <b>BA5379 +</b> <b>Crankcase Breather</b> (5410100080)..... <b>CV15001</b> <b>Trans.</b> (2690321)..... <b>PT9423</b> <b>Steering</b> ..... <b>P106-HD</b>	<b>Arocs 2042 w/OM471LA (BlueTec 5/6) Eng. (04/13-on)</b> <b>Lube</b> (A4731800009)..... <b>P7505</b> <b>Fuel/Water Separator</b> (A9604770003)..... <b>BF1297-O</b> <b>Fuel</b> (Mahle Assembly) (A4710909052)..... <b>PF9908 KIT</b> <b>263 mm Air</b> (A0040946804)..... <b>CA30104</b> <b>228 mm Air</b> (A0040946904)..... <b>CA30103</b> <b>210 mm Air</b> (A0040947204)..... <b>CA30105</b> <b>Cab Air</b> (A9608300018)..... <b>PA30122</b> <b>Cab Air (w/Carbon)</b> (A9608300118)..... <b>PA30123</b> <b>Cab Air</b> (A9608300218)..... <b>PA30124</b> <b>Cab Air</b> (A0008307518)..... <b>PA5585<sup>90</sup></b> <b>Air Dryer</b> (A0004295695)..... <b>BA5379 +</b> <b>Coolant</b> (A4722030255)..... <b>P5092</b> <b>Steering</b> (A0004660604)..... <b>P106-HD</b> <b>Urea</b> (A0001421089)..... <b>PE17002 KIT</b>	<b>Actros II MP4 2043 w/OM470LA (BlueTec 5/6) Eng. (09/12-on)</b> <b>Fuel/Water Separator</b> (A9604770003)..... <b>BF1297-O</b> <b>210 mm Air</b> (A0040947204)..... <b>CA30105</b> <b>228 mm Air</b> (A0040946904)..... <b>CA30103</b> <b>263 mm Air</b> (A0040946804)..... <b>CA30104</b> <b>Cab Air</b> (A9608300018)..... <b>PA30122</b> <b>Cab Air (w/Carbon)</b> (A9608300118)..... <b>PA30123</b> <b>Cab Air</b> (A0008307518)..... <b>PA5585</b> <b>Cab Air</b> (A9608300218)..... <b>PA30124</b> <b>Air Dryer</b> (A0004295695)..... <b>BA5379 +</b> <b>Steering</b> (A0004660604)..... <b>P106-HD</b> <b>Urea</b> (A0001421089)..... <b>PE17002 KIT</b>
		<b>Arocs 2043 w/OM470LA (BlueTec 5/6) Eng. (04/13-on)</b> <b>Fuel/Water Separator</b> (A9604770003)..... <b>BF1297-O</b> <b>210 mm Air</b> (A0040947204)..... <b>CA30105</b>

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
 Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
<b>Arocs 2043 w/OM470LA (BlueTec 5/6) Eng. (04/13-on) (Cont'd)</b> 228 mm Air (A0040946904)..... CA30103 263 mm Air (A0040946804)..... CA30104 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A0008307518)..... PA5585 Cab Air (A9608300218)..... PA30124 Air Dryer (A0004295695)..... BA5379 + Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT	<b>Actros II 2044 w/OM501LA Eng. (04/03-on) (Cont'd)</b> Radial Seal Air (Replacement Ele.) (40942404)..... RS30065 Panel Air (A0040941104)..... PA5426 38.9 mm Height Cab Air..... PA4956 40.5 mm Height Cab Air (w/o Charcoal)..... PA4912 40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Crankcase Breather (5410100080)..... CV15001 Steering..... P106-HD <b>Actros III 2044 BlueTec 4+5 w/OM501LA Eng. (03/08-on)</b> F-F Lube..... P7192 Fuel/Water Separator..... BF1391-O P. Fuel..... PF7761 Pre-Fuel (924105)..... PF7939 338.1 mm Radial Seal Air w/Lid (Initial Installation)..... RS30065 KIT 322.3 mm Radial Seal Air (Replacement Ele.)..... RS30065 532.6 mm Radial Seal Air..... RS5358 Air (w/Extra Urea Tank)..... PA3765 379.4 mm Cab Air..... PA4956 381.8 mm Cab Air (w/o Charcoal) PA4912 381.8 mm Cab Air (w/Charcoal) (A0008303418)..... PA5492 Air Dryer (4295695)..... BA5379 + Steering..... P106-HD Urea (A0001420089)..... PE5272 <b>Arocs 2045 w/OM471LA (BlueTec 5/6) Eng. (04/13-on)</b> Lube (A4731800009)..... P7505 Fuel/Water Separator (A9604770003)..... BF1297-O Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT 263 mm Air (A0040946804)..... CA30104 228 mm Air (A0040946904)..... CA30103 210 mm Air (A0040947204)..... CA30105 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A9608300218)..... PA30124 Cab Air (A0008307518)..... PA5585 90 Air Dryer (A0004295695)..... BA5379 + Coolant (A4722030255)..... P5092 Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT	<b>Actros 2045 w/OM471LA (BlueTec 5/6) Eng. (09/12-on) (Cont'd)</b> Fuel/Water Separator (A9604770003)..... BF1297-O Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT 263 mm Air (A0040946804)..... CA30104 228 mm Air (A0040946904)..... CA30103 210 mm Air (A0040947204)..... CA30105 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A9608300218)..... PA30124 Cab Air (A0008307518)..... PA5585 90 Air Dryer (A0004295695)..... BA5379 + Coolant (A4722030255)..... P5092 Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT <b>Actros II MP4 2045 w/OM471LA (BlueTec 5/6) Eng. (09/11-on)</b> Lube (A4731800009)..... P7505 Fuel/Water Separator (A9604770003)..... BF1297-O Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT 263 mm Air (A0040946804)..... CA30104 228 mm Air (A0040946904)..... CA30103 210 mm Air (A0040947204)..... CA30105 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A9608300218)..... PA30124 Cab Air (A0008307518)..... PA5585 90 Air Dryer (A0004295695)..... BA5379 + Coolant (A4722030255)..... P5092 Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT <b>Actros I 2046 w/OM501LA Eng. (09/96-12/03)</b> F-F Lube..... P7192 B-P Lube (21840525)..... C704-L Pre-Fuel (924105)..... PF7939 Fuel..... PF7761 Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363 Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O Radial Seal Air (4094204)..... RS5343 261.9 mm Air..... PA3838 90 318.3 mm Air..... PA3844 Panel Air (A0040941104)..... PA5426 38.9 mm Height Cab Air..... PA4956 40.5 mm Height Cab Air (w/o Charcoal)..... PA4912 40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Crankcase Breather (5410100080)..... CV15001 Trans. (2690321)..... PT9423 Steering..... P106-HD <b>Actros II 2044 w/OM501LA Eng. (04/03-on)</b> F-F Lube..... P7192 Pre-Fuel (924105)..... PF7939 Fuel..... PF7761 Fuel/Water Separator..... BF1391-O Radial Seal Air (Initial Installation) RS30065 KIT

+ See Product Guide for Variations of This Number. 90 Obsolete Pending.


Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Actros I 2046 w/OM501LA Eng. (09/96-12/03) (Cont'd) Crankcase Breather (541010080)..... CV15001 Trans. (2690321)..... PT9423 Steering..... P106-HD	Arocs 2048 w/OM471LA (BlueTec 5/6) Eng. (04/13-on) (Cont'd) Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A9608300218)..... PA30124 Cab Air (A0008307518)..... PA5585 <sup>90</sup> Air Dryer (A0004295695)..... BA5379 + Coolant (A4722030255)..... P5092 Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT	Actros III 2048 BlueTec 4+5 w/OM501LA Eng. (03/08-on) (Cont'd) 532.6 mm Radial Seal Air..... RS5358 Air (w/Extra Urea Tank)..... PA3765 379.4 mm Cab Air..... PA4956 381.8 mm Cab Air (w/o Charcoal) PA4912 381.8 mm Cab Air (w/Charcoal) (A0008303418)..... PA5492 Air Dryer (4295695)..... BA5379 + Steering..... P106-HD Urea (A0001420089)..... PE5272
Actros II 2046 w/OM501LA Eng. (04/03-on) F-F Lube..... P7192 Pre-Fuel (924105)..... PF7939 Fuel..... PF7761 Fuel/Water Separator..... BF1391-O Radial Seal Air (Initial Installation) (40942404)..... RS30065 KIT Radial Seal Air (Replacement Ele.) (40942404)..... RS30065 Panel Air (A0040941104)..... PA5426 38.9 mm Height Cab Air..... PA4956 40.5 mm Height Cab Air (w/o Charcoal)..... PA4912 40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Crankcase Breather (541010080)..... CV15001 Steering..... P106-HD	Antos 2048 w/OM471LA (BlueTec 5/6) Eng. (09/12-on) Lube (A4731800009)..... P7505 Fuel/Water Separator (A9604770003)..... BF1297-O Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT 263 mm Air (A0040946804)..... CA30104 228 mm Air (A0040946904)..... CA30103 210 mm Air (A0040947204)..... CA30105 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A9608300218)..... PA30124 Cab Air (A0008307518)..... PA5585 <sup>90</sup> Air Dryer (A0004295695)..... BA5379 + Coolant (A4722030255)..... P5092 Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT	Actros II 2050 w/OM502LA Eng. (04/03-on) F-F Lube..... P7192 Pre-Fuel (924105)..... PF7939 Fuel..... PF7761 Fuel/Water Separator..... BF1391-O Radial Seal Air (Initial Installation) (40942404)..... RS30065 KIT Radial Seal Air (Replacement Ele.) (40942404)..... RS30065 Panel Air (A0040941104)..... PA5426 38.9 mm Height Cab Air..... PA4956 40.5 mm Height Cab Air (w/o Charcoal)..... PA4912 40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Crankcase Breather (541010080)..... CV15001 Steering..... P106-HD
Actros III 2046 BlueTec 4+5 w/OM501LA Eng. (03/08-on) F-F Lube..... P7192 Fuel/Water Separator..... BF1391-O P. Fuel..... PF7761 Pre-Fuel (924105)..... PF7939 338.1 mm Radial Seal Air w/Lid (Initial Installation)..... RS30065 KIT 322.3 mm Radial Seal Air (Replacement Ele.)..... RS30065 532.6 mm Radial Seal Air..... RS5358 Air (w/Extra Urea Tank)..... PA3765 379.4 mm Cab Air..... PA4956 381.8 mm Cab Air (w/o Charcoal) PA4912 381.8 mm Cab Air (w/Charcoal) (A0008303418)..... PA5492 Air Dryer (4295695)..... BA5379 + Steering..... P106-HD Urea (A0001420089)..... PE5272	Actros II MP4 2048 w/OM471LA (BlueTec 5/6) Eng. (09/11-on) Lube (A4731800009)..... P7505 Fuel/Water Separator (A9604770003)..... BF1297-O Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT 263 mm Air (A0040946804)..... CA30104 228 mm Air (A0040946904)..... CA30103 210 mm Air (A0040947204)..... CA30105 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A9608300218)..... PA30124 Cab Air (A0008307518)..... PA5585 <sup>90</sup> Air Dryer (A0004295695)..... BA5379 + Coolant (A4722030255)..... P5092 Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT	Arocs 2051 w/OM471LA (BlueTec 5/6) Eng. (04/13-on) Lube (A4731800009)..... P7505 Fuel/Water Separator (A9604770003)..... BF1297-O Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT 263 mm Air (A0040946804)..... CA30104 228 mm Air (A0040946904)..... CA30103 210 mm Air (A0040947204)..... CA30105 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A9608300218)..... PA30124 Cab Air (A0008307518)..... PA5585 <sup>90</sup> Air Dryer (A0004295695)..... BA5379 + Coolant (A4722030255)..... P5092 Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT
Arocs 2048 w/OM471LA (BlueTec 5/6) Eng. (04/13-on) Lube (A4731800009)..... P7505 Fuel/Water Separator (A9604770003)..... BF1297-O Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT 263 mm Air (A0040946804)..... CA30104 228 mm Air (A0040946904)..... CA30103 210 mm Air (A0040947204)..... CA30105 Cab Air (A9608300018)..... PA30122	Actros III 2048 BlueTec 4+5 w/OM501LA Eng. (03/08-on) F-F Lube..... P7192 Fuel/Water Separator..... BF1391-O P. Fuel..... PF7761 Pre-Fuel (924105)..... PF7939 338.1 mm Radial Seal Air w/Lid (Initial Installation)..... RS30065 KIT 322.3 mm Radial Seal Air (Replacement Ele.)..... RS30065	Antos 2051 w/OM471LA (BlueTec 5/6) Eng. (09/12-on) Lube (A4731800009)..... P7505 Fuel/Water Separator (A9604770003)..... BF1297-O Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
<b>Antos 2051 w/OM471LA (BlueTec 5/6) Eng. (09/12-on) (Cont'd)</b> 263 mm Air (A0040946804)..... CA30104 228 mm Air (A0040946904)..... CA30103 210 mm Air (A0040947204)..... CA30105 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A9608300218)..... PA30124 Cab Air (A0008307518)..... PA5585 <sup>90</sup> Air Dryer (A0004295695)..... BA5379 + Coolant (A4722030255)..... P5092 Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT	<b>Arocs 2052 w/OM473LA (BlueTec 5/6) Eng. (04/13-on) (Cont'd)</b> 228 mm Air (A0040946904)..... CA30103 210 mm Air (A0040947204)..... CA30105 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A0008307518)..... PA5585 Cab Air (A9608300218)..... PA30124 Air Dryer (A0004295695)..... BA5379 + Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT	<b>Actros III 2055 BlueTec 4+5 w/OM502LA Eng. (03/08-on)</b> F-F Lube..... P7192 Fuel/Water Separator..... BF1391-O P. Fuel..... PF7761 Pre-Fuel (924105)..... PF7939 338.1 mm Radial Seal Air w/Lid (Initial Installation)..... RS30065 KIT 322.3 mm Radial Seal Air (Replacement Ele.)..... RS30065 532.6 mm Radial Seal Air..... RS5358 Air (w/Extra Urea Tank)..... PA3765 379.4 mm Cab Air..... PA4956 381.8 mm Cab Air (w/o Charcoal) (A0008303418)..... PA5492 381.8 mm Cab Air (w/Charcoal) (A0008303418)..... PA5492 Air Dryer (4295695)..... BA5379 + Steering..... P106-HD Urea (A0001420089)..... PE5272
<b>Actros II MP4 2051 w/OM471LA (BlueTec 5/6) Eng. (09/11-on)</b> Lube (A4731800009)..... P7505 Fuel/Water Separator (A9604770003)..... BF1297-O Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT 263 mm Air (A0040946804)..... CA30104 228 mm Air (A0040946904)..... CA30103 210 mm Air (A0040947204)..... CA30105 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A9608300218)..... PA30124 Cab Air (A0008307518)..... PA5585 <sup>90</sup> Air Dryer (A0004295695)..... BA5379 + Coolant (A4722030255)..... P5092 Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT	<b>Actros I 2053S w/OM502LA Eng. (09/96-12/03)</b> F-F Lube..... P7192 B-P Lube (21840525)..... C704-L Pre-Fuel (924105)..... PF7939 Fuel..... PF7761 Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363 Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O 261.9 mm Air (Mann C421404)..... PA3838 <sup>90</sup> 318.3 mm Air (Mann C421729)..... PA3844 Radial Seal Air (A0040940204)..... RS5343 Panel Air (A0040941104)..... PA5426 38.9 mm Height Cab Air..... PA4956 40.5 mm Height Cab Air (w/o Charcoal)..... PA4912 40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695)..... BA5379 + Crankcase Breather (5410100080)..... CV15001 Trans. (2690321)..... PT9423 Steering..... P106-HD	<b>Actros II 2058 w/OM502LA Eng. (04/03-on)</b> F-F Lube..... P7192 Pre-Fuel (924105)..... PF7939 Fuel..... PF7761 Fuel/Water Separator..... BF1391-O Radial Seal Air (Initial Installation) (40942404)..... RS30065 KIT Radial Seal Air (Replacement Ele.) (40942404)..... RS30065 Panel Air (A0040941104)..... PA5426 38.9 mm Height Cab Air..... PA4956 40.5 mm Height Cab Air (w/o Charcoal)..... PA4912 40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695)..... BA5379 + Crankcase Breather (5410100080)..... CV15001 Steering..... P106-HD
<b>Actros III 2051 BlueTec 4+5 w/OM502LA Eng. (03/08-on)</b> F-F Lube..... P7192 Fuel/Water Separator..... BF1391-O P. Fuel..... PF7761 Pre-Fuel (924105)..... PF7939 338.1 mm Radial Seal Air w/Lid (Initial Installation)..... RS30065 KIT 322.3 mm Radial Seal Air (Replacement Ele.)..... RS30065 532.6 mm Radial Seal Air..... RS5358 Air (w/Extra Urea Tank)..... PA3765 379.4 mm Cab Air..... PA4956 381.8 mm Cab Air (w/o Charcoal) (A0008303418)..... PA5492 381.8 mm Cab Air (w/Charcoal) (A0008303418)..... PA5492 Air Dryer (4295695)..... BA5379 + Steering..... P106-HD Urea (A0001420089)..... PE5272	<b>Actros II 2054 w/OM502LA Eng. (04/03-on)</b> F-F Lube..... P7192 Pre-Fuel (924105)..... PF7939 Fuel..... PF7761 Fuel/Water Separator..... BF1391-O Radial Seal Air (Initial Installation) (40942404)..... RS30065 KIT Radial Seal Air (Replacement Ele.) (40942404)..... RS30065 Panel Air (A0040941104)..... PA5426 38.9 mm Height Cab Air..... PA4956 40.5 mm Height Cab Air (w/o Charcoal)..... PA4912 40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695)..... BA5379 + Crankcase Breather (5410100080)..... CV15001 Steering..... P106-HD	<b>Arocs 2063 w/OM473LA (BlueTec 5/6) Eng. (04/13-on)</b> Lube (A4731800009)..... P7505 Fuel/Water Separator (A9604770003)..... BF1297-O 263 mm Air (A0040946804)..... CA30104 228 mm Air (A0040946904)..... CA30103 210 mm Air (A0040947204)..... CA30105 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A0008307518)..... PA5585 Cab Air (A9608300218)..... PA30124 Air Dryer (A0004295695)..... BA5379 + Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT
<b>Arocs 2052 w/OM473LA (BlueTec 5/6) Eng. (04/13-on)</b> Lube (A4731800009)..... P7505 Fuel/Water Separator (A9604770003)..... BF1297-O 263 mm Air (A0040946804)..... CA30104		

\* See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.


Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>MERCEDES-BENZ</b> European Trucks, Vans (cont'd)	<b>MERCEDES-BENZ</b> European Trucks, Vans (cont'd)	<b>MERCEDES-BENZ</b> European Trucks, Vans (cont'd)
<b>Atego II 915 w/OM904LA Eng. (09/04-on)</b> <b>Lube</b> ..... P7199 <b>Fuel</b> ..... PF7735 <b>Fuel/Water Separator</b> ..... BF1391-O <b>Radial Seal Air (30949504)</b> ..... RS5342 <b>Cab Air (9738350147)</b> ..... PA5340 <b>Air Dryer (Desiccant) (Mann TB1374X)</b> ..... BA5374 + <b>Air Dryer (Coalescer) (4295695)</b> .. BA5379 + <b>Steering</b> ..... P106-HD	<b>Actros II MP4 2430 w/OM936LA (BlueTec 5/6) Eng. (09/12-on)</b> <b>Lube (A9361800009)</b> ..... P40003 <b>Fuel/Water Separator (A9604770003)</b> ..... BF1297-O <b>210 mm Air (A0040947204)</b> ..... CA30105 <b>228 mm Air (A0040946904)</b> ..... CA30103 <b>263 mm Air (A0040946804)</b> ..... CA30104 <b>Cab Air (A9608300018)</b> ..... PA30122 <b>Cab Air (w/Carbon) (A9608300118)</b> ..... PA30123 <b>Cab Air (A0008307518)</b> ..... PA5585 <b>Cab Air (A9608300218)</b> ..... PA30124 <b>Air Dryer (A0004295695)</b> ..... BA5379 + <b>Steering (A0004660604)</b> ..... P106-HD <b>Urea (A0001421089)</b> ..... PE17002 KIT	<b>Actros II MP4 2433 w/OM470LA (BlueTec 5/6) Eng. (09/12-on) (Cont'd)</b> <b>Cab Air (A0008307518)</b> ..... PA5585 <b>Cab Air (A9608300218)</b> ..... PA30124 <b>Air Dryer (A0004295695)</b> ..... BA5379 + <b>Steering (A0004660604)</b> ..... P106-HD <b>Urea (A0001421089)</b> ..... PE17002 KIT
<b>Antos 2427 w/OM936LA (BlueTec 5/6) Eng. (09/12-on)</b> <b>Lube (A9361800009)</b> ..... P40003 <b>Fuel/Water Separator (A9604770003)</b> ..... BF1297-O <b>210 mm Air (A0040947204)</b> ..... CA30105 <b>228 mm Air (A0040946904)</b> ..... CA30103 <b>263 mm Air (A0040946804)</b> ..... CA30104 <b>Cab Air (A9608300018)</b> ..... PA30122 <b>Cab Air (w/Carbon) (A9608300118)</b> ..... PA30123 <b>Cab Air (A0008307518)</b> ..... PA5585 <b>Cab Air (A9608300218)</b> ..... PA30124 <b>Air Dryer (A0004295695)</b> ..... BA5379 + <b>Steering (A0004660604)</b> ..... P106-HD <b>Urea (A0001421089)</b> ..... PE17002 KIT	<b>Actros II MP4 2432 w/OM936LA (BlueTec 5/6) Eng. (09/12-on)</b> <b>Lube (A9361800009)</b> ..... P40003 <b>Fuel/Water Separator (A9604770003)</b> ..... BF1297-O <b>210 mm Air (A0040947204)</b> ..... CA30105 <b>228 mm Air (A0040946904)</b> ..... CA30103 <b>263 mm Air (A0040946804)</b> ..... CA30104 <b>Cab Air (A9608300018)</b> ..... PA30122 <b>Cab Air (w/Carbon) (A9608300118)</b> ..... PA30123 <b>Cab Air (A0008307518)</b> ..... PA5585 <b>Cab Air (A9608300218)</b> ..... PA30124 <b>Air Dryer (A0004295695)</b> ..... BA5379 + <b>Steering (A0004660604)</b> ..... P106-HD <b>Urea (A0001421089)</b> ..... PE17002 KIT	<b>Antos 2433 w/OM470LA (BlueTec 5/6) Eng. (09/12-on)</b> <b>Lube (A9361800009)</b> ..... P40003 <b>Fuel/Water Separator (A9604770003)</b> ..... BF1297-O <b>210 mm Air (A0040947204)</b> ..... CA30105 <b>228 mm Air (A0040946904)</b> ..... CA30103 <b>263 mm Air (A0040946804)</b> ..... CA30104 <b>Cab Air (A9608300018)</b> ..... PA30122 <b>Cab Air (w/Carbon) (A9608300118)</b> ..... PA30123 <b>Cab Air (A0008307518)</b> ..... PA5585 <b>Cab Air (A9608300218)</b> ..... PA30124 <b>Air Dryer (A0004295695)</b> ..... BA5379 + <b>Steering (A0004660604)</b> ..... P106-HD <b>Urea (A0001421089)</b> ..... PE17002 KIT
<b>Actros II MP4 2427 w/OM936LA (BlueTec 5/6) Eng. (09/12-on)</b> <b>Lube (A9361800009)</b> ..... P40003 <b>Fuel/Water Separator (A9604770003)</b> ..... BF1297-O <b>210 mm Air (A0040947204)</b> ..... CA30105 <b>228 mm Air (A0040946904)</b> ..... CA30103 <b>263 mm Air (A0040946804)</b> ..... CA30104 <b>Cab Air (A9608300018)</b> ..... PA30122 <b>Cab Air (w/Carbon) (A9608300118)</b> ..... PA30123 <b>Cab Air (A0008307518)</b> ..... PA5585 <b>Cab Air (A9608300218)</b> ..... PA30124 <b>Air Dryer (A0004295695)</b> ..... BA5379 + <b>Steering (A0004660604)</b> ..... P106-HD <b>Urea (A0001421089)</b> ..... PE17002 KIT	<b>Actros II MP4 2432 w/OM936LA (BlueTec 5/6) Eng. (09/12-on)</b> <b>Lube (A9361800009)</b> ..... P40003 <b>Fuel/Water Separator (A9604770003)</b> ..... BF1297-O <b>210 mm Air (A0040947204)</b> ..... CA30105 <b>228 mm Air (A0040946904)</b> ..... CA30103 <b>263 mm Air (A0040946804)</b> ..... CA30104 <b>Cab Air (A9608300018)</b> ..... PA30122 <b>Cab Air (w/Carbon) (A9608300118)</b> ..... PA30123 <b>Cab Air (A0008307518)</b> ..... PA5585 <b>Cab Air (A9608300218)</b> ..... PA30124 <b>Air Dryer (A0004295695)</b> ..... BA5379 + <b>Steering (A0004660604)</b> ..... P106-HD <b>Urea (A0001421089)</b> ..... PE17002 KIT	<b>Antos 2435 w/OM936LA (BlueTec 5/6) Eng. (09/12-on)</b> <b>Lube (A9361800009)</b> ..... P40003 <b>Fuel/Water Separator (A9604770003)</b> ..... BF1297-O <b>210 mm Air (A0040947204)</b> ..... CA30105 <b>228 mm Air (A0040946904)</b> ..... CA30103 <b>263 mm Air (A0040946804)</b> ..... CA30104 <b>Cab Air (A9608300018)</b> ..... PA30122 <b>Cab Air (w/Carbon) (A9608300118)</b> ..... PA30123 <b>Cab Air (A0008307518)</b> ..... PA5585 <b>Cab Air (A9608300218)</b> ..... PA30124 <b>Air Dryer (A0004295695)</b> ..... BA5379 + <b>Steering (A0004660604)</b> ..... P106-HD <b>Urea (A0001421089)</b> ..... PE17002 KIT
<b>Antos 2430 w/OM936LA (BlueTec 5/6) Eng. (09/12-on)</b> <b>Lube (A9361800009)</b> ..... P40003 <b>Fuel/Water Separator (A9604770003)</b> ..... BF1297-O <b>210 mm Air (A0040947204)</b> ..... CA30105 <b>228 mm Air (A0040946904)</b> ..... CA30103 <b>263 mm Air (A0040946804)</b> ..... CA30104 <b>Cab Air (A9608300018)</b> ..... PA30122 <b>Cab Air (w/Carbon) (A9608300118)</b> ..... PA30123 <b>Cab Air (A0008307518)</b> ..... PA5585 <b>Cab Air (A9608300218)</b> ..... PA30124 <b>Air Dryer (A0004295695)</b> ..... BA5379 + <b>Steering (A0004660604)</b> ..... P106-HD <b>Urea (A0001421089)</b> ..... PE17002 KIT	<b>Actros II MP4 2433 w/OM470LA (BlueTec 5/6) Eng. (09/12-on)</b> <b>Lube (A9361800009)</b> ..... P40003 <b>Fuel/Water Separator (A9604770003)</b> ..... BF1297-O <b>210 mm Air (A0040947204)</b> ..... CA30105 <b>228 mm Air (A0040946904)</b> ..... CA30103 <b>263 mm Air (A0040946804)</b> ..... CA30104 <b>Cab Air (A9608300018)</b> ..... PA30122 <b>Cab Air (w/Carbon) (A9608300118)</b> ..... PA30123 <b>Cab Air (A0008307518)</b> ..... PA5585 <b>Cab Air (A9608300218)</b> ..... PA30124 <b>Air Dryer (A0004295695)</b> ..... BA5379 + <b>Steering (A0004660604)</b> ..... P106-HD <b>Urea (A0001421089)</b> ..... PE17002 KIT	<b>Actros II MP4 2435 w/OM936LA (BlueTec 5/6) Eng. (09/12-on)</b> <b>Lube (A9361800009)</b> ..... P40003 <b>Fuel/Water Separator (A9604770003)</b> ..... BF1297-O <b>210 mm Air (A0040947204)</b> ..... CA30105 <b>228 mm Air (A0040946904)</b> ..... CA30103 <b>263 mm Air (A0040946804)</b> ..... CA30104 <b>Cab Air (A9608300018)</b> ..... PA30122 <b>Cab Air (w/Carbon) (A9608300118)</b> ..... PA30123 <b>Cab Air (A0008307518)</b> ..... PA5585 <b>Cab Air (A9608300218)</b> ..... PA30124 <b>Air Dryer (A0004295695)</b> ..... BA5379 + <b>Steering (A0004660604)</b> ..... P106-HD <b>Urea (A0001421089)</b> ..... PE17002 KIT

\* See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Actros II MP4 2436 w/OM470LA (BlueTec 5/6) Eng. (09/12-on) <b>Fuel/Water Separator</b> (A9604770003)..... <b>BF1297-O</b> <b>210 mm Air</b> (A0040947204)..... <b>CA30105</b> <b>228 mm Air</b> (A0040946904)..... <b>CA30103</b> <b>263 mm Air</b> (A0040946804)..... <b>CA30104</b> <b>Cab Air</b> (A9608300018)..... <b>PA30122</b> <b>Cab Air</b> (w/Carbon) (A9608300118)..... <b>PA30123</b> <b>Cab Air</b> (A0008307518)..... <b>PA5585</b> <b>Cab Air</b> (A9608300218)..... <b>PA30124</b> <b>Air Dryer</b> (A0004295695)..... <b>BA5379 +</b> <b>Steering</b> (A0004660604)..... <b>P106-HD</b> <b>Urea</b> (A0001421089)..... <b>PE17002 KIT</b>	Antos 2440 w/OM470LA (BlueTec 5/6) Eng. (09/12-on) (Cont'd) <b>Steering</b> (A0004660604)..... <b>P106-HD</b> <b>Urea</b> (A0001421089)..... <b>PE17002 KIT</b> Antos 2442 w/OM471LA (BlueTec 5/6) Eng. (09/12-on) <b>Lube</b> (A4731800009)..... <b>P7505</b> <b>Fuel/Water Separator</b> (A9604770003)..... <b>BF1297-O</b> <b>Fuel</b> (Mahle Assembly) (A4710909052)..... <b>PF9908 KIT</b> <b>263 mm Air</b> (A0040946804)..... <b>CA30104</b> <b>228 mm Air</b> (A0040946904)..... <b>CA30103</b> <b>210 mm Air</b> (A0040947204)..... <b>CA30105</b> <b>Cab Air</b> (A9608300018)..... <b>PA30122</b> <b>Cab Air</b> (w/Carbon) (A9608300118)..... <b>PA30123</b> <b>Cab Air</b> (A9608300218)..... <b>PA30124</b> <b>Cab Air</b> (A0008307518)..... <b>PA5585<sup>90</sup></b> <b>Air Dryer</b> (A0004295695)..... <b>BA5379 +</b> <b>Coolant</b> (A4722030255)..... <b>P5092</b> <b>Steering</b> (A0004660604)..... <b>P106-HD</b> <b>Urea</b> (A0001421089)..... <b>PE17002 KIT</b> Actros II MP4 2442 w/OM471LA (BlueTec 5/6) Eng. (09/11-on) <b>Lube</b> (A4731800009)..... <b>P7505</b> <b>Fuel/Water Separator</b> (A9604770003)..... <b>BF1297-O</b> <b>Fuel</b> (Mahle Assembly) (A4710909052)..... <b>PF9908 KIT</b> <b>263 mm Air</b> (A0040946804)..... <b>CA30104</b> <b>228 mm Air</b> (A0040946904)..... <b>CA30103</b> <b>210 mm Air</b> (A0040947204)..... <b>CA30105</b> <b>Cab Air</b> (A9608300018)..... <b>PA30122</b> <b>Cab Air</b> (w/Carbon) (A9608300118)..... <b>PA30123</b> <b>Cab Air</b> (A9608300218)..... <b>PA30124</b> <b>Cab Air</b> (A0008307518)..... <b>PA5585<sup>90</sup></b> <b>Air Dryer</b> (A0004295695)..... <b>BA5379 +</b> <b>Coolant</b> (A4722030255)..... <b>P5092</b> <b>Steering</b> (A0004660604)..... <b>P106-HD</b> <b>Urea</b> (A0001421089)..... <b>PE17002 KIT</b> Actros II MP4 2443 w/OM470LA (BlueTec 5/6) Eng. (09/12-on) <b>Fuel/Water Separator</b> (A9604770003)..... <b>BF1297-O</b> <b>210 mm Air</b> (A0040947204)..... <b>CA30105</b> <b>228 mm Air</b> (A0040946904)..... <b>CA30103</b> <b>263 mm Air</b> (A0040946804)..... <b>CA30104</b> <b>Cab Air</b> (A9608300018)..... <b>PA30122</b> <b>Cab Air</b> (w/Carbon) (A9608300118)..... <b>PA30123</b> <b>Cab Air</b> (A0008307518)..... <b>PA5585</b> <b>Cab Air</b> (A9608300218)..... <b>PA30124</b> <b>Air Dryer</b> (A0004295695)..... <b>BA5379 +</b> <b>Steering</b> (A0004660604)..... <b>P106-HD</b> <b>Urea</b> (A0001421089)..... <b>PE17002 KIT</b>	Antos 2443 w/OM470LA (BlueTec 5/6) Eng. (09/12-on) <b>Fuel/Water Separator</b> (A9604770003)..... <b>BF1297-O</b> <b>210 mm Air</b> (A0040947204)..... <b>CA30105</b> <b>228 mm Air</b> (A0040946904)..... <b>CA30103</b> <b>263 mm Air</b> (A0040946804)..... <b>CA30104</b> <b>Cab Air</b> (A9608300018)..... <b>PA30122</b> <b>Cab Air</b> (w/Carbon) (A9608300118)..... <b>PA30123</b> <b>Cab Air</b> (A0008307518)..... <b>PA5585</b> <b>Cab Air</b> (A9608300218)..... <b>PA30124</b> <b>Air Dryer</b> (A0004295695)..... <b>BA5379 +</b> <b>Steering</b> (A0004660604)..... <b>P106-HD</b> <b>Urea</b> (A0001421089)..... <b>PE17002 KIT</b> Antos 2445 w/OM471LA (BlueTec 5/6) Eng. (09/12-on) <b>Lube</b> (A4731800009)..... <b>P7505</b> <b>Fuel/Water Separator</b> (A9604770003)..... <b>BF1297-O</b> <b>Fuel</b> (Mahle Assembly) (A4710909052)..... <b>PF9908 KIT</b> <b>263 mm Air</b> (A0040946804)..... <b>CA30104</b> <b>228 mm Air</b> (A0040946904)..... <b>CA30103</b> <b>210 mm Air</b> (A0040947204)..... <b>CA30105</b> <b>Cab Air</b> (A9608300018)..... <b>PA30122</b> <b>Cab Air</b> (w/Carbon) (A9608300118)..... <b>PA30123</b> <b>Cab Air</b> (A9608300218)..... <b>PA30124</b> <b>Cab Air</b> (A0008307518)..... <b>PA5585<sup>90</sup></b> <b>Air Dryer</b> (A0004295695)..... <b>BA5379 +</b> <b>Coolant</b> (A4722030255)..... <b>P5092</b> <b>Steering</b> (A0004660604)..... <b>P106-HD</b> <b>Urea</b> (A0001421089)..... <b>PE17002 KIT</b> Actros II MP4 2445 w/OM471LA (BlueTec 5/6) Eng. (09/11-on) <b>Lube</b> (A4731800009)..... <b>P7505</b> <b>Fuel/Water Separator</b> (A9604770003)..... <b>BF1297-O</b> <b>Fuel</b> (Mahle Assembly) (A4710909052)..... <b>PF9908 KIT</b> <b>263 mm Air</b> (A0040946804)..... <b>CA30104</b> <b>228 mm Air</b> (A0040946904)..... <b>CA30103</b> <b>210 mm Air</b> (A0040947204)..... <b>CA30105</b> <b>Cab Air</b> (A9608300018)..... <b>PA30122</b> <b>Cab Air</b> (w/Carbon) (A9608300118)..... <b>PA30123</b> <b>Cab Air</b> (A9608300218)..... <b>PA30124</b> <b>Cab Air</b> (A0008307518)..... <b>PA5585<sup>90</sup></b> <b>Air Dryer</b> (A0004295695)..... <b>BA5379 +</b> <b>Coolant</b> (A4722030255)..... <b>P5092</b> <b>Steering</b> (A0004660604)..... <b>P106-HD</b> <b>Urea</b> (A0001421089)..... <b>PE17002 KIT</b> Antos 2448 w/OM471LA (BlueTec 5/6) Eng. (09/12-on) <b>Lube</b> (A4731800009)..... <b>P7505</b> <b>Fuel/Water Separator</b> (A9604770003)..... <b>BF1297-O</b>

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.


Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Antos 2448 w/OM471LA (BlueTec 5/6) Eng. (09/12-on) (Cont'd) Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT 263 mm Air (A0040946804)..... CA30104 228 mm Air (A0040946904)..... CA30103 210 mm Air (A0040947204)..... CA30105 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A9608300218)..... PA30124 Cab Air (A0008307518)..... PA5585 <sup>90</sup> Air Dryer (A0004295695)..... BA5379 + Coolant (A4722030255)..... P5092 Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT	Actros II MP4 2451 w/OM471LA (BlueTec 5/6) Eng. (09/11-on) (Cont'd) Fuel/Water Separator (A9604770003)..... BF1297-O Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT 263 mm Air (A0040946804)..... CA30104 228 mm Air (A0040946904)..... CA30103 210 mm Air (A0040947204)..... CA30105 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A9608300218)..... PA30124 Cab Air (A0008307518)..... PA5585 <sup>90</sup> Air Dryer (A0004295695)..... BA5379 + Coolant (A4722030255)..... P5092 Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT	Antos 2463 w/OM473LA (BlueTec 6) Eng. (11/13-on) (Cont'd) Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A0008307518)..... PA5585 Cab Air (A9608300218)..... PA30124 Air Dryer (A9608300218)..... PA30124 Air Dryer (A0004295695)..... BA5379 + Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT
Actros II MP4 2448 w/OM471LA (BlueTec 5/6) Eng. (09/11-on) Lube (A4731800009)..... P7505 Fuel/Water Separator (A9604770003)..... BF1297-O Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT 263 mm Air (A0040946804)..... CA30104 228 mm Air (A0040946904)..... CA30103 210 mm Air (A0040947204)..... CA30105 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A9608300218)..... PA30124 Cab Air (A0008307518)..... PA5585 <sup>90</sup> Air Dryer (A0004295695)..... BA5379 + Coolant (A4722030255)..... P5092 Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT	Antos 2452 w/OM473LA (BlueTec 6) Eng. (11/13-on) Lube (A4731800009)..... P7505 Fuel/Water Separator (A9604770003)..... BF1297-O 263 mm Air (A0040946804)..... CA30104 228 mm Air (A0040946904)..... CA30103 210 mm Air (A0040947204)..... CA30105 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A0008307518)..... PA5585 Cab Air (A9608300218)..... PA30124 Air Dryer (A0004295695)..... BA5379 + Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT	Atego I 2523 w/OM906LA Eng. (09/98-on) Lube..... P7188 Fuel..... PF7735 Fuel/Water Separator..... BF1391-O Radial Seal Air (30949504)..... RS5342 Cab Air..... PA4945 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Steering..... P106-HD
Antos 2451 w/OM471LA (BlueTec 5/6) Eng. (09/12-on) Lube (A4731800009)..... P7505 Fuel/Water Separator (A9604770003)..... BF1297-O Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT 263 mm Air (A0040946804)..... CA30104 228 mm Air (A0040946904)..... CA30103 210 mm Air (A0040947204)..... CA30105 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A9608300218)..... PA30124 Cab Air (A0008307518)..... PA5585 <sup>90</sup> Air Dryer (A0004295695)..... BA5379 + Coolant (A4722030255)..... P5092 Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT	Antos 2458 w/OM473LA (BlueTec 6) Eng. (11/13-on) Lube (A4731800009)..... P7505 Fuel/Water Separator (A9604770003)..... BF1297-O 263 mm Air (A0040946804)..... CA30104 228 mm Air (A0040946904)..... CA30103 210 mm Air (A0040947204)..... CA30105 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A0008307518)..... PA5585 Cab Air (A9608300218)..... PA30124 Air Dryer (A0004295695)..... BA5379 + Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT	Axor II 2523 w/OM906LA Eng. (09/04-on) Lube..... P7188 Fuel..... PF7735 Fuel/Water Separator..... BF1391-O Pre-Fuel (924105)..... PF7939 Radial Seal Air (30949604)..... RS5342 Cab Air..... PA4945 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Steering..... P106-HD
Actros II MP4 2451 w/OM471LA (BlueTec 5/6) Eng. (09/11-on) Lube (A4731800009)..... P7505	Antos 2463 w/OM473LA (BlueTec 6) Eng. (11/13-on) Lube (A4731800009)..... P7505 Fuel/Water Separator (A9604770003)..... BF1297-O 263 mm Air (A0040946804)..... CA30104 228 mm Air (A0040946904)..... CA30103 210 mm Air (A0040947204)..... CA30105 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A0008307518)..... PA5585 Cab Air (A9608300218)..... PA30124 Air Dryer (A0004295695)..... BA5379 + Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT	Axors 2527 w/OM936LA (BlueTec 5/6) Eng. (04/13-on) Lube (A9361800009)..... P40003 Fuel/Water Separator (A9604770003)..... BF1297-O 210 mm Air (A0040947204)..... CA30105 228 mm Air (A0040946904)..... CA30103 263 mm Air (A0040946804)..... CA30104 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A0008307518)..... PA5585 Cab Air (A9608300218)..... PA30124 Air Dryer (A0004295695)..... BA5379 + Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT
Actros II MP4 2451 w/OM471LA (BlueTec 5/6) Eng. (09/11-on) Lube (A4731800009)..... P7505	Antos 2463 w/OM473LA (BlueTec 6) Eng. (11/13-on) Lube (A4731800009)..... P7505 Fuel/Water Separator (A9604770003)..... BF1297-O 263 mm Air (A0040946804)..... CA30104 228 mm Air (A0040946904)..... CA30103 210 mm Air (A0040947204)..... CA30105	Antos 2527 w/OM936LA (BlueTec 5/6) Eng. (09/12-on) Lube (A9361800009)..... P40003 Fuel/Water Separator (A9604770003)..... BF1297-O 210 mm Air (A0040947204)..... CA30105 228 mm Air (A0040946904)..... CA30103 263 mm Air (A0040946804)..... CA30104 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123

\* See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Antos 2527 w/OM936LA (BlueTec 5/6) Eng. (09/12-on) (Cont'd)	Arocs 2530 w/OM936LA (BlueTec 5/6) Eng. (04/13-on) (Cont'd)	Actros I 2531 w/OM501LA Eng. (09/96-12/03) (Cont'd)
Cab Air (A0008307518)..... PA5585	Steering (A0004660604)..... P106-HD	Crankcase Breather (5410100080)..... CV15001
Cab Air (A9608300218)..... PA30124	Urea (A0001421089)..... PE17002 KIT	Trans. (2690321)..... PT9423
Air Dryer (A0004295695)..... BA5379 +	Antos 2530 w/OM936LA (BlueTec 5/6) Eng. (09/12-on)	Steering (1902137)..... P106-HD
Steering (A0004660604)..... P106-HD	Lube (A9361800009)..... P40003	Arocs 2532 w/OM936LA (BlueTec 5/6) Eng. (04/13-on)
Urea (A0001421089)..... PE17002 KIT	Fuel/Water Separator (A9604770003)..... BF1297-O	Lube (A9361800009)..... P40003
Actros II MP4 2527 w/OM936LA (BlueTec 5/6) Eng. (09/12-on)	210 mm Air (A0040947204)..... CA30105	Fuel/Water Separator (A9604770003)..... BF1297-O
Lube (A9361800009)..... P40003	228 mm Air (A0040946904)..... CA30103	210 mm Air (A0040947204)..... CA30105
Fuel/Water Separator (A9604770003)..... BF1297-O	263 mm Air (A0040946804)..... CA30104	228 mm Air (A0040946904)..... CA30103
210 mm Air (A0040947204)..... CA30105	Cab Air (A9608300018)..... PA30122	263 mm Air (A0040946804)..... CA30104
228 mm Air (A0040946904)..... CA30103	Cab Air (w/Carbon) (A9608300118)..... PA30123	Cab Air (A9608300018)..... PA30122
263 mm Air (A0040946804)..... CA30104	Cab Air (A0008307518)..... PA5585	Cab Air (w/Carbon) (A9608300118)..... PA30123
Cab Air (A9608300018)..... PA30122	Cab Air (A9608300218)..... PA30124	Cab Air (A0008307518)..... PA5585
Cab Air (w/Carbon) (A9608300118)..... PA30123	Air Dryer (A0004295695)..... BA5379 +	Cab Air (A9608300218)..... PA30124
Cab Air (A0008307518)..... PA5585	Steering (A0004660604)..... P106-HD	Air Dryer (A0004295695)..... BA5379 +
Cab Air (A9608300218)..... PA30124	Urea (A0001421089)..... PE17002 KIT	Steering (A0004660604)..... P106-HD
Air Dryer (A0004295695)..... BA5379 +	Actros II MP4 2530 w/OM936LA (BlueTec 5/6) Eng. (09/12-on)	Urea (A0001421089)..... PE17002 KIT
Steering (A0004660604)..... P106-HD	Lube (A9361800009)..... P40003	Antos 2532 w/OM936LA (BlueTec 5/6) Eng. (09/12-on)
Urea (A0001421089)..... PE17002 KIT	Fuel/Water Separator (A9604770003)..... BF1297-O	Lube (A9361800009)..... P40003
Atego I 2528 w/OM906LA Eng. (09/98-on)	210 mm Air (A0040947204)..... CA30105	Fuel/Water Separator (A9604770003)..... BF1297-O
Lube..... P7188	228 mm Air (A0040946904)..... CA30103	210 mm Air (A0040947204)..... CA30105
Fuel..... PF7735	263 mm Air (A0040946804)..... CA30104	228 mm Air (A0040946904)..... CA30103
Fuel/Water Separator..... BF1391-O	Cab Air (A9608300018)..... PA30122	263 mm Air (A0040946804)..... CA30104
Radial Seal Air (30949504)..... RS5342	Cab Air (w/Carbon) (A9608300118)..... PA30123	Cab Air (A9608300018)..... PA30122
Cab Air..... PA4945	Cab Air (A0008307518)..... PA5585	Cab Air (w/Carbon) (A9608300118)..... PA30123
Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	Cab Air (A9608300218)..... PA30124	Cab Air (A0008307518)..... PA5585
Air Dryer (Coalescer) (4295695).. BA5379 +	Air Dryer (A0004295695)..... BA5379 +	Cab Air (A9608300218)..... PA30124
Steering..... P106-HD	Steering (A0004660604)..... P106-HD	Air Dryer (A0004295695)..... BA5379 +
Axor II 2528 w/OM906LA Eng. (09/04-on)	Urea (A0001421089)..... PE17002 KIT	Steering (A0004660604)..... P106-HD
Lube..... P7188	Actros I 2531 w/OM501LA Eng. (09/96-12/03)	Urea (A0001421089)..... PE17002 KIT
Fuel..... PF7735	F-F Lube Ele. (5411800009)..... P7192	Actros II MP4 2532 w/OM936LA (BlueTec 5/6) Eng. (09/12-on)
Fuel/Water Separator..... BF1391-O	B-P Lube (21840525)..... C704-L	Lube (A9361800009)..... P40003
Pre-Fuel (924105)..... PF7939	Pre-Fuel (924105)..... PF7939	Fuel/Water Separator (A9604770003)..... BF1297-O
Radial Seal Air (30949604)..... RS5342	Fuel (5410920305)..... PF7761	210 mm Air (A0040947204)..... CA30105
Cab Air..... PA4945	Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363	228 mm Air (A0040946904)..... CA30103
Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O	263 mm Air (A0040946804)..... CA30104
Air Dryer (Coalescer) (4295695).. BA5379 +	261.9 mm Air (A0030949204)..... PA3838 <sup>90</sup>	Cab Air (A9608300018)..... PA30122
Steering..... P106-HD	318.3 mm Air (A0030949104)..... PA3844	Cab Air (w/Carbon) (A9608300118)..... PA30123
Arocs 2530 w/OM936LA (BlueTec 5/6) Eng. (04/13-on)	Radial Seal Air (A0040940204)..... RS5343	Cab Air (A0008307518)..... PA5585
Lube (A9361800009)..... P40003	Panel Air (A0040941104)..... PA5426	Cab Air (A9608300218)..... PA30124
Fuel/Water Separator (A9604770003)..... BF1297-O	38.9 mm Height Cab Air (Mann CU3869)..... PA4956	Air Dryer (A0004295695)..... BA5379 +
210 mm Air (A0040947204)..... CA30105	40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	Steering (A0004660604)..... P106-HD
228 mm Air (A0040946904)..... CA30103	40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	Urea (A0001421089)..... PE17002 KIT
263 mm Air (A0040946804)..... CA30104	Air Dryer (Coalescer) (4295695).. BA5379 +	
Cab Air (A9608300018)..... PA30122	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	
Cab Air (w/Carbon) (A9608300118)..... PA30123		
Cab Air (A0008307518)..... PA5585		
Cab Air (A9608300218)..... PA30124		
Air Dryer (A0004295695)..... BA5379 +		

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.

Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Actros II 2532 (BlueTec 4/5) w/OM501LA Eng. (02/05-on)	Actros III 2532 BlueTec 4+5 w/OM501LA Eng. (03/08-on) (Cont'd)	Atego I 2533 w/OM926LA Eng. (10/02-on) (Cont'd)
F-F Lube..... P7192	Air Dryer (4295695)..... BA5379 +	Air Dryer (Coalescer) (4295695).. BA5379 +
Pre-Fuel (924105)..... PF7939	Steering..... P106-HD	Steering..... P106-HD
Fuel..... PF7761	Urea (A0001420089)..... PE5272	
Fuel/Water Separator..... BF1391-O	Actros II 2533 w/OM470LA (Euro 5/6) Eng. (09/12-on)	Axor II 2533 w/OM926LA Eng. (09/04-on)
338.1 mm Radial Seal Air w/Lid (Initial Installation)..... RS30065 KIT	Fuel/Water Separator (A9604770003)..... BF1297-O	Lube..... P7188
322.3 mm Radial Seal Air (Replacement Ele.) (40942404)..... RS30065	210 mm Air (A0040947204)..... CA30105	Fuel..... PF7735
532.6 mm Radial Seal Air (40943504)..... RS5358	228 mm Air (A0040946904)..... CA30103	Fuel/Water Separator..... BF1391-O
Urea Air (30947004)..... PA3765	263 mm Air (A0040946804)..... CA30104	Pre-Fuel (924105)..... PF7939
38.9 mm Height Cab Air..... PA4956	Cab Air (A9608300018)..... PA30122	Radial Seal Air (30949604)..... RS5342
40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	Cab Air (w/Carbon) (A9608300118)..... PA30123	Cab Air..... PA4945
40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	Cab Air (A0008307518)..... PA5585	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +
Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	Cab Air (A9608300218)..... PA30124	Air Dryer (Coalescer) (4295695).. BA5379 +
Air Dryer (Coalescer) (4295695).. BA5379 +	Air Dryer (A0004295695)..... BA5379 +	Steering..... P106-HD
Steering..... P106-HD	Steering (A0004660604)..... P106-HD	
	Urea (A0001421089)..... PE17002 KIT	Axros 2535 w/OM936LA (BlueTec 5/6) Eng. (04/13-on)
Actros II 2532 w/OM501LA Eng. (02/03-on)	Axros 2533 w/OM470LA (BlueTec 5/6) Eng. (04/13-on)	Lube (A9361800009)..... P40003
F-F Lube..... P7192	Fuel/Water Separator (A9604770003)..... BF1297-O	Fuel/Water Separator (A9604770003)..... BF1297-O
Pre-Fuel (924105)..... PF7939	210 mm Air (A0040947204)..... CA30105	210 mm Air (A0040947204)..... CA30105
Fuel..... PF7761	228 mm Air (A0040946904)..... CA30103	228 mm Air (A0040946904)..... CA30103
Fuel/Water Separator..... BF1391-O	263 mm Air (A0040946804)..... CA30104	263 mm Air (A0040946804)..... CA30104
Radial Seal Air (Initial Installation) (40942404)..... RS30065 KIT	Cab Air (A9608300018)..... PA30122	Cab Air (A9608300018)..... PA30122
Radial Seal Air (Replacement Ele.) (40942404)..... RS30065	Cab Air (w/Carbon) (A9608300118)..... PA30123	Cab Air (w/Carbon) (A9608300118)..... PA30123
Panel Air (A0040941104)..... PA5426	Cab Air (A0008307518)..... PA5585	Cab Air (A0008307518)..... PA5585
38.9 mm Height Cab Air..... PA4956	Cab Air (A9608300218)..... PA30124	Cab Air (A9608300218)..... PA30124
40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	Air Dryer (A0004295695)..... BA5379 +	Air Dryer (A0004295695)..... BA5379 +
40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	Steering (A0004660604)..... P106-HD	Steering (A0004660604)..... P106-HD
Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	Urea (A0001421089)..... PE17002 KIT	Urea (A0001421089)..... PE17002 KIT
Air Dryer (Coalescer) (4295695).. BA5379 +		
Crankcase Breather (5410100080)..... CV15001	Actros III 2532 BlueTec 4+5 w/OM501LA Eng. (03/08-on)	Antos 2533 w/OM936LA (BlueTec 5/6) Eng. (09/12-on)
Steering..... P106-HD	F-F Lube..... P7192	Lube (A9361800009)..... P40003
	Fuel/Water Separator..... BF1391-O	Fuel/Water Separator (A9604770003)..... BF1297-O
Actros III 2532 BlueTec 4+5 w/OM501LA Eng. (03/08-on)	P. Fuel..... PF7761	210 mm Air (A0040947204)..... CA30105
F-F Lube..... P7192	Pre-Fuel (924105)..... PF7939	228 mm Air (A0040946904)..... CA30103
Fuel/Water Separator..... BF1391-O	338.1 mm Radial Seal Air w/Lid (Initial Installation)..... RS30065 KIT	263 mm Air (A0040946804)..... CA30104
322.3 mm Radial Seal Air (Replacement Ele.)..... RS30065	322.3 mm Radial Seal Air (Replacement Ele.)..... RS30065	Cab Air (A9608300018)..... PA30122
532.6 mm Radial Seal Air..... RS5358	532.6 mm Radial Seal Air..... RS5358	Cab Air (w/Carbon) (A9608300118)..... PA30123
Air (w/Extra Urea Tank)..... PA3765	Air (w/Extra Urea Tank)..... PA3765	Cab Air (A0008307518)..... PA5585
379.4 mm Cab Air..... PA4956	379.4 mm Cab Air..... PA4956	Cab Air (A9608300218)..... PA30124
381.8 mm Cab Air (w/o Charcoal)..... PA4912	381.8 mm Cab Air (w/o Charcoal)..... PA4912	Air Dryer (A0004295695)..... BA5379 +
381.8 mm Cab Air (w/Charcoal) (A0008303418)..... PA5492	381.8 mm Cab Air (w/Charcoal) (A0008303418)..... PA5492	Steering (A0004660604)..... P106-HD
		Urea (A0001421089)..... PE17002 KIT
		Actros II MP4 2535 w/OM936LA (BlueTec 5/6) Eng. (09/12-on)
		Lube (A9361800009)..... P40003
		Fuel/Water Separator (A9604770003)..... BF1297-O
		210 mm Air (A0040947204)..... CA30105
		228 mm Air (A0040946904)..... CA30103
		263 mm Air (A0040946804)..... CA30104
		Cab Air (A9608300018)..... PA30122
		Cab Air (w/Carbon) (A9608300118)..... PA30123

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Actros II MP4 2535 w/OM936LA (BlueTec 5/6) Eng. (09/12-on) (Cont'd)	Arocs 2536 w/OM470LA (BlueTec 5/6) Eng. (04/13-on)	Actros II 2536 (BlueTec 4/5) w/OM501LA Eng. (02/05-on) (Cont'd)
<b>Cab Air</b> (A0008307518)..... <b>PA5585</b>	<b>Fuel/Water Separator</b> (A9604770003)..... <b>BF1297-O</b>	<b>38.9 mm Height Cab Air</b> ..... <b>PA4956</b>
<b>Cab Air</b> (A9608300218)..... <b>PA30124</b>	<b>210 mm Air</b> (A0040947204)..... <b>CA30105</b>	<b>40.5 mm Height Cab Air</b> (w/o Charcoal)..... <b>PA4912</b>
<b>Air Dryer</b> (A0004295695)..... <b>BA5379 +</b>	<b>228 mm Air</b> (A0040946904)..... <b>CA30103</b>	<b>40.5 mm Height Cab Air</b> (w/Charcoal) (A0008303418)..... <b>PA5492</b>
<b>Steering</b> (A0004660604)..... <b>P106-HD</b>	<b>263 mm Air</b> (A0040946804)..... <b>CA30104</b>	<b>Air Dryer</b> (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b>
<b>Urea</b> (A0001421089)..... <b>PE17002 KIT</b>	<b>Cab Air</b> (A9608300018)..... <b>PA30122</b>	<b>Air Dryer</b> (Coalescer) (4295695).. <b>BA5379 +</b>
Actros I 2535 w/OM501LA Eng. (09/96-12/03)	<b>Cab Air</b> (w/Carbon) (A9608300118)..... <b>PA30123</b>	<b>Steering</b> ..... <b>P106-HD</b>
<b>F-F Lube</b> (5411800009)..... <b>P7192</b>	<b>Cab Air</b> (A0008307518)..... <b>PA5585</b>	Actros II 2536 w/OM501LA Eng. (02/03-on)
<b>B-P Lube</b> (21840525)..... <b>C704-L</b>	<b>Cab Air</b> (A9608300218)..... <b>PA30124</b>	<b>F-F Lube</b> ..... <b>P7192</b>
<b>Pre-Fuel</b> (924105)..... <b>PF7939</b>	<b>Air Dryer</b> (A0004295695)..... <b>BA5379 +</b>	<b>Fuel</b> ..... <b>PF7761</b>
<b>Fuel</b> (5410920305)..... <b>PF7761</b>	<b>Steering</b> (A0004660604)..... <b>P106-HD</b>	<b>Fuel/Water Separator</b> ..... <b>BF1391-O</b>
<b>Fuel/Water Separator</b> (w/Drain) (A0004771302)..... <b>BF1363</b>	<b>Urea</b> (A0001421089)..... <b>PE17002 KIT</b>	<b>Pre-Fuel</b> (924105)..... <b>PF7939</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b>	Actros II 2536 w/OM470LA (Euro 5/6) Eng. (09/12-on)	<b>Radial Seal Air</b> (Initial Installation) (40942404)..... <b>RS30065 KIT</b>
<b>Radial Seal Air</b> (A0040940204)..... <b>RS5343</b>	<b>Fuel/Water Separator</b> (A9604770003)..... <b>BF1297-O</b>	<b>Radial Seal Air</b> (Replacement Ele.) (40942404)..... <b>RS30065</b>
<b>Panel Air</b> (A0040941104)..... <b>PA5426</b>	<b>210 mm Air</b> (A0040947204)..... <b>CA30105</b>	<b>Panel Air</b> (A0040941104)..... <b>PA5426</b>
<b>261.9 mm Air</b> (A0030949204)..... <b>PA3838<sup>90</sup></b>	<b>228 mm Air</b> (A0040946904)..... <b>CA30103</b>	<b>38.9 mm Height Cab Air</b> ..... <b>PA4956</b>
<b>318.3 mm Air</b> (A0030949104)..... <b>PA3844</b>	<b>263 mm Air</b> (A0040946804)..... <b>CA30104</b>	<b>40.5 mm Height Cab Air</b> (w/o Charcoal)..... <b>PA4912</b>
<b>38.9 mm Height Cab Air</b> (Mann CU3869)..... <b>PA4956</b>	<b>Cab Air</b> (A9608300018)..... <b>PA30122</b>	<b>40.5 mm Height Cab Air</b> (w/Charcoal) (A0008303418)..... <b>PA5492</b>
<b>40.5 mm Height Cab Air</b> (w/o Charcoal)..... <b>PA4912</b>	<b>Cab Air</b> (w/Carbon) (A9608300118)..... <b>PA30123</b>	<b>Air Dryer</b> (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b>
<b>40.5 mm Height Cab Air</b> (w/Charcoal) (A0008303418)..... <b>PA5492</b>	<b>Cab Air</b> (A0008307518)..... <b>PA5585</b>	<b>Air Dryer</b> (Coalescer) (4295695).. <b>BA5379 +</b>
<b>Air Dryer</b> (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b>	<b>Cab Air</b> (A9608300218)..... <b>PA30124</b>	<b>Crankcase Breather</b> (5410100080)..... <b>CV15001</b>
<b>Air Dryer</b> (Coalescer) (4295695).. <b>BA5379 +</b>	<b>Air Dryer</b> (A0004295695)..... <b>BA5379 +</b>	<b>Steering</b> ..... <b>P106-HD</b>
<b>Crankcase Breather</b> (5410100080)..... <b>CV15001</b>	<b>Steering</b> (A0004660604)..... <b>P106-HD</b>	Actros III 2536 BlueTec 4+5 w/OM501LA Eng. (03/08-on)
<b>Trans.</b> (2690321)..... <b>PT9423</b>	<b>Urea</b> (A0001421089)..... <b>PE17002 KIT</b>	<b>F-F Lube</b> ..... <b>P7192</b>
<b>Steering</b> (1902137)..... <b>P106-HD</b>	Antos 2536 w/OM470LA (BlueTec 5/6) Eng. (09/12-on)	<b>Fuel/Water Separator</b> ..... <b>BF1391-O</b>
Axor I 2535 w/OM457LA Eng. (10/02-12/04)	<b>Fuel/Water Separator</b> (A9604770003)..... <b>BF1297-O</b>	<b>P. Fuel</b> ..... <b>PF7761</b>
<b>Lube</b> ..... <b>P7230</b>	<b>210 mm Air</b> (A0040947204)..... <b>CA30105</b>	<b>Pre-Fuel</b> (924105)..... <b>PF7939</b>
<b>Fuel</b> ..... <b>PF7761</b>	<b>228 mm Air</b> (A0040946904)..... <b>CA30103</b>	<b>338.1 mm Radial Seal Air w/Lid</b> (Initial Installation)..... <b>RS30065 KIT</b>
<b>Fuel/Water Separator</b> ..... <b>BF1391-O</b>	<b>263 mm Air</b> (A0040946804)..... <b>CA30104</b>	<b>322.3 mm Radial Seal Air</b> (Replacement Ele.)..... <b>RS30065</b>
<b>Pre-Fuel</b> (924105)..... <b>PF7939</b>	<b>Cab Air</b> (A9608300018)..... <b>PA30122</b>	<b>532.6 mm Radial Seal Air</b> ..... <b>RS5358</b>
<b>261.9 mm Air</b> (10/01-03/03)..... <b>PA3838<sup>90</sup></b>	<b>Cab Air</b> (w/Carbon) (A9608300118)..... <b>PA30123</b>	<b>Air</b> (w/Extra Urea Tank)..... <b>PA3765</b>
<b>318.3 mm Air</b> (10/01-03/03)..... <b>PA3844</b>	<b>Cab Air</b> (A0008307518)..... <b>PA5585</b>	<b>379.4 mm Cab Air</b> ..... <b>PA4956</b>
<b>Cab Air</b> ..... <b>PA4945</b>	<b>Cab Air</b> (A9608300218)..... <b>PA30124</b>	<b>381.8 mm Cab Air</b> (w/o Charcoal)..... <b>PA4912</b>
<b>Air Dryer</b> (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b>	<b>Air Dryer</b> (A0004295695)..... <b>BA5379 +</b>	<b>381.8 mm Cab Air</b> (w/Charcoal) (A0008303418)..... <b>PA5492</b>
<b>Air Dryer</b> (Coalescer) (4295695).. <b>BA5379 +</b>	<b>Steering</b> (A0004660604)..... <b>P106-HD</b>	<b>Air Dryer</b> (4295695)..... <b>BA5379 +</b>
<b>Steering</b> ..... <b>P106-HD</b>	<b>Urea</b> (A0001421089)..... <b>PE17002 KIT</b>	<b>Steering</b> ..... <b>P106-HD</b>
Axor II 2535 w/OM457LA Eng. (09/04-on)	Actros II 2536 (BlueTec 4/5) w/OM501LA Eng. (02/05-on)	<b>Urea</b> (A0001420089)..... <b>PE5272</b>
<b>Lube</b> ..... <b>P7230</b>	<b>F-F Lube</b> ..... <b>P7192</b>	Axor II 2536 (BlueTec) w/OM457LA Eng. (09/05-on)
<b>Fuel</b> ..... <b>PF7761</b>	<b>Pre-Fuel</b> (924105)..... <b>PF7939</b>	<b>Lube</b> ..... <b>P7230</b>
<b>Fuel/Water Separator</b> ..... <b>BF1391-O</b>	<b>Fuel</b> ..... <b>PF7761</b>	<b>Fuel</b> ..... <b>PF7761</b>
<b>Pre-Fuel</b> (924105)..... <b>PF7939</b>	<b>Fuel/Water Separator</b> ..... <b>BF1391-O</b>	<b>Fuel/Water Separator</b> ..... <b>BF1391-O</b>
<b>Radial Seal Air</b> (Initial Installation) (40942404)..... <b>RS30065 KIT</b>	<b>338.1 mm Radial Seal Air w/Lid</b> (Initial Installation) (40942404)..... <b>RS30065 KIT</b>	<b>Pre-Fuel</b> (924105)..... <b>PF7939</b>
<b>Radial Seal Air</b> (Replacement Ele.) (40942404)..... <b>RS30065</b>	<b>322.3 mm Radial Seal Air</b> (Replacement Ele.) (40942404)..... <b>RS30065</b>	
<b>Cab Air</b> ..... <b>PA4945</b>	<b>532.6 mm Radial Seal Air</b> (40943504)..... <b>RS5358</b>	
<b>Air Dryer</b> (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b>	<b>Urea Air</b> (30947004)..... <b>PA3765</b>	
<b>Air Dryer</b> (Coalescer) (4295695).. <b>BA5379 +</b>		
<b>Steering</b> ..... <b>P106-HD</b>		

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.


Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Axor II 2536 (BlueTec) w/OM457LA Eng. (09/05-on) (Cont'd) 338.1 mm Radial Seal Air w/Lid (Initial Installation)..... <b>RS30065 KIT</b> Radial Seal Air (Replacement Ele.) (40942404)..... <b>RS30065</b> Cab Air..... <b>PA4945</b> Air Dryer (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer (Coalescer) (4295695).. <b>BA5379 +</b> Steering..... <b>P106-HD</b>	Arocs 2540 w/OM470LA (BlueTec 5/6) Eng. (04/13-on) Fuel/Water Separator (A9604770003)..... <b>BF1297-O</b> 210 mm Air (A0040947204)..... <b>CA30105</b> 228 mm Air (A0040946904)..... <b>CA30103</b> 263 mm Air (A0040946804)..... <b>CA30104</b> Cab Air (A9608300018)..... <b>PA30122</b> Cab Air (w/Carbon) (A9608300118)..... <b>PA30123</b> Cab Air (A0008307518)..... <b>PA5585</b> Cab Air (A9608300218)..... <b>PA30124</b> Air Dryer (A0004295695)..... <b>BA5379 +</b> Steering (A0004660604)..... <b>P106-HD</b> Urea (A0001421089)..... <b>PE17002 KIT</b>	Axor I 2540 w/OM457LA Eng. (10/02-12/04) Lube..... <b>P7230</b> Fuel..... <b>PF7761</b> Fuel/Water Separator..... <b>BF1391-O</b> Pre-Fuel (924105)..... <b>PF7939</b> 261.9 mm Air (10/01-03/03)..... <b>PA3838 90</b> 318.3 mm Air (10/01-03/03)..... <b>PA3844</b> Cab Air..... <b>PA4945</b> Air Dryer (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer (Coalescer) (4295695).. <b>BA5379 +</b> Steering..... <b>P106-HD</b>
Arocs 2539 w/OM470LA (BlueTec 5/6) Eng. (04/13-on) Fuel/Water Separator (A9604770003)..... <b>BF1297-O</b> 210 mm Air (A0040947204)..... <b>CA30105</b> 228 mm Air (A0040946904)..... <b>CA30103</b> 263 mm Air (A0040946804)..... <b>CA30104</b> Cab Air (A9608300018)..... <b>PA30122</b> Cab Air (w/Carbon) (A9608300118)..... <b>PA30123</b> Cab Air (A0008307518)..... <b>PA5585</b> Cab Air (A9608300218)..... <b>PA30124</b> Air Dryer (A0004295695)..... <b>BA5379 +</b> Steering (A0004660604)..... <b>P106-HD</b> Urea (A0001421089)..... <b>PE17002 KIT</b>	Antos 2540 w/OM470LA (BlueTec 5/6) Eng. (09/12-on) Fuel/Water Separator (A9604770003)..... <b>BF1297-O</b> 210 mm Air (A0040947204)..... <b>CA30105</b> 228 mm Air (A0040946904)..... <b>CA30103</b> 263 mm Air (A0040946804)..... <b>CA30104</b> Cab Air (A9608300018)..... <b>PA30122</b> Cab Air (w/Carbon) (A9608300118)..... <b>PA30123</b> Cab Air (A0008307518)..... <b>PA5585</b> Cab Air (A9608300218)..... <b>PA30124</b> Air Dryer (A0004295695)..... <b>BA5379 +</b> Steering (A0004660604)..... <b>P106-HD</b> Urea (A0001421089)..... <b>PE17002 KIT</b>	Axor II 2540 w/OM457LA Eng. (09/04-on) Lube..... <b>P7230</b> Fuel..... <b>PF7761</b> Fuel/Water Separator..... <b>BF1391-O</b> Pre-Fuel (924105)..... <b>PF7939</b> Radial Seal Air (Initial Installation) (40942404)..... <b>RS30065 KIT</b> Radial Seal Air (Replacement Ele.) (40942404)..... <b>RS30065</b> Cab Air..... <b>PA4945</b> Air Dryer (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer (Coalescer) (4295695).. <b>BA5379 +</b> Steering..... <b>P106-HD</b>
Actros II 2539 w/OM470LA (Euro 5/6) Eng. (09/12-on) Fuel/Water Separator (A9604770003)..... <b>BF1297-O</b> 210 mm Air (A0040947204)..... <b>CA30105</b> 228 mm Air (A0040946904)..... <b>CA30103</b> 263 mm Air (A0040946804)..... <b>CA30104</b> Cab Air (A9608300018)..... <b>PA30122</b> Cab Air (w/Carbon) (A9608300118)..... <b>PA30123</b> Cab Air (A0008307518)..... <b>PA5585</b> Cab Air (A9608300218)..... <b>PA30124</b> Air Dryer (A0004295695)..... <b>BA5379 +</b> Steering (A0004660604)..... <b>P106-HD</b> Urea (A0001421089)..... <b>PE17002 KIT</b>	Actros II 2540 w/OM501LA Eng. (09/96-12/03) F-F Lube (5411800009)..... <b>P7192</b> B-P Lube (21840525)..... <b>C704-L</b> Pre-Fuel (924105)..... <b>PF7939</b> Fuel (5410920305)..... <b>PF7761</b> Fuel/Water Separator (w/Drain) (A0004771302)..... <b>BF1363</b> Fuel/Water Separator (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b> Radial Seal Air (A0040940204)..... <b>RS5343</b> Panel Air (A0040941104)..... <b>PA5426</b> 261.9 mm Air (A0030949204)..... <b>PA3838 90</b> 318.3 mm Air (A0030949104)..... <b>PA3844</b> 38.9 mm Height Cab Air..... <b>PA4956</b> 40.5 mm Height Cab Air (w/o Charcoal)..... <b>PA4912</b> 40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... <b>PA5492</b> Air Dryer (Coalescer) (4295695).. <b>BA5379 +</b> Air Dryer (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> Crankcase Breather (5410100080)..... <b>CV15001</b> Trans. (2690321)..... <b>PT9423</b> Steering (1902137)..... <b>P106-HD</b>	Actros II 2541 (BlueTec 4/5) w/OM501LA Eng. (02/05-on) F-F Lube..... <b>P7192</b> Pre-Fuel (924105)..... <b>PF7939</b> Fuel..... <b>PF7761</b> Fuel/Water Separator..... <b>BF1391-O</b> 338.1 mm Radial Seal Air w/Lid (Initial Installation) (40942404)..... <b>RS30065 KIT</b> 322.3 mm Radial Seal Air (Replacement Ele.) (40942404)..... <b>RS30065</b> 532.6 mm Radial Seal Air (40943504)..... <b>RS5358</b> Air (w/Extra Urea Tank)..... <b>PA3765</b> 38.9 mm Height Cab Air..... <b>PA4956</b> 40.5 mm Height Cab Air (w/o Charcoal)..... <b>PA4912</b> 40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... <b>PA5492</b> Air Dryer (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer (Coalescer) (4295695).. <b>BA5379 +</b> Crankcase Breather (5410100080)..... <b>CV15001</b> Steering..... <b>P106-HD</b>
Actros II MP4 2540 w/OM470LA (BlueTec 5/6) Eng. (09/12-on) Fuel/Water Separator (A9604770003)..... <b>BF1297-O</b> 210 mm Air (A0040947204)..... <b>CA30105</b> 228 mm Air (A0040946904)..... <b>CA30103</b> 263 mm Air (A0040946804)..... <b>CA30104</b> Cab Air (A9608300018)..... <b>PA30122</b> Cab Air (w/Carbon) (A9608300118)..... <b>PA30123</b> Cab Air (A0008307518)..... <b>PA5585</b> Cab Air (A9608300218)..... <b>PA30124</b> Air Dryer (A0004295695)..... <b>BA5379 +</b> Steering (A0004660604)..... <b>P106-HD</b> Urea (A0001421089)..... <b>PE17002 KIT</b>	Actros II 2541 w/OM501LA Eng. (02/03-on) F-F Lube..... <b>P7192</b> Pre-Fuel (924105)..... <b>PF7939</b> Fuel..... <b>PF7761</b> Fuel/Water Separator..... <b>BF1391-O</b> Radial Seal Air (Initial Installation) (40942404)..... <b>RS30065 KIT</b> Radial Seal Air (Replacement Ele.) (40942404)..... <b>RS30065</b>	

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).


MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Actros II 2541 w/OM501LA Eng. (02/03-on) (Cont'd)	Actros II 2542 w/OM471LA (Euro 5/6) Eng. (09/11-on) (Cont'd)	Actros II 2543 w/OM470LA (Euro 5/6) Eng. (09/12-on) (Cont'd)
Panel Air (A0040941104)..... PA5426	Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT	Cab Air (w/Carbon) (A9608300118)..... PA30123
38.9 mm Height Cab Air..... PA4956	210 mm Air (A0040947204)..... CA30105	Cab Air (A0008307518)..... PA5585
40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	228 mm Air (A0040946904)..... CA30103	Cab Air (A9608300218)..... PA30124
40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	263 mm Air (A0040946804)..... CA30104	Air Dryer (A0004295695)..... BA5379 +
Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	Cab Air (A9608300018)..... PA30122	Steering (A0004660604)..... P106-HD
Air Dryer (Coalescer) (4295695).. BA5379 +	Cab Air (w/Carbon) (A9608300118)..... PA30123	Urea (A0001421089)..... PE17002 KIT
Crankcase Breather (5410100080)..... CV15001	Cab Air (A0008307518)..... PA5585	Antos 2543 w/OM470LA (BlueTec 5/6) Eng. (09/12-on)
Steering..... P106-HD	Cab Air (A9608300218)..... PA30124	Fuel/Water Separator (A9604770003)..... BF1297-O
Actros III 2541 BlueTec 4+5 w/OM501LA Eng. (03/08-on)	Air Dryer (A0004295695)..... BA5379 +	210 mm Air (A0040947204)..... CA30105
F-F Lube..... P7192	Coolant (A4722030255)..... P5092	228 mm Air (A0040946904)..... CA30103
Fuel/Water Separator..... BF1391-O	Steering (A0004660604)..... P106-HD	263 mm Air (A0040946804)..... CA30104
P. Fuel..... PF7761	Urea (A0001421089)..... PE17002 KIT	Cab Air (A9608300018)..... PA30122
Pre-Fuel (924105)..... PF7939	Arcos 2542 w/OM471LA (BlueTec 5/6) Eng. (04/13-on)	Cab Air (w/Carbon) (A9608300118)..... PA30123
338.1 mm Radial Seal Air w/Lid (Initial Installation)..... RS30065 KIT	Lube (A4721800309)..... P7505	Cab Air (A0008307518)..... PA5585
322.3 mm Radial Seal Air (Replacement Ele.)..... RS30065	Fuel/Water Separator (A9604770003)..... BF1297-O	Cab Air (A9608300218)..... PA30124
532.6 mm Radial Seal Air..... RS5358	Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT	Air Dryer (A0004295695)..... BA5379 +
Air (w/Extra Urea Tank)..... PA3765	210 mm Air (A0040947204)..... CA30105	Steering (A0004660604)..... P106-HD
379.4 mm Cab Air..... PA4956	228 mm Air (A0040946904)..... CA30103	Urea (A0001421089)..... PE5272
381.8 mm Cab Air (w/o Charcoal) ..... PA4912	263 mm Air (A0040946804)..... CA30104	Actros I 2543 w/OM501LA Eng. (09/96-12/03)
381.8 mm Cab Air (w/Charcoal) (A0008303418)..... PA5492	Cab Air (A9608300018)..... PA30122	F-F Lube (5411800009)..... P7192
Air Dryer (4295695)..... BA5379 +	Cab Air (w/Carbon) (A9608300118)..... PA30123	B-P Lube (21840525)..... C704-L
Steering..... P106-HD	Cab Air (A0008307518)..... PA5585	Pre-Fuel (924105)..... PF7939
Urea (A0001420089)..... PE5272	Cab Air (A9608300218)..... PA30124	Fuel (5410920305)..... PF7761
Antos 2542 w/OM471LA (BlueTec 5/6) Eng. (09/12-on)	Air Dryer (A0004295695)..... BA5379 +	Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363
Lube (A4731800009)..... P7505	Coolant (A4722030255)..... P5092	Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O
Fuel/Water Separator (A9604770003)..... BF1297-O	Steering (A0004660604)..... P106-HD	Radial Seal Air (A0040940204).. RS5343
Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT	Urea (A0001421089)..... PE17002 KIT	Panel Air (A0040941104)..... PA5426
263 mm Air (A0040946804)..... CA30104	Arcos 2543 w/OM470LA (BlueTec 5/6) Eng. (04/13-on)	261.9 mm Air (A0030949204)..... PA3838 <sup>90</sup>
228 mm Air (A0040946904)..... CA30103	Fuel/Water Separator (A9604770003)..... BF1297-O	318.3 mm Air (A0030949104)..... PA3844
210 mm Air (A0040947204)..... CA30105	210 mm Air (A0040947204)..... CA30105	38.9 mm Height Cab Air..... PA4956
Cab Air (A9608300018)..... PA30122	228 mm Air (A0040946904)..... CA30103	40.5 mm Height Cab Air (w/o Charcoal)..... PA4912
Cab Air (w/Carbon) (A9608300118)..... PA30123	263 mm Air (A0040946804)..... CA30104	40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492
Cab Air (A0008307518)..... PA5585	Cab Air (A9608300018)..... PA30122	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +
Cab Air (A9608300218)..... PA30124	Cab Air (w/Carbon) (A9608300118)..... PA30123	Air Dryer (Coalescer) (4295695).. BA5379 +
Cab Air (A0008307518)..... PA5585 <sup>90</sup>	Cab Air (A0008307518)..... PA5585	Crankcase Breather (5410100080)..... CV15001
Air Dryer (A0004295695)..... BA5379 +	Cab Air (A9608300218)..... PA30124	Trans. (2690321)..... PT9423
Coolant (A4722030255)..... P5092	Air Dryer (A0004295695)..... BA5379 +	Steering (1902137)..... P106-HD
Steering (A0004660604)..... P106-HD	Coolant (A0004660604)..... P106-HD	Axor I 2543 w/OM457LA Eng. (10/02-12/04)
Urea (A0001421089)..... PE17002 KIT	Urea (A0001421089)..... PE17002 KIT	Lube..... P7230
Actros II 2542 w/OM471LA (Euro 5/6) Eng. (09/11-on)	Actros II 2543 w/OM470LA (Euro 5/6) Eng. (09/12-on)	Fuel..... PF7761
Lube (A4721800309)..... P7505	Fuel/Water Separator (A9604770003)..... BF1297-O	Fuel/Water Separator..... BF1391-O
Fuel/Water Separator (A9604770003)..... BF1297-O	210 mm Air (A0040947204)..... CA30105	Pre-Fuel (924105)..... PF7939
Actros II 2542 w/OM471LA (Euro 5/6) Eng. (09/11-on)	228 mm Air (A0040946904)..... CA30103	261.9 mm Air (10/01-03/03)..... PA3838 <sup>90</sup>
Lube (A4721800309)..... P7505	263 mm Air (A0040946804)..... CA30104	318.3 mm Air (10/01-03/03)..... PA3844
Fuel/Water Separator (A9604770003)..... BF1297-O	Cab Air (A9608300018)..... PA30122	Cab Air..... PA4945
		Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Axor I 2543 w/OM457LA Eng. (10/02-12/04) (Cont'd) Air Dryer (Coalescer) (4295695).. BA5379 + Steering..... P106-HD	Actros II 2544 w/OM501LA Eng. (02/03-on) (Cont'd) Crankcase Breather (5410100080)..... CV15001 Steering..... P106-HD	Actros II 2545 w/OM471LA (Euro 5/6) Eng. (09/11-on) (Cont'd) Air Dryer (A0004295695)..... BA5379 + Coolant (A4722030255)..... P5092 Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT
Axor II 2543 w/OM457LA Eng. (09/04-on) Lube..... P7230 Fuel..... PF7761 Fuel/Water Separator..... BF1391-O Pre-Fuel (924105)..... PF7939 Radial Seal Air (Initial Installation) (40942404)..... RS30065 KIT Radial Seal Air (Replacement Ele.) (40942404)..... RS30065 Cab Air..... PA4945 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Steering..... P106-HD	Actros III 2544 BlueTec 4+5 w/OM501LA Eng. (03/08-on) F-F Lube..... P7192 Fuel/Water Separator..... BF1391-O P. Fuel..... PF7761 Pre-Fuel (924105)..... PF7939 338.1 mm Radial Seal Air w/Lid (Initial Installation)..... RS30065 KIT 322.3 mm Radial Seal Air (Replacement Ele.)..... RS30065 532.6 mm Radial Seal Air..... RS5358 Air (w/Extra Urea Tank)..... PA3765 379.4 mm Cab Air..... PA4956 381.8 mm Cab Air (w/o Charcoal) PA4912 381.8 mm Cab Air (w/Charcoal) (A0008303418)..... PA5492 Air Dryer (4295695)..... BA5379 + Steering..... P106-HD Urea (A0001420089)..... PE5272	Axros 2545 w/OM471LA (BlueTec 5/6) Eng. (04/13-on) Lube (A4721800309)..... P7505 Fuel/Water Separator (A9604770003)..... BF1297-O Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT 210 mm Air (A0040947204)..... CA30105 228 mm Air (A0040946904)..... CA30103 263 mm Air (A0040946804)..... CA30104 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A0008307518)..... PA5585 Cab Air (A9608300218)..... PA30124 Air Dryer (A0004295695)..... BA5379 + Coolant (A4722030255)..... P5092 Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT
Actros II 2544 (BlueTec 4/5) w/OM501LA Eng. (02/05-on) F-F Lube..... P7192 Pre-Fuel (924105)..... PF7939 Fuel..... PF7761 Fuel/Water Separator..... BF1391-O 338.1 mm Radial Seal Air w/Lid (Initial Installation) (40942404)... RS30065 KIT 322.3 mm Radial Seal Air (Replacement Ele.) (40942404)... RS30065 532.6 mm Radial Seal Air..... RS5358 Air (w/Extra Urea Tank)..... PA3765 38.9 mm Height Cab Air..... PA4956 40.5 mm Height Cab Air (w/o Charcoal)..... PA4912 40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Crankcase Breather (5410100080)..... CV15001 Steering..... P106-HD	Antos 2545 w/OM471LA (BlueTec 5/6) Eng. (09/12-on) Lube (A4731800009)..... P7505 Fuel/Water Separator (A9604770003)..... BF1297-O Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT 263 mm Air (A0040946804)..... CA30104 228 mm Air (A0040946904)..... CA30103 210 mm Air (A0040947204)..... CA30105 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A9608300218)..... PA30124 Cab Air (A0008307518)..... PA5585 <sup>90</sup> Air Dryer (A0004295695)..... BA5379 + Coolant (A4722030255)..... P5092 Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT	Axros I 2546 w/OM501LA Eng. (09/96-12/03) F-F Lube..... P7192 B-P Lube (21840525)..... C704-L Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363 Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O Pre-Fuel (924105)..... PF7939 Fuel..... PF7761 338.1 mm Radial Seal Air w/Lid (Initial Installation) (40942404)... RS30065 KIT 261.9 mm Air..... PA3838 <sup>90</sup> 318.3 mm Air..... PA3844 322.3 mm Radial Seal Air (Replacement Ele.) (40940204)... RS30065 Panel Air (A0040941104)..... PA5426 38.9 mm Height Cab Air..... PA4956 40.5 mm Height Cab Air (w/o Charcoal)..... PA4912 40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Crankcase Breather (5410100080)..... CV15001 Trans. (2690321)..... PT9423 Steering..... P106-HD
Actros II 2544 w/OM501LA Eng. (02/03-on) F-F Lube..... P7192 Pre-Fuel (924105)..... PF7939 Fuel..... PF7761 Fuel/Water Separator..... BF1391-O Radial Seal Air (Initial Installation) (40942404)..... RS30065 KIT Radial Seal Air (Replacement Ele.) (40942404)..... RS30065 Panel Air (A0040941104)..... PA5426 38.9 mm Height Cab Air..... PA4956 40.5 mm Height Cab Air (w/o Charcoal)..... PA4912 40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 +	Actros II 2545 w/OM471LA (Euro 5/6) Eng. (09/11-on) Lube (A4721800309)..... P7505 Fuel/Water Separator (A9604770003)..... BF1297-O Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT 210 mm Air (A0040947204)..... CA30105 228 mm Air (A0040946904)..... CA30103 263 mm Air (A0040946804)..... CA30104 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A0008307518)..... PA5585 Cab Air (A9608300218)..... PA30124	Actros II 2546 (BlueTec 4/5) w/OM501LA Eng. (02/05-on) F-F Lube..... P7192 Pre-Fuel (924105)..... PF7939 Fuel..... PF7761

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Actros II 2546 (BlueTec 4/5) w/OM501LA Eng. (02/05-on) (Cont'd)	Actros 2548 w/OM471LA (BlueTec 5/6) Eng. (09/12-on)	Actros II 2548 (BlueTec 4/5) w/OM501LA Eng. (02/05-on) (Cont'd)
Fuel/Water Separator..... BF1391-O	Lube (A4731800009)..... P7505	40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492
338.1 mm Radial Seal Air w/Lid (Initial Installation) (40942404)... RS30065 KIT	Fuel/Water Separator (A9604770003)..... BF1297-O	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +
322.3 mm Radial Seal Air (Replacement Ele.) (40942404)... RS30065	Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT	Air Dryer (Coalescer) (4295695).. BA5379 +
532.6 mm Radial Seal Air (40943504)..... RS5358	263 mm Air (A0040946804)..... CA30104	Steering..... P106-HD
Air (w/Extra Urea Tank)..... PA3765	228 mm Air (A0040946904)..... CA30103	Actros II 2548 w/OM471LA (Euro 5/6) Eng. (09/11-on)
38.9 mm Height Cab Air..... PA4956	210 mm Air (A0040947204)..... CA30105	Lube (A4721800309)..... P7505
40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	Cab Air (A9608300018)..... PA30122	Fuel/Water Separator (A9604770003)..... BF1297-O
40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	Cab Air (w/Carbon) (A9608300118)..... PA30123	Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT
Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	Cab Air (A9608300218)..... PA30124	210 mm Air (A0040947204)..... CA30105
Air Dryer (Coalescer) (4295695).. BA5379 +	Cab Air (A0008307518)..... PA5585 <sup>90</sup>	228 mm Air (A0040946904)..... CA30103
Steering..... P106-HD	Air Dryer (A0004295695)..... BA5379 +	263 mm Air (A0040946804)..... CA30104
Actros II 2546 w/OM501LA Eng. (02/03-on)	Coolant (A4722030255)..... P5092	Cab Air (A9608300018)..... PA30122
F-F Lube..... P7192	Steering (A0004660604)..... P106-HD	Cab Air (w/Carbon) (A9608300118)..... PA30123
Pre-Fuel (924105)..... PF7939	Urea (A0001421089)..... PE17002 KIT	Cab Air (A0008307518)..... PA5585
Fuel..... PF7761	Actros I 2548 w/OM502LA Eng. (09/96-12/03)	Cab Air (A9608300218)..... PA30124
Fuel/Water Separator..... BF1391-O	F-F Lube (5411800009)..... P7192	Air Dryer (A0004295695)..... BA5379 +
Radial Seal Air (Initial Installation) (40942404)..... RS30065 KIT	B-P Lube (21840525)..... C704-L	Coolant (A4722030255)..... P5092
Radial Seal Air (Replacement Ele.) (40942404)..... RS30065	Pre-Fuel (924105)..... PF7939	Steering (A0004660604)..... P106-HD
Panel Air (A0040941104)..... PA5426	Fuel (5410920305)..... PF7761	Urea (A0001421089)..... PE17002 KIT
38.9 mm Height Cab Air..... PA4956	Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363	Actros III 2548 BlueTec 4+5 w/OM501LA Eng. (03/08-on)
40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O	F-F Lube..... P7192
40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	318.3 mm Air (A0030949104)..... PA3844	Fuel/Water Separator..... BF1391-O
Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	496.9 mm Air (10947904)..... PA2475	P. Fuel..... PF7761
Air Dryer (Coalescer) (4295695).. BA5379 +	38.9 mm Height Cab Air (Mann CU3869)..... PA4956	Pre-Fuel (924105)..... PF7939
Crankcase Breather (5410100080)..... CV15001	40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	338.1 mm Radial Seal Air w/Lid (Initial Installation)..... RS30065 KIT
Steering..... P106-HD	40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	322.3 mm Radial Seal Air (Replacement Ele.)..... RS30065
Actros III 2546 BlueTec 4+5 w/OM501LA Eng. (03/08-on)	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	532.6 mm Radial Seal Air..... RS5358
F-F Lube..... P7192	Air Dryer (Coalescer) (4295695).. BA5379 +	Air (w/Extra Urea Tank)..... PA3765
Fuel/Water Separator..... BF1391-O	Crankcase Breather (5410100080)..... CV15001	379.4 mm Cab Air..... PA4956
P. Fuel..... PF7761	Trans. (2690321)..... PT9423	381.8 mm Cab Air (w/o Charcoal)..... PA4912
Pre-Fuel (924105)..... PF7939	Steering (1902137)..... P106-HD	381.8 mm Cab Air (w/Charcoal) (A0008303418)..... PA5492
338.1 mm Radial Seal Air w/Lid (Initial Installation)..... RS30065 KIT	Actros II 2548 (BlueTec 4/5) w/OM501LA Eng. (02/05-on)	Air Dryer (4295695)..... BA5379 +
322.3 mm Radial Seal Air (Replacement Ele.)..... RS30065	F-F Lube..... P7192	Steering..... P106-HD
532.6 mm Radial Seal Air..... RS5358	Pre-Fuel (924105)..... PF7939	Urea (A0001420089)..... PE5272
Air (w/Extra Urea Tank)..... PA3765	Fuel..... PF7761	Arcos 2548 w/OM471LA (BlueTec 5/6) Eng. (04/13-on)
379.4 mm Cab Air..... PA4956	Fuel/Water Separator..... BF1391-O	Lube (A4721800309)..... P7505
381.8 mm Cab Air (w/o Charcoal)..... PA4912	338.1 mm Radial Seal Air w/Lid (Initial Installation) (40942404)... RS30065 KIT	Fuel/Water Separator (A9604770003)..... BF1297-O
381.8 mm Cab Air (w/Charcoal) (A0008303418)..... PA5492	322.3 mm Radial Seal Air (Replacement Ele.) (40942404)... RS30065	Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT
Air Dryer (4295695)..... BA5379 +	532.6 mm Radial Seal Air (40943504)..... RS5358	210 mm Air (A0040947204)..... CA30105
Steering..... P106-HD	38.9 mm Height Cab Air..... PA4956	228 mm Air (A0040946904)..... CA30103
Urea (A0001420089)..... PE5272	40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	263 mm Air (A0040946804)..... CA30104

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.


Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Arocs 2548 w/OM471LA (BlueTec 5/6) Eng. (04/13-on) (Cont'd) Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A0008307518)..... PA5585 Cab Air (A9608300218)..... PA30124 Air Dryer (A0004295695)..... BA5379 + Coolant (A4722030255)..... P5092 Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT	Actros II 2551 (BlueTec 4/5) w/OM502LA Eng. (07/05-on) (Cont'd) 322.3 mm Radial Seal Air (Replacement Ele.) (40942404)... RS30065 532.6 mm Radial Seal Air (40943504)..... RS5358 Air (w/Extra Urea Tank)..... PA3765 38.9 mm Height Cab Air..... PA4956 40.5 mm Height Cab Air (w/o Charcoal)..... PA4912 40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Steering..... P106-HD	Arocs 2551 w/OM471LA (BlueTec 5/6) Eng. (04/13-on) (Cont'd) Fuel/Water Separator (A9604770003)..... BF1297-O Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT 210 mm Air (A0040947204)..... CA30105 228 mm Air (A0040946904)..... CA30103 263 mm Air (A0040946804)..... CA30104 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A0008307518)..... PA5585 Cab Air (A9608300218)..... PA30124 Air Dryer (A0004295695)..... BA5379 + Coolant (A4722030255)..... P5092 Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT
Actros II 2550 w/OM502LA Eng. (04/03-on) F-F Lube..... P7192 Pre-Fuel (924105)..... PF7939 Fuel..... PF7761 Fuel/Water Separator..... BF1391-O Radial Seal Air (Initial Installation) (40942404)..... RS30065 KIT Radial Seal Air (Replacement Ele.) (40942404)..... RS30065 Panel Air (A0040941104)..... PA5426 38.9 mm Height Cab Air..... PA4956 40.5 mm Height Cab Air (w/o Charcoal)..... PA4912 40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Crankcase Breather (5410100080)..... CV15001 Steering..... P106-HD	Actros II 2551 w/OM471LA (Euro 5/6) Eng. (09/11-on) Lube (A4721800309)..... P7505 Fuel/Water Separator (A9604770003)..... BF1297-O Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT 210 mm Air (A0040947204)..... CA30105 228 mm Air (A0040946904)..... CA30103 263 mm Air (A0040946804)..... CA30104 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A0008307518)..... PA5585 Cab Air (A9608300218)..... PA30124 Air Dryer (A0004295695)..... BA5379 + Coolant (A4722030255)..... P5092 Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT	Arocs 2552 w/OM473LA (BlueTec 5/6) Eng. (04/13-on) Lube (A4731800009)..... P7505 Fuel/Water Separator (A9604770003)..... BF1297-O 263 mm Air (A0040946804)..... CA30104 228 mm Air (A0040946904)..... CA30103 210 mm Air (A0040947204)..... CA30105 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A0008307518)..... PA5585 Cab Air (A9608300218)..... PA30124 Air Dryer (A0004295695)..... BA5379 + Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT
Antos 2551 w/OM471LA (BlueTec 5/6) Eng. (09/12-on) Lube (A4731800009)..... P7505 Fuel/Water Separator (A9604770003)..... BF1297-O Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT 263 mm Air (A0040946804)..... CA30104 228 mm Air (A0040946904)..... CA30103 210 mm Air (A0040947204)..... CA30105 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A9608300218)..... PA30124 Cab Air (A0008307518)..... PA5585 <sup>90</sup> Air Dryer (A0004295695)..... BA5379 + Coolant (A4722030255)..... P5092 Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT	Actros III 2551 BlueTec 4+5 w/OM502LA Eng. (03/08-on) F-F Lube..... P7192 Fuel/Water Separator..... BF1391-O P. Fuel..... PF7761 Pre-Fuel (924105)..... PF7939 338.1 mm Radial Seal Air w/Lid (Initial Installation)..... RS30065 KIT 322.3 mm Radial Seal Air (Replacement Ele.)..... RS30065 532.6 mm Radial Seal Air..... RS5358 Air (w/Extra Urea Tank)..... PA3765 379.4 mm Cab Air..... PA4956 381.8 mm Cab Air (w/o Charcoal) PA4912 381.8 mm Cab Air (w/Charcoal) (A0008303418)..... PA5492 Air Dryer (4295695)..... BA5379 + Steering..... P106-HD Urea (A0001420089)..... PE5272	Antos 2552 w/OM473LA (BlueTec 6) Eng. (11/13-on) Lube (A4731800009)..... P7505 Fuel/Water Separator (A9604770003)..... BF1297-O 263 mm Air (A0040946804)..... CA30104 228 mm Air (A0040946904)..... CA30103 210 mm Air (A0040947204)..... CA30105 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A0008307518)..... PA5585 Cab Air (A9608300218)..... PA30124 Air Dryer (A0004295695)..... BA5379 + Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT
Actros II 2551 (BlueTec 4/5) w/OM502LA Eng. (07/05-on) F-F Lube..... P7192 Pre-Fuel (924105)..... PF7939 Fuel..... PF7761 Fuel/Water Separator..... BF1391-O 338.1 mm Radial Seal Air w/Lid (Initial Installation) (40942404)... RS30065 KIT	Arocs 2551 w/OM471LA (BlueTec 5/6) Eng. (04/13-on) Lube (A4721800309)..... P7505	Actros II MP4 2552 w/OM473LA (BlueTec 5/6) Eng. (11/13-on) Lube (A4731800009)..... P7505 Fuel/Water Separator (A9604770003)..... BF1297-O 263 mm Air (A0040946804)..... CA30104 228 mm Air (A0040946904)..... CA30103 210 mm Air (A0040947204)..... CA30105

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Actros II MP4 2552 w/OM473LA (BlueTec 5/6) Eng. (11/13-on) (Cont'd)	Actros II 2555 (BlueTec 4/5) w/OM502LA Eng. (07/05-on)	Actros I 2557 w/OM502LA Eng. (09/96-12/03) (Cont'd)
Cab Air (A9608300018)..... PA30122	F-F Lube..... P7192	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +
Cab Air (w/Carbon) (A9608300118)..... PA30123	Pre-Fuel (924105)..... PF7939	Air Dryer (Coalescer) (4295695).. BA5379 +
Cab Air (A0008307518)..... PA5585	Fuel..... PF7761	Crankcase Breather (5410100080)..... CV15001
Cab Air (A9608300218)..... PA30124	Fuel/Water Separator..... BF1391-O	Trans. (2690321)..... PT9423
Air Dryer (A0004295695)..... BA5379 +	338.1 mm Radial Seal Air w/Lid (Initial Installation) (40942404)... RS30065 KIT	Steering (1902137)..... P106-HD
Steering (A0004660604)..... P106-HD	322.3 mm Radial Seal Air (Replacement Ele.) (40942404)... RS30065	Urea (A0001421089)..... PE17002 KIT
Urea (A0001421089)..... PE17002 KIT	532.6 mm Radial Seal Air (40943504)..... RS5358	Antos 2558 w/OM473LA (BlueTec 6) Eng. (11/13-on)
Actros I 2553 w/OM502LA Eng. (09/96-12/03)	Air (w/Extra Urea Tank)..... PA3765	Lube (A4731800009)..... P7505
F-F Lube (5411800009)..... P7192	38.9 mm Height Cab Air..... PA4956	Fuel/Water Separator (A9604770003)..... BF1297-O
B-P Lube (21840525)..... C704-L	40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	263 mm Air (A0040946804)..... CA30104
Pre-Fuel (924105)..... PF7939	40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	228 mm Air (A0040946904)..... CA30103
Fuel (5410920305)..... PF7761	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	210 mm Air (A0040947204)..... CA30105
Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363	Air Dryer (Coalescer) (4295695).. BA5379 +	Cab Air (A9608300018)..... PA30122
Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O	Steering..... P106-HD	Cab Air (w/Carbon) (A9608300118)..... PA30123
318.3 mm Air (A0030949104)..... PA3844	Actros III 2555 BlueTec 4+5 w/OM502LA Eng. (03/08-on)	Cab Air (A0008307518)..... PA5585
496.9 mm Air (10947904)..... PA2475	F-F Lube..... P7192	Cab Air (A9608300218)..... PA30124
38.9 mm Height Cab Air (CU3869)..... PA4956	Fuel/Water Separator..... BF1391-O	Air Dryer (A0004295695)..... BA5379 +
40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	P. Fuel..... PF7761	Steering (A0004660604)..... P106-HD
40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	Pre-Fuel (924105)..... PF7939	Urea (A0001421089)..... PE17002 KIT
Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	338.1 mm Radial Seal Air w/Lid (Initial Installation) (40942404)... RS30065 KIT	Actros II MP4 2558 w/OM473LA (BlueTec 5/6) Eng. (11/13-on)
Air Dryer (Coalescer) (4295695).. BA5379 +	322.3 mm Radial Seal Air (Replacement Ele.)..... RS30065	Lube (A4731800009)..... P7505
Crankcase Breather (5410100080)..... CV15001	532.6 mm Radial Seal Air..... RS5358	Fuel/Water Separator (A9604770003)..... BF1297-O
Trans. (2690321)..... PT9423	Air (w/Extra Urea Tank)..... PA3765	263 mm Air (A0040946804)..... CA30104
Steering (1902137)..... P106-HD	379.4 mm Cab Air..... PA4956	228 mm Air (A0040946904)..... CA30103
Actros II 2554 w/OM502LA Eng. (02/03-on)	381.8 mm Cab Air (w/o Charcoal)..... PA4912	210 mm Air (A0040947204)..... CA30105
F-F Lube..... P7192	381.8 mm Cab Air (w/Charcoal) (A0008303418)..... PA5492	Cab Air (A9608300018)..... PA30122
Pre-Fuel (924105)..... PF7939	Air Dryer (4295695)..... BA5379 +	Cab Air (w/Carbon) (A9608300118)..... PA30123
Fuel..... PF7761	Steering..... P106-HD	Cab Air (A0008307518)..... PA5585
Fuel/Water Separator..... BF1391-O	Urea (A0001420089)..... PE5272	Cab Air (A9608300218)..... PA30124
Radial Seal Air (Initial Installation) (40942404)..... RS30065 KIT	Actros I 2557 w/OM502LA Eng. (09/96-12/03)	Air Dryer (A0004295695)..... BA5379 +
Radial Seal Air (Replacement Ele.) (40942404)..... RS30065	F-F Lube (5411800009)..... P7192	Steering (A0004660604)..... P106-HD
Panel Air (A0040941104)..... PA5426	B-P Lube (21840525)..... C704-L	Urea (A0001421089)..... PE17002 KIT
38.9 mm Height Cab Air..... PA4956	Pre-Fuel (924105)..... PF7939	Actros II 2558 w/OM502LA Eng. (02/03-on)
40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	Fuel (5410920305)..... PF7761	F-F Lube..... P7192
40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363	Pre-Fuel (924105)..... PF7939
Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O	Fuel..... PF7761
Air Dryer (Coalescer) (4295695).. BA5379 +	318.3 mm Air (A0030949104)..... PA3844	Fuel/Water Separator..... BF1391-O
Crankcase Breather (5410100080)..... CV15001	496.9 mm Air (10947904)..... PA2475	Radial Seal Air (Initial Installation) (40942404)..... RS30065 KIT
Steering..... P106-HD	38.9 mm Height Cab Air (Mann CU3869)..... PA4956	Radial Seal Air (Replacement Ele.) (40942404)..... RS30065
	40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	Panel Air (A0040941104)..... PA5426
	40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	38.9 mm Height Cab Air..... PA4956
		40.5 mm Height Cab Air (w/o Charcoal)..... PA4912
		40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492
		Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Actros II 2558 w/OM502LA Eng. (02/03-on) (Cont'd) Air Dryer (Coalescer) (4295695).. BA5379 + Crankcase Breather (5410100080)..... CV15001 Steering..... P106-HD	Arocs 2563 w/OM473LA (BlueTec 5/6) Eng. (04/13-on) (Cont'd) Cab Air (A0008307518)..... PA5585 Cab Air (A9608300218)..... PA30124 Air Dryer (A0004295695)..... BA5379 + Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT	Antos 2627 w/OM936LA (BlueTec 5/6) Eng. (09/12-on) Lube (A9361800009)..... P40003 Fuel/Water Separator (A9604770003)..... BF1297-O 210 mm Air (A0040947204)..... CA30105 228 mm Air (A0040946904)..... CA30103 263 mm Air (A0040946804)..... CA30104 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A0008307518)..... PA5585 Cab Air (A9608300218)..... PA30124 Air Dryer (A0004295695)..... BA5379 + Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT
Actros II 2560 (BlueTec 4/5) w/OM502LA Eng. (07/05-on) F-F Lube..... P7192 Pre-Fuel (924105)..... PF7939 Fuel..... PF7761 Fuel/Water Separator..... BF1391-O 338.1 mm Radial Seal Air w/Lid (Initial Installation) (40942404)... RS30065 KIT 322.3 mm Radial Seal Air (Replacement Ele.) (40942404)... RS30065 532.6 mm Radial Seal Air (40943504)..... RS5358 Air (w/Extra Urea Tank)..... PA3765 38.9 mm Height Cab Air..... PA4956 40.5 mm Height Cab Air (w/o Charcoal)..... PA4912 40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Steering..... P106-HD	Antos 2563 w/OM473LA (BlueTec 6) Eng. (11/13-on) Lube (A4731800009)..... P7505 Fuel/Water Separator (A9604770003)..... BF1297-O 263 mm Air (A0040946804)..... CA30104 228 mm Air (A0040946904)..... CA30103 210 mm Air (A0040947204)..... CA30105 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A0008307518)..... PA5585 Cab Air (A9608300218)..... PA30124 Air Dryer (A0004295695)..... BA5379 + Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT	Actros II MP4 2627 w/OM936LA (BlueTec 5/6) Eng. (09/12-on) Lube (A9361800009)..... P40003 Fuel/Water Separator (A9604770003)..... BF1297-O 210 mm Air (A0040947204)..... CA30105 228 mm Air (A0040946904)..... CA30103 263 mm Air (A0040946804)..... CA30104 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A0008307518)..... PA5585 Cab Air (A9608300218)..... PA30124 Air Dryer (A0004295695)..... BA5379 + Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT
Actros III 2560 BlueTec 4+5 w/OM502LA Eng. (03/08-on) F-F Lube..... P7192 Fuel/Water Separator..... BF1391-O P. Fuel..... PF7761 Pre-Fuel (924105)..... PF7939 338.1 mm Radial Seal Air w/Lid (Initial Installation) (40942404)... RS30065 KIT 322.3 mm Radial Seal Air (Replacement Ele.)..... RS30065 532.6 mm Radial Seal Air..... RS5358 Air (w/Extra Urea Tank)..... PA3765 379.4 mm Cab Air..... PA4956 381.8 mm Cab Air (w/o Charcoal) 381.8 mm Cab Air (w/Charcoal) (A0008303418)..... PA5492 Air Dryer (4295695)..... BA5379 + Steering..... P106-HD Urea (A0001420089)..... PE5272	Actros II MP4 2563 w/OM473LA (BlueTec 5/6) Eng. (11/13-on) Lube (A4731800009)..... P7505 Fuel/Water Separator (A9604770003)..... BF1297-O 263 mm Air (A0040946804)..... CA30104 228 mm Air (A0040946904)..... CA30103 210 mm Air (A0040947204)..... CA30105 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A0008307518)..... PA5585 Cab Air (A9608300218)..... PA30124 Air Dryer (A0004295695)..... BA5379 + Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT	Actros II MP4 2627 w/OM936LA (BlueTec 5/6) Eng. (04/13-on) Lube (A9361800009)..... P40003 Fuel/Water Separator (A9604770003)..... BF1297-O 210 mm Air (A0040947204)..... CA30105 228 mm Air (A0040946904)..... CA30103 263 mm Air (A0040946804)..... CA30104 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A0008307518)..... PA5585 Cab Air (A9608300218)..... PA30124 Air Dryer (A0004295695)..... BA5379 + Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT
Arocs 2563 w/OM473LA (BlueTec 5/6) Eng. (04/13-on) Lube (A4731800009)..... P7505 Fuel/Water Separator (A9604770003)..... BF1297-O 263 mm Air (A0040946804)..... CA30104 228 mm Air (A0040946904)..... CA30103 210 mm Air (A0040947204)..... CA30105 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123	Arocs 2627 w/OM936LA (BlueTec 5/6) Eng. (04/13-on) Lube (A9361800009)..... P40003 Fuel/Water Separator (A9604770003)..... BF1297-O 210 mm Air (A0040947204)..... CA30105 228 mm Air (A0040946904)..... CA30103 263 mm Air (A0040946804)..... CA30104 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A0008307518)..... PA5585 Cab Air (A9608300218)..... PA30124 Air Dryer (A0004295695)..... BA5379 + Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT	Atego I 2628 w/OM906LA Eng. (07/98-on) Lube..... P7188 Fuel..... PF7735 Fuel/Water Separator..... BF1391-O Radial Seal Air (30949504)..... RS5342 Cab Air..... PA4945 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Steering..... P106-HD
		Axor II 2628 w/OM906LA Eng. (09/04-on) Lube..... P7188 Fuel..... PF7735 Fuel/Water Separator..... BF1391-O Pre-Fuel (924105)..... PF7939 Radial Seal Air (30949604)..... RS5342 Cab Air..... PA4945 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Steering..... P106-HD
		Econic 2628 w/OM906LA Eng. (07/98-on) Lube..... P7188 Fuel..... PF7735 Fuel/Water Separator..... BF1391-O Air..... PA3844

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Econic 2628 w/OM906LA Eng. (07/98-on) (Cont'd)	Antos 2630 w/OM936LA (BlueTec 5/6) Eng. (09/12-on)	Arocs 2632 w/OM936LA (BlueTec 5/6) Eng. (04/13-on)
Radial Seal Air (30949604)..... RS5342	Lube (A9361800009)..... P40003	Lube (A9361800009)..... P40003
Cab Air..... PA4945	Fuel/Water Separator	Fuel/Water Separator
Air Dryer (Desiccant) (Mann	(A9604770003)..... BF1297-O	(A9604770003)..... BF1297-O
TB1374X)..... BA5374 +	210 mm Air (A0040947204)..... CA30105	210 mm Air (A0040947204)..... CA30105
Air Dryer (Coalescer) (4295695).. BA5379 +	228 mm Air (A0040946904)..... CA30103	228 mm Air (A0040946904)..... CA30103
Steering..... P106-HD	263 mm Air (A0040946804)..... CA30104	263 mm Air (A0040946804)..... CA30104
Econic 2628 NTG w/M906LAG Eng. (09/02-on)	Cab Air (A9608300018)..... PA30122	Cab Air (A9608300018)..... PA30122
Lube..... P7188	Cab Air (w/Carbon)	Cab Air (w/Carbon)
Air..... PA3844	(A9608300118)..... PA30123	(A9608300118)..... PA30123
Radial Seal Air (30949604)..... RS5342	Cab Air (A0008307518)..... PA5585	Cab Air (A0008307518)..... PA5585
Cab Air..... PA4945	Cab Air (A9608300218)..... PA30124	Cab Air (A9608300218)..... PA30124
Air Dryer (Desiccant) (Mann	Air Dryer (A0004295695)..... BA5379 +	Air Dryer (A0004295695)..... BA5379 +
TB1374X)..... BA5374 +	Steering (A0004660604)..... P106-HD	Steering (A0004660604)..... P106-HD
Air Dryer (Coalescer) (4295695).. BA5379 +	Urea (A0001421089)..... PE17002 KIT	Urea (A0001421089)..... PE17002 KIT
Steering..... P106-HD	Actros II MP4 2630 w/OM936LA (BlueTec 5/6)	Actros 2632 w/OM936LA (BlueTec 5/6) Eng. (09/12-on)
Axor II 2629 (BlueTec) w/OM906LA Eng. (09/05-on)	Eng. (09/12-on)	Lube (A9361800009)..... P40003
Lube..... P7188	Lube (A9361800009)..... P40003	Fuel/Water Separator
Fuel..... PF7735	Fuel/Water Separator	(A9604770003)..... BF1297-O
Fuel/Water Separator..... BF1391-O	(A9604770003)..... BF1297-O	210 mm Air (A0040947204)..... CA30105
Pre-Fuel (924105)..... PF7939	210 mm Air (A0040947204)..... CA30105	228 mm Air (A0040946904)..... CA30103
Radial Seal Air (30949504)..... RS5342	228 mm Air (A0040946904)..... CA30103	263 mm Air (A0040946804)..... CA30104
Cab Air..... PA4945	263 mm Air (A0040946804)..... CA30104	Cab Air (A9608300018)..... PA30122
Air Dryer (Desiccant) (Mann	Cab Air (A9608300018)..... PA30122	Cab Air (w/Carbon)
TB1374X)..... BA5374 +	Cab Air (w/Carbon)	(A9608300118)..... PA30123
Air Dryer (Coalescer) (4295695).. BA5379 +	(A9608300118)..... PA30123	Cab Air (A0008307518)..... PA5585
Steering..... P106-HD	Cab Air (A0008307518)..... PA5585	Cab Air (A9608300218)..... PA30124
Econic 2629 w/OM906LA Eng. (09/06-on)	Cab Air (A9608300218)..... PA30124	Air Dryer (A0004295695)..... BA5379 +
Lube (A0001801709)..... P7188	Air Dryer (A0004295695)..... BA5379 +	Steering (A0004660604)..... P106-HD
Fuel/Water Separator (w/Drain)	Steering (A0004660604)..... P106-HD	Urea (A0001421089)..... PE17002 KIT
(A0004771302)..... BF1363	Urea (A0001421089)..... PE17002 KIT	Actros II MP4 2632 w/OM936LA (BlueTec 5/6)
Fuel/Water Separator (Open End	Actros I 2631 w/OM501LA Eng. (09/96-12/03)	Eng. (09/12-on)
for Bowl) (A0004771302)..... BF1391-O	F-F Lube (5411800009)..... P7192	Lube (A9361800009)..... P40003
Fuel Screen (A0000901351)..... PF7974	B-P Lube (21840525)..... C704-L	Fuel/Water Separator
Fuel Ele. (A0000901251)..... PF7735	Pre-Fuel (924105)..... PF7939	(A9604770003)..... BF1297-O
Air (A9570940004)..... PA2500	Fuel (5410920305)..... PF7761	210 mm Air (A0040947204)..... CA30105
Cab Air (9408350047)..... PA4945	Fuel/Water Separator (w/Drain)	228 mm Air (A0040946904)..... CA30103
Air Dryer (A0004295695)..... BA5379 +	(A0004771302)..... BF1363	263 mm Air (A0040946804)..... CA30104
Steering (A0004660604)..... P106-HD	Fuel/Water Separator (Open End	Cab Air (A9608300018)..... PA30122
Urea (A0001420089)..... PE5272	for Bowl) (A0004771302)..... BF1391-O	Cab Air (w/Carbon)
Arocs 2630 w/OM936LA (BlueTec 5/6) Eng. (04/13-on)	318.3 mm Air (A0030949104)..... PA3844	(A9608300118)..... PA30123
Lube (A9361800009)..... P40003	496.9 mm Air (10947904)..... PA2475	Cab Air (A0008307518)..... PA5585
Fuel/Water Separator	Radial Seal Air (A0040940204)..... RS5343	Cab Air (A9608300218)..... PA30124
(A9604770003)..... BF1297-O	Panel Air (A0040941104)..... PA5426	Air Dryer (A0004295695)..... BA5379 +
210 mm Air (A0040947204)..... CA30105	38.9 mm Height Cab Air (Mann	Steering (A0004660604)..... P106-HD
228 mm Air (A0040946904)..... CA30103	CU3869)..... PA4956	Urea (A0001421089)..... PE17002 KIT
263 mm Air (A0040946804)..... CA30104	40.5 mm Height Cab Air (w/o	Actros II 2632 w/OM501LA Eng. (04/03-on)
Cab Air (A9608300018)..... PA30122	Charcoal)..... PA4912	F-F Lube..... P7192
Cab Air (w/Carbon)	40.5 mm Height Cab Air	Pre-Fuel (924105)..... PF7939
(A9608300118)..... PA30123	(w/Charcoal) (A0008303418)..... PA5492	Fuel..... PF7761
Cab Air (A0008307518)..... PA5585	Air Dryer (Desiccant) (Mann	Fuel/Water Separator..... BF1391-O
Cab Air (A9608300218)..... PA30124	TB1374X)..... BA5374 +	Radial Seal Air (Initial Installation)
Air Dryer (A0004295695)..... BA5379 +	Air Dryer (Coalescer) (4295695).. BA5379 +	(40942404)..... RS30065 KIT
Steering (A0004660604)..... P106-HD	Crankcase Breather	Radial Seal Air (Replacement
Urea (A0001421089)..... PE17002 KIT	(5410100080)..... CV15001	Ele.) (40942404)..... RS30065
	Trans. (2690321)..... PT9423	
	Steering (1902137)..... P106-HD	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Actros II 2632 w/OM501LA Eng. (04/03-on) (Cont'd)	Actros II MP4 2633 w/OM470LA (BlueTec 5/6) Eng. (09/12-on) (Cont'd)	Econic 2633 w/OM926LA Eng. (05/04-on)
Radial Seal Air (9/03-on) (40943504)..... RS5358	Cab Air (A9608300018)..... PA30122	Lube..... P7188
Air (w/Extra Urea Tank)..... PA3765	Cab Air (w/Carbon) (A9608300118)..... PA30123	Fuel..... PF7735
Panel Air (A0040941104)..... PA5426	Cab Air (A0008307518)..... PA5585	Fuel/Water Separator..... BF1391-O
38.9 mm Height Cab Air..... PA4956	Cab Air (A9608300218)..... PA30124	Air..... PA3844
40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	Air Dryer (A0004295695)..... BA5379 +	Radial Seal Air (30949604)..... RS5342
40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	Steering (A0004660604)..... P106-HD	Cab Air..... PA4945
Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	Urea (A0001421089)..... PE17002 KIT	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +
Air Dryer (Coalescer) (4295695).. BA5379 +		Air Dryer (Coalescer) (4295695).. BA5379 +
Crankcase Breather (5410100080)..... CV15001	Antos 2633 w/OM470LA (BlueTec 5/6) Eng. (09/12-on)	Steering..... P106-HD
Steering..... P106-HD	Fuel/Water Separator (A9604770003)..... BF1297-O	
Actros III 2632 BlueTec 4+5 w/OM501LA Eng. (03/08-on)	210 mm Air (A0040947204)..... CA30105	Aprocs 2635 w/OM936LA (BlueTec 5/6) Eng. (04/13-on)
F-F Lube..... P7192	228 mm Air (A0040946904)..... CA30103	Lube (A9361800009)..... P40003
Fuel/Water Separator..... BF1391-O	263 mm Air (A0040946804)..... CA30104	Fuel/Water Separator (A9604770003)..... BF1297-O
P. Fuel..... PF7761	Cab Air (A9608300018)..... PA30122	210 mm Air (A0040947204)..... CA30105
Pre-Fuel (924105)..... PF7939	Cab Air (w/Carbon) (A9608300118)..... PA30123	228 mm Air (A0040946904)..... CA30103
338.1 mm Radial Seal Air w/Lid (Initial Installation)..... RS30065 KIT	Cab Air (A0008307518)..... PA5585	263 mm Air (A0040946804)..... CA30104
322.3 mm Radial Seal Air (Replacement Ele.)..... RS30065	Cab Air (A9608300218)..... PA30124	Cab Air (A9608300018)..... PA30122
532.6 mm Radial Seal Air..... RS5358	Air Dryer (A0004295695)..... BA5379 +	Cab Air (w/Carbon) (A9608300118)..... PA30123
Air (w/Extra Urea Tank)..... PA3765	Steering (A0004660604)..... P106-HD	Cab Air (A0008307518)..... PA5585
379.4 mm Cab Air..... PA4956	Urea (A0001421089)..... PE17002 KIT	Cab Air (A9608300218)..... PA30124
381.8 mm Cab Air (w/o Charcoal) ..... PA4912		Air Dryer (A0004295695)..... BA5379 +
381.8 mm Cab Air (w/Charcoal) (A0008303418)..... PA5492	Atego I 2633 w/OM926LA Eng. (10/02-on)	Steering (A0004660604)..... P106-HD
Air Dryer (4295695)..... BA5379 +	Lube..... P7188	Urea (A0001421089)..... PE17002 KIT
Steering..... P106-HD	Fuel..... PF7735	
Urea (A0001420089)..... PE5272	Fuel/Water Separator..... BF1391-O	Antos 2635 w/OM936LA (BlueTec 5/6) Eng. (09/12-on)
Aprocs 2633 w/OM470LA (BlueTec 5/6) Eng. (04/13-on)	Radial Seal Air (30949504)..... RS5342	Lube (A9361800009)..... P40003
Fuel/Water Separator (A9604770003)..... BF1297-O	Cab Air..... PA4945	Fuel/Water Separator (A9604770003)..... BF1297-O
210 mm Air (A0040947204)..... CA30105	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	210 mm Air (A0040947204)..... CA30105
228 mm Air (A0040946904)..... CA30103	Air Dryer (Coalescer) (4295695).. BA5379 +	228 mm Air (A0040946904)..... CA30103
263 mm Air (A0040946804)..... CA30104	Steering..... P106-HD	263 mm Air (A0040946804)..... CA30104
Cab Air (A9608300018)..... PA30122		Cab Air (A9608300018)..... PA30122
Cab Air (w/Carbon) (A9608300118)..... PA30123	Axor II 2633 (BlueTec) w/OM926LA Eng. (09/05-on)	Cab Air (w/Carbon) (A9608300118)..... PA30123
Cab Air (A0008307518)..... PA5585	Lube..... P7188	Cab Air (A0008307518)..... PA5585
Cab Air (A9608300218)..... PA30124	Fuel..... PF7735	Cab Air (A9608300218)..... PA30124
Air Dryer (A0004295695)..... BA5379 +	Fuel/Water Separator..... BF1391-O	Air Dryer (A0004295695)..... BA5379 +
Steering (A0004660604)..... P106-HD	Pre-Fuel (924105)..... PF7939	Steering (A0004660604)..... P106-HD
Urea (A0001421089)..... PE17002 KIT	Radial Seal Air (30949504)..... RS5342	Urea (A0001421089)..... PE17002 KIT
Actros II MP4 2633 w/OM470LA (BlueTec 5/6) Eng. (09/12-on)	Cab Air..... PA4945	
Fuel/Water Separator (A9604770003)..... BF1297-O	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	Actros II MP4 2635 w/OM936LA (BlueTec 5/6) Eng. (09/12-on)
210 mm Air (A0040947204)..... CA30105	Air Dryer (Coalescer) (4295695).. BA5379 +	Lube (A9361800009)..... P40003
228 mm Air (A0040946904)..... CA30103	Steering..... P106-HD	Fuel/Water Separator (A9604770003)..... BF1297-O
263 mm Air (A0040946804)..... CA30104		210 mm Air (A0040947204)..... CA30105
Cab Air (A9608300018)..... PA30122	Axor II 2633 w/OM926LA Eng. (09/04-on)	228 mm Air (A0040946904)..... CA30103
Cab Air (w/Carbon) (A9608300118)..... PA30123	Lube..... P7188	263 mm Air (A0040946804)..... CA30104
Cab Air (A0008307518)..... PA5585	Fuel..... PF7735	Cab Air (A9608300018)..... PA30122
Cab Air (A9608300218)..... PA30124	Fuel/Water Separator..... BF1391-O	Cab Air (w/Carbon) (A9608300118)..... PA30123
Air Dryer (A0004295695)..... BA5379 +	Pre-Fuel (924105)..... PF7939	Cab Air (A0008307518)..... PA5585
Steering (A0004660604)..... P106-HD	Radial Seal Air (30949504)..... RS5342	Cab Air (A9608300218)..... PA30124
Urea (A0001421089)..... PE17002 KIT	Cab Air..... PA4945	Air Dryer (A0004295695)..... BA5379 +
Actros II MP4 2633 w/OM470LA (BlueTec 5/6) Eng. (09/12-on)	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	Steering (A0004660604)..... P106-HD
Fuel/Water Separator (A9604770003)..... BF1297-O	Air Dryer (Coalescer) (4295695).. BA5379 +	
210 mm Air (A0040947204)..... CA30105	Steering..... P106-HD	
228 mm Air (A0040946904)..... CA30103		
263 mm Air (A0040946804)..... CA30104		

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Actros II MP4 2635 w/OM936LA (BlueTec 5/6) Eng. (09/12-on) (Cont'd) Urea (A0001421089)..... <b>PE17002 KIT</b>	Actros II MP4 2636 w/OM470LA (BlueTec 5/6) Eng. (09/12-on) (Cont'd) Urea (A0001421089)..... <b>PE17002 KIT</b>	Actros III 2636 BlueTec 4+5 w/OM501LA Eng. (03/08-on) (Cont'd) Steering..... <b>P106-HD</b> Urea (A0001420089)..... <b>PE5272</b>
Actros I 2635 w/OM501LA Eng. (09/96-12/03) F-F Lube (5411800009)..... <b>P7192</b> B-P Lube (21840525)..... <b>C704-L</b> Pre-Fuel (924105)..... <b>PF7939</b> Fuel (5410920305)..... <b>PF7761</b> Fuel/Water Separator (w/Drain) (A0004771302)..... <b>BF1363</b> Fuel/Water Separator (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b> 261.9 mm Air (A0030949204)..... <b>PA3838</b> <sup>90</sup> 318.3 mm Air (A0030949104)..... <b>PA3844</b> Radial Seal Air (A0040940204)..... <b>RS5343</b> Panel Air (A0040941104)..... <b>PA5426</b> 38.9 mm Height Cab Air (Mann CU3869)..... <b>PA4956</b> 40.5 mm Height Cab Air (w/o Charcoal)..... <b>PA4912</b> 40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... <b>PA5492</b> Air Dryer (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer (Coalescer) (4295695)..... <b>BA5379 +</b> Crankcase Breather (5410100080)..... <b>CV15001</b> Trans. (2690321)..... <b>PT9423</b> Steering (1902137)..... <b>P106-HD</b>	Antos 2636 w/OM470LA (BlueTec 5/6) Eng. (09/12-on) Fuel/Water Separator (A9604770003)..... <b>BF1297-O</b> 210 mm Air (A0040947204)..... <b>CA30105</b> 228 mm Air (A0040946904)..... <b>CA30103</b> 263 mm Air (A0040946804)..... <b>CA30104</b> Cab Air (A9608300018)..... <b>PA30122</b> Cab Air (w/Carbon) (A9608300118)..... <b>PA30123</b> Cab Air (A0008307518)..... <b>PA5585</b> Cab Air (A9608300218)..... <b>PA30124</b> Air Dryer (A0004295695)..... <b>BA5379 +</b> Steering (A0004660604)..... <b>P106-HD</b> Urea (A0001421089)..... <b>PE17002 KIT</b>	Arcos 2639 w/OM470LA (BlueTec 5/6) Eng. (04/13-on) Fuel/Water Separator (A9604770003)..... <b>BF1297-O</b> 210 mm Air (A0040947204)..... <b>CA30105</b> 228 mm Air (A0040946904)..... <b>CA30103</b> 263 mm Air (A0040946804)..... <b>CA30104</b> Cab Air (A9608300018)..... <b>PA30122</b> Cab Air (w/Carbon) (A9608300118)..... <b>PA30123</b> Cab Air (A0008307518)..... <b>PA5585</b> Cab Air (A9608300218)..... <b>PA30124</b> Air Dryer (A0004295695)..... <b>BA5379 +</b> Steering (A0004660604)..... <b>P106-HD</b> Urea (A0001421089)..... <b>PE17002 KIT</b>
Arcos 2636 w/OM470LA (BlueTec 5/6) Eng. (04/13-on) Fuel/Water Separator (A9604770003)..... <b>BF1297-O</b> 210 mm Air (A0040947204)..... <b>CA30105</b> 228 mm Air (A0040946904)..... <b>CA30103</b> 263 mm Air (A0040946804)..... <b>CA30104</b> Cab Air (A9608300018)..... <b>PA30122</b> Cab Air (w/Carbon) (A9608300118)..... <b>PA30123</b> Cab Air (A0008307518)..... <b>PA5585</b> Cab Air (A9608300218)..... <b>PA30124</b> Air Dryer (A0004295695)..... <b>BA5379 +</b> Steering (A0004660604)..... <b>P106-HD</b> Urea (A0001421089)..... <b>PE17002 KIT</b>	Actros II 2636 w/OM501LA Eng. (04/03-on) F-F Lube..... <b>P7192</b> Pre-Fuel (924105)..... <b>PF7939</b> Fuel..... <b>PF7761</b> Fuel/Water Separator..... <b>BF1391-O</b> Radial Seal Air (Initial Installation) (40942404)..... <b>RS30065 KIT</b> Radial Seal Air (Replacement Ele.) (40942404)..... <b>RS30065</b> Radial Seal Air (9/03-on) (40943504)..... <b>RS5358</b> Panel Air (A0040941104)..... <b>PA5426</b> 38.9 mm Height Cab Air..... <b>PA4956</b> 40.5 mm Height Cab Air (w/o Charcoal)..... <b>PA4912</b> 40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... <b>PA5492</b> Air Dryer (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer (Coalescer) (4295695)..... <b>BA5379 +</b> Crankcase Breather (5410100080)..... <b>CV15001</b> Steering..... <b>P106-HD</b>	Actros II MP4 2640 w/OM470LA (BlueTec 5/6) Eng. (09/12-on) Fuel/Water Separator (A9604770003)..... <b>BF1297-O</b> 210 mm Air (A0040947204)..... <b>CA30105</b> 228 mm Air (A0040946904)..... <b>CA30103</b> 263 mm Air (A0040946804)..... <b>CA30104</b> Cab Air (A9608300018)..... <b>PA30122</b> Cab Air (w/Carbon) (A9608300118)..... <b>PA30123</b> Cab Air (A0008307518)..... <b>PA5585</b> Cab Air (A9608300218)..... <b>PA30124</b> Air Dryer (A0004295695)..... <b>BA5379 +</b> Steering (A0004660604)..... <b>P106-HD</b> Urea (A0001421089)..... <b>PE17002 KIT</b>
Arcos 2640 w/OM470LA (BlueTec 5/6) Eng. (04/13-on) Fuel/Water Separator (A9604770003)..... <b>BF1297-O</b> 210 mm Air (A0040947204)..... <b>CA30105</b> 228 mm Air (A0040946904)..... <b>CA30103</b> 263 mm Air (A0040946804)..... <b>CA30104</b> Cab Air (A9608300018)..... <b>PA30122</b> Cab Air (w/Carbon) (A9608300118)..... <b>PA30123</b> Cab Air (A0008307518)..... <b>PA5585</b> Cab Air (A9608300218)..... <b>PA30124</b> Air Dryer (A0004295695)..... <b>BA5379 +</b> Steering (A0004660604)..... <b>P106-HD</b> Urea (A0001421089)..... <b>PE17002 KIT</b>	Actros III 2636 BlueTec 4+5 w/OM501LA Eng. (03/08-on) F-F Lube..... <b>P7192</b> Fuel/Water Separator..... <b>BF1391-O</b> P. Fuel..... <b>PF7761</b> Pre-Fuel (924105)..... <b>PF7939</b> 338.1 mm Radial Seal Air w/Lid (Initial Installation)..... <b>RS30065 KIT</b> 322.3 mm Radial Seal Air (Replacement Ele.)..... <b>RS30065</b> 532.6 mm Radial Seal Air..... <b>RS5358</b> Air (w/Extra Urea Tank)..... <b>PA3765</b> 379.4 mm Cab Air..... <b>PA4956</b> 381.8 mm Cab Air (w/o Charcoal)..... <b>PA4912</b> 381.8 mm Cab Air (w/Charcoal) (A0008303418)..... <b>PA5492</b> Air Dryer (4295695)..... <b>BA5379 +</b>	Arcos 2640 w/OM470LA (BlueTec 5/6) Eng. (09/12-on) Fuel/Water Separator (A9604770003)..... <b>BF1297-O</b> 210 mm Air (A0040947204)..... <b>CA30105</b> 228 mm Air (A0040946904)..... <b>CA30103</b> 263 mm Air (A0040946804)..... <b>CA30104</b> Cab Air (A9608300018)..... <b>PA30122</b>
Actros II MP4 2636 w/OM470LA (BlueTec 5/6) Eng. (09/12-on) Fuel/Water Separator (A9604770003)..... <b>BF1297-O</b> 210 mm Air (A0040947204)..... <b>CA30105</b> 228 mm Air (A0040946904)..... <b>CA30103</b> 263 mm Air (A0040946804)..... <b>CA30104</b> Cab Air (A9608300018)..... <b>PA30122</b> Cab Air (w/Carbon) (A9608300118)..... <b>PA30123</b> Cab Air (A0008307518)..... <b>PA5585</b> Cab Air (A9608300218)..... <b>PA30124</b> Air Dryer (A0004295695)..... <b>BA5379 +</b> Steering (A0004660604)..... <b>P106-HD</b>	Actros III 2636 BlueTec 4+5 w/OM501LA Eng. (03/08-on) F-F Lube..... <b>P7192</b> Fuel/Water Separator..... <b>BF1391-O</b> P. Fuel..... <b>PF7761</b> Pre-Fuel (924105)..... <b>PF7939</b> 338.1 mm Radial Seal Air w/Lid (Initial Installation)..... <b>RS30065 KIT</b> 322.3 mm Radial Seal Air (Replacement Ele.)..... <b>RS30065</b> 532.6 mm Radial Seal Air..... <b>RS5358</b> Air (w/Extra Urea Tank)..... <b>PA3765</b> 379.4 mm Cab Air..... <b>PA4956</b> 381.8 mm Cab Air (w/o Charcoal)..... <b>PA4912</b> 381.8 mm Cab Air (w/Charcoal) (A0008303418)..... <b>PA5492</b> Air Dryer (4295695)..... <b>BA5379 +</b>	Antos 2640 w/OM470LA (BlueTec 5/6) Eng. (09/12-on) Fuel/Water Separator (A9604770003)..... <b>BF1297-O</b> 210 mm Air (A0040947204)..... <b>CA30105</b> 228 mm Air (A0040946904)..... <b>CA30103</b> 263 mm Air (A0040946804)..... <b>CA30104</b> Cab Air (A9608300018)..... <b>PA30122</b>

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.


Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Antos 2640 w/OM470LA (BlueTec 5/6) Eng. (09/12-on) (Cont'd)	Axor II 2640 w/OM457LA Eng. (09/04-on) (Cont'd)	Actros III 2641 BlueTec 4+5 w/OM501LA Eng. (03/08-on) (Cont'd)
Cab Air (w/Carbon) (A9608300118)..... PA30123	Cab Air..... PA4945	338.1 mm Radial Seal Air w/Lid (Initial Installation)..... RS30065 KIT
Cab Air (A0008307518)..... PA5585	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	322.3 mm Radial Seal Air (Replacement Ele.)..... RS30065
Cab Air (A9608300218)..... PA30124	Air Dryer (Coalescer) (4295695).. BA5379 +	532.6 mm Radial Seal Air..... RS5358
Air Dryer (A0004295695)..... BA5379 +	Steering..... P106-HD	Air (w/Extra Urea Tank)..... PA3765
Steering (A0004660604)..... P106-HD	Actros I 2640LS w/OM501LA Eng. (09/96-12/03)	379.4 mm Cab Air..... PA4956
Urea (A0001421089)..... PE17002 KIT	F-F Lube (5411800009)..... P7192	381.8 mm Cab Air (w/o Charcoal) PA4912
Actros I 2640 w/OM501LA Eng. (09/96-12/03)	B-P Lube (21840525)..... C704-L	381.8 mm Cab Air (w/Charcoal) (A0008303418)..... PA5492
F-F Lube (5411800009)..... P7192	Fuel (5410920305)..... PF7761	Air Dryer (4295695)..... BA5379 +
B-P Lube (21840525)..... C704-L	Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363	Steering..... P106-HD
Pre-Fuel (924105)..... PF7939	Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O	Urea (A0001420089)..... PE5272
Fuel (5410920305)..... PF7761	Radial Seal Air (A0040940204).... RS5343	Antos 2642 w/OM471LA (BlueTec 5/6) Eng. (09/12-on)
Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363	Panel Air (A0040941104)..... PA5426	Lube (A4731800009)..... P7505
Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O	261.9 mm Air (A0030949204).... PA3838 <sup>90</sup>	Fuel/Water Separator (A9604770003)..... BF1297-O
Radial Seal Air (A0040940204).... RS5343	318.3 mm Air (A0030949104).... PA3844	Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT
Panel Air (A0040941104)..... PA5426	38.9 mm Height Cab Air (Mann CU3869)..... PA4956	263 mm Air (A0040946804)..... CA30104
261.9 mm Air (A0030949204).... PA3838 <sup>90</sup>	40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	228 mm Air (A0040946904)..... CA30103
318.3 mm Air (A0030949104).... PA3844	40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	210 mm Air (A0040947204)..... CA30105
38.9 mm Height Cab Air (Mann CU3869)..... PA4956	Air Dryer (Mann TB1374X)..... BA5374 +	Cab Air (A9608300018)..... PA30122
40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	Crankcase Breather (5410100080)..... CV15001	Cab Air (w/Carbon) (A9608300118)..... PA30123
40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	Trans. (2690321)..... PT9423	Cab Air (A9608300218)..... PA30124
Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	Steering (1902137)..... P106-HD	Cab Air (A0008307518)..... PA5585 <sup>90</sup>
Air Dryer (Coalescer) (4295695).. BA5379 +	Actros II 2641 w/OM501LA Eng. (04/03-on)	Air Dryer (A0004295695)..... BA5379 +
Crankcase Breather (5410100080)..... CV15001	F-F Lube..... P7192	Coolant (A4722030255)..... P5092
Trans. (2690321)..... PT9423	Pre-Fuel (924105)..... PF7939	Steering (A0004660604)..... P106-HD
Steering (1902137)..... P106-HD	Fuel..... PF7761	Urea (A0001421089)..... PE17002 KIT
Axor II 2640 (BlueTec) w/OM457LA Eng. (09/04-on)	Fuel/Water Separator..... BF1391-O	Actros II MP4 2642 w/OM471LA (BlueTec 5/6) Eng. (09/11-on)
Lube..... P7230	Radial Seal Air (Initial Installation) (40942404)..... RS30065 KIT	Lube (A4731800009)..... P7505
Fuel..... PF7761	Radial Seal Air (Replacement Ele.) (40942404)..... RS30065	Fuel/Water Separator (A9604770003)..... BF1297-O
Fuel/Water Separator..... BF1391-O	Radial Seal Air (9/03-on) (40943504)..... RS5358	Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT
Pre-Fuel (924105)..... PF7939	Panel Air (A0040941104)..... PA5426	263 mm Air (A0040946804)..... CA30104
Radial Seal Air (Initial Installation) (40942404)..... RS30065 KIT	38.9 mm Height Cab Air..... PA4956	228 mm Air (A0040946904)..... CA30103
Radial Seal Air (Replacement Ele.) (40942404)..... RS30065	40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	210 mm Air (A0040947204)..... CA30105
Cab Air..... PA4945	40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	Cab Air (A9608300018)..... PA30122
Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	Cab Air (w/Carbon) (A9608300118)..... PA30123
Air Dryer (Coalescer) (4295695).. BA5379 +	Air Dryer (Coalescer) (4295695).. BA5379 +	Cab Air (A9608300218)..... PA30124
Steering..... P106-HD	Crankcase Breather (5410100080)..... CV15001	Cab Air (A0008307518)..... PA5585 <sup>90</sup>
Axor II 2640 w/OM457LA Eng. (09/04-on)	Steering..... P106-HD	Air Dryer (A0004295695)..... BA5379 +
Lube..... P7230	Actros III 2641 BlueTec 4+5 w/OM501LA Eng. (03/08-on)	Coolant (A4722030255)..... P5092
Fuel..... PF7761	F-F Lube..... P7192	Steering (A0004660604)..... P106-HD
Fuel/Water Separator..... BF1391-O	Fuel/Water Separator..... BF1391-O	Urea (A0001421089)..... PE17002 KIT
Pre-Fuel (924105)..... PF7939	P. Fuel..... PF7761	Arocros 2642 w/OM471LA (BlueTec 5/6) Eng. (04/13-on)
Radial Seal Air w/Lid (Initial Installation) (40942404)..... RS30065 KIT	Pre-Fuel (924105)..... PF7939	Lube (A4721800309)..... P7505
Radial Seal Air (Replacement Ele.) (40942404)..... RS30065		Fuel/Water Separator (A9604770003)..... BF1297-O

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
<b>Arocs 2642 w/OM471LA (BlueTec 5/6) Eng. (04/13-on) (Cont'd)</b> Fuel (Mahle Assembly) (A4710909052)..... <b>PF9908 KIT</b> 210 mm Air (A0040947204)..... <b>CA30105</b> 228 mm Air (A0040946904)..... <b>CA30103</b> 263 mm Air (A0040946804)..... <b>CA30104</b> Cab Air (A9608300018)..... <b>PA30122</b> Cab Air (w/Carbon) (A9608300118)..... <b>PA30123</b> Cab Air (A0008307518)..... <b>PA5585</b> Cab Air (A9608300218)..... <b>PA30124</b> Air Dryer (A0004295695)..... <b>BA5379 +</b> Coolant (A4722030255)..... <b>P5092</b> Steering (A0004660604)..... <b>P106-HD</b> Urea (A0001421089)..... <b>PE17002 KIT</b>	<b>Antos 2643 w/OM470LA (BlueTec 5/6) Eng. (09/12-on) (Cont'd)</b> Air Dryer (A0004295695)..... <b>BA5379 +</b> Steering (A0004660604)..... <b>P106-HD</b> Urea (A0001421089)..... <b>PE17002 KIT</b> <b>Actros I 2643 w/OM501LA Eng. (09/96-12/03)</b> F-F Lube (5411800009)..... <b>P7192</b> B-P Lube (21840525)..... <b>C704-L</b> Pre-Fuel (924105)..... <b>PF7939</b> Fuel (5410920305)..... <b>PF7761</b> Fuel/Water Separator (w/Drain) (A0004771302)..... <b>BF1363</b> Fuel/Water Separator (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b> Radial Seal Air (A0040940204)..... <b>RS5343</b> Panel Air (A0040941104)..... <b>PA5426</b> 261.9 mm Air (A0030949204)..... <b>PA3838 90</b> 318.3 mm Air (A0030949104)..... <b>PA3844</b> 38.9 mm Height Cab Air (Mann CU3869)..... <b>PA4956</b> 40.5 mm Height Cab Air (w/o Charcoal)..... <b>PA4912</b> 40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... <b>PA5492</b> Crankcase Breather (5410100080)..... <b>CV15001</b> Trans. (2690321)..... <b>PT9423</b> Steering (1902137)..... <b>P106-HD</b>	<b>Actros I 2643L w/OM501LA Eng. (09/96-12/03)</b> F-F Lube (5411800009)..... <b>P7192</b> B-P Lube (21840525)..... <b>C704-L</b> Fuel (5410920305)..... <b>PF7761</b> Fuel/Water Separator (w/Drain) (A0004771302)..... <b>BF1363</b> Fuel/Water Separator (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b> Radial Seal Air (A0040940204)..... <b>RS5343</b> Panel Air (A0040941104)..... <b>PA5426</b> 261.9 mm Air (A0030949204)..... <b>PA3838 90</b> 318.3 mm Air (A0030949104)..... <b>PA3844</b> 38.9 mm Height Cab Air (Mann CU3869)..... <b>PA4956</b> 40.5 mm Height Cab Air (w/o Charcoal)..... <b>PA4912</b> 40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... <b>PA5492</b> Crankcase Breather (5410100080)..... <b>CV15001</b> Trans. (2690321)..... <b>PT9423</b> Steering (1902137)..... <b>P106-HD</b> <b>Actros I 2643LS w/OM501LA Eng. (09/96-12/03)</b> F-F Lube (5411800009)..... <b>P7192</b> B-P Lube (21840525)..... <b>C704-L</b> Fuel (5410920305)..... <b>PF7761</b> Fuel/Water Separator (w/Drain) (A0004771302)..... <b>BF1363</b> Fuel/Water Separator (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b> Radial Seal Air (A0040940204)..... <b>RS5343</b> Panel Air (A0040941104)..... <b>PA5426</b> 261.9 mm Air (A0030949204)..... <b>PA3838 90</b> 318.3 mm Air (A0030949104)..... <b>PA3844</b> 38.9 mm Height Cab Air (Mann CU3869)..... <b>PA4956</b> 40.5 mm Height Cab Air (w/o Charcoal)..... <b>PA4912</b> 40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... <b>PA5492</b> Crankcase Breather (5410100080)..... <b>CV15001</b> Trans. (2690321)..... <b>PT9423</b> Steering (1902137)..... <b>P106-HD</b> <b>Actros II 2644 w/OM501LA Eng. (04/03-on)</b> F-F Lube..... <b>P7192</b> Pre-Fuel (924105)..... <b>PF7939</b> Fuel..... <b>PF7761</b> Fuel/Water Separator..... <b>BF1391-O</b> Radial Seal Air (Initial Installation) (40942404)..... <b>RS30065 KIT</b> Radial Seal Air (Replacement Ele.) (40942404)..... <b>RS30065</b> Radial Seal Air (9/03-on) (40943504)..... <b>RS5358</b> Panel Air (A0040941104)..... <b>PA5426</b> 38.9 mm Height Cab Air..... <b>PA4956</b> 40.5 mm Height Cab Air (w/o Charcoal)..... <b>PA4912</b>
<b>Arocs 2643 w/OM470LA (BlueTec 5/6) Eng. (04/13-on)</b> Fuel/Water Separator (A9604770003)..... <b>BF1297-O</b> 210 mm Air (A0040947204)..... <b>CA30105</b> 228 mm Air (A0040946904)..... <b>CA30103</b> 263 mm Air (A0040946804)..... <b>CA30104</b> Cab Air (A9608300018)..... <b>PA30122</b> Cab Air (w/Carbon) (A9608300118)..... <b>PA30123</b> Cab Air (A0008307518)..... <b>PA5585</b> Cab Air (A9608300218)..... <b>PA30124</b> Air Dryer (A0004295695)..... <b>BA5379 +</b> Steering (A0004660604)..... <b>P106-HD</b> Urea (A0001421089)..... <b>PE17002 KIT</b>	<b>Axor II 2643 (BlueTec) w/OM457LA Eng. (09/05-on)</b> Lube..... <b>P7230</b> Fuel..... <b>PF7761</b> Fuel/Water Separator..... <b>BF1391-O</b> Pre-Fuel (924105)..... <b>PF7939</b> Radial Seal Air (Initial Installation) (40942404)..... <b>RS30065 KIT</b> Radial Seal Air (Replacement Ele.) (40942404)..... <b>RS30065</b> Cab Air..... <b>PA4945</b> Air Dryer (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer (Coalescer) (4295695)..... <b>BA5379 +</b> Steering..... <b>P106-HD</b>	<b>Actros II 2644 w/OM501LA Eng. (04/03-on)</b> F-F Lube..... <b>P7192</b> Pre-Fuel (924105)..... <b>PF7939</b> Fuel..... <b>PF7761</b> Fuel/Water Separator..... <b>BF1391-O</b> Radial Seal Air (Initial Installation) (40942404)..... <b>RS30065 KIT</b> Radial Seal Air (Replacement Ele.) (40942404)..... <b>RS30065</b> Radial Seal Air (9/03-on) (40943504)..... <b>RS5358</b> Panel Air (A0040941104)..... <b>PA5426</b> 38.9 mm Height Cab Air..... <b>PA4956</b> 40.5 mm Height Cab Air (w/o Charcoal)..... <b>PA4912</b>
<b>Antos 2643 w/OM470LA (BlueTec 5/6) Eng. (09/12-on)</b> Fuel/Water Separator (A9604770003)..... <b>BF1297-O</b> 210 mm Air (A0040947204)..... <b>CA30105</b> 228 mm Air (A0040946904)..... <b>CA30103</b> 263 mm Air (A0040946804)..... <b>CA30104</b> Cab Air (A9608300018)..... <b>PA30122</b> Cab Air (w/Carbon) (A9608300118)..... <b>PA30123</b> Cab Air (A0008307518)..... <b>PA5585</b> Cab Air (A9608300218)..... <b>PA30124</b> Air Dryer (A0004295695)..... <b>BA5379 +</b> Steering (A0004660604)..... <b>P106-HD</b> Urea (A0001421089)..... <b>PE17002 KIT</b>	<b>Axor II 2643 w/OM457LA Eng. (09/04-on)</b> Lube..... <b>P7230</b> Fuel..... <b>PF7761</b> Fuel/Water Separator..... <b>BF1391-O</b> Pre-Fuel (924105)..... <b>PF7939</b> Radial Seal Air (Initial Installation) (40942404)..... <b>RS30065 KIT</b> Radial Seal Air (Replacement Ele.) (40942404)..... <b>RS30065</b> Cab Air..... <b>PA4945</b> Air Dryer (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer (Coalescer) (4295695)..... <b>BA5379 +</b> Steering..... <b>P106-HD</b>	

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.

Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>MERCEDES-BENZ</b> <b>European Trucks, Vans (cont'd)</b>	<b>MERCEDES-BENZ</b> <b>European Trucks, Vans (cont'd)</b>	<b>MERCEDES-BENZ</b> <b>European Trucks, Vans (cont'd)</b>
<b>Actros II 2644 w/OM501LA Eng. (04/03-on)</b> (Cont'd) <b>40.5 mm Height Cab Air</b> (w/Charcoal) (A0008303418)..... <b>PA5492</b> <b>Air Dryer</b> (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> (Coalescer) (4295695).. <b>BA5379 +</b> <b>Crankcase Breather</b> (5410100080)..... <b>CV15001</b> <b>Steering</b> ..... <b>P106-HD</b>	<b>Actros II MP4 2645 w/OM471LA (BlueTec 5/6)</b> Eng. (09/11-on) (Cont'd) <b>Cab Air</b> (A9608300018)..... <b>PA30122</b> <b>Cab Air</b> (w/Carbon) (A9608300118)..... <b>PA30123</b> <b>Cab Air</b> (A9608300218)..... <b>PA30124</b> <b>Cab Air</b> (A0008307518)..... <b>PA5585<sup>90</sup></b> <b>Air Dryer</b> (A0004295695)..... <b>BA5379 +</b> <b>Coolant</b> (A4722030255)..... <b>P5092</b> <b>Steering</b> (A0004660604)..... <b>P106-HD</b> <b>Urea</b> (A0001421089)..... <b>PE17002 KIT</b>	<b>Actros II 2646 w/OM501LA Eng. (04/03-on)</b> <b>F-F Lube</b> ..... <b>P7192</b> <b>Pre-Fuel</b> (924105)..... <b>PF7939</b> <b>Fuel</b> ..... <b>PF7761</b> <b>Fuel/Water Separator</b> ..... <b>BF1391-O</b> <b>Radial Seal Air (Initial Installation)</b> (40942404)..... <b>RS30065 KIT</b> <b>Radial Seal Air (Replacement Ele.)</b> (40942404)..... <b>RS30065</b> <b>Radial Seal Air</b> (9/03-on) (40943504)..... <b>RS5358</b> <b>Panel Air</b> (A0040941104)..... <b>PA5426</b> <b>38.9 mm Height Cab Air</b> ..... <b>PA4956</b> <b>40.5 mm Height Cab Air</b> (w/o Charcoal)..... <b>PA4912</b> <b>40.5 mm Height Cab Air</b> (w/Charcoal) (A0008303418)..... <b>PA5492</b> <b>Air Dryer</b> (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> (Coalescer) (4295695).. <b>BA5379 +</b> <b>Crankcase Breather</b> (5410100080)..... <b>CV15001</b> <b>Steering</b> ..... <b>P106-HD</b>
<b>Actros III 2644 BlueTec 4+5 w/OM501LA Eng. (03/08-on)</b> <b>F-F Lube</b> ..... <b>P7192</b> <b>Fuel/Water Separator</b> ..... <b>BF1391-O</b> <b>P. Fuel</b> ..... <b>PF7761</b> <b>Pre-Fuel</b> (924105)..... <b>PF7939</b> <b>338.1 mm Radial Seal Air w/Lid</b> (Initial Installation)..... <b>RS30065 KIT</b> <b>322.3 mm Radial Seal Air</b> (Replacement Ele.)..... <b>RS30065</b> <b>532.6 mm Radial Seal Air</b> ..... <b>RS5358</b> <b>Air</b> (w/Extra Urea Tank)..... <b>PA3765</b> <b>379.4 mm Cab Air</b> ..... <b>PA4956</b> <b>381.8 mm Cab Air</b> (w/o Charcoal) <b>PA4912</b> <b>381.8 mm Cab Air</b> (w/Charcoal) (A0008303418)..... <b>PA5492</b> <b>Air Dryer</b> (4295695)..... <b>BA5379 +</b> <b>Steering</b> ..... <b>P106-HD</b> <b>Urea</b> (A0001420089)..... <b>PE5272</b>	<b>Arocs 2645 w/OM471LA (BlueTec 5/6) Eng. (04/13-on)</b> <b>Lube</b> (A4721800309)..... <b>P7505</b> <b>Fuel/Water Separator</b> (A9604770003)..... <b>BF1297-O</b> <b>Fuel</b> (Mahle Assembly) (A4710909052)..... <b>PF9908 KIT</b> <b>210 mm Air</b> (A0040947204)..... <b>CA30105</b> <b>228 mm Air</b> (A0040946904)..... <b>CA30103</b> <b>263 mm Air</b> (A0040946804)..... <b>CA30104</b> <b>Cab Air</b> (A9608300018)..... <b>PA30122</b> <b>Cab Air</b> (w/Carbon) (A9608300118)..... <b>PA30123</b> <b>Cab Air</b> (A0008307518)..... <b>PA5585</b> <b>Cab Air</b> (A9608300218)..... <b>PA30124</b> <b>Air Dryer</b> (A0004295695)..... <b>BA5379 +</b> <b>Coolant</b> (A4722030255)..... <b>P5092</b> <b>Steering</b> (A0004660604)..... <b>P106-HD</b> <b>Urea</b> (A0001421089)..... <b>PE17002 KIT</b>	<b>Actros III 2646 BlueTec 4+5 w/OM501LA Eng. (03/08-on)</b> <b>F-F Lube</b> ..... <b>P7192</b> <b>Fuel/Water Separator</b> ..... <b>BF1391-O</b> <b>P. Fuel</b> ..... <b>PF7761</b> <b>Pre-Fuel</b> (924105)..... <b>PF7939</b> <b>338.1 mm Radial Seal Air w/Lid</b> (Initial Installation)..... <b>RS30065 KIT</b> <b>322.3 mm Radial Seal Air</b> (Replacement Ele.)..... <b>RS30065</b> <b>532.6 mm Radial Seal Air</b> ..... <b>RS5358</b> <b>Air</b> (w/Extra Urea Tank)..... <b>PA3765</b> <b>379.4 mm Cab Air</b> ..... <b>PA4956</b> <b>381.8 mm Cab Air</b> (w/o Charcoal) <b>PA4912</b> <b>381.8 mm Cab Air</b> (w/Charcoal) (A0008303418)..... <b>PA5492</b> <b>Air Dryer</b> (4295695)..... <b>BA5379 +</b> <b>Steering</b> ..... <b>P106-HD</b> <b>Urea</b> (A0001420089)..... <b>PE5272</b>
<b>Antos 2645 w/OM471LA (BlueTec 5/6) Eng. (09/12-on)</b> <b>Lube</b> (A4731800009)..... <b>P7505</b> <b>Fuel/Water Separator</b> (A9604770003)..... <b>BF1297-O</b> <b>Fuel</b> (Mahle Assembly) (A4710909052)..... <b>PF9908 KIT</b> <b>263 mm Air</b> (A0040946804)..... <b>CA30104</b> <b>228 mm Air</b> (A0040946904)..... <b>CA30103</b> <b>210 mm Air</b> (A0040947204)..... <b>CA30105</b> <b>Cab Air</b> (A9608300018)..... <b>PA30122</b> <b>Cab Air</b> (w/Carbon) (A9608300118)..... <b>PA30123</b> <b>Cab Air</b> (A9608300218)..... <b>PA30124</b> <b>Cab Air</b> (A0008307518)..... <b>PA5585<sup>90</sup></b> <b>Air Dryer</b> (A0004295695)..... <b>BA5379 +</b> <b>Coolant</b> (A4722030255)..... <b>P5092</b> <b>Steering</b> (A0004660604)..... <b>P106-HD</b> <b>Urea</b> (A0001421089)..... <b>PE17002 KIT</b>	<b>Actros I 2646 w/OM501LA Eng. (09/96-12/03)</b> <b>F-F Lube</b> (5411800009)..... <b>P7192</b> <b>B-P Lube</b> (21840525)..... <b>C704-L</b> <b>Pre-Fuel</b> (924105)..... <b>PF7939</b> <b>Fuel</b> (5410920305)..... <b>PF7761</b> <b>Fuel/Water Separator</b> (w/Drain) (A0004771302)..... <b>BF1363</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b> <b>Radial Seal Air</b> (A0040940204)... <b>RS5343</b> <b>Panel Air</b> (A0040941104)..... <b>PA5426</b> <b>261.9 mm Air</b> (A0030949204)..... <b>PA3838<sup>90</sup></b> <b>318.3 mm Air</b> (A0030949104)..... <b>PA3844</b> <b>38.9 mm Height Cab Air</b> (Mann CU3869)..... <b>PA4956</b> <b>40.5 mm Height Cab Air</b> (w/o Charcoal)..... <b>PA4912</b> <b>40.5 mm Height Cab Air</b> (w/Charcoal) (A0008303418)..... <b>PA5492</b> <b>Air Dryer</b> (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> (Coalescer) (4295695).. <b>BA5379 +</b> <b>Crankcase Breather</b> (5410100080)..... <b>CV15001</b> <b>Trans.</b> (2690321)..... <b>PT9423</b> <b>Steering</b> (1902137)..... <b>P106-HD</b>	<b>Actros I 2646LS w/OM501LA Eng. (09/96-12/03)</b> <b>F-F Lube</b> (5411800009)..... <b>P7192</b> <b>B-P Lube</b> (21840525)..... <b>C704-L</b> <b>Fuel</b> (5410920305)..... <b>PF7761</b> <b>Fuel/Water Separator</b> (w/Drain) (A0004771302)..... <b>BF1363</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b> <b>Radial Seal Air</b> (A0040940204)... <b>RS5343</b> <b>Panel Air</b> (A0040941104)..... <b>PA5426</b> <b>261.9 mm Air</b> (A0030949204)..... <b>PA3838<sup>90</sup></b> <b>318.3 mm Air</b> (A0030949104)..... <b>PA3844</b> <b>38.9 mm Height Cab Air</b> (Mann CU3869)..... <b>PA4956</b> <b>40.5 mm Height Cab Air</b> (w/o Charcoal)..... <b>PA4912</b>
<b>Actros II MP4 2645 w/OM471LA (BlueTec 5/6) Eng. (09/11-on)</b> <b>Lube</b> (A4731800009)..... <b>P7505</b> <b>Fuel/Water Separator</b> (A9604770003)..... <b>BF1297-O</b> <b>Fuel</b> (Mahle Assembly) (A4710909052)..... <b>PF9908 KIT</b> <b>263 mm Air</b> (A0040946804)..... <b>CA30104</b> <b>228 mm Air</b> (A0040946904)..... <b>CA30103</b> <b>210 mm Air</b> (A0040947204)..... <b>CA30105</b>		

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
 Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Actros I 2646LS w/OM501LA Eng. (09/96-12/03) (Cont'd)	Actros I 2648 w/OM502LA Eng. (09/96-12/03) (Cont'd)	Actros I 2648L w/OM502LA Eng. (09/96-12/03)
40.5 mm Height Cab Air (w/Charcoal) (A0008303418).....	261.9 mm Air (A0030949204).....	F-F Lube (5411800009).....
PA5492	PA3838 <sup>90</sup>	P7192
Air Dryer (Mann TB1374X).....	318.3 mm Air (A0030949104).....	B-P Lube (21840525).....
BA5374 +	PA3844	C704-L
Crankcase Breather (5410100080).....	38.9 mm Height Cab Air (Mann CU3869).....	Fuel (5410920305).....
CV15001	PA4956	PF7761
Trans. (2690321).....	40.5 mm Height Cab Air (w/o Charcoal).....	Fuel/Water Separator (w/Drain) (A0004771302).....
PT9423	PA4912	BF1363
Steering (1902137).....	40.5 mm Height Cab Air (w/Charcoal) (A0008303418).....	Fuel/Water Separator (Open End for Bowl) (A0004771302).....
P106-HD	PA5492	BF1391-O
Antos 2648 w/OM471LA (BlueTec 5/6) Eng. (09/12-on)	Air Dryer (Desiccant) (Mann TB1374X).....	Radial Seal Air (A0040940204)...
Lube (A4731800009).....	BA5374 +	RS5343
P7505	BA5379 +	PA5426
Fuel/Water Separator (A9604770003).....	Crankcase Breather (5410100080).....	261.9 mm Air (A0030949204).....
BF1297-O	CV15001	PA3838 <sup>90</sup>
Fuel (Mahle Assembly) (A4710909052).....	Trans. (2690321).....	318.3 mm Air (A0030949104).....
PF9908 KIT	PT9423	PA3844
263 mm Air (A0040946804).....	Steering (1902137).....	38.9 mm Height Cab Air (Mann CU3869).....
CA30104	P106-HD	PA4956
228 mm Air (A0040946904).....	Actros III 2648 BlueTec 4+5 w/OM501LA Eng. (03/08-on)	40.5 mm Height Cab Air (w/o Charcoal).....
CA30103	F-F Lube.....	PA4912
210 mm Air (A0040947204).....	P7192	40.5 mm Height Cab Air (w/Charcoal) (A0008303418).....
CA30105	Fuel/Water Separator.....	PA5492
Cab Air (A9608300018).....	BF1391-O	Air Dryer (Mann TB1374X).....
PA30122	PF7761	BA5374 +
Cab Air (w/Carbon) (A9608300118).....	P. Fuel.....	Crankcase Breather (5410100080).....
PA30123	PF7939	CV15001
Cab Air (A9608300218).....	Pre-Fuel (924105).....	Trans. (2690321).....
PA30124	PF7939	PT9423
Cab Air (A0008307518).....	338.1 mm Radial Seal Air w/Lid (Initial Installation).....	Steering (1902137).....
PA5585 <sup>90</sup>	RS30065 KIT	P106-HD
Air Dryer (A0004295695).....	322.3 mm Radial Seal Air (Replacement Ele.).....	Actros I 2648 w/OM502LA Eng. (09/96-12/03)
BA5379 +	RS30065	F-F Lube (5411800009).....
Coolant (A4722030255).....	RS5358	P7192
P5092	PA3765	B-P Lube (21840525).....
Steering (A0004660604).....	379.4 mm Cab Air.....	C704-L
P106-HD	PA4912	PF7761
Urea (A0001421089).....	381.8 mm Cab Air (w/o Charcoal) (A0008303418).....	Fuel/Water Separator (w/Drain) (A0004771302).....
PE17002 KIT	PA5492	BF1363
Actros II MP4 2648 w/OM471LA (BlueTec 5/6) Eng. (09/11-on)	Air Dryer (4295695).....	Fuel/Water Separator (Open End for Bowl) (A0004771302).....
Lube (A4731800009).....	BA5379 +	BF1391-O
P7505	P106-HD	RS5343
Fuel/Water Separator (A9604770003).....	PE5272	PA5426
BF1297-O	Arcos 2648 w/OM471LA (BlueTec 5/6) Eng. (04/13-on)	261.9 mm Air (A0030949204).....
Fuel (Mahle Assembly) (A4710909052).....	Lube (A4721800309).....	PA3838 <sup>90</sup>
PF9908 KIT	P7505	PA3844
263 mm Air (A0040946804).....	Fuel/Water Separator (A9604770003).....	38.9 mm Height Cab Air (Mann CU3869).....
CA30104	BF1297-O	PA4956
228 mm Air (A0040946904).....	Fuel (Mahle Assembly) (A4710909052).....	40.5 mm Height Cab Air (w/o Charcoal).....
CA30103	PF9908 KIT	PA4912
210 mm Air (A0040947204).....	210 mm Air (A0040947204).....	40.5 mm Height Cab Air (w/Charcoal) (A0008303418).....
CA30105	CA30105	PA5492
Cab Air (A9608300018).....	228 mm Air (A0040946904).....	Air Dryer (Mann TB1374X).....
PA30122	CA30103	BA5374 +
Cab Air (w/Carbon) (A9608300118).....	263 mm Air (A0040946804).....	Crankcase Breather (5410100080).....
PA30123	CA30104	CV15001
Cab Air (A9608300218).....	Cab Air (A9608300018).....	Trans. (2690321).....
PA30124	PA30122	PT9423
Cab Air (A0008307518).....	Cab Air (w/Carbon) (A9608300118).....	Steering (1902137).....
PA5585 <sup>90</sup>	PA30123	P106-HD
Air Dryer (A0004295695).....	PA5585	Actros II 2650 w/OM502LA Eng. (04/03-on)
BA5379 +	PA30124	F-F Lube.....
Coolant (A4722030255).....	Air Dryer (A0004295695).....	P7192
P5092	BA5379 +	Pre-Fuel (924105).....
Steering (A0004660604).....	P5092	PF7939
P106-HD	PT9423	PF7761
Urea (A0001421089).....	Steering (A0004660604).....	Fuel.....
PE17002 KIT	P106-HD	BF1391-O
Actros I 2648 w/OM502LA Eng. (09/96-12/03)	Urea (A0001421089).....	Radial Seal Air (Initial Installation) (40942404).....
F-F Lube (5411800009).....	PE17002 KIT	RS30065 KIT
P7192	Actros I 2648 w/OM502LA Eng. (09/96-12/03)	Radial Seal Air (Replacement Ele.) (40942404).....
B-P Lube (21840525).....	F-F Lube (5411800009).....	RS30065
C704-L	P7192	Radial Seal Air (9/03-on) (40943504).....
PF7939	C704-L	RS5358
PF7761	Pre-Fuel (924105).....	PA5426
Fuel (5410920305).....	PF7939	Panel Air (A0040941104).....
PF7761	Fuel.....	PA4956
Fuel/Water Separator (w/Drain) (A0004771302).....	Fuel/Water Separator.....	
BF1363	BF1391-O	
Fuel/Water Separator (Open End for Bowl) (A0004771302).....	Radial Seal Air (Initial Installation) (40942404).....	
BF1391-O	RS30065 KIT	
Radial Seal Air (A0040940204)...	Radial Seal Air (Replacement Ele.) (40942404).....	
RS5343	RS30065	
Panel Air (A0040941104).....	Radial Seal Air (9/03-on) (40943504).....	
PA5426	RS5358	
	PA5426	
	Panel Air (A0040941104).....	
	PA4956	
	38.9 mm Height Cab Air.....	
	PA4956	

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.

Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Actros II 2650 w/OM502LA Eng. (04/03-on) (Cont'd)	Actros III 2651 BlueTec 4+5 w/OM502LA Eng. (03/08-on) (Cont'd)	Antos 2652 w/OM473LA (BlueTec 6) Eng. (11/13-on) (Cont'd)
40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	322.3 mm Radial Seal Air (Replacement Ele.)..... RS30065	Cab Air (w/Carbon) (A9608300118)..... PA30123
40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	532.6 mm Radial Seal Air..... RS5358	Cab Air (A0008307518)..... PA5585
Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	Air (w/Extra Urea Tank)..... PA3765	Cab Air (A9608300218)..... PA30124
Air Dryer (Coalescer) (4295695).. BA5379 +	379.4 mm Cab Air..... PA4956	Air Dryer (A0004295695)..... BA5379 +
Crankcase Breather (5410100080)..... CV15001	381.8 mm Cab Air (w/o Charcoal) (A0008303418)..... PA5492	Steering (A0004660604)..... P106-HD
Steering..... P106-HD	Air Dryer (4295695)..... BA5379 +	Urea (A0001421089)..... PE17002 KIT
Antos 2651 w/OM471LA (BlueTec 5/6) Eng. (09/12-on)	Arcos 2651 w/OM471LA (BlueTec 5/6) Eng. (04/13-on)	Actros I 2653 w/OM502LA Eng. (09/96-12/03)
Lube (A4731800009)..... P7505	Lube (A4721800309)..... P7505	F-F Lube (5411800009)..... P7192
Fuel/Water Separator (A9604770003)..... BF1297-O	Fuel/Water Separator (A9604770003)..... BF1297-O	B-P Lube (21840525)..... C704-L
Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT	Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT	Pre-Fuel (924105)..... PF7939
263 mm Air (A0040946804)..... CA30104	210 mm Air (A0040947204)..... CA30105	Fuel (5410920305)..... PF7761
228 mm Air (A0040946904)..... CA30103	228 mm Air (A0040946904)..... CA30103	Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363
210 mm Air (A0040947204)..... CA30105	263 mm Air (A0040946804)..... CA30104	Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O
Cab Air (A9608300018)..... PA30122	Cab Air (A9608300018)..... PA30122	Radial Seal Air (A0040940204)..... RS5343
Cab Air (w/Carbon) (A9608300118)..... PA30123	Cab Air (w/Carbon) (A9608300118)..... PA30123	Panel Air (A0040941104)..... PA5426
Cab Air (A9608300218)..... PA30124	Cab Air (A0008307518)..... PA5585	261.9 mm Air (A0030949204)..... PA3838 <sup>90</sup>
Cab Air (A0008307518)..... PA5585 <sup>90</sup>	Cab Air (A9608300218)..... PA30124	318.3 mm Air (A0030949104)..... PA3844
Air Dryer (A0004295695)..... BA5379 +	Air Dryer (A0004295695)..... BA5379 +	38.9 mm Height Cab Air (Mann CU3869)..... PA4956
Coolant (A4722030255)..... P5092	Coolant (A4722030255)..... P5092	40.5 mm Height Cab Air (w/o Charcoal)..... PA4912
Steering (A0004660604)..... P106-HD	Steering (A0004660604)..... P106-HD	40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492
Urea (A0001421089)..... PE17002 KIT	Urea (A0001421089)..... PE17002 KIT	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +
Actros II 2651 w/OM471LA (Euro 5/6) Eng. (09/11-on)	Arcos 2652 w/OM473LA (BlueTec 5/6) Eng. (04/13-on)	Air Dryer (Coalescer) (4295695).. BA5379 +
Lube (A4721800309)..... P7505	Lube (A4731800009)..... P7505	Crankcase Breather (5410100080)..... CV15001
Fuel/Water Separator (A9604770003)..... BF1297-O	Fuel/Water Separator (A9604770003)..... BF1297-O	Trans. (2690321)..... PT9423
Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT	263 mm Air (A0040946804)..... CA30104	Steering (1902137)..... P106-HD
210 mm Air (A0040947204)..... CA30105	228 mm Air (A0040946904)..... CA30103	Actros II 2654 w/OM502LA Eng. (04/03-on)
228 mm Air (A0040946904)..... CA30103	210 mm Air (A0040947204)..... CA30105	F-F Lube..... P7192
263 mm Air (A0040946804)..... CA30104	Cab Air (A9608300018)..... PA30122	Pre-Fuel (924105)..... PF7939
Cab Air (A9608300018)..... PA30122	Cab Air (w/Carbon) (A9608300118)..... PA30123	Fuel..... PF7761
Cab Air (w/Carbon) (A9608300118)..... PA30123	Cab Air (A0008307518)..... PA5585	Fuel/Water Separator..... BF1391-O
Cab Air (A0008307518)..... PA5585	Cab Air (A9608300218)..... PA30124	Radial Seal Air (Initial Installation) (40942404)..... RS30065 KIT
Cab Air (A9608300218)..... PA30124	Air Dryer (A0004295695)..... BA5379 +	Radial Seal Air (Replacement Ele.) (40942404)..... RS30065
Air Dryer (A0004295695)..... BA5379 +	Steering (A0004660604)..... P106-HD	Radial Seal Air (9/03-on) (40943504)..... RS5358
Coolant (A4722030255)..... P5092	Urea (A0001421089)..... PE17002 KIT	Panel Air (A0040941104)..... PA5426
Steering (A0004660604)..... P106-HD	Antos 2652 w/OM473LA (BlueTec 6) Eng. (11/13-on)	38.9 mm Height Cab Air..... PA4956
Urea (A0001421089)..... PE17002 KIT	Lube (A4731800009)..... P7505	40.5 mm Height Cab Air (w/o Charcoal)..... PA4912
Actros III 2651 BlueTec 4+5 w/OM502LA Eng. (03/08-on)	Fuel/Water Separator (A9604770003)..... BF1297-O	40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492
F-F Lube..... P7192	263 mm Air (A0040946804)..... CA30104	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +
Fuel/Water Separator..... BF1391-O	228 mm Air (A0040946904)..... CA30103	Air Dryer (Coalescer) (4295695).. BA5379 +
P. Fuel..... PF7761	210 mm Air (A0040947204)..... CA30105	Crankcase Breather (5410100080)..... CV15001
Pre-Fuel (924105)..... PF7939	Cab Air (A9608300018)..... PA30122	Steering..... P106-HD
338.1 mm Radial Seal Air w/Lid (Initial Installation)..... RS30065 KIT		

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Actros III 2655 BlueTec 4+5 w/OM502LA Eng. (03/08-on)	Actros 2658 w/OM473LA (BlueTec 6) Eng. (11/13-on) (Cont'd)	Arocs 2663 w/OM473LA (BlueTec 5/6) Eng. (04/13-on) (Cont'd)
F-F Lube..... P7192	Steering (A0004660604)..... P106-HD	Cab Air (A9608300218)..... PA30124
Fuel/Water Separator..... BF1391-O	Urea (A0001421089)..... PE17002 KIT	Air Dryer (A0004295695)..... BA5379 +
P. Fuel..... PF7761	Actros II 2658 w/OM502LA Eng. (04/03-on)	Steering (A0004660604)..... P106-HD
Pre-Fuel (924105)..... PF7939	F-F Lube..... P7192	Urea (A0001421089)..... PE17002 KIT
338.1 mm Radial Seal Air w/Lid (Initial Installation)..... RS30065 KIT	Pre-Fuel (924105)..... PF7939	Actros 2663 w/OM473LA (BlueTec 6) Eng. (11/13-on)
322.3 mm Radial Seal Air (Replacement Ele.)..... RS30065	Fuel..... PF7761	Lube (A4731800009)..... P7505
532.6 mm Radial Seal Air..... RS5358	Fuel/Water Separator..... BF1391-O	Fuel/Water Separator (A9604770003)..... BF1297-O
Air (w/Extra Urea Tank)..... PA3765	Radial Seal Air (Initial Installation) (40942404)..... RS30065 KIT	263 mm Air (A0040946804)..... CA30104
379.4 mm Cab Air..... PA4956	Radial Seal Air (Replacement Ele.) (40942404)..... RS30065	228 mm Air (A0040946904)..... CA30103
381.8 mm Cab Air (w/o Charcoal)..... PA4912	Radial Seal Air (9/03-on) (40943504)..... RS5358	210 mm Air (A0040947204)..... CA30105
381.8 mm Cab Air (w/Charcoal) (A0008303418)..... PA5492	Panel Air (A0040941104)..... PA5426	Cab Air (A9608300018)..... PA30122
Air Dryer (4295695)..... BA5379 +	38.9 mm Height Cab Air..... PA4956	Cab Air (w/Carbon) (A9608300118)..... PA30123
Steering..... P106-HD	40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	Cab Air (A0008307518)..... PA5585
Urea (A0001420089)..... PE5272	40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	Cab Air (A9608300218)..... PA30124
Actros I 2657 w/OM502LA Eng. (09/96-12/03)	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	Air Dryer (A0004295695)..... BA5379 +
F-F Lube (5411800009)..... P7192	Air Dryer (Coalescer) (4295695) (5410100080)..... CV15001	Steering (A0004660604)..... P106-HD
B-P Lube (21840525)..... C704-L	Steering..... P106-HD	Urea (A0001421089)..... PE17002 KIT
Pre-Fuel (924105)..... PF7939	Actros III 2660 BlueTec 4+5 w/OM502LA Eng. (03/08-on)	Zetros 2733 w/OM926LA Eng. (05/09-on)
Fuel (5410920305)..... PF7761	F-F Lube..... P7192	Lube (A0001801709)..... P7188
Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363	Fuel/Water Separator..... BF1391-O	Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363
Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O	P. Fuel..... PF7761	Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O
Radial Seal Air (A0040940204)..... RS5343	Pre-Fuel (924105)..... PF7939	Fuel Screen (A0000901351)..... PF7974
Panel Air (A0040941104)..... PA5426	338.1 mm Radial Seal Air w/Lid (Initial Installation)..... RS30065 KIT	Fuel Ele. (A0000901251)..... PF7735
261.9 mm Air (A0030949204)..... PA3838 <sup>90</sup>	322.3 mm Radial Seal Air (Replacement Ele.)..... RS30065	O. Air (A0040945004)..... PA30235 +
318.3 mm Air (A0030949104)..... PA3844	532.6 mm Radial Seal Air..... RS5358	I. Air (3880947104)..... PA3494
38.9 mm Height Cab Air (Mann CU3869)..... PA4956	Air (w/Extra Urea Tank)..... PA3765	Cab Air (w/o Carbon) (A0008301218)..... PA4912
40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	379.4 mm Cab Air..... PA4956	Cab Air (w/Carbon) (A0008301318)..... PA5492
40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	381.8 mm Cab Air (w/o Charcoal)..... PA4912	Air Dryer (Desiccant Vers.) (4291097)..... BA5374 +
Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	381.8 mm Cab Air (w/Charcoal) (A0008301318)..... PA5492	Air Dryer (Coalescer Vers.) (A0004295695)..... BA5379 +
Air Dryer (Coalescer) (4295695)..... BA5379 +	Air Dryer (4295695)..... BA5379 +	Steering (A0004660604)..... P106-HD
Crankcase Breather (5410100080)..... CV15001	Steering..... P106-HD	Urea (A0001420089)..... PE5272
Trans. (2690321)..... PT9423	Urea (A0001420089)..... PE5272	Actros I 2831 w/OM501LA Eng. (09/96-12/03)
Steering (1902137)..... P106-HD	Arocs 2663 w/OM473LA (BlueTec 5/6) Eng. (04/13-on)	F-F Lube (5411800009)..... P7192
Actros 2658 w/OM473LA (BlueTec 6) Eng. (11/13-on)	Lube (A4731800009)..... P7505	B-P Lube (21840525)..... C704-L
Lube (A4731800009)..... P7505	Fuel/Water Separator (A9604770003)..... BF1297-O	Pre-Fuel (924105)..... PF7939
Fuel/Water Separator (A9604770003)..... BF1297-O	263 mm Air (A0040946804)..... CA30104	Fuel..... PF7761
263 mm Air (A0040946804)..... CA30104	228 mm Air (A0040946904)..... CA30103	Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363
228 mm Air (A0040946904)..... CA30103	210 mm Air (A0040947204)..... CA30105	Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O
210 mm Air (A0040947204)..... CA30105	Cab Air (A9608300018)..... PA30122	Radial Seal Air (A0040940204)..... RS5343
Cab Air (A9608300018)..... PA30122	Cab Air (w/Carbon) (A9608300118)..... PA30123	Panel Air (A0040941104)..... PA5426
Cab Air (A0008307518)..... PA5585	Cab Air (A0008307518)..... PA5585	261.9 mm Air (A0030949204)..... PA3838 <sup>90</sup>
Cab Air (A9608300218)..... PA30124	Actros 2663 w/OM473LA (BlueTec 5/6) Eng. (04/13-on)	318.3 mm Air (A0030949104)..... PA3844
Air Dryer (A0004295695)..... BA5379 +	Lube (A4731800009)..... P7505	38.9 mm Height Cab Air (Mann CU3869)..... PA4956
	Fuel/Water Separator (A9604770003)..... BF1297-O	40.5 mm Height Cab Air (w/o Charcoal)..... PA4912
	263 mm Air (A0040946804)..... CA30104	
	228 mm Air (A0040946904)..... CA30103	
	210 mm Air (A0040947204)..... CA30105	
	Cab Air (A9608300018)..... PA30122	
	Cab Air (w/Carbon) (A9608300118)..... PA30123	
	Cab Air (A0008307518)..... PA5585	

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.


Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Actros I 2831 w/OM501LA Eng. (09/96-12/03) (Cont'd) 40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492 Air Dryer (Desiccant)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Crankcase Breather (5410100080)..... CV15001 Trans. (2690321)..... PT9423 Steering (1902137)..... P106-HD	Actros I 2321 w/OM501LA Eng. (09/96-12/03) F-F Lube (5411800009)..... P7192 B-P Lube (21840525)..... C704-L Pre-Fuel (924105)..... PF7939 Fuel..... PF7761 Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363 Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O Radial Seal Air (A004094204).... RS5343 Panel Air (A0040941104)..... PA5426 261.9 mm Air (A0030949204).... PA3838 90 318.3 mm Air (A0030949104).... PA3844 38.9 mm Height Cab Air (Mann CU3869)..... PA4956 40.5 mm Height Cab Air (w/o Charcoal)..... PA4912 40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Crankcase Breather (5410100080)..... CV15001 Trans. (2690321)..... PT9423 Steering (1902137)..... P106-HD	Actros II 3232 w/OM501LA Eng. (04/03-on) (Cont'd) Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Crankcase Breather (5410100080)..... CV15001 Steering..... P106-HD Actros III 3232 BlueTec 4+5 w/OM501LA Eng. (03/08-on) F-F Lube..... P7192 Fuel/Water Separator..... BF1391-O P. Fuel..... PF7761 Pre-Fuel (924105)..... PF7939 338.1 mm Radial Seal Air w/Lid (Initial Installation)..... RS30065 KIT 322.3 mm Radial Seal Air (Replacement Ele.)..... RS30065 532.6 mm Radial Seal Air..... RS5358 Air (w/Extra Urea Tank)..... PA3765 379.4 mm Cab Air..... PA4956 381.8 mm Cab Air (w/o Charcoal) PA4912 381.8 mm Cab Air (w/Charcoal) (A0008301318)..... PA5492 Air Dryer (4295695)..... BA5379 + Steering..... P106-HD Urea (A0001420089)..... PE5272
Arocs 3227 w/OM936LA (BlueTec 5/6) Eng. (04/13-on) Lube (A9361800009)..... P40003 Fuel/Water Separator (A9604770003)..... BF1297-O 210 mm Air (A0040947204)..... CA30105 228 mm Air (A0040946904)..... CA30103 263 mm Air (A0040946804)..... CA30104 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A0008307518)..... PA5585 Cab Air (A9608300218)..... PA30124 Air Dryer (A0004295695)..... BA5379 + Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT	Arocs 3232 w/OM936LA (BlueTec 5/6) Eng. (04/13-on) Lube (A9361800009)..... P40003 Fuel/Water Separator (A9604770003)..... BF1297-O 210 mm Air (A0040947204)..... CA30105 228 mm Air (A0040946904)..... CA30103 263 mm Air (A0040946804)..... CA30104 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A0008307518)..... PA5585 Cab Air (A9608300218)..... PA30124 Air Dryer (A0004295695)..... BA5379 + Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT	Actros III 3233 w/OM470LA (BlueTec 5/6) Eng. (04/13-on) Fuel/Water Separator (A9604770003)..... BF1297-O 210 mm Air (A0040947204)..... CA30105 228 mm Air (A0040946904)..... CA30103 263 mm Air (A0040946804)..... CA30104 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A0008307518)..... PA5585 Cab Air (A9608300218)..... PA30124 Air Dryer (A0004295695)..... BA5379 + Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT
Axor II 3228 w/OM906LA Eng. (09/04-on) Lube..... P7188 Fuel..... PF7735 Fuel/Water Separator..... BF1391-O Pre-Fuel (924105)..... PF7939 322.3 mm Radial Seal Air (Replacement Ele.) (40942404).. RS30065 338.1 mm Radial Seal Air w/Lid (Initial Installation) (40942404).. RS30065 KIT 350.0 mm Radial Seal Air (30949604)..... RS5342 Cab Air..... PA4945 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Steering..... P106-HD	Arocs 3230 w/OM936LA (BlueTec 5/6) Eng. (04/13-on) Lube (A9361800009)..... P40003 Fuel/Water Separator (A9604770003)..... BF1297-O 210 mm Air (A0040947204)..... CA30105 228 mm Air (A0040946904)..... CA30103 263 mm Air (A0040946804)..... CA30104 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A0008307518)..... PA5585 Cab Air (A9608300218)..... PA30124 Air Dryer (A0004295695)..... BA5379 + Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT	Econic 3233 w/OM926LA Eng. (05/05-on) Lube (A0001801709)..... P7188 Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363 Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O Fuel Screen (A0000901351)..... PF7974 Fuel Ele. (A0000901251)..... PF7735 Radial Seal Air (A0040947404)... RS5342 Air (A9570940004)..... PA2500 Cab Air (9408350047)..... PA4945 Air Dryer (A0004295695)..... BA5379 + Steering (A0004660604)..... P106-HD

+ See Product Guide for Variations of This Number. 90 Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Arocs 3235 w/OM936LA (BlueTec 5/6) Eng. (04/13-on)	Arocs 3236 w/OM470LA (BlueTec 5/6) Eng. (04/13-on)	Axor II 3236 (BlueTec) w/OM457LA Eng. (09/05-on)
Lube (A9361800009)..... P40003	Fuel/Water Separator (A9604770003)..... BF1297-O	Lube..... P7230
Fuel/Water Separator (A9604770003)..... BF1297-O	210 mm Air (A0040947204)..... CA30105	Fuel..... PF7761
210 mm Air (A0040947204)..... CA30105	228 mm Air (A0040946904)..... CA30103	Fuel/Water Separator..... BF1391-O
228 mm Air (A0040946904)..... CA30103	263 mm Air (A0040946804)..... CA30104	Pre-Fuel (924105)..... PF7939
263 mm Air (A0040946804)..... CA30104	Cab Air (A9608300018)..... PA30122	Radial Seal Air (Initial Installation) RS30065 KIT
Cab Air (A9608300018)..... PA30122	Cab Air (w/Carbon) (A9608300118)..... PA30123	Radial Seal Air (Replacement Ele.) (40942404)..... RS30065
Cab Air (w/Carbon) (A9608300118)..... PA30123	Cab Air (A0008307518)..... PA5585	Cab Air..... PA4945
Cab Air (A0008307518)..... PA5585	Cab Air (A9608300218)..... PA30124	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +
Cab Air (A9608300218)..... PA30124	Air Dryer (A0004295695)..... BA5379 +	Air Dryer (Coalescer) (4295695).. BA5379 +
Air Dryer (A0004295695)..... BA5379 +	Steering (A0004660604)..... P106-HD	Steering (Coalescer) (4295695).. P106-HD
Steering (A0004660604)..... P106-HD	Urea (A0001421089)..... PE17002 KIT	
Urea (A0001421089)..... PE17002 KIT	Actros II 3236 w/OM501LA Eng. (04/03-on)	Arocs 3240 w/OM470LA (BlueTec 5/6) Eng. (04/13-on)
Actros I 3235 w/OM501LA Eng. (09/96-12/03)	F-F Lube..... P7192	Fuel/Water Separator (A9604770003)..... BF1297-O
F-F Lube (5411800009)..... P7192	Pre-Fuel (924105)..... PF7939	210 mm Air (A0040947204)..... CA30105
B-P Lube (21840525)..... C704-L	Fuel..... PF7761	228 mm Air (A0040946904)..... CA30103
Pre-Fuel (924105)..... PF7939	Fuel/Water Separator..... BF1391-O	263 mm Air (A0040946804)..... CA30104
Fuel..... PF7761	Radial Seal Air (Initial Installation) (40942404)..... RS30077	Cab Air (A9608300018)..... PA30122
Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363	Radial Seal Air (Replacement Ele.) (40942404)..... RS30065	Cab Air (w/Carbon) (A9608300118)..... PA30123
Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O	Radial Seal Air (9/03-on) (40943504)..... RS5358	Cab Air (A0008307518)..... PA5585
Radial Seal Air (A0040940204)..... RS5343	Panel Air (A0040941104)..... PA5426	Cab Air (A9608300218)..... PA30124
Panel Air (A0040941104)..... PA5426	38.9 mm Height Cab Air..... PA4956	Air Dryer (A0004295695)..... BA5379 +
261.9 mm Air (A0030949204)..... PA3838 <sup>90</sup>	40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	Steering (A0004660604)..... P106-HD
318.3 mm Air (A0030949104)..... PA3844	40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	Urea (A0001421089)..... PE17002 KIT
38.9 mm Height Cab Air (Mann CU3869)..... PA4956	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	
40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	Air Dryer (Coalescer) (4295695).. BA5379 +	Actros I 3240 w/OM501LA Eng. (09/96-12/03)
40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	Crankcase Breather (5410100080)..... CV15001	F-F Lube (5411800009)..... P7192
Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	Steering..... P106-HD	B-P Lube (21840525)..... C704-L
Air Dryer (Coalescer) (4295695).. BA5379 +	Actros III 3236 BlueTec 4+5 w/OM501LA Eng. (03/08-on)	Pre-Fuel (924105)..... PF7939
Crankcase Breather (5410100080)..... CV15001	F-F Lube..... P7192	Fuel..... PF7761
Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O	Fuel/Water Separator..... BF1391-O	Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363
Radial Seal Air (A0040940204)..... RS5343	P. Fuel..... PF7761	Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O
Panel Air (A0040941104)..... PA5426	Pre-Fuel (924105)..... PF7939	Radial Seal Air (A0040940204)..... RS5343
261.9 mm Air (A0030949204)..... PA3838 <sup>90</sup>	338.1 mm Radial Seal Air w/Lid (Initial Installation)..... RS30065 KIT	Panel Air (A0040941104)..... PA5426
318.3 mm Air (A0030949104)..... PA3844	322.3 mm Radial Seal Air (Replacement Ele.)..... RS30065	261.9 mm Air (A0030949204)..... PA3838 <sup>90</sup>
38.9 mm Height Cab Air (Mann CU3869)..... PA4956	532.6 mm Radial Seal Air..... RS5358	38.9 mm Height Cab Air (Mann CU3869)..... PA4956
40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	Air (w/Extra Urea Tank)..... PA3765	40.5 mm Height Cab Air (w/o Charcoal)..... PA4912
40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	379.4 mm Cab Air..... PA4956	40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492
Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	381.8 mm Cab Air (w/o Charcoal)..... PA4912	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +
Air Dryer (Coalescer) (4295695).. BA5379 +	381.8 mm Cab Air (w/Charcoal) (A0008303418)..... PA5492	Air Dryer (Coalescer) (4295695).. BA5379 +
Steering..... P106-HD	Air Dryer (4295695)..... BA5379 +	Crankcase Breather (5410100080)..... CV15001
	Steering..... P106-HD	Trans. (2690321)..... PT9423
	Urea (A0001420089)..... PE5272	Steering (1902137)..... P106-HD

\* See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.


Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Axor II 3240 (BlueTec) w/OM457LA Eng. (09/05-on)	Actros III 3241 BlueTec 4+5 w/OM501LA Eng. (03/08-on) (Cont'd)	Actros I 3243 w/OM501LA Eng. (09/96-12/03) (Cont'd)
Lube..... P7230	338.1 mm Radial Seal Air w/Lid (Initial Installation)..... RS30065 KIT	Radial Seal Air (A0040942020)... RS5343
Fuel..... PF7761	322.3 mm Radial Seal Air (Replacement Ele.)..... RS30065	Panel Air (A0040941104)..... PA5426
Fuel/Water Separator..... BF1391-O	532.6 mm Radial Seal Air..... RS5358	261.9 mm Air (A0030949204)..... PA3838 <sup>90</sup>
Pre-Fuel (924105)..... PF7939	Air (w/Extra Urea Tank)..... PA3765	318.3 mm Air (A0030949104)..... PA3844
Radial Seal Air (Initial Installation) (40942404)..... RS30065 KIT	379.4 mm Cab Air..... PA4956	38.9 mm Height Cab Air (Mann CU3869)..... PA4956
Radial Seal Air (Replacement Ele.) (40942404)..... RS30065	381.8 mm Cab Air (w/o Charcoal)..... PA4912	40.5 mm Height Cab Air (w/o Charcoal)..... PA4912
Cab Air..... PA4945	381.8 mm Cab Air (w/Charcoal) (A0008303418)..... PA5492	40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492
Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	Air Dryer (4295695)..... BA5379 +	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +
Air Dryer (Coalescer) (4295695).. BA5379 +	Steering..... P106-HD	Air Dryer (Coalescer) (4295695).. BA5379 +
Steering..... P106-HD	Urea (A0001420089)..... PE5272	Crankcase Breather (5410100080)..... CV15001
Axor II 3240 w/OM457LA Eng. (09/04-on)	Arocs 3242 w/OM471LA (BlueTec 5/6) Eng. (04/13-on)	Trans. (2690321)..... PT9423
Lube..... P7230	Lube (A4731800009)..... P7505	Steering (1902137)..... P106-HD
Fuel..... PF7761	Fuel/Water Separator (A9604770003)..... BF1297-O	Axor II 3243 (BlueTec) w/OM457LA Eng. (09/05-on)
Fuel/Water Separator..... BF1391-O	Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT	Lube..... P7230
Pre-Fuel (924105)..... PF7939	263 mm Air (A0040946804)..... CA30104	Fuel..... PF7761
Radial Seal w/Lid (Initial Installation) (40942404)..... RS30065 KIT	228 mm Air (A0040946904)..... CA30103	Fuel/Water Separator..... BF1391-O
Radial Seal Air (Replacement Ele.) (40942404)..... RS30065	210 mm Air (A0040947204)..... CA30105	Pre-Fuel (924105)..... PF7939
Cab Air..... PA4945	Cab Air (A9608300018)..... PA30122	Radial Seal Air (Initial Installation) (40942404)..... RS30065 KIT
Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	Cab Air (w/Carbon) (A9608300118)..... PA30123	Radial Seal Air (Replacement Ele.) (40942404)..... RS30065
Air Dryer (Coalescer) (4295695).. BA5379 +	Cab Air (A9608300218)..... PA30124	Cab Air..... PA4945
Steering..... P106-HD	Cab Air (A0008307518)..... PA5585 <sup>90</sup>	Air Dryer (Mann TB1374X)..... BA5374 +
Axctros II 3241 w/OM501LA Eng. (04/03-on)	Air Dryer (A0004295695)..... BA5379 +	Air Dryer (4295695)..... BA5379 +
F-F Lube..... P7192	Coolant (A4722030255)..... P5092	Steering..... P106-HD
Pre-Fuel (924105)..... PF7939	Steering (A0004660604)..... P106-HD	Axor II 3243 w/OM457LA Eng. (09/04-on)
Fuel..... PF7761	Urea (A0001421089)..... PE17002 KIT	Lube..... P7230
Fuel/Water Separator..... BF1391-O	Arocs 3243 w/OM470LA (BlueTec 5/6) Eng. (04/13-on)	Fuel..... PF7761
Radial Seal Air (Initial Installation) (40942404)..... RS30065 KIT	Fuel/Water Separator (A9604770003)..... BF1297-O	Fuel/Water Separator..... BF1391-O
Radial Seal Air (Replacement Ele.) (40942404)..... RS30065	210 mm Air (A0040947204)..... CA30105	Pre-Fuel (924105)..... PF7939
Radial Seal Air (9/03-on) (40943504)..... RS5358	228 mm Air (A0040946904)..... CA30103	Radial Seal Air (Initial Installation) (40942404)..... RS30065 KIT
Panel Air (A0040941104)..... PA5426	263 mm Air (A0040946804)..... CA30104	Radial Seal Air (Replacement Ele.) (40942404)..... RS30065
38.9 mm Height Cab Air..... PA4956	Cab Air (A9608300018)..... PA30122	Cab Air..... PA4945
40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	Cab Air (w/Carbon) (A9608300118)..... PA30123	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +
40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	Cab Air (A0008307518)..... PA5585	Air Dryer (Coalescer) (4295695).. BA5379 +
Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	Cab Air (A9608300218)..... PA30124	Steering..... P106-HD
Air Dryer (Coalescer) (4295695).. BA5379 +	Air Dryer (A0004295695)..... BA5379 +	Actros II 3244 w/OM501LA Eng. (04/03-on)
Crankcase Breather (5410100080)..... CV15001	Steering (A0004660604)..... P106-HD	F-F Lube..... P7192
Steering..... P106-HD	Urea (A0001421089)..... PE17002 KIT	Pre-Fuel (924105)..... PF7939
Actros III 3241 BlueTec 4+5 w/OM501LA Eng. (03/08-on)	Actros I 3243 w/OM501LA Eng. (09/96-12/03)	Fuel..... PF7761
F-F Lube..... P7192	F-F Lube (5411800009)..... P7192	Fuel/Water Separator..... BF1391-O
Fuel/Water Separator..... BF1391-O	B-P Lube (21840525)..... C704-L	Radial Seal Air (Initial Installation) (40942404)..... RS30065 KIT
P. Fuel..... PF7761	Pre-Fuel (924105)..... PF7939	Radial Seal Air (Replacement Ele.) (40942404)..... RS30065
Pre-Fuel (924105)..... PF7939	Fuel..... PF7761	Radial Seal Air (9/03-on) (40943504)..... RS5358
	Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363	Panel Air (A0040941104)..... PA5426
	Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O	

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Actros II 3244 w/OM501LA Eng. (04/03-on) (Cont'd)	Actros I 3246 w/OM501LA Eng. (09/96-12/03) (Cont'd)	Actros III 3246 BlueTec 4+5 w/OM501LA Eng. (03/08-on) (Cont'd)
38.9 mm Height Cab Air..... PA4956	Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O	381.8 mm Cab Air (w/Charcoal) (A0008303418)..... PA5492
40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	Radial Seal Air (A0040942024)... RS5343	Air Dryer (4295695)..... BA5379 +
40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	Panel Air (A0040941104)..... PA5426	Steering..... P106-HD
Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	261.9 mm Air (A0030949204)..... PA3838 <sup>90</sup>	Urea (A0001420089)..... PE5272
Air Dryer (Coalescer) (4295695).. BA5379 +	318.3 mm Air (A0030949104)..... PA3844	
Crankcase Breather (5410100080)..... CV15001	38.9 mm Height Cab Air (Mann CU3869)..... PA4956	Arocs 3248 w/OM471LA (BlueTec 5/6) Eng. (04/13-on)
Steering..... P106-HD	40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	Lube (A4731800009)..... P7505
Actros III 3244 BlueTec 4+5 w/OM501LA Eng. (03/08-on)	40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	Fuel/Water Separator (A9604770003)..... BF1297-O
F-F Lube..... P7192	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT
Fuel/Water Separator..... BF1391-O	Air Dryer (Coalescer) (4295695).. BA5379 +	263 mm Air (A0040946804)..... CA30104
P. Fuel..... PF7761	Crankcase Breather (5410100080)..... CV15001	228 mm Air (A0040946904)..... CA30103
Pre-Fuel (924105)..... PF7939	Trans. (2690321)..... PT9423	210 mm Air (A0040947204)..... CA30105
338.1 mm Radial Seal Air w/Lid (Initial Installation)..... RS30065 KIT	Steering (1902137)..... P106-HD	Cab Air (A9608300018)..... PA30122
322.3 mm Radial Seal Air (Replacement Ele.)..... RS30065	Actros II 3246 w/OM501LA Eng. (04/03-on)	Cab Air (w/Carbon) (A9608300118)..... PA30123
532.6 mm Radial Seal Air..... RS5358	F-F Lube..... P7192	Cab Air (A9608300218)..... PA30124
Air (w/Extra Urea Tank)..... PA3765	Pre-Fuel (924105)..... PF7939	Cab Air (A0008307518)..... PA5585 <sup>90</sup>
379.4 mm Cab Air..... PA4956	Fuel..... PF7761	Air Dryer (A0004295695)..... BA5379 +
381.8 mm Cab Air (w/o Charcoal) ..... PA4912	Fuel/Water Separator..... BF1391-O	Coolant (A4722030255)..... P5092
381.8 mm Cab Air (w/Charcoal) (A0008303418)..... PA5492	Radial Seal Air (Initial Installation) (40942404)..... RS30065 KIT	Steering (A0004660604)..... P106-HD
Air Dryer (4295695)..... BA5379 +	Radial Seal Air (Replacement Ele.) (40942404)..... RS30065	Urea (A0001420089)..... PE17002 KIT
Steering..... P106-HD	Radial Seal Air (9/03-on) (40943504)..... RS5358	Actros III 3248 BlueTec 4+5 w/OM501LA Eng. (03/08-on)
Urea (A0001420089)..... PE5272	Panel Air (A0040941104)..... PA5426	F-F Lube..... P7192
Arocs 3245 w/OM471LA (BlueTec 5/6) Eng. (04/13-on)	38.9 mm Height Cab Air..... PA4956	Fuel/Water Separator..... BF1391-O
Lube (A4731800009)..... P7505	40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	P. Fuel..... PF7761
Fuel/Water Separator (A9604770003)..... BF1297-O	40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	Pre-Fuel (924105)..... PF7939
Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	338.1 mm Radial Seal Air w/Lid (Initial Installation)..... RS30065 KIT
263 mm Air (A0040946804)..... CA30104	Air Dryer (Coalescer) (4295695).. BA5379 +	322.3 mm Radial Seal Air (Replacement Ele.)..... RS30065
228 mm Air (A0040946904)..... CA30103	Crankcase Breather (5410100080)..... CV15001	532.6 mm Radial Seal Air..... RS5358
210 mm Air (A0040947204)..... CA30105	Steering..... P106-HD	Air (w/Extra Urea Tank)..... PA3765
Cab Air (A9608300018)..... PA30122	Actros III 3246 BlueTec 4+5 w/OM501LA Eng. (03/08-on)	379.4 mm Cab Air..... PA4956
Cab Air (w/Carbon) (A9608300118)..... PA30123	F-F Lube..... P7192	381.8 mm Cab Air (w/o Charcoal) ..... PA4912
Cab Air (A9608300218)..... PA30124	Fuel/Water Separator..... BF1391-O	381.8 mm Cab Air (w/Charcoal) (A0008303418)..... PA5492
Cab Air (A0008307518)..... PA5585 <sup>90</sup>	P. Fuel..... PF7761	Air Dryer (4295695)..... BA5379 +
Air Dryer (A0004295695)..... BA5379 +	Pre-Fuel (924105)..... PF7939	Steering..... P106-HD
Coolant (A4722030255)..... P5092	338.1 mm Radial Seal Air w/Lid (Initial Installation)..... RS30065 KIT	Urea (A0001420089)..... PE5272
Steering (A0004660604)..... P106-HD	322.3 mm Radial Seal Air (Replacement Ele.)..... RS30065	Actros II 3250 w/OM502LA Eng. (04/03-on)
Urea (A0001420089)..... PE17002 KIT	532.6 mm Radial Seal Air..... RS5358	F-F Lube..... P7192
Actros I 3246 w/OM501LA Eng. (09/96-12/03)	Air (w/Extra Urea Tank)..... PA3765	Pre-Fuel (924105)..... PF7939
F-F Lube (5411800009)..... P7192	379.4 mm Cab Air..... PA4956	Fuel..... PF7761
B-P Lube (21840525)..... C704-L	381.8 mm Cab Air (w/o Charcoal) ..... PA4912	Fuel/Water Separator..... BF1391-O
Pre-Fuel (924105)..... PF7939		Radial Seal Air (Initial Installation) (40942404)..... RS30065 KIT
Fuel..... PF7761		Radial Seal Air (Replacement Ele.) (40942404)..... RS30065
Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363		Radial Seal Air (9/03-on) (40943504)..... RS5358
		Panel Air (A0040941104)..... PA5426
		38.9 mm Height Cab Air..... PA4956

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Actros II 3250 w/OM502LA Eng. (04/03-on) (Cont'd)	Arocs 3263 w/OM473LA (BlueTec 5/6) Eng. (04/13-on) (Cont'd)	Actros I 3331K w/OM501LA Eng. (09/96-12/03)
40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	Cab Air (A9608300218)..... PA30124	F-F Lube (5411800009)..... P7192
40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	Air Dryer (A0004295695)..... BA5379 +	B-P Lube (21840525)..... C704-L
Air Dryer (Desiccant)..... BA5374 +	Steering (A0004660604)..... P106-HD	Fuel (5410920305)..... PF7761
Air Dryer (Coalescer) (4295695).. BA5379 +	Urea (A0001421089)..... PE17002 KIT	Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363
Crankcase Breather (5410100080)..... CV15001	Actros I 3331 w/OM501LA Eng. (09/96-12/03)	Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O
Steering..... P106-HD	F-F Lube (5411800009)..... P7192	Radial Seal Air (A0040940204)... RS5343
Arocs 3251 w/OM471LA (BlueTec 5/6) Eng. (04/13-on)	B-P Lube (21840525)..... C704-L	Panel Air (A0040941104)..... PA5426
Lube (A4731800009)..... P7505	Pre-Fuel (924105)..... PF7939	261.9 mm Air (A0030949204)..... PA3838 90
Fuel/Water Separator (A9604770003)..... BF1297-O	Fuel (5410920305)..... PF7761	318.3 mm Air (A0030949104)..... PA3844
Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT	Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363	38.9 mm Height Cab Air (Mann CU3869)..... PA4956
263 mm Air (A0040946804)..... CA30104	Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O	40.5 mm Height Cab Air (w/o Charcoal)..... PA4912
228 mm Air (A0040946904)..... CA30103	Radial Seal Air (A0040940204)... RS5343	40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492
210 mm Air (A0040947204)..... CA30105	Panel Air (A0040941104)..... PA5426	Air Dryer (Mann TB1374X)..... BA5374 +
Cab Air (A9608300018)..... PA30122	261.9 mm Air (A0030949204)..... PA3838 90	Crankcase Breather (5410100080)..... CV15001
Cab Air (w/Carbon) (A9608300118)..... PA30123	318.3 mm Air (A0030949104)..... PA3844	Trans. (2690321)..... PT9423
Cab Air (A9608300218)..... PA30124	38.9 mm Height Cab Air (Mann CU3869)..... PA4956	Steering (1902137)..... P106-HD
Cab Air (A0008307518)..... PA5585 90	40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	Actros II 3332 w/OM501LA Eng. (04/03-on)
Air Dryer (A0004295695)..... BA5379 +	40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	F-F Lube..... P7192
Coolant (A4722030255)..... P5092	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	Pre-Fuel (924105)..... PF7939
Steering (A0004660604)..... P106-HD	Air Dryer (Coalescer) (4295695).. BA5379 +	Fuel..... PF7761
Urea (A0001421089)..... PE17002 KIT	Crankcase Breather (5410100080)..... CV15001	Fuel/Water Separator..... BF1391-O
Arocs 3252 w/OM473LA (BlueTec 5/6) Eng. (04/13-on)	Trans. (2690321)..... PT9423	Radial Seal Air (Initial Installation) (40942404)..... RS30065 KIT
Lube (A4731800009)..... P7505	Steering (1902137)..... P106-HD	Radial Seal Air (Replacement Ele.) (40942404)..... RS30065
Fuel/Water Separator (A9604770003)..... BF1297-O	Actros I 3331B w/OM501LA Eng. (09/96-12/03)	Radial Seal Air (9/03-on) (40943504)..... RS5358
263 mm Air (A0040946804)..... CA30104	F-F Lube (5411800009)..... P7192	Panel Air (A0040941104)..... PA5426
228 mm Air (A0040946904)..... CA30103	B-P Lube (21840525)..... C704-L	38.9 mm Height Cab Air..... PA4956
210 mm Air (A0040947204)..... CA30105	Fuel (5410920305)..... PF7761	40.5 mm Height Cab Air (w/o Charcoal)..... PA4912
Cab Air (A9608300018)..... PA30122	Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363	40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492
Cab Air (w/Carbon) (A9608300118)..... PA30123	Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +
Cab Air (A0008307518)..... PA5585	Radial Seal Air (A0040940204)... RS5343	Air Dryer (Coalescer) (4295695).. BA5379 +
Cab Air (A9608300218)..... PA30124	Panel Air (A0040941104)..... PA5426	Crankcase Breather (5410100080)..... CV15001
Air Dryer (A0004295695)..... BA5379 +	261.9 mm Air (A0030949204)..... PA3838 90	Steering..... P106-HD
Steering (A0004660604)..... P106-HD	318.3 mm Air (A0030949104)..... PA3844	Actros III 3332 BlueTec 4+5 w/OM501LA Eng. (03/08-on)
Urea (A0001421089)..... PE17002 KIT	38.9 mm Height Cab Air (Mann CU3869)..... PA4956	F-F Lube..... P7192
Arocs 3263 w/OM473LA (BlueTec 5/6) Eng. (04/13-on)	40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	Fuel/Water Separator..... BF1391-O
Lube (A4731800009)..... P7505	40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	P. Fuel..... PF7761
Fuel/Water Separator (A9604770003)..... BF1297-O	Air Dryer (Mann TB1374X)..... BA5374 +	Pre-Fuel (924105)..... PF7939
263 mm Air (A0040946804)..... CA30104	Crankcase Breather (5410100080)..... CV15001	338.1 mm Radial Seal Air w/Lid (Initial Installation)..... RS30065 KIT
228 mm Air (A0040946904)..... CA30103	Trans. (2690321)..... PT9423	322.3 mm Radial Seal Air (Replacement Ele.)..... RS30065
210 mm Air (A0040947204)..... CA30105	Steering (1902137)..... P106-HD	532.6 mm Radial Seal Air..... RS5358
Cab Air (A9608300018)..... PA30122	Actros I 3331B w/OM501LA Eng. (09/96-12/03)	Air (w/Extra Urea Tank)..... PA3765
Cab Air (w/Carbon) (A9608300118)..... PA30123	F-F Lube (5411800009)..... P7192	379.4 mm Cab Air..... PA4956
Cab Air (A0008307518)..... PA5585	B-P Lube (21840525)..... C704-L	
	Fuel (5410920305)..... PF7761	
	Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363	
	Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O	
	Radial Seal Air (A0040940204)... RS5343	
	Panel Air (A0040941104)..... PA5426	
	261.9 mm Air (A0030949204)..... PA3838 90	
	318.3 mm Air (A0030949104)..... PA3844	
	38.9 mm Height Cab Air (Mann CU3869)..... PA4956	
	40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	
	40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	
	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	
	Air Dryer (Coalescer) (4295695).. BA5379 +	
	Crankcase Breather (5410100080)..... CV15001	
	Trans. (2690321)..... PT9423	
	Steering (1902137)..... P106-HD	

+ See Product Guide for Variations of This Number. 90 Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>MERCEDES-BENZ</b> European Trucks, Vans (cont'd)	<b>MERCEDES-BENZ</b> European Trucks, Vans (cont'd)	<b>MERCEDES-BENZ</b> European Trucks, Vans (cont'd)
Actros III 3332 BlueTec 4+5 w/OM501LA Eng. (03/08-on) (Cont'd)	Actros I 3335 w/OM501LA Eng. (09/96-12/03) (Cont'd)	Actros I 3335S w/OM501LA Eng. (09/96-12/03) (Cont'd)
381.8 mm Cab Air (w/o Charcoal) PA4912	Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363	38.9 mm Height Cab Air (Mann CU3869)..... PA4956
381.8 mm Cab Air (w/Charcoal) (A0008303418)..... PA5492	Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O	40.5 mm Height Cab Air (w/o Charcoal)..... PA4912
Air Dryer (4295695)..... BA5379 +	Radial Seal Air (A0040942024)..... RS5343	40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492
Steering..... P106-HD	Panel Air (A0040941104)..... PA5426	Air Dryer (Mann TB1374X)..... BA5374 +
Urea (A0001420089)..... PE5272	261.9 mm Air (A0030949204)..... PA3838 <sup>90</sup>	Crankcase Breather (5410100080)..... CV15001
Arocs 3333 w/OM470LA (BlueTec 5/6) Eng. (04/13-on)	318.3 mm Air (A0030949104)..... PA3844	Trans. (2690321)..... PT9423
Fuel/Water Separator (A9604770003)..... BF1297-O	38.9 mm Height Cab Air (Mann CU3869)..... PA4956	Steering (1902137)..... P106-HD
210 mm Air (A0040947204)..... CA30105	40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	Arocs 3336 w/OM470LA (BlueTec 5/6) Eng. (04/13-on)
228 mm Air (A0040946904)..... CA30103	40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	Fuel/Water Separator (A9604770003)..... BF1297-O
263 mm Air (A0040946804)..... CA30104	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	210 mm Air (A0040947204)..... CA30105
Cab Air (A9608300018)..... PA30122	Air Dryer (Coalescer) (4295695)..... BA5379 +	228 mm Air (A0040946904)..... CA30103
Cab Air (w/Carbon) (A9608300118)..... PA30123	Crankcase Breather (5410100080)..... CV15001	263 mm Air (A0040946804)..... CA30104
Cab Air (A0008307518)..... PA5585	Trans. (2690321)..... PT9423	Cab Air (A9608300018)..... PA30122
Cab Air (A9608300218)..... PA30124	Steering (1902137)..... P106-HD	Cab Air (w/Carbon) (A9608300118)..... PA30123
Air Dryer (A0004295695)..... BA5379 +	Axor II 3335 w/OM457LA Eng. (09/04-on)	Cab Air (A0008307518)..... PA5585
Steering (A0004660604)..... P106-HD	Lube (A0001802109)..... P7230	Cab Air (A9608300218)..... PA30124
Urea (A0001421089)..... PE17002 KIT	Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363	Air Dryer (A0004295695)..... BA5379 +
Actros II MP4 3333 w/OM470LA (BlueTec 5/6) Eng. (09/12-on)	Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O	Steering (A0004660604)..... P106-HD
Fuel/Water Separator (A9604770003)..... BF1297-O	Fuel/Water Separator (Bio Diesel) (A0004771702)..... BF46105-O	Urea (A0001421089)..... PE17002 KIT
210 mm Air (A0040947204)..... CA30105	Fuel Screen (A0000902051)..... PF7939	Actros II MP4 3336 w/OM470LA (BlueTec 5/6) Eng. (09/12-on)
228 mm Air (A0040946904)..... CA30103	338.1 mm Radial Seal Air w/Lid (Initial Installation) (A0040942404)..... RS30065 KIT	Fuel/Water Separator (A9604770003)..... BF1297-O
263 mm Air (A0040946804)..... CA30104	532.6 mm Radial Seal O. Air (4760940004)..... RS5358	210 mm Air (A0040947204)..... CA30105
Cab Air (A9608300018)..... PA30122	Radial Seal I. Air (A0040947304)..... RS5549	228 mm Air (A0040946904)..... CA30103
Cab Air (w/Carbon) (A9608300118)..... PA30123	322.3 mm Radial Seal Air (Replacement Ele.) (A0040942404)..... RS30065	263 mm Air (A0040946804)..... CA30104
Cab Air (A0008307518)..... PA5585	Air (Pre-Cleaner) (A0030949004)..... PA5426	Cab Air (A9608300018)..... PA30122
Cab Air (A9608300218)..... PA30124	Cab Air (9408350047)..... PA4945	Cab Air (w/Carbon) (A9608300118)..... PA30123
Air Dryer (A0004295695)..... BA5379 +	Air Dryer (A0004295695)..... BA5379 +	Cab Air (A0008307518)..... PA5585
Steering (A0004660604)..... P106-HD	Steering (A0004660604)..... P106-HD	Cab Air (A9608300218)..... PA30124
Urea (A0001421089)..... PE17002 KIT	Actros I 3335S w/OM501LA Eng. (09/96-12/03)	Air Dryer (A0004295695)..... BA5379 +
Antos 3333 w/OM470LA (BlueTec 5/6) Eng. (09/12-on)	F-F Lube (5411800009)..... P7192	Steering (A0004660604)..... P106-HD
Fuel/Water Separator (A9604770003)..... BF1297-O	B-P Lube (21840525)..... C704-L	Urea (A0001421089)..... PE17002 KIT
210 mm Air (A0040947204)..... CA30105	Fuel (5410920305)..... PF7761	Antos 3336 w/OM470LA (BlueTec 5/6) Eng. (09/12-on)
228 mm Air (A0040946904)..... CA30103	Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363	Fuel/Water Separator (A9604770003)..... BF1297-O
263 mm Air (A0040946804)..... CA30104	Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O	210 mm Air (A0040947204)..... CA30105
Cab Air (A9608300018)..... PA30122	Radial Seal Air (A0040942024)..... RS5343	228 mm Air (A0040946904)..... CA30103
Cab Air (w/Carbon) (A9608300118)..... PA30123	Panel Air (A0040941104)..... PA5426	263 mm Air (A0040946804)..... CA30104
Cab Air (A0008307518)..... PA5585	261.9 mm Air (A0030949204)..... PA3838 <sup>90</sup>	Cab Air (A9608300018)..... PA30122
Cab Air (A9608300218)..... PA30124	318.3 mm Air (A0030949104)..... PA3844	Cab Air (w/Carbon) (A9608300118)..... PA30123
Air Dryer (A0004295695)..... BA5379 +		Cab Air (A0008307518)..... PA5585
Steering (A0004660604)..... P106-HD		Cab Air (A9608300218)..... PA30124
Urea (A0001421089)..... PE17002 KIT		Air Dryer (A0004295695)..... BA5379 +
Actros I 3335 w/OM501LA Eng. (09/96-12/03)		Steering (A0004660604)..... P106-HD
F-F Lube (5411800009)..... P7192		Urea (A0001421089)..... PE17002 KIT
B-P Lube (21840525)..... C704-L		
Pre-Fuel (924105)..... PF7939		
Fuel (5410920305)..... PF7761		

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.


Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Actros II 3336 w/OM501LA Eng. (04/03-on) F-F Lube..... P7192 Pre-Fuel (924105)..... PF7939 Fuel..... PF7761 Fuel/Water Separator..... BF1391-O Radial Seal Air (Initial Installation) (40942404)..... RS30065 KIT Radial Seal Air (Replacement Ele.) (40942404)..... RS30065 Radial Seal Air (9/03-on) (40943504)..... RS5358 Panel Air (A0040941104)..... PA5426 38.9 mm Height Cab Air..... PA4956 40.5 mm Height Cab Air (w/o Charcoal)..... PA4912 40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Crankcase Breather (5410100080)..... CV15001 Steering..... P106-HD	Actros II MP4 3340 w/OM470LA (BlueTec 5/6) Eng. (09/12-on) Fuel/Water Separator (A9604770003)..... BF1297-O 210 mm Air (A0040947204)..... CA30105 228 mm Air (A0040946904)..... CA30103 263 mm Air (A0040946804)..... CA30104 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A0008307518)..... PA5585 Cab Air (A9608300218)..... PA30124 Air Dryer (A0004295695)..... BA5379 + Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT Arocs 3340 w/OM470LA (BlueTec 5/6) Eng. (04/13-on) Fuel/Water Separator (A9604770003)..... BF1297-O 210 mm Air (A0040947204)..... CA30105 228 mm Air (A0040946904)..... CA30103 263 mm Air (A0040946804)..... CA30104 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A0008307518)..... PA5585 Cab Air (A9608300218)..... PA30124 Air Dryer (A0004295695)..... BA5379 + Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT Antos 3340 w/OM470LA (BlueTec 5/6) Eng. (09/12-on) Fuel/Water Separator (A9604770003)..... BF1297-O 210 mm Air (A0040947204)..... CA30105 228 mm Air (A0040946904)..... CA30103 263 mm Air (A0040946804)..... CA30104 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A0008307518)..... PA5585 Cab Air (A9608300218)..... PA30124 Air Dryer (A0004295695)..... BA5379 + Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT Actros I 3340 w/OM501LA Eng. (09/96-12/03) F-F Lube (5411800009)..... P7192 B-P Lube (21840525)..... C704-L Pre-Fuel (924105)..... PF7939 Fuel (5410920305)..... PF7761 Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363 Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O Radial Seal Air (A0040940204)..... RS5343 Panel Air (A0040941104)..... PA5426 261.9 mm Air (A0030949204)..... PA3838 <sup>90</sup> 318.3 mm Air (A0030949104)..... PA3844 38.9 mm Height Cab Air (Mann CU3869)..... PA4956 40.5 mm Height Cab Air (w/o Charcoal)..... PA4912 40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492 Air Dryer (Mann TB1374X)..... BA5374 + Crankcase Breather (5410100080)..... CV15001	Actros I 3340 w/OM501LA Eng. (09/96-12/03) (Cont'd) 38.9 mm Height Cab Air (Mann CU3869)..... PA4956 40.5 mm Height Cab Air (w/o Charcoal)..... PA4912 40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Crankcase Breather (5410100080)..... CV15001 Trans. (2690321)..... PT9423 Steering (1902137)..... P106-HD Axor II 3340 w/OM457LA Eng. (09/04-on) Lube (A0001802109)..... P7230 Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363 Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O Fuel/Water Separator (Bio Diesel) (A0004771702)..... BF46105-O Fuel Screen (A0000902051)..... PF7939 338.1 mm Radial Seal Air w/Lid (Initial Installation) (A0040942404)..... RS30065 KIT 322.3 mm Radial Seal Air (Replacement Ele.) (A0040942404)..... RS30065 532.6 mm Radial Seal O. Air (4760940004)..... RS5358 Radial Seal I. Air (A0040947304)..... RS5549 Air (Pre-Cleaner) (A0030949004)..... PA5426 Cab Air (9408350047)..... PA4945 Air Dryer (A0004295695)..... BA5379 + Steering (A0004660604)..... P106-HD Actros I 3340B w/OM501LA Eng. (09/96-12/03) F-F Lube (5411800009)..... P7192 B-P Lube (21840525)..... C704-L Fuel (5410920305)..... PF7761 Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363 Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O Radial Seal Air (A0040940204)..... RS5343 Panel Air (A0040941104)..... PA5426 261.9 mm Air (A0030949204)..... PA3838 <sup>90</sup> 318.3 mm Air (A0030949104)..... PA3844 38.9 mm Height Cab Air (Mann CU3869)..... PA4956 40.5 mm Height Cab Air (w/o Charcoal)..... PA4912 40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492 Air Dryer (Mann TB1374X)..... BA5374 + Crankcase Breather (5410100080)..... CV15001
Axros III 3336 BlueTec 4+5 w/OM501LA Eng. (03/08-on) F-F Lube..... P7192 Fuel/Water Separator..... BF1391-O P. Fuel..... PF7761 Pre-Fuel (924105)..... PF7939 338.1 mm Radial Seal Air (Initial Installation) (40942404)..... RS30065 KIT 322.3 mm Radial Seal Air (Replacement Ele.) (40942404).. RS30065 532.6 mm Radial Seal Air..... RS5358 Air (w/Extra Urea Tank)..... PA3765 379.4 mm Cab Air..... PA4956 381.8 mm Cab Air (w/o Charcoal) PA4912 381.8 mm Cab Air (w/Charcoal) (A0008303418)..... PA5492 Air Dryer (4295695)..... BA5379 + Steering..... P106-HD Urea (A0001420089)..... PE5272	Arocs 3339 w/OM470LA (BlueTec 5/6) Eng. (04/13-on) Fuel/Water Separator (A9604770003)..... BF1297-O 210 mm Air (A0040947204)..... CA30105 228 mm Air (A0040946904)..... CA30103 263 mm Air (A0040946804)..... CA30104 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A0008307518)..... PA5585 Cab Air (A9608300218)..... PA30124 Air Dryer (A0004295695)..... BA5379 + Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT	

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Actros I 3340B w/OM501LA Eng. (09/96-12/03) (Cont'd)	Actros III 3341 BlueTec 4+5 w/OM501LA Eng. (03/08-on) (Cont'd)	Arocs 3342 w/OM471LA (BlueTec 5/6) Eng. (04/13-on) (Cont'd)
Trans. (2690321)..... PT9423	322.3 mm Radial Seal Air (Replacement Ele.)..... RS30065	210 mm Air (A0040947204)..... CA30105
Steering (1902137)..... P106-HD	532.6 mm Radial Seal Air..... RS5358	228 mm Air (A0040946904)..... CA30103
Actros I 3340S w/OM501LA Eng. (09/96-12/03)	Air (w/Extra Urea Tank)..... PA3765	263 mm Air (A0040946804)..... CA30104
F-F Lube (5411800009)..... P7192	379.4 mm Cab Air..... PA4956	Cab Air (A9608300018)..... PA30122
B-P Lube (21840525)..... C704-L	381.8 mm Cab Air (w/o Charcoal) (A0008303418)..... PA4912	Cab Air (w/Carbon) (A9608300118)..... PA30123
Fuel (5410920305)..... PF7761	Air Dryer (4295695)..... BA5379 +	Cab Air (A0008307518)..... PA5585
Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363	Steering..... P106-HD	Cab Air (A9608300218)..... PA30124
Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O	Urea (A0001420089)..... PE5272	Air Dryer (A0004295695)..... BA5379 +
Radial Seal Air (A0040940204)..... RS5343	Actros 3342 w/OM471LA (BlueTec 5/6) Eng. (09/12-on)	Coolant (A4722030255)..... P5092
Panel Air (A0040941104)..... PA5426	Lube (A4731800009)..... P7505	Steering (A0004660604)..... P106-HD
261.9 mm Air (A0030949204)..... PA3838 <sup>90</sup>	Fuel/Water Separator (A9604770003)..... BF1297-O	Urea (A0001421089)..... PE17002 KIT
318.3 mm Air (A0030949104)..... PA3844	Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT	Arocs 3343 w/OM470LA (BlueTec 5/6) Eng. (04/13-on)
38.9 mm Height Cab Air (Mann CU3869)..... PA4956	263 mm Air (A0040946804)..... CA30104	Fuel/Water Separator (A9604770003)..... BF1297-O
40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	228 mm Air (A0040946904)..... CA30103	210 mm Air (A0040947204)..... CA30105
40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	210 mm Air (A0040947204)..... CA30105	228 mm Air (A0040946904)..... CA30103
Air Dryer (Mann TB1374X)..... BA5374 +	Cab Air (A9608300018)..... PA30122	263 mm Air (A0040946804)..... CA30104
Crankcase Breather (5410100080)..... CV15001	Cab Air (w/Carbon) (A9608300118)..... PA30123	Cab Air (A9608300018)..... PA30122
Trans. (2690321)..... PT9423	Cab Air (A9608300218)..... PA30124	Cab Air (w/Carbon) (A9608300118)..... PA30123
Steering (1902137)..... P106-HD	Cab Air (A0008307518)..... PA5585 <sup>90</sup>	Cab Air (A0008307518)..... PA5585
Actros II 3341 w/OM501LA Eng. (04/03-on)	Air Dryer (A0004295695)..... BA5379 +	Cab Air (A9608300218)..... PA30124
F-F Lube..... P7192	Coolant (A4722030255)..... P5092	Air Dryer (A0004295695)..... BA5379 +
Pre-Fuel (924105)..... PF7939	Steering (A0004660604)..... P106-HD	Steering (A0004660604)..... P106-HD
Fuel..... PF7761	Urea (A0001421089)..... PE17002 KIT	Urea (A0001421089)..... PE17002 KIT
Fuel/Water Separator..... BF1391-O	Actros II MP4 3342 w/OM471LA (BlueTec 5/6) Eng. (09/11-on)	Actros II MP4 3343 w/OM470LA (BlueTec 5/6) Eng. (09/12-on)
Radial Seal Air (Initial Installation) (40942404)..... RS30065 KIT	Lube (A4731800009)..... P7505	Fuel/Water Separator (A9604770003)..... BF1297-O
Radial Seal Air (Replacement Ele.) (40942404)..... RS30065	Fuel/Water Separator (A9604770003)..... BF1297-O	210 mm Air (A0040947204)..... CA30105
Radial Seal Air (9/03-on) (40943504)..... RS5358	Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT	228 mm Air (A0040946904)..... CA30103
Panel Air (A0040941104)..... PA5426	263 mm Air (A0040946804)..... CA30104	263 mm Air (A0040946804)..... CA30104
38.9 mm Height Cab Air..... PA4956	228 mm Air (A0040946904)..... CA30103	Cab Air (A9608300018)..... PA30122
40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	210 mm Air (A0040947204)..... CA30105	Cab Air (w/Carbon) (A9608300118)..... PA30123
40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	Cab Air (A9608300018)..... PA30122	Cab Air (A0008307518)..... PA5585
Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	Cab Air (w/Carbon) (A9608300118)..... PA30123	Cab Air (A9608300218)..... PA30124
Air Dryer (Coalescer) (4295695)..... BA5379 +	Cab Air (A9608300218)..... PA30124	Air Dryer (A0004295695)..... BA5379 +
Crankcase Breather (5410100080)..... CV15001	Air Dryer (A0004295695)..... BA5379 +	Steering (A0004660604)..... P106-HD
Steering..... P106-HD	Coolant (A4722030255)..... P5092	Urea (A0001421089)..... PE17002 KIT
Actros III 3341 BlueTec 4+5 w/OM501LA Eng. (03/08-on)	Steering (A0004660604)..... P106-HD	Actros 3343 w/OM470LA (BlueTec 5/6) Eng. (09/12-on)
F-F Lube..... P7192	Urea (A0001421089)..... PE17002 KIT	Fuel/Water Separator (A9604770003)..... BF1297-O
Fuel/Water Separator..... BF1391-O	Arocs 3342 w/OM471LA (BlueTec 5/6) Eng. (04/13-on)	210 mm Air (A0040947204)..... CA30105
P. Fuel..... PF7761	Lube (A4721800309)..... P7505	228 mm Air (A0040946904)..... CA30103
Pre-Fuel (924105)..... PF7939	Fuel/Water Separator (A9604770003)..... BF1297-O	263 mm Air (A0040946804)..... CA30104
338.1 mm Radial Seal Air w/Lid (Initial Installation)..... RS30065 KIT	Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT	Cab Air (A9608300018)..... PA30122

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.


Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Antos 3343 w/OM470LA (BlueTec 5/6) Eng. (09/12-on) (Cont'd) Urea (A0001421089)..... PE17002 KIT	Actros I 3343S w/OM501LA Eng. (09/96-12/03) (Cont'd) Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O Radial Seal Air (A004094204)..... RS5343 Panel Air (A0040941104)..... PA5426 261.9 mm Air (A0030949204)..... PA3838 <sup>90</sup> 318.3 mm Air (A0030949104)..... PA3844 38.9 mm Height Cab Air (Mann CU3869)..... PA4956 40.5 mm Height Cab Air (w/o Charcoal)..... PA4912 40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Crankcase Breather (5410100080)..... CV15001 Trans. (2690321)..... PT9423 Steering (1902137)..... P106-HD	Actros III 3344 BlueTec 4+5 w/OM501LA Eng. (03/08-on) (Cont'd) Steering..... P106-HD Urea (A0001420089)..... PE5272
Actros I 3343 w/OM501LA Eng. (09/96-12/03) F-F Lube (5411800009)..... P7192 B-P Lube (21840525)..... C704-L Pre-Fuel (924105)..... PF7939 Fuel (5410920305)..... PF7761 Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363 Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O Radial Seal Air (A004094204)..... RS5343 Panel Air (A0040941104)..... PA5426 261.9 mm Air (A0030949204)..... PA3838 <sup>90</sup> 318.3 mm Air (A0030949104)..... PA3844 38.9 mm Height Cab Air (Mann CU3869)..... PA4956 40.5 mm Height Cab Air (w/o Charcoal)..... PA4912 40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Crankcase Breather (5410100080)..... CV15001 Trans. (2690321)..... PT9423 Steering (1902137)..... P106-HD	Actros II 3344 w/OM501LA Eng. (04/03-on) F-F Lube..... P7192 Pre-Fuel (924105)..... PF7939 Fuel..... PF7761 Fuel/Water Separator..... BF1391-O Radial Seal Air (Initial Installation) (40942404)..... RS30065 KIT Radial Seal Air (Replacement Ele.) (40942404)..... RS30065 Radial Seal Air (9/03-on) (40943504)..... RS5358 Panel Air (A0040941104)..... PA5426 38.9 mm Height Cab Air..... PA4956 40.5 mm Height Cab Air (w/o Charcoal)..... PA4912 40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Crankcase Breather (5410100080)..... CV15001 Steering..... P106-HD	Actros III 3344 BlueTec 4+5 w/OM501LA Eng. (03/08-on) F-F Lube..... P7192 Fuel/Water Separator..... BF1391-O P. Fuel..... PF7761 Pre-Fuel (924105)..... PF7939 338.1 mm Radial Seal Air w/Lid (Initial Installation)..... RS30065 KIT 322.3 mm Radial Seal Air (Replacement Ele.)..... RS30065 532.6 mm Radial Seal Air..... RS5358 Air (w/Extra Urea Tank)..... PA3765 379.4 mm Cab Air..... PA4956 381.8 mm Cab Air (w/o Charcoal)..... PA4912 381.8 mm Cab Air (w/Charcoal) (A0008303418)..... PA5492 Air Dryer (4295695)..... BA5379 +
Axor II 3343 w/OM457LA Eng. (09/04-on) Lube (A0001802109)..... P7230 Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363 Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O Fuel/Water Separator (Bio Diesel) (A0004771702)..... BF46105-O Fuel Screen (A0000902051)..... PF7939 532.6 mm Radial Seal O. Air (4760940004)..... RS5358 Radial Seal I. Air (A0040947304)..... RS5549 338.1 mm Radial Seal Air w/Lid (Initial Installation) (A0040942404)..... RS30065 KIT 322.3 mm Radial Seal Air (Replacement Ele.) (A0040942404)..... RS30065 Air (Pre-Cleaner) (A0030949004). PA5426 Cab Air (9408350047)..... PA4945 Air Dryer (A0004295695)..... BA5379 + Steering (A0004660604)..... P106-HD	Actros II MP4 3345 w/OM471LA (BlueTec 5/6) Eng. (09/11-on) Lube (A4731800009)..... P7505 Fuel/Water Separator (A9604770003)..... BF1297-O Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT 263 mm Air (A0040946804)..... CA30104 228 mm Air (A0040946904)..... CA30103 210 mm Air (A0040947204)..... CA30105 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A9608300218)..... PA30124 Cab Air (A0008307518)..... PA5585 <sup>90</sup> Air Dryer (A0004295695)..... BA5379 + Coolant (A4722030255)..... P5092 Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT	Actros III 3344 BlueTec 4+5 w/OM501LA Eng. (03/08-on) (Cont'd) Steering..... P106-HD Urea (A0001420089)..... PE5272
Actros I 3343S w/OM501LA Eng. (09/96-12/03) F-F Lube (5411800009)..... P7192 B-P Lube (21840525)..... C704-L Fuel (5410920305)..... PF7761 Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363	Actros III 3344 BlueTec 4+5 w/OM501LA Eng. (03/08-on) F-F Lube..... P7192 Fuel/Water Separator..... BF1391-O P. Fuel..... PF7761 Pre-Fuel (924105)..... PF7939 338.1 mm Radial Seal Air w/Lid (Initial Installation)..... RS30065 KIT 322.3 mm Radial Seal Air (Replacement Ele.)..... RS30065 532.6 mm Radial Seal Air..... RS5358 Air (w/Extra Urea Tank)..... PA3765 379.4 mm Cab Air..... PA4956 381.8 mm Cab Air (w/o Charcoal)..... PA4912 381.8 mm Cab Air (w/Charcoal) (A0008303418)..... PA5492 Air Dryer (4295695)..... BA5379 +	Axros 3345 w/OM471LA (BlueTec 5/6) Eng. (04/13-on) Lube (A4721800309)..... P7505 Fuel/Water Separator (A9604770003)..... BF1297-O Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT 210 mm Air (A0040947204)..... CA30105 228 mm Air (A0040946904)..... CA30103 263 mm Air (A0040946804)..... CA30104 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A0008307518)..... PA5585 Cab Air (A9608300218)..... PA30124 Air Dryer (A0004295695)..... BA5379 +

\* See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
<b>Arocs 3345 w/OM471LA (BlueTec 5/6) Eng. (04/13-on) (Cont'd)</b> Coolant (A4722030255)..... P5092 Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT	<b>Actros III 3346 BlueTec 4+5 w/OM501LA Eng. (03/08-on) (Cont'd)</b> Pre-Fuel (924105)..... PF7939 338.1 mm Radial Seal Air w/Lid (Initial Installation)..... RS30065 KIT 322.3 mm Radial Seal Air (Replacement Ele.)..... RS30065 532.6 mm Radial Seal Air..... RS5358 Air (w/Extra Urea Tank)..... PA3765 379.4 mm Cab Air..... PA4956 381.8 mm Cab Air (w/o Charcoal) PA4912 381.8 mm Cab Air (w/Charcoal) (A0008303418)..... PA5492 Air Dryer (4295695)..... BA5379 + Steering..... P106-HD Urea (A0001420089)..... PE5272	<b>Actros II MP4 3348 w/OM471LA (BlueTec 5/6) Eng. (09/11-on)</b> Lube (A4731800009)..... P7505 <b>Fuel/Water Separator (A9604770003)..... BF1297-O</b> Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT 263 mm Air (A0040946804)..... CA30104 228 mm Air (A0040946904)..... CA30103 210 mm Air (A0040947204)..... CA30105 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A9608300218)..... PA30124 Cab Air (A0008307518)..... PA5585 <sup>90</sup> Air Dryer (A0004295695)..... BA5379 + Coolant (A4722030255)..... P5092 Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT
<b>Actros I 3346 w/OM501LA Eng. (09/96-12/03)</b> F-F Lube (5411800009)..... P7192 B-P Lube (21840525)..... C704-L Pre-Fuel (924105)..... PF7939 Fuel (5410920305)..... PF7761 Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363 Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O Radial Seal Air (A0040940204)..... RS5343 Panel Air (A0040941104)..... PA5426 261.9 mm Air (A0030949204)..... PA3838 <sup>90</sup> 318.3 mm Air (A0030949104)..... PA3844 38.9 mm Height Cab Air (Mann CU3869)..... PA4956 40.5 mm Height Cab Air (w/o Charcoal)..... PA4912 40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Crankcase Breather (5410100080)..... CV15001 Trans. (2690321)..... PT9423 Steering (1902137)..... P106-HD	<b>Actros I 3346S w/OM501LA Eng. (09/96-12/03)</b> F-F Lube (5411800009)..... P7192 B-P Lube (21840525)..... C704-L Fuel (5410920305)..... PF7761 Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363 Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O Radial Seal Air (A0040940204)..... RS5343 Panel Air (A0040941104)..... PA5426 261.9 mm Air (A0030949204)..... PA3838 <sup>90</sup> 318.3 mm Air (A0030949104)..... PA3844 38.9 mm Height Cab Air (Mann CU3869)..... PA4956 40.5 mm Height Cab Air (w/o Charcoal)..... PA4912 40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492 Air Dryer (Mann TB1374X)..... BA5374 + Crankcase Breather (5410100080)..... CV15001 Trans. (2690321)..... PT9423 Steering (1902137)..... P106-HD	<b>Actros I 3348 w/OM502LA Eng. (09/96-12/03)</b> F-F Lube (5411800009)..... P7192 B-P Lube (21840525)..... C704-L Pre-Fuel (924105)..... PF7939 Fuel (5410920305)..... PF7761 Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363 Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O 261.9 mm Air (A0030949204)..... PA3838 <sup>90</sup> 318.3 mm Air (A0030949104)..... PA3844 38.9 mm Height Cab Air (Mann CU3869)..... PA4956 40.5 mm Height Cab Air (w/o Charcoal)..... PA4912 40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Crankcase Breather (5410100080)..... CV15001 Trans. (2690321)..... PT9423 Steering (1902137)..... P106-HD
<b>Actros II 3346 w/OM501LA Eng. (04/03-on)</b> F-F Lube..... P7192 Pre-Fuel (924105)..... PF7939 Fuel..... PF7761 Fuel/Water Separator..... BF1391-O Radial Seal Air (Initial Installation) (40942404)..... RS30065 KIT Radial Seal Air (Replacement Ele.) (40942404)..... RS30065 Radial Seal Air (9/03-on) (40943504)..... RS5358 Panel Air (A0040941104)..... PA5426 38.9 mm Height Cab Air..... PA4956 40.5 mm Height Cab Air (w/o Charcoal)..... PA4912 40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Crankcase Breather (5410100080)..... CV15001 Steering..... P106-HD	<b>Antos 3348 w/OM471LA (BlueTec 5/6) Eng. (09/12-on)</b> Lube (A4731800009)..... P7505 Fuel/Water Separator (A9604770003)..... BF1297-O Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT 263 mm Air (A0040946804)..... CA30104 228 mm Air (A0040946904)..... CA30103 210 mm Air (A0040947204)..... CA30105 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A9608300218)..... PA30124 Cab Air (A0008307518)..... PA5585 <sup>90</sup> Air Dryer (A0004295695)..... BA5379 + Coolant (A4722030255)..... P5092 Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT	<b>Actros III 3348 BlueTec 4+5 w/OM501LA Eng. (03/08-on)</b> F-F Lube..... P7192 Fuel/Water Separator..... BF1391-O P. Fuel..... PF7761 Pre-Fuel (924105)..... PF7939 338.1 mm Radial Seal Air w/Lid (Initial Installation)..... RS30065 KIT 322.3 mm Radial Seal Air (Replacement Ele.)..... RS30065 532.6 mm Radial Seal Air..... RS5358 Air (w/Extra Urea Tank)..... PA3765 379.4 mm Cab Air..... PA4956 381.8 mm Cab Air (w/o Charcoal) PA4912 381.8 mm Cab Air (w/Charcoal) (A0008303418)..... PA5492
<b>Actros III 3346 BlueTec 4+5 w/OM501LA Eng. (03/08-on)</b> F-F Lube..... P7192 Fuel/Water Separator..... BF1391-O P. Fuel..... PF7761		

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.


Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Actros III 3348 BlueTec 4+5 w/OM501LA Eng. (03/08-on) (Cont'd) Air Dryer (4295695)..... BA5379 + Steering..... P106-HD Urea (A0001420089)..... PE5272	Actros II 3350 w/OM501LA Eng. (04/03-on) (Cont'd) 40.5 mm Height Cab Air (w/o Charcoal)..... PA4912 40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492 Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 + Air Dryer (Coalescer) (4295695).. BA5379 + Crankcase Breather (5410100080)..... CV15001 Steering..... P106-HD	Actros III 3351 BlueTec 4+5 w/OM502LA Eng. (03/08-on) (Cont'd) 322.3 mm Radial Seal Air (Replacement Ele.)..... RS30065 532.6 mm Radial Seal Air..... RS5358 Air (w/Extra Urea Tank)..... PA3765 379.4 mm Cab Air..... PA4956 381.8 mm Cab Air (w/o Charcoal) PA4912 381.8 mm Cab Air (w/Charcoal) (A0008303418)..... PA5492 Air Dryer (4295695)..... BA5379 + Steering..... P106-HD Urea (A0001420089)..... PE5272
Arocs 3348 w/OM471LA (BlueTec 5/6) Eng. (04/13-on) Lube (A4721800309)..... P7505 Fuel/Water Separator (A9604770003)..... BF1297-O Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT 210 mm Air (A0040947204)..... CA30105 228 mm Air (A0040946904)..... CA30103 263 mm Air (A0040946804)..... CA30104 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A0008307518)..... PA5585 Cab Air (A9608300218)..... PA30124 Air Dryer (A0004295695)..... BA5379 + Coolant (A4722030255)..... P5092 Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT	Antos 3351 w/OM471LA (BlueTec 5/6) Eng. (09/12-on) Lube (A4731800009)..... P7505 Fuel/Water Separator (A9604770003)..... BF1297-O Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT 263 mm Air (A0040946804)..... CA30104 228 mm Air (A0040946904)..... CA30103 210 mm Air (A0040947204)..... CA30105 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A9608300218)..... PA30124 Cab Air (A0008307518)..... PA5585 <sup>90</sup> Air Dryer (A0004295695)..... BA5379 + Coolant (A4722030255)..... P5092 Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT	Arocs 3351 w/OM471LA (BlueTec 5/6) Eng. (04/13-on) Lube (A4721800309)..... P7505 Fuel/Water Separator (A9604770003)..... BF1297-O Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT 210 mm Air (A0040947204)..... CA30105 228 mm Air (A0040946904)..... CA30103 263 mm Air (A0040946804)..... CA30104 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A0008307518)..... PA5585 Cab Air (A9608300218)..... PA30124 Air Dryer (A0004295695)..... BA5379 + Coolant (A4722030255)..... P5092 Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT
Actros I 3348S w/OM502LA Eng. (09/96-12/03) F-F Lube (5411800009)..... P7192 B-P Lube (21840525)..... C704-L Fuel (5410920305)..... PF7761 Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363 Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O 261.9 mm Air (A0030949204)..... PA3838 <sup>90</sup> 318.3 mm Air (A0030949104)..... PA3844 38.9 mm Height Cab Air (Mann CU3869)..... PA4956 40.5 mm Height Cab Air (w/o Charcoal)..... PA4912 40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492 Air Dryer (Mann TB1374X)..... BA5374 + Crankcase Breather (5410100080)..... CV15001 Trans. (2690321)..... PT9423 Steering (1902137)..... P106-HD	Actros II MP4 3351 w/OM471LA (BlueTec 5/6) Eng. (09/11-on) Lube (A4731800009)..... P7505 Fuel/Water Separator (A9604770003)..... BF1297-O Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT 263 mm Air (A0040946804)..... CA30104 228 mm Air (A0040946904)..... CA30103 210 mm Air (A0040947204)..... CA30105 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A9608300218)..... PA30124 Cab Air (A0008307518)..... PA5585 <sup>90</sup> Air Dryer (A0004295695)..... BA5379 + Coolant (A4722030255)..... P5092 Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT	Arocs 3352 w/OM473LA (BlueTec 5/6) Eng. (04/13-on) Lube (A4731800009)..... P7505 Fuel/Water Separator (A9604770003)..... BF1297-O 263 mm Air (A0040946804)..... CA30104 228 mm Air (A0040946904)..... CA30103 210 mm Air (A0040947204)..... CA30105 Cab Air (A9608300018)..... PA30122 Cab Air (w/Carbon) (A9608300118)..... PA30123 Cab Air (A0008307518)..... PA5585 Cab Air (A9608300218)..... PA30124 Air Dryer (A0004295695)..... BA5379 + Steering (A0004660604)..... P106-HD Urea (A0001421089)..... PE17002 KIT
Actros II 3350 w/OM501LA Eng. (04/03-on) F-F Lube..... P7192 Pre-Fuel (924105)..... PF7939 Fuel..... PF7761 Fuel/Water Separator..... BF1391-O Radial Seal Air (Initial Installation) (40942404)..... RS30065 KIT Radial Seal Air (Replacement Ele.) (40942404)..... RS30065 Radial Seal Air (9/03-on) (40943504)..... RS5358 Panel Air (A0040941104)..... PA5426 38.9 mm Height Cab Air..... PA4956	Actros III 3351 BlueTec 4+5 w/OM502LA Eng. (03/08-on) F-F Lube..... P7192 Fuel/Water Separator..... BF1391-O P. Fuel..... PF7761 Pre-Fuel (924105)..... PF7939 338.1 mm Radial Seal Air w/Lid (Initial Installation)..... RS30065 KIT	Actros I 3353 w/OM502LA Eng. (09/96-12/03) F-F Lube (5411800009)..... P7192 B-P Lube (21840525)..... C704-L Pre-Fuel (924105)..... PF7939 Fuel (5410920305)..... PF7761 Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363 Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O 261.9 mm Air (A0030949204)..... PA3838 <sup>90</sup>

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Actros I 3353 w/OM502LA Eng. (09/96-12/03) (Cont'd)	Actros I 3357 w/OM502LA Eng. (09/96-12/03)	Actros III 3360 BlueTec 4+5 w/OM502LA Eng. (03/08-on) (Cont'd)
318.3 mm Air (A0030949104)..... PA3844	F-F Lube (5411800009)..... P7192	379.4 mm Cab Air..... PA4956
38.9 mm Height Cab Air (Mann CU3869)..... PA4956	B-P Lube (21840525)..... C704-L	381.8 mm Cab Air (w/o Charcoal) PA4912
40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	Pre-Fuel (924105)..... PF7939	381.8 mm Cab Air (w/Charcoal) (A0008301318)..... PA5492
40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	Fuel (5410920305)..... PF7761	Air Dryer (4295695)..... BA5379 +
Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363	Steering..... P106-HD
Air Dryer (Coalescer) (4295695).. BA5379 +	Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O	Urea (A0001420089)..... PE5272
Crankcase Breather (5410100080)..... CV15001	261.9 mm Air (A0030949204)..... PA3838 <sup>90</sup>	
Trans. (2690321)..... PT9423	318.3 mm Air (A0030949104)..... PA3844	Arocs 3363 w/OM473LA (BlueTec 5/6) Eng. (04/13-on)
Steering (1902137)..... P106-HD	38.9 mm Height Cab Air (Mann CU3869)..... PA4956	Lube (A4731800009)..... P7505
Actros II 3354 w/OM502LA Eng. (04/03-on)	40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	Fuel/Water Separator (A9604770003)..... BF1297-O
F-F Lube..... P7192	40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	263 mm Air (A0040946804)..... CA30104
Pre-Fuel (924105)..... PF7939	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	228 mm Air (A0040946904)..... CA30103
Fuel..... PF7761	Air Dryer (Coalescer) (4295695).. BA5379 +	210 mm Air (A0040947204)..... CA30105
Fuel/Water Separator..... BF1391-O	Crankcase Breather (5410100080)..... CV15001	Cab Air (A9608300018)..... PA30122
Radial Seal Air (Initial Installation) (40942404)..... RS30065 KIT	Trans. (2690321)..... PT9423	Cab Air (w/Carbon) (A9608300118)..... PA30123
Radial Seal Air (Replacement Ele.) (40942404)..... RS30065	Steering (1902137)..... P106-HD	Cab Air (A0008307518)..... PA5585
Radial Seal Air (9/03-on) (40943504)..... RS5358	Actros II 3358 w/OM502LA Eng. (04/03-on)	Cab Air (A9608300218)..... PA30124
Panel Air (A0040941104)..... PA5426	F-F Lube..... P7192	Air Dryer (A0004295695)..... BA5379 +
38.9 mm Height Cab Air..... PA4956	Pre-Fuel (924105)..... PF7939	Steering (A0004660604)..... P106-HD
40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	Fuel..... PF7761	Urea (A0001421089)..... PE17002 KIT
40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	Fuel/Water Separator..... BF1391-O	
Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	Radial Seal Air (Initial Installation) (40942404)..... RS30065 KIT	Arocs 4133 w/OM470LA (BlueTec 5/6) Eng. (04/13-on)
Air Dryer (Coalescer) (4295695).. BA5379 +	Radial Seal Air (Replacement Ele.) (40942404)..... RS30065	Fuel/Water Separator (A9604770003)..... BF1297-O
Crankcase Breather (5410100080)..... CV15001	Radial Seal Air (9/03-on) (40943504)..... RS5358	210 mm Air (A0040947204)..... CA30105
Steering..... P106-HD	Panel Air (A0040941104)..... PA5426	228 mm Air (A0040946904)..... CA30103
Actros III 3355 BlueTec 4+5 w/OM502LA Eng. (03/08-on)	38.9 mm Height Cab Air..... PA4956	263 mm Air (A0040946804)..... CA30104
F-F Lube..... P7192	40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	Cab Air (A9608300018)..... PA30122
Fuel/Water Separator..... BF1391-O	40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	Cab Air (w/Carbon) (A9608300118)..... PA30123
P. Fuel..... PF7761	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	Cab Air (A0008307518)..... PA5585
Pre-Fuel (924105)..... PF7939	Air Dryer (Coalescer) (4295695).. BA5379 +	Cab Air (A9608300218)..... PA30124
338.1 mm Radial Seal Air w/Lid (Initial Installation)..... RS30065 KIT	Crankcase Breather (5410100080)..... CV15001	Air Dryer (A0004295695)..... BA5379 +
322.3 mm Radial Seal Air (Replacement Ele.)..... RS30065	Steering..... P106-HD	Steering (A0004660604)..... P106-HD
532.6 mm Radial Seal Air..... RS5358	Actros III 3360 BlueTec 4+5 w/OM502LA Eng. (03/08-on)	Urea (A0001421089)..... PE17002 KIT
Air (w/Extra Urea Tank)..... PA3765	F-F Lube..... P7192	
379.4 mm Cab Air..... PA4956	Fuel/Water Separator..... BF1391-O	Axor II 4135 w/OM457LA Eng. (06/09-on)
381.8 mm Cab Air (w/o Charcoal) PA4912	P. Fuel..... PF7761	Lube (A0001802109)..... P7230
381.8 mm Cab Air (w/Charcoal) (A0008301318)..... PA5492	Pre-Fuel (924105)..... PF7939	Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363
Air Dryer (4295695)..... BA5379 +	338.1 mm Radial Seal Air w/Lid (Initial Installation)..... RS30065 KIT	Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O
Steering..... P106-HD	322.3 mm Radial Seal Air (Replacement Ele.)..... RS30065	Fuel/Water Separator (Bio Diesel) (A0004771702)..... BF46105-O
Urea (A0001420089)..... PE5272	532.6 mm Radial Seal Air..... RS5358	Fuel Screen (A0000902051)..... PF7939

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.


Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Axor II 4135 w/OM457LA Eng. (06/09-on) (Cont'd) Air (Pre-Cleaner) (A0030949004)..... <b>PA5426</b> Cab Air (9408350047)..... <b>PA4945</b> Air Dryer (A0004295695)..... <b>BA5379 +</b> Steering (A0004660604)..... <b>P106-HD</b>	Axor II 4140 w/OM457LA Eng. (09/04-on) (Cont'd) Cab Air (9408350047)..... <b>PA4945</b> Air Dryer (A0004295695)..... <b>BA5379 +</b> Steering (A0004660604)..... <b>P106-HD</b>	Actros III 4141 BlueTec 4+5 w/OM501LA Eng. (03/08-on) F-F Lube..... <b>P7192</b> Fuel/Water Separator..... <b>BF1391-O</b> P. Fuel..... <b>PF7761</b> Pre-Fuel (924105)..... <b>PF7939</b> 338.1 mm Radial Seal Air w/Lid (Initial Installation)..... <b>RS30065 KIT</b> 322.3 mm Radial Seal Air (Replacement Ele.)..... <b>RS30065</b> 532.6 mm Radial Seal Air..... <b>RS5358</b> Air (w/Extra Urea Tank)..... <b>PA3765</b> 379.4 mm Cab Air..... <b>PA4956</b> 381.8 mm Cab Air (w/o Charcoal)..... <b>PA4912</b> 381.8 mm Cab Air (w/Charcoal) (A0008303418)..... <b>PA5492</b> Air Dryer (4295695)..... <b>BA5379 +</b> Steering..... <b>P106-HD</b> Urea (A0001420089)..... <b>PE5272</b>
Arocs 4136 w/OM470LA (BlueTec 5/6) Eng. (04/13-on) Fuel/Water Separator (A9604770003)..... <b>BF1297-O</b> 210 mm Air (A0040947204)..... <b>CA30105</b> 228 mm Air (A0040946904)..... <b>CA30103</b> 263 mm Air (A0040946804)..... <b>CA30104</b> Cab Air (A9608300018)..... <b>PA30122</b> Cab Air (w/Carbon) (A9608300118)..... <b>PA30123</b> Cab Air (A0008307518)..... <b>PA5585</b> Cab Air (A9608300218)..... <b>PA30124</b> Air Dryer (A0004295695)..... <b>BA5379 +</b> Steering (A0004660604)..... <b>P106-HD</b> Urea (A0001421089)..... <b>PE17002 KIT</b>	Actros I 4140AK w/OM501LA Eng. (09/96-12/03) F-F Lube..... <b>P7192</b> B-P Lube (21840525)..... <b>C704-L</b> Pre-Fuel (924105)..... <b>PF7939</b> Fuel..... <b>PF7761</b> Fuel/Water Separator (w/Drain) (A0004771302)..... <b>BF1363</b> Fuel/Water Separator (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b> Radial Seal Air (A0040940204)..... <b>RS5343</b> 261.9 mm Air..... <b>PA3838 90</b> 318.3 mm Air..... <b>PA3844</b> Panel Air (A0040941104)..... <b>PA5426</b> 38.9 mm Height Cab Air..... <b>PA4956</b> 40.5 mm Height Cab Air (w/o Charcoal)..... <b>PA4912</b> 40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... <b>PA5492</b> Air Dryer (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer (Coalescer) (4295695)..... <b>BA5379 +</b> Crankcase Breather (5410100080)..... <b>CV15001</b> Trans. (2690321)..... <b>PT9423</b> Steering..... <b>P106-HD</b>	Actros II 4141AK w/OM501LA Eng. (04/03-on) F-F Lube..... <b>P7192</b> Pre-Fuel (924105)..... <b>PF7939</b> Fuel..... <b>PF7761</b> Fuel/Water Separator..... <b>BF1391-O</b> Radial Seal Air (Initial Installation) (40942404)..... <b>RS30065 KIT</b> Radial Seal Air (Replacement Ele.) (40942404)..... <b>RS30065</b> Radial Seal Air (9/03-on) (40943504)..... <b>RS5358</b> Panel Air (A0040941104)..... <b>PA5426</b> 38.9 mm Height Cab Air..... <b>PA4956</b> 40.5 mm Height Cab Air (w/o Charcoal)..... <b>PA4912</b> 40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... <b>PA5492</b> Air Dryer (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer (Coalescer) (4295695)..... <b>BA5379 +</b> Crankcase Breather (5410100080)..... <b>CV15001</b> Steering..... <b>P106-HD</b>
Arocs 4140 w/OM470LA (BlueTec 5/6) Eng. (04/13-on) Fuel/Water Separator (A9604770003)..... <b>BF1297-O</b> 210 mm Air (A0040947204)..... <b>CA30105</b> 228 mm Air (A0040946904)..... <b>CA30103</b> 263 mm Air (A0040946804)..... <b>CA30104</b> Cab Air (A9608300018)..... <b>PA30122</b> Cab Air (w/Carbon) (A9608300118)..... <b>PA30123</b> Cab Air (A0008307518)..... <b>PA5585</b> Cab Air (A9608300218)..... <b>PA30124</b> Air Dryer (A0004295695)..... <b>BA5379 +</b> Steering (A0004660604)..... <b>P106-HD</b> Urea (A0001421089)..... <b>PE17002 KIT</b>	Actros I 4140K w/OM501LA Eng. (09/96-12/03) F-F Lube..... <b>P7192</b> B-P Lube (21840525)..... <b>C704-L</b> Pre-Fuel (924105)..... <b>PF7939</b> Fuel..... <b>PF7761</b> Fuel/Water Separator (w/Drain) (A0004771302)..... <b>BF1363</b> Fuel/Water Separator (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b> Radial Seal Air (A0040940204)..... <b>RS5343</b> 261.9 mm Air..... <b>PA3838 90</b> 318.3 mm Air..... <b>PA3844</b> Panel Air (A0040941104)..... <b>PA5426</b> 38.9 mm Height Cab Air..... <b>PA4956</b> 40.5 mm Height Cab Air (w/o Charcoal)..... <b>PA4912</b> 40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... <b>PA5492</b> Air Dryer (Desiccant) (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer (Coalescer) (4295695)..... <b>BA5379 +</b> Crankcase Breather (5410100080)..... <b>CV15001</b> Trans. (2690321)..... <b>PT9423</b> Steering..... <b>P106-HD</b>	Actros II 4141K w/OM501LA Eng. (04/03-on) F-F Lube..... <b>P7192</b> Pre-Fuel (924105)..... <b>PF7939</b> Fuel..... <b>PF7761</b> Fuel/Water Separator..... <b>BF1391-O</b> Radial Seal Air (Initial Installation) (40942404)..... <b>RS30065 KIT</b> Radial Seal Air (Replacement Ele.) (40942404)..... <b>RS30065</b> Radial Seal Air (9/03-on) (40943504)..... <b>RS5358</b> Panel Air (A0040941104)..... <b>PA5426</b> 38.9 mm Height Cab Air..... <b>PA4956</b> 40.5 mm Height Cab Air (w/o Charcoal)..... <b>PA4912</b> 40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... <b>PA5492</b>
Axor II 4140 w/OM457LA Eng. (09/04-on) Lube (A0001802109)..... <b>P7230</b> Fuel/Water Separator (w/Drain) (A0004771302)..... <b>BF1363</b> Fuel/Water Separator (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b> Fuel/Water Separator (Bio Diesel) (A0004771702)..... <b>BF46105-O</b> Fuel Screen (A0000902051)..... <b>PF7939</b> 532.6 mm Radial Seal O. Air (4760940004)..... <b>RS5358</b> Radial Seal I. Air (A0040947304)..... <b>RS5549</b> 338.1 mm Radial Seal Air w/Lid (Initial Installation) (A0040942404)..... <b>RS30065 KIT</b> 322.3 mm Radial Seal Air (Replacement Ele.) (A0040942404)..... <b>RS30065</b> Air (Pre-Cleaner) (A0030949004)..... <b>PA5426</b>		

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Actros II 4141K w/OM501LA Eng. (04/03-on) (Cont'd)	Axor II 4143 w/OM457LA Eng. (09/04-on) (Cont'd)	Actros I 4143K w/OM501LA Eng. (09/96-12/03) (Cont'd)
Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	322.3 mm Radial Seal Air (Replacement Ele.) (A0040942404)..... RS30065	Crankcase Breather (5410100080)..... CV15001
Air Dryer (Coalescer) (4295695).. BA5379 +	Air (Pre-Cleaner) (A0030949004). PA5426	Trans. (2690321)..... PT9423
Crankcase Breather (5410100080)..... CV15001	Cab Air (9408350047)..... PA4945	Steering (1902137)..... P106-HD
Steering..... P106-HD	Air Dryer (A0004295695)..... BA5379 +	Actros III 4144 BlueTec 4+5 w/OM501LA Eng. (03/08-on)
Arocs 4142 w/OM471LA (BlueTec 5/6) Eng. (04/13-on)	Steering (A0004660604)..... P106-HD	F-F Lube..... P7192
Lube (A4731800009)..... P7505	Actros I 4143AK w/OM501LA Eng. (09/96-12/03)	Fuel/Water Separator..... BF1391-O
Fuel/Water Separator (A9604770003)..... BF1297-O	F-F Lube (5411800009)..... P7192	P. Fuel..... PF7761
Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT	B-P Lube (21840525)..... C704-L	Pre-Fuel (924105)..... PF7939
263 mm Air (A0040946804)..... CA30104	Pre-Fuel (924105)..... PF7939	338.1 mm Radial Seal Air w/Lid (Initial Installation)..... RS30065 KIT
228 mm Air (A0040946904)..... CA30103	Fuel (Mann PU999/1x)..... PF7761	322.3 mm Radial Seal Air (Replacement Ele.)..... RS30065
210 mm Air (A0040947204)..... CA30105	Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363	532.6 mm Radial Seal Air..... RS5358
Cab Air (A9608300018)..... PA30122	Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O	Air (w/Extra Urea Tank)..... PA3765
Cab Air (w/Carbon) (A9608300118)..... PA30123	Radial Seal Air (A0040940204).... RS5343	379.4 mm Cab Air..... PA4956
Cab Air (A9608300218)..... PA30124	261.9 mm Air (Mann C421404).... PA3838 <sup>90</sup>	381.8 mm Cab Air (w/o Charcoal) (A0008303418)..... PA5492
Cab Air (A0008307518)..... PA5585 <sup>90</sup>	318.3 mm Air (Mann C421729).... PA3844	Air Dryer (4295695)..... BA5379 +
Air Dryer (A0004295695)..... BA5379 +	Panel Air (A0040941104)..... PA5426	Steering..... P106-HD
Coolant (A4722030255)..... P5092	38.9 mm Height Cab Air (Mann CU3869)..... PA4956	Urea (A0001420089)..... PE5272
Steering (A0004660604)..... P106-HD	40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	Axor II 4144 w/OM457LA (BlueTec 4/5) Eng. (01/11-on)
Urea (A0001421089)..... PE17002 KIT	40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	Lube (A0001802109)..... P7230
Arocs 4143 w/OM470LA (BlueTec 5/6) Eng. (04/13-on)	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363
Fuel/Water Separator (A9604770003)..... BF1297-O	Air Dryer (Coalescer) (4295695).. BA5379 +	Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O
210 mm Air (A0040947204)..... CA30105	Crankcase Breather (5410100080)..... CV15001	Fuel/Water Separator (Bio Diesel) (A0004771702)..... BF46105-O
228 mm Air (A0040946904)..... CA30103	Trans. (2690321)..... PT9423	Fuel Screen (A0000902051)..... PF7939
263 mm Air (A0040946804)..... CA30104	Steering (1902137)..... P106-HD	532.6 mm Radial Seal O. Air (4760940004)..... RS5358
Cab Air (A9608300018)..... PA30122	Actros I 4143K w/OM501LA Eng. (09/96-12/03)	Radial Seal I. Air (A0040947304)..... RS5549
Cab Air (w/Carbon) (A9608300118)..... PA30123	F-F Lube (5411800009)..... P7192	338.1 mm Radial Seal Air w/Lid (Initial Installation) (A0040942404)..... RS30065 KIT
Cab Air (A0008307518)..... PA5585	B-P Lube (21840525)..... C704-L	322.3 mm Radial Seal Air (Replacement Ele.) (A0040942404)..... RS30065
Cab Air (A9608300218)..... PA30124	Pre-Fuel (924105)..... PF7939	Air (Pre-Cleaner) (A0030949004). PA5426
Air Dryer (A0004295695)..... BA5379 +	Fuel (Mann PU999/1x)..... PF7761	Cab Air (9408350047)..... PA4945
Steering (A0004660604)..... P106-HD	Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363	Air Dryer (A0004295695)..... BA5379 +
Urea (A0001421089)..... PE17002 KIT	Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O	Steering (A0004660604)..... P106-HD
Axor II 4143 w/OM457LA Eng. (09/04-on)	Radial Seal Air (A0040940204).... RS5343	Urea (A0001420089)..... PE5272
Lube (A0001802109)..... P7230	261.9 mm Air (Mann C421404).... PA3838 <sup>90</sup>	Actros II 4144AK w/OM501LA Eng. (04/03-on)
Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363	318.3 mm Air (Mann C421729).... PA3844	F-F Lube..... P7192
Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O	Panel Air (A0040941104)..... PA5426	Pre-Fuel (924105)..... PF7939
Fuel/Water Separator (Bio Diesel) (A0004771702)..... BF46105-O	38.9 mm Height Cab Air (Mann CU3869)..... PA4956	Fuel..... PF7761
Fuel Screen (A0000902051)..... PF7939	40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	Fuel/Water Separator..... BF1391-O
532.6 mm Radial Seal O. Air (4760940004)..... RS5358	40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	Radial Seal Air (Initial Installation) (40942404)..... RS30065 KIT
Radial Seal I. Air (A0040947304)..... RS5549	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	
338.1 mm Radial Seal Air w/Lid (Initial Installation) (A0040942404)..... RS30065 KIT	Air Dryer (Coalescer) (4295695).. BA5379 +	

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.


Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Actros II 4144AK w/OM501LA Eng. (04/03-on) (Cont'd)	Arocs 4145 w/OM471LA (BlueTec 5/6) Eng. (04/13-on) (Cont'd)	Actros II 4146AK w/OM501LA Eng. (04/03-on) (Cont'd)
Radial Seal Air (Replacement Ele.) (40942404)..... RS30065	Urea (A0001421089)..... PE17002 KIT	Radial Seal Air (9/03-on) (40943504)..... RS5358
Radial Seal Air (9/03-on) (40943504)..... RS5358	Actros III 4146 BlueTec 4+5 w/OM501LA Eng. (03/08-on)	Panel Air (A0040941104)..... PA5426
Panel Air (A0040941104)..... PA5426	F-F Lube..... P7192	38.9 mm Height Cab Air..... PA4956
38.9 mm Height Cab Air..... PA4956	Fuel/Water Separator..... BF1391-O	40.5 mm Height Cab Air (w/o Charcoal)..... PA4912
40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	P. Fuel..... PF7761	40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492
40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	Pre-Fuel (924105)..... PF7939	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +
Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	338.1 mm Radial Seal Air w/Lid (Initial Installation)..... RS30065 KIT	Air Dryer (Coalescer) (4295695).. BA5379 +
Air Dryer (Coalescer) (4295695).. BA5379 +	322.3 mm Radial Seal Air (Replacement Ele.)..... RS30065	Crankcase Breather (5410100080)..... CV15001
Crankcase Breather (5410100080)..... CV15001	532.6 mm Radial Seal Air..... RS5358	Steering..... P106-HD
Steering..... P106-HD	Air (w/Extra Urea Tank)..... PA3765	Actros I 4146K w/OM501LA Eng. (09/96-12/03)
Actros II 4144K w/OM501LA Eng. (04/03-on)	379.4 mm Cab Air..... PA4956	F-F Lube..... P7192
F-F Lube..... P7192	381.8 mm Cab Air (w/o Charcoal)..... PA4912	B-P Lube (21840525)..... C704-L
Pre-Fuel (924105)..... PF7939	381.8 mm Cab Air (w/Charcoal) (A0008303418)..... PA5492	Pre-Fuel (924105)..... PF7939
Fuel..... PF7761	Air Dryer (4295695)..... BA5379 +	Fuel..... PF7761
Fuel/Water Separator..... BF1391-O	Steering..... P106-HD	Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363
Radial Seal Air (Initial Installation) (40942404)..... RS30065 KIT	Urea (A0001420089)..... PE5272	Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O
Radial Seal Air (Replacement Ele.) (40942404)..... RS30065	Actros I 4146AK w/OM501LA Eng. (09/96-12/03)	Radial Seal Air (A0040940204)..... RS5343
Radial Seal Air (9/03-on) (40943504)..... RS5358	F-F Lube..... P7192	261.9 mm Air..... PA3838 90
Panel Air (A0040941104)..... PA5426	B-P Lube (21840525)..... C704-L	318.3 mm Air..... PA3844
38.9 mm Height Cab Air..... PA4956	Pre-Fuel (924105)..... PF7939	Panel Air (A0040941104)..... PA5426
40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	Fuel..... PF7761	38.9 mm Height Cab Air..... PA4956
40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363	40.5 mm Height Cab Air (w/o Charcoal)..... PA4912
Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O	40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492
Air Dryer (Coalescer) (4295695).. BA5379 +	Radial Seal Air (A0040940204)..... RS5343	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +
Crankcase Breather (5410100080)..... CV15001	261.9 mm Air..... PA3838 90	Air Dryer (Coalescer) (4295695).. BA5379 +
Steering..... P106-HD	318.3 mm Air..... PA3844	Crankcase Breather (5410100080)..... CV15001
Arocs 4145 w/OM471LA (BlueTec 5/6) Eng. (04/13-on)	Panel Air (A0040941104)..... PA5426	Trans. (2690321)..... PT9423
Lube (A4731800009)..... P7505	38.9 mm Height Cab Air..... PA4956	Steering..... P106-HD
Fuel/Water Separator (A9604770003)..... BF1297-O	40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	Actros II 4146K w/OM501LA Eng. (04/03-on)
Fuel (Mahle Assembly) (A4710909052)..... PF9908 KIT	40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	F-F Lube..... P7192
263 mm Air (A0040946804)..... CA30104	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	Pre-Fuel (924105)..... PF7939
228 mm Air (A0040946904)..... CA30103	Air Dryer (Coalescer) (4295695).. BA5379 +	Fuel..... PF7761
210 mm Air (A0040947204)..... CA30105	Crankcase Breather (5410100080)..... CV15001	Fuel/Water Separator..... BF1391-O
Cab Air (A9608300018)..... PA30122	Trans. (2690321)..... PT9423	Radial Seal Air (Initial Installation) (40942404)..... RS30065 KIT
Cab Air (w/Carbon) (A9608300118)..... PA30123	Steering..... P106-HD	Radial Seal Air (Replacement Ele.) (40942404)..... RS30065
Cab Air (A9608300218)..... PA30124	Actros II 4146AK w/OM501LA Eng. (04/03-on)	Radial Seal Air (9/03-on) (40943504)..... RS5358
Cab Air (A0008307518)..... PA5585 90	F-F Lube..... P7192	38.9 mm Height Cab Air..... PA4956
Air Dryer (A0004295695)..... BA5379 +	Pre-Fuel (924105)..... PF7939	40.5 mm Height Cab Air (w/o Charcoal)..... PA4912
Coolant (A4722030255)..... P5092	Fuel..... PF7761	40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492
Steering (A0004660604)..... P106-HD	Fuel/Water Separator..... BF1391-O	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +
	Radial Seal Air (Initial Installation) (40942404)..... RS30065 KIT	
	Radial Seal Air (Replacement Ele.) (40942404)..... RS30065	

+ See Product Guide for Variations of This Number. 90 Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Actros II 4146K w/OM501LA Eng. (04/03-on) (Cont'd)	Actros I 4148AK w/OM502LA Eng. (09/96-12/03) (Cont'd)	Actros II 4150AK w/OM502LA Eng. (04/03-on) (Cont'd)
Air Dryer (Coalescer) (4295695).. BA5379 +	38.9 mm Height Cab Air..... PA4956	Crankcase Breather
Crankcase Breather	40.5 mm Height Cab Air (w/o	(5410100080)..... CV15001
(5410100080)..... CV15001	Charcoal)..... PA4912	Steering..... P106-HD
Steering..... P106-HD	40.5 mm Height Cab Air	Actros II 4150K w/OM502LA Eng. (04/03-on)
Arocs 4148 w/OM471LA (BlueTec 5/6) Eng. (04/13-on)	(w/Charcoal) (A0008303418)..... PA5492	F-F Lube..... P7192
Lube (A4731800009)..... P7505	Air Dryer (Desiccant) (Mann	Fuel..... PF7761
Fuel/Water Separator	TB1374X)..... BA5374 +	Fuel/Water Separator
(A9604770003)..... BF1297-O	Air Dryer (Coalescer) (4295695).. BA5379 +	(Fleetguard FS19737)..... BF46105-O
Fuel (Mahle Assembly)	Crankcase Breather	Radial Seal Air (Initial Installation)
(A4710909052)..... PF9908 KIT	(5410100080)..... CV15001	(40942404)..... RS30065 KIT
263 mm Air (A0040946804)..... CA30104	Trans. (2690321)..... PT9423	Radial Seal Air (Replacement
228 mm Air (A0040946904)..... CA30103	Steering..... P106-HD	Ele.) (40942404)..... RS30065
210 mm Air (A0040947204)..... CA30105	Actros I 4148K w/OM502LA Eng. (09/96-12/03)	Radial Seal Air (9/03-on)
Cab Air (A9608300018)..... PA30122	F-F Lube..... P7192	(40943504)..... RS5358
Cab Air (w/Carbon)	B-P Lube (21840525)..... C704-L	Panel Air (A0040941104)..... PA5426
(A9608300118)..... PA30123	Pre-Fuel (924105)..... PF7939	38.9 mm Height Cab Air..... PA4956
Cab Air (A9608300218)..... PA30124	Fuel..... PF7761	40.5 mm Height Cab Air (w/o
Cab Air (A0008307518)..... PA5585 90	Fuel/Water Separator (w/Drain)	Charcoal)..... PA4912
Air Dryer (A0004295695)..... BA5379 +	(A0004771302)..... BF1363	40.5 mm Height Cab Air
Coolant (A4722030255)..... P5092	Fuel/Water Separator (Open End	(w/Charcoal) (A0008303418)..... PA5492
Steering (A0004660604)..... P106-HD	for Bowl) (A0004771302)..... BF1391-O	Air Dryer (Mann TB1374X)..... BA5374 +
Urea (A0001421089)..... PE17002 KIT	Radial Seal Air (A0040940204).... RS5343	Crankcase Breather
Actros III 4148 BlueTec 4+5 w/OM501LA Eng. (03/08-on)	261.9 mm Air..... PA3838 90	(5410100080)..... CV15001
F-F Lube..... P7192	318.3 mm Air..... PA3844	Steering..... P106-HD
Fuel/Water Separator..... BF1391-O	Panel Air (A0040941104)..... PA5426	Arocs 4151 w/OM471LA (BlueTec 5/6) Eng. (04/13-on)
P. Fuel..... PF7761	38.9 mm Height Cab Air..... PA4956	Lube (A4731800009)..... P7505
Pre-Fuel (924105)..... PF7939	40.5 mm Height Cab Air (w/o	Fuel/Water Separator
338.1 mm Radial Seal Air w/Lid	Charcoal)..... PA4912	(A9604770003)..... BF1297-O
(Initial Installation)..... RS30065 KIT	40.5 mm Height Cab Air	Fuel (Mahle Assembly)
322.3 mm Radial Seal Air	(w/Charcoal) (A0008303418)..... PA5492	(A4710909052)..... PF9908 KIT
(Replacement Ele.)..... RS30065	Air Dryer (Desiccant) (Mann	263 mm Air (A0040946804)..... CA30104
532.6 mm Radial Seal Air..... RS5358	TB1374X)..... BA5374 +	228 mm Air (A0040946904)..... CA30103
Air (w/Extra Urea Tank)..... PA3765	Air Dryer (Coalescer) (4295695).. BA5379 +	210 mm Air (A0040947204)..... CA30105
379.4 mm Cab Air..... PA4956	Crankcase Breather	Cab Air (A9608300018)..... PA30122
381.8 mm Cab Air (w/o Charcoal) PA4912	(5410100080)..... CV15001	Cab Air (w/Carbon)
381.8 mm Cab Air (w/Charcoal)	Trans. (2690321)..... PT9423	(A9608300118)..... PA30123
(A0008303418)..... PA5492	Steering..... P106-HD	Cab Air (A9608300218)..... PA30124
Air Dryer (4295695)..... BA5379 +	Actros II 4150AK w/OM502LA Eng. (04/03-on)	Cab Air (A0008307518)..... PA5585 90
Steering..... P106-HD	F-F Lube..... P7192	Air Dryer (A0004295695)..... BA5379 +
Urea (A0001420089)..... PE5272	Fuel..... PF7761	Coolant (A4722030255)..... P5092
Actros I 4148AK w/OM502LA Eng. (09/96-12/03)	Fuel/Water Separator..... BF1391-O	Steering (A0004660604)..... P106-HD
F-F Lube..... P7192	Pre-Fuel (924105)..... PF7939	Urea (A0001421089)..... PE17002 KIT
B-P Lube (21840525)..... C704-L	Radial Seal Air (Initial Installation)	Actros II 4151 (BlueTec 5) w/OM502LA Eng. (07/06-on)
Pre-Fuel (924105)..... PF7939	(40942404)..... RS30065 KIT	F-F Lube..... P7192
Fuel..... PF7761	Radial Seal Air (Replacement	Pre-Fuel (924105)..... PF7939
Fuel/Water Separator (w/Drain)	Ele.) (40942404)..... RS30065	Fuel..... PF7761
(A0004771302)..... BF1363	Radial Seal Air (9/03-on)	Fuel/Water Separator..... BF1391-O
Fuel/Water Separator (Open End	(40943504)..... RS5358	338.1 mm Radial Seal Air w/Lid
for Bowl) (A0004771302)..... BF1391-O	Panel Air (A0040941104)..... PA5426	(Initial Installation) (40942404).... RS30065 KIT
Radial Seal Air (A0040940204).... RS5343	38.9 mm Height Cab Air..... PA4956	322.3 mm Radial Seal Air
261.9 mm Air..... PA3838 90	40.5 mm Height Cab Air (w/o	(Replacement Ele.) (40942404).... RS30065
318.3 mm Air..... PA3844	Charcoal)..... PA4912	532.6 mm Radial Seal Air
Panel Air (A0040941104)..... PA5426	40.5 mm Height Cab Air	(40943504)..... RS5358
	(w/Charcoal) (A0008303418)..... PA5492	Air (w/Extra Urea Tank)..... PA3765
	Air Dryer (Desiccant) (Mann	
	TB1374X)..... BA5374 +	
	Air Dryer (Coalescer) (4295695).. BA5379 +	

+ See Product Guide for Variations of This Number. 90 Obsolete Pending.

Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Actros II 4151 (BlueTec 5) w/OM502LA Eng. (07/06-on) (Cont'd)	Arocs 4152 w/OM473LA (BlueTec 5/6) Eng. (04/13-on) (Cont'd)	Actros II 4154K w/OM502LA Eng. (10/03-on) (Cont'd)
38.9 mm Height Cab Air..... PA4956	Air Dryer (A0004295695)..... BA5379 +	Radial Seal Air (9/03-on) (40943504)..... RS5358
40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	Coolant (A4722030255)..... P5092	Panel Air (A0040941104)..... PA5426
40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	Steering (A0004660604)..... P106-HD	38.9 mm Height Cab Air..... PA4956
Air Dryer (4295695)..... BA5379 +	Urea (A0001421089)..... PE17002 KIT	40.5 mm Height Cab Air (w/o Charcoal)..... PA4912
Steering..... P106-HD		40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492
Urea (A0001420089)..... PE5272		Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +
Actros III 4151 BlueTec 4+5 w/OM502LA Eng. (03/08-on)	Actros II 4154 (BlueTec 5) w/OM502LA Eng. (07/06-on)	Air Dryer (Coalescer) (4295695).. BA5379 +
F-F Lube..... P7192	F-F Lube..... P7192	Crankcase Breather (5410100080)..... CV15001
Fuel/Water Separator..... BF1391-O	Pre-Fuel (924105)..... PF7939	Steering..... P106-HD
P. Fuel..... PF7761	Fuel..... PF7761	
Pre-Fuel (924105)..... PF7939	Fuel/Water Separator..... BF1391-O	Actros II MP4 4158 w/OM473LA (BlueTec 5/6) Eng. (01/14-on)
338.1 mm Radial Seal Air w/Lid (Initial Installation) (40942404)... RS30065 KIT	338.1 mm Radial Seal Air w/Lid (Replacement Ele.) (40942404)... RS30065	Lube (A4731800009)..... P7505
322.3 mm Radial Seal Air (Replacement Ele.)..... RS30065	532.6 mm Radial Seal Air (40943504)..... RS5358	Fuel/Water Separator (A9604770003)..... BF1297-O
532.6 mm Radial Seal Air (w/Extra Urea Tank)..... PA3765	Air (w/Extra Urea Tank)..... PA3765	263 mm Air (A0040946804)..... CA30104
379.4 mm Cab Air..... PA4956	38.9 mm Height Cab Air..... PA4956	228 mm Air (A0040946904)..... CA30103
381.8 mm Cab Air (w/o Charcoal) PA4912	40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	210 mm Air (A0040947204)..... CA30105
381.8 mm Cab Air (w/Charcoal) (A0008303418)..... PA5492	40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	Cab Air (A9608300018)..... PA30122
Air Dryer (4295695)..... BA5379 +	Air Dryer (4295695)..... BA5379 +	Cab Air (w/Carbon) (A9608300118)..... PA30123
Steering..... P106-HD	Steering..... P106-HD	Cab Air (A0008307518)..... PA5585
Urea (A0001420089)..... PE5272	Urea (A0001420089)..... PE5272	Cab Air (A9608300218)..... PA30124
Actros II MP4 4152 w/OM473LA (BlueTec 5/6) Eng. (01/14-on)	Actros II 4154AK w/OM502LA Eng. (10/03-on)	Air Dryer (A0004295695)..... BA5379 +
Lube (A4731800009)..... P7505	F-F Lube..... P7192	Steering (A0004660604)..... P106-HD
Fuel/Water Separator (A9604770003)..... BF1297-O	Pre-Fuel (924105)..... PF7939	Urea (A0001421089)..... PE17002 KIT
263 mm Air (A0040946804)..... CA30104	Fuel..... PF7761	
228 mm Air (A0040946904)..... CA30103	Fuel/Water Separator..... BF1391-O	Arocs 4158 w/OM473LA (BlueTec 5/6) Eng. (04/13-on)
210 mm Air (A0040947204)..... CA30105	Radial Seal Air (Initial Installation) (40942404)..... RS30065 KIT	Lube (A4721800309)..... P7505
Cab Air (A9608300018)..... PA30122	Radial Seal Air (Replacement Ele.) (40942404)..... RS30065	Fuel/Water Separator (A9604770003)..... BF1297-O
Cab Air (w/Carbon) (A9608300118)..... PA30123	Radial Seal Air (9/03-on) (40943504)..... RS5358	210 mm Air (A0040947204)..... CA30105
Cab Air (A0008307518)..... PA5585	Panel Air (A0040941104)..... PA5426	228 mm Air (A0040946904)..... CA30103
Cab Air (A9608300218)..... PA30124	38.9 mm Height Cab Air..... PA4956	263 mm Air (A0040946804)..... CA30104
Air Dryer (A0004295695)..... BA5379 +	40.5 mm Height Cab Air (w/o Charcoal)..... PA4912	Cab Air (A9608300018)..... PA30122
Steering (A0004660604)..... P106-HD	40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	Cab Air (w/Carbon) (A9608300118)..... PA30123
Urea (A0001421089)..... PE17002 KIT	Air Dryer (Desiccant) (Mann TB1374X)..... BA5374 +	Cab Air (A0008307518)..... PA5585
Actros II MP4 4152 w/OM473LA (BlueTec 5/6) Eng. (01/14-on)	Air Dryer (Coalescer) (4295695).. BA5379 +	Cab Air (A9608300218)..... PA30124
Lube (A4731800009)..... P7505	Crankcase Breather (5410100080)..... CV15001	Air Dryer (A0004295695)..... BA5379 +
Fuel/Water Separator (A9604770003)..... BF1297-O	Steering..... P106-HD	Coolant (A4722030255)..... P5092
210 mm Air (A0040947204)..... CA30105		Steering (A0004660604)..... P106-HD
228 mm Air (A0040946904)..... CA30103	Actros II 4154K w/OM502LA Eng. (10/03-on)	Urea (A0001421089)..... PE17002 KIT
263 mm Air (A0040946804)..... CA30104	F-F Lube..... P7192	
Cab Air (A9608300018)..... PA30122	Pre-Fuel (924105)..... PF7939	Actros II 4160 (BlueTec 5) w/OM502LA Eng. (07/06-on)
Cab Air (w/Carbon) (A9608300118)..... PA30123	Fuel..... PF7761	F-F Lube..... P7192
Cab Air (A0008307518)..... PA5585	Fuel/Water Separator..... BF1391-O	Pre-Fuel (924105)..... PF7939
Cab Air (A9608300218)..... PA30124	Radial Seal Air (Initial Installation) (40942404)..... RS30065 KIT	Fuel..... PF7761
	Radial Seal Air (Replacement Ele.) (40942404)..... RS30065	Fuel/Water Separator..... BF1391-O

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ European Trucks, Vans (cont'd)
Actros II 4160 (BlueTec 5) w/OM502LA Eng. (07/06-on) (Cont'd)	Arocs 4165 w/OM473LA (BlueTec 5/6) Eng. (04/13-on) (Cont'd)	Arocs 4451 w/OM471LA (BlueTec 5/6) Eng. (04/13-on) (Cont'd)
322.3 mm Radial Seal Air (Replacement Ele.) (40942404)... <b>RS30065</b>	<b>Cab Air</b> (w/Carbon) (A9608300118)..... <b>PA30123</b>	<b>Cab Air</b> (w/Carbon) (A9608300118)..... <b>PA30123</b>
532.6 mm Radial Seal Air (40943504)..... <b>RS5358</b>	<b>Cab Air</b> (A0008307518)..... <b>PA5585</b>	<b>Cab Air</b> (A9608300218)..... <b>PA30124</b>
<b>Air</b> (w/Extra Urea Tank)..... <b>PA3765</b>	<b>Cab Air</b> (A9608300218)..... <b>PA30124</b>	<b>Cab Air</b> (A0008307518)..... <b>PA5585<sup>90</sup></b>
<b>38.9 mm Height Cab Air</b> ..... <b>PA4956</b>	<b>Air Dryer</b> (A0004295695)..... <b>BA5379 +</b>	<b>Air Dryer</b> (A0004295695)..... <b>BA5379 +</b>
<b>40.5 mm Height Cab Air</b> (w/o Charcoal)..... <b>PA4912</b>	<b>Steering</b> (A0004660604)..... <b>P106-HD</b>	<b>Coolant</b> (A4722030255)..... <b>P5092</b>
<b>40.5 mm Height Cab Air</b> (w/Charcoal) (A0008303418)..... <b>PA5492</b>	<b>Urea</b> (A0001421089)..... <b>PE17002 KIT</b>	<b>Steering</b> (A0004660604)..... <b>P106-HD</b>
<b>Air Dryer</b> (4295695)..... <b>BA5379 +</b>	Actros III 4165 BlueTec 4+5 w/OM502LA Eng. (03/08-on)	<b>Urea</b> (A0001421089)..... <b>PE17002 KIT</b>
<b>Steering</b> ..... <b>P106-HD</b>	<b>F-F Lube</b> ..... <b>P7192</b>	Arocs 4452 w/OM473LA (BlueTec 5/6) Eng. (04/13-on)
<b>Urea</b> (A0001420089)..... <b>PE5272</b>	<b>Fuel/Water Separator</b> ..... <b>BF1391-O</b>	<b>Lube</b> (A4731800009)..... <b>P7505</b>
Actros II MP4 4163 w/OM473LA (BlueTec 5/6) Eng. (01/14-on)	<b>P. Fuel</b> ..... <b>PF7761</b>	<b>Fuel/Water Separator</b> (A9604770003)..... <b>BF1297-O</b>
<b>Lube</b> (A4731800009)..... <b>P7505</b>	<b>Pre-Fuel</b> (924105)..... <b>PF7939</b>	<b>263 mm Air</b> (A0040946804)..... <b>CA30104</b>
<b>Fuel/Water Separator</b> (A9604770003)..... <b>BF1297-O</b>	<b>338.1 mm Radial Seal Air w/Lid</b> (Initial Installation)..... <b>RS30065 KIT</b>	<b>228 mm Air</b> (A0040946904)..... <b>CA30103</b>
<b>263 mm Air</b> (A0040946804)..... <b>CA30104</b>	<b>322.3 mm Radial Seal Air</b> (Replacement Ele.)..... <b>RS30065</b>	<b>210 mm Air</b> (A0040947204)..... <b>CA30105</b>
<b>228 mm Air</b> (A0040946904)..... <b>CA30103</b>	<b>532.6 mm Radial Seal Air</b> ..... <b>RS5358</b>	<b>Cab Air</b> (A9608300018)..... <b>PA30122</b>
<b>210 mm Air</b> (A0040947204)..... <b>CA30105</b>	<b>Air</b> (w/Extra Urea Tank)..... <b>PA3765</b>	<b>Cab Air</b> (w/Carbon) (A9608300118)..... <b>PA30123</b>
<b>Cab Air</b> (A9608300018)..... <b>PA30122</b>	<b>379.4 mm Cab Air</b> ..... <b>PA4956</b>	<b>Cab Air</b> (A0008307518)..... <b>PA5585</b>
<b>Cab Air</b> (w/Carbon) (A9608300118)..... <b>PA30123</b>	<b>381.8 mm Cab Air</b> (w/o Charcoal)..... <b>PA4912</b>	<b>Cab Air</b> (A9608300218)..... <b>PA30124</b>
<b>Cab Air</b> (A0008307518)..... <b>PA5585</b>	<b>381.8 mm Cab Air</b> (w/Charcoal) (A0008303418)..... <b>PA5492</b>	<b>Air Dryer</b> (A0004295695)..... <b>BA5379 +</b>
<b>Cab Air</b> (A9608300218)..... <b>PA30124</b>	<b>Air Dryer</b> (4295695)..... <b>BA5379 +</b>	<b>Steering</b> (A0004660604)..... <b>P106-HD</b>
<b>Air Dryer</b> (A0004295695)..... <b>BA5379 +</b>	<b>Steering</b> ..... <b>P106-HD</b>	<b>Urea</b> (A0001421089)..... <b>PE17002 KIT</b>
<b>Steering</b> (A0004660604)..... <b>P106-HD</b>	<b>Urea</b> (A0001420089)..... <b>PE5272</b>	Arocs 4458 w/OM473LA (BlueTec 5/6) Eng. (10/13-on)
<b>Urea</b> (A0001421089)..... <b>PE17002 KIT</b>	Arocs 4448 w/OM471LA (BlueTec 5/6) Eng. (04/13-on)	<b>Lube</b> (A4731800009)..... <b>P7505</b>
Arocs 4163 w/OM473LA (BlueTec 5/6) Eng. (04/13-on)	<b>Lube</b> (A4731800009)..... <b>P7505</b>	<b>Fuel/Water Separator</b> (A9604770003)..... <b>BF1297-O</b>
<b>Lube</b> (A4721800309)..... <b>P7505</b>	<b>Fuel/Water Separator</b> (A9604770003)..... <b>BF1297-O</b>	<b>263 mm Air</b> (A0040946804)..... <b>CA30104</b>
<b>Fuel/Water Separator</b> (A9604770003)..... <b>BF1297-O</b>	<b>Fuel</b> (Mahle Assembly) (A4710909052)..... <b>PF9908 KIT</b>	<b>228 mm Air</b> (A0040946904)..... <b>CA30103</b>
<b>210 mm Air</b> (A0040947204)..... <b>CA30105</b>	<b>263 mm Air</b> (A0040946804)..... <b>CA30104</b>	<b>210 mm Air</b> (A0040947204)..... <b>CA30105</b>
<b>228 mm Air</b> (A0040946904)..... <b>CA30103</b>	<b>228 mm Air</b> (A0040946904)..... <b>CA30103</b>	<b>Cab Air</b> (A9608300018)..... <b>PA30122</b>
<b>263 mm Air</b> (A0040946804)..... <b>CA30104</b>	<b>210 mm Air</b> (A0040947204)..... <b>CA30105</b>	<b>Cab Air</b> (w/Carbon) (A9608300118)..... <b>PA30123</b>
<b>Cab Air</b> (A9608300018)..... <b>PA30122</b>	<b>Cab Air</b> (A9608300018)..... <b>PA30122</b>	<b>Cab Air</b> (w/Carbon) (A9608300118)..... <b>PA30123</b>
<b>Cab Air</b> (w/Carbon) (A9608300118)..... <b>PA30123</b>	<b>Cab Air</b> (w/Carbon) (A9608300118)..... <b>PA30123</b>	<b>Cab Air</b> (A0008307518)..... <b>PA5585</b>
<b>Cab Air</b> (A0008307518)..... <b>PA5585</b>	<b>Cab Air</b> (A9608300218)..... <b>PA30124</b>	<b>Cab Air</b> (A9608300218)..... <b>PA30124</b>
<b>Cab Air</b> (A9608300218)..... <b>PA30124</b>	<b>Cab Air</b> (A0008307518)..... <b>PA5585<sup>90</sup></b>	<b>Air Dryer</b> (A0004295695)..... <b>BA5379 +</b>
<b>Air Dryer</b> (A0004295695)..... <b>BA5379 +</b>	<b>Air Dryer</b> (A0004295695)..... <b>BA5379 +</b>	<b>Coolant</b> (A4722030255)..... <b>P5092</b>
<b>Coolant</b> (A4722030255)..... <b>P5092</b>	<b>Coolant</b> (A4722030255)..... <b>P5092</b>	<b>Steering</b> (A0004660604)..... <b>P106-HD</b>
<b>Steering</b> (A0004660604)..... <b>P106-HD</b>	<b>Steering</b> (A0004660604)..... <b>P106-HD</b>	<b>Urea</b> (A0001421089)..... <b>PE17002 KIT</b>
<b>Urea</b> (A0001421089)..... <b>PE17002 KIT</b>	<b>Urea</b> (A0001421089)..... <b>PE17002 KIT</b>	Econic 2635 w/OM936LA (Euro 6) Eng. (05/13-on)
Arocs 4165 w/OM473LA (BlueTec 5/6) Eng. (04/13-on)	Arocs 4451 w/OM471LA (BlueTec 5/6) Eng. (04/13-on)	<b>Lube</b> (A9361800009)..... <b>P40003</b>
<b>Lube</b> (A4731800009)..... <b>P7505</b>	<b>Lube</b> (A4731800009)..... <b>P7505</b>	<b>Fuel/Water Separator</b> (A9604770003)..... <b>BF1297-O</b>
<b>Fuel/Water Separator</b> (A9604770003)..... <b>BF1297-O</b>	<b>Fuel/Water Separator</b> (A9604770003)..... <b>BF1297-O</b>	<b>Air</b> (A0040947504)..... <b>CA5788</b>
<b>263 mm Air</b> (A0040946804)..... <b>CA30104</b>	<b>Fuel</b> (Mahle Assembly) (A4710909052)..... <b>PF9908 KIT</b>	<b>Cab Air</b> (A0008301118)..... <b>PA4956</b>
<b>228 mm Air</b> (A0040946904)..... <b>CA30103</b>	<b>263 mm Air</b> (A0040946804)..... <b>CA30104</b>	<b>Cab Air</b> (A0008301318)..... <b>PA5492</b>
<b>210 mm Air</b> (A0040947204)..... <b>CA30105</b>	<b>228 mm Air</b> (A0040946904)..... <b>CA30103</b>	<b>Steering</b> (A0004660604)..... <b>P106-HD</b>
<b>Cab Air</b> (A9608300018)..... <b>PA30122</b>	<b>210 mm Air</b> (A0040947204)..... <b>CA30105</b>	<b>Urea</b> (A0001420789)..... <b>PE17002 KIT</b>
<b>Cab Air</b> (w/Carbon) (A9608300118)..... <b>PA30123</b>	<b>Cab Air</b> (A9608300018)..... <b>PA30122</b>	Econic 2630 NGT w/M936G (Euro 6) Eng. (2014-on)
<b>Cab Air</b> (A0008307518)..... <b>PA5585</b>		<b>Lube</b> (A9361800009)..... <b>P40003</b>
<b>Cab Air</b> (A9608300218)..... <b>PA30124</b>		<b>Air</b> (A0040947504)..... <b>CA5788</b>
<b>Air Dryer</b> (A0004295695)..... <b>BA5379 +</b>		<b>Cab Air</b> (A0008301118)..... <b>PA4956</b>
<b>Coolant</b> (A4722030255)..... <b>P5092</b>		<b>Cab Air</b> (A0008301318)..... <b>PA5492</b>
<b>Steering</b> (A0004660604)..... <b>P106-HD</b>		
<b>Urea</b> (A0001421089)..... <b>PE17002 KIT</b>		

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.

Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ European Trucks, Vans (cont'd)	MERCEDES-BENZ Latin America Buses (cont'd)	MERCEDES-BENZ Latin America Buses (cont'd)
Econic 2630 NGT w/M936G (Euro 6) Eng. (2014-on) (Cont'd) <b>Steering</b> (A0004660604)..... <b>P106-HD</b> Econic 2630 w/OM936LA (Euro 6) Eng. (05/13-on) <b>Lube</b> (A9361800009)..... <b>P40003</b> <b>Fuel/Water Separator</b> (A9604770003)..... <b>BF1297-O</b> <b>Air</b> (A0040947504)..... <b>CA5788</b> <b>Cab Air</b> (A0008301118)..... <b>PA4956</b> <b>Cab Air</b> (A0008301318)..... <b>PA5492</b> <b>Steering</b> (A0004660604)..... <b>P106-HD</b> <b>Urea</b> (A0001420789)..... <b>PE17002 KIT</b>	Allegro w/OM906 Eng. (Cont'd) <b>Fuel/Water Separator</b> (Open End for Bowl) (A3844777015)..... <b>BF46109-O</b> Allegro w/OM906LA Eng. <b>Fuel/Water Separator</b> (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> <b>Fuel/Water Separator</b> (With Bowl) (Mann WK1060/1)..... <b>BF46072</b> <b>Fuel/Water Separator</b> (With Drain) (Mann WK1060/1)..... <b>BF1329</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A3844777015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A3844777015)..... <b>BF46109-O</b>	LK-1300/34 w/OM904LA Eng. (Cont'd) <b>Fuel/Water Separator</b> (With Drain) (Mann WK1060/1)..... <b>BF1329</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A3844777015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A3844777015)..... <b>BF46109-O</b> LO 610 <b>Fuel/Water Separator</b> (A3820927005)..... <b>BF9922-O</b> <b>Fuel</b> (To identification number D 031294) (A3524700092)..... <b>[2] F834-F</b> <b>Air</b> (A0030943304)..... <b>PA2845</b> <b>Steering</b> (A0004660604)..... <b>P106-HD</b>
Econic 1835 w/OM936LA (Euro 6) Eng. (05/13-on) <b>Lube</b> (A9361800009)..... <b>P40003</b> <b>Fuel/Water Separator</b> (A9604770003)..... <b>BF1297-O</b> <b>Air</b> (A0040947504)..... <b>CA5788</b> <b>Cab Air</b> (A0008301118)..... <b>PA4956</b> <b>Cab Air</b> (A0008301318)..... <b>PA5492</b> <b>Steering</b> (A0004660604)..... <b>P106-HD</b> <b>Urea</b> (A0001420789)..... <b>PE17002 KIT</b>	Andare 1628 w/OM906 Eng. <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A3844777015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A3844777015)..... <b>BF46109-O</b>	LO 712 Bus Chassis w/OM 364 LA Eng. <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A9794770015)..... <b>BF46109-O</b> <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0001842225)..... <b>P106-HD</b>
Econic 1830 NGT w/M936G (Euro 6) Eng. (2014-on) <b>Lube</b> (A9361800009)..... <b>P40003</b> <b>Air</b> (A0040947504)..... <b>CA5788</b> <b>Cab Air</b> (A0008301118)..... <b>PA4956</b> <b>Cab Air</b> (A0008301318)..... <b>PA5492</b> <b>Steering</b> (A0004660604)..... <b>P106-HD</b>	Andare 1728 w/OM906LA Eng. <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A3844777015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A3844777015)..... <b>BF46109-O</b>	LO 712/37 w/OM 364 LA (Euro III) Eng. <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A9794770015)..... <b>BF46109-O</b> <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0001842225)..... <b>P106-HD</b>
Econic 1830 w/OM936LA (Euro 6) Eng. (05/13-on) <b>Lube</b> (A9361800009)..... <b>P40003</b> <b>Fuel/Water Separator</b> (A9604770003)..... <b>BF1297-O</b> <b>Air</b> (A0040947504)..... <b>CA5788</b> <b>Cab Air</b> (A0008301118)..... <b>PA4956</b> <b>Cab Air</b> (A0008301318)..... <b>PA5492</b> <b>Steering</b> (A0004660604)..... <b>P106-HD</b> <b>Urea</b> (A0001420789)..... <b>PE17002 KIT</b>	Boxer w/OM904 Eng. <b>Fuel/Water Separator</b> (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> <b>Fuel/Water Separator</b> (With Bowl) (Mann WK1060/1)..... <b>BF46072</b> <b>Fuel/Water Separator</b> (With Drain) (Mann WK1060/1)..... <b>BF1329</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b>	LO 812 w/OM 364 LA (Euro III) Eng. <b>Fuel/Water Separator</b> (A3820927005)..... <b>BF9922-O</b> <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0004660604)..... <b>P106-HD</b>
<p style="text-align: center;"><b>MERCEDES-BENZ</b> <b>Latin America Buses</b></p> Allegro w/OM906 Eng. <b>Fuel/Water Separator</b> (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> <b>Fuel/Water Separator</b> (With Bowl) (Mann WK1060/1)..... <b>BF46072</b> <b>Fuel/Water Separator</b> (With Drain) (Mann WK1060/1)..... <b>BF1329</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A3844777015)..... <b>BF46071</b>	Boxer w/OM904LA Eng. <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A3844777015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A3844777015)..... <b>BF46109-O</b> LK-1300/34 w/OM904LA Eng. <b>Fuel/Water Separator</b> (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> <b>Fuel/Water Separator</b> (With Bowl) (Mann WK1060/1)..... <b>BF46072</b>	LO 814 <b>Fuel/Water Separator</b> (A3820927005)..... <b>BF9922-O</b> <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0004660604)..... <b>P106-HD</b> LO 914 <b>Lube</b> (A0001801609)..... <b>P7199</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9584770115)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A3844777015)..... <b>BF46109-O</b> <b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115)..... <b>BF46123-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Air</b> (A0040944104)..... <b>PA3843</b>

+ See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



MERCEDES-BENZ Latin America Buses (cont'd)	MERCEDES-BENZ Latin America Buses (cont'd)	MERCEDES-BENZ Latin America Buses (cont'd)
LO 914 (Cont'd)	MBO 1219/52 w/OM904LA Eng. (Cont'd)	O303 w/OM403 Eng.
419.1 mm Radial Seal Air (A3740947104).....	Fuel/Water Separator (Sensor Port Thread 9/16-18) (Mann WK1060/1).....	188.1 mm Lube (4011840025).....
RS5452	BF1329-SP	P242
Air Dryer (A0004300969).....		264.3 mm Lube (4031840025).....
BA5374 *		P294
LO 915 w/OM 904 LA (Euro III) Eng.	Fuel/Water Separator (Sensor Port Thread 1/2-20) (Mann WK1060/1).....	Fuel (3524700092).....
Lube (A0001801609).....	BF1339-SP *	F834-F
P7199		374.7 mm O. Air (10944204).....
Fuel/Water Separator (w/Drain (A0004771302).....)		PA2405
BF1363		371.5 mm I. Air (61200190033)...
Fuel/Water Separator (Open End for Bowl) (A0004771302).....		PA2835
BF1391-O		381.0 mm Some Air (10944704)...
Fuel/Water Separator (w/Undetachable Bowl) (A9794770015).....		PA2474
BF46071		496.9 mm Some Air (10947904)...
Fuel/Water Separator (Open End for Bowl) (A9794770015).....		PA2475
BF46109-O		Steering (4660004).....
Fuel/Water Separator (A3820927005).....		PT691
BF9922-O		O305G w/OM407A, OM407HA Engs.
Fuel (A0000901551).....		Lube (11843825).....
PF7735		P294
Radial Seal O. Air (A3740947104).....		Fuel (3524700092).....
RS5452		F834-F
Radial Seal I. Air (A3740947204).....		Air (10948304).....
RS5453		PA2838
Air Dryer (Knorr System) (A0004300969).....		Steering (4660004).....
BA5374 *		PT691
Steering (A0004660604).....		O305G, O305ST, O307 w/OM407H Eng.
P106-HD		Lube (4031840025).....
MBO 1019/44 w/OM904LA Eng.		P294
Fuel/Water Separator (Open End for Bowl) (Mann WK1060/1).....		114.3 mm Some Fuel Ele. (3524700092).....
BF46083-O		F834-F
Fuel/Water Separator (With Bowl) (Mann WK1060/1).....		142.9 mm Some Fuel Ele. (4220900051).....
BF46072		F950-F
Fuel/Water Separator (With Drain) (Mann WK1060/1).....		254.0 mm Air (10949304).....
BF1329		PA2812
Fuel/Water Separator (Sensor Port Thread 9/16-18) (Mann WK1060/1).....		383.4 mm Air (10941004).....
BF1329-SP		PA2847
Fuel/Water Separator (Sensor Port Thread 1/2-20) (Mann WK1060/1).....		Steering (4660004).....
BF1339-SP *		PT691
MBO 1200/52 OF w/OM904LA Eng.		O309B
Fuel/Water Separator (Open End for Bowl) (Mann WK1060/1).....		Fuel Ele. (To 1964) (3524700092).....
BF46083-O		F834-F
Fuel/Water Separator (With Bowl) (Mann WK1060/1).....		O309D w/OM314 Eng.
BF46072		B-P Lube (1845825).....
Fuel/Water Separator (With Drain) (Mann WK1060/1).....		P41
BF1329		Fuel Ele. (To 1978).....
Fuel/Water Separator (Sensor Port Thread 9/16-18) (Mann WK1060/1).....		F950-F
BF1329-SP		O309D w/OM352 Eng.
Fuel/Water Separator (Sensor Port Thread 1/2-20) (Mann WK1060/1).....		196.9 mm Lube (1846725).....
BF1339-SP *		P42
MBO 1219/52 w/OM904LA Eng.		199.2 mm Lube (11845225).....
Fuel/Water Separator (Open End for Bowl) (Mann WK1060/1).....		P7015
BF46083-O		Fuel (3524700092).....
Fuel/Water Separator (With Bowl) (Mann WK1060/1).....		F834-F
BF46072		O309D w/OM615 Eng.
Fuel/Water Separator (With Drain) (Mann WK1060/1).....		Lube (1848525).....
BF1329		P40
Fuel/Water Separator (Sensor Port Thread 9/16-18) (Mann WK1060/1).....		Fuel (3524700092).....
BF1329-SP		F834-F
Fuel/Water Separator (Sensor Port Thread 1/2-20) (Mann WK1060/1).....		O309D w/OM616, OM617 Engs.
BF1339-SP *		Lube (6171840125).....
MBO 1219/52 w/OM904LA Eng.		P102
Fuel/Water Separator (Open End for Bowl) (Mann WK1060/1).....		O317 w/OM326 Eng.
BF46083-O		Lube (11844925).....
Fuel/Water Separator (With Bowl) (Mann WK1060/1).....		P721
BF46072		Fuel Ele. (4220900051).....
Fuel/Water Separator (With Drain) (Mann WK1060/1).....		F950-F
BF1329		Steering (4660004).....
Fuel/Water Separator (Sensor Port Thread 9/16-18) (Mann WK1060/1).....		PT691
BF1329-SP		O317 w/OM355HA Eng.
Fuel/Water Separator (Sensor Port Thread 1/2-20) (Mann WK1060/1).....		Lube (3551800009).....
BF1339-SP *		P7052
MBO 1219/52 w/OM904LA Eng.		Fuel Ele. (4220900051).....
Fuel/Water Separator (Open End for Bowl) (Mann WK1060/1).....		F950-F
BF46083-O		Steering (4660004).....
Fuel/Water Separator (With Bowl) (Mann WK1060/1).....		PT691
BF46072		O319D w/M121, M929 Engs.
Fuel/Water Separator (With Drain) (Mann WK1060/1).....		Fuel (3524700092).....
BF1329		F834-F

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ Latin America Buses (cont'd)	MERCEDES-BENZ Latin America Buses (cont'd)	MERCEDES-BENZ Latin America Buses (cont'd)
O319D w/OM621, OM913 Engs. B-P Lube (1848525)..... P40 Fuel (3524700092)..... F834-F	O 371 UL w/OM 366 LA Eng. Fuel (A0000901451)..... [2] F950-F Fuel (A3524700092)..... [2] F834-F Steering (A0004660604)..... P106-HD	O405 w/OM447HA Eng. Lube (11843825)..... P294 Fuel Ele. (4220900051)..... PF950 Air (10947904)..... PA2475 Trans. (ZF 2701098)..... PT8385 Steering (4660204)..... P106-HD
O321H, O322 w/OM322, OM346 Engs. Lube (11844925)..... P721 P. Fuel Ele. (4220900051)..... F950-F S. Fuel Ele. (4774515)..... PF231 Steering (4660004)..... PT691	O 371 UP w/OM 355/5A Eng. Fuel (A0000901451)..... [2] F950-F Fuel (A3524700092)..... [2] F834-F Air (A3880947004)..... PA2776 Steering (A0001842225)..... P106-HD	O405, O405G w/OM427H Eng. Lube (11843825)..... P294 Fuel Ele. (4220900051)..... F950-F Air (10944704)..... PA2474
O321H, O322 w/OM352 Eng. B-P Lube (1846725)..... P42 Fuel Ele. (4220900051)..... F950-F	O400 w/OM457LA Eng. Fuel/Water Separator (w/Undetachable Bowl) (A3844777015)..... BF46071 Fuel/Water Separator (Open End for Bowl) (A3844777015)..... BF46109-O	O407D w/OM616, OM617 Engs. Lube (6171800009)..... P102
O340 w/OM441LA Eng. Lube..... P7016 Fuel Ele..... F950-F Air (30941504)..... PA2776 Steering..... P106-HD	O 400 RSD w/OM 447 LA Eng. Lube (A0001801109)..... P294 Fuel/Water Separator (A3820927005)..... BF9922-O Fuel (A0000901451)..... [2] F950-F O. Air (A3880947004)..... PA2776 Opt. I. Air..... PA3494 Steering (A0004660604)..... P106-HD	O407H w/OM427H, OM427HA Engs. Lube (4031840025)..... P294 Fuel Ele. (4220900051)..... F950-F Air (10944704)..... PA2474
O 370 w/OM 355 LA Eng. Fuel (A0000901451)..... [2] F950-F Fuel (A3524700092)..... [2] F834-F Steering (A0001842225)..... P106-HD	O 400 RSE w/OM 477 LA Eng. Lube (A0001801109)..... P294 Fuel/Water Separator (A3820927005)..... BF9922-O Fuel (A0000901451)..... [2] F950-F O. Air (A3880947004)..... PA2776 Opt. I. Air (A3880947104)..... PA3494 Steering (A0004660604)..... P106-HD	O409D w/OM616, OM617 Engs. Lube (6171800009)..... P102
O 371 w/OM 355 A Eng. Fuel/Water Separator (A3820927005)..... BF9922-O Fuel (A3524700092)..... [2] F834-F Steering (A0004660604)..... P106-HD	O 500 M w/OM906 (Euro III) Eng. Lube (A0001801709)..... P7188 Fuel/Water Separator (w/Male Thread for Bowl) (A9584770115).. BF46123-O Fuel/Water Separator (w/Undetachable Bowl) (A9794770015)..... BF46071 Fuel/Water Separator (w/Female Thread for Bowl) (A9794770015).. BF46109-O Fuel (A0000901551)..... PF7735 O. Air (A6345280306)..... RS5627 I. Air (A6345280206)..... RS5628 Air Dryer (A0004300969)..... BA5374 + Trans. (A0002701098)..... PT8385 Steering (A0001842225)..... P106-HD	O 500 1725 w/OM906LA Eng. Fuel/Water Separator (w/Undetachable Bowl) (A3844777015)..... BF46071 Fuel/Water Separator (Open End for Bowl) (A3844777015)..... BF46109-O
O 371 R w/OM 449 LA Eng. Lube (A0001801109)..... P294 Fuel/Water Separator (A3820927005)..... BF9922-O Fuel (A0000901451)..... [2] F950-F Steering (A0004660604)..... P106-HD	O 400 RSL w/OM 447 LA Eng. Lube (A0001801109)..... P294 Fuel/Water Separator (A3820927005)..... BF9922-O Fuel (A0000901451)..... [2] F950-F Air (A3880947004)..... PA2776 Steering (A0004660604)..... P106-HD	O 500 M w/OM 926 LA (Euro V) Eng. Lube (A0001801709)..... P7188 Fuel/Water Separator (w/Undetachable Bowl) (A9794770015)..... BF46071 Fuel/Water Separator (w/Female Thread for Bowl) (A9794770015).. BF46109-O Fuel/Water Separator (w/Male Thread for Bowl) (A9584770115).. BF46123-O Fuel (A0000901551)..... PF7735 Radial Seal I. Air (To identification number D 375298) (A3760948004)..... RS5628 Radial Seal O. Air (Identification number D 375299-on) (A6345280306)..... RS5627 Radial Seal I. Air (Identification number D 375299-on) (A6345280206)..... RS5628
O 371 RDS Steering (A0001842225)..... P106-HD	O 400 UP w/OM 449 LA Eng. Lube (A0001801109)..... P294 Fuel/Water Separator (A3820927005)..... BF9922-O Fuel (A0000901451)..... [2] F950-F Air Dryer (A0004293795)..... BA5374 + Steering (A0004660604)..... P106-HD	
O 371 RS w/OM 447 LA Eng. Lube (A0001801109)..... P294 Fuel (A0000901451)..... [2] F950-F Air (A3880947004)..... PA2776 Steering (A0004660604)..... P106-HD	O402 w/OM366 Eng. Lube (4011800009)..... P242 Fuel (3524700092)..... F834-F	
O 371 RSD w/OM 447 LA Eng. Lube (A0001801109)..... P294 Fuel (A0000901451)..... [2] F950-F Air (A3880947004)..... PA2776 Steering (A0004660604)..... P106-HD	O404 w/OM401LA, OM402A, OM442LA Engs. Lube (4411800009)..... P7016 Fuel Ele. (4220900051)..... F950-F Air (30941504)..... PA2776	
O 371 RSE w/OM 447 LA Eng. Lube (A0001801109)..... P294 Fuel (A0000901451)..... [2] F950-F Air (A3880947004)..... PA2776 Steering (A0004660604)..... P106-HD	O405, O405G w/OM407A, OM407HA Engs. Lube (11843825)..... P294 Some Fuel Ele. (3524700092)..... F834-F Air (10948304)..... PA2838 Steering (4660004)..... PT691	
O 371 RSL w/OM 447 LA Eng. Lube (A0001801109)..... P294 Fuel (A0000901451)..... [2] F950-F Air (A3880947004)..... PA2776 Steering (A0004660604)..... P106-HD		

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ Latin America Buses (cont'd)	MERCEDES-BENZ Latin America Buses (cont'd)	MERCEDES-BENZ Latin America Buses (cont'd)
O 500 M w/OM 926 LA (Euro V) Eng. (Cont'd)	O 500 U w/OM 906 LA Eng. (Cont'd)	OF 1113
<b>Trans.</b> (ZF) (A0002701098)..... <b>PT8385</b>	<b>Radial Seal I. Air</b> (Identification number: D375299-on) (A6345280206)..... <b>RS5628</b>	<b>Lube</b> (A0001842225)..... <b>P106</b>
<b>Steering</b> (A0001842225)..... <b>P106-HD</b>	<b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b>	OF 1114 w/OM 352 A Eng.
<b>Urea</b> (A0001420289)..... <b>PE5272</b>	<b>Trans.</b> (ZF Ecomat Trans.) (A0002701098)..... <b>PT8385</b>	<b>Fuel</b> (A3524700092)..... <b>F834-F</b>
O 500 R Bus Chassis w/OM 926 LA Eng.	<b>Steering</b> (A0001842225)..... <b>P106-HD</b>	<b>Steering</b> (A0004660604)..... <b>P106-HD</b>
<b>Lube</b> (A0001801709)..... <b>P7188</b>	<b>Urea</b> (A0001420289)..... <b>PE5272</b>	OF 1115 w/OM 366 Eng.
<b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b>	O 500 U 59CA w/OM 906 LA (Euro III) Eng.	<b>Fuel/Water Separator</b> (A3820927005)..... <b>BF9922-O</b>
<b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A9794770015).. <b>BF46109-O</b>	<b>Lube</b> (A0001801709)..... <b>P7188</b>	<b>Fuel</b> (A3444700092)..... <b>F834-F</b>
<b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b>	<b>Fuel</b> (A0000901551)..... <b>PF7735</b>	<b>Fuel</b> (A3524700092)..... <b>[2] F834-F</b>
<b>Fuel</b> (A0000901551)..... <b>PF7735</b>	<b>O. Air</b> (A6345280306)..... <b>RS5627</b>	<b>Air</b> (A0010944704)..... <b>PA2474</b>
<b>O. Air</b> (A6345280306)..... <b>RS5627</b>	<b>I. Air</b> (A6345280206)..... <b>RS5628</b>	<b>Steering</b> (A0001842225)..... <b>P106-HD</b>
<b>I. Air</b> (A6345280206)..... <b>RS5628</b>	<b>Trans.</b> (ZF Ecomat Trans.) (A0002701098)..... <b>PT8385</b>	OF 1313 w/OM 352 I Eng.
<b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b>	O609D w/OM364 Eng.	<b>Fuel</b> (A0000901451)..... <b>[2] F950-F</b>
<b>Steering</b> (To identification number D 285869) (A0004660204)..... <b>P106-HD</b>	<b>Lube</b> (S/N 286115-up)..... <b>P7017</b>	<b>Fuel</b> (A3524700092)..... <b>[2] F834-F</b>
<b>Steering</b> (Identification number D 285870-on) (A0001842225)..... <b>P106-HD</b>	<b>Fuel</b> ..... <b>F834-F</b>	<b>Single Air</b> (A0010945204)..... <b>PA2405</b>
O 500 RSD w/OM457 (Euro V) Eng.	<b>Steering</b> ..... <b>P106-HD</b>	<b>Steering</b> (A0001842225)..... <b>P106-HD</b>
<b>Lube</b> (A0001802909)..... <b>P7230</b>	O611D, O614D w/OM364A, OM364LA Engs.	OF 1314 w/OM 352 I Eng.
<b>Fuel/Water Separator</b> (w/Drain) (A0004771302)..... <b>BF1363</b>	<b>Lube</b> (3141800109)..... <b>P7017</b>	<b>Fuel</b> (A0000901451)..... <b>[2] F950-F</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b>	<b>Fuel</b> ..... <b>F834-F</b>	<b>Fuel</b> (A3524700092)..... <b>[2] F834-F</b>
<b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b>	<b>Air</b> (20949304)..... <b>PA3843</b>	<b>Single Air</b> (A0010945204)..... <b>PA2405</b>
<b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A9794770015).. <b>BF46109-O</b>	<b>Steering</b> ..... <b>P106-HD</b>	<b>Steering</b> (A0001842225)..... <b>P106-HD</b>
<b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b>	O614D w/OM364A Eng.	OF 1315 w/OM 366 Eng.
<b>Fuel</b> (A5410900151)..... <b>PF7761</b>	<b>Lube</b> (3141800109)..... <b>P7017</b>	<b>Fuel/Water Separator</b> (A3820927005)..... <b>BF9922-O</b>
<b>Radial Seal O. Air</b> (A4760940004)..... <b>RS5358</b>	<b>Fuel</b> ..... <b>F834-F</b>	<b>Fuel</b> (A3444700092)..... <b>F834-F</b>
<b>Radial Seal I. Air</b> (A4760940104)..... <b>RS5549</b>	<b>Steering</b> ..... <b>P106-HD</b>	<b>Fuel</b> (A3524700092)..... <b>[2] F834-F</b>
<b>Air Dryer</b> (A0004293795)..... <b>BA5374 +</b>	O1200/52 OF w/OM904LA Eng.	<b>Air</b> (A0010944704)..... <b>PA2474</b>
<b>Trans.</b> (A0002701098)..... <b>PT8385</b>	<b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A3844777015)..... <b>BF46071</b>	<b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b>
<b>Steering</b> (Identification number: D285870-on) (A0001842225)..... <b>P106-HD</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (A3844777015)..... <b>BF46109-O</b>	<b>Steering</b> (A0001842225)..... <b>P106-HD</b>
<b>Urea</b> (A0001420289)..... <b>PE5272</b>	O1400/60 OF w/OM904LA Eng.	OF 1318 w/OM 366 LA Eng.
O 500 U w/OM 906 LA Eng.	<b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A3844777015)..... <b>BF46071</b>	<b>Fuel</b> (A3900920001)..... <b>BF970 +</b>
<b>Lube</b> (A0001801709)..... <b>P7188</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (A3844777015)..... <b>BF46109-O</b>	<b>Air</b> (A0010945204)..... <b>PA2405</b>
<b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b>	O1419/60 w/OM904LA Eng.	<b>Steering</b> (A0004660604)..... <b>P106-HD</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (A9794770015)..... <b>BF46109-O</b>	<b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A3844777015)..... <b>BF46071</b>	OF 1417 (Argentina)
<b>Fuel</b> (A0000901551)..... <b>PF7735</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (A3844777015)..... <b>BF46109-O</b>	<b>Radial Seal Air</b> (A3740947104)..... <b>RS5452</b>
<b>Radial Seal I. Air</b> (To identification number: D375298) (A3760948004)..... <b>RS5628</b>	OF 812 w/OM 364 A Eng.	OF 1417 (Brazil)
<b>Radial Seal O. Air</b> (Identification number: D375299-on) (A6345280306)..... <b>RS5627</b>	<b>Fuel/Water Separator</b> (A3820927005)..... <b>BF9922-O</b>	<b>Lube</b> (A0001842225)..... <b>P106</b>
	<b>Fuel</b> (A3524700092)..... <b>F834-F</b>	<b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9584770115)..... <b>BF46071</b>
	<b>Air</b> (A0030943304)..... <b>PA2845</b>	<b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A3844777015).. <b>BF46109-O</b>
	<b>Air Dryer</b> (A0004293695)..... <b>BA5374 +</b>	<b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b>
	<b>Steering</b> (A0004660604)..... <b>P106-HD</b>	<b>103.2 mm Fuel</b> (A0000901551).... <b>PF7735</b>
		<b>419.1 mm Radial Seal Air</b> (A3740947104)..... <b>RS5452</b>
		<b>438.2 mm Radial Seal Air</b> (A3760948204)..... <b>RS30130</b>
		<b>Radial Seal I. Air</b> (A3760948304)..... <b>RS5676</b>
		<b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ Latin America Buses (cont'd)	MERCEDES-BENZ Latin America Buses (cont'd)	MERCEDES-BENZ Latin America Buses (cont'd)
OF 1418 (Argentina) Lube (A0001801609)..... P7199	OH 1313 w/OM 352 I Eng. Fuel (A3524700092)..... [2] F834-F Air (A0010945204)..... PA2405 Steering (A0001842225)..... P106-HD	OH 1421 L w/OM 366 LA Eng. (Cont'd) Air (A0010945204)..... PA2405 Air Dryer (A0004300969)..... BA5374 + Steering (A0001842225)..... P106-HD
OF 1418 (Brazil) Fuel/Water Separator (Open End for Bowl) (A9794770015)..... BF46109-O Fuel/Water Separator (Open End for Bowl) (A9794770015)..... BF46071 Radial Seal O. Air (A3740947104)..... RS5452	OH 1314 w/OM 352 Eng. Fuel (A3524700092)..... F834-F Steering (A0004660204)..... P106-HD	OH 1517 w/OM 355/5 Eng. Fuel (A3524700092)..... [2] F834-F Air (A0010945204)..... PA2405 Steering (A0001842225)..... P106-HD
OF-1519 w/OM-924-LA (Euro V) Eng. Lube..... P7199 Radial Seal O. Air (A3740947104)..... RS5452	OH 1315 w/OM366 Eng. Fuel (A3524700092)..... F834-F Steering (A0004660604)..... P106-HD	OH 1518 Bus Chassis w/OM 904 LA Eng. Lube (A0001801609)..... P7199 Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363 Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O Fuel/Water Separator (w/Undetachable Bowl) (A9794770015)..... BF46071 Fuel/Water Separator (w/Female Thread for Bowl) (A9794770015).. BF46109-O Fuel/Water Separator (w/Male Thread for Bowl) (A9584770115).. BF46123-O Fuel (A0000901551)..... PF7735 O. Air (A6345280306)..... RS5627 I. Air (A6345280206)..... RS5628 Air Dryer (A0004300969)..... BA5374 + Steering (A0001842225)..... P106-HD Urea (A0001420289)..... PE5272
OF 1618 w/OM 366 A Eng. Fuel/Water Separator (A3820927005)..... BF9922-O Fuel (A3524700092)..... [2] F834-F Air (A0010944704)..... PA2474 Air Dryer (A0004300969)..... BA5374 +	OH 1315-52 Urbano Bus w/OM 904 LA (Euro III) Eng. Lube (A0001801609)..... P7199 Fuel/Water Separator (w/Undetachable Bowl) (A3844777015)..... BF46071 Fuel/Water Separator (Open End for Bowl) (A3844777015)..... BF46109-O Fuel (A0000901551)..... PF7735 Air Dryer (A0004293795)..... BA5374 + Steering (A0004660604)..... P106-HD	OH 1518 w/OM 926 LA (Euro V) Eng. Lube (A0001801709)..... P7188 Fuel/Water Separator (w/Undetachable Bowl) (A9794770015)..... BF46071 Fuel/Water Separator (w/Female Thread for Bowl) (A9794770015).. BF46109-O Fuel/Water Separator (w/Male Thread for Bowl) (A9584770115).. BF46123-O Fuel (A0000901551)..... PF7735 O. Air (A6345280306)..... RS5627 I. Air (A6345280206)..... RS5628 Air Dryer (A0004300969)..... BA5374 + Steering (A0001842225)..... P106-HD Urea (A0001420289)..... PE5272
OF 1721 w/OM 366LA Eng. Fuel/Water Separator (A3820927005)..... BF9922-O Fuel (A3524700092)..... [2] F834-F Single Air (A0010944704)..... PA2474 Radial Seal O. Air (A3760948204)..... RS30130 Radial Seal I. Air (A3760948304)..... RS5676 Air Dryer (A0004300969)..... BA5374 + Steering (A0001842225)..... P106-HD	OH 1316 Lube (A0001801609)..... P7199 Fuel/Water Separator (w/Undetachable Bowl) (A3844777015)..... BF46071 Fuel/Water Separator (Open End for Bowl) (A3844777015)..... BF46109-O Fuel (A0000901551)..... PF7735 Air Dryer (A0004293795)..... BA5374 + Steering (A0004660604)..... P106-HD	OH 1520 w/OM 926 LA (Euro V) Eng. Lube (A0001801709)..... P7188 Fuel/Water Separator (w/Undetachable Bowl) (A9794770015)..... BF46071 Fuel/Water Separator (w/Female Thread for Bowl) (A9794770015).. BF46109-O Fuel/Water Separator (w/Male Thread for Bowl) (A9584770115).. BF46123-O Fuel (A0000901551)..... PF7735 O. Air (A6345280306)..... RS5627 I. Air (A6345280206)..... RS5628 Air Dryer (A0004300969)..... BA5374 + Steering (A0001842225)..... P106-HD Urea (A0001420289)..... PE5272
OF 1721 (Brazil) Lube (A0001842225)..... P106 Fuel/Water Separator (w/Undetachable Bowl) (A9584770115)..... BF46071 Fuel/Water Separator (w/Female Thread for Bowl) (A3844777015).. BF46109-O Fuel/Water Separator (w/Male Thread for Bowl) (A9584770115).. BF46123-O Radial Seal Air (A3760948204)... RS30130 Radial Seal I. Air (A3760948304)..... RS5676 Radial Seal O. Air (A6345280306)..... RS5627 Radial Seal I. Air (A6345280206)..... RS5628 Air Dryer (A0004300969)..... BA5374 +	OH 1318 w/OM 366A Eng. Fuel (A3444700092)..... F834-F Fuel (A3524700092)..... [2] F834-F Air (A0010945204)..... PA2405 Steering (A0004660604)..... P106-HD	
OF 1722 (Argentina) Lube (A0001801709)..... P7188	OH 1418 w/OM 366 LA Eng. Fuel (A3900920001)..... BF970 + Steering (A0004660604)..... P106-HD	
OF 1722 (Brazil) Fuel/Water Separator (Open End for Bowl) (A9794770015)..... BF46109-O Fuel/Water Separator (w/Bowl) (A9794770015)..... BF46071 Radial Seal Air (3760948204)..... RS30130	OH 1419 w/OM 366 A Eng. Lube (A3661800009)..... P7015 Fuel (A3524700092)..... [2] F834-F Steering (A0004660604)..... P106-HD	
	OH 1420 w/OM 366 A Eng. Lube (A0001842225)..... P106 Lube (A3661800009)..... P7015 Fuel (A3524700092)..... [2] F834-F Steering (A0004660604)..... P106-HD	
	OH 1421 Air Dryer (A0004300969)..... BA5374 +	
	OH 1421 L w/OM 366 LA Eng. Fuel/Water Separator (A3820927005)..... BF9922-O Fuel (A3524700092)..... [2] F834-F	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ Latin America Buses (cont'd)	MERCEDES-BENZ Latin America Buses (cont'd)	MERCEDES-BENZ Latin America Buses (cont'd)
OH 1618 Urbano Bus w/OM 904 LA (Euro III) Eng. <b>Lube</b> (A0001801609)..... <b>P7199</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A9794770015).. <b>BF46109-O</b> <b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>O. Air</b> (A6345280306)..... <b>RS5627</b> <b>I. Air</b> (A6345280206)..... <b>RS5628</b> <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0001842225)..... <b>P106-HD</b> <b>Urea</b> (A0001420289)..... <b>PE5272</b>	OH 1625 L w/OM 449 LA Eng. (Cont'd) <b>Steering</b> (A0001842225)..... <b>P106-HD</b> OH 1628 L w/OM 449 LA Eng. <b>Lube</b> (A0001801109)..... <b>P294</b> <b>Fuel/Water Separator</b> (A3820927005)..... <b>BF9922-O</b> <b>Fuel</b> (A0000901451)..... <b>[2] F950-F</b> <b>O. Air</b> (A3880947004)..... <b>PA2776</b> <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0001842225)..... <b>P106-HD</b> OH 1630 <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> OH 1635 L w/OM 447 LA Eng. <b>Lube</b> (A0001801109)..... <b>P294</b> <b>Fuel/Water Separator</b> (A3820927005)..... <b>BF9922-O</b> <b>Fuel</b> (A0000901451)..... <b>[2] F950-F</b> <b>O. Air</b> (A3880947004)..... <b>PA2776</b> <b>Opt. I. Air</b> (A3880947104)..... <b>PA3494</b> <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0001842225)..... <b>P106-HD</b> OM 610 <b>Lube</b> (A0001842225)..... <b>P106</b> OMC 1400/51 w/OM906 Eng. <b>Fuel/Water Separator</b> (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> <b>Fuel/Water Separator</b> (With Bowl) (Mann WK1060/1)..... <b>BF46072</b> <b>Fuel/Water Separator</b> (With Drain) (Mann WK1060/1)..... <b>BF1329</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b> OMC 1400/51 w/OM906LA Eng. <b>Fuel/Water Separator</b> (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> <b>Fuel/Water Separator</b> (With Bowl) (Mann WK1060/1)..... <b>BF46072</b> <b>Fuel/Water Separator</b> (With Drain) (Mann WK1060/1)..... <b>BF1329</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A384477015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A384477015)..... <b>BF46109-O</b> OH 1621 w/OM 366 LA Eng. <b>Fuel</b> (A3900920001)..... <b>BF970 +</b> <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0004660604)..... <b>P106-HD</b> OH 1621 L w/OM 366A/LA (Euro III) Eng. <b>Lube</b> (A3661800009)..... <b>P7015</b> <b>Fuel</b> (A3900920001)..... <b>BF970 +</b> <b>Air Dryer</b> (A0004293795)..... <b>BA5374 +</b> <b>Steering</b> (A0004660604)..... <b>P106-HD</b> OH 1621 L w/OM 924 LA (Euro V) Eng. <b>Lube</b> (A0001801609)..... <b>P7199</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A9794770015).. <b>BF46109-O</b> <b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>O. Air</b> (A6345280306)..... <b>RS5627</b> <b>I. Air</b> (A6345280206)..... <b>RS5628</b> <b>Steering</b> (A0001842225)..... <b>P106-HD</b> <b>Urea</b> (A0001420289)..... <b>PE5272</b> OH 1622 L Bus Chassis w/OM 924 LA (Euro V) Eng. <b>Lube</b> (A0001801609)..... <b>P7199</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A9794770015)..... <b>BF46109-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>O. Air</b> (A6345280306)..... <b>RS5627</b> <b>I. Air</b> (A6345280206)..... <b>RS5628</b> <b>Steering</b> (A0001842225)..... <b>P106-HD</b> <b>Urea</b> (A0001420289)..... <b>PE5272</b> OH 1625 L w/OM 449 LA Eng. <b>Fuel/Water Separator</b> (A3820927005)..... <b>BF9922-O</b> <b>Fuel</b> (A0000901451)..... <b>[2] F950-F</b> <b>Air</b> (A0010945204)..... <b>PA2405</b> <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b>	Paradiso 1200 w/OM906LA Eng. <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A384477015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A384477015)..... <b>BF46109-O</b> Series Boxer 40 w/OM904LA Eng. <b>Fuel/Water Separator</b> (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> <b>Fuel/Water Separator</b> (With Bowl) (Mann WK1060/1)..... <b>BF46072</b> <b>Fuel/Water Separator</b> (With Drain) (Mann WK1060/1)..... <b>BF1329</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A384477015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A384477015)..... <b>BF46109-O</b> Series Boxer 50 w/OM904LA Eng. <b>Fuel/Water Separator</b> (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> <b>Fuel/Water Separator</b> (With Bowl) (Mann WK1060/1)..... <b>BF46072</b> <b>Fuel/Water Separator</b> (With Drain) (Mann WK1060/1)..... <b>BF1329</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A384477015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A384477015)..... <b>BF46109-O</b> Series Boxer 60 MBO w/OM904LA Eng. <b>Fuel/Water Separator</b> (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> <b>Fuel/Water Separator</b> (With Bowl) (Mann WK1060/1)..... <b>BF46072</b> <b>Fuel/Water Separator</b> (With Drain) (Mann WK1060/1)..... <b>BF1329</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A384477015)..... <b>BF46071</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ Latin America Buses (cont'd)	MERCEDES-BENZ Latin America Buses (cont'd)	MERCEDES-BENZ Latin America Buses (cont'd)
Series Boxer 60 MBO w/OM904LA Eng. (Cont'd) <b>Fuel/Water Separator</b> (Open End for Bowl) (A3844777015)..... <b>BF46109-O</b>	Torino 1119/40 w/OM924LA (Euro III) Eng. (Mexico) (Cont'd) <b>Fuel/Water Separator</b> (Open End for Bowl) (A9794770015)..... <b>BF46109-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b>	Torino 1419/51 w/OM924LA (Euro III) Eng. (Mexico) <b>Lube</b> (A0001801609)..... <b>P7199</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A9794770015)..... <b>BF46109-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b>
Torino w/OM906 Eng. <b>Fuel/Water Separator</b> (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> <b>Fuel/Water Separator</b> (With Bowl) (Mann WK1060/1)..... <b>BF46072</b> <b>Fuel/Water Separator</b> (With Drain) (Mann WK1060/1)..... <b>BF1329</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A3844777015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A3844777015)..... <b>BF46109-O</b>	Boxer OF 1119/41 w/OM924LA (EPA 04) Eng. (Mexico) <b>Lube</b> (A0001801609)..... <b>P7199</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A9794770015)..... <b>BF46109-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Radial Seal O. Air</b> (A3760948204)..... <b>RS30130</b> <b>Radial Seal I. Air</b> (A3760948304)..... <b>RS5676</b> <b>Steering</b> (A0001842225)..... <b>P106-HD</b>	1419/60 w/OM904LA or OM924LS Engines <b>Radial Seal O. Air</b> (A3740947104)..... <b>RS5452</b> <b>Radial Seal I. Air</b> (A3740947204)..... <b>RS5453</b>
Torino w/OM906LA Eng. <b>Fuel/Water Separator</b> (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> <b>Fuel/Water Separator</b> (With Bowl) (Mann WK1060/1)..... <b>BF46072</b> <b>Fuel/Water Separator</b> (With Drain) (Mann WK1060/1)..... <b>BF1329</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A3844777015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A3844777015)..... <b>BF46109-O</b>	1219/52 w/OM904LA or OM924LS Engines <b>Radial Seal O. Air</b> (A3740947104)..... <b>RS5452</b> <b>Radial Seal I. Air</b> (A3740947204)..... <b>RS5453</b>	Boxer 60 1419/60 w/OM924LA (Euro III) Eng. (Mexico) <b>Lube</b> (A0001801609)..... <b>P7199</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A9794770015)..... <b>BF46109-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b>
Boxer 40 1019/44 w/OM904LA (Euro III) Eng. (Mexico) <b>Lube</b> (A0001801609)..... <b>P7199</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A3844777015)..... <b>BF46109-O</b>	Boxer 50 1219/52 w/OM924LA (Euro III) Eng. (Mexico) <b>Lube</b> (A0001801609)..... <b>P7199</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A9794770015)..... <b>BF46109-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b>	Boxer 60 1419/65 w/OM924LA (Euro III) Eng. (Mexico) <b>Lube</b> (A0001801609)..... <b>P7199</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A9794770015)..... <b>BF46109-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b>
Boxer 40 1019/44 w/OM904LA (Euro III) Eng. (Mexico) <b>Lube</b> (A0001801609)..... <b>P7199</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A9794770015)..... <b>BF46109-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Radial Seal O. Air</b> (A3760948204)..... <b>RS30130</b> <b>Radial Seal I. Air</b> (A3760948304)..... <b>RS5676</b> <b>Steering</b> (A0001842225)..... <b>P106-HD</b>	Boxer OF 1319/44 w/OM924LA (EPA 04) Eng. (Mexico) <b>Lube</b> (A0001801609)..... <b>P7199</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A9794770015)..... <b>BF46109-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Radial Seal O. Air</b> (A3760948204)..... <b>RS30130</b> <b>Radial Seal I. Air</b> (A3760948304)..... <b>RS5676</b> <b>Steering</b> (A0001842225)..... <b>P106-HD</b>	Torino 1423/51 w/OM906LA (EPA 04) Eng. (Mexico) <b>Lube</b> (A0001801709)..... <b>P7188</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A9794770015)..... <b>BF46109-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Radial Seal O. Air</b> (Standard) (Don. P527682)..... <b>RS3518</b> <b>Radial Seal XP O. Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b> <b>Radial Seal I. Air</b> (Don. P527683)..... <b>RS3519</b>
Torino 1119/40 w/OM924LA (Euro III) Eng. (Mexico) <b>Lube</b> (A0001801609)..... <b>P7199</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A3844777015)..... <b>BF46071</b>	Torino 1419/47 w/OM924LA (Euro III) Eng. (Mexico) <b>Lube</b> (A0001801609)..... <b>P7199</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A9794770015)..... <b>BF46109-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b>	Torino OH 1519/47 w/OM924LA (EPA 04) Eng. (Mexico) <b>Lube</b> (A0001801609)..... <b>P7199</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A9794770015)..... <b>BF46109-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Radial Seal O. Air</b> (CA5626PU)..... <b>RS5627</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ Latin America Buses (cont'd)	MERCEDES-BENZ Latin America Buses (cont'd)	MERCEDES-BENZ Latin America Trucks (cont'd)
Torino OH 1519/47 w/OM924LA (EPA 04) Eng. (Mexico) (Cont'd) <b>Radial Seal I. Air</b> (CA5626SYPU)..... <b>RS5628</b> <b>Steering</b> (A0001842225)..... <b>P106-HD</b>	Torino OH 1623/52 w/OM906LA (EPA 04) Eng. (Mexico) (Cont'd) <b>Radial Seal I. Air</b> (Fram CA5626SYPU)..... <b>RS5628</b> <b>Steering</b> (A0001842225)..... <b>P106-HD</b>	1418 L/EL w/OM901LA Eng. (01/02-on) <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A3844777015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A3844777015)..... <b>BF46109-O</b>
Torino OH 1519/52 w/OM924LA (EPA 04) Eng. (Mexico) <b>Lube</b> (A0001801609)..... <b>P7199</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A9794770015)..... <b>BF46109-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Radial Seal O. Air</b> (CA5626PU)..... <b>RS5627</b> <b>Radial Seal I. Air</b> (CA5626SYPU)..... <b>RS5628</b> <b>Steering</b> (A0001842225)..... <b>P106-HD</b>	Torino 1623/58 w/OM906LA (EPA 04) Eng. (Mexico) <b>Lube</b> (A0001801709)..... <b>P7188</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A9794770015)..... <b>BF46109-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Radial Seal O. Air</b> (Standard) (Don. P527682)..... <b>RS3518</b> <b>Radial Seal XP O. Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b> <b>Radial Seal I. Air</b> (Don. P527683)..... <b>RS3519</b>	1420 w/OM366LA Eng. (01/02-on) <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A3844777015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A3844777015)..... <b>BF46109-O</b>
Torino OH 1523/52 w/OM906LA (EPA 04) Eng. (Mexico) <b>Lube</b> (A0001801609)..... <b>P7199</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A9794770015)..... <b>BF46109-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Radial Seal O. Air</b> (Fram CA5626PU)..... <b>RS5627</b> <b>Radial Seal I. Air</b> (Fram CA5626SYPU)..... <b>RS5628</b> <b>Steering</b> (A0001842225)..... <b>P106-HD</b>	1628 w/OM906 Eng. <b>Fuel/Water Separator</b> (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> <b>Fuel/Water Separator</b> (With Bowl) (Mann WK1060/1)..... <b>BF46072</b> <b>Fuel/Water Separator</b> (With Drain) (Mann WK1060/1)..... <b>BF1329</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b>	1620 L w/OM906LA Eng. (01/98-on) <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A3844777015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A3844777015)..... <b>BF46109-O</b>
Torino 1623/51L w/OM906LA (EPA 04) Eng. (Mexico) <b>Lube</b> (A0001801709)..... <b>P7188</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A9794770015)..... <b>BF46109-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Radial Seal O. Air</b> (Standard) (Don. P527682)..... <b>RS3518</b> <b>Radial Seal XP O. Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b> <b>Radial Seal I. Air</b> (Don. P527683)..... <b>RS3519</b>	1728 w/OM906LA Eng. <b>Fuel/Water Separator</b> (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> <b>Fuel/Water Separator</b> (With Bowl) (Mann WK1060/1)..... <b>BF46072</b> <b>Fuel/Water Separator</b> (With Drain) (Mann WK1060/1)..... <b>BF1329</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b>	1622 L w/OM924LA Eng. (01/01-on) <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A3844777015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A3844777015)..... <b>BF46109-O</b>
Torino OH 1623/52 w/OM906LA (EPA 04) Eng. (Mexico) <b>Lube</b> (A0001801609)..... <b>P7199</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A9794770015)..... <b>BF46109-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Radial Seal O. Air</b> (Fram CA5626PU)..... <b>RS5627</b>	<b>MERCEDES-BENZ Latin America Trucks</b> 1318 w/OM904LA Eng. (01/03-on) <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A3844777015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A3844777015)..... <b>BF46109-O</b>	1714 L w/OM366LA Eng. (01/96-on) <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A3844777015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A3844777015)..... <b>BF46109-O</b>
		1833-CP w/OM926 Eng. <b>Fuel/Water Separator</b> (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> <b>Fuel/Water Separator</b> (With Bowl) (Mann WK1060/1)..... <b>BF46072</b> <b>Fuel/Water Separator</b> (With Drain) (Mann WK1060/1)..... <b>BF1329</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A3844777015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A3844777015)..... <b>BF46109-O</b>
		FL-60 w/Cummins ISB Eng. <b>Fuel/Water Separator</b> (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> <b>Fuel/Water Separator</b> (With Bowl) (Mann WK1060/1)..... <b>BF46072</b> <b>Fuel/Water Separator</b> (With Drain) (Mann WK1060/1)..... <b>BF1329</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ Latin America Trucks (cont'd)	MERCEDES-BENZ Latin America Trucks (cont'd)	MERCEDES-BENZ Latin America Trucks (cont'd)
FL-60 w/Cummins ISB Eng. (Cont'd) <b>Fuel/Water Separator</b> (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A3844777015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A3844777015)..... <b>BF46109-O</b>	L-1200/39 w/OM904LA Eng. (Cont'd) <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A3844777015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A3844777015)..... <b>BF46109-O</b> L-1200/52 w/OM904LA Eng. <b>Fuel/Water Separator</b> (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> <b>Fuel/Water Separator</b> (With Bowl) (Mann WK1060/1)..... <b>BF46072</b> <b>Fuel/Water Separator</b> (With Drain) (Mann WK1060/1)..... <b>BF1329</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A3844777015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A3844777015)..... <b>BF46109-O</b> L-1400/52 w/OM904LA Eng. <b>Fuel/Water Separator</b> (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> <b>Fuel/Water Separator</b> (With Bowl) (Mann WK1060/1)..... <b>BF46072</b> <b>Fuel/Water Separator</b> (With Drain) (Mann WK1060/1)..... <b>BF1329</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A3844777015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A3844777015)..... <b>BF46109-O</b>	L-1400/59 w/OM904LA Eng. (Cont'd) <b>Fuel/Water Separator</b> (Open End for Bowl) (A3844777015)..... <b>BF46109-O</b> LK-1300/34 w/OM904LA Eng. <b>Fuel/Water Separator</b> (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> <b>Fuel/Water Separator</b> (With Bowl) (Mann WK1060/1)..... <b>BF46072</b> <b>Fuel/Water Separator</b> (With Drain) (Mann WK1060/1)..... <b>BF1329</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A3844777015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A3844777015)..... <b>BF46109-O</b> LK-1400/34 w/OM904LA Eng. <b>Fuel/Water Separator</b> (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> <b>Fuel/Water Separator</b> (With Bowl) (Mann WK1060/1)..... <b>BF46072</b> <b>Fuel/Water Separator</b> (With Drain) (Mann WK1060/1)..... <b>BF1329</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A3844777015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A3844777015)..... <b>BF46109-O</b>
FL-70 w/Cummins ISB Eng. <b>Fuel/Water Separator</b> (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> <b>Fuel/Water Separator</b> (With Bowl) (Mann WK1060/1)..... <b>BF46072</b> <b>Fuel/Water Separator</b> (With Drain) (Mann WK1060/1)..... <b>BF1329</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A3844777015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A3844777015)..... <b>BF46109-O</b>	L-1400/59 w/OM904LA Eng. <b>Fuel/Water Separator</b> (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> <b>Fuel/Water Separator</b> (With Bowl) (Mann WK1060/1)..... <b>BF46072</b> <b>Fuel/Water Separator</b> (With Drain) (Mann WK1060/1)..... <b>BF1329</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A3844777015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A3844777015)..... <b>BF46109-O</b>	<b>MERCEDES-BENZ</b> <b>South America Trucks, Buses, Vans</b> Models w/Mercedes OM 460 LA (Euro III) Eng. (Brazil) <b>Lube</b> (A0001802909)..... <b>P7230</b> Sprinter 208 CDI w/OM611 DE22LA Eng. <b>Lube</b> (A6111800009)..... <b>P1443</b> <b>Air</b> (A0040942604)..... <b>PA4600</b> <b>Cab Air</b> (w/o AirCond.) (A0008303318)..... <b>PA4489</b> <b>Cab Air</b> (w/AirCond.) (A9018300418)..... <b>PA4409</b> Sprinter 211 CDI w/OM611 DE22LA Eng. <b>Lube</b> (A6111800009)..... <b>P1443</b> <b>Air</b> (A0040942604)..... <b>PA4600</b> <b>Cab Air</b> (w/o AirCond.) (A0008303318)..... <b>PA4489</b> <b>Cab Air</b> (w/AirCond.) (A9018300418)..... <b>PA4409</b>
FL-80 w/Cummins ISC Eng. <b>Fuel/Water Separator</b> (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> <b>Fuel/Water Separator</b> (With Bowl) (Mann WK1060/1)..... <b>BF46072</b> <b>Fuel/Water Separator</b> (With Drain) (Mann WK1060/1)..... <b>BF1329</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A3844777015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A3844777015)..... <b>BF46109-O</b>	L-1200/39 w/OM904LA Eng. <b>Fuel/Water Separator</b> (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> <b>Fuel/Water Separator</b> (With Bowl) (Mann WK1060/1)..... <b>BF46072</b> <b>Fuel/Water Separator</b> (With Drain) (Mann WK1060/1)..... <b>BF1329</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A3844777015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A3844777015)..... <b>BF46109-O</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



MERCEDES-BENZ South America Trucks, Buses, Vans (cont'd)	MERCEDES-BENZ South America Trucks, Buses, Vans (cont'd)	MERCEDES-BENZ South America Trucks, Buses, Vans (cont'd)
Sprinter 213 CDI w/OM611 DE22LA Eng. <b>Lube</b> (A611800009)..... <b>P1443</b> <b>Air</b> (A0040942604)..... <b>PA4600</b> <b>Cab Air</b> (w/o AirCond.) (A0008303318)..... <b>PA4489</b> <b>Cab Air</b> (w/AirCond.) (A9018300418)..... <b>PA4409</b>	Sprinter 311 CDI w/OM611 DE22LA Eng. <b>Lube</b> (A611800009)..... <b>P1443</b> <b>Air</b> (A0040942604)..... <b>PA4600</b> <b>Cab Air</b> (w/o AirCond.) (A0008303318)..... <b>PA4489</b> <b>Cab Air</b> (w/AirCond.) (A9018300418)..... <b>PA4409</b> <b>Trans.</b> (A1402770095)..... <b>20048</b>	Sprinter 408 CDI w/OM 611 LA Eng. <b>Lube</b> (A611800009)..... <b>P1443</b> <b>Fuel/Water Separator</b> (A0004779415)..... <b>BF46026-O</b> <b>Fuel</b> (A6110920601)..... <b>BF7756</b> <b>Air</b> (w/Foam Pad) (A0030948304)..... <b>PA4601</b> <b>Air</b> (w/o Foam Pad) (A0040942604)..... <b>PA4600</b> <b>Air</b> (w/AirCond.) (A9018300418).. <b>PA4409</b> <b>Cab Air</b> (w/o AirCond.)..... <b>PA4489</b> (A0008303318)..... <b>PA4489</b> <b>Trans.</b> (1402770095)..... <b>20048</b>
Sprinter 214 w/M111 E23 Eng. <b>Lube</b> (A1041800109)..... <b>P1419</b> <b>Fuel</b> (A0024772701)..... <b>BF1195</b> <b>Air</b> (w/Foam Pad) (A0030948304)..... <b>PA4601</b> <b>Air</b> (w/o Foam Pad) (A0040942604)..... <b>PA4600</b> <b>Cab Air</b> (A0008303318)..... <b>PA4489</b>	Sprinter 311 CDI Chassis <b>115.9 mm Lube</b> (A611800009).. <b>P1443</b> <b>Fuel</b> (A6110920601)..... <b>BF7756</b> <b>Air</b> (A6900947004)..... <b>PA4601</b>	Sprinter 408 CDI w/OM611 DE22LA Eng. <b>Lube</b> (A611800009)..... <b>P1443</b> <b>Air</b> (A0040942604)..... <b>PA4600</b> <b>Cab Air</b> (w/o AirCond.) (A0008303318)..... <b>PA4489</b> <b>Cab Air</b> (w/AirCond.) (A9018300418)..... <b>PA4409</b> <b>Trans.</b> (A1402770095)..... <b>20048</b>
Sprinter 216 CDI w/OM612 DE27LA Eng. <b>Lube</b> (A611800009)..... <b>P1443</b> <b>Air</b> (A0040942604)..... <b>PA4600</b> <b>Cab Air</b> (w/o AirCond.) (A0008303318)..... <b>PA4489</b> <b>Cab Air</b> (w/AirCond.) (A9018300418)..... <b>PA4409</b>	Sprinter 311 CDI Passageiro <b>Lube</b> (A611800009)..... <b>P1443</b>	Sprinter 411 CDI w/OM 612 DE LA Eng. <b>Lube</b> (A611800009)..... <b>P1443</b> <b>Fuel/Water Separator</b> (A0004779415)..... <b>BF46026-O</b>
Sprinter 308 CDI w/OM 611 LA (Euro III) Eng. <b>Lube</b> (A611800009)..... <b>P1443</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A0004779415)..... <b>BF46026-O</b> <b>Fuel</b> (A6110920601)..... <b>BF7756</b> <b>Air</b> (w/Foam Pad) (A0030948304)..... <b>PA4601</b> <b>Air</b> (w/o Foam Pad) (A0040942604)..... <b>PA4600</b> <b>Cab Air</b> (w/AirCond.) (A9018300418)..... <b>PA4409</b>	Sprinter 311 CDI Furgao <b>Lube</b> (A611800009)..... <b>P1443</b>	Sprinter 411 CDI w/OM 612 DE LA Eng. <b>Lube</b> (A611800009)..... <b>P1443</b> <b>Fuel/Water Separator</b> (A6120920001)..... <b>BF7778</b> <b>Fuel</b> (A6110920601)..... <b>BF7756</b> <b>Air</b> (w/Foam Pad) (A0030948304)..... <b>PA4601</b> <b>Air</b> (w/o Foam Pad) (A0040942604)..... <b>PA4600</b> <b>Cab Air</b> (w/o AirCond.) (A0008303318)..... <b>PA4489</b> <b>Cab Air</b> (w/AirCond.) (A9018300418)..... <b>PA4409</b> <b>Trans.</b> (A1402770095)..... <b>20048</b>
Sprinter 308 CDI w/OM611 DE22LA Eng. <b>Lube</b> (A611800009)..... <b>P1443</b> <b>Air</b> (A0040942604)..... <b>PA4600</b> <b>Cab Air</b> (w/o AirCond.) (A0008303318)..... <b>PA4489</b> <b>Cab Air</b> (w/AirCond.) (A9018300418)..... <b>PA4409</b> <b>Trans.</b> (A1402770095)..... <b>20048</b>	Sprinter 312D w/OM 602 DE LA Eng. <b>Lube</b> (A6061800009)..... <b>P7196</b> <b>Fuel</b> (A6010901552)..... <b>BF7619</b> <b>Air</b> (A0040942604)..... <b>PA4600</b> <b>Cab Air</b> (w/o AirCond.) (A0008303318)..... <b>PA4489</b> <b>Cab Air</b> (w/AirCond.) (A9018300418)..... <b>PA4409</b>	Sprinter 412D Chassis w/OM 612 DE LA Eng. <b>Lube</b> (A6061800009)..... <b>P7196</b> <b>Fuel</b> (A6010901552)..... <b>BF7619</b> <b>Air</b> (w/Foam Pad) (A0030948304)..... <b>PA4601</b> <b>Air</b> (w/o Foam Pad) (A0040942604)..... <b>PA4600</b> <b>Cab Air</b> (w/o AirCond.) (A0008303318)..... <b>PA4489</b> <b>Cab Air</b> (w/AirCond.) (A9018300418)..... <b>PA4409</b>
Sprinter 308 CDI w/OM611 DE22LA Eng. <b>Lube</b> (A611800009)..... <b>P1443</b> <b>Air</b> (A0040942604)..... <b>PA4600</b> <b>Cab Air</b> (w/o AirCond.) (A0008303318)..... <b>PA4489</b> <b>Cab Air</b> (w/AirCond.) (A9018300418)..... <b>PA4409</b> <b>Trans.</b> (A1402770095)..... <b>20048</b>	Sprinter 313 CDI w/OM 611 LA (Euro III) Eng. <b>Lube</b> (A611800009)..... <b>P1443</b> <b>Fuel/Water Separator</b> (A0004779415)..... <b>BF46026-O</b> <b>Fuel</b> (A6110920601)..... <b>BF7756</b> <b>Air</b> (w/Foam Pad) (A0030948304)..... <b>PA4601</b> <b>Air</b> (w/o Foam Pad) (A0040942604)..... <b>PA4600</b> <b>Cab Air</b> (w/o AirCond.) (A0008303318)..... <b>PA4489</b> <b>Cab Air</b> (w/AirCond.) (A9018300418)..... <b>PA4409</b> <b>Trans.</b> (A1402770095)..... <b>20048</b>	Sprinter 412D Chassis w/OM 612 DE LA Eng. <b>Lube</b> (A6061800009)..... <b>P7196</b> <b>Fuel</b> (A6010901552)..... <b>BF7619</b> <b>Air</b> (w/Foam Pad) (A0030948304)..... <b>PA4601</b> <b>Air</b> (w/o Foam Pad) (A0040942604)..... <b>PA4600</b> <b>Cab Air</b> (w/o AirCond.) (A0008303318)..... <b>PA4489</b> <b>Cab Air</b> (w/AirCond.) (A9018300418)..... <b>PA4409</b>
Sprinter Furgon 308 CDI w/OM611 LA (Euro III) Eng. <b>Lube</b> (A611800009)..... <b>P1443</b> <b>Air</b> (A0040942604)..... <b>PA4600</b> <b>Cab Air</b> (w/o AirCond.) (A0008303318)..... <b>PA4489</b> <b>Cab Air</b> (w/AirCond.) (A9018300418)..... <b>PA4409</b> <b>Trans.</b> (A1402770095)..... <b>20048</b>	Sprinter 314 w/M111 E23 Eng. <b>Lube</b> (A1041800109)..... <b>P1419</b> <b>Fuel</b> (A0024772701)..... <b>BF1195</b> <b>Air</b> (w/Foam Pad) (A0030948304)..... <b>PA4601</b> <b>Air</b> (w/o Foam Pad) (A0040942604)..... <b>PA4600</b> <b>Cab Air</b> (A0008303318)..... <b>PA4489</b>	
Sprinter 311 CDI w/OM611 Eng. <b>Lube</b> (A611800009)..... <b>P1443</b> <b>Cab Air</b> (w/o AirCond.) (A0008303318)..... <b>PA4489</b> <b>Cab Air</b> (w/AirCond.) (A9018300418)..... <b>PA4409</b>	Sprinter 316 CDI w/OM612 DE27LA Eng. <b>Lube</b> (A611800009)..... <b>P1443</b> <b>Air</b> (A0040942604)..... <b>PA4600</b> <b>Cab Air</b> (w/o AirCond.) (A0008303318)..... <b>PA4489</b> <b>Cab Air</b> (w/AirCond.) (A9018300418)..... <b>PA4409</b> <b>Trans.</b> (A1402770095)..... <b>20048</b>	

Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>MERCEDES-BENZ</b> South America Trucks, Buses, Vans (cont'd)	<b>MERCEDES-BENZ</b> South America Trucks, Buses, Vans (cont'd)	<b>MERCEDES-BENZ</b> South America Trucks, Buses, Vans (cont'd)
Sprinter 413 CDI w/OM 611 LA (Euro III) Eng. Lube (A6111800009)..... P1443 Fuel (A6110920601)..... BF7756 Cab Air (w/o AirCond.) (A0008303318)..... PA4489 Cab Air (w/AirCond.) (A9018300418)..... PA4409	710 w/OM364 Eng. (Argentina) (Cont'd) Fuel/Water Separator (w/Male Thread for Bowl) (A9584770115).. BF46123-O Fuel (A3524700092)..... [2] F834-F Steering (A0004660604)..... P106-HD	914 C w/OM 904 LA Eng. (Cont'd) Fuel/Water Separator (w/Undetachable Bowl) (A9584770115)..... BF46071 Fuel (A0000901551)..... PF7735 Radial Seal O. Air (A3740947104)..... RS5452 Radial Seal I. Air (A3740947204)..... RS5453 Steering (A0001842225)..... P106-HD
Sprinter 413 CDI w/OM611 DE22LA Eng. Lube (A6111800009)..... P1443 Air (A0040942604)..... PA4600 Cab Air (w/o AirCond.) (A0008303318)..... PA4489 Cab Air (w/AirCond.) (A9018300418)..... PA4409 Trans. (A1402770095)..... 20048	710 Plus w/OM-364 LA (Euro III) Eng. Radial Seal Air (A3740947104)... RS5452	Accelo 915 C w/Mercedes OM 904 LA (Euro III) Eng. Lube (A0001801609)..... P7199 Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363 Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O Fuel/Water Separator (w/Male Thread for Bowl) (A9584770115).. BF46123-O Fuel/Water Separator (w/Undetachable Bowl) (A9794770015)..... BF46071 Fuel/Water Separator (w/Female Thread for Bowl) (A9794770015).. BF46109-O Fuel (A0000901551)..... PF7735 Radial Seal Air (A3740947104)... RS5452
Sprinter 414 w/M111 E23 Eng. Lube (A1041800109)..... P1419 Fuel (A0024772701)..... BF1195 Air (w/Foam Pad) (A0030948304)..... PA4601 Air (w/o Foam Pad) (A0040942604)..... PA4600 Cab Air (A0008303318)..... PA4489	712 w/OM 364 A Eng. Fuel (A0000901551)..... PF7735 Fuel (A3524700092)..... [2] F834-F Air (A0030943304)..... PA2845 Steering (A0004660604)..... P106-HD	1114 w/OM 364 LA Eng. Fuel (A3444700092)..... F834-F Steering (A0004660604)..... P106-HD
Sprinter 416 CDI w/OM612 DE27LA Eng. Lube (A6111800009)..... P1443 Fuel/Water Separator (A0004779415)..... BF46026-O Fuel/Water Separator (A6120920001)..... BF7778 Fuel (A6110920601)..... BF7756 Air (A0040942604)..... PA4600 Cab Air (w/o AirCond.) (A0008303318)..... PA4489 Cab Air (w/AirCond.) (A9018300418)..... PA4409 Trans. (A1402770095)..... 20048	Chassi 712 E w/OM 364 LA (Euro III) Eng. Steering (A0004660604)..... P106-HD	1115 OF L w/OM904LA Eng. (01/00-on) Fuel/Water Separator (w/Undetachable Bowl) (A3844777015)..... BF46071 Fuel/Water Separator (Open End for Bowl) (A3844777015)..... BF46109-O
Sprinter 416 CDI w/OM612 DE27LA Eng. Lube (A6111800009)..... P1443 Fuel/Water Separator (A0004779415)..... BF46026-O Fuel/Water Separator (A6120920001)..... BF7778 Fuel (A6110920601)..... BF7756 Air (A0040942604)..... PA4600 Cab Air (w/o AirCond.) (A0008303318)..... PA4489 Cab Air (w/AirCond.) (A9018300418)..... PA4409 Trans. (A1402770095)..... 20048	Accelo 715 w/OM 612 Eng. Fuel (A6110920601)..... BF7756 Radial Seal Air (3740947104).... RS5452	1115 OF SB w/OM904LA Eng. (01/00-on) Fuel/Water Separator (w/Undetachable Bowl) (A3844777015)..... BF46071 Fuel/Water Separator (Open End for Bowl) (A3844777015)..... BF46109-O
Sprinter 616 CDI w/OM612 DE27LA Eng. Lube (A6111800009)..... P1443 Fuel/Water Separator (A6120920001)..... BF7778 Fuel (A6110920601)..... BF7756 Air (A0040942604)..... PA4600 Cab Air (w/o AirCond.) (A0008303318)..... PA4489 Cab Air (w/AirCond.) (A9018300418)..... PA4409 Trans. (A1402770095)..... 20048	912 w/OM 364 A Eng. Fuel (A3444700092)..... F834-F Steering (A0004660604)..... P106-HD	Atego 1214 w/OM 904 LA (Euro III) Eng. Lube (A0001801609)..... P7199 Fuel/Water Separator (w/Undetachable Bowl) (A9794770015)..... BF46071 Fuel/Water Separator (w/Male Thread for Bowl) (A9584770115).. BF46123-O Fuel/Water Separator (w/Female Thread for Bowl) (A9794770015).. BF46109-O Fuel (A0000901551)..... PF7735 Radial Seal Air (A3740947104)... RS5452 Air Dryer (Knorr System) (A0004300969)..... BA5374 + Steering (A0001842225)..... P106-HD
Chassi 500M Air (6345280306)..... RS5627	912 C w/OM904LA Eng. (01/00-on) Fuel/Water Separator (w/Undetachable Bowl) (A3844777015)..... BF46071 Fuel/Water Separator (Open End for Bowl) (A3844777015)..... BF46109-O	
709 w/OM 354 (Euro III) Eng. Fuel (A0000901151)..... F834-F	914 w/OM 364 LA Eng. Fuel (A3444700092)..... F834-F Steering (A0004660604)..... P106-HD	
710 w/OM364 Eng. (Argentina) Lube (A3661840225)..... P7017 Fuel/Water Separator (w/Undetachable Bowl) (A9584770115)..... BF46071	914 C w/OM 904 LA Eng. Lube (A0001801609)..... P7199 Fuel/Water Separator (w/Female Thread for Bowl) (A3844777015).. BF46109-O Fuel/Water Separator (w/Male Thread for Bowl) (A9584770115).. BF46123-O	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ South America Trucks, Buses, Vans (cont'd)	MERCEDES-BENZ South America Trucks, Buses, Vans (cont'd)	MERCEDES-BENZ South America Trucks, Buses, Vans (cont'd)
1214 C w/OM 364 LA Eng. <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0001842225)..... <b>P106-HD</b>	1318 w/OM 904 LA Eng. <b>Lube</b> (A0001801609)..... <b>P7199</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9584770115)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A3844777015).. <b>BF46109-O</b> <b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b> <b>103.2 mm Fuel</b> (A0000901551).... <b>PF7735</b> <b>201.6 mm Fuel</b> (A5410900151).... <b>PF7761</b> <b>Radial Seal Air</b> (A3740947104)... <b>RS5452</b> <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0001842225)..... <b>P106-HD</b>	Atego 1518 w/OM 904 LA (Euro III) Eng. <b>Lube</b> (A0001801609)..... <b>P7199</b> <b>Fuel/Water Separator</b> (w/Drain) (A0004771302)..... <b>BF1363</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A9794770015).. <b>BF46109-O</b> <b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Radial Seal Air</b> (To identification number: D510809) (A0030949604)..... <b>RS5342</b> <b>Cab Air</b> (A9738350147)..... <b>PA5340</b> <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0004660204)..... <b>P106-HD</b>
1215 C w/OM 904 LA Eng. <b>Lube</b> (A0001801609)..... <b>P7199</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A3844777015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A3844777015)..... <b>BF46109-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Radial Seal Air</b> (A3740947104)... <b>RS5452</b> <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0001842225)..... <b>P106-HD</b>	1414 w/OM 366 Eng. <b>Fuel</b> (A3524700092)..... <b>[2] F834-F</b> <b>Steering</b> (A0004660604)..... <b>P106-HD</b>	1614 L/LK w/OM366 Eng. (01/89-on) <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A3844777015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A3844777015)..... <b>BF46109-O</b>
1218 w/OM366A Eng. <b>Fuel</b> (A3524700092)..... <b>[2] F834-F</b> <b>Air</b> (A0010945204)..... <b>PA2405</b>	1417 OF-Electronico w/OM904L/LA Eng. (01/98-on) <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A3844777015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A3844777015)..... <b>BF46109-O</b>	Atego 1618 w/OM 904 LA (Euro III) Eng. <b>Lube</b> (A0001801609)..... <b>P7199</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A9794770015).. <b>BF46109-O</b> <b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Radial Seal Air</b> (A3740947104)... <b>RS5452</b> <b>Air Dryer</b> (Non-Wabco System) (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0001842225)..... <b>P106-HD</b>
1218 L w/OM904LA Eng. (01/98-on) <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A3844777015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A3844777015)..... <b>BF46109-O</b>	Atego 1418 w/OM-904 LA (Euro III) Eng. <b>Lube</b> (A0001801609)..... <b>P7199</b> <b>Fuel/Water Separator</b> (w/Drain) (A0004771302)..... <b>BF1363</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A9794770015).. <b>BF46109-O</b> <b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Radial Seal Air</b> (To identification number: D510809) (A0030949604)..... <b>RS5342</b> <b>Cab Air</b> (A9738350147)..... <b>PA5340</b> <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0004660204)..... <b>P106-HD</b>	1618M <b>Lube</b> (A0001801609)..... <b>P7199</b> <b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A3844777015).. <b>BF46109-O</b> <b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9584770115)..... <b>BF46071</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Radial Seal Air</b> (A3740947104)... <b>RS5452</b> <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0001842225)..... <b>P106-HD</b>
1218 LK Electronico w/OM904LA Eng. (01/98-on) <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A3844777015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A3844777015)..... <b>BF46109-O</b>	1418 L/EL w/OM904LA Eng. (01/02-on) <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A3844777015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A3844777015)..... <b>BF46109-O</b>	1620 L w/OM906LA Eng. (01/98-on) <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A3844777015)..... <b>BF46071</b>
Atego 1315 w/OM 904 LA (Euro III) Eng. <b>Lube</b> (A0001801609)..... <b>P7199</b> <b>Fuel/Water Separator</b> (w/Drain) (A0004771302)..... <b>BF1363</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b> <b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A9794770015).. <b>BF46109-O</b> <b>Opt. Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Radial Seal Air</b> (To identification number: D510809) (A0030949604)..... <b>RS5342</b> <b>Cab Air</b> (Special vehicles require Qty. 2) (A9738350147)..... <b>PA5340</b> <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0004662804)..... <b>P106-HD</b>	1418 R w/OM 366 LA Eng. <b>Fuel</b> (A3524700092)..... <b>[2] F834-F</b> <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0001842225)..... <b>P106-HD</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>MERCEDES-BENZ</b> South America Trucks, Buses, Vans (cont'd)	<b>MERCEDES-BENZ</b> South America Trucks, Buses, Vans (cont'd)	<b>MERCEDES-BENZ</b> South America Trucks, Buses, Vans (cont'd)
1620 L w/OM906LA Eng. (01/98-on) (Cont'd) <b>Fuel/Water Separator</b> (Open End for Bowl) (A3844777015)..... <b>BF46109-O</b>	1718 A w/OM 366 A Eng. <b>Fuel</b> (A3524700092)..... <b>[2] F834-F</b> <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0001842225)..... <b>P106-HD</b>	Atego 1725 w/OM-906 LA (Euro III) Eng. (Cont'd) <b>Fuel/Water Separator</b> (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A9794770015).. <b>BF46109-O</b> <b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Radial Seal Air</b> (To identification number: D510809) (A0030949604)..... <b>RS5342</b> <b>Cab Air</b> (Special vehicles require Qty. 2) (A9738350147)..... <b>PA5340</b> <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0004660204)..... <b>P106-HD</b> <b>Urea</b> (A0001420289)..... <b>PE5272</b>
1622 L w/OM924LA Eng. (01/01-on) <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A3844777015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A3844777015)..... <b>BF46109-O</b>	1718 K w/OM 366 A Eng. <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0001842225)..... <b>P106-HD</b>	Atego 1725A w/OM 904 LA (Euro III) Eng. <b>Lube</b> (A0001801609)..... <b>P7199</b> <b>Fuel/Water Separator</b> (w/Drain) (A0004771302)..... <b>BF1363</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A9794770015).. <b>BF46109-O</b> <b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Radial Seal Air</b> (To identification number: D510809) (A0030949604)..... <b>RS5342</b> <b>Cab Air</b> (A9738350147)..... <b>PA5340</b> <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0004660204)..... <b>P106-HD</b>
1623 L w/OM906L/LA Eng. (01/98-on) <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A3844777015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A3844777015)..... <b>BF46109-O</b>	1720 w/OM 366 LA II Eng. <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0001842225)..... <b>P106-HD</b>	Atego 1725 A 4x4 w/OM 906 LA (Euro III) Eng. <b>Lube</b> (A0001801709)..... <b>P7188</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A9794770015).. <b>BF46109-O</b> <b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Radial Seal Air</b> (A0030949604)..... <b>RS5342</b> <b>Cab Air</b> (Special vehicles require Qty. 2) (A9738350147)..... <b>PA5340</b> <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0004660204)..... <b>P106-HD</b> <b>Urea</b> (A0001420289)..... <b>PE5272</b>
1624 L w/OM906LA Eng. (01/01-on) <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A3844777015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A3844777015)..... <b>BF46109-O</b>	1720A w/OM 366 LA II Eng. <b>Fuel</b> (A3524700092)..... <b>[2] F834-F</b> <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b>	
1714 w/OM366 Eng. <b>Fuel</b> (A3444700092)..... <b>F834-F</b> <b>Fuel</b> (A3524700092)..... <b>[2] F834-F</b> <b>Air</b> (A0010945204)..... <b>PA2405</b> <b>Steering</b> (A0004660604)..... <b>P106-HD</b>	1720K w/OM 366 LA II Eng. <b>Fuel</b> (A3524700092)..... <b>[2] F834-F</b> <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0001842225)..... <b>P106-HD</b>	
1714 K <b>Fuel</b> (A3524700092)..... <b>[2] F834-F</b> <b>Fuel</b> (A3444700092)..... <b>F834-F</b> <b>Air</b> (A0010945204)..... <b>PA2405</b> <b>Steering</b> (A0004660604)..... <b>P106-HD</b>	1721 w/OM 366 LA Eng. <b>Fuel/Water Separator</b> (A3820927005)..... <b>BF9922-O</b> <b>Fuel</b> (A3444700092)..... <b>[2] F834-F</b> <b>Air</b> (A0010945204)..... <b>PA2405</b> <b>Steering</b> (A0004660604)..... <b>P106-HD</b>	
Atego 1718 w/OM-904 LA (Euro III) Eng. <b>Lube</b> (A0001801609)..... <b>P7199</b> <b>Fuel/Water Separator</b> (w/Drain) (A0004771302)..... <b>BF1363</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A9794770015).. <b>BF46109-O</b> <b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b> <b>103.2 mm Fuel</b> (A0000901551).... <b>PF7735</b> <b>Radial Seal Air</b> (To identification number: D510809) (A0030949604)..... <b>RS5342</b> <b>Cab Air</b> (Special vehicles require Qty. 2) (A9738350147)..... <b>PA5340</b> <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0004660204)..... <b>P106-HD</b> <b>Urea</b> (A0001420289)..... <b>PE5272</b>	1721 OF Electronico w/OM906LA Eng. (01/98-on) <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A3844777015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A3844777015)..... <b>BF46109-O</b>	
	1721S w/OM 366 LA Eng. <b>Fuel/Water Separator</b> (A3820927005)..... <b>BF9922-O</b> <b>Fuel</b> (A3444700092)..... <b>[2] F834-F</b> <b>Air</b> (A0010945204)..... <b>PA2405</b> <b>Steering</b> (A0004660604)..... <b>P106-HD</b>	
	1723 w/OM 366 LA Eng. <b>Fuel</b> (A3524700092)..... <b>[2] F834-F</b> <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0001842225)..... <b>P106-HD</b>	
	1723 L w/OM906LA Eng. (01/98-on) <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A3844777015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A3844777015)..... <b>BF46109-O</b>	
	1723S w/OM 366 LA Eng. <b>Fuel</b> (A3524700092)..... <b>[2] F834-F</b> <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0001842225)..... <b>P106-HD</b>	
	Atego 1725 w/OM-906 LA (Euro III) Eng. <b>Lube</b> (A0001801709)..... <b>P7188</b> <b>Fuel/Water Separator</b> (w/Drain) (A0004771302)..... <b>BF1363</b>	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).


MERCEDES-BENZ South America Trucks, Buses, Vans (cont'd)	MERCEDES-BENZ South America Trucks, Buses, Vans (cont'd)	MERCEDES-BENZ South America Trucks, Buses, Vans (cont'd)
Atego 1728 w/OM-926 LA (Euro III) Eng. 212.7 mm Lube (A0001801709).. P7188 Lube (A0001842225)..... P106-HD Fuel/Water Separator (w/Undetachable Bowl) (A9584770115)..... BF46071 Fuel/Water Separator (w/Female Thread for Bowl) (A384477015).. BF46109-O Fuel/Water Separator (w/Male Thread for Bowl) (A9584770115).. BF46123-O Fuel (A0000901551)..... PF7735 Air Dryer (A0004300969)..... BA5374 +	1938 w/OM 457 LA Eng. (Cont'd) Radial Seal Air (A4760940004)... RS5358 Radial Seal I. Air (A4760940104)..... RS5549 Cab Air (A9408350047)..... PA4945 Air Dryer (A0004300969)..... BA5374 + Steering (A0004660204)..... P106-HD 1938S w/OM 457 LA Eng. Lube (A4571800009)..... P7192 Fuel/Water Separator (Open End for Bowl) (A4570920001)..... BF1360-O Fuel/Water Separator (w/Drain) (A4570920001)..... BF1360 Fuel/Water Separator (w/Undetachable Bowl) (A9584770115)..... BF46071 Fuel/Water Separator (w/Female Thread for Bowl) (A384477015).. BF46109-O Fuel/Water Separator (w/Male Thread for Bowl) (A9584770115).. BF46123-O Fuel/Water Separator (w/Sensor Port) (A4570920001)..... BF1360-SP Fuel (A5410900151)..... PF7761 Radial Seal O. Air (4760940004).. RS5358 Radial Seal I. Air (A4760940104)..... RS5549 Cab Air (A9408350047)..... PA4945 Air Dryer (A0004300969)..... BA5374 + Steering (A0004660204)..... P106-HD 1944S Lube (A4571800009)..... P7192 Fuel/Water Separator (Open End for Bowl) (A4570920001)..... BF1360-O Fuel/Water Separator (w/Drain) (A4570920001)..... BF1360 Fuel/Water Separator (w/Undetachable Bowl) (A9584770115)..... BF46071 Fuel/Water Separator (w/Female Thread for Bowl) (A384477015).. BF46109-O Fuel/Water Separator (w/Male Thread for Bowl) (A9584770115).. BF46123-O Fuel/Water Separator (w/Sensor Port) (A4570920001)..... BF1360-SP Fuel (A5410900151)..... PF7761 Radial Seal O. Air (4760940004).. RS5358 Radial Seal I. Air (A4760940104)..... RS5549 Cab Air (A9408350047)..... PA4945 Air Dryer (A0004300969)..... BA5374 + Steering (A0004660204)..... P106-HD	Axor 2035 w/OM 457 LA (Euro III) Eng. (Cont'd) Radial Seal O. Air (A0040943504)..... RS5358 Radial Seal I. Air (A4760940104)..... RS5549 Cab Air (A9408350047)..... PA4945 Air Dryer (A0004300969)..... BA5374 + Steering (A0004660204)..... P106-HD Urea (A0001420289)..... PE5272 Axor 2035 S w/OM 457 LA Eng. Lube (A0001802909)..... P7230 Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363 Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O Fuel/Water Separator (w/Undetachable Bowl) (A9794770015)..... BF46071 Fuel/Water Separator (w/Female Thread for Bowl) (A9794770015).. BF46109-O Fuel/Water Separator (w/Male Thread for Bowl) (A9584770115).. BF46123-O Fuel (A4570900051)..... PF7761 Radial Seal O. Air (A0040943504)..... RS5358 Radial Seal I. Air (A4760940104)..... RS5549 Cab Air (A9408350047)..... PA4945 Air Dryer (A0004300969)..... BA5374 + Steering (A0004660204)..... P106-HD Urea (A0001420289)..... PE5272 Axor 2040 w/OM 457 LA (Euro III) Eng. Lube (A0001802909)..... P7230 Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363 Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O Fuel/Water Separator (w/Undetachable Bowl) (A9794770015)..... BF46071 Fuel/Water Separator (w/Female Thread for Bowl) (A9794770015).. BF46109-O Fuel/Water Separator (w/Male Thread for Bowl) (A9584770115).. BF46123-O Fuel (A5410900151)..... PF7761 Radial Seal O. Air (A0040943504)..... RS5358 Radial Seal I. Air (A4760940104)..... RS5549 Cab Air (A9408350047)..... PA4945 Air Dryer (A0004300969)..... BA5374 + Steering (A0004660204)..... P106-HD Urea (A0001420289)..... PE5272 Axor 2040 S w/OM 457 LA (Euro V) Eng. Lube (A0001802909)..... P7230 Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363
1728 S w/OM-926 LA (Euro V) Eng. Lube (A0001801709)..... P7188 Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363 Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O Fuel/Water Separator (w/Undetachable Bowl) (A9794770015)..... BF46071 Fuel/Water Separator (w/Female Thread for Bowl) (A9794770015).. BF46109-O Fuel/Water Separator (w/Male Thread for Bowl) (A9584770115).. BF46123-O Fuel (A0000901551)..... PF7735 Radial Seal Air (To identification # D 510809) (A0030949604)..... RS5342 Cab Air (Special vehicles require Qty. 2) (A9738350147)..... PA5340 Air Dryer (A0004300969)..... BA5374 + Steering (A0004660204)..... P106-HD Urea (A0001420289)..... PE5272	Axor 1933 w/OM-926 LA (Euro III) Eng. Lube (A0001801709)..... P7188 Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363 Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O Fuel (A0000901551)..... PF7735 Radial Seal Air (A0030949604)... RS5342 Cab Air (A9408350047)..... PA4945 Air Dryer (A0004300969)..... BA5374 + Steering (A0004660204)..... P106-HD	
1938 w/OM 457 LA Eng. Lube (A4571800009)..... P7192 Fuel/Water Separator (w/Undetachable Bowl) (A9584770115)..... BF46071 Fuel/Water Separator (Open End for Bowl) (A4570920001)..... BF1360-O Fuel/Water Separator (w/Drain) (A4570920001)..... BF1360 Fuel/Water Separator (w/Sensor Port) (A4570920001)..... BF1360-SP Fuel (A4570920001)..... BF1360 Fuel/Water Separator (w/Male Thread for Bowl) (A9584770115).. BF46123-O Fuel (A4570900051)..... PF7761	Axor 2035 w/OM 457 LA (Euro III) Eng. Lube (A0001802909)..... P7230 Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363 Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>MERCEDES-BENZ</b> South America Trucks, Buses, Vans (cont'd)	<b>MERCEDES-BENZ</b> South America Trucks, Buses, Vans (cont'd)	<b>MERCEDES-BENZ</b> South America Trucks, Buses, Vans (cont'd)
Axor 2040 S w/OM 457 LA (Euro V) Eng. (Cont'd) <b>Fuel/Water Separator</b> (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A9794770015).. <b>BF46109-O</b> <b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b> <b>Fuel</b> (A4570900051)..... <b>PF7761</b> <b>Radial Seal O. Air</b> (A0040943504)..... <b>RS5358</b> <b>Radial Seal I. Air</b> (A4760940104)..... <b>RS5549</b> <b>Cab Air</b> (A9408350047)..... <b>PA4945</b> <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0004660204)..... <b>P106-HD</b>	2423 K w/OM 906 LA (Euro III) Eng. <b>Lube</b> (A0001801709)..... <b>P7188</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9584770115)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A384477015).. <b>BF46109-O</b> <b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Radial Seal I. Air</b> (A3760948004)..... <b>RS5628</b> <b>Air Dryer</b> (Knorr System) (A0004300969)..... <b>BA5374 +</b> <b>Air Dryer</b> (Wabco System) (A0004293395)..... <b>BA5374 +</b> <b>Steering</b> (A0001842225)..... <b>P106-HD</b>	Atego 2425 6x2 w/OM-906 LA (Euro III) Eng. (Cont'd) <b>Urea</b> (A0001420289)..... <b>PE5272</b>
Axor 2044 w/Mercedes OM 457 LA (Euro III) Eng. <b>Lube</b> (A0001802909)..... <b>P7230</b> <b>Fuel/Water Separator</b> (w/Drain) (A0004771302)..... <b>BF1363</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A9794770015).. <b>BF46109-O</b> <b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b> <b>Radial Seal O. Air</b> (A0040943504)..... <b>RS5358</b> <b>Radial Seal I. Air</b> (A4760940104)..... <b>RS5549</b> <b>Cab Air</b> (A9408350047)..... <b>PA4945</b> <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0004660204)..... <b>P106-HD</b> <b>Urea</b> (A0001420289)..... <b>PE5272</b>	Atego 2425 w/OM-906 LA (Euro III) Eng. <b>Lube</b> (A0001801709)..... <b>P7188</b> <b>Fuel/Water Separator</b> (w/Drain) (A0004771302)..... <b>BF1363</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A9794770015).. <b>BF46109-O</b> <b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Radial Seal Air</b> (To identification # D 510809) (A0030949604)..... <b>RS5342</b> <b>Cab Air</b> (Special vehicles require Qty. 2) (A9738350147)..... <b>PA5340</b> <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0004660204)..... <b>P106-HD</b> <b>Urea</b> (A0001420289)..... <b>PE5272</b>	Atego 2428 w/OM-926 LA (Euro III) Eng. <b>Lube</b> (A0001801709)..... <b>P7188</b> <b>Fuel/Water Separator</b> (w/Drain) (A0004771302)..... <b>BF1363</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A9794770015).. <b>BF46109-O</b> <b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Radial Seal Air</b> (To identification number: D510809) (A0030949604)..... <b>RS5342</b> <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0004660204)..... <b>P106-HD</b>
Axor 2044 S <b>Lube</b> (A0001802909)..... <b>P7230</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A9794770015)..... <b>BF46109-O</b> <b>Fuel/Water Separator</b> (w/Bowl) (A9794770015)..... <b>BF46071</b> <b>201.6 mm Fuel</b> (A5410900151).... <b>PF7761</b> <b>Radial Seal Air</b> (A0040943504)... <b>RS5358</b>	Atego 2425 6x2 w/OM-906 LA (Euro III) Eng. <b>Lube</b> (A0001801709)..... <b>P7188</b> <b>Fuel/Water Separator</b> (w/Drain) (A0004771302)..... <b>BF1363</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A9794770015).. <b>BF46109-O</b> <b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Radial Seal Air</b> (To identification # D 510809) (A0030949604)..... <b>RS5342</b> <b>Cab Air</b> (Special vehicles require Qty. 2) (A9738350147)..... <b>PA5340</b> <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0004660204)..... <b>P106-HD</b>	Axor 2533 w/OM 926 LA (Euro III) Eng. <b>Lube</b> (A0001801709)..... <b>P7188</b> <b>Fuel/Water Separator</b> (w/Drain) (A0004771302)..... <b>BF1363</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A9794770015).. <b>BF46109-O</b> <b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Radial Seal Air</b> (A0030949604)... <b>RS5342</b> <b>Cab Air</b> (A9408350047)..... <b>PA4945</b> <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0004660204)..... <b>P106-HD</b> <b>Urea</b> (A0001420289)..... <b>PE5272</b>
2418 w/OM 366 A Eng. <b>Fuel/Water Separator</b> (A3820927005)..... <b>BF9922-O</b> <b>Fuel</b> (A3444700092)..... <b>[2] F834-F</b> <b>Air</b> (A0010945204)..... <b>PA2405</b> <b>Steering</b> (A0004660604)..... <b>P106-HD</b>	Axor 2535 w/OM-457 LA (Euro III) Eng. <b>Lube</b> (A0001802909)..... <b>P7230</b> <b>Fuel/Water Separator</b> (w/Drain) (A0004771302)..... <b>BF1363</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A9794770015).. <b>BF46109-O</b> <b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b> <b>Fuel</b> (A4570900051)..... <b>PF7761</b> <b>Radial Seal O. Air</b> (A0040943504)..... <b>RS5358</b>	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ South America Trucks, Buses, Vans (cont'd)	MERCEDES-BENZ South America Trucks, Buses, Vans (cont'd)	MERCEDES-BENZ South America Trucks, Buses, Vans (cont'd)
Axor 2535 w/OM-457 LA (Euro III) Eng. (Cont'd)	2638 L w/OM457LA Eng. (01/99-on)	Axor 2640 S w/OM 502 LA Eng. (Cont'd)
<b>Radial Seal I. Air</b> (A4760940104)..... <b>RS5549</b>	<b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A3844777015)..... <b>BF46071</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b>
<b>Cab Air</b> (A9408350047)..... <b>PA4945</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (A3844777015)..... <b>BF46109-O</b>	<b>Fuel/Water Separator</b> (A0004771702)..... <b>BF46105-O</b>
<b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b>	2638 LS w/OM447LA Eng. (To 12/97)	<b>Air</b> (A0040946604)..... <b>PA5426</b>
<b>Steering</b> (A0004660204)..... <b>P106-HD</b>	<b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A3844777015)..... <b>BF46071</b>	<b>Cab Air</b> (A9408350047)..... <b>PA4945</b>
Axor 2540 w/OM-457 LA (Euro III)	<b>Fuel/Water Separator</b> (Open End for Bowl) (A3844777015)..... <b>BF46109-O</b>	<b>Air Dryer</b> (Khorr System) (A0004295795)..... <b>[2] BA5379 +</b>
<b>Lube</b> (A0001802909)..... <b>P7230</b>	2638 LK w/OM457LA Eng. (01/99-on)	<b>Air Dryer</b> (Knecht System) (A0004293695)..... <b>[2] BA5374 +</b>
<b>Fuel/Water Separator</b> (w/Drain) (A0004771302)..... <b>BF1363</b>	<b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A3844777015)..... <b>BF46071</b>	<b>Air Dryer</b> (Mann & Hummel System) (A0004293795)..... <b>[2] BA5374 +</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (A3844777015)..... <b>BF46109-O</b>	<b>Air Dryer</b> (Wabco System) (A0004295695)..... <b>[2] BA5379 +</b>
<b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (A3844777015)..... <b>BF46109-O</b>	<b>Steering</b> (A0004662804)..... <b>P106-HD</b>
<b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A9794770015).. <b>BF46109-O</b>	2638 LS w/OM447LA Eng. (To 12/97)	<b>Urea</b> (A0001420289)..... <b>PE5272</b>
<b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b>	<b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A3844777015)..... <b>BF46071</b>	Axor 2644 w/OM 457 LA (Euro III) Eng.
<b>Fuel</b> (A5410900151)..... <b>PF7761</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (A3844777015)..... <b>BF46109-O</b>	<b>Lube</b> (A0001802909)..... <b>P7230</b>
<b>Radial Seal O. Air</b> (A0040943504)..... <b>RS5358</b>	2638 LS w/OM457 Eng. (01/99-on)	<b>Fuel/Water Separator</b> (w/Drain) (A0004771302)..... <b>BF1363</b>
<b>Radial Seal I. Air</b> (A4760940104)..... <b>RS5549</b>	<b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A3844777015)..... <b>BF46071</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b>
<b>Cab Air</b> (A9408350047)..... <b>PA4945</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (A3844777015)..... <b>BF46109-O</b>	<b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b>
<b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b>	<b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A9794770015).. <b>BF46109-O</b>	<b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b>
<b>Steering</b> (A0004660204)..... <b>P106-HD</b>	Axor 2640 w/OM 457 LA (Euro III) Eng.	<b>Fuel</b> (A5410900151)..... <b>PF7761</b>
Axor 2540 S w/OM 457 LA (Euro V) Eng.	<b>Lube</b> (A0001802909)..... <b>P7230</b>	<b>Radial Seal O. Air</b> (A0040943504)..... <b>RS5358</b>
<b>Lube</b> (A0001802909)..... <b>P7230</b>	<b>Fuel/Water Separator</b> (w/Drain) (A0004771302)..... <b>BF1363</b>	<b>Radial Seal I. Air</b> (A4760940104)..... <b>RS5549</b>
<b>Fuel/Water Separator</b> (w/Drain) (A0004771302)..... <b>BF1363</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b>	<b>Cab Air</b> (A9408350047)..... <b>PA4945</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b>	<b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b>	<b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b>
<b>Fuel</b> (A4570900051)..... <b>PF7761</b>	<b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A9794770015).. <b>BF46109-O</b>	<b>Steering</b> (A0004660204)..... <b>P106-HD</b>
<b>Radial Seal O. Air</b> (A0040943504)..... <b>RS5358</b>	<b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b>	<b>Urea</b> (A0001420289)..... <b>PE5272</b>
<b>Radial Seal I. Air</b> (A4760940104)..... <b>RS5549</b>	Axor 2640 S w/OM 457 LA (Euro III) Eng.	Actros 2644 S w/OM 457 LA Eng. (Chile)
<b>Cab Air</b> (A9408350047)..... <b>PA4945</b>	<b>Lube</b> (A0001802909)..... <b>P7230</b>	<b>Lube</b> (A0001802909)..... <b>P7230</b>
<b>Steering</b> (A0004660204)..... <b>P106-HD</b>	<b>Fuel/Water Separator</b> (w/Drain) (A0004771302)..... <b>BF1363</b>	<b>Fuel/Water Separator</b> (w/Drain) (A0004771302)..... <b>BF1363</b>
<b>Urea</b> (A0001420289)..... <b>PE5272</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b>
Axor 2544 S	<b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A3844777015)..... <b>BF46071</b>	<b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b>
<b>Lube</b> (A0001802909)..... <b>P7230</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b>	<b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A9794770015).. <b>BF46109-O</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (A9794770015)..... <b>BF46109-O</b>	<b>Fuel</b> (A5410900151)..... <b>PF7761</b>	<b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b>
<b>Fuel/Water Separator</b> (w/Bowl) (A9794770015)..... <b>BF46071</b>	<b>Radial Seal O. Air</b> (A0040943504)..... <b>RS5358</b>	<b>Fuel</b> (A5410900151)..... <b>PF7761</b>
<b>201.6 mm Fuel</b> (A5410900151).... <b>PF7761</b>	<b>Radial Seal I. Air</b> (A4760940104)..... <b>RS5549</b>	<b>Radial Seal O. Air</b> (A0040943504)..... <b>RS5358</b>
<b>Radial Seal Air</b> (A0040943504)... <b>RS5358</b>	<b>Cab Air</b> (A9408350047)..... <b>PA4945</b>	<b>Radial Seal I. Air</b> (A4760940104)..... <b>RS5549</b>
2638	<b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b>	<b>Cab Air</b> (A9408350047)..... <b>PA4945</b>
<b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b>	<b>Steering</b> (A0004660204)..... <b>P106-HD</b>	
2638 L w/OM447LA Eng. (To 12/97)	<b>Steering</b> (A0004660204)..... <b>P106-HD</b>	
<b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A3844777015)..... <b>BF46071</b>	<b>Urea</b> (A0001420289)..... <b>PE5272</b>	
<b>Fuel/Water Separator</b> (Open End for Bowl) (A3844777015)..... <b>BF46109-O</b>	Axor 2640 S w/OM 502 LA Eng.	
	<b>Lube</b> (A5411800209)..... <b>P7192</b>	
	<b>Fuel/Water Separator</b> (w/Drain) (A0004771302)..... <b>BF1363</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>MERCEDES-BENZ</b> South America Trucks, Buses, Vans (cont'd)	<b>MERCEDES-BENZ</b> South America Trucks, Buses, Vans (cont'd)	<b>MERCEDES-BENZ</b> South America Trucks, Buses, Vans (cont'd)
Axros 2644 S w/OM 457 LA Eng. (Chile) (Cont'd) <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0004660204)..... <b>P106-HD</b>	Axor 2826 w/OM 926 LA (Euro III) Eng. <b>Lube</b> (A0001801709)..... <b>P7188</b> <b>Fuel/Water Separator</b> (w/Drain) (A0004771302)..... <b>BF1363</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A9794770015).. <b>BF46109-O</b> <b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Radial Seal Air</b> (A0030949604)... <b>RS5342</b> <b>Cab Air</b> (A9408350047)..... <b>PA4945</b> <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0004660204)..... <b>P106-HD</b> <b>Urea</b> (A0001420289)..... <b>PE5272</b>	Axor 2831 48 6x4 w/OM-926 LA (Euro V) Eng. (Cont'd) <b>Cab Air</b> (A9408350047)..... <b>PA4945</b> <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0004660604)..... <b>P106-HD</b> <b>Urea</b> (A0001420289)..... <b>PE5272</b>
Axor 2644 S (Brazil) <b>Lube</b> (A0001802909)..... <b>P7230</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A9794770015)..... <b>BF46109-O</b> <b>Fuel/Water Separator</b> (w/Bowl) (A9794770015)..... <b>BF46071</b> <b>201.6 mm Fuel</b> (A5410900151)... <b>PF7761</b> <b>Radial Seal Air</b> (A0040943504)... <b>RS5358</b>	Axor 2831 <b>Lube</b> (A0001802909)..... <b>P7230</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b>	Axor 2831 K w/OM 926 LA (Euro V) Eng. <b>Lube</b> (A0001801709)..... <b>P7188</b> <b>Fuel/Water Separator</b> (w/Drain) (A0004771302)..... <b>BF1363</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A9794770015).. <b>BF46109-O</b> <b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Radial Seal Air</b> (A0030949604)... <b>RS5342</b> <b>Cab Air</b> (A9408350047)..... <b>PA4945</b> <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0004660604)..... <b>P106-HD</b> <b>Urea</b> (A0001420289)..... <b>PE5272</b>
2726 w/OM 906 LA (Euro III) Eng. <b>Lube</b> (A0001801709)..... <b>P7188</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9584770115)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Radial Seal O. Air</b> (A6345280306)..... <b>RS5627</b> <b>Radial Seal I. Air</b> (A6345280206)..... <b>RS5628</b> <b>Air Dryer</b> (Knorr System) (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0001842225)..... <b>P106-HD</b>	Axor 2831 w/OM 460 LA (Euro III) Eng. <b>Lube</b> (A0001801709)..... <b>P7188</b>	Axor 3340 w/OM-457 LA (Euro III) Eng. <b>Lube</b> (A0001802909)..... <b>P7230</b> <b>Fuel/Water Separator</b> (w/Drain) (A0004771302)..... <b>BF1363</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A9794770015).. <b>BF46109-O</b> <b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b> <b>Fuel</b> (A5410900151)..... <b>PF7761</b> <b>Radial Seal O. Air</b> (A0040943504)..... <b>RS5358</b> <b>Radial Seal I. Air</b> (A4760940104)..... <b>RS5549</b> <b>Cab Air</b> (A9408350047)..... <b>PA4945</b> <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0004660204)..... <b>P106-HD</b>
2726 B-36 w/OM 906 LA (Euro III) Eng. <b>Lube</b> (A0001801709)..... <b>P7188</b> <b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9584770115)..... <b>BF46071</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Radial Seal O. Air</b> (A6345280306)..... <b>RS5627</b> <b>Radial Seal I. Air</b> (A6345280206)..... <b>RS5628</b> <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0001842225)..... <b>P106-HD</b>	Axor 2831 w/OM 926 LA (Euro V) Eng. <b>Lube</b> (A0001801709)..... <b>P7188</b> <b>Fuel/Water Separator</b> (w/Drain) (A0004771302)..... <b>BF1363</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A9794770015).. <b>BF46109-O</b> <b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Radial Seal Air</b> (A0030949604)... <b>RS5342</b> <b>Cab Air</b> (A9408350047)..... <b>PA4945</b> <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0004660204)..... <b>P106-HD</b> <b>Urea</b> (A0001420289)..... <b>PE5272</b>	Axor 3340 K w/OM-457 LA (Euro III) Eng. <b>Lube</b> (A0001802909)..... <b>P7230</b> <b>Fuel/Water Separator</b> (w/Drain) (A0004771302)..... <b>BF1363</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A9794770015).. <b>BF46109-O</b>
2726 K-36 w/OM 906 LA (Euro III) Eng. <b>Lube</b> (A0001801709)..... <b>P7188</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9584770115)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Radial Seal O. Air</b> (A6345280306)..... <b>RS5627</b> <b>Radial Seal I. Air</b> (A6345280206)..... <b>RS5628</b> <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0001842225)..... <b>P106-HD</b>	Axor 2831 48 6x4 w/OM-926 LA (Euro V) Eng. <b>Lube</b> (A0001801709)..... <b>P7188</b> <b>Fuel/Water Separator</b> (w/Drain) (A0004771302)..... <b>BF1363</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A9794770015).. <b>BF46109-O</b> <b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Air</b> (A0030949604)..... <b>RS5342</b>	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



<b>MERCEDES-BENZ</b> South America Trucks, Buses, Vans (cont'd)	<b>MERCEDES-BENZ</b> South America Trucks, Buses, Vans (cont'd)	<b>MERCEDES-BENZ</b> South America Trucks, Buses, Vans (cont'd)
Axor 3340 K w/OM-457 LA (Euro III) Eng. (Cont'd) <b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b> <b>Fuel</b> (A4570900051)..... <b>PF7761</b> <b>Radial Seal O. Air</b> (A0040943504)..... <b>RS5358</b> <b>Radial Seal I. Air</b> (A4760940104)..... <b>RS5549</b> <b>Cab Air</b> (A9408350047)..... <b>PA4945</b> <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0004660204)..... <b>P106-HD</b> <b>Urea</b> (A0001420289)..... <b>PE5272</b>	Axor 3344 w/OM-457 LA (Euro III) Eng. <b>Lube</b> (A0001802909)..... <b>P7230</b> <b>Fuel/Water Separator</b> (w/Drain) (A0004771302)..... <b>BF1363</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A9794770015).. <b>BF46109-O</b> <b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b> <b>Fuel</b> (A5410900151)..... <b>PF7761</b> <b>Radial Seal O. Air</b> (A0040943504)..... <b>RS5358</b> <b>Radial Seal I. Air</b> (A4760940104)..... <b>RS5549</b> <b>Cab Air</b> (A9408350047)..... <b>PA4945</b> <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0004660204)..... <b>P106-HD</b>	Actros 3344 S w/OM 457 LA (Euro V) Eng. (Cont'd) <b>Radial Seal O. Air</b> (A0040943504)..... <b>RS5358</b> <b>Radial Seal I. Air</b> (A4760940104)..... <b>RS5549</b> <b>Cab Air</b> (A9408350047)..... <b>PA4945</b> <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0004660204)..... <b>P106-HD</b>
Axor 3340 S w/OM-457 LA (Euro V) Eng. <b>Lube</b> (A0001802909)..... <b>P7230</b> <b>Fuel/Water Separator</b> (w/Drain) (A0004771302)..... <b>BF1363</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b> <b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A9794770015).. <b>BF46109-O</b> <b>Fuel</b> (A5410900151)..... <b>PF7761</b> <b>Radial Seal O. Air</b> (A0040943504)..... <b>RS5358</b> <b>Radial Seal I. Air</b> (A4760940104)..... <b>RS5549</b> <b>Cab Air</b> (A9408350047)..... <b>PA4945</b> <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0004660204)..... <b>P106-HD</b> <b>Urea</b> (A0001420289)..... <b>PE5272</b>	Axor 3344 K w/OM 457 LA (Euro V) Eng. <b>Lube</b> (A0001802909)..... <b>P7230</b> <b>Fuel/Water Separator</b> (w/Drain) (A0004771302)..... <b>BF1363</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A9794770015).. <b>BF46109-O</b> <b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b> <b>Fuel</b> (A5410900151)..... <b>PF7761</b> <b>Radial Seal O. Air</b> (A0040943504)..... <b>RS5358</b> <b>Radial Seal I. Air</b> (A4760940104)..... <b>RS5549</b> <b>Cab Air</b> (A9408350047)..... <b>PA4945</b> <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0004660204)..... <b>P106-HD</b> <b>Urea</b> (A0001420289)..... <b>PE5272</b>	Axor 4140 w/OM 457 LA (Euro V) Eng. <b>Lube</b> (A0001802909)..... <b>P7230</b> <b>Fuel/Water Separator</b> (w/Drain) (A0004771302)..... <b>BF1363</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A9794770015).. <b>BF46109-O</b> <b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b> <b>Fuel</b> (A5410900151)..... <b>PF7761</b> <b>Radial Seal O. Air</b> (A0040943504)..... <b>RS5358</b> <b>Radial Seal I. Air</b> (A4760940104)..... <b>RS5549</b> <b>Cab Air</b> (A9408350047)..... <b>PA4945</b> <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0004660204)..... <b>P106-HD</b> <b>Urea</b> (A0001420289)..... <b>PE5272</b>
Axor 3340 S/K w/OM 457 LA (Euro V) <b>Lube</b> (A0001802909)..... <b>P7230</b> <b>Fuel/Water Separator</b> (w/Drain) (A0004771302)..... <b>BF1363</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A9794770015).. <b>BF46109-O</b> <b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b> <b>Fuel</b> (A4570900051)..... <b>PF7761</b> <b>Radial Seal O. Air</b> (A0040943504)..... <b>RS5358</b> <b>Radial Seal I. Air</b> (A4760940104)..... <b>RS5549</b> <b>Cab Air</b> (A9408350047)..... <b>PA4945</b> <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0004660204)..... <b>P106-HD</b> <b>Urea</b> (A0001420289)..... <b>PE5272</b>	Actros 3344 S w/OM 457 LA (Euro V) Eng. <b>Lube</b> (A0001802909)..... <b>P7230</b> <b>Fuel/Water Separator</b> (w/Drain) (A0004771302)..... <b>BF1363</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A9794770015).. <b>BF46109-O</b> <b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b> <b>Fuel</b> (A5410900151)..... <b>PF7761</b>	Axor 4144 w/OM 457 LA (Euro V) Eng. <b>Lube</b> (A0001802909)..... <b>P7230</b> <b>Fuel/Water Separator</b> (w/Drain) (A0004771302)..... <b>BF1363</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A9794770015).. <b>BF46109-O</b> <b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b> <b>Fuel</b> (A5410900151)..... <b>PF7761</b> <b>Radial Seal O. Air</b> (A0040943504)..... <b>RS5358</b> <b>Radial Seal I. Air</b> (A4760940104)..... <b>RS5549</b> <b>Cab Air</b> (A9408350047)..... <b>PA4945</b> <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0004660204)..... <b>P106-HD</b> <b>Urea</b> (A0001420289)..... <b>PE5272</b>
	Andare 1728 w/OM906LA Eng. <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b>	


+ See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ South America Trucks, Buses, Vans (cont'd)	MERCEDES-BENZ South America Trucks, Buses, Vans (cont'd)	MERCEDES-BENZ South America Trucks, Buses, Vans (cont'd)
Andare 1728 w/OM906LA Eng. (Cont'd) <b>Fuel/Water Separator</b> (Open End for Bowl) (A9794770015)..... <b>BF46109-O</b>	L 1418 w/OM 904 LA Eng. <b>Lube</b> (A0001801609)..... <b>P7199</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A9794770015).. <b>BF46109-O</b> <b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Radial Seal O. Air</b> (A3740947104)..... <b>RS5452</b> <b>Radial Seal I. Air</b> (A3740947204)..... <b>RS5453</b> <b>Steering</b> (A0001842225)..... <b>P106-HD</b>	L 1620 w/OM 906 LA Eng. (Cont'd) <b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Radial Seal I. Air</b> (A3760948304)..... <b>RS5676</b> <b>Urea</b> (A0001420289)..... <b>PE5272</b>
L 1214 w/OM366 Eng. <b>Fuel</b> (A3444700092)..... <b>[2] F834-F</b> <b>Air</b> (A3820927005)..... <b>BF9922-O</b> <b>Air</b> (A0010945204)..... <b>PA2405</b> <b>Air Dryer</b> (Knorr System) (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0004660604)..... <b>P106-HD</b>	L 1418 EL <b>150.8 mm Lube</b> (A0001801609).. <b>P7199</b> <b>Lube</b> (A0001842225)..... <b>P106</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9584770115)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A3844777015).. <b>BF46109-O</b> <b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Radial Seal Air</b> (A3740947104).. <b>RS5452</b> <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b>	L 1620 w/OM 924 LA Eng. <b>Lube</b> (A0001801609)..... <b>P7199</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A9794770015).. <b>BF46109-O</b> <b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Radial Seal O. Air</b> (A3760948204)..... <b>RS30130</b> <b>Radial Seal I. Air</b> (A3760948304)..... <b>RS5676</b> <b>Steering</b> (A0001842225)..... <b>P106-HD</b> <b>Urea</b> (A0001420289)..... <b>PE5272</b>
L 1218 w/OM924 LA (Euro V) Eng. <b>Lube</b> (A0001801609)..... <b>P7199</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A9794770015).. <b>BF46109-O</b> <b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Radial Seal Air</b> (A3740947104).. <b>RS5452</b> <b>Steering</b> (A0001842225)..... <b>P106-HD</b>	L 1218 R w/OM366A Eng. <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0001842225)..... <b>P106-HD</b>	L 1620 w/OM 926 LA (Euro V) Eng. <b>Lube</b> (A0001801709)..... <b>P7188</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A9794770015).. <b>BF46109-O</b> <b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Radial Seal I. Air</b> (A3760948304)..... <b>RS5676</b> <b>Steering</b> (A0001842225)..... <b>P106-HD</b> <b>Urea</b> (A0001420289)..... <b>PE5272</b>
L 1218 R w/OM366A Eng. <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0001842225)..... <b>P106-HD</b>	L 1313 <b>Air</b> (A0010945204)..... <b>PA2405</b>	L 1620 w/OM 926 LA (Euro V) Eng. <b>Lube</b> (A0001801709)..... <b>P7188</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A9794770015).. <b>BF46109-O</b> <b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Radial Seal I. Air</b> (A3760948304)..... <b>RS5676</b> <b>Steering</b> (A0001842225)..... <b>P106-HD</b> <b>Urea</b> (A0001420289)..... <b>PE5272</b>
L 1313 <b>Air</b> (A0010945204)..... <b>PA2405</b>	L 1314 w/OM366 LA Eng. <b>Fuel</b> (A3900920001)..... <b>BF970 +</b> <b>Air</b> (A0010945204)..... <b>PA2405</b> <b>Steering</b> (A0004660604)..... <b>P106-HD</b>	L-1620 w/OM 366 LA (Euro III) Eng. (Brazil) <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b>
L 1316 <b>Air</b> (A0010945204)..... <b>PA2405</b>	L 1513 <b>Lube</b> (A0001842225)..... <b>P106</b> <b>Air</b> (A0010945204)..... <b>PA2405</b>	L-1620 w/OM-906 LA (Euro III) Eng. (Brazil) <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b>
L 1317 <b>Air</b> (A0010945204)..... <b>PA2405</b>	L 1514 <b>Lube</b> (A0001842225)..... <b>P106</b> <b>Air</b> (A0010945204)..... <b>PA2405</b>	L 1620EL <b>Radial Seal Air</b> (3760948204)..... <b>RS30130</b>
L 1318 w/OM 904 LA (Euro III) Eng. <b>Lube</b> (A0001801609)..... <b>P7199</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A9794770015).. <b>BF46109-O</b> <b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Radial Seal O. Air</b> (A3740947104)..... <b>RS5452</b> <b>Radial Seal I. Air</b> (A3740947204)..... <b>RS5453</b> <b>Air Dryer</b> (Knorr System) (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0001842225)..... <b>P106-HD</b>	L 1516 <b>Lube</b> (A0001842225)..... <b>P106</b> <b>Air</b> (A0010945204)..... <b>PA2405</b>	L 1622 w/OM 924 LA Eng. <b>Lube</b> (A0001801609)..... <b>P7199</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A9794770015).. <b>BF46109-O</b> <b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Radial Seal O. Air</b> (A3760948204)..... <b>RS30130</b> <b>Radial Seal I. Air</b> (A3760948304)..... <b>RS5676</b>
L 1318 w/OM 904 LA (Euro III) Eng. <b>Lube</b> (A0001801609)..... <b>P7199</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A9794770015).. <b>BF46109-O</b> <b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Radial Seal O. Air</b> (A3740947104)..... <b>RS5452</b> <b>Radial Seal I. Air</b> (A3740947204)..... <b>RS5453</b> <b>Air Dryer</b> (Knorr System) (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0001842225)..... <b>P106-HD</b>	L 1517 <b>Lube</b> (A0001842225)..... <b>P106</b> <b>Air</b> (A0010945204)..... <b>PA2405</b>	
L 1318 w/OM 904 LA (Euro III) Eng. <b>Lube</b> (A0001801609)..... <b>P7199</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A9794770015).. <b>BF46109-O</b> <b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Radial Seal O. Air</b> (A3740947104)..... <b>RS5452</b> <b>Radial Seal I. Air</b> (A3740947204)..... <b>RS5453</b> <b>Air Dryer</b> (Knorr System) (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0001842225)..... <b>P106-HD</b>	L 1518 (Brazil) <b>Lube</b> (A0001842225)..... <b>P106</b> <b>Air</b> (A0010945204)..... <b>PA2405</b>	
L 1318 w/OM 904 LA (Euro III) Eng. <b>Lube</b> (A0001801609)..... <b>P7199</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A9794770015).. <b>BF46109-O</b> <b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Radial Seal O. Air</b> (A3740947104)..... <b>RS5452</b> <b>Radial Seal I. Air</b> (A3740947204)..... <b>RS5453</b> <b>Air Dryer</b> (Knorr System) (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0001842225)..... <b>P106-HD</b>	L 1519 <b>Lube</b> (A0001842225)..... <b>P106</b> <b>Fuel</b> (A3440927405)..... <b>PF950</b>	
L 1318 w/OM 904 LA (Euro III) Eng. <b>Lube</b> (A0001801609)..... <b>P7199</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A9794770015).. <b>BF46109-O</b> <b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Radial Seal O. Air</b> (A3760948204)..... <b>RS30130</b> <b>Radial Seal I. Air</b> (A3760948304)..... <b>RS5676</b>	L 1520 <b>Lube</b> (A0001842225)..... <b>P106</b> <b>Fuel</b> (A3440927405)..... <b>PF950</b>	
L 1318 w/OM 904 LA (Euro III) Eng. <b>Lube</b> (A0001801609)..... <b>P7199</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A9794770015).. <b>BF46109-O</b> <b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Radial Seal O. Air</b> (A3760948204)..... <b>RS30130</b> <b>Radial Seal I. Air</b> (A3760948304)..... <b>RS5676</b>	L 1620 w/OM 906 LA Eng. <b>Lube</b> (A0001801709)..... <b>P7188</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9794770015)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (w/Female Thread for Bowl) (A9794770015).. <b>BF46109-O</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ South America Trucks, Buses, Vans (cont'd)	MERCEDES-BENZ South America Trucks, Buses, Vans (cont'd)	MERCEDES-BENZ South America Trucks, Buses, Vans (cont'd)
L 1622 w/OM 924 LA Eng. (Cont'd)	L 1624 w/OM 926 LA (Euro V) Eng. (Cont'd)	L 2638
Steering (A0001842225)..... P106-HD	Fuel/Water Separator (Open End for Bowl) (A9794770015)..... BF46109-O	Lube (A0001801109)..... P294
Urea (A0001420289)..... PE5272	Fuel (A0000901551)..... PF7735	Fuel/Water Separator (Open End for Bowl) (A4570920001)..... BF1360-O
L 1622 w/OM 926 LA (Euro V) Eng.	Radial Seal O. Air (A3760948204)..... RS30130	Fuel/Water Separator (w/Drain) (A4570920001)..... BF1360
Lube (A0001801709)..... P7188	Radial Seal I. Air (A3760948304)..... RS5676	Fuel/Water Separator (w/Sensor Port) (A4570920001)..... BF1360-SP
Fuel/Water Separator (w/Undetachable Bowl) (A9794770015)..... BF46071	Steering (A0001842225)..... P106-HD	203.2 mm Fuel (A5410900151).... PF7761
Fuel/Water Separator (w/Female Thread for Bowl) (A9794770015).. BF46109-O	Urea (A0001420289)..... PE5272	473.9 mm STD. Air (A3880947004)..... PA2776
Fuel/Water Separator (w/Male Thread for Bowl) (A9584770115).. BF46123-O	L 1632	532.6 mm Radial Seal Air (A4760940004)..... RS5358
Fuel (A0000901551)..... PF7735	Air (A3880947004)..... PA2776	Radial Seal I. Air (A4760940104)..... RS5549
Radial Seal O. Air (A3760948204)..... RS30130	Air Dryer (A0004300969)..... BA5374 +	I. Air (A3880947104)..... PA3494
Radial Seal I. Air (A3760948304)..... RS5676	Turbocharger (A0001842225).... P106-HD	Air Dryer (A0004300969)..... BA5374 +
Steering (A0001842225)..... P106-HD	L 1634 w/OM477 (Euro III) Eng.	Turbocharger (A0001842225).... P106
Urea (A0001420289)..... PE5272	Steering (A0004660604)..... P106-HD	LA1313
L 1623	L 1634 EL w/OM457 (Euro III) Eng.	Air (A0010945204)..... PA2405
Air Dryer (A0004300969)..... BA5374 +	Fuel (A5410900151)..... PF7761	LA 1314
L 1624 w/OM 906 LA (Euro III) Eng.	Air (A3880947004)..... PA2776	Air (A0010945204)..... PA2405
Lube (A0001801709)..... P7188	Steering (A0004660604)..... P106-HD	LA 1317
Fuel/Water Separator (w/Undetachable Bowl) (A9794770015)..... BF46071	L 1938 EL w/OM457 (Euro III) Eng.	Air (A0010945204)..... PA2405
Fuel/Water Separator (w/Female Thread for Bowl) (A9794770015).. BF46109-O	Fuel (A5410900151)..... PF7761	LAK 1314
Fuel/Water Separator (w/Male Thread for Bowl) (A9584770115).. BF46123-O	Air (A3880947004)..... PA2776	Air (A0010945204)..... PA2405
Fuel (A0000901551)..... PF7735	Steering (A0004660604)..... P106-HD	LAK 1317
Radial Seal O. Air (A3760948204)..... RS30130	L 2013 w/OM 352 I Eng.	Air (A0010945204)..... PA2405
Radial Seal I. Air (A3760948304)..... RS5676	Fuel (A3524700092)..... [2] F834-F	LAK 1317
Steering (A0001842225)..... P106-HD	Steering (A0004660604)..... P106-HD	Air (A0010945204)..... PA2405
Urea (A0001420289)..... PE5272	L 2014 w/OM 352 I Eng.	LAK 1418 w/OM 366 A Eng.
L 1624 w/OM 924 LA Eng.	Fuel (A3524700092)..... [2] F834-F	Fuel (A3524700092)..... [2] F834-F
Lube (A0001801609)..... P7199	Steering (A0001842225)..... P106-HD	Steering (A0004660604)..... P106-HD
Fuel/Water Separator (w/Undetachable Bowl) (A9794770015)..... BF46071	L 2017 w/OM 352 I Eng.	LB2213
Fuel/Water Separator (Open End for Bowl) (A9794770015)..... BF46109-O	Fuel (A3524700092)..... [2] F834-F	Lube (A0001842225)..... P106
Fuel (A0000901551)..... PF7735	Steering (A0001842225)..... P106-HD	LB 2214
Radial Seal O. Air (A3760948204)..... RS30130	L 2213	Lube (A0001842225)..... P106
Radial Seal I. Air (A3760948304)..... RS5676	Lube (A0001842225)..... P106	LB 2217
Steering (A0001842225)..... P106-HD	Air (A0010945204)..... PA2405	Lube (A0001842225)..... P106
Urea (A0001420289)..... PE5272	L 2214 w/OM 352 I Eng.	Air (A0010945204)..... PA2405
L 1624 w/OM 926 LA (Euro V) Eng.	Fuel (A3524700092)..... [2] F834-F	LB 2219
Lube (A0001801709)..... P7188	Steering (A0001842225)..... P106-HD	Lube (A0001842225)..... P106
Fuel/Water Separator (w/Undetachable Bowl) (A9794770015)..... BF46071	L 2216	LB 2220
Fuel/Water Separator (w/Undetachable Bowl) (A9794770015)..... BF46071	Lube (A0001842225)..... P106	Lube (A0001842225)..... P106
Fuel (A0000901551)..... PF7735	Air (A0010945204)..... PA2405	LB 2220
Radial Seal O. Air (A3760948204)..... RS30130	L 2217	Lube (A0001842225)..... P106
Radial Seal I. Air (A3760948304)..... RS5676	Lube (A0001842225)..... P106	LK 1214 w/OM 366 Eng.
Steering (A0001842225)..... P106-HD	Air (A0010945204)..... PA2405	Fuel/Water Separator (A3820927005)..... BF9922-O
Urea (A0001420289)..... PE5272	L 2219	Fuel (A3524700092)..... [2] F834-F
L 1624 w/OM 926 LA (Euro V) Eng.	Lube (A0001842225)..... P106	Steering (A0004660604)..... P106-HD
Lube (A0001801709)..... P7188	Fuel (A3440927405)..... PF950	LK 1218 w/OM 904 LA Eng.
Fuel/Water Separator (w/Undetachable Bowl) (A9794770015)..... BF46071	L 2220	Lube (A0001801609)..... P7199
	Lube (A0001842225)..... P106	Fuel/Water Separator (w/Undetachable Bowl) (A9794770015)..... BF46071
	Fuel (A3440927405)..... PF950	Fuel/Water Separator (Open End for Bowl) (A9794770015)..... BF46109-O
	L 2225	Fuel (A0000901551)..... PF7735
	Lube (A0001842225)..... P106	


\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ South America Trucks, Buses, Vans (cont'd)	MERCEDES-BENZ South America Trucks, Buses, Vans (cont'd)	MERCEDES-BENZ South America Trucks, Buses, Vans (cont'd)
LK 1218 w/OM 904 LA Eng. (Cont'd)	LK 1520 w/OM 355 Eng.	LK 2638 (Cont'd)
Radial Seal O. Air (A3740947104)..... RS5452	Fuel (A3524700092)..... [2] F834-F	I. Air (A3880947104)..... PA3494
Radial Seal I. Air (A3740947204)..... RS5453	O. Air (A0010945204)..... PA2405	Air Dryer (A0004300969)..... BA5374 +
Steering (A0001842225)..... P106-HD	Steering (A0001842225)..... P106-HD	Steering (A0001842225)..... P106-HD
LK 1218 w/OM 924 LA (Euro V) Eng.	LK 1614 w/OM366 Eng. (01/89-12/94)	Chassi LO 610 w/OM 364 LA Eng.
Lube (A0001801609)..... P7199	Fuel/Water Separator (w/Undetachable Bowl)	Fuel/Water Separator (A3820927005)..... BF9922-O
Fuel/Water Separator (w/Undetachable Bowl)	(A3844777015)..... BF46071	Fuel (To identification number D 031294) (A3524700092)..... [2] F834-F
(A9794770015)..... BF46071	Fuel/Water Separator (Open End for Bowl) (A3844777015)..... BF46109-O	Air (A0030943304)..... PA2845
Fuel/Water Separator (Open End for Bowl) (A9794770015)..... BF46109-O	LK 1620 w/OM 366 LA Eng.	Steering (A0004660604)..... P106-HD
Fuel (A0000901551)..... PF7735	Fuel (A3524700092)..... [2] F834-F	Chassi LO812 w/OM 364 LA Eng.
Radial Seal O. Air (A3740947104)..... RS5452	Radial Seal I. Air (A3760948004)..... RS5628	Fuel/Water Separator (A3820927005)..... BF9922-O
Radial Seal I. Air (A3740947204)..... RS5453	Air Dryer (A0004300969)..... BA5374 +	Single Air (To identification number D 339845)
Steering (A0001842225)..... P106-HD	Steering (A0001842225)..... P106-HD	(A0030943304)..... PA2845
LK 1218 R	LK 1621 w/OM 366 LA Eng.	Air Dryer (A0004300969)..... BA5374 +
Lube (A0001842225)..... P106	Fuel/Water Separator (A3820927005)..... BF9922-O	Steering (A0004660604)..... P106-HD
Air Dryer (A0004300969)..... BA5374 +	Fuel (A3444700092)..... [2] F834-F	LO 814 w/OM 364 LA Eng.
LK1313	Air (Short Cab) (A0010945204)..... PA2405	Fuel/Water Separator (A3820927005)..... BF9922-O
Air (A0010945204)..... PA2405	Steering (A0004660604)..... P106-HD	Air Dryer (A0004300969)..... BA5374 +
LK 1316	LK 2213 w/OM 352 I Eng.	Steering (A0004660604)..... P106-HD
Air (A0010945204)..... PA2405	Fuel (A3524700092)..... [2] F834-F	LO 914
LK 1318 w/OM 904 LA Eng.	Air (A0010945204)..... PA2405	Lube (A0001801609)..... P7199
100.8 mm Lube (A0001842225)..... P106	Steering (A0001842225)..... P106-HD	Fuel/Water Separator (w/Undetachable Bowl)
150.8 mm Lube (A0001801609)..... P7199	LK 2214 w/OM 352 I Eng.	(A9584770115)..... BF46071
Fuel/Water Separator (w/Undetachable Bowl)	Fuel (A3524700092)..... [2] F834-F	Fuel/Water Separator (w/Female Thread for Bowl) (A3844777015)..... BF46109-O
(A9584770115)..... BF46071	O. Air (A0010945204)..... PA2405	Fuel/Water Separator (w/Male Thread for Bowl) (A9584770115)..... BF46123-O
Fuel/Water Separator (w/Female Thread for Bowl) (A3844777015)..... BF46109-O	Steering (A0001842225)..... P106-HD	Fuel (A0000901551)..... PF7735
Fuel/Water Separator (w/Male Thread for Bowl) (A9584770115)..... BF46123-O	LK 2219	Air (A0040944104)..... PA3843
Fuel (A0000901551)..... PF7735	Lube (A0001842225)..... P106	419.1 mm Radial Seal Air (A3740947104)..... RS5452
Radial Seal Air (A3740947104)..... RS5452	Fuel (A3440927405)..... PF950	Air Dryer (A0004300969)..... BA5374 +
Air Dryer (A0004300969)..... BA5374 +	LK 2220	LO 915 AT w/OM 364 LA Eng.
LK1414 w/OM 366 Eng.	Lube (A0001842225)..... P106	Fuel/Water Separator (w/Undetachable Bowl)
Fuel (A3524700092)..... [2] F834-F	Fuel (A3440927405)..... PF950	(A9794770015)..... BF46071
LK 1418 w/OM 904 LA Eng.	LK 2325 w/OM 449 A Eng.	Fuel/Water Separator (Open End for Bowl) (A9794770015)..... BF46109-O
Lube (A0001801609)..... P7199	Lube (A0001801109)..... P294	LS 1520
Fuel (A0000901551)..... PF7735	Fuel/Water Separator (A3820927005)..... BF9922-O	Lube (A0001842225)..... P106
Air Dryer (A0004300969)..... BA5374 +	Fuel (A0000901451)..... [2] F950-F	Fuel (A3440927405)..... PF950
Steering (A0004660604)..... P106-HD	Steering (A0004660604)..... P106-HD	LS 1524
LK 1513	LK 2638	Lube (A0001842225)..... P106
Lube (A0001842225)..... P106	Lube (A0001801109)..... P294	LS 1525
LK 1514	Fuel/Water Separator (Open End for Bowl) (A4570920001)..... BF1360-O	Lube (A0001842225)..... P106
Lube (A0001842225)..... P106	Fuel/Water Separator (w/Drain) (A4570920001)..... BF1360	LS 1525
LK 1518 w/OM 352 A Eng.	Fuel/Water Separator (w/Sensor Port) (A4570920001)..... BF1360-SP	Lube (A0001842225)..... P106
Fuel (A3524700092)..... F834-F	Fuel (A5410900151)..... PF7761	LS 1625 w/OM 449 A Eng.
Steering (A0004660604)..... P106-HD	Radial Seal O. Air (A4760940004)..... RS5358	Lube (A0001801109)..... P294
	Radial Seal I. Air (A4760940104)..... RS5549	Fuel/Water Separator (A3820927005)..... BF9922-O
	O. Air (A3880947004)..... PA2776	Fuel (A0000901451)..... [2] F950-F

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>MERCEDES-BENZ</b> South America Trucks, Buses, Vans (cont'd)	<b>MERCEDES-BENZ</b> South America Trucks, Buses, Vans (cont'd)	<b>MERCEDES-BENZ</b> South America Trucks, Buses, Vans (cont'd)
LS 1625 w/OM 449 A Eng. (Cont'd) <b>Steering</b> (A0004660604)..... <b>P106-HD</b>	LS 1634 EL w/OM 457 LA Eng. (Cont'd) <b>Air Dryer</b> (Knorr System) (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0001842225)..... <b>P106-HD</b> <b>Urea</b> (A0001420289)..... <b>PE5272</b>	LS 2638 w/OM 457 LA Eng. <b>Lube</b> (A0001801109)..... <b>P294</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A4570920001)..... <b>BF1360-O</b> <b>Fuel/Water Separator</b> (w/Drain) (A4570920001)..... <b>BF1360</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (A4570920001)..... <b>BF1360-SP</b> <b>Fuel</b> (A5410900151)..... <b>PF7761</b> <b>Std. O. Air</b> (A3880947004)..... <b>PA2776</b> <b>Std. I. Air</b> (A3880947104)..... <b>PA3494</b> <b>Radial Seal Air</b> (A4760940004).... <b>RS5358</b> <b>Radial Seal I. Air</b> (A4760940104)..... <b>RS5549</b> <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0001842225)..... <b>P106-HD</b>
LS 1630 w/OM 449 A Eng. <b>Lube</b> (A0001801109)..... <b>P294</b> <b>Fuel/Water Separator</b> (A3820927005)..... <b>BF9922-O</b> <b>Fuel</b> (A0000901451)..... <b>[2] F950-F</b> <b>Steering</b> (A0004660604)..... <b>P106-HD</b>	LS 1929 w/OM 447 A Eng. <b>Lube</b> (A0001801109)..... <b>P294</b> <b>Fuel/Water Separator</b> (A3820927005)..... <b>BF9922-O</b> <b>Fuel</b> (A0000901451)..... <b>[2] F950-F</b> <b>O. Air</b> (A3880947004)..... <b>PA2776</b> <b>I. Air</b> (A3880947104)..... <b>PA3494</b> <b>Steering</b> (A0004660604)..... <b>P106-HD</b>	<b>MERCEDES-BENZ</b> <b>Trucks, Vans</b> Vaneo 1.6 CDI, 1.7 CDI w/OM668 Eng. <b>Fuel</b> (Mann WK842/13)..... <b>BF7756</b> <b>Air</b> (Mann C11120)..... <b>PA697</b>
LS 1632 w/OM 449 LA Eng. <b>Lube</b> (A0001801109)..... <b>P294</b> <b>Fuel</b> (A0000901451)..... <b>[2] F950-F</b> <b>Air</b> (A0010945204)..... <b>PA2405</b> <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0001842225)..... <b>P106-HD</b>	LS 1930 w/OM 355 A Eng. <b>Fuel</b> (A0000901451)..... <b>[2] F950-F</b> <b>Steering</b> (A0001842225)..... <b>P106-HD</b>	Vito 108 CDI, 110 CDI, 112 CDI w/OM611 Eng. <b>Lube</b> (Mann HU718/1k)..... <b>P1443</b> <b>Fuel</b> (Mann WK842/13)..... <b>BF7756</b> <b>Air</b> (Mann C32338)..... <b>PA4600</b>
LS 1633 w/OM 449 LA Eng. <b>Lube</b> (A4011800009)..... <b>P242</b> <b>Fuel/Water Separator</b> (A3820927005)..... <b>BF9922-O</b> <b>Fuel</b> (A0000901451)..... <b>[2] F950-F</b> <b>Steering</b> (A0004660604)..... <b>P106-HD</b>	LS 1932 w/OM 355 A Eng. <b>Fuel</b> (A0000901451)..... <b>[2] F950-F</b> <b>Steering</b> (A0001842225)..... <b>P106-HD</b>	207D, 208D <b>Lube</b> (1977-on) (6171840125)..... <b>P102</b> <b>Fuel</b> (109204401)..... <b>BF1056</b> <b>Air</b> (20947004)..... <b>PA2888</b>
LS 1634 w/OM 447 LA (Euro II) Eng. (Uruguay) <b>Lube</b> (A0001801109)..... <b>P294</b> <b>Fuel</b> (A0000901451)..... <b>[2] F950-F</b> <b>Air</b> (A0010945204)..... <b>PA2405</b> <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b> <b>Steering</b> (A0001842225)..... <b>P106-HD</b>	LS 1933 w/OM 355 A Eng. <b>Fuel</b> (A0000901451)..... <b>[2] F950-F</b> <b>Steering</b> (A0001842225)..... <b>P106-HD</b>	Sprinter 208CDI, 211CDI, 213CDI, 216CDI w/OM611, OM612 Engs. <b>Lube</b> (Mann HU718/1k)..... <b>P1443</b> <b>Fuel</b> (Mann WK842/13)..... <b>BF7756</b> <b>Air</b> (Mann C32338)..... <b>PA4600</b> <b>Air</b> (High Capacity) (Mann C32338/1)..... <b>PA4601</b> <b>Cab Air</b> (Mann CU3858)..... <b>PA4489</b>
LS 1634 (Brazil) <b>Lube</b> (A0001801109)..... <b>P294</b> <b>Lube</b> (A0001842225)..... <b>P106</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A4570920001)..... <b>BF1360-O</b> <b>Fuel/Water Separator</b> (w/Drain) (A4570920001)..... <b>BF1360</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (A4570920001)..... <b>BF1360-SP</b> <b>203.2 mm Fuel</b> (A5410900151).... <b>PF7761</b> <b>Radial Seal Air</b> (A4760940004).... <b>RS5358</b>	LS 1934 w/OM 355 A Eng. <b>Fuel</b> (A0000901451)..... <b>[2] F950-F</b> <b>Steering</b> (A0001842225)..... <b>P106-HD</b>	Sprinter 208D, 210D, 212D w/OM601, OM602 Engs. <b>Lube</b> (Mann HU951x)..... <b>P7196</b> <b>Fuel</b> (Mann WK817/3)..... <b>BF9892-D</b> <b>Air</b> (Mann C32338)..... <b>PA4600</b> <b>Air</b> (High Capacity) (Mann C32338/1)..... <b>PA4601</b> <b>Cab Air</b> (Mann CU3858)..... <b>PA4489</b>
LS-1634 w/OM-457 LA (Euro III) Eng. (Brazil) <b>Radial Seal Air</b> (4760940004)..... <b>RS5358</b> <b>Air Dryer</b> (A0004300969)..... <b>BA5374 +</b>	LS 1935 w/OM 447 A Eng. <b>Lube</b> (A0001801109)..... <b>P294</b> <b>Fuel/Water Separator</b> (A3820927005)..... <b>BF9922-O</b> <b>Fuel</b> (A0000901451)..... <b>[2] F950-F</b> <b>O. Air</b> (A0010945204)..... <b>PA2405</b> <b>Steering</b> (A0004660604)..... <b>P106-HD</b>	Sprinter 214 w/M111 Eng. <b>Lube</b> (1/1996-on) (Mann HU727/1x)..... <b>P1419</b> <b>Fuel</b> (Mann WK831)..... <b>BF1195</b> <b>Air</b> (Mann C32338)..... <b>PA4600</b> <b>Air</b> (High Capacity) (Mann C32338/1)..... <b>PA4601</b> <b>Cab Air</b> (Mann CU3858)..... <b>PA4489</b>
LS 1634 EL w/OM 457 LA Eng. <b>Lube</b> (A0001801109)..... <b>P294</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A4570920001)..... <b>BF1360-O</b> <b>Fuel/Water Separator</b> (w/Drain) (A4570920001)..... <b>BF1360</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (A4570920001)..... <b>BF1360-SP</b> <b>Fuel/Water Separator</b> (w/Undetachable Bowl) (A9584770115)..... <b>BF46071</b> <b>Fuel/Water Separator</b> (w/Male Thread for Bowl) (A9584770115).. <b>BF46123-O</b> <b>Fuel</b> (A5410900151)..... <b>PF7761</b> <b>Radial Seal Air</b> (A4760940004).... <b>RS5358</b> <b>Air Dryer</b> (Wabco System) (A0004293395)..... <b>BA5374 +</b>	LS 1941 w/OM 447 A Eng. <b>Lube</b> (A0001801109)..... <b>P294</b> <b>Fuel/Water Separator</b> (A3820927005)..... <b>BF9922-O</b> <b>Fuel</b> (A0000901451)..... <b>F950-F</b> <b>O. Air</b> (A3880947004)..... <b>PA2776</b> <b>I. Air</b> (A3880947104)..... <b>PA3494</b> <b>Steering</b> (A0004660604)..... <b>P106-HD</b>	


+ See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ Trucks, Vans (cont'd)	MERCEDES-BENZ Trucks, Vans (cont'd)	MERCEDES-BENZ Trucks, Vans (cont'd)
307D Lube (1977-on) (6171840125)..... P102 Fuel (109204401)..... BF1056 Air (20947004)..... PA2888	Sprinter 408D, 410D, 412D w/OM601, OM602 Eng. Lube (Mann H951x)..... P7196 Fuel (Mann WK817/3)..... BF9892-D Air (Mann C32338)..... PA4600 Air (High Capacity) (Mann C32338/1)..... PA4601 Cab Air (Mann CU3858)..... PA4489	Sprinter 616 CDI w/OM612 Eng. Lube (Mann HU718/1k)..... P1443 Fuel (Mann WK842/13)..... BF7756 Air (Mann C32338)..... PA4600 Air (High Capacity) (Mann C32338/1)..... PA4601 Cab Air (Mann CU3858)..... PA4489
Sprinter 308 CDI, 311 CDI, 313 CDI, 316 CDI w/OM611, OM612 Eng. Lube (Mann HU718/1k)..... P1443 Fuel (Mann WK842/13)..... BF7756 Air (Mann C32338)..... PA4600 Air (High Capacity) (Mann C32338/1)..... PA4601 Cab Air (Mann CU3858)..... PA4489	Sprinter 414 w/M111 Eng. Lube (1/1996-on) (Mann HU727/1x)..... P1419 Fuel (Mann WK831)..... BF1195 Air (Mann C32338)..... PA4600 Air (High Capacity) (Mann C32338/1)..... PA4601 Cab Air (Mann CU3858)..... PA4489	709 w/M314 Eng. Lube (To 2/77)..... P41 Fuel..... F834-F Steering..... P106-HD
Sprinter 308D, 310D, 312D w/OM601, OM602 Eng. Lube (Mann HU951x)..... P7196 Fuel (Mann WK817/3)..... BF9892-D Air (Mann C32338)..... PA4600 Air (High Capacity) (Mann C32338/1)..... PA4601 Cab Air (Mann CU3858)..... PA4489	Sprinter 314 w/M111 Eng. Lube (1/1996-on) (Mann HU727/1x)..... P1419 Fuel (Mann WK831)..... BF1195 Air (Mann C32338)..... PA4600 Air (High Capacity) (Mann C32338/1)..... PA4601 Cab Air (Mann CU3858)..... PA4489	709 w/OM364 Eng. Lube (S/N 286115-up)..... P7017 Fuel..... F834-F Air (4/84-on)..... PA3681 Steering..... P106-HD
Sprinter 319D, 319DB w/OM636 VIII Eng. Fuel (3524700092)..... F834-F	507D, 508D 136.5 mm Lube (3661840225)..... P7017 169.9 mm Lube..... P7615 193.7 mm Lube (6171840125)..... P102 88.1 mm Fuel (109204401)..... BF1056 155.6 mm Fuel..... BF587-D + 81.0 mm Height Air (20949304)..... PA3843 Steering (1902137)..... P106-HD	709D w/OM364 Eng. Lube (S/N 286115-up) (3661840225)..... P7017 Fuel..... F834-F Steering (1902137)..... P106-HD
319DC w/OM616, OM617, OM621 Eng. B-P Lube (1845825)..... P41 Fuel (3524700092)..... F834-F	510D, 512D 136.5 mm Lube (3661840225)..... P7017 169.9 mm Lube..... P7615 193.7 mm Lube (6171840125)..... P102 88.1 mm Fuel (109204401)..... BF1056 155.6 mm Fuel..... BF587-D + 81.0 mm Height Air (20949304)..... PA3843 Steering (1902137)..... P106-HD	710 w/OM346, OM352 Eng. Lube (OM346 Eng.)..... P52 Lube (OM352 Eng.) To 1978..... P52 Lube (OM352 Eng.) 1978-on..... P7015 Fuel (3440927005)..... [2] PF834 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10945204)..... PA2405 383.4 mm Air (10941004)..... PA2847 Steering..... P106-HD
325 w/OM325 Eng. Fuel Ele. (4220900051)..... F950-F	Vario 609D, Vario 611D 136.5 mm Lube (3661840225)..... P7017 169.9 mm Lube..... P7615 193.7 mm Lube (6171800009)..... P102 Fuel Ele. (4220900051)..... F950-F 88.1 mm Fuel Spin-on (109204401)..... BF1056 155.6 mm Fuel Spin-on..... BF587-D + 81.0 mm Height Air (20949304)..... PA3843 Steering..... P106-HD	711D w/OM364A Eng. Lube..... P7017 Fuel..... F834-F Air (4/86-on) (20949304)..... PA3843
327 Lube (11844925)..... P721 Fuel Ele. (4220900051)..... F950-F Steering (4660004)..... PT691	613 w/OM352 Eng. Lube (To 1978)..... P52 Lube (1978-on)..... P7015 Fuel..... F834-F	809 w/OM314 Eng. Lube (To 2/77)..... P41 Fuel..... F834-F Steering (1902137)..... P106-HD
328 Fuel Ele. (4220900051)..... F950-F	Vario 614D 136.5 mm Lube (3661840225)..... P7017 169.9 mm Lube..... P7615 193.7 mm Lube..... P102 Fuel Ele. (4220900051)..... F950-F 88.1 mm Fuel Spin-on (109204401)..... BF1056 155.6 mm Fuel Spin-on..... BF587-D + 81.0 mm Height Air (20949304)..... PA3843 Steering (1902137)..... P106-HD	809 w/OM364 Eng. Lube (S/N 286115-up) (3661840225)..... P7017 Fuel..... F834-F Air (4/84-on)..... PA3681 Steering (1902137)..... P106-HD
334, 337 Lube (11844925)..... P721 Fuel Ele. (4220900051)..... F950-F Steering (4660004)..... PT691		809D 136.5 mm Lube (3661840225)..... P7017 169.9 mm Lube..... P7615 193.7 mm Lube (6171800009)..... P102 Fuel Ele. (4220900051)..... F950-F 88.1 mm Fuel Spin-on (109204401)..... BF1056 155.6 mm Fuel Spin-on..... BF587-D + 81.0 mm Height Air Panel (20949304)..... PA3843 220.7 mm Air (10946504)..... PA3807 254.8 mm Air (20947304)..... PA3681 Steering (1902137)..... P106-HD
338 w/OM326 Eng. Fuel Ele. (4220900051)..... F950-F Steering (4660004)..... PT691		
Sprinter 408 CDI, 411 CDI, 413 CDI, 416 CDI w/OM611, OM612 Eng. Lube (Mann HU718/1k)..... P1443 Fuel (Mann WK842/13)..... BF7756 Air (Mann C32338)..... PA4600 Air (High Capacity) (Mann C32338/1)..... PA4601 Cab Air (Mann CU3858)..... PA4489		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ Trucks, Vans (cont'd)	MERCEDES-BENZ Trucks, Vans (cont'd)	MERCEDES-BENZ Trucks, Vans (cont'd)
810, 811 w/OM346, OM352 Engs. Lube (OM346 Eng.)..... P52 199.2 mm Lube (OM352 Eng.) 1978-on..... P7015 203.2 mm Lube (OM352 Eng.) To 1978..... P52 Fuel (3440927005)..... [2] PF834 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10945204)..... PA2405 383.4 mm Air (10941004)..... PA2847 Steering (1902137)..... P106-HD	814D 136.5 mm Lube (3661840225).... P7017 169.9 mm Lube..... P7615 193.7 mm Lube..... P102 193.7 mm Lube..... P102 Fuel Ele. (4220900051)..... F950-F 88.1 mm Fuel Spin-on (109204401)..... BF1056 155.6 mm Fuel Spin-on..... BF587-D + 220.7 mm Air (10946504)..... PA3807 254.8 mm Air (20947304)..... PA3681 81.0 mm Height Air Panel (20949304)..... PA3843 Steering (1902137)..... P106-HD	913 w/OM352X Eng. B-P Lube (1845825)..... P41 Fuel (3524700092)..... F834-F Air (10949404)..... PA3807 Steering (4660604)..... P106-HD
811D 136.5 mm Lube (3661840225).... P7017 169.9 mm Lube..... P7615 193.7 mm Lube..... P102 Fuel Ele. (4220900051)..... F950-F 88.1 mm Fuel Spin-on (109204401)..... BF1056 155.6 mm Fuel Spin-on..... BF587-D + 220.7 mm Air (10946504)..... PA3807 254.8 mm Air (20947304)..... PA3681 81.0 mm Height Air Panel (20949304)..... PA3843 Steering (1902137)..... P106-HD	814D w/OM364LA Eng. Lube..... P7017 Fuel..... F834-F Air (20949304)..... PA3843	914 83.3 mm O.D. Lube (4411800109)..... P7016 84.1 mm O.D. Lube (11844325).. P7015 169.9 mm Lube..... P7615 188.1 mm Lube (11840225)..... P242 Fuel Ele. (4220900051)..... F950-F Air (20947304)..... PA3681 Air Panel (20949304)..... PA3843
811D w/OM364A Eng. Lube..... P7017 Fuel..... F834-F Air (4/86-on) (20949304)..... PA3843	817 w/OM366A Eng. Lube (To Eng. S/N 923826) (4011800009)..... P242 Lube (Eng. S/N 923827-up) (3661840125)..... P7305 Fuel (3524700092)..... [2] F834-F 254.0 mm Air (10949304)..... PA2812 356.4 mm Air (20942404)..... PA2955 90 381.0 mm Air (10944704)..... PA2474 Steering (4660604)..... P106-HD	914 w/OM366 Eng. Lube (To Eng. S/N 915577) (3661840125)..... P7305 Lube (Eng. S/N 915577-up) (3141800109)..... P7017 Fuel..... F834-F Air (20947304)..... PA3681 Steering (1902137)..... P106-HD
813 w/OM352X Eng. B-P Lube (1845825)..... P41 Fuel (3524700092)..... F834-F Air (10949404)..... PA3807 Steering (4660604)..... P106-HD	817D 83.3 mm O.D. Lube (4411800109)..... P7016 84.1 mm O.D. Lube (11844325).. P7015 169.9 mm Lube..... P7615 Fuel Ele. (4220900051)..... F950-F 254.0 mm Air (10949304)..... PA2812 356.4 mm Air (20942404)..... PA2955 90 381.0 mm Air (1094474)..... PA2474 Air Panel (20949304)..... PA3843 Steering (1902137)..... P106-HD	917 w/OM366A Eng. Lube (To Eng. S/N 923826) (4011800009)..... P242 Lube (Eng. S/N 923827-up) (3661840125)..... P7305 Fuel (3524700092)..... [2] F834-F 254.0 mm Air (10949304)..... PA2812 356.4 mm Air (20942404)..... PA2955 90 381.0 mm Air (10944704)..... PA2474 Steering (4660604)..... P106-HD
813D 136.5 mm Lube (3661840225).... P7017 169.9 mm Lube..... P7615 193.7 mm Lube..... P102 Fuel Ele. (4220900051)..... F950-F 88.1 mm Fuel Spin-on (109204401)..... BF1056 155.6 mm Fuel Spin-on..... BF587-D + 220.7 mm Air (10946504)..... PA3807 254.8 mm Air (20947304)..... PA3681 81.0 mm Height Air Panel (20949304)..... PA3843 Steering (1902137)..... P106-HD	911 w/OM346, OM352 Engs. Lube (OM346 Eng.)..... P52 Lube (OM352 Eng.) To 1978..... P52 Lube (OM352 Eng.) 1978-on..... P7015 Fuel (3440927005)..... [2] PF834 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10945204)..... PA2405 383.4 mm Air (10941004)..... PA2847 Steering (1902137)..... P106-HD	917D 83.3 mm O.D. Lube (4411800109)..... P7016 84.1 mm O.D. Lube (11844325).. P7015 169.9 mm Lube..... P7615 Fuel Ele. (4220900051)..... F950-F 254.0 mm Air (10949304)..... PA2812 356.4 mm Air (20942404)..... PA2955 90 381.0 mm Air (1094474)..... PA2474 Air Panel (20949304)..... PA3843 Steering (1902137)..... P106-HD
814 w/OM366 Eng. Lube (To Eng. S/N 915577) (3661840125)..... P7305 Lube (Eng. S/N 915577-up) (3141800109)..... P7017 Fuel..... F834-F Air (20947304)..... PA3681 Steering..... P106-HD	912 83.3 mm O.D. Lube (4411800109)..... P7016 84.1 mm O.D. Lube (11844325).. P7015 169.9 mm Lube..... P7615 188.1 mm Lube (11840225)..... P242 Fuel Ele. (4220900051)..... F950-F Air (20947304)..... PA3681 Air Panel (20949304)..... PA3843	1013 w/OM346 Eng. B-P Lube (1846725)..... P42 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604).... P106-HD 115.9 mm Steering (4660004).... PT691

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.

Check Original Equipment Numbers In Parentheses.




**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ Trucks, Vans (cont'd)	MERCEDES-BENZ Trucks, Vans (cont'd)	MERCEDES-BENZ Trucks, Vans (cont'd)
1013 w/OM352 Eng. Lube (To 1977) (1846725)..... P42 Lube (1978-on) (11844325)..... P7015 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691	1113 w/OM355 Eng. (Cont'd) 115.9 mm Steering (4660004)..... PT691 1114 w/OM366 Eng. Lube (To Eng. S/N 915577) (3661840125)..... P7305 Lube (Eng. S/N 915577-up) (3141800109)..... P7017 Fuel..... F834-F Air (20947304)..... PA3681 Steering (4660604)..... P106-HD 1117 w/OM366A Eng. 136.5 mm Lube Ele. (1992-on).... P7017 188.1 mm Lube Ele. (4011800009)..... P242 199.2 mm Lube Ele..... P7015 Fuel..... F834-F 381.0 mm Air (10944704)..... PA2474 254.0 mm O. Air..... PA2812 356.4 mm Some O. Air (1989-on) ..... PA2955 <sup>90</sup> Steering..... P106-HD 1120 w/OM366LA Eng. Lube (To Eng. S/N 923826) (4011800009)..... P242 Lube (Eng. S/N 923827-up) (3661840125)..... P7305 Fuel (3524700092)..... [2] F834-F Air (10944704)..... PA2474 Air (10949304)..... PA2812 Steering (4660604)..... P106-HD 1213 w/OM346 Eng. B-P Lube (1846725)..... P42 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691 1113 w/OM346 Eng. B-P Lube (1846725)..... P42 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691 1113 w/OM352 Eng. Lube (To 1977) (1846725)..... P42 Lube (1978-on) (11844325)..... P7015 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691 1113 w/OM355 Eng. Lube (To 3/78) (1846725)..... P42 Lube (4/78-on) (11845625)..... P7052 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691 1213 w/OM355 Eng. Lube (To 3/78) (1846725)..... P42 Lube (4/78-on) (11845625)..... P7052 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691	1213 w/OM355 Eng. (Cont'd) 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691 1219 w/OM401 Eng. Lube (4011800009)..... P242 Fuel (3524700092)..... [2] F834-F Air (9/73-on) (10949304)..... PA2812 Steering (4660004)..... PT691 1222 w/OM421 Eng. Lube (4031840025)..... P294 Fuel Ele. (4220900051)..... F950-F Air (5/82-on) (10949304)..... PA2812 Steering..... P106-HD 1222 w/OM441 Eng. Lube (4011800009)..... P242 Fuel Ele. (4220900051)..... F950-F Air..... PA2942 Steering..... P106-HD 1313 w/OM346 Eng. B-P Lube (1846725)..... P42 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691 1313 w/OM352 Eng. Lube (To 1977) (1846725)..... P42 Lube (1978-on) (11844325)..... P7015 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691 1313 w/OM355 Eng. Lube (To 3/78) (1846725)..... P42 Lube (4/78-on) (11845625)..... P7052 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691

<sup>90</sup> Obsolete Pending.

Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



MERCEDES-BENZ Trucks, Vans (cont'd)	MERCEDES-BENZ Trucks, Vans (cont'd)	MERCEDES-BENZ Trucks, Vans (cont'd)
1314 w/OM366 Eng. Lube (To Eng. S/N 915577) (3661840125)..... P7305 Lube (Eng. S/N 915577-up) (3141800109)..... P7017 Fuel..... F834-F Air (20947304)..... PA3681 Steering (4660604)..... P106-HD	1319 w/190E, OM366LA Engs. Lube (31841701)..... B263 1319 w/OM352 Eng. Lube (To 1977) (1846725)..... P42 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691	1413 w/OM352 Eng. Lube (To 1977) (1846725)..... P42 Lube (1978-on) (11844325)..... P7015 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691
1317 w/OM346 Eng. B-P Lube (1846725)..... P42 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691	1319 w/OM355 Eng. Lube (To 3/78) (1846725)..... P42 Lube (4/78-on) (11845625)..... P7052 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691	1413 w/OM355 Eng. Lube (To 3/78) (1846725)..... P42 Lube (4/78-on) (11845625)..... P7052 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691
1317 w/OM352 Eng. Lube (To 1977) (1846725)..... P42 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691	1319 w/OM360 Eng. B-P Lube..... P52 Fuel Ele. (4220900051)..... F950-F Air (10941004)..... PA2847 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691	1414 w/OM366 Eng. Lube (To Eng. S/N 915577) (3661840125)..... P7305 Lube (Eng. S/N 915577-up) (3141800109)..... P7017 Fuel (3524700092)..... F834-F 220.7 mm Air (10949404)..... PA3807 254.0 mm Air (10949304)..... PA2812 Steering (4660604)..... P106-HD
1317 w/OM355 Eng. Lube (To 4/78) (1846725)..... P42 Lube (4/78-on) (11845625)..... P7052 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691	1320 w/OM366LA Eng. Lube (To Eng. S/N 923826) (4011800009)..... P242 Lube (Eng. S/N 923827-up) (3661840125)..... P7305 Fuel (3524700092)..... [2] F834-F 254.0 mm Air (10949304)..... PA2812 381.0 mm Air (10944704)..... PA2474 Steering (4660604)..... P106-HD	1417 w/OM366A Eng. 136.5 mm Lube Ele. (1992-on) (3661840225)..... P7017 188.1 mm Lube Ele. (4011800009)..... P242 199.2 mm Lube Ele..... P7015 Fuel..... F834-F 254.0 mm O. Air (10943304)..... PA2812 356.4 mm Some O. Air (1989-on) ..... PA2955 <sup>90</sup> 381.0 mm Air (10944704)..... PA2474 Steering (1902137)..... P106-HD
1317 w/OM366A Eng. 136.5 mm Lube Ele. (1992-on) (3661840225)..... P7017 188.1 mm Lube Ele. (4011800009)..... P242 199.2 mm Lube Ele..... P7015 Fuel..... F834-F 254.0 mm O. Air (10943304)..... PA2812 356.4 mm Some O. Air (1989-on) ..... PA2955 <sup>90</sup> 381.0 mm Air (10944704)..... PA2474 Steering (1902137)..... P106-HD	1324 w/OM366LA Eng. (1990) Lube..... P7015 Fuel (3524700092)..... F834-F 254.0 mm Air (10949304)..... PA2812 381.0 mm Air (10944704)..... PA2474 Steering (4660204)..... P106-HD	1418 w/OM346 Eng. B-P Lube (1846725)..... P42 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691
	1413 w/OM346 Eng. B-P Lube (1846725)..... P42 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691	

<sup>90</sup> Obsolete Pending.

Check Original Equipment Numbers In Parentheses.




**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

Trucks & Buses Applications **BALDWIN FILTERS**

MERCEDES-BENZ Trucks, Vans (cont'd)	MERCEDES-BENZ Trucks, Vans (cont'd)	MERCEDES-BENZ Trucks, Vans (cont'd)
1418 w/OM352 Eng. Lube (To 1977) (1846725)..... P42 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604).... P106-HD 115.9 mm Steering (4660004).... PT691	1424 w/OM355 Eng. Lube (To 4/78) (1846725)..... P42 Lube (4/78-on) (11845625)..... P7052 Fuel Ele. (4220900051)..... F950-F Air (10941004)..... PA2847 100.8 mm Steering (4660604).... P106-HD 115.9 mm Steering (4660004).... PT691	1513 w/OM355 Eng. (Cont'd) 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604).... P106-HD 115.9 mm Steering (4660004).... PT691
1418 w/OM355 Eng. Lube (To 3/78) (1846725)..... P42 Lube (4/78-on) (11845625)..... P7052 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604).... P106-HD 115.9 mm Steering (4660004).... PT691	1424 w/OM402 Eng. 188.1 mm Lube (4011800009).... P242 264.3 mm Lube (4031840025).... P294 136.5 mm Some Lube..... P7017 Fuel (3524700092)..... [2] F834-F Air (1973-on) (10949304)..... PA2812 Steering (4660004)..... PT691	1514 w/OM366 Eng. Lube (To Eng. S/N 915577) (3661840125)..... P7305 Lube (Eng. S/N 915577-up) (3141800109)..... P7017 Fuel (3524700092)..... F834-F 220.7 mm Air (10949404)..... PA3807 254.0 mm Air (10949304)..... PA2812 Steering (4660604)..... P106-HD
1419 w/OM362LA Eng. Lube (3661800009)..... P7015 Fuel (3524700092)..... F834-F Air (10949304)..... PA2812 Steering (4660204)..... P106-HD	1425 w/OM422 Eng. F-F Lube (4031840025)..... P294 Fuel (To 7/82) (3524700092).... [2] F834-F Fuel Ele. (7/82-on) (4220900051) [2] F950-F Air (10949304)..... PA2812 Steering (4660604)..... P106-HD	1517 w/OM346 Eng. B-P Lube (1846725)..... P42 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604).... P106-HD 115.9 mm Steering (4660004).... PT691
1419 w/OM366 Eng. Lube Spin-on (31841701)..... B263 Fuel (922705)..... PF834	1426 w/OM442 Eng. Lube (To 7/90)..... P294 Lube (7/90-on) (4411800009).... P7016 Fuel Ele..... F950-F O. Air (30944204)..... PA2942 Steering..... P106-HD	1517 w/OM352 Eng. Lube (To 1977) (1846725)..... P42 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604).... P106-HD 115.9 mm Steering (4660004).... PT691
1419 w/OM401 Eng. Lube (4011800009)..... P242 Fuel (3524700092)..... [2] F834-F Air (9/73-on) (10949304)..... PA2812 Steering (4660004)..... PT691	1426 w/OM442 Eng. Lube (To 7/90)..... P294 Lube (7/90-on) (4411800009).... P7016 Fuel Ele..... F950-F O. Air (30944204)..... PA2942 Steering..... P106-HD	1517 w/OM355 Eng. Lube (To 4/78) (1846725)..... P42 Lube (4/78-on) (11845625)..... P7052 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604).... P106-HD 115.9 mm Steering (4660004).... PT691
1420 w/OM366LA Eng. Lube (To Eng. S/N 923826) (4011800009)..... P242 Lube (Eng. S/N 923827-up) (3661840125)..... P7305 Fuel (3524700092)..... [2] F834-F 254.0 mm Air (10949304)..... PA2812 381.0 mm Air (10944704)..... PA2474 Steering (4660604)..... P106-HD	1426 w/OM442 Eng. Lube (4031840025)..... P294 Fuel Ele. (4220900051)..... F950-F Air (5/82-on) (10949304)..... PA2812 Steering (1902137)..... P106-HD	1517 w/OM366A Eng. 136.5 mm Lube Ele. (1992-on) (3661840225)..... P7017 188.1 mm Lube Ele. (4011800009)..... P242 199.2 mm Lube Ele..... P7015 Fuel..... F834-F 254.0 mm O. Air (10943304)..... PA2812 356.4 mm Some O. Air (1989-on) ..... PA2955 <sup>90</sup> 381.0 mm Air (10944704)..... PA2474
1422 w/OM421 Eng. Lube (4031840025)..... P294 Fuel Ele. (4220900051)..... F950-F Air (5/82-on) (10949304)..... PA2812 Steering (1902137)..... P106-HD	1426 w/OM441 Eng. Lube (4011800009)..... P242 Fuel Ele. (4220900051)..... F950-F Air (30944204)..... PA2942 Steering (1902137)..... P106-HD	
1422 w/OM441 Eng. Lube (4011800009)..... P242 Fuel Ele. (4220900051)..... F950-F Air (30944204)..... PA2942 Steering (1902137)..... P106-HD	1426 w/OM441 Eng. Lube (4011800009)..... P242 Fuel Ele. (4220900051)..... F950-F Air (30944204)..... PA2942 Steering (1902137)..... P106-HD	
	1513 w/OM355 Eng. Lube (To 4/78) (1846725)..... P42 Lube (4/78-on) (11845625)..... P7052 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405	

<sup>90</sup> Obsolete Pending.

Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ Trucks, Vans (cont'd)	MERCEDES-BENZ Trucks, Vans (cont'd)	MERCEDES-BENZ Trucks, Vans (cont'd)
1517 w/OM366A Eng. (Cont'd)	1519 w/OM355 Eng.	1619 w/OM346 Eng. (Cont'd)
Steering (1902137)..... P106-HD	Lube (To 4/78) (1846725)..... P42	115.9 mm Steering (4660004)..... PT691
1518 w/OM346 Eng.	Lube (4/78-on) (11845625)..... P7052	1619 w/OM352 Eng.
B-P Lube (1846725)..... P42	114.3 mm Fuel Ele.	Lube (To 1977) (1846725)..... P42
(3524700092)..... F834-F	(3524700092)..... F834-F	114.3 mm Fuel Ele.
114.3 mm Fuel Ele.	142.9 mm Fuel Ele.	(3524700092)..... F834-F
(4220900051)..... F950-F	(4220900051)..... F950-F	142.9 mm Fuel Ele.
220.7 mm Air (10949404)..... PA3807	220.7 mm Air (10949404)..... PA3807	(4220900051)..... F950-F
374.7 mm Air (10944204)..... PA2405	374.7 mm Air (10944204)..... PA2405	220.7 mm Air (10949404)..... PA3807
383.4 mm Air (10941004)..... PA2847	383.4 mm Air (10941004)..... PA2847	374.7 mm Air (10944204)..... PA2405
100.8 mm Steering (4660604)..... P106-HD	100.8 mm Steering (4660604)..... P106-HD	383.4 mm Air (10941004)..... PA2847
115.9 mm Steering (4660004)..... PT691	115.9 mm Steering (4660004)..... PT691	100.8 mm Steering (4660604)..... P106-HD
1518 w/OM352 Eng.	1520 w/OM366LA Eng.	115.9 mm Steering (4660004)..... PT691
Lube (To 1977) (1846725)..... P42	Lube (To Eng. S/N 923826)	1619 w/OM355 Eng.
114.3 mm Fuel Ele.	(4011800009)..... P242	Lube (To 4/78) (1846725)..... P42
(3524700092)..... F834-F	Lube (Eng. S/N 923827-up)	Lube (4/78-on) (11845625)..... P7052
142.9 mm Fuel Ele.	(3661840125)..... P7305	114.3 mm Fuel Ele.
(4220900051)..... F950-F	Fuel (3524700092)..... [2] F834-F	(3524700092)..... F834-F
220.7 mm Air (10949404)..... PA3807	254.0 mm Air (10949304)..... PA2812	142.9 mm Fuel Ele.
374.7 mm Air (10944204)..... PA2405	381.0 mm Air (10944704)..... PA2474	(4220900051)..... F950-F
383.4 mm Air (10941004)..... PA2847	Steering (4660604)..... P106-HD	220.7 mm Air (10949404)..... PA3807
100.8 mm Steering (4660604)..... P106-HD	1524 w/OM366LA Eng. (1990)	374.7 mm Air (10944204)..... PA2405
115.9 mm Steering (4660004)..... PT691	Lube..... P7015	383.4 mm Air (10941004)..... PA2847
1518 w/OM355 Eng.	Fuel (3524700092)..... F834-F	100.8 mm Steering (4660604)..... P106-HD
Lube (To 4/78) (1846725)..... P42	254.0 mm Air (10949304)..... PA2812	115.9 mm Steering (4660004)..... PT691
Lube (4/78-on) (11845625)..... P7052	381.0 mm Air (10944704)..... PA2474	1619 w/OM360 Eng.
114.3 mm Fuel Ele.	Steering (4660204)..... P106-HD	B-P Lube (1846725)..... P42
(3524700092)..... F834-F	1614 w/OM366 Eng.	Fuel Ele. (4220900051)..... F950-F
142.9 mm Fuel Ele.	Lube (To Eng. S/N 915577)	Air (10941004)..... PA2847
(4220900051)..... F950-F	(3661840125)..... P7305	100.8 mm Steering (4660604)..... P106-HD
220.7 mm Air (10949404)..... PA3807	Lube (Eng. S/N 915577-up)	115.9 mm Steering (4660004)..... PT691
374.7 mm Air (10944204)..... PA2405	(3141800109)..... P7017	1619 w/OM362LA Eng.
383.4 mm Air (10941004)..... PA2847	Fuel (3524700092)..... F834-F	Lube (3661800009)..... P7015
100.8 mm Steering (4660604)..... P106-HD	220.7 mm Air (10949404)..... PA3807	Fuel (3524700092)..... F834-F
115.9 mm Steering (4660004)..... PT691	254.0 mm Air (10949304)..... PA2812	Air (10949304)..... PA2812
1519 w/OM346 Eng.	Steering (4660604)..... P106-HD	Steering (4660204)..... P106-HD
B-P Lube (1846725)..... P42	1617 w/OM366A Eng.	1619 w/OM401 Eng.
114.3 mm Fuel Ele.	136.5 mm Lube Ele. (1992-on)	Lube (4011800009)..... P242
(3524700092)..... F834-F	(3661840225)..... P7017	Fuel (3524700092)..... [2] F834-F
142.9 mm Fuel Ele.	188.1 mm Lube Ele.	Air (9/73-on) (10949304)..... PA2812
(4220900051)..... F950-F	(4011800009)..... P242	Steering (4660004)..... PT691
220.7 mm Air (10949404)..... PA3807	199.2 mm Lube Ele. .... P7015	1620 w/OM346 Eng.
374.7 mm Air (10944204)..... PA2405	Fuel..... F834-F	B-P Lube (1846725)..... P42
383.4 mm Air (10941004)..... PA2847	254.0 mm O. Air (10943304)..... PA2812	114.3 mm Fuel Ele.
100.8 mm Steering (4660604)..... P106-HD	356.4 mm Some O. Air (1989-on)	(3524700092)..... F834-F
115.9 mm Steering (4660004)..... PT691	..... PA2955 <sup>90</sup>	142.9 mm Fuel Ele.
1519 w/OM352 Eng.	381.0 mm Air (10944704)..... PA2474	(4220900051)..... F950-F
Lube (To 1977) (1846725)..... P42	Steering (1902137)..... P106-HD	220.7 mm Air (10949404)..... PA3807
114.3 mm Fuel Ele.	1619 w/OM346 Eng.	374.7 mm Air (10944204)..... PA2405
(3524700092)..... F834-F	B-P Lube (1846725)..... P42	383.4 mm Air (10941004)..... PA2847
142.9 mm Fuel Ele.	114.3 mm Fuel Ele.	100.8 mm Steering (4660604)..... P106-HD
(4220900051)..... F950-F	(3524700092)..... F834-F	115.9 mm Steering (4660004)..... PT691
220.7 mm Air (10949404)..... PA3807	142.9 mm Fuel Ele.	1620 w/OM352 Eng.
374.7 mm Air (10944204)..... PA2405	(4220900051)..... F950-F	Lube (To 1978) (1846725)..... P42
383.4 mm Air (10941004)..... PA2847	220.7 mm Air (10949404)..... PA3807	Lube (1978-on) (11844325)..... P7015
100.8 mm Steering (4660604)..... P106-HD	374.7 mm Air (10944204)..... PA2405	114.3 mm Fuel Ele.
115.9 mm Steering (4660004)..... PT691	383.4 mm Air (10941004)..... PA2847	(3524700092)..... F834-F
1519 w/OM346 Eng.	100.8 mm Steering (4660604)..... P106-HD	
B-P Lube (1846725)..... P42		
114.3 mm Fuel Ele.		
(3524700092)..... F834-F		
142.9 mm Fuel Ele.		
(4220900051)..... F950-F		
220.7 mm Air (10949404)..... PA3807		
374.7 mm Air (10944204)..... PA2405		
383.4 mm Air (10941004)..... PA2847		
100.8 mm Steering (4660604)..... P106-HD		
115.9 mm Steering (4660004)..... PT691		


<sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ Trucks, Vans (cont'd)	MERCEDES-BENZ Trucks, Vans (cont'd)	MERCEDES-BENZ Trucks, Vans (cont'd)
1620 w/OM352 Eng. (Cont'd) 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691	1621 w/OM355 Eng. (Cont'd) 114.3 mm Fuel Ele. (3524700092)..... F834-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691	1624 w/OM355 Eng. (Cont'd) 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691
1620 w/OM355 Eng. Lube (To 4/78)..... P52 Lube (4/78-on)..... P7052 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691	1622 w/OM421 Eng. Lube (4031840025)..... P294 Fuel Ele. (4220900051)..... F950-F Air (5/82-on) (10949304)..... PA2812 Steering (1902137)..... P106-HD	1624 w/OM402 Eng. 188.1 mm Lube (4011800009)..... P242 264.3 mm Lube (4031840025)..... P294 136.5 mm Some Lube (3661840225)..... P7017 Fuel (3524700092)..... [2] F834-F Air (1973-on) (10949304)..... PA2812 Steering (4660004)..... PT691
1620 w/OM366LA Eng. Lube (To Eng. S/N 923826) (4011800009)..... P242 Lube (Eng. S/N 923827-up) (3661840125)..... P7305 Fuel (3524700092)..... [2] F834-F 254.0 mm Air (10949304)..... PA2812 381.0 mm Air (10944704)..... PA2474 Steering (4660604)..... P106-HD	1622 w/OM441 Eng. Lube (4011800009)..... P242 Fuel Ele. (4220900051)..... F950-F Air (30944204)..... PA2942 Steering (1902137)..... P106-HD	1625 w/OM422 Eng. F-F Lube (4031840025)..... P294 Fuel (To 7/82) (3524700092)..... [2] F834-F Fuel Ele. (7/82-on) (4220900051) [2] F950-F Air (10949304)..... PA2812 Steering (4660604)..... P106-HD
1621 w/OM346 Eng. B-P Lube (1846725)..... P42 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691	1623 w/OM346 Eng. B-P Lube (1846725)..... P42 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691	1626 w/OM402, OM403 Eng. 188.1 mm Lube (4011800009)..... P242 264.3 mm Lube (4031840025)..... P294 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F Air (10949304)..... PA2812 Steering (4660004)..... PT691
1621 w/OM346 Eng. B-P Lube (1846725)..... P42 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691	1623 w/OM352 Eng. Lube (To 1978) (1846725)..... P42 Lube (1978-on) (11844325)..... P7015 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691	1628 w/OM422 Eng. Lube (4021800009)..... P294 Fuel (To 7/82) (3524700092)..... [2] F834-F Fuel Ele. (7/82-on) (4220900051) [2] F950-F 254.0 mm Air (10949304)..... PA2812 255.6 mm Some Air..... PA2838 Steering (4660604)..... P106-HD
1621 w/OM352 Eng. Lube (To 1978) (1846725)..... P42 Lube (1978-on) (11844325)..... P7015 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691	1623 w/OM355 Eng. Lube (To 4/78) (1846725)..... P42 Lube (4/78-on) (11845625)..... P7052 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691	1629 Air (30944204)..... PA2942
1621 w/OM355 Eng. Lube Ele. (To 3/78) (1846725)..... P42 Lube Ele. (3/78-on) (3551800009)..... P7052 142.9 mm Fuel Ele. (4220900051)..... F950-F	1624 w/OM355 Eng. Lube (To 4/78) (1846725)..... P42 Lube (4/78-on) (11845625)..... P7052 Fuel Ele. (4220900051)..... F950-F Air (10941004)..... PA2847	1632 w/OM403 Eng. F-F Lube (4031840025)..... P294 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele..... F950-F Air (1973-on) (10948304)..... PA2838 Steering (4660004)..... PT691
		1633 w/OM422A Eng. Lube (4031840025)..... P294 Fuel Ele. (4220900051)..... [2] F950-F Air..... PA2955 <sup>90</sup> Steering (4660604)..... P106-HD
		1635 w/OM442A, OM442LA Eng. Lube (To 8/90) (4021800009)..... P294 Lube (8/90-on) (4411800009)..... P7016 Fuel Ele. (4220900051)..... F950-F O. Air (5/88-on) (30941504)..... PA2776 Air (To 4/88) (20942404)..... PA2955 <sup>90</sup> 374.7 mm Some Air (9/88-on) (20940004)..... PA2405 255.6 mm Some Air (30944204)..... PA2942 Steering..... P106-HD

<sup>90</sup> Obsolete Pending.

Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ Trucks, Vans (cont'd)	MERCEDES-BENZ Trucks, Vans (cont'd)	MERCEDES-BENZ Trucks, Vans (cont'd)
1636 w/OM423 Eng. Lube (4031840025)..... P294 Fuel Ele. (4220900051)..... [2] F950-F Air (10948304)..... PA2838 Hyd..... P106-HD	1729 w/OM442 Eng. Lube (To 8/90) (4021800009)..... P294 Lube (8/90-on) (4411800009)..... P7016 Fuel Ele..... [2] F950-F Air (30944204)..... PA2942 Steering (4660604)..... P106-HD	1813 w/OM355 Eng. (Cont'd) 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691
1638 w/OM422LA Eng. Lube (4021800009)..... P294 Fuel Ele. (4220900051)..... [2] F950-F Air (20942404)..... PA2955 <sup>90</sup> Steering (4660604)..... P106-HD	1733 w/OM441LA Eng. (1988) Lube (4411800009)..... P7016 Fuel Ele..... F950-F 255.6 mm Air (30944204)..... PA2942 473.9 mm Air (30941504)..... PA2776 Steering..... P106-HD	1816 w/OM366A Eng. (1992) Lube (To Eng. S/N 28611)..... P7015 Some Lube (To Eng. S/N 28611)..... P7017
1644 w/OM442LA Eng. Lube (To 8/90) (4031840025)..... P294 Lube (8/90-on) (4411800009)..... P7016 Fuel Ele..... F834-F Air (To S/N 5343252)..... PA2955 <sup>90</sup> Air (S/N 5343252-up) (30941504)..... PA2776 254.8 mm Air..... PA3681 479.4 mm Air (30947004)..... PA3765 Steering (4660604)..... P106-HD	1735 w/OM442A, OM442LA Eng. Lube (To 8/90) (4021800009)..... P294 Lube (8/90-on) (4411800009)..... P7016 Fuel Ele. (4220900051)..... F950-F O. Air (5/88-on) (30941504)..... PA2776 Air (To 4/88) (20942404)..... PA2955 <sup>90</sup> Some Air (9/88-on) (20940004)..... PA2405 Some Air (30944204)..... PA2942 Steering (1902137)..... P106-HD	1819 w/OM346 Eng. B-P Lube (1846725)..... P42 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691
1717 w/OM366A Eng. 136.5 mm Lube Ele. (1992-on) (3661840225)..... P7017 188.1 mm Lube Ele. (4011800009)..... P242 199.2 mm Lube Ele..... P7015 Fuel..... F834-F 381.0 mm Air (10944704)..... PA2474 254.0 mm O. Air (10943304)..... PA2812 356.4 mm Some O. Air (1989-on)..... PA2955 <sup>90</sup> Steering (1902137)..... P106-HD	1748 w/OM442A Eng. Lube (To 8/90) (4021800009)..... P294 Lube (8/90-on) (4411800009)..... P7016 Fuel (3524700092)..... F834-F O. Air (30941504)..... PA2776 Air (1988-on) (20942404)..... PA2955 <sup>90</sup> Steering (4660604)..... P106-HD	1819 w/OM352 Eng. Lube (To 1977) (1846725)..... P42 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691
1719 w/OM401 Eng. Lube (4011800009)..... P242 Fuel (3524700092)..... [2] F834-F Air (9/73-on) (10949304)..... PA2812 Steering (4660004)..... PT691	1813 w/OM346 Eng. B-P Lube (1846725)..... P42 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691	1819 w/OM355 Eng. Lube (To 4/78) (1846725)..... P42 Lube (4/78-on) (11845625)..... P7052 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691
1720, 1720A w/OM366LA Eng. Lube (To Eng. S/N 923827) (4011800009)..... P242 Lube (Eng. S/N 923827-up) (3661840125)..... P7305 Fuel (3524700092)..... [2] F834-F 254.0 mm Air (10949304)..... PA2812 381.0 mm Air (10944704)..... PA2474 Steering (4660604)..... P106-HD	1813 w/OM352 Eng. Lube (To 1978) (1846725)..... P42 Lube (1978-on) (11844325)..... P7015 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691	1819 w/OM360 Eng. B-P Lube (1846725)..... P42 Fuel Ele. (4220900051)..... F950-F Air (10941004)..... PA2847 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691
1722SK w/OM441 Eng. Lube (4411800009)..... P7016 Fuel Ele..... F950-F Air..... PA2942 Steering..... P106-HD	1813 w/OM355 Eng. Lube (To 4/78) (1846725)..... P42 Lube (4/78-on) (11845625)..... P7052 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F	1820 w/OM366LA Eng. Lube (To Eng. S/N 923826) (4011800009)..... P242 Lube (Eng. S/N 923827-up) (3661840125)..... P7305 Fuel (3524700092)..... [2] F834-F 254.0 mm Air (10949304)..... PA2812 381.0 mm Air (10944704)..... PA2474
1726 w/OM442 Eng. Lube (To 7/90)..... P294 Lube (7/90-on) (4411800009)..... P7016 Fuel Ele..... F950-F O. Air (30944204)..... PA2942 Steering (1902137)..... P106-HD		

<sup>90</sup> Obsolete Pending.


Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ Trucks, Vans (cont'd)	MERCEDES-BENZ Trucks, Vans (cont'd)	MERCEDES-BENZ Trucks, Vans (cont'd)
1820 w/OM366LA Eng. (Cont'd) Steering (4660604)..... P106-HD	Actros II 1846L w/OM501LA Eng. F-F Lube (5411800009)..... P7192	1921 w/OM346 Eng. B-P Lube (1846725)..... P42
1821 w/OM366A Eng. (1993) Lube..... P7016 Fuel..... F834-F Air..... PA2942	Fuel (5410920305)..... PF7761 Fuel/Water Separator..... BF1363 Panel Air (30949004)..... PA5426 261.9 mm Air (A0030949204)..... PA3838 <sup>90</sup> 318.3 mm Air (A0030949104)..... PA3844 496.9 mm Air (10947904)..... PA2475 Radial Seal Air (40940204)..... RS5343 Cab Air (Mann CU3869)..... PA4956 Air Dryer (Mann TB1374X)..... BA5374 + Trans. (Mann H613x)..... PT9423 Steering (1902137)..... P106-HD	114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691
1827 w/OM401A Eng. Lube (4411800009)..... P7016 Fuel Ele..... F950-F Air..... PA2942	Actros II 1846LL w/OM501LA Eng. F-F Lube (5411800009)..... P7192 Fuel (5410920305)..... PF7761 Fuel/Water Separator..... BF1363 261.9 mm Air (A0030949204)..... PA3838 <sup>90</sup> 318.3 mm Air (A0030949104)..... PA3844 496.9 mm Air (10947904)..... PA2475 Panel Air (30949004)..... PA5426 Radial Seal Air (40940204)..... RS5343 Cab Air (Mann CU3869)..... PA4956 Air Dryer (Mann TB1374X)..... BA5374 + Trans. (Mann H613x)..... PT9423 Steering (1902137)..... P106-HD	1921 w/OM352 Eng. Lube (To 1978) (1846725)..... P42 Lube (1978-on) (11844325)..... P7015 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691
1827 w/OM401LA Eng. Lube..... P7016 Fuel..... F834-F Air..... PA2942	Actros I 1835LS w/OM501LA Eng. F-F Lube (5411800009)..... P7192 Fuel (5410920305)..... PF7761 Radial Seal Air (40940204)..... RS5343 261.9 mm Air (A0030949204)..... PA3838 <sup>90</sup> 318.3 mm Air (A0030949104)..... PA3844 496.9 mm Air (10947904)..... PA2475 Panel Air (30949004)..... PA5426 Cab Air (Mann CU3869)..... PA4956 Trans. (Mann H613x)..... PT9423 Steering..... P106-HD	1921 w/OM355 Eng. Lube Ele. (To 3/78) (1846725)..... P42 Lube Ele. (3/78-on) (3551800009)..... P7052 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691
1831 w/OM401LA Eng. Lube (4411800009)..... P7016 Fuel..... F834-F Air (30944204)..... PA2942	Actros II 1846LS w/OM501LA Eng. F-F Lube (5411800009)..... P7192 Fuel (5410920305)..... PF7761 Fuel/Water Separator..... BF1363 261.9 mm Air (A0030949204)..... PA3838 <sup>90</sup> 318.3 mm Air (A0030949104)..... PA3844 496.9 mm Air (10947904)..... PA2475 Panel Air (30949004)..... PA5426 Radial Seal Air (40940204)..... RS5343 Cab Air (Mann CU3869)..... PA4956 Air Dryer (Mann TB1374X)..... BA5374 + Trans. (Mann H613x)..... PT9423 Steering (1902137)..... P106-HD	1922 w/OM421 Eng. Lube (4031840025)..... P294 Fuel Ele. (4220900051)..... F950-F Air (5/82-on) (10949304)..... PA2812 Steering (1902137)..... P106-HD
1834 w/OM441LA Eng. Lube (4411800009)..... P7016 Fuel (4220900051)..... F834-F Air (30944204)..... PA2942	1850 w/OM402, OM442LA Engs. Lube (4411800009)..... P7016 Fuel..... F834-F 254.8 mm Air..... PA3681 255.6 mm Air (30944204)..... PA2942 473.9 mm Air (30941504)..... PA2776 479.4 mm Air (30947004)..... PA3765	1922 w/OM441 Eng. Lube (4011800009)..... P242 Fuel Ele. (4220900051)..... F950-F Air (30944204)..... PA2942 Steering (1902137)..... P106-HD
Actros I 1835LS w/OM501LA Eng. F-F Lube (5411800009)..... P7192 Fuel (5410920305)..... PF7761 Radial Seal Air (40940204)..... RS5343 261.9 mm Air (A0030949204)..... PA3838 <sup>90</sup> 318.3 mm Air (A0030949104)..... PA3844 496.9 mm Air (10947904)..... PA2475 Panel Air (30949004)..... PA5426 Cab Air (Mann CU3869)..... PA4956 Trans. (Mann H613x)..... PT9423 Steering..... P106-HD	1853 w/OM442LA Eng. Lube (4411800009)..... P7016 Fuel Ele..... F950-F Air (30947004)..... PA3765 Steering..... P106-HD	1922SK w/OM441 Eng. Lube (4411800009)..... P7016 Fuel Ele..... F950-F Air (30944204)..... PA2942 Steering (1902137)..... P106-HD
1838 w/OM402LA Eng. Lube (4411800009)..... P7016 Fuel..... F834-F 254.8 mm Air..... PA3681 255.6 mm Air (30944204)..... PA2942 473.9 mm Air (30941504)..... PA2776	1919 w/OM401 Eng. Lube (4011800009)..... P242 Fuel (3524700092)..... [2] F834-F Air (9/73-on) (10949304)..... PA2812 Steering (4660004)..... PT691	1923 w/OM346 Eng. B-P Lube (1846725)..... P42 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807
1840 w/OM402, OM442LA Engs. Lube (4411800009)..... P7016 Fuel..... F834-F 254.8 mm Air..... PA3681 255.6 mm Air (30944204)..... PA2942 473.9 mm Air (30941504)..... PA2776 479.4 mm Air (30947004)..... PA3765		
1844 w/OM442LA Eng. Lube (To 8/90) (4031840025)..... P294 Lube (8/90-on) (4411800009)..... P7016 Fuel Ele..... F834-F 254.8 mm Air..... PA3681 356.4 mm Air (To S/N 5343252) (20942404)..... PA2955 <sup>90</sup> 473.9 mm Air (S/N 5343252-up) (30941504)..... PA2776 479.4 mm Air (30947004)..... PA3765 Steering (4660604)..... P106-HD		

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ Trucks, Vans (cont'd)	MERCEDES-BENZ Trucks, Vans (cont'd)	MERCEDES-BENZ Trucks, Vans (cont'd)
1923 w/OM346 Eng. (Cont'd)	1932 w/OM403 Series Engs.	1948 w/OM442A Eng.
374.7 mm Air (10944204)..... PA2405	F-F Lube (4031840025)..... P294	Lube (To 8/90) (4021800009)..... P294
383.4 mm Air (10941004)..... PA2847	114.3 mm Fuel Ele. (3524700092)..... F834-F	Lube (8/90-on) (4411800009)..... P7016
100.8 mm Steering (4660604)..... P106-HD	142.9 mm Fuel Ele. Air (1973-on) (10948304)..... PA2838	Fuel (3524700092)..... F834-F
115.9 mm Steering (4660004)..... PT691	Steering (4660004)..... PT691	O. Air (30941504)..... PA2776
1923 w/OM352 Eng.	1933 w/OM422A Eng.	Single Air (1988-on) (20942404)..... PA2955 <sup>90</sup>
Lube (To 1978) (1846725)..... P42	Lube (4031840025)..... P294	Steering (4660604)..... P106-HD
Lube (1978-on) (11844325)..... P7015	Fuel Ele. (4220900051)..... [2] F950-F	2020 w/OM346 Eng.
114.3 mm Fuel Ele. (3524700092)..... F834-F	Air..... PA2955 <sup>90</sup>	B-P Lube (1846725)..... P42
142.9 mm Fuel Ele. (4220900051)..... F950-F	Steering (4660604)..... P106-HD	114.3 mm Fuel Ele. (3524700092)..... F834-F
220.7 mm Air (10949404)..... PA3807	1933 w/OM441LA Eng. (1988)	142.9 mm Fuel Ele. (4220900051)..... F950-F
374.7 mm Air (10944204)..... PA2405	Lube (4411800009)..... P7016	220.7 mm Air (10949404)..... PA3807
383.4 mm Air (10941004)..... PA2847	Fuel Ele..... F950-F	374.7 mm Air (10944204)..... PA2405
100.8 mm Steering (4660604)..... P106-HD	255.6 mm Air (30944204)..... PA2942	383.4 mm Air (10941004)..... PA2847
115.9 mm Steering (4660004)..... PT691	473.9 mm Air (30941504)..... PA2776	100.8 mm Steering (4660604)..... P106-HD
1923 w/OM355 Eng.	Steering (1902137)..... P106-HD	115.9 mm Steering (4660004)..... PT691
Lube (To 4/78) (1846725)..... P42	1935 w/OM442A, OM442LA Engs.	2020 w/OM352 Eng.
Lube (4/78-on) (11845625)..... P7052	Lube (To 8/90) (4021800009)..... P294	Lube (To 1978) (1846725)..... P42
114.3 mm Fuel Ele. (3524700092)..... F834-F	Lube (8/90-on) (4411800009)..... P7016	Lube (1978-on) (11844325)..... P7015
142.9 mm Fuel Ele. (4220900051)..... F950-F	Fuel Ele. (4220900051)..... F950-F	114.3 mm Fuel Ele. (3524700092)..... F834-F
220.7 mm Air (10949404)..... PA3807	Air (To 4/88) (20942404)..... PA2955 <sup>90</sup>	142.9 mm Fuel Ele. (4220900051)..... F950-F
374.7 mm Air (10944204)..... PA2405	O. Air (5/88-on) (30941504)..... PA2776	220.7 mm Air (10949404)..... PA3807
383.4 mm Air (10941004)..... PA2847	255.6 mm Some Air (30944204)..... PA2942	374.7 mm Air (10944204)..... PA2405
100.8 mm Steering (4660604)..... P106-HD	374.7 mm Some Air (9/88-on) (20940004)..... PA2405	383.4 mm Air (10941004)..... PA2847
115.9 mm Steering (4660004)..... PT691	Steering (1902137)..... P106-HD	100.8 mm Steering (4660604)..... P106-HD
1924 w/OM355 Eng.	1936 w/OM423 Eng.	115.9 mm Steering (4660004)..... PT691
Lube (To 4/78) (1846725)..... P42	Lube (4031840025)..... P294	2020 w/OM355 Eng.
Lube (4/78-on) (11845625)..... P7052	Fuel Ele. (4220900051)..... [2] F950-F	Lube (To 4/78) (1846725)..... P52
Fuel Ele. (4220900051)..... F950-F	Air (10948304)..... PA2838	Lube (4/78-on) (11844325)..... P7052
Air (10941004)..... PA2847	Hyd. (1902137)..... P106-HD	114.3 mm Fuel Ele. (3524700092)..... F834-F
100.8 mm Steering (4660604)..... P106-HD	1938 w/OM422LA Eng.	142.9 mm Fuel Ele. (4220900051)..... F950-F
115.9 mm Steering (4660004)..... PT691	Lube (4021800009)..... P294	220.7 mm Air (10949404)..... PA3807
1926 w/OM402, OM403 Engs.	Fuel Ele. (4220900051)..... [2] F950-F	374.7 mm Air (10944204)..... PA2405
188.1 mm Lube (4011800009)..... P242	Air (20942404)..... PA2955 <sup>90</sup>	383.4 mm Air (10941004)..... PA2847
264.3 mm Lube (4031840025)..... P294	Steering (4660604)..... P106-HD	100.8 mm Steering (4660604)..... P106-HD
114.3 mm Fuel Ele. (3524700092)..... F834-F	1940 w/OM402, OM442LA Engs.	115.9 mm Steering (4660004)..... PT691
142.9 mm Fuel Ele. (4220900051)..... F950-F	Lube (4411800009)..... P7016	2023 w/OM346 Eng.
Air (10949304)..... PA2812	Fuel..... F834-F	B-P Lube (1846725)..... P42
Steering (4660004)..... PT691	254.8 mm Air..... PA3681	114.3 mm Fuel Ele. (3524700092)..... F834-F
1928 w/OM422 Eng.	255.6 mm Air (30944204)..... PA2942	142.9 mm Fuel Ele. (4220900051)..... F950-F
Lube (4021800009)..... P294	473.9 mm Air (30941504)..... PA2776	220.7 mm Air (10949404)..... PA3807
Fuel (To 7/82) (3524700092)..... [2] F834-F	479.4 mm Air (30947004)..... PA3765	374.7 mm Air (10944204)..... PA2405
Fuel Ele. (7/82-on) (4220900051)..... [2] F950-F	1944 w/OM442LA Eng.	383.4 mm Air (10941004)..... PA2847
254.0 mm Air (10949304)..... PA2812	Lube (To 8/90) (4031840025)..... P294	100.8 mm Steering (4660604)..... P106-HD
255.6 mm Some Air..... PA2838	Lube (8/90-on) (4411800009)..... P7016	115.9 mm Steering (4660004)..... PT691
Steering (4660604)..... P106-HD	Fuel Ele..... F834-F	2023 w/OM352 Eng.
1929 w/OM442 Eng.	Air (To S/N 5343252) (20942404)..... PA2955 <sup>90</sup>	Lube (To 1978) (1846725)..... P42
Lube (To 8/90) (4021800009)..... P294	Air (S/N 5343252-up) (30941504)..... PA2776	Lube (1978-on) (11844325)..... P7015
Lube (8/90-on) (4411800009)..... P7016	254.8 mm Air..... PA3681	114.3 mm Fuel Ele. (3524700092)..... F834-F
Fuel Ele..... [2] F950-F	479.4 mm Air (30947004)..... PA3765	
Air (30944204)..... PA2942	Steering (4660604)..... P106-HD	
Steering (4660604)..... P106-HD		

<sup>90</sup> Obsolete Pending.

Check Original Equipment Numbers In Parentheses.




**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ Trucks, Vans (cont'd)	MERCEDES-BENZ Trucks, Vans (cont'd)	MERCEDES-BENZ Trucks, Vans (cont'd)
2023 w/OM352 Eng. (Cont'd) 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691	2033LS (6x2, 6x4) w/OM422A Eng. Lube (4021800009)..... P294 Fuel Ele. (4220900051)..... F950-F O. Air (10944204)..... PA2405 Steering (4660604)..... P106-HD 2035 w/OM442A, OM442LA Engs. Lube (To 8/90) (4021800009)..... P294 Lube (8/90-on) (4411800009)..... P7016 Fuel Ele. (4220900051)..... F950-F 473.9 mm O. Air (5/88-on) (30941504)..... PA2776 356.4 mm Air (To 4/88) (20942404)..... PA2955 <sup>90</sup> 374.7 mm Some Air (9/88-on) (20940004)..... PA2405 255.6 mm Some Air (30944204)..... PA2942 Steering (1902137)..... P106-HD	2219 w/OM401 Eng. Lube (4011800009)..... P242 Fuel (3524700092)..... [2] F834-F Air (9/73-on) (10949304)..... PA2812 Steering (4660004)..... PT691 2220 w/OM346 Eng. B-P Lube (1846725)..... P42 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691
2023 w/OM355 Eng. Lube (To 4/78) (1846725)..... P42 Lube (4/78-on) (11845625)..... P7052 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691	2036 w/OM423 Eng. Lube (4031840025)..... P294 Fuel Ele. (4220900051)..... [2] F950-F Air (10948304)..... PA2838 Hyd. (1902137)..... P106-HD 2038 w/OM402LA Eng. Lube (4411800009)..... P7016 Fuel..... F834-F 254.8 mm Air..... PA3681 255.6 mm Air (30944204)..... PA2942 473.9 mm Air (30941504)..... PA2776	2220 w/OM352 Eng. Lube (To 1978) (1846725)..... P42 Lube (1978-on) (11844325)..... P7015 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691
2024 w/OM355 Eng. Lube (To 4/78) (1846725)..... P42 Lube (4/78-on) (11845625)..... P7052 Fuel Ele. (4220900051)..... F950-F Air (10941004)..... PA2847 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691	2044 w/OM442LA Eng. Lube (To 8/90) (4031840025)..... P294 Lube (8/90-on) (4411800009)..... P7016 Fuel Ele..... F834-F 356.4 mm Air (To S/N 5343252) (20942404)..... PA2955 <sup>90</sup> 473.9 mm Air (S/N 5343252-up) (30941504)..... PA2776 479.4 mm Air (30947004)..... PA3765 254.8 mm Air..... PA3681 Steering (4660604)..... P106-HD	2220 w/OM355 Eng. Lube (To 4/78)..... P52 Lube (4/78-on)..... P7052 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691
2025 w/OM422 Eng. F-F Lube (4031840025)..... P294 Fuel (To 7/82) (3524700092)..... [2] F834-F Fuel Ele. (7/82-on) (4220900051)..... [2] F950-F Air (10949304)..... PA2812 Steering (4660604)..... P106-HD	2050 w/OM402, OM442LA Engs. Lube (4411800009)..... P7016 Fuel..... F834-F 254.8 mm Air..... PA3681 255.6 mm Air (30944204)..... PA2942 473.9 mm Air (30941504)..... PA2776 479.4 mm Air (30947004)..... PA3765	2220 w/OM366LA Eng. Lube (To Eng. S/N 923826) (4011800009)..... P242 Lube (Eng. S/N 923827-up) (3661840125)..... P7305 Fuel (3524700092)..... [2] F834-F 254.0 mm Air (10949304)..... PA2812 381.0 mm Air (10944704)..... PA2474 Steering (4660604)..... P106-HD
2026 w/OM402 Eng. 136.5 mm Lube (3661840225)..... P7017 188.1 mm Lube (4011800009)..... P242 264.3 mm Lube (4031840025)..... P294 Fuel (3524700092)..... [2] F834-F Air (10949304)..... PA2812 Steering (4660004)..... PT691	2044 w/OM442LA Eng. Lube (To 8/90) (4031840025)..... P294 Lube (8/90-on) (4411800009)..... P7016 Fuel Ele..... F834-F 356.4 mm Air (To S/N 5343252) (20942404)..... PA2955 <sup>90</sup> 473.9 mm Air (S/N 5343252-up) (30941504)..... PA2776 479.4 mm Air (30947004)..... PA3765 254.8 mm Air..... PA3681 Steering (4660604)..... P106-HD	2222 w/OM421 Eng. Lube (4031840025)..... P294 Fuel Ele. (4220900051)..... F950-F Air (5/82-on) (10949304)..... PA2812 Steering (1902137)..... P106-HD
2028 w/OM422 Eng. Lube (4021800009)..... P294 Fuel (To 7/82) (3524700092)..... [2] F834-F Fuel Ele. (7/82-on) (4220900051)..... [2] F950-F 254.0 mm Air (10949304)..... PA2812 255.6 mm Air..... PA2838 Steering (4660604)..... P106-HD	2050 w/OM402, OM442LA Engs. Lube (4411800009)..... P7016 Fuel..... F834-F 254.8 mm Air..... PA3681 255.6 mm Air (30944204)..... PA2942 473.9 mm Air (30941504)..... PA2776 479.4 mm Air (30947004)..... PA3765	2222 w/OM421 Eng. Lube (4031840025)..... P294 Fuel Ele. (4220900051)..... F950-F Air (5/82-on) (10949304)..... PA2812 Steering (1902137)..... P106-HD
2028LS (6x2, 6x4) w/OM422A Eng. Lube (4021800009)..... P294 Fuel Ele. (4220900051)..... F950-F O. Air (10944204)..... PA2405 Steering (4660604)..... P106-HD	2044 w/OM442LA Eng. Lube (To 8/90) (4031840025)..... P294 Lube (8/90-on) (4411800009)..... P7016 Fuel Ele..... F834-F 356.4 mm Air (To S/N 5343252) (20942404)..... PA2955 <sup>90</sup> 473.9 mm Air (S/N 5343252-up) (30941504)..... PA2776 479.4 mm Air (30947004)..... PA3765 254.8 mm Air..... PA3681 Steering (4660604)..... P106-HD	2222 w/OM421 Eng. Lube (4031840025)..... P294 Fuel Ele. (4220900051)..... F950-F Air (5/82-on) (10949304)..... PA2812 Steering (1902137)..... P106-HD
2033 w/OM422A Eng. Lube (4031840025)..... P294 Fuel Ele. (4220900051)..... [2] F950-F Air..... PA2955 <sup>90</sup> Steering (4660604)..... P106-HD	2044 w/OM442LA Eng. Lube (To 8/90) (4031840025)..... P294 Lube (8/90-on) (4411800009)..... P7016 Fuel Ele..... F834-F 356.4 mm Air (To S/N 5343252) (20942404)..... PA2955 <sup>90</sup> 473.9 mm Air (S/N 5343252-up) (30941504)..... PA2776 479.4 mm Air (30947004)..... PA3765 254.8 mm Air..... PA3681 Steering (4660604)..... P106-HD	2222 w/OM421 Eng. Lube (4031840025)..... P294 Fuel Ele. (4220900051)..... F950-F Air (5/82-on) (10949304)..... PA2812 Steering (1902137)..... P106-HD

<sup>90</sup> Obsolete Pending.

Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



MERCEDES-BENZ Trucks, Vans (cont'd)	MERCEDES-BENZ Trucks, Vans (cont'd)	MERCEDES-BENZ Trucks, Vans (cont'd)
2222 w/OM441 Eng. Lube (401180009)..... P242 Fuel Ele. (4220900051)..... F950-F Air (30944204)..... PA2942 Steering (1902137)..... P106-HD	2225 w/OM422 Eng. F-F Lube (4031840025)..... P294 Fuel (To 7/82) (3524700092)..... [2] F834-F Fuel Ele. (7/82-on) (4220900051) [2] F950-F Air (10949304)..... PA2812 Steering (4660604)..... P106-HD	2244 w/OM442LA Eng. Lube (To 8/90) (4031840025)..... P294 Lube (8/90-on) (4411800009)..... P7016 Fuel Ele..... F834-F 356.4 mm Air (To S/N 5343252) (20942404)..... PA2955 90 473.9 mm Air (S/N 5343252-up) (30941504)..... PA2776 254.8 mm Air..... PA3681 479.4 mm Air (30947004)..... PA3765 Steering (4660604)..... P106-HD
2223 w/OM346 Eng. B-P Lube (1846725)..... P42 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691	2226 w/OM402, OM403 Eng. 136.5 mm Lube (3661840225)..... P7017 188.1 mm Lube (4011800009)..... P242 264.3 mm Lube (4031840025)..... P294 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F Air (10949304)..... PA2812 Steering (4660004)..... PT691	2419 w/OM401 Eng. Lube (4011840025)..... P242 Fuel (3524700092)..... F834-F Air (1973-on) (10949304)..... PA2812 Steering (4660004)..... PT691
2223 w/OM352 Eng. Lube (To 1978) (1846725)..... P42 Lube (1978-on) (11844325)..... P7015 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691	2228 w/OM422 Eng. Lube (4021800009)..... P294 Fuel (To 7/82) (3524700092)..... [2] F834-F Fuel Ele. (7/82-on) (4220900051) [2] F950-F 254.0 mm Air (10949304)..... PA2812 255.6 mm Air..... PA2838 Steering (4660604)..... P106-HD	2422 w/OM421 Eng. Lube (4031840025)..... P294 Fuel Ele. (4220900051)..... F950-F Air (5/82-on) (10949304)..... PA2812 Steering (1902137)..... P106-HD
2223 w/OM355 Eng. Lube (To 4/78) (1846725)..... P42 Lube (4/78-on) (11845625)..... P7052 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691	2232 w/OM403 Series Eng. F-F Lube (4031840025)..... P294 (3524700092)..... F834-F 142.9 mm Fuel Ele..... F950-F Air (1973-on) (10948304)..... PA2838 Steering (4660004)..... PT691	2422 w/OM441 Eng. Lube (4011800009)..... P242 Fuel Ele. (4220900051)..... F950-F Air (30944204)..... PA2942 Steering (1902137)..... P106-HD
2224 w/OM355 Eng. Lube (To 4/78) (1846725)..... P42 Lube (4/78-on) (11845625)..... P7052 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691	2233 w/OM422A Eng. Lube (4031840025)..... P294 Fuel Ele. (4220900051)..... [2] F950-F Air..... PA2955 90 Steering (4660604)..... P106-HD	2426 w/OM442 Eng. Lube (To 7/90)..... P294 Lube (7/90-on) (4411800009)..... P7016 Fuel Ele..... F950-F O. Air (30944204)..... PA2942 Steering (1902137)..... P106-HD
2224 w/OM402 Eng. 136.5 mm Lube (3661840225)..... P7017 188.1 mm Lube (4011800009)..... P242 264.3 mm Lube (4031840025)..... P294 Fuel (3524700092)..... [2] F834-F Air (1973-on) (10949304)..... PA2812 Steering (4660004)..... PT691	2235 w/OM442A, OM442LA Eng. Lube (To 8/90) (4021800009)..... P294 Lube (8/90-on) (4411800009)..... P7016 Fuel Ele. (4220900051)..... F950-F 473.9 mm O. Air (5/88-on) (30941504)..... PA2776 356.4 mm Air (To 4/88) (20942404)..... PA2955 90 374.7 mm Some Air (9/88-on) (20940004)..... PA2405 255.6 mm Some Air (30944204)..... PA2942 Steering (1902137)..... P106-HD	2428 w/OM422 Eng. Lube (4021800009)..... P294 Fuel (To 7/82) (3524700092)..... [2] F834-F Fuel Ele. (7/82-on) (4220900051) [2] F950-F 254.0 mm Air (10949304)..... PA2812 255.6 mm Air..... PA2838 Steering (4660604)..... P106-HD
2224 w/OM402 Eng. 136.5 mm Lube (3661840225)..... P7017 188.1 mm Lube (4011800009)..... P242 264.3 mm Lube (4031840025)..... P294 Fuel (3524700092)..... [2] F834-F Air (1973-on) (10949304)..... PA2812 Steering (4660004)..... PT691	2236 w/OM423 Eng. Lube (4031840025)..... P294 Fuel Ele. (4220900051)..... [2] F950-F Air (10948304)..... PA2838 Hyd. (1902137)..... P106-HD	2429 w/OM442 Eng. Lube (To 8/90) (4021800009)..... P294 Lube (8/90-on) (4411800009)..... P7016 Fuel Ele..... [2] F950-F Air (30944204)..... PA2942 Steering (4660604)..... P106-HD
2224 w/OM402 Eng. 136.5 mm Lube (3661840225)..... P7017 188.1 mm Lube (4011800009)..... P242 264.3 mm Lube (4031840025)..... P294 Fuel (3524700092)..... [2] F834-F Air (1973-on) (10949304)..... PA2812 Steering (4660004)..... PT691	2238 w/OM422LA Eng. Lube (4021800009)..... P294 Fuel Ele. (4220900051)..... [2] F950-F Air (20942404)..... PA2955 90 Steering (4660604)..... P106-HD	2433 w/OM441LA Eng. (1988) Lube (4411800009)..... P7016 Fuel Ele..... F950-F 255.6 mm Air (30944204)..... PA2942 473.9 mm Air (30941504)..... PA2776 Steering (1902137)..... P106-HD
2224 w/OM402 Eng. 136.5 mm Lube (3661840225)..... P7017 188.1 mm Lube (4011800009)..... P242 264.3 mm Lube (4031840025)..... P294 Fuel (3524700092)..... [2] F834-F Air (1973-on) (10949304)..... PA2812 Steering (4660004)..... PT691	2238 w/OM422LA Eng. Lube (4021800009)..... P294 Fuel Ele. (4220900051)..... [2] F950-F Air (20942404)..... PA2955 90 Steering (4660604)..... P106-HD	2435 w/OM442A, OM442LA Eng. Lube (To 8/90) (4021800009)..... P294 Lube (8/90-on) (4411800009)..... P7016 Fuel Ele. (4220900051)..... F950-F 356.4 mm Air (To 4/88) (20942404)..... PA2955 90

<sup>90</sup> Obsolete Pending.

Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ Trucks, Vans (cont'd)	MERCEDES-BENZ Trucks, Vans (cont'd)	MERCEDES-BENZ Trucks, Vans (cont'd)
2435 w/OM442A, OM442LA Engs. (Cont'd) 473.9 mm O. Air (5/88-on) (30941504)..... PA2776 374.7 mm Some Air (9/88-on) (20940004)..... PA2405 255.6 mm Some Air (30944204).. PA2942 Steering (1902137)..... P106-HD	2550 w/OM402, OM442LA Engs. Lube (4411800009)..... P7016 Fuel..... F834-F 254.8 mm Air..... PA3681 255.6 mm Air (30944204)..... PA2942 473.9 mm Air (30941504)..... PA2776 479.4 mm Air (30947004)..... PA3765	2629 w/OM442 Eng. Lube (To 8/90) (4021800009)..... P294 Lube (8/90-on) (4411800009)..... P7016 Fuel Ele..... [2] F950-F Air (30944204)..... PA2942 Steering (4660604)..... P106-HD
2440 w/OM402LA, OM442LA Engs. I. Air..... PA3681	2553 w/OM442LA Eng. Lube (4411800009)..... P7016 Fuel Ele..... F950-F Air (30947004)..... PA3765 Steering (1902137)..... P106-HD	2632 w/OM403 Series Engs. F-F Lube (4031840025)..... P294 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele..... F950-F Air (1973-on) (10948304)..... PA2838 Steering (4660004)..... PT691
2448 w/OM442A Eng. Lube (To 8/90) (4021800009)..... P294 Lube (8/90-on) (4411800009)..... P7016 Fuel (3524700092)..... F834-F O. Air (30941504)..... PA2776 Single Air (1988-on) (20942404). PA2955 <sup>90</sup> Steering (4660604)..... P106-HD	2623 w/OM352 Eng. Lube (To 1978) (1846725)..... P42 Lube (1978-on) (11844325)..... P7015 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691	2633 w/OM422A Eng. Lube (4031840025)..... P294 Fuel Ele. (4220900051)..... [2] F950-F Air..... PA2955 <sup>90</sup> Steering (4660604)..... P106-HD
2527 w/OM401A Eng. Lube (4411800009)..... P7016 Fuel Ele..... F950-F Air (30944204)..... PA2942	2623 w/OM355 Eng. Lube (To 4/78) (1846725)..... P42 Lube (4/78-on) (11845625)..... P7052 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele. (4220900051)..... F950-F 220.7 mm Air (10949404)..... PA3807 374.7 mm Air (10944204)..... PA2405 383.4 mm Air (10941004)..... PA2847 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691	2635 w/OM442A, OM442LA Engs. Lube (To 8/90) (4021800009)..... P294 Lube (8/90-on) (4411800009)..... P7016 Fuel Ele. (4220900051)..... F950-F 473.9 mm O. Air (5/88-on) (30941504)..... PA2776 356.4 mm Air (To 4/88) (20942404)..... PA2955 <sup>90</sup> 374.7 mm Some Air (9/88-on) (20940004)..... PA2405 255.6 mm Some Air (30944204).. PA2942 Steering (1902137)..... P106-HD
2527 w/OM401LA Eng. Lube (1026)..... P7016 Fuel..... F834-F Air (30944204)..... PA2942	2624 w/OM355 Eng. Lube (To 4/78) (1846725)..... P42 Lube (4/78-on) (11845625)..... P7052 Fuel Ele. (4220900051)..... F950-F Air (10941004)..... PA2847 100.8 mm Steering (4660604)..... P106-HD 115.9 mm Steering (4660004)..... PT691	2636 w/OM423 Eng. Lube (4031840025)..... P294 Fuel Ele. (4220900051)..... [2] F950-F Air (10948304)..... PA2838 Steering (4660604)..... P106-HD
2531 w/OM401LA Eng. Lube (4411800009)..... P7016 Fuel..... F834-F Air (30944204)..... PA2942	2628 w/OM422 Eng. Lube (4021800009)..... P294 Fuel (To 7/82) (3524700092)..... [2] F834-F Fuel Ele. (7/82-on) (4220900051) [2] F950-F 254.0 mm Air (10949304)..... PA2812 255.6 mm Air..... PA2838 Steering (4660604)..... P106-HD	2638 w/OM422LA Eng. Lube (4021800009)..... P294 Fuel Ele. (4220900051)..... [2] F950-F Air (20942404)..... PA2955 <sup>90</sup> Steering (4660604)..... P106-HD
2533 w/OM422A Eng. Lube (4031840025)..... P294 Fuel Ele. (4220900051)..... [2] F950-F Air..... PA2955 <sup>90</sup> Steering (4660604)..... P106-HD	2626 w/OM402 Eng. 136.5 mm Lube (3661840225)..... P7017 188.1 mm Lube (4011800009)..... P242 264.3 mm Lube (4031840025)..... P294 Fuel (3524700092)..... [2] F834-F Air (10949304)..... PA2812 Steering (4660004)..... PT691	2644 w/OM442LA Eng. Lube (To 8/90) (4031840025)..... P294 Lube (8/90-on) (4411800009)..... P7016 Fuel Ele..... F834-F 356.4 mm Air (To S/N 5343252) (20942404)..... PA2955 <sup>90</sup> 473.9 mm Air (S/N 5343252-up) (30941504)..... PA2776 254.8 mm Air..... PA3681 479.4 mm Air (30947004)..... PA3765 Steering (4660604)..... P106-HD
2538 w/OM402LA Eng. Lube (4411800009)..... P7016 Fuel..... F834-F 254.8 mm Air..... PA3681 255.6 mm Air (30944204)..... PA2942 473.9 mm Air (30941504)..... PA2776	2628 w/OM422 Eng. Lube (4021800009)..... P294 Fuel (To 7/82) (3524700092)..... [2] F834-F Fuel Ele. (7/82-on) (4220900051) [2] F950-F 254.0 mm Air (10949304)..... PA2812 255.6 mm Air..... PA2838 Steering (4660604)..... P106-HD	2648 w/OM442A Eng. Lube (To 8/90) (4021800009)..... P294 Lube (8/90-on) (4411800009)..... P7016 Fuel (3524700092)..... F834-F O. Air (30941504)..... PA2776 Single Air (1988-on) (20942404). PA2955 <sup>90</sup> Steering (4660604)..... P106-HD
2540 w/OM402, OM442LA Engs. Lube (4411800009)..... P7016 Fuel..... F834-F 254.8 mm Air..... PA3681 255.6 mm Air (30944204)..... PA2942 473.9 mm Air (30941504)..... PA2776 479.4 mm Air (30947004)..... PA3765	2628 w/OM422 Eng. Lube (4021800009)..... P294 Fuel (To 7/82) (3524700092)..... [2] F834-F Fuel Ele. (7/82-on) (4220900051) [2] F950-F 254.0 mm Air (10949304)..... PA2812 255.6 mm Air..... PA2838 Steering (4660604)..... P106-HD	
2544 w/OM442LA Eng. Lube (To 8/90) (4031840025)..... P294 Lube (8/90-on) (4411800009)..... P7016 Fuel Ele..... F834-F 356.4 mm Air (To S/N 5343252) (20942404)..... PA2955 <sup>90</sup> 473.9 mm Air (S/N 5343252-up) (30941504)..... PA2776 254.8 mm Air..... PA3681 479.4 mm Air (30947004)..... PA3765 Steering (4660604)..... P106-HD		

<sup>90</sup> Obsolete Pending.

Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ Trucks, Vans (cont'd)	MERCEDES-BENZ Trucks, Vans (cont'd)	MERCEDES-BENZ Trucks, Vans (cont'd)
2650 w/OM402, OM442LA Engs. Lube (4411800009)..... P7016 Fuel..... F834-F 254.8 mm Air..... PA3681 255.6 mm Air (30944204)..... PA2942 473.9 mm Air (30941504)..... PA2776 479.4 mm Air (30947004)..... PA3765	3233 w/OM441LA Eng. (1988) Lube (4411800009)..... P7016 Fuel Ele..... F950-F 255.6 mm Air (30944204)..... PA2942 473.9 mm Air (30941504)..... PA2776 Steering (1902137)..... P106-HD	3535 w/OM442A, OM442LA Engs. Lube (To 8/90) (4021800009)..... P294 Lube (8/90-on) (4411800009)..... P7016 Fuel Ele. (4220900051)..... F950-F 473.9 mm O. Air (5/88-on) (30941504)..... PA2776 356.4 mm Air (To 4/88) (20942404)..... PA2955 <sup>90</sup> 374.7 mm Some Air (9/88-on) (20940004)..... PA2405 255.6 mm Some Air (30944204)..... PA2942 Steering (1902137)..... P106-HD
2653 w/OM442LA Eng. Lube (4411800009)..... P7016 Fuel Ele..... F950-F Air (30947004)..... PA3765 Steering (1902137)..... P106-HD	3235 w/OM442A, OM442LA Engs. Lube (To 8/90) (4021800009)..... P294 Lube (8/90-on) (4411800009)..... P7016 Fuel Ele. (4220900051)..... F950-F 473.9 mm O. Air (5/88-on) (30941504)..... PA2776 356.4 mm Air (To 4/88) (20942404)..... PA2955 <sup>90</sup> 374.7 mm Some Air (9/88-on) (20940004)..... PA2405 255.6 mm Some Air (30944204)..... PA2942 Steering (1902137)..... P106-HD	3536 w/OM423 Eng. Lube (4031840025)..... P294 Fuel Ele. (4220900051)..... [2] F950-F Air (10948304)..... PA2838 Steering (1902137)..... P106-HD
3025 w/OM422 Eng. F-F Lube (4031840025)..... P294 Fuel (To 7/82) (3524700092)..... [2] F834-F Fuel Ele. (7/82-on) (4220900051) [2] F950-F Air (10949304)..... PA2812 Steering (4660604)..... P106-HD	3238 w/OM402LA Eng. Lube (4411800009)..... P7016 Fuel..... F834-F 254.8 mm Air..... PA3681 255.6 mm Air (30944204)..... PA2942 473.9 mm Air (30941504)..... PA2776	3538 w/OM402LA Eng. Lube (4411800009)..... P7016 Fuel..... F834-F 254.8 mm Air..... PA3681 255.6 mm Air (30944204)..... PA2942 473.9 mm Air (30941504)..... PA2776
3028 w/OM422 Eng. Lube (4021800009)..... P294 Fuel (To 7/82) (3524700092)..... [2] F834-F Fuel Ele. (7/82-on) (4220900051) [2] F950-F 254.0 mm Air (10949304)..... PA2812 255.6 mm Some Air..... PA2838 Steering (4660604)..... P106-HD	3244 w/OM442LA Eng. Lube (To 8/90) (4031840025)..... P294 Lube (8/90-on) (4411800009)..... P7016 Fuel Ele..... F834-F 356.4 mm Air (To S/N 5343252) (20942404)..... PA2955 <sup>90</sup> 473.9 mm Air (S/N 5343252-up) (30941504)..... PA2776 479.4 mm Air (30947004)..... PA3765 254.8 mm Air..... PA3681 Steering (4660604)..... P106-HD	3544 w/OM442LA Eng. Lube (To 8/90) (4031840025)..... P294 Lube (8/90-on) (4411800009)..... P7016 Fuel Ele..... F834-F 356.4 mm Air (To S/N 5343252) (20942404)..... PA2955 <sup>90</sup> 473.9 mm Air (S/N 5343252-up) (30941504)..... PA2776 254.8 mm Air..... PA3681 479.4 mm Air (30947004)..... PA3765 Steering (4660604)..... P106-HD
3032 w/OM403 Series Engs. F-F Lube (4031840025)..... P294 114.3 mm Fuel Ele. (3524700092)..... F834-F 142.9 mm Fuel Ele..... F950-F Air (1973-on) (10948304)..... PA2838 Steering (4660004)..... PT691	3250 w/OM426LA, OM443LA Engs. Lube (4031840025)..... P294 Fuel Ele. (4220900051)..... F950-F Air (10948304)..... PA2838 Steering (4660604)..... P106-HD	3548 w/OM442A Eng. Lube (To 8/90) (4021800009)..... P294 Lube (8/90-on) (4411800009)..... P7016 Fuel (3524700092)..... F834-F O. Air (30941504)..... PA2776 Air (1988-on) (20942404)..... PA2955 <sup>90</sup> Steering (4660604)..... P106-HD
3033 w/OM422A Eng. Lube (4031840025)..... P294 Fuel Ele. (4220900051)..... [2] F950-F Air..... PA2955 <sup>90</sup> Steering (4660604)..... P106-HD	3328 w/OM422 Eng. Lube (4021800009)..... P294 Fuel (To 7/82) (3524700092)..... [2] F834-F Fuel Ele. (7/82-on) (4220900051) [2] F950-F 254.0 mm Air (10949304)..... PA2812 255.6 mm Some Air..... PA2838 Steering (4660604)..... P106-HD	3553 w/OM442LA Eng. Lube (4411800009)..... P7016 Fuel Ele..... F950-F Air (30947004)..... PA3765 Steering (1902137)..... P106-HD
3050 w/OM402, OM442LA Engs. Lube (4411800009)..... P7016 Fuel..... F834-F 254.8 mm Air..... PA3681 255.6 mm Air (30944204)..... PA2942 473.9 mm Air (30941504)..... PA2776 479.4 mm Air (30947004)..... PA3765	3333 w/OM422A Eng. Lube (4031840025)..... P294 Fuel Ele. (4220900051)..... [2] F950-F Air..... PA2955 <sup>90</sup> Steering (4660604)..... P106-HD	Actros I 3840S w/OM501LA Eng. F-F Lube (5411800009)..... P7192 Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363 Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O Fuel (5410920305)..... PF7761 Fuel/Water Separator (w/Drain)..... BF1363 Radial Seal Air (40940204)..... RS5343 Panel Air (30949004)..... PA5426 261.9 mm Air (A0030949204)..... PA3838 <sup>90</sup> 318.3 mm Air (A0030949104)..... PA3844
3053 w/OM442LA Eng. Lube (4411800009)..... P7016 Fuel Ele..... F950-F Air (30947004)..... PA3765 Steering (1902137)..... P106-HD	3336 w/OM423 Eng. Lube (4031840025)..... P294 Fuel Ele. (4220900051)..... [2] F950-F Air (10948304)..... PA2838 Steering (1902137)..... P106-HD	
3229 w/OM442 Eng. Lube (To 8/90) (4021800009)..... P294 Lube (8/90-on) (4411800009)..... P7016 Fuel Ele..... [2] F950-F Air (30944204)..... PA2942 Steering (4660604)..... P106-HD		

<sup>90</sup> Obsolete Pending.

Check Original Equipment Numbers In Parentheses.




**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MERCEDES-BENZ Trucks, Vans (cont'd)	MERCEDES-BENZ Trucks, Vans (cont'd)	MERCEDES-BENZ Trucks, Vans (cont'd)
Actros I 3840S w/OM501LA Eng. (Cont'd)	Actros I 4146 w/OM502LA Eng. (Cont'd)	L1113
496.9 mm Air (10947904)..... PA2475	Steering (1902137)..... P106-HD	228.6 mm Lube (3445868090)..... P507
38.9 mm Height Cab Air (Mann CU3869)..... PA4956	Actros I 4148 w/OM502LA Eng.	244.5 mm Lube (11843325)..... P7052
40.5 mm Height Cab Air (w/o Charcoal) (Mann CU3855)..... PA4912	F-F Lube (5411800009)..... P7192	B-P Lube (1846725)..... P42
40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363	Fuel Ele. (3440927005)..... PF834
Trans. (Mann H613x)..... PT9423	Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O	374.7 mm Air (10945204)..... PA2405
Steering (1902137)..... P106-HD	Fuel (5410920305)..... PF7761	414.3 mm Air (3760947104)..... PA1902-FN
3850 w/OM426LA, OM443LA Eng.	Fuel/Water Separator (w/Drain)..... BF1363	Steering (4660604)..... P106-HD
Lube (4031840025)..... P294	Radial Seal Air (40940204)..... RS5343	L1116
Fuel Ele. (4220900051)..... F950-F	261.9 mm Air (A0030949204)..... PA3838 <sup>90</sup>	228.6 mm Lube (3445868090)..... P507
Air (10948304)..... PA2838	318.3 mm Air (A0030949104)..... PA3844	244.5 mm Lube (11843325)..... P7052
Steering (4660604)..... P106-HD	496.9 mm Air (10947904)..... PA2475	B-P Lube (1846725)..... P42
3850AS w/OM423LA Eng.	Panel Air (30949004)..... PA5426	Fuel Ele. (3440927005)..... PF834
Lube (11843825)..... P294	38.9 mm Height Cab Air (Mann CU3869)..... PA4956	374.7 mm Air (10945204)..... PA2405
Fuel Ele. (4220900051)..... F950-F	40.5 mm Height Cab Air (w/o Charcoal) (Mann CU3855)..... PA4912	414.3 mm Air (3760947104)..... PA1902-FN
Actros I 4140 w/OM501LA Eng.	40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	Steering (4660604)..... P106-HD
F-F Lube (5411800009)..... P7192	Trans. (Mann H613x)..... PT9423	L1117
Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363	Steering (1902137)..... P106-HD	Lube (To S/N 818239) (3445868090)..... P507
Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O	4435 w/OM442A, OM442LA Eng.	Lube (S/N 818239-up) (4011800009)..... P242
Fuel (5410920305)..... PF7761	Lube (To 8/90) (4021800009)..... P294	Fuel (3444777215)..... [2] PF834
Fuel/Water Separator (w/Drain)..... BF1363	Lube (8/90-on) (4411800009)..... P7016	Air (3760947104)..... PA1902-FN
Radial Seal Air (40940204)..... RS5343	Fuel Ele. (4220900051)..... F950-F	Steering (4660604)..... P106-HD
Panel Air (30949004)..... PA5426	473.9 mm O. Air (5/88-on) (30941504)..... PA2776	L1316
261.9 mm Air (A0030949204)..... PA3838 <sup>90</sup>	356.4 mm Air (To 4/88) (20942404)..... PA2955 <sup>90</sup>	Lube (3445868090)..... P507
318.3 mm Air (A0030949104)..... PA3844	374.7 mm Some Air (9/88-on) (20940004)..... PA2405	Fuel (3444777215)..... PF834
496.9 mm Air (10947904)..... PA2475	255.6 mm Some Air (30944204)..... PA2942	374.7 mm Air (10945204)..... PA2405
38.9 mm Height Cab Air (Mann CU3869)..... PA4956	Steering (1902137)..... P106-HD	414.3 mm Air (3760947104)..... PA1902-FN
40.5 mm Height Cab Air (w/o Charcoal) (Mann CU3855)..... PA4912	4436 w/OM423 Eng.	Steering (4660604)..... P106-HD
40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	Lube (4031840025)..... P294	L1317
Trans. (Mann H613x)..... PT9423	Fuel Ele. (4220900051)..... [2] F950-F	Lube (To S/N 818239) (3445868090)..... P507
Steering (1902137)..... P106-HD	Air (10948304)..... PA2838	Lube (S/N 818239-up) (4011800009)..... P242
Actros I 4146 w/OM502LA Eng.	Steering (1902137)..... P106-HD	Fuel (3444777215)..... [2] PF834
F-F Lube (5411800009)..... P7192	5038 w/OM422LA Eng.	Air (3760947104)..... PA1902-FN
Fuel/Water Separator (w/Drain) (A0004771302)..... BF1363	Lube (4021800009)..... P294	Steering (4660604)..... P106-HD
Fuel/Water Separator (Open End for Bowl) (A0004771302)..... BF1391-O	Fuel Ele. (4220900051)..... [2] F950-F	L1418, LS1418
Fuel (5410920305)..... PF7761	Air (20942404)..... PA2955 <sup>90</sup>	Lube (3551800009)..... P7052
Fuel/Water Separator (w/Drain)..... BF1363	Steering (4660604)..... P106-HD	Fuel Ele. (4220900051)..... F950-F
Radial Seal Air (40940204)..... RS5343	A Class A160, A170 w/OM668 Eng.	414.3 mm Air (3760947104)..... PA1902-FN
261.9 mm Air (A0030949204)..... PA3838 <sup>90</sup>	Fuel (Mann WK842/13)..... BF7756	374.7 mm Some Air (10945204)..... PA2405
318.3 mm Air (A0030949104)..... PA3844	Air (Mann C11120)..... PA697	Steering (4660604)..... P106-HD
496.9 mm Air (10947904)..... PA2475	L1013	L1928 w/OM355, OM355LA Eng.
Panel Air (30949004)..... PA5426	Lube (3445868090)..... P507	Lube (11845625)..... P7052
38.9 mm Height Cab Air (Mann CU3869)..... PA4956	Fuel (3444777215)..... PF834	Fuel Ele. (4220900051)..... F950-F
40.5 mm Height Cab Air (w/o Charcoal) (Mann CU3855)..... PA4912	374.7 mm Air (10945204)..... PA2405	Air (10947904)..... PA2475
40.5 mm Height Cab Air (w/Charcoal) (A0008303418)..... PA5492	414.3 mm Air (3760947104)..... PA1902-FN	Steering (4660604)..... P106-HD
Trans. (Mann H613x)..... PT9423	Steering (4660604)..... P106-HD	L2628 w/OM355, OM355LA Eng.
		Lube (11845625)..... P7052
		Fuel Ele. (4220900051)..... F950-F
		Air (10947904)..... PA2475
		Steering (4660604)..... P106-HD

<sup>90</sup> Obsolete Pending.

Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).


MERCEDES-BENZ Trucks, Vans (cont'd)	MID BUS Buses (cont'd)	MID BUS Buses (cont'd)
L3828 w/OM355, OM355LA Engs. <b>Lube</b> (11845625)..... <b>P7052</b> <b>Fuel Ele.</b> (4220900051)..... <b>F950-F</b> <b>Air</b> (10947904)..... <b>PA2475</b> <b>Steering</b> (4660604)..... <b>P106-HD</b>	Grand Guide w/GM 6.0L Gas Eng. (Cont'd) <b>Trans.</b> (4L60E D. Pan) (24208576)..... <b>18056</b> <b>Trans.</b> (4L80E) (24210956)..... <b>18027</b>	Guide w/GM 4.8L Gas Eng. (Cont'd) <b>Radial Seal Air</b> (ACDelco A1621C)..... <b>RS4131</b> <b>Trans.</b> (4L60E S. Pan) (24200796)..... <b>18010</b> <b>Trans.</b> (4L60E D. Pan) (24208576)..... <b>18056</b> <b>Trans.</b> (4L80E) (24210956)..... <b>18027</b>
L407D <b>Lube</b> (1977-on) (6171840125)..... <b>P102</b>	Grand Guide w/GM 6.6L Diesel Eng. <b>Lube</b> (ACDelco PF2232)..... <b>B1441</b> <b>Fuel/Water Separator</b> (Upgrade) (ACDelco TP3018)..... <b>BF46062<sup>89</sup></b>	Guide w/GM 6.0L Gas Eng. <b>Lube</b> (2003-06) (ACDelco PF46).. <b>B31</b> <b>Lube</b> (2007-on)..... <b>B160</b> <b>Fuel</b> (2003-05 (Thd. Both Ends)) (ACDelco GF652)..... <b>BF853</b> <b>Fuel</b> (2003-05 (Thd. One End)) (ACDelco GF578)..... <b>BF1171</b> <b>Fuel</b> (2006-on) (N/S)..... <b>N/S</b> <b>Radial Seal Air</b> (ACDelco A1621C)..... <b>RS4131</b> <b>Trans.</b> (4L60E S. Pan) (24200796)..... <b>18010</b> <b>Trans.</b> (4L60E D. Pan) (24208576)..... <b>18056</b> <b>Trans.</b> (4L80E) (24210956)..... <b>18027</b>
LPS1525 w/OM429LA Eng. <b>Fuel Ele.</b> ..... <b>[2] PF950</b> <b>Air</b> ..... <b>PA2521</b> <b>Steering</b> ..... <b>P106-HD</b>	<b>Radial Seal Air</b> (ACDelco A2032C)..... <b>RS4859</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Steering</b> (88892858)..... <b>P106-HD</b>	Super Guide w/Ford 6.0L Diesel Eng. <b>Lube</b> (w/o Screw on Cap) (Motorcraft FL2016)..... <b>P7235</b> <b>Lube</b> (w/Screw on Cap) (Wix 57312)..... <b>P7436</b> <b>Fuel</b> (Motorcraft FD4606)..... <b>PF7852 KIT</b> <b>Channel Flow Air</b> (Motorcraft FA1746)..... <b>CA4999</b> <b>Trans. Ele.</b> (Motorcraft FT145).... <b>P7247</b> <b>Trans. Pan-Type</b> (To 11/07) (Motorcraft FT144)..... <b>20005</b> <b>Trans. Pan-Type</b> (11/07-on) (Motorcraft FT180)..... <b>20021</b>
MB100D Van w/OM615, OM616 Engs. <b>Lube Ele.</b> ..... <b>P102</b>	Guide w/Ford 5.4L Gas Eng. <b>Lube</b> (Motorcraft FL820S)..... <b>B329</b> <b>Fuel</b> (Motorcraft FG986B)..... <b>BF7668<sup>+</sup></b> <b>Air</b> (Motorcraft FA1632)..... <b>PA4075</b> <b>Trans.</b> (4R100 S. Pan) (Motorcraft FT113)..... <b>18264</b> <b>Trans.</b> (4R100 D. Pan) (Motorcraft FT144)..... <b>20005</b> <b>Trans.</b> (4R70W) (Motorcraft FT105)..... <b>18029</b> <b>Trans.</b> (5R110W, To 11/07) (Motorcraft FT144)..... <b>20005</b> <b>Trans.</b> (5R110W, 11/07-on) (Motorcraft FT180)..... <b>20021</b> <b>Trans. Ele.</b> (5R110W) (Motorcraft FT145)..... <b>P7247</b>	Super Guide w/Ford 6.0L Diesel Eng. <b>Lube</b> (w/o Screw on Cap) (Motorcraft FL2016)..... <b>P7235</b> <b>Lube</b> (w/Screw on Cap) (Wix 57312)..... <b>P7436</b> <b>Fuel</b> (Motorcraft FD4606)..... <b>PF7852 KIT</b> <b>Channel Flow Air</b> (Motorcraft FA1746)..... <b>CA4999</b> <b>Trans. Ele.</b> (Motorcraft FT145).... <b>P7247</b> <b>Trans. Pan-Type</b> (To 11/07) (Motorcraft FT144)..... <b>20005</b> <b>Trans. Pan-Type</b> (11/07-on) (Motorcraft FT180)..... <b>20021</b>
Sprinter 4500 w/V6 (3.0L) Turbo Diesel (2019) <b>Lube</b> (6421800009)..... <b>P7413</b>	Guide w/Ford 6.0L Diesel Eng. <b>Lube</b> (w/o Screw on Cap) (Motorcraft FL2016)..... <b>P7235</b> <b>Lube</b> (w/Screw on Cap) (Wix 57312)..... <b>P7436</b> <b>Fuel</b> (Motorcraft FD4606)..... <b>PF7852 KIT</b> <b>Channel Flow Air</b> (Motorcraft FA1746)..... <b>CA4999</b> <b>Trans. Ele.</b> (Motorcraft FT145).... <b>P7247</b> <b>Trans. Pan-Type</b> (To 11/07) (Motorcraft FT144)..... <b>20005</b> <b>Trans. Pan-Type</b> (11/07-on) (Motorcraft FT180)..... <b>20021</b>	Super Guide w/GM 6.0L Gas Eng. <b>Lube</b> (2003-06) (ACDelco PF46).. <b>B31</b> <b>Lube</b> (2007-on)..... <b>B160</b> <b>Fuel</b> (2003-05 (Thd. Both Ends)) (ACDelco GF652)..... <b>BF853</b> <b>Fuel</b> (2003-05 (Thd. One End)) (ACDelco GF578)..... <b>BF1171</b> <b>Fuel</b> (2006-on) (N/S)..... <b>N/S</b> <b>Radial Seal Air</b> (ACDelco A1621C)..... <b>RS4131</b> <b>Trans.</b> (4L60E S. Pan) (24200796)..... <b>18010</b>
V Class V200, V220 w/OM611 Eng. <b>Lube</b> (Mann HU718/1k)..... <b>P1443</b> <b>Fuel</b> (Mann WK842/13)..... <b>BF7756</b> <b>Air</b> (Mann C32338)..... <b>PA4600</b>	Guide w/GM 4.8L Gas Eng. <b>Lube</b> (2003-05) (ACDelco PF46).. <b>B31</b> <b>Lube</b> (2006-on)..... <b>B160</b> <b>Fuel</b> (2003-05 (Thd. Both Ends)) (ACDelco GF652)..... <b>BF853</b> <b>Fuel</b> (2003-05 (Thd. One End)) (ACDelco GF578)..... <b>BF1171</b> <b>Fuel</b> (2006-on) (N/S)..... <b>N/S</b>	Super Guide w/GM 6.0L Gas Eng. <b>Lube</b> (2003-06) (ACDelco PF46).. <b>B31</b> <b>Lube</b> (2007-on)..... <b>B160</b> <b>Fuel</b> (2003-05 (Thd. Both Ends)) (ACDelco GF652)..... <b>BF853</b> <b>Fuel</b> (2003-05 (Thd. One End)) (ACDelco GF578)..... <b>BF1171</b> <b>Fuel</b> (2006-on) (N/S)..... <b>N/S</b>
Vito w/OM646 2.2L Eng. Mexico <b>Fuel</b> (A6460920701)..... <b>BF7972</b>		
<b>MERITOR Axle Housings</b>		
3200 Series <b>Rear Axle</b> (To 11/93) (3280-V-5040)..... <b>B27</b> <b>Rear Axle</b> (11/93-on) (3280-V-8394)..... <b>B233</b>		
SL-100, SQ-100, SQHP <b>Rear Axle</b> (3280-V-5040)..... <b>B27</b>		
<b>MID BUS Buses</b>		
Grand Guide w/Ford 6.0L Diesel Eng. <b>Lube</b> (w/o Screw on Cap) (Motorcraft FL2016)..... <b>P7235</b> <b>Lube</b> (w/Screw on Cap) (Wix 57312)..... <b>P7436</b> <b>Fuel</b> (Motorcraft FD4606)..... <b>PF7852 KIT</b> <b>Channel Flow Air</b> (Motorcraft FA1746)..... <b>CA4999</b> <b>Trans. Ele.</b> (Motorcraft FT145).... <b>P7247</b> <b>Trans. Pan-Type</b> (To 11/07) (Motorcraft FT144)..... <b>20005</b> <b>Trans. Pan-Type</b> (11/07-on) (Motorcraft FT180)..... <b>20021</b>	Grand Guide w/GM 6.0L Gas Eng. <b>Lube</b> (2003-06) (ACDelco PF46).. <b>B31</b> <b>Lube</b> (2007-on)..... <b>B160</b> <b>Fuel</b> (2003-05 (Thd. Both Ends)) (ACDelco GF652)..... <b>BF853</b> <b>Fuel</b> (2003-05 (Thd. One End)) (ACDelco GF578)..... <b>BF1171</b> <b>Fuel</b> (2006-on) (N/S)..... <b>N/S</b> <b>Radial Seal Air</b> (ACDelco A1621C)..... <b>RS4131</b> <b>Trans.</b> (4L60E S. Pan) (24200796)..... <b>18010</b>	Super Guide w/GM 6.0L Gas Eng. <b>Lube</b> (2003-06) (ACDelco PF46).. <b>B31</b> <b>Lube</b> (2007-on)..... <b>B160</b> <b>Fuel</b> (2003-05 (Thd. Both Ends)) (ACDelco GF652)..... <b>BF853</b> <b>Fuel</b> (2003-05 (Thd. One End)) (ACDelco GF578)..... <b>BF1171</b> <b>Fuel</b> (2006-on) (N/S)..... <b>N/S</b>

<sup>+</sup> See Product Guide for Variations of This Number. <sup>89</sup> Inner Fender Liner Removal Recommended for Proper Installation.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MID BUS Buses (cont'd)	MITSUBISHI Diesel Engines (cont'd)	MITSUBISHI Diesel Engines (cont'd)
Super Guide w/GM 6.0L Gas Eng. (Cont'd)	4D31C, 4D31CT (3.3L)	8DC9
Radial Seal Air (ACDelco A1621C)..... RS4131	F-F Lube Spin-on (ME014833).... B7189	Lube..... P7000 KIT
Trans. (4L60E S. Pan) (24200796)..... 18010	B-P Lube Spin-on (ME014838).... BT338	Fuel..... PF7592
Trans. (4L60E D. Pan) (24208576)..... 18056	Fuel Spin-on (ME016823)..... BF792	
Trans. (4L80E) (24210956)..... 18027	Fuel Spin-on (ME035393)..... BF720	
Super Guide w/GM 6.6L Diesel Eng.	Fuel Spin-on (ME056670)..... BF7993	<b>MITSUBISHI</b> <b>European Light Duty Vehicles</b>
Lube (ACDelco PF2232)..... B1441	4D33, 4D34T, 4D35	Canter VI 2.5D w/4D56 Eng. (10/93-07/98)
Fuel/Water Separator (Upgrade) (ACDelco TP3018)..... BF46062 <sup>89</sup>	Dual-Flow Lube (ME013343)..... BD7028	Lube (MD013661)..... B202
Radial Seal Air (ACDelco A2032C)..... RS4859	Fuel Spin-on (ME016823)..... BF792	Lube (MD162326)..... B161-S
Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004	4P10 (3.0L)	Fuel (ME006066)..... BF7552
Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016	Lube (QC000001)..... P40037	Fuel (ME016872)..... BF792
Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003	Fuel (MK667920)..... PF46076	Canter VI 2.8TD w/4M40A Eng. (01/95-12/00)
Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017	4M40T	Dual-Flow Lube (ME013307)..... BD7028
Trans. Spin-on (Allison 29539579)..... BT8460	Dual-Flow Lube (ME013343)..... BD7028	Fuel (ME006066)..... BF7552
Steering (88892858)..... P106-HD	4M50 (4.9L) Turbo Diesel	Fuel (ME016872)..... BF792
<b>MITSUBISHI</b> <b>Buses</b>	Lube (ME088532)..... B7121	Canter VI 3.9TD w/4D34 Eng. (01/95-12/00)
BE64D w/4M50 Eng. (01/November/2007-on)	Fuel (ME222135)..... PF9803	Dual-Flow Lube (ME013307)..... BD7028
Dual-Flow Lube (ME088532)..... B7121	6D14C	Fuel (ME006066)..... BF7552
Fuel (14/November/2002-on) (ME222135)..... PF9803	Lube Ele. (ME034611)..... P249	Fuel (ME016872)..... BF792
Radial Seal Air (ME017246)..... RS4806	Dual-Flow Lube Spin-on (ME074013)..... BD1403	Canter VI 3.3TD w/4D31T Eng. (01/95-12/00)
BE649 w/4D34 Eng.	Fuel Spin-on (ME035829)..... BF720	Lube (ME004099)..... B109
Dual-Flow Lube (ME215002)..... BD7028	6D14T	Lube (ME014833)..... B7189
Fuel (From 13/November/2002) (ME016872)..... BF792	Dual-Flow Lube (ME074013)..... BD1403	Fuel (ME006066)..... BF7552
Fuel (14/November/2002-on) (ME132525)..... BF7842	Fuel (ME056670)..... BF7993	Fuel (ME016872)..... BF792
Radial Seal Air (ME017246)..... RS4806	6D15C	Canter VI 4.9TD w/6D31T Eng. (01/95-12/00)
BK w/6D14 Eng.	Lube Ele. (ME034611)..... P249	Lube (ME004099)..... B109
Dual-Flow Lube (ME074013)..... BD1403	Dual-Flow Lube Spin-on (ME074013)..... BD1403	Lube (ME014833)..... B7189
B-P Lube (ME034879)..... B7577	Fuel Spin-on (ME035393)..... BF720	Canter VII 35 3.0TD w/4M42T (Euro3) Eng. (07/01-06/05)
Fuel (ME035829)..... BF720	6D16, 6D16T (7.5L)	Dual-Flow Lube (ME013307)..... BD7028
Air (ME033717)..... PA2761	Lube Ele. (ME034611)..... P249	Canter VII 55 3.0TD w/4M42T (Euro3) Eng. (07/01-06/05)
Rosa	Dual-Flow Lube Spin-on (ME074013)..... BD1403	Dual-Flow Lube (ME013307)..... BD7028
Dual-Flow Lube (ME215002)..... BD7028	Fuel Spin-on (ME056670)..... BF7993	Canter VII 60 3.9TD w/4D34 Eng. (07/01-06/05)
Fuel (To 12/02) (ME132525)..... BF7842	6D22T, 6D22TC	Dual-Flow Lube (ME013307)..... BD7028
Fuel (12/02-on) (ME016872)..... BF792	Lube (ME064356)..... P7000 KIT	Canter VII 60 3.9TD w/4D34T (Euro3) Eng. (07/01-06/05)
Radial Seal Air (ME017246)..... RS4806	Fuel Ele. (ME971552)..... PF7592	Dual-Flow Lube (ME013307)..... BD7028
<b>MITSUBISHI</b> <b>Diesel Engines</b>	Fuel Spin-on (ME056670)..... BF7993	Canter VII 75 3.9TD w/4D34 Eng. (07/01-06/05)
4D30C, 4D30CT	6D31, 6D31T (5.0L)	Dual-Flow Lube (ME013307)..... BD7028
Dual-Flow Lube (ME013343)..... BD7028	F-F Lube Spin-on (ME084530).... B75	Canter VII 75 3.9TD w/4D34T (Euro3) Eng. (07/01-06/05)
Fuel Ele. (ME023835)..... P7103	B-P Lube Spin-on (ME014838).... BT338	Dual-Flow Lube (ME013307)..... BD7028
Fuel Spin-on (ME016823)..... BF792	Dual-Flow Lube (ME013343)..... BD7028	Canter VIII 3C11 w/4M42-3AT1 (Euro4) Eng. (06/05-on)
	Fuel Spin-on (ME035393)..... BF720	Dual-Flow Lube (ME013307)..... BD7028
	6DS70C	Fuel (ME132525)..... BF7842
	Lube Ele. (ME021074)..... P7021	Canter VIII 3C11D w/4M42-3AT1 (Euro4) Eng. (06/05-on)
	Fuel Ele. (ME023835)..... P7103	Dual-Flow Lube (ME013307)..... BD7028
	Fuel Spin-on (ME016823)..... BF792	Fuel (ME132525)..... BF7842
	6M60 (7.5L) Turbo Diesel	Canter VIII 3C13 w/4M42-3AT2 (Euro4) Eng. (06/05-on)
	Dual-Flow Lube (ME130968)..... BD1403	Dual-Flow Lube (ME013307)..... BD7028
	Fuel (ME301897)..... PF7982	Fuel (ME132525)..... BF7842
	8DC8	Canter VIII 3C13 w/4M42-3AT2 (Euro4) Eng. (06/05-on)
	Lube..... P7000 KIT	Dual-Flow Lube (ME013307)..... BD7028
		Fuel (ME132525)..... BF7842

<sup>89</sup> Inner Fender Liner Removal Recommended for Proper Installation.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>MITSUBISHI</b>	<b>MITSUBISHI</b>	<b>MITSUBISHI</b>
<b>European Light Duty Vehicles (cont'd)</b>	<b>European Light Duty Vehicles (cont'd)</b>	<b>European Light Duty Vehicles (cont'd)</b>
Canter VIII 3C13 w/4P10T2 (Euro 5) Eng. (2009-on) <b>Lube</b> (MK666096)..... <b>B7388</b>	Canter VIII 6C15 w/4M42-3AT4 (Euro4) Eng. (06/05-on) <b>Dual-Flow Lube</b> (ME013307)..... <b>BD7028</b> <b>Fuel</b> (ME132525)..... <b>BF7842</b>	Canter VIII 7C15D w/4P10T3 (Euro 5) Eng. (2009-on) <b>Lube</b> (MK666096)..... <b>B7388</b>
Canter VIII 3C13D w/4M42-3AT2 (Euro4) Eng. (06/05-on) <b>Dual-Flow Lube</b> (ME013307)..... <b>BD7028</b> <b>Fuel</b> (ME132525)..... <b>BF7842</b>	Canter VIII 6C15 w/4P10T3 (Euro 5) Eng. (2009-on) <b>Lube</b> (MK666096)..... <b>B7388</b>	Canter VIII 7C18 w/4M50-5AT5 (Euro4) Eng. (06/05-on) <b>Dual-Flow Lube</b> (ME013307)..... <b>BD7028</b> <b>Fuel</b> (ME132525)..... <b>BF7842</b>
Canter VIII 3C13D w/4P10T2 (Euro 5) Eng. (2009-on) <b>Lube</b> (MK666096)..... <b>B7388</b>	Canter VIII 6C15D w/145 HP Eng. (10/06-on) <b>Dual-Flow Lube</b> (ME013307)..... <b>BD7028</b> <b>Fuel</b> (ME132525)..... <b>BF7842</b>	Canter VIII 7C18 w/4P10T6 BlueTec 5 (Euro 5) Eng. (2009-on) <b>Lube</b> (MK666096)..... <b>B7388</b>
Canter VIII 3C15 w/4M42-3AT4 (Euro4) Eng. (06/05-on) <b>Dual-Flow Lube</b> (ME013307)..... <b>BD7028</b> <b>Fuel</b> (ME132525)..... <b>BF7842</b>	Canter VIII 6C15D w/4M42-3AT4 (Euro4) Eng. (06/05-on) <b>Dual-Flow Lube</b> (ME013307)..... <b>BD7028</b> <b>Fuel</b> (ME132525)..... <b>BF7842</b>	Canter VIII 7C18D w/4M50-5AT5 (Euro4) Eng. (06/05-on) <b>Dual-Flow Lube</b> (ME013307)..... <b>BD7028</b> <b>Fuel</b> (ME132525)..... <b>BF7842</b>
Canter VIII 3C15 w/4P10T3 (Euro 5) Eng. (2009-on) <b>Lube</b> (MK666096)..... <b>B7388</b>	Canter VIII 6C15D w/4P10T3 (Euro 5) Eng. (2009-on) <b>Lube</b> (MK666096)..... <b>B7388</b>	Canter VIII 7C18D w/4P10T6 BlueTec 5 (Euro 5) Eng. <b>Lube</b> (MK666096)..... <b>B7388</b>
Canter VIII 3S11 w/4M42-3AT1 (Euro4) Eng. (06/05-on) <b>Dual-Flow Lube</b> (ME013307)..... <b>BD7028</b> <b>Fuel</b> (ME132525)..... <b>BF7842</b>	Canter VIII 6C18 w/4M50-5AT5 (Euro4) Eng. (06/05-on) <b>Dual-Flow Lube</b> (ME013307)..... <b>BD7028</b> <b>Fuel</b> (ME132525)..... <b>BF7842</b>	L200 2.5 DI-D w/128 HP Eng. (04/10-on) <b>Dual-Flow Lube</b> (1230A045)..... <b>BD28</b> <b>Fuel</b> (1770A053)..... <b>BF7535</b>
Canter VIII 3S11D w/4M42-3AT1 (Euro4) Eng. (06/05-on) <b>Dual-Flow Lube</b> (ME013307)..... <b>BD7028</b> <b>Fuel</b> (ME132525)..... <b>BF7842</b>	Canter VIII 6C18 w/4P10T6 BlueTec 5 (Euro 5) Eng. (2009-on) <b>Lube</b> (MK666096)..... <b>B7388</b>	L200 2.5 DI-D w/136 HP Eng. (02/06-on) <b>Dual-Flow Lube</b> (1230A045)..... <b>BD28</b> <b>Fuel</b> (1770A053)..... <b>BF7535</b>
Canter VIII 3S13 w/130 HP Eng. (10/09-on) <b>Lube</b> (MK667378)..... <b>B7388</b>	Canter VIII 6C18D w/4M50-5AT5 (Euro4) Eng. (06/05-on) <b>Dual-Flow Lube</b> (ME013307)..... <b>BD7028</b> <b>Fuel</b> (ME132525)..... <b>BF7842</b>	L200 2.5 DI-D w/167 HP Eng. (10/07-on) <b>Dual-Flow Lube</b> (1230A045)..... <b>BD28</b> <b>Fuel</b> (1770A053)..... <b>BF7535</b>
Canter VIII 3S13 w/4M42-3AT2 125 HP (Euro4) Eng. (06/05-on) <b>Dual-Flow Lube</b> (ME013307)..... <b>BD7028</b> <b>Fuel</b> (ME132525)..... <b>BF7842</b>	Canter VIII 6C18D w/4P10T6 BlueTec 5 (Euro 5) Eng. (2009-on) <b>Lube</b> (MK666096)..... <b>B7388</b>	L200 2.5 DI-D w/178 HP Eng. (01/09-on) <b>Dual-Flow Lube</b> (1230A045)..... <b>BD28</b> <b>Fuel</b> (1770A053)..... <b>BF7535</b>
Canter VIII 3S13D w/4M42-3AT2 (Euro4) Eng. (06/05-on) <b>Dual-Flow Lube</b> (ME013307)..... <b>BD7028</b> <b>Fuel</b> (ME132525)..... <b>BF7842</b>	Canter VIII 7C14 w/1463 HP Eng. (06/05-on) <b>Dual-Flow Lube</b> (ME013307)..... <b>BD7028</b> <b>Fuel</b> (ME132525)..... <b>BF7842</b>	L200 2.5 TD (K64T/K74T) w/115 HP Eng. (10/01-03/06) <b>Dual-Flow Lube</b> (1230A045)..... <b>BD28</b> <b>Fuel</b> (MB220900)..... <b>BF7534</b> <b>Air</b> (MD620563)..... <b>PA3411-FN</b>
Canter VIII 3S13D w/4P10 Euro 5 Eng. (10/09-on) <b>Lube</b> (MK667378)..... <b>B7388</b>	Canter VIII 7C14D w/143 HP Eng. (06/05-on) <b>Dual-Flow Lube</b> (ME013307)..... <b>BD7028</b> <b>Fuel</b> (ME132525)..... <b>BF7842</b>	L200 2.5 TD (K64T/Liberty) w/133 HP Eng. (10/03-03/06) <b>Dual-Flow Lube</b> (1230A045)..... <b>BD28</b> <b>Fuel</b> (MB220900)..... <b>BF7534</b> <b>Air</b> (MD620563)..... <b>PA3411-FN</b>
Canter VIII 5S13 w/130 HP Eng. (10/09-on) <b>Lube</b> (MK667378)..... <b>B7388</b>	Canter VIII 7C15 w/4M42-3AT4 (Euro4) Eng. (06/05-on) <b>Dual-Flow Lube</b> (ME013307)..... <b>BD7028</b> <b>Fuel</b> (ME132525)..... <b>BF7842</b>	
Canter VIII 5S13D w/130 HP Eng. (10/09-on) <b>Lube</b> (MK667378)..... <b>B7388</b>	Canter VIII 7C15 w/4P10T3 (Euro 5) Eng. (2009-on) <b>Lube</b> (MK666096)..... <b>B7388</b>	<b>MITSUBISHI FUSO</b>
Canter VIII 6C14 w/143 HP Eng. (06/05-on) <b>Dual-Flow Lube</b> (ME013307)..... <b>BD7028</b> <b>Fuel</b> (ME132525)..... <b>BF7842</b>	Canter VIII 7C15D w/145 HP Eng. (10/06-on) <b>Dual-Flow Lube</b> (ME013307)..... <b>BD7028</b> <b>Fuel</b> (ME132525)..... <b>BF7842</b>	<b>Trucks</b>
Canter VIII 6C14D w/143 HP Eng. (06/05-on) <b>Dual-Flow Lube</b> (ME013307)..... <b>BD7028</b> <b>Fuel</b> (ME132525)..... <b>BF7842</b>	Canter VIII 7C15D w/4M42-3AT4 (Euro4) Eng. (06/05-on) <b>Dual-Flow Lube</b> (ME013307)..... <b>BD7028</b> <b>Fuel</b> (ME222135)..... <b>PF9803</b>	B620, B622 w/6DS3 Eng. <b>Lube Ele.</b> (ME021074)..... <b>P7021</b> <b>Fuel</b> (ME023835)..... <b>P7103</b>
Canter VIII 6C15 w/145 HP Eng. (10/06-on) <b>Dual-Flow Lube</b> (ME013307)..... <b>BD7028</b> <b>Fuel</b> (ME132525)..... <b>BF7842</b>		B623 w/6DS7 Eng. <b>Lube Ele.</b> (ME021074)..... <b>P7021</b> <b>Fuel</b> (ME023835)..... <b>P7103</b>
		Canter FE125 w/4P10 (3.0L) Eng. (2012-14) <b>Lube</b> (QC000001)..... <b>P40037</b> <b>Fuel</b> (MK667920)..... <b>PF46076</b> <b>Cab Air</b> (MK583342)..... <b>CLN&amp;R</b>

Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MITSUBISHI FUSO Trucks (cont'd)	MITSUBISHI FUSO Trucks (cont'd)	MITSUBISHI FUSO Trucks (cont'd)
Canter FE125 w/4P10 (3.0L) Eng. (2015-16) Lube (QC000001)..... <b>P40037</b> Fuel (MK667920)..... <b>PF46076</b>	Canter FE160 w/GM V8-364 (6.0L) Eng. (2020) (Cont'd) <b>Pan-Type Trans.</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Pan-Type Trans.</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Pan-Type Trans.</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	FB511 <b>Dual-Flow Lube</b> (ME202472)..... <b>BD7028</b> <b>Fuel/Water Separator</b> (MB220900)..... <b>BF7534</b>
Canter FE125 w/4P10 (3.0L) Eng. (2017) Lube (QC000001)..... <b>P40037</b> Fuel (MK667920)..... <b>PF46076</b>	Canter FE180 w/4P10 (3.0L) Eng. (2012-14) Lube (QC000001)..... <b>P40037</b> Fuel (MK667920)..... <b>PF46076</b> <b>Cab Air</b> (MK583342)..... <b>CLN&amp;R</b>	FB511B w/4M40 Eng. <b>Dual-Flow Lube</b> (ME202472)..... <b>BD7028</b> <b>Fuel/Water Separator</b> (MB220900)..... <b>BF7534</b>
Canter FE130 w/4P10 (3.0L) Eng. (2017) Lube (QC000001)..... <b>P40037</b> Fuel (MK667920)..... <b>PF46076</b> <b>Cabin Air</b> (MK583342)..... <b>CLN&amp;R</b>	Canter FE180 w/4P10 (3.0L) Eng. (2015-16) Lube (QC000001)..... <b>P40037</b> Fuel (MK667920)..... <b>PF46076</b> <b>Cabin Air</b> (MK583342)..... <b>CLN&amp;R</b>	FC432 Fuel (3888428)..... <b>BF928</b>
Canter FE140 w/GM V8-364 (6.0L) Eng. (2020) Fuel (N/S)..... <b>N/S</b> <b>Cab Air</b> (MK583342)..... <b>CLN&amp;R</b> <b>Pan-Type Trans.</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Pan-Type Trans.</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Pan-Type Trans.</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Pan-Type Trans.</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	Canter FE180 w/4P10 (3.0L) Eng. (2018) Lube (QC000001)..... <b>P40037</b> Fuel (ML239124)..... <b>PF46076</b>	FC432C w/4G54 Eng. Lube (MD360935)..... <b>B1402 +</b> Fuel (MB129591)..... <b>BF928</b>
Canter FE160 w/4P10 (3.0L) Eng. (2012-14) Lube (QC000001)..... <b>P40037</b> Fuel (MK667920)..... <b>PF46076</b> <b>Cab Air</b> (MK583342)..... <b>CLN&amp;R</b>	Canter FE180 w/GM V8-364 (6.0L) Eng. (2020) Fuel (N/S)..... <b>N/S</b> <b>Cab Air</b> (MK583342)..... <b>CLN&amp;R</b> <b>Pan-Type Trans.</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Pan-Type Trans.</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Pan-Type Trans.</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Pan-Type Trans.</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	FC432E w/4G54 Eng. Lube (MD360935)..... <b>B1402 +</b> Fuel (MB129591)..... <b>BF928</b>
Canter FE160 w/4P10 (3.0L) Eng. (2015-16) Lube (QC000001)..... <b>P40037</b> Fuel (MK667920)..... <b>PF46076</b> <b>Cabin Air</b> (MK583342)..... <b>CLN&amp;R</b>	Canter FG4x4 w/4P10 (3.0L) Eng. (2012-13) Lube (QC000001)..... <b>P40037</b> Fuel (MK667920)..... <b>PF46076</b> <b>Cab Air Front</b> (MK583342)..... <b>CLN&amp;R</b>	FE w/4D31-0AT (3.3L) Eng. (1987-91) F-F Lube (ME014833)..... <b>B7189</b> B-P Lube (ME014838)..... <b>BT338</b> Fuel (ME016823)..... <b>BF792</b> Fuel Spin-on (ME006066)..... <b>BF7552</b> 7 3/8 In. Air (MB120298)..... <b>PA3660-FN</b> 13 1/2 In. Air (ME033717)..... <b>PA2761</b>
Canter FE160 w/4P10 (3.0L) Eng. (2017) Lube (QC000001)..... <b>P40037</b> Fuel (MK667920)..... <b>PF46076</b> <b>Cabin Air</b> (MK583342)..... <b>CLN&amp;R</b>	Canter FG4x4 w/4P10 (3.0L) Eng. (2014-16) Lube (QC000001)..... <b>P40037</b> Fuel (MK667920)..... <b>PF46076</b> <b>Cabin Air</b> (MK583342)..... <b>CLN&amp;R</b>	FE w/4D31-0AT (3.3L) Eng. (1992-on) <b>Dual-Flow Lube</b> (ME215002)..... <b>BD7028</b> Fuel (ME015254)..... <b>BF720</b> Fuel Spin-on (ME006066)..... <b>BF7552</b> 7 3/8 In. Air (MB120298)..... <b>PA3660-FN</b> 13 1/2 In. Air (ME033717)..... <b>PA2761</b>
Canter FE160 w/4P10 (3.0L) Eng. (2018) Lube (QC000001)..... <b>P40037</b> Fuel (ML239124)..... <b>PF46076</b>	Canter FG4x4 w/4P10 (3.0L) Eng. (2017) Lube (QC000001)..... <b>P40037</b> Fuel (MK667920)..... <b>PF46076</b> <b>Cabin Air</b> (MK583342)..... <b>CLN&amp;R</b>	FE w/4D31-1AT3 (3.9L) Eng. (1992-95) <b>Dual-Flow Lube</b> (ME013343)..... <b>BD7028</b> Fuel Spin-on (ME016823)..... <b>BF792</b> Fuel Spin-on (ME015254)..... <b>BF720</b> Std. Air (ME033717)..... <b>PA2761</b> Radial Seal Air (ME017246)..... <b>RS4806</b>
Canter FE160 w/GM V8-364 (6.0L) Eng. (2019) Lube (89017524)..... <b>B160</b> Fuel (N/S)..... <b>N/S</b> <b>Cab Air</b> (MK583342)..... <b>CLN&amp;R</b> <b>Pan-Type Trans.</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Pan-Type Trans.</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Pan-Type Trans.</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Pan-Type Trans.</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	Canter FG4x4 w/4P10 (3.0L) Eng. (2018) Lube (QC000001)..... <b>P40037</b> Fuel (ML239124)..... <b>PF46076</b>	FE w/4D34-2AT3A (3.9L) Eng. (1996-98) <b>Dual-Flow Lube</b> (ME013343)..... <b>BD7028</b> Fuel Spin-on (ME016823)..... <b>BF792</b> Fuel Spin-on (ME015254)..... <b>BF720</b> Std. Air (ME033717)..... <b>PA2761</b> Radial Seal Air (ME017246)..... <b>RS4806</b>
Canter FE160 w/GM V8-364 (6.0L) Eng. (2020) Fuel (N/S)..... <b>N/S</b> <b>Cab Air</b> (MK583342)..... <b>CLN&amp;R</b> <b>Pan-Type Trans.</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>		FE w/4D34-3AT3A (3.9L) Eng. (1999) <b>Dual-Flow Lube</b> (ME013343)..... <b>BD7028</b> Fuel Spin-on (ME016823)..... <b>BF792</b> Fuel Spin-on (ME015254)..... <b>BF720</b> Std. Air (ME033717)..... <b>PA2761</b> Radial Seal Air (ME017246)..... <b>RS4806</b>
		FE w/4D34-3AT3B (3.9L) Eng. (2000-04) <b>Dual-Flow Lube</b> (ME013343)..... <b>BD7028</b> Fuel Spin-on (ME016823)..... <b>BF792</b> Fuel Spin-on (ME015254)..... <b>BF720</b> Std. Air (ME033717)..... <b>PA2761</b> Radial Seal Air (ME017246)..... <b>RS4806</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).




MITSUBISHI FUSO Trucks (cont'd)	MITSUBISHI FUSO Trucks (cont'd)	MITSUBISHI FUSO Trucks (cont'd)
FE5 Dual-Flow Lube (ME215002)..... <b>BD7028</b> Fuel (ME016872)..... <b>BF792</b>	FE120 w/4M50-3AT8 (4.9L) Eng. (2005) Lube (ME088532)..... <b>B7121</b> Fuel (ME222135)..... <b>PF9803 +</b> Radial Seal Air (ME017246)..... <b>RS4806</b>	FE444F w/4D34 Eng. F-F Lube (ME014833)..... <b>B7189</b> B-P Lube (ME014838)..... <b>BT338</b> Fuel (ME016872)..... <b>BF792</b>
FE6 Dual-Flow Lube (ME215002)..... <b>BD7028</b> Fuel (ME016872)..... <b>BF792</b>	FE125 w/4M50-3AT8 (4.9L) Eng. (2008-11) Lube (ME088532)..... <b>B7121</b> Fuel (ME222135)..... <b>PF9803 +</b> Radial Seal Air (ME017246)..... <b>RS4806</b>	FE449C w/4D34 Eng. F-F Lube (ME014833)..... <b>B7189</b> B-P Lube (ME014838)..... <b>BT338</b> Fuel (ME016872)..... <b>BF792</b>
FE73B w/4M40 Eng. Dual-Flow Lube (ME215002)..... <b>BD7028</b> Fuel (ME132525)..... <b>BF7842</b> Radial Seal Air (ME017246)..... <b>RS4806</b>	FE140 w/4M50-3AT7 (4.9L) Eng. (2006-07) Lube (ME088532)..... <b>B7121</b> Fuel (ME222135)..... <b>PF9803 +</b> Radial Seal Air (ME017246)..... <b>RS4806</b>	FE534 (To 09/02) Dual-Flow Lube (ME215002)..... <b>BD7028</b> Fuel (ME016872)..... <b>BF792</b>
FE83P (05/05-on) Dual-Flow Lube (ME215002)..... <b>BD7028</b> Fuel (ME015254)..... <b>BF720</b> Radial Seal Air (ME017246)..... <b>RS4806</b>	FE140 w/4M50-3AT8 (4.9L) Eng. (2006-07) Lube (ME088532)..... <b>B7121</b> Fuel (ME222135)..... <b>PF9803 +</b> Radial Seal Air (ME017246)..... <b>RS4806</b>	FE534 (09/02-on) Dual-Flow Lube (ME202472)..... <b>BD7028</b> Fuel (ME132525)..... <b>BF7842</b> Radial Seal Air (ME017246)..... <b>RS4806</b>
FE83PC w/4D34 Eng. Dual-Flow Lube (ME215002)..... <b>BD7028</b> Fuel (ME015254)..... <b>BF720</b> Radial Seal Air (ME017246)..... <b>RS4806</b>	FE145 w/4M50-3AT7 (4.9L) Eng. (2005-07) Lube (ME088532)..... <b>B7121</b> Fuel (ME222135)..... <b>PF9803 +</b> Radial Seal Air (ME017246)..... <b>RS4806</b>	FE534C w/4M42 Eng. Fuel (ME132525)..... <b>BF7842</b> Radial Seal Air (ME017246)..... <b>RS4806</b>
FE83PE w/4D34 Eng. Dual-Flow Lube (ME215002)..... <b>BD7028</b> Fuel (ME015254)..... <b>BF720</b> Radial Seal Air (ME017246)..... <b>RS4806</b>	FE145 w/4M50-3AT8 (4.9L) Eng. (2008-on) Lube (ME088532)..... <b>B7121</b> Fuel (ME222135)..... <b>PF9803 +</b> Radial Seal Air (ME017246)..... <b>RS4806</b>	FE537 (To 09/02) Dual-Flow Lube (ME202472)..... <b>BD7028</b> Fuel (ME132525)..... <b>BF7842</b> Fuel (ME016872)..... <b>BF792</b> Radial Seal Air (ME017246)..... <b>RS4806</b>
FE84P (05/05-on) Dual-Flow Lube (ME215002)..... <b>BD7028</b> Fuel (ME015254)..... <b>BF720</b> Radial Seal Air (ME017246)..... <b>RS4806</b>	FE145CC w/4M50-3AT8 (4.9L) Eng. (2005-11) Lube (ME088532)..... <b>B7121</b> Fuel (ME222135)..... <b>PF9803 +</b>	FE537B w/4D33 Eng. Dual-Flow Lube (ME215002)..... <b>BD7028</b> Fuel (ME016872)..... <b>BF792</b>
FE84PC w/4D34 Eng. Dual-Flow Lube (ME215002)..... <b>BD7028</b> Fuel (ME015254)..... <b>BF720</b> Radial Seal Air (ME017246)..... <b>RS4806</b>	FE180 w/4M50-3AT8 (4.9L) Eng. (2005-07) Lube (ME088532)..... <b>B7121</b> Fuel (ME222135)..... <b>PF9803 +</b> Radial Seal Air (ME017246)..... <b>RS4806</b>	FE537E w/4D33 Eng. Dual-Flow Lube (ME215002)..... <b>BD7028</b> Fuel (ME016872)..... <b>BF792</b>
FE84PE w/4D34 Eng. Dual-Flow Lube (ME215002)..... <b>BD7028</b> Fuel (ME015254)..... <b>BF720</b> Radial Seal Air (ME017246)..... <b>RS4806</b>	FE180 w/4M50-3AT8 (4.9L) Eng. (2008-11) Lube (ME088532)..... <b>B7121</b> Fuel (ME222135)..... <b>PF9803 +</b> Radial Seal Air (ME017246)..... <b>RS4806</b>	FE539B w/4D34 Eng. Dual-Flow Lube (ME215002)..... <b>BD7028</b> Fuel (ME016872)..... <b>BF792</b>
FE85P (05/05-on) Dual-Flow Lube (ME215002)..... <b>BD7028</b> Fuel (ME015254)..... <b>BF720</b> Radial Seal Air (ME017246)..... <b>RS4806</b>	FE334 F-F Lube (ME014833)..... <b>B7189</b> B-P Lube (ME014838)..... <b>BT338</b> Fuel (ME006066)..... <b>BF7552</b>	FE539E w/4D34 Eng. Dual-Flow Lube (ME215002)..... <b>BD7028</b> Fuel (ME016872)..... <b>BF792</b>
FE85PE w/4D34 Eng. Dual-Flow Lube (ME215002)..... <b>BD7028</b> Fuel (ME015254)..... <b>BF720</b> Radial Seal Air (ME017246)..... <b>RS4806</b>	FE334B w/4D31 Eng. F-F Lube (ME014833)..... <b>B7189</b> B-P Lube (ME014838)..... <b>BT338</b> Fuel (ME016872)..... <b>BF792</b>	FE637 Dual-Flow Lube (ME215002)..... <b>BD7028</b> Fuel (ME016872)..... <b>BF792</b>
FE85PJ w/4D34 Eng. Dual-Flow Lube (ME215002)..... <b>BD7028</b> Fuel (ME015254)..... <b>BF720</b> Radial Seal Air (ME017246)..... <b>RS4806</b>	FE339B w/4D34 Eng. F-F Lube (ME014833)..... <b>B7189</b> B-P Lube (ME014838)..... <b>BT338</b> Fuel (ME016872)..... <b>BF792</b>	FE637C w/4D33 Eng. Dual-Flow Lube (ME215002)..... <b>BD7028</b> Fuel (ME016872)..... <b>BF792</b>
FE101, K-FE101, FE111, K-FE111, FE211, K-FE211, FE221, K-FE211 w/6DS7 Eng. Fuel Ele. (ME023835)..... <b>P7103</b>	FE434 (Australia) F-F Lube (ME014833)..... <b>B7189</b> B-P Lube (ME014838)..... <b>BT338</b> Fuel (ME006066)..... <b>BF7552</b>	FE637E w/4D33 Eng. Dual-Flow Lube (ME215002)..... <b>BD7028</b> Fuel (ME016872)..... <b>BF792</b>
FE120 w/4M50-3AT7 (4.9L) Eng. (2005) Lube (ME088532)..... <b>B7121</b> Fuel (ME222135)..... <b>PF9803 +</b> Radial Seal Air (ME017246)..... <b>RS4806</b>	FE434, FE444 (1992-95) (USA) Dual-Flow Lube (ME215002)..... <b>BD7028</b> Fuel (ME015254)..... <b>BF720</b> Air (ME033717)..... <b>PA2761</b>	FE639 (09/02-on) (Australia) Dual-Flow Lube (ME215002)..... <b>BD7028</b> Fuel (ME015254)..... <b>BF720</b> Radial Seal Air (ME017246)..... <b>RS4806</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MITSUBISHI FUSO Trucks (cont'd)	MITSUBISHI FUSO Trucks (cont'd)	MITSUBISHI FUSO Trucks (cont'd)
FE647 Dual-Flow Lube (ME215002)..... BD7028 Fuel (ME016872)..... BF792	FE-SP w/4D34-2AT3B (3.9L) Eng. (1996-99) Dual-Flow Lube (ME215002)..... BD7028 Fuel (ME015254)..... BF720 Radial Seal Air (ME017246)..... RS4806	FG434C w/4D31 Eng. F-F Lube (ME014833)..... B7189 B-P Lube (ME014838)..... BT338 Fuel (ME016872)..... BF792
FE647C w/4D33 Eng. Dual-Flow Lube (ME215002)..... BD7028 Fuel (ME016872)..... BF792	FE-SP w/4D34-3AT3B (3.9L) Eng. (2000-04) Dual-Flow Lube (ME215002)..... BD7028 Fuel (ME015254)..... BF720 Radial Seal Air (ME017246)..... RS4806	FG439C w/4D34 Eng. F-F Lube (ME014833)..... B7189 B-P Lube (ME014838)..... BT338 Fuel (ME016872)..... BF792
FE647E w/4D33 Eng. Dual-Flow Lube (ME215002)..... BD7028 Fuel (ME016872)..... BF792	FE-SP w/4M50-1AT2 (4.9L) Eng. (2001-04) Lube (ME088532)..... B7121 Fuel (ME132525)..... BF7842 Radial Seal Air (ME017246)..... RS4806	FG439E w/4D34 Eng. F-F Lube (ME014833)..... B7189 B-P Lube (ME014838)..... BT338 Fuel (ME016872)..... BF792
FE649 (09/02-on) (Australia) Dual-Flow Lube (ME215002)..... BD7028 Fuel (ME015254)..... BF720 Radial Seal Air (ME017246)..... RS4806	K-FV215, K-FV215JR w/8DC9, 8DC9T Eng. Lube (ME064356)..... P7000 KIT Fuel (ME971552)..... PF7592 Air (31230-12700)..... PA1885 +	FG637 (4WD) Dual-Flow Lube (ME215002)..... BD7028 Fuel (ME016872)..... BF792
FE649C w/4D34 Eng. Dual-Flow Lube (ME215002)..... BD7028 Fuel (ME016872)..... BF792	FG w/4D31-0AT (3.3L) Eng. (1990-91) (USA) F-F Lube (ME014833)..... B7189 B-P Lube (ME014838)..... BT338 Fuel (ME016872)..... BF792 Air (ME033717)..... PA2761	FG637C w/4D33 Eng. Dual-Flow Lube (ME215002)..... BD7028 Fuel (ME016872)..... BF792
FE649E w/4D34 Eng. Dual-Flow Lube (ME215002)..... BD7028 Fuel (ME016872)..... BF792	FG w/4D34-1AT3 (3.9L) Eng. (1992-93) (USA) Dual-Flow Lube (ME215002)..... BD7028 Fuel (ME015254)..... BF720 Air (ME033717)..... PA2761	FG637E w/4D33 Eng. Dual-Flow Lube (ME215002)..... BD7028 Fuel (ME016872)..... BF792
FE657 Dual-Flow Lube (ME215002)..... BD7028 Fuel (ME016872)..... BF792	FG w/4D34-2AT3A (3.9L) Eng. (1998-99) (USA) Dual-Flow Lube (ME215002)..... BD7028 Fuel (ME015254)..... BF720 Radial Seal Air (ME017246)..... RS4806	FG639C w/4D34 (3.9L) Eng. Dual-Flow Lube (ME215002)..... BD7028 Fuel (ME016872)..... BF792
FE657E w/4D33 Eng. Dual-Flow Lube (ME215002)..... BD7028 Fuel (ME016872)..... BF792	FG w/4D34-3AT3A (3.9L) Eng. (2000-04) (USA) Dual-Flow Lube (ME215002)..... BD7028 Fuel (ME015254)..... BF720 Radial Seal Air (ME017246)..... RS4806	FG639E w/4D34 Eng. Dual-Flow Lube (ME215002)..... BD7028 Fuel (ME016872)..... BF792
FE657F w/4D33 Eng. Dual-Flow Lube (ME215002)..... BD7028 Fuel (ME016872)..... BF792	FG140 w/4P10 Eng. Lube (QC000001)..... P40037 Fuel (MK667920)..... PF46076	FG649 (09/02-on) (Australia) Dual-Flow Lube (ME215002)..... BD7028 Fuel (ME015254)..... BF720 Radial Seal O. Air (ME017246)..... RS4806
FE659 (09/02-on) Dual-Flow Lube (ME215002)..... BD7028 Fuel (ME015254)..... BF720 Radial Seal Air (ME017246)..... RS4806	FG140 w/4M50-3AT7 (4.9L) Eng. (2005-07) Lube (ME088532)..... B7121 Fuel (ME222135)..... PF9803 + Radial Seal Air (ME017246)..... RS4806	FG649 w/4D34 (3.9L) Eng. (2001-04) (USA) Dual-Flow Lube (ME215002)..... BD7028 Fuel (ME015254)..... BF720 Radial Seal Air (ME017246)..... RS4806
FE659E w/4D34 Eng. Dual-Flow Lube (ME215002)..... BD7028 Fuel (ME016872)..... BF792	FG140 w/4M50-3AT8 (4.9L) Eng. (2008-11) Lube (ME088532)..... B7121 Fuel (ME222135)..... PF9803 + Radial Seal Air (ME017246)..... RS4806	FG649C w/4D34 Eng. Dual-Flow Lube (ME215002)..... BD7028 Fuel (ME015254)..... BF720 Radial Seal O. Air (ME017246)..... RS4806
FE659F w/4D34 Eng. Dual-Flow Lube (ME215002)..... BD7028 Fuel (ME016872)..... BF792	FG180 w/4M50 Eng. (2005-on) Lube (ME088532)..... B7121	FG649E w/4D34 Eng. Dual-Flow Lube (ME215002)..... BD7028 Fuel (ME015254)..... BF720 Radial Seal O. Air (ME017246)..... RS4806
FE-CA w/4D34-3AT3B (3.9L) Eng. (2001) Dual-Flow Lube (ME215002)..... BD7028 Fuel (ME016823)..... BF792 Radial Seal Air (ME017246)..... RS4806	FG345 (1992-94) Dual-Flow Lube (ME215002)..... BD7028 Fuel (ME015254)..... BF720 Air (ME033717)..... PA2761	FH w/4M50-1AT2 (4.9L) Eng. (2003-04) Lube (ME088532)..... B7121 Fuel (ME132525)..... BF7842 Radial Seal Air (ME073160)..... RS3731
FE-HD w/4D34-2AT3A (3.9L) Eng. (1996-98) Dual-Flow Lube (ME215002)..... BD7028 Fuel (ME016823)..... BF792 Radial Seal Air (ME017246)..... RS4806	FG434 (Australia) F-F Lube (ME014833)..... B7189 B-P Lube (ME014838)..... BT338 Fuel (ME006066)..... BF7552	FH w/6D31-0AT (5.0L) Eng. (1988-91) F-F Lube (ME088519)..... B75 B-P Lube (ME014838)..... BT338 Fuel (ME015254)..... BF720 Air (ME033717)..... PA2761
FE-HD w/4D34-3AT3A (3.9L) Eng. (1999) Dual-Flow Lube (ME215002)..... BD7028 Fuel (ME016823)..... BF792 Radial Seal Air (ME017246)..... RS4806		
FE-HD w/4D34-3AT3B (3.9L) Eng. (2000-04) Dual-Flow Lube (ME215002)..... BD7028 Fuel (ME016823)..... BF792 Radial Seal Air (ME017246)..... RS4806		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MITSUBISHI FUSO Trucks (cont'd)	MITSUBISHI FUSO Trucks (cont'd)	MITSUBISHI FUSO Trucks (cont'd)
FH w/6D31-0AT (5.0L) Eng. (1992-on) <b>Dual-Flow Lube</b> (ME215002)..... <b>BD7028</b> <b>Fuel</b> (ME056670)..... <b>BF7993</b> <b>Air</b> (ME033717)..... <b>PA2761</b>	FK w/6D16-1AT4 (7.5L) Eng. (1992-95) (USA) <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME056670)..... <b>BF7993</b> <b>Air</b> (ME073252)..... <b>PA3906</b>	FK103, FK115, FK115DR w/6DS7 Eng. <b>Lube</b> (ME034481)..... <b>P7021</b> FK115 w/6D14-1A Eng. (1983-85) <b>Lube</b> (ME034611)..... <b>P249</b> <b>P. Fuel</b> (ME971553)..... <b>PF7592</b> <b>S. Fuel</b> (ME015254)..... <b>BF720</b> <b>Air</b> (ME060219)..... <b>PA1636-FN</b>
FH w/6D31-1AT2 (5.0L) Eng. (To 1992) <b>F-F Lube</b> (ME088519)..... <b>B75</b> <b>B-P Lube</b> (ME014838)..... <b>BT338</b> <b>Fuel</b> (ME015254)..... <b>BF720</b> <b>Air</b> (ME033717)..... <b>PA2761</b>	FK w/6D16-2AT3 (7.5L) Eng. (1996-99) (USA) <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME056670)..... <b>BF7993</b> <b>Radial Seal Air</b> (ME073821)..... <b>RS3731</b>	FK200 w/6M60 (7.5L) Eng. <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME306306)..... <b>PF7982 +</b> <b>Radial Seal Air</b> (ME073821)..... <b>RS3731</b> <b>Breather</b> (ME302763)..... <b>CV15011</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
FH w/6D31-1AT2 (5.0L) Eng. (1992-95) <b>Dual-Flow Lube</b> (ME215002)..... <b>BD7028</b> <b>Fuel</b> (ME056670)..... <b>BF7993</b> <b>Air</b> (ME033717)..... <b>PA2761</b>	FK w/6D16-2AT4 (7.5L) Eng. (1996-98) (USA) <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME056670)..... <b>BF7993</b> <b>Radial Seal Air</b> (ME073821)..... <b>RS3731</b>	FK260 w/6M60-3AT1 (7.5L) Eng. (To 2009) <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME301897)..... <b>PF7982 +</b> <b>Radial Seal Air</b> (ME073821)..... <b>RS3731</b> <b>Breather</b> (ME302763)..... <b>CV15011</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
FH w/6D34-0AT2 (5.9L) Eng. (1996-2002) <b>Dual-Flow Lube</b> (ME215002)..... <b>BD7028</b> <b>Fuel</b> (ME056670)..... <b>BF7993</b> <b>Axial Seal Air</b> (ME033603)..... <b>PA2784</b>	FK w/6D16-3AT3 (7.5L) Eng. (2000-2004) (USA) <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME056670)..... <b>BF7993</b> <b>Radial Seal Air</b> (ME073821)..... <b>RS3731</b>	FK260 w/6M60-3AT1 (7.5L) Eng. (2010) <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME306306)..... <b>PF7982 +</b> <b>Radial Seal Air</b> (ME413506)..... <b>RS3731</b> <b>Breather</b> (ME302763)..... <b>CV15011</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
FH w/6D34-0AT2 (5.9L) Eng. (2003-04) <b>Dual-Flow Lube</b> (ME215002)..... <b>BD7028</b> <b>Fuel</b> (ME056670)..... <b>BF7993</b> <b>Radial Seal Air</b> (ME073160)..... <b>RS3731</b>	FK61F (09/02-on) <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>P. Fuel</b> (ME300361)..... <b>PF9890</b> <b>S. Fuel</b> (ME131824)..... <b>BF798</b> <b>Radial Seal O. Air</b> (ME073821)..... <b>RS3731</b> <b>Radial Seal I. Air</b> (ME291563)..... <b>RS3732</b>	FK260 w/6M60-3AT1 (7.5L) Eng. (2011-on) <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME306306)..... <b>PF7982 +</b> <b>Radial Seal Air</b> (ME413506)..... <b>RS3731</b> <b>Breather</b> (ME302763)..... <b>CV15011</b>
FH100 (Australia) <b>Dual-Flow Lube</b> (ME215002)..... <b>BD7028</b> <b>Fuel</b> (ME015254)..... <b>BF720</b> <b>O. Air</b> (ME033717)..... <b>PA2761</b> <b>I. Air</b> (ME033773)..... <b>PA3417</b>	FK61FH w/6M60 Eng. <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME131824)..... <b>BF798</b> <b>Fuel</b> (ME300361)..... <b>PF9890</b> <b>Radial Seal O. Air</b> (ME073821)..... <b>RS3731</b>	
FH100G w/6D31 Eng. <b>Dual-Flow Lube</b> (ME215002)..... <b>BD7028</b> <b>Fuel</b> (ME016872)..... <b>BF792</b> <b>O. Air</b> (ME033717)..... <b>PA2761</b> <b>I. Air</b> (ME033773)..... <b>PA3417</b>	FK61FK w/6M60 Eng. <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME131824)..... <b>BF798</b> <b>Fuel</b> (ME300361)..... <b>PF9890</b> <b>Radial Seal O. Air</b> (ME073821)..... <b>RS3731</b>	
FH100H w/6D31 Eng. <b>Dual-Flow Lube</b> (ME215002)..... <b>BD7028</b> <b>Fuel</b> (ME016872)..... <b>BF792</b> <b>O. Air</b> (ME033717)..... <b>PA2761</b> <b>I. Air</b> (ME033773)..... <b>PA3417</b>	FK61FL w/6M60 Eng. <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME131824)..... <b>BF798</b> <b>Fuel</b> (ME300361)..... <b>PF9890</b> <b>Radial Seal O. Air</b> (ME073821)..... <b>RS3731</b>	
FK w/6D14-2AT (6.6L) Eng. (1986-87) (USA) <b>F-F Lube</b> (ME034878)..... <b>B75</b> <b>B-P Lube</b> (ME034879)..... <b>B7577</b> <b>Fuel</b> (ME035394)..... <b>BF7529</b> <b>Air</b> (ME033717)..... <b>PA2761</b>	FK61FM w/6M60 Eng. <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME131824)..... <b>BF798</b> <b>Fuel</b> (ME300361)..... <b>PF9890</b> <b>Radial Seal O. Air</b> (ME073821)..... <b>RS3731</b>	
FK w/6D14-2AT (6.6L) Eng. (1988-91) (USA) <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME015254)..... <b>BF720</b> <b>Air</b> (ME033603)..... <b>PA2784</b>	FK61FL w/6M60 Eng. <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME131824)..... <b>BF798</b> <b>Fuel</b> (ME300361)..... <b>PF9890</b> <b>Radial Seal O. Air</b> (ME073821)..... <b>RS3731</b>	
FK w/6D14-2AT2 (6.6L) Eng. (1986-87) (USA) <b>F-F Lube</b> (ME034878)..... <b>B75</b> <b>B-P Lube</b> (ME034879)..... <b>B7577</b> <b>Fuel</b> (ME035394)..... <b>BF7529</b> <b>Air</b> (ME033717)..... <b>PA2761</b>	FK102 w/6D70 Eng. <b>Lube</b> (ME021074)..... <b>P7021</b> <b>90.5 mm Fuel</b> (ME023835)..... <b>P7103</b>	
FK w/6D14-2AT2 (6.6L) Eng. (1988-91) (USA) <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME015254)..... <b>BF720</b> <b>Air</b> (ME033603)..... <b>PA2784</b>	FK102, FK102F20, FK102J20, K-FK102, K-MK102 w/6DS7 Eng. <b>Lube Ele.</b> (ME021074)..... <b>P7021</b> <b>Fuel Ele.</b> (1976-79) (ME023835)..... <b>P7103</b> <b>Fuel</b> (1980-83) (ME971553)..... <b>PF7592</b> <b>Fuel Spin-on</b> (1980-83) (ME016872)..... <b>BF792</b>	


\* See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>MITSUBISHI FUSO Trucks (cont'd)</b>	<b>MITSUBISHI FUSO Trucks (cont'd)</b>	<b>MITSUBISHI FUSO Trucks (cont'd)</b>
FK260 w/6M60-3AT1 (7.5L) Eng. (2011-on) (Cont'd) <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	FK417KS w/6D16 Eng. <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME015254)..... <b>BF720</b> <b>O. Air</b> (ME073252)..... <b>PA3906</b> <b>I. Air</b> (ME073385)..... <b>PA5412</b>	FK617GS w/6D16 Eng. <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME131989)..... <b>BF798</b> <b>Radial Seal O. Air</b> (ME073821)... <b>RS3731</b> <b>Radial Seal I. Air</b> (ME291563)..... <b>RS3732</b>
FK415 w/6D14-2A Eng. (1985-89) (Australia) <b>Lube Ele.</b> (1985-89) (ME034611). <b>P249</b> <b>Fuel</b> (ME015254)..... <b>BF720</b> <b>O. Air</b> (ME033717)..... <b>PA2761</b> <b>I. Air</b> (1986-92) (ME033773)..... <b>PA3417</b>	FK417KW w/6D16 Eng. <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME015254)..... <b>BF720</b> <b>O. Air</b> (ME033717)..... <b>PA2761</b> <b>I. Air</b> (ME033773)..... <b>PA3417</b>	FK617HH w/6D16 Eng. <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME015254)..... <b>BF720</b> <b>Radial Seal O. Air</b> (ME073160)... <b>RS3731</b> <b>Radial Seal I. Air</b> (ME291563)..... <b>RS3732</b>
FK415FR w/6D14 Eng. <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME015254)..... <b>BF720</b> <b>O. Air</b> (ME033717)..... <b>PA2761</b> <b>I. Air</b> (ME033773)..... <b>PA3417</b>	FK455 w/6D14-2A Eng. (1987-89) (Australia) <b>Lube</b> (ME034611)..... <b>P249</b> <b>Fuel</b> (ME015254)..... <b>BF720</b> <b>O. Air</b> (ME033717)..... <b>PA2761</b> <b>I. Air</b> (ME033773)..... <b>PA3417</b>	FK617HJ w/6D16 Eng. <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME015254)..... <b>BF720</b> <b>Radial Seal O. Air</b> (ME073160)... <b>RS3731</b> <b>Radial Seal I. Air</b> (ME291563)..... <b>RS3732</b>
FK415KR w/6D14 Eng. <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME015254)..... <b>BF720</b> <b>O. Air</b> (ME033717)..... <b>PA2761</b> <b>I. Air</b> (ME033773)..... <b>PA3417</b>	FK FK455 w/6D14 (6.6L) Eng. (1986-87) (USA) <b>F-F Lube</b> (ME034878)..... <b>B75</b> <b>B-P Lube</b> (ME034879)..... <b>B7577</b> <b>Fuel</b> (ME035394)..... <b>BF7529</b> <b>Air</b> (ME033717)..... <b>PA2761</b>	FK617HS w/6D16 Eng. <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME131989)..... <b>BF798</b> <b>Radial Seal O. Air</b> (ME073821)... <b>RS3731</b> <b>Radial Seal I. Air</b> (ME291563)..... <b>RS3732</b>
FK417 (Australia) <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME015254)..... <b>BF720</b> <b>O. Air</b> (Non-Turbo) (ME033717)... <b>PA2761</b> <b>I. Air</b> (Non-Turbo) (ME033773).... <b>PA3417</b> <b>O. Air</b> (Turbo) (ME073252)..... <b>PA3906</b> <b>I. Air</b> (Turbo) (ME073385)..... <b>PA5412</b> <b>O. Air</b> (Turbo Crew Cab) (ME033603)..... <b>PA2784</b> <b>I. Air</b> (Turbo Crew Cab) (ME033839)..... <b>PA3578</b>	FK FK455 w/6D14 (6.6L) Eng. (1988-91) (USA) <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME015254)..... <b>BF720</b> <b>Air</b> (ME033603)..... <b>PA2784</b>	FK617KJ w/6D16 Eng. <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME015254)..... <b>BF720</b> <b>Radial Seal O. Air</b> (ME073160)... <b>RS3731</b> <b>Radial Seal I. Air</b> (ME291563)..... <b>RS3732</b>
FK417FR w/6D16 Eng. <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME015254)..... <b>BF720</b> <b>O. Air</b> (ME033717)..... <b>PA2761</b> <b>I. Air</b> (ME033773)..... <b>PA3417</b>	FK457 (Australia) <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME015254)..... <b>BF720</b> <b>O. Air</b> (Non-Turbo) (ME033717)... <b>PA2761</b> <b>I. Air</b> (Non-Turbo) (ME033773).... <b>PA3417</b> <b>O. Air</b> (Turbo) (ME073252)..... <b>PA3906</b> <b>I. Air</b> (Turbo) (ME073385)..... <b>PA5412</b>	FK617KW w/6D16 Eng. <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME015254)..... <b>BF720</b> <b>O. Air</b> (ME033717)..... <b>PA2761</b> <b>I. Air</b> (ME033773)..... <b>PA3417</b>
FK417FS w/6D16 Eng. <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME015254)..... <b>BF720</b> <b>I. Air</b> (ME073385)..... <b>PA5412</b>	FK457KR w/6D16 Eng. <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME015254)..... <b>BF720</b> <b>O. Air</b> (ME033717)..... <b>PA2761</b> <b>I. Air</b> (ME033773)..... <b>PA3417</b>	FK617LH w/6D16 Eng. <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME015254)..... <b>BF720</b> <b>Radial Seal O. Air</b> (ME073160)... <b>RS3731</b> <b>Radial Seal I. Air</b> (ME291563)..... <b>RS3732</b>
FK417HS w/6D16 Eng. <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME015254)..... <b>BF720</b> <b>O. Air</b> (ME073252)..... <b>PA3906</b> <b>I. Air</b> (ME073385)..... <b>PA5412</b>	FK457KS w/6D16 Eng. <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME015254)..... <b>BF720</b> <b>O. Air</b> (ME073252)..... <b>PA3906</b> <b>I. Air</b> (ME073385)..... <b>PA5412</b>	FK617LW w/6D16 Eng. <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME015254)..... <b>BF720</b> <b>O. Air</b> (ME033717)..... <b>PA2761</b> <b>I. Air</b> (ME033773)..... <b>PA3417</b>
FK417KR w/6D16 Eng. <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME015254)..... <b>BF720</b> <b>O. Air</b> (ME033717)..... <b>PA2761</b> <b>I. Air</b> (ME033773)..... <b>PA3417</b>	FK617GJ w/6D16 Eng. <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME015254)..... <b>BF720</b> <b>Radial Seal O. Air</b> (ME073160)... <b>RS3731</b> <b>Radial Seal I. Air</b> (ME291563).... <b>RS3732</b>	FK618 <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME015254)..... <b>BF720</b> <b>Radial Seal O. Air</b> (AW347463)... <b>RS3731</b> <b>Radial Seal I. Air</b> (ME291563)..... <b>RS3732</b>

Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MITSUBISHI FUSO Trucks (cont'd)	MITSUBISHI FUSO Trucks (cont'd)	MITSUBISHI FUSO Trucks (cont'd)
FK618HJ w/6D17 Eng. Dual-Flow Lube (ME130968)..... <b>BD1403</b> Fuel (ME015254)..... <b>BF720</b> Radial Seal O. Air (ME073160)... <b>RS3731</b> Radial Seal I. Air (ME291563).... <b>RS3732</b>	FM w/6D16-0AT2 (7.5L) Eng. (1992-95) (USA) Dual-Flow Lube (ME130968)..... <b>BD1403</b> Fuel (ME056670)..... <b>BF7993</b> Air (ME073252)..... <b>PA3906</b>	FM65FL w/6M60 Eng. Dual-Flow Lube (ME130968)..... <b>BD1403</b> Fuel (ME131824)..... <b>BF798</b> Fuel (ME300361)..... <b>PF9890</b> Radial Seal O. Air (ME073821)... <b>RS3731</b> Radial Seal I. Air (ME291563).... <b>RS3732</b>
FK618KJ w/6D17 Eng. Dual-Flow Lube (ME130968)..... <b>BD1403</b> Fuel (ME015254)..... <b>BF720</b> Radial Seal O. Air (ME073160)... <b>RS3731</b> Radial Seal I. Air (ME291563).... <b>RS3732</b>	FM w/6D16-1AT2 (7.5L) Eng. (1990-91) (USA) Dual-Flow Lube (ME130968)..... <b>BD1403</b> Fuel (ME015254)..... <b>BF720</b> Fuel (ME056670)..... <b>BF7993</b> Air (ME073252)..... <b>PA3906</b>	FM65FM w/6M60 Eng. Dual-Flow Lube (ME130968)..... <b>BD1403</b> Fuel (ME131824)..... <b>BF798</b> Fuel (ME300361)..... <b>PF9890</b> Radial Seal O. Air (ME073821)... <b>RS3731</b> Radial Seal I. Air (ME291563).... <b>RS3732</b>
FK618LH w/6D17 Eng. Dual-Flow Lube (ME130968)..... <b>BD1403</b> Fuel (ME015254)..... <b>BF720</b> Radial Seal O. Air (ME073160)... <b>RS3731</b> Radial Seal I. Air (ME291563).... <b>RS3732</b>	FM w/6D16-1AT2 (7.5L) Eng. (1992-95) (USA) Dual-Flow Lube (ME130968)..... <b>BD1403</b> Fuel (ME056670)..... <b>BF7993</b> Air (ME073252)..... <b>PA3906</b>	FM65FP w/6M60 Eng. Dual-Flow Lube (ME130968)..... <b>BD1403</b> Fuel (ME131824)..... <b>BF798</b> Fuel (ME300361)..... <b>PF9890</b> Radial Seal O. Air (ME073821)... <b>RS3731</b> Radial Seal I. Air (ME291563).... <b>RS3732</b>
FK618LW w/6D17 Eng. Dual-Flow Lube (ME130968)..... <b>BD1403</b> Fuel (ME015254)..... <b>BF720</b> O. Air (ME033717)..... <b>PA2761</b> I. Air (ME033773)..... <b>PA3417</b>	FM w/6D16-1AT4 (7.5L) Eng. (1990-91) (USA) Dual-Flow Lube (ME130968)..... <b>BD1403</b> Fuel (ME015254)..... <b>BF720</b> Air (ME073252)..... <b>PA3906</b>	FM67F (09/02-on) Dual-Flow Lube (ME130968)..... <b>BD1403</b> P. Fuel (ME300361)..... <b>PF9890</b> S. Fuel (ME131824)..... <b>BF798</b> Radial Seal O. Air (ME073821)... <b>RS3731</b> Radial Seal I. Air (ME291563).... <b>RS3732</b>
FL439 F-F Lube (ME014833)..... <b>B7189</b> B-P Lube (ME014838)..... <b>BT338</b> Fuel (ME006066)..... <b>BF7552</b>	FM w/6D16-1AT4 (7.5L) Eng. (1992-95) (USA) Dual-Flow Lube (ME130968)..... <b>BD1403</b> Fuel (ME056670)..... <b>BF7993</b> Air (ME073252)..... <b>PA3906</b>	FM67FM w/6D16 Eng. Dual-Flow Lube (ME130968)..... <b>BD1403</b> Fuel (ME131824)..... <b>BF798</b> Fuel (ME300361)..... <b>PF9890</b> Radial Seal O. Air (ME073821)... <b>RS3731</b> Radial Seal I. Air (ME291563).... <b>RS3732</b>
FLK617KS w/6D16 Eng. Dual-Flow Lube (ME130968)..... <b>BD1403</b> Fuel (ME131989)..... <b>BF798</b> Radial Seal O. Air (ME073821)... <b>RS3731</b> Radial Seal I. Air (ME291563).... <b>RS3732</b>	FM61F (09/02-on) Dual-Flow Lube (ME130968)..... <b>BD1403</b> P. Fuel (ME300361)..... <b>PF9890</b> S. Fuel (ME131824)..... <b>BF798</b> Radial Seal O. Air (ME073821)... <b>RS3731</b> Radial Seal I. Air (ME291563).... <b>RS3732</b>	FM67FP w/6D16 Eng. Dual-Flow Lube (ME130968)..... <b>BD1403</b> Fuel (ME131824)..... <b>BF798</b> Fuel (ME300361)..... <b>PF9890</b> Radial Seal O. Air (ME073821)... <b>RS3731</b> Radial Seal I. Air (ME291563).... <b>RS3732</b>
FM w/6D14-2AT (6.6L) Eng. (1986-87) Lube Ele. (ME034611)..... <b>P249</b> Dual-Flow Lube Spin-on (ME074013)..... <b>BD1403</b> B-P Lube Spin-on (ME034879)... <b>B7577</b> Fuel (ME035394)..... <b>BF7529</b> Air (ME033603)..... <b>PA2784</b> Air (ME073252)..... <b>PA3906</b>	FM61FH w/6M60 Eng. Dual-Flow Lube (ME130968)..... <b>BD1403</b> Fuel (ME131824)..... <b>BF798</b> Fuel (ME300361)..... <b>PF9890</b> Radial Seal O. Air (ME073821)... <b>RS3731</b> Radial Seal I. Air (ME291563).... <b>RS3732</b>	FM104 w/6D11 Eng. Lube (ME034481)..... <b>P7021</b> 90.5 mm Fuel (ME023835)..... <b>P7103</b> Air (ME060219)..... <b>PA1636-FN</b>
FM w/6D14-2AT (6.6L) Eng. (1988-89) Lube Ele. (ME034611)..... <b>P249</b> Dual-Flow Lube Spin-on (ME074013)..... <b>BD1403</b> B-P Lube Spin-on (ME034879)... <b>B7577</b> Fuel (ME035829)..... <b>BF720</b> Air (ME033603)..... <b>PA2784</b> Air (ME073252)..... <b>PA3906</b>	FM61FM w/6M60 Eng. Dual-Flow Lube (ME130968)..... <b>BD1403</b> Fuel (ME131824)..... <b>BF798</b> Fuel (ME300361)..... <b>PF9890</b> Radial Seal O. Air (ME073821)... <b>RS3731</b> Radial Seal I. Air (ME291563).... <b>RS3732</b>	FM215 w/6D14 Eng. (To Eng. # 258720) Lube (ME034481)..... <b>P7021</b> 110.3 mm Fuel (ME036478)..... <b>PF7758<sup>90</sup></b>
FM w/6D14-2AT (6.6L) Eng. (1990-91) Lube Ele. (ME034611)..... <b>P249</b> Dual-Flow Lube Spin-on (ME074013)..... <b>BD1403</b> B-P Lube Spin-on (ME034879)... <b>B7577</b> Air (ME033603)..... <b>PA2784</b> Air (ME073252)..... <b>PA3906</b>	FM65F (09/02-on) Dual-Flow Lube (ME130968)..... <b>BD1403</b> P. Fuel (ME300361)..... <b>PF9890</b> S. Fuel (ME131824)..... <b>BF798</b> Radial Seal O. Air (ME073821)... <b>RS3731</b> Radial Seal I. Air (ME291563).... <b>RS3732</b>	FM215 w/6D14 Eng. (Eng. # 258721-on) Lube (ME034611)..... <b>P249</b> Fuel Ele. (ME971553)..... <b>PF7592</b> Fuel Spin-on (ME015254)..... <b>BF720</b>
FM w/6D16-0AT2 (7.5L) Eng. (1990-91) (USA) Dual-Flow Lube (ME130968)..... <b>BD1403</b> Fuel (ME015254)..... <b>BF720</b> Air (ME073252)..... <b>PA3906</b>	FM65FH w/6M60 Eng. Dual-Flow Lube (ME130968)..... <b>BD1403</b> Fuel (ME131824)..... <b>BF798</b> Fuel (ME300361)..... <b>PF9890</b> Radial Seal O. Air (ME073821)... <b>RS3731</b> Radial Seal I. Air (ME291563).... <b>RS3732</b>	FM260 w/6M60 (7.5L) Eng. (To 2008) Dual-Flow Lube (ME130968)..... <b>BD1403</b> Fuel (ME301897)..... <b>PF7982 +</b> Radial Seal Air (ME073821)..... <b>RS3731</b> Breather (ME302763)..... <b>CV15011</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.

Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MITSUBISHI FUSO Trucks (cont'd)	MITSUBISHI FUSO Trucks (cont'd)	MITSUBISHI FUSO Trucks (cont'd)
FM260 w/6M60 (7.5L) Eng. (To 2008) (Cont'd) <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	FM330 w/6M60-3AT2 (7.5L) Eng. (To 2008) <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME301897)..... <b>PF7982 +</b> <b>Radial Seal Air</b> (ME073821)..... <b>RS3731</b> <b>Breather</b> (ME302763)..... <b>CV15011</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	FM517HS w/6D16 Eng. <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME015254)..... <b>BF720</b> <b>O. Air</b> (ME073252)..... <b>PA3906</b> <b>I. Air</b> (ME073385)..... <b>PA5412</b>
FM260 w/6M60 (7.5L) Eng. (2009-on) <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME301897)..... <b>PF7982 +</b> <b>Radial Seal Air</b> (ME413506)..... <b>RS3731</b> <b>Breather</b> (ME302763)..... <b>CV15011</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	FM330 w/6M60-3AT2 (7.5L) Eng. (2008-09) <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME301897)..... <b>PF7982 +</b> <b>Breather</b> (ME302763)..... <b>CV15011</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	FM517MR w/6D16 Eng. <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME015254)..... <b>BF720</b> <b>O. Air</b> (ME033717)..... <b>PA2761</b> <b>I. Air</b> (ME033773)..... <b>PA3417</b>
FM330 w/6M60-3AT1 (7.5L) Eng. (To 2008) <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME301897)..... <b>PF7982 +</b> <b>Radial Seal Air</b> (ME073821)..... <b>RS3731</b> <b>Breather</b> (ME302763)..... <b>CV15011</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	FM330 w/6M60-3AT2 (7.5L) Eng. (2009-10) <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Radial Seal Air</b> (ME413506)..... <b>RS3731</b> <b>Breather</b> (ME302763)..... <b>CV15011</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	FM517MS w/6D16 Eng. <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME015254)..... <b>BF720</b> <b>O. Air</b> (ME073252)..... <b>PA3906</b> <b>I. Air</b> (ME073385)..... <b>PA5412</b>
FM330 w/6M60-3AT1 (7.5L) Eng. (2008) <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME301897)..... <b>PF7982 +</b> <b>Radial Seal Air</b> (ME413506)..... <b>RS3731</b> <b>Breather</b> (ME302763)..... <b>CV15011</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	FM330 w/6M60-3AT2 (7.5L) Eng. (2010-on) <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME306306)..... <b>PF7982 +</b> <b>Radial Seal Air</b> (ME413506)..... <b>RS3731</b> <b>Breather</b> (ME302763)..... <b>CV15011</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	FM517MW w/6D16 Eng. <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME015254)..... <b>BF720</b> <b>O. Air</b> (ME033717)..... <b>PA2761</b> <b>I. Air</b> (ME033773)..... <b>PA3417</b>
FM330 w/6M60-3AT1 (7.5L) Eng. (2009) <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Radial Seal Air</b> (ME413506)..... <b>RS3731</b> <b>Breather</b> (ME302763)..... <b>CV15011</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	FM515 <b>Lube</b> (ME034611)..... <b>P249</b> <b>Fuel</b> (ME015254)..... <b>BF720</b> <b>Single Air</b> (Non-Turbo) (ME033717)..... <b>PA2761</b> <b>Single Air</b> (Turbo) (ME033603)..... <b>PA2784</b> <b>O. Air</b> (Non-Turbo) (ME033717)..... <b>PA2761</b> <b>I. Air</b> (Non-Turbo) (ME033773)..... <b>PA3417</b> <b>O. Air</b> (Turbo) (ME033603)..... <b>PA2784</b> <b>I. Air</b> (Turbo) (ME033839)..... <b>PA3578</b>	FM555 w/6D14 Eng. (1988-89) (Australia) <b>Lube</b> (ME034611)..... <b>P249</b> <b>Fuel</b> (ME015254)..... <b>BF720</b> <b>O. Air</b> (AE033603)..... <b>PA2784</b> <b>I. Air</b> (ME033839)..... <b>PA3578</b>
FM330 w/6M60-3AT1 (7.5L) Eng. (2010-11) <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME306306)..... <b>PF7982 +</b> <b>Radial Seal Air</b> (ME413506)..... <b>RS3731</b> <b>Breather</b> (ME302763)..... <b>CV15011</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	FM517 <b>Lube</b> (ME034611)..... <b>P249</b> <b>Fuel</b> (ME015254)..... <b>BF720</b> <b>Single Air</b> (Non-Turbo) (ME033717)..... <b>PA2761</b> <b>Single Air</b> (Turbo) (ME033603)..... <b>PA2784</b> <b>O. Air</b> (Non-Turbo) (ME033717)..... <b>PA2761</b> <b>I. Air</b> (Non-Turbo) (ME033773)..... <b>PA3417</b> <b>O. Air</b> (Turbo) (ME033603)..... <b>PA2784</b> <b>I. Air</b> (Turbo) (ME033839)..... <b>PA3578</b>	FM FM555 Fuso w/6D14 (6.6L) Eng. (1986-87) (USA) <b>F-F Lube</b> (ME034878)..... <b>B75</b> <b>B-P Lube</b> (ME034879)..... <b>B7577</b> <b>Fuel</b> (ME035394)..... <b>BF7529</b> <b>Air</b> (ME033603)..... <b>PA2784</b>
FM330 w/6M60-3AT1 (7.5L) Eng. (2010-11) <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME306306)..... <b>PF7982 +</b> <b>Radial Seal Air</b> (ME413506)..... <b>RS3731</b> <b>Breather</b> (ME302763)..... <b>CV15011</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	FM517 w/6D16 Eng. (1991-95) <b>Fuel</b> (ME015254)..... <b>BF720</b> <b>O. Air</b> (ME033717)..... <b>PA2761</b> <b>I. Air</b> (ME033773)..... <b>PA3417</b> <b>O. Air</b> (ME033603)..... <b>PA2784</b> <b>I. Air</b> (ME033839)..... <b>PA3578</b> <b>O. Air</b> (ME073252)..... <b>PA3906</b> <b>I. Air</b> (ME073385)..... <b>PA5412</b>	FM FM555 Fuso w/6D14 (6.6L) Eng. (1988-91) (USA) <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME015254)..... <b>BF720</b> <b>Air</b> (ME033603)..... <b>PA2784</b>
FM330 w/6M60-3AT1 (7.5L) Eng. (2010-11) <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME306306)..... <b>PF7982 +</b> <b>Radial Seal Air</b> (ME413506)..... <b>RS3731</b> <b>Breather</b> (ME302763)..... <b>CV15011</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	FM517HR w/6D16 Eng. <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME015254)..... <b>BF720</b> <b>O. Air</b> (ME033717)..... <b>PA2761</b> <b>I. Air</b> (ME033773)..... <b>PA3417</b>	FM557 w/6D16 Eng. (Australia) <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME015254)..... <b>BF720</b> <b>O. Air</b> (ME033717)..... <b>PA2761</b> <b>I. Air</b> (ME033773)..... <b>PA3417</b>
FM330 w/6M60-3AT1 (7.5L) Eng. (2010-11) <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME306306)..... <b>PF7982 +</b> <b>Radial Seal Air</b> (ME413506)..... <b>RS3731</b> <b>Breather</b> (ME302763)..... <b>CV15011</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	FM517HR w/6D16 Eng. <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME015254)..... <b>BF720</b> <b>O. Air</b> (ME033717)..... <b>PA2761</b> <b>I. Air</b> (ME033773)..... <b>PA3417</b>	FM557 w/6D16 Eng. (1989-95) (Australia) <b>Fuel</b> (ME015254)..... <b>BF720</b> <b>O. Air</b> (ME033717)..... <b>PA2761</b> <b>I. Air</b> (ME033773)..... <b>PA3417</b> <b>O. Air</b> (ME073252)..... <b>PA3906</b> <b>I. Air</b> (ME073385)..... <b>PA5412</b>
FM330 w/6M60-3AT1 (7.5L) Eng. (2010-11) <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME306306)..... <b>PF7982 +</b> <b>Radial Seal Air</b> (ME413506)..... <b>RS3731</b> <b>Breather</b> (ME302763)..... <b>CV15011</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	FM517HR w/6D16 Eng. <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME015254)..... <b>BF720</b> <b>O. Air</b> (ME033717)..... <b>PA2761</b> <b>I. Air</b> (ME033773)..... <b>PA3417</b>	FM-HR w/6D16-2AT3 (7.5L) Eng. (1996-99) (USA) <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME056670)..... <b>BF7993</b> <b>Radial Seal Air</b> (ME073821)..... <b>RS3731</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MITSUBISHI FUSO Trucks (cont'd)	MITSUBISHI FUSO Trucks (cont'd)	MITSUBISHI FUSO Trucks (cont'd)
FM-HR w6D16-2AT3 (7.5L) Eng. (1996-99) (USA) (Cont'd) Trans. Spin-on (Allison 29510922)..... <b>BT8316-MPG</b>	FM-MR w/6D16-3AT3 (7.5L) Eng. (2000-04) (USA) (Cont'd) Trans. Spin-on (Allison 29510922)..... <b>BT8316-MPG</b>	FM-SP w/6D16-2AT3 (7.5L) Eng. (1998) (USA) <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME056670)..... <b>BF7993</b> <b>Radial Seal Air</b> (ME073821)..... <b>RS3731</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b>
FM-HR w6D16-2AT4 (7.5L) Eng. (1996-98) (USA) <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME056670)..... <b>BF7993</b> <b>Radial Seal Air</b> (ME073821)..... <b>RS3731</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b>	FM618 w/6D17 Eng. (1995-on) <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME015254)..... <b>BF720</b> <b>Radial Seal O. Air</b> (Single Cab) (AW347463)..... <b>RS3731</b> <b>Radial Seal I. Air</b> (Single Cab) (ME291563)..... <b>RS3732</b> <b>O. Air</b> (Crew Cab) (ME033717)..... <b>PA2761</b> <b>I. Air</b> (Crew Cab) (ME033773)..... <b>PA3417</b>	FM-SP w/6D16-3AT2 (7.5L) Eng. (2000-04) (USA) <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME056670)..... <b>BF7993</b> <b>Radial Seal Air</b> (ME073821)..... <b>RS3731</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b>
FM-HR w6D16-3AT3 (7.5L) Eng. (2000-03) (USA) <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME056670)..... <b>BF7993</b> <b>Radial Seal Air</b> (ME073821)..... <b>RS3731</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b>	FM618HA w/6D17 Eng. <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME015254)..... <b>BF720</b> <b>Radial Seal O. Air</b> (ME073160)..... <b>RS3731</b> <b>Radial Seal I. Air</b> (ME291563)..... <b>RS3732</b>	FM-SR w/6D16-2AT3 (7.5L) Eng. (1996-99) (USA) <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME056670)..... <b>BF7993</b> <b>Radial Seal Air</b> (ME073821)..... <b>RS3731</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b>
FM-MR w/6D16-2AT3 (7.5L) Eng. (1996-99) (USA) <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME056670)..... <b>BF7993</b> <b>Radial Seal Air</b> (ME073821)..... <b>RS3731</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b>	FM618LA w/6D17 Eng. <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME015254)..... <b>BF720</b> <b>Radial Seal O. Air</b> (ME073160)..... <b>RS3731</b> <b>Radial Seal I. Air</b> (ME291563)..... <b>RS3732</b>	FM-SR w/6D16-3AT3 (7.5L) Eng. (2000-04) (USA) <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME056670)..... <b>BF7993</b> <b>Radial Seal Air</b> (ME073821)..... <b>RS3731</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b>
FM-MR w/6D16-2AT4 (7.5L) Eng. (1996-99) (USA) <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME056670)..... <b>BF7993</b> <b>Radial Seal Air</b> (ME073821)..... <b>RS3731</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b>	FM618MA w/6D17 Eng. <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME015254)..... <b>BF720</b> <b>Radial Seal O. Air</b> (ME073160)..... <b>RS3731</b> <b>Radial Seal I. Air</b> (ME291563)..... <b>RS3732</b>	FM-SR w/6D16-2AT3 (7.5L) Eng. (1996-99) (USA) <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME056670)..... <b>BF7993</b> <b>Radial Seal Air</b> (ME073821)..... <b>RS3731</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b>
FM-MR w/6D16-2AT3 (7.5L) Eng. (1996-99) (USA) <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME056670)..... <b>BF7993</b> <b>Radial Seal Air</b> (ME073821)..... <b>RS3731</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b>	FM618MW w/6D17 Eng. <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME015254)..... <b>BF720</b> <b>O. Air</b> (ME033717)..... <b>PA2761</b> <b>I. Air</b> (ME033773)..... <b>PA3417</b>	FM-SR w/6D16-3AT3 (7.5L) Eng. (2000-04) (USA) <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME056670)..... <b>BF7993</b> <b>Radial Seal Air</b> (ME073821)..... <b>RS3731</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b>
FM-MR w/6D16-2AT4 (7.5L) Eng. (1996-99) (USA) <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME056670)..... <b>BF7993</b> <b>Radial Seal Air</b> (ME073821)..... <b>RS3731</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b>	FM657 w/6D16 Eng. (1995-on) (Australia) <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME015254)..... <b>BF720</b> <b>Fuel</b> (ME056670)..... <b>BF7993</b> <b>Radial Seal O. Air</b> (Single Cab) (AW347463)..... <b>RS3731</b> <b>Radial Seal I. Air</b> (Single Cab) (ME291563)..... <b>RS3732</b> <b>O. Air</b> (Crew Cab) (ME033717)..... <b>PA2761</b> <b>I. Air</b> (Crew Cab) (ME033773)..... <b>PA3417</b>	FM657HS w/6D16 Eng. <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME015254)..... <b>BF720</b> <b>Radial Seal O. Air</b> (ME073821)..... <b>RS3731</b> <b>Radial Seal I. Air</b> (ME291563)..... <b>RS3732</b>
FM-MR w/6D16-3AT3 (7.5L) Eng. (2000-04) (USA) <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME056670)..... <b>BF7993</b> <b>Radial Seal Air</b> (ME073821)..... <b>RS3731</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b>	FM-SP w/6D16-2AT2 (7.5L) Eng. (1996-99) (USA) <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME056670)..... <b>BF7993</b> <b>Radial Seal Air</b> (ME073821)..... <b>RS3731</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b>	FM657LS w/6D16 Eng. <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME015254)..... <b>BF720</b> <b>Radial Seal O. Air</b> (ME073821)..... <b>RS3731</b> <b>Radial Seal I. Air</b> (ME291563)..... <b>RS3732</b>
FM-MR w/6D16-3AT3 (7.5L) Eng. (2000-04) (USA) <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME056670)..... <b>BF7993</b> <b>Radial Seal Air</b> (ME073821)..... <b>RS3731</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>	FM657MS w/6D16 Eng. <b>Dual-Flow Lube</b> (ME130968)..... <b>BD1403</b> <b>Fuel</b> (ME015254)..... <b>BF720</b> <b>Radial Seal O. Air</b> (ME073821)..... <b>RS3731</b> <b>Radial Seal I. Air</b> (ME291563)..... <b>RS3732</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

MITSUBISHI FUSO Trucks (cont'd)	MITSUBISHI FUSO Trucks (cont'd)	MITSUBISHI FUSO Trucks (cont'd)
FM657PS w/6D16 Eng. Dual-Flow Lube (ME130968)..... <b>BD1403</b> Fuel (ME015254)..... <b>BF720</b> Radial Seal O. Air (ME073821)... <b>RS3731</b> Radial Seal I. Air (ME291563)..... <b>RS3732</b>	FN63FU w/6M60 Eng. Dual-Flow Lube (ME130968)..... <b>BD1403</b> Fuel (ME131824)..... <b>BF798</b> Fuel (ME300361)..... <b>PF9890</b> Radial Seal O. Air (ME073821)... <b>RS3731</b> Radial Seal I. Air (ME291563)..... <b>RS3732</b>	FP418FR w/6D22 Eng. Lube (ME121789)..... <b>P7000 KIT</b> Fuel (ME056670)..... <b>[2] BF7993</b> O. Air (AE063150)..... <b>LL1885 +</b> I. Air (AE063155)..... <b>PA1893</b>
FM658 w/6D17 Eng. (1995-on) Fuel (ME015254)..... <b>BF720</b> Radial Seal O. Air (AW347463)... <b>RS3731</b> Radial Seal I. Air (ME291563)..... <b>RS3732</b>	FN64FU w/6M60 Eng. Dual-Flow Lube (ME130968)..... <b>BD1403</b> Fuel (ME131824)..... <b>BF798</b> Fuel (ME300361)..... <b>PF9890</b> Radial Seal O. Air (ME073821)... <b>RS3731</b> Radial Seal I. Air (ME291563)..... <b>RS3732</b>	FP418NR w/6D22 Eng. Lube (ME121789)..... <b>P7000 KIT</b> Fuel (ME056670)..... <b>[2] BF7993</b> O. Air (AE063150)..... <b>LL1885 +</b> I. Air (AE063155)..... <b>PA1893</b>
FM658HR w/6D17 Eng. Dual-Flow Lube (ME130968)..... <b>BD1403</b> Fuel (ME015254)..... <b>BF720</b> Radial Seal O. Air (ME073160)... <b>RS3731</b> Radial Seal I. Air (ME291563)..... <b>RS3732</b>	FN527 Lube (ME034611)..... <b>P249</b> Fuel (ME015254)..... <b>BF720</b>	FP418NS w/6D22 Eng. Lube (ME121789)..... <b>P7000 KIT</b> Fuel (ME056670)..... <b>[2] BF7993</b> O. Air (AE063150)..... <b>LL1885 +</b> I. Air (AE063155)..... <b>PA1893</b>
FM658LR w/6D17 Eng. Dual-Flow Lube (ME130968)..... <b>BD1403</b> Fuel (ME015254)..... <b>BF720</b> Radial Seal O. Air (ME073160)... <b>RS3731</b> Radial Seal I. Air (ME291563)..... <b>RS3732</b>	FN600 (09/02-on) Dual-Flow Lube (ME130968)..... <b>BD1403</b> P. Fuel (ME300361)..... <b>PF9890</b> S. Fuel (ME131824)..... <b>BF798</b> Radial Seal O. Air (ME073821)... <b>RS3731</b> Radial Seal I. Air (ME291563)..... <b>RS3732</b>	FP418RS w/6D22 Eng. Lube (ME121789)..... <b>P7000 KIT</b> Fuel (ME056670)..... <b>[2] BF7993</b> O. Air (AE063150)..... <b>LL1885 +</b> I. Air (AE063155)..... <b>PA1893</b>
FM658MR w/6D17 Eng. Dual-Flow Lube (ME130968)..... <b>BD1403</b> Fuel (ME015254)..... <b>BF720</b> Radial Seal O. Air (ME073160)... <b>RS3731</b> Radial Seal I. Air (ME291563)..... <b>RS3732</b>	FN627 Dual-Flow Lube (ME130968)..... <b>BD1403</b> Fuel (ME131989)..... <b>BF798</b>	FP547 w/6D24 Eng. (11/99-on) Lube (ME064356)..... <b>P7000 KIT</b>
FM658PR w/6D17 Eng. Dual-Flow Lube (ME130968)..... <b>BD1403</b> Fuel (ME015254)..... <b>BF720</b> Radial Seal O. Air (ME073160)... <b>RS3731</b> Radial Seal I. Air (ME291563)..... <b>RS3732</b>	FP Series w/6D22-1AT2 Eng. Fuel (ME056280)..... <b>BF798</b>	FP547GR w/6D24 Eng. Lube (ME180514)..... <b>P7000 KIT</b>
FM677 w/6D16 Eng. (1998) Fuel (ME015254)..... <b>BF720</b> Radial Seal O. Air (AW347464)... <b>RS3731</b> Radial Seal I. Air (ME291563)..... <b>RS3732</b>	FP54J Lube (ME180514)..... <b>P7000 KIT</b> P. Fuel (ME300647)..... <b>PF9897</b>	FQ112 w/8DC4 Eng. (1976-3/80) Lube (ME064356)..... <b>P7000 KIT</b> Fuel (31162-09012)..... <b>PF7592</b>
FM677MS w/6D16 Eng. Dual-Flow Lube (ME130968)..... <b>BD1403</b> Fuel (ME015254)..... <b>BF720</b> Radial Seal O. Air (ME073821)... <b>RS3731</b> Radial Seal I. Air (ME291563)..... <b>RS3732</b>	FP54JG w/6D24 Eng. Lube (ME180514)..... <b>P7000 KIT</b> Fuel (ME300647)..... <b>PF9897</b>	FR Series Fuel (ME056280)..... <b>BF798</b>
FM677PS w/6D16 Eng. Dual-Flow Lube (ME130968)..... <b>BD1403</b> Fuel (ME015254)..... <b>BF720</b> Radial Seal O. Air (ME073821)... <b>RS3731</b> Radial Seal I. Air (ME291563)..... <b>RS3732</b>	FP103 w/8DC6 Eng. Lube (ME064356)..... <b>P7000 KIT</b>	FS Series w/6D22-1AT2 Eng. Fuel (ME056280)..... <b>BF798</b>
FN61FU w/6M60 Eng. Dual-Flow Lube (ME130968)..... <b>BD1403</b> Fuel (ME131824)..... <b>BF798</b> Fuel (ME300361)..... <b>PF9890</b> Radial Seal O. Air (ME073821)... <b>RS3731</b> Radial Seal I. Air (ME291563)..... <b>RS3732</b>	FP113 w/8DC8 Eng. Lube (ME064356)..... <b>P7000 KIT</b> 136.5 mm Fuel (MC763227)..... <b>PF7592</b>	FS52J Lube (ME180514)..... <b>P7000 KIT</b> P. Fuel (ME300647)..... <b>PF9897</b>
FN62FK w/6M60 Eng. Dual-Flow Lube (ME130968)..... <b>BD1403</b> Fuel (ME131824)..... <b>BF798</b> Fuel (ME300361)..... <b>PF9890</b> Radial Seal O. Air (ME073821)... <b>RS3731</b> Radial Seal I. Air (ME291563)..... <b>RS3732</b>	FP214 w/10DC8 Eng. (1976-3/80) Lube (ME064356)..... <b>P7000 KIT</b> Fuel (ME971552)..... <b>PF7592</b>	FS52JS w/6M70 Eng. Lube (ME180514)..... <b>P7000 KIT</b> Fuel (ME300647)..... <b>PF9897</b>
	FP215 w/8DC9 Eng. (1980-9/83) Lube (ME064356)..... <b>P7000 KIT</b> Fuel (ME971552)..... <b>PF7592</b>	FS427 w/6D24 Eng. (1996-98) Lube (ME064356)..... <b>P7000 KIT</b> O. Air (ME063150)..... <b>PA1885 +</b> I. Air (ME063155)..... <b>PA1893</b>
	FP417 w/6D24 Eng. (1996-98) Lube (ME064356)..... <b>P7000 KIT</b> O. Air (ME063150)..... <b>PA1885 +</b> I. Air (ME063155)..... <b>PA1893</b>	FS427SS w/6D24 Eng. Lube (ME121789)..... <b>P7000 KIT</b> O. Air (AE063150)..... <b>LL1885 +</b> I. Air (AE063155)..... <b>PA1893</b>
	FP418 w/6D22 Eng. (1985-96) Lube (ME064356)..... <b>P7000 KIT</b> Fuel (ME056670)..... <b>[2] BF7993</b> O. Air (AE063150)..... <b>LL1885 +</b> I. Air (ME063155)..... <b>PA1893</b> Coolant (ME065322)..... <b>BW5072</b>	FS428 w/6D22 Eng. (1987-96) Lube (ME064356)..... <b>P7000 KIT</b> Fuel (ME056670)..... <b>[2] BF7993</b> O. Air (ME063150)..... <b>PA1885 +</b> I. Air (ME063155)..... <b>PA1893</b> Coolant (ME065322)..... <b>BW5072</b>
		FS428SS w/6D22 Eng. Lube (ME121789)..... <b>P7000 KIT</b> Fuel (ME056670)..... <b>[2] BF7993</b> O. Air (AE063150)..... <b>LL1885 +</b> I. Air (AE063155)..... <b>PA1893</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



MITSUBISHI FUSO Trucks (cont'd)	MITSUBISHI FUSO Trucks (cont'd)	MITSUBISHI FUSO Trucks (cont'd)
FS527 6D24 Eng. (1998) Lube (ME064356)..... P7000 KIT	FV417JS w/6D24 Eng. Lube (ME121789)..... P7000 KIT O. Air (AE063150)..... LL1885 + I. Air (AE063155)..... PA1893	K-FK116, K-MK116 w/6D15 Eng. Lube (ME034481)..... P7021
FS527S w/6D24 Eng. Lube (ME180514)..... P7000 KIT	FV417TS w/6D24 Eng. Lube (ME121789)..... P7000 KIT O. Air (AE063150)..... LL1885 + I. Air (AE063155)..... PA1893	K-FK215 w/6D14 Eng. Lube (ME034481)..... P7021
FV Series w/6D22-1ATO Eng. Fuel (ME056280)..... BF798	FV418 w/6D22 Eng. (1987-96) Lube (ME064356)..... P7000 KIT Fuel (ME056670)..... [2] BF7993 O. Air (ME063150)..... PA1885 + I. Air (ME063155)..... PA1893 Coolant (ME065322)..... BW5072	K-FK216 w/6D15 Eng. Lube (ME034481)..... P7021
FV51J Lube (ME180514)..... P7000 KIT P. Fuel (ME300647)..... PF9897	FV418JR w/6D22 Eng. Lube (ME121789)..... P7000 KIT Fuel (ME056670)..... [2] BF7993 O. Air (AE063150)..... LL1885 + I. Air (AE063155)..... PA1893	K-FM215 w/6D14 Eng. Lube (ME034481)..... P7021 Air (ME060219)..... PA1636-FN
FV51JKD w/6M70 Eng. Lube (ME180514)..... P7000 KIT Fuel (ME300647)..... PF9897	FV418KR w/6D22 Eng. Lube (ME121789)..... P7000 KIT Fuel (ME056670)..... [2] BF7993 O. Air (AE063150)..... LL1885 + I. Air (AE063155)..... PA1893	K-FM315, K-FM316 w/6D14T, 6D15 Eng. Lube (ME034481)..... P7021 Air (ME060219)..... PA1636-FN
FV51JKM w/6M70 Eng. Lube (ME180514)..... P7000 KIT Fuel (ME300647)..... PF9897	FV418KS w/6D22 Eng. Lube (ME121789)..... P7000 KIT Fuel (ME056670)..... [2] BF7993 O. Air (AE063150)..... LL1885 + I. Air (AE063155)..... PA1893	K-FP313, K-FP313DR, K-FS313, K-FU313, K-FBV313 w/6D22, 6D22T, 8DC8, 8DC9 Eng. Lube (ME064356)..... P7000 KIT Fuel (ME971552)..... PF7592
FV54J Lube (ME180514)..... P7000 KIT P. Fuel (ME300647)..... PF9897	FV418TS w/6D22 Eng. Lube (ME121789)..... P7000 KIT Fuel (ME056670)..... [2] BF7993 O. Air (AE063150)..... LL1885 + I. Air (AE063155)..... PA1893	K-FP315, K-FP315DR, K-FU315, K-FV315 w/6D22, 6D22T, 8DC8, 8DC9 Eng. Lube (ME064356)..... P7000 KIT Fuel (ME971552)..... PF7592
FV54JL w/6M70 Eng. Lube (ME180514)..... P7000 KIT Fuel (ME300647)..... PF9897	FV458 w/6D22 Eng. (1984-95) Lube (ME064356)..... P7000 KIT Fuel (ME056670)..... [2] BF7993 O. Air (ME063150)..... PA1885 + I. Air (ME063155)..... PA1893 Coolant (ME065322)..... BW5072	K-FP318, K-FU318 w/6D22, 6D22T, 8DC8, 8DC9 Eng. Lube (ME064356)..... P7000 KIT Fuel (ME971552)..... PF7592
FV54JT w/6M70 Eng. Lube (ME180514)..... P7000 KIT Fuel (ME300647)..... PF9897	FV458KR w/6D22 Eng. Lube (ME121789)..... P7000 KIT Fuel (ME056670)..... [2] BF7993 O. Air (AE063150)..... LL1885 + I. Air (AE063155)..... PA1893	K-FU353, K-FU358 w/6D22, 6D22T, 8DC8, 8DC9 Eng. Lube (ME064356)..... P7000 KIT Fuel (ME971552)..... PF7592
FV103 w/8DC6 Eng. Lube (ME064356)..... P7000 KIT	FV517K w/6D24 Eng. (11/99-on) Lube (ME064356)..... P7000 KIT	K-FW123M w/8DC9 Eng. Lube (ME064356)..... P7000 KIT Fuel (31162-09012)..... PF7592
FV113 w/8DC8 Eng. (1976) Lube (ME064356)..... P7000 KIT Fuel (MC763227)..... PF7592	FV517KD w/6D24 Eng. Lube (ME121789)..... P7000 KIT	K-MM116, K-MM516 w/6D15 Eng. Lube (ME034481)..... P7021 Air (31130-02300)..... PA1636-FN
FV315H w/8DC9-0A Eng. (1982-84) Lube (ME064356)..... P7000 KIT Fuel (ME971552)..... PF7592 O. Air (ME063150)..... PA1885 + I. Air (ME063155)..... PA1893	FV517KM w/6D24 Eng. Lube (ME121789)..... P7000 KIT	K-MP107 w/6D15 Eng. Lube (ME034481)..... P7021 Air (31130-02300)..... PA1636-FN
FV358 6D22 Eng. (1983-84) (Australia) Lube (ME064356)..... P7000 KIT Fuel (ME971550)..... PF7592 O. Air (ME063150)..... PA1885 + I. Air (ME063155)..... PA1893	FV547 w/6D24 Eng. Lube (ME180514)..... P7000 KIT	K-MP107 w/6D21 Eng. (3/79-84) Lube (ME064356)..... P7000 KIT Air (1/82-84) (30930-35100)..... PA1750-FN
FV358J w/6D22 Eng. (USA) Lube (ME064356)..... P7000 KIT Fuel (ME971552)..... PF7592 O. Air..... PA1885 + I. Air..... PA1893		K-MP118, K-MP518 w/6D22 Eng. Lube (ME064356)..... P7000 KIT Fuel Ele. (ME971552)..... PF7592 Air (31930-35100)..... PA1646-FN
FV415 w/8DC9 Eng. (1984-92) Lube (ME064356)..... P7000 KIT Fuel (ME056670)..... [2] BF7993 O. Air (ME063150)..... PA1885 + I. Air (ME063155)..... PA1893 Coolant (ME065322)..... BW5072		K-MS613, K-MS615, K-MS713 w/8DC8, 8DC9 Eng. Lube (ME064356)..... P7000 KIT Fuel Ele. (ME971552)..... PF7592 Air (31230-60600)..... PA1637-FN
FV417 w/6D24 Eng. (1996-98) Lube (ME064356)..... P7000 KIT O. Air (ME063150)..... PA1885 + I. Air (ME063155)..... PA1893		K-NW413 w/8DC8 Eng. Lube (ME064356)..... P7000 KIT Fuel Ele. (ME971552)..... PF7592

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).




NEOPLAN Buses	NEW FLYER Buses (cont'd)	NEW FLYER Buses (cont'd)
Jetliner w/M.A.N. D2066 LUH Eng. <b>Lube Ele.</b> (51055040122)..... <b>P7329</b> <b>Fuel/Water Separator</b> (w/o Heater) (81125030086)..... <b>BF7912</b> <b>Fuel Ele.</b> (51125030061)..... <b>PF7935</b> <b>Fuel Pre-filter</b> (51125030062)..... <b>PF7939</b> <b>Fuel Ele.</b> (Preheater) (81125030039)..... <b>PF7833</b> <b>Radial Seal I. Air</b> (81084050027). <b>RS5549</b> <b>Radial Seal I. Air</b> (81084050028). <b>RS30306</b> <b>Cab Air</b> (Charcoal) (81619100019)..... <b>PA5477</b> <b>Cab Air</b> (81619100029)..... <b>PA4955</b> <b>Air Dryer</b> (81521020008)..... <b>BA5374 +</b> <b>Trans.</b> (81332150002)..... <b>PT8385</b> <b>Steering</b> (81473016005)..... <b>P106-HD</b> <b>Return Hyd.</b> (81066680006)..... <b>PT9237</b>	D30LF w/Detroit Diesel Series 50 (8.5L) Eng. <b>Lube</b> (23530573)..... <b>[2] B495</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b> <b>Coolant</b> (23516489)..... <b>BW5200</b> D35 w/Detroit Diesel Series 50 (8.5L) Eng. <b>Lube</b> (23530573)..... <b>[2] B495</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b> <b>Coolant</b> (23516489)..... <b>BW5200</b> D35LF w/Detroit Diesel Series 50 (8.5L) Eng. <b>Lube</b> (23530573)..... <b>[2] B495</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b> <b>Coolant</b> (23516489)..... <b>BW5200</b> D40 w/Detroit Diesel Series 50 (8.5L) Eng. <b>Lube</b> (23530573)..... <b>[2] B495</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b> <b>Coolant</b> (23516489)..... <b>BW5200</b> D40LF w/Cummins ISL Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel</b> (Fleetguard FF5488)..... <b>BF7815</b> D40LF w/Detroit Diesel Series 50 (8.5L) Eng. <b>Lube</b> (23530573)..... <b>[2] B495</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b> <b>Coolant</b> (23516489)..... <b>BW5200</b> D45HF w/Detroit Diesel Series 50 (8.5L) Eng. <b>Lube</b> (23530573)..... <b>[2] B495</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b> <b>Coolant</b> (23516489)..... <b>BW5200</b> D60 w/Detroit Diesel Series 50 (8.5L) Eng. <b>Lube</b> (23530573)..... <b>[2] B495</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b> <b>Coolant</b> (23516489)..... <b>BW5200</b> D60LF w/Detroit Diesel Series 50 (8.5L) Eng. <b>Lube</b> (23530573)..... <b>[2] B495</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b> <b>Coolant</b> (23516489)..... <b>BW5200</b> L35LF w/Detroit Diesel Series 50 (8.5L) Eng. <b>Lube</b> (23530573)..... <b>[2] B495</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b> <b>Coolant</b> (23516489)..... <b>BW5200</b> L40 w/Detroit Diesel Series 50 (8.5L) Eng. <b>Lube</b> (23530573)..... <b>[2] B495</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b> <b>Coolant</b> (23516489)..... <b>BW5200</b>	Xcelsior w/Cummins ISB 6.7 (6.7L) Eng. (2018) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636).... <b>CV15010</b> Xcelsior w/Cummins ISB 6.7 (6.7L) Eng. (2019) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636).... <b>CV15010</b> Xcelsior w/Cummins ISB6.7 (6.7L) Eng. (2020) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636).... <b>CV15010</b> Xcelsior w/Cummins ISB 6.7 (6.7L) Eng. (2021) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636).... <b>CV15010</b> Xcelsior w/Cummins ISB 6.7 (6.7L) Eng. (2022) <b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b> Xcelsior w/Cummins ISL 8.9 (8.9L) Eng. (2018) <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> Xcelsior w/Cummins ISL 8.9 (8.9L) Eng. (2019) <b>Lube</b> (3401544)..... <b>B40142</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> Xcelsior w/Cummins ISL 8.9 (8.9L) Eng. (2020) <b>Lube</b> (5444774)..... <b>B40142</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> Xcelsior w/Cummins ISL 8.9 (8.9L) Eng. (2021) <b>Lube</b> (5444774)..... <b>B40142</b> Xcelsior w/Cummins ISL 8.9 (8.9L) Eng. (2022) <b>Lube</b> (5444774)..... <b>B40142</b> <b>Fuel</b> (5660774)..... <b>BF63000</b> Xcelsior w/Cummins ISL-G (8.9L) Eng. (2018) <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel/Water Separator</b> (Fleetguard NG5900)..... <b>BF7695</b> Xcelsior w/Cummins ISL-G (8.9L) Eng. (2019) <b>Lube</b> (Fleetguard LF9009)..... <b>B40142</b> <b>Fuel/Water Separator</b> (Fleetguard NG5900)..... <b>BF7695</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b> Xcelsior w/Cummins ISL-G (8.9L) Eng. (2020) <b>Lube</b> (Fleetguard LF9009)..... <b>B40142</b> <b>Fuel</b> (Fleetguard NG5900)..... <b>BF7695</b> Xcelsior w/Cummins ISL-G (8.9L) Eng. (2022) <b>Lube</b> (5444774)..... <b>B40142</b> <b>Fuel/Water Separator</b> (3607140). <b>BF7695</b>
<b>NEW FLYER Buses</b>		
C40 w/Detroit Diesel Series 50 (8.5L) Eng. <b>Lube</b> (23530573)..... <b>[2] B495</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b> <b>Coolant</b> (23516489)..... <b>BW5200</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

NISSAN Buses	NISSAN Engines (cont'd)	NISSAN European Light Duty Vehicles (cont'd)
Civilian w/TD42T Eng. F-F Lube (15208-05D00)..... B7022 B-P Lube (15209-05D60)..... PT8335 Fuel (16403-05D00)..... BF7614 Air (16546-01D20)..... PA2712	NE6TA (7.4L) F-F Lube (15201-Z9007)..... B605 B-P Lube (15201-Z9008)..... B7018 Fuel Spin-on (16444-99525)..... BF970 + Fuel Spin-on (BF40399013)..... BF984	Atleon 56.13 w/BD30 TI/TI E Eng. (07/04-10/06) Fuel (164037F40A)..... BF9904
RB30 w/PE6 Eng. Lube (15274-EP128)..... P7107 Fuel (16444-EP025)..... PF7554 O. Air (16546-97015)..... LL1884 + I. Air (16546-96010)..... PA1911	PE6, PE6T Lube (15274-99027)..... PT8335 Lube (15274-99087)..... P7059	Atleon 56.15 w/ZD30 Eng. (11/06-on) Lube (1520900QAC)..... P7365 Fuel (164037F40A)..... BF9904 Air (16546MA70A)..... RS5670
RB31 w/PE6 Eng. Fuel/Water Separator (16444-EP027)..... PF7618 Fuel (16444-EP025)..... PF7554 I. Air (16546-96014)..... PA1893	TD42T (4.2L) Lube (15208-05D00)..... [2] B7022 Fuel (16403-05D00)..... BF7614	Atleon 70.14 w/Cummins ISB4-4L Eng. (11/06-on) Lube (15208-LA40A)..... BT7237 Fuel (16400LA40A)..... BF7813
TFA21 Fuel/Water Separator (16444-EP027)..... PF7618 Fuel (16444-EP025)..... PF7554	<b>NISSAN European Light Duty Vehicles</b> Atleon 12.024 w/BD30 TI/TI E Eng. (07/04-10/06) Fuel (164037F40A)..... BF9904	Atleon 75.19 w/Cummins ISB4-4L Eng. (11/06-on) Lube (15208-LA40A)..... BT7237 Fuel (16400LA40A)..... BF7813
TZA520 Fuel/Water Separator (16444-EP027)..... PF7618	Atleon 12.056 w/BD30 TI/TI E Eng. (07/04-10/06) Fuel (164037F40A)..... BF9904	Atleon 80.14 w/B4-40 TI Eng. (07/04-10/06) Lube (15208-Y9701)..... BT216 + Fuel (1640359E00)..... BF7532 Radial Seal Air (16546-D6200).... RS3922
<b>NISSAN Engines</b>	Atleon 12.35H w/BD30 TI/TI E Eng. (07/04-10/06) Fuel (164037F40A)..... BF9904	Atleon 80.14 w/Cummins ISB4-4L Eng. (11/06-on) Lube (15208LA40A)..... BT7237 Fuel (16400LA40A)..... BF7813
FD35T (3.5L) Lube (15209-01D20)..... BT365 Fuel (16403-Z9003)..... BF13	Atleon 14.080 w/B4-40 TI Eng. (07/04-10/06) Lube (15208-Y9701)..... BT216 + Fuel (1640359E00)..... BF7532 Radial Seal Air (16546-D6200).... RS3922	Atleon 80.19 w/Cummins ISB4-4L Eng. (11/06-on) Fuel (16400LA40A)..... BF7813
FE6, FE6T (6.9L) Lube (15208-Z9006)..... B45 Fuel (16403-Z9003)..... BF13	Atleon 16.095 w/B6-60 TIL Eng. (07/04-10/06) Lube (15209T9005)..... B236 + Fuel (164037F40A)..... BF9904 Air (16546-D9200)..... PA2474	Atleon 95.16 w/B6-60 TIL Eng. (07/04-10/06) Lube (15209T9005)..... B236 + Fuel (164037F40A)..... BF9904 Air (16546-D9200)..... PA2474
FE6TA (6.9L) F-F Lube (15201-Z9007)..... B605 B-P Lube (15201-Z9008)..... B7018 Dual-Flow Lube (15201-Z9009).... BD1403 Fuel Spin-on (16444-99525)..... BF970 +	Atleon 16.120 w/B6-60 TIL Eng. (07/04-10/06) Lube (15209T9005)..... B236 + Fuel (164037F40A)..... BF9904 Air (16546-D9200)..... PA2474	Atleon 95.19 w/Cummins ISB4-4L Eng. (11/06-on) Fuel (16400LA40A)..... BF7813
MD-175 (4.7L) Turbo Diesel Dual-Flow Lube..... BD7105 Fuel/Water Separator (Open End for Bowl) (RK444Z5002)..... BF1360-O Fuel/Water Separator (w/o Sensor Port) (RK444Z5002)..... BF1360 Fuel/Water Separator (w/Sensor Port) (RK444Z5002)..... BF1360-SP	Atleon 16.130 w/B6-60 TIL Eng. (07/04-10/06) Lube (15209T9005)..... B236 + Fuel (164037F40A)..... BF9904 Air (16546-D9200)..... PA2474	Atleon 95.22 w/Cummins ISB4-6L Eng. (11/06-on) Fuel (16400LA40A)..... BF7813 Radial Seal Air (16546LA40A).... RS5441
MD-230 (7.68L) Turbo Diesel Dual-Flow Lube (BF209Z5008).... BD7325 Fuel/Water Separator (Open End for Bowl) (RK444Z5002)..... BF1360-O Fuel/Water Separator (w/o Sensor Port) (RK444Z5002)..... BF1360 Fuel/Water Separator (w/Sensor Port) (RK444Z5002)..... BF1360-SP	Atleon 35.13 w/BD30 TI/TI E Eng. (07/04-10/06) Fuel (164037F40A)..... BF9904	Atleon 110.35 w/BD30 TI Eng. (02/00-10/06) Fuel (1640359E00)..... BF7532 Radial Seal Air (16546-D6200).... RS3922
NE6T (7.4L) Lube (15274-99189)..... BT398 Fuel Spin-on (16444-99525)..... BF970 + Fuel Spin-on (BF40399013)..... BF984	Atleon 35.15 w/ZD30 Eng. (11/06-on) Lube (1520900QAC)..... P7365 Fuel (164037F40A)..... BF9904 Air (16546MA70A)..... RS5670	Atleon 110.45 w/BD30 TI Eng. (02/00-10/06) Fuel (1640359E00)..... BF7532 Radial Seal Air (16546-D6200).... RS3922
	Atleon 35H.15 w/ZD30 Eng. (11/06-on) Lube (1520900QAC)..... P7365 Fuel (164037F40A)..... BF9904 Air (16546MA70A)..... RS5670	Atleon 110.56 w/BD30 TI Eng. (02/00-10/06) Fuel (1640359E00)..... BF7532 Radial Seal Air (16546-D6200).... RS3922
	Atleon 45.15 w/ZD30 Eng. (11/06-on) Lube (1520900QAC)..... P7365 Fuel (164037F40A)..... BF9904 Air (16546MA70A)..... RS5670	Atleon 120.035H w/BD30 TI Eng. (01/01-10/06) Fuel (1640359E00)..... BF7532 Radial Seal Air (16546-D6200).... RS3922
		Atleon 120.05 w/BD30 TI Eng. (01/01-10/06) Fuel (1640359E00)..... BF7532 Radial Seal Air (16546-D6200).... RS3922

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

NISSAN European Light Duty Vehicles (cont'd)	NISSAN European Light Duty Vehicles (cont'd)	NISSAN European Light Duty Vehicles (cont'd)
Atleon 120.056 w/BD30 TI Eng. (01/01-10/06) <b>Fuel</b> (1640359E00)..... <b>BF7532</b> <b>Radial Seal Air</b> (16546-D6200).... <b>RS3922</b>	Atleon 165.120 w/B6-60 TI Eng. (02/00-10/06) <b>Lube</b> (15209T9005)..... <b>B236 +</b> <b>Fuel</b> (1640359E00)..... <b>BF7532</b> <b>Air</b> (16546-D9200)..... <b>PA2474</b>	Cabstar E 95.32 w/TD27 EGR Eng. (03/99-10/06) <b>Fuel</b> (To 05/01) (1640359E00)..... <b>BF7532</b> <b>Fuel</b> (06/01-on) (16400BN303)..... <b>BF9904</b>
Atleon 120.22 w/Cummins ISB4-6L Eng. (11/06-on) <b>Fuel</b> (16400LA40A)..... <b>BF7813</b> <b>Radial Seal Air</b> (16546LA40A).... <b>RS5441</b>	Atleon 165.130 w/B6-60 TI Eng. (02/00-10/06) <b>Lube</b> (15209T9005)..... <b>B236 +</b> <b>Fuel</b> (1640359E00)..... <b>BF7532</b> <b>Air</b> (16546-D9200)..... <b>PA2474</b>	Cabstar E 110.35 w/BD30 TI Eng. (03/99-10/06) <b>Fuel</b> (To 05/01) (1640359E00)..... <b>BF7532</b> <b>Fuel</b> (06/01-on) (16400BN303)..... <b>BF9904</b>
Atleon 120R.25 w/Cummins ISB4-6H Eng. (11/06-on) <b>Lube</b> (15208LA40A)..... <b>BT7237</b> <b>Fuel</b> (16400LA40A)..... <b>BF7813</b> <b>Radial Seal Air</b> (16546LA40A).... <b>RS5441</b>	Atleon 165.75 w/B6-60 TI Eng. (02/00-10/06) <b>Lube</b> (15209T9005)..... <b>B236 +</b> <b>Fuel</b> (1640359E00)..... <b>BF7532</b> <b>Air</b> (16546-D9200)..... <b>PA2474</b>	Cabstar E 110.35-110.45 w/BD30 Ti Eng. (03/99-05/01) <b>Lube</b> (1520865001)..... <b>B118</b> <b>Fuel</b> (1640359E00)..... <b>BF7532</b>
Atleon 130.22 w/Cummins ISB4-6L Eng. (11/06-on) <b>Lube</b> (15208LA40A)..... <b>BT7237</b> <b>Fuel</b> (16400LA40A)..... <b>BF7813</b> <b>Radial Seal Air</b> (16546LA40A).... <b>RS5441</b>	Atleon 165.95 w/B6-60 TI Eng. (02/00-10/06) <b>Lube</b> (15209T9005)..... <b>B236 +</b> <b>Fuel</b> (1640359E00)..... <b>BF7532</b> <b>Air</b> (16546-D9200)..... <b>PA2474</b>	Cabstar E 110.35-110.45 w/BD30 Ti Eng. (06/01-on) <b>Lube</b> (1520865001)..... <b>B118</b> <b>Fuel</b> (16400BN303)..... <b>BF9904</b>
Atleon 130.25 w/Cummins ISB4-6H Eng. (11/06-on) <b>Lube</b> (15208LA40A)..... <b>BT7237</b> <b>Fuel</b> (16400LA40A)..... <b>BF7813</b> <b>Radial Seal Air</b> (16546LA40A).... <b>RS5441</b>	Atleon 210.130 w/B6-60 TI Eng. (02/00-10/06) <b>Lube</b> (15209T9005)..... <b>B236 +</b> <b>Fuel</b> (1640359E00)..... <b>BF7532</b> <b>Air</b> (16546-D9200)..... <b>PA2474</b>	Cabstar E 110.45 w/BD30 TI Eng. (03/99-10/06) <b>Fuel</b> (To 05/01) (1640359E00)..... <b>BF7532</b> <b>Fuel</b> (06/01-on) (16400BN303)..... <b>BF9904</b>
Atleon 130R.25 w/Cummins ISB4-6H Eng. (11/06-on) <b>Lube</b> (15208LA40A)..... <b>BT7237</b> <b>Fuel</b> (16400LA40A)..... <b>BF7813</b> <b>Radial Seal Air</b> (16546LA40A).... <b>RS5441</b>	Atleon 210.150 w/B6-60 TI Eng. (02/00-10/06) <b>Lube</b> (15209T9005)..... <b>B236 +</b> <b>Fuel</b> (1640359E00)..... <b>BF7532</b> <b>Air</b> (16546-D9200)..... <b>PA2474</b>	Cabstar E 120.35 w/BD30 TI Eng. (03/99-10/06) <b>Fuel</b> (To 05/01) (1640359E00)..... <b>BF7532</b> <b>Fuel</b> (06/01-on) (16400BN303)..... <b>BF9904</b>
Atleon 130R.25 w/Cummins ISB4-6H Eng. (11/06-on) <b>Lube</b> (15208LA40A)..... <b>BT7237</b> <b>Fuel</b> (16400LA40A)..... <b>BF7813</b> <b>Radial Seal Air</b> (16546LA40A).... <b>RS5441</b>	Cabstar E 75.28 w/LD23 EGR Eng. (03/99-05/01) <b>Lube</b> (15208W1106)..... <b>B120</b> <b>Fuel</b> (1640359E00)..... <b>BF7532</b>	Cabstar E 120.35-120.44-120.45 w/BD30 Ti Eng. (03/99-05/01) <b>Lube</b> (1520865001)..... <b>B118</b> <b>Fuel</b> (1640359E00)..... <b>BF7532</b>
Atleon 140.080 w/B4-40 TI Eng. (01/01-10/06) <b>Lube</b> (15208-Y9701)..... <b>BT216 +</b> <b>Fuel</b> (1640359E00)..... <b>BF7532</b> <b>Radial Seal Air</b> (16546-D6200).... <b>RS3922</b>	Cabstar E 75.28 w/LD23 EGR Eng. (03/99-10/06) <b>Lube</b> (1520829D00)..... <b>B120</b> <b>Fuel</b> (To 05/01) (1640359E00)..... <b>BF7532</b> <b>Fuel</b> (06/01-on) (16400BN303)..... <b>BF9904</b>	Cabstar E 120.35-120.44-120.45 w/BD30 Ti Eng. (06/01-on) <b>Lube</b> (1520865001)..... <b>B118</b> <b>Fuel</b> (16400BN303)..... <b>BF9904</b>
Atleon 140.75 w/B4-40 TI Eng. (01/01-10/06) <b>Lube</b> (15208-Y9701)..... <b>BT216 +</b> <b>Fuel</b> (1640359E00)..... <b>BF7532</b> <b>Radial Seal Air</b> (16546-D6200).... <b>RS3922</b>	Cabstar E 75.28 w/LD23 EGR Eng. (06/01-on) <b>Lube</b> (15208W1106)..... <b>B120</b> <b>Fuel</b> (16400BN303)..... <b>BF9904</b>	Cabstar E 120.44 w/BD30 TI Eng. (03/99-10/06) <b>Fuel</b> (To 05/01) (1640359E00)..... <b>BF7532</b> <b>Fuel</b> (06/01-on) (16400BN303)..... <b>BF9904</b>
Atleon 140.80 w/B4-40 TI Eng. (02/00-10/06) <b>Lube</b> (15208-Y9701)..... <b>BT216 +</b> <b>Fuel</b> (1640359E00)..... <b>BF7532</b> <b>Radial Seal Air</b> (16546-D6200).... <b>RS3922</b>	Cabstar E 90.32 w/TD27 EGR Eng. (03/99-10/06) <b>Fuel</b> (To 05/01) (1640359E00)..... <b>BF7532</b> <b>Fuel</b> (06/01-on) (16400BN303)..... <b>BF9904</b>	Cabstar E 120.45 w/BD30 TI Eng. (03/99-10/06) <b>Fuel</b> (To 05/01) (1640359E00)..... <b>BF7532</b> <b>Fuel</b> (06/01-on) (16400BN303)..... <b>BF9904</b>
Atleon 150.25 w/Cummins ISB4-6H Eng. (11/06-on) <b>Lube</b> (15208LA40A)..... <b>BT7237</b> <b>Fuel</b> (16400LA40A)..... <b>BF7813</b> <b>Radial Seal Air</b> (16546LA40A).... <b>RS5441</b>	Cabstar E 90.32-95.28-95.32 w/TD27 EGR Eng. (03/99-05/01) <b>Lube</b> (1520865001)..... <b>B118</b> <b>Fuel</b> (1640359E00)..... <b>BF7532</b>	Cabstar E TL 28.10 w/BD30T EGR Eng. (01/04-10/06) <b>Fuel</b> (To 05/01) (1640359E00)..... <b>BF7532</b> <b>Fuel</b> (06/01-on) (16400BN303)..... <b>BF9904</b>
Atleon 150R.25 w/Cummins ISB4-6H Eng. (11/06-on) <b>Lube</b> (15208LA40A)..... <b>BT7237</b> <b>Fuel</b> (16400LA40A)..... <b>BF7813</b> <b>Radial Seal Air</b> (16546LA40A).... <b>RS5441</b>	Cabstar E 90.32-95.28-95.32 w/TD27 EGR Eng. (06/01-on) <b>Lube</b> (1520865001)..... <b>B118</b> <b>Fuel</b> (16400BN303)..... <b>BF9904</b>	Cabstar E TL 28.10-33.10-35.10 w/BD30T EGR Eng. (01/04-on) <b>Lube</b> (1520865001)..... <b>B118</b> <b>Fuel</b> (16400BN303)..... <b>BF9904</b>
Atleon 165.095 w/B6-60 TI Eng. (01/01-10/06) <b>Lube</b> (15209T9005)..... <b>B236 +</b> <b>Fuel</b> (1640359E00)..... <b>BF7532</b> <b>Air</b> (16546-D9200)..... <b>PA2474</b>	Cabstar E 95.28 w/TD27 EGR Eng. (03/99-10/06) <b>Fuel</b> (To 05/01) (1640359E00)..... <b>BF7532</b> <b>Fuel</b> (06/01-on) (16400BN303)..... <b>BF9904</b>	Cabstar E TL 32.10 w/BD30T EGR Eng. (01/04-10/06) <b>Fuel</b> (164037F40A)..... <b>BF9904</b>
		Cabstar E TL 35.10 w/BD30T EGR Eng. (01/04-10/06) <b>Fuel</b> (164037F40A)..... <b>BF9904</b>
		Cabstar E TL 35.13 w/BD30 TI Eng. (01/04-10/06) <b>Fuel</b> (164037F40A)..... <b>BF9904</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.




**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

NISSAN European Light Duty Vehicles (cont'd)	NISSAN European Light Duty Vehicles (cont'd)	NISSAN European Light Duty Vehicles (cont'd)
Cabstar E TL 35.13-45.13 w/BD30Ti Eng. (01/04-on) Lube (1520865001)..... <b>B118</b> Fuel (16400BN303)..... <b>BF9904</b>	Interstar 1.9 DCI w/F9Q-772 Eng. (04/02-10/03) Lube (15208BN700)..... <b>B7276</b> Fuel (1640500QAC)..... <b>PF46112</b>	Navara ( D40) 2.5 DCI w/YD25DDTI Eng. (06/05-on) Lube (15208BN300)..... <b>B7431</b> Fuel (164037F40A)..... <b>BF9904</b> Air (16546EB300)..... <b>PA4793</b> Cabin Air (27274EA000)..... <b>PA4410 KIT</b>
Cabstar E TL 45.13 w/BD30 TI Eng. (01/04-10/06) Fuel (164037F40A)..... <b>BF9904</b>	Interstar 1.9 DCI 80 w/F9Q770/772/774 Eng. (04/02-02/11) Lube (8200033468)..... <b>B7276</b> Fuel (1640500QAB)..... <b>PF9801</b> <sup>90</sup>	Navara ( D40) 2.5 DCI w/YD25DDTI Eng. (10/06-03/10) Lube (15208BN300)..... <b>B7431</b> Air (16546EB300)..... <b>PA4793</b> Cabin Air (27274EA000)..... <b>PA4410 KIT</b>
Cabstar III 28.11 2.5dCi w/YD25 Eng. (10/06-on) Lube (15208BN300)..... <b>B7431</b> Air (16546MA70A)..... <b>RS5670</b>	Interstar 1.9 DCI 80 w/F9Q-774 Eng. (10/03-on) Lube (15208BN700)..... <b>B7276</b> Fuel (1640500QAC)..... <b>PF46112</b>	Navara ( D40)3.0 DCI w/231 HP Eng. (06/10-on) Air (16546EB300)..... <b>PA4793</b> Cabin Air (27274EA000)..... <b>PA4410 KIT</b>
Cabstar III 28.11 2.5dCi w/YD25 Eng. (10/06-on) Lube (15208BN300)..... <b>B7431</b> Fuel (16400BN303)..... <b>BF9904</b> Air (16546MA70A)..... <b>RS5670</b>	Interstar 2.2 DCI 90 w/G9T-720 Eng. (10/03-on) Lube (7701472321)..... <b>P7455</b> Fuel (1640500QAB)..... <b>PF9801</b> <sup>90</sup>	NP300 Pick Up 2.5 DCI w/YD25EFI Eng. (04/08-on) Lube (15208BN300)..... <b>B7431</b>
Cabstar III 28.12 2.5 dCi w/YD25K3 LD-5 Eng. (01/12-on) Lube (15208BN300)..... <b>B7431</b> Air (16546MA70A)..... <b>RS5670</b>	Interstar 2.2 DCI 90 w/G9T-722 Eng. (04/02-10/03) Lube (7701472321)..... <b>P7455</b> Fuel (1640500QAB)..... <b>PF9801</b> <sup>90</sup>	NV 200 1.5 w/110 HP Eng. (11/09-on) Lube (1520865F01)..... <b>B1400</b> Fuel (N/S)..... <b>N/S</b> Cabin Air (27891EL00A)..... <b>PA10376</b>
Cabstar III 35.12 2.5dCi w/YD25K3 LD-5 Eng. (01/12-on) Lube (15208BN300)..... <b>B7431</b> Air (16546MA70A)..... <b>RS5670</b>	Interstar 2.2 DCI 90 w/G9T-722-720-750 Eng. (04/02-02/11) Lube (1520900Q0B)..... <b>P7455</b> Fuel (1640500QAB)..... <b>PF9801</b> <sup>90</sup>	NV 200 1.5 DCI w/82 HP Eng. (04/11-on) Cabin Air (27891EL00A)..... <b>PA10376</b>
Cabstar III 35.13 2.5dCi w/YD25 Eng. (10/06-on) Lube (15208BN300)..... <b>B7431</b> Air (16546MA70A)..... <b>RS5670</b>	Interstar 2.2 DCI 100 w/G9U-650 Eng. (07/06-02/11) Lube (1520900Q0B)..... <b>P7455</b> Fuel (1640500QAB)..... <b>PF9801</b> <sup>90</sup>	NV 200 1.5 DCI w/86 HP Eng. (11/09-on) Cabin Air (27891EL00A)..... <b>PA10376</b>
Cabstar III 35.14 2.5dCi w/150 Eng. (01/12-on) Lube (15208BN300)..... <b>B7431</b> Air (16546MA70A)..... <b>RS5670</b>	Interstar 2.5 DCI w/G9U-720 Eng. (04/02-10/03) Lube (7701472321)..... <b>P7455</b> Fuel (1640500QAB)..... <b>PF9801</b> <sup>90</sup>	NV 200 1.5 DCI w/110 HP Eng. (04/11-on) Cabin Air (27891EL00A)..... <b>PA10376</b>
Cabstar III 35.15 3.0dCi w/ZD30 Eng. (10/06-on) Lube (1520900QAC)..... <b>P7365</b> Fuel (16400BN303)..... <b>BF9904</b> Air (16546MA70A)..... <b>RS5670</b>	Interstar 2.5 DCI 100 w/100 HP Eng. (07/06-on) Lube (7701472321)..... <b>P7455</b> Fuel (1640500QAC)..... <b>PF46112</b>	NV 400 2.3 DCI 100 w/M9T670/676/690/692 Eng. (10/11-on) Fuel (1640500QAB)..... <b>PF9801</b> <sup>90</sup> Fuel (1640500QAC)..... <b>PF46112</b>
Cabstar III 35.15 3.0dCi w/ZF30, ZD30H HD-5 Eng. (10/06-on) Lube (152082W200)..... <b>P7365</b> Air (16546MA70A)..... <b>RS5670</b>	Interstar 2.5 DCI 100 w/G9U-750/754 Eng. (10/03-on) Lube (7701472321)..... <b>P7455</b> Fuel (1640500QAB)..... <b>PF9801</b> <sup>90</sup>	NV 400 2.3 DCI 125 w/M9T676/686/690/692/696/698 Eng. (10/11-on) Fuel (1640500QAB)..... <b>PF9801</b> <sup>90</sup> Fuel (1640500QAC)..... <b>PF46112</b>
Cabstar III 45.13 2.5dCi w/YD25 Eng. (10/06-on) Lube (15208BN300)..... <b>B7431</b> Air (16546MA70A)..... <b>RS5670</b>	Interstar 2.5 DCI 120 w/120 HP Eng. (07/06-on) Lube (7701472321)..... <b>P7455</b> Fuel (1640500QAC)..... <b>PF46112</b>	NV 400 2.3 DCI 150 w/M9T678/680/686/694/696/698 Eng. (10/11-on) Fuel (1640500QAB)..... <b>PF9801</b> <sup>90</sup> Fuel (1640500QAC)..... <b>PF46112</b>
Cabstar III 45.15 3.0dCi w/ZD30 Eng. (10/06-on) Lube (1520900QAC)..... <b>P7365</b> Fuel (16400BN303)..... <b>BF9904</b> Air (16546MA70A)..... <b>RS5670</b>	Interstar 2.5 DCI 120 w/G9T-750 Eng. (10/03-on) Lube (7701472321)..... <b>P7455</b> Fuel (1640500QAB)..... <b>PF9801</b> <sup>90</sup>	Primestar 1.9 DCI 80 w/F9Q-762 Eng. (09/02-07/06) Fuel (1640500QAB)..... <b>PF9801</b> <sup>90</sup> Air (1654600QAE)..... <b>PA4319</b> <sup>90</sup>
Cabstar III 45.15 3.0dCi w/ZF30, ZD30H HD-5 Eng. (10/06-on) Lube (152082W200)..... <b>P7365</b> Air (16546MA70A)..... <b>RS5670</b>	Interstar 2.5 DCI 150 w/146 HP Eng. (07/06-on) Lube (7701472321)..... <b>P7455</b> Fuel (1640500QAC)..... <b>PF46112</b>	Primestar 1.9 DCI 100 w/F9Q-760 Eng. (09/02-07/06) Fuel (1640500QAB)..... <b>PF9801</b> <sup>90</sup> Air (1654600QAE)..... <b>PA4319</b> <sup>90</sup>
Cabstar III E 35.13 2.5dCi w/YD25 Eng. (10/06-on) Lube (15208BN300)..... <b>B7431</b> Fuel (16400BN303)..... <b>BF9904</b> Air (16546MA70A)..... <b>RS5670</b>	Interstar 3.0 DCI 140 w/ZD3-200/203 Eng. (01/04-on) Lube (1520900QAC)..... <b>P7365</b> Fuel (1640500QAB)..... <b>PF9801</b> <sup>90</sup>	Primestar 2.0 16V w/F4R720/722 Eng. (10/03-on) Lube (8200033468)..... <b>B7276</b>
	Navara ( D40) 2.5 DCI w/190 HP Eng. (04/10-on) Lube (15208BN300)..... <b>B7431</b> Fuel (164037F40A)..... <b>BF9904</b> Air (16546EB300)..... <b>PA4793</b> Cabin Air (27274EA000)..... <b>PA4410 KIT</b>	

<sup>90</sup> Obsolete Pending.

Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

NISSAN European Light Duty Vehicles (cont'd)	NISSAN UD Trucks (cont'd)	NISSAN UD Trucks (cont'd)
Primestar 2.0 DCI 90 w/M9R-780 Eng. (07/06-on) <b>Fuel</b> (1640500QAB)..... <b>PF9801</b> <sup>90</sup>	1300 w/TD42T (4.2L) Eng. (1992-98) <b>B-P Lube Ele.</b> (15209-05D60)..... <b>PT8335</b> <b>F-F Lube Spin-on</b> (BF208-05D02)..... <b>[2] B7047</b> <b>Fuel</b> (16403-05D00)..... <b>BF7614</b> <b>Air</b> (16546-Z9007)..... <b>PA2779</b>	1800, UD1800 w/FE6 (6.9L) Eng. (1989-91) <b>Lube</b> (15208-Z9007)..... <b>B45</b> <b>Fuel/Water Separator</b> (RK6442NIS02)..... <b>BF1273-SP</b> <b>Fuel</b> (FL403-Z9005)..... <b>BF13</b> <b>Air</b> (D6546-Z9007)..... <b>PA2504</b> <b>Coolant</b> (FL915-99003)..... <b>BW5073</b> <b>Trans.</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans.</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>
Primestar 2.0 DCI 115 w/M9R-780 Eng. (07/06-on) <b>Fuel</b> (1640500QAB)..... <b>PF9801</b> <sup>90</sup>	1300 w/MD-175 (J05D-TA) (4.7L) Eng. (2005-07) <b>Dual-Flow Lube</b> ..... <b>BD7105</b> <b>Fuel/Water Separator</b> (w/o Sensor Port) (RK444Z5002)..... <b>BF1360</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (RK444Z5002)..... <b>BF1360-SP</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (RK444Z5002)..... <b>BF1360-O</b> <b>Air</b> (D6546-Z9007)..... <b>PA2504</b>	1800, UD1800 w/FE6T (6.9L) Eng. (1989-91) <b>Lube</b> (15208-Z9007)..... <b>B45</b> <b>Fuel/Water Separator</b> (RK6442NIS02)..... <b>BF1273-SP</b> <b>Fuel</b> (FL403-Z9005)..... <b>BF13</b> <b>Air</b> (D6546-Z9007)..... <b>PA2504</b> <b>Coolant</b> (FL915-99003)..... <b>BW5073</b> <b>Trans.</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans.</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>
Primestar 2.5 DCI w/133 HP Eng. (09/02-07/06) <b>Lube</b> (1520900Q0B)..... <b>P7455</b> <b>Fuel</b> (1640500QAB)..... <b>PF9801</b> <sup>90</sup>	1400 w/TD42T (4.2L) Eng. (1994) <b>F-F Lube</b> (BF208-05D02)..... <b>[2] B7047</b> <b>B-P Lube</b> (15209-05D60)..... <b>PT8335</b> <b>Fuel</b> (16403-05D00)..... <b>BF7614</b> <b>Air</b> (16546-01D20)..... <b>PA2712</b>	1800, UD1800 w/FE6TA (6.9L) Eng. (1992-94) <b>F-F Lube</b> (FL201-Z9010)..... <b>B605</b> <b>B-P Lube</b> (FL201-Z9011)..... <b>B7018</b> <b>Fuel/Water Separator</b> (RK6442NIS02)..... <b>BF1273-SP</b> <b>Fuel</b> (BF403-99013)..... <b>BF984</b> <b>Air</b> (D6546-Z9007)..... <b>PA2504</b> <b>Coolant</b> (FL915-99003)..... <b>BW5073</b> <b>Trans.</b> (Allison MT Series) (Allison 29538489)..... <b>19739 +</b>
Primestar 2.5 DCI w/146 HP Eng. (07/06-on) <b>Fuel</b> (1640500QAB)..... <b>PF9801</b> <sup>90</sup> <b>Fuel</b> (1640500QAC)..... <b>PF46112</b>	1400 w/MD-175 (J05D-TA) (4.7L) Eng. (2005-07) <b>Dual-Flow Lube</b> ..... <b>BD7105</b> <b>Fuel/Water Separator</b> (w/o Sensor Port) (RK444Z5002)..... <b>BF1360</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (RK444Z5002)..... <b>BF1360-SP</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (RK444Z5002)..... <b>BF1360-O</b> <b>Air</b> (D6546-Z9007)..... <b>PA2504</b>	1800, UD1800 w/FE6TA (6.9L) Eng. (1992-94) <b>F-F Lube</b> (FL201-Z9010)..... <b>B605</b> <b>B-P Lube</b> (FL201-Z9011)..... <b>B7018</b> <b>Fuel/Water Separator</b> (RK6442NIS02)..... <b>BF1273-SP</b> <b>Fuel</b> (BF403-99013)..... <b>BF984</b> <b>Air</b> (D6546-Z9007)..... <b>PA2504</b> <b>Coolant</b> (FL915-99003)..... <b>BW5073</b> <b>Trans.</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans.</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>
Primestar 2.5 DCI 140 w/G9U730 Eng. (09/03-07/06) <b>Lube</b> (1520900Q0B)..... <b>P7455</b> <b>Fuel</b> (1640500QAB)..... <b>PF9801</b> <sup>90</sup> <b>Fuel</b> (1640500QAC)..... <b>PF46112</b>	1400 w/TD42T (4.2L) Eng. (1995-98) <b>F-F Lube</b> (BF208-05D02)..... <b>[2] B7047</b> <b>B-P Lube</b> (15209-05D60)..... <b>PT8335</b> <b>Fuel</b> (16403-05D00)..... <b>BF7614</b> <b>Air</b> (16546-01D20)..... <b>PA2712</b>	1800, UD1800 w/GH7 (7.0L) Eng. (2011-13) <b>Radial Seal XP Air</b> (D6546NY108)..... <b>RS30222XP</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Diesel Exhaust Fluid</b> (5282269261)..... <b>PE17001</b>
<h3 style="text-align: center;">NISSAN UD Trucks</h3> 550T w/NE6T (7.4L) Eng. (1989-91) <b>Lube</b> (15274-99189)..... <b>BT398</b> <b>Fuel/Water Separator</b> (RK6442NIS02)..... <b>BF1273-SP</b> <b>Fuel Spin-on</b> (BF403-99013)..... <b>BF984</b> <b>O. Air</b> (D6546-Z9007)..... <b>PA2504</b> <b>I. Air</b> (D6546-Z9006)..... <b>PA2545</b> <b>Coolant</b> (FL915-99003)..... <b>BW5073</b> <b>Trans.</b> (Allison MT Series) (Allison 29538489)..... <b>19739 +</b>	1400 w/WD46TA-U1 (4.6L) Eng. (2002-04) <b>Fuel/Water Separator</b> (RK6442NIS02)..... <b>BF1273-SP</b> <b>Fuel</b> (BF403-99013)..... <b>BF984</b> <b>Air</b> (D6546-Z9007)..... <b>PA2504</b>	1800CS w/J05D-TA (4.7L) Eng. (2008-10) <b>Fuel/Water Separator</b> (w/o Sensor Port) (RK444Z5002)..... <b>BF1360</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (RK444Z5002)..... <b>BF1360-SP</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (RK444Z5002)..... <b>BF1360-O</b> <b>Air</b> (BF546Z9007)..... <b>PA2779</b>
600T w/NE6TA (7.4L) Eng. (1992-94) <b>F-F Lube</b> (FL201Z-9010)..... <b>B605</b> <b>B-P Lube</b> (FL201-Z9011)..... <b>B7018</b> <b>Fuel/Water Separator</b> (RK6442NIS02)..... <b>BF1273-SP</b> <b>Fuel</b> (BF403-99013)..... <b>BF984</b> <b>O. Air</b> (D6546-Z9009)..... <b>PA2577</b> <b>I. Air</b> (D6546-Z9008)..... <b>PA2578</b> <b>Coolant</b> (FL915-99003)..... <b>BW5073</b> <b>Trans.</b> (Allison MT Series) (Allison 29538489)..... <b>19739 +</b>	1400 w/WD46TA-U2 (4.6L) Eng. (1999-2004) <b>Fuel/Water Separator</b> (RK6442NIS02)..... <b>BF1273-SP</b> <b>Fuel</b> (BF403-99013)..... <b>BF984</b> <b>Air</b> (D6546-Z9007)..... <b>PA2504</b>	1800CS w/J05D-TA (4.7L) Eng. (2008-10) <b>Fuel/Water Separator</b> (w/o Sensor Port) (RK444Z5002)..... <b>BF1360</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (RK444Z5002)..... <b>BF1360-SP</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (RK444Z5002)..... <b>BF1360-O</b> <b>Radial Seal XP Air</b> (D6546NY108)..... <b>RS30222XP</b>
1100 w/FD35T (3.5L) Eng. (1989-91) <b>Lube</b> (FL209-01D20)..... <b>BT365</b> <b>Fuel</b> (FL403-Z9005)..... <b>BF13</b> <b>Air</b> (16546-01D20)..... <b>PA2712</b> <b>Coolant</b> (FL915-99003)..... <b>BW5073</b>	1400 w/MD-175 (J05D-TA) (4.7L) Eng. (2005-07) <b>Dual-Flow Lube</b> ..... <b>BD7105</b> <b>Fuel/Water Separator</b> (w/o Sensor Port) (RK444Z5002)..... <b>BF1360</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (RK444Z5002)..... <b>BF1360-SP</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (RK444Z5002)..... <b>BF1360-O</b> <b>Air</b> (D6546-Z9007)..... <b>PA2504</b>	1800CS w/J05D-TA (4.7L) Eng. (2008-10) <b>Fuel/Water Separator</b> (w/o Sensor Port) (RK444Z5002)..... <b>BF1360</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (RK444Z5002)..... <b>BF1360-SP</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (RK444Z5002)..... <b>BF1360-O</b> <b>Radial Seal XP Air</b> (D6546NY108)..... <b>RS30222XP</b>
1200 w/FD46TA-U2 (4.6L) Eng. (1999-2004) <b>Fuel/Water Separator</b> (RK6442NIS02)..... <b>BF1273-SP</b> <b>Fuel</b> (BF403-99013)..... <b>BF984</b> <b>Air</b> (D6546-Z9007)..... <b>PA2504</b>	1400 w/J05D-TA (4.7L) Eng. (2008-10) <b>Fuel/Water Separator</b> (w/o Sensor Port) (RK444Z5002)..... <b>BF1360</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (RK444Z5002)..... <b>BF1360-SP</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (RK444Z5002)..... <b>BF1360-O</b> <b>Air</b> (BF546Z9007)..... <b>PA2779</b>	1800CS w/J05D-TA (4.7L) Eng. (2008-10) <b>Fuel/Water Separator</b> (w/o Sensor Port) (RK444Z5002)..... <b>BF1360</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (RK444Z5002)..... <b>BF1360-SP</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (RK444Z5002)..... <b>BF1360-O</b> <b>Radial Seal XP Air</b> (D6546NY108)..... <b>RS30222XP</b>
1200 w/FD46TA-U1 (4.6L) Eng. (2002-04) <b>Fuel/Water Separator</b> (RK6442NIS02)..... <b>BF1273-SP</b> <b>Fuel</b> (BF403-99013)..... <b>BF984</b> <b>Air</b> (D6546-Z9007)..... <b>PA2504</b>	1400 w/J05D-TA (4.7L) Eng. (2008-10) <b>Fuel/Water Separator</b> (w/o Sensor Port) (RK444Z5002)..... <b>BF1360</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (RK444Z5002)..... <b>BF1360-SP</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (RK444Z5002)..... <b>BF1360-O</b> <b>Air</b> (BF546Z9007)..... <b>PA2779</b>	1800CS w/J05D-TA (4.7L) Eng. (2008-10) <b>Fuel/Water Separator</b> (w/o Sensor Port) (RK444Z5002)..... <b>BF1360</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (RK444Z5002)..... <b>BF1360-SP</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (RK444Z5002)..... <b>BF1360-O</b> <b>Radial Seal XP Air</b> (D6546NY108)..... <b>RS30222XP</b>

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.

Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

NISSAN UD Trucks (cont'd)	NISSAN UD Trucks (cont'd)	NISSAN UD Trucks (cont'd)
1800CS w/J05D-TA (4.7L) Eng. (2008-10) (Cont'd) <b>Cab Air</b> (Fresh Air) (2721300Z06)..... <b>CLN&amp;R</b>	1800HD, UD1800HD w/MD-230 (J08E-TE) (7.7L) Eng. (2005-07) (Cont'd) <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	2000 w/FE6TA-U1 (6.9L) Eng. (1999-2004) (Cont'd) <b>Trans. Spin-on</b> (AT Series) (Allison 29510922)..... <b>BT8316-MPG</b>
1800CS, UD1800CS w/FD46TA-U1 (4.6L) Eng. (1999-2004) <b>Fuel/Water Separator</b> (RK6442NIS02)..... <b>BF1273-SP</b> <b>Air</b> (D6546-Z9007)..... <b>PA2504</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	2000 w/FE6TA-U2 (6.9L) Eng. (1999-2004) <b>Lube</b> (FL201Z9009)..... <b>BD1403</b> <b>Fuel/Water Separator</b> (RK6442NIS02)..... <b>BF1273-SP</b> <b>Fuel</b> (BF40399013)..... <b>BF984</b> <b>Radial Seal Air</b> (BF546Z9100)..... <b>RS3710</b> <b>Cab Air</b> (Fresh Air) (2721300Z06)..... <b>CLN&amp;R</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
1800CS, UD1800CS w/MD-175 (J05D-TA) (4.7L) Eng. (2005-07) <b>Dual-Flow Lube</b> ..... <b>BD7105</b> <b>Fuel/Water Separator</b> (w/o Sensor Port) (RK444Z5002)..... <b>BF1360</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (RK444Z5002)..... <b>BF1360-SP</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (RK444Z5002)..... <b>BF1360-O</b> <b>Radial Seal XP Air</b> (D6546NY108)..... <b>RS30222XP</b> <b>Cab Air</b> (2721330Z00)..... <b>CLN&amp;R</b>	2000 w/FE6TA (6.9L) Eng. (1998) <b>Lube</b> (FL201-Z9009)..... <b>BD1403</b> <b>Fuel/Water Separator</b> (RK6442NIS02)..... <b>BF1273-SP</b> <b>Fuel</b> (BF40399013)..... <b>BF984</b> <b>Radial Seal Air</b> (BF546Z9100)..... <b>RS3710</b> <b>Cab Air</b> (Fresh Air) (2721300Z06)..... <b>CLN&amp;R</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Pan-Type</b> (3.8 In. Pan, AT Series Trans.) (Allison 29540976). <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan, A.T. Series Trans.) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (AT Series) (Allison 29510922)..... <b>BT8316-MPG</b>	<b>Trans. Pan-Type</b> (3.8 In. Pan, AT Series Trans.) (Allison 29540976). <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan, A.T. Series Trans.) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (AT Series) (Allison 29510922)..... <b>BT8316-MPG</b>
1800HD w/J08E-TE (7.7L) Eng. (2008-10) <b>Dual-Flow Lube</b> (BF209Z5008)..... <b>BD7325</b> <b>Fuel/Water Separator</b> (w/o Sensor Port) (RK444Z5002)..... <b>BF1360</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (RK444Z5002)..... <b>BF1360-SP</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (RK444Z5002)..... <b>BF1360-O</b> <b>Radial Seal XP Air</b> (D6546NY108)..... <b>RS30222XP</b> <b>Cab Air</b> (Fresh Air) (2721300Z06)..... <b>CLN&amp;R</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	2000 w/FE6TA-U1 (6.9L) Eng. (1999-2004) <b>Lube</b> (FL201Z9009)..... <b>BD1403</b> <b>Fuel/Water Separator</b> (RK6442NIS02)..... <b>BF1273-SP</b> <b>Fuel</b> (BF40399013)..... <b>BF984</b> <b>Radial Seal Air</b> (BF546Z9100)..... <b>RS3710</b> <b>Cab Air</b> (Fresh Air) (2721300Z06)..... <b>CLN&amp;R</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	2000 w/J08E-TE (7.7L) Eng. (2008-10) <b>Dual-Flow Lube</b> (BF209Z5008)..... <b>BD7325</b> <b>Fuel/Water Separator</b> (w/o Sensor Port) (RK444Z5002)..... <b>BF1360</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (RK444Z5002)..... <b>BF1360-SP</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (RK444Z5002)..... <b>BF1360-O</b> <b>Radial Seal XP Air</b> (D6546NY108)..... <b>RS30222XP</b> <b>Cab Air</b> (Fresh Air) (2721300Z06)..... <b>CLN&amp;R</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
1800HD, UD1800HD w/MD-230 (J08E-TE) (7.7L) Eng. (2005-07) <b>Dual-Flow Lube</b> (BF209-Z5001)..... <b>BD7325</b> <b>Fuel/Water Separator</b> (w/o Sensor Port) (RK444Z5002)..... <b>BF1360</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (RK444Z5002)..... <b>BF1360-SP</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (RK444Z5002)..... <b>BF1360-O</b> <b>Radial Seal XP Air</b> (D6546-NY108)..... <b>RS30222XP</b> <b>Cab Air</b> (27213-30Z00)..... <b>CLN&amp;R</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Pan-Type</b> (3.8 In. Pan, AT Series Trans.) (Allison 29540976). <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan, A.T. Series Trans.) (Allison 29538489)..... <b>19739 +</b>	2000 w/GH7 (7.0L) Eng. (2011-13) <b>Radial Seal XP Air</b> (D6546NY108)..... <b>RS30222XP</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).




NISSAN UD Trucks (cont'd)	NISSAN UD Trucks (cont'd)	NISSAN UD Trucks (cont'd)
2000 w/GH7 (7.0L) Eng. (2011-13) (Cont'd) <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Diesel Exhaust Fluid</b> (5221516516)..... <b>PE17000</b>	2000, UD2000 w/MD-230 (J08E-TE) (7.7L) Eng. (2005-07) (Cont'd) <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	2300 w/FE6TA-U1 (6.9L) Eng. (2001-04) (Cont'd) <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
2000, UD2000 w/FE6 (6.9L) Eng. (1989-91) <b>Lube</b> (15208-Z9007)..... <b>B45</b> <b>Fuel/Water Separator</b> (RK6442NIS02)..... <b>BF1273-SP</b> <b>Fuel</b> (FL403-Z9005)..... <b>BF13</b> <b>Air</b> (D6546-Z9007)..... <b>PA2504</b> <b>Coolant</b> (FL915-99003)..... <b>BW5073</b> <b>Trans.</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans.</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>	2000, UD2000 w/MD-230 (J08E-TE) Eng. (2011) <b>Radial Seal XP Air</b> (D6546NY108)..... <b>RS30222XP</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Diesel Exhaust Fluid</b> (5282269261)..... <b>PE17001</b>	2300 w/FE6TA-U2 (6.9L) Eng. (1999-2000) <b>Dual-Flow Lube</b> (FL201-Z9009).. <b>BD1403</b> <b>Fuel/Water Separator</b> (RK6442NIS02)..... <b>BF1273-SP</b> <b>Fuel</b> (BF403-99013)..... <b>BF984</b> <b>Radial Seal Air</b> (D6546-Z9100).... <b>RS3710</b> <b>Cab Air</b> (27213-30Z00)..... <b>CLN&amp;R</b> <b>Trans.</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans.</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>
2000, UD2000 w/FE6T (6.9L) Eng. (1989-91) <b>Lube</b> (15208-Z9007)..... <b>B45</b> <b>Fuel/Water Separator</b> (RK6442NIS02)..... <b>BF1273-SP</b> <b>Fuel</b> (FL403-Z9005)..... <b>BF13</b> <b>Air</b> (D6546-Z9007)..... <b>PA2504</b> <b>Coolant</b> (FL915-99003)..... <b>BW5073</b> <b>Trans.</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans.</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>	2300 w/FE6TA (6.9L) Eng. (1995-98) <b>Dual-Flow Lube</b> (FL201-Z9009).. <b>BD1403</b> <b>Fuel/Water Separator</b> (RK6442NIS02)..... <b>BF1273-SP</b> <b>Fuel</b> (BF403-99013)..... <b>BF984</b> <b>Radial Seal Air</b> (D6546-Z9100).... <b>RS3710</b> <b>Cab Air</b> (Chassis S/N 50001-up) (27213-30Z00)..... <b>CLN&amp;R</b> <b>Trans.</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans.</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>	2300 w/FE6TA-U2 (6.9L) Eng. (2001-04) <b>Dual-Flow Lube</b> (FL201Z9009).... <b>BD1403</b> <b>Fuel</b> (16403NY001)..... <b>BF984</b> <b>Radial Seal Air</b> (BF546Z9100).... <b>RS3710</b> <b>Cab Air</b> (2721330Z00)..... <b>CLN&amp;R</b> <b>Trans. Pan-Type</b> (AT Series, 3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (AT Series, 5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
2000, UD2000 w/FE6TA (6.9L) Eng. (1992-94) <b>Lube</b> (FL201-Z9010)..... <b>B605</b> <b>Fuel/Water Separator</b> (RK6442NIS02)..... <b>BF1273-SP</b> <b>Fuel</b> (BF40399013)..... <b>BF984</b> <b>Air</b> (D6546-Z9007)..... <b>PA2504</b> <b>Coolant</b> (FL915-99003)..... <b>BW5073</b> <b>Trans.</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans.</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>	2300 w/FE6TA-U1 (6.9L) Eng. (1999-2000) <b>Dual-Flow Lube</b> (FL201-Z9009).. <b>BD1403</b> <b>Fuel/Water Separator</b> (RK6442NIS02)..... <b>BF1273-SP</b> <b>Fuel</b> (BF403-99013)..... <b>BF984</b> <b>Radial Seal Air</b> (D6546-Z9100).... <b>RS3710</b> <b>Cab Air</b> (27213-30Z00)..... <b>CLN&amp;R</b> <b>Trans.</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans.</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>	2300, UD2300 w/FE6T (6.9L) Eng. (1989-91) <b>Lube</b> (15208-Z9007)..... <b>B45</b> <b>Fuel/Water Separator</b> (RK6442NIS02)..... <b>BF1273-SP</b> <b>Fuel</b> (FL403-Z9005)..... <b>BF13</b> <b>Air</b> (D6546-Z9007)..... <b>PA2504</b> <b>Coolant</b> (FL915-99003)..... <b>BW5073</b> <b>Trans.</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans.</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>
2000, UD2000 w/MD-230 (J08E-TE) (7.7L) Eng. (2005-07) <b>Dual-Flow Lube</b> (BF209-Z5001).. <b>BD7325</b> <b>Fuel/Water Separator</b> (w/o Sensor Port) (RK444Z5002)..... <b>BF1360</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (RK444Z5002)..... <b>BF1360-SP</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (RK444Z5002)..... <b>BF1360-O</b> <b>Radial Seal XP Air</b> (D6546-NY108)..... <b>RS30222XP</b> <b>Cab Air</b> (27213-30Z00)..... <b>CLN&amp;R</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	2300 w/FE6TA-U1 (6.9L) Eng. (2001-04) <b>Dual-Flow Lube</b> (FL201Z9009).... <b>BD1403</b> <b>Fuel</b> (16403NY001)..... <b>BF984</b> <b>Radial Seal Air</b> (BF546Z9100).... <b>RS3710</b> <b>Cab Air</b> (2721330Z00)..... <b>CLN&amp;R</b> <b>Trans. Pan-Type</b> (AT Series, 3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (AT Series, 5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	2300, UD2300 w/FE6TA (6.9L) Eng. (1992-94) <b>F-F Lube</b> (FL201-Z9010)..... <b>B605</b> <b>B-P Lube</b> (FL201-Z9011)..... <b>B7018</b> <b>Fuel/Water Separator</b> (RK6442NIS02)..... <b>BF1273-SP</b> <b>Fuel</b> (BF403-99013)..... <b>BF984</b> <b>Air</b> (D6546-Z9007)..... <b>PA2504</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>NISSAN UD Trucks (cont'd)</b>	<b>NISSAN UD Trucks (cont'd)</b>	<b>NISSAN UD Trucks (cont'd)</b>
2300, UD2300 w/FE6TA (6.9L) Eng. (1992-94) (Cont'd) <b>Coolant</b> (FL915-99003)..... <b>BW5073</b> <b>Trans.</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans.</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>	2300DH, UD2300DH w/MD-230 (J08E-TE) (7.7L) Eng. (2005-07) (Cont'd) <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	2600 w/FE6TA (6.9L) Eng. (1995-1998) (Cont'd) A.T. Series Trans.) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (AT Series) (Allison 29510922)..... <b>BT8316-MPG</b>
2300DH w/J08E-TE (7.7L) Eng. (2008-10) <b>Dual-Flow Lube</b> (BF209Z5008)... <b>BD7325</b> <b>Fuel/Water Separator</b> (w/o Sensor Port) (RK444Z5002)..... <b>BF1360</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (RK444Z5002)..... <b>BF1360-SP</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (RK444Z5002)..... <b>BF1360-O</b> <b>Radial Seal XP Air</b> (D6546NY108)..... <b>RS30222XP</b> <b>Cab Air</b> (2721300Z06)..... <b>CLN&amp;R</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	2300LP w/GH7 (7.0L) Eng. (2011-13) <b>Radial Seal XP Air</b> (D6546NY108)..... <b>RS30222XP</b> <b>Cab Air</b> (Fresh Air) (2721300Z06)..... <b>CLN&amp;R</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Diesel Exhaust Fluid</b> (5221516516)..... <b>PE17000</b>	2600 w/FE6TA-U1 (6.9L) Eng. (1999-2004) <b>Lube</b> (FL201Z9009)..... <b>BD1403</b> <b>Fuel</b> (BF40399013)..... <b>BF984</b> <b>Radial Seal Air</b> (BF546Z9100).... <b>RS3710</b> <b>Cab Air</b> (Fresh Air) (2721300Z06)..... <b>CLN&amp;R</b> <b>Trans. Pan-Type</b> (3.8 In. Pan, AT Series Trans.) (Allison 29540976). <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan, A.T. Series Trans.) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (AT Series) (Allison 29510922)..... <b>BT8316-MPG</b>
2300DH w/GH7 (7.0L) Eng. (2011-13) <b>Radial Seal XP Air</b> (D6546NY108)..... <b>RS30222XP</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Diesel Exhaust Fluid</b> (5221516516)..... <b>PE17000</b>	2300LP, UD2300LP w/MD-230 (J08E-TE) (7.7L) Eng. (2005-07) <b>Dual-Flow Lube</b> (BF209-Z5001).. <b>BD7325</b> <b>Fuel/Water Separator</b> (w/o Sensor Port) (RK444Z5002)..... <b>BF1360</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (RK444Z5002)..... <b>BF1360-SP</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (RK444Z5002)..... <b>BF1360-O</b> <b>Radial Seal XP Air</b> (D6546-NY108)..... <b>RS30222XP</b> <b>Cab Air</b> (27213-30Z00)..... <b>CLN&amp;R</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	2600 w/FE6TA-U2 (6.9L) Eng. (1999-2004) <b>Lube</b> (FL201Z9009)..... <b>BD1403</b> <b>Fuel</b> (BF40399013)..... <b>BF984</b> <b>Radial Seal Air</b> (BF546Z9100).... <b>RS3710</b> <b>Cab Air</b> (Fresh Air) (2721300Z06)..... <b>CLN&amp;R</b> <b>Trans. Pan-Type</b> (3.8 In. Pan, AT Series Trans.) (Allison 29540976). <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan, A.T. Series Trans.) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (AT Series) (Allison 29510922)..... <b>BT8316-MPG</b>
2300DH, UD2300DH w/MD-230 (J08E-TE) (7.7L) Eng. (2005-07) <b>Dual-Flow Lube</b> (BF209-Z5001).. <b>BD7325</b> <b>Fuel/Water Separator</b> (w/o Sensor Port) (RK444Z5002)..... <b>BF1360</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (RK444Z5002)..... <b>BF1360-SP</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (RK444Z5002)..... <b>BF1360-O</b> <b>Fuel</b> (16403-NY001)..... <b>BF984</b> <b>Radial Seal XP Air</b> (D6546-NY108)..... <b>RS30222XP</b> <b>Cab Air</b> (27213-30Z00)..... <b>CLN&amp;R</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	2600 w/J08E-TE (7.7L) Eng. (2008-2010) <b>Dual-Flow Lube</b> (BF209Z5008)... <b>BD7325</b> <b>Fuel/Water Separator</b> (w/o Sensor Port) (RK444Z5002)..... <b>BF1360</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (RK444Z5002)..... <b>BF1360-SP</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (RK444Z5002)..... <b>BF1360-O</b> <b>Radial Seal XP Air</b> (D6546NY108)..... <b>RS30222XP</b> <b>Cab Air</b> (Fresh Air) (2721300Z06)..... <b>CLN&amp;R</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	2600 w/GH7 (7.0L) Eng. (2011-13) <b>Radial Seal XP Air</b> (D6546NY108)..... <b>RS30222XP</b> <b>Cab Air</b> (Fresh Air) (2721300Z06)..... <b>CLN&amp;R</b>
2600 w/FE6TA (6.9L) Eng. (1995-1998) <b>Lube</b> (FL201Z9009)..... <b>BD1403</b> <b>Fuel</b> (BF40399013)..... <b>BF984</b> <b>Radial Seal Air</b> (BF546Z9100).... <b>RS3710</b> <b>Cab Air</b> (Fresh Air) (2721300Z06)..... <b>CLN&amp;R</b> <b>Trans. Pan-Type</b> (3.8 In. Pan, AT Series Trans.) (Allison 29540976). <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan,		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

NISSAN UD Trucks (cont'd)	NISSAN UD Trucks (cont'd)	NISSAN UD Trucks (cont'd)
2600 w/GH7 (7.0L) Eng. (2011-13) (Cont'd) <b>Cab Air</b> (Recirculating Air) (2721330Z00)..... <b>CLN&amp;R</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Diesel Exhaust Fluid</b> (5221516516)..... <b>PE17000</b>	2600, UD2600 w/MD-230 (J08E-TE) (7.7L) Eng. (2005-07) (Cont'd) <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> 2800, UD2800 w/FE6T (6.9L) Eng. (1989-91) <b>Lube</b> (15208-Z9007)..... <b>B45</b> <b>Fuel/Water Separator</b> (RK6442NIS02)..... <b>BF1273-SP</b> <b>Fuel</b> (FL403-Z9005)..... <b>BF13</b> <b>O. Air</b> (D6546-Z9007)..... <b>PA2504</b> <b>I. Air</b> (Cab Back Snorkel System) (D6546-Z9006)..... <b>PA2545</b> <b>Coolant</b> (FL915-99003)..... <b>BW5073</b> <b>Trans.</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans.</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> 2800, UD2800 w/FE6TA (6.9L) Eng. (1992-94) <b>F-F Lube</b> (FL201-Z9010)..... <b>B605</b> <b>B-P Lube</b> (FL201-Z9011)..... <b>B7018</b> <b>Fuel/Water Separator</b> (RK6442NIS02)..... <b>BF1273-SP</b> <b>Fuel</b> (BF403-99013)..... <b>BF984</b> <b>Air</b> (D6546-Z9007)..... <b>PA2504</b> <b>Coolant</b> (FL915-99003)..... <b>BW5073</b> <b>Trans.</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans.</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> 3000 w/FE6TA (6.9L) Eng. (1995-1998) <b>Lube</b> (FL201Z9009)..... <b>BD1403</b> <b>Fuel</b> (BF40399013)..... <b>BF984</b> <b>Radial Seal Air</b> (BF546Z9100)..... <b>RS3710</b> <b>Cab Air</b> (Fresh Air) (2721300Z06)..... <b>CLN&amp;R</b> <b>Trans. Pan-Type</b> (3.8 In. Pan, AT Series Trans.) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan, A.T. Series Trans.) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (AT Series) (Allison 29510922)..... <b>BT8316-MPG</b> 3000 w/FE6TA-U1 (6.9L) Eng. (1999-2000) <b>Lube</b> (FL201Z9009)..... <b>BD1403</b> <b>Fuel</b> (BF40399013)..... <b>BF984</b> <b>Radial Seal Air</b> (BF546Z9100)..... <b>RS3710</b> <b>Cab Air</b> (Fresh Air) (2721300Z06)..... <b>CLN&amp;R</b> <b>Trans. Pan-Type</b> (3.8 In. Pan, AT Series Trans.) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan, A.T. Series Trans.) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (AT Series) (Allison 29510922)..... <b>BT8316-MPG</b>	3000 w/FE6TA-U2 (6.9L) Eng. (1999-2000) <b>Lube</b> (FL201Z9009)..... <b>BD1403</b> <b>Fuel</b> (BF40399013)..... <b>BF984</b> <b>Radial Seal Air</b> (BF546Z9100)..... <b>RS3710</b> <b>Cab Air</b> (Fresh Air) (2721300Z06)..... <b>CLN&amp;R</b> <b>Trans. Pan-Type</b> (3.8 In. Pan, AT Series Trans.) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan, A.T. Series Trans.) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (AT Series) (Allison 29510922)..... <b>BT8316-MPG</b> 3000, UD3000 w/NE6T (7.4L) Eng. (1989-91) <b>Lube</b> (15274-99189)..... <b>BT398</b> <b>Fuel/Water Separator</b> (RK6442NIS02)..... <b>BF1273-SP</b> <b>Fuel</b> (BF403-99013)..... <b>BF984</b> <b>O. Air</b> (D6546-Z9007)..... <b>PA2504</b> <b>I. Air</b> (D6546-Z9006)..... <b>PA2545</b> <b>Coolant</b> (FL915-99003)..... <b>BW5073</b> <b>Trans.</b> (Allison 29538489)..... <b>19739 +</b> 3000HD, UD3000HD w/NE6TA (7.4L) Eng. (1992-94) <b>F-F Lube</b> (FL201-Z9010)..... <b>B605</b> <b>B-P Lube</b> (FL201-Z9011)..... <b>B7018</b> <b>Fuel/Water Separator</b> (RK6442NIS02)..... <b>BF1273-SP</b> <b>Fuel</b> (BF403-99013)..... <b>BF984</b> <b>O. Air</b> (D6546-Z9009)..... <b>PA2577</b> <b>I. Air</b> (D6546-Z9008)..... <b>PA2578</b> <b>Coolant</b> (FL915-99003)..... <b>BW5073</b> <b>Trans.</b> (Allison 29538489)..... <b>19739 +</b> 3000SD, UD3000SD w/FE6TA (6.9L) Eng. (1992-94) <b>F-F Lube</b> (FL201-Z9010)..... <b>B605</b> <b>B-P Lube</b> (FL201-Z9011)..... <b>B7018</b> <b>Fuel/Water Separator</b> (RK6442NIS02)..... <b>BF1273-SP</b> <b>Fuel</b> (BF403-99013)..... <b>BF984</b> <b>O. Air</b> (D6546-Z9007)..... <b>PA2504</b> <b>Coolant</b> (FL915-99003)..... <b>BW5073</b> <b>Trans.</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans.</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> 3300 w/NE6TA (7.4L) Eng. (1992-94) <b>B-P Lube</b> (BF201Z9011)..... <b>B7018</b> <b>Fuel</b> (BF40399013)..... <b>BF984</b> <b>O. Air</b> (BF546Z9009)..... <b>PA2577</b> <b>Cab Air</b> (Fresh Air) (2721300Z06)..... <b>CLN&amp;R</b> <b>Trans. Pan-Type</b> (MT Series) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (MT Series) (Allison 29510922)..... <b>BT8316-MPG</b>
2600, UD2600 w/FE6T (6.9L) Eng. (1989-91) <b>Lube</b> (15208-Z9007)..... <b>B45</b> <b>Fuel/Water Separator</b> (RK6442NIS02)..... <b>BF1273-SP</b> <b>Fuel</b> (FL403-Z9005)..... <b>BF13</b> <b>O. Air</b> (D6546-Z9007)..... <b>PA2504</b> <b>I. Air</b> (Cab Back Snorkel System) (D6546-Z9006)..... <b>PA2545</b> <b>Coolant</b> (FL915-99003)..... <b>BW5073</b> <b>Trans.</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans.</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>	2600, UD2600 w/FE6TA (6.9L) Eng. (1992-94) <b>F-F Lube</b> (FL201-Z9010)..... <b>B605</b> <b>B-P Lube</b> (FL201-Z9011)..... <b>B7018</b> <b>Fuel/Water Separator</b> (RK6442NIS02)..... <b>BF1273-SP</b> <b>Fuel</b> (BF403-99013)..... <b>BF984</b> <b>Air</b> (D6546-Z9007)..... <b>PA2504</b> <b>Coolant</b> (FL915-99003)..... <b>BW5073</b> <b>Trans.</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans.</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>	
2600, UD2600 w/MD-230 (J08E-TE) (7.7L) Eng. (2005-07) <b>Dual-Flow Lube</b> (BF209-Z5001)..... <b>BD7325</b> <b>Fuel/Water Separator</b> (w/o Sensor Port) (RK444Z5002)..... <b>BF1360</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (RK444Z5002)..... <b>BF1360-SP</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (RK444Z5002)..... <b>BF1360-O</b> <b>Radial Seal XP Air</b> (D6546-NY108)..... <b>RS30222XP</b> <b>Cab Air</b> (27213-30Z00)..... <b>CLN&amp;R</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>		

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>NISSAN UD Trucks (cont'd)</b>	<b>NISSAN UD Trucks (cont'd)</b>	<b>NISSAN UD Trucks (cont'd)</b>
3300 w/FE6TA-U1 (6.9L) Eng. (1999-2004) <b>Lube</b> (FL201Z9009)..... <b>BD1403</b> <b>Fuel</b> (BF40399013)..... <b>BF984</b> <b>O. Air</b> (BF546Z9009)..... <b>PA2577</b> <b>Cab Air</b> (Fresh Air) (2721300Z06)..... <b>CLN&amp;R</b>	3300, UD3300 w/NE6 (7.4L) Eng. (1989-91) <b>Lube</b> (15274-99189)..... <b>BT398</b> <b>Fuel/Water Separator</b> (RK6442NIS02)..... <b>BF1273-SP</b> <b>Fuel</b> (BF403-99013)..... <b>BF984</b> <b>O. Air</b> (D6546-Z9007)..... <b>PA2504</b> <b>I. Air</b> (D6546-Z9006)..... <b>PA2545</b> <b>Coolant</b> (FL915-99003)..... <b>BW5073</b> <b>Trans.</b> (Allison 29538489)..... <b>19739 +</b>	CD45 <b>Lube</b> (15274-99227)..... <b>PT8335</b> <b>Lube</b> (15274-99329)..... <b>P7059</b> <b>Fuel</b> (16444-99128)..... <b>PF7554</b>
3300 w/FE6TA-U2 (6.9L) Eng. (1999-2004) <b>Lube</b> (FL201Z9009)..... <b>BD1403</b> <b>Fuel</b> (BF40399013)..... <b>BF984</b> <b>O. Air</b> (BF546Z9009)..... <b>PA2577</b> <b>Cab Air</b> (Fresh Air) (2721300Z06)..... <b>CLN&amp;R</b>	3300, UD3300 w/FE6TA Eng. (1992-94) <b>F-F Lube</b> (FL201-Z9010)..... <b>B605</b> <b>B-P Lube</b> (FL201-Z9011)..... <b>B7018</b> <b>Fuel/Water Separator</b> (RK6442NIS02)..... <b>BF1273-SP</b> <b>Fuel</b> (BF403-99013)..... <b>BF984</b> <b>O. Air</b> (D6546-Z9009)..... <b>PA2577</b> <b>I. Air</b> (D6546-Z9008)..... <b>PA2578</b> <b>Coolant</b> (FL915-99003)..... <b>BW5073</b> <b>Trans.</b> (Allison 29538489)..... <b>19739 +</b>	CD50 w/RD8 Eng. (8/73-8/76) <b>Lube</b> (15274-99227)..... <b>PT8335</b> <b>Lube</b> (15274-90225)..... <b>P7107</b> <b>Fuel</b> (16444-99028)..... <b>PF7553</b>
3300 w/J08E-TE (7.7L) Eng. (2008-10) <b>Dual-Flow Lube</b> (BF209Z5008)..... <b>BD7325</b> <b>Fuel/Water Separator</b> (w/o Sensor Port) (RK444Z5002)..... <b>BF1360</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (RK444Z5002)..... <b>BF1360-SP</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (RK444Z5002)..... <b>BF1360-O</b> <b>Radial Seal XP Air</b> (D6546NY108)..... <b>RS30222XP</b> <b>Cab Air</b> (Fresh Air) (2721300Z06)..... <b>CLN&amp;R</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	3300, UD3300 w/MD-230 (J08E-TE) (7.7L) Eng. (2005-07) <b>Dual-Flow Lube</b> (BF209-Z5001)..... <b>BD7325</b> <b>Fuel/Water Separator</b> (w/o Sensor Port) (RK444Z5002)..... <b>BF1360</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (RK444Z5002)..... <b>BF1360-SP</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (RK444Z5002)..... <b>BF1360-O</b> <b>Radial Seal XP Air</b> (D6546-NY108)..... <b>RS30222XP</b> <b>Cab Air</b> (27213-30Z00)..... <b>CLN&amp;R</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	CD50, CD51 w/RD8 Eng. (1976-78) <b>Lube</b> (15274-99225)..... <b>P7107</b> <b>Lube</b> (15274-99285)..... <b>P7058</b>
3300 w/GH7 (7.0L) Eng. (2011-13) <b>Radial Seal XP Air</b> (D6546NY108)..... <b>RS30222XP</b> <b>Cab Air</b> (Fresh Air) (2721300Z06)..... <b>CLN&amp;R</b> <b>Cab Air</b> (Recirculating Air) (2721330Z00)..... <b>CLN&amp;R</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Diesel Exhaust Fluid</b> (5221516516)..... <b>PE17000</b>	A-CW50, K-CV50, K-CV50U, A-CW52, K-CW60, K-CW61 w/RD8, RD10 Eng. <b>Lube</b> (15274-99227)..... <b>PT8335</b> <b>Lube</b> (15274-99329)..... <b>P7059</b> <b>Fuel</b> (16444-99028)..... <b>PF7553</b>	CG450 (5/90-5/96) <b>F-F Lube</b> (15274-EP025A)..... <b>P7059</b> <b>B-P Lube</b> (15274-EP026A)..... <b>PT8335</b> <b>Fuel</b> (16403-99011)..... <b>BF970 +</b> <b>O. Std. Air</b> (16546-97013)..... <b>PA2676 +</b> <b>O. XP Air</b> (16546-97013)..... <b>PA2676XP +</b> <b>I. Air</b> (16546-97012)..... <b>PA3668</b>
	AZ45 Crane w/PE6T Eng. <b>Lube</b> (15274-EP027)..... <b>PT8335</b> <b>I. Air</b> (16546-96014)..... <b>PA1893</b>	CGA45 w/PE6T Eng. <b>F-F Lube</b> (15274-EP025A)..... <b>P7059</b> <b>B-P Lube</b> (15274-EP026A)..... <b>PT8335</b> <b>Std. O. Air</b> (16546-97004)..... <b>PA1846 +</b> <b>O. Air</b> (Upgrade) (16546-97004)..... <b>PA1846XP +</b> <b>I. Air</b> (16546-99508)..... <b>PA1880</b>
	CD30 w/PE6 Eng. <b>Lube</b> ..... <b>P7104</b>	CGA45T, CGA45U, CKA45, CKA45CT w/PE6T Eng. <b>F-F Lube</b> (15274-99329)..... <b>P7059</b> <b>B-P Lube</b> (15274-99226)..... <b>PT8335</b> <b>Fuel</b> (16444-99129)..... <b>PF7554</b> <b>Std. O. Air</b> (16546-97004)..... <b>PA1846 +</b> <b>O. Air</b> (Upgrade) (16546-97004)..... <b>PA1846XP +</b> <b>I. Air</b> (16546-97005)..... <b>PA1880</b>
	CD31, CD32 w/PE6 Eng. <b>Lube</b> (15274-99225)..... <b>P7107</b>	CGA46 w/PE6T Eng. <b>F-F Lube</b> (15274-EP025A)..... <b>P7059</b> <b>B-P Lube</b> (15274-EP026A)..... <b>PT8335</b> <b>O. Std. Air</b> (16546-97013)..... <b>PA2676 +</b> <b>O. XP Air</b> (16546-97013)..... <b>PA2676XP +</b> <b>I. Air</b> (16546-97012)..... <b>PA3668</b>
	CD40, CD41, CD42, CD43 w/PD6T Eng. <b>Lube</b> (15274-99225)..... <b>P7107</b> <b>Lube</b> (15274-99285)..... <b>P7058</b> <b>Fuel</b> (16444-99028)..... <b>PF7553</b>	CGB290 w/PF6T, PF6TA, PF6TB Eng. <b>Lube</b> (15274-EP027)..... <b>PT8335</b> <b>O. Std. Air</b> (16546-97013)..... <b>PA2676 +</b> <b>O. XP Air</b> (16546-97013)..... <b>PA2676XP +</b> <b>I. Air</b> (16546-97012)..... <b>PA3668</b>
	CD40, CD41, CD42, CD43 w/PD6T Eng. <b>Lube</b> (15274-99225)..... <b>P7107</b> <b>Lube</b> (15274-99285)..... <b>P7058</b> <b>Fuel</b> (16444-99028)..... <b>PF7553</b>	CGB320 w/PF6T, PF6TA, PF6TB Eng. <b>Lube</b> (15274-EP027)..... <b>PT8335</b> <b>O. Std. Air</b> (16546-97013)..... <b>PA2676 +</b> <b>O. XP Air</b> (16546-97013)..... <b>PA2676XP +</b> <b>I. Air</b> (16546-97012)..... <b>PA3668</b>
		CGB350 w/PF6T, PF6TA, PF6TB Eng. <b>Lube</b> (15274-EP027)..... <b>PT8335</b> <b>O. Std. Air</b> (16546-97013)..... <b>PA2676 +</b> <b>O. XP Air</b> (16546-97013)..... <b>PA2676XP +</b> <b>I. Air</b> (16546-97012)..... <b>PA3668</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

NISSAN UD Trucks (cont'd)	NISSAN UD Trucks (cont'd)	NISSAN UD Trucks (cont'd)
CK10 w/ND6 Eng. Lube..... P7104 O. Air (16546-96015)..... PA1902-FN	CKB290 w/PF6T, PF6TA, PF6TB Engs. Lube (15274-EP027)..... PT8335 O. Air (16546-97013)..... PA2676 + I. Air (16546-97012)..... PA3668	CLA83, CMA83 w/FE6, FE6T Engs. Lube (1987-88) (15208-Z9006).... B45 Fuel (1987-88) (16403-Z9003).... BF13 Air (D6546-Z9007)..... PA2504 Coolant (FL915-99003)..... BW5073
CK11 w/ND6 Eng. O. Air (16546-96015)..... PA1902-FN	CKB320 w/PF6T, PF6TA, PF6TB Engs. Lube (15274-EP027)..... PT8335 O. Std. Air (16546-97013)..... PA2676 + O. XP Air (16546-97013)..... PA2676XP + I. Air (16546-97012)..... PA3668	CMA86 w/FD6, FD6T Eng. Fuel (16403-Z9000)..... BF954 + Air (16546-Z9004)..... PA2779
CK11D, CK11L w/ND6 Eng. Lube..... P7104 O. Air..... PA1902-FN I. Air..... PA2545	CKB350 w/PF6T, PF6TA, PF6TB Engs. Lube (15274-EP027)..... PT8335 O. Std. Air (16546-97013)..... PA2676 + O. XP Air (16546-97013)..... PA2676XP + I. Air (16546-97012)..... PA3668	CMA87 w/FE6A, FE6B Engs. Fuel (16403-Z9000)..... BF954 + Fuel (16444-EP029A)..... PF7554 Air (16546-Z9004)..... PA2779
CK30 B-P Lube (15274-EP026A)..... PT8335 O. Air (16546-96016)..... PA1884 + O. Air (1654696015)..... PA1902-FN	CKB450 (5/90-5/96) F-F Lube (15274-EP025A)..... P7059 B-P Lube (15274-EP026A)..... PT8335 Fuel (16403-99011)..... BF970 + O. Std. Air (16546-97013)..... PA2676 + O. XP Air (16546-97013)..... PA2676XP + I. Air (16546-97012)..... PA3668	CMB87 w/FE6A, FE6B Engs. Fuel (16403-Z9000)..... BF954 + Fuel (16444-EP029A)..... PF7554 Air (16546-Z9004)..... PA2779
CK40 w/PD6T Eng. B-P Lube (15274-EP026A)..... PT8335 I. Air (16546-96014)..... PA1893	CKB450 (5/90-5/96) F-F Lube (15274-EP025A)..... P7059 B-P Lube (15274-EP026A)..... PT8335 Fuel (16403-99011)..... BF970 + O. Std. Air (16546-97013)..... PA2676 + O. XP Air (16546-97013)..... PA2676XP + I. Air (16546-97012)..... PA3668	CMF87 w/FE6A Eng. (North America) Lube..... BT234
CK40, CK45 w/PD6T, PE6T Engs. Lube (15274-99227)..... PT8335 Lube (15274-99329)..... P7059 Fuel (16444-99128)..... PF7554 Std. O. Air (16546-97004)..... PA1846 + O. Air (Upgrade) (16546-97004).... PA1846XP + I. Air (16546-97005)..... PA1880	CLA w/FE6, FE6T Engs. (1986-88) Lube (15208-Z9007)..... B45 Fuel (16403Z9005)..... BF13 Air (D6546-Z9007)..... PA2504 Coolant (FL915-99003)..... BW5073	CMF87 w/FE6A, FE6B Engs. (Australia) Fuel (16403-Z9000)..... BF954 + Fuel (16444-EP029A)..... PF7554 Air (16546-Z9004)..... PA2779
CK50-BT, CK60, CK60-BT Lube (15274-99226)..... PT8335 Lube (15274-99329)..... P7059 Fuel (16444-99028)..... PF7553	CLG87 w/FE6A, FE6B Engs. Fuel (16403-Z9000)..... BF954 + Fuel (16444-EP029A)..... PF7554 O. Air (16546-Z9004)..... PA2779 I. Air (16546-Z9006)..... PA2545	CMF88 Fuel (16403-99011)..... BF970 + Fuel (16444-EP029A)..... PF7554 O. Air (16546-Z9004)..... PA2779 I. Air (16546-Z9006)..... PA2545
CK60 w/RD10 Eng. Lube (15274-90227)..... P7107 Lube (15274-99285)..... P7058 Fuel (16444-99028)..... PF7553	CLG88 w/FE6T Eng. Fuel (16403-99011)..... BF970 + Fuel (16444-EP029A)..... PF7554 O. Air (16546-Z9004)..... PA2779 I. Air (16546-Z9006)..... PA2545	CMF89 Fuel (16403-Z9000)..... BF954 + Fuel (16444-EP029A)..... PF7554 Air (16546-Z9004)..... PA2779
CK320 (1/96-11/02) F-F Lube (15274-EP025A)..... P7059 B-P Lube (15274-EP026A)..... PT8335 Fuel (16403-99011)..... BF970 + O. Std. Air (16546-97013)..... PA2676 + O. XP Air (16546-97013)..... PA2676XP + I. Air (16546-97012)..... PA3668	CM80 w/FD6 Eng. I. Air (16546-Z5003)..... PA1981	Condor CM w/ED6 Eng. Lube (15208-Z9025)..... P723 Fuel (16444-Z9000)..... P7103
Trans. (Nissan Trans) (32622-90002)..... B113	CM80K w/FD6 Eng. F-F Lube Ele. (15208-Z9025)..... P723 Fuel Ele. (16444-Z9000)..... P7103 O. Air (16546-Z5004)..... PA1902-FN I. Air (16546-Z5003)..... PA1981	Condor GF w/ED6, FD6, FD6T Engs. F-F Lube (15208-Z9025)..... P723 Fuel (16444-Z9000)..... P7103
CK330e w/ME92TB Eng. Dual-Flow Lube (15201Z9013).... BD1403 O. Air (1654696064)..... PA2582 Trans. (32622-90002)..... B113	CM90 w/FD6 Eng. I. Air (16546-Z5003)..... PA1981	CPB w/NE6, NE6T Engs. (1986-88) Lube (15274-99189)..... BT398 Fuel (BF40399013)..... BF984 O. Air (D6546-Z9007)..... PA2504 I. Air (D6546-Z9006)..... PA2545 Coolant (FL915-99003)..... BW5073
CKA45 w/PE6T Eng. F-F Lube (15274-EP025A)..... P7059 B-P Lube (15274-EP026A)..... PT8335 Std. O. Air (16546-97004)..... PA1846 + O. Air (Upgrade) (16546-97004).... PA1846XP + I. Air (16546-99508)..... PA1880	CMA w/FE6, FE6T Engs. (1986-88) Lube (15208-Z9007)..... B45 Fuel (16403Z9005)..... BF13 Air (D6546-Z9007)..... PA2504 Coolant (FL915-99003)..... BW5073	CPB12 w/NE6 Eng. (Australia) O. Air (16546-97015)..... LL1884 + I. Air (16546-96010)..... PA1911
CKA46 w/PE6T Eng. F-F Lube (15274-EP025A)..... P7059 B-P Lube (15274-EP026A)..... PT8335 O. Std. Air (16546-97013)..... PA2676 + O. XP Air (16546-97013)..... PA2676XP + I. Air (16546-97012)..... PA3668	CMA81 w/FD6, FD6T Eng. Fuel (16403-Z9000)..... BF954 + Fuel (16444-EP029A)..... PF7554 Air (16546-Z9004)..... PA2779	CPB12 w/NE6T Eng. (Australia) O. Air (16546-Z9004)..... PA2779 I. Air (16546-Z9006)..... PA2545


+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

NISSAN UD Trucks (cont'd)	NISSAN UD Trucks (cont'd)	NISSAN UD Trucks (cont'd)
CPB12, CPC12, CPC12BT w/NE6, NE6T Engs. (North America) (Cont'd) Coolant (FL915-99003)..... <b>BW5073</b>	CW40 w/PD6T Eng. B-P Lube (15274-EP026A)..... <b>PT8335</b> I. Air (16546-96014)..... <b>PA1893</b>	CW385 w/GE13TB Eng. (Cont'd) O. Std. Air (16546-97013)..... <b>PA2676 +</b> O. XP Air (16546-97013)..... <b>PA2676XP +</b> I. Air (17801-2310)..... <b>PA3668</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b>
CPB14 O. Air (16546-Z9004)..... <b>PA2779</b> I. Air (16546-Z9006)..... <b>PA2545</b>	CW41 w/PD6T Eng. B-P Lube (15274-EP026A)..... <b>PT8335</b> I. Air (16546-96014)..... <b>PA1893</b>	CW420 F-F Lube (15274-EP025A)..... <b>P7059</b> B-P Lube (15274-EP026A)..... <b>PT8335</b> Fuel/Water Separator (16444-EP027)..... <b>PF7618</b> Fuel (16403-99011)..... <b>BF970 +</b>
CPB87 Fuel (16403-Z9000)..... <b>BF954 +</b> Fuel (16444-EP029A)..... <b>PF7554</b> O. Air (16546-Z9004)..... <b>PA2779</b> I. Air (16546-Z9006)..... <b>PA2545</b>	CW50 F-F Lube (15274-99285)..... <b>P7058</b> B-P Lube (15274-EP026A)..... <b>PT8335</b>	CW440e w/GE13TD Eng. F-F Lube (1527499985)..... <b>P7059</b> Fuel/Water Separator (w/Drain) (16403-NY000)..... <b>BF1281</b> Fuel/Water Separator (Open End for Bowl) (16403-NY000)..... <b>BF46018-O</b> O. Std. Air (16546-97013)..... <b>PA2676 +</b> O. XP Air (16546-97013)..... <b>PA2676XP +</b> I. Air (16546-97012)..... <b>PA3668</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b>
CPB88 Fuel (16403-99011)..... <b>BF970 +</b> Fuel (16444-EP029A)..... <b>PF7554</b> O. Air (16546-Z9004)..... <b>PA2779</b> I. Air (16546-Z9006)..... <b>PA2545</b> Single Air (16546-Z9003)..... <b>PA2504</b>	CW60 w/RD10 Eng. Lube (15274-90227)..... <b>P7107</b> Lube (15274-99285)..... <b>P7058</b> Fuel (16444-99028)..... <b>PF7553</b>	CW445 w/GE13TD Eng. F-F Lube (Chassis # to-205) (1527499985)..... <b>P7059</b> F-F Lube Ele. (15274-99286)..... <b>P7059</b> Fuel/Water Separator (w/Drain) (16403-NY000)..... <b>BF1281</b> Fuel/Water Separator (Open End for Bowl) (16403-NY000)..... <b>BF46018-O</b> Fuel..... <b>BF970 +</b> O. Std. Air (16546-97013)..... <b>PA2676 +</b> O. XP Air (16546-97013)..... <b>PA2676XP +</b> I. Air (16546-97012)..... <b>PA3668</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b>
CPC w/NE6, NE6T Engs. (1986-88) Lube (15274-99189)..... <b>BT398</b> Fuel (BF40399013)..... <b>BF984</b> O. Air (D6546-Z9007)..... <b>PA2504</b> I. Air (D6546-Z9006)..... <b>PA2545</b> Coolant (FL915-99003)..... <b>BW5073</b>	CW240 w/NE6TA Eng. Dual-Flow Lube (15201-EP025A)..... <b>BD1403</b> Fuel (16403-99011)..... <b>BF970 +</b> O. Air (16546-99316)..... <b>PA2577</b>	CW420 F-F Lube (15274-EP025A)..... <b>P7059</b> B-P Lube (15274-EP026A)..... <b>PT8335</b> Fuel/Water Separator (16444-EP027)..... <b>PF7618</b> Fuel (16403-99011)..... <b>BF970 +</b>
CPC12 w/NE6 Eng. (Australia) O. Air (16546-97015)..... <b>LL1884 +</b> I. Air (16546-96010)..... <b>PA1911</b>	CW250 w/NE6TA Eng. Dual-Flow Lube (15201-EP025A)..... <b>BD1403</b> Fuel (16403-99011)..... <b>BF970 +</b> O. Air (16546-99316)..... <b>PA2577</b>	CW445 w/GE13TD Eng. F-F Lube (Chassis # to-205) (1527499985)..... <b>P7059</b> F-F Lube Ele. (15274-99286)..... <b>P7059</b> Fuel/Water Separator (w/Drain) (16403-NY000)..... <b>BF1281</b> Fuel/Water Separator (Open End for Bowl) (16403-NY000)..... <b>BF46018-O</b> Fuel..... <b>BF970 +</b> O. Std. Air (16546-97013)..... <b>PA2676 +</b> O. XP Air (16546-97013)..... <b>PA2676XP +</b> I. Air (16546-97012)..... <b>PA3668</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b>
CPC12 w/NE6T Eng. (Australia) O. Air (16546-Z9004)..... <b>PA2779</b> I. Air (16546-Z9006)..... <b>PA2545</b>	CW290 (5/90-5/96) F-F Lube (15274-EP025A)..... <b>P7059</b> B-P Lube (15274-EP026A)..... <b>PT8335</b> Fuel (16403-99011)..... <b>BF970 +</b> O. Std. Air (16546-97013)..... <b>PA2676 +</b> O. XP Air (16546-97013)..... <b>PA2676XP +</b> I. Air (16546-97012)..... <b>PA3668</b>	CW445 w/GE13TD Eng. F-F Lube (Chassis # to-205) (1527499985)..... <b>P7059</b> F-F Lube Ele. (15274-99286)..... <b>P7059</b> Fuel/Water Separator (w/Drain) (16403-NY000)..... <b>BF1281</b> Fuel/Water Separator (Open End for Bowl) (16403-NY000)..... <b>BF46018-O</b> Fuel..... <b>BF970 +</b> O. Std. Air (16546-97013)..... <b>PA2676 +</b> O. XP Air (16546-97013)..... <b>PA2676XP +</b> I. Air (16546-97012)..... <b>PA3668</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b>
CPC14 w/NE6T Eng. O. Air (16546-Z9004)..... <b>PA2779</b> I. Air (16546-Z9006)..... <b>PA2545</b>	CW320 (5/90-5/96) F-F Lube (15274-EP025A)..... <b>P7059</b> B-P Lube (15274-EP026A)..... <b>PT8335</b> Fuel (16403-99011)..... <b>BF970 +</b> O. Air (16546-97013)..... <b>PA2676 +</b> I. Air (16546-97012)..... <b>PA3668</b>	CWA12 w/NE6 Eng. O. Air (16546-97015)..... <b>LL1884 +</b> I. Air (16546-96010)..... <b>PA1911</b>
CPC15 w/NE6T Eng. (Australia) O. Air (16546-Z9004)..... <b>PA2779</b> I. Air (16546-Z9006)..... <b>PA2545</b>	CW350 (5/90-11/02) F-F Lube (15274-EP025A)..... <b>P7059</b> B-P Lube (15274-EP026A)..... <b>PT8335</b> Fuel (16403-99011)..... <b>BF970 +</b> O. Std. Air (16546-97013)..... <b>PA2676 +</b> O. XP Air (16546-97013)..... <b>PA2676XP +</b> I. Air (16546-97012)..... <b>PA3668</b>	CWA12 w/NE6T Eng. O. Air (16546-Z9004)..... <b>PA2779</b> I. Air (16546-Z9006)..... <b>PA2545</b>
CPC15, CWA15 w/NE6T Eng. Lube..... <b>BT234</b>	CW380 (1/96-11/02) F-F Lube (15274-EP025A)..... <b>P7059</b> B-P Lube (15274-EP026A)..... <b>PT8335</b> Fuel (16403-99011)..... <b>BF970 +</b> O. Std. Air (16546-97013)..... <b>PA2676 +</b> O. XP Air (16546-97013)..... <b>PA2676XP +</b> I. Air (16546-97012)..... <b>PA3668</b>	CWA14 w/NE6T Eng. O. Air (16546-Z9004)..... <b>PA2779</b> I. Air (16546-Z9006)..... <b>PA2545</b>
CPCBT w/NE6, NE6T Engs. (1986-88) Lube (15274-99189)..... <b>BT398</b> Fuel (BF40399013)..... <b>BF984</b> O. Air (D6546-Z9007)..... <b>PA2504</b> I. Air (D6546-Z9006)..... <b>PA2545</b> Coolant (FL915-99003)..... <b>BW5073</b>	CW385 w/GE13TB Eng. F-F Lube (15274-99286)..... <b>P7059</b> Fuel/Water Separator (w/Drain) (16403-NY000)..... <b>BF1281</b> Fuel/Water Separator (Open End for Bowl) (16403-NY000)..... <b>BF46018-O</b> Fuel..... <b>BF970 +</b>	CWA15 w/NE6T Eng. O. Air (16546-Z9004)..... <b>PA2779</b> I. Air (16546-Z9006)..... <b>PA2545</b>
CV40, CV41 w/PD6T Eng. Lube (15274-90227)..... <b>P7107</b> Fuel (16444-99128)..... <b>PF7554</b>	CW420 F-F Lube (15274-EP025A)..... <b>P7059</b> B-P Lube (15274-EP026A)..... <b>PT8335</b> Fuel/Water Separator (16444-EP027)..... <b>PF7618</b> Fuel (16403-99011)..... <b>BF970 +</b>	CWA45 w/PE6T Eng. (Australia) F-F Lube (15274-EP025A)..... <b>P7059</b> B-P Lube (15274-EP026A)..... <b>PT8335</b> Std. O. Air (16546-97004)..... <b>PA1846 +</b> O. Air (Upgrade) (16546-97004)..... <b>PA1846XP +</b> I. Air (16546-99508)..... <b>PA1880</b>
CV41 B-P Lube (15274-EP026A)..... <b>PT8335</b> Air (16546-97015)..... <b>LL1884 +</b>	CW440e w/GE13TD Eng. F-F Lube (1527499985)..... <b>P7059</b> Fuel/Water Separator (w/Drain) (16403-NY000)..... <b>BF1281</b> Fuel/Water Separator (Open End for Bowl) (16403-NY000)..... <b>BF46018-O</b> Fuel..... <b>BF970 +</b>	CWA45, CWA45HD, CWA45PH w/PE6T Eng. Lube (15274-99227)..... <b>PT8335</b> Lube (15274-99329)..... <b>P7059</b> Fuel (16444-99129)..... <b>PF7554</b> Std. O. Air (16546-97004)..... <b>PA1846 +</b>
CV56U, CV56V w/RD8, RD8T Engs. Lube (15274-99227)..... <b>PT8335</b> Lube (15274-99329)..... <b>P7059</b> Fuel (16444-99028)..... <b>PF7553</b>	CW445 w/GE13TD Eng. F-F Lube (Chassis # to-205) (1527499985)..... <b>P7059</b> F-F Lube Ele. (15274-99286)..... <b>P7059</b> Fuel/Water Separator (w/Drain) (16403-NY000)..... <b>BF1281</b> Fuel/Water Separator (Open End for Bowl) (16403-NY000)..... <b>BF46018-O</b> Fuel..... <b>BF970 +</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

NISSAN UD Trucks (cont'd)	NISSAN UD Trucks (cont'd)	NISSAN UD Trucks (cont'd)
CWA45, CWA45HD, CWA45PH w/PE6T Eng. (Cont'd)	CWB450 (5/90-5/96)	KG45 Crane w/PE6T Eng.
O. Air (Upgrade) (16546-97004)... PA1846XP +	F-F Lube (15274-EP025A)..... P7059	Lube (15274-EP027)..... PT8335
I. Air (16546-97005)..... PA1880	B-P Lube (15274-EP026A)..... PT8335	I. Air (16546-96014)..... PA1893
CWA46 w/PE6T Eng.	Fuel (16403-99011)..... BF970 +	KG50 Crane w/RD/E8 Eng.
F-F Lube (15274-EP025A)..... P7059	O. Std. Air (16546-97013)..... PA2676 +	Lube (15274-EP027)..... PT8335
B-P Lube (15274-EP026A)..... PT8335	O. XP Air (16546-97013)..... PA2676XP +	P. Fuel (16444EP027A)..... PF7618
Std. O. Air (16546-97004)..... PA1846 +	I. Air (16546-97012)..... PA3668	I. Air (16546-96014)..... PA1893
O. Air (Upgrade) (16546-97004)... PA1846XP +	CWB452 (5/94-5/96)	KG51 Crane w/RD/E8 Eng.
I. Air (16546-99508)..... PA1880	F-F Lube (15274-EP025A)..... P7059	Lube (15274-EP027)..... PT8335
O. Std. Air (16546-97013)..... PA2676 +	B-P Lube (15274-EP026A)..... PT8335	P. Fuel (16444EP027A)..... PF7618
O. XP Air (16546-97013)..... PA2676XP +	Fuel..... BF970 +	I. Air (16546-96014)..... PA1893
I. Air (16546-97012)..... PA3668	O. Std. Air (16546-97013)..... PA2676 +	KG53 Crane w/RD/E8 Eng.
CWA70 w/GD6T Eng.	O. XP Air (16546-97013)..... PA2676XP +	Lube (15274-EP027)..... PT8335
F-F Lube (15274-EP025A)..... P7059	I. Air (16546-97012)..... PA3668	P. Fuel (16444EP027A)..... PF7618
B-P Lube (Small) (15274-EP026)..... PT8335	CWB455 (1/96-11/02)	I. Air (16546-96014)..... PA1893
Std. O. Air (16546-97004)..... PA1846 +	F-F Lube (15274-EP025A)..... P7059	KG54 Crane w/RD/E8 Eng.
O. Air (Upgrade) (16546-97004)... PA1846XP +	B-P Lube (15274-EP026A)..... PT8335	Lube (15274-EP027)..... PT8335
I. Air (16546-99508)..... PA1880	Fuel (16403-99011)..... BF970 +	P. Fuel (16444EP027A)..... PF7618
CWA71 w/GD6T Eng.	O. Std. Air (16546-97013)..... PA2676 +	I. Air (16546-96014)..... PA1893
F-F Lube (15274-EP025A)..... P7059	O. XP Air (16546-97013)..... PA2676XP +	KG60 Crane w/RD10 Eng.
B-P Lube (Small) (15274-EP026)..... PT8335	I. Air (16546-97012)..... PA3668	Lube (15274-EP027)..... PT8335
Std. O. Air (16546-97004)..... PA1846 +	CWB520	P. Fuel (16444EP027A)..... PF7618
O. Air (Upgrade) (16546-97004)... PA1846XP +	F-F Lube (15274-EP025)..... P7059	Std. O. Air (16546-97004)..... PA1846 +
I. Air (16546-99508)..... PA1880	B-P Lube (15274-EP026)..... PT8335	O. Air (Upgrade) (16546-97004)... PA1846XP +
CWA445 w/GE13TD Eng.	Fuel/Water Separator (16444-EP027)..... PF7618	I. Air (16546-99508)..... PA1880
F-F Lube Ele. (15274-99286)..... P7059	Fuel (16444-EP025)..... PF7554	KH60 Crane w/RD10 Eng.
Fuel/Water Separator (w/Drain) (16403-NY000)..... BF1281	O. Air (16546-96071)..... PA2577	Lube (15274-EP027)..... PT8335
Fuel/Water Separator (Open End for Bowl) (16403-NY000)..... BF46018-O	O. Air (1654696064)..... PA2582	P. Fuel (16444EP027A)..... PF7618
Fuel..... BF970 +	CWB545 w/RF8TC Eng.	Std. O. Air (16546-97004)..... PA1846 +
I. Air (17801-2310)..... PA3668	Lube (15274-EP027)..... PT8335	O. Air (Upgrade) (16546-97004)... PA1846XP +
Opt. Trans. (Fuller 17237)..... B2 +	GK400	I. Air (16546-99508)..... PA1880
CWB45	Urea (20421-NY00J)..... PE5270	KW30 Crane w/PE6 Eng.
F-F Lube (15274-EP025)..... P7059	JP251	Lube (15274-EP027)..... PT8335
B-P Lube (15274-EP026)..... PT8335	Fuel/Water Separator (16444-EP027)..... PF7618	O. Air (16546-97015)..... LL1884 +
Fuel/Water Separator (16444-EP027)..... PF7618	K-CD45, K-CF45, K-CK45 w/PE6T Eng.	I. Air (16546-96010)..... PA1911
Fuel (16444-EP025)..... PF7554	Lube (15274-99227)..... PT8335	LK185 w/FE6T Eng.
CWB290 w/PF6T, PF6TA, PF6TB Eng.	Lube (15274-99329)..... P7059	Dual-Flow Lube (15201-EP025A)..... BD1403
Lube (15274-EP027)..... PT8335	Fuel (16444-99129)..... PF7554	Fuel (16403-99011)..... BF970 +
O. Std. Air (16546-97013)..... PA2676 +	O. Air (4/83-5/84) (16546-99203)..... PA2577	Fuel (16444-EP029A)..... PF7554
O. XP Air (16546-97013)..... PA2676XP +	I. Air (4/83-5/84) (16546-99202)... PA2578	Radial Seal O. Air (16546-Z9106)..... RS3710
I. Air (16546-97012)..... PA3668	K-CF30, K-CK31 w/PE6 Eng.	Radial Seal I. Air (16546-Z9101)..... RS3711
CWB320 w/PF6T, PF6TA, PF6TB Eng.	Lube (15274-99227)..... PT8335	LK235 w/FE6T Eng.
Lube (15274-EP027)..... PT8335	Lube (15274-99329)..... P7059	Dual-Flow Lube (15201-EP025A)..... BD1403
O. Std. Air (16546-97013)..... PA2676 +	Fuel (16444-99129)..... PF7554	Fuel (16403-99011)..... BF970 +
O. XP Air (16546-97013)..... PA2676XP +	K-RM80 w/FD6, FD6T Eng.	Fuel (16444-EP029A)..... PF7554
I. Air (16546-97012)..... PA3668	Lube Ele. (15208-Z9025)..... [2] P723	Radial Seal O. Air (16546-Z9106)..... RS3710
CWB350 w/PF6T, PF6TA, PF6TB Eng.	Fuel Ele. (16444-Z9000)..... P7103	Radial Seal I. Air (16546-Z9101)..... RS3711
Lube (15274-EP027)..... PT8335	KG30 Crane w/PE6 Eng.	LK245 w/FE6TB Eng.
O. Std. Air (16546-97013)..... PA2676 +	Lube (15274-EP027)..... PT8335	Dual-Flow Lube (15201-Z9014)... BD1403
O. XP Air (16546-97013)..... PA2676XP +	O. Air (16546-97015)..... LL1884 +	Fuel (16403-NY001)..... BF984
I. Air (16546-97012)..... PA3668	I. Air (16546-96010)..... PA1911	Radial Seal O. Air (16546-Z9106)..... RS3710
		Radial Seal I. Air (16546-Z9101)..... RS3711

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

NISSAN UD Trucks (cont'd)	NISSAN UD Trucks (cont'd)	NISSAN UD Trucks (cont'd)
<b>LK246</b> <b>Dual-Flow Lube</b> (15201-Z9014).. <b>BD1403</b> <b>Fuel/Water Separator</b> (16444-EP027)..... <b>PF7618</b> <b>Fuel</b> (16403-NY001)..... <b>BF984</b> <b>Radial Seal O. Air</b> (16546-Z9106)..... <b>RS3710</b> <b>Radial Seal I. Air</b> (16546-Z9101). <b>RS3711</b>	<b>MK180 w/FE6T Eng.</b> <b>Dual-Flow Lube</b> (15201-EP025A)..... <b>BD1403</b> <b>Fuel</b> (16403-99011)..... <b>BF970 +</b> <b>Fuel</b> (16444-EP029A)..... <b>PF7554</b> <b>Radial Seal O. Air</b> (16546-Z9106)..... <b>RS3710</b> <b>Radial Seal I. Air</b> (16546-Z9101). <b>RS3711</b>	<b>MK265 w/FE6TA Eng.</b> <b>Dual-Flow Lube</b> (15201-EP025).. <b>BD1403</b> <b>Fuel/Water Separator</b> (16444-EP027)..... <b>PF7618</b> <b>Fuel</b> (16403-NY001)..... <b>BF984</b> <b>Radial Seal O. Air</b> (16546-Z9106)..... <b>RS3710</b> <b>Radial Seal I. Air</b> (16546-Z9101). <b>RS3711</b>
<b>LK265</b> <b>Dual-Flow Lube</b> (15201-Z9014).. <b>BD1403</b> <b>Fuel/Water Separator</b> (16444-EP027)..... <b>PF7618</b> <b>Fuel</b> (16403-NY001)..... <b>BF984</b> <b>Radial Seal O. Air</b> (16546-Z9106)..... <b>RS3710</b> <b>Radial Seal I. Air</b> (16546-Z9101). <b>RS3711</b>	<b>MK185 w/FE6T Eng.</b> <b>Dual-Flow Lube</b> (15201-EP025A)..... <b>BD1403</b> <b>Fuel</b> (16403-99011)..... <b>BF970 +</b> <b>Fuel</b> (16444-EP029A)..... <b>PF7554</b> <b>Radial Seal O. Air</b> (16546-Z9106)..... <b>RS3710</b> <b>Radial Seal I. Air</b> (16546-Z9101). <b>RS3711</b>	<b>PK9</b> <b>Radial Seal Air</b> (Standard) (16546-NY108)..... <b>RS2863</b> <b>Radial Seal XP Air</b> (Upgrade) (16546-NY108)..... <b>RS2863XP</b>
<b>MK5</b> <b>Radial Seal Air</b> (Standard) (16546-NY108)..... <b>RS2863</b> <b>Radial Seal XP Air</b> (Upgrade) (16546-NY108)..... <b>RS2863XP</b>	<b>MK190 w/FE6T Eng.</b> <b>Dual-Flow Lube</b> (15201-EP025A)..... <b>BD1403</b> <b>Fuel</b> (16403-99011)..... <b>BF970 +</b> <b>Fuel</b> (16444-EP029A)..... <b>PF7554</b> <b>Radial Seal O. Air</b> (16546-Z9106)..... <b>RS3710</b> <b>Radial Seal I. Air</b> (16546-Z9101). <b>RS3711</b>	<b>PK10</b> <b>Radial Seal Air</b> (Standard) (16546-NY108)..... <b>RS2863</b> <b>Radial Seal XP Air</b> (Upgrade) (16546-NY108)..... <b>RS2863XP</b>
<b>MK6</b> <b>Radial Seal Air</b> (Standard) (16546-NY108)..... <b>RS2863</b> <b>Radial Seal XP Air</b> (Upgrade) (16546-NY108)..... <b>RS2863XP</b>	<b>MK225 w/FE6T Eng.</b> <b>Dual-Flow Lube</b> (15201-EP025A)..... <b>BD1403</b> <b>Fuel</b> (16403-99011)..... <b>BF970 +</b> <b>Fuel</b> (16444-EP029A)..... <b>PF7554</b> <b>Radial Seal O. Air</b> (16546-Z9106)..... <b>RS3710</b> <b>Radial Seal I. Air</b> (16546-Z9101). <b>RS3711</b>	<b>PK220 w/FE6TA Eng.</b> <b>Dual-Flow Lube</b> (15201-EP025).. <b>BD1403</b> <b>Fuel</b> (16444-EP029A)..... <b>PF7554</b> <b>O. Air</b> (16546-99316)..... <b>PA2577</b>
<b>MK130 w/FD46TA Eng.</b> <b>F-F Lube</b> (15209-0T000)..... <b>B236 +</b> <b>Fuel/Water Separator</b> (16405-01T70)..... <b>BF46148</b> <b>Fuel</b> (16403-Z9000)..... <b>BF954 +</b> <b>O. Air</b> (17801-2070)..... <b>PA2779</b> <b>I. Air</b> (1-14215145-0)..... <b>PA2545</b>	<b>MK235 w/FE6T Eng.</b> <b>Dual-Flow Lube</b> (15201-EP025A)..... <b>BD1403</b> <b>Fuel</b> (16403-99011)..... <b>BF970 +</b> <b>Fuel</b> (16444-EP029A)..... <b>PF7554</b> <b>Radial Seal O. Air</b> (16546-Z9106)..... <b>RS3710</b> <b>Radial Seal I. Air</b> (16546-Z9101). <b>RS3711</b>	<b>PK235 w/FE6TA Eng.</b> <b>Dual-Flow Lube</b> (15201-EP025A)..... <b>BD1403</b> <b>Fuel</b> (16444-EP029A)..... <b>PF7554</b> <b>Radial Seal O. Air</b> (16546-Z9106)..... <b>RS3710</b> <b>Radial Seal I. Air</b> (16546-Z9101). <b>RS3711</b>
<b>MK150 w/FD46TA Eng.</b> <b>F-F Lube</b> (15209-0T000)..... <b>B236 +</b> <b>Fuel/Water Separator</b> (16405-01T70)..... <b>BF46148</b> <b>Fuel</b> (16403-Z9000)..... <b>BF954 +</b> <b>O. Air</b> (17801-2070)..... <b>PA2779</b> <b>I. Air</b> (1-14215145-0)..... <b>PA2545</b>	<b>MK240 w/FE6TA Eng.</b> <b>Dual-Flow Lube</b> (15201-EP025).. <b>BD1403</b> <b>Fuel/Water Separator</b> (16444-EP027)..... <b>PF7618</b> <b>Fuel</b> (16403-NY001)..... <b>BF984</b> <b>Radial Seal O. Air</b> (16546-Z9106)..... <b>RS3710</b> <b>Radial Seal I. Air</b> (16546-Z9101). <b>RS3711</b>	<b>PK240 w/NE6TA Eng.</b> <b>Dual-Flow Lube</b> (15201-EP025A)..... <b>BD1403</b> <b>Fuel</b> (16403-99011)..... <b>BF970 +</b> <b>O. Air</b> (16546-99316)..... <b>PA2577</b>
<b>MK170 w/FD46TA Eng.</b> <b>F-F Lube</b> (15209-0T000)..... <b>B236 +</b> <b>Fuel</b> ..... <b>BF970 +</b> <b>O. Air</b> (17801-2070)..... <b>PA2779</b> <b>I. Air</b> (1-14215145-0)..... <b>PA2545</b>	<b>MK245 w/FE6TA Eng.</b> <b>Dual-Flow Lube</b> (15201-EP025).. <b>BD1403</b> <b>Fuel/Water Separator</b> (16444-EP027)..... <b>PF7618</b> <b>Fuel</b> (16403-NY001)..... <b>BF984</b> <b>Radial Seal O. Air</b> (16546-Z9106)..... <b>RS3710</b> <b>Radial Seal I. Air</b> (16546-Z9101). <b>RS3711</b>	<b>PK245 w/FE6TB/C Eng.</b> <b>Dual-Flow Lube</b> (15201-EP025).. <b>BD1403</b> <b>Fuel</b> (16403-NY001)..... <b>BF984</b> <b>O. Air</b> (16546-99316)..... <b>PA2577</b>
<b>MK175 w/FD46TA Eng.</b> <b>F-F Lube</b> (15208-29D00)..... <b>B120</b> <b>F-F Lube</b> (15209-0T000)..... <b>B236 +</b> <b>Fuel</b> ..... <b>BF970 +</b> <b>O. Air</b> (17801-2070)..... <b>PA2779</b> <b>I. Air</b> (1-14215145-0)..... <b>PA2545</b>	<b>MK245 w/FE6TA Eng.</b> <b>Dual-Flow Lube</b> (15201-EP025).. <b>BD1403</b> <b>Fuel/Water Separator</b> (16444-EP027)..... <b>PF7618</b> <b>Fuel</b> (16403-NY001)..... <b>BF984</b> <b>Radial Seal O. Air</b> (16546-Z9106)..... <b>RS3710</b> <b>Radial Seal I. Air</b> (16546-Z9101). <b>RS3711</b>	<b>PK250 w/NE6TA Eng.</b> <b>Dual-Flow Lube</b> (15201-EP025A)..... <b>BD1403</b> <b>Fuel</b> (16403-99011)..... <b>BF970 +</b> <b>O. Air</b> (16546-99316)..... <b>PA2577</b>
<b>MK175T w/FD46TA Eng.</b> <b>F-F Lube</b> (15209-0T000)..... <b>B236 +</b> <b>Fuel</b> ..... <b>BF970 +</b> <b>O. Air</b> (17801-2070)..... <b>PA2779</b> <b>I. Air</b> (1-14215145-0)..... <b>PA2545</b>	<b>MK245 w/FE6TA Eng.</b> <b>Dual-Flow Lube</b> (15201-EP025).. <b>BD1403</b> <b>Fuel/Water Separator</b> (16444-EP027)..... <b>PF7618</b> <b>Fuel</b> (16403-NY001)..... <b>BF984</b> <b>Radial Seal O. Air</b> (16546-Z9106)..... <b>RS3710</b> <b>Radial Seal I. Air</b> (16546-Z9101). <b>RS3711</b>	<b>PK255 w/FE6TC Eng.</b> <b>Dual-Flow Lube</b> (15201-EP025A)..... <b>BD1403</b> <b>Fuel/Water Separator</b> (16444-EP027)..... <b>PF7618</b> <b>Fuel</b> (16403-NY001)..... <b>BF984</b> <b>O. Air</b> (16546-99316)..... <b>PA2577</b>
	<b>MK265 w/FE6TA Eng.</b> <b>Dual-Flow Lube</b> (15201-EP025).. <b>BD1403</b> <b>Fuel/Water Separator</b> (16444-EP027)..... <b>PF7618</b> <b>Fuel</b> (16403-NY001)..... <b>BF984</b> <b>Radial Seal O. Air</b> (16546-Z9106)..... <b>RS3710</b> <b>Radial Seal I. Air</b> (16546-Z9101). <b>RS3711</b>	<b>PK265 w/FE6TB/C Eng.</b> <b>Dual-Flow Lube</b> (15201-EP025).. <b>BD1403</b> <b>Fuel/Water Separator</b> (16444-EP027)..... <b>PF7618</b> <b>Fuel</b> (16403-NY001)..... <b>BF984</b> <b>O. Air</b> (16546-99316)..... <b>PA2577</b>

+ See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.


**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).





NISSAN UD Trucks (cont'd)	NISSAN UD Trucks (cont'd)	ONAN RV Generators (cont'd)
UD2300LP w/FE6TA (6.9L) Eng. (2001-04) (Cont'd) Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>	UD2600 w/MD-230 (J08E-TE) Eng. (2011-12) (Cont'd) Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Diesel Exhaust Fluid</b> (5282269261)..... <b>PE17001</b>	BGA RV Lube (122-0645)..... <b>BT223</b> Air (140-0495)..... <b>PA675</b>
UD2300LP w/MD-230 (J08E-TE) (7.7L) Eng. (2008-10) Dual-Flow Lube (BF209Z5001)... <b>BD7325</b> Fuel/Water Separator (w/o Sensor Port) (RK444Z5002)..... <b>BF1360</b> Fuel/Water Separator (w/Sensor Port) (RK444Z5002)..... <b>BF1360-SP</b> Fuel/Water Separator (Open End for Bowl) (RK444Z5002)..... <b>BF1360-O</b> Radial Seal XP Air (D6546NY108)..... <b>RS30222XP</b> Cab Air (Recirculation) (2721330Z00)..... <b>CLN&amp;R</b> Cab Air (Fresh Air) (2721300Z06)..... <b>CLN&amp;R</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>	UD3300 w/MD-230 (J08E-TE) Eng. (2011-12) Radial Seal XP Air (D6546NY108)..... <b>RS30222XP</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Diesel Exhaust Fluid</b> (5282269261)..... <b>PE17001</b>	BGAL Lube (122-0645)..... <b>BT223</b> Air (140-0495)..... <b>PA675</b> BGAL RV Lube (122-0645)..... <b>BT223</b> Air (140-0495)..... <b>PA675</b> BGE Lube (122-0645)..... <b>BT223</b> Fuel (Eng. Spec Letter H) (149-1353)..... <b>BF879</b> Air (140-2379)..... <b>PA4557</b> BGM Lube (122-0645)..... <b>BT223</b> Fuel (Eng. Spec Letter G, H) (149-2341)..... <b>BF46242</b> Air (140-2379)..... <b>PA4557</b> BGEL Lube (122-0645)..... <b>BT223</b> Air (140-2379)..... <b>PA4557</b>
UD2300LP w/MD-230 (J08E-TE) Eng. (2011-12) Radial Seal XP Air (D6546NY108)..... <b>RS30222XP</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>	<b>NORTH AMERICAN BUS INDUSTRIES (NABI)</b> <b>Buses</b> 40 Foot w/CNG Eng. (1998-2001) Dual-Flow Lube..... <b>BD103 +</b> Fuel Coalescer..... <b>BF7695</b> Air..... <b>PA2525</b> Coolant..... <b>B5134 +</b>	CCK Mobile/RV Lube (122-0800)..... <b>B7020</b> Air (Eng. Spec Letters R, S, T, U) (140-0495)..... <b>PA675</b>
UD2300LP w/MD-230 (J08E-TE) Eng. (2011-12) Radial Seal XP Air (D6546NY108)..... <b>RS30222XP</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> <b>Diesel Exhaust Fluid</b> (5282269261)..... <b>PE17001</b>	<b>ONAN</b> <b>RV Generators</b> AJ Fuel (149-1353)..... <b>BF879</b> Air (140-1188)..... <b>PA1712</b> BF Power Drawer Lube (122-0645)..... <b>BT223</b> BF RV Air (140-0495)..... <b>PA675</b> BFA Air (140-0495)..... <b>PA675</b> BFA AUX Lube (122-0800)..... <b>B7020</b> Air (140-0495)..... <b>PA675</b> BFA RV Lube (122-0645)..... <b>BT223</b> Air (140-0495)..... <b>PA675</b> BGA Lube (122-0645)..... <b>BT223</b> Air (140-0495)..... <b>PA675</b>	CMSD 5.0 (HDKAS) w/Kubota D905 Eng. Lube (185-5835)..... <b>B161-S</b> Fuel/Water Separator (149-2106)..... <b>BF1267</b> Radial Seal Air (140-3071)..... <b>RS3715</b> CMSD 6.0 (HDKAS) w/Kubota D905 Eng. Lube (185-5835)..... <b>B161-S</b> Fuel/Water Separator (149-2106)..... <b>BF1267</b> Radial Seal Air (140-3071)..... <b>RS3715</b> CMSD 6.0 (HDKAL) w/Kubota D1105 Eng. Lube (185-5835)..... <b>B161-S</b> Fuel/Water Separator (149-2106)..... <b>BF1267</b> Radial Seal Air (140-3071)..... <b>RS3715</b> CMSD 7.5 (HDKAL) w/Kubota D1105 Eng. Lube (185-5835)..... <b>B161-S</b> Fuel/Water Separator (149-2106)..... <b>BF1267</b> Radial Seal Air (140-3071)..... <b>RS3715</b> CMSD 8.0 w/Kubota D1305 Eng. Lube (185-5835)..... <b>B161-S</b> Fuel/Water Separator (149-2106)..... <b>BF1267</b> Air (140-2842)..... <b>PA1865-FN</b> CMSD 10.0 w/Kubota D1305 Eng. Lube (185-5835)..... <b>B161-S</b> Fuel/Water Separator (149-2106)..... <b>BF1267</b> Air (140-2842)..... <b>PA1865-FN</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

ONAN RV Generators (cont'd)	ONAN RV Generators (cont'd)	ONAN RV Generators (cont'd)
<b>CMQD 5500, QuietDiesel 5500 w/Kubota Z482 Eng.</b> <b>Lube (185-7444)..... B1400</b> <b>Fuel/Water Separator (149-2513)..... BF806</b> <b>Air (140-3351)..... PA30050</b>	<b>DKD RV</b> <b>Lube (122-0827)..... B179</b> <b>Fuel/Water Separator (Eng. Spec Letters A, B) (149-1914-05)..... BF1253</b> <b>Fuel/Water Separator (Eng. Spec Letters C, D, E) (149-2106)..... BF1267</b> <b>Air (140-2842)..... PA1865-FN</b>	<b>HDKAQ</b> <b>Lube (185-5835)..... B161-S</b> <b>Fuel/Water Separator (149-2106)..... BF1267</b> <b>Radial Seal Air (140-3071)..... RS3715</b>
<b>CMQD 7500, QuietDiesel 7500 w/Kubota D722 Eng.</b> <b>Lube (122-0833)..... B227</b> <b>Fuel/Water Separator (149-2513)..... BF806</b> <b>Air (140-2897)..... PA5658</b>	<b>DKG</b> <b>Lube (122-0827)..... B179</b> <b>Fuel/Water Separator (149-2106)..... BF1267</b> <b>Air (140-2680)..... PA4619</b>	<b>HDKAR</b> <b>Lube (185-5835)..... B161-S</b> <b>Fuel/Water Separator (149-2106)..... BF1267</b> <b>Radial Seal Air (140-3071)..... RS3715</b>
<b>CMQD 8000, QuietDiesel 8000 w/Kubota D722 Eng.</b> <b>Lube (122-0833)..... B227</b> <b>Fuel/Water Separator (149-2513)..... BF806</b> <b>Air (140-2897)..... PA5658</b>	<b>HDCAA</b> <b>Lube (187-1000)..... B179</b> <b>Fuel/Water Separator (149-2513)..... BF806</b> <b>Radial Seal Air (140-3071)..... RS3715</b>	<b>HDKAS</b> <b>Lube (185-5835)..... B161-S</b> <b>Fuel/Water Separator (149-2106)..... BF1267</b> <b>Radial Seal Air (140-3071)..... RS3715</b>
<b>CMQD 10000 (HDKA) w/Kubota Eng.</b> <b>Lube (122-0810)..... B233</b> <b>Fuel/Water Separator (149-2513)..... BF806</b>	<b>HDCAB</b> <b>Lube (187-1000)..... B179</b> <b>Fuel/Water Separator (149-2513)..... BF806</b> <b>Radial Seal Air (140-3071)..... RS3715</b>	<b>HDKBA</b> <b>Fuel/Water Separator (149-2513)..... BF806</b> <b>Air (140-3351)..... PA30050</b>
<b>CMQD 12000 (HDCA) w/Kubota Eng.</b> <b>Lube (122-0810)..... B233</b> <b>Fuel/Water Separator (149-2513)..... BF806</b> <b>Radial Seal Air (140-3071)..... RS3715</b>	<b>HDCAC</b> <b>Lube (187-1000)..... B179</b> <b>Box-Style Fuel/Water Separator (149-2513)..... BF806</b>	<b>HDKCA</b> <b>Lube (122-0893)..... B7152</b> <b>Box-Style Fuel/Water Separator (149-2513)..... BF806</b> <b>Radial Seal Air (140-3071)..... RS3715</b>
<b>CMQD 12000 (HDKC) w/Kubota Eng.</b> <b>Lube (122-0810)..... B233</b> <b>Fuel/Water Separator (149-2513)..... BF806</b>	<b>HDKAG</b> <b>Lube (185-5835)..... B161-S</b> <b>Fuel/Water Separator (149-2106)..... BF1267</b> <b>Air (140-2842)..... PA1865-FN</b>	<b>HDKCB</b> <b>Lube (122-0893)..... B7152</b> <b>Box-Style Fuel/Water Separator (149-2513)..... BF806</b> <b>Radial Seal Air (140-3071)..... RS3715</b>
<b>CNQD 10000 (HDCA) w/Kubota Eng.</b> <b>Lube (187-1000)..... B179</b> <b>Fuel/Water Separator (149-2513)..... BF806</b> <b>Radial Seal Air (140-3071)..... RS3715</b>	<b>HDKAH</b> <b>Lube (122-0833)..... B227</b> <b>Fuel/Water Separator (149-2513)..... BF806</b> <b>Radial Seal Air (140-3071)..... RS3715</b>	<b>HGJAA</b> <b>Lube (Eng. Spec Letters A, B, C) (122-0836)..... B7238</b> <b>Fuel (Gas Eng. Spec Letter A) (149-2341-01)..... BF46242</b> <b>Fuel (Eng. Spec Letter D) (147-0860)..... BF1049</b> <b>Air (140-3116)..... PA5733</b>
<b>DKC</b> <b>Lube (122-0827)..... B179</b> <b>Fuel/Water Separator (Eng. Spec Letter A) (149-1914-05)..... BF1253</b> <b>Fuel/Water Separator (Eng. Spec Letter B) (149-2106)..... BF1267</b> <b>Air (140-2842)..... PA1865-FN</b>	<b>HDKAJ</b> <b>Lube (Eng. Spec Letters A,B,C,D,E,F,G,H) (122-0833)..... B227</b> <b>Fuel/Water Separator (Eng. Spec Letters A,B,C,D,E,F,G,H) (149-2513)..... BF806</b> <b>Air (Eng. Spec Letters A,B,C,D,E,H,K) (140-2897)..... PA5658</b>	<b>HGJAB</b> <b>Lube (Gas Eng.) (122-0836)..... B7238</b> <b>Lube (LPG Eng. Spec Letters A, B) (122-0836)..... B7238</b> <b>Fuel (Gas Eng.) (149-2341-01)..... BF46242</b> <b>Air (Eng. Spec Letters A, B, C) (140-3116)..... PA5733</b>
<b>DKC RV</b> <b>Lube (122-0827)..... B179</b> <b>Fuel/Water Separator (149-1914-05)..... BF1253</b> <b>Air (140-2842)..... PA1865-FN</b>	<b>HDKAK</b> <b>Lube (Eng. Spec Letters A,B,C,D,E,F,G,H) (122-0833)..... B227</b> <b>Fuel/Water Separator (Eng. Spec Letter A,B,C,D,E,F,G,H,K) (149-2513)..... BF806</b> <b>Air (140-2897)..... PA5658</b>	<b>HGJAC</b> <b>Lube (122-0836)..... B7238</b> <b>Fuel (Gas Eng.) (149-2341-01)..... BF46242</b> <b>Air (140-3116)..... PA5733</b>
<b>DKD</b> <b>Lube (122-0827)..... B179</b> <b>Fuel/Water Separator (Eng. Spec Letters A, B) (149-1914-05)..... BF1253</b> <b>Fuel/Water Separator (Eng. Spec Letters C, D, E) (149-2106)..... BF1267</b> <b>Air (140-2842)..... PA1865-FN</b>	<b>HDKAL</b> <b>Lube (185-5835)..... B161-S</b> <b>Fuel/Water Separator (149-2106)..... BF1267</b> <b>Radial Seal Air (140-3071)..... RS3715</b>	<b>KV</b> <b>Lube (Eng. Spec Letter A) (122-0836)..... B7238</b> <b>Air (Eng. Spec Letter A) (140-3116)..... PA5733</b>

Check Original Equipment Numbers In Parentheses.




**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

ONAN RV Generators (cont'd)	OPEL European Light Duty Vehicles	OPEL European Light Duty Vehicles (cont'd)
LK RV Fuel (149-1353)..... <b>BF879</b>	Combo 1.6 CDTI (X12) w/A16FDH Eng. (02/12-on) Cabin Air (1808029)..... <b>PA10085</b>	Combo D 1.6 CDTI (X12) w/A16FDL Eng. (02/12-on) Lube (650181)..... <b>P40114</b> Fuel (818020)..... <b>BF46051</b> Cabin Air (Left Hand Drive) (1808029)..... <b>PA10085</b>
NH Lube (122-0800)..... <b>B7020</b> Air (140-0495)..... <b>PA675</b>	Combo 1.6 CDTI (X12) w/A16FDL Eng. (02/12-on) Cabin Air (1808029)..... <b>PA10085</b>	Combo D 1.6 CDTI (X12) w/A20FD Eng. (02/12-on) Lube (650181)..... <b>P40114</b> Fuel (818020)..... <b>BF46051</b> Cabin Air (Left Hand Drive) (1808029)..... <b>PA10085</b>
NH Power Drawer Lube (122-0800)..... <b>B7020</b>	Combo 2.0 CDTI (X12) w/A20FD Eng. (02/12-on) Cabin Air (1808029)..... <b>PA10085</b>	Combo B 1.3 CDTI w/Z13DT Eng. (06/04-01/06) Lube (5650367)..... <b>P40058</b> Cab Air (1808619)..... <b>PA10177</b>
NH RV Lube (Eng. Spec Letters A-C, E-H, J-R) (122-0800)..... <b>B7020</b> Air (140-0495)..... <b>PA675</b>	Combo B 1.3 CDTI w/Z13DTJ Eng. (12/05-on) Lube (5650367)..... <b>P40058</b> Cab Air (1808619)..... <b>PA10177</b>	Movano A 1.9 CDTI (Diesel Purflux H.86) w/F9Q 774 Eng. (11/03-on) Fuel (4412830)..... <b>PF46112</b>
NHE Lube (122-0800)..... <b>B7020</b> Fuel (Eng. Spec Letter H) (149-1353)..... <b>BF879</b> Air (140-2379)..... <b>PA4557</b>	Combo B 1.4 16V w/Z14XEP Eng. (06/04-on) Lube (5650359)..... <b>P7489</b> Fuel (818509)..... <b>BF1185</b> Cab Air (1808619)..... <b>PA10177</b>	Movano A 1.9 CDTI (Diesel Purflux H.120) w/F9Q 774 Eng. (11/03-on) Fuel (4411637)..... <b>PF9801</b> <sup>90</sup>
NHEL Lube (122-0800)..... <b>B7020</b> Air (140-2379)..... <b>PA4557</b>	Combo B 1.6 w/Z16SE Eng. (09/01-08/04) Fuel (818509)..... <b>BF1185</b> Cab Air (1808619)..... <b>PA10177</b>	Movano A 1.9 DTI w/F9Q-772/774 Eng. (10/01-06/10) Fuel (4412830)..... <b>PF46112</b> Fuel (4411637)..... <b>PF9801</b> <sup>90</sup>
NHL Lube (122-0800)..... <b>B7020</b> Air (140-0495)..... <b>PA675</b>	Combo B 1.6 CNG w/Y/Z16YNG Eng. (06/05-on) Fuel (818509)..... <b>BF1185</b> Cab Air (1808619)..... <b>PA10177</b>	Movano A 1.9 DTI w/F9QT770 Eng. (09/00-12/03) Lube (4402718)..... <b>B7276</b> Air (4416403)..... <b>PA4319</b> <sup>90</sup>
NHM w/Gas Eng. Lube (122-0800)..... <b>B7020</b> Fuel (Eng. Spec Letter G, H) (149-2341)..... <b>BF46242</b> Air (140-2379)..... <b>PA4557</b>	Combo B 1.7 CDTI w/Z17DTH Eng. (06/04-on) Cab Air (1808619)..... <b>PA10177</b>	Movano A 1.9 DTI (Bosch Injection System) w/F9QT772 Eng. (11/01-12/03) Lube (4402718)..... <b>B7276</b> Fuel (4411637)..... <b>PF9801</b> <sup>90</sup>
NHM w/LPG Eng. Lube (122-0800)..... <b>B7020</b> Air (140-2379)..... <b>PA4557</b>	Combo B 1.7 DI w/Y17DLT Eng. (09/01-08/04) Cab Air (1808619)..... <b>PA10177</b>	Movano A 1.9 DTI (CAV Injection System) w/F9QT772 Eng. (11/01-12/03) Lube (4402718)..... <b>B7276</b>
NH Power Drawer 9000 Lube (122-0800)..... <b>B7020</b>	Combo B 1.7 DTI w/Y17DT Eng. (09/01-08/04) Cab Air (1808619)..... <b>PA10177</b>	Movano A 2.2 CDTI w/G9T 720 Eng. (11/03-on) Lube (4506039)..... <b>P7455</b> Fuel (4411637)..... <b>PF9801</b> <sup>90</sup>
QuietDiesel 10000 (HDKC) w/Kubota Eng. Lube (122-0810)..... <b>B233</b> Fuel/Water Separator (149-2513)..... <b>BF806</b> Radial Seal Air (140-3071)..... <b>RS3715</b>	Combo D 1.3 CDTI (X12) w/A13FD Eng. (02/12-on) Fuel (818020)..... <b>BF46051</b> Cabin Air (Left Hand Drive) (1808029)..... <b>PA10085</b>	Movano A 2.2 DTI w/G9T-720/722/750 Eng. (09/00-06/10) Lube (4415941)..... <b>P7455</b> Fuel (4412830)..... <b>PF46112</b> Fuel (4411637)..... <b>PF9801</b> <sup>90</sup>
QuietDiesel 10000 (HDCA) w/Kubota Eng. Lube (187-1000)..... <b>B179</b> Fuel/Water Separator (149-2513)..... <b>BF806</b> Radial Seal Air (140-3071)..... <b>RS3715</b>	Combo D 1.4 (X12) w/A14FP Eng. (02/12-on) Lube (649007)..... <b>B7441</b> Cabin Air (Left Hand Drive) (1808029)..... <b>PA10085</b>	Movano A 2.2 DTI w/G9T-720/722/750 Eng. (09/00-06/10) Lube (4506039)..... <b>P7455</b> Fuel (4412830)..... <b>PF46112</b> Fuel (4411637)..... <b>PF9801</b> <sup>90</sup>
QuietDiesel 12500 (HDCA) w/Kubota Eng. Lube (187-1000)..... <b>B179</b> Fuel/Water Separator (149-2513)..... <b>BF806</b> Radial Seal Air (140-3071)..... <b>RS3715</b>	Combo D 1.4 CNG (X12) w/A14FC Eng. (02/12-on) Lube (5650342)..... <b>P9605</b> Cabin Air (Left Hand Drive) (1808029)..... <b>PA10085</b>	Movano A 2.2 DTI w/G9TT720 Eng. (09/00-12/03) Lube (4415941)..... <b>P7455</b>
QuietDiesel 12500 (HDKC) w/Kubota Eng. Lube (122-0810)..... <b>B233</b> Fuel/Water Separator (149-2513)..... <b>BF806</b> Radial Seal Air (140-3071)..... <b>RS3715</b>	Combo D 1.6 CDTI (X12) w/A16FDH Eng. (02/12-on) Lube (650181)..... <b>P40114</b> Fuel (818020)..... <b>BF46051</b> Cabin Air (Left Hand Drive) (1808029)..... <b>PA10085</b>	Movano A 2.5 CDTI w/G9U 750/720 Eng. (11/03-07/06) Lube (4415941)..... <b>P7455</b> Fuel (4412830)..... <b>PF46112</b> Fuel (4411637)..... <b>PF9801</b> <sup>90</sup>

<sup>90</sup> Obsolete Pending.

Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

OPEL European Light Duty Vehicles (cont'd)	OPEL European Light Duty Vehicles (cont'd)	OPEL European Light Duty Vehicles (cont'd)
Movano A 2.5 CDTI w/G9U 754 Eng. (11/03-07/06) Lube (4415941)..... <b>P7455</b> Fuel (4412830)..... <b>PF46112</b> Fuel (4411637)..... <b>PF9801</b> <sup>90</sup>	Movano B 2.3 CDTI 125 w/M9T676/686/690/692/696/698 Eng. (04/10-on) Fuel (4411637)..... <b>PF9801</b> <sup>90</sup>	Vivaro 1.9 CDTI/DTI w/F9Q760 Eng. (03/01-08/06) Fuel (4412830)..... <b>PF46112</b> Fuel (4411637)..... <b>PF9801</b> <sup>90</sup> Air (4416403)..... <b>PA4319</b> <sup>90</sup>
Movano A 2.5 CDTI w/G9U750/754 Eng. (11/03-on) Lube (4415941)..... <b>P7455</b> Fuel (4411637)..... <b>PF9801</b> <sup>90</sup>	Movano B 2.3 CDTI 150 w/M9T678/680/686/694/696/698 Eng. (04/10-on) Fuel (4411637)..... <b>PF9801</b> <sup>90</sup>	Vivaro 1.9 DI w/F9Q 760 Eng. (03/01-08/04) Lube (4402718)..... <b>B7276</b> Fuel (4412830)..... <b>PF46112</b> Air (4416403)..... <b>PA4319</b> <sup>90</sup>
Movano A 2.5 CDTI w/G9U 754 Eng. (11/03-07/06) Lube (4415941)..... <b>P7455</b> Fuel (4412830)..... <b>PF46112</b> Fuel (4411637)..... <b>PF9801</b> <sup>90</sup>	Movano I 1.9 DTI w/F9QT770 Eng. (09/00-12/03) Lube (4402718)..... <b>B7276</b> Air (4416403)..... <b>PA4319</b> <sup>90</sup>	Vivaro 1.9 DTI w/F9Q 760 Eng. (03/01-on) Lube (4402718)..... <b>B7276</b> Fuel (4412830)..... <b>PF46112</b> Air (4416403)..... <b>PA4319</b> <sup>90</sup>
Movano A 2.5 CDTI 100 w/G9U 650 Eng. (7/06-06/10) Lube (4415941)..... <b>P7455</b> Fuel (4412830)..... <b>PF46112</b> Fuel (4411637)..... <b>PF9801</b> <sup>90</sup>	Movano I 2.5 D w/S8U Eng. (03/98-12/03) Dual-Flow Lube (4402665)..... <b>BD232</b>	Vivaro 1.9 DTI/CDTI w/F9Q 760 Eng. (09/04-on) Lube (4402718)..... <b>B7276</b> Fuel (4412830)..... <b>PF46112</b> Air (4416403)..... <b>PA4319</b> <sup>90</sup>
Movano A 2.5 CDTI 120 w/G9U 650 Eng. (7/06-06/10) Lube (4415941)..... <b>P7455</b> Fuel (4412830)..... <b>PF46112</b> Fuel (4411637)..... <b>PF9801</b> <sup>90</sup>	Movano I 2.5 DTI w/G9U-720 Eng. (09/01-12/03) Lube (4506039)..... <b>P7455</b>	Vivaro 2.0 16V w/F4R Eng. (09/06-on) Lube (4402718)..... <b>B7276</b>
Movano A 2.5 CDTI 150 w/G9U 632 Eng. (7/06-06/10) Lube (4415941)..... <b>P7455</b> Fuel (4412830)..... <b>PF46112</b> Fuel (4411637)..... <b>PF9801</b> <sup>90</sup>	Movano I 2.8 DTI w/S9W Eng. (03/98-12/03) Dual-Flow Lube (4402665)..... <b>BD232</b>	Vivaro 2.0 16V w/F4RL7, F4R720 Eng. (03/01-on) Lube (4402718)..... <b>B7276</b>
Movano A 2.5 D w/S8U (Sofim) Eng. (03/98-12/03) Dual-Flow Lube (4402665)..... <b>BD232</b>	Movano II 1.9 CDTI (Diesel Purflux H.120) w/F9Q 774 Eng. (11/03-on) Lube (4402718)..... <b>B7276</b> Fuel (4411637)..... <b>PF9801</b> <sup>90</sup>	Vivaro 2.0 CDTI 90 w/M9R-780 Eng. (09/06-on) Fuel (4412830)..... <b>PF46112</b> Fuel (4411637)..... <b>PF9801</b> <sup>90</sup>
Movano A 2.5 DTI w/G9U-720/724/754 Eng. (09/01-12/03) Lube (4415941)..... <b>P7455</b> Fuel (4412830)..... <b>PF46112</b> Fuel (4411637)..... <b>PF9801</b> <sup>90</sup>	Movano II 1.9 CDTI (Diesel Purflux H.86) w/F9Q 774 Eng. (11/03-on) Fuel (4412830)..... <b>PF46112</b> Fuel (4411637)..... <b>PF9801</b> <sup>90</sup>	Vivaro 2.0 CDTI 115 w/M9R-780 Eng. (09/06-on) Fuel (4411637)..... <b>PF9801</b> <sup>90</sup>
Movano A 2.5 DTI w/G9U-720 Eng. (09/01-12/03) Lube (4415941)..... <b>P7455</b>	Movano II 2.5 CDTI w/G9U750/754 Eng. (11/03-on) Lube (4506039)..... <b>P7455</b> Fuel (4411637)..... <b>PF9801</b> <sup>90</sup>	Vivaro 2.5 CDTI 150 w/G9U-630/632 Eng. (09/06-on) Fuel (4412830)..... <b>PF46112</b> Fuel (4411637)..... <b>PF9801</b> <sup>90</sup>
Movano A 2.8 DTI w/S9W (Sofim) Eng. (03/98-12/03) Dual-Flow Lube (4402665)..... <b>BD232</b>	Movano II 2.5 CDTI 100 w/100 HP Eng. (07/06-on) Lube (4506039)..... <b>P7455</b> Fuel (4412830)..... <b>PF46112</b>	Vivaro 2.5 DTI/CDTI w/G9U730/G9UB7 Eng. (02/03-08/06) Lube (4506039)..... <b>P7455</b> Fuel (4411637)..... <b>PF9801</b> <sup>90</sup> Fuel (4412830)..... <b>PF46112</b>
Movano A 3.0 CDTI w/ZD3 200/202 Eng. (01/04-07/06) Lube (4415218)..... <b>P7365</b> Fuel (4411637)..... <b>PF9801</b> <sup>90</sup> Air (4415430)..... <b>PA10012</b>	Movano II 2.5 CDTI 120 w/120 HP Eng. (07/06-on) Lube (4506039)..... <b>P7455</b> Fuel (4412830)..... <b>PF46112</b>	<b>OPEL Trucks</b>
Movano B 2.3 CDTI 100 w/M9T670/676/690/692 Eng. (04/10-on) Fuel (4411637)..... <b>PF9801</b> <sup>90</sup>	Movano II 2.5 CDTI 150 w/146 HP Eng. (07/06-on) Lube (4506039)..... <b>P7455</b> Fuel (4412830)..... <b>PF46112</b>	1.9 Litre Truck Lube..... <b>B233</b> Fuel..... <b>BF840</b> <sup>+</sup>
	Movano II 3.0 CDTI w/ZD3 200/203 Eng. (01/04-on) Lube (4415218)..... <b>P7365</b> Fuel (4411637)..... <b>PF9801</b> <sup>90</sup> Air (4417325)..... <b>PA10012</b>	<b>OPTI</b> <b>Auxiliary Power Units (APU)</b>
	Vivaro 1.9 CDTI w/F9Q760 Eng. (03/01-08/06) Fuel (4412830)..... <b>PF46112</b> Fuel (4411637)..... <b>PF9801</b> <sup>90</sup> Air (4416403)..... <b>PA4319</b> <sup>90</sup>	OPTI6800T w/KSD186FAGE Diesel Eng. Lube..... <b>CLN&amp;R</b> Air..... <b>CLN&amp;R</b>
		<b>ORION Buses</b>
		Models w/Detroit 6V92 Eng. (1992) Lube..... <b>B95</b> <sup>+</sup> P. Fuel..... <b>BF5800</b> <sup>+</sup> S. Fuel..... <b>BF5810</b> Air..... <b>PA3951</b> Trans..... <b>PT8330-MPG</b> Hyd..... <b>BT287-10</b>


<sup>+</sup> See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

OSHKOSH Trucks	OSHKOSH Trucks (cont'd)	OSHKOSH Trucks (cont'd)
287C18, 387C18, 487C18, 687C18 Lube..... P52 S. Fuel Ele. (1958-on)..... PF810 Fuel Ele. (1955-57)..... PF821-S	FT1091HS, WA2206 w/Hall-Scott 6182G1 Eng. Lube..... [2] P52	J3080 w/Cat 3408 Eng. Lube..... [2] B99 + Fuel Spin-on..... BF614 +
B1838, B1844 w/GMC 6-71N, 6V-92 Engs. F-F Lube Ele. (5573014)..... P20-HD + B-P Lube (5572425)..... P52 P. Fuel Sock (5574961)..... F916-C P. Fuel Ele. (5575032)..... PF845 P. Fuel Spin-on (6438839)..... BF5800 + S. Fuel Ele. (5574508)..... PF902 S. Fuel Spin-on (6438840)..... BF5810	HB2718 w/Cat C11 Eng. w/Cat C15 or C16 Blower Eng. Lube (Drive & Blower Eng. (To 1/04)) (1R0716)..... B99 + Lube (Drive & Blower Eng. (To 1/04)) (1R1808)..... B7299 + Fuel/Water Separator (Open End for Bowl) (Racor R90P)..... BF46083-O Fuel/Water Separator (w/Bowl) (Racor R90P)..... BF46072 Fuel/Water Separator (w/Drain) (Racor R90P)..... BF1329 Fuel/Water Separator (Sensor Port Thd. 9/16-18) (Racor R90P).. BF1329-SP Fuel/Water Separator (Sensor Port Thd. 1/2-20) (Racor R90P).... BF1339-SP + Trans. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	J30120 w/Detroit Diesel 12V-71 Eng. F-F Lube Ele..... [2] P20-HD + F-F Lube Spin-on..... [2] B95 + P. Fuel Spin-on..... BF784 S. Fuel Spin-on..... BF785
B2038, B2044, B2055, B2065, B2338, B2344, F2344, B2355, B2365, F2365 w/GMC 6V-71, 6V-92, 8V-92 Engs. F-F Lube Ele..... P20-HD + P. Fuel Spin-on..... BF5800 + S. Fuel Spin-on..... BF5810	B2038, B2044, B2338 w/Cummins V555 Eng. F-F Lube Ele..... P999-HD B-P Lube Ele..... C704-L + Fuel/Water Separator..... BF1212 + Fuel Spin-on..... [2] BF957 + Breather Ele. (w/o Turbo) (256837)..... PA1627 Coolant Spin-on..... BW5071	MPT-Series w/Cat C10 Eng. Lube (To 1/04) (1R0716)..... B99 + Lube (1/04-on) (1R1808)..... B7299 + Fuel/Water Separator (Open End for Bowl) (Racor R90P)..... BF46083-O Fuel/Water Separator (w/Bowl) (Racor R90P)..... BF46072 Fuel/Water Separator (w/Drain) (Racor R90P)..... BF1329 Fuel/Water Separator (Sensor Port Thd. 9/16-18) (Racor R90P).. BF1329-SP Fuel/Water Separator (Sensor Port Thd. 1/2-20) (Racor R90P).... BF1339-SP + Air Dryer (Bendix 107796)..... BA5377 Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT Opt. Trans. Spin-on (Fuller 17237)..... B2 +
B2038, B2044, P2323, B2338, F2338, B2344, F2344 w/Cat 3208 Eng. Lube (Early) (9L9200)..... [2] BT364 Lube (Late) (9N5570)..... [2] BT230 + Box-Style Fuel/Water Separator. BF912 Fuel Spin-on..... BF970 +	B2038, B2044, S2046, F2338, B2344, F2344 w/Cat 3306 Eng. Lube (Standard Vers.) (1R0739).. B76 Box-Style Fuel/Water Separator. BF912 Fuel Spin-on (1R0740)..... BF970 +	MPT-Series w/Cat C11 Eng. Lube (To 1/04) (1R0716)..... B99 + Lube (1/04-on) (1R1808)..... B7299 + Fuel/Water Separator (Open End for Bowl) (Racor R90P)..... BF46083-O Fuel/Water Separator (w/Bowl) (Racor R90P)..... BF46072 Fuel/Water Separator (w/Drain) (Racor R90P)..... BF1329 Fuel/Water Separator (Sensor Port Thd. 9/16-18) (Racor R90P).. BF1329-SP Fuel/Water Separator (Sensor Port Thd. 1/2-20) (Racor R90P).... BF1339-SP + Air Dryer (Bendix 107796)..... BA5377 Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT Opt. Trans. Spin-on (Fuller 17237)..... B2 +
F2546 w/Cat 3306 Eng. Lube (Standard Vers.)..... B76 + Lube (Severe Service)..... B76-SS + Box-Style Fuel/Water Separator. BF912 Fuel Spin-on..... BF970 +	HT2723 w/Cat C13 Eng. Lube (To 1/04) (1R0716)..... B99 + Lube (1/04-on) (1R1808)..... B7299 + Fuel/Water Separator (Open End for Bowl) (Racor R90P)..... BF46083-O Fuel/Water Separator (w/Bowl) (Racor R90P)..... BF46072 Fuel/Water Separator (w/Drain) (Racor R90P)..... BF1329 Fuel/Water Separator (Sensor Port Thd. 9/16-18) (Racor R90P).. BF1329-SP Fuel/Water Separator (Sensor Port Thd. 1/2-20) (Racor R90P).... BF1339-SP + Trans. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	MPT-Series w/Cat C12 Eng. Lube (To 1/04) (1R0716)..... B99 + Lube (1/04-on) (1R1808)..... B7299 + Fuel/Water Separator (Open End for Bowl) (Racor R90P)..... BF46083-O Fuel/Water Separator (w/Bowl) (Racor R90P)..... BF46072 Fuel/Water Separator (w/Drain) (Racor R90P)..... BF1329 Fuel/Water Separator (Sensor Port Thd. 9/16-18) (Racor R90P).. BF1329-SP
F2365 w/Cat 3408 Eng. Lube..... [2] B99 + Fuel Spin-on..... BF614 +	F2565 w/Detroit Diesel 8V-92 Eng. F-F Lube Ele..... P20-HD + F-F Lube Spin-on..... B95 + P. Fuel Spin-on..... BF5800 + S. Fuel Spin-on..... BF5810	
FT817W, W2211, M4819, M4829 w/Waukesha 145GZ Eng. F-F Lube Sock..... V1656-O B-P Lube (Michiana SA12800).... P52		

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

OSHKOSH Trucks (cont'd)	OSHKOSH Trucks (cont'd)	OSHKOSH Trucks (cont'd)
MPT-Series w/Cat C12 Eng. (Cont'd)	MPT-Series w/Cummins N14 Eng. (Cont'd)	S Series w/Cat C11 (11.1L) Eng. (To 1/2004) (Cont'd)
<b>Fuel/Water Separator</b> (Sensor Port Thd. 1/2-20) (Racor R90P)..... <b>BF1339-SP +</b>	<b>Fuel/Water Separator</b> (Sensor Port Thd. 1/2-20) (Racor R90P)..... <b>BF1339-SP +</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R120S)..... <b>BF1283-O +</b>
<b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b>	<b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Trans. Spin-on</b> (126-1817)..... <b>BT8878-MPG</b>
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	S Series w/Cat C11 (11.1L) Eng. (1/2004-on)
MPT-Series w/Cat C13 Eng.	MPT-Series w/Detroit Series 60 Eng.	<b>Lube</b> (1R1808)..... <b>B7299 +</b>
<b>Lube</b> (To 1/04) (1R0716)..... <b>B99 +</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R90P)..... <b>BF46083-O</b>	<b>Fuel/Water Separator</b> (w/o SP) (129-0373)..... <b>BF1283 +</b>
<b>Lube</b> (1/04-on) (1R1808)..... <b>B7299 +</b>	<b>Fuel/Water Separator</b> (w/Bowl) (Racor R90P)..... <b>BF46072</b>	<b>Fuel/Water Separator</b> (w/SP) (129-0373)..... <b>BF1283-SP +</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R90P)..... <b>BF46083-O</b>	<b>Fuel/Water Separator</b> (w/Drain) (Racor R90P)..... <b>BF1329</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R120S)..... <b>BF1283-O +</b>
<b>Fuel/Water Separator</b> (w/Bowl) (Racor R90P)..... <b>BF46072</b>	<b>Fuel/Water Separator</b> (Sensor Port Thd. 9/16-18) (Racor R90P).. <b>BF1329-SP</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Fuel/Water Separator</b> (w/Drain) (Racor R90P)..... <b>BF1329</b>	<b>Fuel/Water Separator</b> (Sensor Port Thd. 1/2-20) (Racor R90P).... <b>BF1339-SP +</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Fuel/Water Separator</b> (Sensor Port Thd. 9/16-18) (Racor R90P).. <b>BF1329-SP</b>	<b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b>	<b>Trans. Spin-on</b> (126-1817)..... <b>BT8878-MPG</b>
<b>Fuel/Water Separator</b> (Sensor Port Thd. 1/2-20) (Racor R90P).... <b>BF1339-SP +</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	S Series w/Cat C13 (12.5L) Eng. (To 1/2004)
<b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Lube</b> (1R0716)..... <b>B99 +</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Fuel/Water Separator</b> (w/o SP) (129-0373)..... <b>BF1283 +</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	P Series w/Cat 3208 (10.4L) Eng.	<b>Fuel/Water Separator</b> (w/SP) (129-0373)..... <b>BF1283-SP +</b>
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Lube</b> (8N9586)..... <b>[2] BT230 +</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R120S)..... <b>BF1283-O +</b>
MPT-Series w/Cummins ISC 8.3 (8.3L) Eng.	<b>Lube</b> (9N5680)..... <b>[2] BT364</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b>	<b>Box-Style Fuel/Water Separator.</b> <b>BF912</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R90P)..... <b>BF46083-O</b>	<b>Fuel Spin-on</b> ..... <b>BF970 +</b>	<b>Trans. Spin-on</b> (126-1817)..... <b>BT8878-MPG</b>
<b>Fuel/Water Separator</b> (w/Bowl) (Racor R90P)..... <b>BF46072</b>	P Series w/Cat 3306 (10.5L) Eng.	S Series w/Cat C13 (12.5L) Eng. (1/2004-on)
<b>Fuel/Water Separator</b> (w/Drain) (Racor R90P)..... <b>BF1329</b>	<b>Lube</b> (Standard Vers.)..... <b>B76 +</b>	<b>Lube</b> (1R1808)..... <b>B7299 +</b>
<b>Fuel/Water Separator</b> (Sensor Port Thd. 9/16-18) (Racor R90P).. <b>BF1329-SP</b>	<b>Lube</b> (Severe Service)..... <b>B76-SS +</b>	<b>Fuel/Water Separator</b> (w/o SP) (129-0373)..... <b>BF1283 +</b>
<b>Fuel/Water Separator</b> (Sensor Port Thd. 1/2-20) (Racor R90P).... <b>BF1339-SP +</b>	<b>Box-Style Fuel/Water Separator.</b> <b>BF912</b>	<b>Fuel/Water Separator</b> (w/SP) (129-0373)..... <b>BF1283-SP +</b>
<b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b>	<b>Fuel Spin-on</b> ..... <b>BF970 +</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R120S)..... <b>BF1283-O +</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	P2527, P2530, P4546 w/Cummins NTC300, NTC350 Engs.	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>F-F Lube Spin-on</b> ..... <b>B196 +</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>B-P Lube Ele.</b> ..... <b>C750-E +</b>	<b>Trans. Spin-on</b> (126-1817)..... <b>BT8878-MPG</b>
MPT-Series w/Cummins N14 Eng.	<b>B-P Lube Spin-on</b> ..... <b>B7577</b>	S Series w/Cummins ISM Eng.
<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R90P)..... <b>BF46083-O</b>	<b>Fuel Spin-on</b> ..... <b>BF957 +</b>	<b>11 13/16 In. Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154 +</b>
<b>Fuel/Water Separator</b> (w/Bowl) (Racor R90P)..... <b>BF46072</b>	<b>Coolant</b> ..... <b>BW5071</b>	<b>14 7/32 In. Dual-Flow Lube</b> (Fleetguard LF9000)..... <b>BD7153 +</b>
<b>Fuel/Water Separator</b> (w/Drain) (Racor R90P)..... <b>BF1329</b>	R1644, R1655, R1665 w/Cat 1693T, 1693TA Engs.	<b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>
<b>Fuel/Water Separator</b> (Sensor Port Thd. 9/16-18) (Racor R90P).. <b>BF1329-SP</b>	<b>Lube Ele.</b> ..... <b>[2] PT88-HD B99 +</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Fuel/Water Separator</b> (Sensor Port Thd. 1/2-20) (Racor R90P).... <b>BF1339-SP +</b>	<b>Lube Spin-on</b> ..... <b>PF823-E</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b>	<b>Fuel Spin-on</b> ..... <b>[2] BF970 +</b>	<b>Trans. Spin-on</b> (126-1817)..... <b>BT8878-MPG</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Air Comp. Breather</b> ..... <b>PA1704</b>	S Series w/Cat C11 (11.1L) Eng. (To 1/2004)
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	S Series w/Cat C11 (11.1L) Eng. (To 1/2004)	<b>Lube</b> (1R0716)..... <b>B99 +</b>
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Lube</b> (1R0716)..... <b>B99 +</b>	<b>Fuel/Water Separator</b> (w/o SP) (129-0373)..... <b>BF1283 +</b>
MPT-Series w/Cummins N14 Eng.	<b>Fuel/Water Separator</b> (w/SP) (129-0373)..... <b>BF1283-SP +</b>	<b>Fuel/Water Separator</b> (w/SP) (129-0373)..... <b>BF1283-SP +</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R90P)..... <b>BF46083-O</b>		
<b>Fuel/Water Separator</b> (w/Bowl) (Racor R90P)..... <b>BF46072</b>		
<b>Fuel/Water Separator</b> (w/Drain) (Racor R90P)..... <b>BF1329</b>		
<b>Fuel/Water Separator</b> (Sensor Port Thd. 9/16-18) (Racor R90P).. <b>BF1329-SP</b>		


+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

OSHKOSH Trucks (cont'd)	OTTAWA Trucks (cont'd)	OTTAWA Trucks (cont'd)
S Series w/Cummins ISM Eng. (Cont'd) Trans. Spin-on (126-1817)..... <b>BT8878-MPG</b>	6 X 4 w/Cummins ISB (5.9L) Eng. (Cont'd) Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	Ottawa T2 w/Cummins ISB 6.7 (6.7L) Eng. (2021) Lube (3937736)..... <b>B7177</b> Fuel (5303743)..... <b>BF63000</b> Crankcase Breather (4936636)... <b>CV15010</b>
S Series w/Cummins L10 Eng. F-F Lube..... <b>B196 +</b> B-P Lube..... <b>B7577</b> Dual-Flow Lube..... <b>BD103 +</b> Opt. Fuel/Water Separator..... <b>BF1212 +</b> Fuel..... <b>BF957 +</b> Coolant (3315116)..... <b>BW5071</b>	29540494)..... <b>PT9415-MPG KIT</b> Hyd. (Frame Mtd.) (Luberfiner LFP1652)..... <b>BT839 +</b>	Ottawa T2 w/Cummins ISB 6.7 (6.7L) Eng. (2022) Lube (Fleetguard LF3970)..... <b>B7177</b>
S Series w/Mack AMI Aset Eng. Lube (485GB3236)..... <b>[2] B7225 +</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (126-1817)..... <b>BT8878-MPG</b>	Commando Series w/Ford V8-361 Eng. Lube Ele..... <b>P80</b> Lube Spin-on..... <b>BT251</b> B-P Lube Ele. (500 Size)..... <b>C704-L +</b> Lube Ele..... <b>P80-HD</b> Fuel Ele..... <b>PF827</b> In-Line Fuel (Carb.)..... <b>BF879</b>	Commando CYT30 w/Cummins 6BT5.9 Eng. Lube..... <b>BT339 +</b> Fuel/Water Separator..... <b>BF1226</b> Radial Seal Air (Don. P527484)... <b>RS2863</b> Radial Seal XP Air (Don. P527484)..... <b>RS2863XP</b> Air (400292-000A)..... <b>PA3907</b>
Striker w/Cat C16 Eng. Lube (To 1/04) (1R0716)..... <b>B99 +</b> Lube (1/04-on) (1R1808)..... <b>B7299 +</b> Air Dryer (Bendix 65624)..... <b>BA5373</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Commando Series w/GMC 4-53 Eng. Lube Ele..... <b>P20-HD +</b> P. Fuel Sock..... <b>F916-C</b> P. Fuel Spin-on..... <b>BF5800 +</b> S. Fuel Ele. (5573261)..... <b>PF906</b> S. Fuel Ele. (5574508)..... <b>PF902</b> S. Fuel Spin-on..... <b>BF5810</b>	CYT30 w/Cummins ISB Eng. Lube (Fleetguard LF3970)..... <b>B7177</b> Fuel/Water Separator Ele. (Fleetguard FS19579)..... <b>PF7777</b> Fuel (Fleetguard FF5632)..... <b>BF7940</b> Disposable Air Hsg. (Fleetguard AH1193)..... <b>PA3556</b> Disposable Air Hsg. (90020293). <b>PA3493</b> Trans. Pan-Type (Allison 29538489)..... <b>19739 +</b> Trans. Spin-on (Allison 29510922)..... <b>BT8316-MPG</b>
V Line w/Cummins 6C8.3 Eng. F-F Lube (3313281)..... <b>B205 +</b> Dual-Flow Lube (3318853)..... <b>BD103 +</b> Fuel/Water Separator (3925274). <b>BF1280 +</b> S. Fuel (3903640)..... <b>BF788</b>	Commando 50 w/Ford V8-534 Eng. Lube Ele..... <b>P47</b> Fuel Ele..... <b>PF821-S</b> Fuel Spin-on..... <b>BF585</b>	Ottawa 4 X 2 w/Cat 3126 (7.2L) Eng. Lube (1R1807)..... <b>B7700</b>
WA906, WA1600CD, WA2208, W2209 B-P Lube Ele..... <b>C750-E +</b> Opt. B-P Lube Sock (Deluxe DF) <b>DF408 90</b> S. Fuel Ele..... <b>PF902</b>	Commando 60T w/Cat 1160 Eng. Lube..... <b>[2] BT364</b> Fuel..... <b>BF583</b>	Ottawa 6 X 4 w/Cat 3126 (7.2L) Eng. Lube (1R1807)..... <b>B7700</b>
<b>OTTAWA Trucks</b>	Ottawa T2 w/Cummins ISB 6.7 (6.7L) Eng. (2018) Lube (3937736)..... <b>B7177</b> Fuel/Water Separator (Fleetguard FS20081)..... <b>PF46171</b> Fuel (Fleetguard FF63009)..... <b>BF63000</b> Primary EnduraPanel Air (5261249)..... <b>PA31002</b> Secondary EnduraPanel Air (5261251)..... <b>PA31003</b> Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b> Crankcase Breather (4936636)... <b>CV15010</b> Diesel Exhaust Fluid (Fleetguard UF106)..... <b>PE17002 KIT</b>	YT30 w/Cat C7 Eng. (To 1/2004) Lube (Standard Vers.) (1R0739).. <b>B76 +</b> Lube (Severe Service) (1R0739).. <b>B76-SS +</b> Fuel (1R0751)..... <b>BF7632</b> Std. Air (99105821)..... <b>PA2450</b> Radial Seal Air (90023953)..... <b>RS2863</b> Radial Seal XP Air (90023953)... <b>RS2863XP</b> Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
4 X 2 w/Cummins ISB (5.9L) Eng. Lube (Fleetguard LF3970)..... <b>B7177</b> Fuel/Water Separator (Fleetguard FS19732)..... <b>BF1385-SPS</b> Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Hyd. (Frame Mtd.) (Luberfiner LFP1652)..... <b>BT839 +</b>	Ottawa T2 w/Cummins ISB 6.7 (6.7L) Eng. (2019) Lube (3937736)..... <b>B7177</b> Fuel (5303743)..... <b>BF63000</b> Crankcase Breather (4936636)... <b>CV15010</b>	YT30 w/Cat C7 Eng. (1/2004-on) Lube (1R1807)..... <b>B7700 +</b> Fuel (1R0751)..... <b>BF7632</b> Std. Air (99105821)..... <b>PA2450</b> Radial Seal Air (90023953)..... <b>RS2863</b> Radial Seal XP Air (90023953)... <b>RS2863XP</b> Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
4x2 w/Cummins QSB 6.7L Eng. Lube (Fleetguard LF3970)..... <b>B7177</b> Fuel/Water Separator (Fleetguard FS19732)..... <b>BF1385-SPS</b> Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Ottawa T2 w/Cummins ISB 6.7 (6.7L) Eng. (2020) Lube (3937736)..... <b>B7177</b> Fuel (5303743)..... <b>BF63000</b> Crankcase Breather (4936636)... <b>CV15010</b>	YT30 w/Cat 3126 (7.2L) Eng. (To 1/2004) Lube (Standard Vers.) (1R0739).. <b>B76 +</b> Lube (Severe Service) (1R0739).. <b>B76-SS +</b> Fuel (1R0751)..... <b>BF7632</b> Radial Seal Air (90023953)..... <b>RS2863</b>
6 X 4 w/Cummins ISB (5.9L) Eng. Lube (Fleetguard LF3970)..... <b>B7177</b> Fuel/Water Separator (Fleetguard FS19732)..... <b>BF1385-SPS</b>		


+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).




<b>OTTAWA Trucks (cont'd)</b>	<b>OTTAWA Trucks (cont'd)</b>	<b>PACCAR Engines (cont'd)</b>
YT30 w/Cat 3126 (7.2L) Eng. (To 1/2004) (Cont'd)	YT30, YT60T w/Cummins 6BT5.9, BTA5.9 Engs. (Cont'd)	PX-7 (6.7L)
Radial Seal XP Air (90023953).... <b>RS2863XP</b>	Fuel Spin-on..... <b>BF788</b>	Lube (Fleetguard LF9104)..... <b>B7177</b>
Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	Opt. Fuel In-Line (Strainer) (3826094)..... <b>BF1173</b>	Opt. Fuel/Water Separator (Fleetguard FS1065)..... <b>BF1378-SPS</b>
Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Disposable Air Hsg. (Farr 114880-003)..... <b>PA3493</b>	Fuel (Fleetguard FF63009)..... <b>BF63000</b>
YT30 w/Cat 3126 (7.2L) Eng. (1/2004-on)	Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	Breather (Rear Engine Mounted) (Fleetguard CV50607)..... <b>CV15000</b>
Lube (1R1807)..... <b>B7700 +</b>	Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Crankcase Breather (Rocker Lever Cover Mounted) (Fleetguard CV52001)..... <b>CV15010</b>
Fuel (1R0751)..... <b>BF7632</b>	Trans. Spin-on..... <b>BT230 +</b>	PX-8 (8.3L)
Radial Seal Air (90023953)..... <b>RS2863</b>	Hyd..... <b>BT839-10 +</b>	Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309 +</b>
Radial Seal XP Air (90023953).... <b>RS2863XP</b>	YT50 w/Cummins 6BT5.9 (5.9L) Eng.	Fuel/Water Separator (Fleetguard FS1000)..... <b>BF1259</b>
Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	Lube (Chrysler 5083285AA)..... <b>BT7349</b>	Fuel/Water Separator (Fleetguard FS1065)..... <b>BF1378-SPS</b>
Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Fuel (Fleetguard FF5052)..... <b>BF788</b>	Fuel (Fleetguard FF5488)..... <b>BF7815</b>
YT30 w/Cummins ISB Eng.	Air (Farr 400292-000)..... <b>PA3907</b>	Fuel (Fleetguard FF5636)..... <b>BF7924</b>
Lube (Fleetguard LF3970)..... <b>B7177</b>	Trans. Ele. (Allison 29538489).... <b>19739 +</b>	PX-9 (8.9L)
Fuel/Water Separator (Fleetguard FS1065)..... <b>BF1378-SPS</b>	Trans. Spin-on (Allison 29510922)..... <b>BT8316-MPG</b>	Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309 +</b>
Fuel (Fleetguard FF5632)..... <b>BF7940</b>	YT50 w/Cat 3126 (7.2L) Eng.	Lube (Upgrade) (3401544)..... <b>B40142</b>
Radial Seal Air (90023953)..... <b>RS2863</b>	Lube (1R0739)..... <b>B76 +</b>	Fuel (Fleetguard FF63009)..... <b>BF63000</b>
Radial Seal XP Air (90023953).... <b>RS2863XP</b>	T2E w/Cummins ISB 6.7 (6.7L) Eng. (2020)	MX (12.9L)
Crankcase Breather (1/07-on) (4936636)..... <b>CV15010</b>	Lube (3937736)..... <b>B7177</b>	Lube (1643070)..... <b>P40019</b>
Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	Fuel (5303743)..... <b>BF63000</b>	Lube Spinner (1643072)..... <b>BC7326 +</b>
Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Crankcase Breather (4936636)... <b>CV15010</b>	Fuel/Water Separator (K37-1005)..... <b>PF9928</b>
Trans. Pan-Type (Allison 29538489)..... <b>19739 +</b>	YT60T w/Cat 3126 (7.2L) Eng. (To 1/2004)	Fuel (1655115)..... <b>BF9927</b>
Trans. Spin-on (Allison 29510922)..... <b>BT8316-MPG</b>	Lube (Standard Vers.) (1R0739).. <b>B76 +</b>	Some Fuel (2007 Emissions) (1643080)..... <b>PF7947</b>
YT30 w/Cummins ISC 8.3 (8.3L) Eng.	Lube (Severe Service) (1R0739).. <b>B76-SS +</b>	Coolant (1843659)..... <b>B5088 +</b>
Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309 +</b>	Fuel (1R0751)..... <b>BF7632</b>	MX-11 (10.8L)
Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	Radial Seal Air (90023953)..... <b>RS2863</b>	F-F Lube (1928868PE)..... <b>P40008</b>
Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Radial Seal XP Air (90023953).... <b>RS2863XP</b>	Centrifugal Lube (1928869PE)... <b>BC40009</b>
YT30 w/Detroit Series 40 Eng.	YT60T w/Cat 3126 (7.2L) Eng. (1/2004-on)	Centrifugal Lube (1922496PE)... <b>BC40148</b>
Lube (23529744)..... <b>B7030</b>	Lube (1R1807)..... <b>B7700 +</b>	Fuel/Water Separator (2133096PE)..... <b>PF46106</b>
Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	Fuel (1R0751)..... <b>BF7632</b>	Coolant (1843659PE)..... <b>B5088</b>
Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Radial Seal Air (90023953)..... <b>RS2863</b>	MX-13 (12.9L)
YT30 w/IHC DT466 Eng.	Radial Seal XP Air (90023953).... <b>RS2863XP</b>	Lube Ele. (Pre 2017 Emissions) (1643070)..... <b>P40019</b>
Lube (1819452-C1)..... <b>B7030</b>	YT60T w/Cummins ISC 8.3 (8.3L) Eng.	Lube Ele. (2017 Emissions) (2151728PE)..... <b>P40069</b>
Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309 +</b>	Lube Ele. (1928868PE)..... <b>P40008</b>
Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	FR (4.5L)	Centrifugal Lube (1872106)..... <b>BC7326 +</b>
YT30 w/IHC DT466 Eng.	Lube (Fleetguard LF16015)..... <b>BT7237</b>	Centrifugal Lube (1922496PE)... <b>BC40148</b>
Lube (1819452-C1)..... <b>B7030</b>	Fuel (Fleetguard FF5485)..... <b>BF7813</b>	Centrifugal Lube (1928869PE)... <b>BC40009</b>
Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	PX-6 (6.7L)	Fuel/Water Separator (K371005) <b>PF9928</b>
Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Lube (Fleetguard LF3970)..... <b>B7177</b>	Fuel (1852006)..... <b>PF46106</b>
YT30, YT60T w/Cummins 6BT5.9, BTA5.9 Engs.	Fuel/Water Separator (Fleetguard FS1065)..... <b>BF1378-SPS</b>	Coolant (1843659)..... <b>B5088 +</b>
Lube..... <b>BT339 +</b>	Fuel (Fleetguard FF5632)..... <b>BF7940</b>	<b>PACIFIC CAR &amp; FOUNDRY</b>
Lube (3937743)..... <b>BT7349</b>	Breather (Rear Eng. Mtd.) (Fleetguard CV50601)..... <b>CV15000</b>	<b>Trucks &amp; Buses</b>
Opt. Fuel/Water Separator (Fleetguard FS1251)..... <b>BF1226</b>	Crankcase Breather (Fleetguard CV52001)..... <b>CV15010</b>	Cargo Winch Truck

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

PACIFIC CAR & FOUNDRY Trucks & Buses (cont'd)	PEGASO Trucks (cont'd)	PEGASO Trucks (cont'd)
CT61E, CT73E w/IHC RD501 Eng. B-P Lube Sock (70690H)..... CU406 <sup>90</sup>	1087/10, 1089, 1181L, 1184/10, 1187/10, 1190, 1228T, 1231R, 1231T, 1331, 1331T, 1431	2217 (TRONER), 2217.15 (TRONER), 2323K (TRONER), 2326.26K (TRONER)
<b>PARKS INDUSTRIES</b> Auxiliary Power Units (APU) HP2000 w/Kohler KDW702 Eng. Lube..... BT310 Fuel (Wix 33961)..... BF7915 Air..... PA3953	(Cont'd) Lube..... B7113 Can-Type Fuel..... BF825 + Air..... PA2475	Lube..... B7113 Can-Type Fuel..... BF825 + O. Air..... PA2474 I. Air..... PA2836
HP2000 w/Perkins 402D-05 Eng. Lube..... B37 Fuel (130366040)..... PF937 Radial Seal Air (Don. P822686)... RS3715	1217 Series, 1231R, 1231 Series, 1331 Series, 1431 Series Lube..... B7113 Can-Type Fuel..... BF825 + Air..... PA2405	2331K (TECNO), 2331R (TECNO), 2331T (TECNO), 2331.26K (TECNO) w/96Y1CX Eng. Lube..... B7113 Can-Type Fuel..... BF825 + Air..... PA2405
<b>PDM INDUSTRIES</b> Auxiliary Power Units (APU) HP 15 w/Perkins 6H3XL Eng. Lube (2201523)..... B1405 2 23/32 In. Fuel (130366040)..... PF937 3 1/2 In. Fuel (130366050)..... PF717 Radial Seal Air (Don. P822686)... RS3715	1223, 2321K Lube..... BT216 + Lube..... B7113 Can-Type Fuel..... BF825 + Air..... PA2474	2331.38R (TECNO), 2331.38T (TECNO), 2431.36K (TECNO) w/96Y1CX Eng. Lube..... B7113 Can-Type Fuel..... BF825 + Air..... PA2405
<b>PEGASO</b> Buses 5117 Lube..... B7113 Can-Type Fuel..... BF825 + O. Air..... PA2405 I. Air..... PA2835	1234R (TECNO), 1234.38R (TECNO), 1234.38T (TECNO), 1334.38R (TECNO), 1334.38RG (TECNO), 1434 (TECNO) Lube..... B7113 Can-Type Fuel..... BF884 Air..... PA2776	2334.26K (TECNO), 2337.38T (TECNO), 2434.36K (TECNO) Lube..... B7113 Can-Type Fuel..... BF884 Air..... PA2776
5123 Lube..... B7113 Can-Type Fuel..... BF825 + O. Air..... PA2474 I. Air..... PA2836	1234 Series, 1237 Series, 1240 Series, 1237 Series Lube..... B7113 Can-Type Fuel..... BF884	3088/92, 3089/1, 3089/2, 3181, 3188/92, 3189, 3500, 3560, 3560/1, 3560/3, 3560/4, 3562/1, 3570 Lube..... BT216 + Lube..... B7113 Can-Type Fuel..... BF825 + Air..... PA2475
5226.23 w/95R3AX Eng. Lube..... B7113 Can-Type Fuel..... BF825 + Air..... PA2475	1236.38R (TRONER), 1236.38T (TRONER), 1336.38R (TRONER), 1436.38G (TRONER) w/96R1EX Eng. Some Lube..... BT347 Some Lube..... B7113 Can-Type Fuel..... BF884	<b>PETER PIRSCH</b> Trucks Models w/Continental Eng. Lube (Michiana 15500)..... P52 Lube (Fram F30)..... P42
5232.23 w/96R3EW Eng. Lube..... B7113 Can-Type Fuel..... BF884 Air..... PA2475	1331 (TECNO), 1431 (TECNO), 1431G (TECNO), 1431K (TECNO) w/96Y1CX Eng. Lube..... B7113 Can-Type Fuel..... BF825 + Air..... PA2405	Models w/Waukesha Eng. Lube (Fram F30)..... P42
5237.23 w/96R3EV Eng. Lube..... B7113 Can-Type Fuel..... BF884	2081C, 2081LC, 2081/60, 2082/60, 2082/80, 2089/60, 2089/80, 2090, 2091, 2181/60, 2182/60, 2189/60, 2 Lube..... BT216 + Lube..... B7113 Can-Type Fuel..... BF825 + Air..... PA2475	<b>PETERBILT</b> Trucks 13-210, 22-210 Mid-Ranger w/Cummins 6CT8.3 Eng. Lube..... B205 + P. Fuel/Water Separator..... BF1280 + S. Fuel..... BF788 Air (Don. P129545)..... PA2521
6420 Lube..... B7113 2 13/16 In. Can-Type Fuel..... BF825 + 4 13/32 In. Can-Type Fuel..... BF884 Air..... PA3760	2081C, 2081LC, 2081/60, 2082/60, 2082/80, 2089/60, 2089/80, 2090, 2091, 2181/60, 2182/60, 2189/60, 2 Lube..... BT216 + Lube..... B7113 Can-Type Fuel..... BF825 + Air..... PA2475	200 w/Cummins 6BT5.9 (5.9L) Eng. Lube..... BT339 + Opt. Fuel/Water Separator..... BF1226 P. Fuel/Water Separator..... BF1280 + S. Fuel..... BF788
6424 Lube..... B7113 2 13/16 In. Can-Type Fuel..... BF825 + 4 13/32 In. Can-Type Fuel..... BF884	2190 w/96Y1CX Eng. Lube..... B7113 Can-Type Fuel..... BF825 + Air..... PA2405	200 w/Cummins 6CT8.3 (8.3L) Eng. Dual-Flow Lube (3825970)..... BD103 + Fuel/Water Separator (3925274)..... BF1280 + Fuel (3903640)..... BF788 Std. Air (Don. P129545)..... PA2521 Radial Seal Air (Don. P527484)... RS2863 Radial Seal XP Air (Don. P527484)..... RS2863XP
<b>PEGASO</b> Trucks 1087/10, 1089, 1181L, 1184/10, 1187/10, 1190, 1228T, 1231R, 1231T, 1331, 1331T, 1431 Lube..... BT216 +		

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>
200 w/Cummins ISB 5.9 (5.9L) Eng. <b>Std. Air</b> (Don. P129545)..... <b>PA2521</b> <b>Radial Seal Air</b> (Don. P527484)... <b>RS2863</b> <b>Radial Seal XP Air</b> (Don. P527484)..... <b>RS2863XP</b>	210 w/Paccar PX-7 (6.7L) Eng. (Cont'd) <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b> <b>Steering</b> (229348)..... <b>P106-HD</b> <b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>	220 w/Paccar PX-7 (6.7L) Eng. (2014-18) (Cont'd) <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Steering</b> (229348)..... <b>P106-HD</b> <b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>
200 w/Cummins ISC 8.3 (8.3L) Eng. <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19856)..... <b>PF7977</b> <b>Std. Air</b> (Don. P129545)..... <b>PA2521</b> <b>Radial Seal Air</b> (Don. P527484)... <b>RS2863</b> <b>Radial Seal XP Air</b> (Don. P527484)..... <b>RS2863XP</b>	220 w/Cummins ISB (5.9L) Eng. <b>Lube</b> (3937736)..... <b>B7177</b> <b>Lube</b> (4897898)..... <b>BT7237</b> <b>Fuel</b> (Fleetguard FF5632)..... <b>BF7940</b>	220 w/Paccar PX-7 (6.7L) Eng. (2019) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Radial Seal Air</b> (1679397)..... <b>RS5692</b> <b>Air Dryer</b> (Wabco R950068A)..... <b>BA5379</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (229348)..... <b>P106-HD</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b>
200, 300 w/Detroit Diesel 6V-53N Eng. <b>F-F Lube Ele.</b> ..... <b>P20-HD</b> <b>P. Fuel Sock</b> ..... <b>F916-C</b> <b>S. Fuel Ele.</b> ..... <b>PF906</b>	210 w/Paccar PX-6 (6.7L) Eng. <b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b> <b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b> <b>Fuel</b> (Fleetguard FF5632)..... <b>BF7940</b> <b>Radial Seal Air</b> (Fleetguard AF4878)..... <b>RS2863</b> <b>Radial Seal XP Air</b> (Fleetguard AF4878)..... <b>RS2863XP</b> <b>Air Dryer</b> (DAF 1391510)..... <b>BA5376+</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (229348)..... <b>P106-HD</b>	220 w/Paccar PX-7 (6.7L) Eng. (2020) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b> <b>Pan-Type Trans.</b> (S. Pan, w/o Gskt.) (29537965)..... <b>20004</b> <b>Pan-Type Trans.</b> (S. Pan, w/Gskt.) (29537965)..... <b>20016</b> <b>Pan-Type Trans.</b> (D. Pan, w/o Gskt.) (29537966)..... <b>20003</b> <b>Pan-Type Trans.</b> (D. Pan, w/Gskt.) (29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (29539579)..... <b>BT8460</b> <b>Steering</b> (229348)..... <b>P106-HD</b>
210 w/Paccar PX-6 (6.7L) Eng. <b>Lube</b> (Fleetguard LF9104)..... <b>B7177</b> <b>Opt. Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b> <b>Air Dryer</b> (AD-SP System) (Bendix 5008414)..... <b>BA5374+</b> <b>Air Dryer</b> (System Saver 1200) (Wabco R950068)..... <b>BA5379+</b> <b>Crankcase Breather</b> (Fleetguard CV15000)..... <b>CV15000</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	220 w/Paccar PX-7 (6.7L) Eng. (2014-18) <b>Lube</b> (Fleetguard LF9104)..... <b>B7177</b> <b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Radial Seal Air</b> (1679397)..... <b>RS5692</b> <b>Air Dryer</b> (Wabco R950011)..... <b>BA5374+</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b> <b>Breather</b> (Rear Eng. Mounted) (Fleetguard CV50607)..... <b>CV15000</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	220 w/Paccar PX-7 (6.7L) Eng. (2021) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Pan-Type Trans.</b> (S. Pan, w/o Gskt.) (29537965)..... <b>20004</b> <b>Pan-Type Trans.</b> (S. Pan, w/Gskt.) (29537965)..... <b>20016</b> <b>Pan-Type Trans.</b> (D. Pan, w/o Gskt.) (29537966)..... <b>20003</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>
220 w/Paccar PX-7 (6.7L) Eng. (2021) (Cont'd) <b>Pan-Type Trans.</b> (D. Pan, w/Gskt.) (29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (29539579)..... <b>BT8460</b>	282, 288, 289, 349H, 351, 352H, 353, 358, 383 w/Cummins Eng. (Cont'd) <b>Turbocharger</b> ..... <b>BT112</b>	310 w/Cummins NTC240 Eng. (Cont'd) <b>Coolant</b> ..... <b>BW5071</b>
220 w/Paccar PX-7 (6.7L) Eng. (2022) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Pan-Type Trans.</b> (S. Pan, w/o Gskt.) (29537965)..... <b>20004</b> <b>Pan-Type Trans.</b> (S. Pan, w/Gskt.) (29537965)..... <b>20016</b> <b>Pan-Type Trans.</b> (D. Pan, w/o Gskt.) (29537966)..... <b>20003</b> <b>Pan-Type Trans.</b> (D. Pan, w/Gskt.) (29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (29539579)..... <b>BT8460</b>	282, 289, 348, 352, 352H, 359 w/Cat 1693T Eng. <b>Lube Ele.</b> ..... <b>[2] PT88-HD</b> <b>Lube Spin-on</b> ..... <b>B99 +</b> <b>Fuel Ele.</b> ..... <b>[2] PF823 +</b> <b>Fuel Spin-on</b> ..... <b>[2] BF970 +</b> <b>Air Comp. Breather</b> ..... <b>PA1704</b>	310 w/Detroit Diesel 6V-92N (9.0L) Eng. <b>F-F Lube Ele.</b> ..... <b>P20-HD</b> <b>F-F Lube Spin-on</b> ..... <b>B95 +</b> <b>P. Fuel Spin-on</b> ..... <b>BF5800 +</b> <b>S. Fuel Spin-on</b> ..... <b>BF5810</b>
224, 227, 265 w/Cummins 6CT8.3 (8.3L) Eng. <b>Lube</b> ..... <b>B205 +</b> <b>Opt. Fuel/Water Separator</b> ..... <b>BF1226</b> <b>P. Fuel/Water Separator</b> ..... <b>BF1280 +</b> <b>S. Fuel</b> ..... <b>BF788</b>	289, 352H w/Cat 3408 Eng. <b>Lube</b> ..... <b>[2] B99 +</b> <b>Fuel Spin-on</b> ..... <b>BF614 +</b> <b>Opt. Air</b> (5L1203)..... <b>PA1631-S</b> <b>Coolant</b> ..... <b>BW5137</b>	310, 320 w/Cummins LTA10 Series Engs. <b>F-F Lube</b> ..... <b>B196 +</b> <b>B-P Lube</b> ..... <b>BF757</b> <b>Fuel Spin-on</b> ..... <b>BF957-D +</b>
270 w/Cummins 6BT5.9 (5.9L) Eng. <b>Lube</b> (Chrysler 5083285AA)..... <b>BT7349</b> <b>Fuel/Water Separator</b> (4741689)..... <b>BF1223 +</b> <b>Fuel/Water Separator</b> (3903202)..... <b>BF1226</b>	310 w/Cat 3306 (10.5L) Eng. <b>Lube Ele.</b> (5S0484)..... <b>PT670</b> <b>Lube Spin-on</b> (1R0716)..... <b>B99 +</b> <b>Lube Spin-on</b> (Standard Vers.) (1R0739)..... <b>B76 +</b> <b>Lube Spin-on</b> (Severe Service) (1R0739)..... <b>B76-SS +</b> <b>P. Fuel Ele.</b> (9M2342)..... <b>PF935</b> <b>P. Fuel Spin-on</b> (1R1740)..... <b>BF970 +</b> <b>S. Fuel Spin-on</b> (1R0750)..... <b>BF7633 +</b>	320 w/Cat C7 (7.2L) Eng. (To 1/2004) <b>Lube</b> (Standard Vers.) (1R0739).. <b>B76 +</b> <b>Lube</b> (1R1808)..... <b>B7299 +</b> <b>Lube</b> (Severe Service) (1R0739).. <b>B76-SS +</b> <b>Fuel/Water Separator</b> (1752949)..... <b>BF1268</b> <b>Air</b> (Don. P182000)..... <b>LL1637-FN</b> <b>Air</b> (Don. P182099)..... <b>LL2333</b> <b>Air</b> (Don. P181057)..... <b>PA2326 +</b> <b>XP Air</b> (Don. P181057)..... <b>PA2326XP +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Steering</b> (Nelson 87972A)..... <b>PT9386-MPG</b>
270 w/Cummins ISB 5.9 (5.9L) Eng. <b>Lube</b> (3937144)..... <b>B7177</b> <b>Lube</b> (Fleetguard LF3729)..... <b>BT595</b> <b>Fuel/Water Separator Ele.</b> ..... <b>PF7777</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS19519)..... <b>BF1271</b> <b>Radial Seal Air</b> (DAF ACHD040)..... <b>RS4794</b> <b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b> <b>Steering</b> (Leyland BBU5866)..... <b>P106-HD</b>	310 w/Cummins L10 (10.0L) Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Opt. Fuel/Water Separator</b> (3308638)..... <b>BF1212 +</b> <b>Fuel</b> (154789)..... <b>BF957-D +</b> <b>Coolant</b> (w/4 Units BTA+) (3315116)..... <b>BW5071</b> <b>Coolant</b> (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b>	320 w/Cat C7 (7.2L) Eng. (1/2004-on) <b>Lube</b> (1R1807)..... <b>B7700 +</b> <b>Lube</b> (1R1808)..... <b>B7299 +</b> <b>Fuel/Water Separator</b> (1752949)..... <b>BF1268</b> <b>Air</b> (Don. P182000)..... <b>LL1637-FN</b> <b>Air</b> (Don. P182099)..... <b>LL2333</b> <b>Air</b> (Don. P181057)..... <b>PA2326 +</b> <b>XP Air</b> (Don. P181057)..... <b>PA2326XP +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Steering</b> (Nelson 87972A)..... <b>PT9386-MPG</b>
277 w/Cummins 6CT8.3 Eng. <b>Lube</b> ..... <b>B205 +</b> <b>Opt. Fuel/Water Separator</b> ..... <b>BF1226</b> <b>P. Fuel/Water Separator</b> ..... <b>BF1280 +</b> <b>S. Fuel</b> ..... <b>BF788</b>	310 w/Cummins N14 (14.0L) Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Opt. Fuel/Water Separator</b> (3308638)..... <b>BF1212 +</b> <b>Fuel</b> (154789)..... <b>BF957-D +</b> <b>Coolant</b> (w/4 Units BTA+) (3315116)..... <b>BW5071</b>	
282 w/Cat 3406 Eng. <b>Lube</b> ..... <b>B99 +</b> <b>Fuel Spin-on</b> ..... <b>BF614 +</b>	310 w/Cummins NTC240 Eng. <b>F-F Lube Ele.</b> ..... <b>P999-HD</b> <b>F-F Lube Spin-on</b> ..... <b>B196 +</b> <b>B-P Lube Ele.</b> ..... <b>C750-E +</b> <b>B-P Lube Spin-on</b> ..... <b>B7577</b> <b>Fuel/Water Separator</b> ..... <b>BF1212 +</b> <b>4 3/8 In. Fuel Spin-on</b> ..... <b>BF948 +</b> <b>5 3/4 In. Fuel Spin-on</b> ..... <b>BF957 +</b> <b>11 7/32 In. Fuel Spin-on</b> ..... <b>BF596 +</b> <b>Breather Ele.</b> (w/Turbo) (255963) <b>PA643</b> <b>Breather Ele.</b> (w/o Turbo) (256837)..... <b>PA1627</b> <b>Coolant Spin-on</b> ..... <b>BW5071</b>	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

PETERBILT Trucks (cont'd)	PETERBILT Trucks (cont'd)	PETERBILT Trucks (cont'd)
320 w/Cat C10 (10.3L) Eng. (To 1/2004)	320 w/Cat C11 (11.1L) Eng. (To 1/2004)	320 w/Cat C13 Eng. (Cont'd)
F-F Lube (1R0716)..... B99 +	(Cont'd)	Steering (Nelson 87972A)..... PT9386-MPG
B-P Lube (1W8845)..... B7577	18 9/16 In. Air (Don. P182099).... LL2333	320 w/Cat 3126 (7.2L) Eng.
Fuel/Water Separator Ele. (Davco 382116)..... PF7755	O. Air (Don. P182057)..... LL2326 +	Lube (Standard Vers.)..... B76
Fuel/Water Separator Ele. (Fleetguard FS1201)..... PF316	I. Air (Don. P158050)..... PA1904	P. Fuel Ele..... PF935
Fuel/Water Separator Spin-on (Fleetguard FS1000)..... BF1259	Air Dryer (Bendix 109493)..... BA5373	P. Fuel Spin-on (1R-0759)..... BF7634
Fuel Ele..... [2] PF935	Coolant (Fleetguard WF2122)..... B5088 +	S. Fuel Spin-on (1R-0751)..... BF7632
Fuel Spin-on (Std.)..... BF7587 +	Trans. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	12 1/2 In. Air (Don. P182000).... LL1637-FN
Fuel Spin-on (High Efficiency).... BF614 +	Trans. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	18 9/16 In. Air (Don. P182099).... LL2333
12 1/2 In. Air (Don. P182000).... LL1637-FN	Steering (Nelson 87972A)..... PT9386-MPG	Air Dryer (Bendix 109493)..... BA5373
18 9/16 In. Air (Don. P182099).... LL2333	320 w/Cat C11 (11.1L) Eng. (1/2004-on)	Coolant (Fleetguard WF2122)..... B5088 +
O. Air (Don. P182057)..... LL2326 +	F-F Lube (1R1808)..... B7299 +	Trans. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT
I. Air (Don. P158050)..... PA1904	B-P Lube (1W8845)..... B7577	Trans. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT
Air Dryer (Bendix 109493)..... BA5373	Fuel/Water Separator Ele. (Davco 382116)..... PF7755	Steering (Nelson 87972A)..... PT9386-MPG
Coolant (Fleetguard WF2122)..... B5088 +	Fuel/Water Separator Ele. (Fleetguard FS1201)..... PF316	320 w/Cat 3176 (10.3L) Eng.
Trans. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	Fuel/Water Separator Spin-on (Fleetguard FS1000)..... BF1259	F-F Lube (Std. Version) (1R0716)..... B99 +
Trans. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Fuel Ele..... [2] PF935	F-F Lube (High Efficiency Vers.) (1R1808)..... B7299 +
Steering (Nelson 87972A)..... PT9386-MPG	Fuel Spin-on (Std.)..... BF7587 +	F-F Lube (1R0713)..... [2] BT230 +
320 w/Cat C10 (10.3L) Eng. (1/2004-on)	Fuel Spin-on (High Efficiency).... BF614 +	F-F Lube (1R0714)..... [2] B75
F-F Lube (1R1808)..... B7299 +	12 1/2 In. Air (Don. P182000).... LL1637-FN	Opt. B-P Lube (1W8845)..... B7577
B-P Lube (1W8845)..... B7577	18 9/16 In. Air (Don. P182099).... LL2333	Fuel/Water Separator Ele. (8N0205)..... PF316
Fuel/Water Separator Ele. (Davco 382116)..... PF7755	O. Air (Don. P182057)..... LL2326 +	Fuel/Water Separator Spin-on (2568753)..... BF1259
Fuel/Water Separator Ele. (Fleetguard FS1201)..... PF316	I. Air (Don. P158050)..... PA1904	P. Fuel Ele. (9M2342)..... [2] PF935
Fuel/Water Separator Spin-on (Fleetguard FS1000)..... BF1259	Air Dryer (Bendix 109493)..... BA5373	P. Fuel Spin-on (1R1740)..... BF970 +
Fuel Ele..... [2] PF935	Coolant (Fleetguard WF2122)..... B5088 +	S. Fuel Spin-on (1R0750)..... BF7633 +
Fuel Spin-on (Std.)..... BF7587 +	Trans. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	320 w/Cat 3306 (10.5L) Eng.
Fuel Spin-on (High Efficiency).... BF614 +	Trans. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	F-F Lube (Standard Vers.)..... B76
12 1/2 In. Air (Don. P182000).... LL1637-FN	Steering (Nelson 87972A)..... PT9386-MPG	B-P Lube (Luberfiner 750-CT).... C750-E +
18 9/16 In. Air (Don. P182099).... LL2333	320 w/Cat C13 Eng.	Fuel/Water Separator Ele. (Racor 1000FG)..... PF7890
O. Air (Don. P182057)..... LL2326 +	Lube (1R1808)..... B7299 +	Fuel/Water Separator Spin-on (Fleetguard FS1212)..... BF1212 +
I. Air (Don. P158050)..... PA1904	Fuel/Water Separator (Fleetguard FS1000)..... BF1259	P. Fuel Ele..... PF935
Air Dryer (Bendix 109493)..... BA5373	Fuel (1R0749)..... BF7587 +	Fuel Spin-on..... BF970 +
Coolant (Fleetguard WF2122)..... B5088 +	Std. O. Air (Don. P181057)..... PA2326 +	Air (Don. P181000)..... PA1637-FN
Trans. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	XP O. Air (Don. P181057)..... PA2326XP +	Air Dryer (Wabco R950011)..... BA5374 +
Trans. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	I. Air (Don. P158050)..... PA1904	Coolant (Fleetguard WF2075).... BW5075
Steering (Nelson 87972A)..... PT9386-MPG	Air Dryer (AD-IP System) (Bendix 109493)..... BA5373	Opt. Trans. (Fuller 17237)..... B2 +
320 w/Cat C11 (11.1L) Eng. (To 1/2004)	Air Dryer (AD-IS System) (Bendix 5008414)..... BA5374 +	Steering (Nelson 83804E)..... P528
F-F Lube (1R0716)..... B99 +	Breather (2007-on) (296-8325).... CV15008	320 w/Cat 3406 (14.6L) Eng.
B-P Lube (1W8845)..... B7577	Coolant (Fleetguard WF2071)..... BW5071	F-F Lube (Std. Version) (1R0716)..... B99 +
Fuel/Water Separator Ele. (Davco 382116)..... PF7755	Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	F-F Lube (High Efficiency Vers.) (1R1808)..... B7299 +
Fuel/Water Separator Ele. (Fleetguard FS1201)..... PF316	Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Fuel/Water Separator (1752949).... BF1268
Fuel/Water Separator Spin-on (Fleetguard FS1000)..... BF1259	Trans. Pan-Type (Allison 29538489)..... 19739 +	Fuel/Water Separator (2568753).... BF1259
Fuel Ele..... [2] PF935	Trans. Spin-on (Allison 29510922)..... BT8316-MPG	Fuel (1R0749)..... BF7587 +
Fuel Spin-on (Std.)..... BF7587 +	Opt. Trans. Spin-on (Fuller 17237)..... B2 +	Fuel (1R0712)..... BF614 +
Fuel Spin-on (High Efficiency).... BF614 +		
12 1/2 In. Air (Don. P182000).... LL1637-FN		


+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>
320 w/Cummins 6CT8.3 Eng. F-F Lube (3313281)..... <b>B205 +</b> Fuel/Water Separator (Fleetguard FS1212)..... <b>BF1212 +</b> Fuel/Water Separator (3925274)..... <b>BF1280 +</b> S. Fuel (3903640)..... <b>BF788</b> Air (Don. P182000)..... <b>LL1637-FN</b> Coolant (w/4 Units BTA+)..... (3315116)..... <b>BW5071</b> Coolant (w/8 Units BTA+)..... (3315115)..... <b>BW5073</b> Trans. Pan-Type (Allison 29538489)..... <b>19739 +</b> Trans. Spin-on (Allison 29510922)..... <b>BT8316-MPG</b> Steering (Nelson 83804E)..... <b>P528</b>	320 w/Cummins ISL-G (8.9L) Eng. (2018) (Cont'd) Air Dryer (System Saver 1200) (Wabco R950068)..... <b>BA5379</b> Coolant (w/4 Units BTA +) (Fleetguard WF2071)..... <b>BW5071</b> Coolant (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b> Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Steering (Fleetguard LF627)..... <b>P528</b>	320 w/Cummins ISM 10.8 (10.8L) Eng. (To 2007) (Cont'd) Fuel/Water Separator Spin-on (Fleetguard FS1000)..... <b>BF1259</b> Std. O. Air (Don. P181057)..... <b>PA2326 +</b> XP O. Air (Don. P181057)..... <b>PA2326XP +</b> I. Air (Don. P158050)..... <b>PA1904</b> O. Air (Don. P182049)..... <b>LL2456 +</b> I. Air (Don. P116446)..... <b>PA2457</b> Air Dryer (AD-IP System) (Bendix 109493)..... <b>BA5373</b> Air Dryer (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> Coolant (w/o Chemical) (4920476)..... <b>B5090</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Trans. Pan-Type (Allison 29538489)..... <b>19739 +</b> Trans. Spin-on (Allison 29510922)..... <b>BT8316-MPG</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Steering (Nelson 87972A)..... <b>PT9386-MPG</b>
320 w/Cummins ISC 8.3 (8.3L) Eng. Dual-Flow Lube (3401544)..... <b>BD7309 +</b> Dual-Flow Lube (3825970)..... <b>BD103 +</b> Lube (Upgrade) (3401544)..... <b>B40142 +</b> Fuel/Water Separator Ele..... <b>PF7755</b> Fuel/Water Separator Spin-on..... <b>BF1272-SPS</b> Fuel (Fleetguard FF5488)..... <b>BF7815</b> 12 1/2 In. Air..... <b>LL1637-FN</b> 18 9/16 In. Air..... <b>LL2333</b> Air Dryer (AD-IP System) (Bendix 65624)..... <b>BA5373</b> Coolant..... <b>BW5071</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Steering (Nelson 87972A)..... <b>PT9386-MPG</b>	320 w/Cummins ISL 8.9 (8.9L) Eng. Dual-Flow Lube (3401544)..... <b>BD7309 +</b> Dual-Flow Lube..... <b>BD103 +</b> Lube (Upgrade) (3401544)..... <b>B40142 +</b> Fuel/Water Separator Ele..... <b>PF7755</b> Fuel/Water Separator Ele. (Davco 382116)..... <b>PF7755</b> Fuel/Water Separator Ele. (K371004)..... <b>PF9928</b> Fuel/Water Separator Spin-on..... <b>BF1272-SPS</b> Fuel/Water Separator Spin-on (Fleetguard FS1003)..... <b>BF1293-SPS</b> Fuel (5303743)..... <b>BF63000</b> Fuel (Fleetguard FF5488)..... <b>BF7815</b> Fuel (Fleetguard FF5636)..... <b>BF7924</b> Radial Seal XP O. Air (w/Blank Band) (Don. P777868)..... <b>RS3870XP +</b> Single Air..... <b>LL2333</b> O. Air (Don. P182049)..... <b>LL2456 +</b> I. Air (Don. P116446)..... <b>PA2457</b> Air (Don. P158050)..... <b>PA1904</b> Radial Seal O. Air (w/o Blank Band) (Don. P777868)..... <b>RS4638</b> Radial Seal O. Air (w/Blank Band) (Don. P777868)..... <b>RS3870</b> Radial Seal I. Air (Don. P777869)..... <b>RS3871</b> Air Dryer (AD-IP System) (Bendix 109493)..... <b>BA5373</b> Air Dryer (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> Coolant..... <b>BW5071</b> Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Steering (Nelson 87972A)..... <b>PT9386-MPG</b> Diesel Exhaust Fluid (5303604)..... <b>PE17000</b>	320 w/Cummins ISM 10.8 (10.8L) Eng. (2007-on) Dual-Flow Lube (Fleetguard LF9001)..... <b>BD7154 +</b> Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> Fuel/Water Separator Ele. (Fleetguard FS19727)..... <b>PF7895</b> Fuel/Water Separator Spin-on (Fleetguard FS1000)..... <b>BF1259</b> Std. O. Air (Don. P181057)..... <b>PA2326 +</b> XP O. Air (Don. P181057)..... <b>PA2326XP +</b> I. Air (Don. P158050)..... <b>PA1904</b> O. Air (Don. P182049)..... <b>LL2456 +</b> I. Air (Don. P116446)..... <b>PA2457</b> Air Dryer (AD-IP System) (Bendix 109493)..... <b>BA5373</b> Air Dryer (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> Breather (3683918)..... <b>CV15000</b> Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> Coolant (w/o Chemical) (4920476)..... <b>B5090</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Trans. Pan-Type (Allison 29538489)..... <b>19739 +</b>
320 w/Cummins ISL-G (8.9L) Eng. (2018) Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309 +</b> Fuel/Water Separator (Fleetguard NG5900)..... <b>BF7695</b> Air (Don. P119370)..... <b>PA1904</b> Cab Air (FR11110)..... <b>CLN&amp;R</b> Air Dryer (AD-SP System) (Bendix 5008414)..... <b>BA5374 +</b>	320 w/Cummins ISM 10.8 (10.8L) Eng. (To 2007) Dual-Flow Lube (Fleetguard LF9001)..... <b>BD7154 +</b> Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> Fuel/Water Separator Ele. (Fleetguard FS19727)..... <b>PF7895</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

PETERBILT Trucks (cont'd)	PETERBILT Trucks (cont'd)	PETERBILT Trucks (cont'd)
320 w/Cummins ISM 10.8 (10.8L) Eng. (2007-on) (Cont'd)	320 w/Cummins ISX 11.9G (11.9L) Eng. (2018)	320 w/Cummins M11 (10.8L) Eng. (To 12/1995) (Cont'd)
Trans. Spin-on (Allison 29510922).....	Dual-Flow Lube (4367100).....	Trans. (2 In. Kit) (Allison 29540493).....
BT8316-MPG	BD50000	PT9416-MPG KIT
Opt. Trans. Spin-on (Fuller 17237).....	Fuel/Water Separator (3607140).....	Trans. (4 In. Kit) (Allison 29540494).....
B2 +	PA1904	PT9415-MPG KIT
Steering (Nelson 87972A).....	Air (Don. P119370).....	
PT9386-MPG	CLN&R	
320 w/Cummins ISX 11.9 (11.9L) Eng. (2011-17)	Air Dryer (AD-SP System) (Bendix 5008414).....	
Dual-Flow Lube (Fleetguard LF9070).....	BA5374 +	
BD7153 +	Air Dryer (System Saver 1200) (Wabco R950068).....	
Dual-Flow Lube (3401544).....	BA5379	
BD7309 +	B5087	
Dual-Flow Lube (Fleetguard LF9080).....	Trans. (2 In. Kit) (Allison 29540493).....	
BD7154 +	PT9416-MPG KIT	
Lube (Upgrade) (3401544).....	Trans. (4 In. Kit) (Allison 29540494).....	
B40142 +	PT9415-MPG KIT	
Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN).....	Steering (Fleetguard LF627).....	
BD50000	P528	
Fuel/Water Separator (Fleetguard FS19764).....	320 w/Cummins ISX 15.0 (14.9L) Eng.	
PF9814	Dual-Flow Lube (Fleetguard LF9070).....	
Fuel (Standard) (Fleetguard FF5776).....	BD7153 +	
BF9885 +	Dual-Flow Lube (Fleetguard LF9080).....	
Fuel (Upgrade) (Fleetguard FF5825NN).....	BD7154 +	
BF46129	Dual-Flow Lube (High Efficiency) (Fleetguard LF14000NN).....	
Std. I. Air (Don. P119370).....	BD50000	
PA1904	Fuel/Water Separator Ele. (Fleetguard FF5369W).....	
Radial Seal O. Air (Don. P777868).....	PF7744	
RS4638 +	Fuel/Water Separator Ele. (Fleetguard FS19729).....	
Radial Seal I. Air (Don. P777869).....	PF7755	
RS3871	Fuel Spin-on (Fleetguard FF2200).....	
Cab Air (FR11100).....	BF7766	
CLN&R	Fuel Spin-on (Fleetguard FF2203).....	
Air Dryer (AD-IS System) (Bendix 5008414).....	BF7760	
BA5374 +	PA1904	
Coolant (w/o Chemical) (Fleetguard WF2127).....	CV15000	
B5087	Crankcase Breather (3683918).....	
Coolant (w/11 1/2 Units BTA+) (Fleetguard WF2125).....	CV15000	
BW5086	Coolant (w/o Chemical) (Fleetguard WF2127).....	
Trans. (2 In. Kit) (Allison 29540493).....	B5087	
PT9416-MPG KIT	Coolant (w/11 1/2 Units BTA+) (Fleetguard WF2126).....	
Trans. (4 In. Kit) (Allison 29540494).....	BW5086	
PT9415-MPG KIT	Coolant (Controlled Release BTA+) (Fleetguard WF2121).....	
Steering (Nelson 87972A).....	BW5250	
PT9386-MPG	Steering (Nelson 87972A).....	
Diesel Exhaust Fluid (5303604).....	PT9386-MPG	
PE17000	320 w/Cummins L10 Eng.	
320 w/Cummins ISX 11.9 (11.9L) Eng. (2018)	Dual-Flow Lube (3318853).....	
Dual-Flow Lube (Fleetguard LF14000NN).....	BD103 +	
BD50000	Fuel/Water Separator (Fleetguard FS1212).....	
Fuel (Fleetguard FF5776).....	BF1212 +	
BF9885	Air (Don. P182000).....	
Air (Don. P119370).....	LL1637-FN	
PA1904	Air Dryer (Wabco 950011).....	
Cab Air (FR111100).....	BA5374 +	
CLN&R	BW5073	
Air Dryer (AD-SP System) (Bendix 5008414).....	Coolant (3315115).....	
BA5374 +	Trans. Ele. (2 In. Kit) (Allison 29540493).....	
Air Dryer (System Saver 1200) (Wabco R950068).....	PT9416-MPG KIT	
BA5379	Trans. Ele. (4 In. Kit) (Allison 29540494).....	
Trans. (2 In. Kit) (Allison 29540493).....	PT9415-MPG KIT	
PT9416-MPG KIT	Opt. Trans. Spin-on (Fuller 17237).....	
Trans. (4 In. Kit) (Allison 29540494).....	B2 +	
PT9415-MPG KIT	P528	
Steering (Fleetguard LF627).....	Steering (Nelson 83804E).....	
P528	P528	
	320 w/Cummins M11 (10.8L) Eng. (To 12/1995)	
	Dual-Flow Lube (3318853).....	
	BD103 +	
	Fuel/Water Separator Ele. (Fleetguard FS1029W).....	
	PF7680	
	Fuel/Water Separator Spin-on (3308638).....	
	BF1212 +	
	320 w/Paccar MX-11 (10.8L) Eng. (2018)	
	F-F Lube (1928868PE).....	
	P40008	
	Centrifugal Lube (1928869PE).....	
	BC40009	
	Fuel/Water Separator (Fleetguard FS1029W).....	
	PF7680	
	Fuel/Water Separator (Fleetguard FS19765).....	
	PF7930	
	Fuel (1852006PE).....	
	PF46106	
	Air (Don. P119370).....	
	PA1904	
	Cab Air (FR111100).....	
	CLN&R	
	Air Dryer (AD-SP System) (Bendix 5008414).....	
	BA5374 +	
	Air Dryer (System Saver 1200) (Wabco R950068).....	
	BA5379	
	Coolant (1843659PE).....	
	B5088 +	
	Steering (Fleetguard LF627).....	
	P528	
	Diesel Exhaust Fluid (4388378).....	
	PE17002 KIT	
	320 w/Paccar PX-9 (8.9L) Eng. (2014-17)	
	Dual-Flow Lube (Fleetguard LF9009).....	
	BD7309 +	
	Air (Don. P119370).....	
	PA1904	
	Air Dryer (AD-SP System) (Bendix 5008414).....	
	BA5374 +	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>
320 w/Paccar PX-9 (8.9L) Eng. (2014-17) (Cont'd) <b>Air Dryer</b> (System Saver 1200) (Wabco R950068)..... <b>BA5379 +</b> <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (Nelson 87972A)..... <b>PT9386-MPG</b>	325 w/Paccar PX-6 (6.7L) Eng. (Cont'd) <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	330 w/Cat C7 (7.2L) Eng. (Cont'd) <b>Fuel/Water Separator</b> (Open End for Bowl) (Racor S3225P)..... <b>BF1348-O</b> <b>Fuel</b> (1R0751)..... <b>BF7632</b> <b>Radial Seal Air</b> (Don. P527484)... <b>RS2863</b> <b>Radial Seal XP Air</b> (Don. P527484)..... <b>RS2863XP</b> <b>Cab Air</b> (Elixaire 5X010007)..... <b>PA5320</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b> <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>
320 w/Paccar PX-9 (8.9L) Eng. (2018) <b>Lube</b> (3401544)..... <b>B40142</b> <b>Fuel/Water Separator</b> (Fleetguard FS1003)..... <b>BF1293-SPS</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Air</b> (Don. P119370)..... <b>PA1904</b> <b>Cab Air</b> (FR111100)..... <b>CLN&amp;R</b> <b>Air Dryer</b> (AD-SP System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Air Dryer</b> (System Saver 1200) (Wabco R950068)..... <b>BA5379</b> <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (Fleetguard LF627)..... <b>P528</b>	325 w/Paccar PX-7 (6.7L) Eng. (2014-17) <b>Lube</b> (Fleetguard LF9104)..... <b>B7177</b> <b>Opt. Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b> <b>Air Dryer</b> (AD-SP System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Air Dryer</b> (System Saver 1200) (Wabco R950068)..... <b>BA5379 +</b> <b>Crankcase Breather</b> (Fleetguard CV50607)..... <b>CV15000</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (Nelson 87972A)..... <b>PT9386-MPG</b>	330 w/Cat 3116 (6.6L) Eng. <b>Lube</b> (Standard Vers.) (1R0739).. <b>B76 +</b> <b>Lube</b> (Severe Service) (1R0739).. <b>B76-SS +</b> <b>Radial Seal Air</b> (Don. P527484)... <b>RS2863</b> <b>Radial Seal XP Air</b> (Don. P527484)..... <b>RS2863XP</b> <b>Disposable Air Hsg.</b> (Farr 400820022)..... <b>PA4860</b> <b>Cab Air</b> (Elixaire 5X010007)..... <b>PA5320</b> <b>Steering</b> (1698964C92)..... <b>PT9354-MPG</b>
320 HE (Hybrid) w/Cummins ISM Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154 +</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Air Dryer</b> (AD-IP System) (Bendix 109493)..... <b>BA5373</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Breather</b> (1/07-on) (3683918)..... <b>CV15000</b> <b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Pan-Type</b> (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	325 w/Paccar PX-7 (6.7L) Eng. (2018) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Air</b> (Don. P119370)..... <b>PA1904</b> <b>Crankcase Breather</b> (Fleetguard CV52001)..... <b>CV15010</b>	330 w/Cat 3126 (7.2L) Eng. <b>F-F Lube</b> (Standard Vers.) (1R0739)..... <b>B76</b> <b>F-F Lube</b> (1R1807)..... <b>B7700 +</b> <b>Fuel Ele.</b> (8H7204)..... <b>PF935</b> <b>Fuel Spin-on</b> (Fleetguard FF105)..... <b>BF957 +</b> <b>Fuel Spin-on</b> (1R0751)..... <b>BF7632</b> <b>Radial Seal Air</b> (Don. P527484)... <b>RS2863</b> <b>Radial Seal XP Air</b> (Don. P527484)..... <b>RS2863XP</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>
325 w/Paccar PX-6 (6.7L) Eng. <b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b> <b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b> <b>Fuel</b> (Fleetguard FF5632)..... <b>BF7940</b> <b>Radial Seal Air</b> (Don. P527484)... <b>RS2863</b> <b>Radial Seal XP Air</b> (Don. P527484)..... <b>RS2863XP</b> <b>Cab Air</b> (Elixaire 5X010007)..... <b>PA5320</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	325 w/Paccar PX-7 (6.7L) Eng. (2019) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	330 w/Cat 3126E (7.2L) Eng. <b>F-F Lube</b> (Standard Vers.) (1R0739)..... <b>B76 +</b> <b>F-F Lube</b> (1R1807)..... <b>B7700 +</b> <b>F-F Lube</b> (Severe Service) (1R0739)..... <b>B76-SS +</b> <b>Fuel Ele.</b> (8H7204)..... <b>PF935</b> <b>Fuel Spin-on</b> (Fleetguard FF105)..... <b>BF957 +</b> <b>Fuel Spin-on</b> (1R0751)..... <b>BF7632</b> <b>Radial Seal Air</b> (Don. P527484)... <b>RS2863</b> <b>Radial Seal XP Air</b> (Don. P527484)..... <b>RS2863XP</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>
325 w/Paccar PX-7 (6.7L) Eng. (2020) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	325 w/Paccar PX-7 (6.7L) Eng. (2021) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	330 w/Cat 3126E (7.2L) Eng. <b>F-F Lube</b> (Standard Vers.) (1R0739)..... <b>B76 +</b> <b>F-F Lube</b> (1R1807)..... <b>B7700 +</b> <b>F-F Lube</b> (Severe Service) (1R0739)..... <b>B76-SS +</b> <b>Fuel Ele.</b> (8H7204)..... <b>PF935</b> <b>Fuel Spin-on</b> (Fleetguard FF105)..... <b>BF957 +</b> <b>Fuel Spin-on</b> (1R0751)..... <b>BF7632</b> <b>Radial Seal Air</b> (Don. P527484)... <b>RS2863</b> <b>Radial Seal XP Air</b> (Don. P527484)..... <b>RS2863XP</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>
325 w/Paccar PX-7 (6.7L) Eng. (2022) <b>Lube</b> (3937736)..... <b>B7177</b>	330 w/Cat C7 (7.2L) Eng. <b>Lube</b> (1R1807)..... <b>B7700 +</b> <b>Fuel/Water Separator</b> (Fleetguard FS1022)..... <b>BF1272-SPS</b> <b>Fuel/Water Separator</b> (Fleetguard FS1003)..... <b>BF1293-SPS</b> <b>Fuel/Water Separator</b> (w/o SP) (Racor S3225P)..... <b>BF1348</b> <b>Fuel/Water Separator</b> (w/SP) (Racor S3225P)..... <b>BF1348-SP</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



PETERBILT Trucks (cont'd)	PETERBILT Trucks (cont'd)	PETERBILT Trucks (cont'd)
330 w/Cat 3126E (7.2L) Eng. (Cont'd)	330 w/Cummins ISC 8.3 (8.3L) Eng. (Cont'd)	330 w/Paccar PX-6 (6.7L) Diesel Eng. (2008-13)
<b>Air Dryer</b> (AD-9 System) (Bendix 107796).....	<b>Fuel/Water Separator</b> (Fleetguard FS1003).....	<b>Lube</b> (Fleetguard LF3970).....
<b>BA5377</b>	<b>BF1293-SPS</b>	<b>B7177</b>
<b>Opt. Trans.</b> (Fuller 17237).....	<b>Fuel</b> (Fleetguard FF5488).....	<b>Fuel/Water Separator</b> (Fleetguard FS1003).....
<b>B2+</b>	<b>BF7815</b>	<b>BF1293-SPS</b>
<b>Steering</b> (Nelson 87904M).....	<b>Radial Seal O. Air</b> (Don. P527484).....	<b>Fuel/Water Separator</b> (Fleetguard FS1065).....
<b>PT9354-MPG</b>	<b>RS2863</b>	<b>BF1378-SPS</b>
330 w/Cat 3406 (14.6L) Eng.	<b>Radial Seal XP O. Air</b> (Don. P527484).....	<b>Fuel</b> (Fleetguard FF5632).....
<b>F-F Lube</b> (Std. Version) (1R0716).....	<b>RS2863XP</b>	<b>BF7940</b>
<b>B99+</b>	<b>Radial Seal O. Air</b> (Standard) (3520400-C1).....	<b>Radial Seal Air</b> (Don. P527484)...
<b>F-F Lube</b> (High Efficiency Vers.) (1R1808).....	<b>RS3518</b>	<b>RS2863</b>
<b>B7299+</b>	<b>Radial Seal XP O. Air</b> (Upgrade) (DBA5069).....	<b>Radial Seal XP Air</b> (Don. P527484).....
<b>Fuel/Water Separator</b> (1752949).....	<b>RS3518XP</b>	<b>RS2863XP</b>
<b>BF1268</b>	<b>Disposable Air Hsg.</b> (Farr 400820-023).....	<b>Cab Air</b> (8 1/8 In. Length) (Elixaire 5X010007).....
<b>Fuel/Water Separator</b> (2568753).....	<b>PA5735</b>	<b>PA5320</b>
<b>BF1259</b>	<b>Cab Air</b> (Elixaire 5X010007).....	<b>Cab Air</b> (9 3/32 In. Length) (Elixaire 5S013817).....
<b>Fuel</b> (1R0749).....	<b>PA5320</b>	<b>PA5765</b>
<b>BF7587+</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414).....	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414).....
<b>Fuel</b> (1R0712).....	<b>BA5374+</b>	<b>BA5374+</b>
<b>BF614+</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624).....	<b>Crankcase Breather</b> (4936636)...
330 w/Cummins 6CT8.3 (8.3L) Eng.	<b>BA5373</b>	<b>CV15010</b>
<b>Dual-Flow Lube</b> (3318853).....	<b>Coolant</b> (Fleetguard WF2071).....	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493).....
<b>BD103+</b>	<b>BW5071</b>	<b>PT9416-MPG KIT</b>
<b>Fuel/Water Separator</b> (3903410).....	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493).....	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494).....
<b>BF1280+</b>	<b>PT9416-MPG KIT</b>	<b>PT9415-MPG KIT</b>
<b>Fuel/Water Separator</b> (3286503).....	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494).....	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965).....
<b>BF1226</b>	<b>PT9415-MPG KIT</b>	<b>20004</b>
<b>In-Line Fuel</b> (3826094).....	<b>Opt. Trans. Spin-on</b> (Fuller 17237).....	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965).....
<b>BF1173</b>	<b>B2+</b>	<b>20016</b>
<b>Fuel Spin-on</b> (3903640).....	<b>Steering</b> (Nelson 87904M).....	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966).....
<b>BF788</b>	<b>PT9354-MPG</b>	<b>20003</b>
<b>Radial Seal Air</b> (Don. P527484)...	330 w/Cummins M11 (10.8L) Eng. (To 12/1995)	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966).....
<b>RS2863</b>	<b>Dual-Flow Lube</b> (3318853).....	<b>20017</b>
<b>Radial Seal XP Air</b> (Don. P527484).....	<b>BD103+</b>	<b>Trans. Spin-on</b> (Allison 29539579).....
<b>RS2863XP</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W).....	<b>BT8460</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493).....	<b>PF7680</b>	<b>PT9354-MPG</b>
<b>PT9416-MPG KIT</b>	<b>Fuel/Water Separator Spin-on</b> (3308638).....	<b>PE17000</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494).....	<b>BF1212+</b>	330 w/Paccar PX-6 (6.7L) Electric/Diesel Eng. (2008)
<b>PT9415-MPG KIT</b>	330 w/Cummins M11 (10.8L) Eng. (12/1995-on)	<b>Lube</b> (Fleetguard LF3970).....
330 w/Cummins C8.3 (8.3L) Eng.	<b>Dual-Flow Lube</b> (3318853).....	<b>B7177</b>
<b>F-F Lube</b> .....	<b>BD103+</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1065).....
<b>B205+</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W).....	<b>BF1378-SPS</b>
<b>Dual-Flow Lube</b> (3318853).....	<b>PF7680</b>	<b>BF7940</b>
<b>BD103+</b>	<b>Fuel/Water Separator Spin-on</b> (3329289).....	<b>RS2863</b>
<b>Fuel/Water Separator</b> .....	<b>BF1259</b>	<b>Radial Seal Air</b> (Don. P527484)...
<b>BF1280+</b>	330 w/Cummins N14 (14.0L) Eng.	<b>RS2863</b>
<b>Fuel Ele.</b> (Cat. 8H7204).....	<b>Dual-Flow Lube</b> (3318853).....	<b>Radial Seal XP Air</b> (Don. P527484).....
<b>PF935</b>	<b>BD103+</b>	<b>RS2863XP</b>
<b>S. Fuel Spin-on</b> .....	<b>F-F Lube</b> (Fleetguard LF670SC).....	<b>BA5374+</b>
<b>BF788</b>	<b>B196+</b>	<b>BW5071</b>
<b>Radial Seal Air</b> (Don. P527484)...	<b>B-P Lube</b> (3304232).....	<b>B2+</b>
<b>RS2863</b>	<b>B7577</b>	<b>PT9354-MPG</b>
<b>Radial Seal XP Air</b> (Don. P527484).....	<b>Opt. Fuel/Water Separator</b> (3329289).....	330 w/Cummins ISB (5.9L) Eng.
<b>RS2863XP</b>	<b>BF1259</b>	<b>Lube</b> (3937736).....
<b>Air Dryer</b> (Bendix 109994).....	<b>Fuel</b> (154789).....	<b>B7177</b>
<b>BA5374+</b>	<b>BF957-D+</b>	<b>Fuel</b> (4934845).....
<b>Coolant</b> (3315116).....	<b>BW5071</b>	<b>BF7940</b>
<b>BW5071</b>	<b>Coolant</b> (w/4 Units BTA+) (3315116).....	<b>PF935</b>
<b>Opt. Trans.</b> (Fuller 17237).....	<b>BF5813+</b>	<b>RS2863</b>
<b>B2+</b>	330 w/Detroit Diesel Series 50 (8.5L) Eng.	<b>Radial Seal Air</b> (Don. P527484)...
<b>Steering</b> (Nelson 87904M).....	<b>Lube</b> (23530573).....	<b>RS2863XP</b>
<b>PT9354-MPG</b>	<b>[2] B495</b>	<b>Cab Air</b> (Elixaire 5X010007).....
330 w/Cummins ISB (5.9L) Eng.	<b>Fuel/Water Separator Spin-on</b> (w/Drain) (23535985).....	<b>PA5320</b>
<b>Lube</b> (3937736).....	<b>BF5813+</b>	<b>Air Dryer</b> (Bendix 5008414).....
<b>B7177</b>	<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (23535985).....	<b>BA5374+</b>
<b>Fuel</b> (4934845).....	<b>BF5813-O+</b>	<b>CV15010</b>
<b>BF7940</b>	<b>P. Fuel</b> (23530706).....	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965).....
<b>Radial Seal Air</b> (Don. P527484)...	<b>BF5800+</b>	<b>20004</b>
<b>RS2863</b>	<b>S. Fuel</b> (23530707).....	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965).....
<b>Radial Seal XP Air</b> (Don. P527484).....	<b>BF5810</b>	<b>20016</b>
<b>RS2863XP</b>	330 w/Cummins ISC 8.3 (8.3L) Eng.	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966).....
<b>Crankcase Breather</b> (4936636)...	<b>Dual-Flow Lube</b> .....	<b>20003</b>
<b>CV15010</b>	<b>BD7309+</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966).....
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493).....	<b>Fuel/Water Separator</b> (175-2949).....	<b>20017</b>
<b>PT9416-MPG KIT</b>	<b>BF1268</b>	<b>Trans. Spin-on</b> (Allison 29539579).....
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494).....	<b>BF1272-SPS</b>	<b>BT8460</b>
<b>PT9415-MPG KIT</b>	330 w/Cummins ISC 8.3 (8.3L) Eng.	<b>PT9416-MPG KIT</b>
<b>Trans. Spin-on</b> .....	<b>Dual-Flow Lube</b> .....	
<b>BT595</b>	<b>BD7309+</b>	


\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>
330 w/Paccar PX-6 (6.7L) Electric/Diesel Eng. (2008) (Cont'd) Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	330 w/Paccar PX-7 (6.7L) Eng. (2019) (Cont'd) Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>	330 w/Paccar PX-8 Eng. (Cont'd) <b>Fuel/Water Separator</b> (Fleetguard FS1003)..... <b>BF1293-SPS</b> <b>Fuel</b> (Fleetguard FF5488)..... <b>BF7815</b> <b>Radial Seal Air</b> (Don. P527484)... <b>RS2863</b> <b>Radial Seal XP Air</b> (Don. P527484)..... <b>RS2863XP</b> <b>Cab Air</b> (Elixaire 5X010007)..... <b>PA5320</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>
330 w/Paccar PX-7 (6.7L) Eng. (2014-18) Lube (Fleetguard LF9104)..... <b>B7177</b> Opt. Fuel/Water Separator (Fleetguard FS1065)..... <b>BF1378-SPS</b> Fuel (5303743)..... <b>BF63000</b> Radial Seal Air (Don. P527484)... <b>RS2863</b> Radial Seal XP Air (Don. P527484)..... <b>RS2863XP</b> Cab Air (8 1/8 In. Length) (Elixaire 5X010007)..... <b>PA5320</b> Cab Air (9 3/32 In. Length) (Elixaire 5S013817)..... <b>PA5765</b> Air Dryer (AD-SP System) (Bendix 5008414)..... <b>BA5374 +</b> Air Dryer (Bendix 5008414PG).... <b>BA5379</b> Crankcase Breather (Fleetguard CV50607)..... <b>CV15000</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Diesel Exhaust Fluid (4388378).. <b>PE17002 KIT</b>	330 w/Paccar PX-7 (6.7L) Eng. (2020) Lube (3937736)..... <b>B7177</b> Fuel/Water Separator (Fleetguard FS1003)..... <b>BF1293-SPS</b> Fuel/Water Separator (Fleetguard FS1065)..... <b>BF1378-SPS</b> Fuel (Fleetguard FF63009)..... <b>BF63000</b> Radial Seal XP Air (Don. P527484)..... <b>RS2863XP</b> Cab Air (5S013817)..... <b>PA5765</b> Crankcase Breather (4936636)... <b>CV15010</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	335 w/Cat 3126 (7.2L) Eng. Lube (1R1807)..... <b>B7700 +</b> Fuel/Water Separator (1752949). <b>BF1268</b> Fuel/Water Separator (2568753). <b>BF1259</b> Fuel/Water Separator (w/Sensor Port) (1986378)..... <b>BF7798-SP</b> Fuel/Water Separator (Open End for Bowl) (1986378)..... <b>BF7798-O</b> Fuel Ele. (9M2342)..... <b>[2] PF935</b> Fuel Spin-on (1R0751)..... <b>BF7632</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>
330 w/Paccar PX-7 (6.7L) Eng. (2019) Lube (3937736)..... <b>B7177</b> Fuel/Water Separator (Fleetguard FS1065)..... <b>BF1378-SPS</b> Fuel (5303743)..... <b>BF63000</b> Radial Seal Air (Don. P527484)... <b>RS2863</b> Radial Seal XP Air (Don. P527484)..... <b>RS2863XP</b> Cab Air (5S013817)..... <b>PA5765</b> Crankcase Breather (4936636)... <b>CV15010</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	330 w/Paccar PX-7 (6.7L) Eng. (2021) Lube (3937736)..... <b>B7177</b> Fuel (5303743)..... <b>BF63000</b> Crankcase Breather (CV15010).. <b>CV15010</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>	335 w/Cat C7 (7.2L) Eng. (To 1/2004) Lube (Standard Vers.) (1R0739).. <b>B76 +</b> Lube (Severe Service) (1R0739).. <b>B76-SS +</b> Fuel/Water Separator (175-2949)..... <b>BF1268</b> Fuel (1R0751)..... <b>BF7632</b> Radial Seal Air (Don. P527484)... <b>RS2863</b> Radial Seal XP Air (Don. P527484)..... <b>RS2863XP</b> Cab Air (Elixaire 5X010007)..... <b>PA5320</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Coolant (9N3368)..... <b>BW5137</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
330 w/Paccar PX-7 (6.7L) Eng. (2022) Lube (3937736)..... <b>B7177</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>	330 w/Paccar PX-8 Eng. Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309 +</b> Fuel/Water Separator (Fleetguard FS1000)..... <b>BF1259</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).


PETERBILT Trucks (cont'd)	PETERBILT Trucks (cont'd)	PETERBILT Trucks (cont'd)
335 w/Cat C7 (7.2L) Eng. (To 1/2004) (Cont'd)	335 w/Cummins ISC (8.3L) Eng.	335 w/Cummins ISM Eng. (Cont'd)
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966).....	<b>Dual-Flow Lube</b> (Fleetguard LF9009).....	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494).....
<b>20017</b>	<b>BD7309 +</b>	<b>PT9415-MPG KIT</b>
<b>Trans. Spin-on</b> (Allison 29539579).....	<b>Fuel/Water Separator</b> (Fleetguard FS1022).....	<b>Opt. Trans. Spin-on</b> (Fuller 17237).....
<b>BT8460</b>	<b>BF1272-SPS</b>	<b>B2 +</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493).....	<b>Fuel/Water Separator</b> (Fleetguard FS1003).....	<b>Steering</b> (Nelson 87904M).....
<b>PT9416-MPG KIT</b>	<b>BF1293-SPS</b>	<b>PT9354-MPG</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494).....	<b>Fuel</b> (Fleetguard FF5488).....	335 w/Paccar PX-6 (6.7L) Diesel Eng. (2008-10)
<b>PT9415-MPG KIT</b>	<b>BF7815</b>	<b>Lube</b> (Fleetguard LF3970).....
<b>Opt. Trans. Spin-on</b> (Fuller 17237).....	<b>Fuel</b> (Fleetguard FF5636).....	<b>B7177</b>
<b>B2 +</b>	<b>BF7924</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1065).....
<b>Steering</b> (Nelson 87904M).....	<b>Radial Seal Air</b> (Don. P527484)...	<b>BF1378-SPS</b>
<b>PT9354-MPG</b>	<b>Radial Seal XP Air</b> (Don. P527484).....	<b>Fuel/Water Separator</b> (Fleetguard FS1003).....
335 w/Cat C7 (7.2L) Eng. (1/2004-on)	<b>Disposable Air Hsg.</b> (Farr 400820-023).....	<b>BF1293-SPS</b>
<b>Lube</b> (1R1807).....	<b>PA5735</b>	<b>Fuel</b> (Fleetguard FF5632).....
<b>B7700 +</b>	<b>Cab Air</b> (Elixaire 5X010007).....	<b>BF7940</b>
<b>Fuel/Water Separator</b> (175-2949).....	<b>PA5320</b>	<b>Radial Seal Air</b> (Don. P527484)...
<b>BF1268</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414).....	<b>RS2863</b>
<b>Fuel</b> (1R0751).....	<b>BA5374 +</b>	<b>Radial Seal XP Air</b> (Don. P527484).....
<b>BF7632</b>	<b>Coolant</b> (Fleetguard WF2071).....	<b>RS2863XP</b>
<b>Radial Seal Air</b> (Don. P527484)...	<b>BW5071</b>	<b>RS2863XP</b>
<b>RS2863</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965).....	<b>Fuel/Water Separator</b> (Fleetguard FS1003).....
<b>Radial Seal XP Air</b> (Don. P527484).....	<b>20004</b>	<b>BF1293-SPS</b>
<b>RS2863XP</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965).....	<b>Fuel</b> (Fleetguard FF5632).....
<b>Cab Air</b> (Elixaire 5X010007).....	<b>20016</b>	<b>BF7940</b>
<b>PA5320</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966).....	<b>Radial Seal Air</b> (Don. P527484)...
<b>Air Dryer</b> (Bendix 5008414).....	<b>20003</b>	<b>RS2863</b>
<b>BA5374 +</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966).....	<b>Radial Seal XP Air</b> (Don. P527484).....
<b>Coolant</b> (9N3368).....	<b>20003</b>	<b>RS2863XP</b>
<b>BW5137</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966).....	<b>Fuel/Water Separator</b> (Fleetguard FS1065).....
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965).....	<b>20017</b>	<b>BF1378-SPS</b>
<b>20004</b>	<b>Trans. Spin-on</b> (Allison 29539579).....	<b>Fuel</b> (Fleetguard FF5632).....
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965).....	<b>BT8460</b>	<b>BF7940</b>
<b>20016</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493).....	<b>Radial Seal Air</b> (Don. P527484)...
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966).....	<b>PT9416-MPG KIT</b>	<b>RS2863</b>
<b>20003</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494).....	<b>Radial Seal XP Air</b> (Don. P527484).....
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966).....	<b>PT9415-MPG KIT</b>	<b>RS2863XP</b>
<b>20003</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237).....	<b>Cab Air</b> (Elixaire 5X010007).....
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537965).....	<b>B2 +</b>	<b>PA5320</b>
<b>20016</b>	<b>Steering</b> (Nelson 87904M).....	<b>Air Dryer</b> (Bendix 5008414).....
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966).....	<b>PT9354-MPG</b>	<b>BA5374 +</b>
<b>20003</b>	335 w/Cummins ISM Eng.	<b>Crankcase Breather</b> (4936636)...
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966).....	<b>Dual-Flow Lube</b> (Fleetguard LF9000).....	<b>CV15010</b>
<b>20017</b>	<b>BD7153 +</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493).....
<b>Trans. Spin-on</b> (Allison 29539579).....	<b>Fuel/Water Separator</b> (Fleetguard FS1022).....	<b>PT9416-MPG KIT</b>
<b>BT8460</b>	<b>BF1272-SPS</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494).....
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493).....	<b>BF7815</b>	<b>PT9415-MPG KIT</b>
<b>20003</b>	<b>BF7924</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237).....
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966).....	<b>RS2863</b>	<b>B2 +</b>
<b>20017</b>	<b>Radial Seal Air</b> (Don. P527484)...	<b>Steering</b> (Nelson 87904M).....
<b>Trans. Spin-on</b> (Allison 29539579).....	<b>Radial Seal XP Air</b> (Don. P527484).....	<b>PT9354-MPG</b>
<b>BT8460</b>	<b>RS2863XP</b>	335 w/Paccar PX-6 (6.7L) Electric/Diesel Eng. (2008)
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493).....	<b>Cab Air</b> (Elixaire 5X010007).....	<b>Lube</b> (Fleetguard LF3970).....
<b>PT9416-MPG KIT</b>	<b>PA5320</b>	<b>B7177</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494).....	<b>Coolant</b> (Fleetguard WF2071).....	<b>Fuel/Water Separator</b> (Fleetguard FS1065).....
<b>PT9415-MPG KIT</b>	<b>BW5071</b>	<b>BF1378-SPS</b>
<b>Opt. Trans. Spin-on</b> (Fuller 17237).....	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965).....	<b>Fuel</b> (Fleetguard FF5632).....
<b>B2 +</b>	<b>20004</b>	<b>BF7940</b>
<b>Steering</b> (Nelson 87904M).....	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965).....	<b>Radial Seal Air</b> (Don. P527484)...
<b>PT9354-MPG</b>	<b>20016</b>	<b>RS2863</b>
335 w/Cummins ISB Eng.	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966).....	<b>Radial Seal XP Air</b> (Don. P527484).....
<b>Lube</b> (Fleetguard LF3970).....	<b>20003</b>	<b>RS2863XP</b>
<b>B7177</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966).....	<b>Fuel/Water Separator</b> (Fleetguard FS1065).....
<b>Fuel/Water Separator</b> (Fleetguard FS1065).....	<b>20017</b>	<b>BF1378-SPS</b>
<b>BF1378-SPS</b>	<b>Trans. Spin-on</b> (Allison 29539579).....	<b>Fuel</b> (Fleetguard FF5632).....
<b>Fuel</b> (Fleetguard FF5632).....	<b>BT8460</b>	<b>BF7940</b>
<b>BF7940</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493).....	<b>Radial Seal Air</b> (Don. P527484)...
<b>Radial Seal Air</b> (Don. P527484)...	<b>PT9416-MPG KIT</b>	<b>RS2863</b>
<b>RS2863</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494).....	<b>Radial Seal XP Air</b> (Don. P527484).....
<b>Radial Seal XP Air</b> (Don. P527484).....	<b>PT9415-MPG KIT</b>	<b>RS2863XP</b>
<b>RS2863XP</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237).....	<b>Cab Air</b> (Elixaire 5X010007).....
<b>Air Dryer</b> (AD-IS System) (Bendix 5008414).....	<b>B2 +</b>	<b>PA5320</b>
<b>BA5374 +</b>	<b>Steering</b> (Nelson 87904M).....	<b>Air Dryer</b> (Bendix 5008414).....
<b>Crankcase Breather</b> (Fleetguard CV52001).....	<b>PT9354-MPG</b>	<b>BA5374 +</b>
<b>CV15010</b>	335 w/Cummins ISM Eng.	<b>Crankcase Breather</b> (4936636)...
<b>Trans.</b> (2 In. Kit) (Allison 29540493).....	<b>Dual-Flow Lube</b> (Fleetguard LF9000).....	<b>CV15010</b>
<b>PT9416-MPG KIT</b>	<b>BD7153 +</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493).....
<b>Trans.</b> (4 In. Kit) (Allison 29540494).....	<b>Fuel/Water Separator</b> (Fleetguard FS1022).....	<b>PT9416-MPG KIT</b>
<b>PT9415-MPG KIT</b>	<b>BF1272-SPS</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494).....
	<b>BF7815</b>	<b>PT9415-MPG KIT</b>
	<b>BF7924</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237).....
	<b>BF7924</b>	<b>B2 +</b>
	<b>RS2863</b>	<b>Steering</b> (Nelson 87904M).....
	<b>RS2863XP</b>	<b>PT9354-MPG</b>
	<b>PA5320</b>	
	<b>BW5071</b>	
	<b>20004</b>	
	<b>20016</b>	
	<b>20003</b>	
	<b>20017</b>	
	<b>BT8460</b>	
	<b>PT9416-MPG KIT</b>	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>
335 w/Paccar PX-8 (8.3L) Eng. Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309 +</b> Fuel/Water Separator (Fleetguard FS1000)..... <b>BF1259</b> Fuel/Water Separator (Fleetguard FS1003)..... <b>BF1293-SPS</b> Fuel/Water Separator (Fleetguard FS1065)..... <b>BF1378-SPS</b> Fuel (Fleetguard FF5488)..... <b>BF7815</b> Fuel (4940647)..... <b>BF7924</b> Radial Seal Air (Don. P527484)... <b>RS2863</b> Radial Seal XP Air (Don. P527484)..... <b>RS2863XP</b> Cab Air (Elixaire 5X010007)..... <b>PA5320</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	337 w/Cummins ISL-G (8.9L) Eng. (2016-17) (Cont'd) Trans. Ele. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> 337 w/Cummins ISL-G (8.9L) Eng. (2018) Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309 +</b> Fuel/Water Separator (Fleetguard NG5900)..... <b>BF7695</b> Radial Seal Air (Don. P527484)... <b>RS2863</b> Radial Seal XP Air (Don. P527484)..... <b>RS2863XP</b> Cab Air (5X013817)..... <b>PA5765</b> Air Dryer (Bendix 5008414PG).... <b>BA5379</b> Coolant (w/4 Units BTA +) (Fleetguard WF2071)..... <b>BW5071</b> Coolant (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b> 337 w/Cummins ISL-G (8.9L) Eng. (2019) Lube (Fleetguard LF9009)..... <b>B40142</b> Fuel/Water Separator (Fleetguard NG5900)..... <b>BF7695</b> Radial Seal Air (Don. P527484)... <b>RS2863</b> Radial Seal XP Air (Don. P527484)..... <b>RS2863XP</b> Cab Air (5S013817)..... <b>PA5765</b> Air Dryer (Bendix 5008414PG).... <b>BA5379</b> Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> Coolant (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> 337 w/Cummins ISL-G (8.9L) Eng. (2020) Lube (Fleetguard LF9009)..... <b>B40142</b> Fuel (Fleetguard NG5900)..... <b>BF7695</b> Radial Seal XP Air (Don. P527484)..... <b>RS2863XP</b> Cab Air (5S013817)..... <b>PA5765</b> Air Dryer (Bendix 5008414PG).... <b>BA5379</b>	337 w/Cummins ISL-G (8.9L) Eng. (2020) (Cont'd) Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b> 337 w/Cummins ISL-G (8.9L) Eng. (2022) Lube (5444774)..... <b>B40142</b> Fuel/Water Separator (3607140)..... <b>BF7695</b> 337 w/Paccar PX-6 (6.7L) Eng. Lube (Fleetguard LF3970)..... <b>B7177</b> Fuel/Water Separator (Fleetguard FS1065)..... <b>BF1378-SPS</b> Fuel (Fleetguard FF5632)..... <b>BF7940</b> Radial Seal Air (Don. P527484)... <b>RS2863</b> Radial Seal XP Air (Don. P527484)..... <b>RS2863XP</b> Cab Air (5S013817)..... <b>PA5765</b> Air Dryer (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> Crankcase Breather (Fleetguard CV52001)..... <b>CV15010</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Diesel Exhaust Fluid (2010 Emissions) (2888182)..... <b>PE17000</b> 337 w/Paccar PX-7 (6.7L) Eng. (2014-18) Lube (Fleetguard LF9104)..... <b>B7177</b> Fuel/Water Separator (Fleetguard FS1065)..... <b>BF1378-SPS</b> Fuel (Fleetguard FF63009)..... <b>BF63000</b> Radial Seal Air (Don. P527484)... <b>RS2863</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

PETERBILT Trucks (cont'd)	PETERBILT Trucks (cont'd)	PETERBILT Trucks (cont'd)
337 w/Paccar PX-7 (6.7L) Eng. (2014-18) (Cont'd)	337 w/Paccar PX-7 (6.7L) Eng. (2020)	337 w/Paccar PX-7 (6.7L) Eng. (2022) (Cont'd)
Radial Seal XP Air (Don. P527484)..... <b>RS2863XP</b>	Lube (3937736)..... <b>B7177</b>	Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>
Cab Air (5S013817)..... <b>PA5765</b>	Fuel/Water Separator (Fleetguard FS1003)..... <b>BF1293-SPS</b>	Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
Air Dryer (Bendix 5008414)..... <b>BA5374 +</b>	Fuel/Water Separator (Fleetguard FS1065)..... <b>BF1378-SPS</b>	Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
Air Dryer (Bendix 5008414PG).... <b>BA5379</b>	Fuel (Fleetguard FF63009)..... <b>BF63000</b>	
Breather (Rear Eng. Mounted) (Fleetguard CV50607)..... <b>CV15000</b>	Radial Seal XP Air (Don. P527484)..... <b>RS2863XP</b>	337 w/Paccar PX-7 (6.7L) Eng. (2023)
Crankcase Breather (4936636).... <b>CV15010</b>	Cab Air (5S013817)..... <b>PA5765</b>	Lube (3937736)..... <b>B7177</b>
Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	Air Dryer (Bendix 5008414)..... <b>BA5374 +</b>	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	Crankcase Breather (4936636).... <b>CV15010</b>	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>
Trans. Ele. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	
Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	Fuel/Water Separator (Fleetguard FS1003)..... <b>BF1293-SPS</b>
Trans. Spin-on (Fuller 4304827).. <b>BT223</b>	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	Fuel/Water Separator (Fleetguard FS1065)..... <b>BF1378-SPS</b>
Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>	Fuel (4940647)..... <b>BF7924</b>
Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	Radial Seal Air (Don. P527484)... <b>RS2863</b>
Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	Radial Seal XP Air (Don. P527484)..... <b>RS2863XP</b>
Diesel Exhaust Fluid (5303604).. <b>PE17000</b>	337 w/Paccar PX-7 (6.7L) Eng. (2021)	Cab Air (5S013817)..... <b>PA5765</b>
Diesel Exhaust Fluid (5303604).. <b>PE17000</b>	Lube (3937736)..... <b>B7177</b>	Air Dryer (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>
337 w/Paccar PX-7 (6.7L) Eng. (2019)	Fuel/Water Separator (4934879). <b>BF1378-SPS</b>	Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
Lube (3937736)..... <b>B7177</b>	Fuel (5303743)..... <b>BF63000</b>	Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
Fuel/Water Separator (4934879). <b>BF1378-SPS</b>	Crankcase Breather (4936636).... <b>CV15010</b>	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
Fuel (5303743)..... <b>BF63000</b>	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20016</b>	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20016</b>
Radial Seal Air (Don. P527484)... <b>RS2863</b>	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537966)..... <b>20016</b>
Radial Seal XP Air (Don. P527484)..... <b>RS2863XP</b>	Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
Cab Air (5S013817)..... <b>PA5765</b>	Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>
Air Dryer (Bendix 5008414PG).... <b>BA5379</b>	Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Steering (Nelson 87904M)..... <b>PT9354-MPG</b>
Crankcase Breather (4936636).... <b>CV15010</b>		Diesel Exhaust Fluid (2010 Emissions) (2888182)..... <b>PE17000</b>
Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	337 w/Paccar PX-7 (6.7L) Eng. (2022)	337 w/Paccar PX-9 (8.9L) Eng. (2014-18)
Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	Lube (3937736)..... <b>B7177</b>	Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309 +</b>
Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	Fuel/Water Separator (Fleetguard FS1065)..... <b>BF1378-SPS</b>
Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	Fuel/Water Separator (Fleetguard FS1003)..... <b>BF1293-SPS</b>
Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	Fuel (Fleetguard FF63009)..... <b>BF63000</b>
Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>	Radial Seal Air (Don. P527484)... <b>RS2863</b>
Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	
Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>
337 w/Paccar PX-9 (8.9L) Eng. (2014-18) (Cont'd)	337 w/Paccar PX-9 (8.9L) Eng. (2020) (Cont'd)	340 w/Cummins ISC 8.3 (8.3L) Eng.
Radial Seal XP Air (Don. P527484)..... <b>RS2863XP</b>	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	Dual-Flow Lube (3401544)..... <b>BD7309 +</b>
Cab Air (5S013817)..... <b>PA5765</b>	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	Lube (Upgrade) (3401544)..... <b>B40142 +</b>
Air Dryer (Bendix 5008414)..... <b>BA5374 +</b>	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	Fuel/Water Separator (Fleetguard FS19596)..... <b>BF1293-SPS</b>
Air Dryer (Bendix 5008414PG).... <b>BA5379</b>	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	Fuel/Water Separator (Fleetguard FS1065)..... <b>BF1378-SPS</b>
Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>	Fuel (Fleetguard FF5636)..... <b>BF7924</b>
Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	Fuel (3959612)..... <b>BF7815</b>
Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	Radial Seal Air (Don. P527484)... <b>RS2863</b>
Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	337 w/Paccar PX-9 (8.9L) Eng. (2021)	Radial Seal XP Air (Don. P527484)..... <b>RS2863XP</b>
Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>	Lube (5444774)..... <b>B40142</b>	Cab Air (Elixaire 5X010007)..... <b>PA5320</b>
Trans. Ele. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	Fuel (5303743)..... <b>BF63000</b>	Air Dryer (Bendix 5008414)..... <b>BA5374 +</b>
Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>
Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	Steering (Nelson 87904M)..... <b>PT9354-MPG</b>
Diesel Exhaust Fluid (5303604).... <b>PE17000</b>	Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>	340 w/Paccar PX-6 Eng
337 w/Paccar PX-9 (8.9L) Eng. (2019)	Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	Lube (Fleetguard LF3970)..... <b>B7177</b>
Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309 +</b>	Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Fuel/Water Separator (Fleetguard FS1065)..... <b>BF1378-SPS</b>
Fuel/Water Separator (Fleetguard FS1003)..... <b>BF1293-SPS</b>	337 w/Paccar PX-9 (8.9L) Eng. (2022)	Fuel (Fleetguard FF5632)..... <b>BF7940</b>
Fuel (Fleetguard FF63009)..... <b>BF63000</b>	Lube (5444774)..... <b>B40142</b>	Radial Seal Air (Don. P527484)... <b>RS2863</b>
Radial Seal Air (Don. P527484).... <b>RS2863</b>	Fuel/Water Separator (Fleetguard FS1003)..... <b>BF1293-SPS</b>	Radial Seal XP Air (Don. P527484)..... <b>RS2863XP</b>
Radial Seal XP Air (Don. P527484)..... <b>RS2863XP</b>	Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	Cab Air (Elixaire 5X010007)..... <b>PA5320</b>
Cab Air (5S013817)..... <b>PA5765</b>	Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Air Dryer (Bendix 5008414)..... <b>BA5374 +</b>
Air Dryer (Bendix 5008414PG).... <b>BA5379</b>	337 w/Paccar PX-9 (8.9L) Eng. (2023)	Crankcase Breather (4936636)... <b>CV15010</b>
Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	Lube (5520789)..... <b>B40142</b>	Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	340 w/Cat C7 Eng.	Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	Lube (1R1807)..... <b>B7700 +</b>	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>
Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	Fuel/Water Separator (175-2949)..... <b>BF1268</b>	Steering (Nelson 87904M)..... <b>PT9354-MPG</b>
Diesel Exhaust Fluid (4388378).. <b>PE17002 KIT</b>	Fuel (1R0751)..... <b>BF7632</b>	340 w/Paccar PX-8 (8.3L)Eng
337 w/Paccar PX-9 (8.9L) Eng. (2020)	Radial Seal Air (Fleetguard AF4878)..... <b>RS2863</b>	Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309 +</b>
Lube (3401544)..... <b>B40142</b>	Radial Seal XP Air (Fleetguard AF4878)..... <b>RS2863XP</b>	Fuel/Water Separator (Fleetguard FS1000)..... <b>BF1259</b>
Fuel/Water Separator (Fleetguard FS1003)..... <b>BF1293-SPS</b>	Cab Air (Elixaire 5X010007)..... <b>PA5320</b>	Fuel/Water Separator (Fleetguard FS1003)..... <b>BF1293-SPS</b>
Fuel (5303743)..... <b>BF63000</b>	Air Dryer (Bendix 5008414)..... <b>BA5374 +</b>	Fuel/Water Separator (Fleetguard FS1065)..... <b>BF1378-SPS</b>
Radial Seal XP Air (Don. P5278484)..... <b>RS2863XP</b>	Coolant..... <b>BW5071</b>	Fuel (Fleetguard FF5488)..... <b>BF7815</b>
Cab Air (5S013817)..... <b>PA5765</b>	Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	Fuel (Fleetguard FF5636)..... <b>BF7924</b>
Air Dryer (Bendix 5008414)..... <b>BA5374 +</b>	Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Radial Seal Air (Don. P527484)... <b>RS2863</b>
Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	Radial Seal XP Air (Don. P527484)..... <b>RS2863XP</b>
Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>		Cab Air (Elixaire 5X010007)..... <b>PA5320</b>
		Air Dryer (Bendix 5008414)..... <b>BA5374 +</b>
		Opt. Coolant (Fleetguard WF2071)..... <b>BW5071</b>
		Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>
340 w/Paccar PX-8 (8.3L) Eng (Cont'd) Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Diesel Exhaust Fluid</b> (2880298).. <b>PE17000</b>	348 w/Cummins ISL-G (8.9L) Eng. (2018) (Cont'd) <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	348 w/Cummins L10 (10.0L) Eng. (Cont'd) <b>Opt. Fuel/Water Separator</b> (3308638)..... <b>BF1212 +</b> <b>Fuel</b> (154789)..... <b>BF957-D +</b> <b>Coolant</b> (w/4 Units BTA+) (3315116)..... <b>BW5071</b> <b>Coolant</b> (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b>
346, 348 w/Cat 1160 Eng. <b>Lube</b> ..... <b>[2] BT364</b> <b>Fuel</b> ..... <b>BF583</b>	348 w/Cummins ISL-G (8.9L) Eng. (2019) <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel/Water Separator</b> (Fleetguard NG5900)..... <b>BF7695</b> <b>Radial Seal Air</b> (Don. P527484)... <b>RS2863</b> <b>Radial Seal XP Air</b> (Don. P527484)..... <b>RS2863XP</b> <b>Cab Air</b> (5S013770)..... <b>PA5765</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Coolant</b> (w/4 Units BTA +) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b> <b>Trans.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9354-MPG</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9415-MPG KIT</b>	348 w/Cummins N14 (14.0L) Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Opt. Fuel/Water Separator</b> (3308638)..... <b>BF1212 +</b> <b>Fuel</b> (154789)..... <b>BF957-D +</b> <b>Coolant</b> (w/4 Units BTA+) (3315116)..... <b>BW5071</b>
346, 348, 349, 375, 377, 379 w/Cat 3306 (10.5L) Eng. <b>Lube</b> (Standard Vers.) (1R0739).. <b>B76</b> <b>Fuel/Water Separator Box-Style</b> ..... <b>BF912</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1212)..... <b>BF1212 +</b> <b>Fuel</b> (1P2299)..... <b>BF970 +</b> <b>Fuel</b> (1R0750)..... <b>BF7633 +</b> <b>13 1/2 In. Std. Opt. Air</b> (4M9334). <b>PA1634</b> <b>13 1/2 In. Opt. Air</b> (Upgrade) (4M9334)..... <b>PA1634XP</b> <b>22 13/16 In. Air</b> (Don. P181007)... <b>PA2312</b> <b>Cab Air</b> (Elixair 5X010007)..... <b>PA5320</b> <b>Air Dryer</b> (AD-SP System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	348 w/Cummins ISL-G (8.9L) Eng. (2020) <b>Lube</b> (Fleetguard LF9009)..... <b>B40142</b> <b>Fuel</b> (Fleetguard NG5900)..... <b>BF7695</b> <b>Radial Seal Air</b> (Don. P527484)... <b>RS2863</b> <b>Radial Seal XP Air</b> (Don. P527484)..... <b>RS2863XP</b> <b>Cab Air</b> (5S013817)..... <b>PA5765</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	348 w/Paccar PX-6 (6.7L) Eng. (2011-12) <b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b> <b>Fuel</b> (Fleetguard FF5632)..... <b>BF7940</b> <b>Disposable Air Hsg.</b> (Farr 400820023)..... <b>PA5735</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
348 w/Cummins ISL-G (8.9L) Eng. (2016-17) <b>Dual-Flow Lube</b> (3401544)..... <b>BD7309 +</b> <b>Lube</b> (Upgrade) (3401544)..... <b>B40142 +</b> <b>Radial Seal Air</b> (Don. P527484)... <b>RS2863</b> <b>Radial Seal XP Air</b> (Don. P527484)..... <b>RS2863XP</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	348 w/Cummins ISL-G (8.9L) Eng. (2018) <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel/Water Separator</b> (Fleetguard NG5900)..... <b>BF7695</b> <b>Radial Seal Air</b> (Fleetguard AF25033M)..... <b>RS3530</b> <b>Radial Seal XP Air</b> (Fleetguard AF25033M)..... <b>RS3530XP</b> <b>Cab Air</b> (5X013817)..... <b>PA5765</b> <b>Air Dryer</b> (Bendix 5008414PG)... <b>BA5379</b> <b>Coolant</b> (w/4 Units BTA +) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	348 w/Paccar PX-7 (6.7L) Eng. (2018) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Radial Seal Air</b> (Fleetguard AF25033M)..... <b>RS3530</b> <b>Radial Seal XP Air</b> (Fleetguard AF25033M)..... <b>RS3530XP</b> <b>Cab Air</b> (5X013817)..... <b>PA5765</b> <b>Air Dryer</b> (Bendix 5008414PG)... <b>BA5379</b> <b>Crankcase Breather</b> (Fleetguard CV52001)..... <b>CV15010</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (4388378).. <b>PE17002 KIT</b>
348 w/Cummins ISL-G (8.9L) Eng. (2018) <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel/Water Separator</b> (Fleetguard NG5900)..... <b>BF7695</b> <b>Radial Seal Air</b> (Fleetguard AF25033M)..... <b>RS3530</b> <b>Radial Seal XP Air</b> (Fleetguard AF25033M)..... <b>RS3530XP</b> <b>Cab Air</b> (5X013817)..... <b>PA5765</b> <b>Air Dryer</b> (Bendix 5008414PG)... <b>BA5379</b> <b>Coolant</b> (w/4 Units BTA +) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	348 w/Cummins ISL-G (8.9L) Eng. (2022) <b>Lube</b> (5444774)..... <b>B40142</b> <b>Fuel/Water Separator</b> (3607140). <b>BF7695</b>	348 w/Paccar PX-7 (6.7L) Eng. (2019) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Radial Seal Air</b> (Don. P527484)... <b>RS2863</b>
348 w/Cummins ISL-G (8.9L) Eng. (2018) <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel/Water Separator</b> (Fleetguard NG5900)..... <b>BF7695</b> <b>Radial Seal Air</b> (Fleetguard AF25033M)..... <b>RS3530</b> <b>Radial Seal XP Air</b> (Fleetguard AF25033M)..... <b>RS3530XP</b> <b>Cab Air</b> (5X013817)..... <b>PA5765</b> <b>Air Dryer</b> (Bendix 5008414PG)... <b>BA5379</b> <b>Coolant</b> (w/4 Units BTA +) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	348 w/Cummins L10 (10.0L) Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>
348 w/Paccar PX-7 (6.7L) Eng. (2019) (Cont'd) Radial Seal XP Air (Don. P527484)..... <b>RS2863XP</b> Cab Air (5S013770)..... <b>PA5765</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Crankcase Breather (4936636).... <b>CV15010</b> Trans. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Rear Axle (Meritor 3280V8394).... <b>B233</b>	348 w/Paccar PX-8 (8.3L) Eng. (2010-13) (Cont'd) Radial Seal Air (Don. P527484).... <b>RS2863</b> Radial Seal XP Air (Don. P527484)..... <b>RS2863XP</b> Cab Air (10 13/16 In. Length) (23-15619)..... <b>PA5320</b> Cab Air (13 11/32 In. Length) (5S013817)..... <b>PA5765</b> Air Dryer (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Diesel Exhaust Fluid (2010 Emissions) (2880298)..... <b>PE17000</b>	348 w/Paccar PX-9 (8.9L) Eng. (2019) (Cont'd) Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Diesel Exhaust Fluid (4388378).. <b>PE17002 KIT</b>
348 w/Paccar PX-7 (6.7L) Eng. (2020) Lube (3937736)..... <b>B7177</b> Fuel/Water Separator (Fleetguard FS1003)..... <b>BF1293-SPS</b> Fuel (Fleetguard FF63009)..... <b>BF63000</b> Radial Seal Air (Don. P527484).... <b>RS2863</b> Radial Seal XP Air (Don. P527484)..... <b>RS2863XP</b> Cab Air (5S013817)..... <b>PA5765</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Crankcase Breather (4936636).... <b>CV15010</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	348 w/Paccar PX-9 (8.9L) Eng. (2014-18) Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309 +</b> Fuel/Water Separator (Fleetguard FS1003)..... <b>BF1293-SPS</b> Fuel/Water Separator (Fleetguard FS1065)..... <b>BF1378-SPS</b> Fuel (Fleetguard FF63009)..... <b>BF63000</b> Radial Seal Air (Don. P527484).... <b>RS2863</b> Radial Seal XP Air (Don. P527484)..... <b>RS2863XP</b> Radial Seal Air (Fleetguard AF25033M)..... <b>RS3530</b> Radial Seal XP Air (Fleetguard AF25033M)..... <b>RS3530XP</b> Cab Air (5S013817)..... <b>PA5765</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Air Dryer (Bendix 5008414PG).... <b>BA5379</b> Trans. Ele. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Diesel Exhaust Fluid (4388378).. <b>PE17002 KIT</b> Diesel Exhaust Fluid (5303604).. <b>PE17000</b>	348 w/Paccar PX-9 (8.9L) Eng. (2020) Lube (3401544)..... <b>B40142</b> Fuel/Water Separator (Fleetguard FS1003)..... <b>BF1293-SPS</b> Fuel (5303743)..... <b>BF63000</b> Radial Seal Air (Don. P527484).... <b>RS2863</b> Radial Seal XP Air (Don. P527484)..... <b>RS2863XP</b> Cab Air (5S013817)..... <b>PA5765</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>
348 w/Paccar PX-7 (6.7L) Eng. (2021) Lube (3937736)..... <b>B7177</b> Fuel (5303743)..... <b>BF63000</b> Crankcase Breather (4936636).... <b>CV15010</b>	348 w/Paccar PX-9 (8.9L) Eng. (2021-18) Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309 +</b> Fuel/Water Separator (Fleetguard FS1003)..... <b>BF1293-SPS</b> Fuel (Fleetguard FF63009)..... <b>BF63000</b> Radial Seal Air (Don. P527484).... <b>RS2863</b> Radial Seal XP Air (Don. P527484)..... <b>RS2863XP</b> Cab Air (5S013817)..... <b>PA5765</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Air Dryer (Bendix 5008414PG).... <b>BA5379</b> Trans. Ele. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Diesel Exhaust Fluid (4388378).. <b>PE17002 KIT</b> Diesel Exhaust Fluid (5303604).. <b>PE17000</b>	348 w/Paccar PX-9 (8.9L) Eng. (2021) Lube (5444774)..... <b>B40142</b> Fuel/Water Separator (Fleetguard FS1003)..... <b>BF1293-SPS</b> Fuel (5303743)..... <b>BF63000</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b>
348 w/Paccar PX-7 (6.7L) Eng. (2022) Lube (3937736)..... <b>B7177</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	348 w/Paccar PX-9 (8.9L) Eng. (2019) Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309 +</b> Fuel/Water Separator (Fleetguard FS1003)..... <b>BF1293-SPS</b> Fuel (Fleetguard FF63009)..... <b>BF63000</b> Radial Seal Air (Don. P527484).... <b>RS2863</b> Radial Seal XP Air (Don. P527484)..... <b>RS2863XP</b> Cab Air (5S013770)..... <b>PA5765</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b>	348 w/Paccar PX-9 (8.9L) Eng. (2022) Lube (5444774)..... <b>B40142</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>
348 w/Paccar PX-8 (8.3L) Eng. (2010-13) Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309 +</b> Fuel/Water Separator (Fleetguard FS1003)..... <b>BF1293-SPS</b> Fuel/Water Separator (Fleetguard FS1065)..... <b>BF1378-SPS</b> Fuel (Fleetguard FF5636)..... <b>BF7924</b> Fuel (Fleetguard FF5632)..... <b>BF7940</b> Disposable Air Hsg. (Farr 400820023)..... <b>PA5735</b>	348 w/Paccar PX-9 (8.9L) Eng. (2023) Lube (5520789)..... <b>B40142</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	349 w/Cat 3406 (14.6L) Eng. F-F Lube (Std. Version) (1R0716)..... <b>B99 +</b> F-F Lube (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



<b>PETERBILT Trucks (cont'd)</b>	
349 w/Cat 3406 (14.6L) Eng. (Cont'd)	
Fuel/Water Separator (1752949).....	<b>BF1268</b>
Fuel/Water Separator (2568753).....	<b>BF1259</b>
Fuel (1R0749).....	<b>BF7587 +</b>
Fuel (1R0712).....	<b>BF614 +</b>
349 w/Cummins L10 (10.0L) Eng.	
Dual-Flow Lube (3318853).....	<b>BD103 +</b>
F-F Lube (Fleetguard LF670SC)..	<b>B196 +</b>
B-P Lube (3304232).....	<b>B7577</b>
Opt. Fuel/Water Separator (3308638).....	<b>BF1212 +</b>
Fuel (154789).....	<b>BF957-D +</b>
Coolant (w/4 Units BTA+) (3315116).....	<b>BW5071</b>
Coolant (w/15 Units BTA+) (Fleetguard WF2075).....	<b>BW5075</b>
349 w/Cummins N14 (14.0L) Eng.	
Dual-Flow Lube (3318853).....	<b>BD103 +</b>
F-F Lube (Fleetguard LF670SC)..	<b>B196 +</b>
B-P Lube (3304232).....	<b>B7577</b>
Opt. Fuel/Water Separator (3308638).....	<b>BF1212 +</b>
Fuel (154789).....	<b>BF957-D +</b>
Coolant (w/4 Units BTA+) (3315116).....	<b>BW5071</b>
349 w/Cummins VT225 (9.1L) Eng.	
F-F Lube (3313281).....	<b>B205 +</b>
B-P Lube (3304232).....	<b>B7577</b>
Fuel (158172).....	<b>BF957 +</b>
Coolant (w/4 Units BTA+) (3315116).....	<b>BW5071</b>
349 w/Cummins VT903 (14.8L) Eng.	
F-F Lube Ele. (158139).....	<b>P999-HD</b>
F-F Lube Spin-on (3313279).....	<b>B96 +</b>
B-P Lube Ele. (256838).....	<b>C750-E +</b>
B-P Lube Spin-on (3313283).....	<b>B7577</b>
Fuel/Water Separator (3308638).....	<b>BF1212 +</b>
Fuel (156172).....	<b>BF957-D +</b>
349, 352, 359 w/Detroit Diesel Series 60 Eng.	
F-F Lube Ele.....	<b>P20-HD</b>
F-F Lube Spin-on.....	<b>B95 +</b>
Fuel/Water Separator (Fleetguard FS1212).....	<b>BF1212 +</b>
P. Fuel Spin-on.....	<b>BF5800 +</b>
S. Fuel Spin-on.....	<b>BF5810</b>
Air (Don. P181008).....	<b>[2] PA2317 +</b>
Air Dryer (Wabco R950011).....	<b>BA5374 +</b>
Coolant (Fleetguard WF2075).....	<b>BW5075</b>
Opt. Trans. (Fuller 17237).....	<b>B2 +</b>
Steering (Nelson 87972A).....	<b>PT9386-MPG</b>
352 w/Cat 3406 (14.6L) Eng.	
F-F Lube (Std. Version) (1R0716).....	<b>B99 +</b>
F-F Lube (High Efficiency Vers.) (1R1808).....	<b>B7299 +</b>
Fuel/Water Separator (1752949).....	<b>BF1268</b>
Fuel/Water Separator (2568753).....	<b>BF1259</b>
Fuel (1R0749).....	<b>BF7587 +</b>

<b>PETERBILT Trucks (cont'd)</b>	
352 w/Cat 3406 (14.6L) Eng. (Cont'd)	
Fuel (1R0712).....	<b>BF614 +</b>
352 w/Cummins N14 (14.0L) Eng.	
Dual-Flow Lube (3318853).....	<b>BD103 +</b>
F-F Lube (Fleetguard LF670SC)..	<b>B196 +</b>
B-P Lube (3304232).....	<b>B7577</b>
Opt. Fuel/Water Separator (3308638).....	<b>BF1212 +</b>
Fuel (154789).....	<b>BF957-D +</b>
Coolant (w/4 Units BTA+) (3315116).....	<b>BW5071</b>
353 w/Cat 3306 (10.5L) Eng.	
Lube Ele. (5S0484).....	<b>PT670</b>
Lube Spin-on (1R0716).....	<b>B99 +</b>
Lube Spin-on (Standard Vers.) (1R0739).....	<b>B76 +</b>
Lube Spin-on (Severe Service) (1R0739).....	<b>B76-SS +</b>
P. Fuel Ele. (9M2342).....	<b>PF935</b>
P. Fuel Spin-on (1R1740).....	<b>BF970 +</b>
S. Fuel Spin-on (1R0750).....	<b>BF7633 +</b>
353 w/Cat 3406 (14.6L) Eng.	
F-F Lube (Std. Version) (1R0716).....	<b>B99 +</b>
F-F Lube (High Efficiency Vers.) (1R1808).....	<b>B7299 +</b>
Fuel/Water Separator (1752949).....	<b>BF1268</b>
Fuel/Water Separator (2568753).....	<b>BF1259</b>
Fuel (1R0749).....	<b>BF7587 +</b>
Fuel (1R0712).....	<b>BF614 +</b>
353 w/Cat 3408 (18.0L) Eng.	
F-F Lube (1R0716).....	<b>[2] B99 +</b>
Fuel Ele. (9M2342).....	<b>[2] PF935</b>
Fuel Spin-on (4N5823).....	<b>BF614 +</b>
Fuel Spin-on (1R0749).....	<b>BF7587 +</b>
353 w/Cummins N14 (14.0L) Eng.	
Dual-Flow Lube (3318853).....	<b>BD103 +</b>
F-F Lube (Fleetguard LF670SC)..	<b>B196 +</b>
B-P Lube (3304232).....	<b>B7577</b>
Opt. Fuel/Water Separator (3308638).....	<b>BF1212 +</b>
Fuel (154789).....	<b>BF957-D +</b>
Coolant (w/4 Units BTA+) (3315116).....	<b>BW5071</b>
353 w/Cummins VT903 (14.8L) Eng.	
F-F Lube Ele. (158139).....	<b>P999-HD</b>
F-F Lube Spin-on (3313279).....	<b>B96 +</b>
B-P Lube Ele. (256838).....	<b>C750-E +</b>
B-P Lube Spin-on (3313283).....	<b>B7577</b>
Fuel/Water Separator (3308638).....	<b>BF1212 +</b>
Fuel (156172).....	<b>BF957-D +</b>
357 w/Cat C7 (7.2L) Eng. (To 1/2004)	
Lube (Standard Vers.) (1R0739).....	<b>B76 +</b>
Lube (1R1808).....	<b>B7299 +</b>
Lube (Severe Service) (1R0739).....	<b>B76-SS +</b>
Fuel/Water Separator (1752949).....	<b>BF1268</b>

<b>PETERBILT Trucks (cont'd)</b>	
357 w/Cat C7 (7.2L) Eng. (1/2004-on)	
Lube (1R1807).....	<b>B7700 +</b>
Lube (1R1808).....	<b>B7299 +</b>
Fuel/Water Separator (1752949).....	<b>BF1268</b>
357 w/Cat C9 Eng.	
Lube (1R1808).....	<b>B7299 +</b>
Fuel Spin-on (1R0751).....	<b>BF7632</b>
Remote Mtd. Fuel Spin-on.....	<b>BF957 +</b>
Radial Seal Air (Don. P605322)...	<b>RS3516</b>
Radial Seal XP Air (Don. DBA5106).....	<b>RS3516XP</b>
Air Dryer (AD-IP System) (Bendix 65624).....	<b>BA5373</b>
Coolant.....	<b>BW5071</b>
Trans. Ele. (2 In. Kit) (Allison 29540493).....	<b>PT9416-MPG KIT</b>
Trans. Ele. (4 In. Kit) (Allison 29540494).....	<b>PT9415-MPG KIT</b>
357 w/Cat C10 (10.3L) Eng. (To 1/2004)	
F-F Lube (1R0716).....	<b>B99 +</b>
B-P Lube.....	<b>B7577</b>
Fuel/Water Separator Ele.....	<b>PF316</b>
Fuel/Water Separator Spin-on.....	<b>BF5812</b>
Fuel Ele.....	<b>[2] PF935</b>
Fuel Spin-on (1R0749).....	<b>BF7587 +</b>
Fuel Spin-on (1R0712).....	<b>BF614 +</b>
Fuel Spin-on (Fleetguard FF105).....	<b>BF957 +</b>
Axial Seal Air (Don. P522293).....	<b>PA2732</b>
Radial Seal Air.....	<b>RS3539</b>
Cab Air (Elixair 5X010007).....	<b>PA5320</b>
Air Dryer (AD-SP System) (Bendix 5008414).....	<b>BA5374 +</b>
Air Dryer (AD-9 System) (Bendix 107796).....	<b>BA5377</b>
Coolant (w/o Chemical) (Fleetguard WF2127).....	<b>B5087</b>
Coolant (w/Chemical) (Fleetguard WF2071).....	<b>BW5071</b>
Opt. Trans. (Fuller 17237).....	<b>B2 +</b>
Steering (Nelson 87904M).....	<b>PT9354-MPG</b>
357 w/Cat C10 (10.3L) Eng. (1/2004-on)	
F-F Lube (1R1808).....	<b>B7299 +</b>
B-P Lube.....	<b>B7577</b>
Fuel/Water Separator Ele.....	<b>PF316</b>
Fuel/Water Separator Spin-on.....	<b>BF5812</b>
Fuel Ele.....	<b>[2] PF935</b>
Fuel Spin-on (1R0749).....	<b>BF7587 +</b>
Fuel Spin-on (1R0712).....	<b>BF614 +</b>
Fuel Spin-on (Fleetguard FF105).....	<b>BF957 +</b>
Axial Seal Air (Don. P522293).....	<b>PA2732</b>
Radial Seal Air.....	<b>RS3539</b>
Cab Air (Elixair 5X010007).....	<b>PA5320</b>
Air Dryer (AD-SP System) (Bendix 5008414).....	<b>BA5374 +</b>
Air Dryer (AD-9 System) (Bendix 107796).....	<b>BA5377</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>
357 w/Cat C10 (10.3L) Eng. (1/2004-on) (Cont'd)	357 w/Cat C12 (12.0L) Eng. (1/2004-on) (Cont'd)	357 w/Cat C16 Eng. (Cont'd)
<b>Coolant</b> (w/o Chemical) (Fleetguard WF2127)..... <b>B5087</b>	<b>Fuel Spin-on</b> (Fleetguard FF105)..... <b>BF957 +</b>	<b>Radial Seal Air</b> (Don. P534816)... <b>RS3539</b>
<b>Coolant</b> (w/Chemical) (Fleetguard WF2071)..... <b>BW5071</b>	<b>Axial Seal Air</b> (Don. P522293).... <b>PA2732</b>	<b>Radial Seal XP Air</b> (Don. P534816)..... <b>RS3539XP</b>
<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	<b>Radial Seal Air</b> ..... <b>RS3539</b>	<b>Cab Air</b> (Elixaire 5X010007)..... <b>PA5320</b>
<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>Cab Air</b> (Elixaire 5X010007)..... <b>PA5320</b>	<b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b>
357 w/Cat C11 (11.1L) Eng.	<b>Air Dryer</b> (AD-SP System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Coolant</b> ..... <b>B5087</b>
<b>F-F Lube</b> (1R1808)..... <b>B7299 +</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>
<b>Fuel/Water Separator Ele</b> ..... <b>PF7755</b>	<b>Coolant</b> (w/o Chemical) (Fleetguard WF2127)..... <b>B5087</b>	<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>
<b>Fuel Spin-on</b> (1R0749)..... <b>BF7587 +</b>	<b>Coolant</b> (w/Chemical) (Fleetguard WF2071)..... <b>BW5071</b>	357 w/Cat C12 (12.0L) Eng. (To 1/2004)
<b>23 7/16 In. Radial Seal Air</b> (Don. P534096)..... <b>RS3516</b>	<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	<b>F-F Lube</b> (1R0716)..... <b>B99 +</b>
<b>23 23/32 In. Radial Seal Air</b> (Don. P534816)..... <b>[2] RS3539</b>	<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>B-P Lube</b> ..... <b>B7577</b>
<b>Radial Seal XP Air</b> (Don. DBA5106)..... <b>RS3516XP</b>	357 w/Cat C13 (12.5L) Eng.	<b>Fuel/Water Separator Ele</b> ..... <b>PF316</b>
<b>23 23/32 In. Radial Seal XP Air</b> (Don. P534816)..... <b>[2] RS3539XP</b>	<b>F-F Lube</b> (1R1808)..... <b>B7299 +</b>	<b>Fuel/Water Separator Spin-on</b> ..... <b>BF5812</b>
<b>Cab Air</b> (Elixaire 5X010007)..... <b>PA5320</b>	<b>Fuel/Water Separator Ele</b> ..... <b>PF7755</b>	<b>Fuel Ele</b> ..... <b>[2] PF935</b>
<b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b>	<b>Fuel Spin-on</b> (1R0749)..... <b>BF7587 +</b>	<b>Fuel Spin-on</b> (1R0712)..... <b>BF614 +</b>
<b>Coolant</b> (w/o Chemical) (Fleetguard WF2127)..... <b>B5087</b>	<b>23 7/16 In. Radial Seal Air</b> (Don. P534096)..... <b>RS3516</b>	<b>Fuel Spin-on</b> (Fleetguard FF105)..... <b>BF957 +</b>
<b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>	<b>23 23/32 In. Radial Seal Air</b> (Don. P534816)..... <b>[2] RS3539</b>	<b>Axial Seal Air</b> (Don. P522293).... <b>PA2732</b>
<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	<b>Radial Seal XP Air</b> (Don. DBA5106)..... <b>RS3516XP</b>	<b>Radial Seal Air</b> ..... <b>RS3539</b>
<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>23 23/32 In. Radial Seal XP Air</b> (Don. P534816)..... <b>[2] RS3539XP</b>	<b>Cab Air</b> (Elixaire 5X010007)..... <b>PA5320</b>
357 w/Cat C12 (12.0L) Eng. (To 1/2004)	<b>Cab Air</b> (Elixaire 5X010007)..... <b>PA5320</b>	<b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b>
<b>F-F Lube</b> (1R0716)..... <b>B99 +</b>	<b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b>	<b>Coolant</b> (w/o Chemical) (Fleetguard WF2127)..... <b>B5087</b>
<b>B-P Lube</b> ..... <b>B7577</b>	<b>Coolant</b> (w/o Chemical) (Fleetguard WF2127)..... <b>B5087</b>	<b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>
<b>Fuel/Water Separator Ele</b> ..... <b>PF316</b>	<b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>	<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>
<b>Fuel/Water Separator Spin-on</b> ..... <b>BF5812</b>	<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>
<b>Fuel Ele</b> ..... <b>[2] PF935</b>	<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	357 w/Cat C15 Eng.
<b>Fuel Spin-on</b> (1R0749)..... <b>BF7587 +</b>	357 w/Cat C15 Eng.	<b>F-F Lube</b> (To 1/2004)..... <b>B99 +</b>
<b>Fuel Spin-on</b> (1R0712)..... <b>BF614 +</b>	<b>F-F Lube</b> (1/2004-on)..... <b>B7299 +</b>	<b>F-F Lube</b> (1/2004-on)..... <b>B7299 +</b>
<b>Fuel Spin-on</b> (Fleetguard FF105)..... <b>BF957 +</b>	<b>B-P Lube</b> ..... <b>B7577</b>	<b>B-P Lube</b> ..... <b>B7577</b>
<b>Axial Seal Air</b> (Don. P522293).... <b>PA2732</b>	<b>Fuel/Water Separator Ele</b> ..... <b>PF7755</b>	<b>Fuel/Water Separator Ele</b> ..... <b>PF7755</b>
<b>Radial Seal Air</b> ..... <b>RS3539</b>	<b>Fuel/Water Separator Spin-on</b> ..... <b>BF1212 +</b>	<b>Fuel/Water Separator Spin-on</b> ..... <b>BF1212 +</b>
<b>Cab Air</b> (Elixaire 5X010007)..... <b>PA5320</b>	<b>Fuel</b> ..... <b>BF7587 +</b>	<b>Fuel</b> ..... <b>BF7587 +</b>
<b>Air Dryer</b> (AD-SP System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Radial Seal Air</b> (Don. P534816)... <b>RS3539</b>	<b>Radial Seal Air</b> (Don. P534816)... <b>RS3539</b>
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Radial Seal XP Air</b> (Don. P534816)..... <b>RS3539XP</b>	<b>Radial Seal XP Air</b> (Don. P534816)..... <b>RS3539XP</b>
<b>Coolant</b> (w/o Chemical) (Fleetguard WF2127)..... <b>B5087</b>	<b>Cab Air</b> (Elixaire 5X010007)..... <b>PA5320</b>	<b>Cab Air</b> (Elixaire 5X010007)..... <b>PA5320</b>
<b>Coolant</b> (w/Chemical) (Fleetguard WF2071)..... <b>BW5071</b>	<b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b>	<b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b>
<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	<b>Coolant</b> ..... <b>B5087</b>	<b>Coolant</b> ..... <b>B5087</b>
<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>
357 w/Cat C12 (12.0L) Eng. (1/2004-on)	<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>
<b>F-F Lube</b> (1R1808)..... <b>B7299 +</b>	357 w/Cat C16 Eng.	357 w/Cat C16 Eng.
<b>B-P Lube</b> ..... <b>B7577</b>	<b>F-F Lube</b> (To 1/2004)..... <b>B99 +</b>	<b>F-F Lube</b> (To 1/2004)..... <b>B99 +</b>
<b>Fuel/Water Separator Ele</b> ..... <b>PF316</b>	<b>F-F Lube</b> (1/2004-on)..... <b>B7299 +</b>	<b>F-F Lube</b> (1/2004-on)..... <b>B7299 +</b>
<b>Fuel/Water Separator Spin-on</b> ..... <b>BF5812</b>	<b>B-P Lube</b> ..... <b>B7577</b>	<b>B-P Lube</b> ..... <b>B7577</b>
<b>Fuel Ele</b> ..... <b>[2] PF935</b>	<b>Fuel/Water Separator Ele</b> ..... <b>PF7755</b>	<b>Fuel/Water Separator Ele</b> ..... <b>PF7755</b>
<b>Fuel Spin-on</b> (1R0749)..... <b>BF7587 +</b>	<b>Fuel/Water Separator Spin-on</b> ..... <b>BF1212 +</b>	<b>Fuel/Water Separator Spin-on</b> ..... <b>BF1212 +</b>
<b>Fuel Spin-on</b> (1R0712)..... <b>BF614 +</b>	<b>Fuel</b> ..... <b>BF7587 +</b>	<b>Fuel</b> ..... <b>BF7587 +</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

PETERBILT Trucks (cont'd)	
357 w/Cat 3406 (14.6L) Eng. (Cont'd)	
Trans. (Allison 25010975).....	BT359
Trans. (Fuller 4304827).....	BT223
Steering (Nelson 83804E).....	P528
357 w/Cummins 6BT5.9 (5.9L) Eng.	
Lube (Chrysler 5083285AA).....	BT7349
Fuel/Water Separator (4741689).....	BF1223 +
Fuel/Water Separator (3903202).....	BF1226
357 w/Cummins 6CT8.3 Eng.	
F-F Lube.....	B205 +
B-P Lube (Fleetguard LF777).....	B7577
P. Fuel/Water Separator.....	BF1280 +
Fuel/Water Separator (Fleetguard FS1251).....	BF1226
S. Fuel (Fleetguard FF5052).....	BF788
Cab Air (Elixaire 5X000190).....	PA5321
Coolant (w/2 Units BTA+).....	BW5070
Coolant (w/4 Units BTA+) (Fleetguard WF2071).....	BW5071
Opt. Trans. (Fuller 17237).....	B2 +
Steering (Nelson 87972A).....	PT9386-MPG
357 w/Cummins ISC 8.3 (8.3L) Eng.	
Dual-Flow Lube (Standard Vers.) (3318853).....	BD103 +
Dual-Flow Lube (High Velocity) (3401544).....	BD7309 +
Lube (Upgrade) (3401544).....	B40142 +
Fuel/Water Separator Ele.....	PF7755
Fuel/Water Separator Spin-on.....	BF1272-SPS
21 9/32 In. Radial Seal Air (Fleetguard AF25858).....	RS4564
23 25/32 In. Radial Seal Air.....	RS3516
23 25/32 In. Radial Seal XP Air (Don. DBA5106).....	RS3516XP
Cab Air (Elixaire 5X010007).....	PA5320
Air Dryer (Bendix 5008414).....	BA5374 +
Coolant.....	BW5071
Opt. Trans. (Fuller 17237).....	B2 +
Steering (Nelson 87904M).....	PT9354-MPG
357 w/Cummins ISL 8.9 (8.9L) Eng.	
Dual-Flow Lube (Standard Vers.) (3318853).....	BD103 +
Dual-Flow Lube (High Velocity) (3401544).....	BD7309 +
Lube (Upgrade) (3401544).....	B40142 +
Fuel/Water Separator Ele.....	PF7755
Fuel/Water Separator Spin-on.....	BF1272-SPS
Fuel (Fleetguard FF5488).....	BF7815
Radial Seal Air (Don. P534096).....	RS3516
Radial Seal XP Air (Don. DBA5106).....	RS3516XP
Cab Air (Elixaire 5X010007).....	PA5320
Air Dryer (Bendix 5008414).....	BA5374 +
Coolant.....	BW5071
Opt. Trans. (Fuller 17237).....	B2 +
Steering (Nelson 87904M).....	PT9354-MPG

PETERBILT Trucks (cont'd)	
357 w/Cummins ISM 10.8 (10.8L) Eng. (To 2007)	
Dual-Flow Lube (Fleetguard LF9001).....	BD7154 +
Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN).....	BD50000
Fuel/Water Separator Ele.....	PF7755
Fuel/Water Separator Spin-on.....	BF1272-SPS
Radial Seal Air (Don. P534096).....	RS3516
Radial Seal XP Air (Don. DBA5106).....	RS3516XP
Cab Air (Elixaire 5X010007).....	PA5320
Air Dryer (Bendix 5008414).....	BA5374 +
Coolant.....	BW5071
Opt. Trans. (Fuller 17237).....	B2 +
Steering (Nelson 87904M).....	PT9354-MPG
357 w/Cummins ISM 10.8 (10.8L) Eng. (2007-on)	
Dual-Flow Lube (Fleetguard LF9001).....	BD7154 +
Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN).....	BD50000
Fuel/Water Separator Ele.....	PF7755
Fuel/Water Separator Spin-on.....	BF1272-SPS
Radial Seal Air (Don. P534096).....	RS3516
Radial Seal XP Air (Don. DBA5106).....	RS3516XP
Cab Air (Elixaire 5X010007).....	PA5320
Air Dryer (Bendix 5008414).....	BA5374 +
Breather (3683918).....	CV15000
Coolant.....	BW5071
Opt. Trans. (Fuller 17237).....	B2 +
Steering (Nelson 87904M).....	PT9354-MPG
357 w/Cummins ISX 15.0 (14.9L) Eng. (To 2007)	
11 13/16 In. Dual-Flow Lube.....	BD7154 +
14 7/32 In. Dual-Flow Lube.....	BD7153 +
Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN).....	BD50000
Fuel/Water Separator Ele.....	PF7755
Fuel/Water Separator Spin-on.....	BF1277-SP
Fuel (Fleetguard FF2200).....	BF7766
Fuel (Standard) (Fleetguard FF5776).....	BF9885 +
Fuel (Upgrade) (Fleetguard FF5825NN).....	BF46129
Radial Seal Air (Don. P542753).....	[2] RS4564
Cab Air (Elixaire 5X010007).....	PA5320
Air Dryer (Bendix 5008414).....	BA5374 +
Coolant (w/11 1/2 units BTA+) (Fleetguard WF2126).....	BW5086
Coolant (w/o Chemical) (Fleetguard WF2127).....	B5087
Opt. Trans. (Fuller 17237).....	B2 +
Steering (Nelson 87904M).....	PT9354-MPG
357 w/Cummins ISX 15.0 (14.9L) Eng. (2007-on)	
Dual-Flow Lube.....	BD103 +
B-P Lube (Fleetguard LF777).....	B7577
Fuel/Water Separator Ele. (DAHL 200).....	200
Fuel/Water Separator Ele. (Racor 1000FG).....	PF7890
Fuel/Water Separator Spin-on (Fleetguard FS1212).....	BF1212 +
Fuel (Fleetguard FF105).....	BF957 +
Axial Seal Air (Don. P181008).....	PA2317 +
Conical Air (Don. P521598).....	PA2729
Cab Air (Elixaire 5X000190).....	PA5321
Air Dryer (AD-9 System) (Bendix 107796).....	BA5377
Air Dryer (Wabco R950011).....	BA5374 +
Coolant (Fleetguard WF2071).....	BW5071
Opt. Trans. (Fuller 17237).....	B2 +
Steering Ele. (Nelson 87972A).....	PT9386-MPG
Steering Spin-on (Nelson 85098A).....	BT364
357 w/Cummins NTC400 Eng.	
Dual-Flow Lube (3825970).....	BD103 +
Fuel (Fleetguard FF105).....	BF957 +
Air (Don. P181000).....	[2] PA1637-FN
Opt. Trans. (Fuller 17237).....	B2 +
Steering (Nelson 83804E).....	P528
357 w/Cummins VT225 (9.1L) Eng.	
F-F Lube (3313281).....	B205 +
B-P Lube (3304232).....	B7577
Fuel (158172).....	BF957 +
Coolant (w/4 Units BTA+) (3315116).....	BW5071

PETERBILT Trucks (cont'd)	
357 w/Cummins ISX 15.0 (14.9L) Eng. (2007-on)	
11 13/16 In. Dual-Flow Lube.....	BD7154 +
14 7/32 In. Dual-Flow Lube.....	BD7153 +
Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN).....	BD50000
Fuel/Water Separator Ele.....	PF7755
Fuel/Water Separator Spin-on.....	BF1277-SP
Fuel (Fleetguard FF2200).....	BF7766
Fuel (Standard) (Fleetguard FF5776).....	BF9885 +
Fuel (Upgrade) (Fleetguard FF5825NN).....	BF46129
Radial Seal Air (Don. P542753).....	[2] RS4564
Cab Air (Elixaire 5X010007).....	PA5320
Air Dryer (Bendix 5008414).....	BA5374 +
Breather (3683918).....	CV15000
Coolant (w/11 1/2 units BTA+) (Fleetguard WF2126).....	BW5086
Coolant (w/o Chemical) (Fleetguard WF2127).....	B5087
Opt. Trans. (Fuller 17237).....	B2 +
Steering (Nelson 87904M).....	PT9354-MPG
357 w/Cummins M11 Eng.	
Dual-Flow Lube.....	BD103 +
B-P Lube (Fleetguard LF777).....	B7577
Fuel/Water Separator Ele. (DAHL 200).....	200
Fuel/Water Separator Ele. (Racor 1000FG).....	PF7890
Fuel/Water Separator Spin-on (Fleetguard FS1212).....	BF1212 +
Fuel (Fleetguard FF105).....	BF957 +
Axial Seal Air (Don. P181008).....	PA2317 +
Conical Air (Don. P521598).....	PA2729
Cab Air (Elixaire 5X000190).....	PA5321
Air Dryer (AD-9 System) (Bendix 107796).....	BA5377
Air Dryer (Wabco R950011).....	BA5374 +
Coolant (Fleetguard WF2071).....	BW5071
Opt. Trans. (Fuller 17237).....	B2 +
Steering Ele. (Nelson 87972A).....	PT9386-MPG
Steering Spin-on (Nelson 85098A).....	BT364
357 w/Cummins NTC400 Eng.	
Dual-Flow Lube (3825970).....	BD103 +
Fuel (Fleetguard FF105).....	BF957 +
Air (Don. P181000).....	[2] PA1637-FN
Opt. Trans. (Fuller 17237).....	B2 +
Steering (Nelson 83804E).....	P528
357 w/Cummins VT225 (9.1L) Eng.	
F-F Lube (3313281).....	B205 +
B-P Lube (3304232).....	B7577
Fuel (158172).....	BF957 +
Coolant (w/4 Units BTA+) (3315116).....	BW5071

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

**Trucks & Buses Applications** **BALDWIN FILTERS**

<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>
357 w/Detroit Diesel 12V71 (14.0L) Eng. Lube (23530407)..... [2] B95 + Lube (Upgrade) (23530408)..... [2] B95-MPG + P. Fuel (23530642)..... [2] BF784 S. Fuel (23530643)..... BF785 S. Fuel (23530644)..... BF7697	357, 375 w/Cummins L10 Eng. Dual-Flow Lube (3318853)..... BD103 + Fuel/Water Separator (Fleetguard FS1212)..... BF1212 + Fuel (Fleetguard FF105)..... BF957 + Air (Don. P522293)..... PA2732 Air (Don. P181009)..... [2] PA2357 Air Dryer (AD-9 System) (Bendix 107796)..... BA5377 Coolant (3316053)..... BW5075 Opt. Trans. (Fuller 17237)..... B2 + Steering (Nelson 83804E)..... P528	359 w/Cummins L10 (10.0L) Eng. (Cont'd) Coolant (w/15 Units BTA+) (Fleetguard WF2075)..... BW5075 Trans. (Fuller 4304827)..... BT223 Opt. Trans. (Fuller 17237)..... B2 +
357 w/Detroit Diesel Series 60 (12.7L) Eng. (To 1993) F-F Lube (25010495)..... [2] B95 + B-P Lube (23530413)..... B7577 Fuel/Water Separator (25011689)..... BF1212 + P. Fuel (25014274)..... BF5800 + S. Fuel (23518482)..... BF5810 Air (Don. P181008)..... [2] PA2317 + Coolant (23516489)..... BW5200 Trans. (Fuller 4304827)..... BT223 Opt. Trans. (Fuller 17237)..... B2 +	359 w/Cat 3306 (10.5L) Eng. Lube Ele. (5S0484)..... PT670 Lube Spin-on (1R0716)..... B99 + Lube Spin-on (Standard Vers.) (1R0739)..... B76 + Lube Spin-on (Severe Service) (1R0739)..... B76-SS + P. Fuel Ele. (9M2342)..... PF935 P. Fuel Spin-on (1R1740)..... BF970 + S. Fuel Spin-on (1R0750)..... BF7633 + Trans. (Fuller 4304827)..... BT223 Opt. Trans. (Fuller 17237)..... B2 +	359 w/Cummins N14 (14.0L) Eng. Dual-Flow Lube (3318853)..... BD103 + F-F Lube (Fleetguard LF670SC).. B196 + B-P Lube (3304232)..... B7577 Opt. Fuel/Water Separator (3308638)..... BF1212 + Fuel (154789)..... BF957-D + Coolant (w/4 Units BTA+) (3315116)..... BW5071 Trans. (Fuller 4304827)..... BT223 Opt. Trans. (Fuller 17237)..... B2 +
357 w/Detroit Diesel Series 60 (12.7L) Eng. (1993-on) F-F Lube (23518480)..... [2] B495 Fuel/Water Separator (25011689)..... BF1212 + P. Fuel (25014274)..... BF5800 + S. Fuel (23518482)..... BF5810 Air (Don. P181008)..... [2] PA2317 + Coolant (23516489)..... BW5200 Trans. (Fuller 4304827)..... BT223 Opt. Trans. (Fuller 17237)..... B2 +	359 w/Cat 3406 (14.6L) Eng. F-F Lube..... B99 + Fuel (Fleetguard FF105)..... BF957 + Fuel Spin-on..... BF7587 + 28 1/2 In. Air (Don. P150694)..... PA2660 Air (Don. XLP182008)..... LL2317 + 29 In. Air (Don. P522293)..... PA2732 Radial Seal Air (Don. P534816).. [2] RS3539 Radial Seal XP Air (Don. P534816)..... [2] RS3539XP Air Dryer (AD-9 System) (Bendix 107796)..... BA5377 Coolant (w/4 Units BTA+)..... BW5071 Coolant (w/15 Units BTA+) (Fleetguard WF2075)..... BW5075 Trans. (Allison 25010975)..... BT359 Trans. (Fuller 4304827)..... BT223 Steering (Nelson 83804E)..... P528	359 w/Cummins VT225 (9.1L) Eng. F-F Lube (3313281)..... B205 + B-P Lube (3304232)..... B7577 Fuel (158172)..... BF957 + Coolant (w/4 Units BTA+) (3315116)..... BW5071
357, 362 w/Cummins N14 (14.0L) Eng. Dual-Flow Lube..... BD103 + F-F Lube Spin-on..... B196 + B-P Lube Spin-on..... B7577 Opt. Fuel/Water Separator..... BF1212 + Fuel Spin-on..... BF957 + Air (Don. P181008)..... [2] PA2317 + Air Dryer (AD-9 System) (Bendix 107796)..... BA5377 Coolant (Fleetguard WF2075)..... BW5075 Opt. Trans. (Fuller 17237)..... B2 + Steering (Nelson 83804E)..... P528	359 w/Cat 3408 (18.0L) Eng. F-F Lube (1R0716)..... [2] B99 + Fuel Ele. (9M2342)..... [2] PF935 Fuel Spin-on (4N5823)..... BF614 + Fuel Spin-on (1R0749)..... BF7587 + Trans. (Fuller 4304827)..... BT223 Opt. Trans. (Fuller 17237)..... B2 +	359 w/Cummins VT903 (14.8L) Eng. F-F Lube Ele. (158139)..... P999-HD F-F Lube Spin-on (3313279)..... B96 + B-P Lube Ele. (256838)..... C750-E + B-P Lube Spin-on (3313283)..... B7577 Fuel/Water Separator (3308638).. BF1212 + Fuel (156172)..... BF957-D +
357, 375 w/Cat 3176 Eng. F-F Lube (1R0716)..... B99 + B-P Lube..... B7577 P. Fuel Ele. (Add G323 Gasket)... [2] PF935 Fuel Spin-on (1R0712)..... BF614 + Fuel Spin-on (1R0749)..... BF7587 + Fuel Spin-on (Fleetguard FF105)..... BF957 + Air (Don. P522293)..... PA2732 Air Dryer (AD-9 System) (Bendix 107796)..... BA5377 Coolant (Fleetguard WF2075)..... BW5075 Opt. Trans. (Fuller 17237)..... B2 + Steering (Nelson 83213H)..... PT903	359 w/Cummins L10 (10.0L) Eng. Dual-Flow Lube (3318853)..... BD103 + F-F Lube (Fleetguard LF670SC).. B196 + B-P Lube (3304232)..... B7577 Opt. Fuel/Water Separator (3308638)..... BF1212 + Fuel (154789)..... BF957-D + Coolant (w/4 Units BTA+) (3315116)..... BW5071	362 w/Cat C10 (10.3L) Eng. (To 1/2004) F-F Lube..... B99 + B-P Lube..... B7577 Fuel/Water Separator Ele..... PF316 Fuel/Water Separator Spin-on.... BF5812 Fuel Ele..... [2] PF935 Fuel Spin-on (1R0749)..... BF7587 + Fuel Spin-on (1R0712)..... BF614 + Air (Don. P150695)..... PA2680 Air Dryer (Bendix 109493)..... BA5373 Coolant (Fleetguard WF2127).... B5087 Opt. Trans. (Fuller 17237)..... B2 + 4 1/16 In. Steering (Nelson 87972A)..... PT9386-MPG 4 3/16 In. Steering (Nelson 83804E)..... P528
		362 w/Cat C10 (10.3L) Eng. (1/2004-on) F-F Lube..... B7299 + B-P Lube..... B7577 Fuel/Water Separator Ele..... PF316 Fuel/Water Separator Spin-on.... BF5812 Fuel Ele..... [2] PF935 Fuel Spin-on (1R0749)..... BF7587 + Fuel Spin-on (1R0712)..... BF614 + Air (Don. P150695)..... PA2680 Air Dryer (Bendix 109493)..... BA5373 Coolant (Fleetguard WF2127).... B5087 Opt. Trans. (Fuller 17237)..... B2 +

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

PETERBILT Trucks (cont'd)	PETERBILT Trucks (cont'd)	PETERBILT Trucks (cont'd)
362 w/Cat C10 (10.3L) Eng. (1/2004-on) (Cont'd) 4 1/16 In. Steering (Nelson 87972A)..... <b>PT9386-MPG</b> 4 3/16 In. Steering (Nelson 83804E)..... <b>P528</b>	362 w/Cat 3176 (10.3L) Eng. (Cont'd) <b>Fuel/Water Separator Spin-on</b> (2568753)..... <b>BF1259</b> P. Fuel Ele. (9M2342)..... <b>[2] PF935</b> P. Fuel Spin-on (1R1740)..... <b>BF970 +</b> S. Fuel Spin-on (1R0750)..... <b>BF7633 +</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	362 w/Cummins M11 (10.8L) Eng. (To 12/1995) (Cont'd) <b>Fuel/Water Separator Spin-on</b> (3308638)..... <b>BF1212 +</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b>
362 w/Cat C11 (11.1L) Eng. F-F Lube..... <b>B7299 +</b> Fuel/Water Separator Ele..... <b>PF7755</b> Fuel Spin-on..... <b>BF7587 +</b> Air..... <b>PA2732</b> Coolant..... <b>B5087</b>	362 w/Cat 3306 (10.5L) Eng. Lube Ele. (5S0484)..... <b>PT670</b> Lube Spin-on (1R0716)..... <b>B99 +</b> Lube Spin-on (Standard Vers.) (1R0739)..... <b>B76 +</b> Lube Spin-on (Severe Service) (1R0739)..... <b>B76-SS +</b> P. Fuel Ele. (9M2342)..... <b>PF935</b> P. Fuel Spin-on (1R1740)..... <b>BF970 +</b> S. Fuel Spin-on (1R0750)..... <b>BF7633 +</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	362 w/Cummins M11 (10.8L) Eng. (12/1995-on) <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> (3329289)..... <b>BF1259</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b>
362 w/Cat C12 (12.0L) Eng. (To 1/2004) F-F Lube..... <b>B99 +</b> B-P Lube..... <b>B7577</b> Fuel/Water Separator Ele..... <b>PF316</b> Fuel/Water Separator Spin-on..... <b>BF5812</b> Fuel Spin-on (1R0749)..... <b>BF7587 +</b> Fuel Spin-on (1R0712)..... <b>BF614 +</b> Air (Don. P537791)..... <b>PA2705</b> Air Dryer (Bendix 109493)..... <b>BA5373</b> Coolant (Fleetguard WF2127)..... <b>B5087</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	362 w/Cat 3408 Eng. F-F Lube..... <b>[2] B99 +</b> Fuel Spin-on..... <b>BF614 +</b>	362 w/Cummins NTC Eng. <b>Dual-Flow Lube</b> (3825970)..... <b>BD103 +</b> Fuel (Fleetguard FF105)..... <b>BF957 +</b> Air (Don. P181008)..... <b>PA2317 +</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Steering (Nelson 83804E)..... <b>P528</b>
362 w/Cat C12 (12.0L) Eng. (1/2004-on) F-F Lube..... <b>B7299 +</b> B-P Lube..... <b>B7577</b> Fuel/Water Separator Ele..... <b>PF316</b> Fuel/Water Separator Spin-on..... <b>BF5812</b> Fuel Spin-on (1R0749)..... <b>BF7587 +</b> Fuel Spin-on (1R0712)..... <b>BF614 +</b> Air (Don. P537791)..... <b>PA2705</b> Air Dryer (Bendix 109493)..... <b>BA5373</b> Coolant (Fleetguard WF2127)..... <b>B5087</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	362 w/Cummins ISM 10.8 (10.8L) Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154 +</b> <b>Dual-Flow Lube</b> (Fleetguard LF9031)..... <b>BD7509 +</b> <b>Dual-Flow Lube</b> (Fleetguard LF9000)..... <b>BD7153 +</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> Coolant (w/o Chemical) (Fleetguard WF2127)..... <b>B5087</b> Coolant (w/Controlled Release) (Fleetguard WF2121)..... <b>BW5250</b> Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> Coolant (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b>	362 w/Cummins VT903 (14.8L) Eng. F-F Lube Ele. (158139)..... <b>P999-HD</b> F-F Lube Spin-on (3313279)..... <b>B96 +</b> B-P Lube Ele. (256838)..... <b>C750-E +</b> B-P Lube Spin-on (3313283)..... <b>B7577</b> Fuel/Water Separator (3308638)..... <b>BF1212 +</b> Fuel (156172)..... <b>BF957-D +</b>
362 w/Cat C13 (12.5L) Eng. F-F Lube..... <b>B7299 +</b> Fuel/Water Separator Ele..... <b>PF7755</b> Fuel Spin-on..... <b>BF7587 +</b> Air..... <b>PA2732</b> Coolant..... <b>B5087</b>	362 w/Cummins L10 (10.0L) Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> F-F Lube (Fleetguard LF670SC)..... <b>B196 +</b> B-P Lube (3304232)..... <b>B7577</b> Opt. Fuel/Water Separator (3308638)..... <b>BF1212 +</b> Fuel (154789)..... <b>BF957-D +</b> Coolant (w/4 Units BTA+) (3315116)..... <b>BW5071</b> Coolant (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	362 w/Detroit Diesel 12V71 (14.0L) Eng. Lube (23530407)..... <b>[2] B95 +</b> Lube (Upgrade) (23530408)..... <b>[2] B95-MPG +</b> P. Fuel (23530642)..... <b>[2] BF784</b> S. Fuel (23530643)..... <b>BF785</b> S. Fuel (23530644)..... <b>BF7697</b>
362 w/Cat C15 Eng. F-F Lube..... <b>B7299 +</b> Fuel/Water Separator Ele..... <b>PF7755</b> Fuel Spin-on..... <b>BF7587 +</b> Air..... <b>PA2608 +</b>	362 w/Cat 3176 (10.3L) Eng. F-F Lube (Std. Version) (1R0716)..... <b>B99 +</b> F-F Lube (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> F-F Lube (1R0713)..... <b>[2] BT230 +</b> F-F Lube (1R0714)..... <b>[2] B75</b> Opt. B-P Lube (1W8845)..... <b>B7577</b> Fuel/Water Separator Ele. (8N0205)..... <b>PF316</b>	362 w/Detroit Diesel Series 60 (12.7L) Eng. (To 1993) F-F Lube (23518671)..... <b>[2] B95 +</b> B-P Lube (23518672)..... <b>B7577</b> Fuel/Water Separator Ele. (23521528)..... <b>PF7744</b> Fuel/Water Separator Spin-on (Fleetguard FS1212)..... <b>BF1212 +</b> Fuel/Water Separator (Racor 2020PM)..... <b>PF7890-30</b> Fuel/Water Separator Spin-on..... <b>BF5812</b> P. Fuel..... <b>BF5800 +</b> S. Fuel (23518482)..... <b>BF5810</b> Conical Air (Don. P522293)..... <b>PA2732</b> Axial Seal Air (Don. P150695)..... <b>PA2680</b> 23 23/32 In. Radial Seal Air (Don. P534816)..... <b>[2] RS3539</b> 23 23/32 In. Radial Seal XP Air (Don. P534816)..... <b>[2] RS3539XP</b> 25 23/32 In. Radial Seal Air (Don. P534925)..... <b>[2] RS3534</b> Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b> Air Dryer (Wabco R950011)..... <b>BA5374 +</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>
362 w/Detroit Diesel Series 60 (12.7L) Eng. (To 1993) (Cont'd)	365 w/Cat C9 Eng. (Cont'd)	365 w/Cummins ISL 8.9 (8.9L) Eng. (2008-14) (Cont'd)
<b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Cab Air</b> (9 3/32 In. Length) (Elixaire 5S013817)..... <b>PA5765</b>
<b>Coolant</b> (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>
<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>
<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b>
362 w/Detroit Diesel Series 60 (12.7L) Eng. (1993-on)	365 w/Cat C13 Eng.	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Lube</b> ..... <b>[2] B495</b>	<b>F-F Lube</b> (1R1808)..... <b>B7299 +</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Fuel/Water Separator Ele.</b> (23521528)..... <b>PF7744</b>	<b>F-F Lube</b> (249-2347)..... <b>[2] B7402</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
<b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1212)..... <b>BF1212 +</b>	<b>Fuel/Water Separator</b> (1752949)..... <b>BF1268</b>	<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>
<b>Fuel/Water Separator</b> (Racor 2020PM)..... <b>PF7890-30</b>	<b>Fuel/Water Separator</b> (280-2700)..... <b>BF1259</b>	<b>Diesel Exhaust Fluid</b> (2010 Emissions) (2888182)..... <b>PE17000</b>
<b>Fuel/Water Separator Spin-on</b> ..... <b>BF5812</b>	<b>Fuel</b> (1R0749)..... <b>BF7587 +</b>	365 w/Cummins ISL 8.9 (8.9L) Eng. (2018)
<b>P. Fuel</b> ..... <b>BF5800 +</b>	<b>Air</b> (Don. P522293)..... <b>PA2732</b>	<b>Dual-Flow Lube</b> (3401544)..... <b>BD7309</b>
<b>S. Fuel</b> (23518482)..... <b>BF5810</b>	<b>Cab Air</b> (Elixaire 5X010007)..... <b>PA5320</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1003)..... <b>BF1293-SPS</b>
<b>Conical Air</b> (Don. P522293)..... <b>PA2732</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b>
<b>Axial Seal Air</b> (Don. P150695)..... <b>PA2680</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Fuel</b> (Fleetguard FF63008)..... <b>BF63000</b>
<b>23 23/32 In. Radial Seal Air</b> (Don. P534816)..... <b>[2] RS3539</b>	<b>Breather</b> (2007-on) (296-8325)..... <b>CV15008</b>	<b>Air</b> (Don. P522293)..... <b>PA2732</b>
<b>23 23/32 In. Radial Seal XP Air</b> (Don. P534816)..... <b>[2] RS3539XP</b>	<b>Coolant</b> (1170189)..... <b>BW5139</b>	<b>Cab Air</b> (5S013817)..... <b>PA5765</b>
<b>25 23/32 In. Radial Seal Air</b> (Don. P534925)..... <b>[2] RS3534</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Air Dryer</b> (Bendix 5008414PG)..... <b>BA5379</b>
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Crankcase Breather</b> (4936636)..... <b>CV15010</b>
<b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29558328)..... <b>PT9416-MPG KIT</b>
<b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>	<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29558329)..... <b>PT9415-MPG KIT</b>
<b>Coolant</b> (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b>	365 w/Cat C15 Eng.	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2</b>
<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	<b>F-F Lube</b> (1R1808)..... <b>B7299 +</b>	<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>
<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1000)..... <b>BF1259</b>	<b>Diesel Exhaust Fluid</b> (4388378)..... <b>PE17002 KIT</b>
362, 372, 375, 377A/E w/Cat 3406E Eng.	<b>Fuel</b> (1R0749)..... <b>BF7587 +</b>	365 w/Cummins ISL-G (8.9L) Eng. (2010-17)
<b>F-F Lube</b> ..... <b>B99 +</b>	<b>Air</b> (Don. P522293)..... <b>PA2732</b>	<b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b>
<b>Fuel/Water Separator</b> ..... <b>BF5812</b>	<b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1003)..... <b>BF1293-SPS</b>
<b>Fuel Spin-on</b> (1R0749)..... <b>BF7587 +</b>	<b>Breather</b> (296-8325)..... <b>CV15008</b>	<b>Fuel</b> (Fleetguard NG5900)..... <b>BF7695</b>
<b>Fuel</b> (Fleetguard FF105)..... <b>BF957 +</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Air</b> (Don. P522293)..... <b>PA2732</b>
<b>28 1/2 In. Air</b> (Don. P150694)..... <b>PA2660</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>
<b>29 In. Air</b> (Don. P522293)..... <b>PA2732</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Coolant</b> (w/4 Units BTA+)..... <b>BW5071</b>	365 w/Cummins ISL 8.9 (8.9L) Eng. (2008-14)	365 w/Cummins ISL-G (8.9L) Eng. (2018)
<b>Coolant</b> (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b>	<b>Dual-Flow Lube</b> (3401544)..... <b>BD7309 +</b>	<b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309</b>
<b>Steering</b> (Nelson 83213H)..... <b>PT903</b>	<b>Lube</b> (Upgrade) (3401544)..... <b>B40142 +</b>	<b>Fuel/Water Separator</b> (Fleetguard NG5900)..... <b>BF7695</b>
365 w/Cat C9 Eng.	<b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b>	<b>Air</b> (Don. P522293)..... <b>PA2732</b>
<b>Lube</b> (1R1808)..... <b>B7299 +</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1003)..... <b>BF1293-SPS</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>
<b>Fuel/Water Separator</b> (175-2949)..... <b>BF1268</b>	<b>Fuel/Water Separator</b> (K371004)..... <b>PF9928</b>	<b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Fuel</b> (1R0751)..... <b>BF7632</b>	<b>Fuel</b> (Fleetguard FF5636)..... <b>BF7924</b>	<b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Air</b> (Don. P522293)..... <b>PA2732</b>	<b>Air</b> (Don. P522293)..... <b>PA2732</b>	<b>Fuel/Water Separator</b> (Fleetguard NG5900)..... <b>BF7695</b>
<b>Cab Air</b> (Elixaire 5X010007)..... <b>PA5320</b>	<b>Cab Air</b> (8 1/8 In. Length) (Elixaire 5X010007)..... <b>PA5320</b>	<b>Air</b> (Don. P522293)..... <b>PA2732</b>
<b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b>		<b>Cab Air</b> (5X013817)..... <b>PA5765</b>
		<b>Air Dryer</b> (Bendix 5008414PG)..... <b>BA5379</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>
365 w/Cummins ISL-G (8.9L) Eng. (2018) (Cont'd)	365 w/Cummins ISX 11.9 (11.9L) Eng. (2011-18) (Cont'd)	365 w/Cummins ISX 11.9G (11.9L) Eng. (2014-17) (Cont'd)
<b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>	<b>Air</b> (Don. P522293)..... <b>PA2732</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>
<b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b>	<b>Cab Air</b> (Elixaire 5S013817)..... <b>PA5765</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Air Dryer</b> (AD-SP System) (Bendix 109994)..... <b>BA5374+</b>	<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Air Dryer</b> (Bendix 5008414PG).... <b>BA5379</b>	
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2</b>	<b>Breather</b> (Fleetguard CV50634)... <b>CV15000</b>	
<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>Coolant</b> (Fleetguard WF2127)..... <b>B5087</b>	
365 w/Cummins ISL-G (8.9L) Eng. (2019)	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	365 w/Cummins ISX 11.9G (11.9L) Eng. (2018)
<b>Lube</b> (Fleetguard LF9009)..... <b>B40142</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	<b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b>
<b>Fuel/Water Separator</b> (Fleetguard NG5900)..... <b>BF7695</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>Fuel/Water Separator</b> (3607140). <b>BF7695</b>
<b>Air</b> (Don. P522293)..... <b>PA2732</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b>	<b>Air</b> (Don. P522293)..... <b>PA2732</b>
<b>Cab Air</b> (5S013817)..... <b>PA5765</b>	<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>Cab Air</b> (5X013817)..... <b>PA5765</b>
<b>Air Dryer</b> (Bendix 5008414PG).... <b>BA5379</b>	<b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>	<b>Air Dryer</b> (Bendix 5008414PG).... <b>BA5379</b>
<b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>	365 w/Cummins ISX 11.9 (11.9L) Eng. (2019)	<b>Coolant</b> (3680434)..... <b>B5087</b>
<b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b>	<b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b>	<b>Trans. (Fuller 4304827)..... BT223</b>
<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>Fuel/Water Separator</b> (Fleetguard FS19764G)..... <b>PF46091</b>	<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>
365 w/Cummins ISM Eng.	<b>Fuel</b> (2893612)..... <b>BF9885+</b>	365 w/Cummins ISX 11.9G (11.9L) Eng. (2019)
<b>Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154+</b>	<b>Air</b> (Don. P522293)..... <b>PA2732</b>	<b>Dual-Flow Lube</b> (Fleetguard LF9080)..... <b>BD50000</b>
<b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>	<b>Cab Air</b> (5S013817)..... <b>PA5765</b>	<b>Fuel/Water Separator</b> (Fleetguard NG5900)..... <b>BF7695</b>
<b>Fuel/Water Separator</b> (Fleetguard FS1000)..... <b>BF1259</b>	<b>Air Dryer</b> (Bendix 5008414PG).... <b>BA5379</b>	<b>Air</b> (Don. P522293)..... <b>PA2732</b>
<b>Air</b> (Don. P522293)..... <b>PA2732</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	<b>Cab Air</b> (5S013817)..... <b>PA5765</b>
<b>Cab Air</b> (Elixaire 5X010007)..... <b>PA5320</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	<b>Air Dryer</b> (Bendix 5008414PG).... <b>BA5379</b>
<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374+</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>
<b>Breather</b> (3683918)..... <b>CV15000</b>	<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>
<b>Coolant</b> (w/o Chemical) (4920476)..... <b>B5090</b>	<b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>	<b>Trans. Spin-on</b> (Fuller 17237)..... <b>B2</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	365 w/Cummins ISX 11.9 (11.9L) Eng. (2020)	<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b>	365 w/Cummins ISX 11.9G (11.9L) Eng. (2020)
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b>	<b>Fuel/Water Separator</b> (K371029) <b>PF46081</b>	<b>Dual-Flow Lube</b> (Fleetguard LF14000NN)..... <b>BD50000</b>
<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>Fuel</b> (2893612)..... <b>BF9885+</b>	<b>Fuel</b> (Fleetguard NG5900)..... <b>BF7695</b>
365 w/Cummins ISX 11.9 (11.9L) Eng. (2011-18)	<b>Air</b> (Don. P522293)..... <b>PA2732</b>	<b>Air</b> (Don. P522293)..... <b>PA2732</b>
<b>Dual-Flow Lube</b> (Upgrade) (4367100)..... <b>BD50000</b>	<b>Cab Air</b> (5S013817)..... <b>PA5765</b>	<b>Cab Air</b> (5S013817)..... <b>PA5765</b>
<b>Dual-Flow Lube</b> (Don. P559000). <b>BD7154+</b>	<b>Air Dryer</b> (AD-SP System) (Bendix 109994)..... <b>BA5374+</b>	<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>
<b>Fuel/Water Separator</b> (K371004) <b>PF9928</b>	<b>Coolant</b> (w/o Chemical) (Fleetguard WF2127)..... <b>B5087</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
<b>Fuel/Water Separator</b> (K371011) <b>PF46081</b>	<b>Coolant</b> (w/11 1/2 Units BTA+) (Fleetguard WF2125)..... <b>BW5086</b>	
<b>Fuel/Water Separator</b> (Fleetguard FS19764)..... <b>PF9814</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	
<b>Fuel</b> (Standard) (Fleetguard FF5776)..... <b>BF9885+</b>		
<b>Fuel</b> (Upgrade) (Fleetguard FF5825NN)..... <b>BF46129</b>		
365 w/Cummins ISX 11.9 (11.9L) Eng. (2011-18)	365 w/Cummins ISX 11.9G (11.9L) Eng. (2014-17)	365 w/Cummins ISX 15.0 (14.9L) Eng.
<b>Dual-Flow Lube</b> (Upgrade) (4367100)..... <b>BD50000</b>	<b>Dual-Flow Lube</b> (2882674)..... <b>BD7154+</b>	<b>Dual-Flow Lube</b> (Don. P559000). <b>BD7154+</b>
<b>Dual-Flow Lube</b> (Don. P559000). <b>BD7154+</b>	<b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>	<b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>
<b>Fuel/Water Separator</b> (K371004) <b>PF9928</b>	<b>Fuel/Water Separator</b> (3606712). <b>BF7695</b>	<b>Fuel/Water Separator</b> (K371004) <b>PF9928</b>
<b>Fuel/Water Separator</b> (K371011) <b>PF46081</b>	<b>Air</b> (Don. P522293)..... <b>PA2732</b>	<b>Fuel</b> (Standard) (Fleetguard FF5776)..... <b>BF9885+</b>
<b>Fuel/Water Separator</b> (Fleetguard FS19764)..... <b>PF9814</b>	<b>Cab Air</b> (Elixaire 5S013817)..... <b>PA5765</b>	<b>Fuel</b> (Upgrade) (Fleetguard FF5825NN)..... <b>BF46129</b>
<b>Fuel</b> (Standard) (Fleetguard FF5776)..... <b>BF9885+</b>	<b>Air Dryer</b> (AD-SP System) (Bendix 109994)..... <b>BA5374+</b>	<b>Air</b> (Don. P522293)..... <b>[2] PA2732</b>
<b>Fuel</b> (Upgrade) (Fleetguard FF5825NN)..... <b>BF46129</b>	<b>Breather</b> (Fleetguard CV50634)... <b>CV15000</b>	<b>Cab Air</b> (Elixaire 5S013817)..... <b>PA5765</b>
	<b>Coolant</b> (Fleetguard WF2127)..... <b>B5087</b>	<b>Air Dryer</b> (AD-SP System) (Bendix 109994)..... <b>BA5374+</b>
	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	<b>Coolant</b> (Fleetguard WF2127)..... <b>B5087</b>
		<b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>
365 w/Cummins ISX 15.0 (14.9L) Eng. (Cont'd) Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>	365 w/Paccar MX-11 (10.8L) Eng. (2020) (Cont'd) <b>Cab Air</b> (5S013817)..... <b>PA5765</b> <b>Coolant</b> (1843659PE)..... <b>B5088</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	365 w/Paccar MX-13 (12.9L) Eng. (2020) <b>F-F Lube</b> (2151728PE)..... <b>P40069</b> <b>Centrifugal Lube</b> (1922496PE)... <b>BC40148</b> <b>Fuel/Water Separator</b> (Fleetguard FS19765)..... <b>PF7930</b> <b>Fuel</b> (2133096PE)..... <b>PF46106</b> <b>Air</b> (Don. P522293)..... <b>PA2732</b> <b>Cab Air</b> (5S013817)..... <b>PA5765</b> <b>Coolant</b> (1843659PE)..... <b>B5088</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
365 w/Paccar MX Eng. <b>Lube Ele.</b> (1629393)..... <b>P40019</b> <b>Lube Spinner</b> (1643072)..... <b>BC7326 +</b> <b>Fuel/Water Separator</b> (K37-1005)..... <b>PF9928</b> <b>Fuel/Water Separator</b> (Fleetguard FS19765)..... <b>PF7930</b> <b>Fuel</b> (1655115)..... <b>BF9927</b> <b>Air</b> (Don. P522293)..... <b>PA2732</b> <b>Cab Air</b> (5S013817)..... <b>PA5765</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Coolant</b> (1843659)..... <b>B5088 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Diesel Exhaust Fluid</b> (2888182).. <b>PE17000</b>	365 w/Paccar MX-11 (10.8L) Eng. (2021) <b>Lube</b> (2129253PE)..... <b>P40008</b> 365 w/Paccar MX-13 (12.9L) Eng. (2014-17) <b>Lube Ele.</b> (1643070)..... <b>P40019</b> <b>Lube</b> (2047411)..... <b>P40069</b> <b>Centrifugal Lube</b> (1922496)..... <b>BC40148</b> <b>Fuel/Water Separator</b> (Fleetguard FS19765)..... <b>PF7930</b> <b>Fuel/Water Separator</b> (K371012) <b>PF46082</b> <b>Fuel</b> (1852006)..... <b>PF46106</b> <b>Air</b> (Don. P522293)..... <b>PA2732</b> <b>Cab Air</b> (5S013817)..... <b>PA5765</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Air Dryer</b> (Bendix 5008414PG)... <b>BA5379</b> <b>Coolant</b> (1843659)..... <b>B5088 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>	365 w/Paccar MX-13 (12.9L) Eng. (2021) <b>F-F Lube</b> (2234788PE)..... <b>P40069</b> <b>Centrifugal Lube</b> (1922496PE)... <b>BC40148</b> <b>Fuel</b> (2277129PE)..... <b>PF46106</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2</b>
365 w/Paccar MX-11 (10.8L) Eng. (2018) <b>F-F Lube</b> (1928868PE)..... <b>P40008</b> <b>Centrifugal Lube</b> (1928869PE)... <b>BC40009</b> <b>Fuel/Water Separator</b> (FS1029W)..... <b>PF7680</b> <b>Fuel/Water Separator</b> (Fleetguard FS19765)..... <b>PF7930</b> <b>Fuel</b> (1852006PE)..... <b>PF46106</b> <b>Air</b> (Don. P522293)..... <b>PA2732</b> <b>Cab Air</b> (5X013817)..... <b>PA5765</b> <b>Air Dryer</b> (Bendix 5008414PG)... <b>BA5379</b> <b>Coolant</b> (1843659PE)..... <b>B5088 +</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Diesel Exhaust Fluid</b> (4388378).. <b>PE17002 KIT</b>	365 w/Paccar MX-13 (12.9L) Eng. (2018) <b>F-F Lube</b> (2047411)..... <b>P40069</b> <b>Centrifugal Lube</b> (1922496)..... <b>BC40148</b> <b>Fuel/Water Separator</b> (Fleetguard FS19765)..... <b>PF7930</b> <b>Fuel</b> (1852006)..... <b>PF46106</b> <b>Air</b> (Don. P522293)..... <b>PA2732</b> <b>Cab Air</b> (5S013817)..... <b>PA5765</b> <b>Air Dryer</b> (Bendix 5008414PG)... <b>BA5379</b> <b>Coolant</b> (1843659)..... <b>B5088 +</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Diesel Exhaust Fluid</b> (2122909PE)..... <b>PE17002 KIT</b>	365 w/Paccar PX-9 (8.9L) Eng. (2014-18) <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel/Water Separator</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b> <b>Fuel/Water Separator</b> (Fleetguard FS1003)..... <b>BF1293-SPS</b> <b>Fuel/Water Separator</b> (K371029) <b>PF46081</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> <b>Air</b> (Don. P522293)..... <b>[2] PA2732</b> <b>Cab Air</b> (5S013817)..... <b>PA5765</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Air Dryer</b> (Bendix 5008414PG)... <b>BA5379</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b> <b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>
365 w/Paccar MX-11 (10.8L) Eng. (2019) <b>F-F Lube</b> (2129253PE)..... <b>P40008</b> <b>Centrifugal Lube</b> (1928869PE)... <b>BC40009</b> <b>Fuel</b> (2133096PE)..... <b>PF46106</b> <b>Air</b> (Don. P522293)..... <b>PA2732</b> <b>Cab Air</b> (5S013817)..... <b>PA5765</b> <b>Air Dryer</b> (Bendix 5008414PG)... <b>BA5379</b> <b>Coolant</b> (1843659PE)..... <b>B5088</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Diesel Exhaust Fluid</b> (2122909PE)..... <b>PE17002 KIT</b>	365 w/Paccar MX-13 (12.9L) Eng. (2019) <b>F-F Lube</b> (2047411PE)..... <b>P40069</b> <b>Centrifugal Lube</b> (1922496PE)... <b>BC40148</b> <b>Fuel/Water Separator</b> (K371022) <b>PF46237</b> <b>Fuel</b> (2133096PE)..... <b>PF46106</b> <b>Air</b> (Don. P522293)..... <b>PA2732</b> <b>Cab Air</b> (5S013817)..... <b>PA5765</b> <b>Air Dryer</b> (Bendix 5008414PG)... <b>BA5379</b> <b>Coolant</b> (1843659PE)..... <b>B5088 +</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	365 w/Paccar PX-9 (8.9L) Eng. (2019) <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel/Water Separator</b> (K371017) <b>PF46238</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> <b>Air</b> (Don. P522293)..... <b>PA2732</b> <b>Cab Air</b> (5S013817)..... <b>PA5765</b> <b>Air Dryer</b> (Bendix 5008414PG)... <b>BA5379</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Diesel Exhaust Fluid</b> (Fleetguard UF101)..... <b>PE17000</b>
365 w/Paccar MX-11 (10.8L) Eng. (2020) <b>Lube</b> (2129253PE)..... <b>P40008</b> <b>Fuel/Water Separator</b> (2164463PE)..... <b>PF46106</b> <b>Fuel</b> (2277129PE)..... <b>PF46106</b> <b>Air</b> (Don. P522293)..... <b>PA2732</b>		

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



PETERBILT Trucks (cont'd)	PETERBILT Trucks (cont'd)	PETERBILT Trucks (cont'd)
365 w/Paccar PX-9 (8.9L) Eng. (2020)	367 w/Cat C15 Eng. (Cont'd)	367 w/Cummins ISX 11.9 (11.9L) Eng. (2011-17) (Cont'd)
Lube (3401544)..... <b>B40142</b>	Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	Fuel/Water Separator Ele. (K371004)..... <b>PF9928</b>
Fuel/Water Separator (K371017)..... <b>PF46238</b>	Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Fuel/Water Separator Ele. (K371029)..... <b>PF46081</b>
Fuel (5303743)..... <b>BF63000</b>	Trans. Spin-on (Fuller 4304827).. <b>BT223</b>	Fuel/Water Separator Ele. (K371012)..... <b>PF46082</b>
Air (Don. P522293)..... <b>PA2732</b>	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	Fuel/Water Separator Ele. (Fleetguard FS19729)..... <b>PF7755</b>
Cab Air (5S013817)..... <b>PA5765</b>	Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	Fuel/Water Separator Ele. (Fleetguard FS19764)..... <b>PF9814</b>
Trans. Ele. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	367 w/Cummins ISM 10.8 (10.8L) Eng. (2008-11)	Fuel/Water Separator Spin-on (4010651)..... <b>BF1277-SPS</b>
Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	Dual-Flow Lube (Fleetguard LF9001)..... <b>BD7154 +</b>	Fuel (Fleetguard FF104)..... <b>BF948 +</b>
Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>	Fuel (Pre-2010 Emissions) (Fleetguard FF2200)..... <b>BF7766</b>
Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	Fuel/Water Separator (Fleetguard FS1000)..... <b>BF1259</b>	Fuel (Pre-2010 Emissions) (Fleetguard FF2203)..... <b>BF7760</b>
365 w/Paccar PX-9 (8.9L) Eng. (2021)	Axial Seal Air (Don. P153551)..... <b>PA2705</b>	Fuel (2010 Emissions) (Fleetguard FF5686)..... <b>BF9860 +</b>
Lube (5444774)..... <b>B40142</b>	21 19/32 In. Radial Seal Air (Don. P544243)..... <b>[2] RS4572</b>	Fuel (2010 Emissions) (Fleetguard FF5776)..... <b>BF9885 +</b>
Fuel (5303743)..... <b>BF63000</b>	23 23/32 In. Radial Seal Air (Don. P534816)..... <b>RS3539</b>	Fuel (Upgrade) (Fleetguard FF5825NN)..... <b>BF46129</b>
365 w/Paccar PX-9 (8.9L) Eng. (2022)	23 23/32 In. Radial Seal XP Air (Don. P534816)..... <b>RS3539XP</b>	Axial Seal Air (Don. P153551)..... <b>PA2705</b>
Lube (5444774)..... <b>B40142</b>	Cab Air (Elixaire 5X010007)..... <b>PA5320</b>	Conical Air (Don. P522293)..... <b>[2] PA2732</b>
367 w/Cat C13 Eng.	Air Dryer (Bendix 5008414)..... <b>BA5374 +</b>	21 11/32 In. Radial Seal Air (Don. P542753)..... <b>[2] RS4564</b>
Lube (1R1808)..... <b>B7299 +</b>	Breather (3683918)..... <b>CV15000</b>	22 29/32 In. Std. Radial Seal Air (P614986)..... <b>[2] RS5288</b>
Lube (249-2347)..... <b>[2] B7402</b>	Coolant (w/o Chemical) (4920476)..... <b>B5090</b>	22 29/32 In. Radial Seal XP Air (Paccar P614986)..... <b>[2] RS5288XP</b>
Fuel/Water Separator (256-8753)..... <b>BF1259</b>	Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	23 23/32 In. Radial Seal Air (Don. P534816)..... <b>RS3539</b>
Fuel (1R0749)..... <b>BF7587 +</b>	Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	23 23/32 In. Radial Seal XP Air (Don. P534816)..... <b>RS3539XP</b>
Air (Don. P153551)..... <b>PA2705</b>	Trans. Spin-on (Fuller 4304827).. <b>BT223</b>	Cab Air (8 1/8 In. Length) (Elixaire 5X010007)..... <b>PA5320</b>
Radial Seal Air (Don. P534816)..... <b>RS3539</b>	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	Cab Air (9 3/32 In. Length) (5S013817)..... <b>PA5765</b>
Radial Seal XP Air (Don. P534816)..... <b>RS3539XP</b>	Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	Air Dryer (Bendix 5008414)..... <b>BA5374 +</b>
Cab Air (Elixaire 5X010007)..... <b>PA5320</b>	367 w/Cummins ISM 10.8 (10.8L) Eng. (2018)	Breather (4312013)..... <b>CV15000</b>
Air Dryer (Bendix 5008414)..... <b>BA5374 +</b>	Std. Radial Seal Air (P614986)..... <b>[2] RS5288</b>	Coolant (w/o Chemical) (3680434)..... <b>B5087</b>
Breather (2007-on) (296-8325)..... <b>CV15008</b>	Radial Seal XP Air (Paccar P614986)..... <b>[2] RS5288XP</b>	Coolant (w/11 1/2 Units BTA+)..... <b>BW5086</b>
Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	Cab Air (5X013817)..... <b>PA5765</b>	Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Air Dryer (Bendix 5008414PG)..... <b>BA5379</b>	Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
Trans. Spin-on (Fuller 4304827).. <b>BT223</b>	Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	Trans. Spin-on (Fuller 4304827).. <b>BT223</b>
Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>
Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	Trans. Spin-on (Fuller 4304827).. <b>BT223</b>	Steering (Nelson 87904M)..... <b>PT9354-MPG</b>
367 w/Cat C15 Eng.	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	Diesel Exhaust Fluid (5303604).. <b>PE17000</b>
Lube (1R1808)..... <b>B7299 +</b>	Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	
Fuel/Water Separator Ele. (Racor 2020SMOR)..... <b>PF7890</b>	Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	
Fuel/Water Separator Spin-on (280-2700)..... <b>BF1259</b>	367 w/Cummins ISX 11.9 (11.9L) Eng. (2011-17)	
Fuel (1R0749)..... <b>BF7587 +</b>	Dual-Flow Lube (Upgrade) (4367100)..... <b>BD50000</b>	
Axial Seal Air (Don. P153551)..... <b>PA2705</b>	Dual-Flow Lube (Fleetguard LF9080)..... <b>BD7154 +</b>	
Radial Seal Air (Don. P534816)..... <b>RS3539</b>		
Radial Seal XP Air (Don. P534816)..... <b>RS3539XP</b>		
Radial Seal Air (Don. P542753)..... <b>[2] RS4564</b>		
Cab Air (Elixaire 5X010007)..... <b>PA5320</b>		
Air Dryer (AD-IP System) (Bendix 65624)..... <b>BA5373</b>		
Air Dryer (AD-IS, AD-SP System) (Bendix 5008414)..... <b>BA5374 +</b>		
Breather (2007 Emissions) (296-8325)..... <b>CV15008</b>		


\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>
367 w/Cummins ISX 11.9 (11.9L) Eng. (2018) <b>Dual-Flow Lube</b> (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel</b> (Fleetguard FF5776)..... <b>BF9885 +</b> <b>Std. Radial Seal Air</b> (P614986)... <b>[2] RS5288</b> <b>Radial Seal XP Air</b> (Paccar P614986)..... <b>[2] RS5288XP</b> <b>Cab Air</b> (5X013817)..... <b>PA5765</b> <b>Air Dryer</b> (Bendix 5008414PG)... <b>BA5379</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	367 w/Cummins ISX 15.0 (14.9L) Eng. (2008-2017) (Cont'd) <b>22 29/32 In. Std. Radial Seal Air</b> (P614986)..... <b>[2] RS5288</b> <b>22 29/32 In. Radial Seal XP Air</b> (Paccar P614986)..... <b>[2] RS5288XP</b> <b>Cab Air</b> (5S013817)..... <b>PA5765</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Crankcase Breather</b> (4312013)... <b>CV15000</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>	367 w/Cummins ISX 15.0 (14.9L) Eng. (2020) (Cont'd) <b>Fuel</b> (5365988)..... <b>BF46129</b> <b>Radial Seal Air</b> (P614986)..... <b>[2] RS5288</b> <b>Radial Seal XP Air</b> (P614986).... <b>[2] RS5288XP</b> <b>Cab Air</b> (5S013817)..... <b>PA5765</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
367 w/Cummins ISX 11.9 (11.9L) Eng. (2019) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel</b> (2893612)..... <b>BF9885 +</b> <b>Std. Radial Seal Air</b> (P614986)... <b>[2] RS5288</b> <b>Radial Seal XP Air</b> (P614986).... <b>[2] RS5288XP</b> <b>Cab Air</b> (5S013817)..... <b>PA5765</b> <b>Air Dryer</b> (TRP AC1001)..... <b>BA5374 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>	367 w/Cummins ISX 15.0 (14.9L) Eng. (2018) <b>Dual-Flow Lube</b> (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (K371029) <b>PF46081</b> <b>Fuel</b> (Upgrade) (Fleetguard FF5825NN)..... <b>BF46129</b> <b>Std. Radial Seal Air</b> (P614986)... <b>RS5288</b> <b>Radial Seal XP Air</b> (P614986).... <b>RS5288XP</b> <b>Cab Air</b> (5S013817)..... <b>PA5765</b> <b>Air Dryer</b> (Bendix 5008414PG)... <b>BA5379</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Diesel Exhaust Fluid</b> (4388378).. <b>PE17002 KIT</b>	367 w/Cummins ISX 15.0 (14.9L) Eng. (2021) <b>Lube</b> (5575298)..... <b>B40145</b> <b>Fuel/Water Separator</b> (Fleetguard FS19764)..... <b>PF9814</b> <b>Fuel/Water Separator</b> (Fleetguard FS19764G)..... <b>PF46091</b> <b>Fuel</b> (5365988)..... <b>BF46129</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>
367 w/Cummins ISX 11.9 (11.9L) Eng. (2020) <b>Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (Fleetguard FS19764)..... <b>PF9814</b> <b>Fuel</b> (2893612)..... <b>BF9885</b> <b>Radial Seal Air</b> (P614986)..... <b>[2] RS5288</b> <b>Radial Seal XP Air</b> (P614986).... <b>[2] RS5288XP</b> <b>Cab Air</b> (5S013817)..... <b>PA5765</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	367 w/Cummins ISX 15.0 (14.9L) Eng. (2019) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (Fleetguard FS19764)..... <b>PF9814</b> <b>Fuel</b> (5365988)..... <b>BF46129 +</b> <b>Std. Radial Seal Air</b> (P614986)... <b>[2] RS5288</b> <b>Radial Seal XP Air</b> (Don. P614986)..... <b>[2] RS5288XP</b> <b>Cab Air</b> (5S013817)..... <b>PA5765</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	367 w/Cummins X15 (14.9L) Eng. (2018) <b>Dual-Flow Lube</b> (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (K371029) <b>PF46081</b> <b>Fuel</b> (Upgrade) (Fleetguard FF5825NN)..... <b>BF46129</b> <b>Std. Radial Seal Air</b> (P614986)... <b>RS5288</b> <b>Radial Seal XP Air</b> (P614986).... <b>RS5288XP</b> <b>Cab Air</b> (5S013817)..... <b>PA5765</b> <b>Air Dryer</b> (Bendix 5008414PG)... <b>BA5379</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (4388378).. <b>PE17002 KIT</b>
367 w/Cummins ISX 15.0 (14.9L) Eng. (2008-2017) <b>Dual-Flow Lube</b> (4331005)..... <b>BD7154 +</b> <b>Dual-Flow Lube</b> (Upgrade) (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (K371011) <b>PF46081</b> <b>Fuel</b> (Standard) (Fleetguard FF5776)..... <b>BF9885 +</b> <b>Fuel</b> (Upgrade) (Fleetguard FF5825NN)..... <b>BF46129</b> <b>Fuel</b> (Upgrade) (Fleetguard FF5811)..... <b>BF46179</b>	367 w/Cummins ISX 15.0 (14.9L) Eng. (2020) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (K371029) <b>PF46081</b> <b>Fuel/Water Separator</b> (Fleetguard FS19764)..... <b>PF9814</b>	367 w/Cummins X15 (14.9L) Eng. (2019) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (Fleetguard FS19764)..... <b>PF9814</b> <b>Fuel</b> (5365988)..... <b>BF46129 +</b> <b>Std. Radial Seal Air</b> (P614986)... <b>[2] RS5288</b> <b>Radial Seal XP Air</b> (P614986).... <b>[2] RS5288XP</b> <b>Cab Air</b> (5S013817)..... <b>PA5765</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

PETERBILT Trucks (cont'd)	PETERBILT Trucks (cont'd)	PETERBILT Trucks (cont'd)
367 w/Cummins X15 (14.9L) Eng. (2019) (Cont'd) Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	367 w/Paccar MX-13 (12.9L) Eng. (2014-18) (Cont'd) Std. Radial Seal Air (P614556)... [2] <b>RS5287</b> Radial Seal XP Air (P614556).... [2] <b>RS5287XP +</b> Cab Air (5S013817)..... <b>PA5765</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Air Dryer (Bendix 5008414PG).... <b>BA5379</b> Coolant (1843659)..... <b>B5088 +</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b> Diesel Exhaust Fluid (5303604).. <b>PE17000</b> Diesel Exhaust Fluid (2122909PE)..... <b>PE17002 KIT</b>	367 w/Westport HD GX (15.0L) Eng. Dual-Flow Lube (Fleetguard LF9080)..... <b>BD7154 +</b> Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> Fuel/Water Separator (Fleetguard NG5900)..... <b>BF7695</b> Radial Seal Air (Don. P542753)... [2] <b>RS4564</b> Cab Air (Elixair 5X010007)..... <b>PA5320</b> Air Dryer (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> Coolant (w/o Chemical) (Fleetguard WF2127)..... <b>B5087</b> Coolant (w/Chemical) (Fleetguard WF2126)..... <b>BW5086</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>
367 w/Cummins X15 (14.9L) Eng. (2020) Dual-Flow Lube (4367100)..... <b>BD50000</b> Fuel/Water Separator (K371029) <b>PF46081</b> Fuel/Water Separator (Fleetguard FS19764)..... <b>PF9814</b> Fuel (5365988)..... <b>BF46129</b> Radial Seal Air (P614986)..... [2] <b>RS5288</b> Radial Seal XP Air (P614986).... [2] <b>RS5288XP</b> Cab Air (5S013817)..... <b>PA5765</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Trans. (Fuller 4304827)..... <b>BT223</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	367 w/Paccar MX-13 (12.9L) Eng. (2019) F-F Lube (2047411PE)..... <b>P40069</b> Centrifugal Lube (1922496PE)... <b>BC40148</b> Fuel/Water Separator (K371022) <b>PF46237</b> Fuel (2133096PE)..... <b>PF46106</b> Std. Radial Seal Air (P614986)... [2] <b>RS5288</b> Radial Seal XP Air (P614986).... [2] <b>RS5288XP</b> Cab Air (5S013817)..... <b>PA5765</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Coolant (1843659PE)..... <b>B5088 +</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b> Diesel Exhaust Fluid (2122909PE)..... <b>PE17002 KIT</b>	372 w/Cat 3176 (10.3L) Eng. F-F Lube (Std. Version) (1R0716)..... <b>B99 +</b> F-F Lube (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> F-F Lube (1R0713)..... [2] <b>BT230 +</b> F-F Lube (1R0714)..... [2] <b>B75</b> Opt. B-P Lube (1W8845)..... <b>B7577</b> Fuel/Water Separator Ele. (8N0205)..... <b>PF316</b> Fuel/Water Separator Spin-on (2568753)..... <b>BF1259</b> P. Fuel Ele. (9M2342)..... [2] <b>PF935</b> P. Fuel Spin-on (1R1740)..... <b>BF970 +</b> S. Fuel Spin-on (1R0750)..... <b>BF7633 +</b>
367 w/Paccar MX Eng. F-F Lube (1643070)..... <b>P40019</b> B-P Lube Spinner (1643072)..... <b>BC7326 +</b> Fuel/Water Separator (Fleetguard FS19624)..... <b>PF7748</b> Fuel/Water Separator (Fleetguard FS19727)..... <b>PF7895</b> Fuel/Water Separator (Fleetguard FS19765)..... <b>PF7930</b> Fuel/Water Separator (K371005) <b>PF9928</b> Fuel (1655115)..... <b>BF9927</b> 22 29/32 In. Std. Radial Seal Air (P614986)..... [2] <b>RS5288</b> 22 29/32 In. Radial Seal XP Air (Paccar P614986)..... [2] <b>RS5288XP</b> 23 23/32 In. Radial Seal Air (Don. P534816)..... <b>RS3539</b> 23 23/32 In. Radial Seal XP Air (Don. EAF5100)..... <b>RS3539XP</b> Cab Air (5S013817)..... <b>PA5765</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Trans. (Fuller 4304827)..... <b>BT223</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Diesel Exhaust Fluid (5303604).. <b>PE17000</b>	367 w/Paccar MX-13 (12.9L) Eng. (2020) F-F Lube (2151728PE)..... <b>P40069</b> Centrifugal Lube (1922496PE)... <b>BC40148</b> Fuel/Water Separator (Fleetguard FS19765)..... <b>PF7930</b> Fuel (2133096PE)..... <b>PF46106</b> Radial Seal Air (P614986)..... [2] <b>RS5288</b> Radial Seal XP Air (P614986).... [2] <b>RS5288XP</b> Cab Air (5S013817)..... <b>PA5765</b> Air Dryer (Bendix 5008414)..... <b>BA5374</b> Coolant (1843659PE)..... <b>B5088</b> Trans. (Fuller 4304827)..... <b>BT223</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b> Diesel Exhaust Fluid (2122909PE)..... <b>PE17002 KIT</b>	372 w/Cat C15 Eng. Lube (To 1/2004)..... <b>B99 +</b> Lube (1/2004-on)..... <b>B7299 +</b> Fuel (1R0749)..... <b>BF7587 +</b> Fuel (Fleetguard FF105)..... <b>BF957 +</b> Axial Seal Air (Don. P181186).... <b>PA2608 +</b> Radial Seal Air (Don. P542101)... <b>RS3750</b> Radial Seal XP Air (Don. P542101)..... <b>RS3750XP</b> Air Dryer (AD-SP System) (Bendix 5008414)..... <b>BA5374 +</b> Coolant (Fleetguard WF2071)..... <b>BW5071</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b>
367 w/Paccar MX-13 (12.9L) Eng. (2014-18) Lube Ele. (1643070)..... <b>P40019</b> Lube (2047411)..... <b>P40069</b> Centrifugal Lube (1922496)..... <b>BC40148</b> Fuel/Water Separator (Fleetguard FS19765)..... <b>PF7930</b> Fuel/Water Separator (K371009) <b>PF9929</b> Fuel/Water Separator (K371012) <b>PF46082</b> Fuel (1852006)..... <b>PF46106</b> Conical Air (Don. P522293)..... [2] <b>PA2732</b> Std. Radial Seal Air (P614986)... [2] <b>RS5288</b> Radial Seal XP Air (Paccar P614986)..... [2] <b>RS5288XP</b>	367 w/Paccar MX-13 (12.9L) Eng. (2021) F-F Lube (2234788PE)..... <b>P40069</b> Centrifugal Lube (1922496PE)... <b>BC40148</b> Fuel (2277129PE)..... <b>PF46106</b>	372 w/Cummins M11 (10.8L) Eng. (To 12/1995) Dual-Flow Lube (3318853)..... <b>BD103 +</b> Fuel/Water Separator Ele. (Fleetguard FS1029W)..... <b>PF7680</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>
372 w/Cummins M11 (10.8L) Eng. (To 12/1995) (Cont'd) <b>Fuel/Water Separator Spin-on</b> (3308638)..... <b>BF1212 +</b>	372 w/Detroit Diesel Series 60 (12.7L) Eng. (1993-on) (Cont'd) <b>25 23/32 In. Radial Seal Air</b> (Don. P534925)..... <b>[2] RS3534</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	375 w/Cummins M11 (10.8L) Eng. (To 12/1995) (Cont'd) <b>Fuel/Water Separator Spin-on</b> (3308638)..... <b>BF1212 +</b> 375 w/Detroit Series 60 Eng. <b>Lube</b> (23527033)..... <b>[2] B495</b> <b>Fuel/Water Separator</b> (Fleetguard FS1212)..... <b>BF1212 +</b> <b>Fuel</b> (23518482)..... <b>BF5810</b> <b>Air</b> (Don. P522293)..... <b>PA2732</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (Fleetguard WF2075)..... <b>BW5075</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 83213H)..... <b>PT903</b>
372 w/Detroit Diesel Series 60 (12.7L) Eng. (To 1993) <b>F-F Lube</b> (23518671)..... <b>[2] B95 +</b> <b>B-P Lube</b> (23518672)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (23521528)..... <b>PF7744</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1212)..... <b>BF1212 +</b> <b>Fuel/Water Separator</b> (Racor 2020PM)..... <b>PF7890-30</b> <b>Fuel/Water Separator Spin-on</b> ..... <b>BF5812</b> <b>P. Fuel</b> ..... <b>BF5800 +</b> <b>S. Fuel</b> (23518482)..... <b>BF5810</b> <b>Conical Air</b> (Don. P522293)..... <b>PA2732</b> <b>Axial Seal Air</b> (Don. P150695)..... <b>PA2680</b> <b>23 23/32 In. Radial Seal Air</b> (Don. P534816)..... <b>[2] RS3539</b> <b>23 23/32 In. Radial Seal XP Air</b> (Don. P534816)..... <b>[2] RS3539XP</b> <b>25 23/32 In. Radial Seal Air</b> (Don. P534925)..... <b>[2] RS3534</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	372, 375, 377, 378, 379 w/Cummins N14 (14.0L) Eng. <b>Dual-Flow Lube</b> (Fleetguard LF3000)..... <b>BD103 +</b> <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>F-F Lube Spin-on</b> ..... <b>B196 +</b> <b>B-P Lube Spin-on</b> ..... <b>B7577</b> <b>Opt. Fuel/Water Separator</b> (Fleetguard FS1212)..... <b>BF1212 +</b> <b>Fuel/Water Separator</b> (Fleetguard FS1000)..... <b>BF1259</b> <b>Fuel Spin-on</b> (Fleetguard FF105)..... <b>BF957 +</b> <b>Fuel Spin-on</b> (Fleetguard FF1108)..... <b>BF888</b> <b>Air</b> (Don. P522293)..... <b>[2] PA2732</b> <b>Cab Air</b> (Elixair 5X010007)..... <b>PA5320</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-SP System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Coolant</b> (3844234)..... <b>BW5076</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>2 23/32 In. Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>4 3/16 In. Steering</b> (Nelson 83213H)..... <b>PT903</b>	376 w/Cat 3176 (10.3L) Eng. <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99 +</b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> <b>F-F Lube</b> (1R0713)..... <b>[2] BT230 +</b> <b>F-F Lube</b> (1R0714)..... <b>[2] B75</b> <b>Opt. B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Fuel/Water Separator Spin-on</b> (2568753)..... <b>BF1259</b> <b>P. Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>P. Fuel Spin-on</b> (1R1740)..... <b>BF970 +</b> <b>S. Fuel Spin-on</b> (1R0750)..... <b>BF7633 +</b>
372 w/Detroit Diesel Series 60 (12.7L) Eng. (1993-on) <b>Lube</b> ..... <b>[2] B495</b> <b>Fuel/Water Separator Ele.</b> (23521528)..... <b>PF7744</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1212)..... <b>BF1212 +</b> <b>Fuel/Water Separator</b> (Racor 2020PM)..... <b>PF7890-30</b> <b>Fuel/Water Separator Spin-on</b> ..... <b>BF5812</b> <b>P. Fuel</b> ..... <b>BF5800 +</b> <b>S. Fuel</b> (23518482)..... <b>BF5810</b> <b>Conical Air</b> (Don. P522293)..... <b>PA2732</b> <b>Axial Seal Air</b> (Don. P150695)..... <b>PA2680</b> <b>23 23/32 In. Radial Seal Air</b> (Don. P534816)..... <b>[2] RS3539</b> <b>23 23/32 In. Radial Seal XP Air</b> (Don. P534816)..... <b>[2] RS3539XP</b>	375 w/Cummins M11 (10.8L) Eng. (12/1995-on) <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> (3329289)..... <b>BF1259</b>	376 w/Cat 3406 (14.6L) Eng. <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99 +</b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> <b>Fuel/Water Separator</b> (1752949)..... <b>BF1268</b> <b>Fuel/Water Separator</b> (2568753)..... <b>BF1259</b> <b>Fuel</b> (1R0749)..... <b>BF7587 +</b> <b>Fuel</b> (1R0712)..... <b>BF614 +</b>
	375 w/Cummins M11 (10.8L) Eng. (To 12/1995) <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b>	376 w/Cummins 6CT8.3 (8.3L) Eng. <b>F-F Lube</b> (3313281)..... <b>B205 +</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Fuel/Water Separator</b> (3903410)..... <b>BF1280 +</b> <b>Fuel/Water Separator</b> (3286503)..... <b>BF1226</b> <b>Fuel Spin-on</b> (3903640)..... <b>BF788</b>
	375 w/Cummins M11 (10.8L) Eng. (To 12/1995) <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b>	376 w/Cummins L10 (10.0L) Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>F-F Lube</b> (Fleetguard LF670SC)..... <b>B196 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Opt. Fuel/Water Separator</b> (3308638)..... <b>BF1212 +</b> <b>Fuel</b> (154789)..... <b>BF957-D +</b> <b>Coolant</b> (w/4 Units BTA+) (3315116)..... <b>BW5071</b> <b>Coolant</b> (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

PETERBILT Trucks (cont'd)	PETERBILT Trucks (cont'd)	PETERBILT Trucks (cont'd)
376 w/Cummins N14 (14.0L) Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Opt. Fuel/Water Separator</b> (3308638)..... <b>BF1212 +</b> <b>Fuel</b> (154789)..... <b>BF957-D +</b> <b>Coolant</b> (w/4 Units BTA+)..... (3315116)..... <b>BW5071</b>	377 w/Cat 3176 Eng. <b>F-F Lube</b> (1R0716)..... <b>B99 +</b> <b>P. Fuel</b> (1R1740)..... <b>BF970 +</b> <b>S. Fuel</b> (1R0750)..... <b>BF7633 +</b> <b>Fuel</b> (1R0749)..... <b>BF7587 +</b> <b>Air</b> (Don. P522293)..... <b>PA2732</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (w/15 Units BTA+)..... (Fleetguard WF2075)..... <b>BW5075</b> <b>Coolant</b> (Controlled Release) (Nalcool NF2088)..... <b>BW5200</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>2 23/32 In. Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>2 31/32 In. Steering</b> (ZF 7632-141-102)..... <b>P106-HD</b>	377 w/Cummins M11 Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Fuel/Water Separator</b> (Fleetguard FS1212)..... <b>BF1212 +</b> <b>Air</b> (Don. P522293)..... <b>PA2732</b> <b>Air Dryer</b> (AD-SP System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>
377 w/Cat C10 Eng. <b>Lube</b> (1R0716)..... <b>B99 +</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (1335673)..... <b>BF1395-O</b> <b>Fuel/Water Separator</b> (w/Drain) (1335673)..... <b>BF1265</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (1335673)..... <b>BF1395-SP</b> <b>Fuel/Water Separator</b> (1752949). <b>BF1268</b> <b>Fuel Ele.</b> (9M2342)..... <b>PF935</b> <b>Fuel Spin-on</b> (1R0749)..... <b>BF7587 +</b> <b>Radial Seal Air</b> (Don. EAF5106).. <b>RS3516</b> <b>Radial Seal XP Air</b> (Don. DBA5106)..... <b>RS3516XP</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (w/4 Units BTE) (9N3368)..... <b>BW5137</b> <b>Coolant</b> (w/8 Units BTE) (9N3367)..... <b>BW5139</b> <b>Coolant</b> (Controlled Release) (Nalcool NF2088)..... <b>BW5200</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	377 w/Cummins 6B 5.9L Eng. <b>Lube</b> (To 1998) (3914395)..... <b>BT339 +</b> <b>Lube</b> (1998-on) (Chrysler 5083285AA)..... <b>BT7349</b> <b>Fuel/Water Separator</b> (3925274). <b>BF1280 +</b> <b>Fuel</b> (3903640)..... <b>BF788</b>	377 w/Cummins Signature 600 (15.0L) Eng. <b>11 25/32 In. Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154 +</b> <b>14 7/32 In. Dual-Flow Lube</b> (Fleetguard LF9000)..... <b>BD7153 +</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (3331096). <b>BF1274-SP</b> <b>Fuel/Water Separator</b> (4010651). <b>BF1277-SPS</b> <b>Coolant</b> (Fleetguard WF2126)..... <b>BW5086</b>
377 w/Cat C12 Eng. <b>Lube</b> (1R0716)..... <b>B99 +</b> <b>5 7/16 In. Fuel</b> (Fleetguard FF105)..... <b>BF957 +</b> <b>10 1/2 In. Fuel</b> (1R0749)..... <b>BF7587 +</b> <b>Radial Seal Air</b> (Don. EAF5106).. <b>RS3516</b> <b>Radial Seal XP Air</b> (Don. DBA5106)..... <b>RS3516XP</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-SP System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	377 w/Cummins ISX 15.0 (14.9L) Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9070)..... <b>BD7153 +</b> <b>Dual-Flow Lube</b> (Fleetguard LF9080)..... <b>BD7154 +</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FF5369W)..... <b>PF7744</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19728)..... <b>PF7782</b> <b>Fuel Spin-on</b> (Fleetguard FF2200)..... <b>BF7766</b> <b>Fuel Spin-on</b> (Fleetguard FF2203)..... <b>BF7760</b> <b>Coolant</b> (w/o Chemical) (Fleetguard WF2127)..... <b>B5087</b> <b>Coolant</b> (w/11 1/2 Units BTA+)..... (Fleetguard WF2126)..... <b>BW5086</b> <b>Coolant</b> (Controlled Release BTA+) (Fleetguard WF2121)..... <b>BW5250</b>	377 w/Cummins VT903 (14.8L) Eng <b>F-F Lube Ele.</b> (158139)..... <b>P999-HD</b> <b>F-F Lube Spin-on</b> (3313279)..... <b>B96 +</b> <b>B-P Lube Ele.</b> (256838)..... <b>C750-E +</b> <b>B-P Lube Spin-on</b> (3313283)..... <b>B7577</b> <b>Fuel/Water Separator</b> (3308638). <b>BF1212 +</b> <b>Fuel</b> (156172)..... <b>BF957-D +</b>
377 w/Cat C15 Eng. <b>Lube</b> (1R0716)..... <b>B99 +</b> <b>Fuel</b> (1R0749)..... <b>BF7587 +</b> <b>Radial Seal Air</b> (Don. EAF5106).. <b>RS3516</b> <b>Radial Seal XP Air</b> (Don. DBA5106)..... <b>RS3516XP</b> <b>Cab Air</b> (Elixaire 5X010007)..... <b>PA5320</b> <b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	377 w/Cummins L10 (10.0L) Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Opt. Fuel/Water Separator</b> (3308638)..... <b>BF1212 +</b> <b>Fuel</b> (154789)..... <b>BF957-D +</b> <b>Coolant</b> (w/4 Units BTA+)..... (3315116)..... <b>BW5071</b> <b>Coolant</b> (w/15 Units BTA+)..... (Fleetguard WF2075)..... <b>BW5075</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	377 w/Detroit Diesel Series 60 (12.7L) Eng. (To 1993) <b>F-F Lube</b> (23518671)..... <b>[2] B95 +</b> <b>B-P Lube</b> (23518672)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (23521528)..... <b>PF7744</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1212)..... <b>BF1212 +</b> <b>Fuel/Water Separator</b> (Racor 2020PM)..... <b>PF7890-30</b> <b>Fuel/Water Separator Spin-on</b> .... <b>BF5812</b> <b>P. Fuel</b> ..... <b>BF5800 +</b> <b>S. Fuel</b> (23518482)..... <b>BF5810</b> <b>Conical Air</b> (Don. P522293)..... <b>PA2732</b> <b>Axial Seal Air</b> (Don. P150695).... <b>PA2680</b> <b>23 23/32 In. Radial Seal Air</b> (Don. P534816)..... <b>[2] RS3539</b> <b>23 23/32 In. Radial Seal XP Air</b> (Don. P534816)..... <b>[2] RS3539XP</b> <b>25 23/32 In. Radial Seal Air</b> (Don. P534925)..... <b>[2] RS3534</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b> <b>Coolant</b> (w/4 Units BTA+)..... (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/15 Units BTA+)..... (Fleetguard WF2075)..... <b>BW5075</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

**Trucks & Buses Applications** **BALDWIN FILTERS**

<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>
377 w/Detroit Diesel Series 60 (12.7L) Eng. (1993-on)	378 w/Cat C10 (10.3L) Eng. (1/2004-on) (Cont'd)	378 w/Cat C12 (12.0L) Eng. (To 1/2004) (Cont'd)
Lube..... [2] B495	Fuel/Water Separator Spin-on (Fleetguard FS1212)..... BF1212 +	Coolant (w/o Chemical) (Fleetguard WF2127)..... B5087
Fuel/Water Separator Ele. (23521528)..... PF7744	Fuel Ele..... [2] PF935	Coolant (w/Chemical) (Fleetguard WF2071)..... BW5071
Fuel/Water Separator Spin-on (Fleetguard FS1212)..... BF1212 +	Fuel Spin-on (1R0749)..... BF7587 +	Opt. Trans. (Fuller 17237)..... B2 +
Fuel/Water Separator (Racor 2020PM)..... PF7890-30	Fuel Spin-on (1R0712)..... BF614 +	Steering (Nelson 87904M)..... PT9354-MPG
Fuel/Water Separator Spin-on..... BF5812	Fuel Spin-on (Fleetguard FF105)..... BF957 +	378 w/Cat C12 (12.0L) Eng. (1/2004-on)
P. Fuel..... BF5800 +	Axial Seal Air (Don. P522293)..... PA2732	F-F Lube (1R1808)..... B7299 +
S. Fuel (23518482)..... BF5810	21 9/32 In. Radial Seal Air (Don. P542753)..... RS4564	B-P Lube..... B7577
Conical Air (Don. P522293)..... PA2732	23 23/32 In. Radial Seal Air..... RS3539	Fuel/Water Separator Ele..... PF316
Axial Seal Air (Don. P150695)..... PA2680	Cab Air (Elixaire 5X010007)..... PA5320	Fuel/Water Separator Spin-on..... BF5812
23 23/32 In. Radial Seal Air (Don. P534816)..... [2] RS3539	Air Dryer (AD-IP System) (Bendix 65624)..... BA5373	Fuel/Water Separator Spin-on (Fleetguard FS1212)..... BF1212 +
23 23/32 In. Radial Seal XP Air (Don. P534816)..... [2] RS3539XP	Coolant (w/o Chemical) (Fleetguard WF2127)..... B5087	Fuel Ele..... [2] PF935
25 23/32 In. Radial Seal Air (Don. P534925)..... [2] RS3534	Coolant (w/Chemical) (Fleetguard WF2071)..... BW5071	Fuel Spin-on (1R0749)..... BF7587 +
Air Dryer (AD-9 System) (Bendix 107796)..... BA5377	Opt. Trans. (Fuller 17237)..... B2 +	Fuel Spin-on (1R0712)..... BF614 +
Air Dryer (Wabco R950011)..... BA5374 +	Steering (Nelson 87904M)..... PT9354-MPG	Fuel Spin-on (Fleetguard FF105)..... BF957 +
Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071	378 w/Cat C11 (11.1L) Eng.	Axial Seal Air (Don. P522293)..... PA2732
Coolant (w/15 Units BTA+) (Fleetguard WF2075)..... BW5075	F-F Lube..... B7299 +	21 9/32 In. Radial Seal Air (Don. P542753)..... RS4564
Opt. Trans. (Fuller 17237)..... B2 +	Fuel/Water Separator Ele..... PF7755	23 23/32 In. Radial Seal Air..... RS3539
Steering (Nelson 87904M)..... PT9354-MPG	Fuel Spin-on (Fleetguard FF105)..... BF957 +	Cab Air (Elixaire 5X010007)..... PA5320
378 w/Cat C10 (10.3L) Eng. (To 1/2004)	Fuel Spin-on (1R0749)..... BF7587 +	Air Dryer (AD-IP System) (Bendix 65624)..... BA5373
F-F Lube (1R0716)..... B99 +	Radial Seal Air (Don. P534816)..... RS3539	Coolant (w/o Chemical) (Fleetguard WF2127)..... B5087
B-P Lube..... B7577	Radial Seal XP Air (Don. P534816)..... RS3539XP	Coolant (w/Chemical) (Fleetguard WF2071)..... BW5071
Fuel/Water Separator Ele..... PF316	Air Dryer (AD-SP System) (Bendix 5008414)..... BA5374 +	Opt. Trans. (Fuller 17237)..... B2 +
Fuel/Water Separator Spin-on..... BF5812	Coolant (Fleetguard WF2127)..... B5087	Steering (Nelson 87904M)..... PT9354-MPG
Fuel/Water Separator Spin-on (Fleetguard FS1212)..... BF1212 +	Trans. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	378 w/Cat C13 (12.5L) Eng.
Fuel Ele..... [2] PF935	Trans. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	F-F Lube..... B7299 +
Fuel Spin-on (1R0749)..... BF7587 +	Steering (Nelson 87904M)..... PT9354-MPG	Fuel/Water Separator Ele..... PF7755
Fuel Spin-on (1R0712)..... BF614 +	378 w/Cat C12 (12.0L) Eng. (To 1/2004)	Fuel Spin-on (Fleetguard FF105)..... BF957 +
Fuel Spin-on (Fleetguard FF105)..... BF957 +	F-F Lube (1R0716)..... B99 +	Fuel Spin-on (1R0749)..... BF7587 +
Axial Seal Air (Don. P522293)..... PA2732	B-P Lube..... B7577	Radial Seal Air (Don. P534816)..... RS3539
21 9/32 In. Radial Seal Air (Don. P542753)..... RS4564	Fuel/Water Separator Ele..... PF316	Radial Seal XP Air (Don. P534816)..... RS3539XP
23 23/32 In. Radial Seal Air..... RS3539	Fuel/Water Separator Spin-on..... BF5812	Air Dryer (AD-SP System) (Bendix 5008414)..... BA5374 +
Cab Air (Elixaire 5X010007)..... PA5320	Fuel/Water Separator Spin-on (Fleetguard FS1212)..... BF1212 +	Coolant (Fleetguard WF2127)..... B5087
Air Dryer (AD-IP System) (Bendix 65624)..... BA5373	Fuel Ele..... [2] PF935	Trans. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT
Coolant (w/o Chemical) (Fleetguard WF2127)..... B5087	Fuel Spin-on (1R0749)..... BF7587 +	Trans. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT
Coolant (w/Chemical) (Fleetguard WF2071)..... BW5071	Fuel Spin-on (1R0712)..... BF614 +	Steering (Nelson 87904M)..... PT9354-MPG
Opt. Trans. (Fuller 17237)..... B2 +	Fuel Spin-on (Fleetguard FF105)..... BF957 +	378 w/Cat C15, C16 Eng.
Steering (Nelson 87904M)..... PT9354-MPG	Axial Seal Air (Don. P522293)..... PA2732	F-F Lube (To 1/2004) (1R0716)..... B99 +
378 w/Cat C10 (10.3L) Eng. (1/2004-on)	21 9/32 In. Radial Seal Air (Don. P542753)..... RS4564	F-F Lube (1/2004-on) (1R1808)..... B7299 +
F-F Lube (1R1808)..... B7299 +	23 23/32 In. Radial Seal Air..... RS3539	B-P Lube..... B7577
B-P Lube..... B7577	Cab Air (Elixaire 5X010007)..... PA5320	Fuel/Water Separator Ele. (Davco 382113)..... PF7748
Fuel/Water Separator Ele..... PF316	Air Dryer (AD-IP System) (Bendix 65624)..... BA5373	Fuel/Water Separator Spin-on..... BF5812
Fuel/Water Separator Spin-on..... BF5812		P. Fuel Spin-on..... BF7587 +
		S. Fuel Spin-on..... BF7633 +

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

PETERBILT Trucks (cont'd)	PETERBILT Trucks (cont'd)	PETERBILT Trucks (cont'd)
378 w/Cat C15, C16 Engs. (Cont'd)	378 w/Cat 3306 Eng. (Cont'd)	378 w/Cummins ISM 10.8 (10.8L) Eng.
Fuel (Fleetguard FF105)..... <b>BF957 +</b>	Coolant (Fleetguard WF2075)..... <b>BW5075</b>	(2007-on)
Axial Seal Air (Don. P522293)..... <b>PA2732</b>	Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	Dual-Flow Lube..... <b>BD7153 +</b>
Radial Seal Air (Don. P534816)... <b>RS3539</b>	Steering (Nelson 83213H)..... <b>PT903</b>	Fuel/Water Separator Ele..... <b>PF7755</b>
Radial Seal XP Air (Don. P534816)..... <b>RS3539XP</b>	378 w/Cat 3406 Eng.	Fuel/Water Separator Spin-on..... <b>BF1272-SPS</b>
Cab Air (Elixiaire 5X010007)..... <b>PA5320</b>	Lube (1R0716)..... <b>B99 +</b>	Air (Don. P522293)..... <b>PA2732</b>
Air Dryer (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	Lube (High Efficiency) (1R1808).. <b>B7299 +</b>	Cab Air (Elixiaire 5X010007)..... <b>PA5320</b>
Air Dryer (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	Fuel/Water Separator (Fleetguard FS1212)..... <b>BF1212 +</b>	Air Dryer (Bendix 109493)..... <b>BA5373</b>
Coolant (w/o Chemical) (Fleetguard WF2127)..... <b>B5087</b>	Fuel (Fleetguard FF105)..... <b>BF957 +</b>	Breather (3683918)..... <b>CV15000</b>
Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>	Conical Air (Don. P522293)..... <b>PA2732</b>	Coolant..... <b>BW5071</b>
Coolant (w/4 Units BTE)..... <b>BW5137</b>	Axial Seal Air (Don. P181007).... <b>[2] PA2312</b>	Opt. Trans. (Fuller 17237)..... <b>B2 +</b>
Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	23 23/32 In. Radial Seal Air (Don. P534816)..... <b>RS3539</b>	Steering (Nelson 87904M)..... <b>PT9354-MPG</b>
2 23/32 In. Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	23 23/32 In. Radial Seal XP Air (Don. P534816)..... <b>RS3539XP</b>	378 w/Cummins ISX Eng.
4 3/16 In. Steering (Nelson 83804E)..... <b>P528</b>	25 23/32 In. Radial Seal Air (Don. P534925)..... <b>[2] RS3534</b>	11 13/16 In. Dual-Flow Lube (Fleetguard LF9001)..... <b>BD7154 +</b>
378 w/Cat 3126 (7.2L) Eng.	Air Dryer (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	14 7/32 In. Dual-Flow Lube..... <b>BD7153 +</b>
Lube (Standard Vers.) (1R0739).. <b>B76 +</b>	Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>	Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>
Lube (Severe Service) (1R0739).. <b>B76-SS +</b>	Coolant (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b>	Fuel/Water Separator Ele. (Racor 1000FG)..... <b>PF7890</b>
Fuel/Water Separator (1752949). <b>BF1268</b>	Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	Fuel/Water Separator Ele. (Davco 382116)..... <b>PF7755</b>
Fuel/Water Separator (2568753). <b>BF1259</b>	2 23/32 In. Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	Fuel/Water Separator Spin-on (Fleetguard FS1007)..... <b>BF1274-SP</b>
Fuel/Water Separator (w/Sensor Port) (1986378)..... <b>BF7798-SP</b>	4 3/16 In. Steering (Nelson 83804E)..... <b>P528</b>	Fuel/Water Separator Spin-on (Fleetguard FS1040)..... <b>BF1277-SPS</b>
Fuel/Water Separator (Open End for Bowl) (1986378)..... <b>BF7798-O</b>	378 w/Cummins 6BT5.9 (5.9L) Eng.	Fuel (Fleetguard FF2200)..... <b>BF7766</b>
Fuel Ele. (9M2342)..... <b>[2] PF935</b>	Lube (Chrysler 5083285AA)..... <b>BT7349</b>	Fuel (Fleetguard FF2203)..... <b>BF7760</b>
Fuel Spin-on (1R0751)..... <b>BF7632</b>	Fuel/Water Separator (4741689). <b>BF1223 +</b>	Radial Seal Air (Don. P534816)... <b>[2] RS3539</b>
Trans. (Fuller 4304827)..... <b>BT223</b>	Fuel/Water Separator (3903202). <b>BF1226</b>	Radial Seal XP Air (Don. P534816)..... <b>[2] RS3539XP</b>
Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	378 w/Cummins 6CT8.3 (8.3L) Eng.	Cab Air (Elixiaire 5X010007)..... <b>PA5320</b>
378 w/Cat 3176 Eng.	F-F Lube (3313281)..... <b>B205 +</b>	Air Dryer (Bendix 109493)..... <b>BA5373</b>
F-F Lube (1R0716)..... <b>B99 +</b>	Dual-Flow Lube (3318853)..... <b>BD103 +</b>	Breather (3683918)..... <b>CV15000</b>
Fuel/Water Separator Ele. (8N0205)..... <b>PF316</b>	Fuel/Water Separator (3903410). <b>BF1280 +</b>	Coolant (w/11 1/2 units BTA+) (Fleetguard WF2126)..... <b>BW5086</b>
Fuel Ele. (8H7204)..... <b>PF935</b>	Fuel/Water Separator (3286503). <b>BF1226</b>	Coolant (w/o Chemical) (Fleetguard WF2127)..... <b>B5087</b>
Fuel Spin-on (Fleetguard FF105)..... <b>BF957 +</b>	Fuel Spin-on (3903640)..... <b>BF788</b>	Opt. Trans. (Fuller 17237)..... <b>B2 +</b>
Conical Air (Don. P521598)..... <b>PA2729</b>	378 w/Cummins ISB (5.9L) Eng.	Steering (Nelson 87904M)..... <b>PT9354-MPG</b>
Axial Seal Air (Don. P181008).... <b>PA2317 +</b>	Lube (3937736)..... <b>B7177</b>	378 w/Cummins L10 Eng.
Air Dryer (Wabco R950011)..... <b>BA5374 +</b>	Lube (4897898)..... <b>BT7237</b>	Dual-Flow Lube (3318853)..... <b>BD103 +</b>
Coolant (Fleetguard WF2075).... <b>BW5075</b>	Fuel (Fleetguard FF5632)..... <b>BF7940</b>	F-F Lube (Fleetguard LF670SC).. <b>B196 +</b>
Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	378 w/Cummins ISM 10.8 (10.8L) Eng. (To 2007)	B-P Lube (3304232)..... <b>B7577</b>
2 23/32 In. Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	Dual-Flow Lube..... <b>BD7153 +</b>	Fuel (154789)..... <b>BF957-D +</b>
4 3/16 In. Steering (Nelson 83213H)..... <b>PT903</b>	Fuel/Water Separator Ele..... <b>PF7755</b>	Coolant (Fleetguard WF2074).... <b>BW5074</b>
378 w/Cat 3306 Eng.	Fuel/Water Separator Spin-on.... <b>BF1272-SPS</b>	378 w/Cummins M11 Eng.
Lube (Standard Vers.) (1R0739).. <b>B76 +</b>	Air (Don. P522293)..... <b>PA2732</b>	Dual-Flow Lube (Fleetguard LF3000)..... <b>BD103 +</b>
Lube (Spinner II 70669)..... <b>BC7186 KIT</b>	Cab Air (Elixiaire 5X010007)..... <b>PA5320</b>	Fuel/Water Separator (Fleetguard FS1000)..... <b>BF1259</b>
Lube (Severe Service) (1R0739).. <b>B76-SS +</b>	Air Dryer (Bendix 109493)..... <b>BA5373</b>	Conical Air (Don. P522293)..... <b>PA2732</b>
Fuel (Fleetguard FF105)..... <b>BF957 +</b>	Coolant..... <b>BW5071</b>	Axial Seal Air (Don. P181007).... <b>PA2312</b>
Fuel (1R0750)..... <b>BF7633 +</b>	Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	Cab Air (Elixiaire 5X010007).... <b>PA5320</b>
Air (Don. P140822)..... <b>PA2500 +</b>	Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b>		Coolant (Fleetguard WF2071).... <b>BW5071</b>
		Opt. Trans. (Fuller 17237)..... <b>B2 +</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

**Trucks & Buses Applications** **BALDWIN FILTERS**

<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>
378 w/Cummins M11 Eng. (Cont'd) 2 23/32 In. Steering (Nelson 87904M)..... <b>PT9354-MPG</b> 3 31/32 In. Steering (ZF 7632-141-102)..... <b>P106-HD</b>	378 w/Detroit Diesel Series 60 (12.7L) Eng. (1993-12/2003) F-F Lube (23527033)..... <b>[2] B495</b> B-P Lube (23518672)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (23521528)..... <b>PF7744</b> <b>Fuel/Water Separator Spin-on</b> ..... <b>BF5812</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1212)..... <b>BF1212 +</b> S. Fuel (23518482)..... <b>BF5810</b> Axial Seal Air (Don. P181008)..... <b>PA2317 +</b> Radial Seal Air (Don. P534816)..... <b>[2] RS3539</b> Radial Seal XP Air (Don. P534816)..... <b>[2] RS3539XP</b> Air Dryer (AD-9 System) (Bendix 107794)..... <b>BA5377</b> Air Dryer (AD-SP System) (Bendix 5008414)..... <b>BA5374 +</b> Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> Coolant (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> 2 23/32 In. Steering (Nelson 87904M)..... <b>PT9354-MPG</b> 4 3/16 In. Steering (Nelson 83213H)..... <b>PT903</b>	379 w/Cat 3126 (7.2L) Eng. (Cont'd) <b>Fuel/Water Separator</b> (w/Sensor Port) (1986378)..... <b>BF7798-SP</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (1986378)..... <b>BF7798-O</b> <b>Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (1R0751)..... <b>BF7632</b>
378 w/Cummins NTC350 Eng. Dual-Flow Lube (Fleetguard LF3000)..... <b>BD103 +</b> Dual-Flow Lube (Upgrade) (Fleetguard LF9009)..... <b>BD7309 +</b> Air (Don. P181007)..... <b>[2] PA2312</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Steering (ZF 7632-141-107)..... <b>P106-HD</b>	378 w/Detroit Diesel Series 60 (12.7L) Eng. (12/2003-on) F-F Lube (23527033)..... <b>[2] B495</b> B-P Lube (23518672)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (23521528)..... <b>PF7744</b> <b>Fuel/Water Separator Spin-on</b> ..... <b>BF5812</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1212)..... <b>BF1212 +</b> S. Fuel (23530645)..... <b>BF5815</b> Axial Seal Air (Don. P181008)..... <b>PA2317 +</b> Radial Seal Air (Don. P534816)..... <b>[2] RS3539</b> Radial Seal XP Air (Don. P534816)..... <b>[2] RS3539XP</b> Air Dryer (AD-9 System) (Bendix 107794)..... <b>BA5377</b> Air Dryer (AD-SP System) (Bendix 5008414)..... <b>BA5374 +</b> Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> Coolant (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> 2 23/32 In. Steering (Nelson 87904M)..... <b>PT9354-MPG</b> 4 3/16 In. Steering (Nelson 83213H)..... <b>PT903</b>	379 w/Cat 3176 (10.3L) Eng. F-F Lube (Std. Version) (1R0716)..... <b>B99 +</b> F-F Lube (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> F-F Lube (1R0713)..... <b>[2] BT230 +</b> F-F Lube (1R0714)..... <b>[2] B75</b> Opt. B-P Lube (1W8845)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Fuel/Water Separator Spin-on</b> (2568753)..... <b>BF1259</b> P. Fuel Ele. (9M2342)..... <b>[2] PF935</b> P. Fuel Spin-on (1R1740)..... <b>BF970 +</b> S. Fuel Spin-on (1R0750)..... <b>BF7633 +</b>
378 w/Cummins NTC444 Eng. Dual-Flow Lube (Fleetguard LF3000)..... <b>BD103 +</b> Fuel (Fleetguard FF105)..... <b>BF957 +</b> Air (Don. P181007)..... <b>[2] PA2312</b> Steering (ZF 7632-141-102)..... <b>P106-HD</b>	378 w/Detroit Diesel Series 60 (12.7L) Eng. (To 1993) F-F Lube (23518671)..... <b>[2] B95 +</b> B-P Lube (23518672)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (23521528)..... <b>PF7744</b> <b>Fuel/Water Separator Spin-on</b> ..... <b>BF5812</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1212)..... <b>BF1212 +</b> S. Fuel (23518482)..... <b>BF5810</b> Axial Seal Air (Don. P181008)..... <b>PA2317 +</b> Radial Seal Air (Don. P534816)..... <b>[2] RS3539</b> Radial Seal XP Air (Don. P534816)..... <b>[2] RS3539XP</b> Air Dryer (AD-9 System) (Bendix 107794)..... <b>BA5377</b> Air Dryer (AD-SP System) (Bendix 5008414)..... <b>BA5374 +</b> Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> Coolant (w/15 Units BTA+) (Fleetguard WF2075)..... <b>BW5075</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> 2 23/32 In. Steering (Nelson 87904M)..... <b>PT9354-MPG</b> 4 3/16 In. Steering (Nelson 83213H)..... <b>PT903</b>	379 w/Cat 3208 (10.4L) Eng. Lube (1R0713)..... <b>[2] BT230 +</b> Lube (1R0714)..... <b>[2] B75</b> Lube (9L9200)..... <b>[2] BT364</b> <b>Box-Style Fuel/Water Separator</b> (8N9803)..... <b>BF912</b> P. Fuel Ele. (9M2341)..... <b>PF935</b> P. Fuel Spin-on (1R0740)..... <b>BF970 +</b> S. Fuel Spin-on (1R0750)..... <b>BF7633 +</b>
378 w/Cummins Signature 600 (15.0L) Eng. 11 25/32 In. Dual-Flow Lube (Fleetguard LF9001)..... <b>BD7154 +</b> 14 7/32 In. Dual-Flow Lube (Fleetguard LF9000)..... <b>BD7153 +</b> Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> Fuel/Water Separator (3331096)..... <b>BF1274-SP</b> Fuel/Water Separator (4010651)..... <b>BF1277-SPS</b> Coolant (Fleetguard WF2126)..... <b>BW5086</b>	379 w/Cat 3406 (14.6L) Eng. F-F Lube (1R0716)..... <b>B99 +</b> Opt. Fuel/Water Separator (175-2949)..... <b>BF1268</b> Opt. Fuel/Water Separator (Fleetguard FS1000)..... <b>BF1259</b> <b>Fuel/Water Separator</b> (Fleetguard FS1212)..... <b>BF1212 +</b> <b>Fuel Spin-on</b> (1R0749)..... <b>BF7587 +</b> <b>Fuel Spin-on</b> (Fleetguard FF105)..... <b>BF957 +</b> <b>Axial Seal Air</b> (Don. P521598)..... <b>PA2729</b> <b>23 23/32 In. Radial Seal Air</b> (Don. P534816)..... <b>RS3539</b> <b>23 23/32 In. Radial Seal XP Air</b> (Don. P534816)..... <b>RS3539XP</b> <b>25 23/32 In. Radial Seal Air</b> (Don. P534925)..... <b>RS3534</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-SP System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b> <b>Opt. Coolant</b> (Controlled Release BTE)..... <b>BW5200</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



PETERBILT Trucks (cont'd)	
379 w/Cat C16 Eng.	
Lube.....	B99 +
Fuel/Water Separator Ele. (Davco 380087).....	PF7680
Fuel/Water Separator Ele. (Racor 1000FG).....	PF7890
Fuel (1R0749).....	BF7587 +
Fuel (Fleetguard FF105).....	BF957 +
Air (Vortex VF160R).....	[2] PA2608 +
Cab Air (Elixaire 5X010007).....	PA5320
Air Dryer (AD-IS, AD-SP System) (Bendix 5008414).....	BA5374 +
Coolant (Fleetguard WF2071).....	BW5071
Steering (Nelson 87904M).....	PT9354-MPG
379 w/Cummins 6BT5.9 (5.9L) Eng.	
Lube (Chrysler 5083285AA).....	BT7349
Fuel/Water Separator (4741689).....	BF1223 +
Fuel/Water Separator (3903202).....	BF1226
379 w/Cummins 6CT8.3 (8.3L) Eng.	
F-F Lube (3313281).....	B205 +
Dual-Flow Lube (3318853).....	BD103 +
Fuel/Water Separator (3903410).....	BF1280 +
Fuel/Water Separator (3286503).....	BF1226
Fuel Spin-on (3903640).....	BF788
379 w/Cummins L10 (10.0L) Eng.	
Dual-Flow Lube (3318853).....	BD103 +
F-F Lube (Fleetguard LF670SC).....	B196 +
B-P Lube (3304232).....	B7577
Opt. Fuel/Water Separator (3308638).....	BF1212 +
Fuel (154789).....	BF957-D +
Coolant (w/4 Units BTA+) (3315116).....	BW5071
Coolant (w/12 Units BTA+) (Fleetguard WF2074).....	BW5074
379 w/Cummins M11 (10.8L) Eng. (To 12/1995)	
Dual-Flow Lube (3318853).....	BD103 +
Fuel/Water Separator Ele. (Fleetguard FS1029W).....	PF7680
Fuel/Water Separator Spin-on (3308638).....	BF1212 +
379 w/Cummins M11 (10.8L) Eng. (12/1995-on)	
Dual-Flow Lube (3318853).....	BD103 +
Fuel/Water Separator Ele. (Fleetguard FS1029W).....	PF7680
Fuel/Water Separator Spin-on (3329289).....	BF1259
379 w/Cummins Signature 600 (15.0L) Eng.	
11 25/32 In. Dual-Flow Lube (Fleetguard LF9001).....	BD7154 +
14 7/32 In. Dual-Flow Lube (Fleetguard LF9000).....	BD7153 +
Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN).....	BD50000
Fuel/Water Separator (3331096).....	BF1274-SP
Fuel/Water Separator (4010651).....	BF1277-SPS
Coolant (Fleetguard WF2126).....	BW5086

PETERBILT Trucks (cont'd)	
379 w/Detroit Diesel 8V-71 (9.3L) Eng.	
Lube (23530407).....	B95 +
Lube (Upgrade) (23530408).....	B95-MPG +
379 w/Detroit Diesel 12V71 (14.0L) Eng.	
Lube (23530407).....	[2] B95 +
Lube (Upgrade) (23530408).....	[2] B95-MPG +
P. Fuel (23530642).....	[2] BF784
S. Fuel (23530643).....	BF785
S. Fuel (23530644).....	BF7697
379 w/Detroit Diesel Series 50 (8.5L) Eng.	
Lube (23530573).....	[2] B495
P. Fuel (23530706).....	BF5800 +
S. Fuel (23530707).....	BF5810
379 w/Detroit Diesel Series 60 (12.7L) Eng. (To 1993)	
F-F Lube (23518671).....	[2] B95 +
B-P Lube (23518672).....	B7577
Fuel/Water Separator Ele. (23521528).....	PF7744
Fuel/Water Separator Spin-on (Fleetguard FS1212).....	BF1212 +
Fuel/Water Separator (Racor 2020PM).....	PF7890-30
Fuel/Water Separator Spin-on.....	BF5812
P. Fuel.....	BF5800 +
S. Fuel (23518482).....	BF5810
Conical Air (Don. P522293).....	PA2732
Axial Seal Air (Don. P150695).....	PA2680
23 23/32 In. Radial Seal Air (Don. P534816).....	[2] RS3539
23 23/32 In. Radial Seal XP Air (Don. P534816).....	[2] RS3539XP
25 23/32 In. Radial Seal Air (Don. P534925).....	[2] RS3534
Air Dryer (AD-9 System) (Bendix 107796).....	BA5377
Air Dryer (Wabco R950011).....	BA5374 +
Coolant (w/4 Units BTA+) (Fleetguard WF2071).....	BW5071
Coolant (w/15 Units BTA+) (Fleetguard WF2075).....	BW5075
Opt. Trans. (Fuller 17237).....	B2 +
Steering (Nelson 87904M).....	PT9354-MPG
379 w/Detroit Diesel Series 60 (12.7L) Eng. (1993-on)	
Lube.....	[2] B495
Fuel/Water Separator Ele. (23521528).....	PF7744
Fuel/Water Separator Spin-on (Fleetguard FS1212).....	BF1212 +
Fuel/Water Separator (Racor 2020PM).....	PF7890-30
Fuel/Water Separator Spin-on.....	BF5812
P. Fuel.....	BF5800 +
S. Fuel (23518482).....	BF5810
Conical Air (Don. P522293).....	PA2732
Axial Seal Air (Don. P150695).....	PA2680

PETERBILT Trucks (cont'd)	
379 w/Detroit Diesel Series 60 (12.7L) Eng. (1993-on) (Cont'd)	
23 23/32 In. Radial Seal Air (Don. P534816).....	[2] RS3539
23 23/32 In. Radial Seal XP Air (Don. P534816).....	[2] RS3539XP
25 23/32 In. Radial Seal Air (Don. P534925).....	[2] RS3534
Air Dryer (AD-9 System) (Bendix 107796).....	BA5377
Air Dryer (Wabco R950011).....	BA5374 +
Coolant (w/4 Units BTA+) (Fleetguard WF2071).....	BW5071
Coolant (w/15 Units BTA+) (Fleetguard WF2075).....	BW5075
Opt. Trans. (Fuller 17237).....	B2 +
Steering (Nelson 87904M).....	PT9354-MPG
379, 379x w/Cat C10 (10.3L) Eng. (To 1/2004)	
F-F Lube.....	B99 +
B-P Lube.....	B7577
Fuel/Water Separator Ele.....	PF316
Fuel/Water Separator Spin-on (w/o SP) (1290373).....	BF1283 +
Fuel/Water Separator Spin-on (w/SP) (1290373).....	BF1283-SP +
Fuel/Water Separator Spin-on (Open End for Bowl) (Racor R120S).....	BF1283-O +
Fuel Ele.....	[2] PF935
Fuel Spin-on (1R0712).....	BF614 +
Fuel Spin-on (High Efficiency) (1R0749).....	BF7587 +
Radial Seal Air.....	RS3534
Cab Air (Elixaire 5X010007).....	PA5320
Air Dryer (Bendix 5008414).....	BA5374 +
Coolant (Fleetguard WF2071).....	BW5071
Opt. Trans. (Fuller 17237).....	B2 +
Steering (Nelson 87904M).....	PT9354-MPG
379, 379x w/Cat C10 (10.3L) Eng. (1/2004-on)	
F-F Lube.....	B7299 +
B-P Lube.....	B7577
Fuel/Water Separator Ele.....	PF316
Fuel/Water Separator Spin-on (w/o SP) (1290373).....	BF1283 +
Fuel/Water Separator Spin-on (w/SP) (1290373).....	BF1283-SP +
Fuel/Water Separator Spin-on (Open End for Bowl) (Racor R120S).....	BF1283-O +
Fuel Ele.....	[2] PF935
Fuel Spin-on (1R0712).....	BF614 +
Fuel Spin-on (High Efficiency) (1R0749).....	BF7587 +
Radial Seal Air.....	RS3534
Cab Air (Elixaire 5X010007).....	PA5320
Air Dryer (Bendix 5008414).....	BA5374 +
Coolant (Fleetguard WF2071).....	BW5071
Opt. Trans. (Fuller 17237).....	B2 +
Steering (Nelson 87904M).....	PT9354-MPG

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

**Trucks & Buses Applications** **BALDWIN FILTERS**

<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>
379, 379x w/Cat C11 (11.1L) Eng. Lube (1R1808)..... <b>B7299 +</b> Fuel/Water Separator Ele..... <b>PF7755</b> Fuel (1R0749)..... <b>BF7587 +</b> Fuel (Fleetguard FF105)..... <b>BF957 +</b> Fuel (9M2342)..... <b>PF935</b> 23 23/32 In. Radial Seal Air (Don. P534816)..... <b>RS3539</b> 23 23/32 In. Radial Seal XP Air (Don. P534816)..... <b>RS3539XP</b> 25 23/32 In. Radial Seal Air (Don. P534925)..... <b>RS3534</b> Air Dryer (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> Coolant (w/4 Units BTE) (9N3368)..... <b>BW5137</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	379, 379x w/Cat C12 (12.0L) Eng. (1/2004-on) (Cont'd) Steering (Nelson 87904M)..... <b>PT9354-MPG</b> 379, 379x w/Cat C13 (12.5L) Eng. Lube (1R1808)..... <b>B7299 +</b> Fuel/Water Separator Ele..... <b>PF7755</b> Fuel (1R0749)..... <b>BF7587 +</b> Fuel (Fleetguard FF105)..... <b>BF957 +</b> Fuel (9M2342)..... <b>PF935</b> 23 23/32 In. Radial Seal Air (Don. P534816)..... <b>RS3539</b> 23 23/32 In. Radial Seal XP Air (Don. P534816)..... <b>RS3539XP</b> 25 23/32 In. Radial Seal Air (Don. P534925)..... <b>RS3534</b> Air Dryer (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> Coolant (w/4 Units BTE) (9N3368)..... <b>BW5137</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	379, 379x w/Cat C15 (14.6L) Eng. (1/2004-on) (Cont'd) Fuel Spin-on (Frame Mtd.) (Fleetguard FF105)..... <b>BF957 +</b> Radial Seal Air (11 3/8 O.D.) (Don. P534816)..... <b>[2] RS3539</b> Radial Seal XP Air (11 3/8 O.D.) (Don. P534816)..... <b>[2] RS3539XP</b> Radial Seal Air (13 3/32 O.D.) (Don. P534925)..... <b>[2] RS3534</b> Axial Seal Air (Vortex VF160R)... <b>PA2608 +</b> Cab Air (Elixaire 5X010007)..... <b>PA5320</b> Air Dryer (AD-IP System) (Bendix 65624)..... <b>BA5373</b> Air Dryer (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> Coolant..... <b>BW5071</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>
379, 379x w/Cat C12 (12.0L) Eng. (To 1/2004) F-F Lube..... <b>B99 +</b> B-P Lube..... <b>B7577</b> Fuel/Water Separator Ele..... <b>PF316</b> Fuel/Water Separator Spin-on (w/o SP) (1290373)..... <b>BF1283 +</b> Fuel/Water Separator Spin-on (w/SP) (1290373)..... <b>BF1283-SP +</b> Fuel/Water Separator Spin-on (Open End for Bowl) (Racor R120S)..... <b>BF1283-O +</b> Fuel Ele..... <b>[2] PF935</b> Fuel Spin-on (1R0712)..... <b>BF614 +</b> Fuel Spin-on (High Efficiency) (1R0749)..... <b>BF7587 +</b> Radial Seal Air..... <b>RS3534</b> Cab Air (Elixaire 5X010007)..... <b>PA5320</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Coolant (Fleetguard WF2071)..... <b>BW5071</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	379, 379x w/Cat C15 (14.6L) Eng. (To 1/2004) F-F Lube (1R0716)..... <b>B99 +</b> B-P Lube..... <b>B7577</b> Fuel/Water Separator Ele. (Davco 380087)..... <b>PF7680</b> Fuel/Water Separator Ele. (Davco 382116)..... <b>PF7755</b> Fuel/Water Separator Spin-on..... <b>BF1212 +</b> Fuel Spin-on (Eng. Mtd.) (1R0749)..... <b>BF7587 +</b> Fuel Spin-on (Frame Mtd.) (Fleetguard FF105)..... <b>BF957 +</b> Radial Seal Air (11 3/8 O.D.) (Don. P534816)..... <b>[2] RS3539</b> Radial Seal XP Air (11 3/8 O.D.) (Don. P534816)..... <b>[2] RS3539XP</b> Radial Seal Air (13 3/32 O.D.) (Don. P534925)..... <b>[2] RS3534</b> Axial Seal Air (Vortex VF160R)... <b>PA2608 +</b> Cab Air (Elixaire 5X010007)..... <b>PA5320</b> Air Dryer (AD-IP System) (Bendix 65624)..... <b>BA5373</b> Air Dryer (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> Coolant..... <b>BW5071</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	379, 379x w/Cummins ISC Eng. Dual-Flow Lube (Standard Vers.) (Fleetguard LF3000)..... <b>BD103 +</b> Dual-Flow Lube (High Velocity) (3401544)..... <b>BD7309 +</b> Lube (Upgrade) (3401544)..... <b>B40142 +</b> Fuel/Water Separator Ele..... <b>PF7755</b> Fuel/Water Separator Spin-on..... <b>BF1272-SPS</b> Radial Seal Air..... <b>RS3534</b> Cab Air (Elixaire 5X010007)..... <b>PA5320</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Coolant..... <b>BW5071</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>
379, 379x w/Cat C12 (12.0L) Eng. (1/2004-on) F-F Lube..... <b>B7299 +</b> B-P Lube..... <b>B7577</b> Fuel/Water Separator Ele..... <b>PF316</b> Fuel/Water Separator Spin-on (w/o SP) (1290373)..... <b>BF1283 +</b> Fuel/Water Separator Spin-on (w/SP) (1290373)..... <b>BF1283-SP +</b> Fuel/Water Separator Spin-on (Open End for Bowl) (Racor R120S)..... <b>BF1283-O +</b> Fuel Ele..... <b>[2] PF935</b> Fuel Spin-on (1R0712)..... <b>BF614 +</b> Fuel Spin-on (High Efficiency) (1R0749)..... <b>BF7587 +</b> Radial Seal Air..... <b>RS3534</b> Cab Air (Elixaire 5X010007)..... <b>PA5320</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Coolant (Fleetguard WF2071)..... <b>BW5071</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	379, 379x w/Cat C15 (14.6L) Eng. (1/2004-on) F-F Lube (1R1808)..... <b>B7299 +</b> B-P Lube..... <b>B7577</b> Fuel/Water Separator Ele. (Davco 380087)..... <b>PF7680</b> Fuel/Water Separator Ele. (Davco 382116)..... <b>PF7755</b> Fuel/Water Separator Spin-on..... <b>BF1212 +</b> Fuel Spin-on (Eng. Mtd.) (1R0749)..... <b>BF7587 +</b>	379, 379x w/Cummins ISL Eng. Dual-Flow Lube (Standard Vers.) (Fleetguard LF3000)..... <b>BD103 +</b> Dual-Flow Lube (High Velocity) (3401544)..... <b>BD7309 +</b> Lube (Upgrade) (3401544)..... <b>B40142 +</b> Fuel/Water Separator Ele..... <b>PF7755</b> Fuel/Water Separator Spin-on..... <b>BF1272-SPS</b> Fuel (Fleetguard FF5488)..... <b>BF7815</b> Radial Seal Air..... <b>RS3534</b> Cab Air (Elixaire 5X010007)..... <b>PA5320</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Coolant..... <b>BW5071</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>
	379, 379x w/Cat C15 (14.6L) Eng. (1/2004-on) F-F Lube (1R1808)..... <b>B7299 +</b> B-P Lube..... <b>B7577</b> Fuel/Water Separator Ele. (Davco 380087)..... <b>PF7680</b> Fuel/Water Separator Ele. (Davco 382116)..... <b>PF7755</b> Fuel/Water Separator Spin-on..... <b>BF1212 +</b> Fuel Spin-on (Eng. Mtd.) (1R0749)..... <b>BF7587 +</b>	379, 379x w/Cummins ISM 10.8 (10.8L) Eng. (To 2007) Dual-Flow Lube..... <b>BD7153 +</b> Fuel/Water Separator Ele..... <b>PF7755</b> Fuel/Water Separator Spin-on..... <b>BF1272-SPS</b> 23 23/32 In. Radial Seal Air (Don. P534816)..... <b>RS3539</b> 23 23/32 In. Radial Seal XP Air (Don. P534816)..... <b>RS3539XP</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

PETERBILT Trucks (cont'd)	PETERBILT Trucks (cont'd)	PETERBILT Trucks (cont'd)
379, 379x w/Cummins ISM 10.8 (10.8L) Eng. (To 2007) (Cont'd)	379, 379x w/Cummins ISX 15.0 (14.9L) Eng. (2007-on) (Cont'd)	382 w/Cummins ISL-G (8.9L) Eng. (Cont'd)
25 23/32 In. Radial Seal Air (Don. P534925)..... <b>RS3534</b>	Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>	Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
Cab Air (Elixaire 5X010007)..... <b>PA5320</b>	Fuel/Water Separator (Std. Thd.) <b>BF1272-SPS</b>	Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
Air Dryer (AD-IS, AD-SP System) (Bendix 5008414)..... <b>BA5374 +</b>	Fuel/Water Separator (Metric Thread)..... <b>BF1277-SP</b>	Steering (Nelson 87904M)..... <b>PT9354-MPG</b>
Coolant..... <b>BW5071</b>	Fuel (4088272)..... <b>BF7766</b>	382 w/Paccar PX-9 (8.9L) Eng.
Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	Fuel (Pre-Filter) (Fleetguard FF2203)..... <b>BF7760</b>	Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309 +</b>
Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	Radial Seal Air (Don. P534925)..... <b>RS3534</b>	Fuel/Water Separator (Fleetguard FS1065)..... <b>BF1378-SPS</b>
379, 379x w/Cummins ISM 10.8 (10.8L) Eng. (2007-on)	Cab Air (Elixaire 5X010007)..... <b>PA5320</b>	Fuel/Water Separator (Fleetguard FS1003)..... <b>BF1293-SPS</b>
Dual-Flow Lube..... <b>BD7153 +</b>	Air Dryer (Bendix 5008414)..... <b>BA5374 +</b>	Fuel (Fleetguard FF63009)..... <b>BF63000</b>
Fuel/Water Separator Ele..... <b>PF7755</b>	Breather (3683918)..... <b>CV15000</b>	Radial Seal Air (Don. P527484)..... <b>RS2863</b>
Fuel/Water Separator Spin-on..... <b>BF1272-SPS</b>	Coolant (Controlled Release BTA+) (Fleetguard WF2121)..... <b>BW5250</b>	Radial Seal XP Air (Don. P527484)..... <b>RS2863XP</b>
23 23/32 In. Radial Seal Air (Don. P534816)..... <b>RS3539</b>	Coolant (w/11 1/2 Units BTA+) (Fleetguard WF2125)..... <b>BW5086</b>	Cab Air (5S013817)..... <b>PA5765</b>
23 23/32 In. Radial Seal XP Air (Don. P534816)..... <b>RS3539XP</b>	Coolant (w/o Chemical) (3680434)..... <b>B5087</b>	Air Dryer (Bendix 5008414)..... <b>BA5374 +</b>
25 23/32 In. Radial Seal Air (Don. P534925)..... <b>RS3534</b>	Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	Trans. (Fuller 4304827)..... <b>BT223</b>
Cab Air (Elixaire 5X010007)..... <b>PA5320</b>	Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	Opt. Trans. (Fuller 17237)..... <b>B2 +</b>
Air Dryer (AD-IS, AD-SP System) (Bendix 5008414)..... <b>BA5374 +</b>	382 w/Cummins ISL 8.9 (8.9L) Eng.	Steering (Nelson 87904M)..... <b>PT9354-MPG</b>
Breather (3683918)..... <b>CV15000</b>	Dual-Flow Lube (3401544)..... <b>BD7309 +</b>	Diesel Exhaust Fluid (5303604)..... <b>PE17000</b>
Coolant..... <b>BW5071</b>	Lube (Upgrade) (3401544)..... <b>B40142 +</b>	384 w/Cat C9 Eng.
Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	Fuel/Water Separator (Fleetguard FS1003)..... <b>BF1293-SPS</b>	Lube (1R1808)..... <b>B7299 +</b>
Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	Fuel/Water Separator (Fleetguard FS1065)..... <b>BF1378-SPS</b>	Fuel/Water Separator (Fleetguard FS1000)..... <b>BF1259</b>
379, 379x w/Cummins ISX 15.0 (14.9L) Eng. (To 2007)	Fuel (Fleetguard FF5636)..... <b>BF7924</b>	Fuel (1R0751)..... <b>BF7632</b>
11 13/16 In. Dual-Flow Lube (Fleetguard LF9001)..... <b>BD7154 +</b>	Radial Seal Air (Don. P527484)..... <b>RS2863</b>	Radial Seal Air (Don. P185106)..... <b>RS3516</b>
14 7/32 In. Dual-Flow Lube..... <b>BD7153 +</b>	Radial Seal XP Air (Don. P527484)..... <b>RS2863XP</b>	Radial Seal XP Air (Don. DBA5106)..... <b>RS3516XP</b>
Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>	Cab Air (5S013817)..... <b>PA5765</b>	Cab Air (Elixaire 5X010007)..... <b>PA5320</b>
Fuel/Water Separator (Std. Thd.) <b>BF1272-SPS</b>	Air Dryer (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	Air Dryer (Bendix 5008414)..... <b>BA5374 +</b>
Fuel/Water Separator (Metric Thread)..... <b>BF1277-SP</b>	Coolant (Fleetguard WF2071)..... <b>BW5071</b>	Opt. Trans. (Fuller 17237)..... <b>B2 +</b>
Fuel (4088272)..... <b>BF7766</b>	Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	Steering (Nelson 87904M)..... <b>PT9354-MPG</b>
Fuel (Pre-Filter) (Fleetguard FF2203)..... <b>BF7760</b>	Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	384 w/Cat C13 Eng.
Radial Seal Air (Don. P534925)..... <b>RS3534</b>	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	F-F Lube (1R1808)..... <b>B7299 +</b>
Cab Air (Elixaire 5X010007)..... <b>PA5320</b>	Steering (Nelson 87904A)..... <b>PT9354-MPG</b>	F-F Lube (249-2347)..... <b>[2] B7402</b>
Air Dryer (Bendix 5008414)..... <b>BA5374 +</b>	Diesel Exhaust Fluid (2888182)..... <b>PE17000</b>	Fuel/Water Separator (280-2700)..... <b>BF1259</b>
Coolant (Controlled Release BTA+) (Fleetguard WF2121)..... <b>BW5250</b>	382 w/Cummins ISL-G (8.9L) Eng.	Fuel (1R0749)..... <b>BF7587 +</b>
Coolant (w/11 1/2 Units BTA+) (Fleetguard WF2125)..... <b>BW5086</b>	Dual-Flow Lube (3401544)..... <b>BD7309 +</b>	Radial Seal Air (Don. P185106)..... <b>RS3516</b>
Coolant (w/o Chemical) (3680434)..... <b>B5087</b>	Lube (Upgrade) (3401544)..... <b>B40142 +</b>	Radial Seal XP Air (Don. DBA5106)..... <b>RS3516XP</b>
Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	Fuel/Water Separator (3606712)..... <b>BF7695</b>	Cab Air (Elixaire 5X010007)..... <b>PA5320</b>
Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	Radial Seal Air (Don. P527484)..... <b>RS2863</b>	Air Dryer (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>
379, 379x w/Cummins ISX 15.0 (14.9L) Eng. (2007-on)	Radial Seal XP Air (Don. P527484)..... <b>RS2863XP</b>	Breather (2007-on) (296-8325)..... <b>CV15008</b>
11 13/16 In. Dual-Flow Lube (Fleetguard LF9001)..... <b>BD7154 +</b>	Cab Air (5S013817)..... <b>PA5765</b>	Opt. Trans. (Fuller 17237)..... <b>B2 +</b>
14 7/32 In. Dual-Flow Lube..... <b>BD7153 +</b>	Air Dryer (AD-SP System) (Bendix 109994)..... <b>BA5374 +</b>	Steering (Nelson 87904M)..... <b>PT9354-MPG</b>
	Coolant (w/4 Units BTA+) (3100304)..... <b>BW5071</b>	384 w/Cummins ISL 8.9 (8.9L) Eng.
	Coolant (w/12 Units BTA+) (3100307)..... <b>BW5074</b>	Radial Seal Air (Don. EAF5106)..... <b>RS3516</b>
		Radial Seal XP Air (Don. DBA5106)..... <b>RS3516XP</b>
		Air Dryer (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>
		Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>

\* See Product Guide for Variations of This Number. Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>
384 w/Cummins ISL 8.9 (8.9L) Eng. (Cont'd) Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	384 w/Cummins ISX 11.9 (11.9L) Eng. (Cont'd) <b>Coolant</b> (w/Chemical) (Fleetguard WF2126)..... <b>BW5086</b> <b>Coolant</b> (w/o Chemical) (Fleetguard WF2127)..... <b>B5087</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2+</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Diesel Exhaust Fluid</b> (2010 Emissions) (2888182)..... <b>PE17000</b>	384 w/Paccar MX Eng. (Cont'd) <b>Coolant</b> (Long Version) (1649751)..... <b>B5090</b> <b>Coolant</b> (1843659)..... <b>B5088+</b> <b>Coolant</b> (Short Version) (1649751)..... <b>B5088</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2+</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Diesel Exhaust Fluid</b> (5303604)..... <b>PE17000</b>
384 w/Cummins ISL-G Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309+</b> <b>Fuel/Water Separator</b> (Fleetguard FS1003)..... <b>BF1293-SPS</b> Fuel (Fleetguard NG5900)..... <b>BF7695</b> <b>Radial Seal Air</b> (Don. EAF5106).. <b>RS3516</b> <b>Radial Seal XP Air</b> (Don. DBA5106)..... <b>RS3516XP</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374+</b> Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	384 w/Cummins ISX 15.0 (14.9L) Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9080)..... <b>BD7154+</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (Fleetguard FS1000)..... <b>BF1259</b> <b>Fuel/Water Separator</b> (K371004) <b>PF9928</b> Fuel (Standard) (Fleetguard FF5776)..... <b>BF9885+</b> Fuel (Upgrade) (Fleetguard FF5825NN)..... <b>BF46129</b> <b>Radial Seal Air</b> (Don. EAF5106).. <b>RS3516</b> <b>Radial Seal XP Air</b> (Don. DBA5106)..... <b>RS3516XP</b> <b>Cab Air</b> (5S013817)..... <b>PA5765</b> <b>Air Dryer</b> (AD-IS Model) (Bendix 5008414)..... <b>BA5374+</b> <b>Breather</b> (Fleetguard CV50626)..... <b>CV15000</b> <b>Coolant</b> (w/o Chemical) (4920476)..... <b>B5090</b> <b>Coolant</b> (w/Chemical) (Fleetguard WF2126)..... <b>BW5086</b> <b>Coolant</b> (w/o Chemical) (Fleetguard WF2127)..... <b>B5087</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2+</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Diesel Exhaust Fluid</b> (2010 Emissions) (2888182)..... <b>PE17000</b>	384 w/Paccar MX-13 Eng. <b>Lube Ele.</b> (1643070)..... <b>P40019</b> <b>Centrifugal Lube</b> (1872106)..... <b>BC7326+</b> <b>Fuel/Water Separator</b> (Fleetguard FS19765)..... <b>PF7930</b> Fuel (1852006)..... <b>PF46106</b> <b>Air</b> (Don. EAF5106)..... <b>RS3516</b> <b>Radial Seal XP Air</b> (Don. DBA5106)..... <b>RS3516XP</b> <b>Cab Air</b> (5S013817)..... <b>PA5765</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374+</b> <b>Coolant</b> (1843659)..... <b>B5088+</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2+</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Diesel Exhaust Fluid</b> (5303604)..... <b>PE17000</b>
384 w/Cummins ISM Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154+</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (Fleetguard FS1000)..... <b>BF1259</b> <b>Radial Seal Air</b> (Don. P185106)..... <b>RS3516</b> <b>Radial Seal XP Air</b> (Don. DBA5106)..... <b>RS3516XP</b> <b>Cab Air</b> (Elixair 5X010007)..... <b>PA5320</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374+</b> <b>Breather</b> (3683918)..... <b>CV15000</b> <b>Coolant</b> (w/o Chemical) (4920476)..... <b>B5090</b> <b>Coolant</b> (Fleetguard WF2127)..... <b>B5087</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2+</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	384 w/Paccar PX-9 (8.9L) Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309+</b> <b>Radial Seal Air</b> (Don. P534096)..... <b>RS3516</b> <b>Radial Seal XP Air</b> (Don. DBA5106)..... <b>RS3516XP</b> <b>Cab Air</b> (5S013817)..... <b>PA5765</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2+</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	384 w/Paccar C10 Eng. F-F Lube..... <b>B99+</b> B-P Lube..... <b>B7577</b> <b>Fuel/Water Separator</b> (23516189)..... <b>BF5812</b> <b>Fuel/Water Separator</b> (Fleetguard FS1212)..... <b>BF1212+</b> Fuel (1R0712)..... <b>BF614+</b> Fuel (Fleetguard FF105)..... <b>BF957+</b> <b>Radial Seal Air</b> (Don. P534096)..... <b>RS3516</b> <b>Radial Seal XP Air</b> (Don. DBA5106)..... <b>RS3516XP</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374+</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>
384 w/Cummins ISX 11.9 (11.9L) Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9080)..... <b>BD7154+</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (Fleetguard FS1000)..... <b>BF1259</b> <b>Fuel/Water Separator</b> (K371004) <b>PF9928</b> Fuel (Standard) (Fleetguard FF5776)..... <b>BF9885+</b> Fuel (Upgrade) (Fleetguard FF5825NN)..... <b>BF46129</b> <b>Radial Seal Air</b> (Don. EAF5106).. <b>RS3516</b> <b>Radial Seal XP Air</b> (Don. DBA5106)..... <b>RS3516XP</b> <b>Cab Air</b> (5S013817)..... <b>PA5765</b> <b>Air Dryer</b> (AD-IS Model) (Bendix 5008414)..... <b>BA5374+</b> <b>Coolant</b> (w/o Chemical) (4920476)..... <b>B5090</b>	384 w/Paccar MX Eng. <b>Lube Ele.</b> (1643070)..... <b>P40019</b> <b>Lube Spinner</b> (1643072)..... <b>BC7326+</b> <b>Fuel/Water Separator</b> (Fleetguard FS19624)..... <b>PF7748</b> <b>Fuel/Water Separator</b> (Fleetguard FS19765)..... <b>PF7930</b> <b>Fuel/Water Separator</b> (K37-1005)..... <b>PF9928</b> <b>Fuel/Water Separator</b> (K371029) <b>PF46081</b> <b>Fuel/Water Separator</b> (K371012) <b>PF46082</b> Fuel (1655115)..... <b>BF9927</b> <b>Radial Seal Air</b> (Don. EAF5106).. <b>RS3516</b> <b>Radial Seal XP Air</b> (Don. DBA5106)..... <b>RS3516XP</b> <b>Cab Air</b> (5S013817)..... <b>PA5765</b> <b>Air Dryer</b> (AD-IS Model) (Bendix 5008414)..... <b>BA5374+</b>	385 w/Cat C10 Eng. F-F Lube..... <b>B99+</b> B-P Lube..... <b>B7577</b> <b>Fuel/Water Separator</b> (23516189)..... <b>BF5812</b> <b>Fuel/Water Separator</b> (Fleetguard FS1212)..... <b>BF1212+</b> Fuel (1R0712)..... <b>BF614+</b> Fuel (Fleetguard FF105)..... <b>BF957+</b> <b>Radial Seal Air</b> (Don. P534096)..... <b>RS3516</b> <b>Radial Seal XP Air</b> (Don. DBA5106)..... <b>RS3516XP</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374+</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>
	385 w/Cat C11 Eng. F-F Lube (1R1808)..... <b>B7299+</b> B-P Lube..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> ..... <b>PF7755</b> Fuel (1R0749)..... <b>BF7587+</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

PETERBILT Trucks (cont'd)	PETERBILT Trucks (cont'd)	PETERBILT Trucks (cont'd)
385 w/Cat C11 Eng. (Cont'd)	385 w/Cat C15 Eng.	385 w/Cummins ISL Eng. (Cont'd)
Radial Seal Air (Don. P534096)... <b>RS3516</b>	F-F Lube (1/2004-on) (1R1808)... <b>B7299 +</b>	Radial Seal Air (Don. P534096)... <b>RS3516</b>
Radial Seal XP Air (Don. DBA5106)..... <b>RS3516XP</b>	F-F Lube (To 1/2004)..... <b>B99 +</b>	Radial Seal XP Air (Don. DBA5106)..... <b>RS3516XP</b>
Cab Air (Elixaire 5X010007)..... <b>PA5320</b>	B-P Lube..... <b>B7577</b>	Cab Air (Elixaire 5X010007)..... <b>PA5320</b>
Air Dryer (Bendix 5008414)..... <b>BA5374 +</b>	Fuel/Water Separator Ele..... <b>PF7755</b>	Air Dryer (Bendix 5008414)..... <b>BA5374 +</b>
Coolant (Fleetguard WF2071)..... <b>BW5071</b>	P. Fuel (1R0749)..... <b>BF7587 +</b>	Coolant..... <b>BW5071</b>
Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	S. Fuel..... <b>BF957 +</b>	Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Radial Seal Air (Don. P534096).... <b>RS3516</b>	Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	Radial Seal XP Air (Don. DBA5106)..... <b>RS3516XP</b>	Steering (Nelson 87904M)..... <b>PT9354-MPG</b>
385 w/Cat C12 Eng.	Cab Air (Elixaire 5X010007)..... <b>PA5320</b>	385 w/Cummins ISM 10.8 (10.8L) Eng. (To 2007)
F-F Lube..... <b>B99 +</b>	Air Dryer (Bendix 5008414)..... <b>BA5374 +</b>	11 25/32 In. Dual-Flow Lube (Fleetguard LF9001)..... <b>BD7154 +</b>
B-P Lube..... <b>B7577</b>	Coolant..... <b>BW5071</b>	14 7/32 In. Dual-Flow Lube..... <b>BD7153 +</b>
Fuel/Water Separator..... <b>BF5812</b>	Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>
Fuel (1R0712)..... <b>BF614 +</b>	Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	Fuel/Water Separator Ele..... <b>PF7755</b>
Fuel (Fleetguard FF105)..... <b>BF957 +</b>	385 w/Cat 3176 (10.3L) Eng.	Fuel/Water Separator Spin-on (3329289)..... <b>BF1259</b>
Radial Seal Air (Don. EAF5106).... <b>RS3516</b>	Lube..... <b>B99 +</b>	Fuel/Water Separator Spin-on (3800394)..... <b>BF1272-SPS</b>
Radial Seal XP Air (Don. DBA5106)..... <b>RS3516XP</b>	Fuel/Water Separator (Fleetguard FS1212)..... <b>BF1212 +</b>	Radial Seal Air (Don. P534096).... <b>RS3516</b>
Cab Air (Elixaire 5X010007)..... <b>PA5320</b>	P. Fuel Ele..... <b>[2] PF935</b>	Radial Seal XP Air (Don. DBA5106)..... <b>RS3516XP</b>
Air Dryer (AD-IS, AD-SP System) (Bendix 5008414)..... <b>BA5374 +</b>	Fuel Spin-on..... <b>BF614 +</b>	Cab Air (Elixaire 5X010007)..... <b>PA5320</b>
Coolant (Fleetguard WF2071)..... <b>BW5071</b>	Radial Seal Air (Don. P534096).... <b>RS3516</b>	Air Dryer (Bendix 5008414)..... <b>BA5374 +</b>
Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	Radial Seal XP Air (Don. DBA5106)..... <b>RS3516XP</b>	Coolant (3100304)..... <b>BW5071</b>
Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	Cab Air (P93CAB4102-01S)..... <b>PA5320</b>	Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
385 w/Cat C13 (12.5L) Eng. (To 1/2004)	Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
F-F Lube..... <b>B99 +</b>	Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	Steering (Nelson 87904M)..... <b>PT9354-MPG</b>
B-P Lube..... <b>B7577</b>	385 w/Cat 3306 Eng.	385 w/Cummins ISM 10.8 (10.8L) Eng. (2007-on)
Fuel/Water Separator Ele..... <b>PF7755</b>	Lube (Standard Vers.) (1R0739).... <b>B76 +</b>	11 25/32 In. Dual-Flow Lube (Fleetguard LF9001)..... <b>BD7154 +</b>
Fuel (1R0749)..... <b>BF7587 +</b>	Lube (Severe Service) (1R0739).... <b>B76-SS +</b>	14 7/32 In. Dual-Flow Lube..... <b>BD7153 +</b>
Radial Seal Air (Don. P534096).... <b>RS3516</b>	Fuel (1R0750)..... <b>BF7633 +</b>	Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>
Radial Seal XP Air (Don. DBA5106)..... <b>RS3516XP</b>	Fuel (Fleetguard FF105)..... <b>BF957 +</b>	Fuel/Water Separator Ele..... <b>PF7755</b>
Cab Air (Elixaire 5X010007)..... <b>PA5320</b>	Radial Seal Air (Don. P534096).... <b>RS3516</b>	Fuel/Water Separator Spin-on (3329289)..... <b>BF1259</b>
Air Dryer (Bendix 5008414)..... <b>BA5374 +</b>	Radial Seal XP Air (Don. DBA5106)..... <b>RS3516XP</b>	Fuel/Water Separator Spin-on (3800394)..... <b>BF1272-SPS</b>
Coolant..... <b>BW5137</b>	Cab Air (Elixaire 5X000190)..... <b>PA5321</b>	Radial Seal Air (Don. P534096).... <b>RS3516</b>
Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	Radial Seal XP Air (Don. DBA5106)..... <b>RS3516XP</b>
Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	Cab Air (Elixaire 5X010007)..... <b>PA5320</b>
Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	Air Dryer (Bendix 5008414)..... <b>BA5374 +</b>
385 w/Cat C13 (12.5L) Eng. (1/2004-on)	385 w/Cummins 6CT8.3 (8.3L) Eng.	Breather (3683918)..... <b>CV15000</b>
F-F Lube (1R1808)..... <b>B7299 +</b>	F-F Lube (3313281)..... <b>B205 +</b>	Coolant (3100304)..... <b>BW5071</b>
B-P Lube..... <b>B7577</b>	Dual-Flow Lube (3318853)..... <b>BD103 +</b>	Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
Fuel/Water Separator Ele..... <b>PF7755</b>	Fuel/Water Separator (3903410).... <b>BF1280 +</b>	Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
Fuel (1R0749)..... <b>BF7587 +</b>	Fuel/Water Separator (3286503).... <b>BF1226</b>	Steering (Nelson 87904M)..... <b>PT9354-MPG</b>
Radial Seal Air (Don. P534096).... <b>RS3516</b>	Fuel Spin-on (3903640)..... <b>BF788</b>	
Radial Seal XP Air (Don. DBA5106)..... <b>RS3516XP</b>	385 w/Cummins ISL Eng.	
Cab Air (Elixaire 5X010007)..... <b>PA5320</b>	Dual-Flow Lube (Standard Vers.) (3318853)..... <b>BD103 +</b>	
Air Dryer (Bendix 5008414)..... <b>BA5374 +</b>	Dual-Flow Lube (High Velocity) (3401544)..... <b>BD7309 +</b>	
Coolant..... <b>BW5137</b>	Lube (Upgrade) (3401544)..... <b>B40142 +</b>	
Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	Fuel/Water Separator Ele..... <b>PF7755</b>	
Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Fuel/Water Separator Spin-on..... <b>BF1272-SPS</b>	
Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	Fuel (Fleetguard FF5488)..... <b>BF7815</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

PETERBILT Trucks (cont'd)	PETERBILT Trucks (cont'd)	PETERBILT Trucks (cont'd)
385 w/Cummins ISX 15.0 (14.9L) Eng. (To 2007)	385 w/Cummins L10 Eng. (Cont'd)	386 w/Cat C15 Eng.
11 13/16 In. Dual-Flow Lube..... BD7154 +	Steering (Nelson 87904M)..... PT9354-MPG	Lube (1R1808)..... B7299 +
14 7/32 In. Dual-Flow Lube..... BD7153 +	385 w/Cummins M11 Eng.	Fuel/Water Separator
Dual-Flow Lube (Upgrade)	Dual-Flow Lube..... BD103 +	(Fleetguard FS1212)..... BF1212 +
(Fleetguard LF14000NN)..... BD50000	Fuel/Water Separator	Fuel/Water Separator
Fuel/Water Separator Ele..... PF7755	(Fleetguard FS1000)..... BF1259	(280-2700)..... BF1259
Fuel/Water Separator Spin-on..... BF1277-SP	Radial Seal Air (Don. EAF5106).. RS3516	Fuel (Eng. Mtd.) (1R0749)..... BF7587 +
Fuel..... BF7766	Radial Seal XP Air (Don.	Fuel (Frame Mtd.) (Fleetguard
Radial Seal Air (Don. P534096).. RS3516	DBA5106)..... RS3516XP	FF105)..... BF957 +
Radial Seal XP Air (Don.	Air Dryer (AD-SP System)	Radial Seal Air (Don. EAF5106).. RS3516
DBA5106)..... RS3516XP	(Bendix 5008414)..... BA5374 +	Radial Seal XP Air (Don.
Cab Air (Elixaire 5X010007)..... PA5320	Coolant..... BW5071	DBA5106)..... RS3516XP
Air Dryer (Bendix 5008414)..... BA5374 +	Opt. Trans. (Fuller 17237)..... B2 +	Cab Air (Elixaire 5X010007)..... PA5320
Coolant (w/11 1/2 units BTA+)	385 w/Cummins N14 (14.0L) Eng.	Air Dryer (AD-IP System) (Bendix
(Fleetguard WF2126)..... BW5086	Dual-Flow Lube (3318853)..... BD103 +	65624)..... BA5373
Coolant (w/o Chemical)	F-F Lube (Fleetguard LF670SC).. B196 +	Air Dryer (AD-IS, AD-SP System)
(Fleetguard WF2127)..... B5087	B-P Lube (3304232)..... B7577	(Bendix 5008414)..... BA5374 +
Trans. (2 In. Kit) (Allison	Opt. Fuel/Water Separator	Breather (2007-on) (296-8325).... CV15008
29540493)..... PT9416-MPG KIT	(3308638)..... BF1212 +	Coolant (w/4 Units BTE)
Trans. (4 In. Kit) (Allison	Fuel (154789)..... BF957-D +	(9N3368)..... BW5137
29540494)..... PT9415-MPG KIT	Coolant (w/4 Units BTA+)	Coolant (w/4 Units BTA+)
Steering (Nelson 87904M)..... PT9354-MPG	(3315116)..... BW5071	(Fleetguard WF2071)..... BW5071
385 w/Cummins ISX 15.0 (14.9L) Eng. (2007-on)	385 w/Cummins Signature 600 (15.0L) Eng.	Trans. (Fuller 4304827)..... BT223
11 13/16 In. Dual-Flow Lube..... BD7154 +	11 25/32 In. Dual-Flow Lube	Opt. Trans. (Fuller 17237)..... B2 +
14 7/32 In. Dual-Flow Lube..... BD7153 +	(Fleetguard LF9001)..... BD7154 +	Steering (Nelson 87904M)..... PT9354-MPG
Dual-Flow Lube (Upgrade)	14 7/32 In. Dual-Flow Lube	386 w/Cummins ISM 10.8 (10.8L) Eng.
(Fleetguard LF14000NN)..... BD50000	(Fleetguard LF9000)..... BD7153 +	Dual-Flow Lube (Fleetguard
Fuel/Water Separator Ele..... PF7755	Dual-Flow Lube (Upgrade)	LF9001)..... BD7154 +
Fuel/Water Separator Spin-on..... BF1277-SP	(Fleetguard LF14000NN)..... BD50000	Dual-Flow Lube (Upgrade)
Fuel..... BF7766	Fuel/Water Separator (3331096). BF1274-SP	(Fleetguard LF14000NN)..... BD50000
Radial Seal Air (Don. P534096).. RS3516	Fuel/Water Separator (4010651). BF1277-SPS	Crankcase Breather (3683918)... CV15000
Radial Seal XP Air (Don.	Coolant (Fleetguard WF2126)..... BW5086	Trans. Ele. (2 In. Kit) (Allison
DBA5106)..... RS3516XP	385 w/Detroit Series 60 Eng.	29540493)..... PT9416-MPG KIT
Cab Air (Elixaire 5X010007)..... PA5320	F-F Lube (23530573)..... [2] B495	Trans. Ele. (4 In. Kit) (Allison
Air Dryer (Bendix 5008414)..... BA5374 +	P. Fuel (23530706)..... BF5800 +	29540494)..... PT9415-MPG KIT
Breather (3683918)..... CV15000	S. Fuel (23530707)..... BF5810	Trans. Spin-on (Fuller 4304827).. BT223
Coolant (w/11 1/2 units BTA+)	386 w/Cat C13 Eng.	Opt. Trans. Spin-on (Fuller
(Fleetguard WF2126)..... BW5086	F-F Lube (1R1808)..... B7299 +	17237)..... B2 +
Coolant (w/o Chemical)	F-F Lube (249-2347)..... [2] B7402	386 w/Cummins ISX 11.9 (11.9L) Eng.
(Fleetguard WF2127)..... B5087	Fuel/Water Separator	Dual-Flow Lube (Fleetguard
Trans. (2 In. Kit) (Allison	(256-8753)..... BF1259	LF9001)..... BD7154 +
29540493)..... PT9416-MPG KIT	Fuel (1R0749)..... BF7587 +	Dual-Flow Lube (Upgrade)
Trans. (4 In. Kit) (Allison	Fuel (Frame Mounted)	(Fleetguard LF14000NN)..... BD50000
29540494)..... PT9415-MPG KIT	(Fleetguard FF105)..... BF957 +	Fuel/Water Separator Ele.
Steering (Nelson 87904M)..... PT9354-MPG	Radial Seal Air (Don. EAF5106).. RS3516	(Fleetguard FS19729)..... PF7755
385 w/Cummins L10 Eng.	Radial Seal XP Air (Don.	Fuel/Water Separator Ele.
Dual-Flow Lube (3318853)..... BD103 +	DBA5106)..... RS3516XP	(Fleetguard FS19764)..... PF9814
Fuel/Water Separator	Cab Air (Elixaire 5X010007)..... PA5320	Fuel/Water Separator Ele.
(Fleetguard FS1000)..... BF1259	Air Dryer (AD-SP System)	(K371004)..... PF9928
Radial Seal Air (Don. P534096).. RS3516	(Bendix 5008414)..... BA5374 +	Fuel (Fleetguard FF104)..... BF948 +
Radial Seal XP Air (Don.	Breather (2007-on) (296-8325).... CV15008	Fuel (Pre-2010 Emissions)
DBA5106)..... RS3516XP	Coolant (9N3368)..... BW5137	(Fleetguard FF2200)..... BF7766
Cab Air (Elixaire 5X000190)..... PA5321	Trans. (Fuller 4304827)..... BT223	Fuel (Pre-2010 Emissions)
Air Dryer (AD-9 System) (Bendix	Opt. Trans. (Fuller 17237)..... B2 +	(Fleetguard FF2203)..... BF7760
107796)..... BA5377	Steering (Nelson 87904M)..... PT9354-MPG	Fuel (2010 Emissions)
Coolant (3315115)..... BW5073		(Fleetguard FF5686)..... BF9860 +
Opt. Trans. (Fuller 17237)..... B2 +		Fuel (2010 Emissions)
		(Fleetguard FF5776)..... BF9885 +

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

PETERBILT Trucks (cont'd)	PETERBILT Trucks (cont'd)	PETERBILT Trucks (cont'd)
386 w/Cummins ISX 11.9 (11.9L) Eng. (Cont'd)	386 w/Cummins ISX 15.0 (14.9L) Eng. (Cont'd)	386 w/Paccar MX-13 Eng. (Cont'd)
Fuel (Upgrade) (Fleetguard FF5825NN)..... <b>BF46129</b>	Coolant (w/o Chemicals) (3300721)..... <b>B5134 +</b>	<b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>
<b>Radial Seal Air</b> (Don. EAF5106).. <b>RS3516</b>	<b>Trans.</b> (Fuller 4304827)..... <b>BT223</b>	386 w/Westport HD GX (15.0L) Eng.
<b>Radial Seal XP Air</b> (Don. DBA5106)..... <b>RS3516XP</b>	<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	<b>Dual-Flow Lube</b> (Fleetguard LF9080)..... <b>BD7154 +</b>
<b>Cab Air</b> (8 1/8 In. Length) (Elixaire 5X010007)..... <b>PA5320</b>	<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>
<b>Cab Air</b> (10 1/32 In. Length) (5X014010)..... <b>PA30140</b>	<b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>	<b>Fuel/Water Separator</b> (Fleetguard NG5900)..... <b>BF7695</b>
<b>Cab Air</b> (9 3/32 In. Length) (5S013817)..... <b>PA5765</b>	386 w/Cummins ISX-G Eng.	<b>Radial Seal Air</b> (Don. EAF5106).. <b>RS3516</b>
<b>Air Dryer</b> (AD-IS, AD-SP System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154 +</b>	<b>Radial Seal XP Air</b> (Don. DBA5106)..... <b>RS3516XP</b>
<b>Breather</b> (Fleetguard CV50634)... <b>CV15000</b>	<b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>
<b>Coolant</b> (Ext. Life Coolant) (Fleetguard WF2127)..... <b>B5087</b>	<b>Fuel</b> (Fleetguard NG5900)..... <b>BF7695</b>	<b>Coolant</b> (w/o Chemical) (Fleetguard WF2127)..... <b>B5087</b>
<b>Coolant</b> (w/o Chemicals) (3300721)..... <b>B5134 +</b>	<b>Radial Seal XP Air</b> (Don. DBA5106)..... <b>RS3516XP</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>
<b>Trans.</b> (Fuller 4304827)..... <b>BT223</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	387 w/Cat 3126 (7.2L) Eng.
<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	<b>Breather</b> (3683918)..... <b>CV15000</b>	<b>Lube</b> (Standard Vers.) (1R0739).. <b>B76 +</b>
<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>Coolant</b> (Fleetguard WF2127)..... <b>B5087</b>	<b>Lube</b> (Severe Service) (1R0739).. <b>B76-SS +</b>
<b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>	<b>Trans.</b> (Fuller 4304827)..... <b>BT223</b>	<b>Fuel/Water Separator</b> (1752949).. <b>BF1268</b>
386 w/Cummins ISX 15.0 (14.9L) Eng.	386 w/Paccar MX Eng.	<b>Fuel/Water Separator</b> (2568753).. <b>BF1259</b>
<b>Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154 +</b>	<b>Lube Ele.</b> (1629393)..... <b>P40019</b>	<b>Fuel/Water Separator</b> (w/Sensor Port) (1986378)..... <b>BF7798-SP</b>
<b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>	<b>Lube Spinner</b> (1643072)..... <b>BC7326 +</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (1986378)..... <b>BF7798-O</b>
<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19729)..... <b>PF7755</b>	<b>Fuel/Water Separator</b> (Fleetguard FS19624)..... <b>PF7748</b>	<b>Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b>
<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19764)..... <b>PF9814</b>	<b>Fuel/Water Separator</b> (Fleetguard FS19765)..... <b>PF7930</b>	<b>Fuel Spin-on</b> (1R0751)..... <b>BF7632</b>
<b>Fuel/Water Separator Ele.</b> (K371004)..... <b>PF9928</b>	<b>Fuel/Water Separator</b> (K37-1005)..... <b>PF9928</b>	387 w/Cat 3406 (14.6L) Eng.
<b>Fuel</b> (Fleetguard FF104)..... <b>BF948 +</b>	<b>Fuel</b> (1655115)..... <b>BF9927</b>	<b>F-F Lube</b> (1R0716)..... <b>B99 +</b>
<b>Fuel</b> (Pre-2010 Emissions) (Fleetguard FF2200)..... <b>BF7766</b>	<b>Radial Seal Air</b> (Don. EAF5106).. <b>RS3516</b>	<b>Opt. Fuel/Water Separator</b> (175-2949)..... <b>BF1268</b>
<b>Fuel</b> (Pre-2010 Emissions) (Fleetguard FF2203)..... <b>BF7760</b>	<b>Radial Seal XP Air</b> (Don. DBA5106)..... <b>RS3516XP</b>	<b>Opt. Fuel/Water Separator</b> (Fleetguard FS1000)..... <b>BF1259</b>
<b>Fuel</b> (2010 Emissions) (Fleetguard FF5686)..... <b>BF9860 +</b>	<b>Cab Air</b> (8 1/8 In. Length) (Elixaire 5X010007)..... <b>PA5320</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1212)..... <b>BF1212 +</b>
<b>Fuel</b> (2010 Emissions) (Fleetguard FF5776)..... <b>BF9885 +</b>	<b>Cab Air</b> (10 1/32 In. Length) (5X014010)..... <b>PA30140</b>	<b>Fuel Spin-on</b> (1R0749)..... <b>BF7587 +</b>
<b>Fuel</b> (Upgrade) (Fleetguard FF5825NN)..... <b>BF46129</b>	<b>Cab Air</b> (9 3/32 In. Length) (5S013817)..... <b>PA5765</b>	<b>Fuel Spin-on</b> (Fleetguard FF105)..... <b>BF957 +</b>
<b>Radial Seal Air</b> (Don. P185106).. <b>RS3516</b>	<b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b>	<b>Axial Seal Air</b> (Don. P521598)..... <b>PA2729</b>
<b>Radial Seal XP Air</b> (Don. DBA5106)..... <b>RS3516XP</b>	<b>Coolant</b> (1843659)..... <b>B5088 +</b>	<b>23 23/32 In. Radial Seal Air</b> (Don. P534816)..... <b>RS3539</b>
<b>Cab Air</b> (8 1/8 In. Length) (Elixaire 5X010007)..... <b>PA5320</b>	<b>Trans.</b> (Fuller 4304827)..... <b>BT223</b>	<b>23 23/32 In. Radial Seal XP Air</b> (Don. P534816)..... <b>RS3539XP</b>
<b>Cab Air</b> (10 1/32 In. Length) (5X014010)..... <b>PA30140</b>	<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	<b>25 23/32 In. Radial Seal Air</b> (Don. P534925)..... <b>RS3534</b>
<b>Cab Air</b> (9 3/32 In. Length) (5S013817)..... <b>PA5765</b>	<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
<b>Air Dryer</b> (AD-IS, AD-SP System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>	<b>Air Dryer</b> (AD-SP System) (Bendix 5008414)..... <b>BA5374 +</b>
<b>Breather</b> (Fleetguard CV50634)... <b>CV15000</b>	386 w/Paccar MX-13 Eng.	<b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b>
<b>Coolant</b> (Ext. Life Coolant) (Fleetguard WF2127)..... <b>B5087</b>	<b>Lube Ele.</b> (1643070)..... <b>P40019</b>	<b>Opt. Coolant</b> (Controlled Release BTE)..... <b>BW5200</b>
	<b>Centrifugal Lube</b> (1872106)..... <b>BC7326 +</b>	<b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>
	<b>Fuel/Water Separator</b> (K371009)..... <b>PF9929</b>	<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>
	<b>Fuel</b> (1852006)..... <b>PF46106</b>	
	<b>Radial Seal Air</b> (Don. P185106).. <b>RS3516</b>	
	<b>Radial Seal XP Air</b> (Don. DBA5106)..... <b>RS3516XP</b>	
	<b>Cab Air</b> (5S013817)..... <b>PA5765</b>	
	<b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b>	
	<b>Coolant</b> (1843659)..... <b>B5088 +</b>	
	<b>Trans.</b> (Fuller 4304827)..... <b>BT223</b>	
	<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>
387 w/Cat C11 (11.1L) Eng. (To 1/2004) Lube (1R0716)..... <b>B99 +</b> Fuel/Water Separator (2568753). <b>BF1259</b> Fuel (Standard Vers.) (1R1712)... <b>BF614 +</b> Fuel (High Efficiency Vers.) (1R0749)..... <b>BF7587 +</b> Fuel (1R0762)..... <b>BF7753</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	387 w/Cat C13 (12.5L) Eng. (To 1/2004) (Cont'd) 23 7/16 In. Radial Seal XP Air (Don. DBA5106)..... <b>RS3516XP</b> Cab Air (Bergstrom 525838BSM)..... <b>PA5694</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Coolant..... <b>BW5071</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Trans. (Fuller 4304827)..... <b>BT223</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	387 w/Cat C15 (14.6L) Eng. (To 1/2004) (Cont'd) Trans. (Fuller 4304827)..... <b>BT223</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> 387 w/Cat C15 (14.6L) Eng. (1/2004-on) F-F Lube (1R1808)..... <b>B7299 +</b> B-P Lube..... <b>B7577</b> Opt. Fuel/Water Separator Ele. (Davco 382114)..... <b>PF7748</b> Fuel/Water Separator Ele..... <b>PF7755</b> Fuel/Water Separator Spin-on..... <b>BF1212 +</b> Fuel/Water Separator Spin-on (Fleetguard FS1000)..... <b>BF1259</b> P. Fuel Spin-on (1R0749)..... <b>BF7587 +</b> S. Fuel Spin-on (5 7/16 In. (Remote Mtd.))..... <b>BF957 +</b> S. Fuel Spin-on (10 1/2 In.)..... <b>BF614 +</b> 15 21/32 In. Radial Seal Air (Don. P185093)..... <b>RS3750</b> 15 21/32 In. Radial Seal XP Air (Don. P185093)..... <b>RS3750XP</b> 23 7/16 In. Radial Seal Air (Don. EAF5106)..... <b>RS3516</b> 23 7/16 In. Radial Seal XP Air (Don. DBA5106)..... <b>RS3516XP</b> Cab Air (Bergstrom 525838BSM)..... <b>PA5694</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Breather (296-8325)..... <b>CV15008</b> Coolant (Fleetguard WF2071)..... <b>BW5071</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Trans. (Fuller 4304827)..... <b>BT223</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>
387 w/Cat C11 (11.1L) Eng. (1/2004-on) Lube (1R1808)..... <b>B7299 +</b> Fuel/Water Separator (2568753). <b>BF1259</b> Fuel (Standard Vers.) (1R1712)... <b>BF614 +</b> Fuel (High Efficiency Vers.) (1R0749)..... <b>BF7587 +</b> Fuel (1R0762)..... <b>BF7753</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	387 w/Cat C13 (12.5L) Eng. (1/2004-on) Lube (1R1808)..... <b>B7299 +</b> Fuel/Water Separator Spin-on..... <b>BF1212 +</b> Fuel/Water Separator Spin-on (256-8753)..... <b>BF1259</b> Fuel Spin-on (1R0749)..... <b>BF7587 +</b> 15 21/32 In. Radial Seal Air (Don. P542101)..... <b>RS3750</b> 15 21/32 In. Radial Seal XP Air (Don. P542101)..... <b>RS3750XP</b> 23 7/16 In. Radial Seal Air (Don. EAF5106)..... <b>RS3516</b> 23 7/16 In. Radial Seal XP Air (Don. DBA5106)..... <b>RS3516XP</b> Cab Air (Bergstrom 525838BSM)..... <b>PA5694</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Breather (296-8325)..... <b>CV15008</b> Coolant..... <b>BW5071</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Trans. (Fuller 4304827)..... <b>BT223</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	387 w/Cat C15 (14.6L) Eng. (1/2004-on) F-F Lube (1R0716)..... <b>B99 +</b> B-P Lube..... <b>B7577</b> Fuel/Water Separator Ele..... <b>PF316</b> Fuel/Water Separator Spin-on..... <b>BF1212 +</b> Fuel (High Efficiency) (1R0749).... <b>BF7587 +</b> Fuel..... <b>BF614 +</b> Radial Seal Air (Don. P542101)... <b>RS3750</b> Radial Seal XP Air (Don. P542101)..... <b>RS3750XP</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Coolant..... <b>BW5071</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>
387 w/Cat C12 (12.0L) Eng. (1/2004-on) F-F Lube (1R1808)..... <b>B7299 +</b> B-P Lube..... <b>B7577</b> Fuel/Water Separator Ele..... <b>PF316</b> Fuel/Water Separator Spin-on..... <b>BF1212 +</b> Fuel (High Efficiency) (1R0749).... <b>BF7587 +</b> Fuel..... <b>BF614 +</b> Radial Seal Air (Don. P542101)... <b>RS3750</b> Radial Seal XP Air (Don. P542101)..... <b>RS3750XP</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Coolant..... <b>BW5071</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	387 w/Cat C15 (14.6L) Eng. (To 1/2004) F-F Lube (1R0716)..... <b>B99 +</b> B-P Lube..... <b>B7577</b> Opt. Fuel/Water Separator Ele. (Davco 382114)..... <b>PF7748</b> Fuel/Water Separator Ele..... <b>PF7755</b> Fuel/Water Separator Spin-on..... <b>BF1212 +</b> Fuel/Water Separator Spin-on (Fleetguard FS1000)..... <b>BF1259</b> P. Fuel Spin-on (1R0749)..... <b>BF7587 +</b> S. Fuel Spin-on (5 7/16 In. (Remote Mtd.))..... <b>BF957 +</b> S. Fuel Spin-on (10 1/2 In.)..... <b>BF614 +</b> 15 21/32 In. Radial Seal Air (Don. P185093)..... <b>RS3750</b> 15 21/32 In. Radial Seal XP Air (Don. P185093)..... <b>RS3750XP</b> 23 7/16 In. Radial Seal Air (Don. EAF5106)..... <b>RS3516</b> 23 7/16 In. Radial Seal XP Air (Don. DBA5106)..... <b>RS3516XP</b> Cab Air (Bergstrom 525838BSM)..... <b>PA5694</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Coolant (Fleetguard WF2071)..... <b>BW5071</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	387 w/Cat C16 (15.8L) Eng. (To 1/2004) Lube (1R0716)..... <b>B99 +</b> Fuel/Water Separator (Open End for Bowl) (1335673)..... <b>BF1395-O</b> Fuel/Water Separator (w/Drain) (1335673)..... <b>BF1265</b> Fuel/Water Separator (w/Sensor Port) (1335673)..... <b>BF1395-SP</b> Fuel/Water Separator (2568753). <b>BF1259</b> Fuel Ele. (9M2342)..... <b>[2] PF935</b> Fuel Spin-on (Standard Vers.) (1R1712)..... <b>BF614 +</b> Fuel Spin-on (High Efficiency Vers.) (1R0749)..... <b>BF7587 +</b> Radial Seal Air (15 21/32 In.) (Don. P542101)..... <b>RS3750</b> Radial Seal XP Air (15 21/32 In.) (Don. P542101)..... <b>RS3750XP</b> Radial Seal Air (23 7/16 In.) (Don. P531026)..... <b>RS3516</b> Radial Seal XP Air (23 7/16 In.) (Don. DBA5106)..... <b>RS3516XP</b> Cab Air (Bergstrom 525838BSM)..... <b>PA5694</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
387 w/Cat C12 (12.0L) Eng. (1/2004-on) F-F Lube (1R1808)..... <b>B7299 +</b> B-P Lube..... <b>B7577</b> Fuel/Water Separator Ele..... <b>PF316</b> Fuel/Water Separator Spin-on..... <b>BF1212 +</b> Fuel (High Efficiency) (1R0749).... <b>BF7587 +</b> Fuel..... <b>BF614 +</b> Radial Seal Air (Don. P542101)... <b>RS3750</b> Radial Seal XP Air (Don. P542101)..... <b>RS3750XP</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Coolant..... <b>BW5071</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	387 w/Cat C13 (12.5L) Eng. (To 1/2004) Lube (1R0716)..... <b>B99 +</b> Fuel/Water Separator Spin-on..... <b>BF1212 +</b> Fuel/Water Separator Spin-on (256-8753)..... <b>BF1259</b> Fuel Spin-on (1R0749)..... <b>BF7587 +</b> Std. Air (Don. P542101)..... <b>RS3750</b> XP Air (Don. P542101)..... <b>RS3750XP</b> 23 7/16 In. Radial Seal Air (Don. EAF5106)..... <b>RS3516</b>	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).




<b>PETERBILT Trucks (cont'd)</b>	
387 w/Cat C16 (15.8L) Eng. (To 1/2004) (Cont'd)	
Trans. Ele. (4 In. Kit) (Allison 29540494).....	PT9415-MPG KIT
Trans. Spin-on (Fuller 4304827)..	BT223
Opt. Trans. Spin-on (Fuller 17237).....	B2 +
Steering (Nelson 87904M).....	PT9354-MPG
387 w/Cat C16 (15.8L) Eng. (1/2004-on)	
Lube (1R1808).....	B7299 +
Fuel/Water Separator (Open End for Bowl) (1335673).....	BF1395-O
Fuel/Water Separator (w/Drain) (1335673).....	BF1265
Fuel/Water Separator (w/Sensor Port) (1335673).....	BF1395-SP
Fuel/Water Separator (2568753).....	BF1259
Fuel Ele. (9M2342).....	[2] PF935
Fuel Spin-on (Standard Vers.) (1R1712).....	BF614 +
Fuel Spin-on (High Efficiency Vers.) (1R0749).....	BF7587 +
Radial Seal Air (15 21/32 In.) (Don. P542101).....	RS3750
Radial Seal XP Air (15 21/32 In.) (Don. P542101).....	RS3750XP
Radial Seal Air (23 7/16 In.) (Don. P531026).....	RS3516
Radial Seal XP Air (23 7/16 In.) (Don. DBA5106).....	RS3516XP
Cab Air (Bergstrom 525838BSM).....	PA5694
Trans. Ele. (2 In. Kit) (Allison 29540493).....	PT9416-MPG KIT
Trans. Ele. (4 In. Kit) (Allison 29540494).....	PT9415-MPG KIT
Trans. Spin-on (Fuller 4304827)..	BT223
Opt. Trans. Spin-on (Fuller 17237).....	B2 +
Steering (Nelson 87904M).....	PT9354-MPG
387 w/Cummins 6BT5.9 (5.9L) Eng.	
Lube (Chrysler 5083285AA).....	BT7349
Fuel/Water Separator (4741689).....	BF1223 +
Fuel/Water Separator (3903202).....	BF1226
387 w/Cummins ISM 10.8 (10.8L) Eng. (To 2007)	
Dual-Flow Lube.....	BD7153 +
Fuel/Water Separator Ele.....	PF7755
Fuel/Water Separator Spin-on.....	BF1272-SPS
Radial Seal Air.....	RS3750
Radial Seal XP Air.....	RS3750XP
Cab Air (Bergstrom 525838BSM).....	PA5694
Air Dryer (Bendix 5008414).....	BA5374 +
Coolant.....	BW5071
Opt. Trans. (Fuller 17237).....	B2 +
Steering (Nelson 87904M).....	PT9354-MPG

<b>PETERBILT Trucks (cont'd)</b>	
387 w/Cummins ISM 10.8 (10.8L) Eng. (2007-on)	
Dual-Flow Lube.....	BD7153 +
Fuel/Water Separator Ele.....	PF7755
Fuel/Water Separator Spin-on.....	BF1272-SPS
Radial Seal Air.....	RS3750
Radial Seal XP Air.....	RS3750XP
Cab Air (Bergstrom 525838BSM).....	PA5694
Air Dryer (Bendix 5008414).....	BA5374 +
Breather (3683918).....	CV15000
Coolant.....	BW5071
Opt. Trans. (Fuller 17237).....	B2 +
Steering (Nelson 87904M).....	PT9354-MPG
387 w/Cummins ISX 15.0 (14.9L) Eng. (To 2007)	
11 13/16 In. Dual-Flow Lube (Fleetguard LF9031).....	BD7509 +
11 13/16 In. Dual-Flow Lube (Fleetguard LF9080).....	BD7154 +
14 7/32 In. Dual-Flow Lube.....	BD7153 +
Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN).....	BD50000
Fuel/Water Separator Ele. (Fleetguard FS19729).....	PF7755
Fuel/Water Separator Spin-on.....	BF1277-SP
Fuel (Fleetguard FF104).....	BF948 +
Fuel (Fleetguard FF2203).....	BF7760
Fuel (Fleetguard FF2200).....	BF7766
15 21/32 In. Radial Seal Air (Don. P542101).....	RS3750
15 21/32 In. Radial Seal XP Air (Don. P542101).....	RS3750XP
23 7/16 In. Radial Seal Air (Don. EAF5106).....	RS3516
23 7/16 In. Radial Seal XP Air (Don. DBA5106).....	RS3516XP
Cab Air (Bergstrom 525838BSM).....	PA5694
Air Dryer (AD-IS System) (Bendix 5008414).....	BA5374 +
Coolant (w/11 1/2 units BTA+) (Fleetguard WF2126).....	BW5086
Coolant (w/o Chemical) (Fleetguard WF2127).....	B5087
Trans. (Fuller 4304827).....	BT223
Opt. Trans. (Fuller 17237).....	B2 +
Steering (Nelson 87904M).....	PT9354-MPG
Diesel Exhaust Fluid (2880298)..	PE17000
387 w/Cummins ISX 15.0 (14.9L) Eng. (2007-on)	
11 13/16 In. Dual-Flow Lube (Fleetguard LF9031).....	BD7509 +
11 13/16 In. Dual-Flow Lube (Fleetguard LF9080).....	BD7154 +
14 7/32 In. Dual-Flow Lube.....	BD7153 +
Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN).....	BD50000

<b>PETERBILT Trucks (cont'd)</b>	
387 w/Cummins ISX 15.0 (14.9L) Eng. (2007-on) (Cont'd)	
Fuel/Water Separator Ele. (Fleetguard FS19729).....	PF7755
Fuel/Water Separator Spin-on.....	BF1277-SP
Fuel (Fleetguard FF104).....	BF948 +
Fuel (Fleetguard FF2203).....	BF7760
Fuel (Fleetguard FF2200).....	BF7766
15 21/32 In. Radial Seal Air (Don. P542101).....	RS3750
15 21/32 In. Radial Seal XP Air (Don. P542101).....	RS3750XP
23 7/16 In. Radial Seal Air (Don. EAF5106).....	RS3516
23 7/16 In. Radial Seal XP Air (Don. DBA5106).....	RS3516XP
Cab Air (Bergstrom 525838BSM).....	PA5694
Air Dryer (AD-IS System) (Bendix 5008414).....	BA5374 +
Breather (3683918).....	CV15000
Coolant (w/11 1/2 units BTA+) (Fleetguard WF2126).....	BW5086
Coolant (w/o Chemical) (Fleetguard WF2127).....	B5087
Trans. (Fuller 4304827).....	BT223
Opt. Trans. (Fuller 17237).....	B2 +
Steering (Nelson 87904M).....	PT9354-MPG
Diesel Exhaust Fluid (2880298)..	PE17000
387 w/Cummins M11 (10.8L) Eng. (To 12/1995)	
Dual-Flow Lube (3318853).....	BD103 +
Fuel/Water Separator Ele. (Fleetguard FS1029W).....	PF7680
Fuel/Water Separator Spin-on (3308638).....	BF1212 +
387 w/Cummins M11 (10.8L) Eng. (12/1995-on)	
Dual-Flow Lube (3318853).....	BD103 +
Fuel/Water Separator Ele. (Fleetguard FS1029W).....	PF7680
Fuel/Water Separator Spin-on (3329289).....	BF1259
387 w/Cummins N14 (14.0L) Eng.	
Dual-Flow Lube (3318853).....	BD103 +
F-F Lube (Fleetguard LF670SC)..	B196 +
B-P Lube (3304232).....	B7577
Opt. Fuel/Water Separator (3308638).....	BF1212 +
Fuel (154789).....	BF957-D +
Coolant (w/4 Units BTA+) (3315116).....	BW5071
Trans. Ele. (2 In. Kit) (Allison 29540493).....	PT9416-MPG KIT
Trans. Ele. (4 In. Kit) (Allison 29540494).....	PT9415-MPG KIT
Trans. Spin-on (Fuller 4304827)..	BT223
Opt. Trans. Spin-on (Fuller 17237).....	B2 +

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>
387 w/Detroit Diesel 6-71 (7.0L) Eng. Lube (23530407)..... <b>B95+</b> Lube (Upgrade) (23530408)..... <b>B95-MPG+</b> P. Fuel (23530706)..... <b>BF5800+</b> S. Fuel (23530707)..... <b>BF5810</b> S. Fuel (23530645)..... <b>BF5815</b>	388 w/Cat C15 Eng. (Cont'd) Air Dryer (AD-SP System) (Bendix 5008414)..... <b>BA5374+</b> Breather (2007 Emissions) (296-8325)..... <b>CV15008</b> Coolant (Fleetguard WF2071)..... <b>BW5071</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2+</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	388 w/Cummins ISX 11.9 (11.9L) Eng. (Cont'd) 23 23/32 In. Radial Seal XP Air (Don. EAF5100)..... <b>[2] RS3539XP</b> 24 13/16 In. Std. Radial Seal Air (P614556)..... <b>[2] RS5287</b> 24 13/16 In. Radial Seal XP Air (P614556)..... <b>[2] RS5287XP</b> 25 23/32 In. Radial Seal Air (Don. P534925)..... <b>[2] RS3534</b> Cab Air (11 1/8 In. Length) (Elixaire 5X000190)..... <b>PA5321</b> Cab Air (Elixaire 5S014010)..... <b>PA30140</b> Cab Air (13 11/32 In. Length) (5S013817)..... <b>PA5765</b> Air Dryer (AD-IS System) (Bendix 5008414)..... <b>BA5374+</b> Air Dryer (AD-IP System) (Bendix 65624)..... <b>BA5373</b> Breather (Fleetguard CV50634)..... <b>CV15000</b> Coolant (Fleetguard WF2127)..... <b>B5087</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2+</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Diesel Exhaust Fluid (2010 Emissions) (2888182)..... <b>PE17000</b>
387 w/Paccar MX Eng. Lube (1643070)..... <b>P40019</b> Lube Spinner (1643072)..... <b>BC7326+</b> Fuel/Water Separator (K371005)..... <b>PF9928</b> Fuel (1655115)..... <b>BF9927</b> Cab Air (Bergstrom 525838BBSM)..... <b>PA5694</b> Air Dryer (Bendix 5008414)..... <b>BA5374+</b> Coolant (Long Version) (1649751)..... <b>B5090</b> Coolant (Short Version) (1649751)..... <b>B5088</b> Opt. Trans. (Fuller 17237)..... <b>B2+</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	388 w/Cummins ISM Eng. Dual-Flow Lube (Fleetguard LF9001)..... <b>BD7154+</b> Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> Fuel/Water Separator (Fleetguard FS1000)..... <b>BF1259</b> 23 23/32 In. Radial Seal Air (Don. P534816)..... <b>[2] RS3539</b> 23 23/32 In. Radial Seal XP Air (Don. P534816)..... <b>[2] RS3539XP</b> 25 23/32 In. Radial Seal Air (Don. P534925)..... <b>[2] RS3534</b> Cab Air (Elixaire 5X000190)..... <b>PA5321</b> Air Dryer (Bendix 5008414)..... <b>BA5374+</b> Breather (3683918)..... <b>CV15000</b> Coolant (w/o Chemical) (4920476)..... <b>B5090</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2+</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	388 w/Cummins ISX 15.0 (15.0L) Eng. Dual-Flow Lube (Fleetguard LF9080)..... <b>BD7154+</b> Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> Fuel/Water Separator (Fleetguard FS19729)..... <b>PF7755</b> Fuel/Water Separator (Fleetguard FS19765)..... <b>PF7930</b> Fuel/Water Separator (Fleetguard FS19764)..... <b>PF9814</b> Fuel/Water Separator (K371004)..... <b>PF9928</b> Fuel (Pre-2010 Emissions) (Fleetguard FF2203)..... <b>BF7760</b> Fuel (Pre-2010 Emissions) (Fleetguard FF2200)..... <b>BF7766</b> Fuel (2010 Emissions) (Fleetguard FF5776)..... <b>BF9885+</b> Fuel (2010 Emissions) (Fleetguard FF5686)..... <b>BF9860+</b> Fuel (Upgrade) (Fleetguard FF5825NN)..... <b>BF46129</b> 22 29/32 In. Std. Radial Seal Air (P614986)..... <b>[2] RS5288</b> 22 29/32 In. Radial Seal XP Air (Paccar P614986)..... <b>[2] RS5288XP</b> 23 23/32 In. Radial Seal Air (Don. P534816)..... <b>[2] RS3539</b> 23 23/32 In. Radial Seal XP Air (Don. EAF5100)..... <b>[2] RS3539XP</b> 24 13/16 In. Std. Radial Seal Air (P614556)..... <b>[2] RS5287</b> 24 13/16 In. Radial Seal XP Air (P614556)..... <b>[2] RS5287XP</b>
388 w/Cat C13 Eng. Lube (1R1808)..... <b>B7299+</b> Lube (249-2347)..... <b>[2] B7402</b> Fuel/Water Separator (256-8753)..... <b>BF1259</b> Fuel (1R0749)..... <b>BF7587+</b> Fuel (Fleetguard FF105)..... <b>BF957+</b> 23 23/32 In. Radial Seal Air (Don. P534816)..... <b>[2] RS3539</b> 23 23/32 In. Radial Seal XP Air (Don. P534816)..... <b>[2] RS3539XP</b> 25 23/32 In. Radial Seal Air (Don. P534925)..... <b>[2] RS3534</b> Cab Air (Elixaire 5X000190)..... <b>PA5321</b> Air Dryer (Bendix 5008414)..... <b>BA5374+</b> Breather (2007-on) (296-8325)..... <b>CV15008</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2+</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	388 w/Cummins ISX 11.9 (11.9L) Eng. Dual-Flow Lube (Fleetguard LF9080)..... <b>BD7154+</b> Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> Fuel/Water Separator (Fleetguard FS19729)..... <b>PF7755</b> Fuel/Water Separator (Fleetguard FS19765)..... <b>PF7930</b> Fuel/Water Separator (Fleetguard FS19764)..... <b>PF9814</b> Fuel/Water Separator (K371004)..... <b>PF9928</b> Fuel (Pre-2010 Emissions) (Fleetguard FF2203)..... <b>BF7760</b> Fuel (Pre-2010 Emissions) (Fleetguard FF2200)..... <b>BF7766</b> Fuel (2010 Emissions) (Fleetguard FF5776)..... <b>BF9885+</b> Fuel (2010 Emissions) (Fleetguard FF5686)..... <b>BF9860+</b> Fuel (Upgrade) (Fleetguard FF5825NN)..... <b>BF46129</b> 22 29/32 In. Std. Radial Seal Air (P614986)..... <b>[2] RS5288</b> 22 29/32 In. Radial Seal XP Air (Paccar P614986)..... <b>[2] RS5288XP</b> 23 23/32 In. Radial Seal Air (Don. P534816)..... <b>[2] RS3539</b> 23 23/32 In. Radial Seal XP Air (Don. EAF5100)..... <b>[2] RS3539XP</b> 24 13/16 In. Std. Radial Seal Air (P614556)..... <b>[2] RS5287</b> 24 13/16 In. Radial Seal XP Air (P614556)..... <b>[2] RS5287XP</b>	388 w/Cat C15 Eng. F-F Lube (1R-1808)..... <b>B7299+</b> B-P Lube (9Y4468)..... <b>B7577</b> Fuel/Water Separator Ele. (Fleetguard FS19624)..... <b>PF7748</b> Fuel/Water Separator Spin-on (280-2700)..... <b>BF1259</b> Fuel/Water Separator Spin-on (Don. P558000)..... <b>BF1212+</b> Fuel (1R0749)..... <b>BF7587+</b> 23 23/32 In. Radial Seal Air (Don. P534816)..... <b>[2] RS3539</b> 23 23/32 In. Radial Seal XP Air (Don. P534816)..... <b>[2] RS3539XP</b> 25 23/32 In. Radial Seal Air (Don. P534925)..... <b>[2] RS3534</b> Cab Air (Elixaire 5X000190)..... <b>PA5321</b> Air Dryer (AD-IP System) (Bendix 65624)..... <b>BA5373</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

PETERBILT Trucks (cont'd)	PETERBILT Trucks (cont'd)	PETERBILT Trucks (cont'd)
388 w/Cummins ISX 15.0 (15.0L) Eng. (Cont'd) <b>25 23/32 In. Radial Seal Air</b> (Don. P534925)..... [2] <b>RS3534</b> <b>Cab Air</b> (11 1/8 In. Length) (Elixaire 5X000190)..... <b>PA5321</b> <b>Cab Air</b> (Elixaire 5S014010)..... <b>PA30140</b> <b>Cab Air</b> (13 11/32 In. Length) (5S013817)..... <b>PA5765</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b> <b>Breather</b> (Fleetguard CV50634).... <b>CV15000</b> <b>Coolant</b> (Fleetguard WF2127)..... <b>B5087</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Diesel Exhaust Fluid</b> (2010 Emissions) (2888182)..... <b>PE17000</b>	388 w/Westport GX (15.0L) Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9080)..... <b>BD7154 +</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (Fleetguard NG5900)..... <b>BF7695</b> <b>Fuel</b> (Fleetguard FF5686)..... <b>BF9860 +</b> <b>Coolant</b> (w/o Chemical) (Fleetguard WF2127)..... <b>B5087</b> <b>Coolant</b> (w/11 1/2 Units BTA+) (Fleetguard WF2126)..... <b>BW5086</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	389 w/Cummins ISX 11.9 (11.9L) Eng. (2015-18) (Cont'd) <b>11 9/16 In. Fuel</b> (2010 Emissions) (Fleetguard FF5686)... <b>BF9860 +</b> <b>8 27/32 In. Fuel</b> (Upgrade) (Fleetguard FF5825NN)..... <b>BF46129</b> <b>Std. Radial Seal Air</b> (P614986).... [2] <b>RS5288</b> <b>Radial Seal XP Air</b> (P614986).... [2] <b>RS5288XP</b> <b>24 13/16 In. Std. Radial Seal Air</b> (P614556)..... [2] <b>RS5287</b> <b>24 13/16 In. Radial Seal XP Air</b> (P614556)..... [2] <b>RS5287XP</b> <b>25 13/16 In. Radial Seal Air</b> (Don. P534925)..... [2] <b>RS3534</b> <b>Cab Air</b> (10 13/16 In. Length) (Elixaire 5X010007)..... <b>PA5320</b> <b>Cab Air</b> (13 11/32 In.) (Elixaire 5S013817)..... <b>PA5765</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Air Dryer</b> (Bendix 5008414PG).... <b>BA5379</b> <b>Breather</b> (4312013)..... <b>CV15000</b> <b>Coolant</b> (Fleetguard WF2127)..... <b>B5087</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>
388 w/Detroit Diesel Series 60 (12.7L) Eng. <b>Lube</b> (23518480)..... [2] <b>B495</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23533726)..... <b>BF5816</b> <b>S. Fuel</b> (23530645)..... <b>BF5815</b> <b>Coolant</b> (23516489)..... <b>BW5200</b>	389 w/Cat C15 Eng. <b>Lube</b> (1R1808)..... <b>B7299 +</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19727)..... <b>PF7895</b> <b>Fuel/Water Separator Spin-on</b> (2568753)..... <b>BF1259</b> <b>Fuel</b> (1R0749)..... <b>BF7587 +</b> <b>Radial Seal Air</b> (Don. P534925).... [2] <b>RS3534</b> <b>Cab Air</b> (Elixaire 5X010007)..... <b>PA5320</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Breather</b> (2007-on) (296-8325).... <b>CV15008</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	389 w/Cummins ISX 11.9 (11.9L) Eng. (2019) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (K371029) <b>PF46081</b> <b>Fuel</b> (2893612)..... <b>BF9885 +</b> <b>Std. Radial Seal Air</b> (X011622).... [2] <b>RS5287</b> <b>Radial Seal XP Air</b> (X011622).... [2] <b>RS5287XP +</b> <b>Cab Air</b> (5S013817)..... <b>PA5765</b> <b>Air Dryer</b> (TRP AC1001)..... <b>BA5374 +</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>
388 w/Paccar MX Eng. <b>F-F Lube Ele.</b> (1643070)..... <b>P40019</b> <b>Lube Spinner</b> (1643072)..... <b>BC7326 +</b> <b>Fuel/Water Separator</b> (K37-1005)..... <b>PF9928</b> <b>Fuel</b> (1655115)..... <b>BF9927</b> <b>Std. Radial Seal Air</b> (P614986).... [2] <b>RS5288</b> <b>Radial Seal XP Air</b> (Paccar P614986)..... [2] <b>RS5288XP</b> <b>Cab Air</b> (5S014010)..... <b>PA30140</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Coolant</b> (1843659)..... <b>B5088 +</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Diesel Exhaust Fluid</b> (2888182).. <b>PE17000</b>	389 w/Cat C16 Eng. <b>Lube</b> (1R1808)..... <b>B7299 +</b> <b>Fuel/Water Separator</b> (280-2700)..... <b>BF1259</b> <b>Fuel</b> (1R0749)..... <b>BF7587 +</b> <b>Radial Seal Air</b> (Don. P534925).... [2] <b>RS3534</b> <b>Cab Air</b> (Elixaire 5X010007)..... <b>PA5320</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b>	389 w/Cummins ISX 11.9 (11.9L) Eng. (2020) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (K371029) <b>PF46081</b> <b>Fuel</b> (2893612)..... <b>BF9885</b> <b>Radial Seal Air</b> (P614986)..... [2] <b>RS5288</b> <b>Radial Seal XP Air</b> (P614986).... [2] <b>RS5288XP</b> <b>Cab Air</b> (5S013817)..... <b>PA5765</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>
388 w/Paccar MX-13 Eng. <b>Lube Ele.</b> (1643070)..... <b>P40019</b> <b>Centrifugal Lube</b> (1872106)..... <b>BC7326 +</b> <b>Fuel/Water Separator</b> (K371009) <b>PF9929</b> <b>Fuel</b> (1852006)..... <b>PF46106</b> <b>Std. Radial Seal Air</b> (P614556).... [2] <b>RS5287</b> <b>Radial Seal Air XP</b> (P614556).... [2] <b>RS5287XP</b> <b>Cab Air</b> (5S013817)..... <b>PA5765</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Coolant</b> (1843659)..... <b>B5088 +</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>	389 w/Cummins ISX 11.9 (11.9L) Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9080)..... <b>BD7154 +</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19729)..... <b>PF7755</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19764)..... <b>PF9814</b> <b>Fuel/Water Separator Ele.</b> (K371004)..... <b>PF9928</b> <b>Fuel/Water Separator Ele.</b> (K371029)..... <b>PF46081</b> <b>Fuel</b> (2007 Emissions) (Fleetguard FF2203)..... <b>BF7760</b> <b>Fuel</b> (Pre-2010 Emissions) (Fleetguard FF2200)..... <b>BF7766</b> <b>8 27/32 In. Fuel</b> (2010 Emissions) (Fleetguard FF5776).... <b>BF9885 +</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

**Trucks & Buses Applications** **BALDWIN FILTERS**

<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>
389 w/Cummins ISX 11.9 (11.9L) Eng. (2021) <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	389 w/Cummins ISX 15.0 (14.9L) / X15 (14.9L) Eng. (2018) (Cont'd) <b>Air Dryer</b> (Bendix 5008414PG).... <b>BA5379</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (4388378).. <b>PE17002 KIT</b>	389 w/Cummins ISX 15.0 (14.9L) Eng. (2023) <b>Lube</b> (5575298)..... <b>B40145</b> <b>Fuel/Water Separator</b> (Fleetguard FS19764G)..... <b>PF46091</b> <b>Fuel</b> (5575143)..... <b>BF46248</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
389 w/Cummins ISX 15.0 (14.9L) Eng. (2008-17) <b>Dual-Flow Lube</b> (Upgrade) (4367100)..... <b>BD50000</b> <b>Dual-Flow Lube</b> (Fleetguard LF9080)..... <b>BD7154 +</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19729)..... <b>PF7755</b> <b>Fuel/Water Separator Ele.</b> (K371004)..... <b>PF9928</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19764)..... <b>PF9814</b> <b>Fuel</b> (2007 Emissions) (Fleetguard FF2203)..... <b>BF7760</b> <b>Fuel</b> (Pre-2010 Emissions) (Fleetguard FF2200)..... <b>BF7766</b> <b>8 27/32 In. Fuel</b> (2010 Emissions) (Fleetguard FF5776).. <b>BF9885 +</b> <b>11 9/16 In. Fuel</b> (2010 Emissions) (Fleetguard FF5686).. <b>BF9860 +</b> <b>8 27/32 In. Fuel</b> (Upgrade) (Fleetguard FF5825NN)..... <b>BF46129</b> <b>Radial Seal XP Air</b> (X011623).... <b>[2] RS30187XP</b> <b>Std. Radial Seal Air</b> (P614556).... <b>[2] RS5287</b> <b>Radial Seal XP Air</b> (P614556).... <b>[2] RS5287XP</b> <b>Radial Seal Air</b> (Don. P534925).... <b>[2] RS3534</b> <b>Cab Air</b> (10 13/16 In. Length) (Elixaire 5X010007)..... <b>PA5320</b> <b>Cab Air</b> (13 11/32 In.) (Elixaire 5S013817)..... <b>PA5765</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Air Dryer</b> (TRP AC1001)..... <b>BA5374 +</b> <b>Breather</b> (4312013)..... <b>CV15000</b> <b>Coolant</b> (Fleetguard WF2127)..... <b>B5087</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>	389 w/Cummins ISX 15.0 (14.9L) Eng. (2019) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (Fleetguard FS19764G)..... <b>PF46091</b> <b>Fuel</b> (5365988)..... <b>BF46129 +</b> <b>Std. Radial Seal Air</b> (X011622).... <b>[2] RS5287</b> <b>Radial Seal XP Air</b> (X011622).... <b>[2] RS5287XP +</b> <b>Cab Air</b> (5S013817)..... <b>PA5765</b> <b>Air Dryer</b> (TRP AC1001)..... <b>BA5374 +</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	389 w/Cummins X15 (14.9L) Eng. (2019) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (Fleetguard FS19764G)..... <b>PF46091</b> <b>Fuel</b> (5365988)..... <b>BF46129</b> <b>Std. Radial Seal Air</b> (X011622).... <b>[2] RS5287</b> <b>Radial Seal XP Air</b> (X011622).... <b>[2] RS5287XP</b> <b>Cab Air</b> (5S013817)..... <b>PA5765</b> <b>Air Dryer</b> (TRP AC1001)..... <b>BA5374 +</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
389 w/Cummins ISX 15.0 (14.9L) / X15 (14.9L) Eng. (2018)	389 w/Cummins ISX 15.0 (14.9L) Eng. (2020) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (Fleetguard FS19764G)..... <b>PF46091</b> <b>Fuel/Water Separator</b> (K371011) <b>PF46081</b> <b>Fuel</b> (5365988)..... <b>BF46129</b> <b>Radial Seal Air</b> (P614986)..... <b>[2] RS5288</b> <b>Radial Seal XP Air</b> (P614986).... <b>[2] RS5288XP</b> <b>Cab Air</b> (5S013817)..... <b>PA5765</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	389 w/Cummins X15 (14.9L) Eng. (2020) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (Fleetguard FS19764G)..... <b>PF46091</b> <b>Fuel/Water Separator</b> (K371011) <b>PF46081</b> <b>Fuel</b> (5365988)..... <b>BF46129</b> <b>Radial Seal Air</b> (P614986)..... <b>[2] RS5288</b> <b>Radial Seal XP Air</b> (P614986).... <b>[2] RS5288XP</b> <b>Cab Air</b> (5S013817)..... <b>PA5765</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
389 w/Cummins ISX 15.0 (14.9L) / X15 (14.9L) Eng. (2018)	389 w/Cummins ISX 15.0 (14.9L) Eng. (2021) <b>Lube</b> (5575298)..... <b>B40145</b> <b>Fuel/Water Separator</b> (Fleetguard FS19764G)..... <b>PF46091</b> <b>Fuel</b> (5365988)..... <b>BF46129</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	389 w/Detroit Diesel Series 60 (12.7L) Eng. <b>Lube</b> (23518480)..... <b>[2] B495</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23533726)..... <b>BF5816</b> <b>S. Fuel</b> (23530645)..... <b>BF5815</b> <b>Air</b> (Don. P150695)..... <b>PA2680</b> <b>Air</b> (Don. P522293)..... <b>PA2732</b> <b>Coolant</b> (23516489)..... <b>BW5200</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>
389 w/Cummins ISX 15.0 (14.9L) / X15 (14.9L) Eng. (2018)	389 w/Cummins ISX 15.0 (14.9L) Eng. (2022) <b>Lube</b> (5575298)..... <b>B40145</b> <b>Fuel/Water Separator</b> (Fleetguard FS19764G)..... <b>PF46091</b> <b>Fuel</b> (5575143)..... <b>BF46248</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	389 w/Paccar MX Eng. <b>Lube</b> (1643070)..... <b>P40019</b> <b>Lube Spinner</b> (1643072)..... <b>BC7326 +</b> <b>Fuel/Water Separator</b> (K37-1005)..... <b>PF9928</b> <b>Fuel</b> (1655115)..... <b>BF9927</b> <b>24 13/16 In. Std. Radial Seal Air</b> (P614556)..... <b>[2] RS5287</b> <b>24 13/16 In. Radial Seal XP Air</b> (P614556)..... <b>[2] RS5287XP</b> <b>25 13/16 In. Radial Seal Air</b> (Don. P534925)..... <b>[2] RS3534</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

PETERBILT Trucks (cont'd)	PETERBILT Trucks (cont'd)	PETERBILT Trucks (cont'd)
389 w/Paccar MX Eng. (Cont'd)	389 w/Paccar MX-13 (12.9L) Eng. (2020)	520 w/Cummins ISL-G (8.9L) Eng. (2018)
Cab Air (10 13/16 In. Length) (Elixaire 5X010007).....	F-F Lube (2151728PE).....	(Cont'd)
PA5320	P40069	Radial Seal XP O. Air (w/Blank Band) (Don. P777868).....
Cab Air (13 11/32 In. Length) (5S013817).....	Centrifugal Lube (1922496PE)... Fuel/Water Separator	RS3870XP +
PA5765	(Fleetguard FS19765G).....	Radial Seal I. Air (Don. P777869).....
Air Dryer (Bendix 5008414).....	PF46094	RS3871
BA5374 +	Fuel/Water Separator (K371011) Fuel (2133096PE).....	CLN&R
BA5374 +	PF46081	BA5379
B5088 +	PF46106	Coolant (w/4 Units BTA +) (Fleetguard WF2071).....
BT223	[2] RS5288	BW5071
B2 +	[2] RS5288XP	Coolant (w/12 Units BTA+) (Fleetguard WF2074).....
PT9354-MPG	PA5765	BW5074
PE17000	BA5374	Trans. Ele. (2 In. Kit) (Allison 29558117).....
389 w/Paccar MX-13 (12.9L) Eng. (2014-18)	B5088	PT9416-MPG KIT
Lube Ele. (1948921).....	BT223	Trans. Ele. (4 In. Kit) (Allison 29558118).....
P40019	PT9354-MPG	PT9415-MPG KIT
P40069	Opt. Rear Axle (Meritor 3280V8394).....	PT9386-MPG
BC40148	B233	Opt. Rear Axle (Meritor 3280V8394).....
Centrifugal Lube (1922496).....	PE17002 KIT	B233
BC40148	389 w/Paccar MX-13 (12.9L) Eng. (2021)	520 w/Cummins ISL-G (8.9L) Eng. (2019)
Fuel/Water Separator	F-F Lube (2234788PE).....	Dual-Flow Lube (Fleetguard LF9009).....
(Fleetguard FS19765G).....	P40069	BD7309
PF46094	Centrifugal Lube (1922496PE)... Fuel/Water Separator	Fuel/Water Separator
PF9929	(Fleetguard FS19765G).....	(Fleetguard NG5900).....
PF46082	PF46106	BF7695
Fuel/Water Separator (K371012) Fuel/Water Separator	PF46106	Radial Seal O. Air (w/o Blank Band) (Don. P777868).....
(Fleetguard FS19765).....	BA5374 +	RS4638
PF7930	Opt. Trans. Spin-on (Fuller 17237).....	Radial Seal O. Air (w/Blank Band) (Don. P777868).....
PF46106	B2	RS3870
[2] RS30187XP	BT223	Radial Seal XP O. Air (w/Blank Band) (Don. P777868).....
[2] RS5287	Opt. Rear Axle (Meritor 3280V8394).....	RS3870XP +
[2] RS5287XP	B233	Radial Seal I. Air (Don. P777869).....
[2] RS5288	389 w/Paccar MX-13 (12.9L) Eng. (2022)	RS3871 +
[2] RS5288XP	Trans. (Fuller 4304827).....	CLN&R
PA5765	BT223	BA5379
BA5374 +	Opt. Rear Axle (Meritor 3280V8394).....	Coolant (w/4 Units BTA +) (Fleetguard WF2071).....
BA5379	B233	BW5071
B5088 +	389 w/Paccar MX-13 (12.9L) Eng. (2023)	Coolant (w/12 Units BTA+) (Fleetguard WF2074).....
BT223	Trans. (Fuller 4304827).....	BW5074
B2 +	BT223	Trans. (2 In. Kit) (Allison 29558117).....
PT9354-MPG	Opt. Rear Axle (Meritor 3280V8394).....	PT9416-MPG KIT
PT9354-MPG	B233	Trans. (4 In. Kit) (Allison 29558118).....
B233	389 w/Paccar MX-13 (12.9L) Eng. (2019)	PT9415-MPG KIT
PE17002 KIT	F-F Lube (Std. Version) (1R0716).....	PT9386-MPG
PE17000	B99 +	Opt. Rear Axle (Meritor 3280V8394).....
389 w/Paccar MX-13 (12.9L) Eng. (2019)	F-F Lube (High Efficiency Vers.) (1R1808).....	B233
F-F Lube (2047411PE).....	B7299 +	520 w/Cummins ISL-G (8.9L) Eng. (2020)
P40069	Fuel/Water Separator Spin-on (8N0205).....	520 w/Cummins ISL-G (8.9L) Eng. (2021)
BC40148	BF1268	Lube (Fleetguard LF9009).....
PF46237	Fuel/Water Separator Spin-on (2568753).....	B40142
PF46106	BF1259	BF7695
[2] RS5287	BF7587 +	CLN&R
[2] RS5287XP	BF614 +	Opt. Rear Axle (Meritor 3280V8394).....
PA5765	520 w/Cummins ISL-G (8.9L) Eng. (2018)	B233
BA5374 +	Dual-Flow Lube (Fleetguard LF9009).....	520 w/Cummins ISL-G (8.9L) Eng. (2022)
B5088 +	BD7309	Lube (5444774).....
BT223	Fuel/Water Separator	B40142
PT9354-MPG	(Fleetguard NG5900).....	BF7695
PT9354-MPG	BF7695	Trans. (2 In. Kit) (Allison 29548987).....
B233	RS4638	PT9416-MPG KIT
PE17002 KIT	Radial Seal O. Air (w/Blank Band) (Don. P777868).....	
	RS3870	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>
520 w/Cummins ISL-G (8.9L) Eng. (2022) (Cont'd) Trans. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	520 w/Cummins ISX 11.9 (11.9L) Eng. (2020) (Cont'd) Trans. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>	520 w/Cummins ISX 11.9G (11.9L) Eng. (2020) (Cont'd) Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
520 w/Cummins ISX 11.9 (11.9L) Eng. (2017-18) <b>Dual-Flow Lube</b> (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (Fleetguard FS19764)..... <b>PF9814</b> Fuel (2893612)..... <b>BF9885 +</b> <b>Radial Seal O. Air</b> (w/o Blank Band) (Don. P777868)..... <b>RS4638</b> <b>Radial Seal O. Air</b> (w/Blank Band) (Don. P777868)..... <b>RS3870</b> <b>Radial Seal XP O. Air</b> (w/Blank Band) (Don. P777868)..... <b>RS3870XP +</b> <b>Radial Seal I. Air</b> (Don. P777869)..... <b>RS3871</b> <b>Cab Air</b> (FR11110)..... <b>CLN&amp;R</b> <b>Air Dryer</b> (Bendix 5008414PG).... <b>BA5379</b> Trans. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (Nelson 87972A)..... <b>PT9386-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>	520 w/Cummins ISX 11.9G (11.9L) Eng. (2018) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (3607140). <b>BF7695</b> <b>Radial Seal O. Air</b> (w/o Blank Band) (Don. P777868)..... <b>RS4638</b> <b>Radial Seal O. Air</b> (w/Blank Band) (Don. P777868)..... <b>RS3870</b> <b>Radial Seal XP O. Air</b> (w/Blank Band) (Don. P777868)..... <b>RS3870XP +</b> <b>Radial Seal I. Air</b> (Don. P777869)..... <b>RS3871</b> <b>Cab Air</b> (FR11110)..... <b>CLN&amp;R</b> <b>Air Dryer</b> (Bendix 5008414PG).... <b>BA5379</b> <b>Coolant</b> (3680434)..... <b>B5087</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (Nelson 87972A)..... <b>PT9386-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	520 w/Cummins ISX 11.9G (11.9L) Eng. (2021) <b>Lube</b> (5575298)..... <b>B40145</b> <b>Fuel</b> (3607140)..... <b>BF7695</b> <b>Coolant</b> (3680434)..... <b>B5087</b>
520 w/Cummins ISX 11.9 (11.9L) Eng. (2019) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (Fleetguard FS19764)..... <b>PF9814</b> Fuel (2893612)..... <b>BF9885 +</b> <b>Radial Seal O. Air</b> (w/o Blank Band) (Don. P777868)..... <b>RS4638</b> <b>Radial Seal O. Air</b> (w/Blank Band) (Don. P777868)..... <b>RS3870</b> <b>Radial Seal XP O. Air</b> (w/Blank Band) (Don. P777868)..... <b>RS3870XP +</b> <b>Radial Seal I. Air</b> (Don. P777869)..... <b>RS3871 +</b> <b>Cab Air</b> (FR11110)..... <b>CLN&amp;R</b> <b>Air Dryer</b> (Bendix 5008414PG).... <b>BA5379</b> Trans. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (Nelson 87972A)..... <b>PT9386-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>	520 w/Cummins ISX 11.9G (11.9L) Eng. (2019) <b>Dual-Flow Lube</b> (Fleetguard LF9080)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (Fleetguard NG5900)..... <b>BF7695</b> <b>Radial Seal O. Air</b> (w/o Blank Band) (Don. P777868)..... <b>RS4638</b> <b>Radial Seal O. Air</b> (w/Blank Band) (Don. P777868)..... <b>RS3870</b> <b>Radial Seal XP O. Air</b> (w/Blank Band) (Don. P777868)..... <b>RS3870XP +</b> <b>Radial Seal I. Air</b> (Don. P777869)..... <b>RS3871</b> <b>Cab Air</b> (CLN&R)..... <b>CLN&amp;R</b> <b>Air Dryer</b> (Bendix 5008414PG).... <b>BA5379</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (Nelson 87972A)..... <b>PT9386-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	520 w/Cummins L9N (8.9L) Eng. (2020) <b>Lube</b> (3401544)..... <b>B40142</b> <b>Fuel</b> (3607140)..... <b>BF7695</b> <b>Radial Seal Air</b> (Don. P777869)... <b>RS3871</b> <b>Cab Air</b> (FR11110)..... <b>CLN&amp;R</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
520 w/Cummins ISX 11.9 (11.9L) Eng. (2020) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> Fuel (2893612)..... <b>BF9885</b> <b>Radial Seal Air</b> (Don. P777869)... <b>RS3871</b> <b>Cab Air</b> (FR11110)..... <b>CLN&amp;R</b>	520 w/Cummins ISX 11.9G (11.9L) Eng. (2020) <b>Dual-Flow Lube</b> (Fleetguard LF14000NN)..... <b>BD50000</b> Fuel (Fleetguard NG5900)..... <b>BF7695</b> <b>Radial Seal Air</b> (Don. P777869)... <b>RS3871</b> <b>Cab Air</b> (FR11110)..... <b>CLN&amp;R</b>	520 w/Paccar PX-9 (8.9L) Eng. (2017-18) <b>Lube</b> (3401544)..... <b>B40142</b> <b>Fuel/Water Separator</b> (K371029) <b>PF46081</b> Fuel (5303743)..... <b>BF63000</b> <b>Radial Seal O. Air</b> (w/o Blank Band) (Don. P777868)..... <b>RS4638</b> <b>Radial Seal O. Air</b> (w/Blank Band) (Don. P777868)..... <b>RS3870</b> <b>Radial Seal XP O. Air</b> (w/Blank Band) (Don. P777868)..... <b>RS3870XP +</b> <b>Radial Seal I. Air</b> (Don. P777869)..... <b>RS3871</b> <b>Cab Air</b> (FR11110)..... <b>CLN&amp;R</b> <b>Air Dryer</b> (Bendix 5008414PG).... <b>BA5379</b> Trans. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (Nelson 87972A)..... <b>PT9386-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (4388378).. <b>PE17002 KIT</b>
520 w/Cummins ISX 11.9 (11.9L) Eng. (2020) <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel/Water Separator</b> (K371017) <b>PF46238</b> Fuel (Fleetguard FF63009)..... <b>BF63000</b> <b>Radial Seal O. Air</b> (w/o Blank Band) (Don. P777868)..... <b>RS4638</b> <b>Radial Seal O. Air</b> (w/Blank Band) (Don. P777868)..... <b>RS3870</b> <b>Radial Seal XP O. Air</b> (w/Blank Band) (Don. P777868)..... <b>RS3870XP +</b> <b>Radial Seal I. Air</b> (Don. P777869)..... <b>RS3871</b>	520 w/Paccar PX-9 (8.9L) Eng. (2019) <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel/Water Separator</b> (K371017) <b>PF46238</b> Fuel (Fleetguard FF63009)..... <b>BF63000</b> <b>Radial Seal O. Air</b> (w/o Blank Band) (Don. P777868)..... <b>RS4638</b> <b>Radial Seal O. Air</b> (w/Blank Band) (Don. P777868)..... <b>RS3870</b> <b>Radial Seal XP O. Air</b> (w/Blank Band) (Don. P777868)..... <b>RS3870XP +</b> <b>Radial Seal I. Air</b> (Don. P777869)..... <b>RS3871</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

PETERBILT Trucks (cont'd)	PETERBILT Trucks (cont'd)	PETERBILT Trucks (cont'd)
520 w/Paccar PX-9 (8.9L) Eng. (2019) (Cont'd)	520 w/Paccar MX-11 (10.8L) Eng. (2018)	520 w/Paccar MX-11 (10.8L) Eng. (2022)
<b>Cab Air</b> (FR11110)..... <b>CLN&amp;R</b>	(Cont'd)	<b>S. Fuel/Water Separator</b>
<b>Air Dryer</b> (Bendix 5008414PG).... <b>BA5379</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	(2277129)..... <b>PF7930</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	<b>Steering</b> (Nelson 87972A)..... <b>PT9386-MPG</b>	<b>Trans.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	<b>Trans.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>
<b>Steering</b> (Nelson 87972A)..... <b>PT9386-MPG</b>	<b>Diesel Exhaust Fluid</b> (4388378).. <b>PE17002 KIT</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	520 w/Paccar MX-11 (10.8L) Eng. (2019)	536 w/Cummins ISL-G (8.9L) Eng. (2022)
<b>Diesel Exhaust Fluid</b> (4388378).. <b>PE17002 KIT</b>	<b>F-F Lube</b> (2129253PE)..... <b>P40008</b>	<b>Lube</b> (5444774)..... <b>B40142</b>
520 w/Paccar PX-9 (8.9L) Eng. (2020)	<b>Centrifugal Lube</b> (1928869PE)... <b>BC40009</b>	<b>Fuel/Water Separator</b> (3607140). <b>BF7695</b>
<b>Lube</b> (3401544)..... <b>B40142</b>	<b>Fuel/Water Separator</b> (K371012) <b>PF46082</b>	536 w/Paccar PX-7 (6.7L) Eng. (2022)
<b>Fuel/Water Separator</b> (K371017) <b>PF46238</b>	<b>Fuel</b> (2133096PE)..... <b>PF46106</b>	<b>Lube</b> (3937736)..... <b>B7177</b>
<b>Fuel</b> (5303743)..... <b>BF63000</b>	<b>Radial Seal O. Air</b> (w/o Blank Band) (Don. P777868)..... <b>RS4638</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Cab Air</b> (FR11110)..... <b>CLN&amp;R</b>	<b>Radial Seal O. Air</b> (w/Blank Band) (Don. P777868)..... <b>RS3870</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	<b>Radial Seal XP O. Air</b> (w/Blank Band) (Don. P777868)..... <b>RS3870XP +</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	<b>Radial Seal I. Air</b> (Don. P777869)..... <b>RS3871</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	<b>Cab Air</b> (FR11110)..... <b>CLN&amp;R</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
520 w/Paccar PX-9 (8.9L) Eng. (2021)	<b>Air Dryer</b> (Bendix 5008414PG).... <b>BA5379</b>	537 w/Paccar PX-9 (8.9L) Eng. (2022)
<b>Lube</b> (5444774)..... <b>B40142</b>	<b>Coolant</b> (1843659PE)..... <b>B5088</b>	<b>Lube</b> (5444774)..... <b>B40142</b>
<b>Fuel</b> (5303743)..... <b>BF63000</b>	<b>Trans.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	548 w/Paccar PX-9 (8.9L) Eng. (2022)
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	<b>Trans.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	<b>Lube</b> (5444774)..... <b>B40142</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	<b>Steering</b> (Nelson 87972A)..... <b>PT9386-MPG</b>	567 w/Cummins ISL-G (8.9L) Eng. (2018)
520 w/Paccar PX-9 (8.9L) Eng. (2022)	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	<b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309</b>
<b>Lube</b> (5444774)..... <b>B40142</b>	<b>Diesel Exhaust Fluid</b> (2122909PE)..... <b>PE17002 KIT</b>	<b>Fuel/Water Separator</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	520 w/Paccar MX-11 (10.8L) Eng. (2020)	(Fleetguard NG5900)..... <b>BF7695</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	<b>Lube</b> (2129253PE)..... <b>P40008</b>	<b>EnduraCube Air</b> (Don. P621725) <b>PA32000</b>
<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	<b>Fuel/Water Separator</b> (K371012) <b>PF46082</b>	<b>Cab Air</b> (Fresh Air) (X1987001).... <b>PA30093</b>
520 w/Paccar MX-11 (10.8L) Eng. (2018)	<b>Fuel/Water Separator</b> (2164463PE)..... <b>PF46106</b>	<b>Cab Air</b> (Recirc.) (W2084001)..... <b>PA30107</b>
<b>F-F Lube</b> (1928868PE)..... <b>P40008</b>	<b>Fuel</b> (2277129PE)..... <b>PF46106</b>	<b>Air Dryer</b> (Bendix 5008414PG).... <b>BA5379</b>
<b>Centrifugal Lube</b> (1928869PE)... <b>BC40009</b>	<b>Radial Seal Air</b> (Don. P777869)... <b>RS3871</b>	<b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>
<b>Fuel/Water Separator</b> (FS1029W)..... <b>PF7680</b>	<b>Cab Air</b> (FR11110)..... <b>CLN&amp;R</b>	<b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b>
<b>Fuel/Water Separator</b> (Fleetguard FS19765)..... <b>PF7930</b>	<b>Coolant</b> (1843659PE)..... <b>B5088</b>	<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>
<b>Fuel</b> (1852006PE)..... <b>PF46106</b>	<b>Trans.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
<b>Radial Seal O. Air</b> (w/o Blank Band) (Don. P777868)..... <b>RS4638</b>	<b>Trans.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	567 w/Cummins ISL-G (8.9L) Eng. (2019)
<b>Radial Seal O. Air</b> (w/Blank Band) (Don. P777868)..... <b>RS3870</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	<b>Lube</b> (Fleetguard LF9009)..... <b>B40142</b>
<b>Radial Seal XP O. Air</b> (w/Blank Band) (Don. P777868)..... <b>RS3870XP +</b>	520 w/Paccar MX-11 (10.8L) Eng. (2021)	<b>Fuel/Water Separator</b>
<b>Radial Seal I. Air</b> (Don. P777869)..... <b>RS3871</b>	<b>Lube</b> (2129253PE)..... <b>P40008</b>	(Fleetguard NG5900)..... <b>BF7695</b>
<b>Cab Air</b> (FR11110)..... <b>CLN&amp;R</b>	<b>Fuel</b> (2277129PE)..... <b>PF46106</b>	<b>Air</b> (P621725)..... <b>PA32000</b>
<b>Air Dryer</b> (Bendix 5008414PG).... <b>BA5379</b>	<b>Trans.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	<b>Cab Air</b> (X1987001)..... <b>PA30093</b>
<b>Coolant</b> (1843659PE)..... <b>B5088 +</b>	<b>Trans.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	<b>Air Dryer</b> (Bendix 5008414PG).... <b>BA5379</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>		<b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>
		<b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b>
		<b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>
567 w/Cummins ISL-G (8.9L) Eng. (2020) <b>Lube</b> (Fleetguard LF9009)..... <b>B40142</b> <b>Fuel</b> (Fleetguard NG5900)..... <b>BF7695</b> <b>EnduraCube Air</b> (P621730)..... <b>PA32003</b> <b>Cab Air</b> (F371018)..... <b>PA30269</b> <b>Cab Air</b> (Fresh Air) (X1987001).... <b>PA30093</b> <b>Cab Air</b> (Recirc.) (W2084001)..... <b>PA30107</b> <b>Air Dryer</b> (Bendix 5008414PG).... <b>BA5379</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	567 w/Cummins ISX 11.9 (11.9L) Eng. (2020) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (Fleetguard FS19764)..... <b>PF9814</b> <b>Fuel</b> (2893612)..... <b>BF9885</b> <b>EnduraCube Air</b> (P621730)..... <b>PA32003</b> <b>Cab Air</b> (F371018)..... <b>PA30269</b> <b>Cab Air</b> (Fresh Air) (X1987001).... <b>PA30093</b> <b>Cab Air</b> (Recirc.) (W2084001).... <b>PA30107</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>	567 w/Cummins ISX 11.9G (11.9L) Eng. (2019) (Cont'd) <b>Trans.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
567 w/Cummins ISX 11.9 (11.9L) Eng. (2014-18) <b>Dual-Flow Lube</b> (Upgrade) (4367100)..... <b>BD50000</b> <b>Dual-Flow Lube</b> (Fleetguard LF9080)..... <b>BD7154 +</b> <b>Fuel/Water Separator</b> (Fleetguard FS19764)..... <b>PF7930</b> <b>Fuel/Water Separator</b> (Fleetguard FS1029)..... <b>PF7680</b> <b>Fuel</b> (Standard) (Fleetguard FF5776)..... <b>BF9885 +</b> <b>Fuel</b> (Upgrade) (Fleetguard FF5825NN)..... <b>BF46129</b> <b>EnduraCube Air</b> (P621725)..... <b>PA32000</b> <b>Cab Air</b> (X1987001)..... <b>PA30093</b> <b>Cab Air Foam</b> (W2084001)..... <b>PA30107</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Breather</b> (4312013)..... <b>CV15000</b> <b>Coolant</b> (3680434)..... <b>B5087</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>	567 w/Cummins ISX 11.9 (11.9L) Eng. (2021) <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	567 w/Cummins ISX 11.9G (11.9L) Eng. (2020) <b>Dual-Flow Lube</b> (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel</b> (Fleetguard NG5900)..... <b>BF7695</b> <b>EnduraCube Air</b> (P621730)..... <b>PA32003</b> <b>Cab Air</b> (F371018)..... <b>PA30269</b> <b>Cab Air</b> (Fresh Air) (X1987001).... <b>PA30093</b> <b>Cab Air</b> (Recirc.) (W2084001).... <b>PA30107</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Trans. Ele.</b> (2 In. Kit) (29558117).. <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (29558118).. <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
567 w/Cummins ISX 11.9 (11.9L) Eng. (2016-17) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>EnduraCube Air</b> (P621725)..... <b>PA32000</b> <b>Cab Air</b> (X1987001)..... <b>PA30093</b> <b>Cab Air Foam</b> (W2084001)..... <b>PA30107</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	567 w/Cummins ISX 11.9G (11.9L) Eng. (2018) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (3607140). <b>BF7695</b> <b>EnduraCube Air</b> (P621725)..... <b>PA32000</b> <b>Cab Air</b> (Fresh Air) (X1987001).... <b>PA30093</b> <b>Cab Air</b> (Recirculating Air) (W2084001)..... <b>PA30107</b> <b>Air Dryer</b> (Bendix 5008414PG).... <b>BA5379</b> <b>Coolant</b> (3680434)..... <b>B5087</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	567 w/Cummins ISX 11.9G (11.9L) Eng. (2022) <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
567 w/Cummins ISX 11.9 (11.9L) Eng. (2019) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (Fleetguard FS19764G)..... <b>PF46091</b> <b>Fuel</b> (2893612)..... <b>BF9885 +</b> <b>EnduraCube Air</b> (P621725)..... <b>PA32000</b> <b>Cab Air</b> (X1987001)..... <b>PA30093</b> <b>Air Dryer</b> (Bendix 5008414PG).... <b>BA5379</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>	567 w/Cummins ISX 11.9G (11.9L) Eng. (2019) <b>Dual-Flow Lube</b> (Fleetguard LF9080)..... <b>BD50000</b> <b>Fuel</b> (Fleetguard NG5900)..... <b>BF7695</b> <b>EnduraCube Air</b> (P621725)..... <b>PA32000</b> <b>Cab Air</b> (X1987001)..... <b>PA30093</b> <b>Air Dryer</b> (Bendix 5008414PG).... <b>BA5379</b>	567 w/Cummins ISX 11.9G (11.9L) Eng. (2023) <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
567 w/Cummins ISX 11.9 (11.9L) Eng. (2014-17) <b>Dual-Flow Lube</b> (Upgrade) (4367100)..... <b>BD50000</b> <b>Dual-Flow Lube</b> (Fleetguard LF9080)..... <b>BD7154 +</b> <b>Fuel/Water Separator</b> (Fleetguard FS1029)..... <b>PF7680</b> <b>Fuel/Water Separator</b> (K371011) <b>PF46081</b> <b>Fuel</b> (Standard) (Fleetguard FF5776)..... <b>BF9885 +</b> <b>Fuel</b> (Upgrade) (Fleetguard FF5825NN)..... <b>BF46129</b> <b>Fuel</b> (Upgrade) (Fleetguard FF5811)..... <b>BF46179</b> <b>EnduraCube Air</b> (P621725)..... <b>PA32000</b> <b>Cab Air</b> (X1987001)..... <b>PA30093</b> <b>Cab Air Foam</b> (W2084001)..... <b>PA30107</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Breather</b> (4312013)..... <b>CV15000</b> <b>Coolant</b> (3680434)..... <b>B5087</b>	567 w/Cummins ISX 15.0 (14.9L) Eng. (2014-17) <b>Dual-Flow Lube</b> (Upgrade) (4367100)..... <b>BD50000</b> <b>Dual-Flow Lube</b> (Fleetguard LF9080)..... <b>BD7154 +</b> <b>Fuel/Water Separator</b> (Fleetguard FS1029)..... <b>PF7680</b> <b>Fuel/Water Separator</b> (K371011) <b>PF46081</b> <b>Fuel</b> (Standard) (Fleetguard FF5776)..... <b>BF9885 +</b> <b>Fuel</b> (Upgrade) (Fleetguard FF5825NN)..... <b>BF46129</b> <b>Fuel</b> (Upgrade) (Fleetguard FF5811)..... <b>BF46179</b> <b>EnduraCube Air</b> (P621725)..... <b>PA32000</b> <b>Cab Air</b> (X1987001)..... <b>PA30093</b> <b>Cab Air Foam</b> (W2084001)..... <b>PA30107</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Breather</b> (4312013)..... <b>CV15000</b> <b>Coolant</b> (3680434)..... <b>B5087</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



PETERBILT Trucks (cont'd)	PETERBILT Trucks (cont'd)	PETERBILT Trucks (cont'd)
567 w/Cummins ISX 15.0 (14.9L) Eng. (2014-17) (Cont'd)	567 w/Cummins ISX 15.0 (14.9L) Eng. (2020) (Cont'd)	567 w/Cummins X15 (14.9L) Eng. (2020)
Trans. Ele. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	<b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b>
Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	<b>Fuel/Water Separator</b> (Fleetguard FS19764G)..... <b>PF46091</b>
Trans. Spin-on (Fuller 4304827).. <b>BT223</b>	Trans. Spin-on (Fuller 4304827).. <b>BT223</b>	<b>Fuel/Water Separator</b> (K371021) <b>PF46236</b>
Opt. Trans. Spin-on (Fuller 17237)..... <b>B2+</b>	Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>Fuel</b> (5365988)..... <b>BF46129</b>
Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	<b>EnduraCube Air</b> (P621730)..... <b>PA32003</b>
<b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>	567 w/Cummins ISX 15.0 (14.9L) Eng. (2021)	<b>Cab Air</b> (F371018)..... <b>PA30269</b>
567 w/Cummins ISX 15.0 (14.9L) / X15 (14.9L) Eng. (2018)	<b>Lube</b> (5575298)..... <b>B40145</b>	<b>Cab Air</b> (Fresh Air) (X1987001).... <b>PA30093</b>
<b>Dual-Flow Lube</b> (Fleetguard LF14000NN)..... <b>BD50000</b>	<b>Fuel</b> (5365988)..... <b>BF46129</b>	<b>Cab Air</b> (Recirculation Air) (W2084001)..... <b>PA30107</b>
<b>Fuel/Water Separator</b> (Fleetguard FS19765)..... <b>PF7930</b>	Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Air Dryer</b> (Bendix 5008414PG).... <b>BA5379</b>
<b>Fuel</b> (Upgrade) (Fleetguard FF5825NN)..... <b>BF46129</b>	Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Trans. Ele. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>
<b>EnduraCube Air</b> (P621725)..... <b>PA32000</b>	Trans. Spin-on (Fuller 4304827).. <b>BT223</b>	Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>
<b>Cab Air</b> (Fresh Air) (X1987001).... <b>PA30093</b>	Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	Trans. Spin-on (Fuller 4304827).. <b>BT223</b>
<b>Cab Air</b> (Recirculation Air) (W2084001)..... <b>PA30107</b>	567 w/Cummins ISX 15.0 (14.9L) Eng. (2022)	Steering (Nelson 87904M)..... <b>PT9354-MPG</b>
<b>Air Dryer</b> (Bendix 5008414PG).... <b>BA5379</b>	<b>Lube</b> (5575298)..... <b>B40145</b>	Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>
Trans. Ele. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	<b>Fuel</b> (5575143)..... <b>BF46248</b>	567 w/Paccar MX-11 (10.8L) Eng. (2016-18)
Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Lube Ele.</b> (1928868PE)..... <b>P40008</b>
Trans. Spin-on (Fuller 4304827).. <b>BT223</b>	Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Centrifugal Lube</b> (1928869)..... <b>BC40009</b>
Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	Trans. Spin-on (Fuller 4304827).. <b>BT223</b>	<b>Fuel/Water Separator</b> (Fleetguard FS19765)..... <b>PF7930</b>
Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1029W)..... <b>PF7680</b>
<b>Diesel Exhaust Fluid</b> (4388378).. <b>PE17002 KIT</b>	Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	<b>Fuel</b> (1852006PE)..... <b>PF46106</b>
567 w/Cummins ISX 15.0 (14.9L) Eng. (2019)	567 w/Cummins ISX 15.0 (14.9L) Eng. (2023)	<b>EnduraCube Air</b> (P621725)..... <b>PA32000</b>
<b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b>	<b>Lube</b> (5575298)..... <b>B40145</b>	<b>Cab Air</b> (X1987001)..... <b>PA30093</b>
<b>Fuel/Water Separator</b> (K371029) <b>PF46081</b>	<b>Fuel</b> (5575143)..... <b>BF46248</b>	<b>Cab Air Foam</b> (W2084001)..... <b>PA30107</b>
<b>Fuel</b> (5365988)..... <b>BF46129</b>	Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374+</b>
<b>EnduraCube Air</b> (P621725)..... <b>PA32000</b>	Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Air Dryer</b> (Bendix 5008414PG).... <b>BA5379</b>
<b>Cab Air</b> (X1987001)..... <b>PA30093</b>	Trans. Spin-on (Fuller 4304827).. <b>BT223</b>	<b>Coolant</b> (1843659)..... <b>B5088+</b>
<b>Air Dryer</b> (Bendix 5008414PG).... <b>BA5379</b>	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2</b>	Trans. Ele. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>
Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>
Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	567 w/Cummins X15 (14.9L) Eng. (2019)	Steering (Nelson 87904M)..... <b>PT9354-MPG</b>
Trans. (Fuller 4304827)..... <b>BT223</b>	<b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b>	Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>
Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	<b>Fuel/Water Separator</b> (K371029) <b>PF46081</b>	567 w/Paccar MX-11 (10.8L) Eng. (2019)
Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	<b>Fuel</b> (5365988)..... <b>BF46129</b>	<b>F-F Lube</b> (2129253PE)..... <b>P40008</b>
567 w/Cummins ISX 15.0 (14.9L) Eng. (2020)	<b>EnduraCube Air</b> (P621725)..... <b>PA32000</b>	<b>Centrifugal Lube</b> (1928869PE).... <b>BC40009</b>
<b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b>	<b>Cab Air</b> (X1987001)..... <b>PA30093</b>	<b>Fuel</b> (2133096PE)..... <b>PF46106</b>
<b>Fuel/Water Separator</b> (Fleetguard FS19764G)..... <b>PF46091</b>	<b>Air Dryer</b> (Bendix 5008414PG).... <b>BA5379</b>	<b>EnduraCube Air</b> (P621725)..... <b>PA32000</b>
<b>Fuel/Water Separator</b> (K371021) <b>PF46236</b>	Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	<b>Cab Air</b> (X1987001)..... <b>PA30093</b>
<b>Fuel</b> (5365988)..... <b>BF46129</b>	Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	<b>Air Dryer</b> (Bendix 5008414PG).... <b>BA5379</b>
<b>EnduraCube Air</b> (P621730)..... <b>PA32003</b>	Trans. (Fuller 4304827)..... <b>BT223</b>	<b>Coolant</b> (1843659PE)..... <b>B5088</b>
<b>Cab Air</b> (F371018)..... <b>PA30269</b>	Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	Trans. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>
<b>Cab Air</b> (Fresh Air) (X1987001).... <b>PA30093</b>	Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	Trans. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>
<b>Cab Air</b> (Recirc.) (W2084001)..... <b>PA30107</b>	567 w/Cummins ISX 15.0 (14.9L) Eng. (2020)	Steering (Nelson 87904M)..... <b>PT9354-MPG</b>
<b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374+</b>	<b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b>	Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>
	<b>Fuel/Water Separator</b> (K371029) <b>PF46081</b>	
	<b>Fuel</b> (5365988)..... <b>BF46129</b>	
	<b>EnduraCube Air</b> (P621725)..... <b>PA32000</b>	
	<b>Cab Air</b> (X1987001)..... <b>PA30093</b>	
	<b>Air Dryer</b> (Bendix 5008414PG).... <b>BA5379</b>	
	Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	
	Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	
	Trans. (Fuller 4304827)..... <b>BT223</b>	
	Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	
	Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>
567 w/Paccar MX-11 (10.8L) Eng. (2020) Lube (2129253PE)..... <b>P40008</b> Fuel/Water Separator (2164463PE)..... <b>PF46106</b> Fuel (2277129PE)..... <b>PF46106</b> EnduraCube Air (P621730)..... <b>PA32003</b> Cab Air (F371018)..... <b>PA30269</b> Cab Air (Fresh Air) (X1987001).... <b>PA30093</b> Cab Air (Recirc.) (W2084001)..... <b>PA30107</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Coolant (1843659PE)..... <b>B5088</b> Trans. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	567 w/Paccar MX-13 (12.9L) Eng. (2014-18) (Cont'd) Cab Air Foam (W2084001)..... <b>PA30107</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Air Dryer (Bendix 5008414PG).... <b>BA5379</b> Coolant (1843659)..... <b>B5088 +</b> Trans. Ele. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b> Diesel Exhaust Fluid (5303604).. <b>PE17000</b> Diesel Exhaust Fluid (2122909PE)..... <b>PE17002 KIT</b>	567 w/Paccar MX-13 (12.9L) Eng. (2021) F-F Lube (2234788PE)..... <b>P40069</b> Centrifugal Lube (1922496PE)... <b>BC40148</b> Fuel (2277129PE)..... <b>PF46106</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>
567 w/Paccar MX-11 (10.8L) Eng. (2021) Lube (2129253PE)..... <b>P40008</b> Fuel (2277129PE)..... <b>PF46106</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	567 w/Paccar MX-13 (12.9L) Eng. (2019) F-F Lube (2047411PE)..... <b>P40069</b> Centrifugal Lube (1922496PE)... <b>BC40148</b> Fuel/Water Separator (K371022) <b>PF46237</b> Fuel (2133096PE)..... <b>PF46106</b> EnduraCube Air (P621725)..... <b>PA32000</b> Cab Air (X1987001)..... <b>PA30093</b> Air Dryer (Bendix 5008414PG).... <b>BA5379</b> Coolant (1843659PE)..... <b>B5088 +</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Trans. (Fuller 4304827)..... <b>BT223</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	567 w/Paccar MX-13 (12.9L) Eng. (2022) S. Fuel/Water Separator (2277129)..... <b>PF46106</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>
567 w/Paccar MX-11 (10.8L) Eng. (2022) P. Fuel/Water Separator (K371022)..... <b>PF46237</b> S. Fuel/Water Separator (2277129)..... <b>PF46106</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	567 w/Paccar MX-13 (12.9L) Eng. (2020) F-F Lube (2151728PE)..... <b>P40069</b> Centrifugal Lube (1922496PE)... <b>BC40148</b> Fuel/Water Separator (K371012) <b>PF46082</b> Fuel (2133096PE)..... <b>PF46106</b> EnduraCube Air (P621730)..... <b>PA32003</b> Cab Air (F371018)..... <b>PA30269</b> Cab Air (Fresh Air) (X1987001).... <b>PA30093</b> Cab Air (Recirc.) (W2084001)..... <b>PA30107</b> Air Dryer (Bendix 5008414)..... <b>BA5374</b> Coolant (1843659PE)..... <b>B5088</b> Trans. Ele. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>BT223</b>	567 w/Paccar MX-13 (12.9L) Eng. (2023) Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>
567 w/Paccar MX-11 (10.8L) Eng. (2023) Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	567 w/Paccar MX-13 (12.9L) Eng. (2014-18) Lube Ele. (1948921)..... <b>P40019</b> Lube (2047411)..... <b>P40069</b> Centrifugal Lube (1922496)..... <b>BC40148</b> Fuel/Water Separator (Fleetguard FS19765)..... <b>PF7930</b> Fuel/Water Separator (Fleetguard FS19765G)..... <b>PF46094</b> Fuel/Water Separator (K371012) <b>PF46082</b> Fuel (1852006)..... <b>PF46106</b> EnduraCube Air (P621725)..... <b>PA32000</b> Cab Air (X1987001)..... <b>PA30093</b>	567 w/Paccar PX-9 (8.9L) Eng. (2015-18) Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309 +</b> Fuel/Water Separator (Fleetguard FS1003)..... <b>BF1293-SPS</b> Fuel (Fleetguard FF63009)..... <b>BF63000</b> EnduraCube Air (P621725)..... <b>PA32000</b> Cab Air (X1987001)..... <b>PA30093</b> Cab Air Foam (W2084001)..... <b>PA30107</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Trans. Ele. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Diesel Exhaust Fluid (5303604).. <b>PE17000</b>
	567 w/Paccar MX-13 (12.9L) Eng. (2021) F-F Lube (2234788PE)..... <b>P40069</b> Centrifugal Lube (1922496PE)... <b>BC40148</b> Fuel (2277129PE)..... <b>PF46106</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	567 w/Paccar PX-9 (8.9L) Eng. (2015-18) Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309 +</b> Fuel/Water Separator (Fleetguard FS1003)..... <b>BF1293-SPS</b> Fuel (Fleetguard FF63009)..... <b>BF63000</b> EnduraCube Air (P621725)..... <b>PA32000</b> Cab Air (X1987001)..... <b>PA30093</b> Air Dryer (Bendix 5008414PG).... <b>BA5379</b>
	567 w/Paccar MX-13 (12.9L) Eng. (2022) S. Fuel/Water Separator (2277129)..... <b>PF46106</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	567 w/Paccar PX-9 (8.9L) Eng. (2015-18) Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309 +</b> Fuel/Water Separator (Fleetguard FS1003)..... <b>BF1293-SPS</b> Fuel (Fleetguard FF63009)..... <b>BF63000</b> EnduraCube Air (P621725)..... <b>PA32000</b> Cab Air (X1987001)..... <b>PA30093</b> Air Dryer (Bendix 5008414PG).... <b>BA5379</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

PETERBILT Trucks (cont'd)	PETERBILT Trucks (cont'd)	PETERBILT Trucks (cont'd)
567 w/Paccar PX-9 (8.9L) Eng. (2019) (Cont'd)	579 w/Cummins ISX 11.9 (11.9L) Diesel Eng. (2014-18) (Cont'd)	579 w/Cummins ISX 11.9G (11.9L) CNG Eng. (2015) (Cont'd)
Trans. Ele. (2 In. Kit) (Allison 29558117).....	Fuel/Water Separator Ele. (Fleetguard FS19764).....	Fuel/Water Separator (3607140). [2] BF7695
PT9416-MPG KIT	PF9814	PA32003
Trans. Ele. (4 In. Kit) (Allison 29558118).....	Fuel/Water Separator (K371029) Fuel (Standard) (Fleetguard FF5776).....	Cab Air Foam (W2084001).....
PT9415-MPG KIT	PF46081	PA30107
Opt. Trans. Spin-on (Fuller 17237).....	BF9885 +	Cab Air (X1987001).....
B2 +	BF9885 +	PA30093
Steering (Nelson 87904M).....	Fuel (Upgrade) (Fleetguard FF5825NN).....	Air Dryer (AD-IS System) (Bendix 5008414).....
PT9354-MPG	BF46129	BA5374 +
Opt. Rear Axle (Meritor 3280V8394).....	BF9860 +	B5087
B233	BF9860 +	BT223
567 w/Paccar PX-9 (8.9L) Eng. (2020)	Fuel (Long Vers.) (Fleetguard FF5686).....	Steering (Nelson 87904M).....
Lube (3401544).....	BF9860 +	PT9354-MPG
B40142	BF9860 +	579 w/Cummins ISX 11.9G (11.9L) CNG Eng. (2018)
Fuel (5303743).....	EnduraCube Air (P621725).....	Dual-Flow Lube (4367100).....
BF63000	PA32000	BD50000
EnduraCube Air (P621730).....	PA32003	Fuel/Water Separator (3607140). [2] BF7695
PA32003	PA32003	PA32000
Cab Air (F371018).....	Cab Air Foam (W2084001).....	EnduraCube Air (P621730).....
PA30269	PA30107	PA32003
Cab Air (Fresh Air) (X1987001)....	Cab Air (X1987001).....	Cab Air (X1987001).....
PA30093	PA30093	PA30093
Cab Air (Recirc.) (W2084001).....	Air Dryer (AD-IS System) (Bendix 5008414).....	Air Dryer (Bendix 5008414PG)....
PA30107	BA5374 +	BA5379
Air Dryer (Bendix 5008414).....	Air Dryer (AD-IS System) (Bendix 5008414PG).....	Coolant (3680434).....
BA5374 +	BA5379	B5087
Trans. Ele. (2 In. Kit) (Allison 29558117).....	Breather (Fleetguard CV50634)....	Steering (Nelson 87904M).....
PT9416-MPG KIT	CV15000	PT9354-MPG
Trans. Ele. (4 In. Kit) (Allison 29558118).....	Coolant (3680434).....	Opt. Rear Axle (Meritor 3280V8394).....
PT9415-MPG KIT	B5087	B233
Steering (Nelson 87904M).....	Trans. (Fuller 4304827).....	579 w/Cummins ISX 11.9G (11.9L) CNG Eng. (2019)
PT9354-MPG	BT223	Dual-Flow Lube (4367100).....
Opt. Rear Axle (Meritor 3280V8394).....	Opt. Trans. (Fuller 17237).....	BD50000
B233	B2 +	Fuel/Water Separator (3607140). [2] BF7695
567 w/Paccar PX-9 (8.9L) Eng. (2021)	Steering (Nelson 87904M).....	EnduraCube Air (P621725).....
Lube (5444774).....	PT9354-MPG	PA32000
B40142	Opt. Rear Axle (Meritor 3280V8394).....	Cab Air Foam (W2084001).....
Fuel (5303743).....	B233	PA30107
BF63000	B233	Cab Air (X1987001).....
Trans. Ele. (2 In. Kit) (Allison 29540493).....	Diesel Exhaust Fluid (5303604)..	PA30093
PT9416-MPG KIT	PE17000	Air Dryer (Bendix 5008414).....
Trans. Ele. (4 In. Kit) (Allison 29540494).....	579 w/Cummins ISX 11.9 (11.9L) Diesel Eng. (2019)	BA5374 +
PT9415-MPG KIT	Dual-Flow Lube (4367100).....	B5087
Opt. Trans. Spin-on (Fuller 17237).....	BD50000	PT9354-MPG
B2	Fuel/Water Separator (Fleetguard FS19764).....	579 w/Cummins ISX 11.9G (11.9L) CNG Eng. (2020)
Opt. Rear Axle (Meritor 3280V8394).....	PF9814	Dual-Flow Lube (Fleetguard LF14000NN).....
B233	PF9885 +	BD50000
567 w/Paccar PX-9 (8.9L) Eng. (2022)	Fuel (2893612).....	Fuel (Fleetguard NG5900).....
Lube (5444774).....	PA32000	BF7695
B40142	PA32000	EnduraCube Air (P621725).....
Trans. Ele. (2 In. Kit) (Allison 29540493).....	Cab Air (X1987001).....	PA32000
PT9416-MPG KIT	PA30093	Cab Air Foam (W2084001).....
Trans. Ele. (4 In. Kit) (Allison 29540494).....	PA30107	PA30107
PT9415-MPG KIT	PA30093	Cab Air (X1987001).....
Opt. Rear Axle (Meritor 3280V8394).....	Cab Air Foam (W2084001).....	PA30093
B233	PA30107	Air Dryer (Bendix 5008414).....
579 w/Cummins ISL-G (8.9L) Eng. (2022)	Air Dryer (Bendix 5008414).....	BA5374 +
Lube (5444774).....	BA5374 +	BT223
B40142	PT9354-MPG	PT9354-MPG
Fuel/Water Separator (3607140). BF7695	Diesel Exhaust Fluid (5303604)..	Opt. Rear Axle (Meritor 3280V8394).....
Opt. Rear Axle (Meritor 3280V8394).....	PE17000	B233
B233	579 w/Cummins ISX 11.9 (11.9L) Diesel Eng. (2020)	579 w/Cummins ISX 11.9G (11.9L) CNG Eng. (2021)
579 w/Cummins ISX 11.9 (11.9L) Diesel Eng. (2014-18)	Dual-Flow Lube (4367100).....	Dual-Flow Lube (5575298).....
Dual-Flow Lube (Fleetguard LF9080).....	BD50000	B40145
BD7154 +	Fuel (2893612).....	Fuel (3607140).....
Dual-Flow Lube (Upgrade) (4367100).....	BF9885	BF7695
BD50000	BF9885	Coolant (3680434).....
Fuel/Water Separator Ele. (K371004).....	EnduraCube Air (P621725).....	B5087
PF9928	PA32000	579 w/Cummins ISX 11.9G (11.9L) CNG Eng. (2022)
579 w/Cummins ISX 11.9 (11.9L) Diesel Eng. (2014-18)	Cab Air Foam (W2084001).....	Opt. Rear Axle (Meritor 3280V8394).....
Dual-Flow Lube (Fleetguard LF9080).....	PA30107	B233
BD7154 +	PA30093	579 w/Cummins ISX 11.9G (11.9L) CNG Eng. (2022)
Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN).....	Air Dryer (Bendix 5008414).....	Opt. Rear Axle (Meritor 3280V8394).....
BD50000	BA5374 +	B233
579 w/Cummins ISX 11.9G (11.9L) CNG Eng. (2015)	Trans. (Fuller 4304827).....	579 w/Cummins ISX 11.9G (11.9L) CNG Eng. (2021)
Dual-Flow Lube (Fleetguard LF9080).....	BT223	Lube (5575298).....
BD7154 +	PT9354-MPG	B40145
Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN).....	Opt. Rear Axle (Meritor 3280V8394).....	Fuel (3607140).....
BD50000	B233	BF7695
579 w/Cummins ISX 11.9G (11.9L) Diesel Eng. (2014-18)	Diesel Exhaust Fluid (5303604)..	Coolant (3680434).....
Dual-Flow Lube (Fleetguard LF9080).....	PE17000	B5087
BD7154 +	579 w/Cummins ISX 11.9G (11.9L) CNG Eng. (2015)	579 w/Cummins ISX 11.9G (11.9L) CNG Eng. (2022)
Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN).....	Dual-Flow Lube (Fleetguard LF9080).....	Opt. Rear Axle (Meritor 3280V8394).....
BD50000	BD7154 +	B233
579 w/Cummins ISX 11.9G (11.9L) Diesel Eng. (2014-18)	Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN).....	579 w/Cummins ISX 11.9G (11.9L) CNG Eng. (2021)
Dual-Flow Lube (Fleetguard LF9080).....	BD50000	Lube (5575298).....
BD7154 +	579 w/Cummins ISX 11.9G (11.9L) CNG Eng. (2015)	B40145
Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN).....	Dual-Flow Lube (Fleetguard LF9080).....	Fuel (3607140).....
BD50000	BD7154 +	BF7695
579 w/Cummins ISX 11.9G (11.9L) Diesel Eng. (2014-18)	Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN).....	Coolant (3680434).....
Dual-Flow Lube (Fleetguard LF9080).....	BD50000	B5087
BD7154 +	579 w/Cummins ISX 11.9G (11.9L) CNG Eng. (2015)	579 w/Cummins ISX 11.9G (11.9L) CNG Eng. (2022)
Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN).....	Dual-Flow Lube (Fleetguard LF9080).....	Opt. Rear Axle (Meritor 3280V8394).....
BD50000	BD7154 +	B233

\* See Product Guide for Variations of This Number. Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>	<b>PETERBILT Trucks (cont'd)</b>
579 w/Cummins ISX 15.0 (14.9L) Eng. (2013-17) <b>Dual-Flow Lube</b> (Upgrade) (4367100)..... <b>BD50000</b> <b>Dual-Flow Lube</b> (Fleetguard LF9080)..... <b>BD7154 +</b> <b>Fuel/Water Separator Ele.</b> (K371004)..... <b>PF9928</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19764)..... <b>PF9814</b> <b>Fuel</b> (Standard) (Fleetguard FF5776)..... <b>BF9885 +</b> <b>Fuel</b> (Upgrade) (Fleetguard FF5825NN)..... <b>BF46129</b> <b>Fuel</b> (Long Vers.) (Fleetguard FF5686)..... <b>BF9860 +</b> <b>EnduraCube Air</b> (P621725)..... <b>PA32000</b> <b>Cab Air Foam</b> (W2084001)..... <b>PA30107</b> <b>Cab Air</b> (X1987001)..... <b>PA30093</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Breather</b> (Fleetguard CV50634).... <b>CV15000</b> <b>Coolant</b> (3680434)..... <b>B5087</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Diesel Exhaust Fluid</b> (5303604)..< <b>PE17000</b>	579 w/Cummins ISX 15.0 (14.9L) Eng. (2020) (Cont'd) <b>Cab Air</b> (X1987001)..... <b>PA30093</b> <b>Air Dryer</b> (Desiccant) (Bendix 5008414)..... <b>BA5374</b> <b>Air Dryer</b> (Coalescer) (Bendix 5008414PG)..... <b>BA5379</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	579 w/Paccar MX Eng. (Cont'd) <b>EnduraCube Air</b> (P621725)..... <b>PA32000</b> <b>Cab Air Foam</b> (W2084001)..... <b>PA30107</b> <b>Cab Air</b> (X1987001)..... <b>PA30093</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Coolant</b> (1843659)..... <b>B5088 +</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Diesel Exhaust Fluid</b> (5303604)..< <b>PE17000</b>
579 w/Cummins ISX 15.0 (14.9L) Eng. (2021) <b>Lube</b> (5575298)..... <b>B40145</b> <b>Fuel</b> (5365988)..... <b>BF46129</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b>	579 w/Cummins ISX 15.0 (14.9L) Eng. (2022) <b>Lube</b> (5575298)..... <b>B40145</b> <b>Fuel</b> (5575143)..... <b>BF46248</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	579 w/Paccar MX-11 (10.8L) Eng. (2016-18) <b>Lube Ele.</b> (1928868PE)..... <b>P40008</b> <b>Centrifugal Lube</b> (1928869PE).... <b>BC40009</b> <b>Fuel/Water Separator</b> (Fleetguard FS19765)..... <b>PF7930</b> <b>Fuel</b> (1852006PE)..... <b>PF46106</b> <b>EnduraCube Air</b> (P621725)..... <b>PA32000</b> <b>EnduraCube Air</b> (P621730)..... <b>PA32003</b> <b>Cab Air</b> (W2084001)..... <b>PA30093</b> <b>Cab Air Foam</b> (W2084001)..... <b>PA30107</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414PG)..... <b>BA5379</b> <b>Coolant</b> (1843659)..... <b>B5088 +</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (5303604)..< <b>PE17000</b>
579 w/Cummins ISX 15.0 (14.9L) / X15 (14.9L) Eng. (2018) <b>Dual-Flow Lube</b> (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (K371029) <b>PF46081</b> <b>Fuel</b> (Upgrade) (Fleetguard FF5825NN)..... <b>BF46129</b> <b>EnduraCube Air</b> (P621730)..... <b>PA32003</b> <b>Cab Air</b> (X1987001)..... <b>PA30093</b> <b>Air Dryer</b> (Bendix 5008414PG).... <b>BA5379</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (4388378)..< <b>PE17002 KIT</b>	579 w/Cummins X15 (14.9L) Eng. (2019) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (K371029) <b>PF46081</b> <b>Fuel</b> (5365988)..... <b>BF46129 +</b> <b>EnduraCube Air</b> (P621725)..... <b>PA32000</b> <b>Cab Air</b> (X1987001)..... <b>PA30093</b> <b>Cab Air Foam</b> (W2084001)..... <b>PA30107</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	579 w/Paccar MX-11 (10.8L) Eng. (2019) <b>F-F Lube</b> (2129253PE)..... <b>P40008</b> <b>Centrifugal Lube</b> (1928869PE).... <b>BC40009</b> <b>Fuel/Water Separator</b> (Fleetguard FS19765)..... <b>PF7930</b> <b>Fuel</b> (2133096PE)..... <b>PF46106</b> <b>EnduraCube Air</b> (P621725)..... <b>PA32000</b> <b>Cab Air</b> (X1987001)..... <b>PA30093</b> <b>Cab Air Foam</b> (W2084001)..... <b>PA30107</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Coolant</b> (1843659PE)..... <b>B5088</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>
579 w/Cummins ISX 15.0 (14.9L) Eng. (2019) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (K371029) <b>PF46081</b> <b>Fuel</b> (5365988)..... <b>BF46129 +</b> <b>EnduraCube Air</b> (P621725)..... <b>PA32000</b> <b>Cab Air</b> (X1987001)..... <b>PA30093</b> <b>Cab Air Foam</b> (W2084001)..... <b>PA30107</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b>	579 w/Cummins X15 (14.9L) Eng. (2020) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (K371021) <b>PF46236</b> <b>Fuel</b> (5365988)..... <b>BF46129</b> <b>EnduraCube Air</b> (P621725)..... <b>PA32000</b> <b>Cab Air Foam</b> (W2084001)..... <b>PA30107</b> <b>Cab Air</b> (X1987001)..... <b>PA30093</b> <b>Air Dryer</b> (Bendix 5008414PG).... <b>BA5379</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	579 w/Paccar MX-11 (10.8L) Eng. (2020) <b>F-F Lube</b> (2151728PE)..... <b>P40069</b> <b>Centrifugal Lube</b> (1922496PE).... <b>BC40148</b> <b>Fuel/Water Separator</b> (2164463PE)..... <b>PF46106</b> <b>Fuel</b> (2277129PE)..... <b>PF46106</b> <b>EnduraCube Air</b> (P621725)..... <b>PA32000</b> <b>Cab Air Foam</b> (W2084001)..... <b>PA30107</b> <b>Cab Air</b> (X1987001)..... <b>PA30093</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Coolant</b> (1843659PE)..... <b>B5088</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
579 w/Cummins ISX 15.0 (14.9L) Eng. (2020) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (K371021) <b>PF46236</b> <b>Fuel</b> (5365988)..... <b>BF46129</b> <b>EnduraCube Air</b> (P621725)..... <b>PA32000</b> <b>Cab Air Foam</b> (W2084001)..... <b>PA30107</b>	579 w/Electric Motor (2022) <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	
579 w/Paccar MX Eng. <b>F-F Lube Ele.</b> (1643070)..... <b>P40019</b> <b>B-P Lube Spinner</b> (1643072)..... <b>BC7326 +</b> <b>Fuel/Water Separator</b> (Fleetguard FS19765)..... <b>PF7930</b> <b>Fuel</b> (1655115)..... <b>BF9927</b> <b>Radial Seal XP Air</b> (Don. EAF5107)..... <b>RS3750XP</b>		

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

PETERBILT Trucks (cont'd)	PETERBILT Trucks (cont'd)	PETERBILT Trucks (cont'd)
579 w/Paccar MX-11 (10.8L) Eng. (2020) (Cont'd) <b>Diesel Exhaust Fluid</b> (2122909PE)..... <b>PE17002 KIT</b>	579 w/Paccar MX-13 (12.9L) Eng. (2020) (Cont'd) <b>Air Dryer</b> (Desiccant) (Bendix 5008414)..... <b>BA5374</b> <b>Air Dryer</b> (Coalescer) (Bendix 5008414PG)..... <b>BA5379</b> <b>Coolant</b> (1843659PE)..... <b>B5088</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	579 w/Paccar PX-9 (8.9L) Eng. (2019) (Cont'd) <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> 579 w/Paccar PX-9 (8.9L) Eng. (2020) <b>Lube</b> (3401544)..... <b>B40142</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Air</b> (P621725)..... <b>PA32000</b> <b>Cab Air</b> ((Foam) W2084001)..... <b>PA30107</b> <b>Cab Air</b> (X1987001)..... <b>PA30093</b> <b>Air Dryer</b> (Bendix 5008414PG).... <b>BA5379</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
579 w/Paccar MX-11 (10.8L) Eng. (2022) <b>S. Fuel/Water Separator</b> (2277129)..... <b>PF46106</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	579 w/Paccar MX-13 (12.9L) Eng. (2021) <b>Fuel/Water Separator</b> (Fleetguard FS19765G)..... <b>PF46094</b> <b>Fuel</b> (2277129PE)..... <b>PF46106</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b>	579 w/Paccar PX-9 (8.9L) Eng. (2021) <b>Lube</b> (5444774)..... <b>B40142</b> <b>Fuel</b> (5303743)..... <b>BF63000</b>
579 w/Paccar MX-13 (12.9L) Eng. (2014-18) <b>Lube Ele.</b> (1948921)..... <b>P40019</b> <b>Lube</b> (2047411)..... <b>P40069</b> <b>Centrifugal Lube</b> (1922496)..... <b>BC40148</b> <b>Fuel/Water Separator</b> (Fleetguard FS19765)..... <b>PF7930</b> <b>Fuel/Water Separator</b> (K371004) <b>PF9928</b> <b>Fuel/Water Separator</b> (K371009) <b>PF9929</b> <b>Fuel/Water Separator</b> (K371012) <b>PF46082</b> <b>Fuel</b> (1852006)..... <b>PF46106</b> <b>EnduraCube Air</b> (P621725)..... <b>PA32000</b> <b>EnduraCube Air</b> (P621730)..... <b>PA32003</b> <b>Cab Air Foam</b> (W2084001)..... <b>PA30107</b> <b>Cab Air</b> (X1987001)..... <b>PA30093</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414PG)..... <b>BA5379</b> <b>Coolant</b> (1843659)..... <b>B5088 +</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>	579 w/Paccar MX-13 (12.9L) Eng. (2022) <b>S. Fuel/Water Separator</b> (2277129)..... <b>PF46106</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	579 w/Paccar PX-9 (8.9L) Eng. (2022) <b>Lube</b> (5444774)..... <b>B40142</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
579 w/Paccar MX-13 (12.9L) Eng. (2019) <b>F-F Lube</b> (2047411PE)..... <b>P40069</b> <b>Centrifugal Lube</b> (1922496PE).... <b>BC40148</b> <b>Fuel/Water Separator</b> (K371022) <b>PF46237</b> <b>Fuel</b> (2133096PE)..... <b>PF46106</b> <b>EnduraCube Air</b> (P621725)..... <b>PA32000</b> <b>Cab Air</b> (X1987001)..... <b>PA30093</b> <b>Cab Air Foam</b> (W2084001)..... <b>PA30107</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Coolant</b> (1843659PE)..... <b>B5088 +</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Diesel Exhaust Fluid</b> (2122909PE)..... <b>PE17002 KIT</b>	579 w/Paccar MX-13 (12.9L) Eng. (2022) <b>S. Fuel/Water Separator</b> (2277129)..... <b>PF46106</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	587 w/Cummins ISX 15.0 (14.9L) Eng. (2011-17) <b>Dual-Flow Lube</b> (Upgrade) (4367100)..... <b>BD50000</b> <b>Dual-Flow Lube</b> (Fleetguard LF9080)..... <b>BD7154 +</b> <b>Fuel/Water Separator</b> (K371011) <b>PF46081</b> <b>Fuel</b> (Standard) (Fleetguard FF5776)..... <b>BF9885 +</b> <b>Fuel</b> (Upgrade) (Fleetguard FF5825NN)..... <b>BF46129</b> <b>Fuel</b> (Long Vers.) (Fleetguard FF5686)..... <b>BF9860 +</b> <b>Radial Seal XP Air</b> (Don. EAF5107)..... <b>RS3750XP</b> <b>Cab Air</b> (Bergstrom 525838BSM)..... <b>PA5694</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Breather</b> (Fleetguard CV50634)... <b>CV15000</b> <b>Coolant</b> (Fleetguard WF2127)..... <b>B5087</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>
579 w/Paccar MX-13 (12.9L) Eng. (2020) <b>F-F Lube</b> (2151728PE)..... <b>P40069</b> <b>Fuel</b> (2133096PE)..... <b>PF46106</b> <b>EnduraCube Air</b> (P621725)..... <b>PA32000</b> <b>Cab Air Foam</b> (W2084001)..... <b>PA30107</b> <b>Cab Air</b> (X1987001)..... <b>PA30093</b>	579 w/Paccar MX-13 (12.9L) Eng. (2021) <b>Fuel/Water Separator</b> (Fleetguard FS1003)..... <b>BF1293-SPS</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> <b>EnduraCube Air</b> (P621725)..... <b>PA32000</b> <b>Cab Air Foam</b> (W2084001)..... <b>PA30107</b> <b>Cab Air</b> (X1987001)..... <b>PA30093</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b>	587 w/Cummins ISX 15.0 (14.9L) Eng. (2018) <b>Dual-Flow Lube</b> (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (K371029) <b>PF46081</b> <b>Fuel</b> (Fleetguard FF5825NN)..... <b>BF46129</b> <b>Radial Seal XP Air</b> (Don. EAF5107)..... <b>RS3750XP</b> <b>Cab Air</b> (SR2000057)..... <b>PA5694</b> <b>Air Dryer</b> (Bendix 5008414PG).... <b>BA5379</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Diesel Exhaust Fluid</b> (4388378).. <b>PE17002 KIT</b>
579 w/Paccar MX-13 (12.9L) Eng. (2020) <b>F-F Lube</b> (2151728PE)..... <b>P40069</b> <b>Fuel</b> (2133096PE)..... <b>PF46106</b> <b>EnduraCube Air</b> (P621725)..... <b>PA32000</b> <b>Cab Air Foam</b> (W2084001)..... <b>PA30107</b> <b>Cab Air</b> (X1987001)..... <b>PA30093</b>	579 w/Paccar PX-9 (8.9L) Eng. (2018-17) <b>Dual-Flow Lube</b> (3401544)..... <b>BD7309 +</b> <b>Lube</b> (Upgrade) (3401544)..... <b>B40142 +</b> <b>Fuel/Water Separator</b> (Fleetguard FS1003)..... <b>BF1293-SPS</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>EnduraCube Air</b> (P621725)..... <b>PA32000</b> <b>Cab Air Foam</b> (W2084001)..... <b>PA30107</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>	579 w/Paccar PX-9 (8.9L) Eng. (2018) <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel/Water Separator</b> (Fleetguard FS1003)..... <b>BF1293-SPS</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> <b>EnduraCube Air</b> (P621725)..... <b>PA32000</b> <b>Cab Air Foam</b> (W2084001)..... <b>PA30107</b> <b>Cab Air</b> (X1987001)..... <b>PA30093</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b>


+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>PETERBILT</b> <b>Trucks (cont'd)</b>	<b>PEUGEOT</b> <b>European Light Duty Vehicles</b>	<b>PEUGEOT</b> <b>European Light Duty Vehicles (cont'd)</b>
587 w/Cummins X15 (14.9L) Eng. (2018) <b>Dual-Flow Lube</b> (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (K371029) <b>PF46081</b> <b>Fuel</b> (Upgrade) (Fleetguard FF5825NN)..... <b>BF46129</b> <b>Radial Seal XP Air</b> (Don. EAF5107)..... <b>RS3750XP</b> <b>Cab Air</b> (SR2000057)..... <b>PA5694</b> <b>Air Dryer</b> (Bendix 5008414PG).... <b>BA5379</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2+</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Diesel Exhaust Fluid</b> (4388378).. <b>PE17002 KIT</b>	306 1.8 D (1993-on) <b>Air</b> (1444.H1)..... <b>PA4388</b> 306 1.9 D (1993-on) <b>Air</b> (1444.H1)..... <b>PA4388</b> Bipper 1.3 HDI 75 w/F130DTE5 Eng. (09/10-on) <b>Fuel</b> (1606384980)..... <b>BF46051</b> <b>Cabin Air</b> (Left Hand Drive) (647963)..... <b>PA10085</b> Bipper 1.4 w/TU3A Eng. (02/08-on) <b>Lube</b> (1109X3)..... <b>P7450</b> <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Cabin Air</b> (Left Hand Drive) (647963)..... <b>PA10085</b>	Boxer I 2.5 TD w/T8A (DJ5T) Eng. (08/94-08/98) <b>Lube</b> (110987)..... <b>B7042</b> <b>Fuel</b> (190608)..... <b>BF825+</b> Boxer I 2.5 TD w/T8A (DJ5T) Eng. (09/98-12/00) <b>Lube</b> (1109N2)..... <b>B7167</b> <b>Fuel</b> (190608)..... <b>BF825+</b> Boxer I 2.5 TDI w/THX (DJ5TED) Eng. (01/97-08/98) <b>Lube</b> (110987)..... <b>B7042</b> <b>Fuel</b> (Bosch System)..... <b>BF5587-D</b> <b>Fuel</b> (CAV/Delphi System) (190608)..... <b>BF825+</b>
587 w/Paccar MX (12.9L) Eng. <b>F-F Lube Ele.</b> (1643070)..... <b>P40019</b> <b>Lube Spinner</b> (1643072)..... <b>BC7326+</b> <b>Fuel/Water Separator</b> (K371004) <b>PF9928</b> <b>Fuel</b> (1655115)..... <b>BF9927</b> <b>Radial Seal Air</b> (Don. P185093).. <b>RS3750</b> <b>Radial Seal XP Air</b> (Don. P185093)..... <b>RS3750XP</b> <b>Cab Air</b> (Bergstrom 525838BSM)..... <b>PA5694</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374+</b> <b>Coolant</b> (1843659)..... <b>B5088+</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>	Bipper 1.4 HDI w/DV4TED Eng. (02/08-on) <b>Cabin Air</b> (Left Hand Drive) (647963)..... <b>PA10085</b> Boxer I 1.9 Diesel w/D8C (XUD9AU) Eng. (03/94-06/99) <b>Lube</b> ..... <b>B7167</b> <b>Fuel</b> (190608)..... <b>BF825+</b> <b>Air</b> (144409)..... <b>PA3836</b> Boxer I 1.9 Diesel w/D8C (XUD9AU) Eng. (07/99-03/02) <b>Lube</b> (1109R0)..... <b>B7428</b> <b>Fuel</b> (190608)..... <b>BF825+</b> <b>Air</b> (144409)..... <b>PA3836</b>	Boxer I 2.5 TDI w/THX (DJ5TED) Eng. (09/98-12/00) <b>Lube</b> ..... <b>B7167</b> <b>Fuel</b> (Bosch System)..... <b>BF5587-D</b> <b>Fuel</b> (CAV/Delphi System) (190608)..... <b>BF825+</b> Boxer I 2.8 HDI w/8140.43S Eng. (09/00-03/02) <b>Dual-Flow Lube</b> (1109Q0)..... <b>BD232</b> <b>Fuel</b> (190666)..... <b>BF7976</b> Boxer II 2.0 HDI w/RHV (DW10UTD) Eng. (02/02-on) <b>Lube</b> (1109R0)..... <b>B7428</b> <b>Fuel</b> (190666)..... <b>BF7976</b>
587 w/Paccar MX-13 (12.9L) Eng. (2014-17) <b>Lube Ele.</b> (1643070)..... <b>P40019</b> <b>Centrifugal Lube</b> (1872106)..... <b>BC7326+</b> <b>Fuel/Water Separator</b> (Fleetguard FS19765G)..... <b>PF46094</b> <b>Fuel</b> (1852006)..... <b>PF46106</b> <b>Radial Seal Air</b> (Don. P185093).. <b>RS3750</b> <b>Radial Seal XP Air</b> (Don. P185093)..... <b>RS3750XP</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374+</b> <b>Coolant</b> (1843659)..... <b>B5088+</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2+</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>	Boxer I 1.9 TurboDiesel w/DHY-D8C (XUD9TE-F) Eng. (03/94-06/99) <b>Lube</b> ..... <b>B7167</b> <b>Fuel</b> (190608)..... <b>BF825+</b> Boxer I 1.9 TurboDiesel w/DHY-D8C (XUD9TE-F) Eng. (07/99-03/02) <b>Lube</b> (1109R0)..... <b>B7428</b> <b>Fuel</b> (190608)..... <b>BF825+</b> Boxer I 2.0 HDI TurboDiesel w/DW10TD Eng. (08/01-03/02) <b>Lube</b> (1109R0)..... <b>B7428</b> <b>Fuel</b> (190666)..... <b>BF7976</b>	Boxer II 2.0 i w/RFL (XU10J2U) Eng. (02/02-on) <b>Lube</b> ..... <b>B7167</b> <b>Fuel</b> (N/S)..... <b>N/S</b> Boxer II 2.2 HDI w/4HY (DW12UTED) Eng. (02/02-on) <b>Lube</b> (1109R0)..... <b>B7428</b> <b>Fuel</b> (190666)..... <b>BF7976</b> Boxer II 2.8 HDI w/8140.43S (127 HP) Eng. (02/02-on) <b>Dual-Flow Lube</b> (1109Q0)..... <b>BD232</b> <b>Fuel</b> (190666)..... <b>BF7976</b>
587 w/Paccar MX-13 (12.9L) Eng. (2018) <b>F-F Lube</b> (2047411)..... <b>P40069</b> <b>Centrifugal Lube</b> (1922496)..... <b>BC40148</b> <b>Fuel/Water Separator</b> (K371012) <b>PF46082</b> <b>Fuel</b> (1852006)..... <b>PF46106</b> <b>Radial Seal XP Air</b> (Don. EAF5107)..... <b>RS3750XP</b> <b>Cab Air</b> (SR2000057)..... <b>PA5694</b> <b>Air Dryer</b> (Bendix 5008414PG).... <b>BA5379</b> <b>Coolant</b> (1843659)..... <b>B5088+</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Diesel Exhaust Fluid</b> (2122909PE)..... <b>PE17002 KIT</b>	Boxer I 2.0i w/RFW (XU10J2U) Eng. (07/99-03/02) <b>Lube</b> (1109R0)..... <b>B7428</b> <b>Fuel</b> (156705)..... <b>BF885</b> Boxer I 2.0i w/RFW (XU10J2U) Eng. (07/99-03/02) <b>Lube</b> (1109R0)..... <b>B7428</b> <b>Fuel</b> (156705)..... <b>BF885</b> Boxer I 2.5 D w/T9A (DJ5) Eng. (07/94-08/98) <b>Lube</b> (110987)..... <b>B7042</b> <b>Fuel</b> (190608)..... <b>BF825+</b> <b>Air</b> (144409)..... <b>PA3836</b> Boxer I 2.5 D w/T9A (DJ5) Eng. (09/98-03/02) <b>Lube</b> (1109N2)..... <b>B7167</b> <b>Fuel</b> (190608)..... <b>BF825+</b> <b>Air</b> (144409)..... <b>PA3836</b>	Boxer II 2.8 HDI w/8140.43S (146 HP) Eng. (04/04-on) <b>Dual-Flow Lube</b> (1109Q0)..... <b>BD232</b> <b>Fuel</b> (190666)..... <b>BF7976</b> Boxer III 2.2 HDI w/4HU Eng. <b>Lube</b> (1109X3)..... <b>P7450</b> <b>Air</b> (1444QT)..... <b>PA4472</b> <b>Cab Air</b> (6447YA)..... <b>PA5798<sup>90</sup></b> Boxer III 2.2 HDI w/4HV Eng. (05/06-on) <b>Lube</b> (1109X3)..... <b>P7450</b> <b>Air</b> (1444QT)..... <b>PA4472</b> <b>Cab Air</b> (6447YA)..... <b>PA5798<sup>90</sup></b> Boxer III 2.2 HDI FAP 110 w/22 DT PUMA Euro 5 Eng. (07/11-on) <b>Lube</b> (1109X3)..... <b>P7450</b> <b>Air</b> (1444QT)..... <b>PA4472</b> <b>Cabin Air</b> (6447YC)..... <b>PA5798<sup>90</sup></b>

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
 Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

PEUGEOT European Light Duty Vehicles (cont'd)	PEUGEOT European Light Duty Vehicles (cont'd)	PEUGEOT European Light Duty Vehicles (cont'd)
Boxer III 2.2 HDI FAP 130 w/22 DT PUMA Euro 5 Eng. (07/11-on) Lube (1109X3)..... P7450 Air (1444QT)..... PA4472 Cabin Air (6447YC)..... PA5798 <sup>90</sup>	Expert I 2.0 HDI 110 w/RHW/RHZ (DW10ATED) Eng. (02/00-01/07) Lube (1109AL)..... B7428 Fuel..... PF822	Partner II 1.6 w/EP6C Eng. (04/10-on) Lube (1109X3)..... P7450 Air (1444RJ)..... PA10336
Boxer III 2.2 HDI FAP 150 w/22 DT PUMA Euro 5 Eng. (07/11-on) Lube (1109X3)..... P7450 Air (1444QT)..... PA4472 Cabin Air (6447YC)..... PA5798 <sup>90</sup>	Expert II 2.0 w/EW10A Eng. (01/07-on) Lube (1109X3)..... P7450	Partner II 1.6 w/EP6CDTR Eng. (08/10-on) Lube (1109X3)..... P7450 Air (1444RJ)..... PA10336
Boxer III 3.0 HDI w/F1C Eng. (05/06-on) Lube (1109X3)..... P7450 Air (1444QT)..... PA4472 Cab Air (6447YA)..... PA5798 <sup>90</sup>	Expert II 2.0 HDI 120 w/DW10UTED4 Eng. (01/07-on) Lube (1109X3)..... P7450	Partner II 1.6 w/TU5JP4B Eng. (04/08-on) Lube (1109X3)..... P7450 Fuel (N/S)..... N/S
Boxer III 3.0 HDI 160 w/F30DT/F30DTE5 Eng. (07/06-on) Lube (1606267580)..... B7388 Air (1444QT)..... PA4472 Cabin Air (6447YC)..... PA5798 <sup>90</sup>	Expert II 2.0 HDI FAP 95 w/DW10CDE5 Eng. (07/11-on) Lube (1109X3)..... P7450	Partner II 1.6 w/TU5JP4 Eng. (04/08-on) Lube (1109X3)..... P7450 Fuel (N/S)..... N/S
Boxer III 3.0 HDI FAP w/F30DTE5 Eng. (01/10-on) Lube (1606267580)..... B7388 Air (1444QT)..... PA4472 Cabin Air (6447YC)..... PA5798 <sup>90</sup>	Expert II 2.0 HDI FAP 125 w/DW10CEE5 Eng. (07/11-on) Lube (1109X3)..... P7450	<b>PEUGEOT Light-Duty Vehicles</b>
Boxer III 3.0 HDI FAP 180 w/F30DTEuro5 Eng. (07/11-on) Lube (1606267580)..... B7388 Air (1444QT)..... PA4472 Cabin Air (6447YC)..... PA5798 <sup>90</sup>	Expert II 2.0 HDI FAP 165 w/DW10CTED4 Eng. (07/10-on) Lube (1109X3)..... P7450	Boxer 1.9D, 1.9TD, 2.0 Lube (Sakura C2105)..... B7167 Can-Type Fuel..... BF825 + Air (1.9D)..... PA3836
Expert I 1.6 w/222A2 (1580 SPI) Eng. (02/96-01/07) Lube (1109AL)..... B7428 Fuel (156713)..... BF1195	Expert 4 (K0) 2.0 HDI w/DW10FD 150HP Eng. (2016-on) Lube Spin-on (1109AL)..... B7428	Boxer 2.5D Lube (Sakura L34480)..... B7042 Can-Type Fuel..... BF825 + Air..... PA3836
Expert I 1.9 D w/DW8 (WJY/WJZ) Eng. (04/98-01/07) Lube (1109AL)..... B7428	Expert 4 (K0) 2.0 HDI w/DW10FC 180HP Eng. (2016-on) Lube Spin-on (1109AL)..... B7428	J5 1.8L, 2.0L w/XM7T, XN1T Engs. Lube (To 1983)..... B195 Lube (1983-on) (Sakura C2105)... B7167 In-Line Fuel..... BF833
Expert I 1.9 D w/D9B (XUD9U) Eng. (02/96-01/07) Lube (1109AL)..... B7428 Fuel (190638)..... PF7817	Partner 1.8 D (1996-on) Air (1444.H1)..... PA4388	J5 1.9D, 2.5D w/XUD9A, U25/661 Engs. Lube (1.9D)..... B7167 Lube (2.5D 1983-on) (Sakura L34480)..... B7042
Expert I 1.9 TD w/D8B (XUD9TEF) Eng. (02/96-01/07) Lube (1109AL)..... B7428 Fuel (190638)..... PF7817	Partner 1.9 D (1996-on) Air (1444.H1)..... PA4388	J7 2.0D, 2.1D, 2.3D w/XDP88, XDP90, XD2P94 Engs. Lube..... B195
Expert I 1.9 TD w/DHX (XUD9TF) Eng. (02/96-01/07) Lube (1109AL)..... B7428	Partner I (Ranch) 1.1 w/HDZ/HFX (TU1M/TU1JP) Eng. (06/96-05/08) Lube (To 06/99) (110962)..... B7042 Lube (08/00-on) (1109R0)..... B7428	J9 1.6, 2.0 w/XC7T, XN1P Engs. Lube (To 1983)..... B195 Lube (1983-on) (Sakura C2105)... B7167
Expert I 2.0 16V w/RFN (WD10J4) Eng. (03/00-01/07) Lube (1109AL)..... B7428	Partner I (Ranch) 1.4 w/KFW/KFX (TU3JP) Eng. (06/96-12/09) Lube (To 06/99) (110962)..... B7042 Lube (08/00-on) (1109R0)..... B7428	J9 2.3D, 2.5D w/XD2P, XD3P Engs. Lube (To 1981)..... B195 Lube (1981-on) (Sakura C2105)... B7167
Expert I 2.0 HDI w/RHX (DW10BTED) Eng. (02/00-01/07) Lube (1109AL)..... B7428 Fuel..... PF822	Partner I (Ranch) 1.4 BiFuel w/TU3 JP Eng. (04/03-12/09) Lube (1109X3)..... P7450	<b>PIERCE Fire Trucks</b>
	Partner I (Ranch) 1.6 16V w/NFU (TU5JPA) Eng. (10/00-05/08) Lube (1109X3)..... P7450	Models w/Farr Air Filters Air (Farr 99842-005)..... PA4657 Air (Farr 99842004)..... PA30039
	Partner I (Ranch) 1.9 D w/WJY(DW8B)/WJZ(DW8) Engs. (12/98-05/08) Lube (1109AL)..... B7428 Air (To 10/02) (1444H2)..... PA4388	Saber Disposable Air Housing (Farr 400470002)..... PA30038
	Partner I (Ranch) 2.0 HDI w/RHY (DW10TD) Eng. (06/99-12/09) Lube (1109AL)..... B7428	Pierce w/Cat 3208 Eng. Lube (1R0713)..... [2] BT230 + Lube (1R0714)..... [2] B75 Lube (9L9200)..... [2] BT364 Fuel/Water Separator (8N9803).. BF912 Fuel Ele. (9M2341)..... PF935 Fuel Spin-on (1R0740)..... BF970 + Fuel Spin-on (1R0750)..... BF7633 +

\* See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>PONY PACK</b>	<b>POWERPAC</b>	<b>PREVOST</b>
<b>Auxiliary Power Units (APU)</b>	<b>Auxiliary Power Units (APU) (cont'd)</b>	<b>Buses (Also See Engine Listings) (cont'd)</b>
104-105 w/Kubota Z482E Eng. Lube (70000-15241)..... <b>B179</b> Fuel In-Line (13351-43010)..... <b>BF840</b> + Fuel Ele. (15231-43560)..... <b>PF872</b> Air (Don. ECD045003)..... <b>PA2832</b>	APUC w/Cat CO.5 Eng. (Cont'd) Fuel/Water Separator (Open End for Bowl) (Racor R12T)..... <b>BF1380-O</b> Fuel (150-4142)..... <b>BF7648</b> Radial Seal Air (Enginaire 2SE1). <b>RS3715</b>	X3-45 w/Volvo D13 Eng. (Cont'd) S. Fuel (20405160)..... <b>BF7814</b> Air (Nelson 70337-N)..... <b>PA2839</b> Air Dryer (3097369)..... <b>BA16000</b> Coolant (20458771)..... <b>B5145</b> Steering (Nelson 83804E)..... <b>P528</b>
PP 200 w/Kubota Z482E Eng. 2 9/16 In. O.D. Lube (15853-32430)..... <b>B7285</b> 3 In. O.D. Lube (70000-15241)..... <b>B179</b> Fuel (15231-43560)..... <b>PF872</b> Air..... <b>CLN&amp;R</b>	APUK w/Kubota Z-482 Eng. 3 In. Lube (15853-32430)..... <b>B7285</b> 5 9/32 In. Lube (70000-32091)..... <b>B2</b> + Fuel/Water Separator (w/Drain and Sensor Port) (Racor R12T).... <b>BF1380</b> Fuel/Water Separator (Open End for Bowl) (Racor R12T)..... <b>BF1380-O</b> Fuel (15221-43081)..... <b>BF940</b> Air (14971-11180)..... <b>PA3983-FN</b> Radial Seal Air (Enginaire 2SE1). <b>RS3715</b>	XL w/Detroit Series 50 Eng. (1989-2000) Lube (25014505)..... [2] <b>B495</b> Opt. Fuel/Water Separator Spin-on (w/Drain) (Racor S3202). <b>BF5813</b> + Opt. Fuel/Water Separator Spin-on (Open End for Bowl) (Racor S3202)..... <b>BF5813-O</b> + P. Fuel (25014274)..... <b>BF5800</b> + S. Fuel (25014342)..... <b>BF5810</b> Air (Nelson 70337-N)..... <b>PA2839</b> Air Dryer (Wabco R950011)..... <b>BA5374</b> + Coolant (23507545)..... <b>BW5137</b> Steering (Nelson 83804E)..... <b>P528</b>
<b>POST OFFICE</b>	<b>PREVOST</b>	<b>Buses (Also See Engine Listings)</b>
<b>Post Office Vehicles</b>	<b>Buses (Also See Engine Listings)</b>	<b>Buses (Also See Engine Listings)</b>
Models w/3 1/4 In. by 5 1/4 In. O.D. Round Air Filter Air (111316)..... <b>PA649</b>	H3 w/Detroit Series 60 Eng. (1996-2006) Lube (510458)..... [2] <b>B495</b> Opt. P. Fuel/Water Separator (w/Drain) (531407)..... <b>BF5813</b> + Opt. P. Fuel/Water Separator (Open End for Bowl) (531407)..... <b>BF5813-O</b> + P. Fuel (510137)..... <b>BF5800</b> + S. Fuel (510128)..... <b>BF5810</b> Air (530197)..... <b>PA2839</b> Air Dryer (1996-97) (641278)..... <b>BA5374</b> + Air Dryer (1998-2001) (Bendix 107796)..... <b>BA5377</b> Air Dryer (2003-04) (3097369)..... <b>BA16000</b> Coolant (550630)..... <b>BW5137</b> Steering (660987)..... <b>P528</b>	XL w/Detroit Series 60 Eng. (1989-2000) Lube (25014505)..... [2] <b>B495</b> Opt. Fuel/Water Separator Spin-on (w/Drain) (Racor S3202). <b>BF5813</b> + Opt. Fuel/Water Separator Spin-on (Open End for Bowl) (Racor S3202)..... <b>BF5813-O</b> + P. Fuel (25014274)..... <b>BF5800</b> + S. Fuel (25014342)..... <b>BF5810</b> Air (Nelson 70337-N)..... <b>PA2839</b> Air Dryer (Wabco R950011)..... <b>BA5374</b> + Coolant (23507545)..... <b>BW5137</b> Steering (Nelson 83804E)..... <b>P528</b>
<b>POWER TECH</b>	<b>PREVOST</b>	<b>Buses (Also See Engine Listings)</b>
<b>Auxiliary Power Units (APU)</b>	<b>Buses (Also See Engine Listings)</b>	<b>Buses (Also See Engine Listings)</b>
Models w/Cat CO.5 Eng. Lube (220-1523)..... <b>B1405</b> Fuel/Water Separator (w/Drain and Sensor Port) (Racor R12T).... <b>BF1380</b> Fuel/Water Separator (Open End for Bowl) (Racor R12T)..... <b>BF1380-O</b> Fuel (150-4142)..... <b>BF7648</b> Radial Seal Air (Enginaire 2SE1). <b>RS3715</b>	X3-45 w/Detroit Series 60 Eng. Lube (25014505)..... [2] <b>B495</b> Fuel/Water Separator Ele. (23521528)..... <b>PF7744</b> Fuel/Water Separator Spin-on (w/Drain) (Racor S3202)..... <b>BF5813</b> + Fuel/Water Separator Spin-on (Open End for Bowl) (Racor S3202)..... <b>BF5813-O</b> + P. Fuel (25014274)..... <b>BF5800</b> + S. Fuel (25014342)..... <b>BF5810</b> Air (Nelson 70337-N)..... <b>PA2839</b> Air Dryer (3097369)..... <b>BA16000</b> Coolant (w/4 Units BTE) (23507545)..... <b>BW5137</b> Coolant (w/16 Units BTE) (23507189)..... <b>BW5140</b> Steering (Nelson 83804E)..... <b>P528</b>	XLII w/Detroit Series 60 Eng. (1999-2003) Lube (25014505)..... [2] <b>B495</b> Opt. Fuel/Water Separator Spin-on (w/Drain) (Racor S3202). <b>BF5813</b> + Opt. Fuel/Water Separator Spin-on (Open End for Bowl) (Racor S3202)..... <b>BF5813-O</b> + P. Fuel (25014274)..... <b>BF5800</b> + S. Fuel (25014342)..... <b>BF5810</b> Air (Nelson 70337-N)..... <b>PA2839</b> Cab Air..... <b>CLN&amp;R</b> Air Dryer (Bendix 107796)..... <b>BA5377</b> Coolant (23507545)..... <b>BW5137</b> Steering (Nelson 83804E)..... <b>P528</b>
Models w/Kubota Z482 Eng. 3 In. Lube (15853-32430)..... <b>B7285</b> 5 9/32 In. Lube (70000-32091)..... <b>B2</b> + Fuel/Water Separator (w/Drain and Sensor Port) (Racor R12T).... <b>BF1380</b> Fuel/Water Separator (Open End for Bowl) (Racor R12T)..... <b>BF1380-O</b> Fuel Spin-on (15221-43081)..... <b>BF940</b> Radial Seal Air (Enginaire 2SE1). <b>RS3715</b> Air (14971-11180)..... <b>PA3983-FN</b>	<b>PREVOST</b>	<b>Motorhomes</b>
<b>POWER TECH</b>	<b>Buses (Also See Engine Listings)</b>	<b>Buses (Also See Engine Listings)</b>
<b>RV Generators</b>	<b>Buses (Also See Engine Listings)</b>	<b>Buses (Also See Engine Listings)</b>
CD7000 w/Kubota D1105 Eng. Lube (Napa 1344)..... <b>B161-S</b> Fuel (15221-43081)..... <b>BF940</b> Air (Napa 6270)..... <b>PA1865-FN</b>	X3-45 w/Volvo D13 Eng. P. Fuel/Water Separator Spin-on (20879806)..... <b>BF1386-O</b> Fuel/Water Separator (510795).... <b>PF7748</b> Opt. Fuel/Water Separator (w/Drain) (531390)..... <b>BF5813</b> + Opt. Fuel/Water Separator (Open End for Bowl) (531390)..... <b>BF5813-O</b> +	XL w/Detroit Series 50 Eng. (1989-2000) Lube (25014505)..... [2] <b>B495</b> Opt. Fuel/Water Separator Spin-on (w/Drain) (Racor S3202). <b>BF5813</b> + Opt. Fuel/Water Separator Spin-on (Open End for Bowl) (Racor S3202)..... <b>BF5813-O</b> + P. Fuel (25014274)..... <b>BF5800</b> + S. Fuel (25014342)..... <b>BF5810</b>
PT-7000 w/Kubota D1105 Eng. Lube (Napa 1344)..... <b>B161-S</b> Fuel (15221-43081)..... <b>BF940</b> Air (Napa 6270)..... <b>PA1865-FN</b>	<b>POWERPAC</b>	
TPU-7000 w/Kubota D1105 Eng. Lube (Napa 1344)..... <b>B161-S</b> Fuel (15221-43081)..... <b>BF940</b> Air (Napa 6270)..... <b>PA1865-FN</b>	<b>Auxiliary Power Units (APU)</b>	
	APUC w/Cat CO.5 Eng. Lube (220-1523)..... <b>B1405</b> Lube (150-4140)..... <b>B74</b> Fuel/Water Separator (w/Drain and Sensor Port) (Racor R12T).... <b>BF1380</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



PREVOST Motorhomes (cont'd)	PROHEAT Auxiliary Power Units (APU) (cont'd)	R.V.I. Buses (cont'd)
XL w/Detroit Series 50 Eng. (1989-2000) (Cont'd)	GEN4 w/Kubota Z482-B Eng. (Cont'd)	Magnum 400 w/E7-400 ETECH Eng. (Cont'd)
Air (Nelson 70337-N)..... PA2839	Radial Seal Air (Don. P822686)... RS3715	Coolant (To S/N 2016072416) (25MF436)..... BW5179
Air Dryer (Wabco R950011)..... BA5374 +	PC5000D w/Kubota Z482-B Eng	P, PJE, PJK, PUN, PJP, PP, PS w/Renault 720, 797 Eng.
Coolant (23507545)..... BW5137	Lube (96-952-02K)..... B179	Lube Spin-on (5000040870)..... B114
Steering (Nelson 83804E)..... P528	Radial Seal Air (30-724-11K)..... RS3715	O. Air (3564117)..... PA1884 +
XL w/Detroit Series 60 Eng. (1989-2000)	<b>R.V.I. Buses</b>	I. Air (3564115)..... PA1911
Lube (25014505)..... [2] B495	lliade 340, 385	225.4 mm O.D. Some Air (5000243970)..... PA3446
Opt. Fuel/Water Separator	F-F Lube (5000670700)..... B76 +	PH3
Spin-on (w/Drain) (Racor S3202). BF5813 +	B-P Lube Spinner (5000670737). BC110	B-P Lube (944700123)..... P42
Opt. Fuel/Water Separator	Fuel (5000814227)..... BF988 +	PH10-100
Spin-on (Open End for Bowl)	Radial Seal Air (5010230916)..... RS3728	B-P Lube (944700123)..... P42
(Racor S3202)..... BF5813-O +	Steering (1902137)..... P106-HD	PR2 Cruisair w/Detroit Diesel Eng.
P. Fuel (25014274)..... BF5800 +	520, 620	Lube Ele. (3139010)..... P20-HD +
S. Fuel (25014342)..... BF5810	B-P Lube (944700123)..... P42	Fuel (3139661)..... PF902
Air (Nelson 70337-N)..... PA2839	Agora w/MIDR 06.2045 Eng.	492.1 mm O. Air (3563513)..... PA3477
Air Dryer (Wabco R950011)..... BA5374 +	Lube (5010240400)..... B7227	473.1 mm I. Air..... PA2814
Coolant (23507545)..... BW5137	Fuel (To S/N 2016072416) (Mann WK727)..... BF988 +	262.7 mm O. Air (3564024)..... PA1690-FN +
Steering (Nelson 83804E)..... P528	Air (Mann C311256)..... PA3558	314.3 mm Air (3564035)..... PA1681-FN
XLII w/Detroit Series 60 Eng. (1999-2003)	Trans. (Mann H710/1x)..... PT8385	317.5 mm Air (3564049)..... PA1637-FN
Lube (25014505)..... [2] B495	Steering (Mann H601/4)..... P106-HD	PR2A Cruisair w/V800 Eng.
Opt. Fuel/Water Separator	Agora w/MIDS 06.2045 Eng.	F-F Lube Ele. (24568011)..... PT670
Spin-on (w/Drain) (Racor S3202). BF5813 +	F-F Lube (5000670700)..... B76 +	374.7 mm O. Air (3563512)..... PA2405
Opt. Fuel/Water Separator	B-P Lube Spinner (5000670737). BC110	371.5 mm I. Air..... PA2835
Spin-on (Open End for Bowl)	Fuel (5000814227)..... BF988 +	492.1 mm O. Air (3563513)..... PA3477
(Racor S3202)..... BF5813-O +	Steering (1902137)..... P106-HD	473.1 mm I. Air..... PA2814
P. Fuel (25014274)..... BF5800 +	Gearbox Hyd. (5001831431)..... PT8335	PR3, PR3A Cruisair w/Detroit Diesel Eng.
S. Fuel (25014342)..... BF5810	FR1 w/MIDR 06.20.45 Eng.	Lube Ele. (3139010)..... P20-HD +
Air (Nelson 70337-N)..... PA2839	206.4 mm F-F Lube (5000670670)..... B403	Fuel (3139661)..... PF902
Cab Air..... CLN&R	265.1 mm F-F Lube (5000670700)..... B76 +	492.1 mm O. Air (3563513)..... PA3477
Air Dryer (Bendix 107796)..... BA5377	B-P Lube Spinner (5000670737). BC110	473.1 mm I. Air..... PA2814
Coolant (23507545)..... BW5137	123.0 mm Fuel (5000790570)..... BF988 +	262.7 mm O. Air (3564024)..... PA1690-FN +
Steering (Nelson 83804E)..... P528	186.5 mm Fuel (5000133546)..... BF876	314.3 mm Air (3564035)..... PA1681-FN
<b>PROHEAT</b>	O. Air (5000953712)..... PA2945	317.5 mm Air (3564049)..... PA1637-FN
<b>Auxiliary Power Units (APU)</b>	I. Air (3564119)..... PA1893	PR3A w/V800 Eng.
GEN1 w/Kubota Z482 Eng.	Some Air (1993-on) (5010094154)..... PA3558	F-F Lube Ele. (24568011)..... PT670
Lube (Canada) (70000-32050)..... B227	Steering (5000820895)..... P106-HD	374.7 mm O. Air (3563512)..... PA2405
Lube (USA) (70000-15241)..... B179	lliade 300	371.5 mm I. Air (5000802977)..... PA2835
Fuel Ele. (15231-43560)..... PF872	F-F Lube (5000670700)..... B76 +	492.1 mm O. Air (3563513)..... PA3477
In-Line Fuel (Mann WK31/4)..... BF7725	B-P Lube Spinner (5000670737). BC110	473.1 mm I. Air..... PA2814
Air (Don. P524382)..... PA2104	Fuel (5000814227)..... BF988 +	PR10 w/MIDR 06.20.30, MIDS 06.20.30 Eng.
GEN2 w/Kubota Z482 Eng.	Radial Seal Air (5010230916)..... RS3728	Lube Spin-on (5000670670)..... B403
Lube (Canada) (70000-32050)..... B227	Steering (1902137)..... P106-HD	Fuel Spin-on (5000814227)..... BF988 +
Lube (USA) (70000-15241)..... B179	Magnum 400 w/E7-400 ETECH Eng.	O. Air (5000242503)..... PA2474
Fuel Ele. (15231-43560)..... PF872	F-F Lube (485GB3191B)..... B76 +	Some Air (5000242504)..... PA2475
In-Line Fuel (Mann WK31/4)..... BF7725	B-P Lube Spinner (To S/N 2016072416) (57GC2134)..... BC110	PR12, PR14S, PR14SL w/MIDR 06.20.30, MIDS 06.20.30 Eng.
I.C.E. GEN3 w/Kubota Z482-B Eng.	P. Fuel (To S/N 2016072416) (483GB444)..... BF877 +	Lube Spin-on (5000670670)..... B403
Lube (Canada) (70000-32050)..... B227	S. Fuel (To S/N 2016072416) (483GB440)..... BF976	Fuel Spin-on (5000814227)..... BF988 +
Lube (USA) (70000-15241)..... B179	Radial Seal Air (To S/N 2016072416) (5010230841)..... RS3727	O. Air (5000242503)..... PA2474
P. Fuel (15231-43560)..... PF872		Some Air (5000242504)..... PA2475
In-Line Fuel (Mann WK31/4)..... BF7725		
Air (Wix 42434)..... PA30050		
GEN4 w/Kubota Z482-B Eng.		
Lube (Canada) (70000-32050)..... B227		
Lube (USA) (70000-15241)..... B179		
P. Fuel (Canada) (70000-43081)..... BF7683		
P. Fuel (USA) (15221-43081)..... BF940		
In-Line Fuel (Mann WK31/4)..... BF7725		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

R.V.I. Buses (cont'd)	R.V.I. Buses (cont'd)	R.V.I. Buses (cont'd)
PR40S w/MIDR 06.20.30 Eng. Lube Spin-on..... <b>B403</b>	SC10 w/D0846HM8U Eng. Lube Ele..... <b>PT12</b> S. Fuel Ele..... <b>PF834</b>	S105R, S105RX w/D0846HM Eng. Lube Ele. (5000275939)..... <b>PT12</b> Lube Spin-on (5000670670)..... <b>B403</b> P. Fuel Ele. (854806000)..... <b>F953-F</b> S. Fuel..... <b>PF834</b> Can-Type Fuel (7701010100)..... <b>BF825 +</b> O. Air (3564117)..... <b>PA1884 +</b> I. Air (3564115)..... <b>PA1911</b>
PR100, PR100-2 w/MIP 06.20.30, MIDS 06.20.30 Engs. Lube Spin-on (5000670670)..... <b>B403</b> Fuel Spin-on (5000814227)..... <b>BF988 +</b> 374.7 mm O. Air (5000241796).... <b>PA2405</b> 381.0 mm Some Air (5000242503)..... <b>PA2474</b> Coolant (5000663625)..... <b>BW5139</b>	S45 w/Fulger F646 Eng. F-F Lube Ele. (6750492156)..... <b>P7017</b> Lube Spin-on (5000040870)..... <b>B114</b> P. Fuel Ele. (24866064)..... <b>F950-F</b> S. Fuel Ele. (24866092)..... <b>PF950</b>	Tracer w/MIDR 06.20.45 Eng. Lube Spin-on (5000670670)..... <b>B403</b> Fuel Spin-on (To S/N 2016072416) (5000790570)..... <b>BF988 +</b> 398.5 mm O. Air (5010094094).... <b>PA3558</b> 377.8 mm I. Air (Don. P775064)... <b>PA3566</b> 423.9 mm O. Air..... <b>LL2945</b> 406.4 mm I. Air (3564119)..... <b>PA1893</b>
PR100, PR100A, PR100B, PR100L w/Perkins V8-510 Eng. Lube Ele. (3082658)..... <b>PT12</b> Can-Type Fuel (5000243097)..... <b>BF825 +</b> 374.7 mm O. Air (5000241796).... <b>PA2405</b> 371.5 mm Some I. Air (5000802977)..... <b>PA2835</b> 496.9 mm O. Air (5000242504).... <b>PA2475</b>	S45GT w/597 Eng. Lube Spin-on (To S/N 2016072416) (5000040870)..... <b>B114</b> Can-Type Fuel (7701010100)..... <b>BF825 +</b> Some Fuel Ele. (854975700)..... <b>PF7596</b>	Tracer w/MIHR 06.2045 Eng. Lube (5010240400)..... <b>B7227</b> Fuel (Mann WK727)..... <b>BF988 +</b> O. Air (Mann C311310)..... <b>PA2945</b> I. Air (Mann C17149)..... <b>PA1893</b> 398.5 mm Some O. Air (Mann C311256)..... <b>PA3558</b> 377.8 mm Some I. Air (Mann C17124)..... <b>PA3566</b> Trans. (Mann H710/1x)..... <b>PT8385</b> Steering (Mann H601/4)..... <b>P106-HD</b>
PR112, PR118 w/MIPR 06.2045 Eng. Lube (To S/N 2016072416) (5010240400)..... <b>B7227</b> Fuel (To S/N 2016072416) (Mann WK727)..... <b>BF988 +</b> Trans. (To S/N 2016072416) (Mann H710/1x)..... <b>PT8385</b> Steering (To S/N 2016072416) (Mann H601/4)..... <b>P106-HD</b>	S45GT w/D0836, HM4U Engs. F-F Lube (4055040006)..... <b>P235</b> 114.3 mm P. Fuel (8548060)..... <b>F834-F</b> 108.7 mm S. Fuel (8701760)..... <b>PF834</b> 142.9 mm Some P. Fuel Ele. (24866064)..... <b>F950-F</b> 148.4 mm Some S. Fuel Ele. (24866092)..... <b>PF950</b>	TRM2000, TRM4000 Lube Spin-on (5000040870)..... <b>B114</b> Can-Type Fuel (7701010100)..... <b>BF825 +</b> Fuel Spin-on (5000790570)..... <b>BF988 +</b> 419.1 mm Air (TRM2000)..... <b>PA2783</b> 339.7 mm Air (5000243970)..... <b>PA3446</b>
PR180, PR180-2 w/MIP 06.20.30, MIDS 06.20.30 Engs. Lube Spin-on (5000670670)..... <b>B403</b> Fuel Spin-on (5000814227)..... <b>BF988 +</b> 374.7 mm O. Air (5000241796).... <b>PA2405</b> 381.0 mm Some Air (5000242503)..... <b>PA2474</b> Coolant (5000663625)..... <b>BW5139</b>	S45R, S45RX, S53R, S53RX w/D0846HM Eng. Lube Ele. (To S/N 2016072416) (5000275939)..... <b>PT12</b> P. Fuel (854806000)..... <b>F953-F</b> S. Fuel..... <b>PF834</b> O. Air (3564117)..... <b>PA1884 +</b> I. Air (3564115)..... <b>PA1911</b>	TRM2000, TRM4000 Lube Spin-on (5000040870)..... <b>B114</b> Can-Type Fuel (7701010100)..... <b>BF825 +</b> Fuel Spin-on (5000790570)..... <b>BF988 +</b> 419.1 mm Air (TRM2000)..... <b>PA2783</b> 339.7 mm Air (5000243970)..... <b>PA3446</b>
PR180, PR180-2 w/MIP 06.20.30, MIDS 06.20.30 Engs. Lube Spin-on (5000670670)..... <b>B403</b> Fuel Spin-on (5000814227)..... <b>BF988 +</b> 374.7 mm O. Air (5000241796).... <b>PA2405</b> 381.0 mm Some Air (5000242503)..... <b>PA2474</b> Coolant (5000663625)..... <b>BW5139</b>	S53 w/Fulger F646 Eng. F-F Lube Ele. (6750492156)..... <b>P7017</b> Lube Spin-on (5000040870)..... <b>B114</b> P. Fuel Ele. (24866064)..... <b>F950-F</b> S. Fuel Ele. (24866092)..... <b>PF950</b>	T9000, T10000 Lube Spin-on (5000670670)..... <b>B403</b> Fuel Spin-on (5000790570)..... <b>BF988 +</b> 419.1 mm Air (TRM10000) (3564118)..... <b>PA1885 +</b> 381.0 mm Some Air (5000242503)..... <b>PA2474</b> 496.9 mm Some Air (5000242504)..... <b>PA2475</b>
PX30 F-F Lube Ele. (3571013)..... <b>P174</b> Lube Spin-on..... <b>B236 +</b> O. Air (3564110)..... <b>PA2312</b>	S53GT w/597 Eng. Lube Spin-on (5000040870)..... <b>B114</b> Can-Type Fuel (7701010100)..... <b>BF825 +</b> Some Fuel Ele. (854975700)..... <b>PF7596</b>	<b>R.V.I. Engines</b>
R312 w/MIDS 06.20.45 Eng. Lube Spin-on (5000670670)..... <b>B403</b> Fuel Spin-on (5000790570)..... <b>BF988 +</b> 406.4 mm Air (3564119)..... <b>PA1893</b> 423.9 mm Some O. Air (5000953712)..... <b>PA2945</b> 398.5 mm Some O. Air (5010094094)..... <b>PA3558</b>	S53GT, S53M w/D0836, HM4U Engs. F-F Lube (4055040006)..... <b>P235</b> 114.3 mm P. Fuel (8548060)..... <b>F834-F</b> 108.7 mm S. Fuel (8701760)..... <b>PF834</b> 142.9 mm Some P. Fuel Ele. (24866064)..... <b>F950-F</b> 148.4 mm Some S. Fuel Ele. (24866092)..... <b>PF950</b>	dCi4 F-F Lube..... <b>B7227</b> Fuel..... <b>BF7886</b>
Recreo w/MIHR 06.2045 Eng. Lube (To S/N 2016072416) (5010240400)..... <b>B7227</b> Fuel (To S/N 2016072416) (Mann WK727)..... <b>BF988 +</b> Steering (Mann H601/4)..... <b>P106-HD</b>	S105M w/597 Eng. Lube Spin-on (5000040870)..... <b>B114</b> Can-Type Fuel (7701010100)..... <b>BF825 +</b> Some Fuel Ele. (854975700)..... <b>PF7596</b>	dCi 6 F-F Lube..... <b>B76 +</b> B-P Lube..... <b>BC7173</b> Fuel..... <b>BF7886</b>
	S105M w/D0836, HM4U Engs. F-F Lube (4055040006)..... <b>P235</b> 114.3 mm P. Fuel (8548060)..... <b>F834-F</b> 108.7 mm S. Fuel (8701760)..... <b>PF834</b> 142.9 mm Some P. Fuel Ele. (24866064)..... <b>F950-F</b> 148.4 mm Some S. Fuel Ele. (24866092)..... <b>PF950</b>	dC i11 F-F Lube..... <b>B76 +</b> B-P Lube..... <b>BC7173</b> Fuel..... <b>BF7886</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

R.V.I. Engines (cont'd)	R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)
dCi11 F-F Lube..... B76 + B-P Lube..... BC7173 Fuel..... BF7886	SG5 w/597, 797 Engs. Lube Ele. (6750492156)..... P7017 Lube Spin-on (5000040870)..... B114 Air..... PA3446	JP7 Lube..... B2 + Lube (Upgrade)..... B2-HPG
MIDR 04 F-F Lube..... B7227 Fuel..... BF988 +	SG5, SG5C w/720 Eng. Lube Spin-on (5000040870)..... B114	S7 w/Perkins 6.354 Eng. F-F Lube Ele. (24867468)..... PT12 Lube Spin-on..... BT237
MIDR 06 F-F Lube..... B76 + B-P Lube..... BC7173 B-P Lube..... BC110 Fuel..... BF988 + Fuel..... BF7886	SG5C w/597, 817 Engs. Lube Spin-on (5000044959)..... B114	SM7 w/597, 797 Engs. Lube Spin-on (5000040870)..... B114 Can-Type Fuel (7701010100)..... BF825 + Air..... PA3446
<b>R.V.I. Trucks</b>	SM5 w/580, 591, 712 Engs. Lube Spin-on (5000040870)..... B114 Fuel Ele..... PF7596	SM7 w/798 Eng. Lube Spin-on (5000040870)..... B114
SG1 w/Indenor Eng. F-F Lube Spin-on..... B195 Fuel (5000241250)..... PF7596	SM5 w/720 Eng. Lube Spin-on (5000040870)..... B114	PLB8, PLR8 w/640 Eng. B-P Lube (944700123)..... P42
SB2 w/580, 591, 712 Engs. Lube Spin-on (5000040870)..... B114 Some Fuel Ele..... PF7596	TLB5-19 B-P Lube (944700122)..... P41 Fuel Ele. (24866092)..... PF950	GLR8 w/640 Eng. B-P Lube (944700123)..... P42
SB2 w/597, 817 Engs. Lube Spin-on (5000044959)..... B114	DCI 6 w/6 Cyl. 6.2L 12 Valve Eng. Lube (5000670700)..... B76 +	S8 w/Perkins 6.354 Eng. F-F Lube Ele. (24867468)..... PT12 Lube Spin-on..... BT237
SG2, SG3 w/580, 591, 597, 599, 720, 797, 817 Engs. F-F Lube Spin-on (24151017)..... B114 Fuel Ele. (5000241250)..... PF7596	GLC6 B-P Lube (944700122)..... P41 Fuel Ele. (24866092)..... PF950	SM8 w/597, 797 Engs. Lube Ele. (6750492156)..... P7017 Lube Spin-on (5000040870)..... B114 Air..... PA3446
TP3 Lube Spin-on (5000040870)..... B114 Fuel Spin-on (5000790570)..... BF988 +	PLB6 B-P Lube (944700122)..... P41 Fuel Ele. (24866092)..... PF950	SM8 w/798 Eng. Lube Spin-on (5000040870)..... B114
SG4 w/580, 591, 597, 599, 720, 797, 817 Engs. F-F Lube Spin-on (24151017)..... B114 Fuel Ele. (5000241250)..... PF7596	S6 w/Perkins 6.354 Eng. F-F Lube Ele. (24867468)..... PT12 Lube Spin-on..... BT237	SM8T w/597, 797 Engs. Lube Spin-on (5000040870)..... B114 Can-Type Fuel (7701010100)..... BF825 + Air..... PA3446
5F, 5R Lube Ele. (944700122)..... P41 Fuel Ele. (24866092)..... PF950	SC6 w/597 Eng. Lube Ele. (6750492156)..... P7017 Lube Spin-on (5000040870)..... B114	SM8T Lube Spin-on (5000040870)..... B114 Fuel Ele. (3005121)..... PF838
GAF5, GAK5 B-P Lube Ele. (944700122)..... P41 Fuel Ele. (24866092)..... PF950	SC6P F-F Lube Ele. (4083040016)..... PT12 Lube Ele. (6750492156)..... P7017	JE9 w/060212 Eng. 134.1 mm Lube (5000040870)..... B114 206.4 mm Lube (5000670670)..... B403 Fuel (5000814227)..... BF988 + Coolant (5000663625)..... BW5139
GLA5-19, GLB5-19 B-P Lube (944700122)..... P41 Fuel Ele. (24866092)..... PF950	SM6 w/597, 797 Engs. Lube Spin-on (5000040870)..... B114 Can-Type Fuel (7701010100)..... BF825 + Air..... PA3446	S9 w/Fulger Eng. Lube (6750492156)..... P7017
PLA5-19 B-P Lube (944700122)..... P41 Fuel Ele. (24866092)..... PF950	SM6B w/798 Eng. Lube Spin-on (5000040870)..... B114	GBM10, GFK10, GLM10 w/640 Eng. B-P Lube (944700123)..... P42
SC5P F-F Lube Ele. (4083040016)..... PT12 Lube Ele. (6750492156)..... P7017	E7C, E7N w/M.A.N. 2156 HM5F, R.V.I. 597 Engs. Lube Ele. (4055040006)..... P235 Lube Spin-on (5000040870)..... B114 P. Fuel Ele. (24866064)..... F950-F S. Fuel Ele. (24866092)..... PF950	PLRC10H w/640 Eng. B-P Lube (944700123)..... P42
SG5 w/580, 591, 599, 817 Engs. F-F Lube Spin-on (24151017)..... B114 Fuel Ele. (5000241250)..... PF7596	E7N w/M.A.N. 2156 HM5F Eng. Lube Ele. (4055040006)..... P235 P. Fuel Ele. (24866064)..... F950-F S. Fuel Ele. (24866092)..... PF950	SC10 w/M.A.N. D0836HM8U Eng. F-F Lube Ele. (4055040006)..... P235 P. Fuel (854806000)..... F953-F S. Fuel (870176000)..... PF834

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

**Trucks & Buses Applications** **BALDWIN FILTERS**

R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)
SM10S w/M.A.N. Eng. Lube Ele. .... P235 S. Fuel Ele. .... PF231	TBH12 w/M635CD Eng. Lube Spin-on (5000670670)..... B403 O. Air ..... LL1884 + I. Air ..... PA1911	HF15B w/06.20.30 Eng. Lube (5000670670)..... B403 Can-Type Fuel (7701010100)..... BF825 +
TLR10 w/640 Eng. B-P Lube (944700123)..... P42	TF12 w/640 Eng. B-P Lube (944700123)..... P42	HM15 w/M.A.N. D2565 Eng. 188.1 mm Lube Ele. (5000242510)..... P242 264.3 mm Lube Ele. (5000243098)..... P294 P. Fuel Ele. (24866064)..... F950-F S. Fuel Ele. (24866092)..... PF950
TP10C, TP10N Lube (24151104)..... P7017	TF12 B-P Lube (944700122)..... P41 Fuel Ele. (24866092)..... PF950	HR15 w/798 Eng. Lube Spin-on (5000040870)..... B114 Can-Type Fuel (7701010100)..... BF825 +
DCI II w/6 Cyl. 11.0L, 12 Valve Eng. Lube (5000670700)..... [2] B76 + Fuel (5010412350)..... [2] BF7886	TLM12, TLM12S Lube Spin-on (5000670670)..... B403 O. Air ..... LL1884 + I. Air (3564115)..... PA1911	HR15 w/797 Eng. Lube Spin-on (5000040870)..... B114 Can-Type Fuel (7701010100)..... BF825 + Fuel Ele. (854975700)..... PF7596
JE11 w/060212 Eng. 134.1 mm Lube (5000040870)..... B114 206.4 mm Lube (5000670670)..... B403 Fuel (5000814227)..... BF988 + Coolant (5000663625)..... BW5139	TLR12 w/640 Eng. B-P Lube (944700123)..... P42	PLRC15 w/640 Eng. B-P Lube (944700123)..... P42
JP11 w/Renault Eng. 134.1 mm Lube (5000040870)..... B114 206.4 mm Lube (5000670670)..... B403 Fuel (5000814227)..... BF988 + 296.9 mm Air (5000809894)..... PA2865 339.7 mm Air (5000243970)..... PA3446	TR12 B-P Lube (944700122)..... P41 Fuel Ele. (24866092)..... PF950	TLM15 w/640 Eng. B-P Lube (944700123)..... P42
JP11 w/797 Eng. Lube Spin-on (5000044064)..... B114 Can-Type Fuel (5000243097)..... BF825 + 296.9 mm Air (Mann C21461)..... PA2865 339.7 mm Air (Mann C19377)..... PA3446	JE13 w/060212 Eng. 134.1 mm Lube (5000040870)..... B114 206.4 mm Lube (5000670670)..... B403 Fuel (5000814227)..... BF988 + Coolant (5000663625)..... BW5139	S16 w/580, 591, 671 Eng. Fuel Ele. (5000241676)..... PF7596
GF12 w/640 Eng. B-P Lube (944700123)..... P42	JP13A, JP13B w/Renault Eng. 134.1 mm Lube (5000040870)..... B114 206.4 mm Lube (5000670670)..... B403 Fuel Can-Type ..... BF825 + Fuel Spin-on (5000814227)..... BF988 + 296.9 mm Air (5000809894)..... PA2865 339.7 mm Air (5000243970)..... PA3446	HB17, HB17B w/MID 06.20.30, MIDS 06.20.30 Eng. Lube (5000670670)..... B403 Can-Type Fuel (7701010100)..... BF825 +
GF12 B-P Lube (944700122)..... P41 Fuel Ele. (24866092)..... PF950	JP13B, JP13C w/Saviem 798 Eng. Lube ..... B7156 Can-Type Fuel ..... BF825 + 225.4 mm O.D. Air ..... PA3446	HF17, HF17B, HF17C w/06.20.30 Eng. Lube (5000670670)..... B403 Can-Type Fuel (7701010100)..... BF825 +
GLM12 (4x2), GLM12S (6x4) w/MD 06.35.40 Eng. Lube (5000670670)..... B403 Air (3564117)..... PA1884 + Some Air (3564115)..... PA1911	JP13C, JP14 w/Renault Eng. 134.1 mm Lube (5000040870)..... B114 206.4 mm Lube (5000670670)..... B403 Fuel (5000814227)..... BF988 + 296.9 mm Air (5000809894)..... PA2865 339.7 mm Air (5000243970)..... PA3446	HM17, HM17B w/M.A.N. D2565 Eng. 188.1 mm Lube Ele. (5000242510)..... P242 264.3 mm Lube Ele. (5000243098)..... P294 P. Fuel Ele. (24866064)..... F950-F S. Fuel Ele. (24866092)..... PF950
GR12 B-P Lube (944700122)..... P41 Fuel Ele. (24866092)..... PF950	TR14 Lube (5000670670)..... B403 O. Air (5000783932)..... PA2474 I. Air (5000802978)..... PA2836	HM17 w/798 Eng. Lube Spin-on (5000040870)..... B114 Can-Type Fuel (7701010100)..... BF825 +
JP12 Lube ..... B2 + Lube (Upgrade)..... B2-HPG	15.215 Lube (4055040006)..... P235 P. Fuel Ele. (24866064)..... F950-F S. Fuel Ele. (24866092)..... PF950	HN17 w/M.A.N. D2565, D2566 Eng. Lube Ele. (5000243098)..... P294 P. Fuel Ele. (24866064)..... F950-F S. Fuel Ele. (24866092)..... PF950
PMH12 (6x4) w/M635CD Eng. Lube Spin-on (5000670670)..... B403 O. Air (3564117)..... PA1884 + Some I. Air (3564115)..... PA1911	GMO15 w/640 Eng. B-P Lube (944700123)..... P42	TLC18 w/640 Eng. B-P Lube (944700123)..... P42
SM12 w/M.A.N. D0836HMN Eng. F-F Lube Ele. (4055040006)..... P235 P. Fuel (854806000)..... F953-F S. Fuel (870176000)..... PF834	HB15 w/MID 06.20.30, MIDS 06.20.30 Eng. Lube (5000670670)..... B403 Can-Type Fuel (7701010100)..... BF825 +	HB19B w/MID 06.20.30, MIDS 06.20.30 Eng. Lube (5000670670)..... B403 Can-Type Fuel (7701010100)..... BF825 +
SM12S w/M.A.N. Eng. Lube Ele. (Sakura O6201)..... P235 S. Fuel Ele. .... PF231		HF19 w/06.20.30 Eng. Lube (5000670670)..... B403 Can-Type Fuel (7701010100)..... BF825 +

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)
HM19, HM19B w/M.A.N. D2565 Eng. <b>188.1 mm Lube Ele.</b> (5000242510)..... <b>P242</b> <b>264.3 mm Lube Ele.</b> (5000243098)..... <b>P294</b> <b>P. Fuel Ele.</b> (24866064)..... <b>F950-F</b> <b>S. Fuel Ele.</b> (24866092)..... <b>PF950</b>	JL21 w/Fulger Eng. <b>136.5 mm Lube Ele.</b> (6750492156)..... <b>P7017</b> <b>198.4 mm Lube Ele.</b> (4055040004)..... <b>P235</b> <b>P. Fuel</b> (854806000)..... <b>F953-F</b> <b>S. Fuel</b> (24152005)..... <b>PF834</b> <b>Single Fuel Ele.</b> (3005821)..... <b>PF838</b>	HM26, HM26B, HM26T w/M.A.N. D2565 Eng. <b>188.1 mm Lube Ele.</b> (5000242510)..... <b>P242</b> <b>264.3 mm Lube Ele.</b> (5000243098)..... <b>P294</b> <b>P. Fuel Ele.</b> (24866064)..... <b>F950-F</b> <b>S. Fuel Ele.</b> (24866092)..... <b>PF950</b>
HM19 w/798 Eng. <b>Lube Spin-on</b> (5000040870)..... <b>B114</b> <b>Can-Type Fuel</b> (7701010100)..... <b>BF825 +</b>	JP21 <b>Lube Spin-on</b> (5000044064)..... <b>B114</b> <b>Can-Type Fuel</b> (5000243097)..... <b>BF825 +</b>	HM26 w/798 Eng. <b>Lube Spin-on</b> (5000040870)..... <b>B114</b> <b>Can-Type Fuel</b> (7701010100)..... <b>BF825 +</b>
HN19 w/M.A.N. D2565, D2566 Eng. <b>Lube Ele.</b> (5000243098)..... <b>P294</b> <b>P. Fuel Ele.</b> (24866064)..... <b>F950-F</b> <b>S. Fuel Ele.</b> (24866092)..... <b>PF950</b>	JR21 w/Saviem 798 Eng. <b>Can-Type Fuel</b> ..... <b>BF825 +</b> <b>225.4 mm O.D. Air</b> ..... <b>PA3446</b>	HN26T Series w/M.A.N. D2565, D2566 Eng. <b>Lube Ele.</b> (5000243098)..... <b>P294</b> <b>P. Fuel Ele.</b> (24866064)..... <b>F950-F</b> <b>S. Fuel Ele.</b> (24866092)..... <b>PF950</b>
J19 <b>F-F Lube Ele.</b> (3661840225)..... <b>P7017</b> <b>Lube Spin-on</b> (5000040870)..... <b>B114</b> <b>Can-Type Fuel</b> (7701010100)..... <b>BF825 +</b> <b>Air</b> (5000243970)..... <b>PA3446</b>	JR21A, JR21B, JR21C w/Saviem Eng. <b>Lube Spin-on</b> ..... <b>B114</b> <b>Can-Type Fuel</b> ..... <b>BF825 +</b>	HL28 <b>Lube Ele.</b> (5000243098)..... <b>P294</b> <b>Lube Spin-on</b> (24564103)..... <b>B403</b> <b>P. Fuel</b> (854806000)..... <b>F953-F</b> <b>S. Fuel</b> (870465700)..... <b>PF834</b>
JL19 w/Fulger Eng. <b>136.5 mm Lube Ele.</b> (6750492156)..... <b>P7017</b> <b>198.4 mm Lube Ele.</b> (4055040004)..... <b>P235</b> <b>P. Fuel</b> (854806000)..... <b>F953-F</b> <b>S. Fuel</b> (24152005)..... <b>PF834</b> <b>Single Fuel Ele.</b> (3005821)..... <b>PF838</b>	JR21A, JR21B, JR21C w/798, MIDR 06.02.12 Eng. <b>Lube Spin-on</b> (5000040870)..... <b>B114</b> <b>339.7 mm Air</b> (5000243970)..... <b>PA3446</b>	JL28 w/Fulger Eng. <b>198.4 mm Lube Ele.</b> (4055040004)..... <b>P235</b> <b>136.5 mm Lube Ele.</b> (6750492156)..... <b>P7017</b> <b>P. Fuel</b> (854806000)..... <b>F953-F</b> <b>S. Fuel</b> (24152005)..... <b>PF834</b> <b>Single Fuel Ele.</b> (3005821)..... <b>PF838</b>
JR19 w/Saviem 798 Eng. <b>Can-Type Fuel</b> ..... <b>BF825 +</b> <b>225.4 mm O.D. Air</b> ..... <b>PA3446</b>	JX21AT, JX21BT, JX21CT w/797 Eng. <b>Lube Spin-on</b> ..... <b>B114</b> <b>339.7 mm Air</b> (5000243970)..... <b>PA3446</b>	PX28 <b>Can-Type Fuel</b> (7701028181)..... <b>BF884</b>
JR19A, JR19B w/798, MIDR 06.02.12 Eng. <b>Lube Spin-on</b> (5000040870)..... <b>B114</b> <b>339.7 mm Air</b> (5000243970)..... <b>PA3446</b>	SM21, SM21-180 w/M.A.N. Eng. <b>Lube Ele.</b> (4083040018)..... <b>P235</b> <b>P. Fuel Ele.</b> (24866064)..... <b>F950-F</b> <b>S. Fuel Ele.</b> (24866092)..... <b>PF950</b>	S28 <b>Lube Ele.</b> (4083040016)..... <b>PT12</b> <b>P. Fuel</b> (854806000)..... <b>F953-F</b> <b>S. Fuel</b> (870176000)..... <b>PF834</b> <b>Can-Type Fuel</b> (7701010100)..... <b>BF825 +</b>
JL20 w/Fulger Eng. <b>136.5 mm Lube Ele.</b> (6750492156)..... <b>P7017</b> <b>198.4 mm Lube Ele.</b> (4055040004)..... <b>P235</b> <b>P. Fuel</b> (854806000)..... <b>F953-F</b> <b>S. Fuel</b> (24152005)..... <b>PF834</b> <b>Single Fuel Ele.</b> (3005821)..... <b>PF838</b>	SM21-180 w/M.A.N. D0846HMN Eng. <b>Lube Ele.</b> (5000273542)..... <b>P235</b> <b>P. Fuel</b> (854806000)..... <b>F953-F</b> <b>S. Fuel</b> (870176000)..... <b>PF834</b>	S28 <b>Lube Ele.</b> (4083040016)..... <b>PT12</b> <b>P. Fuel</b> (854806000)..... <b>F953-F</b> <b>S. Fuel</b> (870176000)..... <b>PF834</b> <b>Can-Type Fuel</b> (7701010100)..... <b>BF825 +</b>
JL20 w/Henschel 520D6T Eng. <b>Lube Ele.</b> (4083040018)..... <b>P235</b> <b>P. Fuel Ele.</b> (24866064)..... <b>F950-F</b> <b>S. Fuel Ele.</b> (24866092)..... <b>PF950</b>	JL23 w/Fulger Eng. <b>F-F Lube Ele.</b> (4055040004)..... <b>P235</b> <b>F-F Lube Ele.</b> (6750492156)..... <b>P7017</b> <b>P. Fuel</b> (854806000)..... <b>F953-F</b> <b>S. Fuel</b> (24152005)..... <b>PF834</b> <b>Single Fuel Ele.</b> (3005821)..... <b>PF838</b>	JL29 w/Fulger Eng. <b>136.5 mm Lube Ele.</b> (6750492156)..... <b>P7017</b> <b>198.4 mm Lube Ele.</b> (4055040004)..... <b>P235</b> <b>P. Fuel</b> (854806000)..... <b>F953-F</b> <b>S. Fuel</b> (24152005)..... <b>PF834</b> <b>Single Fuel Ele.</b> (3005821)..... <b>PF838</b>
JL20 <b>F-F Lube Ele.</b> ..... <b>P7017</b> <b>Lube Spin-on</b> (5000040870)..... <b>B114</b> <b>Can-Type Fuel</b> (7701010100)..... <b>BF825 +</b> <b>Air</b> (5000243970)..... <b>PA3446</b>	S24 w/580, 591, 671 Eng. <b>Fuel Ele.</b> (5000241676)..... <b>PF7596</b>	PR30, PS30T w/M.A.N. D2566 Eng. <b>F-F Lube</b> (5000243098)..... <b>P294</b> <b>P. Fuel Ele.</b> (24866064)..... <b>F950-F</b> <b>S. Fuel Ele.</b> ..... <b>PF231</b>
21.215 <b>Lube</b> (4055040006)..... <b>P235</b> <b>P. Fuel Ele.</b> (24866064)..... <b>F950-F</b> <b>S. Fuel Ele.</b> (24866092)..... <b>PF950</b>	JL25 w/Fulger Eng. <b>F-F Lube Ele.</b> (4055040004)..... <b>P235</b> <b>F-F Lube Ele.</b> (6750492156)..... <b>P7017</b> <b>P. Fuel</b> (854806000)..... <b>F953-F</b> <b>S. Fuel</b> (24152005)..... <b>PF834</b> <b>Fuel Ele.</b> (3005821)..... <b>PF838</b>	PX30, PX30T <b>F-F Lube Ele.</b> ..... <b>P174</b> <b>Lube Spin-on</b> ..... <b>B403</b> <b>Can-Type Fuel</b> (7701028181)..... <b>BF884</b> <b>O. Air</b> (3564110)..... <b>PA2312</b>
	HB26, HB26B, HB26BT, HB26CT, HB26ET, HB26T w/MID 06.20.30, MIDS 06.20.30 Eng. <b>Lube</b> (5000670670)..... <b>B403</b> <b>Can-Type Fuel</b> (7701010100)..... <b>BF825 +</b>	JL32 w/Henschel 520D6T Eng. <b>Lube</b> (4083040018)..... <b>P235</b> <b>P. Fuel Ele.</b> (24866064)..... <b>F950-F</b> <b>S. Fuel Ele.</b> (24866092)..... <b>PF950</b>
	HF26V, HF26VR <b>Can-Type Fuel</b> (7701010100)..... <b>BF825 +</b> <b>O. Air</b> (5000242503)..... <b>PA2474</b> <b>I. Air</b> (5000802978)..... <b>PA2836</b>	

\* See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)
SM36-280 w/M.A.N. D214HM, D2146HM3 Engs. Lube (4083040018)..... P235 P. Fuel Ele. (24866064)..... F950-F S. Fuel Ele. (24866092)..... PF950 Fuel Spin-on (5000814227)..... BF988 +	JK60A, JK60B w/720 Eng. (Cont'd) 296.9 mm Air (5000809894)..... PA2865	JN80 w/797 Eng. Lube Spin-on (5000040870)..... B114 Can-Type Fuel (7701010100)..... BF825 + Fuel Spin-on (5000814227)..... BF988 + 339.7 mm Air (5000243970)..... PA3446
E37 w/M.A.N. 2156 HM5F, R.V.I. 597 Engs. Lube Ele. (4055040006)..... P235 Lube Spin-on (5000040870)..... B114 P. Fuel Ele. (24866064)..... F950-F S. Fuel Ele. (24866092)..... PF950	JN60, JN60A w/797 Eng. Lube Spin-on (5000040870)..... B114 Can-Type Fuel (7701010100)..... BF825 + Fuel Spin-on (5000814227)..... BF988 + 339.7 mm Air (5000243970)..... PA3446	E85 w/M.A.N. 2156 HM5F, R.V.I. 597 Engs. Lube Ele. (4055040006)..... P235 Lube Spin-on (5000040870)..... B114 P. Fuel Ele. (24866064)..... F950-F S. Fuel Ele. (24866092)..... PF950
HL38, HL38T w/M.A.N. D2566 Eng. Lube (5000243098)..... P294 P. Fuel Ele. (24866064)..... F950-F S. Fuel Ele. (24866092)..... PF231	65 Lube Ele. (944700122)..... P41 Fuel Ele. (24866092)..... PF950	JN85 w/720 Eng. Lube Spin-on..... B114 Fuel Spin-on..... BF988 + 225.4 mm O.D. Air (5000243970)..... PA3446
SM38-820 w/M.A.N. D214HM, D2146HM3 Engs. Lube (4083040018)..... P235 P. Fuel Ele. (24866064)..... F950-F S. Fuel Ele. (24866092)..... PF950 Fuel Spin-on (5000814227)..... BF988 +	JK65 w/720 Eng. Lube Spin-on (5000040870)..... B114 Can-Type Fuel..... BF825 + Fuel Spin-on (5000814227)..... BF988 + 296.9 mm Air (5000809894)..... PA2865	JN85 w/797 Eng. Lube..... B114 Can-Type Fuel..... BF825 + Air..... PA3446
PX40 O. Air..... PA2398	JP65 Lube Spin-on (5000044064)..... B114 Can-Type Fuel (5000243097)..... BF825 +	SM89TM w/597, 797 Engs. Lube Spin-on (5000040870)..... B114 Can-Type Fuel (7701010100)..... BF825 + Air..... PA3446
E45 w/M.A.N. 2156 HM5F, R.V.I. 597 Engs. Lube Ele. (4055040006)..... P235 Lube Spin-on (5000040870)..... B114 P. Fuel Ele. (24866064)..... F950-F S. Fuel Ele. (24866092)..... PF950	L68-8RA w/M520 Eng. Fuel (941718018)..... BF719	B90 w/SOFIM 8140 Eng. Lube (To 3/86)..... BT5 Dual-Flow Lube (5000816070).... BD232 Fuel Ele. (5000241250)..... PF7596 Fuel Spin-on..... BF988 + Fuel/Water Separator..... BF1276 Steering (Iveco 1902137)..... P106-HD
SG45GT w/597 Eng. Fuel Ele. .... PF7596	B70 w/SOFIM 8140 Eng. Lube (To 3/86)..... BT5 Dual-Flow Lube (5000816070).... BD232 Fuel Ele. (5000241250)..... PF7596 Fuel Spin-on..... BF988 + Fuel/Water Separator..... BF1276 Steering (Iveco 1902137)..... P106-HD	JN90 w/797 Eng. Lube Spin-on..... B114 Can-Type Fuel..... BF825 + Fuel Spin-on..... BF988 + 339.7 mm Air (5000243970)..... PA3446
50 Lube Ele. (944700122)..... P41 Fuel Ele. (24866092)..... PF950	JK75 w/720 Eng. Lube Spin-on (5000040870)..... B114 Can-Type Fuel..... BF825 + Fuel Spin-on (5000814227)..... BF988 + 296.9 mm Air (5000809894)..... PA2865	JP90 Lube Spin-on (5000044064)..... B114 Can-Type Fuel (5000243097)..... BF825 +
GAK50 w/Perkins 6.288 Eng. 119.1 mm Lube Ele. (3082658).... PT12 141.3 mm Lube Ele. (943235102)..... P174 Lube Spin-on..... BT215 Can-Type Fuel (855589600)..... [2] BF825 +	JN75 w/720 Eng. Lube Spin-on..... B114 Fuel Spin-on..... BF988 + 225.4 mm O.D. Air (5000243970)..... PA3446	S90 w/Renault Eng. 134.1 mm Lube Spin-on (5000040870)..... B114 206.4 mm Lube Spin-on (5000670670)..... B403 Can-Type Fuel (7701010100)..... BF825 + Fuel Spin-on (5000790570)..... BF988 + 296.9 mm Air (5000809894)..... PA2865 339.7 mm Air (5000243970)..... PA3446 Some I. Air (3564106)..... PA2419
JK50 Fuel (5000814227)..... BF988 +	JN75 w/797 Eng. Lube..... B114 Can-Type Fuel..... BF825 + Air..... PA3446	JN95 w/797 Eng. Lube Spin-on..... B114 Can-Type Fuel..... BF825 + Fuel Spin-on..... BF988 + 339.7 mm Air (5000243970)..... PA3446
S53M w/597 Eng. Fuel Ele. .... PF7596	JP75 Lube Spin-on (5000044064)..... B114 Can-Type Fuel (5000243097)..... BF825 +	
JK55 Fuel (5000814227)..... BF988 +	B80 w/SOFIM 8140 Eng. Lube (To 3/86)..... BT5 Dual-Flow Lube (5000816070).... BD232 Fuel Ele. (5000241250)..... PF7596 Fuel Spin-on..... BF988 + Fuel/Water Separator..... BF1276 Steering (Iveco 1902137)..... P106-HD	
60 Lube Ele. (944700122)..... P41 Fuel Ele. (24866092)..... PF950	GBK80 Can-Type Fuel (7701010100)..... BF825 + Fuel Spin-on (3036404)..... BF797	
JK60 Lube Spin-on (5000044064)..... B114 Can-Type Fuel (5000243097)..... BF825 +		
JK60A, JK60B w/720 Eng. Lube Spin-on (5000040870)..... B114 Can-Type Fuel..... BF825 + Fuel Spin-on (5000814227)..... BF988 +		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)
S100 w/Perkins Eng. Lube Spin-on (5000040870)..... <b>B114</b> Can-Type Fuel (7701010100)..... <b>BF825+</b> 296.9 mm Air (5000809894)..... <b>PA2865</b> 339.7 mm Air (5000243970)..... <b>PA3446</b> Some I. Air (3564106)..... <b>PA2419</b>	Midlum 135.07 w/MIDR 04.02.26 Eng. (02/00-12/01) Lube (Mann W1160/2)..... <b>B7227</b> Opt. Fuel/Water Separator (Racor Hsg.) (Racor 2010PM)..... <b>PF598-30</b> Fuel (Mann WK727)..... <b>BF988+</b> Opt. Fuel/Water Separator (R.V.I. Hsg.) (5000790559)..... <b>CLN&amp;R</b> Single Air (Mann C23440/1)..... <b>PA2474</b> Radial Seal O. Air..... <b>RS3727</b> Radial Seal O. Air (w/FRM) (5001865723)..... <b>RS5390</b> Radial Seal I. Air (5010317187)... <b>RS5351</b> 161.9 mm Air Dryer (Mann TB1374/3X)..... <b>BA5375</b> 167.5 mm Air Dryer (Mann TB1374X)..... <b>BA5374+</b> Trans. (w/ZF Ecosplit Gearbox) (ZF 750131003)..... <b>PT8385</b> Steering..... <b>P106-HD</b>	Midlum 135.09 w/MIDR 04.02.26 Eng. (02/00-12/01) (Cont'd) 161.9 mm Air Dryer (Mann TB1374/3X)..... <b>BA5375</b> 167.5 mm Air Dryer (Mann TB1374X)..... <b>BA5374+</b> Trans. (w/ZF Ecosplit Gearbox) (ZF 750131003)..... <b>PT8385</b> Steering..... <b>P106-HD</b>
S105M w/M.A.N. D0836HM4U Eng. F-F Lube Ele. (4055040006)..... <b>P235</b> F-F Lube Spin-on (5000040870)..... <b>B114</b> P. Fuel Ele. (854806000)..... <b>F953-F</b> S. Fuel Ele. (875492156)..... <b>PF834</b> Some Can-Type P. Fuel..... <b>BF825+</b> Some S. Fuel Ele..... <b>PF7596</b>	Midlum 135.10 w/MIDR 04.02.26 Eng. (02/00-12/01) Lube (Mann W1160/2)..... <b>B7227</b> Opt. Fuel/Water Separator (Racor Hsg.) (Racor 2010PM)..... <b>PF598-30</b> Fuel (Mann WK727)..... <b>BF988+</b> Opt. Fuel/Water Separator (R.V.I. Hsg.) (5000790559)..... <b>CLN&amp;R</b> Single Air (Mann C23440/1)..... <b>PA2474</b> Radial Seal O. Air..... <b>RS3727</b> Radial Seal O. Air (w/FRM) (5001865723)..... <b>RS5390</b> Radial Seal I. Air (5010317187)... <b>RS5351</b> 161.9 mm Air Dryer (Mann TB1374/3X)..... <b>BA5375</b> 167.5 mm Air Dryer (Mann TB1374X)..... <b>BA5374+</b> Trans. (w/ZF Ecosplit Gearbox) (ZF 750131003)..... <b>PT8385</b> Steering..... <b>P106-HD</b>	Midlum 135.10 w/MIDR 04.02.26 Eng. (02/00-12/01) Lube (Mann W1160/2)..... <b>B7227</b> Opt. Fuel/Water Separator (Racor Hsg.) (Racor 2010PM)..... <b>PF598-30</b> Fuel (Mann WK727)..... <b>BF988+</b> Opt. Fuel/Water Separator (R.V.I. Hsg.) (5000790559)..... <b>CLN&amp;R</b> Single Air (Mann C23440/1)..... <b>PA2474</b> Radial Seal O. Air..... <b>RS3727</b> Radial Seal O. Air (w/FRM) (5001865723)..... <b>RS5390</b> Radial Seal I. Air (5010317187)... <b>RS5351</b> 161.9 mm Air Dryer (Mann TB1374/3X)..... <b>BA5375</b> 167.5 mm Air Dryer (Mann TB1374X)..... <b>BA5374+</b> Trans. (w/ZF Ecosplit Gearbox) (ZF 750131003)..... <b>PT8385</b> Steering..... <b>P106-HD</b>
S105M w/597 Eng. Fuel Ele..... <b>PF7596</b>	Midlum 135.08 w/MIDR 04.02.26 Eng. (02/00-12/01) Lube (Mann W1160/2)..... <b>B7227</b> Opt. Fuel/Water Separator (Racor Hsg.) (Racor 2010PM)..... <b>PF598-30</b> Fuel (Mann WK727)..... <b>BF988+</b> Opt. Fuel/Water Separator (R.V.I. Hsg.) (5000790559)..... <b>CLN&amp;R</b> Single Air (Mann C23440/1)..... <b>PA2474</b> Radial Seal O. Air..... <b>RS3727</b> Radial Seal O. Air (w/FRM) (5001865723)..... <b>RS5390</b> Radial Seal I. Air (5010317187)... <b>RS5351</b> 161.9 mm Air Dryer (Mann TB1374/3X)..... <b>BA5375</b> 167.5 mm Air Dryer (Mann TB1374X)..... <b>BA5374+</b> Trans. (w/ZF Ecosplit Gearbox) (ZF 750131003)..... <b>PT8385</b> Steering..... <b>P106-HD</b>	M140 w/MIDR 06.02.26, MIDS 06.02.12 Eng. Lube (5000670700)..... <b>B76+</b> Fuel Spin-on (5000686589)..... <b>BF988+</b> 381.0 mm O. Air (5000242503)... <b>PA2474</b> 388.9 mm O. Air (5010094146)... <b>PA3699</b> 377.8 mm Some I. Air (5010094145)..... <b>PA3566</b> Steering (5000820895)..... <b>P106-HD</b>
B110 Messenger w/SOFIM 8140 Eng. Dual-Flow Lube (5000816070)... <b>BD232</b> Fuel Spin-on..... <b>BF988+</b> Air (3563565)..... <b>PA2845</b> Steering (Iveco 1902137)..... <b>P106-HD</b>	S1130.08 Midliner w/MIDR 04.0226 Eng. Lube (5010240400)..... <b>B7227</b> Fuel (Mann WK727)..... <b>BF988+</b> Steering (Mann H601/4)..... <b>P106-HD</b>	M140 w/MIDR 06.02.26, MIDS 06.02.12 Eng. Lube (5000670700)..... <b>B76+</b> Fuel Spin-on (5000686589)..... <b>BF988+</b> 381.0 mm O. Air (5000242503)... <b>PA2474</b> 388.9 mm O. Air (5010094146)... <b>PA3699</b> 377.8 mm Some I. Air (5010094145)..... <b>PA3566</b> Steering (5000820895)..... <b>P106-HD</b>
E110 w/M.A.N. 2156 HM5F, R.V.I. 597 Eng. Lube Ele. (4055040006)..... <b>P235</b> Lube Spin-on (5000040870)..... <b>B114</b> P. Fuel Ele. (24866064)..... <b>F950-F</b> S. Fuel Ele. (24866092)..... <b>PF950</b>	Midlum 135.08 w/MIDR 04.02.26 Eng. (02/00-12/01) Lube (Mann W1160/2)..... <b>B7227</b> Opt. Fuel/Water Separator (Racor Hsg.) (Racor 2010PM)..... <b>PF598-30</b> Fuel (Mann WK727)..... <b>BF988+</b> Opt. Fuel/Water Separator (R.V.I. Hsg.) (5000790559)..... <b>CLN&amp;R</b> Single Air (Mann C23440/1)..... <b>PA2474</b> Radial Seal O. Air..... <b>RS3727</b> Radial Seal O. Air (w/FRM) (5001865723)..... <b>RS5390</b> Radial Seal I. Air (5010317187)... <b>RS5351</b> 161.9 mm Air Dryer (Mann TB1374/3X)..... <b>BA5375</b> 167.5 mm Air Dryer (Mann TB1374X)..... <b>BA5374+</b> Trans. (w/ZF Ecosplit Gearbox) (ZF 750131003)..... <b>PT8385</b> Steering..... <b>P106-HD</b>	M140 w/MIDR 06.02.26, MIDS 06.02.12 Eng. Lube (5000670700)..... <b>B76+</b> Fuel Spin-on (5000686589)..... <b>BF988+</b> 381.0 mm O. Air (5000242503)... <b>PA2474</b> 388.9 mm O. Air (5010094146)... <b>PA3699</b> 377.8 mm Some I. Air (5010094145)..... <b>PA3566</b> Steering (5000820895)..... <b>P106-HD</b>
S110 Lube (5000670670)..... <b>B403</b> Can-Type Fuel (7701010100)..... <b>BF825+</b> Fuel Spin-on (5000790570)..... <b>BF988+</b> 296.9 mm Air (5000809894)..... <b>PA2865</b> 339.7 mm Air (5000243970)..... <b>PA3446</b> Some I. Air..... <b>PA2419</b>	Midlum 135.09 w/MIDR 04.02.26 Eng. (02/00-12/01) Lube (Mann W1160/2)..... <b>B7227</b> Opt. Fuel/Water Separator (Racor Hsg.) (Racor 2010PM)..... <b>PF598-30</b> Fuel (Mann WK727)..... <b>BF988+</b> Opt. Fuel/Water Separator (R.V.I. Hsg.) (5000790559)..... <b>CLN&amp;R</b> Single Air (Mann C23440/1)..... <b>PA2474</b> Radial Seal O. Air..... <b>RS3727</b> Radial Seal O. Air (w/FRM) (5001865723)..... <b>RS5390</b> Radial Seal I. Air (5010317187)... <b>RS5351</b> 161.9 mm Air Dryer (Mann TB1374/3X)..... <b>BA5375</b> 167.5 mm Air Dryer (Mann TB1374X)..... <b>BA5374+</b> Trans. (w/ZF Ecosplit Gearbox) (ZF 750131003)..... <b>PT8385</b> Steering..... <b>P106-HD</b>	M140 w/MIDR 06.02.26, MIDS 06.02.12 Eng. Lube (5000670700)..... <b>B76+</b> Fuel Spin-on (5000686589)..... <b>BF988+</b> 381.0 mm O. Air (5000242503)... <b>PA2474</b> 388.9 mm O. Air (5010094146)... <b>PA3699</b> 377.8 mm Some I. Air (5010094145)..... <b>PA3566</b> Steering (5000820895)..... <b>P106-HD</b>
B120 Messenger w/SOFIM 8140 Eng. Dual-Flow Lube (5000816070)... <b>BD232</b> Fuel Spin-on..... <b>BF988+</b> Air (3563565)..... <b>PA2845</b> Steering (Iveco 1902137)..... <b>P106-HD</b>	Midlum 150.08 w/dCi4 Eng. (11/01-on) Lube (Mann W1160/2)..... <b>B7227</b> Opt. Fuel/Water Separator (Racor Hsg.) (Racor 2010PM)..... <b>PF598-30</b> Fuel (Mann WK940/20)..... <b>BF7886</b> Opt. Fuel/Water Separator (R.V.I. Hsg.) (5000790559)..... <b>CLN&amp;R</b> Radial Seal O. Air..... <b>RS3727</b> Radial Seal O. Air (w/FRM) (5001865723)..... <b>RS5390</b> Radial Seal I. Air (5010317187)... <b>RS5351</b> 161.9 mm Air Dryer (Mann TB1374/3X)..... <b>BA5375</b> 167.5 mm Air Dryer (Mann TB1374X)..... <b>BA5374+</b> Trans. (w/ZF Ecosplit Gearbox) (ZF 750131003)..... <b>PT8385</b> Steering..... <b>P106-HD</b>	M140 w/MIDR 06.02.26, MIDS 06.02.12 Eng. Lube (5000670700)..... <b>B76+</b> Fuel Spin-on (5000686589)..... <b>BF988+</b> 381.0 mm O. Air (5000242503)... <b>PA2474</b> 388.9 mm O. Air (5010094146)... <b>PA3699</b> 377.8 mm Some I. Air (5010094145)..... <b>PA3566</b> Steering (5000820895)..... <b>P106-HD</b>
C130 Lube (5000670670)..... <b>B403</b> Can-Type Fuel (855589600)..... <b>BF825+</b> Fuel Spin-on (5000814227)..... <b>BF988+</b> Air (24551160)..... <b>PA2845</b>	S135.08 Midliner w/MIDR 04.0226 Eng. Lube (5010240400)..... <b>B7227</b> Fuel (Mann WK727)..... <b>BF988+</b> Steering (Mann H601/4)..... <b>P106-HD</b>	M140 w/MIDR 06.02.26, MIDS 06.02.12 Eng. Lube (5000670700)..... <b>B76+</b> Fuel Spin-on (5000686589)..... <b>BF988+</b> 381.0 mm O. Air (5000242503)... <b>PA2474</b> 388.9 mm O. Air (5010094146)... <b>PA3699</b> 377.8 mm Some I. Air (5010094145)..... <b>PA3566</b> Steering (5000820895)..... <b>P106-HD</b>
S130 w/Renault Eng. Lube Spin-on (5000040870)..... <b>B114</b> Can-Type Fuel (7701010100)..... <b>BF825+</b> Fuel Spin-on (5000790570)..... <b>BF988+</b> 296.9 mm Air (5000809894)..... <b>PA2865</b> 339.7 mm Air (5000243970)..... <b>PA3446</b> Some I. Air (3564106)..... <b>PA2419</b>	Midlum 135.09 w/MIDR 04.02.26 Eng. (02/00-12/01) Lube (Mann W1160/2)..... <b>B7227</b> Opt. Fuel/Water Separator (Racor Hsg.) (Racor 2010PM)..... <b>PF598-30</b> Fuel (Mann WK727)..... <b>BF988+</b> Opt. Fuel/Water Separator (R.V.I. Hsg.) (5000790559)..... <b>CLN&amp;R</b> Single Air (Mann C23440/1)..... <b>PA2474</b> Radial Seal O. Air..... <b>RS3727</b> Radial Seal O. Air (w/FRM) (5001865723)..... <b>RS5390</b> Radial Seal I. Air (5010317187)... <b>RS5351</b>	M140 w/MIDR 06.02.26, MIDS 06.02.12 Eng. Lube (5000670700)..... <b>B76+</b> Fuel Spin-on (5000686589)..... <b>BF988+</b> 381.0 mm O. Air (5000242503)... <b>PA2474</b> 388.9 mm O. Air (5010094146)... <b>PA3699</b> 377.8 mm Some I. Air (5010094145)..... <b>PA3566</b> Steering (5000820895)..... <b>P106-HD</b>
GB131 w/797 Eng. Lube (5000670670)..... <b>B403</b> Fuel (854975700)..... <b>PF7596</b> Air (5000243970)..... <b>PA3446</b>		

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)
Midlum 150.08 w/MIDR 04.02.26 Eng. (02/00-12/01) <b>Lube</b> (Mann W1160/2)..... <b>B7227</b> <b>Opt. Fuel/Water Separator</b> (Racor Hsg.) (Racor 2010PM)..... <b>PF598-30</b> <b>Fuel</b> (Mann WK727)..... <b>BF988 +</b> <b>Opt. Fuel/Water Separator</b> (R.V.I. Hsg.) (5000790559)..... <b>CLN&amp;R</b> <b>Radial Seal O. Air</b> ..... <b>RS3727</b> <b>Radial Seal O. Air</b> (w/FRM) (5001865723)..... <b>RS5390</b> <b>Radial Seal I. Air</b> (5010317187)... <b>RS5351</b> <b>Single Air</b> (Mann C23440/1)..... <b>PA2474</b> <b>161.9 mm Air Dryer</b> (Mann TB1374/3X)..... <b>BA5375</b> <b>167.5 mm Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Trans.</b> (w/ZF Ecosplit Gearbox) (ZF 750131003)..... <b>PT8385</b> <b>Steering</b> ..... <b>P106-HD</b>	Midlum 150.12 w/dCi4 Eng. (11/01-on) <b>Lube</b> (Mann W1160/2)..... <b>B7227</b> <b>Opt. Fuel/Water Separator</b> (Racor Hsg.) (Racor 2010PM)..... <b>PF598-30</b> <b>Fuel</b> (Mann WK940/20)..... <b>BF7886</b> <b>Opt. Fuel/Water Separator</b> (R.V.I. Hsg.) (5000790559)..... <b>CLN&amp;R</b> <b>Radial Seal O. Air</b> ..... <b>RS3727</b> <b>Radial Seal O. Air</b> (w/FRM) (5001865723)..... <b>RS5390</b> <b>Radial Seal I. Air</b> (5010317187)... <b>RS5351</b> <b>161.9 mm Air Dryer</b> (Mann TB1374/3X)..... <b>BA5375</b> <b>167.5 mm Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Trans.</b> (w/ZF Ecosplit Gearbox) (ZF 750131003)..... <b>PT8385</b> <b>Steering</b> ..... <b>P106-HD</b>	GF151D <b>Lube</b> (5000670670)..... <b>B403</b> <b>Fuel</b> (5000686589)..... <b>BF988 +</b> <b>374.7 mm O. Air</b> (5000241796).... <b>PA2405</b> <b>371.5 mm I. Air</b> (5000802977).... <b>PA2835</b> <b>Coolant</b> (5000663625)..... <b>BW5139</b> <b>Steering</b> (5000807081)..... <b>P18-HD</b>
Midlum 150.09 w/MIDR 04.02.26 Eng. (02/00-12/01) <b>Lube</b> (Mann W1160/2)..... <b>B7227</b> <b>Fuel/Water Separator</b> ..... <b>PF598-30</b> <b>Fuel</b> (Mann WK727)..... <b>BF988 +</b> <b>Fuel/Water Separator</b> (5000822272)..... <b>CLN&amp;R</b> <b>Radial Seal O. Air</b> ..... <b>RS3727</b> <b>Radial Seal O. Air</b> (w/FRM) (5001865723)..... <b>RS5390</b> <b>Radial Seal I. Air</b> (5010317187)... <b>RS5351</b> <b>Single Air</b> (Mann C23440/1)..... <b>PA2474</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Air Dryer</b> (Mann TB1374/3X)..... <b>BA5375</b> <b>Trans.</b> (w/ZF Ecosplit Gearbox) (ZF 750131003)..... <b>PT8385</b> <b>Steering</b> ..... <b>P106-HD</b>	Midlum 150.12 w/MIDR 04.02.26 Eng. (02/00-12/01) <b>Lube</b> (Mann W1160/2)..... <b>B7227</b> <b>Fuel/Water Separator</b> ..... <b>PF598-30</b> <b>Fuel</b> (Mann WK727)..... <b>BF988 +</b> <b>Fuel/Water Separator</b> (5000822272)..... <b>CLN&amp;R</b> <b>Radial Seal O. Air</b> ..... <b>RS3727</b> <b>Radial Seal O. Air</b> (w/FRM) (5001865723)..... <b>RS5390</b> <b>Radial Seal I. Air</b> (5010317187)... <b>RS5351</b> <b>Single Air</b> (Mann C23440/1)..... <b>PA2474</b> <b>161.9 mm Air Dryer</b> (Mann TB1374/3X)..... <b>BA5375</b> <b>167.5 mm Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Trans.</b> (ZF Ecosplit Gearbox) (ZF 750131003)..... <b>PT8385</b> <b>Steering</b> ..... <b>P106-HD</b>	160 Midlum w/Volvo DXi5 (Euro 4-5) Eng. (05/06-on) <b>Lube</b> (7420796782)..... <b>P7329</b> <b>Fuel/Water Separator</b> (7420851191)..... <b>BF1388-O</b> <b>P. Fuel</b> (7420796772)..... <b>PF7938</b> <b>Radial Seal O. Air</b> (5001865723). <b>RS5390</b> <b>Radial Seal I. Air</b> ..... <b>RS5351</b> <b>Air Dryer</b> (5001865404)..... <b>BA5566</b> <b>Urea</b> (7421333098)..... <b>PE5271</b>
Midlum 150.10 w/dCi4 Eng. (11/01-on) <b>Lube</b> (Mann W1160/2)..... <b>B7227</b> <b>Opt. Fuel/Water Separator</b> (Racor Hsg.) (Racor 2010PM)..... <b>PF598-30</b> <b>Fuel</b> (Mann WK940/20)..... <b>BF7886</b> <b>Opt. Fuel/Water Separator</b> (R.V.I. Hsg.) (5000790559)..... <b>CLN&amp;R</b> <b>Radial Seal O. Air</b> ..... <b>RS3727</b> <b>Radial Seal O. Air</b> (w/FRM) (5001865723)..... <b>RS5390</b> <b>Radial Seal I. Air</b> (5010317187)... <b>RS5351</b> <b>161.9 mm Air Dryer</b> (Mann TB1374/3X)..... <b>BA5375</b> <b>167.5 mm Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Trans.</b> (w/ZF Ecosplit Gearbox) (ZF 750131003)..... <b>PT8385</b> <b>Steering</b> ..... <b>P106-HD</b>	D Serie D 150 w/Volvo DTI 3 Eng. (04/14-on) <b>F-F Lube</b> (7701057828)..... <b>P7365</b> <b>Fuel/Water Separator</b> (7421538977)..... <b>BF1292-O</b> <b>Radial Seal O. Air</b> (5001869822). <b>RS5670</b> <b>Air</b> (Air Brake System) (7485138330)..... <b>PA30101</b> <b>Air Dryer</b> (5001865404)..... <b>BA5566</b> <b>Urea</b> (7421574991)..... <b>PE17000</b>	Midlum II 160.08 Dxi, 160.10 Dxi, 160.12 Dxi w/Dxi5 Eng. (05/06-on) <b>Lube</b> (7420796782)..... <b>P7329</b> <b>Fuel/Water Separator</b> (7420851191)..... <b>BF1388-O</b> <b>Fuel</b> (7420796772)..... <b>PF7938</b> <b>Radial Seal O. Air</b> (5001865723). <b>RS5390</b> <b>Radial Seal I. Air</b> (5010317187)... <b>RS5351</b> <b>Radial Seal Air</b> (Standard Media) (5010315990)..... <b>RS5301</b> <b>Radial Seal Air</b> (Flame Retardant Media) (5001865724)..... <b>RS30236</b> <b>Cab Air</b> (5001867491)..... <b>PA30188</b> <b>Air Dryer</b> (5001865404)..... <b>BA5566</b> <b>Steering</b> (5000820895)..... <b>P106-HD</b> <b>Urea</b> (7420877953)..... <b>PE5271</b>
Midlum 150.10 w/dCi4 Eng. (11/01-on) <b>Lube</b> (Mann W1160/2)..... <b>B7227</b> <b>Opt. Fuel/Water Separator</b> (Racor Hsg.) (Racor 2010PM)..... <b>PF598-30</b> <b>Fuel</b> (Mann WK940/20)..... <b>BF7886</b> <b>Opt. Fuel/Water Separator</b> (R.V.I. Hsg.) (5000790559)..... <b>CLN&amp;R</b> <b>Radial Seal O. Air</b> ..... <b>RS3727</b> <b>Radial Seal O. Air</b> (w/FRM) (5001865723)..... <b>RS5390</b> <b>Radial Seal I. Air</b> (5010317187)... <b>RS5351</b> <b>161.9 mm Air Dryer</b> (Mann TB1374/3X)..... <b>BA5375</b> <b>167.5 mm Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Trans.</b> (w/ZF Ecosplit Gearbox) (ZF 750131003)..... <b>PT8385</b> <b>Steering</b> ..... <b>P106-HD</b>	S150 w/Renault Eng. <b>Lube Spin-on</b> (5000040870)..... <b>B114</b> <b>Can-Type Fuel</b> (7701010100)..... <b>BF825 +</b> <b>Fuel Spin-on</b> (5000790570)..... <b>BF988 +</b> <b>296.9 mm Air</b> (5000809894)..... <b>PA2865</b> <b>339.7 mm Air</b> (5000243970)..... <b>PA3446</b> <b>Some I. Air</b> (3564106)..... <b>PA2419</b>	GBC160MT (6x6) <b>Fuel</b> (941718018)..... <b>BF719</b>
		GLR160 w/520, M260 Engs. <b>Fuel</b> (941718018)..... <b>BF719</b> <b>O. Air</b> (3564117)..... <b>PA1884 +</b> <b>I. Air</b> (3564115)..... <b>PA1911</b>
		M160 w/MIDS 06.02.12, MIDR 06.02.26 Engs. <b>Lube</b> (5000670700)..... <b>B76 +</b> <b>Fuel Spin-on</b> (5000686589)..... <b>BF988 +</b> <b>381.0 mm O. Air</b> (5000242503).... <b>PA2474</b> <b>388.9 mm O. Air</b> (5010094146).... <b>PA3699</b> <b>377.8 mm Some I. Air</b> (5010094145)..... <b>PA3566</b> <b>Steering</b> (5000820895)..... <b>P106-HD</b>
		D170-14, D170-17 w/MIDR 06.02.12 Eng. <b>Lube</b> ..... <b>B403</b> <b>Fuel</b> ..... <b>BF988 +</b> <b>Coolant</b> ..... <b>B5134 +</b>
		G170 w/MIDS 06.02.12 Eng. <b>206.4 mm Lube</b> (5000670670).... <b>B403</b> <b>265.1 mm Lube</b> (5000670700).... <b>B76 +</b> <b>Fuel</b> (5000814227)..... <b>BF988 +</b> <b>Coolant</b> (5000663625)..... <b>BW5139</b>
		S150.08, S150.09 Midliners w/MIDR 04.0226 Eng. <b>Lube</b> (5010240400)..... <b>B7227</b> <b>Fuel</b> (Mann WK727)..... <b>BF988 +</b> <b>Steering</b> (Mann H601/4)..... <b>P106-HD</b>

+ See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)
JM170 w/M.A.N. Eng. Lube Ele. (4055040004)..... P235 P. Fuel (854806000)..... F953-F S. Fuel (870176000)..... PF834 Fuel Spin-on (5000814227)..... BF988 +	Midlum II 180.08 Dxi, 180.10 Dxi, 180.12 Dxi w/Dxi5 Eng. (07/09-on) Lube (7420796782)..... P7329 Fuel/Water Separator (7420851191)..... BF1388-O Fuel (7420796772)..... PF7938 Radial Seal O. Air (5001865723)..... RS5390 Radial Seal I. Air (5010317187)..... RS5351 Radial Seal Air (Standard Media) (5010315990)..... RS5301 Radial Seal Air (Flame Retardant Media) (5001865724)..... RS30236 Cab Air (5001867491)..... PA30188 Air Dryer (5001865404)..... BA5566 Steering (5000820895)..... P106-HD Urea (7420877953)..... PE5271	Midlum 180.12 w/dCi4-150 Eng. (11/01-on) (Cont'd) Radial Seal O. Air (w/FRM) (5001865723)..... RS5390 Radial Seal I. Air (5010317187)..... RS5351 161.9 mm Air Dryer (Mann TB1374/3X)..... BA5375 167.5 mm Air Dryer (Mann TB1374X)..... BA5374 + Trans. (w/ZF Ecosplit Gearbox) (ZF 750131003)..... PT8385 Steering..... P106-HD
S170 Lube (5000670700)..... B76 + Fuel (5000790570)..... BF988 + 296.9 mm Air (5000809894)..... PA2865 339.7 mm Air..... PA3446 358.0 mm Some I. Air (3564106)..... PA2419	Midlum 180.10 w/dCi4-150 Eng. (11/01-on) Lube (Mann W1160/2)..... B7227 Fuel (Mann WK940/20)..... BF7886 Radial Seal O. Air (Mann C321447)..... RS3727 Radial Seal O. Air (w/FRM) (5001865723)..... RS5390 Radial Seal I. Air (5010317187)..... RS5351 161.9 mm Air Dryer (Mann TB1374/3X)..... BA5375 167.5 mm Air Dryer (Mann TB1374X)..... BA5374 + Trans. (w/ZF Ecosplit Gearbox) (ZF 750131003)..... PT8385 Steering..... P106-HD	D Serie D 180 w/Volvo DTI 3 Eng. (04/14-on) F-F Lube (7701057828)..... P7365 Fuel/Water Separator (7421538977)..... BF1292-O Radial Seal O. Air (5001869822)..... RS5670 Air (Air Brake System) (7485138330)..... PA30101 Air Dryer (5001865404)..... BA5566 Urea (7421574991)..... PE17000
Midlum SM170 w/M.A.N. D0836 Eng. 195.3 mm Lube Ele. (7701009924)..... P721 198.4 mm Lube Ele. (5000273542)..... P235 P. Fuel (854806000)..... F953-F S. Fuel (870176000)..... PF834	Midlum 180.10 w/dCi4-150 Eng. (11/01-on) Lube (Mann W1160/2)..... B7227 Fuel (Mann WK940/20)..... BF7886 Radial Seal O. Air (Mann C321447)..... RS3727 Radial Seal O. Air (w/FRM) (5001865723)..... RS5390 Radial Seal I. Air (5010317187)..... RS5351 161.9 mm Air Dryer (Mann TB1374/3X)..... BA5375 167.5 mm Air Dryer (Mann TB1374X)..... BA5374 + Trans. (w/ZF Ecosplit Gearbox) (ZF 750131003)..... PT8385 Steering..... P106-HD	190 Midlum w/Volvo DXi5 (Euro 4-5) Eng. (05/06-on) Lube (7420796782)..... P7329 Fuel/Water Separator (7420851191)..... BF1388-O P. Fuel (7420796772)..... PF7938 Radial Seal O. Air (5001865723)..... RS5390 Radial Seal I. Air..... RS5351 Air Dryer (5001865404)..... BA5566 Urea (7421333098)..... PE5271
Midlum 180.08 w/dCi4-150 Eng. (11/01-on) Lube (Mann W1160/2)..... B7227 Fuel/Water Separator..... PF598-30 Fuel (Mann WK940/20)..... BF7886 Fuel/Water Separator (5000822272)..... CLN&R Radial Seal O. Air (Mann C321447)..... RS3727 Radial Seal O. Air (w/FRM) (5001865723)..... RS5390 Radial Seal I. Air (5010317187)..... RS5351 161.9 mm Air Dryer (Mann TB1374/3X)..... BA5375 167.5 mm Air Dryer (Mann TB1374X)..... BA5374 + Trans. (w/ZF Ecosplit Gearbox) (ZF 750131003)..... PT8385 Steering..... P106-HD	Midlum 180.10, 180.12 w/MIDR 06.02.26 Eng. (02/00-12/01) Lube..... B76 + Opt. Fuel/Water Separator (Racor Hsg.) (Racor 2010PM)..... PF598-30 Fuel..... BF988 + Opt. Fuel/Water Separator (R.V.I. Hsg.) (5000790559)..... CLN&R Single Air..... PA2474 Radial Seal O. Air..... RS3727 Radial Seal O. Air (w/FRM) (5001865723)..... RS5390 Radial Seal I. Air (5010317187)..... RS5351 161.9 mm Air Dryer (Mann TB1374/3X)..... BA5375 167.5 mm Air Dryer (Mann TB1374X)..... BA5374 + Trans. (w/ZF Ecosplit Gearbox) (ZF 750131003)..... PT8385 Steering..... P106-HD	Midlum II 190.08 Dxi, 190.10 Dxi, 190.12 Dxi, 190.13 Dxi, 190.14 Dxi w/Dxi5 Eng. (05/06-on) Lube (7420796782)..... P7329 Fuel/Water Separator (7420851191)..... BF1388-O Fuel (7420796772)..... PF7938 Radial Seal O. Air (5001865723)..... RS5390 Radial Seal I. Air (5010317187)..... RS5351 Radial Seal Air (Standard Media) (5010315990)..... RS5301 Radial Seal Air (Flame Retardant Media) (5001865724)..... RS30236 Cab Air (5001867491)..... PA30188 Air Dryer (5001865404)..... BA5566 Steering (5000820895)..... P106-HD Urea (7420877953)..... PE5271
Midlum 180.08 w/MIDR 04.02.26 Eng. (02/00-12/01) Lube (Mann W1160/2)..... B7227 Opt. Fuel/Water Separator (Racor Hsg.) (Racor 2010PM)..... PF598-30 Fuel (Mann WK727)..... BF988 + Opt. Fuel/Water Separator (R.V.I. Hsg.) (5000790559)..... CLN&R Radial Seal O. Air (Mann C321447)..... RS3727 Radial Seal O. Air (w/FRM) (5001865723)..... RS5390 Radial Seal I. Air (5010317187)..... RS5351 Single Air (Mann C23440/1)..... PA2474 161.9 mm Air Dryer (Mann TB1374/3X)..... BA5375 167.5 mm Air Dryer (Mann TB1374X)..... BA5374 + Trans. (w/ZF Ecosplit Gearbox) (ZF 750131003)..... PT8385 Steering..... P106-HD	Midlum 180.12 w/dCi4-150 Eng. (11/01-on) Lube (Mann W1160/2)..... B7227 Fuel/Water Separator..... PF598-30 Fuel (Mann WK940/20)..... BF7886 Fuel/Water Separator (5000822272)..... CLN&R Radial Seal O. Air (Mann C321447)..... RS3727	GC190, GF190 w/MID 06.20.30 Eng. Lube (504020)..... B403 Can-Type Fuel (5006163)..... BF825 + Fuel Spin-on (5000814227)..... BF988 + 374.7 mm O. Air (5000241796)..... PA2405 596.9 mm Some Air..... PA2580
		GLC190 Lube (5000670670)..... B403 Fuel (5000790570)..... BF988 + O. Air (5000242503)..... PA2474 I. Air (5000802978)..... PA2836

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)
GLR190, GR190, GR190A w/MID 06.20.30 Eng. Lube (504020)..... <b>B403</b> Can-Type Fuel (5006163)..... <b>BF825 +</b> Fuel Spin-on (5000814227)..... <b>BF988 +</b> 374.7 mm O. Air (5000241796).... <b>PA2405</b> 371.5 mm I. Air (5000802977).... <b>PA2835</b> 596.9 mm Some Air..... <b>PA2580</b>	Midlum 210.08 w/MIDR 06.02.26 Eng. (02/00-12/01) Lube..... <b>B76 +</b> Opt. Fuel/Water Separator (Racor Hsg.) (Racor 2010PM)..... <b>PF598-30</b> Fuel..... <b>BF988 +</b> Opt. Fuel/Water Separator (R.V.I. Hsg.) (5000790559)..... <b>CLN&amp;R</b> Single Air..... <b>PA2474</b> Radial Seal O. Air..... <b>RS3727</b> Radial Seal O. Air (w/FRM) (5001865723)..... <b>RS5390</b> Radial Seal I. Air (5010317187)... <b>RS5351</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Air Dryer (Mann TB1374/3X)..... <b>BA5375</b> Trans. (w/ZF Ecosplit Gearbox) (ZF 750131003)..... <b>PT8385</b> Steering..... <b>P106-HD</b>	Midlum 210.12 w/MIDR 06.02.26 Eng. (02/00-12/01) Lube..... <b>B76 +</b> Opt. Fuel/Water Separator (Racor Hsg.) (Racor 2010PM)..... <b>PF598-30</b> Fuel..... <b>BF988 +</b> Opt. Fuel/Water Separator (R.V.I. Hsg.) (5000790559)..... <b>CLN&amp;R</b> Single Air..... <b>PA2474</b> Radial Seal O. Air..... <b>RS3727</b> Radial Seal O. Air (w/FRM) (5001865723)..... <b>RS5390</b> Radial Seal I. Air (5010317187)... <b>RS5351</b> 161.9 mm Air Dryer (Mann TB1374/3X)..... <b>BA5375</b> 167.5 mm Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Trans. (w/ZF Ecosplit Gearbox) (ZF 750131003)..... <b>PT8385</b> Steering..... <b>P106-HD</b>
SM190 w/M.A.N. Eng. Lube (4055040006)..... <b>P235</b> P. Fuel (854806000)..... <b>F953-F</b> S. Fuel (870176000)..... <b>PF834</b>	Midlum 210.09 w/MIDR 06.02.26 Eng. (02/00-12/01) Lube..... <b>B76 +</b> Opt. Fuel/Water Separator (Racor Hsg.) (Racor 2010PM)..... <b>PF598-30</b> Fuel..... <b>BF988 +</b> Opt. Fuel/Water Separator (R.V.I. Hsg.) (5000790559)..... <b>CLN&amp;R</b> Single Air..... <b>PA2474</b> Radial Seal O. Air..... <b>RS3727</b> Radial Seal O. Air (w/FRM) (5001865723)..... <b>RS5390</b> Radial Seal I. Air (5010317187)... <b>RS5351</b> 161.9 mm Air Dryer (Mann TB1374/3X)..... <b>BA5375</b> 167.5 mm Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Trans. (w/ZF Ecosplit Gearbox) (ZF 750131003)..... <b>PT8385</b> Steering..... <b>P106-HD</b>	Midlum 210.13 w/MIDR 06.02.26 Eng. (02/00-12/01) Lube..... <b>B76 +</b> Opt. Fuel/Water Separator (Racor Hsg.) (Racor 2010PM)..... <b>PF598-30</b> Fuel..... <b>BF988 +</b> Opt. Fuel/Water Separator (R.V.I. Hsg.) (5000790559)..... <b>CLN&amp;R</b> Single Air..... <b>PA2474</b> Radial Seal O. Air..... <b>RS3727</b> Radial Seal O. Air (w/FRM) (5001865723)..... <b>RS5390</b> Radial Seal I. Air (5010317187)... <b>RS5351</b> 161.9 mm Air Dryer (Mann TB1374/3X)..... <b>BA5375</b> 167.5 mm Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Trans. (w/ZF Ecosplit Gearbox) (ZF 750131003)..... <b>PT8385</b> Steering..... <b>P106-HD</b>
GB191, GC191, GF191, GR191, TB191 w/MID 06.20.30 Eng. Lube (5000670670)..... <b>B403</b> Fuel (5000686589)..... <b>BF988 +</b> 374.7 mm O. Air (5000241796).... <b>PA2405</b> 371.5 mm I. Air (5000802977).... <b>PA2835</b> 381.0 mm O. Air (3563595)..... <b>PA2474</b> 379.4 mm I. Air (5000802978).... <b>PA2836</b> Coolant (5000663625)..... <b>BW5139</b> Steering (5000807081)..... <b>P18-HD</b>	Midlum 210.10 w/MIDR 06.02.26 Eng. (02/00-12/01) Lube..... <b>B76 +</b> Opt. Fuel/Water Separator (Racor Hsg.) (Racor 2010PM)..... <b>PF598-30</b> Fuel..... <b>BF988 +</b> Opt. Fuel/Water Separator (R.V.I. Hsg.) (5000790559)..... <b>CLN&amp;R</b> Single Air..... <b>PA2474</b> Radial Seal O. Air..... <b>RS3727</b> Radial Seal O. Air (w/FRM) (5001865723)..... <b>RS5390</b> Radial Seal I. Air (5010317187)... <b>RS5351</b> 161.9 mm Air Dryer (Mann TB1374/3X)..... <b>BA5375</b> 167.5 mm Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Trans. (w/ZF Ecosplit Gearbox) (ZF 750131003)..... <b>PT8385</b> Steering..... <b>P106-HD</b>	Midlum 210.14 w/MIDR 06.02.26 Eng. (02/00-12/01) Lube..... <b>B76 +</b> Opt. Fuel/Water Separator (Racor Hsg.) (Racor 2010PM)..... <b>PF598-30</b> Fuel..... <b>BF988 +</b> Opt. Fuel/Water Separator (R.V.I. Hsg.) (5000790559)..... <b>CLN&amp;R</b> Single Air..... <b>PA2474</b> Radial Seal O. Air..... <b>RS3727</b> Radial Seal O. Air (w/FRM) (5001865723)..... <b>RS5390</b> Radial Seal I. Air (5010317187)... <b>RS5351</b> 161.9 mm Air Dryer (Mann TB1374/3X)..... <b>BA5375</b> 167.5 mm Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Trans. (w/ZF Ecosplit Gearbox) (ZF 750131003)..... <b>PT8385</b>
GLR200 w/520, M260 Eng. Fuel (941718018)..... <b>BF719</b> O. Air (3564117)..... <b>PA1884 +</b> I. Air (3564115)..... <b>PA1911</b>	SM200 w/M.A.N. D214HM, D2146HM3 Eng. Lube (4083040018)..... <b>P235</b> P. Fuel Ele. (24866064)..... <b>F950-F</b> S. Fuel Ele. (24866092)..... <b>PF950</b> Fuel Spin-on (5000814227)..... <b>BF988 +</b>	
JL200, JM200 w/Henschel 520D6T Eng. Lube Ele..... <b>P235</b> P. Fuel Ele. (24866064)..... <b>F950-F</b> S. Fuel Ele. (24866092)..... <b>PF950</b>	SM200 w/M.A.N. D214HM, D2146HM3 Eng. Lube (4083040018)..... <b>P235</b> P. Fuel Ele. (24866064)..... <b>F950-F</b> S. Fuel Ele. (24866092)..... <b>PF950</b> Fuel Spin-on (5000814227)..... <b>BF988 +</b>	
JM200 w/M.A.N. D214HM, D2146HM3 Eng. Lube (4083040018)..... <b>P235</b> P. Fuel Ele. (24866064)..... <b>F950-F</b> S. Fuel Ele. (24866092)..... <b>PF950</b> Fuel Spin-on (5000814227)..... <b>BF988 +</b>	SM200 w/M.A.N. Eng. Lube (4055040006)..... <b>P235</b> P. Fuel (854806000)..... <b>F953-F</b> S. Fuel (870176000)..... <b>PF834</b>	
M200 w/MIDR 06.02.26, MIDS 06.02.12 Eng. Lube (5000670700)..... <b>B76 +</b> Fuel Spin-on (5000686589)..... <b>BF988 +</b> 381.0 mm O. Air (5000242503).... <b>PA2474</b> 388.9 mm O. Air (5010094146).... <b>PA3699</b> 377.8 mm Some I. Air (5010094145)..... <b>PA3566</b> Steering (5000820895)..... <b>P106-HD</b>	GR205, GR205A, GR205B w/M620Z3 Eng. Fuel (941718018)..... <b>BF719</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)
Midlum 210.14 w/MIDR 06.02.26 Eng. (02/00-12/01) (Cont'd) <b>Steering</b> ..... P106-HD	G210 w/MIDS 06.20.30, MIDS 06.20.45 Engs. <b>Lube</b> (5000670670)..... B403 <b>Fuel Spin-on</b> (5000814227)..... BF988 + <b>Coolant</b> (5000663625)..... BW5139	Midlum II 220.08 Dxi, 220.10 Dxi, 220.12 Dxi, 220.13 Dxi, 220.14 Dxi w/Dxi5 Eng. (05/06-on) (Cont'd) <b>Fuel</b> (7420796772)..... PF7938 <b>Radial Seal O. Air</b> (5001865723)..... RS5390 <b>Radial Seal I. Air</b> (5010317187)... RS5351 <b>Radial Seal Air</b> (Standard Media) (5010315990)..... RS5301 <b>Radial Seal Air</b> (Flame Retardant Media) (5001865724)..... RS30236 <b>Cab Air</b> (5001867491)..... PA30188 <b>Air Dryer</b> (5001865404)..... BA5566 <b>Steering</b> (5000820895)..... P106-HD <b>Urea</b> (7420877953)..... PE5271
Midlum 210.15 w/MIDR 06.02.26 Eng. (02/00-12/01) <b>Lube</b> ..... B76 + <b>Opt. Fuel/Water Separator</b> (Racor Hsg.) (Racor 2010PM)..... PF598-30 <b>Fuel</b> ..... BF988 + <b>Opt. Fuel/Water Separator</b> (R.V.I. Hsg.) (5000790559)..... CLN&R <b>Single Air</b> ..... PA2474 <b>Radial Seal O. Air</b> ..... RS3727 <b>Radial Seal O. Air</b> (w/FRM) (5001865723)..... RS5390 <b>Radial Seal I. Air</b> (5010317187)... RS5351 <b>161.9 mm Air Dryer</b> (Mann TB1374/3X)..... BA5375 <b>167.5 mm Air Dryer</b> (Mann TB1374X)..... BA5374 + <b>Trans.</b> (w/ZF Ecosplit Gearbox) (ZF 750131003)..... PT8385 <b>Steering</b> ..... P106-HD	Premium HD210 w/MIDR 06.02.26 Eng. (04/96-on) <b>F-F Lube</b> (5000670700)..... B76 + <b>B-P Lube Spinner</b> (5000670737)..... BC110 <b>Opt. Fuel/Water Separator</b> (Racor Hsg.) (Racor 2010PM)..... PF598-30 <b>Fuel</b> (22852800)..... BF988 + <b>Fuel/Water Separator</b> ..... BF1221 + <b>Opt. Fuel/Water Separator</b> (R.V.I. Hsg.) (5000790559)..... CLN&R <b>Radial Seal O. Air</b> (5010230841)..... RS3727 <b>Radial Seal O. Air</b> (w/FRM) (5001865723)..... RS5390 <b>Radial Seal I. Air</b> (5010317187)... RS5351 <b>Air Dryer</b> (Mann TB1374X)..... BA5374 + <b>Trans.</b> (w/ZF Ecosplit Gearbox) (ZF 750131003)..... PT8385 <b>Steering</b> (Iveco 1902137)..... P106-HD <b>Gearbox Hyd.</b> (5000791145)..... B307	Midlum 220.10 w/dCi6 Eng. (11/01-on) <b>Lube</b> ..... B76 + <b>Opt. Fuel/Water Separator</b> (Racor Hsg.) (Racor 2010PM)..... PF598-30 <b>Fuel</b> ..... BF7886 <b>Opt. Fuel/Water Separator</b> (R.V.I. Hsg.) (5000790559)..... CLN&R <b>Fuel/Water Separator</b> (5001846015)..... BF7989-D <b>Radial Seal O. Air</b> ..... RS3727 <b>Radial Seal O. Air</b> (w/FRM) (5001865723)..... RS5390 <b>Radial Seal I. Air</b> (5010317187)... RS5351 <b>161.9 mm Air Dryer</b> (Mann TB1374/3X)..... BA5375 <b>167.5 mm Air Dryer</b> (Mann TB1374X)..... BA5374 + <b>Trans.</b> (w/ZF Ecosplit Gearbox) (ZF 5000807213)..... PT8385 <b>Steering</b> ..... P106-HD
Midlum 210.16 w/MIDR 06.02.26 Eng. (02/00-12/01) <b>Lube</b> ..... B76 + <b>Opt. Fuel/Water Separator</b> (Racor Hsg.) (Racor 2010PM)..... PF598-30 <b>Fuel</b> ..... BF988 + <b>Opt. Fuel/Water Separator</b> (R.V.I. Hsg.) (5000790559)..... CLN&R <b>Single Air</b> ..... PA2474 <b>Radial Seal O. Air</b> ..... RS3727 <b>Radial Seal O. Air</b> (w/FRM) (5001865723)..... RS5390 <b>Radial Seal I. Air</b> (5010317187)... RS5351 <b>161.9 mm Air Dryer</b> (Mann TB1374/3X)..... BA5375 <b>167.5 mm Air Dryer</b> (Mann TB1374X)..... BA5374 + <b>Trans.</b> (w/ZF Ecosplit Gearbox) (ZF 750131003)..... PT8385 <b>Steering</b> ..... P106-HD	Midlum 220 w/Volvo DXi5 (Euro 4-5) Eng. (05/06-on) <b>Lube</b> (7420796782)..... P7329 <b>Fuel/Water Separator</b> (7420851191)..... BF1388-O <b>P. Fuel</b> (7420796772)..... PF7938 <b>Radial Seal O. Air</b> (5001865723)..... RS5390 <b>Radial Seal I. Air</b> ..... RS5351 <b>Air Dryer</b> (5001865404)..... BA5566 <b>Urea</b> (7421333098)..... PE5271	Midlum 220.12 w/dCi6 Eng. (11/01-on) <b>Lube</b> ..... B76 + <b>Opt. Fuel/Water Separator</b> (Racor Hsg.) (Racor 2010PM)..... PF598-30 <b>Fuel</b> ..... BF7886 <b>Opt. Fuel/Water Separator</b> (R.V.I. Hsg.) (5000790559)..... CLN&R <b>Fuel/Water Separator</b> (5001846015)..... BF7989-D <b>Radial Seal O. Air</b> ..... RS3727 <b>Radial Seal O. Air</b> (w/FRM) (5001865723)..... RS5390 <b>Radial Seal I. Air</b> (5010317187)... RS5351 <b>161.9 mm Air Dryer</b> (Mann TB1374/3X)..... BA5375 <b>167.5 mm Air Dryer</b> (Mann TB1374X)..... BA5374 + <b>Trans.</b> (w/ZF Ecosplit Gearbox) (ZF 5000807213)..... PT8385 <b>Steering</b> ..... P106-HD
C210 w/MIDS 06.20.30 Eng. <b>Lube</b> (5000670670)..... B403 <b>Fuel</b> (5000814227)..... BF988 + <b>Coolant</b> (5000663625)..... BW5139 <b>Steering</b> (5000820895)..... P106-HD	Midlum 220.08 w/dCi6 Eng. (11/01-on) <b>Lube</b> ..... B76 + <b>Opt. Fuel/Water Separator</b> (Racor Hsg.) (Racor 2010PM)..... PF598-30 <b>Fuel</b> ..... BF7886 <b>Opt. Fuel/Water Separator</b> (R.V.I. Hsg.) (5000790559)..... CLN&R <b>Fuel/Water Separator</b> (5001846015)..... BF7989-D <b>Radial Seal O. Air</b> ..... RS3727 <b>Radial Seal O. Air</b> (w/FRM) (5001865723)..... RS5390 <b>Radial Seal I. Air</b> (5010317187)... RS5351 <b>161.9 mm Air Dryer</b> (Mann TB1374/3X)..... BA5375 <b>167.5 mm Air Dryer</b> (Mann TB1374X)..... BA5374 + <b>Trans.</b> (w/ZF Ecosplit Gearbox) (ZF 5000807213)..... PT8385 <b>Steering</b> ..... P106-HD	Midlum 220.13 w/dCi6 Eng. (11/01-on) <b>Lube</b> ..... B76 + <b>Opt. Fuel/Water Separator</b> (Racor Hsg.) (Racor 2010PM)..... PF598-30 <b>Fuel</b> ..... BF7886
D Serie D 210 w/Volvo DTI 5 Eng. (09/13-on) <b>Fuel/Water Separator</b> (7421538977)..... BF1292-O <b>Radial Seal Air</b> (Long) (5001865723)..... RS5390 <b>Radial Seal Air</b> (Short) (5001865724)..... RS30236 <b>Radial Seal Air</b> (5010315990)..... RS5301 <b>Cab Air</b> (5001867491)..... PA30188 <b>Air Dryer</b> (5001865404)..... BA5566	Midlum II 220.08 Dxi, 220.10 Dxi, 220.12 Dxi, 220.13 Dxi, 220.14 Dxi w/Dxi5 Eng. (05/06-on) <b>Lube</b> (7420796782)..... P7329 <b>Fuel/Water Separator</b> (7420851191)..... BF1388-O	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)
<b>Midlum 220.13 w/dCi6 Eng. (11/01-on) (Cont'd)</b> <b>Opt. Fuel/Water Separator (R.V.I. Hsg.) (5000790559).....</b> CLN&R <b>Fuel/Water Separator (5001846015).....</b> BF7989-D <b>Radial Seal O. Air.....</b> RS3727 <b>Radial Seal O. Air (w/FRM) (5001865723).....</b> RS5390 <b>Radial Seal I. Air (5010317187)...</b> RS5351 <b>161.9 mm Air Dryer (Mann TB1374/3X).....</b> BA5375 <b>167.5 mm Air Dryer (Mann TB1374X).....</b> BA5374 + <b>Trans. (w/ZF Ecosplit Gearbox) (ZF 5000807213).....</b> PT8385 <b>Steering.....</b> P106-HD	<b>Midlum 220.18 w/dCi6 Eng. (11/01-on)</b> <b>Lube.....</b> B76 + <b>Opt. Fuel/Water Separator (Racor Hsg.) (Racor 2010PM).....</b> PF598-30 <b>Fuel.....</b> BF7886 <b>Opt. Fuel/Water Separator (R.V.I. Hsg.) (5000790559).....</b> CLN&R <b>Fuel/Water Separator (5001846015).....</b> BF7989-D <b>Radial Seal O. Air.....</b> RS3727 <b>Radial Seal O. Air (w/FRM) (5001865723).....</b> RS5390 <b>Radial Seal I. Air (5010317187)...</b> RS5351 <b>161.9 mm Air Dryer (Mann TB1374/3X).....</b> BA5375 <b>167.5 mm Air Dryer (Mann TB1374X).....</b> BA5374 + <b>Trans. (w/ZF Ecosplit Gearbox) (ZF 5000807213).....</b> PT8385 <b>Steering.....</b> P106-HD	<b>G230 w/MIDS 06.02.26 Eng.</b> <b>Can-Type Fuel (941709013).....</b> BF825 + <b>Fuel Spin-on (Mann WK727).....</b> BF988 + <b>O. Air (5000783932).....</b> PA2474 <b>I. Air (Mann CF1200).....</b> PA2836
<b>Midlum 220.14 w/dCi6 Eng. (11/01-on)</b> <b>Lube.....</b> B76 + <b>Opt. Fuel/Water Separator (Racor Hsg.) (Racor 2010PM).....</b> PF598-30 <b>Fuel.....</b> BF7886 <b>Opt. Fuel/Water Separator (R.V.I. Hsg.) (5000790559).....</b> CLN&R <b>Fuel/Water Separator (5001846015).....</b> BF7989-D <b>Radial Seal O. Air.....</b> RS3727 <b>Radial Seal O. Air (w/FRM) (5001865723).....</b> RS5390 <b>Radial Seal I. Air (5010317187)...</b> RS5351 <b>161.9 mm Air Dryer (Mann TB1374/3X).....</b> BA5375 <b>167.5 mm Air Dryer (Mann TB1374X).....</b> BA5374 + <b>Trans. (w/ZF Ecosplit Gearbox) (ZF 5000807213).....</b> PT8385 <b>Steering.....</b> P106-HD	<b>CLR220 w/MIDS 06.20.30 Eng.</b> <b>Lube (5000670670).....</b> B403 <b>Fuel (5000814227).....</b> BF988 + <b>Coolant (5000663625).....</b> BW5139	<b>G230 w/MIDS 06.20.30, MIDS 06.20.45 Engs.</b> <b>Lube (5000670670).....</b> B403 <b>Fuel (5000814227).....</b> BF988 + <b>Coolant (5000663625).....</b> BW5139
<b>Midlum 220.16 w/dCi6 Eng. (11/01-on)</b> <b>Lube.....</b> B76 + <b>Opt. Fuel/Water Separator (Racor Hsg.) (Racor 2010PM).....</b> PF598-30 <b>Fuel.....</b> BF7886 <b>Opt. Fuel/Water Separator (R.V.I. Hsg.) (5000790559).....</b> CLN&R <b>Fuel/Water Separator (5001846015).....</b> BF7989-D <b>Radial Seal O. Air.....</b> RS3727 <b>Radial Seal O. Air (w/FRM) (5001865723).....</b> RS5390 <b>Radial Seal I. Air (5010317187)...</b> RS5351 <b>161.9 mm Air Dryer (Mann TB1374/3X).....</b> BA5375 <b>167.5 mm Air Dryer (Mann TB1374X).....</b> BA5374 + <b>Trans. (w/ZF Ecosplit Gearbox) (ZF 5000807213).....</b> PT8385 <b>Steering.....</b> P106-HD	<b>G220 w/MIDR 06.02.26 Eng.</b> <b>Lube (Mann W11102/11).....</b> B76 + <b>Fuel (Mann WK727).....</b> BF988 + <b>O. Air (5000819340).....</b> PA1885 + <b>I. Air (3564138).....</b> PA1893	<b>M230 w/MIDR 06.02.26, MIDS 06.02.12 Engs.</b> <b>Lube (5000670700).....</b> B76 + <b>Fuel (5000686589).....</b> BF988 + <b>381.0 mm O. Air (5000242503)...</b> PA2474 <b>388.9 mm O. Air (5010094146)...</b> PA3699 <b>377.8 mm Some I. Air (5010094145).....</b> PA3566 <b>Steering (5000820895).....</b> P106-HD
<b>Premium HD220 w/dCi 6 Eng. (11/01-on)</b> <b>F-F Lube.....</b> B76 + <b>B-P Lube Spinner.....</b> BC7173 <b>Opt. Fuel/Water Separator (Racor Hsg.) (Racor 2010PM).....</b> PF598-30 <b>Fuel.....</b> BF7886 <b>Opt. Fuel/Water Separator (R.V.I. Hsg.) (5000790559).....</b> CLN&R <b>Single Radial Seal Air.....</b> RS3727 <b>Radial Seal O. Air.....</b> RS3728 <b>Radial Seal O. Air (w/FRM) (5001865723).....</b> RS5390 <b>Radial Seal I. Air.....</b> RS3729 <b>Air Dryer (Mann TB1374X).....</b> BA5374 + <b>Trans. (w/ZF Ecosplit Gearbox) (ZF 750131003).....</b> PT8385 <b>Steering.....</b> P106-HD <b>Hyd.....</b> B307	<b>S220, S220TI w/MIDR 06.02.26A Eng.</b> <b>206.4 mm Lube (5000670670).....</b> B403 <b>265.1 mm Lube (5000670700)....</b> B76 + <b>Fuel (5000814227).....</b> BF988 + <b>339.7 mm Air (5000243970).....</b> PA3446 <b>Coolant (5000663625).....</b> BW5139	<b>TB230</b> <b>Lube (504020).....</b> B403 <b>381.0 mm O. Air.....</b> PA2474 <b>379.4 mm I. Air (5000802978)....</b> PA2836
<b>S220, S220TI w/MIDR 06.02.26A Eng.</b> <b>206.4 mm Lube (5000670670).....</b> B403 <b>265.1 mm Lube (5000670700)....</b> B76 + <b>Fuel (5000814227).....</b> BF988 + <b>339.7 mm Air (5000243970).....</b> PA3446 <b>Coolant (5000663625).....</b> BW5139	<b>C230 w/MIDS 06.20.30 Eng.</b> <b>Lube (504020).....</b> B403 <b>Fuel (5000814227).....</b> BF988 + <b>381.0 mm O. Air (3563595).....</b> PA2474	<b>TF230, TF230A w/MIDS 06.20.30 Eng.</b> <b>Lube (5000670670).....</b> B403 <b>O. Air (5000242503).....</b> PA2474 <b>I. Air (5000802978).....</b> PA2836
<b>TR230 w/MIDS 06.20.30 Eng.</b> <b>Lube Spin-on (504020).....</b> B403	<b>GB231, GC231, GF231, GR231 w/MID 06.20.30 Eng.</b> <b>Lube (5000670670).....</b> B403 <b>Fuel (5000686589).....</b> BF988 + <b>374.7 mm O. Air (5000241796)....</b> PA2405 <b>371.5 mm I. Air (5000802977)....</b> PA2835 <b>381.0 mm O. Air (3563595).....</b> PA2474 <b>379.4 mm I. Air (5000802978)....</b> PA2836 <b>Coolant (5000663625).....</b> BW5139 <b>Steering (5000807081).....</b> P18-HD	<b>GRH231 w/MIVS 08.35.40 Eng.</b> <b>Lube Ele.....</b> PT670 <b>Lube Spin-on (5000670670).....</b> B403 <b>O. Air (5000819342).....</b> PA2398
<b>PGC231</b> <b>O. Air (5000242503).....</b> PA2474 <b>I. Air (5000802978).....</b> PA2836	<b>TB231 w/MID 06.20.30 Eng.</b> <b>Lube (5000670670).....</b> B403 <b>Fuel (5000686589).....</b> BF988 + <b>374.7 mm O. Air (5000241796)....</b> PA2405 <b>371.5 mm I. Air (5000802977)....</b> PA2835	

+ See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)
TB231 w/MID 06.20.30 Eng. (Cont'd)	Premium HD240 w/Volvo DXi7 (Euro 4-5) Eng. (05/06-on)	Midlum 250.13 w/MIDR 06.02.26 Eng. (02/00-12/01) (Cont'd)
381.0 mm O. Air (3563595)..... PA2474	Lube (7420796782)..... P7329	Radial Seal O. Air (w/FRM) (5001865723)..... RS5390
379.4 mm I. Air (5000802978)..... PA2836	Fuel/Water Separator (7420851191)..... BF1388-O	Radial Seal I. Air (5010317187)... RS5351
Coolant (5000663625)..... BW5139	Fuel (7420796772)..... PF7938	161.9 mm Air Dryer (Mann TB1374/3X)..... BA5375
Steering (5000807081)..... P18-HD	Radial Seal Air (5001865723)..... RS5390	167.5 mm Air Dryer (Mann TB1374X)..... BA5374 +
TF231 w/MIDS 06.20.30 Eng.	Air Dryer (Wabco, Right-Hand Thd.) (5001865037)..... BA5379 +	Trans. (w/ZF Ecosplit Gearbox) (ZF 750131003)..... PT8385
Lube (5000670670)..... B403	Air Dryer (Knorr, Left-Hand Thd.) (5001865404)..... BA5566	Steering..... P106-HD
O. Air (5000242503)..... PA2474	Steering..... P106-HD	Midlum 250.14 w/MIDR 06.02.26 Eng. (02/00-12/01)
I. Air (5000802978)..... PA2836	Urea (7421333098)..... PE5271	Lube..... B76 +
TR231 w/MIDS 06.20.30 Eng.	JM240, SM240 w/M.A.N. D214HM, D2146HM3 Engs.	Opt. Fuel/Water Separator (Racor Hsg.) (Racor 2010PM)..... PF598-30
Lube (5000670670)..... B403	Lube (4083040018)..... P235	Fuel..... BF988 +
O. Air (5000242503)..... PA2474	P. Fuel Ele. (24866064)..... F950-F	Opt. Fuel/Water Separator (R.V.I. Hsg.) (5000790559)..... CLN&R
I. Air (5000802978)..... PA2836	S. Fuel Ele. (24866092)..... PF950	Single Air..... PA2474
240 Midlum w/Volvo DXi7 (Euro 4-5) Eng. (05/06-on)	Fuel Spin-on (5000814227)..... BF988 +	Radial Seal O. Air..... RS3727
Lube (7420796782)..... P7329	M240 w/MIDR 06.02.26, MIDS 06.02.12 Engs.	Radial Seal O. Air (w/FRM) (5001865723)..... RS5390
Fuel/Water Separator (7420851191)..... BF1388-O	Lube (5000670700)..... B76 +	Radial Seal I. Air (5010317187)... RS5351
P. Fuel (7420796772)..... PF7938	Fuel Spin-on (5000686589)..... BF988 +	161.9 mm Air Dryer (Mann TB1374/3X)..... BA5375
Radial Seal O. Air (5001865723)..... RS5390	381.0 mm O. Air (5000242503)... PA2474	167.5 mm Air Dryer (Mann TB1374X)..... BA5374 +
Radial Seal I. Air..... RS5351	388.9 mm O. Air (5010094146)... PA3699	Trans. (w/ZF Ecosplit Gearbox) (ZF 750131003)..... PT8385
Air Dryer (5001865404)..... BA5566	377.8 mm Some I. Air (5010094145)..... PA3566	Steering..... P106-HD
Urea (7421333098)..... PE5271	Steering (5000820895)..... P106-HD	Midlum 250.15 w/MIDR 06.02.26 Eng. (02/00-12/01)
Midlum II 240.12 Dxi, 240.13 Dxi, 240.14 Dxi, 240.15 Dxi, 240.16 Dxi w/Dxi7 Eng. (05/06-on)	Midlum 250.12 w/MIDR 06.02.26 Eng. (02/00-12/01)	Lube..... B76 +
Lube (7420796782)..... P7329	Lube..... B76 +	Opt. Fuel/Water Separator (Racor Hsg.) (Racor 2010PM)..... PF598-30
Fuel/Water Separator (7420851191)..... BF1388-O	Opt. Fuel/Water Separator (Racor Hsg.) (Racor 2010PM)..... PF598-30	Fuel..... BF988 +
Fuel (7420796772)..... PF7938	Fuel..... BF988 +	Opt. Fuel/Water Separator (R.V.I. Hsg.) (5000790559)..... CLN&R
Radial Seal O. Air (5001865723)..... RS5390	Opt. Fuel/Water Separator (R.V.I. Hsg.) (5000790559)..... CLN&R	Single Air..... PA2474
Radial Seal I. Air (5010317187)... RS5351	Single Air..... PA2474	Radial Seal O. Air..... RS3727
Radial Seal Air (Standard Media) (5010315990)..... RS5301	Radial Seal O. Air..... RS3727	Radial Seal O. Air (w/FRM) (5001865723)..... RS5390
Radial Seal Air (Flame Retardant Media) (5001865724)..... RS30236	Radial Seal O. Air (w/FRM) (5001865723)..... RS5390	Radial Seal I. Air (5010317187)... RS5351
Cab Air (5001867491)..... PA30188	Radial Seal I. Air (5010317187)... RS5351	161.9 mm Air Dryer (Mann TB1374/3X)..... BA5375
Air Dryer (5001865404)..... BA5566	161.9 mm Air Dryer (Mann TB1374/3X)..... BA5375	167.5 mm Air Dryer (Mann TB1374X)..... BA5374 +
Steering (5000820895)..... P106-HD	167.5 mm Air Dryer (Mann TB1374X)..... BA5374 +	Trans. (w/ZF Ecosplit Gearbox) (ZF 750131003)..... PT8385
Urea (7420877953)..... PE5271	Trans. (w/ZF Ecosplit Gearbox) (ZF 750131003)..... PT8385	Steering..... P106-HD
CBH240	Steering..... P106-HD	Midlum 250.16 w/MIDR 06.02.26 Eng. (02/00-12/01)
Lube (5000670670)..... B403	Midlum 250.13 w/MIDR 06.02.26 Eng. (02/00-12/01)	Lube..... B76 +
Fuel (5000790570)..... BF988 +	Lube..... B76 +	Opt. Fuel/Water Separator (Racor Hsg.) (Racor 2010PM)..... PF598-30
O. Air (5010064371)..... PA3558	Opt. Fuel/Water Separator (Racor Hsg.) (Racor 2010PM)..... PF598-30	Fuel..... BF988 +
I. Air (5010064372)..... PA3566	Fuel..... BF988 +	Opt. Fuel/Water Separator (R.V.I. Hsg.) (5000790559)..... CLN&R
D Serie D 240 w/Volvo DTI 5 Eng. (09/13-on)	Opt. Fuel/Water Separator (R.V.I. Hsg.) (5000790559)..... CLN&R	Single Air..... PA2474
Fuel/Water Separator (7421538977)..... BF1292-O	Single Air..... PA2474	Radial Seal O. Air..... RS3727
Radial Seal Air (Long) (5001865723)..... RS5390	Radial Seal O. Air..... RS3727	Radial Seal O. Air (w/FRM) (5001865723)..... RS5390
Radial Seal Air (Short) (5001865724)..... RS30236	Radial Seal I. Air (5010317187)... RS5351	Radial Seal I. Air (5010317187)... RS5351
Radial Seal Air (5010315990)..... RS5301	161.9 mm Air Dryer (Mann TB1374/3X)..... BA5375	161.9 mm Air Dryer (Mann TB1374/3X)..... BA5375
Cab Air (5001867491)..... PA30188	167.5 mm Air Dryer (Mann TB1374X)..... BA5374 +	167.5 mm Air Dryer (Mann TB1374X)..... BA5374 +
Air Dryer (5001865404)..... BA5566	Trans. (w/ZF Ecosplit Gearbox) (ZF 750131003)..... PT8385	Trans. (w/ZF Ecosplit Gearbox) (ZF 750131003)..... PT8385
	Steering..... P106-HD	Steering..... P106-HD

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)
Midlum 250.16 w/MIDR 06.02.26 Eng. (02/00-12/01) (Cont'd) <b>Opt. Fuel/Water Separator</b> (R.V.I. Hsg.) (5000790559)..... <b>CLN&amp;R</b> <b>Single Air</b> ..... <b>PA2474</b> <b>Radial Seal O. Air</b> ..... <b>RS3727</b> <b>Radial Seal O. Air</b> (w/FRM) (5001865723)..... <b>RS5390</b> <b>Radial Seal I. Air</b> (5010317187)... <b>RS5351</b> <b>161.9 mm Air Dryer</b> (Mann TB1374/3X)..... <b>BA5375</b> <b>167.5 mm Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Trans.</b> (w/ZF Ecosplit Gearbox) (ZF 750131003)..... <b>PT8385</b> <b>Steering</b> ..... <b>P106-HD</b>	Kerax 260 w/MIDR 06.20.45 Eng. (09/97-on) <b>F-F Lube</b> (5000670700)..... <b>B76 +</b> <b>Opt. Fuel/Water Separator</b> (Racor Hsg.) (Racor 2010PM)..... <b>PF598-30</b> <b>Fuel</b> (5000790570)..... <b>BF988 +</b> <b>Opt. Fuel/Water Separator</b> (R.V.I. Hsg.) (5000790559)..... <b>CLN&amp;R</b> <b>Radial Seal O. Air</b> (5010230916). <b>RS3728</b> <b>Radial Seal I. Air</b> (5010269584)... <b>RS3729</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Trans.</b> (ZF 7633141101)..... <b>PT691</b> <b>Steering</b> (Iveco 1902137)..... <b>P106-HD</b> <b>Gearbox Hyd.</b> (5000791145)..... <b>B307</b>	GR260 w/MIDS 06.35.40 Eng. (Cont'd) <b>469.9 mm Std. Some Air</b> (3564137)..... <b>PA1846 +</b> <b>469.9 mm Some Air</b> (Upgrade) (3564137)..... <b>PA1846XP</b> <b>Premium HD260 w/MIDR 06.20.45 Eng.</b> (04/96-on) <b>F-F Lube</b> ..... <b>B76 +</b> <b>B-P Lube Spinner</b> ..... <b>BC110</b> <b>Opt. Fuel/Water Separator</b> (Racor Hsg.) (Racor 2010PM)..... <b>PF598-30</b> <b>Fuel</b> ..... <b>BF988 +</b> <b>Opt. Fuel/Water Separator</b> (R.V.I. Hsg.) (5000790559)..... <b>CLN&amp;R</b> <b>Radial Seal O. Air</b> ..... <b>RS3727</b> <b>Radial Seal O. Air</b> (w/FRM) (5001865723)..... <b>RS5390</b> <b>Radial Seal I. Air</b> (5010317187)... <b>RS5351</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Trans.</b> (w/ZF Ecosplit Gearbox) (ZF 750131003)..... <b>PT8385</b> <b>Steering</b> ..... <b>P106-HD</b> <b>Hyd.</b> ..... <b>B307</b>
C Serie C 250 w/Volvo DTI 8 Eng. (0/13-on) <b>Fuel/Water Separator</b> (7421538977)..... <b>BF1292-O</b> <b>Cab Air</b> (7482348995)..... <b>PA30114</b> <b>Cab Air</b> (7482379897)..... <b>PA30113</b> <b>Air Dryer</b> (5001865404)..... <b>BA5566</b> <b>Steering</b> (5000820895)..... <b>P106-HD</b> <b>Urea</b> (7421574991)..... <b>PE17000</b>	C260 w/MIDR 06.20.45 Eng. <b>Lube</b> (5000670670)..... <b>B403</b> <b>Fuel</b> (5000814227)..... <b>BF988 +</b> <b>398.5 mm O. Air</b> (5010064371)... <b>PA3558</b> <b>377.8 mm I. Air</b> (5010064372).... <b>PA3566</b> <b>419.1 mm O. Air</b> (3564118)..... <b>PA1885 +</b> <b>406.4 mm I. Air</b> (3564119)..... <b>PA1893</b> <b>423.9 mm Some Air</b> (5000953712)..... <b>PA2945</b> <b>Coolant</b> (5000663625)..... <b>BW5139</b> <b>Steering</b> (5000820895)..... <b>P106-HD</b>	SM260 w/M.A.N. D214HM, D2146HM3 Engs. <b>Lube</b> (4083040018)..... <b>P235</b> <b>P. Fuel Ele.</b> (24866064)..... <b>F950-F</b> <b>S. Fuel Ele.</b> (24866092)..... <b>PF950</b> <b>Fuel Spin-on</b> (5000814227)..... <b>BF988 +</b>
D Serie D 250 w/Volvo DTI 8 Eng. (09/13-on) <b>Fuel/Water Separator</b> (7421538977)..... <b>BF1292-O</b> <b>Radial Seal Air</b> (Long) (5001865723)..... <b>RS5390</b> <b>Radial Seal Air</b> (Short) (5001865724)..... <b>RS30236</b> <b>Radial Seal Air</b> (5010315990)..... <b>RS5301</b> <b>Cab Air</b> (5001867491)..... <b>PA30188</b> <b>Air Dryer</b> (5001865404)..... <b>BA5566</b>	G260 w/MIDR 06.20.45, MIDS 06.20.45 Engs. <b>Lube</b> (5000670670)..... <b>B403</b> <b>Fuel Spin-on</b> (5000814227)..... <b>BF988 +</b> <b>Coolant</b> (5000663625)..... <b>BW5139</b>	SM260 w/M.A.N. Eng. <b>Lube Ele.</b> (4055040006)..... <b>P235</b> <b>P. Fuel</b> (854806000)..... <b>F953-F</b> <b>S. Fuel</b> (870176000)..... <b>PF834</b>
Premium HD250 w/MIDR 06.02.26 Eng. (04/96-on) <b>F-F Lube</b> (5000670700)..... <b>B76 +</b> <b>B-P Lube Spinner</b> (5000670737). <b>BC110</b> <b>Opt. Fuel/Water Separator</b> (Racor Hsg.) (Racor 2010PM)..... <b>PF598-30</b> <b>Fuel</b> (22852800)..... <b>BF988 +</b> <b>Fuel/Water Separator</b> ..... <b>BF1221 +</b> <b>Opt. Fuel/Water Separator</b> (R.V.I. Hsg.) (5000790559)..... <b>CLN&amp;R</b> <b>Radial Seal O. Air</b> (5010230841). <b>RS3727</b> <b>Radial Seal I. Air</b> (5010317187)... <b>RS5351</b> <b>Radial Seal O. Air</b> (w/FRM) (5001865723)..... <b>RS5390</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Trans.</b> (w/ZF Ecosplit Gearbox) (ZF 750131003)..... <b>PT8385</b> <b>Steering</b> (Iveco 1902137)..... <b>P106-HD</b> <b>Gearbox Hyd.</b> (5000791145)..... <b>B307</b>	GBH260 w/MIDS 06.35.40 Eng. <b>Lube</b> (5000670670)..... <b>B403</b> <b>Fuel</b> (3036404)..... <b>BF797</b> <b>342.9 mm O. Air</b> (3564117)..... <b>PA1884 +</b> <b>330.2 mm I. Air</b> (3564115)..... <b>PA1911</b> <b>419.1 mm Some O. Air</b> (3564118)..... <b>PA1885 +</b> <b>406.4 mm Some I. Air</b> (3564119). <b>PA1893</b> <b>469.9 mm Std. Some Air</b> (3564137)..... <b>PA1846 +</b> <b>469.9 mm Some Air</b> (Upgrade) (3564137)..... <b>PA1846XP</b>	TBH260 w/MIDS 06.35.40 Eng. <b>Lube</b> (5000670670)..... <b>B403</b> <b>Fuel Spin-on</b> (3036404)..... <b>BF797</b> <b>342.9 mm O. Air</b> ..... <b>LL1884 +</b> <b>330.2 mm I. Air</b> ..... <b>PA1911</b> <b>406.4 mm Air</b> (3564119)..... <b>PA1893</b> <b>419.1 mm Air</b> (3564118)..... <b>PA1885 +</b> <b>469.9 mm Std. Air</b> (3564137)..... <b>PA1846 +</b> <b>469.9 mm Air</b> (Upgrade) (3564137)..... <b>PA1846XP</b>
TR251 <b>Lube Ele.</b> (5000043298)..... <b>P294</b> <b>Lube Spin-on</b> (5000670670)..... <b>B403</b> <b>Fuel Ele.</b> (Felt)..... <b>F834-F</b> <b>S. Fuel Spin-on</b> (870175600)..... <b>BF719</b>	GBH260 (6x4) w/MIDS 06.35.40 Eng. <b>Lube</b> (4307426)..... <b>PT670</b> <b>111.1 mm Fuel Spin-on</b> (941718018)..... <b>BF719</b> <b>136.5 mm Fuel Spin-on</b> (3036404)..... <b>BF797</b> <b>266.7 mm Air</b> (3564001)..... <b>PA1646-FN</b> <b>330.2 mm Air</b> (3564115)..... <b>PA1911</b> <b>342.9 mm Air</b> (3564117)..... <b>PA1884 +</b>	TR260 w/MIDS 06.35.40 Eng. <b>Lube Spin-on</b> (5000670670)..... <b>B403</b> <b>Fuel Spin-on</b> (3036404)..... <b>BF797</b> <b>342.9 mm O. Air</b> ..... <b>LL1884 +</b> <b>330.2 mm I. Air</b> (3564115)..... <b>PA1911</b> <b>469.9 mm Std. Some Air</b> (3564137)..... <b>PA1846 +</b> <b>469.9 mm Some Air</b> (Upgrade) (3564137)..... <b>PA1846XP</b> <b>419.1 mm O. Air</b> (3564118)..... <b>PA1885 +</b> <b>406.4 mm I. Air</b> (3564119)..... <b>PA1893</b>
	GR260 w/MIDS 06.35.40 Eng. <b>Lube</b> (504020)..... <b>B403</b> <b>Fuel</b> (3036404)..... <b>BF797</b> <b>342.9 mm O. Air</b> (3564117)..... <b>PA1884 +</b> <b>330.2 mm I. Air</b> (3564115)..... <b>PA1911</b> <b>419.1 mm Some O. Air</b> (3564118)..... <b>PA1885 +</b> <b>406.4 mm Some I. Air</b> (3564119). <b>PA1893</b>	Kerax 270 w/dCi11 Eng. (11/01-on) <b>F-F Lube</b> ..... <b>B76 +</b> <b>B-P Lube Spinner</b> ..... <b>BC7173</b> <b>Opt. Fuel/Water Separator</b> (Racor Hsg.) (Racor 2010PM)..... <b>PF598-30</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)
Kerax 270 w/dCi11 Eng. (11/01-on) (Cont'd)	Midlum 270.12 w/dCi6 Eng. (11/01-on) (Cont'd)	Midlum 270.14 w/dCi6 Eng. (11/01-on) (Cont'd)
Fuel..... <b>BF7886</b>	Trans. (w/ZF Ecosplit Gearbox) (ZF 750131003)..... <b>PT8385</b>	Steering..... <b>P106-HD</b>
Opt. Fuel/Water Separator (R.V.I. Hsg.) (5000790559)..... <b>CLN&amp;R</b>	Steering..... <b>P106-HD</b>	Midlum 270.16 w/dCi6 Eng. (11/01-on)
Radial Seal O. Air..... <b>RS3728</b>	Midlum II 270.12 Dxi, 270.13 Dxi, 270.14 Dxi, 270.16 Dxi, 270.18 Dxi w/Dxi7 Eng. (07/09-on)	Lube..... <b>B76 +</b>
Radial Seal I. Air..... <b>RS3729</b>	Lube (7420796782)..... <b>P7329</b>	Opt. Fuel/Water Separator (Racor Hsg.) (Racor 2010PM)..... <b>PF598-30</b>
Air Dryer (Mann TB1374X)..... <b>BA5374 +</b>	Fuel/Water Separator (7420851191)..... <b>BF1388-O</b>	Fuel..... <b>BF7886</b>
Trans. (ZF 7633141101)..... <b>PT691</b>	Fuel (7420796772)..... <b>PF7938</b>	Opt. Fuel/Water Separator (R.V.I. Hsg.) (5000790559)..... <b>CLN&amp;R</b>
Steering..... <b>P106-HD</b>	Radial Seal O. Air (5001865723)..... <b>RS5390</b>	Fuel/Water Separator (5001846015)..... <b>BF7989-D</b>
Hyd..... <b>B307</b>	Radial Seal I. Air (5010317187)..... <b>RS5351</b>	Radial Seal O. Air..... <b>RS3727</b>
Premium HD 270 Dxi w/Dxi7 Eng. (05/06-on)	Radial Seal Air (Standard Media) (5010315990)..... <b>RS5301</b>	Radial Seal O. Air (w/FRM) (5001865723)..... <b>RS5390</b>
Lube (7420796782)..... <b>P7329</b>	Radial Seal Air (Flame Retardant Media) (5001865724)..... <b>RS30236</b>	Radial Seal I. Air (5010317187)..... <b>RS5351</b>
Fuel/Water Separator (7420851191)..... <b>BF1388-O</b>	Cab Air (5001867491)..... <b>PA30188</b>	<b>161.9 mm Air Dryer</b> (Mann TB1374/3X)..... <b>BA5375</b>
Fuel (7420796772)..... <b>PF7938</b>	Air Dryer (5001865404)..... <b>BA5566</b>	<b>167.5 mm Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b>
Radial Seal O. Air (5001865723)..... <b>RS5390</b>	Steering (5000820895)..... <b>P106-HD</b>	Trans. (w/ZF Ecosplit Gearbox) (ZF 750131003)..... <b>PT8385</b>
Radial Seal I. Air (5010317187)..... <b>RS5351</b>	Urea (7420877953)..... <b>PE5271</b>	Steering..... <b>P106-HD</b>
Radial Seal O. Air (5001865725)..... <b>RS30116</b>	Midlum 270.13 w/dCi6 Eng. (11/01-on)	Midlum 270.18 w/dCi6 Eng. (11/01-on)
Radial Seal I. Air (5010269584)..... <b>RS3729</b>	Lube..... <b>B76 +</b>	Lube..... <b>B76 +</b>
Cab Air (5001867491)..... <b>PA30188</b>	Opt. Fuel/Water Separator (Racor Hsg.) (Racor 2010PM)..... <b>PF598-30</b>	Opt. Fuel/Water Separator (Racor Hsg.) (Racor 2010PM)..... <b>PF598-30</b>
Air Dryer (Wabco, Right-hand Thd.) (5001865037)..... <b>BA5379 +</b>	Fuel..... <b>BF7886</b>	Fuel..... <b>BF7886</b>
Air Dryer (Knorr, Left-hand Thd.) (5001865404)..... <b>BA5566</b>	Opt. Fuel/Water Separator (R.V.I. Hsg.) (5000790559)..... <b>CLN&amp;R</b>	Opt. Fuel/Water Separator (R.V.I. Hsg.) (5000790559)..... <b>CLN&amp;R</b>
Steering (5000820895)..... <b>P106-HD</b>	Fuel/Water Separator (5001846015)..... <b>BF7989-D</b>	Fuel/Water Separator (5001846015)..... <b>BF7989-D</b>
Urea (7420877953)..... <b>PE5271</b>	Radial Seal O. Air..... <b>RS3727</b>	Radial Seal O. Air..... <b>RS3727</b>
Premium HL 270 Dxi w/Dxi7 Eng. (05/06-on)	Radial Seal O. Air (w/FRM) (5001865723)..... <b>RS5390</b>	Radial Seal O. Air (w/FRM) (5001865723)..... <b>RS5390</b>
Lube (7420796782)..... <b>P7329</b>	Radial Seal I. Air (5010317187)..... <b>RS5351</b>	Radial Seal I. Air (5010317187)..... <b>RS5351</b>
Fuel/Water Separator (7420851191)..... <b>BF1388-O</b>	<b>161.9 mm Air Dryer</b> (Mann TB1374/3X)..... <b>BA5375</b>	<b>161.9 mm Air Dryer</b> (Mann TB1374/3X)..... <b>BA5375</b>
Fuel (7420796772)..... <b>PF7938</b>	<b>167.5 mm Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b>	<b>167.5 mm Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b>
Radial Seal O. Air (5001865723)..... <b>RS5390</b>	Trans. (w/ZF Ecosplit Gearbox) (ZF 750131003)..... <b>PT8385</b>	Trans. (w/ZF Ecosplit Gearbox) (ZF 750131003)..... <b>PT8385</b>
Radial Seal I. Air (5010317187)..... <b>RS5351</b>	Steering..... <b>P106-HD</b>	Steering..... <b>P106-HD</b>
Radial Seal O. Air (5001865725)..... <b>RS30116</b>	Midlum 270.14 w/dCi6 Eng. (11/01-on)	G270 w/MIDR 06.20.45 Eng.
Radial Seal I. Air (5010269584)..... <b>RS3729</b>	Lube..... <b>B76 +</b>	Lube (Mann W11102/11)..... <b>B76 +</b>
Cab Air (5001867491)..... <b>PA30188</b>	Opt. Fuel/Water Separator (Racor Hsg.) (Racor 2010PM)..... <b>PF598-30</b>	Fuel (Mann WK727)..... <b>BF988 +</b>
Air Dryer (Wabco, Right-hand Thd.) (5001865037)..... <b>BA5379 +</b>	Fuel..... <b>BF7886</b>	O. Air (Mann C311256)..... <b>PA3558</b>
Air Dryer (Knorr, Left-hand Thd.) (5001865404)..... <b>BA5566</b>	Opt. Fuel/Water Separator (R.V.I. Hsg.) (5000790559)..... <b>CLN&amp;R</b>	I. Air (Mann C17124)..... <b>PA3566</b>
Steering (5000820895)..... <b>P106-HD</b>	Fuel/Water Separator (5001846015)..... <b>BF7989-D</b>	Steering (8499135552)..... <b>P106</b>
Urea (7420877953)..... <b>PE5271</b>	Radial Seal O. Air..... <b>RS3727</b>	Premium HD270 w/dCi 6 Eng. (11/01-on)
Midlum 270.12 w/dCi6 Eng. (11/01-on)	Radial Seal O. Air (w/FRM) (5001865723)..... <b>RS5390</b>	F-F Lube..... <b>B76 +</b>
Lube..... <b>B76 +</b>	Radial Seal I. Air (5010317187)..... <b>RS5351</b>	B-P Lube Spinner..... <b>BC7173</b>
Opt. Fuel/Water Separator (Racor Hsg.) (Racor 2010PM)..... <b>PF598-30</b>	<b>161.9 mm Air Dryer</b> (Mann TB1374/3X)..... <b>BA5375</b>	Opt. Fuel/Water Separator (Racor Hsg.) (Racor 2010PM)..... <b>PF598-30</b>
Fuel..... <b>BF7886</b>	<b>167.5 mm Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b>	Fuel..... <b>BF7886</b>
Opt. Fuel/Water Separator (R.V.I. Hsg.) (5000790559)..... <b>CLN&amp;R</b>	Trans. (w/ZF Ecosplit Gearbox) (ZF 750131003)..... <b>PT8385</b>	Opt. Fuel/Water Separator (R.V.I. Hsg.) (5000790559)..... <b>CLN&amp;R</b>
Fuel/Water Separator (5001846015)..... <b>BF7989-D</b>		Single Radial Seal Air..... <b>RS3727</b>
Radial Seal O. Air..... <b>RS3727</b>		Radial Seal O. Air..... <b>RS3728</b>
Radial Seal O. Air (w/FRM) (5001865723)..... <b>RS5390</b>		
Radial Seal I. Air (5010317187)..... <b>RS5351</b>		
<b>161.9 mm Air Dryer</b> (Mann TB1374/3X)..... <b>BA5375</b>		
<b>167.5 mm Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)
Premium HD270 w/dCi 6 Eng. (11/01-on) (Cont'd)	C Serie C 280 w/Volvo DTI 8 Eng. (0/13-on)	GR280, GR280 (6x2) w/MDS 06.35.40 Eng.
Radial Seal O. Air (w/FRM) (5001865723)..... RS5390	<b>Fuel/Water Separator</b> (7421538977)..... BF1292-O	F-F Lube Ele. (4307426)..... PT670
Radial Seal I. Air..... RS3729	Cab Air (7482348995)..... PA30114	F-F Lube Spin-on (504020)..... B403
Air Dryer (Mann TB1374X)..... BA5374 +	Cab Air (7482379897)..... PA30113	112.7 mm Fuel Can-Type..... BF884
Trans. (w/ZF Ecosplit Gearbox) (ZF 750131003)..... PT8385	Air Dryer (5001865404)..... BA5566	71.4 mm Fuel Can-Type..... BF825 +
Steering..... P106-HD	Steering (5000820895)..... P106-HD	Fuel Spin-on..... BF988 +
Hyd..... B307	Urea (7421574991)..... PE17000	419.1 mm O. Air (3564118)..... PA1885 +
Premium HL270 w/dCi 6 Eng. (11/01-on)	CBH280, CLM280 w/MIDS 06.35.40 Eng.	406.4 mm I. Air (3564119)..... PA1893
F-F Lube..... B76 +	Lube..... B403	579.4 mm O. Air (3564110)..... PA2312
B-P Lube Spinner..... BC7173	Fuel..... BF988 +	GR280A, GRH280B, GRH280 w/MDS 06.35.40 Eng.
Opt. Fuel/Water Separator (Racor Hsg.) (Racor 2010PM)..... PF598-30	387.4 mm O. Air (5000814797)..... PA2833	F-F Lube Ele. (4307426)..... PT670
Fuel..... BF7886	369.1 mm I. Air (5000814798)..... PA2834	F-F Lube Spin-on (504020)..... B403
Opt. Fuel/Water Separator (R.V.I. Hsg.) (5000790559)..... CLN&R	398.5 mm O. Air (5010064371)..... PA3558	406.4 mm I. Air (3564119)..... PA1893
Single Radial Seal Air..... RS3727	377.8 mm I. Air (5010064372)..... PA3566	419.1 mm O. Air (3564118)..... PA1885 +
Radial Seal O. Air..... RS3728	D Serie D 280 w/Volvo DTI 8 Eng. (09/13-on)	579.4 mm O. Air (3564110)..... PA2312
Radial Seal O. Air (w/FRM) (5001865723)..... RS5390	<b>Fuel/Water Separator</b> (7421538977)..... BF1292-O	GRH280
Radial Seal I. Air..... RS3729	Radial Seal Air (Long) (5001865723)..... RS5390	141.3 mm Lube Ele. (3571013)..... P174
Air Dryer (Mann TB1374X)..... BA5374 +	Radial Seal Air (Short) (5001865724)..... RS30236	235.7 mm Lube Ele. (24568011)..... PT670
Trans. (w/ZF Ecosplit Gearbox) (ZF 750131003)..... PT8385	Radial Seal Air (5010315990)..... RS5301	Lube Spin-on (504020)..... B403
Steering..... P106-HD	Cab Air (5001867491)..... PA30188	Can-Type Fuel..... BF825 +
Hyd..... B307	Air Dryer (5001865404)..... BA5566	O. Air (3564110)..... PA2312
Midlum 280 w/Volvo DXi7 (Euro 4-5) Eng. (05/06-on)	FG280A w/MIDS 06.35.40 Eng.	Premium HD280 w/Volvo DXi7 (Euro 4-5) Eng. (05/06-on)
Lube (7420796782)..... P7329	F-F Lube (5000670670)..... B403	Lube (7420796782)..... P7329
Fuel/Water Separator (7420851191)..... BF1388-O	Fuel (3036404)..... BF797	Fuel/Water Separator (7420851191)..... BF1388-O
P. Fuel (7420796772)..... PF7938	O. Air (3564110)..... PA2312	P. Fuel (7420796772)..... PF7938
Radial Seal O. Air (5001865723)..... RS5390	G280 w/MIDR 06.20.45, MIDS 06.20.45 Eng.	Radial Seal Air (5001865723)..... RS5390
Radial Seal I. Air..... RS5351	Lube (5000670670)..... B403	Air Dryer (Wabco, Right-Hand Thd.) (5001865037)..... BA5379 +
Air Dryer (5001865404)..... BA5566	Fuel Spin-on (5000814227)..... BF988 +	Air Dryer (Knorr, Left-Hand Thd.) (5001865404)..... BA5566
Urea (7421333098)..... PE5271	Coolant (5000663625)..... BW5139	Steering..... P106-HD
Midlum II 280.12 Dxi, 280.13 Dxi, 280.14 Dxi, 280.16 Dxi, 280.18 Dxi w/Dxi7 Eng. (05/06-on)	GBH280 w/MIDS 06.35.40 Eng.	Urea (7421333098)..... PE5271
Lube (7420796782)..... P7329	Lube (5000670670)..... B403	SM280 w/M.A.N. V2658 Eng.
Fuel/Water Separator (7420851191)..... BF1388-O	Fuel Spin-on (5000790570)..... BF988 +	F-F Lube Ele. (7701009924)..... P721
Fuel (7420796772)..... PF7938	406.4 mm I. Air (3564119)..... PA1893	P. Fuel Ele. (4125030024)..... F950-F
Radial Seal O. Air (5001865723)..... RS5390	419.1 mm O. Air (3564118)..... PA1885 +	S. Fuel Ele..... PF231
Radial Seal I. Air (5010317187)..... RS5351	469.9 mm Std. Some Air (5000819343)..... PA1846 +	TBH280 w/MIDS 06.35.40 Eng.
Radial Seal Air (Standard Media) (5010315990)..... RS5301	469.9 mm Some Air (Upgrade) (5000819343)..... PA1846XP	Lube Spin-on (5000670670)..... B403
Radial Seal Air (Flame Retardant Media) (5001865724)..... RS30236	GLM280 w/MIDS 06.35.40 Eng.	Fuel Spin-on (5000790570)..... BF988 +
Cab Air (5001867491)..... PA30188	Lube (5000670670)..... B403	419.1 mm O. Air (3564118)..... PA1885 +
Air Dryer (5001865404)..... BA5566	Fuel (5000790570)..... BF988 +	406.4 mm I. Air (3564119)..... PA1893
Steering (5000820895)..... P106-HD	419.1 mm O. Air (3564118)..... PA1885 +	469.9 mm Std. Air (5000819343)..... PA1846 +
Urea (7420877953)..... PE5271	406.4 mm I. Air (3564119)..... PA1893	469.9 mm Air (Upgrade) (5000819343)..... PA1846XP
	469.9 mm Std. Some Air (5000819343)..... PA1846 +	TLM280 w/MIDS 06.35.40 Eng.
	469.9 mm Some Air (Upgrade) (5000819343)..... PA1846XP	Lube Spin-on (5000670670)..... B403
	GLM280, GLR280	Fuel Spin-on..... BF988 +
	O. Air (3564118)..... PA1885 +	419.1 mm O. Air..... PA1885 +
	I. Air (3564119)..... PA1893	406.4 mm I. Air (3564119)..... PA1893
		469.9 mm Some Air (5000819343)..... PA1846 +
		469.9 mm Air (Upgrade) (5000819343)..... PA1846XP

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)
TLR280, TLR280A, TLR280C, TLR280E w/MIDS 06.35.40 Eng. Lube Ele. (25568011)..... <b>PT670</b> Lube Spin-on (5000670670)..... <b>B403</b> 419.1 mm O. Air (3564118)..... <b>PA1885 +</b> 579.4 mm O. Air..... <b>LL2312</b> I. Air..... <b>PA1893</b>	Kerax 300 w/MIDR 06.20.45 Eng. (09/97-on) (Cont'd) Trans. (ZF 7633141101)..... <b>PT691</b> Steering (Iveco 1902137)..... <b>P106-HD</b> Gearbox Hyd. (5000791145)..... <b>B307</b> Premium 300 w/MIDR 06.02.45 Eng. F-F Lube (5000670700)..... <b>B76 +</b> B-P Lube Spinner (5000670737)..... <b>BC110</b> Fuel (22852800)..... <b>BF988 +</b> Fuel/Water Separator..... <b>BF1221 +</b> Radial Seal O. Air (5010230916)..... <b>RS3728</b> Radial Seal I. Air (5010269584)..... <b>RS3729</b> Single Radial Seal Air (5010230841)..... <b>RS3727</b> Steering (Iveco 1902137)..... <b>P106-HD</b> Gearbox Hyd. (5000791145)..... <b>B307</b>	G300, G300T w/MIDR 06.20.25D Eng. (Cont'd) <b>115.1 mm B-P Lube Spinner</b> (Mack 57GC2187)..... <b>BC7173</b> Fuel (5000814227)..... <b>BF988 +</b> O. Air (5010094094)..... <b>PA3558</b> I. Air (5010064372)..... <b>PA3566</b>
TR280, TR280A Lube Ele. (4307426)..... <b>PT670</b> Lube Spin-on (5000670670)..... <b>B403</b> Can-Type Fuel (7701028181)..... <b>BF884</b> Fuel Spin-on (3036404)..... <b>BF797</b> O. Air (3564110)..... <b>PA2312</b>	300 Radial Seal Air (5010230841)..... <b>RS3727</b>	GR300 w/MIDR 06.20.25D Eng. F-F Lube..... <b>B76 +</b> B-P Lube Spinner..... <b>BC110</b> Fuel (5000814227)..... <b>BF988 +</b> O. Air (5010094094)..... <b>PA3558</b> I. Air (5010064372)..... <b>PA3566</b>
TR280 Turbo, TR280T 141.3 mm Lube Ele. (3571013).... <b>P174</b> 235.7 mm Lube Ele. (24568011).... <b>PT670</b> Lube Spin-on (Fram C7549)..... <b>B403</b> Can-Type Fuel..... <b>BF825 +</b> O. Air (3564110)..... <b>PA2312</b>	Midlum II 300.12 Dxi, 300.13 Dxi, 300.14 Dxi, 300.16 Dxi, 300.18 Dxi w/Dxi7 Eng. (05/06-on) Lube (7420796782)..... <b>P7329</b> Fuel/Water Separator (7420851191)..... <b>BF1388-O</b> Fuel (7420796772)..... <b>PF7938</b> Radial Seal O. Air (5001865723)..... <b>RS5390</b> Radial Seal I. Air (5010317187).... <b>RS5351</b> Radial Seal Air (Standard Media) (5010315990)..... <b>RS5301</b> Radial Seal Air (Flame Retardant Media) (5001865724)..... <b>RS30236</b> Cab Air (5001867491)..... <b>PA30188</b> Air Dryer (5001865404)..... <b>BA5566</b> Steering (5000820895)..... <b>P106-HD</b> Urea (7420877953)..... <b>PE5271</b>	GR300 w/MIV 835.40 Eng. <b>230.2 mm F-F Lube Ele.</b> (3139010)..... <b>P20-HD +</b> <b>235.7 mm F-F Lube Ele.</b> (25568011)..... <b>PT670</b> F-F Lube Spin-on (5000670670).... <b>B403</b> O. Air (3564110)..... <b>PA2312</b>
TRL280, TRL280C 141.3 mm Lube Ele. (3571013).... <b>P174</b> 235.7 mm Lube Ele. (24568011).... <b>PT670</b> Lube Spin-on (5000670670)..... <b>B403</b> Can-Type Fuel..... <b>BF825 +</b> O. Air..... <b>LL2312</b>	C300 (1991) F-F Lube (5000670670)..... <b>B403</b> B-P Lube Spinner (5000670737).... <b>BC110</b> Fuel (5000790570)..... <b>BF988 +</b> O. Air (5010094092)..... <b>PA3699</b>	Premium HD300 w/MIDR 06.20.45 Eng. (04/96-on) F-F Lube..... <b>B76 +</b> B-P Lube Spinner..... <b>BC110</b> Opt. Fuel/Water Separator (Racor Hsg.) (Racor 2010PM)..... <b>PF598-30</b> Fuel..... <b>BF988 +</b> Opt. Fuel/Water Separator (R.V.I. Hsg.) (5000790559)..... <b>CLN&amp;R</b> Radial Seal O. Air..... <b>RS3727</b> Radial Seal O. Air (w/FRM) (5001865723)..... <b>RS5390</b> Radial Seal I. Air (5010317187).... <b>RS5351</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Trans. (w/ZF Ecosplit Gearbox) (ZF 750131003)..... <b>PT8385</b> Steering..... <b>P106-HD</b> Hyd..... <b>B307</b>
C290 w/MIDR 06.20.45 Eng. Lube (5000670670)..... <b>B403</b> Fuel (5000814227)..... <b>BF988 +</b> 398.5 mm O. Air (5010064371).... <b>PA3558</b> 377.8 mm I. Air (5010064372).... <b>PA3566</b> 419.1 mm O. Air (3564118)..... <b>PA1885 +</b> 406.4 mm I. Air (3564119)..... <b>PA1893</b> 423.9 mm Some Air (5000953712)..... <b>PA2945</b> Coolant (5000663625)..... <b>BW5139</b> Steering (5000820895)..... <b>P106-HD</b>	CCH300 w/MIDR 06.20.45 D3 EURO1 Eng. (1993) F-F Lube (5000670670)..... <b>B403</b> B-P Lube Spinner (5000670737).... <b>BC110</b> Fuel (5000790570)..... <b>BF988 +</b> O. Air (5010094092)..... <b>PA3699</b>	SM300, SM300VT w/M.A.N. V2658 Eng. F-F Lube Ele. (7701009924)..... <b>P721</b> P. Fuel Ele. (4125030024)..... <b>F950-F</b> S. Fuel Ele..... <b>PF231</b>
C290T Lube (5000670670)..... <b>B403</b> Fuel Spin-on (5000814227)..... <b>BF988 +</b> O. Air (3564118)..... <b>PA1885 +</b> I. Air (3564119)..... <b>PA1893</b> Coolant (5000663625)..... <b>BW5139</b> Steering (5000820895)..... <b>P106-HD</b>	G300 w/MIDR 06.20.45 Eng. Lube (Mann W11102/11)..... <b>B76 +</b> Fuel (Mann WK727)..... <b>BF988 +</b> 388.9 mm O. Air (3564105)..... <b>PA2418-FN +</b> 358.0 mm I. Air (3564106)..... <b>PA2419</b> 398.5 mm O. Air (Mann C311256)..... <b>PA3558</b> 377.8 mm Air (Mann C17124)..... <b>PA3566</b>	TR300 w/MIV 08.35.40 Eng. <b>230.2 mm Lube Ele.</b> (3139010).... <b>P20-HD +</b> <b>235.7 mm Lube Ele.</b> (25568011).... <b>PT670</b> Lube Spin-on (5000670670)..... <b>B403</b> O. Air..... <b>LL2312</b>
G290 w/MIDR 06.20.45, MIDS 06.20.45 Eng. Lube (5000670670)..... <b>B403</b> Fuel Spin-on (5000814227)..... <b>BF988 +</b> Coolant (5000663625)..... <b>BW5139</b>	Kerax 300 w/MIDR 06.20.45 Eng. (09/97-on) F-F Lube (5000670700)..... <b>B76 +</b> Opt. Fuel/Water Separator (Racor Hsg.) (Racor 2010PM)..... <b>PF598-30</b> Fuel (5000790570)..... <b>BF988 +</b> Opt. Fuel/Water Separator (R.V.I. Hsg.) (5000790559)..... <b>CLN&amp;R</b> Radial Seal O. Air (5010230916).... <b>RS3728</b> Radial Seal I. Air (5010269584).... <b>RS3729</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b>	GR305, GRH305 w/MIDR 06.35.40 Eng. Lube (504020)..... <b>B403</b> O. Air (3564110)..... <b>PA2312</b>
		TR305, TR305H w/06.35.40 Eng. Lube Spin-on (5000670670)..... <b>B403</b> O. Air (3564110)..... <b>PA2312</b>
		Premium HD 310 Dxi w/Dxi7 Eng. (05/06-on) Lube (7420796782)..... <b>P7329</b> Fuel/Water Separator (7420851191)..... <b>BF1388-O</b> Fuel (7420796772)..... <b>PF7938</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.




**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

**Trucks & Buses Applications** **BALDWIN FILTERS**

R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)
Premium HD 310 Dxi w/Dxi7 Eng. (05/06-on) (Cont'd)	Kerax 320 w/dCi11 Eng. (11/01-on) (Cont'd) Hyd..... <b>B307</b>	GR320, GR320B w/MIV 08.35.40 Eng. (Cont'd) F-F Lube Spin-on (5000670670). <b>B403</b> O. Air (3564110)..... <b>PA2312</b>
Radial Seal O. Air (5001865723). <b>RS5390</b> Radial Seal I. Air (5010317187)... <b>RS5351</b> Radial Seal O. Air (5001865725). <b>RS30116</b> Radial Seal I. Air (5010269584)... <b>RS3729</b> Cab Air (5001867491)..... <b>PA30188</b> Air Dryer (Wabco, Right-hand Thd.) (5001865037)..... <b>BA5379 +</b> Air Dryer (Knorr, Left-hand Thd.) (5001865404)..... <b>BA5566</b> Steering (5000820895)..... <b>P106-HD</b> Urea (7420877953)..... <b>PE5271</b>	Premium HL 320 Dci w/Dci 11-320 Eng. (02/04-on) F-F Lube (5000670699)..... <b>B76 +</b> B-P Lube Spinner (5010437356). <b>BC7173</b> Severe Service F-F Lube (5000670699)..... <b>B76-SS +</b> Fuel (5001853860)..... <b>BF7886</b> Radial Seal O. Air (465.9 mm) (5010230841)..... <b>RS3727</b> Radial Seal I. Air (5010317187)... <b>RS5351</b> Radial Seal O. Air (555.6 mm) (5010230916)..... <b>RS3728</b> Radial Seal I. Air (5010269584)... <b>RS3729</b> Cab Air (05/06-on) (5001867491) <b>PA30188</b> Air Dryer (Wabco, Right-hand Thd.) (5001865037)..... <b>BA5379 +</b> Air Dryer (Knorr, Left-hand Thd.) (5001865404)..... <b>BA5566</b> Steering (5000820895)..... <b>P106-HD</b>	Premium HD320 w/Volvo DXi7 (Euro 4-5) Eng. (05/06-on) Lube (7420796782)..... <b>P7329</b> Fuel/Water Separator (7420851191)..... <b>BF1388-O</b> P. Fuel (7420796772)..... <b>PF7938</b> Radial Seal Air (5001865723)..... <b>RS5390</b> Air Dryer (Wabco, Right-Hand Thd.) (5001865037)..... <b>BA5379 +</b> Air Dryer (Knorr, Left-Hand Thd.) (5001865404)..... <b>BA5566</b> Steering..... <b>P106-HD</b> Urea (7421333098)..... <b>PE5271</b>
Premium HL 310 Dxi w/Dxi7 Eng. (05/06-on) Lube (7420796782)..... <b>P7329</b> Fuel/Water Separator (7420851191)..... <b>BF1388-O</b> Fuel (7420796772)..... <b>PF7938</b> Radial Seal O. Air (5001865723). <b>RS5390</b> Radial Seal I. Air (5010317187)... <b>RS5351</b> Radial Seal O. Air (5001865725). <b>RS30116</b> Radial Seal I. Air (5010269584)... <b>RS3729</b> Cab Air (5001867491)..... <b>PA30188</b> Air Dryer (Wabco, Right-hand Thd.) (5001865037)..... <b>BA5379 +</b> Air Dryer (Knorr, Left-hand Thd.) (5001865404)..... <b>BA5566</b> Steering (5000820895)..... <b>P106-HD</b> Urea (7420877953)..... <b>PE5271</b>	C Serie C 320 w/Volvo DTI 8 Eng. (0/13-on) Fuel/Water Separator (7421538977)..... <b>BF1292-O</b> Cab Air (7482348995)..... <b>PA30114</b> Cab Air (7482379897)..... <b>PA30113</b> Air Dryer (5001865404)..... <b>BA5566</b> Steering (5000820895)..... <b>P106-HD</b> Urea (7421574991)..... <b>PE17000</b>	Premium HD320 w/dCi 11 Eng. (11/01-on) F-F Lube..... <b>B76 +</b> B-P Lube Spinner..... <b>BC7173</b> Opt. Fuel/Water Separator (Racor Hsg.) (Racor 2010PM)..... <b>PF598-30</b> Fuel..... <b>BF7886</b> Opt. Fuel/Water Separator (R.V.I. Hsg.) (5000790559)..... <b>CLN&amp;R</b> Radial Seal O. Air (w/FRM) (5001865723)..... <b>RS5390</b> Radial Seal O. Air..... <b>RS3727</b> Opt. Radial Seal I. Air (5010317187)..... <b>RS5351</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Trans. (w/ZF Ecosplit Gearbox) (ZF 750131003)..... <b>PT8385</b> Steering..... <b>P106-HD</b> Hyd..... <b>B307</b>
R310 w/MIDR 06.35.40C Eng. 206.4 mm Lube Spin-on (5000670670)..... <b>B403</b> 265.1 mm Lube Spin-on (5000670700)..... <b>B76 +</b> Fuel Spin-on (5000790570)..... <b>BF988 +</b> 423.9 mm O. Air (5000953712).... <b>PA2945</b> 406.4 mm I. Air (3564119)..... <b>PA1893</b> 533.4 mm Some Air (5000819342)..... <b>PA2398</b> 579.4 mm Some Air (3564110).... <b>PA2312</b>	CBH320 (1993) Lube..... <b>B403</b> Fuel..... <b>BF988 +</b> 387.4 mm O. Air (5000814797).... <b>PA2833</b> 369.1 mm I. Air (5000814798).... <b>PA2834</b> 398.5 mm O. Air (5010064371).... <b>PA3558</b> 377.8 mm I. Air (5010064372).... <b>PA3566</b>	Premium HL320 w/dCi 6 Eng. (11/01-on) F-F Lube..... <b>B76 +</b> B-P Lube Spinner..... <b>BC7173</b> Fuel/Water Separator (Racor Hsg.)..... <b>PF598-30</b> P. Fuel..... <b>BF7886</b> Fuel/Water Separator (R.V.I. Hsg.) (5000822272)..... <b>CLN&amp;R</b> 465.9 mm Radial Seal O. Air..... <b>RS3727</b> 465.9 mm Radial Seal O. Air (w/FRM) (5001865723)..... <b>RS5390</b> 555.6 mm Radial Seal O. Air..... <b>RS3728</b> 536.6 mm Radial Seal I. Air..... <b>RS3729</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Trans. (w/ZF Ecosplit Gearbox).... <b>PT8385</b> Steering..... <b>P106-HD</b> Hyd..... <b>B307</b>
TR310 Lube Spin-on (5000670670)..... <b>B403</b> Fuel Spin-on..... <b>BF988 +</b> 517.5 mm O. Air..... <b>PA2461</b> 533.4 mm O. Air (3564135)..... <b>PA2398</b> 579.4 mm O. Air..... <b>LL2312</b>	D Serie D 320 w/Volvo DTI 8 Eng. (09/13-on) Fuel/Water Separator (7421538977)..... <b>BF1292-O</b> Radial Seal Air (Long) (5001865723)..... <b>RS5390</b> Radial Seal Air (Short) (5001865724)..... <b>RS30236</b> Radial Seal Air (5010315990)..... <b>RS5301</b> Cab Air (5001867491)..... <b>PA30188</b> Air Dryer (5001865404)..... <b>BA5566</b>	Premium HR320 w/dCi 11 Eng. (11/01-on) F-F Lube..... <b>B76 +</b> B-P Lube Spinner..... <b>BC7173</b> Opt. Fuel/Water Separator (Racor Hsg.) (Racor 2010PM)..... <b>PF598-30</b> Fuel..... <b>BF7886</b>
Kerax 320 w/dCi11 Eng. (11/01-on) F-F Lube..... <b>B76 +</b> B-P Lube Spinner..... <b>BC7173</b> Opt. Fuel/Water Separator (Racor Hsg.) (Racor 2010PM)..... <b>PF598-30</b> Fuel..... <b>BF7886</b> Opt. Fuel/Water Separator (R.V.I. Hsg.) (5000790559)..... <b>CLN&amp;R</b> Radial Seal O. Air..... <b>RS3728</b> Radial Seal I. Air..... <b>RS3729</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Steering..... <b>P106-HD</b>	G320, G320GT Lube (5000670700)..... <b>B76 +</b> Fuel (5000790570)..... <b>BF988 +</b> 398.5 mm O. Air (5010064371).... <b>PA3558</b> 377.8 mm I. Air (5010064372).... <b>PA3566</b> 388.9 mm O. Air (5010094146).... <b>PA3699</b> Steering (5000820895)..... <b>P106-HD</b>	
	GR320, GR320B w/MIV 08.35.40 Eng. 230.2 mm F-F Lube Ele. (3139010)..... <b>P20-HD +</b> 235.7 mm F-F Lube Ele. (25568011)..... <b>PT670</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).


R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)
Premium HR320 w/dCi 11 Eng. (11/01-on) (Cont'd)	R330 w/MIDR 06.35.40C Eng. (Cont'd)	CLM340 w/MIDS 06.35.40 Eng.
Opt. Fuel/Water Separator (R.V.I. Hsg.) (5000790559)..... <b>CLN&amp;R</b>	406.4 mm I. Air (3564119)..... <b>PA1893</b>	Lube (5000670670)..... <b>B403</b>
Radial Seal O. Air..... <b>RS3727</b>	533.4 mm Some Air (5000819342)..... <b>PA2398</b>	Fuel (5000790570)..... <b>BF988 +</b>
Radial Seal O. Air (w/FRM) (5001865723)..... <b>RS5390</b>	579.4 mm Some Air (3564110).... <b>PA2312</b>	O. Air (5010064371)..... <b>PA3558</b>
Opt. Radial Seal I. Air (5010317187)..... <b>RS5351</b>	Kerax 340 w/MIDR 06.20.45 Eng. (09/97-on)	I. Air (5010064372)..... <b>PA3566</b>
Air Dryer (Mann TB1374X)..... <b>BA5374 +</b>	F-F Lube (5000670700)..... <b>B76 +</b>	G340TI w/MIDR 06.35.45 Eng.
Trans. (w/ZF Ecosplit Gearbox) (ZF 750131003)..... <b>PT8385</b>	B-P Lube Spinner (5000670737). <b>BC110</b>	F-F Lube (5000670700)..... <b>B76 +</b>
Steering..... <b>P106-HD</b>	Opt. Fuel/Water Separator (Racor Hsg.) (Racor 2010PM)..... <b>PF598-30</b>	B-P Lube Spinner (5000670737). <b>BC110</b>
Hyd..... <b>B307</b>	Fuel (5000790570)..... <b>BF988 +</b>	Fuel (5000790570)..... <b>BF988 +</b>
TR320, TR320A, TRH320 (4x4) w/MIV 08.35.40 Eng.	Opt. Fuel/Water Separator (R.V.I. Hsg.) (5000790559)..... <b>CLN&amp;R</b>	398.5 mm O. Air (5010094094).... <b>PA3558</b>
230.2 mm F-F Lube Ele..... <b>P20-HD +</b>	Radial Seal O. Air (5010230916). <b>RS3728</b>	377.8 mm I. Air (5000751590).... <b>PA3566</b>
235.7 mm F-F Lube Ele..... <b>PT670</b>	Radial Seal I. Air (5010269584)... <b>RS3729</b>	388.9 mm Some O. Air (5010094092)..... <b>PA3699</b>
Lube Spin-on (5000670670)..... <b>B403</b>	Air Dryer (Mann TB1374X)..... <b>BA5374 +</b>	Coolant (5000592852)..... <b>BW5139</b>
O. Air..... <b>PA2398</b>	Trans. (ZF 7633141101)..... <b>PT691</b>	GT340TI w/MIDR 06.35.45 Eng. (1990)
TRH320 (6x4) w/MIVS 08.35.40 Eng.	Steering (Iveco 1902137)..... <b>P106-HD</b>	F-F Lube (5000670670)..... <b>B403</b>
Lube Ele. (25568011)..... <b>PT670</b>	Gearbox Hyd. (5000791145)..... <b>B307</b>	B-P Lube Spinner (5000670737). <b>BC110</b>
Lube Spin-on (5000670670)..... <b>B403</b>	Premium HD 340 Dxi w/Dxi7 Eng. (05/06-on)	Fuel Spin-on (5000790570)..... <b>BF988 +</b>
O. Air (5000819342)..... <b>PA2398</b>	Lube (7420796782)..... <b>P7329</b>	398.5 mm O. Air (5010094094).... <b>PA3558</b>
Premium HR330 w/Volvo DXi 11 Eng. (10/05-on)	Fuel/Water Separator (7420851191)..... <b>BF1388-O</b>	377.8 mm I. Air (5000751590).... <b>PA3566</b>
F-F Lube..... <b>B76-SS +</b>	Fuel (7420796772)..... <b>PF7938</b>	388.9 mm Some O. Air (5010094092)..... <b>PA3699</b>
B-P Lube..... <b>B7685</b>	Radial Seal O. Air (5001865723). <b>RS5390</b>	Coolant (5000592852)..... <b>BW5139</b>
P. Fuel..... <b>BF7814</b>	Radial Seal I. Air (5010317187)... <b>RS5351</b>	Premium HD340 w/MIDR 06.20.45 Eng. (04/96-on)
Fuel/Water Separator (7420541383)..... <b>BF1366-O</b>	Radial Seal O. Air (5001865725). <b>RS30116</b>	F-F Lube..... <b>B76 +</b>
Radial Seal O. Air (w/FRM) (5001865723)..... <b>RS5390</b>	Radial Seal I. Air (5010269584)... <b>RS3729</b>	B-P Lube Spinner..... <b>BC110</b>
Opt. Radial Seal I. Air (5010317187)..... <b>RS5351</b>	Cab Air (5001867491)..... <b>PA30188</b>	Opt. Fuel/Water Separator (Racor Hsg.) (Racor 2010PM)..... <b>PF598-30</b>
Air Dryer (Wabco, Right-Hand Thd.) (5001865037)..... <b>BA5379 +</b>	Air Dryer (Wabco, Right-hand Thd.) (5001865037)..... <b>BA5379 +</b>	Fuel..... <b>BF988 +</b>
Air Dryer (Knorr, Left-Hand Thd.) (5001865404)..... <b>BA5566</b>	Air Dryer (Knorr, Left-hand Thd.) (5001865404)..... <b>BA5566</b>	Opt. Fuel/Water Separator (R.V.I. Hsg.) (5000790559)..... <b>CLN&amp;R</b>
Trans. (Automatic Gearbox) (7485105048)..... <b>PT9417</b>	Steering (5000820895)..... <b>P106-HD</b>	Radial Seal O. Air..... <b>RS3727</b>
Steering..... <b>P106-HD</b>	Urea (7420877953)..... <b>PE5271</b>	Radial Seal O. Air (w/FRM) (5001865723)..... <b>RS5390</b>
Urea (7421333098)..... <b>PE5271</b>	Premium HL 340 Dxi w/Dxi7 Eng. (05/06-on)	Opt. Radial Seal I. Air (5010317187)..... <b>RS5351</b>
K330 w/MIDR 06.35.40 Eng. (1989)	Lube (7420796782)..... <b>P7329</b>	Air Dryer (Mann TB1374X)..... <b>BA5374 +</b>
Lube Spin-on (5000670670)..... <b>B403</b>	Fuel/Water Separator (7420851191)..... <b>BF1388-O</b>	Trans. (w/ZF Ecosplit Gearbox) (ZF 750131003)..... <b>PT8385</b>
Fuel Spin-on (5000790570)..... <b>BF988 +</b>	Fuel (7420796772)..... <b>PF7938</b>	Steering..... <b>P106-HD</b>
406.4 mm I. Air (3564119)..... <b>PA1893</b>	Radial Seal O. Air (5001865723). <b>RS5390</b>	Hyd..... <b>B307</b>
423.9 mm O. Air (5000953712).... <b>PA2945</b>	Radial Seal I. Air (5010317187)... <b>RS5351</b>	Premium HR340 w/MIDR 06.20.45 Eng. (04/96-on)
533.4 mm O. Air (5000819342).... <b>PA2398</b>	Radial Seal O. Air (5001865725). <b>RS30116</b>	F-F Lube..... <b>B76 +</b>
579.4 mm O. Air (3564110)..... <b>PA2312</b>	Radial Seal I. Air (5010269584)... <b>RS3729</b>	B-P Lube Spinner..... <b>BC110</b>
R330 w/MIDR 06.35.40C Eng.	Cab Air (5001867491)..... <b>PA30188</b>	Opt. Fuel/Water Separator (Racor Hsg.) (Racor 2010PM)..... <b>PF598-30</b>
206.4 mm Lube Spin-on (5000670670)..... <b>B403</b>	Air Dryer (Wabco, Right-hand Thd.) (5001865037)..... <b>BA5379 +</b>	Fuel..... <b>BF988 +</b>
265.1 mm Lube Spin-on (5000670700)..... <b>B76 +</b>	Air Dryer (Knorr, Left-hand Thd.) (5001865404)..... <b>BA5566</b>	Opt. Fuel/Water Separator (R.V.I. Hsg.) (5000790559)..... <b>CLN&amp;R</b>
Fuel Spin-on (5000790570)..... <b>BF988 +</b>	Steering (5000820895)..... <b>P106-HD</b>	Radial Seal O. Air..... <b>RS3727</b>
423.9 mm O. Air (5000953712).... <b>PA2945</b>	Urea (7420877953)..... <b>PE5271</b>	Radial Seal O. Air (w/FRM) (5001865723)..... <b>RS5390</b>
	CBH340 w/MIDS 06.35.40 Eng.	Opt. Radial Seal I. Air (5010317187)..... <b>RS5351</b>
	Lube (Fram) (5000670670)..... <b>B403</b>	Air Dryer (Mann TB1374X)..... <b>BA5374 +</b>
	Fuel..... <b>BF988 +</b>	
	387.4 mm O. Air (5000814797).... <b>PA2833</b>	
	369.1 mm I. Air (5000814798).... <b>PA2834</b>	
	398.5 mm O. Air (5010064371).... <b>PA3558</b>	
	377.8 mm I. Air (5010064372).... <b>PA3566</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)
Premium HR340 w/MIDR 06.20.45 Eng. (04/96-on) (Cont'd) Trans. (w/ZF Ecosplit Gearbox) (ZF 750131003)..... <b>PT8385</b> Steering..... <b>P106-HD</b> Hyd..... <b>B307</b>	TR350 w/MIVS 08.35.40 Eng. Lube Spin-on (5000670670)..... <b>B403</b> O. Air..... <b>PA2398</b>	Premium HL 370 Dci w/Dci 11-370 Eng. (02/04-on) (Cont'd) Radial Seal I. Air (5010317187)... <b>RS5351</b> Radial Seal O. Air (555.6 mm) (5010230916)..... <b>RS3728</b> Radial Seal I. Air (5010269584)... <b>RS3729</b> Cab Air (05/06-on) (5001867491) <b>PA30188</b> Air Dryer (Wabco, Right-hand Thd.) (5001865037)..... <b>BA5379 +</b> Air Dryer (Knorr, Left-hand Thd.) (5001865404)..... <b>BA5566</b> Steering (5000820895)..... <b>P106-HD</b>
R340 w/MIDR 06.20.45 Eng. Lube (Mann W11102/11)..... <b>B76 +</b> Fuel (Mann WK727)..... <b>BF988 +</b> Air (3564110)..... <b>PA2312</b> Some Air (Mann C331605)..... <b>PA2398</b>	TRH350, TRH350TS w/MIVS 08.35.40 Eng. O. Air (5000819342)..... <b>PA2398</b>	R340 w/MIDR 06.35.40C Eng. 206.4 mm Lube Spin-on (5000670670)..... <b>B403</b> 265.1 mm Some Lube Spin-on (5000670700)..... <b>B76 +</b> Fuel Spin-on (5000790570)..... <b>BF988 +</b> 423.9 mm O. Air (5000953712).... <b>PA2945</b> 406.4 mm I. Air (3564119)..... <b>PA1893</b> 533.4 mm Some Air (5000819342)..... <b>PA2398</b> 579.4 mm Some Air (3564110).... <b>PA2312</b>
R340 w/MIDR 06.35.40C Eng. 206.4 mm Lube Spin-on (5000670670)..... <b>B403</b> 265.1 mm Some Lube Spin-on (5000670700)..... <b>B76 +</b> Fuel Spin-on (5000790570)..... <b>BF988 +</b> 423.9 mm O. Air (5000953712).... <b>PA2945</b> 406.4 mm I. Air (3564119)..... <b>PA1893</b> 533.4 mm Some Air (5000819342)..... <b>PA2398</b> 579.4 mm Some Air (3564110).... <b>PA2312</b>	R360, R360 Turbo w/MIVR 08.35.30, MIVS 08.35.40 Eng. Lube Spin-on (5000670670)..... <b>B403</b> Fuel Spin-on (5000814227)..... <b>BF988 +</b> 533.4 mm O. Air (5000819342).... <b>PA2398</b> 579.4 mm Some Air (3564110).... <b>PA2312</b> Coolant (5000663625)..... <b>BW5139</b>	Kerax 370 DXi w/Volvo DXi11 Euro 4/5 Eng. (05/06-on) F-F Lube..... <b>B76-SS +</b> B-P Lube..... <b>B7685</b> Fuel/Water Separator (7420514654)..... <b>BF1366-O</b> P. Fuel..... <b>BF7814</b> Fuel/Water Separator (7420754418)..... <b>BF9867-O</b> Single Radial Seal Air (5001865723)..... <b>RS5390</b> Radial Seal O. Air..... <b>RS3728</b> Radial Seal I. Air..... <b>RS3729</b> Air Dryer (Wabco, Right-Hand thread) (5001865037)..... <b>BA5379 +</b> Air Dryer (Knorr, Left-Hand thread) (5001865404)..... <b>BA5566</b> Trans. (Automatic Gearbox) (7485105048)..... <b>PT9417</b> Steering..... <b>P106-HD</b> Urea (7420877950)..... <b>PE5271</b>
R340TI w/MIDR 06.20.45 Eng. (1990) F-F Lube (5000670700)..... <b>B76 +</b> B-P Lube Spinner (5000670737). <b>BC110</b> Fuel Spin-on (5000790570)..... <b>BF988 +</b> 398.5 mm Air (5010094094)..... <b>PA3558</b> 579.4 mm Some Air..... <b>LL2312</b>	R365 w/MIDR 06.35.40C Eng. 206.4 mm Lube Spin-on (5000670670)..... <b>B403</b> 265.1 mm Some Lube Spin-on (5000670700)..... <b>B76 +</b> Fuel Spin-on (5000790570)..... <b>BF988 +</b> 423.9 mm O. Air (5000953712).... <b>PA2945</b> 406.4 mm I. Air (3564119)..... <b>PA1893</b> 533.4 mm Some Air (5000819342)..... <b>PA2398</b> 579.4 mm Some Air (3564110).... <b>PA2312</b>	Premium HD370 w/dCi 11 Eng. (11/01-on) F-F Lube..... <b>B76 +</b> B-P Lube Spinner..... <b>BC7173</b> Opt. Fuel/Water Separator (Racor Hsg.) (Racor 2010PM).... <b>PF598-30</b> Fuel..... <b>BF7886</b> Opt. Fuel/Water Separator (R.V.I. Hsg.) (5000790559)..... <b>CLN&amp;R</b> Radial Seal O. Air (w/FRM) (5001865723)..... <b>RS5390</b> Opt. Radial Seal I. Air (5010317187)..... <b>RS5351</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Trans. (w/ZF Ecosplit Gearbox) (ZF 750131003)..... <b>PT8385</b> Steering..... <b>P106-HD</b> Hyd..... <b>B307</b>
SM340, SM340VT F-F Lube Ele. (7701006018)..... <b>P721</b> S. Fuel Ele..... <b>PF231</b>	R365 w/MIDR 06.35.40H Eng. Lube Spin-on (5000670670)..... <b>B403</b> Fuel Spin-on (5000814227)..... <b>BF988 +</b> 579.4 mm O. Air (3564110)..... <b>PA2312</b> 533.4 mm Some Air (5000819342)..... <b>PA2398</b> Coolant (5000663625)..... <b>BW5139</b>	Premium HD370 w/DXi 11 Euro 4/5 Eng. (05/06-on) F-F Lube Spin-on..... <b>B76-SS +</b> B-P Lube..... <b>B7685</b> Fuel..... <b>BF7814</b> Fuel/Water Separator (7420541383)..... <b>BF1366-O</b>
Kerax 350 w/MIDR 06.23.56 Eng. (01/03-on) F-F Lube (5010550600)..... <b>B76 +</b> B-P Lube Spinner (5000670735). <b>BC110</b> Severe Service F-F Lube (5010550600)..... <b>B76-SS +</b> Fuel (870017560)..... <b>BF988 +</b> Radial Seal O. Air (5010230916). <b>RS3728</b> Radial Seal I. Air (5010269584)... <b>RS3729</b> Air Dryer (Knorr, Left-hand Thd.) (5001865404)..... <b>BA5566</b> Air Dryer (Wabco, Right-hand Thd.) (5001865037)..... <b>BA5379 +</b> Steering (5000820895)..... <b>P106-HD</b>	Kerax 370 w/dCi11 Eng. (11/01-on) F-F Lube..... <b>B76 +</b> B-P Lube Spinner..... <b>BC7173</b> Opt. Fuel/Water Separator (Racor Hsg.) (Racor 2010PM).... <b>PF598-30</b> Fuel..... <b>BF7886</b> Opt. Fuel/Water Separator (R.V.I. Hsg.) (5000790559)..... <b>CLN&amp;R</b> Radial Seal O. Air..... <b>RS3728</b> Radial Seal I. Air..... <b>RS3729</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Trans. (ZF 7633141101)..... <b>PT691</b> Steering..... <b>P106-HD</b> Hyd..... <b>B307</b>	Premium HD370 w/dCi 11 Eng. (11/01-on) F-F Lube..... <b>B76 +</b> B-P Lube Spinner..... <b>BC7173</b> Opt. Fuel/Water Separator (Racor Hsg.) (Racor 2010PM).... <b>PF598-30</b> Fuel..... <b>BF7886</b> Opt. Fuel/Water Separator (R.V.I. Hsg.) (5000790559)..... <b>CLN&amp;R</b> Radial Seal O. Air (w/FRM) (5001865723)..... <b>RS5390</b> Opt. Radial Seal I. Air (5010317187)..... <b>RS5351</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Trans. (w/ZF Ecosplit Gearbox) (ZF 750131003)..... <b>PT8385</b> Steering..... <b>P106-HD</b> Hyd..... <b>B307</b>
CBH350 (1993) Lube (Fram C7549)..... <b>B403</b> Fuel..... <b>BF988 +</b> 387.4 mm O. Air (5000814797).... <b>PA2833</b> 369.1 mm I. Air (5000814798).... <b>PA2834</b> 398.5 mm O. Air (5010064371).... <b>PA3558</b> 377.8 mm I. Air (5010064372).... <b>PA3566</b>	Premium HL 370 Dci w/Dci 11-370 Eng. (02/04-on) F-F Lube (5000670699)..... <b>B76 +</b> B-P Lube Spinner (5010437356). <b>BC7173</b> Severe Service F-F Lube (5000670699)..... <b>B76-SS +</b> Fuel (5001853860)..... <b>BF7886</b> Radial Seal O. Air (465.9 mm) (5010230841)..... <b>RS3727</b>	Premium HD370 w/DXi 11 Euro 4/5 Eng. (05/06-on) F-F Lube Spin-on..... <b>B76-SS +</b> B-P Lube..... <b>B7685</b> Fuel..... <b>BF7814</b> Fuel/Water Separator (7420541383)..... <b>BF1366-O</b>
GR350, GRH350 w/MIVS 08.35.30 Eng. Lube (5000670670)..... <b>B403</b> O. Air (5000819342)..... <b>PA2398</b>		

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)
Premium HD370 w/DXi 11 Euro 4/5 Eng. (05/06-on) (Cont'd)	Premium HR370 w/Volvo DXi 11 Euro 4/5 Eng. (05/06-on) (Cont'd)	Kerax 380 Dxi w/Dxi 11 Euro 5 Eng. (06/09-on) (Cont'd)
Radial Seal O. Air (5001865723)..... <b>RS5390</b>	Air Dryer (Wabco, Right-Hand Thd.) (5001865037)..... <b>BA5379 +</b>	Air Dryer (Wabco, Right-hand Thd.) (5001865037)..... <b>BA5379 +</b>
Opt. Radial Seal I. Air..... <b>RS5351</b>	Air Dryer (Knorr, Left-Hand Thd.) (5001865404)..... <b>BA5566</b>	Trans. (7422051238)..... <b>PT9417</b>
Air Dryer (Wabco, Right-Hand Thd.) (5001865037)..... <b>BA5379 +</b>	Trans. (Automatic Gearbox) (7485105048)..... <b>PT9417</b>	Steering (5000820895)..... <b>P106-HD</b>
Air Dryer (Knorr, Left-Hand Thd.) (5001865404)..... <b>BA5566</b>	Steering..... <b>P106-HD</b>	Urea (7420877953)..... <b>PE5271</b>
Trans. (7485105048)..... <b>PT9417</b>	Urea (7421333098)..... <b>PE5271</b>	Premium HD 380 Dxi w/Dxi 11 Euro 4/5 Eng. (06/09-on)
Steering..... <b>P106-HD</b>	Premium HR370 w/dCi 11 Eng. (11/01-on)	F-F Lube (7420709459)..... <b>B76-SS +</b>
Urea (7421333098)..... <b>PE5271</b>	F-F Lube..... <b>B76 +</b>	B-P Lube (5001846647)..... <b>B7685</b>
Premium HL370 w/dCi 6 Eng. (11/01-on)	B-P Lube Spinner..... <b>BC7173</b>	Fuel/Water Separator (7420998346)..... <b>BF1386-O</b>
F-F Lube..... <b>B76 +</b>	Opt. Fuel/Water Separator (Racor Hsg.) (Racor 2010PM)..... <b>PF598-30</b>	Fuel/Water Separator (7420998349)..... <b>BF1387-O</b>
B-P Lube Spinner..... <b>BC7173</b>	Fuel..... <b>BF7886</b>	Fuel (7420541381)..... <b>BF7814</b>
Fuel/Water Separator (Racor Hsg.)..... <b>PF598-30</b>	Opt. Fuel/Water Separator (R.V.I. Hsg.) (5000790559)..... <b>CLN&amp;R</b>	Radial Seal O. Air (5001865723)..... <b>RS5390</b>
Fuel..... <b>BF7886</b>	Radial Seal O. Air..... <b>RS3727</b>	Radial Seal I. Air (5010317187)..... <b>RS5351</b>
Fuel/Water Separator (R.V.I. Hsg.) (5000822272)..... <b>CLN&amp;R</b>	Radial Seal O. Air (w/FRM) (5001865723)..... <b>RS5390</b>	Cab Air (5001867491)..... <b>PA30188</b>
465.9 mm Radial Seal O. Air..... <b>RS3727</b>	Opt. Radial Seal I. Air (5010317187)..... <b>RS5351</b>	Air Dryer (Wabco, Right-hand Thd.) (5001865037)..... <b>BA5379 +</b>
465.9 mm Radial Seal O. Air (w/FRM) (5001865723)..... <b>RS5390</b>	Air Dryer (Mann TB1374X)..... <b>BA5374 +</b>	Air Dryer (Knorr, Left-hand Thd.) (5001865404)..... <b>BA5566</b>
555.6 mm Radial Seal O. Air..... <b>RS3728</b>	Trans. (w/ZF Ecosplit Gearbox) (ZF 750131003)..... <b>PT8385</b>	Trans. (7422051238)..... <b>PT9417</b>
536.6 mm Radial Seal I. Air..... <b>RS3729</b>	Steering..... <b>P106-HD</b>	Steering (5000820895)..... <b>P106-HD</b>
Air Dryer (Mann TB1374X)..... <b>BA5374 +</b>	Hyd..... <b>B307</b>	Urea (7420877953)..... <b>PE5271</b>
Trans. (w/ZF Ecosplit Gearbox)..... <b>PT8385</b>	R370 w/MIVR 08.35.30, MIVS 08.35.40 Eng.	Premium HL370 w/Volvo DXi 11 Euro 4/5 Eng. (06/09-on)
Steering..... <b>P106-HD</b>	Lube Spin-on (5000670670)..... <b>B403</b>	F-F Lube (7420709459)..... <b>B76-SS +</b>
Hyd..... <b>B307</b>	Fuel Spin-on (5000814227)..... <b>BF988 +</b>	B-P Lube (5001846647)..... <b>B7685</b>
Premium HL370 w/Volvo DXi 11 Euro 4/5 Eng. (05/06-on)	533.4 mm O. Air (5000819342)..... <b>PA2398</b>	Fuel/Water Separator (7420998346)..... <b>BF1386-O</b>
F-F Lube..... <b>B76-SS +</b>	579.4 mm Some Air (3564110)..... <b>PA2312</b>	Fuel/Water Separator (7420998349)..... <b>BF1387-O</b>
B-P Lube..... <b>B7685</b>	Coolant (5000663625)..... <b>BW5139</b>	Fuel (7420541381)..... <b>BF7814</b>
P. Fuel..... <b>BF7814</b>	R370T	Radial Seal O. Air (5001865723)..... <b>RS5390</b>
Fuel/Water Separator (7420541383)..... <b>BF1366-O</b>	O. Air (5000819342)..... <b>PA2398</b>	Radial Seal I. Air (5010317187)..... <b>RS5351</b>
Radial Seal O. Air (5001865723)..... <b>RS5390</b>	RI375 w/MIDR 06.35.40H Eng.	Cab Air (5001867491)..... <b>PA30188</b>
444.5 mm Radial Seal I. Air..... <b>RS5351</b>	Lube Spin-on (5000670670)..... <b>B403</b>	Air Dryer (Wabco, Right-hand Thd.) (5001865037)..... <b>BA5379 +</b>
Radial Seal O. Air (w/FRM) (5001865725)..... <b>RS30116</b>	Fuel Spin-on (5000814227)..... <b>BF988 +</b>	Air Dryer (Knorr, Left-hand Thd.) (5001865404)..... <b>BA5566</b>
536.6 mm Radial Seal I. Air..... <b>RS3729</b>	579.4 mm O. Air (3564110)..... <b>PA2312</b>	Trans. (7422051238)..... <b>PT9417</b>
Air Dryer (Wabco, Right-Hand Thd.) (5001865037)..... <b>BA5379 +</b>	533.4 mm Some Air (5000819342)..... <b>PA2398</b>	Steering (5000820895)..... <b>P106-HD</b>
Air Dryer (Knorr, Left-Hand Thd.) (5001865404)..... <b>BA5566</b>	Coolant (5000663625)..... <b>BW5139</b>	Urea (7420877953)..... <b>PE5271</b>
Trans. (Automatic Gearbox) (7401521527)..... <b>PT9417</b>	Kerax 380 Dxi w/Dxi 11 Euro 5 Eng. (06/09-on)	Magnum AE380, AE380.19, AE380.19T, AE380.22T, AE380.26 Airtronic w/MIDR 06.35.40H Eng. (09/90-02/00)
Trans. (Automatic Gearbox) (7485105048)..... <b>PT9417</b>	F-F Lube (7420709459)..... <b>B76-SS +</b>	F-F Lube (5000670700)..... <b>B76 +</b>
Steering..... <b>P106-HD</b>	B-P Lube (5001846647)..... <b>B7685</b>	B-P Lube Spinner (5000670737)..... <b>BC110</b>
Urea (7421333098)..... <b>PE5271</b>	B-P Lube (Upgrade) (7421561284)..... <b>B7409</b>	Fuel (5000814227)..... <b>BF988 +</b>
Premium HR370 w/Volvo DXi 11 Euro 4/5 Eng. (05/06-on)	Fuel/Water Separator (7420998346)..... <b>BF1386-O</b>	O. Air (5001834600)..... <b>PA3688</b>
F-F Lube..... <b>B76-SS +</b>	Fuel/Water Separator (7420998349)..... <b>BF1387-O</b>	I. Air (5010066387)..... <b>PA3566</b>
B-P Lube..... <b>B7685</b>	Fuel (7420541381)..... <b>BF7814</b>	Air Dryer (Mann TB1374X)..... <b>BA5374 +</b>
Fuel..... <b>BF7814</b>	Radial Seal O. Air (5001865725)..... <b>RS30116</b>	Trans. (w/ZF Ecosplit Gearbox) (ZF 750131003)..... <b>PT8385</b>
Fuel/Water Separator (7420541383)..... <b>BF1366-O</b>	Radial Seal I. Air (5010269584)..... <b>RS3729</b>	Steering (5000820895)..... <b>P106-HD</b>
Radial Seal Air (5001865723)..... <b>RS5390</b>	Cab Air (5001867491)..... <b>PA30188</b>	Hyd..... <b>B307</b>
	Air Dryer (Knorr, Left-hand Thd.) (5001865404)..... <b>BA5566</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)
C Serie C 380 w/Volvo DTI 11 Eng. (08/13-on)	K Serie K 380 w/Volvo DTI 11 Eng. (08/13-on)	Kerax 385 w/MIDR 06.23.56 Eng. (09/98-on)
F-F Lube (5001846641)..... B76 +	F-F Lube (5001846641)..... B76 +	(Cont'd)
B-P Lube (7421561284)..... B7409	B-P Lube (7421561284)..... B7409	Hyd. (5000791145)..... B307
Severe Service F-F Lube (5001846641)..... B76-SS +	Severe Service F-F Lube (5001846641)..... B76-SS +	Magnum AE385 w/MIDR 06.35.40 Eng. (09/90-02/00)
Fuel/Water Separator (7424993622)..... BF1292-O	Fuel/Water Separator (7421764968)..... BF1386-O	F-F Lube (5000670700)..... B76 +
Fuel/Water Separator (Fleetguard FS20132)..... BF46182-O	Fuel (Short) (7421764961)..... BF46131	B-P Lube Spinner (5000670737)..... BC110
Fuel (Short) (7421764961)..... BF46131	Fuel (Long) (7421764958)..... BF46117	Fuel (5000814227)..... BF988 +
Fuel (Long) (7421764958)..... BF46117	Cab Air (7482348995)..... PA30114	O. Air (5001834600)..... PA3688
Cab Air (7482348995)..... PA30114	Cab Air Pre-Filter (7482379897)..... PA30113	I. Air (5010066387)..... PA3566
Cab Air Pre-Filter (7482379897)..... PA30113	Air Dryer (5001865404)..... BA5566	Air Dryer (Mann TB1374X)..... BA5374 +
Air Dryer (5001865404)..... BA5566	Coolant (Volvo 1699830)..... BW5141	Trans. (w/ZF Ecosplit Gearbox) (ZF 750131003)..... PT8385
Coolant (Volvo 1699830)..... BW5141	Steering (5000820895)..... P106-HD	Steering..... P106-HD
Steering (5000820895)..... P106-HD	Urea (7421574991)..... PE17000	Hyd..... B307
Urea (7421574991)..... PE17000	R380 (1990)	Magnum AE385TI w/MIDR 06.35.40H Eng.
CLM380 w/MIDS 06.35.40 Eng.	Lube (5000670700)..... B76 +	F-F Lube (5000670700)..... B76 +
Lube (5000670670)..... B403	Fuel Spin-on (5000790570)..... BF988 +	B-P Lube Spinner (5000670737)..... BC110
Fuel (5000790570)..... BF988 +	O. Air (3564110)..... PA2312	Fuel (5000814227)..... BF988 +
O. Air (5010064371)..... PA3558	T Serie T 380 w/Volvo DTI 11 Eng.	O. Air (5001834600)..... PA3688
I. Air (5010064372)..... PA3566	F-F Lube (5001846641)..... B76 +	I. Air (5010066387)..... PA3566
D Serie D 380 (D wide) w/Volvo DTI 11 Eng. (01/16-on)	B-P Lube (7421561284)..... B7409	Steering (5000820895)..... P106-HD
F-F Lube (5001846641)..... B76 +	Severe Service F-F Lube (5001846641)..... B76-SS +	Premium HR385 w/MIDR 06.23.56 Eng. (04/96-on)
B-P Lube (7421561284)..... B7409	Fuel/Water Separator (7421764968)..... BF1386-O	F-F Lube (5000670700)..... B76 +
Severe Service F-F Lube (5001846641)..... B76-SS +	Fuel (Short) (7421764961)..... BF46131	B-P Lube Spinner (5000670737)..... BC110
Fuel/Water Separator (7421764968)..... BF1386-O	Fuel (Long) (7421764958)..... BF46117	Opt. Fuel/Water Separator (Racor Hsg.) (Racor 2010PM)..... PF598-30
Fuel (Short) (7421764961)..... BF46131	Cab Air (7482348995)..... PA30114	Fuel (22852800)..... BF988 +
Fuel (long) (7421764958)..... BF46117	Cab Air Pre-Filter (7482379897)..... PA30113	Fuel/Water Separator..... BF1221 +
Radial Seal O. Air (5001865723)..... RS5390	Air Dryer (5001865404)..... BA5566	Opt. Fuel/Water Separator (R.V.I. Hsg.) (5000790559)..... CLN&R
Cab Air (5001867491)..... PA30188	Coolant (Volvo 1699830)..... BW5141	Radial Seal O. Air (5010230841)..... RS3727
Air Dryer (5001865404)..... BA5566	Steering (5000820895)..... P106-HD	Radial Seal O. Air (w/FRM) (5001865723)..... RS5390
Steering (5000820895)..... P106-HD	Urea (7421574991)..... PE17000	Opt. Radial Seal I. Air (5010317187)..... RS5351
Urea (7421574991)..... PE17000	Kerax 385 w/MIDR 06.20.45 Eng.	Air Dryer (Mann TB1374X)..... BA5374 +
Premium HR380 w/Volvo DXi 11 Eng. (10/05-on)	F-F Lube (5000670700)..... B76 +	Trans. (w/ZF Ecosplit Gearbox) (ZF 750131003)..... PT8385
F-F Lube..... B76-SS +	B-P Lube Spinner (5000670737)..... BC110	Steering (Iveco 1902137)..... P106-HD
B-P Lube..... B7685	Fuel (5000790570)..... BF988 +	Hyd. (5000791145)..... B307
Fuel..... BF7814	Opt. Fuel/Water Separator..... BF1221 +	R385TI w/MIDR 06.35.40H Eng. (1991)
Fuel/Water Separator (7420541383)..... BF1366-O	465.9 mm Radial Seal O. Air (5010230841)..... RS3727	Lube (5000670700)..... B76 +
Radial Seal O. Air..... RS3727	555.6 mm Radial Seal O. Air (5010230916)..... RS3728	Fuel Spin-on (5000814227)..... BF988 +
Radial Seal O. Air (w/FRM) (5001865723)..... RS5390	536.6 mm Radial Seal I. Air (5010269584)..... RS3729	Air (3564110)..... PA2312
Opt. Radial Seal I. Air (5010317187)..... RS5351	Steering (Iveco 1902137)..... P106-HD	Some Air (Mann C331605)..... PA2398
Air Dryer (Wabco, Right-Hand Thd.) (5001865037)..... BA5379 +	Gearbox Hyd. (5000791145)..... B307	Magnum AE390 w/MIDR 06.24.65 Eng. (02/00-05/05)
Air Dryer (Knorr, Left-Hand Thd.) (5001865404)..... BA5566	Kerax 385 w/MIDR 06.23.56 Eng. (09/98-on)	F-F Lube..... B76 +
Trans. (Automatic Gearbox) (7485105048)..... PT9417	F-F Lube (5000670700)..... B76 +	B-P Lube Spinner..... BC7173
Steering..... P106-HD	Opt. Fuel/Water Separator (Racor Hsg.) (Racor 2010PM)..... PF598-30	Fuel..... BF7886
Urea (7421333098)..... PE5271	Fuel (5000790570)..... BF988 +	Single Radial Seal Air..... RS3727
	Opt. Fuel/Water Separator (R.V.I. Hsg.) (5000790559)..... CLN&R	Radial Seal O. Air (w/FRM) (5001865723)..... RS5390
	Radial Seal O. Air (5010230916)..... RS3728	Radial Seal I. Air..... RS5351
	Radial Seal I. Air (5010269584)..... RS3729	Air Dryer (Mann TB1374X)..... BA5374 +
	Air Dryer (Mann TB1374X)..... BA5374 +	
	Trans. (ZF 7633141101)..... PT691	
	Steering (Iveco 1902137)..... P106-HD	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)
Magnum AE390 w/MIDR 06.24.65 Eng. (02/00-05/05) (Cont'd) Trans. (w/ZF Ecosplit Gearbox) (ZF 750131003)..... <b>PT8385</b> Steering..... <b>P106-HD</b> Hyd..... <b>B307</b>	Premium HR400 w/MIDR 06.20.45 Eng. (04/96-on) F-F Lube (5000670700)..... <b>B76 +</b> B-P Lube Spinner (5000670737). <b>BC110</b> Opt. Fuel/Water Separator (Racor Hsg.) (Racor 2010PM)..... <b>PF598-30</b> Fuel (22852800)..... <b>BF988 +</b> Fuel/Water Separator..... <b>BF1221 +</b> Opt. Fuel/Water Separator (R.V.I. Hsg.) (5000790559)..... <b>CLN&amp;R</b> Radial Seal O. Air (5010230841). <b>RS3727</b> Radial Seal O. Air (w/FRM) (5001865723)..... <b>RS5390</b> Opt. Radial Seal I. Air (5010317187)..... <b>RS5351</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Trans. (w/ZF Ecosplit Gearbox) (ZF 750131003)..... <b>PT8385</b> Steering (Iveco 1902137)..... <b>P106-HD</b> Hyd. (5000791145)..... <b>B307</b>	Premium HL410 w/Volvo DXi 11 Euro 4/5 Eng. (05/06-on) F-F Lube..... <b>B76-SS +</b> B-P Lube (B7685)..... <b>B7685</b> P. Fuel..... <b>BF7814</b> Fuel/Water Separator (7420541383)..... <b>BF1366-O</b> Radial Seal O. Air (5001865723). <b>RS5390</b> 444.5 mm Radial Seal I. Air..... <b>RS5351</b> Radial Seal O. Air (w/FRM) (5001865725)..... <b>RS30116</b> 536.6 mm Radial Seal I. Air..... <b>RS3729</b> Air Dryer (Wabco, Right-Hand Thd.) (5001865037)..... <b>BA5379 +</b> Air Dryer (Knorr, Left-Hand Thd.) (5001865404)..... <b>BA5566</b> Trans. (7485105048)..... <b>PT9417</b> Steering..... <b>P106-HD</b> Urea (7421333098)..... <b>PE5271</b>
R390 w/MIVR 08.35.30, MIVS 08.35.40 Engs. Lube Spin-on (5000670670)..... <b>B403</b> Fuel Spin-on (5000814227)..... <b>BF988 +</b> 533.4 mm O. Air (5000819342).... <b>PA2398</b> 579.4 mm Some Air (3564110).... <b>PA2312</b> Coolant (5000663625)..... <b>BW5139</b>	Kerax 410 DXi w/Volvo DXi 11 Euro 4/5 Eng. (05/06-on) F-F Lube..... <b>B76-SS +</b> B-P Lube..... <b>B7685</b> Fuel/Water Separator (7420514654)..... <b>BF1366-O</b> P. Fuel..... <b>BF7814</b> Fuel/Water Separator (7420754418)..... <b>BF9867-O</b> Single Radial Seal Air (5001865723)..... <b>RS5390</b> Radial Seal O. Air (5001865725). <b>RS30116</b> Radial Seal I. Air..... <b>RS3729</b> Air Dryer (Wabco, Right-hand Thd.) (5001865037)..... <b>BA5379 +</b> Air Dryer (Knorr, Left-Hand Thd.) (5001865404)..... <b>BA5566</b> Trans. (7401521527)..... <b>PT9417</b> Steering..... <b>P106-HD</b> Urea (7421333098)..... <b>PE5271</b>	Premium HR410 w/Volvo DXi Euro 4/5 Eng. (05/06-on) F-F Lube..... <b>B76-SS +</b> B-P Lube..... <b>B7685</b> Fuel/Water Separator (7420514654)..... <b>BF1366-O</b> P. Fuel..... <b>BF7814</b> Radial Seal Air (5001865723)..... <b>RS5390</b> Air Dryer (Wabco, Right-Hand Thd.) (5001865037)..... <b>BA5379 +</b> Air Dryer (Knorr, Left-Hand Thd.) (5001865404)..... <b>BA5566</b> Trans. (7485105048)..... <b>PT9417</b> Steering..... <b>P106-HD</b> Urea (7421333098)..... <b>PE5271</b>
Kerax 400 w/MIDR 06.23.56 Eng. (09/98-on) F-F Lube (5000670700)..... <b>B76 +</b> Severe Service F-F Lube (5000670700)..... <b>B76-SS +</b> Opt. Fuel/Water Separator (Racor Hsg.) (Racor 2010PM)..... <b>PF598-30</b> Fuel (5000790570)..... <b>BF988 +</b> Opt. Fuel/Water Separator (R.V.I. Hsg.) (5000790559)..... <b>CLN&amp;R</b> Radial Seal O. Air (5010230916). <b>RS3728</b> Radial Seal I. Air (5010269584)... <b>RS3729</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Trans. (ZF 7633141101)..... <b>PT691</b> Steering (Iveco 1902137)..... <b>P106-HD</b> Hyd. (5000791145)..... <b>B307</b>	Magnum AE400 E-Tech w/MIDR 06.24.65 Eng. (02/00-05/05) F-F Lube..... <b>B76 +</b> B-P Lube Spinner..... <b>BC7173</b> Fuel..... <b>BF7886</b> Radial Seal Air..... <b>RS3727</b> Radial Seal O. Air (w/FRM) (5001865723)..... <b>RS5390</b> Radial Seal I. Air..... <b>RS5351</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Trans. (w/ZF Ecosplit Gearbox) (5000807213)..... <b>PT8385</b> Steering..... <b>P106-HD</b> Hyd..... <b>B307</b>	Kerax 420 w/DCi11D Eng. (11/01-on) F-F Lube (Mann W11102/11)..... <b>B76 +</b> B-P Lube Spinner..... <b>BC7173</b> Opt. Fuel/Water Separator (Racor Hsg.) (Racor 2010PM)..... <b>PF598-30</b> Fuel (Mann WK940/20)..... <b>BF7886</b> Opt. Fuel/Water Separator (R.V.I. Hsg.) (5000790559)..... <b>CLN&amp;R</b> Radial Seal O. Air..... <b>RS3728</b> Radial Seal I. Air..... <b>RS3729</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Trans. (ZF 7633141101)..... <b>PT691</b> Steering..... <b>P106-HD</b> Hyd..... <b>B307</b>
Magnum AE400 E-Tech w/MIDR 06.24.65 Eng. (02/00-05/05) F-F Lube..... <b>B76 +</b> B-P Lube Spinner..... <b>BC7173</b> Fuel..... <b>BF7886</b> Radial Seal Air..... <b>RS3727</b> Radial Seal O. Air (w/FRM) (5001865723)..... <b>RS5390</b> Radial Seal I. Air..... <b>RS5351</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Trans. (w/ZF Ecosplit Gearbox) (5000807213)..... <b>PT8385</b> Steering..... <b>P106-HD</b> Hyd..... <b>B307</b>	Premium HD410 w/Volvo DXi 11 Euro 4/5 Eng. (05/06-on) F-F Lube..... <b>B76-SS +</b> B-P Lube..... <b>B7685</b> Fuel/Water Separator (7420514654)..... <b>BF1366-O</b> P. Fuel..... <b>BF7814</b> Radial Seal O. Air (5001865723). <b>RS5390</b> Opt. Radial Seal I. Air..... <b>RS5351</b> Air Dryer (Wabco, Right-Hand Thd.) (5001865037)..... <b>BA5379 +</b> Air Dryer (Knorr, Left-Hand Thd.) (5001865404)..... <b>BA5566</b> Trans. (Automatic Gearbox) (7401521527)..... <b>PT9417</b> Steering..... <b>P106-HD</b> Urea Service Kit (7421333098)... <b>PE5271</b>	Magnum AE420, AE420.19TI w/MIDR 06.35.40H Eng. (09/90-02/00) F-F Lube (5000670700)..... <b>B76 +</b> B-P Lube Spinner (5000670737). <b>BC110</b> Fuel (5000814227)..... <b>BF988 +</b> Radial Seal O. Air (5001865723). <b>RS5390</b> Radial Seal I. Air..... <b>RS5351</b> O. Air..... <b>PA3688</b> I. Air..... <b>PA3566</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b>
Premium HR400 w/MIDR 06.23.56 Eng. (01/99-on) F-F Lube (5000670700)..... <b>B76 +</b> B-P Lube Spinner (5000670737). <b>BC110</b> Fuel/Water Separator (Racor Hsg.)..... <b>PF598-30</b> Fuel (22852800)..... <b>BF988 +</b> Fuel/Water Separator (R.V.I. Hsg.) (5000822272)..... <b>CLN&amp;R</b> Radial Seal O. Air (5010230841). <b>RS3727</b> Opt. Radial Seal I. Air (5010317187)..... <b>RS5351</b> Air Dryer (Mann TB1374X)..... <b>BA5374 +</b> Trans. (w/ZF Ecosplit Gearbox).... <b>PT8385</b> Steering (Iveco 1902137)..... <b>P106-HD</b> Hyd. (5000791145)..... <b>B307</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)
Magnum AE420, AE420.19T1 w/MIDR 06.35.40H Eng. (09/90-02/00) (Cont'd) Trans. (w/ZF Ecosplit Gearbox) (ZF 750131003)..... <b>PT8385</b> Steering..... <b>P106-HD</b> Hyd..... <b>B307</b>	R420 w/MIVR 08.35.30, MIVS 08.35.40 Engs. <b>Lube Spin-on</b> (5000670670)..... <b>B403</b> <b>Fuel Spin-on</b> (5000814227)..... <b>BF988 +</b> <b>O. Air</b> (5000819342)..... <b>PA2398</b> <b>Some Air</b> (3564110)..... <b>PA2312</b> <b>Coolant</b> (5000663625)..... <b>BW5139</b>	Premium HL 430 Dxi w/Dxi 11 Euro 4/5 Eng. (06/09-on) (Cont'd) <b>Air Dryer</b> (Knorr, Left-hand Thd.) (5001865404)..... <b>BA5566</b> <b>Trans.</b> (7422051238)..... <b>PT9417</b> <b>Steering</b> (5000820895)..... <b>P106-HD</b> <b>Urea</b> (7420877953)..... <b>PE5271</b>
Premium HD420 w/dCi 11 Eng. (05/00-on) <b>F-F Lube</b> ..... <b>B76 +</b> <b>B-P Lube Spinner</b> ..... <b>BC7173</b> <b>Opt. Fuel/Water Separator</b> (Racor Hsg.) (Racor 2010PM)..... <b>PF598-30</b> <b>Fuel</b> ..... <b>BF7886</b> <b>Opt. Fuel/Water Separator</b> (R.V.I. Hsg.) (5000790559)..... <b>CLN&amp;R</b> <b>Radial Seal O. Air</b> ..... <b>RS3727</b> <b>Radial Seal O. Air</b> (w/FRM) (5001865723)..... <b>RS5390</b> <b>Opt. Radial Seal I. Air</b> (5010317187)..... <b>RS5351</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Trans.</b> (w/ZF Ecosplit Gearbox) (ZF 750131003)..... <b>PT8385</b> <b>Steering</b> ..... <b>P106-HD</b>	Kerax 430 Dxi w/Dxi 11 Euro 5 Eng. (06/09-on) <b>F-F Lube</b> (7420709459)..... <b>B76-SS +</b> <b>B-P Lube</b> (5001846647)..... <b>B7685</b> <b>B-P Lube</b> (Upgrade) (7421561284)..... <b>B7409</b> <b>Fuel/Water Separator</b> (7420998346)..... <b>BF1386-O</b> <b>Fuel/Water Separator</b> (7420998349)..... <b>BF1387-O</b> <b>Fuel</b> (7420541381)..... <b>BF7814</b> <b>Radial Seal O. Air</b> (5001865725)..... <b>RS30116</b> <b>Radial Seal I. Air</b> (5010269584)..... <b>RS3729</b> <b>Cab Air</b> (5001867491)..... <b>PA30188</b> <b>Air Dryer</b> (Knorr, Left-hand Thd.) (5001865404)..... <b>BA5566</b> <b>Air Dryer</b> (Wabco, Right-hand Thd.) (5001865037)..... <b>BA5379 +</b> <b>Trans.</b> (7422051238)..... <b>PT9417</b> <b>Steering</b> (5000820895)..... <b>P106-HD</b> <b>Urea</b> (7420877953)..... <b>PE5271</b>	Premium HR 430 Dxi w/Dxi 11 Euro 4/5 Eng. (06/09-on) <b>F-F Lube</b> (7420709459)..... <b>B76-SS +</b> <b>B-P Lube</b> (5001846647)..... <b>B7685</b> <b>Fuel/Water Separator</b> (7420998346)..... <b>BF1386-O</b> <b>Fuel/Water Separator</b> (7420998349)..... <b>BF1387-O</b> <b>Fuel</b> (7420541381)..... <b>BF7814</b> <b>Radial Seal O. Air</b> (5001865723)..... <b>RS5390</b> <b>Radial Seal I. Air</b> (5010317187)..... <b>RS5351</b> <b>Cab Air</b> (5001867491)..... <b>PA30188</b> <b>Air Dryer</b> (Wabco, Right-hand Thd.) (5001865037)..... <b>BA5379 +</b> <b>Air Dryer</b> (Knorr, Left-hand Thd.) (5001865404)..... <b>BA5566</b> <b>Trans.</b> (7422051238)..... <b>PT9417</b> <b>Steering</b> (5000820895)..... <b>P106-HD</b> <b>Urea</b> (7420877953)..... <b>PE5271</b>
Premium HL420 w/dCi 11 Eng. (05/00-on) <b>F-F Lube</b> ..... <b>B76 +</b> <b>B-P Lube Spinner</b> ..... <b>BC7173</b> <b>Opt. Fuel/Water Separator</b> (Racor Hsg.) (Racor 2010PM)..... <b>PF598-30</b> <b>P. Fuel</b> ..... <b>BF7886</b> <b>Opt. Fuel/Water Separator</b> (R.V.I. Hsg.) (5000790559)..... <b>CLN&amp;R</b> <b>Radial Seal O. Air</b> ..... <b>RS3727</b> <b>Radial Seal O. Air</b> (w/FRM) (5001865723)..... <b>RS5390</b> <b>Opt. Radial Seal I. Air</b> (5010317187)..... <b>RS5351</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Trans.</b> (w/ZF Ecosplit Gearbox) (ZF 750131003)..... <b>PT8385</b> <b>Steering</b> ..... <b>P106-HD</b>	Premium HD 430 Dxi w/Dxi 11 Euro 4/5 Eng. (06/09-on) <b>F-F Lube</b> (7420709459)..... <b>B76-SS +</b> <b>B-P Lube</b> (5001846647)..... <b>B7685</b> <b>Fuel/Water Separator</b> (7420998346)..... <b>BF1386-O</b> <b>Fuel/Water Separator</b> (7420998349)..... <b>BF1387-O</b> <b>Fuel</b> (7420541381)..... <b>BF7814</b> <b>Radial Seal O. Air</b> (5001865723)..... <b>RS5390</b> <b>Radial Seal I. Air</b> (5010317187)..... <b>RS5351</b> <b>Cab Air</b> (5001867491)..... <b>PA30188</b> <b>Air Dryer</b> (Wabco, Right-hand Thd.) (5001865037)..... <b>BA5379 +</b> <b>Air Dryer</b> (Knorr, Left-hand Thd.) (5001865404)..... <b>BA5566</b> <b>Trans.</b> (7422051238)..... <b>PT9417</b> <b>Steering</b> (5000820895)..... <b>P106-HD</b> <b>Urea</b> (7420877953)..... <b>PE5271</b>	Magnum AE430 w/MIDR 06.24.65 Eng. (02/00-05/05) <b>F-F Lube</b> ..... <b>B76 +</b> <b>B-P Lube Spinner</b> ..... <b>BC7173</b> <b>Fuel</b> ..... <b>BF7886</b> <b>Radial Seal O. Air</b> ..... <b>RS3727</b> <b>Radial Seal O. Air</b> (w/FRM) (5001865723)..... <b>RS5390</b> <b>Radial Seal I. Air</b> ..... <b>RS5351</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Trans.</b> (w/ZF Ecosplit Gearbox) (5000807213)..... <b>PT8385</b> <b>Steering</b> ..... <b>P106-HD</b> <b>Hyd</b> ..... <b>B307</b>
Premium HR420 w/dCi 11 Eng. (05/00-on) <b>F-F Lube</b> ..... <b>B76 +</b> <b>B-P Lube Spinner</b> ..... <b>BC7173</b> <b>Opt. Fuel/Water Separator</b> (Racor Hsg.) (Racor 2010PM)..... <b>PF598-30</b> <b>Fuel</b> ..... <b>BF7886</b> <b>Opt. Fuel/Water Separator</b> (R.V.I. Hsg.) (5000790559)..... <b>CLN&amp;R</b> <b>Radial Seal O. Air</b> ..... <b>RS3727</b> <b>Radial Seal O. Air</b> (w/FRM) (5001865723)..... <b>RS5390</b> <b>Opt. Radial Seal I. Air</b> (5010317187)..... <b>RS5351</b> <b>Air Dryer</b> (Mann TB1374X)..... <b>BA5374 +</b> <b>Trans.</b> (w/ZF Ecosplit Gearbox) (ZF 750131003)..... <b>PT8385</b> <b>Steering</b> ..... <b>P106-HD</b>	Premium HL 430 Dxi w/Dxi 11 Euro 4/5 Eng. (06/09-on) <b>F-F Lube</b> (7420709459)..... <b>B76-SS +</b> <b>B-P Lube</b> (5001846647)..... <b>B7685</b> <b>Fuel/Water Separator</b> (7420998346)..... <b>BF1386-O</b> <b>Fuel/Water Separator</b> (7420998349)..... <b>BF1387-O</b> <b>Fuel</b> (7420541381)..... <b>BF7814</b> <b>Radial Seal O. Air</b> (5001865723)..... <b>RS5390</b> <b>Radial Seal I. Air</b> (5010317187)..... <b>RS5351</b> <b>Cab Air</b> (5001867491)..... <b>PA30188</b> <b>Air Dryer</b> (Wabco, Right-hand Thd.) (5001865037)..... <b>BA5379 +</b>	C Serie C 430 w/Volvo DTI 11 Eng. (08/13-on) <b>F-F Lube</b> (5001846641)..... <b>B76 +</b> <b>B-P Lube</b> (7421561284)..... <b>B7409</b> <b>Severe Service F-F Lube</b> (5001846641)..... <b>B76-SS +</b> <b>Fuel/Water Separator</b> (7424993622)..... <b>BF1292-O</b> <b>Fuel/Water Separator</b> (Fleetguard FS20132)..... <b>BF46182-O</b> <b>Fuel</b> (Short) (7421764961)..... <b>BF46131</b> <b>Fuel</b> (Long) (7421764958)..... <b>BF46117</b> <b>Cab Air</b> (7482348995)..... <b>PA30114</b> <b>Cab Air Pre-Filter</b> (7482379897)..... <b>PA30113</b> <b>Air Dryer</b> (5001865404)..... <b>BA5566</b> <b>Coolant</b> (Volvo 1699830)..... <b>BW5141</b> <b>Steering</b> (5000820895)..... <b>P106-HD</b> <b>Urea</b> (7421574991)..... <b>PE17000</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)
D Serie D 430 (D wide) w/Volvo DTI 11 Eng. (01/16-on)	Kerax 440 Dxi w/Volvo DXi11 Euro 4/5 Eng. (05/06-on) (Cont'd)	Magnum AE 440 Dxi13 w/Dxi 13 Euro 4/5 Eng. (03/09-on)
F-F Lube (5001846641)..... B76 +	Cab Air (5001867491)..... PA30188	F-F Lube (7420709459)..... B76-SS +
B-P Lube (7421561284)..... B7409	Air Dryer (Wabco, Right-Hand Thd.) (5001865037)..... BA5379 +	B-P Lube (5001846647)..... B7685
Severe Service F-F Lube (5001846641)..... B76-SS +	Air Dryer (Knorr, Left-Hand Thd.) (5001865404)..... BA5566	B-P Lube (Upgrade) (7421561284)..... B7409
Fuel/Water Separator (7421764968)..... BF1386-O	Trans. (7401521527)..... PT9417	Fuel/Water Separator (7420998346)..... BF1386-O
Fuel (Short) (7421764961)..... BF46131	Steering (5000820895)..... P106-HD	Fuel/Water Separator (7420998349)..... BF1387-O
Fuel (long) (7421764958)..... BF46117	Urea (7421333098)..... PE5271	Fuel (7420541381)..... BF7814
Radial Seal O. Air (5001865723)..... RS5390	Premium HL 440 Dxi w/Dxi 11 Eng. (10/05-on)	Radial Seal O. Air (5001865723)..... RS5390
Cab Air (5001867491)..... PA30188	F-F Lube (7420709459)..... B76-SS +	Radial Seal I. Air (5010317187)..... RS5351
Air Dryer (5001865404)..... BA5566	B-P Lube (5001846647)..... B7685	Air Dryer (Knorr, Left-hand Thd.) (5001865404)..... BA5566
Steering (5000820895)..... P106-HD	Fuel/Water Separator (7420998346)..... BF1386-O	Air Dryer (Wabco, Right-hand Thd.) (5001865037)..... BA5379 +
Urea (7421574991)..... PE17000	Fuel/Water Separator (7420998349)..... BF1387-O	Trans. (7422051238)..... PT9417
K Serie K 430 w/Volvo DTI 11 Eng. (08/13-on)	Fuel (7420541381)..... BF7814	Steering (5000820895)..... P106-HD
F-F Lube (5001846641)..... B76 +	Radial Seal O. Air (5001865723)..... RS5390	Urea (7420877953)..... PE5271
B-P Lube (7421561284)..... B7409	Radial Seal I. Air (5010317187)..... RS5351	C Serie C 440 w/Volvo DTI 13 Eng. (08/13-on)
Severe Service F-F Lube (5001846641)..... B76-SS +	Cab Air (05/06-on) (5001867491)..... PA30188	F-F Lube (5001846641)..... B76 +
Fuel/Water Separator (7421764968)..... BF1386-O	Air Dryer (Wabco, Right-hand Thd.) (5001865037)..... BA5379 +	B-P Lube (7421561284)..... B7409
Fuel (Short) (7421764961)..... BF46131	Air Dryer (Knorr, Left-hand Thd.) (5001865404)..... BA5566	Severe Service F-F Lube (5001846641)..... B76-SS +
Fuel (Long) (7421764958)..... BF46117	Trans. (7422051238)..... PT9417	Fuel/Water Separator (Fleetguard FS20132)..... BF46182-O
Cab Air (7482348995)..... PA30114	Steering (5000820895)..... P106-HD	Cab Air (7482348995)..... PA30114
Cab Air Pre-Filter (7482379897)..... PA30113	Magnum AE440 DXi w/Volvo DXi 12 Eng. (03/05-on)	Cab Air Pre-Filter (7482379897)..... PA30113
Air Dryer (5001865404)..... BA5566	F-F Lube..... B76-SS +	Air Dryer (5001865404)..... BA5566
Coolant (Volvo 1699830)..... BW5141	B-P Lube..... B7685	Coolant (Volvo 1699830)..... BW5141
Steering (5000820895)..... P106-HD	Fuel..... BF7814	Steering (5000820895)..... P106-HD
Urea (7421574991)..... PE17000	Fuel/Water Separator (7420541383)..... BF1366-O	Urea (7421574991)..... PE17000
T Serie T 430 w/Volvo DTI 11 Eng.	Radial Seal O. Air..... RS3727	Premium HR440 w/Volvo DXi 11 Eng. (10/05-on)
F-F Lube (5001846641)..... B76 +	Radial Seal O. Air (w/FRM) (5001865723)..... RS5390	F-F Lube..... B76-SS +
B-P Lube (7421561284)..... B7409	Radial Seal I. Air..... RS5351	B-P Lube..... B7685
Severe Service F-F Lube (5001846641)..... B76-SS +	Air Dryer (Wabco, Right-Hand Thd.) (5001865037)..... BA5379 +	Fuel/Water Separator (7420514654)..... BF1366-O
Fuel/Water Separator (7421764968)..... BF1386-O	Air Dryer (Knorr, Left-Hand Thd.) (5001865404)..... BA5566	P. Fuel..... BF7814
Fuel (Short) (7421764961)..... BF46131	Trans. (15215270)..... PT9417	Radial Seal O. Air..... RS3727
Fuel (Long) (7421764958)..... BF46117	Steering..... P106-HD	Opt. Radial Seal I. Air (5010317187)..... RS5351
Cab Air (7482348995)..... PA30114	Magnum AE440 E-Tech w/MIDR 06.24.65 Eng. (02/00-05/05)	Radial Seal O. Air (w/FRM) (5001865723)..... RS5390
Cab Air Pre-Filter (7482379897)..... PA30113	F-F Lube..... B76 +	Air Dryer (Wabco, Left-Hand Thd.) (5001865037)..... BA5379 +
Air Dryer (5001865404)..... BA5566	B-P Lube Spinner..... BC7173	Air Dryer (Knorr, Left-Hand Thd.) (5001865404)..... BA5566
Coolant (Volvo 1699830)..... BW5141	Fuel..... BF7886	Trans. (7485105048)..... PT9417
Steering (5000820895)..... P106-HD	Radial Seal O. Air..... RS3727	Steering..... P106-HD
Urea (7421574991)..... PE17000	Radial Seal O. Air (w/FRM) (5001865723)..... RS5390	Urea (7421333098)..... PE5271
Kerax 440 Dxi w/Volvo DXi11 Euro 4/5 Eng. (05/06-on)	Radial Seal I. Air..... RS5351	K Serie K 440 w/Volvo DTI 13 Eng. (08/13-on)
F-F Lube (7420709459)..... B76-SS +	Trans. (w/ZF Ecosplit Gearbox) (750131003)..... PT8385	F-F Lube (5001846641)..... B76 +
B-P Lube (5001846647)..... B7685	Steering..... P106-HD	B-P Lube (7421561284)..... B7409
Fuel/Water Separator (7420514654)..... BF1366-O	Hyd..... B307	Severe Service F-F Lube (5001846641)..... B76-SS +
Fuel/Water Separator (7420754418)..... BF9867-O		Fuel/Water Separator (7421764968)..... BF1386-O
Fuel (7420541381)..... BF7814		
Radial Seal Air (5001865723)..... RS5390		
Radial Seal I. Air (5010269584)..... RS3729		
Radial Seal O. Air (FRM) (5001865725)..... RS30116		

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)
K Serie K 440 w/Volvo DTI 13 Eng. (08/13-on) (Cont'd)	Premium HD450 w/Volvo DXi 11 Euro 4/5 Eng. (05/06-on) (Cont'd)	Kerax 460 Dxi w/Dxi 11 Euro 5 Eng. (06/09-on) (Cont'd)
<b>Cab Air</b> (7482348995)..... <b>PA30114</b>	<b>Trans.</b> (Automatic Gearbox) (7485105048)..... <b>PT9417</b>	<b>Air Dryer</b> (Wabco, Right-hand Thd.) (5001865037)..... <b>BA5379 +</b>
<b>Cab Air Pre-Filter</b> (7482379897). <b>PA30113</b>	<b>Steering</b> ..... <b>P106-HD</b>	<b>Trans.</b> (7422051238)..... <b>PT9417</b>
<b>Air Dryer</b> (5001865404)..... <b>BA5566</b>	<b>Urea</b> (7421333098)..... <b>PE5271</b>	<b>Steering</b> (5000820895)..... <b>P106-HD</b>
<b>Coolant</b> (Volvo 1699830)..... <b>BW5141</b>	Premium HL450 w/Volvo DXi 11 Euro 4/5 Eng. (05/06-on)	<b>Urea</b> (7420877953)..... <b>PE5271</b>
<b>Steering</b> (5000820895)..... <b>P106-HD</b>	<b>F-F Lube</b> ..... <b>B76-SS +</b>	Kerax 460 Dxi w/Volvo DXi11 Euro 4/5 Eng. (2008-on)
<b>Urea</b> (7421574991)..... <b>PE17000</b>	<b>B-P Lube</b> ..... <b>B7685</b>	<b>F-F Lube</b> (7420709459)..... <b>B76-SS +</b>
T Serie T 440 w/Volvo DTI 13 Eng.	<b>P. Fuel</b> ..... <b>BF7814</b>	<b>B-P Lube</b> (5001846647)..... <b>B7685</b>
<b>F-F Lube</b> (5001846641)..... <b>B76 +</b>	<b>Fuel/Water Separator</b> (7420541383)..... <b>BF1366-O</b>	<b>Fuel/Water Separator</b> (7420754418)..... <b>BF9867-O</b>
<b>B-P Lube</b> (7421561284)..... <b>B7409</b>	<b>Radial Seal O. Air</b> (5001865723). <b>RS5390</b>	<b>Fuel</b> (7420541381)..... <b>BF7814</b>
<b>Severe Service F-F Lube</b> (5001846641)..... <b>B76-SS +</b>	<b>444.5 mm Radial Seal I. Air</b> ..... <b>RS5351</b>	<b>Radial Seal Air</b> (5001865723)..... <b>RS5390</b>
<b>Fuel/Water Separator</b> (7421764968)..... <b>BF1386-O</b>	<b>Radial Seal O. Air</b> (w/FRM) (5001865725)..... <b>RS30116</b>	<b>Radial Seal I. Air</b> (5010269584)... <b>RS3729</b>
<b>Radial Seal Air</b> (7421243188)..... <b>RS5730</b>	<b>536.6 mm Radial Seal I. Air</b> ..... <b>RS3729</b>	<b>Radial Seal O. Air</b> (FRM) (5001865725)..... <b>RS30116</b>
<b>Air</b> (Inner) (Volvo 21115501)..... <b>RS5731</b>	<b>Air Dryer</b> (Wabco, Right-Hand Thd.) (5001865037)..... <b>BA5379 +</b>	<b>Cab Air</b> (5001867491)..... <b>PA30188</b>
<b>Cab Air</b> (7482348995)..... <b>PA30114</b>	<b>Air Dryer</b> (Knorr, Left-Hand Thd.) (5001865404)..... <b>BA5566</b>	<b>Air Dryer</b> (Wabco, Right-Hand Thd.) (5001865037)..... <b>BA5379 +</b>
<b>Cab Air Pre-Filter</b> (7482379897). <b>PA30113</b>	<b>Trans.</b> (Automatic Gearbox) (7485105048)..... <b>PT9417</b>	<b>Air Dryer</b> (Knorr, Left-Hand Thd.) (5001865404)..... <b>BA5566</b>
<b>Air Dryer</b> (5001865404)..... <b>BA5566</b>	<b>Steering</b> ..... <b>P106-HD</b>	<b>Trans.</b> (7401521527)..... <b>PT9417</b>
<b>Coolant</b> (Volvo 1699830)..... <b>BW5141</b>	<b>Urea</b> (7421333098)..... <b>PE5271</b>	<b>Steering</b> (5000820895)..... <b>P106-HD</b>
<b>Steering</b> (5000820895)..... <b>P106-HD</b>	Premium HR450 w/Volvo DXi 11 Euro 4/5 Eng. (05/06-on)	<b>Urea</b> (7421333098)..... <b>PE5271</b>
<b>Urea</b> (7421574991)..... <b>PE17000</b>	<b>F-F Lube</b> ..... <b>B76-SS +</b>	Premium HD 460 Dxi w/Dxi 11 Euro 4/5 Eng. (06/09-on)
Kerax 450 DXi w/Volvo DXi Euro 4/5 Eng. (05/06-on)	<b>B-P Lube</b> ..... <b>B7685</b>	<b>F-F Lube</b> (7420709459)..... <b>B76-SS +</b>
<b>F-F Lube</b> ..... <b>B76-SS +</b>	<b>P. Fuel</b> ..... <b>BF7814</b>	<b>B-P Lube</b> (5001846647)..... <b>B7685</b>
<b>B-P Lube</b> ..... <b>B7685</b>	<b>Fuel/Water Separator</b> (7420541383)..... <b>BF1366-O</b>	<b>Fuel/Water Separator</b> (7420998346)..... <b>BF1386-O</b>
<b>P. Fuel</b> ..... <b>BF7814</b>	<b>Radial Seal Air</b> (5001865723)..... <b>RS5390</b>	<b>Fuel/Water Separator</b> (7420998349)..... <b>BF1387-O</b>
<b>Fuel/Water Separator</b> (7420541383)..... <b>BF1366-O</b>	<b>Air Dryer</b> (Wabco, Right-Hand Thd.) (5001865037)..... <b>BA5379 +</b>	<b>Fuel</b> (7420541381)..... <b>BF7814</b>
<b>Fuel/Water Separator</b> (7420754418)..... <b>BF9867-O</b>	<b>Air Dryer</b> (Knorr, Left-Hand Thd.) (5001865404)..... <b>BA5566</b>	<b>Radial Seal O. Air</b> (5001865723). <b>RS5390</b>
<b>Single Radial Seal Air</b> (5001865723)..... <b>RS5390</b>	<b>Trans.</b> (Automatic Gearbox) (7485105048)..... <b>PT9417</b>	<b>Radial Seal I. Air</b> (5010317187)... <b>RS5351</b>
<b>Radial Seal O. Air</b> (5001865725). <b>RS30116</b>	<b>Steering</b> ..... <b>P106-HD</b>	<b>Cab Air</b> (5001867491)..... <b>PA30188</b>
<b>Radial Seal I. Air</b> ..... <b>RS3729</b>	<b>Urea</b> (7421333098)..... <b>PE5271</b>	<b>Air Dryer</b> (Wabco, Right-hand Thd.) (5001865037)..... <b>BA5379 +</b>
<b>Air Dryer</b> (Wabco, Right-hand Thd.) (5001865037)..... <b>BA5379 +</b>	Kerax 460 Dxi w/Dxi 11 Euro 5 Eng. (06/09-on)	<b>Air Dryer</b> (Knorr, Left-hand Thd.) (5001865404)..... <b>BA5566</b>
<b>Air Dryer</b> (Knorr, Left-Hand Thd.) (5001865404)..... <b>BA5566</b>	<b>F-F Lube</b> (7420709459)..... <b>B76-SS +</b>	<b>Trans.</b> (7422051238)..... <b>PT9417</b>
<b>Trans.</b> (Automatic Gearbox) (7485105048)..... <b>PT9417</b>	<b>B-P Lube</b> (5001846647)..... <b>B7685</b>	<b>Steering</b> (5000820895)..... <b>P106-HD</b>
<b>Steering</b> ..... <b>P106-HD</b>	<b>B-P Lube</b> (Upgrade) (7421561284)..... <b>B7409</b>	<b>Urea</b> (7420877953)..... <b>PE5271</b>
<b>Urea</b> (7420877953)..... <b>PE5271</b>	<b>Fuel/Water Separator</b> (7420998346)..... <b>BF1386-O</b>	Premium HL 460 Dxi w/Dxi 11 Euro 4/5 Eng. (06/09-on)
Premium HD450 w/Volvo DXi 11 Euro 4/5 Eng. (05/06-on)	<b>Fuel/Water Separator</b> (7420998349)..... <b>BF1387-O</b>	<b>F-F Lube</b> (7420709459)..... <b>B76-SS +</b>
<b>F-F Lube</b> ..... <b>B76-SS +</b>	<b>Fuel</b> (7420541381)..... <b>BF7814</b>	<b>B-P Lube</b> (5001846647)..... <b>B7685</b>
<b>B-P Lube</b> ..... <b>B7685</b>	<b>Radial Seal O. Air</b> (5001865725). <b>RS30116</b>	<b>Fuel/Water Separator</b> (7420998346)..... <b>BF1386-O</b>
<b>Fuel/Water Separator</b> (7420514654)..... <b>BF1366-O</b>	<b>Radial Seal I. Air</b> (5010269584)... <b>RS3729</b>	<b>Fuel/Water Separator</b> (7420998349)..... <b>BF1387-O</b>
<b>P. Fuel</b> ..... <b>BF7814</b>	<b>Cab Air</b> (5001867491)..... <b>PA30188</b>	<b>Fuel</b> (7420541381)..... <b>BF7814</b>
<b>Radial Seal O. Air</b> (5001865723). <b>RS5390</b>	<b>Air Dryer</b> (Knorr, Left-hand Thd.) (5001865404)..... <b>BA5566</b>	<b>Radial Seal O. Air</b> (5001865723). <b>RS5390</b>
<b>Opt. Radial Seal I. Air</b> ..... <b>RS5351</b>		<b>Radial Seal I. Air</b> (5010317187)... <b>RS5351</b>
<b>Air Dryer</b> (Wabco, Right-Hand Thd.) (5001865037)..... <b>BA5379 +</b>		<b>Cab Air</b> (5001867491)..... <b>PA30188</b>
<b>Air Dryer</b> (Knorr, Left-Hand Thd.) (5001865404)..... <b>BA5566</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)
Premium HL 460 Dxi w/Dxi 11 Euro 4/5 Eng. (06/09-on) (Cont'd)	C Serie C 460 w/Volvo DTI 11 Eng. (08/13-on) (Cont'd)	Kerax 480 Dxi w/Dxi 13 Euro 4/5 Eng. (02/08-on) (Cont'd)
Air Dryer (Wabco, Right-hand Thd.) (5001865037)..... <b>BA5379 +</b>	Urea (7421574991)..... <b>PE17000</b>	Radial Seal O. Air (5001865725)..... <b>RS30116</b>
Air Dryer (Knorr, Left-hand Thd.) (5001865404)..... <b>BA5566</b>	K Serie K 460 w/Volvo DTI 11 Eng. (08/13-on)	Radial Seal I. Air (5010269584).... <b>RS3729</b>
Trans. (7422051238)..... <b>PT9417</b>	F-F Lube (5001846641)..... <b>B76 +</b>	Cab Air (5001867491)..... <b>PA30188</b>
Steering (5000820895)..... <b>P106-HD</b>	B-P Lube (7421561284)..... <b>B7409</b>	Air Dryer (Knorr, Left-hand Thd.) (5001865404)..... <b>BA5566</b>
Urea (7420877953)..... <b>PE5271</b>	Severe Service F-F Lube (5001846641)..... <b>B76-SS +</b>	Air Dryer (Wabco, Right-hand Thd.) (5001865037)..... <b>BA5379 +</b>
Premium HR 460 Dxi w/Dxi 11 Euro 4/5 Eng. (06/09-on)	Fuel/Water Separator (7421764968)..... <b>BF1386-O</b>	Trans. (7422051238)..... <b>PT9417</b>
F-F Lube (7420709459)..... <b>B76-SS +</b>	Fuel (Short) (7421764961)..... <b>BF46131</b>	Steering (5000820895)..... <b>P106-HD</b>
B-P Lube (5001846647)..... <b>B7685</b>	Fuel (Long) (7421764958)..... <b>BF46117</b>	Urea (7420877953)..... <b>PE5271</b>
Fuel/Water Separator (7420998346)..... <b>BF1386-O</b>	Cab Air (7482348995)..... <b>PA30114</b>	Magnum AE480 DXi w/Volvo DXi 12 Eng. (03/05-on)
Fuel/Water Separator (7420998349)..... <b>BF1387-O</b>	Cab Air Pre-Filter (7482379897)..... <b>PA30113</b>	F-F Lube..... <b>B76-SS +</b>
Fuel (7420541381)..... <b>BF7814</b>	Air Dryer (5001865404)..... <b>BA5566</b>	B-P Lube..... <b>B7685</b>
Radial Seal O. Air (5001865723)..... <b>RS5390</b>	Coolant (Volvo 1699830)..... <b>BW5141</b>	Fuel..... <b>BF7814</b>
Radial Seal I. Air (5010317187).... <b>RS5351</b>	Steering (5000820895)..... <b>P106-HD</b>	Fuel/Water Separator (7420514654)..... <b>BF1366-O</b>
Cab Air (5001867491)..... <b>PA30188</b>	Urea (7421574991)..... <b>PE17000</b>	Radial Seal O. Air..... <b>RS3727</b>
Air Dryer (Wabco, Right-hand Thd.) (5001865037)..... <b>BA5379 +</b>	T Serie T 460 w/Volvo DTI 11 Eng.	Radial Seal O. Air (w/FRM) (5001865723)..... <b>RS5390</b>
Air Dryer (Knorr, Left-hand Thd.) (5001865404)..... <b>BA5566</b>	F-F Lube (5001846641)..... <b>B76 +</b>	Radial Seal I. Air..... <b>RS5351</b>
Trans. (7422051238)..... <b>PT9417</b>	B-P Lube (7421561284)..... <b>B7409</b>	Air Dryer (Wabco, Right-Hand Thd.) (5001865037)..... <b>BA5379 +</b>
Steering (5000820895)..... <b>P106-HD</b>	Severe Service F-F Lube (5001846641)..... <b>B76-SS +</b>	Air Dryer (Knorr, Left-Hand Thd.) (5001865404)..... <b>BA5566</b>
Urea (7420877953)..... <b>PE5271</b>	Fuel/Water Separator (7421764968)..... <b>BF1386-O</b>	Trans. (15215270)..... <b>PT9417</b>
Magnum AE460 DXi w/Volvo DXi 13 Euro 4/5 Eng. (03/)	Fuel (Short) (7421764961)..... <b>BF46131</b>	Steering..... <b>P106-HD</b>
F-F Lube..... <b>B76-SS +</b>	Fuel (Long) (7421764958)..... <b>BF46117</b>	Magnum AE480 E-Tech w/MIDR 06.24.65 Eng. (02/00-05/05)
B-P Lube..... <b>B7685</b>	Cab Air (7482348995)..... <b>PA30114</b>	F-F Lube..... <b>B76 +</b>
Fuel..... <b>BF7814</b>	Cab Air Pre-Filter (7482379897)..... <b>PA30113</b>	B-P Lube Spinner..... <b>BC7173</b>
Fuel/Water Separator (7420541383)..... <b>BF1366-O</b>	Air Dryer (5001865404)..... <b>BA5566</b>	Fuel..... <b>BF7886</b>
Radial Seal Air (5001865723)..... <b>RS5390</b>	Coolant (Volvo 1699830)..... <b>BW5141</b>	Radial Seal O. Air..... <b>RS3727</b>
Air Dryer (Wabco, Right-Hand Thd.) (5001865037)..... <b>BA5379 +</b>	Steering (5000820895)..... <b>P106-HD</b>	Radial Seal O. Air (w/FRM) (5001865723)..... <b>RS5390</b>
Air Dryer (Knorr, Left-Hand Thd.) (5001865404)..... <b>BA5566</b>	Urea (7421574991)..... <b>PE17000</b>	Radial Seal I. Air..... <b>RS5351</b>
Trans. (15215270)..... <b>PT9417</b>	Magnum AE470 w/MIDR 06.24.65 Eng. (02/00-05/05)	Air Dryer (Mann TB1374X)..... <b>BA5374 +</b>
Steering..... <b>P106-HD</b>	F-F Lube..... <b>B76 +</b>	Trans. (w/ZF Ecosplit Gearbox) (ZF 750131003)..... <b>PT8385</b>
C Serie C 460 w/Volvo DTI 11 Eng. (08/13-on)	B-P Lube Spinner..... <b>BC7173</b>	Steering..... <b>P106-HD</b>
F-F Lube (5001846641)..... <b>B76 +</b>	Severe Service F-F Lube..... <b>B76-SS +</b>	Hyd..... <b>B307</b>
B-P Lube (7421561284)..... <b>B7409</b>	Fuel..... <b>BF7886</b>	Magnum AE 480 Dxi13 w/Dxi 13 Euro 4/5 Eng. (03/09-on)
Severe Service F-F Lube (5001846641)..... <b>B76-SS +</b>	Radial Seal O. Air..... <b>RS3727</b>	F-F Lube (7420709459)..... <b>B76-SS +</b>
Fuel/Water Separator (7424993622)..... <b>BF1292-O</b>	Radial Seal O. Air (w/FRM)..... <b>RS5390</b>	B-P Lube (5001846647)..... <b>B7685</b>
Fuel/Water Separator (Fleetguard FS20132)..... <b>BF46182-O</b>	Radial Seal I. Air..... <b>RS5351</b>	B-P Lube (Upgrade) (7421561284)..... <b>B7409</b>
Fuel (Short) (7421764961)..... <b>BF46131</b>	Air Dryer (Mann TB1374X)..... <b>BA5374 +</b>	Fuel/Water Separator (7420998346)..... <b>BF1386-O</b>
Fuel (Long) (7421764958)..... <b>BF46117</b>	Trans. (w/ZF Ecosplit Gearbox) (ZF 750131003)..... <b>PT8385</b>	Fuel/Water Separator (7420998349)..... <b>BF1387-O</b>
Cab Air (7482348995)..... <b>PA30114</b>	Steering..... <b>P106-HD</b>	Fuel (7420541381)..... <b>BF7814</b>
Cab Air Pre-Filter (7482379897)..... <b>PA30113</b>	Hyd..... <b>B307</b>	Radial Seal O. Air (5001865723)..... <b>RS5390</b>
Air Dryer (5001865404)..... <b>BA5566</b>	Kerax 480 Dxi w/Dxi 13 Euro 4/5 Eng. (02/08-on)	Radial Seal I. Air (5010317187).... <b>RS5351</b>
Coolant (Volvo 1699830)..... <b>BW5141</b>	F-F Lube (7420709459)..... <b>B76-SS +</b>	Air Dryer (Knorr, Left-hand Thd.) (5001865404)..... <b>BA5566</b>
Steering (5000820895)..... <b>P106-HD</b>	B-P Lube (5001846647)..... <b>B7685</b>	
	B-P Lube (Upgrade) (7421561284)..... <b>B7409</b>	
	Fuel/Water Separator (7420998346)..... <b>BF1386-O</b>	
	Fuel/Water Separator (7420998349)..... <b>BF1387-O</b>	
	Fuel (7420541381)..... <b>BF7814</b>	
	Radial Seal O. Air (5001865723)..... <b>RS5390</b>	
	Radial Seal I. Air (5010317187).... <b>RS5351</b>	
	Air Dryer (Knorr, Left-hand Thd.) (5001865404)..... <b>BA5566</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)
Magnum AE 480 Dxi13 w/Dxi 13 Euro 4/5 Eng. (03/09-on) (Cont'd)	Kerax 500 Dxi w/Volvo DXi13 Euro 4/5 Eng. (2008-on) (Cont'd)	Magnum AE500.16 w/Mack EE9 Eng.
<b>Air Dryer</b> (Wabco, Right-hand Thd.) (5001865037)..... <b>BA5379 +</b>	<b>Radial Seal O. Air</b> (FRM) (5001865725)..... <b>RS30116</b>	<b>F-F Lube</b> (5000670700)..... <b>B76 +</b>
<b>Trans.</b> (7422051238)..... <b>PT9417</b>	<b>Cab Air</b> (5001867491)..... <b>PA30188</b>	<b>B-P Lube Spinner</b> (5000670737)..... <b>BC110</b>
<b>Steering</b> (5000820895)..... <b>P106-HD</b>	<b>Air Dryer</b> (Wabco, Right-Hand Thd.) (5001865037)..... <b>BA5379 +</b>	<b>Fuel</b> (5000814227)..... <b>BF988 +</b>
<b>Urea</b> (7420877953)..... <b>PE5271</b>	<b>Air Dryer</b> (Knorr, Left-Hand Thd.) (5001865404)..... <b>BA5566</b>	<b>O. Air</b> (5001834600)..... <b>PA3688</b>
C Serie C 480 w/Volvo DTI 13 Eng. (08/13-on)	<b>Trans.</b> (7401521527)..... <b>PT9417</b>	<b>I. Air</b> (5010066387)..... <b>PA3566</b>
<b>F-F Lube</b> (5001846641)..... <b>B76 +</b>	<b>Steering</b> (5000820895)..... <b>P106-HD</b>	<b>Coolant</b> (25MF429)..... <b>BW5179</b>
<b>B-P Lube</b> (7421561284)..... <b>B7409</b>	<b>Urea</b> (7421333098)..... <b>PE5271</b>	<b>Steering</b> (5000820895)..... <b>P106-HD</b>
<b>Severe Service F-F Lube</b> (5001846641)..... <b>B76-SS +</b>	Magnum AE 500 w/Mack EE9-502 Eng. (09/90-10/92)	Magnum AE500.19 w/Mack EE9 Eng.
<b>Fuel/Water Separator</b> (7421764981)..... <b>BF1386-O</b>	<b>F-F Lube</b> (5000670699)..... <b>B76 +</b>	<b>F-F Lube</b> (5000670700)..... <b>B76 +</b>
<b>Cab Air</b> (7482348995)..... <b>PA30114</b>	<b>B-P Lube Spinner</b> (5000670735)..... <b>BC110</b>	<b>B-P Lube Spinner</b> (5000670737)..... <b>BC110</b>
<b>Cab Air Pre-Filter</b> (7482379897)..... <b>PA30113</b>	<b>Severe Service F-F Lube</b> (5000670699)..... <b>B76-SS +</b>	<b>Fuel</b> (5000814227)..... <b>BF988 +</b>
<b>Air Dryer</b> (5001865404)..... <b>BA5566</b>	<b>Fuel</b> (870017560)..... <b>BF988 +</b>	<b>O. Air</b> (5001834600)..... <b>PA3688</b>
<b>Coolant</b> (Volvo 1699830)..... <b>BW5141</b>	<b>Air</b> (469.9 mm) (5010066304)..... <b>PA3688</b>	<b>I. Air</b> (5001834600)..... <b>PA3688</b>
<b>Steering</b> (5000820895)..... <b>P106-HD</b>	<b>Air</b> (475.5 mm) (5010317060)..... <b>PA3780</b>	<b>I. Air</b> (5010066387)..... <b>PA3566</b>
<b>Urea</b> (7421574991)..... <b>PE17000</b>	<b>Air Dryer</b> (Knorr, Left-hand Thd.) (5001865404)..... <b>BA5566</b>	<b>Coolant</b> (25MF429)..... <b>BW5179</b>
K Serie K 480 w/Volvo DTI 13 Eng. (08/13-on)	<b>Air Dryer</b> (Wabco, Right-hand Thd.) (5001865037)..... <b>BA5379 +</b>	<b>Steering</b> (5000820895)..... <b>P106-HD</b>
<b>F-F Lube</b> (5001846641)..... <b>B76 +</b>	<b>Coolant</b> (5000823838)..... <b>BW5179</b>	Magnum AE500.22 w/Mack EE9 Eng.
<b>B-P Lube</b> (7421561284)..... <b>B7409</b>	Magnum AE 500 Dxi w/Volvo DXi 13 Euro 4/5 Eng. (03)	<b>F-F Lube</b> (5000670700)..... <b>B76 +</b>
<b>Severe Service F-F Lube</b> (5001846641)..... <b>B76-SS +</b>	<b>F-F Lube</b> ..... <b>B76-SS +</b>	<b>B-P Lube Spinner</b> (5000670737)..... <b>BC110</b>
<b>Fuel/Water Separator</b> (7421764968)..... <b>BF1386-O</b>	<b>B-P Lube</b> ..... <b>B7685</b>	<b>Fuel</b> (5000814227)..... <b>BF988 +</b>
<b>Cab Air</b> (7482348995)..... <b>PA30114</b>	<b>Fuel</b> ..... <b>BF7814</b>	<b>O. Air</b> (5001834600)..... <b>PA3688</b>
<b>Cab Air Pre-Filter</b> (7482379897)..... <b>PA30113</b>	<b>Fuel/Water Separator</b> (7420514654)..... <b>BF1366-O</b>	<b>I. Air</b> (5010066387)..... <b>PA3566</b>
<b>Air Dryer</b> (5001865404)..... <b>BA5566</b>	<b>Radial Seal O. Air</b> (5001865723)..... <b>RS5390</b>	<b>Coolant</b> (25MF429)..... <b>BW5179</b>
<b>Coolant</b> (Volvo 1699830)..... <b>BW5141</b>	<b>Opt. Radial Seal I. Air</b> (5010317187)..... <b>RS5351</b>	<b>Steering</b> (5000820895)..... <b>P106-HD</b>
<b>Steering</b> (5000820895)..... <b>P106-HD</b>	<b>Air Dryer</b> (Wabco, Right-Hand Thd.) (5001865037)..... <b>BA5379 +</b>	<b>Urea</b> (7421574991)..... <b>PE17000</b>
<b>Urea</b> (7421574991)..... <b>PE17000</b>	<b>Air Dryer</b> (Knorr, Left-Hand Thd.) (5001865404)..... <b>BA5566</b>	T Serie T 480 w/Volvo DTI 13 Eng.
	<b>Trans.</b> (15215270)..... <b>PT9417</b>	<b>F-F Lube</b> (5001846641)..... <b>B76 +</b>
	<b>Steering</b> ..... <b>P106-HD</b>	<b>B-P Lube</b> (7421561284)..... <b>B7409</b>
	<b>Urea</b> (7421333098)..... <b>PE5271</b>	<b>Severe Service F-F Lube</b> (5001846641)..... <b>B76-SS +</b>
	Magnum AE500 w/Mack E9-500 Eng.	<b>Fuel/Water Separator</b> (7421764968)..... <b>BF1386-O</b>
	<b>Lube</b> ..... <b>B76 +</b>	<b>Radial Seal Air</b> (7421243188)..... <b>RS5730</b>
	<b>P. Fuel</b> ..... <b>BF877 +</b>	<b>Air</b> (Inner) (Volvo 21115501)..... <b>RS5731</b>
	<b>S. Fuel</b> ..... <b>BF976</b>	<b>Cab Air</b> (7482348995)..... <b>PA30114</b>
	Magnum AE500 w/Mack EE9 Eng.	<b>Cab Air Pre-Filter</b> (7482379897)..... <b>PA30113</b>
	<b>F-F Lube</b> (5000670700)..... <b>B76 +</b>	<b>Air Dryer</b> (5001865404)..... <b>BA5566</b>
	<b>B-P Lube Spinner</b> (5000670737)..... <b>BC110</b>	<b>Coolant</b> (Volvo 1699830)..... <b>BW5141</b>
	<b>Fuel</b> (5000814227)..... <b>BF988 +</b>	<b>Steering</b> (5000820895)..... <b>P106-HD</b>
	<b>O. Air</b> (5001834600)..... <b>PA3688</b>	<b>Urea</b> (7421574991)..... <b>PE17000</b>
	<b>I. Air</b> (5010066387)..... <b>PA3566</b>	Kerax 500 Dxi w/Volvo DXi13 Euro 4/5 Eng. (2008-on)
	<b>Coolant</b> (25MF429)..... <b>BW5179</b>	<b>F-F Lube</b> (7420709459)..... <b>B76-SS +</b>
	<b>Steering</b> (5000820895)..... <b>P106-HD</b>	<b>B-P Lube</b> (5001846647)..... <b>B7685</b>
		<b>Fuel/Water Separator</b> (7420754418)..... <b>BF9867-O</b>
		<b>Fuel</b> (7420541381)..... <b>BF7814</b>
		<b>Radial Seal Air</b> (5001865723)..... <b>RS5390</b>
		<b>Radial Seal I. Air</b> (5010269584)..... <b>RS3729</b>
		<b>Air Dryer</b> (Knorr, Left-hand Thd.) (5001865404)..... <b>BA5566</b>
		<b>Air Dryer</b> (Wabco, Right-hand Thd.) (5001865037)..... <b>BA5379 +</b>
		<b>Magnum AE500.26 Airtronic w/Mack EE9 Eng.</b>
		<b>F-F Lube</b> (5000670700)..... <b>B76 +</b>
		<b>B-P Lube Spinner</b> (5000670737)..... <b>BC110</b>
		<b>Fuel</b> (5000814227)..... <b>BF988 +</b>
		<b>O. Air</b> (5001834600)..... <b>PA3688</b>
		<b>I. Air</b> (5010066387)..... <b>PA3566</b>
		<b>Coolant</b> (25MF429)..... <b>BW5179</b>
		<b>Steering</b> (5000820895)..... <b>P106-HD</b>
		<b>Kerax 520 Dxi w/Dxi 13 Euro 4/5 Eng. (02/08-on)</b>
		<b>F-F Lube</b> (7420709459)..... <b>B76-SS +</b>
		<b>B-P Lube</b> (5001846647)..... <b>B7685</b>
		<b>B-P Lube</b> (Upgrade) (7421561284)..... <b>B7409</b>
		<b>Fuel/Water Separator</b> (7420998346)..... <b>BF1386-O</b>
		<b>Fuel/Water Separator</b> (7420998349)..... <b>BF1387-O</b>
		<b>Fuel</b> (7420541381)..... <b>BF7814</b>
		<b>Radial Seal O. Air</b> (5001865725)..... <b>RS30116</b>
		<b>Radial Seal I. Air</b> (5010269584)..... <b>RS3729</b>
		<b>Cab Air</b> (5001867491)..... <b>PA30188</b>
		<b>Air Dryer</b> (Knorr, Left-hand Thd.) (5001865404)..... <b>BA5566</b>
		<b>Air Dryer</b> (Wabco, Right-hand Thd.) (5001865037)..... <b>BA5379 +</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)
Kerax 520 Dxi w/Dxi 13 Euro 4/5 Eng. (02/08-on) (Cont'd)	C Serie C 520 w/Volvo DTI 13 Eng. (08/13-on)	560K6 w/Perkins 6.354.2, 6.354.4 Engs.
Trans. (7422051238)..... PT9417	F-F Lube (5001846641)..... B76 +	Lube Spin-on (3141914)..... B114
Steering (5000820895)..... P106-HD	B-P Lube (7421561284)..... B7409	Can-Type Fuel (7701010100)..... BF825 +
Urea (7420877953)..... PE5271	Severe Service F-F Lube (5001846641)..... B76-SS +	600KB
Magnum AE 520 w/Mack EE9-530 Eng. (10/92-03/96)	Fuel/Water Separator (7421764981)..... BF1386-O	Fuel Spin-on (3036404)..... BF797
F-F Lube (5000670699)..... B76 +	Cab Air (7482348995)..... PA30114	Can-Type Fuel (7701010100)..... BF825 +
B-P Lube Spinner (5000670735)..... BC110	Cab Air Pre-Filter (7482379897)..... PA30113	610K6 w/Perkins 6.354.2, 6.354.4 Engs.
Severe Service F-F Lube (5000670699)..... B76-SS +	Air Dryer (5001865404)..... BA5566	Lube Spin-on (3141914)..... B114
Fuel (870017560)..... BF988 +	Coolant (Volvo 1699830)..... BW5141	Can-Type Fuel (7701010100)..... BF825 +
Air (469.9 mm) (5010066304)..... PA3688	Steering (5000820895)..... P106-HD	620KB w/M 420.30 Eng.
Air (475.5 mm) (5010317060)..... PA3780	Urea (7421574991)..... PE17000	Lube (5000670670)..... B403
Air Dryer (Knorr, Left-hand Thd.) (5001865404)..... BA5566	K Serie K 520 w/Volvo DTI 13 Eng. (08/13-on)	Can-Type Fuel (7701010100)..... BF825 +
Air Dryer (Wabco, Right-hand Thd.) (5001865037)..... BA5379 +	F-F Lube (5001846641)..... B76 +	Air (4207090)..... PA2845
Coolant (5000823838)..... BW5179	B-P Lube (7421561284)..... B7409	650H w/M.A.N. Eng.
Magnum AE520 w/Mack EE9 Eng.	Severe Service F-F Lube (5001846641)..... B76-SS +	Lube (4055040006)..... P235
F-F Lube (5000670700)..... B76 +	Fuel/Water Separator (7421764968)..... BF1386-O	P. Fuel (854806000)..... F953-F
B-P Lube Spinner (5000670737)..... BC110	Cab Air (7482348995)..... PA30114	S. Fuel (870176000)..... PF834
Fuel (5000814227)..... BF988 +	Cab Air Pre-Filter (7482379897)..... PA30113	660KB, 680KB
O. Air (5001834600)..... PA3688	Air Dryer (5001865404)..... BA5566	Fuel Spin-on (3036404)..... BF797
I. Air (5010066387)..... PA3566	Coolant (Volvo 1699830)..... BW5141	Can-Type Fuel (7701010100)..... BF825 +
Coolant (25MF429)..... BW5179	Steering (5000820895)..... P106-HD	700KB w/M 420.30 Eng.
Steering (5000820895)..... P106-HD	Urea (7421574991)..... PE17000	Lube (5000670670)..... B403
Magnum AE 520 Dxi 13 w/Dxi 13 Euro 4/5 Eng. (03/09-on)	T Serie T 520 w/Volvo DTI 13 Eng.	Can-Type Fuel (7701010100)..... BF825 +
F-F Lube (7420709459)..... B76-SS +	F-F Lube (5001846641)..... B76 +	Air (4207090)..... PA2845
B-P Lube (5001846647)..... B7685	B-P Lube (7421561284)..... B7409	GL750 w/Perkins 6.354 Eng.
B-P Lube (Upgrade) (7421561284)..... B7409	Severe Service F-F Lube (5001846641)..... B76-SS +	Lube Ele. (3082658)..... PT12
Fuel/Water Separator (7420998346)..... BF1386-O	Fuel/Water Separator (7421764968)..... BF1386-O	Lube Spin-on..... BT216 +
Fuel/Water Separator (7420998349)..... BF1387-O	Radial Seal Air (7421243188)..... RS5730	770K
Fuel (7420541381)..... BF7814	Air (Inner) (Volvo 21115501)..... RS5731	Can-Type Fuel (7701010100)..... BF825 +
Radial Seal O. Air (5001865723)..... RS5390	Cab Air (7482348995)..... PA30114	Fuel Spin-on (3036404)..... BF797
Radial Seal I. Air (5010317187)..... RS5351	Cab Air Pre-Filter (7482379897)..... PA30113	770KB w/M 420.30 Eng.
Air Dryer (Knorr, Left-hand Thd.) (5001865404)..... BA5566	Air Dryer (5001865404)..... BA5566	Lube (5000670670)..... B403
Air Dryer (Wabco, Right-hand Thd.) (5001865037)..... BA5379 +	Coolant (Volvo 1699830)..... BW5141	Can-Type Fuel (7701010100)..... BF825 +
Trans. (7422051238)..... PT9417	Steering (5000820895)..... P106-HD	Air (4207090)..... PA2845
Steering (5000820895)..... P106-HD	Urea (7421574991)..... PE17000	770KB, 771K, 771KB, 880K, 880KBT
Urea (7420877953)..... PE5271	Magnum AE 560 w/Mack EE9 Eng. (02/96-02/00)	Can-Type Fuel (7701010100)..... BF825 +
Magnum AE520.19 Airtronic w/Mack EE9 Eng.	F-F Lube (5000670699)..... B76 +	Fuel Spin-on (3036404)..... BF797
F-F Lube (5000670700)..... B76 +	B-P Lube Spinner (5000670735)..... BC110	880KBT
B-P Lube Spinner (5000670737)..... BC110	Severe Service F-F Lube (5000670699)..... B76-SS +	Lube (5000670670)..... B403
Fuel (5000814227)..... BF988 +	Fuel (870017560)..... BF988 +	Can-Type Fuel (7701010100)..... BF825 +
O. Air (5001834600)..... PA3688	Radial Seal O. Air (5010230841)..... RS3727	O. Air (4207090)..... PA2845
I. Air (5010066387)..... PA3566	Radial Seal I. Air (5010317187)..... RS5351	881KB
Coolant (25MF429)..... BW5179	Air (469.9 mm) (5010066304)..... PA3688	Can-Type Fuel (7701010100)..... BF825 +
Steering (5000820895)..... P106-HD	Air (475.5 mm) (5010317060)..... PA3780	Fuel Spin-on (3036404)..... BF797
	Air Dryer (Knorr, Left-hand Thd.) (5001865404)..... BA5566	881KBT
	Air Dryer (Wabco, Right-hand Thd.) (5001865037)..... BA5379 +	Lube (5000670670)..... B403
	Coolant (5000823838)..... BW5179	Can-Type Fuel (7701010100)..... BF825 +
	Steering (5000820895)..... P106-HD	GL900, GL900E w/M 420.30 Eng.
		Lube (504020)..... B403
		Can-Type Fuel (855589600)..... BF825 +
		349.3 mm O. Air (3563565)..... PA2845
		341.3 mm I. Air..... PA2837

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)	R.V.I. Trucks (cont'd)
GL900, GL900E w/M 420.30 Eng. (Cont'd) 381.0 mm O. Air (4212748)..... PA2474 379.4 mm I. Air (5000802978)..... PA2836	5130,06/08/09/11/13/14 w/797 Eng. (Cont'd) 339.7 mm Air (5000243970)..... PA3446 Coolant (5000663625)..... BW5139	Premium 260 w/MIDR 06.02.45 Eng. F-F Lube (5000670700)..... B76 + B-P Lube Spinner (5000670737)..... BC110 Fuel (22852800)..... BF988 + Fuel/Water Separator..... BF1221 + 465.9 mm Radial Seal O. Air (5010230841)..... RS3727 555.6 mm Radial Seal O. Air (5010230916)..... RS3728 Radial Seal I. Air (5010269584)..... RS3729 Steering (Iveco 1902137)..... P106-HD Gearbox Hyd. (5000791145)..... B307
TL900 w/M 420.30 Eng. Lube (504020)..... B403 Can-Type Fuel (855589600)..... BF825 + 349.3 mm O. Air (3563565)..... PA2845 341.3 mm I. Air..... PA2837 381.0 mm O. Air..... PA2474 379.4 mm I. Air..... PA2836	6126 w/597 Eng. Lube Spin-on (5000040870)..... B114 7521 w/Fulger Eng. Lube (24151104)..... P7017 Fuel..... BF719	Premium 340 w/MIDR 06.02.45 Eng. F-F Lube (5000670700)..... B76 + B-P Lube Spinner (5000670737)..... BC110 Fuel (22852800)..... BF988 + Fuel/Water Separator..... BF1221 + 465.9 mm Radial Seal O. Air (5010230841)..... RS3727 555.6 mm Radial Seal O. Air (5010230916)..... RS3728 536.6 mm Radial Seal I. Air (5010269584)..... RS3729 Steering (Iveco 1902137)..... P106-HD Gearbox Hyd. (5000791145)..... B307
950 Lube (5000670670)..... B403 Can-Type Fuel (7701010100)..... BF825 +	GBA O. Air (3564105)..... PA2418-FN + I. Air (3564106)..... PA2419	TBHO B-P Lube (944700122)..... P41 Fuel Ele. (24866092)..... PF950
950BKT6 Lube Spin-on (24564103)..... B403	GBD (4x4) w/MID 06.20.30 Eng. Lube (504020)..... B403 O. Air (5000241796)..... PA2405	Traffic w/SOFIM Diesel Eng. Lube (To 3/86) (7701349779)..... BT5 Fuel Ele. (5000241250)..... PF7596 71.4 mm Fuel Can-Type..... BF825 + 112.7 mm Fuel Can-Type..... BF884 Fuel Spin-on (770130546)..... BF587-D +
950BKT6A, 950BKT6B, 950BKT6C, 950BKT6E w/MID 620.30 Eng. Lube (24564058)..... B236 +	GBD (6x6) O. Air (3564118)..... PA1885 + I. Air (3564119)..... PA1893	Traffic w/Gas Eng. 81.8 mm Lube..... B173-S 110.3 mm Lube..... B233 Air..... PA2099
950KB Lube (5000670670)..... B403 Can-Type Fuel (7701010100)..... BF825 + Air (4207090)..... PA2845	GBH (6x6) w/MIDS 06.35.40 Eng. Lube (4307426)..... PT670 111.1 mm Fuel Spin-on (941718018)..... BF719 136.5 mm Fuel Spin-on (3036404)..... BF797 Single Air (3564001)..... PA1646-FN O. Air (3564115)..... PA1911 I. Air (3564117)..... PA1884 +	TRK w/640 Eng. B-P Lube (944700123)..... P42
950KB, 950KBT w/MIDS 06.20.30 Eng. Lube (24564103)..... B403 O. Air (5000241796)..... PA2405 I. Air (5000802977)..... PA2835	GBK, GBO Lube Ele. (944700122)..... P41 Fuel Ele. (24866092)..... PF950	
950KB6S, 950KBT1S w/MIDS 06.20.30 Eng. Lube (5000670670)..... B403 O. Air (5000242503)..... PA2474 I. Air (5000802978)..... PA2836	JE w/R.V.I. 797 Eng. 134.1 mm Lube (5000040870)..... B114 206.4 mm Lube (5000670670)..... B403 Fuel Spin-on (5000814227)..... BF988 + 339.7 mm Air (5000243970)..... PA3446	
951KB, 951KBF Lube (5000670670)..... B403 Can-Type Fuel (7701010100)..... BF825 + Air (4207090)..... PA2845	Master Diesel w/SOFIM Eng. Lube (To 3/86) (7701349779)..... BT5 Fuel Ele. (5000241250)..... PF7596 71.4 mm Fuel Can-Type..... BF825 + 112.7 mm Fuel Can-Type..... BF884	
1080H w/M.A.N. Eng. Lube (4055040006)..... P235 P. Fuel (854806000)..... F953-F S. Fuel (870176000)..... PF834	Master Diesel J8S Lube (7701349942)..... B7352 Can-Type Fuel..... BF884 Fuel Spin-on (770130546)..... BF587-D +	
1080H Lube (4055040006)..... P235 P. Fuel Ele. (24866064)..... F950-F S. Fuel Ele. (24866092)..... PF950	Premium 250 w/MIDR 06.02.26 Eng. F-F Lube (5000670700)..... B76 + B-P Lube Spinner (5000670737)..... BC110 Fuel (22852800)..... BF988 + Fuel/Water Separator..... BF1221 + Radial Seal O. Air (5010230916)..... RS3728 Radial Seal I. Air (5010269584)..... RS3729 Single Radial Seal Air (5010230841)..... RS3727 Steering (Iveco 1902137)..... P106-HD Gearbox Hyd. (5000791145)..... B307	
1521, 1530, 1531 w/Fulger Eng. Lube (24151104)..... P7017 Fuel Spin-on..... BF719		
4123, 4154 w/Fulger Eng. Lube (24151104)..... P7017 Fuel Spin-on..... BF719		
5130,06/08/09/11/13/14 w/797 Eng. 206.4 mm Lube Spin-on (5000670670)..... B403 134.1 mm Lube Spin-on (5000040870)..... B114 Can-Type Fuel (7701010100)..... BF825 + Fuel Spin-on (5000814227)..... BF988 + 296.9 mm Air (5000809894)..... PA2865		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

RAINIER Trucks (cont'd)	
RT1600 w/Cummins ISB (6.7L) Eng. (Cont'd)	
Trans. Ele. (2 In. Kit) (Allison 29548987).....	PT9416-MPG KIT
Trans. Ele. (4 In. Kit) (Allison 29548988).....	PT9415-MPG KIT
RT1950 w/Cummins ISB (6.7L) Eng.	
Lube (3937736).....	B7177
Fuel (Fleetguard FF5632).....	BF7940
Crankcase Breather (Fleetguard CV52001).....	CV15010
Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965).....	20004
Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965).....	20016
Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966).....	20003
Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966).....	20017
Trans. Spin-on (Allison 29539579).....	BT8460
Trans. Ele. (2 In. Kit) (Allison 29548987).....	PT9416-MPG KIT
Trans. Ele. (4 In. Kit) (Allison 29548988).....	PT9415-MPG KIT
RT2600 w/Cummins ISB (6.7L) Eng.	
Lube (3937736).....	B7177
Fuel (Fleetguard FF5632).....	BF7940
Crankcase Breather (Fleetguard CV52001).....	CV15010
Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965).....	20004
Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965).....	20016
Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966).....	20003
Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966).....	20017
Trans. Spin-on (Allison 29539579).....	BT8460
Trans. Ele. (2 In. Kit) (Allison 29548987).....	PT9416-MPG KIT
Trans. Ele. (4 In. Kit) (Allison 29548988).....	PT9415-MPG KIT
RT3300 w/Cummins ISB (6.7L) Eng.	
Lube (3937736).....	B7177
Fuel (Fleetguard FF5632).....	BF7940
Crankcase Breather (Fleetguard CV52001).....	CV15010
Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965).....	20004
Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965).....	20016
Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966).....	20003
Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966).....	20017
Trans. Spin-on (Allison 29539579).....	BT8460

RAINIER Trucks (cont'd)	
RT3300 w/Cummins ISB (6.7L) Eng. (Cont'd)	
Trans. Ele. (2 In. Kit) (Allison 29548987).....	PT9416-MPG KIT
Trans. Ele. (4 In. Kit) (Allison 29548988).....	PT9415-MPG KIT
RAM Trucks	
4500 w/V8-392 (6.4L) Eng. (2014-16)	
Lube (4892339AB).....	B160
Fuel (N/S).....	N/S
Air (68190705AA).....	PA10022
Trans. 4 x 2 (5179267AC).....	19999
Trans. 4 x 4 (5179267AC).....	20000
4500 w/V8-392 (6.4L) Eng. (2017)	
Lube (4892339AB).....	B160
Fuel (N/S).....	N/S
Air (68190705AA).....	PA10022
Cabin Air (5058693AA).....	PA4373
Trans. (68224232AA).....	20070
4500 w/V8-392 (6.4L) Eng. (2018)	
Lube (4892339AB).....	B160
Fuel (N/S).....	N/S
Air (68190705AA).....	PA10022
Cabin Air (68406048AA).....	PA10136
Trans. (68224232AA).....	20070
4500 w/V8-392 (6.4L) Eng. (2019)	
Lube (4892339AB).....	B160
Fuel (N/S).....	N/S
Air (53034051AB).....	PA4318
Cab Air (68406048AA).....	PA10136
Trans. (68224232AA).....	20070
4500 w/V8-392 (6.4L) Eng. (2020)	
Lube (4892339AB).....	B160
Fuel (N/S).....	N/S
Air (53034051AB).....	PA4318
Cab Air (68406048AA).....	PA10136
4500 w/V8-392 (6.4L) Eng. (2021)	
Lube (4892339AB).....	B160
Fuel (N/S).....	N/S
Air (53034051AB).....	PA4318
Cab Air (68406048AA).....	PA10136
4500 w/L6-408 (6.7L) Turbo Diesel Eng. (2011-12)	
Lube (5083285AA).....	BT7349
Fuel/Water Separator Spin-on (Mounted Under Cab Frame) (68197867AA).....	BF46031
Fuel Ele. (68065608AA).....	PF9870
Air (53034051AB).....	PA4318
Crankcase Breather (68002433AB).....	CV15010
Trans. (68224232AA).....	20070
Trans. (66RFE) (68019688AA).....	20025

RAM Trucks (cont'd)	
4500 w/L6-408 (6.7L) Turbo Diesel Eng. (2013)	
Lube (5083285AA).....	BT7349
Fuel/Water Separator Spin-on (Mounted Under Cab Frame) (68197867AA).....	BF46031
Fuel Ele. (68065608AA).....	PF9870
Fuel Ele. (Late 2013 Models) (68157291AA).....	PF46108
Air (53034051AB).....	PA4318
Crankcase Breather (68002433AB).....	CV15010
Trans. (68224232AA).....	20070
Trans. (66RFE) (68019688AA).....	20025
4500 w/L6-408 (6.7L) Turbo Diesel Eng. (2014-17)	
Lube (5083285AA).....	BT7349
Fuel/Water Separator Spin-on (Mounted Under Cab Frame) (68197867AA).....	BF46031
Fuel Ele. (Under Hood-Drivers Side) (68157291AA).....	PF46108
Air (53034051AB).....	PA4318
Opt. Cab Air (68406048AA).....	PA10136
Crankcase Breather (68002433AB).....	CV15010
Trans. (68224232AA).....	20070
Trans. (66RFE) (68019688AA).....	20025
4500 w/L6-408 (6.7L) Turbo Diesel Eng. (2018)	
Lube (5083285AA).....	BT7349
Fuel/Water Separator Spin-on (Mounted Under Cab Frame) (68197867AA).....	BF46031
Fuel Ele. (Under Hood-Drivers Side) (68157291AA).....	PF46108
Air (53034051AB).....	PA4318
Cabin Air (68406048AA).....	PA10136
Crankcase Breather (68002433AC).....	CV15010
Trans. (68224232AA).....	20070
4500 w/L6-408 (6.7L) Turbo Diesel Eng. (2019)	
Lube (5083285AA).....	BT7349
Fuel/Water Separator (Frame Mounted) (68436631AA).....	PF46152
Fuel (Under Hood) (68157291AA).....	PF46108
Air (53034051AB).....	PA4318
Cab Air (68406048AA).....	PA10136
Crankcase Breather (68002433AC).....	CV15010
Trans. (68224232AA).....	20070
4500 w/L6-408 (6.7L) Turbo Diesel Eng. (2020)	
Lube (5083285AA).....	BT7349
Fuel/Water Separator (Mounted Under Cab Frame) (68436631AA).....	PF46152
Fuel/Water Separator (Under Hood) (68157291AA).....	PF46108
Air (53034051AB).....	PA4318
Cab Air (68406048AA).....	PA10136

Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>RAM Trucks (cont'd)</b>	<b>RAM Trucks (cont'd)</b>	<b>RAM Trucks (cont'd)</b>
4500 w/L6-408 (6.7L) Turbo Diesel Eng. (2020) (Cont'd) <b>Crankcase Breather</b> (68002433AC)..... <b>CV15010</b> <b>Trans.</b> (68224232AA)..... <b>20070</b>	5500 w/V8-392 (6.4L) Eng. (2021) <b>Lube</b> (4892339AB)..... <b>B160</b> <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Air</b> (53034051AB)..... <b>PA4318</b> <b>Cab Air</b> (68406048AA)..... <b>PA10136</b>	5500 w/L6-408 (6.7L) Turbo Diesel Eng. (2018) <b>Lube</b> (5083285AA)..... <b>BT7349</b> <b>Fuel/Water Separator Spin-on</b> (Mounted Under Cab Frame) (68197867AA)..... <b>BF46031</b> <b>Fuel Ele.</b> (Under Hood-Drivers Side) (68157291AA)..... <b>PF46108</b> <b>Air</b> (53034051AB)..... <b>PA4318</b> <b>Cabin Air</b> (68406048AA)..... <b>PA10136</b> <b>Cabin Air</b> (5058693AA)..... <b>PA4373</b> <b>Crankcase Breather</b> (68002433AC)..... <b>CV15010</b> <b>Trans.</b> (68224232AA)..... <b>20070</b>
4500 w/L6-408 (6.7L) Turbo Diesel Eng. (2021) <b>Lube</b> (5083285AA)..... <b>BT7349</b> <b>Fuel/Water Separator</b> (Under Hood) (68157291AA)..... <b>PF46108</b> <b>Fuel/Water Separator</b> (Frame Mounted) (68436631AA)..... <b>PF46152</b> <b>Air</b> (68517554AA)..... <b>PA4318</b> <b>Cab Air</b> (68406048AA)..... <b>PA10136</b> <b>Crankcase Breather</b> (68002433AC)..... <b>CV15010</b> <b>Trans.</b> (68224232AA)..... <b>20070</b>	5500 w/L6-408 (6.7L) Turbo Diesel Eng. (2011-12) <b>Lube</b> (5083285AA)..... <b>BT7349</b> <b>Fuel/Water Separator Spin-on</b> (Mounted Under Cab Frame) (68197867AA)..... <b>BF46031</b> <b>Fuel Ele.</b> (68065608AA)..... <b>PF9870</b> <b>Air</b> (53034051AB)..... <b>PA4318</b> <b>Crankcase Breather</b> (68002433AB)..... <b>CV15010</b> <b>Trans.</b> (68224232AA)..... <b>20070</b> <b>Trans.</b> (66RFE) (68019688AA)..... <b>20025</b>	5500 w/L6-408 (6.7L) Turbo Diesel Eng. (2019) <b>Lube</b> (5083285AA)..... <b>BT7349</b> <b>Fuel/Water Separator</b> (Frame Mounted) (68436631AA)..... <b>PF46152</b> <b>Fuel</b> (Under Hood) (68157291AA)..... <b>PF46108</b> <b>Air</b> (53034051AB)..... <b>PA4318</b> <b>Cab Air</b> (68406048AA)..... <b>PA10136</b> <b>Crankcase Breather</b> (68002433AC)..... <b>CV15010</b> <b>Trans.</b> (68224232AA)..... <b>20070</b>
4500 w/L6-408 (6.7L) Turbo Diesel Eng. (2022) <b>Lube</b> (5083285AA)..... <b>BT7349</b> <b>Fuel/Water Separator</b> (Under Hood) (68157291AA)..... <b>PF46108</b> <b>Fuel/Water Separator</b> (Frame Mounted) (68436631AA)..... <b>PF46152</b> <b>Air</b> (68517554AA)..... <b>PA4318</b> <b>Cab Air</b> (68406048AA)..... <b>PA10136</b> <b>Crankcase Breather</b> (68002433AC)..... <b>CV15010</b> <b>Trans.</b> (68224232AA)..... <b>20070</b>	5500 w/L6-408 (6.7L) Turbo Diesel Eng. (2013) <b>Lube</b> (5083285AA)..... <b>BT7349</b> <b>Fuel/Water Separator Spin-on</b> (Mounted Under Cab Frame) (68197867AA)..... <b>BF46031</b> <b>Fuel Ele.</b> (To Early 2013 Models) (68065608AA)..... <b>PF9870</b> <b>Fuel Ele.</b> (Late 2013 Models) (68157291AA)..... <b>PF46108</b> <b>Air</b> (53034051AB)..... <b>PA4318</b> <b>Crankcase Breather</b> (68002433AB)..... <b>CV15010</b> <b>Trans.</b> (68224232AA)..... <b>20070</b> <b>Trans.</b> (66RFE) (68019688AA)..... <b>20025</b>	5500 w/L6-408 (6.7L) Turbo Diesel Eng. (2020) <b>Lube</b> (5083285AA)..... <b>BT7349</b> <b>Fuel/Water Separator</b> (Mounted Under Cab Frame) (68436631AA) <b>PF46152</b> <b>Fuel/Water Separator</b> (Under Hood) (68157291AA)..... <b>PF46108</b> <b>Air</b> (53034051AB)..... <b>PA4318</b> <b>Cab Air</b> (68406048AA)..... <b>PA10136</b> <b>Crankcase Breather</b> (68002433AC)..... <b>CV15010</b> <b>Trans.</b> (68224232AA)..... <b>20070</b>
5500 w/V8-392 (6.4L) Eng. (2014-16) <b>Lube</b> (4892339AB)..... <b>B160</b> <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Air</b> (68190705AA)..... <b>PA10022</b> <b>Trans. 4 x 2</b> (5179267AC)..... <b>19999</b> <b>Trans. 4 x 4</b> (5179267AC)..... <b>20000</b>	5500 w/L6-408 (6.7L) Turbo Diesel Eng. (2014-16) <b>Lube</b> (5083285AA)..... <b>BT7349</b> <b>Fuel/Water Separator Spin-on</b> (Mounted Under Cab Frame) (68197867AA)..... <b>BF46031</b> <b>Fuel Ele.</b> (Under Hood-Drivers Side) (68157291AA)..... <b>PF46108</b> <b>Air</b> (53034051AB)..... <b>PA4318</b> <b>Opt. Cab Air</b> (68406048AA)..... <b>PA10136</b> <b>Crankcase Breather</b> (68002433AB)..... <b>CV15010</b> <b>Trans.</b> (68224232AA)..... <b>20070</b> <b>Trans.</b> (66RFE) (68019688AA)..... <b>20025</b>	5500 w/L6-408 (6.7L) Turbo Diesel Eng. (2021) <b>Lube</b> (5083285AA)..... <b>BT7349</b> <b>Fuel/Water Separator</b> (Under Hood) (68157291AA)..... <b>PF46108</b> <b>Fuel/Water Separator</b> (Frame Mounted) (68436631AA)..... <b>PF46152</b> <b>Air</b> (68517554AA)..... <b>PA4318</b> <b>Cab Air</b> (68406048AA)..... <b>PA10136</b> <b>Crankcase Breather</b> (68002433AC)..... <b>CV15010</b> <b>Trans.</b> (68224232AA)..... <b>20070</b>
5500 w/V8-392 (6.4L) Eng. (2017) <b>Lube</b> (4892339AB)..... <b>B160</b> <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Air</b> (68190705AA)..... <b>PA10022</b> <b>Cabin Air</b> (5058693AA)..... <b>PA4373</b> <b>Trans.</b> (68224232AA)..... <b>20070</b>	5500 w/L6-408 (6.7L) Turbo Diesel Eng. (2017) <b>Lube</b> (5083285AA)..... <b>BT7349</b> <b>Fuel/Water Separator Spin-on</b> (Mounted Under Cab Frame) (68197867AA)..... <b>BF46031</b> <b>Fuel Ele.</b> (Under Hood-Drivers Side) (68157291AA)..... <b>PF46108</b> <b>Air</b> (53034051AB)..... <b>PA4318</b> <b>Cabin Air</b> (68406048AA)..... <b>PA10136</b> <b>Crankcase Breather</b> (68002433AB)..... <b>CV15010</b> <b>Trans.</b> (68224232AA)..... <b>20070</b> <b>Trans.</b> (66RFE) (68019688AA)..... <b>20025</b>	5500 w/L6-408 (6.7L) Turbo Diesel Eng. (2022) <b>Lube</b> (5083285AA)..... <b>BT7349</b> <b>Fuel/Water Separator</b> (Under Hood) (68157291AA)..... <b>PF46108</b> <b>Fuel/Water Separator</b> (Frame Mounted) (68436631AA)..... <b>PF46152</b> <b>Air</b> (68517554AA)..... <b>PA4318</b> <b>Cab Air</b> (68406048AA)..... <b>PA10136</b> <b>Crankcase Breather</b> (68002433AC)..... <b>CV15010</b> <b>Trans.</b> (68224232AA)..... <b>20070</b>
5500 w/V8-392 (6.4L) Eng. (2018) <b>Lube</b> (4892339AB)..... <b>B160</b> <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Air</b> (68190705AA)..... <b>PA10022</b> <b>Cabin Air</b> (68406048AA)..... <b>PA10136</b> <b>Trans.</b> (68224232AA)..... <b>20070</b>	5500 w/L6-408 (6.7L) Turbo Diesel Eng. (2017) <b>Lube</b> (5083285AA)..... <b>BT7349</b> <b>Fuel/Water Separator Spin-on</b> (Mounted Under Cab Frame) (68197867AA)..... <b>BF46031</b> <b>Fuel Ele.</b> (Under Hood-Drivers Side) (68157291AA)..... <b>PF46108</b> <b>Air</b> (53034051AB)..... <b>PA4318</b> <b>Cabin Air</b> (68406048AA)..... <b>PA10136</b> <b>Crankcase Breather</b> (68002433AB)..... <b>CV15010</b> <b>Trans.</b> (68224232AA)..... <b>20070</b> <b>Trans.</b> (66RFE) (68019688AA)..... <b>20025</b>	
5500 w/V8-392 (6.4L) Eng. (2019) <b>Lube</b> (4892339AB)..... <b>B160</b> <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Air</b> (53034051AB)..... <b>PA4318</b> <b>Cab Air</b> (68406048AA)..... <b>PA10136</b> <b>Trans.</b> (68224232AA)..... <b>20070</b>	5500 w/L6-408 (6.7L) Turbo Diesel Eng. (2017) <b>Lube</b> (5083285AA)..... <b>BT7349</b> <b>Fuel/Water Separator Spin-on</b> (Mounted Under Cab Frame) (68197867AA)..... <b>BF46031</b> <b>Fuel Ele.</b> (Under Hood-Drivers Side) (68157291AA)..... <b>PF46108</b> <b>Air</b> (53034051AB)..... <b>PA4318</b> <b>Cabin Air</b> (68406048AA)..... <b>PA10136</b> <b>Crankcase Breather</b> (68002433AB)..... <b>CV15010</b> <b>Trans.</b> (68224232AA)..... <b>20070</b>	
5500 w/V8-392 (6.4L) Eng. (2020) <b>Lube</b> (4892339AB)..... <b>B160</b> <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Air</b> (53034051AB)..... <b>PA4318</b> <b>Cab Air</b> (68406048AA)..... <b>PA10136</b>	5500 w/L6-408 (6.7L) Turbo Diesel Eng. (2017) <b>Lube</b> (5083285AA)..... <b>BT7349</b> <b>Fuel/Water Separator Spin-on</b> (Mounted Under Cab Frame) (68197867AA)..... <b>BF46031</b> <b>Fuel Ele.</b> (Under Hood-Drivers Side) (68157291AA)..... <b>PF46108</b> <b>Air</b> (53034051AB)..... <b>PA4318</b> <b>Cabin Air</b> (68406048AA)..... <b>PA10136</b> <b>Crankcase Breather</b> (68002433AB)..... <b>CV15010</b> <b>Trans.</b> (68224232AA)..... <b>20070</b>	

Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



RENAULT European Light Duty Vehicles	RENAULT European Light Duty Vehicles (cont'd)	RENAULT European Light Duty Vehicles (cont'd)
Kangoo I 1.5 DCI w/K9K Eng. (11/02-on) <b>Lube</b> (7702144083)..... <b>B7276</b> <b>Air</b> (8200023480)..... <b>PA10007</b>	Mascott 130 DXI w/DXI 3 Eng. (05/04-on) <b>Lube</b> (7701057828)..... <b>P7365</b> <b>Steering</b> (5000820895)..... <b>P106-HD</b>	Master I 2.1 Diesel (CAV System H 72) w/J8S-330 Eng. (09/80-07/98) <b>Lube</b> (8200007832)..... <b>B7432</b> <b>Fuel</b> (7701016181)..... <b>BF825 +</b>
Kangoo I 1.5 DCI w/K9K702 Eng. (07/01-on) <b>Lube</b> (7702144083)..... <b>B7276</b> <b>Air</b> (8200023480)..... <b>PA10007</b>	Mascott 130.35 w/DXI 3 Eng. (05/04-on) <b>Lube</b> (7701057828)..... <b>P7365</b> <b>Steering</b> (5000820895)..... <b>P106-HD</b>	Master I 2.1 Diesel (CAV System H 112) w/J8S-330 Eng. (09/80-07/98) <b>Lube</b> (8200007832)..... <b>B7432</b> <b>Fuel</b> (7701028181)..... <b>BF884</b>
Kangoo I 1.5 DCI w/K9K710 Eng. (04/02-on) <b>Lube</b> (7702144083)..... <b>B7276</b> <b>Air</b> (8200023480)..... <b>PA10007</b>	Mascott 130.50 w/DXI 3 Eng. (05/04-on) <b>Lube</b> (7701057828)..... <b>P7365</b> <b>Steering</b> (5000820895)..... <b>P106-HD</b>	Master I 2.2 w/J5R-718 Eng. (10/86-07/98) <b>Lube</b> (7700856339)..... <b>B7352</b> <b>Fuel</b> ..... <b>BF7736</b> <b>Air</b> (5001000878)..... <b>PA4890</b>
Kangoo I 1.5 DCI w/K9K714 Eng. (06/05-on) <b>Lube</b> (7702144083)..... <b>B7276</b> <b>Air</b> (8200023480)..... <b>PA10007</b>	Mascott 130.55 w/DXI 3 Eng. (05/04-on) <b>Lube</b> (7701057828)..... <b>P7365</b> <b>Steering</b> (5000820895)..... <b>P106-HD</b>	Master I 2.2i w/J7T-782 Eng. (09/80-07/98) <b>Lube</b> (7700856339)..... <b>B7352</b> <b>Fuel</b> (4055020005)..... <b>BF1195</b> <b>Air</b> (5001000878)..... <b>PA4890</b>
Kangoo I 1.5 DCI w/K9K718 Eng. (06/05-on) <b>Lube</b> (7702144083)..... <b>B7276</b> <b>Air</b> (8200023480)..... <b>PA10007</b>	Mascott 130.65 w/DXI 3 Eng. (05/04-on) <b>Lube</b> (7701057828)..... <b>P7365</b> <b>Steering</b> (5000820895)..... <b>P106-HD</b>	Master I 2.5 Diesel w/S8U770 Eng. (06/97-07/98) <b>Dual-Flow Lube</b> (7701035650).... <b>BD232</b>
Kangoo I 1.6 16 V w/K4M750/753 Eng. (07/01-on) <b>Lube</b> (7702144083)..... <b>B7276</b>	Mascott 150 DCI w/DCI 2.8 Eng. (10/01-07/04) <b>Dual-Flow Lube</b> (7701035650).... <b>BD232</b> <b>Fuel</b> (7700700092)..... <b>BF587-D +</b> <b>Fuel</b> (5001846015)..... <b>BF7989-D</b> <b>Air</b> (5001847123)..... <b>PA30149</b> <b>Steering</b> (5000820895)..... <b>P106-HD</b>	Master I 2.5 Diesel w/Sofim 814067 (S8U742) Eng. (08/89-07/98) <b>Dual-Flow Lube</b> (7701035650).... <b>BD232</b> <b>Fuel</b> (7701028181)..... <b>BF884</b> <b>Air</b> (5001000878)..... <b>PA4890</b>
Kangoo I 1.6 16 V Bivalent (CNG) w/K4M Eng. (07/06-on) <b>Lube</b> (7702144083)..... <b>B7276</b>	Mascott 150 DXI w/DXI 3 Eng. (05/04-on) <b>Lube</b> (7701057828)..... <b>P7365</b> <b>Steering</b> (5000820895)..... <b>P106-HD</b>	Master I 2.5 TD (Bosch System) w/Sofim 8140.27-S9U714 Eng. (09/80-07/98) <b>Dual-Flow Lube</b> (7701035650).... <b>BD232</b> <b>Fuel</b> (854975700)..... <b>PF7596</b> <b>Air</b> (5001000878)..... <b>PA4890</b>
Kangoo I 1.9 DCI w/F9Q Eng. (10/03-on) <b>Air</b> (7701047285)..... <b>PA4319</b> <sup>90</sup>	Mascott 150 DXI w/DXI 3 Eng. (05/04-on) <b>Lube</b> (7701057828)..... <b>P7365</b> <b>Steering</b> (5000820895)..... <b>P106-HD</b>	Master I 2.5 TD (CAV System H 72) w/Sofim 8140.27-S9U714 Eng. (09/80-07/98) <b>Dual-Flow Lube</b> (7701035650).... <b>BD232</b> <b>Fuel</b> (7701016181)..... <b>BF825 +</b> <b>Air</b> (5001000878)..... <b>PA4890</b>
Kangoo I 1.9 DCI w/F9Q-782/790 Eng. (09/01-on) <b>Air</b> (7701047285)..... <b>PA4319</b> <sup>90</sup>	Mascott 160 DXI w/DXI 3 Eng. (05/04-on) <b>Lube</b> (7701057828)..... <b>P7365</b> <b>Steering</b> (5000820895)..... <b>P106-HD</b>	Master I 2.5 TD (CAV System H 112) w/Sofim 8140.27-S9U714 Eng. (09/80-07/98) <b>Dual-Flow Lube</b> (7701035650).... <b>BD232</b> <b>Fuel</b> (7701028181)..... <b>BF884</b> <b>Air</b> (5001000878)..... <b>PA4890</b>
Kangoo I 1.9 DTI w/F9Q-780 Eng. (03/00-on) <b>Air</b> (7701047285)..... <b>PA4319</b> <sup>90</sup>	Mascott 150.35 w/DXI 3 Eng. (05/04-on) <b>Lube</b> (7701057828)..... <b>P7365</b> <b>Steering</b> (5000820895)..... <b>P106-HD</b>	Master I 2.5 TD (Sofim System) w/Sofim 8140.27-S9U714 Eng. (09/80-07/98) <b>Dual-Flow Lube</b> (7701035650).... <b>BD232</b> <b>Fuel</b> (7701016181)..... <b>BF825 +</b> <b>Air</b> (5001000878)..... <b>PA4890</b>
Kangoo II 1.6 8V w/K7M750 Eng. (05/08-on) <b>Lube</b> (7700873583)..... <b>B7276</b>	Mascott 150.55 w/DXI 3 Eng. (05/04-on) <b>Lube</b> (7701057828)..... <b>P7365</b> <b>Steering</b> (5000820895)..... <b>P106-HD</b>	Master I 2.5 TD (CAV System H 72) w/Sofim 8140.27-S9U714 Eng. (09/80-07/98) <b>Dual-Flow Lube</b> (7701035650).... <b>BD232</b> <b>Fuel</b> (7701016181)..... <b>BF825 +</b> <b>Air</b> (5001000878)..... <b>PA4890</b>
Kangoo II 1.6 16V w/K4M Eng. (02/08-on) <b>Lube</b> (7700873583)..... <b>B7276</b> <b>Fuel</b> (N/S)..... <b>N/S</b>	Mascott 150.65 w/DXI 3 Eng. (05/04-on) <b>Lube</b> (7701057828)..... <b>P7365</b> <b>Steering</b> (5000820895)..... <b>P106-HD</b>	Master I 2.5 TD (CAV System H 112) w/Sofim 8140.27-S9U714 Eng. (09/80-07/98) <b>Dual-Flow Lube</b> (7701035650).... <b>BD232</b> <b>Fuel</b> (7701028181)..... <b>BF884</b> <b>Air</b> (5001000878)..... <b>PA4890</b>
Kangoo II 1.6 16V LPG w/K4A834 Eng. (02/08-on) <b>Lube</b> (7700873583)..... <b>B7276</b> <b>Fuel</b> (N/S)..... <b>N/S</b>	Master I 1.4 w/1397cc Eng. (07/84-07/98) <b>Lube</b> (7702144083)..... <b>B7276</b> <b>Fuel</b> ..... <b>BF7736</b> <b>Air</b> (7700565729)..... <b>PA2099</b>	Master I 2.5 TDi (Lucas System) w/G9U Eng. (06/97-07/98) <b>Dual-Flow Lube</b> (7701035650).... <b>BD232</b>
Mascott 110 DCI w/DCI 2.8 Eng. (10/01-07/04) <b>Dual-Flow Lube</b> (7701035650).... <b>BD232</b> <b>Fuel</b> (7700700092)..... <b>BF587-D +</b> <b>Fuel</b> (5001846015)..... <b>BF7989-D</b> <b>Air</b> (5001847123)..... <b>PA30149</b> <b>Steering</b> (5000820895)..... <b>P106-HD</b>	Master I 1.7 w/1721cc Eng. (07/84-07/98) <b>Lube</b> (7702144083)..... <b>B7276</b> <b>Fuel</b> ..... <b>BF7736</b> <b>Air</b> (7700565729)..... <b>PA2099</b>	Master I 2.5 TDi (Purflux System) w/G9U Eng. (06/97-07/98) <b>Dual-Flow Lube</b> (7701035650).... <b>BD232</b>
Mascott 120 DXI w/DXI 3 Eng. (05/04-on) <b>Lube</b> (7701057828)..... <b>P7365</b> <b>Steering</b> (5000820895)..... <b>P106-HD</b>	Master I 2.0 w/J5R-718/728 Eng. (10/86-07/98) <b>Lube</b> (7700856339)..... <b>B7352</b> <b>Fuel</b> (5000031168)..... <b>BF7865</b> <b>Air</b> (5001000878)..... <b>PA4890</b>	Master II 1.9 DCI (Lucas System) w/F9Q-772 Eng. (09/01-11/03) <b>Lube</b> (7702144083)..... <b>B7276</b>
Mascott 130 DCI w/DCI 2.8 Eng. (10/01-07/04) <b>Dual-Flow Lube</b> (7701035650).... <b>BD232</b> <b>Fuel</b> (7700700092)..... <b>BF587-D +</b> <b>Fuel</b> (5001846015)..... <b>BF7989-D</b> <b>Air</b> (5001847123)..... <b>PA30149</b> <b>Steering</b> (5000820895)..... <b>P106-HD</b>	Master I 2.1 Diesel (Bosch System) w/J8S-330 Eng. (09/80-07/98) <b>Lube</b> (8200007832)..... <b>B7432</b> <b>Fuel</b> (Bosch System)..... <b>BF5587-D</b> <b>Fuel</b> (CAV System H72)..... <b>BF825 +</b> <b>Fuel</b> (CAV System H112)..... <b>BF884</b>	Master II 1.9 DCI (Purflux System) w/F9Q-772 Eng. (09/01-11/03) <b>Lube</b> (7702144083)..... <b>B7276</b> <b>Fuel</b> (7701475229)..... <b>PF46112</b>

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.

Check Original Equipment Numbers In Parentheses.




**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

RENAULT European Light Duty Vehicles (cont'd)	RENAULT European Light Duty Vehicles (cont'd)	RENAULT European Light Duty Vehicles (cont'd)	
Master II 1.9 DTI (Lucas System) w/F9Q-780 Eng. (03/00-11/03) Lube (7702144083)..... <b>B7276</b> Air (7701047285)..... <b>PA4319</b> <sup>90</sup>	Master III 2.5 DCI 150 w/146 HP Eng. (07/06-on) Lube (7701472321)..... <b>P7455</b> Fuel (7701475229)..... <b>PF46112</b>	Trafic 1.9 Dci 100 w/F9Q-760 Eng. (02/01-08/06) Fuel (7701207667)..... <b>PF9801</b> <sup>90</sup> Fuel (7701475229)..... <b>PF46112</b> Air (7701047285)..... <b>PA4319</b> <sup>90</sup>	
Master II 1.9 DTI (Purflux System) w/F9Q-780 Eng. (03/00-11/03) Lube (7702144083)..... <b>B7276</b> Air (7701047285)..... <b>PA4319</b> <sup>90</sup>	Master III 3.0 DCI 140 w/ZD3-200/203 Eng. (01/04-07/06) Lube (7701057828)..... <b>P7365</b> Fuel (7701207667)..... <b>PF9801</b> <sup>90</sup> Air (8200283082)..... <b>PA10012</b>	Trafic 2.0 16V w/F4R720/722 Eng. (02/01-on) Lube (7702144083)..... <b>B7276</b>	
Master II 2.2 DCI (Lucas System) w/G9T-720 Eng. (10/00-11/03) Lube (7701472321)..... <b>P7455</b>	Master III 3.0 DCI 160 w/ZD3 Eng. (05/04-on) Lube (7701057828)..... <b>P7365</b> Fuel (7701207667)..... <b>PF9801</b> <sup>90</sup> Air (8200283082)..... <b>PA10012</b>	Trafic 2.0 Dci 90 w/M9R-630, MR9-782 Eng. (09/06-on) Fuel (7701207667)..... <b>PF9801</b> <sup>90</sup>	
Master II 2.2 DCI (Purflux System) w/G9T-720 Eng. (10/00-11/03) Lube (7701472321)..... <b>P7455</b> Fuel (7701207667)..... <b>PF9801</b> <sup>90</sup>	Master IV 2.3 DCI 100 w/Dci 100 Eng. (04/10-on) Fuel (7701207667)..... <b>PF9801</b> <sup>90</sup>	Trafic 2.0 Dci 115 w/M9R-630, MR9-780 Eng. (09/06-on) Fuel (7701207667)..... <b>PF9801</b> <sup>90</sup>	
Master II 2.5 D w/S8U 770 Eng. (07/98-02/01) Dual-Flow Lube (7701035650).... <b>BD232</b>	Master IV 2.3 DCI 125 w/Dci 125 Eng. (04/10-on) Fuel (7701207667)..... <b>PF9801</b> <sup>90</sup>	Trafic 2.5 Dci 140 w/G9U730 Eng. (09/02-08/06) Lube (7700109402)..... <b>P7455</b> Fuel (7701207667)..... <b>PF9801</b> <sup>90</sup>	
Master II 2.5 DCI (Lucas System) w/G9U-720 Eng. (09/01-11/03) Lube (7701472321)..... <b>P7455</b>	Master IV 2.3 DCI 150 w/Dci 150 Eng. (04/10-on) Fuel (7701207667)..... <b>PF9801</b> <sup>90</sup>	Trafic 2.5 Dci 150 w/G9U-630/632 Eng. (09/06-on) Fuel (7701207667)..... <b>PF9801</b> <sup>90</sup>	
Master II 2.8 DTI T28-T33-T35 w/S9W-700 Eng. (07/98-11/01) Dual-Flow Lube (7701035650).... <b>BD232</b>	Maxity 110.28 w/DXi 2.5 Eng. (03/07-on) Lube (5001869771)..... <b>B7431</b> Air (5001869822)..... <b>RS5670</b>	<b>RIG MASTER</b> <b>Auxiliary Power Units (APU)</b>	
Master III 1.9 DCI 80 w/F9Q-774 Eng. (10/03-on) Lube (7702144083)..... <b>B7276</b> Fuel (7701207667)..... <b>PF9801</b> <sup>90</sup>	Maxity 110.32 w/DXi 2.5 Eng. (03/07-on) Lube (5001869771)..... <b>B7431</b> Air (5001869822)..... <b>RS5670</b>	Models w/Cat C0.5 Eng. Lube (220-1523)..... <b>B1405</b>	
Master III 2.2 DCI 90 w/G9T-720 Eng. (10/03-on) Lube (7701472321)..... <b>P7455</b> Fuel (7701207667)..... <b>PF9801</b> <sup>90</sup>	Maxity 110.34 w/DXi 2.5 Eng. (03/07-on) Lube (5001869771)..... <b>B7431</b> Air (5001869822)..... <b>RS5670</b>	Models w/Isuzu 6H3XL Eng. Lube (150-4140)..... <b>B74</b> Air (Enginaire C1140)..... <b>PA4758</b>	
Master III 2.3 DCI 100 w/M9T Eng. (04/10-on) Fuel (7701207667)..... <b>PF9801</b> <sup>90</sup>	Maxity 110.34 w/DXi 2.5 Eng. (03/07-on) Lube (5001869771)..... <b>B7431</b> Air (5001869822)..... <b>RS5670</b>	MTS LG200 w/2 Cyl. Cat Eng. Lube (Perkins 140516250)..... <b>B37</b> Fuel (Perkins 130366040)..... <b>PF937</b> Air (Mann C1140)..... <b>PA4758</b>	
Master III 2.3 DCI 125 w/M9T Eng. (04/10-on) Fuel (7701207667)..... <b>PF9801</b> <sup>90</sup>	Maxity 120 w/Dxi Eng. (01/12-on) Lube (5001869771)..... <b>B7431</b> Air (5001869822)..... <b>RS5670</b>	MTS LG200 w/2 Cyl. Perkins Eng. Lube (140516250)..... <b>B37</b> Fuel (130366040)..... <b>PF937</b> Air (Mann C1140)..... <b>PA4758</b>	
Master III 2.5 DCI 100 w/100 HP Eng. (07/06-on) Lube (7701472321)..... <b>P7455</b> Fuel (7701475229)..... <b>PF46112</b>	Maxity 130.35 w/DXi 2.5 Eng. (03/07-on) Lube (5001869771)..... <b>B7431</b> Air (5001869822)..... <b>RS5670</b>	MTS T4-6 w/2 Cyl. Cat Eng. Lube (Perkins 140516250)..... <b>B37</b> Fuel (Perkins 130366040)..... <b>PF937</b> Air (Mann C1140)..... <b>PA4758</b>	
Master III 2.5 DCI 100 w/G9U-750/754 Eng. (10/03-07/06) Lube (7701472321)..... <b>P7455</b> Fuel (7701207667)..... <b>PF9801</b> <sup>90</sup>	Maxity 130.45 w/DXi 2.5 Eng. (03/07-on) Lube (5001869771)..... <b>B7431</b> Air (5001869822)..... <b>RS5670</b>	MTS T4-6 w/Perkins Tier 4 Eng. Lube (140516250)..... <b>B37</b> Fuel (130366040)..... <b>PF937</b> Air (Mann C1140)..... <b>PA4758</b>	
Master III 2.5 DCI 120 w/120 HP Eng. (07/06-on) Lube (7701472321)..... <b>P7455</b> Fuel (7701475229)..... <b>PF46112</b>	Maxity 140 w/Dxi Eng. (01/12-on) Lube (5001869771)..... <b>B7431</b> Air (5001869822)..... <b>RS5670</b>	MTS V10 w/2 Cyl. Cat Eng. Lube (Perkins 140516250)..... <b>B37</b> Fuel (Perkins 130366040)..... <b>PF937</b> Air (Mann C1140)..... <b>PA4758</b>	
Master III 2.5 DCI 120 w/G9T-750 Eng. (10/03-07/06) Lube (7701472321)..... <b>P7455</b> Fuel (7701207667)..... <b>PF9801</b> <sup>90</sup>	Maxity 150.35 w/DXi 3 Eng. (03/07-on) Lube (7701057828)..... <b>P7365</b> Air (5001869822)..... <b>RS5670</b>	MTS V10 w/2 Cyl. Perkins Eng. Lube (140516250)..... <b>B37</b> Fuel (130366040)..... <b>PF937</b> Air (Mann C1140)..... <b>PA4758</b>	
	Maxity 150.45 w/DXi 3 Eng. (03/07-on) Lube (7701057828)..... <b>P7365</b> Air (5001869822)..... <b>RS5670</b>	RMP-10-40 w/Perkins 402-05 Eng. Lube (140516250)..... <b>B37</b> Fuel (130366040)..... <b>PF937</b> Air (Don. C045001)..... <b>PA3643</b>	
	Trafic 1.9 Dci 80 w/F9Q-766 Eng. (02/01-08/06) Fuel (7701207667)..... <b>PF9801</b> <sup>90</sup> Fuel (7701475229)..... <b>PF46112</b> Air (7701047285)..... <b>PA4319</b> <sup>90</sup>		

<sup>90</sup> Obsolete Pending.

Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>RIG MASTER</b> Auxiliary Power Units (APU) (cont'd)	<b>ROLLS-ROYCE</b> Diesel Engines	<b>SCANIA</b> Buses (cont'd)
RMP-14-6 w/Perkins 402-05 Eng. Lube (140516250)..... B37 Fuel (130366040)..... PF937 Air (Mann C1140)..... PA4758	Models w/Torque Converter TorqConv. (CD1369)..... PT213	B65, CF65, CF75 Fuel Ele..... PF950
RPM-14-6 w/Perkins 5H3XL Eng. Lube (140516250)..... B37 Fuel (130366040)..... PF937 Air (Mann C1140)..... PA4758	C Range 5 1/2 In. Lube Ele..... P104 Fuel Ele. (OD2673)..... PF838 Fuel Ele. (OD3928)..... PF831	B110, BF110 w/DS11 Turbo Eng. Lube (173171)..... B229 Fuel Spin-on (364624)..... BF988 + O. Air (235586)..... PA2474
RMP104 w/Perkins 402-05 Eng. Lube (140516250)..... B37 Fuel (130366040)..... PF937 Air (Mann C1140)..... PA4758	C4, CG Series Fuel Ele..... [2] PF838	B110, BF110, CR110, CR111 w/D11 Eng. Opt. Fuel/Water Separator..... BF1221 + Fuel Spin-on (210970)..... BF988 + P. Fuel Ele..... F950-F S. Fuel Ele. (152875)..... PF950
RMP110 w/Perkins 402-05 Eng. Lube (140516250)..... B37 Fuel (130366040)..... PF937 Air (Don. C045001)..... PA3643	C6 Series Opt. Breather..... PA1718	B111, BR111 w/D11 Eng. P. Fuel Ele..... F950-F S. Fuel Ele. (152875)..... PF950 Fuel Spin-on (364624)..... BF988 + O. Air (218989)..... PA2405
RMPLG-10 w/Perkins 402-05 Eng. Lube (140516250)..... B37 Fuel (130366040)..... PF937 Air (Mann C1140)..... PA4758	C6, FL Series 168 Fuel..... PF831	BF80 w/D8 Eng. P. Fuel Ele..... F950-F S. Fuel Ele. (152875)..... PF950 O. Air (235586)..... PA2474
RMP-P10-4 w/Perkins 402-05 Eng. Lube (140516250)..... B37 Fuel (130366040)..... PF937 Air (Don. C045001)..... PA3643	C8 Series Fuel Ele..... [3] PF838	BF80, BF86S w/DS8 Turbo Eng. Lube (173171)..... B229 Fuel (364624)..... BF988 + O. Air (218989)..... PA2405
RMP-T4-6 w/Perkins Tier 4 Eng. Lube (140516250)..... B37 Fuel (130366040)..... PF937 Air (Mann C1140)..... PA4758	Eagle Range 205, 220, 260 Can-Type Fuel..... BF825 +	BR85, CR85 w/D8 Eng. P. Fuel Ele..... F950-F S. Fuel Ele. (152875)..... PF950 O. Air (235586)..... PA2474
<b>ROADMASTER RAIL</b> Chassis	<b>RTS</b> Buses	BR112, CR112, K112, N112A, BR116 w/DS11 Eng. Lube (w/Turbo) (173171)..... B229 Fuel (364624)..... BF988 + Some Fuel (343144)..... BF587 Air (309443)..... PA3477 Coolant (378396)..... BW5139
A-Straight Rail w/Cat C7 Eng. Lube (1R1807)..... B7700 + Fuel (1R0751)..... BF7632 Coolant (9N-6123)..... BW5139	Nova Lube..... [2] B495 S. Fuel..... BF5810 Coolant..... B5134 + P. Turbocharger..... BF5800 +	BR145, CR145 w/DS11 Eng. Lube (w/Turbo) (173171)..... B229 Fuel (364624)..... BF988 + O. Air (235586)..... PA2474
AE-Stacked Rail w/Cummins ISC 8.3 (8.3L) Eng. Dual-Flow Lube (Fleetguard LF9009)..... BD7309 + Fuel (Fleetguard FF5488)..... BF7815 Fuel (Fleetguard 3942533)..... BF1271	<b>RYDER</b> Trucks	K82 w/DS18 Turbo Eng. Lube (173171)..... B229 Fuel (364624)..... BF988 + Some Fuel (343144)..... BF587 Air (309443)..... PA3477 Coolant (378396)..... BW5139
R-Raised Rail w/Cummins ISC Eng. Dual-Flow Lube (Fleetguard LF9009)..... BD7309 + Fuel (Fleetguard FF5488)..... BF7815 Fuel (Fleetguard 3942533)..... BF1271	Paymaster w/Cat 1160 Eng. Lube..... [2] BT364 Fuel..... BF583	K92 w/DS9, DSC9 Eng. Lube (w/Turbo) (173171)..... B229 Fuel (364624)..... BF988 + Air (309443)..... PA3477 Coolant (378396)..... BW5139
R-Raised Rail w/Cummins ISL Eng. Dual-Flow Lube (Fleetguard LF9009)..... BD7309 + Fuel (Fleetguard FF5488)..... BF7815 Fuel (Fleetguard 3942533)..... BF1271	Paymaster w/Cummins Eng. F-F Lube Bag..... P996 F-F Lube Ele..... P999-HD F-F Lube Spin-on..... B196 + B-P Lube Ele..... C750-E + Fuel/Water Separator..... BF1212 + 4 3/8 In. Fuel Spin-on..... BF948 + 5 3/4 In. Fuel Spin-on..... BF957 + 11 7/32 In. Fuel Spin-on..... BF596 + Breather Ele. (w/Turbo) (255963) PA643 Breather Ele. (w/o Turbo) (256837)..... PA1627 Turbocharger..... BT112	K94 w/DC11 06 Eng. Fuel/Water Separator (Open End for Bowl) (Mann WK1060/1)..... BF46083-O Fuel/Water Separator (With Bowl) (Mann WK1060/1)..... BF46072
<b>ROCKWELL</b> Rear Ends	Paymaster w/GMC 8V-71 Eng. F-F Lube Ele..... P20-HD + B-P Lube Ele..... P52 P. Fuel Spin-on..... BF5800 + S. Fuel Spin-on..... BF5810 P. Fuel Sock (5574961)..... F916-C P. Fuel Ele. (5575032)..... PF845 P. Fuel Sock (5574980)..... F844-A S. Fuel Ele. (5574508)..... PF902 S. Fuel Ele. (6436719)..... PF846	
SQHP Lube Spin-on..... B27	<b>SCANIA</b> Buses	
	B56, B66, B71, BF71, BF73 Fuel Ele..... PF838	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

SCANIA Buses (cont'd)	SCANIA Buses (cont'd)	SCANIA Engines (cont'd)
K94 w/DC11 06 Eng. (Cont'd) <b>Fuel/Water Separator</b> (With Drain) (Mann WK1060/1)..... <b>BF1329</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b>	K124 w/DSC12-05 Eng. (01/98-on) (Cont'd) <b>Fuel/Water Separator</b> (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b> K124 EB/NB w/DSC12 Eng. (01/98-on) <b>Fuel/Water Separator</b> (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> <b>Fuel/Water Separator</b> (With Bowl) (Mann WK1060/1)..... <b>BF46072</b> <b>Fuel/Water Separator</b> (With Drain) (Mann WK1060/1)..... <b>BF1329</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b>	DC9 <b>Lube</b> (173171)..... <b>B229</b> <b>Lube</b> (Standard Vers.)..... <b>B76</b> <b>Fuel Ele.</b> ..... <b>PF7936</b> <b>Fuel Spin-on</b> (1372444)..... <b>BF7624</b> <b>Fuel Spin-on</b> ..... <b>BF7908</b>
K114 w/DSC11 Eng. (01/03-on) <b>Fuel/Water Separator</b> (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> <b>Fuel/Water Separator</b> (With Bowl) (Mann WK1060/1)..... <b>BF46072</b> <b>Fuel/Water Separator</b> (With Drain) (Mann WK1060/1)..... <b>BF1329</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b>	K310 w/DC11 06 Eng. <b>Fuel/Water Separator</b> (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> <b>Fuel/Water Separator</b> (With Bowl) (Mann WK1060/1)..... <b>BF46072</b> <b>Fuel/Water Separator</b> (With Drain) (Mann WK1060/1)..... <b>BF1329</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b>	DC11 <b>Lube</b> (Standard Vers.)..... <b>B76</b> <b>Fuel</b> ..... <b>BF7908</b>
K124 w/DC12 (Euro 3) Eng. (08/99-on) <b>Fuel/Water Separator</b> (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> <b>Fuel/Water Separator</b> (With Bowl) (Mann WK1060/1)..... <b>BF46072</b> <b>Fuel/Water Separator</b> (With Drain) (Mann WK1060/1)..... <b>BF1329</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b>	N112DR w/DN11 Eng. <b>Fuel</b> (364624)..... <b>BF988 +</b> <b>Some Fuel</b> (343144)..... <b>BF587</b> <b>Air</b> (309443)..... <b>PA3477</b> <b>Coolant</b> (378396)..... <b>BW5139</b>	DC12 <b>Lube</b> (173171)..... <b>B229</b> <b>Lube</b> (Standard Vers.)..... <b>B76</b> <b>Fuel Ele.</b> ..... <b>PF7936</b> <b>Fuel Spin-on</b> ..... <b>BF7908</b> <b>Fuel Spin-on</b> (1372444)..... <b>BF7624</b>
K124 w/DSC12 Eng. (01/98-on) <b>Fuel/Water Separator</b> (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> <b>Fuel/Water Separator</b> (With Bowl) (Mann WK1060/1)..... <b>BF46072</b> <b>Fuel/Water Separator</b> (With Drain) (Mann WK1060/1)..... <b>BF1329</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b>	<b>SCANIA Engines</b>	DC16 <b>Lube</b> ..... <b>P7319</b> <b>Fuel</b> (1429059)..... <b>PF7896</b>
K124 w/DSC12 Eng. (01/98-on) <b>Fuel/Water Separator</b> (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> <b>Fuel/Water Separator</b> (With Bowl) (Mann WK1060/1)..... <b>BF46072</b> <b>Fuel/Water Separator</b> (With Drain) (Mann WK1060/1)..... <b>BF1329</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b>	D7 <b>Can-Type Fuel</b> ..... <b>BF825 +</b> <b>Fuel Ele.</b> (C.A.V. 7111/44)..... <b>PF838</b>	DI12 <b>Lube</b> (Standard Vers.) (1117285)..... <b>B76</b> <b>Fuel</b> (1174423)..... <b>BF7931</b>
K124 w/DSC12-05 Eng. (01/98-on) <b>Fuel/Water Separator</b> (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> <b>Fuel/Water Separator</b> (With Bowl) (Mann WK1060/1)..... <b>BF46072</b> <b>Fuel/Water Separator</b> (With Drain) (Mann WK1060/1)..... <b>BF1329</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b>	D8RO3 <b>P. Fuel</b> ..... <b>BF877 +</b> <b>S. Fuel</b> ..... <b>BF876</b>	DSC9 <b>Lube</b> (Standard Vers.)..... <b>B76</b> <b>Fuel</b> ..... <b>BF7624</b>
K124 w/DSC12-05 Eng. (01/98-on) <b>Fuel/Water Separator</b> (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> <b>Fuel/Water Separator</b> (With Bowl) (Mann WK1060/1)..... <b>BF46072</b> <b>Fuel/Water Separator</b> (With Drain) (Mann WK1060/1)..... <b>BF1329</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b>	D400, D420, D440, D441-446, D600, D631-646, D800 <b>Can-Type Fuel</b> (C.A.V. 7111/296)..... <b>BF825 +</b> <b>69.9 mm Fuel Ele.</b> (C.A.V. 7111/44)..... <b>PF838</b> <b>141.3 mm Fuel Ele.</b> (Bosch 1457431270)..... <b>PF950</b>	DSC11 <b>Lube</b> (Standard Vers.)..... <b>B76</b> <b>Fuel</b> ..... <b>BF7624</b>
K124 w/DSC12-05 Eng. (01/98-on) <b>Fuel/Water Separator</b> (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> <b>Fuel/Water Separator</b> (With Bowl) (Mann WK1060/1)..... <b>BF46072</b> <b>Fuel/Water Separator</b> (With Drain) (Mann WK1060/1)..... <b>BF1329</b> <b>Fuel/Water Separator</b> (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b>	D10 <b>Fuel Ele.</b> (Bosch 1457431271)..... <b>PF950</b>	DSC12 <b>Lube</b> (Standard Vers.)..... <b>B76</b> <b>Fuel</b> ..... <b>BF7624</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

SCANIA Trucks (cont'd)	SCANIA Trucks (cont'd)	SCANIA Trucks (cont'd)
114 (Cont'd)	G82, P82 w/DN8, DS8 Engs.	Serie G G250 w/DC09 (Euro 6) Eng. (10/13-on)
465.1 mm Radial Seal Air (1387549).....	Lube (w/Turbo) (173171).....	Lube (1742037).....
RS4963	B229	P7502
Cab Air (1420197).....	123.0 mm Fuel (364624).....	Fuel Kit (1736248).....
PA4938	BF988 +	PF9829 KIT
Air Dryer.....	155.6 mm Some Fuel (343144)...	Radial Seal Air (1869993).....
BA5375	BF587	RS30142 KIT
Coolant (342988).....	Coolant (378396).....	Cab Air (1770813).....
B5089 +	BW5139	PA5493
Steering (153468).....	G92, P92, R92, T92 w/DS9 Eng.	Air Dryer (1774598).....
P106-HD	Lube (w/Turbo) (173171).....	BA5378
Gearbox (1301696).....	B229	Trans. (1301696).....
BT9318	BF988 +	BT9318
PT9374	Fuel (364624).....	Steering (153468).....
	472.3 mm O. Air (370754).....	PT9374
	PA2801	Hyd. (1893214).....
	BW5139	PT9374
	Coolant (378396).....	Retarder (1329876).....
		PT9374
124	G93, P93, R93, T93 w/DS9 Turbo Eng.	Serie G G270 w/DC9 17-270 (Euro4) Eng. (10/07-on)
Lube (Standard Vers.) (1117285).	Lube.....	Lube (Standard Vers.).....
B76	B229	B76
Fuel/Water Separator (1393640).	Fuel (364624).....	Fuel/Water Separator (1393640).
BF46083-O	BF988 +	BF46083-O
Fuel (1372444).....	High Intake O. Air (395773).....	Fuel (1459762).....
BF7624	PA2813	PF7936
HiPerf. Fuel (1411894).....	Low Intake O. Air (395776).....	Radial Seal Air (Don. Air System) (Replacement Element) (1728667)
BF7908	PA3794	RS30142
Fuel (DT12 Eng.) (1459762).....	Some Coolant (378396).....	Radial Seal O. Air (Don. Air System).....
PF7936	BW5139	RS3724
446.9 mm Radial Seal Air (1421022).....	G112, P112, R112 w/DS11 Eng.	Radial Seal Air (Don. Air System) (Initial Installation) (1728667).....
RS3724	Lube (w/Turbo) (173171).....	RS30142 KIT
465.1 mm Radial Seal Air (1387549).....	B229	Radial Seal Air (Plastic End Cap) Radial Seal O. Air (Mahle/Knecht Air System).....
RS4963	BF988 +	RS4963
PA4938	BF587	19.8 mm Height Cab Air (1913500).....
BA5375	PA2801	PA5493
BA5375	BW5139	69.1 mm Height Cab Air.....
B5089 +	G113, P113, R113, T113 w/DS11 Turbo Eng.	PA4938
P106-HD	Lube (173171).....	Air Dryer (1774598).....
PT9237	B229	BA5378
PT9318	BF988 +	Steering.....
BT9318	PA2813	PT9374
BT9318	PA3794	PT9374
PT9374	PA3794	Retarder.....
	Some Coolant (378396).....	PT9374
	BW5139	
Serie 4 144	G143, P143, R143 w/DS14 Eng.	Serie G G280 w/ DC09 (Euro 6) Eng. (10/13-on)
Lube (Standard Vers.) (1117285).	Lube (w/Turbo) (173171).....	Lube (1742037).....
B76	B229	P7502
Fuel/Water Separator (1393640).	Fuel (364624).....	Fuel (1736248).....
BF46083-O	BF988 +	PF9829 KIT
Fuel (1372444).....	Air (395773).....	Radial Seal Air (1869993).....
BF7624	PA2813	RS30142 KIT
522.3 mm Radial Seal Air (1387548).....	Coolant (378396).....	Cab Air (1770813).....
RS4638 +	BW5139	PA5493
526.3 mm Radial Seal Air (1421021).....	Serie G G230 w/DC9 16-230 (Euro4) Eng. (10/07-on)	Air Dryer (1774598).....
RS3726	Lube (Standard Vers.).....	BA5378
PA4938	B76	Air Dryer (Haldex) (1393551).....
PA4938	PF7936	BA16000
BA5375	PF7936	Trans. (1301696).....
B5089 +	Fuel/Water Separator (w/o SP)...	BT9318
P106-HD	BF1329	Steering (153468).....
PT9318	BF1329-SP	P106-HD
PT9318	Fuel/Water Separator (w/SP).....	PT9374
PT9374	BF46083-O	PT9374
	Fuel/Water Separator (Open End for Bowl).....	Retarder (1329876).....
	BF46083-O	PE17002 KIT
	Radial Seal Air (Don. Air System) (Replacement Element) (1728667)	Serie G G310 w/DC9 18-310 (Euro4) Eng. (10/07-on)
	RS30142	Lube (Standard Vers.).....
	Radial Seal O. Air (Don. Air System).....	B76
	RS3724	Fuel/Water Separator (1393640).
	Radial Seal Air (Don. Air System) (Initial Installation) (1728667).....	BF46083-O
	RS30142 KIT	Fuel (1459762).....
	Radial Seal Air (Plastic End Cap) Radial Seal O. Air (Mahle/Knecht Air System).....	PF7936
	RS30142 KIT	Radial Seal Air (Don. Air System) (Replacement Element) (1728667)
	RS4963	RS30142
	PA4938	Radial Seal O. Air (Don. Air System).....
	69.1 mm Height Cab Air.....	RS3724
	PA5493	Radial Seal Air (Don. Air System) (Initial Installation) (1728667).....
	BA5378	RS30142 KIT
	PT9374	Radial Seal Air (Plastic End Cap) Radial Seal O. Air (Mahle/Knecht Air System).....
	PT9374	RS4963
	PT9374	19.8 mm Height Cab Air (1913500).....
		PA5493
		69.1 mm Height Cab Air.....
		PA4938

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

SCANIA Trucks (cont'd)	SCANIA Trucks (cont'd)	SCANIA Trucks (cont'd)
Serie G G310 w/DC9 18-310 (Euro4) Eng. (10/07-on) (Cont'd)	Serie G G370 w/ DC13 (Euro 6) Eng. (10/13-on) (Cont'd)	Serie G G420 w/DT12 12-420 (Euro4) Eng. (10/07-on)
Air Dryer (1774598)..... BA5378	Hyd. (1893214)..... PT9374	Lube (Standard Vers.)..... B76
Steering..... P106-HD	Retarder (1329876)..... PT9374	Fuel/Water Separator (1393640)..... BF46083-O
Retarder..... PT9374	Urea Filter (2265672)..... PE17002 KIT	Fuel (1459762)..... PF7936
Serie G G320 w/ DC09 (Euro 6) Eng. (10/13-on)	Serie G G380 w/DC12 13-380 (Euro4) Eng. (10/07-on)	Radial Seal Air (Don. Air System) (Replacement Element) (1728667)..... RS30142
Lube (1742037)..... P7502	Lube (Standard Vers.)..... B76	Radial Seal O. Air (Don. Air System)..... RS3724
Fuel (1736248)..... PF9829 KIT	Fuel/Water Separator (1393640)..... BF46083-O	Radial Seal Air (Don. Air System) (Initial Installation) (1728667)..... RS30142 KIT
Radial Seal Air (1869993)..... RS30142 KIT	Fuel (1459762)..... PF7936	Radial Seal Air (Plastic End Cap)..... RS30142 KIT
Cab Air (1770813)..... PA5493	Radial Seal Air (Don. Air System) (Replacement Element) (1728667)..... RS30142	Radial Seal O. Air (Mahle/Knecht Air System)..... RS4963
Air Dryer (1774598)..... BA5378	Radial Seal O. Air (Don. Air System)..... RS3724	19.8 mm Height Cab Air (1913500)..... PA5493
Air Dryer (Haldex) (1393551)..... BA16000	Radial Seal Air (Don. Air System) (Initial Installation) (1728667)..... RS30142 KIT	69.1 mm Height Cab Air..... PA4938
Trans. (1301696)..... BT9318	Radial Seal Air (Plastic End Cap)..... RS30142 KIT	Air Dryer (1774598)..... BA5378
Steering (153468)..... P106-HD	Radial Seal O. Air (Mahle/Knecht Air System)..... RS4963	Steering..... P106-HD
Hyd. (1329876)..... PT9374	Cab Air (1913500)..... PA4938	Retarder..... PT9374
Retarder (1893214)..... PT9374	Air Dryer (1774598)..... BA5378	Serie G G420 w/DC12 15-420 (Euro5) Eng. (10/07-on)
Urea Filter (2265672)..... PE17002 KIT	Steering..... P106-HD	Lube (Standard Vers.)..... B76
Serie G G340 w/DC12 10-340 (Euro4) Eng. (10/07-on)	Retarder..... PT9374	Fuel/Water Separator (1393640)..... BF46083-O
Lube (Standard Vers.)..... B76	Serie G G380 w/DC12 18-380 (Euro5) Eng. (10/07-on)	Fuel (1459762)..... PF7936
Fuel/Water Separator (1393640)..... BF46083-O	Lube (Standard Vers.)..... B76	Radial Seal Air (Don. Air System) (Replacement Element) (1728667)..... RS30142
Fuel (1459762)..... PF7936	Fuel/Water Separator (1393640)..... BF46083-O	Radial Seal O. Air (Don. Air System)..... RS3724
Radial Seal Air (Don. Air System) (Replacement Element) (1728667)..... RS30142	Fuel (1459762)..... PF7936	Radial Seal Air (Don. Air System) (Initial Installation) (1728667)..... RS30142 KIT
Radial Seal O. Air (Don. Air System)..... RS3724	Radial Seal Air (Don. Air System) (Replacement Element) (1728667)..... RS30142	Radial Seal Air (Plastic End Cap)..... RS30142 KIT
Radial Seal Air (Don. Air System) (Initial Installation) (1728667)..... RS30142 KIT	Radial Seal O. Air (Don. Air System)..... RS3724	Radial Seal O. Air (Mahle/Knecht Air System)..... RS4963
Radial Seal Air (Plastic End Cap)..... RS30142 KIT	Radial Seal Air (Don. Air System) (Initial Installation) (1728667)..... RS30142 KIT	19.8 mm Height Cab Air (1913500)..... PA5493
Radial Seal O. Air (Mahle/Knecht Air System)..... RS4963	Radial Seal Air (Plastic End Cap)..... RS30142 KIT	69.1 mm Height Cab Air..... PA4938
19.8 mm Height Cab Air (1913500)..... PA5493	Radial Seal O. Air (Mahle/Knecht Air System)..... RS4963	Air Dryer (1774598)..... BA5378
69.1 mm Height Cab Air..... PA4938	19.8 mm Height Cab Air (1913500)..... PA5493	Steering..... P106-HD
Air Dryer (1774598)..... BA5378	69.1 mm Height Cab Air..... PA4938	Retarder..... PT9374
Steering..... P106-HD	Air Dryer (1774598)..... BA5378	Serie G G360 w/DC09 (Euro6) Eng. (10/13-on)
Retarder..... PT9374	Steering..... P106-HD	Lube (1742037)..... P7502
Serie G G360 w/DC09 (Euro6) Eng. (10/13-on)	Retarder..... PT9374	Fuel (1736248)..... PF9829 KIT
Lube (1742037)..... P7502	Serie G G410 w/ DC13 (Euro 6) Eng. (10/13-on)	Radial Seal Air (1869993)..... RS30142 KIT
Fuel (1736248)..... PF9829 KIT	Lube (1742037)..... P7502	Cab Air (1770813)..... PA5493
Radial Seal Air (1869993)..... RS30142 KIT	Fuel (1736248)..... PF9829 KIT	Air Dryer (1774598)..... BA5378
Cab Air (1770813)..... PA5493	Radial Seal Air (1869993)..... RS30142 KIT	Air Dryer (Haldex) (1393551)..... BA16000
Air Dryer (1774598)..... BA5378	Cab Air (1770813)..... PA5493	Trans. (1301696)..... BT9318
Air Dryer (Haldex) (1393551)..... BA16000	Air Dryer (1774598)..... BA5378	Steering (153468)..... P106-HD
Trans. (1301696)..... BT9318	Air Dryer (Haldex) (1393551)..... BA16000	Retarder (1329876)..... PT9374
Steering (153468)..... P106-HD	Trans. (1301696)..... BT9318	Urea Filter (2265672)..... PE17002 KIT
Hyd. (1893214)..... PT9374	Steering (153468)..... P106-HD	Serie G G440 w/DC13 10-440 (Euro5) Eng. (04/10-on)
Retarder (1329876)..... PT9374	Hyd. (1893214)..... PT9374	Lube..... P7502
Urea Filter (2265672)..... PE17002 KIT	Retarder (1329876)..... PT9374	Fuel Kit (1736250)..... PF9829 KIT
Serie G G370 w/ DC13 (Euro 6) Eng. (10/13-on)	Urea Filter (2265672)..... PE17002 KIT	Radial Seal Air (1485592)..... RS5358
Lube (1742037)..... P7502	Serie G G450 w/DC13 (Euro6) Eng. (10/13-on)	Cab Air (1770813)..... PA5493
Fuel (1736248)..... PF9829 KIT	Lube (1742037)..... P7502	Air Dryer (1774598)..... BA5378
Radial Seal Air (1869993)..... RS30142 KIT	Fuel Kit (1736248)..... PF9829 KIT	Trans. (1301696)..... BT9318
Cab Air (1770813)..... PA5493	Radial Seal Air (1869993)..... RS30142 KIT	Steering (153468)..... P106-HD
Air Dryer (1774598)..... BA5378	Cab Air (1770813)..... PA5493	Retarder (1329876)..... PT9374
Air Dryer (Haldex) (1393551)..... BA16000	Air Dryer (1774598)..... BA5378	Serie G G450 w/DC13 (Euro6) Eng. (10/13-on)
Trans. (1301696)..... BT9318	Air Dryer (Haldex) (1393551)..... BA16000	Lube (1742037)..... P7502
Steering (153468)..... P106-HD	Trans. (1301696)..... BT9318	Fuel Kit (1736248)..... PF9829 KIT

Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>SCANIA Trucks (cont'd)</b>	
Serie G G450 w/DC13 (Euro6) Eng. (10/13-on) (Cont'd)	
Steering (153468).....	P106-HD
Hyd. (1893214).....	PT9374
Retarder (1329876).....	PT9374
Urea Filter (2265672).....	PE17002 KIT
Serie G G480 w/DT12 17-480 (Euro4) Eng. (10/07-on)	
Lube (Standard Vers.).....	B76
Fuel/Water Separator (1393640).....	BF46083-O
Fuel (1459762).....	PF7936
Radial Seal Air (Don. Air System) (Replacement Element) (1728667).....	RS30142
Radial Seal O. Air (Don. Air System).....	RS3724
Radial Seal Air (Don. Air System) (Initial Installation) (1728667).....	RS30142 KIT
Radial Seal Air (Plastic End Cap).....	RS30142 KIT
Radial Seal O. Air (Mahle/Knecht Air System).....	RS4963
19.8 mm Height Cab Air (1913500).....	PA5493
69.1 mm Height Cab Air.....	PA4938
Air Dryer.....	BA5375
Steering.....	P106-HD
Retarder.....	PT9374
Serie G G490 w/ DC13 (Euro 6) Eng. (10/13-on)	
Lube (1742037).....	P7502
Fuel Kit (1736248).....	PF9829 KIT
Radial Seal Air (1869993).....	RS30142 KIT
Cab Air (1770813).....	PA5493
Air Dryer (1774598).....	BA5378
Air Dryer (Haldex) (1393551).....	BA16000
Trans. (1301696).....	BT9318
Steering (153468).....	P106-HD
Hyd. (1893214).....	PT9374
Retarder (1329876).....	PT9374
Urea Filter (2265672).....	PE17002 KIT
GP82 w/DS9 Eng.	
Air (370754).....	PA2801
L36	
Lube.....	BT223
L50 w/D5, DS5 Engs.	
Can-Type Fuel (181642).....	BF825 +
L51, L55, L56, LS56, L66	
Can-Type Fuel (C.A.V. 7111/296).....	BF825 +
Fuel Ele. (C.A.V. 7111/44).....	PF838
L75, L76, LB76, LBS76, LS76	
Fuel Ele.....	PF950
Steering.....	P40
L80, LB80 w/D8 Eng.	
P. Fuel Ele.....	F950-F
S. Fuel Ele. (152875).....	PF950
Can-Type Fuel (181642).....	BF825 +
Steering (153468).....	P106-HD

<b>SCANIA Trucks (cont'd)</b>	
L80, LB81, LB86, LBS86 w/DS8 Turbo Eng.	
Lube (173171).....	B229
Fuel (364624).....	BF988 +
Steering (153468).....	P106-HD
L81, LB81, LB86, LBS86, LS86 w/D8 Eng.	
Lube (173171).....	B229
P. Fuel Ele.....	F950-F
S. Fuel Ele. (152875).....	PF950
Steering (153468).....	P106-HD
L86	
Lube (w/Turbo) (173171).....	B229
Air (Don. P184035).....	PA1646-FN
Steering (153468).....	P106-HD
L110, LB110, LB111, LBS111, LBT111, SBA111 w/D11 Eng.	
P. Fuel Ele.....	F950-F
S. Fuel Ele. (152875).....	PF950
O. Air (218989).....	PA2405
Steering (153468).....	P106-HD
L110, LB110, LBS110, LBT110, LT110 w/DS11 Turbo Eng.	
Lube (173171).....	B229
Fuel (364624).....	BF988 +
O. Air (217517).....	PA2475
L111, LS111, LT111 w/D11 Eng.	
P. Fuel Ele.....	F950-F
S. Fuel Ele. (152875).....	PF950
496.9 mm O. Air (219517).....	PA2475
419.1 mm O. Air (Don. P182046).....	LL1885 +
406.4 mm I. Air (310814).....	PA1893
330.2 mm Some Air (Don. P182037).....	LL1642-2
Steering (153468).....	P106-HD
L140, LS140 w/DS14 Turbo Eng.	
Lube (173171).....	B229
Fuel (364624).....	BF988 +
O. Air (217517).....	PA2475
L141, L146, T145, T146	
Lube (w/Turbo) (173171).....	B229
Fuel (210970).....	BF988 +
Opt. Fuel/Water Separator.....	BF1221 +
LB111, LBS111, LBT111, LS111, LT111, SBAT111 w/DS11 Turbo Eng.	
Lube (173171).....	B229
Fuel (364624).....	BF988 +
496.9 mm O. Air (217517).....	PA2475
419.1 mm O. Air (310813).....	LL1885 +
406.4 mm I. Air (310814).....	PA1893
330.2 mm Some Air (Don. P182037).....	LL1642-2
Steering (153468).....	P106-HD
LB140, LBS140 w/DS14 Turbo Eng.	
Lube (173171).....	B229
Fuel (364624).....	BF988 +
Air (211589).....	PA3477
Steering (153468).....	P106-HD

<b>SCANIA Trucks (cont'd)</b>	
LBT140, L141, LB141, LB141S, LBS141, LBS141S, LBT141, LBT141S, LS141, LT145, LT146 w/DS14 Turbo Eng.	
Lube (173171).....	B229
Fuel (364624).....	BF988 +
O. Air (370754).....	PA2801
LKT141H, LTK141	
Single Air (Don. P184031).....	PA1630-2
O. Air (310816).....	LL1846 +
I. Air (310817).....	PA1880
LS5 w/DS10 Eng.	
Lube Ele.....	P106
Lube Spin-on.....	BT223
LS55 w/DS10 Eng.	
Lube Ele.....	P106
Lube Spin-on.....	BT223
LT145, LT145S w/D14 Eng.	
P. Fuel Ele.....	F950-F
S. Fuel Ele. (152875).....	PF950
Air (370754).....	PA2801
Steering (153468).....	P106-HD
LT145, LT145S w/DS14 Turbo Eng.	
Lube (173171).....	B229
Fuel (364624).....	BF988 +
O. Air (370754).....	PA2801
Steering (153468).....	P106-HD
P93, T93 w/DSC9 Eng.	
Lube (Mann W9207).....	B229
Fuel Spin-on (457431326).....	BF988 +
Fuel Spin-on (w/Drain) (Mann WK842).....	BF587-D +
O. Air (Mann C30703).....	PA2813
I. Air (Mann CF1610).....	PA4809
Single Air (Mann C311238).....	PA3794
Trans. (Mann W930/14).....	BT9318
Steering (153468).....	P106-HD
Hyd. (Mann H929/3).....	PT9374
Serie 4 P94 w/DSC9 (Euro2) Eng. (10/95-10/04)	
Lube (Standard Vers.) (Mann W11102/14).....	
	B76
Fuel/Water Separator (1393640).....	BF46083-O
Fuel (1372444).....	BF7624
Radial Seal Air (Don. Air System) (Replacement Element) (1728667).....	RS30142
Radial Seal Air (Don. Air System) (Mann C301240).....	RS3724
Radial Seal Air (Don. Air System) (Initial Installation) (1728667).....	RS30142 KIT
Radial Seal Air (Plastic End Cap).....	RS30142 KIT
Radial Seal Air (Mahle/Knecht Air System).....	RS4963
Cab Air (1420197).....	PA4938
Air Dryer (Mann TB1374/3X).....	BA5375
Trans.....	BT9318
Steering (1902137).....	P106-HD
Retarder (1381235).....	PT9374

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>SCANIA Trucks (cont'd)</b>	<b>SCANIA Trucks (cont'd)</b>	<b>SCANIA Trucks (cont'd)</b>
<p>Serie 4 P94 w/DC9 (Euro3) Eng. (03/99-10/04)</p> <p><b>Lube</b> (Standard Vers.)..... <b>B76</b></p> <p><b>Fuel/Water Separator</b> (1393640). <b>BF46083-O</b></p> <p><b>Fuel</b> (1411894)..... <b>BF7908</b></p> <p><b>Radial Seal Air</b> (Don. Air System) (Replacement Element) (1728667) <b>RS30142</b></p> <p><b>Radial Seal Air</b> (Don. Air System) <b>RS3724</b></p> <p><b>Radial Seal Air</b> (Don. Air System) (Initial Installation) (1728667)..... <b>RS30142 KIT</b></p> <p><b>Radial Seal Air</b> (Plastic End Cap) <b>RS30142 KIT</b></p> <p><b>Radial Seal Air</b> (Mahle/Knecht Air System)..... <b>RS4963</b></p> <p><b>Cab Air</b> (1420197)..... <b>PA4938</b></p> <p><b>Air Dryer</b> (Mann TB1374/3X)..... <b>BA5375</b></p> <p><b>Trans.</b>..... <b>BT9318</b></p> <p><b>Steering</b>..... <b>P106-HD</b></p> <p><b>Retarder</b> (1381235)..... <b>PT9374</b></p> <hr/> <p>P112, R112 w/DSC1006 Eng.</p> <p><b>Lube</b> (w/Turbo)..... <b>B229</b></p> <p><b>Fuel</b>..... <b>[2] BF988 +</b></p> <p><b>O. Air</b>..... <b>PA1885 +</b></p> <p><b>I. Air</b>..... <b>PA1893</b></p> <hr/> <p>P113, R113, T113 w/DSC11 Eng.</p> <p><b>Lube</b> (Mann W920/7)..... <b>B229</b></p> <p><b>Fuel Spin-on</b> (Mann WK723/1).... <b>BF988 +</b></p> <p><b>Fuel Spin-on</b> (w/Drain) (Mann WK842)..... <b>BF587-D +</b></p> <p><b>O. Air</b> (Mann C30703)..... <b>PA2813</b></p> <p><b>I. Air</b> (Mann CF1610)..... <b>PA4809</b></p> <p><b>Single Air</b> (Mann C311238)..... <b>PA3794</b></p> <p><b>Steering</b> (153468)..... <b>P106-HD</b></p> <p><b>Hyd.</b> (Mann H929/3)..... <b>PT9374</b></p> <hr/> <p>Serie 4 P114 w/DSC11(Euro2) Eng. (10/96-10/04)</p> <p><b>Lube</b> (Standard Vers.) (1117285). <b>B76 +</b></p> <p><b>Lube</b> (Severe Service) (1117285) <b>B76-SS +</b></p> <p><b>Fuel/Water Separator</b> (1393640). <b>BF46083-O</b></p> <p><b>Fuel</b> (1341638)..... <b>BF7624</b></p> <p><b>Radial Seal Air</b> (1421022)..... <b>RS3724</b></p> <p><b>Radial Seal Air</b> (Don. Air System) (1869995)..... <b>RS30142 KIT</b></p> <p><b>Radial Seal Air</b> (Knecht Air System) (1526087)..... <b>RS4963</b></p> <p><b>Cab Air</b> (1420197)..... <b>PA4938</b></p> <p><b>Air Dryer</b> (1384549)..... <b>BA5375</b></p> <p><b>Trans.</b> (1301696)..... <b>BT9318</b></p> <p><b>Steering</b> (153468)..... <b>P106-HD</b></p> <p><b>Retarder</b> (1329876)..... <b>PT9374</b></p> <hr/> <p>Serie 4 P114 w/DC11(Euro3) Eng. (03/99-10/04)</p> <p><b>Lube</b> (Standard Vers.)..... <b>B76 +</b></p> <p><b>Lube</b> (Severe Service)..... <b>B76-SS +</b></p> <p><b>Fuel/Water Separator</b> (1393640). <b>BF46083-O</b></p> <p><b>Fuel</b> (1411894)..... <b>BF7908</b></p> <p><b>Radial Seal Air</b> (Don. Air System) (Replacement Element) (1728667) <b>RS30142</b></p> <p><b>Radial Seal Air</b> (Don. Air System) <b>RS3724</b></p> <p><b>Radial Seal Air</b> (Don. Air System) (Initial Installation) (1728667)..... <b>RS30142 KIT</b></p>	<p>Serie 4 P114 w/DC11(Euro3) Eng. (03/99-10/04) (Cont'd)</p> <p><b>Radial Seal Air</b> (Plastic End Cap) <b>RS30142 KIT</b></p> <p><b>Radial Seal Air</b> (Mahle/Knecht Air System)..... <b>RS4963</b></p> <p><b>Cab Air</b> (1420197)..... <b>PA4938</b></p> <p><b>Air Dryer</b> (Mann TB1374/3X)..... <b>BA5375</b></p> <p><b>Trans.</b>..... <b>BT9318</b></p> <p><b>Steering</b>..... <b>P106-HD</b></p> <p><b>Retarder</b> (1381235)..... <b>PT9374</b></p> <hr/> <p>Serie 4 P124 w/DC12 (Euro3) Eng. (03/99-10/04)</p> <p><b>Lube</b> (Standard Vers.)..... <b>B76</b></p> <p><b>Fuel/Water Separator</b> (1393640). <b>BF46083-O</b></p> <p><b>Fuel</b> (1411894)..... <b>BF7908</b></p> <p><b>Radial Seal Air</b> (Don. Air System) (Replacement Element) (1728667) <b>RS30142</b></p> <p><b>Radial Seal Air</b> (Don. Air System) <b>RS3724</b></p> <p><b>Radial Seal Air</b> (Don. Air System) (Initial Installation) (1728667)..... <b>RS30142 KIT</b></p> <p><b>Radial Seal Air</b> (Plastic End Cap) <b>RS30142 KIT</b></p> <p><b>Radial Seal Air</b> (Mahle/Knecht Air System)..... <b>RS4963</b></p> <p><b>Cab Air</b> (1420197)..... <b>PA4938</b></p> <p><b>Air Dryer</b> (Mann TB1374/3X)..... <b>BA5375</b></p> <p><b>Trans.</b>..... <b>BT9318</b></p> <p><b>Steering</b>..... <b>P106-HD</b></p> <p><b>Retarder</b> (1381235)..... <b>PT9374</b></p> <hr/> <p>Serie 4 P124 w/DC1203 (Euro3-1) Eng. (10/02-10/04)</p> <p><b>Lube</b> (Standard Vers.)..... <b>B76</b></p> <p><b>Fuel/Water Separator</b> (1393640). <b>BF46083-O</b></p> <p><b>Fuel</b> (1411894)..... <b>BF7908</b></p> <p><b>Radial Seal Air</b> (Don. Air System) (Replacement Element) (1728667) <b>RS30142</b></p> <p><b>Radial Seal Air</b> (Don. Air System) <b>RS3724</b></p> <p><b>Radial Seal Air</b> (Don. Air System) (Initial Installation) (1728667)..... <b>RS30142 KIT</b></p> <p><b>Radial Seal Air</b> (Plastic End Cap) <b>RS30142 KIT</b></p> <p><b>Radial Seal Air</b> (Mahle/Knecht Air System)..... <b>RS4963</b></p> <p><b>Cab Air</b> (1420197)..... <b>PA4938</b></p> <p><b>Air Dryer</b> (Mann TB1374/3X)..... <b>BA5375</b></p> <p><b>Trans.</b>..... <b>BT9318</b></p> <p><b>Steering</b>..... <b>P106-HD</b></p> <p><b>Retarder</b> (1381235)..... <b>PT9374</b></p> <hr/> <p>Serie 4 P124 w/DT1202/08 (Euro3) Eng. (02/01-10/04)</p> <p><b>Lube</b> (Standard Vers.)..... <b>B76</b></p> <p><b>Fuel/Water Separator</b> (1393640). <b>BF46083-O</b></p> <p><b>Fuel</b> (1459762)..... <b>PF7936</b></p> <p><b>Radial Seal Air</b> (Don. Air System) (Replacement Element) (1728667) <b>RS30142</b></p> <p><b>Radial Seal Air</b> (Don. Air System) <b>RS3724</b></p> <p><b>Radial Seal Air</b> (Don. Air System) (Initial Installation) (1728667)..... <b>RS30142 KIT</b></p> <p><b>Radial Seal Air</b> (Plastic End Cap) <b>RS30142 KIT</b></p>	<p>Serie 4 P124 w/DT1202/08 (Euro3) Eng. (02/01-10/04) (Cont'd)</p> <p><b>Radial Seal Air</b> (Mahle/Knecht Air System)..... <b>RS4963</b></p> <p><b>Cab Air</b> (1420197)..... <b>PA4938</b></p> <p><b>Air Dryer</b> (Mann TB1374/3X)..... <b>BA5375</b></p> <p><b>Trans.</b>..... <b>BT9318</b></p> <p><b>Steering</b>..... <b>P106-HD</b></p> <p><b>Retarder</b> (1381235)..... <b>PT9374</b></p> <hr/> <p>Serie 4 P124 w/DSC12 (Euro2) Eng. (01/96-10/04)</p> <p><b>Lube</b> (Standard Vers.) (1117285). <b>B76</b></p> <p><b>Fuel/Water Separator</b> (1393640). <b>BF46083-O</b></p> <p><b>Fuel</b> (1372444)..... <b>BF7624</b></p> <p><b>Radial Seal Air</b> (Don. Air System) (Replacement Element) (1728667) <b>RS30142</b></p> <p><b>Radial Seal Air</b> (Don. Air System) (1335679)..... <b>RS3724</b></p> <p><b>Radial Seal Air</b> (Don. Air System) (Initial Installation) (1728667)..... <b>RS30142 KIT</b></p> <p><b>Radial Seal Air</b> (Plastic End Cap) <b>RS30142 KIT</b></p> <p><b>Radial Seal Air</b> (Mahle/Knecht Air System)..... <b>RS4963</b></p> <p><b>Cab Air</b> (1420197)..... <b>PA4938</b></p> <p><b>Air Dryer</b> (Mann TB1374/3X)..... <b>BA5375</b></p> <p><b>Trans.</b> (1301696)..... <b>BT9318</b></p> <p><b>Steering</b> (1902137)..... <b>P106-HD</b></p> <p><b>Retarder</b> (1381235)..... <b>PT9374</b></p> <hr/> <p>P142, R142, T142</p> <p><b>O. Air</b> (310816)..... <b>LL1846 +</b></p> <p><b>I. Air</b> (310817)..... <b>PA1880</b></p> <hr/> <p>Serie 4 P144 w/DSC14 Eng. (1117285).</p> <p><b>Lube</b> (Standard Vers.) (1117285). <b>B76</b></p> <p><b>143.7 mm Fuel</b> (1372444)..... <b>BF7624</b></p> <p><b>155.6 mm Fuel</b> (w/Drain) (Mann WK842)..... <b>BF587-D +</b></p> <p><b>446.9 mm Radial Seal Air</b> (1335679)..... <b>RS3724</b></p> <p><b>526.3 mm Radial Seal Air</b> (1335678)..... <b>RS3726</b></p> <p><b>Coolant</b>..... <b>BW5139</b></p> <p><b>Trans.</b> (Mann W930/14)..... <b>BT9318</b></p> <p><b>Steering</b> (1902137)..... <b>P106-HD</b></p> <p><b>Hyd.</b> (Mann H929/3)..... <b>PT9374</b></p> <hr/> <p>Serie P P230 w/DC9 13-230 (Euro3) Eng. (09/04-on)</p> <p><b>Lube</b> (Standard Vers.)..... <b>B76</b></p> <p><b>Fuel/Water Separator</b> (1393640). <b>BF46083-O</b></p> <p><b>Fuel</b> (1411894)..... <b>BF7908</b></p> <p><b>Radial Seal Air</b> (Don. Air System) (Replacement Element) (1728667) <b>RS30142</b></p> <p><b>Radial Seal Air</b> (Don. Air System) <b>RS3724</b></p> <p><b>Radial Seal Air</b> (Don. Air System) (Initial Installation) (1728667)..... <b>RS30142 KIT</b></p> <p><b>Radial Seal Air</b> (Plastic End Cap) <b>RS30142 KIT</b></p> <p><b>Radial Seal Air</b> (Mahle/Knecht Air System)..... <b>RS4963</b></p>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).




SCANIA Trucks (cont'd)	SCANIA Trucks (cont'd)	SCANIA Trucks (cont'd)
<b>Serie P P230 w/DC9 13-230 (Euro3) Eng. (09/04-on) (Cont'd)</b> <b>19.8 mm Height Cab Air</b> (1913500)..... <b>PA5493</b> <b>69.1 mm Height Cab Air</b> (1420197)..... <b>PA4938</b> <b>Air Dryer</b> (Mann TB1374/3X)..... <b>BA5375</b> <b>Trans.</b> (1301696)..... <b>BT9318</b> <b>Steering</b> ..... <b>P106-HD</b> <b>Retarder</b> (1381235)..... <b>PT9374</b>	<b>Serie P P270 w/DC9 (Euro 3) 13-230 Eng. (09/04-on)</b> <b>Lube</b> (Standard Vers.)..... <b>B76</b> <b>Fuel</b> (1411894)..... <b>BF7908</b> <b>Radial Seal Air</b> (Don. Air System) <b>RS3724</b> <b>Radial Seal Air</b> (Mahle/Knecht Air System)..... <b>RS4963</b> <b>Cab Air</b> (1420197)..... <b>PA4938</b> <b>Air Dryer</b> (Mann TB1374/3X)..... <b>BA5375</b> <b>Trans.</b> (1301696)..... <b>BT9318</b> <b>Steering</b> ..... <b>P106-HD</b> <b>Retarder</b> (1381235)..... <b>PT9374</b>	<b>Serie P P280 w/DC9 29/36-280 (Euro5+EEV) Eng. (10/07-on) (Cont'd)</b> <b>Fuel</b> (1794863)..... <b>PF9829 KIT</b> <b>Radial Seal Air</b> (1869993)..... <b>RS30142 KIT</b> <b>19.8 mm Height Cab Air</b> ..... <b>PA5493</b> <b>69.1 mm Height Cab Air</b> ..... <b>PA4938</b> <b>Air Dryer</b> (1774598)..... <b>BA5378</b> <b>Steering</b> ..... <b>P106-HD</b> <b>Retarder</b> ..... <b>PT9374</b>
<b>Serie P P230 w/DC9 16-230 (Euro4) Eng. (10/05-on)</b> <b>Lube</b> (Standard Vers.)..... <b>B76</b> <b>Fuel/Water Separator</b> (1393640). <b>BF46083-O</b> <b>Fuel</b> (1459762)..... <b>PF7936</b> <b>Radial Seal Air</b> (Don. Air System) (Replacement Element) (1728667) <b>RS30142</b> <b>Radial Seal Air</b> (Don. Air System) <b>RS3724</b> <b>Radial Seal Air</b> (Don. Air System) (Initial Installation) (1728667)..... <b>RS30142 KIT</b> <b>Radial Seal Air</b> (Plastic End Cap) <b>RS30142 KIT</b> <b>Radial Seal Air</b> (Mahle/Knecht Air System)..... <b>RS4963</b> <b>19.8 mm Height Cab Air</b> (1913500)..... <b>PA5493</b> <b>69.1 mm Height Cab Air</b> (1420197)..... <b>PA4938</b> <b>Air Dryer</b> (Mann TB1394/3x)..... <b>BA5378</b> <b>Trans.</b> (1301696)..... <b>BT9318</b> <b>Steering</b> ..... <b>P106-HD</b> <b>Retarder</b> (1381235)..... <b>PT9374</b>	<b>Serie P P270 w/DC9 12-270 (Euro3) Eng. (09/04-on)</b> <b>Lube</b> (Standard Vers.)..... <b>B76</b> <b>Fuel/Water Separator</b> (1393640). <b>BF46083-O</b> <b>Fuel</b> (1411894)..... <b>BF7908</b> <b>Radial Seal Air</b> (Don. Air System) (Replacement Element) (1728667) <b>RS30142</b> <b>Radial Seal Air</b> (Don. Air System) <b>RS3724</b> <b>Radial Seal Air</b> (Don. Air System) (Initial Installation) (1728667)..... <b>RS30142 KIT</b> <b>Radial Seal Air</b> (Plastic End Cap) <b>RS30142 KIT</b> <b>Radial Seal Air</b> (Mahle/Knecht Air System)..... <b>RS4963</b> <b>19.8 mm Height Cab Air</b> (1913500)..... <b>PA5493</b> <b>69.1 mm Height Cab Air</b> (1420197)..... <b>PA4938</b> <b>Air Dryer</b> (Mann TB1374/3X)..... <b>BA5375</b> <b>Trans.</b> ..... <b>BT9318</b> <b>Steering</b> ..... <b>P106-HD</b> <b>Retarder</b> (1381235)..... <b>PT9374</b>	<b>Serie P P280 w/DC09 (Euro 6) Eng. (10/13-on)</b> <b>Lube</b> (1742037)..... <b>P7502</b> <b>Fuel Kit</b> (1736248)..... <b>PF9829 KIT</b> <b>Radial Seal Air</b> (1869993)..... <b>RS30142 KIT</b> <b>Cab Air</b> (1770813)..... <b>PA5493</b> <b>Air Dryer</b> (1774598)..... <b>BA5378</b> <b>Trans.</b> (1301696)..... <b>BT9318</b> <b>Steering</b> (153468)..... <b>P106-HD</b> <b>Hyd.</b> (1893214)..... <b>PT9374</b> <b>Retarder</b> (1329876)..... <b>PT9374</b> <b>Urea Filter</b> (2265672)..... <b>PE17002 KIT</b>
<b>Serie P P230 w/DC9 30/35-230 (Euro5+EEV) Eng. (10/07-on)</b> <b>Lube</b> (1742037)..... <b>P7502</b> <b>Fuel/Water Separator</b> (1393640). <b>BF46083-O</b> <b>Fuel</b> (1794863)..... <b>PF9829 KIT</b> <b>Radial Seal Air</b> (1869993)..... <b>RS30142 KIT</b> <b>19.8 mm Height Cab Air</b> ..... <b>PA5493</b> <b>69.1 mm Height Cab Air</b> ..... <b>PA4938</b> <b>Air Dryer</b> (1774598)..... <b>BA5378</b> <b>Trans.</b> (1301696)..... <b>BT9318</b> <b>Steering</b> ..... <b>P106-HD</b> <b>Retarder</b> ..... <b>PT9374</b>	<b>Serie P P270 w/DC9 17-270 (Euro4) Eng. (10/05-on)</b> <b>Lube</b> (Standard Vers.)..... <b>B76</b> <b>Fuel/Water Separator</b> (1393640). <b>BF46083-O</b> <b>Fuel</b> (1459762)..... <b>PF7936</b> <b>Radial Seal Air</b> (Don. Air System) (Replacement Element) (1728667) <b>RS30142</b> <b>Radial Seal Air</b> (Don. Air System) <b>RS3724</b> <b>Radial Seal Air</b> (Don. Air System) (Initial Installation) (1728667)..... <b>RS30142 KIT</b> <b>Radial Seal Air</b> (Plastic End Cap) <b>RS30142 KIT</b> <b>Radial Seal Air</b> (Mahle/Knecht Air System)..... <b>RS4963</b> <b>19.8 mm Height Cab Air</b> (1913500)..... <b>PA5493</b> <b>69.1 mm Height Cab Air</b> (1420197)..... <b>PA4938</b> <b>Air Dryer</b> (Mann TB1394/3X)..... <b>BA5378</b> <b>Trans.</b> ..... <b>BT9318</b> <b>Steering</b> ..... <b>P106-HD</b> <b>Retarder</b> (1381235)..... <b>PT9374</b>	<b>Serie P P310 w/DC9 11-310 (Euro3) Eng. (09/04-on)</b> <b>Lube</b> (Standard Vers.)..... <b>B76</b> <b>Fuel/Water Separator</b> (1393640). <b>BF46083-O</b> <b>Fuel</b> (1411894)..... <b>BF7908</b> <b>Radial Seal Air</b> (Don. Air System) (Replacement Element) (1728667) <b>RS30142</b> <b>Radial Seal Air</b> (Don. Air System) <b>RS3724</b> <b>Radial Seal Air</b> (Don. Air System) (Initial Installation) (1728667)..... <b>RS30142 KIT</b> <b>Radial Seal Air</b> (Plastic End Cap) <b>RS30142 KIT</b> <b>Radial Seal Air</b> (Mahle/Knecht Air System)..... <b>RS4963</b> <b>19.8 mm Height Cab Air</b> (1913500)..... <b>PA5493</b> <b>69.1 mm Height Cab Air</b> (1420197)..... <b>PA4938</b> <b>Air Dryer</b> (Mann TB1374/3X)..... <b>BA5375</b> <b>Trans.</b> ..... <b>BT9318</b> <b>Steering</b> ..... <b>P106-HD</b> <b>Retarder</b> (1381235)..... <b>PT9374</b>
<b>Serie P P250 w/DC09(Euro 6) Eng. (10/13-on)</b> <b>Lube</b> (1742037)..... <b>P7502</b> <b>Fuel</b> (1736248)..... <b>PF9829 KIT</b> <b>Radial Seal Air</b> (1869993)..... <b>RS30142 KIT</b> <b>Cab Air</b> (1770813)..... <b>PA5493</b> <b>Air Dryer</b> (1774598)..... <b>BA5378</b> <b>Air Dryer</b> (Haldex) (1393551)..... <b>BA16000</b> <b>Trans.</b> (1301696)..... <b>BT9318</b> <b>Steering</b> (153468)..... <b>P106-HD</b> <b>Hyd.</b> (1893214)..... <b>PT9374</b> <b>Retarder</b> (1329876)..... <b>PT9374</b> <b>Urea Filter</b> (2265672)..... <b>PE17002 KIT</b>	<b>Serie P P270 w/DC9 17-270 (Euro4) Eng. (10/05-on)</b> <b>Lube</b> (Standard Vers.)..... <b>B76</b> <b>Fuel/Water Separator</b> (1393640). <b>BF46083-O</b> <b>Fuel</b> (1459762)..... <b>PF7936</b> <b>Radial Seal Air</b> (Don. Air System) (Replacement Element) (1728667) <b>RS30142</b> <b>Radial Seal Air</b> (Don. Air System) <b>RS3724</b> <b>Radial Seal Air</b> (Don. Air System) (Initial Installation) (1728667)..... <b>RS30142 KIT</b> <b>Radial Seal Air</b> (Plastic End Cap) <b>RS30142 KIT</b> <b>Radial Seal Air</b> (Mahle/Knecht Air System)..... <b>RS4963</b> <b>19.8 mm Height Cab Air</b> (1913500)..... <b>PA5493</b> <b>69.1 mm Height Cab Air</b> (1420197)..... <b>PA4938</b> <b>Air Dryer</b> (Mann TB1394/3X)..... <b>BA5378</b> <b>Trans.</b> ..... <b>BT9318</b> <b>Steering</b> ..... <b>P106-HD</b> <b>Retarder</b> (1381235)..... <b>PT9374</b>	<b>Serie P P310 w/DC9 (Euro 3) 13-230 Eng. (09/04-on)</b> <b>Lube</b> (Standard Vers.)..... <b>B76</b> <b>Fuel</b> (1411894)..... <b>BF7908</b> <b>Radial Seal Air</b> (Don. Air System) <b>RS3724</b> <b>Radial Seal Air</b> (Mahle/Knecht Air System)..... <b>RS4963</b> <b>Cab Air</b> (1420197)..... <b>PA4938</b> <b>Air Dryer</b> (Mann TB1374/3X)..... <b>BA5375</b> <b>Trans.</b> (1301696)..... <b>BT9318</b> <b>Steering</b> ..... <b>P106-HD</b> <b>Retarder</b> (1381235)..... <b>PT9374</b>
<b>Serie P P250 w/DC09(Euro 6) Eng. (10/13-on)</b> <b>Lube</b> (1742037)..... <b>P7502</b> <b>Fuel/Water Separator</b> (1393640). <b>BF46083-O</b> <b>Fuel</b> (1794863)..... <b>PF9829 KIT</b> <b>Radial Seal Air</b> (1869993)..... <b>RS30142 KIT</b> <b>Cab Air</b> (1770813)..... <b>PA5493</b> <b>Air Dryer</b> (1774598)..... <b>BA5378</b> <b>Trans.</b> (1301696)..... <b>BT9318</b> <b>Steering</b> (153468)..... <b>P106-HD</b> <b>Hyd.</b> (1893214)..... <b>PT9374</b> <b>Retarder</b> (1329876)..... <b>PT9374</b> <b>Urea Filter</b> (2265672)..... <b>PE17002 KIT</b>	<b>Serie P P280 w/DC9 29/36-280 (Euro5+EEV) Eng. (10/07-on)</b> <b>Lube</b> (1742037)..... <b>P7502</b> <b>Fuel/Water Separator</b> (1393640). <b>BF46083-O</b>	

Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

SCANIA Trucks (cont'd)	SCANIA Trucks (cont'd)	SCANIA Trucks (cont'd)
Serie P P310 w/DC9 18-310 (Euro4) Eng. (11/05-on)	Serie P P340 w/DC11-340 (Euro3) Eng. (09/04-on) (Cont'd)	Serie P P370 w/ DC13 (Euro 6) Eng. (10/13-on)
Lube (Standard Vers.)..... B76	19.8 mm Height Cab Air (1913500)..... PA5493	Lube (1742037)..... P7502
Fuel/Water Separator (1393640). BF46083-O	69.1 mm Height Cab Air (1420197)..... PA4938	Fuel (1736248)..... PF9829 KIT
Fuel (1459762)..... PF7936	Air Dryer (Mann TB1374/3X)..... BA5375	Radial Seal Air (1869993)..... RS30142 KIT
Radial Seal Air (Don. Air System) (Replacement Element) (1728667) RS30142	Trans. (1301696)..... BT9318	Cab Air (1770813)..... PA5493
Radial Seal Air (Don. Air System) RS3724	Steering..... P106-HD	Air Dryer (1774598)..... BA5378
Radial Seal Air (Don. Air System) (Initial Installation) (1728667)..... RS30142 KIT	Retarder (1381235)..... PT9374	Air Dryer (Haldex) (1393551)..... BA16000
Radial Seal Air (Plastic End Cap) RS30142 KIT	Serie P P340 w/DC12-340 (Euro4) Eng. (05/06-on)	Trans. (1301696)..... BT9318
Radial Seal Air (Mahle/Knecht Air System)..... RS4963	Lube (Standard Vers.)..... B76	Steering (153468)..... P106-HD
19.8 mm Height Cab Air (1913500)..... PA5493	Fuel/Water Separator (1393640). BF46083-O	Hyd. (1893214)..... PT9374
69.1 mm Height Cab Air (1420197)..... PA4938	Fuel (1459762)..... PF7936	Retarder (1329876)..... PT9374
Air Dryer (Mann TB1394/3X)..... BA5378	Radial Seal Air (Don. Air System) (Replacement Element) (1728667) RS30142	Urea Filter (2265672)..... PE17002 KIT
Trans..... BT9318	Radial Seal Air (Don. Air System) (Initial Installation) (1728667)..... RS30142 KIT	Serie P P380 w/DC11 09-380 (Euro 3) Eng. (09/04-on)
Steering..... P106-HD	Radial Seal Air (Plastic End Cap) RS30142 KIT	Lube (Standard Vers.)..... B76
Retarder (1381235)..... PT9374	Radial Seal Air (Mahle/Knecht Air System)..... RS4963	Fuel/Water Separator (1393640). BF46083-O
Serie P P320 w/DC9 28-320 (Euro5) Eng. (10/07-on)	19.8 mm Height Cab Air (1913500)..... PA5493	Fuel (1411894)..... BF7908
Lube (1742037)..... P7502	69.1 mm Height Cab Air (1420197)..... PA4938	Radial Seal Air (Don. Air System) (Replacement Element) (1728667) RS30142
Fuel/Water Separator (1393640). BF46083-O	Air Dryer (Mann TB1394/3X)..... BA5378	Radial Seal Air (Don. Air System) (Initial Installation) (1728667)..... RS30142 KIT
Fuel (1794863)..... PF9829 KIT	Trans. (1301696)..... BT9318	Radial Seal Air (Plastic End Cap) RS30142 KIT
Radial Seal Air (1869993)..... RS30142 KIT	Steering..... P106-HD	Radial Seal Air (Mahle/Knecht Air System)..... RS4963
19.8 mm Height Cab Air (1913500)..... PA5493	Retarder (1381235)..... PT9374	19.8 mm Height Cab Air (1913500)..... PA5493
69.1 mm Height Cab Air..... PA4938	Serie P P360 w/DC13 06-360 (Euro5) Eng. (10/07-on)	69.1 mm Height Cab Air (1420197)..... PA4938
Air Dryer (1774598)..... BA5378	Lube (1742037)..... P7502	Air Dryer (Mann TB1374/3X)..... BA5375
Air Dryer (1774598)..... BA5378	Fuel/Water Separator (1393640). BF46083-O	Trans. (1301696)..... BT9318
Steering..... P106-HD	Fuel (1794863)..... PF9829 KIT	Steering..... P106-HD
Retarder..... PT9374	Radial Seal Air (1869993)..... RS30142 KIT	Retarder (1381235)..... PT9374
Serie P P320 w/DC09 (Euro 6) Eng. (10/13-on)	19.8 mm Height Cab Air (1913500)..... PA5493	Serie P P380 w/DC12-380 (Euro4) Eng. (10/05-on)
Lube (1742037)..... P7502	69.1 mm Height Cab Air..... PA4938	Lube (Standard Vers.)..... B76
Fuel Kit (1736248)..... PF9829 KIT	Air Dryer (1774598)..... BA5378	Fuel/Water Separator (1393640). BF46083-O
Radial Seal Air (1869993)..... RS30142 KIT	Air Dryer (Haldex) (1393551)..... BA16000	Fuel (1459762)..... PF7936
Cab Air (1770813)..... PA5493	Trans. (1301696)..... BT9318	Radial Seal Air (Don. Air System) (Replacement Element) (1728667) RS30142
Air Dryer (1774598)..... BA5378	Steering (153468)..... P106-HD	Radial Seal Air (Plastic End Cap) RS30142 KIT
Air Dryer (Haldex) (1393551)..... BA16000	Hyd. (1893214)..... PT9374	Radial Seal Air (Mahle/Knecht Air System)..... RS4963
Trans. (1301696)..... BT9318	Retarder (1329876)..... PT9374	Cab Air (1420197)..... PA4938
Steering (153468)..... P106-HD	Urea Filter (2265672)..... PE17002 KIT	Air Dryer (Mann TB1394/3X)..... BA5378
Hyd. (1893214)..... PT9374	Serie P P360 w/DC09 (Euro 6) Eng. (10/13-on)	Trans. (1301696)..... BT9318
Retarder (1329876)..... PT9374	Lube (1742037)..... P7502	Steering..... P106-HD
Urea Filter (2265672)..... PE17002 KIT	Fuel (1736248)..... PF9829 KIT	Retarder (1381235)..... PT9374
Serie P P340 w/DC11-340 (Euro3) Eng. (09/04-on)	Radial Seal Air (1869993)..... RS30142 KIT	Serie P P380 w/DC12 18-380 (Euro5) Eng. (10/07-on)
Lube (Standard Vers.)..... B76	Cab Air (1770813)..... PA5493	Lube (Standard Vers.)..... B76
Fuel/Water Separator (1393640). BF46083-O	Air Dryer (1774598)..... BA5378	Fuel/Water Separator (1393640). BF46083-O
Fuel (1411894)..... BF7908	Air Dryer (Haldex) (1393551)..... BA16000	Fuel (1459762)..... PF7936
Radial Seal Air (Don. Air System) (Replacement Element) (1728667) RS30142	Trans. (1301696)..... BT9318	Radial Seal Air (Don. Air System) (Replacement Element) (1728667) RS30142
Radial Seal Air (Don. Air System) RS3724	Steering (153468)..... P106-HD	Radial Seal O. Air (Don. Air System)..... RS3724
Radial Seal Air (Don. Air System) (Initial Installation) (1728667)..... RS30142 KIT	Hyd. (1893214)..... PT9374	Radial Seal Air (Don. Air System) (Initial Installation) (1728667)..... RS30142 KIT
Radial Seal Air (Plastic End Cap) RS30142 KIT	Retarder (1329876)..... PT9374	
Radial Seal Air (Mahle/Knecht Air System)..... RS4963	Urea Filter (2265672)..... PE17002 KIT	

Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).


SCANIA Trucks (cont'd)	SCANIA Trucks (cont'd)	SCANIA Trucks (cont'd)
<p>Serie P P380 w/DC12 18-380 (Euro5) Eng. (10/07-on) (Cont'd)</p> <p><b>Radial Seal Air</b> (Plastic End Cap) <b>RS30142 KIT</b></p> <p><b>Radial Seal Air</b> (Mahle/Knecht Air System)..... <b>RS4963</b></p> <p><b>19.8 mm Height Cab Air</b> (1913500)..... <b>PA5493</b></p> <p><b>69.1 mm Height Cab Air</b>..... <b>PA4938</b></p> <p><b>Air Dryer</b> (1774598)..... <b>BA5378</b></p> <p><b>Trans.</b>..... <b>BT9318</b></p> <p><b>Steering</b>..... <b>P106-HD</b></p> <p><b>Retarder</b>..... <b>PT9374</b></p> <hr/> <p>Serie P P400 w/DC13 05-400 (Euro5) Eng. (10/07-on)</p> <p><b>Lube</b> (1742032)..... <b>P7502</b></p> <p><b>Fuel/Water Separator</b> (1393640). <b>BF46083-O</b></p> <p><b>Fuel</b> (1794863)..... <b>PF9829 KIT</b></p> <p><b>Radial Seal Air</b> (1869993)..... <b>RS30142 KIT</b></p> <p><b>19.8 mm Height Cab Air</b> (1913500)..... <b>PA5493</b></p> <p><b>69.1 mm Height Cab Air</b>..... <b>PA4938</b></p> <p><b>Air Dryer</b> (1774598)..... <b>BA5378</b></p> <p><b>Steering</b>..... <b>P106-HD</b></p> <p><b>Retarder</b>..... <b>PT9374</b></p> <hr/> <p>Serie P P410 w/DC13 (Euro 6) Eng. (10/13-on)</p> <p><b>Lube</b> (1742037)..... <b>P7502</b></p> <p><b>Fuel</b> (1736248)..... <b>PF9829 KIT</b></p> <p><b>Radial Seal Air</b> (1869993)..... <b>RS30142 KIT</b></p> <p><b>Cab Air</b> (1770813)..... <b>PA5493</b></p> <p><b>Air Dryer</b> (1774598)..... <b>BA5378</b></p> <p><b>Air Dryer</b> (Haldex) (1393551)..... <b>BA16000</b></p> <p><b>Trans.</b> (1301696)..... <b>BT9318</b></p> <p><b>Steering</b> (153468)..... <b>P106-HD</b></p> <p><b>Hyd.</b> (1893214)..... <b>PT9374</b></p> <p><b>Retarder</b> (1329876)..... <b>PT9374</b></p> <p><b>Urea Filter</b> (2265672)..... <b>PE17002 KIT</b></p> <hr/> <p>Serie P P420 w/DC12 14-420 (Euro3) Eng. (09/04-on)</p> <p><b>Lube</b> (Standard Vers.)..... <b>B76</b></p> <p><b>Fuel/Water Separator</b> (1393640). <b>BF46083-O</b></p> <p><b>Fuel</b> (1411894)..... <b>BF7908</b></p> <p><b>Radial Seal Air</b> (Don. Air System) (Replacement Element) (1728667) <b>RS30142</b></p> <p><b>Radial Seal Air</b> (Don. Air System) <b>RS3724</b></p> <p><b>Radial Seal Air</b> (Don. Air System) (Initial Installation) (1728667)..... <b>RS30142 KIT</b></p> <p><b>Radial Seal Air</b> (Plastic End Cap) <b>RS30142 KIT</b></p> <p><b>Radial Seal Air</b> (Mahle/Knecht Air System)..... <b>RS4963</b></p> <p><b>19.8 mm Height Cab Air</b> (1913500)..... <b>PA5493</b></p> <p><b>69.1 mm Height Cab Air</b> (1420197)..... <b>PA4938</b></p> <p><b>Air Dryer</b> (Mann TB1374/3X)..... <b>BA5375</b></p> <p><b>Trans.</b> (1301696)..... <b>BT9318</b></p> <p><b>Steering</b>..... <b>P106-HD</b></p> <p><b>Retarder</b> (1381235)..... <b>PT9374</b></p> <hr/> <p>Serie P P420 w/DC12 15-420 (Euro5) Eng. (05/06-on)</p> <p><b>Lube</b> (Standard Vers.)..... <b>B76</b></p> <p><b>Fuel/Water Separator</b> (1393640). <b>BF46083-O</b></p> <p><b>Fuel</b> (1459762)..... <b>PF7936</b></p> <p><b>Radial Seal Air</b> (Don. Air System) (Replacement Element) (1728667) <b>RS30142</b></p> <p><b>Radial Seal Air</b> (Don. Air System) <b>RS3724</b></p> <p><b>Radial Seal Air</b> (Don. Air System) (Initial Installation) (1728667)..... <b>RS30142 KIT</b></p> <p><b>Radial Seal Air</b> (Plastic End Cap) <b>RS30142 KIT</b></p> <p><b>Radial Seal Air</b> (Mahle/Knecht Air System)..... <b>RS4963</b></p> <p><b>19.8 mm Height Cab Air</b> (1913500)..... <b>PA5493</b></p> <p><b>69.1 mm Height Cab Air</b> (1420197)..... <b>PA4938</b></p> <p><b>Air Dryer</b> (Mann TB1374/3X)..... <b>BA5375</b></p> <p><b>Trans.</b> (1301696)..... <b>BT9318</b></p> <p><b>Steering</b>..... <b>P106-HD</b></p> <p><b>Retarder</b> (1381235)..... <b>PT9374</b></p> <hr/> <p>Serie P P420 w/DT12 12-420 (Euro4) Eng. (09/04-on)</p> <p><b>Lube</b> (Standard Vers.)..... <b>B76</b></p> <p><b>Fuel/Water Separator</b> (1393640). <b>BF46083-O</b></p> <p><b>Fuel</b> (1459762)..... <b>PF7936</b></p> <p><b>Radial Seal Air</b> (Don. Air System) (Replacement Element) (1728667) <b>RS30142</b></p> <p><b>Radial Seal Air</b> (Don. Air System) <b>RS3724</b></p> <p><b>Radial Seal Air</b> (Don. Air System) (Initial Installation) (1728667)..... <b>RS30142 KIT</b></p> <p><b>Radial Seal Air</b> (Plastic End Cap) <b>RS30142 KIT</b></p> <p><b>Radial Seal Air</b> (Mahle/Knecht Air System)..... <b>RS4963</b></p> <p><b>19.8 mm Height Cab Air</b> (1913500)..... <b>PA5493</b></p> <p><b>69.1 mm Height Cab Air</b> (1420197)..... <b>PA4938</b></p> <p><b>Air Dryer</b> (Mann TB1394/3X)..... <b>BA5378</b></p> <p><b>Trans.</b> (1301696)..... <b>BT9318</b></p> <p><b>Steering</b>..... <b>P106-HD</b></p> <p><b>Retarder</b> (1381235)..... <b>PT9374</b></p> <hr/> <p>Serie P P450 w/ DC13 (Euro 6) Eng. (10/13-on)</p> <p><b>Lube</b> (1742037)..... <b>P7502</b></p> <p><b>Fuel Kit</b> (1736248)..... <b>PF9829 KIT</b></p> <p><b>Radial Seal Air</b> (1869993)..... <b>RS30142 KIT</b></p> <p><b>Cab Air</b> (1770813)..... <b>PA5493</b></p> <p><b>Air Dryer</b> (1774598)..... <b>BA5378</b></p> <p><b>Air Dryer</b> (Haldex) (1393551)..... <b>BA16000</b></p> <p><b>Trans.</b> (1301696)..... <b>BT9318</b></p> <p><b>Steering</b> (153468)..... <b>P106-HD</b></p> <p><b>Hyd.</b> (1893214)..... <b>PT9374</b></p> <p><b>Retarder</b> (1329876)..... <b>PT9374</b></p> <p><b>Urea Filter</b> (2265672)..... <b>PE17002 KIT</b></p> <hr/> <p>Serie P P470 w/DT12 06-470 (Euro 3) Eng. (09/04-on)</p> <p><b>Lube</b> (Standard Vers.)..... <b>B76</b></p> <p><b>Fuel/Water Separator</b> (1393640). <b>BF46083-O</b></p>	<p>Serie P P470 w/DT12 06-470 (Euro 3) Eng. (09/04-on) (Cont'd)</p> <p><b>Fuel</b> (1459762)..... <b>PF7936</b></p> <p><b>Radial Seal Air</b> (Don. Air System) (Replacement Element) (1728667) <b>RS30142</b></p> <p><b>Radial Seal Air</b> (Don. Air System) <b>RS3724</b></p> <p><b>Radial Seal Air</b> (Don. Air System) (Initial Installation) (1728667)..... <b>RS30142 KIT</b></p> <p><b>Radial Seal Air</b> (Plastic End Cap) <b>RS30142 KIT</b></p> <p><b>Radial Seal Air</b> (Mahle/Knecht Air System)..... <b>RS4963</b></p> <p><b>19.8 mm Height Cab Air</b> (1913500)..... <b>PA5493</b></p> <p><b>69.1 mm Height Cab Air</b> (1420197)..... <b>PA4938</b></p> <p><b>Air Dryer</b> (Mann TB1374/3X)..... <b>BA5375</b></p> <p><b>Trans.</b> (1301696)..... <b>BT9318</b></p> <p><b>Steering</b>..... <b>P106-HD</b></p> <p><b>Retarder</b> (1381235)..... <b>PT9374</b></p> <hr/> <p>Serie P P490 w/ DC13 (Euro 6) Eng. (10/13-on)</p> <p><b>Lube</b> (1742037)..... <b>P7502</b></p> <p><b>Fuel Kit</b> (1736248)..... <b>PF9829 KIT</b></p> <p><b>Radial Seal Air</b> (1869993)..... <b>RS30142 KIT</b></p> <p><b>Cab Air</b> (1770813)..... <b>PA5493</b></p> <p><b>Air Dryer</b> (1774598)..... <b>BA5378</b></p> <p><b>Air Dryer</b> (Haldex) (1393551)..... <b>BA16000</b></p> <p><b>Trans.</b> (1301696)..... <b>BT9318</b></p> <p><b>Steering</b> (153468)..... <b>P106-HD</b></p> <p><b>Hyd.</b> (1893214)..... <b>PT9374</b></p> <p><b>Retarder</b> (1329876)..... <b>PT9374</b></p> <p><b>Urea Filter</b> (2265672)..... <b>PE17002 KIT</b></p> <hr/> <p>PR93</p> <p><b>Fuel</b> (364624)..... <b>[2] BF988 +</b></p> <p><b>O. Air</b> (395773)..... <b>PA2813</b></p> <p><b>Opt. I. Air</b> (397813)..... <b>PA4809</b></p> <p><b>Air</b> (w/low air inlet) (395776)..... <b>PA3794</b></p> <p><b>Coolant</b> (w/o Chemical) (342988) <b>B5089 +</b></p> <p><b>Coolant</b> (w/8 Units BTE) (378396)..... <b>BW5139</b></p> <p><b>Turbocharger</b> (173171)..... <b>B229</b></p> <p><b>Steering</b> (153468)..... <b>P106-HD</b></p> <p><b>Some Gearbox</b> (1301696)..... <b>BT9318</b></p> <hr/> <p>PR94</p> <p><b>Lube</b> (Standard Vers.) (1117285). <b>B76</b></p> <p><b>Fuel</b> (1372444)..... <b>BF7624</b></p> <p><b>Radial Seal Air</b> (Don. Air System) (1421022)..... <b>RS3724</b></p> <p><b>Radial Seal Air</b> (Knecht Air System) (1387549)..... <b>RS4963</b></p> <p><b>Cab Air</b> (1420197)..... <b>PA4938</b></p> <p><b>Coolant</b> (w/o Chemical) (342988) <b>B5089 +</b></p> <p><b>Coolant</b> (w/8 Units BTE) (378396)..... <b>BW5139</b></p> <p><b>Steering</b> (153468)..... <b>P106-HD</b></p> <p><b>Gearbox</b> (1301696)..... <b>BT9318</b></p>	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

SCANIA Trucks (cont'd)	SCANIA Trucks (cont'd)	SCANIA Trucks (cont'd)
PR113 Lube (173171)..... <b>B229</b> Fuel (364624)..... <b>[2] BF988 +</b> O. Air (395773)..... <b>PA2813</b> Opt. I. Air (397813)..... <b>PA4809</b> Air (w/low air inlet) (395776)..... <b>PA3794</b> Coolant (w/o Chemical) (342988) <b>B5089 +</b> Coolant (w/8 Units BTE) (378396)..... <b>BW5139</b> Steering (153468)..... <b>P106-HD</b> Some Gearbox (1301696)..... <b>BT9318</b>	Serie 4 R/T144 w/DSC 14 (Euro2) Eng. (11/95-12/01) (Cont'd) Radial Seal Air (Don. Air System) (Replacement Ele.) (1728817)..... <b>RS30143 90</b> Radial Seal Air (Don. Air System) (1335678)..... <b>RS3726</b> Radial Seal Air (Mahle/Knecht Air System)..... <b>RS4638 +</b> Cab Air (1420197)..... <b>PA4938</b> Air Dryer (Mann TB1374/3X)..... <b>BA5375</b> Coolant (342988)..... <b>B5089 +</b> Trans..... <b>BT9318</b> Steering (1902137)..... <b>P106-HD</b> Retarder (1381235)..... <b>PT9374</b>	Serie 4 R/T124 w/DT1202/08 (Euro3) Eng. (02/01-10/04) (Cont'd) Radial Seal Air (Don. Air System) (Initial Installation) (1728667)..... <b>RS30142 KIT</b> Radial Seal Air (Plastic End Cap) <b>RS30142 KIT</b> Radial Seal Air (Mahle/Knecht Air System)..... <b>RS4963</b> Cab Air (1420197)..... <b>PA4938</b> Air Dryer (Mann TB1374/3X)..... <b>BA5375</b> Trans..... <b>BT9318</b> Steering..... <b>P106-HD</b> Retarder (1381235)..... <b>PT9374</b>
PR114 Fuel (1372444)..... <b>BF7624</b> Radial Seal Air (Don. Air System) (1421022)..... <b>RS3724</b> Radial Seal Air (Knecht Air System) (1387549)..... <b>RS4963</b> Cab Air (1420197)..... <b>PA4938</b> Coolant (w/o Chemical) (342988) <b>B5089 +</b> Coolant (w/8 Units BTE) (378396)..... <b>BW5139</b> Turbocharger (173171)..... <b>B229</b> Steering (153468)..... <b>P106-HD</b> Gearbox (1301696)..... <b>BT9318</b>	Serie 4 R/T124 w/DSC12 (Euro2) Eng. (11/95-10/04) Lube (Standard Vers.)..... <b>B76</b> Fuel/Water Separator (1393640). <b>BF46083-O</b> Fuel..... <b>BF7624</b> Radial Seal Air (Don. Air System) (Replacement Element) (1728667) <b>RS30142</b> Radial Seal Air (Don. Air System) <b>RS3724</b> Radial Seal Air (Don. Air System) (Initial Installation) (1728667)..... <b>RS30142 KIT</b> Radial Seal Air (Plastic End Cap) <b>RS30142 KIT</b> Radial Seal Air (Mahle/Knecht Air System)..... <b>RS4963</b> Cab Air (1420197)..... <b>PA4938</b> Air Dryer (Mann TB1374/3X)..... <b>BA5375</b> Trans. (1301696)..... <b>BT9318</b> Steering..... <b>P106-HD</b> Retarder (1381235)..... <b>PT9374</b>	Serie 4 R/T124 w/DC1203 (Euro3-1) Eng. (10/02-10/04) Lube (Standard Vers.)..... <b>B76</b> Fuel/Water Separator (1393640). <b>BF46083-O</b> Fuel (1411894)..... <b>BF7908</b> Radial Seal Air (Don. Air System) (Replacement Element) (1728667) <b>RS30142</b> Radial Seal Air (Don. Air System) <b>RS3724</b> Radial Seal Air (Don. Air System) (Initial Installation) (1728667)..... <b>RS30142 KIT</b> Radial Seal Air (Plastic End Cap) <b>RS30142 KIT</b> Radial Seal Air (Mahle/Knecht Air System)..... <b>RS4963</b> Cab Air (1420197)..... <b>PA4938</b> Air Dryer (Mann TB1374/3X)..... <b>BA5375</b> Trans..... <b>BT9318</b> Steering..... <b>P106-HD</b> Retarder (1381235)..... <b>PT9374</b>
PR124 Lube (Standard Vers.) (1117285). <b>B76</b> Fuel (1372444)..... <b>BF7624</b> Radial Seal Air (Don. Air System) (1421022)..... <b>RS3724</b> Radial Seal Air (Knecht Air System) (1387549)..... <b>RS4963</b> Coolant (w/o Chemical) (342988) <b>B5089 +</b> Coolant (w/8 Units BTE) (378396)..... <b>BW5139</b> Steering (153468)..... <b>P106-HD</b> Gearbox (1301696)..... <b>BT9318</b>	Serie 4 R/T124 w/DC12 Eng. (3/99-10/04) Lube (Standard Vers.)..... <b>B76 +</b> Lube (Severe Service)..... <b>B76-SS +</b> Fuel/Water Separator (1393640). <b>BF46083-O</b> Fuel..... <b>BF7624</b> Radial Seal Air (Don. Air System) (Replacement Element) (1728667) <b>RS30142</b> Radial Seal Air (Don. Air System) <b>RS3724</b> Radial Seal Air (Don. Air System) (Initial Installation) (1728667)..... <b>RS30142 KIT</b> Radial Seal Air (Plastic End Cap) <b>RS30142 KIT</b> Radial Seal Air (Mahle/Knecht Air System)..... <b>RS4963</b> Cab Air (1420197)..... <b>PA4938</b> Air Dryer (Mann TB1374/3X)..... <b>BA5375</b> Trans. (1301696)..... <b>BT9318</b> Steering..... <b>P106-HD</b> Retarder (1381235)..... <b>PT9374</b>	Serie 4 R/T164 V8 w/DC16.01, DC16.02 Engs. (06/00-10/04) Lube (1439036)..... <b>P7319</b> Fuel/Water Separator (1393640). <b>BF46083-O</b> Fuel (Fleetguard FF5423)..... <b>PF7896</b> Radial Seal O. Air (Don. Air System)..... <b>RS3726</b> Radial Seal I. Air (Don. Air System)..... <b>RS5313</b> Single Radial Seal Air (Don. Air System) (1st Install) (1728817)..... <b>RS30143 KIT 90</b> Single Radial Seal Air (Don. Air System) (Replacement Ele.) (1728817)..... <b>RS30143 90</b> Radial Seal Air (Mahle/Knecht Air System)..... <b>RS4638 +</b> Cab Air (1420197)..... <b>PA4938</b> Air Dryer (Mann TB1374/3X)..... <b>BA5375</b> Trans..... <b>BT9318</b> Steering..... <b>P106-HD</b> Retarder (1381235)..... <b>PT9374</b>
PR143 Fuel (364624)..... <b>[2] BF988 +</b> O. Air (395773)..... <b>PA2813</b> Opt. I. Air (397813)..... <b>PA4809</b> Air (w/low air inlet) (395776)..... <b>PA3794</b> Coolant (w/o Chemical) (342988) <b>B5089 +</b> Coolant (w/8 Units BTE) (378396)..... <b>BW5139</b> Turbocharger (173171)..... <b>B229</b> Steering (153468)..... <b>P106-HD</b> Some Gearbox (1301696)..... <b>BT9318</b>	Serie 4 R/T124 w/DT1202/08 (Euro3) Eng. (02/01-10/04) Lube (Standard Vers.)..... <b>B76</b> Fuel/Water Separator (1393640). <b>BF46083-O</b> Fuel (1459762)..... <b>PF7936</b> Radial Seal Air (Don. Air System) (Replacement Element) (1728667) <b>RS30142</b> Radial Seal Air (Don. Air System) <b>RS3724</b> Radial Seal Air (Don. Air System) (Initial Installation) (1728667)..... <b>RS30142 KIT</b> Radial Seal Air (Plastic End Cap) <b>RS30142 KIT</b> Radial Seal Air (Mahle/Knecht Air System)..... <b>RS4963</b> Cab Air (1420197)..... <b>PA4938</b> Air Dryer (Mann TB1374/3X)..... <b>BA5375</b> Trans. (1301696)..... <b>BT9318</b> Steering..... <b>P106-HD</b> Retarder (1381235)..... <b>PT9374</b>	Serie 4 R/T164 V8 (164-480) w/ DC 16.02 Eng. (06/00-10/04) Lube (1439036)..... <b>P7319</b> Fuel/Water Separator (1393640). <b>BF46083-O</b> Fuel (1446432)..... <b>PF7896</b> Radial Seal Air (1421021)..... <b>RS3726</b>
Serie 4 PRT124 w/DT12 Eng. (1393640)..... <b>BF46083-O</b> Fuel (1459762)..... <b>PF7936</b>	Serie 4 R/T144 w/DSC 14 (Euro2) Eng. (11/95-12/01) Lube (Standard Vers.) (1117285). <b>B76</b> Fuel/Water Separator (1393640). <b>BF46083-O</b> Fuel (1372444)..... <b>BF7624</b> Radial Seal Air (Don. Air System) (1st Install) (1728817)..... <b>RS30143 KIT 90</b>	

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

SCANIA Trucks (cont'd)	SCANIA Trucks (cont'd)	SCANIA Trucks (cont'd)
<p>Serie 4 R/T164 V8 (164-480) w/ DC 16.02 Eng. (06/00-10/04) (Cont'd)</p> <p><b>Radial Seal Air</b> (Don. Air System) (1st Install) (1869992)..... <b>RS30143 KIT<sup>90</sup></b></p> <p><b>Radial Seal Air</b> (Don. Air System) (Replacement Ele.) (1869992)..... <b>RS30143<sup>90</sup></b></p> <p><b>Radial Seal Air</b> (Knecht Air System) (1387548)..... <b>RS4638</b></p> <p><b>Radial Seal I. Air</b> (1335680)..... <b>RS5313</b></p> <p><b>Cab Air</b> (1420197)..... <b>PA4938</b></p> <p><b>Air Dryer</b> (1384549)..... <b>BA5375</b></p> <p><b>Trans.</b> (1301696)..... <b>BT9318</b></p> <p><b>Steering</b> (153468)..... <b>P106-HD</b></p> <p><b>Retarder</b> (1329876)..... <b>PT9374</b></p> <p><b>Urea Filter</b> (1795459)..... <b>PE5270</b></p> <hr/> <p>Serie 4 R/T164 V8 (164-580) w/ DC 16.01 Eng. (06/00-10/04)</p> <p><b>Lube</b> (1439036)..... <b>P7319</b></p> <p><b>Fuel/Water Separator</b> (1393640). <b>BF46083-O</b></p> <p><b>Fuel</b> (1446432)..... <b>PF7896</b></p> <p><b>Radial Seal Air</b> (1421021)..... <b>RS3726</b></p> <p><b>Radial Seal Air</b> (Don. Air System) (1st Install) (1869992)..... <b>RS30143 KIT<sup>90</sup></b></p> <p><b>Radial Seal Air</b> (Don. Air System) (Replacement Ele.) (1869992)..... <b>RS30143<sup>90</sup></b></p> <p><b>Radial Seal Air</b> (Knecht Air System) (1387548)..... <b>RS4638</b></p> <p><b>Radial Seal I. Air</b> (1335680)..... <b>RS5313</b></p> <p><b>Cab Air</b> (1420197)..... <b>PA4938</b></p> <p><b>Air Dryer</b> (1384549)..... <b>BA5375</b></p> <p><b>Trans.</b> (1301696)..... <b>BT9318</b></p> <p><b>Steering</b> (153468)..... <b>P106-HD</b></p> <p><b>Retarder</b> (1329876)..... <b>PT9374</b></p> <hr/> <p>Serie 4 R94 w/DSC9 (Euro 2) Eng. (10/95-10/04)</p> <p><b>Lube</b> (Standard Vers.) (Mann W11102/14)..... <b>B76</b></p> <p><b>Fuel/Water Separator</b> (1393640). <b>BF46083-O</b></p> <p><b>Fuel Spin-on</b> (1372444)..... <b>BF7624</b></p> <p><b>Radial Seal Air</b> (Don. Air System) (Replacement Element) (1728667) <b>RS30142</b></p> <p><b>Radial Seal O. Air</b> (Don. Air System) (Mann C301240)..... <b>RS3724</b></p> <p><b>Radial Seal Air</b> (Don. Air System) (Initial Installation) (1728667)..... <b>RS30142 KIT</b></p> <p><b>Radial Seal Air</b> (Plastic End Cap) <b>RS30142 KIT</b></p> <p><b>Radial Seal Air</b> (Mahle/Knecht Air System)..... <b>RS4963</b></p> <p><b>Cab Air</b> (1420197)..... <b>PA4938</b></p> <p><b>Air Dryer</b> (Mann TB1374/3X)..... <b>BA5375</b></p> <p><b>Trans.</b>..... <b>BT9318</b></p> <p><b>Steering</b> (1902137)..... <b>P106-HD</b></p> <p><b>Retarder</b> (1381235)..... <b>PT9374</b></p> <hr/> <p>Serie 4 R94 w/DC9 (Euro 3) Eng. (03/99-10/04)</p> <p><b>Lube</b> (Standard Vers.)..... <b>B76</b></p> <p><b>Fuel/Water Separator</b> (1393640). <b>BF46083-O</b></p> <p><b>Fuel</b> (1411894)..... <b>BF7908</b></p> <p><b>Radial Seal Air</b> (Don. Air System) <b>RS3724</b></p> <p><b>Radial Seal Air</b> (Plastic End Cap) <b>RS30142 KIT</b></p> <p><b>Radial Seal Air</b> (Mahle/Knecht Air System)..... <b>RS4963</b></p> <p><b>Cab Air</b> (1420197)..... <b>PA4938</b></p> <p><b>Air Dryer</b> (Mann TB1374/3X)..... <b>BA5375</b></p> <p><b>Trans.</b>..... <b>BT9318</b></p> <p><b>Steering</b>..... <b>P106-HD</b></p> <p><b>Retarder</b> (1381235)..... <b>PT9374</b></p> <hr/> <p>Serie 4 R94 w/DC9 (Euro 3) Eng. (03/99-10/04)</p> <p><b>Lube</b> (Standard Vers.)..... <b>B76</b></p> <p><b>Fuel/Water Separator</b> (1393640). <b>BF46083-O</b></p> <p><b>Fuel</b> (1411894)..... <b>BF7908</b></p>	<p>Serie 4 R94 w/DC9 (Euro 3) Eng. (03/99-10/04) (Cont'd)</p> <p><b>Radial Seal Air</b> (Don. Air System) (Replacement Element) (1728667) <b>RS30142</b></p> <p><b>Radial Seal Air</b> (Don. Air System) <b>RS3724</b></p> <p><b>Radial Seal Air</b> (Don. Air System) (Initial Installation) (1728667)..... <b>RS30142 KIT</b></p> <p><b>Radial Seal Air</b> (Plastic End Cap) <b>RS30142 KIT</b></p> <p><b>Radial Seal Air</b> (Mahle/Knecht Air System)..... <b>RS4963</b></p> <p><b>Cab Air</b> (1420197)..... <b>PA4938</b></p> <p><b>Air Dryer</b> (Mann TB1374/3X)..... <b>BA5375</b></p> <p><b>Trans.</b>..... <b>BT9318</b></p> <p><b>Steering</b>..... <b>P106-HD</b></p> <p><b>Retarder</b> (1381235)..... <b>PT9374</b></p> <hr/> <p>Serie 4 R114 w/DSC11 (Euro2) Eng. (10/96-10/04)</p> <p><b>Lube</b> (Standard Vers.) (1117285). <b>B76</b></p> <p><b>Fuel/Water Separator</b> (1393640). <b>BF46083-O</b></p> <p><b>Fuel</b> (1372444)..... <b>BF7624</b></p> <p><b>Radial Seal Air</b> (Don. Air System) (Replacement Element) (1728667) <b>RS30142</b></p> <p><b>Radial Seal Air</b> (Don. Air System) (1335679)..... <b>RS3724</b></p> <p><b>Radial Seal Air</b> (Don. Air System) (Initial Installation) (1728667)..... <b>RS30142 KIT</b></p> <p><b>Radial Seal Air</b> (Plastic End Cap) <b>RS30142 KIT</b></p> <p><b>Radial Seal Air</b> (Mahle/Knecht Air System)..... <b>RS4963</b></p> <p><b>Cab Air</b> (1420197)..... <b>PA4938</b></p> <p><b>Air Dryer</b> (Mann TB1374/3X)..... <b>BA5375</b></p> <p><b>Trans.</b>..... <b>BT9318</b></p> <p><b>Steering</b> (1902137)..... <b>P106-HD</b></p> <p><b>Retarder</b> (1381235)..... <b>PT9374</b></p> <hr/> <p>Serie 4 R114 w/DC11 (Euro 3) Eng. (03/99-10/04)</p> <p><b>Lube</b> (Standard Vers.)..... <b>B76</b></p> <p><b>Fuel/Water Separator</b> (1393640). <b>BF46083-O</b></p> <p><b>Fuel</b> (1411894)..... <b>BF7908</b></p> <p><b>Radial Seal Air</b> (Don. Air System) <b>RS3724</b></p> <p><b>Radial Seal Air</b> (Plastic End Cap) <b>RS30142 KIT</b></p> <p><b>Radial Seal Air</b> (Mahle/Knecht Air System)..... <b>RS4963</b></p> <p><b>Cab Air</b> (1420197)..... <b>PA4938</b></p> <p><b>Air Dryer</b> (Mann TB1374/3X)..... <b>BA5375</b></p> <p><b>Trans.</b>..... <b>BT9318</b></p> <p><b>Steering</b>..... <b>P106-HD</b></p> <p><b>Retarder</b> (1381235)..... <b>PT9374</b></p> <hr/> <p>R114GA w/DSC12 02 Eng.</p> <p><b>Fuel/Water Separator</b> (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b></p> <p><b>Fuel/Water Separator</b> (With Bowl) (Mann WK1060/1)..... <b>BF46072</b></p> <p><b>Fuel/Water Separator</b> (With Drain) (Mann WK1060/1)..... <b>BF1329</b></p> <p><b>Fuel/Water Separator</b> (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b></p> <p><b>Fuel/Water Separator</b> (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b></p> <hr/> <p>R124GA w/DSC12 02 Eng.</p> <p><b>Fuel/Water Separator</b> (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b></p> <p><b>Fuel/Water Separator</b> (With Bowl) (Mann WK1060/1)..... <b>BF46072</b></p> <p><b>Fuel/Water Separator</b> (With Drain) (Mann WK1060/1)..... <b>BF1329</b></p> <p><b>Fuel/Water Separator</b> (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b></p> <p><b>Fuel/Water Separator</b> (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b></p> <hr/> <p>R124LA w/DSC12 02 Eng.</p> <p><b>Fuel/Water Separator</b> (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b></p> <p><b>Fuel/Water Separator</b> (With Bowl) (Mann WK1060/1)..... <b>BF46072</b></p> <p><b>Fuel/Water Separator</b> (With Drain) (Mann WK1060/1)..... <b>BF1329</b></p> <p><b>Fuel/Water Separator</b> (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b></p> <p><b>Fuel/Water Separator</b> (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b></p>	<p>R114GA w/DSC12 02 Eng. (Cont'd)</p> <p><b>Fuel/Water Separator</b> (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b></p> <hr/> <p>R114LA w/DSC12 02 Eng.</p> <p><b>Fuel/Water Separator</b> (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b></p> <p><b>Fuel/Water Separator</b> (With Bowl) (Mann WK1060/1)..... <b>BF46072</b></p> <p><b>Fuel/Water Separator</b> (With Drain) (Mann WK1060/1)..... <b>BF1329</b></p> <p><b>Fuel/Water Separator</b> (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b></p> <p><b>Fuel/Water Separator</b> (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b></p> <hr/> <p>Serie 4 R124 w/DSC12 Eng.</p> <p><b>Lube</b> (Standard Vers.) (1117285). <b>B76</b></p> <p><b>Fuel</b> (1372444)..... <b>BF7624</b></p> <p><b>446.9 mm Radial Seal Air</b> (1335679)..... <b>RS3724</b></p> <p><b>526.3 mm Radial Seal Air</b> (1335678)..... <b>RS3726</b></p> <p><b>Coolant</b>..... <b>BW5139</b></p> <p><b>Trans.</b> (Mann W930/14)..... <b>BT9318</b></p> <p><b>Steering</b> (1902137)..... <b>P106-HD</b></p> <p><b>Retarder</b> (1381235)..... <b>PT9374</b></p> <hr/> <p>R124GA w/DSC12 02 Eng.</p> <p><b>Fuel/Water Separator</b> (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b></p> <p><b>Fuel/Water Separator</b> (With Bowl) (Mann WK1060/1)..... <b>BF46072</b></p> <p><b>Fuel/Water Separator</b> (With Drain) (Mann WK1060/1)..... <b>BF1329</b></p> <p><b>Fuel/Water Separator</b> (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b></p> <p><b>Fuel/Water Separator</b> (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b></p> <hr/> <p>R124LA w/DSC12 02 Eng.</p> <p><b>Fuel/Water Separator</b> (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b></p> <p><b>Fuel/Water Separator</b> (With Bowl) (Mann WK1060/1)..... <b>BF46072</b></p> <p><b>Fuel/Water Separator</b> (With Drain) (Mann WK1060/1)..... <b>BF1329</b></p> <p><b>Fuel/Water Separator</b> (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b></p> <p><b>Fuel/Water Separator</b> (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b></p>

\* See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

SCANIA Trucks (cont'd)	SCANIA Trucks (cont'd)	SCANIA Trucks (cont'd)
R142H, R142M, R142MA, T142E, T142H w/DS14 Turbo Eng. Lube (173171)..... <b>B229</b> Fuel (364624)..... <b>BF988 +</b> O. Air (370754)..... <b>PA2801</b> Coolant (378396)..... <b>BW5139</b>	Serie R R230 w/DC9 16-230 (Euro4) Eng. (10/05-on) (Cont'd) Radial Seal Air (Don. Air System) (Initial Installation) (1728667)..... <b>RS30142 KIT</b> Radial Seal Air (Plastic End Cap)..... <b>RS30142 KIT</b> Radial Seal Air (Mahle/Knecht Air System)..... <b>RS4963</b> 19.8 mm Height Cab Air (1913500)..... <b>PA5493</b> 69.1 mm Height Cab Air (1420197)..... <b>PA4938</b> Air Dryer (Mann TB1394/3X)..... <b>BA5378</b> Trans. (1301696)..... <b>BT9318</b> Steering..... <b>P106-HD</b> Retarder (1381235)..... <b>PT9374</b>	Serie R R270 w/DC9 17-270 (Euro4) Eng. (10/05-on) (Cont'd) 19.8 mm Height Cab Air (1913500)..... <b>PA5493</b> 69.1 mm Height Cab Air (1420197)..... <b>PA4938</b> Air Dryer (Mann TB1394/3X)..... <b>BA5378</b> Trans. (1301696)..... <b>BT9318</b> Steering..... <b>P106-HD</b> Retarder (1381235)..... <b>PT9374</b>
R143 w/DSC14 Eng. Lube (Mann W920/7)..... <b>B229</b> Fuel Spin-on (457431326)..... <b>BF988 +</b> Fuel Spin-on (w/Drain) (Mann WK842)..... <b>BF587-D +</b> O. Air (Mann C30703)..... <b>PA2813</b> I. Air (Mann CF1610)..... <b>PA4809</b> Trans. (Mann W930/14)..... <b>BT9318</b> Steering (153468)..... <b>P106-HD</b> Hyd. (Mann H929/3)..... <b>PT9374</b>	Serie R R250 w/DC09 (Euro 6) Eng. (10/13-on) Lube (1742037)..... <b>P7502</b> Fuel (1736248)..... <b>PF9829 KIT</b> Cab Air (1770813)..... <b>PA5493</b> Air Dryer (1774598)..... <b>BA5378</b> Trans. (1301696)..... <b>BT9318</b> Steering (153468)..... <b>P106-HD</b> Hyd. (1329876)..... <b>PT9374</b>	Serie R R280 w/DC09 (Euro 6) Eng. (10/13-on) Lube (1742037)..... <b>P7502</b> Fuel (1736248)..... <b>PF9829 KIT</b> Cab Air (1770813)..... <b>PA5493</b> Air Dryer (1774598)..... <b>BA5378</b> Trans. (1301696)..... <b>BT9318</b> Steering (153468)..... <b>P106-HD</b> Hyd. (1329876)..... <b>PT9374</b>
Serie 4 R164 Lube..... <b>P7319</b> Fuel..... <b>PF7896</b> Radial Seal Air (Don. Air System) (1421021)..... <b>RS3726</b> Radial Seal Air (Knecht Air System) (1387548)..... <b>RS4638 +</b> Cab Air..... <b>PA4938</b> Air Dryer..... <b>BA5375</b> Steering..... <b>P106-HD</b> Gearbox..... <b>BT9318</b> Retarder..... <b>PT9374</b>	Serie R R270 w/DC9 12-270 (Euro3) Eng. (06/04-on) Lube (Standard Vers.)..... <b>B76</b> Fuel/Water Separator (1393640)..... <b>BF46083-O</b> Fuel (1411894)..... <b>BF7908</b> Radial Seal Air (Don. Air System) (Replacement Element) (1728667)..... <b>RS30142</b> Radial Seal Air (Don. Air System) (Initial Installation) (1728667)..... <b>RS30142 KIT</b> Radial Seal Air (Plastic End Cap)..... <b>RS30142 KIT</b> Radial Seal Air (Mahle/Knecht Air System)..... <b>RS4963</b> 19.8 mm Height Cab Air (1913500)..... <b>PA5493</b> 69.1 mm Height Cab Air (1420197)..... <b>PA4938</b> Air Dryer (Mann TB1374/3X)..... <b>BA5375</b> Trans. (1301696)..... <b>BT9318</b> Steering..... <b>P106-HD</b> Retarder (1381235)..... <b>PT9374</b>	Serie R R310 w/DC9 11-310 (Euro3) Eng. (06/04-on) Lube (Standard Vers.)..... <b>B76</b> Fuel/Water Separator (1393640)..... <b>BF46083-O</b> Fuel (1411894)..... <b>BF7908</b> Radial Seal Air (Don. Air System) (Replacement Element) (1728667)..... <b>RS30142</b> Radial Seal Air (Don. Air System) (Initial Installation) (1728667)..... <b>RS30142 KIT</b> Radial Seal Air (Plastic End Cap)..... <b>RS30142 KIT</b> Radial Seal Air (Mahle/Knecht Air System)..... <b>RS4963</b> 19.8 mm Height Cab Air (1913500)..... <b>PA5493</b> 69.1 mm Height Cab Air (1420197)..... <b>PA4938</b> Air Dryer (Mann TB1374/3X)..... <b>BA5375</b> Trans. (1301696)..... <b>BT9318</b> Steering..... <b>P106-HD</b> Retarder (1381235)..... <b>PT9374</b>
Serie R R230 w/DC9 13-230 (Euro3) Eng. (06/04-on) Lube (Standard Vers.)..... <b>B76</b> Fuel/Water Separator (1393640)..... <b>BF46083-O</b> Fuel (1411894)..... <b>BF7908</b> Radial Seal Air (Don. Air System) (Replacement Element) (1728667)..... <b>RS30142</b> Radial Seal Air (Don. Air System) (Initial Installation) (1728667)..... <b>RS30142 KIT</b> Radial Seal Air (Plastic End Cap)..... <b>RS30142 KIT</b> Radial Seal Air (Mahle/Knecht Air System)..... <b>RS4963</b> 19.8 mm Height Cab Air (1913500)..... <b>PA5493</b> 69.1 mm Height Cab Air (1420197)..... <b>PA4938</b> Air Dryer (Mann TB1374/3X)..... <b>BA5375</b> Trans. (1301696)..... <b>BT9318</b> Steering..... <b>P106-HD</b> Retarder (1381235)..... <b>PT9374</b>	Serie R R270 w/DC9 12-270 (Euro3) Eng. (06/04-on) Lube (Standard Vers.)..... <b>B76</b> Fuel/Water Separator (1393640)..... <b>BF46083-O</b> Fuel (1411894)..... <b>BF7908</b> Radial Seal Air (Don. Air System) (Replacement Element) (1728667)..... <b>RS30142</b> Radial Seal Air (Don. Air System) (Initial Installation) (1728667)..... <b>RS30142 KIT</b> Radial Seal Air (Plastic End Cap)..... <b>RS30142 KIT</b> Radial Seal Air (Mahle/Knecht Air System)..... <b>RS4963</b> 19.8 mm Height Cab Air (1913500)..... <b>PA5493</b> 69.1 mm Height Cab Air (1420197)..... <b>PA4938</b> Air Dryer (Mann TB1374/3X)..... <b>BA5375</b> Trans. (1301696)..... <b>BT9318</b> Steering..... <b>P106-HD</b> Retarder (1381235)..... <b>PT9374</b>	Serie R R310 w/DC9 18-310 (Euro4) Eng. (10/05-on) Lube (Standard Vers.)..... <b>B76</b> Fuel/Water Separator (1393640)..... <b>BF46083-O</b> Fuel (1459762)..... <b>PF7936</b> Radial Seal Air (Don. Air System) (Replacement Element) (1728667)..... <b>RS30142</b> Radial Seal Air (Don. Air System) (Initial Installation) (1728667)..... <b>RS30142 KIT</b> Radial Seal Air (Plastic End Cap)..... <b>RS30142 KIT</b> Radial Seal Air (Mahle/Knecht Air System)..... <b>RS4963</b> 19.8 mm Height Cab Air (1913500)..... <b>PA5493</b> 69.1 mm Height Cab Air (1420197)..... <b>PA4938</b> Air Dryer (Mann TB1394/3X)..... <b>BA5378</b> Trans. (1301696)..... <b>BT9318</b>
Serie R R230 w/DC9 16-230 (Euro4) Eng. (10/05-on) Lube (Standard Vers.)..... <b>B76</b> Fuel/Water Separator (1393640)..... <b>BF46083-O</b> Fuel (1459762)..... <b>PF7936</b> Radial Seal Air (Don. Air System) (Replacement Element) (1728667)..... <b>RS30142</b> Radial Seal Air (Don. Air System)..... <b>RS3724</b>	Serie R R270 w/DC9 17-270 (Euro4) Eng. (10/05-on) Lube (Standard Vers.)..... <b>B76</b> Fuel/Water Separator (1393640)..... <b>BF46083-O</b> Fuel (1459762)..... <b>PF7936</b> Radial Seal Air (Don. Air System) (Replacement Element) (1728667)..... <b>RS30142</b> Radial Seal Air (Don. Air System) (Initial Installation) (1728667)..... <b>RS30142 KIT</b> Radial Seal Air (Plastic End Cap)..... <b>RS30142 KIT</b> Radial Seal Air (Mahle/Knecht Air System)..... <b>RS4963</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

SCANIA Trucks (cont'd)	SCANIA Trucks (cont'd)	SCANIA Trucks (cont'd)
Serie R R310 w/DC9 18-310 (Euro4) Eng. (10/05-on) (Cont'd)	Serie R R360 w/DC13 06-360 (Euro5) Eng. (10/07-on) (Cont'd)	Serie R R380 w/DC12 13-380 (Euro4) Eng. (10/05-on) (Cont'd)
Steering..... P106-HD	19.8 mm Height Cab Air (1913500)..... PA5493	19.8 mm Height Cab Air (1913500)..... PA5493
Retarder (1381235)..... PT9374	69.1 mm Height Cab Air..... PA4938	69.1 mm Height Cab Air (1420197)..... PA4938
Serie R R320 w/DC09 (Euro 6) Eng. (10/13-on)	Air Dryer (1774598)..... BA5378	Air Dryer (Mann TB1394/3X)..... BA5378
Lube (1742037)..... P7502	Steering..... P106-HD	Trans. (1301696)..... BT9318
Fuel (1736248)..... PF9829 KIT	Retarder..... PT9374	Steering..... P106-HD
Cab Air (1770813)..... PA5493	Serie R R360 w/DC09 (Euro 6) Eng. (10/13-on)	Retarder (1381235)..... PT9374
Air Dryer (1774598)..... BA5378	Lube (1742037)..... P7502	Serie R R380 w/DC12 13-380 (Euro5) Eng. (09/06-on)
Trans. (1301696)..... BT9318	Fuel (1736248)..... PF9829 KIT	Lube (Standard Vers.)..... B76
Steering (153468)..... P106-HD	Cab Air (1770813)..... PA5493	Fuel/Water Separator (1393640)..... BF46083-O
Hyd. (1329876)..... PT9374	Air Dryer (1774598)..... BA5378	Fuel (1459762)..... PF7936
Serie R R340 w/DC11 (Euro3) Eng. (06/04-on)	Trans. (1301696)..... BT9318	Radial Seal Air (Don. Air System) (Replacement Element) (1728667)..... RS30142
Lube (Standard Vers.)..... B76	Steering (153468)..... P106-HD	Radial Seal O. Air (Don. Air System) (Replacement Element) (1728667)..... RS30142
Fuel/Water Separator (1393640)..... BF46083-O	Hyd. (1329876)..... PT9374	Radial Seal Air (Don. Air System) (Initial Installation) (1728667)..... RS30142 KIT
Fuel (1411894)..... BF7908	Urea Filter (2265672)..... PE17002 KIT	Radial Seal Air (Plastic End Cap)..... RS30142 KIT
Radial Seal Air (Don. Air System) (Replacement Element) (1728667)..... RS30142	Serie R R370 w/DC13 (Euro 6) Eng. (10/13-on)	Radial Seal Air (Mahle/Knecht Air System)..... RS4963
Radial Seal Air (Don. Air System) (Initial Installation) (1728667)..... RS30142 KIT	Lube (1742037)..... P7502	19.8 mm Height Cab Air (1913500)..... PA5493
Radial Seal Air (Plastic End Cap)..... RS30142 KIT	Fuel (1736248)..... PF9829 KIT	69.1 mm Height Cab Air..... PA4938
Radial Seal Air (Mahle/Knecht Air System)..... RS4963	Cab Air (1770813)..... PA5493	Air Dryer (Mann TB1374/3X)..... BA5375
19.8 mm Height Cab Air (1913500)..... PA5493	Air Dryer (1774598)..... BA5378	Trans. (1301696)..... BT9318
69.1 mm Height Cab Air..... PA4938	Trans. (1301696)..... BT9318	Steering..... P106-HD
Air Dryer (Mann TB1374/3X)..... BA5375	Steering (153468)..... P106-HD	Retarder (1381235)..... PT9374
Trans. (1301696)..... BT9318	Hyd. (1329876)..... PT9374	Serie R R340 w/DC12 (Euro4) Eng. (10/05-on)
Steering..... P106-HD	Serie R R380 w/DC11 (Euro 3) Eng. (06/04-on)	Lube (Standard Vers.)..... B76
Retarder (1381235)..... PT9374	Lube (Standard Vers.)..... B76	Fuel/Water Separator (1393640)..... BF46083-O
Serie R R340 w/DC12 (Euro4) Eng. (10/05-on)	Fuel/Water Separator (1393640)..... BF46083-O	Fuel (1411894)..... BF7908
Lube (Standard Vers.)..... B76	Fuel (1411894)..... BF7908	Radial Seal Air (Don. Air System) (Replacement Element) (1728667)..... RS30142
Fuel/Water Separator (1393640)..... BF46083-O	Radial Seal Air (Don. Air System) (Initial Installation) (1728667)..... RS30142 KIT	Radial Seal Air (Don. Air System) (Initial Installation) (1728667)..... RS30142 KIT
Fuel (1459762)..... PF7936	Radial Seal Air (Plastic End Cap)..... RS30142 KIT	Radial Seal Air (Mahle/Knecht Air System)..... RS4963
Radial Seal Air (Don. Air System) (Replacement Element) (1728667)..... RS30142	Radial Seal Air (Mahle/Knecht Air System)..... RS4963	19.8 mm Height Cab Air (1913500)..... PA5493
Radial Seal Air (Don. Air System) (Initial Installation) (1728667)..... RS30142 KIT	19.8 mm Height Cab Air (1913500)..... PA5493	69.1 mm Height Cab Air..... PA4938
Radial Seal Air (Plastic End Cap)..... RS30142 KIT	69.1 mm Height Cab Air..... PA4938	Air Dryer (Mann TB1374/3X)..... BA5375
Radial Seal Air (Mahle/Knecht Air System)..... RS4963	Air Dryer (Mann TB1374/3X)..... BA5375	Trans. (1301696)..... BT9318
19.8 mm Height Cab Air (1913500)..... PA5493	Trans. (1301696)..... BT9318	Steering..... P106-HD
69.1 mm Height Cab Air (1420197)..... PA4938	Steering..... P106-HD	Retarder (1381235)..... PT9374
Air Dryer (Mann TB1394/3X)..... BA5378	Retarder (1381235)..... PT9374	Serie R R400 w/DC13 05-400 (Euro5) Eng. (10/07-on)
Trans. (1301696)..... BT9318	Serie R R380 w/DC12 13-380 (Euro4) Eng. (10/05-on)	Lube (1742037)..... P7502
Steering..... P106-HD	Lube (Standard Vers.)..... B76	Fuel/Water Separator (1393640)..... BF46083-O
Retarder (1381235)..... PT9374	Fuel/Water Separator (1393640)..... BF46083-O	Fuel (1794863)..... PF9829 KIT
Serie R R360 w/DC13 06-360 (Euro5) Eng. (10/07-on)	Fuel (1459762)..... PF7936	Radial Seal Air (1869993)..... RS30142 KIT
Lube (1742037)..... P7502	Radial Seal Air (Don. Air System) (Replacement Element) (1728667)..... RS30142	19.8 mm Height Cab Air (1913500)..... PA5493
Fuel/Water Separator (1393640)..... BF46083-O	Radial Seal Air (Don. Air System) (Initial Installation) (1728667)..... RS30142 KIT	69.1 mm Height Cab Air..... PA4938
Fuel (1794863)..... PF9829 KIT	Radial Seal Air (Plastic End Cap)..... RS30142 KIT	Air Dryer..... BA5375
Radial Seal Air (1869993)..... RS30142 KIT	Radial Seal Air (Mahle/Knecht Air System)..... RS4963	Steering..... P106-HD
Serie R R360 w/DC13 06-360 (Euro5) Eng. (10/07-on)	Serie R R380 w/DC12 13-380 (Euro4) Eng. (10/05-on)	Retarder..... PT9374
Lube (1742037)..... P7502	Lube (Standard Vers.)..... B76	Serie R R410 w/DC13 (Euro 6) Eng. (10/13-on)
Fuel/Water Separator (1393640)..... BF46083-O	Fuel/Water Separator (1393640)..... BF46083-O	Lube (1742037)..... P7502
Fuel (1794863)..... PF9829 KIT	Fuel (1459762)..... PF7936	Fuel (1736248)..... PF9829 KIT
Radial Seal Air (1869993)..... RS30142 KIT	Radial Seal Air (Don. Air System) (Replacement Element) (1728667)..... RS30142	Cab Air (1770813)..... PA5493
Serie R R360 w/DC13 06-360 (Euro5) Eng. (10/07-on)	Radial Seal Air (Don. Air System) (Initial Installation) (1728667)..... RS30142 KIT	Air Dryer (1774598)..... BA5378
Lube (1742037)..... P7502	Radial Seal Air (Plastic End Cap)..... RS30142 KIT	Trans. (1301696)..... BT9318
Fuel/Water Separator (1393640)..... BF46083-O	Radial Seal Air (Mahle/Knecht Air System)..... RS4963	Steering (153468)..... P106-HD
Fuel (1794863)..... PF9829 KIT	Serie R R420 w/DC12 14-420 (Euro3) Eng. (06/04-on)	Hyd. (1329876)..... PT9374
Radial Seal Air (1869993)..... RS30142 KIT	Lube (Standard Vers.)..... B76	Serie R R420 w/DC12 14-420 (Euro3) Eng. (06/04-on)
Serie R R360 w/DC13 06-360 (Euro5) Eng. (10/07-on)	Fuel/Water Separator (1393640)..... BF46083-O	Lube (Standard Vers.)..... B76
Lube (1742037)..... P7502	Fuel (1411894)..... BF7908	Fuel/Water Separator (1393640)..... BF46083-O
Fuel/Water Separator (1393640)..... BF46083-O	Radial Seal Air (Don. Air System) (Replacement Element) (1728667)..... RS30142	Fuel (1411894)..... BF7908
Fuel (1794863)..... PF9829 KIT	Radial Seal Air (Don. Air System) (Initial Installation) (1728667)..... RS30142 KIT	Radial Seal Air (Don. Air System) (Replacement Element) (1728667)..... RS30142
Radial Seal Air (1869993)..... RS30142 KIT	Radial Seal Air (Plastic End Cap)..... RS30142 KIT	
	Radial Seal Air (Mahle/Knecht Air System)..... RS4963	


Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

**Trucks & Buses Applications** **BALDWIN FILTERS**

SCANIA Trucks (cont'd)	SCANIA Trucks (cont'd)	SCANIA Trucks (cont'd)
Serie R R420 w/DC12 14-420 (Euro3) Eng. (06/04-on) (Cont'd)	Serie R R440 w/DC13 10-440 (Euro5) Eng. (10/07-on)	Serie R R470 w/DT12 03-470 (Euro4) Eng. (10/05-on) (Cont'd)
Radial Seal Air (Don. Air System) RS3724	Lube (1742037)..... P7502	Retarder (1381235)..... PT9374
Radial Seal Air (Don. Air System) (Initial Installation) (1728667)..... RS30142 KIT	Fuel/Water Separator (1393640) BF46083-O	Serie R R470 w/DT12 06-470 (Euro3) Eng. (06/04-on)
Radial Seal Air (Plastic End Cap) RS30142 KIT	Fuel (1794863)..... PF9829 KIT	Lube (Standard Vers.)..... B76
Radial Seal Air (Mahle/Knecht Air System)..... RS4963	Radial Seal Air (1869993)..... RS30142 KIT	Fuel/Water Separator (1393640) BF46083-O
19.8 mm Height Cab Air (1913500)..... PA5493	19.8 mm Height Cab Air (1913500)..... PA5493	Fuel (1459762)..... PF7936
69.1 mm Height Cab Air (1420197)..... PA4938	69.1 mm Height Cab Air..... PA4938	Radial Seal Air (Don. Air System) (Replacement Element) (1728667)..... RS30142
Air Dryer (Mann TB1374/3X)..... BA5375	Air Dryer (1774598)..... BA5378	Radial Seal Air (Don. Air System) (Initial Installation) (1728667)..... RS30142 KIT
Trans. (1301696)..... BT9318	Steering..... P106-HD	Radial Seal Air (Plastic End Cap) RS30142 KIT
Steering..... P106-HD	Retarder..... PT9374	Radial Seal Air (Mahle/Knecht Air System)..... RS4963
Retarder (1381235)..... PT9374	R440 w/DC13 (Euro6) Eng. (2012-on)	19.8 mm Height Cab Air (1913500)..... PA5493
Serie R R420 w/DC12 15-420 (Euro5) Eng. (02/06-on)	Lube (2022275)..... P7502	69.1 mm Height Cab Air (1420197)..... PA4938
Lube (Standard Vers.)..... B76	Fuel..... PF9829 KIT	Air Dryer (Mann TB1374/3X)..... BA5375
Fuel/Water Separator (1393640) BF46083-O	Radial Seal Air..... RS30142 KIT	Trans. (1301696)..... BT9318
Fuel (1459762)..... PF7936	Cab Air..... PA5493	Steering..... P106-HD
Radial Seal Air (Don. Air System) (Replacement Element) (1728667) RS30142	Air Dryer..... BA5378	Retarder (1381235)..... PT9374
Radial Seal Air (Don. Air System) (Initial Installation) (1728667)..... RS30142 KIT	Trans. (1301696)..... BT9318	Serie R R450 w/DC13 (Euro6) Eng. (2016-on)
Radial Seal Air (Plastic End Cap) RS30142 KIT	Steering (153468)..... P106-HD	Lube (1742037)..... P7502
Radial Seal Air (Mahle/Knecht Air System)..... RS4963	Hyd. (Retarder) (1329876)..... PT9374	Fuel Kit (1736250)..... PF9829 KIT
19.8 mm Height Cab Air (1913500)..... PA5493	Urea Filter (2265672)..... PE17002 KIT	Air Dryer (1774598)..... BA5378
69.1 mm Height Cab Air (1420197)..... PA4938	Serie R R450 w/DC13 (Euro 6) Eng. (10/13-on)	Air Dryer (Haldex) (1393551)..... BA16000
Air Dryer (Mann TB1394/3X)..... BA5378	Lube (1742037)..... P7502	Trans. (1301696)..... BT9318
Trans. (1301696)..... BT9318	Fuel (1736248)..... PF9829 KIT	Steering (153468)..... P106-HD
Steering..... P106-HD	Cab Air (1770813)..... PA5493	Hyd. (1329876)..... PT9374
Retarder (1381235)..... PT9374	Air Dryer (1774598)..... BA5378	Serie R R470 w/DT12 03-470 (Euro4) Eng. (10/05-on)
Serie R R420 w/DT12 12-420 (Euro4) Eng. (06/04-on)	Trans. (1301696)..... BT9318	Lube (Standard Vers.)..... B76
Lube (Standard Vers.)..... B76	Steering (153468)..... P106-HD	Fuel/Water Separator (1393640) BF46083-O
Fuel/Water Separator (1393640) BF46083-O	Hyd. (1329876)..... PT9374	Fuel (1459762)..... PF7936
Fuel (1459762)..... PF7936	Serie R R470 w/DT12 03-470 (Euro4) Eng. (10/05-on)	Radial Seal Air..... RS30142 KIT
Radial Seal Air (Don. Air System) (Replacement Element) (1728667) RS30142	Lube (Standard Vers.)..... B76	Cab Air..... PA5493
Radial Seal Air (Don. Air System) (Initial Installation) (1728667)..... RS30142 KIT	Fuel/Water Separator (1393640) BF46083-O	Air Dryer..... BA5378
Radial Seal Air (Don. Air System) (Replacement Element) (1728667)..... RS30142	Fuel (1459762)..... PF7936	Trans..... BT9318
Radial Seal Air (Plastic End Cap) RS30142 KIT	Radial Seal Air (Don. Air System) (Replacement Element) (1728667) RS30142	Steering..... P106-HD
Radial Seal Air (Mahle/Knecht Air System)..... RS4963	Radial Seal Air (Don. Air System) (Initial Installation) (1728667)..... RS30142 KIT	Retarder..... PT9374
19.8 mm Height Cab Air (1913500)..... PA5493	Radial Seal Air (Plastic End Cap) RS30142 KIT	R480 w/DC13 (Euro6) Eng. (2012-on)
69.1 mm Height Cab Air (1420197)..... PA4938	Radial Seal Air (Mahle/Knecht Air System)..... RS4963	Lube (2022275)..... P7502
Air Dryer (Mann TB1374/3X)..... BA5375	69.1 mm Height Cab Air (1420197)..... PA4938	Fuel..... PF9829 KIT
Trans. (1301696)..... BT9318	19.8 mm Height Cab Air (1913500)..... PA5493	Radial Seal Air..... RS30142 KIT
Steering..... P106-HD	Air Dryer (Mann TB1394/3X)..... BA5378	Cab Air..... PA5493
Retarder (1381235)..... PT9374	Trans. (1301696)..... BT9318	Air Dryer..... BA5378
Serie R R420 w/DT12 12-420 (Euro4) Eng. (06/04-on)	Steering..... P106-HD	Trans..... BT9318
Lube (Standard Vers.)..... B76	Serie R R470 w/DT12 03-470 (Euro4) Eng. (10/05-on)	Steering..... P106-HD
Fuel/Water Separator (1393640) BF46083-O	Lube (Standard Vers.)..... B76	Retarder..... PT9374
Fuel (1459762)..... PF7936	Fuel/Water Separator (1393640) BF46083-O	Serie R R480 w/DT12 17-480 (Euro4) Eng. (09/06-on)
Radial Seal Air (Don. Air System) (Replacement Element) (1728667) RS30142	Fuel (1459762)..... PF7936	Lube (Standard Vers.)..... B76
Radial Seal Air (Don. Air System) (Initial Installation) (1728667)..... RS30142 KIT	Radial Seal Air (Don. Air System) (Replacement Element) (1728667) RS30142	Fuel/Water Separator (1393640) BF46083-O
Radial Seal Air (Don. Air System) (Initial Installation) (1728667)..... RS30142 KIT	Radial Seal Air (Don. Air System) (Initial Installation) (1728667)..... RS30142 KIT	Fuel (1459762)..... PF7936
Radial Seal Air (Plastic End Cap) RS30142 KIT	Radial Seal Air (Plastic End Cap) RS30142 KIT	Radial Seal Air (Don. Air System) (Replacement Element) (1728667) RS30142
Radial Seal Air (Mahle/Knecht Air System)..... RS4963	Radial Seal Air (Mahle/Knecht Air System)..... RS4963	Radial Seal Air (Don. Air System) (Replacement Element) (1728667) RS30142
19.8 mm Height Cab Air (1913500)..... PA5493	69.1 mm Height Cab Air (1420197)..... PA4938	Radial Seal Air (Don. Air System) (Initial Installation) (1728667)..... RS30142 KIT
69.1 mm Height Cab Air (1420197)..... PA4938	19.8 mm Height Cab Air (1913500)..... PA5493	Radial Seal Air (Plastic End Cap) RS30142 KIT
Air Dryer (Mann TB1374/3X)..... BA5375	Air Dryer (Mann TB1394/3X)..... BA5378	Radial Seal Air (Mahle/Knecht Air System)..... RS4963
Trans. (1301696)..... BT9318	Trans. (1301696)..... BT9318	
Steering..... P106-HD	Steering..... P106-HD	
Retarder (1381235)..... PT9374		

Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).




SCANIA Trucks (cont'd)	SCANIA Trucks (cont'd)	SCANIA Trucks (cont'd)
<b>Serie R R480 w/DT12 17-480 (Euro4) Eng. (09/06-on) (Cont'd)</b> <b>19.8 mm Height Cab Air</b> (1913500)..... <b>PA5493</b> <b>69.1 mm Height Cab Air</b> ..... <b>PA4938</b> <b>Air Dryer</b> (Mann TB1394/3X)..... <b>BA5378</b> <b>Trans</b> ..... <b>BT9318</b> <b>Steering</b> ..... <b>P106-HD</b> <b>Retarder</b> (1381235)..... <b>PT9374</b>	<b>Serie R R500 w/DC16 06-500 (Euro4) Eng. (02/06-on) (Cont'd)</b> <b>Radial Seal I. Air</b> (Don. Air System)..... <b>RS5313</b> <b>Single Radial Seal Air</b> (Don. Air System) (1st Install) (1728817)..... <b>RS30143 KIT<sup>90</sup></b> <b>Single Radial Seal Air</b> (Don. Air System) (Replacement Ele.) (1728817)..... <b>RS30143<sup>90</sup></b> <b>Radial Seal Air</b> (Mahle/Knecht Air System)..... <b>RS4638 +</b> <b>19.8 mm Height Cab Air</b> (1913500)..... <b>PA5493</b> <b>69.1 mm Height Cab Air</b> (1420197)..... <b>PA4938</b> <b>Air Dryer</b> (Mann TB1394/3X)..... <b>BA5378</b> <b>Trans</b> ..... <b>BT9318</b> <b>Steering</b> ..... <b>P106-HD</b> <b>Retarder</b> (1381235)..... <b>PT9374</b>	<b>Serie R R520 w/DC13 (Euro 6) Eng. (10/13-on) (Cont'd)</b> <b>Hyd.</b> (1329876)..... <b>PT9374</b> <b>Serie R R560 w/DC16 05-560 (Euro4) Eng. (02/06-on)</b> <b>Lube</b> (1439036)..... <b>P7319</b> <b>Fuel/Water Separator</b> (1393640)..... <b>BF46083-O</b> <b>Fuel</b> ..... <b>PF7896</b> <b>Radial Seal O. Air</b> (Don. Air System)..... <b>RS3726</b> <b>Radial Seal I. Air</b> (Don. Air System)..... <b>RS5313</b> <b>Single Radial Seal Air</b> (Don. Air System) (1st Install) (1728817)..... <b>RS30143 KIT<sup>90</sup></b> <b>Single Radial Seal Air</b> (Don. Air System) (Replacement Ele.) (1728817)..... <b>RS30143<sup>90</sup></b> <b>Radial Seal Air</b> (Mahle/Knecht Air System)..... <b>RS4638 +</b> <b>19.8 mm Height Cab Air</b> (1913500)..... <b>PA5493</b> <b>69.1 mm Height Cab Air</b> (1420197)..... <b>PA4938</b> <b>Air Dryer</b> (Mann TB1394/3X)..... <b>BA5378</b> <b>Trans.</b> (1301696)..... <b>BT9318</b> <b>Steering</b> ..... <b>P106-HD</b> <b>Retarder</b> (1381235)..... <b>PT9374</b>
<b>Serie R R490 w/DC13 (Euro 6) Eng. (10/13-on)</b> <b>Lube</b> (1742037)..... <b>P7502</b> <b>Fuel</b> (1736248)..... <b>PF9829 KIT</b> <b>Cab Air</b> (1770813)..... <b>PA5493</b> <b>Air Dryer</b> (1774598)..... <b>BA5378</b> <b>Trans.</b> (1301696)..... <b>BT9318</b> <b>Steering</b> (153468)..... <b>P106-HD</b> <b>Hyd.</b> (1329876)..... <b>PT9374</b>	<b>Serie R R500 w/DC16 09-500 (Euro5) Eng. (05/06-on)</b> <b>Lube</b> (1439036)..... <b>P7319</b> <b>Fuel/Water Separator</b> (1393640)..... <b>BF46083-O</b> <b>Fuel</b> ..... <b>PF7896</b> <b>Radial Seal O. Air</b> (Don. Air System)..... <b>RS3726</b> <b>Radial Seal I. Air</b> (Don. Air System)..... <b>RS5313</b> <b>Single Radial Seal Air</b> (Don. Air System) (1st Install) (1728817)..... <b>RS30143 KIT<sup>90</sup></b> <b>Single Radial Seal Air</b> (Don. Air System) (Replacement Ele.) (1728817)..... <b>RS30143<sup>90</sup></b> <b>Radial Seal Air</b> (Mahle/Knecht Air System)..... <b>RS4638 +</b> <b>19.8 mm Height Cab Air</b> (1913500)..... <b>PA5493</b> <b>69.1 mm Height Cab Air</b> (1420197)..... <b>PA4938</b> <b>Air Dryer</b> (Mann TB1374/3X)..... <b>BA5375</b> <b>Trans</b> ..... <b>BT9318</b> <b>Steering</b> ..... <b>P106-HD</b> <b>Retarder</b> (1381235)..... <b>PT9374</b>	<b>Serie R R560 w/DC16 18-560 (Euro5) Eng. (10/07-on)</b> <b>Lube</b> (1439036)..... <b>P7319</b> <b>Fuel/Water Separator</b> (1393640)..... <b>BF46083-O</b> <b>Fuel</b> ..... <b>PF7896</b> <b>Radial Seal O. Air</b> (Don. Air System)..... <b>RS3726</b> <b>Radial Seal I. Air</b> (Don. Air System)..... <b>RS5313</b> <b>Single Radial Seal Air</b> (Don. Air System) (1st Install) (1728817)..... <b>RS30143 KIT<sup>90</sup></b> <b>Single Radial Seal Air</b> (Don. Air System) (Replacement Ele.) (1728817)..... <b>RS30143<sup>90</sup></b> <b>Radial Seal Air</b> (Mahle/Knecht Air System)..... <b>RS4638 +</b> <b>19.8 mm Height Cab Air</b> (1913500)..... <b>PA5493</b> <b>69.1 mm Height Cab Air</b> (1420197)..... <b>PA4938</b> <b>Air Dryer</b> (Mann TB1394/3X)..... <b>BA5378</b> <b>Trans.</b> (1301696)..... <b>BT9318</b> <b>Steering</b> ..... <b>P106-HD</b> <b>Retarder</b> (1381235)..... <b>PT9374</b>
<b>Serie R R500 w/DC16 04-500 (Euro3) Eng. (06/04-on)</b> <b>Lube</b> (1439036)..... <b>P7319</b> <b>Fuel/Water Separator</b> (1393640)..... <b>BF46083-O</b> <b>Fuel</b> ..... <b>PF7896</b> <b>Radial Seal O. Air</b> (Don. Air System)..... <b>RS3726</b> <b>Radial Seal I. Air</b> (Don. Air System)..... <b>RS5313</b> <b>Single Radial Seal Air</b> (Don. Air System) (1st Install) (1728817)..... <b>RS30143 KIT<sup>90</sup></b> <b>Single Radial Seal Air</b> (Don. Air System) (Replacement Ele.) (1728817)..... <b>RS30143<sup>90</sup></b> <b>Radial Seal Air</b> (Mahle/Knecht Air System)..... <b>RS4638 +</b> <b>19.8 mm Height Cab Air</b> (1913500)..... <b>PA5493</b> <b>69.1 mm Height Cab Air</b> (1420197)..... <b>PA4938</b> <b>Air Dryer</b> (Mann TB1374/3X)..... <b>BA5375</b> <b>Trans</b> ..... <b>BT9318</b> <b>Steering</b> ..... <b>P106-HD</b> <b>Retarder</b> (1381235)..... <b>PT9374</b>	<b>Serie R R520 w/DC16 (Euro6) Eng. (2016-on)</b> <b>Lube</b> (1439036)..... <b>P7319</b> <b>Fuel Kit</b> (1736250)..... <b>PF9829 KIT</b> <b>Air Dryer</b> (1774598)..... <b>BA5378</b> <b>Air Dryer</b> (Haldex) (1393551)..... <b>BA16000</b> <b>Trans.</b> (1301696)..... <b>BT9318</b> <b>Steering</b> (153468)..... <b>P106-HD</b> <b>Hyd.</b> (Retarder) (1329876)..... <b>PT9374</b> <b>Urea Filter</b> (2265672)..... <b>PE17002 KIT</b>	<b>Serie R R520 w/DC13 (Euro 6) Eng. (10/13-on)</b> <b>Lube</b> (1439036)..... <b>P7319</b> <b>Fuel Kit</b> (1736250)..... <b>PF9829 KIT</b> <b>Air Dryer</b> (1774598)..... <b>BA5378</b> <b>Air Dryer</b> (Haldex) (1393551)..... <b>BA16000</b> <b>Trans.</b> (1301696)..... <b>BT9318</b> <b>Steering</b> (153468)..... <b>P106-HD</b>
<b>Serie R R500 w/DC16 06-500 (Euro4) Eng. (02/06-on)</b> <b>Lube</b> (1439036)..... <b>P7319</b> <b>Fuel/Water Separator</b> (1393640)..... <b>BF46083-O</b> <b>Fuel</b> ..... <b>PF7896</b> <b>Radial Seal O. Air</b> (Don. Air System)..... <b>RS3726</b>	<b>Serie R R520 w/DC16 (Euro6) Eng. (2016-on)</b> <b>Lube</b> (1439036)..... <b>P7319</b> <b>Fuel Kit</b> (1736250)..... <b>PF9829 KIT</b> <b>Air Dryer</b> (1774598)..... <b>BA5378</b> <b>Air Dryer</b> (Haldex) (1393551)..... <b>BA16000</b> <b>Trans.</b> (1301696)..... <b>BT9318</b> <b>Steering</b> (153468)..... <b>P106-HD</b> <b>Hyd.</b> (Retarder) (1329876)..... <b>PT9374</b> <b>Urea Filter</b> (2265672)..... <b>PE17002 KIT</b>	<b>Serie R R580 w/DC16 (Euro6) Eng. (2016-on)</b> <b>Lube</b> (1439036)..... <b>P7319</b> <b>Fuel Kit</b> (1736250)..... <b>PF9829 KIT</b> <b>Air Dryer</b> (1774598)..... <b>BA5378</b> <b>Air Dryer</b> (Haldex) (1393551)..... <b>BA16000</b> <b>Trans.</b> (1301696)..... <b>BT9318</b> <b>Steering</b> (153468)..... <b>P106-HD</b>

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
 Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

SCANIA Trucks (cont'd)	SCANIA Trucks (cont'd)	SCANIA Trucks (cont'd)
Serie R R580 w/DC16 (Euro6) Eng. (2016-on) (Cont'd) Hyd. (Retarder) (1329876)..... PT9374 Urea Filter (2265672)..... PE17002 KIT	Serie R R620 w/DC16 08-620 (Euro4) Eng. (05/06-on) (Cont'd) Radial Seal O. Air (Don. Air System)..... RS3726 Radial Seal I. Air (Don. Air System)..... RS5313 Single Radial Seal Air (Don. Air System) (1st Install) (1728817)..... RS30143 KIT 90 Single Radial Seal Air (Don. Air System) (Replacement Ele.) (1728817)..... RS30143 90 Radial Seal Air (Mahle/Knecht Air System)..... RS4638 + 19.8 mm Height Cab Air (1913500)..... PA5493 69.1 mm Height Cab Air (1420197)..... PA4938 Air Dryer (Mann TB1394/3X)..... BA5378 Trans. (1301696)..... BT9318 Steering..... P106-HD Retarder (1381235)..... PT9374	Serie R R730 w/DC16 21-730 (Euro5 + EEV) Eng. (2010-on) (Cont'd) Fuel/Water Separator (w/o SP)... BF1329 Fuel/Water Separator (w/SP)..... BF1329-SP Fuel/Water Separator (Open End for Bowl)..... BF46083-O Cab Air..... PA5493 Air Dryer..... BA5378 Trans..... BT9318 Steering..... P106-HD Retarder..... PT9374
Serie R R580 w/DC16 (Euro 6) Eng. (10/13-on) Lube (1439036)..... P7319 Fuel Kit (1736250)..... PF9829 KIT Single Radial Seal Air (Don. Air System) (1st Install) (1728817)..... RS30143 KIT 90 Single Radial Seal Air (Don. Air System) (Replacement Ele.) (1728817)..... RS30143 90 Cab Air (1770813)..... PA5493 Air Dryer (1774598)..... BA5378 Air Dryer (Haldex) (1393551)..... BA16000 Trans. (1301696)..... BT9318 Steering (153468)..... P106-HD Hyd. (Retarder) (1329876)..... PT9374 Hyd. (1893214)..... PT9374 Urea Filter (2265672)..... PE17002 KIT	Serie R R620 w/DC16 17-620 (Euro5) Eng. (10/07-on) Lube (1439036)..... P7319 Fuel/Water Separator (1393640)..... BF46083-O Fuel..... PF7896 Radial Seal O. Air (Don. Air System)..... RS3726 Radial Seal I. Air (Don. Air System)..... RS5313 Single Radial Seal Air (Don. Air System) (1st Install) (1728817)..... RS30143 KIT 90 Single Radial Seal Air (Don. Air System) (Replacement Ele.) (1728817)..... RS30143 90 Radial Seal Air (Mahle/Knecht Air System)..... RS4638 + 19.8 mm Height Cab Air (1913500)..... PA5493 69.1 mm Height Cab Air (1420197)..... PA4938 Air Dryer (Mann TB1374/3X)..... BA5375 Trans. (1301696)..... BT9318 Steering..... P106-HD Retarder (1381235)..... PT9374	Serie R R730 w/DC13 (Euro 6) Eng. (10/13-on) Lube (1439036)..... P7319 Fuel (1736248)..... PF9829 KIT Cab Air (1770813)..... PA5493 Air Dryer (1774598)..... BA5378 Trans. (1301696)..... BT9318 Steering (153468)..... P106-HD Hyd. (1329876)..... PT9374 Urea (1795459)..... PE5270
Serie R R580 w/DC13 (Euro 6) Eng. (10/13-on) Lube (1439036)..... P7319 Fuel (1736248)..... PF9829 KIT Cab Air (1770813)..... PA5493 Air Dryer (1774598)..... BA5378 Trans. (1301696)..... BT9318 Steering (153468)..... P106-HD Hyd. (1329876)..... PT9374	Serie R R580 w/DC16 03-580 (Euro3) Eng. (06/04-on) Lube (1439036)..... P7319 Fuel/Water Separator (1393640)..... BF46083-O Fuel..... PF7896 Radial Seal O. Air (Don. Air System)..... RS3726 Radial Seal I. Air (Don. Air System)..... RS5313 Single Radial Seal Air (Don. Air System) (1st Install) (1728817)..... RS30143 KIT 90 Single Radial Seal Air (Don. Air System) (Replacement Ele.) (1728817)..... RS30143 90 Radial Seal Air (Mahle/Knecht Air System)..... RS4638 + 19.8 mm Height Cab Air (1913500)..... PA5493 69.1 mm Height Cab Air (1420197)..... PA4938 Air Dryer (Mann TB1374/3X)..... BA5375 Trans. (1301696)..... BT9318 Steering..... P106-HD Retarder (1381235)..... PT9374	Serie S S410 w/DC13 (Euro6) Eng. (2016-on) Lube (1742037)..... P7502 Fuel Kit (1736250)..... PF9829 KIT Air Dryer (1774598)..... BA5378 Air Dryer (Haldex) (1393551)..... BA16000 Trans. (1301696)..... BT9318 Steering (153468)..... P106-HD Hyd. (Retarder) (1329876)..... PT9374 Urea Filter (2265672)..... PE17002 KIT
Serie R R620 w/DC16 08-620 (Euro4) Eng. (05/06-on) Lube (1439036)..... P7319 Fuel/Water Separator (1393640)..... BF46083-O Fuel..... PF7896	Serie R R730 w/DC16 (Euro6) Eng. (2016-on) Lube (1439036)..... P7319 Fuel Kit (1736250)..... PF9829 KIT Air Dryer (1774598)..... BA5378 Air Dryer (Haldex) (1393551)..... BA16000 Trans. (1301696)..... BT9318 Steering (153468)..... P106-HD Hyd. (Retarder) (1329876)..... PT9374 Urea Filter (2265672)..... PE17002 KIT	Serie S S450 w/DC13 (Euro6) Eng. (2016-on) Lube (1742037)..... P7502 Fuel Kit (1736250)..... PF9829 KIT Air Dryer (1774598)..... BA5378 Air Dryer (Haldex) (1393551)..... BA16000 Trans. (1301696)..... BT9318 Steering (153468)..... P106-HD Hyd. (Retarder) (1329876)..... PT9374 Urea Filter (2265672)..... PE17002 KIT
Serie R R620 w/DC16 08-620 (Euro4) Eng. (05/06-on) Lube (1439036)..... P7319 Fuel/Water Separator (1393640)..... BF46083-O Fuel..... PF7896	Serie R R730 w/DC16 21-730 (Euro5 + EEV) Eng. (2010-on) Lube..... P7319 Fuel (2003505)..... PF9829 KIT	Serie S S500 w/DC13 (Euro6) Eng. (2016-on) Lube (1742037)..... P7502 Fuel Kit (1736250)..... PF9829 KIT Air Dryer (1774598)..... BA5378 Air Dryer (Haldex) (1393551)..... BA16000 Trans. (1301696)..... BT9318 Steering (153468)..... P106-HD Hyd. (Retarder) (1329876)..... PT9374 Urea Filter (2265672)..... PE17002 KIT
Serie R R620 w/DC16 08-620 (Euro4) Eng. (05/06-on) Lube (1439036)..... P7319 Fuel/Water Separator (1393640)..... BF46083-O Fuel..... PF7896	Serie R R730 w/DC16 21-730 (Euro6) Eng. (2016-on) Lube (1439036)..... P7319 Fuel Kit (1736250)..... PF9829 KIT Air Dryer (1774598)..... BA5378 Air Dryer (Haldex) (1393551)..... BA16000 Trans. (1301696)..... BT9318 Steering (153468)..... P106-HD Hyd. (Retarder) (1329876)..... PT9374 Urea Filter (2265672)..... PE17002 KIT	Serie S S520 w/DC16 (Euro6) Eng. (2016-on) Lube (1439036)..... P7319 Fuel Kit (1736250)..... PF9829 KIT Air Dryer (1774598)..... BA5378 Air Dryer (Haldex) (1393551)..... BA16000 Trans. (1301696)..... BT9318 Steering (153468)..... P106-HD Hyd. (Retarder) (1329876)..... PT9374 Urea Filter (2265672)..... PE17002 KIT

+ See Product Guide for Variations of This Number. 90 Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

SCANIA Trucks (cont'd)	SCANIA Trucks (cont'd)	SCANIA Trucks (cont'd)
<p>Serie S S580 w/DC16 (Euro6) Eng. (2016-on)</p> <p>Lube (1439036)..... P7319</p> <p>Fuel Kit (1736250)..... PF9829 KIT</p> <p>Air Dryer (1774598)..... BA5378</p> <p>Air Dryer (Haldex) (1393551)..... BA16000</p> <p>Trans. (1301696)..... BT9318</p> <p>Steering (153468)..... P106-HD</p> <p>Hyd. (Retarder) (1329876)..... PT9374</p> <p>Urea Filter (2265672)..... PE17002 KIT</p> <hr/> <p>Serie S S730 w/DC16 (Euro6) Eng. (2016-on)</p> <p>Lube (1439036)..... P7319</p> <p>Fuel Kit (1736250)..... PF9829 KIT</p> <p>Air Dryer (1774598)..... BA5378</p> <p>Air Dryer (Haldex) (1393551)..... BA16000</p> <p>Trans. (1301696)..... BT9318</p> <p>Steering (153468)..... P106-HD</p> <p>Hyd. (Retarder) (1329876)..... PT9374</p> <p>Urea Filter (2265672)..... PE17002 KIT</p> <hr/> <p>T82 w/DN8, DS8 Engs.</p> <p>Lube (w/Turbo) (173171)..... B229</p> <p>123.0 mm Fuel (364624)..... BF988 +</p> <p>155.6 mm Some Fuel (343144).... BF587</p> <p>472.3 mm O. Air (370754)..... PA2801</p> <p>Coolant (378396)..... BW5139</p> <hr/> <p>Serie 4 T94 w/DC9 (Euro2) Eng. (10/96-10/04)</p> <p>Lube (Standard Vers.) (Mann W11102/14)..... B76</p> <p>Fuel/Water Separator (1393640)..... BF46083-O</p> <p>Fuel (1372444)..... BF7624</p> <p>Radial Seal Air (Don. Air System) (Replacement Element) (1728667) RS30142</p> <p>Radial Seal O. Air (Don. Air System) (Mann C301240)..... RS3724</p> <p>Radial Seal Air (Don. Air System) (Initial Installation) (1728667)..... RS30142 KIT</p> <p>Radial Seal Air (Plastic End Cap) RS30142 KIT</p> <p>Radial Seal Air (Mahle/Knecht Air System)..... RS4963</p> <p>Cab Air (1420197)..... PA4938</p> <p>Air Dryer (Mann TB1374/3X)..... BA5375</p> <p>Trans..... BT9318</p> <p>Steering (1902137)..... P106-HD</p> <p>Retarder (1381235)..... PT9374</p> <hr/> <p>Serie 4 T94 w/DC9 (Euro 3) Eng. (03/99-10/04)</p> <p>Lube (Standard Vers.)..... B76</p> <p>Fuel/Water Separator (1393640)..... BF46083-O</p> <p>Fuel (1411894)..... BF7908</p> <p>Radial Seal Air (Don. Air System) (Replacement Element) (1728667) RS30142</p> <p>Radial Seal Air (Don. Air System) RS3724</p> <p>Radial Seal Air (Don. Air System) (Initial Installation) (1728667)..... RS30142 KIT</p> <p>Radial Seal Air (Plastic End Cap) RS30142 KIT</p> <p>Radial Seal Air (Mahle/Knecht Air System)..... RS4963</p> <p>Cab Air (1420197)..... PA4938</p> <p>Air Dryer (Mann TB1374/3X)..... BA5375</p> <p>Trans..... BT9318</p>	<p>Serie 4 T94 w/DC9 (Euro 3) Eng. (03/99-10/04) (Cont'd)</p> <p>Steering..... P106-HD</p> <p>Retarder (1381235)..... PT9374</p> <hr/> <p>T112, T112E, T112M w/DN11, DS11 Engs.</p> <p>123.0 mm Fuel (364624)..... BF988 +</p> <p>155.6 mm Some Fuel (343144).... BF587</p> <p>472.3 mm O. Air (370754)..... PA2801</p> <p>Coolant (378396)..... BW5139</p> <hr/> <p>T112 w/DSC1103 Turbo Eng.</p> <p>Lube..... B229</p> <p>Fuel..... [2] BF988 +</p> <p>Opt. Fuel/Water Separator..... BF1221 +</p> <p>O. Std. Air (Don. P181002)..... PA1846 +</p> <p>O. Air (Upgrade) (Don. P181002)..... PA1846XP</p> <p>I. Air (Don. P119372)..... PA1880</p> <hr/> <p>T112H w/DN11 Eng.</p> <p>Fuel (210970)..... BF988 +</p> <p>Opt. Fuel/Water Separator..... BF1221 +</p> <p>472.3 mm Air (261185)..... PA2801</p> <p>492.1 mm Air (309443)..... PA3477</p> <hr/> <p>Serie 4 T114 w/DC11 (Euro3) Eng. (03/98-10/04)</p> <p>Lube (Standard Vers.)..... B76</p> <p>Fuel/Water Separator (1393640)..... BF46083-O</p> <p>Fuel (1411894)..... BF7908</p> <p>Radial Seal Air (Don. Air System) (Replacement Element) (1728667) RS30142</p> <p>Radial Seal Air (Don. Air System) (Initial Installation) (1728667)..... RS30142 KIT</p> <p>Radial Seal Air (Plastic End Cap) RS30142 KIT</p> <p>Radial Seal Air (Mahle/Knecht Air System)..... RS4963</p> <p>Cab Air (1420197)..... PA4938</p> <p>Air Dryer (Mann TB1374/3X)..... BA5375</p> <p>Trans..... BT9318</p> <p>Steering..... P106-HD</p> <p>Retarder (1381235)..... PT9374</p> <hr/> <p>Serie 4 T124 w/DSC12 Eng.</p> <p>Lube (Standard Vers.) (1117285)..... B76</p> <p>Fuel (1372444)..... BF7624</p> <p>446.9 mm Radial Seal Air (1335679)..... RS3724</p> <p>526.3 mm Radial Seal Air (1335678)..... RS3726</p> <p>Coolant..... BW5139</p> <p>Trans. (Mann W930/14)..... BT9318</p> <p>Steering (1902137)..... P106-HD</p> <p>Retarder (1381235)..... PT9374</p> <hr/> <p>R124LA w/DSC12 02 Eng.</p> <p>Fuel/Water Separator (Open End for Bowl) (Mann WK1060/1)..... BF46083-O</p> <p>Fuel/Water Separator (With Bowl) (Mann WK1060/1)..... BF46072</p> <p>Fuel/Water Separator (With Drain) (Mann WK1060/1)..... BF1329</p> <p>Fuel/Water Separator (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... BF1329-SP</p> <p>Fuel/Water Separator (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... BF1339-SP +</p>	<p>R124LA w/DSC12 02 Eng. (Cont'd)</p> <p>Fuel/Water Separator (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... BF1329-SP</p> <p>Fuel/Water Separator (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... BF1339-SP +</p> <hr/> <p>R124LA w/DSC12 02 Eng.</p> <p>Fuel/Water Separator (Open End for Bowl) (Mann WK1060/1)..... BF46083-O</p> <p>Fuel/Water Separator (With Bowl) (Mann WK1060/1)..... BF46072</p> <p>Fuel/Water Separator (With Drain) (Mann WK1060/1)..... BF1329</p> <p>Fuel/Water Separator (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... BF1329-SP</p> <p>Fuel/Water Separator (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... BF1339-SP +</p> <hr/> <p>T143 w/DS14 Eng.</p> <p>Lube (w/Turbo) (173171)..... B229</p> <p>Fuel (364624)..... BF988 +</p> <p>O. Air..... PA3794</p> <p>Coolant (378396)..... BW5139</p> <hr/> <p>T143 w/DSC14 Eng.</p> <p>123.0 mm Fuel (457431326)..... BF988 +</p> <p>155.6 mm Fuel (343144)..... BF587</p> <p>Steering (153468)..... P106-HD</p> <hr/> <p>Serie 4 T144 w/DSC14 Eng.</p> <p>Lube (Standard Vers.) (1117285)..... B76</p> <p>143.7 mm Fuel (1372444)..... BF7624</p> <p>155.6 mm Fuel (w/Drain) (Mann WK842)..... BF587-D +</p> <p>446.9 mm Radial Seal Air (1335679)..... RS3724</p> <p>526.3 mm Radial Seal Air (1335678)..... RS3726</p> <p>Coolant..... BW5139</p> <p>Trans. (Mann W930/14)..... BT9318</p> <p>Steering (1902137)..... P106-HD</p> <p>Hyd. (Mann H929/3)..... PT9374</p> <hr/> <p>Serie T T340 w/DC11 (Euro3) Eng. (09/04-12/05)</p> <p>Lube (Standard Vers.)..... B76</p> <p>Fuel/Water Separator (1393640)..... BF46083-O</p> <p>Fuel (1411894)..... BF7908</p> <p>Radial Seal Air (Don. Air System) (Replacement Element) (1728667) RS30142</p> <p>Radial Seal Air (Don. Air System) RS3724</p> <p>Radial Seal Air (Don. Air System) (Initial Installation) (1728667)..... RS30142 KIT</p> <p>Radial Seal Air (Plastic End Cap) RS30142 KIT</p> <p>Radial Seal Air (Mahle/Knecht Air System)..... RS4963</p> <p>Cab Air (1420197)..... PA4938</p> <p>Air Dryer (Mann TB1374/3X)..... BA5375</p> <p>Trans. (1301696)..... BT9318</p> <p>Steering..... P106-HD</p> <p>Retarder (1381235)..... PT9374</p>


+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

SCANIA Trucks (cont'd)	SCANIA Trucks (cont'd)	SCANIA Trucks (cont'd)
<p>Serie T T380 w/DC11 (Euro 3) Eng. (09/04-12/05)</p> <p>Lube (Standard Vers.)..... B76</p> <p>Fuel/Water Separator (1393640). BF46083-O</p> <p>Fuel (1411894)..... BF7908</p> <p>Radial Seal Air (Don. Air System) (Replacement Element) (1728667) RS30142</p> <p>Radial Seal Air (Don. Air System) RS3724</p> <p>Radial Seal Air (Don. Air System) (Initial Installation) (1728667)..... RS30142 KIT</p> <p>Radial Seal Air (Plastic End Cap) RS30142 KIT</p> <p>Radial Seal Air (Mahle/Knecht Air System)..... RS4963</p> <p>Cab Air (1420197)..... PA4938</p> <p>Air Dryer (Mann TB1374/3X)..... BA5375</p> <p>Trans. (1301696)..... BT9318</p> <p>Steering..... P106-HD</p> <p>Retarder (1381235)..... PT9374</p> <hr/> <p>Serie T T420 w/DC12 14-420 (Euro3) Eng. (09/04-12/05)</p> <p>Lube (Standard Vers.)..... B76</p> <p>Fuel/Water Separator (1393640). BF46083-O</p> <p>Fuel (1411894)..... BF7908</p> <p>Radial Seal Air (Don. Air System) (Replacement Element) (1728667) RS30142</p> <p>Radial Seal Air (Don. Air System) RS3724</p> <p>Radial Seal Air (Don. Air System) (Initial Installation) (1728667)..... RS30142 KIT</p> <p>Radial Seal Air (Plastic End Cap) RS30142 KIT</p> <p>Radial Seal Air (Mahle/Knecht Air System)..... RS4963</p> <p>Cab Air (1420197)..... PA4938</p> <p>Air Dryer (Mann TB1374/3X)..... BA5375</p> <p>Trans. (1301696)..... BT9318</p> <p>Steering..... P106-HD</p> <p>Retarder (1381235)..... PT9374</p> <hr/> <p>Serie T T420 w/DT12 (Euro4) Eng. (09/04-12/05)</p> <p>Lube (Standard Vers.)..... B76</p> <p>Fuel/Water Separator (1393640). BF46083-O</p> <p>Fuel (1459762)..... PF7936</p> <p>Radial Seal Air (Don. Air System) (Replacement Element) (1728667) RS30142</p> <p>Radial Seal Air (Don. Air System) RS3724</p> <p>Radial Seal Air (Don. Air System) (Initial Installation) (1728667)..... RS30142 KIT</p> <p>Radial Seal Air (Plastic End Cap) RS30142 KIT</p> <p>Radial Seal Air (Mahle/Knecht Air System)..... RS4963</p> <p>Cab Air (1420197)..... PA4938</p> <p>Air Dryer (Mann TB1374/3X)..... BA5375</p> <p>Trans. (1301696)..... BT9318</p> <p>Steering..... P106-HD</p> <p>Retarder (1381235)..... PT9374</p> <hr/> <p>Serie T T470 w/DT12 Eng. (09/04-12/05)</p> <p>Lube (Standard Vers.)..... B76</p> <p>Fuel/Water Separator (1393640). BF46083-O</p> <p>Fuel (1459762)..... PF7936</p>	<p>Serie T T470 w/DT12 Eng. (09/04-12/05) (Cont'd)</p> <p>Radial Seal Air (Don. Air System) (Replacement Element) (1728667) RS30142</p> <p>Radial Seal Air (Don. Air System) (Initial Installation) (1728667)..... RS30142 KIT</p> <p>Radial Seal Air (Plastic End Cap) RS30142 KIT</p> <p>Radial Seal Air (Mahle/Knecht Air System)..... RS4963</p> <p>Cab Air (1420197)..... PA4938</p> <p>Air Dryer (Mann TB1374/3X)..... BA5375</p> <p>Trans. (1301696)..... BT9318</p> <p>Steering..... P106-HD</p> <p>Retarder (1381235)..... PT9374</p> <hr/> <p>Serie T T500 w/DC16 (Euro 3) Eng. (09/04-12/05)</p> <p>Lube (1439036)..... P7319</p> <p>Fuel/Water Separator (1393640). BF46083-O</p> <p>Fuel..... PF7896</p> <p>Radial Seal O. Air (Don. Air System)..... RS3726</p> <p>Radial Seal I. Air (Don. Air System)..... RS5313</p> <p>Single Radial Seal Air (Don. Air System) (1st Install) (1728817)..... RS30143 KIT <sup>90</sup></p> <p>Single Radial Seal Air (Don. Air System) (Replacement Ele.) (1728817)..... RS30143 <sup>90</sup></p> <p>Radial Seal Air (Mahle/Knecht Air System)..... RS4638 +</p> <p>Cab Air (1420197)..... PA4938</p> <p>Air Dryer (Mann TB1374/3X)..... BA5375</p> <p>Trans. (1301696)..... BT9318</p> <p>Steering..... P106-HD</p> <p>Retarder (1381235)..... PT9374</p> <hr/> <p>Serie T T560 w/DC16 18-560 (Euro5) Eng. (10/07-on)</p> <p>Lube..... P7319</p> <p>Fuel/Water Separator (1393640). BF46083-O</p> <p>Fuel..... PF7896</p> <p>Radial Seal O. Air (Don. Air System)..... RS3726</p> <p>Radial Seal I. Air (Don. Air System)..... RS5313</p> <p>Single Radial Seal Air (Don. Air System) (1st Install) (1728817)..... RS30143 KIT <sup>90</sup></p> <p>Single Radial Seal Air (Don. Air System) (Replacement Ele.) (1728817)..... RS30143 <sup>90</sup></p> <p>Radial Seal Air (Mahle/Knecht Air System)..... RS4638 +</p> <p>Cab Air..... PA4938</p> <p>Air Dryer..... BA5375</p> <p>Steering..... P106-HD</p> <p>Retarder..... PT9374</p>	<p>Serie T T580 w/DC16 (Euro 3) Eng. (09/04-12/05)</p> <p>Lube (1439036)..... P7319</p> <p>Fuel/Water Separator (1393640). BF46083-O</p> <p>Fuel..... PF7896</p> <p>Radial Seal O. Air (Don. Air System)..... RS3726</p> <p>Radial Seal I. Air (Don. Air System)..... RS5313</p> <p>Single Radial Seal Air (Don. Air System) (1st Install) (1728817)..... RS30143 KIT <sup>90</sup></p> <p>Single Radial Seal Air (Don. Air System) (Replacement Ele.) (1728817)..... RS30143 <sup>90</sup></p> <p>Radial Seal Air (Mahle/Knecht Air System)..... RS4638 +</p> <p>Cab Air (1420197)..... PA4938</p> <p>Air Dryer (Mann TB1374/3X)..... BA5375</p> <p>Trans. (1301696)..... BT9318</p> <p>Steering..... P106-HD</p> <p>Retarder (1381235)..... PT9374</p> <hr/> <p>Serie T T620 w/DC16 17-620 (Euro5) Eng. (10/07-on)</p> <p>Lube..... P7319</p> <p>Fuel/Water Separator (1393640). BF46083-O</p> <p>Fuel..... PF7896</p> <p>Radial Seal O. Air (Don. Air System)..... RS3726</p> <p>Radial Seal I. Air (Don. Air System)..... RS5313</p> <p>Single Radial Seal Air (Don. Air System) (1st Install) (1728817)..... RS30143 KIT <sup>90</sup></p> <p>Single Radial Seal Air (Don. Air System) (Replacement Ele.) (1728817)..... RS30143 <sup>90</sup></p> <p>Radial Seal Air (Mahle/Knecht Air System)..... RS4638 +</p> <p>Cab Air..... PA4938</p> <p>Air Dryer..... BA5375</p> <p>Steering..... P106-HD</p> <p>Retarder..... PT9374</p> <hr/> <p style="text-align: center;"><b>SEAGRAVE</b> Fire Trucks</p> <p>66</p> <p>Lube..... P42</p> <hr/> <p>500, 900</p> <p>Lube..... P42</p> <p>Fuel..... PF945</p> <hr/> <p>F31, R37 w/IHC RD450 Eng.</p> <p>F-F Lube Ele..... P204</p> <p>B-P Lube Sock..... CU406 <sup>90</sup></p> <hr/> <p style="text-align: center;"><b>SEDDON</b> Trucks</p> <p>Cursor</p> <p>Fuel/Water Separator (1908547). BF1217</p>

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>SEDDON</b> Trucks (cont'd)	<b>SETRA</b> Buses (cont'd)	<b>SOUTHERN COACH</b> Buses
Cursor EuroTrakker MP340E35H Air (C33920/3)..... PA3606	S417 GT-HD w/Mercedes-Benz OM457 Eng. Fuel..... PF7761	Models w/Bendix-Westinghouse Air Compressor Air Comp. Breather..... PA1704
<b>SETRA</b> Buses	S417 HDH w/Mercedes-Benz OM502 Eng. F-F Lube (Mann HU12140x)..... P7192	Models w/Cummins V6-140, V8-185 Eng. Lube..... P998
S313 UL w/Mercedes-Benz OM457 Eng. Fuel (Mann PU999/1x)..... PF7761 Air Dryer (Mann TB1374x)..... BA5374 + Steering (Mann H601/4)..... P106-HD	Fuel (Mann PU999/1x)..... PF7761 Air Dryer (Mann TB1374x)..... BA5374 + Steering (Mann H601/4)..... P106-HD	Most Models w/Cummins Eng. F-F Lube Bag..... P996 F-F Lube Ele..... P999-HD F-F Lube Spin-on..... B196 + B-P Lube Ele..... C750-E + Fuel/Water Separator..... BF1212 + 4 3/8 In. Fuel Spin-on..... BF948 + 5 3/4 In. Fuel Spin-on..... BF957 + 11 7/32 In. Fuel Spin-on..... BF596 + Breather Ele. (w/Turbo) (255963) PA643 Breather Ele. (w/o Turbo) (256837)..... PA1627 Turbocharger..... BT112
S315 H w/Mercedes-Benz OM457 Eng. Lube (Mann HU945/2x)..... P7188 Fuel Ele. (Mann PU999/1x)..... PF7761 Air Dryer (Mann TB1374x)..... BA5374 + Steering (Mann H601/4)..... P106-HD	S431 DT w/Mercedes-Benz OM502 Eng. F-F Lube (Mann HU12140x)..... P7192 Fuel (Mann PU999/1x)..... PF7761 Air Dryer (Mann TB1374x)..... BA5374 + Steering (Mann H601/4)..... P106-HD	S36M Lube (1952-54)..... P52
S315 NF, S315 UL w/Mercedes-Benz OM457 Eng. Lube (HU945/2x)..... P7188 Fuel (Mann PU999/1x)..... PF7761 Air Dryer (Mann TB1374x)..... BA5374 + Steering (Mann H601/4)..... P106-HD	SG321 UL w/Mercedes-Benz OM457 Eng. Lube (Mann HU945/2x)..... P7188 Fuel (Mann PU999/1x)..... PF7761 Air (Mann C31980)..... RS5483 Air Dryer (Mann TB1374x)..... BA5374 + Steering (Mann H601/4)..... P106-HD Some Steering (Mann P919/7).... PT691	<b>SPARTAN</b> Fire Truck Chassis
S316 UL w/Mercedes-Benz OM457 Eng. Lube (Mann H12110/2x)..... P294 Some Lube (Mann HU945/2x).... P7188 Fuel (Mann PU999/1x)..... PF7761 Air Dryer (Mann TB1374x)..... BA5374 + Steering (Mann H601/4)..... P106-HD	<b>SOLARIS</b> Buses	Advantage Trans. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT
S317 UL w/Mercedes-Benz OM457 Eng. Lube (Mann HU945/2x)..... P7188 Fuel (Mann PU999/1x)..... PF7761 Air Dryer (Mann TB1374x)..... BA5374 + Steering (Mann H601/4)..... P106-HD Some Steering (Mann P919/7).... PT691	Urbino 10 w/Cummins ISBE6 (Euro 6) Eng. Lube (Fleetguard LF16015)..... BT7237 Fuel/Water Separator (Fleetguard FS19731)..... PF7687 Radial Seal O. Air (Fleetguard AF26124)..... RS5429 Radial Seal I. Air (Fleetguard AF26125)..... RS5430 Primary EnduraCube Air (Fleetguard AF55014)..... PA31002 Secondary EnduraCube Air (Fleetguard AF55308)..... PA31003 Crankcase Breather (Fleetguard CV52001)..... CV15010 Steering (Fleetguard HF6162).... P106-HD Diesel Exhaust Fluid (Fleetguard UF101)..... PE17000	Big Easy Trans. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT
S319 NF, S319 UL w/Mercedes-Benz OM457 Eng. Lube (Mann HU945/2x)..... P7188 Fuel (Mann PU999/1x)..... PF7761 Air Dryer (Mann TB1374x)..... BA5374 + Steering (Mann H601/4)..... P106-HD Some Steering (Mann P919/7).... PT691	Urbino 12 w/Cummins ISBE6 (Euro 6) Eng. Lube (Fleetguard LF16015)..... BT7237 Fuel/Water Separator (Fleetguard FS19731)..... PF7687 Radial Seal O. Air (Fleetguard AF26124)..... RS5429 Radial Seal I. Air (Fleetguard AF26125)..... RS5430 Primary EnduraCube Air (Fleetguard AF55014)..... PA31002 Secondary EnduraCube Air (Fleetguard AF55308)..... PA31003 Crankcase Breather (Fleetguard CV52001)..... CV15010 Steering (Fleetguard HF6162).... P106-HD Diesel Exhaust Fluid (Fleetguard UF101)..... PE17000	Diamond Trans. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT Trans. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT
S411 HD w/Mercedes-Benz OM501 Eng. F-F Lube (Mann H12140x)..... P7192 Fuel Ele. (Mann PU999/1x)..... PF7761 Air Dryer (Mann TB1374x)..... BA5374 + Steering (Mann H601/4)..... P106-HD		ERV-Classic-Commercial w/MaxxForce 9 Eng. F-F Lube (1889124-C91)..... B7503 Centrifugal Lube (2606467-C91) BC7485 + B-P Lube Spinner (73165)..... BC7456 KIT Fuel/Water Separator (Fleetguard FS1003)..... BF1293-SPS Fuel (1873910-C91)..... PF7994 Air Dryer (AD-9 System) (Bendix 107796)..... BA5377 Air Dryer (Wabco R950011)..... BA5374 + Air Dryer (Wabco R950068)..... BA5379 + Trans. (2 In. Kit) (Allison 29548987)..... PT9416-MPG KIT Trans. (4 In. Kit) (Allison 29548988)..... PT9415-MPG KIT
S415 HD, S415 HDH w/Mercedes-Benz OM457 Eng. Lube (Mann HU945/2x)..... P7188 Fuel (Mann PU999/1x)..... PF7761 Air Dryer (Mann TB1374x)..... BA5374 + Steering (Mann H601/4)..... P106-HD		ERV-Classic-Custom w/Cummins ISL Eng. Dual-Flow Lube (Fleetguard LF9009)..... BD7309 + Fuel/Water Separator (Fleetguard FS1003)..... BF1293-SPS Fuel (Fleetguard FF5636)..... BF7924
S416 GT-HD w/Mercedes-Benz OM457 Eng. Fuel..... PF7761		
S416 HDH w/Mercedes-Benz OM502 Eng. F-F Lube..... P7192 Fuel..... PF7761		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>SPARTAN</b> Fire Truck Chassis (cont'd)	<b>SPARTAN</b> Fire Truck Chassis (cont'd)	<b>SPARTAN</b> Fire Truck Chassis (cont'd)
ERV-Classic-Custom w/Cummins ISL Eng. (Cont'd)	Gladiator w/Cat C11 Eng.	Gladiator w/Cummins ISX 15.0 (14.9L) Eng. (2021)
Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	Lube (To 1/2004) (1R0716)..... <b>B99 +</b>	Lube (5575298)..... <b>B40145</b>
Air Dryer (Wabco R950011)..... <b>BA5374 +</b>	Lube (1/2004-on) (1R1808)..... <b>B7299 +</b>	Fuel (5365988)..... <b>BF46129</b>
Air Dryer (Wabco R950068)..... <b>BA5379 +</b>	<b>Some Fuel/Water Separator</b>	Metro Star w/Cummins ISC 8.3 (8.3L) Eng.
Trans. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	(256-8753)..... <b>BF1259</b>	<b>Dual-Flow Lube</b> (Fleetguard
Trans. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	Fuel (High Efficiency) (1R0749).... <b>BF7587 +</b>	LF9009)..... <b>BD7309 +</b>
<b>Diesel Exhaust Fluid</b> (2880298).. <b>PE17000</b>	Fuel (1R0762)..... <b>BF7753</b>	Fuel (Fleetguard FF5488)..... <b>BF7815</b>
ERV-Legend-Commercial w/MaxxForce 9 Eng.	Fuel (1R1712)..... <b>BF614 +</b>	Fuel (Fleetguard FF5636)..... <b>BF7924</b>
F-F Lube (1889124-C91)..... <b>B7503</b>	Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
Centrifugal Lube (2606467-C91) <b>BC7485 +</b>	Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Air Dryer (Wabco R950011)..... <b>BA5374 +</b>
B-P Lube Spinner (73165)..... <b>BC7456 KIT</b>	Gladiator w/Cat C13 (12.5L) Eng. (To 1/2004)	Air Dryer (Wabco R950068)..... <b>BA5379 +</b>
<b>Fuel/Water Separator</b>	Lube (1R0716)..... <b>B99 +</b>	Trans. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>
(Fleetguard FS1003)..... <b>BF1293-SPS</b>	<b>Some Fuel/Water Separator</b>	Trans. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>
Fuel (1873910-C91)..... <b>PF7994</b>	(256-8753)..... <b>BF1259</b>	Metro Star w/Cummins ISL 8.9 (8.9L) Eng. (2003-17)
Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	Fuel (High Efficiency) (1R0749).... <b>BF7587 +</b>	<b>Dual-Flow Lube</b> (Fleetguard
Air Dryer (Wabco R950011)..... <b>BA5374 +</b>	Fuel (1R1712)..... <b>BF614 +</b>	LF9009)..... <b>BD7309 +</b>
Air Dryer (Wabco R950068)..... <b>BA5379 +</b>	Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Fuel/Water Separator</b>
Trans. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	(Fleetguard FS1003)..... <b>BF1293-SPS</b>
Trans. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	Gladiator w/Cat C13 (12.5L) Eng. (1/2004-on)	Fuel (Fleetguard FF5636)..... <b>BF7924</b>
ERV-Star-Commercial w/MaxxForce 9 Eng.	Lube (1R1808)..... <b>B7299 +</b>	Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
F-F Lube (1889124-C91)..... <b>B7503</b>	<b>Some Fuel/Water Separator</b>	Air Dryer (Wabco R950011)..... <b>BA5374 +</b>
Centrifugal Lube (2606467-C91) <b>BC7485 +</b>	(256-8753)..... <b>BF1259</b>	Air Dryer (Wabco R950068)..... <b>BA5379 +</b>
B-P Lube Spinner (73165)..... <b>BC7456 KIT</b>	Fuel (High Efficiency) (1R0749).... <b>BF7587 +</b>	Trans. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>
<b>Fuel/Water Separator</b>	Fuel (1R1712)..... <b>BF614 +</b>	Trans. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>
(Fleetguard FS1003)..... <b>BF1293-SPS</b>	Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	Metro Star w/Cummins ISL 8.9 (8.9L) Eng. (2018)
Fuel (1873910-C91)..... <b>PF7994</b>	Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Dual-Flow Lube</b> (Fleetguard
Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	Gladiator w/Cummins ISL 8.9 (8.9L) Eng. (2018)	LF9009)..... <b>BD7309 +</b>
Air Dryer (Wabco R950011)..... <b>BA5374 +</b>	<b>Dual-Flow Lube</b> (Fleetguard	Fuel (Fleetguard FF63009)..... <b>BF63000</b>
Air Dryer (Wabco R950068)..... <b>BA5379 +</b>	LF9009)..... <b>BD7309 +</b>	Metro Star w/Cummins ISL 8.9 (8.9L) Eng. (2019)
Trans. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	Fuel (Fleetguard FF63009)..... <b>BF63000</b>	Lube (3401544)..... <b>B40142</b>
Trans. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	Gladiator w/Cummins ISL 8.9 (8.9L) Eng. (2019)	Fuel (5303743)..... <b>BF63000</b>
ERV-Star-Custom w/Cummins ISL Eng.	Lube (5444774)..... <b>B40142</b>	Gladiator w/Cummins ISL 8.9 (8.9L) Eng. (2020)
<b>Dual-Flow Lube</b> (Fleetguard	Fuel (5303743)..... <b>BF63000</b>	Lube (5444774)..... <b>B40142</b>
LF9009)..... <b>BD7309 +</b>	Gladiator w/Cummins ISX 15.0 (14.9L) Eng. (2018)	Fuel (5303743)..... <b>BF63000</b>
<b>Fuel/Water Separator</b>	<b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b>	Metro Star w/Cummins ISL 8.9 (8.9L) Eng. (2020)
(Fleetguard FS1003)..... <b>BF1293-SPS</b>	<b>Fuel/Water Separator</b>	Lube (5444774)..... <b>B40142</b>
Fuel (Fleetguard FF5636)..... <b>BF7924</b>	(Fleetguard FS19764)..... <b>PF9814</b>	Fuel (5303743)..... <b>BF63000</b>
Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	Fuel (Fleetguard FF5825NN)..... <b>BF46129 +</b>	Metro Star w/Cummins ISL 8.9 (8.9L) Eng. (2021)
Air Dryer (Wabco R950011)..... <b>BA5374 +</b>	Coolant (Fleetguard WF2127)..... <b>B5087</b>	Lube (5444774)..... <b>B40142</b>
Air Dryer (Wabco R950068)..... <b>BA5379 +</b>	<b>Diesel Exhaust Fluid</b> (Fleetguard UF106)..... <b>PE17002 KIT</b>	Metro Star-X w/Cummins ISC 8.3 (8.3L) Eng.
Trans. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	Gladiator w/Cummins ISX 15.0 (14.9L) Eng. (2019)	<b>Dual-Flow Lube</b> (Fleetguard
Trans. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	<b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b>	LF9009)..... <b>BD7309 +</b>
<b>Diesel Exhaust Fluid</b> (2880298).. <b>PE17000</b>	Fuel (5365988)..... <b>BF46129</b>	Fuel (Fleetguard FF5488)..... <b>BF7815</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>SPARTAN</b> Fire Truck Chassis (cont'd)	<b>SPARTAN</b> Motorhome Chassis (cont'd)	<b>SPARTAN</b> Motorhome Chassis (cont'd)
Metro Star-X w/Cummins ISC 8.3 (8.3L) Eng. (Cont'd)	EC2000 w/Cummins 6BT5.9 (5.9L) Eng. (To 1998)	K2 w/Cummins ISM 10.8 (10.8L) Eng. (2004-on) (Cont'd)
Trans. (2 In. Kit) (Allison 29548987).....	Lube (3914395).....	Air (w/Mechanical Fan) (Farr 62891-002).....
<b>PT9416-MPG KIT</b>	<b>BT339 +</b>	<b>PA2722</b>
Trans. (4 In. Kit) (Allison 29548988).....	Fuel/Water Separator (3925274).....	Air (w/Hyd. Fan) (Farr 62891-003).....
<b>PT9415-MPG KIT</b>	<b>BF1280 +</b>	<b>PA2723</b>
Diesel Exhaust Fluid (2880298).....	Fuel (3903640).....	Trans. (2 In. Kit) (Allison 29540493).....
<b>PE17000</b>	<b>BF788</b>	<b>PT9416-MPG KIT</b>
Metro Star X w/Cummins ISL 8.9 (8.9L) Eng. (2018)	EC2000 w/Cummins 6BT5.9 (5.9L) Eng. (1999-on)	Trans. (4 In. Kit) (Allison 29540494).....
Dual-Flow Lube (Fleetguard LF9009).....	Lube (Chrysler 5083285AA).....	<b>PT9415-MPG KIT</b>
<b>BD7309 +</b>	<b>BT7349</b>	Steering (w/Mechanical Fan) (Nelson 83804E).....
Fuel (Fleetguard FF63009).....	Fuel/Water Separator (3925274).....	<b>P528</b>
<b>BF63000</b>	<b>BF1280 +</b>	K3 w/Cummins ISX 15.0 (14.9L) Eng. (2004-15)
Mountain Star	Fuel (3903640).....	Trans. (2 In. Kit) (Allison 29540493).....
Trans. (2 In. Kit) (Allison 29540493).....	<b>BF788</b>	<b>PT9416-MPG KIT</b>
Trans. (4 In. Kit) (Allison 29540494).....	Highlander w/Cummins 6B5.9L Eng.	Trans. (4 In. Kit) (Allison 29540494).....
<b>PT9415-MPG KIT</b>	F-F Lube (3313281).....	<b>PT9415-MPG KIT</b>
	Dual-Flow Lube (3318853).....	Steering (Rexhall models) (Nelson 83804E).....
	Fuel/Water Separator (3925274).....	<b>P528</b>
	Fuel (3903640).....	K3 w/Cummins ISX 15.0 (14.9L) Eng. (2018)
	<b>BF788</b>	Dual-Flow Lube (4367100).....
	K2 w/Cummins ISL 8.9 (8.9L) Eng. (2018)	Fuel (5365988).....
	Dual-Flow Lube (Fleetguard LF9009).....	<b>BF46129 +</b>
	<b>BD7309 +</b>	K3 w/Cummins ISX 15.0 (14.9L) Eng. (2019)
	Fuel (Fleetguard FF63009).....	Lube (3401544).....
	<b>BF63000</b>	<b>B40142</b>
	K2 w/Cummins ISL 8.9 (8.9L) Eng. (2019)	Fuel (5365988).....
	Lube (3401544).....	<b>BF46129</b>
	<b>B40142</b>	K3 w/Cummins ISX 15.0 (14.9L) Eng. (2020)
	Fuel (5303743).....	Dual-Flow Lube (4367100).....
	<b>BF63000</b>	Fuel (5365988).....
	K2 w/Cummins ISL 8.9 (8.9L) Eng. (2020)	<b>BF46129</b>
	Lube (5444774).....	K3 w/Cummins ISX 15.0 (14.9L) Eng. (2021)
	<b>B40142</b>	Lube (5575298).....
	Fuel (5303743).....	<b>B40145</b>
	<b>BF63000</b>	K3 w/Cummins ISX 15.0 (14.9L) Eng. (2022)
	K2 w/Cummins ISL 8.9 (8.9L) Eng. (2021)	Lube (5575298).....
	Lube (5444774).....	<b>B40145</b>
	<b>B40142</b>	Fuel (5575143).....
	Fuel (5660774).....	<b>BF46248</b>
	<b>BF63000</b>	K4 w/Cummins ISX 15.0 (14.9L) Eng. (2018)
	K2 w/Cummins ISM 10.8 (10.8L) Eng. (To 2003)	Dual-Flow Lube (4367100).....
	11 13/16 In. Dual-Flow Lube (Fleetguard LF9001).....	Fuel (Fleetguard FF5825NN).....
	<b>BD7154 +</b>	<b>BF46129 +</b>
	14 7/32 In. Dual-Flow Lube (Fleetguard LF9000).....	K4 w/Cummins ISX 15.0 (14.9L) Eng. (2019)
	<b>BD7153 +</b>	Dual-Flow Lube (4367100).....
	Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN).....	Fuel (5365988).....
	<b>BD50000</b>	<b>BF46129</b>
	Fuel/Water Separator (Fleetguard FS1000).....	K4 w/Cummins ISX 15.0 (14.9L) Eng. (2020)
	<b>BF1259</b>	Dual-Flow Lube (4367100).....
	Air (w/Mechanical Fan) (Farr 62891-002).....	<b>BD50000</b>
	<b>PA2722</b>	Fuel (5365988).....
	Air (w/Hyd. Fan) (Farr 62891-003).....	<b>BF46129</b>
	<b>PA2723</b>	K4 w/Cummins ISX 15.0 (14.9L) Eng. (2021)
	Trans. (2 In. Kit) (Allison 29540493).....	Lube (5575298).....
	<b>PT9416-MPG KIT</b>	<b>B40145</b>
	Trans. (4 In. Kit) (Allison 29540494).....	Fuel (5365988).....
	<b>PT9415-MPG KIT</b>	<b>BF46129</b>
	Steering (w/Mechanical Fan) (Nelson 83804E).....	K4 w/Cummins ISX 15.0 (14.9L) Eng. (2022)
	<b>P528</b>	Lube (5575298).....
	K2 w/Cummins ISM 10.8 (10.8L) Eng. (2004-on)	Fuel (Researching).....
	11 13/16 In. Dual-Flow Lube (Fleetguard LF9001).....	<b>BF46248</b>
	<b>BD7154 +</b>	Mountain Master w/Cummins 6BT5.9 (5.9L) Eng.
	14 7/32 In. Dual-Flow Lube (Fleetguard LF9000).....	F-F Lube (3313281).....
	<b>BD7153 +</b>	Dual-Flow Lube (3318853).....
	Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN).....	Fuel/Water Separator (3925274).....
	<b>BD50000</b>	Fuel (3903640).....
		<b>BF1280 +</b>
		<b>BF788</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>SPARTAN</b> Motorhome Chassis (cont'd)	<b>SPARTAN</b> Motorhome Chassis (cont'd)	<b>STERLING</b> Trucks (cont'd)
Mountain Master w/Cummins N14 Eng. F-F Lube (Fleetguard LF670SC).. <b>B196 +</b> B-P Lube (3304232)..... <b>B7577</b> Dual-Flow Lube (3318853)..... <b>BD103 +</b> Fuel (154789)..... <b>BF957-D +</b>	NVS GT, NVS ME w/Cummins ISC Eng. (Cont'd) Fuel/Water Separator (Fleetguard FS1022)..... <b>BF1272-SPS</b> Air (Farr 62891-001)..... <b>PA2721</b> Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	Acterra w/Cat C7 (7.2L) Eng. (1/2004-on) F-F Eng. Lube (1R1807)..... <b>B7700 +</b> Fuel/Water Separator (2568753). <b>BF1259</b> Fuel/Water Separator (1752949). <b>BF1268</b> Fuel (1R0751)..... <b>BF7632</b> Trans. Pan-Type (Allison 29538489)..... <b>19739 +</b> Trans. Spin-on (Allison 29510922)..... <b>BT8316-MPG</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>
Mountain Master, Mountain Master ME w/Cummins ISC 8.3 (8.3L) Eng. Dual-Flow Lube (Fleetguard LF3000)..... <b>BD103 +</b> Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309 +</b> Fuel/Water Separator (Fleetguard FS1022)..... <b>BF1272-SPS</b> Air (Farr 62891-001)..... <b>PA2721</b> Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	Travel Ride III w/Cummins ISX 15.0 (14.9L) Eng. (2021) Lube (5575298)..... <b>B40145</b> Fuel (5365988)..... <b>BF46129</b>	Acterra w/Cummins ISB (5.9L) Eng. Lube (3937144)..... <b>B7177</b> Fuel/Water Separator Ele. (4941252)..... <b>PF7977</b> Fuel/Water Separator Ele. (3942470)..... <b>PF7777</b> Fuel (4934845)..... <b>BF7940</b> Cab Air (Fresh Air) (F6HZ19N619AA)..... <b>PA5337</b> Cab Air (Recirculation) (F6HZ-19N619-BA)..... <b>PA5393</b> Air Dryer (Bendix 65624)..... <b>BA5373</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Some Rear Axle (Meritor 3280V5040)..... <b>B27</b>
Mountain Master, Mountain Master GT w/Cummins ISL 8.9 (8.9L) Eng. Dual-Flow Lube (Fleetguard LF3000)..... <b>BD103 +</b> Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309 +</b> P. Fuel/Water Separator (Fleetguard FS1003)..... <b>BF1293-SPS</b> Fuel/Water Separator (Fleetguard FS1022)..... <b>BF1272-SPS</b> S. Fuel (Fleetguard FF5488)..... <b>BF7815</b> Air (Farr 62891-001)..... <b>PA2721</b> Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Steering (w/Mechanical Fan) (Nelson 83804E)..... <b>P528</b>	<b>STARK MFG.</b> Auxiliary Power Units (APU) HP2000 w/2 Cyl. Perkins Eng. Fuel (130366040)..... <b>PF937</b> Radial Seal Air (Don. P822686)... <b>RS3715</b>	Fuel/Water Separator Ele. (3942470)..... <b>PF7777</b> Fuel (4934845)..... <b>BF7940</b> Cab Air (Recirculation) (F6HZ-19N619-BA)..... <b>PA5393</b> Air Dryer (Bendix 65624)..... <b>BA5373</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Some Rear Axle (Meritor 3280V5040)..... <b>B27</b>
Mountain Master, Mountain Master GT w/Cummins ISL 8.9 (8.9L) Eng. Dual-Flow Lube (Fleetguard LF3000)..... <b>BD103 +</b> Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309 +</b> P. Fuel/Water Separator (Fleetguard FS1003)..... <b>BF1293-SPS</b> Fuel/Water Separator (Fleetguard FS1022)..... <b>BF1272-SPS</b> S. Fuel (Fleetguard FF5488)..... <b>BF7815</b> Air (Farr 62891-001)..... <b>PA2721</b> Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Steering (w/Mechanical Fan) (Nelson 83804E)..... <b>P528</b>	<b>STERLING</b> Trucks 360 w/Mitsubishi 4M50-3AT8 (4.9L) Eng. Lube (ME088532)..... <b>B7121</b> Fuel (ME222135)..... <b>PF9803</b> Radial Seal Air (ME017246)..... <b>RS4806</b>	Acterra w/Cummins ISB 6.7 (6.7L) Eng. Lube (3937144)..... <b>B7177</b> Fuel/Water Separator Ele. (4941252)..... <b>PF7977</b> Fuel/Water Separator Ele. (3942470)..... <b>PF7777</b> Fuel (4934845)..... <b>BF7940</b> Radial Seal Air (Don. P527484)... <b>RS2863</b> Radial Seal XP Air (Don. P527484)..... <b>RS2863XP</b> Cab Air (Fresh Air) (F6HZ19N619AA)..... <b>PA5337</b> Cab Air (Recirculation) (F6HZ-19N619-BA)..... <b>PA5393</b> Air Dryer (Bendix 65624)..... <b>BA5373</b>
NVS w/Cummins ISB Eng. Air (Farr 62891-001)..... <b>PA2721</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Steering (Rexhall models only) (Nelson 83804E)..... <b>P528</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	Acterra w/Cat C7 (7.2L) Eng. (To 1/2004) F-F Lube (Standard Vers.) (1R0739)..... <b>B76 +</b> F-F Lube (Severe Service) (1R0739)..... <b>B76-SS +</b> Fuel/Water Separator (2568753). <b>BF1259</b> Fuel/Water Separator (1752949). <b>BF1268</b> Fuel (1R0751)..... <b>BF7632</b> Trans. Pan-Type (Allison 29538489)..... <b>19739 +</b> Trans. Spin-on (Allison 29510922)..... <b>BT8316-MPG</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	Acterra w/Cat C7 (7.2L) Eng. (1/2004-on) F-F Eng. Lube (1R1807)..... <b>B7700 +</b> Fuel/Water Separator (2568753). <b>BF1259</b> Fuel/Water Separator (1752949). <b>BF1268</b> Fuel (1R0751)..... <b>BF7632</b> Trans. Pan-Type (Allison 29538489)..... <b>19739 +</b> Trans. Spin-on (Allison 29510922)..... <b>BT8316-MPG</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>
NVS GT, NVS ME w/Cummins ISC Eng. Dual-Flow Lube (Fleetguard LF3000)..... <b>BD103 +</b> Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309 +</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



STERLING Trucks (cont'd)	STERLING Trucks (cont'd)	STERLING Trucks (cont'd)
Acterra w/Cummins ISB 6.7 (6.7L) Eng. (Cont'd)	Acterra w/Cummins ISC 8.3 (8.3L) Eng.	Acterra w/Mercedes-Benz OM906 (6.4L) Eng.
Trans. Ele. (2 In. Kit) (Allison 29540493).....	(2007-on)	Lube (A0001801609).....
PT9416-MPG KIT	Dual-Flow Lube (3401544).....	P7199
Trans. Ele. (4 In. Kit) (Allison 29540494).....	BD7309 +	Fuel/Water Separator (A0004771302).....
PT9415-MPG KIT	B40142 +	BF1363
Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965).....	Fuel/Water Separator (w/Rectangle Sensor) (3800394)..	Fuel (A9060920305).....
20004	BF1293-SPS	PF7735
Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965).....	Fuel/Water Separator (w/Oval Sensor) (3800394).....	Trans. (Fuller 4304827).....
20016	BF1272-SPS	BT223
Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966).....	Fuel (Fleetguard FF5636).....	Opt. Trans. (Fuller 17237).....
20003	BF7924	B2 +
Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966).....	BF7924	
20017	RS2863	
Trans. Spin-on (Allison 29539579).....	Radial Seal Air (Don. P527484)...	
BT8460	Radial Seal XP Air (Don. P527484).....	
Steering (VMLT1808D).....	Cab Air (Fresh Air) (F6HZ19N619AA).....	
BT9388	PA5337	
Some Rear Axle (Meritor 3280V5040).....	Cab Air (Recirculation) (F6HZ19N619BA).....	
B27	PA5393	
	BA5373	
	BW5071	
	Trans. Ele. (2 In. Kit) (Allison 29540493).....	
	PT9416-MPG KIT	
	Trans. Ele. (4 In. Kit) (Allison 29540494).....	
	PT9415-MPG KIT	
	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965).....	
	20004	
	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965).....	
	20016	
	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966).....	
	20003	
	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966).....	
	20017	
	Trans. Spin-on (Allison 29539579).....	
	BT8460	
	Opt. Trans. Spin-on (Fuller 17237).....	
	B2 +	
	Steering (VMLT1808D).....	
	BT9388	
	Some Rear Axle (Meritor 3280-V-5040).....	
	B27	
	Acterra w/Mercedes-Benz MBE904 (4.3L) Eng.	
	5 15/16 In. F-F Lube (1801609)...	
	P7199	
	8 3/8 In. F-F Lube (1801709).....	
	P7188	
	Opt. B-P Lube Spinner (A9061810086).....	
	BC7326 +	
	Fuel (A0000901551).....	
	PF7735	
	Fuel (A5410920305).....	
	PF7761	
	Trans. Ele. (2 In. Kit) (Allison 29540493).....	
	PT9416-MPG KIT	
	Trans. Ele. (4 In. Kit) (Allison 29540494).....	
	PT9415-MPG KIT	
	Acterra w/Mercedes-Benz MBE906 (6.4L) Eng.	
	F-F Lube (1801709).....	
	P7188	
	Opt. B-P Lube Spinner (A9061810086).....	
	BC7326 +	
	Fuel (A0000901551).....	
	PF7735	
	Fuel (A5410920305).....	
	PF7761	
	Trans. Ele. (2 In. Kit) (Allison 29540493).....	
	PT9416-MPG KIT	
	Trans. Ele. (4 In. Kit) (Allison 29540494).....	
	PT9415-MPG KIT	
	Acterra 5500 w/Cat 3126 (7.2L) Eng.	
	Lube (Standard Vers.).....	
	B76	
	Acterra 5500 w/Mercedes-Benz MBE900 (4.3L) Eng.	
	F-F Lube Ele. (1801709).....	
	P7188	
	Opt. B-P Lube Spinner (A9061810086).....	
	BC7326 +	
	Fuel/Water Separator (Alliance ABPN122R50418).....	
	BF9898-O	
	Fuel/Water Separator Spin-on (w/o SP) (Alliance ABP/S3226FL02).....	
	BF1346 +	
	Fuel/Water Separator Spin-on (w/SP) (Alliance ABP/S3226FL02).....	
	BF1346-SP +	
	Fuel/Water Separator Spin-on (Fleetguard FS1065).....	
	BF1378-SPS	
	Fuel/Water Separator Spin-on (Fleetguard FS1003).....	
	BF1293-SPS	
	P. Fuel (901551).....	
	PF7735	
	P. Fuel (A5410920805).....	
	PF7761	
	S. Fuel (901351).....	
	PF7974	
	Radial Seal Air (Don. P185067)...	
	RS2863	
	Radial Seal XP Air (Don. P185067).....	
	RS2863XP	
	Cab Air (Fresh Air) (F6HZ19N619AA).....	
	PA5337	
	Cab Air (Recirculation) (F6HZ19N619BA).....	
	PA5393	
	Air Dryer (Bendix 65624).....	
	BA5373	
	Coolant (Fleetguard WF2071).....	
	BW5200	
	Trans. Ele. (2 In. Kit) (Allison 29540493).....	
	PT9416-MPG KIT	
	Trans. Ele. (4 In. Kit) (Allison 29540494).....	
	PT9415-MPG KIT	
	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965).....	
	20004	
	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965).....	
	20016	
	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966).....	
	20003	
	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966).....	
	20017	
	Trans. Spin-on (Allison 29539579).....	
	BT8460	
	Opt. Trans. Spin-on (Fuller 17237).....	
	B2 +	
	Steering (VMLT1808D).....	
	BT9388	
	Some Rear Axle (Meritor 3280-V-5040).....	
	B27	

+ See Product Guide for Variations of This Number. Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

STERLING Trucks (cont'd)	STERLING Trucks (cont'd)	STERLING Trucks (cont'd)
Acterra 5500 w/Mercedes-Benz MBE904 (4.3L) Eng. 5 15/16 In. F-F Lube (1801609)... P7199 8 3/8 In. F-F Lube (1801709)... P7188 Opt. B-P Lube Spinner (A9061810086)... BC7326 + Fuel (A0000901551)... PF7735 Fuel (A5410920305)... PF7761	Acterra 5500, Acterra 6500 w/Cummins ISC (8.3L) Eng. (To 2007) (Cont'd) Fuel/Water Separator (Alliance ABPN122R50418)... BF9898-O Fuel/Water Separator (Fleetguard FS1022)... BF1272-SPS Fuel (3959612)... BF7815 Radial Seal Air (Don. P527484)... RS2863 Radial Seal XP Air (Don. P527484)... RS2863XP Cab Air (Fresh Air) (F6HZ19N619AA)... PA5337 Cab Air (Recirculation) (F6HZ19N619BA)... PA5393 Air Dryer (Bendix 65624)... BA5373 Coolant (Fleetguard WF2071)... BW5071 Trans. Ele. (2 In. Kit) (Allison 29540493)... PT9416-MPG KIT Trans. Ele. (4 In. Kit) (Allison 29540494)... PT9415-MPG KIT Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)... 20004 Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)... 20016 Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)... 20003 Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)... 20017 Trans. Spin-on (Allison 29539579)... BT8460 Opt. Trans. Spin-on (Fuller 17237)... B2 + Steering (VML/T1808D)... BT9388 Some Rear Axle (Meritor 3280-V-5040)... B27	Acterra 5500, Acterra 6500 w/Cummins ISC (8.3L) Eng. (2007-on) (Cont'd) Trans. Ele. (2 In. Kit) (Allison 29540493)... PT9416-MPG KIT Trans. Ele. (4 In. Kit) (Allison 29540494)... PT9415-MPG KIT Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)... 20004 Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)... 20016 Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)... 20003 Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)... 20017 Trans. Spin-on (Allison 29539579)... BT8460 Opt. Trans. Spin-on (Fuller 17237)... B2 + Steering (VML/T1808D)... BT9388 Some Rear Axle (Meritor 3280-V-5040)... B27
Acterra 5500 w/Mercedes-Benz MBE906 (6.4L) Eng. F-F Lube (1801709)... P7188 Opt. B-P Lube Spinner (A9061810086)... BC7326 + Fuel (A0000901551)... PF7735 Fuel (A5410920305)... PF7761	Acterra 5500, Acterra 6500 w/Cummins ISC (8.3L) Eng. (2007-on) Dual-Flow Lube (3401544)... BD7309 + Lube (Upgrade) (3401544)... B40142 + Fuel/Water Separator (w/Drain) (ABPN122S3226FL01)... BF1347 Fuel/Water Separator (Open End for Bowl) (ABPN122S3226FL01)... BF1347-O Fuel/Water Separator (w/Sensor Port) (ABPN122S3226FL01)... BF1373-SP Fuel/Water Separator (Alliance ABPN122R50418)... BF9898-O Fuel/Water Separator (Fleetguard FS1022)... BF1272-SPS Fuel (Fleetguard FF5636)... BF7924 Radial Seal Air (Don. P527484)... RS2863 Radial Seal XP Air (Don. P527484)... RS2863XP Cab Air (Fresh Air) (F6HZ19N619AA)... PA5337 Cab Air (Recirculation) (F6HZ19N619BA)... PA5393 Air Dryer (Bendix 65624)... BA5373 Coolant (Fleetguard WF2071)... BW5071	Acterra 5500, Acterra 6500, Acterra 7500 w/Cummins ISB (5.9L) Eng. Lube (Fleetguard LF3970)... B7177 Fuel/Water Separator (Fleetguard FS19579)... PF7777 Fuel (Fleetguard FF5632)... BF7940 Radial Seal Air (Don. P527484)... RS2863 Radial Seal XP Air (Don. P527484)... RS2863XP Cab Air (Fresh Air) (F6HZ-19N619-AA)... PA5337 Cab Air (Recirculation) (F6HZ-19N619-BA)... PA5393 Air Dryer (Bendix 65624)... BA5373 Crankcase Breather (2007-on) (4936636)... CV15010 Trans. Ele. (2 In. Kit) (Allison 29540493)... PT9416-MPG KIT Trans. Ele. (4 In. Kit) (Allison 29540494)... PT9415-MPG KIT Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)... 20004 Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)... 20016 Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)... 20003 Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)... 20017 Trans. Spin-on (Allison 29539579)... BT8460 Steering (VML/T1808D)... BT9388 Some Rear Axle (Meritor 3280-V-5040)... B27
Acterra 5500, Acterra 6500 w/Cat C7 (7.2L) Eng. Lube (1R1807)... B7700 + Fuel/Water Separator (Alliance ABPN122R50418)... BF9898-O Fuel (1R0751)... BF7632 Radial Seal XP Air (Don. EAF5067)... RS2863XP Opt. Radial Seal I. Air (Don. P531751)... RS3501 Cab Air (Fresh Air) (F6HZ19N619AA)... PA5337 Cab Air (Recirculation) (F6HZ19N619BA)... PA5393 Coolant (9N-6123)... BW5139 Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)... 20004 Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)... 20016 Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)... 20003 Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)... 20017 Trans. Spin-on (Allison 29539579)... BT8460 Trans. Ele. (2 In. Kit) (Allison 29540493)... PT9416-MPG KIT Trans. Ele. (4 In. Kit) (Allison 29540494)... PT9415-MPG KIT Opt. Trans. Spin-on (Fuller 17237)... B2 + Steering (F8HZ3C602AA)... BT9388	Acterra 5500, Acterra 6500 w/Cummins ISC (8.3L) Eng. (To 2007) Dual-Flow Lube (3401544)... BD7309 + Lube (Upgrade) (3401544)... B40142 + Fuel/Water Separator (w/Drain) (ABPN122S3226FL01)... BF1347 Fuel/Water Separator (Open End for Bowl) (ABPN122S3226FL01)... BF1347-O Fuel/Water Separator (w/Sensor Port) (ABPN122S3226FL01)... BF1373-SP Fuel/Water Separator (Alliance ABPN122R50418)... BF9898-O Fuel/Water Separator (Fleetguard FS1022)... BF1272-SPS Fuel (Fleetguard FF5636)... BF7924 Radial Seal Air (Don. P527484)... RS2863 Radial Seal XP Air (Don. P527484)... RS2863XP Cab Air (Fresh Air) (F6HZ19N619AA)... PA5337 Cab Air (Recirculation) (F6HZ19N619BA)... PA5393 Air Dryer (Bendix 65624)... BA5373 Coolant (Fleetguard WF2071)... BW5071	Acterra 6500 w/Cat 3126 (7.2L) Eng. Lube (Standard Vers.)... B76

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

STERLING Trucks (cont'd)	STERLING Trucks (cont'd)	STERLING Trucks (cont'd)
Acterra 6500 w/Cat C15 (14.6L) Eng. <b>Lube</b> (1R0716)..... <b>B99 +</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (1335673)..... <b>BF1395-O</b> <b>Fuel/Water Separator</b> (w/Drain) (1335673)..... <b>BF1265</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (1335673)..... <b>BF1395-SP</b> <b>Fuel/Water Separator</b> (2568753). <b>BF1259</b> <b>Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (Standard Vers.) (1R1712)..... <b>BF614 +</b> <b>Fuel Spin-on</b> (High Efficiency Vers.) (1R0749)..... <b>BF7587 +</b>	Acterra 6500 w/Mercedes-Benz MBE900 (4.3L) Eng. (Cont'd) <b>Cab Air</b> (Recirculation) (F6HZ19N619BA)..... <b>PA5393</b> <b>Air Dryer</b> (Bendix 65624)..... <b>BA5373</b> <b>Coolant</b> (Nalcool NF2088)..... <b>BW5200</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (VML/T1808D)..... <b>BT9388</b> <b>Some Rear Axle</b> (Meritor 3280-V-5040)..... <b>B27</b>	Acterra 7500 w/Cat C7 (7.2L) Eng. (1/2004-on) <b>Lube</b> (1R1807)..... <b>B7700 +</b> <b>In-Line Fuel</b> (9R9925)..... <b>BF1173</b> <b>Fuel Spin-on</b> (1R0751)..... <b>BF7632</b> <b>Radial Seal XP Air</b> (Don. EAF5067)..... <b>RS2863XP</b>
Acterra 6500 w/Cummins 6BT5.9 (5.9L) Eng. <b>Lube</b> (Chrysler 5083285AA)..... <b>BT7349</b> <b>Fuel/Water Separator</b> (3925274). <b>BF1280 +</b> <b>Fuel</b> (3903640)..... <b>BF788</b>	Acterra 6500 w/Mercedes-Benz MBE904 (4.3L) Eng. <b>5 15/16 In. F-F Lube</b> (1801609)... <b>P7199</b> <b>8 3/8 In. F-F Lube</b> (1801709)..... <b>P7188</b> <b>Opt. B-P Lube Spinner</b> (A9061810086)..... <b>BC7326 +</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Fuel</b> (A5410920305)..... <b>PF7761</b>	Acterra 7500 w/Cat 3126 (7.2L) Eng. <b>Lube</b> (1R1807)..... <b>B7700 +</b> <b>Fuel</b> (1R0751)..... <b>BF7632</b> <b>Trans. Pan-Type</b> (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b>
Acterra 6500 w/Cummins 6CT8.3 (8.3L) Eng. <b>F-F Lube</b> (3313281)..... <b>B205 +</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Fuel/Water Separator</b> (3903410). <b>BF1280 +</b> <b>Fuel/Water Separator</b> (3286503). <b>BF1226</b> <b>Fuel Spin-on</b> (3903640)..... <b>BF788</b>	Acterra 6500 w/Mercedes-Benz MBE906 (6.4L) Eng. <b>F-F Lube</b> (1801709)..... <b>P7188</b> <b>Opt. B-P Lube Spinner</b> (A9061810086)..... <b>BC7326 +</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Fuel</b> (A5410920305)..... <b>PF7761</b>	Acterra 7500 w/Cummins ISC (8.3L) Eng. <b>Dual-Flow Lube</b> ..... <b>BD7309 +</b> <b>F-F Lube</b> (Fleetguard LF3970)..... <b>B7177</b> <b>Fuel/Water Separator</b> (Fleetguard FS19579)..... <b>PF7777</b> <b>Radial Seal O. Air</b> (Fleetguard AF4878)..... <b>RS2863</b> <b>Radial Seal XP O. Air</b> (Fleetguard AF4878)..... <b>RS2863XP</b> <b>Radial Seal I. Air</b> (Don. P531751)..... <b>RS3501</b> <b>Coolant</b> (Fleetguard WF2071)..... <b>BW5071</b>
Acterra 6500 w/Cummins NTC (14.0L) Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>F-F Lube Ele.</b> (158139)..... <b>P999-HD</b> <b>F-F Lube Spin-on</b> (3313279)..... <b>B196 +</b> <b>B-P Lube Ele.</b> (256838)..... <b>C750-E +</b> <b>B-P Lube Spin-on</b> (3313283)..... <b>B7577</b> <b>Fuel/Water Separator</b> (3308638). <b>BF1212 +</b> <b>Fuel</b> (158172)..... <b>BF957 +</b>	Acterra 6500 w/Mercedes-Benz MBE906 (6.4L) Eng. <b>Lube</b> (A0001801609)..... <b>P7199</b> <b>Fuel/Water Separator</b> (w/Drain) (A0004771302)..... <b>BF1363</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b> <b>Fuel</b> (A9060920305)..... <b>PF7735</b>	Acterra 7500 w/Mercedes-Benz MBE900 (4.3L) Eng. <b>F-F Lube Ele.</b> (1801709)..... <b>P7188</b> <b>Opt. B-P Lube Spinner</b> (A9061810086)..... <b>BC7326 +</b> <b>Fuel</b> (901551)..... <b>PF7735</b> <b>Fuel</b> (901351)..... <b>PF7974</b> <b>Radial Seal Air</b> (Don. P533930)... <b>RS3548</b> <b>Radial Seal XP Air</b> (Don. P533930)..... <b>RS3548XP</b> <b>Coolant</b> (Nalcool NF2088)..... <b>BW5200</b>
Acterra 6500 w/Mercedes-Benz MBE900 (4.3L) Eng. <b>F-F Lube Ele.</b> (1801709)..... <b>P7188</b> <b>Opt. B-P Lube Spinner</b> (A9061810086)..... <b>BC7326 +</b> <b>Fuel/Water Separator</b> (Alliance ABPN122R50418)..... <b>BF9898-O</b> <b>Fuel/Water Separator Spin-on</b> (w/o SP) (Alliance ABP/S3226FL02)..... <b>BF1346 +</b> <b>Fuel/Water Separator Spin-on</b> (w/SP) (Alliance ABP/S3226FL02)..... <b>BF1346-SP +</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1003)..... <b>BF1293-SPS</b> <b>P. Fuel</b> (901551)..... <b>PF7735</b> <b>P. Fuel</b> (A5410920805)..... <b>PF7761</b> <b>S. Fuel</b> (901351)..... <b>PF7974</b> <b>Radial Seal Air</b> (Don. P185067)... <b>RS2863</b> <b>Radial Seal XP Air</b> (Don. P185067)..... <b>RS2863XP</b> <b>Cab Air</b> (Fresh Air) (F6HZ19N619AA)..... <b>PA5337</b>	Acterra 6500 w/Mercedes-Benz OM906 (6.4L) Eng. <b>Lube</b> (A0001801609)..... <b>P7199</b> <b>Fuel/Water Separator</b> (w/Drain) (A0004771302)..... <b>BF1363</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b> <b>Fuel</b> (A9060920305)..... <b>PF7735</b>	Acterra 7500 w/Mercedes-Benz MBE904 (4.3L) Eng. <b>5 15/16 In. F-F Lube</b> (1801609)... <b>P7199</b> <b>8 3/8 In. F-F Lube</b> (1801709)..... <b>P7188</b> <b>Opt. B-P Lube Spinner</b> (A9061810086)..... <b>BC7326 +</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Fuel</b> (A5410920305)..... <b>PF7761</b> <b>Radial Seal Air</b> (Don. P533930)... <b>RS3548</b> <b>Radial Seal XP Air</b> (Don. P533930)..... <b>RS3548XP</b>
	Acterra 7500 w/Cat C7 (7.2L) Eng. (To 1/2004) <b>Lube</b> (Standard Vers.) (1R0739).. <b>B76 +</b> <b>Lube</b> (Severe Service) (1R0739).. <b>B76-SS +</b> <b>In-Line Fuel</b> (9R9925)..... <b>BF1173</b> <b>Fuel Spin-on</b> (1R0751)..... <b>BF7632</b> <b>Radial Seal XP Air</b> (Don. EAF5067)..... <b>RS2863XP</b>	Acterra 7500 w/Mercedes-Benz MBE906 (6.4L) Eng. <b>F-F Lube</b> (1801709)..... <b>P7188</b> <b>Opt. B-P Lube Spinner</b> (A9061810086)..... <b>BC7326 +</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Fuel</b> (A5410920305)..... <b>PF7761</b> <b>Radial Seal Air</b> (Don. P533930)... <b>RS3548</b> <b>Radial Seal XP Air</b> (Don. P533930)..... <b>RS3548XP</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

STERLING Trucks (cont'd)	STERLING Trucks (cont'd)	STERLING Trucks (cont'd)
Acterra 7500 w/Mercedes-Benz MBE906 (6.4L) Eng. (Cont'd) Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Acterra 8500 w/Cummins ISB (5.9L) Eng. (Cont'd) Cab Air (Fresh Air) (F6HZ-19N619-AA)..... <b>PA5337</b> Cab Air (Recirculation) (F6HZ-19N619-BA)..... <b>PA5393</b> Air Dryer (Bendix 65624)..... <b>BA5373</b> Crankcase Breather (2007-on) (4936636)..... <b>CV15010</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Steering (VML/T1808D)..... <b>BT9388</b> Some Rear Axle (Meritor 3280-V-5040)..... <b>B27</b>	Acterra 8500 w/Cummins NTC (14.0L) Eng. Dual-Flow Lube (3318853)..... <b>BD103 +</b> F-F Lube Ele. (158139)..... <b>P999-HD</b> F-F Lube Spin-on (3313279)..... <b>B196 +</b> B-P Lube Ele. (256838)..... <b>C750-E +</b> B-P Lube Spin-on (3313283)..... <b>B7577</b> Fuel/Water Separator (3308638)..... <b>BF1212 +</b> Fuel (158172)..... <b>BF957 +</b>
Acterra 8500 w/Cat C7 Eng. (To 1/2004) Lube (Standard Vers.) (1R0739).. <b>B76 +</b> Lube (Severe Service) (1R0739).. <b>B76-SS +</b> Fuel/Water Separator (Motorcraft FD4597)..... <b>BF7806</b> In-Line Fuel (9R9925)..... <b>BF1173</b> Fuel Spin-on (1R0751)..... <b>BF7632</b> Radial Seal XP Air (Don. EAF5067)..... <b>RS2863XP</b>	Acterra 8500 w/Cat C7 Eng. (1/2004-on) Lube (1R1807)..... <b>B7700 +</b> Fuel/Water Separator (Motorcraft FD4597)..... <b>BF7806</b> In-Line Fuel (9R9925)..... <b>BF1173</b> Fuel Spin-on (1R0751)..... <b>BF7632</b> Radial Seal XP Air (Don. EAF5067)..... <b>RS2863XP</b>	Acterra 8500 w/Detroit Diesel Series 55 (12.0L) Eng. Lube (23550401)..... <b>B7135</b> Fuel (23530707)..... <b>BF5810</b>
Acterra 8500 w/Cat C7 Eng. (1/2004-on) Lube (1R1807)..... <b>B7700 +</b> Fuel/Water Separator (Motorcraft FD4597)..... <b>BF7806</b> In-Line Fuel (9R9925)..... <b>BF1173</b> Fuel Spin-on (1R0751)..... <b>BF7632</b> Radial Seal XP Air (Don. EAF5067)..... <b>RS2863XP</b>	Acterra 8500 w/Mercedes-Benz MBE906 (6.4L) Eng. F-F Lube Ele. (1801709)..... <b>P7188</b> Opt. B-P Lube Spinner (A9061810086)..... <b>BC7326 +</b> Fuel (901551)..... <b>PF7735</b> Fuel (901351)..... <b>PF7974</b> Radial Seal XP Air (Don. EAF5067)..... <b>RS2863XP</b>	Acterra 8500 w/Mercedes-Benz MBE906 (6.4L) Eng. F-F Lube Ele. (1801709)..... <b>P7188</b> Opt. B-P Lube Spinner (A9061810086)..... <b>BC7326 +</b> Fuel (901551)..... <b>PF7735</b> Fuel (901351)..... <b>PF7974</b> Radial Seal XP Air (Don. EAF5067)..... <b>RS2863XP</b>
Acterra 8500 w/Cat 3126 (7.2L) Eng. Lube (Standard Vers.)..... <b>B76</b> Fuel/Water Separator (1752949)..... <b>BF1268</b> Fuel/Water Separator (w/Sensor Port) (1986378)..... <b>BF7798-SP</b> Fuel/Water Separator (Open End for Bowl) (1986378)..... <b>BF7798-O</b> Fuel/Water Separator (Fleetguard FS1000)..... <b>BF1259</b> Fuel Ele. (9M2342)..... <b>[2] PF935</b> Fuel Spin-on (1R0751)..... <b>BF7632</b> Fuel (1R0759)..... <b>BF7634</b> Coolant (2266565)..... <b>BW5071</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Acterra 8500 w/Cummins ISC 8.3 (8.3L) Eng. Dual-Flow Lube..... <b>BD7309 +</b> F-F Lube (Fleetguard LF3970).... <b>B7177</b> Fuel/Water Separator Ele. (Fleetguard FS19579)..... <b>PF7777</b> Fuel/Water Separator Spin-on (Fleetguard FS1022)..... <b>BF1272-SPS</b> Fuel (Fleetguard FF5636)..... <b>BF7924</b> Radial Seal Air (Don. P527484).... <b>RS2863</b> Radial Seal XP Air (Don. P527484)..... <b>RS2863XP</b> Cab Air (Fresh Air) (F6HZ-19N619-AA)..... <b>PA5337</b> Cab Air (Recirculation) (F6HZ-19N619-BA)..... <b>PA5393</b> Air Dryer (Bendix 65624)..... <b>BA5373</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Steering (VML/T1808D)..... <b>BT9388</b> Some Rear Axle (Meritor 3280-V-5040)..... <b>B27</b>	Acterra 8500 w/Mercedes-Benz MBE906 (6.4L) Eng. A-Line w/Cat C9 Eng. Lube (To 1/2004) (1R0716)..... <b>B99 +</b> Lube (1/2004-on) (1R1808)..... <b>B7299 +</b> Fuel/Water Separator Ele. (Don. P550467)..... <b>PF7748</b> Fuel/Water Separator Spin-on (1752949)..... <b>BF1268</b> Fuel (1R0751)..... <b>BF7632</b> Radial Seal Air (Don. P533930).... <b>RS3548</b> Radial Seal XP Air (Don. P533930)..... <b>RS3548XP</b> Cab Air (Fresh Air) (F6HZ19N619AA)..... <b>PA5337</b> Cab Air (Recirculation) (F6HZ19N619BA)..... <b>PA5393</b> Coolant (Fleetguard WF2077)..... <b>B5134 +</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Trans. Breather..... <b>CLN&amp;R</b> Steering (Nelson 87904M)..... <b>PT9354-MPG</b> Some Rear Axle (Meritor 3280-V-5040)..... <b>B27</b>
Acterra 8500 w/Cummins 6BT5.9 (5.9L) Eng. Lube (Chrysler 5083285AA)..... <b>BT7349</b> Fuel/Water Separator (3925274)..... <b>BF1280 +</b> Fuel (3903640)..... <b>BF788</b>	Acterra 8500 w/Cummins 6CT8.3 (8.3L) Eng. F-F Lube (3313281)..... <b>B205 +</b> Dual-Flow Lube (3318853)..... <b>BD103 +</b> Fuel/Water Separator (3903410)..... <b>BF1280 +</b> Fuel/Water Separator (3286503)..... <b>BF1226</b> Fuel Spin-on (3903640)..... <b>BF788</b>	Acterra 8500 w/Cummins 6CT8.3 (8.3L) Eng. Lube (To 1/2004) (1R0716)..... <b>B99 +</b> Lube (1/2004-on) (1R1808)..... <b>B7299 +</b> Fuel/Water Separator Ele. (Davco 382114)..... <b>PF7748</b> Fuel/Water Separator (Alliance ABPN122R50418)..... <b>BF9898-O</b> Fuel/Water Separator Spin-on (Alliance S3226FL02)..... <b>BF1346 +</b> Fuel (1R0749)..... <b>BF7587 +</b> Radial Seal Air (Don. P533930).... <b>RS3548</b> Radial Seal XP Air (Don. P533930)..... <b>RS3548XP</b> Cab Air (Fresh Air) (F6HZ19N619AA)..... <b>PA5337</b>
Acterra 8500 w/Cummins ISB (5.9L) Eng. Lube (Fleetguard LF3970)..... <b>B7177</b> Fuel/Water Separator (Fleetguard FS19579)..... <b>PF7777</b> Fuel (Fleetguard FF5632)..... <b>BF7940</b> Radial Seal Air (Don. P527484).... <b>RS2863</b> Radial Seal XP Air (Don. P527484)..... <b>RS2863XP</b>	Acterra 8500 w/Cummins ISB (5.9L) Eng. (Cont'd) Cab Air (Fresh Air) (F6HZ-19N619-AA)..... <b>PA5337</b> Cab Air (Recirculation) (F6HZ-19N619-BA)..... <b>PA5393</b> Air Dryer (Bendix 65624)..... <b>BA5373</b> Crankcase Breather (2007-on) (4936636)..... <b>CV15010</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Steering (VML/T1808D)..... <b>BT9388</b> Some Rear Axle (Meritor 3280-V-5040)..... <b>B27</b>	Acterra 8500 w/Mercedes-Benz MBE906 (6.4L) Eng. A-Line w/Cat C11 Eng. Lube (To 1/2004) (1R0716)..... <b>B99 +</b> Lube (1/2004-on) (1R1808)..... <b>B7299 +</b> Fuel/Water Separator Ele. (Davco 382114)..... <b>PF7748</b> Fuel/Water Separator (Alliance ABPN122R50418)..... <b>BF9898-O</b> Fuel/Water Separator Spin-on (Alliance S3226FL02)..... <b>BF1346 +</b> Fuel (1R0749)..... <b>BF7587 +</b> Radial Seal Air (Don. P533930).... <b>RS3548</b> Radial Seal XP Air (Don. P533930)..... <b>RS3548XP</b> Cab Air (Fresh Air) (F6HZ19N619AA)..... <b>PA5337</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

STERLING Trucks (cont'd)	STERLING Trucks (cont'd)	STERLING Trucks (cont'd)
A-Line w/Cat C11 Eng. (Cont'd)	A-Line w/Cat C15 Eng. (Cont'd)	A-Line w/Mercedes-Benz MBE4000 Eng.
<b>Cab Air</b> (Recirculation)	<b>Fuel/Water Separator Spin-on</b>	<b>Lube</b> (1802109)..... P7230
(F6HZ19N619BA)..... PA5393	(w/Sensor Port) (Racor S3226P).. BF1346-SP	<b>Fuel/Water Separator Ele.</b> (Don.
<b>Coolant</b> (Fleetguard WF2077)..... B5134 +	<b>Fuel</b> (1R0749)..... BF7587 +	P550467)..... PF7748
<b>Opt. Trans.</b> (Fuller 17237)..... B2 +	<b>Radial Seal O. Air</b> (Standard)	<b>Fuel/Water Separator Spin-on</b> ..... BF1259
<b>Trans. Breather</b> ..... CLN&R	(Fleetguard AF25139M)..... RS3518	<b>Fuel</b> (5410900151)..... PF7761
<b>Steering</b> (Nelson 87904M)..... PT9354-MPG	<b>Radial Seal XP O. Air</b> (Upgrade)	<b>15 1/4 In. Radial Seal Air</b>
<b>Some Rear Axle</b> (Meritor	(DBA5069)..... RS3518XP	(Standard) (Don. P527682)..... RS3518
3280-V-5040)..... B27	<b>Radial Seal I. Air</b> (Fleetguard	<b>15 1/4 In. Radial Seal XP Air</b>
A-Line w/Cat C13 Eng.	AF25345)..... RS3519	(Upgrade) (Don. P527682)..... RS3518XP
<b>Lube</b> (To 1/2004) (1R0716)..... B99 +	<b>Single Radial Seal Air</b> (Don.	<b>17 9/32 In. Radial Seal Air</b> (Don.
<b>Lube</b> (1/2004-on) (1R1808)..... B7299 +	P533814)..... RS3749	P533814)..... RS3749
<b>Fuel/Water Separator Ele.</b>	<b>Cab Air</b> (Fresh Air)	<b>Cab Air</b> (Fresh Air)
(Davco 382114)..... PF7748	(F6HZ19N619AA)..... PA5337	(F6HZ19N619AA)..... PA5337
<b>Fuel/Water Separator Spin-on</b>	<b>Cab Air</b> (Recirculation)	<b>Cab Air</b> (Recirculation)
(Open End for Bowl) (Racor	(F6HZ19N619BA)..... PA5393	(F6HZ19N619BA)..... PA5393
S3226P)..... BF1346-O	<b>Air Dryer</b> (Bendix 107796)..... BA5377	<b>Air Dryer</b> (Bendix 107796)..... BA5377
<b>Fuel/Water Separator Spin-on</b>	<b>Breather</b> (296-8325)..... CV15008	<b>Coolant</b> (Nalcool NF2088)..... BW5200
(w/Drain) (Racor S3226P)..... BF1346	<b>Coolant</b> (9N3368)..... BW5137	<b>Opt. Trans.</b> (Fuller 17237)..... B2 +
<b>Fuel/Water Separator Spin-on</b>	<b>Trans.</b> (Fuller 4304827)..... BT223	<b>Trans.</b> (Fuller 4304827)..... BT223
(w/Sensor Port) (Racor S3226P).. BF1346-SP	<b>Opt. Trans.</b> (Fuller 17237)..... B2 +	<b>Trans. Breather</b> ..... CLN&R
<b>Fuel</b> (1R0749)..... BF7587 +	<b>Trans. Breather</b> ..... CLN&R	<b>Steering</b> (Nelson 87904M)..... PT9354-MPG
<b>15 5/8 In. Radial Seal Air</b> (Don.	<b>Steering</b> (Nelson 87904M)..... PT9354-MPG	<b>Steering</b> (VML/T1808D)..... BT9388
P533930)..... RS3548	<b>Steering</b> (VML/T1808D)..... BT9388	<b>Some Rear Axle</b> (Meritor
<b>15 5/8 In. Radial Seal XP Air</b>	<b>Some Rear Axle</b> (Meritor	3280-V-5040)..... B27
(Don. P533930)..... RS3548XP	3280-V-5040)..... B27	A-Line A9500 w/Cat C9 Eng. (To 1/2004)
<b>17 9/32 In. Radial Seal Air</b> (Don.	A-Line w/Detroit Diesel Series 60 Eng.	<b>Lube</b> (1R0716)..... B99 +
P533814)..... RS3749	<b>Lube</b> (23530573)..... [2] B495	<b>Fuel/Water Separator Ele.</b> (Don.
<b>Cab Air</b> (Fresh Air)	<b>Fuel/Water Separator Ele.</b>	P550467)..... PF7748
(F6HZ19N619AA)..... PA5337	(Davco 382114)..... PF7748	<b>Fuel/Water Separator Spin-on</b>
<b>Cab Air</b> (Recirculation)	<b>Fuel/Water Separator</b> (Alliance	(1752949)..... BF1268
(F6HZ19N619BA)..... PA5393	ABP/N122-BR90FRT10)..... BF9871-O	<b>Fuel</b> (1R0751)..... BF7632
<b>Air Dryer</b> (Bendix 107796)..... BA5377	<b>P. Fuel</b> (23530706)..... BF5800 +	<b>Radial Seal Air</b> (Don. P533930)... RS3548
<b>Breather</b> (2007-on) (296-8325)... CV15008	<b>S. Fuel</b> (To 12/03) (23518482)..... BF5810	<b>Radial Seal XP Air</b> (Don.
<b>Coolant</b> (w/o Chemical)	<b>S. Fuel</b> (12/03-on) (23530645)..... BF5815	P533930)..... RS3548XP
(Fleetguard WF2077)..... B5134 +	<b>S. Fuel</b> (12/03-on) (23533726)..... BF5816	<b>Cab Air</b> (Fresh Air)
<b>Coolant</b> (w/Chemical)	<b>15 1/4 In. Radial Seal Air</b>	(F6HZ19N619AA)..... PA5337
(Fleetguard WF2071)..... BW5071	(Standard) (Don. P527682)..... RS3518	<b>Cab Air</b> (Recirculation)
<b>Opt. Trans.</b> (Fuller 17237)..... B2 +	<b>15 1/4 In. Radial Seal XP Air</b>	(F6HZ19N619BA)..... PA5393
<b>Trans.</b> (Fuller 4304827)..... BT223	(Upgrade) (Don. P527682)..... RS3518XP	<b>Coolant</b> (Fleetguard WF2077)..... B5134 +
<b>Trans. Breather</b> ..... CLN&R	<b>17 9/32 In. Radial Seal Air</b> (Don.	<b>Opt. Trans.</b> (Fuller 17237)..... B2 +
<b>Steering</b> (Nelson 87904M)..... PT9354-MPG	P533814)..... RS3749	<b>Trans. Breather</b> ..... CLN&R
<b>Steering</b> (VML/T1808D)..... BT9388	<b>Cab Air</b> (Fresh Air)	<b>Steering</b> (Nelson 87904M)..... PT9354-MPG
<b>Some Rear Axle</b> (Meritor	(F6HZ19N619AA)..... PA5337	<b>Some Rear Axle</b> (Meritor
3280-V-5040)..... B27	<b>Cab Air</b> (Recirculation)	3280-V-5040)..... B27
A-Line w/Cat C15 Eng.	(F6HZ19N619BA)..... PA5393	A-Line A9500 w/Cat C9 Eng. (1/2004-on)
<b>Lube</b> (To 1/2004) (1R0716)..... B99 +	<b>Air Dryer</b> (Bendix 107796)..... BA5377	<b>Lube</b> (1R1808)..... B7299 +
<b>Lube</b> (1/2004-on) (1R1808)..... B7299 +	<b>Coolant</b> (w/o Chemical)	<b>Fuel/Water Separator Ele.</b> (Don.
<b>Fuel/Water Separator Ele.</b>	(Fleetguard WF2077)..... B5134 +	P550467)..... PF7748
(Fleetguard FS1029)..... PF7680	<b>Coolant</b> (w/Chemical) (Nalcool	<b>Fuel/Water Separator Spin-on</b>
<b>Fuel/Water Separator Ele.</b>	NF2088)..... BW5200	(1752949)..... BF1268
(Fleetguard FS19624)..... PF7748	<b>Opt. Trans.</b> (Fuller 17237)..... B2 +	<b>Fuel</b> (1R0751)..... BF7632
<b>Fuel/Water Separator Spin-on</b>	<b>Trans.</b> (Fuller 4304827)..... BT223	<b>Radial Seal Air</b> (Don. P533930)... RS3548
(Open End for Bowl) (Racor	<b>Trans. Breather</b> ..... CLN&R	<b>Radial Seal XP Air</b> (Don.
S3226P)..... BF1346-O	<b>Steering</b> (Nelson 87904M)..... PT9354-MPG	P533930)..... RS3548XP
<b>Fuel/Water Separator Spin-on</b>	<b>Steering</b> (VML/T1808D)..... BT9388	<b>Cab Air</b> (Fresh Air)
(w/Drain) (17001-4406)..... BF1259	<b>Some Rear Axle</b> (Meritor	(F6HZ19N619AA)..... PA5337
<b>Fuel/Water Separator Spin-on</b>	3280-V-5040)..... B27	<b>Cab Air</b> (Recirculation)
(w/Drain) (Racor S3226P)..... BF1346		(F6HZ19N619BA)..... PA5393

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

STERLING Trucks (cont'd)	STERLING Trucks (cont'd)	STERLING Trucks (cont'd)
A-Line A9500 w/Cat C9 Eng. (1/2004-on) (Cont'd)	A-Line A9500 w/Cat C13 Eng. (To 1/2004) (Cont'd)	A-Line A9500 w/Cat C15 Eng. (To 1/2004) (Cont'd)
Coolant (Fleetguard WF2077)..... B5134 +	Fuel (1R0749)..... BF7587 +	Some Rear Axle (Meritor 3280-V-5040)..... B27
Opt. Trans. (Fuller 17237)..... B2 +	Radial Seal Air (Don. P533930)... RS3548	A-Line A9500 w/Cat C15 Eng. (1/2004-on)
Trans. Breather..... CLN&R	Radial Seal XP Air (Don. P533930)..... RS3548XP	Lube (1R1808)..... B7299 +
Steering (Nelson 87904M)..... PT9354-MPG	Cab Air (Fresh Air (F6HZ19N619AA)..... PA5337	Fuel/Water Separator Ele. (Davco 382114)..... PF7748
Some Rear Axle (Meritor 3280-V-5040)..... B27	Cab Air (Recirculation) (F6HZ19N619BA)..... PA5393	Fuel (1R0749)..... BF7587 +
A-Line A9500 w/Cat C11 Eng. (To 1/2004)	Coolant (Fleetguard WF2071)..... BW5071	Radial Seal Air (Standard) (Don. P527682)..... RS3518
Lube (1R0716)..... B99 +	Opt. Trans. (Fuller 17237)..... B2 +	Radial Seal XP Air (Upgrade) (Don. P527682)..... RS3518XP
Fuel/Water Separator (Fleetguard FS19624)..... PF7748	Trans. Breather..... CLN&R	Cab Air (Fresh Air) (F6HZ19N619AA)..... PA5337
Fuel/Water Separator (Alliance ABPN122R50418)..... BF9898-O	Steering (Nelson 87904M)..... PT9354-MPG	Cab Air (Recirculation) (F6HZ19N619BA)..... PA5393
Fuel (1R0749)..... BF7587 +	Some Rear Axle (Meritor 3280-V-5040)..... B27	Coolant (9Y-1022)..... BW5139
Radial Seal Air (Don. P533930)... RS3548	A-Line A9500 w/Cat C13 Eng. (1/2004-on)	Opt. Trans. (Fuller 17237)..... B2 +
Radial Seal XP Air (Don. P533930)..... RS3548XP	Lube (1R1808)..... B7299 +	Trans. Breather..... CLN&R
Cab Air (Fresh Air) (F6HZ19N619AA)..... PA5337	Fuel/Water Separator Ele. (Davco 382114)..... PF7748	Steering (Nelson 87904M)..... PT9354-MPG
Cab Air (Recirculation) (F6HZ19N619BA)..... PA5393	Fuel/Water Separator Spin-on (Open End for Bowl) (Racor S3226P)..... BF1346-O	Some Rear Axle (Meritor 3280-V-5040)..... B27
Coolant (Fleetguard WF2077)..... B5134 +	Fuel/Water Separator Spin-on (w/Drain) (Racor S3226P)..... BF1346	A-Line A9500 w/Detroit Diesel Series 60 Eng. (To 12/2003)
Opt. Trans. (Fuller 17237)..... B2 +	Fuel/Water Separator Spin-on (w/Sensor Port) (Racor S3226P).. BF1346-SP	Some Lube (23530573)..... [2] B495
Trans. Breather..... CLN&R	Fuel (1R0749)..... BF7587 +	Fuel/Water Separator (Davco 382114)..... PF7748
Steering (Nelson 87904M)..... PT9354-MPG	Radial Seal Air (Don. P533930)... RS3548	P. Fuel (23518481)..... BF5800 +
Some Rear Axle (Meritor 3280-V-5040)..... B27	Radial Seal XP Air (Don. P533930)..... RS3548XP	S. Fuel (23518482)..... BF5810
A-Line A9500 w/Cat C11 Eng. (1/2004-on)	Cab Air (Fresh Air) (F6HZ19N619AA)..... PA5337	Radial Seal Air (Standard) (Don. P527682)..... RS3518
Lube (1R1808)..... B7299 +	Cab Air (Recirculation) (F6HZ19N619BA)..... PA5393	Radial Seal XP Air (Upgrade) (Don. P527682)..... RS3518XP
Fuel/Water Separator (Fleetguard FS19624)..... PF7748	Coolant (Fleetguard WF2071)..... BW5071	Cab Air (Fresh Air) (F6HZ19N619AA)..... PA5337
Fuel/Water Separator (Alliance ABPN122R50418)..... BF9898-O	Opt. Trans. (Fuller 17237)..... B2 +	Cab Air (Recirculation) (F6HZ19N619BA)..... PA5393
Fuel (1R0749)..... BF7587 +	Trans. Breather..... CLN&R	Opt. Trans. (Fuller 17237)..... B2 +
Radial Seal Air (Don. P533930)... RS3548	Steering (Nelson 87904M)..... PT9354-MPG	Trans. Breather..... CLN&R
Radial Seal XP Air (Don. P533930)..... RS3548XP	Some Rear Axle (Meritor 3280-V-5040)..... B27	Steering (Nelson 87904M)..... PT9354-MPG
Cab Air (Fresh Air) (F6HZ19N619AA)..... PA5337	A-Line A9500 w/Cat C15 Eng. (To 1/2004)	Some Rear Axle (Meritor 3280-V-5040)..... B27
Cab Air (Recirculation) (F6HZ19N619BA)..... PA5393	Lube (1R0716)..... B99 +	A-Line A9500 w/Detroit Diesel Series 60 Eng. (12/2003-on)
Coolant (Fleetguard WF2077)..... B5134 +	Fuel/Water Separator Ele. (Davco 382114)..... PF7748	Some Lube (23530573)..... [2] B495
Opt. Trans. (Fuller 17237)..... B2 +	Fuel (1R0749)..... BF7587 +	Fuel/Water Separator (Davco 382114)..... PF7748
Trans. Breather..... CLN&R	Radial Seal Air (Standard) (Don. P527682)..... RS3518	P. Fuel (23518481)..... BF5800 +
Steering (Nelson 87904M)..... PT9354-MPG	Radial Seal XP Air (Upgrade) (Don. P527682)..... RS3518XP	S. Fuel (23533726)..... BF5816
Some Rear Axle (Meritor 3280-V-5040)..... B27	Cab Air (Fresh Air) (F6HZ19N619AA)..... PA5337	Radial Seal Air (Standard) (Don. P527682)..... RS3518
A-Line A9500 w/Cat C13 Eng. (To 1/2004)	Cab Air (Recirculation) (F6HZ19N619BA)..... PA5393	Radial Seal XP Air (Upgrade) (Don. P527682)..... RS3518XP
Lube (1R0716)..... B99 +	Coolant (9Y-1022)..... BW5139	Cab Air (Fresh Air) (F6HZ19N619AA)..... PA5337
Fuel/Water Separator Ele. (Davco 382114)..... PF7748	Opt. Trans. (Fuller 17237)..... B2 +	Cab Air (Recirculation) (F6HZ19N619BA)..... PA5393
Fuel (1R0749)..... BF7587 +	Trans. Breather..... CLN&R	
Radial Seal Air (Standard) (Don. P527682)..... RS3518	Steering (Nelson 87904M)..... PT9354-MPG	
Radial Seal XP Air (Upgrade) (Don. P527682)..... RS3518XP		
Cab Air (Fresh Air) (F6HZ19N619AA)..... PA5337		
Cab Air (Recirculation) (F6HZ19N619BA)..... PA5393		
Coolant (9Y-1022)..... BW5139		
Opt. Trans. (Fuller 17237)..... B2 +		
Trans. Breather..... CLN&R		
Steering (Nelson 87904M)..... PT9354-MPG		

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

STERLING Trucks (cont'd)	STERLING Trucks (cont'd)	STERLING Trucks (cont'd)
A-Line A9500 w/Detroit Diesel Series 60 Eng. (12/2003-on) (Cont'd)	A-Line AT9500 w/Cat C11 Eng. (To 1/2004)	A-Line AT9500 w/Cat C13 Eng. (To 1/2004) (Cont'd)
Opt. Trans. (Fuller 17237)..... B2 +	Lube (1R0716)..... B99 +	Some Rear Axle (Meritor 3280-V-5040)..... B27
Trans. Breather..... CLN&R	Fuel/Water Separator Ele. (Davco 382114)..... PF7748	A-Line AT9500 w/Cat C13 Eng. (1/2004-on)
Steering (Nelson 87904M)..... PT9354-MPG	Fuel/Water Separator Spin-on (Alliance S3226FL02)..... BF1346 +	Lube (1R1808)..... B7299 +
Some Rear Axle (Meritor 3280-V-5040)..... B27	Fuel (1R0749)..... BF7587 +	Fuel/Water Separator Ele. (Fleetguard FS19624)..... PF7748
A-Line A9500 w/Mercedes Benz MBE4000 Eng.	Radial Seal Air (Fleetguard AF25354)..... RS3548	Fuel (1R0749)..... BF7587 +
Lube (1802109)..... P7230	Radial Seal XP Air (Fleetguard AF25354)..... RS3548XP	15 5/8 In. Radial Seal Air (Fleetguard AF25354)..... RS3548
Fuel/Water Separator Ele. (Don. P550467)..... PF7748	Cab Air (Fresh Air) (F6HZ19N619AA)..... PA5337	15 5/8 In. Radial Seal XP Air (Fleetguard AF25354)..... RS3548XP
Fuel (5410900151)..... PF7761	Cab Air (Recirculation) (F6HZ19N619BA)..... PA5393	17 9/32 In. Radial Seal Air (Don. P533814)..... RS3749
Radial Seal Air (Standard) (Don. P527682)..... RS3518	Coolant (Fleetguard WF2077)..... B5134 +	Cab Air (Fresh Air) (F6HZ19N619AA)..... PA5337
Radial Seal XP Air (Upgrade) (Don. P527682)..... RS3518XP	Opt. Trans. (Fuller 17237)..... B2 +	Cab Air (Recirculation) (F6HZ19N619BA)..... PA5393
Cab Air (Fresh Air) (F6HZ19N619AA)..... PA5337	Steering (Nelson 87904M)..... PT9354-MPG	Air Dryer (Bendix 107796)..... BA5377
Cab Air (Recirculation) (F6HZ19N619BA)..... PA5393	A-Line AT9500 w/Cat C11 Eng. (1/2004-on)	Breather (296-8325)..... CV15008
Opt. Trans. (Fuller 17237)..... B2 +	Lube (1R1808)..... B7299 +	Coolant (Fleetguard WF2077)..... B5134 +
Trans. Breather..... CLN&R	Fuel/Water Separator Ele. (Davco 382114)..... PF7748	Trans. (Fuller 4304827)..... BT223
Steering (Nelson 87904M)..... PT9354-MPG	Fuel/Water Separator Spin-on (Alliance S3226FL02)..... BF1346 +	Opt. Trans. (Fuller 17237)..... B2 +
Some Rear Axle (Meritor 3280-V-5040)..... B27	Fuel (1R0749)..... BF7587 +	Steering (Nelson 87904M)..... PT9354-MPG
A-Line AT9500 w/Cat C9 Eng. (1/2004-on)	Radial Seal Air (Fleetguard AF25354)..... RS3548	Steering (VML/T1808D)..... BT9388
Lube (1R1808)..... B7299 +	Radial Seal XP Air (Fleetguard AF25354)..... RS3548XP	Some Rear Axle (Meritor 3280-V-5040)..... B27
Fuel/Water Separator Ele. (Don. P550467)..... PF7748	Cab Air (Fresh Air) (F6HZ19N619AA)..... PA5337	A-Line AT9500 w/Cat C15 Eng. (To 1/2004)
Fuel (1R0751)..... BF7632	Cab Air (Recirculation) (F6HZ19N619BA)..... PA5393	Lube..... B99 +
Radial Seal Air (Don. P533930)..... RS3548	Coolant (Fleetguard WF2077)..... B5134 +	Fuel/Water Separator Ele. (Fleetguard FS1029)..... PF7680
Radial Seal XP Air (Don. P533930)..... RS3548XP	Opt. Trans. (Fuller 17237)..... B2 +	Fuel/Water Separator Ele. (Fleetguard FS19624)..... PF7748
Cab Air (Fresh Air) (F6HZ19N619AA)..... PA5337	Steering (Nelson 87904M)..... PT9354-MPG	Fuel Spin-on (1R0749)..... BF7587 +
Cab Air (Recirculation) (F6HZ19N619BA)..... PA5393	A-Line AT9500 w/Cat C13 Eng. (To 1/2004)	15 1/4 In. Radial Seal Air (Standard) (Don. P527682)..... RS3518
Coolant (Fleetguard WF2077)..... B5134 +	Lube (1R0716)..... B99 +	15 1/4 In. Radial Seal XP Air (Upgrade) (Don. P527682)..... RS3518XP
Opt. Trans. (Fuller 17237)..... B2 +	Fuel/Water Separator Ele. (Fleetguard FS19624)..... PF7748	17 9/32 In. Radial Seal Air (Don. P533814)..... RS3749
Steering (Nelson 87904M)..... PT9354-MPG	Fuel (1R0749)..... BF7587 +	Cab Air (Fresh Air) (F6HZ19N619AA)..... PA5337
A-Line AT9500 w/Cat C9 Eng. (To 1/2004)	15 5/8 In. Radial Seal Air (Fleetguard AF25354)..... RS3548	Cab Air (Recirculation) (F6HZ19N619BA)..... PA5393
Lube (1R0716)..... B99 +	15 5/8 In. Radial Seal XP Air (Fleetguard AF25354)..... RS3548XP	Air Dryer (Bendix 107796)..... BA5377
Fuel/Water Separator Ele. (Don. P550467)..... PF7748	17 9/32 In. Radial Seal Air (Don. P533814)..... RS3749	Breather (296-8325)..... CV15008
Fuel (1R0751)..... BF7632	Cab Air (Fresh Air) (F6HZ19N619AA)..... PA5337	Trans. (Fuller 4304827)..... BT223
Radial Seal Air (Don. P533930)..... RS3548	Cab Air (Recirculation) (F6HZ19N619BA)..... PA5393	Opt. Trans. (Fuller 17237)..... B2 +
Radial Seal XP Air (Don. P533930)..... RS3548XP	Coolant (Fleetguard WF2077)..... B5134 +	Steering (Nelson 87904M)..... PT9354-MPG
Cab Air (Fresh Air) (F6HZ19N619AA)..... PA5337	Trans. (Fuller 4304827)..... BT223	Steering (VML/T1808D)..... BT9388
Cab Air (Recirculation) (F6HZ19N619BA)..... PA5393	Opt. Trans. (Fuller 17237)..... B2 +	Some Rear Axle (Meritor 3280-V-5040)..... B27
Coolant (Fleetguard WF2077)..... B5134 +	Steering (Nelson 87904M)..... PT9354-MPG	A-Line AT9500 w/Cat C15 Eng. (1/2004-on)
Opt. Trans. (Fuller 17237)..... B2 +	Steering (VML/T1808D)..... BT9388	Lube (1R1808)..... B7299 +
Steering (Nelson 87904M)..... PT9354-MPG		Fuel/Water Separator Ele. (Fleetguard FS1029)..... PF7680
		Fuel/Water Separator Ele. (Fleetguard FS19624)..... PF7748

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

STERLING Trucks (cont'd)	STERLING Trucks (cont'd)	STERLING Trucks (cont'd)
A-Line AT9500 w/Cat C15 Eng. (1/2004-on) (Cont'd)	A-Line AT9500 w/Detroit Diesel Series 60 Eng. (12/2003-on) (Cont'd)	A9500 w/Cat C10 (10.3L) Eng. (Cont'd)
Fuel Spin-on (1R0749)..... BF7587 +	15 1/4 In. Radial Seal XP Air (Upgrade) (Don. P527682)..... RS3518XP	Fuel/Water Separator (w/Sensor Port) (1335673)..... BF1395-SP
15 1/4 In. Radial Seal Air (Standard) (Don. P527682)..... RS3518	Cab Air (Fresh Air) (F6HZ19N619AA)..... PA5337	Fuel/Water Separator Spin-on (1752949)..... BF1268
15 1/4 In. Radial Seal XP Air (Upgrade) (Don. P527682)..... RS3518XP	Cab Air (Recirculation) (F6HZ19N619BA)..... PA5393	Fuel Ele. (9M2342)..... [2] PF935
17 9/32 In. Radial Seal Air (Don. P533814)..... RS3749	Air Dryer (Bendix 107796)..... BA5377	Fuel Spin-on (Standard Vers.) (1R1712)..... BF614 +
Cab Air (Fresh Air) (F6HZ19N619AA)..... PA5337	Coolant (Fleetguard WF2077)..... B5134 +	Fuel Spin-on (High Efficiency Vers.) (1R0749)..... BF7587 +
Cab Air (Recirculation) (F6HZ19N619BA)..... PA5393	Trans. (Fuller 4304827)..... BT223	Coolant (w/4 Units BTE) (9N3717)..... BW5137
Air Dryer (Bendix 107796)..... BA5377	Opt. Trans. (Fuller 17237)..... B2 +	Coolant (w/8 Units BTE) (9N6123)..... BW5139
Breather (296-8325)..... CV15008	Steering (Nelson 87904M)..... PT9354-MPG	Trans. Spin-on (Fuller 4304827)..... BT223
Trans. (Fuller 4304827)..... BT223	Steering (VML/T1808D)..... BT9388	Opt. Trans. Spin-on (Fuller 17237)..... B2 +
Opt. Trans. (Fuller 17237)..... B2 +	Some Rear Axle (Meritor 3280-V-5040)..... B27	
Steering (Nelson 87904M)..... PT9354-MPG		A9500 w/Cat C12 (12.0L) Eng.
Steering (VML/T1808D)..... BT9388		F-F Lube (Std. Version) (1R0716)..... B99 +
Some Rear Axle (Meritor 3280-V-5040)..... B27	A-Line AT9500 w/Mercedes Benz MBE4000 Eng.	F-F Lube (High Efficiency Vers.) (1R1808)..... B7299 +
	Lube (1802109)..... P7230	B-P Lube (1W8845)..... B7577
A-Line AT9500 w/Detroit Diesel Series 60 Eng. (To 12/2003)	Fuel/Water Separator Ele. (Don. P550467)..... PF7748	Fuel/Water Separator Ele. (8N0205)..... PF316
Lube (23530573)..... [2] B495	Fuel (5410900151)..... PF7761	Fuel/Water Separator (Open End for Bowl) (1335673)..... BF1395-O
Fuel/Water Separator (Davco 382114)..... PF7748	Radial Seal Air (Don. P533814)..... RS3749	Fuel/Water Separator (w/Drain) (1335673)..... BF1265
P. Fuel (23530706)..... BF5800 +	Cab Air (Fresh Air) (F6HZ19N619AA)..... PA5337	Fuel/Water Separator (w/Sensor Port) (1335673)..... BF1395-SP
S. Fuel (23518482)..... BF5810	Cab Air (Recirculation) (F6HZ19N619BA)..... PA5393	Fuel/Water Separator (1752949)..... BF1268
15 1/4 In. Radial Seal Air (Standard) (Don. P527682)..... RS3518	Air Dryer (Bendix 107796)..... BA5377	Fuel/Water Separator (3261641)..... BF9903-SP
17 9/32 In. Radial Seal Air (Don. P533814)..... RS3749	Coolant (Nalcool NF2088)..... BW5200	Fuel/Water Separator Spin-on (2568753)..... BF1259
15 1/4 In. Radial Seal XP Air (Upgrade) (Don. P527682)..... RS3518XP	Trans. (Fuller 4304827)..... BT223	Fuel Ele. (9M2342)..... [2] PF935
Cab Air (Fresh Air) (F6HZ19N619AA)..... PA5337	Opt. Trans. (Fuller 17237)..... B2 +	Fuel Spin-on (Standard Vers.) (1R1712)..... BF614 +
Cab Air (Recirculation) (F6HZ19N619BA)..... PA5393	Steering (Nelson 87904M)..... PT9354-MPG	Fuel Spin-on (High Efficiency Vers.) (1R0749)..... BF7587 +
Air Dryer (Bendix 107796)..... BA5377	Steering (VML/T1808D)..... BT9388	Coolant (w/4 Units BTE) (9N3717)..... BW5137
Coolant (Fleetguard WF2077)..... B5134 +	Some Rear Axle (Meritor 3280-V-5040)..... B27	Coolant (w/8 Units BTE) (9N6123)..... BW5139
Trans. (Fuller 4304827)..... BT223		Trans. Spin-on (Fuller 4304827)..... BT223
Opt. Trans. (Fuller 17237)..... B2 +	A9500 w/Cat 3126 (7.2L) Eng.	Opt. Trans. Spin-on (Fuller 17237)..... B2 +
Steering (Nelson 87904M)..... PT9354-MPG	Lube (Standard Vers.) (1R0739)..... B76 +	
Steering (VML/T1808D)..... BT9388	Lube (Severe Service) (1R0739)..... B76-SS +	A9500 w/Cat C10 (10.3L) Eng.
Some Rear Axle (Meritor 3280-V-5040)..... B27	Fuel/Water Separator (1752949)..... BF1268	F-F Lube (Std. Version) (1R0716)..... B99 +
	Fuel/Water Separator (2568753)..... BF1259	F-F Lube (High Efficiency Vers.) (1R1808)..... B7299 +
	Fuel/Water Separator (w/Sensor Port) (1986378)..... BF7798-SP	B-P Lube (1W8845)..... B7577
	Fuel/Water Separator (Open End for Bowl) (1986378)..... BF7798-O	Fuel/Water Separator Ele. (8N0205)..... PF316
	Fuel Ele. (9M2342)..... [2] PF935	Fuel/Water Separator (Open End for Bowl) (1335673)..... BF1395-O
	Fuel Spin-on (1R0751)..... BF7632	Fuel/Water Separator (w/Drain) (1335673)..... BF1265
A-Line AT9500 w/Detroit Diesel Series 60 Eng. (12/2003-on)		A9500 w/Cat C16 (15.8L) Eng.
Lube (23530573)..... [2] B495		Lube (1R0716)..... B99 +
Fuel/Water Separator (Davco 382114)..... PF7748		Fuel/Water Separator (Open End for Bowl) (1335673)..... BF1395-O
P. Fuel (23530706)..... BF5800 +		Fuel/Water Separator (w/Drain) (1335673)..... BF1265
S. Fuel (23530645)..... BF5815		Fuel/Water Separator (w/Sensor Port) (1335673)..... BF1395-SP
S. Fuel (23533726)..... BF5816		Fuel/Water Separator (2568753)..... BF1259
15 1/4 In. Radial Seal Air (Standard) (Don. P527682)..... RS3518		Fuel Ele. (9M2342)..... [2] PF935
17 9/32 In. Radial Seal Air (Don. P533814)..... RS3749		Fuel Spin-on (Standard Vers.) (1R1712)..... BF614 +

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



STERLING Trucks (cont'd)	STERLING Trucks (cont'd)	STERLING Trucks (cont'd)
A9500 w/Cat C16 (15.8L) Eng. (Cont'd) <b>Fuel Spin-on</b> (High Efficiency Vers.) (1R0749)..... <b>BF7587 +</b>	A9500 w/Cummins N14 (14.0L) Eng. (Cont'd) <b>Fuel</b> (154789)..... <b>BF957-D +</b>	A9513 w/Cat C12 (12.0L) Eng. (Cont'd) <b>Fuel Spin-on</b> (Standard Vers.) (1R1712)..... <b>BF614 +</b>
A9500 w/Cummins ISL 8.9 (8.9L) Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b>	A9500 w/Cummins Signature 600 (15.0L) Eng. <b>11 25/32 In. Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154 +</b>	<b>Fuel Spin-on</b> (High Efficiency Vers.) (1R0749)..... <b>BF7587 +</b>
<b>Dual-Flow Lube</b> (Fleetguard LF9548)..... <b>BD324 +</b>	<b>14 7/32 In. Dual-Flow Lube</b> (Fleetguard LF9000)..... <b>BD7153 +</b>	<b>Coolant</b> (w/4 Units BTE) (9N3717)..... <b>BW5137</b>
<b>Fuel</b> (Fleetguard FF5488)..... <b>BF7815</b>	<b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>	<b>Coolant</b> (w/8 Units BTE) (9N6123)..... <b>BW5139</b>
<b>Fuel</b> (Fleetguard FF5636)..... <b>BF7924</b>	<b>Fuel/Water Separator</b> (3331096)..... <b>BF1274-SP</b>	A9513 w/Cummins M11 (10.8L) Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Fuel/Water Separator</b> (4010651)..... <b>BF1277-SPS</b>	<b>Fuel/Water Separator Spin-on</b> (3329289)..... <b>BF1259</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	A9500 w/Detroit Diesel DD13 (12.8L) Eng. <b>Lube</b> (A4731800109)..... <b>P7505</b>	<b>Coolant</b> (3318318)..... <b>BW5075</b>
A9500 w/Cummins ISM 10.8 (10.8L) Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154 +</b>	<b>Fuel Kit</b> (A0000904251)..... <b>PF9924 KIT</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Dual-Flow Lube</b> (Fleetguard LF9031)..... <b>BD7509 +</b>	<b>Coolant</b> (A4722030155)..... <b>P5092</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Dual-Flow Lube</b> (Fleetguard LF9000)..... <b>BD7153 +</b>	A9500 w/Detroit Diesel DD15 (14.8L) Eng. <b>Lube</b> (A4731800109)..... <b>P7505</b>	<b>Trans. Spin-on</b> (Fuller 4304827)..... <b>BT223</b>
<b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>	<b>Fuel Kit</b> (A0000904251)..... <b>PF9924 KIT</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Coolant</b> (A4722030155)..... <b>P5092</b>	A9513 w/Cummins N14 (14.0L) Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	A9513 w/Cat C10 (10.3L) Eng. <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99 +</b>	<b>F-F Lube</b> (Fleetguard LF670SC)..... <b>B196 +</b>
A9500 w/Cummins ISX 15.0 (14.9L) Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9070)..... <b>BD7153 +</b>	<b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b>	<b>B-P Lube</b> (3304232)..... <b>B7577</b>
<b>Dual-Flow Lube</b> (Fleetguard LF9080)..... <b>BD7154 +</b>	<b>B-P Lube</b> (1W8845)..... <b>B7577</b>	<b>Opt. Fuel/Water Separator</b> (3308638)..... <b>BF1212 +</b>
<b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>	<b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b>	<b>Fuel</b> (154789)..... <b>BF957-D +</b>
<b>Fuel/Water Separator Ele.</b> (Fleetguard FF5369W)..... <b>PF7744</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (1335673)..... <b>BF1395-O</b>	<b>Trans. Spin-on</b> (Fuller 4304827)..... <b>BT223</b>
<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19728)..... <b>PF7782</b>	<b>Fuel/Water Separator</b> (w/Drain) (1335673)..... <b>BF1265</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
<b>Fuel Spin-on</b> (Fleetguard FF2200)..... <b>BF7766</b>	<b>Fuel/Water Separator</b> (w/Sensor Port) (1335673)..... <b>BF1395-SP</b>	A9522 w/Cat C10 (10.3L) Eng. <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99 +</b>
<b>Fuel Spin-on</b> (Fleetguard FF2203)..... <b>BF7760</b>	<b>Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b>	<b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Fuel Spin-on</b> (Standard Vers.) (1R1712)..... <b>BF614 +</b>	<b>B-P Lube</b> (1W8845)..... <b>B7577</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Fuel Spin-on</b> (High Efficiency Vers.) (1R0749)..... <b>BF7587 +</b>	<b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b>
A9500 w/Cummins M11 (10.8L) Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b>	<b>Coolant</b> (w/4 Units BTE) (9N3717)..... <b>BW5137</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (1335673)..... <b>BF1395-O</b>
<b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b>	<b>Coolant</b> (w/8 Units BTE) (9N6123)..... <b>BW5139</b>	<b>Fuel/Water Separator</b> (w/Drain) (1335673)..... <b>BF1265</b>
<b>Fuel/Water Separator Spin-on</b> (3329289)..... <b>BF1259</b>	A9513 w/Cat C12 (12.0L) Eng. <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99 +</b>	<b>Fuel/Water Separator</b> (w/Sensor Port) (1335673)..... <b>BF1395-SP</b>
A9500 w/Cummins N14 (14.0L) Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b>	<b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b>	<b>Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b>
<b>F-F Lube</b> (Fleetguard LF670SC)..... <b>B196 +</b>	<b>B-P Lube</b> (1W8845)..... <b>B7577</b>	<b>Fuel Spin-on</b> (Standard Vers.) (1R1712)..... <b>BF614 +</b>
<b>B-P Lube</b> (3304232)..... <b>B7577</b>	<b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b>	<b>Fuel Spin-on</b> (High Efficiency Vers.) (1R0749)..... <b>BF7587 +</b>
<b>Opt. Fuel/Water Separator</b> (3308638)..... <b>BF1212 +</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (1335673)..... <b>BF1395-O</b>	<b>Coolant</b> (w/4 Units BTE) (9N3717)..... <b>BW5137</b>
	<b>Fuel/Water Separator</b> (w/Drain) (1335673)..... <b>BF1265</b>	<b>Coolant</b> (w/8 Units BTE) (9N6123)..... <b>BW5139</b>
	<b>Fuel/Water Separator</b> (w/Sensor Port) (1335673)..... <b>BF1395-SP</b>	A9500 w/Cat 3176 (10.3L) Eng. <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99 +</b>
	<b>Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b>	<b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

STERLING Trucks (cont'd)	STERLING Trucks (cont'd)	STERLING Trucks (cont'd)
AT9500 w/Cat 3176 (10.3L) Eng. (Cont'd) <b>Opt. B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Fuel/Water Separator Spin-on</b> (2568753)..... <b>BF1259</b> <b>P. Fuel Spin-on</b> (1R1740)..... <b>BF970 +</b> <b>S. Fuel Spin-on</b> (1R0750)..... <b>BF7633 +</b>	AT9500 w/Cat C12 (12.0L) Eng. (Cont'd) <b>Fuel Spin-on</b> (High Efficiency Vers.) (1R0749)..... <b>BF7587 +</b> <b>Coolant</b> (w/4 Units BTE) (9N3717)..... <b>BW5137</b> <b>Coolant</b> (w/8 Units BTE) (9N6123)..... <b>BW5139</b>	AT9500 w/Cummins M11 (10.8L) Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Fuel/Water Separator Ele.</b> (Davco 380087)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> (3329289)..... <b>BF1259</b>
AT9500 w/Cat 3406 (14.6L) Eng. <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99 +</b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> <b>Fuel/Water Separator Spin-on</b> (2568753)..... <b>BF1259</b> <b>P. Fuel Ele.</b> (9M2341)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (1R0749)..... <b>BF7587 +</b> <b>Fuel Spin-on</b> (1R0712)..... <b>BF614 +</b>	AT9500 w/Cat C16 (15.8L) Eng. <b>Lube</b> (1R0716)..... <b>B99 +</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (1335673)..... <b>BF1395-O</b> <b>Fuel/Water Separator</b> (w/Drain) (1335673)..... <b>BF1265</b> <b>Fuel/Water Separator</b> (2568753)..... <b>BF1259</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (1335673)..... <b>BF1395-SP</b> <b>Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (Standard Vers.) (1R1712)..... <b>BF614 +</b> <b>Fuel Spin-on</b> (High Efficiency Vers.) (1R0749)..... <b>BF7587 +</b>	AT9500 w/Cummins N14 (14.0L) Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Opt. Fuel/Water Separator</b> (3308638)..... <b>BF1212 +</b> <b>Fuel</b> (154789)..... <b>BF957-D +</b>
AT9500 w/Cat C10 (10.3L) Eng. <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99 +</b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> <b>B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (1335673)..... <b>BF1395-O</b> <b>Fuel/Water Separator</b> (w/Drain) (1335673)..... <b>BF1265</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (1335673)..... <b>BF1395-SP</b> <b>Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (Standard Vers.) (1R1712)..... <b>BF614 +</b> <b>Fuel Spin-on</b> (High Efficiency Vers.) (1R0749)..... <b>BF7587 +</b> <b>Coolant</b> (w/4 Units BTE) (9N3717)..... <b>BW5137</b> <b>Coolant</b> (w/8 Units BTE) (9N6123)..... <b>BW5139</b>	AT9500 w/Cummins ISC 8.3 (8.3L) Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Dual-Flow Lube</b> (Fleetguard LF9548)..... <b>BD324 +</b> <b>Fuel</b> (Fleetguard FF5488)..... <b>BF7815</b> <b>Fuel</b> (Fleetguard FF5636)..... <b>BF7924</b>	AT9500 w/Detroit Diesel Series 50 (8.5L) Eng. <b>Lube</b> (23530573)..... <b>[2] B495</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (23535985)..... <b>BF5813 +</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (23535985).. <b>BF5813-O +</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b>
AT9500 w/Cat C12 (12.0L) Eng. <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99 +</b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> <b>B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (1335673)..... <b>BF1395-O</b> <b>Fuel/Water Separator</b> (w/Drain) (1335673)..... <b>BF1265</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (1335673)..... <b>BF1395-SP</b> <b>Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (Standard Vers.) (1R1712)..... <b>BF614 +</b> <b>Fuel Spin-on</b> (High Efficiency Vers.) (1R0749)..... <b>BF7587 +</b> <b>Coolant</b> (w/4 Units BTE) (9N3717)..... <b>BW5137</b> <b>Coolant</b> (w/8 Units BTE) (9N6123)..... <b>BW5139</b>	AT9500 w/Cummins ISL 8.9 (8.9L) Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Dual-Flow Lube</b> (Fleetguard LF9548)..... <b>BD324 +</b> <b>Fuel</b> (Fleetguard FF5488)..... <b>BF7815</b> <b>Fuel</b> (Fleetguard FF5636)..... <b>BF7924</b>	AT9500 w/Detroit Diesel Series 55 (12.0L) Eng. <b>Lube</b> (23550401)..... <b>B7135</b> <b>Fuel</b> (23530707)..... <b>BF5810</b>
AT9500 w/Cat C10 (10.3L) Eng. <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99 +</b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> <b>B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (1335673)..... <b>BF1395-O</b> <b>Fuel/Water Separator</b> (w/Drain) (1335673)..... <b>BF1265</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (1335673)..... <b>BF1395-SP</b> <b>Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (Standard Vers.) (1R1712)..... <b>BF614 +</b> <b>Fuel Spin-on</b> (High Efficiency Vers.) (1R0749)..... <b>BF7587 +</b> <b>Coolant</b> (w/4 Units BTE) (9N3717)..... <b>BW5137</b> <b>Coolant</b> (w/8 Units BTE) (9N6123)..... <b>BW5139</b>	AT9500 w/Cummins ISM 10.8 (10.8L) Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154 +</b> <b>Dual-Flow Lube</b> (Fleetguard LF9031)..... <b>BD7509 +</b> <b>Dual-Flow Lube</b> (Fleetguard LF9000)..... <b>BD7153 +</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>	AT9513 w/Cat C10 (10.3L) Eng. <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99 +</b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> <b>B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (1335673)..... <b>BF1395-O</b> <b>Fuel/Water Separator</b> (w/Drain) (1335673)..... <b>BF1265</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (1335673)..... <b>BF1395-SP</b> <b>Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (Standard Vers.) (1R1712)..... <b>BF614 +</b> <b>Fuel Spin-on</b> (High Efficiency Vers.) (1R0749)..... <b>BF7587 +</b> <b>Coolant</b> (w/4 Units BTE) (9N3717)..... <b>BW5137</b> <b>Coolant</b> (w/8 Units BTE) (9N6123)..... <b>BW5139</b>
AT9500 w/Cat C12 (12.0L) Eng. <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99 +</b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> <b>B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (1335673)..... <b>BF1395-O</b> <b>Fuel/Water Separator</b> (w/Drain) (1335673)..... <b>BF1265</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (1335673)..... <b>BF1395-SP</b> <b>Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (Standard Vers.) (1R1712)..... <b>BF614 +</b>	AT9500 w/Cummins L10 (10.0L) Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Fuel/Water Separator</b> (3308638)..... <b>BF1212 +</b> <b>Fuel</b> (154789)..... <b>BF957-D +</b> <b>Coolant</b> (4 Units BTA PLUS) (3315116)..... <b>BW5071</b> <b>Coolant</b> (15 Units BTA PLUS) (3318318)..... <b>BW5075</b>	AT9513 w/Cummins N14 Eng. <b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Fuel/Water Separator</b> (3889716)..... <b>BF1259</b> <b>Fuel</b> (154789)..... <b>BF957-D +</b> <b>Radial Seal O. Air</b> (F6HZ-9601-CA)..... <b>RS3738</b> <b>Radial Seal I. Air</b> (F6HZ-9602-AA)..... <b>RS3739</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

STERLING Trucks (cont'd)	STERLING Trucks (cont'd)	STERLING Trucks (cont'd)
AT9513, AT9522 w/Cat 3406E Eng. Lube..... <b>B99 +</b> P. Fuel Ele..... <b>[2] PF935</b> Fuel Spin-on..... <b>BF7587 +</b>	Bullet 45, Bullet 55 w/6-408 (6.7L) Turbo Diesel Eng. Lube (Chrysler 5083285AA)..... <b>BT7349</b> Fuel/Water Separator (Ele. for Upgraded Hsg.) (68061634AA).... <b>PF1392</b> Fuel (Upgraded Hsg. w/Ele.) (5183410AA)..... <b>BF1392-SPS KIT</b> Air (53034051AB)..... <b>PA4318</b> Trans. (6 Spd.) (68019688AA)..... <b>20025</b>	Condor w/Cat C13 Eng. (To 1/2004) (Cont'd) Fuel (1R0749)..... <b>BF7587 +</b> Condor w/Cat C13 Eng. (1/2004-on) Lube (1R1808)..... <b>B7299 +</b> Fuel/Water Separator Spin-on (Open End for Bowl) (Racor S3226P)..... <b>BF1346-O</b> Fuel/Water Separator Spin-on (w/Drain) (Racor S3226P)..... <b>BF1346</b> Fuel/Water Separator Spin-on (w/Sensor Port) (Racor S3226P).. <b>BF1346-SP</b> Fuel (1R0749)..... <b>BF7587 +</b>
AT9513, AT9522 w/Cat C12 Eng. Lube (1R0716)..... <b>B99 +</b> Fuel Spin-on (1R0712)..... <b>BF614 +</b> Radial Seal Air (Don. P533930)... <b>RS3548</b> Radial Seal XP Air (Don. P533930)..... <b>RS3548XP</b>	Car Hauler w/Detroit Diesel Series 60 (14.0L) Eng. Lube (23518480)..... <b>[2] B495</b> Fuel/Water Separator Ele. (23529168)..... <b>PF7748</b> Fuel/Water Separator Spin-on (w/Drain) (23512317)..... <b>BF5813 +</b> Fuel/Water Separator Spin-on (Open End for Bowl) (23512317).. <b>BF5813-O +</b> P. Fuel (23530706)..... <b>BF5800 +</b> S. Fuel (23518482)..... <b>BF5810</b>	Condor w/Cat 3126 Eng. Lube (Standard Vers.)..... <b>B76</b> Condor w/Cummins 6CT8.3 (8.3L) Eng. F-F Lube (3313281)..... <b>B205 +</b> Dual-Flow Lube (3318853)..... <b>BD103 +</b> Fuel/Water Separator (3903410) <b>BF1280 +</b> Fuel/Water Separator (3286503) <b>BF1226</b> Fuel Spin-on (3903640)..... <b>BF788</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
AT9513, AT9522 w/Cummins M11 Eng. Dual-Flow Lube..... <b>BD103 +</b> Fuel/Water Separator..... <b>BF1259</b> Radial Seal O. Air (Standard) (Don. P526947)..... <b>RS3518</b> Radial Seal XP O. Air (Upgrade) (Don. P526947)..... <b>RS3518XP</b> Radial Seal I. Air..... <b>RS3519</b>	Condor w/Cat C7 Eng. (To 1/2004) Lube (Standard Vers.) (1R0739).. <b>B76 +</b> Lube (Severe Service) (1R0739).. <b>B76-SS +</b> Fuel/Water Separator (Motorcraft FD4597)..... <b>BF7806</b> Fuel (1R0751)..... <b>BF7632</b>	Condor w/Cummins 6CT8.3 (8.3L) Eng. Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
AT9513, AT9522 w/Detroit Diesel Series 60 Eng. Lube..... <b>[2] B495</b> Fuel/Water Separator (w/Drain) (23512317)..... <b>BF5813 +</b> Fuel/Water Separator (Open End for Bowl) (23512317)..... <b>BF5813-O +</b> S. Fuel..... <b>BF5810</b> Radial Seal O. Air (Standard) (Don. P526947)..... <b>RS3518</b> Radial Seal XP O. Air (Upgrade) (Don. P526947)..... <b>RS3518XP</b> Radial Seal I. Air..... <b>RS3519</b> Coolant (23507189)..... <b>[2] BW5140</b>	Condor w/Cat C7 Eng. (1/2004-on) Lube (1R1807)..... <b>B7700 +</b> Fuel/Water Separator (Motorcraft FD4597)..... <b>BF7806</b> Fuel (1R0751)..... <b>BF7632</b>	Condor w/Cummins C8.3G (8.3L) Eng. Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
AT9522 w/Cat 3306 (10.5L) Eng. Lube Ele. (5S0484)..... <b>PT670</b> Lube Spin-on (1R0716)..... <b>B99 +</b> Lube Spin-on (Standard Vers.) (1R0739)..... <b>B76 +</b> Lube Spin-on (Severe Service) (1R0739)..... <b>B76-SS +</b> P. Fuel Ele. (9M2342)..... <b>PF935</b> P. Fuel Spin-on (1R1740)..... <b>BF970 +</b> S. Fuel Spin-on (1R0750)..... <b>BF7633 +</b>	Condor w/Cat C9 Eng. (To 1/2004) Lube (1R0716)..... <b>B99 +</b> Fuel (1R0751)..... <b>BF7632</b>	Condor w/Cummins ISB Eng. Lube..... <b>B7177</b>
AT9522 w/Cummins N14 (14.0L) Eng. Dual-Flow Lube (3318853)..... <b>BD103 +</b> F-F Lube (Fleetguard LF670SC).. <b>B196 +</b> B-P Lube (3304232)..... <b>B7577</b> Opt. Fuel/Water Separator (3308638)..... <b>BF1212 +</b> Fuel (154789)..... <b>BF957-D +</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	Condor w/Cat C9 Eng. (1/2004-on) Lube (1R1808)..... <b>B7299 +</b> Fuel (1R0751)..... <b>BF7632</b>	Condor w/Cummins ISC 8.3 (8.3L) Eng. Dual-Flow Lube..... <b>BD7309 +</b>
	Condor w/Cat C10, C12 Eng. (To 1/2004) Lube (1R0716)..... <b>B99 +</b>	Condor w/Cummins ISL 8.9 (8.9L) Eng. Dual-Flow Lube (3318853)..... <b>BD103 +</b> Dual-Flow Lube (3401544)..... <b>BD7309 +</b> Lube (Upgrade) (3401544)..... <b>B40142 +</b> Fuel/Water Separator (w/Drain) (3355903)..... <b>BF1249</b> Fuel/Water Separator (Open End for Bowl) (3355903)..... <b>BF1249-O</b> Fuel/Water Separator (w/Drain & Sensor Port) (3355903)..... <b>BF1249-SP</b> Fuel/Water Separator (w/Drain & Sensor Port, High Efficiency Version) (3355903)..... <b>BF1393-SP</b>
	Condor w/Cat C10, C12 Eng. (1/2004-on) Lube (1R1808)..... <b>B7299 +</b>	Condor w/Cummins ISM 10.8 (10.8L) Eng. Dual-Flow Lube (Fleetguard LF9001)..... <b>BD7154 +</b> Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> Fuel/Water Separator (3406889) <b>BF1293-SPS</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b>
	Condor w/Cat C11 (11.1L) Eng. Lube (1R1808)..... <b>B7299 +</b> Fuel/Water Separator (2568753) <b>BF1259</b> Fuel (Standard Vers.) (1R1712)... <b>BF614 +</b> Fuel (High Efficiency Vers.) (1R0749)..... <b>BF7587 +</b> Fuel (1R0762)..... <b>BF7753</b>	
	Condor w/Cat C13 Eng. (To 1/2004) Lube (1R0716)..... <b>B99 +</b> Fuel/Water Separator Spin-on (Open End for Bowl) (Racor S3226P)..... <b>BF1346-O</b> Fuel/Water Separator Spin-on (w/Drain) (Racor S3226P)..... <b>BF1346</b> Fuel/Water Separator Spin-on (w/Sensor Port) (Racor S3226P).. <b>BF1346-SP</b>	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>STERLING Trucks (cont'd)</b>	<b>STERLING Trucks (cont'd)</b>	<b>STERLING Trucks (cont'd)</b>
Condor w/Cummins ISM 10.8 (10.8L) Eng. (Cont'd) <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b> <hr/> Condor w/Cummins M11 (10.8L) Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103+</b> <b>Fuel/Water Separator Ele.</b> (Davco 380087)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> (3329289)..... <b>BF1259</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <hr/> DD115, HC115, HC115H, HC144, HC147, HC155, HD145, HWS160, RWS160, RWS23S, RWS262 <b>Lube</b> (1945-52)..... <b>P52</b> <hr/> HCS297H <b>B-P Lube Ele.</b> ..... <b>C750-E+</b> <hr/> L7500 w/Cummins ISB (5.9L) Eng. <b>Lube</b> ..... <b>B7177</b> <hr/> L7500 w/Cummins ISC (8.3L) Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309+</b> <b>Fuel/Water Separator</b> ..... <b>BF1272-SPS</b> <b>Fuel</b> (Fleetguard FF5636)..... <b>BF7924</b> <b>Radial Seal Air</b> (Standard) (Don. P527682)..... <b>RS3518</b> <b>Radial Seal XP Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b> <b>Cab Air</b> (Fresh Air) (F6HZ-19N619-AA)..... <b>PA5337</b> <b>Cab Air</b> (Recirculation) (F6HZ-19N619-BA)..... <b>PA5393</b> <b>Air Dryer</b> (Wabco R950011)..... <b>BA5374+</b> <b>Coolant</b> (3100304)..... <b>BW5071</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b> <b>Steering</b> (VMLT1808D)..... <b>BT9388</b>	L7500 w/Mercedes-Benz MBE906 (6.4L) Eng. <b>F-F Lube</b> (1801709)..... <b>P7188</b> <b>Opt. B-P Lube Spinner</b> (A9061810086)..... <b>BC7326+</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Fuel</b> (A5410920305)..... <b>PF7761</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <hr/> L7500, LT7500 w/Cat C7 (7.2L) Eng. (To 1/2004) <b>Lube</b> (Standard Vers.) (1R0739).. <b>B76+</b> <b>Lube</b> (Severe Service) (1R0739).. <b>B76-SS+</b> <b>Fuel/Water Separator</b> (Alliance ABP/N122-32FRT02)..... <b>BF1376</b> <b>Fuel</b> (1R0751)..... <b>BF7632</b> <b>Radial Seal Air</b> (Don. P533930).. <b>RS3548</b> <b>Radial Seal XP Air</b> (Don. P533930)..... <b>RS3548XP</b> <b>Cab Air</b> (Fresh Air) (F6HZ19N619AA)..... <b>PA5337</b> <b>Cab Air</b> (Recirculation) (F6HZ19N619BA)..... <b>PA5393</b> <b>Coolant</b> (3827423)..... <b>B5134+</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b> <b>Trans. Breather</b> (Fuller Trans.)... <b>CLN&amp;R</b> <b>Steering</b> (87904M)..... <b>PT9354-MPG</b> <b>Some Rear Axle</b> (Meritor 3280-V-5040)..... <b>B27</b> <hr/> L7500, LT7500 w/Cat C7 (7.2L) Eng. (1/2004-on) <b>Lube</b> (1R1807)..... <b>B7700+</b> <b>Fuel/Water Separator</b> (Alliance ABP/N122-32FRT02)..... <b>BF1376</b> <b>Fuel</b> (1R0751)..... <b>BF7632</b> <b>Radial Seal Air</b> (Don. P533930).. <b>RS3548</b> <b>Radial Seal XP Air</b> (Don. P533930)..... <b>RS3548XP</b> <b>Cab Air</b> (Fresh Air) (F6HZ19N619AA)..... <b>PA5337</b> <b>Cab Air</b> (Recirculation) (F6HZ19N619BA)..... <b>PA5393</b> <b>Coolant</b> (3827423)..... <b>B5134+</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b> <b>Trans. Breather</b> (Fuller Trans.)... <b>CLN&amp;R</b> <b>Steering</b> (87904M)..... <b>PT9354-MPG</b> <b>Some Rear Axle</b> (Meritor 3280-V-5040)..... <b>B27</b>	L7500, LT7500 w/Cat 3126 (7.2L) Eng. <b>Lube</b> (Standard Vers.)..... <b>B76</b> <b>Lube</b> (High Efficiency) (1R1807).. <b>B7700+</b> <b>Fuel</b> (1R0751)..... <b>BF7632</b> <b>Coolant</b> (4 Units BTE) (9N3368).. <b>BW5137</b> <b>Coolant</b> (8 Units BTE) (9N3367).. <b>BW5139</b> <hr/> L7501 w/Cummins 6BT5.9 (5.9L) Eng. <b>Lube</b> (Chrysler 5083285AA)..... <b>BT7349</b> <b>Fuel/Water Separator</b> (3925274).. <b>BF1280+</b> <b>Fuel</b> (3903640)..... <b>BF788</b> <hr/> L7501 w/Cummins NTC (14.0L) Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103+</b> <b>F-F Lube Ele.</b> (158139)..... <b>P999-HD</b> <b>F-F Lube Spin-on</b> (3313279)..... <b>B196+</b> <b>B-P Lube Ele.</b> (256838)..... <b>C750-E+</b> <b>B-P Lube Spin-on</b> (3313283)..... <b>B7577</b> <b>Fuel/Water Separator</b> (3308638).. <b>BF1212+</b> <b>Fuel</b> (158172)..... <b>BF957+</b> <hr/> L7501, LT7501 w/Cat 3126 Eng. <b>Lube</b> (Standard Vers.)..... <b>B76</b> <b>Fuel</b> ..... <b>BF7632</b> <b>Radial Seal Air</b> (Don. P533930).. <b>RS3548</b> <b>Radial Seal XP Air</b> (Don. P533930)..... <b>RS3548XP</b> <hr/> L7501, LT7501 w/Cummins 6CT8.3 (8.3L) Eng. <b>F-F Lube</b> (3313281)..... <b>B205+</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103+</b> <b>Fuel/Water Separator</b> (3925274).. <b>BF1280+</b> <b>Fuel</b> (3903640)..... <b>BF788</b> <b>Radial Seal Air</b> (Don. P533930).. <b>RS3548</b> <b>Radial Seal XP Air</b> (Don. P533930)..... <b>RS3548XP</b> <hr/> LT7500 w/Cat C9 (8.8L) Eng. (To 1/2004) <b>Lube</b> (1R0716)..... <b>B99+</b> <b>Fuel/Water Separator</b> (Alliance ABPN122R50418)..... <b>BF9898-O</b> <b>Fuel/Water Separator</b> (Racor R50404)..... <b>BF1362</b> <b>Fuel</b> (1R0751)..... <b>BF7632</b> <b>Radial Seal Air</b> (Don. P533930).. <b>RS3548</b> <b>Radial Seal XP Air</b> (Don. P533930)..... <b>RS3548XP</b> <b>Cab Air</b> (Fresh Air) (F6HZ19N619AA)..... <b>PA5337</b> <b>Cab Air</b> (Recirculation) (F6HZ19N619BA)..... <b>PA5393</b> <b>Coolant</b> (Fleetguard WF2077)..... <b>B5134+</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b> <b>Trans. Breather</b> ..... <b>CLN&amp;R</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Some Rear Axle</b> (Meritor 3280-V-5040)..... <b>B27</b>

\* See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

STERLING Trucks (cont'd)	STERLING Trucks (cont'd)	STERLING Trucks (cont'd)
LT7500 w/Cat C9 (8.8L) Eng. (1/2004-on) <b>Lube</b> (1R1808)..... <b>B7299 +</b> <b>Fuel/Water Separator</b> (Alliance ABPN122R50418)..... <b>BF9898-O</b> <b>Fuel/Water Separator</b> (Racor R50404)..... <b>BF1362</b> <b>Fuel</b> (1R0751)..... <b>BF7632</b> <b>Radial Seal Air</b> (Don. P533930)... <b>RS3548</b> <b>Radial Seal XP Air</b> (Don. P533930)..... <b>RS3548XP</b> <b>Cab Air</b> (Fresh Air) (F6HZ19N619AA)..... <b>PA5337</b> <b>Cab Air</b> (Recirculation) (F6HZ19N619BA)..... <b>PA5393</b> <b>Coolant</b> (Fleetguard WF2077)..... <b>B5134 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Trans. Breather</b> ..... <b>CLN&amp;R</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Some Rear Axle</b> (Meritor 3280-V-5040)..... <b>B27</b>	LT7500 w/Cummins ISC 8.3 (8.3L) Eng. (Cont'd) <b>Coolant</b> (3100304)..... <b>BW5071</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (VML/T1808D)..... <b>BT9388</b>	LT7500 w/Mercedes-Benz MBE4000 (12.8L) Eng. (Cont'd) <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Trans. Breather</b> (Fuller Trans.)... <b>CLN&amp;R</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Steering</b> (VML/T1808D)..... <b>BT9388</b> <b>Some Rear Axle</b> (Meritor 3280-V-5040)..... <b>B27</b>
LT7500 w/Cat C16 (15.8L) Eng. <b>Lube</b> (1R0716)..... <b>B99 +</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (1335673)..... <b>BF1395-O</b> <b>Fuel/Water Separator</b> (w/Drain) (1335673)..... <b>BF1265</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (1335673)..... <b>BF1395-SP</b> <b>Fuel/Water Separator</b> (2568753)..... <b>BF1259</b> <b>Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (Standard Vers.) (1R1712)..... <b>BF614 +</b> <b>Fuel Spin-on</b> (High Efficiency Vers.) (1R0749)..... <b>BF7587 +</b>	LT7500 w/Cummins L10 (10.0L) Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196 +</b> <b>B-P Lube</b> (3304232)..... <b>BF577</b> <b>Fuel</b> (154789)..... <b>BF957-D +</b>	LT7500 w/Mercedes-Benz OM906 (6.4L) Eng. (Cont'd) <b>Lube</b> (A0001801609)..... <b>P7199</b> <b>Fuel/Water Separator</b> (w/Drain) (A0004771302)..... <b>BF1363</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b> <b>Fuel</b> (A9060920305)..... <b>PF7735</b>
LT7500 w/Cummins M11 (10.8L) Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Fuel/Water Separator Ele.</b> (Davco 380087)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> (3329289)..... <b>BF1259</b>	LT7500 w/Detroit Diesel Series 55 (12.0L) Eng. <b>Lube</b> (23550401)..... <b>B7135</b> <b>Fuel</b> (23530707)..... <b>BF5810</b>	LT7500 w/Mercedes-Benz OM906 (6.4L) Eng. <b>F-F Lube</b> (1801709)..... <b>P7188</b> <b>Opt. B-P Lube Spinner</b> (A9061810086)..... <b>BC7326 +</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Fuel</b> (A5410920305)..... <b>PF7761</b>
LT7500 w/Cummins 6CT8.3 (8.3L) Eng. <b>F-F Lube</b> (3313281)..... <b>B205 +</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Fuel/Water Separator</b> (3903410)..... <b>BF1280 +</b> <b>Fuel/Water Separator</b> (3286503)..... <b>BF1226</b> <b>Fuel Spin-on</b> (3903640)..... <b>BF788</b>	LT7500 w/Mercedes-Benz MBE4000 (12.8L) Eng. <b>Lube</b> (1802109)..... <b>P7230</b> <b>Fuel/Water Separator Ele.</b> ..... <b>PF7748</b> <b>Fuel/Water Separator Spin-on</b> ..... <b>BF1259</b> <b>Fuel/Water Separator</b> (Alliance ABP/N122-BR90FRT30)..... <b>BF46016-O</b> <b>Fuel</b> (5410900151)..... <b>PF7761</b> <b>Radial Seal Air</b> (Standard) (Don. P527682)..... <b>RS3518</b> <b>Radial Seal XP Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b> <b>Cab Air</b> (Fresh Air) (F6HZ19N619AA)..... <b>PA5337</b> <b>Cab Air</b> (Recirculation) (F6HZ19N619BA)..... <b>PA5393</b> <b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b>	LT7500 w/Mercedes-Benz MBE906 (6.4L) Eng. <b>F-F Lube</b> (1801709)..... <b>P7188</b> <b>Opt. B-P Lube Spinner</b> (A9061810086)..... <b>BC7326 +</b> <b>Fuel</b> (A0000901551)..... <b>PF7735</b> <b>Fuel</b> (A5410920305)..... <b>PF7761</b>
LT7500 w/Cummins ISC 8.3 (8.3L) Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel/Water Separator</b> ..... <b>BF1272-SPS</b> <b>Fuel</b> (Fleetguard FF5636)..... <b>BF7924</b> <b>Radial Seal Air</b> (Standard) (Don. P527682)..... <b>RS3518</b> <b>Radial Seal XP Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b> <b>Cab Air</b> (Fresh Air) (F6HZ-19N619-AA)..... <b>PA5337</b> <b>Cab Air</b> (Recirculation) (F6HZ-19N619-BA)..... <b>PA5393</b> <b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b>	LT7500 w/Mercedes-Benz MBE4000 (12.8L) Eng. <b>Lube</b> (1802109)..... <b>P7230</b> <b>Fuel/Water Separator Ele.</b> ..... <b>PF7748</b> <b>Fuel/Water Separator Spin-on</b> ..... <b>BF1259</b> <b>Fuel/Water Separator</b> (Alliance ABP/N122-BR90FRT30)..... <b>BF46016-O</b> <b>Fuel</b> (5410900151)..... <b>PF7761</b> <b>Radial Seal Air</b> (Standard) (Don. P527682)..... <b>RS3518</b> <b>Radial Seal XP Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b> <b>Cab Air</b> (Fresh Air) (F6HZ19N619AA)..... <b>PA5337</b> <b>Cab Air</b> (Recirculation) (F6HZ19N619BA)..... <b>PA5393</b> <b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b>	LT7500 w/Mercedes-Benz OM906 (6.4L) Eng. <b>Lube</b> (A0001801609)..... <b>P7199</b> <b>Fuel/Water Separator</b> (w/Drain) (A0004771302)..... <b>BF1363</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b> <b>Fuel</b> (A9060920305)..... <b>PF7735</b>
		LT8500, LT8500 w/Cat C7 (7.2L) Eng. (To 1/2004) <b>Lube</b> (Standard Vers.) (1R0739).. <b>B76 +</b> <b>Lube</b> (Severe Service) (1R0739).. <b>B76-SS +</b> <b>Fuel/Water Separator</b> (Alliance ABP/N122-32FRT02)..... <b>BF1376</b> <b>Fuel/Water Separator</b> (Alliance ABPN122R50418)..... <b>BF9898-O</b> <b>Fuel/Water Separator</b> (Motorcraft FD4597)..... <b>BF7806</b> <b>Fuel</b> (1R0751)..... <b>BF7632</b> <b>Radial Seal Air</b> (Don. P533930)... <b>RS3548</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

STERLING Trucks (cont'd)	STERLING Trucks (cont'd)	STERLING Trucks (cont'd)
L8500, LT8500 w/Cat C7 (7.2L) Eng. (To 1/2004) (Cont'd)	L8500, LT8500 w/Cat C9 (8.8L) Eng. (To 1/2004) (Cont'd)	L8500, LT8500 w/Cummins ISC 8.3 (8.3L) Eng. (Cont'd)
Radial Seal XP Air (Don. P533930)..... <b>RS3548XP</b>	Cab Air (Fresh Air) (F6HZ19N619AA)..... <b>PA5337</b>	Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
Cab Air (Fresh Air) (F6HZ19N619AA)..... <b>PA5337</b>	Cab Air (Recirculation) (F6HZ19N619BA)..... <b>PA5393</b>	Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
Cab Air (Recirculation) (F6HZ19N619BA)..... <b>PA5393</b>	Coolant (Fleetguard WF2077)..... <b>B5134 +</b>	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
Coolant (3827423)..... <b>B5134 +</b>	Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	Trans. Breather..... <b>CLN&amp;R</b>	Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>
Trans. Breather (Fuller Trans.)..... <b>CLN&amp;R</b>	Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>
Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	Some Rear Axle (Meritor 3280-V-5040)..... <b>B27</b>	Steering (VML/T1808D)..... <b>BT9388</b>
Some Rear Axle (Meritor 3280-V-5040)..... <b>B27</b>	L8500, LT8500 w/Cat C9 (8.8L) Eng. (1/2004-on)	L8500, LT8500 w/Cummins ISL 8.9 (8.9L) Eng.
L8500, LT8500 w/Cat C7 (7.2L) Eng. (1/2004-on)	Lube (1R1808)..... <b>B7299 +</b>	Dual-Flow Lube..... <b>BD7309 +</b>
Lube (1R1807)..... <b>B7700 +</b>	Fuel/Water Separator (Alliance ABPN122R50418)..... <b>BF9898-O</b>	Fuel/Water Separator..... <b>BF1259</b>
Fuel/Water Separator (Alliance ABPN122-32FRT02)..... <b>BF1376</b>	Fuel/Water Separator (Racor R50404)..... <b>BF1362</b>	L8500, LT8500, L8501, LT8501, LT8511, L8513, LT8513 w/Cat 3126 (7.2L) Eng. (1/2004-on)
Fuel/Water Separator (Alliance ABPN122R50418)..... <b>BF9898-O</b>	Fuel (1R0751)..... <b>BF7632</b>	Lube (1R1807)..... <b>B7700 +</b>
Fuel/Water Separator (Motorcraft FD4597)..... <b>BF7806</b>	Radial Seal Air (Don. P533930)..... <b>RS3548</b>	Trans. Ele. (Allison 3000 Series, 2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
Fuel (1R0751)..... <b>BF7632</b>	Radial Seal XP Air (Don. P533930)..... <b>RS3548XP</b>	Trans. Ele. (Allison 3000 Series, 4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
Radial Seal Air (Don. P533930)..... <b>RS3548</b>	Cab Air (Fresh Air) (F6HZ19N619AA)..... <b>PA5337</b>	Trans. Pan-Type (Allison MT Series) (Allison 29538489)..... <b>19739 +</b>
Radial Seal XP Air (Don. P533930)..... <b>RS3548XP</b>	Cab Air (Recirculation) (F6HZ19N619BA)..... <b>PA5393</b>	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>
Cab Air (Fresh Air) (F6HZ19N619AA)..... <b>PA5337</b>	Coolant (Fleetguard WF2077)..... <b>B5134 +</b>	L8500, LT8500, L8501, LT8501, LT8511, L8513, LT8513 w/Cat 3126 (7.2L) Eng. (To 1/2004)
Cab Air (Recirculation) (F6HZ19N619BA)..... <b>PA5393</b>	Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	Lube (Standard Vers.) (1R0739)..... <b>B76 +</b>
Coolant (3827423)..... <b>B5134 +</b>	Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Lube (Severe Service) (1R0739)..... <b>B76-SS +</b>
Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	Trans. Ele. (Allison 3000 Series, 2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	L8500, LT8500 w/Cummins ISC 8.3 (8.3L) Eng.	Trans. Ele. (Allison 3000 Series, 4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309 +</b>	Trans. Pan-Type (Allison MT Series) (Allison 29538489)..... <b>19739 +</b>
Trans. Breather (Fuller Trans.)..... <b>CLN&amp;R</b>	Fuel/Water Separator..... <b>BF1272-SPS</b>	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>
Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	Fuel (Fleetguard FF5636)..... <b>BF7924</b>	L8500, LT8500, L8501, LT8501, LT8511, L8513, LT8513 w/Cummins 6CT8.3 (8.3L) Eng.
Some Rear Axle (Meritor 3280-V-5040)..... <b>B27</b>	Radial Seal Air (Standard) (Don. P527682)..... <b>RS3518</b>	F-F Lube (3313281)..... <b>B205 +</b>
L8500, LT8500 w/Cummins ISC 8.3 (8.3L) Eng.	Radial Seal XP Air (Upgrade) (Don. P527682)..... <b>RS3518XP</b>	Dual-Flow Lube (3318853)..... <b>BD103 +</b>
Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309 +</b>	Cab Air (Fresh Air) (F6HZ-19N619-AA)..... <b>PA5337</b>	Fuel/Water Separator (3925274)..... <b>BF1280 +</b>
Fuel/Water Separator..... <b>BF1272-SPS</b>	Cab Air (Recirculation) (F6HZ-19N619-BA)..... <b>PA5393</b>	Fuel (3903640)..... <b>BF788</b>
Fuel (Fleetguard FF5636)..... <b>BF7924</b>	Air Dryer (Wabco R950011)..... <b>BA5374 +</b>	Radial Seal Air (Don. P533930)..... <b>RS3548</b>
Radial Seal Air (Standard) (Don. P527682)..... <b>RS3518</b>	Coolant (3100304)..... <b>BW5071</b>	Radial Seal XP Air (Don. P533930)..... <b>RS3548XP</b>
Radial Seal XP Air (Upgrade) (Don. P527682)..... <b>RS3518XP</b>		
Cab Air (Fresh Air) (F6HZ-19N619-AA)..... <b>PA5337</b>		
Cab Air (Recirculation) (F6HZ-19N619-BA)..... <b>PA5393</b>		
Air Dryer (Wabco R950011)..... <b>BA5374 +</b>		
Coolant (3100304)..... <b>BW5071</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

STERLING Trucks (cont'd)	STERLING Trucks (cont'd)	STERLING Trucks (cont'd)
L8501 w/Cummins 6BT5.9 (5.9L) Eng. Lube (Chrysler 5083285AA)..... <b>BT7349</b> Fuel/Water Separator (3925274)..... <b>BF1280 +</b> Fuel (3903640)..... <b>BF788</b>	LT8500 w/Cat C15 (14.6L) Eng. (To 1/2004) (Cont'd) <b>15 1/4 In. Radial Seal Air</b> (Upgrade) (DBA5069)..... <b>RS3518XP</b> <b>15 5/8 In. Radial Seal Air</b> (Don. P533930)..... <b>RS3548</b> <b>15 5/8 In. Radial Seal XP Air</b> (Don. P533930)..... <b>RS3548XP</b> <b>Cab Air</b> (Fresh Air) (F6HZ19N619AA)..... <b>PA5337</b> <b>Cab Air</b> (Recirculation) (F6HZ19N619BA)..... <b>PA5393</b> <b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b> <b>Breather</b> (296-8325)..... <b>CV15008</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	LT8500 w/Cat C15 (14.6L) Eng. (1/2004-on) (Cont'd) <b>15 5/8 In. Radial Seal XP Air</b> (Don. P533930)..... <b>RS3548XP</b> <b>Cab Air</b> (Fresh Air) (F6HZ19N619AA)..... <b>PA5337</b> <b>Cab Air</b> (Recirculation) (F6HZ19N619BA)..... <b>PA5393</b> <b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b> <b>Breather</b> (296-8325)..... <b>CV15008</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Trans. Breather</b> (Fuller Trans.).... <b>CLN&amp;R</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Steering</b> (VML/T1808D)..... <b>BT9388</b> <b>Some Rear Axle</b> (Meritor 3280-V-5040)..... <b>B27</b>
L8511 w/Cat 3126 (7.2L) Eng. Lube (Standard Vers.) (1R0739).. <b>B76 +</b> Lube (Severe Service) (1R0739).. <b>B76-SS +</b> Fuel/Water Separator (1752949). <b>BF1268</b> Fuel/Water Separator (2568753). <b>BF1259</b> Fuel/Water Separator (w/Sensor Port) (1986378)..... <b>BF7798-SP</b> Fuel/Water Separator (Open End for Bowl) (1986378)..... <b>BF7798-O</b> Fuel Ele. (9M2342)..... <b>[2] PF935</b> Fuel Spin-on (1R0751)..... <b>BF7632</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	LT8500 w/Cat C15 (14.6L) Eng. (1/2004-on) Lube (1R1808)..... <b>B7299 +</b> Fuel/Water Separator Ele. (Fleetguard FS1029)..... <b>PF7680</b> Fuel/Water Separator Ele. (Fleetguard FS19624)..... <b>PF7748</b> Fuel/Water Separator Spin-on (Open End for Bowl) (Racor S3226P)..... <b>BF1346-O</b> Fuel/Water Separator Spin-on (w/Drain) (Racor S3226P)..... <b>BF1346</b> Fuel/Water Separator Spin-on (w/Sensor Port) (Racor S3226P).. <b>BF1346-SP</b> Fuel Spin-on..... <b>BF7587 +</b> Radial Seal Air (Don. P533814).... <b>RS3749</b>	LT8500 w/Detroit Diesel Series 55 (12.0L) Eng. Lube (23550401)..... <b>B7135</b> Fuel (23530707)..... <b>BF5810</b>
L8511 w/Cummins 6CT8.3 (8.3L) Eng. F-F Lube (3313281)..... <b>B205 +</b> Dual-Flow Lube (3318853)..... <b>BD103 +</b> Fuel/Water Separator (3925274). <b>BF1280 +</b> Fuel (3903640)..... <b>BF788</b> Radial Seal Air (Don. P533930)... <b>RS3548</b> Radial Seal XP Air (Don. P533930)..... <b>RS3548XP</b>	LT8500 w/Cat C15 (14.6L) Eng. (1/2004-on) Lube (1R0716)..... <b>B99 +</b> Fuel/Water Separator Ele. (Fleetguard FS1029)..... <b>PF7680</b> Fuel/Water Separator Ele. (Fleetguard FS19624)..... <b>PF7748</b> Fuel/Water Separator Spin-on (Open End for Bowl) (Racor S3226P)..... <b>BF1346-O</b> Fuel/Water Separator Spin-on (w/Drain) (17001-4406)..... <b>BF1259</b> Fuel/Water Separator Spin-on (w/Drain) (Racor S3226P)..... <b>BF1346</b> Fuel/Water Separator Spin-on (w/Sensor Port) (Racor S3226P).. <b>BF1346-SP</b> Fuel (1R0749)..... <b>BF7587 +</b> <b>15 1/4 In. Radial Seal Air</b> (Standard) (Fleetguard AF25139M)..... <b>RS3518</b> <b>15 1/4 In. Radial Seal Air</b> (Upgrade) (DBA5069)..... <b>RS3518XP</b> <b>15 5/8 In. Radial Seal Air</b> (Don. P533930)..... <b>RS3548</b>	LT8500 w/Mercedes-Benz MBE906 (6.4L) Eng. F-F Lube (1801709)..... <b>P7188</b> Opt. B-P Lube Spinner (A9061810086)..... <b>BC7326 +</b> Fuel (A0000901551)..... <b>PF7735</b> Fuel (A5410920305)..... <b>PF7761</b>
LT8513 w/Cat C12 (12.0L) Eng. Lube..... <b>B99 +</b> Fuel/Water Separator Spin-on (Open End for Bowl) (Racor S3226P)..... <b>BF1346-O</b> Fuel/Water Separator Spin-on (w/Drain) (Racor S3226P)..... <b>BF1346</b> Fuel/Water Separator Spin-on (w/Sensor Port) (Racor S3226P).. <b>BF1346-SP</b> Fuel Spin-on..... <b>BF7587 +</b> Radial Seal Air (Don. P533814).... <b>RS3749</b>	LT8500 w/Cat C15 (14.6L) Eng. (To 1/2004) Lube (1R0716)..... <b>B99 +</b> Fuel/Water Separator Ele. (Fleetguard FS1029)..... <b>PF7680</b> Fuel/Water Separator Ele. (Fleetguard FS19624)..... <b>PF7748</b> Fuel/Water Separator Spin-on (Open End for Bowl) (Racor S3226P)..... <b>BF1346-O</b> Fuel/Water Separator Spin-on (w/Drain) (17001-4406)..... <b>BF1259</b> Fuel/Water Separator Spin-on (w/Drain) (Racor S3226P)..... <b>BF1346</b> Fuel/Water Separator Spin-on (w/Sensor Port) (Racor S3226P).. <b>BF1346-SP</b> Fuel (1R0749)..... <b>BF7587 +</b> <b>15 1/4 In. Radial Seal Air</b> (Standard) (Fleetguard AF25139M)..... <b>RS3518</b> <b>15 1/4 In. Radial Seal Air</b> (Upgrade) (DBA5069)..... <b>RS3518XP</b> <b>15 5/8 In. Radial Seal Air</b> (Don. P533930)..... <b>RS3548</b>	LT8500 w/Mercedes-Benz OM906 (6.4L) Eng. Lube (A0001801609)..... <b>P7199</b> Fuel/Water Separator (w/Drain) (A0004771302)..... <b>BF1363</b> Fuel/Water Separator (Open End for Bowl) (A0004771302)..... <b>BF1391-O</b> Fuel (A9060920305)..... <b>PF7735</b>
LT8500 w/Cat C15 (14.6L) Eng. (To 1/2004) Lube (1R0716)..... <b>B99 +</b> Fuel/Water Separator Ele. (Fleetguard FS1029)..... <b>PF7680</b> Fuel/Water Separator Ele. (Fleetguard FS19624)..... <b>PF7748</b> Fuel/Water Separator Spin-on (Open End for Bowl) (Racor S3226P)..... <b>BF1346-O</b> Fuel/Water Separator Spin-on (w/Drain) (17001-4406)..... <b>BF1259</b> Fuel/Water Separator Spin-on (w/Drain) (Racor S3226P)..... <b>BF1346</b> Fuel/Water Separator Spin-on (w/Sensor Port) (Racor S3226P).. <b>BF1346-SP</b> Fuel (1R0749)..... <b>BF7587 +</b> <b>15 1/4 In. Radial Seal Air</b> (Standard) (Fleetguard AF25139M)..... <b>RS3518</b> <b>15 1/4 In. Radial Seal Air</b> (Upgrade) (DBA5069)..... <b>RS3518XP</b> <b>15 5/8 In. Radial Seal Air</b> (Don. P533930)..... <b>RS3548</b>	LT8501 w/Cat C10 (10.3L) Eng. Lube..... <b>B99 +</b> Fuel (1R0749)..... <b>BF7587 +</b> Radial Seal Air..... <b>RS3739</b> Coolant..... <b>B5134 +</b>	LT8501 w/Cat C10 (10.3L) Eng. Lube Ele. (5S0484)..... <b>PT670</b> Lube Spin-on (1R0716)..... <b>B99 +</b> Lube Spin-on (Standard Vers.) (1R0739)..... <b>B76 +</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

STERLING Trucks (cont'd)	STERLING Trucks (cont'd)	STERLING Trucks (cont'd)
L9500 w/Cat 3306 (10.5L) Eng. (Cont'd) <b>Lube Spin-on</b> (Severe Service) (1R0739)..... <b>B76-SS+</b> <b>P. Fuel Ele.</b> (9M2342)..... <b>PF935</b> <b>P. Fuel Spin-on</b> (1R1740)..... <b>BF970+</b> <b>S. Fuel Spin-on</b> (1R0750)..... <b>BF7633+</b>	L9500 w/Detroit Diesel Series 60 (11.1L), (12.7L) or (14.0L) Eng. (To 12/2003) (Cont'd) <b>P. Fuel</b> (23530706)..... <b>BF5800+</b> <b>S. Fuel</b> (23518482)..... <b>BF5810</b> <b>Radial Seal Air</b> (Standard) (Don. P527682)..... <b>RS3518</b> <b>Radial Seal XP Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b> <b>Cab Air</b> (Fresh Air) (F6HZ19N619AA)..... <b>PA5337</b> <b>Cab Air</b> (Recirculation) (F6HZ19N619BA)..... <b>PA5393</b> <b>Air Dryer</b> (Wabco R950011)..... <b>BA5374+</b> <b>Coolant</b> (Nalcool NF2088)..... <b>BW5200</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b> <b>Trans. Breather</b> (Fuller Trans.).... <b>CLN&amp;R</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Steering</b> (VML/T1808D)..... <b>BT9388</b> <b>Some Rear Axle</b> (Meritor 3280-V-5040)..... <b>B27</b>	L9500 w/Detroit Diesel Series 60 (11.1L), (12.7L) or (14.0L) Eng. (12/2003-on) (Cont'd) <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b> <b>Trans. Breather</b> (Fuller Trans.).... <b>CLN&amp;R</b> <b>Steering</b> (Nelson 87904M)..... <b>PT9354-MPG</b> <b>Steering</b> (VML/T1808D)..... <b>BT9388</b> <b>Some Rear Axle</b> (Meritor 3280-V-5040)..... <b>B27</b>
L9500 w/Cummins M11 (10.8L) Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103+</b> <b>Fuel/Water Separator Ele.</b> (Davco 380087)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> (3329289)..... <b>BF1259</b>	L9500 w/Detroit Diesel DD15 (14.8L) Eng. <b>Lube</b> (A4731800109)..... <b>P7505</b> <b>Fuel Kit</b> (A0000904251)..... <b>PF9924 KIT</b> <b>Radial Seal Air</b> (Standard) (Don. P527682)..... <b>RS3518</b> <b>Radial Seal XP Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b> <b>Cab Air</b> (Fresh Air) (F6HZ19N619AA)..... <b>PA5337</b> <b>Cab Air</b> (Recirculation) (F6HZ19N619BA)..... <b>PA5393</b> <b>Air Dryer</b> (Wabco R950011)..... <b>BA5374+</b> <b>Coolant</b> (A4722030255)..... <b>P5092</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (VML/T1808D)..... <b>BT9388</b> <b>Some Rear Axle</b> (Meritor 3280-V-5040)..... <b>B27</b>	L9500, L9501, L9511, L9513, L9522, LT9500, LT9501, LT9511, LT9513, LT9522 w/Cat C10 (10.3L) Eng. <b>Lube</b> ..... <b>B99+</b> <b>Fuel</b> (1R0749)..... <b>BF7587+</b> <b>Radial Seal Air</b> ..... <b>RS3739</b> <b>Coolant</b> ..... <b>B5134+</b>
L9500 w/Detroit Diesel Series 60 (11.1L), (12.7L) or (14.0L) Eng. (To 12/2003) <b>Lube</b> (23530573)..... <b>[2] B495</b> <b>Fuel/Water Separator Ele.</b> (23529168)..... <b>PF7748</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (23512317)..... <b>BF5813+</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (23512317).. <b>BF5813-O+</b> <b>P. Fuel</b> (23530706)..... <b>BF5800+</b> <b>S. Fuel</b> (23530645)..... <b>BF5815</b> <b>S. Fuel</b> (23533726)..... <b>BF5816</b> <b>Radial Seal Air</b> (Standard) (Don. P527682)..... <b>RS3518</b> <b>Radial Seal XP Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b> <b>Cab Air</b> (Fresh Air) (F6HZ19N619AA)..... <b>PA5337</b> <b>Cab Air</b> (Recirculation) (F6HZ19N619BA)..... <b>PA5393</b> <b>Air Dryer</b> (Wabco R950011)..... <b>BA5374+</b> <b>Coolant</b> (Nalcool NF2088)..... <b>BW5200</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	L9500, L9501, L9511, L9513, L9522, LT9500, LT9501, LT9511, LT9513, LT9522 w/Cat C12 (12.0L) Eng. <b>Lube</b> ..... <b>B99+</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Racor S3226P)..... <b>BF1346-O</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (Racor S3226P)..... <b>BF1346</b> <b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (Racor S3226P).. <b>BF1346-SP</b> <b>Fuel Spin-on</b> (1R0712)..... <b>BF614+</b> <b>Fuel Spin-on</b> (1R0749)..... <b>BF7587+</b> <b>Radial Seal Air</b> (Don. P533814)... <b>RS3749</b> <b>Radial Seal Air</b> (Don. P533930)... <b>RS3548</b> <b>Radial Seal XP Air</b> (Don. P533930)..... <b>RS3548XP</b>	L9500, L9511, LT9500, LT9513, LT9522 w/Cat C15 (14.6L) Eng. (To 1/2004) <b>Lube</b> (1R0716)..... <b>B99+</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029)..... <b>PF7680</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19624)..... <b>PF7748</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Racor S3226P)..... <b>BF1346-O</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (17001-4406)..... <b>BF1259</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



STERLING Trucks (cont'd)	STERLING Trucks (cont'd)	STERLING Trucks (cont'd)
L9500, L9511, LT9500, LT9513, LT9522 w/Cat C15 (14.6L) Eng. (To 1/2004) (Cont'd)	L9500, L9511, LT9500, LT9513, LT9522 w/Cat C15 (14.6L) Eng. (1/2004-on) (Cont'd)	L9500, LT9500 w/Cat C9 (8.8L) Eng. (To 1/2004) (Cont'd)
<b>Fuel/Water Separator Spin-on</b> (w/Drain) (Racor S3226P).....	<b>Fuel</b> (1R0749).....	<b>Opt. Trans. Spin-on</b> (Fuller 17237).....
<b>BF1346</b>	<b>BF7587 +</b>	<b>B2 +</b>
<b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (Racor S3226P)..	<b>15 1/4 In. Radial Seal Air</b> (Standard) (Fleetguard AF25139M).....	<b>Trans. Breather</b> .....
<b>BF1346-SP</b>	<b>RS3518</b>	<b>CLN&amp;R</b>
<b>Fuel</b> (1R0749).....	<b>15 1/4 In. Radial Seal Air</b> (Upgrade) (DBA5069).....	<b>Steering</b> (Nelson 87904M).....
<b>BF7587 +</b>	<b>RS3518XP</b>	<b>PT9354-MPG</b>
<b>15 1/4 In. Radial Seal Air</b> (Standard) (Fleetguard AF25139M).....	<b>15 5/8 In. Radial Seal Air</b> (Don. P533930).....	<b>Some Rear Axle</b> (Meritor 3280-V-5040).....
<b>RS3518</b>	<b>RS3548</b>	<b>B27</b>
<b>15 1/4 In. Radial Seal Air</b> (Upgrade) (DBA5069).....	<b>15 5/8 In. Radial Seal XP Air</b> (Don. P533930).....	L9500, LT9500 w/Cat C9 (8.8L) Eng. (1/2004-on)
<b>RS3518XP</b>	<b>RS3548XP</b>	<b>Lube</b> (1R1808).....
<b>15 5/8 In. Radial Seal Air</b> (Don. P533930).....	<b>Cab Air</b> (Fresh Air) (F6HZ19N619AA).....	<b>B7299 +</b>
<b>RS3548</b>	<b>PA5337</b>	<b>Fuel/Water Separator</b> (Alliance ABPN122R50418).....
<b>15 5/8 In. Radial Seal XP Air</b> (Don. P533930).....	<b>Cab Air</b> (Recirculation) (F6HZ19N619BA).....	<b>BF9898-O</b>
<b>RS3548XP</b>	<b>PA5393</b>	<b>Fuel/Water Separator</b> (Racor R50404).....
<b>Cab Air</b> (Fresh Air) (F6HZ19N619AA).....	<b>Air Dryer</b> (Wabco R950011).....	<b>BF1362</b>
<b>PA5337</b>	<b>BA5374 +</b>	<b>BF7632</b>
<b>Cab Air</b> (Recirculation) (F6HZ19N619BA).....	<b>Breather</b> (296-8325).....	<b>RS3548</b>
<b>PA5393</b>	<b>CV15008</b>	<b>Radial Seal XP Air</b> (Don. P533930).....
<b>Air Dryer</b> (Wabco R950011).....	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965).....	<b>RS3548XP</b>
<b>BA5374 +</b>	<b>20004</b>	<b>Cab Air</b> (Fresh Air) (F6HZ19N619AA).....
<b>Breather</b> (296-8325).....	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965).....	<b>PA5337</b>
<b>CV15008</b>	<b>20016</b>	<b>Cab Air</b> (Recirculation) (F6HZ19N619BA).....
<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965).....	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966).....	<b>PA5393</b>
<b>20004</b>	<b>20003</b>	<b>B5134 +</b>
<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965).....	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966).....	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493).....
<b>20016</b>	<b>20017</b>	<b>PT9416-MPG KIT</b>
<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966).....	<b>Trans. Spin-on</b> (Allison 29539579).....	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494).....
<b>20003</b>	<b>BT8460</b>	<b>PT9415-MPG KIT</b>
<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966).....	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493).....	<b>Opt. Trans. Spin-on</b> (Fuller 17237).....
<b>20017</b>	<b>PT9416-MPG KIT</b>	<b>B2 +</b>
<b>Trans. Spin-on</b> (Allison 29539579).....	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494).....	<b>Trans. Breather</b> .....
<b>BT8460</b>	<b>PT9415-MPG KIT</b>	<b>CLN&amp;R</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493).....	<b>Opt. Trans. Spin-on</b> (Fuller 17237).....	<b>Steering</b> (Nelson 87904M).....
<b>PT9416-MPG KIT</b>	<b>B2 +</b>	<b>PT9354-MPG</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494).....	<b>Trans. Breather</b> (Fuller Trans.)....	<b>BT9388</b>
<b>PT9415-MPG KIT</b>	<b>CLN&amp;R</b>	<b>Some Rear Axle</b> (Meritor 3280-V-5040).....
<b>Opt. Trans. Spin-on</b> (Fuller 17237).....	<b>Steering</b> (Nelson 87904M).....	<b>B27</b>
<b>B2 +</b>	<b>PT9354-MPG</b>	L9500, LT9500 w/Cat C9 (8.8L) Eng. (To 1/2004)
<b>Trans. Breather</b> (Fuller Trans.)....	<b>Steering</b> (VML/T1808D).....	<b>Lube</b> (1R0716).....
<b>CLN&amp;R</b>	<b>BT9388</b>	<b>B99 +</b>
<b>Steering</b> (Nelson 87904M).....	<b>Some Rear Axle</b> (Meritor 3280-V-5040).....	<b>Fuel/Water Separator</b> (Fleetguard FS19624).....
<b>PT9354-MPG</b>	<b>B27</b>	<b>PF7748</b>
<b>Steering</b> (VML/T1808D).....	L9500, LT9500 w/Cat C9 (8.8L) Eng. (To 1/2004)	<b>Fuel</b> (1R0749).....
<b>BT9388</b>	<b>Lube</b> (1R0716).....	<b>BF7587 +</b>
<b>Some Rear Axle</b> (Meritor 3280-V-5040).....	<b>B99 +</b>	<b>RS3548</b>
<b>B27</b>	<b>Fuel/Water Separator</b> (Alliance ABPN122R50418).....	<b>Radial Seal XP Air</b> (Don. P533930).....
L9500, L9511, LT9500, LT9513, LT9522 w/Cat C15 (14.6L) Eng. (1/2004-on)	<b>BF9898-O</b>	<b>RS3548XP</b>
<b>Lube</b> (1R1808).....	<b>Fuel/Water Separator</b> (Racor R50404).....	<b>Cab Air</b> (Fresh Air) (F6HZ19N619AA).....
<b>B7299 +</b>	<b>BF1362</b>	<b>PA5337</b>
<b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029).....	<b>Fuel</b> (1R0751).....	<b>Cab Air</b> (Recirculation) (F6HZ19N619BA).....
<b>PF7680</b>	<b>BF7632</b>	<b>PA5393</b>
<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19624).....	<b>Radial Seal Air</b> (Don. P533930)...	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493).....
<b>PF7748</b>	<b>RS3548</b>	<b>PT9416-MPG KIT</b>
<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Racor S3226P).....	<b>Radial Seal XP Air</b> (Don. P533930).....	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494).....
<b>BF1346-O</b>	<b>RS3548XP</b>	<b>PT9415-MPG KIT</b>
<b>Fuel/Water Separator Spin-on</b> (w/Drain) (17001-4406).....	<b>Cab Air</b> (Fresh Air) (F6HZ19N619AA).....	<b>Opt. Trans. Spin-on</b> (Fuller 17237).....
<b>BF1259</b>	<b>PA5337</b>	<b>B2 +</b>
<b>Fuel/Water Separator Spin-on</b> (w/Drain) (Racor S3226P).....	<b>Cab Air</b> (Recirculation) (F6HZ19N619BA).....	<b>Trans. Breather</b> (Fuller Trans.)....
<b>BF1346</b>	<b>PA5393</b>	<b>CLN&amp;R</b>
<b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (Racor S3226P)..	<b>Coolant</b> (Fleetguard WF2077).....	<b>Steering</b> (Nelson 87904M).....
<b>BF1346-SP</b>	<b>B5134 +</b>	<b>PT9354-MPG</b>
	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493).....	<b>Some Rear Axle</b> (Meritor 3280-V-5040).....
	<b>PT9416-MPG KIT</b>	<b>B27</b>
	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494).....	
	<b>PT9415-MPG KIT</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

STERLING Trucks (cont'd)	STERLING Trucks (cont'd)	STERLING Trucks (cont'd)
L9500, LT9500 w/Cat C11 (11.1L) Eng. (1/2004-on)	L9500, LT9500 w/Cat C13 (12.5L) Eng. (To 1/2004) (Cont'd)	L9500, LT9500 w/Cummins ISL 8.9 (8.9L) Eng.
Lube (1R1808)..... B7299 +	Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	Dual-Flow Lube..... BD7309 +
Fuel/Water Separator (Fleetguard FS19624)..... PF7748	Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Fuel/Water Separator..... BF1259
Fuel (1R0749)..... BF7587 +	Opt. Trans. Spin-on (Fuller 17237)..... B2 +	L9500, LT9500 w/Mercedes-Benz MBE4000 (12.8L) Eng.
Radial Seal Air (Don. P533930).... RS3548	Trans. Breather (Fuller Trans.).... CLN&R	Lube (1802109)..... P7230
Radial Seal XP Air (Don. P533930)..... RS3548XP	Steering (Nelson 87904M)..... PT9354-MPG	Fuel/Water Separator Ele..... PF7748
Cab Air (Fresh Air) (F6HZ19N619AA)..... PA5337	Steering (VML/T 1808D)..... BT9388	Fuel/Water Separator Spin-on.... BF1259
Cab Air (Recirculation) (F6HZ19N619BA)..... PA5393	Some Rear Axle (Meritor 3280-V-5040)..... B27	Fuel/Water Separator (Alliance ABP/N122-BR90FRT30)..... BF46016-O
Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	L9500, LT9500 w/Cat C13 (12.5L) Eng. (1/2004-on)	Fuel (5410900151)..... PF7761
Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Lube (1R1808)..... B7299 +	Radial Seal Air (Standard) (Don. P527682)..... RS3518
Opt. Trans. Spin-on (Fuller 17237)..... B2 +	Fuel/Water Separator Spin-on (Open End for Bowl) (Racor S3226P)..... BF1346-O	Radial Seal XP Air (Upgrade) (Don. P527682)..... RS3518XP
Trans. Breather (Fuller Trans.).... CLN&R	Fuel/Water Separator Spin-on (w/Drain) (Racor S3226P)..... BF1346	Cab Air (Fresh Air) (F6HZ19N619AA)..... PA5337
Steering (Nelson 87904M)..... PT9354-MPG	Fuel/Water Separator Spin-on (w/Sensor Port) (Racor S3226P).. BF1346-SP	Cab Air (Recirculation) (F6HZ19N619BA)..... PA5393
Some Rear Axle (Meritor 3280-V-5040)..... B27	Fuel (1R0749)..... BF7587 +	Air Dryer (Wabco R950011)..... BA5374 +
L9500, LT9500 w/Cat C13 (12.5L) Eng. (To 1/2004)	15 1/4 In. Radial Seal Air (Standard) (Don. P527682)..... RS3518	Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT
Lube (1R0716)..... B99 +	15 1/4 In. Radial Seal XP Air (Upgrade) (Don. P527682)..... RS3518XP	Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT
Fuel/Water Separator Spin-on (Open End for Bowl) (Racor S3226P)..... BF1346-O	15 5/8 In. Radial Seal Air (Don. P533930)..... RS3548	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004
Fuel/Water Separator Spin-on (w/Drain) (Racor S3226P)..... BF1346	15 5/8 In. Radial Seal XP Air (Don. P533930)..... RS3548XP	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016
Fuel/Water Separator Spin-on (w/Sensor Port) (Racor S3226P).. BF1346-SP	Cab Air (Fresh Air) (F6HZ19N619AA)..... PA5337	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003
Fuel (1R0749)..... BF7587 +	Cab Air (Recirculation) (F6HZ19N619BA)..... PA5393	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017
15 1/4 In. Radial Seal Air (Standard) (Don. P527682)..... RS3518	Air Dryer (Wabco R950011)..... BA5374 +	Trans. Spin-on (Allison 29539579)..... BT8460
15 1/4 In. Radial Seal XP Air (Upgrade) (Don. P527682)..... RS3518XP	Breather (296-8325)..... CV15008	Opt. Trans. Spin-on (Fuller 17237)..... B2 +
15 5/8 In. Radial Seal Air (Don. P533930)..... RS3548	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004	Trans. Breather (Fuller Trans.).... CLN&R
15 5/8 In. Radial Seal XP Air (Don. P533930)..... RS3548XP	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016	Steering (Nelson 87904M)..... PT9354-MPG
Cab Air (Fresh Air) (F6HZ19N619AA)..... PA5337	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003	Steering (VML/T 1808D)..... BT9388
Cab Air (Recirculation) (F6HZ19N619BA)..... PA5393	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017	Some Rear Axle (Meritor 3280-V-5040)..... B27
Air Dryer (Wabco R950011)..... BA5374 +	Trans. Spin-on (Allison 29539579)..... BT8460	L9500, LT9500, LT9513 w/Cummins ISM 10.8 (10.8L) Eng.
Breather (296-8325)..... CV15008	Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	Dual-Flow Lube (Fleetguard LF9000)..... BD7153 +
Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... 20004	Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Dual-Flow Lube (Fleetguard LF9001)..... BD7154 +
Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... 20016	Opt. Trans. Spin-on (Fuller 17237)..... B2 +	Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... BD50000
Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... 20003	Trans. Breather (Fuller Trans.).... CLN&R	Fuel/Water Separator (3329289)..... BF1259
Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... 20017	Steering (Nelson 87904M)..... PT9354-MPG	Radial Seal Air (Standard) (Don. P527682)..... RS3518
Trans. Spin-on (Allison 29539579)..... BT8460	Steering (VML/T 1808D)..... BT9388	Radial Seal XP Air (Upgrade) (Don. P527682)..... RS3518XP
	Some Rear Axle (Meritor 3280-V-5040)..... B27	Cab Air (Fresh Air) (F6HZ-19N619-AA)..... PA5337
		Cab Air (Recirculation) (F6HZ-19N619-BA)..... PA5393
		Air Dryer (Wabco R950011)..... BA5374 +

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

STERLING Trucks (cont'd)	STERLING Trucks (cont'd)	STERLING Trucks (cont'd)
L9500, LT9500, LT9513 w/Cummins ISM 10.8 (10.8L) Eng. (Cont'd)	L9511 w/Cummins M11 (10.8L) Eng. (Cont'd)	L9511, L9513, LT9500, LT9501, LT9511, LT9513, LT9522 w/Detroit Diesel Series 60 Eng. (To 12/2003) (Cont'd)
Coolant (3100304)..... <b>BW5071</b>	Fuel/Water Separator Spin-on (3329289)..... <b>BF1259</b>	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2+</b>
Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	Dual-Flow Lube (3318853)..... <b>BD103+</b>	Trans. Breather (Fuller Trans.).... <b>CLN&amp;R</b>
Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	F-F Lube (Fleetguard LF670SC).. <b>B196+</b>	Steering (Nelson 87904M)..... <b>PT9354-MPG</b>
Trans. Pan-Type (MT Series) (Allison 29538489)..... <b>19739+</b>	B-P Lube (3304232)..... <b>B7577</b>	Steering (VML/T1808D)..... <b>BT9388</b>
Trans. Pan-Type (1000 Series, S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	Opt. Fuel/Water Separator (3308638)..... <b>BF1212+</b>	Some Rear Axle (Meritor 3280-V-5040)..... <b>B27</b>
Trans. Pan-Type (1000 Series, S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	Fuel (154789)..... <b>BF957-D+</b>	
Trans. Pan-Type (1000 Series, D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	L9511 w/Cummins NTC (14.0L) Eng.	L9511, L9513, LT9500, LT9501, LT9511, LT9513, LT9522 w/Detroit Diesel Series 60 Eng (12/2003-on)
Trans. Pan-Type (1000 Series, D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	Dual-Flow Lube (3318853)..... <b>BD103+</b>	Lube (23530573)..... <b>[2] B495</b>
Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>	F-F Lube Ele. (158139)..... <b>P999-HD</b>	Fuel/Water Separator Ele. (23529168)..... <b>PF7748</b>
Opt. Trans. Spin-on (Fuller 17237)..... <b>B2+</b>	F-F Lube Spin-on (3313279)..... <b>B196+</b>	Fuel/Water Separator Spin-on (w/Drain) (23512317)..... <b>BF5813+</b>
Some Rear Axle (Meritor 3280-V-5040)..... <b>B27</b>	B-P Lube Ele. (256838)..... <b>C750-E+</b>	Fuel/Water Separator Spin-on (Open End for Bowl) (23512317).. <b>BF5813-O+</b>
	B-P Lube Spin-on (3313283)..... <b>B7577</b>	P. Fuel (23530706)..... <b>BF5800+</b>
	Fuel/Water Separator (3308638). <b>BF1212+</b>	S. Fuel (23530645)..... <b>BF5815</b>
	Fuel (158172)..... <b>BF957+</b>	S. Fuel (23533726)..... <b>BF5816</b>
	L9511 w/Detroit Diesel Series 55 (12.0L) Eng.	Radial Seal Air (Standard) (Don. P527682)..... <b>RS3518</b>
	Lube (23550401)..... <b>B7135</b>	Radial Seal XP Air (Upgrade) (Don. P527682)..... <b>RS3518XP</b>
	Fuel (23530707)..... <b>BF5810</b>	Cab Air (Fresh Air) (F6HZ19N619AA)..... <b>PA5337</b>
	L9511, L9513, LT9500, LT9501, LT9511, LT9513, LT9522 w/Detroit Diesel Series 60 Eng (To 12/2003)	Cab Air (Recirculation) (F6HZ19N619BA)..... <b>PA5393</b>
	Lube (23530573)..... <b>[2] B495</b>	Air Dryer (Wabco R950011)..... <b>BA5374+</b>
	Fuel/Water Separator Ele. (23529168)..... <b>PF7748</b>	Coolant (Nalcool NF2088)..... <b>BW5200</b>
	Fuel/Water Separator Spin-on (w/Drain) (23512317)..... <b>BF5813+</b>	Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
	Fuel/Water Separator Spin-on (Open End for Bowl) (23512317).. <b>BF5813-O+</b>	Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
	P. Fuel (23530706)..... <b>BF5800+</b>	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
	S. Fuel (23518482)..... <b>BF5810</b>	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
	Radial Seal Air (Standard) (Don. P527682)..... <b>RS3518</b>	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
	Radial Seal XP Air (Upgrade) (Don. P527682)..... <b>RS3518XP</b>	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
	Cab Air (Fresh Air) (F6HZ19N619AA)..... <b>PA5337</b>	Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>
	Cab Air (Recirculation) (F6HZ19N619BA)..... <b>PA5393</b>	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2+</b>
	Air Dryer (Wabco R950011)..... <b>BA5374+</b>	Trans. Breather (Fuller Trans.).... <b>CLN&amp;R</b>
	Coolant (Nalcool NF2088)..... <b>BW5200</b>	Steering (Nelson 87904M)..... <b>PT9354-MPG</b>
	Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	Steering (VML/T1808D)..... <b>BT9388</b>
	Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	Some Rear Axle (Meritor 3280-V-5040)..... <b>B27</b>
	Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	
	Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	L9513 w/Cat 3306 (10.5L) Eng.
	Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	Lube Ele. (5S0484)..... <b>PT670</b>
	Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	Lube Spin-on (1R0716)..... <b>B99+</b>
	Trans. Spin-on (Allison 29539579)..... <b>BT8460</b>	Lube Spin-on (Standard Vers.) (1R0739)..... <b>B76+</b>
	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2+</b>	Lube Spin-on (Severe Service) (1R0739)..... <b>B76-SS+</b>
	Trans. Breather (Fuller Trans.).... <b>CLN&amp;R</b>	P. Fuel Ele. (9M2342)..... <b>PF935</b>
	Steering (Nelson 87904M)..... <b>PT9354-MPG</b>	P. Fuel Spin-on (1R1740)..... <b>BF970+</b>
	Steering (VML/T1808D)..... <b>BT9388</b>	S. Fuel Spin-on (1R0750)..... <b>BF7633+</b>
	Some Rear Axle (Meritor 3280-V-5040)..... <b>B27</b>	
		L9501 w/Cat 3306 (10.5L) Eng.
		Dual-Flow Lube (3318853)..... <b>BD103+</b>
		Fuel/Water Separator Ele. (Davco 380087)..... <b>PF7680</b>
		Fuel/Water Separator Spin-on (3329289)..... <b>BF1259</b>
		L9511 w/Cat 3306 (10.5L) Eng.
		Lube Ele. (5S0484)..... <b>PT670</b>
		Lube Spin-on (1R0716)..... <b>B99+</b>
		Lube Spin-on (Standard Vers.) (1R0739)..... <b>B76+</b>
		Lube Spin-on (Severe Service) (1R0739)..... <b>B76-SS+</b>
		P. Fuel Ele. (9M2342)..... <b>PF935</b>
		P. Fuel Spin-on (1R1740)..... <b>BF970+</b>
		S. Fuel Spin-on (1R0750)..... <b>BF7633+</b>
		L9511 w/Cummins M11 (10.8L) Eng.
		Dual-Flow Lube (3318853)..... <b>BD103+</b>
		Fuel/Water Separator Ele. (Davco 380087)..... <b>PF7680</b>

\* See Product Guide for Variations of This Number. Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

STERLING Trucks (cont'd)	STERLING Trucks (cont'd)	STERLING Trucks (cont'd)
<b>LT9513 w/Cat 3306 (10.5L) Eng. (Cont'd)</b> <b>Lube Spin-on (Severe Service)</b> (1R0739)..... <b>B76-SS+</b> <b>P. Fuel Ele. (9M2342)..... PF935</b> <b>P. Fuel Spin-on (1R1740)..... BF970+</b> <b>S. Fuel Spin-on (1R0750)..... BF7633+</b>	<b>LT9500 w/Cat 3306 (10.5L) Eng.</b> <b>Lube Ele. (5S0484)..... PT670</b> <b>Lube Spin-on (1R0716)..... B99+</b> <b>Lube Spin-on (Standard Vers.) (1R0739)..... B76+</b> <b>Lube Spin-on (Severe Service) (1R0739)..... B76-SS+</b> <b>P. Fuel Ele. (9M2342)..... PF935</b> <b>P. Fuel Spin-on (1R1740)..... BF970+</b> <b>S. Fuel Spin-on (1R0750)..... BF7633+</b> <b>Radial Seal Air (Standard) (Don. P527682)..... RS3518</b> <b>Radial Seal XP Air (Upgrade) (Don. P527682)..... RS3518XP</b>	<b>LT9500 w/Cummins L10 (10.0L) Eng.</b> <b>Dual-Flow Lube (3318853)..... BD103+</b> <b>F-F Lube (Fleetguard LF670SC).. B196+</b> <b>B-P Lube (3304232)..... B7577</b> <b>Fuel (154789)..... BF957-D+</b>
<b>LT9513 w/Cummins M11 (10.8L) Eng.</b> <b>Dual-Flow Lube (3318853)..... BD103+</b> <b>Fuel/Water Separator Ele. (Davco 380087)..... PF7680</b> <b>Fuel/Water Separator Spin-on (3329289)..... BF1259</b>	<b>LT9500 w/Cat 3406 (14.6L) Eng.</b> <b>F-F Lube (Std. Version) (1R0716)..... B99+</b> <b>F-F Lube (High Efficiency Vers.) (1R1808)..... B7299+</b> <b>Fuel/Water Separator Spin-on (2568753)..... BF1259</b> <b>P. Fuel Ele. (9M2341)..... [2] PF935</b> <b>Fuel Spin-on (1R0749)..... BF7587+</b> <b>Fuel Spin-on (1R0712)..... BF614+</b> <b>Radial Seal Air (Standard) (Don. P527682)..... RS3518</b> <b>Radial Seal XP Air (Upgrade) (Don. P527682)..... RS3518XP</b>	<b>LT9500 w/Cummins M11 (10.8L) Eng.</b> <b>Dual-Flow Lube (3318853)..... BD103+</b> <b>Fuel/Water Separator Ele. (Davco 380087)..... PF7680</b> <b>Fuel/Water Separator Spin-on (3329289)..... BF1259</b> <b>Radial Seal Air (Standard) (Don. P527682)..... RS3518</b> <b>Radial Seal XP Air (Upgrade) (Don. P527682)..... RS3518XP</b>
<b>LT9513 w/Cummins N14 (14.0L) Eng.</b> <b>Dual-Flow Lube (3318853)..... BD103+</b> <b>F-F Lube (Fleetguard LF670SC).. B196+</b> <b>B-P Lube (3304232)..... B7577</b> <b>Opt. Fuel/Water Separator (3308638)..... BF1212+</b> <b>Fuel (154789)..... BF957-D+</b>	<b>LT9500 w/Cat C16 (15.8L) Eng.</b> <b>Lube (1R0716)..... B99+</b> <b>Fuel/Water Separator (Open End for Bowl) (1335673)..... BF1395-O</b> <b>Fuel/Water Separator (w/Drain) (1335673)..... BF1265</b> <b>Fuel/Water Separator (w/Sensor Port) (1335673)..... BF1395-SP</b> <b>Fuel/Water Separator (2568753)..... BF1259</b> <b>Fuel Ele. (9M2342)..... [2] PF935</b> <b>Fuel Spin-on (Standard Vers.) (1R1712)..... BF614+</b> <b>Fuel Spin-on (High Efficiency Vers.) (1R0749)..... BF7587+</b> <b>Radial Seal Air (Standard) (Don. P527682)..... RS3518</b> <b>Radial Seal XP Air (Upgrade) (Don. P527682)..... RS3518XP</b>	<b>LT9500 w/Cummins N14 (14.0L) Eng.</b> <b>Dual-Flow Lube (3318853)..... BD103+</b> <b>F-F Lube (Fleetguard LF670SC).. B196+</b> <b>B-P Lube (3304232)..... B7577</b> <b>Opt. Fuel/Water Separator (3308638)..... BF1212+</b> <b>Fuel (154789)..... BF957-D+</b> <b>Radial Seal Air (Standard) (Don. P527682)..... RS3518</b> <b>Radial Seal XP Air (Upgrade) (Don. P527682)..... RS3518XP</b>
<b>L9522, LT9501 w/Cat 3126 (7.2L) Eng. (To 1/2004)</b> <b>Lube (Standard Vers.) (1R0739).. B76+</b> <b>Lube (Severe Service) (1R0739).. B76-SS+</b> <b>Trans. Ele. (Allison 3000 Series, 2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT</b> <b>Trans. Ele. (Allison 3000 Series, 4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT</b> <b>Trans. Pan-Type (Allison MT Series) (Allison 29538489)..... 19739+</b> <b>Opt. Trans. Spin-on (Fuller 17237)..... B2+</b>	<b>LT9500 w/Cat 3176 (10.3L) Eng.</b> <b>F-F Lube (Std. Version) (1R0716)..... B99+</b> <b>F-F Lube (High Efficiency Vers.) (1R1808)..... B7299+</b> <b>Opt. B-P Lube (1W8845)..... B7577</b> <b>Fuel/Water Separator Ele. (8N0205)..... PF316</b> <b>Fuel/Water Separator Spin-on (2568753)..... BF1259</b> <b>P. Fuel Spin-on (1R1740)..... BF970+</b> <b>S. Fuel Spin-on (1R0750)..... BF7633+</b>	<b>LT9500 w/Detroit Diesel Series 55 (12.0L) Eng.</b> <b>Lube (23550401)..... B7135</b> <b>Fuel (23530707)..... BF5810</b>
<b>L9522, LT9501 w/Cat 3126 (7.2L) Eng. (1/2004-on)</b> <b>Lube (1R1807)..... B7700+</b> <b>Trans. Ele. (Allison 3000 Series, 2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT</b> <b>Trans. Ele. (Allison 3000 Series, 4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT</b> <b>Trans. Pan-Type (Allison MT Series) (Allison 29538489)..... 19739+</b> <b>Opt. Trans. Spin-on (Fuller 17237)..... B2+</b>	<b>LT9501 w/Cat 3176 (10.3L) Eng.</b> <b>F-F Lube (Std. Version) (1R0716)..... B99+</b> <b>F-F Lube (High Efficiency Vers.) (1R1808)..... B7299+</b> <b>Opt. B-P Lube (1W8845)..... B7577</b> <b>Fuel/Water Separator Ele. (8N0205)..... PF316</b> <b>Fuel/Water Separator Spin-on (2568753)..... BF1259</b> <b>P. Fuel Spin-on (1R1740)..... BF970+</b> <b>S. Fuel Spin-on (1R0750)..... BF7633+</b>	<b>LT9501 w/Cat 3176 (10.3L) Eng.</b> <b>F-F Lube (Std. Version) (1R0716)..... B99+</b> <b>F-F Lube (High Efficiency Vers.) (1R1808)..... B7299+</b> <b>Opt. B-P Lube (1W8845)..... B7577</b> <b>Fuel/Water Separator Ele. (8N0205)..... PF316</b> <b>Fuel/Water Separator Spin-on (2568753)..... BF1259</b> <b>P. Fuel Spin-on (1R1740)..... BF970+</b> <b>S. Fuel Spin-on (1R0750)..... BF7633+</b>
<b>LT9500 w/Cat 3176 (10.3L) Eng.</b> <b>F-F Lube (Std. Version) (1R0716)..... B99+</b> <b>F-F Lube (High Efficiency Vers.) (1R1808)..... B7299+</b> <b>Opt. B-P Lube (1W8845)..... B7577</b> <b>Fuel/Water Separator Ele. (8N0205)..... PF316</b> <b>Fuel/Water Separator Spin-on (2568753)..... BF1259</b> <b>P. Fuel Spin-on (1R1740)..... BF970+</b> <b>S. Fuel Spin-on (1R0750)..... BF7633+</b>	<b>LT9500 w/Cat C16 (15.8L) Eng.</b> <b>Lube (1R0716)..... B99+</b> <b>Fuel/Water Separator (Open End for Bowl) (1335673)..... BF1395-O</b> <b>Fuel/Water Separator (w/Drain) (1335673)..... BF1265</b> <b>Fuel/Water Separator (w/Sensor Port) (1335673)..... BF1395-SP</b> <b>Fuel/Water Separator (2568753)..... BF1259</b> <b>Fuel Ele. (9M2342)..... [2] PF935</b> <b>Fuel Spin-on (Standard Vers.) (1R1712)..... BF614+</b> <b>Fuel Spin-on (High Efficiency Vers.) (1R0749)..... BF7587+</b> <b>Radial Seal Air (Standard) (Don. P527682)..... RS3518</b> <b>Radial Seal XP Air (Upgrade) (Don. P527682)..... RS3518XP</b>	<b>LT9501 w/Cat 3306 (10.5L) Eng.</b> <b>Lube Ele. (5S0484)..... PT670</b> <b>Lube Spin-on (1R0716)..... B99+</b> <b>Lube Spin-on (Standard Vers.) (1R0739)..... B76+</b> <b>Lube Spin-on (Severe Service) (1R0739)..... B76-SS+</b> <b>P. Fuel Ele. (9M2342)..... PF935</b> <b>P. Fuel Spin-on (1R1740)..... BF970+</b> <b>S. Fuel Spin-on (1R0750)..... BF7633+</b>
<b>LT9500 w/Cat 3176 (10.3L) Eng.</b> <b>F-F Lube (Std. Version) (1R0716)..... B99+</b> <b>F-F Lube (High Efficiency Vers.) (1R1808)..... B7299+</b> <b>Opt. B-P Lube (1W8845)..... B7577</b> <b>Fuel/Water Separator Ele. (8N0205)..... PF316</b> <b>Fuel/Water Separator Spin-on (2568753)..... BF1259</b> <b>P. Fuel Spin-on (1R1740)..... BF970+</b> <b>S. Fuel Spin-on (1R0750)..... BF7633+</b>	<b>LT9500 w/Cummins 4BT3.9 (3.9L) Eng.</b> <b>Lube (3903224)..... BT427+</b> <b>Fuel/Water Separator (3903202)..... BF1226</b> <b>Fuel (3903640)..... BF788</b>	<b>LT9501 w/Cummins M11 (10.8L) Eng.</b> <b>Dual-Flow Lube (3318853)..... BD103+</b> <b>Fuel/Water Separator Ele. (Davco 380087)..... PF7680</b> <b>Fuel/Water Separator Spin-on (3329289)..... BF1259</b>
<b>LT9500 w/Cummins 6CT8.3 (8.3L) Eng.</b> <b>F-F Lube (3313281)..... B205+</b> <b>Dual-Flow Lube (3318853)..... BD103+</b> <b>Fuel/Water Separator (3925274)..... BF1280+</b> <b>Fuel (3903640)..... BF788</b> <b>Radial Seal Air (Don. P533930)..... RS3548</b> <b>Radial Seal XP Air (Don. P533930)..... RS3548XP</b>	<b>LT9500 w/Cummins 6CT8.3 (8.3L) Eng.</b> <b>F-F Lube (3313281)..... B205+</b> <b>Dual-Flow Lube (3318853)..... BD103+</b> <b>Fuel/Water Separator (3925274)..... BF1280+</b> <b>Fuel (3903640)..... BF788</b> <b>Radial Seal Air (Don. P533930)..... RS3548</b> <b>Radial Seal XP Air (Don. P533930)..... RS3548XP</b>	<b>LT9501 w/Cummins M11 (10.8L) Eng.</b> <b>Dual-Flow Lube (3318853)..... BD103+</b> <b>Fuel/Water Separator Ele. (Davco 380087)..... PF7680</b> <b>Fuel/Water Separator Spin-on (3329289)..... BF1259</b>

\* See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

STERLING Trucks (cont'd)	STERLING Trucks (cont'd)	STERLING Trucks (cont'd)
LT9501 w/Cummins N14 (14.0L) Eng. Dual-Flow Lube (3318853)..... <b>BD103</b> + F-F Lube (Fleetguard LF670SC).. <b>B196</b> + B-P Lube (3304232)..... <b>B7577</b> Opt. Fuel/Water Separator (3308638)..... <b>BF1212</b> + Fuel (154789)..... <b>BF957-D</b> +	LT9511 w/Detroit Diesel Series 55 (12.0L) Eng. Lube (23550401)..... <b>B7135</b> Fuel (23530707)..... <b>BF5810</b> LT9513 w/Cat 3306 (10.5L) Eng. Lube Ele. (5S0484)..... <b>PT670</b> Lube Spin-on (1R0716)..... <b>B99</b> + Lube Spin-on (Standard Vers.) (1R0739)..... <b>B76</b> + Lube Spin-on (Severe Service) (1R0739)..... <b>B76-SS</b> + P. Fuel Ele. (9M2342)..... <b>PF935</b> P. Fuel Spin-on (1R1740)..... <b>BF970</b> + S. Fuel Spin-on (1R0750)..... <b>BF7633</b> + LT9513 w/Cat 3406 (14.6L) Eng. F-F Lube (Std. Version) (1R0716)..... <b>B99</b> + F-F Lube (High Efficiency Vers.) (1R1808)..... <b>B7299</b> + Fuel/Water Separator Spin-on (2568753)..... <b>BF1259</b> P. Fuel Ele. (9M2341)..... <b>[2] PF935</b> Fuel Spin-on (1R0749)..... <b>BF7587</b> + Fuel Spin-on (1R0712)..... <b>BF614</b> + LT9513 w/Cummins M11 (10.8L) Eng. Dual-Flow Lube (3318853)..... <b>BD103</b> + Fuel/Water Separator Ele. (Davco 380087)..... <b>PF7680</b> Fuel/Water Separator Spin-on (3329289)..... <b>BF1259</b> LT9513 w/Detroit Diesel Series 55 (12.0L) Eng. Lube (23550401)..... <b>B7135</b> Fuel (23530707)..... <b>BF5810</b> LT9522 w/Cat 3406 (14.6L) Eng. F-F Lube (Std. Version) (1R0716)..... <b>B99</b> + F-F Lube (High Efficiency Vers.) (1R1808)..... <b>B7299</b> + Fuel/Water Separator Spin-on (2568753)..... <b>BF1259</b> P. Fuel Ele. (9M2341)..... <b>[2] PF935</b> Fuel Spin-on (1R0749)..... <b>BF7587</b> + Fuel Spin-on (1R0712)..... <b>BF614</b> + LT9522 w/Cummins M11 (10.8L) Eng. Dual-Flow Lube (3318853)..... <b>BD103</b> + Fuel/Water Separator Ele. (Davco 380087)..... <b>PF7680</b> Fuel/Water Separator Spin-on (3329289)..... <b>BF1259</b> LT9522 w/Cummins N14 (14.0L) Eng. Dual-Flow Lube (3318853)..... <b>BD103</b> + F-F Lube (Fleetguard LF670SC).. <b>B196</b> + B-P Lube (3304232)..... <b>B7577</b> Opt. Fuel/Water Separator (3308638)..... <b>BF1212</b> + Fuel (154789)..... <b>BF957-D</b> +	SC7000 Cargo w/Cat 3126 (7.2L) Eng. Lube (Standard Vers.) (1R0739).. <b>B76</b> + Lube (Severe Service) (1R0739).. <b>B76-SS</b> + Fuel/Water Separator (1752949).. <b>BF1268</b> Fuel/Water Separator (2568753).. <b>BF1259</b> Fuel/Water Separator (w/Sensor Port) (1986378)..... <b>BF7798-SP</b> Fuel/Water Separator (Open End for Bowl) (1986378)..... <b>BF7798-O</b> Fuel Ele. (9M2342)..... <b>[2] PF935</b> Fuel Spin-on (1R0751)..... <b>BF7632</b> SC7000 Cargo w/Cummins ISC 8.3 (8.3L) Eng. Dual-Flow Lube (Fleetguard LF9009)..... <b>BD7309</b> + Dual-Flow Lube (Fleetguard LF9548)..... <b>BD324</b> + Fuel (Fleetguard FF5488)..... <b>BF7815</b> Fuel (Fleetguard FF5636)..... <b>BF7924</b> SC7000 Cargo w/Cummins ISB (5.9L) Eng. Lube (3937736)..... <b>B7177</b> Fuel/Water Separator (w/Drain) (ABPN122S3226FL01)..... <b>BF1347</b> Fuel/Water Separator (Open End for Bowl) (ABPN122S3226FL01).. <b>BF1347-O</b> Fuel/Water Separator (w/Sensor Port) (ABPN122S3226FL01)..... <b>BF1373-SP</b> Fuel/Water Separator (Alliance ABPN122R50418)..... <b>BF9898-O</b> Trans. Spin-on (3000 Series) (Allison 29539579)..... <b>BT8460</b> Trans. Pan-Type (3000 Series, S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (3000 Series, S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (3000 Series, D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (3000 Series, D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Pan-Type (MT Series) (Allison 29538489)..... <b>19739</b> + Opt. Trans. Spin-on (Fuller 17237)..... <b>B2</b> + Trans. Breather (Fuller Trans.).... <b>CLN&amp;R</b> SC7000 Cargo w/Mercedes-Benz MBE4000 (12.8L) Eng. Lube (1802109)..... <b>P7230</b> Fuel (5410900151)..... <b>PF7761</b> SC8000 Cargo w/Cummins 6BT5.9 (5.9L) Eng. Lube (Chrysler 5083285AA)..... <b>BT7349</b> Fuel/Water Separator (3925274).. <b>BF1280</b> + Fuel (3903640)..... <b>BF788</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

**Trucks & Buses Applications** **BALDWIN FILTERS**

<b>STERLING Trucks (cont'd)</b>	<b>STERLING Trucks (cont'd)</b>	<b>STERLING Trucks (cont'd)</b>
SC8000 Cargo w/Cummins ISB (5.9L) Eng. <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel/Water Separator</b> (w/Drain) (ABPN122S3226FL01)..... <b>BF1347</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (ABPN122S3226FL01).. <b>BF1347-O</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (ABPN122S3226FL01)..... <b>BF1373-SP</b> <b>Fuel/Water Separator</b> (Alliance ABPN122R50418)..... <b>BF9898-O</b> <b>Trans. Pan-Type</b> (3000 Series, S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (3000 Series, S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (3000 Series, D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (3000 Series, D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (3000 Series) (Allison 29539579)..... <b>BT8460</b> <b>Trans. Pan-Type</b> (MT Series) (Allison 29538489)..... <b>19739 +</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Trans. Breather</b> (Fuller Trans.).... <b>CLN&amp;R</b>	Sports Chassis 6500 w/Cat 3126B Eng. (Cont'd) <b>Radial Seal XP Air</b> (Don. P185067)..... <b>RS2863XP</b> ST9500 w/Cat 3126 (7.2L) Eng. <b>Lube</b> (Standard Vers.) (1R0739).. <b>B76 +</b> <b>Lube</b> (Severe Service) (1R0739).. <b>B76-SS +</b> <b>Fuel/Water Separator</b> (1752949).. <b>BF1268</b> <b>Fuel/Water Separator</b> (2568753).. <b>BF1259</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (1986378)..... <b>BF7798-SP</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (1986378)..... <b>BF7798-O</b> <b>Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (1R0751)..... <b>BF7632</b> <b>Radial Seal Air</b> (Standard) (Don. P527682)..... <b>RS3518</b> <b>Radial Seal XP Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b> ST9500 w/Cat 3406 (14.6L) Eng. <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99 +</b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> <b>Fuel/Water Separator Spin-on</b> (2568753)..... <b>BF1259</b> <b>P. Fuel Ele.</b> (9M2341)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (1R0749)..... <b>BF7587 +</b> <b>Fuel Spin-on</b> (1R0712)..... <b>BF614 +</b> <b>Radial Seal Air</b> (Standard) (Don. P527682)..... <b>RS3518</b> <b>Radial Seal XP Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b> ST9500 w/Cat C12 (12.0L) Eng. <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99 +</b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> <b>B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (1335673)..... <b>BF1395-O</b> <b>Fuel/Water Separator</b> (w/Drain) (1335673)..... <b>BF1265</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (1335673)..... <b>BF1395-SP</b> <b>Fuel/Water Separator Spin-on</b> (2568753)..... <b>BF1259</b> <b>Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (Standard Vers.) (1R1712)..... <b>BF614 +</b> <b>Fuel Spin-on</b> (High Efficiency Vers.) (1R0749)..... <b>BF7587 +</b> <b>Radial Seal Air</b> (Standard) (Don. P527682)..... <b>RS3518</b> <b>Radial Seal XP Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b>	ST9500 w/Cat C15 (14.6L) Eng. <b>Lube</b> (1R0716)..... <b>B99 +</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (1335673)..... <b>BF1395-O</b> <b>Fuel/Water Separator</b> (w/Drain) (1335673)..... <b>BF1265</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (1335673)..... <b>BF1395-SP</b> <b>Fuel/Water Separator</b> (2568753).. <b>BF1259</b> <b>Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (Standard Vers.) (1R1712)..... <b>BF614 +</b> <b>Fuel Spin-on</b> (High Efficiency Vers.) (1R0749)..... <b>BF7587 +</b> <b>Radial Seal Air</b> (Standard) (Don. P527682)..... <b>RS3518</b> <b>Radial Seal XP Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b> ST9500 w/Cat C16 (15.8L) Eng. <b>Lube</b> (1R0716)..... <b>B99 +</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (1335673)..... <b>BF1395-O</b> <b>Fuel/Water Separator</b> (w/Drain) (1335673)..... <b>BF1265</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (1335673)..... <b>BF1395-SP</b> <b>Fuel/Water Separator</b> (2568753).. <b>BF1259</b> <b>Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (Standard Vers.) (1R1712)..... <b>BF614 +</b> <b>Fuel Spin-on</b> (High Efficiency Vers.) (1R0749)..... <b>BF7587 +</b> <b>Radial Seal Air</b> (Standard) (Don. P527682)..... <b>RS3518</b> <b>Radial Seal XP Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b> ST9500 w/Cummins ISM 10.8 (10.8L) Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154 +</b> <b>Dual-Flow Lube</b> (Fleetguard LF9031)..... <b>BD7509 +</b> <b>Dual-Flow Lube</b> (Fleetguard LF9000)..... <b>BD7153 +</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> (3406889)..... <b>BF1293-SPS</b> <b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1000)..... <b>BF1259</b> <b>Fuel/Water Separator Spin-on</b> (Closed End) (Fleetguard FS1282)..... <b>BF1282 +</b> <b>Radial Seal Air</b> (Standard) (Don. P527682)..... <b>RS3518</b> <b>Radial Seal XP Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b>
Silver Star w/Cat C15 Eng. <b>Lube</b> ..... <b>B99 +</b> <b>Fuel Spin-on</b> ..... <b>BF7587 +</b> <b>Radial Seal O. Air</b> (Ford F6HZ-9601-CA)..... <b>RS3738</b> <b>Radial Seal I. Air</b> (Ford F6HZ-9602-AA)..... <b>RS3739</b>		
Silver Star w/Cummins Signature 600 Eng. <b>14 7/32 In. Dual-Flow Lube</b> ..... <b>BD7153 +</b> <b>Opt. 11 13/16 In. Dual-Flow Lube</b> <b>BD7154 +</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator</b> ..... <b>BF1274-SP</b>		
Silver Star w/Detroit Diesel Series 60 Eng. <b>Lube</b> ..... <b>[2] B495</b>		
Sports Chassis 6500 w/Cat 3126B Eng. <b>Lube</b> (Standard Vers.)..... <b>B76</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R90P)..... <b>BF46083-O</b> <b>Fuel/Water Separator</b> (w/Bowl) (Racor R90P)..... <b>BF46072</b> <b>Fuel/Water Separator</b> (w/Drain) (Racor R90P)..... <b>BF1329</b> <b>Fuel/Water Separator</b> (Sensor Port Thd. 9/16-18) (Racor R90P).. <b>BF1329-SP</b> <b>Fuel/Water Separator</b> (Sensor Port Thd. 1/2-20) (Racor R90P).... <b>BF1339-SP +</b> <b>Fuel</b> ..... <b>BF7632</b> <b>Radial Seal Air</b> (Don. P185067).... <b>RS2863</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>STERLING Trucks (cont'd)</b>	<b>TEMSA BUS Buses (cont'd)</b>	<b>THERMO KING Engines (cont'd)</b>	
ST9500 w/Cummins ISM 10.8 (10.8L) Eng. (Cont'd)	TS35 w/Cummins ISL 8.9 (8.9L) Eng. (2017) (Cont'd)	DI 2.2L	
<b>Coolant</b> (w/o Chemical) (Fleetguard WF2127)..... <b>B5087</b>	<b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b>	<b>Std. F-F Lube</b> (11-3712)..... <b>BT365</b>	
<b>Coolant</b> (Controlled Release BTA+) (Fleetguard WF2121)..... <b>BW5250</b>	TS35 w/Cummins ISL 8.9 (8.9L) Eng. (2018)	<b>Heavy Duty F-F Lube</b> (11-5702).. <b>B129</b>	
<b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>	<b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b>	<b>B-P Lube</b> (11-5703)..... <b>B128</b>	
<b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b>	<b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b>	<b>Dual-Flow Lube</b> (11-7382)..... <b>BD7095</b>	
ST9500 w/Cummins N14 (14.0L) Eng.	TS35 w/Cummins ISL 8.9 (8.9L) Eng. (2019)	<b>Std. Fuel</b> (11-3693)..... <b>BF992</b>	
<b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b>	<b>Lube</b> (3401544)..... <b>B40142</b>	<b>Heavy Duty Fuel</b> (11-5705)..... <b>BF888</b>	
<b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196 +</b>	<b>Fuel</b> (5303743)..... <b>BF63000</b>	<b>Air</b> (11-7400)..... <b>PA2804</b>	
<b>B-P Lube</b> (3304232)..... <b>B7577</b>	TS35 w/Cummins ISL 8.9 (8.9L) Eng. (2020)	<b>THERMO KING Refrigeration Units</b>	
<b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1000)..... <b>BF1259</b>	<b>Lube</b> (5444774)..... <b>B40142</b>	Models w/Sunstrand Hydraulic Drive Unit Hyd..... <b>P186</b>	
<b>Fuel</b> (154789)..... <b>BF957-D +</b>	<b>Fuel</b> (5303743)..... <b>BF63000</b>	Models w/Fram Hsgs.	
<b>Radial Seal Air</b> (Standard) (Don. P527682)..... <b>RS3518</b>	TS45 w/Cummins ISX 11.9 (11.9L) Eng. (2018)	<b>Air</b> (FA121PL)..... <b>PA652</b>	
<b>Radial Seal XP Air</b> (Upgrade) (Don. P527682)..... <b>RS3518XP</b>	<b>Dual-Flow Lube</b> (Fleetguard LF14000NN)..... <b>BD50000</b>	CGS1250, GS1250 w/Mercedes-Benz C201, OM636 Engs.	
<b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>	<b>Fuel</b> (Fleetguard FF5776)..... <b>BF9885</b>	<b>F-F Lube Ele.</b> (11-2093)..... <b>PT82-HD +</b>	
ST9500 w/Detroit Diesel Series 60 (12.7L) and (14.0L) Eng.	TS45 w/Cummins ISX 11.9 (11.9L) Eng. (2019)	<b>F-F Lube Spin-on</b> (11-3712)..... <b>BT365</b>	
<b>Lube</b> ..... [2] <b>B495</b>	<b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b>	<b>F-F Lube Spin-on</b> (11-3871)..... <b>B129</b>	
<b>Fuel/Water Separator</b> (23521528)..... <b>PF7744</b>	<b>Fuel</b> (2893612)..... <b>BF9885</b>	<b>B-P Lube Ele.</b> (11-2685)..... <b>P52</b>	
<b>Radial Seal Air</b> (Standard) (Don. P526947)..... <b>RS3518</b>	TS45 w/Cummins ISX 11.9 (11.9L) Eng. (2020)	<b>B-P Lube Spin-on</b> (11-3746)..... <b>B128</b>	
<b>Radial Seal XP Air</b> (Upgrade) (Don. P526947)..... <b>RS3518XP</b>	<b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b>	<b>P. Fuel Ele.</b> (11-2230)..... <b>PF916</b>	
<b>Coolant</b> (23516489)..... <b>BW5200</b>	<b>Fuel</b> (2893612)..... <b>BF9885</b>	<b>P. Fuel Spin-on</b> (11-3692)..... <b>BF991</b>	
<b>TEMCO METAL PRODUCTS Auxiliary Power Units (APU)</b>		<b>P. Fuel Spin-on</b> (11-3854)..... <b>BF979 +</b>	
Idle Solutions w/403C-11 Perkins Eng.	<b>THAMES TRADER Trucks</b>		
<b>Lube</b> (140517050)..... <b>B1405</b>	Models w/4 Cyl. Eng.	<b>S. Fuel Ele.</b> (11-3068)..... <b>PF902</b>	
<b>Fuel</b> (26561117)..... <b>BF825 +</b>	<b>Lube</b> ..... <b>P190</b>	<b>S. Fuel Spin-on</b> (11-3693)..... <b>BF992</b>	
<b>Radial Seal Air</b> (Don. P822686)..... <b>RS3715</b>	1/2, 3/4 Ton Vans	<b>S. Fuel Spin-on</b> (11-3855)..... <b>BF888</b>	
<b>TEMSA BUS Buses</b>		Crown 500 w/Mercedes-Benz C201, OM636 Engs.	
TS30 w/Cummins ISB6.7 (6.7L) Eng. (2014)	4D, 800	<b>F-F Lube Ele.</b> (11-2093)..... <b>PT82-HD +</b>	
<b>Lube</b> (3937736)..... <b>B7177</b>	<b>Lube</b> ..... <b>P190</b>	<b>F-F Lube Spin-on</b> (11-3712)..... <b>BT365</b>	
<b>Crankcase Breather</b> (4936636).... <b>CV15010</b>	<b>Fuel Ele.</b> ..... <b>PF816-S</b>	<b>F-F Lube Spin-on</b> (11-3871)..... <b>B129</b>	
<b>Diesel Exhaust Fluid</b> (2888182).... <b>PE17000</b>	5-7 CWT	<b>B-P Lube Ele.</b> (11-2685)..... <b>P52</b>	
TS30 w/Cummins ISB 6.7 (6.7L) Eng. (2020)	<b>Lube</b> (1962)..... <b>P240</b>	<b>B-P Lube Spin-on</b> (11-3746)..... <b>B128</b>	
<b>Lube</b> (3937736)..... <b>B7177</b>	6D	<b>P. Fuel Ele.</b> (11-2230)..... <b>PF916</b>	
<b>Fuel</b> (5303743)..... <b>BF63000</b>	<b>Lube</b> ..... <b>P15</b>	<b>P. Fuel Spin-on</b> (11-3692)..... <b>BF991</b>	
<b>Crankcase Breather</b> (4936636).... <b>CV15010</b>	<b>Fuel Ele.</b> ..... <b>PF816-S</b>	<b>P. Fuel Spin-on</b> (11-3854)..... <b>BF979 +</b>	
TS30 w/Cummins ISB 6.7 (6.7L) Eng. (2021)	<b>THERMO KING Auxiliary Power Units (APU)</b>		
<b>Lube</b> (3937736)..... <b>B7177</b>	TriPac w/2.70M TIER I Eng.	<b>S. Fuel Ele.</b> (11-3068)..... <b>PF902</b>	
<b>Fuel</b> (5303743)..... <b>BF63000</b>	<b>Lube</b> (11-6182)..... <b>B161-S</b>	<b>S. Fuel Spin-on</b> (11-3693)..... <b>BF992</b>	
<b>Crankcase Breather</b> (4936636).... <b>CV15010</b>	<b>Fuel</b> (11-9342)..... <b>BF9894</b>	<b>S. Fuel Spin-on</b> (11-3855)..... <b>BF888</b>	
TS35 w/Cummins ISL 8.9 (8.9L) Eng. (2017)	<b>Radial Seal Air</b> (11-9059)..... <b>RS3715</b>	DE	
<b>Lube</b> (Fleetguard LF9009)..... <b>B40142</b>	TriPac w/2.70M TIER II Eng.	<b>Dual-Flow Lube</b> (11-7382)..... <b>BD7095</b>	
<b>Fuel/Water Separator</b> (Fleetguard FS20081)..... <b>PF46171</b>	<b>Lube</b> (11-6182)..... <b>B161-S</b>	<b>Fuel/Water Separator</b> (11-9342). <b>BF9894</b>	
<b>THERMO KING Engines</b>		FB2M5 w/Mercedes-Benz OM636 Eng.	
	270M	<b>Lube</b> ..... <b>PT82-HD +</b>	
	<b>Lube</b> (11-6182)..... <b>B161-S</b>	<b>P. Fuel Sock</b> ..... <b>F916-C</b>	
		<b>S. Fuel Ele.</b> ..... <b>PF902</b>	
		JD	
		<b>F-F Lube</b> (11-6182)..... <b>B161-S</b>	
		<b>B-P Lube</b> (11-6228)..... <b>B7025</b>	
		<b>S. Fuel Ele.</b> (11-3068)..... <b>PF902</b>	
		<b>S. Fuel Spin-on</b> (11-3693)..... <b>BF992</b>	
		<b>Air</b> (11-7234)..... <b>PA3840</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

THERMO KING Refrigeration Units (cont'd)	THERMO KING Refrigeration Units (cont'd)	THERMO KING Refrigeration Units (cont'd)
<b>JD 1</b> F-F Lube (11-6182)..... B161-S B-P Lube (11-6228)..... B7025 Fuel (11-9098)..... BF992 Air (11-7234)..... PA3840	<b>LR w/Yanmar TK353 Eng.</b> F-F Lube (116182)..... B161-S B-P Lube (116228)..... B7025 Fuel (119098)..... BF992	<b>NWD, Super NWD, RMN, RMS, RMU, Sentry w/Mercedes-Benz C201, OM636 Engs.</b> F-F Lube Ele. (11-2093)..... PT82-HD + F-F Lube Spin-on (11-3712)..... BT365 F-F Lube Spin-on (11-3871)..... B129 B-P Lube Ele. (11-2685)..... P52 B-P Lube Spin-on (11-3746)..... B128 P. Fuel Ele. (11-2230)..... PF916 P. Fuel Spin-on (11-3692)..... BF991 P. Fuel Spin-on (11-3854)..... BF979 + S. Fuel Ele. (11-3068)..... PF902 S. Fuel Spin-on (11-3693)..... BF992 S. Fuel Spin-on (11-3855)..... BF888
<b>JDII (Australia)</b> F-F Lube (11-6182)..... B161-S B-P Lube (11-9321)..... B7025	<b>LR, MD w/TK353 Eng.</b> F-F Lube (11-5522)..... B247 B-P Lube (11-5703)..... B128 Fuel (11-3693)..... BF992	<b>RD w/TK353 Eng.</b> F-F Lube (11-5522)..... B247 B-P Lube (11-5703)..... B128 Fuel (11-3693)..... BF992
<b>JD II (New Zealand)</b> F-F Lube (11-6182)..... B161-S B-P Lube (11-6228)..... B7025 Fuel (11-9098)..... BF992 Air (11-7234)..... PA3840	<b>MD</b> F-F Lube (11-6182)..... B161-S B-P Lube (11-6228)..... B7025 S. Fuel Ele. (11-3068)..... PF902 S. Fuel Spin-on (11-9098)..... BF992 Air (11-7234)..... PA3840	<b>RD</b> F-F Lube (11-6182)..... B161-S B-P Lube (11-6228)..... B7025 S. Fuel Ele. (11-3068)..... PF902 S. Fuel Spin-on (11-9098)..... BF992 Air (11-7234)..... PA3840
<b>KD w/TK353 Eng.</b> F-F Lube (11-5522)..... B247 B-P Lube (11-5703)..... B128 Fuel (11-3693)..... BF992	<b>MDI w/Yanmar TK235 Eng.</b> F-F Lube (116182)..... B161-S B-P Lube (116228)..... B7025 P. Fuel (119098)..... BF992	<b>RD II, RS II SR (North America)</b> F-F Lube (11-6182)..... B161-S B-P Lube (11-6228)..... B7025 S. Fuel (11-9103)..... BF888 Air (11-7234)..... PA3840
<b>KD</b> F-F Lube (11-6182)..... B161-S B-P Lube (11-6228)..... B7025 S. Fuel Ele. (11-3068)..... PF902 S. Fuel Spin-on (11-3693)..... BF992 Air (11-7234)..... PA3840	<b>MDII MAX (New Zealand)</b> F-F Lube (11-6182)..... B161-S B-P Lube (11-6228)..... B7025 Fuel (11-9098)..... BF992 Air (11-7234)..... PA3840	<b>RDI w/Yanmar TK353 Eng.</b> F-F Lube (116182)..... B161-S B-P Lube (116228)..... B7025 P. Fuel (119098)..... BF992
<b>KDI w/Yanmar TK235 Eng.</b> F-F Lube (116182)..... B161-S B-P Lube (116228)..... B7025 P. Fuel (119098)..... BF992	<b>MDII (Australia)</b> F-F Lube (11-6182)..... B161-S B-P Lube (11-9321)..... B7025	<b>RDII (Australia)</b> F-F Lube (11-6182)..... B161-S B-P Lube (11-9321)..... B7025
<b>KDII (Australia)</b> F-F Lube (11-6182)..... B161-S B-P Lube (11-9321)..... B7025	<b>MDII w/Yanmar TK366, TK374 Engs. (North America)</b> F-F Lube (116182)..... B161-S B-P Lube (116228)..... B7025 P. Fuel (119098)..... BF992 Air (117234)..... PA3840	<b>RDII w/Yanmar TK388, TK395 Engs.</b> F-F Lube (116182)..... B161-S B-P Lube (116228)..... B7025 P. Fuel (119098)..... BF992 Air (117234)..... PA3840
<b>KDII w/Yanmar TK366, TK374 Engs. (North America)</b> F-F Lube (116182)..... B161-S B-P Lube (116228)..... B7025 P. Fuel (119098)..... BF992 Air (117234)..... PA3840	<b>MD1, RD1 Series w/TK235 Eng.</b> Lube (11-5522)..... B247 P. Fuel (11-3692)..... BF991 S. Fuel (11-3693)..... BF992	<b>RDII MAX</b> F-F Lube (11-6182)..... B161-S B-P Lube (11-6228)..... B7025 Fuel (11-9098)..... BF992 Air (11-7234)..... PA3840
<b>KD II, KD II Max, MD II (North America)</b> Lube (11-6228)..... B7025 Fuel (11-3693)..... BF992 Air (11-7234)..... PA3840	<b>MD-100</b> F-F Lube (11-6182)..... B161-S B-P Lube (11-9321)..... B7025	<b>RTDII</b> F-F Lube (11-6182)..... B161-S B-P Lube (11-9321)..... B7025
<b>KDII MAX</b> F-F Lube (11-6182)..... B161-S B-P Lube (11-6228)..... B7025 Fuel (11-9098)..... BF992 Air (11-7234)..... PA3840	<b>MD1T</b> Lube Spin-on (11-6228)..... B7025	<b>SB</b> Dual-Flow Lube (11-7382)..... BD7095 Fuel/Water Separator (11-9342)..... BF9894
<b>LND w/Yanmar TK353 Eng.</b> F-F Lube (116182)..... B161-S B-P Lube (116228)..... B7025 Fuel (119098)..... BF992	<b>MD-200</b> F-F Lube (11-6182)..... B161-S B-P Lube (11-9321)..... B7025	<b>SB I w/Isuzu C201 Eng. (New Zealand)</b> F-F Lube (11-9100)..... B129 F-F Lube (11-9099)..... BT365 B-P Lube (11-9101)..... B128 Fuel/Water Separator (11-5948)..... BF1212 + Air (11-7400)..... PA2804
<b>LND, LND II</b> Lube (11-6182)..... B161-S Fuel..... BF992 Air (11-5692)..... PA1865-FN	<b>MD-300</b> F-F Lube (11-6182)..... B161-S B-P Lube (11-9321)..... B7025	
	<b>NWD w/Mercedes Benz OM636 Eng.</b> F-F Lube Ele. (112093)..... PT82-HD + F-F Lube (119099)..... BT365 B-P Lube (112685)..... P52 P. Fuel (112230)..... PF916 P. Fuel (119097)..... BF991 S. Fuel (113068)..... PF902 S. Fuel (119098)..... BF992	

+ See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



THERMO KING Refrigeration Units (cont'd)	THERMO KING Refrigeration Units (cont'd)	THERMO KING Refrigeration Units (cont'd)
<b>SB1 w/Isuzu C201 Eng. (North America)</b> F-F Lube (119099)..... <b>BT365</b> F-F Lube..... <b>B129</b> B-P Lube..... <b>B128</b> P. Fuel (119097)..... <b>BF991</b> P. Fuel (119102)..... <b>BF979 +</b> S. Fuel (119098)..... <b>BF992</b> S. Fuel (119103)..... <b>BF888</b>	<b>SBII w/DI 2.2 Eng</b> F-F Lube (119099)..... <b>BT365</b> F-F Lube..... <b>B129</b> B-P Lube..... <b>B128</b> P. Fuel (119097)..... <b>BF991</b> P. Fuel (119102)..... <b>BF979 +</b> P. Fuel (116285)..... <b>BF7579</b> S. Fuel (119098)..... <b>BF992</b> S. Fuel (119103)..... <b>BF888</b> S. Fuel (117264)..... <b>BF7580</b> S. Fuel (116286)..... <b>BF7576</b>	<b>SB III w/Se Eng. (New Zealand)</b> Dual-Flow Lube (11-7382)..... <b>BD7095</b> Fuel/Water Separator Box-Style (11-7264)..... <b>BF7580</b> Fuel/Water Separator Spin-on (11-8047)..... <b>BF9894</b> Box-Style Fuel (11-6285)..... <b>BF7579</b> Air (11-7400)..... <b>PA2804</b>
<b>SB-I</b> F-F Lube (11-9099)..... <b>BT365</b> F-F Lube (11-5702)..... <b>B129</b> B-P Lube (11-5703)..... <b>B128</b> Dual-Flow Lube (11-7382)..... <b>BD7095</b> Fuel/Water Separator (11-7264)..... <b>BF7580</b> P. Fuel (11-9097)..... <b>BF991</b> P. Fuel (11-9102)..... <b>BF979 +</b> S. Fuel Spin-on (11-3693)..... <b>BF992</b> S. Fuel Spin-on (11-5705)..... <b>BF888</b> Air (11-3331)..... <b>PA1690-FN +</b> Disposable Air Hsg. (11-7400).... <b>PA2804</b> Air (11-7234)..... <b>PA3840</b>	<b>SB-II</b> F-F Lube (11-9099)..... <b>BT365</b> F-F Lube (11-5702)..... <b>B129</b> B-P Lube (11-5703)..... <b>B128</b> Dual-Flow Lube (11-7382)..... <b>BD7095</b> Fuel/Water Separator (11-7264)..... <b>BF7580</b> P. Fuel (11-9102)..... <b>BF979 +</b> P. Fuel (11-9103)..... <b>BF888</b> P. Fuel (11-9097)..... <b>BF991</b> P. Fuel (11-6285)..... <b>BF7579</b> S. Fuel (11-9098)..... <b>BF992</b> Disposable Air Hsg. (11-7400).... <b>PA2804</b> Air (11-7234)..... <b>PA3840</b>	<b>SB-III w/TK486 EMI 3000 Eng.</b> F-F Lube (119182)..... <b>B7375</b> Fuel/Water Separator (119342).... <b>BF9894</b> Radial Seal Air (119300)..... <b>RS5387 KIT</b>
<b>SB1 w/Mercedes-Benz C201, OM636 Eng.</b> F-F Lube Ele. (11-2093)..... <b>PT82-HD +</b> F-F Lube Spin-on (11-3712)..... <b>BT365</b> F-F Lube Spin-on (11-3871)..... <b>B129</b> B-P Lube Ele. (11-2685)..... <b>P52</b> B-P Lube Spin-on (11-3746)..... <b>B128</b> P. Fuel Ele. (11-2230)..... <b>PF916</b> P. Fuel Spin-on (11-3692)..... <b>BF991</b> P. Fuel Spin-on (11-3854)..... <b>BF979 +</b> S. Fuel Ele. (11-3068)..... <b>PF902</b> S. Fuel Spin-on (11-3693)..... <b>BF992</b> S. Fuel Spin-on (11-3855)..... <b>BF888</b>	<b>SB II (Australia)</b> F-F Lube (11-9101)..... <b>B128</b> Comp. Lube (66-4917)..... <b>BT8842-MPG</b> P. Fuel (11-9097)..... <b>BF991</b> S. Fuel (11-9098)..... <b>BF992</b>	<b>SB-III w/Yanmar TK486 Eng.</b> Dual-Flow Lube (117382)..... <b>BD7095</b> Fuel/Water Separator (119342).... <b>BF9894</b> Air (117400)..... <b>PA2804</b>
<b>SB2 w/Mercedes-Benz C201, OM636 Eng.</b> F-F Lube Ele. (11-2093)..... <b>PT82-HD +</b> F-F Lube Spin-on (11-3712)..... <b>BT365</b> F-F Lube Spin-on (11-3871)..... <b>B129</b> B-P Lube Ele. (11-2685)..... <b>P52</b> B-P Lube Spin-on (11-3746)..... <b>B128</b> P. Fuel Ele. (11-2230)..... <b>PF916</b> P. Fuel Spin-on (11-3692)..... <b>BF991</b> P. Fuel Spin-on (11-3854)..... <b>BF979 +</b> S. Fuel Ele. (11-3068)..... <b>PF902</b> S. Fuel Spin-on (11-3693)..... <b>BF992</b> S. Fuel Spin-on (11-3855)..... <b>BF888</b>	<b>SB II w/DI Eng. (New Zealand)</b> F-F Lube (11-9099)..... <b>BT365</b> F-F Lube (Extended Maintenance Interval) (11-9100).... <b>B129</b> B-P Lube (11-9101)..... <b>B128</b> Fuel/Water Separator (11-5947)..... <b>BF1212 +</b> Air (11-7400)..... <b>PA2804</b>	<b>SB-III w/Se 2.2 Eng. (North America)</b> Dual-Flow Lube (117382)..... <b>BD7095</b> P. Fuel/Water Separator (119342).... <b>BF9894</b> S. Fuel/Water Separator (117264)..... <b>BF7580</b> Air (117400)..... <b>PA2804</b>
<b>SB2 II Max</b> F-F Lube (11-3871)..... <b>B129</b> B-P Lube (11-5703)..... <b>B128</b> S. Fuel (11-3693)..... <b>BF992</b> S. Fuel (11-5705)..... <b>BF888</b>	<b>SB III, SB III Max, SB III SRT w/Isuzu FE (2.2L) Eng.</b> Dual-Flow Lube (11-7382)..... <b>BD7095</b> Box-Style Fuel/Water Separator (11-7264)..... <b>BF7580</b> Box-Style Fuel (11-6285)..... <b>BF7579</b> Air (11-7400)..... <b>PA2804</b>	<b>SB-III</b> F-F Lube (11-9099)..... <b>BT365</b> F-F Lube (11-5702)..... <b>B129</b> F-F Lube (11-5703)..... <b>B128</b> Dual-Flow Lube (11-7382)..... <b>BD7095</b> B-P Lube (11-5703)..... <b>B128</b> Fuel/Water Separator Box-Style (11-7264)..... <b>BF7580</b> Fuel/Water Separator Spin-on (11-9342)..... <b>BF9894</b> P. Fuel (11-9103)..... <b>BF888</b> P. Fuel (11-5704)..... <b>BF979 +</b> P. Fuel (11-6285)..... <b>BF7579</b> S. Fuel (11-9098)..... <b>BF992</b> Disposable Air Hsg. (11-7400).... <b>PA2804</b> Air (11-7234)..... <b>PA3840</b>
<b>SBII w/Isuzu C201 Eng.</b> F-F Lube (119099)..... <b>BT365</b> F-F Lube..... <b>B129</b> B-P Lube..... <b>B128</b> P. Fuel (119097)..... <b>BF991</b> P. Fuel (119102)..... <b>BF979 +</b> S. Fuel (119098)..... <b>BF992</b> S. Fuel (119103)..... <b>BF888</b>	<b>SB III (Australia)</b> Dual-Flow Lube (11-7382)..... <b>BD7095</b> B-P Lube (11-9101)..... <b>B128</b> F-F Lube (11-9182)..... <b>B7375</b> Comp. Lube (66-4917)..... <b>BT8842-MPG</b> Fuel/Water Separator Box-Style (11-7264)..... <b>BF7580</b> Fuel/Water Separator Spin-on (Extended Maintenance Interval) (11-9342)..... <b>BF9894</b> Box-Style Fuel (11-6285)..... <b>BF7579</b> S. Fuel Spin-on (11-9098)..... <b>BF992</b>	<b>SB-100</b> Dual-Flow Lube (11-7382)..... <b>BD7095</b> Fuel/Water Separator (11-9342).... <b>BF9894</b>
	<b>SB-110</b> Dual-Flow Lube (11-7382)..... <b>BD7095</b> Fuel/Water Separator (11-9342).... <b>BF9894</b>	<b>SB-190 (Australia)</b> Dual-Flow Lube (11-7382)..... <b>BD7095</b> Fuel/Water Separator (11-9342).... <b>BF9894</b>
	<b>SB 190 (New Zealand)</b> Lube (11-9182)..... <b>B7375</b> Fuel/Water Separator (11-9342).... <b>BF9894</b> Air (11-9300)..... <b>RS5387 KIT</b>	<b>SB-200 (Australia)</b> Dual-Flow Lube (11-7382)..... <b>BD7095</b> Fuel/Water Separator (11-9342).... <b>BF9894</b>

+ See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

THERMO KING Refrigeration Units (cont'd)	THERMO KING Refrigeration Units (cont'd)	THERMO KING Refrigeration Units (cont'd)
SB200, SB300 (North America) Fuel/Water Separator (w/Drain) (119982)..... <b>BF1355</b> Fuel/Water Separator (w/Drain & Sensor Port) (119982)..... <b>BF1355-SP</b> Fuel/Water Separator (Open End for Bowl) (119982)..... <b>BF1355-O</b>	Sentry (Australia) Dual-Flow Lube (11-7382)..... <b>BD7095</b> F-F Lube (11-9182)..... <b>B7375</b> B-P Lube (11-9101)..... <b>B128</b> Comp. Lube (66-4917)..... <b>BT8842-MPG</b> Fuel/Water Separator Box-Style (11-7264)..... <b>BF7580</b> Fuel Box-Style (11-6285)..... <b>BF7579</b> Fuel (11-9097)..... <b>BF991</b> S. Fuel (11-9098)..... <b>BF992</b>	SL100, SL200, SL300, SL400 (North America) (Cont'd) Fuel/Water Separator Spin-on (Open End for Bowl) (119982)..... <b>BF1355-O</b> S. Fuel Spin-on (11-9342)..... <b>BF9894</b> Air (To 2/01) (11-7400)..... <b>PA2804</b> Radial Seal Air (2/2001-on) (11-9300)..... <b>RS5387 KIT</b>
SB-210 Dual-Flow Lube (11-7382)..... <b>BD7095</b> Fuel/Water Separator (11-9342)..... <b>BF9894</b>	Sentry (North America) F-F Lube (11-5702)..... <b>B129</b> F-F Lube (11-5703)..... <b>B128</b> F-F Lube (11-9099)..... <b>BT365</b> B-P Lube (11-5703)..... <b>B128</b> Dual-Flow Lube (11-7382)..... <b>BD7095</b> Fuel/Water Separator (11-7264)..... <b>BF7580</b> P. Fuel (11-9097)..... <b>BF991</b> P. Fuel (11-9103)..... <b>BF888</b> P. Fuel (11-5704)..... <b>BF979 +</b> P. Fuel (11-6285)..... <b>BF7579</b> S. Fuel (11-9098)..... <b>BF992</b> Disposable Air Hsg. (11-7400)..... <b>PA2804</b> Air (117234)..... <b>PA3840</b>	Spectrum F-F Lube (11-6182)..... <b>B161-S</b> B-P Lube (11-9321)..... <b>B7025</b>
SB-230 w/Yanmar TK486 Eng. Dual-Flow Lube (11-7382)..... <b>BD7095</b> F-F Lube (EMI 3000) (11-9182).... <b>B7375</b> Fuel/Water Separator (11-9342)..... <b>BF9894</b> Air (11-7400)..... <b>PA2804</b>	Spectrum SB TCI Lube (11-9182)..... <b>B7375</b> Fuel/Water Separator (11-9342)..... <b>BF9894</b> Air (11-9300)..... <b>RS5387 KIT</b>	Spectrum SL Lube (11-9182)..... <b>B7375</b> Fuel/Water Separator (11-9342)..... <b>BF9894</b> Air (11-9300)..... <b>RS5387 KIT</b>
SB 300 (New Zealand) Lube (11-9182)..... <b>B7375</b> Fuel/Water Separator (11-9342)..... <b>BF9894</b> Air (11-9300)..... <b>RS5387 KIT</b> Air (To 02/01) (11-7400)..... <b>PA2804</b>	Spectrum TS (Australia) F-F Lube (11-6182)..... <b>B161-S</b> B-P Lube (11-9321)..... <b>B7025</b>	Spectrum TS w/TK 3.95 Eng. (New Zealand) Lube (Extended Maintenance Interval) (11-9321)..... <b>B7025</b> F-F Lube (11-6182)..... <b>B161-S</b> Fuel (11-9341)..... <b>BF992</b> Radial Seal Air (11-9059)..... <b>RS3715</b>
SB-300 (Australia) Dual-Flow Lube (11-7382)..... <b>BD7095</b> Fuel/Water Separator (11-9342)..... <b>BF9894</b>	SNWD w/Isuzu C201 Eng. F-F Lube..... <b>B129</b> F-F Lube (119099)..... <b>BT365</b> B-P Lube..... <b>B128</b> P. Fuel (119097)..... <b>BF991</b> P. Fuel (119102)..... <b>BF979 +</b> S. Fuel (119098)..... <b>BF992</b> S. Fuel (119103)..... <b>BF888</b>	SR w/Yanmar TK374 Eng. F-F Lube (116182)..... <b>B161-S</b> B-P Lube (116228)..... <b>B7025</b> P. Fuel (119098)..... <b>BF992</b> Air (117234)..... <b>PA3840</b>
SB-310 Dual-Flow Lube (11-7382)..... <b>BD7095</b> Fuel/Water Separator (11-9342)..... <b>BF9894</b>	SMX, SMX SR, SMX II SR Dual-Flow Lube (11-7382)..... <b>BD7095</b> Fuel/Water Separator (11-7264)..... <b>BF7580</b> Fuel (11-6285)..... <b>BF7579</b> Air (11-7400)..... <b>PA2804</b>	SR w/Yanmar TK395 Eng. F-F Lube (116182)..... <b>B161-S</b> B-P Lube (116228)..... <b>B7025</b> P. Fuel (119098)..... <b>BF992</b> Air (117234)..... <b>PA3840</b>
SB 400 (New Zealand) Lube (11-9182)..... <b>B7375</b> Fuel/Water Separator (11-9342)..... <b>BF9894</b> Air (11-9300)..... <b>RS5387 KIT</b>	SNWD Lube (11-9099)..... <b>BT365</b> Lube (11-5702)..... <b>B129</b> Lube (11-5703)..... <b>B128</b> P. Fuel (11-9097)..... <b>BF991</b> P. Fuel (11-9102)..... <b>BF979 +</b> P. Fuel (11-9103)..... <b>BF888</b> S. Fuel (11-9098)..... <b>BF992</b> Air (11-3331)..... <b>PA1690-FN +</b> Air (11-7234)..... <b>PA3840</b>	SRL Lube..... <b>P40</b> Air..... <b>PA640</b>
SB-400 (Australia) Dual-Flow Lube (11-7382)..... <b>BD7095</b> Fuel/Water Separator (11-9342)..... <b>BF9894</b>	SL 100, SL 200 (New Zealand) Lube (11-9182)..... <b>B7375</b> Fuel/Water Separator (11-9342)..... <b>BF9894</b> Air (02/01-on) (11-9300)..... <b>RS5387 KIT</b>	SUPER F-F Lube (11-3712)..... <b>BT365</b> F-F Lube (11-5702)..... <b>B129</b> Dual-Flow Lube (11-7382)..... <b>BD7095</b> B-P Lube (11-5703)..... <b>B128</b> Fuel/Water Separator Box-Style (11-6286)..... <b>BF7576</b> Fuel/Water Separator Box-Style (11-7264)..... <b>BF7580</b> Fuel/Water Separator Spin-on (11-9342)..... <b>BF9894</b> P. Fuel (11-3692)..... <b>BF991</b> P. Fuel (11-5704)..... <b>BF979 +</b> P. Fuel (11-6285)..... <b>BF7579</b> S. Fuel (11-3693)..... <b>BF992</b> S. Fuel (11-5705)..... <b>BF888</b>
SDZ F-F Lube (11-6182)..... <b>B161-S</b> B-P Lube (11-6228)..... <b>B7025</b> S. Fuel (11-9103)..... <b>BF888</b> Air (11-7234)..... <b>PA3840</b>	Sentry w/Isuzu C201 Eng. F-F Lube..... <b>B129</b> F-F Lube (119099)..... <b>BT365</b> B-P Lube..... <b>B128</b> P. Fuel (119097)..... <b>BF991</b> P. Fuel (119102)..... <b>BF979 +</b> S. Fuel (119098)..... <b>BF992</b> S. Fuel (119103)..... <b>BF888</b>	
Sentry w/DI 2.2 Eng. F-F Lube..... <b>B129</b> F-F Lube (119099)..... <b>BT365</b> B-P Lube..... <b>B128</b> P. Fuel (119097)..... <b>BF991</b> P. Fuel (119102)..... <b>BF979 +</b> S. Fuel (119098)..... <b>BF992</b> S. Fuel (119103)..... <b>BF888</b>	SL100, SL200, SL300, SL400 (North America) Dual-Flow Lube (11-7382)..... <b>BD7095</b> Fuel/Water Separator Spin-on (w/Drain) (119982)..... <b>BF1355</b> Fuel/Water Separator Spin-on (w/Drain & Sensor Port) (119982)..... <b>BF1355-SP</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

THERMO KING Refrigeration Units (cont'd)	THERMO KING Refrigeration Units (cont'd)	THERMO KING Refrigeration Units (cont'd)
SUPER (Cont'd)	Super II w/Se Eng. (New Zealand)	TS-200 (Australia)
Disposable Air Hsg. (11-7400).... PA2804	Dual-Flow Lube (11-7382)..... BD7095	F-F Lube (11-6182)..... B161-S
Super II SR	Fuel/Water Separator (11-7264). BF7580	B-P Lube (11-9321)..... B7025
Dual-Flow Lube (11-7382)..... BD7095	Fuel (11-6285)..... BF7579	TS200 w/TK374 EMI 2000 Eng. (North America)
Box-Style Fuel/Water Separator (11-7264)..... BF7580	Air (11-7400)..... PA2804	F-F Lube (116182)..... B161-S
Box-Style Fuel (11-6285)..... BF7579	Super II	B-P Lube (119321)..... B7025
Air (11-7400)..... PA2804	F-F Lube (11-3712)..... BT365	P. Fuel (119341)..... BF992
SuperII Early w/Yanmar TK486 Eng.	B-P Lube (11-5703)..... B128	Radial Seal Air (119059)..... RS3715
Dual-Flow Lube (117382)..... BD7095	Fuel/Water Separator (11-6286). BF7576	TS-300 (Australia)
P. Fuel/Water Separator (119342)..... BF9894	Box-Style Fuel (11-6285)..... BF7579	F-F Lube (11-6182)..... B161-S
Air (117400)..... PA2804	T-600	B-P Lube (11-9321)..... B7025
Super II (Australia)	F-F Lube (11-6182)..... B161-S	TS300 w/TK 374 Eng. (North America)
Dual-Flow Lube (11-7382)..... BD7095	B-P Lube (11-9321)..... B7025	Lube (Extended Maintenance Interval) (11-9321)..... B7025
F-F Lube (11-9182)..... B7375	T-800	F-F Lube (11-6182)..... B161-S
B-P Lube (11-9101)..... B128	F-F Lube (11-6182)..... B161-S	F-F Lube (11-6182)..... B161-S
Comp. Lube (66-4917)..... BT8842-MPG	B-P Lube (11-9321)..... B7025	Fuel (11-9341)..... BF992
Fuel/Water Separator Box-Style (11-7264)..... BF7580	T-1000	Radial Seal Air (11-9059)..... RS3715
Fuel/Water Separator Spin-on (Extended Maintenance Interval) (11-9342)..... BF9894	F-F Lube (11-6182)..... B161-S	TS-500 (Australia)
P. Fuel (11-6285)..... BF7579	B-P Lube (11-9321)..... B7025	F-F Lube (11-6182)..... B161-S
Super II w/TK486 EMI 3000 Eng. (North America)	TD	B-P Lube (11-9321)..... B7025
F-F Lube (119182)..... B7375	F-F Lube (11-6182)..... B161-S	TS500, TS600 (North America)
P. Fuel/Water Separator (119342)..... BF9894	B-P Lube (11-5703)..... B128	F-F Lube (11-6182)..... B161-S
Radial Seal Air (119300)..... RS5387 KIT	Fuel/Water Separator (11-7264). BF7580	B-P Lube (11-6228)..... B7025
Super II w/DI 2.2 Eng. (North America)	S. Fuel Ele. (11-3068)..... PF902	S. Fuel (11-9098)..... BF992
F-F Lube..... B129	S. Fuel Spin-on (11-3693)..... BF992	Radial Seal Air (11-9059)..... RS3715
F-F Lube (119099)..... BT365	Air (11-7234)..... PA3840	TS-600 (Australia)
B-P Lube..... B128	TD1 Fuel Saver w/TK353 Eng.	F-F Lube (11-6182)..... B161-S
P. Fuel (119097)..... BF991	F-F Lube (11-5522)..... B247	B-P Lube (11-9321)..... B7025
P. Fuel (119102)..... BF979 +	B-P Lube (11-5703)..... B128	TWD w/Mercedes-Benz C201, OM636 Eng.
S. Fuel (119098)..... BF992	Fuel (11-3693)..... BF992	F-F Lube Ele. (11-2093)..... PT82-HD +
S. Fuel (119103)..... BF888	TDII w/Yanmar TK388, TK395 Eng. (North America)	F-F Lube Spin-on (11-3712)..... BT365
Super II w/DI Eng. (New Zealand)	F-F Lube (116182)..... B161-S	F-F Lube Spin-on (11-3871)..... B129
F-F Lube (11-9099)..... BT365	B-P Lube (116228)..... B7025	B-P Lube Ele. (11-2685)..... P52
F-F Lube (Extended Maintenance Interval) (11-9100).... B129	P. Fuel (119098)..... BF992	B-P Lube Spin-on (11-3746)..... B128
Fuel/Water Separator (To 04/91) (11-7264)..... BF7580	Air (117234)..... PA3840	P. Fuel Ele. (11-2230)..... PF916
Fuel (11-6285)..... BF7579	TD II	P. Fuel Spin-on (11-3692)..... BF991
Air (11-7400)..... PA2804	F-F Lube (11-6182)..... B161-S	P. Fuel Spin-on (11-3854)..... BF979 +
Super II w/Se 2.2 Eng. (North America)	B-P Lube (11-6228)..... B7025	S. Fuel Ele. (11-3068)..... PF902
Dual-Flow Lube (117382)..... BD7095	S. Fuel (11-9103)..... BF888	S. Fuel Spin-on (11-3693)..... BF992
P. Fuel/Water Separator Spin-on (119342)..... BF9894	Air (11-7234)..... PA3840	S. Fuel Spin-on (11-3855)..... BF888
S. Fuel/Water Separator Box-Style (117264)..... BF7580	TD II (New Zealand)	UL
Air (117400)..... PA2804	F-F Lube (11-6182)..... B161-S	Lube..... P40
Super II w/Se 2.2 Eng. (North America)	B-P Lube (11-6228)..... B7025	Air..... PA640
Dual-Flow Lube (117382)..... BD7095	Fuel (11-9098)..... BF992	UMD (New Zealand)
P. Fuel/Water Separator Spin-on (119342)..... BF9894	Air (11-7234)..... PA3840	Lube (11-6182)..... B161-S
S. Fuel/Water Separator Box-Style (117264)..... BF7580	TD II MAX	Fuel (11-9098)..... BF992
Air (117400)..... PA2804	F-F Lube (11-6182)..... B161-S	UMD, URD w/TK353 Eng. (North America)
	B-P Lube (11-6228)..... B7025	F-F Lube (11-5522)..... B247
	Fuel (11-9098)..... BF992	B-P Lube (11-5703)..... B128
	Air (11-7234)..... PA3840	Fuel (11-3693)..... BF992
	TS	URD (New Zealand)
	S. Fuel (11-9098)..... BF992	Lube (11-6182)..... B161-S
	Radial Seal Air (11-9059)..... RS3715	Fuel/Water Separator (11-8047). BF9894

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

THERMO KING Refrigeration Units (cont'd)	THOMAS Buses (cont'd)	THOMAS Buses (cont'd)
UTS	Models w/Luberfiner Air Cleaners	Saf-T-Liner w/Cat C7 Eng. (To 1/2004) (Cont'd)
Lube (11-6182)..... B161-S	Air (1992-on) (LAF959)..... PA2540 +	Steering (VMLT1808D)..... BT9388
Fuel/Water Separator (11-8047) BF9894	Saf-T-Liner w/Cat C7 Eng. (To 1/2004)	Saf-T-Liner w/Cat C7 Eng. (1/2004-on)
UWD, Super UWD, UWTD w/Mercedes-Benz C201, OM636 Eng.	Lube (Standard Vers.) (1R0739).. B76 +	Lube (1R1807)..... B7700 +
F-F Lube Ele. (11-2093)..... PT82-HD +	Lube (Severe Service) (1R0739).. B76-SS +	Fuel/Water Separator (w/o SP) (Alliance ABP-S3226FL02)..... BF1346 +
F-F Lube Spin-on (11-3712)..... BT365	Fuel/Water Separator (w/o SP) (Alliance ABP-S3226FL02)..... BF1346 +	Fuel/Water Separator Ele. (Davco 382 System) (Fleetguard FS19729)..... PF7755
F-F Lube Spin-on (11-3871)..... B129	Fuel/Water Separator Ele. (Davco 382 System) (Fleetguard FS19729)..... PF7755	Fuel/Water Separator Spin-on (w/SP) (Alliance ABP-S3226FL02)..... BF1346-SP +
B-P Lube Ele. (11-2685)..... P52	Fuel/Water Separator Spin-on (w/SP) (Alliance ABP-S3226FL02)..... BF1346-SP +	Fuel/Water Separator Spin-on (Racor R50418)..... BF9898-O
B-P Lube Spin-on (11-3746)..... B128	Fuel/Water Separator Spin-on (Racor R50418)..... BF9898-O	Fuel (1R0751)..... BF7632
P. Fuel Ele. (11-2230)..... PF916	Fuel (1R0751)..... BF7632	Disposable Air Hsg. (61100179) PA3891
P. Fuel Spin-on (11-3692)..... BF991	Disposable Air Hsg. (61100179) PA3891	Air (End Inlet) (Farr 114500-003) PA3556
P. Fuel Spin-on (11-3854)..... BF979 +	Air (End Inlet) (Farr 114500-003) PA3556	Channel Flow Air (Don. P607955)..... CA4700 +
S. Fuel Ele. (11-3068)..... PF902	Channel Flow Air (Don. P607955)..... CA4700 +	Channel Flow Air (w/Flame Retardant Media) (Don. P607960) CA5420 +
S. Fuel Spin-on (11-3693)..... BF992	Channel Flow Air (w/Flame Retardant Media) (Don. P607960) CA5420 +	Air (Side Inlet) (Farr 114880-003) PA3493
S. Fuel Spin-on (11-3855)..... BF888	Air (Side Inlet) (Farr 114880-003) PA3493	Channel Flow Secondary Air (Don. P544432)..... PA4701
XDS w/Yanmar TK395 Eng. (New Zealand)	Channel Flow Secondary Air (Don. P544432)..... PA4701	Cab Air (Main AirCond. Unit) (VCC36000006)..... PA5359
Lube (Extended Maintenance Interval) (11-9321)..... B7025	Cab Air (Main AirCond. Unit) (VCC36000006)..... PA5359	Air Dryer (AD-9 System) (Bendix 107796)..... BA5377
F-F Lube (11-6182)..... B161-S	Air Dryer (AD-9 System) (Bendix 107796)..... BA5377	Air Dryer (AD-IP System) (Bendix 65624)..... BA5373
Fuel (11-9341)..... BF992	Air Dryer (AD-IP System) (Bendix 65624)..... BA5373	Trans. Pan-Type (1000, 2000 Series S. Pan w/o Gskt.) (Allison 29537965)..... 20004
Radial Seal Air (11-9059)..... RS3715	Trans. Pan-Type (1000, 2000 Series S. Pan w/o Gskt.) (Allison 29537965)..... 20004	Trans. Pan-Type (1000, 2000 Series S. Pan w/Gskt.) (Allison 29537965)..... 20016
XDS w/Yanmar TK395 Eng. (North America)	Trans. Pan-Type (1000, 2000 Series S. Pan w/Gskt.) (Allison 29537965)..... 20016	Trans. Pan-Type (1000, 2000 Series D. Pan w/o Gskt.) (Allison 29537966)..... 20003
F-F Lube (116182)..... B161-S	Trans. Pan-Type (1000, 2000 Series D. Pan w/o Gskt.) (Allison 29537966)..... 20003	Trans. Pan-Type (1000, 2000 Series D. Pan w/Gskt.) (Allison 29537966)..... 20017
B-P Lube (116228)..... B7025	Trans. Pan-Type (1000, 2000 Series D. Pan w/Gskt.) (Allison 29537966)..... 20017	Trans. Spin-on (1000, 2000 Series) (Allison 29539579)..... BT8460
P. Fuel (119098)..... BF992	Trans. Spin-on (1000, 2000 Series) (Allison 29539579)..... BT8460	Trans. Ele. (3000 & 4000 Series, 2 In Kit) (Allison 29540493)..... PT9416-MPG KIT
Air (117234)..... PA3840	Trans. Ele. (3000 & 4000 Series, 2 In Kit) (Allison 29540493)..... PT9416-MPG KIT	Trans. Ele. (3000 & 4000 Series, 4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT
XDS SR	Trans. Ele. (3000 & 4000 Series, 4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Trans. Pan-Type (AT Series, 3.8 In. Pan) (Allison 29540976)..... 19992 +
Lube (11-6182)..... B161-S	Trans. Pan-Type (AT Series, 3.8 In. Pan) (Allison 29540976)..... 19992 +	Trans. Pan-Type (AT & MT Series, 5.3 In. Pan) (Allison 29538489)..... 19739 +
Fuel (11-9098)..... BF992	Trans. Pan-Type (AT & MT Series, 5.3 In. Pan) (Allison 29538489)..... 19739 +	Trans. Spin-on (AT & MT Series) (Allison 29510922)..... BT8316-MPG
Radial Seal Air (11-9059)..... RS3715	Trans. Spin-on (AT & MT Series) (Allison 29510922)..... BT8316-MPG	Trans. Spin-on (Fuller 4304827)..... BT223
XMD Series	Trans. Spin-on (Fuller 4304827)..... BT223	Opt. Trans. Spin-on (Fuller 17237)..... B2 +
F-F Lube (11-4565)..... B975	Opt. Trans. Spin-on (Fuller 17237)..... B2 +	Steering (VMLT1808D)..... BT9388
F-F Lube (11-4948)..... B243	THOMAS Buses	
P. Fuel (11-3692)..... BF991	Models w/Farr Air Cleaners	
S. Fuel (11-3693)..... BF992	Air (119862-001)..... PA3891	
XNWD w/Mercedes-Benz C201, OM636 Eng.	Air (119862-003)..... PA3987	
F-F Lube Ele. (11-2093)..... PT82-HD +		
F-F Lube Spin-on (11-3712)..... BT365		
F-F Lube Spin-on (11-3871)..... B129		
B-P Lube Ele. (11-2685)..... P52		
B-P Lube Spin-on (11-3746)..... B128		
P. Fuel Ele. (11-2230)..... PF916		
P. Fuel Spin-on (11-3692)..... BF991		
P. Fuel Spin-on (11-3854)..... BF979 +		
S. Fuel Ele. (11-3068)..... PF902		
S. Fuel Spin-on (11-3693)..... BF992		
S. Fuel Spin-on (11-3855)..... BF888		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

THOMAS Buses (cont'd)	THOMAS Buses (cont'd)	THOMAS Buses (cont'd)
Saf-T Liner w/Cat 3126 Eng. (To 1/2004)	Saf-T Liner w/Cat 3126 Eng. (1/2004-on)	Saf-T Liner w/Cat 3126B Eng. (To 1/2004)
<b>Lube</b> (Standard Vers.) (1R0739).. <b>B76 +</b>	(Cont'd)	(Cont'd)
<b>Lube</b> (Severe Service) (1R0739).. <b>B76-SS +</b>	<b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960) <b>CA5420 +</b>	<b>Trans. Pan-Type</b> (1000, 2000 Series S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Fuel/Water Separator Ele.</b> (Davco 382 System) (Fleetguard FS19729)..... <b>PF7755</b>	<b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b>	<b>Trans. Pan-Type</b> (1000, 2000 Series D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Fuel</b> (1R0751)..... <b>BF7632</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Trans. Pan-Type</b> (1000, 2000 Series D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
<b>Disposable Air Hsg.</b> (61100179). <b>PA3891</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Trans. Spin-on</b> (1000, 2000 Series) (Allison 29539579)..... <b>BT8460</b>
<b>Channel Flow Air</b> (Don. P607955)..... <b>CA4700 +</b>	<b>Trans. Pan-Type</b> (1000, 2000 Series S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Trans. Ele.</b> (3000 & 4000 Series, 2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960) <b>CA5420 +</b>	<b>Trans. Pan-Type</b> (1000, 2000 Series S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Trans. Ele.</b> (3000 & 4000 Series, 4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b>	<b>Trans. Pan-Type</b> (1000, 2000 Series D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Trans. Pan-Type</b> (AT Series, 3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b>
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Trans. Pan-Type</b> (1000, 2000 Series D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Trans. Pan-Type</b> (AT & MT Series, 5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>
<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Trans. Spin-on</b> (1000, 2000 Series) (Allison 29539579)..... <b>BT8460</b>	<b>Trans. Spin-on</b> (AT & MT Series) (Allison 29510922)..... <b>BT8316-MPG</b>
<b>Trans. Pan-Type</b> (1000, 2000 Series S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Trans. Ele.</b> (3000 & 4000 Series, 2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>
<b>Trans. Pan-Type</b> (1000, 2000 Series S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Trans. Ele.</b> (3000 & 4000 Series, 4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
<b>Trans. Pan-Type</b> (1000, 2000 Series D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Trans. Pan-Type</b> (AT Series, 3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b>	
<b>Trans. Pan-Type</b> (1000, 2000 Series S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Trans. Pan-Type</b> (AT & MT Series, 5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>	
<b>Trans. Pan-Type</b> (1000, 2000 Series D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Trans. Spin-on</b> (AT & MT Series) (Allison 29510922)..... <b>BT8316-MPG</b>	
<b>Trans. Pan-Type</b> (1000, 2000 Series D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	
<b>Trans. Spin-on</b> (1000, 2000 Series) (Allison 29539579)..... <b>BT8460</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	
<b>Trans. Ele.</b> (3000 & 4000 Series, 2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>		
<b>Trans. Ele.</b> (3000 & 4000 Series, 4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>		
<b>Trans. Pan-Type</b> (AT Series, 3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b>		
<b>Trans. Pan-Type</b> (AT & MT Series, 5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>		
<b>Trans. Spin-on</b> (AT & MT Series) (Allison 29510922)..... <b>BT8316-MPG</b>		
<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>		
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>		
Saf-T Liner w/Cat 3126 Eng. (1/2004-on)	Saf-T Liner w/Cat 3126B Eng. (To 1/2004)	Saf-T Liner w/Cat 3126B Eng. (1/2004-on)
<b>Lube</b> (To 1/2004 (Std. Version)) (1R0739)..... <b>B76 +</b>	<b>Lube</b> (Standard Vers.) (1R0739).. <b>B76 +</b>	<b>Lube</b> (1R1807)..... <b>B7700 +</b>
<b>Lube</b> (1/2004-on) (1R1807)..... <b>B7700 +</b>	<b>Lube</b> (Severe Service) (1R0739).. <b>B76-SS +</b>	<b>Fuel/Water Separator Ele.</b> (Davco 382 System) (Fleetguard FS19729)..... <b>PF7755</b>
<b>Lube</b> (To 1/2004 (Severe Service)) (1R0739)..... <b>B76-SS +</b>	<b>Fuel/Water Separator Ele.</b> (Davco 382 System) (Fleetguard FS19729)..... <b>PF7755</b>	<b>Fuel</b> (1R0751)..... <b>BF7632</b>
<b>Fuel/Water Separator Ele.</b> (Davco 382 System) (Fleetguard FS19729)..... <b>PF7755</b>	<b>Fuel</b> (1R0751)..... <b>BF7632</b>	<b>Disposable Air Hsg.</b> (61100179). <b>PA3891</b>
<b>Fuel</b> (1R0751)..... <b>BF7632</b>	<b>Disposable Air Hsg.</b> (61100179). <b>PA3891</b>	<b>Channel Flow Air</b> (Don. P607955)..... <b>CA4700 +</b>
<b>Disposable Air Hsg.</b> (61100179). <b>PA3891</b>	<b>Channel Flow Air</b> (Don. P607955)..... <b>CA4700 +</b>	<b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960) <b>CA5420 +</b>
<b>Channel Flow Air</b> (Don. P607955)..... <b>CA4700 +</b>	<b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960) <b>CA5420 +</b>	<b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b>
	<b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>
	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Trans. Pan-Type</b> (1000, 2000 Series S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
	<b>Trans. Pan-Type</b> (1000, 2000 Series S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Trans. Pan-Type</b> (1000, 2000 Series S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
		<b>Trans. Pan-Type</b> (1000, 2000 Series D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
		<b>Trans. Pan-Type</b> (1000, 2000 Series D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
		<b>Trans. Spin-on</b> (1000, 2000 Series) (Allison 29539579)..... <b>BT8460</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>THOMAS Buses (cont'd)</b>	<b>THOMAS Buses (cont'd)</b>	<b>THOMAS Buses (cont'd)</b>
Saf-T-Liner w/Cat 3126B Eng. (1/2004-on) (Cont'd)	Saf-T-Liner w/Cummins ISB Eng. (Cont'd)	Saf-T-Liner w/Cummins ISB6.7 (6.7L) Eng. (2020) (Cont'd)
<b>Trans. Ele.</b> (3000 & 4000 Series, 2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Trans. Ele.</b> (3000 & 4000 Series, 2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Trans. Ele.</b> (3000 & 4000 Series, 4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Trans. Ele.</b> (3000 & 4000 Series, 4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Trans. Pan-Type</b> (AT Series, 3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b>	<b>Trans. Pan-Type</b> (AT Series 3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Trans. Pan-Type</b> (AT & MT Series, 5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>	<b>Trans. Pan-Type</b> (AT & MT Series, 5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
<b>Trans. Spin-on</b> (AT & MT Series) (Allison 29510922)..... <b>BT8316-MPG</b>	<b>Trans. Spin-on</b> (AT & MT Series) (Allison 29510922)..... <b>BT8316-MPG</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>Trans. Spin-on</b> (Fuller 4304827)..... <b>BT223</b>	<b>Trans. Spin-on</b> (Fuller 4304827)..... <b>BT223</b>	Saf-T-Liner w/Cummins ISB 6.7 (6.7L) Eng. (2021)
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Lube</b> (3937736)..... <b>B7177</b>
Saf-T-Liner w/Cummins ISB Eng.	Saf-T-Liner w/Cummins ISB6.7 (6.7L) Eng. (2018)	<b>Fuel</b> (5303743)..... <b>BF63000</b>
<b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b>	<b>Lube</b> (3937736)..... <b>B7177</b>	<b>Crankcase Breather</b> (4936636)..... <b>CV15010</b>
<b>Fuel/Water Separator Spin-on</b> (w/Drain) (Racor R50419)..... <b>BF1347</b>	<b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b>	Saf-T-Liner w/Cummins ISB 6.7 (6.7L) Eng. (2022)
<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Racor R50419)..... <b>BF1347-O</b>	<b>Primary Channel Flow Air</b> (Don. P617499)..... <b>CA5514</b>	<b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b>
<b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (Racor R50419)..... <b>BF1373-SP</b>	<b>Secondary Channel Flow Air</b> (Don. P601560)..... <b>PA5515</b>	Saf-T-Liner w/Cummins ISC 8.3 (8.3L) Eng. (2003-17)
<b>Fuel/Water Separator Spin-on</b> (Fleetguard FS1065)..... <b>BF1378-SPS</b>	<b>Crankcase Breather</b> (4936636)..... <b>CV15010</b>	<b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b>
<b>Fuel</b> (2007-on) (Fleetguard FF5632)..... <b>BF7940</b>	Saf-T-Liner w/Cummins ISB6.7 (6.7L) Eng. (2019)	<b>Fuel</b> (Fleetguard FF5636)..... <b>BF7924</b>
<b>Disposable Air Hsg.</b> (61100179)..... <b>PA3891</b>	<b>Lube</b> (3937736)..... <b>B7177</b>	<b>Disposable Air Hsg.</b> (61100179)..... <b>PA3891</b>
<b>Channel Flow Air</b> (Don. P607955)..... <b>CA4700 +</b>	<b>Fuel</b> (5303743)..... <b>BF63000</b>	<b>Channel Flow Air</b> (Don. P607955)..... <b>CA4700 +</b>
<b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960)..... <b>CA5420 +</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960)..... <b>CA5420 +</b>
<b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b>
<b>Cab Air</b> (Main AirCond. Unit) (VCC36000006)..... <b>PA5359</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>
<b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Trans. Pan-Type</b> (1000, 2000 Series S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Crankcase Breather</b> (2007-on) (Fleetguard CV52001)..... <b>CV15010</b>	<b>Crankcase Breather</b> (4936636)..... <b>CV15010</b>	<b>Trans. Pan-Type</b> (1000, 2000 Series S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Trans. Pan-Type</b> (1000, 2000 Series S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	Saf-T-Liner w/Cummins ISB6.7 (6.7L) Eng. (2020)	<b>Trans. Pan-Type</b> (1000, 2000 Series D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Trans. Pan-Type</b> (1000, 2000 Series S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Lube</b> (3937736)..... <b>B7177</b>	<b>Trans. Pan-Type</b> (1000, 2000 Series D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>
<b>Trans. Pan-Type</b> (1000, 2000 Series D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Fuel/Water Separator</b> (w/Sensor Port) (Racor S3226T)..... <b>BF1373-SP</b>	<b>Trans. Spin-on</b> (1000, 2000 Series) (Allison 29539579)..... <b>BT8460</b>
<b>Trans. Pan-Type</b> (1000, 2000 Series D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor S3226T)..... <b>BF1347-O</b>	<b>Trans. Ele.</b> (3000 & 4000 Series, 2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Trans. Spin-on</b> (1000, 2000 Series) (Allison 29539579)..... <b>BT8460</b>	<b>Fuel/Water Separator</b> (w/Drain) (Racor S3226T)..... <b>BF1347</b>	<b>Trans. Ele.</b> (3000 & 4000 Series, 4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>
	<b>Fuel</b> (5303743)..... <b>BF63000</b>	<b>Trans. Pan-Type</b> (AT Series, 3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b>
	<b>Channel Flow Air</b> (Don. P607955)..... <b>CA4700</b>	<b>Trans. Pan-Type</b> (AT & MT 5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>
	<b>Air</b> (61100179)..... <b>PA3891</b>	
	<b>Crankcase Breather</b> (4936636)..... <b>CV15010</b>	
	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	
	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

THOMAS Buses (cont'd)	THOMAS Buses (cont'd)	THOMAS Buses (cont'd)
Saf-T-Liner w/Cummins ISC 8.3 (8.3L) Eng. (2003-17) (Cont'd) <b>Trans. Spin-on</b> (AT & MT Series) (Allison 29510922)..... <b>BT8316-MPG</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b>	Saf-T-Liner w/Cummins ISL-G (8.9L) Eng. (2018) (Cont'd) <b>Channel Flow Secondary Air</b> (Don. P601560)..... <b>PA5515</b>	Saf-T-Liner w/John Deere 6081 (8.1L) CNG Eng. (Cont'd) <b>Trans. Ele.</b> (3000 & 4000 Series, 4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Pan-Type</b> (AT Series, 3.8 In. Pan) (Allison 29540976)..... <b>19992+</b> <b>Trans. Pan-Type</b> (AT & MT Series, 5.3 In. Pan) (Allison 29538489)..... <b>19739+</b> <b>Trans. Spin-on</b> (AT & MT Series) (Allison 29510922)..... <b>BT8316-MPG</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b>
Saf-T-Liner w/Cummins ISL 8.9 (8.9L) Eng. (2018) <b>Lube</b> (Fleetguard LF9009)..... <b>B40142</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> <b>Channel Flow Primary Air</b> (Don. P617499)..... <b>CA5514</b> <b>Channel Flow Secondary Air</b> (Don. P601560)..... <b>PA5515</b>	Saf-T-Liner w/Cummins ISL-G (8.9L) Eng. (2019) <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309</b> <b>Fuel/Water Separator</b> (Fleetguard NG5900)..... <b>BF7695</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b>	Saf-T-Liner w/Mercedes-Benz MBE900 Eng. <b>F-F Lube</b> (A0001801709)..... <b>P7188</b> <b>Opt. B-P Lube</b> (A9061810086).... <b>BC7326+</b> <b>Fuel/Water Separator Ele.</b> (Davco 382 System) (Fleetguard FS19624)..... <b>PF7748</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Racor R50418)..... <b>BF9898-O</b> <b>4 1/16 In. Fuel</b> (A0000901551)..... <b>PF7735</b> <b>7 31/32 In. Fuel</b> (A5410920805).... <b>PF7761</b> <b>Disposable Air Hsg.</b> (61100179).... <b>PA3891</b> <b>Channel Flow Air</b> (Don. P607955)..... <b>CA4700+</b> <b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960) <b>CA5420+</b> <b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b> <b>Cab Air</b> (36000006)..... <b>PA5359</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b> <b>Trans. Pan-Type</b> (1000, 2000 Series S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (1000, 2000 Series S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Spin-on</b> (1000, 2000 Series) (Allison 29539579)..... <b>BT8460</b> <b>Trans. Ele.</b> (3000 & 4000 Series, 2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (3000 & 4000 Series, 4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Pan-Type</b> (AT Series, 3.8 In. Pan) (Allison 29540976)..... <b>19992+</b> <b>Trans. Pan-Type</b> (AT & MT I Series 5.3 In. Pan) (Allison 29538489)..... <b>19739</b>
Saf-T-Liner w/Cummins ISL 8.9 (8.9L) Eng. (2019) <b>Lube</b> (3401544)..... <b>B40142</b> <b>Fuel</b> (5303743)..... <b>BF63000</b>	Saf-T-Liner w/Cummins ISL-G (8.9L) Eng. (2020) <b>Lube</b> (Fleetguard LF9009)..... <b>B40142</b> <b>Fuel</b> (Fleetguard NG5900)..... <b>BF7695</b>	
Saf-T-Liner w/Cummins ISL 8.9 (8.9L) Eng. (2020) <b>Lube</b> (5444774)..... <b>B40142</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Channel Flow Air</b> (Don. P607955)..... <b>CA4700</b> <b>Air</b> (61100179)..... <b>PA3891</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	Saf-T-Liner w/Cummins ISL-G (8.9L) Eng. (2022) <b>Lube</b> (5444774)..... <b>B40142</b> <b>Fuel</b> (3607140)..... <b>BF7695</b>	
Saf-T-Liner w/Cummins ISL 8.9 (8.9L) Eng. (2021) <b>Lube</b> (5444774)..... <b>B40142</b>	Saf-T-Liner w/Cummins ISL-G (8.9L) Eng. (2023) <b>Lube</b> (5444774)..... <b>B40142</b> <b>Fuel</b> (3607140)..... <b>BF7695</b>	
Saf-T-Liner w/Cummins ISL 8.9 (8.9L) Eng. (2022) <b>Lube</b> (5444774)..... <b>B40142</b> <b>Fuel</b> (5660774)..... <b>BF63000</b>	Saf-T-Liner w/John Deere 6081 (8.1L) CNG Eng. <b>Lube Ele.</b> (RE509672)..... <b>P7233</b> <b>Lube Spin-on</b> (RE57394)..... <b>BT486</b> <b>Disposable Air Hsg.</b> (61100179).... <b>PA3891</b> <b>Channel Flow Air</b> (Don. P607955)..... <b>CA4700+</b> <b>Channel Flow Air</b> (w/Flame Retardant Media) (Don. P607960) <b>CA5420+</b> <b>Channel Flow Secondary Air</b> (Don. P544432)..... <b>PA4701</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (AD-IP System) (Bendix 65624)..... <b>BA5373</b> <b>Trans. Pan-Type</b> (1000, 2000 Series S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (1000, 2000 Series S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (1000, 2000 Series D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (1000, 2000 Series D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (1000, 2000 Series) (Allison 29539579)..... <b>BT8460</b> <b>Trans. Ele.</b> (3000 & 4000 Series, 2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	
Saf-T-Liner w/Cummins ISL-G (8.9L) Eng. (2018) <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309+</b> <b>Fuel/Water Separator</b> (Fleetguard NG5900)..... <b>BF7695</b> <b>Channel Flow Primary Air</b> (Don. P617499)..... <b>CA5514</b>		

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

THOMAS Buses (cont'd)	THOMAS Buses (cont'd)	THOMAS Buses (cont'd)
Saf-T-Liner w/Mercedes-Benz MBE900 Eng. (Cont'd) <b>Trans. Spin-on</b> (AT & MT Series) (Allison 29510922)..... <b>BT8316-MPG</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 *</b> <b>Steering</b> (T1808D)..... <b>BT9388</b>	Transit Liner w/Cummins ISL 8.9 (8.9L) Eng. (2018) <b>Lube</b> (Fleetguard LF9009)..... <b>B40142</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b>	Vista School Bus w/Cummins ISB 6.7 (6.7L) Eng. (Cont'd) <b>Fuel/Water Separator Ele.</b> (4947561)..... <b>PF9870</b> <b>Fuel/Water Separator Spin-on</b> (4934879)..... <b>BF1378-SPS</b> <b>Fuel</b> (Fleetguard FF5632)..... <b>BF7940</b> <b>Fuel</b> (3978040)..... <b>BF7966</b>
Transit Liner w/Cummins ISB6.7 (6.7L) Eng. (2018) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	Transit Liner w/Cummins ISL 8.9 (8.9L) Eng. (2019) <b>Lube</b> (3401544)..... <b>B40142</b> <b>Fuel</b> (5303743)..... <b>BF63000</b>	<b>Trans. Ele. (2 In. Kit)</b> (Allison 29545776)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele. (4 In. Kit)</b> (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
Transit Liner w/Cummins ISB6.7 (6.7L) Eng. (2019) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	Transit Liner w/Cummins ISL 8.9 (8.9L) Eng. (2020) <b>Lube</b> (5444774)..... <b>B40142</b> <b>Fuel</b> (5303743)..... <b>BF63000</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
Transit Liner w/Cummins ISB6.7 (6.7L) Eng. (2020) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (Racor S3226T)..... <b>BF1373-SP</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (Racor S3226T)..... <b>BF1347-O</b> <b>Fuel/Water Separator</b> (w/Drain) (Racor S3226T)..... <b>BF1347</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Channel Flow Air</b> (Don. P607955)..... <b>CA4700</b> <b>Air</b> (61100179)..... <b>PA3891</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b> <b>Trans. Ele. (2 In. Kit)</b> (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele. (4 In. Kit)</b> (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	Transit Liner w/Cummins ISL-G (8.9L) Eng. (2020) <b>Lube</b> (Fleetguard LF9009)..... <b>B40142</b> <b>Fuel</b> (Fleetguard NG5900)..... <b>BF7695</b>	Vista w/IHC DT360 Eng. <b>Lube</b> (1808896-C1)..... <b>B299 +</b> <b>Lube</b> (1811953-C1)..... <b>B309</b> <b>Fuel/Water Separator</b> (1808623-C1)..... <b>BF7584 +</b> <b>Fuel</b> (1809789-C1)..... <b>BF7629 +</b> <b>Std. O. Air</b> (482647-C91)..... <b>PA2521</b> <b>Opt. Std. I. Air</b> (482647-C91)..... <b>PA2522</b> <b>Radial Seal Air</b> (1691027-C1)..... <b>RS2863 +</b> <b>Radial Seal XP Air</b> (1691027-C1)..... <b>RS2863XP +</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b> <b>Steering</b> (Fleetguard HF6162)..... <b>P106-HD</b>
Transit Liner w/Cummins ISB6.7 (6.7L) Eng. (2021) <b>Lube</b> (3937736)..... <b>B7177</b> <b>Fuel</b> (5303743)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	Vista School Bus w/Cat 3126 (7.2L) Eng. <b>Lube</b> (1R1807)..... <b>B7700 +</b> <b>Fuel/Water Separator</b> (1752949)..... <b>BF1268</b> <b>Fuel/Water Separator</b> (2568753)..... <b>BF1259</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (1986378)..... <b>BF7798-SP</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (1986378)..... <b>BF7798-O</b> <b>Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (1R0751)..... <b>BF7632</b>	Vista w/IHC DT408 Eng. <b>Lube</b> (1819452-C1)..... <b>B7030</b> <b>Fuel</b> (1822588-C1)..... <b>BF7629 +</b> <b>Std. O. Air</b> (482647C-91)..... <b>PA2521</b> <b>Opt. Std. I. Air</b> (482647C-91)..... <b>PA2522</b> <b>Radial Seal Air</b> (1691027-C1)..... <b>RS2863 +</b> <b>Radial Seal XP Air</b> (1691027-C1)..... <b>RS2863XP +</b> <b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b> <b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b> <b>Steering</b> (Fleetguard HF6162)..... <b>P106-HD</b>
Transit Liner w/Cummins ISB6.7 (6.7L) Eng. (2022) <b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b>	Vista School Bus w/Cat C7 (7.2L) Eng. <b>F-F Lube</b> (1R1808)..... <b>B7299 +</b> <b>F-F Lube</b> (1R1807)..... <b>B7700 +</b> <b>Fuel/Water Separator</b> (2568753)..... <b>BF1259</b> <b>Fuel/Water Separator</b> (1752949)..... <b>BF1268</b> <b>Fuel</b> (1R0751)..... <b>BF7632</b>	
	Vista School Bus w/Cummins ISB (5.9L) Eng. <b>Lube</b> (3937736)..... <b>B7177</b> <b>Lube</b> (4897898)..... <b>BT7237</b> <b>Fuel/Water Separator Ele.</b> (3942470)..... <b>PF7777</b> <b>Fuel/Water Separator Spin-on</b> (3942533)..... <b>BF1271</b> <b>Fuel/Water Separator Spin-on</b> (3406889)..... <b>BF1293-SPS</b> <b>Fuel/Water Separator Spin-on</b> (4934879)..... <b>BF1378-SPS</b> <b>Fuel</b> (Fleetguard FF5632)..... <b>BF7940</b>	
	Vista School Bus w/Cummins ISB 6.7 (6.7L) Eng. <b>Lube</b> (3937736)..... <b>B7177</b> <b>Lube</b> (Fleetguard LF3972)..... <b>BT7349</b>	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).




<b>THOMAS Buses (cont'd)</b>	<b>TIFFIN Buses &amp; Motorhomes (cont'd)</b>	<b>TIFFIN Buses &amp; Motorhomes (cont'd)</b>
Vista w/IHC T444E (7.3L) Eng. <b>Lube</b> (1814562-C1)..... <b>B7039</b>	Allegro Bay w/Cummins ISB 6.7 (6.7L) Eng. (2019) (Cont'd) <b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	Allegro Bus w/Cummins ISL 8.9 (8.9L) Eng. (2021) <b>Lube</b> (5444774)..... <b>B40142</b>
<b>Fuel/Water Separator</b> (To 1995 (w/o SP)) (1813104-C91)..... <b>BF1222 +</b>	Allegro Bay w/Cummins ISB 6.7 (6.7L) Eng. (2020) <b>Lube</b> (3937736)..... <b>B7177</b>	Allegro Bus w/Cummins ISL 8.9 (8.9L) Eng. (2022) <b>Lube</b> (5444774)..... <b>B40142</b>
<b>Fuel/Water Separator</b> (To 1995 (w/SP)) (1813104-C91)..... <b>BF1222-SP +</b>	<b>Fuel</b> (5303743)..... <b>BF63000</b>	<b>Fuel</b> (5660774)..... <b>BF63000</b>
<b>Fuel/Water Separator</b> (To 1995), (Open End for Bowl)..... <b>BF1222-O +</b>	<b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	Allegro Bus w/Cummins ISX 15.0 (14.9L) Eng. (2018) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b>
<b>Fuel Ele.</b> (1996-on) (1822631-C91)..... <b>PF7678</b>	Allegro Bay w/Cummins ISB 6.7 (6.7L) Eng. (2021) <b>Lube</b> (3937736)..... <b>B7177</b>	<b>Fuel</b> (Fleetguard FF5825NN)..... <b>BF46129</b>
<b>Std. O. Air</b> (482647C-91)..... <b>PA2521</b>	<b>Fuel</b> (5303743)..... <b>BF63000</b>	Allegro Bus w/Cummins ISX 15.0 (14.9L) Eng. (2019) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b>
<b>Opt. Std. I. Air</b> (482647C-91)..... <b>PA2522</b>	<b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	<b>Fuel</b> (5365988)..... <b>BF46129</b>
<b>Radial Seal Air</b> (1691027-C1)..... <b>RS2863 +</b>	Allegro Breeze w/IHC MaxxFORCE 7 Eng. <b>Lube</b> (2013) (1899332-C91)..... <b>B7506</b>	Allegro Bus w/Cummins ISX 15.0 (14.9L) Eng. (2020) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b>
<b>Radial Seal XP Air</b> (1691027-C1)..... <b>RS2863XP +</b>	<b>Fuel</b> (2011-12) (1876533-C93)..... <b>BF9858 KIT</b>	<b>Fuel</b> (5365988)..... <b>BF46129</b>
<b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b>	<b>Fuel</b> (2013) (1884207-C92)..... <b>PF9914 KIT</b>	Allegro Bus w/Cummins ISX 15.0 (14.9L) Eng. (2021) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b>
<b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>	<b>Air</b> (2011-12) (Parker/Racor 94973004)..... <b>PA3891</b>	<b>Fuel</b> (5365988)..... <b>BF46129</b>
<b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b>	<b>Air</b> (2013) (Parker/Racor 114880005)..... <b>PA4655</b>	Allegro Bus w/Cummins ISX 15.0 (14.9L) Eng. (2022) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b>
<b>Steering</b> (Fleetguard HF6162)..... <b>P106-HD</b>	<b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b>	<b>Fuel</b> (5365988)..... <b>BF46129</b>
Vista w/IHC DT466 Eng. <b>Lube</b> (To 1994) (1808896-C1)..... <b>B299 +</b>	<b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b>	Allegro Bus w/Cummins ISX 15.0 (14.9L) Eng. (2021) <b>Lube</b> (5575298)..... <b>B40145</b>
<b>Lube</b> (To 1994) (1811953-C1)..... <b>B309</b>	<b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Fuel</b> (5365988)..... <b>BF46129</b>
<b>Lube</b> (1994-on) (1833121-C1)..... <b>B7030</b>	<b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	Allegro Bus w/Cummins ISX 15.0 (14.9L) Eng. (2022) <b>Lube</b> (5575298)..... <b>B40145</b>
<b>Fuel</b> (674293-C91)..... <b>BF588</b>	<b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Fuel</b> (5575143)..... <b>BF46248</b>
<b>Std. O. Air</b> (482647-C91)..... <b>PA2521</b>	Allegro Bus w/Cummins ISL Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b>	Breeze w/Cummins ISB 6.7 (6.7L) Eng. (2019) <b>Lube</b> (3937736)..... <b>B7177</b>
<b>Opt. Std. I. Air</b> (482647-C91)..... <b>PA2522</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1003)..... <b>BF1293-SPS</b>	<b>Fuel</b> (5303743)..... <b>BF63000</b>
<b>Radial Seal Air</b> (1691027-C1)..... <b>RS2863 +</b>	<b>Fuel</b> (Fleetguard FF5636)..... <b>BF7924</b>	<b>Crankcase Breather</b> (4936636)... <b>CV15010</b>
<b>Radial Seal XP Air</b> (1691027-C1)..... <b>RS2863XP +</b>	<b>Air</b> (Parker/Racor 94973007)..... <b>PA30073</b>	Breeze w/Cummins ISB 6.7 (6.7L) Eng. (2021) <b>Lube</b> (3937736)..... <b>B7177</b>
<b>Coolant</b> (w/o Chemical) (1820358-C1)..... <b>B5134 +</b>	<b>Trans.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	<b>Fuel</b> (5303743)..... <b>BF63000</b>
<b>Coolant</b> (w/Chemical) (1822313-C1)..... <b>BW5082</b>	<b>Trans.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	<b>Crankcase Breather</b> (4936636)... <b>CV15010</b>
<b>Trans. Pan-Type</b> (3.8 In. Pan) (Allison 29540976)..... <b>19992 +</b>	Allegro Bus w/Cummins ISL 8.9 (8.9L) Eng. (2018) <b>Lube</b> (Fleetguard LF9009)..... <b>B40142</b>	Breeze w/Cummins ISB 6.7 (6.7L) Eng. (2020) <b>Lube</b> (3937736)..... <b>B7177</b>
<b>Trans. Pan-Type</b> (5.3 In. Pan) (Allison 29538489)..... <b>19739 +</b>	<b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b>	<b>Fuel</b> (5303743)..... <b>BF63000</b>
<b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b>	<b>Air</b> (Parker/Racor 94973007)..... <b>PA30073</b>	<b>Crankcase Breather</b> (4936636)... <b>CV15010</b>
<b>Steering</b> (Fleetguard HF6162)..... <b>P106-HD</b>	<b>Trans.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	Breeze w/Cummins ISB 6.7 (6.7L) Eng. (2022) <b>Lube</b> (Fleetguard LF3970)..... <b>B7177</b>
<b>THORNYCROFT Trucks</b>	Allegro Bus w/Cummins ISL 8.9 (8.9L) Eng. (2019) <b>Lube</b> (3401544)..... <b>B40142</b>	Breeze w/Cummins ISV5.0 (5.0L) Eng. (2018) <b>Lube</b> (4378318)..... <b>B7420</b>
CR6, JR6, NR6, QR6, RTR6 Engs. <b>F-F Lube</b> ..... <b>P198</b>	<b>Fuel</b> (5303743)..... <b>BF63000</b>	Phaeton w/Cummins ISL Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b>
<b>B-P Lube</b> ..... <b>P42</b>	Allegro Bus w/Cummins ISL 8.9 (8.9L) Eng. (2020) <b>Lube</b> (5444774)..... <b>B40142</b>	<b>Fuel/Water Separator</b> (Fleetguard FS1003)..... <b>BF1293-SPS</b>
<b>Opt. Fuel Ele.</b> ..... <b>PF838</b>	<b>Fuel</b> (5303743)..... <b>BF63000</b>	<b>Fuel</b> (Fleetguard FF5636)..... <b>BF7924</b>
Road Transport <b>Lube</b> ..... <b>P177</b>	Allegro Bus w/Cummins ISL 8.9 (8.9L) Eng. (2021) <b>Lube</b> (3401544)..... <b>B40142</b>	<b>Air</b> (Parker/Racor 94973007)..... <b>PA30073</b>
<b>Opt. Fuel Ele.</b> ..... <b>PF838</b>	<b>Fuel</b> (5303743)..... <b>BF63000</b>	<b>Trans.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>
<b>TIFFIN Buses &amp; Motorhomes</b>	Allegro Bus w/Cummins ISL 8.9 (8.9L) Eng. (2020) <b>Lube</b> (5444774)..... <b>B40142</b>	<b>Trans.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>
Allegro Bay w/Cummins ISB 6.7 (6.7L) Eng. (2019) <b>Lube</b> (3937736)..... <b>B7177</b>	<b>Fuel</b> (5303743)..... <b>BF63000</b>	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

TIFFIN Buses & Motorhomes (cont'd)	TRANS TECH Buses (cont'd)	TRANS TECH Buses (cont'd)
Phaeton w/Cummins ISL 8.9 (8.9L) Eng. (2018) Lube (Fleetguard LF9009)..... <b>B40142</b> Fuel (Fleetguard FF63009)..... <b>BF63000</b>	4500 w/GM 6.0L Gas Eng. (Cont'd) Trans. (4L60E S. Pan) (24200796)..... <b>18010</b> Trans. (4L60E D. Pan) (24208576)..... <b>18056</b> Trans. (4L80E) (24210956)..... <b>18027</b>	SRW w/Ford 5.4L Gas Eng. Lube (Motorcraft FL820S)..... <b>B329</b> Fuel (Motorcraft FG986B)..... <b>BF7668</b> + Air (Motorcraft FA1634)..... <b>PA4075</b> Trans. (4R100 S. Pan) (Motorcraft FT113)..... <b>18264</b> Trans. (4R100 D. Pan) (Motorcraft FT114)..... <b>18265</b> Trans. (4R70W) (Motorcraft FT105)..... <b>18029</b> Trans. (5R110W, To 11/07) (Motorcraft FT144)..... <b>20005</b> Trans. (5R110W, 11/07-on) (Motorcraft FT180)..... <b>20021</b> Trans. Ele. (5R110W) (Motorcraft FT145)..... <b>P7247</b>
Phaeton w/Cummins ISL 8.9 (8.9L) Eng. (2019) Lube (3401544)..... <b>B40142</b> Fuel (5303743)..... <b>BF63000</b>	5500 w/GM 6.6L Diesel Eng. Lube (ACDelco PF2232)..... <b>B1441</b> Fuel/Water Separator (Upgrade) (ACDelco TP3018)..... <b>BF46062</b> <sup>89</sup>	SRW w/GM 4.8L Gas Eng. Lube (2003-05) (ACDelco PF46).. <b>B31</b> Lube (2006-on)..... <b>B160</b> Fuel (2003-05 (Thd. Both Ends)) (ACDelco GF652)..... <b>BF853</b> Fuel (2003-05 (Thd. One End)) (ACDelco GF578)..... <b>BF1171</b> Fuel (2006-on) (N/S)..... <b>N/S</b> Radial Seal Air (ACDelco A1621C)..... <b>RS4131</b> Trans. (4L60E S. Pan) (24200796)..... <b>18010</b> Trans. (4L60E D. Pan) (24208576)..... <b>18056</b> Trans. (4L80E) (24210956)..... <b>18027</b>
Phaeton w/Cummins ISL 8.9 (8.9L) Eng. (2020) Lube (5444774)..... <b>B40142</b> Fuel (5303743)..... <b>BF63000</b>	Radial Seal Air (ACDelco A2032C)..... <b>RS4859</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Steering (88892858)..... <b>P106-HD</b>	SRW w/GM 6.0L Gas Eng. Lube (2003-06) (ACDelco PF46).. <b>B31</b> Lube (2007-on)..... <b>B160</b> Fuel (2003-05 (Thd. Both Ends)) (ACDelco GF652)..... <b>BF853</b> Fuel (2003-05 (Thd. One End)) (ACDelco GF578)..... <b>BF1171</b> Fuel (2006-on) (N/S)..... <b>N/S</b> Radial Seal Air (ACDelco A1621C)..... <b>RS4131</b> Trans. (4L60E S. Pan) (24200796)..... <b>18010</b> Trans. (4L60E D. Pan) (24208576)..... <b>18056</b> Trans. (4L80E) (24210956)..... <b>18027</b>
Phaeton w/Cummins ISL 8.9 (8.9L) Eng. (2021) Lube (5444774)..... <b>B40142</b>	DRW w/Ford 5.4L Gas Eng. Lube (Motorcraft FL820S)..... <b>B329</b> Fuel (Motorcraft FG986B)..... <b>BF7668</b> + Air (Motorcraft FA1634)..... <b>PA4075</b> Trans. (4R100 S. Pan) (Motorcraft FT113)..... <b>18264</b> Trans. (4R100 D. Pan) (Motorcraft FT114)..... <b>18265</b> Trans. (4R70W) (Motorcraft FT105)..... <b>18029</b> Trans. (5R110W, To 11/07) (Motorcraft FT144)..... <b>20005</b> Trans. (5R110W, 11/07-on) (Motorcraft FT180)..... <b>20021</b> Trans. Ele. (5R110W) (Motorcraft FT145)..... <b>P7247</b>	SRW w/GM 6.6L Diesel Eng. Lube (ACDelco PF2232)..... <b>B1441</b> Fuel/Water Separator (Upgrade) (ACDelco TP3018)..... <b>BF46062</b> <sup>89</sup> Radial Seal Air (ACDelco A2032C)..... <b>RS4859</b> Trans. Pan-Type (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> Trans. Pan-Type (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> Trans. Pan-Type (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> Trans. Spin-on (Allison 29539579)..... <b>BT8460</b> Steering (88892858)..... <b>P106-HD</b>
Phaeton w/Cummins ISL 8.9 (8.9L) Eng. (2022) Lube (5444774)..... <b>B40142</b> Fuel (5660774)..... <b>BF63000</b>		
Zephyr w/Cummins ISX 15.0 (14.9L) Eng. (2018) Dual-Flow Lube (4367100)..... <b>BD50000</b> Fuel (Fleetguard FF5825NN)..... <b>BF46129</b>		
Zephyr w/Cummins ISX 15.0 (14.9L) Eng. (2019) Dual-Flow Lube (4367100)..... <b>BD50000</b> Fuel (5365988)..... <b>BF46129</b>		
Zephyr w/Cummins ISX 15.0 (14.9L) Eng. (2020) Dual-Flow Lube (4367100)..... <b>BD50000</b> Fuel (5365988)..... <b>BF46129</b>		
Zephyr w/Cummins ISX 15.0 (14.9L) Eng. (2021) Lube (5575298)..... <b>B40145</b> Fuel (5365988)..... <b>BF46129</b>		
Zephyr w/Cummins ISX 15.0 (14.9L) Eng. (2022) Lube (5575298)..... <b>B40145</b> Fuel (5575143)..... <b>BF46248</b>		
<b>TOYOTA</b> <b>Trucks, Vans</b>		
Commuter w/2.4L Eng. Air (17801-64030)..... <b>PA4608</b>		
HiAce w/2.2L, 2.4L Eng. Air (17801-64030)..... <b>PA4608</b>		
LiteAce w/1.8L Eng. Air (17801-64030)..... <b>PA4608</b>		
<b>TRANS TECH</b> <b>Buses</b>		
4500 w/GM 6.0L Gas Eng. Lube (2003-06) (ACDelco PF46).. <b>B31</b> Lube (2007-on)..... <b>B160</b> Fuel (2003-05 (Thd. Both Ends)) (ACDelco GF652)..... <b>BF853</b> Fuel (2003-05 (Thd. One End)) (ACDelco GF578)..... <b>BF1171</b> Fuel (2006-on) (N/S)..... <b>N/S</b> Radial Seal Air (ACDelco A1621C)..... <b>RS4131</b>		

+ See Product Guide for Variations of This Number. <sup>89</sup> Inner Fender Liner Removal Recommended for Proper Installation.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>TRANS TECH</b> Buses (cont'd)	<b>TRUCK MATE GENERATORS</b> Auxiliary Power Units (APU) (cont'd)	<b>UNIMOG</b> Trucks (cont'd)
SRW w/GM 6.6L Diesel Eng. (Cont'd)	655-DS w/Yanmar 3TNV Eng. (Cont'd)	Unimog U80 (413)
Trans. Pan-Type (D. Pan w/Gskt.) (Allison 29537966).....	Radial Seal Air (Don. P822686)...	Lube (3141800109).....
20017	RS3715	B-P Lube (1845825).....
Trans. Spin-on (Allison 29539579).....	<b>TWIN COACH</b> Buses	Fuel (3524700092).....
BT8460	Pony Express	Air (10949404).....
Steering (88892858).....	Lube.....	PA3807
P106-HD	P40	Unimog U84 (406), (416)
<b>TRANSIT</b> Buses	<b>UNIMOG</b> Trucks	Lube (11845525).....
Models w/Continental B6427, K6330 Engs.	Unimog Model D	B-P Lube (1845825).....
Lube.....	Fuel.....	Fuel (3524700092).....
P52	PF834	Air (10949404).....
Models w/Zinga Hydraulics	Unimog Model S	Steering (4660604).....
Hyd. (LE3).....	Lube.....	P106-HD
B7011	Unimog U34 (411)	Unimog U90 (416)
<b>TRIDAKO ENERGY SYSTEMS</b> Auxiliary Power Units (APU)	Fuel (3524700092).....	Lube (11845525).....
PowerCube HC6000 w/Kubota Z602 Engine.	F834-F	B-P Lube (1845825).....
Lube (70000-15241).....	Unimog U40, U45, U52 (421) w/OM615, OM616, OM621 Engs.	Fuel (3524700092).....
B179	Lube (6171800009).....	F834-F
Radial Seal Air (Don. P822686)...	B-P Lube (1845825).....	Fuel (3524700092).....
RS3715	Fuel (3524700092).....	Air (10949404).....
<b>TRUCK GEN</b> Auxiliary Power Units (APU)	Air (942804).....	Steering (4660604).....
Hybrid w/Kubota EA300 Eng.	PA1639	Unimog U95
Lube.....	Unimog U54 (403)	Lube (11845525).....
CLN&R	Lube (3141800109).....	B-P Lube (1845825).....
Fuel/Water Separator (w/Drain and Sensor Port) (Racor R12S)....	B-P Lube (1845825).....	Fuel (3524700092).....
BF1379	Fuel (3524700092).....	Air (10949404).....
Fuel/Water Separator (Open End for Bowl) (Racor R12S).....	Air (10949404).....	Steering (4660604).....
BF1379-O	Unimog U60T (421) w/OM615, OM616, OM621 Engs.	Unimog U100 (416)
Fuel (15231-43560).....	Lube (6171800009).....	Lube (11845525).....
PF872	B-P Lube (1845825).....	B-P Lube (1845825).....
Air (Plastic Air Hsg.) (Wix 42716).	Fuel (3524700092).....	Fuel (3524700092).....
PA643	Air (942804).....	Air (10949404).....
Air (Metal Air Hsg.) (14971-11180).....	PA1639	Steering (4660604).....
PA3983-FN	Unimog U66 (403)	Unimog U110, U110T (406), (416)
UCRV 1-3.5 w/Kubota EA300 Eng.	Lube (3141800109).....	Lube (11845525).....
Lube.....	B-P Lube (1845825).....	B-P Lube (1845825).....
CLN&R	Fuel (3524700092).....	Fuel (3524700092).....
Fuel/Water Separator (w/Drain and Sensor Port) (Racor R12S)....	Air (942804).....	Air (10949404).....
BF1379	Unimog U70 (406)	Steering (4660604).....
Fuel/Water Separator (Open End for Bowl) (Racor R12S).....	Lube (11845525).....	Unimog U120 (425)
BF1379-O	B-P Lube (1845825).....	Lube (3141800109).....
Fuel (15231-43560).....	Fuel (3524700092).....	Fuel (3524700092).....
PF872	Air (10949404).....	F834-F
Air (Plastic Air Hsg.) (Wix 42716).	PA3807	Unimog U125 (416)
PA643	Steering (4660604).....	Lube (11845525).....
Air (Metal Air Hsg.) (14971-11180).....	Unimog U72 (403), (406)	B-P Lube (1845825).....
PA3983-FN	Lube (3141800109).....	Fuel (3524700092).....
UCT 1-3.5 w/Kubota EA300 Eng.	B-P Lube (1845825).....	Air (10949404).....
Lube.....	Fuel (3524700092).....	Steering (4660604).....
CLN&R	Air (10949404).....	Unimog U150 (425)
Fuel/Water Separator (w/Drain and Sensor Port) (Racor R12S)....	PA3807	Lube (3141800109).....
BF1379	Steering (4660604).....	Fuel (3524700092).....
Fuel/Water Separator (Open End for Bowl) (Racor R12S).....	Unimog U80 (406), (416)	F834-F
BF1379-O	Lube (11845525).....	Unimog U600, U600L, U600T w/OM615, OM616, OM621 Engs.
Fuel (15231-43560).....	B-P Lube (1845825).....	123.8 mm B-P Lube (1845825)....
PF872	Fuel (3524700092).....	193.7 mm B-P Lube (6171800009).....
Air (Plastic Air Hsg.) (Wix 42716).	Air (10949404).....	P102
PA643	PA3807	Fuel (3524700092).....
Air (Metal Air Hsg.) (14971-11180).....	Some Air (10949404).....	F834-F
PA3983-FN	PA3807	127.0 mm Air (942804).....
UCT 2-5.5 w/Kubota Z482 Eng.	Unimog U70 (406)	220.7 mm Air (10949404).....
Lube (70000-15241).....	Lube (11845525).....	PA3807
B179	B-P Lube (1845825).....	Unimog U80 (406), (416)
Fuel (70000-43081).....	Fuel (3524700092).....	Lube (11845525).....
BF7683	Air (10949404).....	B-P Lube (1845825).....
<b>TRUCK MATE GENERATORS</b> Auxiliary Power Units (APU)	Steering (4660604).....	Fuel (3524700092).....
655-DS w/Yanmar 3TNV Eng.	P106-HD	Air (942804).....
Lube (119005-35151).....	Unimog U70 (406)	PA1639
B161-S	Lube (3141800109).....	PA3807
Fuel (119802-55801).....	B-P Lube (1845825).....	Unimog U80 (406), (416)
BF9887	Fuel (3524700092).....	Lube (11845525).....

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>UNIMOG Trucks (cont'd)</b>	<b>VAN HOOL Buses (cont'd)</b>	<b>VAN HOOL Buses (cont'd)</b>
Unimog U800, U800L Lube (3141800109)..... <b>P7017</b> B-P Lube (1845825)..... <b>P41 +</b> Fuel (3524700092)..... <b>F834-F</b> Air (10949404)..... <b>PA3807</b>	A300L w/Cummins LT10 Eng. (Cont'd) <b>Fuel/Water Separator</b> (Open End for Bowl) (Fleetguard FS1242)..... <b>BF1249-O</b> <b>Fuel/Water Separator</b> (w/Drain & Sensor Port) (Fleetguard FS1242) <b>BF1249-SP</b> <b>Fuel/Water Separator</b> (w/Drain & Sensor Port, High Efficiency Version) (Fleetguard FS1242)..... <b>BF1393-SP</b> Fuel (Fleetguard FF105)..... <b>BF957 +</b> Coolant (Fleetguard WF2071)..... <b>BW5071</b>	A508 w/Cummins 6BT 5.9L Eng. Lube (Fleetguard LF3349)..... <b>BT339 +</b> Fuel (Fleetguard FF42000)..... <b>BF788</b>
Unimog U900 B-P Lube..... <b>P41 +</b> Lube (11845525)..... <b>P7015</b> Fuel (3524700092)..... <b>F834-F</b> Air (10949404)..... <b>PA3807</b> Steering (4660604)..... <b>P106-HD</b>	A300L w/DAF NS156G Eng. Fuel (Fleetguard FF4070)..... <b>BF980</b>	Acron T815 w/DAF DKX1160ATI Eng. Fuel (Fleetguard FF4070)..... <b>BF980</b>
Unimog U1000, U1000T Lube (11845525)..... <b>P7015</b> Fuel (3524700092)..... <b>F834-F</b> Air (10949404)..... <b>PA3807</b> Steering (4660604)..... <b>P106-HD</b>	A309 w/Cummins ISB Eng. Lube (4897898)..... <b>BT7237</b> Fuel (4897833)..... <b>BF7813</b> Air Dryer (1506635)..... <b>BA5379 +</b> Steering (229348)..... <b>P106-HD</b> Diesel Exhaust Fluid (3967874).. <b>PE5270</b>	AG300 w/DAF PE228C Eng. Lube Ele. (5 7/8 In.) (1397764).... <b>P7232</b> Lube Ele. (8 17/32 In.) (1397765) <b>P7330</b> B-P Lube Centrifugal (1376481). <b>BC7194</b> Fuel/Water Separator (1355891). <b>BF1281 +</b> Fuel (8 In.) (1397766)..... <b>PF7767</b> Fuel (9 3/4 In.) (1450184)..... <b>PF7946</b> Radial Seal O. Air (1146384)..... <b>RS30232</b> Air Dryer (1782420)..... <b>BA5379 +</b> Steering (229348)..... <b>P106-HD</b>
Unimog U1100, U1100L, U1100T (416) B-P Lube (1845825)..... <b>P41 +</b> Lube (11845525)..... <b>P7015</b> Fuel (3524700092)..... <b>F834-F</b> Air (10949404)..... <b>PA3807</b> Steering (4660604)..... <b>P106-HD</b>	A330 w/DAF PR183 Eng. Lube Ele. (1397765)..... <b>P7330</b> B-P Lube Centrifugal (1376481). <b>BC7194</b> Fuel (1811391)..... <b>PF7946</b> Air Dryer (1782420)..... <b>BA5379 +</b> Steering (229348)..... <b>P106-HD</b> Diesel Exhaust Fluid (3967874).. <b>PE5270</b>	AG300 w/DAF PE265C Eng. Lube Ele. (5 7/8 In.) (1397764).... <b>P7232</b> Lube Ele. (8 17/32 In.) (1397765) <b>P7330</b> B-P Lube Centrifugal (1376481). <b>BC7194</b> Fuel/Water Separator (1355891). <b>BF1281 +</b> Fuel (8 In.) (1397766)..... <b>PF7767</b> Fuel (9 3/4 In.) (1450184)..... <b>PF7946</b> Radial Seal O. Air (1146384)..... <b>RS30232</b> Air Dryer (1782420)..... <b>BA5379 +</b> Steering (229348)..... <b>P106-HD</b>
Unimog U1200 w/OM352, OM352A Eng. 136.5 mm Lube (3141800109).... <b>P7017</b> 199.2 mm Lube (11845525)..... <b>P7015</b> Fuel (3524700092)..... <b>F834-F</b>	A330 w/DAF PR228 Eng. Lube Ele. (1397765)..... <b>P7330</b> B-P Lube Centrifugal (1376481). <b>BC7194</b> Fuel (1811391)..... <b>PF7946</b> Air Dryer (1782420)..... <b>BA5379 +</b> Steering (229348)..... <b>P106-HD</b> Diesel Exhaust Fluid (3967874).. <b>PE5270</b>	AG300 w/DAF PR183 Eng. Lube Ele. (1397765)..... <b>P7330</b> B-P Lube Centrifugal (1376481). <b>BC7194</b> Fuel (1811391)..... <b>PF7946</b> Steering (229348)..... <b>P106-HD</b>
Unimog U1300, U1300L 136.5 mm Lube (3141800109).... <b>P7017</b> 195.3 mm Lube (11844925)..... <b>P721</b> 199.2 mm Lube (11845525)..... <b>P7015</b> Fuel (3524700092)..... <b>F834-F</b>	A330 w/DAF PR265 Eng. Lube Ele. (1397765)..... <b>P7330</b> B-P Lube Centrifugal (1376481). <b>BC7194</b> Fuel (1811391)..... <b>PF7946</b> Steering (229348)..... <b>P106-HD</b>	AG300 w/DAF PR228 Eng. Lube Ele. (1397765)..... <b>P7330</b> B-P Lube Centrifugal (1376481). <b>BC7194</b> Fuel (1811391)..... <b>PF7946</b> Air Dryer (1782420)..... <b>BA5379 +</b> Steering (229348)..... <b>P106-HD</b> Diesel Exhaust Fluid (3967874).. <b>PE5270</b>
Unimog U1500, U1500L 136.5 mm Lube (3141800109).... <b>P7017</b> 195.3 mm Lube (11844925)..... <b>P721</b> 199.2 mm Lube (11845525)..... <b>P7015</b> Fuel (3524700092)..... <b>F834-F</b>	A360 w/DAF PR183 Eng. Lube Ele. (1397765)..... <b>P7330</b> B-P Lube Centrifugal (1376481). <b>BC7194</b> Fuel (1811391)..... <b>PF7946</b> Air Dryer (1506635)..... <b>BA5379 +</b> Steering (229348)..... <b>P106-HD</b> Diesel Exhaust Fluid (3967874).. <b>PE5270</b>	AG300 w/DAF PR265 Eng. Lube Ele. (1397765)..... <b>P7330</b> B-P Lube Centrifugal (1376481). <b>BC7194</b> Fuel (1811391)..... <b>PF7946</b> Air Dryer (1782420)..... <b>BA5379 +</b> Steering (229348)..... <b>P106-HD</b> Diesel Exhaust Fluid (3967874).. <b>PE5270</b>
U1700 195.3 mm Lube (11844925)..... <b>P721</b> 199.2 mm Lube (11845525)..... <b>P7015</b> 136.5 mm Lube (3141800109).... <b>P7017</b> Fuel (3524700092)..... <b>F834-F</b>	A360 w/DAF PR228 Eng. Lube Ele. (1397765)..... <b>P7330</b> B-P Lube Centrifugal (1376481). <b>BC7194</b> Fuel (1811391)..... <b>PF7946</b> Steering (229348)..... <b>P106-HD</b>	Alicron T916 w/DAF MX300S Eng. Lube Ele. (1629393)..... <b>P40019</b> B-P Lube Centrifugal (1643072). <b>BC7326 +</b> Fuel/Water Separator (1433649). <b>BF1383-O</b> Fuel (1616361)..... <b>PF7947</b> Steering (229348)..... <b>P106-HD</b> Diesel Exhaust Fluid (649425).... <b>PE5270</b>
Unimog U500 w/OM906 Eng. Lube..... <b>P7188</b>	A360 w/DAF PR265 Eng. Lube Ele. (1397765)..... <b>P7330</b> B-P Lube Centrifugal (1376481). <b>BC7194</b> Fuel (1811391)..... <b>PF7946</b> Steering (229348)..... <b>P106-HD</b>	Alizee 760 w/DAF Eng. Lube (Fleetguard LF4054)..... <b>B236 +</b> Fuel Ele. (Fleetguard FF147)..... <b>PF950</b> Fuel Spin-on (Fleetguard FF4070)..... <b>BF980</b> Coolant (Fleetguard WF2053)..... <b>BW5139</b>
<b>UNIVERSAL COACH Buses</b>		
Models w/Nelson Air Filters Air (70157D)..... <b>PA3916</b>		
<b>VAN HOOL Buses</b>		
A300L w/Cummins LT10 Eng. Std. F-F Lube (Fleetguard LF670)..... <b>B196 +</b> Ext. Life F-F Lube (Fleetguard LF670)..... <b>B96 +</b> B-P Lube (Fleetguard LF777)..... <b>B7577</b> Fuel/Water Separator (w/Drain) (Fleetguard FS1242)..... <b>BF1249</b>		

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

VAN HOOL Buses (cont'd)	VAN HOOL Buses (cont'd)	VAN HOOL Buses (cont'd)
Alizee 760 w/DAF Eng. (Cont'd) <b>Steering</b> (Fleetguard HF6161)..... <b>PT691</b>	Commuter Coach CX w/Cummins L9 (9.0L) Eng. (2018) <b>Lube</b> (3401544)..... <b>B40142</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b> <b>Crankcase Breather</b> (4936636)... <b>CV15010</b>	T2100 w/Detroit Diesel Series 60 (12.7L) Eng. (1997-2011) (Cont'd) <b>Coolant</b> (23516489)..... <b>BW5200</b> <b>Trans.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>
Astromega TD824 w/DAF DKX1160ATI Eng. <b>Lube</b> (Fleetguard LF4054)..... <b>B236 +</b> <b>Fuel</b> (Fleetguard FF4070)..... <b>BF980</b>	Commuter Coach CX w/Cummins L9 (9.0L) Eng. (2019) <b>Lube</b> (3401544)..... <b>B40142</b> <b>Fuel</b> (5303743)..... <b>BF63000</b>	TD925 w/DAF MX300S Eng. <b>Fuel/Water Separator</b> (1433649). <b>BF1383-O</b> <b>Fuel</b> (1616361)..... <b>PF7947</b>
Astromega TD925 w/DAF MX375S Eng. <b>Lube Ele.</b> (1629393)..... <b>P40019</b> <b>B-P Lube Centrifugal</b> (1643072). <b>BC7326 +</b> <b>Fuel/Water Separator</b> (1433649). <b>BF1383-O</b> <b>Fuel</b> (1616361)..... <b>PF7947</b> <b>Steering</b> (229348)..... <b>P106-HD</b> <b>Diesel Exhaust Fluid</b> (649425).... <b>PE5270</b>	Commuter Coach CX w/Cummins L9 (9.0L) Eng. (2020) <b>Lube</b> (5444774)..... <b>B40142</b> <b>Fuel</b> (5303743)..... <b>BF63000</b>	TD925 w/DAF MX340 Eng. <b>Lube Ele.</b> (1629393)..... <b>P40019</b> <b>B-P Lube Centrifugal</b> (1643072). <b>BC7326 +</b> <b>Fuel/Water Separator</b> (1433649). <b>BF1383-O</b> <b>Fuel</b> (1616361)..... <b>PF7947</b> <b>Air Dryer</b> (1506635)..... <b>BA5379 +</b> <b>Steering</b> (229348)..... <b>P106-HD</b> <b>Diesel Exhaust Fluid</b> (3967874).. <b>PE5270</b>
Astromega TD927 w/DAF XE355C Eng. <b>Lube Ele.</b> (1397765)..... <b>P7330</b> <b>B-P Lube Centrifugal</b> (1376481). <b>BC7194</b> <b>Fuel</b> (1450184)..... <b>PF7946</b> <b>Radial Seal O. Air</b> (1146384)..... <b>RS30232</b> <b>Radial Seal I. Air</b> (1147590)..... <b>RS30181</b> <b>Steering</b> (229348)..... <b>P106-HD</b>	Commuter Coach CX w/Cummins X12 (11.9L) Eng. (2020) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel</b> (5365988)..... <b>BF46129</b>	TDX Double Decker Coach w/Cummins ISX 11.9 (11.9L) Eng. (2018) <b>Dual-Flow Lube</b> (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel</b> (Fleetguard FF5776)..... <b>BF9885</b>
CL915 w/DAF MX300S Eng. <b>Fuel</b> (1616361)..... <b>PF7947</b> <b>Steering</b> (229348)..... <b>P106-HD</b>	Commuter Coach CX w/Cummins X12 (11.9L) Eng. (2022) <b>Lube</b> (5575298)..... <b>B40145</b> <b>Fuel</b> (5365988)..... <b>BF46129</b>	TDX Double Decker Coach w/Cummins ISX 11.9 (11.9L) Eng. (2019) <b>Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel</b> (2893612)..... <b>BF9885</b>
CL915 w/DAF MX340 Eng. <b>Lube Ele.</b> (1629393)..... <b>P40019</b> <b>B-P Lube Centrifugal</b> (1643072). <b>BC7326 +</b> <b>Fuel/Water Separator</b> (1433649). <b>BF1383-O</b> <b>Fuel</b> (1616361)..... <b>PF7947</b> <b>Air Dryer</b> (1681575)..... <b>BA5284 +</b> <b>Steering</b> (229348)..... <b>P106-HD</b> <b>Diesel Exhaust Fluid</b> (3967874).. <b>PE5270</b>	Commuter Coach CX w/Detroit DD13 (12.8L) Eng. (2018) <b>Dual-Flow Lube</b> (A4731800109).. <b>P7505</b> <b>Fuel</b> (A4720900651)..... <b>PF9908 KIT</b>	TDX Double Decker Coach w/Cummins ISX 11.9 (11.9L) Eng. (2020) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel</b> (2893612)..... <b>BF9885</b>
CL916 w/DAF MX300S, MX340 Eng. <b>Lube Ele.</b> (1629393)..... <b>P40019</b> <b>B-P Lube Centrifugal</b> (1643072). <b>BC7326 +</b> <b>Fuel/Water Separator</b> (1433649). <b>BF1383-O</b> <b>Fuel</b> (1616361)..... <b>PF7947</b> <b>Radial Seal Air</b> (Don. P777871)... <b>RS3826</b> <b>Air Dryer</b> (1681575)..... <b>BA5284 +</b> <b>Steering</b> (229348)..... <b>P106-HD</b> <b>Diesel Exhaust Fluid</b> (3967874).. <b>PE5270</b>	Commuter Coach CX w/Detroit DD13 (12.8L) Eng. (2019) <b>Lube</b> (A4731800409)..... <b>P7505</b> <b>Fuel</b> (A4720900651)..... <b>PF9908 KIT</b>	TDX Double Decker Coach w/Cummins ISX 11.9 (11.9L) Eng. (2021) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel</b> (5365988)..... <b>BF46129</b>
Commuter Coach CX w/Cummins ISL 8.9 (8.9L) Eng. (2018) <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Fuel</b> (Fleetguard FF63009)..... <b>BF63000</b>	Commuter Coach CX w/Detroit DD13 (12.8L) Eng. (2021) <b>Fuel</b> (A4700903151)..... <b>PF9908 KIT</b>	TL916 w/DAF MX300S Eng. <b>Lube Ele.</b> (1629393)..... <b>P40019</b> <b>B-P Lube Centrifugal</b> (1643072). <b>BC7326 +</b> <b>Fuel/Water Separator</b> (1433649). <b>BF1383-O</b> <b>Fuel</b> (1616361)..... <b>PF7947</b> <b>Radial Seal Air</b> (Don. P777871)... <b>RS3826</b> <b>Air Dryer</b> (1506635)..... <b>BA5379 +</b> <b>Steering</b> (229348)..... <b>P106-HD</b> <b>Diesel Exhaust Fluid</b> (3967874).. <b>PE5270</b>
Commuter Coach CX w/Cummins ISX 11.9 (11.9L) Eng. (2018) <b>Dual-Flow Lube</b> (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel</b> (Fleetguard FF5776)..... <b>BF9885</b>	EOS100 w/DAF DKX1160ATI Eng. <b>Lube</b> (Fleetguard LF4054)..... <b>B236 +</b> <b>Fuel</b> (Fleetguard FF4070)..... <b>BF980</b>	Tourist Coach TX w/Cummins ISX 11.9 (11.9L) Eng. (2018) <b>Dual-Flow Lube</b> (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel</b> (Fleetguard FF5776)..... <b>BF9885</b>
Commuter Coach CX w/Cummins ISX 11.9 (11.9L) Eng. (2019) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel</b> (2893612)..... <b>BF9885</b>	T2100 w/Cummins ISM 10.8 (10.8L) Eng. (1999-2011) <b>Trans.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	Tourist Coach TX w/Cummins ISX 11.9 (11.9L) Eng. (2019) <b>Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel</b> (2893612)..... <b>BF9885</b>
	T2100 w/Detroit Diesel Series 60 (12.7L) Eng. (1997-2011) <b>Lube</b> (23518480)..... <b>[2] B495</b> <b>Fuel/Water Separator</b> (w/Drain) (23512317)..... <b>BF5813 +</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (23512317)..... <b>BF5813-O +</b> <b>Fuel</b> (23533726)..... <b>BF5816</b>	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>VAN HOOL</b> <b>Buses (cont'd)</b>	<b>VOLKSWAGEN</b> <b>European Light Duty Vehicles (cont'd)</b>	<b>VOLKSWAGEN</b> <b>European Light Duty Vehicles (cont'd)</b>
Tourist Coach TX w/Detroit DD13 (12.8L) Eng. (2018) <b>Dual-Flow Lube</b> (A4731800109)..... <b>P7505</b> <b>Fuel</b> (A4720900651)..... <b>PF9908 KIT</b>	Caddy III 1.4 (2KA, 2KB, 2KH, 2KJ) w/BCA Eng. (02/04-12/10) <b>Fuel</b> (6Q0201051A)..... <b>BF9805</b>	Caddy IV 2.0 Ecofuel w/BSX Eng. (10/10-on) <b>Fuel</b> (1K0201051C)..... <b>BF46221</b> <b>Air</b> (1F0129620)..... <b>PA10113</b>
Tourist Coach TX w/Detroit DD13 (12.8L) Eng. (2019) <b>Lube</b> (A4731800409)..... <b>P7505</b> <b>Fuel</b> (A4720900651)..... <b>PF9908 KIT</b>	Caddy III 1.4 16 V (2KA, 2KB, 2KH, 2KJ) w/BUD Eng. (06/06-12/10) <b>Fuel</b> (6Q0201051A)..... <b>BF9805</b>	Caddy IV 2.0 TDI (2C) w/CFHC, CFHE, CFHF, CLCA Engs. (09/10-on) <b>Lube</b> (3L115466)..... <b>P40024</b> <b>(115.9 mm) Fuel</b> (1K0127177B)... <b>PF9861</b> <b>(136.5 mm) Fuel</b> (3C0127434).... <b>PF46188</b> <b>Air</b> (1K0129620D)..... <b>PA4428</b>
Tourist Coach TX w/Detroit DD13 (12.8L) Eng. (2020) <b>Lube</b> (To Eng. S/N 472910S0690710) (A4731800409)..... <b>P7505</b> <b>Fuel</b> (A4700903151)..... <b>PF9908 KIT</b>	Caddy III 1.6 (2KA, 2KB, 2KH, 2KJ) w/BGU, BSE, BSF Eng. (02/04-12/10) <b>Lube</b> (30115561C)..... <b>B178</b> <b>Fuel</b> (6Q0201051A)..... <b>BF9805</b> <b>Air</b> (1F0129620)..... <b>PA10113</b>	Caddy IV 2.0 TDI (2C) w/CFJA Eng. (05/12-on) <b>Lube</b> (3L115466)..... <b>P40024</b> <b>(115.9 mm) Fuel</b> (1K0127177B)... <b>PF9861</b> <b>(136.5 mm) Fuel</b> (3C0127434).... <b>PF46188</b> <b>Air</b> (1K0129620D)..... <b>PA4428</b>
Urban Bus w/Cummins L9 (9.0L) Eng. (2021) <b>Lube</b> (5444774)..... <b>B40142</b> <b>Fuel</b> (5303743)..... <b>BF63000</b>	Caddy III 1.9 TDI (2KA, 2KB, 2KH, 2KJ) w/BJB, BLS Eng. (02/04-12/10) <b>Lube</b> (45115466)..... <b>P7415</b> <b>(115.9 mm) Fuel</b> (1K0127177B)... <b>PF9861</b> <b>(136.5 mm) Fuel</b> (3C0127434).... <b>PF46188</b> <b>(142.1 mm) Fuel</b> (1K0127177A)... <b>PF9872</b> <b>Air</b> (1K0129620D)..... <b>PA4428</b>	Caravelle 1.9 TDI (7HM, 7HF) w/AXB, AXC Engs. (05/03-12/09) <b>Lube</b> (45115466)..... <b>P7415</b> <b>Cabin Air</b> (w/o Charcoal) (7H0819631)..... <b>PA10034</b> <b>Cabin Air</b> (w/Charcoal) (7H0819631A)..... <b>PA10018</b>
<b>VOLKSWAGEN</b> <b>European Light Duty Vehicles</b>	Caddy III 1.9 TDI (2KA, 2KB, 2KH, 2KJ) w/BSU Eng. (09/05-12/10) <b>Lube</b> (45115466)..... <b>P7415</b> <b>(115.9 mm) Fuel</b> (1K0127177B)... <b>PF9861</b> <b>(136.5 mm) Fuel</b> (3C0127434).... <b>PF46188</b> <b>(142.1 mm) Fuel</b> (1K0127177A)... <b>PF9872</b> <b>Air</b> (1K0129620D)..... <b>PA4428</b>	Caravelle 1.9 TDI (7HM, 7HF) w/BRR, BRS Engs. (01/06-12/09) <b>Lube</b> (45115466)..... <b>P7415</b> <b>Cabin Air</b> (w/o Charcoal) (7H0819631)..... <b>PA10034</b> <b>Cabin Air</b> (w/Charcoal) (7H0819631A)..... <b>PA10018</b>
Amarok 2.0 tDI (2H) w/CDBA, CNFA Eng. (01/10-on) <b>Lube</b> (3L115466)..... <b>P40024</b> <b>Cabin Air</b> (w/o Charcoal) (7H0819631)..... <b>PA10034</b> <b>Cabin Air</b> (w/Charcoal) (7H0819631A)..... <b>PA10018</b>	Caddy III 2.0 Ecofuel (2KA, 2KB, 2KH, 2KJ) w/BSX Eng. (04/06-12/10) <b>Lube</b> (30115561C)..... <b>B178</b> <b>Fuel</b> (6Q0201051A)..... <b>BF9805</b> <b>Air</b> (1F0129620)..... <b>PA10113</b>	Caravelle 2.0 TDI (7E) w/CAAA, CAAB, CAAC Eng. (09/09-on) <b>Lube</b> (3L115466)..... <b>P40024</b> <b>Cabin Air</b> (w/o Charcoal) (7H0819631)..... <b>PA10034</b> <b>Cabin Air</b> (w/Charcoal) (7H0819631A)..... <b>PA10018</b>
Amarok 2.0 tDI (2H) w/CDCA Eng. (01/10-on) <b>Lube</b> (3L115466)..... <b>P40024</b> <b>Cabin Air</b> (w/o Charcoal) (7H0819631)..... <b>PA10034</b> <b>Cabin Air</b> (w/Charcoal) (7H0819631A)..... <b>PA10018</b>	Caddy III 2.0 SDI (2KA, 2KB, 2KH, 2KJ) w/BDJ, BST Engs. (02/04-12/10) <b>Lube</b> (45115466)..... <b>P7415</b> <b>(115.9 mm) Fuel</b> (1K0127177B)... <b>PF9861</b> <b>(136.5 mm) Fuel</b> (3C0127434).... <b>PF46188</b> <b>(142.1 mm) Fuel</b> (1K0127177A)... <b>PF9872</b> <b>Air</b> (1F0129620)..... <b>PA10113</b>	Caravelle 2.0 TDI (7E) w/CAAD Eng. (05/11-on) <b>Lube</b> (3L115466)..... <b>P40024</b> <b>Cabin Air</b> (w/o Charcoal) (7H0819631)..... <b>PA10034</b> <b>Cabin Air</b> (w/Charcoal) (7H0819631A)..... <b>PA10018</b>
Amarok 2.0 tDI (2H) w/CFPA Eng. (12/10-on) <b>Lube</b> (6H115561)..... <b>B7452</b> <b>Fuel</b> (1K0201051C)..... <b>BF46221</b> <b>Cabin Air</b> (w/o Charcoal) (7H0819631)..... <b>PA10034</b> <b>Cabin Air</b> (w/Charcoal) (7H0819631A)..... <b>PA10018</b>	Caddy III 2.0 TDI (2KA, 2KB, 2KH, 2KJ) w/BMM Eng. (09/07-12/10) <b>Lube</b> (45115466)..... <b>P7415</b> <b>Fuel</b> (3C0127434)..... <b>PF46188</b> <b>Air</b> (1K0129620D)..... <b>PA4428</b>	Caravelle 2.0 TDI (7E) w/CAAE, CCHB Engs. (05/10-on) <b>Lube</b> (3L115466)..... <b>P40024</b> <b>Cabin Air</b> (w/o Charcoal) (7H0819631)..... <b>PA10034</b> <b>Cabin Air</b> (w/Charcoal) (7H0819631A)..... <b>PA10018</b>
Amarok 2.0 tDI (2H) w/CNEA, CSHA Engs. (11/11-on) <b>Lube</b> (3L115466)..... <b>P40024</b> <b>Cabin Air</b> (w/o Charcoal) (7H0819631)..... <b>PA10034</b> <b>Cabin Air</b> (w/Charcoal) (7H0819631A)..... <b>PA10018</b>	Caddy IV 1.2 TSI (2C) w/CBZA Eng. (09/10-on) <b>Fuel</b> (1K0201051C)..... <b>BF46221</b> <b>Air</b> (1F0129620)..... <b>PA10113</b>	
Amarok 2.0 tDI (2H) w/CNFB Engs. (07/12-on) <b>Lube</b> (3L115466)..... <b>P40024</b> <b>Cabin Air</b> (w/o Charcoal) (7H0819631)..... <b>PA10034</b> <b>Cabin Air</b> (w/Charcoal) (7H0819631A)..... <b>PA10018</b>	Caddy IV 1.6 (2C) w/BSF, CHGA (Bifuel/LPG) Engs. (10/10-on) <b>Fuel</b> (1K0201051C)..... <b>BF46221</b> <b>Air</b> (1F0129620)..... <b>PA10113</b>	
Caddy II 1.4 (9K9) w/AUA Eng. (08/00-02/04) <b>Fuel</b> ..... <b>BF1049</b> <b>Cabin Air</b> (1H0819638A)..... <b>PA4331</b>	Caddy IV 1.6 TDI (2C) w/CAYD, CAYE Eng. (09/10-on) <b>Lube</b> (3L115466)..... <b>P40024</b> <b>(115.9 mm) Fuel</b> (1K0127177B)... <b>PF9861</b> <b>(136.5 mm) Fuel</b> (3C0127434).... <b>PF46188</b> <b>Air</b> (1K0129620D)..... <b>PA4428</b>	

Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

VOLKSWAGEN European Light Duty Vehicles (cont'd)	VOLKSWAGEN European Light Duty Vehicles (cont'd)	VOLKSWAGEN European Light Duty Vehicles (cont'd)
Caravelle 2.0 TDI (7E) w/CFCA Eng. (09/09-on) <b>Cabin Air</b> (w/o Charcoal) (7H0819631)..... <b>PA10034</b> <b>Cabin Air</b> (w/Charcoal) (7H0819631A)..... <b>PA10018</b>	Crafter 2.0 TDI (2E/2F) w/BJJ, CEBA Engs. (04/06-07/11) (Cont'd) <b>369.9 mm Cabin Air</b> (2E0819638A)..... <b>PA4336</b>	Crafter 2.5 TDI w/BJL, CEBA Eng. (04/06-on) <b>Lube Ele.</b> (74115562)..... <b>P7308</b> <b>Fuel</b> (2E0127159)..... <b>PF46118</b> <b>Air</b> (2E0129620B)..... <b>PA4390</b> <b>369.9 mm Cabin Air</b> (2E0819638A)..... <b>PA4336</b> <b>354.8 mm Cabin Air</b> (2E0819638)..... <b>PA4488</b>
Caravelle 2.0 TDI (7E) w/CJKA Eng. (06/11-on) <b>Lube</b> (6H115561)..... <b>B7452</b> <b>Fuel</b> (1K0201051C)..... <b>BF46221</b> <b>Cabin Air</b> (w/o Charcoal) (7H0819631)..... <b>PA10034</b> <b>Cabin Air</b> (w/Charcoal) (7H0819631A)..... <b>PA10018</b>	Crafter 2.0 TDI (2E/2F) w/BJK, BJJ, CEBA, CECA Engs. (04/06-on) <b>Lube</b> (38115466)..... <b>P7308</b> <b>Fuel</b> (2E0127159)..... <b>PF46118</b> <b>Air</b> (2E0129620B)..... <b>PA4390</b> <b>354.8 mm Cabin Air</b> (2E0819638)..... <b>PA4488</b> <b>369.9 mm Cabin Air</b> (2E0819638A)..... <b>PA4336</b>	Crafter 2.5 TDI w/BJK, CEBA Eng. (04/06-on) <b>Lube Ele.</b> (74115562)..... <b>P7308</b> <b>Fuel</b> (2E0127159)..... <b>PF46118</b> <b>Air</b> (2E0129620B)..... <b>PA4390</b> <b>369.9 mm Cabin Air</b> (2E0819638A)..... <b>PA4336</b> <b>354.8 mm Cabin Air</b> (2E0819638)..... <b>PA4488</b>
Caravelle 2.0 TDI (7E) w/CJKB Eng. (07/12-on) <b>Lube</b> (6H115561)..... <b>B7452</b> <b>Fuel</b> (1K0201051C)..... <b>BF46221</b> <b>Cabin Air</b> (w/o Charcoal) (7H0819631)..... <b>PA10034</b> <b>Cabin Air</b> (w/Charcoal) (7H0819631A)..... <b>PA10018</b>	Crafter 2.0 TDI (2E/2F) w/BJM, CECB Engs. (04/06-07/11) <b>Lube</b> (38115466)..... <b>P7308</b> <b>Fuel</b> (2E0127159)..... <b>PF46118</b> <b>Air</b> (2E0129620B)..... <b>PA4390</b> <b>354.8 mm Cabin Air</b> (2E0819638)..... <b>PA4488</b> <b>369.9 mm Cabin Air</b> (2E0819638A)..... <b>PA4336</b>	Crafter CR30 w/2,5 BlueTDI EURO V (04/06-on) <b>Lube</b> (38115466)..... <b>P7308</b> <b>Fuel</b> (2E0127159)..... <b>PF46118</b> <b>Air</b> (2E0129620B)..... <b>PA4390</b> <b>369.9 mm Cabin Air</b> (2E0819638A)..... <b>PA4336</b> <b>354.8 mm Cabin Air</b> (2E0819638)..... <b>PA4488</b>
Caravelle 2.5 TDI (7HM, 7HF) w/AXD, AXE, BNZ, BPC Engs. (05/03-12/09) <b>Lube</b> (45115466)..... <b>P7415</b> <b>Cabin Air</b> (w/o Charcoal) (7H0819631)..... <b>PA10034</b> <b>Cabin Air</b> (w/Charcoal) (7H0819631A)..... <b>PA10018</b>	Crafter 2.0 TDI (2E/2F) w/CKTB, CKTC, CKUB Engs. (06/11-on) <b>Lube</b> (3L115466)..... <b>P40024</b> <b>Air</b> (2E0129620B)..... <b>PA4390</b> <b>354.8 mm Cabin Air</b> (2E0819638)..... <b>PA4488</b> <b>369.9 mm Cabin Air</b> (2E0819638A)..... <b>PA4336</b>	Crafter CR35 w/2,5 BlueTDI EURO V (04/06-on) <b>Lube</b> (38115466)..... <b>P7308</b> <b>Fuel</b> (2E0127159)..... <b>PF46118</b> <b>Air</b> (2E0129620B)..... <b>PA4390</b> <b>369.9 mm Cabin Air</b> (2E0819638A)..... <b>PA4336</b> <b>354.8 mm Cabin Air</b> (2E0819638)..... <b>PA4488</b>
Caravelle 2.5 TDI (7HM, 7HF) w/BLJ Eng. (11/03-12/09) <b>Lube</b> (45115466)..... <b>P7415</b> <b>Cabin Air</b> (w/o Charcoal) (7H0819631)..... <b>PA10034</b> <b>Cabin Air</b> (w/Charcoal) (7H0819631A)..... <b>PA10018</b>	Crafter 2.0 TDI (2E/2F) w/CKUC Eng. (10/11-on) <b>Lube</b> (3L115466)..... <b>P40024</b> <b>Air</b> (2E0129620B)..... <b>PA4390</b> <b>354.8 mm Cabin Air</b> (2E0819638)..... <b>PA4488</b> <b>369.9 mm Cabin Air</b> (2E0819638A)..... <b>PA4336</b>	Crafter CR50 w/2,5 BlueTDI EURO V (04/06-on) <b>Lube</b> (38115466)..... <b>P7308</b> <b>Fuel</b> (2E0127159)..... <b>PF46118</b> <b>Air</b> (2E0129620B)..... <b>PA4390</b> <b>369.9 mm Cabin Air</b> (2E0819638A)..... <b>PA4336</b> <b>354.8 mm Cabin Air</b> (2E0819638)..... <b>PA4488</b>
Caravelle 3.2 V6 (7HM, 7HF) w/BDL Eng. (05/03-12/09) <b>Lube</b> (21115561B)..... <b>P7136</b> <b>Fuel</b> (1J0201511A)..... <b>BF7670</b> <b>Cabin Air</b> (w/o Charcoal) (7H0819631)..... <b>PA10034</b> <b>Cabin Air</b> (w/Charcoal) (7H0819631A)..... <b>PA10018</b>	Crafter 2.5 TDI w/BJM, CECB Eng. (04/06-07/11) <b>Lube Ele.</b> (74115562)..... <b>P7308</b> <b>Fuel</b> (2E0127159)..... <b>PF46118</b> <b>Air</b> (2E0129620B)..... <b>PA4390</b> <b>369.9 mm Cabin Air</b> (2E0819638A)..... <b>PA4336</b> <b>354.8 mm Cabin Air</b> (2E0819638)..... <b>PA4488</b>	Fox 1.2 w/CHFA 60 HP (2010-2011) <b>Lube</b> (3D198819A)..... <b>P40014</b> <b>Fuel</b> (6X0201511B)..... <b>BF1185</b>
Caravelle 3.2 V6 (7HM, 7HF) w/CFLA, BKK Engs. (11/03-12/09) <b>Lube</b> (21115561B)..... <b>P7136</b> <b>Fuel</b> (1J0201511A)..... <b>BF7670</b> <b>Cabin Air</b> (w/o Charcoal) (7H0819631)..... <b>PA10034</b> <b>Cabin Air</b> (w/Charcoal) (7H0819631A)..... <b>PA10018</b>	Crafter 2.5 TDI w/BJJ, CEBA Eng. (04/06-07/11) <b>Lube Ele.</b> (74115562)..... <b>P7308</b> <b>Fuel</b> (2E0127159)..... <b>PF46118</b> <b>Air</b> (2E0129620B)..... <b>PA4390</b> <b>369.9 mm Cabin Air</b> (2E0819638A)..... <b>PA4336</b> <b>354.8 mm Cabin Air</b> (2E0819638)..... <b>PA4488</b>	Fox 1.2 w/BMD/ CHFB 55 HP Eng. (2004-2010) <b>Lube</b> (3D198819A)..... <b>P40014</b> <b>Fuel</b> (6X0201511B)..... <b>BF1185</b>
Crafter 2.0 TDI (2E/2F) w/BJJ, CEBA Engs. (04/06-07/11) <b>Lube</b> (38115466)..... <b>P7308</b> <b>Fuel</b> (2E0127159)..... <b>PF46118</b> <b>Air</b> (2E0129620B)..... <b>PA4390</b> <b>354.8 mm Cabin Air</b> (2E0819638)..... <b>PA4488</b>		Fox 1.4 w/BKR 75 HP Eng (2004-2011) <b>Fuel</b> (6X0201511B)..... <b>BF1185</b>
		Fox 1.4 TDI w/BNM 70 HP Eng (2004-2011) <b>Lube</b> (71115562C)..... <b>P7415</b>
		Golf MK5 1.4 w/BCA 74 HP Eng. (2003-2006) <b>Fuel</b> (6Q0201051A)..... <b>BF9805</b>
		Golf MK5 1.4 w/BUD 79 HP Eng. (2006-2008) <b>Fuel</b> (6Q0201051A)..... <b>BF9805</b>


Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

VOLKSWAGEN European Light Duty Vehicles (cont'd)	VOLKSWAGEN European Light Duty Vehicles (cont'd)	VOLKSWAGEN European Light Duty Vehicles (cont'd)
Golf MK5 1.4 FSI w/BKG/BLN 89 HP Eng. (2003-2006) Fuel (1K0201051C)..... <b>BF46221</b>	Golf MK5 2.0 TDI DPF w/BKD/ BMM/ CBDB 138 HP Eng. (2006-2008) Lube (71115562C)..... <b>P7415</b> Fuel (1K0127434B)..... <b>PF9861</b> Air (1K0129620D)..... <b>PA4428</b>	Golf MK6 2.0 GTI w/CCZB 210 HP Eng. (2009-2013) Lube (6J115403Q)..... <b>B7452</b> Fuel (1K0201051C)..... <b>BF46221</b> Air (1K0129620D)..... <b>PA4428</b>
Golf MK5 1.4 TSI w/BMY 138 HP Eng. (2005-2007) Fuel (1K0201051C)..... <b>BF46221</b> Air (1K0129620D)..... <b>PA4428</b>	Golf MK5 2.0 TDI DPF w/ BMN 168 HP Eng. (2006-2008) Lube (71115562C)..... <b>P7415</b> Fuel (1K0127434B)..... <b>PF9861</b> Air (1K0129620D)..... <b>PA4428</b>	Golf MK6 2.0 GTI 35 w/CDL 235 HP Eng. (2008-2013) Lube (6D115562)..... <b>P7399</b> Fuel (1K0201051C)..... <b>BF46221</b> Air (1K0129620D)..... <b>PA4428</b>
Golf MK5 1.4 TSI w/CAVD 168 HP Eng. (2005-2007) Fuel (1K0201051C)..... <b>BF46221</b> Air (1K0129620D)..... <b>PA4428</b>	Golf MK5 2.0 TFSI w/BYD 227 HP Eng. (2007-2010) Lube (6A115561B)..... <b>B178</b> Fuel (1K0201051C)..... <b>BF46221</b> Air (1K0129620D)..... <b>PA4428</b>	Golf MK6 2.0 TDI w/CBDC 110 HP Eng. (2008-2013) Lube (71115562C)..... <b>P7415</b> Fuel (1K0127434B)..... <b>PF9861</b> Air (1K0129620D)..... <b>PA4428</b>
Golf MK5 1.4 TSI w/CAXA 120 HP Eng. (2007-2008) Fuel (1K0201051C)..... <b>BF46221</b> Air (1F0129620)..... <b>PA10113</b>	Golf MK5 2.0 TFSI GTI w/AXX/ BWA/ BPY/ CAWB 197 HP Eng. (2004-2008) Lube (6A115561B)..... <b>B178</b> Fuel (1K0201051C)..... <b>BF46221</b> Air (1K0129620D)..... <b>PA4428</b>	Golf MK6 2.0 TDI BlueMotion w/CBAA/ CBAB 140 HP Eng. (2008-2013) Lube (71115562C)..... <b>P7415</b> Fuel (1K0127434B)..... <b>PF9861</b> Air (1K0129620D)..... <b>PA4428</b>
Golf MK5 1.6 w/BGU/ BSE/ BSF 101 HP Eng. (2004-2008) Lube (6A115561B)..... <b>B178</b> Fuel (6Q0201051A)..... <b>BF9805</b> Air (1F0129620)..... <b>PA10113</b>	Golf MK5 R32 VR6 24V w/BUB 247 HP Eng. (2005-2008) Lube (70115562)..... <b>P7415</b> Fuel (6Q0201051A)..... <b>BF9805</b> Air (1K0129620D)..... <b>PA4428</b>	Golf MK6 2.0 TSI w/CCZA 200 HP Eng. (2009-2013) Lube (6J115403Q)..... <b>B7452</b> Fuel (1K0201051C)..... <b>BF46221</b> Air (1K0129620D)..... <b>PA4428</b>
Golf MK5 1.6 FSI w/BAG/ BLF/ BLP 113 HP Eng. (2003-2007) Fuel (6Q0201051A)..... <b>BF9805</b> Air (1J0129620)..... <b>PA4111</b>	Golf MK6 1.2 TSI w/CBZA 86 HP Eng. (2010-2013) Fuel (1K0201051C)..... <b>BF46221</b> Air (1F0129620)..... <b>PA10113</b>	Golf MK6 2.5 w/BGQ 172 HP Eng. (2008-2013) Lube (6D115562)..... <b>P7399</b> Fuel (1K0201051C)..... <b>BF46221</b> Air (1K0129620D)..... <b>PA4428</b>
Golf MK5 1.9 TDI w/BJB/ BKC/ BXE/ BLS 104 HP Eng. (2003-2008) Lube (71115562C)..... <b>P7415</b> Fuel (1K0127434B)..... <b>PF9861</b> Air (1K0129620D)..... <b>PA4428</b>	Golf MK6 1.2 TSI w/CBZB 105 HP Eng. (2008-2013) Fuel (1K0201051C)..... <b>BF46221</b> Air (1F0129620)..... <b>PA10113</b>	Golf MK6 GTD w/CBBB 170 HP Eng. (2008-2013) Lube (3L115562)..... <b>P40024</b> Fuel (1K0127434B)..... <b>PF9861</b> Air (1K0129620D)..... <b>PA4428</b>
Golf MK5 1.9 TDI w/BRU/ BXF/ BXJ 89 HP Eng. (2004-2008) Lube (71115562C)..... <b>P7415</b> Fuel (1K0127434B)..... <b>PF9861</b> Air (1K0129620D)..... <b>PA4428</b>	Golf MK6 1.4 TSI w/CAVD 160 HP Eng. (2008-2013) Fuel (1K0201051C)..... <b>BF46221</b> Air (1K0129620D)..... <b>PA4428</b>	Golf MK6 R w/CDL 270 HP Eng. (2008-2013) Lube (6D115562)..... <b>P7399</b> Fuel (1K0201051C)..... <b>BF46221</b> Air (1K0129620D)..... <b>PA4428</b>
Golf MK5 1.9 TDI BlueMotion w/ BJB/ BKC/ BXE/ BLS 104 HP Eng. (2007-2008) Lube (71115562C)..... <b>P7415</b> Fuel (1K0127434B)..... <b>PF9861</b> Air (1K0129620D)..... <b>PA4428</b>	Golf MK6 1.4 TSI w/CAXA 122 HP Eng. (2008-2013) Fuel (1K0201051C)..... <b>BF46221</b> Air (1F0129620)..... <b>PA10113</b>	Golf MK7 1.2 TSI BlueMotion w/CJZA 104 HP Eng. (2012-on) Fuel (N/S)..... <b>N/S</b> Air (4E129620)..... <b>PA10282</b> Cabin Air (5Q0819653)..... <b>PA10404</b>
Golf MK5 2.0 FSI w/AXW/ BLR/BLX/ BVY/ BVX 148 HP Eng. (2004-2008) Lube (6D115562)..... <b>P7399</b> Fuel (1K0201051C)..... <b>BF46221</b> Air (1K0129620D)..... <b>PA4428</b>	Golf MK6 1.6 w/BSE/ BSF/ CCSA 102 HP Eng. (2008-2013) Lube (1JM115561BZ)..... <b>B178</b> Fuel (6Q0201051A)..... <b>BF9805</b> Air (1F0129620)..... <b>PA10113</b>	Golf MK7 1.2 TSI BlueMotion w/CJZB 84 HP Eng. (2012-on) Fuel (N/S)..... <b>N/S</b> Air (4E129620)..... <b>PA10282</b> Cabin Air (5Q0819653)..... <b>PA10404</b>
Golf MK5 2.0 SDI w/BDK 75 HP Eng. (2004-2008) Lube (71115562C)..... <b>P7415</b> Fuel (1K0127434B)..... <b>PF9861</b> Air (1K0129620D)..... <b>PA4428</b>	Golf MK6 1.6 TDI BlueMotion w/CAYC 105 HP Eng. (2009-2013) Lube (3L115562)..... <b>P40024</b> Fuel (1K0127434B)..... <b>PF9861</b> Air (1K0129620D)..... <b>PA4428</b>	Golf MK7 1.2 TSI BlueMotion w/CYVB 110 HP Eng. (2013-on) Fuel (N/S)..... <b>N/S</b> Air (4E129620)..... <b>PA10282</b> Cabin Air (5Q0819653)..... <b>PA10404</b>
Golf MK5 2.0 TDI w/AZV 138 HP Eng. (2003-2008) Lube (71115562C)..... <b>P7415</b> Fuel (1K0127434B)..... <b>PF9861</b> Air (1K0129620D)..... <b>PA4428</b>		

Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



VOLKSWAGEN European Light Duty Vehicles (cont'd)	VOLKSWAGEN European Light Duty Vehicles (cont'd)	VOLKSWAGEN European Light Duty Vehicles (cont'd)
Golf MK7 1.4 TSI BlueMotion w/CHPA/ CPTA 138 HP Eng. (2012-on) Fuel (N/S)..... N/S Air (4E129620)..... PA10282 Cabin Air (5Q0819653)..... PA10404	Golf MK7 2.0 TDI w/CRVA/ CYKB 108 HP Eng. (2012-on) Lube (3N115562)..... P40061 Air (5Q0129620B)..... PA10089 Cabin Air (5Q0819653)..... PA10404	Passat B6 1.8 TSI w/CDA 158 HP Eng. (2008-2010) Lube (6J115403Q)..... B7452 Fuel (N/S)..... N/S Air (1K0129620D)..... PA4428
Golf MK7 1.4 TSI BlueMotion w/CMBA/ CPVA/ CXSA 120 HP Eng. (2012-on) Fuel (N/S)..... N/S Air (4E129620)..... PA10282 Cabin Air (5Q0819653)..... PA10404	Golf MK7 2.0 TDI BlueMotion w/CKFC/ CRBC/ CRLB/ CRMB 150 HP Eng. (2012-on) Lube (3N115562)..... P40061 Air (5Q0129620B)..... PA10089 Cabin Air (5Q0819653)..... PA10404	Passat B6 1.9 TDI w/BKC/ BXE/ BLS 104 HP Eng. (2005-2009) Lube (71115562C)..... P7415 Fuel (3C0127434)..... PF46188 Air (1K0129620D)..... PA4428
Golf MK7 1.4 TSI BlueMotion w/CZCA/ CPVB 123 HP Eng. (2014-on) Fuel (N/S)..... N/S Air (4E129620)..... PA10282 Cabin Air (5Q0819653)..... PA10404	LT 2.5 TDI w/BBE 82 HP Eng. (05/01-07/06) Lube Ele. (74115562)..... P7308 Fuel Spin-on (1J0127401A)..... BF7958 Air Panel (2D0129620B)..... PA4600 Cabin Air (2D0819638A)..... PA4489	Passat B6 2.0 BlueTDI w/CBAC 141 HP Eng. (2009-2010) Lube (71115562C)..... P7415 Fuel (3C0127434)..... PF46188 Air (1K0129620D)..... PA4428
Golf MK7 1.4 TSI BlueMotion w/CZEA/ CZDA/ CHPB/ CUKB 148 HP Eng. (2014-on) Fuel (N/S)..... N/S Air (4E129620)..... PA10282 Cabin Air (5Q0819653)..... PA10404	LT 2.5 TDI w/BBF 94 HP Eng. (05/01-07/06) Lube Ele. (74115562)..... P7308 Fuel Spin-on (1J0127401A)..... BF7958 Air Panel (2D0129620B)..... PA4600 Cabin Air (2D0819638A)..... PA4489	Passat B6 2.0 FSI w/BLR/ BVX/ BVY 148 HP Eng. (2005-2010) Lube (6D115562)..... P7399 Fuel (N/S)..... N/S Air (1F0129620)..... PA10113
Golf MK7 1.6 TDI BlueMotion w/CLHA 104 HP Eng. (2012-on) Lube (3N115562)..... P40061 Air (5Q0129620B)..... PA10089 Cabin Air (5Q0819653)..... PA10404	LT 2.5 TDI w/ANJ/AVR 110 HP Eng. (06/99-07/06) Lube Ele. (74115562)..... P7308 Fuel Spin-on (1J0127401A)..... BF7958 Air Panel (2D0129620B)..... PA4600 Cabin Air (2D0819638A)..... PA4489	Passat B6 2.0 TDI w/BMA 134 HP Eng. (2005-2008) Lube (71115562C)..... P7415 Fuel (3C0127434)..... PF46188 Air (1K0129620D)..... PA4428
Golf MK7 1.6 TDI BlueMotion w/CLHB/ CRKA 89 HP Eng. (2012-on) Lube (3N115562)..... P40061 Air (5Q0129620B)..... PA10089 Cabin Air (5Q0819653)..... PA10404	LT 2.8 TDI w/AUH/BCQ 156 HP Eng. (02/02-07/06) Air Panel (2D0129620B)..... PA4600 Cabin Air (2D0819638A)..... PA4489	Passat B6 2.0 TDI w/BMP 138 HP Eng. (2005-2008) Lube (71115562C)..... P7415 Fuel (3C0127434)..... PF46188 Air (1K0129620D)..... PA4428
Golf MK7 2.0 GTD w/CUNA 181 HP Eng. (2013-on) Lube (3N115562)..... P40061 Air (5Q0129620B)..... PA10089 Cabin Air (5Q0819653)..... PA10404	Passat B6 1.4 TSI w/CAXA 120 HP Eng. (2007-2010) Fuel (N/S)..... N/S Air (1F0129620)..... PA10113	Passat B6 2.0 TDI 16V w/BKP 138 HP Eng. (2005-2008) Lube (71115562C)..... P7415 Fuel (3C0127434)..... PF46188 Air (1K0129620D)..... PA4428
Golf MK7 2.0 GTI w/CHHA 227 HP Eng. (2013-on) Lube (6J115403Q)..... B7452 Fuel (N/S)..... N/S Air (5Q0129620B)..... PA10089 Cabin Air (5Q0819653)..... PA10404	Passat B6 1.4 TSI EcoFuel w/CDGA 148 HP Eng. (2008-2010) Fuel (1K0201051C)..... BF46221 Air (1K0129620D)..... PA4428	Passat B6 2.0 TDI 16V w/BMR 168 HP Eng. (2005-2008) Lube (71115562C)..... P7415 Fuel (3C0127434)..... PF46188 Air (1K0129620D)..... PA4428
Golf MK7 2.0 GTI w/CHHB 217 HP Eng. (2013-on) Lube (6J115403Q)..... B7452 Fuel (N/S)..... N/S Air (5Q0129620B)..... PA10089 Cabin Air (5Q0819653)..... PA10404	Passat B6 1.6 w/BSE/ BSF/ CCSA 101 HP Eng. (2005-2010) Lube (6A115561B)..... B178 Fuel (N/S)..... N/S Air (1F0129620)..... PA10113	Passat B6 2.0 TDI 16V w/BVD/ BE 120 HP Eng. (2005-2006) Lube (71115562C)..... P7415 Fuel (3C0127434)..... PF46188 Air (1K0129620D)..... PA4428
Golf MK7 2.0 R w/CJXC/ CJXB/ CJXD/ CYFB 300 HP Eng. (2013-on) Lube (6J115403Q)..... B7452 Fuel (N/S)..... N/S Air (5Q0129620B)..... PA10089 Cabin Air (5Q0819653)..... PA10404	Passat B6 1.6 TDI w/CAYC 104 HP Eng. (2009-2010) Lube (3L115562)..... P40024 Fuel (3C0127434)..... PF46188 Air (1K0129620D)..... PA4428	Passat B6 2.0 TDI 16V w/CBAB 138 HP Eng. (2008-2010) Lube (71115562C)..... P7415 Fuel (3C0127434)..... PF46188 Air (1K0129620D)..... PA4428
	Passat B6 1.8 TSI w/BZB 158 HP Eng. (2007-2010) Lube (6J115403Q)..... B7452 Fuel (N/S)..... N/S Air (1K0129620D)..... PA4428	Passat B6 2.0 TDI 16V w/CBBB 168 HP Eng. (2008-2010) Lube (71115562C)..... P7415 Fuel (3C0127434)..... PF46188 Air (1K0129620D)..... PA4428


Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

VOLKSWAGEN European Light Duty Vehicles (cont'd)	VOLKSWAGEN European Light Duty Vehicles (cont'd)	VOLKSWAGEN European Light Duty Vehicles (cont'd)
Passat B6 2.0 TDI 16V w/CBDC 108 HP Eng. (2008-2010) Lube (71115562C)..... P7415 Fuel (3C0127434)..... PF46188 Air (1K0129620D)..... PA4428	Passat B7 2.0 TDI w/CFG 177 HP Eng. (2013-on) Lube (3L115562)..... P40024 Fuel (7N0127177B)..... PF46189 Air (1K0129620D)..... PA4428	Polo MK4 1.8T GTI w/BXJ 150 HP Eng. (2006-2009) Lube (6A115561B)..... B178
Passat B6 2.0 TFSI w/AXX/ BWA/ BPY 197 HP Eng. (2005-2007) Lube (6D115562)..... P7399 Fuel (N/S)..... N/S Air (6F133843A)..... PA4383	Passat B7 2.0 TSI w/CCZB 207 HP Eng. (2010-on) Lube (6J115403Q)..... B7452 Fuel (N/S)..... N/S Air (1K0129620D)..... PA4428	Polo MK4 1.8 GTI Cup Edition w/BBU 180 HP Eng. (2006-2009) Lube (6A115561B)..... B178
Passat B6 2.0 TSI w/CAWB 197 HP Eng. (2008-2010) Lube (6J115403C)..... B7452 Fuel (N/S)..... N/S Air (1K0129620D)..... PA4428	Passat B7 3.6 V6 FSI w/BWS 296 HP Eng. (2010-on) Lube (3H115562)..... P40035 Fuel (N/S)..... N/S Air (1K0129620)..... PA4396	Polo MK4 1.9 SDI w/ASY 63 HP Eng. (2001-2005) Lube (71115562C)..... P7415
Passat B7 1.4 TSI w/CKMA 160 HP Eng. (2010-on) Fuel (N/S)..... N/S Air (1K0129620D)..... PA4428	Polo MK4 1.2 w/AWY/ BMD 54 HP Eng. (2001-2007) Lube (3D198819A)..... P40014 Fuel (6Q0201051C)..... BF9805	Polo MK4 1.9 TDI w/ASZ/ BLT 130 HP Eng. (2003-2009) Lube (71115562C)..... P7415
Passat B7 1.4 TSI EcoFuel w/CDGA 148 HP Eng. (2010-on) Fuel (N/S)..... N/S Air (1K0129620D)..... PA4428	Polo MK4 1.2 w/BBM 59 HP Eng. (2007-2009) Lube (3D198819A)..... P40014 Fuel (6Q0201051C)..... BF9805	Polo MK4 1.9 TDI w/ATD/ AXR/ BMT 100 HP Eng. (2001-2009) Lube (71115562C)..... P7415
Passat B7 1.6 TDI w/CAYC 104 HP Eng. (2010-on) Lube (3L115562)..... P40024 Fuel (7N0127177B)..... PF46189 Air (1K0129620D)..... PA4428	Polo MK4 1.2 12V w/AZQ/ BME 63 HP Eng. (2001-2007) Lube (3D198819A)..... P40014	Polo MK4 2.0 w/BBX 115 HP Eng. (2002-2009) Lube (6A115561B)..... B178 Fuel (6Q0201051C)..... BF9805
Passat B7 1.8 TSI w/CDA 158 HP Eng. (2010-on) Lube (6J115403Q)..... B7452 Fuel (N/S)..... N/S Air (1K0129620D)..... PA4428	Polo MK4 1.2 12V w/BZG 69 HP Eng. (2007-2009) Lube (3D198819A)..... P40014 Fuel (6Q0201051C)..... BF9805	Polo MK5 1.0 w/CHYA 59 HP Eng. (2014-on) Fuel (1K0201051K)..... BF46221
Passat B7 1.8 TSI w/CDAB 152 HP Eng. (2010-on) Lube (6J115403Q)..... B7452 Fuel (N/S)..... N/S Air (1K0129620D)..... PA4428	Polo MK4 1.4 w/AUA/ BBY/ BKY 74 HP Eng. (2001-2007) Fuel (6Q0201051C)..... BF9805	Polo MK5 1.0 w/CHYB 74 HP Eng. (2014-on) Fuel (1K0201051K)..... BF46221
Passat B7 2.0 BlueTDI w/CFFA 138 HP Eng. (2010-on) Lube (3L115562)..... P40024 Fuel (7N0127177B)..... PF46189 Air (1K0129620D)..... PA4428	Polo MK4 1.4 w/AUB/ BBZ 100 HP Eng. (2002-2006) Fuel (6Q0201051C)..... BF9805	Polo MK5 1.0 TSI w/CHZB 95 HP Eng. (2014-on) Fuel (1K0201051K)..... BF46221
Passat B7 2.0 TDI w/CFFB 138 HP Eng. (2010-on) Lube (3L115562)..... P40024 Fuel (7N0127177B)..... PF46189 Air (1K0129620D)..... PA4428	Polo MK4 1.4 FSI w/AXU 85 HP Eng. (2002-2006) Fuel (6Q0201051C)..... BF9805	Polo MK5 1.0 TSI w/CHZC 110 HP Eng. (2014-on) Fuel (1K0201051K)..... BF46221
Passat B7 2.0 TDI w/CFGB 168 HP Eng. (2010-on) Lube (3L115562)..... P40024 Fuel (7N0127177B)..... PF46189 Air (1K0129620D)..... PA4428	Polo MK4 1.4 TDI w/AMF/ BAY 74 HP Eng. (2001-2005) Lube (71115562C)..... P7415	Polo MK5 1.2 w/CGPA/ CGPB/ CHFA 59/ 69 HP Eng. (2009-2012) Lube (3D198819A)..... P40014 Fuel (1K0201051K)..... BF46221
	Polo MK4 1.4 TDI w/BNM/ BWB 69 HP Eng. (2005-2009) Lube (71115562C)..... P7417	Polo MK5 1.2 TSI w/CBZB 104 HP Eng. (2009-on) Fuel (1K0201051K)..... BF46221
	Polo MK4 1.4 TDI w/BNV/ BMS 79 HP Eng. (2005-2009) Lube (71115562C)..... P7415	Polo MK5 1.2 TSI w/CBZC/ CJZC 89 HP Eng. (2011-on) Fuel (1K0201051K)..... BF46221
	Polo MK4 1.6 w/BTS 104 HP Eng. (2006-2009) Fuel (6Q0201051C)..... BF9805	Polo MK5 1.2 TSI w/CJZD 110 HP Eng. (2014-on) Fuel (1K0201051K)..... BF46221 Air (4E129620)..... PA10282
		Polo MK5 1.4 16V w/CGGB 84 HP Eng. (2009-2014) Fuel (1K0201051K)..... BF46221 Air (4E129620)..... PA10282
		Polo MK5 1.4 Blue GT w/CPTA 140 HP Eng. (2012 - 2014) Fuel (1K0201051K)..... BF46221 Air (4E129620)..... PA10282
		Polo MK5 1.4 GTI w/CAVE 180 HP Eng. (2010-2014) Fuel (1K0201051K)..... BF46221

Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

VOLKSWAGEN European Light Duty Vehicles (cont'd)	VOLKSWAGEN European Light Duty Vehicles (cont'd)	VOLKSWAGEN European Light Duty Vehicles (cont'd)
Polo MK5 1.4 TSI w/CZEA 150 HP Eng. (2014-on) <b>Fuel</b> (1K0201051K)..... <b>BF46221</b> <b>Fuel</b> (6Q0201051J)..... <b>BF9805</b> <b>Air</b> (4E129620)..... <b>PA10282</b>	Scirocco 2.0 CR TDI w/CUUB 150 HP Eng. (2014-on) <b>Lube</b> (3N115562)..... <b>P40061</b> <b>Air</b> (1K0129620D)..... <b>PA4428</b>	Touareg 7L 3.2 V6 w/AZZ/ BAA/ BRS 217 HP Eng. (2003-2010) (Cont'd) <b>Cabin Air</b> (w/o Charcoal) (7H0819631)..... <b>PA10034</b>
Polo MK5 1.6 w/CWVA 110 HP Eng. (2014-on) <b>Fuel</b> (1K0201051K)..... <b>BF46221</b> <b>Fuel</b> (6Q0201051J)..... <b>BF9805</b>	Scirocco 2.0 CR TDI w/CUWA 184 HP Eng. (2014-on) <b>Lube</b> (3N115562)..... <b>P40061</b> <b>Air</b> (1K0129620D)..... <b>PA4428</b>	Touareg 7L 3.2 V6 w/BMV/ BMX/ BKJ/ BRJ 238 HP Eng. (2003-2010) <b>Lube</b> (21115562A)..... <b>P7136</b> <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Air</b> (7L0129620A)..... <b>PA10279</b> <b>Cabin Air</b> (w/Charcoal) (7H0819631A)..... <b>PA10018</b> <b>Cabin Air</b> (w/o Charcoal) (7H0819631)..... <b>PA10034</b>
Polo MK5 1.6 TDI w/CAYA 89 HP Eng. (2009-2014) <b>Lube</b> (3L115562)..... <b>P40024</b>	Scirocco 2.0 CR TDI w/CUXA 179 HP Eng. (2014-on) <b>Lube</b> (3N115562)..... <b>P40061</b> <b>Air</b> (1K0129620D)..... <b>PA4428</b>	Touareg 7L 3.6 V6 FSI w/BHK 276 HP Eng. (2005-2010) <b>Lube</b> (21115562A)..... <b>P7136</b> <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Air</b> (7L0129620)..... <b>PA10279</b> <b>Cabin Air</b> (w/Charcoal) (7H0819631A)..... <b>PA10018</b> <b>Cabin Air</b> (w/o Charcoal) (7H0819631)..... <b>PA10034</b>
Polo MK5 1.6 TDI w/CAYB 74 HP Eng. (2009-2014) <b>Lube</b> (3L115562)..... <b>P40024</b>	Scirocco 2.0 FSI R w/CDLA 261 HP Eng. (2009-on) <b>Lube</b> (6D115562)..... <b>P7399</b> <b>Fuel (11/2010-on)</b> (1K0201051K)..... <b>BF46221</b>	Touareg 7L 4.2 V8 w/AXQ/ BHX 306 HP Eng. (2003-2006) <b>Lube</b> (77115562)..... <b>P40096</b> <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Air</b> (7L0129620)..... <b>PA10279</b> <b>Cabin Air</b> (w/Charcoal) (7H0819631A)..... <b>PA10018</b> <b>Cabin Air</b> (w/o Charcoal) (7H0819631)..... <b>PA10034</b>
Polo MK5 1.6 TDI w/CAYC/ CLNA 104 HP Eng. (2009-2014) <b>Lube</b> (3L115562)..... <b>P40024</b>	Scirocco 2.0 FSI R w/CDLC 256 HP Eng. (2009-on) <b>Lube</b> (6D115562)..... <b>P7399</b> <b>Fuel (11/2010-on)</b> (1K0201051K)..... <b>BF46221</b>	Touareg 7L 4.2 V8 w/BAR 348 HP Eng. (2007-2010) <b>Lube</b> (79198405B)..... <b>P40103</b> <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Air</b> (7L0129620)..... <b>PA10279</b> <b>Cabin Air</b> (w/Charcoal) (7H0819631A)..... <b>PA10018</b> <b>Cabin Air</b> (w/o Charcoal) (7H0819631)..... <b>PA10034</b>
Polo MK5 1.8 GTI w/DAJA/ DAJB 192 HP Eng. (2014-on) <b>Lube</b> (6L115562)..... <b>P40010</b> <b>Fuel</b> (1K0201051K)..... <b>BF46221</b>	Scirocco 2.0 FSI R w/CDLK 280 HP Eng. (2014-on) <b>Lube</b> (6D115562)..... <b>P7399</b> <b>Fuel (N/S)</b> ..... <b>N/S</b>	Touareg 7L 5.0 V10 TDI w/AYH/ BLE 309 HP Eng. (2003-2010) <b>Lube</b> (7Z115562)..... <b>P40117</b> <b>Air</b> (7L0129620)..... <b>PA10279</b> <b>Cabin Air</b> (w/Charcoal) (7H0819631A)..... <b>PA10018</b> <b>Cabin Air</b> (w/o Charcoal) (7H0819631)..... <b>PA10034</b>
Scirocco 1.4 TSI w/CAVD/ CNWA/ CTHD/ CTKA 160 HP Eng. (2008-on) <b>Fuel (11/2010-on)</b> (1K0201051K)..... <b>BF46221</b> <b>Air</b> (1K0129620D)..... <b>PA4428</b>	Scirocco 2.0 TSI w/CBFA/ CCTA/ CAWB 207 HP Eng. (2008-on) <b>Lube</b> (6J115403Q)..... <b>B7452</b> <b>Fuel (11/2010-on)</b> (1K0201051K)..... <b>BF46221</b> <b>Air</b> (1K0129620D)..... <b>PA4428</b>	Touareg 7L 6.0 W12 w/BJN 430 HP Eng. (2004-2010) <b>Lube</b> (7C115562E)..... <b>P40115</b> <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Air</b> (7L0129620)..... <b>PA10279</b> <b>Cabin Air</b> (w/Charcoal) (7H0819631A)..... <b>PA10018</b> <b>Cabin Air</b> (w/o Charcoal) (7H0819631)..... <b>PA10034</b>
Scirocco 1.4 TSI w/CAXA/ CMSB 120 HP Eng. (2008-on) <b>Fuel (11/2010-on)</b> (1K0201051K)..... <b>BF46221</b> <b>Air</b> (1K0129620)..... <b>PA4396</b>	Touareg 7L 2.5 R5 TDI w/BAC/ BPE 172 HP Eng. (2003-2010) <b>Lube</b> (70115562)..... <b>P7415</b> <b>Air</b> (7L0129620)..... <b>PA10279</b> <b>Cabin Air</b> (w/Charcoal) (7H0819631A)..... <b>PA10018</b> <b>Cabin Air</b> (w/o Charcoal) (7H0819631)..... <b>PA10034</b>	
Scirocco 2.0 CR TDI w/CBBB/ CFGB 168 HP Eng. (2009-on) <b>Lube</b> (71115562C)..... <b>P7415</b> <b>Fuel</b> (3C0127434)..... <b>PF46188</b> <b>Air</b> (1K0129620D)..... <b>PA4428</b>	Touareg 7L 3.0 V6 TDI w/BKS/ CATA 222 HP Eng. (2004-2010) <b>Fuel</b> (7L6127434B)..... <b>PF46186</b> <b>Air</b> (7L0129620)..... <b>PA10279</b> <b>Cabin Air</b> (w/Charcoal) (7H0819631A)..... <b>PA10018</b> <b>Cabin Air</b> (w/o Charcoal) (7H0819631)..... <b>PA10034</b>	
Scirocco 2.0 CR TDI w/CBDB/ CFHC 138 HP Eng. (2008-on) <b>Lube</b> (71115562C)..... <b>P7415</b> <b>Fuel</b> (3C0127434)..... <b>PF46188</b> <b>Air</b> (1K0129620D)..... <b>PA4428</b>	Touareg 7L 3.2 V6 w/AZZ/ BAA/ BRS 217 HP Eng. (2003-2010) <b>Lube</b> (21115562A)..... <b>P7136</b> <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Air</b> (7L0129620A)..... <b>PA10279</b> <b>Cabin Air</b> (w/Charcoal) (7H0819631A)..... <b>PA10018</b>	
Scirocco 2.0 CR TDI w/CFGC 177 HP Eng. (2013-on) <b>Lube</b> (3L115562)..... <b>P40024</b> <b>Fuel</b> (3C0127434)..... <b>PF46188</b> <b>Air</b> (1K0129620D)..... <b>PA4428</b>		
Scirocco 2.0 CR TDI w/CFHB 136 HP Eng. (2010-on) <b>Lube</b> (3L115562)..... <b>P40024</b> <b>Fuel</b> (3C0127434)..... <b>PF46188</b> <b>Air</b> (1K0129620D)..... <b>PA4428</b>		


Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

VOLKSWAGEN European Light Duty Vehicles (cont'd)	VOLKSWAGEN European Light Duty Vehicles (cont'd)	VOLKSWAGEN European Light Duty Vehicles (cont'd)
Touareg 7P5 3.0 V6 TDI w/CASA/ CNRB/ CVWA 237 HP Eng. (2010-on) <b>Lube</b> (57115561M)..... <b>P40110</b> <b>Fuel</b> (06-2010 on) (7P6127177A). <b>PF46187</b> <b>Air</b> (7P0129620A)..... <b>PA10340</b> <b>Cabin Air</b> (7P0819631)..... <b>PA10018</b>	Touran 1.4 TSI EcoFuel w/CDGA 148 HP Eng. (2009-on) <b>Fuel</b> (1K0201051K)..... <b>BF46221</b> <b>Air</b> (1K0129620D)..... <b>PA4428</b>	Touran 2.0 TDI DPFw/AZV 134 HP Eng. (2003-2004) <b>Lube</b> (3L115562)..... <b>P40024</b> <b>Fuel</b> (1K0127434A)..... <b>PF9872</b> <b>Air</b> (1K0129620D)..... <b>PA4428</b>
Touareg 7P5 3.0 V6 TDI w/CASD/ CJMA 201 HP Eng. (2010-on) <b>Lube</b> (57115561M)..... <b>P40110</b> <b>Fuel</b> (06-2010 on) (7P6127177A). <b>PF46187</b> <b>Air</b> (7P0129620A)..... <b>PA10340</b> <b>Cabin Air</b> (7P0819631)..... <b>PA10018</b>	Touran 1.6 TDI w/CAYC 103 HP Eng. (2010-on) <b>Lube</b> (3L115562)..... <b>P40024</b> <b>Fuel</b> (3C0127434)..... <b>PF46188</b> <b>Air</b> (1K0129620D)..... <b>PA4428</b>	Touran 2.0 FSI w/AXW/ BLR/ BLX/ BVY/ BVX 148 HP Eng. (2003-06) <b>Lube</b> (6D115562)..... <b>P7399</b> <b>Fuel</b> (6X0201511B)..... <b>BF1185</b> <b>Air</b> (1F0129620)..... <b>PA10113</b> <b>Air</b> (1K0129620D)..... <b>PA4428</b>
Touareg 7P5 3.0 V6 TDI w/CJGD/ CRCA 242 HP Eng. (2011-on) <b>Lube</b> (59198405)..... <b>P40111</b> <b>Fuel</b> (06-2010 on) (7P6127177A). <b>PF46187</b> <b>Air</b> (7P0129620A)..... <b>PA10340</b> <b>Cabin Air</b> (7P0819631)..... <b>PA10018</b>	Touran 1.6 FSI w/BAG/ BLF/ BLP 114 HP Eng. (2003-2006) <b>Fuel</b> (6X0201511B)..... <b>BF1185</b>	Touran 2.0 EcoFuel w/BSX 107 HP Eng. (2006-2009) <b>Lube</b> (6A115561B)..... <b>B178</b> <b>Fuel</b> (6Q0201051C)..... <b>BF9805</b> <b>Fuel</b> (1K0201051C)..... <b>BF46221</b> <b>Air</b> (1F0129620)..... <b>PA10113</b> <b>Air</b> (1K0129620D)..... <b>PA4428</b>
Touareg 7P5 3.0 V6 TSI Hybrid w/CGEA/ CGFA 328 HP Eng. (2010-on) <b>Lube</b> (6E115562A)..... <b>P7414</b> <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Air</b> (7P0129620A)..... <b>PA10340</b> <b>Cabin Air</b> (7P0819631)..... <b>PA10018</b>	Touran 1.6 w/BGU/ BSE/ BSF 101 HP Eng. (2003-2010) <b>Lube</b> (6A115561B)..... <b>B178</b> <b>Fuel</b> (6X0201511B)..... <b>BF1185</b> <b>Air</b> (1F0129620)..... <b>PA10113</b>	Transporter T4 1.9 D w/1X Eng. (09/90-06/03) <b>Lube</b> (69115561)..... <b>B114</b> <b>Fuel</b> (191127401A)..... <b>BF1215</b> <b>Air</b> (44129620)..... <b>PA4693</b> <sup>90</sup> <b>Cab Air</b> (703819989)..... <b>PA10020</b> <sup>90</sup>
Touareg 7P5 3.6 V6 FSI w/CGRA 276 HP Eng. (2010-on) <b>Lube</b> (21115562A)..... <b>P7136</b> <b>Fuel</b> (N/S)..... <b>N/S</b> <b>Air</b> (7P0129620A)..... <b>PA10340</b> <b>Cabin Air</b> (7P0819631)..... <b>PA10018</b>	Touran 1.9 TDI w/BRU/ BXF/ BXJ 89 HP Eng. (2004-2010) <b>Lube</b> (71115562C)..... <b>P7415</b> <b>Fuel</b> (1K0127434A)..... <b>PF9872</b> <b>Air</b> (1K0129620D)..... <b>PA4428</b>	Transporter T4 1.9 D (Export) w/1X Eng. (09/90-06/03) <b>Lube</b> (69115561)..... <b>B114</b> <b>Fuel</b> (191127401A)..... <b>BF1215</b> <b>Air</b> (44129620A)..... <b>PA2772</b> <b>Cab Air</b> (703819989)..... <b>PA10020</b> <sup>90</sup>
Touareg 7P5 4.2 FSI w/CGNA 360 HP Eng. (2011-on) <b>Lube</b> (79198405E)..... <b>P40103</b> <b>Fuel</b> (6X0201511B)..... <b>BF1185</b> <b>Air</b> (7P0129620A)..... <b>PA10340</b> <b>Cabin Air</b> (7P0819631)..... <b>PA10018</b>	Touran 1.9 TDI w/AVQ 99 HP Eng. (2003-2004) <b>Lube</b> (71115562C)..... <b>P7415</b> <b>Fuel</b> (1K0127434A)..... <b>PF9872</b> <b>Air</b> (1K0129620D)..... <b>PA4428</b>	Transporter T4 1.9 TD w/ABL Eng. (07/96-06/03) <b>Fuel</b> (191127401A)..... <b>BF1215</b> <b>Cab Air</b> (703819989)..... <b>PA10020</b> <sup>90</sup>
Touareg 7P5 4.2 V8 TDI w/CKDA 335 HP Eng. (2010-on) <b>Lube</b> (57115561M)..... <b>P40110</b> <b>Fuel</b> (06-2010 on) (7P6127177A). <b>PF46187</b> <b>Air</b> (7P0129620A)..... <b>PA10340</b> <b>Cabin Air</b> (7P0819631)..... <b>PA10018</b>	Touran 2.0 TDI DPF w/BMN 168 HP Eng. (2005-2010) <b>Lube</b> (71115562C)..... <b>P7415</b> <b>Fuel</b> (3C0127434)..... <b>PF46188</b> <b>Air</b> (1K0129620D)..... <b>PA4428</b>	Transporter T4 2.0 w/AAC Eng. (08/99-06/03) <b>Lube</b> (56115561)..... <b>B178</b> <b>Fuel</b> (1H0201511)..... <b>BF1195</b> <b>Cab Air</b> (703819989)..... <b>PA10020</b> <sup>90</sup>
Touran 1.2 TSI w/CBZB 103 HP Eng. (2010-on) <b>Fuel</b> (1K0201051K)..... <b>BF46221</b> <b>Air</b> (1F0129620)..... <b>PA10113</b>	Touran 2.0 TDI DPF w/BMM 138 HP Eng. (2005-2010) <b>Lube</b> (71115562C)..... <b>P7415</b> <b>Fuel</b> (3C0127434)..... <b>PF46188</b> <b>Air</b> (1K0129620D)..... <b>PA4428</b>	Transporter T4 2.0 w/AAC Eng. (09/95-07/99) <b>Lube</b> (56115561)..... <b>B178</b> <b>Fuel</b> (1H0201511)..... <b>BF1195</b> <b>Cab Air</b> (703819989)..... <b>PA10020</b> <sup>90</sup>
Touran 1.4 TSI EcoFuel w/BLG/ CAVB 168 HP Eng. (2007-on) <b>Fuel</b> (6Q0201051C)..... <b>BF9805</b> <b>Fuel</b> (1K0201051C)..... <b>BF46221</b> <b>Air</b> (1K0129620D)..... <b>PA4428</b>	Touran 2.0 TDI w/CFJB 130 HP Eng. (2013-on) <b>Lube</b> (3L115562)..... <b>P40024</b> <b>Fuel</b> (3C0127434)..... <b>PF46188</b> <b>Air</b> (1K0129620D)..... <b>PA4428</b>	Transporter T4 2.0 (Export) w/AAC Eng. (07/90-07/99) <b>Lube</b> (56115561)..... <b>B178</b> <b>Fuel</b> (BF7736)..... <b>BF7736</b> <b>Air</b> (44129620A)..... <b>PA2772</b> <b>Cab Air</b> (703819989)..... <b>PA10020</b> <sup>90</sup>
Touran 1.4 TSI EcoFuel w/BMY/ CAVC 138 HP Eng. (2006-on) <b>Fuel</b> (6Q0201051C)..... <b>BF9805</b> <b>Fuel</b> (1K0201051C)..... <b>BF46221</b> <b>Air</b> (1K0129620D)..... <b>PA4428</b>	Touran 2.0 TDI DPFw/BKD 138 HP Eng. (2004-2010) <b>Lube</b> (3L115562)..... <b>P40024</b> <b>Fuel</b> (1K0127434A)..... <b>PF9872</b> <b>Air</b> (1K0129620D)..... <b>PA4428</b>	Transporter T4 2.0 (Export) w/AAC Eng. (08/99-06/03) <b>Lube</b> (56115561)..... <b>B178</b> <b>Fuel</b> ..... <b>BF7736</b> <b>Air</b> (44129620A)..... <b>PA2772</b> <b>Cab Air</b> (703819989)..... <b>PA10020</b> <sup>90</sup>

<sup>90</sup> Obsolete Pending.

Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

VOLKSWAGEN European Light Duty Vehicles (cont'd)	VOLKSWAGEN European Light Duty Vehicles (cont'd)	VOLKSWAGEN European Light Duty Vehicles (cont'd)
Transporter T4 2.4 D w/AAB Eng. (09/95-06/03) <b>Fuel</b> (191127401A)..... <b>BF1215</b> <b>Cab Air</b> (703819989)..... <b>PA10020</b> <sup>90</sup>	Transporter T5 1.9 TDI w/AXC Eng. (05/03-12/09) <b>Lube</b> (45115466)..... <b>P7415</b> <b>Cabin Air</b> (w/o Charcoal) (7H0819631)..... <b>PA10034</b> <b>Cabin Air</b> (w/Charcoal) (7H0819631A)..... <b>PA10018</b>	Transporter T5 2.0 TDI w/CFCA Eng. (09/09-on) <b>Cabin Air</b> (w/o Charcoal) (7H0819631)..... <b>PA10034</b> <b>Cabin Air</b> (w/Charcoal) (7H0819631A)..... <b>PA10018</b>
Transporter T4 2.4 D (Export) w/AAB Eng. (10/90-06/03) <b>Fuel</b> (191127401A)..... <b>BF1215</b> <b>Air</b> (44129620A)..... <b>PA2772</b> <b>Cab Air</b> (703819989)..... <b>PA10020</b> <sup>90</sup>	Transporter T5 1.9 TDI w/BRR Eng. (01/06-12/09) <b>Lube</b> (45115466)..... <b>P7415</b> <b>Cabin Air</b> (w/o Charcoal) (7H0819631)..... <b>PA10034</b> <b>Cabin Air</b> (w/Charcoal) (7H0819631A)..... <b>PA10018</b>	Transporter T5 2.0 TDI (7E, 7F) w/CAAA, CFCA Eng. (09/09-on) <b>Lube</b> (3L115466)..... <b>P40024</b> <b>Cabin Air</b> (w/o Charcoal) (7H0819631)..... <b>PA10034</b> <b>Cabin Air</b> (w/Charcoal) (7H0819631A)..... <b>PA10018</b>
Transporter T4 2.4 SD Diesel w/AJA Eng. (05/98-06/03) <b>Fuel</b> (191127401A)..... <b>BF1215</b> <b>Cab Air</b> (703819989)..... <b>PA10020</b> <sup>90</sup>	Transporter T5 1.9 TDI w/BRS Eng. (01/06-12/09) <b>Lube</b> (45115466)..... <b>P7415</b> <b>Cabin Air</b> (w/o Charcoal) (7H0819631)..... <b>PA10034</b> <b>Cabin Air</b> (w/Charcoal) (7H0819631A)..... <b>PA10018</b>	Transporter T5 2.0 TDI (7E, 7F) w/CAAB, CAAC, CCHA Eng. (09/09-on) <b>Lube</b> (3L115466)..... <b>P40024</b> <b>Cabin Air</b> (w/o Charcoal) (7H0819631)..... <b>PA10034</b> <b>Cabin Air</b> (w/Charcoal) (7H0819631A)..... <b>PA10018</b>
Transporter T4 2.5 w/AAF-ACU-AEN Eng. (09/95-06/03) <b>Fuel</b> (1H0201511)..... <b>BF1195</b> <b>Cab Air</b> (703819989)..... <b>PA10020</b> <sup>90</sup>	Transporter T5 1.9 TDI w/BRS Eng. (01/06-12/09) <b>Lube</b> (45115466)..... <b>P7415</b> <b>Cabin Air</b> (w/o Charcoal) (7H0819631)..... <b>PA10034</b> <b>Cabin Air</b> (w/Charcoal) (7H0819631A)..... <b>PA10018</b>	Transporter T5 2.0 TDI (7E, 7F) w/CAAD Eng. (05/11-on) <b>Lube</b> (3L115466)..... <b>P40024</b> <b>Cabin Air</b> (w/o Charcoal) (7H0819631)..... <b>PA10034</b> <b>Cabin Air</b> (w/Charcoal) (7H0819631A)..... <b>PA10018</b>
Transporter T4 2.5 w/AET-AEU Eng. (08/96-06/03) <b>Fuel</b> (1H0201511)..... <b>BF1195</b> <b>Cab Air</b> (703819989)..... <b>PA10020</b> <sup>90</sup>	Transporter T5 2.0 w/AXA Eng. (05/03-on) <b>Lube</b> (56115561)..... <b>B178</b> <b>Fuel</b> (1J0201511A)..... <b>BF7670</b> <b>Cabin Air</b> (w/o Charcoal) (7H0819631)..... <b>PA10034</b> <b>Cabin Air</b> (w/Charcoal) (7H0819631A)..... <b>PA10018</b>	Transporter T5 2.0 TDI (7E, 7F) w/CAAE, CCHB Eng. (05/10-on) <b>Lube</b> (3L115466)..... <b>P40024</b> <b>Cabin Air</b> (w/o Charcoal) (7H0819631)..... <b>PA10034</b> <b>Cabin Air</b> (w/Charcoal) (7H0819631A)..... <b>PA10018</b>
Transporter T4 2.5 (Export) w/AAF-ACU-AEN Eng. (10/90-06/03) <b>Fuel</b> (1H0201511)..... <b>BF1195</b> <b>Air</b> (44129620A)..... <b>PA2772</b> <b>Cab Air</b> (703819989)..... <b>PA10020</b> <sup>90</sup>	Transporter T5 2.0 TDI w/AXA Eng. (05/03-on) <b>Lube</b> (56115561)..... <b>B178</b> <b>Fuel</b> (1J0201511A)..... <b>BF7670</b> <b>Cabin Air</b> (w/o Charcoal) (7H0819631)..... <b>PA10034</b> <b>Cabin Air</b> (w/Charcoal) (7H0819631A)..... <b>PA10018</b>	Transporter T5 2.0 TSI w/CJKA Eng. (06/11-on) <b>Lube</b> (6H115561)..... <b>B7452</b> <b>Fuel</b> (1K0201051C)..... <b>BF46221</b> <b>Cabin Air</b> (w/o Charcoal) (7H0819631)..... <b>PA10034</b> <b>Cabin Air</b> (w/Charcoal) (7H0819631A)..... <b>PA10018</b>
Transporter T4 2.5 TDI TD w/ACV-AUF-AYC Eng. (09/95-06/03) <b>Fuel</b> (191127401A)..... <b>BF1215</b> <b>Cab Air</b> (703819989)..... <b>PA10020</b> <sup>90</sup>	Transporter T5 2.0 TDI w/CAAA, CAAB, CAAC, CCHA Eng. (09/09-on) <b>Lube</b> (3L115466)..... <b>P40024</b> <b>Cabin Air</b> (w/o Charcoal) (7H0819631)..... <b>PA10034</b> <b>Cabin Air</b> (w/Charcoal) (7H0819631A)..... <b>PA10018</b>	Transporter T5 2.0 TSI w/CJKB Eng. (07/12-on) <b>Lube</b> (6H115561)..... <b>B7452</b> <b>Fuel</b> (1K0201051C)..... <b>BF46221</b> <b>Cabin Air</b> (w/o Charcoal) (7H0819631)..... <b>PA10034</b> <b>Cabin Air</b> (w/Charcoal) (7H0819631A)..... <b>PA10018</b>
Transporter T4 2.5 TDI TD w/AHY Eng. (05/98-06/03) <b>Fuel</b> (191127401A)..... <b>BF1215</b> <b>Cab Air</b> (703819989)..... <b>PA10020</b> <sup>90</sup>	Transporter T5 2.0 TDI w/CAAD Eng. (09/09-on) <b>Lube</b> (3L115466)..... <b>P40024</b> <b>Cabin Air</b> (w/o Charcoal) (7H0819631)..... <b>PA10034</b> <b>Cabin Air</b> (w/Charcoal) (7H0819631A)..... <b>PA10018</b>	Transporter T5 2.0 TSI (7E, 7F) w/CJKA Eng. (06/11-on) <b>Lube</b> (45115466)..... <b>P7415</b> <b>Fuel</b> (1K0201051C)..... <b>BF46221</b> <b>Cabin Air</b> (w/o Charcoal) (7H0819631)..... <b>PA10034</b> <b>Cabin Air</b> (w/Charcoal) (7H0819631A)..... <b>PA10018</b>
Transporter T4 2.5 TDI TD w/AJT-AYY Eng. (05/98-06/03) <b>Fuel</b> (191127401A)..... <b>BF1215</b> <b>Cab Air</b> (703819989)..... <b>PA10020</b> <sup>90</sup>	Transporter T5 2.0 TDI w/CAAE, CCHB Eng. (09/09-on) <b>Lube</b> (3L115466)..... <b>P40024</b> <b>Cabin Air</b> (w/o Charcoal) (7H0819631)..... <b>PA10034</b> <b>Cabin Air</b> (w/Charcoal) (7H0819631A)..... <b>PA10018</b>	
Transporter T4 2.8 w/AES Eng. (11/95-06/03) <b>Lube</b> (21115561B)..... <b>P7136</b> <b>Fuel</b> (1H0201511)..... <b>BF1195</b> <b>Cab Air</b> (703819989)..... <b>PA10020</b> <sup>90</sup>		
Transporter T4 2.8 V6 w/AMV Eng. (06/00-06/03) <b>Lube</b> (45115466)..... <b>P7415</b> <b>Fuel</b> (1H0201511)..... <b>BF1195</b> <b>Cab Air</b> (703819989)..... <b>PA10020</b> <sup>90</sup>		
Transporter T5 1.9 TDI w/AXB Eng. (05/03-12/09) <b>Lube</b> (45115466)..... <b>P7415</b> <b>Cabin Air</b> (w/o Charcoal) (7H0819631)..... <b>PA10034</b> <b>Cabin Air</b> (w/Charcoal) (7H0819631A)..... <b>PA10018</b>		

<sup>90</sup> Obsolete Pending.

Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

VOLKSWAGEN European Light Duty Vehicles (cont'd)	VOLKSWAGEN European Light Duty Vehicles (cont'd)	VOLKSWAGEN Trucks, Vans (cont'd)
Transporter T5 2.0 TSI (7E, 7F) w/CJKB Eng. (07/12-on) Lube (45115466)..... P7415 Fuel (1K0201051C)..... BF46221 Cabin Air (w/o Charcoal) (7H0819631)..... PA10034 Cabin Air (w/Charcoal) (7H0819631A)..... PA10018	Transporter T5 3.2 V6 (7H, 7HJ) w/BKK, CFLA Engs. (11/03-12/09) Lube (21115561B)..... P7136 Fuel (1J0201511A)..... BF7670 Cabin Air (w/o Charcoal) (7H0819631)..... PA10034 Cabin Air (w/Charcoal) (7H0819631A)..... PA10018	26.220 w/Cummins 6CTAA Eng. (Cont'd) Fuel (Fleetguard FF42002)..... BF790 O. Air (2S0129620)..... RS5627 I. Air (2S0129620A)..... RS5628 Steering (Fleetguard HF6162)..... P106-HD
Transporter T5 2.5 TDI w/AXD Eng. (05/03-on) Lube (45115466)..... P7415 Cabin Air (w/o Charcoal) (7H0819631)..... PA10034 Cabin Air (w/Charcoal) (7H0819631A)..... PA10018	Transporter T5 T26 w/2,0 TDI EURO V Eng. (2009-on) Lube (3L115466)..... P40024 Cabin Air (w/o Charcoal) (7H0819631)..... PA10034 Cabin Air (w/Charcoal) (7H0819631A)..... PA10018	26.260 w/Cummins 6CTAA Eng. Dual-Flow Lube (Standard) (3318853)..... BD103 + Dual-Flow Lube (Upgrade) (2T0115561)..... BD7309 Fuel/Water Separator (w/Drain) (2TD127491A)..... BF1249 Fuel/Water Separator (Open End for Bowl) (2TD127491A)..... BF1249-O Fuel/Water Separator (w/Drain & Sensor Port) (2TD127491A)..... BF1249-SP Fuel/Water Separator (w/Drain & Sensor Port, High Efficiency Version) (2TD127491A)..... BF1393-SP Fuel (Fleetguard FF42002)..... BF790 O. Air (2S0129620)..... RS5627 I. Air (2S0129620A)..... RS5628 Steering (Fleetguard HF6162)..... P106-HD
Transporter T5 2.5 TDI w/AXD, AXE, BLJ Engs. (05/03-on) Lube (45115466)..... P7415 Cabin Air (w/o Charcoal) (7H0819631)..... PA10034 Cabin Air (w/Charcoal) (7H0819631A)..... PA10018	Transporter T5 T28 w/2,0 TDI EURO V Eng. (2009-on) Lube (3L115466)..... P40024 Cabin Air (w/o Charcoal) (7H0819631)..... PA10034 Cabin Air (w/Charcoal) (7H0819631A)..... PA10018	26.260 E w/6.12 TCE Eng. Lube (Fleetguard LF3346)..... BT349 Fuel/Water Separator (2R0127177D)..... BF1249 Fuel Spin-on (2R0127177E)..... BF46230 O. Air (2S0129620B)..... RS5627 I. Air (2S0129620A)..... RS5628 Air Dryer (2TB607439)..... BA5374 Steering (Fleetguard HF6162)..... P106-HD
Transporter T5 2.5 TDI w/AXE Eng. (05/03-on) Lube (45115466)..... P7415 Cabin Air (w/o Charcoal) (7H0819631)..... PA10034 Cabin Air (w/Charcoal) (7H0819631A)..... PA10018	Transporter T5 T30 w/2,0 TDI EURO V Eng. (2009-on) Lube (3L115466)..... P40024 Cabin Air (w/o Charcoal) (7H0819631)..... PA10034 Cabin Air (w/Charcoal) (7H0819631A)..... PA10018	26.300 w/Cummins 6CTAA Eng. Dual-Flow Lube (Standard) (3318853)..... BD103 + Dual-Flow Lube (Upgrade) (2T0115561)..... BD7309 Fuel/Water Separator (w/Drain) (2TD127491A)..... BF1249 Fuel/Water Separator (Open End for Bowl) (2TD127491A)..... BF1249-O Fuel/Water Separator (w/Drain & Sensor Port) (2TD127491A)..... BF1249-SP Fuel/Water Separator (w/Drain & Sensor Port, High Efficiency Version) (2TD127491A)..... BF1393-SP Fuel (Fleetguard FF42002)..... BF790 O. Air (2S0129620B)..... RS5627 I. Air (2S0129620A)..... RS5628 Steering (Fleetguard HF6162)..... P106-HD
Transporter T5 2.5 TDI w/BLJ Eng. (05/03-on) Lube (45115466)..... P7415 Cabin Air (w/o Charcoal) (7H0819631)..... PA10034 Cabin Air (w/Charcoal) (7H0819631A)..... PA10018	Transporter T5 T32 w/2,0 TDI EURO V Eng. (2009-on) Lube (3L115466)..... P40024 Cabin Air (w/o Charcoal) (7H0819631)..... PA10034 Cabin Air (w/Charcoal) (7H0819631A)..... PA10018	26.310 w/Cummins 6CTAA Eng. Dual-Flow Lube (Standard) (3318853)..... BD103 + Dual-Flow Lube (Upgrade) (2T0115561)..... BD7309 Fuel/Water Separator (w/Drain) (2TD127491A)..... BF1249 Fuel/Water Separator (Open End for Bowl) (2TD127491A)..... BF1249-O
Transporter T5 2.5 TSI (7H, 7J) w/AXD, AXE, BLJ, BNZ, BPC Engs. (05/03-12/09) Lube (45115466)..... P7415 Cabin Air (w/o Charcoal) (7H0819631)..... PA10034 Cabin Air (w/Charcoal) (7H0819631A)..... PA10018		
Transporter T5 3.2 V6 w/BLD-BKK Eng. (05/03-on) Lube (21115561B)..... P7136 Fuel (1J0201511A)..... BF7670 Cabin Air (w/o Charcoal) (7H0819631)..... PA10034 Cabin Air (w/Charcoal) (7H0819631A)..... PA10018		
Transporter T5 3.2 V6 (7H, 7HJ) w/BDL Eng. (05/03-12/09) Lube (21115561B)..... P7136 Fuel (1J0201511A)..... BF7670 Cabin Air (w/o Charcoal) (7H0819631)..... PA10034 Cabin Air (w/Charcoal) (7H0819631A)..... PA10018	<b>VOLKSWAGEN Trucks, Vans</b> 26.220 w/Cummins 6CTAA Eng. Dual-Flow Lube (Standard) (3318853)..... BD103 + Dual-Flow Lube (Upgrade) (2T0115561)..... BD7309 Fuel/Water Separator (w/Drain) (2TD127491A)..... BF1249 Fuel/Water Separator (Open End for Bowl) (2TD127491A)..... BF1249-O Fuel/Water Separator (w/Drain & Sensor Port) (2TD127491A)..... BF1249-SP Fuel/Water Separator (w/Drain & Sensor Port, High Efficiency Version) (2TD127491A)..... BF1393-SP	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

VOLKSWAGEN Trucks, Vans (cont'd)	VOLVO Buses (cont'd)	VOLVO Buses (cont'd)
26.310 w/Cummins 6CTAA Eng. (Cont'd)	7350 w/D7C Eng. (Cont'd)	9700 w/D13 (12.8L) Eng. (2019)
Fuel/Water Separator (w/Drain & Sensor Port) (2TD127491A)..... <b>BF1249-SP</b>	Fuel/Water Separator (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b>	F-F Lube (21707133)..... [2] <b>B76</b>
Fuel/Water Separator (w/Drain & Sensor Port, High Efficiency Version) (2TD127491A)..... <b>BF1393-SP</b>	Fuel/Water Separator (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b>	B-P Lube (21707132)..... <b>B7409</b>
Fuel (Fleetguard FF42002)..... <b>BF790</b>		Fuel (22474709)..... <b>BF46117</b>
O. Air (2S0129620)..... <b>RS5627</b>	7550 w/N12 Eng.	Coolant (21937327)..... <b>B5145</b>
S. Eng. Air (2S0129620A)..... <b>RS5628</b>	Fuel/Water Separator (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b>	Diesel Exhaust Fluid (Pump) (21516229)..... <b>PE17000</b>
Steering (Fleetguard HF6162)..... <b>P106-HD</b>	Fuel/Water Separator (With Bowl) (Mann WK1060/1)..... <b>BF46072</b>	Diesel Exhaust Fluid (Tank Strainer) (82269261)..... <b>PE17001</b>
Constellation 26.390 w/Cummins ISL (Euro 5) Eng.	Fuel/Water Separator (With Drain) (Mann WK1060/1)..... <b>BF1329</b>	9700 w/D13 (12.8L) Eng. (2020)
Fuel/Water Separator (Fleetguard FS19727)..... <b>PF7895</b>	Fuel/Water Separator (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b>	F-F Lube (21707133)..... [2] <b>B76</b>
LT28, LT31, LT35 Vans w/2.4D Eng. (1982-on)	Fuel/Water Separator (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b>	B-P Lube (21707132)..... <b>B7409</b>
Some Lube..... <b>BT251</b>		Fuel (22474709)..... <b>BF46117</b>
In-Line Fuel/Water Separator..... <b>BF1215</b>	8500, 8700 w/DH12D Eng.	Coolant (21937327)..... <b>B5145</b>
Can-Type Fuel..... <b>BF825 +</b>	F-F Lube (Mann W11102/4)..... <b>B76 +</b>	9700, 9900 w/DH12D Eng.
Some Air..... <b>PA2792</b>	F-F Lube (Upgrade) (Mann W11102/20)..... <b>B76-SS +</b>	F-F Lube (Mann W11102/4)..... <b>B76 +</b>
Some Air..... <b>PA2845</b>	B-P Lube (Mann WP11102)..... <b>B7685</b>	F-F Lube (Upgrade) (Mann W11102/20)..... <b>B76-SS +</b>
LT28, LT35, LT46 Vans w/2.3L Eng.	Fuel (20430751)..... <b>BF7814</b>	B-P Lube (Mann WP11102)..... <b>B7685</b>
Lube (Mann HU727/1x)..... <b>P1419</b>	Fuel (22480372)..... <b>BF46161</b>	Fuel (20430751)..... <b>BF7814</b>
Fuel (Mann WK831)..... <b>BF1195</b>		Fuel (22480372)..... <b>BF46161</b>
Air (Mann C32338)..... <b>PA4600</b>	9700 w/D11K (Euro 6) Eng. (2014)	9900 w/D11K (Euro 6) Eng. (2013)
Air (High Capacity) (Mann C32338/1)..... <b>PA4601</b>	Fuel/Water Separator (Fleetguard FS20132)..... <b>BF46182-O</b>	Fuel/Water Separator (Fleetguard FS20132)..... <b>BF46182-O</b>
Cab Air (Mann CU3858)..... <b>PA4489</b>		B6 w/D60A, D60B, TD60A, TD60B Engs.
LT28, LT35, LT46 Vans w/2.5 TDI Eng.	9700 w/D13 (12.8L) Eng. (2009-17)	Lube (To S/N 47590) (469954).... <b>B975</b>
Lube (Mann HU726/2x)..... <b>P7308</b>	F-F Lube (21707133)..... [2] <b>B76 +</b>	Lube (S/N 47590-up) (4666343)... <b>B76 +</b>
Fuel (Mann WK8533)..... <b>BF7958</b>	F-F Lube (4787362)..... [2] <b>B76-SS +</b>	Lube (S/N 47590-up) (Upgrade).... <b>B76-SS +</b>
Air (Mann C32338)..... <b>PA4600</b>	B-P Lube (21707132)..... <b>B7409</b>	Fuel Spin-on (4669875)..... <b>BF988 +</b>
Air (High Capacity) (Mann C32338/1)..... <b>PA4601</b>	B-P Lube (4775565)..... <b>B7685</b>	517.5 mm Air (6777970)..... <b>PA2659</b>
Cab Air (Mann CU3858)..... <b>PA4489</b>	Fuel/Water Separator (Open End for Bowl) (20514654)..... <b>BF1366-O</b>	Breather (1082111)..... <b>PA2798</b>
Transporter 1600, 1700, 1800, 2000 Lube (1968-81)..... <b>B233</b>	Fuel (20430751)..... <b>BF7814</b>	B7 w/D70A, D70B, TD70A, TD70B, TD70E, TD70H Engs.
Transporter 4 (1990-on)	Fuel (22480372)..... <b>BF46161</b>	Lube Spin-on (469954)..... <b>B975</b>
Some Lube..... <b>B178</b>	Coolant (w/o Chemical) (21937327)..... <b>B5145</b>	F-F Lube Spin-on (466634)..... <b>B76 +</b>
Some Lube..... <b>BT251</b>	Coolant (w/8 Units BTE) (21388476)..... <b>BW5142</b>	F-F Lube Spin-on (Upgrade)..... <b>B76-SS +</b>
In-Line Fuel/Water Separator..... <b>BF1215</b>	9700 w/D13 (12.8L) Eng. (2018)	Opt. Fuel/Water Separator..... <b>BF1221 +</b>
Some Air..... <b>PA2772</b>	F-F Lube (21707133)..... [2] <b>B76 +</b>	Fuel Spin-on (243004)..... <b>BF988 +</b>
<b>VOLVO</b>	B-P Lube (21707132)..... <b>B7409</b>	Can-Type Fuel (236628)..... <b>BF825 +</b>
<b>Buses</b>	Severe Service F-F Lube (21707133)..... [2] <b>B76-SS +</b>	O. Air (476769)..... <b>PA2869</b>
7350 w/D7C Eng.	Fuel (22474709)..... <b>BF46117</b>	B 7R w/D7B260 Eng.
Fuel/Water Separator (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b>	Cab Air (20435801)..... <b>PA4681</b>	Fuel/Water Separator (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b>
Fuel/Water Separator (With Bowl) (Mann WK1060/1)..... <b>BF46072</b>	Coolant (21937327)..... <b>B5145</b>	Fuel/Water Separator (With Bowl) (Mann WK1060/1)..... <b>BF46072</b>
Fuel/Water Separator (With Drain) (Mann WK1060/1)..... <b>BF1329</b>	Trans. (21479106)..... <b>PT9417</b>	Fuel/Water Separator (With Drain) (Mann WK1060/1)..... <b>BF1329</b>
	Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	Fuel/Water Separator (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b>
	Diesel Exhaust Fluid (Filler Neck) (82269261)..... <b>PE17001</b>	Fuel/Water Separator (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b>
	Diesel Exhaust Fluid (Tank Filter) (21516229)..... <b>PE17000</b>	B9M
		Lube Spin-on (469954)..... <b>B975</b>
		Fuel Spin-on (4669875)..... <b>BF988 +</b>
		O. Air (16606196)..... <b>PA2707</b>
		Hyd. Spin-on (1193976)..... <b>BT230</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>VOLVO Buses (cont'd)</b>	<b>VOLVO Buses (cont'd)</b>	<b>VOLVO Buses (cont'd)</b>
B9M (Cont'd) Hyd. (Gear Box Ele.) (267518)..... <b>PT385 +</b>	B54 w/D50A, HD100A, THD100A, THD100D Engs. Lube Spin-on (423135)..... <b>B975</b> Opt. Fuel/Water Separator..... <b>BF1221 +</b> Fuel Spin-on (243004)..... <b>BF988 +</b> S. Fuel Ele. (233897)..... <b>PF950</b>	B725 w/D96AS, D96L Engs. S. Fuel Ele. (233898)..... <b>PF834</b>
B10 w/DH10A Eng. Lube (466634)..... <b>[2] B76 +</b> Air (1544449)..... <b>PA2774</b> Coolant (20532237)..... <b>BW5142</b> M.T. Trans. (3517857)..... <b>B132</b> A.T. Trans. (3098081)..... <b>PT8385</b> Steering (349619)..... <b>P106-HD</b>	B57, BB57 w/D70A, D70B, TD70A, TD70B, TD70E, TD70H Engs. Lube Spin-on (469954)..... <b>B975</b> F-F Lube Spin-on (466634)..... <b>B76 +</b> F-F Lube Spin-on (Upgrade)..... <b>B76-SS +</b> Opt. Fuel/Water Separator..... <b>BF1221 +</b> Can-Type Fuel (236628)..... <b>BF825 +</b> Fuel Spin-on (243004)..... <b>BF988 +</b> O. Air (476769)..... <b>PA2869</b>	B725, B755 S. Fuel Ele. (233897)..... <b>PF950</b>
B10, B10M w/TD100, TD100B, THD100EC Engs. Lube Spin-on (423135)..... <b>B975</b> F-F Lube Spin-on (466634)..... <b>B76 +</b> F-F Lube Spin-on (Upgrade)..... <b>B76-SS +</b> Opt. Fuel/Water Separator..... <b>BF1221 +</b> Fuel Spin-on (243004)..... <b>BF988 +</b> O. Air (1542743)..... <b>PA2707</b> Trans. (66175068)..... <b>PT385 +</b>	B58 w/HD100A, THD100A, THD100D Engs. Lube Spin-on (469954)..... <b>B975</b> Opt. Fuel/Water Separator..... <b>BF1221 +</b> S. Fuel Ele. (233897)..... <b>PF950</b> Fuel Spin-on (4669875)..... <b>BF988 +</b> 262.7 mm O. Air (476769)..... <b>PA2869</b>	B1200 w/D70B Eng. Lube Spin-on (423135)..... <b>B975</b> Opt. Fuel/Water Separator..... <b>BF1221 +</b> Fuel Spin-on (4669875)..... <b>BF988 +</b> Air (823701)..... <b>PA2771</b>
B10M Lube Spin-on (469954)..... <b>B975</b> Fuel Spin-on (4669875)..... <b>BF988 +</b> O. Air (16606196)..... <b>PA2707</b> Hyd. (Gear Box Ele.) (267518)..... <b>PT385 +</b> Hyd. Spin-on (1193976)..... <b>BT230</b>	B59 w/HD100A, THD100A Engs. Lube Spin-on (423135)..... <b>B975</b> Opt. Fuel/Water Separator..... <b>BF1221 +</b> S. Fuel Ele. (233897)..... <b>PF950</b> Fuel Spin-on (241672)..... <b>BF988 +</b> 262.7 mm O. Air (476769)..... <b>PA2869</b>	C10M F-F Lube (4666343)..... <b>B76 +</b> F-F Lube (Upgrade)..... <b>B76-SS +</b> B-P Lube (477556)..... <b>B7685</b> Fuel Spin-on (2430049)..... <b>BF988 +</b> O. Air (16606196)..... <b>PA2707</b> Cab Air (15845753)..... <b>PA3414</b>
B10R w/THD100DB Eng. Lube Spin-on (469954)..... <b>B975</b> F-F Lube Spin-on (466634)..... <b>B76 +</b> F-F Lube Spin-on (Upgrade)..... <b>B76-SS +</b> Fuel Spin-on (4669875)..... <b>BF988 +</b> Trans. (66175068)..... <b>PT385 +</b> Hyd. (Gear Box Ele.) (267518)..... <b>PT385 +</b> Hyd. Spin-on (1193976)..... <b>BT230</b>	B59 Lube Spin-on..... <b>B975</b> Opt. Fuel/Water Separator..... <b>BF1221 +</b> Fuel Spin-on..... <b>BF988 +</b> Air..... <b>PA2847</b>	City Bus w/THD100EA Eng. Lube Spin-on (4231353)..... <b>B975</b> Opt. Fuel/Water Separator..... <b>BF1221 +</b> Fuel Spin-on (2430049)..... <b>BF988 +</b>
B10-12 Fuel/Water Separator (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> Fuel/Water Separator (With Bowl) (Mann WK1060/1)..... <b>BF46072</b> Fuel/Water Separator (With Drain) (Mann WK1060/1)..... <b>BF1329</b> Fuel/Water Separator (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b> Fuel/Water Separator (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b>	B615 w/D67A Eng. Fuel Ele. (7078472)..... <b>PF838</b>	V 12 Fuel/Water Separator (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> Fuel/Water Separator (With Bowl) (Mann WK1060/1)..... <b>BF46072</b> Fuel/Water Separator (With Drain) (Mann WK1060/1)..... <b>BF1329</b> Fuel/Water Separator (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b> Fuel/Water Separator (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b>
9900 w/D11K (Euro 6) Eng. (2013) Fuel/Water Separator (Fleetguard FS20132)..... <b>BF46182-O</b>	B615 w/VDC Eng. S. Fuel Ele. (233897)..... <b>PF950</b>	<b>VOLVO Engines</b>
B54 w/D50, TD50 Engs. Lube Spin-on (469954)..... <b>B975</b> Fuel Spin-on (4669875)..... <b>BF988 +</b> S. Fuel Ele. (233897)..... <b>PF950</b> O. Air (476769)..... <b>PA2869</b>	B635 w/VDF, D96AS Engs. 142.9 mm P. Fuel..... <b>F950-F</b> 141.3 mm S. Fuel (233897)..... <b>PF950</b> 114.3 mm P. Fuel (702582)..... <b>F953-F</b> 108.7 mm S. Fuel (233988)..... <b>PF834</b>	9A, V9A (9.4L) F-F Lube (478736-2)..... <b>[2] B76-SS +</b> B-P Lube (477556-5)..... <b>B7685</b> Fuel (20430751)..... <b>BF7814</b> Fuel (22480372)..... <b>BF46161</b>
	B655 w/D96AS, D96L Engs. S. Fuel Ele. (233898)..... <b>PF834</b>	12D Series F-F Lube (478736-2)..... <b>[2] B76-SS +</b> B-P Lube (477556-5)..... <b>B7685</b> Fuel (20430751)..... <b>BF7814</b> Fuel (22480372)..... <b>BF46161</b>
	B655 S. Fuel Ele. (233897)..... <b>PF950</b>	D6A F-F Lube..... <b>B76 +</b> F-F Lube (Upgrade)..... <b>B76-SS +</b> B-P Lube..... <b>B7685</b> Fuel..... <b>BF988 +</b>
	B705 w/TD47A Eng. S. Fuel Ele. (233897)..... <b>PF950</b>	D6B F-F Lube..... <b>B76 +</b> F-F Lube (Upgrade)..... <b>B76-SS +</b> B-P Lube..... <b>B7685</b> Fuel/Water Separator (20386080)..... <b>BF1398-O</b> Fuel..... <b>BF7644</b>
	B715 w/D67A Eng. Fuel Ele. (7078472)..... <b>PF838</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).




VOLVO Engines (cont'd)	VOLVO Engines (cont'd)	VOLVO Engines (cont'd)
<b>D7A</b>	<b>D12, D12D (Cont'd)</b>	<b>D13 (12.8L) (Cont'd)</b>
F-F Lube..... B76 +	<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (20514654).. <b>BF1366-O</b>	<b>Coolant (w/o Chemical)</b> (21937327)..... <b>B5145</b>
F-F Lube (Upgrade)..... <b>B76-SS +</b>	Fuel (8193841)..... <b>BF7653</b>	<b>D13A</b>
B-P Lube..... <b>B7685</b>	Fuel (D12D Eng.) (20430751)..... <b>BF7814</b>	F-F Lube..... <b>B76 +</b>
Fuel/Water Separator..... <b>BF1329</b>	Fuel (D12D Eng.) (22480372)..... <b>BF46161</b>	F-F Lube (Upgrade)..... <b>B76-SS +</b>
Fuel..... <b>BF7644</b>	<b>Coolant (Long Life Coolant)</b> (3969696)..... <b>B5144</b>	B-P Lube..... <b>B7685</b>
<b>D7C</b>	<b>Coolant (Ext. Service Coolant)</b> (20458771)..... <b>B5145</b>	<b>Fuel/Water Separator</b> (20879812)..... <b>BF1387-O</b>
F-F Lube..... <b>B76 +</b>	<b>Coolant (w/8 Units BTE)</b> (3945411)..... <b>BW5142</b>	<b>Fuel/Water Separator</b> ..... <b>BF1366-O</b>
F-F Lube (Upgrade)..... <b>B76-SS +</b>		Fuel..... <b>BF7814</b>
B-P Lube..... <b>B7685</b>		<b>D16 (16.1L)</b>
Fuel/Water Separator..... <b>BF1329</b>	<b>D12A</b>	F-F Lube (478736-2)..... <b>[2] B76-SS +</b>
Fuel..... <b>BF7644</b>	F-F Lube..... <b>B76 +</b>	F-F Lube (21707133)..... <b>[2] B76 +</b>
<b>D7E</b>	F-F Lube (Upgrade)..... <b>B76-SS +</b>	B-P Lube (21707132)..... <b>B7409</b>
F-F Lube (20998807)..... <b>P7329</b>	B-P Lube..... <b>B7685</b>	B-P Lube (477556-5)..... <b>B7685</b>
Fuel/Water Separator (20853583)..... <b>BF1388-O</b>	Fuel/Water Separator..... <b>BF1329</b>	<b>Fuel/Water Separator (Open End</b> for Bowl) (20514654)..... <b>BF1366-O</b>
Fuel..... <b>PF7938</b>	Fuel..... <b>BF7644</b>	<b>Single Fuel (20430751)..... BF7814</b>
<b>D9A</b>	<b>Coolant..... BW5141</b>	<b>Single Fuel (22480372)..... BF46161</b>
F-F Lube..... <b>B76 +</b>	<b>D12B</b>	<b>Coolant (21388476)..... BW5142</b>
F-F Lube (Upgrade)..... <b>B76-SS +</b>	F-F Lube..... <b>B76 +</b>	<b>Coolant (w/o Chemical)</b> (21937327)..... <b>B5145</b>
B-P Lube..... <b>B7685</b>	F-F Lube (Upgrade)..... <b>B76-SS +</b>	<b>D16A</b>
Fuel/Water Separator (20381204)..... <b>BF1389-O</b>	B-P Lube..... <b>B7685</b>	F-F Lube..... <b>B76 +</b>
Fuel/Water Separator (20450423)..... <b>BF1390-O</b>	Fuel/Water Separator..... <b>BF1329</b>	F-F Lube (Upgrade)..... <b>B76-SS +</b>
Fuel..... <b>BF7814</b>	Fuel..... <b>BF7644</b>	B-P Lube..... <b>B7685</b>
Coolant..... <b>BW5141</b>	<b>Coolant..... BW5141</b>	Fuel/Water Separator..... <b>BF1349</b>
<b>D9B</b>	<b>D12C</b>	Fuel..... <b>BF988 +</b>
F-F Lube..... <b>B76 +</b>	F-F Lube..... <b>B76 +</b>	Coolant..... <b>BW5141</b>
F-F Lube (Upgrade)..... <b>B76-SS +</b>	F-F Lube (Upgrade)..... <b>B76-SS +</b>	<b>D16B</b>
B-P Lube..... <b>B7685</b>	B-P Lube..... <b>B7685</b>	F-F Lube..... <b>B76 +</b>
Fuel/Water Separator..... <b>BF1366-O</b>	Fuel/Water Separator..... <b>BF1349</b>	F-F Lube (Upgrade)..... <b>B76-SS +</b>
Fuel..... <b>BF7814</b>	Fuel..... <b>BF7644</b>	B-P Lube..... <b>B7685</b>
<b>D10B</b>	<b>Coolant..... BW5141</b>	Fuel..... <b>BF988 +</b>
F-F Lube..... <b>B76 +</b>	<b>D12D</b>	Coolant..... <b>BW5141</b>
F-F Lube (Upgrade)..... <b>B76-SS +</b>	F-F Lube..... <b>B76 +</b>	<b>D16C</b>
B-P Lube..... <b>B7685</b>	F-F Lube (Upgrade)..... <b>B76-SS +</b>	F-F Lube..... <b>B76 +</b>
Fuel..... <b>BF7644</b>	B-P Lube..... <b>B7685</b>	F-F Lube (Upgrade)..... <b>B76-SS +</b>
Coolant..... <b>BW5141</b>	Fuel/Water Separator (20381204)..... <b>BF1389-O</b>	B-P Lube..... <b>B7685</b>
<b>D11 (11.0L)</b>	Fuel..... <b>BF7814</b>	Fuel/Water Separator..... <b>BF1366-O</b>
F-F Lube (4787362)..... <b>[2] B76-SS +</b>	<b>Coolant..... BW5141</b>	Fuel..... <b>BF7814</b>
B-P Lube (477556-5)..... <b>B7685</b>	<b>D13 (12.8L)</b>	Coolant..... <b>BW5141</b>
Fuel/Water Separator (Open End for Bowl) (20514654)..... <b>BF1366-O</b>	F-F Lube (4787362)..... <b>[2] B76-SS +</b>	<b>D16E</b>
Fuel (To 2017) (20430751)..... <b>BF7814</b>	F-F Lube (21707133)..... <b>[2] B76 +</b>	F-F Lube..... <b>B76 +</b>
Fuel (2018-on) (22474709)..... <b>BF46117</b>	B-P Lube (477556-5)..... <b>B7685</b>	F-F Lube (Upgrade)..... <b>B76-SS +</b>
Fuel (To 2017) (22480372)..... <b>BF46161</b>	B-P Lube (21707132)..... <b>B7409</b>	B-P Lube..... <b>B7685</b>
Coolant (21388476)..... <b>BW5142</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FF5369)..... <b>PF7744</b>	Fuel..... <b>BF7814</b>
<b>D12, D12D</b>	<b>Fuel/Water Separator</b> (21380475)..... <b>BF1386-O</b>	Coolant..... <b>BW5141</b>
<b>Dual-Flow Lube (Fleetguard</b> LF9001)..... <b>BD7154 +</b>	<b>Fuel Spin-on (To 2017)</b> (20430751)..... <b>BF7814</b>	<b>D16I</b>
<b>Dual-Flow Lube (Upgrade)</b> (Fleetguard LF14000NN)..... <b>BD50000</b>	Fuel (2018-on) (22474709)..... <b>BF46117</b>	F-F Lube..... <b>B76 +</b>
F-F Lube (478736)..... <b>[2] B76-SS +</b>	<b>Fuel Spin-on (To 2017)</b> (22480372)..... <b>BF46161</b>	F-F Lube (Upgrade)..... <b>B76-SS +</b>
B-P Lube (477556)..... <b>B7685</b>	<b>Coolant (w/8 Units BTE)</b> (20458769)..... <b>BW5142</b>	B-P Lube..... <b>B7685</b>
Fuel/Water Separator Ele. (Davco 382119)..... <b>PF7782</b>		Fuel..... <b>BF7814</b>
		Coolant..... <b>BW5141</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>VOLVO</b> Engines (cont'd)	<b>VOLVO</b> Engines (cont'd)	<b>VOLVO</b> European Trucks, Vans (cont'd)
DXi7 Lube (7420796782)..... P7329 Fuel/Water Separator (7420851191)..... BF1388-O Fuel..... PF7938	VED11 (11.0L) F-F Lube (4787362)..... [2] B76-SS + B-P Lube (477556-5)..... B7685 Fuel/Water Separator (Open End for Bowl) (20514654)..... BF1366-O Fuel (20430751)..... BF7814 Fuel (22480372)..... BF46161 Coolant (3945411)..... BW5142	FM/FMX Serie 370 w/D11K Euro 6 Eng. (07/13-on) F-F Lube (21707133)..... B76 + F-F Lube (Upgrade)..... B76-SS + B-P Lube (21707132)..... B7409 Cab Air (Pre-Filter) (82354791).... PA30113 Cab Air (82348995)..... PA30114 Coolant (16998307)..... BW5141 Steering (3496197)..... P106-HD
DXi 11 F-F Lube..... B76-SS + B-P Lube..... B7685 Fuel/Water Separator..... BF1366-O Fuel..... BF7814	VED12 (12.0L) Dual-Flow Lube (Fleetguard LF9001)..... BD7154 + Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... BD50000 F-F Lube (478736-2)..... B76-SS + B-P Lube (477556)..... B7685 Fuel/Water Separator Ele. (Davco 382119)..... PF7782 Fuel/Water Separator Spin-on (Open End for Bowl) (20514654).. BF1366-O Fuel (8193841)..... BF7653 Fuel (20430751)..... BF7814 Fuel (22480372)..... BF46161 Coolant (20458771)..... B5145	FM/FMX Serie 410 w/D11K Euro 6 Eng. (07/13-on) F-F Lube (21707133)..... B76 + F-F Lube (Upgrade)..... B76-SS + B-P Lube (21707132)..... B7409 Cab Air (Pre-Filter) (82354791).... PA30113 Cab Air (82348995)..... PA30114 Coolant (16998307)..... BW5141 Steering (3496197)..... P106-HD
DXi 12 F-F Lube..... B76-SS + B-P Lube..... B7685 Fuel/Water Separator..... BF1366-O Fuel..... BF7814	VED13 (13.0L) F-F Lube (4787362)..... [2] B76-SS + B-P Lube (477556-5)..... B7685 Fuel/Water Separator Ele. (Fleetguard FF5369)..... PF7744 Fuel/Water Separator Spin-on (Open End for Bowl) (20514654).. BF1366-O Fuel/Water Separator (21380475)..... BF1386-O Fuel (20430751)..... BF7814 Fuel (22480372)..... BF46161 Coolant (20458769)..... BW5142	FM/FMX Serie 420 w/D13K Euro 6 Eng. (07/13-on) F-F Lube (21707133)..... B76 + F-F Lube (Upgrade)..... B76-SS + B-P Lube (21707132)..... B7409 Cab Air (Pre-Filter) (82354791).... PA30113 Cab Air (82348995)..... PA30114 Coolant (16998307)..... BW5141 Steering (3496197)..... P106-HD
DXi 13 F-F Lube..... B76-SS + B-P Lube..... B7685 Fuel/Water Separator..... BF1366-O Fuel..... BF7814	VED16 (16.0L) F-F Lube (4787362)..... [2] B76-SS + B-P Lube (477556-5)..... B7685 Fuel/Water Separator (Open End for Bowl) (20514654)..... BF1366-O Fuel (20430751)..... BF7814 Fuel (22480372)..... BF46161 Coolant (21388476)..... BW5142	FM/FMX Serie 450 w/D11K Euro 6 Eng. (07/13-on) F-F Lube (21707133)..... B76 + F-F Lube (Upgrade)..... B76-SS + B-P Lube (21707132)..... B7409 Cab Air (Pre-Filter) (82354791).... PA30113 Cab Air (82348995)..... PA30114 Coolant (16998307)..... BW5141 Steering (3496197)..... P106-HD
TAD720GE, TD720GE Lube (3831236)..... B236 + Fuel (3825133)..... BF988 +	<b>VOLVO</b> European Trucks, Vans FM/FMX Serie 330 w/D11K Euro 6 Eng. (07/13-on) F-F Lube (21707133)..... B76 + F-F Lube (Upgrade)..... B76-SS + B-P Lube (4775565)..... B7685 B-P Lube (21707132)..... B7409 Cab Air (Pre-Filter) (82354791).... PA30113 Cab Air (82348995)..... PA30114 Coolant (16998307)..... BW5141 Steering (3496197)..... P106-HD	FM/FMX Serie 460 w/D13K Euro 6 Eng. (07/13-on) F-F Lube (21707133)..... B76 + F-F Lube (Upgrade)..... B76-SS + B-P Lube (21707132)..... B7409 Cab Air (Pre-Filter) (82354791).... PA30113 Cab Air (82348995)..... PA30114 Coolant (16998307)..... BW5141 Steering (3496197)..... P106-HD
TD61 Series Lube..... B76 + Lube (Upgrade)..... B76-SS + Fuel..... BF988 +	VE12 F-F Lube (466634)..... [2] B76 + B-P Lube (477556)..... B7685 Fuel (466987-5)..... [2] BF988 +	FM/FMX Serie 500 w/D13K Euro 6 Eng. (07/13-on) F-F Lube (21707133)..... B76 + F-F Lube (Upgrade)..... B76-SS + B-P Lube (21707132)..... B7409 Cab Air (Pre-Filter) (82354791).... PA30113 Cab Air (82348995)..... PA30114 Coolant (16998307)..... BW5141 Steering (3496197)..... P106-HD
TD71 Series Lube..... B76 + Lube (Upgrade)..... B76-SS + Fuel..... BF988 +	VD16 (16.1L) F-F Lube (478736-2)..... [2] B76-SS + B-P Lube (477556-5)..... B7685 Fuel/Water Separator (Open End for Bowl) (20514654)..... BF1366-O Single Fuel (20430751)..... BF7814 Single Fuel (22480372)..... BF46161 Coolant (3945411)..... BW5142	
TD122 F-F Lube (466634)..... B76 + Severe Service F-F Lube (466634)..... B76-SS + P. Fuel (466987)..... BF988 + S. Fuel..... BF788	VED7 F-F Lube (V478736)..... B76-SS + B-P Lube (477556)..... B7685 Fuel (V466987)..... BF988 +	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

VOLVO European Trucks, Vans (cont'd)	VOLVO European Trucks, Vans (cont'd)	VOLVO European Trucks, Vans (cont'd)
<b>FM/FMX Serie 540 w/D13K Euro 6 Eng. (07/13-on)</b> F-F Lube (21707133)..... B76 + F-F Lube (Upgrade)..... B76-SS + B-P Lube (21707132)..... B7409 Cab Air (Pre-Filter) (82354791).... PA30113 Cab Air (82348995)..... PA30114 Coolant (16998307)..... BW5141 Steering (3496197)..... P106-HD	<b>FE II Serie FE240 w/D7E/240 (Euro 4-5) (05/06-on) (Cont'd)</b> Air Dryer (20754416)..... BA5566 Trans. Ele. (85104633)..... PT9417 Trans. Spin-on (110366077)..... BT8851-MPG Steering (3496197)..... P106-HD Urea (21333097)..... PE5271	<b>FE II Serie FE320 w/D7E320 (Euro 4-5) (05/06-on) (Cont'd)</b> Trans. Spin-on (110366077)..... BT8851-MPG Steering (3496197)..... P106-HD Urea (21333097)..... PE5271
<b>FE613 w/TD61GE Eng. (03/86-12/00)</b> F-F Lube (466634)..... [2] B76 + F-F Lube (Upgrade) (4787362).... [2] B76-SS + B-P Lube (4775565)..... B7685 Fuel (4669875)..... BF988 + Air (6776714)..... PA2785 Cab Air (6774452)..... PA2101A Steering (1585618)..... PT9131	<b>FE II Serie FE260 w/D7F260 (Euro 5) (2009-on)</b> Lube (20796785)..... P7329 <b>Fuel/Water Separator (20853583)..... BF1388-O</b> Fuel (20796775)..... PF7938 Radial Seal O. Air (20732733).... RS30116 Radial Seal I. Air (20732734).... RS3729 Cab Air (20559447)..... PA30188 Air Dryer (20754416)..... BA5566 Trans. Ele. (85104633)..... PT9417 Trans. Spin-on (110366077)..... BT8851-MPG Steering (3496197)..... P106-HD Urea (21333097)..... PE5271	<b>FE II Serie FE340 w/D7F340 (Euro 5) (2009-on)</b> Lube (20998807)..... P7329 Fuel (21276079)..... PF7938 <b>Fuel/Water Separator (21380403)..... BF1388-O</b> Radial Seal O. Air (20732733).... RS30116 Radial Seal I. Air (20732734).... RS3729 Cab Air (20559447)..... PA30188 Air Dryer (20754416)..... BA5566 Trans. Ele. (85104633)..... PT9417 Trans. Spin-on (110366077)..... BT8851-MPG Steering (3496197)..... P106-HD Urea (21333097)..... PE5271
<b>FE614 w/TD61FB Eng. (03/86-12/00)</b> F-F Lube (466634)..... [2] B76 + F-F Lube (Upgrade) (4787362).... [2] B76-SS + B-P Lube (4775565)..... B7685 Fuel (4669875)..... BF988 + Air (6776714)..... PA2785 Cab Air (6774452)..... PA2101A Steering (1585618)..... PT9131	<b>FE II Serie FE280 w/D7E280 (Euro 4-5) (05/06-on)</b> Lube (20998807)..... P7329 <b>Fuel/Water Separator (20853583)..... BF1388-O</b> Fuel (20796775)..... PF7938 Radial Seal O. Air (20732726).... RS5390 Radial Seal I. Air (20732728).... RS5351 Cab Air (20559447)..... PA30188 Air Dryer (20754416)..... BA5566 Trans. Ele. (85104633)..... PT9417 Trans. Spin-on (110366077)..... BT8851-MPG Steering (3496197)..... P106-HD Urea (21333097)..... PE5271	<b>FH 12 Serie FH12 w/D12A, D12B, D12C Eng. (08/93-03/02)</b> F-F Lube (466634)..... [2] B76 + F-F Lube (Upgrade) (4787362).... [2] B76-SS + B-P Lube (4775565)..... B7685 <b>Fuel/Water Separator (w/Drain) (81599755)..... BF1329</b> <b>Fuel/Water Separator (Open End for Bowl) (81599755)..... BF46083-O</b> <b>Fuel/Water Separator (w/Bowl) (81599755)..... BF46072</b> <b>Fuel/Water Separator (w/Sensor Port Thd. 9/16-18) (81599755)..... BF1329-SP</b> <b>Fuel/Water Separator (w/Sensor Port Thd. 1/2-20) (81599755)..... BF1339-SP +</b> Fuel (420799)..... BF7644 O. Air (1665898)..... PA3767 I. Air (1665937)..... PA3925 Cab Air (8143691)..... PA3839 Air Dryer (3090288)..... BA5374 + Coolant (21192875)..... BW5141 Trans. Ele. (VT/VTO Geartronic gearbox) (85104633)..... PT9417 Trans. Spin-on (15261886)..... B178 100.8 mm Steering (349619)..... P106-HD 115.9 mm Steering (3231396)..... PT691 116.7 mm Steering (1585618)..... PT9131
<b>FE615 w/TD61FB Eng. (03/86-12/00)</b> F-F Lube (466634)..... [2] B76 + F-F Lube (Upgrade) (4787362).... [2] B76-SS + B-P Lube (4775565)..... B7685 Fuel (4669875)..... BF988 + Air (6776714)..... PA2785 Cab Air (6774452)..... PA2101A Steering (1585618)..... PT9131	<b>FE II Serie FE300 w/D7F300 (Euro 5) (2009-on)</b> Lube (20998807)..... P7329 Fuel (21276079)..... PF7938 <b>Fuel/Water Separator (21380403)..... BF1388-O</b> Radial Seal O. Air (20732733).... RS30116 Radial Seal I. Air (20732734).... RS3729 Cab Air (20559447)..... PA30188 Air Dryer (20754416)..... BA5566 Trans. Ele. (85104633)..... PT9417 Trans. Spin-on (110366077)..... BT8851-MPG Steering (3496197)..... P106-HD Urea (21333097)..... PE5271	<b>FH 12 Serie FH12 w/D12D Series Eng. (11/01-12/05)</b> F-F Lube (466634)..... [2] B76 + F-F Lube (Upgrade) (4787362).... [2] B76-SS + B-P Lube (4775565)..... B7685 <b>89.7 mm Fuel Water Separator (20381204)..... BF1389-O</b> <b>142.9 mm Fuel Water Separator (20998346)..... BF1366-O</b> <b>157.2 mm Fuel Water Separator (20450423)..... BF1390-O</b> Fuel (20430751)..... BF7814 Fuel (20972293)..... BF7943
<b>FE715 w/TD71FA Eng. (03/86-12/00)</b> F-F Lube (To S/N 2016072416) (466634)..... [2] B76 + F-F Lube (Upgrade) (4787362).... [2] B76-SS + B-P Lube (4775565)..... B7685 Fuel (4669875)..... BF988 + Cab Air (6774452)..... PA2101A Steering (1585618)..... PT9131	<b>FE II Serie FE320 w/D7E320 (Euro 4-5) (05/06-on)</b> Lube (20998807)..... P7329 <b>Fuel/Water Separator (20853583)..... BF1388-O</b> Fuel (20796775)..... PF7938 Radial Seal O. Air (20732726).... RS5390 Radial Seal I. Air (20732728).... RS5351 Cab Air (20559447)..... PA30188 Air Dryer (20754416)..... BA5566 Trans. Ele. (85104633)..... PT9417	
<b>FE716 w/TD71FA Eng. (03/86-12/00)</b> F-F Lube (466634)..... [2] B76 + F-F Lube (Upgrade) (4787362).... [2] B76-SS + B-P Lube (4775565)..... B7685 Fuel (4669875)..... BF988 + Cab Air (6774452)..... PA2101A Steering (1585618)..... PT9131	<b>FE II Serie FE240 w/D7E/240 (Euro 4-5) (05/06-on)</b> Lube (20998807)..... P7329 <b>Fuel/Water Separator (20853583)..... BF1388-O</b> Fuel (20796775)..... PF7938 Radial Seal Air (20732726)..... RS5390 Radial Seal Air (20732730)..... RS30236 Radial Seal Air (20732728)..... RS5351 Cab Air (20559447)..... PA30188	

\* See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>VOLVO</b> European Trucks, Vans (cont'd)	<b>VOLVO</b> European Trucks, Vans (cont'd)	<b>VOLVO</b> European Trucks, Vans (cont'd)
<b>FH 12 Serie FH12 w/D12D Series Eng.</b> (11/01-12/05) (Cont'd) <b>Fuel</b> (22480372)..... <b>BF46161</b> <b>Radial Seal Air</b> (8149961)..... <b>RS4967</b> <b>Radial Seal Air (w/FRM)</b> (21834210)..... <b>RS5776</b> <b>Std. I. Air (To S/N 2016072416)</b> (1665937)..... <b>PA3925</b> <b>Cab Air (To S/N 2016072416)</b> (8143691)..... <b>PA3839</b> <b>Air Dryer (To S/N 2016072416)</b> (20773824)..... <b>BA16000</b> <b>Air Dryer (Desiccant Vers.)</b> (20410155)..... <b>BA5374 +</b> <b>Air Dryer (Coalescer Vers.)</b> (21508133)..... <b>BA5379 +</b> <b>Coolant (To S/N 2016072416)</b> (21192875)..... <b>BW5141</b> <b>Trans. Ele. (VT/VTO Geartronic gearbox)</b> (85104633)..... <b>PT9417</b> <b>Trans. Spin-on (Powertronic)</b> (110366077)..... <b>BT8851-MPG</b> <b>Urea (To S/N 2016072416)</b> (21333097)..... <b>PE5271</b>	<b>FH 16 Serie FH16 w/D16B Eng. (08/93-12/03)</b> <b>F-F Lube</b> (466634)..... <b>[2] B76 +</b> <b>F-F Lube (Upgrade)</b> (4787362).... <b>[2] B76-SS +</b> <b>B-P Lube</b> (477556)..... <b>B7685</b> <b>Fuel/Water Separator (Open End for Bowl)</b> (20450423)..... <b>BF1390-O</b> <b>Fuel</b> (4669875)..... <b>BF988 +</b> <b>Fuel/Water Separator (w/Drain)</b> .... <b>BF1349</b> <b>O. Air</b> (1665908)..... <b>PA3768</b> <b>I. Air</b> (1665937)..... <b>PA3925</b> <b>Cab Air</b> (8143691)..... <b>PA3839</b> <b>Air Dryer</b> (3090288)..... <b>BA5374 +</b> <b>Coolant (w/2 Units BTE)</b> (1661964)..... <b>BW5141</b> <b>Coolant (w/8 Units BTE)</b> (20532237)..... <b>BW5142</b> <b>Trans.</b> (15261886)..... <b>B178</b> <b>100.8 mm Steering</b> (3496197).... <b>P106-HD</b> <b>116.7 mm Steering</b> (1585618).... <b>PT9131</b>	<b>FH Serie FH16-540 w/D16G 540 (Euro 5) Eng.</b> (01/09-on) (Cont'd) <b>100.8 mm Steering</b> (3496197).... <b>P106-HD</b> <b>116.7 mm Steering</b> (1585618).... <b>PT9131</b> <b>Urea</b> (21333097)..... <b>PE5271</b>
<b>FH13 w/D13C Eng. (2009-on)</b> <b>F-F Lube</b> (4787362)..... <b>[2] B76-SS +</b> <b>B-P Lube</b> (4775565)..... <b>B7685</b> <b>Fuel</b> (20430751)..... <b>BF7814</b> <b>Fuel</b> (22480372)..... <b>BF46161</b> <b>Fuel/Water Separator</b> (20514654)..... <b>BF1366-O</b> <b>Radial Seal Air</b> (21115483)..... <b>RS5730</b> <b>Cab Air</b> (8143691)..... <b>PA3839</b> <b>Coolant</b> (1661964)..... <b>BW5141</b> <b>Trans.</b> (11448509)..... <b>BT9363-MPG</b> <b>Trans.</b> (85108176)..... <b>PT9417</b> <b>Steering</b> (349619)..... <b>P106-HD</b>	<b>FH Serie FH16-540 w/D16E-540 Eng.</b> (02/06-on) <b>F-F Lube</b> (466634)..... <b>[2] B76 +</b> <b>F-F Lube (Upgrade)</b> (4787362).... <b>[2] B76-SS +</b> <b>B-P Lube</b> (4775565)..... <b>B7685</b> <b>160.3 mm Fuel/Water Separator</b> (20879812)..... <b>BF1387-O</b> <b>Fuel</b> (20430751)..... <b>BF7814</b> <b>Fuel/Water Separator</b> (20514654)..... <b>BF1366-O</b> <b>Fuel</b> (22480372)..... <b>BF46161</b> <b>Fuel</b> (20972293)..... <b>BF7943</b> <b>Radial Seal O. Air</b> (20411815).... <b>RS4642</b> <b>Radial Seal I. Air</b> (20411816).... <b>RS4643</b> <b>Cab Air</b> (8143691)..... <b>PA3839</b> <b>Air Dryer</b> (21508133)..... <b>BA5379 +</b> <b>Coolant</b> (20532237)..... <b>BW5142</b> <b>Trans. (VT/VTO Serie)</b> (85108176)..... <b>PT9417</b> <b>Trans. (I-Shift)</b> (20779040)..... <b>PT9417</b> <b>100.8 mm Steering</b> (3496197).... <b>P106-HD</b> <b>116.7 mm Steering</b> (1585618).... <b>PT9131</b> <b>Urea</b> (21333097)..... <b>PE5271</b> <b>Urea (from 2011)</b> (21516229).... <b>PE17000</b>	<b>FH 16 Serie FH16-580 w/D16E-580 Eng.</b> (02/06-on) <b>F-F Lube</b> (466634)..... <b>[2] B76 +</b> <b>F-F Lube (Upgrade)</b> (4787362).... <b>[2] B76-SS +</b> <b>B-P Lube</b> (4775565)..... <b>B7685</b> <b>160.3 mm Fuel/Water Separator</b> (20879812)..... <b>BF1387-O</b> <b>Fuel</b> (20972293)..... <b>BF7943</b> <b>Fuel/Water Separator</b> (20514654)..... <b>BF1366-O</b> <b>Fuel</b> (20430751)..... <b>BF7814</b> <b>Fuel</b> (22480372)..... <b>BF46161</b> <b>Radial Seal O. Air</b> (20411815).... <b>RS4642</b> <b>Radial Seal I. Air</b> (20411816).... <b>RS4643</b> <b>Cab Air</b> (8143691)..... <b>PA3839</b> <b>Air Dryer</b> (21508133)..... <b>BA5379 +</b> <b>Coolant</b> (20532237)..... <b>BW5142</b> <b>Trans. (VT/VTO Serie)</b> (85108176)..... <b>PT9417</b> <b>Trans. (I-Shift)</b> (20779040)..... <b>PT9417</b> <b>Urea</b> (21333097)..... <b>PE5271</b>
<b>FH 16 Serie FH16 w/D16A470EDC Eng.</b> (08/93-12/03) <b>F-F Lube</b> (466634)..... <b>[2] B76 +</b> <b>F-F Lube (Upgrade)</b> (4787362).... <b>[2] B76-SS +</b> <b>B-P Lube</b> (477556)..... <b>B7685</b> <b>Fuel</b> (4669875)..... <b>BF988 +</b> <b>Fuel/Water Separator</b> ..... <b>BF1349</b> <b>O. Air</b> (1665908)..... <b>PA3768</b> <b>I. Air</b> (1665937)..... <b>PA3925</b> <b>Cab Air</b> (8143691)..... <b>PA3839</b> <b>Air Dryer</b> (3090288)..... <b>BA5374 +</b> <b>Coolant (w/2 Units BTE)</b> (1661964)..... <b>BW5141</b> <b>Coolant (w/8 Units BTE)</b> (20532237)..... <b>BW5142</b> <b>Trans.</b> (15261886)..... <b>B178</b> <b>100.8 mm Steering</b> (3496197).... <b>P106-HD</b> <b>116.7 mm Steering</b> (1585618).... <b>PT9131</b>	<b>FH Serie FH16-540 w/D16G 540 (Euro 5) Eng.</b> (01/09-on) <b>F-F Lube</b> (466634)..... <b>[2] B76 +</b> <b>F-F Lube (Upgrade)</b> (4787362).... <b>[2] B76-SS +</b> <b>B-P Lube</b> (4775565)..... <b>B7685</b> <b>160.3 mm Fuel/Water Separator</b> (20879812)..... <b>BF1387-O</b> <b>Fuel</b> (20972293)..... <b>BF7943</b> <b>Fuel/Water Separator</b> (20514654)..... <b>BF1366-O</b> <b>Radial Seal O. Air</b> (20411815).... <b>RS4642</b> <b>Radial Seal I. Air</b> (20411816).... <b>RS4643</b> <b>Cab Air</b> (8143691)..... <b>PA3839</b> <b>Air Dryer</b> (21508133)..... <b>BA5379 +</b> <b>Coolant</b> (20532237)..... <b>BW5142</b> <b>Trans. (I-Shift)</b> (20779040)..... <b>PT9417</b>	<b>FH Serie FH16-600 w/D16G 600 (Euro 5) Eng.</b> (01/09-on) <b>F-F Lube</b> (466634)..... <b>[2] B76 +</b> <b>F-F Lube (Upgrade)</b> (4787362).... <b>[2] B76-SS +</b> <b>B-P Lube</b> (4775565)..... <b>B7685</b> <b>160.3 mm Fuel/Water Separator</b> (20879812)..... <b>BF1387-O</b> <b>Fuel</b> (20972293)..... <b>BF7943</b> <b>Fuel/Water Separator</b> (20514654)..... <b>BF1366-O</b> <b>Radial Seal O. Air</b> (20411815).... <b>RS4642</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

VOLVO European Trucks, Vans (cont'd)	VOLVO European Trucks, Vans (cont'd)	VOLVO European Trucks, Vans (cont'd)
<b>FH Serie FH16-600 w/D16G 600 (Euro 5) Eng. (01/09-on) (Cont'd)</b> Radial Seal I. Air (20411816)..... <b>RS4643</b> Cab Air (8143691)..... <b>PA3839</b> Air Dryer (21508133)..... <b>BA5379 +</b> Coolant (20532237)..... <b>BW5142</b> Trans. (I-Shift) (20779040)..... <b>PT9417</b> 100.8 mm Steering (3496197)..... <b>P106-HD</b> 116.7 mm Steering (1585618)..... <b>PT9131</b> Urea (21333097)..... <b>PE5271</b> Urea (from 2011) (21516229)..... <b>PE17000</b>	<b>FH Serie FH16-700 w/D16G 700 (Euro 5) Eng. (01/09-on) (Cont'd)</b> B-P Lube (4775565)..... <b>B7685</b> <b>160.3 mm Fuel/Water Separator</b> (20879812)..... <b>BF1387-O</b> Fuel (20972293)..... <b>BF7943</b> <b>Fuel/Water Separator</b> (20514654)..... <b>BF1366-O</b> Radial Seal O. Air (20411815)..... <b>RS4642</b> Radial Seal I. Air (20411816)..... <b>RS4643</b> Cab Air (8143691)..... <b>PA3839</b> Air Dryer (21508133)..... <b>BA5379 +</b> Coolant (20532237)..... <b>BW5142</b> Trans. (I-Shift) (20779040)..... <b>PT9417</b> 100.8 mm Steering (3496197)..... <b>P106-HD</b> 116.7 mm Steering (1585618)..... <b>PT9131</b> Urea (21333097)..... <b>PE5271</b> Urea (from 2011) (21516229)..... <b>PE17000</b>	<b>FH Serie FH 420 w/D13C (Euro 5) Eng. (2009-on)</b> F-F Lube (466634)..... <b>[2] B76 +</b> F-F Lube (Upgrade) (4787362)..... <b>[2] B76-SS +</b> B-P Lube (4775565)..... <b>B7685</b> <b>149.9 mm Fuel Water Separator</b> (20998346)..... <b>BF1366-O</b> <b>160.3 mm Fuel/Water Separator</b> (20879812)..... <b>BF1387-O</b> P. Fuel (20430751)..... <b>BF7814</b> P. Fuel (22480372)..... <b>BF46161</b> P. Fuel (20972293)..... <b>BF7943</b> <b>409.6 mm Radial Seal O. Air</b> (21243188)..... <b>RS5730</b> I. Air (21115501)..... <b>RS5731</b> Cab Air (8143691)..... <b>PA3839</b> Air Dryer (20773824)..... <b>BA16000</b> Air Dryer (21508133)..... <b>BA5379 +</b> Trans. (VT/VO Serie) (85108176)..... <b>PT9417</b> Trans. (I-Shift) (20779040)..... <b>PT9417</b> Trans. (110366077)..... <b>BT8851-MPG</b> Steering (3496197)..... <b>P106-HD</b> Urea (21333097)..... <b>PE5271</b> Urea (from 2011) (21516229)..... <b>PE17000</b>
<b>FH 16 Serie FH16-610 w/D16C-610 Eng. (06/03-on)</b> F-F Lube (466634)..... <b>[2] B76 +</b> F-F Lube (Upgrade) (4787362)..... <b>[2] B76-SS +</b> B-P Lube (4775565)..... <b>B7685</b> <b>160.3 mm Fuel/Water Separator</b> (20879812)..... <b>BF1387-O</b> Fuel (20430751)..... <b>BF7814</b> <b>Fuel/Water Separator</b> (20514654)..... <b>BF1366-O</b> Fuel (22480372)..... <b>BF46161</b> Radial Seal O. Air (20411815)..... <b>RS4642</b> Radial Seal I. Air (20411816)..... <b>RS4643</b> Cab Air (8143691)..... <b>PA3839</b> Air Dryer (21508133)..... <b>BA5379 +</b> Coolant (20532237)..... <b>BW5142</b> Trans. (VT/VO Serie) (85108176)..... <b>PT9417</b> Trans. (I-Shift) (20779040)..... <b>PT9417</b> 100.8 mm Steering (3496197)..... <b>P106-HD</b> 116.7 mm Steering (1585618)..... <b>PT9131</b>	<b>FH16-750 w/D16G 750 (Euro 5) Eng. (01/12-on)</b> F-F Lube (4787362)..... <b>B76-SS +</b> B-P Lube (4775565)..... <b>B7685</b> <b>142.9 mm Fuel Water Separator</b> (20998346)..... <b>BF1366-O</b> <b>160.3 mm Fuel/Water Separator</b> (20879812)..... <b>BF1387-O</b> Fuel (20972293)..... <b>BF7943</b> Radial Seal O. Air (21716424)..... <b>RS4642</b> Radial Seal I. Air (20411816)..... <b>RS4643</b> Cab Air (8143691)..... <b>PA3839</b> Air Dryer (21508133)..... <b>BA5379 +</b> Coolant (20532237)..... <b>BW5142</b> Trans. (20779040)..... <b>PT9417</b> 100.8 mm Steering (3496197)..... <b>P106-HD</b> 116.7 mm Steering (1585618)..... <b>PT9131</b> Urea (21516229)..... <b>PE17000</b>	<b>FH Serie FH 420 w/D13C (Euro 5) Eng. (2013-on)</b> F-F Lube (21707133)..... <b>B76 +</b> F-F Lube (Upgrade)..... <b>B76-SS +</b> B-P Lube (4775565)..... <b>B7685</b> B-P Lube (21707132)..... <b>B7409</b> <b>Fuel/Water Separator</b> (20879806)..... <b>BF1386-O</b> <b>Fuel/Water Separator</b> (20879812)..... <b>BF1387-O</b> P. Fuel (20430751)..... <b>BF7814</b> P. Fuel (22480372)..... <b>BF46161</b> P. Fuel (20972293)..... <b>BF7943</b> Radial Seal O. Air (21115483)..... <b>RS5730</b> Radial Seal I. Air (21115501)..... <b>RS5731</b> Cab Air (Pre-Filter) (82354791)..... <b>PA30113</b> Cab Air (82348995)..... <b>PA30014</b> Coolant (16998307)..... <b>BW5141</b> Trans. Ele. (Gearbox VT/VO) (1521527)..... <b>PT9417</b> Trans. Spin-on (powertronic gearbox) (110366077)..... <b>BT8851-MPG</b> Steering (3496197)..... <b>P106-HD</b> Urea (21516229)..... <b>PE17000</b>
<b>FH 16 Serie FH16 w/D16E-660 Eng. (02/06-on)</b> F-F Lube (466634)..... <b>[2] B76 +</b> F-F Lube (Upgrade) (4787362)..... <b>[2] B76-SS +</b> B-P Lube (4775565)..... <b>B7685</b> <b>160.3 mm Fuel/Water Separator</b> (20879812)..... <b>BF1387-O</b> Fuel (20972293)..... <b>BF7943</b> <b>Fuel/Water Separator</b> (20514654)..... <b>BF1366-O</b> Fuel (20430751)..... <b>BF7814</b> Fuel (22480372)..... <b>BF46161</b> Radial Seal O. Air (20411815)..... <b>RS4642</b> Radial Seal I. Air (20411816)..... <b>RS4643</b> Cab Air (8143691)..... <b>PA3839</b> Air Dryer (21508133)..... <b>BA5379 +</b> Coolant (20532237)..... <b>BW5142</b> Trans. (VT/VO Serie) (85108176)..... <b>PT9417</b> Trans. (I-Shift) (1585618)..... <b>PT9131</b> 100.8 mm Steering (3496197)..... <b>P106-HD</b> 116.7 mm Steering (1585618)..... <b>PT9131</b> Urea (21333097)..... <b>PE5271</b>	<b>FH Serie FH 400 w/D13A/B-400 (Euro 4-5) Eng. (09/05-on)</b> F-F Lube (466634)..... <b>[2] B76 +</b> F-F Lube (Upgrade) (4787362)..... <b>[2] B76-SS +</b> B-P Lube (4775565)..... <b>B7685</b> <b>160.3 mm Fuel/Water Separator</b> (20879812)..... <b>BF1387-O</b> Fuel (20430751)..... <b>BF7814</b> Fuel (20972293)..... <b>BF7943</b> <b>Fuel/Water Separator</b> (20514654)..... <b>BF1366-O</b> Fuel (22480372)..... <b>BF46161</b> Radial Seal Air (814996-1)..... <b>RS4967</b> Radial Seal Air (w/FRM) (21834210)..... <b>RS5776</b> Std. I. Air (1665937)..... <b>PA3925</b> Cab Air (8143691)..... <b>PA3839</b> Air Dryer (20773824)..... <b>BA16000</b> Air Dryer (21508133)..... <b>BA5379 +</b> Trans. Ele. (85104633)..... <b>PT9417</b> Trans. Spin-on (110366077)..... <b>BT8851-MPG</b> Steering (3496197)..... <b>P106-HD</b> Urea (21333097)..... <b>PE5271</b>	<b>FH Serie FH 440 w/D13A/B-400 (Euro 4-5) Eng. (09/05-on)</b> F-F Lube (466634)..... <b>[2] B76 +</b> F-F Lube (Upgrade) (4787362)..... <b>[2] B76-SS +</b> B-P Lube (4775565)..... <b>B7685</b> <b>160.3 mm Fuel/Water Separator</b> (20879812)..... <b>BF1387-O</b> Fuel (20430751)..... <b>BF7814</b> Fuel (20972293)..... <b>BF7943</b>
<b>FH Serie FH16-700 w/D16G 700 (Euro 5) Eng. (01/09-on)</b> F-F Lube (466634)..... <b>[2] B76 +</b> F-F Lube (Upgrade) (4787362)..... <b>[2] B76-SS +</b>		

\* See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>VOLVO</b> European Trucks, Vans (cont'd)	<b>VOLVO</b> European Trucks, Vans (cont'd)	<b>VOLVO</b> European Trucks, Vans (cont'd)
FH Serie FH 440 w/D13A/B-400 (Euro 4-5) Eng. (09/05-on) (Cont'd)	FH Serie FH 460 w/D13C (Euro 5) Eng. (2013-on) (Cont'd)	FH Serie FH 500 w/D13C (Euro 5) Eng. (2009-on) (Cont'd)
<b>Fuel/Water Separator</b> (20514654)..... <b>BF1366-O</b>	<b>Trans. Ele.</b> (Gearbox VT/VTO) (1521527)..... <b>PT9417</b>	<b>160.3 mm Fuel/Water Separator</b> (20879812)..... <b>BF1387-O</b>
<b>Fuel</b> (22480372)..... <b>BF46161</b>	<b>Trans. Spin-on</b> (powertronic gearbox) (110366077)..... <b>BT8851-MPG</b>	<b>P. Fuel</b> (20430751)..... <b>BF7814</b>
<b>Radial Seal Air</b> (814996-1)..... <b>RS4967</b>	<b>Steering</b> (3496197)..... <b>P106-HD</b>	<b>P. Fuel</b> (22480372)..... <b>BF46161</b>
<b>Radial Seal Air</b> (w/FRM) (21834210)..... <b>RS5776</b>	<b>Urea</b> (21516229)..... <b>PE17000</b>	<b>P. Fuel</b> (20972293)..... <b>BF7943</b>
<b>Std. I. Air</b> (1665937)..... <b>PA3925</b>	FH Serie FH 480 w/D13A-480 (Euro 4-5) Eng. (09/05-on)	<b>409.6 mm Radial Seal O. Air</b> (21243188)..... <b>RS5730</b>
<b>Cab Air</b> (8143691)..... <b>PA3839</b>	<b>F-F Lube</b> (466634)..... <b>[2] B76 +</b>	<b>Radial Seal I. Air</b> (21115501)..... <b>RS5731</b>
<b>Air Dryer</b> (20773824)..... <b>BA16000</b>	<b>F-F Lube</b> (Upgrade) (4787362).... <b>[2] B76-SS +</b>	<b>Cab Air</b> (8143691)..... <b>PA3839</b>
<b>Air Dryer</b> (21508133)..... <b>BA5379 +</b>	<b>B-P Lube</b> (4775565)..... <b>B7685</b>	<b>Air Dryer</b> (20773824)..... <b>BA16000</b>
<b>Trans. Ele.</b> (85104633)..... <b>PT9417</b>	<b>160.3 mm Fuel/Water Separator</b> (20879812)..... <b>BF1387-O</b>	<b>Air Dryer</b> (21508133)..... <b>BA5379 +</b>
<b>Trans. Spin-on</b> (110366077)..... <b>BT8851-MPG</b>	<b>Fuel</b> (20430751)..... <b>BF7814</b>	<b>Trans. (VT/VTO Serie)</b> (85108176)..... <b>PT9417</b>
<b>Steering</b> (3496197)..... <b>P106-HD</b>	<b>Fuel/Water Separator</b> (20514654)..... <b>BF1366-O</b>	<b>Trans. (I-Shift)</b> (20779040)..... <b>PT9417</b>
<b>Urea</b> (21333097)..... <b>PE5271</b>	<b>Fuel</b> (22480372)..... <b>BF46161</b>	<b>Trans. (110366077)..... <b>BT8851-MPG</b></b>
FH Serie FH 460 w/D13C (Euro 5) Eng. (2009-on)	<b>Radial Seal Air</b> (814996-1)..... <b>RS4967</b>	<b>Steering</b> (3496197)..... <b>P106-HD</b>
<b>F-F Lube</b> (466634)..... <b>[2] B76 +</b>	<b>Radial Seal Air</b> (w/FRM) (21834210)..... <b>RS5776</b>	<b>Urea</b> (21333097)..... <b>PE5271</b>
<b>F-F Lube</b> (Upgrade) (4787362).... <b>[2] B76-SS +</b>	<b>Std. I. Air</b> (1665937)..... <b>PA3925</b>	<b>Urea</b> (from 2011) (21516229)..... <b>PE17000</b>
<b>B-P Lube</b> (4775565)..... <b>B7685</b>	<b>Cab Air</b> (8143691)..... <b>PA3839</b>	FH Serie FH 520 w/D13A-520 Eng. (09/05-on)
<b>149.9 mm Fuel Water Separator</b> (20998346)..... <b>BF1366-O</b>	<b>Air Dryer</b> (20773824)..... <b>BA16000</b>	<b>F-F Lube</b> (466634)..... <b>[2] B76 +</b>
<b>160.3 mm Fuel/Water Separator</b> (20879812)..... <b>BF1387-O</b>	<b>Trans. (Ele.)</b> (20776259)..... <b>PT9417</b>	<b>F-F Lube</b> (Upgrade) (4787362).... <b>[2] B76-SS +</b>
<b>P. Fuel</b> (20430751)..... <b>BF7814</b>	<b>Trans. (Spin-on)</b> (110366077)..... <b>BT8851-MPG</b>	<b>B-P Lube</b> (4775565)..... <b>B7685</b>
<b>P. Fuel</b> (22480372)..... <b>BF46161</b>	<b>Urea</b> (21333097)..... <b>PE5271</b>	<b>160.3 mm Fuel/Water Separator</b> (20879812)..... <b>BF1387-O</b>
<b>P. Fuel</b> (20972293)..... <b>BF7943</b>	FH Serie FH 500 w/D13B-500 (Euro 4-5) Eng. (09/05-on)	<b>Fuel</b> (20430751)..... <b>BF7814</b>
<b>409.6 mm Radial Seal O. Air</b> (21243188)..... <b>RS5730</b>	<b>F-F Lube</b> (466634)..... <b>[2] B76 +</b>	<b>Fuel</b> (20972293)..... <b>BF7943</b>
<b>Radial Seal I. Air</b> (21115501)..... <b>RS5731</b>	<b>F-F Lube</b> (Upgrade) (4787362).... <b>[2] B76-SS +</b>	<b>Fuel/Water Separator</b> (20514654)..... <b>BF1366-O</b>
<b>Cab Air</b> (8143691)..... <b>PA3839</b>	<b>B-P Lube</b> (4775565)..... <b>B7685</b>	<b>Fuel</b> (22480372)..... <b>BF46161</b>
<b>Air Dryer</b> (20773824)..... <b>BA16000</b>	<b>160.3 mm Fuel/Water Separator</b> (20879812)..... <b>BF1387-O</b>	<b>Radial Seal Air</b> (814996-1)..... <b>RS4967</b>
<b>Air Dryer</b> (21508133)..... <b>BA5379 +</b>	<b>Fuel</b> (20430751)..... <b>BF7814</b>	<b>Radial Seal Air</b> (w/FRM) (21834210)..... <b>RS5776</b>
<b>Trans. (VT/VTO Serie)</b> (85108176)..... <b>PT9417</b>	<b>Fuel</b> (20972293)..... <b>BF7943</b>	<b>Std. I. Air</b> (1665937)..... <b>PA3925</b>
<b>Trans. (I-Shift)</b> (20779040)..... <b>PT9417</b>	<b>Fuel/Water Separator</b> (20514654)..... <b>BF1366-O</b>	<b>Cab Air</b> (8143691)..... <b>PA3839</b>
<b>Trans. (110366077)..... <b>BT8851-MPG</b></b>	<b>Fuel</b> (22480372)..... <b>BF46161</b>	<b>Air Dryer</b> (20773824)..... <b>BA16000</b>
<b>Steering</b> (3496197)..... <b>P106-HD</b>	<b>Radial Seal Air</b> (814996-1)..... <b>RS4967</b>	<b>Air Dryer</b> (21508133)..... <b>BA5379 +</b>
<b>Urea</b> (21333097)..... <b>PE5271</b>	<b>Radial Seal Air</b> (w/FRM) (21834210)..... <b>RS5776</b>	<b>Trans. Ele.</b> (85104633)..... <b>PT9417</b>
<b>Urea</b> (from 2011) (21516229)..... <b>PE17000</b>	<b>Std. I. Air</b> (1665937)..... <b>PA3925</b>	<b>Trans. Spin-on</b> (110366077)..... <b>BT8851-MPG</b>
FH Serie FH 460 w/D13C (Euro 5) Eng. (2013-on)	<b>Cab Air</b> (8143691)..... <b>PA3839</b>	<b>Steering</b> (3496197)..... <b>P106-HD</b>
<b>F-F Lube</b> (21707133)..... <b>B76 +</b>	<b>Air Dryer</b> (20773824)..... <b>BA16000</b>	<b>Urea</b> (21333097)..... <b>PE5271</b>
<b>F-F Lube</b> (Upgrade)..... <b>B76-SS +</b>	<b>Air Dryer</b> (21508133)..... <b>BA5379 +</b>	FH Serie FH 520 w/D13C (Euro 5) Eng. (2013-on)
<b>B-P Lube</b> (4775565)..... <b>B7685</b>	<b>Trans. Ele.</b> (85104633)..... <b>PT9417</b>	<b>F-F Lube</b> (21707133)..... <b>B76 +</b>
<b>B-P Lube</b> (21707132)..... <b>B7409</b>	<b>Trans. Spin-on</b> (110366077)..... <b>BT8851-MPG</b>	<b>F-F Lube</b> (Upgrade)..... <b>B76-SS +</b>
<b>Fuel/Water Separator</b> (20879806)..... <b>BF1386-O</b>	<b>Steering</b> (3496197)..... <b>P106-HD</b>	<b>B-P Lube</b> (4775565)..... <b>B7685</b>
<b>Fuel/Water Separator</b> (20879812)..... <b>BF1387-O</b>	<b>Urea</b> (21333097)..... <b>PE5271</b>	<b>B-P Lube</b> (21707132)..... <b>B7409</b>
<b>P. Fuel</b> (20430751)..... <b>BF7814</b>	FH Serie FH 500 w/D13C (Euro 5) Eng. (2009-on)	<b>Fuel/Water Separator</b> (20879806)..... <b>BF1386-O</b>
<b>P. Fuel</b> (22480372)..... <b>BF46161</b>	<b>F-F Lube</b> (466634)..... <b>[2] B76 +</b>	<b>Fuel/Water Separator</b> (20879812)..... <b>BF1387-O</b>
<b>P. Fuel</b> (20972293)..... <b>BF7943</b>	<b>F-F Lube</b> (Upgrade) (4787362).... <b>[2] B76-SS +</b>	<b>P. Fuel</b> (20430751)..... <b>BF7814</b>
<b>Radial Seal O. Air</b> (21115483)..... <b>RS5730</b>	<b>B-P Lube</b> (4775565)..... <b>B7685</b>	<b>P. Fuel</b> (22480372)..... <b>BF46161</b>
<b>Radial Seal I. Air</b> (21115501)..... <b>RS5731</b>	<b>149.9 mm Fuel Water Separator</b> (20998346)..... <b>BF1366-O</b>	<b>P. Fuel</b> (20972293)..... <b>BF7943</b>
<b>Cab Air</b> (Pre-Filter) (82354791).... <b>PA30113</b>		<b>Radial Seal O. Air</b> (21115483).... <b>RS5730</b>
<b>Cab Air</b> (82348995)..... <b>PA30114</b>		<b>Radial Seal I. Air</b> (21115501)..... <b>RS5731</b>
<b>Coolant</b> (16998307)..... <b>BW5141</b>		<b>Cab Air</b> (Pre-Filter) (82354791).... <b>PA30113</b>
		<b>Cab Air</b> (82348995)..... <b>PA30114</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.


 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

VOLVO European Trucks, Vans (cont'd)	VOLVO European Trucks, Vans (cont'd)	VOLVO European Trucks, Vans (cont'd)
<b>FH Serie FH 520 w/D13C (Euro 5) Eng.</b> (2013-on) (Cont'd) <b>Coolant</b> (16998307)..... <b>BW5141</b> <b>Trans. Ele.</b> (Gearbox VT/VTO) (1521527)..... <b>PT9417</b> <b>Trans. Spin-on</b> (powertronic gearbox) (110366077)..... <b>BT8851-MPG</b> <b>Steering</b> (3496197)..... <b>P106-HD</b> <b>Urea</b> (21516229)..... <b>PE17000</b>	<b>FH Serie FH 550 w/D16K (Euro 6) Eng.</b> (2014-on) <b>B-P Lube</b> (21707132)..... <b>B7409</b> <b>Lube</b> (21707133)..... <b>B76 +</b> <b>Lube</b> (Upgrade)..... <b>B76-SS +</b> <b>Fuel/Water Separator</b> (20998367)..... <b>BF1366-O</b> <b>Fuel</b> (20430751)..... <b>BF7814</b> <b>Fuel</b> (22480372)..... <b>BF46161</b> <b>Fuel</b> (Upgrade) (20972293)..... <b>BF7943</b> <b>Radial Seal O. Air</b> (21716424)..... <b>RS4642</b> <b>Radial Seal I. Air</b> (20411816)..... <b>RS4643</b> <b>Cab Air</b> (Pre-Filter) (82354791).... <b>PA30113</b> <b>Cab Air</b> (82348995)..... <b>PA30114</b> <b>Coolant</b> (16998307)..... <b>BW5141</b> <b>Trans.</b> (powertronic gearbox) (110366077)..... <b>BT8851-MPG</b> <b>Trans.</b> (Gearbox VT/VTO) (1521527)..... <b>PT9417</b> <b>Steering</b> (3496197)..... <b>P106-HD</b> <b>Urea</b> (21516229)..... <b>PE17000</b>	<b>FH Serie FH 650 w/D16K (Euro 6) Eng.</b> (2014-on) (Cont'd) <b>Coolant</b> (16998307)..... <b>BW5141</b> <b>Trans.</b> (powertronic gearbox) (110366077)..... <b>BT8851-MPG</b> <b>Trans.</b> (Gearbox VT/VTO) (1521527)..... <b>PT9417</b> <b>Steering</b> (3496197)..... <b>P106-HD</b> <b>Urea</b> (21516229)..... <b>PE17000</b>
<b>FH Serie FH 540 w/D13C (Euro 5) Eng.</b> (2013-on) <b>F-F Lube</b> (21707133)..... <b>B76 +</b> <b>F-F Lube</b> (Upgrade)..... <b>B76-SS +</b> <b>B-P Lube</b> (4775565)..... <b>B7685</b> <b>B-P Lube</b> (21707132)..... <b>B7409</b> <b>Fuel/Water Separator</b> (20879806)..... <b>BF1386-O</b> <b>Fuel/Water Separator</b> (20879812)..... <b>BF1387-O</b> <b>P. Fuel</b> (20430751)..... <b>BF7814</b> <b>P. Fuel</b> (22480372)..... <b>BF46161</b> <b>P. Fuel</b> (20972293)..... <b>BF7943</b> <b>Radial Seal O. Air</b> (21115483)..... <b>RS5730</b> <b>Radial Seal I. Air</b> (21115501)..... <b>RS5731</b> <b>Cab Air</b> (Pre-Filter) (82354791).... <b>PA30113</b> <b>Cab Air</b> (82348995)..... <b>PA30114</b> <b>Coolant</b> (16998307)..... <b>BW5141</b> <b>Trans. Ele.</b> (Gearbox VT/VTO) (1521527)..... <b>PT9417</b> <b>Trans. Spin-on</b> (powertronic gearbox) (110366077)..... <b>BT8851-MPG</b> <b>Steering</b> (3496197)..... <b>P106-HD</b> <b>Urea</b> (21516229)..... <b>PE17000</b>	<b>FH Serie FH 600 w/D16G (Euro 5) Eng.</b> (2013-on) <b>F-F Lube</b> (21707133)..... <b>B76 +</b> <b>F-F Lube</b> (Upgrade)..... <b>B76-SS +</b> <b>B-P Lube</b> (4775565)..... <b>B7685</b> <b>B-P Lube</b> (21707132)..... <b>B7409</b> <b>Fuel/Water Separator</b> (20998346)..... <b>BF1366-O</b> <b>Fuel/Water Separator</b> (20782330)..... <b>BF46134-O</b> <b>P. Fuel</b> (20430751)..... <b>BF7814</b> <b>P. Fuel</b> (22480372)..... <b>BF46161</b> <b>P. Fuel</b> (20972293)..... <b>BF7943</b> <b>Radial Seal O. Air</b> (21716424)..... <b>RS4642</b> <b>Radial Seal I. Air</b> (20411816)..... <b>RS4643</b> <b>Cab Air</b> (Pre-Filter) (82354791).... <b>PA30113</b> <b>Cab Air</b> (82348995)..... <b>PA30114</b> <b>Coolant</b> (16998307)..... <b>BW5141</b> <b>Trans. Ele.</b> (Gearbox VT/VTO) (1521527)..... <b>PT9417</b> <b>Trans. Spin-on</b> (powertronic gearbox) (110366077)..... <b>BT8851-MPG</b> <b>Steering</b> (3496197)..... <b>P106-HD</b> <b>Urea</b> (21516229)..... <b>PE17000</b>	<b>FH Serie FH 700 w/D16G (Euro 5) Eng.</b> (2013-on) <b>F-F Lube</b> (21707133)..... <b>B76 +</b> <b>F-F Lube</b> (Upgrade)..... <b>B76-SS +</b> <b>B-P Lube</b> (4775565)..... <b>B7685</b> <b>B-P Lube</b> (21707132)..... <b>B7409</b> <b>Fuel/Water Separator</b> (20998346)..... <b>BF1366-O</b> <b>Fuel/Water Separator</b> (20782330)..... <b>BF46134-O</b> <b>P. Fuel</b> (20430751)..... <b>BF7814</b> <b>P. Fuel</b> (22480372)..... <b>BF46161</b> <b>P. Fuel</b> (20972293)..... <b>BF7943</b> <b>Radial Seal O. Air</b> (21716424).... <b>RS4642</b> <b>Radial Seal I. Air</b> (20411816)..... <b>RS4643</b> <b>Cab Air</b> (Pre-Filter) (82354791).... <b>PA30113</b> <b>Cab Air</b> (82348995)..... <b>PA30114</b> <b>Coolant</b> (16998307)..... <b>BW5141</b> <b>Trans. Ele.</b> (Gearbox VT/VTO) (1521527)..... <b>PT9417</b> <b>Trans. Spin-on</b> (powertronic gearbox) (110366077)..... <b>BT8851-MPG</b> <b>Steering</b> (3496197)..... <b>P106-HD</b> <b>Urea</b> (21516229)..... <b>PE17000</b>
<b>FH Serie FH 540 w/D16G (Euro 5) Eng.</b> (2013-on) <b>F-F Lube</b> (21707133)..... <b>B76 +</b> <b>F-F Lube</b> (Upgrade)..... <b>B76-SS +</b> <b>B-P Lube</b> (4775565)..... <b>B7685</b> <b>B-P Lube</b> (21707132)..... <b>B7409</b> <b>Fuel/Water Separator</b> (20998346)..... <b>BF1366-O</b> <b>Fuel/Water Separator</b> (20782330)..... <b>BF46134-O</b> <b>P. Fuel</b> (20430751)..... <b>BF7814</b> <b>P. Fuel</b> (22480372)..... <b>BF46161</b> <b>P. Fuel</b> (20972293)..... <b>BF7943</b> <b>Radial Seal O. Air</b> (21716424).... <b>RS4642</b> <b>Radial Seal I. Air</b> (20411816)..... <b>RS4643</b> <b>Cab Air</b> (Pre-Filter) (82354791).... <b>PA30113</b> <b>Cab Air</b> (82348995)..... <b>PA30114</b> <b>Coolant</b> (16998307)..... <b>BW5141</b> <b>Trans. Ele.</b> (Gearbox VT/VTO) (1521527)..... <b>PT9417</b> <b>Trans. Spin-on</b> (powertronic gearbox) (110366077)..... <b>BT8851-MPG</b> <b>Steering</b> (3496197)..... <b>P106-HD</b> <b>Urea</b> (21516229)..... <b>PE17000</b>	<b>FH Serie FH 650 w/D16K (Euro 6) Eng.</b> (2014-on) <b>B-P Lube</b> (21707132)..... <b>B7409</b> <b>Lube</b> (21707133)..... <b>B76 +</b> <b>Lube</b> (Upgrade)..... <b>B76-SS +</b> <b>Fuel/Water Separator</b> (20998367)..... <b>BF1366-O</b> <b>Fuel</b> (20430751)..... <b>BF7814</b> <b>Fuel</b> (22480372)..... <b>BF46161</b> <b>Fuel</b> (Upgrade) (20972293)..... <b>BF7943</b> <b>Radial Seal O. Air</b> (21716424).... <b>RS4642</b> <b>Radial Seal I. Air</b> (20411816)..... <b>RS4643</b> <b>Cab Air</b> (Pre-Filter) (82354791).... <b>PA30113</b> <b>Cab Air</b> (82348995)..... <b>PA30114</b>	<b>FH Serie FH 750 w/D16G (Euro 5) Eng.</b> (2013-on) <b>F-F Lube</b> (21707133)..... <b>B76 +</b> <b>F-F Lube</b> (Upgrade)..... <b>B76-SS +</b> <b>B-P Lube</b> (4775565)..... <b>B7685</b> <b>B-P Lube</b> (21707132)..... <b>B7409</b> <b>Fuel/Water Separator</b> (20998346)..... <b>BF1366-O</b> <b>Fuel/Water Separator</b> (20782330)..... <b>BF46134-O</b> <b>P. Fuel</b> (20430751)..... <b>BF7814</b> <b>P. Fuel</b> (22480372)..... <b>BF46161</b> <b>P. Fuel</b> (20972293)..... <b>BF7943</b> <b>Radial Seal O. Air</b> (21716424).... <b>RS4642</b> <b>Radial Seal I. Air</b> (20411816)..... <b>RS4643</b> <b>Cab Air</b> (Pre-Filter) (82354791).... <b>PA30113</b> <b>Cab Air</b> (82348995)..... <b>PA30114</b> <b>Coolant</b> (16998307)..... <b>BW5141</b> <b>Trans. Ele.</b> (Gearbox VT/VTO) (1521527)..... <b>PT9417</b> <b>Trans. Spin-on</b> (powertronic gearbox) (110366077)..... <b>BT8851-MPG</b> <b>Steering</b> (3496197)..... <b>P106-HD</b> <b>Urea</b> (21516229)..... <b>PE17000</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>VOLVO</b> European Trucks, Vans (cont'd)	<b>VOLVO</b> European Trucks, Vans (cont'd)	<b>VOLVO</b> European Trucks, Vans (cont'd)
FL Serie FL180 w/D6A/B180 Engs. (05/00-07/06) F-F Lube (21707133)..... [2] B76 + F-F Lube (Upgrade)..... [2] B76-SS + B-P Lube (4775565)..... B7685 Fuel/Water Separator (20386080)..... BF1398-O Fuel (420799)..... BF7644 Fuel/Water Separator (20386081)..... BF46025-O Air (3120490)..... PA4929 Cab Air (6774452)..... PA2101A Air Dryer (20557234)..... BA5379 + Trans. Ele. (85104633)..... PT9417 Trans. Spin-on (110366077)..... BT8851-MPG	FL II Serie FL260 w/D7F260 (Euro 5) (2009-on) Lube (20998807)..... P7329 Fuel (21276079)..... PF7938 Fuel/Water Separator (21380403)..... BF1388-O Radial Seal O. Air (20732726)..... RS5390 Radial Seal I. Air (20732728)..... RS5351 Cab Air (20559447)..... PA30188 Air Dryer (21267818)..... BA5566 Trans. Ele. (85104633)..... PT9417 Trans. Spin-on (110366077)..... BT8851-MPG Urea (21333097)..... PE5271 FL II Serie FL280 w/D7E/280 (Euro 4-5) (04/06-on) Lube (20998807)..... P7329 Fuel/Water Separator (20853583)..... BF1388-O Fuel (20796775)..... PF7938 Radial Seal O. Air (20732726)..... RS5390 Radial Seal I. Air (20732728)..... RS5351 Cab Air (20559447)..... PA30188 Air Dryer (21267818)..... BA5566 Trans. Ele. (85104633)..... PT9417 Trans. Spin-on (110366077)..... BT8851-MPG Urea (21333097)..... PE5271 FL II Serie FL290 w/D7F290 (Euro 5) (2009-on) Lube (20998807)..... P7329 Fuel (21276079)..... PF7938 Fuel/Water Separator (21380403)..... BF1388-O Radial Seal O. Air (20732726)..... RS5390 Radial Seal I. Air (20732728)..... RS5351 Cab Air (20559447)..... PA30188 Air Dryer (21267818)..... BA5566 Trans. Ele. (85104633)..... PT9417 Trans. Spin-on (110366077)..... BT8851-MPG Urea (21333097)..... PE5271 FL Serie FL608 w/D6A Eng. (01/95-09/00) F-F Lube (21707133)..... [2] B76 + F-F Lube (Upgrade)..... [2] B76-SS + B-P Lube (4775565)..... B7685 Fuel (4669875)..... BF988 + Air (6776714)..... PA2785 Cab Air (6774452)..... PA2101A Air Dryer (3090288)..... BA5374 + Steering (3496197)..... P106-HD FL Serie FL611 w/D6A Eng. (01/95-08/00) F-F Lube (21707133)..... [2] B76 + F-F Lube (Upgrade)..... [2] B76-SS + B-P Lube (4775565)..... B7685 Fuel (4669875)..... BF988 + Air (6776714)..... PA2785 Cab Air (6774452)..... PA2101A Air Dryer (3090288)..... BA5374 + Steering (3496197)..... P106-HD	FL Serie FL612 w/D6A Eng. (01/95-08/00) F-F Lube (21707133)..... [2] B76 + F-F Lube (Upgrade)..... [2] B76-SS + B-P Lube (4775565)..... B7685 Fuel (4669875)..... BF988 + Air (6776714)..... PA2785 Cab Air (6774452)..... PA2101A Air Dryer (3090288)..... BA5374 + Steering (3496197)..... P106-HD FL Serie FL613 w/D6A Eng. (2000-on) F-F Lube (21707133)..... B76 + F-F Lube (Upgrade)..... B76-SS + B-P Lube (4775565)..... B7685 Fuel (420799)..... BF7644 Air (3120490)..... PA4929 Cab Air (6774452)..... PA2101A FL Serie FL614 w/D6A Eng. (01/95-08/00) F-F Lube (21707133)..... [2] B76 + F-F Lube (Upgrade)..... [2] B76-SS + B-P Lube (4775565)..... B7685 Fuel (4669875)..... BF988 + Air (6776714)..... PA2785 Cab Air (6774452)..... PA2101A Air Dryer (3090288)..... BA5374 + Steering (3496197)..... P106-HD FL Serie FL615 w/D6A Eng. (01/95-08/00) F-F Lube (21707133)..... [2] B76 + F-F Lube (Upgrade)..... [2] B76-SS + B-P Lube (4775565)..... B7685 Fuel (4669875)..... BF988 + Air (6776714)..... PA2785 Cab Air (6774452)..... PA2101A Air Dryer (3090288)..... BA5374 + Steering (3496197)..... P106-HD FL Serie FL618 w/D6A Eng. (01/95-08/00) F-F Lube (21707133)..... [2] B76 + F-F Lube (Upgrade)..... [2] B76-SS + B-P Lube (4775565)..... B7685 Fuel (4669875)..... BF988 + Air (6776714)..... PA2785 Cab Air (6774452)..... PA2101A Air Dryer (3090288)..... BA5374 + Steering (3496197)..... P106-HD FL Serie FL621 w/D6A Eng. (2000-on) F-F Lube (21707133)..... B76 + F-F Lube (Upgrade)..... B76-SS + B-P Lube (4775565)..... B7685 Fuel (420799)..... BF7644 Air (3120490)..... PA4929 Cab Air (6774452)..... PA2101A FL Serie FL626 w/D6A Eng. (2000-on) F-F Lube (21707133)..... B76 + F-F Lube (Upgrade)..... B76-SS + B-P Lube (4775565)..... B7685 Fuel (420799)..... BF7644 Air (3120490)..... PA4929 Cab Air (6774452)..... PA2101A
<p>* See Product Guide for Variations of This Number. Check Original Equipment Numbers In Parentheses.</p>		

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



VOLVO European Trucks, Vans (cont'd)	VOLVO European Trucks, Vans (cont'd)	VOLVO European Trucks, Vans (cont'd)
<b>FL I w/D6A/B Engs (2000-06)</b> <b>F-F Lube</b> (466634)..... <b>B76 +</b> <b>B-P Lube</b> (4775565)..... <b>B7685</b> <b>Severe Service F-F Lube</b> (466634)..... <b>B76-SS +</b> <b>Fuel/Water Separator</b> (20386080)..... <b>BF1398-O</b> <b>Fuel</b> (8193841)..... <b>BF7653</b> <b>Fuel/Water Separator</b> (20386081)..... <b>BF46025-O</b> <b>Cab Air</b> (6774452)..... <b>PA2101A</b> <hr/> <b>FL II w/D7E/F Engs. (2006-on)</b> <b>Lube</b> (20796785)..... <b>P7329</b> <b>Fuel/Water Separator</b> (20853583)..... <b>BF1388-O</b> <b>Fuel</b> (20796775)..... <b>PF7938</b> <b>Radial Seal O. Air</b> (20732726)..... <b>RS5390</b> <b>Radial Seal I. Air</b> (20732728)..... <b>RS5351</b> <b>Cab Air</b> (20559447)..... <b>PA30188</b> <hr/> <b>FM 7 Serie FM7-230 w/D7A230 Eng.</b> (01/99-02/02) <b>F-F Lube</b> (21707133)..... <b>[2] B76 +</b> <b>F-F Lube</b> (Upgrade)..... <b>[2] B76-SS +</b> <b>B-P Lube</b> (4775565)..... <b>B7685</b> <b>Fuel/Water Separator</b> (w/Drain) (81599755)..... <b>BF1329</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (81599755)..... <b>BF46083-O</b> <b>Fuel/Water Separator</b> (w/Bowl) (81599755)..... <b>BF46072</b> <b>Fuel/Water Separator</b> (w/Sensor Port Thd. 9/16-18) (81599755)..... <b>BF1329-SP</b> <b>Fuel/Water Separator</b> (w/Sensor Port Thd. 1/2-20) (81599755)..... <b>BF1339-SP +</b> <b>Fuel</b> (420799)..... <b>BF7644</b> <b>Radial Seal O. Air</b> (21834199)..... <b>RS4966</b> <b>Radial Seal I. Air</b> (3979928)..... <b>RS5408</b> <b>Cab Air</b> (8143691)..... <b>PA3839</b> <b>Trans. Ele.</b> (85104633)..... <b>PT9417</b> <b>Trans. Spin-on</b> (110366077)..... <b>BT8851-MPG</b> <b>Steering</b> (3496197)..... <b>P106-HD</b> <hr/> <b>FM 7 Serie FM7-250 w/D7C250 Eng.</b> (08/98-02/02) <b>F-F Lube</b> (21707133)..... <b>[2] B76 +</b> <b>F-F Lube</b> (Upgrade)..... <b>[2] B76-SS +</b> <b>B-P Lube</b> (4775565)..... <b>B7685</b> <b>Fuel/Water Separator</b> (w/Drain) (81599755)..... <b>BF1329</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (81599755)..... <b>BF46083-O</b> <b>Fuel/Water Separator</b> (w/Bowl) (81599755)..... <b>BF46072</b> <b>Fuel/Water Separator</b> (w/Sensor Port Thd. 9/16-18) (81599755)..... <b>BF1329-SP</b> <b>Fuel/Water Separator</b> (w/Sensor Port Thd. 1/2-20) (81599755)..... <b>BF1339-SP +</b> <b>Fuel</b> (420799)..... <b>BF7644</b> <b>Radial Seal O. Air</b> (21834199)..... <b>RS4966</b> <b>Radial Seal I. Air</b> (3979928)..... <b>RS5408</b> <b>Cab Air</b> (8143691)..... <b>PA3839</b> <b>Trans. Ele.</b> (85104633)..... <b>PT9417</b> <b>Trans. Spin-on</b> (110366077)..... <b>BT8851-MPG</b> <b>Steering</b> (3496197)..... <b>P106-HD</b> <hr/> <b>FM 7 Serie FM7-290 w/D7C290 Eng.</b> (08/98-02/02) <b>F-F Lube</b> (21707133)..... <b>[2] B76 +</b> <b>F-F Lube</b> (Upgrade)..... <b>[2] B76-SS +</b> <b>B-P Lube</b> (4775565)..... <b>B7685</b> <b>Fuel/Water Separator</b> (w/Drain) (81599755)..... <b>BF1329</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (81599755)..... <b>BF46083-O</b> <b>Fuel/Water Separator</b> (w/Bowl) (81599755)..... <b>BF46072</b> <b>Fuel/Water Separator</b> (w/Sensor Port Thd. 9/16-18) (81599755)..... <b>BF1329-SP</b> <b>Fuel/Water Separator</b> (w/Sensor Port Thd. 1/2-20) (81599755)..... <b>BF1339-SP +</b> <b>Fuel</b> (420799)..... <b>BF7644</b> <b>Radial Seal O. Air</b> (21834199)..... <b>RS4966</b> <b>Radial Seal I. Air</b> (3979928)..... <b>RS5408</b> <b>Cab Air</b> (8143691)..... <b>PA3839</b> <b>Trans. Ele.</b> (85104633)..... <b>PT9417</b> <b>Trans. Spin-on</b> (110366077)..... <b>BT8851-MPG</b> <b>100.8 mm Steering</b> (3496197)..... <b>P106-HD</b> <b>116.7 mm Steering</b> (1585618)..... <b>PT9131</b> <hr/> <b>FM 9 Serie FM9-260 w/D9A Eng. (11/01-on)</b> <b>F-F Lube</b> (21707133)..... <b>[2] B76 +</b> <b>F-F Lube</b> (Upgrade) (478736-2)..... <b>[2] B76-SS +</b> <b>B-P Lube</b> (477556-5)..... <b>B7685</b> 	<b>FM 7 Serie FM7-250 w/D7C250 Eng.</b> (08/98-02/02) (Cont'd) <b>Radial Seal I. Air</b> (3979928)..... <b>RS5408</b> <b>Cab Air</b> (8143691)..... <b>PA3839</b> <b>Trans. Ele.</b> (85104633)..... <b>PT9417</b> <b>Trans. Spin-on</b> (110366077)..... <b>BT8851-MPG</b> <b>100.8 mm Steering</b> (3496197)..... <b>P106-HD</b> <b>116.7 mm Steering</b> (1585618)..... <b>PT9131</b> <hr/> <b>FM 7 Serie FM7-260 w/D7A260 Eng.</b> (01/99-02/02) <b>F-F Lube</b> (21707133)..... <b>[2] B76 +</b> <b>F-F Lube</b> (Upgrade)..... <b>[2] B76-SS +</b> <b>B-P Lube</b> (4775565)..... <b>B7685</b> <b>Fuel/Water Separator</b> (w/Drain) (81599755)..... <b>BF1329</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (81599755)..... <b>BF46083-O</b> <b>Fuel/Water Separator</b> (w/Bowl) (81599755)..... <b>BF46072</b> <b>Fuel/Water Separator</b> (w/Sensor Port Thd. 9/16-18) (81599755)..... <b>BF1329-SP</b> <b>Fuel/Water Separator</b> (w/Sensor Port Thd. 1/2-20) (81599755)..... <b>BF1339-SP +</b> <b>Fuel</b> (420799)..... <b>BF7644</b> <b>Radial Seal O. Air</b> (21834199)..... <b>RS4966</b> <b>Radial Seal I. Air</b> (3979928)..... <b>RS5408</b> <b>Cab Air</b> (8143691)..... <b>PA3839</b> <b>Trans. Ele.</b> (85104633)..... <b>PT9417</b> <b>Trans. Spin-on</b> (110366077)..... <b>BT8851-MPG</b> <b>Steering</b> (3496197)..... <b>P106-HD</b> <hr/> <b>FM 7 Serie FM7-290 w/D7C290 Eng.</b> (08/98-02/02) <b>F-F Lube</b> (21707133)..... <b>[2] B76 +</b> <b>F-F Lube</b> (Upgrade)..... <b>[2] B76-SS +</b> <b>B-P Lube</b> (4775565)..... <b>B7685</b> <b>Fuel/Water Separator</b> (w/Drain) (81599755)..... <b>BF1329</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (81599755)..... <b>BF46083-O</b> <b>Fuel/Water Separator</b> (w/Bowl) (81599755)..... <b>BF46072</b> <b>Fuel/Water Separator</b> (w/Sensor Port Thd. 9/16-18) (81599755)..... <b>BF1329-SP</b> <b>Fuel/Water Separator</b> (w/Sensor Port Thd. 1/2-20) (81599755)..... <b>BF1339-SP +</b> <b>Fuel</b> (420799)..... <b>BF7644</b> <b>Radial Seal O. Air</b> (21834199)..... <b>RS4966</b> <b>Radial Seal I. Air</b> (3979928)..... <b>RS5408</b> <b>Cab Air</b> (8143691)..... <b>PA3839</b> <b>Trans. Ele.</b> (85104633)..... <b>PT9417</b> <b>Trans. Spin-on</b> (110366077)..... <b>BT8851-MPG</b> <b>Steering</b> (3496197)..... <b>P106-HD</b> <hr/> <b>FM 9 Serie FM9-300 w/D9A Eng. (11/01-on)</b> <b>F-F Lube</b> (21707133)..... <b>[2] B76 +</b> <b>F-F Lube</b> (Upgrade) (478736-2)..... <b>[2] B76-SS +</b> <b>B-P Lube</b> (477556-5)..... <b>B7685</b> <b>89.7 mm Fuel Water Separator</b> (20381204)..... <b>BF1389-O</b> <b>142.9 mm Fuel Water Separator</b> (20998367)..... <b>BF1366-O</b> <b>157.2 mm Fuel Water Separator</b> (20450423)..... <b>BF1390-O</b> <b>Fuel</b> (20430751)..... <b>BF7814</b> <b>Fuel</b> (22480372)..... <b>BF46161</b> <b>Radial Seal O. Air</b> (8149064)..... <b>RS4966</b> <b>Radial Seal I. Air</b> (21041296)..... <b>RS5408</b> <b>Cab Air</b> (Mann CU2184)..... <b>PA3839</b> <b>Air Dryer</b> (3097369)..... <b>BA16000</b> <b>Coolant</b> (21192875)..... <b>BW5141</b> <b>Trans. Ele.</b> (85104633)..... <b>PT9417</b> <b>Trans. Spin-on</b> (110366077)..... <b>BT8851-MPG</b> <b>Steering</b> (3496197)..... <b>P106-HD</b> <hr/> <b>FM 9 Serie FM9-340 w/D9A Eng. (11/01-on)</b> <b>F-F Lube</b> (21707133)..... <b>[2] B76 +</b> <b>F-F Lube</b> (Upgrade) (478736-2)..... <b>[2] B76-SS +</b> <b>B-P Lube</b> (477556-5)..... <b>B7685</b> <b>89.7 mm Fuel Water Separator</b> (20381204)..... <b>BF1389-O</b> <b>142.9 mm Fuel Water Separator</b> (20998367)..... <b>BF1366-O</b> <b>157.2 mm Fuel Water Separator</b> (20450423)..... <b>BF1390-O</b> <b>Fuel</b> (20430751)..... <b>BF7814</b> <b>Fuel</b> (22480372)..... <b>BF46161</b> <b>Radial Seal O. Air</b> (8149064)..... <b>RS4966</b> <b>Radial Seal I. Air</b> (21041296)..... <b>RS5408</b> <b>Cab Air</b> (Mann CU2184)..... <b>PA3839</b> <b>Air Dryer</b> (3097369)..... <b>BA16000</b> <b>Coolant</b> (21192875)..... <b>BW5141</b> <b>Trans. Ele.</b> (85104633)..... <b>PT9417</b> <b>Trans. Spin-on</b> (110366077)..... <b>BT8851-MPG</b> <b>Steering</b> (3496197)..... <b>P106-HD</b>	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>VOLVO</b> European Trucks, Vans (cont'd)	<b>VOLVO</b> European Trucks, Vans (cont'd)	<b>VOLVO</b> European Trucks, Vans (cont'd)
<b>FM 9 Serie FM9-380 w/D9A Eng. (11/01-on)</b> <b>F-F Lube (21707133)..... [2] B76 +</b> <b>F-F Lube (Upgrade) (478736-2).... [2] B76-SS +</b> <b>B-P Lube (477556-5)..... B7685</b> <b>89.7 mm Fuel Water Separator</b> (20381204)..... <b>BF1389-O</b> <b>142.9 mm Fuel Water Separator</b> (20998367)..... <b>BF1366-O</b> <b>157.2 mm Fuel Water Separator</b> (20450423)..... <b>BF1390-O</b> <b>Fuel (20430751)..... BF7814</b> <b>Fuel (22480372)..... BF46161</b> <b>Radial Seal O. Air (8149064)..... RS4966</b> <b>Radial Seal I. Air (21041296)..... RS5408</b> <b>Cab Air (Mann CU2184)..... PA3839</b> <b>Air Dryer (3097369)..... BA16000</b> <b>Coolant (21192875)..... BW5141</b> <b>Trans. Ele. (85104633)..... PT9417</b> <b>Trans. Spin-on (110366077)..... BT8851-MPG</b> <b>Steering (3496197)..... P106-HD</b>	<b>FM 10 Serie FM10-360 w/D10B-360 Eng. (08/98-on) (Cont'd)</b> <b>Fuel/Water Separator (w/Sensor Port Thd. 1/2-20) (8159975)..... BF1339-SP +</b> <b>Fuel/Water Separator (Open End for Bowl) (20450423)..... BF1390-O</b> <b>Fuel (420799)..... BF7644</b> <b>Radial Seal O. Air (8149064)..... RS4966</b> <b>Radial Seal I. Air (21041296)..... RS5408</b> <b>Cab Air (8143691)..... PA3839</b> <b>Air Dryer (3097369)..... BA16000</b> <b>Coolant (21192875)..... BW5141</b> <b>Steering (3496197)..... P106-HD</b> <b>FM 12 Serie FM12-340 w/D12C Eng. (08/98-01/02)</b> <b>F-F Lube (4666343)..... [2] B76 +</b> <b>F-F Lube (Upgrade)..... [2] B76-SS +</b> <b>B-P Lube (4775565)..... B7685</b> <b>Fuel/Water Separator..... BF1349</b> <b>Fuel Spin-on (420799)..... BF7644</b> <b>Radial Seal O. Air (8149064)..... RS4966</b> <b>Radial Seal I. Air (3979928)..... RS5408</b> <b>Cab Air (4771477)..... PA3414</b> <b>Air Dryer (3097369)..... BA16000</b> <b>Coolant (21192875)..... BW5141</b> <b>Trans. Ele. (85104633)..... PT9417</b> <b>Trans. Spin-on (110366077)..... BT8851-MPG</b> <b>100.8 mm Steering (3496197)..... P106-HD</b> <b>115.9 mm Steering (323139)..... PT691</b> <b>116.7 mm Steering (1585618)..... PT9131</b>	<b>FM 12 Serie FM12-380 w/D12C Eng. (08/98-01/02) (Cont'd)</b> <b>Radial Seal I. Air (3979928)..... RS5408</b> <b>Cab Air (4771477)..... PA3414</b> <b>Air Dryer (3097369)..... BA16000</b> <b>Coolant (21192875)..... BW5141</b> <b>Trans. Ele. (85104633)..... PT9417</b> <b>Trans. Spin-on (110366077)..... BT8851-MPG</b> <b>100.8 mm Steering (3496197)..... P106-HD</b> <b>115.9 mm Steering (323139)..... PT691</b> <b>116.7 mm Steering (1585618)..... PT9131</b> <b>FM 12 Serie FM12-380 w/D12D Eng. (11/01-on)</b> <b>F-F Lube (4666343)..... [2] B76 +</b> <b>F-F Lube (Upgrade) (4787362).... [2] B76-SS +</b> <b>B-P Lube (477556)..... B7685</b> <b>Fuel/Water Separator</b> (20381204)..... <b>BF1389-O</b> <b>Fuel Spin-on (20976003)..... BF7814</b> <b>Radial Seal O. Air (21834199).... RS4966</b> <b>Radial Seal I. Air (3979928)..... RS5408</b> <b>I. Air (Mann C16167)..... PA2787</b> <b>210.3 mm Length Cab Air</b> (8143691)..... <b>PA3839</b> <b>269.9 mm Length Cab Air (Mann CU2785)..... PA3414</b> <b>Air Dryer (3097369)..... BA16000</b> <b>Coolant (21192875)..... BW5141</b> <b>Trans. Ele. (85104633)..... PT9417</b> <b>Trans. Spin-on (110366077)..... BT8851-MPG</b> <b>100.8 mm Steering (V349619)..... P106-HD</b> <b>115.9 mm Steering (323139)..... PT691</b> <b>FM 12 Serie FM12-420 w/D12C Eng. (08/98-01/02)</b> <b>F-F Lube (4666343)..... [2] B76 +</b> <b>F-F Lube (Upgrade)..... [2] B76-SS +</b> <b>B-P Lube (4775565)..... B7685</b> <b>Fuel/Water Separator..... BF1349</b> <b>Fuel Spin-on (420799)..... BF7644</b> <b>Radial Seal O. Air (8149064)..... RS4966</b> <b>Radial Seal I. Air (3979928)..... RS5408</b> <b>Cab Air (4771477)..... PA3414</b> <b>Air Dryer (3097369)..... BA16000</b> <b>Coolant (21192875)..... BW5141</b> <b>Trans. Ele. (85104633)..... PT9417</b> <b>Trans. Spin-on (110366077)..... BT8851-MPG</b> <b>100.8 mm Steering (3496197).... P106-HD</b> <b>115.9 mm Steering (323139)..... PT691</b> <b>116.7 mm Steering (1585618)..... PT9131</b> <b>FM 12 Serie FM12-420 w/D12D Eng. (11/01-on)</b> <b>F-F Lube (4666343)..... [2] B76 +</b> <b>F-F Lube (Upgrade) (4787362).... [2] B76-SS +</b> <b>B-P Lube (477556)..... B7685</b> <b>Fuel/Water Separator</b> (20381204)..... <b>BF1389-O</b> <b>Fuel Spin-on (20976003)..... BF7814</b> <b>Radial Seal O. Air (21834199).... RS4966</b> <b>Radial Seal I. Air (3979928)..... RS5408</b> <b>I. Air (Mann C16167)..... PA2787</b>
<b>FM 10 Serie FM10-320 w/D10B-320 Eng. (08/98-on)</b> <b>F-F Lube (21707133)..... [2] B76 +</b> <b>F-F Lube (Upgrade)..... [2] B76-SS +</b> <b>B-P Lube (4775565)..... B7685</b> <b>Fuel/Water Separator (Open End for Bowl) (8159975)..... BF46083-O</b> <b>Fuel/Water Separator (w/Bowl) (8159975)..... BF46072</b> <b>Fuel/Water Separator (w/Drain) (8159975)..... BF1329</b> <b>Fuel/Water Separator (w/Sensor Port Thd. 9/16-18) (8159975)..... BF1329-SP</b> <b>Fuel/Water Separator (w/Sensor Port Thd. 1/2-20) (8159975)..... BF1339-SP +</b> <b>Fuel/Water Separator (Open End for Bowl) (20450423)..... BF1390-O</b> <b>Fuel (420799)..... BF7644</b> <b>Radial Seal O. Air (8149064)..... RS4966</b> <b>Radial Seal I. Air (21041296)..... RS5408</b> <b>Cab Air (8143691)..... PA3839</b> <b>Air Dryer (3097369)..... BA16000</b> <b>Coolant (21192875)..... BW5141</b> <b>Trans. Ele. (85104633)..... PT9417</b> <b>Trans. Spin-on (110366077)..... BT8851-MPG</b> <b>Steering (3496197)..... P106-HD</b>	<b>FM 12 Serie FM12-340 w/D12D Eng. (11/01-on)</b> <b>F-F Lube (4666343)..... [2] B76 +</b> <b>F-F Lube (Upgrade) (4787362).... [2] B76-SS +</b> <b>B-P Lube (477556)..... B7685</b> <b>Fuel/Water Separator</b> (20381204)..... <b>BF1389-O</b> <b>Fuel Spin-on (20976003)..... BF7814</b> <b>Radial Seal O. Air (21834199).... RS4966</b> <b>Radial Seal I. Air (3979928)..... RS5408</b> <b>I. Air (Mann C16167)..... PA2787</b> <b>210.3 mm Length Cab Air</b> (8143691)..... <b>PA3839</b> <b>269.9 mm Length Cab Air (Mann CU2785)..... PA3414</b> <b>Air Dryer (3097369)..... BA16000</b> <b>Coolant (21192875)..... BW5141</b> <b>Trans. Ele. (85104633)..... PT9417</b> <b>Trans. Spin-on (110366077)..... BT8851-MPG</b> <b>100.8 mm Steering (V349619).... P106-HD</b> <b>115.9 mm Steering (323139)..... PT691</b>	<b>FM 12 Serie FM12-380 w/D12C Eng. (08/98-01/02)</b> <b>F-F Lube (4666343)..... [2] B76 +</b> <b>F-F Lube (Upgrade)..... [2] B76-SS +</b> <b>B-P Lube (477556)..... B7685</b> <b>Fuel/Water Separator..... BF1349</b> <b>Fuel Spin-on (420799)..... BF7644</b> <b>Radial Seal O. Air (8149064)..... RS4966</b> <b>Radial Seal I. Air (3979928)..... RS5408</b> <b>Cab Air (4771477)..... PA3414</b> <b>Air Dryer (3097369)..... BA16000</b> <b>Coolant (21192875)..... BW5141</b> <b>Trans. Ele. (85104633)..... PT9417</b> <b>Trans. Spin-on (110366077)..... BT8851-MPG</b> <b>100.8 mm Steering (3496197).... P106-HD</b> <b>115.9 mm Steering (323139)..... PT691</b> <b>116.7 mm Steering (1585618)..... PT9131</b>
<b>FM 10 Serie FM10-360 w/D10B-360 Eng. (08/98-on)</b> <b>F-F Lube (21707133)..... [2] B76 +</b> <b>F-F Lube (Upgrade)..... [2] B76-SS +</b> <b>B-P Lube (4775565)..... B7685</b> <b>Fuel/Water Separator (w/Drain) (8159975)..... BF1329</b> <b>Fuel/Water Separator (Open End for Bowl) (8159975)..... BF46083-O</b> <b>Fuel/Water Separator (w/Bowl) (8159975)..... BF46072</b> <b>Fuel/Water Separator (w/Sensor Port Thd. 9/16-18) (8159975)..... BF1329-SP</b>	<b>FM 12 Serie FM12-380 w/D12C Eng. (08/98-01/02)</b> <b>F-F Lube (4666343)..... [2] B76 +</b> <b>F-F Lube (Upgrade)..... [2] B76-SS +</b> <b>B-P Lube (4775565)..... B7685</b> <b>Fuel/Water Separator..... BF1349</b> <b>Fuel Spin-on (420799)..... BF7644</b> <b>Radial Seal O. Air (8149064)..... RS4966</b>	

+ See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

VOLVO European Trucks, Vans (cont'd)	VOLVO European Trucks, Vans (cont'd)	VOLVO European Trucks, Vans (cont'd)
<b>FM 12 Serie FM12-420 w/D12D Eng. (11/01-on) (Cont'd)</b> <b>210.3 mm Length Cab Air</b> (8143691)..... <b>PA3839</b> <b>269.9 mm Length Cab Air (Mann CU2785)</b> ..... <b>PA3414</b> <b>Air Dryer (3097369)</b> ..... <b>BA16000</b> <b>Coolant (21192875)</b> ..... <b>BW5141</b> <b>Trans. Ele. (85104633)</b> ..... <b>PT9417</b> <b>Trans. Spin-on (110366077)</b> ..... <b>BT8851-MPG</b> <b>100.8 mm Steering (V349619)</b> ..... <b>P106-HD</b> <b>115.9 mm Steering (323139)</b> ..... <b>PT691</b>	<b>FM Serie FM 330 w/D11C Euro 5 Eng. (2009-on) (Cont'd)</b> <b>Fuel/Water Separator (21380488)</b> ..... <b>BF1387-O</b> <b>Radial Seal O. Air (21834199)</b> ..... <b>RS4966</b> <b>Radial Seal I. Air (21041296)</b> ..... <b>RS5408</b> <b>Cab Air (8143691)</b> ..... <b>PA3839</b> <b>Air Dryer (3097369)</b> ..... <b>BA16000</b> <b>Trans. (VT/VTO Serie) (85108176)</b> ..... <b>PT9417</b> <b>Trans. (I-Shift) (20779040)</b> ..... <b>PT9417</b> <b>Trans. (110366077)</b> ..... <b>BT8851-MPG</b> <b>Steering (3496197)</b> ..... <b>P106-HD</b> <b>Urea (21333097)</b> ..... <b>PE5271</b> <b>Urea (from 2011) (21516229)</b> ..... <b>PE17000</b>	<b>FM Serie FM 370 w/D11C Euro 5 Eng. (2009-on) (Cont'd)</b> <b>P. Fuel (20972293)</b> ..... <b>BF7943</b> <b>Fuel/Water Separator (21380488)</b> ..... <b>BF1387-O</b> <b>Radial Seal O. Air (21834199)</b> ..... <b>RS4966</b> <b>Radial Seal I. Air (21041296)</b> ..... <b>RS5408</b> <b>Cab Air (8143691)</b> ..... <b>PA3839</b> <b>Air Dryer (3097369)</b> ..... <b>BA16000</b> <b>Trans. (VT/VTO Serie) (85108176)</b> ..... <b>PT9417</b> <b>Trans. (I-Shift) (20779040)</b> ..... <b>PT9417</b> <b>Trans. (110366077)</b> ..... <b>BT8851-MPG</b> <b>Steering (3496197)</b> ..... <b>P106-HD</b> <b>Urea (21333097)</b> ..... <b>PE5271</b> <b>Urea (from 2011) (21516229)</b> ..... <b>PE17000</b>
<b>FM 12 Serie FM12-460 w/D12D Eng. (05/03-on)</b> <b>F-F Lube (4666343)</b> ..... <b>[2] B76 +</b> <b>F-F Lube (Upgrade) (4787362)</b> ..... <b>[2] B76-SS +</b> <b>B-P Lube (477556)</b> ..... <b>B7685</b> <b>Fuel/Water Separator (20381204)</b> ..... <b>BF1389-O</b> <b>123.0 mm Fuel (4669875)</b> ..... <b>[2] BF988 +</b> <b>265.9 mm Fuel (20976003)</b> ..... <b>BF7814</b> <b>Radial Seal O. Air (21834199)</b> ..... <b>RS4966</b> <b>Radial Seal I. Air (3979928)</b> ..... <b>RS5408</b> <b>210.3 mm Length Cab Air (8143691)</b> ..... <b>PA3839</b> <b>269.9 mm Length Cab Air (Mann CU2785)</b> ..... <b>PA3414</b> <b>Air Dryer (3097369)</b> ..... <b>BA16000</b> <b>Coolant (21192875)</b> ..... <b>BW5141</b> <b>Trans. Ele. (85104633)</b> ..... <b>PT9417</b> <b>Trans. Spin-on (110366077)</b> ..... <b>BT8851-MPG</b> <b>100.8 mm Steering (V349619)</b> ..... <b>P106-HD</b> <b>115.9 mm Some Steering (323139)</b> ..... <b>PT691</b>	<b>FM Serie FM340 w/D9B-340 Eng. (09/05-on)</b> <b>F-F Lube (21707133)</b> ..... <b>[2] B76 +</b> <b>F-F Lube (Upgrade)</b> ..... <b>[2] B76-SS +</b> <b>B-P Lube (4775565)</b> ..... <b>B7685</b> <b>131.8 mm Fuel/Water Separator (21380475)</b> ..... <b>BF1386-O</b> <b>130.2 mm Fuel/Water Separator (20853583)</b> ..... <b>BF1388-O</b> <b>P. Fuel (20972293)</b> ..... <b>BF7943</b> <b>Radial Seal O. Air (8149064)</b> ..... <b>RS4966</b> <b>Radial Seal I. Air (21041296)</b> ..... <b>RS5408</b> <b>Cab Air (8143691)</b> ..... <b>PA3839</b> <b>Air Dryer (3097369)</b> ..... <b>BA16000</b> <b>Trans. Ele. (85104633)</b> ..... <b>PT9417</b> <b>Trans. Spin-on (110366077)</b> ..... <b>BT8851-MPG</b> <b>Steering (3496197)</b> ..... <b>P106-HD</b> <b>Urea (21333097)</b> ..... <b>PE5271</b>	<b>FM Serie FM380 w/D9B-380 Eng. (09/05-on)</b> <b>F-F Lube (21707133)</b> ..... <b>[2] B76 +</b> <b>F-F Lube (Upgrade)</b> ..... <b>[2] B76-SS +</b> <b>B-P Lube (4775565)</b> ..... <b>B7685</b> <b>131.8 mm Fuel/Water Separator (21380475)</b> ..... <b>BF1386-O</b> <b>130.2 mm Fuel/Water Separator (20853583)</b> ..... <b>BF1388-O</b> <b>P. Fuel (20972293)</b> ..... <b>BF7943</b> <b>Radial Seal O. Air (8149064)</b> ..... <b>RS4966</b> <b>Radial Seal I. Air (21041296)</b> ..... <b>RS5408</b> <b>Cab Air (8143691)</b> ..... <b>PA3839</b> <b>Air Dryer (3097369)</b> ..... <b>BA16000</b> <b>Trans. Ele. (85104633)</b> ..... <b>PT9417</b> <b>Trans. Spin-on (110366077)</b> ..... <b>BT8851-MPG</b> <b>Steering (3496197)</b> ..... <b>P106-HD</b> <b>Urea (21333097)</b> ..... <b>PE5271</b>
<b>FM Serie FM300 w/D9B-300 Eng. (09/05-on)</b> <b>F-F Lube (21707133)</b> ..... <b>[2] B76 +</b> <b>F-F Lube (Upgrade)</b> ..... <b>[2] B76-SS +</b> <b>B-P Lube (4775565)</b> ..... <b>B7685</b> <b>131.8 mm Fuel/Water Separator (21380475)</b> ..... <b>BF1386-O</b> <b>130.2 mm Fuel/Water Separator (20853583)</b> ..... <b>BF1388-O</b> <b>P. Fuel (20972293)</b> ..... <b>BF7943</b> <b>Radial Seal O. Air (8149064)</b> ..... <b>RS4966</b> <b>Radial Seal I. Air (21041296)</b> ..... <b>RS5408</b> <b>Cab Air (8143691)</b> ..... <b>PA3839</b> <b>Air Dryer (3097369)</b> ..... <b>BA16000</b> <b>Trans. Ele. (85104633)</b> ..... <b>PT9417</b> <b>Trans. Spin-on (110366077)</b> ..... <b>BT8851-MPG</b> <b>Steering (3496197)</b> ..... <b>P106-HD</b> <b>Urea (21333097)</b> ..... <b>PE5271</b>	<b>FM Serie FM360 w/D13A-360 Eng. (09/05-on)</b> <b>F-F Lube (21707133)</b> ..... <b>[2] B76 +</b> <b>F-F Lube (Upgrade)</b> ..... <b>[2] B76-SS +</b> <b>B-P Lube (4775565)</b> ..... <b>B7685</b> <b>160.3 mm Fuel/Water Separator (20879812)</b> ..... <b>BF1387-O</b> <b>P. Fuel (20976003)</b> ..... <b>BF7814</b> <b>Fuel/Water Separator (20514654)</b> ..... <b>BF1366-O</b> <b>Radial Seal Air (8149961)</b> ..... <b>RS4967</b> <b>Radial Seal Air (w/FRM) (21834210)</b> ..... <b>RS5776</b> <b>I. Air (1665937)</b> ..... <b>PA3925</b> <b>Cab Air (8143691)</b> ..... <b>PA3839</b> <b>Air Dryer (3097369)</b> ..... <b>BA16000</b> <b>Trans. Ele. (85104633)</b> ..... <b>PT9417</b> <b>Trans. Spin-on (110366077)</b> ..... <b>BT8851-MPG</b> <b>Steering (3496197)</b> ..... <b>P106-HD</b> <b>Urea (21333097)</b> ..... <b>PE5271</b>	<b>FM Serie FM 380 w/D13C Euro 5 Eng. (2009-on)</b> <b>F-F Lube (21707133)</b> ..... <b>[2] B76 +</b> <b>F-F Lube (Upgrade)</b> ..... <b>[2] B76-SS +</b> <b>B-P Lube (4775565)</b> ..... <b>B7685</b> <b>Fuel/Water Separator (20998367)</b> ..... <b>BF1366-O</b> <b>P. Fuel (20976003)</b> ..... <b>BF7814</b> <b>P. Fuel (20972293)</b> ..... <b>BF7943</b> <b>Fuel/Water Separator (21380488)</b> ..... <b>BF1387-O</b> <b>Radial Seal O. Air (8149961)</b> ..... <b>RS4967</b> <b>Radial Seal Air (w/FRM) (21834210)</b> ..... <b>RS5776</b> <b>I. Air (1665937)</b> ..... <b>PA3925</b> <b>Cab Air (8143691)</b> ..... <b>PA3839</b> <b>Air Dryer (3097369)</b> ..... <b>BA16000</b> <b>Trans. (VT/VTO Serie) (85108176)</b> ..... <b>PT9417</b> <b>Trans. (I-Shift) (20779040)</b> ..... <b>PT9417</b> <b>Trans. (110366077)</b> ..... <b>BT8851-MPG</b> <b>Steering (3496197)</b> ..... <b>P106-HD</b> <b>Urea (21333097)</b> ..... <b>PE5271</b> <b>Urea (from 2011) (21516229)</b> ..... <b>PE17000</b>
<b>FM Serie FM 330 w/D11C Euro 5 Eng. (2009-on)</b> <b>F-F Lube (21707133)</b> ..... <b>[2] B76 +</b> <b>F-F Lube (Upgrade)</b> ..... <b>[2] B76-SS +</b> <b>B-P Lube (4775565)</b> ..... <b>B7685</b> <b>Fuel/Water Separator (20998367)</b> ..... <b>BF1366-O</b> <b>P. Fuel (20976003)</b> ..... <b>BF7814</b> <b>P. Fuel (20972293)</b> ..... <b>BF7943</b>	<b>FM Serie FM 370 w/D11C Euro 5 Eng. (2009-on)</b> <b>F-F Lube (21707133)</b> ..... <b>[2] B76 +</b> <b>F-F Lube (Upgrade)</b> ..... <b>[2] B76-SS +</b> <b>B-P Lube (4775565)</b> ..... <b>B7685</b> <b>Fuel/Water Separator (20998367)</b> ..... <b>BF1366-O</b> <b>P. Fuel (20976003)</b> ..... <b>BF7814</b>	

+ See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>VOLVO</b> European Trucks, Vans (cont'd)	<b>VOLVO</b> European Trucks, Vans (cont'd)	<b>VOLVO</b> European Trucks, Vans (cont'd)
<b>FM Serie FM400 w/D13A-400 Eng. (09/05-on)</b> <b>F-F Lube</b> (21707133)..... [2] B76 + <b>F-F Lube</b> (Upgrade)..... [2] B76-SS + <b>B-P Lube</b> (4775565)..... B7685 <b>160.3 mm Fuel/Water Separator</b> (20879812)..... BF1387-O <b>P. Fuel</b> (20976003)..... BF7814 <b>Fuel/Water Separator</b> (20514654)..... BF1366-O <b>Radial Seal Air</b> (8149961)..... RS4967 <b>Radial Seal Air</b> (w/FRM) (21834210)..... RS5776 <b>I. Air</b> (1665937)..... PA3925 <b>Cab Air</b> (8143691)..... PA3839 <b>Air Dryer</b> (3097369)..... BA16000 <b>Trans. Ele.</b> (85104633)..... PT9417 <b>Trans. Spin-on</b> (110366077)..... BT8851-MPG <b>Steering</b> (3496197)..... P106-HD <b>Urea</b> (21333097)..... PE5271	<b>FM Serie FM 420 w/D13C Euro 5 Eng. (2009-on) (Cont'd)</b> <b>Trans. (VT/VTO Serie)</b> (85108176)..... PT9417 <b>Trans. (I-Shift)</b> (20779040)..... PT9417 <b>Trans. (110366077)</b> ..... BT8851-MPG <b>Steering</b> (3496197)..... P106-HD <b>Urea</b> (21333097)..... PE5271 <b>Urea</b> (from 2011) (21516229)..... PE17000 <b>FM Serie FM440 w/D13A-440 Eng. (09/05-on)</b> <b>F-F Lube</b> (21707133)..... [2] B76 + <b>F-F Lube</b> (Upgrade)..... [2] B76-SS + <b>B-P Lube</b> (4775565)..... B7685 <b>160.3 mm Fuel/Water Separator</b> (20879812)..... BF1387-O <b>P. Fuel</b> (20976003)..... BF7814 <b>Fuel/Water Separator</b> (20514654)..... BF1366-O <b>Radial Seal Air</b> (8149961)..... RS4967 <b>Radial Seal Air</b> (w/FRM) (21834210)..... RS5776 <b>I. Air</b> (1665937)..... PA3925 <b>Cab Air</b> (8143691)..... PA3839 <b>Air Dryer</b> (3097369)..... BA16000 <b>Trans. Ele.</b> (85104633)..... PT9417 <b>Trans. Spin-on</b> (110366077)..... BT8851-MPG <b>Steering</b> (3496197)..... P106-HD <b>Urea</b> (21333097)..... PE5271	<b>FM Serie FM 460 w/D13C Euro 5 Eng. (2009-on) (Cont'd)</b> <b>P. Fuel</b> (20972293)..... BF7943 <b>Fuel/Water Separator</b> (21380488)..... BF1387-O <b>Radial Seal O. Air</b> (8149961)..... RS4967 <b>Radial Seal Air</b> (w/FRM) (21834210)..... RS5776 <b>I. Air</b> (1665937)..... PA3925 <b>Cab Air</b> (8143691)..... PA3839 <b>Air Dryer</b> (3097369)..... BA16000 <b>Trans. (VT/VTO Serie)</b> (85108176)..... PT9417 <b>Trans. (I-Shift)</b> (20779040)..... PT9417 <b>Trans. (110366077)</b> ..... BT8851-MPG <b>Steering</b> (3496197)..... P106-HD <b>Urea</b> (21333097)..... PE5271 <b>Urea</b> (from 2011) (21516229)..... PE17000 <b>FM Serie FM480 w/D13A-480 Eng. (09/05-on)</b> <b>F-F Lube</b> (21707133)..... [2] B76 + <b>F-F Lube</b> (Upgrade)..... [2] B76-SS + <b>B-P Lube</b> (4775565)..... B7685 <b>160.3 mm Fuel/Water Separator</b> (20879812)..... BF1387-O <b>P. Fuel</b> (20976003)..... BF7814 <b>Fuel/Water Separator</b> (20514654)..... BF1366-O <b>Radial Seal Air</b> (8149961)..... RS4967 <b>Radial Seal Air</b> (w/FRM) (21834210)..... RS5776 <b>I. Air</b> (1665937)..... PA3925 <b>Cab Air</b> (8143691)..... PA3839 <b>Air Dryer</b> (3097369)..... BA16000 <b>Trans. Ele.</b> (85104633)..... PT9417 <b>Trans. Spin-on</b> (110366077)..... BT8851-MPG <b>Steering</b> (3496197)..... P106-HD <b>Urea</b> (21333097)..... PE5271
<b>FM Serie FM 410 w/D11C Euro 5 Eng. (2009-on)</b> <b>F-F Lube</b> (21707133)..... [2] B76 + <b>F-F Lube</b> ..... [2] B76-SS + <b>B-P Lube</b> (4775565)..... B7685 <b>Fuel/Water Separator</b> (20998367)..... BF1366-O <b>P. Fuel</b> (20976003)..... BF7814 <b>P. Fuel</b> (20972293)..... BF7943 <b>Fuel/Water Separator</b> (21380488)..... BF1387-O <b>Radial Seal O. Air</b> (21834199)..... RS4966 <b>Radial Seal I. Air</b> (21041296)..... RS5408 <b>Cab Air</b> (8143691)..... PA3839 <b>Air Dryer</b> (3097369)..... BA16000 <b>Trans. (VT/VTO Serie)</b> (85108176)..... PT9417 <b>Trans. (I-Shift)</b> (20779040)..... PT9417 <b>Trans. (110366077)</b> ..... BT8851-MPG <b>Steering</b> (3496197)..... P106-HD <b>Urea</b> (21333097)..... PE5271 <b>Urea</b> (from 2011) (21516229)..... PE17000	<b>FM Serie FM 450 w/D11C Euro 5 Eng. (2009-on)</b> <b>F-F Lube</b> (21707133)..... [2] B76 + <b>F-F Lube</b> (Upgrade)..... [2] B76-SS + <b>B-P Lube</b> (4775565)..... B7685 <b>Fuel/Water Separator</b> (20998367)..... BF1366-O <b>P. Fuel</b> (20976003)..... BF7814 <b>P. Fuel</b> (20972293)..... BF7943 <b>Fuel/Water Separator</b> (21380488)..... BF1387-O <b>Radial Seal O. Air</b> (21834199)..... RS4966 <b>Radial Seal I. Air</b> (21041296)..... RS5408 <b>Cab Air</b> (8143691)..... PA3839 <b>Air Dryer</b> (3097369)..... BA16000 <b>Trans. (VT/VTO Serie)</b> (85108176)..... PT9417 <b>Trans. (I-Shift)</b> (20779040)..... PT9417 <b>Trans. (110366077)</b> ..... BT8851-MPG <b>Steering</b> (3496197)..... P106-HD <b>Urea</b> (21333097)..... PE5271 <b>Urea</b> (from 2011) (21516229)..... PE17000	<b>FM Serie FM 500 w/D13C Euro 5 Eng. (2009-on)</b> <b>F-F Lube</b> (21707133)..... [2] B76 + <b>F-F Lube</b> (Upgrade)..... [2] B76-SS + <b>B-P Lube</b> (4775565)..... B7685 <b>Fuel/Water Separator</b> (20998367)..... BF1366-O <b>P. Fuel</b> (20976003)..... BF7814 <b>P. Fuel</b> (20972293)..... BF7943 <b>Fuel/Water Separator</b> (21380488)..... BF1387-O <b>Radial Seal O. Air</b> (8149961)..... RS4967 <b>Radial Seal Air</b> (w/FRM) (21834210)..... RS5776 <b>I. Air</b> (1665937)..... PA3925 <b>Cab Air</b> (8143691)..... PA3839 <b>Air Dryer</b> (3097369)..... BA16000 <b>Trans. (VT/VTO Serie)</b> (85108176)..... PT9417 <b>Trans. (I-Shift)</b> (20779040)..... PT9417 <b>Trans. (110366077)</b> ..... BT8851-MPG <b>Steering</b> (3496197)..... P106-HD
<b>FM Serie FM 420 w/D13C Euro 5 Eng. (2009-on)</b> <b>F-F Lube</b> (21707133)..... [2] B76 + <b>F-F Lube</b> (Upgrade)..... [2] B76-SS + <b>B-P Lube</b> (4775565)..... B7685 <b>Fuel/Water Separator</b> (20998367)..... BF1366-O <b>P. Fuel</b> (20976003)..... BF7814 <b>P. Fuel</b> (20972293)..... BF7943 <b>Fuel/Water Separator</b> (21380488)..... BF1387-O <b>Radial Seal O. Air</b> (8149961)..... RS4967 <b>Radial Seal Air</b> (w/FRM) (21834210)..... RS5776 <b>I. Air</b> (1665937)..... PA3925 <b>Cab Air</b> (8143691)..... PA3839 <b>Air Dryer</b> (3097369)..... BA16000	<b>FM Serie FM 460 w/D13C Euro 5 Eng. (2009-on)</b> <b>F-F Lube</b> (21707133)..... [2] B76 + <b>F-F Lube</b> (Upgrade)..... [2] B76-SS + <b>B-P Lube</b> (4775565)..... B7685 <b>Fuel/Water Separator</b> (20998367)..... BF1366-O <b>P. Fuel</b> (20976003)..... BF7814	

+ See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

VOLVO European Trucks, Vans (cont'd)	VOLVO European Trucks, Vans (cont'd)	VOLVO European Trucks, Vans (cont'd)
<b>FM Serie FM 500 w/D13C Euro 5 Eng.</b> (2009-on) (Cont'd) <b>Urea</b> (21333097)..... PE5271 <b>Urea</b> (from 2011) (21516229)..... PE17000	<b>FMX Serie FMX 380 w/D13C Euro 5 Eng.</b> (2009-on) (Cont'd) <b>Fuel/Water Separator</b> (21380488)..... BF1387-O <b>Radial Seal O. Air</b> (8149961)..... RS4967 <b>Radial Seal Air</b> (w/FRM) (21834210)..... RS5776 <b>I. Air</b> (1665937)..... PA3925 <b>Cab Air</b> (8143691)..... PA3839 <b>Air Dryer</b> (3097369)..... BA16000 <b>Trans.</b> (VT/VTO Serie) (85108176)..... PT9417 <b>Trans.</b> (I-Shift) (20779040)..... PT9417 <b>Trans.</b> (110366077)..... BT8851-MPG <b>Steering</b> (3496197)..... P106-HD <b>Urea</b> (21333097)..... PE5271 <b>Urea</b> (from 2011) (21516229)..... PE17000	<b>FMX Serie FMX 420 w/D13C Euro 5 Eng.</b> (2009-on) (Cont'd) <b>Trans.</b> (110366077)..... BT8851-MPG <b>Steering</b> (3496197)..... P106-HD <b>Urea</b> (21333097)..... PE5271 <b>Urea</b> (from 2011) (21516229)..... PE17000
<b>FMX Serie FMX 330 w/D11C Euro 5 Eng.</b> (2009-on) <b>F-F Lube</b> (21707133)..... [2] B76 + <b>F-F Lube</b> (Upgrade)..... [2] B76-SS + <b>B-P Lube</b> (4775565)..... B7685 <b>Fuel/Water Separator</b> (20998367)..... BF1366-O <b>P. Fuel</b> (20976003)..... BF7814 <b>P. Fuel</b> (20972293)..... BF7943 <b>Fuel/Water Separator</b> (21380488)..... BF1387-O <b>Radial Seal O. Air</b> (21834199)..... RS4966 <b>Radial Seal I. Air</b> (21041296)..... RS5408 <b>Cab Air</b> (8143691)..... PA3839 <b>Air Dryer</b> (3097369)..... BA16000 <b>Trans.</b> (VT/VTO Serie) (85108176)..... PT9417 <b>Trans.</b> (I-Shift) (20779040)..... PT9417 <b>Trans.</b> (110366077)..... BT8851-MPG <b>Steering</b> (3496197)..... P106-HD <b>Urea</b> (21333097)..... PE5271 <b>Urea</b> (from 2011) (21516229)..... PE17000	<b>FMX Serie FMX 410 w/D11C Euro 5 Eng.</b> (2009-on) <b>F-F Lube</b> (21707133)..... [2] B76 + <b>F-F Lube</b> (Upgrade)..... [2] B76-SS + <b>B-P Lube</b> (4775565)..... B7685 <b>Fuel/Water Separator</b> (20998367)..... BF1366-O <b>P. Fuel</b> (20976003)..... BF7814 <b>P. Fuel</b> (20972293)..... BF7943 <b>Fuel/Water Separator</b> (21380488)..... BF1387-O <b>Radial Seal O. Air</b> (21834199)..... RS4966 <b>Radial Seal I. Air</b> (21041296)..... RS5408 <b>Cab Air</b> (8143691)..... PA3839 <b>Air Dryer</b> (3097369)..... BA16000 <b>Trans.</b> (VT/VTO Serie) (85108176)..... PT9417 <b>Trans.</b> (I-Shift) (20779040)..... PT9417 <b>Trans.</b> (110366077)..... BT8851-MPG <b>Steering</b> (3496197)..... P106-HD <b>Urea</b> (21333097)..... PE5271 <b>Urea</b> (from 2011) (21516229)..... PE17000	<b>FMX Serie FMX 450 w/D11C Euro 5 Eng.</b> (2009-on) <b>F-F Lube</b> (21707133)..... [2] B76 + <b>F-F Lube</b> (Upgrade)..... [2] B76-SS + <b>B-P Lube</b> (4775565)..... B7685 <b>Fuel/Water Separator</b> (20998367)..... BF1366-O <b>P. Fuel</b> (20976003)..... BF7814 <b>P. Fuel</b> (20972293)..... BF7943 <b>Fuel/Water Separator</b> (21380488)..... BF1387-O <b>Radial Seal O. Air</b> (21834199)..... RS4966 <b>Radial Seal I. Air</b> (21041296)..... RS5408 <b>Cab Air</b> (8143691)..... PA3839 <b>Air Dryer</b> (3097369)..... BA16000 <b>Trans.</b> (VT/VTO Serie) (85108176)..... PT9417 <b>Trans.</b> (I-Shift) (20779040)..... PT9417 <b>Trans.</b> (110366077)..... BT8851-MPG <b>Steering</b> (3496197)..... P106-HD <b>Urea</b> (21333097)..... PE5271 <b>Urea</b> (from 2011) (21516229)..... PE17000
<b>FMX Serie FMX 370 w/D11C Euro 5 Eng.</b> (2009-on) <b>F-F Lube</b> (21707133)..... [2] B76 + <b>F-F Lube</b> (Upgrade)..... [2] B76-SS + <b>B-P Lube</b> (4775565)..... B7685 <b>Fuel/Water Separator</b> (20998367)..... BF1366-O <b>P. Fuel</b> (20976003)..... BF7814 <b>P. Fuel</b> (20972293)..... BF7943 <b>Fuel/Water Separator</b> (21380488)..... BF1387-O <b>Radial Seal O. Air</b> (21834199)..... RS4966 <b>Radial Seal I. Air</b> (21041296)..... RS5408 <b>Cab Air</b> (8143691)..... PA3839 <b>Air Dryer</b> (3097369)..... BA16000 <b>Trans.</b> (VT/VTO Serie) (85108176)..... PT9417 <b>Trans.</b> (I-Shift) (20779040)..... PT9417 <b>Trans.</b> (110366077)..... BT8851-MPG <b>Steering</b> (3496197)..... P106-HD <b>Urea</b> (21333097)..... PE5271 <b>Urea</b> (from 2011) (21516229)..... PE17000	<b>FMX Serie FMX 420 w/D13C Euro 5 Eng.</b> (2009-on) <b>F-F Lube</b> (21707133)..... [2] B76 + <b>F-F Lube</b> (Upgrade)..... [2] B76-SS + <b>B-P Lube</b> (4775565)..... B7685 <b>Fuel/Water Separator</b> (20998367)..... BF1366-O <b>P. Fuel</b> (20976003)..... BF7814 <b>P. Fuel</b> (20972293)..... BF7943 <b>Fuel/Water Separator</b> (21380488)..... BF1387-O <b>Radial Seal O. Air</b> (8149961)..... RS4967 <b>Radial Seal Air</b> (w/FRM) (21834210)..... RS5776 <b>I. Air</b> (1665937)..... PA3925 <b>Cab Air</b> (8143691)..... PA3839 <b>Air Dryer</b> (3097369)..... BA16000 <b>Trans.</b> (VT/VTO Serie) (85108176)..... PT9417 <b>Trans.</b> (I-Shift) (20779040)..... PT9417 <b>Trans.</b> (110366077)..... BT8851-MPG <b>Steering</b> (3496197)..... P106-HD <b>Urea</b> (21333097)..... PE5271 <b>Urea</b> (from 2011) (21516229)..... PE17000	<b>FMX Serie FMX 460 w/D13C Euro 5 Eng.</b> (2009-on) <b>F-F Lube</b> (21707133)..... [2] B76 + <b>F-F Lube</b> (Upgrade)..... [2] B76-SS + <b>B-P Lube</b> (4775565)..... B7685 <b>Fuel/Water Separator</b> (20998367)..... BF1366-O <b>P. Fuel</b> (20976003)..... BF7814 <b>P. Fuel</b> (20972293)..... BF7943 <b>Fuel/Water Separator</b> (21380488)..... BF1387-O <b>Radial Seal O. Air</b> (8149961)..... RS4967 <b>Radial Seal Air</b> (w/FRM) (21834210)..... RS5776 <b>I. Air</b> (1665937)..... PA3925 <b>Cab Air</b> (8143691)..... PA3839 <b>Air Dryer</b> (3097369)..... BA16000 <b>Trans.</b> (VT/VTO Serie) (85108176)..... PT9417 <b>Trans.</b> (I-Shift) (20779040)..... PT9417 <b>Trans.</b> (110366077)..... BT8851-MPG <b>Steering</b> (3496197)..... P106-HD <b>Urea</b> (21333097)..... PE5271 <b>Urea</b> (from 2011) (21516229)..... PE17000
<b>FMX Serie FMX 380 w/D13C Euro 5 Eng.</b> (2009-on) <b>F-F Lube</b> (21707133)..... [2] B76 + <b>F-F Lube</b> (Upgrade)..... [2] B76-SS + <b>B-P Lube</b> (4775565)..... B7685 <b>Fuel/Water Separator</b> (20998367)..... BF1366-O <b>P. Fuel</b> (20976003)..... BF7814 <b>P. Fuel</b> (20972293)..... BF7943	<b>FMX Serie FMX 420 w/D13C Euro 5 Eng.</b> (2009-on) <b>F-F Lube</b> (21707133)..... [2] B76 + <b>F-F Lube</b> (Upgrade)..... [2] B76-SS + <b>B-P Lube</b> (4775565)..... B7685 <b>Fuel/Water Separator</b> (20998367)..... BF1366-O <b>P. Fuel</b> (20976003)..... BF7814 <b>P. Fuel</b> (20972293)..... BF7943 <b>Fuel/Water Separator</b> (21380488)..... BF1387-O <b>Radial Seal O. Air</b> (8149961)..... RS4967 <b>Radial Seal Air</b> (w/FRM) (21834210)..... RS5776 <b>I. Air</b> (1665937)..... PA3925 <b>Cab Air</b> (8143691)..... PA3839 <b>Air Dryer</b> (3097369)..... BA16000 <b>Trans.</b> (VT/VTO Serie) (85108176)..... PT9417 <b>Trans.</b> (I-Shift) (20779040)..... PT9417	<b>FMX Serie FMX 500 w/D13C Euro 5 Eng.</b> (2009-on) <b>F-F Lube</b> (21707133)..... [2] B76 + <b>F-F Lube</b> (Upgrade)..... [2] B76-SS + <b>B-P Lube</b> (4775565)..... B7685

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>VOLVO</b> European Trucks, Vans (cont'd)	<b>VOLVO</b> European Trucks, Vans (cont'd)	<b>VOLVO</b> European Trucks, Vans (cont'd)
<b>FMX Serie FMX 500 w/D13C Euro 5 Eng. (2009-on) (Cont'd)</b> <b>Fuel/Water Separator</b> (20998367)..... <b>BF1366-O</b> <b>P. Fuel</b> (20976003)..... <b>BF7814</b> <b>P. Fuel</b> (20972293)..... <b>BF7943</b> <b>Fuel/Water Separator</b> (21380488)..... <b>BF1387-O</b> <b>Radial Seal O. Air</b> (8149961)..... <b>RS4967</b> <b>Radial Seal Air (w/FRM)</b> (21834210)..... <b>RS5776</b> <b>I. Air</b> (1665937)..... <b>PA3925</b> <b>Cab Air</b> (8143691)..... <b>PA3839</b> <b>Air Dryer</b> (3097369)..... <b>BA16000</b> <b>Trans. (VT/VTO Serie)</b> (85108176)..... <b>PT9417</b> <b>Trans. (I-Shift)</b> (20779040)..... <b>PT9417</b> <b>Trans.</b> (110366077)..... <b>BT8851-MPG</b> <b>Steering</b> (3496197)..... <b>P106-HD</b> <b>Urea</b> (21333097)..... <b>PE5271</b> <b>Urea</b> (from 2011) (21516229)..... <b>PE17000</b>	<b>FE III 320 CNG w/G9K320 Eng. (01/16-on)</b> <b>Lube</b> (21707132)..... <b>B7409</b> <b>Lube</b> (21707133)..... <b>B76 +</b> <b>Severe Service F-F Lube</b> (21707133)..... <b>B76-SS +</b> <b>Radial Seal Air (Long)</b> (20732726)..... <b>RS5390</b> <b>Radial Seal Air (Short)</b> (20732730)..... <b>RS30236</b> <b>Cab Air</b> (85134455)..... <b>PA30188</b> <b>Air Dryer</b> (21267818)..... <b>BA5566</b>	<b>FM/FMX 500 w/D13K Euro 6 Eng. (2013-on)</b> <b>F-F Lube</b> (21707133)..... <b>B76 +</b> <b>B-P Lube</b> (21707132)..... <b>B7409</b> <b>Severe Service F-F Lube</b> (21707133)..... <b>B76-SS +</b> <b>Fuel/Water Separator</b> (21764966)..... <b>BF1386-O</b> <b>Cab Air (Pre-Filter)</b> (82354791).... <b>PA30113</b> <b>Cab Air</b> (82348995)..... <b>PA30114</b> <b>Coolant</b> (16998307)..... <b>BW5141</b> <b>Steering</b> (3496197)..... <b>P106-HD</b> <b>Urea</b> (21516229)..... <b>PE17000</b>
<b>FL III 280 w/D8K Eng. (09/13-on)</b> <b>Fuel/Water Separator</b> (21538975)..... <b>BF1292-O</b> <b>Radial Seal Air (Short)</b> (20732730)..... <b>RS30236</b> <b>Cab Air</b> (85134455)..... <b>PA30188</b> <b>Air Dryer</b> (21267818)..... <b>BA5566</b> <b>Steering</b> (349619)..... <b>P106-HD</b> <b>Urea</b> (21516229)..... <b>PE17000</b>	<b>FE III 320 w/D8K Eng. (09/13-on)</b> <b>Fuel/Water Separator</b> (21538975)..... <b>BF1292-O</b> <b>Radial Seal Air (Long)</b> (20732726)..... <b>RS5390</b> <b>Radial Seal Air (Short)</b> (20732730)..... <b>RS30236</b> <b>Cab Air</b> (85134455)..... <b>PA30188</b> <b>Air Dryer</b> (21267818)..... <b>BA5566</b> <b>Steering</b> (349619)..... <b>P106-HD</b> <b>Urea</b> (21516229)..... <b>PE17000</b>	<b>FM/FMX 460 w/D13K Euro 6 Eng. (2013-on)</b> <b>F-F Lube</b> (21707133)..... <b>B76 +</b> <b>B-P Lube</b> (21707132)..... <b>B7409</b> <b>Severe Service F-F Lube</b> (21707133)..... <b>B76-SS +</b> <b>Fuel/Water Separator</b> (21764966)..... <b>BF1386-O</b> <b>Cab Air (Pre-Filter)</b> (82354791).... <b>PA30113</b> <b>Cab Air</b> (82348995)..... <b>PA30114</b> <b>Coolant</b> (16998307)..... <b>BW5141</b> <b>Steering</b> (3496197)..... <b>P106-HD</b> <b>Urea</b> (21516229)..... <b>PE17000</b>
<b>FL III 250 w/D8K Eng. (09/13-on)</b> <b>Fuel/Water Separator</b> (21538975)..... <b>BF1292-O</b> <b>Radial Seal Air (Short)</b> (20732730)..... <b>RS30236</b> <b>Cab Air</b> (85134455)..... <b>PA30188</b> <b>Air Dryer</b> (21267818)..... <b>BA5566</b> <b>Steering</b> (349619)..... <b>P106-HD</b> <b>Urea</b> (21516229)..... <b>PE17000</b>	<b>FE III 280 w/D8K Eng. (09/13-on)</b> <b>Fuel/Water Separator</b> (21538975)..... <b>BF1292-O</b> <b>Radial Seal Air (Long)</b> (20732726)..... <b>RS5390</b> <b>Radial Seal Air (Short)</b> (20732730)..... <b>RS30236</b> <b>Cab Air</b> (85134455)..... <b>PA30188</b> <b>Air Dryer</b> (21267818)..... <b>BA5566</b> <b>Steering</b> (349619)..... <b>P106-HD</b> <b>Urea</b> (21516229)..... <b>PE17000</b>	<b>FM/FMX 450 w/D11K Euro 6 Eng. (2013-on)</b> <b>F-F Lube</b> (21707133)..... <b>B76 +</b> <b>B-P Lube</b> (21707132)..... <b>B7409</b> <b>Severe Service F-F Lube</b> (21707133)..... <b>B76-SS +</b> <b>Fuel/Water Separator</b> (21764966)..... <b>BF1386-O</b> <b>Cab Air (Pre-Filter)</b> (82354791).... <b>PA30113</b> <b>Cab Air</b> (82348995)..... <b>PA30114</b> <b>Coolant</b> (16998307)..... <b>BW5141</b> <b>Steering</b> (3496197)..... <b>P106-HD</b> <b>Urea</b> (21516229)..... <b>PE17000</b>
<b>FL III 240 w/D5K Eng. (09/13-on)</b> <b>Fuel/Water Separator</b> (21538975)..... <b>BF1292-O</b> <b>Radial Seal Air (Short)</b> (20732730)..... <b>RS30236</b> <b>Cab Air</b> (85134455)..... <b>PA30188</b> <b>Air Dryer</b> (21267818)..... <b>BA5566</b> <b>Steering</b> (349619)..... <b>P106-HD</b> <b>Urea</b> (21516229)..... <b>PE17000</b>	<b>FE III 250 w/D8K Eng. (09/13-on)</b> <b>Fuel/Water Separator</b> (21538975)..... <b>BF1292-O</b> <b>Radial Seal Air (Long)</b> (20732726)..... <b>RS5390</b> <b>Radial Seal Air (Short)</b> (20732730)..... <b>RS30236</b> <b>Cab Air</b> (85134455)..... <b>PA30188</b> <b>Air Dryer</b> (21267818)..... <b>BA5566</b> <b>Steering</b> (349619)..... <b>P106-HD</b> <b>Urea</b> (21516229)..... <b>PE17000</b>	<b>FM/FMX 420 w/D13K Euro 6 Eng. (2013-on)</b> <b>F-F Lube</b> (21707133)..... <b>B76 +</b> <b>B-P Lube</b> (21707132)..... <b>B7409</b> <b>Severe Service F-F Lube</b> (21707133)..... <b>B76-SS +</b> <b>Fuel/Water Separator</b> (21764966)..... <b>BF1386-O</b> <b>Cab Air (Pre-Filter)</b> (82354791).... <b>PA30113</b> <b>Cab Air</b> (82348995)..... <b>PA30114</b> <b>Coolant</b> (16998307)..... <b>BW5141</b> <b>Steering</b> (3496197)..... <b>P106-HD</b> <b>Urea</b> (21516229)..... <b>PE17000</b>
<b>FL III 210 w/D5K Eng. (09/13-on)</b> <b>Fuel/Water Separator</b> (21538975)..... <b>BF1292-O</b> <b>Radial Seal O. Air (Short)</b> (20732730)..... <b>RS30236</b> <b>Cab Air</b> (85134455)..... <b>PA30188</b> <b>Air Dryer</b> (21267818)..... <b>BA5566</b> <b>Steering</b> (349619)..... <b>P106-HD</b> <b>Urea</b> (21516229)..... <b>PE17000</b>	<b>FM/FMX 540 w/D13K Euro 6 Eng. (2013-on)</b> <b>F-F Lube</b> (21707133)..... <b>B76 +</b> <b>B-P Lube</b> (21707132)..... <b>B7409</b> <b>Severe Service F-F Lube</b> (21707133)..... <b>B76-SS +</b> <b>Fuel/Water Separator</b> (21764966)..... <b>BF1386-O</b> <b>Cab Air (Pre-Filter)</b> (82354791).... <b>PA30113</b> <b>Cab Air</b> (82348995)..... <b>PA30114</b> <b>Coolant</b> (16998307)..... <b>BW5141</b> <b>Steering</b> (3496197)..... <b>P106-HD</b> <b>Urea</b> (21516229)..... <b>PE17000</b>	<b>FM/FMX 410 w/D11K Euro 6 Eng. (2013-on)</b> <b>F-F Lube</b> (21707133)..... <b>B76 +</b> <b>B-P Lube</b> (21707132)..... <b>B7409</b> <b>Severe Service F-F Lube</b> (21707133)..... <b>B76-SS +</b> <b>Fuel/Water Separator</b> (21764966)..... <b>BF1386-O</b> <b>Cab Air (Pre-Filter)</b> (82354791).... <b>PA30113</b> <b>Cab Air</b> (82348995)..... <b>PA30114</b> <b>Coolant</b> (16998307)..... <b>BW5141</b> <b>Steering</b> (3496197)..... <b>P106-HD</b>

+ See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

VOLVO European Trucks, Vans (cont'd)	VOLVO North America Trucks	VOLVO North America Trucks (cont'd)
FM/FMX 410 w/D11K Euro 6 Eng. (2013-on) (Cont'd)	ACL w/Cat 3176 (10.5L) Eng.	ACL w/Cummins N14 (14.0L) Eng.
Urea (21516229)..... PE17000	F-F Lube (Std. Version) (1R0716)..... B99 +	Dual-Flow Lube (3318853)..... BD103 +
FM/FMX 370 w/D11K Euro 6 Eng. (2013-on)	F-F Lube (High Efficiency Vers.) (1R1808)..... B7299 +	Opt. Fuel/Water Separator (3329289)..... BF1259
F-F Lube (21707133)..... B76 +	Opt. B-P Lube (1W8845)..... B7577	Coolant (w/23 Units BTA+) (3844234)..... BW5076
B-P Lube (21707132)..... B7409	Fuel/Water Separator Ele. (8N0205)..... PF316	Opt. Trans. Spin-on (Fuller 17237)..... B2 +
Severe Service F-F Lube (21707133)..... B76-SS +	Fuel/Water Separator Spin-on (2568753)..... BF1259	ACL w/Detroit Diesel Series 60 (11.1L) or (12.7L) Eng.
Fuel/Water Separator (21764966)..... BF1386-O	P. Fuel Ele. (9M2342)..... [2] PF935	Lube (23518480)..... [2] B495
Cab Air (Pre-Filter) (82354791).... PA30113	P. Fuel Spin-on (1R1740)..... BF970 +	P. Fuel (23530706)..... BF5800 +
Cab Air (82348995)..... PA30114	S. Fuel Spin-on (1R0750)..... BF7633 +	S. Fuel (23518482)..... BF5810
Coolant (16998307)..... BW5141	ACL w/Cat 3306 (10.5L) Eng.	Coolant (23516489)..... BW5200
Steering (3496197)..... P106-HD	Lube Ele. (5S0484)..... PT670	ACL w/Volvo D12 (12.1L) Eng.
Urea (21516229)..... PE17000	Lube Spin-on (1R0716)..... B99 +	Dual-Flow Lube (Fleetguard LF9001)..... BD7154 +
FM/FMX 330 w/D11K Euro 6 Eng. (2013-on)	Lube Spin-on (Standard Vers.) (1R0739)..... B76 +	Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... BD50000
F-F Lube (21707133)..... B76 +	Lube Spin-on (Severe Service) (1R0739)..... B76-SS +	F-F Lube (4787362)..... B76-SS +
B-P Lube (21707132)..... B7409	P. Fuel Ele. (9M2342)..... PF935	B-P Lube (4775565)..... B7685
Severe Service F-F Lube (21707133)..... B76-SS +	P. Fuel Spin-on (1R1740)..... BF970 +	B10M Mk1
Fuel/Water Separator (21764966)..... BF1386-O	S. Fuel Spin-on (1R0750)..... BF7633 +	F-F Lube (423135)..... [2] B975
Cab Air (Pre-Filter) (82354791).... PA30113	ACL w/Cat 3406 (14.6L) Eng.	B-P Lube (477556)..... B7685
Cab Air (82348995)..... PA30114	F-F Lube (Std. Version) (1R0716)..... B99 +	O. Air (1660619)..... PA2707
Coolant (16998307)..... BW5141	F-F Lube (High Efficiency Vers.) (1R1808)..... B7299 +	Some I. Air (1660903)..... PA2775
Steering (3496197)..... P106-HD	Box-Style Glass Fuel/Water Separator (8N9803)..... BF912	Comp. Air (w/o Air Suspension) (8152009)..... PA2798
Urea (21516229)..... PE17000	Fuel/Water Separator Spin-on (8N0205)..... BF1268	Comp. Air (w/Air Suspension) (8152010)..... PA3679
	Fuel/Water Separator Spin-on (2568753)..... BF1259	Gearbox (w/ZF Gearbox) (1193281)..... PT8385
<b>VOLVO</b> Latin America Trucks	Fuel Ele. (9M2342)..... [2] PF935	B10M Mk2
7550 w/N12 Eng.	Fuel Spin-on (1R0749)..... BF7587 +	Lube (423135)..... [2] B975
Fuel/Water Separator (Open End for Bowl) (Mann WK1060/1)..... BF46083-O	Coolant (w/8 Units BTE) (9N6123)..... BW5139	O. Air (1660619)..... PA2707
Fuel/Water Separator (With Bowl) (Mann WK1060/1)..... BF46072	Opt. Trans. (Fuller 17237)..... B2 +	Some I. Air (1660903)..... PA2775
Fuel/Water Separator (With Drain) (Mann WK1060/1)..... BF1329	ACL w/Cummins L10 (10.0L) Eng.	Comp. Air (w/o Air Suspension) (8152009)..... PA2798
Fuel/Water Separator (Sensor Port Thread 9/16-20) (Mann WK1060/1)..... BF1329-SP	Dual-Flow Lube (3318853)..... BD103 +	Comp. Air (w/Air Suspension) (8152010)..... PA3679
Fuel/Water Separator (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... BF1339-SP +	F-F Lube (Fleetguard LF670SC)..... B196 +	Steering (349619)..... P106-HD
7550 w/N12 Eng.	B-P Lube (3304232)..... B7577	Gearbox (w/ZF Gearbox) (1193281)..... PT8385
Fuel/Water Separator (Open End for Bowl) (Mann WK1060/1)..... BF46083-O	Fuel (154789)..... BF957-D +	B10M Mk3
Fuel/Water Separator (With Bowl) (Mann WK1060/1)..... BF46072	ACL w/Cummins M11 (10.8L) Eng. (To 12/1995)	Lube (423135)..... [2] B975
Fuel/Water Separator (With Drain) (Mann WK1060/1)..... BF1329	Dual-Flow Lube (3318853)..... BD103 +	O. Air (1660619)..... PA2707
Fuel/Water Separator (Sensor Port Thread 9/16-20) (Mann WK1060/1)..... BF1329-SP	Fuel/Water Separator Ele. (Fleetguard FS1029W)..... PF7680	Some I. Air (1660903)..... PA2775
Fuel/Water Separator (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... BF1339-SP +	Fuel/Water Separator Spin-on (3308638)..... BF1212 +	Comp. Air (w/o Air Suspension) (8152009)..... PA2798
	ACL w/Cummins M11 (10.8L) Eng. (12/1995-on)	Comp. Air (w/Air Suspension) (8152010)..... PA3679
	Dual-Flow Lube (3318853)..... BD103 +	Steering (349619)..... P106-HD
	Fuel/Water Separator Ele. (Fleetguard FS1029W)..... PF7680	Gearbox (w/ZF Gearbox) (1193281)..... PT8385
	Fuel/Water Separator Spin-on (3329289)..... BF1259	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>VOLVO</b> North America Trucks (cont'd)	<b>VOLVO</b> North America Trucks (cont'd)	<b>VOLVO</b> North America Trucks (cont'd)
<b>B10M Mk4</b> Lube (423135)..... [2] B975 O. Air (1544449)..... PA2774 Some I. Air (1660903)..... PA2775 Comp. Air (w/o Air Suspension) (8152009)..... PA2798 Comp. Air (w/Air Suspension) (8152010)..... PA3679 Steering (349619)..... P106-HD Gearbox (w/ZF Gearbox) (1193281)..... PT8385	<b>F6S w/TD60A, TD60B, TD60C Engs. (Cont'd)</b> Fuel Spin-on (4669875)..... BF988 + Air (6872683)..... PA2659 Some Air (1660602)..... PA2649 Cab Air (15845753)..... PA3414 Breather (1082111)..... PA2798 Some Steering (349619)..... P106-HD Allison Hyd. (Gear Box) (15268956)..... P18-HD <b>F7 w/TD70F, TD70FS, TD70G Engs.</b> F-F Lube (466634)..... B76 + Lube (Upgrade)..... B76-SS + Fuel Spin-on (4669875)..... BF988 + O. Air (6897063)..... PA2963 I. Air (6897064)..... PA2964 <sup>90</sup> Cab Air (15845753)..... PA3414 Breather (1082111)..... PA2798 Breather (w/Air Suspension) (1082368)..... PA3679 Some Steering (349619)..... P106-HD Allison Hyd. (Gear Box) (15268956)..... P18-HD	<b>F12 w/TD100, TD101, TD102, TD121, TD122 Engs. (Cont'd)</b> O. Air (1660377-1)..... PA2915 I. Air (1660376-3)..... PA2914 O. Air (From 1992) (1080918)..... PA3484 I. Air (From 1992) (1080920)..... PA3865 Some Air (475755)..... PA2757 Some Air (S/N 344405-up) (6897063)..... PA2963 Cab Air (15845753)..... PA3414 Breather (1586882-1)..... PA2798 Breather (w/Air Suspension) (1082368-0)..... PA3679 Some Steering (349619)..... P106-HD Hyd. (Gear Box Cooling) (423135)..... B975 Hyd. (Gear Box QR/SR) (1266286)..... B163 <b>F16 w/TD162 Eng.</b> F-F Lube (466634)..... [2] B76 + F-F Lube (Upgrade)..... [2] B76-SS + B-P Lube (477556)..... B7685 Fuel Spin-on (4669875)..... BF988 + Cab Air (15845753)..... PA3414 Breather (w/Air Suspension) (1082368-0)..... PA3679 Breather (15868821)..... PA2798 Coolant (1661964-5)..... BW5141 Trans. (w/SR2000 Gear Box) (1266286)..... B163 Some Hyd. (349619)..... P106-HD
<b>B57</b> Lube (423135)..... [2] B975	<b>F8 w/TD70E Eng.</b> Lube Spin-on (423135)..... B975 Opt. Fuel/Water Separator..... BF1221 + Fuel Spin-on (2430049)..... BF988 + O. Air (476769)..... PA2869	<b>F82, F82B</b> F-F Lube Ele. (482051)..... PT29 Can-Type Fuel (236628)..... BF825 +
<b>B58</b> Lube (423135)..... [2] B975	<b>F10 w/TD100, TD101, TD102 Engs.</b> Lube (TD100 Eng.) (423135)..... [2] B975 F-F Lube (Exc. TD100 Eng.) (466634)..... [2] B76 + F-F Lube (Upgrade) (Exc. TD100 Eng.)..... [2] B76-SS + Fuel Spin-on (466987)..... [2] BF988 + O. Air (1992-on) (1080918)..... PA3484 I. Air (1992-on) (1080920)..... PA3865 O. Air (1660377-1)..... PA2915 I. Air (1660376-3)..... PA2914 Some Air (475755)..... PA2757 Some Air (S/N 344405-up) (6897063)..... PA2963 Cab Air (15845753)..... PA3414 Breather (w/Air Suspension) (1082368-0)..... PA3679 Breather (1586882-1)..... PA2798 Some Steering (349619)..... P106-HD Hyd. (Gear Box Cooling) (423135)..... B975 Hyd. (Gear Box QR/SR) (1266286)..... B163	<b>F82S</b> Lube Spin-on (484074)..... BT216 + Can-Type Fuel (236628)..... BF825 +
<b>F4 w/D39C Eng.</b> Lube Spin-on (4840740)..... BT216 + Can-Type Fuel (2366284)..... BF825 + Cab Air (15845753)..... PA3414 Breather (1082111)..... PA2798 Steering (349619)..... P106-HD	<b>F12 w/TD100, TD101, TD102, TD121, TD122 Engs.</b> Lube (TD100 Eng.) (423135)..... [2] B975 F-F Lube (Exc. TD100 Eng.) (466634)..... [2] B76 + F-F Lube (Upgrade) (Exc. TD100 Eng.)..... [2] B76-SS + Fuel Spin-on (466987)..... [2] BF988 + O. Air (1992-on) (1080918)..... PA3484 I. Air (1992-on) (1080920)..... PA3865 O. Air (1660377-1)..... PA2915 I. Air (1660376-3)..... PA2914 Some Air (475755)..... PA2757 Some Air (S/N 344405-up) (6897063)..... PA2963 Cab Air (15845753)..... PA3414 Breather (w/Air Suspension) (1082368-0)..... PA3679 Breather (1586882-1)..... PA2798 Some Steering (349619)..... P106-HD Hyd. (Gear Box Cooling) (423135)..... B975 Hyd. (Gear Box QR/SR) (1266286)..... B163	<b>F83, F83B</b> F-F Lube Ele. (482051)..... PT29 Can-Type Fuel (236628)..... BF825 +
<b>F4 w/TD40 Eng.</b> Lube Spin-on (4710349)..... B447 Fuel Spin-on (243464)..... BF587-D + Cab Air (15845753)..... PA3414 Breather (1082111)..... PA2798 Some Hyd. (349619)..... P106-HD	<b>F16 w/TD162 Eng.</b> F-F Lube (466634)..... [2] B76 + F-F Lube (Upgrade)..... [2] B76-SS + B-P Lube (477556)..... B7685 Fuel Spin-on (4669875)..... BF988 + Cab Air (15845753)..... PA3414 Breather (w/Air Suspension) (1082368-0)..... PA3679 Breather (15868821)..... PA2798 Coolant (1661964-5)..... BW5141 Trans. (w/SR2000 Gear Box) (1266286)..... B163 Some Hyd. (349619)..... P106-HD	<b>F83S</b> Lube Spin-on (484074)..... BT216 + Can-Type Fuel (236628)..... BF825 +
<b>F6 Series</b> F-F Lube Spin-on (To S/N 47590)..... B975 F-F Lube Spin-on (S/N 47590-up)..... B76 + B-P Lube Ele..... C704-L Fuel..... BF988 + Air (6872683)..... PA2659	<b>F8 w/TD70E Eng.</b> Lube Spin-on (423135)..... B975 Opt. Fuel/Water Separator..... BF1221 + Fuel Spin-on (2430049)..... BF988 + O. Air (476769)..... PA2869	<b>F84, N84 w/D50, TD50, TD60 Engs.</b> Lube Spin-on (423135)..... B975 S. Fuel Ele. (233897)..... PF950 Fuel Spin-on (466987)..... BF988 + O. Air (476769)..... PA2869
<b>F6 w/D60 Eng.</b> Fuel Spin-on (4669875)..... BF988 + Cab Air (15845753)..... PA3414 Breather (1082111)..... PA2798 Some Steering (349619)..... P106-HD Allison Hyd. (Gear Box) (15268956)..... P18-HD	<b>F10 w/TD100, TD101, TD102 Engs.</b> Lube (TD100 Eng.) (423135)..... [2] B975 F-F Lube (Exc. TD100 Eng.) (466634)..... [2] B76 + F-F Lube (Upgrade) (Exc. TD100 Eng.)..... [2] B76-SS + Fuel Spin-on (466987)..... [2] BF988 + O. Air (1992-on) (1080918)..... PA3484 I. Air (1992-on) (1080920)..... PA3865 O. Air (1660377-1)..... PA2915 I. Air (1660376-3)..... PA2914 Some Air (475755)..... PA2757 Some Air (S/N 344405-up) (6897063)..... PA2963 Cab Air (15845753)..... PA3414 Breather (w/Air Suspension) (1082368-0)..... PA3679 Breather (1586882-1)..... PA2798 Some Steering (349619)..... P106-HD Hyd. (Gear Box Cooling) (423135)..... B975 Hyd. (Gear Box QR/SR) (1266286)..... B163	<b>F84, N84 w/TD100 Eng.</b> Lube Spin-on (423135)..... B975 Opt. Fuel/Water Separator..... BF1221 + P. Fuel Ele..... F950-F S. Fuel Ele. (233897)..... PF950 Fuel Spin-on (243004)..... BF988 + Air (475338)..... PA2869 Air (475755)..... PA2757
<b>F6 w/TD60A, TD60B, TD60C Engs.</b> Lube (To S/N 47589) (423135)..... B975 Lube (S/N 47590-up) (466634)..... B76 + Lube (S/N 47590-up (Upgrade))..... B76-SS + Fuel Spin-on (4669875)..... BF988 + Air (6872683)..... PA2659 Cab Air (15845753)..... PA3414 Breather (1082111)..... PA2798 Some Steering (349619)..... P106-HD Allison Hyd. (Gear Box) (15268956)..... P18-HD	<b>F8 w/TD70E Eng.</b> Lube Spin-on (423135)..... B975 Opt. Fuel/Water Separator..... BF1221 + Fuel Spin-on (2430049)..... BF988 + O. Air (476769)..... PA2869	
<b>F6S w/TD60A, TD60B, TD60C Engs.</b> Lube (To S/N 47590) (423135)..... B975 Lube (S/N 47590-up) (466634)..... B76 + Lube (S/N 47590-up (Upgrade))..... B76-SS +	<b>F12 w/TD100, TD101, TD102, TD121, TD122 Engs.</b> Lube (TD100 Eng.) (423135)..... [2] B975 F-F Lube (Exc. TD100 Eng.) (466634)..... [2] B76 + F-F Lube (Upgrade) (Exc. TD100 Eng.)..... [2] B76-SS + Fuel Spin-on (466987)..... [2] BF988 +	

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



<b>VOLVO</b> North America Trucks (cont'd)	<b>VOLVO</b> North America Trucks (cont'd)	<b>VOLVO</b> North America Trucks (cont'd)
F85 w/D50, TD50, TD60 Engs. Lube Spin-on (423135)..... <b>B975</b> Opt. Fuel/Water Separator..... <b>BF1221 +</b> S. Fuel Ele. (233897)..... <b>PF950</b> Fuel Spin-on (466987)..... <b>BF988 +</b> O. Air (476769)..... <b>PA2869</b>	FE w/Cat 3116 (6.6L) Eng. (Cont'd) P. Fuel Spin-on (1R1740)..... <b>BF970 +</b> S. Fuel Spin-on (1R0750)..... <b>BF7633 +</b> Air (Don. P772523)..... <b>LL2945</b> Cab Air (6774452)..... <b>PA2101A</b> Air Comp. Breather (9L2169)..... <b>PA1704</b> Coolant (w/4 Units BTE) (9N3717)..... <b>BW5137</b> Coolant (w/8 Units BTE) (9N6123)..... <b>BW5139</b> Steering (V349619)..... <b>P106-HD</b>	FE64 w/Cat 3176 Eng. F-F Lube..... <b>B99 +</b> Opt. B-P Lube..... <b>B7577</b> Fuel Spin-on..... <b>BF7587 +</b>
F85, F85M, F85T, F86, F86T w/TD100 Eng. Lube Spin-on (423135)..... <b>B975</b> Opt. Fuel/Water Separator..... <b>BF1221 +</b> P. Fuel Ele..... <b>F950-F</b> S. Fuel Ele. (233897)..... <b>PF950</b> Fuel Spin-on (243004)..... <b>BF988 +</b> Air (475338)..... <b>PA2869</b> Air (475755)..... <b>PA2757</b>	FE w/Cat 3306 (10.5L) Eng. Lube Ele. (5S0484)..... <b>PT670</b> Lube Spin-on (1R0716)..... <b>B99 +</b> Lube Spin-on (Standard Vers.) (1R0739)..... <b>B76 +</b> Lube Spin-on (Severe Service) (1R0739)..... <b>B76-SS +</b> P. Fuel Ele. (9M2342)..... <b>PF935</b> P. Fuel Spin-on (1R1740)..... <b>BF970 +</b> S. Fuel Spin-on (1R0750)..... <b>BF7633 +</b>	FL4 w/TD41 Eng. Lube Spin-on (4231353)..... <b>B975</b> Fuel Spin-on (12572012)..... <b>BF587-D +</b> Air (67925545)..... <b>PA2785</b> Cab Air (15845753)..... <b>PA3414</b> Breather (1082111)..... <b>PA2798</b> Steering (349619)..... <b>P106-HD</b>
F86, FB86, N86 w/D70A, D70B, D70C, D70D, TD70A, TD70E Engs. Lube Spin-on (423135)..... <b>B975</b> B-P Lube (1517575)..... <b>C750-E +</b> Can-Type Fuel (2366284)..... <b>BF825 +</b> Fuel Spin-on (466987)..... <b>BF988 +</b> O. Air (476769)..... <b>PA2869</b>	FE w/D12 (12.1L) Eng. Dual-Flow Lube (Fleetguard LF9001)..... <b>BD7154 +</b> Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> F-F Lube (4787362)..... <b>B76-SS +</b> B-P Lube (4775565)..... <b>B7685</b>	FL Serie FL6 w/TD61F, TD61G, TD61GS Engs. F-F Lube (466634)..... <b>B76 +</b> F-F Lube (Upgrade)..... <b>B76-SS +</b> Fuel (466987)..... <b>[2] BF988 +</b> Air (67925545)..... <b>PA2785</b> Cab Air (15845753)..... <b>PA3414</b> Breather (1082111)..... <b>PA2798</b> Steering (349619)..... <b>P106-HD</b>
F87, NF87 w/D70A, D70B, D70C, D70D, TD70A, TD70E Engs. Lube Spin-on (423135)..... <b>B975</b> B-P Lube (1517575)..... <b>C750-E +</b> Can-Type Fuel (2366284)..... <b>BF825 +</b> Fuel Spin-on (466987)..... <b>BF988 +</b> O. Air (476769)..... <b>PA2869</b>	FE6 w/TD61 Eng. Lube..... <b>B76 +</b> Severe Service Lube..... <b>B76-SS +</b> Fuel..... <b>BF988 +</b>	FL7 w/TD71, TD72 Engs. F-F Lube (4666343)..... <b>B76 +</b> F-F Lube (Upgrade)..... <b>B76-SS +</b> B-P Lube (477556)..... <b>B7685</b> Fuel Spin-on (4669875)..... <b>BF988 +</b> O. Air (1660600)..... <b>PA2786</b> I. Air (1660601)..... <b>PA2787</b> Air (1990-on) (1665563)..... <b>PA2982</b> Cab Air (15845753)..... <b>PA3414</b> Breather (15868821)..... <b>PA2798</b> Steering (349619)..... <b>P106-HD</b>
F88, F88T, FB88, FB88T, N88T, NB88T w/TD100A, TD100B Engs. Lube Spin-on (423135)..... <b>B975</b> Opt. Fuel/Water Separator..... <b>BF1221 +</b> P. Fuel Ele..... <b>F950-F</b> S. Fuel Ele. (233897)..... <b>PF950</b> Fuel Spin-on (466987)..... <b>BF988 +</b>	FE7 (1986-on) F-F Lube (466634)..... <b>B76 +</b> F-F Lube (Upgrade)..... <b>B76-SS +</b> B-P Lube (477556)..... <b>B7685</b> Fuel (466987)..... <b>[2] BF988 +</b> Air (677872-9)..... <b>PA3946</b>	FL10 w/D10A Eng. F-F Lube Spin-on (4666343)..... <b>[2] B76 +</b> F-F Lube Spin-on (Upgrade) (4787362)..... <b>[2] B76-SS +</b> B-P Lube Spin-on (477556)..... <b>B7685</b> Fuel Spin-on (4669875)..... <b>[2] BF988 +</b> I. Air (Mann C16167)..... <b>PA2787</b> Cab Air (Mann CU2785)..... <b>PA3414</b> Trans. (3517857-3)..... <b>B1434</b> Steering (V349619)..... <b>P106-HD</b> Some Steering (323139)..... <b>PT691</b>
F88, F88T, FB88, G88, N88T, NB88T w/D100, TD100 Engs. Lube Spin-on (423135)..... <b>B975</b> P. Fuel Ele..... <b>F950-F</b> S. Fuel Ele. (233897)..... <b>PF950</b> Fuel Spin-on (466987)..... <b>BF988 +</b>	FE42 w/VE7 Eng. F-F Lube (466634)..... <b>B76 +</b> F-F Lube (Upgrade)..... <b>B76-SS +</b> B-P Lube (477556)..... <b>B7685</b> Fuel/Water Separator (Fleetguard FS1212)..... <b>BF1212 +</b> Fuel Spin-on (466987)..... <b>[2] BF988 +</b> Air (Don. P772523)..... <b>LL2945</b> Cab Air (6774452)..... <b>PA2101A</b> Air Dryer (AD-IP System) (Bendix 65624)..... <b>BA5373</b> Steering (349619)..... <b>P106-HD</b>	FL10 w/TD101, TD102 Engs. F-F Lube Spin-on (4666343)..... <b>[2] B76 +</b> F-F Lube Spin-on (Upgrade)..... <b>[2] B76-SS +</b> B-P Lube Spin-on (477556)..... <b>B7685</b> Fuel Spin-on (4669875)..... <b>[2] BF988 +</b> O. Air (1660600)..... <b>PA2786</b> I. Air (1660601)..... <b>PA2787</b> Air (S/N 324581-up) (1665563)..... <b>PA2982</b> Cab Air (15845753)..... <b>PA3414</b> Breather (1586882-1)..... <b>PA2798</b>
F88, F88B w/D120, TD120 Engs. Lube Spin-on (423135)..... <b>B975</b> Opt. Fuel/Water Separator..... <b>BF1221 +</b> Fuel Spin-on (466987)..... <b>BF988 +</b>	FE42, FE42T w/Cat 3176 Eng. F-F Lube..... <b>B99 +</b> Opt. B-P Lube..... <b>B7577</b> Fuel Spin-on..... <b>BF7587 +</b>	FL12 Fuel/Water Separator (Open End for Bowl) (8159975)..... <b>BF46083-O</b> Opt. Fuel/Water Separator (Open End for Bowl) (20514654)..... <b>BF1366-O</b> Fuel (8193841)..... <b>BF7653</b> Fuel (420799)..... <b>BF7644</b>
F89, G89 w/D120, TD120 Engs. Lube Spin-on (423135)..... <b>B975</b> Opt. Fuel/Water Separator..... <b>BF1221 +</b> Fuel Spin-on (466987)..... <b>BF988 +</b>		
FE w/Cat 3116 (6.6L) Eng. Lube (Standard Vers.) (1R0739)..... <b>B76 +</b> Lube (High Efficiency Vers.) (1R1807)..... <b>B7700 +</b> Lube (Severe Service) (1R0739)..... <b>B76-SS +</b> Fuel/Water Separator (3132887)..... <b>BF1212 +</b> Opt. Fuel/Water Separator..... <b>BF1214</b> P. Fuel Spin-on (7E9763)..... <b>BF984</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

VOLVO North America Trucks (cont'd)	VOLVO North America Trucks (cont'd)	VOLVO North America Trucks (cont'd)
FL12 (Cont'd)	N12 w/TD120, TD121, TD122 Engs.	N88, NB88 w/TD100 Eng.
Fuel (20430751)..... <b>BF7814</b>	Lube Spin-on (423135)..... <b>B975</b>	Lube Spin-on (423135)..... <b>B975</b>
Fuel/Water Separator (w/Bowl) (8159975)..... <b>BF46072</b>	Fuel Spin-on (466987)..... <b>BF988 +</b>	Opt. Fuel/Water Separator..... <b>BF1221 +</b>
Fuel/Water Separator (w/Drain) (8159975)..... <b>BF1329</b>	O. Air (1660619)..... <b>PA2707</b>	P. Fuel Ele..... <b>F950-F</b>
Fuel/Water Separator (w/Sensor Port Thd. 9/16-18) (8159975)..... <b>BF1329-SP</b>	I. Air (1544298)..... <b>PA2773</b>	S. Fuel Ele. (233897)..... <b>PF950</b>
Fuel/Water Separator (w/Sensor Port Thd. 1/2-20) (8159975)..... <b>BF1339-SP +</b>	Air (S/N 30600-up) (1660903)..... <b>PA2775</b>	Fuel Spin-on (243004)..... <b>BF988 +</b>
Fuel (22480372)..... <b>BF46161</b>	Some Air (1544449)..... <b>PA2774</b>	Air (475338)..... <b>PA2869</b>
O. Air (1660377-1)..... <b>PA2915</b>	Breather (15868821)..... <b>PA2798</b>	Air (475755)..... <b>PA2757</b>
I. Air (1660376-3)..... <b>PA2914</b>	Some Steering (349619)..... <b>P106-HD</b>	
Breather (1586882-1)..... <b>PA2798</b>	Hyd. (Gear Box Spin-on) (1266286)..... <b>B163</b>	
Steering (349619)..... <b>P106-HD</b>	N12 w/TD120E, TD120G, TD120GA Engs.	N88, NB88 w/TD100A, TD100B Engs.
FLC	F-F Lube Spin-on (4666343)..... <b>B76 +</b>	Lube Spin-on (4231353)..... <b>B975</b>
Lube (3976603)..... <b>BT237 +</b>	F-F Lube Spin-on (Upgrade)..... <b>B76-SS +</b>	S. Fuel Ele. (233897)..... <b>PF950</b>
Fuel (3976655)..... <b>BF5587-D</b>	Fuel Spin-on (466987)..... <b>BF988 +</b>	Fuel Spin-on (4669875)..... <b>BF988 +</b>
FM7	O. Air (1660619)..... <b>PA2707</b>	O. Air (476769)..... <b>PA2869</b>
Fuel/Water Separator (Open End for Bowl) (8159975)..... <b>BF46083-O</b>	I. Air (1544298)..... <b>PA2773</b>	
Opt. Fuel/Water Separator (Open End for Bowl) (20514654)..... <b>BF1366-O</b>	Air (S/N 30600-up) (1660903)..... <b>PA2775</b>	NL10 w/TD102, TD103 Engs.
Fuel (206.4 mm) (8193841)..... <b>BF7653</b>	Breather (15868821)..... <b>PA2798</b>	F-F Lube (466634)..... <b>B76 +</b>
Fuel (420799)..... <b>BF7644</b>	Some Steering (349619)..... <b>P106-HD</b>	F-F Lube (Upgrade)..... <b>B76-SS +</b>
Fuel (20430751)..... <b>BF7814</b>	Hyd. (Gear Box Spin-on) (1266286)..... <b>B163</b>	Fuel Spin-on (4669875)..... <b>BF988 +</b>
Fuel (22480372)..... <b>BF46161</b>	N7 w/TD70B, TD70E Engs.	
Fuel/Water Separator (w/Bowl) (8159975)..... <b>BF46072</b>	Lube Spin-on (423135)..... <b>B975</b>	TF10 w/TD101F, TD101G Engs.
Fuel/Water Separator (w/Drain) (8159975)..... <b>BF1329</b>	Fuel Spin-on (466987)..... <b>BF988 +</b>	F-F Lube..... [2] <b>B76 +</b>
Fuel/Water Separator (w/Sensor Port Thd. 9/16-18) (8159975)..... <b>BF1329-SP</b>	O. Air (1660619)..... <b>PA2707</b>	F-F Lube (Upgrade)..... [2] <b>B76-SS +</b>
Fuel/Water Separator (w/Sensor Port Thd. 1/2-20) (8159975)..... <b>BF1339-SP +</b>	I. Air (1544298)..... <b>PA2773</b>	B-P Lube..... <b>B7685</b>
Radial Seal Air (8149064)..... <b>RS4966</b>	Breather (15868821)..... <b>PA2798</b>	Fuel..... [2] <b>BF988 +</b>
Cab Air (8143691)..... <b>PA3839</b>	Some Steering (349619)..... <b>P106-HD</b>	O. Air (1660376)..... <b>PA2914</b>
N10 w/TD100, TD101, TD102 Engs.	Hyd. (Gear Box) (15268956)..... <b>P18-HD</b>	I. Air (1660377)..... <b>PA2915</b>
F-F Lube Spin-on (4666343)..... [2] <b>B76 +</b>	N7 w/TD70G Eng.	TF12 w/TD121F, TD121G Engs.
F-F Lube Spin-on (Upgrade)..... [2] <b>B76-SS +</b>	F-F Lube Spin-on (4666343)..... <b>B76 +</b>	F-F Lube..... [2] <b>B76 +</b>
Fuel Spin-on (466987)..... [2] <b>BF988 +</b>	F-F Lube Spin-on (Upgrade)..... <b>B76-SS +</b>	F-F Lube (Upgrade)..... [2] <b>B76-SS +</b>
O. Air (1660619)..... <b>PA2707</b>	Fuel Spin-on (466987)..... <b>BF988 +</b>	B-P Lube..... <b>B7685</b>
I. Air (1544298)..... <b>PA2773</b>	O. Air (1660619)..... <b>PA2707</b>	Fuel..... [2] <b>BF988 +</b>
Air (S/N 30600-up) (1660903)..... <b>PA2775</b>	I. Air (1544298)..... <b>PA2773</b>	O. Air (1660376)..... <b>PA2914</b>
Breather (15868821)..... <b>PA2798</b>	Breather (15868821)..... <b>PA2798</b>	I. Air (1660377)..... <b>PA2915</b>
Some Steering (349619)..... <b>P106-HD</b>	Some Steering (349619)..... <b>P106-HD</b>	TL385 w/D67 Eng.
Hyd. (Gear Box) (15268956)..... <b>P18-HD</b>	Hyd. (Gear Box) (15268956)..... <b>P18-HD</b>	Fuel Ele. (78472)..... <b>PF838</b>
N10 w/TD100B Eng.	N86 w/TD100 Eng.	VAH w/D11 (10.8L) Eng. (2018)
Lube Spin-on (423135)..... <b>B975</b>	Lube Spin-on (423135)..... <b>B975</b>	F-F Lube (21707133)..... [2] <b>B76 +</b>
Fuel Spin-on (466987)..... <b>BF988 +</b>	Opt. Fuel/Water Separator..... <b>BF1221 +</b>	B-P Lube (21707132)..... <b>B7409</b>
O. Air (1660619)..... <b>PA2707</b>	P. Fuel Ele..... <b>F950-F</b>	Severe Service F-F Lube (21707133)..... [2] <b>B76-SS +</b>
I. Air (1544298)..... <b>PA2773</b>	S. Fuel Ele. (233897)..... <b>PF950</b>	Fuel/Water Separator (21737499)..... <b>PF7930</b>
Air (S/N 30600-up) (1660903)..... <b>PA2775</b>	Fuel Spin-on (243004)..... <b>BF988 +</b>	Fuel (22474709)..... <b>BF46117</b>
Breather (15868821)..... <b>PA2798</b>	Air (475338)..... <b>PA2869</b>	Radial Seal Air (21715813)..... <b>RS4642</b>
Some Steering (349619)..... <b>P106-HD</b>	Air (475755)..... <b>PA2757</b>	Cab Air (20435801)..... <b>PA4681</b>
Hyd. (Gear Box) (15268956)..... <b>P18-HD</b>		Air Dryer (Bendix 65624)..... <b>BA5373</b>
N86, NB86 w/D70A, D70B, TD70A, TD70B Engs.	N86, NB86 w/D70A, D70B, TD70A, TD70B Engs.	Coolant (21937327)..... <b>B5145</b>
Lube Spin-on (423135)..... <b>B975</b>	Lube Spin-on (423135)..... <b>B975</b>	Trans. (21479106)..... <b>PT9417</b>
Can-Type Fuel (236628)..... <b>BF825 +</b>	Can-Type Fuel (236628)..... <b>BF825 +</b>	Steering (85108880)..... <b>P528</b>
Fuel Spin-on (4669875)..... <b>BF988 +</b>	Fuel Spin-on (4669875)..... <b>BF988 +</b>	Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>
O. Air (476769)..... <b>PA2869</b>	O. Air (476769)..... <b>PA2869</b>	Diesel Exhaust Fluid (Filler Neck) (82269261)..... <b>PE17001</b>
		Diesel Exhaust Fluid (Tank Filter) (21516229)..... <b>PE17000</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).


VOLVO North America Trucks (cont'd)	VOLVO North America Trucks (cont'd)	VOLVO North America Trucks (cont'd)
VAH w/D11 (10.8L) Eng. (2019)	VAH w/D13 (12.8L) Eng. (2019) (Cont'd)	VAH200 w/D13 (12.8L) Eng. (2018) (Cont'd)
F-F Lube (21707133)..... [2] B76 +	<b>Severe Service F-F Lube</b>	<b>Air Dryer</b> (Bendix 65624)..... BA5373
B-P Lube (21707132)..... B7409	(21707133)..... [2] B76-SS +	<b>Coolant</b> (21937327)..... B5145
<b>Severe Service F-F Lube</b>	<b>Fuel/Water Separator</b>	<b>Trans.</b> (21479106)..... PT9417
(21707133)..... [2] B76-SS +	(21737499)..... PF7930	<b>Steering</b> (85108880)..... P528
<b>Fuel/Water Separator</b>	<b>Fuel</b> (22474709)..... BF46117	<b>Opt. Rear Axle</b> (Meritor
(Fleetguard FS19765)..... PF7930	<b>Radial Seal Air</b> (21715813)..... RS4642	3280V8394)..... B233
<b>Fuel</b> (22474709)..... BF46117	<b>Cab Air</b> (20435801)..... PA4681	<b>Diesel Exhaust Fluid</b> (Filler Neck)
<b>Radial Seal Air</b> (21715813)..... RS4642	<b>Coolant</b> (21937327)..... B5145	(82269261)..... PE17001
<b>Cab Air</b> (20435801)..... PA4681	<b>Trans.</b> (21479106)..... PT9417	<b>Diesel Exhaust Fluid</b> (Tank)
<b>Coolant</b> (21937327)..... B5145	<b>Opt. Rear Axle</b> (Meritor	(21516229)..... PE17000
<b>Trans. Ele.</b> (21479106)..... PT9417	3280V8394)..... B233	
<b>Opt. Trans. Spin-on</b> (Fuller	VAH w/D13 (12.8L) Eng. (2020)	VAH430 w/D13 (12.8L) Eng. (2011-16)
17237)..... B2	F-F Lube (21707133)..... [2] B76 +	F-F Lube (21707133)..... [2] B76 +
<b>Opt. Rear Axle</b> (Meritor	B-P Lube (21707132)..... B7409	B-P Lube (21707132)..... B7409
3280V8394)..... B233	<b>Fuel/Water Separator</b>	B-P Lube (4775565)..... B7685
	(85120233)..... PF7930	<b>Severe Service F-F Lube</b>
VAH w/D11 (10.8L) Eng. (2020)	<b>Fuel</b> (22474709)..... BF46117	(21707133)..... [2] B76-SS +
F-F Lube (21707133)..... [2] B76	<b>Radial Seal Air</b> (21715813)..... RS4642	<b>Fuel/Water Separator Ele.</b>
B-P Lube (21707132)..... B7409	<b>Cab Air</b> (20435801)..... PA4681	(Davco 382) (21737499)..... PF7930
<b>Fuel/Water Separator</b>	<b>Coolant</b> (21937327)..... B5145	<b>Fuel/Water Separator Spin-on</b>
(Fleetguard FS19765)..... PF7930	<b>Trans.</b> (Fuller 4304827)..... BT223	(21380475)..... BF1386-O
<b>Fuel</b> (22474709)..... BF46117	<b>Opt. Trans.</b> (Fuller 17237)..... B2	<b>Fuel</b> (20976003)..... BF7814
<b>Radial Seal Air</b> (21715813)..... RS4642	<b>Opt. Rear Axle</b> (Meritor	<b>Fuel</b> (21879886)..... BF46233
<b>Cab Air</b> (20435801)..... PA4681	3280V8394)..... B233	<b>Radial Seal Air</b> (21716424)..... RS4642
<b>Coolant</b> (21937327)..... B5145		<b>Cab Air</b> (20435801)..... [2] PA4681
<b>Trans.</b> (Fuller 4304827)..... BT223	VAH w/D13 (12.8L) Eng. (2021)	<b>Air Dryer</b> (Bendix 109493)..... BA5373
<b>Opt. Trans.</b> (Fuller 17237)..... B2	F-F Lube (23151592)..... [2] B40153	<b>Coolant</b> (21937327)..... B5145
<b>Opt. Rear Axle</b> (Meritor	F-F Lube (21707133)..... [2] B76	<b>Trans.</b> (21479106)..... PT9417
3280V8394)..... B233	B-P Lube (21707132)..... B7409	<b>Steering</b> (Fleetguard 3937557S).. PT9354-MPG
	<b>Fuel</b> (23856886)..... BF46117	<b>Diesel Exhaust Fluid</b> (21516229) PE17000
VAH w/D11 (10.8L) Eng. (2021)	VAH200 w/D13 (12.8L) Eng. (2011-17)	VAH430 w/D13 (EPA 2017) (12.8L) Eng. (2017)
F-F Lube (21707133)..... [2] B76	F-F Lube (21707133)..... [2] B76 +	F-F Lube (21707133)..... [2] B76 +
B-P Lube (21707132)..... B7409	B-P Lube (21707132)..... B7409	B-P Lube (21707132)..... B7409
<b>Fuel</b> (23856886)..... BF46117	<b>Severe Service F-F Lube</b>	B-P Lube (4775565)..... B7685
<b>Coolant</b> (21937327)..... B5145	(21707133)..... [2] B76-SS +	<b>Severe Service F-F Lube</b>
	<b>Fuel/Water Separator Ele.</b>	(21707133)..... [2] B76-SS +
VAH w/D13 (12.8L) Eng. (2018)	(21737499)..... PF7930	<b>Fuel/Water Separator Ele.</b>
F-F Lube (21707133)..... [2] B76 +	<b>Fuel</b> (23044511)..... BF46233	(Davco 382) (21737499)..... PF7930
B-P Lube (21707132)..... B7409	<b>Radial Seal O. Air</b> (20411815)..... RS4642	<b>Fuel/Water Separator Spin-on</b>
<b>Severe Service F-F Lube</b>	<b>Radial Seal I. Air</b> (20411816)..... RS4643	(21380475)..... BF1386-O
(21707133)..... [2] B76-SS +	<b>Cab Air</b> (20435801)..... PA4681	<b>Fuel</b> (20976003)..... BF7814
<b>Fuel/Water Separator</b>	<b>Air Dryer</b> (System Saver 1200)	<b>Fuel</b> (21879886)..... BF46233
(21737499)..... PF7930	(Wabco R950011)..... BA5374 +	<b>Radial Seal Air</b> (21716424)..... RS4642
<b>Fuel</b> (22474709)..... BF46117	<b>Air Dryer</b> (Volvo 85110799)..... BA5592 <sup>90</sup>	<b>Cab Air</b> (20435801)..... [2] PA4681
<b>Radial Seal Air</b> (21715813)..... RS4642	<b>Coolant</b> (21937327)..... B5145	<b>Air Dryer</b> (Bendix 109493)..... BA5373
<b>Cab Air</b> (20435801)..... PA4681	<b>Trans. Ele.</b> (1521527)..... PT9417	<b>Coolant</b> (21937327)..... B5145
<b>Air Dryer</b> (Bendix 65624)..... BA5373	<b>Trans. Spin-on</b> (Fuller 4304827).. BT223	<b>Trans.</b> (21479106)..... PT9417
<b>Coolant</b> (21937327)..... B5145	<b>Steering</b> (Nelson 87904M)..... PT9354-MPG	<b>Steering</b> (Fleetguard 3937557S).. PT9354-MPG
<b>Trans.</b> (21479106)..... PT9417	<b>Diesel Exhaust Fluid</b> (82269261) PE17001	<b>Diesel Exhaust Fluid</b> (21516229) PE17000
<b>Steering</b> (85108880)..... P528		
<b>Opt. Rear Axle</b> (Meritor	VAH200 w/D13 (12.8L) Eng. (2018)	VAH430 w/D13 (12.8L) Eng. (2018)
3280V8394)..... B233	F-F Lube (21707133)..... [2] B76 +	F-F Lube (21707133)..... [2] B76 +
<b>Diesel Exhaust Fluid</b> (Filler Neck)	B-P Lube (21707132)..... B7409	B-P Lube (21707132)..... B7409
(82269261)..... PE17001	<b>Severe Service F-F Lube</b>	<b>Severe Service F-F Lube</b>
<b>Diesel Exhaust Fluid</b> (Tank)	(21707133)..... [2] B76-SS +	(21707133)..... [2] B76-SS +
(21516229)..... PE17000	<b>Fuel/Water Separator</b>	<b>Fuel/Water Separator</b>
	(21737499)..... PF7930	(21737499)..... PF7930
VAH w/D13 (12.8L) Eng. (2019)	<b>Fuel</b> (22474709)..... BF46117	<b>Fuel</b> (22474709)..... BF46117
F-F Lube (21707133)..... [2] B76 +	<b>Radial Seal Air</b> (21715813)..... RS4642	<b>Radial Seal Air</b> (21715813)..... RS4642
B-P Lube (21707132)..... B7409	<b>Cab Air</b> (20435801)..... PA4681	<b>Cab Air</b> (20435801)..... PA4681

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

VOLVO North America Trucks (cont'd)	VOLVO North America Trucks (cont'd)	VOLVO North America Trucks (cont'd)
VAH430 w/D13 (12.8L) Eng. (2018) (Cont'd)	VHD w/Cummins ISM 10.8 (10.8L) Eng.	VHD w/D11 (10.8L) Eng. (2011-17) (Cont'd)
Air Dryer (Bendix 65624)..... BA5373	Dual-Flow Lube (Fleetguard LF9001)..... BD7154 +	Fuel (20430751)..... BF7814
Coolant (21937327)..... B5145	Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... BD50000	Fuel (22480372)..... BF46161
Trans. (21479106)..... PT9417	Dual-Flow Lube (Fleetguard LF9031)..... BD7509 +	Fuel (20972293)..... BF7943
Steering (85108880)..... P528	Dual-Flow Lube (Fleetguard LF9000)..... BD7153 +	Radial Seal O. Air (20882320)..... RS4642
Opt. Rear Axle (Meritor 3280V8394)..... B233	Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	Radial Seal I. Air (20411816)..... RS4643
Diesel Exhaust Fluid (Filler Neck) (82269261)..... PE17001	Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Cab Air (20435801)..... PA4681
Diesel Exhaust Fluid (Tank) (21516229)..... PE17000	Trans. Spin-on (Fuller 17237)..... B2 +	Air Dryer (AD-SP System) (Bendix 109994)..... BA5374 +
VAH630 w/D13 (12.8L) Eng.	VHD w/Cummins ISX Eng.	Air Dryer (System Saver 1200) (Wabco R950011)..... BA5374 +
F-F Lube (21707133)..... [2] B76 +	Dual-Flow Lube (3101869)..... BD7154 +	Air Dryer (85110799)..... BA5592 90
B-P Lube (21707132)..... B7409	Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... BD50000	Trans. Ele. (1521527)..... PT9417
B-P Lube (4775565)..... B7685	Fuel/Water Separator (85105574)..... PF7680	Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT
Severe Service F-F Lube (21707133)..... [2] B76-SS +	Fuel (4920586)..... BF7766	Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT
Fuel/Water Separator Ele. (Davco 382) (21737499)..... PF7930	Radial Seal Air (20882320)..... RS4642	Trans. Spin-on (Fuller 4304827)..... BT223
Fuel/Water Separator Spin-on (21380475)..... BF1386-O	Cab Air (20435801)..... PA4681	Opt. Trans. Spin-on (Fuller 17237)..... B2 +
Fuel (20976003)..... BF7814	Air Dryer (Wabco R950011)..... BA5374 +	VHD w/D11 (10.8L) Eng. (2018)
Fuel (21879886)..... BF46233	Breather (3683918)..... CV15000	F-F Lube (21707133)..... [2] B76 +
Radial Seal Air (21715813)..... RS4642	Coolant (w/o Chemical) (Fleetguard WF2127)..... B5087	B-P Lube (21707132)..... B7409
Cab Air (20435801)..... PA4681	Coolant (w/Chemical) (Fleetguard WF2126)..... BW5086	Severe Service F-F Lube (21707133)..... [2] B76-SS +
Air Dryer (Bendix 109493)..... BA5373	Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	Fuel/Water Separator (21737499)..... PF7930
Coolant (21937327)..... B5145	Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Fuel (22474709)..... BF46117
Trans. (21479106)..... PT9417	Trans. Spin-on (Fuller 4304827)..... BT223	Radial Seal Air (21715813)..... RS4642
Steering (Fleetguard 3937557S)..... PT9354-MPG	Opt. Trans. Spin-on (Fuller 17237)..... B2 +	Cab Air (20435801)..... PA4681
Diesel Exhaust Fluid (21516229) PE17000	Steering (349619)..... P106-HD	Air Dryer (21620181)..... BA5379 +
VH200 w/VE D12 Eng.	VHD w/Cummins M11 (10.8L) Eng.	Coolant (21937327)..... B5145
F-F Lube (478736-2)..... [2] B76-SS +	Dual-Flow Lube (3318853)..... BD103 +	Trans. (21479106)..... PT9417
B-P Lube (477556)..... B7685	Fuel/Water Separator Ele. (Fleetguard FS1029W)..... PF7680	Steering (85108880)..... P528
Fuel/Water Separator (Open End for Bowl) (20514654)..... BF1366-O	Fuel/Water Separator Spin-on (3329289)..... BF1259	Opt. Rear Axle (Meritor 3280V8394)..... B233
Fuel (20430751)..... BF7814	Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	Diesel Exhaust Fluid (Filler Neck) (82269261)..... PE17001
Fuel (22480372)..... BF46161	Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Diesel Exhaust Fluid (Tank) (21516229)..... PE17000
Some Fuel (8193841)..... BF7653	Trans. Spin-on (Fuller 4304827)..... BT223	VHD w/D11 (10.8L) Eng. (2019)
Radial Seal O. Air (20411815)..... RS4642	Opt. Trans. Spin-on (Fuller 17237)..... B2 +	F-F Lube (21707133)..... [2] B76 +
Radial Seal I. Air (20411816)..... RS4643	VHD w/D11 (10.8L) Eng. (2011-17)	B-P Lube (21707132)..... B7409
Cab Air (20435801)..... PA4681	F-F Lube (478736-2)..... [2] B76-SS +	Severe Service F-F Lube (21707133)..... [2] B76-SS +
Air Dryer (AD-SP System) (Bendix 109994)..... BA5374 +	B-P Lube (477556-5)..... B7685	Fuel/Water Separator (21764964)..... BF46182-O
Air Dryer (System Saver 1200) (Wabco R950011)..... BA5374 +	Fuel/Water Separator Ele. (Davco 382) (21737499)..... PF7930	Fuel (22474709)..... BF46117
Coolant (20458771)..... B5145	Fuel/Water Separator Spin-on (Open End for Bowl) (20514654)..... BF1366-O	Radial Seal Air (21715813)..... RS4642
Opt. Trans. (Fuller 17237)..... B2 +		Cab Air (20435801)..... [2] PA4681
Steering (85108880)..... P528		Air Dryer (21620181)..... BA5379 +
VHD w/Cummins ISL 8.9 (8.9L) Eng.		Coolant (21937327)..... B5145
Dual-Flow Lube (Fleetguard LF9009)..... BD7309 +		Trans. Ele. (I-Shift) (21479106)..... PT9417
Dual-Flow Lube (Fleetguard LF9548)..... BD324 +		Trans. Ele. (2 In. Kit) (Allison 29558117)..... PT9416-MPG KIT
Fuel (Fleetguard FF5488)..... BF7815		Trans. Ele. (4 In. Kit) (Allison 29558118)..... PT9415-MPG KIT
Fuel (Fleetguard FF5636)..... BF7924		Trans. Spin-on (Fuller 4304827)..... BT223
		Steering (85108880)..... P528

+ See Product Guide for Variations of This Number. 90 Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

VOLVO North America Trucks (cont'd)	VOLVO North America Trucks (cont'd)	VOLVO North America Trucks (cont'd)
VHD w/D11 (10.8L) Eng. (2019) (Cont'd)	VHD w/D12 (12.1L) Eng. (Cont'd)	VHD w/D13 (12.8L) Eng. (2011-17) (Cont'd)
Opt. Rear Axle (Meritor 3280V8394).....	Fuel/Water Separator (Open End for Bowl) (20514654).....	Trans. Ele. (I-Shift) (1521527).....
B233	BF1366-O	PT9417
Diesel Exhaust Fluid (21516229) PE17000	Fuel/Water Separator (Alliance ABPN122R50551).....	Trans. Ele. (2 In. Kit) (Allison 29540493).....
VHD w/D11 (10.8L) Eng. (2020)	BF46016-O	PT9416-MPG KIT
F-F Lube (21707133).....	Fuel (20430751).....	Trans. Ele. (4 In. Kit) (Allison 29540494).....
[2] B76	BF7814	PT9415-MPG KIT
B-P Lube (21707132).....	Fuel (22480372).....	Trans. Spin-on (Fuller 4304827)..
B7409	BF46161	BT223
Severe Service F-F Lube (21707133).....	Some Fuel (8193841).....	Opt. Trans. Spin-on (Fuller 17237).....
[2] B76-SS +	RS4642	B2 +
Fuel/Water Separator (Open End for Bowl) (3945966).....	Opt. Radial Seal I. Air (20411816).....	2 25/32 In. Steering (w/Gasket) (Nelson 84365M).....
BF46083-O	RS4643	PT903
Fuel/Water Separator (w/Bowl) (3945966).....	Cab Air (20435801).....	2 25/32 In. Steering (w/o Gasket) (Nelson 84365M).....
BF46072	PA4681	PT951
Fuel/Water Separator (SP Thd. 1/2-20) (3945966).....	Air Dryer (AD-SP System) (Bendix 109994).....	3 31/32 In. Steering (349619).....
BF1339-SP	BA5374 +	P106-HD
Fuel/Water Separator (SP Thd. 9/16-18) (3945966).....	Air Dryer (System Saver 1200) (Wabco R950011).....	4 3/16 In. Steering (85108880).....
BF1329-SP	BA5374 +	P528
Fuel/Water Separator (w/Drain) (3945966).....	Coolant (20458771).....	Diesel Exhaust Fluid (21516229) PE17000
BF1329	B5145	VHD w/D13 (12.8L) Eng. (2018)
Fuel (22474709).....	Coolant (21388476).....	F-F Lube (21707133).....
BF46117	BW5142	[2] B76 +
Radial Seal Air (8076195).....	Trans. Ele. (1521527).....	B7409
RS3740	PT9416-MPG KIT	Severe Service F-F Lube (21707133).....
Cab Air (20435801).....	Trans. Ele. (2 In. Kit) (Allison 29540493).....	[2] B76-SS +
PA4681	PT9415-MPG KIT	Fuel/Water Separator (21737499).....
Coolant (21937327).....	Trans. Spin-on (Fuller 4304827)..	PF7930
B5145	BT223	Fuel (22474709).....
Trans. Ele. (20779040).....	Opt. Trans. Spin-on (Fuller 17237).....	BF46117
PT9417	B2 +	Radial Seal Air (21715813).....
Opt. Trans. Spin-on (Fuller 17237).....	P106-HD	RS4642
B2	P528	Cab Air (20435801).....
Steering (85108880).....	Steering (2 5/16 O.D.) (349619)...	PA4681
P528	Steering (4 3/4 O.D.) (85108880).	BA5379 +
Opt. Rear Axle (Meritor 3280V8394).....	VHD w/D13 (12.8L) Eng. (2011-17)	B5145
B233	F-F Lube (4787362).....	PT9417
Diesel Exhaust Fluid (23381562) PE17000	[2] B76-SS +	Trans. (4 In. Kit) (Allison 29548988).....
VHD w/D11 (10.8L) Eng. (2021)	[2] B76 +	PT9415-MPG KIT
F-F Lube (21707133).....	B7685	Trans. (2 In. Kit) (Allison 29548987).....
[2] B76	B7409	PT9416-MPG KIT
B-P Lube (21707132).....	Fuel/Water Separator Ele. (85105574).....	Steering (85108880).....
B7409	PF7680	P528
Fuel (23856886).....	Fuel/Water Separator Ele. (85120233).....	Opt. Rear Axle (Meritor 3280V8394).....
BF46117	PF7930	B233
Radial Seal Air (21715813).....	Fuel/Water Separator Ele. (Fleetguard FF5369W).....	Diesel Exhaust Fluid (Filler Neck) (82269261).....
RS4642	PF7744	PE17001
Coolant (21937327).....	Fuel/Water Separator Ele. (Davco 382119).....	Diesel Exhaust Fluid (Tank) (21516229).....
B5145	PF7782	PE17000
Trans. Ele. (2 In. Kit) (Allison 29558117).....	Fuel/Water Separator Spin-on (21380475).....	VHD w/D13 (12.8L) Eng. (2019)
PT9416-MPG KIT	BF1386-O	F-F Lube (21707133).....
Trans. Ele. (4 In. Kit) (Allison 29558118).....	BF7814	[2] B76 +
PT9415-MPG KIT	BF7814	B7409
Opt. Rear Axle (Meritor 3280V8394).....	Fuel (20430751).....	Severe Service F-F Lube (21707133).....
B233	BF46161	[2] B76-SS +
VHD w/D12 (12.1L) Eng.	Fuel (20972293).....	Fuel/Water Separator (21737499).....
F-F Lube (478736-2).....	BF7943	PF7930
[2] B76-SS +	RS4642	Fuel (22474709).....
B-P Lube (477556-5).....	Radial Seal O. Air (20882320).....	BF46117
B7685	RS4643	Radial Seal Air (21715813).....
Dual-Flow Lube (Fleetguard LF9001).....	PA4681	RS4642
BD7154 +	BA5374 +	Cab Air (20435801).....
Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN).....	BA5374 +	PA4681
BD50000	BA5592 <sup>90</sup>	Air Dryer (21620181).....
Fuel/Water Separator (w/Drain) (3945966).....	Coolant (w/o Chemical) (21388479).....	BA5379 +
BF1329	B5145	B5145
Fuel/Water Separator (Open End for Bowl) (3945966).....	Coolant (w/Chemical) (20458769).....	PT9417
BF46083-O	BW5142	Trans. Ele. (I-Shift) (21479106)....
Fuel/Water Separator (w/9/16-18 SP Thd.) (3945966).....		PT9416-MPG KIT
BF1329-SP		Trans. Ele. (2 In. Kit) (Allison 29558117).....
Fuel/Water Separator (w/1/2-20 SP Thd.) (3945966).....		PT9415-MPG KIT
BF1339-SP +		Trans. Spin-on (Fuller 4304827)..
Fuel/Water Separator Spin-on (w/Bowl) (3945966).....		BT223
BF46072		P528

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.

Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>VOLVO</b> <b>North America Trucks (cont'd)</b>	<b>VOLVO</b> <b>North America Trucks (cont'd)</b>	<b>VOLVO</b> <b>North America Trucks (cont'd)</b>
VHD w/D13 (12.8L) Eng. (2019) (Cont'd) Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b> Diesel Exhaust Fluid (21516229) <b>PE17000</b>	VHD200 w/D11 (10.8L) Eng. (2011-17) (Cont'd) Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Steering (w/Gasket) (Nelson 84365M)..... <b>PT903</b> Steering (w/o Gasket) (Nelson 84365M)..... <b>PT951</b> Steering (5839-84148A)..... <b>P528</b> Diesel Exhaust Fluid (21496419) <b>PE17000</b>	VHD200 w/D12 (12.1L) Eng. (Cont'd) Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> Fuel/Water Separator (w/Drain) (3945966)..... <b>BF1329</b> Fuel/Water Separator (Open End for Bowl) (3945966)..... <b>BF46083-O</b> Fuel/Water Separator (w/9/16-18 SP Thd.) (3945966)..... <b>BF1329-SP</b> Fuel/Water Separator (w/1/2-20 SP Thd.) (3945966)..... <b>BF1339-SP +</b> Fuel/Water Separator Spin-on (w/Bowl) (3945966)..... <b>BF46072</b> Fuel/Water Separator (Alliance ABPN122R50551)..... <b>BF46016-O</b> Fuel/Water Separator (Open End for Bowl) (20514654)..... <b>BF1366-O</b> Fuel (20430751)..... <b>BF7814</b> Fuel (22480372)..... <b>BF46161</b> Some Fuel (8193841)..... <b>BF7653</b> Single Radial Seal Air (20882320)..... <b>RS4642</b> Radial Seal O. Air (20411815)..... <b>RS4642</b> Radial Seal I. Air (20411816)..... <b>RS4643</b> Cab Air (20435801)..... <b>PA4681</b> Air Dryer (AD-SP System) (Bendix 109994)..... <b>BA5374 +</b> Air Dryer (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b> Coolant (20458771)..... <b>B5145</b> Trans. Ele. (1521527)..... <b>PT9417</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> 3 31/32 In. Steering (349619)..... <b>P106-HD</b> 4 3/16 In. Steering (85108880).... <b>P528</b>
VHD w/D13 (12.8L) Eng. (2020) F-F Lube (21707133)..... <b>[2] B76 +</b> B-P Lube (21707132)..... <b>B7409</b> Fuel (22474709)..... <b>BF46117</b> Radial Seal Air (8076195)..... <b>RS3740</b> Cab Air (20435801)..... <b>PA4681</b> Coolant (21937327)..... <b>B5145</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Steering (85108880)..... <b>P528</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b> Diesel Exhaust Fluid (23381562) <b>PE17000</b>	VHD200 w/D11 (10.8L) Eng. (2018) F-F Lube (21707133)..... <b>[2] B76 +</b> B-P Lube (21707132)..... <b>B7409</b> Severe Service F-F Lube (21707133)..... <b>[2] B76-SS +</b> Fuel/Water Separator (21737499)..... <b>PF7930</b> Fuel (22474709)..... <b>BF46117</b> Radial Seal Air (21715813)..... <b>RS4642</b> Cab Air (20435801)..... <b>PA4681</b> Air Dryer (21620181)..... <b>BA5379 +</b> Coolant (21937327)..... <b>B5145</b> Trans. (21479106)..... <b>PT9417</b> Steering (85108880)..... <b>P528</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b> Diesel Exhaust Fluid (Filler Neck) (82269261)..... <b>PE17001</b> Diesel Exhaust Fluid (Tank) (21516229)..... <b>PE17000</b>	VHD200 w/D12 (12.1L) Eng. (Cont'd) F-F Lube (21707133)..... <b>[2] B76 +</b> F-F Lube (Severe Service) (4787362)..... <b>[2] B76-SS +</b> B-P Lube (477556-5)..... <b>B7685</b> B-P Lube (21707132)..... <b>B7409</b> Fuel/Water Separator Ele. (21737499)..... <b>PF7930</b> Fuel/Water Separator Spin-on (Open End for Bowl) (20514654).. <b>BF1366-O</b> Fuel (20430751)..... <b>BF7814</b> Fuel (22480372)..... <b>BF46161</b> Fuel (23044511)..... <b>BF46233</b> Radial Seal Air (20882320)..... <b>RS4642</b> Cab Air (20435801)..... <b>PA4681</b> Air Dryer (Bendix 109994)..... <b>BA5374 +</b> Air Dryer (85110799)..... <b>BA5592<sup>90</sup></b> Coolant (w/o Chemicals) (21937327)..... <b>B5145</b> Coolant (w/8 Units BTE) (3945411)..... <b>BW5142</b> Trans. Ele. (1521527)..... <b>PT9417</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>
VHD w/D13 (12.8L) Eng. (2021) F-F Lube (21707133)..... <b>[2] B76</b> B-P Lube (21707132)..... <b>B7409</b> F-F Lube (23151592)..... <b>[2] B40153</b> Fuel (23856886)..... <b>BF46117</b> Radial Seal Air (21715813)..... <b>RS4642</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Trans. Ele. (20779040)..... <b>PT9417</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	VHD200 w/D11 (10.8L) Eng. (2019) F-F Lube (21707133)..... <b>[2] B76 +</b> B-P Lube (21707132)..... <b>B7409</b> Severe Service F-F Lube (21707133)..... <b>[2] B76-SS +</b> Fuel/Water Separator (21764964)..... <b>BF46182-O</b> Fuel (22474709)..... <b>BF46117</b> Radial Seal Air (21715813)..... <b>RS4642</b> Cab Air (20435801)..... <b>[2] PA4681</b> Air Dryer (21620181)..... <b>BA5379 +</b> Coolant (21937327)..... <b>B5145</b> Trans. Ele. (I-Shift) (21479106).... <b>PT9417</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Steering (85108880)..... <b>P528</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b> Diesel Exhaust Fluid (21516229) <b>PE17000</b>	VHD200 w/D13 (12.8L) Eng. (2011-17) F-F Lube (21707133)..... <b>[2] B76 +</b> F-F Lube (21707133)..... <b>[2] B76 +</b> Fuel/Water Separator Ele. (21737499)..... <b>PF7930</b> Fuel/Water Separator Spin-on (Open End for Bowl) (20514654).. <b>BF1366-O</b> Fuel (20430751)..... <b>BF7814</b> Fuel (22480372)..... <b>BF46161</b> Fuel (20972293)..... <b>BF7943</b> Radial Seal O. Air (20411815).... <b>RS4642</b> Radial Seal I. Air (20411816)..... <b>RS4643</b>
VHD w/D13 (12.8L) Eng. (2022) Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	VHD200 w/D11 (10.8L) Eng. (2011-17) F-F Lube (4787362)..... <b>[2] B76-SS +</b> B-P Lube (477556-5)..... <b>B7685</b> B-P Lube (21707132)..... <b>B7409</b> Fuel/Water Separator Ele. (Davco 382) (21737499)..... <b>PF7930</b> Fuel/Water Separator Spin-on (Open End for Bowl) (20514654).. <b>BF1366-O</b> Fuel (20430751)..... <b>BF7814</b> Fuel (22480372)..... <b>BF46161</b> Fuel (23044511)..... <b>BF46233</b> Radial Seal Air (20882320)..... <b>RS4642</b> Cab Air (20435801)..... <b>PA4681</b> Air Dryer (Bendix 109994)..... <b>BA5374 +</b> Air Dryer (85110799)..... <b>BA5592<sup>90</sup></b> Coolant (w/o Chemicals) (21937327)..... <b>B5145</b> Coolant (w/8 Units BTE) (3945411)..... <b>BW5142</b> Trans. Ele. (1521527)..... <b>PT9417</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	VHD200 w/D13 (12.8L) Eng. (2011-17) F-F Lube (21707133)..... <b>[2] B76 +</b> F-F Lube (Severe Service) (4787362)..... <b>[2] B76-SS +</b> B-P Lube (477556-5)..... <b>B7685</b> B-P Lube (21707132)..... <b>B7409</b> Fuel/Water Separator Ele. (21737499)..... <b>PF7930</b> Fuel/Water Separator Ele. (85105574)..... <b>PF7680</b> Fuel/Water Separator Ele. (Fleetguard FF5369W)..... <b>PF7744</b> Fuel/Water Separator Spin-on (Open End for Bowl) (20514654).. <b>BF1366-O</b> Fuel (20430751)..... <b>BF7814</b> Fuel (22480372)..... <b>BF46161</b> Fuel (20972293)..... <b>BF7943</b> Radial Seal O. Air (20411815).... <b>RS4642</b> Radial Seal I. Air (20411816)..... <b>RS4643</b>

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

VOLVO North America Trucks (cont'd)	VOLVO North America Trucks (cont'd)	VOLVO North America Trucks (cont'd)
VHD200 w/D13 (12.8L) Eng. (2011-17) (Cont'd)	VHD200 w/D13 (12.8L) Eng. (2019) (Cont'd)	VHD300 w/D11 (10.8L) Eng. (2020) (Cont'd)
<b>Cab Air</b> (20435801)..... <b>PA4681</b>	<b>Trans. Ele.</b> (I-Shift) (21479106).... <b>PT9417</b>	<b>Diesel Exhaust Fluid</b> (23381562) <b>PE17000</b>
<b>Air Dryer</b> (AD-SP System) (Bendix 109994)..... <b>BA5374 +</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	VHD300 w/D13 (12.8L) Eng. (2019)
<b>Air Dryer</b> (System Saver 1200) (Wabco R950011)..... <b>BA5374 +</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	<b>F-F Lube</b> (21707133)..... <b>[2] B76 +</b>
<b>Air Dryer</b> (85110799)..... <b>BA5592<sup>90</sup></b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>B-P Lube</b> (21707132)..... <b>B7409</b>
<b>Coolant</b> (w/o Chemical) (20458771)..... <b>B5145</b>	<b>Steering</b> (85108880)..... <b>P528</b>	<b>Severe Service F-F Lube</b> (21707133)..... <b>[2] B76-SS +</b>
<b>Coolant</b> (w/Chemical) (20458769)..... <b>BW5142</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	<b>Fuel/Water Separator</b> (21764964)..... <b>BF46182-O</b>
<b>Trans. Ele.</b> (1521527)..... <b>PT9417</b>	<b>Diesel Exhaust Fluid</b> (21516229) <b>PE17000</b>	<b>Fuel</b> (22474709)..... <b>BF46117</b>
<b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	VHD300 w/D11 (10.8L) Eng. (2019)	<b>Radial Seal Air</b> (21715813)..... <b>RS4642</b>
<b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>F-F Lube</b> (21707133)..... <b>[2] B76 +</b>	<b>Cab Air</b> (20435801)..... <b>[2] PA4681</b>
<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>B-P Lube</b> (21707132)..... <b>B7409</b>	<b>Air Dryer</b> (21620181)..... <b>BA5379 +</b>
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Severe Service F-F Lube</b> (21707133)..... <b>[2] B76-SS +</b>	<b>Coolant</b> (21937327)..... <b>B5145</b>
<b>3 31/32 In. Steering</b> (349619)..... <b>P106-HD</b>	<b>Fuel/Water Separator</b> (21764964)..... <b>BF46182-O</b>	<b>Trans. Ele.</b> (I-Shift) (21479106).... <b>PT9417</b>
<b>4 3/16 In. Steering</b> (85108880).... <b>P528</b>	<b>Fuel</b> (22474709)..... <b>BF46117</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>
<b>Diesel Exhaust Fluid</b> (82269261) <b>PE17001</b>	<b>Radial Seal Air</b> (21715813)..... <b>RS4642</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>
<b>Diesel Exhaust Fluid</b> (21516229) <b>PE17000</b>	<b>Cab Air</b> (20435801)..... <b>[2] PA4681</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>
VHD200 w/D13 (12.8L) Eng. (2018)	<b>Air Dryer</b> (21620181)..... <b>BA5379 +</b>	<b>Steering</b> (85108880)..... <b>P528</b>
<b>F-F Lube</b> (21707133)..... <b>[2] B76 +</b>	<b>Coolant</b> (21937327)..... <b>B5145</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
<b>B-P Lube</b> (21707132)..... <b>B7409</b>	<b>Trans.</b> (21479106)..... <b>PT9417</b>	<b>Diesel Exhaust Fluid</b> (21516229) <b>PE17000</b>
<b>Severe Service F-F Lube</b> (Severe Service) (21707133)..... <b>[2] B76-SS +</b>	<b>Trans. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b></b>	VHD300 w/D11 (10.8L) Eng. (2020)
<b>Fuel/Water Separator</b> (21737499)..... <b>PF7930</b>	<b>Trans. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b></b>	<b>F-F Lube</b> (21707133)..... <b>[2] B76</b>
<b>Fuel</b> (22474709)..... <b>BF46117</b>	<b>Steering</b> (85108880)..... <b>P528</b>	<b>B-P Lube</b> (21707132)..... <b>B7409</b>
<b>Radial Seal Air</b> (21715813)..... <b>RS4642</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	<b>Severe Service F-F Lube</b> (21707133)..... <b>[2] B76-SS +</b>
<b>Cab Air</b> (20435801)..... <b>PA4681</b>	<b>Diesel Exhaust Fluid</b> (Filler Neck) (82269261)..... <b>PE17001</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (3945966)..... <b>BF46083-O</b>
<b>Air Dryer</b> (21620181)..... <b>BA5379 +</b>	<b>Diesel Exhaust Fluid</b> (Tank) (21516229)..... <b>PE17000</b>	<b>Fuel/Water Separator</b> (w/Bowl) (3945966)..... <b>BF46072</b>
<b>Coolant</b> (21937327)..... <b>B5145</b>	VHD200 w/D13 (12.8L) Eng. (2019)	<b>Fuel/Water Separator</b> (SP Thd. 1/2-20) (3945966)..... <b>BF1339-SP</b>
<b>Trans.</b> (21479106)..... <b>PT9417</b>	<b>F-F Lube</b> (21707133)..... <b>[2] B76 +</b>	<b>Fuel/Water Separator</b> (SP Thd. 9/16-18) (3945966)..... <b>BF1329-SP</b>
<b>Trans. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b></b>	<b>B-P Lube</b> (21707132)..... <b>B7409</b>	<b>Fuel/Water Separator</b> (w/Drain) (3945966)..... <b>BF1329</b>
<b>Trans. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b></b>	<b>Severe Service F-F Lube</b> (21707133)..... <b>[2] B76-SS +</b>	<b>Fuel</b> (22474709)..... <b>BF46117</b>
<b>Steering</b> (85108880)..... <b>P528</b>	<b>Fuel/Water Separator</b> (21764964)..... <b>BF46182-O</b>	<b>Radial Seal Air</b> (8076195)..... <b>RS3740</b>
<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	<b>Fuel</b> (22474709)..... <b>BF46117</b>	<b>Cab Air</b> (20435801)..... <b>PA4681</b>
<b>Diesel Exhaust Fluid</b> (Filler Neck) (82269261)..... <b>PE17001</b>	<b>Radial Seal Air</b> (21715813)..... <b>RS4642</b>	<b>Coolant</b> (21937327)..... <b>B5145</b>
<b>Diesel Exhaust Fluid</b> (Tank) (21516229)..... <b>PE17000</b>	<b>Cab Air</b> (20435801)..... <b>[2] PA4681</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>
VHD200 w/D13 (12.8L) Eng. (2019)	<b>Air Dryer</b> (21620181)..... <b>BA5379 +</b>	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>
<b>F-F Lube</b> (21707133)..... <b>[2] B76 +</b>	<b>Coolant</b> (21937327)..... <b>B5145</b>	<b>Steering</b> (85108880)..... <b>P528</b>
<b>B-P Lube</b> (21707132)..... <b>B7409</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
<b>Severe Service F-F Lube</b> (21707133)..... <b>[2] B76-SS +</b>	<b>Fuel/Water Separator</b> (21764964)..... <b>BF46182-O</b>	<b>Diesel Exhaust Fluid</b> (23381562) <b>PE17000</b>
<b>Fuel/Water Separator</b> (21764964)..... <b>BF46182-O</b>	<b>Fuel</b> (22474709)..... <b>BF46117</b>	VHD430 w/D13 (12.8L) Eng. (To 2018)
<b>Fuel</b> (22474709)..... <b>BF46117</b>	<b>Radial Seal Air</b> (21715813)..... <b>RS4642</b>	<b>F-F Lube</b> (4787362)..... <b>[2] B76-SS +</b>
<b>Radial Seal Air</b> (21715813)..... <b>RS4642</b>	<b>Cab Air</b> (20435801)..... <b>[2] PA4681</b>	<b>B-P Lube</b> (477556-5)..... <b>B7685</b>
<b>Cab Air</b> (20435801)..... <b>[2] PA4681</b>	<b>Air Dryer</b> (21620181)..... <b>BA5379 +</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FF5369)..... <b>PF7744</b>
<b>Air Dryer</b> (21620181)..... <b>BA5379 +</b>	<b>Coolant</b> (21937327)..... <b>B5145</b>	<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (20514654).. <b>BF1366-O</b>
<b>Coolant</b> (21937327)..... <b>B5145</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	<b>Fuel/Water Separator</b> (w/Drain and Sensor Port) (Racor R12P).... <b>BF1381</b>
	<b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R12P)..... <b>BF1381-O</b>
	<b>Steering</b> (85108880)..... <b>P528</b>	<b>Fuel</b> (20430751)..... <b>BF7814</b>
	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	<b>Fuel</b> (22480372)..... <b>BF46161</b>
		<b>Fuel</b> (20972293)..... <b>BF7943</b>
		<b>Single Radial Seal Air</b> (20882320)..... <b>RS4642</b>
		<b>Cab Air</b> (20435801)..... <b>PA4681</b>
		<b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b>

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.

Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>VOLVO</b> North America Trucks (cont'd)	<b>VOLVO</b> North America Trucks (cont'd)	<b>VOLVO</b> North America Trucks (cont'd)
VHD430 w/D13 (12.8L) Eng. (To 2018) (Cont'd)	VN w/Cat 3306 (10.5L) Eng. (Cont'd)	VN Series w/VE D11 Eng. (Cont'd)
Coolant (20458769)..... BW5142	P. Fuel Spin-on (1R1740)..... BF970 +	Opt. Trans. (Fuller 17237)..... B2 +
Trans. Ele. (1521527)..... PT9417	S. Fuel Spin-on (1R0750)..... BF7633 +	Steering (349619)..... P106-HD
Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	VN w/Cat 3406 (14.6L) Eng.	VN Series w/VE D12 Eng.
Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	F-F Lube (Std. Version) (1R0716)..... B99 +	F-F Lube (478736)..... [2] B76-SS +
Trans. Spin-on (Fuller 4304827).. BT223	F-F Lube (High Efficiency Vers.) (1R1808)..... B7299 +	B-P Lube (477556)..... B7685
Opt. Trans. Spin-on (Fuller 17237)..... B2 +	Fuel/Water Separator Spin-on (8N0205)..... BF1268	Fuel/Water Separator Ele. (Davco 382119)..... PF7782
Steering (349619)..... P106-HD	Fuel/Water Separator Spin-on (2568753)..... BF1259	Fuel/Water Separator Spin-on (Alliance ABPN122R50551)..... BF46016-O
VHD430 w/D13 (12.8L) Eng. (2019)	Fuel Spin-on (1R0749)..... BF7587 +	P. Fuel (8193841)..... BF7653
F-F Lube (21707133)..... [2] B76 +	Fuel (1R0712)..... BF614 +	P. Fuel (20430751)..... BF7814
B-P Lube (21707132)..... B7409	Trans. (Fuller 4304827)..... BT223	P. Fuel (22480372)..... BF46161
Severe Service F-F Lube (21707133)..... [2] B76-SS +	Opt. Trans. (Fuller 17237)..... B2 +	Radial Seal O. Air (20411815)..... RS4642
Fuel/Water Separator (21764964)..... BF46182-O	VN w/Cummins M11 (10.8L) Eng.	Radial Seal I. Air (20411816)..... RS4643
Fuel (22474709)..... BF46117	Dual-Flow Lube (3318853)..... BD103 +	Radial Seal O. Air (8076195)..... RS3740
Radial Seal Air (21715813)..... RS4642	Fuel/Water Separator Ele. (Fleetguard FS1029W)..... PF7680	Radial Seal I. Air (8079756)..... RS3741
Cab Air (20435801)..... PA4681	Fuel/Water Separator Spin-on (3329289)..... BF1259	Cab Air (20435801)..... PA4681
Air Dryer (21620181)..... BA5379 +	Coolant (3318318)..... BW5075	Air Dryer (3915558)..... BA5374 +
Coolant (21937327)..... B5145	Trans. Spin-on (Fuller 4304827).. BT223	4 7/16 In. Coolant (20458771)..... B5145
Trans. Ele. (I-Shift) (21479106).... PT9417	Opt. Trans. Spin-on (Fuller 17237)..... B2 +	5 15/32 In. Coolant (Fleetguard WF2127)..... B5087
Trans. Ele. (2 In. Kit) (Allison 29558117)..... PT9416-MPG KIT	VN w/Cummins N14 (14.0L) Eng.	Opt. Trans. (Fuller 17237)..... B2 +
Trans. Ele. (4 In. Kit) (Allison 29558118)..... PT9415-MPG KIT	Dual-Flow Lube (3318853)..... BD103 +	Steering (349619)..... P106-HD
Trans. Spin-on (Fuller 4304827).. BT223	B-P Lube (1W8845)..... B7577	VN Series w/VE D13 Eng.
Steering (85108880)..... P528	F-F Lube (Fleetguard LF670SC).. B196 +	F-F Lube (4787362)..... [2] B76-SS +
Opt. Rear Axle (Meritor 3280V8394)..... B233	Opt. Fuel/Water Separator (3329289)..... BF1259	B-P Lube (477556-5)..... B7685
Diesel Exhaust Fluid (21516229) PE17000	Fuel (154789)..... BF957-D +	Fuel/Water Separator Ele. (Fleetguard FF5369)..... PF7744
VLE w/D7E Eng. (Mexico)	Trans. Spin-on (Fuller 4304827).. BT223	Fuel/Water Separator (Open End for Bowl) (20514654)..... BF1366-O
Lube (478736)..... [2] B76-SS +	Opt. Trans. Spin-on (Fuller 17237)..... B2 +	P. Fuel Spin-on (20430751)..... BF7814
Fuel/Water Separator (20386080)..... BF1398-O	VN w/Cummins Signature 600 (15.0L) Eng.	P. Fuel Spin-on (22480372)..... BF46161
Fuel (8193841)..... BF7653	11 25/32 In. Dual-Flow Lube (Fleetguard LF9001)..... BD7154 +	Radial Seal O. Air (20411815)..... RS4642
VN w/Cat 3176 (10.3L) Eng.	14 7/32 In. Dual-Flow Lube (Fleetguard LF9000)..... BD7153 +	Radial Seal I. Air (20411816)..... RS4643
F-F Lube (Std. Version) (1R0716)..... B99 +	Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... BD50000	Cab Air (20435801)..... PA4681
F-F Lube (High Efficiency Vers.) (1R1808)..... B7299 +	Fuel/Water Separator (3331096). BF1274-SP	Air Dryer (Wabco R950011)..... BA5374 +
Opt. B-P Lube (1W8845)..... B7577	Fuel/Water Separator (4010651). BF1277-SPS	Opt. Trans. (Fuller 17237)..... B2 +
Fuel/Water Separator Ele. (8N0205)..... PF316	Coolant (Fleetguard WF2126)..... BW5086	Steering (349619)..... P106-HD
Fuel/Water Separator Spin-on (2568753)..... BF1259	VN Series w/Detroit Diesel Series 60 Eng.	VN Series w/VE D16 Eng.
P. Fuel Ele. (9M2342)..... [2] PF935	Radial Seal O. Air (8076195)..... RS3740	F-F Lube (478736)..... [2] B76-SS +
P. Fuel Spin-on (1R1740)..... BF970 +	Radial Seal I. Air (8079756)..... RS3741	B-P Lube (477556)..... B7685
S. Fuel Spin-on (1R0750)..... BF7633 +	VN Series w/VE D11 Eng.	Fuel/Water Separator Spin-on (Open End for Bowl) (20514654).. BF1366-O
VN w/Cat 3306 (10.5L) Eng.	F-F Lube (4787362)..... [2] B76-SS +	P. Fuel (20430751)..... BF7814
Lube Ele. (5S0484)..... PT670	B-P Lube (477556-5)..... B7685	P. Fuel (22480372)..... BF46161
Lube Spin-on (1R0716)..... B99 +	P. Fuel (20430751)..... BF7814	Radial Seal O. Air (20411815)..... RS4642
Lube Spin-on (Standard Vers.) (1R0739)..... B76 +	P. Fuel (22480372)..... BF46161	Radial Seal I. Air (20411816)..... RS4643
Lube Spin-on (Severe Service) (1R0739)..... B76-SS +	Radial Seal O. Air (20411815)..... RS4642	Cab Air (20435801)..... PA4681
P. Fuel Ele. (9M2342)..... PF935	Radial Seal I. Air (20411816)..... RS4643	Air Dryer (Bendix 5008414)..... BA5374 +
	Cab Air (20435801)..... PA4681	Air Dryer (Wabco R950011)..... BA5374 +
	Coolant (3945411)..... BW5142	Coolant (w/8 Units BTE) (3945411)..... BW5142
		Opt. Trans. (Fuller 17237)..... B2 +
		Steering (349619)..... P106-HD

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).




VOLVO North America Trucks (cont'd)	VOLVO North America Trucks (cont'd)	VOLVO North America Trucks (cont'd)
VN Series w/Cummins ISX Eng.	VN430 w/VE D16 Eng.	VN670 w/VED12 Eng.
Dual-Flow Lube (Fleetguard LF9001)..... <b>BD7154 +</b>	F-F Lube (478736)..... <b>[2] B76-SS +</b>	F-F Lube (478736-2)..... <b>[2] B76-SS +</b>
Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>	B-P Lube (477556)..... <b>B7685</b>	B-P Lube (477556-5)..... <b>B7685</b>
Fuel/Water Separator Ele. (Davco 382119)..... <b>PF7782</b>	Fuel/Water Separator Ele. (85105574)..... <b>PF7680</b>	Fuel/Water Separator Ele..... <b>PF7755</b>
Fuel/Water Separator Ele..... <b>PF7755</b>	Fuel/Water Separator Spin-on (Open End for Bowl) (20514654).. <b>BF1366-O</b>	Fuel/Water Separator (Open End for Bowl) (Racor R90P)..... <b>BF46083-O</b>
Fuel/Water Separator Spin-on (Open End for Bowl) (Racor S3238P)..... <b>BF1355-O</b>	Fuel (20430751)..... <b>BF7814</b>	Fuel/Water Separator (w/Bowl) (Racor R90P)..... <b>BF46072</b>
Fuel/Water Separator Spin-on..... <b>BF1277-SP</b>	Fuel (22480372)..... <b>BF46161</b>	Fuel/Water Separator (w/Drain) (Racor R90P)..... <b>BF1329</b>
Fuel/Water Separator Spin-on (w/Drain) (Racor S3238P)..... <b>BF1355</b>	Radial Seal O. Air (20411815)..... <b>RS4642</b>	Fuel/Water Separator (Sensor Port Thd. 9/16-18) (Racor R90P).. <b>BF1329-SP</b>
Fuel/Water Separator Spin-on (w/Sensor Port) (Racor S3238P).. <b>BF1355-SP</b>	Radial Seal I. Air (20411816)..... <b>RS4643</b>	Fuel/Water Separator (Sensor Port Thd. 1/2-20) (Racor R90P).... <b>BF1339-SP +</b>
Fuel (Fleetguard FF2200)..... <b>BF7766</b>	Cab Air (20435801)..... <b>PA4681</b>	Fuel (20430751)..... <b>BF7814</b>
Radial Seal O. Air (8076195)..... <b>RS3740</b>	Coolant (w/o Chemical) (20458771)..... <b>B5145</b>	Fuel (22480372)..... <b>BF46161</b>
Radial Seal I. Air (8079756)..... <b>RS3741</b>	Coolant (w/8 Units BTE) (3945411)..... <b>BW5142</b>	Some Fuel (8193841)..... <b>BF7653</b>
Radial Seal O. Air (20411815)..... <b>RS4642</b>	Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	Radial Seal O. Air (20411815)..... <b>RS4642</b>
Radial Seal I. Air (20411816)..... <b>RS4643</b>	Steering (349619)..... <b>P106-HD</b>	Radial Seal I. Air (20411816)..... <b>RS4643</b>
Cab Air (20435801)..... <b>PA4681</b>	VN630 w/VE D12 Eng.	Cab Air (20435801)..... <b>[2] PA4681</b>
Air Dryer (Bendix 5008414)..... <b>BA5374 +</b>	F-F Lube (478736)..... <b>[2] B76-SS +</b>	Air Dryer (3915558)..... <b>BA5374 +</b>
Breather (1/07-on) (3683918)..... <b>CV15000</b>	B-P Lube (477556)..... <b>B7685</b>	Coolant (20458771)..... <b>B5145</b>
Coolant (Fleetguard WF2127)..... <b>B5087</b>	Fuel/Water Separator (Open End for Bowl) (Racor R90P)..... <b>BF46083-O</b>	Opt. Trans. (Fuller 17237)..... <b>B2 +</b>
Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	Fuel/Water Separator (w/Bowl) (Racor R90P)..... <b>BF46072</b>	Steering (349619)..... <b>P106-HD</b>
Steering (349619)..... <b>P106-HD</b>	Fuel/Water Separator (w/Drain) (Racor R90P)..... <b>BF1329</b>	VN670 w/Cummins ISX Eng.
VN430 w/Cummins ISX	Fuel/Water Separator (Sensor Port Thd. 9/16-18) (Racor R90P).. <b>BF1329-SP</b>	Dual-Flow Lube (Fleetguard LF9001)..... <b>BD7154 +</b>
Dual-Flow Lube (Fleetguard LF9001)..... <b>BD7154 +</b>	Fuel/Water Separator (Sensor Port Thd. 1/2-20) (Racor R90P).... <b>BF1339-SP +</b>	Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>
Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>	Fuel (20430751)..... <b>BF7814</b>	Fuel/Water Separator..... <b>PF7755</b>
Fuel (Fleetguard FF2200)..... <b>BF7766</b>	Fuel (22480372)..... <b>BF46161</b>	Fuel (Fleetguard FF2200)..... <b>BF7766</b>
Radial Seal O. Air (8076195)..... <b>RS3740</b>	Some Fuel (8193841)..... <b>BF7653</b>	Radial Seal O. Air (20411815)..... <b>RS4642</b>
Radial Seal I. Air (8079756)..... <b>RS3741</b>	Radial Seal O. Air (20411815)..... <b>RS4642</b>	Radial Seal I. Air (20411816)..... <b>RS4643</b>
Cab Air (20435801)..... <b>PA4681</b>	Radial Seal I. Air (20411816)..... <b>RS4643</b>	Cab Air (20435801)..... <b>[2] PA4681</b>
Breather (3683918)..... <b>CV15000</b>	Cab Air (20435801)..... <b>PA4681</b>	Air Dryer (3915558)..... <b>BA5374 +</b>
Coolant (3680434)..... <b>B5087</b>	Air Dryer (3915558)..... <b>BA5374 +</b>	Breather (1/07-on) (3683918)..... <b>CV15000</b>
Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	Coolant (20458771)..... <b>B5145</b>	Coolant (Fleetguard WF2127)..... <b>B5087</b>
Steering (349619)..... <b>P106-HD</b>	Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	Opt. Trans. (Fuller 17237)..... <b>B2 +</b>
VN430 w/VE D12 Eng.	Steering (349619)..... <b>P106-HD</b>	Steering (349619)..... <b>P106-HD</b>
F-F Lube (478736)..... <b>[2] B76-SS +</b>	VN630 w/Cummins ISX Eng.	VN730 w/Cummins ISX Eng.
B-P Lube (477556)..... <b>B7685</b>	Dual-Flow Lube (Fleetguard LF9001)..... <b>BD7154 +</b>	Dual-Flow Lube (Fleetguard LF9001)..... <b>BD7154 +</b>
Fuel/Water Separator Ele. (Davco 382119)..... <b>PF7782</b>	Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>	Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>
Fuel/Water Separator Spin-on (Open End for Bowl) (20514654).. <b>BF1366-O</b>	Fuel/Water Separator (Davco 382119)..... <b>PF7782</b>	Fuel/Water Separator (Open End for Bowl) (Racor S3238P)..... <b>BF1355-O</b>
Fuel (8193841)..... <b>BF7653</b>	Fuel (Fleetguard FF2200)..... <b>BF7766</b>	Fuel/Water Separator (w/Drain) (Racor S3238P)..... <b>BF1355</b>
Fuel (20430751)..... <b>BF7814</b>	Radial Seal O. Air (20411815)..... <b>RS4642</b>	Fuel/Water Separator (w/Sensor Port) (Racor S3238P)..... <b>BF1355-SP</b>
Fuel (22480372)..... <b>BF46161</b>	Radial Seal I. Air (20411816)..... <b>RS4643</b>	Fuel (Fleetguard FF2200)..... <b>BF7766</b>
Radial Seal O. Air (8076195)..... <b>RS3740</b>	Cab Air (20435801)..... <b>PA4681</b>	Radial Seal O. Air (20411815)..... <b>RS4642</b>
Radial Seal I. Air (8079756)..... <b>RS3741</b>	Air Dryer (3915558)..... <b>BA5374 +</b>	Radial Seal I. Air (20411816)..... <b>RS4643</b>
Cab Air (20435801)..... <b>PA4681</b>	Breather (1/07-on) (3683918)..... <b>CV15000</b>	Cab Air (20435801)..... <b>PA4681</b>
Coolant (w/8 Units BTE) (3945411)..... <b>BW5142</b>	Coolant (Fleetguard WF2127)..... <b>B5087</b>	Air Dryer (Wabco R950011)..... <b>BA5374 +</b>
Coolant (w/o Chemical) (20458771)..... <b>B5145</b>	Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	Breather (3683918)..... <b>CV15000</b>
Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	Steering (349619)..... <b>P106-HD</b>	Coolant (Fleetguard WF2127)..... <b>B5087</b>
Steering (349619)..... <b>P106-HD</b>		Opt. Trans. (Fuller 17237)..... <b>B2 +</b>
		Steering (349619)..... <b>P106-HD</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

VOLVO North America Trucks (cont'd)	VOLVO North America Trucks (cont'd)	VOLVO North America Trucks (cont'd)
VN730 w/VE D12 Eng. F-F Lube (478736)..... [2] B76-SS + B-P Lube (477556)..... B7685 Fuel/Water Separator (Davco 382119)..... PF7782 Fuel (20430751)..... BF7814 Fuel (22480372)..... BF46161 Some Fuel (8193841)..... BF7653 Radial Seal O. Air (20411815)..... RS4642 Radial Seal I. Air (20411816)..... RS4643 Cab Air (20435801)..... PA4681 Air Dryer (Wabco R950011)..... BA5374 + Coolant (20458771)..... B5145 Opt. Trans. (Fuller 17237)..... B2 + Steering (349619)..... P106-HD	VN780 w/VED12 Eng. (Cont'd) Fuel/Water Separator Ele. (Davco 382119)..... PF7782 Fuel/Water Separator (Open End for Bowl) (Racor R90P)..... BF46083-O Fuel/Water Separator (w/Bowl) (Racor R90P)..... BF46072 Fuel/Water Separator (w/Drain) (Racor R90P)..... BF1329 Fuel/Water Separator (Sensor Port Thd. 9/16-18) (Racor R90P).. BF1329-SP Fuel/Water Separator (Sensor Port Thd. 1/2-20) (Racor R90P).... BF1339-SP + Fuel (8193841)..... BF7653 Fuel (20430751)..... BF7814 Fuel (22480372)..... BF46161 Radial Seal O. Air (20411815)..... RS4642 Radial Seal I. Air (20411816)..... RS4643 Cab Air (20435801)..... PA4681 Air Dryer (3915558)..... BA5374 + Coolant (20458771)..... B5145 Opt. Trans. (Fuller 17237)..... B2 + Steering (349619)..... P106-HD	VNL w/Cat 3406 Eng. Lube (1R0716)..... B99 + Fuel/Water Separator (256-8753)..... BF1259 Fuel (4N5823)..... BF614 + VNL w/Cummins ISM 10.8 (10.8L) Eng. Dual-Flow Lube (Fleetguard LF9001)..... BD7154 + Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... BD50000 Dual-Flow Lube (Fleetguard LF9031)..... BD7509 + Dual-Flow Lube (Fleetguard LF9000)..... BD7153 + Trans. Spin-on (Fuller 4304827).. BT223 Opt. Trans. Spin-on (Fuller 17237)..... B2 + VNL w/Cummins ISX 11.9G (11.9L) Eng. (2013-18) Dual-Flow Lube (Fleetguard LF9080)..... BD7154 + Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... BD50000 Fuel/Water Separator (3607140). [2] BF7695 Radial Seal O. Air (21715813)..... RS4642 Radial Seal I. Air (20411816)..... RS4643 Cab Air (20435801)..... PA4681 Air Dryer (85110799)..... BA5592 90 Coolant (Fleetguard WF2127)..... B5087 Trans. Spin-on (Fuller 4304827).. BT223 Opt. Trans. Spin-on (Fuller 17237)..... B2 + Steering (349619)..... P106-HD Opt. Rear Axle (Meritor 3280V8394)..... B233 VNL w/Cummins ISX 11.9G (11.9L) Eng. (2019) Dual-Flow Lube (4367100)..... BD50000 Fuel/Water Separator (Fleetguard NG5900)..... BF7695 Fuel (2893612)..... BF9885 Radial Seal Air (21715813)..... RS4642 Cab Air (20435801)..... PA4681 Air Dryer (21620181)..... BA5379 Trans. Ele. (21479106)..... PT9417 Trans. Spin-on (Fuller 4304827).. BT223 Steering (349619)..... P106-HD Opt. Rear Axle (Meritor 3280V8394)..... B233 VNL w/Cummins ISX 11.9G (11.9L) Eng. (2020) Dual-Flow Lube (Fleetguard LF14000NN)..... BD50000 Fuel (Fleetguard NG5900)..... BF7695 Air (21715813)..... RS4642 Cab Air (20435801)..... PA4681 Air Dryer (21620181)..... BA5379 Trans. Spin-on (Fuller 4304827).. BT223 Steering (349619)..... P106-HD
VN730 w/VE D13 Eng. F-F Lube (4787362)..... [2] B76-SS + B-P Lube (477565)..... B7685 Fuel/Water Separator Ele. (Fleetguard FF5369)..... PF7744 Fuel/Water Separator Ele. (85105574)..... PF7680 Fuel/Water Separator Spin-on (Open End for Bowl) (20514654).. BF1366-O Fuel Spin-on (20405160)..... BF7814 Radial Seal O. Air (20411815)..... RS4642 Radial Seal I. Air (20411816)..... RS4643 Cab Air (20435801)..... PA4681 Air Dryer (Wabco R950011)..... BA5374 + Coolant (w/o Chemicals) (20458771)..... B5145 Coolant (w/Chemicals) (20458769)..... BW5142 Trans. Ele. (1521527)..... PT9417 Opt. Trans. Spin-on (Fuller 17237)..... B2 + Steering (349619)..... P106-HD	VN780 w/Cummins ISX Eng. Dual-Flow Lube (Fleetguard LF9001)..... BD7154 + Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... BD50000 Some Fuel/Water Separator (w/Drain) (85104856)..... BF1355 Some Fuel/Water Separator (w/Drain & Sensor Port) (85104856)..... BF1355-SP Some Fuel/Water Separator (Open End for Bowl) (85104856).. BF1355-O Fuel/Water Separator (Fleetguard FS1040)..... BF1277-SPS Fuel (Fleetguard FF2200)..... BF7766 Radial Seal O. Air (20411815)..... RS4642 Radial Seal I. Air (20411816)..... RS4643 Radial Seal Air (8076195)..... RS3740 Cab Air (20435801)..... PA4681 Air Dryer (3915558)..... BA5374 + Breather (1/07-on) (3683918)..... CV15000 Coolant (Fleetguard WF2127)..... B5087 Opt. Trans. (Fuller 17237)..... B2 + Steering (349619)..... P106-HD	VNL w/Cat 3306 (10.5L) Eng. Lube Ele. (5S0484)..... PT670 Lube Spin-on (1R0716)..... B99 + Lube Spin-on (Standard Vers.) (1R0739)..... B76 + Lube Spin-on (Severe Service) (1R0739)..... B76-SS + P. Fuel Ele. (9M2342)..... PF935 P. Fuel Spin-on (1R1740)..... BF970 + S. Fuel Spin-on (1R0750)..... BF7633 +
VN730 w/VE D16 Eng. F-F Lube (478736)..... [2] B76-SS + B-P Lube (477556)..... B7685 Fuel/Water Separator Ele. (Fleetguard FF5369)..... PF7744 Fuel/Water Separator (Open End for Bowl) (20514654)..... BF1366-O Fuel Spin-on (20430751)..... BF7814 Fuel Spin-on (22480372)..... BF46161 Radial Seal O. Air (20411815)..... RS4642 Radial Seal I. Air (20411816)..... RS4643 Cab Air (20435801)..... PA4681 Air Dryer (Wabco R950011)..... BA5374 + Coolant (w/8 Units BTE) (3945411)..... BW5142 Opt. Trans. (Fuller 17237)..... B2 + Steering (349619)..... P106-HD	VN780 w/VED12 Eng. F-F Lube..... [2] B76 + F-F Lube (478736-2)..... B76-SS + B-P Lube (477556-5)..... B7685	

+ See Product Guide for Variations of This Number. 90 Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).


<b>VOLVO</b>	<b>VOLVO</b>	<b>VOLVO</b>
<b>North America Trucks (cont'd)</b>	<b>North America Trucks (cont'd)</b>	<b>North America Trucks (cont'd)</b>
VNL w/Cummins ISX 11.9G (11.9L) Eng. (2020) (Cont'd) <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	VNL w/Cummins ISX 15.0 (14.9L) Eng. (2019) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (85120233)..... <b>PF7930</b> <b>Fuel/Water Separator</b> (Fleetguard FS19764G)..... <b>PF46091</b> <b>Fuel</b> (5365988)..... <b>BF46129 +</b> <b>Radial Seal Air</b> (21715813)..... <b>RS4642</b> <b>Cab Air</b> (20435801)..... <b>PA4681</b> <b>Air Dryer</b> (21620181)..... <b>BA5379 +</b> <b>Trans. Ele. (I-Shift)</b> (21479106).... <b>PT9417</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Steering</b> (349619)..... <b>P106-HD</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	VNL w/Cummins N14 Eng. (Cont'd) <b>Fuel/Water Separator</b> (w/Bowl) (Racor R90P)..... <b>BF46072</b> <b>Fuel/Water Separator</b> (w/Drain) (Racor R90P)..... <b>BF1329</b> <b>Fuel/Water Separator</b> (Sensor Port Thd. 9/16-18) (Racor R90P).. <b>BF1329-SP</b> <b>Fuel/Water Separator</b> (Sensor Port Thd. 1/2-20) (Racor R90P).... <b>BF1339-SP +</b> <b>Radial Seal Air</b> (8076195)..... <b>RS3740</b> <b>Cab Air</b> (11 13/32 In. Length) (8089705)..... <b>PA3986</b> <b>Cab Air</b> (13 7/16 In. Length) (3948712)..... <b>PA4682</b> <b>Air Dryer</b> (3915558)..... <b>BA5374 +</b> <b>Coolant</b> ..... <b>BW5071</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (349619)..... <b>P106-HD</b>
VNL w/Cummins ISX 11.9G (11.9L) Eng. (2021) <b>Lube</b> (5575298)..... <b>B40145</b> <b>Fuel</b> (3607140)..... <b>BF7695</b> <b>Radial Seal Air</b> (21715813)..... <b>RS4642</b> <b>Coolant</b> (3680434)..... <b>B5087</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	VNL Series w/Cummins ISX 15.0 (14.9L) Eng. (2020) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19764G)..... <b>PF46091</b> <b>Fuel/Water Separator Spin-on</b> (85121709)..... <b>BF46173-O</b> <b>Fuel</b> (5365988)..... <b>BF46129</b> <b>Radial Seal Air</b> (21715813)..... <b>RS4642</b> <b>Cab Air</b> (20435801)..... <b>PA4681</b> <b>Air Dryer</b> (21620181)..... <b>BA5379</b> <b>Coolant</b> (3680434)..... <b>B5087</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Steering</b> (349619)..... <b>P106-HD</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	VNL w/Cummins X15 (14.9L) Eng. (To 2018) <b>Dual-Flow Lube</b> (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (21737499)..... <b>PF7930</b> <b>Fuel</b> (Fleetguard FF5825NN)..... <b>BF46129 +</b> <b>Radial Seal Air</b> (21715813)..... <b>RS4642</b> <b>Cab Air</b> (20435801)..... <b>PA4681</b> <b>Air Dryer</b> (21620181)..... <b>BA5379 +</b> <b>Trans.</b> (21479106)..... <b>PT9417</b> <b>Steering</b> (85108880)..... <b>P528</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (4388378).. <b>PE17002 KIT</b>
VNL w/Cummins ISX 15.0 (14.9L) Eng. (2011) <b>Dual-Flow Lube</b> (3101869)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (Fleetguard FS19764)..... <b>PF9814</b> <b>Fuel</b> (4920586)..... <b>BF7766</b> <b>Radial Seal O. Air</b> (20411815)..... <b>RS4642</b> <b>Radial Seal I. Air</b> (20411816)..... <b>RS4643</b> <b>Cab Air</b> (20435801)..... <b>PA4681</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Crankcase Breather</b> (Fleetguard CV50607)..... <b>CV15000</b> <b>Coolant</b> (4907485)..... <b>BW5086</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (2880298).. <b>PE17000</b>	VNL w/Cummins ISX 15.0 (14.9L) Eng. (2021) <b>Lube</b> (5575298)..... <b>B40145</b> <b>Fuel/Water Separator</b> (Fleetguard FS19764G)..... <b>PF46091</b> <b>Fuel</b> (5365988)..... <b>BF46129</b> <b>Radial Seal Air</b> (21715813)..... <b>RS4642</b> <b>Cab Air</b> (20435801)..... <b>PA4681</b> <b>Air Dryer</b> (21620181)..... <b>BA5379</b> <b>Coolant</b> (3680434)..... <b>B5087</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Steering</b> (349619)..... <b>P106-HD</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	VNL w/Cummins X15 (14.9L) Eng. (2019) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (85120233)..... <b>PF7930</b> <b>Fuel/Water Separator</b> (Fleetguard FS19764G)..... <b>PF46091</b> <b>Fuel</b> (5365988)..... <b>BF46129 +</b> <b>Radial Seal Air</b> (21715813)..... <b>RS4642</b> <b>Cab Air</b> (20435801)..... <b>PA4681</b> <b>Air Dryer</b> (21620181)..... <b>BA5379 +</b> <b>Trans. Ele. (I-Shift)</b> (21479106).... <b>PT9417</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Steering</b> (P106-HD)..... <b>P106-HD</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
VNL w/Cummins ISX 15.0 (14.9L) Eng. (2013) <b>Dual-Flow Lube</b> (2882674)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (Fleetguard FS19764)..... <b>PF9814</b> <b>Fuel</b> (3685306)..... <b>BF9860</b> <b>Radial Seal O. Air</b> (20411815)..... <b>RS4642</b> <b>Radial Seal I. Air</b> (20411816)..... <b>RS4643</b> <b>Cab Air</b> (20435801)..... <b>PA4681</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Coolant</b> (4907485)..... <b>BW5086</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (2888182).. <b>PE17000</b>	VNL w/Cummins ISX 15.0 (14.9L) Eng. (2022) <b>Lube</b> (5575298)..... <b>B40145</b> <b>Fuel</b> (5575143)..... <b>BF46248</b> <b>Coolant</b> (3680434)..... <b>B5087</b>	VNL w/Cummins X15 (14.9L) Eng. (2020) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19764G)..... <b>PF46091</b> <b>Fuel/Water Separator Spin-on</b> (85121709)..... <b>BF46173-O</b> <b>Fuel</b> (5365988)..... <b>BF46129</b> <b>Radial Seal Air</b> (21715813)..... <b>RS4642</b> <b>Cab Air</b> (20435801)..... <b>PA4681</b> <b>Air Dryer</b> (21620181)..... <b>BA5379 +</b> <b>Trans. Ele. (I-Shift)</b> (21479106).... <b>PT9417</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Steering</b> (P106-HD)..... <b>P106-HD</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
VNL w/Cummins ISX 15.0 (14.9L) Eng. (2018) <b>Dual-Flow Lube</b> (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (21737499)..... <b>PF7930</b> <b>Fuel</b> (Fleetguard FF5825NN)..... <b>BF46129 +</b> <b>Radial Seal Air</b> (21715813)..... <b>RS4642</b> <b>Cab Air</b> (20435801)..... <b>PA4681</b> <b>Air Dryer</b> (21620181)..... <b>BA5379 +</b> <b>Trans.</b> (21479106)..... <b>PT9417</b> <b>Steering</b> (85108880)..... <b>P528</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (4388378).. <b>PE17002 KIT</b>	VNL w/Cummins ISX 15.0 (14.9L) Eng. (2023) <b>Lube</b> (5575298)..... <b>B40145</b> <b>Fuel</b> (5575143)..... <b>BF46248</b>	VNL Series w/Cummins X15 (14.9L) Eng. (2020) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19764G)..... <b>PF46091</b> <b>Fuel/Water Separator Spin-on</b> (85121709)..... <b>BF46173-O</b> <b>Fuel</b> (5365988)..... <b>BF46129</b> <b>Radial Seal Air</b> (21715813)..... <b>RS4642</b> <b>Cab Air</b> (20435801)..... <b>PA4681</b> <b>Air Dryer</b> (21620181)..... <b>BA5379</b> <b>Coolant</b> (3680434)..... <b>B5087</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b>
VNL w/Cummins M11 Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Fuel/Water Separator</b> (3329289)..... <b>BF1259</b> <b>Coolant</b> (Fleetguard WF2075)..... <b>BW5075</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	VNL w/Cummins N14 Eng. <b>Dual-Flow Lube</b> ..... <b>BD103 +</b> <b>Fuel/Water Separator</b> (Fleetguard FS1000)..... <b>BF1259</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R90P)..... <b>BF46083-O</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>VOLVO</b>	<b>VOLVO</b>	<b>VOLVO</b>
<b>North America Trucks (cont'd)</b>	<b>North America Trucks (cont'd)</b>	<b>North America Trucks (cont'd)</b>
VNL Series w/Cummins X15 (14.9L) Eng. (2020) (Cont'd)	VNL Series w/D11 (10.8L) Eng. (2020) (Cont'd)	VNL w/D13 (12.8L) Eng. (2007-18) (Cont'd)
Steering (349619)..... P106-HD	<b>Fuel/Water Separator (w/Drain)</b>	<b>Fuel/Water Separator Ele.</b>
Opt. Rear Axle (Meritor 3280V8394)..... B233	(3945966)..... BF1329	(Fleetguard FS19765)..... PF7930
VNL w/Detroit Series 60 Eng.	Fuel (22474709)..... BF46117	<b>Fuel/Water Separator Ele.</b>
Lube (23530407)..... [2] B95 +	Radial Seal Air (21715813)..... RS4642	(Davco 382119)..... PF7782
B-P Lube (23530413)..... B7577	Cab Air (20435801)..... PA4681	<b>Fuel/Water Separator Spin-on</b>
P. Fuel (23530706)..... BF5800 +	Air Dryer (21620181)..... BA5379	(Open End for Bowl) (20514654).. BF1366-O
S. Fuel (23530707)..... BF5810	Coolant (21937327)..... B5145	<b>Fuel/Water Separator Spin-on</b>
Opt. Trans. (Fuller 17237)..... B2 +	Trans. (21479106)..... PT9417	(21380475)..... BF1386-O
VNL w/D11 (10.8L) Eng. (2010-18)	Steering (349619)..... P106-HD	Fuel (20972293)..... BF7943
F-F Lube (4787362)..... [2] B76-SS +	Opt. Rear Axle (Meritor 3280V8394)..... B233	Fuel (20976003)..... BF7814
B-P Lube (477556-5)..... B7685	VNL w/D11 (10.8L) Eng. (2021)	Fuel (23044511)..... BF46233
<b>Fuel/Water Separator</b>	F-F Lube (21707133)..... [2] B76	Radial Seal O. Air (21715813)..... RS4642
(85105574)..... PF7680	B-P Lube (21707132)..... B7409	Opt. Radial Seal I. Air
Fuel (20430751)..... BF7814	Fuel (23856886)..... BF46117	(20411816)..... RS4643
Fuel (22480372)..... BF46161	Radial Seal Air (21715813)..... RS4642	Cab Air (20435801)..... PA4681
Fuel (20972293)..... BF7943	Coolant (21937327)..... B5145	Air Dryer (Wabco 3915558)..... BA5374 +
Radial Seal O. Air (20411815)..... RS4642	Opt. Rear Axle (Meritor 3280V8394)..... B233	Air Dryer (85110799)..... BA5592 <sup>90</sup>
Radial Seal I. Air (20411816)..... RS4643	VNL w/D12 (12.1L) Eng.	Air Dryer (SS1200 System)
Cab Air (20435801)..... PA4681	F-F Lube (478736)..... [2] B76-SS +	(Wabco R950068)..... BA5379 +
Air Dryer (Wabco 3915558)..... BA5374 +	B-P Lube..... B7685	Coolant (w/Chemical)
Coolant (3945411)..... BW5142	Dual-Flow Lube (Fleetguard LF9001)..... BD7154 +	(20458769)..... BW5142
Opt. Trans. (Fuller 17237)..... B2 +	Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... BD50000	Coolant (w/o Chemical)
Steering (349619)..... P106-HD	<b>Fuel/Water Separator Ele.</b>	(21937327)..... B5145
Opt. Rear Axle (Meritor 3280V8394)..... B233	(85105574)..... PF7680	Trans. Ele. (1521527)..... PT9417
VNL w/D11 (10.8L) Eng. (2019)	<b>Fuel/Water Separator Ele.</b>	Trans. Spin-on (Fuller 4304827).. BT223
F-F Lube (21707133)..... [2] B76 +	(Davco 382119)..... PF7782	Opt. Trans. Spin-on (Fuller 17237)..... B2 +
B-P Lube (21707132)..... B7409	<b>Fuel/Water Separator Ele.</b>	Steering (349619)..... P106-HD
Severe Service F-F Lube (21707133)..... [2] B76-SS +	(Fleetguard FF5369W)..... PF7744	Opt. Rear Axle (Meritor 3280V8394)..... B233
<b>Fuel/Water Separator</b>	<b>Fuel/Water Separator Spin-on</b> ..... BF1329	Diesel Exhaust Fluid (82269261) PE17001
(85120233)..... PF7930	<b>Fuel/Water Separator Spin-on</b>	Diesel Exhaust Fluid (21516229) PE17000
Fuel (22474709)..... BF46117	(Alliance ABPN122R50551)..... BF46016-O	VNL w/D13 (12.8L) Eng. (2019)
Radial Seal Air (21715813)..... RS4642	Fuel (20430751)..... BF7814	F-F Lube (21707133)..... [2] B76 +
Cab Air (20435801)..... PA4681	Fuel (22480372)..... BF46161	B-P Lube (21707132)..... B7409
Air Dryer (21620181)..... BA5379 +	Some Fuel..... BF7653	Severe Service F-F Lube (21707133)..... [2] B76-SS +
Coolant (21937327)..... B5145	Radial Seal O. Air (20882320)..... RS4642	<b>Fuel/Water Separator</b>
Trans. Ele. (21479106)..... PT9417	Opt. Radial Seal I. Air (20411816)..... RS4643	(85120233)..... PF7930
Steering (349619)..... P106-HD	Cab Air (20435801)..... PA4681	Fuel (22474709)..... BF46117
Opt. Rear Axle (Meritor 3280V8394)..... B233	Air Dryer (Wabco 3915558)..... BA5374 +	Radial Seal Air (21715813)..... RS4642
Diesel Exhaust Fluid (21516229) PE17000	Coolant (w/o Chemical) (20458771)..... B5145	Cab Air (20435801)..... PA4681
VNL Series w/D11 (10.8L) Eng. (2020)	Coolant (w/Chemical) (20458769)..... BW5142	Air Dryer (21620181)..... BA5379 +
F-F Lube (21707133)..... [2] B76	Trans. Ele. (1521527)..... PT9417	Coolant (21937327)..... B5145
B-P Lube (21707132)..... B7409	Opt. Trans. (Fuller 17237)..... B2 +	Trans. Ele. (I-Shift) (21479106).... PT9417
Severe Service F-F Lube (21707133)..... [2] B76-SS +	Steering (349619)..... P106-HD	Trans. Spin-on (Fuller 4304827).. BT223
<b>Fuel/Water Separator</b> (Open End for Bowl) (3945966)..... BF46083-O	VNL w/D13 (12.8L) Eng. (2007-18)	Steering (349619)..... P106-HD
<b>Fuel/Water Separator</b> (w/Bowl) (3945966)..... BF46072	F-F Lube (21707133)..... [2] B76 +	Opt. Rear Axle (Meritor 3280V8394)..... B233
<b>Fuel/Water Separator</b> (SP Thd. 1/2-20) (3945966)..... BF1339-SP	F-F Lube (Severe Service) (4787362)..... [2] B76-SS +	Diesel Exhaust Fluid (21516229) PE17000
<b>Fuel/Water Separator</b> (SP Thd. 9/16-18) (3945966)..... BF1329-SP	B-P Lube (477556-5)..... B7685	VNL w/D13 (12.8L) Eng. (2020)
	B-P Lube (21707132)..... B7409	F-F Lube (21707133)..... [2] B76
	<b>Fuel/Water Separator Ele.</b> (Fleetguard FF5369)..... PF7744	B-P Lube (21707132)..... B7409
		<b>Fuel/Water Separator</b>
		(Fleetguard FS19764G)..... PF46091
		Fuel (22474709)..... BF46117
		Radial Seal Air (21715813)..... RS4642
		Cab Air (20435801)..... PA4681

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

VOLVO North America Trucks (cont'd)	VOLVO North America Trucks (cont'd)	VOLVO North America Trucks (cont'd)
VNL w/D13 (12.8L) Eng. (2020) (Cont'd)	VNL w/Cummins ISX Eng.	VNL300 w/Cummins ISX Eng. (2007 Emissions)
Air Dryer (21620181)..... BA5379	Dual-Flow Lube (3101869)..... BD7154 +	Dual-Flow Lube (3101869)..... BD7154 +
Coolant (21937327)..... B5145	Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... BD50000	Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... BD50000
Trans. Spin-on (Fuller 4304827).. BT223	Fuel/Water Separator (Davco 382119)..... PF7782	Fuel/Water Separator Ele. (85105574)..... PF7680
Opt. Trans. Spin-on (Fuller 17237)..... B2	Fuel (Fleetguard FF2200)..... BF7766	Fuel/Water Separator Ele. (Fleetguard FS19727)..... PF7895
Steering (349619)..... P106-HD	Fuel (Fleetguard FF2203)..... BF7760	Fuel/Water Separator Ele. (Fleetguard FS19729)..... PF7755
Opt. Rear Axle (Meritor 3280V8394)..... B233	Radial Seal O. Air (20411815).... RS4642	Fuel/Water Separator Ele. (Davco 382119)..... PF7782
Diesel Exhaust Fluid (23381562) PE17000	Radial Seal I. Air (20411816).... RS4643	Fuel/Water Separator Spin-on (Open End for Bowl) (Racor S3238P)..... BF1355-O
VNL w/D13 (12.8L) Eng. (2021)	Radial Seal O. Air..... RS3740	Fuel/Water Separator Spin-on (w/Drain) (Racor S3238P)..... BF1355
F-F Lube (21707133)..... [2] B76	Radial Seal I. Air..... RS3741	Fuel/Water Separator Spin-on (w/Sensor Port) (Racor S3238P).. BF1355-SP
B-P Lube (21707132)..... B7409	Cab Air (20435801)..... PA4681	Fuel/Water Separator (85121709)..... BF46173-O
F-F Lube (23151592)..... [2] B40153	Air Dryer (3915558)..... BA5374 +	Fuel (4088272)..... BF7766
Fuel/Water Separator (Fleetguard FS19764G)..... PF46091	Breather (1/07-on) (3683918).... CV15000	Radial Seal O. Air (20411815).... RS4642
Fuel (23856886)..... BF46117	Coolant (w/o Chemical) (Fleetguard WF2127)..... B5087	Radial Seal I. Air (20411816).... RS4643
Radial Seal Air (21715813)..... RS4642	Coolant (w/Chemical) (Fleetguard WF2126)..... BW5086	Cab Air (20435801)..... PA4681
Opt. Rear Axle (Meritor 3280V8394)..... B233	Opt. Trans. (Fuller 17237)..... B2 +	Air Dryer (Wabco 3915558)..... BA5374 +
VNL w/D13TC (12.8L) Eng. (2021)	Steering (349619)..... P106-HD	Air Dryer (SS1200 System) (Wabco R950068)..... BA5379 +
F-F Lube (21707133)..... [2] B76	VNL64T w/Cat 3406 Eng.	Air Dryer (85110799)..... BA5592 <sup>90</sup>
B-P Lube (21707132)..... B7409	Lube (1R0716)..... B99 +	Breather (CV50617)..... CV15000
Radial Seal Air (21715813)..... RS4642	Fuel/Water Separator (256-8753)..... BF1259	Coolant (w/11 1/2 Units BTA+) (Fleetguard WF2126)..... BW5086
Opt. Rear Axle (Meritor 3280V8394)..... B233	Fuel (4N5823)..... BF614 +	Coolant (w/o Chemical) (Fleetguard WF2127)..... B5087
VNL Series w/D16 (16.1L) Eng. (06-17)	VNL64T w/Cummins ISX Eng.	Opt. Trans. Spin-on (Fuller 17237)..... B2 +
F-F Lube (478736)..... [2] B76-SS +	Dual-Flow Lube (Fleetguard LF9001)..... BD7154 +	Steering (349619)..... P106-HD
B-P Lube (477556)..... B7685	Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... BD50000	Diesel Exhaust Fluid (82269261) PE17001
Fuel/Water Separator Ele. (85105574)..... PF7680	Fuel/Water Separator Ele. (Davco) (Fleetguard FF5369)..... PF7744	VNL300 w/Cummins ISX Eng. (2010 Emissions)
Fuel/Water Separator Spin-on (Open End for Bowl) (20514654).. BF1366-O	Fuel/Water Separator Ele. (Davco) (Fleetguard FS19729).... PF7755	Dual-Flow Lube (3101869)..... BD7154 +
Fuel (20430751)..... BF7814	Fuel (Fleetguard FF2200)..... BF7766	Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... BD50000
Fuel (22480372)..... BF46161	Radial Seal O. Air (20411815).... RS4642	Fuel/Water Separator Ele. (85105574)..... PF7680
Radial Seal O. Air (20411815).... RS4642	Radial Seal I. Air (20411816).... RS4643	Fuel/Water Separator Ele. (Fleetguard FS19727)..... PF7895
Radial Seal I. Air (20411816).... RS4643	Radial Seal I. Air (20411816).... RS4643	Fuel/Water Separator Ele. (Fleetguard FS19729)..... PF7755
Cab Air (20435801)..... PA4681	VNL64T w/Cummins M11 Eng.	Fuel/Water Separator Ele. (Davco 382119)..... PF7782
Air Dryer (Wabco 3915558)..... BA5374 +	Dual-Flow Lube (3318853)..... BD103 +	Fuel/Water Separator Spin-on (Open End for Bowl) (Racor S3238P)..... BF1355-O
Coolant (w/o Chemical) (20458771)..... B5145	Fuel/Water Separator (3329289) BF1259	Fuel/Water Separator Spin-on (w/Drain) (Racor S3238P)..... BF1355
Coolant (w/8 Units BTE) (3945411)..... BW5142	Coolant (Fleetguard WF2075).... BW5075	Fuel/Water Separator Spin-on (w/Sensor Port) (Racor S3238P).. BF1355-SP
Steering (349619)..... P106-HD	Opt. Trans. (Fuller 17237)..... B2 +	Fuel/Water Separator (85121709)..... BF46173-O
VNL Series w/D16 (16.1L) Eng. (2020)	VNL64T w/Cummins N14 Eng.	
F-F Lube (4787362)..... [2] B76-SS	F-F Lube (Fleetguard LF670SC).. B196 +	
Fuel/Water Separator Ele. (85105574)..... PF7680	B-P Lube (3304232)..... B7577	
Fuel/Water Separator Spin-on (20879806)..... BF1386-O	Dual-Flow Lube (3318853)..... BD103 +	
Fuel (20972293)..... BF7943	Fuel (154789)..... BF957-D +	
Radial Seal Air (21715813)..... RS4642	Coolant..... BW5071	
Cab Air (20435801)..... PA4681	Opt. Trans. (Fuller 17237)..... B2 +	
Air Dryer (21620181)..... BA5379	VNL64T w/Detroit Series 60 Eng.	
Trans. (Fuller 4304827)..... BT223	Lube (23530407)..... [2] B95 +	
Opt. Trans. (Fuller 17237)..... B2	B-P Lube (23530413)..... B7577	
Steering (349619)..... P106-HD	P. Fuel (23530706)..... BF5800 +	
Opt. Rear Axle (Meritor 3280V8394)..... B233	S. Fuel (23530707)..... BF5810	
	Opt. Trans. (Fuller 17237)..... B2 +	

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.


Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>VOLVO</b> North America Trucks (cont'd)	<b>VOLVO</b> North America Trucks (cont'd)	<b>VOLVO</b> North America Trucks (cont'd)
VNL300 w/Cummins ISX Eng. (2010 Emissions) (Cont'd)	VNL300 w/Cummins X15 (14.9L) Eng. (2020) (Cont'd)	VNL300 w/D11 (10.8L) Eng. (2020) (Cont'd)
Fuel (2007 Emissions) (4088272) BF7766	Radial Seal Air (21715813)..... RS4642	Fuel/Water Separator (w/Drain) (3945966)..... BF1329
Fuel (2010 Emissions) (Fleetguard FF5686)..... BF9860 +	Cab Air (20435801)..... PA4681	Fuel (22474709)..... BF46117
Radial Seal O. Air (20411815)..... RS4642	Air Dryer (21620181)..... BA5379	Radial Seal Air (21715813)..... RS4642
Radial Seal I. Air (20411816)..... RS4643	Coolant (3680434)..... B5087	Cab Air (20435801)..... PA4681
Cab Air (20435801)..... PA4681	Trans. (Fuller 4304827)..... BT223	Air Dryer (21620181)..... BA5379
Air Dryer (Wabco 3915558)..... BA5374 +	Steering (349619)..... P106-HD	Coolant (21937327)..... B5145
Air Dryer (SS1200 System) (Wabco R950068)..... BA5379 +	Opt. Rear Axle (Meritor 3280V8394)..... B233	Steering (349619)..... P106-HD
Air Dryer (85110799)..... BA5592 90	VNL300 w/VE D11 Eng.	Opt. Rear Axle (Meritor 3280V8394)..... B233
Breather (3683918)..... CV15000	F-F Lube (4787362)..... [2] B76-SS +	VNL300 w/VE D12 Eng.
Coolant (w/11 1/2 Units BTA+) (Fleetguard WF2126)..... BW5086	B-P Lube (477556-5)..... B7685	F-F Lube (478736)..... [2] B76-SS +
Coolant (w/o Chemical) (Fleetguard WF2127)..... B5087	Fuel/Water Separator Ele. (85105574)..... PF7680	B-P Lube..... B7685
Opt. Trans. Spin-on (Fuller 17237)..... B2 +	Fuel/Water Separator (Open End for Bowl) (Racor R90P)..... BF46083-O	Dual-Flow Lube (Fleetguard LF9001)..... BD7154 +
Steering (349619)..... P106-HD	Fuel/Water Separator (w/Bowl) (Racor R90P)..... BF46072	Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... BD50000
Diesel Exhaust Fluid (82269261) PE17001	Fuel/Water Separator (w/Drain) (Racor R90P)..... BF1329	Fuel/Water Separator Ele. (85105574)..... PF7680
VNL300 w/Cummins ISX-G Eng.	Fuel/Water Separator (Sensor Port Thd. 9/16-18) (Racor R90P)..... BF1329-SP	Fuel/Water Separator Ele. (Davco 382119)..... PF7782
Dual-Flow Lube (Fleetguard LF9080)..... BD7154 +	Fuel/Water Separator (Sensor Port Thd. 1/2-20) (Racor R90P)..... BF1339-SP +	Fuel/Water Separator Ele. (Fleetguard FF5369W)..... PF7744
Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... BD50000	Fuel/Water Separator Spin-on (Open End for Bowl) (20514654)..... BF1366-O	Fuel/Water Separator Spin-on (Alliance ABPN122R50551)..... BF46016-O
Fuel/Water Separator (3607140) [2] BF7695	Fuel/Water Separator Spin-on (20853583)..... BF1388-O	Fuel (20430751)..... BF7814
Radial Seal O. Air (21715813)..... RS4642	Fuel (20430751)..... BF7814	Fuel (22480372)..... BF46161
Radial Seal I. Air (20411816)..... RS4643	Fuel (22480372)..... BF46161	S. Fuel (20972293)..... BF7943
Cab Air (20435801)..... PA4681	Radial Seal O. Air (20411815)..... RS4642	Radial Seal O. Air (20411815)..... RS4642
Air Dryer (85110799)..... BA5592 90	Radial Seal I. Air (20411816)..... RS4643	Cab Air (20435801)..... PA4681
Coolant (Fleetguard WF2127)..... B5087	Cab Air (20435801)..... PA4681	Air Dryer (Wabco 3915558)..... BA5374 +
Trans. Spin-on (Fuller 4304827)..... BT223	Air Dryer (To 11/10/08) (Wabco 3915558)..... BA5374 +	Coolant (w/o Chemical) (20458771)..... B5145
Opt. Trans. Spin-on (Fuller 17237)..... B2 +	Air Dryer (11/11/08-on) (85110799)..... BA5592 90	Coolant (w/Chemical) (20458769)..... BW5142
Steering (349619)..... P106-HD	Coolant (w/o Chemical) (20458771)..... B5145	Trans. Ele. (1521527)..... PT9417
VNL300 w/Cummins ISX 15.0 (14.9L) Eng. (2020)	Coolant (w/Chemical) (3945411)..... BW5142	Opt. Trans. (Fuller 17237)..... B2 +
Dual-Flow Lube (4367100)..... BD50000	Trans. Ele. (1521527)..... PT9417	Steering (349619)..... P106-HD
Fuel/Water Separator Ele. (Fleetguard FS19764G)..... PF46091	Opt. Trans. (Fuller 17237)..... B2 +	Diesel Exhaust Fluid (21516229) PE17000
Fuel/Water Separator Spin-on (85121709)..... BF46173-O	Steering (349619)..... P106-HD	VNL300 w/D11 (10.8L) Eng. (2020)
Fuel (5365988)..... BF46129	Diesel Exhaust Fluid (21516229) PE17000	F-F Lube (21707133)..... [2] B76
Radial Seal Air (21715813)..... RS4642	VNL300 w/D13 (12.8L) Eng. (2007-16)	B-P Lube (21707132)..... B7409
Cab Air (20435801)..... PA4681	F-F Lube (Severe Service) (4787362)..... [2] B76-SS +	Fuel/Water Separator Ele. (Fleetguard FF5369)..... PF7744
Air Dryer (21620181)..... BA5379	B-P Lube (477556-5)..... B7685	Fuel/Water Separator Ele. (Fleetguard FS19765)..... PF7930
Coolant (3680434)..... B5087	B-P Lube (21707132)..... B7409	Fuel/Water Separator Ele. (Davco 382119)..... PF7782
Trans. (Fuller 4304827)..... BT223	Fuel/Water Separator Ele. (21707133)..... [2] B76-SS +	Fuel/Water Separator Spin-on (Open End for Bowl) (20514654)..... BF1366-O
Steering (349619)..... P106-HD	Fuel/Water Separator (Open End for Bowl) (3945966)..... BF46083-O	Fuel/Water Separator Spin-on (21380475)..... BF1386-O
Opt. Rear Axle (Meritor 3280V8394)..... B233	Fuel/Water Separator (w/Bowl) (3945966)..... BF46072	Fuel (20972293)..... BF7943
VNL300 w/Cummins X15 (14.9L) Eng. (2020)	Fuel/Water Separator (SP Thd. 1/2-20) (3945966)..... BF1339-SP	
Dual-Flow Lube (4367100)..... BD50000	Fuel/Water Separator (SP Thd. 9/16-18) (3945966)..... BF1329-SP	
Fuel/Water Separator Ele. (Fleetguard FS19764G)..... PF46091		
Fuel/Water Separator Spin-on (85121709)..... BF46173-O		
Fuel (5365988)..... BF46129		

+ See Product Guide for Variations of This Number. 90 Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).


VOLVO North America Trucks (cont'd)	VOLVO North America Trucks (cont'd)	VOLVO North America Trucks (cont'd)
VNL300 w/D13 (12.8L) Eng. (2007-16) (Cont'd)	VNL300 w/D13 (12.8L) Eng. (2020)	VNL300 w/E D16 Eng. (Cont'd)
Fuel (20976003)..... <b>BF7814</b>	F-F Lube (21707133)..... <b>[2] B76 +</b>	Coolant (21388476)..... <b>BW5142</b>
Fuel (23044511)..... <b>BF46233</b>	B-P Lube (21707132)..... <b>B7409</b>	Trans. Ele. (1521527)..... <b>PT9417</b>
Radial Seal O. Air (21715813)..... <b>RS4642</b>	Fuel/Water Separator	Trans. Spin-on (Fuller 4304827).. <b>BT223</b>
Opt. Radial Seal I. Air	(Fleetguard FS19764G)..... <b>PF46091</b>	Opt. Trans. Spin-on (Fuller
(20411816)..... <b>RS4643</b>	Fuel (22474709)..... <b>BF46117</b>	17237)..... <b>B2 +</b>
Cab Air (20435801)..... <b>PA4681</b>	Radial Seal Air (21715813)..... <b>RS4642</b>	Steering (349619)..... <b>P106-HD</b>
Air Dryer (Wabco 3915558)..... <b>BA5374 +</b>	Cab Air (20435801)..... <b>PA4681</b>	Diesel Exhaust Fluid (2010
Air Dryer (85110799)..... <b>BA5592 90</b>	Air Dryer (21620181)..... <b>BA5379</b>	Emissions) (21516229)..... <b>PE17000</b>
Air Dryer (SS1200 System)	Coolant (21937327)..... <b>B5145</b>	Diesel Exhaust Fluid (2010
(Wabco R950068)..... <b>BA5379 +</b>	Opt. Trans. Spin-on (Fuller	Emissions) (82269261)..... <b>PE17001</b>
Coolant (w/Chemical)	17237)..... <b>B2</b>	
(20458769)..... <b>BW5142</b>	Trans. Spin-on (Fuller 4304827).. <b>BT223</b>	VNL400 w/D13 (12.8L) Eng.
Coolant (w/o Chemical)	Steering (349619)..... <b>P106-HD</b>	F-F Lube (21707133)..... <b>[2] B76 +</b>
(21937327)..... <b>B5145</b>	Opt. Rear Axle (Meritor	B-P Lube (21707132)..... <b>B7409</b>
Trans. Ele. (1521527)..... <b>PT9417</b>	3280V8394)..... <b>B233</b>	Severe Service F-F Lube
Trans. Spin-on (Fuller 4304827).. <b>BT223</b>	Diesel Exhaust Fluid (21516229) <b>PE17000</b>	(21707133)..... <b>[2] B76-SS +</b>
Opt. Trans. Spin-on (Fuller		Fuel/Water Separator
17237)..... <b>B2 +</b>	VNL300 w/D13-LNG Eng.	(21737499)..... <b>PF7930</b>
Steering (349619)..... <b>P106-HD</b>	Radial Seal O. Air (21715813)..... <b>RS4642</b>	Fuel (22474709)..... <b>BF46117</b>
Diesel Exhaust Fluid (82269261) <b>PE17001</b>	Radial Seal I. Air (20411816)..... <b>RS4643</b>	Radial Seal Air (21715813)..... <b>RS4642</b>
Diesel Exhaust Fluid (21516229) <b>PE17000</b>	Cab Air (20435801)..... <b>PA4681</b>	Cab Air (20435801)..... <b>PA4681</b>
	Air Dryer (85110799)..... <b>BA5592 90</b>	Air Dryer (21620181)..... <b>BA5379 +</b>
VNL300 w/D13 (GHG2017) (12.8L) Eng. (2017)	Coolant (21937327)..... <b>B5145</b>	Coolant (21937327)..... <b>B5145</b>
F-F Lube (21707133)..... <b>[2] B76 +</b>	Trans. Ele. (1521527)..... <b>PT9417</b>	Trans. (21479106)..... <b>PT9417</b>
B-P Lube (21707132)..... <b>B7409</b>	Trans. Spin-on (Fuller 4304827).. <b>BT223</b>	Steering (349619)..... <b>P106-HD</b>
Severe Service F-F Lube	Opt. Trans. Spin-on (Fuller	Opt. Rear Axle (Meritor
(21707133)..... <b>[2] B76-SS +</b>	17237)..... <b>B2 +</b>	3280V8394)..... <b>B233</b>
Fuel/Water Separator	Steering (349619)..... <b>P106-HD</b>	Diesel Exhaust Fluid (Filler Neck)
(21737499)..... <b>PF7930</b>		(82269261)..... <b>PE17001</b>
Fuel (22474709)..... <b>BF46117</b>	VNL300 w/E D16 Eng.	Diesel Exhaust Fluid (Tank)
Radial Seal Air (21715813)..... <b>RS4642</b>	F-F Lube (478736-2)..... <b>[2] B76-SS +</b>	(21516229)..... <b>PE17000</b>
Cab Air (20435801)..... <b>PA4681</b>	F-F Lube (21707133)..... <b>[2] B76 +</b>	
Air Dryer (21620181)..... <b>BA5379 +</b>	B-P Lube (477556-5)..... <b>B7685</b>	VNL430 w/Cummins ISX Eng.
Coolant (21937327)..... <b>B5145</b>	B-P Lube (21707132)..... <b>B7409</b>	Dual-Flow Lube (3101869)..... <b>BD7154 +</b>
Trans. (21479106)..... <b>PT9417</b>	Fuel/Water Separator Ele.	Dual-Flow Lube (Upgrade)
Steering (349619)..... <b>P106-HD</b>	(85105574)..... <b>PF7680</b>	(Fleetguard LF14000NN)..... <b>BD50000</b>
Diesel Exhaust Fluid (Filler Neck)	Fuel/Water Separator Ele.	Fuel/Water Separator Ele.
(82269261)..... <b>PE17001</b>	(Fleetguard FF5369W)..... <b>PF7744</b>	(Fleetguard FS19765)..... <b>PF7930</b>
Diesel Exhaust Fluid (Tank)	Fuel/Water Separator Ele.	Fuel/Water Separator Spin-on
(21516229)..... <b>PE17000</b>	(Davco 382119)..... <b>PF7782</b>	(Open End for Bowl) (Racor
	Fuel/Water Separator Ele.	S3238P)..... <b>BF1355-O</b>
VNL300 w/D13 (12.8L) Eng. (2019)	(21737499)..... <b>PF7930</b>	Fuel/Water Separator Spin-on
F-F Lube (21707133)..... <b>[2] B76 +</b>	Fuel/Water Separator Spin-on	(w/Drain) (Racor S3238P)..... <b>BF1355</b>
B-P Lube (21707132)..... <b>B7409</b>	(Open End for Bowl) (20514654).. <b>BF1366-O</b>	Fuel/Water Separator Spin-on
Severe Service F-F Lube	Fuel (20430751)..... <b>BF7814</b>	(w/Sensor Port) (Racor S3238P).. <b>BF1355-SP</b>
(21707133)..... <b>[2] B76-SS +</b>	Fuel (22480372)..... <b>BF46161</b>	Fuel/Water Separator
Fuel/Water Separator	Fuel (20972293)..... <b>BF7943</b>	(85121709)..... <b>BF46173-O</b>
(85120233)..... <b>PF7930</b>	Radial Seal O. Air (20411815)..... <b>RS4642</b>	Fuel (4088272)..... <b>BF7766</b>
Fuel (22474709)..... <b>BF46117</b>	Radial Seal I. Air (20411816)..... <b>RS4643</b>	Radial Seal O. Air (8076195)..... <b>RS3740</b>
Radial Seal Air (21715813)..... <b>RS4642</b>	Cab Air (20435801)..... <b>PA4681</b>	Radial Seal I. Air (8079756)..... <b>RS3741</b>
Cab Air (20435801)..... <b>PA4681</b>	Air Dryer (To 11/10/08) (Wabco	Cab Air (20435801)..... <b>[2] PA4681</b>
Air Dryer (21620181)..... <b>BA5379 +</b>	3915558)..... <b>BA5374 +</b>	Air Dryer (Bendix 5008414)..... <b>BA5374 +</b>
Coolant (21937327)..... <b>B5145</b>	Air Dryer (11/11/08-on)	Breather (3683918)..... <b>CV15000</b>
Trans. Ele. (I-Shift) (21479106).... <b>PT9417</b>	(85110799)..... <b>BA5592 90</b>	Coolant (Fleetguard WF2127)..... <b>B5087</b>
Trans. Spin-on (Fuller 4304827).. <b>BT223</b>	Air Dryer (SS1200 System)	Opt. Trans. (Fuller 17237)..... <b>B2 +</b>
Steering (349619)..... <b>P106-HD</b>	(Wabco R950068)..... <b>BA5379 +</b>	Steering (349619)..... <b>P106-HD</b>
Opt. Rear Axle (Meritor	Air Dryer (AD-9 System) (Bendix	
3280V8394)..... <b>B233</b>	107796)..... <b>BA5377</b>	
Diesel Exhaust Fluid (21516229) <b>PE17000</b>	Coolant (w/o Chemical)	
	(20458771)..... <b>B5145</b>	

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

VOLVO North America Trucks (cont'd)	VOLVO North America Trucks (cont'd)	VOLVO North America Trucks (cont'd)
VNL430 w/VE D11 Eng. F-F Lube (478736-2)..... [2] B76-SS + B-P Lube (477556-5)..... B7685 Fuel/Water Separator (Open End for Bowl) (20514654)..... BF1366-O Fuel (20430751)..... BF7814 Fuel (22480372)..... BF46161 Radial Seal Air (20882320)..... RS4642 Cab Air (20435801)..... PA4681 Air Dryer (Bendix 5008414)..... BA5374 + Coolant (21388476)..... BW5142 Trans. Ele. (1521527)..... PT9417 Opt. Trans. (Fuller 17237)..... B2 + Steering (349619)..... P106-HD Diesel Exhaust Fluid (82269261) PE17001	VNL430 w/VE D13 Eng. (Cont'd) Fuel/Water Separator Spin-on (w/Bowl) (3945966)..... BF46072 Fuel/Water Separator Spin-on (Open End for Bowl) (3945966).... BF46083-O Fuel/Water Separator Spin-on (w/9/16-18 SP Thd.) (3945966).... BF1329-SP Fuel/Water Separator Spin-on (w/1/2-20 SP Thd.) (3945966)..... BF1339-SP + Fuel/Water Separator Spin-on (Open End for Bowl) (20514654).. BF1366-O Fuel/Water Separator Spin-on (21380475)..... BF1386-O Fuel (20972293)..... BF7943 Fuel (20430751)..... BF7814 Fuel (22480372)..... BF46161 Fuel (23044511)..... BF46233 Radial Seal Air (21715813)..... RS4642 Cab Air (20435801)..... PA4681 Air Dryer (Wabco 3915558)..... BA5374 + Air Dryer (85110799)..... BA5592 90 Coolant (w/8 Units BTE) (3945411)..... BW5142 Coolant (w/o Chemical) (21937327)..... B5145 Trans. Ele. (1521527)..... PT9417 Trans. Spin-on (Fuller 4304827).. BT223 Opt. Trans. Spin-on (Fuller 17237)..... B2 + Steering (349619)..... P106-HD Diesel Exhaust Fluid (82269261) PE17001 Diesel Exhaust Fluid (21516229) PE17000	VNL610 w/Cummins ISX Eng. (Cont'd) Radial Seal Air (8076195)..... RS3740 Cab Air (11 13/32 In. Length) (8089705)..... PA3986 Cab Air (13 7/16 In. Length) (3948712)..... PA4682 Air Dryer (3915558)..... BA5374 + Coolant (Fleetguard WF2125)..... BW5086 Steering (349619)..... P106-HD VNL610 w/Cummins N14 Eng. Dual-Flow Lube..... BD103 + Fuel/Water Separator (Fleetguard FS1000)..... BF1259 Fuel/Water Separator (Open End for Bowl) (Racor R90P)..... BF46083-O Fuel/Water Separator (w/Bowl) (Racor R90P)..... BF46072 Fuel/Water Separator (w/Drain) (Racor R90P)..... BF1329 Fuel/Water Separator (Sensor Port Thd. 9/16-18) (Racor R90P).. BF1329-SP Fuel/Water Separator (Sensor Port Thd. 1/2-20) (Racor R90P).... BF1339-SP + Radial Seal Air (8076195)..... RS3740 Cab Air (11 13/32 In. Length) (8089705)..... PA3986 Cab Air (13 7/16 In. Length) (3948712)..... PA4682 Air Dryer (3915558)..... BA5374 + Coolant..... BW5071 Opt. Trans. (Fuller 17237)..... B2 + Steering (349619)..... P106-HD VNL610 w/VED12 Eng. F-F Lube (478736)..... [2] B76-SS + B-P Lube (477556)..... B7685 Fuel/Water Separator Ele. (85105574)..... PF7680 Fuel/Water Separator (Open End for Bowl) (Racor R90P)..... BF46083-O Fuel/Water Separator (w/Bowl) (Racor R90P)..... BF46072 Fuel/Water Separator (w/Drain) (Racor R90P)..... BF1329 Fuel/Water Separator (Sensor Port Thd. 9/16-18) (Racor R90P).. BF1329-SP Fuel/Water Separator (Sensor Port Thd. 1/2-20) (Racor R90P).... BF1339-SP + Fuel (8193841)..... BF7653 Fuel (20430751)..... BF7814 Fuel (22480372)..... BF46161 Radial Seal O. Air (20411815).... RS4642 Radial Seal I. Air (20411816)..... RS4643 Air Dryer (3915558)..... BA5374 + Steering (349619)..... P106-HD VNL630 w/Cummins ISX Eng. Dual-Flow Lube (3101869)..... BD7154 + Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... BD50000 Fuel/Water Separator (Fleetguard FS1040)..... BF1277-SPS
VNL430 w/VE D12 Eng. F-F Lube (478736)..... [2] B76-SS + B-P Lube (477556)..... B7685 Dual-Flow Lube (Fleetguard LF9001)..... BD7154 + Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... BD50000 Fuel/Water Separator Ele. (Davco 382119)..... PF7782 Fuel/Water Separator Spin-on (Open End for Bowl) (20514654).. BF1366-O Fuel (20430751)..... BF7814 Fuel (22480372)..... BF46161 Some Fuel (8193841)..... BF7653 Radial Seal O. Air (8076195)..... RS3740 Radial Seal I. Air (8079756)..... RS3741 Single Radial Seal Air (20882320)..... RS4642 Cab Air (20435801)..... PA4681 Air Dryer (Bendix 5008414)..... BA5374 + Air Dryer (Wabco 3915558)..... BA5374 + Coolant (w/8 Units BTE) (20458769)..... BW5142 Coolant (w/o Chemical) (20458771)..... B5145 Trans. Ele. (1521527)..... PT9417 Opt. Trans. (Fuller 17237)..... B2 + Steering (349619)..... P106-HD	VNL430 w/VE D16 Eng. F-F Lube (478736)..... [2] B76-SS + B-P Lube (477556)..... B7685 Fuel/Water Separator Ele. (85105574)..... PF7680 Fuel/Water Separator Spin-on (Open End for Bowl) (20514654).. BF1366-O Fuel (20430751)..... BF7814 Fuel (22480372)..... BF46161 Radial Seal O. Air (20411815).... RS4642 Radial Seal I. Air (20411816)..... RS4643 Cab Air (20435801)..... PA4681 Air Dryer (Bendix 5008414)..... BA5374 + Coolant (w/o Chemical) (20458771)..... B5145 Coolant (w/8 Units BTE) (3945411)..... BW5142 Trans. Ele. (1521527)..... PT9417 Opt. Trans. Spin-on (Fuller 17237)..... B2 + Steering (349619)..... P106-HD VNL610 w/Cummins ISX Eng. Dual-Flow Lube..... BD7154 + Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... BD50000 Fuel/Water Separator (Fleetguard FS1040)..... BF1277-SPS	VNL430 w/VE D13 Eng. F-F Lube (21707133)..... [2] B76 + F-F Lube (Severe Service) (478736)..... [2] B76-SS + B-P Lube (477556)..... B7685 B-P Lube (21707132)..... B7409 Fuel/Water Separator Ele. (Fleetguard FS19728)..... PF7782 Fuel/Water Separator Ele. (Fleetguard FF5369W)..... PF7744 Fuel/Water Separator Ele. (85105574)..... PF7680 Fuel/Water Separator Ele. (Fleetguard FS19765)..... PF7930 Fuel/Water Separator Spin-on (w/Drain) (3945966)..... BF1329

+ See Product Guide for Variations of This Number. 90 Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).




VOLVO North America Trucks (cont'd)	VOLVO North America Trucks (cont'd)	VOLVO North America Trucks (cont'd)
VNL630 w/Cummins ISX Eng. (Cont'd)	VNL630 w/VE D12 Eng.	VNL630 w/D13 (12.8L) Eng. (2007-17) (Cont'd)
<b>Fuel/Water Separator Spin-on</b> (w/Drain) (85104856)..... <b>BF1355</b>	<b>F-F Lube</b> (478736)..... <b>[2] B76-SS +</b>	<b>Fuel/Water Separator Spin-on</b> (SP Thd. 9/16-18) (3945966)..... <b>BF1329-SP</b>
<b>Fuel/Water Separator Spin-on</b> (w/Drain & Sensor Port) (85104856)..... <b>BF1355-SP</b>	<b>B-P Lube</b> (477556)..... <b>B7685</b>	<b>Fuel/Water Separator Spin-on</b> (SP Thd. 1/2-20) (3945966)..... <b>BF1339-SP +</b>
<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (85104856).. <b>BF1355-O</b>	<b>Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154 +</b>	<b>Fuel/Water Separator Spin-on</b> (w/Bowl) (3945966)..... <b>BF46072</b>
<b>Fuel/Water Separator Ele.</b> (Davco 382119)..... <b>PF7782</b>	<b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>	<b>Fuel</b> (20430751)..... <b>BF7814</b>
<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19729)..... <b>PF7755</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FF5369)..... <b>PF7744</b>	<b>Fuel</b> (22480372)..... <b>BF46161</b>
<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19764)..... <b>PF9814</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R90P)..... <b>BF46083-O</b>	<b>Fuel</b> (20972293)..... <b>BF7943</b>
<b>Fuel/Water Separator Ele.</b> (85105574)..... <b>PF7680</b>	<b>Fuel/Water Separator</b> (w/Bowl) (Racor R90P)..... <b>BF46072</b>	<b>Fuel</b> (23044511)..... <b>BF46233</b>
<b>Fuel/Water Separator Ele.</b> (85120233)..... <b>PF7930</b>	<b>Fuel/Water Separator</b> (w/Drain) (Racor R90P)..... <b>BF1329</b>	<b>Radial Seal O. Air</b> (21715813)..... <b>RS4642</b>
<b>Fuel</b> (2007 Emissions) (Fleetguard FF2200)..... <b>BF7766</b>	<b>Fuel/Water Separator</b> (Sensor Port Thd. 9/16-18) (Racor R90P).. <b>BF1329-SP</b>	<b>Radial Seal I. Air</b> (20411816)..... <b>RS4643</b>
<b>Fuel</b> (2010 Emissions) (Fleetguard FF5686)..... <b>BF9860 +</b>	<b>Fuel/Water Separator</b> (Sensor Port Thd. 1/2-20) (Racor R90P).... <b>BF1339-SP +</b>	<b>Cab Air</b> (20435801)..... <b>[2] PA4681</b>
<b>Fuel</b> (2014 Emissions (Standard)) (Fleetguard FF5776).. <b>BF9885 +</b>	<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (20514654).. <b>BF1366-O</b>	<b>Air Dryer</b> (To 11/10/08) (3915558)..... <b>BA5374 +</b>
<b>Fuel</b> (2014 Emissions (Upgrade)) (FF5825NN)..... <b>BF46129</b>	<b>Fuel</b> (20430751)..... <b>BF7814</b>	<b>Air Dryer</b> (11/11/08-on) (85110799)..... <b>BA5592 90</b>
<b>Radial Seal O. Air</b> (20411815)..... <b>RS4642</b>	<b>Fuel</b> (22480372)..... <b>BF46161</b>	<b>Air Dryer</b> (SS1200 System) (Wabco R950068)..... <b>BA5379 +</b>
<b>Radial Seal I. Air</b> (20411816)..... <b>RS4643</b>	<b>Fuel</b> (8193841)..... <b>BF7653</b>	<b>Coolant</b> (w/8 Units BTE) (21388476)..... <b>BW5142</b>
<b>Cab Air</b> (20435801)..... <b>[2] PA4681</b>	<b>Some Fuel</b> (8193841)..... <b>BF7653</b>	<b>Coolant</b> (w/o Chemical) (21937327)..... <b>B5145</b>
<b>Air Dryer</b> (3915558)..... <b>BA5374 +</b>	<b>Radial Seal O. Air</b> (20411815)..... <b>RS4642</b>	<b>Trans. Ele.</b> (1521527)..... <b>PT9417</b>
<b>Air Dryer</b> (85110799)..... <b>BA5592 90</b>	<b>Radial Seal I. Air</b> (20411816)..... <b>RS4643</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
<b>Breather</b> (Fleetguard CV50634).... <b>CV15000</b>	<b>Cab Air</b> (20435801)..... <b>[2] PA4681</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>
<b>Coolant</b> (w/o Chemical) (Fleetguard WF2127)..... <b>B5087</b>	<b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b>	<b>Steering</b> (349619)..... <b>P106-HD</b>
<b>Coolant</b> (w/Chemical) (Fleetguard WF2126)..... <b>BW5086</b>	<b>Coolant</b> (w/o Chemical) (20458771)..... <b>B5145</b>	<b>Diesel Exhaust Fluid</b> (21516229) <b>PE17000</b>
<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>Coolant</b> (w/Chemical) (20458769)..... <b>BW5142</b>	<b>Diesel Exhaust Fluid</b> (82269261) <b>PE17001</b>
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Trans. Ele.</b> (1521527)..... <b>PT9417</b>	VNL630 w/D13 (12.8L) Eng. (2018)
<b>Steering</b> (349619)..... <b>P106-HD</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>F-F Lube</b> (21707133)..... <b>[2] B76 +</b>
<b>Diesel Exhaust Fluid</b> (2010 Emissions) (82269261)..... <b>PE17001</b>	<b>Steering</b> (349619)..... <b>P106-HD</b>	<b>B-P Lube</b> (21707132)..... <b>B7409</b>
<b>Diesel Exhaust Fluid</b> (2010 Emissions) (5303604)..... <b>PE17000</b>	VNL630 w/D13 (12.8L) Eng. (2007-17)	<b>Severe Service F-F Lube</b> (21707133)..... <b>[2] B76-SS +</b>
VNL630 w/VE D11 Eng.	<b>F-F Lube</b> (21707133)..... <b>[2] B76 +</b>	<b>Fuel/Water Separator</b> (21737499)..... <b>PF7930</b>
<b>F-F Lube</b> (478736)..... <b>[2] B76-SS +</b>	<b>F-F Lube</b> (Severe Service) (478736)..... <b>[2] B76-SS +</b>	<b>Fuel</b> (22474709)..... <b>BF46117</b>
<b>B-P Lube</b> (477556)..... <b>B7685</b>	<b>B-P Lube</b> (477556)..... <b>B7685</b>	<b>Radial Seal Air</b> (21715813)..... <b>RS4642</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (20514654)..... <b>BF1366-O</b>	<b>B-P Lube</b> (21707132)..... <b>B7409</b>	<b>Cab Air</b> (20435801)..... <b>PA4681</b>
<b>Fuel</b> (20430751)..... <b>BF7814</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FF5369)..... <b>PF7744</b>	<b>Air Dryer</b> (21620181)..... <b>BA5379 +</b>
<b>Fuel</b> (22480372)..... <b>BF46161</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19765)..... <b>PF7930</b>	<b>Coolant</b> (21937327)..... <b>B5145</b>
<b>Radial Seal O. Air</b> (20411815)..... <b>RS4642</b>	<b>Fuel/Water Separator Ele.</b> (85105574)..... <b>PF7680</b>	<b>Trans.</b> (21479106)..... <b>PT9417</b>
<b>Radial Seal I. Air</b> (20411816)..... <b>RS4643</b>	<b>Fuel/Water Separator Ele.</b> (Davco 382119)..... <b>PF7782</b>	<b>Steering</b> (349619)..... <b>P106-HD</b>
<b>Cab Air</b> (20435801)..... <b>PA4681</b>	<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (20514654).. <b>BF1366-O</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
<b>Air Dryer</b> (3915558)..... <b>BA5374 +</b>	<b>Fuel/Water Separator Spin-on</b> (21380475)..... <b>BF1386-O</b>	<b>Diesel Exhaust Fluid</b> (Filler Neck) (82269261)..... <b>PE17001</b>
<b>Coolant</b> (3945411)..... <b>BW5142</b>	<b>Fuel/Water Separator Spin-on</b> (w/Drain) (3945966)..... <b>BF1329</b>	<b>Diesel Exhaust Fluid</b> (Tank) (21516229)..... <b>PE17000</b>
<b>Trans. Ele.</b> (1521527)..... <b>PT9417</b>	<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (3945966).... <b>BF46083-O</b>	VNL630 w/VE D16 Eng.
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>		<b>F-F Lube</b> (478736)..... <b>[2] B76-SS +</b>
		<b>B-P Lube</b> (477556)..... <b>B7685</b>
		<b>B-P Lube</b> (21707132)..... <b>B7409</b>
		<b>Fuel/Water Separator Ele.</b> (85105574)..... <b>PF7680</b>
		<b>Fuel/Water Separator Ele.</b> (85120233)..... <b>PF7930</b>

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

VOLVO North America Trucks (cont'd)	VOLVO North America Trucks (cont'd)	VOLVO North America Trucks (cont'd)
VNL630 w/VE D16 Eng. (Cont'd)	VNL670 w/Cummins ISX Eng. (Cont'd)	VNL670 w/VE D12 Eng.
Fuel/Water Separator Ele. (Fleetguard FF5369W)..... PF7744	Fuel/Water Separator Ele. (85105574)..... PF7680	F-F Lube (478736-2)..... [2] B76-SS + B-P Lube (477556)..... B7685
Fuel/Water Separator Spin-on (Open End for Bowl) (20514654).. BF1366-O	Fuel/Water Separator Ele. (85120233)..... PF7930	Dual-Flow Lube (Fleetguard LF9001)..... BD7154 +
Fuel (20976003)..... BF7814	Fuel/Water Separator Ele. (Fleetguard FS19764)..... PF9814	Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... BD50000
Fuel (20972293)..... BF7943	Fuel/Water Separator (85121709)..... BF46173-O	Fuel/Water Separator Ele. (Fleetguard FF5369)..... PF7744
Fuel (21879886)..... BF46233	Fuel/Water Separator Spin-on (Open End for Bowl) (Racor S3238P)..... BF1355-O	Fuel/Water Separator Spin-on (w/Drain) (85104856)..... BF1355
Radial Seal O. Air (20411815)..... RS4642	Fuel/Water Separator Spin-on (w/Drain) (Racor S3238P)..... BF1355	Fuel/Water Separator Spin-on (w/Drain & Sensor Port) (85104856)..... BF1355-SP
Radial Seal I. Air (20411816)..... RS4643	Fuel/Water Separator Spin-on (w/Sensor Port) (Racor S3238P).. BF1355-SP	Fuel/Water Separator Spin-on (Open End for Bowl) (85104856).. BF1355-O
Cab Air (20435801)..... [2] PA4681	Fuel (2007 Emissions) (Fleetguard FF2200)..... BF7766	Fuel/Water Separator Spin-on (1-14 Thd.)..... BF1329
Air Dryer (To 11/10/08) (3915558)..... BA5374 +	Fuel (2010 Emissions) (Fleetguard FF5686)..... BF9860 +	Fuel (8193841)..... BF7653
Air Dryer (11/11/08-on) (85110799)..... BA5592 90	Fuel (2014 Emissions (Standard)) (Fleetguard FF5776).. BF9885 +	Fuel (20430751)..... BF7814
Air Dryer (SS1200 System) (Wabco R950068)..... BA5379 +	Fuel (2014 Emissions (Upgrade)) (Fleetguard FF5825NN)..... BF46129	Fuel (22480372)..... BF46161
Coolant (w/o Chemicals) (20458771)..... B5145	Fuel (2014 Emissions, Upgrade) (Fleetguard FF5811)..... BF46179	Fuel (Fleetguard FF2200)..... BF7766
Coolant (w/8 Units BTE) (3945411)..... BW5142	Radial Seal O. Air (20411815)..... RS4642	Single Radial Seal Air (20882320)..... RS4642
Trans. Ele. (1521527)..... PT9417	Radial Seal I. Air (20411816)..... RS4643	Radial Seal O. Air (20411815)..... RS4642
Opt. Trans. Spin-on (Fuller 17237)..... B2 +	Radial Seal I. Air (20411816)..... RS4643	Radial Seal I. Air (20411816)..... RS4643
Trans. Spin-on (Fuller 4304827).. BT223	Cab Air (20435801)..... PA4681	Cab Air (20435801)..... PA4681
Steering (349619)..... P106-HD	Air Dryer (Wabco R950068)..... BA5379 +	Air Dryer (3915558)..... BA5374 +
Diesel Exhaust Fluid (21516229) PE17000	Air Dryer (To 11/10/08) (3915558)..... BA5374 +	Coolant (w/o Chemical) (20458771)..... B5145
Diesel Exhaust Fluid (82269261) PE17001	Air Dryer (11/11/08-on) (85110799)..... BA5592 90	Coolant (w/o Chemical) (Fleetguard WF2127)..... B5087
VNL660 w/Cummins N14 Eng.	Breather (3685528)..... CV15000	Coolant (11 1/2 Units BTA+) (Fleetguard WF2126)..... BW5086
Dual-Flow Lube (3401544)..... BD7309 +	Coolant (w/o Chemical) (Fleetguard WF2127)..... B5087	Trans. Ele. (1521527)..... PT9417
Lube (Upgrade) (3401544)..... B40142 +	Coolant (w/Chemical) (Fleetguard WF2126)..... BW5086	Opt. Trans. Spin-on (Fuller 17237)..... B2 +
Fuel/Water Separator (3329289) BF1259	Trans. Spin-on (Fuller 4304827).. BT223	Steering (349619)..... P106-HD
Coolant (3844234)..... BW5076	Opt. Trans. Spin-on (Fuller 17237)..... B2 +	VNL670 w/D13 (12.8L) Eng. (2007-17)
VNL660 w/Cummins ISX Eng.	Steering (349619)..... P106-HD	F-F Lube (21707133)..... [2] B76 +
Dual-Flow Lube (Fleetguard LF9001)..... BD7154 +	Diesel Exhaust Fluid (82269261) PE17001	F-F Lube (Severe Service) (478736)..... [2] B76-SS +
Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... BD50000	Diesel Exhaust Fluid (5303604).. PE17000	B-P Lube (477556-5)..... B7685
Fuel/Water Separator..... BF1277-SP	VNL670 w/Cummins X15 (14.9L) Eng. (2018)	B-P Lube (21707132)..... B7409
Fuel (4088272)..... BF7766	Dual-Flow Lube (Fleetguard LF14000NN)..... BD50000	Fuel/Water Separator Ele. (85105574)..... PF7680
Radial Seal O. Air (8076195)..... RS3740	Fuel/Water Separator (21737499)..... PF7930	Fuel/Water Separator Ele. (Davco 382119)..... PF7782
Radial Seal I. Air..... RS3741	Fuel (Fleetguard FF5825NN)..... BF46129 +	Fuel/Water Separator Ele. (85120233)..... PF7930
Cab Air (20435801)..... PA4681	Radial Seal Air (21715813)..... RS4642	Fuel/Water Separator Ele. (Fleetguard FF5369)..... PF7744
Air Dryer (3915558)..... BA5374 +	Cab Air (20435801)..... PA4681	Fuel/Water Separator (Open End for Bowl) (Racor R90P)..... BF46083-O
Breather (1/07-on) (3683918)..... CV15000	Air Dryer (21620181)..... BA5379 +	Fuel/Water Separator (w/Bowl) (Racor R90P)..... BF46072
Coolant (w/11 1/2 Units BTA+) (Fleetguard WF2126)..... BW5086	Trans. (21479106)..... PT9417	Fuel/Water Separator (w/Drain) (Racor R90P)..... BF1329
Coolant (w/o Chemical) (Fleetguard WF2127)..... B5087	Steering (349619)..... P106-HD	
Opt. Trans. Spin-on (Fuller 17237)..... B2 +	Opt. Rear Axle (Meritor 3280V8394)..... B233	
Steering (349619)..... P106-HD	Diesel Exhaust Fluid (4388378).. PE17002 KIT	
VNL670 w/Cummins ISX Eng.		
Dual-Flow Lube (Fleetguard LF9080)..... BD7154 +		
Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... BD50000		
Fuel/Water Separator Ele. (Fleetguard FS19728)..... PF7782		

+ See Product Guide for Variations of This Number. 90 Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).


VOLVO North America Trucks (cont'd)	VOLVO North America Trucks (cont'd)	VOLVO North America Trucks (cont'd)
VNL670 w/D13 (12.8L) Eng. (2007-17) (Cont'd)	VNL670 w/D13 (12.8L) Eng. (2019) (Cont'd)	VNL730 w/Cummins ISX Eng.
Fuel/Water Separator (Sensor Port Thd. 9/16-18) (Racor R90P)..	Cab Air (20435801).....	Dual-Flow Lube (Fleetguard LF9080).....
BF1329-SP	Air Dryer (21620181).....	BD7154 +
Fuel/Water Separator (Sensor Port Thd. 1/2-20) (Racor R90P)....	Coolant (21937327).....	Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN).....
BF1339-SP +	Trans. Ele. (I-Shift) (21479106)....	BD50000
Fuel/Water Separator Spin-on (Open End for Bowl) (20514654)..	Trans. Spin-on (Fuller 4304827)..	Fuel/Water Separator Ele. (85120233).....
BF1366-O	Steering (349619).....	PF7930
Fuel/Water Separator Spin-on (21380475).....	Opt. Rear Axle (Meritor 3280V8394).....	Fuel/Water Separator Spin-on (Open End for Bowl) (Racor S3238P).....
BF1386-O	B233	BF1355-O
Fuel (20430751).....	Diesel Exhaust Fluid (21516229)	Fuel/Water Separator Spin-on (w/Drain) (Racor S3238P).....
BF7814	PE17000	BF1355
Fuel (22480372).....	VNL670 w/D13 (12.8L) Eng. (2020)	Fuel/Water Separator Spin-on (w/Sensor Port) (Racor S3238P)..
BF46161	F-F Lube (21707133).....	BF1355-SP
Fuel (20972293).....	[2] B76 +	Fuel/Water Separator (85121709).....
BF7943	B-P Lube (21707132).....	BF46173-O
Fuel (23044511).....	B7409	P. Fuel (2007 Emissions) (Fleetguard FF2200).....
Radial Seal O. Air (20411815)....	Fuel/Water Separator (Fleetguard FS19764G).....	BF7766
RS4642	Fuel (22474709).....	P. Fuel (2010 Emissions) (Fleetguard FF5686).....
Radial Seal I. Air (20411816).....	PF46091	BF9860 +
RS4643	Fuel (22474709).....	P. Fuel (2014 Emissions (Standard)) (Fleetguard FF5776)..
Cab Air (20435801).....	Radial Seal Air (21715813).....	BF9885 +
[2] PA4681	RS4642	P. Fuel (2014 Emissions (Upgrade)) (Fleetguard FF5825NN).....
Air Dryer (3915558).....	Cab Air (20435801).....	BF46129
BA5374 +	PA4681	Radial Seal O. Air (21715813)....
Air Dryer (Wabco R950068).....	Air Dryer (21620181).....	RS4642
BA5379 +	Coolant (21937327).....	Radial Seal I. Air (20411816).....
Air Dryer (85110799).....	B5145	RS4643
BA5592 <sup>90</sup>	Opt. Trans. Spin-on (Fuller 17237).....	Cab Air (20435801).....
Coolant (w/o Chemical) (20458771).....	B2	PA4681
B5145	Trans. Spin-on (Fuller 4304827)..	Air Dryer (3915558).....
Coolant (w/Chemical) (20458769).....	BT223	BA5374 +
BW5142	Steering (349619).....	Air Dryer (85110799).....
Trans. Ele. (1521527).....	P106-HD	BA5592 <sup>90</sup>
PT9417	Opt. Rear Axle (Meritor 3280V8394).....	Air Dryer (Wabco R950068).....
Trans. Spin-on (Fuller 4304827)..	B233	BA5379 +
BT223	Diesel Exhaust Fluid (21516229)	Breather (Fleetguard CV50634)...
Opt. Trans. Spin-on (Fuller 17237).....	PE17000	CV15000
B2 +	VNL670 w/VE D16 Eng.	Coolant (w/o Chemical) (Fleetguard WF2127).....
Steering (349619).....	F-F Lube (478736).....	B5087
P106-HD	[2] B76-SS +	Coolant (w/Chemical) (Fleetguard WF2126).....
Diesel Exhaust Fluid (82269261)	F-F Lube (21707133).....	BW5086
PE17001	[2] B76 +	Trans. Ele. (20779040).....
Diesel Exhaust Fluid (21516229)	B-P Lube (477556).....	PT9417
PE17000	B7409	Trans. Spin-on (Fuller 4304827)..
VNL670 w/D13 (12.8L) Eng. (2018)	Fuel/Water Separator Ele. (Fleetguard FF5369W).....	BT223
F-F Lube (21707133).....	Fuel/Water Separator Ele. (85105574).....	Opt. Trans. Spin-on (Fuller 17237).....
[2] B76 +	PF7744	B2 +
B-P Lube (21707132).....	Fuel/Water Separator Ele. (85105574).....	Steering (349619).....
B7409	PF7680	P106-HD
Severe Service F-F Lube (21707133).....	Fuel/Water Separator Ele. (85120233).....	Diesel Exhaust Fluid (2888182)..
[2] B76-SS +	PF7930	PE17000
Fuel/Water Separator (21737499).....	Fuel/Water Separator Spin-on (Open End for Bowl) (20514654)..	Diesel Exhaust Fluid (82269261)
PF7930	BF1366-O	PE17001
Fuel (22474709).....	Fuel (20430751).....	VNL730 w/VE D12 Eng.
BF46117	BF7814	Dual-Flow Lube (Fleetguard LF9001).....
Radial Seal Air (21715813).....	Fuel (22480372).....	BD7154 +
RS4642	BF46161	Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN).....
Cab Air (20435801).....	Radial Seal O. Air (20411815)....	BD50000
PA4681	RS4642	Fuel/Water Separator (Davco 382119).....
Air Dryer (21620181).....	Radial Seal I. Air (20411816).....	PF7782
BA5379 +	RS4643	Fuel (20430751).....
Coolant (21937327).....	Cab Air (20435801).....	BF7814
B5145	PA4681	Fuel (22480372).....
Trans. (21479106).....	Air Dryer (To 11/10/08) (3915558).....	BF46161
PT9417	BA5374 +	Some Fuel (8193841).....
Steering (349619).....	Air Dryer (11/11/08-on) (85110799).....	BF7653
P106-HD	BA5592 <sup>90</sup>	Radial Seal O. Air (20411815)....
Opt. Rear Axle (Meritor 3280V8394).....	Coolant (w/8 Units BTE) (3945411).....	RS4642
B233	BW5142	Radial Seal I. Air (20411816).....
Diesel Exhaust Fluid (Filler Neck) (82269261).....	Coolant (w/o Chemical) (21937327).....	RS4643
PE17001	B5145	Cab Air (20435801).....
Diesel Exhaust Fluid (Tank) (21516229).....	Trans. Ele. (1521527).....	PA4681
PE17000	PT9417	Air Dryer (Wabco R950011).....
VNL670 w/D13 (12.8L) Eng. (2019)	Opt. Trans. Spin-on (Fuller 17237).....	BA5374 +
F-F Lube (21707133).....	B2 +	Coolant (20458771).....
B76 +	Trans. Spin-on (Fuller 4304827)..	B5145
B-P Lube (21707132).....	BT223	Trans. Ele. (1521527).....
B7409	P106-HD	PT9417
Severe Service F-F Lube (21707133).....	Diesel Exhaust Fluid (82269261)	
B76-SS +	PE17001	
Fuel/Water Separator (85120233).....		
PF7930		
Fuel (22474709).....		
BF46117		
Radial Seal Air (21715813).....		
RS4642		

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

VOLVO North America Trucks (cont'd)	VOLVO North America Trucks (cont'd)	VOLVO North America Trucks (cont'd)
VNL730 w/VE D12 Eng. (Cont'd)	VNL730 w/D13 (12.8L) Eng. (2018) (Cont'd)	VNL740 w/Cummins ISX 15.0 (14.9L) Eng. (2020)
Opt. Trans. Spin-on (Fuller 17237)..... B2 +	Fuel (22474709)..... BF46117	Dual-Flow Lube (4367100)..... BD50000
Steering (349619)..... P106-HD	Radial Seal Air (21715813)..... RS4642	Fuel/Water Separator Ele. (Fleetguard FS19764G)..... PF46091
VNL730 w/D13 (12.8L) Eng. (2007-17)	Cab Air (20435801)..... PA4681	Fuel/Water Separator Spin-on (85121709)..... BF46173-O
F-F Lube (21707133)..... [2] B76 +	Air Dryer (21620181)..... BA5379 +	Fuel (5365988)..... BF46129
F-F Lube (Severe Service) (478736)..... [2] B76-SS +	Coolant (21937327)..... B5145	Radial Seal Air (21715813)..... RS4642
B-P Lube (477556)..... B7685	Trans. (21479106)..... PT9417	Cab Air (20435801)..... PA4681
B-P Lube (21707132)..... B7409	Steering (349619)..... P106-HD	Air Dryer (21620181)..... BA5379
Fuel/Water Separator Ele. (85105574)..... PF7680	Opt. Rear Axle (Meritor 3280V8394)..... B233	Coolant (3680434)..... B5087
Fuel/Water Separator Ele. (Fleetguard FF5369W)..... PF7744	Diesel Exhaust Fluid (Filler Neck) (82269261)..... PE17001	Trans. (Fuller 4304827)..... BT223
Fuel/Water Separator Ele. (Fleetguard FS19765)..... PF7930	Diesel Exhaust Fluid (Tank) (21516229)..... PE17000	Steering (349619)..... P106-HD
Fuel/Water Separator Spin-on (w/Drain) (3945966)..... BF1329	VNL730 w/VE D16 Eng.	Opt. Rear Axle (Meritor 3280V8394)..... B233
Fuel/Water Separator Spin-on (Open End for Bowl) (3945966)..... BF46083-O	F-F Lube (478736)..... [2] B76-SS +	VNL740 w/Cummins X15 (14.9L) Eng. (2020)
Fuel/Water Separator Spin-on (w/9/16-18 SP Thd.) (3945966)..... BF1329-SP	B-P Lube (477556)..... B7685	Dual-Flow Lube (4367100)..... BD50000
Fuel/Water Separator Spin-on (w/1/2-20 SP Thd.) (3945966)..... BF1339-SP +	Fuel/Water Separator Ele. (Fleetguard FF5369)..... PF7744	Fuel/Water Separator Ele. (Fleetguard FS19764G)..... PF46091
Fuel/Water Separator Spin-on (w/Bowl) (3945966)..... BF46072	Fuel/Water Separator Ele. (85105574)..... PF7680	Fuel/Water Separator Spin-on (85121709)..... BF46173-O
Fuel/Water Separator Spin-on (Open End for Bowl) (20514654)..... BF1366-O	Fuel/Water Separator Spin-on (Open End for Bowl) (20514654)..... BF1366-O	Fuel (5365988)..... BF46129
Fuel/Water Separator Spin-on (21380475)..... BF1386-O	Fuel (20430751)..... BF7814	Radial Seal Air (21715813)..... RS4642
Fuel (20976003)..... BF7814	Fuel (22480372)..... BF46161	Cab Air (20435801)..... PA4681
Fuel (20972293)..... BF7943	Fuel (20972293)..... BF7943	Air Dryer (21620181)..... BA5379
Fuel (23044511)..... BF46233	Radial Seal O. Air (20411815)..... RS4642	Coolant (3680434)..... B5087
Single Radial Seal Air (21715813)..... RS4642	Radial Seal I. Air (20411816)..... RS4643	Trans. (Fuller 4304827)..... BT223
Cab Air (20435801)..... PA4681	Cab Air (20435801)..... PA4681	Steering (349619)..... P106-HD
Air Dryer (3915558)..... BA5374 +	Air Dryer (To 11/10/08) (3915558)..... BA5374 +	Opt. Rear Axle (Meritor 3280V8394)..... B233
Air Dryer (85110799)..... BA5592 90	Air Dryer (11/11/08-on) (85110799)..... BA5592 90	VNL740 w/D13 (12.8L) Eng. (2019)
Air Dryer (Wabco R950068)..... BA5379 +	Coolant (w/o Chemical) (20458771)..... B5145	F-F Lube (21707133)..... [2] B76 +
Coolant (w/8 Units BTE) (21388476)..... BW5142	Coolant (w/8 Units BTE) (3945411)..... BW5142	B-P Lube (21707132)..... B7409
Coolant (w/o Chemical) (21937327)..... B5145	Trans. Ele. (1521527)..... PT9417	Severe Service F-F Lube (21707133)..... [2] B76-SS +
Trans. Ele. (20779040)..... PT9417	Opt. Trans. Spin-on (Fuller 17237)..... B2 +	Fuel/Water Separator (85120233)..... PF7930
Trans. Spin-on (Fuller 4304827)..... BT223	Steering (349619)..... P106-HD	Fuel (22474709)..... BF46117
Opt. Trans. Spin-on (Fuller 17237)..... B2 +	VNL740 w/Cummins X15 (14.9L) Eng. (2019)	Radial Seal Air (21715813)..... RS4642
Steering (349619)..... P106-HD	Dual-Flow Lube (4367100)..... BD50000	Cab Air (20435801)..... PA4681
Diesel Exhaust Fluid (2010 Emissions) (21516229)..... PE17000	Fuel/Water Separator (85120233)..... PF7930	Air Dryer (21620181)..... BA5379 +
Diesel Exhaust Fluid (2010 Emissions) (82269261)..... PE17001	Fuel/Water Separator (Fleetguard FS19764G)..... PF46091	Coolant (21937327)..... B5145
VNL730 w/D13 (12.8L) Eng. (2018)	Fuel (5365988)..... BF46129 +	Trans. Ele. (I-Shift) (21479106)..... PT9417
F-F Lube (21707133)..... [2] B76 +	Air (21715813)..... RS4642	Trans. Spin-on (Fuller 4304827)..... BT223
B-P Lube (21707132)..... B7409	Cab Air (20435801)..... PA4681	Steering (349619)..... P106-HD
Severe Service F-F Lube (21707133)..... [2] B76-SS +	Air Dryer (21620181)..... BA5379 +	Opt. Rear Axle (Meritor 3280V8394)..... B233
Fuel/Water Separator (21764964)..... BF46182-O	Trans. Ele. (I-Shift) (21479106)..... PT9417	Diesel Exhaust Fluid (21516229)..... PE17000
	Trans. Spin-on (Fuller 4304827)..... BT223	VNL740 w/D13 (12.8L) Eng. (2020)
	Steering (349619)..... P106-HD	F-F Lube (21707133)..... [2] B76 +
	Opt. Rear Axle (Meritor 3280V8394)..... B233	B-P Lube (21707132)..... B7409
		Fuel/Water Separator (Fleetguard FS19764G)..... PF46091
		Fuel (22474709)..... BF46117
		Radial Seal Air (21715813)..... RS4642
		Cab Air (20435801)..... PA4681
		Air Dryer (21620181)..... BA5379
		Coolant (21937327)..... B5145

+ See Product Guide for Variations of This Number. 90 Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

VOLVO North America Trucks (cont'd)	VOLVO North America Trucks (cont'd)	VOLVO North America Trucks (cont'd)
VNL740 w/D13 (12.8L) Eng. (2020) (Cont'd)	VNL760 w/Cummins X15 (14.9L) Eng. (2020)	VNL770 w/D13 Eng. (Cont'd)
Opt. Trans. Spin-on (Fuller 17237)..... B2	Dual-Flow Lube (4367100)..... BD50000	Radial Seal I. Air (20411816)..... RS4643
Trans. Spin-on (Fuller 4304827).. BT223	Fuel/Water Separator Ele. (Fleetguard FS19764G)..... PF46091	Cab Air (20435801)..... PA4681
Steering (349619)..... P106-HD	Fuel/Water Separator Spin-on (85121709)..... BF46173-O	Air Dryer (Wabco R950011)..... BA5374 +
Opt. Rear Axle (Meritor 3280V8394)..... B233	Fuel (5365988)..... BF46129	Coolant (20458771)..... B5145
Diesel Exhaust Fluid (21516229) PE17000	Radial Seal Air (21715813)..... RS4642	Trans. Ele. (1521527)..... PT9417
VNL760 w/Cummins ISX 15.0 (14.9L) Eng. (2019)	Cab Air (20435801)..... PA4681	Trans. Spin-on (Fuller 4304827).. BT223
Dual-Flow Lube (4367100)..... BD50000	Air Dryer (21620181)..... BA5379	Opt. Trans. Spin-on (Fuller 17237)..... B2 +
Fuel/Water Separator (85120233)..... PF7930	Coolant (3680434)..... B5087	Steering (349619)..... P106-HD
Fuel/Water Separator (Fleetguard FS19764G)..... PF46091	Trans. (Fuller 4304827)..... BT223	VNL770 w/VED12 Eng.
Fuel (5365988)..... BF46129	Steering (349619)..... P106-HD	F-F Lube (478736)..... [2] B76-SS +
Radial Seal Air (20435801)..... RS4642	Opt. Rear Axle (Meritor 3280V8394)..... B233	B-P Lube (477556)..... B7685
Cab Air (20435801)..... PA4681	VNL760 w/D13 (12.8L) Eng. (2019)	Fuel/Water Separator (85105574)..... PF7680
Air Dryer (21620181)..... BA5379 +	F-F Lube (21707133)..... [2] B76 +	Fuel..... BF7653
Trans. Ele. (I-Shift) (21479106).... PT9417	B-P Lube (21707132)..... B7409	Fuel (20430751)..... BF7814
Trans. Spin-on (Fuller 4304827).. BT223	Severe Service F-F Lube (21707133)..... [2] B76-SS +	Fuel (22480372)..... BF46161
Steering (349619)..... P106-HD	Fuel/Water Separator (85120233)..... PF7930	16 7/16 In. Radial Seal Air (8076195)..... RS3740
Opt. Rear Axle (Meritor 3280V8394)..... B233	Fuel (22474709)..... BF46117	19 1/2 In. Radial Seal Air (20411815)..... RS4642
VNL760 w/Cummins ISX 15.0 (14.9L) Eng. (2020)	Radial Seal Air (21715813)..... RS4642	Cab Air (20435801)..... PA4681
Dual-Flow Lube (4367100)..... BD50000	Cab Air (20435801)..... PA4681	Air Dryer (3915558)..... BA5374 +
Fuel/Water Separator Ele. (Fleetguard FS19764G)..... PF46091	Air Dryer (21620181)..... BA5379 +	4 7/16 In. Coolant (20458771).... B5145
Fuel/Water Separator Spin-on (85121709)..... BF46173-O	Coolant (21937327)..... B5145	5 7/16 In. Coolant (3969696)..... B5144
Fuel (5365988)..... BF46129	Trans. Ele. (I-Shift) (21479106).... PT9417	Steering (349619)..... P106-HD
Radial Seal Air (21715813)..... RS4642	Trans. Spin-on (Fuller 4304827).. BT223	VNL780 w/Cummins ISX Eng. (Pre-2007 Emissions)
Cab Air (20435801)..... PA4681	Steering (349619)..... P106-HD	Dual-Flow Lube (Fleetguard LF9031)..... BD7509 +
Air Dryer (21620181)..... BA5379	Opt. Rear Axle (Meritor 3280V8394)..... B233	Dual-Flow Lube (Fleetguard LF9080)..... BD7154 +
Coolant (3680434)..... B5087	Diesel Exhaust Fluid (21516229) PE17000	Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... BD50000
Trans. (Fuller 4304827)..... BT223	VNL760 w/D13 (12.8L) Eng. (2020)	Fuel/Water Separator Spin-on (w/Drain) (85104856)..... BF1355
Steering (349619)..... P106-HD	F-F Lube (21707133)..... [2] B76 +	Fuel/Water Separator Spin-on (w/Drain & Sensor Port) (85104856)..... BF1355-SP
Opt. Rear Axle (Meritor 3280V8394)..... B233	B-P Lube (21707132)..... B7409	Fuel/Water Separator Spin-on (Open End for Bowl) (85104856).. BF1355-O
VNL760 w/Cummins X15 (14.9L) Eng. (2019)	Fuel/Water Separator (Fleetguard FS19764G)..... PF46091	Fuel/Water Separator Ele. (Fleetguard FF5369W)..... PF7744
Dual-Flow Lube (4367100)..... BD50000	Fuel (22474709)..... BF46117	Fuel/Water Separator Ele. (Fleetguard FS1029)..... PF7680
Fuel/Water Separator (85120233)..... PF7930	Radial Seal Air (21715813)..... RS4642	Fuel/Water Separator Ele. (85120233)..... PF7930
Fuel/Water Separator (Fleetguard FS19764G)..... PF46091	Cab Air (20435801)..... PA4681	Fuel/Water Separator Ele. (Fleetguard FS19764)..... PF9814
Fuel (5365988)..... BF46129	Air Dryer (21620181)..... BA5379	Fuel/Water Separator (Fleetguard FS19764G)..... PF46091
Radial Seal Air (21715813)..... RS4642	Coolant (21937327)..... B5145	Fuel (Fleetguard FF2203)..... BF7760
Cab Air (20435801)..... PA4681	Opt. Trans. Spin-on (Fuller 17237)..... B2	Radial Seal O. Air (21715813).... RS4642
Air Dryer (21620181)..... BA5379 +	Trans. Spin-on (Fuller 4304827).. BT223	Opt. Radial Seal I. Air (20411816)..... RS4643
Trans. Ele. (I-Shift) (21479106).... PT9417	Steering (349619)..... P106-HD	Cab Air (20435801)..... PA4681
Trans. Spin-on (Fuller 4304827).. BT223	Opt. Rear Axle (Meritor 3280V8394)..... B233	Opt. Cab Air (20435801)..... [2] PA4681
Steering (349619)..... P106-HD	Diesel Exhaust Fluid (21516229) PE17000	Air Dryer (Wabco R950011)..... BA5374 +
Opt. Rear Axle (Meritor 3280V8394)..... B233	VNL770 w/D13 Eng.	
	F-F Lube (478736)..... [2] B76-SS +	
	B-P Lube (477556)..... B7685	
	Fuel/Water Separator Ele. (Fleetguard FF5369)..... PF7744	
	Fuel/Water Separator Ele. (85105574)..... PF7680	
	S. Fuel (20972293)..... BF7943	
	Radial Seal O. Air (20882320).... RS4642	

+ See Product Guide for Variations of This Number. Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>VOLVO</b> <b>North America Trucks (cont'd)</b>	<b>VOLVO</b> <b>North America Trucks (cont'd)</b>	<b>VOLVO</b> <b>North America Trucks (cont'd)</b>
VNL780 w/Cummins ISX Eng. (Pre-2007 Emissions) (Cont'd)	VNL780 w/Cummins ISX Eng. (2007 Emissions) (Cont'd)	VNL780 w/Cummins ISX Eng. (2014 Emissions) (Cont'd)
<b>Air Dryer</b> (85110799)..... <b>BA5592<sup>90</sup></b>	<b>4 3/16 In. Steering</b> (Nelson 84148A)..... <b>P528</b>	<b>Fuel/Water Separator Spin-on</b> (w/Drain) (85104856)..... <b>BF1355</b>
<b>Breather</b> (3683918)..... <b>CV15000</b>	<b>Diesel Exhaust Fluid</b> (82269261) <b>PE17001</b>	<b>Fuel/Water Separator Spin-on</b> (w/Drain & Sensor Port) (85104856)..... <b>BF1355-SP</b>
<b>Coolant</b> (w/o Chemical) (Fleetguard WF2127)..... <b>B5087</b>	<b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>	<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (85104856).. <b>BF1355-O</b>
<b>Coolant</b> (w/Chemical) (Fleetguard WF2126)..... <b>BW5086</b>	VNL780 w/Cummins ISX Eng. (2010 Emissions)	<b>Fuel/Water Separator Ele.</b> (Fleetguard FF5369W)..... <b>PF7744</b>
<b>Trans. Ele.</b> (20779040)..... <b>PT9417</b>	<b>Dual-Flow Lube</b> (Fleetguard LF9031)..... <b>BD7509 +</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029)..... <b>PF7680</b>
<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>Dual-Flow Lube</b> (Fleetguard LF9080)..... <b>BD7154 +</b>	<b>Fuel/Water Separator Ele.</b> (85120233)..... <b>PF7930</b>
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19764)..... <b>PF9814</b>
<b>3 31/32 In. Steering</b> (349619)..... <b>P106-HD</b>	<b>Fuel/Water Separator Spin-on</b> (w/Drain) (85104856)..... <b>BF1355</b>	<b>Fuel/Water Separator</b> (Fleetguard FS19764G)..... <b>PF46091</b>
<b>4 3/16 In. Steering</b> (Nelson 84148A)..... <b>P528</b>	<b>Fuel/Water Separator Spin-on</b> (w/Drain & Sensor Port) (85104856)..... <b>BF1355-SP</b>	<b>Fuel</b> (Standard) (Fleetguard FF5776)..... <b>BF9885 +</b>
<b>Diesel Exhaust Fluid</b> (82269261) <b>PE17001</b>	<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (85104856).. <b>BF1355-O</b>	<b>Fuel</b> (Upgrade) (Fleetguard FF5825NN)..... <b>BF46129</b>
<b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FF5369W)..... <b>PF7744</b>	<b>Radial Seal O. Air</b> (21715813).... <b>RS4642</b>
VNL780 w/Cummins ISX Eng. (2007 Emissions)	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029)..... <b>PF7680</b>	<b>Opt. Radial Seal I. Air</b> (20411816)..... <b>RS4643</b>
<b>Dual-Flow Lube</b> (Fleetguard LF9031)..... <b>BD7509 +</b>	<b>Fuel/Water Separator Ele.</b> (85120233)..... <b>PF7930</b>	<b>Cab Air</b> (20435801)..... <b>PA4681</b>
<b>Dual-Flow Lube</b> (Fleetguard LF9080)..... <b>BD7154 +</b>	<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19764)..... <b>PF9814</b>	<b>Opt. Cab Air</b> (20435801)..... <b>[2] PA4681</b>
<b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>	<b>Fuel/Water Separator</b> (Fleetguard FS19764G)..... <b>PF46091</b>	<b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b>
<b>Fuel/Water Separator Spin-on</b> (w/Drain) (85104856)..... <b>BF1355</b>	<b>Fuel</b> (Fleetguard FF5686)..... <b>BF9860 +</b>	<b>Air Dryer</b> (85110799)..... <b>BA5592<sup>90</sup></b>
<b>Fuel/Water Separator Spin-on</b> (w/Drain & Sensor Port) (85104856)..... <b>BF1355-SP</b>	<b>Radial Seal O. Air</b> (21715813).... <b>RS4642</b>	<b>Air Dryer</b> (21620181)..... <b>BA5379 +</b>
<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (85104856).. <b>BF1355-O</b>	<b>Opt. Radial Seal I. Air</b> (20411816)..... <b>RS4643</b>	<b>Breather</b> (3683918)..... <b>CV15000</b>
<b>Fuel/Water Separator Ele.</b> (Fleetguard FF5369W)..... <b>PF7744</b>	<b>Cab Air</b> (20435801)..... <b>PA4681</b>	<b>Coolant</b> (w/o Chemical) (Fleetguard WF2127)..... <b>B5087</b>
<b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029)..... <b>PF7680</b>	<b>Opt. Cab Air</b> (20435801)..... <b>[2] PA4681</b>	<b>Coolant</b> (w/Chemical) (Fleetguard WF2126)..... <b>BW5086</b>
<b>Fuel/Water Separator Ele.</b> (85120233)..... <b>PF7930</b>	<b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b>	<b>Trans. Ele.</b> (20779040)..... <b>PT9417</b>
<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19764)..... <b>PF9814</b>	<b>Air Dryer</b> (85110799)..... <b>BA5592<sup>90</sup></b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>
<b>Fuel/Water Separator</b> (Fleetguard FS19764G)..... <b>PF46091</b>	<b>Breather</b> (3683918)..... <b>CV15000</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
<b>Fuel</b> (4088272)..... <b>BF7766</b>	<b>Coolant</b> (w/o Chemical) (Fleetguard WF2127)..... <b>B5087</b>	<b>3 31/32 In. Steering</b> (349619)..... <b>P106-HD</b>
<b>Radial Seal O. Air</b> (21715813).... <b>RS4642</b>	<b>Coolant</b> (w/Chemical) (Fleetguard WF2126)..... <b>BW5086</b>	<b>4 3/16 In. Steering</b> (Nelson 84148A)..... <b>P528</b>
<b>Opt. Radial Seal I. Air</b> (20411816)..... <b>RS4643</b>	<b>Trans. Ele.</b> (20779040)..... <b>PT9417</b>	<b>Diesel Exhaust Fluid</b> (82269261) <b>PE17001</b>
<b>Cab Air</b> (20435801)..... <b>PA4681</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>
<b>Opt. Cab Air</b> (20435801)..... <b>[2] PA4681</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	VNL780 w/VE D12 Eng.
<b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b>	<b>3 31/32 In. Steering</b> (349619)..... <b>P106-HD</b>	<b>F-F Lube</b> (478736)..... <b>[2] B76-SS +</b>
<b>Air Dryer</b> (85110799)..... <b>BA5592<sup>90</sup></b>	<b>4 3/16 In. Steering</b> (Nelson 84148A)..... <b>P528</b>	<b>B-P Lube</b> (477556)..... <b>B7685</b>
<b>Breather</b> (3683918)..... <b>CV15000</b>	<b>Diesel Exhaust Fluid</b> (82269261) <b>PE17001</b>	<b>Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154 +</b>
<b>Coolant</b> (w/o Chemical) (Fleetguard WF2127)..... <b>B5087</b>	<b>Diesel Exhaust Fluid</b> (5303604).. <b>PE17000</b>	<b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>
<b>Coolant</b> (w/Chemical) (Fleetguard WF2126)..... <b>BW5086</b>	VNL780 w/Cummins ISX Eng. (2014 Emissions)	<b>Fuel/Water Separator Ele.</b> (Davco 382119)..... <b>PF7782</b>
<b>Trans. Ele.</b> (20779040)..... <b>PT9417</b>	<b>Dual-Flow Lube</b> (Fleetguard LF9031)..... <b>BD7509 +</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R90P)..... <b>BF46083-O</b>
<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>Dual-Flow Lube</b> (Fleetguard LF9080)..... <b>BD7154 +</b>	<b>Fuel/Water Separator</b> (w/Bowl) (Racor R90P)..... <b>BF46072</b>
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>	
<b>3 31/32 In. Steering</b> (349619)..... <b>P106-HD</b>		

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

VOLVO North America Trucks (cont'd)	VOLVO North America Trucks (cont'd)	VOLVO North America Trucks (cont'd)
VNL780 w/VE D12 Eng. (Cont'd)	VNL780 w/D13 (12.8L) Eng. (2007-17) (Cont'd)	VNL780 w/VE D16 Eng. (Cont'd)
Fuel/Water Separator (w/Drain) (Racor R90P).....	4 3/16 In. Steering (Nelson 84148A).....	Fuel/Water Separator Spin-on (Open End for Bowl) (3945966)....
BF1329	P528	BF46083-O
Fuel/Water Separator (Sensor Port Thd. 9/16-18) (Racor R90P)..	Diesel Exhaust Fluid (21516229) PE17000	Fuel/Water Separator Spin-on (w/9/16-18 SP Thd.) (3945966)....
BF1329-SP	PE17001	BF1329-SP
Fuel/Water Separator (Sensor Port Thd. 1/2-20) (Racor R90P)....	VNL780 w/D13 (12.8L) Eng. (2018)	Fuel/Water Separator Spin-on (w/1/2-20 SP Thd.) (3945966).....
BF1339-SP +	F-F Lube (21707133).....	BF1339-SP +
Fuel (20430751).....	[2] B76 +	Fuel/Water Separator Spin-on (w/Bowl) (3945966).....
BF7814	B-P Lube (21707132).....	BF46072
Fuel (22480372).....	B7409	BF7814
BF46161	Severe Service F-F Lube (21707133).....	BF7943
Some Fuel (8193841).....	[2] B76-SS +	BF46233
BF7653	Fuel/Water Separator (21764964).....	RS4642
Single Radial Seal Air (20882320).....	BF46182-O	Opt. Radial Seal I. Air (20411816).....
RS4642	Fuel (22474709).....	RS4643
Radial Seal O. Air (20411815).....	BF46117	Cab Air (20435801).....
RS4642	Radial Seal Air (21715813).....	PA4681
Radial Seal I. Air (20411816).....	RS4642	Opt. Cab Air (20435801).....
RS4643	Cab Air (20435801).....	[2] PA4681
Cab Air (20435801).....	[2] PA4681	Air Dryer (3915558).....
PA4681	Air Dryer (21620181).....	BA5374 +
Air Dryer (20377023).....	BA5379 +	BA5592 90
BA5374 +	Coolant (21937327).....	BA5379 +
Coolant (M16 x 1.5 Thd.) (20458771).....	B5145	Coolant (w/o Chemical) (21937327).....
B5145	Trans. (21479106).....	B5145
Coolant (M36 x 2.0 Thd.) (Fleetguard WF2127).....	PT9417	Coolant (w/8 Units BTE) (3945411).....
B5087	Steering (349619).....	BW5142
Trans. Ele. (1521527).....	P106-HD	Trans. Ele. (20779040).....
PT9417	Opt. Rear Axle (Meritor 3280V8394).....	PT9417
Trans. Spin-on (Fuller 4304827)..	B233	BT223
BT223	Diesel Exhaust Fluid (Filler Neck) (82269261).....	Opt. Trans. Spin-on (Fuller 17237).....
Opt. Trans. Spin-on (Fuller 17237).....	PE17001	B2 +
B2 +	Diesel Exhaust Fluid (Tank) (21516229).....	P106-HD
Steering (349619).....	PE17000	3 31/32 In. Steering (349619).....
P106-HD	VNL780 w/D13 (12.8L) Eng. (2019)	P106-HD
VNL780 w/D13 (12.8L) Eng. (2007-17)	F-F Lube (21707133).....	4 3/16 In. Steering (Nelson 84148A).....
F-F Lube (21707133).....	[2] B76 +	P528
[2] B76 +	B-P Lube (21707132).....	Diesel Exhaust Fluid (21516229) PE17000
F-F Lube (Severe Service) (4787362).....	B7409	Diesel Exhaust Fluid (82269261) PE17001
[2] B76-SS +	Severe Service F-F Lube (21707133).....	
B-P Lube (477556-5).....	[2] B76-SS +	VNL860 w/Cummins ISX 15.0 (14.9L) Eng. (2020)
B7685	Fuel/Water Separator (85120233).....	Dual-Flow Lube (4367100).....
B-P Lube (21707132).....	PF7930	BD50000
B7409	Fuel (22474709).....	Fuel/Water Separator Ele. (Fleetguard FS19764G).....
Fuel/Water Separator Ele. (85105574).....	BF46117	PF46091
PF7680	Radial Seal Air (21715813).....	Fuel/Water Separator Spin-on (85121709).....
Fuel/Water Separator Ele. (Fleetguard FF5369).....	RS4642	BF46173-O
PF7744	Cab Air (20435801).....	BF46129
Fuel/Water Separator Ele. (Fleetguard FS19765).....	PA4681	RS4642
PF7930	Air Dryer (21620181).....	PA4681
Fuel/Water Separator Spin-on (21380475).....	BA5379 +	BA5379
BF1386-O	Coolant (21937327).....	BA5379
Fuel (20430751).....	B5145	B5087
BF7814	Trans. Ele. (I-Shift) (21479106)....	BT223
Fuel (22480372).....	PT9417	P106-HD
BF46161	Trans. Spin-on (Fuller 4304827)..	Opt. Rear Axle (Meritor 3280V8394).....
Fuel (20972293).....	BT223	B233
BF7943	Steering (349619).....	VNL860 w/Cummins X15 (14.9L) Eng. (2019)
Fuel (23044511).....	P106-HD	Dual-Flow Lube (4367100).....
BF46233	Opt. Rear Axle (Meritor 3280V8394).....	BD50000
Radial Seal O. Air (20411815)....	B233	Fuel/Water Separator (85120233).....
RS4642	Diesel Exhaust Fluid (21516229) PE17000	PF7930
Radial Seal I. Air (20411816).....	VNL780 w/VE D16 Eng.	Fuel/Water Separator (Fleetguard FS19764G).....
RS4643	F-F Lube (478736).....	PF46091
Cab Air (20435801).....	[2] B76-SS +	BF46129 +
PA4681	F-F Lube (21707133).....	RS4642
Opt. Cab Air (20435801).....	[2] B76 +	Cab Air (20435801).....
[2] PA4681	B-P Lube (477556).....	PA4681
Air Dryer (3915558).....	B7685	Air Dryer (21620181).....
BA5374 +	B-P Lube (21707132).....	BA5379
Air Dryer (85110799).....	B7409	BA5379 +
BA5592 90	Fuel/Water Separator Ele. (85120233).....	Coolant (w/o Chemical) (20458771).....
Air Dryer (21620181).....	PF7930	B5145
BA5379 +	Fuel/Water Separator Ele. (Fleetguard FF5369W).....	Coolant (w/Chemical) (20458769).....
Coolant (w/o Chemical) (20458771).....	PF7744	BW5142
B5145	Fuel/Water Separator Ele. (85105574).....	PT9417
Coolant (w/Chemical) (20458769).....	PF7680	BT223
BW5142	Fuel/Water Separator Spin-on (w/Drain) (3945966).....	Trans. Ele. (20779040).....
Trans. Ele. (20779040).....	BF1329	PT9417
PT9417	Fuel/Water Separator Spin-on (Open End for Bowl) (20514654)..	Trans. Spin-on (Fuller 4304827)..
Trans. Spin-on (Fuller 4304827)..	BF1366-O	BT223
BT223		Opt. Trans. Spin-on (Fuller 17237).....
Opt. Trans. Spin-on (Fuller 17237).....		B2 +
B2 +		P106-HD
3 31/32 In. Steering (349619).....		
P106-HD		

+ See Product Guide for Variations of This Number. 90 Obsolete Pending.


Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>VOLVO</b> North America Trucks (cont'd)	<b>VOLVO</b> North America Trucks (cont'd)	<b>VOLVO</b> North America Trucks (cont'd)
VNL860 w/Cummins X15 (14.9L) Eng. (2019) (Cont'd)	VNL860 w/D13 (12.8L) Eng. (2019) (Cont'd)	VNM Series w/Cummins N14 Eng.
Air Dryer (21620181)..... BA5379 +	Opt. Rear Axle (Meritor 3280V8394)..... B233	F-F Lube (Fleetguard LF670SC).. B196 +
Trans. (Fuller 4304827)..... BT223	Diesel Exhaust Fluid (21516229) PE17000	B-P Lube (3304232)..... B7577
Steering (349619)..... P106-HD	VNL860 w/D13 (12.8L) Eng. (2020)	Fuel (154789)..... BF957-D +
Opt. Rear Axle (Meritor 3280V8394)..... B233	F-F Lube (21707133)..... [2] B76 +	Axial Seal Air (22005-5039)..... LL2685
VNL860 w/Cummins X15 (14.9L) Eng. (2020)	B-P Lube (21707132)..... B7409	Radial Seal Air (8076195)..... RS3740
Dual-Flow Lube (4367100)..... BD50000	Fuel/Water Separator (Fleetguard FS19764G)..... PF46091	Air Dryer (3915558)..... BA5374 +
Fuel/Water Separator Ele. (Fleetguard FS19764G)..... PF46091	Fuel (22474709)..... BF46117	Opt. Trans. (Fuller 17237)..... B2 +
Fuel/Water Separator Spin-on (85121709)..... BF46173-O	Radial Seal Air (21715813)..... RS4642	Steering (1742317)..... PT951
Fuel (5365988)..... BF46129	Cab Air (20435801)..... PA4681	Steering (349619)..... P106-HD
Radial Seal Air (21715813)..... RS4642	Air Dryer (21620181)..... BA5379	VNM Series w/Detroit Series 60 Eng.
Cab Air (20435801)..... PA4681	Coolant (21937327)..... B5145	Lube (23518480)..... [2] B495
Air Dryer (21620181)..... BA5379	Opt. Trans. Spin-on (Fuller 17237)..... B2	Radial Seal Air (8076195)..... RS3740
Coolant (3680434)..... B5087	Steering (349619)..... P106-HD	Air Dryer (3915558)..... BA5374 +
Trans. (Fuller 4304827)..... BT223	Opt. Rear Axle (Meritor 3280V8394)..... B233	Opt. Trans. (Fuller 17237)..... B2 +
Steering (349619)..... P106-HD	Diesel Exhaust Fluid (21516229) PE17000	VNM w/D11 (10.8L) Eng. (2010-17)
Opt. Rear Axle (Meritor 3280V8394)..... B233	VNM w/Cummins ISL-G (8.9L) Eng. (2012-16)	F-F Lube (4787362)..... [2] B76-SS +
VNL860 w/D13 (12.8L) Eng. (To 2018)	Dual-Flow Lube (3401544)..... BD7309 +	B-P Lube (477556-5)..... B7685
F-F Lube (21707133)..... [2] B76 +	Lube (Upgrade) (3401544)..... B40142 +	Fuel/Water Separator Ele. (85105574)..... PF7680
B-P Lube (21707132)..... B7409	Fuel/Water Separator (3606712)..... BF7695	Fuel/Water Separator Spin-on (Open End for Bowl) (20514654).. BF1366-O
Severe Service F-F Lube (21707133)..... [2] B76-SS +	Radial Seal Air (20411815)..... RS4642	Fuel (20430751)..... BF7814
Fuel/Water Separator (21380475)..... BF1386-O	Cab Air (20435801)..... PA4681	Fuel (22480372)..... BF46161
Fuel/Water Separator (21764964)..... BF46182-O	Air Dryer (85110799)..... BA5592 90	Fuel (20972293)..... BF7943
Fuel (22474709)..... BF46117	Coolant (w/4 Units BTA+) (3315116)..... BW5071	Radial Seal O. Air (20411815)..... RS4642
Radial Seal Air (21715813)..... RS4642	Coolant (w/12 Units BTA+) (3100307)..... BW5074	Radial Seal I. Air (20411816)..... RS4643
Cab Air (20435801)..... [2] PA4681	Opt. Trans. Spin-on (Fuller 17237)..... B2 +	Cab Air (20435801)..... PA4681
Air Dryer (21620181)..... BA5379 +	Steering (349619)..... P106-HD	Coolant (3945411)..... BW5142
Coolant (21937327)..... B5145	VNM w/Cummins ISL-G (8.9L) Eng. (2018)	Coolant (20458771)..... B5145
Trans. (21479106)..... PT9417	Dual-Flow Lube (Fleetguard LF9009)..... BD7309 +	Trans. Ele. (1521527)..... PT9417
Steering (349619)..... P106-HD	Fuel/Water Separator (Fleetguard NG5900)..... BF7695	Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT
Opt. Rear Axle (Meritor 3280V8394)..... B233	Radial Seal Air (21715813)..... RS4642	Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT
Diesel Exhaust Fluid (Filler Neck) (82269261)..... PE17001	Cab Air (20435801)..... PA4681	Opt. Trans. Spin-on (Fuller 17237)..... B2 +
Diesel Exhaust Fluid (Tank) (21516229)..... PE17000	Air Dryer (21620181)..... BA5379 +	Steering (349619)..... P106-HD
VNL860 w/D13 (12.8L) Eng. (2019)	Trans. (21479106)..... PT9417	VNM w/D11 (10.8L) Eng. (2018)
F-F Lube (21707133)..... [2] B76 +	Steering (349619)..... P106-HD	F-F Lube (21707133)..... [2] B76 +
B-P Lube (21707132)..... B7409	Opt. Rear Axle (Meritor 3280V8394)..... B233	B-P Lube (21707132)..... B7409
Severe Service F-F Lube (21707133)..... [2] B76-SS +	VNM Series w/Cummins ISM Eng.	Severe Service F-F Lube (21707133)..... [2] B76-SS +
Fuel/Water Separator (85120233)..... PF7930	Dual-Flow Lube (Fleetguard LF9001)..... BD7154 +	Fuel/Water Separator (21737499)..... PF7930
Fuel (22474709)..... BF46117	Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... BD50000	Fuel (22474709)..... BF46117
Radial Seal Air (21715813)..... RS4642	Fuel/Water Separator Ele. (Fleetguard FS19557)..... PF7749	Radial Seal Air (21715813)..... RS4642
Cab Air (20435801)..... PA4681	Radial Seal Air (8076195)..... RS3740	Cab Air (20435801)..... PA4681
Air Dryer (21620181)..... BA5379 +	Cab Air (8089705)..... PA3986	Air Dryer (21620181)..... BA5379
Coolant (21937327)..... B5145	Air Dryer (3915558)..... BA5374 +	Coolant (21937327)..... B5145
Trans. Ele. (I-Shift) (21479106)..... PT9417	Coolant (3098689)..... B5088 +	Trans. (21479106)..... PT9417
Trans. Spin-on (Fuller 4304827)..... BT223	Opt. Trans. (Fuller 17237)..... B2 +	Steering (349619)..... P106-HD
Steering (349619)..... P106-HD	Steering (349619)..... P106-HD	Opt. Rear Axle (Meritor 3280V8394)..... B233
		Diesel Exhaust Fluid (Filler Neck) (82269261)..... PE17001
		Diesel Exhaust Fluid (Tank Filter) (21516229)..... PE17000

+ See Product Guide for Variations of This Number. 90 Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



VOLVO North America Trucks (cont'd)	VOLVO North America Trucks (cont'd)	VOLVO North America Trucks (cont'd)
VNM Series w/VE D12 Eng.	VNM Series w/D13 (12.8L) Eng. (2007-17)	VNM200 w/VE D11 Eng. (Cont'd)
F-F Lube (478736)..... [2] B76-SS +	(Cont'd)	Air Dryer (11/11/08-on)
B-P Lube (477556)..... B7685	Opt. Trans. Spin-on (Fuller	(85110799)..... BA5592 90
Fuel/Water Separator Ele.	17237)..... B2 +	Coolant (w/o Chemical)
(85105574)..... PF7680	Steering (349619)..... P106-HD	(21937327)..... B5145
Fuel/Water Separator Ele.	Diesel Exhaust Fluid (21516229) PE17000	Coolant (w/8 Units BTE)
(Davco 382119)..... PF7782		(3945411)..... BW5142
Fuel/Water Separator Spin-on	VNM Series w/D13 (12.8L) Eng. (2018)	Trans. Ele. (20779040)..... PT9417
(w/Drain) (3945966)..... BF1329	F-F Lube (21707133)..... [2] B76 +	Trans. Ele. (2 In. Kit) (Allison
Fuel/Water Separator Spin-on	B-P Lube (21707132)..... B7409	29540493)..... PT9416-MPG KIT
(Open End for Bowl) (3945966)..... BF46083-O	Severe Service F-F Lube	Trans. Ele. (4 In. Kit) (Allison
Fuel/Water Separator Spin-on	(21707133)..... [2] B76-SS +	29540494)..... PT9415-MPG KIT
(w/9/16-18 SP Thd.) (3945966)..... BF1329-SP	Fuel/Water Separator	Opt. Trans. Spin-on (Fuller
Fuel/Water Separator Spin-on	(21737499)..... PF7930	17237)..... B2 +
(w/1/2-20 SP Thd.) (3945966)..... BF1339-SP +	Fuel (22474709)..... BF46117	Steering (349619)..... P106-HD
Fuel/Water Separator Spin-on	Radial Seal Air (21715813)..... RS4642	Diesel Exhaust Fluid (2010
(w/Bowl) (3945966)..... BF46072	Cab Air (20435801)..... PA4681	Emissions) (21516229)..... PE17000
Fuel/Water Separator Spin-on	Air Dryer (21620181)..... BA5379 +	
(Alliance ABPN122R50551)..... BF46016-O	Coolant (21937327)..... B5145	VNM200 w/VE D12 Eng.
Fuel (20430751)..... BF7814	Trans. (21479106)..... PT9417	Dual-Flow Lube (Fleetguard
Fuel (22480372)..... BF46161	Steering (349619)..... P106-HD	LF9001)..... BD7154 +
Fuel (8193841)..... BF7653	Opt. Rear Axle (Meritor	Dual-Flow Lube (Upgrade)
Single Radial Seal Air (8076195) RS3740	3280V8394)..... B233	(Fleetguard LF14000NN)..... BD50000
Radial Seal O. Air (20411815)..... RS4642	Diesel Exhaust Fluid (Filler Neck)	Fuel/Water Separator
Radial Seal I. Air (20411816)..... RS4643	(82269261)..... PE17001	(85105574)..... PF7680
Cab Air (8089705)..... PA3986	Diesel Exhaust Fluid (Tank)	Fuel (20430751)..... BF7814
Cab Air (20435801)..... PA4681	(21516229)..... PE17000	Fuel (22480372)..... BF46161
Air Dryer (3915558)..... BA5374 +	VNM200 w/VE D11 Eng.	Some Fuel (8193841)..... BF7653
4 7/16 In. Coolant (20458771)..... B5145	F-F Lube (4787362)..... [2] B76-SS +	Radial Seal O. Air (20411815)..... RS4642
5 7/16 In. Coolant (3969696)..... B5144	F-F Lube (21707133)..... [2] B76 +	Radial Seal I. Air (20411816)..... RS4643
Trans. Ele. (1521527)..... PT9417	B-P Lube (477556-5)..... B7685	Cab Air (20435801)..... PA4681
Opt. Trans. Spin-on (Fuller	B-P Lube (21707132)..... B7409	Coolant (20458771)..... B5145
17237)..... B2 +	Fuel/Water Separator Ele.	Trans. Ele. (1521527)..... PT9417
Steering (349619)..... P106-HD	(85105574)..... PF7680	Opt. Trans. Spin-on (Fuller
	Fuel/Water Separator Spin-on	17237)..... B2 +
VNM Series w/D13 (12.8L) Eng. (2007-17)	(Open End for Bowl) (20514654)..... BF1366-O	Steering (349619)..... P106-HD
F-F Lube (21707133)..... [2] B76 +	Fuel/Water Separator Spin-on	
F-F Lube (4787362)..... [2] B76-SS +	(21380475)..... BF1386-O	VNM200 w/D13 (12.8L) Eng. (2007-17)
B-P Lube (477556-5)..... B7685	Fuel/Water Separator Spin-on	F-F Lube (21707133)..... [2] B76 +
B-P Lube (21707132)..... B7409	(20853583)..... BF1388-O	B-P Lube (4775565)..... B7685
Fuel/Water Separator Ele.	Fuel/Water Separator Spin-on	B-P Lube (21707132)..... B7409
(21737499)..... PF7930	(w/Drain) (3945966)..... BF1329	Severe Service F-F Lube
Fuel/Water Separator Ele.	Fuel/Water Separator Spin-on	(21707133)..... [2] B76-SS +
(Fleetguard FF5369)..... PF7744	(Open End for Bowl) (3945966)..... BF46083-O	Fuel/Water Separator Ele.
Fuel/Water Separator Spin-on	Fuel/Water Separator Spin-on	(21737499)..... PF7930
(Open End for Bowl) (20514654)..... BF1366-O	(w/9/16-18 SP Thd.) (3945966)..... BF1329-SP	Fuel/Water Separator Spin-on
Fuel Spin-on (20430751)..... BF7814	Fuel/Water Separator Spin-on	(Open End for Bowl) (20514654)..... BF1366-O
Fuel Spin-on (22480372)..... BF46161	(w/1/2-20 SP Thd.) (3945966)..... BF1339-SP +	Fuel (23044511)..... BF46233
Fuel (23044511)..... BF46233	Fuel/Water Separator Spin-on	Fuel (20976003)..... BF7814
Radial Seal O. Air (21715813)..... RS4642	(w/Bowl) (3945966)..... BF46072	Fuel (21879886)..... BF46233
Opt. Radial Seal I. Air	Fuel (20430751)..... BF7814	Radial Seal Air (21715813)..... RS4642
(20411816)..... RS4643	Fuel (22480372)..... BF46161	Cab Air (20435801)..... PA4681
Cab Air (20435801)..... PA4681	S. Fuel (20972293)..... BF7943	Air Dryer (Wabco R950068)..... BA5379 +
Air Dryer (Wabco R950068)..... BA5379 +	Radial Seal O. Air (21715813)..... RS4642	Coolant (51937327)..... B5145
Coolant (51937327)..... B5145	Opt. Radial Seal I. Air	Trans. Ele. (1521527)..... PT9417
Trans. Ele. (1521527)..... PT9417	(20411816)..... RS4643	Steering (349619)..... P106-HD
Trans. Ele. (2 In. Kit) (Allison	Cab Air (20435801)..... PA4681	Diesel Exhaust Fluid (21516229) PE17000
29540493)..... PT9416-MPG KIT	Air Dryer (To 11/10/08) (Wabco	
Trans. Ele. (4 In. Kit) (Allison	3915558)..... BA5374 +	
29540494)..... PT9415-MPG KIT		

+ See Product Guide for Variations of This Number. 90 Obsolete Pending.

Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

VOLVO North America Trucks (cont'd)	VOLVO North America Trucks (cont'd)	VOLVO North America Trucks (cont'd)
VNM200 w/D13 (12.8L) Eng. (2018)	VNM630 w/Cummins ISX Eng. (Cont'd)	VNM630 w/VE D16 Eng. (Cont'd)
F-F Lube (21707133)..... [2] B76 +	Fuel/Water Separator Spin-on	Coolant (20458771)..... B5145
B-P Lube (21707132)..... B7409	(w/Drain & Sensor Port)	Trans. Ele. (1521527)..... PT9417
Severe Service F-F Lube	(85104856)..... BF1355-SP	Trans. Ele. (2 In. Kit) (Allison
(21707133)..... [2] B76-SS +	Fuel/Water Separator Spin-on	29540493)..... PT9416-MPG KIT
Fuel (22474709)..... BF46117	(Open End for Bowl) (85104856)..	Trans. Ele. (4 In. Kit) (Allison
Radial Seal Air (21715813)..... RS4642	Fuel/Water Separator Ele.	29540494)..... PT9415-MPG KIT
Cab Air (20435801)..... [2] PA4681	(Davco 382119)..... PF7782	Trans. Spin-on (Fuller 4304827)..
Air Dryer (21620181)..... BA5379 +	Fuel (4920586)..... BF7766	Opt. Trans. Spin-on (Fuller
Coolant (21937327)..... B5145	Radial Seal Air (20882320)..... RS4642	17237)..... B2 +
Trans. (21479106)..... PT9417	Cab Air (20435801)..... PA4681	Steering (349619)..... P106-HD
Steering (349619)..... P106-HD	Air Dryer (Wabco R950011)..... BA5374 +	VNR w/Cummins ISL-G (8.9L) Eng. (2019)
Opt. Rear Axle (Meritor	Breather (3683918)..... CV15000	Lube (Fleetguard LF9009)..... B40142
3280V8394)..... B233	Coolant (w/o Chemical)	Fuel/Water Separator
Diesel Exhaust Fluid (Filler Neck)	(Fleetguard WF2127)..... B5087	(Fleetguard NG5900)..... BF7695
(82269261)..... PE17001	Coolant (w/Chemical)	Radial Seal O. Air (21715813)..... RS4642
Diesel Exhaust Fluid (Tank)	(Fleetguard WF2126)..... BW5086	Radial Seal I. Air (20411816)..... RS4643
(21516229)..... PE17000	Trans. Ele. (2 In. Kit) (Allison	Cab Air (20435801)..... [2] PA4681
VNM420 w/Cummins M11 Eng.	29548987)..... PT9416-MPG KIT	Air Dryer (Wabco R950068A)..... BA5379
Dual-Flow Lube..... BD103 +	Trans. Ele. (4 In. Kit) (Allison	Coolant (w/4 Units BTA +)
Fuel/Water Separator..... BF1259	29548988)..... PT9415-MPG KIT	(Fleetguard WF2071)..... BW5071
VNM430 w/VE D11 Eng.	Trans. Spin-on (Fuller 4304827)..	Coolant (w/12 Units BTA+)
F-F Lube (4787362)..... [2] B76-SS +	Opt. Trans. Spin-on (Fuller	(Fleetguard WF2074)..... BW5074
B-P Lube (477556-5)..... B7685	17237)..... B2 +	Steering (349619)..... P106-HD
Fuel/Water Separator	Steering (349619)..... P106-HD	Opt. Rear Axle (Meritor
(85105574)..... PF7680	VNM630 w/VE D11 Eng.	3280V8394)..... B233
Fuel (20972293)..... BF7943	F-F Lube (4787362)..... [2] B76-SS +	VNR w/Cummins ISL-G (8.9L) Eng. (2020)
Radial Seal Air (20411815)..... RS4642	B-P Lube (477556-5)..... B7685	Lube (Fleetguard LF9009)..... B40142
Cab Air (20435801)..... PA4681	Fuel/Water Separator	Fuel (Fleetguard NG5900)..... BF7695
Air Dryer (To 11/10/08) (950011)..... BA5374 +	(85105574)..... PF7680	Radial Seal Air (21715813)..... RS4642
Air Dryer (11/11/08-on)	Fuel (20972293)..... BF7943	Cab Air (20435801)..... PA4681
(85110799)..... BA5592 90	Radial Seal Air (20411815)..... RS4642	Air Dryer (Bendix 107794PG)..... BA5377
Coolant (20458771)..... B5145	Cab Air (20435801)..... PA4681	Opt. Rear Axle (Meritor
Trans. Ele. (1521527)..... PT9417	Air Dryer (To 11/10/08)	3280V8394)..... B233
Trans. Ele. (2 In. Kit) (Allison	(3915558)..... BA5374 +	VNR w/Cummins ISL-G (8.9L) Eng. (2021)
29540493)..... PT9416-MPG KIT	Air Dryer (11/11/08-on)	Radial Seal Air (21715813)..... RS4642
Trans. Ele. (4 In. Kit) (Allison	(85110799)..... BA5592 90	Opt. Rear Axle (Meritor
29540494)..... PT9415-MPG KIT	Coolant (20458771)..... B5145	3280V8394)..... B233
Trans. Spin-on (Fuller 4304827)..	Trans. Ele. (1521527)..... PT9417	VNR w/D11 (10.8L) Eng. (2018)
Opt. Trans. Spin-on (Fuller	Trans. Ele. (2 In. Kit) (Allison	F-F Lube (21707133)..... [2] B76 +
17237)..... B2 +	29540493)..... PT9416-MPG KIT	B-P Lube (21707132)..... B7409
Steering (349619)..... P106-HD	Trans. Ele. (4 In. Kit) (Allison	Severe Service F-F Lube
VNM430 w/VE D16 Eng.	29540494)..... PT9415-MPG KIT	(21707133)..... [2] B76-SS +
Trans. Ele. (1521527)..... PT9417	Trans. Spin-on (Fuller 4304827)..	Fuel/Water Separator
Trans. Ele. (2 In. Kit) (Allison	Opt. Trans. Spin-on (Fuller	(21737499)..... PF7930
29540493)..... PT9416-MPG KIT	17237)..... B2 +	Fuel (22474709)..... BF46117
Trans. Ele. (4 In. Kit) (Allison	Steering (349619)..... P106-HD	Radial Seal Air (21715813)..... RS4642
29540494)..... PT9415-MPG KIT	VNM630 w/VE D16 Eng.	Cab Air (20435801)..... PA4681
Trans. Spin-on (Fuller 4304827)..	F-F Lube (478736)..... [2] B76-SS +	Air Dryer (21620181)..... BA5379 +
Opt. Trans. Spin-on (Fuller	B-P Lube (477556)..... B7685	Coolant (21937327)..... B5145
17237)..... B2 +	Fuel/Water Separator	Trans. (21479106)..... PT9417
VNM630 w/Cummins ISX Eng.	(85105574)..... PF7680	Opt. Rear Axle (Meritor
Dual-Flow Lube (3101869)..... BD7154 +	Fuel (20972293)..... BF7943	3280V8394)..... B233
Dual-Flow Lube (Upgrade)	Radial Seal Air (20411815)..... RS4642	Diesel Exhaust Fluid (Filler Neck)
(Fleetguard LF14000NN)..... BD50000	Cab Air (20435801)..... PA4681	(82269261)..... PE17001
Fuel/Water Separator Spin-on	Air Dryer (To 11/10/08)	Diesel Exhaust Fluid (Tank Filter)
(w/Drain) (85104856)..... BF1355	(3915558)..... BA5374 +	(21516229)..... PE17000
	Air Dryer (11/11/08-on)	
	(85110799)..... BA5592 90	

+ See Product Guide for Variations of This Number. 90 Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

VOLVO North America Trucks (cont'd)	VOLVO North America Trucks (cont'd)	VOLVO North America Trucks (cont'd)
VNR w/D11 (10.8L) Eng. (2019)	VNR w/D13 (12.8L) Eng. (2018)	VNR w/D13 (12.8L) Eng. (2020) (Cont'd)
F-F Lube (21707133)..... [2] B76 +	F-F Lube (21707133)..... [2] B76 +	Coolant (21937327)..... B5145
B-P Lube (21707132)..... B7409	B-P Lube (21707132)..... B7409	Trans. Spin-on (Fuller 4304827).. BT223
Severe Service F-F Lube (21707133)..... [2] B76-SS +	Severe Service F-F Lube (21707133)..... [2] B76-SS +	Opt. Trans. Spin-on (Fuller 17237)..... B2
Fuel/Water Separator (Fleetguard 85120233)..... PF7930	Fuel/Water Separator (21737499)..... PF7930	Opt. Rear Axle (Meritor 3280V8394)..... B233
Fuel (22474709)..... BF46117	Fuel (22474709)..... BF46117	VNR w/D13 (12.8L) Eng. (2021)
Radial Seal O. Air (21715813)..... RS4642	Radial Seal Air (21715813)..... RS4642	F-F Lube (21707133)..... [2] B76
Radial Seal I. Air (20411816)..... RS4643	Cab Air (20435801)..... PA4681	B-P Lube (21707132)..... B7409
Cab Air (20435801)..... [2] PA4681	Air Dryer (21620181)..... BA5379 +	F-F Lube (23151592)..... [2] B40153
Air Dryer (Wabco R950068A)..... BA5379 +	Coolant (21937327)..... B5145	Fuel (23856886)..... BF46117
Coolant (21937327)..... B5145	Trans. (21479106)..... PT9417	Radial Seal Air (21715813)..... RS4642
Trans. Ele. (21479106)..... PT9417	Opt. Rear Axle (Meritor 3280V8394)..... B233	Opt. Rear Axle (Meritor 3280V8394)..... B233
Opt. Trans. Spin-on (Fuller 17237)..... B2 +	Diesel Exhaust Fluid (Filler Neck) (82269261)..... PE17001	VNR300 w/D11 (10.8L) Eng. (2018)
Steering (349619)..... P106-HD	Diesel Exhaust Fluid (Tank Filter) (21516229)..... PE17000	F-F Lube (21707133)..... [2] B76 +
Opt. Rear Axle (Meritor 3280V8394)..... B233	VNR w/D13 (12.8L) Eng. (2019)	B-P Lube (21707132)..... B7409
Diesel Exhaust Fluid (21516229) PE17000	F-F Lube (21707133)..... [2] B76 +	Severe Service F-F Lube (21707133)..... [2] B76-SS +
VNR w/D11 (10.8L) Eng. (2020)	B-P Lube (21707132)..... B7409	Fuel/Water Separator (21737499)..... PF7930
F-F Lube (21707133)..... [2] B76	Severe Service F-F Lube (21707133)..... [2] B76-SS +	Fuel (22474709)..... BF46117
B-P Lube (21707132)..... B7409	Fuel/Water Separator (85120233)..... PF7930	Radial Seal Air (21715813)..... RS4642
Severe Service F-F Lube (21707133)..... [2] B76-SS +	Fuel (22474709)..... BF46117	Cab Air (20435801)..... PA4681
Fuel/Water Separator (Open End for Bowl) (3945966)..... BF46083-O	Radial Seal O. Air (21715813)..... RS4642	Air Dryer (21620181)..... BA5379 +
Fuel/Water Separator (w/Bowl) (3945966)..... BF46072	Radial Seal I. Air (20411816)..... RS4643	Coolant (21937327)..... B5145
Fuel/Water Separator (SP Thd. 1/2-20) (3945966)..... BF1339-SP	Cab Air (20435801)..... [2] PA4681	Trans. (21479106)..... PT9417
Fuel/Water Separator (SP Thd. 9/16-18) (3945966)..... BF1329-SP	Air Dryer (Wabco R950068A)..... BA5379 +	Opt. Rear Axle (Meritor 3280V8394)..... B233
Fuel/Water Separator (w/Drain) (3945966)..... BF1329	Coolant (21937327)..... B5145	Diesel Exhaust Fluid (Filler Neck) (82269261)..... PE17001
Fuel (22474709)..... BF46117	Trans. (I-Shift) (21479106)..... PT9417	Diesel Exhaust Fluid (Tank Filter) (21516229)..... PE17000
Radial Seal Air (21715813)..... RS4642	Steering (349619)..... P106-HD	VNR300 w/D11 (10.8L) Eng. (2019)
Cab Air (20435801)..... PA4681	Opt. Rear Axle (Meritor 3280V8394)..... B233	F-F Lube (21707133)..... [2] B76 +
Air Dryer (Bendix 107794PG)..... BA5377	Diesel Exhaust Fluid (Pump Filter) (21516229)..... PE17000	B-P Lube (21707132)..... B7409
Coolant (21937327)..... B5145	Diesel Exhaust Fluid (Tank Filter) (82269261)..... PE17001	Severe Service F-F Lube (21707133)..... [2] B76-SS +
Opt. Trans. Spin-on (Fuller 17237)..... B2	VNR w/D13 (12.8L) Eng. (2020)	Fuel/Water Separator (21737499)..... PF7930
Opt. Rear Axle (Meritor 3280V8394)..... B233	F-F Lube (21707133)..... [2] B76 +	Fuel (22474709)..... BF46117
VNR w/D11 (10.8L) Eng. (2021)	B-P Lube (21707132)..... B7409	Radial Seal O. Air (21715813)..... RS4642
F-F Lube (21707133)..... [2] B76	Fuel/Water Separator (Fleetguard FS19764G)..... PF46091	Radial Seal I. Air (20411816)..... RS4643
B-P Lube (21707132)..... B7409	Fuel/Water Separator (Open End for Bowl) (Racor R90P)..... BF46083-O	Cab Air (20435801)..... [2] PA4681
Fuel/Water Separator (Fleetguard FS19764G)..... PF46091	Fuel/Water Separator (Sensor Port Thd. 1/2-20) (Racor R90P)..... BF1339-SP	Air Dryer (Wabco R950068A)..... BA5379 +
Fuel/Water Separator (Fleetguard FS19765G)..... PF46094	Fuel/Water Separator (Sensor Port Thd. 9/16-18) (Racor R90P)..... BF1329-SP	Coolant (21937327)..... B5145
Fuel (23856886)..... BF46117	Fuel/Water Separator (w/Bowl) (Racor R90P)..... BF46072	Trans. Ele. (21479106)..... PT9417
Radial Seal Air (21715813)..... RS4642	Fuel/Water Separator (w/Drain) (Racor R90P)..... BF1329	Opt. Trans. Spin-on (Fuller 17237)..... B2 +
Coolant (21937327)..... B5145	Fuel (22474709)..... BF46117	Steering (349619)..... P106-HD
Opt. Rear Axle (Meritor 3280V8394)..... B233	Radial Seal Air (21715813)..... RS4642	Opt. Rear Axle (Meritor 3280V8394)..... B233
	Cab Air (20435801)..... PA4681	Diesel Exhaust Fluid (21516229) PE17000
	Air Dryer (Bendix 107794PG)..... BA5377	VNR300 w/D11 (10.8L) Eng. (2020)
		F-F Lube (21707133)..... [2] B76
		B-P Lube (21707132)..... B7409
		Severe Service F-F Lube (21707133)..... [2] B76-SS +

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>VOLVO</b> North America Trucks (cont'd)	<b>VOLVO</b> North America Trucks (cont'd)	<b>VOLVO</b> North America Trucks (cont'd)
VNR300 w/D11 (10.8L) Eng. (2020) (Cont'd)	VNR300 w/D13 (12.8L) Eng. (2020)	VNR400 w/D13 (12.8L) Eng. (To 2018) (Cont'd)
Fuel/Water Separator (Open End for Bowl) (3945966)..... <b>BF46083-O</b>	F-F Lube (21707133)..... <b>[2] B76 +</b>	Diesel Exhaust Fluid (Tank) (21516229)..... <b>PE17000</b>
Fuel/Water Separator (w/Bowl) (3945966)..... <b>BF46072</b>	B-P Lube (21707132)..... <b>B7409</b>	VNR400 w/D13 (12.8L) Eng. (2019)
Fuel/Water Separator (SP Thd. 1/2-20) (3945966)..... <b>BF1339-SP</b>	Fuel/Water Separator (Fleetguard FS19764G)..... <b>PF46091</b>	F-F Lube (21707133)..... <b>B76 +</b>
Fuel/Water Separator (SP Thd. 9/16-18) (3945966)..... <b>BF1329-SP</b>	Fuel/Water Separator (Open End for Bowl) (Racor R90P)..... <b>BF46083-O</b>	B-P Lube (21707132)..... <b>B7409</b>
Fuel/Water Separator (w/Drain) (3945966)..... <b>BF1329</b>	Fuel/Water Separator (Sensor Port Thd. 1/2-20) (Racor R90P).... <b>BF1339-SP</b>	Severe Service F-F Lube (21707133)..... <b>B76-SS +</b>
Fuel (22474709)..... <b>BF46117</b>	Fuel/Water Separator (Sensor Port Thd. 9/16-18) (Racor R90P).. <b>BF1329-SP</b>	Fuel/Water Separator (85120233)..... <b>PF7930</b>
Radial Seal Air (21715813)..... <b>RS4642</b>	Fuel/Water Separator (w/Bowl) (Racor R90P)..... <b>BF46072</b>	Fuel (22474709)..... <b>BF46117</b>
Cab Air (20435801)..... <b>PA4681</b>	Fuel/Water Separator (w/Drain) (Racor R90P)..... <b>BF1329</b>	Radial Seal O. Air (21715813).... <b>RS4642</b>
Air Dryer (Bendix 107794PG)..... <b>BA5377</b>	Fuel (22474709)..... <b>BF46117</b>	Radial Seal I. Air (20411816)..... <b>RS4643</b>
Coolant (21937327)..... <b>B5145</b>	Radial Seal Air (21715813)..... <b>RS4642</b>	Cab Air (20435801)..... <b>[2] PA4681</b>
Opt. Trans. Spin-on (Fuller 17237)..... <b>B2</b>	Cab Air (20435801)..... <b>PA4681</b>	Air Dryer (Wabco R950068A)..... <b>BA5379 +</b>
Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	Air Dryer (Bendix 107794PG)..... <b>BA5377</b>	Coolant (21937327)..... <b>B5145</b>
VNR300 w/D13 (12.8L) Eng. (To 2018)	Coolant (21937327)..... <b>B5145</b>	Trans. (I-Shift) (21479106)..... <b>PT9417</b>
F-F Lube (21707133)..... <b>[2] B76 +</b>	Trans. Spin-on (Fuller 4304827).. <b>BT223</b>	Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>
B-P Lube (21707132)..... <b>B7409</b>	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2</b>	Diesel Exhaust Fluid (Pump Filter) (21516229)..... <b>PE17000</b>
Severe Service F-F Lube (21707133)..... <b>[2] B76-SS +</b>	Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	Diesel Exhaust Fluid (Tank Filter) (82269261)..... <b>PE17001</b>
Fuel/Water Separator (21737499)..... <b>PF7930</b>	VNR400 w/D11 (10.8L) Eng. (2018)	VNR400 w/D13 (12.8L) Eng. (2020)
Fuel (22474709)..... <b>BF46117</b>	F-F Lube (21707133)..... <b>[2] B76 +</b>	F-F Lube (21707133)..... <b>[2] B76 +</b>
Radial Seal Air (21715813)..... <b>RS4642</b>	B-P Lube (21707132)..... <b>B7409</b>	B-P Lube (21707132)..... <b>B7409</b>
Cab Air (20435801)..... <b>PA4681</b>	Severe Service F-F Lube (21707133)..... <b>[2] B76-SS +</b>	Fuel/Water Separator (Fleetguard FS19764G)..... <b>PF46091</b>
Air Dryer (21620181)..... <b>BA5379 +</b>	Fuel/Water Separator (21737499)..... <b>PF7930</b>	Fuel (22474709)..... <b>BF46117</b>
Coolant (21937327)..... <b>B5145</b>	Fuel (22474709)..... <b>BF46117</b>	Radial Seal Air (21715813)..... <b>RS4642</b>
Trans. (21479106)..... <b>PT9417</b>	Radial Seal Air (21715813)..... <b>RS4642</b>	Cab Air (20435801)..... <b>PA4681</b>
Diesel Exhaust Fluid (Filler Neck) (82269261)..... <b>PE17001</b>	Cab Air (20435801)..... <b>PA4681</b>	Air Dryer (Bendix 107794PG)..... <b>BA5377</b>
Diesel Exhaust Fluid (Tank) (21516229)..... <b>PE17000</b>	Air Dryer (21620181)..... <b>BA5379 +</b>	Coolant (21937327)..... <b>B5145</b>
VNR300 w/D13 (12.8L) Eng. (2019)	Coolant (21937327)..... <b>B5145</b>	Trans. Spin-on (Fuller 4304827).. <b>BT223</b>
F-F Lube (21707133)..... <b>[2] B76 +</b>	Trans. (21479106)..... <b>PT9417</b>	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2</b>
B-P Lube (21707132)..... <b>B7409</b>	Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>
Severe Service F-F Lube (21707133)..... <b>[2] B76-SS +</b>	Diesel Exhaust Fluid (Filler Neck) (82269261)..... <b>PE17001</b>	VNR640 w/D11 (10.8L) Eng. (2019)
Fuel/Water Separator (85120233)..... <b>PF7930</b>	Diesel Exhaust Fluid (Tank Filter) (21516229)..... <b>PE17000</b>	F-F Lube (21707133)..... <b>[2] B76 +</b>
Fuel (22474709)..... <b>BF46117</b>	VNR400 w/D13 (12.8L) Eng. (To 2018)	B-P Lube (21707132)..... <b>B7409</b>
Radial Seal O. Air (21715813).... <b>RS4642</b>	F-F Lube (21707133)..... <b>[2] B76 +</b>	Severe Service F-F Lube (21707133)..... <b>[2] B76-SS +</b>
Radial Seal I. Air (20411816)..... <b>RS4643</b>	B-P Lube (21707132)..... <b>B7409</b>	Fuel/Water Separator (Fleetguard FS19765)..... <b>PF7930</b>
Cab Air (20435801)..... <b>[2] PA4681</b>	Severe Service F-F Lube (21707133)..... <b>[2] B76-SS +</b>	Fuel (22474709)..... <b>BF46117</b>
Air Dryer (Wabco R950068A)..... <b>BA5379 +</b>	Fuel/Water Separator (21737499)..... <b>PF7930</b>	Radial Seal O. Air (21715813).... <b>RS4642</b>
Coolant (21937327)..... <b>B5145</b>	Fuel (22474709)..... <b>BF46117</b>	Radial Seal I. Air (20411816)..... <b>RS4643</b>
Trans. (I-Shift) (21479106)..... <b>PT9417</b>	Radial Seal Air (21715813)..... <b>RS4642</b>	Cab Air (20435801)..... <b>[2] PA4681</b>
Steering (349619)..... <b>P106-HD</b>	Cab Air (20435801)..... <b>PA4681</b>	Air Dryer (Wabco R950068A)..... <b>BA5379 +</b>
Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	Air Dryer (21620181)..... <b>BA5379 +</b>	Coolant (21937327)..... <b>B5145</b>
Diesel Exhaust Fluid (Pump Filter) (21516229)..... <b>PE17000</b>	Coolant (21937327)..... <b>B5145</b>	Trans. (I-Shift) (21479106)..... <b>PT9417</b>
Diesel Exhaust Fluid (Tank Filter) (82269261)..... <b>PE17001</b>	Trans. (21479106)..... <b>PT9417</b>	Steering (349619)..... <b>P106-HD</b>
	Diesel Exhaust Fluid (Filler Neck) (82269261)..... <b>PE17001</b>	Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>
		Diesel Exhaust Fluid (21516229) <b>PE17000</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

VOLVO North America Trucks (cont'd)	VOLVO North America Trucks (cont'd)	VOLVO North America Trucks (cont'd)
VNR640 w/D13 (12.8L) Eng. (2018)	VNR640 w/D13 (12.8L) Eng. (2020) (Cont'd)	VT Series w/Cummins ISX Eng. (To 2007)
F-F Lube (21707133)..... [2] B76 +	Coolant (21937327)..... B5145	Dual-Flow Lube (3101869)..... BD7154 +
B-P Lube (21707132)..... B7409	Trans. Spin-on (Fuller 4304827).. BT223	Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... BD50000
Severe Service F-F Lube (21707133)..... [2] B76-SS +	Opt. Trans. Spin-on (Fuller 17237)..... B2	Fuel/Water Separator Spin-on (w/Drain) (85104856)..... BF1355
Fuel/Water Separator (21737499)..... PF7930	Opt. Rear Axle (Meritor 3280V8394)..... B233	Fuel/Water Separator Spin-on (w/Drain & Sensor Port) (85104856)..... BF1355-SP
Fuel (22474709)..... BF46117	VNX w/Cummins ISX 15.0 (14.9L) Eng. (2021)	Fuel/Water Separator Spin-on (Open End for Bowl) (85104856).. BF1355-O
Radial Seal Air (21715813)..... RS4672	Lube (5575298)..... B40145	Fuel/Water Separator Ele. (85105574)..... PF7680
Cab Air (20435801)..... PA4681	Fuel (5365988)..... BF46129	Fuel (Fleetguard FF2200)..... BF7766
Air Dryer (21620181)..... BA5379 +	Trans. (Fuller 4304827)..... BT223	Radial Seal O. Air (20411815).... RS4642
Coolant (21937327)..... B5145	VNX w/Cummins ISX 15.0 (14.9L) Eng. (2022)	Radial Seal I. Air (20411816).... RS4643
Trans. (21479106)..... PT9417	Lube (5575298)..... B40145	Cab Air (20435801)..... PA4681
Opt. Rear Axle (Meritor 3280V8394)..... B233	Fuel (5575143)..... BF46248	Air Dryer (3915558)..... BA5374 +
Diesel Exhaust Fluid (Filler Neck) (82269261)..... PE17001	Coolant (3680434)..... B5087	Coolant (Fleetguard WF2127)..... B5087
Diesel Exhaust Fluid (Tank Filter) (21516229)..... PE17000	VNX w/D13 (12.8L) Eng. (2019)	Opt. Trans. Spin-on (Fuller 17237)..... B2 +
VNR640 w/D13 (12.8L) Eng. (2019)	F-F Lube (21707133)..... [2] B76 +	Trans. Spin-on (Fuller 4304827).. BT223
F-F Lube (21707133)..... [2] B76 +	B-P Lube (21707132)..... B7409	Steering (349619)..... P106-HD
B-P Lube (21707132)..... B7409	Fuel (22474709)..... BF46117	VT Series w/Cummins ISX Eng. (2007-on)
Severe Service F-F Lube (21707133)..... [2] B76-SS +	Coolant (21937327)..... B5145	Dual-Flow Lube (3101869)..... BD7154 +
Fuel/Water Separator (85120233)..... PF7930	Diesel Exhaust Fluid (Pump) (21516229)..... PE17000	Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... BD50000
Fuel (22474709)..... BF46117	Diesel Exhaust Fluid (Tank Strainer) (82269261)..... PE17001	Fuel/Water Separator Spin-on (w/Drain) (85104856)..... BF1355
Radial Seal O. Air (21715813).... RS4642	VNX w/D13 (12.8L) Eng. (2020)	Fuel/Water Separator Spin-on (w/Drain & Sensor Port) (85104856)..... BF1355-SP
Radial Seal I. Air (20411816).... RS4643	F-F Lube (21707133)..... [2] B76	Fuel/Water Separator Spin-on (Open End for Bowl) (85104856).. BF1355-O
Cab Air (20435801)..... [2] PA4681	B-P Lube (21707132)..... B7409	Fuel/Water Separator Ele. (85105574)..... PF7680
Air Dryer (Wabco R950068A)..... BA5379 +	Fuel (22474709)..... BF46117	Fuel (Fleetguard FF2200)..... BF7766
Coolant (21937327)..... B5145	Coolant (21937327)..... B5145	Radial Seal O. Air (20411815).... RS4642
Trans. (I-Shift) (21479106)..... PT9417	VNX w/D13 (12.8L) Eng. (2021)	Radial Seal I. Air (20411816).... RS4643
Steering (349619)..... P106-HD	Lube (23151592)..... [2] B40153	Cab Air (20435801)..... PA4681
Opt. Rear Axle (Meritor 3280V8394)..... B233	F-F Lube (Some) (21707133)..... [2] B76 +	Air Dryer (3915558)..... BA5374 +
Diesel Exhaust Fluid (Pump Filter) (21516229)..... PE17000	B-P Lube (21707132)..... B7409	Breather (3683918)..... CV15000
Diesel Exhaust Fluid (Tank Filter) (82269261)..... PE17001	Fuel (23856886)..... BF46117	Coolant (Fleetguard WF2127)..... B5087
VNR640 w/D13 (12.8L) Eng. (2020)	VNX w/D16 (16.1L) Eng. (2015)	Opt. Trans. Spin-on (Fuller 17237)..... B2 +
F-F Lube (21707133)..... [2] B76 +	F-F Lube (21707133)..... [2] B76 +	Trans. Spin-on (Fuller 4304827).. BT223
B-P Lube (21707132)..... B7409	B-P Lube (21707132)..... B7409	Steering (349619)..... P106-HD
Fuel/Water Separator (Fleetguard FS19764G)..... PF46091	Severe Service F-F Lube (21707133)..... [2] B76-SS +	VT Series w/VE D16 Eng.
Fuel/Water Separator (Open End for Bowl) (Racor R90P)..... BF46083-O	Fuel/Water Separator Ele. (Fleetguard FS19765)..... PF7930	F-F Lube (478736)..... [2] B76-SS +
Fuel/Water Separator (Sensor Port Thd. 1/2-20) (Racor R90P)... BF1339-SP	Fuel (23044511)..... BF46233	B-P Lube (477556)..... B7685
Fuel/Water Separator (Sensor Port Thd. 9/16-18) (Racor R90P).. BF1329-SP	Radial Seal Air (21715813)..... RS4642	Fuel/Water Separator (Open End for Bowl) (20514654)..... BF1366-O
Fuel/Water Separator (w/Bowl) (Racor R90P)..... BF46072	Cab Air (20435801)..... PA4681	Fuel (20430751)..... BF7814
Fuel/Water Separator (w/Drain) (Racor R90P)..... BF1329	Air Dryer (85110799)..... BA5592 <sup>90</sup>	Fuel (22480372)..... BF46161
Fuel (22474709)..... BF46117	Air Dryer (3098953)..... BA5374 +	Radial Seal O. Air (20411815).... RS4642
Radial Seal Air (21715813)..... RS4642	Coolant (21937327)..... B5145	Radial Seal I. Air (20411816).... RS4643
Cab Air (20435801)..... PA4681	Trans. Ele. (1521527)..... PT9417	Cab Air (20435801)..... PA4681
Air Dryer (Bendix 107794PG)..... BA5377	Trans. Spin-on (Fuller 4304827).. BT223	Air Dryer (3915558)..... BA5374 +
	Opt. Trans. Spin-on (Fuller 17237)..... B2 +	
	Steering (349619)..... P106-HD	
	Diesel Exhaust Fluid (21516229) PE17000	
	Diesel Exhaust Fluid (82269261) PE17001	

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.

Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>VOLVO</b> North America Trucks (cont'd)	<b>VOLVO</b> North America Trucks (cont'd)	<b>VOLVO</b> North America Trucks (cont'd)
VT Series w/VE D16 Eng. (Cont'd)	VT800 w/VE D16 Eng. (Cont'd)	VT880 w/VE D16 Eng.
Coolant (w/8 Units BTE) (3945411)..... <b>BW5142</b>	Steering (349619)..... <b>P106-HD</b>	F-F Lube (478736-2)..... [2] <b>B76-SS +</b>
Steering (349619)..... <b>P106-HD</b>	VT830 w/Cummins ISX Eng.	B-P Lube (477556)..... <b>B7685</b>
VT800 w/Cummins ISX Eng.	Dual-Flow Lube (3101869)..... <b>BD7154 +</b>	Fuel/Water Separator Ele. (85105574)..... <b>PF7680</b>
Dual-Flow Lube (3101869)..... <b>BD7154 +</b>	Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>	Fuel/Water Separator Ele. (Davco 382119)..... <b>PF7782</b>
Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>	Fuel/Water Separator (w/Drain) (85104856)..... <b>BF1355</b>	Fuel/Water Separator Ele. (Fleetguard FF5369W)..... <b>PF7744</b>
Fuel/Water Separator Spin-on (w/Drain) (85104856)..... <b>BF1355</b>	Fuel/Water Separator (w/Drain & Sensor Port) (85104856)..... <b>BF1355-SP</b>	Fuel/Water Separator (Open End for Bowl) (Racor R90P)..... <b>BF46083-O</b>
Fuel/Water Separator Spin-on (w/Drain & Sensor Port) (85104856)..... <b>BF1355-SP</b>	Fuel/Water Separator (Open End for Bowl) (85104856)..... <b>BF1355-O</b>	Fuel/Water Separator (w/Bowl) (Racor R90P)..... <b>BF46072</b>
Fuel/Water Separator Spin-on (Open End for Bowl) (85104856).. <b>BF1355-O</b>	Fuel (Fleetguard FF2200)..... <b>BF7766</b>	Fuel/Water Separator (w/Drain) (Racor R90P)..... <b>BF1329</b>
Fuel/Water Separator Ele. (85105574)..... <b>PF7680</b>	Radial Seal O. Air (20411815).... <b>RS4642</b>	Fuel/Water Separator (Sensor Port Thd. 9/16-18) (Racor R90P).. <b>BF1329-SP</b>
Fuel (Fleetguard FF2200)..... <b>BF7766</b>	Radial Seal I. Air (20411816)..... <b>RS4643</b>	Fuel/Water Separator (Sensor Port Thd. 1/2-20) (Racor R90P).... <b>BF1339-SP +</b>
Single Radial Seal Air (20882320)..... <b>RS4642</b>	Cab Air (20435801)..... <b>PA4681</b>	Fuel/Water Separator Spin-on (Open End for Bowl) (20514654).. <b>BF1366-O</b>
Radial Seal O. Air (20411815).... <b>RS4642</b>	Air Dryer (To 11/10/08) (3915558)..... <b>BA5374 +</b>	P. Fuel Spin-on (20976003)..... <b>BF7814</b>
Radial Seal I. Air (20411816)..... <b>RS4643</b>	Air Dryer (11/11/08-on) (85110799)..... <b>BA5592 90</b>	Fuel Spin-on (20972293)..... <b>BF7943</b>
Cab Air (20435801)..... <b>PA4681</b>	Breather (3683918)..... <b>CV15000</b>	Radial Seal O. Air (20411815).... <b>RS4642</b>
Air Dryer (3915558)..... <b>BA5374 +</b>	Coolant (w/o Chemical) (Fleetguard WF2127)..... <b>B5087</b>	Radial Seal I. Air (20411816)..... <b>RS4643</b>
Breather (3683918)..... <b>CV15000</b>	Coolant (w/Chemical) (Fleetguard WF2126)..... <b>BW5086</b>	Cab Air (20435801)..... [2] <b>PA4681</b>
Coolant (w/o Chemical) (Fleetguard WF2127)..... <b>B5087</b>	Trans. Spin-on (Fuller 4304827).. <b>BT223</b>	Air Dryer (To 11/10/08) (3915558)..... <b>BA5374 +</b>
Coolant (w/Chemical) (Fleetguard WF2126)..... <b>BW5086</b>	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	Air Dryer (11/11/08-on) (85110799)..... <b>BA5592 90</b>
Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	Steering (349619)..... <b>P106-HD</b>	Coolant (w/o Chemical) (20458771)..... <b>B5145</b>
Trans. Spin-on (Fuller 4304827).. <b>BT223</b>	VT830 w/VE D16 Eng.	Coolant (w/8 Units BTE) (20458769)..... <b>BW5142</b>
Steering (349619)..... <b>P106-HD</b>	F-F Lube (478736)..... [2] <b>B76-SS +</b>	Trans. Ele. (1521527)..... <b>PT9417</b>
VT800 w/VE D16 Eng.	B-P Lube (477556)..... <b>B7685</b>	Trans. Spin-on (Fuller 4304827).. <b>BT223</b>
F-F Lube (478736)..... [2] <b>B76-SS +</b>	Fuel/Water Separator Ele. (85105574)..... <b>PF7680</b>	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>
B-P Lube (477556)..... <b>B7685</b>	Fuel/Water Separator Ele. (Fleetguard FF5369W)..... <b>PF7744</b>	Steering (349619)..... <b>P106-HD</b>
Fuel/Water Separator Ele. (85105574)..... <b>PF7680</b>	Fuel/Water Separator Ele. (Davco 382119)..... <b>PF7782</b>	VT880 w/Cummins ISX Eng.
Fuel/Water Separator Ele. (Fleetguard FF5369)..... <b>PF7744</b>	Fuel/Water Separator Spin-on (Open End for Bowl) (20514654).. <b>BF1366-O</b>	Dual-Flow Lube (3101869)..... <b>BD7154 +</b>
Fuel/Water Separator Spin-on (Open End for Bowl) (20514654).. <b>BF1366-O</b>	Fuel Spin-on (20976003)..... <b>BF7814</b>	Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>
Fuel Spin-on (20430751)..... <b>BF7814</b>	Radial Seal O. Air (20411815).... <b>RS4642</b>	Fuel/Water Separator Ele. (85105574)..... <b>PF7680</b>
Fuel Spin-on (22480372)..... <b>BF46161</b>	Radial Seal I. Air (20411816)..... <b>RS4643</b>	Fuel/Water Separator Spin-on (w/Drain) (85104856)..... <b>BF1355</b>
Radial Seal O. Air (20411815).... <b>RS4642</b>	Cab Air..... <b>PA4681</b>	Fuel/Water Separator Spin-on (w/Drain & Sensor Port) (85104856)..... <b>BF1355-SP</b>
Radial Seal I. Air (20411816)..... <b>RS4643</b>	Air Dryer (To 11/10/08) (3915558)..... <b>BA5374 +</b>	Fuel/Water Separator Spin-on (Open End for Bowl) (85104856).. <b>BF1355-O</b>
Cab Air (20435801)..... <b>PA4681</b>	Air Dryer (11/11/08-on) (85110799)..... <b>BA5592 90</b>	Fuel (Fleetguard FF2200)..... <b>BF7766</b>
Air Dryer (To 11/10/08) (3915558)..... <b>BA5374 +</b>	Coolant (w/o Chemical) (20458771)..... <b>B5145</b>	Radial Seal O. Air (20411815).... <b>RS4642</b>
Air Dryer (11/11/08-on) (85110799)..... <b>BA5592 90</b>	Coolant (w/8 Units BTE) (3945411)..... <b>BW5142</b>	Radial Seal I. Air (20411816)..... <b>RS4643</b>
Coolant (w/o Chemical) (20458771)..... <b>B5145</b>	Trans. Ele. (1521527)..... <b>PT9417</b>	Single Radial Seal Air (20882320)..... <b>RS4642</b>
Coolant (w/8 Units BTE) (3945411)..... <b>BW5142</b>	Trans. Spin-on (Fuller 4304827).. <b>BT223</b>	Cab Air (20435801)..... <b>PA4681</b>
Trans. Ele. (1521527)..... <b>PT9417</b>	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	Air Dryer (3915558)..... <b>BA5374 +</b>
Trans. Spin-on (Fuller 4304827).. <b>BT223</b>	Steering (349619)..... <b>P106-HD</b>	
Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>		

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

VOLVO North America Trucks (cont'd)	VOLVO North America Trucks (cont'd)	VOLVO North America Trucks (cont'd)
<b>VT880 w/Cummins ISX Eng. (Cont'd)</b> <b>Breather</b> (1/07-on) (3683918)..... <b>CV15000</b> <b>Coolant</b> (w/o Chemical) (Fleetguard WF2127)..... <b>B5087</b> <b>Coolant</b> (w/Chemical) (Fleetguard WF2126)..... <b>BW5086</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2<sup>+</sup></b> <b>Steering</b> (349619)..... <b>P106-HD</b>	<b>WAH w/Detroit Diesel Series 60 (11.1L) or  (12.7L) Eng.</b> <b>Lube</b> (23518480)..... <b>[2] B495</b> <b>P. Fuel</b> (23530706)..... <b>BF5800<sup>+</sup></b> <b>S. Fuel</b> (23518482)..... <b>BF5810</b> <b>Coolant</b> (23516489)..... <b>BW5200</b>	<b>WC w/D12 (12.1L) Eng. (Cont'd)</b> <b>Fuel/Water Separator Spin-on</b> (Alliance ABPN122R50551)..... <b>BF46016-O</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2<sup>+</sup></b>
<b>WAI64T w/Cummins M11 Eng.</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103<sup>+</sup></b> <b>Fuel/Water Separator</b> (3329289). <b>BF1259</b>	<b>WC w/Cat 3176 (10.3L) Eng.</b> <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99<sup>+</sup></b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299<sup>+</sup></b> <b>Opt. B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Fuel/Water Separator Spin-on</b> (2568753)..... <b>BF1259</b> <b>P. Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>P. Fuel Spin-on</b> (1R1740)..... <b>BF970<sup>+</sup></b> <b>S. Fuel Spin-on</b> (1R0750)..... <b>BF7633<sup>+</sup></b>	<b>WG w/Cat 3176 (10.3L) Eng.</b> <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99<sup>+</sup></b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299<sup>+</sup></b> <b>Opt. B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Fuel/Water Separator Spin-on</b> (2568753)..... <b>BF1259</b> <b>P. Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>P. Fuel Spin-on</b> (1R1740)..... <b>BF970<sup>+</sup></b> <b>S. Fuel Spin-on</b> (1R0750)..... <b>BF7633<sup>+</sup></b>
<b>WAI64T w/Cummins N14 Eng.</b> <b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196<sup>+</sup></b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103<sup>+</sup></b> <b>Fuel/Water Separator</b> (3329289). <b>BF1259</b> <b>Fuel</b> (154789)..... <b>BF957-D<sup>+</sup></b>	<b>WC w/Cat 3406 (14.6L) Eng.</b> <b>Lube</b> (1R0716)..... <b>B99<sup>+</sup></b> <b>Fuel/Water Separator</b> (256-8753)..... <b>BF1259</b> <b>Fuel</b> (4N5823)..... <b>BF614<sup>+</sup></b>	<b>WG w/Cat 3306 (10.5L) Eng.</b> <b>Lube</b> (Standard Vers.) (1R0739).. <b>B76<sup>+</sup></b> <b>Lube</b> (Severe Service) (1R0739).. <b>B76-SS<sup>+</sup></b> <b>Fuel/Water Separator Spin-on</b> (3132887)..... <b>BF1212<sup>+</sup></b> <b>Axial Seal Air</b> (22005-5038)..... <b>PA2661</b> <b>Radial Seal Air</b> (Standard) (V1117576)..... <b>RS3518</b> <b>Radial Seal XP Air</b> (Upgrade) (V1117576)..... <b>RS3518XP</b> <b>Air Dryer</b> (Bendix 65624)..... <b>BA5373</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (Nelson 84365A)..... <b>PT951</b> <b>Steering</b> (38708-5002)..... <b>P528</b>
<b>WAI64T w/VED12 Eng.</b> <b>Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154<sup>+</sup></b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>F-F Lube</b> (478736-2)..... <b>B76-SS<sup>+</sup></b> <b>B-P Lube</b> (477556)..... <b>B7685</b> <b>Fuel</b> (8193841)..... <b>BF7653</b> <b>Coolant</b> (20458771)..... <b>B5145</b>	<b>WC w/Cummins M11 (10.8L) Eng. (To 12/1995)</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103<sup>+</sup></b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> (3308638)..... <b>BF1212<sup>+</sup></b>	<b>WG w/Cat 3406 (14.6L) Eng.</b> <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99<sup>+</sup></b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299<sup>+</sup></b> <b>Fuel/Water Separator Spin-on</b> (8N0205)..... <b>BF1268</b> <b>Fuel/Water Separator Spin-on</b> (2568753)..... <b>BF1259</b> <b>Fuel Spin-on</b> (1R0749)..... <b>BF7587<sup>+</sup></b> <b>Fuel</b> (1R0712)..... <b>BF614<sup>+</sup></b>
<b>WAH w/Cummins 6CT8.3 (8.3L) Eng.</b> <b>F-F Lube</b> (3313281)..... <b>B205<sup>+</sup></b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103<sup>+</sup></b> <b>Fuel/Water Separator</b> (Fleetguard 3903410)..... <b>BF1280<sup>+</sup></b> <b>Fuel/Water Separator</b> (3286503). <b>BF1226</b> <b>Fuel Spin-on</b> (3903640)..... <b>BF788</b>	<b>WC w/Cummins M11 (10.8L) Eng. (12/1995-on)</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103<sup>+</sup></b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> (3329289)..... <b>BF1259</b>	<b>WG w/Cat 3406 (14.6L) Eng.</b> <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99<sup>+</sup></b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299<sup>+</sup></b> <b>Fuel/Water Separator Spin-on</b> (8N0205)..... <b>BF1268</b> <b>Fuel/Water Separator Spin-on</b> (2568753)..... <b>BF1259</b> <b>Fuel Spin-on</b> (1R0749)..... <b>BF7587<sup>+</sup></b> <b>Fuel</b> (1R0712)..... <b>BF614<sup>+</sup></b>
<b>WAH w/Cummins M11 (10.8L) Eng. (To  12/1995)</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103<sup>+</sup></b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> (3308638)..... <b>BF1212<sup>+</sup></b> <b>Coolant</b> (3318318)..... <b>BW5075</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2<sup>+</sup></b>	<b>WC w/Detroit Diesel Series 60 (11.1L) or (12.7L)  Eng.</b> <b>Lube</b> (23518480)..... <b>[2] B495</b> <b>P. Fuel</b> (23530706)..... <b>BF5800<sup>+</sup></b> <b>S. Fuel</b> (23518482)..... <b>BF5810</b> <b>Coolant</b> (23516489)..... <b>BW5200</b>	<b>WG w/Cummins ISM Eng.</b> <b>11 25/32 In. Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154<sup>+</sup></b> <b>14 7/32 In. Dual-Flow Lube</b> (Fleetguard LF9000)..... <b>BD7153<sup>+</sup></b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Air</b> (22005-3201)..... <b>LL2685</b> <b>Air</b> (22005-3202)..... <b>PA2661</b> <b>Air Dryer</b> (3915558)..... <b>BA5374<sup>+</sup></b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2<sup>+</sup></b> <b>Steering</b> (349619)..... <b>P106-HD</b>
<b>WAH w/Cummins M11 (10.8L) Eng.  (12/1995-on)</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103<sup>+</sup></b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> (3329289)..... <b>BF1259</b> <b>Coolant</b> (3318318)..... <b>BW5075</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2<sup>+</sup></b>	<b>WC w/D12 (12.1L) Eng.</b> <b>Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154<sup>+</sup></b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>F-F Lube</b> (4787362)..... <b>B76-SS<sup>+</sup></b> <b>B-P Lube</b> (4775565)..... <b>B7685</b>	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>VOLVO</b> <b>North America Trucks (cont'd)</b>	<b>VOLVO</b> <b>North America Trucks (cont'd)</b>	<b>VOLVO</b> <b>North America Trucks (cont'd)</b>
WG w/Cummins ISM Eng. (Cont'd) <b>Some Differential</b> (1119324)..... <b>B233</b>	WG w/Detroit Diesel Series 60 (11.1L) Eng. <b>Lube</b> (23518480)..... <b>[2] B495</b>	WH w/Cat 3176 (10.3L) Eng. (Cont'd) <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b>
WG w/Cummins L10 (10.0L) Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Fuel</b> (154789)..... <b>BF957-D +</b> <b>16 In. Std. Air</b> (22005-3202)..... <b>PA2661</b> <b>Axial Seal Air</b> (V1115700)..... <b>PA2797</b> <b>19 1/2 In. Std. Air</b> (22005-5095).. <b>PA2393</b> <b>Radial Seal Air</b> (Standard) (1117576)..... <b>RS3518</b> <b>Radial Seal XP Air</b> (Upgrade) (1117576)..... <b>RS3518XP</b> <b>Air Dryer</b> (Bendix 65624)..... <b>BA5373</b> <b>Trans. Ele.</b> (Allison 29510918).... <b>PT8330-MPG</b> <b>Trans. Spin-on</b> (3082148)..... <b>BT359</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (349619)..... <b>P106-HD</b> <b>Steering</b> (38708-5002)..... <b>P528</b>	<b>Fuel/Water Separator Spin-on</b> (3132887)..... <b>BF1212 +</b> <b>Fuel/Water Separator</b> (3919762). <b>PF7680</b> <b>Air</b> (22005-3202)..... <b>PA2661</b> <b>Axial Seal Air</b> (22005-5039)..... <b>LL2685</b> <b>Radial Seal Air</b> (Standard) (V1117576)..... <b>RS3518</b> <b>Radial Seal XP Air</b> (Upgrade) (V1117576)..... <b>RS3518XP</b> <b>Air Dryer</b> (Bendix 65624)..... <b>BA5373</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (349619)..... <b>P106-HD</b>	<b>WH w/Cummins M11 (10.8L) Eng. (To 12/1995)</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> (3308638)..... <b>BF1212 +</b>
WG w/Cummins M11 (10.8L) Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Std. 12 1/16 In. O.D. Air</b> (22005-3202)..... <b>PA2661</b> <b>Std. 13 13/16 In. O.D. Air</b> (22005-3201)..... <b>LL2685</b> <b>Radial Seal Air</b> (Standard) (V1117576)..... <b>RS3518</b> <b>Radial Seal XP Air</b> (Upgrade) (V1117576)..... <b>RS3518XP</b> <b>Air Dryer</b> (Bendix 65624)..... <b>BA5373</b> <b>Coolant</b> (3318318)..... <b>BW5075</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (V349619)..... <b>P106-HD</b>	<b>WG w/D12 (12.1L) Eng.</b> <b>F-F Lube</b> (478736)..... <b>[2] B76-SS +</b> <b>B-P Lube</b> (477556)..... <b>B7685</b> <b>Fuel/Water Separator</b> (w/Drain) (3945966)..... <b>BF1329</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (3945966)..... <b>BF46083-O</b> <b>Fuel/Water Separator</b> (w/9/16-18 SP Thd.) (3945966)..... <b>BF1329-SP</b> <b>Fuel/Water Separator</b> (w/1/2-20 SP Thd.) (3945966)..... <b>BF1339-SP +</b> <b>Fuel/Water Separator Spin-on</b> (w/Bowl) (3945966)..... <b>BF46072</b> <b>Fuel/Water Separator</b> (Alliance ABPN122R50551)..... <b>BF46016-O</b> <b>Fuel</b> (8193841)..... <b>BF7653</b> <b>Air</b> (22005-3202)..... <b>PA2661</b> <b>Air Dryer</b> (Bendix 65624)..... <b>BA5373</b> <b>Coolant</b> (w/2 Units BTE) (1699830)..... <b>BW5141</b> <b>Coolant</b> (w/8 Units BTE) (1676546)..... <b>BW5142</b> <b>Coolant</b> (w/o Chemical) (3969696)..... <b>B5144</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (349619)..... <b>P106-HD</b>	<b>WH w/Cummins M11 (10.8L) Eng. (12/1995-on)</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> (3329289)..... <b>BF1259</b>
WG w/Cummins N14 (14.0L) Eng. <b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Fuel</b> (154789)..... <b>BF957-D +</b> <b>Air</b> (22005-3201)..... <b>LL2685</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (V349619)..... <b>P106-HD</b> <b>Steering</b> (1742317)..... <b>PT951</b>	<b>WG w/VED7 Eng.</b> <b>F-F Lube</b> (Standard Vers.)..... <b>B76 +</b> <b>B-P Lube</b> (477556)..... <b>B7685</b> <b>F-F Lube</b> (Severe Service)..... <b>B76-SS +</b> <b>Opt. Fuel/Water Separator Ele.</b> (Racor)..... <b>PF598</b> <b>Fuel</b> ..... <b>BF988 +</b> <b>Air</b> (Don. XLP184108)..... <b>LL2661</b>	<b>WH w/Detroit Diesel Series 60 (11.1L) or (12.7L) Eng.</b> <b>Lube</b> (23518480)..... <b>[2] B495</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23518482)..... <b>BF5810</b> <b>Coolant</b> (23516489)..... <b>BW5200</b>
WG w/Cummins NTC315 Eng. <b>F-F Lube Ele.</b> (158139)..... <b>P999-HD</b> <b>F-F Lube Spin-on</b> (3313279)..... <b>B196 +</b> <b>Dual-Flow Lube Spin-on</b> (3318853)..... <b>BD103 +</b> <b>B-P Lube Ele.</b> (256838)..... <b>C750-E +</b> <b>B-P Lube Spin-on</b> (3313283)..... <b>B7577</b> <b>Fuel/Water Separator</b> (3308638). <b>BF1212 +</b> <b>Fuel</b> (154709)..... <b>BF957 +</b> <b>Air</b> (22005-3202)..... <b>PA2661</b> <b>Steering</b> (V349619)..... <b>P106-HD</b>	<b>WG w/Cat 3176 (10.3L) Eng.</b> <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99 +</b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> <b>Opt. B-P Lube</b> (1W8845)..... <b>B7577</b>	<b>WI w/Cat 3116 (6.6L) Eng.</b> <b>Lube</b> (Standard Vers.) (1R0739).. <b>B76 +</b> <b>Lube</b> (High Efficiency Vers.) (1R1807)..... <b>B7700 +</b> <b>Lube</b> (Severe Service) (1R0739).. <b>B76-SS +</b> <b>P. Fuel Spin-on</b> (1R1740)..... <b>BF970 +</b> <b>S. Fuel Spin-on</b> (1R0750)..... <b>BF7633 +</b> <b>Air Comp. Breather</b> (9L2169)..... <b>PA1704</b>
	<b>WG w/Cat 3176 (10.3L) Eng.</b> <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99 +</b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> <b>Opt. B-P Lube</b> (1W8845)..... <b>B7577</b>	<b>WI w/Cat 3176 (10.3L) Eng.</b> <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99 +</b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> <b>Opt. B-P Lube</b> (1W8845)..... <b>B7577</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



VOLVO North America Trucks (cont'd)	VOLVO North America Trucks (cont'd)	VOLVO North America Trucks (cont'd)
WI w/Cat 3306 (10.5L) Eng. <b>Lube Ele.</b> (5S0484)..... <b>PT670</b> <b>Lube Spin-on</b> (1R0716)..... <b>B99 +</b> <b>Lube Spin-on</b> (Standard Vers.) (1R0739)..... <b>B76 +</b> <b>Lube Spin-on</b> (Severe Service) (1R0739)..... <b>B76-SS +</b> <b>P. Fuel Ele.</b> (9M2342)..... <b>PF935</b> <b>P. Fuel Spin-on</b> (1R1740)..... <b>BF970 +</b> <b>S. Fuel Spin-on</b> (1R0750)..... <b>BF7633 +</b>	WX w/Cat 3208 Eng. (Cont'd) <b>Steering</b> (38708-5002)..... <b>P528</b> WX w/Cat 3306 (10.5L) Eng. <b>Lube</b> (Standard Vers.) (1R0739).. <b>B76</b> <b>Trans. Ele.</b> (Allison 29510918)..... <b>PT8330-MPG</b> WX w/Cummins 6CT8.3 (8.3L) Eng. <b>F-F Lube</b> (3313281)..... <b>B205 +</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Fuel/Water Separator</b> (Fleetguard 3903410)..... <b>BF1280 +</b> <b>Fuel/Water Separator</b> (3286503). <b>BF1226</b> <b>Fuel Spin-on</b> (3903640)..... <b>BF788</b> WX w/Cummins ISL 8.9 (8.9L) Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Dual-Flow Lube</b> (Fleetguard LF9548)..... <b>BD324 +</b> <b>Fuel</b> (Fleetguard FF5488)..... <b>BF7815</b> <b>Fuel</b> (Fleetguard FF5636)..... <b>BF7924</b> WX w/Cummins ISM 10.8 Eng. <b>Dual-Flow 11 25/32 In. Lube</b> (Fleetguard LF9001)..... <b>BD7154 +</b> <b>Dual-Flow 14 7/32 In. Lube</b> (Fleetguard LF9000)..... <b>BD7153 +</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Air</b> (22005-5038)..... <b>PA2661</b> <b>Air Dryer</b> (3915558)..... <b>BA5374 +</b> <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (38708-5002)..... <b>P528</b> WX w/Cummins L10 (10.0L) Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Fuel</b> (154789)..... <b>BF957-D +</b> <b>Air</b> (V1112594)..... <b>PA1904</b> <b>15 11/16 In. Air</b> (22005-0002)..... <b>PA2429</b> <b>16 In. Air</b> (22005-5038)..... <b>PA2661</b> <b>Air Dryer</b> (Bendix 65624)..... <b>BA5373</b> <b>Trans. Ele.</b> (Allison 29510918)..... <b>PT8330-MPG</b> <b>Trans. Spin-on</b> (3082148)..... <b>BT359</b> <b>Steering</b> (38708-5002)..... <b>P528</b> <b>Steering</b> (1742317)..... <b>PT951</b> WX w/Cummins M11 (10.8L) Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Dual-Flow Lube</b> (Fleetguard LF9009)..... <b>BD7309 +</b> <b>Trans. Ele.</b> (HT Series) (Allison 29510918)..... <b>PT8330-MPG</b> WX w/Cummins N14 Eng. <b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Fuel</b> (154789)..... <b>BF957-D +</b>	WX w/Cummins N14 Eng. (Cont'd) <b>Radial Seal Air</b> (Standard) (V1117576)..... <b>RS3518</b> <b>Radial Seal XP Air</b> (Upgrade) (V1117576)..... <b>RS3518XP</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (38708-5002)..... <b>P528</b> WXR64 w/VED7 Eng. <b>F-F Lube</b> (466634)..... <b>B76 +</b> <b>B-P Lube</b> (477556)..... <b>B7685</b> <b>Severe Service F-F Lube</b> (466634)..... <b>B76-SS +</b> <b>Fuel</b> (466987)..... <b>BF988 +</b> <b>Air Dryer</b> (Bendix 65624)..... <b>BA5373</b> <b>Coolant</b> (1676546)..... <b>BW5142</b> <b>Trans.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> VAH w/D11 (10.8L) Eng. (2022) <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B223</b> <h3 style="text-align: center;">VOLVO</h3> <h4 style="text-align: center;">South America Trucks, Vans</h4> B6 <b>Fuel/Water Separator</b> (Open End for Bowl) (8159975)..... <b>BF46083-O</b> <b>Fuel/Water Separator</b> (w/Bowl) (8159975)..... <b>BF46072</b> <b>Fuel/Water Separator</b> (w/Drain) (8159975)..... <b>BF1329</b> <b>Fuel/Water Separator</b> (w/Sensor Port Thd. 9/16-18) (8159975)..... <b>BF1329-SP</b> <b>Fuel/Water Separator</b> (w/Sensor Port Thd. 1/2-20) (8159975)..... <b>BF1339-SP +</b> <b>Fuel</b> (466987)..... <b>BF988 +</b> <b>Air</b> (1660619)..... <b>PA2707</b> <b>Steering</b> (349619)..... <b>P106-HD</b> B6B <b>Steering</b> (349619)..... <b>P106-HD</b> B7 <b>Fuel</b> (466987)..... <b>BF988 +</b> <b>Air</b> (1660619)..... <b>PA2707</b> <b>Steering</b> (349619)..... <b>P106-HD</b> <b>Gearbox</b> (3517857)..... <b>B132</b> B7F <b>Fuel/Water Separator</b> (w/Drain) (8159975)..... <b>BF1329</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (8159975)..... <b>BF46083-O</b> <b>Fuel/Water Separator</b> (w/Bowl) (8159975)..... <b>BF46072</b> <b>Fuel/Water Separator</b> (SP Thd. 1/2-20) (8159975)..... <b>BF1339-SP</b> <b>Fuel/Water Separator</b> (SP Thd. 9/16-18) (8159975)..... <b>BF1329-SP</b> <b>Steering</b> (349619)..... <b>P106-HD</b>
WI w/Cat 3406 (14.6L) Eng. <b>Lube</b> (Std. Efficiency) (1R0716)... <b>B99 +</b> <b>Lube</b> (High Efficiency) (1R1808).. <b>B7299 +</b> <b>Fuel</b> (1R0749)..... <b>BF7587 +</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> WI w/Cummins M11 (10.8L) Eng. (To 12/1995) <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> (3308638)..... <b>BF1212 +</b> WI w/Cummins M11 (10.8L) Eng. (12/1995-on) <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> (3329289)..... <b>BF1259</b> WI w/Cummins N14 (14.0L) Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196 +</b> <b>B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Opt. Fuel/Water Separator</b> (3329289)..... <b>BF1259</b> <b>Fuel</b> (154789)..... <b>BF957-D +</b> WI w/Detroit Diesel Series 60 (11.1L) or (12.7L) Eng. <b>Lube</b> (23518480)..... <b>[2] B495</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23518482)..... <b>BF5810</b> <b>Coolant</b> (23516489)..... <b>BW5200</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> WI w/D12 (12.1L) Eng. <b>Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154 +</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>F-F Lube</b> (4787362)..... <b>B76-SS +</b> <b>B-P Lube</b> (4775565)..... <b>B7685</b> <b>Fuel/Water Separator Spin-on</b> (Alliance ABPN122R50551)..... <b>BF46016-O</b> WX w/Cat 3208 Eng. <b>Trans. Pan-Type</b> (Allison 29538489)..... <b>19739 +</b> <b>Trans. Spin-on</b> (Allison 29510922)..... <b>BT8316-MPG</b>		

\* See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

VOLVO South America Trucks, Vans (cont'd)	VOLVO South America Trucks, Vans (cont'd)	VOLVO South America Trucks, Vans (cont'd)
<b>B7L</b> Steering (349619)..... P106-HD Gearbox (3517857)..... B132	<b>B12 (Cont'd)</b> Fuel (466987)..... BF988 + O. Air (1544449)..... PA2774 I. Air (1660903)..... PA2775 Coolant (20532237)..... BW5142 Trans. Ele. (85108176)..... PT9417 Trans. Spin-on (3517857)..... B132 Steering (349619)..... P106-HD	<b>F12 (Cont'd)</b> 92.1 mm Air Comp. Breather (8152009)..... PA2798 131.8 mm Air Comp. Breather (8152010)..... PA3679 Steering (349619)..... P106-HD Gearbox (3517857)..... B132
<b>B7R</b> Fuel/Water Separator (w/Drain) (8159975)..... BF1329 Fuel/Water Separator (Open End for Bowl) (8159975)..... BF46083-O Fuel/Water Separator (w/Bowl) (8159975)..... BF46072 Fuel/Water Separator (w/Sensor Port Thd. 9/16-18) (8159975)..... BF1329-SP Fuel/Water Separator (w/Sensor Port Thd. 1/2-20) (8159975)..... BF1339-SP + Radial Seal I. Air (20416502)..... RS5676 Steering (349619)..... P106-HD Gearbox (3517857)..... B132	<b>B12B</b> Fuel (8193841)..... BF7653 Coolant (20532237)..... BW5142 <b>B12B</b> Fuel/Water Separator (20998367)..... BF1366-O <b>B12B w/D12A Eng.</b> Fuel (8193841)..... BF7653 <b>B12B w/D12C Eng.</b> Fuel (8193841)..... BF7653 <b>B12B w/D12D Eng.</b> Fuel (20976003)..... BF7814 <b>B12M</b> Fuel/Water Separator (20998367)..... BF1366-O Air (1544449)..... PA2774 <b>B12M w/D12D Eng.</b> Fuel (20976003)..... BF7814 <b>B12R</b> Fuel/Water Separator (20998367)..... BF1366-O <b>B12R w/D12D Eng.</b> Fuel (20976003)..... BF7814 <b>B58</b> Fuel (466987)..... BF988 + 368.3 mm Air (1660619)..... PA2707 Steering (349619)..... P106-HD <b>F6</b> Fuel (466987)..... BF988 + Steering (349619)..... P106-HD <b>F7</b> Steering (349619)..... P106-HD <b>F10</b> Fuel (466987)..... BF988 + 580.2 mm Air (1660376)..... PA2914 589.8 mm Air (1080918)..... PA3484 92.1 mm Air Comp. Breather (8152009)..... PA2798 131.8 mm Air Comp. Breather (8152010)..... PA3679 Steering (349619)..... P106-HD Gearbox (3517857)..... B132 <b>F12</b> Fuel (466987)..... BF988 + 368.3 mm Air (1544449)..... PA2774 580.2 mm Air (1660376)..... PA2914 589.8 mm Air (1080918)..... PA3484	<b>F16</b> Fuel (466987)..... BF988 + 92.1 mm Air Comp. Breather (8152009)..... PA2798 131.8 mm Air Comp. Breather (8152010)..... PA3679 Steering (349619)..... P106-HD Gearbox (3517857)..... B132 <b>FE6</b> Fuel (466987)..... BF988 + Air (6792554)..... PA2785 Air Comp. Breather (8152009)..... PA2798 Steering (349619)..... P106-HD <b>FE7</b> Fuel (466987)..... BF988 + Air Comp. Breather (8152009)..... PA2798 Steering (349619)..... P106-HD Gearbox (3517857)..... B132 <b>FH w/D13A Eng. (Peru)</b> Fuel (20972293)..... BF7943 <b>FH12</b> Fuel/Water Separator (w/Bowl) (8159975)..... BF46072 Fuel/Water Separator (w/Drain) (8159975)..... BF1329 Fuel/Water Separator (Open End for Bowl) (8159975)..... BF46083-O Fuel/Water Separator (w/Sensor Port Thd. 9/16-18) (8159975)..... BF1329-SP Fuel/Water Separator (w/Sensor Port Thd. 1/2-20) (8159975)..... BF1339-SP + Single Air (1665898)..... PA3767 Single Radial Seal Air (8149961) Radial Seal Air (w/Flame Retardant Media) (21834210)..... RS5776 Std. I. Air (1660903)..... PA2775 Radial Seal I. Air (21041296)..... RS5408 Cab Air (8143691)..... PA3839 Coolant (20532237)..... BW5142 Steering (349619)..... P106-HD Gearbox Ele. (85108176)..... PT9417 Gearbox Spin-on (3517857)..... B132 <b>FH12 w/D12 Eng.</b> Fuel (8193841)..... BF7653 Coolant (20532237)..... BW5142 <b>FH12 w/D12D Eng.</b> Fuel (20976003)..... BF7814
<b>B10B</b> Fuel (466987)..... BF988 + Air (1660619)..... PA2707 Air Comp. Breather (8152010)..... PA3679 Steering (349619)..... P106-HD Gearbox (3517857)..... B132	<b>B10L</b> Steering (349619)..... P106-HD	
<b>B10M</b> Fuel/Water Separator (w/Bowl) (8159975)..... BF46072 Fuel/Water Separator (w/Drain) (8159975)..... BF1329 Fuel/Water Separator (Open End for Bowl) (8159975)..... BF46083-O Fuel/Water Separator (w/Sensor Port Thd. 9/16-18) (8159975)..... BF1329-SP Fuel/Water Separator (w/Sensor Port Thd. 1/2-20) (8159975)..... BF1339-SP + Fuel (466987)..... BF988 + O. Air (1544449)..... PA2774 I. Air (1660903)..... PA2775 Steering (349619)..... P106-HD Gearbox Ele. (85108176)..... PT9417 Gearbox Spin-on (3517857)..... B132	<b>B10R</b> I. Air (1660903)..... PA2775 Steering (349619)..... P106-HD Gearbox Ele. (85108176)..... PT9417 Gearbox Spin-on (3517857)..... B132	
<b>B12</b> Fuel/Water Separator (w/Bowl) (8159975)..... BF46072 Fuel/Water Separator (w/Drain) (8159975)..... BF1329 Fuel/Water Separator (Open End for Bowl) (8159975)..... BF46083-O Fuel/Water Separator (w/Sensor Port Thd. 9/16-18) (8159975)..... BF1329-SP Fuel/Water Separator (w/Sensor Port Thd. 1/2-20) (8159975)..... BF1339-SP +		

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

VOLVO South America Trucks, Vans (cont'd)	VOLVO South America Trucks, Vans (cont'd)	VOLVO South America Trucks, Vans (cont'd)
<b>FH16</b>	<b>FL12</b>	<b>FM12 (Cont'd)</b>
Fuel/Water Separator (w/Bowl) (8159975)..... <b>BF46072</b>	Air (1080918)..... <b>PA3484</b>	Coolant (20532237)..... <b>BW5142</b>
Fuel/Water Separator (w/Drain) (8159975)..... <b>BF1329</b>	Air Comp. Breather (8152009).... <b>PA2798</b>	Steering (349619)..... <b>P106-HD</b>
Fuel/Water Separator (Open End for Bowl) (8159975)..... <b>BF46083-O</b>	Steering (349619)..... <b>P106-HD</b>	Gearbox Ele. (85108176)..... <b>PT9417</b>
Fuel/Water Separator (w/Sensor Port Thd. 9/16-18) (8159975)..... <b>BF1329-SP</b>	Gearbox (3517857)..... <b>B132</b>	Gearbox Spin-on (3517857)..... <b>B132</b>
Fuel/Water Separator (w/Sensor Port Thd. 1/2-20) (8159975)..... <b>BF1339-SP +</b>	<b>FL12 w/D12 Eng.</b>	<b>FM12 w/D12 Eng.</b>
Fuel (466987)..... <b>BF988 +</b>	Fuel (8193841)..... <b>BF7653</b>	Coolant (20532237)..... <b>BW5142</b>
I. Air (1660903)..... <b>PA2775</b>	<b>FL608</b>	<b>FM12 w/D12D Eng.</b>
Cab Air (8143691)..... <b>PA3839</b>	Oval Air (3120490)..... <b>PA4929</b>	Fuel (20976003)..... <b>BF7814</b>
Steering (349619)..... <b>P106-HD</b>	Air (w/Lid) (6792554)..... <b>PA2785</b>	<b>FS7</b>
Gearbox Ele. (85108176)..... <b>PT9417</b>	Steering (349619)..... <b>P106-HD</b>	Fuel (466987)..... <b>BF988 +</b>
Gearbox Spin-on (3517857)..... <b>B132</b>	<b>FL615</b>	Air (3120490)..... <b>PA4929</b>
<b>FH16 w/D12D</b>	Oval Air (3120490)..... <b>PA4929</b>	Gearbox (3517857)..... <b>B132</b>
Fuel (20976003)..... <b>BF7814</b>	Air (w/Lid) (6792554)..... <b>PA2785</b>	<b>N10</b>
<b>FL6</b>	Steering (349619)..... <b>P106-HD</b>	Fuel (466987)..... <b>BF988 +</b>
Fuel/Water Separator (Open End for Bowl) (8159975)..... <b>BF46083-O</b>	<b>FL616</b>	Air (1660619)..... <b>PA2707</b>
Fuel/Water Separator (w/Bowl) (8159975)..... <b>BF46072</b>	Oval Air (3120490)..... <b>PA4929</b>	Air Comp. Breather (8152009).... <b>PA2798</b>
Fuel/Water Separator (w/Drain) (8159975)..... <b>BF1329</b>	Air (w/Lid) (6792554)..... <b>PA2785</b>	Steering (349619)..... <b>P106-HD</b>
Fuel/Water Separator (w/Sensor Port Thd. 9/16-18) (8159975)..... <b>BF1329-SP</b>	Steering (349619)..... <b>P106-HD</b>	Gearbox (3517857)..... <b>B132</b>
Fuel/Water Separator (w/Sensor Port Thd. 1/2-20) (8159975)..... <b>BF1339-SP +</b>	<b>FL619</b>	<b>N12</b>
Fuel/Water Separator (Open End for Bowl) (20386080)..... <b>BF1398-O</b>	Oval Air (3120490)..... <b>PA4929</b>	Fuel (466987)..... <b>BF988 +</b>
Fuel (466987)..... <b>BF988 +</b>	Air (w/Lid) (6792554)..... <b>PA2785</b>	305.6 mm O.D. Air (1660619)..... <b>PA2707</b>
Oval Air (3120490)..... <b>PA4929</b>	Steering (349619)..... <b>P106-HD</b>	350.8 mm O.D. Air (1544449)..... <b>PA2774</b>
590.6 mm Air (6792554)..... <b>PA2785</b>	<b>FLT10</b>	Air Comp. Breather (8152009).... <b>PA2798</b>
Breather (8152009)..... <b>PA2798</b>	Air Comp. Breather (8152010).... <b>PA3679</b>	Steering (349619)..... <b>P106-HD</b>
Steering (349619)..... <b>P106-HD</b>	<b>FM (Peru)</b>	Gearbox (3517857)..... <b>B132</b>
Gearbox (3517857)..... <b>B132</b>	Fuel/Water Separator (20998367)..... <b>BF1366-O</b>	<b>NH12</b>
<b>FL7</b>	<b>FM w/D13A Eng. (Peru)</b>	Fuel/Water Separator (Open End for Bowl) (8159975)..... <b>BF46083-O</b>
Fuel (466987)..... <b>BF988 +</b>	Fuel (20972293)..... <b>BF7943</b>	Fuel/Water Separator (w/Bowl) (8159975)..... <b>BF46072</b>
368.3 mm O. Air (1660619)..... <b>PA2707</b>	<b>FM7</b>	Fuel/Water Separator (w/Drain) (8159975)..... <b>BF1329</b>
542.9 mm O. Air (1660600)..... <b>PA2786</b>	I. Air (1660903)..... <b>PA2775</b>	Fuel/Water Separator (w/Sensor Port Thd. 9/16-18) (8159975)..... <b>BF1329-SP</b>
I. Air (1665886)..... <b>PA2787</b>	Gearbox (85108176)..... <b>PT9417</b>	Fuel/Water Separator (w/Sensor Port Thd. 1/2-20) (8159975)..... <b>BF1339-SP +</b>
Single Air (1665563)..... <b>PA2982</b>	<b>FM9</b>	Fuel/Water Separator (Open End for Bowl) (20998367)..... <b>BF1366-O</b>
Air Comp. Air (8152009)..... <b>PA2798</b>	I. Air (1660903)..... <b>PA2775</b>	Radial Seal Air (8149961)..... <b>RS4967</b>
Steering (349619)..... <b>P106-HD</b>	Steering (349619)..... <b>P106-HD</b>	Radial Seal Air (w/Flame Retardant Media) (21834210)..... <b>RS5776</b>
Gearbox (3517857)..... <b>B132</b>	Gearbox (85108176)..... <b>PT9417</b>	Axial Seal Air (1665898)..... <b>PA3767</b>
<b>FL10</b>	<b>FM10</b>	I. Air (1660903)..... <b>PA2775</b>
368.3 mm O. Air (1660619)..... <b>PA2707</b>	Radial Seal Air (8149064)..... <b>RS4966</b>	Cab Air (8143691)..... <b>PA3839</b>
542.9 mm O. Air (1660600)..... <b>PA2786</b>	Std. I. Air (1660903)..... <b>PA2775</b>	Coolant (20532237)..... <b>BW5142</b>
I. Air (1665886)..... <b>PA2787</b>	Gearbox (85108176)..... <b>PT9417</b>	Steering (349619)..... <b>P106-HD</b>
Single Air (1665563)..... <b>PA2982</b>	<b>FM12</b>	Gearbox Ele. (85108176)..... <b>PT9417</b>
Air Comp. Air (8152009)..... <b>PA2798</b>	Fuel/Water Separator (w/Bowl) (8159975)..... <b>BF46072</b>	Gearbox Spin-on (3517857)..... <b>B132</b>
Steering (349619)..... <b>P106-HD</b>	Fuel/Water Separator (Open End for Bowl) (8159975)..... <b>BF46083-O</b>	<b>NH12 w/D12</b>
Gearbox (3517857)..... <b>B132</b>	Fuel/Water Separator (w/Drain) (8159975)..... <b>BF1329</b>	Fuel (8193841)..... <b>BF7653</b>
<b>FL11</b>	Fuel/Water Separator (w/Sensor Port Thd. 9/16-18) (8159975)..... <b>BF1329-SP</b>	Coolant (20532237)..... <b>BW5142</b>
368.3 mm O. Air (1660619)..... <b>PA2707</b>	Fuel/Water Separator (w/Sensor Port Thd. 1/2-20) (8159975)..... <b>BF1339-SP +</b>	<b>NH12 w/D12D</b>
542.9 mm O. Air (1660600)..... <b>PA2786</b>	Radial Seal O. Air (8149064)..... <b>RS4966</b>	Fuel (20976003)..... <b>BF7814</b>
I. Air (1665886)..... <b>PA2787</b>	Radial Seal I. Air (21041296)..... <b>RS5408</b>	
Single Air (1665563)..... <b>PA2982</b>	Std. I. Air (1660903)..... <b>PA2775</b>	
Air Comp. Air (8152009)..... <b>PA2798</b>	Cab Air (8143691)..... <b>PA3839</b>	
Steering (349619)..... <b>P106-HD</b>		
Gearbox (3517857)..... <b>B132</b>		

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>VOLVO</b> South America Trucks, Vans (cont'd)	<b>VOLVO</b> South America Trucks, Vans (cont'd)	<b>VOLVO</b> South America Trucks, Vans (cont'd)
NL10 Fuel/Water Separator (w/Drain) (8159975)..... <b>BF1329</b> Fuel/Water Separator (Open End for Bowl) (8159975)..... <b>BF46083-O</b> Fuel/Water Separator (w/Bowl) (8159975)..... <b>BF46072</b> Fuel/Water Separator (SP Thd. 1/2-20) (8159975)..... <b>BF1339-SP</b> Fuel/Water Separator (SP Thd. 9/16-18) (8159975)..... <b>BF1329-SP</b> Fuel (466987)..... <b>BF988 +</b> O. Air (1544449)..... <b>PA2774</b> Cab Air (8143691)..... <b>PA3839</b> 92.1 mm Air Comp. Breather (8152009)..... <b>PA2798</b> 131.8 mm Air Comp. Breather (8152010)..... <b>PA3679</b> Steering (349619)..... <b>P106-HD</b> Gearbox (3517857)..... <b>B132</b>	SOR2400 Trans. (1526188)..... <b>B178</b> VHD Fuel/Water Separator (20998367)..... <b>BF1366-O</b> VHD w/D12D Eng. Fuel (20976003)..... <b>BF7814</b> VHD w/D13A Eng. Fuel (20972293)..... <b>BF7943</b> VM (Peru) Radial Seal Air (20544738)..... <b>RS5358</b> I. Air (1660903)..... <b>PA2775</b> Gearbox (85108176)..... <b>PT9417</b> VM220 w/MWM7B220 Eng. (01/12-on) Fuel/Water Separator (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> Fuel/Water Separator (With Bowl) (Mann WK1060/1)..... <b>BF46072</b> Fuel/Water Separator (With Drain) (Mann WK1060/1)..... <b>BF1329</b> Fuel/Water Separator (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b> Fuel/Water Separator (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b> VM260 w/MWM7A260 Eng. (01/05-on) Fuel/Water Separator (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> Fuel/Water Separator (With Bowl) (Mann WK1060/1)..... <b>BF46072</b> Fuel/Water Separator (With Drain) (Mann WK1060/1)..... <b>BF1329</b> Fuel/Water Separator (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b> Fuel/Water Separator (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b> VM270 w/MWM7B270 Eng. (01/12-on) Fuel/Water Separator (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> Fuel/Water Separator (With Bowl) (Mann WK1060/1)..... <b>BF46072</b> Fuel/Water Separator (With Drain) (Mann WK1060/1)..... <b>BF1329</b> Fuel/Water Separator (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b> Fuel/Water Separator (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b> VM330 w/MWM7B330 Eng. (01/12-on) Fuel/Water Separator (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> Fuel/Water Separator (With Bowl) (Mann WK1060/1)..... <b>BF46072</b>	VM330 w/MWM7B330 Eng. (01/12-on) (Cont'd) Fuel/Water Separator (With Drain) (Mann WK1060/1)..... <b>BF1329</b> Fuel/Water Separator (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b> Fuel/Water Separator (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b> VN Fuel/Water Separator (20998367)..... <b>BF1366-O</b> VN w/D12D Eng. Fuel (20976003)..... <b>BF7814</b> VN w/D13A Eng. Fuel (20972293)..... <b>BF7943</b> <b>VOLVO</b> <b>Transmissions</b> ATO2612F Trans. (21479106)..... <b>PT9417</b> I-Shift Trans. (1521527)..... <b>PT9417</b> <b>WALTER</b> <b>Trucks</b> FYM-CL w/Waukesha 135GZB Eng. Lube..... <b>P52</b> NDV, QDU w/GMC 8V-71 Eng. F-F Lube Ele..... <b>P20-HD +</b> B-P Lube Ele..... <b>P52</b> P. Fuel Sock (5574980)..... <b>F844-A</b> P. Fuel Sock (5574961)..... <b>F916-C</b> P. Fuel Ele. (5575032)..... <b>PF845</b> S. Fuel Ele. (5574508)..... <b>PF902</b> S. Fuel Ele. (6436719)..... <b>PF846</b> P. Fuel Spin-on..... <b>BF5800 +</b> S. Fuel Spin-on..... <b>BF5810</b> ZOQ w/Cummins V555 Eng. F-F Lube Spin-on..... <b>B196 +</b> F-F Lube Ele..... <b>P999-HD</b> Fuel Spin-on..... <b>BF957 +</b> Coolant Spin-on..... <b>BW5071</b> <b>WARD LAFRANCE</b> <b>Trucks</b> Models w/Continental TD4627, R6572, 4-6602 Engs. Lube..... <b>P52</b> Models w/Continental R6000, T6427 Engs. Lube..... <b>P42</b> Models w/Waukesha MZA, SRKR, 140GZB, 145GK Engs. Lube..... <b>P52</b> 44 Lube..... <b>P60</b>
NL12 Fuel/Water Separator (w/Drain) (8159975)..... <b>BF1329</b> Fuel/Water Separator (Open End for Bowl) (8159975)..... <b>BF46083-O</b> Fuel/Water Separator (w/Bowl) (8159975)..... <b>BF46072</b> Fuel/Water Separator (SP Thd. 1/2-20) (8159975)..... <b>BF1339-SP</b> Fuel/Water Separator (SP Thd. 9/16-18) (8159975)..... <b>BF1329-SP</b> Fuel (466987)..... <b>BF988 +</b> O. Air (1544449)..... <b>PA2774</b> Cab Air (8143691)..... <b>PA3839</b> 92.1 mm Air Comp. Breather (8152009)..... <b>PA2798</b> 131.8 mm Air Comp. Breather (8152010)..... <b>PA3679</b> Steering (349619)..... <b>P106-HD</b> Gearbox (3517857)..... <b>B132</b>	VM260 w/MWM7A260 Eng. (01/05-on) Fuel/Water Separator (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> Fuel/Water Separator (With Bowl) (Mann WK1060/1)..... <b>BF46072</b> Fuel/Water Separator (With Drain) (Mann WK1060/1)..... <b>BF1329</b> Fuel/Water Separator (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b> Fuel/Water Separator (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b> VM270 w/MWM7B270 Eng. (01/12-on) Fuel/Water Separator (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> Fuel/Water Separator (With Bowl) (Mann WK1060/1)..... <b>BF46072</b> Fuel/Water Separator (With Drain) (Mann WK1060/1)..... <b>BF1329</b> Fuel/Water Separator (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b> Fuel/Water Separator (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b> VM330 w/MWM7B330 Eng. (01/12-on) Fuel/Water Separator (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> Fuel/Water Separator (With Bowl) (Mann WK1060/1)..... <b>BF46072</b>	NDV, QDU w/GMC 8V-71 Eng. F-F Lube Ele..... <b>P20-HD +</b> B-P Lube Ele..... <b>P52</b> P. Fuel Sock (5574980)..... <b>F844-A</b> P. Fuel Sock (5574961)..... <b>F916-C</b> P. Fuel Ele. (5575032)..... <b>PF845</b> S. Fuel Ele. (5574508)..... <b>PF902</b> S. Fuel Ele. (6436719)..... <b>PF846</b> P. Fuel Spin-on..... <b>BF5800 +</b> S. Fuel Spin-on..... <b>BF5810</b> ZOQ w/Cummins V555 Eng. F-F Lube Spin-on..... <b>B196 +</b> F-F Lube Ele..... <b>P999-HD</b> Fuel Spin-on..... <b>BF957 +</b> Coolant Spin-on..... <b>BW5071</b> <b>WARD LAFRANCE</b> <b>Trucks</b> Models w/Continental TD4627, R6572, 4-6602 Engs. Lube..... <b>P52</b> Models w/Continental R6000, T6427 Engs. Lube..... <b>P42</b> Models w/Waukesha MZA, SRKR, 140GZB, 145GK Engs. Lube..... <b>P52</b> 44 Lube..... <b>P60</b>
R70 Trans. (1526188)..... <b>B178</b>	VM270 w/MWM7B270 Eng. (01/12-on) Fuel/Water Separator (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> Fuel/Water Separator (With Bowl) (Mann WK1060/1)..... <b>BF46072</b> Fuel/Water Separator (With Drain) (Mann WK1060/1)..... <b>BF1329</b> Fuel/Water Separator (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b> Fuel/Water Separator (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b> VM330 w/MWM7B330 Eng. (01/12-on) Fuel/Water Separator (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> Fuel/Water Separator (With Bowl) (Mann WK1060/1)..... <b>BF46072</b>	WARD LAFRANCE <b>Trucks</b> Models w/Continental TD4627, R6572, 4-6602 Engs. Lube..... <b>P52</b> Models w/Continental R6000, T6427 Engs. Lube..... <b>P42</b> Models w/Waukesha MZA, SRKR, 140GZB, 145GK Engs. Lube..... <b>P52</b> 44 Lube..... <b>P60</b>
R71 Trans. (1526188)..... <b>B178</b>	VM270 w/MWM7B270 Eng. (01/12-on) Fuel/Water Separator (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> Fuel/Water Separator (With Bowl) (Mann WK1060/1)..... <b>BF46072</b> Fuel/Water Separator (With Drain) (Mann WK1060/1)..... <b>BF1329</b> Fuel/Water Separator (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b> Fuel/Water Separator (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b> VM330 w/MWM7B330 Eng. (01/12-on) Fuel/Water Separator (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> Fuel/Water Separator (With Bowl) (Mann WK1060/1)..... <b>BF46072</b>	WARD LAFRANCE <b>Trucks</b> Models w/Continental TD4627, R6572, 4-6602 Engs. Lube..... <b>P52</b> Models w/Continental R6000, T6427 Engs. Lube..... <b>P42</b> Models w/Waukesha MZA, SRKR, 140GZB, 145GK Engs. Lube..... <b>P52</b> 44 Lube..... <b>P60</b>
SR70 Trans. (1526188)..... <b>B178</b>	VM270 w/MWM7B270 Eng. (01/12-on) Fuel/Water Separator (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> Fuel/Water Separator (With Bowl) (Mann WK1060/1)..... <b>BF46072</b> Fuel/Water Separator (With Drain) (Mann WK1060/1)..... <b>BF1329</b> Fuel/Water Separator (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b> Fuel/Water Separator (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b> VM330 w/MWM7B330 Eng. (01/12-on) Fuel/Water Separator (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> Fuel/Water Separator (With Bowl) (Mann WK1060/1)..... <b>BF46072</b>	WARD LAFRANCE <b>Trucks</b> Models w/Continental TD4627, R6572, 4-6602 Engs. Lube..... <b>P52</b> Models w/Continental R6000, T6427 Engs. Lube..... <b>P42</b> Models w/Waukesha MZA, SRKR, 140GZB, 145GK Engs. Lube..... <b>P52</b> 44 Lube..... <b>P60</b>
SR71 Trans. (1526188)..... <b>B178</b>	VM270 w/MWM7B270 Eng. (01/12-on) Fuel/Water Separator (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> Fuel/Water Separator (With Bowl) (Mann WK1060/1)..... <b>BF46072</b> Fuel/Water Separator (With Drain) (Mann WK1060/1)..... <b>BF1329</b> Fuel/Water Separator (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b> Fuel/Water Separator (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b> VM330 w/MWM7B330 Eng. (01/12-on) Fuel/Water Separator (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> Fuel/Water Separator (With Bowl) (Mann WK1060/1)..... <b>BF46072</b>	WARD LAFRANCE <b>Trucks</b> Models w/Continental TD4627, R6572, 4-6602 Engs. Lube..... <b>P52</b> Models w/Continental R6000, T6427 Engs. Lube..... <b>P42</b> Models w/Waukesha MZA, SRKR, 140GZB, 145GK Engs. Lube..... <b>P52</b> 44 Lube..... <b>P60</b>
SR2000 Trans. (1526188)..... <b>B178</b>	VM270 w/MWM7B270 Eng. (01/12-on) Fuel/Water Separator (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> Fuel/Water Separator (With Bowl) (Mann WK1060/1)..... <b>BF46072</b> Fuel/Water Separator (With Drain) (Mann WK1060/1)..... <b>BF1329</b> Fuel/Water Separator (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b> Fuel/Water Separator (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b> VM330 w/MWM7B330 Eng. (01/12-on) Fuel/Water Separator (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> Fuel/Water Separator (With Bowl) (Mann WK1060/1)..... <b>BF46072</b>	WARD LAFRANCE <b>Trucks</b> Models w/Continental TD4627, R6572, 4-6602 Engs. Lube..... <b>P52</b> Models w/Continental R6000, T6427 Engs. Lube..... <b>P42</b> Models w/Waukesha MZA, SRKR, 140GZB, 145GK Engs. Lube..... <b>P52</b> 44 Lube..... <b>P60</b>
SR2400 Trans. (1526188)..... <b>B178</b>	VM270 w/MWM7B270 Eng. (01/12-on) Fuel/Water Separator (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> Fuel/Water Separator (With Bowl) (Mann WK1060/1)..... <b>BF46072</b> Fuel/Water Separator (With Drain) (Mann WK1060/1)..... <b>BF1329</b> Fuel/Water Separator (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b> Fuel/Water Separator (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b> VM330 w/MWM7B330 Eng. (01/12-on) Fuel/Water Separator (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> Fuel/Water Separator (With Bowl) (Mann WK1060/1)..... <b>BF46072</b>	WARD LAFRANCE <b>Trucks</b> Models w/Continental TD4627, R6572, 4-6602 Engs. Lube..... <b>P52</b> Models w/Continental R6000, T6427 Engs. Lube..... <b>P42</b> Models w/Waukesha MZA, SRKR, 140GZB, 145GK Engs. Lube..... <b>P52</b> 44 Lube..... <b>P60</b>
SOR2000 Trans. (1526188)..... <b>B178</b>	VM270 w/MWM7B270 Eng. (01/12-on) Fuel/Water Separator (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> Fuel/Water Separator (With Bowl) (Mann WK1060/1)..... <b>BF46072</b> Fuel/Water Separator (With Drain) (Mann WK1060/1)..... <b>BF1329</b> Fuel/Water Separator (Sensor Port Thread 9/16-18) (Mann WK1060/1)..... <b>BF1329-SP</b> Fuel/Water Separator (Sensor Port Thread 1/2-20) (Mann WK1060/1)..... <b>BF1339-SP +</b> VM330 w/MWM7B330 Eng. (01/12-on) Fuel/Water Separator (Open End for Bowl) (Mann WK1060/1)..... <b>BF46083-O</b> Fuel/Water Separator (With Bowl) (Mann WK1060/1)..... <b>BF46072</b>	WARD LAFRANCE <b>Trucks</b> Models w/Continental TD4627, R6572, 4-6602 Engs. Lube..... <b>P52</b> Models w/Continental R6000, T6427 Engs. Lube..... <b>P42</b> Models w/Waukesha MZA, SRKR, 140GZB, 145GK Engs. Lube..... <b>P52</b> 44 Lube..... <b>P60</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



<b>WESTERN STAR Trucks (cont'd)</b>	<b>WESTERN STAR Trucks (cont'd)</b>	<b>WESTERN STAR Trucks (cont'd)</b>
4600 w/Cat C15 Eng. Lube (1R0716)..... <b>B99 +</b>	4700 w/Cummins ISL 8.9 (8.9L) Eng. (2012-17) (Cont'd) Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Steering Ele. (Nelson 84148A).... <b>P528</b> Steering Spin-on (T1808D)..... <b>BT9388</b> Diesel Exhaust Fluid (5303604).. <b>PE17000</b>	4700 w/Cummins ISL 8.9 (8.9L) Eng. (2020) (Cont'd) Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Steering (1417927000)..... <b>PT23629</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>
4700 w/Cummins ISC Eng. Dual-Flow Lube (3401544)..... <b>BD7309 +</b> Lube (Upgrade) (3401544)..... <b>B40142 +</b> Fuel/Water Separator Ele. (Fleetguard FS19727)..... <b>PF7895</b> Fuel/Water Separator Spin-on (Alliance ABPN122R50550)..... <b>BF9871-O</b> Fuel (4940647)..... <b>BF7924</b> Channel Flow Primary Air (Don. P619498)..... <b>CA30132</b> Channel Flow Secondary Air (Don. P616400)..... <b>PA4701</b> Channel Flow Primary Air (Standard Vers.) (Don. P607955). <b>CA4700</b> Channel Flow Primary Air (Flame Retardant Media) (Don. P607960) <b>CA5420</b> Channel Flow Secondary Air (Don. P616400)..... <b>PA4701</b> Channel Flow Air (Standard Vers.) (Don. P607965)..... <b>CA5368</b> Channel Flow Air (Flame Retardant Media) (Don. P605960) <b>CA5419</b> Air Dryer (Wabco R950068)..... <b>BA5379 +</b> Coolant (Fleetguard WF2077)..... <b>B5134 +</b> Trans. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Steering (T1808D)..... <b>BT9388</b>	4700 w/Cummins ISL 8.9 (8.9L) Eng. (2018) Dual-Flow Lube (Standard) (Fleetguard LF9009)..... <b>BD7309</b> Lube (Upgrade) (Fleetguard LF9009)..... <b>B40142</b> Fuel/Water Separator (Alliance R50550)..... <b>BF9871-O</b> Fuel (Fleetguard FF63009)..... <b>BF63000</b> Channel Flow Air (Don. P619498)..... <b>CA30132</b> Channel Flow Secondary Air (Don. P616400)..... <b>PA4701</b> Air Dryer (Bendix 107796PG)..... <b>BA5377</b> Crankcase Breather (4936636).... <b>CV15010</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2</b> Steering (1417927000)..... <b>PT23629</b> Diesel Exhaust Fluid (Fleetguard UF101)..... <b>PE17000</b>	4700 w/Cummins L9 (9.0L) Eng. (2018) Lube (3401544)..... <b>B40142</b> Fuel (5303743)..... <b>BF63000</b> Primary Channel Flow Air (Don. P619498)..... <b>CA30132</b> Secondary Channel Flow Air (Don. P547520)..... <b>PA5418</b>
4700 w/Cummins ISL 8.9 (8.9L) Eng. (2012-17) Dual-Flow Lube (3401544)..... <b>BD7309 +</b> Lube (Upgrade) (3401544)..... <b>B40142 +</b> Fuel/Water Separator (Alliance ABPN122R50550)..... <b>BF9871-O</b> Fuel (2010 Emissions) (4940647). <b>BF7924</b> Fuel (2014 Emissions) (Fleetguard FF63008)..... <b>BF63000</b> Channel Flow Primary Air (Don. P619498)..... <b>CA30132</b> Channel Flow Secondary Air (Don. P616400)..... <b>PA4701</b> Channel Flow Primary Air (Standard Vers.) (Don. P607955). <b>CA4700</b> Channel Flow Primary Air (Flame Retardant Media) (Don. P607960) <b>CA5420</b> Channel Flow Secondary Air (Don. P616400)..... <b>PA4701</b> Channel Flow Air (Standard Vers.) (Don. P607965)..... <b>CA5368</b> Channel Flow Air (Flame Retardant Media) (Don. P605960) <b>CA5419</b> Air Dryer (Wabco R950068)..... <b>BA5379 +</b> Air Dryer (Bendix 5008414)..... <b>BA5374 +</b> Coolant (Fleetguard WF2071)..... <b>BW5071</b> Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b>	4700 w/Cummins ISL 8.9 (8.9L) Eng. (2019) Lube (3401544)..... <b>B40142</b> Fuel/Water Separator (A0000904851)..... <b>PF46171</b> Fuel (5303743)..... <b>BF63000</b> Channel Flow Air (Don. P634517)..... <b>CA30132</b> Air Dryer (Bendix 107796)..... <b>BA5377</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Steering (1417927000)..... <b>PT23629</b>	4700 w/Cummins L9 (9.0L) Eng. (2019) Lube (3401544)..... <b>B40142</b> Fuel/Water Separator (A0000904851)..... <b>PF46171</b> Fuel (5303743)..... <b>BF63000</b> Channel Flow Air (Don. P634517)..... <b>CA30132</b> Air Dryer (Wabco R950068A)..... <b>BA5379</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Steering (1417927000)..... <b>PT23629</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>
	4700 w/Cummins ISL 8.9 (8.9L) Eng. (2020) Lube (5444774)..... <b>B40142</b> Fuel/Water Separator (A0000904851)..... <b>PF46171</b> Fuel (5303743)..... <b>BF63000</b> Channel Flow Air (Don. P634517)..... <b>CA30132</b> Air Dryer (Bendix 107796PG)..... <b>BA5377</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	4700 w/Cummins L9 (9.0L) Eng. (2020) Lube (5444774)..... <b>B40142</b> Fuel (5303743)..... <b>BF63000</b> Air Dryer (Bendix 107796PG)..... <b>BA5377</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

WESTERN STAR Trucks (cont'd)	WESTERN STAR Trucks (cont'd)	WESTERN STAR Trucks (cont'd)
4700 w/Cummins L9 (9.0L) Eng. (2022) <b>Lube</b> (5520789)..... <b>B40142</b>	4700 w/Detroit DD13 (12.8L) Eng. (2016-17) <b>Lube</b> (A4731800109)..... <b>P7505</b>	4700 w/Detroit DD13 (12.8L) Eng. (2019) (Cont'd) <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b>
4700 w/Cummins X12 (11.9L) Eng. (2020) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel</b> (5365988)..... <b>BF46129</b> <b>Channel Flow Air</b> (Don. P634517)..... <b>CA30132</b> <b>Air Dryer</b> (Wabco R950068A)..... <b>BA5379</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	<b>Fuel/Water Separator</b> (A0000903651)..... <b>PF9804</b> <b>Fuel</b> (2 Filter Kit) (A4720900451)..... <b>PF9908 KIT</b> <b>Fuel</b> (3 Filter Kit) (A0000904251)..... <b>PF9924 KIT</b> <b>Channel Flow Primary Air</b> (Don. P619498)..... <b>CA30132</b> <b>Channel Flow Secondary Air</b> (Don. P616400)..... <b>PA4701</b> <b>Air Dryer</b> ..... <b>BA5374 +</b> <b>Coolant</b> (A4722030255)..... <b>P5092</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. 17237)..... <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering Ele.</b> (Nelson 84148A).... <b>P528</b> <b>Diesel Exhaust Fluid</b> (A0001420789)..... <b>PE17002 KIT</b>	4700 w/Detroit DD13 (12.8L) Eng. (2020) <b>Lube</b> (To Eng. S/N A472910S0690710) (A4731800409)..... <b>P7505</b> <b>Fuel/Water Separator</b> (A0000905051)..... <b>PF46145</b> <b>Fuel/Water Separator</b> (Racor R61709)..... <b>PF46235</b> <b>Fuel</b> (A4700903151)..... <b>PF9908 KIT</b> <b>Channel Flow Air</b> (Don. P634517)..... <b>CA30132</b> <b>Air Dryer</b> (Racor R950068A)..... <b>BA5379</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. 17237)..... <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b>
4700 w/Cummins X12 (11.9L) Eng. (2021) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel</b> (5365988)..... <b>BF46129</b> <b>Air Dryer</b> (Bendix 107796PG)..... <b>BA5377</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	4700 w/Detroit Diesel DD13 Eng. (2012-15) <b>Lube</b> (A4731800109)..... <b>P7505</b> <b>Fuel/Water Separator</b> (A0000903651)..... <b>PF9804</b> <b>Fuel Kit</b> (2 Filter Kit) (A4720900451)..... <b>PF9908 KIT</b> <b>Fuel Kit</b> (3 Filter Kit) (A0000904251)..... <b>PF9924 KIT</b> <b>Channel Flow Primary Air</b> (Don. P619498)..... <b>CA30132</b> <b>Channel Flow Secondary Air</b> (Don. P616400)..... <b>PA4701</b> <b>Channel Flow Primary Air</b> (Standard Vers.) (Don. P607955). <b>CA4700</b> <b>Channel Flow Primary Air</b> (Flame Retardant Media) (Don. P607960) <b>CA5420</b> <b>Channel Flow Secondary Air</b> (Don. P616400)..... <b>PA4701</b> <b>Channel Flow Air</b> (Standard Vers.) (Don. P607965)..... <b>CA5368</b> <b>Channel Flow Air</b> (Flame Retardant Media) (Don. P605960) <b>CA5419</b> <b>Air Dryer</b> (Wabco R950068)..... <b>BA5379 +</b> <b>Air Dryer</b> (Bendix 5008414)..... <b>BA5374 +</b> <b>Coolant</b> (A4722030255)..... <b>P5092</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. 17237)..... <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering Ele.</b> (Nelson 84148A).... <b>P528</b> <b>Steering Spin-on</b> (T1808D)..... <b>BT9388</b> <b>Diesel Exhaust Fluid</b> (A0001420289)..... <b>PE5272</b>	4700 w/Detroit DD13 (12.8L) Eng. (2021) <b>Fuel</b> (A4700903151)..... <b>PF9908 KIT</b> <b>Air Dryer</b> (Bendix 107796PG)..... <b>BA5377</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. 17237)..... <b>BT223</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
4700 w/Detroit DD13 (12.8L) Eng. (2018) <b>Lube</b> (A4731800109)..... <b>P7505</b> <b>Fuel/Water Separator</b> (A0000905051)..... <b>PF46145</b> <b>Fuel</b> (A4720900651)..... <b>PF9908 KIT</b> <b>Channel Flow Primary Air</b> (Don. P619498)..... <b>CA30132</b> <b>Channel Flow Secondary Air</b> (Don. P616400)..... <b>PA4701</b> <b>Air Dryer</b> (Bendix 107796PG)..... <b>BA5377</b> <b>Coolant</b> (A4722030355)..... <b>P5092</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. 17237)..... <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b>	4700 w/Detroit DD13 (12.8L) Eng. (2022) <b>Fuel</b> (A4700903151)..... <b>PF9908 KIT</b> <b>Air Dryer</b> (Bendix 107796PG)..... <b>BA5377</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	4700 w/Detroit DD13 (12.8L) Eng. (2019) <b>Lube</b> (A4731800409)..... <b>P7505</b> <b>Fuel/Water Separator</b> (A0000905051)..... <b>PF46145</b> <b>Fuel Kit</b> (A4720900651)..... <b>PF9908 KIT</b> <b>Channel Flow Air</b> (Don. P634517)..... <b>CA30132</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. 17237)..... <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
4700 w/Detroit DD15 (14.8L) Eng. (To 2018) <b>Lube</b> (A4731800409)..... <b>P7505</b> <b>Fuel/Water Separator</b> (A0000905051)..... <b>PF46145</b> <b>Fuel</b> (A4720900651)..... <b>PF9908 KIT</b> <b>Channel Flow Primary Air</b> (Don. P619498)..... <b>CA30132</b> <b>Channel Flow Secondary Air</b> (Don. P616400)..... <b>PA4701</b> <b>Channel Flow Primary Air</b> (Standard Vers.) (Don. P607955). <b>CA4700</b>	4700 w/Detroit DD13 (12.8L) Eng. (2019) <b>Lube</b> (A4731800409)..... <b>P7505</b> <b>Fuel/Water Separator</b> (A0000905051)..... <b>PF46145</b> <b>Fuel Kit</b> (A4720900651)..... <b>PF9908 KIT</b> <b>Channel Flow Air</b> (Don. P634517)..... <b>CA30132</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. 17237)..... <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	4700 w/Detroit DD15 (14.8L) Eng. (To 2018) <b>Lube</b> (A4731800409)..... <b>P7505</b> <b>Fuel/Water Separator</b> (A0000905051)..... <b>PF46145</b> <b>Fuel</b> (A4720900651)..... <b>PF9908 KIT</b> <b>Channel Flow Primary Air</b> (Don. P619498)..... <b>CA30132</b> <b>Channel Flow Secondary Air</b> (Don. P616400)..... <b>PA4701</b> <b>Channel Flow Primary Air</b> (Standard Vers.) (Don. P607955). <b>CA4700</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

WESTERN STAR Trucks (cont'd)	WESTERN STAR Trucks (cont'd)	WESTERN STAR Trucks (cont'd)
4700 w/Detroit DD15 (14.8L) Eng. (To 2018) (Cont'd)	4800 w/Cat C10 (10.3L) Eng. (Cont'd)	4800 w/Cat C16 (15.8L) Eng. (Cont'd)
Channel Flow Primary Air (Flame Retardant Media) (Don. P607960) CA5420	Fuel/Water Separator (Open End for Bowl) (1335673) BF1395-O	Trans. Ele. (4 In. Kit) (Allison 29548988) PT9415-MPG KIT
Channel Flow Secondary Air (Don. P616400) PA4701	Fuel/Water Separator (w/Drain) (1335673) BF1265	Trans. Spin-on (Fuller 4304827) BT223
Channel Flow Air (Standard Vers.) (Don. P607965) CA5368	Fuel/Water Separator (w/Sensor Port) (1335673) BF1395-SP	Opt. Trans. Spin-on (Fuller 17237) B2 +
Channel Flow Air (Flame Retardant Media) (Don. P605960) CA5419	Fuel/Water Separator Spin-on (2568753) BF1259	4800 w/Cat 3116 (6.6L) Eng.
Air Dryer (Bendix 107796PG) BA5377	Fuel Ele. (9M2342) [2] PF935	Lube (Standard Vers.) (1R0739) B76 +
Trans. Ele. (2 In. Kit) (Allison 29540493) PT9416-MPG KIT	Fuel Spin-on (Standard Vers.) (1R1712) BF614 +	Lube (High Efficiency Vers.) (1R1807) B7700 +
Trans. Ele. (4 In. Kit) (Allison 29540494) PT9415-MPG KIT	Fuel Spin-on (High Efficiency Vers.) (1R0749) BF7587 +	Lube (Severe Service) (1R0739) B76-SS +
Trans. Spin-on (Fuller 4304827) BT223	Air Dryer (AD-IS System) (Bendix 5008414) BA5374 +	Fuel/Water Coalescer Ele. w/Drain (1174089) BF7679-D
Opt. Trans. Spin-on (Fuller 17237) B2 +	Trans. Ele. (2 In. Kit) (Allison 29548987) PT9416-MPG KIT	Box-Style Fuel/Water Separator (6N7617) BF912
Steering (1417927000) PT23629	Trans. Ele. (4 In. Kit) (Allison 29548988) PT9415-MPG KIT	Fuel/Water Separator Spin-on (w/Sensor Port) (1466695) BF1350-SP
Diesel Exhaust Fluid (A0001421089) PE17002 KIT	Trans. Spin-on (Fuller 4304827) BT223	Fuel/Water Separator Spin-on (Open End for Bowl) (1466695) BF46030-O
4700SB w/Cummins L9 (9.0L) Eng. (2023)	Opt. Trans. Spin-on (Fuller 17237) B2 +	Fuel (1R0750) BF7633 +
Lube (5520789) B40142	4800 w/Cat C12 (12.0L) Eng.	Fuel (1R0751) BF7632
4700SB w/Cummins X12 (11.9L) Eng. (2022)	Lube (1R0716) B99 +	Air Dryer (AD-IS System) (Bendix 5008414) BA5374 +
Lube (5575298) B40145	Fuel/Water Separator (Alliance ABPN122R50551) BF46016-O	Air Comp. Breather (9L2169) PA1704
Fuel (5365988) BF46129	Fuel (1R-0749) BF7587 +	4800 w/Cat 3126 (7.2L) Eng.
Air Dryer (Bendix 107796PG) BA5377	4800 w/Cat C15 (14.6L) Eng.	Lube (Standard Vers.) (1R0739) B76 +
4700SB w/Detroit DD13 (12.8L) Eng. (2023)	Lube (1R0716) B99 +	Lube (Severe Service) (1R0739) B76-SS +
Trans. Ele. (2 In. Kit) (Allison 29558117) PT9416-MPG KIT	Fuel/Water Separator (3261641) BF9903-SP	Fuel/Water Separator (1752949) BF1268
Trans. Ele. (4 In. Kit) (Allison 29558118) PT9415-MPG KIT	Fuel/Water Separator (Open End for Bowl) (1335673) BF1395-O	Fuel/Water Separator (2568753) BF1259
4700SF w/Cummins L9 (9.0L) Eng. (2022)	Fuel/Water Separator (w/Drain) (1335673) BF1265	Fuel/Water Separator (1986378) BF7798-SP
Lube (5520789) B40142	Fuel/Water Separator (w/Sensor Port) (1335673) BF1395-SP	Fuel Ele. (9M2342) [2] PF935
4700SF w/Cummins X12 (11.9L) Eng. (2022)	Trans. (Fuller 4304827) BT223	Fuel Spin-on (1R0751) BF7632
Lube (5575298) B40145	4800 w/Cat C16 (15.8L) Eng.	Air Dryer (AD-IS System) (Bendix 5008414) BA5374 +
Fuel (5365988) BF46129	Lube (1R0716) B99 +	4800 w/Cat 3176 (10.3L) Eng.
Air Dryer (Bendix 107796PG) BA5377	Fuel/Water Separator (Open End for Bowl) (1335673) BF1395-O	Lube B99 +
Trans. Ele. (2 In. Kit) (Allison 29540493) PT9416-MPG KIT	Fuel/Water Separator (w/Drain) (1335673) BF1265	Opt. B-P Lube Spin-on B7577
Trans. Ele. (4 In. Kit) (Allison 29540494) PT9415-MPG KIT	Fuel/Water Separator (w/Sensor Port) (1335673) BF1395-SP	Fuel Spin-on BF614 +
4700SF w/Detroit DD13 (12.8L) Eng. (2022)	Fuel/Water Separator (2568753) BF1259	4800 w/Cat 3208 (10.4L) Eng.
Fuel (A4700903151) PF9908 KIT	Fuel/Water Separator (Alliance ABPN122R50551) BF46016-O	Lube (9L9200) [2] BT364
Air Dryer (Bendix 107796PG) BA5377	Fuel Ele. (9M2342) [2] PF935	Lube (9N5570) [2] BT230 +
Trans. Ele. (2 In. Kit) (Allison 29540493) PT9416-MPG KIT	Fuel Spin-on (Standard Vers.) (1R1712) BF614 +	Box-Style Fuel/Water Separator BF912
Trans. Ele. (4 In. Kit) (Allison 29540494) PT9415-MPG KIT	Fuel Spin-on (High Efficiency Vers.) (1R0749) BF7587 +	Fuel Spin-on BF970 +
4800 w/Cat C10 (10.3L) Eng.	Air Dryer (AD-IS System) (Bendix 5008414) BA5374 +	4800 w/Cat 3306 (10.5L) Eng.
F-F Lube (Std. Version) (1R0716) B99 +	Trans. Ele. (2 In. Kit) (Allison 29548987) PT9416-MPG KIT	Lube (Standard Vers.) B76 +
F-F Lube (High Efficiency Vers.) (1R1808) B7299 +		Lube (Severe Service) B76-SS +
B-P Lube (1W8845) B7577		Box-Style Fuel/Water Separator BF912
Fuel/Water Separator Ele. (8N0205) PF316		Fuel Spin-on BF970 +
		4800 w/Cat 3406 (14.6L) Eng.
		Lube (1R0716) B99 +
		Fuel Spin-on BF7587 +
		Fuel Spin-on (4N5823) BF614 +
		4800 w/Cat 3408 (18.0L) Eng.
		F-F Lube (Std. Version) (1R0716) B99 +
		F-F Lube (High Efficiency Vers.) (1R1808) B7299 +
		P. Fuel Ele. (9M2341) [2] PF935

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



WESTERN STAR Trucks (cont'd)	WESTERN STAR Trucks (cont'd)	WESTERN STAR Trucks (cont'd)
4800 w/Cat 3408 (18.0L) Eng. (Cont'd)	4800 w/Cummins M11 (10.8L) Eng. (To 12/1995) (Cont'd)	4800 w/Detroit Diesel Series 60 (11.1L) or (12.7L) Eng. (To 1993)
Fuel Spin-on (1R0749)..... <b>BF7587 +</b>	Fuel/Water Separator Ele. (Davco 380087)..... <b>PF7680</b>	F-F Lube (25010495)..... [2] <b>B95 +</b>
Fuel Spin-on (1R0712)..... <b>BF614 +</b>	Fuel/Water Separator Spin-on (3308638)..... <b>BF1212 +</b>	B-P Lube (23530413)..... <b>B7577</b>
Air Dryer (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	Fuel/Water Separator Spin-on (Alliance ABPN122R50551)..... <b>BF46016-O</b>	Fuel/Water Separator (w/Drain) (23512317)..... <b>BF5813 +</b>
4800 w/Cummins 6CT8.3 (8.3L) Eng.	Air Dryer (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	Fuel/Water Separator (Open End for Bowl) (23512317)..... <b>BF5813-O +</b>
Lube..... <b>B205 +</b>	Trans. Spin-on (Fuller 4304827).. <b>BT223</b>	Opt. Fuel/Water Separator (23516189)..... <b>BF5812</b>
P. Fuel/Water Separator..... <b>BF1280 +</b>	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	Opt. Fuel/Water Separator (Alliance ABPN122R50407)..... <b>BF1283-SP +</b>
S. Fuel..... <b>BF788</b>	4800 w/Cummins M11 (10.8L) Eng. (12/1995-on)	P. Fuel (25014274)..... <b>BF5800 +</b>
Coolant..... <b>BW5070</b>	Dual-Flow Lube (3318853)..... <b>BD103 +</b>	S. Fuel (23518482)..... <b>BF5810</b>
4800 w/Cummins ISM 10.8 (10.8L) Eng.	Fuel/Water Separator Ele. (Davco 380087)..... <b>PF7680</b>	Air (Don. P181016)..... <b>PA2493</b>
Dual-Flow Lube (Fleetguard LF9001)..... <b>BD7154 +</b>	Fuel/Water Separator Spin-on (3329289)..... <b>BF1259</b>	Air Dryer (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>
Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b>	Fuel/Water Separator Spin-on (Alliance ABPN122R50551)..... <b>BF46016-O</b>	Trans. Spin-on (Fuller 4304827).. <b>BT223</b>
Dual-Flow Lube (Fleetguard LF9031)..... <b>BD7509 +</b>	Air Dryer (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>
Dual-Flow Lube (Fleetguard LF9000)..... <b>BD7153 +</b>	Trans. Spin-on (Fuller 4304827).. <b>BT223</b>	4800 w/Detroit Diesel Series 60 (11.1L) or (12.7L) Eng. (1993-on)
Fuel/Water Separator Ele. (Fleetguard FS1029W)..... <b>PF7680</b>	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	F-F Lube (23518480)..... [2] <b>B495</b>
Fuel/Water Separator Spin-on (3406889)..... <b>BF1293-SPS</b>	4800 w/Cummins N14 (14.0L) Eng. (To 12/1995)	Fuel/Water Separator (w/Drain) (23512317)..... <b>BF5813 +</b>
Fuel/Water Separator Spin-on (Fleetguard FS1000)..... <b>BF1259</b>	Dual-Flow Lube (3318853)..... <b>BD103 +</b>	Fuel/Water Separator (Open End for Bowl) (23512317)..... <b>BF5813-O +</b>
Fuel/Water Separator Spin-on (Closed End) (Fleetguard FS1282)..... <b>BF1282 +</b>	F-F Lube (Fleetguard LF670SC).. <b>B196 +</b>	Opt. Fuel/Water Separator (23516189)..... <b>BF5812</b>
Air Dryer (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	B-P Lube (3304232)..... <b>B7577</b>	Opt. Fuel/Water Separator (Alliance ABPN122R50407)..... <b>BF1283-SP +</b>
Crankcase Breather (3683918)... <b>CV15000</b>	Fuel/Water Separator Spin-on (3308638)..... <b>BF1212 +</b>	P. Fuel (25014274)..... <b>BF5800 +</b>
Coolant (w/o Chemical) (Fleetguard WF2127)..... <b>B5087</b>	Air Dryer (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	S. Fuel (23518482)..... <b>BF5810</b>
Coolant (Controlled Release BTA+) (Fleetguard WF2121)..... <b>BW5250</b>	Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>	Air (Don. P181016)..... <b>PA2493</b>
Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>	Trans. Spin-on (Fuller 4304827).. <b>BT223</b>	Air Dryer (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>
Coolant (w/12 Units BTA+) (Fleetguard WF2074)..... <b>BW5074</b>	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	Trans. Spin-on (Fuller 4304827).. <b>BT223</b>
4800 w/Cummins L10 (10.0L) Eng.	4800 w/Cummins N14 (14.0L) Eng. (12/1995-on)	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>
Dual-Flow Lube (3318853)..... <b>BD103 +</b>	Dual-Flow Lube (3318853)..... <b>BD103 +</b>	4800 w/Detroit Diesel 6-71 (7.0L), 6V-92N (9.0L), 8V-71 (9.3L), or 8V-92 (12.1L) Eng.
F-F Lube (Fleetguard LF670SC).. <b>B196 +</b>	F-F Lube (Fleetguard LF670SC).. <b>B196 +</b>	Lube Ele..... <b>P20-HD +</b>
B-P Lube (3304232)..... <b>B7577</b>	B-P Lube (3304232)..... <b>B7577</b>	F-F Lube Spin-on..... <b>B95 +</b>
Fuel/Water Separator (3308638). <b>BF1212 +</b>	Fuel/Water Separator Spin-on (3329289)..... <b>BF1259</b>	P. Fuel Spin-on..... <b>BF5800 +</b>
Fuel (154789)..... <b>BF957-D +</b>	Air Dryer (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	S. Fuel Spin-on..... <b>BF5810</b>
Air Dryer (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>	Air (22005-4401)..... <b>PA2493</b>
Coolant (w/4 Units BTA+) (3315116)..... <b>BW5071</b>	Trans. Spin-on (Fuller 4304827).. <b>BT223</b>	4800 w/Detroit DD13 (12.8L) Eng. (2012-17)
Coolant (w/15 Units BTA+) (3318318)..... <b>BW5075</b>	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	Lube (A4731800109)..... <b>P7505</b>
Trans. Spin-on (Fuller 4304827).. <b>BT223</b>	4800 w/Cummins M11 (10.8L) Eng. (To 12/1995)	Fuel/Water Separator (A0000903651)..... <b>PF9804</b>
Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	Dual-Flow Lube (3318853)..... <b>BD103 +</b>	Fuel Kit (2 Filter Kit) (A4720900451)..... <b>PF9908 KIT</b>
4800 w/Cummins M11 (10.8L) Eng. (To 12/1995)	F-F Lube (Fleetguard LF670SC).. <b>B196 +</b>	Fuel Kit (3 Filter Kit) (A0000904251)..... <b>PF9924 KIT</b>
Dual-Flow Lube (3318853)..... <b>BD103 +</b>	B-P Lube (3304232)..... <b>B7577</b>	Air (Fleetguard AF1968M)..... [2] <b>PA2705</b>
	Fuel/Water Separator Spin-on (3329289)..... <b>BF1259</b>	Air Dryer (Wabco R950068)..... <b>BA5379 +</b>
	Air Dryer (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	Air Dryer (Bendix 5008414)..... <b>BA5374 +</b>
	Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>	Coolant (A4722030255)..... <b>P5092</b>
	Trans. Spin-on (Fuller 4304827).. <b>BT223</b>	
	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

WESTERN STAR Trucks (cont'd)	WESTERN STAR Trucks (cont'd)	WESTERN STAR Trucks (cont'd)
4800 w/Detroit DD13 (12.8L) Eng. (2012-17) (Cont'd)	4800 w/Detroit DD13 (12.8L) Eng. (2020)	4900 w/Cat C16 (15.8L) Eng.
Trans. Ele. (2 In. Kit) (Allison 29548987).....	Lube (To Eng. S/N 472910S0690710) (A4731800409).....	Lube (1R0716).....
PT9416-MPG KIT	P7505	B99 +
Trans. Ele. (4 In. Kit) (Allison 29548988).....	Fuel/Water Separator (A0000905051).....	Fuel/Water Separator (Open End for Bowl) (1335673).....
PT9415-MPG KIT	PF46145	BF1395-O
Trans. Spin-on (Fuller 4304827)..	Fuel (A4700903151).....	Fuel/Water Separator (w/Drain) (1335673).....
BT223	PF9908 KIT	BF1265
Opt. Trans. Spin-on (Fuller 17237).....	Air (Don. P153551).....	Fuel/Water Separator (w/Sensor Port) (1335673).....
B2 +	PA2705	BF1395-SP
2 25/32 In. Steering (Nelson 84365A).....	Trans. Spin-on (Fuller 4304827)..	Fuel/Water Separator (2568753).....
PT951 +	BT223	BF1259
4 3/16 In. Steering (Nelson 84148A).....	Opt. Trans. Spin-on (Fuller 17237).....	Fuel/Water Separator (Alliance ABPN122R50551).....
P528	B2	BF46016-O
Diesel Exhaust Fluid (A0001420289).....	Trans. Ele. (2 In. Kit) (Allison 29540493).....	Fuel Ele. (9M2342).....
PE5272	PT9416-MPG KIT	[2] PF935
Diesel Exhaust Fluid (A0001420789).....	Trans. Ele. (4 In. Kit) (Allison 29540494).....	Fuel Spin-on (Standard Vers.) (1R1712).....
PE17002 KIT	PT9415-MPG KIT	BF614 +
4800 w/Detroit DD13 (12.8L) Eng. (2018)	Opt. Rear Axle (Meritor 3280V8394).....	Fuel Spin-on (High Efficiency Vers.) (1R0749).....
Lube (A4731800109).....	B233	BF7587 +
P7505	4800 w/Detroit DD13 (12.8L) Eng. (2021)	Air Dryer (AD-IS System) (Bendix 5008414).....
Fuel/Water Separator (A0000905051).....	Fuel (A4700903151).....	BA5374 +
PF46145	PF9908 KIT	Trans. Ele. (2 In. Kit) (Allison 29548987).....
Fuel (A4720900651).....	Opt. Rear Axle (Meritor 3280V8394).....	PT9416-MPG KIT
PF9908 KIT	B233	Trans. Ele. (4 In. Kit) (Allison 29548988).....
Radial Seal Air (Don. P534816)..	4800SB w/Detroit DD13 (12.8L) Eng. (2022)	PT9415-MPG KIT
RS3539	Fuel (A4700903151).....	Trans. Spin-on (Fuller 4304827)..
Radial Seal XP Air (Don. P534816).....	PF9908 KIT	BT223
RS3539XP	4800SF w/Detroit DD13 (12.8L) Eng. (2022)	Opt. Trans. Spin-on (Fuller 17237).....
BA5377	Fuel (A4700903151).....	B2 +
P5092	PF9908 KIT	4900 w/Cat 3126 (7.2L) Eng.
Trans. Ele. (2 In. Kit) (Allison 29540493).....	4900 w/Cat C10 (10.3L) Eng.	Lube (Standard Vers.) (1R0739)..
PT9416-MPG KIT	F-F Lube (Std. Version) (1R0716).....	B76 +
Trans. Ele. (4 In. Kit) (Allison 29540494).....	B99 +	Lube (Severe Service) (1R0739)..
PT9415-MPG KIT	F-F Lube (High Efficiency Vers.) (1R1808).....	B76-SS +
Trans. Spin-on (Fuller 4304827)..	B7299 +	BF1268
BT223	B7577	Fuel/Water Separator (1752949).....
Opt. Trans. Spin-on (Fuller 17237).....	Fuel/Water Separator Ele. (8N0205).....	BF1259
B2 +	PF316	Fuel/Water Separator (w/Sensor Port) (1986378).....
P528	Fuel/Water Separator (Open End for Bowl) (1335673).....	BF7798-SP
Diesel Exhaust Fluid (A0001421089).....	BF1395-O	Fuel/Water Separator (Open End for Bowl) (1986378).....
PE17002 KIT	BF1265	BF7798-O
4800 w/Detroit DD13 (12.8L) Eng. (2019)	Fuel/Water Separator (w/Sensor Port) (1335673).....	[2] PF935
Lube (A4731800409).....	BF1395-SP	Fuel Ele. (9M2342).....
P7505	Fuel/Water Separator Spin-on (2568753).....	BF7632
Fuel/Water Separator (A0000905051).....	BF1259	Air Dryer (AD-IS System) (Bendix 5008414).....
PF46145	[2] PF935	BA5374 +
Fuel (A4720900651).....	Fuel Ele. (9M2342).....	4900 w/Cat 3176 (10.3L) Eng.
RS3539	[2] PF935	Lube.....
Radial Seal XP Air (Don. P534816).....	Fuel Spin-on (Standard Vers.) (1R1712).....	B99 +
RS3539XP	BF614 +	Opt. B-P Lube Spin-on.....
BA5377	Fuel Spin-on (High Efficiency Vers.) (1R0749).....	B7577
Air Dryer (Bendix 107796PG).....	BF7587 +	BF614 +
BA5377	BF5374 +	4900 w/Cat 3408 (18.0L) Eng.
Trans. Ele. (2 In. Kit) (Allison 29558117).....	Air Dryer (AD-IS System) (Bendix 5008414).....	F-F Lube (Std. Version) (1R0716).....
PT9416-MPG KIT	BA5374 +	B99 +
Trans. Ele. (4 In. Kit) (Allison 29558118).....	Trans. Ele. (2 In. Kit) (Allison 29548987).....	F-F Lube (High Efficiency Vers.) (1R1808).....
PT9415-MPG KIT	PT9416-MPG KIT	B7299 +
Trans. Spin-on (Fuller 4304827)..	Trans. Ele. (4 In. Kit) (Allison 29548988).....	[2] PF935
BT223	PT9415-MPG KIT	BF7587 +
B2 +	BT223	BF614 +
P528	Opt. Trans. Spin-on (Fuller 17237).....	Air Dryer (AD-IS System) (Bendix 5008414).....
Steering (Nelson 84148A).....	B2 +	BA5374 +
P528	4900 w/Cummins L10 (10.0L) Eng.	F-F Lube.....
Opt. Rear Axle (Meritor 3280V8394).....	F-F Lube.....	B196 +
B233	B-P Lube.....	B7577
Diesel Exhaust Fluid (A0001421089).....	Dual-Flow Lube.....	BD103 +
PE17002 KIT	Fuel/Water Separator.....	BF1212 +
	Fuel Spin-on.....	BF957-D +

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

WESTERN STAR Trucks (cont'd)	WESTERN STAR Trucks (cont'd)	WESTERN STAR Trucks (cont'd)
4900 w/Cummins L10 (10.0L) Eng. (Cont'd) <b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	4900 w/Detroit Diesel Series 60 (11.1L) & (12.7L) Eng. (To 1993) (Cont'd) <b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 84148A)..... <b>P528</b> <b>Some Rear Axle</b> (Meritor 3280-V-8394)..... <b>B233</b>	4900, 4900E w/Cat 3406 (14.6L) Eng. <b>Lube</b> (1R0716)..... <b>B99 +</b> <b>Fuel/Water Separator</b> (Racor 32-WS-01)..... <b>BF1259</b> <b>Fuel Ele.</b> (9M2342)..... <b>PF935</b> <b>Fuel Spin-on</b> (1R0712)..... <b>BF614 +</b> <b>Fuel Spin-on</b> (High Efficiency) (1R0749)..... <b>BF7587 +</b> <b>Air</b> (Nelson 70076N)..... <b>[2] PA2493</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Air Dryer</b> (Wabco R950011)..... <b>BA5374 +</b> <b>Coolant Spin-on</b> ..... <b>BW5137</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 87972A)..... <b>PT9386-MPG</b> <b>Steering</b> (Nelson 83213A)..... <b>PT951 +</b> <b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>
4900 w/Cummins Signature 600 (15.0L) Eng. <b>11 25/32 In. Dual-Flow Lube</b> (Fleetguard LF9001)..... <b>BD7154 +</b> <b>14 7/32 In. Dual-Flow Lube</b> (Fleetguard LF9000)..... <b>BD7153 +</b> <b>Dual-Flow Lube</b> (Upgrade) (Fleetguard LF14000NN)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (3331096). <b>BF1274-SP</b> <b>Fuel/Water Separator</b> (4010651). <b>BF1277-SPS</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Coolant</b> (3680433)..... <b>BW5086</b>	4900 w/Detroit Diesel Series 60 (11.1L) & (12.7L) Eng. (1993-on) <b>Lube</b> ..... <b>[2] B495</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19624)..... <b>PF7748</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (23512317)..... <b>BF5813 +</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (23512317).. <b>BF5813-O +</b> <b>P. Fuel</b> ..... <b>BF5800 +</b> <b>S. Fuel</b> (23533726)..... <b>BF5816</b> <b>S. Fuel</b> (23530645)..... <b>BF5815</b> <b>Radial Seal Air</b> (Don. P534925)... <b>[2] RS3534</b> <b>Radial Seal Air</b> (Don. P534816)... <b>[2] RS3539</b> <b>Radial Seal XP Air</b> (Don. P534816)..... <b>[2] RS3539XP</b> <b>Std. Air</b> (Nelson 70076N)..... <b>[2] PA2493</b> <b>Cab Air</b> (Alliance RD3-8416-0).... <b>PA5318</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (w/Chemical)..... <b>BW5137</b> <b>Coolant</b> (Controlled Release) (23516489)..... <b>BW5200</b> <b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 84148A)..... <b>P528</b> <b>Some Rear Axle</b> (Meritor 3280-V-8394)..... <b>B233</b>	4900, 4900E w/Cummins GCT8.3 (8.3L) Eng. <b>Lube</b> ..... <b>B205 +</b> <b>P. Fuel/Water Separator</b> ..... <b>BF1280 +</b> <b>S. Fuel</b> ..... <b>BF788</b> <b>Coolant</b> ..... <b>BW5070</b>
4900 w/Detroit Diesel 6-71 (7.0L), 6V-92N (9.0L), 8V-71 (9.3L), or 8V-92 (12.1L) Eng. <b>Lube Ele</b> ..... <b>P20-HD +</b> <b>F-F Lube Spin-on</b> ..... <b>B95 +</b> <b>P. Fuel Spin-on</b> ..... <b>BF5800 +</b> <b>S. Fuel Spin-on</b> ..... <b>BF5810</b> <b>Air</b> (22005-4401)..... <b>PA2493</b>	4900 w/Detroit Diesel Series 60 (11.1L) & (12.7L) Eng. (To 1993) <b>F-F Lube</b> ..... <b>B95 +</b> <b>B-P Lube</b> ..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19624)..... <b>PF7748</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (23512317)..... <b>BF5813 +</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (23512317).. <b>BF5813-O +</b> <b>P. Fuel</b> ..... <b>BF5800 +</b> <b>S. Fuel</b> (23533726)..... <b>BF5816</b> <b>S. Fuel</b> (23530645)..... <b>BF5815</b> <b>Radial Seal Air</b> (Don. P534925)... <b>[2] RS3534</b> <b>Radial Seal Air</b> (Don. P534816)... <b>[2] RS3539</b> <b>Radial Seal XP Air</b> (Don. P534816)..... <b>[2] RS3539XP</b> <b>Std. Air</b> (Nelson 70076N)..... <b>[2] PA2493</b> <b>Cab Air</b> (Alliance RD3-8416-0).... <b>PA5318</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (w/Chemical)..... <b>BW5137</b> <b>Coolant</b> (Controlled Release) (23516489)..... <b>BW5200</b>	4900, 4900E, 4900EX, 4900FA, 4900SA w/Cat C12 (12.0L) Eng. <b>F-F Lube</b> (1R0716)..... <b>B99 +</b> <b>F-F Lube</b> (High Efficiency) (1R1808)..... <b>B7299 +</b> <b>Fuel/Water Separator</b> (Racor RAI32FRT02)..... <b>BF1279</b> <b>Fuel/Water Separator</b> (Alliance ABPN122R50551)..... <b>BF46016-O</b> <b>Air</b> (Don. P153551)..... <b>PA2705</b> <b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (Fleetguard WF2077)..... <b>B5134 +</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 84148A)..... <b>P528</b> <b>Some Rear Axle</b> (Meritor 3280-V-8394)..... <b>B233</b>
4900 w/Detroit Diesel Series 60 (11.1L) & (12.7L) Eng. (To 1993) <b>F-F Lube</b> ..... <b>B95 +</b> <b>B-P Lube</b> ..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19624)..... <b>PF7748</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (23512317)..... <b>BF5813 +</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (23512317).. <b>BF5813-O +</b> <b>P. Fuel</b> ..... <b>BF5800 +</b> <b>S. Fuel</b> (23533726)..... <b>BF5816</b> <b>S. Fuel</b> (23530645)..... <b>BF5815</b> <b>Radial Seal Air</b> (Don. P534925)... <b>[2] RS3534</b> <b>Radial Seal Air</b> (Don. P534816)... <b>[2] RS3539</b> <b>Radial Seal XP Air</b> (Don. P534816)..... <b>[2] RS3539XP</b> <b>Std. Air</b> (Nelson 70076N)..... <b>[2] PA2493</b> <b>Cab Air</b> (Alliance RD3-8416-0).... <b>PA5318</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (w/Chemical)..... <b>BW5137</b> <b>Coolant</b> (Controlled Release) (23516489)..... <b>BW5200</b>	4900, 4900E, 4900EX, 4900FA, 4900SA w/Cat C15 (14.6L) Eng. (To 1/2004) <b>Lube</b> (1R0716)..... <b>B99 +</b> <b>Fuel/Water Separator</b> (w/Drain) (Racor R50419)..... <b>BF1347</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R50419)..... <b>BF1347-O</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (Racor R50419)..... <b>BF1373-SP</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19624)..... <b>PF7748</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (17001-4406)..... <b>BF1259</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (Racor S3226P)..... <b>BF1346</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Racor S3226P)..... <b>BF1346-O</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>WESTERN STAR Trucks (cont'd)</b>	<b>WESTERN STAR Trucks (cont'd)</b>	<b>WESTERN STAR Trucks (cont'd)</b>
4900, 4900E, 4900EX, 4900FA, 4900SA w/Cat C15 (14.6L) Eng. (To 1/2004) (Cont'd)	4900, 4900E, 4900EX, 4900FA, 4900SA w/Cat C15 (14.6L) Eng. (1/2004-on) (Cont'd)	4900E w/Cat C10 (10.3L) Eng. (Cont'd)
<b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (Racor S3226P).. <b>BF1346-SP</b>	<b>Radial Seal XP Air</b> (Don. P534816)..... <b>[2] RS3539XP</b>	<b>Fuel Spin-on</b> (Standard Vers.) (1R1712)..... <b>BF614 +</b>
<b>Fuel/Water Separator Spin-on</b> (Racor R90T)..... <b>BF1390-O</b>	<b>Cab Air</b> (Alliance RD3-8416-0)..... <b>PA5318</b>	<b>Fuel Spin-on</b> (High Efficiency Vers.) (1R0749)..... <b>BF7587 +</b>
<b>Fuel/Water Separator</b> (Alliance ABPN122R50424)..... <b>BF46163-O</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>
<b>Fuel</b> (1R0749)..... <b>BF7587 +</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Trans. Ele. (2 In. Kit)</b> (Allison 29548987)..... <b>PT9416-MPG KIT</b>
<b>Std. Air</b> (Nelson 70076N)..... <b>[2] PA2493</b>	<b>Breather</b> (2007-on) (296-8325).... <b>CV15008</b>	<b>Trans. Ele. (4 In. Kit)</b> (Allison 29548988)..... <b>PT9415-MPG KIT</b>
<b>Radial Seal Air</b> (Don. P534925).... <b>[2] RS3534</b>	<b>Trans. Ele. (2 In. Kit)</b> (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>
<b>Radial Seal Air</b> (Don. P534816).... <b>[2] RS3539</b>	<b>Trans. Ele. (4 In. Kit)</b> (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
<b>Radial Seal XP Air</b> (Don. P534816)..... <b>[2] RS3539XP</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
<b>Cab Air</b> (Alliance RD3-8416-0)..... <b>PA5318</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Steering</b> (Nelson 84148A)..... <b>P528</b>
<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>Steering</b> (Nelson 84365A)..... <b>PT951 +</b>	<b>Steering</b> (Nelson 84365A)..... <b>PT951 +</b>
<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Some Rear Axle</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Some Rear Axle</b> (Meritor 3280-V-8394)..... <b>B233</b>
<b>Breather</b> (2007-on) (296-8325).... <b>CV15008</b>	4900, 4900E, 4900EX, 4900FA, 4900SA w/Cummins N14 (14.0L) Eng.	4900E w/Cat C16 (15.8L) Eng.
<b>Trans. Ele. (2 In. Kit)</b> (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>F-F Lube</b> ..... <b>B196 +</b>	<b>Lube</b> (1R0716)..... <b>B99 +</b>
<b>Trans. Ele. (4 In. Kit)</b> (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>B-P Lube</b> ..... <b>B7577</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (1335673)..... <b>BF1395-O</b>
<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>Dual-Flow Lube</b> ..... <b>BD103 +</b>	<b>Fuel/Water Separator</b> (Alliance ABPN122R50551)..... <b>BF46016-O</b>
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	<b>Fuel/Water Separator</b> ..... <b>BF1259</b>	<b>Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b>
<b>Steering</b> (Nelson 84148A)..... <b>P528</b>	<b>Fuel Spin-on</b> ..... <b>BF957-D +</b>	<b>Fuel Spin-on</b> (Standard Vers.) (1R1712)..... <b>BF614 +</b>
<b>Steering</b> (Nelson 84365A)..... <b>PT951 +</b>	<b>Air</b> (Nelson 70076N)..... <b>[2] PA2493</b>	<b>Fuel Spin-on</b> (High Efficiency Vers.) (1R0749)..... <b>BF7587 +</b>
<b>Some Rear Axle</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>
4900, 4900E, 4900EX, 4900FA, 4900SA w/Cat C15 (14.6L) Eng. (1/2004-on)	<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	<b>Trans. Ele. (2 In. Kit)</b> (Allison 29548987)..... <b>PT9416-MPG KIT</b>
<b>Lube</b> (1R1808)..... <b>B7299 +</b>	<b>Steering</b> (Nelson 87972A)..... <b>PT9386-MPG</b>	<b>Trans. Ele. (4 In. Kit)</b> (Allison 29548988)..... <b>PT9415-MPG KIT</b>
<b>Fuel/Water Separator</b> (w/Drain) (Racor R50419)..... <b>BF1347</b>	<b>Some Differential</b> (Meritor 3280-V-8394)..... <b>B233</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (Racor R50419)..... <b>BF1347-O</b>	4900, 4900FA, 4900SA w/Cummins M11 (10.8L) Eng.	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
<b>Fuel/Water Separator</b> (w/Sensor Port) (Racor R50419)..... <b>BF1373-SP</b>	<b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b>	4900E w/Cat 3126 (7.2L) Eng.
<b>Fuel/Water Separator Ele.</b> (Fleetguard FS19624)..... <b>PF7748</b>	<b>Fuel/Water Separator</b> (3329289). <b>BF1259</b>	<b>Lube</b> (Standard Vers.) (1R0739).. <b>B76 +</b>
<b>Fuel/Water Separator Spin-on</b> (w/Drain) (170014406)..... <b>BF1259</b>	<b>Fuel/Water Separator</b> (Alliance ABPN122R50551)..... <b>BF46016-O</b>	<b>Lube</b> (Severe Service) (1R0739).. <b>B76-SS +</b>
<b>Fuel/Water Separator Spin-on</b> (w/Drain) (Racor S3226P)..... <b>BF1346</b>	4900E w/Cat C10 (10.3L) Eng.	<b>Fuel/Water Separator</b> (1752949). <b>BF1268</b>
<b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (Racor S3226P)..... <b>BF1346-O</b>	<b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99 +</b>	<b>Fuel/Water Separator</b> (2568753). <b>BF1259</b>
<b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (Racor S3226P).. <b>BF1346-SP</b>	<b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b>	<b>Fuel/Water Separator</b> (w/Sensor Port) (1986378)..... <b>BF7798-SP</b>
<b>Fuel/Water Separator Spin-on</b> (Racor R90T)..... <b>BF1390-O</b>	<b>B-P Lube</b> (1W8845)..... <b>B7577</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (1986378)..... <b>BF7798-O</b>
<b>Fuel/Water Separator</b> (Alliance ABPN122R50424)..... <b>BF46163-O</b>	<b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b>	<b>Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b>
<b>Fuel</b> (1R0749)..... <b>BF7587 +</b>	<b>Fuel/Water Separator</b> (Open End for Bowl) (1335673)..... <b>BF1395-O</b>	<b>Fuel Spin-on</b> (1R0751)..... <b>BF7632</b>
<b>Std. Air</b> (Nelson 70076N)..... <b>[2] PA2493</b>	<b>Fuel/Water Separator</b> (w/Drain) (1335673)..... <b>BF1265</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>
<b>Radial Seal Air</b> (Don. P534925).... <b>[2] RS3534</b>	<b>Fuel/Water Separator</b> (w/Sensor Port) (1335673)..... <b>BF1395-SP</b>	4900E w/Cummins Signature 600 (15.0L) Eng.
<b>Radial Seal Air</b> (Don. P534816).... <b>[2] RS3539</b>	<b>Fuel/Water Separator Spin-on</b> (2568753)..... <b>BF1259</b>	<b>Dual-Flow Lube</b> (Fleetguard LF9000)..... <b>BD7153 +</b>
	<b>Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

WESTERN STAR Trucks (cont'd)	WESTERN STAR Trucks (cont'd)	WESTERN STAR Trucks (cont'd)
4900E w/Detroit Diesel Series 60 (11.1L) & (12.7L) Eng. (To 1993)	4900E w/Detroit Diesel Series 60 (11.1L) & (12.7L) Eng. (1993-on) (Cont'd)	4900EX w/Cat C16 (15.8L) Eng. (Cont'd)
F-F Lube..... B95 +	Air Dryer (AD-9 System) (Bendix 107796)..... BA5377	Fuel/Water Separator (Alliance ABPN122R50551)..... BF46016-O
B-P Lube..... B7577	Coolant (w/Chemical)..... BW5137	Fuel Ele. (9M2342)..... [2] PF935
Fuel/Water Separator Ele. (Fleetguard FS19624)..... PF7748	Coolant (Controlled Release) (23516489)..... BW5200	Fuel Spin-on (Standard Vers.) (1R1712)..... BF614 +
Fuel/Water Separator Spin-on (w/Drain) (23512317)..... BF5813 +	Coolant (w/o Chemical) (Fleetguard WF2077)..... B5134 +	Fuel Spin-on (High Efficiency Vers.) (1R0749)..... BF7587 +
Fuel/Water Separator Spin-on (Open End for Bowl) (23512317).. BF5813-O +	Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	Air Dryer (AD-IS System) (Bendix 5008414)..... BA5374 +
P. Fuel..... BF5800 +	Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Trans. Ele. (2 In. Kit) (Allison 29548987)..... PT9416-MPG KIT
S. Fuel (23533726)..... BF5816	Trans. Spin-on (Fuller 4304827).. BT223	Trans. Ele. (4 In. Kit) (Allison 29548988)..... PT9415-MPG KIT
S. Fuel (23530645)..... BF5815	Opt. Trans. Spin-on (Fuller 17237)..... B2 +	Trans. Spin-on (Fuller 4304827).. BT223
Radial Seal Air (Don. P534925)... [2] RS3534	Steering (Nelson 84148A)..... P528	Opt. Trans. Spin-on (Fuller 17237)..... B2 +
Radial Seal Air (Don. P534816)... [2] RS3539	Some Rear Axle (Meritor 3280-V-8394)..... B233	4900EX w/Cummins ISX 15.0 (14.9L) Eng. (2019)
Radial Seal XP Air (Don. P534816)..... [2] RS3539XP	4900EX w/Cat C10 (10.3L) Eng.	Dual-Flow Lube (4367100)..... BD50000
Std. Air (Nelson 70076N)..... [2] PA2493	F-F Lube (Std. Version) (1R0716)..... B99 +	Fuel/Water Separator (Alliance ABPN122R50550)..... BF9871-O
Cab Air (Alliance RD3-8416-0).... PA5318	F-F Lube (High Efficiency Vers.) (1R1808)..... B7299 +	Fuel (5365988)..... BF46129 +
Air Dryer (AD-IS System) (Bendix 5008414)..... BA5374 +	B-P Lube (1W8845)..... B7577	Radial Seal Air (Don. P534925)... RS3534
Air Dryer (AD-9 System) (Bendix 107796)..... BA5377	Fuel/Water Separator Ele. (8N0205)..... PF316	Air Dryer (AD-9Si System) (Bendix 5008414)..... BA5374 +
Coolant (w/Chemical)..... BW5137	Fuel/Water Separator (Open End for Bowl) (1335673)..... BF1395-O	Trans. Ele. (2 In. Kit) (Allison 29558117)..... PT9416-MPG KIT
Coolant (Controlled Release) (23516489)..... BW5200	Fuel/Water Separator (w/Drain) (1335673)..... BF1265	Trans. Ele. (4 In. Kit) (Allison 29558118)..... PT9415-MPG KIT
Coolant (w/o Chemical) (Fleetguard WF2077)..... B5134 +	Fuel/Water Separator (w/Sensor Port) (1335673)..... BF1395-SP	Trans. Spin-on (Fuller 4304827).. BT223
Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	Fuel/Water Separator Spin-on (2568753)..... BF1259	Steering (1417927000)..... PT23629
Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Fuel Ele. (9M2342)..... [2] PF935	Opt. Rear Axle (Meritor 3280V8394)..... B233
Trans. Spin-on (Fuller 4304827).. BT223	Fuel Spin-on (Standard Vers.) (1R1712)..... BF614 +	4900EX w/Cummins X15 (14.9L) Eng. (2018)
Opt. Trans. Spin-on (Fuller 17237)..... B2 +	Fuel Spin-on (High Efficiency Vers.) (1R0749)..... BF7587 +	Dual-Flow Lube (Fleetguard LF14000NN)..... BD50000
Steering (Nelson 84148A)..... P528	Air Dryer (AD-IS System) (Bendix 5008414)..... BA5374 +	Fuel/Water Separator (Fleetguard FS19765)..... PF7930
Some Rear Axle (Meritor 3280-V-8394)..... B233	Trans. Ele. (2 In. Kit) (Allison 29548987)..... PT9416-MPG KIT	Fuel (Fleetguard FF5825NN)..... BF46129
4900E w/Detroit Diesel Series 60 (11.1L) & (12.7L) Eng. (1993-on)	Trans. Ele. (4 In. Kit) (Allison 29548988)..... PT9415-MPG KIT	Radial Seal Air (Don. P534816)... RS3539
Lube..... [2] B495	Opt. Trans. Spin-on (Fuller 17237)..... B2 +	Radial Seal XP Air (Don. P534816)..... RS3539XP
Fuel/Water Separator Ele. (Fleetguard FS19624)..... PF7748	4900EX w/Cat C16 (15.8L) Eng.	Air Dryer (Bendix 107796PG)..... BA5377
Fuel/Water Separator Spin-on (w/Drain) (23512317)..... BF5813 +	Lube (1R0716)..... B99 +	Trans. Ele. (2 In. Kit) (Allison 29558117)..... PT9416-MPG KIT
Fuel/Water Separator Spin-on (Open End for Bowl) (23512317).. BF5813-O +	Fuel/Water Separator (Open End for Bowl) (1335673)..... BF1395-O	Trans. Ele. (4 In. Kit) (Allison 29558118)..... PT9415-MPG KIT
P. Fuel..... BF5800 +	Fuel/Water Separator (2568753)..... BF1259	Trans. Spin-on (Fuller 4304827).. BT223
S. Fuel (23533726)..... BF5816	Fuel/Water Separator (w/Drain) (1335673)..... BF1265	Steering (Nelson 84365A)..... PT951 +
S. Fuel (23530645)..... BF5815	Fuel/Water Separator (w/Sensor Port) (1335673)..... BF1395-SP	Diesel Exhaust Fluid (4388378).. PE17002 KIT
Radial Seal Air (Don. P534925)... [2] RS3534	4900EX w/Cummins X15 (14.9L) Eng. (2019)	4900EX w/Cummins X15 (14.9L) Eng. (2019)
Radial Seal Air (Don. P534816)... [2] RS3539	Dual-Flow Lube (4367100)..... BD50000	Dual-Flow Lube (4367100)..... BD50000
Radial Seal XP Air (Don. P534816)..... [2] RS3539XP	Fuel/Water Separator (Alliance ABPN122R50550)..... BF9871-O	Fuel/Water Separator (Alliance ABPN122R50550)..... BF9871-O
Std. Air (Nelson 70076N)..... [2] PA2493	Fuel (5365988)..... BF46129 +	Fuel (5365988)..... BF46129 +
Cab Air (Alliance RD3-8416-0).... PA5318	Radial Seal Air (Don. P534925)... RS3534	Radial Seal Air (Don. P534925)... RS3534
Air Dryer (AD-IS System) (Bendix 5008414)..... BA5374 +	Air Dryer (AD-9Si System) (Bendix 5008414)..... BA5374 +	Air Dryer (AD-9Si System) (Bendix 5008414)..... BA5374 +

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

WESTERN STAR Trucks (cont'd)	WESTERN STAR Trucks (cont'd)	WESTERN STAR Trucks (cont'd)
4900EX w/Cummins X15 (14.9L) Eng. (2019) (Cont'd) Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Steering (1417927000)..... <b>PT23629</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	4900EX w/Detroit DD15 (14.8L) Eng. (2019) (Cont'd) Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Steering (1417927000)..... <b>PT23629</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b> Diesel Exhaust Fluid (A0001421089)..... <b>PE17002 KIT</b>	4900EX w/Detroit DD16 (15.6L) Eng. (2019) (Cont'd) Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b> Diesel Exhaust Fluid (A0001421089)..... <b>PE17002 KIT</b>
4900EX w/Cummins X15 (14.9L) Eng. (2020) Dual-Flow Lube (4367100)..... <b>BD50000</b> Fuel (5365988)..... <b>BF46129</b> Radial Seal Air (Don. P534925).. <b>[2] RS3534</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Steering (1417927000)..... <b>PT23629</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	4900EX w/Detroit DD15 (14.8L) Eng. (2020) Lube (To Eng. S/N A472910S0690710) (A4731800409)..... <b>P7505</b> Fuel/Water Separator (A0000905051)..... <b>PF46145</b> Fuel (A4700903151)..... <b>PF9908 KIT</b> Radial Seal Air (Don. P534925).. <b>[2] RS3534</b> Trans. (Fuller 4304827)..... <b>BT223</b> Steering (1417927000)..... <b>PT23629</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	4900EX w/Detroit DD16 (15.6L) Eng. (2020) Lube (To Eng. S/N A472910S0690710) (A4731800409)..... <b>P7505</b> Fuel/Water Separator (A0000905051)..... <b>PF46145</b> Fuel (A4700903151)..... <b>PF9908 KIT</b> Radial Seal Air (Don. P534925).. <b>[2] RS3534</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Steering (1417927000)..... <b>PT23629</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b> Diesel Exhaust Fluid (A0001421089)..... <b>PE17002 KIT</b>
4900EX w/Cummins X15 (14.9L) Eng. (2021) Lube (5575298)..... <b>B40145</b> Fuel (5365988)..... <b>BF46129</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	4900EX w/Detroit DD15 (14.8L) Eng. (2021) Fuel (A4700903151)..... <b>PF9908 KIT</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	4900EX w/Detroit DD16 (15.6L) Eng. (2021) Fuel/Water Separator (A0000905051)..... <b>PF46145</b> Fuel (A4700903151)..... <b>PF9908 KIT</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>
4900EX w/Cummins X15 (14.9L) Eng. (2022) Lube (5575298)..... <b>B40145</b> Fuel (5575143)..... <b>BF46248</b>	4900EX w/Detroit DD15 (14.8L) Eng. (2022) Trans. (Fuller 4304827)..... <b>BT223</b>	4900EX w/Detroit DD16 (15.6L) Eng. (2022) Fuel (A4700903151)..... <b>PF9908 KIT</b>
4900EX w/Detroit DD15 (14.8L) Eng. (2018) Lube (A4731800409)..... <b>P7505</b> Fuel/Water Separator (A0000905051)..... <b>PF46145</b> Fuel (A4720900651)..... <b>PF9908 KIT</b> Radial Seal Air (Don. P534816).. <b>RS3539</b> Radial Seal XP Air (Don. P534816)..... <b>RS3539XP</b> Air Dryer (Bendix 107796PG)..... <b>BA5377</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Steering (Nelson 84365A)..... <b>PT951 +</b> Diesel Exhaust Fluid (A0001421089)..... <b>PE17002 KIT</b>	4900EX w/Detroit DD15 (14.8L) Eng. (2018) Lube (A4731800409)..... <b>P7505</b> Fuel/Water Separator (A0000905051)..... <b>PF46145</b> Fuel (A4720900651)..... <b>PF9908 KIT</b> Radial Seal Air (Don. P534816).. <b>RS3539</b> Radial Seal XP Air (Don. P534816)..... <b>RS3539XP</b> Air Dryer (Bendix 107796PG)..... <b>BA5377</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b> Steering (Nelson 84365A)..... <b>PT951 +</b> Diesel Exhaust Fluid (A0001421089)..... <b>PE17002 KIT</b>	4900EX w/Detroit Diesel Series 60 (11.1L), (12.7L) & (14.0L) Eng. (To 1993) F-F Lube..... <b>B95 +</b> B-P Lube..... <b>B7577</b> Fuel/Water Separator Ele. (Fleetguard FS19624)..... <b>PF7748</b> Fuel/Water Separator Spin-on (w/Drain) (23512317)..... <b>BF5813 +</b> Fuel/Water Separator Spin-on (Open End for Bowl) (23512317).. <b>BF5813-O +</b> P. Fuel..... <b>BF5800 +</b> S. Fuel (23533726)..... <b>BF5816</b> S. Fuel (23530645)..... <b>BF5815</b> Radial Seal Air (Don. P534925).. <b>[2] RS3534</b> Radial Seal Air (Don. P534816).. <b>[2] RS3539</b> Radial Seal XP Air (Don. P534816)..... <b>[2] RS3539XP</b> Std. Air (Nelson 70076N)..... <b>[2] PA2493</b> Cab Air (Alliance RD3-8416-0)..... <b>PA5318</b> Air Dryer (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b> Coolant (w/Chemical)..... <b>BW5137</b>
4900EX w/Detroit DD15 (14.8L) Eng. (2019) Lube (A4731800109)..... <b>P7505</b> Fuel/Water Separator (A0000905051)..... <b>PF46145</b> Fuel (A4720900651)..... <b>PF9908 KIT</b> Radial Seal Air (Don. P534925).. <b>RS3534</b> Air Dryer (AD-9Si System) (Bendix 5008414)..... <b>BA5374 +</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Steering (1417927000)..... <b>PT23629</b>	4900EX w/Detroit DD16 (15.6L) Eng. (2019) Lube (A4731800109)..... <b>P7505</b> Fuel/Water Separator (A0000905051)..... <b>PF46145</b> Fuel Kit (A4720900651)..... <b>PF9908 KIT</b> Radial Seal Air (Don. P534925).. <b>RS3534</b> Air Dryer (AD-9Si System) (Bendix 5008414)..... <b>BA5374 +</b> Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> Trans. Spin-on (Fuller 4304827).. <b>BT223</b> Steering (1417927000)..... <b>PT23629</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

WESTERN STAR Trucks (cont'd)	WESTERN STAR Trucks (cont'd)	WESTERN STAR Trucks (cont'd)
4900EX w/Detroit Diesel Series 60 (11.1L), (12.7L) & (14.0L) Eng. (To 1993) (Cont'd)	4900EX, 4900FA, 4900SA w/Cummins ISX 15.0 (14.9L) Eng. (2002-17) (Cont'd)	4900EX, 4900FA, 4900SA w/Detroit Diesel DD15 (14.8L) Eng. (2009-17) (Cont'd)
Coolant (Controlled Release) (23516489).....	Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN).....	25 13/16 In. Radial Seal Air (Don. P534925).....
BW5200	BD50000	[2] RS3534
Coolant (w/o Chemical) (Fleetguard WF2077).....	Fuel/Water Separator Ele. (Fleetguard FS19764).....	Std. Air (Don. P153551).....
B5134 +	PF9814	PA2705
Trans. Ele. (2 In. Kit) (Allison 29540493).....	Fuel/Water Separator Spin-on (Fleetguard FS1040).....	Cab Air (Alliance RD-38416-0).....
PT9416-MPG KIT	BF1277-SPS	PA5318
Trans. Ele. (4 In. Kit) (Allison 29540494).....	Fuel/Water Separator Spin-on (Fleetguard FS1007).....	Air Dryer (AD-9 System) (Bendix 107794).....
PT9415-MPG KIT	BF1274-SP	BA5377
Trans. Spin-on (Fuller 4304827)..	Fuel/Water Separator Spin-on (Alliance ABPN122R50550).....	Air Dryer (SS1200 System) (Wabco R950011).....
BT223	BF9871-O	BA5374 +
Opt. Trans. Spin-on (Fuller 17237).....	8 27/32 In. Fuel (Standard Vers.) (Fleetguard FF5776).....	Air Dryer (Wabco R950068).....
B2 +	BF9885 +	BA5379 +
Steering (Nelson 84148A).....	Fuel Spin-on (Upgrade) (FF5825NN).....	Air Dryer (AD-IS System) (Bendix 5008414).....
P528	BF46129	BA5374 +
Some Rear Axle (Meritor 3280-V-8394).....	Fuel (Upgrade) (Fleetguard FF5811).....	Coolant (A4722030255).....
B233	BF46179	P5092
4900EX w/Detroit Diesel Series 60 (11.1L), (12.7L) & (14.0L) Eng. (1993-on)	11 9/16 In. Fuel (Fleetguard FF5686).....	Trans. Ele. (2 In. Kit) (Allison 29548987).....
Lube.....	Radial Seal Air (Don. P534816)...	PT9416-MPG KIT
[2] B495	[2] RS3539	Trans. Ele. (4 In. Kit) (Allison 29548988).....
Fuel/Water Separator Ele. (Fleetguard FS19624).....	Radial Seal XP Air (Don. P534816).....	PT9415-MPG KIT
PF7748	[2] RS3539XP	Trans. Spin-on (Fuller 4304827)..
Fuel/Water Separator Spin-on (w/Drain) (23512317).....	Std. Air (Don. P153551).....	BT223
BF5813 +	PA2705	Opt. Trans. Spin-on (Fuller 17237).....
Fuel/Water Separator Spin-on (Open End for Bowl) (23512317)..	Air Dryer (AD-9 System) (Bendix 107796).....	B2 +
BF5813-O +	BA5377	B2 +
BF5800 +	BA5374 +	Steering (Nelson 84365A).....
BF5816	BA5379 +	PT951 +
BF5815	CV15000	P528
[2] RS3534	Coolant (w/o Chemical) (Fleetguard WF2127).....	BT9388
[2] RS3539	B5087	PT23629
Radial Seal Air (Don. P534925)...	Coolant (w/Chemical) (Fleetguard WF2126).....	PE17000
[2] RS3539	BW5086	4900EX, 4900FA, 4900SA w/Detroit Diesel DD16 (15.6L) Eng. (2010-17)
[2] RS3539XP	PT9416-MPG KIT	Lube (A4731800109).....
[2] PA2493	PT9415-MPG KIT	P7505
PA5318	BT223	Fuel/Water Separator (A0000903651).....
Air Dryer (AD-IS System) (Bendix 5008414).....	B2 +	PF9804
BA5374 +	PT951 +	PF9908 KIT
Air Dryer (AD-9 System) (Bendix 107796).....	P528	PF9924 KIT
BA5377	BT9388	23 23/32 In. Radial Seal Air (Don. P534816).....
BA5379 +	PT23629	[2] RS3539
BW5137	PE17000	23 23/32 In. Radial Seal XP Air (Don. P534816).....
BW5200	4900EX, 4900FA, 4900SA w/Detroit Diesel DD15 (14.8L) Eng. (2009-17)	[2] RS3539XP
B5134 +	Lube (A4731800109).....	[2] RS3534
PT9416-MPG KIT	Fuel/Water Separator (A0000903651).....	Air Dryer (AD-9 System) (Bendix 107794).....
PT9415-MPG KIT	PF9804	BA5377
BT223	PF9908 KIT	Air Dryer (SS1200 System) (Wabco R950011).....
Opt. Trans. Spin-on (Fuller 17237).....	PF9924 KIT	BA5374 +
B2 +	[2] RS3539	BA5379 +
Steering (Nelson 84148A).....	23 13/16 In. Radial Seal Air (Don. P534816).....	P5092
P528	[2] RS3539	Trans. Ele. (2 In. Kit) (Allison 29548987).....
Some Rear Axle (Meritor 3280-V-8394).....	23 13/16 In. Radial Seal XP Air (Don. P534816).....	PT9416-MPG KIT
B233	[2] RS3539XP	Trans. Ele. (4 In. Kit) (Allison 29548988).....
4900EX, 4900FA, 4900SA w/Cummins ISX 15.0 (14.9L) Eng. (2002-17)		PT9415-MPG KIT
Dual-Flow Lube (3401544).....		Trans. Spin-on (Fuller 4304827)..
BD7309 +		BT223
Dual-Flow Lube (Fleetguard LF9080).....		Opt. Trans. Spin-on (Fuller 17237).....
BD7154 +		B2 +
B40142 +		Steering (Nelson 84365A).....
Lube (Upgrade) (3401544).....		PT951 +
		P528
		BT9388
		PT23629

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

WESTERN STAR Trucks (cont'd)	WESTERN STAR Trucks (cont'd)	WESTERN STAR Trucks (cont'd)
4900EX, 4900FA, 4900SA w/Detroit Diesel DD16 (15.6L) Eng. (2010-17) (Cont'd) <b>Diesel Exhaust Fluid</b> (A0001420789)..... <b>PE17002 KIT</b>	4900FA w/Cummins ISX 15.0 / X15 (14.9L) Eng. (2018) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (Alliance ABPN122R50550)..... <b>BF9871-O</b> <b>Fuel</b> (Fleetguard FF5825NN)..... <b>BF46129 +</b> <b>Radial Seal Air</b> (Don. P534816)... <b>RS3539</b> <b>Radial Seal XP Air</b> (Don. P534816)..... <b>RS3539XP</b> <b>Air Dryer</b> (Bendix 107796PG)..... <b>BA5377</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (1417927000)..... <b>PT23629</b>	4900FA w/Cummins X15 (14.9L) Eng. (2021) <b>Lube</b> (5575298)..... <b>B40145</b> <b>Fuel</b> (5365988)..... <b>BF46129</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
4900FA w/Cat C10 (10.3L) Eng. <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99 +</b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> <b>B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (1335673)..... <b>BF1395-O</b> <b>Fuel/Water Separator</b> (w/Drain) (1335673)..... <b>BF1265</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (1335673)..... <b>BF1395-SP</b> <b>Fuel/Water Separator Spin-on</b> (2568753)..... <b>BF1259</b> <b>Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (Standard Vers.) (1R1712)..... <b>BF614 +</b> <b>Fuel Spin-on</b> (High Efficiency Vers.) (1R0749)..... <b>BF7587 +</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Trans. Ele. (2 In. Kit)</b> (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele. (4 In. Kit)</b> (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	4900FA w/Cummins X15 (14.9L) Eng. (2019) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (Alliance ABPN122R50550)..... <b>BF9871-O</b> <b>Fuel</b> (5365988)..... <b>BF46129 +</b> <b>Radial Seal Air</b> (Don. P534816)... <b>[2] RS3539</b> <b>Radial Seal XP Air</b> (Don. P534816)..... <b>[2] RS3539XP</b> <b>Air Dryer</b> (AD-9Si System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	4900FA w/Cummins X15 (14.9L) Eng. (2022) <b>Lube</b> (5575298)..... <b>B40145</b> <b>Fuel</b> (5575143)..... <b>BF46248</b>
4900FA w/Cat C16 (15.8L) Eng. <b>Lube</b> (1R0716)..... <b>B99 +</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (1335673)..... <b>BF1395-O</b> <b>Fuel/Water Separator</b> (w/Drain) (1335673)..... <b>BF1265</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (1335673)..... <b>BF1395-SP</b> <b>Fuel/Water Separator</b> (2568753)..... <b>BF1259</b> <b>Fuel/Water Separator</b> (Alliance ABPN122R50551)..... <b>BF46016-O</b> <b>Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (Standard Vers.) (1R1712)..... <b>BF614 +</b> <b>Fuel Spin-on</b> (High Efficiency Vers.) (1R0749)..... <b>BF7587 +</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Trans. Ele. (2 In. Kit)</b> (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele. (4 In. Kit)</b> (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	4900FA w/Cummins X15 (14.9L) Eng. (2020) <b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b> <b>Fuel/Water Separator</b> (Alliance N122R50550)..... <b>BF9871-O</b> <b>Fuel</b> (5365988)..... <b>BF46129</b> <b>Radial Seal Air</b> (Don. P534816)... <b>[2] RS3539</b> <b>Radial Seal XP Air</b> (Don. P534816)..... <b>[2] RS3539XP</b> <b>Air Dryer</b> (Wabco R950068A)..... <b>BA5379</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	4900FA w/Detroit DD13 (12.8L) Eng. (2018) <b>Lube</b> (A4731800109)..... <b>P7505</b> <b>Fuel/Water Separator</b> (A0000905051)..... <b>PF46145</b> <b>Fuel</b> (A4720900651)..... <b>PF9908 KIT</b> <b>Radial Seal Air</b> (Don. P534816)... <b>RS3539</b> <b>Radial Seal XP Air</b> (Don. P534816)..... <b>RS3539XP</b> <b>Air Dryer</b> (Bendix 107796PG)..... <b>BA5377</b> <b>Coolant</b> (A4722030355)..... <b>P5092</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b>
	4900FA w/Detroit DD13 (12.8L) Eng. (2019) <b>Lube</b> (A4731800409)..... <b>P7505</b> <b>Fuel/Water Separator</b> (A0000905051)..... <b>PF46145</b> <b>Fuel Kit</b> (A4720900651)..... <b>PF9908 KIT</b> <b>Radial Seal Air</b> (Don. P534816)... <b>[2] RS3539</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



WESTERN STAR Trucks (cont'd)	WESTERN STAR Trucks (cont'd)	WESTERN STAR Trucks (cont'd)
4900FA w/Detroit DD13 (12.8L) Eng. (2019) (Cont'd)	4900FA w/Detroit DD15 (14.8L) Eng. (2018) (Cont'd)	4900FA w/Detroit DD16 (15.6L) Eng. (2018) (Cont'd)
Radial Seal XP Air (Don. P534816)..... [2] RS3539XP	Steering (1417927000)..... PT23629	Diesel Exhaust Fluid (A0001421089)..... PE17002 KIT
Air Dryer (AD-9Si System) (Bendix 5008414)..... BA5374 +	Diesel Exhaust Fluid (A0001421089)..... PE17002 KIT	4900FA w/Detroit DD16 (15.6L) Eng. (2019)
Trans. Ele. (2 In. Kit) (Allison 29558117)..... PT9416-MPG KIT	4900FA w/Detroit DD15 (14.8L) Eng. (2019)	Lube (A4731800109)..... P7505
Trans. Ele. (4 In. Kit) (Allison 29558118)..... PT9415-MPG KIT	Lube (A4731800109)..... P7505	Fuel/Water Separator (A0000905051)..... PF46145
Trans. Spin-on (Fuller 4304827).. BT223	Fuel/Water Separator (A0000905051)..... PF46145	Fuel Kit (A4720900651)..... PF9908 KIT
Opt. Trans. Spin-on (Fuller 17237)..... B2	Fuel Kit (A4720900651)..... PF9908 KIT	Radial Seal Air (Don. P534816)... [2] RS3539
Steering (1417927000)..... PT23629	Radial Seal Air (Don. P534816).. [2] RS3539	Radial Seal XP Air (Don. P534816)..... [2] RS3539XP
Opt. Rear Axle (Meritor 3280V8394)..... B233	Radial Seal XP Air (Don. P534816)..... [2] RS3539XP	Air Dryer (Bendix 107796)..... BA5377
Diesel Exhaust Fluid (A0001421089)..... PE17002 KIT	Air Dryer (AD-9Si System) (Bendix 5008414)..... BA5374 +	Trans. Ele. (2 In. Kit) (Allison 29558117)..... PT9416-MPG KIT
4900FA w/Detroit DD13 (12.8L) Eng. (2020)	Trans. Ele. (2 In. Kit) (Allison 29558117)..... PT9416-MPG KIT	Trans. Ele. (4 In. Kit) (Allison 29558118)..... PT9415-MPG KIT
Lube (To Eng. S/N A472910S0690710) (A4731800409)..... P7505	Trans. Ele. (4 In. Kit) (Allison 29558118)..... PT9415-MPG KIT	Trans. Spin-on (Fuller 4304827).. BT223
Fuel/Water Separator (A0000905051)..... PF46145	Trans. Spin-on (Fuller 4304827).. BT223	Opt. Trans. Spin-on (Fuller 17237)..... B2 +
Fuel (A4700903151)..... PF9908 KIT	Steering (1417927000)..... PT23629	Steering (1417927000)..... PT23629
Radial Seal Air (Don. P534816)... [2] RS3539	Opt. Rear Axle (Meritor 3280V8394)..... B233	Opt. Rear Axle (Meritor 3280V8394)..... B233
Radial Seal XP Air (Don. P534816)..... [2] RS3539XP	Diesel Exhaust Fluid (A0001421089)..... PE17002 KIT	Diesel Exhaust Fluid (A0001421089)..... PE17002 KIT
Air Dryer (Wabco R950068A)..... BA5379	4900FA w/Detroit DD15 (14.8L) Eng. (2020)	4900FA w/Detroit DD16 (15.6L) Eng. (2020)
Trans. Ele. (2 In. Kit) (Allison 29558117)..... PT9416-MPG KIT	Lube (To Eng. S/N A472910S0690710) (A4731800409)..... P7505	Lube (To Eng. S/N A472910S0690710) (A4731800409)..... P7505
Trans. Ele. (4 In. Kit) (Allison 29558118)..... PT9415-MPG KIT	Fuel/Water Separator (A0000905051)..... PF46145	Fuel/Water Separator (A0000905051)..... PF46145
Trans. Spin-on (Fuller 4304827).. BT223	Fuel (A4700903151)..... PF9908 KIT	Fuel (A4700903151)..... PF9908 KIT
Opt. Trans. Spin-on (Fuller 17237)..... B2	Radial Seal Air (Don. P534816)... [2] RS3539	Radial Seal Air (Don. P534816)... [2] RS3539
Steering (1417927000)..... PT23629	Radial Seal XP Air (Don. P534816)..... [2] RS3539XP	Radial Seal XP Air (Don. P534816)..... [2] RS3539XP
Opt. Rear Axle (Meritor 3280V8394)..... B233	Air Dryer (Wabco R950068A)..... BA5379	Air Dryer (Wabco R950068A)..... BA5379
4900FA w/Detroit DD13 (12.8L) Eng. (2021)	Trans. (Fuller 4304827)..... BT223	Trans. Ele. (2 In. Kit) (Allison 29558117)..... PT9416-MPG KIT
Fuel (A4700903151)..... PF9908 KIT	Steering (1417927000)..... PT23629	Trans. Ele. (4 In. Kit) (Allison 29558118)..... PT9415-MPG KIT
Trans. (Fuller 4304827)..... BT223	Opt. Rear Axle (Meritor 3280V8394)..... B233	Trans. Spin-on (Fuller 4304827).. BT223
Opt. Rear Axle (Meritor 3280V8394)..... B233	4900FA w/Detroit DD15 (14.8L) Eng. (2021)	Steering (1417927000)..... PT23629
4900FA w/Detroit DD13 (12.8L) Eng. (2022)	Fuel (A4700903151)..... PF9908 KIT	Opt. Rear Axle (Meritor 3280V8394)..... B233
Fuel (A4700903151)..... PF9908 KIT	Trans. (Fuller 4304827)..... BT223	Diesel Exhaust Fluid (A0001421089)..... PE17002 KIT
4900FA w/Detroit DD15 (14.8L) Eng. (2018)	Opt. Rear Axle (Meritor 3280V8394)..... B233	4900FA w/Detroit DD16 (15.6L) Eng. (2021)
Lube (A4731800109)..... P7505	4900FA w/Detroit DD16 (15.6L) Eng. (2018)	Lube (A4731800109)..... P7505
Fuel/Water Separator (A0000905051)..... PF46145	Lube (A4731800109)..... P7505	Fuel/Water Separator (A0000905051)..... PF46145
Fuel (A4720900651)..... PF9908 KIT	Fuel/Water Separator (A0000905051)..... PF46145	Fuel (A4700903151)..... PF9908 KIT
Radial Seal Air (Don. P534816)... [2] RS3539	Fuel (A4720900651)..... PF9908 KIT	Trans. (Fuller 4304827)..... BT223
Radial Seal XP Air (Don. P534816)..... [2] RS3539XP	Radial Seal Air (Don. P534816).. [2] RS3539	Opt. Rear Axle (Meritor 3280V8394)..... B233
Air Dryer (Bendix 107796PG)..... BA5377	Radial Seal XP Air (Don. P534816)..... [2] RS3539XP	4900FA w/Detroit DD16 (15.6L) Eng. (2022)
Trans. Spin-on (Fuller 4304827).. BT223	Air Dryer (Bendix 107796PG)..... BA5377	Fuel/Water Separator (A0000905051)..... PF46145
Opt. Trans. Spin-on (Fuller 17237)..... B2 +	Trans. Spin-on (Fuller 4304827).. BT223	Fuel (A4700903151)..... PF9908 KIT
	Opt. Trans. Spin-on (Fuller 17237)..... B2 +	
	Steering (1417927000)..... PT23629	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

WESTERN STAR Trucks (cont'd)	WESTERN STAR Trucks (cont'd)	WESTERN STAR Trucks (cont'd)
4900FA w/Detroit DD16 (15.6L) Eng. (2022) (Cont'd) Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b>	4900FA w/Detroit Diesel Series 60 (12.7L), & (14.0L) Eng. (1993-on) (Cont'd) <b>Radial Seal XP Air</b> (Don. P534816)..... <b>[2] RS3539XP</b> <b>Std. Air</b> (Nelson 70076N)..... <b>[2] PA2493</b> <b>Cab Air</b> (Alliance RD3-8416-0)..... <b>PA5318</b>	4900FA, 4900SA w/Cat C13 (12.5L) Eng. (1/2004-on) (Cont'd) Trans. Ele. (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> Trans. Ele. (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (Nelson 84148A)..... <b>P528</b> <b>Some Rear Axle</b> (Meritor 3280-V-8394)..... <b>B233</b>
4900FA w/Detroit Diesel Series 60 (12.7L), & (14.0L) Eng. (To 1993) <b>F-F Lube</b> ..... <b>B95 +</b> <b>B-P Lube</b> ..... <b>BF577</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19624)..... <b>PF7748</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (23512317)..... <b>BF5813 +</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (23512317).. <b>BF5813-O +</b> <b>P. Fuel</b> ..... <b>BF5800 +</b> <b>S. Fuel</b> (23533726)..... <b>BF5816</b> <b>S. Fuel</b> (23530645)..... <b>BF5815</b> <b>Radial Seal Air</b> (Don. P534925)... <b>[2] RS3534</b> <b>Radial Seal Air</b> (Don. P534816)... <b>[2] RS3539</b> <b>Radial Seal XP Air</b> (Don. P534816)..... <b>[2] RS3539XP</b> <b>Std. Air</b> (Nelson 70076N)..... <b>[2] PA2493</b> <b>Cab Air</b> (Alliance RD3-8416-0)..... <b>PA5318</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (w/Chemical)..... <b>BW5137</b> <b>Coolant</b> (Controlled Release) (23516489)..... <b>BW5200</b> <b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 84148A)..... <b>P528</b> <b>Some Rear Axle</b> (Meritor 3280-V-8394)..... <b>B233</b>	4900FA, 4900SA w/Cat C11 (11.1L) Eng. <b>Lube</b> (1R1808)..... <b>B7299 +</b> <b>Fuel Spin-on</b> (1R0749)..... <b>BF7587 +</b> 4900FA, 4900SA w/Cat C13 (12.5L) Eng. (To 1/2004) <b>Lube</b> (1R0716)..... <b>B99 +</b> <b>Fuel/Water Separator</b> (Fleetguard FS19624)..... <b>PF7748</b> <b>Fuel Spin-on</b> (1R0749)..... <b>BF7587 +</b> <b>Radial Seal Air</b> (Don. P534816)... <b>[2] RS3539</b> <b>Radial Seal XP Air</b> (Don. P534816)..... <b>[2] RS3539XP</b> <b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Steering</b> (Nelson 84148A)..... <b>P528</b> <b>Some Rear Axle</b> (Meritor 3280-V-8394)..... <b>B233</b>	4900FA, 4900SA w/Cummins ISM 10.8 (10.8L) Eng. <b>Dual-Flow Lube</b> ..... <b>BD7153 +</b> <b>Fuel/Water Separator</b> ..... <b>BF1272-SPS</b>
4900FA w/Detroit Diesel Series 60 (12.7L), & (14.0L) Eng. (1993-on) <b>Lube</b> ..... <b>[2] B495</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19624)..... <b>PF7748</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (23512317)..... <b>BF5813 +</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (23512317).. <b>BF5813-O +</b> <b>P. Fuel</b> ..... <b>BF5800 +</b> <b>S. Fuel</b> (23533726)..... <b>BF5816</b> <b>S. Fuel</b> (23530645)..... <b>BF5815</b> <b>Radial Seal Air</b> (Don. P534925)... <b>[2] RS3534</b> <b>Radial Seal Air</b> (Don. P534816)... <b>[2] RS3539</b>	4900FA, 4900SA w/Cat C13 (12.5L) Eng. (1/2004-on) <b>Lube</b> (1R1808)..... <b>B7299 +</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (170014406)..... <b>BF1259</b> <b>Fuel/Water Separator</b> (Fleetguard FS19624)..... <b>PF7748</b> <b>Fuel Spin-on</b> (1R0749)..... <b>BF7587 +</b> <b>Radial Seal Air</b> (Don. P534816)... <b>[2] RS3539</b> <b>Radial Seal XP Air</b> (Don. P534816)..... <b>[2] RS3539XP</b> <b>Air Dryer</b> (Bendix 107796)..... <b>BA5377</b>	4900FA, 4900SA w/Mercedes-Benz MBE4000 (12.8L) Eng. <b>Lube</b> (1802109)..... <b>P7230</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19624)..... <b>PF7748</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (170014406)..... <b>BF1259</b> <b>Fuel/Water Separator Spin-on</b> (Alliance ABPN122R50551)..... <b>BF46016-O</b> <b>Fuel</b> (5410900151)..... <b>PF7761</b> <b>Air</b> (Nelson 70076N)..... <b>[2] PA2493</b> <b>Air</b> (Don. P153551)..... <b>PA2705</b> <b>Radial Seal Air</b> (Don. P534816)... <b>[2] RS3539</b> <b>Radial Seal XP Air</b> (Don. P534816)..... <b>[2] RS3539XP</b> <b>Cab Air</b> (Alliance RD3-8416-0)..... <b>PA5318</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (Fleetguard WF2077)..... <b>B5134 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 84148A)..... <b>P528</b> <b>Some Rear Axle</b> (Meritor 3280-V-8394)..... <b>B233</b>
	4900SA w/Cat C10 (10.3L) Eng. <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99 +</b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> <b>B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (1335673)..... <b>BF1395-O</b> <b>Fuel/Water Separator</b> (w/Drain) (1335673)..... <b>BF1265</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (1335673)..... <b>BF1395-SP</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

WESTERN STAR Trucks (cont'd)	WESTERN STAR Trucks (cont'd)	WESTERN STAR Trucks (cont'd)
4900SA w/Cat C10 (10.3L) Eng. (Cont'd)	4900SA w/Cat 3126 (7.2L) Eng. (Cont'd)	4900SA w/Cummins X15 (14.9L) Eng. (2020)
<b>Fuel/Water Separator Spin-on</b> (2568753)..... <b>BF1259</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b>
<b>Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b>	<b>Fuel</b> (5365988)..... <b>BF46129</b>
<b>Fuel Spin-on</b> (Standard Vers.) (1R1712)..... <b>BF614+</b>	4900SA w/Cummins ISX 15.0 (14.9L) Eng. (2018)	<b>Radial Seal Air</b> (Don. P534816).. <b>RS3539</b>
<b>Fuel Spin-on</b> (High Efficiency Vers.) (1R0749)..... <b>BF7587+</b>	<b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b>	<b>Radial Seal XP Air</b> (Don. P534816)..... <b>RS3539XP</b>
<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374+</b>	<b>Fuel/Water Separator</b> (Alliance ABPN122R50550)..... <b>BF9871-O</b>	<b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>
<b>Trans. Ele. (2 In. Kit)</b> (Allison 29548987)..... <b>PT9416-MPG KIT</b>	<b>Fuel</b> (Fleetguard FF5825NN)..... <b>BF46129+</b>	<b>Trans. Ele. (4 In. Kit)</b> (Allison 29558118)..... <b>PT9415-MPG KIT</b>
<b>Trans. Ele. (4 In. Kit)</b> (Allison 29548988)..... <b>PT9415-MPG KIT</b>	<b>Radial Seal Air</b> (Don. P534816).. <b>[2] RS3539</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>
<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>Radial Seal XP Air</b> (Don. P534816)..... <b>[2] RS3539XP</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b>
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b>	<b>Air Dryer</b> (Bendix 107796PG)..... <b>BA5377</b>	<b>Steering</b> (Nelson 84148A)..... <b>P528</b>
4900SA w/Cat C16 (15.8L) Eng. (1R0716)..... <b>B99+</b>	<b>Trans. Ele. (2 In. Kit)</b> (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (1335673)..... <b>BF1395-O</b>	<b>Trans. Ele. (4 In. Kit)</b> (Allison 29540494)..... <b>PT9415-MPG KIT</b>	4900SA w/Cummins X15 (14.9L) Eng. (2021)
<b>Fuel/Water Separator</b> (w/Drain) (1335673)..... <b>BF1265</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>Lube</b> (5575298)..... <b>B40145</b>
<b>Fuel/Water Separator</b> (w/Sensor Port) (1335673)..... <b>BF1395-SP</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b>	<b>Fuel</b> (5365988)..... <b>BF46129</b>
<b>Fuel/Water Separator</b> (2568753). <b>BF1259</b>	<b>Steering</b> (Nelson 84148A)..... <b>P528</b>	<b>Trans.</b> (Fuller 4304827)..... <b>BT223</b>
<b>Fuel/Water Separator</b> (Alliance ABPN122R50551)..... <b>BF46016-O</b>	4900SA w/Cummins X15 (14.9L) Eng. (2018)	<b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
<b>Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b>	<b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b>	4900SA w/Cummins X15 (14.9L) Eng. (2022)
<b>Fuel Spin-on</b> (Standard Vers.) (1R1712)..... <b>BF614+</b>	<b>Fuel/Water Separator</b> (Alliance ABPN122R50550)..... <b>BF9871-O</b>	<b>Lube</b> (5575298)..... <b>B40145</b>
<b>Fuel Spin-on</b> (High Efficiency Vers.) (1R0749)..... <b>BF7587+</b>	<b>Fuel</b> (Fleetguard FF5825NN)..... <b>BF46129+</b>	<b>Fuel</b> (5575143)..... <b>BF46248</b>
<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374+</b>	<b>Radial Seal Air</b> (Don. P534816).. <b>[2] RS3539</b>	4900SA w/Detroit Diesel DD13 (12.8L) Eng. (2010-14)
<b>Trans. Ele. (2 In. Kit)</b> (Allison 29548987)..... <b>PT9416-MPG KIT</b>	<b>Radial Seal XP Air</b> (Don. P534816)..... <b>[2] RS3539XP</b>	<b>Lube</b> (A4731800109)..... <b>P7505</b>
<b>Trans. Ele. (4 In. Kit)</b> (Allison 29548988)..... <b>PT9415-MPG KIT</b>	<b>Air Dryer</b> (Bendix 107796PG)..... <b>BA5377</b>	<b>Fuel Kit</b> (2 Filter Kit) (A4720900451)..... <b>PF9908 KIT</b>
<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>Trans. Ele. (2 In. Kit)</b> (Allison 29540493)..... <b>PT9416-MPG KIT</b>	<b>Fuel Kit</b> (3 Filter Kit) (A0000904251)..... <b>PF9924 KIT</b>
<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b>	<b>Trans. Ele. (4 In. Kit)</b> (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Radial Seal Air</b> (Fleetguard AF25247)..... <b>[2] RS3539+</b>
4900SA w/Cat 3126 (7.2L) Eng. Lube (Standard Vers.) (1R0739).. <b>B76+</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374+</b>
Lube (Severe Service) (1R0739).. <b>B76-SS+</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b>	<b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>
<b>Fuel/Water Separator</b> (1752949). <b>BF1268</b>	<b>Steering</b> (Nelson 84148A)..... <b>P528</b>	<b>Coolant</b> (A4722030255)..... <b>P5092</b>
<b>Fuel/Water Separator</b> (2568753). <b>BF1259</b>	4900SA w/Cummins X15 (14.9L) Eng. (2019)	<b>Trans. Ele. (2 In. Kit)</b> (Allison 29540493)..... <b>PT9416-MPG KIT</b>
<b>Fuel/Water Separator</b> (w/Sensor Port) (1986378)..... <b>BF7798-SP</b>	<b>Dual-Flow Lube</b> (4367100)..... <b>BD50000</b>	<b>Trans. Ele. (4 In. Kit)</b> (Allison 29540494)..... <b>PT9415-MPG KIT</b>
<b>Fuel/Water Separator</b> (Open End for Bowl) (1986378)..... <b>BF7798-O</b>	<b>Fuel/Water Separator</b> (Alliance ABPN122R50550)..... <b>BF9871-O</b>	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>
<b>Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b>	<b>Fuel</b> (5365988)..... <b>BF46129+</b>	<b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b>
<b>Fuel Spin-on</b> (1R0751)..... <b>BF7632</b>	<b>Radial Seal Air</b> (Don. P534816).. <b>[2] RS3539</b>	<b>Steering</b> (Nelson 84148A)..... <b>P528</b>
<b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374+</b>	<b>Radial Seal XP Air</b> (Don. P534816)..... <b>[2] RS3539XP</b>	<b>Some Rear Axle</b> (Meritor 3280-V-8394)..... <b>B233</b>
<b>Trans. Ele. (2 In. Kit)</b> (Allison 29548987)..... <b>PT9416-MPG KIT</b>	<b>Air Dryer</b> (AD-9Si System) (Bendix 5008414)..... <b>BA5374+</b>	<b>Diesel Exhaust Fluid</b> (2010 Emissions) (A0001420289)..... <b>PE5272</b>
<b>Trans. Ele. (4 In. Kit)</b> (Allison 29548988)..... <b>PT9415-MPG KIT</b>	<b>Trans. Ele. (2 In. Kit)</b> (Allison 29540493)..... <b>PT9416-MPG KIT</b>	4900SA w/Detroit DD13 (12.8L) Eng. (2015)
	<b>Trans. Ele. (4 In. Kit)</b> (Allison 29540494)..... <b>PT9415-MPG KIT</b>	<b>Lube</b> (A4731800109)..... <b>P7505</b>
	<b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	<b>Fuel/Water Separator</b> (A0000903651)..... <b>PF9804</b>
	<b>Steering</b> (1417927000)..... <b>PT23629</b>	<b>Fuel</b> (2 Filter Kit) (A4720900451). <b>PF9908 KIT</b>
		<b>Fuel</b> (3 Filter Kit) (A0000904251). <b>PF9924 KIT</b>
		<b>Radial Seal Air</b> (Don. P534816).. <b>RS3539</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>WESTERN STAR Trucks (cont'd)</b>	<b>WESTERN STAR Trucks (cont'd)</b>	<b>WESTERN STAR Trucks (cont'd)</b>
4900SA w/Detroit DD13 (12.8L) Eng. (2015) (Cont'd)	4900SA w/Detroit DD13 (12.8L) Eng. (2020) (Cont'd)	4900SA w/Detroit DD15 (14.8L) Eng. (2020)
Radial Seal XP Air (Don. P534816)..... <b>RS3539XP</b>	Radial Seal XP Air (Don. P534816)..... <b>RS3539XP</b>	Lube (To Eng. S/N A472910S0690710) (A4731800409)..... <b>P7505</b>
Air Dryer (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	Fuel/Water Separator (A0000905051)..... <b>PF46145</b>
Air Dryer (SS1200 System) (Wabco R950011)..... <b>BA5374 +</b>	Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	Fuel (A4700903151)..... <b>PF9908 KIT</b>
Coolant (A4722030255)..... <b>P5092</b>	Trans. Spin-on (Fuller 4304827).. <b>BT223</b>	Radial Seal Air (Don. P534816)..... <b>RS3539</b>
Trans. (2 In. Kit) (Allison 29548987)..... <b>PT9416-MPG KIT</b>	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	Radial Seal XP Air (Don. P534816)..... <b>RS3539XP</b>
Trans. (4 In. Kit) (Allison 29548988)..... <b>PT9415-MPG KIT</b>	Steering (Nelson 84148A)..... <b>P528</b>	Trans. (Fuller 4304827)..... <b>BT223</b>
Trans. Spin-on (Fuller 4304827).. <b>BT223</b>	Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	Steering (Nelson 84148A)..... <b>P528</b>
Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>		Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>
Steering (14-17927-000)..... <b>PT23629</b>	4900SA w/Detroit DD13 (12.8L) Eng. (2021)	4900SA w/Detroit DD15 (14.8L) Eng. (2021)
Diesel Exhaust Fluid (A0001420789)..... <b>PE17002 KIT</b>	Fuel (A4700903151)..... <b>PF9908 KIT</b>	Fuel/Water Separator (A0000905051)..... <b>PF46145</b>
4900SA w/Detroit DD13 (12.8L) Eng. (2018)	Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>	Fuel (A4700903151)..... <b>PF9908 KIT</b>
Lube (A4731800109)..... <b>P7505</b>	4900SA w/Detroit DD13 (12.8L) Eng. (2022)	Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>
Fuel/Water Separator (A0000905051)..... <b>PF46145</b>	Fuel (A4700903151)..... <b>PF9908 KIT</b>	Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>
Fuel (A4720900651)..... <b>PF9908 KIT</b>	4900SA w/Detroit DD15 (14.8L) Eng. (2018)	Trans. Spin-on (Fuller 4304827).. <b>BT223</b>
Radial Seal Air (Don. P534816)..... <b>[2] RS3539</b>	Lube (A4731800409)..... <b>P7505</b>	Opt. Rear Axle (Meritor 3280V8394)..... <b>B233</b>
Radial Seal XP Air (Don. P534816)..... <b>[2] RS3539XP</b>	Fuel/Water Separator (A0000905051)..... <b>PF46145</b>	4900SA w/Detroit DD16 (15.6L) Eng. (2018)
Air Dryer (Bendix 107796PG)..... <b>BA5377</b>	Fuel (A4720900651)..... <b>PF9908 KIT</b>	Lube (A4731800409)..... <b>P7505</b>
Coolant (A4722030355)..... <b>P5092</b>	Radial Seal Air (Don. P534816)..... <b>[2] RS3539</b>	Fuel/Water Separator (A0000905051)..... <b>PF46145</b>
Trans. (Fuller 4304827)..... <b>BT223</b>	Radial Seal XP Air (Don. P534816)..... <b>[2] RS3539XP</b>	Fuel (A4720900651)..... <b>PF9908 KIT</b>
Steering (Nelson 84148A)..... <b>P528</b>	Air Dryer (Bendix 107796PG)..... <b>BA5377</b>	Radial Seal Air (Don. P534816)..... <b>[2] RS3539</b>
Diesel Exhaust Fluid (A0001421089)..... <b>PE17002 KIT</b>	Trans. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	Radial Seal XP Air (Don. P534816)..... <b>[2] RS3539XP</b>
4900SA w/Detroit DD13 (12.8L) Eng. (2019)	Trans. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	Air Dryer (Bendix 107796PG)..... <b>BA5377</b>
Lube (A4731800409)..... <b>P7505</b>	Trans. Spin-on (Fuller 4304827).. <b>BT223</b>	Trans. Spin-on (Fuller 4304827).. <b>BT223</b>
Fuel/Water Separator (A0000905051)..... <b>PF46145</b>	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>
Fuel Kit (A4720900651)..... <b>PF9908 KIT</b>	Steering (Nelson 84148A)..... <b>P528</b>	Steering (Nelson 84148A)..... <b>P528</b>
Radial Seal Air (Don. P534816)..... <b>[2] RS3539</b>	Diesel Exhaust Fluid (A0001421089)..... <b>PE17002 KIT</b>	Diesel Exhaust Fluid (A0001421089)..... <b>PE17002 KIT</b>
Radial Seal XP Air (Don. P534816)..... <b>[2] RS3539XP</b>	4900SA w/Detroit DD15 (14.8L) Eng. (2019)	4900SA w/Detroit DD16 (15.6L) Eng. (2019)
Air Dryer (Bendix 107796)..... <b>BA5377</b>	Lube (A4731800109)..... <b>P7505</b>	Lube (A4731800109)..... <b>P7505</b>
Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	Fuel/Water Separator (A0000905051)..... <b>PF46145</b>	Fuel/Water Separator (A0000905051)..... <b>PF46145</b>
Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	Fuel Kit (A4720900651)..... <b>PF9908 KIT</b>	Fuel Kit (A4720900651)..... <b>PF9908 KIT</b>
Trans. Spin-on (Fuller 4304827).. <b>BT223</b>	Radial Seal Air (Don. P534816)..... <b>[2] RS3539</b>	Radial Seal Air (Don. P534816)..... <b>[2] RS3539</b>
Steering (1417927000)..... <b>PT23629</b>	Radial Seal XP Air (Don. P534816)..... <b>[2] RS3539XP</b>	Radial Seal XP Air (Don. P534816)..... <b>[2] RS3539XP</b>
Diesel Exhaust Fluid (A0001421089)..... <b>PE17002 KIT</b>	Air Dryer (AD-9Si System) (Bendix 5008414)..... <b>BA5374 +</b>	Air Dryer (AD-9Si System) (Bendix 5008414)..... <b>BA5374 +</b>
4900SA w/Detroit DD13 (12.8L) Eng. (2020)	Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>	Trans. Ele. (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b>
Lube (To Eng. S/N A472910S0690710) (A4731800409)..... <b>P7505</b>	Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>	Trans. Ele. (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b>
Fuel/Water Separator (A0000905051)..... <b>PF46145</b>	Trans. Spin-on (Fuller 4304827).. <b>BT223</b>	Trans. Spin-on (Fuller 4304827).. <b>BT223</b>
Fuel (A4700903151)..... <b>PF9908 KIT</b>	Steering (1417927000)..... <b>PT23629</b>	Steering (1417927000)..... <b>PT23629</b>
Radial Seal Air (Don. P534816)..... <b>RS3539</b>	Diesel Exhaust Fluid (A0001421089)..... <b>PE17002 KIT</b>	Diesel Exhaust Fluid (A0001421089)..... <b>PE17002 KIT</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

WESTERN STAR Trucks (cont'd)	WESTERN STAR Trucks (cont'd)	WESTERN STAR Trucks (cont'd)
4900SA w/Detroit DD16 (15.6L) Eng. (2020) Lube (To Eng. S/N A472910S0690710) (A4731800409)..... <b>P7505</b> <b>Fuel/Water Separator</b> (A0000905051)..... <b>PF46145</b> <b>Fuel</b> (A4700903151)..... <b>PF9908 KIT</b> <b>Radial Seal Air</b> (Don. P534816)... <b>[2] RS3539</b> <b>Radial Seal XP Air</b> (Don. P534816)..... <b>[2] RS3539XP</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Steering</b> (Nelson 84148A)..... <b>P528</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b>	4900SA w/Detroit Diesel Series 60 (12.7L), (14.0L) Eng. (To 1993) (Cont'd) <b>Coolant</b> (w/Chemical)..... <b>BW5137</b> <b>Coolant</b> (Controlled Release) (23516489)..... <b>BW5200</b> <b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 84148A)..... <b>P528</b> <b>Some Rear Axle</b> (Meritor 3280-V-8394)..... <b>B233</b>	5700XE w/Detroit DD13 (12.8L) Eng. (2018) (Cont'd) <b>EnduraCube Air</b> (336867010)..... <b>PA32002</b> <b>Air Dryer</b> (Wabco R950068)..... <b>BA5379 +</b> <b>Coolant</b> (A4722030355)..... <b>P5092</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b>
4900SA w/Detroit DD16 (15.6L) Eng. (2021) <b>Fuel/Water Separator</b> (A0000905051)..... <b>PF46145</b> <b>Fuel</b> (A4700903151)..... <b>PF9908 KIT</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	4900SA w/Detroit Diesel Series 60 (12.7L), (14.0L) Eng. (1993-on) <b>Lube</b> ..... <b>[2] B495</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19624)..... <b>PF7748</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (23512317)..... <b>BF5813 +</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (23512317).. <b>BF5813-O +</b> <b>P. Fuel</b> ..... <b>BF5800 +</b> <b>S. Fuel</b> (23533726)..... <b>BF5816</b> <b>S. Fuel</b> (23530645)..... <b>BF5815</b> <b>Radial Seal Air</b> (Don. P534925)... <b>[2] RS3534</b> <b>Radial Seal Air</b> (Don. P534816)... <b>[2] RS3539</b> <b>Radial Seal XP Air</b> (Don. P534816)..... <b>[2] RS3539XP</b> <b>Std. Air</b> (Nelson 70076N)..... <b>[2] PA2493</b> <b>Cab Air</b> (Alliance RD3-8416-0).... <b>PA5318</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b> <b>Coolant</b> (w/Chemical)..... <b>BW5137</b> <b>Coolant</b> (Controlled Release) (23516489)..... <b>BW5200</b> <b>Coolant</b> (w/o Chemical) (Fleetguard WF2077)..... <b>B5134 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b> <b>Steering</b> (Nelson 84148A)..... <b>P528</b> <b>Some Rear Axle</b> (Meritor 3280-V-8394)..... <b>B233</b>	5700XE w/Detroit DD13 (12.8L) Eng. (2019) <b>Lube</b> (A4731800409)..... <b>P7505</b> <b>Fuel/Water Separator</b> (A0000905051)..... <b>PF46145</b> <b>Fuel Kit</b> (A4720900651)..... <b>PF9908 KIT</b> <b>EnduraCube Air</b> (336867010).... <b>PA32002</b> <b>Air Dryer</b> (Wabco R950068A).... <b>BA5379</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b>
4900SA w/Detroit DD16 (15.6L) Eng. (2022) <b>Fuel/Water Separator</b> (A0000905051)..... <b>PF46145</b> <b>Fuel</b> (A4700903151)..... <b>PF9908 KIT</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29540493)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29540494)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	4900SA w/Detroit Diesel Series 60 (12.7L), (14.0L) Eng. (To 1993) <b>F-F Lube</b> ..... <b>B95 +</b> <b>B-P Lube</b> ..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS19624)..... <b>PF7748</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (23512317)..... <b>BF5813 +</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (23512317).. <b>BF5813-O +</b> <b>P. Fuel</b> ..... <b>BF5800 +</b> <b>S. Fuel</b> (23533726)..... <b>BF5816</b> <b>S. Fuel</b> (23530645)..... <b>BF5815</b> <b>Radial Seal Air</b> (Don. P534925)... <b>[2] RS3534</b> <b>Radial Seal Air</b> (Don. P534816)... <b>[2] RS3539</b> <b>Radial Seal XP Air</b> (Don. P534816)..... <b>[2] RS3539XP</b> <b>Std. Air</b> (Nelson 70076N)..... <b>[2] PA2493</b> <b>Cab Air</b> (Alliance RD3-8416-0).... <b>PA5318</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Air Dryer</b> (AD-9 System) (Bendix 107796)..... <b>BA5377</b>	5700XE w/Detroit DD13 (12.8L) Eng. (2020) <b>Lube</b> (To Eng. S/N A472910S0690710) (A4731800409)..... <b>P7505</b> <b>Fuel/Water Separator</b> (A0000905051)..... <b>PF46145</b> <b>Fuel</b> (A4700903151)..... <b>PF9908 KIT</b> <b>EnduraCube Air</b> (336867010).... <b>PA32002</b> <b>Air Dryer</b> (Wabco R950068A).... <b>BA5379</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
	5700XE w/Detroit DD13 (12.8L) Eng. (2021) <b>Fuel</b> (A4700903151)..... <b>PF9908 KIT</b>	5700XE w/Detroit DD13 (12.8L) Eng. (2022) <b>Fuel</b> (A4700903151)..... <b>PF9908 KIT</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>
	5700XE w/Detroit DD15 (14.8L) Eng. (2018) <b>Lube</b> (A4731800409)..... <b>P7505</b> <b>Fuel/Water Separator</b> (A0000905051)..... <b>PF46145</b> <b>Fuel</b> (A4720900651)..... <b>PF9908 KIT</b> <b>EnduraCube Air</b> (336867010).... <b>PA32002</b> <b>Air Dryer</b> (Wabco R950068).... <b>BA5379 +</b> <b>Trans. Ele.</b> (2 In. Kit) (Allison 29558117)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele.</b> (4 In. Kit) (Allison 29558118)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827).. <b>BT223</b>	
	5700XE w/Detroit DD13 (12.8L) Eng. (2018) <b>Lube</b> (A4731800109)..... <b>P7505</b> <b>Fuel/Water Separator</b> (A0000905051)..... <b>PF46145</b> <b>Fuel</b> (A4720900651)..... <b>PF9908 KIT</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

WESTERN STAR Trucks (cont'd)	WESTERN STAR Trucks (cont'd)	WESTERN STAR Trucks (cont'd)
5700XE w/Detroit DD15 (14.8L) Eng. (2018) (Cont'd) <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b>	5700XE w/Detroit DD16 (15.6L) Eng. (2019) (Cont'd) <b>Air Dryer</b> (Wabco R950068A)..... <b>BA5379</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b>	5800 w/Cat C10 (10.3L) Eng. (Cont'd) <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b>
5700XE w/Detroit DD15 (14.8L) Eng. (2019) <b>Lube</b> (A4731800109)..... <b>P7505</b> <b>Fuel/Water Separator</b> (A0000905051)..... <b>PF46145</b> <b>Fuel Kit</b> (A4720900651)..... <b>PF9908 KIT</b> <b>EnduraCube Air</b> (336867010)..... <b>PA32002</b> <b>Air Dryer</b> (Wabco R950068A)..... <b>BA5379</b> <b>Trans. Spin-on</b> (Fuller 4304827)..... <b>BT223</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b> <b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b>	5700XE w/Detroit DD16 (15.6L) Eng. (2020) <b>Lube</b> (To Eng. S/N A472910S0690710) (A4731800409)..... <b>P7505</b> <b>Fuel/Water Separator</b> (A0000905051)..... <b>PF46145</b> <b>Fuel</b> (A4700903151)..... <b>PF9908 KIT</b> <b>EnduraCube Air</b> (336867010)..... <b>PA32002</b> <b>Air Dryer</b> (Wabco R950068A)..... <b>BA5379</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	5800 w/Cat C12 (12.0L) Eng. <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99+</b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299+</b> <b>B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (1335673)..... <b>BF1395-O</b> <b>Fuel/Water Separator</b> (w/Drain) (1335673)..... <b>BF1265</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (1335673)..... <b>BF1395-SP</b> <b>Fuel/Water Separator Spin-on</b> (2568753)..... <b>BF1259</b> <b>Fuel/Water Separator Spin-on</b> (Alliance ABPN122R50551)..... <b>BF46016-O</b> <b>Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (Standard Vers.) (1R1712)..... <b>BF614+</b> <b>Fuel Spin-on</b> (High Efficiency Vers.) (1R0749)..... <b>BF7587+</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374+</b> <b>Trans. Ele. (2 In. Kit)</b> (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele. (4 In. Kit)</b> (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b>
5700XE w/Detroit DD15 (14.8L) Eng. (2020) <b>Lube</b> (To Eng. S/N A472910S0690710) (A4731800409)..... <b>P7505</b> <b>Fuel/Water Separator</b> (A0000905051)..... <b>PF46145</b> <b>Fuel</b> (A4700903151)..... <b>PF9908 KIT</b> <b>EnduraCube Air</b> (336867010)..... <b>PA32002</b> <b>Air Dryer</b> (Wabco R950068A)..... <b>BA5379</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	5700XE w/Detroit DD16 (15.6L) Eng. (2021) <b>Fuel</b> (A4700903151)..... <b>PF9908 KIT</b>	
5700XE w/Detroit DD15 (14.8L) Eng. (2021) <b>Fuel/Water Separator</b> (A0000905051)..... <b>PF46145</b> <b>Fuel</b> (A4700903151)..... <b>PF9908 KIT</b>	5700XE w/Detroit DD16 (15.6L) Eng. (2022) <b>Fuel</b> (A4700903151)..... <b>PF9908 KIT</b> <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	
5700XE w/Detroit DD15 (14.8L) Eng. (2022) <b>Opt. Rear Axle</b> (Meritor 3280V8394)..... <b>B233</b>	5800 w/Cat C10 (10.3L) Eng. <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99+</b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299+</b> <b>B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (1335673)..... <b>BF1395-O</b> <b>Fuel/Water Separator</b> (w/Drain) (1335673)..... <b>BF1265</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (1335673)..... <b>BF1395-SP</b> <b>Fuel/Water Separator Spin-on</b> (2568753)..... <b>BF1259</b> <b>Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (Standard Vers.) (1R1712)..... <b>BF614+</b> <b>Fuel Spin-on</b> (High Efficiency Vers.) (1R0749)..... <b>BF7587+</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374+</b> <b>Trans. Ele. (2 In. Kit)</b> (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele. (4 In. Kit)</b> (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827)..... <b>BT223</b>	5800 w/Cat C15 (14.6L) Eng. <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99+</b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299+</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (1335673)..... <b>BF1395-O</b> <b>Fuel/Water Separator</b> (2568753)..... <b>BF1259</b> <b>Fuel/Water Separator</b> (w/Drain) (1335673)..... <b>BF1265</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (1335673)..... <b>BF1395-SP</b> <b>Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (Standard Vers.) (1R1712)..... <b>BF614+</b> <b>Fuel Spin-on</b> (High Efficiency Vers.) (1R0749)..... <b>BF7587+</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374+</b> <b>Trans. Ele. (2 In. Kit)</b> (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele. (4 In. Kit)</b> (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827)..... <b>BT223</b>
5700XE w/Detroit DD16 (15.6L) Eng. (2018) <b>Lube</b> (A4731800409)..... <b>P7505</b> <b>Fuel/Water Separator</b> (A0000905051)..... <b>PF46145</b> <b>Fuel</b> (A4720900651)..... <b>PF9908 KIT</b> <b>EnduraCube Air</b> (336867010)..... <b>PA32002</b> <b>Air Dryer</b> (Wabco R950068)..... <b>BA5379+</b> <b>Trans. Spin-on</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b> <b>Steering</b> (1417927000)..... <b>PT23629</b> <b>Diesel Exhaust Fluid</b> (A0001421089)..... <b>PE17002 KIT</b>		
5700XE w/Detroit DD16 (15.6L) Eng. (2019) <b>Lube</b> (A4731800109)..... <b>P7505</b> <b>Fuel/Water Separator</b> (A0000905051)..... <b>PF46145</b> <b>Fuel Kit</b> (A4720900651)..... <b>PF9908 KIT</b> <b>EnduraCube Air</b> (336867010)..... <b>PA32002</b>		

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

WESTERN STAR Trucks (cont'd)	WESTERN STAR Trucks (cont'd)	WESTERN STAR Trucks (cont'd)
5800 w/Cat C15 (14.6L) Eng. (Cont'd) Opt. Trans. Spin-on (Fuller 17237)..... <b>B2 +</b>	5800 w/Cummins M11 (10.8L) Eng. (Cont'd) <b>Fuel/Water Separator Spin-on</b> (3329289)..... <b>BF1259</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	5900 w/Cat C10 (10.3L) Eng. (Cont'd) <b>Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (Standard Vers.) (1R1712)..... <b>BF614 +</b> <b>Fuel Spin-on</b> (High Efficiency Vers.) (1R0749)..... <b>BF7587 +</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Trans. Ele. (2 In. Kit)</b> (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele. (4 In. Kit)</b> (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
5800 w/Cat 3126 (7.2L) Eng. <b>Lube</b> (Standard Vers.) (1R0739)..... <b>B76 +</b> <b>Lube</b> (Severe Service) (1R0739)..... <b>B76-SS +</b> <b>Fuel/Water Separator</b> (1752949)..... <b>BF1268</b> <b>Fuel/Water Separator</b> (2568753)..... <b>BF1259</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (1986378)..... <b>BF7798-SP</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (1986378)..... <b>BF7798-O</b> <b>Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (1R0751)..... <b>BF7632</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Trans. Ele. (2 In. Kit)</b> (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele. (4 In. Kit)</b> (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>	5800 w/Cummins N14 (14.0L) Eng. (To 12/1995) <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>F-F Lube</b> (Fleetguard LF670SC)..... <b>B196 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Fuel/Water Separator Spin-on</b> (3308638)..... <b>BF1212 +</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>	5900 w/Cat C12 (12.0L) Eng. <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99 +</b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> <b>B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (1335673)..... <b>BF1395-O</b> <b>Fuel/Water Separator</b> (w/Drain) (1335673)..... <b>BF1265</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (1335673)..... <b>BF1395-SP</b> <b>Fuel/Water Separator Spin-on</b> (2568753)..... <b>BF1259</b> <b>Fuel/Water Separator Spin-on</b> (Alliance ABPN122R50551)..... <b>BF46016-O</b> <b>Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (Standard Vers.) (1R1712)..... <b>BF614 +</b> <b>Fuel Spin-on</b> (High Efficiency Vers.) (1R0749)..... <b>BF7587 +</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Trans. Ele. (2 In. Kit)</b> (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele. (4 In. Kit)</b> (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
5800 w/Cat 3176 (10.3L) Eng. <b>Lube</b> ..... <b>B99 +</b> <b>Opt. B-P Lube Spin-on</b> ..... <b>B7577</b> <b>Fuel Spin-on</b> ..... <b>BF614 +</b>	5800 w/Cummins N14 (14.0L) Eng. (12/1995-on) <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>F-F Lube</b> (Fleetguard LF670SC)..... <b>B196 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Fuel/Water Separator Spin-on</b> (3329289)..... <b>BF1259</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Coolant</b> (w/4 Units BTA+) (Fleetguard WF2071)..... <b>BW5071</b>	<b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (1335673)..... <b>BF1395-O</b> <b>Fuel/Water Separator</b> (w/Drain) (1335673)..... <b>BF1265</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (1335673)..... <b>BF1395-SP</b> <b>Fuel/Water Separator Spin-on</b> (2568753)..... <b>BF1259</b> <b>Fuel/Water Separator Spin-on</b> (Alliance ABPN122R50551)..... <b>BF46016-O</b> <b>Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (Standard Vers.) (1R1712)..... <b>BF614 +</b> <b>Fuel Spin-on</b> (High Efficiency Vers.) (1R0749)..... <b>BF7587 +</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Trans. Ele. (2 In. Kit)</b> (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele. (4 In. Kit)</b> (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
5800 w/Cat 3306 (10.5L) Eng. <b>Lube</b> (Standard Vers.)..... <b>B76 +</b> <b>Lube</b> (Severe Service)..... <b>B76-SS +</b> <b>Box-Style Fuel/Water Separator.</b> ..... <b>BF912</b> <b>Fuel Spin-on</b> ..... <b>BF970 +</b>	5800 w/Detroit Diesel Series 60 (11.1L) or (12.7L) Eng. <b>F-F Lube</b> (23518480)..... <b>[2] B495</b> <b>Fuel/Water Separator</b> (w/Drain) (23512317)..... <b>BF5813 +</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (23512317)..... <b>BF5813-O +</b> <b>Opt. Fuel/Water Separator</b> (23516189)..... <b>BF5812</b> <b>Opt. Fuel/Water Separator</b> (Alliance ABPN122R50407)..... <b>BF1283-SP +</b> <b>P. Fuel</b> (25014274)..... <b>BF5800 +</b> <b>S. Fuel</b> (23518482)..... <b>BF5810</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b>	<b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99 +</b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> <b>B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (1335673)..... <b>BF1395-O</b> <b>Fuel/Water Separator</b> (w/Drain) (1335673)..... <b>BF1265</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (1335673)..... <b>BF1395-SP</b> <b>Fuel/Water Separator Spin-on</b> (2568753)..... <b>BF1259</b>
5800 w/Cat 3406 (14.6L) Eng. <b>Lube</b> ..... <b>B99 +</b> <b>Fuel/Water Separator</b> ..... <b>BF1218 +</b> <b>Fuel Spin-on</b> ..... <b>BF7587 +</b>	5800 w/Cummins 6CT8.3 (8.3L) Eng. <b>Lube</b> ..... <b>B205 +</b> <b>P. Fuel/Water Separator</b> ..... <b>BF1280 +</b> <b>S. Fuel</b> ..... <b>BF788</b> <b>Coolant</b> ..... <b>BW5070</b>	<b>Trans. Ele. (2 In. Kit)</b> (Allison 29548987)..... <b>PT9416-MPG KIT</b> <b>Trans. Ele. (4 In. Kit)</b> (Allison 29548988)..... <b>PT9415-MPG KIT</b> <b>Trans. Spin-on</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2 +</b>
5800 w/Cummins L10 (10.0L) Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>F-F Lube</b> (Fleetguard LF670SC)..... <b>B196 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Fuel/Water Separator</b> (3308638)..... <b>BF1212 +</b> <b>Fuel</b> (154789)..... <b>BF957-D +</b> <b>Air Dryer</b> (AD-IS System) (Bendix 5008414)..... <b>BA5374 +</b> <b>Coolant</b> (w/4 Units BTA+) (3315116)..... <b>BW5071</b> <b>Coolant</b> (w/15 Units BTA+) (3318318)..... <b>BW5075</b>	5900 w/Cat C10 (10.3L) Eng. <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99 +</b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> <b>B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (1335673)..... <b>BF1395-O</b> <b>Fuel/Water Separator</b> (w/Drain) (1335673)..... <b>BF1265</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (1335673)..... <b>BF1395-SP</b> <b>Fuel/Water Separator Spin-on</b> (2568753)..... <b>BF1259</b>	<b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99 +</b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> <b>Fuel/Water Separator</b> (Open End for Bowl) (1335673)..... <b>BF1395-O</b> <b>Fuel/Water Separator</b> (2568753)..... <b>BF1259</b> <b>Fuel/Water Separator</b> (w/Drain) (1335673)..... <b>BF1265</b> <b>Fuel/Water Separator</b> (w/Sensor Port) (1335673)..... <b>BF1395-SP</b>
5800 w/Cummins M11 (10.8L) Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Fuel/Water Separator Ele.</b> (Davco 380087)..... <b>PF7680</b>		

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>WESTERN STAR Trucks (cont'd)</b>	<b>WESTERN STAR Trucks (cont'd)</b>	<b>WESTERN STAR Trucks (cont'd)</b>
5900 w/Cat C15 (14.6L) Eng. (Cont'd)	5900 w/Detroit Diesel Series 60 (11.1L) or (12.7L) Eng. (Cont'd)	6900 w/Cummins N14 (14.0L) Eng. (To 12/1995) (Cont'd)
Fuel Ele. (9M2342)..... [2] PF935	Air Dryer (Wabco R950011)..... BA5374 +	Air Dryer (AD-IS System) (Bendix 5008414)..... BA5374 +
Fuel Spin-on (Standard Vers.) (1R1712)..... BF614 +	Trans. (Fuller 4304827)..... BT223	Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071
Fuel Spin-on (High Efficiency Vers.) (1R0749)..... BF7587 +	Opt. Trans. (Fuller 17237)..... B2 +	
Air Dryer (AD-IS System) (Bendix 5008414)..... BA5374 +	Steering (Nelson 84148A)..... P528	
Trans. Ele. (2 In. Kit) (Allison 29548987)..... PT9416-MPG KIT	6900 w/Cat 3208 (10.4L) Eng.	6900 w/Cummins N14 (14.0L) Eng. (12/1995-on)
Trans. Ele. (4 In. Kit) (Allison 29548988)..... PT9415-MPG KIT	Lube (9L9200)..... [2] BT364	Dual-Flow Lube (3318853)..... BD103 +
Trans. Spin-on (Fuller 4304827)..... BT223	Lube (9N5570)..... [2] BT230 +	F-F Lube (Fleetguard LF670SC).. B196 +
Opt. Trans. Spin-on (Fuller 17237)..... B2 +	Box-Style Fuel/Water Separator. BF912	B-P Lube (3304232)..... B7577
5900 w/Cat 3176 (10.3L) Eng.	Fuel Spin-on..... BF970 +	Fuel/Water Separator Spin-on (3329289)..... BF1259
Lube..... B99 +	6900 w/Cat 3406 (14.6L) Eng.	Air Dryer (AD-IS System) (Bendix 5008414)..... BA5374 +
Opt. B-P Lube Spin-on..... B7577	F-F Lube (Std. Version) (1R0716)..... B99 +	Coolant (w/4 Units BTA+) (Fleetguard WF2071)..... BW5071
Fuel Spin-on..... BF614 +	F-F Lube (High Efficiency Vers.) (1R1808)..... B7299 +	6900 w/Cummins Signature 600 (15.0L) Eng.
5900 w/Cat 3406 (14.6L) Eng.	Fuel/Water Separator Spin-on (2568753)..... BF1259	14 7/32 In. Dual-Flow Lube..... BD7153 +
Lube..... B99 +	P. Fuel Ele. (9M2341)..... [2] PF935	Opt. 11 13/16 In. Dual-Flow Lube BD7154 +
Fuel/Water Separator..... BF1218 +	Fuel Spin-on (1R0749)..... BF7587 +	Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... BD50000
Fuel Spin-on..... BF7587 +	Fuel Spin-on (1R0712)..... BF614 +	Fuel/Water Separator..... BF1274-SP
Air (Don. P153551)..... PA2705	Air Dryer (AD-IS System) (Bendix 5008414)..... BA5374 +	6900, 6900XD w/Cat C15 (14.6L), or C16 (15.8L) Eng. (To 1/2004)
5900 w/Cummins M11 (10.8L) Eng. (To 12/1995)	6900 w/Cummins ISX 15.0 (14.9L) Eng.	Lube (1R0716)..... B99 +
Dual-Flow Lube (3318853)..... BD103 +	Dual-Flow Lube (Fleetguard LF9070)..... BD7153 +	Fuel/Water Separator Spin-on (w/Drain) (170014406)..... BF1259
Fuel/Water Separator Ele. (Davco 380087)..... PF7680	Dual-Flow Lube (Fleetguard LF9080)..... BD7154 +	Fuel/Water Separator Spin-on (w/Drain) (Racor S3226P)..... BF1346
Fuel/Water Separator Spin-on (3308638)..... BF1212 +	Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... BD50000	Fuel/Water Separator Spin-on (Open End for Bowl) (Racor S3226P)..... BF1346-O
Air Dryer (AD-IS System) (Bendix 5008414)..... BA5374 +	Fuel/Water Separator Ele. (Fleetguard FF5369W)..... PF7744	Fuel/Water Separator Spin-on (w/Sensor Port) (Racor S3226P).. BF1346-SP
5900 w/Cummins M11 (10.8L) Eng. (12/1995-on)	Fuel/Water Separator Ele. (Fleetguard FS19727)..... PF7895	Fuel (1R0749)..... BF7587 +
Dual-Flow Lube (3318853)..... BD103 +	Fuel/Water Separator Ele. (Davco 382116)..... PF7755	Air (Fleetguard AF1616)..... [2] PA2493
Fuel/Water Separator Ele. (Davco 380087)..... PF7680	Fuel/Water Separator Ele. (Davco 102527)..... PF9814	Air Dryer (AD-IS System) (Bendix 5008414)..... BA5374 +
Fuel/Water Separator Spin-on (3329289)..... BF1259	Fuel Spin-on (Fleetguard FF2200)..... BF7766	Air Dryer (AD-9 System) (Bendix 107796)..... BA5377
Air Dryer (AD-IS System) (Bendix 5008414)..... BA5374 +	Fuel Spin-on (Fleetguard FF2203)..... BF7760	Trans. Spin-on (Fuller 4304827)..... BT223
5900 w/Cummins N14 (14.0L) Eng.	Air Dryer (AD-IS System) (Bendix 5008414)..... BA5374 +	Opt. Trans. Spin-on (Fuller 17237)..... B2 +
Dual-Flow Lube..... BD103 +	Coolant (w/o Chemical) (Fleetguard WF2127)..... B5087	Steering (Nelson 84148A)..... P528
Fuel/Water Separator..... BF1212 +	Coolant (w/11 1/2 Units BTA+) (Fleetguard WF2126)..... BW5086	6900, 6900XD w/Cat C15 (14.6L), or C16 (15.8L) Eng. (1/2004-on)
Fuel Spin-on..... BF957-D +	Coolant (Controlled Release BTA+) (Fleetguard WF2121)..... BW5250	Lube (1R1808)..... B7299 +
Air (Don. P153551)..... PA2705	6900 w/Cummins N14 (14.0L) Eng. (To 12/1995)	Fuel/Water Separator Spin-on (w/Drain) (170014406)..... BF1259
Air Dryer (AD-9 System) (Bendix 107796)..... BA5377	Dual-Flow Lube (3318853)..... BD103 +	Fuel/Water Separator Spin-on (w/Drain) (Racor S3226P)..... BF1346
Steering (Nelson 87972A)..... PT9386-MPG	F-F Lube (Fleetguard LF670SC).. B196 +	Fuel/Water Separator Spin-on (Open End for Bowl) (Racor S3226P)..... BF1346-O
5900 w/Detroit Diesel Series 60 (11.1L) or (12.7L) Eng.	B-P Lube (3304232)..... B7577	Fuel/Water Separator Spin-on (w/Sensor Port) (Racor S3226P).. BF1346-SP
F-F Lube (23530573)..... [2] B495	Fuel/Water Separator Spin-on (3308638)..... BF1212 +	Fuel (1R0749)..... BF7587 +
Fuel/Water Separator (Racor R90T)..... BF1390-O		
P. Fuel (23530706)..... BF5800 +		
S. Fuel (23530645)..... BF5815		
Air (Don. P153551)..... PA2705		

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



WESTERN STAR Trucks (cont'd)	WESTERN STAR Trucks (cont'd)	WESTERN STAR Trucks (cont'd)
6900, 6900XD w/Cat C15 (14.6L), or C16 (15.8L) Eng. (1/2004-on) (Cont'd)	6900XD w/Cummins ISX 15.0 (14.9L) Eng. (Cont'd)	WSH w/Cummins N14 (14.0L) Eng. (Cont'd)
Air (Fleetguard AF1616)..... [2] PA2493	Trans. Spin-on (Fuller 4304827).. BT223	Coolant (w/4 Units BTA+ (Fleetguard WF2071)..... BW5071
Air Dryer (AD-IS System) (Bendix 5008414)..... BA5374 +	Opt. Trans. Spin-on (Fuller 17237)..... B2 +	WSH w/Detroit Diesel 8V-92 (12.1L) Eng.
Air Dryer (AD-9 System) (Bendix 107796)..... BA5377	6900XD w/Detroit Diesel DD15 (14.8L) Eng.	Lube Ele..... P20-HD +
Trans. Spin-on (Fuller 4304827).. BT223	Lube (A4731800109)..... P7505	F-F Lube Spin-on..... B95 +
Opt. Trans. Spin-on (Fuller 17237)..... B2 +	Fuel Kit (A0000904251)..... PF9924 KIT	P. Fuel Spin-on..... BF5800 +
Steering (Nelson 84148A)..... P528	Air Dryer (AD-IS System) (Bendix 5008414)..... BA5374 +	S. Fuel Spin-on..... BF5810
6900, 6900XD w/Detroit Diesel Series 60 (11.1L), (12.7L), & (14.0L) Eng.	Coolant (A4722030255)..... P5092	Air (22005-4401)..... PA2493
Lube (23530573)..... [2] B495	Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	Western Star w/Cat 1160 Eng.
Fuel/Water Separator Spin-on (w/Drain) (170014406)..... BF1259	Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Lube..... [2] BT364
Fuel/Water Separator (Fleetguard LFF9013)..... BF7798-SP	Opt. Trans. Spin-on (Fuller 17237)..... B2 +	Fuel..... BF583
S. Fuel (23530645)..... BF5815	Differential (Meritor 3280V8394).. B233	Western Star w/Cat 1674 Eng.
Air (Fleetguard AF1616)..... [2] PA2493	6900XD w/Detroit Diesel DD16 (15.6L) Eng. (2019)	Lube Ele..... PT670
Air Dryer (AD-IS System) (Bendix 5008414)..... BA5374 +	Lube (A4731800109)..... P7505	Fuel Spin-on..... BF970 +
Air Dryer (AD-9 System) (Bendix 107796)..... BA5377	Fuel/Water Separator (A0000905051)..... PF46145	Opt. Air Comp. Breather..... PA1704
Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	Fuel Kit (A4720900651)..... PF9908 KIT	Western Star w/Cat 1693 Series Eng.
Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	EnduraCube Air (336867010)..... PA32002	Lube Ele..... [2] PT88-HD
Trans. Spin-on (Fuller 4304827).. BT223	Trans. Ele. (4 In. Kit) (Allison 29558118)..... PT9415-MPG KIT	Lube Spin-on..... B99 +
Opt. Trans. Spin-on (Fuller 17237)..... B2 +	Trans. Ele. (2 In. Kit) (Allison 29558117)..... PT9416-MPG KIT	Fuel Ele..... [2] PF823 +
Steering (Nelson 84148A)..... P528	Trans. Spin-on (Fuller 4304827).. BT223	Fuel Spin-on..... [2] BF970 +
Some Rear Axle (Meritor 3280-V-8394)..... B233	Steering (1417927000)..... PT23629	Opt. Air Comp. Breather..... PA1704
6900XD w/Cummins ISX 15.0 (14.9L) Eng.	Opt. Rear Axle (Meritor 3280V8394)..... B233	Western Star w/Cummins N10 Eng.
Dual-Flow Lube (Fleetguard LF9070)..... BD7153 +	Diesel Exhaust Fluid (A0001421089)..... PE17002 KIT	F-F Lube..... B196 +
Dual-Flow Lube (Fleetguard LF9080)..... BD7154 +	6900XD w/Detroit Diesel DD16 (15.6L) Eng. (2021)	B-P Lube..... B7577
Dual-Flow Lube (Upgrade) (Fleetguard LF14000NN)..... BD50000	Fuel (A4700903151)..... PF9908 KIT	Dual-Flow Lube..... BD103 +
Fuel/Water Separator Ele. (Fleetguard FF5369W)..... PF7744	6900XD w/Detroit Diesel DD16 (15.6L) Eng. (2022)	Opt. Fuel/Water Separator..... BF1212 +
Fuel/Water Separator Ele. (Fleetguard FS19727)..... PF7895	Fuel (A4700903151)..... PF9908 KIT	Fuel Spin-on..... BF957 +
Fuel/Water Separator Ele. (Davco 382116)..... PF7755	WSH w/Cat 3406 (14.6L) Eng.	Western Star w/GMC 6V-53N Eng.
Fuel/Water Separator Ele. (Davco 102527)..... PF9814	F-F Lube (Std. Version) (1R0716)..... B99 +	F-F Lube Ele..... P20-HD +
Fuel Spin-on (Fleetguard FF2200)..... BF7766	F-F Lube (High Efficiency Vers.) (1R1808)..... B7299 +	B-P Lube Ele..... P52
Fuel Spin-on (Fleetguard FF2203)..... BF7760	Fuel/Water Separator Spin-on (2568753)..... BF1259	P. Fuel Sock..... F916-C
Air Dryer (AD-IS System) (Bendix 5008414)..... BA5374 +	P. Fuel Ele. (9M2341)..... [2] PF935	S. Fuel Ele..... PF906
Trans. Ele. (2 In. Kit) (Allison 29540493)..... PT9416-MPG KIT	Fuel Spin-on (1R0749)..... BF7587 +	Western Star w/GMC 12V-71 Eng.
Trans. Ele. (4 In. Kit) (Allison 29540494)..... PT9415-MPG KIT	Fuel Spin-on (1R0712)..... BF614 +	F-F Lube Ele..... [2] P20-HD +
	WSH w/Cummins N14 (14.0L) Eng.	B-P Lube Ele..... [2] P52
	Dual-Flow Lube (3318853)..... BD103 +	P. Fuel Sock (5574980)..... F844-A
	F-F Lube (Fleetguard LF670SC).. B196 +	P. Fuel Ele. (5575032)..... PF845
	B-P Lube (3304232)..... B7577	S. Fuel Ele. (6436719)..... PF846
	Opt. Fuel/Water Separator Spin-on (3308638)..... BF1212 +	


+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

WHITE/GMC Trucks	WHITE/GMC Trucks (cont'd)	WHITE/GMC Trucks (cont'd)
1500, 2000 Series w/Perkins 6-354 Diesel Eng. Lube Ele. (26540153)..... PT12 P. Fuel Sock..... F916-C Can-Type S. Fuel..... BF825 +	ACL w/Cummins L10 (10.0L) Eng. Dual-Flow Lube (3318853)..... BD103 + F-F Lube (Fleetguard LF670SC).. B196 + B-P Lube (3304232)..... B7577 Fuel/Water Separator (3308638). BF1212 + Fuel (154789)..... BF957-D + Coolant (w/4 Units BTA+) (3315116)..... BW5071 Coolant (w/12 Units BTA+) (3315114)..... BW5074 Coolant (w/15 Units BTA+) (3318318)..... BW5075 Trans. (Auxiliary) (Allison 29510918)..... PT8330-MPG	ACL w/Detroit Diesel Series 60 (11.1L) or (12.7L) Eng. (To 1993) F-F Lube (25010495)..... [2] B95 + B-P Lube (23530413)..... B7577 Fuel/Water Separator Ele. (Davco 301SD19B)..... PF7680 Fuel/Water Separator Ele. (Davco 382114)..... PF7748 Fuel/Water Separator Spin-on (w/Drain) (23512317)..... BF5813 + Fuel/Water Separator Spin-on (Open End for Bowl) (23512317).. BF5813-O + Opt. Fuel/Water Separator Spin-on (23516189)..... BF5812 Opt. Fuel/Water Separator Spin-on (Alliance ABPN122R50407)..... BF1283-SP + P. Fuel (25014274)..... BF5800 + S. Fuel (23518482)..... BF5810 Air Dryer (Coalescer Vers.) (Wabco R950068)..... BA5379 + Air Dryer (Desiccant Vers.) (Bendix 109994)..... BA5374 + Coolant (Nalcool NF2088)..... BW5200 Trans. (Fuller 4304827)..... BT223 Opt. Trans. (Fuller 17237)..... B2 + Trans. (Auxiliary) (Allison 29510918)..... PT8330-MPG
1500, 2000, 3000 Series w/White 6 Cyl. Gas Eng. F-F Lube Ele. (216775)..... P82 B-P Lube Sock (442899)..... CU406 <sup>90</sup> B-P Lube Ele. (216762)..... P53	ACL w/Cummins M11 (10.8L) Eng. (To 12/1995) Dual-Flow Lube (3318853)..... BD103 + Fuel/Water Separator Ele. (Fleetguard FS1029W)..... PF7680 Fuel/Water Separator Spin-on (3308638)..... BF1212 + Trans. (Auxiliary) (Allison 29510918)..... PT8330-MPG	ACL w/Detroit Diesel Series 60 (11.1L) or (12.7L) Eng. (1993-on) F-F Lube (23518480)..... [2] B495 Fuel/Water Separator Ele. (Davco 301SD19B)..... PF7680 Fuel/Water Separator Ele. (Davco 382114)..... PF7748 Fuel/Water Separator Spin-on (w/Drain) (23512317)..... BF5813 + Fuel/Water Separator Spin-on (Open End for Bowl) (23512317).. BF5813-O + Opt. Fuel/Water Separator Spin-on (23516189)..... BF5812 Opt. Fuel/Water Separator Spin-on (Alliance ABPN122R50407)..... BF1283-SP + P. Fuel (25014274)..... BF5800 + S. Fuel (23518482)..... BF5810 Air Dryer (Coalescer Vers.) (Wabco R950068)..... BA5379 + Air Dryer (Desiccant Vers.) (Bendix 109994)..... BA5374 + Coolant (Nalcool NF2088)..... BW5200 Trans. (Fuller 4304827)..... BT223 Opt. Trans. (Fuller 17237)..... B2 + Trans. (Auxiliary) (Allison 29510918)..... PT8330-MPG
9000 Series w/White 6 Cyl. Gas Eng. Lube Sock (872946A)..... VT842-O	ACL w/Cummins M11 (10.8L) Eng. (12/1995-on) Dual-Flow Lube (3318853)..... BD103 + Fuel/Water Separator Ele. (Fleetguard FS1029W)..... PF7680 Fuel/Water Separator Spin-on (3329289)..... BF1259 Trans. (Auxiliary) (Allison 29510918)..... PT8330-MPG	ACL w/Detroit Diesel Series 60 (11.1L) or (12.7L) Eng. (1993-on) F-F Lube (23518480)..... [2] B495 Fuel/Water Separator Ele. (Davco 301SD19B)..... PF7680 Fuel/Water Separator Ele. (Davco 382114)..... PF7748 Fuel/Water Separator Spin-on (w/Drain) (23512317)..... BF5813 + Fuel/Water Separator Spin-on (Open End for Bowl) (23512317).. BF5813-O + Opt. Fuel/Water Separator Spin-on (23516189)..... BF5812 Opt. Fuel/Water Separator Spin-on (Alliance ABPN122R50407)..... BF1283-SP + P. Fuel (25014274)..... BF5800 + S. Fuel (23518482)..... BF5810 Air Dryer (Coalescer Vers.) (Wabco R950068)..... BA5379 + Air Dryer (Desiccant Vers.) (Bendix 109994)..... BA5374 + Coolant (Nalcool NF2088)..... BW5200 Trans. (Fuller 4304827)..... BT223 Opt. Trans. (Fuller 17237)..... B2 + Trans. (Auxiliary) (Allison 29510918)..... PT8330-MPG
9000 Series w/White V8 Eng. Lube Sock (883451)..... V1044-O	ACL w/Cummins N14 (14.0L) Eng. Dual-Flow Lube (3318853)..... BD103 + F-F Lube (Fleetguard LF670SC).. B196 + B-P Lube (3304232)..... B7577 Fuel/Water Separator (3308638). BF1212 + Fuel (154789)..... BF957-D + Air Dryer (Coalescer Vers.) (Wabco R950068)..... BA5379 + Air Dryer (Desiccant Vers.) (Bendix 109994)..... BA5374 + Coolant (w/4 Units BTA+) (3315116)..... BW5071 Coolant (w/23 Units BTA+) (4058965)..... BW5076 Trans. (Fuller 4304827)..... BT223 Opt. Trans. (Fuller 17237)..... B2 + Trans. (Auxiliary) (Allison 29510918)..... PT8330-MPG	ACL w/Detroit Diesel Series 60 (11.1L) or (12.7L) Eng. (1993-on) F-F Lube (23530407)..... B95 + F-F Lube (23530408)..... B95-MPG + P. Fuel (23530706)..... BF5800 + S. Fuel (23530707)..... BF5810 S. Fuel (23530645)..... BF5815
ACL w/Cat 3176 (10.3L) Eng. F-F Lube (Std. Version) (1R0716)..... B99 + F-F Lube (High Efficiency Vers.) (1R1808)..... B7299 + F-F Lube (8N9586)..... BT230 + F-F Lube (9N6007)..... B75 Opt. B-P Lube (1W8845)..... B7577 Fuel/Water Separator Ele. (8N0205)..... PF316 Fuel/Water Separator Spin-on (2568753)..... BF1259 P. Fuel Ele. (9M2342)..... [2] PF935 P. Fuel Spin-on (1R1740)..... BF970 + Fuel Spin-on (1R0712)..... BF614 + S. Fuel Spin-on (1R0750)..... BF7633 + Trans. (Fuller 4304827)..... BT223 Opt. Trans. (Fuller 17237)..... B2 +	ACL w/Cat 3306 (10.5L) Eng. Lube Ele. (5S0484)..... PT670 Lube Spin-on (1R0716)..... B99 + Lube Spin-on (Standard Vers.) (1R0739)..... B76 + Lube Spin-on (Severe Service) (1R0739)..... B76-SS + Box-Style Glass Fuel/Water Separator (6N7617)..... BF912 Fuel/Water Separator Ele. (8N0205)..... PF316 Fuel/Water Separator Spin-on (2568753)..... BF1259 P. Fuel Ele. (9M2342)..... PF935 P. Fuel Spin-on (1R1740)..... BF970 + S. Fuel Spin-on (1R0750)..... BF7633 + Trans. (Auxiliary) (Allison 29510918)..... PT8330-MPG	ACL w/Detroit Diesel 6V-92N (9.0L) Eng. F-F Lube (23530407)..... B95 + F-F Lube (23530408)..... B95-MPG + P. Fuel (23530706)..... BF5800 + S. Fuel (23530707)..... BF5810 S. Fuel (23530645)..... BF5815
ACL w/Cat 3406 (14.6L) Eng. Lube..... B99 + Fuel/Water Separator..... BF1218 + Fuel Spin-on..... BF7587 + Coolant..... BW5140		

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

WHITE/GMC Trucks (cont'd)	WHITE/GMC Trucks (cont'd)	WHITE/GMC Trucks (cont'd)
ACL w/Volvo D12 (12.1L) Eng. <b>Fuel/Water Separator</b> (Alliance ABPN122R50551)..... <b>BF46016-O</b>	ACM w/Cat 3406 (14.6L) Eng. (Cont'd) <b>Fuel Spin-on</b> (1R0749)..... <b>BF7587 +</b> <b>Air Dryer</b> (Coalescer Vers.) (Wabco R950068)..... <b>BA5379 +</b> <b>Air Dryer</b> (Desiccant Vers.) (Bendix 109994)..... <b>BA5374 +</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Trans.</b> (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b>	Conventional, High Cabover, Integral, Integral Tall Sleeper w/Cummins Eng. <b>F-F Lube Spin-on</b> ..... <b>B196 +</b> <b>B-P Lube Ele.</b> ..... <b>C750-E +</b> <b>B-P Lube Spin-on</b> ..... <b>B7577</b> <b>Fuel Spin-on</b> ..... <b>BF957 +</b> <b>Coolant</b> ..... <b>BW5071</b>
ACL w/Volvo TD122 (12.0L) Eng. <b>F-F Lube</b> (21707134)..... <b>B76 +</b> <b>Severe Service F-F Lube</b> (21707134)..... <b>B76-SS +</b> <b>P. Fuel</b> (4669875)..... <b>BF988 +</b> <b>S. Fuel</b> (991203640)..... <b>BF788</b>	ACM w/Cummins L10 (10.0L) Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Fuel/Water Separator</b> (3308638). <b>BF1212 +</b> <b>Fuel</b> (154789)..... <b>BF957-D +</b> <b>Coolant</b> (w/4 Units BTA+) (3315116)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (3315114)..... <b>BW5074</b> <b>Coolant</b> (w/15 Units BTA+) (3318318)..... <b>BW5075</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Trans.</b> (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b>	FE64, WG64 w/Volvo VED7 Eng. <b>F-F Lube</b> (466634-3)..... <b>B76 +</b> <b>B-P Lube</b> (477556)..... <b>B7685</b> <b>Opt. Fuel/Water Separator</b> ..... <b>BF1212 +</b> <b>Fuel</b> ..... <b>[2] BF988 +</b> <b>Radial Seal O. Air</b> (Standard) (V1117576)..... <b>RS3518</b> <b>Radial Seal XP O. Air</b> (Upgrade) (V1117576)..... <b>RS3518XP</b> <b>Radial Seal I. Air</b> ..... <b>RS3519</b>
ACM w/Cat 3176 (10.3L) Eng. <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99 +</b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> <b>F-F Lube</b> (8N9586)..... <b>BT230 +</b> <b>F-F Lube</b> (9N6007)..... <b>B75</b> <b>Opt. B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Fuel/Water Separator Spin-on</b> (2568753)..... <b>BF1259</b> <b>P. Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>P. Fuel Spin-on</b> (1R1740)..... <b>BF970 +</b> <b>Fuel Spin-on</b> (1R0712)..... <b>BF614 +</b> <b>S. Fuel Spin-on</b> (1R0750)..... <b>BF7633 +</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Trans.</b> (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b>	ACM w/Cummins N14 (14.0L) Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Fuel/Water Separator</b> (3308638). <b>BF1212 +</b> <b>Fuel</b> (154789)..... <b>BF957-D +</b> <b>Air Dryer</b> (Coalescer Vers.) (Wabco R950068)..... <b>BA5379 +</b> <b>Air Dryer</b> (Desiccant Vers.) (Bendix 109994)..... <b>BA5374 +</b> <b>Coolant</b> (w/4 Units BTA+) (3315116)..... <b>BW5071</b> <b>Coolant</b> (w/23 Units BTA+) (4058965)..... <b>BW5076</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Trans.</b> (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b>	J8C0 w/Cat 3208 (10.4L) Eng. <b>F-F Lube</b> (9L9200)..... <b>[2] BT364</b> <b>F-F Lube</b> (9N5570)..... <b>[2] BT230</b> <b>F-F Lube</b> (9N6007)..... <b>[2] B75</b> <b>B-P Lube Ele.</b> ..... <b>C750-E +</b> <b>Box-Style Fuel/Water Separator.</b> <b>BF912</b> <b>Fuel Ele.</b> (9M2341)..... <b>PF935</b> <b>Fuel Spin-on</b> ..... <b>BF970 +</b> <b>Fuel Spin-on</b> (1R0750)..... <b>BF7633 +</b> <b>Air</b> (15506047)..... <b>PA2656</b> <b>Air</b> (2009007)..... <b>PA2465</b> <b>Comp. Air</b> ..... <b>PA1909</b>
ACM w/Cat 3306 (10.5L) Eng. <b>Lube Ele.</b> (5S0484)..... <b>PT670</b> <b>Lube Spin-on</b> (1R0716)..... <b>B99 +</b> <b>Lube Spin-on</b> (Standard Vers.) (1R0739)..... <b>B76 +</b> <b>Lube Spin-on</b> (Severe Service) (1R0739)..... <b>B76-SS +</b> <b>Box-Style Glass Fuel/Water Separator</b> (6N7617)..... <b>BF912</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Fuel/Water Separator Spin-on</b> (2568753)..... <b>BF1259</b> <b>P. Fuel Ele.</b> (9M2342)..... <b>PF935</b> <b>P. Fuel Spin-on</b> (1R1740)..... <b>BF970 +</b> <b>S. Fuel Spin-on</b> (1R0750)..... <b>BF7633 +</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Trans.</b> (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b>	ACM w/Detroit Diesel 6-71 (7.0L) Eng. <b>F-F Lube</b> (23530407)..... <b>B95 +</b> <b>F-F Lube</b> (23530408)..... <b>B95-MPG +</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b> <b>S. Fuel</b> (23530645)..... <b>BF5815</b>	J9C0 w/Cummins L10 (10.0L) Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Fuel/Water Separator</b> (3308638). <b>BF1212 +</b> <b>Fuel</b> (154789)..... <b>BF957-D +</b> <b>Coolant</b> (w/4 Units BTA+) (3315116)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (3315114)..... <b>BW5074</b> <b>Coolant</b> (w/15 Units BTA+) (3318318)..... <b>BW5075</b>
ACM w/Cat 3406 (14.6L) Eng. <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99 +</b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> <b>Fuel/Water Separator Spin-on</b> (2568753)..... <b>BF1259</b> <b>P. Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (1R0712)..... <b>BF614 +</b>	ACM w/Volvo TD122 (12.0L) Eng. <b>F-F Lube</b> (21707134)..... <b>B76 +</b> <b>Severe Service F-F Lube</b> (21707134)..... <b>B76-SS +</b> <b>P. Fuel</b> (4669875)..... <b>BF988 +</b> <b>S. Fuel</b> (991203640)..... <b>BF788</b>	J9C0 w/Cummins N14 (14.0L) Eng. <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Fuel/Water Separator</b> (3308638). <b>BF1212 +</b> <b>Fuel</b> (154789)..... <b>BF957-D +</b> <b>Coolant</b> (w/4 Units BTA+) (3315116)..... <b>BW5071</b> <b>Coolant</b> (w/23 Units BTA+) (4058965)..... <b>BW5076</b>
ACM w/Cat 3406 (14.6L) Eng. <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99 +</b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> <b>Fuel/Water Separator Spin-on</b> (2568753)..... <b>BF1259</b> <b>P. Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (1R0712)..... <b>BF614 +</b>	J9C0 w/Detroit Diesel 6-71 (7.0L) Eng. <b>F-F Lube</b> (23530407)..... <b>B95 +</b> <b>F-F Lube</b> (23530408)..... <b>B95-MPG +</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b> <b>S. Fuel</b> (23530645)..... <b>BF5815</b>	J9C0 w/Detroit Diesel 6-71 (7.0L) Eng. <b>F-F Lube</b> (23530407)..... <b>B95 +</b> <b>F-F Lube</b> (23530408)..... <b>B95-MPG +</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b> <b>S. Fuel</b> (23530645)..... <b>BF5815</b>

+ See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

**Trucks & Buses Applications** **BALDWIN FILTERS**

WHITE/GMC Trucks (cont'd)	WHITE/GMC Trucks (cont'd)	WHITE/GMC Trucks (cont'd)
J9C0 w/Detroit Diesel 6V-92N (9.0L) Eng. F-F Lube (23530407)..... B95 + F-F Lube (23530408)..... B95-MPG + P. Fuel (23530706)..... BF5800 + S. Fuel (23530707)..... BF5810 S. Fuel (23530645)..... BF5815	Road Boss 2 w/Cat 3306 Eng. Lube (Standard Vers.)..... B76 Box-Style Fuel/Water Separator..... BF912 Fuel Spin-on..... BF970 + Air (22005-0002)..... PA2429	Road Commander 2 w/Cat 3406 Eng. (Cont'd) Coolant Spin-on..... BW5137
J9C0 w/Detroit Diesel Series 60 (11.1L) Eng. F-F Lube (25010495)..... [2] B95 + B-P Lube (23530413)..... BF5777 Fuel/Water Separator Ele. (Davco 301SD19B)..... PF7680 Fuel/Water Separator Ele. (Davco 382114)..... PF7748 Fuel/Water Separator Spin-on (w/Drain) (23512317)..... BF5813 + Fuel/Water Separator Spin-on (Open End for Bowl) (23512317).. BF5813-O + Opt. Fuel/Water Separator Spin-on (23516189)..... BF5812 Opt. Fuel/Water Separator Spin-on (Alliance ABPN122R50407)..... BF1283-SP + P. Fuel (25014274)..... BF5800 + S. Fuel (23518482)..... BF5810 Coolant (Nalcool NF2088)..... BW5200	Road Boss 2 w/Cat 3406 Eng. Lube..... B99 + Fuel Spin-on..... BF614 + Air (22005-0002)..... PA2429 Air (2-7092086)..... PA2393 Coolant Spin-on..... BW5137	Road Commander 2 w/Detroit Diesel Eng. F-F Lube Ele..... P20-HD + F-F Lube Spin-on..... B95 + P. Fuel Spin-on..... BF5800 + S. Fuel Spin-on..... BF5810 Air (22005-0002)..... PA2429 Air (22005-0008)..... PA2500 + Air (22005-5015)..... PA3951 Air (2-7092086)..... PA2393
Road Boss, Road Boss 2 w/Cat 3208 Eng. Lube (9L9200)..... [2] BT364 Lube (9N5570)..... [2] BT230 + Box-Style Fuel/Water Separator..... BF912 Fuel Spin-on..... BF970 + Air (22005-0002)..... PA2429	Road Commander w/Cat 1674 Eng. Lube..... PT670 Fuel Spin-on..... BF970 + Opt. Air Comp. Breather..... PA1704	Road Xpeditor w/Cat 1160 Eng. Lube..... [2] BT364 Fuel..... BF583
Road Boss, Road Boss 2 w/Cummins Eng. F-F Lube Bag..... P996 F-F Lube Ele..... P999-HD F-F Lube Spin-on..... B196 + B-P Lube Ele..... C750-E + Fuel/Water Separator..... BF1212 + 4 3/8 In. Fuel Spin-on..... BF948 + 5 3/4 In. Fuel Spin-on..... BF957 + 11 7/32 In. Fuel Spin-on..... BF596 + Air (2-7092086)..... PA2393 Air (22005-0002)..... PA2429 Air (22005-0013)..... PA2648 Breather Ele. (w/Turbo) (255963) PA643 Breather Ele. (w/o Turbo) (256837)..... PA1627 Turbocharger..... BT112	Road Commander w/GMC 6-71, 8V-71 Series Engs. F-F Lube Ele..... P20-HD + B-P Lube Ele..... P52 P. Fuel Sock (5574961)..... F916-C S. Fuel Ele. (5574508)..... PF902	Road Xpeditor w/GMC Diesel Eng. F-F Lube..... P20-HD + B-P Lube..... P52 P. Fuel Sock..... F916-C 3 5/8 In. S. Fuel Ele..... PF906 7 13/16 In. S. Fuel Ele..... PF902
Road Boss, Road Boss 2 w/GMC Diesel Eng. F-F Lube Ele..... P20-HD + P. Fuel Spin-on..... BF5800 + S. Fuel Spin-on..... BF5810 Air (22005-0002)..... PA2429 Air (22005-0009)..... PA2544 Air (2-7092086)..... PA2393	Road Commander, Road Commander 2 w/Cat 3208 Eng. Lube (9L9200)..... [2] BT364 Lube (9N5570)..... [2] BT230 + Box-Style Fuel/Water Separator..... BF912 Fuel Spin-on..... BF970 + Air (22005-0002)..... PA2429	Road Xpeditor, Road Xpeditor 2 w/Cat 3208 Eng. Lube (9L9200)..... [2] BT364 Lube (9N5570)..... [2] BT230 + Box-Style Fuel/Water Separator..... BF912 Fuel Spin-on..... BF970 + Air (22005-0002)..... PA2429 Air (2-7092086)..... PA2393
	Road Commander, Road Commander 2 w/Cummins Eng. F-F Lube Bag..... P996 F-F Lube Ele..... P999-HD F-F Lube Spin-on..... B196 + B-P Lube Ele..... C750-E + Fuel/Water Separator..... BF1212 + 4 3/8 In. Fuel Spin-on..... BF948 + 5 3/4 In. Fuel Spin-on..... BF957 + 11 7/32 In. Fuel Spin-on..... BF596 + Air (2-7092086)..... PA2393 Air (22005-5015)..... PA3951 Air (22005-0002)..... PA2429 Breather Ele. (w/Turbo) (255963) PA643 Breather Ele. (w/o Turbo) (256837)..... PA1627 Turbocharger..... BT112	Road Xpeditor, Xpeditor, Road Xpeditor 2 w/Cummins Eng. F-F Lube Bag..... P996 F-F Lube Ele..... P999-HD F-F Lube Spin-on..... B196 + B-P Lube Ele..... C750-E + B-P Lube Spin-on..... B7577 Fuel/Water Separator..... BF1212 + 4 3/8 In. Fuel Spin-on..... BF948 + 5 3/4 In. Fuel Spin-on..... BF957 + 11 7/32 In. Fuel Spin-on..... BF596 + Air (22005-0002)..... PA2429 Air (22005-0008)..... PA2500 + Air (2-7092086)..... PA2393 Breather Ele. (w/Turbo) (255963) PA643 Breather Ele. (w/o Turbo) (256837)..... PA1627 Turbocharger..... BT112
	Road Commander 2 w/Cat 3306 Eng. Lube (Standard Vers.)..... B76 Box-Style Fuel/Water Separator..... BF912 Fuel Spin-on..... BF970 + Air (22005-0002)..... PA2429 Air (2-7092086)..... PA2393	Road Xpeditor 2 w/Cat 3306 Eng. Lube (Standard Vers.)..... B76 Box-Style Fuel/Water Separator..... BF912 Fuel Spin-on..... BF970 + Air (22005-0002)..... PA2429 Air (2-7092086)..... PA2393
	Road Commander 2 w/Cat 3406 Eng. Lube..... B99 + Fuel Spin-on..... BF614 + Air (22005-0002)..... PA2429 Air (22005-5015)..... PA3951 Air (2-7092086)..... PA2393	Road Xpeditor 2 w/Detroit Diesel Eng. F-F Lube Ele..... P20-HD + F-F Lube Spin-on..... B95 + P. Fuel Spin-on..... BF5800 + S. Fuel Spin-on..... BF5810

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

 **WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

WHITE/GMC Trucks (cont'd)	WHITE/GMC Trucks (cont'd)	WHITE/GMC Trucks (cont'd)
Road Xpeditor 2 w/Detroit Diesel Eng. (Cont'd)	WAH w/Detroit Diesel Series 60 (11.1L) Eng. (1993-on)	WCA w/Cat 3306 (10.5L) Eng. (Cont'd)
Air (22005-0002)..... PA2429	F-F Lube (23518480)..... [2] B495	P. Fuel Ele. (9M2342)..... PF935
Air (22005-0008)..... PA2500 +	Fuel/Water Separator Ele. (Davco 301SD19B)..... PF7680	P. Fuel Spin-on (1R1740)..... BF970 +
Air (2-7092086)..... PA2393	Fuel/Water Separator Ele. (Davco 382114)..... PF7748	S. Fuel Spin-on (1R0750)..... BF7633 +
WA, WB, WC Series (Except 28)	Fuel/Water Separator Spin-on (w/Drain) (23512317)..... BF5813 +	Trans. (Fuller 4304827)..... BT223
B-P Lube Sock..... CU406 <sup>90</sup>	Fuel/Water Separator Spin-on (Open End for Bowl) (23512317).. BF5813-O +	Opt. Trans. (Fuller 17237)..... B2 +
WAH w/Cummins M11 (10.8L) Eng. (To 12/1995)	Opt. Fuel/Water Separator Spin-on (23516189)..... BF5812	Trans. (Auxiliary) (Allison 29510918)..... PT8330-MPG
Dual-Flow Lube (3318853)..... BD103 +	Opt. Fuel/Water Separator Spin-on (Alliance ABPN122R50407)..... BF1283-SP +	WCA w/Cat 3406 (14.6L) Eng.
Fuel/Water Separator Ele. (Fleetguard FS1029W)..... PF7680	P. Fuel (25014274)..... BF5800 +	Lube (1R0716)..... B99 +
Fuel/Water Separator Spin-on (3308638)..... BF1212 +	S. Fuel (23518482)..... BF5810	Fuel Ele. (9M2342)..... [2] PF935
Trans. (Fuller 4304827)..... BT223	Air Dryer (Coalescer Vers.) (Wabco R950068)..... BA5379 +	Fuel Spin-on (4N5823)..... BF614 +
Opt. Trans. (Fuller 17237)..... B2 +	Air Dryer (Desiccant Vers.) (Bendix 109994)..... BA5374 +	WCA w/Cummins L10 (10.0L) Eng.
Trans. (Auxiliary) (Allison 29510918)..... PT8330-MPG	Coolant (Nalcool NF2088)..... BW5200	Dual-Flow Lube (3318853)..... BD103 +
WAH w/Cummins M11 (10.8L) Eng. (12/1995-on)	Trans. (Fuller 4304827)..... BT223	F-F Lube (Fleetguard LF670SC).. B196 +
Dual-Flow Lube (3318853)..... BD103 +	Opt. Trans. (Fuller 17237)..... B2 +	B-P Lube (3304232)..... B7577
Fuel/Water Separator Ele. (Fleetguard FS1029W)..... PF7680	Trans. (Auxiliary) (Allison 29510918)..... PT8330-MPG	Fuel/Water Separator (3308638)..... BF1212 +
Fuel/Water Separator Spin-on (3329289)..... BF1259	WCA w/Cat 3176 (10.3L) Eng.	Fuel (154789)..... BF957-D +
Trans. (Fuller 4304827)..... BT223	F-F Lube (Std. Version) (1R0716)..... B99 +	Coolant (w/4 Units BTA+) (3315116)..... BW5071
Opt. Trans. (Fuller 17237)..... B2 +	F-F Lube (High Efficiency Vers.) (1R1808)..... B7299 +	Coolant (w/12 Units BTA+) (3315114)..... BW5074
Trans. (Auxiliary) (Allison 29510918)..... PT8330-MPG	F-F Lube (8N9586)..... BT230 +	Coolant (w/15 Units BTA+) (3318318)..... BW5075
WAH w/Detroit Diesel Series 60 (11.1L) Eng. (To 1993)	F-F Lube (9N6007)..... B75	Trans. (Fuller 4304827)..... BT223
F-F Lube (25010495)..... [2] B95 +	Opt. B-P Lube (1W8845)..... B7577	Opt. Trans. (Fuller 17237)..... B2 +
B-P Lube (23530413)..... B7577	Fuel/Water Separator Ele. (8N0205)..... PF316	Trans. (Auxiliary) (Allison 29510918)..... PT8330-MPG
Fuel/Water Separator Ele. (Davco 301SD19B)..... PF7680	Fuel/Water Separator Spin-on (2568753)..... BF1259	WCA w/Cummins M11 (10.8L) Eng. (To 12/1995)
Fuel/Water Separator Ele. (Davco 382114)..... PF7748	P. Fuel Ele. (9M2342)..... [2] PF935	Dual-Flow Lube (3318853)..... BD103 +
Fuel/Water Separator Spin-on (w/Drain) (23512317)..... BF5813 +	P. Fuel Spin-on (1R1740)..... BF970 +	Fuel/Water Separator Ele. (Fleetguard FS1029W)..... PF7680
Fuel/Water Separator Spin-on (Open End for Bowl) (23512317).. BF5813-O +	Fuel Spin-on (High Efficiency) (1R0750)..... BF7633 +	Fuel/Water Separator Spin-on (3308638)..... BF1212 +
Opt. Fuel/Water Separator Spin-on (23516189)..... BF5812	Fuel Spin-on (1R0712)..... BF614 +	Trans. (Fuller 4304827)..... BT223
Opt. Fuel/Water Separator Spin-on (Alliance ABPN122R50407)..... BF1283-SP +	Trans. (Fuller 4304827)..... BT223	Opt. Trans. (Fuller 17237)..... B2 +
P. Fuel (25014274)..... BF5800 +	Opt. Trans. (Fuller 17237)..... B2 +	Trans. (Auxiliary) (Allison 29510918)..... PT8330-MPG
S. Fuel (23518482)..... BF5810	WCA w/Cat 3306 (10.5L) Eng.	WCA w/Cummins M11 (10.8L) Eng. (12/1995-on)
Air Dryer (Coalescer Vers.) (Wabco R950068)..... BA5379 +	Lube Ele. (5S0484)..... PT670	Dual-Flow Lube (3318853)..... BD103 +
Air Dryer (Desiccant Vers.) (Bendix 109994)..... BA5374 +	Lube Spin-on (1R0716)..... B99 +	Fuel/Water Separator Ele. (Fleetguard FS1029W)..... PF7680
Coolant (Nalcool NF2088)..... BW5200	Lube Spin-on (Standard Vers.) (1R0739)..... B76 +	Fuel/Water Separator Spin-on (3329289)..... BF1259
Trans. (Fuller 4304827)..... BT223	Lube Spin-on (Severe Service) (1R0739)..... B76-SS +	Trans. (Fuller 4304827)..... BT223
Opt. Trans. (Fuller 17237)..... B2 +	Box-Style Glass Fuel/Water Separator (6N7617)..... BF912	Opt. Trans. (Fuller 17237)..... B2 +
Trans. (Auxiliary) (Allison 29510918)..... PT8330-MPG	Fuel/Water Separator Ele. (8N0205)..... PF316	Trans. (Auxiliary) (Allison 29510918)..... PT8330-MPG
	Fuel/Water Separator Spin-on (2568753)..... BF1259	WCA w/Cummins N14 (14.0L) Eng.
		Dual-Flow Lube (3318853)..... BD103 +
		F-F Lube (Fleetguard LF670SC).. B196 +
		B-P Lube (3304232)..... B7577
		Fuel/Water Separator (3308638)..... BF1212 +
		Fuel (154789)..... BF957-D +
		Air Dryer (Coalescer Vers.) (Wabco R950068)..... BA5379 +

+ See Product Guide for Variations of This Number. <sup>90</sup> Obsolete Pending.

Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>WHITE/GMC Trucks (cont'd)</b>	<b>WHITE/GMC Trucks (cont'd)</b>	<b>WHITE/GMC Trucks (cont'd)</b>	
<b>WCA w/Cummins N14 (14.0L) Eng. (Cont'd)</b> <b>Air Dryer</b> (Desiccant Vers.) (Bendix 109994)..... <b>BA5374 +</b> <b>Coolant</b> (w/4 Units BTA+) (3315116)..... <b>BW5071</b> <b>Coolant</b> (w/23 Units BTA+) (4058965)..... <b>BW5076</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Trans.</b> (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b>	<b>WCL w/Cat 3306 (10.5L) Eng. (Cont'd)</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Trans.</b> (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b> <b>WCL w/Cat 3406 (14.6L) Eng.</b> <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99 +</b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> <b>Fuel/Water Separator Spin-on</b> (2568753)..... <b>BF1259</b> <b>P. Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (1R0712)..... <b>BF614 +</b> <b>Fuel Spin-on</b> (1R0749)..... <b>BF7587 +</b> <b>Air Dryer</b> (Coalescer Vers.) (Wabco R950068)..... <b>BA5379 +</b> <b>Air Dryer</b> (Desiccant Vers.) (Bendix 109994)..... <b>BA5374 +</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>WCL w/Cummins L10 (10.0L) Eng.</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Fuel/Water Separator</b> (3308638). <b>BF1212 +</b> <b>Fuel</b> (154789)..... <b>BF957-D +</b> <b>Coolant</b> (w/4 Units BTA+) (3315116)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (3315114)..... <b>BW5074</b> <b>Coolant</b> (w/15 Units BTA+) (3318318)..... <b>BW5075</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Trans.</b> (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b>	<b>WCL w/Detroit Diesel 6V-92N (9.0L) Eng.</b> <b>F-F Lube</b> (23530407)..... <b>B95 +</b> <b>F-F Lube</b> (23530408)..... <b>B95-MPG +</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b> <b>S. Fuel</b> (23530645)..... <b>BF5815</b> <b>WCL w/Detroit Diesel 8V-92 (12.1L) Eng.</b> <b>Lube Ele.</b> (5573013)..... <b>P20-HD</b> <b>Lube Spin-on</b> (23530407)..... <b>B95 +</b> <b>Lube Spin-on</b> (23530408)..... <b>B95-MPG +</b> <b>P. Fuel Ele.</b> (9717391)..... <b>PF845</b> <b>P. Fuel Spin-on</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel Ele.</b> (5574508)..... <b>PF902</b> <b>S. Fuel Spin-on</b> (23530707)..... <b>BF5810</b> <b>S. Fuel Spin-on</b> (23530645)..... <b>BF5815</b> <b>WCL w/Detroit Diesel Series 60 (11.1L), (12.7L) Eng.</b> <b>Lube</b> ..... <b>[2] B495</b> <b>P. Fuel</b> ..... <b>BF5800 +</b> <b>S. Fuel</b> ..... <b>BF5810</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>WCA w/Volvo D12 (12.1L) Eng.</b> <b>Fuel/Water Separator</b> (Alliance ABPN122R50551)..... <b>BF46016-O</b> <b>WCA w/Volvo TD122 (12.0L) Eng.</b> <b>F-F Lube</b> (21707134)..... <b>B76 +</b> <b>Severe Service F-F Lube</b> (21707134)..... <b>B76-SS +</b> <b>P. Fuel</b> (4669875)..... <b>BF988 +</b> <b>S. Fuel</b> (991203640)..... <b>BF788</b> <b>WCL w/Cat 3306 (10.5L) Eng.</b> <b>Lube Ele.</b> (5S0484)..... <b>PT670</b> <b>Lube Spin-on</b> (1R0716)..... <b>B99 +</b> <b>Lube Spin-on</b> (Standard Vers.) (1R0739)..... <b>B76 +</b> <b>Lube Spin-on</b> (Severe Service) (1R0739)..... <b>B76-SS +</b> <b>Box-Style Glass Fuel/Water Separator</b> (6N7617)..... <b>BF912</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Fuel/Water Separator Spin-on</b> (2568753)..... <b>BF1259</b> <b>P. Fuel Ele.</b> (9M2342)..... <b>PF935</b> <b>P. Fuel Spin-on</b> (1R1740)..... <b>BF970 +</b> <b>S. Fuel Spin-on</b> (1R0750)..... <b>BF7633 +</b>	<b>WCL w/Detroit Diesel 8V-92 (12.1L) Eng.</b> <b>Lube Ele.</b> (5573013)..... <b>P20-HD</b> <b>Lube Spin-on</b> (23530407)..... <b>B95 +</b> <b>Lube Spin-on</b> (23530408)..... <b>B95-MPG +</b> <b>P. Fuel Ele.</b> (9717391)..... <b>PF845</b> <b>P. Fuel Spin-on</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel Ele.</b> (5574508)..... <b>PF902</b> <b>S. Fuel Spin-on</b> (23530707)..... <b>BF5810</b> <b>S. Fuel Spin-on</b> (23530645)..... <b>BF5815</b> <b>WCL w/Detroit Diesel Series 60 (11.1L), (12.7L) or (14.0L) Eng.</b> <b>F-F Lube</b> (25010495)..... <b>[2] B95 +</b> <b>B-P Lube</b> (23530413)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (Davco 301SD19B)..... <b>PF7680</b> <b>Fuel/Water Separator Ele.</b> (Davco 382114)..... <b>PF7748</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (23512317)..... <b>BF5813 +</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (23512317).. <b>BF5813-O +</b> <b>Opt. Fuel/Water Separator Spin-on</b> (23516189)..... <b>BF5812</b> <b>Opt. Fuel/Water Separator Spin-on</b> (Alliance ABPN122R50407)..... <b>BF1283-SP +</b> <b>P. Fuel</b> (25014274)..... <b>BF5800 +</b> <b>S. Fuel</b> (23518482)..... <b>BF5810</b> <b>Air Dryer</b> (Coalescer Vers.) (Wabco R950068)..... <b>BA5379 +</b> <b>Air Dryer</b> (Desiccant Vers.) (Bendix 109994)..... <b>BA5374 +</b> <b>Coolant</b> (Nalcool NF2088)..... <b>BW5200</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Trans.</b> (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b> <b>WCL w/Volvo TD122 (12.0L) Eng.</b> <b>F-F Lube</b> (21707134)..... <b>B76 +</b> <b>Severe Service F-F Lube</b> (21707134)..... <b>B76-SS +</b> <b>P. Fuel</b> (4669875)..... <b>BF988 +</b> <b>S. Fuel</b> (991203640)..... <b>BF788</b> <b>WCM w/Cat 3208 (10.4L) Eng.</b> <b>F-F Lube</b> (9L9200)..... <b>[2] BT364</b> <b>F-F Lube</b> (9N5570)..... <b>[2] BT230</b> <b>F-F Lube</b> (9N6007)..... <b>[2] B75</b> <b>B-P Lube Ele.</b> ..... <b>C750-E +</b> <b>Box-Style Fuel/Water Separator.</b> <b>Fuel Ele.</b> (9M2341)..... <b>PF935</b> <b>Fuel Spin-on</b> ..... <b>BF970 +</b> <b>Fuel Spin-on</b> (1R0750)..... <b>BF7633 +</b>

+ See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

WHITE/GMC Trucks (cont'd)	WHITE/GMC Trucks (cont'd)	WHITE/GMC Trucks (cont'd)
WCM w/Cat 3208 (10.4L) Eng. (Cont'd)	WCM w/Detroit Diesel 6V-92N (9.0L) Eng.	WCM w/Detroit Diesel Series 60 (12.7L) Eng. (To 1993) (Cont'd)
Air (2009007)..... PA2465	F-F Lube (23530407)..... B95 +	Fuel/Water Separator Ele. (Davco 301SD19B)..... PF7680
Comp. Air..... PA1909	F-F Lube (23530408)..... B95-MPG +	Fuel/Water Separator Ele. (Davco 382114)..... PF7748
WCM w/Cat 3306 (10.5L) Eng.	P. Fuel (23530706)..... BF5800 +	Fuel/Water Separator Spin-on (w/Drain) (23512317)..... BF5813 +
Lube Ele. (5S0484)..... PT670	S. Fuel (23530707)..... BF5810	Fuel/Water Separator Spin-on (Open End for Bowl) (23512317).. BF5813-O +
Lube Spin-on (1R0716)..... B99 +	S. Fuel (23530645)..... BF5815	Opt. Fuel/Water Separator Spin-on (23516189)..... BF5812
Lube Spin-on (Standard Vers.) (1R0739)..... B76 +	WCM w/Detroit Diesel 8V-71 (9.3L) Eng.	Opt. Fuel/Water Separator Spin-on (Alliance ABPN122R50407)..... BF1283-SP +
Lube Spin-on (Severe Service) (1R0739)..... B76-SS +	F-F Lube (23530407)..... B95 +	P. Fuel (25014274)..... BF5800 +
Box-Style Glass Fuel/Water Separator (6N7617)..... BF912	F-F Lube (23530408)..... B95-MPG +	S. Fuel (23518482)..... BF5810
Fuel/Water Separator Ele. (8N0205)..... PF316	B-P Lube Ele. (5570092)..... P52	Air Dryer (Coalescer Vers.) (Wabco R950068)..... BA5379 +
Fuel/Water Separator Spin-on (2568753)..... BF1259	P. Fuel Sock (5192854)..... F916-C	Air Dryer (Desiccant Vers.) (Bendix 109994)..... BA5374 +
P. Fuel Ele. (9M2342)..... PF935	P. Fuel Sock (5574980)..... F844-A	Coolant (Nalcool NF2088)..... BW5200
P. Fuel Spin-on (1R1740)..... BF970 +	P. Fuel Ele. (9717391)..... PF845	Trans. (Fuller 4304827)..... BT223
S. Fuel Spin-on (1R0750)..... BF7633 +	P. Fuel Spin-on (23530706)..... BF5800 +	Opt. Trans. (Fuller 17237)..... B2 +
Trans. (Fuller 4304827)..... BT223	S. Fuel Ele. (5574508)..... PF902	Trans. (Auxiliary) (Allison 29510918)..... PT8330-MPG
Opt. Trans. (Fuller 17237)..... B2 +	S. Fuel Ele. (6437284)..... PF846	WCM w/Detroit Diesel Series 60 (12.7L) Eng. (1993-on)
Trans. (Auxiliary) (Allison 29510918)..... PT8330-MPG	S. Fuel Spin-on (23530707)..... BF5810	F-F Lube (23518480)..... [2] B495
WCM w/Cat 3406 (14.6L) Eng.	S. Fuel Spin-on (23530645)..... BF5815	Fuel/Water Separator Ele. (Davco 301SD19B)..... PF7680
Lube (1R0716)..... B99 +	WCM w/Detroit Diesel 8V-92 (12.1L) Eng.	Fuel/Water Separator Ele. (Davco 382114)..... PF7748
Fuel Ele. (9M2342)..... [2] PF935	Lube Ele. (5573013)..... P20-HD	Fuel/Water Separator Spin-on (w/Drain) (23512317)..... BF5813 +
Fuel Spin-on (4N5823)..... BF614 +	Lube Spin-on (23530407)..... B95 +	Fuel/Water Separator Spin-on (Open End for Bowl) (23512317).. BF5813-O +
WCM w/Cat 3408 (18.0L) Eng.	Lube Spin-on (23530408)..... B95-MPG +	Opt. Fuel/Water Separator Spin-on (23516189)..... BF5812
F-F Lube (Std. Version) (1R0716)..... B99 +	P. Fuel Ele. (9717391)..... PF845	Opt. Fuel/Water Separator Spin-on (Alliance ABPN122R50407)..... BF1283-SP +
F-F Lube (High Efficiency Vers.) (1R1808)..... B7299 +	P. Fuel Spin-on (23530706)..... BF5800 +	P. Fuel (25014274)..... BF5800 +
P. Fuel Ele. (9M2341)..... [2] PF935	S. Fuel Ele. (5574508)..... PF902	S. Fuel (23518482)..... BF5810
Fuel Spin-on (1R0749)..... BF7587 +	S. Fuel Spin-on (23530707)..... BF5810	Air Dryer (Coalescer Vers.) (Wabco R950068)..... BA5379 +
Fuel Spin-on (1R0712)..... BF614 +	S. Fuel Spin-on (23530645)..... BF5815	Air Dryer (Desiccant Vers.) (Bendix 109994)..... BA5374 +
WCM w/Cummins L10 (10.0L) Eng.	WCM w/Detroit Diesel Series 60 (11.1L) Eng.	Coolant (Nalcool NF2088)..... BW5200
Dual-Flow Lube (3318853)..... BD103 +	F-F Lube (25010495)..... [2] B95 +	Trans. (Fuller 4304827)..... BT223
F-F Lube (Fleetguard LF670SC).. B196 +	B-P Lube (23530413)..... B7577	Opt. Trans. (Fuller 17237)..... B2 +
B-P Lube (3304232)..... B7577	Fuel/Water Separator Ele. (Davco 301SD19B)..... PF7680	Trans. (Auxiliary) (Allison 29510918)..... PT8330-MPG
Fuel (154789)..... BF957-D +	Fuel/Water Separator Ele. (Davco 382114)..... PF7748	WCM w/Volvo TD122 (12.0L) Eng.
WCM w/Cummins N14 (14.0L) Eng.	Fuel/Water Separator Spin-on (w/Drain) (23512317)..... BF5813 +	F-F Lube (21707134)..... B76 +
F-F Lube (Fleetguard LF670SC).. B196 +	Fuel/Water Separator Spin-on (Open End for Bowl) (23512317).. BF5813-O +	Severe Service F-F Lube (21707134)..... B76-SS +
B-P Lube (3304232)..... B7577	Opt. Fuel/Water Separator Spin-on (23516189)..... BF5812	P. Fuel (4669875)..... BF988 +
Dual-Flow Lube (3318853)..... BD103 +	Opt. Fuel/Water Separator Spin-on (Alliance ABPN122R50407)..... BF1283-SP +	S. Fuel (991203640)..... BF788
Fuel (154789)..... BF957-D +	P. Fuel (25014274)..... BF5800 +	
WCM w/Cummins VT903 (14.8L) Eng.	S. Fuel (23518482)..... BF5810	
F-F Lube Ele. (158139)..... P999-HD	Air Dryer (Coalescer Vers.) (Wabco R950068)..... BA5379 +	
F-F Lube Spin-on..... B196 +	Air Dryer (Desiccant Vers.) (Bendix 109994)..... BA5374 +	
B-P Lube Ele. (256838)..... C750-E +	Coolant (Nalcool NF2088)..... BW5200	
B-P Lube Spin-on (3313283)..... B7577	Trans. (Fuller 4304827)..... BT223	
Fuel/Water Separator (3308638)..... BF1212 +	Opt. Trans. (Fuller 17237)..... B2 +	
Fuel Spin-on..... BF957-D +	Trans. (Auxiliary) (Allison 29510918)..... PT8330-MPG	
WCM w/Detroit Diesel 6-71 (7.0L) Eng.	WCM w/Detroit Diesel Series 60 (12.7L) Eng. (To 1993)	
F-F Lube (23530407)..... B95 +	F-F Lube (25010495)..... [2] B95 +	
F-F Lube (23530408)..... B95-MPG +	B-P Lube (23530413)..... B7577	
P. Fuel (23530706)..... BF5800 +		
S. Fuel (23530707)..... BF5810		
S. Fuel (23530645)..... BF5815		

+ See Product Guide for Variations of This Number. Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

**Trucks & Buses Applications** **BALDWIN FILTERS**

<b>WHITE/GMC Trucks (cont'd)</b>	<b>WHITE/GMC Trucks (cont'd)</b>	<b>WHITE/GMC Trucks (cont'd)</b>
<b>WCS w/Cat 3208 (10.4L) Eng.</b> <b>F-F Lube</b> (9L9200)..... [2] <b>BT364</b> <b>F-F Lube</b> (9N5570)..... [2] <b>BT230</b> <b>F-F Lube</b> (9N6007)..... [2] <b>B75</b> <b>Box-Style Fuel/Water Separator.</b> <b>BF912</b> <b>Fuel Ele.</b> (9M2341)..... <b>PF935</b> <b>Fuel Spin-on</b> ..... <b>BF970 +</b> <b>Fuel Spin-on</b> (1R0750)..... <b>BF7633 +</b>	<b>WCS w/Cummins N14 (14.0L) Eng.</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Fuel/Water Separator</b> (3308638). <b>BF1212 +</b> <b>Fuel</b> (154789)..... <b>BF957-D +</b> <b>Air Dryer</b> (Coalescer Vers.) (Wabco R950068)..... <b>BA5379 +</b> <b>Air Dryer</b> (Desiccant Vers.) (Bendix 109994)..... <b>BA5374 +</b> <b>Coolant</b> (w/4 Units BTA+) (3315116)..... <b>BW5071</b> <b>Coolant</b> (w/23 Units BTA+) (4058965)..... <b>BW5076</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Trans.</b> (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b>	<b>WG w/Cat 3176 (10.3L) Eng. (Cont'd)</b> <b>Fuel Spin-on</b> (1R0712)..... <b>BF614 +</b> <b>Fuel Spin-on</b> (High Efficiency) (1R0750)..... <b>BF7633 +</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>
<b>WCS w/Cat 3306 (10.5L) Eng.</b> <b>Lube Ele.</b> (5S0484)..... <b>PT670</b> <b>Lube Spin-on</b> (1R0716)..... <b>B99 +</b> <b>Lube Spin-on</b> (Standard Vers.) (1R0739)..... <b>B76 +</b> <b>Lube Spin-on</b> (Severe Service) (1R0739)..... <b>B76-SS +</b> <b>Box-Style Glass Fuel/Water  Separator</b> (6N7617)..... <b>BF912</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Fuel/Water Separator Spin-on</b> (2568753)..... <b>BF1259</b> <b>P. Fuel Ele.</b> (9M2342)..... <b>PF935</b> <b>P. Fuel Spin-on</b> (1R1740)..... <b>BF970 +</b> <b>S. Fuel Spin-on</b> (1R0750)..... <b>BF7633 +</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Trans.</b> (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b>	<b>WCS w/Detroit Diesel 6-71 (7.0L) Eng.</b> <b>F-F Lube</b> (23530407)..... <b>B95 +</b> <b>F-F Lube</b> (23530408)..... <b>B95-MPG +</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b> <b>S. Fuel</b> (23530645)..... <b>BF5815</b>	<b>WG w/Cat 3306 (10.5L) Eng.</b> <b>Lube Ele.</b> (5S0484)..... <b>PT670</b> <b>Lube Spin-on</b> (1R0716)..... <b>B99 +</b> <b>Lube Spin-on</b> (Standard Vers.) (1R0739)..... <b>B76 +</b> <b>Lube Spin-on</b> (Severe Service) (1R0739)..... <b>B76-SS +</b> <b>Box-Style Glass Fuel/Water  Separator</b> (6N7617)..... <b>BF912</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Fuel/Water Separator Spin-on</b> (2568753)..... <b>BF1259</b> <b>P. Fuel Ele.</b> (9M2342)..... <b>PF935</b> <b>P. Fuel Spin-on</b> (1R1740)..... <b>BF970 +</b> <b>S. Fuel Spin-on</b> (1R0750)..... <b>BF7633 +</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Trans.</b> (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b>
<b>WCS w/Cat 3406 (14.6L) Eng.</b> <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99 +</b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> <b>Fuel/Water Separator Spin-on</b> (2568753)..... <b>BF1259</b> <b>P. Fuel Ele.</b> (9M2342)..... [2] <b>PF935</b> <b>Fuel Spin-on</b> (1R0712)..... <b>BF614 +</b> <b>Fuel Spin-on</b> (1R0749)..... <b>BF7587 +</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	<b>WCS w/Detroit Diesel 6V-92N (9.0L) Eng.</b> <b>F-F Lube</b> (23530407)..... <b>B95 +</b> <b>F-F Lube</b> (23530408)..... <b>B95-MPG +</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b> <b>S. Fuel</b> (23530645)..... <b>BF5815</b>	<b>WG w/Cummins L10 (10.0L) Eng.</b> <b>Dual-Flow Lube</b> ..... <b>BD103 +</b> <b>F-F Lube</b> ..... <b>B196 +</b> <b>B-P Lube</b> ..... <b>B7577</b> <b>Opt. Fuel/Water Separator</b> ..... <b>BF1212 +</b> <b>Fuel Spin-on</b> ..... <b>BF957 +</b> <b>Radial Seal O. Air</b> (Standard) (V1117576)..... <b>RS3518</b> <b>Radial Seal XP O. Air</b> (Upgrade) (V1117576)..... <b>RS3518XP</b> <b>Radial Seal I. Air</b> ..... <b>RS3519</b>
<b>WCS w/Cummins L10 (10.0L) Eng.</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Fuel/Water Separator</b> (3308638). <b>BF1212 +</b> <b>Fuel</b> (154789)..... <b>BF957-D +</b> <b>Coolant</b> (w/4 Units BTA+) (3315116)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (3315114)..... <b>BW5074</b> <b>Coolant</b> (w/15 Units BTA+) (3318318)..... <b>BW5075</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Trans.</b> (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b>	<b>WG w/Cat 3116 (6.6L) Eng.</b> <b>Lube</b> (Standard Vers.) (1R0739).. <b>B76 +</b> <b>Lube</b> (Severe Service) (1R0739).. <b>B76-SS +</b> <b>Box-Style Fuel/Water Separator</b> (6N7617)..... <b>BF912</b> <b>Fuel/Water Coalescer Ele. w/Drain</b> (1174089)..... <b>BF7679-D</b> <b>Fuel/Water Separator Spin-on</b> (w/Sensor Port) (1466695)..... <b>BF1350-SP</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (1466695).... <b>BF46030-O</b> <b>Fuel Spin-on</b> (1R0750)..... <b>BF7633 +</b> <b>Fuel Spin-on</b> (1R0751)..... <b>BF7632</b> <b>Fuel Spin-on</b> ..... <b>BF984</b> <b>Comp. Air Breather</b> (9L2169)..... <b>PA1704</b>	<b>WG w/Cummins M11 (10.8L) Eng. (To 12/1995)</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> (3308638)..... <b>BF1212 +</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>
<b>WCS w/Cummins L10 (10.0L) Eng.</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Fuel/Water Separator</b> (3308638). <b>BF1212 +</b> <b>Fuel</b> (154789)..... <b>BF957-D +</b> <b>Coolant</b> (w/4 Units BTA+) (3315116)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (3315114)..... <b>BW5074</b> <b>Coolant</b> (w/15 Units BTA+) (3318318)..... <b>BW5075</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Trans.</b> (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b>	<b>WG w/Cat 3176 (10.3L) Eng.</b> <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99 +</b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> <b>F-F Lube</b> (8N9586)..... <b>BT230 +</b> <b>F-F Lube</b> (9N6007)..... <b>B75</b> <b>Opt. B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Fuel/Water Separator Spin-on</b> (2568753)..... <b>BF1259</b> <b>P. Fuel Ele.</b> (9M2342)..... [2] <b>PF935</b> <b>P. Fuel Spin-on</b> (1R1740)..... <b>BF970 +</b>	<b>WG w/Cummins M11 (10.8L) Eng. (12/1995-on)</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> (3329289)..... <b>BF1259</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>
	<b>WG w/Cummins N14 (14.0L) Eng.</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Fuel/Water Separator</b> (3308638). <b>BF1212 +</b>	

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



WHITE/GMC Trucks (cont'd)	WHITE/GMC Trucks (cont'd)	WHITE/GMC Trucks (cont'd)
WG w/Cummins N14 (14.0L) Eng. (Cont'd)	WHEB w/Cat 3406 (14.6L) Eng.	WHL w/Cat 3176 (10.3L) Eng.
Fuel (154789)..... <b>BF957-D +</b>	F-F Lube (Std. Version)	F-F Lube (Std. Version)
Radial Seal O. Air (Standard)	(1R0716)..... <b>B99 +</b>	(1R0716)..... <b>B99 +</b>
(V1117576)..... <b>RS3518</b>	F-F Lube (High Efficiency Vers.)	F-F Lube (High Efficiency Vers.)
Radial Seal XP O. Air (Upgrade)	(1R1808)..... <b>B7299 +</b>	(1R1808)..... <b>B7299 +</b>
(V1117576)..... <b>RS3518XP</b>	Fuel/Water Separator Spin-on	F-F Lube (8N9586)..... <b>BT230 +</b>
Radial Seal I. Air..... <b>RS3519</b>	(2568753)..... <b>BF1259</b>	F-F Lube (9N6007)..... <b>B75</b>
Air Dryer (Coalescer Vers.)	P. Fuel Ele. (9M2342)..... <b>[2] PF935</b>	Opt. B-P Lube (1W8845)..... <b>B7577</b>
(Wabco R950068)..... <b>BA5379 +</b>	Fuel Spin-on (1R0712)..... <b>BF614 +</b>	Fuel/Water Separator Ele.
Air Dryer (Desiccant Vers.)	Fuel Spin-on (1R0749)..... <b>BF7587 +</b>	(8N0205)..... <b>PF316</b>
(Bendix 109994)..... <b>BA5374 +</b>	WHEB w/Cummins N14 (14.0 L) Eng.	Fuel/Water Separator Spin-on
Coolant (w/4 Units BTA+)..... <b>BW5071</b>	Dual-Flow Lube (3318853)..... <b>BD103 +</b>	(2568753)..... <b>BF1259</b>
Coolant (w/23 Units BTA+)..... <b>BW5076</b>	F-F Lube (Fleetguard LF670SC)..... <b>B196 +</b>	P. Fuel Ele. (9M2342)..... <b>[2] PF935</b>
(4058965)..... <b>BW5076</b>	B-P Lube (3304232)..... <b>B7577</b>	Fuel Spin-on (1R0712)..... <b>BF614 +</b>
Trans. (Fuller 4304827)..... <b>BT223</b>	Fuel/Water Separator (3308638)..... <b>BF1212 +</b>	Fuel Spin-on (High Efficiency)
Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	Fuel (154789)..... <b>BF957-D +</b>	(1R0750)..... <b>BF7633 +</b>
Trans. (Auxiliary) (Allison	Coolant (w/4 Units BTA+)..... <b>BW5071</b>	Fuel Spin-on (1R1740)..... <b>BF970 +</b>
29510918)..... <b>PT8330-MPG</b>	Coolant (w/23 Units BTA+)..... <b>BW5076</b>	Trans. (Fuller 4304827)..... <b>BT223</b>
WG w/Detroit Diesel Series 60 (11.1L) Eng. (To 1993)	WHEB w/Detroit Diesel Series 60 (11.1L) or (12.7L) Eng. (1993-on)	WHL w/Cat 3208 (10.4L) Eng.
F-F Lube (23530407)..... <b>[2] B95 +</b>	F-F Lube Spin-on (23518480)..... <b>[2] B495</b>	F-F Lube (9L9200)..... <b>[2] BT364</b>
B-P Lube (23530413)..... <b>B7577</b>	Fuel/Water Separator Ele. (Davco 301SD19B)..... <b>PF7680</b>	F-F Lube (9N5570)..... <b>[2] BT230</b>
P. Fuel Spin-on (23530706)..... <b>BF5800 +</b>	Fuel/Water Separator Ele. (Davco 382114)..... <b>PF7748</b>	F-F Lube (9N6007)..... <b>[2] B75</b>
S. Fuel (23530707)..... <b>BF5810</b>	Fuel/Water Separator Spin-on (w/Drain) (23512317)..... <b>BF5813 +</b>	Box-Style Fuel/Water Separator..... <b>BF912</b>
Radial Seal O. Air (Standard)	Fuel/Water Separator Spin-on (Open End for Bowl) (23512317)..... <b>BF5813-O +</b>	Fuel Ele. (9M2341)..... <b>PF935</b>
(V1117576)..... <b>RS3518</b>	Opt. Fuel/Water Separator Spin-on (23516189)..... <b>BF5812</b>	Fuel Spin-on..... <b>BF970 +</b>
Radial Seal XP O. Air (Upgrade)	Opt. Fuel/Water Separator Spin-on (Alliance	Fuel Spin-on (High Efficiency)
(V1117576)..... <b>RS3518XP</b>	ABPN122R50407)..... <b>BF1283-SP +</b>	(1R0750)..... <b>BF7633 +</b>
Radial Seal I. Air..... <b>RS3519</b>	P. Fuel (25014274)..... <b>BF5800 +</b>	WHL w/Cat 3306 (10.5L) Eng.
WG w/Detroit Diesel Series 60 (11.1L) Eng. (1993-on)	S. Fuel (23518482)..... <b>BF5810</b>	Lube Ele. (5S0484)..... <b>PT670</b>
F-F Lube (23530573)..... <b>[2] B495</b>	Coolant (Nalcool NF2088)..... <b>BW5200</b>	Lube Spin-on (1R0716)..... <b>B99 +</b>
P. Fuel Spin-on (23530706)..... <b>BF5800 +</b>	WHEB w/Detroit Diesel Series 60 (11.1L) or (12.7L) Eng. (To 1993)	Lube Spin-on (Standard Vers.) (1R0739)..... <b>B76 +</b>
S. Fuel (23530707)..... <b>BF5810</b>	F-F Lube Spin-on (25010495)..... <b>[2] B95 +</b>	Lube Spin-on (Severe Service) (1R0739)..... <b>B76-SS +</b>
Radial Seal O. Air (Standard)	B-P Lube (23530413)..... <b>B7577</b>	Box-Style Glass Fuel/Water Separator (6N7617)..... <b>BF912</b>
(V1117576)..... <b>RS3518</b>	Fuel/Water Separator Ele. (Davco 301SD19B)..... <b>PF7680</b>	Fuel/Water Separator Ele. (8N0205)..... <b>PF316</b>
Radial Seal XP O. Air (Upgrade)	Fuel/Water Separator Ele. (Davco 382114)..... <b>PF7748</b>	Fuel/Water Separator Spin-on (2568753)..... <b>BF1259</b>
(V1117576)..... <b>RS3518XP</b>	Fuel/Water Separator Spin-on (w/Drain) (23512317)..... <b>BF5813 +</b>	P. Fuel Ele. (9M2342)..... <b>PF935</b>
Radial Seal I. Air..... <b>RS3519</b>	Fuel/Water Separator Spin-on (Open End for Bowl) (23512317)..... <b>BF5813-O +</b>	P. Fuel Spin-on (1R1740)..... <b>BF970 +</b>
WG w/Volvo D12 (12.1L) Eng.	Opt. Fuel/Water Separator Spin-on (23516189)..... <b>BF5812</b>	S. Fuel Spin-on (1R0750)..... <b>BF7633 +</b>
Fuel/Water Separator (Alliance ABPN122R50551)..... <b>BF46016-O</b>	Opt. Fuel/Water Separator Spin-on (Alliance	Trans. (Fuller 4304827)..... <b>BT223</b>
WG w/Volvo TD122 (12.0L) Eng.	ABPN122R50407)..... <b>BF1283-SP +</b>	Opt. Trans. (Fuller 17237)..... <b>B2 +</b>
F-F Lube (466634)..... <b>B76 +</b>	P. Fuel (25014274)..... <b>BF5800 +</b>	Trans. (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b>
Severe Service F-F Lube (466634)..... <b>B76-SS +</b>	S. Fuel (23518482)..... <b>BF5810</b>	WHL w/Cat 3406 (14.6L) Eng.
P. Fuel (466987)..... <b>BF988 +</b>	Coolant (Nalcool NF2088)..... <b>BW5200</b>	F-F Lube (Std. Version)
S. Fuel..... <b>BF788</b>		(1R0716)..... <b>B99 +</b>
Radial Seal O. Air (Standard)		F-F Lube (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b>
(V1117576)..... <b>RS3518</b>		Fuel/Water Separator Spin-on (2568753)..... <b>BF1259</b>
Radial Seal XP O. Air (Upgrade)		P. Fuel Ele. (9M2342)..... <b>[2] PF935</b>
(V1117576)..... <b>RS3518XP</b>		Fuel Spin-on (1R0712)..... <b>BF614 +</b>
Radial Seal I. Air..... <b>RS3519</b>		Fuel Spin-on (1R0749)..... <b>BF7587 +</b>

+ See Product Guide for Variations of This Number. Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

**Trucks & Buses Applications** **BALDWIN FILTERS**

<b>WHITE/GMC Trucks (cont'd)</b>	<b>WHITE/GMC Trucks (cont'd)</b>	<b>WHITE/GMC Trucks (cont'd)</b>
<b>WHL w/Cat 3406 (14.6L) Eng. (Cont'd)</b> <b>Air Dryer</b> (Coalescer Vers.) (Wabco R950068)..... <b>BA5379 +</b> <b>Air Dryer</b> (Desiccant Vers.) (Bendix 109994)..... <b>BA5374 +</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	<b>WHL w/Cummins N14 (14.0L) Eng. (Cont'd)</b> <b>Air Dryer</b> (Desiccant Vers.) (Bendix 109994)..... <b>BA5374 +</b> <b>Coolant</b> (w/4 Units BTA+) (3315116)..... <b>BW5071</b> <b>Coolant</b> (w/23 Units BTA+) (4058965)..... <b>BW5076</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Trans.</b> (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b>	<b>WHL w/Detroit Diesel Series 60 Eng. (1993-on)</b> <b>F-F Lube Spin-on</b> (23518480)..... <b>[2] B495</b> <b>Fuel/Water Separator Ele.</b> (Davco 301SD19B)..... <b>PF7680</b> <b>Fuel/Water Separator Ele.</b> (Davco 382114)..... <b>PF7748</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (23512317)..... <b>BF5813 +</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (23512317).. <b>BF5813-O +</b> <b>Opt. Fuel/Water Separator Spin-on</b> (23516189)..... <b>BF5812</b> <b>Opt. Fuel/Water Separator Spin-on</b> (Alliance ABPN122R50407)..... <b>BF1283-SP +</b> <b>P. Fuel</b> (25014274)..... <b>BF5800 +</b> <b>S. Fuel</b> (23518482)..... <b>BF5810</b> <b>Air Dryer</b> (Coalescer Vers.) (Wabco R950068)..... <b>BA5379 +</b> <b>Air Dryer</b> (Desiccant Vers.) (Bendix 109994)..... <b>BA5374 +</b> <b>Coolant</b> (Nalcool NF2088)..... <b>BW5200</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Trans.</b> (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b>
<b>WHL w/Cat 3408 (18.0L) Eng.</b> <b>F-F Lube Spin-on</b> (1R0716)..... <b>[2] B99 +</b> <b>P. Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (1R0712)..... <b>BF614 +</b> <b>Fuel Spin-on</b> (1R0749)..... <b>BF7587 +</b>	<b>WHL w/Detroit Diesel 6-71 (7.0L) Eng.</b> <b>F-F Lube</b> (23530407)..... <b>B95 +</b> <b>F-F Lube</b> (23530408)..... <b>B95-MPG +</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b> <b>S. Fuel</b> (23530645)..... <b>BF5815</b>	<b>WHLB w/Cat 3176 (10.3L) Eng.</b> <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99 +</b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> <b>F-F Lube</b> (8N9586)..... <b>BT230 +</b> <b>F-F Lube</b> (9N6007)..... <b>B75</b> <b>Opt. B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Fuel/Water Separator Spin-on</b> (2568753)..... <b>BF1259</b> <b>P. Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>P. Fuel Spin-on</b> (1R1740)..... <b>BF970 +</b> <b>Fuel Spin-on</b> (1R0712)..... <b>BF614 +</b> <b>Fuel Spin-on</b> (High Efficiency) (1R0750)..... <b>BF7633 +</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>
<b>WHL w/Cummins L10 (10.0L) Eng.</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Fuel/Water Separator</b> (3308638). <b>BF1212 +</b> <b>Fuel</b> (154789)..... <b>BF957-D +</b> <b>Coolant</b> (w/4 Units BTA+) (3315116)..... <b>BW5071</b> <b>Coolant</b> (w/12 Units BTA+) (3315114)..... <b>BW5074</b> <b>Coolant</b> (w/15 Units BTA+) (3318318)..... <b>BW5075</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Trans.</b> (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b>	<b>WHL w/Detroit Diesel 6V-92N (9.0L) Eng.</b> <b>F-F Lube</b> (23530407)..... <b>B95 +</b> <b>F-F Lube</b> (23530408)..... <b>B95-MPG +</b> <b>P. Fuel</b> (23530706)..... <b>BF5800 +</b> <b>S. Fuel</b> (23530707)..... <b>BF5810</b> <b>S. Fuel</b> (23530645)..... <b>BF5815</b>	<b>WHLB w/Cat 3406 (14.6L) Eng.</b> <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99 +</b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> <b>F-F Lube</b> (8N9586)..... <b>BT230 +</b> <b>F-F Lube</b> (9N6007)..... <b>B75</b> <b>Opt. B-P Lube</b> (1W8845)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Fuel/Water Separator Spin-on</b> (2568753)..... <b>BF1259</b> <b>P. Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>P. Fuel Spin-on</b> (1R1740)..... <b>BF970 +</b> <b>Fuel Spin-on</b> (1R0712)..... <b>BF614 +</b> <b>Fuel Spin-on</b> (High Efficiency) (1R0750)..... <b>BF7633 +</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>
<b>WHL w/Cummins M11 (10.8L) Eng. (To 12/1995)</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> (3308638)..... <b>BF1212 +</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Trans.</b> (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b>	<b>WHL w/Detroit Diesel Series 60 Eng. (To 1993)</b> <b>F-F Lube Spin-on</b> (25010495)..... <b>[2] B95 +</b> <b>B-P Lube</b> (23530413)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (Davco 301SD19B)..... <b>PF7680</b> <b>Fuel/Water Separator Ele.</b> (Davco 382114)..... <b>PF7748</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (23512317)..... <b>BF5813 +</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (23512317).. <b>BF5813-O +</b> <b>Opt. Fuel/Water Separator Spin-on</b> (23516189)..... <b>BF5812</b> <b>Opt. Fuel/Water Separator Spin-on</b> (Alliance ABPN122R50407)..... <b>BF1283-SP +</b> <b>P. Fuel</b> (25014274)..... <b>BF5800 +</b> <b>S. Fuel</b> (23518482)..... <b>BF5810</b> <b>Air Dryer</b> (Coalescer Vers.) (Wabco R950068)..... <b>BA5379 +</b> <b>Air Dryer</b> (Desiccant Vers.) (Bendix 109994)..... <b>BA5374 +</b> <b>Coolant</b> (Nalcool NF2088)..... <b>BW5200</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Trans.</b> (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b>	<b>WHLB w/Cat 3176 (10.3L) Eng.</b> <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99 +</b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> <b>Fuel/Water Separator Spin-on</b> (2568753)..... <b>BF1259</b> <b>P. Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (1R0712)..... <b>BF614 +</b> <b>Fuel Spin-on</b> (1R0749)..... <b>BF7587 +</b> <b>Air Dryer</b> (Coalescer Vers.) (Wabco R950068)..... <b>BA5379 +</b> <b>Air Dryer</b> (Desiccant Vers.) (Bendix 109994)..... <b>BA5374 +</b>
<b>WHL w/Cummins M11 (10.8L) Eng. (12/1995-on)</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> (3329289)..... <b>BF1259</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Trans.</b> (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b>	<b>WHL w/Detroit Diesel Series 60 Eng. (To 1993)</b> <b>F-F Lube Spin-on</b> (25010495)..... <b>[2] B95 +</b> <b>B-P Lube</b> (23530413)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (Davco 301SD19B)..... <b>PF7680</b> <b>Fuel/Water Separator Ele.</b> (Davco 382114)..... <b>PF7748</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (23512317)..... <b>BF5813 +</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (23512317).. <b>BF5813-O +</b> <b>Opt. Fuel/Water Separator Spin-on</b> (23516189)..... <b>BF5812</b> <b>Opt. Fuel/Water Separator Spin-on</b> (Alliance ABPN122R50407)..... <b>BF1283-SP +</b> <b>P. Fuel</b> (25014274)..... <b>BF5800 +</b> <b>S. Fuel</b> (23518482)..... <b>BF5810</b> <b>Air Dryer</b> (Coalescer Vers.) (Wabco R950068)..... <b>BA5379 +</b> <b>Air Dryer</b> (Desiccant Vers.) (Bendix 109994)..... <b>BA5374 +</b> <b>Coolant</b> (Nalcool NF2088)..... <b>BW5200</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Trans.</b> (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b>	<b>WHLB w/Cat 3406 (14.6L) Eng.</b> <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99 +</b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> <b>Fuel/Water Separator Spin-on</b> (2568753)..... <b>BF1259</b> <b>P. Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (1R0712)..... <b>BF614 +</b> <b>Fuel Spin-on</b> (1R0749)..... <b>BF7587 +</b> <b>Air Dryer</b> (Coalescer Vers.) (Wabco R950068)..... <b>BA5379 +</b> <b>Air Dryer</b> (Desiccant Vers.) (Bendix 109994)..... <b>BA5374 +</b>
<b>WHL w/Cummins N14 (14.0L) Eng.</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103 +</b> <b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196 +</b> <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Fuel/Water Separator</b> (3308638). <b>BF1212 +</b> <b>Fuel</b> (154789)..... <b>BF957-D +</b> <b>Air Dryer</b> (Coalescer Vers.) (Wabco R950068)..... <b>BA5379 +</b>	<b>WHL w/Detroit Diesel Series 60 Eng. (To 1993)</b> <b>F-F Lube Spin-on</b> (25010495)..... <b>[2] B95 +</b> <b>B-P Lube</b> (23530413)..... <b>B7577</b> <b>Fuel/Water Separator Ele.</b> (Davco 301SD19B)..... <b>PF7680</b> <b>Fuel/Water Separator Ele.</b> (Davco 382114)..... <b>PF7748</b> <b>Fuel/Water Separator Spin-on</b> (w/Drain) (23512317)..... <b>BF5813 +</b> <b>Fuel/Water Separator Spin-on</b> (Open End for Bowl) (23512317).. <b>BF5813-O +</b> <b>Opt. Fuel/Water Separator Spin-on</b> (23516189)..... <b>BF5812</b> <b>Opt. Fuel/Water Separator Spin-on</b> (Alliance ABPN122R50407)..... <b>BF1283-SP +</b> <b>P. Fuel</b> (25014274)..... <b>BF5800 +</b> <b>S. Fuel</b> (23518482)..... <b>BF5810</b> <b>Air Dryer</b> (Coalescer Vers.) (Wabco R950068)..... <b>BA5379 +</b> <b>Air Dryer</b> (Desiccant Vers.) (Bendix 109994)..... <b>BA5374 +</b> <b>Coolant</b> (Nalcool NF2088)..... <b>BW5200</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b> <b>Trans.</b> (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b>	<b>WHLB w/Cat 3406 (14.6L) Eng.</b> <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99 +</b> <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> <b>Fuel/Water Separator Spin-on</b> (2568753)..... <b>BF1259</b> <b>P. Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (1R0712)..... <b>BF614 +</b> <b>Fuel Spin-on</b> (1R0749)..... <b>BF7587 +</b> <b>Air Dryer</b> (Coalescer Vers.) (Wabco R950068)..... <b>BA5379 +</b> <b>Air Dryer</b> (Desiccant Vers.) (Bendix 109994)..... <b>BA5374 +</b>

+ See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

WHITE/GMC Trucks (cont'd)	WHITE/GMC Trucks (cont'd)	WHITE/GMC Trucks (cont'd)
WHLB w/Cat 3406 (14.6L) Eng. (Cont'd) Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2+</b>	WHLB w/Cummins N14 (14.0L) Eng. (Cont'd) Coolant (w/23 Units BTA+) (4058965)..... <b>BW5076</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2+</b> Trans. (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b>	WHLB w/Detroit Diesel Series 60 (11.1L) or (12.7L) Eng. (To 1993) (Cont'd) Opt. Trans. (Fuller 17237)..... <b>B2+</b> Trans. (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b>
WHLB w/Cummins L10 (10.0L) Eng. Dual-Flow Lube (3318853)..... <b>BD103+</b> F-F Lube (Fleetguard LF670SC).. <b>B196+</b> B-P Lube (3304232)..... <b>B7577</b> Fuel/Water Separator (3308638). <b>BF1212+</b> Fuel (154789)..... <b>BF957-D+</b> Coolant (w/4 Units BTA+) (3315116)..... <b>BW5071</b> Coolant (w/12 Units BTA+) (3315114)..... <b>BW5074</b> Coolant (w/15 Units BTA+) (3318318)..... <b>BW5075</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2+</b> Trans. (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b>	WHLB w/Detroit Diesel Series 60 (11.1L) or (12.7L) Eng. (1993-on) F-F Lube Spin-on (23518480).... <b>[2] B495</b> Fuel/Water Separator Ele. (Davco 301SD19B)..... <b>PF7680</b> Fuel/Water Separator Ele. (Davco 382114)..... <b>PF7748</b> Fuel/Water Separator Spin-on (w/Drain) (23512317)..... <b>BF5813+</b> Fuel/Water Separator Spin-on (Open End for Bowl) (23512317).. <b>BF5813-O+</b> Opt. Fuel/Water Separator Spin-on (23516189)..... <b>BF5812</b> Opt. Fuel/Water Separator Spin-on (Alliance ABPN122R50407)..... <b>BF1283-SP+</b> P. Fuel (25014274)..... <b>BF5800+</b> S. Fuel (23518482)..... <b>BF5810</b> Air Dryer (Coalescer Vers.) (Wabco R950068)..... <b>BA5379+</b> Air Dryer (Desiccant Vers.) (Bendix 109994)..... <b>BA5374+</b> Coolant (Nalcool NF2088)..... <b>BW5200</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2+</b> Trans. (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b>	WHM w/Cat 3406 (14.6L) Eng. F-F Lube (Std. Version) (1R0716)..... <b>B99+</b> F-F Lube (High Efficiency Vers.) (1R1808)..... <b>B7299+</b> Fuel/Water Separator Spin-on (2568753)..... <b>BF1259</b> P. Fuel Ele. (9M2342)..... <b>[2] PF935</b> Fuel Spin-on (1R0712)..... <b>BF614+</b> Fuel Spin-on (1R0749)..... <b>BF7587+</b> Air Dryer (Coalescer Vers.) (Wabco R950068)..... <b>BA5379+</b> Air Dryer (Desiccant Vers.) (Bendix 109994)..... <b>BA5374+</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2+</b>
WHLB w/Cummins M11 (10.8L) Eng. (To 12/1995) Dual-Flow Lube (3318853)..... <b>BD103+</b> Fuel/Water Separator Ele. (Fleetguard FS1029W)..... <b>PF7680</b> Fuel/Water Separator Spin-on (3308638)..... <b>BF1212+</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2+</b> Trans. (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b>	WHLB w/Detroit Diesel Series 60 (11.1L) or (12.7L) Eng. (To 1993) F-F Lube Spin-on (25010495).... <b>[2] B95+</b> B-P Lube (To 1993) (23530413).. <b>B7577</b> Fuel/Water Separator Ele. (Davco 301SD19B)..... <b>PF7680</b> Fuel/Water Separator Ele. (Davco 382114)..... <b>PF7748</b> Fuel/Water Separator Spin-on (w/Drain) (23512317)..... <b>BF5813+</b> Fuel/Water Separator Spin-on (Open End for Bowl) (23512317).. <b>BF5813-O+</b> Opt. Fuel/Water Separator Spin-on (23516189)..... <b>BF5812</b> Opt. Fuel/Water Separator Spin-on (Alliance ABPN122R50407)..... <b>BF1283-SP+</b> P. Fuel (25014274)..... <b>BF5800+</b> S. Fuel (23518482)..... <b>BF5810</b> Air Dryer (Coalescer Vers.) (Wabco R950068)..... <b>BA5379+</b> Air Dryer (Desiccant Vers.) (Bendix 109994)..... <b>BA5374+</b> Coolant (Nalcool NF2088)..... <b>BW5200</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2+</b> Trans. (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b>	WHM w/Cummins N14 (14.0L) Eng. Dual-Flow Lube (3318853)..... <b>BD103+</b> F-F Lube (Fleetguard LF670SC).. <b>B196+</b> B-P Lube (3304232)..... <b>B7577</b> Fuel/Water Separator (3308638). <b>BF1212+</b> Fuel (154789)..... <b>BF957-D+</b> Radial Seal O. Air (Standard) (V1117576)..... <b>RS3518</b> Radial Seal XP O. Air (Upgrade) (V1117576)..... <b>RS3518XP</b> Radial Seal I. Air..... <b>RS3519</b> Air Dryer (Coalescer Vers.) (Wabco R950068)..... <b>BA5379+</b> Air Dryer (Desiccant Vers.) (Bendix 109994)..... <b>BA5374+</b> Coolant (w/4 Units BTA+) (3315116)..... <b>BW5071</b> Coolant (w/23 Units BTA+) (4058965)..... <b>BW5076</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2+</b> Trans. (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b>
WHLB w/Cummins N14 (14.0L) Eng. Dual-Flow Lube (3318853)..... <b>BD103+</b> F-F Lube (Fleetguard LF670SC).. <b>B196+</b> B-P Lube (3304232)..... <b>B7577</b> Fuel/Water Separator (3308638). <b>BF1212+</b> Fuel (154789)..... <b>BF957-D+</b> Radial Seal O. Air (Standard) (V1117576)..... <b>RS3518</b> Radial Seal XP O. Air (Upgrade) (V1117576)..... <b>RS3518XP</b> Radial Seal I. Air..... <b>RS3519</b> Air Dryer (Coalescer Vers.) (Wabco R950068)..... <b>BA5379+</b> Air Dryer (Desiccant Vers.) (Bendix 109994)..... <b>BA5374+</b> Coolant (w/4 Units BTA+) (3315116)..... <b>BW5071</b>	WHLB w/Detroit Diesel Series 60 (11.1L) or (12.7L) Eng. (To 1993) F-F Lube Spin-on (25010495).... <b>[2] B95+</b> B-P Lube (To 1993) (23530413).. <b>B7577</b> Fuel/Water Separator Ele. (Davco 301SD19B)..... <b>PF7680</b> Fuel/Water Separator Ele. (Davco 382114)..... <b>PF7748</b> Fuel/Water Separator Spin-on (w/Drain) (23512317)..... <b>BF5813+</b> Fuel/Water Separator Spin-on (Open End for Bowl) (23512317).. <b>BF5813-O+</b> Opt. Fuel/Water Separator Spin-on (23516189)..... <b>BF5812</b> Opt. Fuel/Water Separator Spin-on (Alliance ABPN122R50407)..... <b>BF1283-SP+</b> P. Fuel (25014274)..... <b>BF5800+</b> S. Fuel (23518482)..... <b>BF5810</b> Air Dryer (Coalescer Vers.) (Wabco R950068)..... <b>BA5379+</b> Air Dryer (Desiccant Vers.) (Bendix 109994)..... <b>BA5374+</b> Coolant (Nalcool NF2088)..... <b>BW5200</b> Trans. (Fuller 4304827)..... <b>BT223</b>	WHM w/Detroit Diesel 6V-92N (9.0L) Eng. F-F Lube (23530407)..... <b>B95+</b> F-F Lube (23530408)..... <b>B95-MPG+</b> P. Fuel (23530706)..... <b>BF5800+</b> S. Fuel (23530707)..... <b>BF5810</b> S. Fuel (23530645)..... <b>BF5815</b>
	WHM w/Detroit Diesel Series 60 (12.7L) Eng. F-F Lube Spin-on (25010495).... <b>[2] B95+</b> B-P Lube (23530413)..... <b>B7577</b> Fuel/Water Separator Ele. (Davco 301SD19B)..... <b>PF7680</b> Fuel/Water Separator Ele. (Davco 382114)..... <b>PF7748</b>	WHM w/Detroit Diesel Series 60 (12.7L) Eng. F-F Lube Spin-on (25010495).... <b>[2] B95+</b> B-P Lube (23530413)..... <b>B7577</b> Fuel/Water Separator Ele. (Davco 301SD19B)..... <b>PF7680</b> Fuel/Water Separator Ele. (Davco 382114)..... <b>PF7748</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>WHITE/GMC Trucks (cont'd)</b>	<b>WHITE/GMC Trucks (cont'd)</b>	<b>WHITE/GMC Trucks (cont'd)</b>
WHM w/Detroit Diesel Series 60 (12.7L) Eng. (Cont'd)	WHR w/Cummins L10 (10.0L) Eng.	WHR w/Cummins N14 (14.0L) Eng. (Cont'd)
Fuel/Water Separator Spin-on (w/Drain) (23512317).....	Dual-Flow Lube (3318853).....	Trans. (Auxiliary) (Allison 29510918).....
BF5813 +	BD103 +	PT8330-MPG
Fuel/Water Separator Spin-on (Open End for Bowl) (23512317)..	F-F Lube (Fleetguard LF670SC)..	
BF5813-O +	B196 +	
Opt. Fuel/Water Separator Spin-on (23516189).....	B-P Lube (3304232).....	
BF5812	B7577	
Opt. Fuel/Water Separator Spin-on (Alliance ABPN122R50407).....	Fuel/Water Separator (3308638).	
BF1283-SP +	BF1212 +	
P. Fuel (25014274).....	Fuel (154789).....	
BF5800 +	BF957-D +	
S. Fuel (23518482).....	Air Dryer (Coalescer Vers.) (Wabco R950068).....	
BF5810	BA5379 +	
Radial Seal I. Air.....	Air Dryer (Desiccant Vers.) (Bendix 109994).....	
RS3519	BA5374 +	
Air Dryer (Coalescer Vers.) (Wabco R950068).....	Coolant (w/4 Units BTA+) (3315116).....	
BA5379 +	BW5071	
Coolant (Nalcool NF2088).....	Coolant (w/12 Units BTA+) (3315114).....	
BW5200	BW5074	
Trans. (Fuller 4304827).....	Coolant (w/15 Units BTA+) (3318318).....	
BT223	BW5075	
Opt. Trans. (Fuller 17237).....	Trans. (Fuller 4304827).....	
B2 +	BT223	
Trans. (Auxiliary) (Allison 29510918).....	Opt. Trans. (Fuller 17237).....	
PT8330-MPG	B2 +	
	Trans. (Auxiliary) (Allison 29510918).....	
	PT8330-MPG	
WHR w/Cat 3176 (10.3L) Eng.	WHR w/Cummins M11 (10.8L) Eng. (To 12/1995)	WHR w/Detroit Diesel Series 60 (11.1L) or (12.7L) Eng. (To 1993)
F-F Lube (Std. Version) (1R0716).....	Dual-Flow Lube (3318853).....	F-F Lube Spin-on (25010495).....
B99 +	BD103 +	[2] B95 +
F-F Lube (High Efficiency Vers.) (1R1808).....	Fuel/Water Separator Ele. (Fleetguard FS1029W).....	B-P Lube (23530413).....
B7299 +	PF7680	B7577
F-F Lube (8N9586).....	Fuel/Water Separator Spin-on (3308638).....	Fuel/Water Separator Ele. (Davco 301SD19B).....
BT230 +	BF1212 +	PF7680
F-F Lube (9N6007).....	Trans. (Fuller 4304827).....	Fuel/Water Separator Ele. (Davco 382114).....
B75	BT223	PF7748
Opt. B-P Lube (1W8845).....	Opt. Trans. (Fuller 17237).....	Fuel/Water Separator Spin-on (w/Drain) (23512317).....
B7577	B2 +	BF5813 +
Fuel/Water Separator Ele. (8N0205).....	Trans. (Auxiliary) (Allison 29510918).....	BF5813-O +
PF316	PT8330-MPG	Opt. Fuel/Water Separator Spin-on (Alliance ABPN122R50407).....
		BF1283-SP +
Fuel/Water Separator Spin-on (2568753).....	WHR w/Cummins M11 (10.8L) Eng. (12/1995-on)	P. Fuel (25014274).....
BF1259	Dual-Flow Lube (3318853).....	BF5800 +
P. Fuel Ele. (9M2342).....	BD103 +	S. Fuel (23518482).....
[2] PF935	Fuel/Water Separator Ele. (Fleetguard FS1029W).....	BF5810
P. Fuel Spin-on (1R1740).....	PF7680	Air Dryer (Coalescer Vers.) (Wabco R950068).....
BF970 +	Fuel/Water Separator Spin-on (3329289).....	BA5379 +
BF614 +	BF1259	Air Dryer (Desiccant Vers.) (Bendix 109994).....
Fuel Spin-on (High Efficiency) (1R0750).....	Trans. (Fuller 4304827).....	BA5374 +
BF7633 +	BT223	BW5200
Trans. (Fuller 4304827).....	Opt. Trans. (Fuller 17237).....	BT223
BT223	B2 +	Opt. Trans. (Fuller 17237).....
Opt. Trans. (Fuller 17237).....	Trans. (Auxiliary) (Allison 29510918).....	B2 +
B2 +	PT8330-MPG	Trans. (Auxiliary) (Allison 29510918).....
		PT8330-MPG
WHR w/Cat 3406 (14.6L) Eng.	WHR w/Cummins N14 (14.0L) Eng.	WHR w/Detroit Diesel Series 60 (11.1L) or (12.7L) Eng. (1993-on)
F-F Lube (Std. Version) (1R0716).....	Dual-Flow Lube (3318853).....	F-F Lube Spin-on (23518480).....
B99 +	BD103 +	[2] B495
F-F Lube (High Efficiency Vers.) (1R1808).....	F-F Lube (Fleetguard LF670SC)..	Fuel/Water Separator Ele. (Davco 301SD19B).....
B7299 +	B196 +	PF7680
Fuel/Water Separator Spin-on (2568753).....	B-P Lube (3304232).....	Fuel/Water Separator Ele. (Davco 382114).....
BF1259	B7577	PF7748
P. Fuel Ele. (9M2342).....	Fuel/Water Separator (3308638).	Fuel/Water Separator Spin-on (w/Drain) (23512317).....
[2] PF935	BF1212 +	BF5813 +
Fuel Spin-on (1R0712).....	Fuel (154789).....	BF5813-O +
BF614 +	BF957-D +	Opt. Fuel/Water Separator Spin-on (Open End for Bowl) (23512317)..
BF7587 +	Air Dryer (Coalescer Vers.) (Wabco R950068).....	BF5812
Air Dryer (Coalescer Vers.) (Wabco R950068).....	BA5379 +	Opt. Fuel/Water Separator Spin-on (Alliance ABPN122R50407).....
BA5379 +	Air Dryer (Desiccant Vers.) (Bendix 109994).....	BF1283-SP +
Air Dryer (Desiccant Vers.) (Bendix 109994).....	BA5374 +	BF5800 +
BA5374 +	Coolant (w/4 Units BTA+) (3315116).....	BF5810
BT223	BW5071	Air Dryer (Coalescer Vers.) (Wabco R950068).....
Opt. Trans. (Fuller 17237).....	BW5076	BA5379 +
B2 +	BT223	Air Dryer (Desiccant Vers.) (Bendix 109994).....
	Opt. Trans. (Fuller 17237).....	BA5374 +
	B2 +	BW5200
		BT223
		Opt. Trans. (Fuller 17237).....
		B2 +
		Trans. (Auxiliary) (Allison 29510918).....
		PT8330-MPG

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

WHITE/GMC Trucks (cont'd)	WHITE/GMC Trucks (cont'd)	WHITE/GMC Trucks (cont'd)
WHS w/Cat 3176 (10.3L) Eng. F-F Lube (Std. Version) (1R0716)..... <b>B99 +</b> F-F Lube (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> F-F Lube (8N9586)..... <b>BT230 +</b> F-F Lube (9N6007)..... <b>B75</b> Opt. B-P Lube (1W8845)..... <b>B7577</b> Fuel/Water Separator Ele. (8N0205)..... <b>PF316</b> Fuel/Water Separator Spin-on (2568753)..... <b>BF1259</b> P. Fuel Ele. (9M2342)..... <b>[2] PF935</b> P. Fuel Spin-on (1R1740)..... <b>BF970 +</b> Fuel Spin-on (1R0712)..... <b>BF614 +</b> Fuel Spin-on (High Efficiency) (1R0750)..... <b>BF7633 +</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	WHS w/Cummins L10 (10.0L) Eng. Dual-Flow Lube (3318853)..... <b>BD103 +</b> F-F Lube (Fleetguard LF670SC).. <b>B196 +</b> B-P Lube (3304232)..... <b>B7577</b> Fuel/Water Separator (3308638). <b>BF1212 +</b> Fuel (154789)..... <b>BF957-D +</b> Coolant (w/4 Units BTA+) (3315116)..... <b>BW5071</b> Coolant (w/12 Units BTA+) (3315114)..... <b>BW5074</b> Coolant (w/15 Units BTA+) (3318318)..... <b>BW5075</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Trans. (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b>	WHS w/Detroit Diesel 8V-92 (12.1L) Eng. Lube Ele. (5573013)..... <b>P20-HD</b> Lube Spin-on (23530407)..... <b>B95 +</b> Lube Spin-on (23530408)..... <b>B95-MPG +</b> P. Fuel Ele. (9717391)..... <b>PF845</b> P. Fuel Spin-on (23530706)..... <b>BF5800 +</b> S. Fuel Ele. (5574508)..... <b>PF902</b> S. Fuel Spin-on (23530707)..... <b>BF5810</b> S. Fuel Spin-on (23530645)..... <b>BF5815</b>
WHS w/Cat 3306 (10.5L) Eng. Lube Ele. (5S0484)..... <b>PT670</b> Lube Spin-on (1R0716)..... <b>B99 +</b> Lube Spin-on (Standard Vers.) (1R0739)..... <b>B76 +</b> Lube Spin-on (Severe Service) (1R0739)..... <b>B76-SS +</b> Box-Style Glass Fuel/Water Separator (6N7617)..... <b>BF912</b> Fuel/Water Separator Ele. (8N0205)..... <b>PF316</b> Fuel/Water Separator Spin-on (2568753)..... <b>BF1259</b> P. Fuel Ele. (9M2342)..... <b>PF935</b> P. Fuel Spin-on (1R1740)..... <b>BF970 +</b> S. Fuel Spin-on (1R0750)..... <b>BF7633 +</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Trans. (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b>	WHS w/Cummins N14 (14.0L) Eng. Dual-Flow Lube (3318853)..... <b>BD103 +</b> F-F Lube (Fleetguard LF670SC).. <b>B196 +</b> B-P Lube (3304232)..... <b>B7577</b> Fuel/Water Separator (3308638). <b>BF1212 +</b> Fuel (154789)..... <b>BF957-D +</b> Air Dryer (Coalescer Vers.) (Wabco R950068)..... <b>BA5379 +</b> Air Dryer (Desiccant Vers.) (Bendix 109994)..... <b>BA5374 +</b> Coolant (w/4 Units BTA+) (3315116)..... <b>BW5071</b> Coolant (w/23 Units BTA+) (4058965)..... <b>BW5076</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Trans. (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b>	WHS w/Detroit Diesel Series 60 (11.1L) or (12.7L) Eng. F-F Lube Spin-on (25010495).... <b>[2] B95 +</b> B-P Lube (23530413)..... <b>B7577</b> Fuel/Water Separator Ele. (Davco 301SD19B)..... <b>PF7680</b> Fuel/Water Separator Ele. (Davco 382114)..... <b>PF7748</b> Fuel/Water Separator Spin-on (w/Drain) (23512317)..... <b>BF5813 +</b> Fuel/Water Separator Spin-on (Open End for Bowl) (23512317).. <b>BF5813-O +</b> Opt. Fuel/Water Separator Spin-on (23516189)..... <b>BF5812</b> Opt. Fuel/Water Separator Spin-on (Alliance ABPN122R50407)..... <b>BF1283-SP +</b> P. Fuel (25014274)..... <b>BF5800 +</b> S. Fuel (23518482)..... <b>BF5810</b> Coolant (Nalcool NF2088)..... <b>BW5200</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Trans. (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b>
WHS w/Cat 3406 (14.6L) Eng. F-F Lube (Std. Version) (1R0716)..... <b>B99 +</b> F-F Lube (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> Fuel/Water Separator Spin-on (2568753)..... <b>BF1259</b> P. Fuel Ele. (9M2342)..... <b>[2] PF935</b> Fuel Spin-on (1R0712)..... <b>BF614 +</b> Fuel Spin-on (1R0749)..... <b>BF7587 +</b> Air Dryer (Coalescer Vers.) (Wabco R950068)..... <b>BA5379 +</b> Air Dryer (Desiccant Vers.) (Bendix 109994)..... <b>BA5374 +</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	WHS w/Detroit Diesel 6-71 (7.0L) Eng. F-F Lube (23530407)..... <b>B95 +</b> F-F Lube (23530408)..... <b>B95-MPG +</b> P. Fuel (23530706)..... <b>BF5800 +</b> S. Fuel (23530707)..... <b>BF5810</b> S. Fuel (23530645)..... <b>BF5815</b>	WIA w/Cat 3176 (10.3L) Eng. F-F Lube (Std. Version) (1R0716)..... <b>B99 +</b> F-F Lube (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> F-F Lube (8N9586)..... <b>BT230 +</b> F-F Lube (9N6007)..... <b>B75</b> Opt. B-P Lube (1W8845)..... <b>B7577</b> Fuel/Water Separator Ele. (8N0205)..... <b>PF316</b> Fuel/Water Separator Spin-on (2568753)..... <b>BF1259</b> P. Fuel Ele. (9M2342)..... <b>[2] PF935</b> P. Fuel Spin-on (1R1740)..... <b>BF970 +</b> Fuel Spin-on (1R0712)..... <b>BF614 +</b> Fuel Spin-on (High Efficiency) (1R0750)..... <b>BF7633 +</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b>
	WHS w/Detroit Diesel 6V-92N (9.0L) Eng. F-F Lube (23530407)..... <b>B95 +</b> F-F Lube (23530408)..... <b>B95-MPG +</b> P. Fuel (23530706)..... <b>BF5800 +</b> S. Fuel (23530707)..... <b>BF5810</b> S. Fuel (23530645)..... <b>BF5815</b>	WIA w/Cat 3208 (10.4L) Eng. F-F Lube (9L9200)..... <b>[2] BT364</b> F-F Lube (9N5570)..... <b>[2] BT230</b> F-F Lube (9N6007)..... <b>[2] B75</b> Box-Style Fuel/Water Separator. <b>BF912</b> Fuel Ele. (9M2341)..... <b>PF935</b> Fuel Spin-on..... <b>BF970 +</b>

+ See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

**Trucks & Buses Applications** **BALDWIN FILTERS**

<b>WHITE/GMC Trucks (cont'd)</b>	<b>WHITE/GMC Trucks (cont'd)</b>	<b>WHITE/GMC Trucks (cont'd)</b>
WIA w/Cat 3208 (10.4L) Eng. (Cont'd) Fuel Spin-on (High Efficiency) (1R0750)..... <b>BF7633 +</b>	WIA w/Cummins N14 (14.0L) Eng. (Cont'd) Coolant (w/23 Units BTA+) (4058965)..... <b>BW5076</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Trans. (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b>	WIL w/Cummins N14 (14.0L) Eng. (Cont'd) Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Trans. (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b>
WIA w/Cat 3306 (10.5L) Eng. Lube Ele. (5S0484)..... <b>PT670</b> Lube Spin-on (1R0716)..... <b>B99 +</b> Lube Spin-on (Standard Vers.) (1R0739)..... <b>B76 +</b> Lube Spin-on (Severe Service) (1R0739)..... <b>B76-SS +</b> Box-Style Glass Fuel/Water Separator (6N7617)..... <b>BF912</b> Fuel/Water Separator Ele. (8N0205)..... <b>PF316</b> Fuel/Water Separator Spin-on (2568753)..... <b>BF1259</b> P. Fuel Ele. (9M2342)..... <b>PF935</b> P. Fuel Spin-on (1R1740)..... <b>BF970 +</b> S. Fuel Spin-on (1R0750)..... <b>BF7633 +</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Trans. (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b>	WIA w/Detroit Diesel Series 60 (11.1L), (12.7L) Eng. Lube..... <b>[2] B495</b> P. Fuel..... <b>BF5800 +</b> S. Fuel..... <b>BF5810</b>	WIL w/Detroit Diesel 8V-71 (9.3L) Eng. F-F Lube (23530407)..... <b>B95 +</b> F-F Lube (23530408)..... <b>B95-MPG +</b> B-P Lube Ele. (5570092)..... <b>P52</b> P. Fuel Sock (5192854)..... <b>F916-C</b> P. Fuel Sock (5574980)..... <b>F844-A</b> P. Fuel Ele. (9717391)..... <b>PF845</b> P. Fuel Spin-on (23530706)..... <b>BF5800 +</b> S. Fuel Ele. (5574508)..... <b>PF902</b> S. Fuel Ele. (6437284)..... <b>BF846</b> S. Fuel Spin-on (23530707)..... <b>BF5810</b> S. Fuel Spin-on (23530645)..... <b>BF5815</b>
WIA w/Cat 3406 (14.6L) Eng. F-F Lube (1R0716)..... <b>B99 +</b> Fuel Ele. (9M2342)..... <b>[2] PF935</b> Fuel Spin-on (4N5823)..... <b>BF614 +</b>	WIA w/Volvo TD122 (12.0L) Eng. F-F Lube (21707134)..... <b>B76 +</b> Severe Service F-F Lube (21707134)..... <b>B76-SS +</b> P. Fuel (4669875)..... <b>BF988 +</b> S. Fuel (991203640)..... <b>BF788</b>	WIL w/Detroit Diesel 8V-92 (12.1L) Eng. Lube Ele. (5573013)..... <b>P20-HD</b> Lube Spin-on (23530407)..... <b>B95 +</b> Lube Spin-on (23530408)..... <b>B95-MPG +</b> P. Fuel Ele. (9717391)..... <b>PF845</b> P. Fuel Spin-on (23530706)..... <b>BF5800 +</b> S. Fuel Ele. (5574508)..... <b>PF902</b> S. Fuel Spin-on (23530707)..... <b>BF5810</b> S. Fuel Spin-on (23530645)..... <b>BF5815</b>
WIA w/Cummins L10 (10.0L) Eng. Dual-Flow Lube (3318853)..... <b>BD103 +</b> F-F Lube (Fleetguard LF670SC).. <b>B196 +</b> B-P Lube (3304232)..... <b>B7577</b> Fuel/Water Separator (3308638).. <b>BF1212 +</b> Fuel (154789)..... <b>BF957-D +</b> Coolant (w/4 Units BTA+) (3315116)..... <b>BW5071</b> Coolant (w/12 Units BTA+) (3315114)..... <b>BW5074</b> Coolant (w/15 Units BTA+) (3318318)..... <b>BW5075</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Trans. (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b>	WIA w/Volvo D12 (12.1L) Eng. F-F Lube (4666343)..... <b>[2] B76 +</b> B-P Lube (477556)..... <b>B7685</b> Severe Service F-F Lube (4666343)..... <b>[2] B76-SS +</b> Fuel/Water Separator (Alliance ABPN122R50551)..... <b>BF46016-O</b> Fuel (466987-5)..... <b>[2] BF988 +</b> Air (22005-5039)..... <b>LL2685</b>	WIL w/Detroit Diesel Series 60 (11.1L) or (12.7L) Eng. F-F Lube Spin-on (25010495)..... <b>[2] B95 +</b> B-P Lube (23530413)..... <b>B7577</b> Fuel/Water Separator Ele. (Davco 301SD19B)..... <b>PF7680</b> Fuel/Water Separator Ele. (Davco 382114)..... <b>PF7748</b> Fuel/Water Separator Spin-on (w/Drain) (23512317)..... <b>BF5813 +</b> Fuel/Water Separator Spin-on (Open End for Bowl) (23512317).. <b>BF5813-O +</b> Opt. Fuel/Water Separator Spin-on (23516189)..... <b>BF5812</b> Opt. Fuel/Water Separator Spin-on (Alliance ABPN122R50407)..... <b>BF1283-SP +</b> P. Fuel (25014274)..... <b>BF5800 +</b> S. Fuel (23518482)..... <b>BF5810</b> Air Dryer (Coalescer Vers.) (Wabco R950068)..... <b>BA5379 +</b> Air Dryer (Desiccant Vers.) (Bendix 109994)..... <b>BA5374 +</b> Coolant (Nalcool NF2088)..... <b>BW5200</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Trans. (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b>
WIA w/Cummins M11 (10.8L) Eng. (To 12/1995) Dual-Flow Lube (3318853)..... <b>BD103 +</b> Fuel/Water Separator (3308638).. <b>BF1212 +</b>	WIL w/Cat 3406 (14.6L) Eng. F-F Lube (Std. Version) (1R0716)..... <b>B99 +</b> F-F Lube (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> Fuel/Water Separator Spin-on (2568753)..... <b>BF1259</b> P. Fuel Ele. (9M2342)..... <b>[2] PF935</b> Fuel Spin-on (1R0712)..... <b>BF614 +</b> Fuel Spin-on (1R0749)..... <b>BF7587 +</b> Air Dryer (Coalescer Vers.) (Wabco R950068)..... <b>BA5379 +</b> Air Dryer (Desiccant Vers.) (Bendix 109994)..... <b>BA5374 +</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	WIL w/Detroit Diesel Series 60 (11.1L) or (12.7L) Eng. F-F Lube Spin-on (25010495)..... <b>[2] B95 +</b> B-P Lube (23530413)..... <b>B7577</b> Fuel/Water Separator Ele. (Davco 301SD19B)..... <b>PF7680</b> Fuel/Water Separator Ele. (Davco 382114)..... <b>PF7748</b> Fuel/Water Separator Spin-on (w/Drain) (23512317)..... <b>BF5813 +</b> Fuel/Water Separator Spin-on (Open End for Bowl) (23512317).. <b>BF5813-O +</b> Opt. Fuel/Water Separator Spin-on (23516189)..... <b>BF5812</b> Opt. Fuel/Water Separator Spin-on (Alliance ABPN122R50407)..... <b>BF1283-SP +</b> P. Fuel (25014274)..... <b>BF5800 +</b> S. Fuel (23518482)..... <b>BF5810</b> Air Dryer (Coalescer Vers.) (Wabco R950068)..... <b>BA5379 +</b> Air Dryer (Desiccant Vers.) (Bendix 109994)..... <b>BA5374 +</b> Coolant (Nalcool NF2088)..... <b>BW5200</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Trans. (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b>
WIA w/Cummins M11 (10.8L) Eng. (12/1995-on) Dual-Flow Lube (3318853)..... <b>BD103 +</b> Fuel/Water Separator (3329289).. <b>BF1259</b>	WIA w/Volvo TD122 (12.0L) Eng. Dual-Flow Lube (3318853)..... <b>BD103 +</b> F-F Lube (Fleetguard LF670SC).. <b>B196 +</b> B-P Lube (3304232)..... <b>B7577</b> Fuel/Water Separator (3308638).. <b>BF1212 +</b> Fuel (154789)..... <b>BF957-D +</b> Air Dryer (Coalescer Vers.) (Wabco R950068)..... <b>BA5379 +</b> Air Dryer (Desiccant Vers.) (Bendix 109994)..... <b>BA5374 +</b> Coolant (w/4 Units BTA+) (3315116)..... <b>BW5071</b> Coolant (w/23 Units BTA+) (4058965)..... <b>BW5076</b> Trans. (Fuller 4304827)..... <b>BT223</b>	WIL w/Volvo TD122 (12.0L) Eng. F-F Lube (21707134)..... <b>B76 +</b> Severe Service F-F Lube (21707134)..... <b>B76-SS +</b> P. Fuel (4669875)..... <b>BF988 +</b>

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

WHITE/GMC Trucks (cont'd)	WHITE/GMC Trucks (cont'd)	WHITE/GMC Trucks (cont'd)
WIL w/Volvo TD122 (12.0L) Eng. (Cont'd) S. Fuel (991203640)..... <b>BF788</b>	WIM w/Cummins N14 (14.0L) Eng. (Cont'd) Fuel (154789)..... <b>BF957-D +</b>	WIM w/Detroit Diesel Series 60 (11.1L) Eng. (Cont'd) Opt. Fuel/Water Separator Spin-on (23516189)..... <b>BF5812</b>
WIM w/Cat 3306 (10.5L) Eng. Lube Ele. (5S0484)..... <b>PT670</b> Lube Spin-on (1R0716)..... <b>B99 +</b> Lube Spin-on (Standard Vers.) (1R0739)..... <b>B76 +</b> Lube Spin-on (Severe Service) (1R0739)..... <b>B76-SS +</b>	Air Dryer (Coalescer Vers.) (Wabco R950068)..... <b>BA5379 +</b> Air Dryer (Desiccant Vers.) (Bendix 109994)..... <b>BA5374 +</b> Coolant (w/4 Units BTA+) (3315116)..... <b>BW5071</b> Coolant (w/23 Units BTA+) (4058965)..... <b>BW5076</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Trans. (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b>	Opt. Fuel/Water Separator Spin-on (Alliance ABPN122R50407)..... <b>BF1283-SP +</b> P. Fuel (25014274)..... <b>BF5800 +</b> S. Fuel (23518482)..... <b>BF5810</b> Air Dryer (Coalescer Vers.) (Wabco R950068)..... <b>BA5379 +</b> Air Dryer (Desiccant Vers.) (Bendix 109994)..... <b>BA5374 +</b> Coolant (Nalcool NF2088)..... <b>BW5200</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Trans. (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b>
Box-Style Glass Fuel/Water Separator (6N7617)..... <b>BF912</b> Fuel/Water Separator Ele. (8N0205)..... <b>PF316</b> Fuel/Water Separator Spin-on (2568753)..... <b>BF1259</b> P. Fuel Ele. (9M2342)..... <b>PF935</b> P. Fuel Spin-on (1R1740)..... <b>BF970 +</b> S. Fuel Spin-on (1R0750)..... <b>BF7633 +</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Trans. (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b>	WIM w/Detroit Diesel 6-71 (7.0L) Eng. F-F Lube (23530407)..... <b>B95 +</b> F-F Lube (23530408)..... <b>B95-MPG +</b> P. Fuel (23530706)..... <b>BF5800 +</b> S. Fuel (23530707)..... <b>BF5810</b> S. Fuel (23530645)..... <b>BF5815</b>	WIM w/Detroit Diesel Series 60 (12.7L) Eng. (To 1993) F-F Lube Spin-on (25010495)..... <b>[2] B95 +</b> B-P Lube (23530413)..... <b>B7577</b> Fuel/Water Separator Ele. (Davco 301SD19B)..... <b>PF7680</b> Fuel/Water Separator Ele. (Davco 382114)..... <b>PF7748</b> Fuel/Water Separator Spin-on (w/Drain) (23512317)..... <b>BF5813 +</b> Fuel/Water Separator Spin-on (Open End for Bowl) (23512317)..... <b>BF5813-O +</b> Opt. Fuel/Water Separator Spin-on (23516189)..... <b>BF5812</b> Opt. Fuel/Water Separator Spin-on (Alliance ABPN122R50407)..... <b>BF1283-SP +</b> P. Fuel (25014274)..... <b>BF5800 +</b> S. Fuel (23518482)..... <b>BF5810</b> Air Dryer (Coalescer Vers.) (Wabco R950068)..... <b>BA5379 +</b> Air Dryer (Desiccant Vers.) (Bendix 109994)..... <b>BA5374 +</b> Coolant (Nalcool NF2088)..... <b>BW5200</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Trans. (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b>
WIM w/Cat 3406 (14.6L) Eng. F-F Lube (Std. Version) (1R0716)..... <b>B99 +</b> F-F Lube (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> Fuel/Water Separator Spin-on (2568753)..... <b>BF1259</b> P. Fuel Ele. (9M2342)..... <b>[2] PF935</b> Fuel Spin-on (1R0712)..... <b>BF614 +</b> Fuel Spin-on (1R0749)..... <b>BF7587 +</b> Air Dryer (Coalescer Vers.) (Wabco R950068)..... <b>BA5379 +</b> Air Dryer (Desiccant Vers.) (Bendix 109994)..... <b>BA5374 +</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	WIM w/Detroit Diesel 6V-92N (9.0L) Eng. F-F Lube (23530407)..... <b>B95 +</b> F-F Lube (23530408)..... <b>B95-MPG +</b> P. Fuel (23530706)..... <b>BF5800 +</b> S. Fuel (23530707)..... <b>BF5810</b> S. Fuel (23530645)..... <b>BF5815</b>	Fuel/Water Separator Spin-on (w/Drain) (23512317)..... <b>BF5813 +</b> Fuel/Water Separator Spin-on (Open End for Bowl) (23512317)..... <b>BF5813-O +</b> Opt. Fuel/Water Separator Spin-on (23516189)..... <b>BF5812</b> Opt. Fuel/Water Separator Spin-on (Alliance ABPN122R50407)..... <b>BF1283-SP +</b> P. Fuel (25014274)..... <b>BF5800 +</b> S. Fuel (23518482)..... <b>BF5810</b>
WIM w/Cummins L10 (10.0L) Eng. Dual-Flow Lube (3318853)..... <b>BD103 +</b> F-F Lube (Fleetguard LF670SC)..... <b>B196 +</b> B-P Lube (3304232)..... <b>B7577</b> Fuel/Water Separator (3308638)..... <b>BF1212 +</b> Fuel (154789)..... <b>BF957-D +</b> Coolant (w/4 Units BTA+) (3315116)..... <b>BW5071</b> Coolant (w/12 Units BTA+) (3315114)..... <b>BW5074</b> Coolant (w/15 Units BTA+) (3318318)..... <b>BW5075</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Trans. (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b>	WIM w/Detroit Diesel 8V-71 (9.3L) Eng. F-F Lube (23530407)..... <b>B95 +</b> F-F Lube (23530408)..... <b>B95-MPG +</b> B-P Lube Ele. (5570092)..... <b>P52</b> P. Fuel Sock (5192854)..... <b>F916-C</b> P. Fuel Sock (5574980)..... <b>F844-A</b> P. Fuel Ele. (9717391)..... <b>PF845</b> P. Fuel Spin-on (23530706)..... <b>BF5800 +</b> S. Fuel Ele. (5574508)..... <b>PF902</b> S. Fuel Ele. (6437284)..... <b>PF846</b> S. Fuel Spin-on (23530707)..... <b>BF5810</b> S. Fuel Spin-on (23530645)..... <b>BF5815</b>	Air Dryer (Coalescer Vers.) (Wabco R950068)..... <b>BA5379 +</b> Air Dryer (Desiccant Vers.) (Bendix 109994)..... <b>BA5374 +</b> Coolant (Nalcool NF2088)..... <b>BW5200</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Trans. (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b>
WIM w/Cummins N14 (14.0L) Eng. Dual-Flow Lube (3318853)..... <b>BD103 +</b> F-F Lube (Fleetguard LF670SC)..... <b>B196 +</b> B-P Lube (3304232)..... <b>B7577</b> Fuel/Water Separator (3308638)..... <b>BF1212 +</b>	WIM w/Detroit Diesel 8V-92 (12.1L) Eng. Lube Ele. (5573013)..... <b>P20-HD</b> Lube Spin-on (23530407)..... <b>B95 +</b> Lube Spin-on (23530408)..... <b>B95-MPG +</b> P. Fuel Ele. (9717391)..... <b>PF845</b> P. Fuel Spin-on (23530706)..... <b>BF5800 +</b> S. Fuel Ele. (5574508)..... <b>PF902</b> S. Fuel Spin-on (23530707)..... <b>BF5810</b> S. Fuel Spin-on (23530645)..... <b>BF5815</b>	WIM w/Detroit Diesel Series 60 (12.7L) Eng. (1993-on) F-F Lube Spin-on (23518480)..... <b>[2] B495</b> Fuel/Water Separator Ele. (Davco 301SD19B)..... <b>PF7680</b> Fuel/Water Separator Ele. (Davco 382114)..... <b>PF7748</b> Fuel/Water Separator Spin-on (w/Drain) (23512317)..... <b>BF5813 +</b> Fuel/Water Separator Spin-on (Open End for Bowl) (23512317)..... <b>BF5813-O +</b> Opt. Fuel/Water Separator Spin-on (23516189)..... <b>BF5812</b>
Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Trans. (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b>	WIM w/Detroit Diesel Series 60 (11.1L) Eng. F-F Lube Spin-on (25010495)..... <b>[2] B95 +</b> B-P Lube (23530413)..... <b>B7577</b> Fuel/Water Separator Ele. (Davco 301SD19B)..... <b>PF7680</b> Fuel/Water Separator Ele. (Davco 382114)..... <b>PF7748</b> Fuel/Water Separator Spin-on (w/Drain) (23512317)..... <b>BF5813 +</b> Fuel/Water Separator Spin-on (Open End for Bowl) (23512317)..... <b>BF5813-O +</b>	

+ See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

**Trucks & Buses Applications** **BALDWIN FILTERS**

<b>WHITE/GMC Trucks (cont'd)</b>	<b>WHITE/GMC Trucks (cont'd)</b>	<b>WHITE/GMC Trucks (cont'd)</b>
<b>WIM w/Detroit Diesel Series 60 (12.7L) Eng. (1993-on) (Cont'd)</b> <b>Opt. Fuel/Water Separator Spin-on</b> (Alliance) ABPN122R50407..... <b>BF1283-SP</b> + <b>P. Fuel</b> (25014274)..... <b>BF5800</b> + <b>S. Fuel</b> (23518482)..... <b>BF5810</b> <b>Air Dryer</b> (Coalescer Vers.) (Wabco R950068)..... <b>BA5379</b> + <b>Air Dryer</b> (Desiccant Vers.) (Bendix 109994)..... <b>BA5374</b> + <b>Coolant</b> (Nalcool NF2088)..... <b>BW5200</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2</b> + <b>Trans.</b> (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b>	<b>WIS w/Cummins L10 (10.0L) Eng. (Cont'd)</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2</b> + <b>Trans.</b> (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b> <b>WIS w/Cummins N14 (14.0L) Eng.</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103</b> + <b>F-F Lube</b> (Fleetguard LF670SC).. <b>B196</b> + <b>B-P Lube</b> (3304232)..... <b>B7577</b> <b>Fuel/Water Separator</b> (3308638). <b>BF1212</b> + <b>Fuel</b> (154789)..... <b>BF957-D</b> + <b>Air Dryer</b> (Coalescer Vers.) (Wabco R950068)..... <b>BA5379</b> + <b>Air Dryer</b> (Desiccant Vers.) (Bendix 109994)..... <b>BA5374</b> + <b>Coolant</b> (w/4 Units BTA+) (3315116)..... <b>BW5071</b> <b>Coolant</b> (w/23 Units BTA+) (4058965)..... <b>BW5076</b> <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2</b> + <b>Trans.</b> (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b> <b>WIS w/Detroit Diesel 6V-92N (9.0L) Eng.</b> <b>F-F Lube</b> (23530407)..... <b>B95</b> + <b>F-F Lube</b> (23530408)..... <b>B95-MPG</b> + <b>P. Fuel</b> (23530706)..... <b>BF5800</b> + <b>S. Fuel</b> (23530707)..... <b>BF5810</b> <b>S. Fuel</b> (23530645)..... <b>BF5815</b>	<b>WX w/Cat 3306 (10.5L) Eng.</b> <b>Lube Ele.</b> (5S0484)..... <b>PT670</b> <b>Lube Spin-on</b> (1R0716)..... <b>B99</b> + <b>Lube Spin-on</b> (Standard Vers.) (1R0739)..... <b>B76</b> + <b>Lube Spin-on</b> (Severe Service) (1R0739)..... <b>B76-SS</b> + <b>Box-Style Glass Fuel/Water Separator</b> (6N7617)..... <b>BF912</b> <b>Fuel/Water Separator Ele.</b> (8N0205)..... <b>PF316</b> <b>Fuel/Water Separator Spin-on</b> (2568753)..... <b>BF1259</b> <b>P. Fuel Ele.</b> (9M2342)..... <b>PF935</b> <b>P. Fuel Spin-on</b> (1R1740)..... <b>BF970</b> + <b>S. Fuel Spin-on</b> (1R0750)..... <b>BF7633</b> + <b>WX w/Cat 3406 (14.6L) Eng.</b> <b>F-F Lube</b> (Std. Version) (1R0716)..... <b>B99</b> + <b>F-F Lube</b> (High Efficiency Vers.) (1R1808)..... <b>B7299</b> + <b>Fuel/Water Separator Spin-on</b> (2568753)..... <b>BF1259</b> <b>P. Fuel Ele.</b> (9M2342)..... <b>[2] PF935</b> <b>Fuel Spin-on</b> (1R0712)..... <b>BF614</b> + <b>Fuel Spin-on</b> (1R0749)..... <b>BF7587</b> + <b>Air Dryer</b> (Coalescer Vers.) (Wabco R950068)..... <b>BA5379</b> + <b>Air Dryer</b> (Desiccant Vers.) (Bendix 109994)..... <b>BA5374</b> + <b>WX w/Cummins 6CT8.3 (8.3L) Eng.</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103</b> + <b>F-F Lube Spin-on</b> (3313281)..... <b>B205</b> + <b>Fuel/Water Separator Spin-on</b> (3925274)..... <b>BF1280</b> + <b>Fuel/Water Separator Spin-on</b> (Opt.) (3903202)..... <b>BF1226</b> <b>S. Fuel</b> (991203640)..... <b>BF788</b> <b>WX w/Cummins L10 (10.0L) Eng.</b> <b>F-F Lube</b> ..... <b>B196</b> + <b>B-P Lube</b> ..... <b>B7577</b> <b>Dual-Flow Lube</b> ..... <b>BD103</b> + <b>Opt. Fuel/Water Separator</b> ..... <b>BF1212</b> + <b>Fuel Spin-on</b> ..... <b>BF957</b> + <b>WX w/Cummins M11 (10.8L) Eng. (To 12/1995)</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103</b> + <b>Fuel/Water Separator Ele.</b> (Fleetguard FS1029W)..... <b>PF7680</b> <b>Fuel/Water Separator Spin-on</b> (3308638)..... <b>BF1212</b> + <b>Trans.</b> (Fuller 4304827)..... <b>BT223</b> <b>Opt. Trans.</b> (Fuller 17237)..... <b>B2</b> + <b>Trans.</b> (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b>

+ See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



WHITE/GMC Trucks (cont'd)	WHITE/GMC Trucks (cont'd)	WHITE/GMC Trucks (cont'd)
WX w/Cummins M11 (10.8L) Eng. (12/1995-on) Dual-Flow Lube (3318853)..... <b>BD103 +</b> Fuel/Water Separator Ele. (Fleetguard FS1029W)..... <b>PF7680</b> Fuel/Water Separator Spin-on (3329289)..... <b>BF1259</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Trans. (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b>	WXLL w/Cat 3306 (10.5L) Eng. (Cont'd) Trans. (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b> WXLL w/Cat 3406 (14.6L) Eng. F-F Lube (Std. Version) (1R0716)..... <b>B99 +</b> F-F Lube (High Efficiency Vers.) (1R1808)..... <b>B7299 +</b> Fuel/Water Separator Spin-on (2568753)..... <b>BF1259</b> P. Fuel Ele. (9M2342)..... <b>[2] PF935</b> Fuel Spin-on (1R0712)..... <b>BF614 +</b> Fuel Spin-on (1R0749)..... <b>BF7587 +</b> Air Dryer (Coalescer Vers.) (Wabco R950068)..... <b>BA5379 +</b> Air Dryer (Desiccant Vers.) (Bendix 109994)..... <b>BA5374 +</b>	WXR w/Cat 3306 (10.5L) Eng. (Cont'd) Box-Style Glass Fuel/Water Separator (6N7617)..... <b>BF912</b> Fuel/Water Separator Ele. (8N0205)..... <b>PF316</b> Fuel/Water Separator Spin-on (2568753)..... <b>BF1259</b> P. Fuel Ele. (9M2342)..... <b>PF935</b> P. Fuel Spin-on (1R1740)..... <b>BF970 +</b> S. Fuel Spin-on (1R0750)..... <b>BF7633 +</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b> Trans. (Auxiliary) (Allison 29510918)..... <b>PT8330-MPG</b>
WX w/Cummins N14 (14.0L) Eng. F-F Lube (Fleetguard LF670SC).. <b>B196 +</b> B-P Lube (3304232)..... <b>B7577</b> Dual-Flow Lube (3318853)..... <b>BD103 +</b> Fuel (154789)..... <b>BF957-D +</b>	WXLL w/Cat 3408 (18.0L) Eng. F-F Lube Spin-on (1R0716)..... <b>[2] B99 +</b> P. Fuel Ele. (9M2342)..... <b>[2] PF935</b> Fuel Spin-on (1R0712)..... <b>BF614 +</b> Fuel Spin-on (1R0749)..... <b>BF7587 +</b>	WXR w/Cummins 6CT8.3 (8.3L) Eng. Dual-Flow Lube (3318853)..... <b>BD103 +</b> F-F Lube Spin-on (3313281)..... <b>B205 +</b> Fuel/Water Separator Spin-on (3925274)..... <b>BF1280 +</b> Fuel/Water Separator Spin-on (Opt.) (3903202)..... <b>BF1226</b> S. Fuel (991203640)..... <b>BF788</b>
WX w/Cummins VT225 (9.1L) Eng. F-F Lube Spin-on (3313281)..... <b>B205 +</b> B-P Lube (3304232)..... <b>B7577</b> Fuel Spin-on (158172)..... <b>BF957 +</b> Coolant (w/4 Units BTA+) (3315116)..... <b>BW5071</b>	WXLL w/Cummins 6CT8.3 (8.3L) Eng. Dual-Flow Lube (3318853)..... <b>BD103 +</b> F-F Lube Spin-on (3313281)..... <b>B205 +</b> Fuel/Water Separator Spin-on (3925274)..... <b>BF1280 +</b> Fuel/Water Separator Spin-on (Opt.) (3903202)..... <b>BF1226</b> S. Fuel (991203640)..... <b>BF788</b>	WXR w/Cummins L10 (10.0L) Eng. F-F Lube..... <b>B196 +</b> B-P Lube..... <b>B7577</b> Dual-Flow Lube..... <b>BD103 +</b> Opt. Fuel/Water Separator..... <b>BF1212 +</b> Fuel Spin-on..... <b>BF957 +</b>
WX w/Detroit Diesel 6-71 (7.0L) Eng. Lube (23530407)..... <b>B95 +</b> P. Fuel (23530706)..... <b>BF5800 +</b> S. Fuel (23530707)..... <b>BF5810</b>	WXLL w/Cummins L10 (10.0L) Eng. F-F Lube..... <b>B196 +</b> B-P Lube..... <b>B7577</b> Dual-Flow Lube..... <b>BD103 +</b> Opt. Fuel/Water Separator..... <b>BF1212 +</b> Fuel Spin-on..... <b>BF957 +</b>	WXR w/Volvo VE7 Eng. F-F Lube (V478736)..... <b>B76-SS +</b> B-P Lube (477556)..... <b>B7685</b> Fuel (V466987)..... <b>BF988 +</b>
WX w/Detroit Diesel 6V-92N (9.0L) Eng. F-F Lube (23530407)..... <b>B95 +</b> F-F Lube (23530408)..... <b>B95-MPG +</b> P. Fuel (23530706)..... <b>BF5800 +</b> S. Fuel (23530707)..... <b>BF5810</b> S. Fuel (23530645)..... <b>BF5815</b>	WXLL w/Cummins L10 (10.0L) Eng. F-F Lube..... <b>B196 +</b> B-P Lube..... <b>B7577</b> Dual-Flow Lube..... <b>BD103 +</b> Opt. Fuel/Water Separator..... <b>BF1212 +</b> Fuel Spin-on..... <b>BF957 +</b>	<b>WILLIS</b> <b>Auxiliary Power Units (APU)</b> Premium w/Kubota D722 Eng. Lube (70000-15241)..... <b>B179</b> Fuel (Roosamaster 33168)..... <b>BF7675-D</b> Radial Seal Air (Enginaire 2S-E1)..... <b>RS3715</b>
WXLL w/Cat 3208 (10.4L) Eng. F-F Lube (9L9200)..... <b>[2] BT364</b> F-F Lube (9N5570)..... <b>[2] BT230</b> F-F Lube (9N6007)..... <b>[2] B75</b> Box-Style Fuel/Water Separator..... <b>BF912</b> Fuel Ele. (9M2341)..... <b>PF935</b> Fuel Spin-on..... <b>BF970 +</b> Fuel Spin-on (High Efficiency) (1R0750)..... <b>BF7633 +</b>	WXLL w/Detroit Diesel 6V-92N (9.0L) Eng. F-F Lube (23530407)..... <b>B95 +</b> F-F Lube (23530408)..... <b>B95-MPG +</b> P. Fuel (23530706)..... <b>BF5800 +</b> S. Fuel (23530707)..... <b>BF5810</b> S. Fuel (23530645)..... <b>BF5815</b>	Willie w/Kubota D722 Eng. Lube (70000-15241)..... <b>B179</b> Fuel (Roosamaster 33168)..... <b>BF7675-D</b> Radial Seal Air (Enginaire 2S-E1)..... <b>RS3715</b>
WXLL w/Cat 3306 (10.5L) Eng. Lube Ele. (5S0484)..... <b>PT670</b> Lube Spin-on (1R0716)..... <b>B99 +</b> Lube Spin-on (Standard Vers.) (1R0739)..... <b>B76 +</b> Lube Spin-on (Severe Service) (1R0739)..... <b>B76-SS +</b> Box-Style Glass Fuel/Water Separator (6N7617)..... <b>BF912</b> Fuel/Water Separator Ele. (8N0205)..... <b>PF316</b> Fuel/Water Separator Spin-on (2568753)..... <b>BF1259</b> P. Fuel Ele. (9M2342)..... <b>PF935</b> P. Fuel Spin-on (1R1740)..... <b>BF970 +</b> S. Fuel Spin-on (1R0750)..... <b>BF7633 +</b> Trans. (Fuller 4304827)..... <b>BT223</b> Opt. Trans. (Fuller 17237)..... <b>B2 +</b>	WXLM w/Cummins 6CT8.3 (8.3L) Eng. Dual-Flow Lube (3318853)..... <b>BD103 +</b> F-F Lube Spin-on (3313281)..... <b>B205 +</b> Fuel/Water Separator Spin-on (3925274)..... <b>BF1280 +</b> Fuel/Water Separator Spin-on (Opt.) (3903202)..... <b>BF1226</b> S. Fuel (991203640)..... <b>BF788</b>	<b>WOLFGANG</b> <b>Trucks</b> Models w/Bendix-Westinghouse Compressor Air Breather (243009)..... <b>PA1704</b> Models w/Cummins Eng. F-F Lube Bag..... <b>P996</b> F-F Lube Ele..... <b>P999-HD</b> F-F Lube Spin-on..... <b>B196 +</b> B-P Lube Ele..... <b>C750-E +</b> Fuel/Water Separator..... <b>BF1212 +</b> 4 3/8 In. Fuel Spin-on..... <b>BF948 +</b> 5 3/4 In. Fuel Spin-on..... <b>BF957 +</b> 11 7/32 In. Fuel Spin-on..... <b>BF596 +</b> Breather Ele. (w/Turbo) (255963) <b>PA643</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>WOLFGANG Trucks (cont'd)</b>	<b>WORKHORSE Chassis (cont'd)</b>	<b>WORKHORSE Chassis (cont'd)</b>
Models w/Cummins Eng. (Cont'd)	P32 w/V8-454 (7.4L) Eng.	W16 w/V8-496 (8.1L) Eng.
<b>Breather Ele.</b> (w/o Turbo)	<b>Lube</b> (W8800474)..... <b>B1428 +</b>	<b>Lube</b> (25324052)..... <b>B1438</b>
(256837)..... <b>PA1627</b>	<b>Fuel</b> (W8800482)..... <b>BF853</b>	<b>Air</b> (W8800481)..... <b>PA2232</b>
<b>Turbocharger</b> ..... <b>BT112</b>	<b>Air</b> (W8800481)..... <b>PA2232</b>	W16D w/IHC MaxxFer 5 Eng.
Models w/GMC Eng.	P32 w/V8-496 (8.1L) Eng. (2001-03)	<b>Lube</b> (1847174-C91)..... <b>P7423</b>
<b>F-F Lube Ele.</b> ..... <b>P20-HD +</b>	<b>Lube</b> (25324052)..... <b>B1438</b>	<b>Fuel</b> (1847170-C93)..... <b>PF7812 KIT</b>
<b>B-P Lube Ele.</b> ..... <b>P52</b>	<b>Fuel</b> (W8800482)..... <b>BF853</b>	<b>Trans. Pan-Type</b> (S. Pan w/o
<b>P. Fuel Sock.</b> ..... <b>F916-C</b>	<b>Air</b> (W8800481)..... <b>PA2232</b>	Gskt.) (Allison 29537965)..... <b>20004</b>
<b>S. Fuel Ele.</b> ..... <b>PF902</b>	P32 w/V8-496 (8.1L) Eng. (2004-06)	<b>Trans. Pan-Type</b> (S. Pan
<b>Air</b> ..... <b>PA616</b>	<b>Lube</b> (25324052)..... <b>B1438</b>	w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>WORKHORSE Chassis</b>	<b>Air</b> (W8800481)..... <b>PA2232</b>	<b>Trans. Pan-Type</b> (D. Pan w/o
Models w/364 CID 6.0L Eng. (2006)	P42 w/V8-395 (6.5L) Turbo Diesel Eng.	Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Lube</b> (W8800470)..... <b>B31</b>	<b>Lube</b> (W8800474)..... <b>B1428 +</b>	<b>Trans. Pan-Type</b> (D. Pan
<b>Air</b> (W8800481)..... <b>PA2232</b>	<b>Fuel/Water Separator</b> (GMC	w/Gskt.) (Allison 29537966)..... <b>20017</b>
Models w/454 CID 7.4L Eng. (1992-96)	12554082)..... <b>BF7674-D</b>	<b>Trans. Spin-on</b> (Allison
<b>Lube</b> (W8800474)..... <b>B1428 +</b>	<b>Air</b> (W8800481)..... <b>PA2232</b>	29539579)..... <b>BT8460</b>
<b>Fuel</b> (W8800482)..... <b>BF853</b>	P42 w/V8-454 (7.4L) Eng.	W18 w/V8-496 (8.1L) Eng.
<b>Air</b> (GMC 6484235)..... <b>PA2008</b>	<b>Lube</b> (W8800474)..... <b>B1428 +</b>	<b>Lube</b> (25324052)..... <b>B1438</b>
Models w/4L80E & 4L85E Trans.	<b>Fuel</b> (W8800482)..... <b>BF853</b>	<b>Air</b> (W8800481)..... <b>PA2232</b>
<b>Trans.</b> (24210956)..... <b>18027</b>	<b>Air</b> (W8800481)..... <b>PA2232</b>	W20 w/V8-496 (8.1L) Eng. (2001-03)
Models w/Allison 1000 & 2100 Trans.	P Series w/Cummins N14 Eng.	<b>Lube</b> (25324052)..... <b>B1438</b>
<b>Trans. Pan-Type</b> (S. Pan w/o	<b>Fuel/Water Separator</b>	<b>Fuel</b> (W8800482)..... <b>BF853</b>
Gskt.) (Allison 29537965)..... <b>20004</b>	(Fleetguard FS1212)..... <b>BF1212 +</b>	<b>Air</b> (W8800481)..... <b>PA2232</b>
<b>Trans. Pan-Type</b> (S. Pan	<b>Air</b> (Don. P153551)..... <b>PA2705</b>	<b>Trans. Pan-Type</b> (S. Pan w/o
w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Coolant</b> (Fleetguard WF2077)..... <b>B5134 +</b>	Gskt.) (Allison 29537965)..... <b>20004</b>
<b>Trans. Pan-Type</b> (D. Pan w/o	<b>Opt. Trans.</b> (Fuller 17237)..... <b>B2 +</b>	<b>Trans. Pan-Type</b> (S. Pan
Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Steering</b> (Nelson 83213M)..... <b>P528</b>	w/Gskt.) (Allison 29537965)..... <b>20016</b>
<b>Trans. Pan-Type</b> (D. Pan	R26 w/V8-496 (8.1L) Eng.	<b>Trans. Pan-Type</b> (D. Pan w/o
w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Lube</b> (25324052)..... <b>B1438</b>	Gskt.) (Allison 29537966)..... <b>20003</b>
<b>Trans. Spin-on</b> (Allison	<b>Air</b> (W8800481)..... <b>PA2232</b>	<b>Trans. Pan-Type</b> (D. Pan
29539579)..... <b>BT8460</b>	R26 w/Cummins ISB6.7 (6.7L) Eng.	w/Gskt.) (Allison 29537966)..... <b>20017</b>
LF72 w/GM V8-403 (6.6L) Turbo Diesel Eng.	<b>Trans. Pan-Type</b> (S. Pan w/o	<b>Trans. Spin-on</b> (Allison
<b>Lube</b> (ACDelco PF2232)..... <b>B1441</b>	Gskt.) (Allison 29537965)..... <b>20004</b>	29539579)..... <b>BT8460</b>
<b>Fuel</b> (Upgrade) (ACDelco	<b>Trans. Pan-Type</b> (S. Pan	W20 w/V8-496 (8.1L) Eng. (2004-09)
TP3018)..... <b>BF46062</b>	w/Gskt.) (Allison 29537965)..... <b>20016</b>	<b>Lube</b> (25324052)..... <b>B1438</b>
<b>Trans. Pan-Type</b> (S. Pan w/o	<b>Trans. Pan-Type</b> (D. Pan w/o	<b>Air</b> (W8800481)..... <b>PA2232</b>
Gskt.) (Allison 29537965)..... <b>20004</b>	Gskt.) (Allison 29537966)..... <b>20003</b>	<b>Trans. Pan-Type</b> (S. Pan w/o
<b>Trans. Pan-Type</b> (S. Pan	<b>Trans. Pan-Type</b> (D. Pan	Gskt.) (Allison 29537965)..... <b>20004</b>
w/Gskt.) (Allison 29537965)..... <b>20016</b>	w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Trans. Pan-Type</b> (S. Pan
<b>Trans. Pan-Type</b> (D. Pan w/o	<b>Trans. Spin-on</b> (Allison	w/Gskt.) (Allison 29537965)..... <b>20016</b>
Gskt.) (Allison 29537966)..... <b>20003</b>	29539579)..... <b>BT8460</b>	<b>Trans. Pan-Type</b> (D. Pan w/o
<b>Trans. Pan-Type</b> (D. Pan	R32 w/Cummins ISC (8.3L) Eng.	Gskt.) (Allison 29537966)..... <b>20003</b>
w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>Dual-Flow Lube</b> (Fleetguard	<b>Trans. Pan-Type</b> (D. Pan
<b>Trans. Spin-on</b> (Allison	LF9009)..... <b>BD7309 +</b>	w/Gskt.) (Allison 29537966)..... <b>20017</b>
29539579)..... <b>BT8460</b>	<b>Fuel</b> (3959612)..... <b>BF7815</b>	<b>Trans. Spin-on</b> (Allison
P32 w/V8-350 (5.7L) Eng.	<b>Trans.</b> (2 In. Kit) (Allison	29539579)..... <b>BT8460</b>
<b>Lube</b> (W8800466)..... <b>B35-S +</b>	29540493)..... <b>PT9416-MPG KIT</b>	W21 w/V8-496 (8.1L) Eng.
<b>Fuel</b> (W8800482)..... <b>BF853</b>	<b>Trans.</b> (4 In. Kit) (Allison	<b>Lube</b> (25324052)..... <b>B1438</b>
<b>Air</b> (W8800481)..... <b>PA2232</b>	29540494)..... <b>PT9415-MPG KIT</b>	<b>Air</b> (W8800481)..... <b>PA2232</b>
P32 w/V8-395 (6.5L) Turbo Diesel Eng.	R32 w/Cummins ISL (8.9L) Eng.	W22 w/V8-496 (8.1L) Eng. (2001-03)
<b>Lube</b> (W8800474)..... <b>B1428 +</b>	<b>Dual-Flow Lube</b> (Fleetguard	<b>Lube</b> (25324052)..... <b>B1438</b>
<b>Fuel/Water Separator</b> (GMC	LF9009)..... <b>BD7309 +</b>	<b>Fuel</b> (W8800482)..... <b>BF853</b>
12554082)..... <b>BF7674-D</b>	<b>Fuel</b> (3959612)..... <b>BF7815</b>	<b>Air</b> (W8800481)..... <b>PA2232</b>
<b>Air</b> (W8800481)..... <b>PA2232</b>	<b>Trans.</b> (2 In. Kit) (Allison	<b>Trans. Pan-Type</b> (S. Pan w/o
	29540493)..... <b>PT9416-MPG KIT</b>	Gskt.) (Allison 29537965)..... <b>20004</b>
	<b>Trans.</b> (4 In. Kit) (Allison	<b>Trans. Pan-Type</b> (S. Pan
	29540494)..... <b>PT9415-MPG KIT</b>	w/Gskt.) (Allison 29537965)..... <b>20016</b>

\* See Product Guide for Variations of This Number.  
Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

<b>WORKHORSE Chassis (cont'd)</b>	<b>WORKHORSE Chassis (cont'd)</b>	<b>WORKHORSE Chassis (cont'd)</b>
<b>W22 w/V8-496 (8.1L) Eng. (2001-03) (Cont'd)</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>W31 w/International VT275 Eng. (Cont'd)</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b> <b>W42 w/Cummins M11 Eng.</b> <b>Dual-Flow Lube</b> (3318853)..... <b>BD103+</b> <b>Fuel/Water Separator</b> (3329289)..... <b>BF1259</b> <b>Air</b> (Don. P153551)..... <b>PA2705</b> <b>Opt. Trans. Spin-on</b> (Fuller 17237)..... <b>B2+</b> <b>Steering</b> (Nelson 83213M)..... <b>P528</b>	<b>W62 w/IHC MaxxForce 5 Eng.</b> <b>Lube</b> (1847174-C91)..... <b>P7423</b> <b>Fuel</b> (1847170-C93)..... <b>PF7812 KIT</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>
<b>W22 w/V8-496 (8.1L) Eng. (2004-11)</b> <b>Lube</b> (25324052)..... <b>B1438</b> <b>Fuel</b> (W8800482)..... <b>BF853</b> <b>Air</b> (W8800481)..... <b>PA2232</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>W42 w/GM V8 4.8L Eng.</b> <b>Lube</b> (GMC 89017524)..... <b>B160</b> <b>Air</b> (Don. P153551)..... <b>PA2705</b> <b>Coolant</b> (Fleetguard WF2077)..... <b>B5134+</b> <b>Trans.</b> (GMC 24210956)..... <b>18027</b> <b>Steering</b> (Nelson 83213M)..... <b>P528</b>	<b>ZANOTTI Refrigeration Units</b> <b>Models w/103-07 Perkins Eng.</b> <b>Lube</b> (140517050)..... <b>B1405</b> <b>Fuel</b> (130366040)..... <b>PF937</b>
<b>W24 w/V8-496 (8.1L) Eng.</b> <b>Lube</b> (25324052)..... <b>B1438</b> <b>Air</b> (W8800481)..... <b>PA2232</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>W42 w/GM V8 6.0L Eng.</b> <b>Lube</b> (GMC 89017524)..... <b>B160</b> <b>Trans.</b> (GMC 24210956)..... <b>18027</b>	<b>Models w/103-10 Perkins Eng.</b> <b>Lube</b> (140517050)..... <b>B1405</b> <b>Fuel</b> (130366120)..... <b>BF954+</b>
<b>W25 w/V8-496 (8.1L) Eng.</b> <b>Lube</b> (25324052)..... <b>B1438</b> <b>Air</b> (W8800481)..... <b>PA2232</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>W42 w/IHC MaxxForce 5 Eng.</b> <b>Lube</b> (1847174-C91)..... <b>P7423</b> <b>Fuel</b> (1847170-C93)..... <b>PF7812 KIT</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Models w/103-15 Perkins Eng.</b> <b>Lube</b> (140517050)..... <b>B1405</b> <b>Fuel</b> (130366120)..... <b>BF954+</b>
<b>W31 w/International VT275 Eng.</b> <b>Lube</b> (6011358C1)..... <b>P7247</b> <b>Fuel</b> (1847170-C93)..... <b>PF7812 KIT</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b>	<b>W42 w/IHC VT275 (4.5L) Eng.</b> <b>Lube</b> (1847174C91)..... <b>P7423</b> <b>Fuel</b> (1847170-C93)..... <b>PF7812 KIT</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Models w/403-C07 Perkins Eng.</b> <b>Lube</b> (140517050)..... <b>B1405</b> <b>Fuel</b> (26561117)..... <b>BF825+</b>
<b>W62 w/GMC V8 8.1L Eng.</b> <b>Lube</b> (ACDelco PF454)..... <b>B1438</b> <b>Air</b> (ACDelco A1236C)..... <b>PA2232</b> <b>Trans. Pan-Type</b> (S. Pan w/o Gskt.) (Allison 29537965)..... <b>20004</b> <b>Trans. Pan-Type</b> (S. Pan w/Gskt.) (Allison 29537965)..... <b>20016</b> <b>Trans. Pan-Type</b> (D. Pan w/o Gskt.) (Allison 29537966)..... <b>20003</b> <b>Trans. Pan-Type</b> (D. Pan w/Gskt.) (Allison 29537966)..... <b>20017</b> <b>Trans. Spin-on</b> (Allison 29539579)..... <b>BT8460</b>	<b>Models w/403-C10 Perkins Eng.</b> <b>Lube</b> (140517050)..... <b>B1405</b> <b>Fuel</b> (26561117)..... <b>BF825+</b>	<b>Models w/403-C15 Perkins Eng.</b> <b>Lube</b> (140517050)..... <b>B1405</b> <b>Fuel</b> (130366040)..... <b>PF937</b>

\* See Product Guide for Variations of This Number.  
 Check Original Equipment Numbers In Parentheses.

**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

**NOTES**

---

## BALDWIN FILTER DATE CODING METHODS

You will find several different date coding methods used on Baldwin products and packaging. Please look for one of these coding methods whenever you are trying to find the date of manufacture for a Baldwin product.

■ **Six (6) Digit Numeric Code - e.g. 010322**

**Introduced November 8, 2002** (Replaces (3) Digit Numeric Code)

1st Two Digits	- 01 -	indicate month (January)
2nd Two Digits	- 03 -	indicate day of month (3rd)
Last Two Digits	- 22 -	indicate year (2022)

■ **Eleven (11) Digit Numeric Code - e.g. 08292214301**

**Introduced November 8, 2002** (Replaces (10) Digit Numeric Code)

1st Two Digits	- 08 -	indicate month (August)
2nd Two Digits	- 29 -	indicate day of month (29th)
5th and 6th Digits	- 22 -	indicate year (2022)
Next 4 Digits	- 1430 -	indicate time of day (Military) (2:30 p.m.)
Last Digit	- 1 -	indicates filter line

### Date Coding Methods Used Prior to 2003

■ **Three (3) Digit Numeric Code - e.g. 082**

1st Two Digits	- 08 -	indicate month (August)
Last Digit	- 2 -	indicates year (2002)

■ **Ten (10) Digit Numeric Code - e.g. 0829214303**

1st Two Digits	- 08 -	indicate month (August)
2nd Two Digits	- 29 -	indicate day of month (29th)
5th Digit	- 2 -	indicates year (2002)
Next 4 Digits	- 1430 -	indicate time of day (Military) (2:30 p.m.)
Last Digit	- 3 -	for internal control purposes

■ **Numeric Digits and Diamonds - e.g. 234 ◆◆◆◆**

1st Digit	- 2 -	indicates last digit of the year (2002)
Diamonds	- ◆◆◆◆ -	indicate month (August) Number of diamonds subtracted from 13 equals the month (13 - 5 = 8 = August)

## A WORD ABOUT WARRANTIES

Heavy-duty equipment manufacturers and dealers like to sell their brand of filter. But, the law does not permit them to require you to use their brand in order to keep the warranty in effect. Baldwin filters meet or exceed manufacturers' requirements and specifications. If engine damage is caused by our filter, our warranty applies regardless of whether your equipment is still under the manufacturer's warranty.

If a filter is suspected of causing a failure, don't throw away the evidence. Instead, in order to process a warranty claim, follow the Product Investigation Procedure . . .

1. Complete a Field Report Form (Form 387). Describe the events on a separate sheet.

2. Obtain a sample of oil, fuel or coolant in the system at the time of the failure.
3. Save damaged parts for evidence of the claimed damage.
4. For an air filter, cover the open ends with tape to prevent dust from entering the element during shipping.
5. Send copies of any repair bills.
6. Send the entire suspect filter, including the gaskets. Do not cut open the filter or tamper with it in any way. Package the filter carefully to prevent damage to packaging or paperwork.

---

## MÉTHODES DE CODAGE DE DATE DES FILTRES BALDWIN

---

Vous trouverez plusieurs méthodes de codage de date sur les produits et emballages Baldwin. Veuillez rechercher une de ces méthodes de codage lorsque vous essayez de trouver la date de fabrication d'un produit Baldwin.

■ **Code numérique à six (6) chiffres - Ex.: 010322**

Introduit le 8 novembre 2002 (remplace le code numérique à trois (3) chiffres)

Deux premiers chiffres	- 01 -	indiquent le mois (janvier)
Deux chiffres du milieu	- 03 -	indiquent le jour du mois (3 <sup>e</sup> )
Deux derniers chiffres	- 22 -	indiquent l'année (2022)

■ **Code numérique à onze (11) chiffres - Ex.: 08292214301**

Introduit le 8 novembre 2002 (remplace le code numérique à dix (10) chiffres)

Deux premiers chiffres	- 08 -	indiquent le mois (août)
Deux chiffres suivants	- 29 -	indiquent le jour du mois (29 <sup>e</sup> )
5 <sup>e</sup> et 6 <sup>e</sup> chiffres	- 22 -	indiquent l'année (2022)
Quatre chiffres suivants	- 1430 -	indiquent l'heure (14h30)
Dernier chiffre	- 1 -	indique la gamme du filtre

### Méthodes de codage de date utilisées avant 2003

■ **Code numérique à trois (3) chiffres - Ex.: 082**

Deux premiers chiffres	- 08 -	indiquent le mois (août)
Dernier chiffre	- 2 -	indique l'année (2002)

■ **Code numérique à dix (10) chiffres - Ex.: 0829214303**

Deux premiers chiffres	- 08 -	indiquent le mois (août)
Deux chiffres suivants	- 29 -	indiquent le jour du mois (29 <sup>e</sup> )
5 <sup>e</sup> chiffre	- 2 -	indique l'année (2002)
Quatre chiffres suivants	- 1430 -	indiquent l'heure (14h30)
Dernier chiffre	- 3 -	pour contrôle interne

■ **Chiffres et losanges - Ex.: 234 ◆◆◆◆**

Premier chiffre	- 2 -	indique le dernier chiffre de l'année (2002)
Losanges	- ◆◆◆◆ -	indiquent le mois (août) Nombre de losanges soustrait de 13 égal le mois (13 - 5 = 8 = août)

---

## UN MOT SUR LES GARANTIES

---

Les concessionnaires et les fabricants de gros équipement aiment vendre les filtres de leur marque. Mais la loi ne les autorise pas à vous obliger d'utiliser leur marque pour conserver la garantie active. Les filtres Baldwin répondent ou surpassent les exigences et spécifications des fabricants. Si votre moteur est endommagé par nos filtres, notre garantie s'applique que votre équipement soit encore ou non sous la garantie du fabricant.

Si un filtre est soupçonné causer une défaillance, n'en jetez pas la preuve. Afin de pouvoir faire une réclamation au titre de la garantie, suivez la Procédure d'investigation de produit . . .

1. Remplissez un formulaire de rapport terrain (Form. 387). Décrivez les événements sur une feuille séparée.

2. Obtenez un échantillon d'huile, de carburant ou de liquide de refroidissement du système au moment de la défaillance.
3. Conservez les pièces endommagées comme preuve des dégâts pour la réclamation.
4. Pour un filtre à air, couvrez de ruban adhésif les extrémités ouvertes pour éviter que la poussière n'entre dans la cartouche pendant l'expédition.
5. Envoyez des copies des factures de réparation éventuelles.
6. Envoyez le filtre suspect entier, y compris les joints. N'ouvrez pas le filtre et n'essayez pas de le modifier de quelque façon que ce soit. Emballez-le soigneusement pour éviter d'endommager l'emballage ou les papiers.

# BALDWIN FILTERS-DATUMSSCHLÜSSEL

Sie werden feststellen, dass mehrere verschiedene Datumsschlüssel auf Baldwin-Produkten und -Verpackungen in Gebrauch sind. Bitte suchen Sie nach einem dieser Schlüssel, wenn Sie nach dem Herstellungsdatum eines Baldwin-Produkts suchen.

## ■ Sechsstelliger Zifferncode - z.B. 010322

eingeführt am 8. November 2002 (tritt an die Stelle des dreistelligen Zifferncodes)

erste 2 Stellen	- 01 -	stehen für den Monat (Januar)
3. und 4. Stelle	- 03 -	stehen für Tag des Monats (3.)
5. und 6. Stelle	- 22 -	stehen für das Jahr (2022)

## ■ Elfstelliger Zifferncode - z.B. 08292214301

eingeführt am 8. November 2002 (tritt an die Stelle des zehnstelligen Zifferncodes)

erste 2 Stellen	- 08 -	stehen für den Monat (August)
3. und 4. Stelle	- 29 -	stehen für Tag des Monats (29.)
5. und 6. Stelle	- 22 -	stehen für das Jahr (2022)
nächste 4 Stellen	- 1430 -	stehen für die Tageszeit (14.30 Uhr)
letzte Stelle	- 1 -	steht für die Filterserie

## Datierungsschlüssel vor 2003

### ■ Dreistelliger Zifferncode - z.B. 082

erste 2 Stellen	- 08 -	stehen für den Monat (August)
letzte Stelle	- 2 -	steht für das Jahr (2002)

### ■ Zehnstelliger (10) Zifferncode - z.B. 0829214303

erste 2 Stellen	- 08 -	stehen für den Monat (August)
nächste 2 Stellen	- 29 -	stehen für den Tag des Monats (29.)
fünfte Stelle	- 2 -	steht für das Jahr (2002)
nächste 4 Stellen	- 1430 -	stehen für die Uhrzeit (14.30 Uhr)
letzte Stelle	- 3 -	dient zu internen Prüfzwecken

### ■ Ziffern und Rauten - z.B. 234 ◆◆◆◆◆

1. Stelle	- 2 -	stehen für die letzte Ziffer der Jahreszahl (2002)
Rauten	- ◆◆◆◆◆ -	Monat (August) Anzahl der Rauten von 13 subtrahieren = Monat (13-5 = 8, d. h. August)

## EIN WORT ZUR GARANTIE

Hersteller und Händler von Hochleistungsfahrzeugen und -maschinen möchten verständlicherweise ihre eigenen Filtermarken verkaufen. Das Gesetz untersagt es ihnen jedoch, Sie zur Verwendung ihrer Marken zu verpflichten, um Garantieansprüche aufrecht zu erhalten. Baldwin-Filter erfüllen oder übertreffen die Anforderungen und Spezifikationen der Hersteller. Bei Motorschäden, die durch unsere Filter hervorgerufen werden, gilt unsere Garantieleistung, ungeachtet der Frage, ob Ihr Fahrzeug/Ihre Maschine noch unter die Garantieleistung des Herstellers fällt.

Steht ein Filter im Verdacht, einen Ausfall hervorgerufen zu haben, werfen Sie das Beweisstück nicht weg. Um einen Garantieanspruch geltend zu machen, richten Sie sich bitte nach dem folgenden Produktuntersuchungsverfahren.

1. Füllen Sie einen Feldbericht aus (Form 387). Beschreiben Sie die Ereignisse auf einem anderen Blatt.

2. Nehmen Sie eine Öl-, Treibstoff- oder Kühlmittelprobe aus der Anlage zum Zeitpunkt des Ausfalls.
3. Heben Sie beschädigte Teile als Beweismaterial für reklamierte Schäden auf.
4. Bei einem Luftfilter verschließen Sie die offenen Enden mit Klebeband, um ein Eindringen von Staub in den Einsatz während des Versands zu vermeiden.
5. Schicken Sie Kopien der Reparaturrechnungen mit ein.
6. Schicken Sie den gesamten unter Verdacht stehenden Filter einschließlich Flachdichtung ein. Schneiden Sie den Filter nicht auf und manipulieren Sie ihn nicht. Verpacken Sie den Filter sorgfältig, um eine Beschädigung der Verpackung oder der Dokumente zu verhindern.

## MÉTODOS DE CODIFICAÇÃO POR DATA DOS FILTROS BALDWIN

Você encontrará diversos métodos de codificação por data nos produtos e embalagens Baldwin. Por favor, procure um destes métodos de codificação sempre que tentar encontrar a data de fabricação de um produto Baldwin.

### ■ Código Numérico de Seis (6) Dígitos - Exemplo: 010322

**Introduzido em 8 de novembro de 2002** (Substitui o código numérico de 3 dígitos)

Primeiros Dois Dígitos	- 01 -	indicam o mês (janeiro)
Segundos Dois Dígitos	- 03 -	indicam o dia do mês (3)
Últimos Dois Dígitos	- 22 -	indicam o ano (2022)

### ■ Código Numérico de Onze (11) Dígitos - Exemplo: 08292214301

**Introduzido em 8 de novembro de 2002** (Substitui o código numérico de 10 dígitos)

Primeiros Dois Dígitos	- 08 -	indicam o mês (agosto)
Segundos Dois Dígitos	- 29 -	indicam o dia do mês (29)
Quinto e Sexto Dígitos	- 22 -	indicam o ano (2022)
Próximos 4 Dígitos	- 1430 -	indicam a hora do dia (14h 30m)
Último Dígitos	- 1 -	indica a linha de filtro

### Métodos de Codificação por Data Usados Antes de 2003

#### ■ Código Numérico de Três (3) Dígitos - Exemplo: 082

Primeiros Dois Dígitos	- 08 -	indicam o mês (agosto)
Último Dígitos	- 2 -	indica o ano (2002)

#### ■ Código Numérico de Dez (10) Dígitos - Exemplo: 0829214303

Primeiros Dois Dígitos	- 08 -	indicam o mês (agosto)
Segundos Dois Dígitos	- 29 -	indicam o dia do mês (29)
Quinto Dígitos	- 2 -	indica o ano (2002)
Próximos 4 Dígitos	- 1430 -	indicam a hora do dia (14h 30m)
Último Dígitos	- 3 -	para fins de controle interno

#### ■ Dígitos Numéricos e Sinais de Diamantes - Exemplo: 234 ◆◆◆◆

Primeiro Dígitos	- 2 -	indica o último dígitos do ano (2002)
Sinais de Diamantes	- ◆◆◆◆ -	indicam o mês (agosto)

O número de sinais de diamantes subtraído de 13 é igual ao número do mês (13 – 5 = 8 = agosto)

## UMA NOTA SOBRE GARANTIA

Os fabricantes e comerciantes de equipamentos para serviços pesados gostam de vender filtros de suas marcas. Porém, a lei não permite que eles exijam que você use as suas marcas a fim de manter a garantia válida. Os filtros Baldwin atendem ou excedem as especificações e requisitos dos fabricantes. Se um dano ao motor for causado por nosso filtro, a nossa garantia é válida, a despeito do seu equipamento ainda estar dentro da garantia do fabricante.

Se um filtro for suspeito de causar um defeito, não jogue fora as evidências. Ao invés, a fim de processar a reclamação de garantia, siga o Procedimento de Investigação de Produto...

1. Preencha o Formulário de Relatório de Campo (Formulário 387). Descreva os fatos numa folha separada.

2. Obtenha uma amostra de óleo, combustível ou refrigerante no sistema na ocasião do defeito.
3. Guarde as peças danificadas como prova do defeito alegado.
4. Para um filtro de ar, cubra as extremidades abertas com fita adesiva para impedir a entrada de pó no elemento durante o transporte.
5. Envie cópias de quaisquer faturas de reparos.
6. Envie todo o filtro suspeito, incluindo as juntas. Não abra o filtro nem o modifique. Acondicione o filtro cuidadosamente para evitar avarias na embalagem ou nos documentos.



## МЕТОДЫ УКАЗАНИЯ ДАТЫ НА ФИЛЬТРАХ КОМПАНИИ “БОЛДУИН”

Для обозначения дат на изделиях и упаковке компании “Болдуин” применяется несколько различных методов. В тех случаях, когда вам требуется найти дату изготовления изделия “Болдуин”, следует искать один из указанных ниже вариантов обозначений.

■ **Цифровое обозначение из 6 (шести) цифр - например: 010322**

—**анные обозначения применяются с 8 ноября 2002 г.** (и заменяют обозначения из 3 цифр)

Первые две цифры	- 01 -	обозначают месяц (январь)
Вторые две цифры	- 03 -	обозначают день месяца (3-е)
Последние две цифры	- 22 -	обозначают год (2022)

■ **Обозначение из 11 (одиннадцати) цифр - например: 08292214301**

—**анные обозначения применяются с 8 ноября 2002 г.** (и заменяют обозначения из 10 цифр)

Первые две цифры	- 08 -	обозначают месяц (август)
Вторые две цифры	- 29 -	обозначают день месяца (29-е)
Пятая и шестая цифры	- 22 -	обозначают год (2022)
Следующие четыре цифры	- 1430 -	обозначают время (14:30)
Последняя цифра	- 1 -	обозначает серию фильтра

### Методы указания даты, применявшиеся до 2003 г.

■ **Обозначение из 3 (трех) цифр - например: 082**

Первые две цифры	- 08 -	обозначают месяц (август)
Последняя цифра	- 2 -	обозначает год (2002)

■ **Обозначение из 10 (десяти) цифр - например: 0829214303**

Первые две цифры	- 08 -	обозначают месяц (август)
Вторые две цифры	- 29 -	обозначают день месяца (29-е)
Пятая цифра	- 2 -	обозначает год (2002)
Следующие четыре цифры	- 1430 -	обозначают время (14:30)
Последняя цифра	- 3 -	предназначается для внутреннего контроля

■ **Цифры и ромбики - например: 234 ◆◆◆◆◆**

Первые цифра	- 2 -	обозначает последнюю цифру года (2002)
Ромбики	- ◆◆◆◆◆ -	обозначают месяц (август) При вычитании числа ромбиков из числа 13 мы получаем месяц (13 - 5 = 8, т.е. август)

## ПРИМЕЧАНИЕ О ГАРАНТИИ

Изготовители и дилеры, предлагающие оборудование, предназначенное для эксплуатации в тяжелом режиме, предпочитают продавать фильтры собственных торговых марок. Однако согласно законодательству они не вправе потребовать от вас использования продукции их торговых марок в качестве условия сохранения гарантии. Характеристики фильтров “Болдуин” соответствуют параметрам, установленным на основании требований и технических условий изготовителей, или превышают данные параметры. Если использование одного из наших фильтров послужило причиной повреждения двигателя, наша гарантия действует независимо от того, находится ли ваше оборудование на гарантии производителя.

Если имеются основания считать, что фильтр послужил причиной отказа, не следует выбрасывать доказательства. Вместо этого, для предъявления гарантийной рекламации, необходимо выполнить инструкцию по расследованию причин отказа изделия . . .

1. Заполните форму протокола по отказам на месте эксплуатации (форма 387). — айте описание событий на отдельном листе.
2. Возьмите пробу масла, топлива или охлаждающей жидкости, находящейся в системе во время отказа.
3. Сохраните поврежденные детали в качестве едоказательств наличия повреждений согласно рекламации.
4. В случае с воздушным фильтром заклейте открытые торцы клейкой лентой для того, чтобы предотвратить пыли внутрь детали во время транспортировки.
5. Пришлите копии счетов за все ремонтные работы.
6. Пришлите блок фильтра, в котором предполагается наличие неисправностей, в сборе с прокладками. Не открывайте фильтр и не вносите в его конструкцию никаких изменений. Аккуратно упакуйте фильтр для того, чтобы предотвратить повреждение упаковки или документации.

## MÉTODOS DE CODIFICACIÓN DE LA FECHA EN LOS FILTROS BALDWIN

En los productos y envases de Baldwin se encontrarán varios métodos distintos de codificación de la fecha. Rogamos buscar uno de estos métodos de codificación cuando se desee encontrar la fecha de fabricación de un producto Baldwin.

### ■ Código numérico de seis (6) dígitos - por ej., 010322

Presentado el 8 de noviembre de 2002 (reemplaza al código numérico de tres (3) dígitos)

Primeros dos dígitos	- 01 -	indican el mes (enero)
Segundos dos dígitos	- 03 -	indican el día del mes (tercer)
Últimos dos dígitos	- 22 -	indican el año (2022)

### ■ Código numérico de once (11) dígitos - por ej., 08292214301

Presentado el 8 de noviembre de 2002 (reemplaza al código numérico de diez (10) dígitos)

Primeros dos dígitos	- 08 -	indican el mes (agosto)
Segundos dos dígitos	- 29 -	indican el día del mes (29)
Quinto y sexto dígito	- 22 -	indican el año (2022)
Siguientes 4 dígitos	- 1430 -	indican la hora del día (militar) (2:30 p.m.)
Último dígito	- 1 -	indica la línea de filtro

### Métodos de codificación de fecha utilizados antes de 2003

#### ■ Código numérico de tres (3) dígitos - por ej., 082

Primeros dos dígitos	- 08 -	indican el mes (agosto)
Último dígito	- 2 -	indica el año (2002)

#### ■ Código numérico de 10 dígitos - por ej., 0829214303

Primeros dos dígitos	- 08 -	indican el mes (agosto)
Segundos dos dígitos	- 29 -	indican el día del mes (29)
Quinto dígito	- 2 -	indica el año (2002)
Próximos 4 dígitos	- 1430 -	indican la hora del día (militar) (2:30 pm)
Último dígito	- 3 -	para propósitos de control interno

#### ■ Dígitos numéricos y rombos - por ej., 234 ◆◆◆◆

Primer dígito	- 2 -	indica el último dígito del año (2002)
Rombos	- ◆◆◆◆ -	indican el mes (agosto) 13 menos el número de rombos es igual al mes (13 - 5 = 8 = Agosto)

## UNA PALABRA ACERCA DE LAS GARANTÍAS

Los fabricantes y concesionarios de equipos para servicio pesado prefieren vender su marca de filtro. Pero, por ley no les está permitido a exigir el uso de su marca para mantener vigente la garantía. Los filtros Baldwin cumplen o exceden los requerimientos y las especificaciones de los fabricantes. Si el motor se llegara a dañar por culpa de nuestro filtro, nuestra garantía es la que es válida indiferente a si el equipo todavía está cubierto por la garantía del fabricante.

Si se sospecha que un filtro es el causante de la avería, no tire a la basura la evidencia. En vez, para poder tramitar el reclamo de garantía, siga el procedimiento de investigación del producto...

1. Llene un formulario de informe de campo (Form 387). Describa los eventos en una hoja aparte.

2. Saque una muestra del aceite, combustible o refrigerante del sistema al momento de ocurrir la avería.
3. Guarde las piezas dañadas como evidencia del daño reclamado.
4. Para un filtro de aire, tape los extremos abiertos con cinta adhesiva con el fin de evitar la entrada de polvo al elemento durante el transporte.
5. Envíe copias de cualquier factura de reparación.
6. Envíe el filtro sospechoso completo, incluidas las juntas. No abra el filtro ni lo estorbe de manera alguna. Empaquete el filtro cuidadosamente para impedir que se dañe el empaquetado o los documentos.

**BALDWIN FILTER WARRANTY****BALDWIN WARRANTY (English)**

Baldwin Filters, Inc. ("Baldwin") warrants that each new product manufactured by Baldwin will be made free of defects in workmanship and material. Baldwin will replace any product found to be defective when you return it to Baldwin or to your Baldwin distributor where you purchased the product.

**Return Process**

You should first contact your salesperson at Baldwin or at your Baldwin distributor if you purchased a product that you believe does not meet the warranty stated above. The salesperson will help you complete the necessary paperwork, and will also help you return the suspected defective product to Baldwin for analysis.

**Warranty Fulfillment**

If Baldwin finds that a returned product does not meet the warranty stated above, Baldwin will promptly replace the defective product. If the defective product directly caused damage to the machine on which it was installed, Baldwin will promptly reimburse the machine owner for that portion of the repair costs that were necessary to restore the machine to its condition immediately prior to the damage caused by the defective product.

**Conditions**

Baldwin's warranty fulfillment obligations above do not apply if: a) the product is not returned to Baldwin for analysis, b) Baldwin finds that the product was not defective, c) the product was improperly installed or used, d) the product was re-used or not replaced inside a normal service interval, or e) the product is tampered with or damaged in a manner that may inhibit Baldwin's ability to conduct a warranty investigation.

**The above warranty and warranty fulfillment obligations are exclusive and in lieu of all other warranties or related remedies. Baldwin is not liable for indirect, incidental, punitive or consequential damages arising in any way from the products it manufactures or sells.**

\*\*\*\*\*

**宝德威保用说明 (Chinese / 中文)**

宝德威过滤器公司（下称“宝德威”）保证由本公司制造的每件新的产品在工艺和材料上均无缺陷。任何产品若发现有缺陷，可退回宝德威或您向其购买产品的宝德威经销商，本公司负责更换。

**退货流程**

如果您认为购买的产品不符合以上保用说明，首先应联系宝德威或宝德威经销商的销售人员。销售人员将帮助您完成必要的文书手续，并协助您将怀疑有缺陷的产品退回宝德威分析。

**履行保用**

如果宝德威认为退回的产品不符合上述保用说明，宝德威将及时更换有缺陷的产品。如果有缺陷的产品直接造成其所安装的机器损坏，宝德威将及时赔偿机器业主将机器恢复到缺陷产品造成损坏之前状态所必需的修理费用。

**条件**

如果存在以下情况，宝德威的履行保用的义务即不适用： a)产品未退回宝德威供分析； b)宝德威认为产品并无缺陷； c)产品安装或使用不当； d)产品系重复使用或未在正常服务间隔内更换，或 e)产品遭到篡改或损坏，以致宝德威无法进行保用调查。

以上保用及保用履行义务具排他性并取代所有其它保用或相关补救措施。宝德威对由其制造或销售的产品以任何方式造成的间接性、偶然性、惩罚性或后果性损失赔偿概不承担责任。

## BALDWIN FILTER WARRANTY

### **(GARANTIE BALDWIN (French / Français))**

Baldwin Filters, Inc. (« Baldwin ») garantit que chaque produit neuf fabriqué par Baldwin est exempt de défauts de matière et de main-d'œuvre. Baldwin remplacera tout produit qui a été déterminé défectueux si vous le renvoyez à Baldwin ou au distributeur Baldwin qui vous a vendu le produit.

#### **Procédure de retour**

Vous devez tout d'abord contacter votre vendeur chez Baldwin ou votre distributeur Baldwin si vous pensez que le produit que vous avez acheté ne satisfait pas aux conditions de la garantie énoncée ci-dessus. Le vendeur vous aidera à remplir les documents nécessaires et à renvoyer le produit supposé défectueux à Baldwin pour analyse.

#### **Traitements des demandes de remplacement au titre de la garantie**

Si Baldwin détermine que le produit renvoyé ne satisfait pas aux conditions de la garantie énoncée ci-dessus, Baldwin remplacera rapidement le produit défectueux. Si le produit défectueux a causé directement des dommages à la machine sur laquelle il a été installé, Baldwin remboursera rapidement le propriétaire de la machine des coûts des réparations qui ont été nécessaires pour remettre la machine dans l'état où elle était immédiatement avant d'être endommagée par le produit défectueux.

#### **Conditions**

Les obligations de Baldwin au titre de la garantie ne s'appliquent pas si : a) le produit n'est pas renvoyé à Baldwin pour analyse, b) Baldwin détermine que le produit n'est pas défectueux, c) le produit a été incorrectement installé ou utilisé, d) le produit a été ré-utilisé ou n'a pas été remplacé dans l'intervalle de service normal, ou e) le produit a été modifié sans autorisation ou endommagé de manière pouvant empêcher Baldwin de l'analyser au titre de la garantie.

**La garantie ci-dessus et les obligations au titre de la garantie sont exclusives et remplacent toutes les autres garanties ou recours associés. Baldwin n'est pas responsable des dommages indirects, accessoires ou punitifs découlant de quelque forme que ce soit des produits qu'elle fabrique ou vend.**

\*\*\*\*\*

### **BALDWIN - GARANTIE (German / Deutsch)**

Baldwin Filters, Inc. („Baldwin“) garantiert, dass jedes von Baldwin hergestellte neue Produkt im Herstellungszustand frei von Verarbeitungs- und Materialmängeln ist. Baldwin ersetzt jedes Produkt, das Sie an Baldwin oder an Ihren Baldwin-Händler, bei dem Sie es gekauft haben, zurückgeben und das für mangelhaft befunden wird.

#### **Reklamation**

Wenden Sie sich bitte zunächst an den zuständigen Vertriebsmitarbeiter bei Baldwin oder Ihrem Baldwin-Händler, wenn Sie zu der Auffassung gelangen, dass ein von Ihnen gekauftes Produkt nicht der obigen Garantieaussage entspricht. Der Vertriebsmitarbeiter hilft Ihnen gerne, die erforderlichen Unterlagen auszufüllen und das mutmaßlich mangelhafte Produkt zur Prüfung an Baldwin einzusenden.

#### **Garantieleistung**

Stellt Baldwin fest, dass ein reklamiertes Produkt tatsächlich nicht der obigen Garantieaussage entspricht, ersetzt Baldwin das mangelhafte Produkt unverzüglich. Hat das mangelhafte Produkt unmittelbar zu einem Schaden an der Maschine, in das es eingebaut wurde, geführt, erstattet Baldwin dem Maschineneigentümer unverzüglich den Anteil der Reparaturkosten, der zur Wiederherstellung des Maschinenzustands unmittelbar vor dem aufgrund des mangelhaften Produkts eingetretenen Schaden aufgewendet werden musste.

#### **Bedingungen**

Die Pflichten von Baldwin gemäß den obigen Garantiezusagen gelten nicht, wenn a) das Produkt nicht zur Prüfung an Baldwin zurückgegeben wird, b) Baldwin feststellt, dass das Produkt nicht mangelhaft war, c) das Produkt unsachgemäß eingebaut oder verwendet wurde, d) das Produkt wiederverwendet oder nicht innerhalb eines normalen Wartungszeitraums gewechselt wurde, oder d) das Produkt auf eine Weise manipuliert oder beschädigt wurde, die Baldwin an einer Garantieprüfung hindern kann.

**Die obige Garantie und die damit verbundenen Pflichten gelten ausschließlich und anstelle aller sonstigen Garantien oder entsprechenden Rechtsbehelfe. Baldwin haftet nicht für indirekte, Begleit- oder Folgeschäden, Schadenersatz oder Bußgelder, die sich auf irgendeine Weise aus den von Baldwin hergestellten bzw. verkauften Produkten ergeben.**

## **BALDWIN FILTER WARRANTY**

### **GARANZIA BALDWIN (Italian / Italiano)**

Baldwin Filters, Inc. ("Baldwin") garantisce che ciascun nuovo prodotto creato da Baldwin sarà privo di difetti di produzione e materiale. Baldwin sostituirà qualsiasi prodotto per il quale verrà rilevato un difetto, a seguito della sua restituzione a Baldwin o al distributore Baldwin presso il quale il prodotto è stato acquistato.

#### **Procedimento di restituzione**

Per prima cosa è necessario contattare il responsabile vendite di Baldwin o del distributore Baldwin presso il quale è stato acquistato il prodotto che si ritiene non soddisfi la garanzia qui riportata. Il responsabile vendite vi aiuterà a completare i documenti necessari e a restituire a Baldwin il prodotto ritenuto difettoso per la relativa analisi.

#### **Adempimento della garanzia**

Se Baldwin riscontra che il prodotto restituito non soddisfa la garanzia riportata, procederà a sostituire velocemente il prodotto difettoso. Se il prodotto difettoso ha provocato direttamente un danno alla macchina in cui è stato installato, Baldwin rimborserà subito il proprietario della macchina per quella parte dei costi di riparazione ritenuti necessari a ripristinare la macchina alla condizione immediatamente precedente al danno causato dal prodotto difettoso.

#### **Condizioni**

Gli obblighi di adempimento della garanzia Baldwin non si applicano se: a) Il prodotto non viene restituito a Baldwin per l'analisi; b) Baldwin rileva che il prodotto non era difettoso; c) Il prodotto è stato installato o utilizzato in modo non corretto; d) Il prodotto è stato riutilizzato o non sostituito entro un intervallo di servizio normale; e) Il prodotto è stato manomesso o danneggiato in modo tale da impedire a Baldwin di condurre un'investigazione per la garanzia.

**La garanzia qui riportata e gli obblighi di adempimento della stessa sono esclusivi e sostituiscono qualsiasi altra garanzia o rimedio correlato. Baldwin non deve essere ritenuta responsabile per danni indiretti, accidentali, punitivi o diretti risultanti in qualsiasi modo dai prodotti creati o venduti.**

\*\*\*\*\*

### **A GARANTIA BALDWIN (Portuguese / Português)**

A Baldwin Filters, Inc. ("Baldwin") garante que cada novo produto fabricado por ela será isento de defeitos de mão-de-obra e materiais. A Baldwin substituirá qualquer produto com defeito quando você o devolver à Baldwin ou ao seu distribuidor Baldwin onde o comprou.

#### **Processo de Devolução**

Em primeiro lugar, você deve contatar o vendedor que o atendeu na Baldwin ou no seu distribuidor Baldwin, se você comprou um produto que acredita não atender à garantia acima declarada. O vendedor o ajudará a preencher os documentos necessários e no processo de devolver o produto com suspeita de defeito à Baldwin para análise.

#### **Atendimento da Garantia**

Se a Baldwin determinar que um produto devolvido não atende à garantia acima declarada, a Baldwin o substituirá imediatamente. Se o produto defeituoso tiver causado danos diretos à máquina no qual estava instalado, a Baldwin imediatamente reembolsará o proprietário da máquina pela parte dos custos de reparo que tiverem sido necessários para restaurar a máquina a sua condição anterior aos danos causados pelo produto defeituoso.

#### **Condições**

As obrigações acima de atendimento da garantia da Baldwin não se aplicam se: a) o produto não for devolvido à Baldwin para análise, b) a Baldwin determinar que o produto não estava defeituoso, c) o produto tiver sido incorretamente instalado ou usado, d) o produto tiver sido reutilizado ou não substituído dentro do intervalo normal em serviço, ou e) o produto tiver sido adulterado ou danificado de maneira a inibir a capacidade da Baldwin conduzir uma investigação de garantia.

**A garantia acima e as obrigações do seu atendimento são exclusivas e substituem quaisquer outras garantias ou soluções relacionadas. A Baldwin não se responsabiliza por danos indiretos, supervenientes, punitivos ou consequentes resultantes de qualquer forma dos produtos que fabrica ou vende.**

## BALDWIN FILTER WARRANTY

### ГАРАНТИЯ КОМПАНИИ BALDWIN (“Болдуин”) (Russian / Русский)

Компания Baldwin Filters, Inc. (“Baldwin”) гарантирует, что в каждом новом товаре, произведенном компанией Baldwin, отсутствуют дефекты производства и материалов. Компания Baldwin произведет замену любого товара, в котором обнаружится брак, после возврата его в компанию Baldwin или дистрибьютору компании Baldwin, у которого был приобретен товар.

#### Процедура возврата товара

Если Вы считаете, что приобрели товар, который не соответствует вышеуказанным условиям гарантии, Вам сначала необходимо обратиться к сотруднику компании Baldwin или дистрибьютору компании Baldwin, у которого был приобретен товар. Данное лицо поможет Вам заполнить необходимые документы и произвести возврат товара с предполагаемым браком в компанию Baldwin для проведения анализа.

#### Исполнение гарантии

Если компания Baldwin придет к выводу, что товар не соответствует вышеуказанным условиям гарантии, она незамедлительно заменит бракованный товар. Если бракованный товар явился непосредственной причиной повреждения оборудованию, на котором он был установлен, компания Baldwin незамедлительно вернет владельцу оборудования средства на ремонт, которые были необходимы для приведения оборудования в состояние, в котором оно находилось непосредственно перед возникновением повреждения, вызванного бракованным товаром.

#### Условия гарантии

Указанные выше обязательства по исполнению гарантии не применяются, если: a) товар не возвращен в компанию Baldwin для проведения анализа, b) компания Baldwin придет к выводу, что товар не является бракованным, c) товар был неправильно установлен или неправильно использовался, d) товар был использован повторно или не был заменен в рамках нормального интервала обслуживания или e) товар подвергнулся таким изменениям или повреждениям, которые могут воспрепятствовать проведению компанией Baldwin расследования.

**Вышеуказанная гарантия и обязательства по исполнению гарантии являются исчерпывающими и применяются вместо всех прочих гарантий или соответствующих средств судебной защиты. Компания Baldwin не несет ответственности за любые косвенные, побочные, штрафные и непрямые убытки, возникшие в любом виде из-за производимых или продаваемых ею товаров.**

\*\*\*\*\*

### GARANTÍA DE BALDWIN (Spanish / Español)

Baldwin Filters, Inc. (“Baldwin”) garantiza que cada producto nuevo fabricado por Baldwin estará libre de defectos de mano de obra y materiales. Baldwin reemplazará todo producto defectuoso cuando lo devuelva a Baldwin o al distribuidor de Baldwin donde lo compró.

#### Proceso de devolución

Primero debe contactar a su asociado de ventas en Baldwin o a su distribuidor de Baldwin si compró un producto que cree que no cumple con la garantía indicada arriba. El asociado de ventas le ayudará a completar la documentación necesaria y a devolver el producto sospechoso a Baldwin para su análisis.

#### Cumplimiento de la garantía

Si Baldwin determina que un producto devuelto no cumple con la garantía indicada arriba, reemplazará inmediatamente el producto defectuoso. Si el producto defectuoso causó daños directos a la máquina en la cual se instaló, Baldwin reembolsará con prontitud al propietario de la máquina por la parte de los costos de reparación que fueron necesarios para restaurar la máquina a su condición inmediatamente anterior al daño causado por el producto defectuoso.

#### Condiciones

Las obligaciones de cumplimiento de la garantía de Baldwin no corresponden si: a) el producto no es devuelto a Baldwin para su análisis, b) Baldwin determina que el producto no estaba defectuoso, c) el producto se había instalado o utilizado en forma inapropiada, d) el producto se reutilizó o no se reemplazó en el intervalo de servicio normal o e) el producto se manipuló o se dañó en una forma que no permite que Baldwin realice una investigación de garantía.

**La garantía y las obligaciones de cumplimiento de garantía son exclusivas y en lugar de toda otra garantía o recursos asociados. Baldwin no es responsable por daños indirectos, incidentales, punitivos o consiguientes derivados en alguna forma de los productos que fabrica o vende.**

---

## PRODUCT INVESTIGATION

---

### Procedure for Service Engineering Product Investigation

This procedure outlines the steps necessary for Baldwin Filters Service Engineering to complete an investigation of products from the field. The steps of this procedure are necessary to provide the most accurate and timely investigation possible.

If a filter is suspected of causing a failure, don't throw away the evidence. In order to process a warranty claim, follow the Product Investigation Procedure . . .

1. Complete a Field Report Form (Form 387) (see next page). Describe the events on a separate sheet.
2. Obtain a sample of oil, fuel or coolant in the system at the time of the failure.
3. Save damaged parts for evidence of the claimed damage.
4. For an air filter, cover the open end(s) with tape to prevent dust from entering the element during shipping.
5. Send copies of any repair bills.

6. Send the entire suspect filter, including the gaskets.

If the investigation is being requested for warranty consideration, repair bills (not estimates) should also accompany the request. Damaged equipment components such as bearings, liners, etc. should be retained by the customer for possible examination by Service Engineering.

Filter products are NOT to be cut open or otherwise tampered with. This may prevent objective analysis and testing, and may void the warranty.

Notice of damages and claims should be made immediately when the damage occurs. Every claim will receive careful and objective consideration. If a Baldwin product is proven to have caused damage, Baldwin will pay the cost required to repair the equipment to its condition at the time the failure occurred. Liability payment will not include consequential damages such as downtime, motel bills, etc.

If you have any questions regarding this procedure, or any product investigation, please contact our Service Engineering Team at:

**(308) 237-9729**

**FIELD REPORT FORM**

**DISTRIBUTOR**

Company Name \_\_\_\_\_  
Address \_\_\_\_\_  
City \_\_\_\_\_  
State \_\_\_\_\_ ZIP \_\_\_\_\_  
Contact \_\_\_\_\_  
Person \_\_\_\_\_  
Phone \_\_\_\_\_

**EQUIPMENT OWNER**

Company Name \_\_\_\_\_  
Address \_\_\_\_\_  
City \_\_\_\_\_  
State \_\_\_\_\_ ZIP \_\_\_\_\_  
Contact \_\_\_\_\_  
Person \_\_\_\_\_  
Phone \_\_\_\_\_

Filter Number \_\_\_\_\_ Installation Date \_\_\_\_\_ Removal Date \_\_\_\_\_

Repair Shop Name \_\_\_\_\_ Cost of Repairs \$ \_\_\_\_\_

(ATTACH ITEMIZED REPAIR BILL)

Street \_\_\_\_\_ Contact \_\_\_\_\_  
City \_\_\_\_\_ Phone \_\_\_\_\_  
State \_\_\_\_\_ ZIP \_\_\_\_\_ FAX \_\_\_\_\_

**EQUIPMENT** Model \_\_\_\_\_ Year \_\_\_\_\_ Serial No. \_\_\_\_\_

Type of Equipment \_\_\_\_\_ Make \_\_\_\_\_  
Damaged Part \_\_\_\_\_ Total Miles or Hours on Unit \_\_\_\_\_  
(Engine, Pump, Etc.) \_\_\_\_\_

**AIR FILTER** Has the system recently been worked on? \_\_\_\_\_

Has the filter been washed? \_\_\_\_\_ Miles/Hours on Oil \_\_\_\_\_ Oil Sump Capacity \_\_\_\_\_  
Pressure/Restriction Gauge reading at removal \_\_\_\_\_ (psi/inches of H<sub>2</sub>O/Mercury)  
Usual Filter Change Interval \_\_\_\_\_ (Miles/Hours)

**COOLANT** How often is the system tested? \_\_\_\_\_

Type of Antifreeze Used \_\_\_\_\_ Cooling System Capacity \_\_\_\_\_ Type of SCA Used \_\_\_\_\_  
Cooling System Last Cleaned \_\_\_\_\_ (Miles/Hours)

**OIL/HYDRAULIC** Has the system recently been worked on? \_\_\_\_\_

Type of Oil \_\_\_\_\_ Oil Sump Capacity \_\_\_\_\_ Miles/Hours on Oil \_\_\_\_\_  
Usual Oil Change Interval \_\_\_\_\_ (Miles/Hours)

**FUEL** Has the system recently been worked on? \_\_\_\_\_

Type of Fuel \_\_\_\_\_ Miles/Hours on Filter \_\_\_\_\_ Fuel System Pressure \_\_\_\_\_

**PLEASE USE A SEPARATE PAGE TO DESCRIBE WHAT HAPPENED!**

Signature of Distributor \_\_\_\_\_ Signature of Owner \_\_\_\_\_

Please send this Report, any Repair Bills, Explanation, Oil/Coolant Samples and Filters to:

ATTN: SERVICE ENGINEERING  
**BALDWIN FILTERS**  
4400 E Hwy 30  
Kearney, NE 68847









# Restore engine performance and fuel economy with Stanadyne fuel additives

## Stanadyne Diesel & Gasoline Additives will:

- Restore and improve horsepower and torque
- Improve fuel economy
- Clean, lubricate and protect the engine's fuel system
- Help the engine start faster and run smoother

**STANADYNE**<sup>™</sup>  
**Fuel Additives**

# BALDWIN HEAVY-DUTY FILTERS

QUALITY. COVERAGE. SERVICE. AVAILABILITY.

---

## FIND THE COVERAGE YOU'RE LOOKING FOR

### FILTERS FOR ALL OF YOUR NEEDS

Baldwin's high quality filters are designed for on and off-road vehicles with diesel engines.

- service shops
- farmers
- trucking companies
- contractors
- municipalities
- fleets or anyone who operates diesel equipment



No matter what the industry or operating conditions, you can be confident that Baldwin's heavy-duty filters provide protection that matches or exceeds the original equipment.

### HEAVY-DUTY FILTER HOTLINE

Toll Free:

**1-800-822-5394**

Cross-Reference Lookup and Other Filter Info:  
**[baldwinfilters.com](http://baldwinfilters.com)**



**[baldwinfilters.com](http://baldwinfilters.com)**